GEOLOGICAL, GEOCHEMICAL, GEOPHYSICAL AND TRENCHING REPORT ON THE ORO PROPERTY

MAYO MINING DISTRICT, YUKON
MAPSHEETS: 105O/02, 03, 06, 07
UTM COORDINATES: 7020000 NORTH, 402500 EAST, ZONE 9, NAD 83

QUARTZ CLAIMS WORKED

CLAIM NAME	TAG #
ORO 1 – ORO 48	YD31351 – YD31397
ORO 49 – ORO 318	YD104903 – YD105172
ORO 319 – ORO 330	YD105441 – YD105452
SOL 1 – SOL 206	YD105453 – YD105658
OS 1 – OS 532	YE42001 – YE42532
ON 1 – ON 400	YE42601 – YE43000
ON 401 – ON 470	YE43261 – YE43330
SNG 1 – SNG 5	YE39295 – YE39299
HS 1 – HS 8	YE43001 – YE43008
HS 11 – HS 24	YE43011 – YE43024
HS 27 – HS 242	YE43027 – YE43242
HS 243 – HS 250	YE39287 – YE39294
HS 251 – HS 256	YE39281 – YE39286

DATES OF WORK: June 25 to September 21, 2011

for

COLORADO RESOURCES LTD.
110 – 2300 CARRINGTON ROAD
WEST KELOWNA, BC
V4T 2N6

by

LINDA DANDY, P.Geo.
Consulting Geologist

February 22, 2012

Linda Dandy, P.Geo., Box 95, Atlin, B.C., V0W 1A0 Phone:250-651-7531 Email: lindadandy@telus.net

SUMMARY

The Oro Property, containing the historic Neve-Brick Minfile (105O/032) occurrence, is located 25 kilometres west of the MacMillan Pass Airstrip and the North Canol Highway, in eastern Yukon. Located on the eastern margin of the Selwyn Basin, the property is underlain by Ordovician to Triassic sedimentary strata which are intruded by variably altered Cretaceous felsic sills and dykes. Cretaceous compressional tectonics have isoclinally folded and faulted the sedimentary strata.

Prior to Colorado Resources Ltd. ("Colorado") acquiring the Oro Property, it had been worked by AGIP Canada Ltd. from 1979 to 1989. No work had been done on the property from 1989 until Colorado acquired it by optioning and staking in late 2010 and early 2011. Previous work on the property included geology, geochemistry, geophysics, trenching and diamond drilling. Prior drilling concentrated on the Neve-Brick Minfile area which includes the J.O., Saddle and Canol Zones. Between 1977 and 1984, on the eastern portion of the claim block, Hudson Bay Exploration and Mining and Cominco Ltd. conducted geochemical programs targeting sedex Pb-Zn-Ba mineralization.

After property acquisition, in 2011, Colorado conducted an airborne geophysical survey, a soil, silt and rock sampling program, prospecting, geological mapping and mini-excavator trenching. This exploration program was conducted with the intent of expanding previously reported mineralization and continuing exploration to discover new mineralized zones.

The 2011 exploration program in significantly expanded the J.O.- Saddle –Canal zone anomaly and identiefied a number of new areas of mineralization including Area 51, Golden Hinge, Golden Ridge, North Steel, Repeater and Limey Ridge.
There are also a number of small scattered geochemical and geophysical targets that require preliminary follow up work.

The Neve area (J.O.-Saddle-Canol Zones) remains the primary target area for 2012 exploration. A strong multi-element, zoned geochemical anomaly trends through this area and extends southeast to the Repeater Zone, for a distance of approximately four kilometres. Geological/structural mapping identified Cretaceous intrusive dykes which may indicate an intrusive-style gold mineralizing system, as seen throughout the Tombstone Suite intrusions. However, this dyke system and nearby significant fault structures are also interpreted to intersect limey potential Carlin host lithologies at depth in this same area. A diamond drilling program is required in order to test this target.

Due to the success of the exploration program on the Oro Property in 2011, an expanded program is recommended for 2012. The 2012 exploration program should consist of continued infill soil geochemical sampling and geological mapping in key target areas. Up to 10,000 soil samples should be collected. Excavator trenching is recommended to follow up soil geochemical anomalies, along with 5000 metres of diamond drilling.

While the soil sampling, trenching and mapping is planned to be conducted over several anomalous zones, diamond drilling should at initially target the Neve occurrence area where structural mapping, geophysics and geochemical indicators all suggest a strong possibility of locating a buried Carlin gold target. Estimated cost for the 2012 exploration program is $4.5 million.

TABLE OF CONTENTS

	Page
SUMMARY ……	1
1) INTRODUCTION……	6
2) LOCATION AND ACCESS ……	6
3) PHYSIOGRAPHY AND CLIMATE……	6
4) CLAIM INFORMATION ……	7
5) HISTORY ……	7
6) WORK DONE BY COLORADO RESOURCES LTD. IN 2011 ……..	10
7) GEOLOGY ……..……	10
8) GEOCHEMISTRY……	18
9) TRENCHING …….	23
10) GEOPHYSICS …….	25
11) CONCLUSIONS ……	31
12) RECOMMENDATIONS ……	32
13) REFERENCES ……	33
14) COST STATEMENT ……..…	35
15) QUALIFICATIONS ……	37
APPENDICES ……..…	38

APPENDIX I – FIGURES 1 TO 27
APPENDIX II – QUARTZ CLAIM INFORMATION
APPENDIX III – PAUL METCALFE GEOLOGY REPORT
APPENDIX IV – KATHRYN DUNN PETROGRAPHIC REPORT
APPENDIX V – ROCK SAMPLE – LOCATIONS, DESCRIPTIONS AND RESULTS (FULL DATABASE IN DIGITAL VERSION ONLY)
APPENDIX VI - ROCK AND TRENCH SAMPLE RESULTS – ACME LABS LTD. CERTIFICATES OF ANALYSES (DIGITAL VERSION ONLY)
APPENDIX VII – SOIL SAMPLES – FULL DATABASE OF LOCATIONS,

DESCRIPTIONS AND RESULTS (DIGITAL VERSION ONLY)
APPENDIX VIII – SOIL SAMPLE RESULTS – ACME LABS CERTIFICATES OF ANALYSES (DIGITAL VERSION ONLY)
APPENDIX IX - SILT SAMPLES – FULL DATABASE OF LOCATIONS, DESCRIPTIONS AND RESULTS (DIGITAL VERSION ONLY)
APPENDIX X – SILT SAMPLE RESULTS – ACME LABS CERTIFICATES OF ANALYSES (DIGITAL VERSION ONLY)
APPENDIX XI – AIRBORNE GEOPHYSICAL SURVEY - REPORT BY FUGRO (PLUS RAW DATA IN DIGITAL VERSION ONLY)
APPENDIX XII – WARD KILBY ASTER IMAGERY

LIST OF TABLES

Page

TABLE I – QUARTZ CLAIM NAMES AND TENURE NUMBERS …… 7

TABLE II – PERCENTILE VALUES OF ROCK AND TRENCH SAMPLES …… 19

TABLE III – PERCENTILE VALUES OF SOIL SAMPLES …… 21

TABLE IV – PERCENTILE VALUES OF SILT SAMPLES …… 21

TABLE V – TRENCH SAMPLE RESULTS ……..…… 24

TABLE VI – AIRBORNE SURVEY CORNER COORDINATES …… 25

TABLE VII – EM ANOMALY STATISTICS …… 27

APPENDIX I
LIST OF FIGURES

FIGURE 1 – LOCATION MAP

FIGURE 2 – CLAIM MAP

FIGURE 3 – ORO REGIONAL GEOLOGY MAP (YGS)

FIGURE 4 – PROPERTY GEOLOGY MAP (YGS and ABBOTT)

FIGURE 5 – GEOLOGICAL MAP OF THE SHOWING AREA (METCALFE)

FIGURE 6 – PROSPECTING ROCK SAMPLE LOCATION MAP

FIGURE 7A – SOIL AND SILT SAMPLE LOCATION MAP – WEST TILE

FIGURE 7B – SOIL AND SILT SAMPLE LOCATION MAP – CENTRE TILE

FIGURE 7C – SOIL AND SILT SAMPLE LOCATION MAP – EAST TILE

FIGURE 7D – SOIL AND SILT SAMPLE LOCATION MAP – J.O.-SADDLE-CANOL ZONES

FIGURE 8 – 2011 SOIL AND SILT SAMPLE RESULTS – AU

FIGURE 9 – 2011 SOIL AND SILT SAMPLE RESULTS – AG

FIGURE 10 – 2011 SOIL AND SILT SAMPLE RESULTS – AS

FIGURE 11 – 2011 SOIL AND SILT SAMPLE RESULTS – SB

FIGURE 12 – 2011 SOIL AND SILT SAMPLE RESULTS – HG

FIGURE 13 – 2011 SOIL AND SILT SAMPLE RESULTS – BI

FIGURE 14 – 2011 SOIL AND SILT SAMPLE RESULTS – TL

FIGURE 15 – 2011 SOIL AND SILT SAMPLE RESULTS – ZN

FIGURE 16 – J.O.-SADDLE-CANOL ZONES – AU GEOCHEMISTRY OVER CONTOURED AS IN SOILS

FIGURE 17 – J.O.-SADDLE-CANOL ZONES – TL GEOCHEMISTRY OVER CONTOURED AS IN SOILS

FIGURE 18 – TRENCH LOCATIONS AND SAMPLE NUMBERS

FIGURES 19A – TRENCHES WITH GEOLOGY AND AU RESULTS

FIGURES 19B – TRENCHES WITH GEOLOGY AND AS RESULTS

FIGURE 20 – AREA 51 – AU GEOCHEMISTRY AND AS CONTOURS

FIGURE 21 – GOLDEN HINGE, GOLDEN RIDGE AND NORTH STEEL AREAS – AU GEOCHEMISTRY ON CONTOURED AG IN SOILS

FIGURE 22 – AIRBORNE GEOPHYSICAL SURVEY - FLIGHT LINES

FIGURE 23 – AIRBORNE GEOPHYSICS – TOTAL MAGNETIC INTENSITY (TMI)

FIGURE 24 – AIRBORNE GEOPHYSICS – TILT DERIVATIVE

FIGURE 25 – AIRBORNE GEOPHYSICS – RESISTIVITY (56K)

FIGURE 26 – AIRBORNE GEOPHYSICS – RESISTIVITY (7200)

FIGURE 27 – AIRBORNE GEOPHYSICS - INTERPRETATION

1) INTRODUCTION

The Oro Property, containing the historic Neve-Brick minfile occurrence (105O 032), is located in the MacMillan Pass area of northeastern Yukon. The central portion of the property was acquired by Colorado Resources Ltd. ("Colorado") in late 2010 and expanded by staking in early 2011.

Colorado acquired this property after studying the regional geological trends and examining historic minfile records and prior company assessment reports documenting Carlin style gold mineralization potential on the property. After property acquisition, in 2011, Colorado conducted an airborne geophysical survey, ASTER image analysis, a soil, silt and rock sampling program, prospecting, geological mapping and mini-excavator trenching. This exploration program was conducted with the intent of expanding previously reported mineralization and continuing exploration to discover new mineralized zones. The 2011 exploration program is the subject of this report.

2) LOCATION AND ACCESS

The eastern end of the Oro Property is located 25 kilometres west of the MacMillan Pass Airstrip and the North Canol Highway in eastern Yukon (Figure 1). The claims cover an area of approximately 37,515 hectares and are centred at UTM coordinates 7020000 North, 402500 East in Zone 9, within mapsheets 105O 02, 03, 06 and 07.

Access to the Oro Property is via helicopter from the MacMillan Pass Airstrip or Colorado's camp located 8 kilometres south of the airstrip along the North Canol Highway. The camp is road accessible from the community of Ross River, located approximately 210 kilometres to the southwest.

A secondary road (the Nidd Road) branches westerly off the North Canol Highway 2 kilometres south of the MacMillan Pass airstrip and travels for 25 kilometres to the Oro Property border. This road has not been used in several years and both the road and the bridge crossing the South MacMillan River require rehabilitation. Additionally, the winter road to Mayo traverses the valley along the southern border of the Oro Property. This road has also not been used for many years and is somewhat overgrown.

3) PHYSIOGRAPHY AND CLIMATE

Situated in the Hess Mountains, topography is moderate to rugged with elevations ranging from 950 to 1800 metres, yielding a maximum relief of 850 metres. The mountain and ridge slopes of shale felsenmeer and scree are generally steep. A resistive weathering, chert pebble conglomerate unit forms more rugged ridges.

Vegetation is typical of eastern Yukon with treeline at about 1350 metres. Vegetation in the valleys is characterized by spruce and balsam with shrubs, alpine grasses and moss at lower elevations.

Water on the property is restricted to the larger creeks in late July and early August. Sufficient water sources are available for any exploration or mining requirements.

The climate in the area of the Oro Property is variable with cool summers and long, cold winters. During the summer (mid June to early August), temperatures range from 5 to 20^{o}C, with 20 to 22 hours of daylight. Winter weather in this region may commence after August 15th with snow, high winds, cooler temperatures, and decreasing daylight.

4) CLAIM INFORMATION

The Oro Property is located within the Mayo Mining District and consists of 1799 quartz claims totaling 37,515 hectares (Figure 2). The claims have been consolidated into three groups. Full claim information, including grouping lists, expiry dates and claim ownership, is listed in Appendix II.

TABLE I
QUARTZ CLAIM NAMES AND TENURE NUMBERS

CLAIM NAME	TENURE #
ORO 1 – ORO 48	YD31351 – YD31397
ORO 49 – ORO 318	YD104903 – YD105172
ORO 319 – ORO 330	YD105441 – YD105452
SOL 1 – SOL 206	YD105453 – YD105658
OS 1 – OS 532	YE42001 – YE42532
ON 1 – ON 400	YE42601 – YE43000
ON 401 – ON 470	YE43261 – YE43330
SNG 1 – SNG 5	YE39295 – YE39299
HS 1 – HS 8	YE43001 – YE43008
HS 11 – HS 24	YE43011 – YE43024
HS 27 – HS 242	YE43027 – YE43242
HS 243 – HS 250	YE39287 – YE39294
HS 251 – HS 256	YE39281 – YE39286

The claims are all owned 100% by Colorado Resources Ltd., except for the Oro 1 to 330 claims which are owned by Cathro Resources Ltd. Colorado has an option to acquire 100% of the Oro 1 to 330 claims.

5) HISTORY

Neve-Brick Area

The majority of historic work conducted on the Oro Property was done by AGIP Canada Ltd. in the area of the Neve-Brick minfile occurrence (105O 032). The first documented work by AGIPconsisted of a stream sediment sampling program in 1980. This work was targeting sedex

lead-zinc-silver mineralization as found on HudBay's Tom Property. Gold was not analysed during this program, however they did find a few anomalous values of zinc and barium (Beauchamp, 1980).

Despite the disappointing stream sediment results, AGIP returned in 1981 with a mapping and sampling program (Garagan, 1981). Along with preliminary geological mapping, AGIP located two outcrop occurrences of realgar-orpiment +/- stibnite veining associated with intrusive dykes. A small soil geochemical survey indicated anomalous areas of gold, silver, arsenic and antimony.

In 1982, two concurrent exploration programs were carried out on the Neve and Brick claims by AGIP. On the Neve claims soil samples and talus fines were collected in three areas, with the conclusion that only a few weak anomalies were found which could probably be explained by local veining. On the Brick claims a trench was dug across a precious metal soil geochemical anomaly. Elevated values in gold, silver, arsenic, antimony and mercury in the trench samples relate to enrichment in veins cutting highly altered quartz-feldspar porphyry dykes. Some enrichment may also be due to low grade precious metal content disseminated within the intrusives (Garagan, 1982).

Also in 1982, AGIP used a small pack-sack drill to put in 117 overburden holes to sample bedrock chips +/or soil at the bedrock-soil interface. Samples were drilled at 5 metre centres in 3 anomalous zones within the Brick claims. In most cases the deeper values were higher than the surface samples, but were also much more variable due possibly to the erratic nature of the mineralization (Garagan, 1983).

In 1983, AGIP conducted a soil sampling and trenching program. Soil sampling of the new 1983 grid located a new zone ("J.O. Zone") of highly anomalous gold values in soil and talus across a steep slope facing northwest. The J.O. Zone soil anomaly is an extension of the Saddle Zone geochemical anomaly, although the zones seem to be geologically distinct. The soil anomalies are defined by the 100 ppb gold contour; the main part of the J.O. Zone anomaly consists of two distinct anomalies exceeding 1000 ppb gold in soil (these anomalies are 150 metres and 70 metres long, respectively). Some soil samples within the J.O. Zone exceed 5000 ppb gold. Maximum gold values in grab samples of rock in the J.O. Zone reached 1.44 g/t. Gold mineralization seems related to the degree of fracturing (Robertson, 1984).

Three trenches were excavated across the strongest parts of the J.O. Zone soil anomaly. Results of gold analyses of soil and rock samples from the trenches confirm the gold values found in surface soil samples of the J.O. Zone. The best gold grades and the most difficult trenching conditions are associated with strongly fractured sooty carbonaceous shales. The best results were from trench 83-1, where soil and rock composite grab samples were collected at 3 metre intervals over its 44 metre length. All but two soil samples contained greater than 1000 ppb gold, with the best result being 4.74 g/t gold. The rock sample results were lower, with the best result being 655 ppb gold. All samples contained greater than 100 ppb gold and 5000 ppb mercury.

AGIP followed up these early soil sampling and trenching programs with diamond drilling programs in 1985 and 1988. In 1985, a total of 1257.3 metres was drilled in 9 BQ size holes, with 5 of these holes being abandoned before reaching their target depths. Drilling results indicate the weighted average for all anomalous gold and silver values is 0.31 g/t Au and 2.59 g/t Ag over an

average true width of 30.4 metres. The anomalous Au-Ag values correspond to intense fracturing, clay altered fault gouge and veining within black carbonaceous shales and siliceous graphitic-carbonaceous shales. The higher gold-silver values generally correlate with increased structural disruption, lost core and/or increased veining (Aupperle, 1985).

In 1988, 10 NQ and HQ sized diamond drill holes totalling 1229.8 metres, were drilled by AGIP. Results of this drill program have been summarized by Hulstein and Keyser (1989):

"Gold mineralization has been identified at two areas: (1) the Canol Zone and (2) the J.O. - Saddle Zone. Mineralization and alteration appear to be related to faulting, fracturing and quartz-carbonate veinlets and stockworks temporally and spatially related to Cretaceous dykes and sills. Disseminated pyrite, realgar, orpiment, stibnite, arsenopyrite and proustite-pyrargyrite are found in narrow quartz veinlets hosted by altered quartz monzonite sills and dykes and adjacent hornfelsed and bleached sediments.

The Canol Zone, approximately one kilometre long by 50-60 metres wide, is underlain by silty limestone and shales. It was drill tested for the first time in 1988. Although no significant anomalous gold values were intersected in the silty limestone unit, anomalous gold values (up to 0.488 g/t over 2.70 metres) were intersected in faulted and sheared shales.

The J.O. - Saddle Zone, approximately 850 by 300-475 metres in area, is underlain by variably hornfelsed and bleached shales and altered quartz monzonite sills and dykes. The Zone is bounded and cut by faults which are locally anomalous in gold. Even though the 1988 drilling had better core recoveries than the 1985 drilling, gold values and widths were similar. The best 1988 results were 5.30 metres of 0.699 g/t gold in a quartz-feldspar porphyry, including 1.108 g/t over 1.20 metres. Another interval returned 0.574 g/t gold over 30.10 metres."

After 1988, until Colorado acquired the property in 2010, no exploration was conducted in this area.

SOL Claims

Between 1977 and 1984, Hudson Bay Mining and Exploration and Cominco Ltd. put in a series of small soil grids over what is now the eastern half of the Oro Property, in the area currently covered by the SOL claims. Both companies were exploring for Sedex style Pb-Zn-Ag +/or Ba mineralization and obtained localized high soil values for each of these elements. Hudson Bay's exploration work was located on the northern portion of Colorado's SOL claims, and interestingly showed some high areas of mercury values in soil (the only other element for which they analysed). They also obtained some significant silver values in soil which correlate well with Colorado's newly identified Golden Ridge/North Steel Zone.

Other Minfile Occurrences

Four additional minfile occurrences have been documented on the Oro Property. Three of these are sedex style bedded barite occurrences (Gow 105O 029, Minorco 105O 046 and Stroshein 105O 045) and one unknown deposit type (Fal 105O 042).

6) WORK DONE BY COLORADO RESOURCES LTD IN 2011

Work completed on the Oro Property between June 25 and September 21, 2011 consisted of airborne geophysics, ASTER image analysis, silt and soil sampling, prospecting and rock sampling, geological mapping and trenching.

Between July 15 and August 2, 2011, Fugro Airborne Surveys conducted a 2114 line kilometre heli-borne magnetic and electromagnetic (Dighem) survey. Survey lines were spaced 200 metre apart with perpendicular tie lies at 2000 metre spacings.

A large soil sampling program was completed, with a total of 13,808 soil samples collected. Grid lines were run north-south and depending on importance of the area were spaced between 100 to 900 metres apart. Samples were generally collected at 50 metre spacings along the lines, with occasional infill sampling at 25 metres.

A total of 339 silt samples were collected from most of the major drainages on the property.

Prospecting and rock grab sampling was carried out over much of the property, most notably in areas with significant colour anomalies (gossans). During the course of the prospecting program, rock samples were collected from mineralized, stockworked and altered outcrops. At total of 746 rock grab samples were collected.

Detailed geological mapping was undertaken by Dr. Paul Metcalfe in the Neve-Brick showing area in order to interpret structural controls that may be important for mineralization conduits. Also, in this area, a series of 15 trenches totalling 1548 metres were excavated with a Can-Dig type mini-excavator. Trenches were geologically mapped and sampled along 3 metre contiguous intervals for their entire lengths. A total of 525 rock chip and talus samples were collected from the trenches.

Work was conducted by a 10 person field crew working out of a camp along the North Canol Highway. Daily access to the property was via helicopter. Field crew were largely under contract to Colorado from Meridian Mapping Ltd. All field work was directly supervised by the author.

7) GEOLOGY

REGIONAL GEOLOGY (Extracted from Yukon Geological Survey, Selwyn Basin Metallogeny, compiled by Daniele Heon.)

Tectonic Evolution of Selwyn Basin (Figure 3)

Selwyn Basin was the locus of deep-water sedimentation that lay southwest of a major carbonate platform from Late Precambrian to Devonian time. The dominantly thin-bedded siliciclastic rocks grade to the northeast into the thick-bedded carbonate sediments of the variably subsiding Mackenzie Platform. From at least late Silurian to early Devonian, shallow-water clastic, volcanic and carbonate rocks of Cassiar Platform marked the southwestern margin of the basin.

Local episodes of igneous activity occurred throughout the sedimentary sequence. The association of widespread local accumulations of alkaline mafic rocks with Cambrian to Devonian unconformities or disconformities and the local presence of coarse clastics are interpreted to be the result of several short-lived pulses of rifting. Volcanism is interpreted to be the result of extension accompanying thermal subsidence and contraction of the lower crust following thermal uplift due to rifting.

From Cambrian to Silurian time, migration of the shelf edge caused interstratification of basinal and platformal facies, the progradation of basinal rocks into the platform and the formation of a series of satellite sub-basins that occur mostly on the N.W.T. side of Selwyn Basin and deep-water troughs (Richardson and Blackstone troughs) extending into, or enclosed within, the carbonate platform. Dominantly mafic and alkaline volcanic rocks are associated with the sub-Late Cambrian unconformity and also occur in Ordovician, Silurian and Devonian times. Rifting events are inferred in each case. Mid-Devonian rifting and/or wrench faulting resulted in a regional marine transgression that abruptly terminated the Selwyn Basin phase of passive margin sedimentation. Coarse grained clastic and siliceous sediments were deposited across the former shelf edge, locally accompanied by mafic and less abundant felsic volcanism.

Selwyn Basin - Passive Margin Phase

The coarse clastic turbidites of the Upper Precambrian to Lower Cambrian Hyland Group are the oldest exposed rocks of Selwyn Basin. They represent thick accumulations of sediments in submarine fans that were fed from an unidentified, rapidly uplifted source area and deposited in a deepening basin. Marginal uplift and sedimentation are interpreted as manifestations of the onset of a major rifting event. The overlying Lower Cambrian Gull Lake Formation marks off-shelf quiet water setting with some clastic input from the Mackenzie Platform. Local mafic volcanic rocks at the base of the Gull Lake Formation and the possibility of a disconformity at that stratigraphic level suggest a less pronounced rift event in late Early Cambrian time.

The sub-Rabbitkettle or sub-Late Cambrian unconformity is a basin-wide feature thought to result from thermal uplift and erosion caused by a Mid to Late Cambrian rifting event. Subsequent widespread Cambrian mafic volcanism lasted into the Ordovician. The SEDEX deposits of the Anvil district occur during this time interval, at the transition between the Mt Mye and Vangorda Formations, which have been respectively correlated to the Gull Lake and Rabbitkettle Formations.

From Late Cambrian-Ordovician to Silurian time, the Road River Group was deposited in euxinic deep-water conditions. The Lower Ordovician to Silurian Duo Lake Formation hosts the large Howards Pass zinc-lead deposit in east-central Selwyn Basin. The Upper Silurian Steel Formation was deposited in a deep but oxygenated environment. Some local tectonic instability is manifested by the sporadic eruption of Cambrian to Ordovician mafic alkaline volcanics and the migration of the shelf edge. The shelf edge was broken by a series of embayments, basins and troughs within which deeper water facies extended from the main part of Selwyn Basin into the platform. Several arches (Mackenzie, Ogilvie) exerted a degree of influence on the distribution of sedimentary facies. To the south, Selwyn Basin was connected to the Kechika Trough of the southern miogeocline (northern BC).

The Misty Creek Embayment formed during Middle Cambrian and younger extension. The Hess River flysch sequence records uplift and erosion of the flanks of the embayment. Deposition of the Rabbitkettle Formation was followed by the eruption of the Middle Ordovician to Middle Devonian volcanic rocks of the Marmot Formation that were deposited along the Duo Lake Formation (Road River Group). The Meilleur River Embayment was a large semi-circular embayment of Selwyn Basin that extended into the southern Mackenzie Platform from Ordovician to Silurian time. The Prairie Creek Embayment developed in Late Silurian as an eastern satellite depression in the Meilleur River Embayment and was the focus of carbonate sedimentation while deposition of Road River shale continued in the rest of the Meilleur River Embayment. Both the Meilleur River Embayment and the Prairie Creek Embayment were located in the central part of the Liard Depression, a long-lived depocentre that developed in the Ordovician and continued in to Devonian time.

Earn Group - Turbidite Basin Phase

The final and most widespread rifting event in the miogeocline occurred in Devono-Mississippian time. Rifting or wrench faulting along the outer miogeocline caused a dramatic change in pattern of sedimentation. Tectonism may have been associated with a back-arc setting, inboard to a pericratonic Devono-Mississippian arc (Yukon Tanana Terrane) that formed on the western margin of North America; the change in sedimentation is coincident to the age of magmatism on the arc. Widespread Middle to Late Devonian and early Mississippian transgression created a deep marine basin. Shale was deposited across the pre-existing platform-basin transition and well into the Mackenzie Platform to the east. At the same time, to the west, the basin was broken by rift zones that controlled deposition in submarine fan complexes of coarse clastics of the Earn Group. Exhalative barite and sulphides were deposited in this setting, forming significant SEDEX deposits in the Macmillan Pass area, at Clear Lake and in the Kechika Trough.

The deposition of coarse-grained clastic sediments was locally interbedded with volcanic assemblages that include mafic and felsic flows and tuffs. Less abundant felsic volcanism occurred on Cassiar Platform and near the Marg VMS deposit. Shale-hosted nickel sulphide mineralization was also deposited during this time interval, as seen at the Nick occurrence.

Structure

Deformation of Selwyn Basin rocks is dominated by Mesozoic structures. Although less obvious, pre-Mesozoic synsedimentary faults are significant as they control the development of secondary sedimentary basins and focus volcanism and SEDEX mineralization. Where preserved, these structures can be recognized from contact relationships. In other cases, these older structures may be cryptic, as they are often been overprinted by younger structures. Other brittle structures, both pre- and post-Mesozoic, control the NNE to ENE steeply dipping veins and faults.

Mesozoic deformation style is controlled by the incompetent nature of the dominant basinal shaly facies. The rocks deformed internally as a homogeneous mass forming the thrust and fold belt called the Selwyn Fold Belt. The Yukon portion of the Selwyn Fold Belt is bounded to the northeast by the carbonate platform edge and the coincident Mackenzie Fold Belt and to the southwest by the leading edge of accreted terranes and by the dextral transcurrent Tintina fault.

Mesozoic deformation reflects response to largely northeasterly-directed compression. Timing of deformation is constrained: it is younger than the age of the youngest rocks cut by thrust faulting and folding (Jurassic) and is older than the age of non-foliated intrusions that cut the deformed strata as well as thrust faults (mid- and Late Cretaceous). Slight variations in these ages occur throughout the belt with variation in age of intrusive activity and age of deformed strata.

The fold belt is characterized by large-scale thrust faulting, open to tight similar folds, imbricate fault zones, and the development of axial planar slaty cleavage. Competent cherts deformed as Chevron folds or isoclinal folds, accommodating significant shortening, with detachment surfaces in less competent strata. In contrast, the thick sequence of competent carbonate rocks of the Mackenzie Platform buckled as large concentric folds and thrust faults, and lacks the slaty cleavage.

Structural trends parallel the arcuate Paleozoic shale-carbonate facies boundary. In some areas complex internal crumpling and faulting may have doubled or tripled stratigraphic thickness without destroying gross stratigraphic integrity.

Faults within Selwyn fold belt have two main orientations: north to northeast trending faults are oblique to the fold trend (<10 kilometres strike length, <400 metres stratigraphic separation), with mostly dip-slope movement; and northwest trending faults are parallel to the trend of folds. Some of these are interpreted as thrusts; most are with dip slip movement. Thrust faults have long strike length, are parallel with fold trends, juxtapose older strata above younger, and cut into stratigraphy along strike.

In western and central Selwyn Fold Belt, strata are folded and imbricated by a series of moderately south-dipping northerly-directed thrust faults. Three principal thrust faults are, from south to north and from older to younger: the Robert Service Thrust, the Tombstone Thrust and the Dawson Thrust. These faults are more than 200 kilometres long and are inferred to root in a single detachment in the Yusezyu Formation of the Hyland Group, with faults cutting progressively deeper in the section from north to south. The intensity of deformation, amount of shortening, and grade of metamorphism all increase from north to south.

The Robert Service Thrust extends from the Dawson map sheet to the northern end of the Mayo map area. In Mayo map area, the Robert Service Thrust sheet gets deformed within the Tombstone Strain Zone.

The Tombstone Thrust parallels the Robert Service Thrust and is characterized by the development of a thick highly strained ductile shear zone in its hanging wall, called the Tombstone Strain Zone ("TSZ") that gradually grades upward into non-strained rocks and juxtaposes progressively older rocks towards the east in both hanging and footwalls, with metamorphic grade increasing toward the east. The thrust probably links into west-northwest striking dextral strike-slip faults of the Macmillan Pass area.

The Tombstone Strain Zone is characterized by prominent foliations and lineations, lenticular compositional layering, shear bands, folding and higher metamorphic grade than rocks outside the zone. TSZ structures and fabrics deform earlier folds and structures resulting in the folding and

imbrication of the earlier Robert Service Thrust. Many kinematic indicators suggest top to the northwest displacement, supported by vergence of asymmetrical folds. The TSZ is itself folded by open regional-scale folds.

The Dawson Thrust fault is a linear Mesozoic thrust more than 200 kilometres long, that sharply juxtaposes basinal rocks on its south side to shallow water platformal sequence on the north side. It forms the southern boundary of Lower Paleozoic shelf-carbonate sequence and the northern boundary of Selwyn Basin. The Ancestral Dawson fault strongly influenced the emplacement of mafic volcanic and intrusive rocks through much of the Paleozoic, Late Proterozoic and possibly earlier. These rocks are in much greater abundance near the Dawson Thrust fault than in equivalent sequences elsewhere. Even though the Dawson thrust marks a significant and sharp boundary between contrasting sedimentary environments, it is interpreted to represent a moderate amount of shortening, with displacement being no greater than displacement on other thrust faults. Offset across the fault could be as little as two to four kilometres. The Dawson Thrust is interpreted to be an ancient underlying basement structure, which repeatedly influenced patterns of sedimentation, igneous activity and faulting, at least since later Proterozoic time.

In the Anvil Range and to the northwest, structure is dominated by moderate southwest dipping or flat-lying strata imbricated by several large northwest trending, northeast directed thrust faults. Detachment surfaces are the base of Devono-Mississippian chert pebble conglomerate or at the base of thick Ordovician volcanics.

In Eastern Selwyn Basin, strike-slip and normal faulting mark the contact with the underlying Proterozoic assemblages. In the Nahanni map area, Devono-Mississippian steep-dipping normal or reverse syn-depositional faults, exhalative barite and Ag-Pb-Zn mineralization suggest an extensional or transtensional regime. Mesozoic deformation is pre Late-Cretaceous and post mid-Triassic. Further north, folding is Early Cretaceous. Some faults are truncated by mid-Cretaceous plutons; others postdate plutonism.

In the Macmillan Pass area (Figure 4), the Macmillan fold belt has a westerly trend and is thought to reflect a deep-seated Devonian fault zone. Folding is tight and a narrow imbricate fault zone of southerly directed east-west trending thrust faults repeats Lower Cambrian to Devonian stratigraphy. South of the imbricate belt, open to closed folds and steep faults are the dominant structures. Some of the steep faults may have been active in the Devonian, forming grabens, and later exerted control on development of the Mesozoic imbricate belt. Northeast from the imbricate belt, structural trend bends northerly to a northwest-southeast orientation. In southwest Macmillan Pass area, the structure is dominated by small to intermediate scale chevron folds in thin-bedded chert of early Paleozoic age. The chert succession has been shortened and thickened but not tilted or imbricated. Displacement was accommodated in the bounding incompetent shales.

Several short-lived pulses of rifting are marked by Cambrian to Devonian unconformities and volcanism. Cretaceous brittle structures control the NNE to ENE steeply dipping veins and faults such as those of the of the Elsa-Keno Hill mining camp silver-lead mineralization. These post-date Tombstone Strain Zone fabrics as well as Cretaceous intrusions but control the emplacement of late dykes.

MacMillan Pass Stratigraphy (Figure 4)

Stratiform deposits of the Macmillan Pass district are hosted by carbonaceous and siliciclastic rocks of the Earn Group that overlie the eastern edge of the Selwyn Basin. In the Macmillan Pass area, the Earn Group ranges in age from Early to Latest Devonian. It is locally subdivided into the Portrait Lake Formation and an alkalic basaltic volcanic suite. Locally, the Portrait Lake Formation is principally divided into the basal Macmillan Pass Member, the informal Tom Member or sequence and the Itsi Member. The Macmillan Pass Member is composed of brown weathering westerly derived shale, conglomerate and sandstone turbidites sandwiching a central chert pebble conglomerate unit; the Tom Sequence consists of blue grey weathering, carbonaceous, radiolarian-rich cherty mudstone and chert; and the Itsi member comprises brown weathering, northerly derived, resistant, micaceous quartz sandstone, siltstone and shale of shallow marine origin. The deposits are confined to a small basin outlined by the outcrop pattern of chert-pebble conglomerates of the Macmillan Pass member and a thickened isopach of the Tom sequence.

Devonian volcanic rocks and related intrusions occur mostly at the base of the Earn Group but in the area of the Boundary Creek prospect, are interbedded with the coarse clastics of the Macmillan Pass Member and have been remobilized into fault scarp proximal diamictites. Conodonts in limestone lens in the volcanics give a Middle Devonian age. Alkalic basaltic volcanism predated and continued up to the time of formation of Zn-Pb deposits and is spatially associated with them, therefore supporting a link between sediment-hosted stratiform deposits and volcanic processes. The volcanics throughout the belt are carbonatized except in the Boundary Creek deposit where complete sideritization is evident.

MacMillan Pass Structure and Tectonic Setting

The host rocks are part of the west-trending Macmillan Fold Belt, which is discordant to the regional northwest structural grain. This fold belt is interpreted to reflect a deep-seated Devonian fault zone that localized facies changes within the Earn Group and also responded differently to Mesozoic deformation. It is divided into three structural blocks based on contrasts in stratigraphy and style of Mesozoic structure: the North, Central and South Blocks.

The ancestral Central block is interpreted as a Devonian graben, a second order basin that was infilled by early coarse clastic turbidites and chert pebble conglomerates, succeeded by thick carbonaceous, cherty and baritic mudstones. The sediments are considerably thicker within the graben and grade laterally into thinner facies on the bounding north and south "horst" blocks. Secondary north-trending syndepositional faults produced localized pull apart, third order basins where they interacted with the major east-trending, graben bounding faults. The complex syndepositional faulting resulted in the deposition of boulder diamictite as debris flows were shed off fault scarps; it also localized early Devonian volcanic centres and the subsequent hydrothermal vents that deposited the base metals.

Late Jurassic and Cretaceous deformation produced three phases of folding and faulting; the second phase of deformation was associated with low-angle thrust faults. Broad open folding and normal faulting characterize the Central block while tighter folding and thrusting is evident in the North and South blocks. The structure of mineralized areas is further complicated by early syndepositional deformation.

PROPERTY GEOLOGY (Metcalfe, 2011)

The only portion of the property mapped in detail by Colorado is the area hosting the historic Neve-Brick minfile occurrence where prior work was done by AGIP. This section describes the lithologies encountered in this area and discusses the structures which possibly control or modify the mineralization.

The following summary and conclusions are excerpts from Colorado's consultant Dr. Paul Metcalfe's report, which can be found in its entirety in Appendix III. Figure 5 shows the geology and a cross-section through the Neve area (J.O.-Saddle-Canol Zones).

Summary

The area mapped during 2011 fieldwork is underlain by a homoclinal sequence of Palæozoic clastic sedimentary rocks with minor limestone and exhalative units. This homoclinal sequence is north-facing, presented in the axis and overturned limb of a north-vergent syncline. The syncline is overthrust from the south by a panel containing Lower Palæozoic Road River Group and is open to the north to the limit of outcrop. Its axial plane dips moderately to the south and its axial plunge appears near-horizontal, but was not determined accurately during 2011 fieldwork.

Rocks exposed in the syncline compose a near-complete paraconformable sequence ranging in age from Ordovician to Mississippian. At the base of this sequence is the Road River Group, comprising siltstone of the Steel Formation overlain by argillaceous limestone of the Sapper Formation. The overlying Devonian Earn Group (Portrait Lake Formation) comprises siliceous shale, argillaceous chert and minor bedded barite of the Niddery Lake member at is base, overlain by siliciclastic rocks of the MacMillan Pass member, in turn overlain by siliceous and carbonaceous shale of the Fuller Lake member. The MacMillan Pass member exhibits a facies variation, fining from chert cobble conglomerate in the east to siltstone in the west. With the exception of a sandy limestone unit near the top of the Fuller Lake member, the Portrait Lake Formation lithologies are non-calcareous. This limestone unit returned conodonts of Late Frasnian age.

Grey shale, siltstone and sandstone overlying the Portrait Lake Formation were identified as the Itsi Formation. This unit is exposed on the south side of the mountain's peak and has a true thickness of roughly 150 metres. The Itsi Formation is overlain by argillaceous chert and siliceous shale grading up into carbonaceous shale and siltstone. A limestone unit near its base returned conodonts of Tournaisian age; lithologies north of the peak are therefore assigned to the basal part of the Tischu Group.

An inferred subvertical fault (the "Secondary Fault") with a strike of 130^{o} repeats the basal Tischu Group section on its north side. The fault is interpreted as downthrown to the north, setting the upright beds to the south against the overturned limb of the fold to the north. The Tischu Group succession north of this fault passes upsection through siliciclastic strata with calcareous cement and a non-calcareous shale unit to the thick Caribou Pass limestone and overlying shale and quartzite units at the limit of exposure.

The sedimentary section has been intruded by numerous irregular subvertical dykes with strikes between 290^o and 310^o. The dykes are peraluminous, with minor garnet as a phenocryst phase and are identified as microgranodiorite porphyry (garnet-bearing, quartz+biotite+plagioclase phyric) in an independent study (Dunne, 2011). The dykes have undergone moderate patchy to intense pervasive phyllic alteration with replacement of all phenocrysts with fine grained dioctahedral mica. The dykes are weakly mineralized with pyrite and arsenopyrite, with late-stage, fracture hosted realgar, orpiment and, less commonly, stibnite. The dykes carry a shear fabric with apparent dextral and minor north side down movement, but their relationship to the Secondary Fault is not known. A second subvertical fault with a strike of 070^o passes to the south of the drill area and offsets the dyke swarm and the Secondary Fault with sinistral sense; displacement is estimated to be 85 metres.

The Oro gold occurrence is hosted by the above stratigraphy, in proximity to the quartz-phyric dykes. It is probable that more consistent grade occurs at the conjunction of the sheared dykes and the reactive argillaceous and silty limestone of the Sapper Formation. It is necessary that any future drill program test the mineralized zone beginning at the shallower, known mineralization, but it is recommended that testing continue to depths where the contact between the Sapper Formation and the overlying Niddery Lake member is predicted by the geometry of the fold. Shallower drilling preceding this deeper testing should take careful note of the limestone units at the base of the Tischu Group and at the top of the Fuller Lake member as aids to refining the fold geometry.

<u>Conclusions</u>
Mapping in 2011 and subsequent analysis indicates that the area is underlain by a homoclinal sequence of Palæozoic clastic sedimentary rocks with minor limestone and exhalative units. This homoclinal sequence is north-facing, presented in the axis and overturned limb of a north-vergent syncline. The syncline is overthrust from the south by a panel containing Lower Palæozoic Road River Group and is open to the north to the limit of outcrop. Its axial plane dips moderately to the south and its axial plunge appears near-horizontal, but was not determined accurately during 2011 fieldwork.

Rocks exposed in the syncline present a near-complete paraconformable sequence ranging in age from Lower Palæozoic Road River Group to Devono-Mississippian Tischu Group. At the base of this sequence is the Road River Group comprising siltstone of the Steel Formation overlain by argillaceous to silty limestone of the Sapper Formation. The overlying Devonian Earn Group (Portrait Lake Formation) includes basal siliceous shale and argillaceous chert of the Niddery Lake member, siliciclastic rocks of the MacMillan Pass member and siliceous and carbonaceous shale of the Fuller Lake member. North of the peak and extending to the Saddle, are basal argillaceous cherts and siliceous shale and siltstone of the Devono-Mississippian Tischu Group. Replication of the basal Tischu section on the other side of the Saddle confirms the presence of the Secondary Fault, but requires vertical rather than strike-slip movement, downthrowing that part of the syncline on the north side of the fault.

The sedimentary sequence is intruded, in the vicinity of the peak by a number of irregular, subvertical dykes with sheared margins, possibly with dextral sense. This sense of movement is inconsistent with the movement of the Secondary Fault and may predate the latter. The shearing,

combined with previous bedding-parallel movement and parasitic folding associated with development of the syncline, will have optimised permeability for hydrothermal fluids. It is suggested here that elongation of the elevated gold zone subparallel to bedding and its coincidence with the location of the dykes implies involvement of the dykes as a heat source for the mineralizing system. A phyllic alteration halo occurs around the dykes and the formation of graphite on bedding and cleavage surfaces in the carbonaceous, siliceous shales is interpreted as a composition-specific response to this phyllic alteration. This might fulfil one requirement of a Carlin-type system, if calcareous units are in proximity. The limestone unit at the base of the Tischu Group is thin but may be responsible for locally elevated gold grades at or near surface in the area drill-tested by AGIP.

Not one but two large calcareous units are available, excluding the Caribou Pass Limestone on the basis of its distance from the dykes. The Squirrel Pass calcareous member within the Tischu Group is much shallower and moreover explicitly in contact with a dyke of the quartz phyric suite on the north side of the Secondary Fault. There is little alteration or mineralization in the vicinity, but the potential of this unit should be noted.

A far more prospective unit is the 150 metre thick argillaceous limestone of the Sapper Formation, overlain by the siliceous and carbonaceous shale of the Niddery Lake member. Indeed the coincidence of the mineralization at surface with this contact on the southern slope of the mountain (the "Canol Zone") was noted by Hulstein and Keyser (1989). Garagan (1983) noted that the syncline's geometry required that the contact between the Sapper argillaceous limestone and the overlying siliceous and carbonaceous shale of the Niddery Lake member be present at between 300 and 500 metres beneath the Saddle Zone. This author suggests a somewhat greater depth of 600 metres or more beneath the peak of the mountain.

This author submits, with respect, that the encouragement encountered in the 1980s drilling records only the tip of the system and that the zone of more regular gold values lies at greater depth. It is recommended that deeper drilling be contemplated and that a closer study made of existing information on gold:silver ratios in the system. Exploration should make use of oriented core with particular attention to core-bedding angles and the location of the two limestone units above and below the Itsi Formation. The target zone for the gold mineralization should be tested from surface to the intersection of the dykes with the Sapper/Niddery Lake contact.

Coincident with the geological mapping of the showing area, Dr. Metcalfe also submitted nine samples for independent petrographic analysis. The petrographic report by Kathryn P.E. Dunne, P.Geo. can be found in Appendix IV. Results of the petrography assisted in interpretation of some of the geological units, most notably the dykes.

8) GEOCHEMISTRY

Lithogeochemistry

In 2011, during the course of geological mapping and prospecting, 746 rock chip and grab samples were collected. Also, a total of 525 three metre contiguous rock chip samples were collected from 15 trenches (for results and discussion – see Trenching section below). Figure 6

shows the rock chip and grab sample numbers and locations. Appendix V is a full listing of all rock sample locations (UTM coordinates), descriptions and results. ACME Labs Certificates of Analyses for rock and trench samples can be found in Appendix VI.

Rock chip samples were collected as continuous rock chips of about golf ball size collected across the true width (wherever possible) of mineralized zones or structures. Grab samples consist of 2 or 3 fist size rock pieces indicative of a certain lithology or mineralization type. Sample sites were marked in the field with spray paint or numbered flagging tape. Samples were put into correspondingly labelled plastic bags with matching bar-coded assay tags inserted and shipped to the laboratory for analyses.

Rock samples were shipped from site via airplane or truck to ACME Laboratory Ltd.'s preparation lab in Whitehorse for sample preparation then shipped on by the laboratory to ACME's Vancouver facility for analyses. All sample preparation was done at the laboratory by their staff. In the laboratory, samples were crushed to minus 200 mesh and fire assayed for gold, plus geochemically analyzed for 36 additional elements by the ICP-MS method.

Statistical analyses were completed for rock and trench sample results. Table II shows percentile breakdowns for select elements which were used for plotting of results.

TABLE II
PERCENTILE VALUES OF ROCK AND TRENCH SAMPLES

percentiles	Au (ppb)	Ag (ppm)	As (ppm)	Sb (ppm)	Hg (ppm)	Bi (ppm)	Tl (ppm)	Zn (ppm)	Ba (ppm)
98%	342.46	4.72	772.30	59.88	40.45	3.60	2.50	1328.60	2974.00
95%	195.00	3.00	499.00	31.75	17.84	1.70	2.00	386.00	2321.00
90%	104.20	1.90	300.50	16.30	9.09	1.10	1.10	217.00	1432.00
75%	18.00	0.90	121.30	6.50	2.27	0.30	0.50	118.00	647.00
50%	4.00	0.20	28.20	1.80	0.32	0.10	0.10	54.00	281.00

Percentile values in this table are somewhat skewed by combining the trench and rock samples, as trench samples overall contain higher gold and indicator element values. It is also interesting to note the relatively high zinc and barium numbers, showing that the property also has sedex mineral association, such as those seen on the nearby Tom (Pb-Zn) and Nidd (Ba) Properties.

Figures 8 to 15 show rock, silt and soil sample results for gold, silver, arsenic, antimony, mercury, bismuth, thallium and zinc, respectively. Results of the rock sampling program will be discussed, along with the soil and silt results, at the end of this geochemistry section.

Soil and Silt Geochemistry

During the 2011 exploration program, a total of 13,808 soil samples and 388 silt samples were collected. Soil sample lines were initially spaced 900 metres apart (to correspond with claim lines), and infilled as results warranted. In the J.O.-Saddle-Canol area, soil lines were spaced much closer, with infill lines in some locations being at 50 metre spacings. Soil samples were

collected at 50 metre intervals along the lines with infill done in key locations at 25 metre sample spacings.

Soil samples were taken from the 'B' soil horizon whenever possible, and were collected using a mattock, shovel or auger. In many instances, samples consisted of talus and scree fines on steeper slopes, and of 'A' horizon soils (sometimes with permafrost) on north facing gentle slopes and in valley bottoms. Three test lines were also put in with a power auger and samples collected near surface and at 90 and 180 centimetre depths along these lines.

Silt samples of stream fines were collected from most of the drainages on the property by manually scooping fine material into labeled cloth stream sediment bags. In areas of talus, coarse particles were screened out of the silt samples at site, in order to ensure sufficient fine material was collected.

Soil and silt sample sites were labelled with fluorescent flagging with the station number recorded on it. Soil was placed in correspondingly labelled Kraft soil bags, while silt samples were placed in cloth silt bags. The soil and silt bags were tagged with bar-coded sample tags, one section of which was stapled to the outside of the bag and a second section inserted into the bag.

At camp, soil and silt samples were dried and sieved to -20 mesh. The -20 mesh fraction was analysed on site utilizing a Niton desk mounted XRF unit. Although gold values do not report accurately by XRF analyses, some pathfinder elements, notably arsenic, were utilized to direct infill and expansion of the soil survey grid. This allowed for daily examination of the XRF data to help direct the exploration program, while awaiting the actual laboratory analyses.

All soil samples were shipped to ACME Laboratory Ltd.'s preparation facility in Whitehorse. The samples were dried, then soil samples were sieved to -230 mesh, while silt samples were sieved to -80 mesh. The prepared samples were then shipped by ACME to their Vancouver laboratory for analyses. The samples were analysed for 36 elements (including gold) by the ICP-MS method.

Appendix VII (in digital version) has a complete database of soil sample locations, descriptions and results. ACME Laboratory Ltd.'s Certificates of Analyses for the soil samples can be seen found in Appendix VIII. Appendix IX (in digital version) has a complete database of silt sample locations, descriptions and results. ACME Laboratory Ltd.'s Certificates of Analyses for the silt samples can be found in Appendix X. Figures 7A to 7D show the soil and silt sample numbers and locations.

Statistical analyses were completed for the soil sample results. Table III shows statistical percentile breakdowns for select elements which were used for plotting of results.

INSERT TABLE III
PERCENTILE VALUES OF SOIL SAMPLES

percentiles	Au (ppb)	Ag (ppm)	As (ppm)	Sb (ppm)	Hg (ppm)	Bi (ppm)	Tl (ppm)	Zn (ppm)	Ba (ppm)
98%	42.7	4.6	307.9	44.7	6.4	0.7	3.3	1551	2497
95%	19.6	3.0	146.9	25.4	2.3	0.5	1.8	881	1877
90%	11.3	2.1	85.4	15.2	1.2	0.4	1.1	508	1333
75%	5.7	1.2	39.7	6.9	0.4	0.3	0.5	245	766
50%	2.9	0.6	21.1	3.1	0.2	0.2	0.2	134	387

Statistical analyses were completed for silt sample results. Table IV shows statistical percentile breakdowns for select elements which were used for plotting of results.

INSERT TABLE IV
PERCENTILE VALUES OF SILT SAMPLES

percentiles	Au (ppb)	Ag (ppm)	As (ppm)	Sb (ppm)	Hg (ppm)	Bi (ppm)	Tl (ppm)	Zn (ppm)	Ba (ppm)
98%	16.4	3.3	227.7	26.4	2.3	0.4	2.5	10000	2314
95%	13.3	2.6	95.5	16.6	1.7	0.3	1.8	4947	1965
90%	8.9	1.8	61.8	12.8	1.1	0.3	1.3	2489	1511
75%	4.9	1.1	39.6	8.0	0.6	0.2	0.9	1255	1083
50%	2.9	0.7	29.2	5.1	0.3	0.2	0.5	593	726

Discussion of Results

Figures 8 through 15 show the property-wide gold, silver, arsenic, antimony, mercury, bismuth, thallium and zinc soil, silt and rock sample values, respectively. Red and pink dots represent the 95th and 98th percentile values for these elements and have their associated values posted. The J.O-Saddle-Canol Zones, Area 51 and the Golden Ridge-North Steel areas have been plotted in more detail on Figures 16, 17, 20 and 21.

J.O.-Saddle-Canol Zones (Neve occurrence)

The Neve occurrence area (J.O.-Saddle-Canol Zones) shows up as a geochemical high for all elements, defining the strong mineralizing system in that vicinity. The correlation between gold (and indictor elements) mineralization with limey sediments, fault and fold structures and intrusive dyke swarms allows for interpretation of two deposit model types.

Throughout the Selwyn trend, Cretaceous aged Tombstone plutonic rocks are responsible for gold occurrences such as at Brewery Bay and Dublin Gulch, where strong Au-As associations occur. These associations are also apparent in the J.O.-Saddle Zones where Cretaceous dykes produce elevations in gold-arsenic and other indicator elements. Of course, these same dykes and nearby fault structures have been interpreted by Metcalfe (2011) to potentially intersect limey Carlin host units at depth below the J.O.-Saddle-Canol Zones. The gold-arsenic mineralization therefore, could also be interpreted to be an indicator of a buried Carlin deposit.

Figure 16 shows the gold values posted on arsenic contours outlining the significant geochemical signatures, with Au soil values as high as 1490 ppb. The gold and arsenic values have a very strong spatial correlation in this area. Figure 17 shows the thallium values plotted on the same arsenic contours for reference. Thallium is considered a key indicator element for Carlin style mineralization in the Yukon and at the Carlin Trend in Nevada. A strong trend of thallium values lies to the southwest of the main arsenic-gold anomaly, along the Canol Zone trend. The Canol Zone does not contain Cretaceous dyke swarms, but does have a much closer association with the limey sedimentary units and is a very important Carlin gold target area.

Silver (Figure 9), antimony (Figure 11) and zinc (Figure 15) also show strong geochemically anomalous trends in the Canol Zone. Mercury (Figure 12) and bismuth (Figure 13) show strong anomalies in the J.O.-Saddle Zone, likely correlating with the intrusive dykes. Additional interpretive work with the geochemical, geological and geophysical data is required in order to fully understand the deposit model signatures and economic potential of this area.

The original geochemical anomaly defined by AGIP in the 1980s covered about one square kilometre. Colorado's 2011 sampling program has expanded this anomalous area over the J.O.-Saddle-Canol Zone to approximately 2.5 kilometres in length, with several of the key indicator elements extending for another 1.5 kilometres to the southeast to join up with the Repeater Zone.

Repeater Zone

The Repeater Zone lies 1.5 kilometres southeast of the J.O.-Saddle-Canol Zones (in fact, along direct trend from the Canol Zone). Although gold geochemistry for soils and rocks is low in this area, it is highly anomalous for most other elements, notably arsenic, antimony, mercury, thallium and zinc. These elements continuously extend along the lithological trend from the Canol Zone, expanding that mineralized trend to 4 kilometres in strike length. Lithologically, the Repeater Zone is underlain by a strongly carbonatized Devonian volcanoclastic unit. Geological/structural mapping is recommended in order to fully understand the significance of the Repeater Zone mineralization and its association to the Canol Zone.

Area 51

In the southeast corner of the Oro Property is another strong geochemically anomalous zone called Area 51. Arsenic and antimony (Figures 10 and 11) values are elevated in this area, associated with spotty high gold geochemical values (up to 1530 ppb). Figure 20 shows in more detail, the gold values plotted on the arsenic contour map. The arsenic-antimony anomaly is approximately 1300 x 250 metres in size.

Unlike the J.O.-Saddle-Canol Zones, Area 51 is associated with a Devonian gabbroic dyke which exhibits strong arsenic alteration and pyrite-arsenopyrite mineralization. This dyke intrudes the Carlin favourable limey siltstones of the Sapper Formation. Geological/structural mapping and detailed soil geochemistry is required in Area 51 in order to determine the significance of this mineralization.

Golden Hinge-Golden Ridge-North Steel Area

Late in the 2011 exploration program, soil samples were collected from a broad east-west trending area hosting the newly termed Golden Hinge, Golden Ridge and North Steel Zones. The Golden

Hinge area lies to the northwest of the J.O.-Saddle-Canol Zones in an area with significant folding of the limey lithologies.

Golden Ridge is probably the most geochemically significant part of the area, with a broad silver signature containing scattered elevated gold values. The silver anomaly trends for 10 kilometres, with an inset gold anomaly extending through the western 6 kilometres (see Figure 21). This trend lines up with a strong regional structure, the Hess River thrust fault, and the adjacent siliceous conglomerate unit. The silver-gold mineralization may represent "leakage" of a buried mineralized body associated with the thrust fault.

The North Steel zone lies in an area of strong structural deformation marked by repetitive northeast-southwest faults. As in the Golden Ridge area, soil sampling has been done only at relatively wide line spacings of 900 or 450 metres. Infill soil sampling, mapping and prospecting is required in this target area in order to better define the core of the mineralized zone.

Limey Ridge

To the east of the J.O.-Saddle-Canol Zones is the newly identified Limey Ridge Zone, consisting of a gold, silver, arsenic and mercury soil geochemical anomaly. The arsenic anomaly extends across 6 grid lines for a distance of 1350 metres. The gold anomaly occurs central to the arsenic anomaly, with gold soil geochemical values up to 1112 ppb.

Thallium Zone

Approximately 6 kilometres west of the J.O.-Saddle-Canol Zones lie two sub-parallel, three kilometre long, east-west trending thallium anomalies of unknown origin (Figure 14). Weak silver and antimony values are associated with these anomalies (Figures 9 and 11).

Conclusion

In general, gold-arsenic-antimony-mercury values occur together, however arsenic is often more widespread and mercury-antimony is less consistent although can return comparatively high values. Bismuth and thallium also often occur with gold, but can also be found in zones independent of gold or other indicators.

9) TRENCHING

In 2011, fifteen trenches, totalling 1548 linear metres, were excavated on the Oro Property. Thirteen of the trenches were located on the mountain hosting the Neve mineralization, while one was located to the northwest and one on the Repeater Zone to the south. Trenches T2011-01 and T2011-02 reopened and expanded historic trenches put in by AGIP in 1982 and 1983. The trenches were designed to test soil geochemical anomalies, contacts and structures believed to be associated with Carlin style gold mineralization.

Trench locations and sample numbers are shown Figure 18. A database with trench sample descriptions and select results can be found in Appendix V and ACME Labs Certificates of Analyses for rock and trench assays can be found in Appendix VI.

Sample Collection, Preparation and Analyses

Sample preparation procedures used by Colorado follow standard industry practice and professional guidelines. After the trenches were mapped, three metre continuous chip samples were collected from the base of the trench wall for the length of the trench. Occasionally a duplicate trench sample was collected from the same site as the original. The trench sample intervals are marked with aluminum tagged pickets labelled with the assay tag number. The chip samples were placed in poly sample bags correspondingly labelled and with a bar coded assay tag inserted into the bag. Standards and blanks were inserted into the sample sequence prior to shipping.

The trench chip samples were shipped by airplane or truck from camp directly to ACME Laboratory Ltd.'s preparation lab in Whitehorse for sample preparation then shipped on by the laboratory to ACME's Vancouver facility for analyses. All sample preparation was done at the laboratory by their staff. In the laboratory, samples were crushed to minus 200 mesh and fire assayed for gold, plus geochemically analyzed for 36 additional elements by the ICP-MS method.

Trench Results

A summary of select trench results has been listed in Table V.

TABLE V
TRENCH SAMPLE RESULTS

TRENCH #	COMMENT	WIDTH (m)	Au (ppb)	Ag (ppm)	As (ppm)	Sb (ppm)	Zn (ppm)	Ba (ppm)
T2011-01	Entire trench	132	111.9	1.9	182	17.5	49	222
	including	12	300.0	2.3	144	17.6	3	153
T2011-02	Entire trench	36	446.3	1.9	355	9.3	65	333
T2011-03	Entire trench	15	105.0	1.2	195	4.7	121	449
T2011-04	Entire trench	231	34.3	1.9	91	11.1	72	301
T2011-05	Entire trench	162	81.9	6.2	138	10.2	159	246
	including	30	390.0	31.5	283	46.6	106	308
	including	6	1218.5	82.4	363	152.4	93	265
T2011-06	Entire trench	30	181.0	0.8	154	7.8	66	635
	including	12	309.5	0.9	200	9.9	78	482
T2011-07	Entire trench	105	1.8	0.2	95	2.1	570	1796
T2011-08	Entire trench	207	21.0	1.3	63	6.9	150	1167
T2011-09	Entire trench	69	142.7	1.0	380	6.9	96	187
	including	9	302.7	0.6	376	2.0	110	173
T2011-10	Entire trench	135	98.6	1.0	483	8.1	82	276
	including	12	316.3	1.4	605	14.3	58	563
T2011-11	Entire trench	30	285.5	1.7	229	16.1	66	193
	Including	6	848.0	2.7	251	35.6	35	241
T2011-12	Entire trench	57	52.8	0.8	165	10.1	125	238
T2011-13	Entire trench	120	41.8	1.2	92	4.3	95	191
	Including	12	312.8	6.0	203	12.3	57	110
T2011-14	Entire trench	84	6.0	0.4	10	0.4	137	1200
T2011-15	Partial trench	48	121.4	1.5	182	88.1	90	760

Figure 19A shows the gold assay values from the trenching program and Figure 19B shows arsenic values. Results from the trenching program are somewhat consistent with previous results from AGIP for the bedrock chip samples. Also, AGIP sampled the talus fines material separately from bedrock and received more highly elevated gold values from this material. Sampling by Colorado included bedrock where exposed and/or talus plus talus fines where bedrock was not exposed. Gold values similar to AGIP's talus fines values were not obtained by Colorado from the media sampled.

However, broad zones of elevated gold grades were obtained, such as 446.3 ppb Au over 36 metres from Trench T2011-02, representing the entire trench length. These elevated gold values, combined with the surrounding large, consistent multi-element soil geochemical anomaly suggest that the trench material may lie distal (above?) to a better mineralized, structurally controlled lithological horizon as suggested by Metcalfe (2011). A substantial diamond drilling program is required to better evaluate the Carlin-style gold mineralization in the Neve area.

10) GEOPHYSICS

Airborne Geophysical Survey

From July 15 to August 2, 2011, a DIGHEM electromagnetic/resistivity/magnetic survey was flown over the Oro Property for Colorado by Fugro Airborne Surveys ("Fugro"). Survey coverage consisted of 2114 line kilometres including 192 line kilometres of tie lines. Flight lines were flown with a line separation of 200 metres. Tie lines were flown perpendicular to the flight direction, with a line spacing of 2000 metres. Flight lines were oriented at 27°/207° and tie lines at 117°/297° (Figure 22).

The survey employed the DIGHEM electromagnetic ("EM") system. Ancillary equipment consisted of a high sensitivity cesium magnetometer, radar and laser altimeters, video camera, digital data recorder, and an electronic navigation system. The instrumentation was installed in an AS-350-B2 turbine helicopter (Registration C-GJIX) that was provided by Questral Helicopters Ltd. The helicopter flew with a nominal EM sensor height of approximately 35 metres.

Table VI lists the corner coordinates of the survey area in NAD83, UTM Zone 9N, central meridian 129°W.

TABLE VI
AIRBORNE SURVEY CORNER COORDINATES

Corners	X-UTM (E)	Y-UTM (N)		Corners	X-UTM (E)	Y-UTM (N)
1	387150	7022700		52	434400	7003800
2	388150	7024432		53	433950	7003021
3	388914	7023991		54	433950	7001100
4	389193	7024337		55	434400	7001100
5	390193	7026069		56	434400	6999300
6	391186	7025496		57	438000	6999300
7	391650	7026300		58	438000	6997950
8	391928	7026300		59	438900	6997950

Corners	X-UTM (E)	Y-UTM (N)		Corners	X-UTM (E)	Y-UTM (N)
9	392509	7027022		60	438900	6997050
10	392847	7026750		61	439800	6997050
11	403350	7026750		62	439800	6993000
12	403350	7026300		63	430800	6993000
13	406050	7026300		64	430800	7000200
14	406050	7025850		65	429900	7000200
15	407850	7025850		66	429900	7001100
16	407850	7025400		67	429000	7001100
17	410550	7025400		68	429000	7001550
18	410550	7024950		69	428100	7001550
19	414150	7024950		70	428100	7002450
20	414150	7016400		71	427200	7002450
21	415050	7016400		72	427200	7002900
22	415050	7015950		73	426300	7002900
23	415950	7015950		74	426300	7003350
24	415950	7015500		75	425400	7003350
25	416850	7015500		76	425400	7003800
26	416850	7015050		77	424500	7003800
27	418650	7015050		78	424500	7004250
28	418650	7014600		79	423150	7004250
29	419550	7014600		80	423150	7005150
30	419550	7013700		81	415050	7005150
31	417699	7013700		82	415050	7010100
32	415950	7010671		83	411450	7010100
33	415950	7009650		84	411450	7010550
34	416850	7009650		85	405150	7010550
35	416850	7008750		86	405150	7011000
36	422583	7008751		87	399750	7011000
37	423189	7009800		88	399750	7011900
38	423652	7009790		89	397950	7011900
39	423639	7009333		90	397950	7014150
40	423303	7008750		91	392550	7014150
41	424050	7008750		92	392550	7017300
42	424050	7007850		93	391650	7017300
43	426750	7007850		94	391650	7018200
44	426750	7007400		95	390750	7018200
45	427650	7007400		96	390750	7018650
46	427650	7006950		97	389850	7018650
47	430800	7006950		98	389850	7019550
48	430800	7004700		99	388950	7019550
49	432600	7004700		100	388950	7020000
50	432600	7004250		101	388050	7020000
51	434400	7004250		102	388050	7020450
				103	387150	7020450

Figures 23 and 24 are coloured contour plots of the airborne magnetics. Overlain on the Total Magnetic Intensity ("TMI") and Tilt Derivative ("TD") magnetic plots are the soil geochemistry contours for gold, silver, arsenic, antimony and thallium values and geologic structures for reference.

The TMI plot (Figure 23) shows a prominent magnetic high feature on the west side of the claim block. This may be related to a buried intrusive, but no outcrop evidence supports this theory. Neither is there elevated soil geochemistry in this area. A second prominent, albeit smaller, magnetic high is located in the vicinity of the Neve (J.O.-Saddle Zones). This magnetic feature is probably related to the abundant Cretaceous dykes located in this area, which are likely feeders to buried intrusive body. A few smaller, less significant magnetic high features trend across the southeastern portion of the Oro Property.

The Tilt Derivative plot (Figure 24) details more structural information. The general NW-SE lithological trend is readily apparent, especially in the southern half of the property. The most prominent feature on this map is a strong NW-SE high paralleling the Golden Ridge Zone, related either to the conglomerate unit or the underlying thrust fault. Several cross structures show up on this plot, and additional geophysical interpretations are recommended in order to fully evaluate the importance of the various features projected.

Figure 25 and 26 are coloured contour plots of apparent resistivities using 7200 Hz and 56,000 Hz frequencies, respectively. By no coincidence, the Neve area (J.O.-Saddle-Canol Zones) lies along a strong structural break as shown by the steep resistivity gradients. Cross structures, which are important in Carlin gold systems, are also visible trending through this area. As with the Tilt Derivative, the Golden Ridge Zone also shows up prominently as a resistivity high feature. Other zones, such as the Repeater Zone and Area 51 lie generally within a belt of low resistivities with subtle associated highs. As with the magnetic data, it is recommended that more detailed geophysical interpretations also be undertaken with the resistivity data in order to identify important features for follow up exploration work.

Table VII summarizes the discrete EM anomaly responses interpreted from the survey data with respect to conductance grade and interpretation for the survey areas. Fugro's interpretation map, which includes magnetic and EM anomalies, is shown on Figure 27.

TABLE VII
EM ANOMALY STATISTICS

CONDUCTOR GRADE	CONDUCTANCE RANGE SIEMENS (MHOS)	NUMBER OF RESPONSES
7	>100	124
6	50 – 100	164
5	20 – 50	441
4	10 – 20	683
3	5 – 10	1057
2	1 – 5	6529
1	<1	2246
*	INDETERMINATE	257
	TOTAL	11501

CONDUCTOR MODEL	MOST LIKELY SOURCE	NUMBER OF RESPONSES
D	DISCRETE BEDROCK CONDUCTOR (THIN DYKE MODEL)	1392
B	BEDROCK CONDUCTOR	6460
S	CONDUCTIVE COVER	3524
E	EDGE OF WIDE CONDUCTOR	10
H	ROCK UNIT OR THICK COVER	115
	TOTAL	11501

The interpretation map (Figure 27) shows prominent magnetic and conductive zones outlined in red or blue, respectively. Linear features that have been interpreted from either the magnetic or resistivity data, and which may reflect possible structural breaks within the survey area, are shown with a dashed green line.

The Oro Property survey area is dominated by a highly conductive zone, R1. It seems to reflect a broad conductive unit, which is made up of multiple, closely spaced, thin conductive trends. The conductivity associated with R1 seems to reflect sources at depth, as the low frequency resistivities are generally lower than those calculated from the high frequency. The changes in the calculated resistivities one frequency to another, gives an approximation of the subsurface.

Conductivity depth sections, such as differential resistivity sections, may be useful in defining the characteristics of complex conductive units such as R1. Differences in depth to conductor, and change in conductivity with depth are readily apparent.

R1 displays some correlation with the magnetic data, as many of the possible breaks identified on the magnetic parameters are also on the resistivity parameters. Several moderately magnetic units, M1, M2 and M3, are situated near the edges of conductive zone R1. All are situated in areas of complexity in the magnetic data, as many prominent breaks are evident in the vicinity of all three magnetic zones. M1 is situated at the northern limit of R1. It is interesting as it seems to be part of an oval shaped magnetic feature defined on the calculated first vertical magnetic derivative map. This also lines up with the J.O.-Saddle-Canol Zones.

M5 differs from M1, M2 and M3 as it is situated within R1 rather than near the edge of the zone. It is coincident with a resistive zone within R1 which is associated with a topographic high. This area is underlain by Devonian volcanic units.

Less extensive conductive zones, R2 and R3, reflect conductive sources at depth. Neither displays any direct correlation with the magnetic data, as they are situated within the relatively non-magnetic northwest area of the survey block. R4, which is situated to the north of R1, also reflects possible bedrock conductivity. Its southern limit is coincident with a prominent northwest/southeast trending break in the magnetic data.

M4 is a complex magnetic zone, with magnetic features generally associated with topographic highs. Many possible structural features, inferred from the magnetic data, intersect this zone. The strongest magnetic feature within M4 is situated at the northern edge of the zone, immediately to

the west of a prominent north-northwest/south-southeast trending magnetic break. Conductive zone R5 is situated along this break, and may reflect weakly conductive features at depth.

Extensive conductive zones such as R1 often reflect formational conductors that may be of minor interest as direct exploration targets. However, attention may be focused on areas where these zones appear to be faulted or folded or where anomaly characteristics differ along strike. Such structural breaks are considered to be of particular interest as they may have influenced mineral deposition within the survey area.

Fugro's conclusions and recommendations state:

The survey has been successful in mapping the magnetic and conductive properties of the survey areas. The survey was also successful in locating anomalous zones that may warrant additional work. The various maps included with this report display the magnetic and conductive properties of the survey areas. It is recommended that a complete assessment and detailed evaluation of the survey results be carried out, in conjunction with all available geophysical, geological and geochemical information.

The interpreted bedrock conductors and anomalous targets defined by the survey should be subjected to further investigation, using appropriate surface exploration techniques. Anomalies that are currently considered to be of moderately low priority may require upgrading if follow-up results are favourable.

It is also recommended that image processing of existing geophysical data be considered, in order to extract the maximum amount of information from the survey results. Current software and imaging techniques often provide valuable information on structure and lithology, which may not be clearly evident on the contour and colour maps. These techniques can yield images that define subtle, but significant, structural details.

The entire Fugro report can be seen in Appendix XI.

ASTER Imagery

In 2011, Colorado contracted Ward Kilby, P.Geo. of Cal Data Ltd. to conduct an ASTER Satellite Imagery review on the Oro Property. The following summary, conclusions and recommendations are excerpted from the report, which can be found in its entirety in Appendix XII.

Summary

Cal Data Ltd. was contracted by Colorado Resources Ltd. to acquire and analyze ASTER Multispectral imagery covering the ORO claim group in eastern Yukon. A search for available ASTER and other imagery was performed. The claim area had very poor ASTER coverage with all imagery having issues with cloud cover or sensor problems.

Good LandSat 7 (ETM+) imagery was available for the claim group. Initially the best available ASTER image was purchased. The preview image showed some problems with the image in the area of the claims but it was felt there could be some useful portions. Unfortunately when acquired virtually the whole region of the claims was useless. The LandSat image was processed

and evaluated. LandSat only has reasonable spectral coverage in the VNIR portion of the spectrum with very limited capabilities in the SWIR (one band). Examination of the LandSat image showed several areas of potential interest.

Two additional ASTER images were acquired to add some additional spectral and spatial resolution in the areas of interest from the LandSat evaluation.

The LandSat image files were obtained through the NASA Land Processes Distribution Active Archive Center (LPDAAC) at no cost. The required ASTER imagery was identified through the LPDAAC website and then purchased from ERSDAC (Earth Remote Sensing Data Analysis Centre) in Japan.

The claim area was fully exposed in the LandSat image but significantly cloud covered in the ASTER images. The two ASTER images that were used in the analysis had VNIR and TIR sensor data and one had SWIR data.

Image analysis included converting the imagery from digital number format (DN) to relative reflectance values through standard preprocessing techniques. The imagery was rectified to the UTM Zone 9 projection, WGS 84 datum.

A full range of products were constructed from the imagery. In the case of the LandSat image these included a pan-sharpened natural colour image, temperature map as well as the mineral maps generated during the analysis. In the case of the ASTER imagery the products included; near-natural colour imagery, DEMs, anaglyph images, temperature maps and mineral maps generated from the spectral analysis.

The spectral analysis was performed on the ORO claim area using hyperspectral and multispectral techniques on both the LandSat and ASTER imagery. Any mineral or rock identification made based on ASTER or LandSat spectra must be considered an estimate as the spectral and spatial resolution of the sensors is not adequate to positively identify individual materials in most cases.

<u>Conclusions and Recommendations</u>
Standard LandSat analysis techniques were applied to the imagery with good results. Crosta Targeted Principal Component Analysis mapped hydroxyl and iron-oxide bearing minerals nicely. Spectral Angle Mapping using spectra from the ORO deposit and a potential jarosite occurrence highlighted a number of sites for field investigation. The 5^{th} factor of a Tasseled Cap transformation also highlighted prospective areas. In most cases all the above analysis tended to identify the same areas. The fact that the known Neve area (J.O.-Saddle-Canol Zones) was positive in all these mappings suggests that other sites identified with these methods may be important. When selecting targets from the analysis reference should always be made to the corresponding natural colour imagery to assure that the prospective area is rock and not some combination of clouds, snow or vegetation that could have a spectral signature similar to the targeted rock. When examining all the mineral map images one should only assume that the very best image matches (red pixels) represent the subject spectra.

Silicification was mapped with the ASTER emissivity data. When using this technique it is especially important to assure that the highlighted pixels are representing good rock exposure as clouds and the thin edges of clouds can give a very similar thermal signature to quartz. Only through field verification should any reference to the existence of a mineral be taken as a given.

In addition to the mineral mappings a number of products were generated from the ASTER data. These included natural colour images, digital elevation models and temperature maps.

The Aster and Landsat imagery spectral plots identified a number of colour anomalies and potential indicator mineral occurrences. In order to provide the best usage, these plots need to be used in conjunction with geological, geochemical and geophysical data. The main Neve occurrence area shows up strongly in multiple parameters, but weaker anomalies have not yet been examined in the field.

11) CONCLUSIONS

On the Oro Property gold and associated indicator element geochemistry, combined with airborne geophysical survey results, have identified several significant mineralized zones.

The Oro Property lies within the Selwyn Basin, along the geological trend from Atac Resources Ltd.'s Carlin gold discoveries. The Neve occurrence (J.O.-Saddle-Canol Zones) was identified in the 1980s by AGIP Canada Ltd. as having the potential to host Carlin style gold mineralization. Geological, geochemical and geophysical work completed in 2011 by Colorado corroborates AGIP's conclusions.

Throughout the Selwyn trend, Cretaceous aged Tombstone plutonic rocks are responsible for gold occurrences such as at Brewery Creek and Dublin Gulch, where strong Au-As associations occur. These associations are also apparent in the J.O.-Saddle Zones where Cretaceous dykes produce elevations in gold-arsenic and other indicator elements. As well, these same dykes and nearby fault structures have been interpreted by Metcalfe (2011) to potentially intersect limey Carlin host units at depth below the J.O.-Saddle-Canol Zones. The gold-arsenic mineralization therefore, could also be interpreted to be an indicator of a buried Carlin deposit.

Detailed geological/structural mapping carried out in the J.O.-Saddle-Canol Zones identified three potential limestone host units, calculated their geometries and postulated their locations of interception with structures (faults and dykes) that may be responsible for deposition of Carlin style gold mineralization. These structural intersections are key diamond drilling targets for 2012.

A good geological compilation map has been produced for most of the Oro Property by Abbott (2012) showing the lithological trends and significant structures. This geology provides a good base for correlations and interpretations of the airborne geophysical survey . More detailed geophysical interpretations are required in order to fully understand the significance of the various anomalous trends and structural breaks identified.

The geochemical surveys produced several strong, often multi-element anomalous zones. Again the geochemistry highlights the J.O.-Saddle-Canol zones, expanding the anomalies to a four kilometre strike length. Several additional areas such as Golden Hinge, Golden Ridge, North Steel, Area 51, Limey Ridge and Repeater Zone also have strong multi-element soil geochemical signatures. Detailed follow up is required in 2012 in order to determine the significance of these anomalous areas.

12) RECOMMENDATIONS

Due to the success of the exploration program on the Oro Property in 2011, an expanded program is recommended for 2012. The 2012 exploration program should consist of continued infill soil geochemical sampling and geological mapping in key target areas. Up to 10,000 soil samples should be collected. Excavator trenching is recommended to follow up soil geochemical anomalies, along with 5000 metres of diamond drilling.

While the soil sampling, trenching and mapping is planned to be conducted over several anomalous areas, diamond drilling should at least initially target the Neve occurrence area (J.O.-Saddle-Canol Zones) where structural mapping, geophysics and geochemical indicators all suggest a strong possibility of locating a buried Carlin gold target.

Estimated cost for the 2012 exploration program is $4.5 million. Work should commence in mid to late May as soon as conditions allow.

Respectfully submitted,

Linda Dandy, P.Geo.
February 22, 2012

13) REFERENCES

ABBOTT, J.G., In Publication; Geology of the MacMillan Pass Area: Yukon Geological Survey, Open File 2012-1.

ABBOTT, J.G., 1983; Structure and Stratigraphy of the MacMillan Fold Belt – Evidence for Devonian Faulting: Geological Survey of Canada Open File 1983-1.

AUPPERLE, M.J., 1985; Assessment Report Brick 1-40 and Neve 1-35 Claims for AGIP Canada Ltd.: Yukon Assessment Report #091770.

BEAUCHAMP, D.A., 1980; Geological Assessment Report Neve Claims for AGIP Canada Ltd.: Yukon Assessment Report #090706.

DEKLERK, R.P., 1982; Geochemical Survey of a Pb-Zn Prospect, Selwyn Basin YT: University of Windsor – Bachelor of Science Thesis.

GARAGAN, T., 1981; Assessment Report Geological Mapping and Geochemical Sampling, Brick Claims for AGIP Canada Ltd.: Yukon Assessment Report #091056.

GARAGAN, T., 1982; Assessment Report Geochemical Sampling Neve Claims for AGIP Canada Ltd.: Yukon Assessment Report #091388.

GARAGAN, T., 1982; Assessment Report Trenching Brick Claims for AGIP Canada Ltd.: Yukon Assessment Report #091389.

GARAGAN, T., 1983; Assessment Report Overburden Drilling Brick Claims for AGIP Canada Ltd.: Yukon Assessment Report #091455.

HEON, D. (compiled by), Selwyn Basin Metallogeny: Yukon Geological Survey Website.

HODSON, T.W., 1984; Assessment Report Geochemistry, Geophysics, Diamond Drilling and Road Building - Nidd Property for Cominco Ltd.: Yukon Assessment Report #091509.

HULSTEIN, R.W. and KEYSER, H.J., 1989; Assessment Report on the 1988 Exploration Program on the Brick Property for AGIP Resources Ltd.: Yukon Assessment Report #092742.

ISREAL, S., COLPRON, M., ROOTS, C. and FRASER, T.; Overview of Yukon Geology: Yukon Geological Survey.

MINING YUKON, MINING AND EXPLORATION PORTAL, 2011; Bedrock Geology of Yukon.

RHODES, D., 1985; Assessment Report Geochemistry - Nidd Property for Cominco Ltd.: Yukon Assessment Report #091606.

ROBERTSON, R.C.R., 1984; Assessment Report Trenching Brick 4 and Brick 9 Claims for AGIP Canada Inc.: Yukon Assessment Report #091544.

ROOTS, C.F. ABBOTT, J.G. CECILE, M.P. GORDEY, S.P., 1995; Bedrock Geology of Lansing Range Map Area (105N), East Half, Hess Mountains, Yukon: Exploration and Geological Services, Yukon Region, and Indian and Northern Affairs Canada.

STROSHEIN, R., 1980; Assessment Report on Geochemical and Geological Surveys – Mac Claims for Hudson Bay Mining and Exploration Ltd.: Yukon Assessment Report # 090666.

TRAVIS, M.S., 1977; Geological and Geochemical Assessment Report on the Nidd Claim Group for Cominco Ltd.: Yukon Assessment Report #090231.

YUKON MINFILE, Neve 105O 032, Gow 105O 029, Fal 105O 042, Stroshein 105O 045, Minorco 105O 046: Yukon Geological Survey.

14) COST STATEMENTS

Two separate work filings were done in 2011 for the Oro Property. The initial filing covered the airborne geophysical survey costs. The second, later filing included the field work component of the 2011 exploration program. For this second filing, the claims were put into 3 groups. The cost statement is broken down to reflect the two work filings and the 3 individual groupings. This report covers all the work complete on the property in 2011.

INITIAL FILING – AIRBORNE GEOPHYSICAL SURVEY

AIRBORNE GEOPHYSICAL SURVEY: 2114 line km @ $188	$397,432.00
FOOD AND ACCOMMODATION (Mac Pass): 52 mandays @ $400	20,800.00
TRANSPORT AND MOBILIZATION:	16,500.00
TOTAL AIRBORNE GEOPHYSICAL SURVEY COSTS:	$434,732.00

2ND FILING – GROUP 1

GEOLOGISTS:	108 days @ $750	$ 81,000.00
PROSPECTORS:	81 days @ $500	40,500.00
SAMPLERS:	198 days @ $450	89,100.00
ANALYSES:	1090 ROCK SAMPLES @ $30.05	32,755.00
	9921 SOIL/SILT SAMPLES @ $21.08	209,135.00
HELICOPTER:	413 HOURS @ $1250	516,250.00
	FUEL	76,322.00
MINI-EXCAVATORS:	720 HOURS @$50	36,000.00
	OPERATORS: 105 days @ $450	47,250.00
FOOD AND ACCOMMODATION (Watson Lake) 620 mandays @ $400:		248,000.00
SUPPLIES, FREIGHT, TRAVEL AND MISCELLANEOUS:		25,500.00
REPORT PREPARATION:		19,000.00
TOTAL COSTS:		$1,420,812.00

2ND FILING – GROUP 2

GEOLOGIST:	5 days @ $750	$ 3,750.00
PROSPECTORS:	23 days @ $500	11,500.00
SAMPLERS:	82 days @ $450	36,900.00
ANALYSES:	26 ROCK SAMPLES @ $30.05	781.00
	2480 SOIL/SILT SAMPLES @ $21.08	52,278.00
HELICOPTER:	100.5 HOURS @ $1250	125,625.00
	FUEL	18,572.00
FOOD AND ACCOMMODATION (Watson Lake) 142 mandays @ $400:		56,800.00
SUPPLIES, FREIGHT, TRAVEL AND MISCELLANEOUS:		9,500.00
REPORT PREPARATION:		7,500.00
TOTAL COSTS:		$323,206.00

2ND FILING – GROUP 3

GEOLOGIST:	5 days @ $750	$ 3,750.00
PROSPECTORS:	28 days @ $500	14,000.00
SAMPLERS:	58 days @ $450	26,100.00
ANALYSES:	123 ROCK SAMPLES @ $30.05	3,696.00
	1754 SOIL/SILT SAMPLES @ $21.08	36,975.00
HELICOPTER:	68 HOURS @ $1250	85,000.00
	FUEL	12,566.00
FOOD AND ACCOMMODATION (Watson Lake) 119 mandays @ $400:		47,600.00
SUPPLIES, FREIGHT, TRAVEL AND MISCELLANEOUS:		7,500.00
REPORT PREPARATION:		7,000.00
TOTAL COSTS:		$244,187.00

15) QUALIFICATIONS

I, Linda Dandy, hereby certify that:

1. I am a Consulting Geologist having an office at 4900 Warm Bay Road, Atlin, British Columbia, V0W 1A0.

2. I am a graduate of the University of British Columbia with the degree of Bachelor of Science in Geology (1981).

3. I am a member of the Association of Professional Engineers and Geoscientists of British Columbia (Registration No. 19236) and a Fellow of the Geological Association of Canada (Membership No. F5201).

4. I have practiced my profession in North America since 1981, having worked as an employee and consultant for Major Mining Corporations, Junior Resource Companies and government.

5. This report is based upon personal examination of all available company and government reports pertinent to the subject property, and upon fieldwork undertaken on the property from June to September 2011. I have directly supervised all field work on the property.

February 22, 2012
Atlin, BC

Linda Dandy, P.Geo.
Consulting Geologist

APPENDICES

APPENDIX I – FIGURES 1 TO 27

APPENDIX II – QUARTZ CLAIM INFORMATION

APPENDIX III – PAUL METCALFE GEOLOGY REPORT

APPENDIX IV – KATHRYN DUNN PETROGRAPHIC REPORT

APPENDIX V – ROCK AND TRENCH SAMPLES – LOCATIONS, DESCRIPTIONS AND RESULTS (FULL DATABASE IN DIGITAL VERSION ONLY)

APPENDIX VI - ROCK AND TRENCH SAMPLE RESULTS – ACME LABS LTD. CERTIFICATES OF ANALYSES (DIGITAL VERSION ONLY)

APPENDIX VII – SOIL SAMPLE LOCATIONS, DESCRIPTIONS AND RESULTS (FULL DATABASE IN DIGITAL VERSION ONLY)

APPENDIX VIII – SOIL SAMPLE RESULTS – ACME LABS LTD. CERTIFICATES OF ANALYSES (DIGITAL VERSION ONLY)

APPENDIX IX – SILT SAMPLE LOCATIONS, DESCRIPTIONS AND RESULTS (FULL DATABASE IN DIGITAL VERSION ONLY)

APPENDIX X – SILT SAMPLE RESULTS – ACME LABS LTD. CERTIFICATES OF ANALYSES (DIGITAL VERSION ONLY)

APPENDIX XI – AIRBORNE GEOPHYSICAL SURVEY - REPORT BY FUGRO (RAW DATA IN DIGITAL VERSION ONLY)

APPENDIX XII – ASTER IMAGERY

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YD31351	Quartz	Oro	1	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31352	Quartz	Oro	2	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31353	Quartz	Oro	3	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31354	Quartz	Oro	4	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31355	Quartz	Oro	5	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31356	Quartz	Oro	6	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31357	Quartz	Oro	7	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31358	Quartz	Oro	8	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31359	Quartz	Oro	9	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31360	Quartz	Oro	10	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31361	Quartz	Oro	11	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31362	Quartz	Oro	12	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31363	Quartz	Oro	13	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31364	Quartz	Oro	14	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31365	Quartz	Oro	15	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31366	Quartz	Oro	16	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31367	Quartz	Oro	17	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31368	Quartz	Oro	18	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31369	Quartz	Oro	19	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31370	Quartz	Oro	20	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31371	Quartz	Oro	21	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31372	Quartz	Oro	22	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31373	Quartz	Oro	23	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31374	Quartz	Oro	24	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31375	Quartz	Oro	25	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31376	Quartz	Oro	26	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31377	Quartz	Oro	27	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31378	Quartz	Oro	28	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31379	Quartz	Oro	29	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31380	Quartz	Oro	30	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31381	Quartz	Oro	31	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31382	Quartz	Oro	32	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31383	Quartz	Oro	33	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31384	Quartz	Oro	34	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31385	Quartz	Oro	35	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31386	Quartz	Oro	36	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31387	Quartz	Oro	37	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31388	Quartz	Oro	38	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31389	Quartz	Oro	39	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31390	Quartz	Oro	40	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31391	Quartz	Oro	41	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31392	Quartz	Oro	42	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31393	Quartz	Oro	43	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31394	Quartz	Oro	44	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31395	Quartz	Oro	45	Cathro Resource Corp. - 100%	18-Nov-14

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YD31396	Quartz	Oro	46	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31397	Quartz	Oro	47	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD31398	Quartz	Oro	48	Cathro Resource Corp. - 100%	18-Nov-14
Mayo	YD104903	Quartz	Oro	49	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104904	Quartz	Oro	50	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104905	Quartz	Oro	51	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104906	Quartz	Oro	52	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104907	Quartz	Oro	53	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104908	Quartz	Oro	54	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104909	Quartz	Oro	55	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104910	Quartz	Oro	56	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104911	Quartz	Oro	57	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104912	Quartz	Oro	58	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104913	Quartz	Oro	59	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104914	Quartz	Oro	60	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104915	Quartz	Oro	61	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104916	Quartz	Oro	62	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104917	Quartz	Oro	63	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104918	Quartz	Oro	64	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104919	Quartz	Oro	65	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104920	Quartz	Oro	66	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104921	Quartz	Oro	67	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104922	Quartz	Oro	68	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104923	Quartz	Oro	69	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104924	Quartz	Oro	70	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104925	Quartz	Oro	71	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104926	Quartz	Oro	72	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104927	Quartz	Oro	73	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104928	Quartz	Oro	74	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104929	Quartz	Oro	75	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104930	Quartz	Oro	76	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104931	Quartz	Oro	77	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104932	Quartz	Oro	78	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104933	Quartz	Oro	79	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104934	Quartz	Oro	80	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104935	Quartz	Oro	81	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104936	Quartz	Oro	82	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104937	Quartz	Oro	83	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104938	Quartz	Oro	84	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104939	Quartz	Oro	85	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104940	Quartz	Oro	86	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104941	Quartz	Oro	87	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104942	Quartz	Oro	88	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104943	Quartz	Oro	89	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104944	Quartz	Oro	90	Cathro Resource Corp. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YD104945	Quartz	Oro	91	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104946	Quartz	Oro	92	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104947	Quartz	Oro	93	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104948	Quartz	Oro	94	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104949	Quartz	Oro	95	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104950	Quartz	Oro	96	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104951	Quartz	Oro	97	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104952	Quartz	Oro	98	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104953	Quartz	Oro	99	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104954	Quartz	Oro	100	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104955	Quartz	Oro	101	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104956	Quartz	Oro	102	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104957	Quartz	Oro	103	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104958	Quartz	Oro	104	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104959	Quartz	Oro	105	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104960	Quartz	Oro	106	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104961	Quartz	Oro	107	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104962	Quartz	Oro	108	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104963	Quartz	Oro	109	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104964	Quartz	Oro	110	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104965	Quartz	Oro	111	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104966	Quartz	Oro	112	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104967	Quartz	Oro	113	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104968	Quartz	Oro	114	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104969	Quartz	Oro	115	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104970	Quartz	Oro	116	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104971	Quartz	Oro	117	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104972	Quartz	Oro	118	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104973	Quartz	Oro	119	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104974	Quartz	Oro	120	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104975	Quartz	Oro	121	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104976	Quartz	Oro	122	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104977	Quartz	Oro	123	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104978	Quartz	Oro	124	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104979	Quartz	Oro	125	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104980	Quartz	Oro	126	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104981	Quartz	Oro	127	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104982	Quartz	Oro	128	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104983	Quartz	Oro	129	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104984	Quartz	Oro	130	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104985	Quartz	Oro	131	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104986	Quartz	Oro	132	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104987	Quartz	Oro	133	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104988	Quartz	Oro	134	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104989	Quartz	Oro	135	Cathro Resource Corp. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YD104990	Quartz	Oro	136	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104991	Quartz	Oro	137	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104992	Quartz	Oro	138	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104993	Quartz	Oro	139	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104994	Quartz	Oro	140	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104995	Quartz	Oro	141	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104996	Quartz	Oro	142	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104997	Quartz	Oro	143	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104998	Quartz	Oro	144	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD104999	Quartz	Oro	145	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105000	Quartz	Oro	146	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105001	Quartz	Oro	147	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105002	Quartz	Oro	148	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105003	Quartz	Oro	149	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105004	Quartz	Oro	150	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105005	Quartz	Oro	151	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105006	Quartz	Oro	152	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105007	Quartz	Oro	153	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105008	Quartz	Oro	154	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105009	Quartz	Oro	155	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105010	Quartz	Oro	156	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105011	Quartz	Oro	157	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105012	Quartz	Oro	158	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105013	Quartz	Oro	159	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105014	Quartz	Oro	160	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105015	Quartz	Oro	161	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105016	Quartz	Oro	162	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105017	Quartz	Oro	163	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105018	Quartz	Oro	164	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105019	Quartz	Oro	165	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105020	Quartz	Oro	166	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105021	Quartz	Oro	167	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105022	Quartz	Oro	168	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105023	Quartz	Oro	169	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105024	Quartz	Oro	170	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105025	Quartz	Oro	171	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105026	Quartz	Oro	172	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105027	Quartz	Oro	173	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105028	Quartz	Oro	174	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105029	Quartz	Oro	175	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105030	Quartz	Oro	176	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105031	Quartz	Oro	177	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105032	Quartz	Oro	178	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105033	Quartz	Oro	179	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105034	Quartz	Oro	180	Cathro Resource Corp. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YD105035	Quartz	Oro	181	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105036	Quartz	Oro	182	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105037	Quartz	Oro	183	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105038	Quartz	Oro	184	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105039	Quartz	Oro	185	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105040	Quartz	Oro	186	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105041	Quartz	Oro	187	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105042	Quartz	Oro	188	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105043	Quartz	Oro	189	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105044	Quartz	Oro	190	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105045	Quartz	Oro	191	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105046	Quartz	Oro	192	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105047	Quartz	Oro	193	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105048	Quartz	Oro	194	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105049	Quartz	Oro	195	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105050	Quartz	Oro	196	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105051	Quartz	Oro	197	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105052	Quartz	Oro	198	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105053	Quartz	Oro	199	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105054	Quartz	Oro	200	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105055	Quartz	Oro	201	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105056	Quartz	Oro	202	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105057	Quartz	Oro	203	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105058	Quartz	Oro	204	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105059	Quartz	Oro	205	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105060	Quartz	Oro	206	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105061	Quartz	Oro	207	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105062	Quartz	Oro	208	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105063	Quartz	Oro	209	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105064	Quartz	Oro	210	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105065	Quartz	Oro	211	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105066	Quartz	Oro	212	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105067	Quartz	Oro	213	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105068	Quartz	Oro	214	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105069	Quartz	Oro	215	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105070	Quartz	Oro	216	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105071	Quartz	Oro	217	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105072	Quartz	Oro	218	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105073	Quartz	Oro	219	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105074	Quartz	Oro	220	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105075	Quartz	Oro	221	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105076	Quartz	Oro	222	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105077	Quartz	Oro	223	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105078	Quartz	Oro	224	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105079	Quartz	Oro	225	Cathro Resource Corp. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YD105080	Quartz	Oro	226	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105081	Quartz	Oro	227	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105082	Quartz	Oro	228	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105083	Quartz	Oro	229	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105084	Quartz	Oro	230	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105085	Quartz	Oro	231	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105086	Quartz	Oro	232	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105087	Quartz	Oro	233	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105088	Quartz	Oro	234	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105089	Quartz	Oro	235	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105090	Quartz	Oro	236	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105091	Quartz	Oro	237	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105092	Quartz	Oro	238	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105093	Quartz	Oro	239	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105094	Quartz	Oro	240	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105095	Quartz	Oro	241	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105096	Quartz	Oro	242	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105097	Quartz	Oro	243	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105098	Quartz	Oro	244	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105099	Quartz	Oro	245	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105100	Quartz	Oro	246	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105101	Quartz	Oro	247	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105102	Quartz	Oro	248	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105103	Quartz	Oro	249	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105104	Quartz	Oro	250	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105105	Quartz	Oro	251	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105106	Quartz	Oro	252	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105107	Quartz	Oro	253	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105108	Quartz	Oro	254	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105109	Quartz	Oro	255	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105110	Quartz	Oro	256	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105111	Quartz	Oro	257	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105112	Quartz	Oro	258	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105113	Quartz	Oro	259	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105114	Quartz	Oro	260	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105115	Quartz	Oro	261	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105116	Quartz	Oro	262	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105117	Quartz	Oro	263	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105118	Quartz	Oro	264	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105119	Quartz	Oro	265	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105120	Quartz	Oro	266	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105121	Quartz	Oro	267	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105122	Quartz	Oro	268	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105123	Quartz	Oro	269	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105124	Quartz	Oro	270	Cathro Resource Corp. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YD105125	Quartz	Oro	271	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105126	Quartz	Oro	272	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105127	Quartz	Oro	273	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105128	Quartz	Oro	274	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105129	Quartz	Oro	275	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105130	Quartz	Oro	276	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105131	Quartz	Oro	277	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105132	Quartz	Oro	278	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105133	Quartz	Oro	279	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105134	Quartz	Oro	280	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105135	Quartz	Oro	281	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105136	Quartz	Oro	282	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105137	Quartz	Oro	283	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105138	Quartz	Oro	284	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105139	Quartz	Oro	285	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105140	Quartz	Oro	286	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105141	Quartz	Oro	287	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105142	Quartz	Oro	288	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105143	Quartz	Oro	289	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105144	Quartz	Oro	290	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105145	Quartz	Oro	291	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105146	Quartz	Oro	292	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105147	Quartz	Oro	293	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105148	Quartz	Oro	294	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105149	Quartz	Oro	295	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105150	Quartz	Oro	296	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105151	Quartz	Oro	297	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105152	Quartz	Oro	298	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105153	Quartz	Oro	299	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105154	Quartz	Oro	300	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105155	Quartz	Oro	301	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105156	Quartz	Oro	302	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105157	Quartz	Oro	303	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105158	Quartz	Oro	304	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105159	Quartz	Oro	305	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105160	Quartz	Oro	306	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105161	Quartz	Oro	307	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105162	Quartz	Oro	308	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105163	Quartz	Oro	309	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105164	Quartz	Oro	310	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105165	Quartz	Oro	311	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105166	Quartz	Oro	312	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105167	Quartz	Oro	313	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105168	Quartz	Oro	314	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105169	Quartz	Oro	315	Cathro Resource Corp. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YD105170	Quartz	Oro	316	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105171	Quartz	Oro	317	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105172	Quartz	Oro	318	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105441	Quartz	Oro	319	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105442	Quartz	Oro	320	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105443	Quartz	Oro	321	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105444	Quartz	Oro	322	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105445	Quartz	Oro	323	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105446	Quartz	Oro	324	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105447	Quartz	Oro	325	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105448	Quartz	Oro	326	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105449	Quartz	Oro	327	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105450	Quartz	Oro	328	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105451	Quartz	Oro	329	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105452	Quartz	Oro	330	Cathro Resource Corp. - 100%	4-Apr-16
Mayo	YD105453	Quartz	Sol	1	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105454	Quartz	Sol	2	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105455	Quartz	Sol	3	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105456	Quartz	Sol	4	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105457	Quartz	Sol	5	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105458	Quartz	Sol	6	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105459	Quartz	Sol	7	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105460	Quartz	Sol	8	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105461	Quartz	Sol	9	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105462	Quartz	Sol	10	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105463	Quartz	Sol	11	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105464	Quartz	Sol	12	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105465	Quartz	Sol	13	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105466	Quartz	Sol	14	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105467	Quartz	Sol	15	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105468	Quartz	Sol	16	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105469	Quartz	Sol	17	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105470	Quartz	Sol	18	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105471	Quartz	Sol	19	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105472	Quartz	Sol	20	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105473	Quartz	Sol	21	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105474	Quartz	Sol	22	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105475	Quartz	Sol	23	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105476	Quartz	Sol	24	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105477	Quartz	Sol	25	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105478	Quartz	Sol	26	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105479	Quartz	Sol	27	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105480	Quartz	Sol	28	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105481	Quartz	Sol	29	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105482	Quartz	Sol	30	Colorado Resources Ltd. - 100%	6-Oct-14

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YD105483	Quartz	Sol	31	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105484	Quartz	Sol	32	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105485	Quartz	Sol	33	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105486	Quartz	Sol	34	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105487	Quartz	Sol	35	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105488	Quartz	Sol	36	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105489	Quartz	Sol	37	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105490	Quartz	Sol	38	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105491	Quartz	Sol	39	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105492	Quartz	Sol	40	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105493	Quartz	Sol	41	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105494	Quartz	Sol	42	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105495	Quartz	Sol	43	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105496	Quartz	Sol	44	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105497	Quartz	Sol	45	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105498	Quartz	Sol	46	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105499	Quartz	Sol	47	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105500	Quartz	Sol	48	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105501	Quartz	Sol	49	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105502	Quartz	Sol	50	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105503	Quartz	Sol	51	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105504	Quartz	Sol	52	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105505	Quartz	Sol	53	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105506	Quartz	Sol	54	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105507	Quartz	Sol	55	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105508	Quartz	Sol	56	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105509	Quartz	Sol	57	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105510	Quartz	Sol	58	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105511	Quartz	Sol	59	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105512	Quartz	Sol	60	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105513	Quartz	Sol	61	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105514	Quartz	Sol	62	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105515	Quartz	Sol	63	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105516	Quartz	Sol	64	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105517	Quartz	Sol	65	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105518	Quartz	Sol	66	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105519	Quartz	Sol	67	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105520	Quartz	Sol	68	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105521	Quartz	Sol	69	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105522	Quartz	Sol	70	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105523	Quartz	Sol	71	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105524	Quartz	Sol	72	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105525	Quartz	Sol	73	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105526	Quartz	Sol	74	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105527	Quartz	Sol	75	Colorado Resources Ltd. - 100%	6-Oct-14

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YD105528	Quartz	Sol	76	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105529	Quartz	Sol	77	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105530	Quartz	Sol	78	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105531	Quartz	Sol	79	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105532	Quartz	Sol	80	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105533	Quartz	Sol	81	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105534	Quartz	Sol	82	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105535	Quartz	Sol	83	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105536	Quartz	Sol	84	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105537	Quartz	Sol	85	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105538	Quartz	Sol	86	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105539	Quartz	Sol	87	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105540	Quartz	Sol	88	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105541	Quartz	Sol	89	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105542	Quartz	Sol	90	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105543	Quartz	Sol	91	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105544	Quartz	Sol	92	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105545	Quartz	Sol	93	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105546	Quartz	Sol	94	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105547	Quartz	Sol	95	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105548	Quartz	Sol	96	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105549	Quartz	Sol	97	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105550	Quartz	Sol	98	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105551	Quartz	Sol	99	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105552	Quartz	Sol	100	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105553	Quartz	Sol	101	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105554	Quartz	Sol	102	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105555	Quartz	Sol	103	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105556	Quartz	Sol	104	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105557	Quartz	Sol	105	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105558	Quartz	Sol	106	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105559	Quartz	Sol	107	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105560	Quartz	Sol	108	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105561	Quartz	Sol	109	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105562	Quartz	Sol	110	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105563	Quartz	Sol	111	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105564	Quartz	Sol	112	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105565	Quartz	Sol	113	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105566	Quartz	Sol	114	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105567	Quartz	Sol	115	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105568	Quartz	Sol	116	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105569	Quartz	Sol	117	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105570	Quartz	Sol	118	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105571	Quartz	Sol	119	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105572	Quartz	Sol	120	Colorado Resources Ltd. - 100%	6-Oct-14

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YD105573	Quartz	Sol	121	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105574	Quartz	Sol	122	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105575	Quartz	Sol	123	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105576	Quartz	Sol	124	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105577	Quartz	Sol	125	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105578	Quartz	Sol	126	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105579	Quartz	Sol	127	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105580	Quartz	Sol	128	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105581	Quartz	Sol	129	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105582	Quartz	Sol	130	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105583	Quartz	Sol	131	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105584	Quartz	Sol	132	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105585	Quartz	Sol	133	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105586	Quartz	Sol	134	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105587	Quartz	Sol	135	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105588	Quartz	Sol	136	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105589	Quartz	Sol	137	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105590	Quartz	Sol	138	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105591	Quartz	Sol	139	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105592	Quartz	Sol	140	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105593	Quartz	Sol	141	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105594	Quartz	Sol	142	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105595	Quartz	Sol	143	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105596	Quartz	Sol	144	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105597	Quartz	Sol	145	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105598	Quartz	Sol	146	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105599	Quartz	Sol	147	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105600	Quartz	Sol	148	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105601	Quartz	Sol	149	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105602	Quartz	Sol	150	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105603	Quartz	Sol	151	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105604	Quartz	Sol	152	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105605	Quartz	Sol	153	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105606	Quartz	Sol	154	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105607	Quartz	Sol	155	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105608	Quartz	Sol	156	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105609	Quartz	Sol	157	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105610	Quartz	Sol	158	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105611	Quartz	Sol	159	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105612	Quartz	Sol	160	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105613	Quartz	Sol	161	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105614	Quartz	Sol	162	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105615	Quartz	Sol	163	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105616	Quartz	Sol	164	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105617	Quartz	Sol	165	Colorado Resources Ltd. - 100%	6-Oct-14

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YD105618	Quartz	Sol	166	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105619	Quartz	Sol	167	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105620	Quartz	Sol	168	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105621	Quartz	Sol	169	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105622	Quartz	Sol	170	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105623	Quartz	Sol	171	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105624	Quartz	Sol	172	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105625	Quartz	Sol	173	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105626	Quartz	Sol	174	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105627	Quartz	Sol	175	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105628	Quartz	Sol	176	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105629	Quartz	Sol	177	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105630	Quartz	Sol	178	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105631	Quartz	Sol	179	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105632	Quartz	Sol	180	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105633	Quartz	Sol	181	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105634	Quartz	Sol	182	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105635	Quartz	Sol	183	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105636	Quartz	Sol	184	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105637	Quartz	Sol	185	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105638	Quartz	Sol	186	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105639	Quartz	Sol	187	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105640	Quartz	Sol	188	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105641	Quartz	Sol	189	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105642	Quartz	Sol	190	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105643	Quartz	Sol	191	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105644	Quartz	Sol	192	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105645	Quartz	Sol	193	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105646	Quartz	Sol	194	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105647	Quartz	Sol	195	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105648	Quartz	Sol	196	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105649	Quartz	Sol	197	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105650	Quartz	Sol	198	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105651	Quartz	Sol	199	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105652	Quartz	Sol	200	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105653	Quartz	Sol	201	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105654	Quartz	Sol	202	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105655	Quartz	Sol	203	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105656	Quartz	Sol	204	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105657	Quartz	Sol	205	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YD105658	Quartz	Sol	206	Colorado Resources Ltd. - 100%	6-Oct-14
Mayo	YE42192	Quartz	OS	192	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42194	Quartz	OS	194	Colorado Resources Ltd. - 100%	4-Apr-14
Mayo	YE42196	Quartz	OS	196	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42198	Quartz	OS	198	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE42200	Quartz	OS	200	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42202	Quartz	OS	202	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42204	Quartz	OS	204	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42206	Quartz	OS	206	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42208	Quartz	OS	208	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42210	Quartz	OS	210	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42225	Quartz	OS	225	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42226	Quartz	OS	226	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42227	Quartz	OS	227	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42228	Quartz	OS	228	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42229	Quartz	OS	229	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42230	Quartz	OS	230	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42231	Quartz	OS	231	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42232	Quartz	OS	232	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42251	Quartz	OS	251	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42252	Quartz	OS	252	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42253	Quartz	OS	253	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42254	Quartz	OS	254	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42255	Quartz	OS	255	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42256	Quartz	OS	256	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42275	Quartz	OS	275	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42276	Quartz	OS	276	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42277	Quartz	OS	277	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42278	Quartz	OS	278	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42297	Quartz	OS	297	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42298	Quartz	OS	298	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42299	Quartz	OS	299	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42300	Quartz	OS	300	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42319	Quartz	OS	319	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42320	Quartz	OS	320	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42321	Quartz	OS	321	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42322	Quartz	OS	322	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42341	Quartz	OS	341	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42342	Quartz	OS	342	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42343	Quartz	OS	343	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42344	Quartz	OS	344	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42363	Quartz	OS	363	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42364	Quartz	OS	364	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42365	Quartz	OS	365	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42366	Quartz	OS	366	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42387	Quartz	OS	387	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42388	Quartz	OS	388	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE39295	Quartz	SNG	1	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE39296	Quartz	SNG	2	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE39297	Quartz	SNG	3	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 1

District	Grant Number	Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE39298	Quartz	SNG	4	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE39299	Quartz	SNG	5	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE43001	Quartz	HS	1	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43002	Quartz	HS	2	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43003	Quartz	HS	3	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43004	Quartz	HS	4	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43005	Quartz	HS	5	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43006	Quartz	HS	6	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43007	Quartz	HS	7	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43008	Quartz	HS	8	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43011	Quartz	HS	11	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43012	Quartz	HS	12	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43013	Quartz	HS	13	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43014	Quartz	HS	14	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43015	Quartz	HS	15	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43016	Quartz	HS	16	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43017	Quartz	HS	17	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43018	Quartz	HS	18	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43019	Quartz	HS	19	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43020	Quartz	HS	20	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43021	Quartz	HS	21	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43022	Quartz	HS	22	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43023	Quartz	HS	23	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43024	Quartz	HS	24	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43027	Quartz	HS	27	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43028	Quartz	HS	28	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43029	Quartz	HS	29	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43030	Quartz	HS	30	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43031	Quartz	HS	31	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43032	Quartz	HS	32	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43033	Quartz	HS	33	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43034	Quartz	HS	34	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43035	Quartz	HS	35	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43036	Quartz	HS	36	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43037	Quartz	HS	37	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43038	Quartz	HS	38	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43039	Quartz	HS	39	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43040	Quartz	HS	40	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43041	Quartz	HS	41	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43042	Quartz	HS	42	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43043	Quartz	HS	43	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43044	Quartz	HS	44	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43045	Quartz	HS	45	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43046	Quartz	HS	46	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43047	Quartz	HS	47	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43048	Quartz	HS	48	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE43049	Quartz	HS	49	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43050	Quartz	HS	50	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43051	Quartz	HS	51	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43052	Quartz	HS	52	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43053	Quartz	HS	53	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43054	Quartz	HS	54	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43055	Quartz	HS	55	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43056	Quartz	HS	56	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43057	Quartz	HS	57	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43058	Quartz	HS	58	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43059	Quartz	HS	59	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43060	Quartz	HS	60	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43061	Quartz	HS	61	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43062	Quartz	HS	62	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43063	Quartz	HS	63	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43064	Quartz	HS	64	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43065	Quartz	HS	65	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43066	Quartz	HS	66	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43067	Quartz	HS	67	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43068	Quartz	HS	68	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43069	Quartz	HS	69	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43070	Quartz	HS	70	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43071	Quartz	HS	71	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43072	Quartz	HS	72	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43073	Quartz	HS	73	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43074	Quartz	HS	74	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43075	Quartz	HS	75	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43076	Quartz	HS	76	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43077	Quartz	HS	77	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43078	Quartz	HS	78	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43079	Quartz	HS	79	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43080	Quartz	HS	80	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43081	Quartz	HS	81	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43082	Quartz	HS	82	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43083	Quartz	HS	83	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43084	Quartz	HS	84	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43085	Quartz	HS	85	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43086	Quartz	HS	86	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43087	Quartz	HS	87	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43088	Quartz	HS	88	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43089	Quartz	HS	89	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43090	Quartz	HS	90	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43091	Quartz	HS	91	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43092	Quartz	HS	92	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE43093	Quartz	HS	93	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43094	Quartz	HS	94	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43095	Quartz	HS	95	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43096	Quartz	HS	96	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43097	Quartz	HS	97	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43098	Quartz	HS	98	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43099	Quartz	HS	99	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43100	Quartz	HS	100	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43101	Quartz	HS	101	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43102	Quartz	HS	102	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43103	Quartz	HS	103	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43104	Quartz	HS	104	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43105	Quartz	HS	105	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43106	Quartz	HS	106	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43107	Quartz	HS	107	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43108	Quartz	HS	108	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43109	Quartz	HS	109	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43110	Quartz	HS	110	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43111	Quartz	HS	111	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43112	Quartz	HS	112	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43113	Quartz	HS	113	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43114	Quartz	HS	114	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43115	Quartz	HS	115	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43116	Quartz	HS	116	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43117	Quartz	HS	117	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43118	Quartz	HS	118	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43119	Quartz	HS	119	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43120	Quartz	HS	120	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43121	Quartz	HS	121	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43122	Quartz	HS	122	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43123	Quartz	HS	123	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43124	Quartz	HS	124	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43125	Quartz	HS	125	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43126	Quartz	HS	126	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43127	Quartz	HS	127	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43128	Quartz	HS	128	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43129	Quartz	HS	129	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43130	Quartz	HS	130	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43131	Quartz	HS	131	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43132	Quartz	HS	132	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43133	Quartz	HS	133	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43134	Quartz	HS	134	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43135	Quartz	HS	135	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43136	Quartz	HS	136	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE43137	Quartz	HS	137	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43138	Quartz	HS	138	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43139	Quartz	HS	139	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43140	Quartz	HS	140	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43141	Quartz	HS	141	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43142	Quartz	HS	142	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43143	Quartz	HS	143	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43144	Quartz	HS	144	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43145	Quartz	HS	145	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43146	Quartz	HS	146	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43147	Quartz	HS	147	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43148	Quartz	HS	148	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43149	Quartz	HS	149	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43150	Quartz	HS	150	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43151	Quartz	HS	151	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43152	Quartz	HS	152	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43153	Quartz	HS	153	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43154	Quartz	HS	154	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43155	Quartz	HS	155	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43156	Quartz	HS	156	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43157	Quartz	HS	157	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43158	Quartz	HS	158	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43159	Quartz	HS	159	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43160	Quartz	HS	160	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43161	Quartz	HS	161	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43162	Quartz	HS	162	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43163	Quartz	HS	163	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43164	Quartz	HS	164	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43165	Quartz	HS	165	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43166	Quartz	HS	166	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43167	Quartz	HS	167	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43168	Quartz	HS	168	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43169	Quartz	HS	169	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43170	Quartz	HS	170	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43171	Quartz	HS	171	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43172	Quartz	HS	172	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43173	Quartz	HS	173	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43174	Quartz	HS	174	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43175	Quartz	HS	175	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43176	Quartz	HS	176	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43177	Quartz	HS	177	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43178	Quartz	HS	178	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43179	Quartz	HS	179	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43180	Quartz	HS	180	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE43181	Quartz	HS	181	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43182	Quartz	HS	182	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43183	Quartz	HS	183	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43184	Quartz	HS	184	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43185	Quartz	HS	185	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43186	Quartz	HS	186	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43187	Quartz	HS	187	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43188	Quartz	HS	188	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43189	Quartz	HS	189	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43190	Quartz	HS	190	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43191	Quartz	HS	191	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43192	Quartz	HS	192	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43193	Quartz	HS	193	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43194	Quartz	HS	194	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43195	Quartz	HS	195	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43196	Quartz	HS	196	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43197	Quartz	HS	197	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43198	Quartz	HS	198	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43199	Quartz	HS	199	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43200	Quartz	HS	200	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43201	Quartz	HS	201	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43202	Quartz	HS	202	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43203	Quartz	HS	203	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43204	Quartz	HS	204	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43205	Quartz	HS	205	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43206	Quartz	HS	206	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43207	Quartz	HS	207	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43208	Quartz	HS	208	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43209	Quartz	HS	209	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43210	Quartz	HS	210	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43211	Quartz	HS	211	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43212	Quartz	HS	212	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43213	Quartz	HS	213	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43214	Quartz	HS	214	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43215	Quartz	HS	215	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43216	Quartz	HS	216	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43217	Quartz	HS	217	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43218	Quartz	HS	218	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43219	Quartz	HS	219	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43220	Quartz	HS	220	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43221	Quartz	HS	221	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43222	Quartz	HS	222	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43223	Quartz	HS	223	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43224	Quartz	HS	224	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE43225	Quartz	HS	225	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43226	Quartz	HS	226	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43227	Quartz	HS	227	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43228	Quartz	HS	228	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43229	Quartz	HS	229	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43230	Quartz	HS	230	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43231	Quartz	HS	231	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43232	Quartz	HS	232	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43233	Quartz	HS	233	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43234	Quartz	HS	234	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43235	Quartz	HS	235	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43236	Quartz	HS	236	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43237	Quartz	HS	237	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43238	Quartz	HS	238	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43239	Quartz	HS	239	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43240	Quartz	HS	240	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43241	Quartz	HS	241	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE43242	Quartz	HS	242	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39287	Quartz	HS	243	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39288	Quartz	HS	244	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39289	Quartz	HS	245	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39290	Quartz	HS	246	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39291	Quartz	HS	247	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39292	Quartz	HS	248	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39293	Quartz	HS	249	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39294	Quartz	HS	250	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39281	Quartz	HS	251	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39282	Quartz	HS	252	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39283	Quartz	HS	253	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39284	Quartz	HS	254	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39285	Quartz	HS	255	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE39286	Quartz	HS	256	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42001	Quartz	OS	1	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42002	Quartz	OS	2	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42003	Quartz	OS	3	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42004	Quartz	OS	4	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42005	Quartz	OS	5	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42006	Quartz	OS	6	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42007	Quartz	OS	7	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42008	Quartz	OS	8	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42009	Quartz	OS	9	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42010	Quartz	OS	10	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42011	Quartz	OS	11	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42012	Quartz	OS	12	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE42013	Quartz	OS	13	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42014	Quartz	OS	14	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42015	Quartz	OS	15	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42016	Quartz	OS	16	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42017	Quartz	OS	17	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42018	Quartz	OS	18	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42019	Quartz	OS	19	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42020	Quartz	OS	20	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42021	Quartz	OS	21	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42022	Quartz	OS	22	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42023	Quartz	OS	23	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42024	Quartz	OS	24	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42025	Quartz	OS	25	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42026	Quartz	OS	26	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42027	Quartz	OS	27	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42028	Quartz	OS	28	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42029	Quartz	OS	29	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42030	Quartz	OS	30	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42031	Quartz	OS	31	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42032	Quartz	OS	32	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42033	Quartz	OS	33	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42034	Quartz	OS	34	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42035	Quartz	OS	35	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42036	Quartz	OS	36	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42037	Quartz	OS	37	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42038	Quartz	OS	38	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42039	Quartz	OS	39	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42040	Quartz	OS	40	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42041	Quartz	OS	41	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42042	Quartz	OS	42	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42043	Quartz	OS	43	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42044	Quartz	OS	44	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42045	Quartz	OS	45	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42046	Quartz	OS	46	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42047	Quartz	OS	47	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42048	Quartz	OS	48	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42049	Quartz	OS	49	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42050	Quartz	OS	50	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42051	Quartz	OS	51	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42052	Quartz	OS	52	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42053	Quartz	OS	53	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42054	Quartz	OS	54	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42055	Quartz	OS	55	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42056	Quartz	OS	56	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE42057	Quartz	OS	57	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42058	Quartz	OS	58	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42059	Quartz	OS	59	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42060	Quartz	OS	60	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42061	Quartz	OS	61	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42062	Quartz	OS	62	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42063	Quartz	OS	63	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42064	Quartz	OS	64	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42065	Quartz	OS	65	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42066	Quartz	OS	66	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42067	Quartz	OS	67	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42068	Quartz	OS	68	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42069	Quartz	OS	69	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42070	Quartz	OS	70	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42071	Quartz	OS	71	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42072	Quartz	OS	72	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42073	Quartz	OS	73	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42074	Quartz	OS	74	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42075	Quartz	OS	75	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42076	Quartz	OS	76	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42077	Quartz	OS	77	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42078	Quartz	OS	78	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42079	Quartz	OS	79	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42080	Quartz	OS	80	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42081	Quartz	OS	81	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42082	Quartz	OS	82	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42083	Quartz	OS	83	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42084	Quartz	OS	84	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42085	Quartz	OS	85	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42086	Quartz	OS	86	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42087	Quartz	OS	87	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42088	Quartz	OS	88	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42089	Quartz	OS	89	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42090	Quartz	OS	90	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42091	Quartz	OS	91	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42092	Quartz	OS	92	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42093	Quartz	OS	93	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42094	Quartz	OS	94	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42095	Quartz	OS	95	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42096	Quartz	OS	96	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42097	Quartz	OS	97	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42098	Quartz	OS	98	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42099	Quartz	OS	99	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42100	Quartz	OS	100	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE42101	Quartz	OS	101	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42102	Quartz	OS	102	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42103	Quartz	OS	103	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42104	Quartz	OS	104	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42105	Quartz	OS	105	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42106	Quartz	OS	106	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42107	Quartz	OS	107	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42108	Quartz	OS	108	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42109	Quartz	OS	109	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42110	Quartz	OS	110	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42111	Quartz	OS	111	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42112	Quartz	OS	112	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42113	Quartz	OS	113	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42114	Quartz	OS	114	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42115	Quartz	OS	115	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42116	Quartz	OS	116	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42117	Quartz	OS	117	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42118	Quartz	OS	118	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42119	Quartz	OS	119	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42120	Quartz	OS	120	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42121	Quartz	OS	121	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42122	Quartz	OS	122	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42123	Quartz	OS	123	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42124	Quartz	OS	124	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42125	Quartz	OS	125	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42126	Quartz	OS	126	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42127	Quartz	OS	127	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42128	Quartz	OS	128	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42129	Quartz	OS	129	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42130	Quartz	OS	130	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42131	Quartz	OS	131	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42132	Quartz	OS	132	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42133	Quartz	OS	133	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42134	Quartz	OS	134	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42135	Quartz	OS	135	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42136	Quartz	OS	136	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42137	Quartz	OS	137	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42138	Quartz	OS	138	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42139	Quartz	OS	139	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42140	Quartz	OS	140	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42141	Quartz	OS	141	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42142	Quartz	OS	142	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42143	Quartz	OS	143	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42144	Quartz	OS	144	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE42145	Quartz	OS	145	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42146	Quartz	OS	146	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42147	Quartz	OS	147	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42148	Quartz	OS	148	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42149	Quartz	OS	149	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42150	Quartz	OS	150	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42151	Quartz	OS	151	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42152	Quartz	OS	152	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42153	Quartz	OS	153	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42154	Quartz	OS	154	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42155	Quartz	OS	155	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42156	Quartz	OS	156	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42157	Quartz	OS	157	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42158	Quartz	OS	158	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42159	Quartz	OS	159	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42160	Quartz	OS	160	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42161	Quartz	OS	161	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42162	Quartz	OS	162	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42163	Quartz	OS	163	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42164	Quartz	OS	164	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42165	Quartz	OS	165	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42166	Quartz	OS	166	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42167	Quartz	OS	167	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42168	Quartz	OS	168	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42169	Quartz	OS	169	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42170	Quartz	OS	170	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42171	Quartz	OS	171	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42172	Quartz	OS	172	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42173	Quartz	OS	173	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42174	Quartz	OS	174	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42175	Quartz	OS	175	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42176	Quartz	OS	176	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42177	Quartz	OS	177	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42178	Quartz	OS	178	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42179	Quartz	OS	179	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42180	Quartz	OS	180	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42181	Quartz	OS	181	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42182	Quartz	OS	182	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42183	Quartz	OS	183	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42184	Quartz	OS	184	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42185	Quartz	OS	185	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42186	Quartz	OS	186	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42187	Quartz	OS	187	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42188	Quartz	OS	188	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE42189	Quartz	OS	189	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42190	Quartz	OS	190	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42191	Quartz	OS	191	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42193	Quartz	OS	193	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42195	Quartz	OS	195	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42197	Quartz	OS	197	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42199	Quartz	OS	199	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42201	Quartz	OS	201	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42203	Quartz	OS	203	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42205	Quartz	OS	205	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42207	Quartz	OS	207	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42209	Quartz	OS	209	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42211	Quartz	OS	211	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42212	Quartz	OS	212	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42213	Quartz	OS	213	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42214	Quartz	OS	214	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42215	Quartz	OS	215	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42216	Quartz	OS	216	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42217	Quartz	OS	217	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42218	Quartz	OS	218	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42219	Quartz	OS	219	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42220	Quartz	OS	220	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42221	Quartz	OS	221	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42222	Quartz	OS	222	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42223	Quartz	OS	223	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42224	Quartz	OS	224	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42233	Quartz	OS	233	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42234	Quartz	OS	234	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42235	Quartz	OS	235	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42236	Quartz	OS	236	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42237	Quartz	OS	237	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42238	Quartz	OS	238	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42239	Quartz	OS	239	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42240	Quartz	OS	240	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42241	Quartz	OS	241	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42242	Quartz	OS	242	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42243	Quartz	OS	243	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42244	Quartz	OS	244	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42245	Quartz	OS	245	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42246	Quartz	OS	246	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42247	Quartz	OS	247	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42248	Quartz	OS	248	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42249	Quartz	OS	249	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42250	Quartz	OS	250	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE42257	Quartz	OS	257	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42258	Quartz	OS	258	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42259	Quartz	OS	259	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42260	Quartz	OS	260	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42261	Quartz	OS	261	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42262	Quartz	OS	262	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42263	Quartz	OS	263	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42264	Quartz	OS	264	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42265	Quartz	OS	265	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42266	Quartz	OS	266	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42267	Quartz	OS	267	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42268	Quartz	OS	268	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42269	Quartz	OS	269	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42270	Quartz	OS	270	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42271	Quartz	OS	271	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42272	Quartz	OS	272	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42273	Quartz	OS	273	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42274	Quartz	OS	274	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42279	Quartz	OS	279	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42280	Quartz	OS	280	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42281	Quartz	OS	281	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42282	Quartz	OS	282	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42283	Quartz	OS	283	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42284	Quartz	OS	284	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42285	Quartz	OS	285	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42286	Quartz	OS	286	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42287	Quartz	OS	287	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42288	Quartz	OS	288	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42289	Quartz	OS	289	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42290	Quartz	OS	290	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42291	Quartz	OS	291	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42292	Quartz	OS	292	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42293	Quartz	OS	293	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42294	Quartz	OS	294	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42295	Quartz	OS	295	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42296	Quartz	OS	296	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42301	Quartz	OS	301	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42302	Quartz	OS	302	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42303	Quartz	OS	303	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42304	Quartz	OS	304	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42305	Quartz	OS	305	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42306	Quartz	OS	306	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42307	Quartz	OS	307	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42308	Quartz	OS	308	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE42309	Quartz	OS	309	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42310	Quartz	OS	310	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42311	Quartz	OS	311	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42312	Quartz	OS	312	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42313	Quartz	OS	313	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42314	Quartz	OS	314	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42315	Quartz	OS	315	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42316	Quartz	OS	316	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42317	Quartz	OS	317	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42318	Quartz	OS	318	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42323	Quartz	OS	323	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42324	Quartz	OS	324	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42325	Quartz	OS	325	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42326	Quartz	OS	326	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42327	Quartz	OS	327	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42328	Quartz	OS	328	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42329	Quartz	OS	329	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42330	Quartz	OS	330	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42331	Quartz	OS	331	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42332	Quartz	OS	332	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42333	Quartz	OS	333	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42334	Quartz	OS	334	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42335	Quartz	OS	335	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42336	Quartz	OS	336	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42337	Quartz	OS	337	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42338	Quartz	OS	338	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42339	Quartz	OS	339	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42340	Quartz	OS	340	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42345	Quartz	OS	345	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42346	Quartz	OS	346	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42347	Quartz	OS	347	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42348	Quartz	OS	348	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42349	Quartz	OS	349	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42350	Quartz	OS	350	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42351	Quartz	OS	351	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42352	Quartz	OS	352	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42353	Quartz	OS	353	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42354	Quartz	OS	354	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42355	Quartz	OS	355	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42356	Quartz	OS	356	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42357	Quartz	OS	357	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42358	Quartz	OS	358	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42359	Quartz	OS	359	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42360	Quartz	OS	360	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE42361	Quartz	OS	361	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42362	Quartz	OS	362	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42367	Quartz	OS	367	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42368	Quartz	OS	368	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42369	Quartz	OS	369	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42370	Quartz	OS	370	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42371	Quartz	OS	371	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42372	Quartz	OS	372	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42373	Quartz	OS	373	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42374	Quartz	OS	374	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42375	Quartz	OS	375	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42376	Quartz	OS	376	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42377	Quartz	OS	377	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42378	Quartz	OS	378	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42379	Quartz	OS	379	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42380	Quartz	OS	380	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42381	Quartz	OS	381	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42382	Quartz	OS	382	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42383	Quartz	OS	383	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42384	Quartz	OS	384	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42385	Quartz	OS	385	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42386	Quartz	OS	386	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42389	Quartz	OS	389	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42390	Quartz	OS	390	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42391	Quartz	OS	391	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42392	Quartz	OS	392	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42393	Quartz	OS	393	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42394	Quartz	OS	394	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42395	Quartz	OS	395	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42396	Quartz	OS	396	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42397	Quartz	OS	397	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42398	Quartz	OS	398	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42399	Quartz	OS	399	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42400	Quartz	OS	400	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42401	Quartz	OS	401	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42402	Quartz	OS	402	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42403	Quartz	OS	403	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42404	Quartz	OS	404	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42405	Quartz	OS	405	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42406	Quartz	OS	406	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42407	Quartz	OS	407	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42408	Quartz	OS	408	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42409	Quartz	OS	409	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42410	Quartz	OS	410	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE42411	Quartz	OS	411	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42412	Quartz	OS	412	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42413	Quartz	OS	413	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42414	Quartz	OS	414	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42415	Quartz	OS	415	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42416	Quartz	OS	416	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42417	Quartz	OS	417	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42418	Quartz	OS	418	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42419	Quartz	OS	419	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42420	Quartz	OS	420	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42421	Quartz	OS	421	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42422	Quartz	OS	422	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42423	Quartz	OS	423	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42424	Quartz	OS	424	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42425	Quartz	OS	425	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42426	Quartz	OS	426	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42427	Quartz	OS	427	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42428	Quartz	OS	428	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42429	Quartz	OS	429	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42430	Quartz	OS	430	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42431	Quartz	OS	431	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42432	Quartz	OS	432	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42433	Quartz	OS	433	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42434	Quartz	OS	434	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42435	Quartz	OS	435	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42436	Quartz	OS	436	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42437	Quartz	OS	437	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42438	Quartz	OS	438	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42439	Quartz	OS	439	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42440	Quartz	OS	440	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42441	Quartz	OS	441	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42442	Quartz	OS	442	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42443	Quartz	OS	443	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42444	Quartz	OS	444	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42445	Quartz	OS	445	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42446	Quartz	OS	446	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42447	Quartz	OS	447	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42448	Quartz	OS	448	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42449	Quartz	OS	449	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42450	Quartz	OS	450	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42451	Quartz	OS	451	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42452	Quartz	OS	452	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42453	Quartz	OS	453	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42454	Quartz	OS	454	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE42455	Quartz	OS	455	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42456	Quartz	OS	456	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42457	Quartz	OS	457	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42458	Quartz	OS	458	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42459	Quartz	OS	459	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42460	Quartz	OS	460	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42461	Quartz	OS	461	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42462	Quartz	OS	462	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42463	Quartz	OS	463	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42464	Quartz	OS	464	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42465	Quartz	OS	465	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42466	Quartz	OS	466	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42467	Quartz	OS	467	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42468	Quartz	OS	468	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42469	Quartz	OS	469	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42470	Quartz	OS	470	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42471	Quartz	OS	471	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42472	Quartz	OS	472	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42473	Quartz	OS	473	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42474	Quartz	OS	474	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42475	Quartz	OS	475	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42476	Quartz	OS	476	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42477	Quartz	OS	477	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42478	Quartz	OS	478	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42479	Quartz	OS	479	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42480	Quartz	OS	480	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42481	Quartz	OS	481	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42482	Quartz	OS	482	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42483	Quartz	OS	483	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42484	Quartz	OS	484	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42485	Quartz	OS	485	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42486	Quartz	OS	486	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42487	Quartz	OS	487	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42488	Quartz	OS	488	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42489	Quartz	OS	489	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42490	Quartz	OS	490	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42491	Quartz	OS	491	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42492	Quartz	OS	492	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42493	Quartz	OS	493	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42494	Quartz	OS	494	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42495	Quartz	OS	495	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42496	Quartz	OS	496	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42497	Quartz	OS	497	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42498	Quartz	OS	498	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 2

District	Grant Number	Reg Type	Claim Name	Claim Number	Claim Owner	Claim Expiry Date
Mayo	YE42499	Quartz	OS	499	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42500	Quartz	OS	500	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42501	Quartz	OS	501	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42502	Quartz	OS	502	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42503	Quartz	OS	503	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42504	Quartz	OS	504	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42505	Quartz	OS	505	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42506	Quartz	OS	506	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42507	Quartz	OS	507	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42508	Quartz	OS	508	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42509	Quartz	OS	509	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42510	Quartz	OS	510	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42511	Quartz	OS	511	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42512	Quartz	OS	512	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42513	Quartz	OS	513	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42514	Quartz	OS	514	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42515	Quartz	OS	515	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42516	Quartz	OS	516	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42517	Quartz	OS	517	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42518	Quartz	OS	518	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42519	Quartz	OS	519	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42520	Quartz	OS	520	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42521	Quartz	OS	521	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42522	Quartz	OS	522	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42523	Quartz	OS	523	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42524	Quartz	OS	524	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42525	Quartz	OS	525	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42526	Quartz	OS	526	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42527	Quartz	OS	527	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42528	Quartz	OS	528	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42529	Quartz	OS	529	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42530	Quartz	OS	530	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42531	Quartz	OS	531	Colorado Resources Ltd. - 100%	4-Apr-15
Mayo	YE42532	Quartz	OS	532	Colorado Resources Ltd. - 100%	4-Apr-15

ORO PROPERTY - CLAIM GROUP 3

District	Grant Number	Reg Type	Claim Name	Claim Nbr	Claim Owner	Claim Expiry Date
Mayo	YE42601	Quartz	ON	1	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42602	Quartz	ON	2	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42603	Quartz	ON	3	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42604	Quartz	ON	4	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42605	Quartz	ON	5	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42606	Quartz	ON	6	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42607	Quartz	ON	7	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42608	Quartz	ON	8	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42609	Quartz	ON	9	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42610	Quartz	ON	10	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42611	Quartz	ON	11	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42612	Quartz	ON	12	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42613	Quartz	ON	13	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42614	Quartz	ON	14	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42615	Quartz	ON	15	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42616	Quartz	ON	16	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42617	Quartz	ON	17	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42618	Quartz	ON	18	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42619	Quartz	ON	19	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42620	Quartz	ON	20	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42621	Quartz	ON	21	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42622	Quartz	ON	22	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42623	Quartz	ON	23	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42624	Quartz	ON	24	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42625	Quartz	ON	25	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42626	Quartz	ON	26	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42627	Quartz	ON	27	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42628	Quartz	ON	28	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42629	Quartz	ON	29	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42630	Quartz	ON	30	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42631	Quartz	ON	31	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42632	Quartz	ON	32	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42633	Quartz	ON	33	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42634	Quartz	ON	34	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42635	Quartz	ON	35	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42636	Quartz	ON	36	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42637	Quartz	ON	37	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42638	Quartz	ON	38	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42639	Quartz	ON	39	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42640	Quartz	ON	40	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42641	Quartz	ON	41	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42642	Quartz	ON	42	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42643	Quartz	ON	43	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42644	Quartz	ON	44	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42645	Quartz	ON	45	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 3

District	Grant Number	Reg Type	Claim Name	Claim Nbr	Claim Owner	Claim Expiry Date
Mayo	YE42646	Quartz	ON	46	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42647	Quartz	ON	47	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42648	Quartz	ON	48	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42649	Quartz	ON	49	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42650	Quartz	ON	50	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42651	Quartz	ON	51	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42652	Quartz	ON	52	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42653	Quartz	ON	53	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42654	Quartz	ON	54	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42655	Quartz	ON	55	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42656	Quartz	ON	56	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42657	Quartz	ON	57	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42658	Quartz	ON	58	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42659	Quartz	ON	59	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42660	Quartz	ON	60	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42661	Quartz	ON	61	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42662	Quartz	ON	62	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42663	Quartz	ON	63	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42664	Quartz	ON	64	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42665	Quartz	ON	65	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42666	Quartz	ON	66	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42667	Quartz	ON	67	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42668	Quartz	ON	68	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42669	Quartz	ON	69	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42670	Quartz	ON	70	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42671	Quartz	ON	71	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42672	Quartz	ON	72	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42673	Quartz	ON	73	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42674	Quartz	ON	74	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42675	Quartz	ON	75	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42676	Quartz	ON	76	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42677	Quartz	ON	77	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42678	Quartz	ON	78	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42679	Quartz	ON	79	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42680	Quartz	ON	80	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42681	Quartz	ON	81	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42682	Quartz	ON	82	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42683	Quartz	ON	83	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42684	Quartz	ON	84	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42685	Quartz	ON	85	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42686	Quartz	ON	86	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42687	Quartz	ON	87	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42688	Quartz	ON	88	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42689	Quartz	ON	89	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42690	Quartz	ON	90	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 3

District	Grant Number	Reg Type	Claim Name	Claim Nbr	Claim Owner	Claim Expiry Date
Mayo	YE42691	Quartz	ON	91	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42692	Quartz	ON	92	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42693	Quartz	ON	93	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42694	Quartz	ON	94	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42695	Quartz	ON	95	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42696	Quartz	ON	96	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42697	Quartz	ON	97	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42698	Quartz	ON	98	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42699	Quartz	ON	99	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42700	Quartz	ON	100	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42701	Quartz	ON	101	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42702	Quartz	ON	102	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42703	Quartz	ON	103	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42704	Quartz	ON	104	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42705	Quartz	ON	105	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42706	Quartz	ON	106	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42707	Quartz	ON	107	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42708	Quartz	ON	108	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42709	Quartz	ON	109	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42710	Quartz	ON	110	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42711	Quartz	ON	111	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42712	Quartz	ON	112	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42713	Quartz	ON	113	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42714	Quartz	ON	114	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42715	Quartz	ON	115	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42716	Quartz	ON	116	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42717	Quartz	ON	117	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42718	Quartz	ON	118	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42719	Quartz	ON	119	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42720	Quartz	ON	120	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42721	Quartz	ON	121	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42722	Quartz	ON	122	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42723	Quartz	ON	123	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42724	Quartz	ON	124	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42725	Quartz	ON	125	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42726	Quartz	ON	126	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42727	Quartz	ON	127	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42728	Quartz	ON	128	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42729	Quartz	ON	129	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42730	Quartz	ON	130	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42731	Quartz	ON	131	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42732	Quartz	ON	132	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42733	Quartz	ON	133	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42734	Quartz	ON	134	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42735	Quartz	ON	135	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 3

District	Grant Number	Reg Type	Claim Name	Claim Nbr	Claim Owner	Claim Expiry Date
Mayo	YE42736	Quartz	ON	136	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42737	Quartz	ON	137	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42738	Quartz	ON	138	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42739	Quartz	ON	139	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42740	Quartz	ON	140	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42741	Quartz	ON	141	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42742	Quartz	ON	142	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42743	Quartz	ON	143	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42744	Quartz	ON	144	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42745	Quartz	ON	145	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42746	Quartz	ON	146	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42747	Quartz	ON	147	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42748	Quartz	ON	148	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42749	Quartz	ON	149	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42750	Quartz	ON	150	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42751	Quartz	ON	151	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42752	Quartz	ON	152	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42753	Quartz	ON	153	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42754	Quartz	ON	154	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42755	Quartz	ON	155	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42756	Quartz	ON	156	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42757	Quartz	ON	157	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42758	Quartz	ON	158	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42759	Quartz	ON	159	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42760	Quartz	ON	160	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42761	Quartz	ON	161	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42762	Quartz	ON	162	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42763	Quartz	ON	163	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42764	Quartz	ON	164	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42765	Quartz	ON	165	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42766	Quartz	ON	166	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42767	Quartz	ON	167	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42768	Quartz	ON	168	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42769	Quartz	ON	169	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42770	Quartz	ON	170	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42771	Quartz	ON	171	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42772	Quartz	ON	172	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42773	Quartz	ON	173	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42774	Quartz	ON	174	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42775	Quartz	ON	175	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42776	Quartz	ON	176	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42777	Quartz	ON	177	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42778	Quartz	ON	178	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42779	Quartz	ON	179	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42780	Quartz	ON	180	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 3

District	Grant Number	Reg Type	Claim Name	Claim Nbr	Claim Owner	Claim Expiry Date
Mayo	YE42781	Quartz	ON	181	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42782	Quartz	ON	182	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42783	Quartz	ON	183	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42784	Quartz	ON	184	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42785	Quartz	ON	185	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42786	Quartz	ON	186	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42787	Quartz	ON	187	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42788	Quartz	ON	188	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42789	Quartz	ON	189	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42790	Quartz	ON	190	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42791	Quartz	ON	191	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42792	Quartz	ON	192	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42793	Quartz	ON	193	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42794	Quartz	ON	194	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42795	Quartz	ON	195	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42796	Quartz	ON	196	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42797	Quartz	ON	197	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42798	Quartz	ON	198	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42799	Quartz	ON	199	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42800	Quartz	ON	200	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42801	Quartz	ON	201	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42802	Quartz	ON	202	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42803	Quartz	ON	203	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42804	Quartz	ON	204	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42805	Quartz	ON	205	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42806	Quartz	ON	206	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42807	Quartz	ON	207	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42808	Quartz	ON	208	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42809	Quartz	ON	209	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42810	Quartz	ON	210	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42811	Quartz	ON	211	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42812	Quartz	ON	212	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42813	Quartz	ON	213	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42814	Quartz	ON	214	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42815	Quartz	ON	215	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42816	Quartz	ON	216	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42817	Quartz	ON	217	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42818	Quartz	ON	218	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42819	Quartz	ON	219	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42820	Quartz	ON	220	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42821	Quartz	ON	221	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42822	Quartz	ON	222	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42823	Quartz	ON	223	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42824	Quartz	ON	224	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42825	Quartz	ON	225	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 3

District	Grant Number	Reg Type	Claim Name	Claim Nbr	Claim Owner	Claim Expiry Date
Mayo	YE42826	Quartz	ON	226	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42827	Quartz	ON	227	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42828	Quartz	ON	228	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42829	Quartz	ON	229	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42830	Quartz	ON	230	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42831	Quartz	ON	231	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42832	Quartz	ON	232	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42833	Quartz	ON	233	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42834	Quartz	ON	234	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42835	Quartz	ON	235	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42836	Quartz	ON	236	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42837	Quartz	ON	237	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42838	Quartz	ON	238	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42839	Quartz	ON	239	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42840	Quartz	ON	240	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42841	Quartz	ON	241	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42842	Quartz	ON	242	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42843	Quartz	ON	243	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42844	Quartz	ON	244	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42845	Quartz	ON	245	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42846	Quartz	ON	246	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42847	Quartz	ON	247	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42848	Quartz	ON	248	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42849	Quartz	ON	249	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42850	Quartz	ON	250	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42851	Quartz	ON	251	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42852	Quartz	ON	252	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42853	Quartz	ON	253	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42854	Quartz	ON	254	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42855	Quartz	ON	255	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42856	Quartz	ON	256	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42857	Quartz	ON	257	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42858	Quartz	ON	258	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42859	Quartz	ON	259	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42860	Quartz	ON	260	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42861	Quartz	ON	261	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42862	Quartz	ON	262	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42863	Quartz	ON	263	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42864	Quartz	ON	264	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42865	Quartz	ON	265	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42866	Quartz	ON	266	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42867	Quartz	ON	267	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42868	Quartz	ON	268	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42869	Quartz	ON	269	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42870	Quartz	ON	270	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 3

District	Grant Number	Reg Type	Claim Name	Claim Nbr	Claim Owner	Claim Expiry Date
Mayo	YE42871	Quartz	ON	271	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42872	Quartz	ON	272	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42873	Quartz	ON	273	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42874	Quartz	ON	274	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42875	Quartz	ON	275	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42876	Quartz	ON	276	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42877	Quartz	ON	277	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42878	Quartz	ON	278	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42879	Quartz	ON	279	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42880	Quartz	ON	280	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42881	Quartz	ON	281	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42882	Quartz	ON	282	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42883	Quartz	ON	283	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42884	Quartz	ON	284	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42885	Quartz	ON	285	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42886	Quartz	ON	286	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42887	Quartz	ON	287	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42888	Quartz	ON	288	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42889	Quartz	ON	289	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42890	Quartz	ON	290	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42891	Quartz	ON	291	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42892	Quartz	ON	292	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42893	Quartz	ON	293	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42894	Quartz	ON	294	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42895	Quartz	ON	295	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42896	Quartz	ON	296	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42897	Quartz	ON	297	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42898	Quartz	ON	298	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42899	Quartz	ON	299	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42900	Quartz	ON	300	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42901	Quartz	ON	301	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42902	Quartz	ON	302	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42903	Quartz	ON	303	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42904	Quartz	ON	304	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42905	Quartz	ON	305	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42906	Quartz	ON	306	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42907	Quartz	ON	307	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42908	Quartz	ON	308	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42909	Quartz	ON	309	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42910	Quartz	ON	310	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42911	Quartz	ON	311	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42912	Quartz	ON	312	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42913	Quartz	ON	313	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42914	Quartz	ON	314	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42915	Quartz	ON	315	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 3

District	Grant Number	Reg Type	Claim Name	Claim Nbr	Claim Owner	Claim Expiry Date
Mayo	YE42916	Quartz	ON	316	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42917	Quartz	ON	317	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42918	Quartz	ON	318	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42919	Quartz	ON	319	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42920	Quartz	ON	320	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42921	Quartz	ON	321	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42922	Quartz	ON	322	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42923	Quartz	ON	323	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42924	Quartz	ON	324	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42925	Quartz	ON	325	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42926	Quartz	ON	326	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42927	Quartz	ON	327	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42928	Quartz	ON	328	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42929	Quartz	ON	329	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42930	Quartz	ON	330	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42931	Quartz	ON	331	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42932	Quartz	ON	332	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42933	Quartz	ON	333	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42934	Quartz	ON	334	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42935	Quartz	ON	335	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42936	Quartz	ON	336	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42937	Quartz	ON	337	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42938	Quartz	ON	338	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42939	Quartz	ON	339	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42940	Quartz	ON	340	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42941	Quartz	ON	341	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42942	Quartz	ON	342	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42943	Quartz	ON	343	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42944	Quartz	ON	344	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42945	Quartz	ON	345	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42946	Quartz	ON	346	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42947	Quartz	ON	347	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42948	Quartz	ON	348	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42949	Quartz	ON	349	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42950	Quartz	ON	350	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42951	Quartz	ON	351	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42952	Quartz	ON	352	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42953	Quartz	ON	353	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42954	Quartz	ON	354	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42955	Quartz	ON	355	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42956	Quartz	ON	356	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42957	Quartz	ON	357	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42958	Quartz	ON	358	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42959	Quartz	ON	359	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42960	Quartz	ON	360	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 3

District	Grant Number	Reg Type	Claim Name	Claim Nbr	Claim Owner	Claim Expiry Date
Mayo	YE42961	Quartz	ON	361	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42962	Quartz	ON	362	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42963	Quartz	ON	363	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42964	Quartz	ON	364	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42965	Quartz	ON	365	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42966	Quartz	ON	366	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42967	Quartz	ON	367	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42968	Quartz	ON	368	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42969	Quartz	ON	369	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42970	Quartz	ON	370	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42971	Quartz	ON	371	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42972	Quartz	ON	372	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42973	Quartz	ON	373	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42974	Quartz	ON	374	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42975	Quartz	ON	375	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42976	Quartz	ON	376	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42977	Quartz	ON	377	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42978	Quartz	ON	378	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42979	Quartz	ON	379	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42980	Quartz	ON	380	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42981	Quartz	ON	381	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42982	Quartz	ON	382	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42983	Quartz	ON	383	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42984	Quartz	ON	384	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42985	Quartz	ON	385	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42986	Quartz	ON	386	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42987	Quartz	ON	387	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42988	Quartz	ON	388	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42989	Quartz	ON	389	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42990	Quartz	ON	390	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42991	Quartz	ON	391	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42992	Quartz	ON	392	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42993	Quartz	ON	393	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42994	Quartz	ON	394	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42995	Quartz	ON	395	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42996	Quartz	ON	396	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42997	Quartz	ON	397	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42998	Quartz	ON	398	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE42999	Quartz	ON	399	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43000	Quartz	ON	400	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43261	Quartz	ON	401	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43262	Quartz	ON	402	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43263	Quartz	ON	403	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43264	Quartz	ON	404	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43265	Quartz	ON	405	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 3

District	Grant Number	Reg Type	Claim Name	Claim Nbr	Claim Owner	Claim Expiry Date
Mayo	YE43266	Quartz	ON	406	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43267	Quartz	ON	407	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43268	Quartz	ON	408	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43269	Quartz	ON	409	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43270	Quartz	ON	410	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43271	Quartz	ON	411	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43272	Quartz	ON	412	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43273	Quartz	ON	413	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43274	Quartz	ON	414	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43275	Quartz	ON	415	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43276	Quartz	ON	416	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43277	Quartz	ON	417	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43278	Quartz	ON	418	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43279	Quartz	ON	419	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43280	Quartz	ON	420	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43281	Quartz	ON	421	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43282	Quartz	ON	422	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43283	Quartz	ON	423	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43284	Quartz	ON	424	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43285	Quartz	ON	425	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43286	Quartz	ON	426	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43287	Quartz	ON	427	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43288	Quartz	ON	428	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43289	Quartz	ON	429	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43290	Quartz	ON	430	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43291	Quartz	ON	431	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43292	Quartz	ON	432	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43293	Quartz	ON	433	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43294	Quartz	ON	434	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43295	Quartz	ON	435	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43296	Quartz	ON	436	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43297	Quartz	ON	437	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43298	Quartz	ON	438	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43299	Quartz	ON	439	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43300	Quartz	ON	440	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43301	Quartz	ON	441	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43302	Quartz	ON	442	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43303	Quartz	ON	443	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43304	Quartz	ON	444	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43305	Quartz	ON	445	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43306	Quartz	ON	446	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43307	Quartz	ON	447	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43308	Quartz	ON	448	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43309	Quartz	ON	449	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43310	Quartz	ON	450	Colorado Resources Ltd. - 100%	4-Apr-16

ORO PROPERTY - CLAIM GROUP 3

District	Grant Number	Reg Type	Claim Name	Claim Nbr	Claim Owner	Claim Expiry Date
Mayo	YE43311	Quartz	ON	451	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43312	Quartz	ON	452	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43313	Quartz	ON	453	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43314	Quartz	ON	454	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43315	Quartz	ON	455	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43316	Quartz	ON	456	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43317	Quartz	ON	457	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43318	Quartz	ON	458	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43319	Quartz	ON	459	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43320	Quartz	ON	460	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43321	Quartz	ON	461	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43322	Quartz	ON	462	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43323	Quartz	ON	463	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43324	Quartz	ON	464	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43325	Quartz	ON	465	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43326	Quartz	ON	466	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43327	Quartz	ON	467	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43328	Quartz	ON	468	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43329	Quartz	ON	469	Colorado Resources Ltd. - 100%	4-Apr-16
Mayo	YE43330	Quartz	ON	470	Colorado Resources Ltd. - 100%	4-Apr-16

GEOLOGICAL MAP OF THE ORO TRENCH AREA

YUKON TERRITORY

NTS MAPSHEETS: 105O/07, 105O/06

Latitude: 63° 17’ 43.1” N

Longitude: 130° 57’ 53.0” W

401,500 m E 7,020,000 m N

(Universal Transverse Mercator Zone 9V; 1983 North American Datum)

prepared for

COLORADO RESOURCES LTD.

by

P. Metcalfe, Ph.D. P.Geo.

Palatine Geological Ltd.

P.O. Box 289, Gabriola, B.C.

V0R 1X0

17th February, 2012

SUMMARY

The area mapped during 2011 fieldwork is underlain by a homoclinal sequence of Palæozoic clastic sedimentary rocks with minor limestone and exhalative units. This homoclinal sequence is north-facing, presented in the axis and overturned limb of a north-vergent syncline. The syncline is overthrust from the south by a panel containing Lower Palæozoic Road River Group and is open to the north to the limit of outcrop. Its axial plane dips moderately to the south and its axial plunge appears near-horizontal, but was not determined accurately during 2011 fieldwork.

Rocks exposed in the syncline compose a near-complete paraconformable sequence ranging in age from Ordovician to Mississippian. At the base of this sequence is the Road River Group comprising siltstone of the Steel Formation overlain by argillaceous limestone of the Sapper Formation. The overlying Devonian Earn Group (Portrait Lake Formation) comprises siliceous shale, argillaceous chert and minor bedded barite of the Niddery Lake member at is base, overlain by siliciclastic rocks of the MacMillan Pass member, in turn overlain by siliceous and carbonaceous shale of the Fuller Lake member. The MacMillan Pass member exhibits a facies variation, fining from chert cobble conglomerate in the east to siltstone in the west. With the exception of a sandy limestone unit near the top of the Fuller Lake member, the Portrait Lake Formation lithologies are non-calcareous. This limestone unit returned conodonts of Late Frasnian age.

Grey shale, siltstone and sandstone overlying the Portrait Lake Formation were identified as the Itsi Formation. This unit is exposed on the south side of the mountain's peak and has a true thickness of roughly 150 m. The Itsi Formation is overlain by argillaceous chert and siliceous shale grading up into carbonaceous shale and siltstone. A limestone unit near its base returned conodonts of Tournaisian age; lithologies north of the peak are therefore assigned to the basal part of the Tischu Group.

An inferred subvertical fault (the "Secondary Fault") with a strike of 130 repeats the basal Tischu Group section on its north side. The fault is interpreted as downthrown to the north, setting the upright beds to the south against the overturned limb of the fold to the north. The Tischu Group succession north of this fault passes upsection through a siliciclastic strata with

calcareous cement and a non-calcareous shale unit to the thick Caribou Pass limestone and overlying shale and quartzite units at the limit of exposure.

The sedimentary section has been intruded by numerous irregular suvertical dykes with strikes between 290 and 310. The dykes are peraluminous, with minor garnet as a phenocryst phase and are identified as microgranodiorite porphyry (garnet-bearing, quartz+biotite+plagioclase phyric) in an independent study. The dykes have undergone moderate patchy to intense pervasive phyllic alteration with replacement of all phenocrysts with fine grained dioctahedral mica. The dykes are weakly mineralized with pyrite and arsenopyrite, with late-stage, fracture hosted realgar, orpiment and, less commonly, stibnite. The dykes carry a shear fabric with apparent dextral and minor north side down movement, but their relationship to the Secondary Fault is not known. A second subvertical fault with a strike of 070 passes to the south of the drill area and offsets the dyke swarm and the Secondary Fault with sinistral sense; displacement is estimated to be 85 m.

The Oro gold occurrence is hosted by the above stratigraphy, in proximity to the quartz-phyric dykes. It is probable that more consistent grade occurs at the conjunction of the sheared dykes and the reactive argillaceous and silty limestone of the Sapper Formation. It is necessary that any future drill program test the mineralized zone beginning at the shallower, known mineralization, but it is recommended that testing continue to depths where the contact between the Sapper Formationand the overlying Niddery Lake member is predicted by the geometry of the fold. Shallower drilling preceding this deeper testing should take careful note of the limestone units at the base of the Tischu Group and at the top of the Fuller Lake member as aids to refining the fold geometry.

TABLE OF CONTENTS

List of plates iii
Introduction 4
Field procedures 4
Topographic and geological base 4
Mapping 4
Map compilation 4
Results of geological mapping 5
Stratigraphic units 5
Layered rocks 5
Intrusive rocks 9
Structure 10
Folding 10
Faulting 12
Metamorphism and/or alteration 15
Mineralization 16
A note on 2011 soil sampling 16
Implications of sample depth 16
Implications of the sample sieving procedure 17
Conclusions 17
Acknowledgements 19
References 20

LIST OF PLATES

Plate 1. Geological map of trench area ..... In pocket

INTRODUCTION

This geological report describes briefly the lithologies encountered on the mountain hosting the main trench area and discusses the structures which possibly control or modify the mineralization observed to date. Units of measure in this report are metric. Maps are presented in Universal Transverse Mercator (UTM) projection, using the 1983 North American Datum (NAD'83); the tenure lies in Zone 9V.

FIELD PROCEDURES

Topographic and geological base

2011 fieldwork used a field topographic base comprising National Topographic Database (NTDB) vector topographic information and digital elevation models (DEMs) at 1:50,000 scale. Orthogonal (vertical) views and maps were generated using MapInfo® v.8.0, incorporating these data. Oblique views of the terrain were generated using Global Mapper® v.11.01 to produce computer graphics images (CGIs), incorporating DEM and elements of the topographic data.

Mapping

Mapping was carried out by the author, on solo traverses and also assisted by Mr. Nicholas L. Barber. Field stations were located using a Garmin GPSMap 62 global positioning unit. Sample stations were numbered alphanumerically and the quoted error of the global positioning unit, number of satellites sampled and signal strength were all recorded at each field station, together with lithological and structural data.

Map compilation

Waypoint locations were downloaded and plotted, together with circular error envelopes with radii twice that of the recorded satellite error. Field stations were checked for consistency and the extents of outcrops examined during fieldwork were plotted accurately. Structural information was keyed to waypoint-specified outcrops, with offset of symbols to avoid obscuring data points and small outcrops. The symbol set used is based upon that of the British Columbia Geological Survey Branch (1997).

RESULTS OF GEOLOGICAL MAPPING

A geological map of the area examined is shown in Plate 1. The area mapped lies in the keel and/or upper limb of a north-vergent overturned syncline dissected by west-northwest- and east-northeast-striking transcurrent faults.

Stratigraphic units

Layered rocks

The considerable amount of work carried out in the area by Abbott and Turner(1991), Cecile and Abbott (1992), Cecile (2000) and most recently by Abbott (in prep.) is beyond the scope of this report and (moreover) obviates the necessity for detailed descriptions of each stratigraphic unit. The reader is referred to these for detailed descriptions and regional implications; this report will confine itself to a brief description of each unit and to their disposition within the study area.

Ordovician to Devonian Road River Group

The Road River Group comprises three formations[1]. The uppermost two, (Steel and Sapper formations) are exposed in the immediate study area in the keel of the syncline and in a north-vergent overthrust panel in the extreme south of the area mapped (Plate1). The sequence is not well exposed and estimates of unit thickness are reliant on Abbott's work.

Steel Formation

The Steel Formation comprises thickly laminated bioturbated, non-calcareous siltstone with a "wispy aspect" The unit weathers to a tan colour and bioturbation is most noticeable on weathered surfaces. Abbott (pers. comm.) also noted a distinctive, musical crunching of Steel talus underfoot.

Considerable exposures are visible elsewhere on the property but the Steel Formation is rarely exposed locally, possibly because of comminution and dismemberment near the thrust fault

v

[1] The reader should note that capitalisation of the word "formation" denotes a formally defined stratigraphic unit; lack of capitalisation denotes informal use. The same convention is applied to members within a formation. Formal terms in the plural are not capitalised.

Sapper Formation

The Sapper Formation comprises dark grey argillaceous and silty limestones and calcareous shale and siltstone. The unit weathers a distinctive colour, familiarised as "black and tan" on dry scree slopes; the "tan" component is closer to sienna or medium brown. The unit weathers recessively; exposures other than proximal float are rare in the mapped area.

The Sapper Formation is of interest to exploration for Carlin-type gold deposits, as a reservoir of carbonate. Lithologies in this formation are strongly calcareous, the carbonate being mainly calcite. Subordinate dolomite may also be present.

The thickness of the Sapper Formation in the general area is estimated to be from negligible to as much as 200 m. In the immediate area it is estimated to be well in excess of 100 m (Abbott pers. comm. 2011)

Devonian Earn Group

The Earn Group comprises mainly fine grained sedimentary rocks with two intervals of coarser grained siliciclastic rocks, the older representing coarse clastic sediment movement from the west, the younger consisting of material transported from the north. Excepting the coarsest rocks, the closely similar lithologies hinder identification of members and formations within the group; identification of specific stratigraphic units on the basis of lithology is often contextual (Abbott pers. comm. 2011).

Portrait Lake Formation

Niddery Lake member

The basal member of the Portrait Lake Formation comprises thinly to thickly laminated black siliceous shale and argillaceous chert with lesser, interlaminated carbonaceous shale. A single occurrence of bedded barite occurs in subcrop in Trench H. The unit is roughly 90 m thick and weathers a distinctive pale bluish grey, an attribute shared with the Fuller Lake lithologies, upsection.

MacMillan Pass member

The basal part of the MacMillan Pass member comprises brown weathering thinly bedded to thickly laminated siltstone and shale with a thickness of roughly 60 m. The lithology is

relatively prominent and is overlain by a discontinuous chert pebble conglomerate facies. The latter is the best exposed lithology on the mountain, owing to its generally coarser and more durable nature. Clasts include chert and are as large as cobbles or small boulders in the conglomerate's main exposure to the southeast of the main trench area. Here, the facies attains its greatest local thickness of as much as 100 m, thinning west along strike to as little as two metres in the valley to the east of the Canol Zone. Clasts in this western exposure rarely exceed small pebble size. The conglomerate is absent further west. In its main exposure, it is overlain, by a coarse grit to coarse sandstone unit with a carbonaceous matrix and abundant rip-up clasts of black shale, apparently a transition to the lithology of the overlying unit.

Fuller Lake member

The Fuller Lake member is not well exposed even in trenches, generally forming large pale blue-grey weathering talus exposures. The unit is lithologically very similar to the Niddery Lake member, albeit with a slightly greater content of carbonaceous material, and records a return to quiet siliceous shale sedimentation, following deposition of the MacMillan Pass siliciclastic rocks. The Fuller Lake member exposed in Trench H on the southern slope of the mountain has a thickness of roughly 40 m. Possible variations in this thickness are discussed below.

Itsi Formation

The Itsi Formation, initially defined as a member of the Portrait Lake Formation, overlies the latter unconformably in the area mapped (Abbott pers. comm. 2011). The basal (southern) contact is poorly exposed and there is no evidence to suggest removal of part of the Fuller Lake section.

The Itsi Formation is characterised by brown weathering shale, siltstone and fine sandstone. These lithologies are very similar to those of the finer (shale and sandstone facies) of the MacMillan Pass member. A significant difference (Abbott pers. comm. 2011) is the presence of detrital muscovite in the Itsi Formation; none occurs in the MacMillan Pass member. This difference is less useful than it seems, as discussed in the section on metamorphism and alteration, below.

Devonian to Mississippian Tischu Group

The Tischu Group is exposed on the north side of the mountain, north of the east-southeast-striking Secondary Fault. Its basal contact was not observed, but the basal argillaceous chert and siliceous shale unit is exposed immediately to the north of the fault and its age confirmed by palæontological sampling (Abbott pers. comm. 2011). This basal member has a thickness of greater than 70 m. Overlying the basal siliceous member is a sequence of tan brown weathering, thinly laminated to thinly bedded shales and siltstones with rare beds of fine grained quartz arenite as thick as 1 m. This siltstone/shale member is roughly 150 m thick.

Upsection from the siltstone/shale member, coarser-grained and thicker beds are more common and the matrices of the clastic rocks are calcareous. The base of this member is a thickly laminated to thinly bedded calcareous siltstone and silty limestone, a few metres thick. Lithologies in this unit exhibit a complete gradation, from silica cement to calcite cement within a single quartz arenite bed, over quite short distances along strike. Notwithstanding its patchy distribution, the calcite in these beds is a second, important reservoir of carbonate for a Carlin-style setting. Upsection, the carbonate peters out, but the clastic lithology remains roughly the same.

The Caribou Pass formation (Abbott in prep.) is the only distinctive lithology within the Tischu Group. It is a massive to thickly bedded, beige to light grey weathering dark grey bioclastic calcarenite, resistant to weathering. The unit is roughly 150 m thick and incorporates a brown weathering dark grey thinly bedded shale and siltstone interval 15 m in thickness in the basal third of the formation. This may not be laterally persistent but this shale interval is also exposed on the ridge to the east of the trench area. The Caribou Pass represents the third reservoir of carbonate and a possible host/trap for a Carlin-type environment. The formation is overlain by 50 m of very poorly exposed dark grey shale and siltstone and another 50 m of quartz-cemented quartz arenite or orthoquartzite; these two units record the apparent resumption of a coarsening upward sequence after the Caribou Pass transgression. The orthoquartzite is the youngest sedimentary unit exposed on the mountain and is of inferred Mississippian age.

Intrusive rocks

Cretaceous quartz phyric dykes

The only igneous rocks exposed on the mountain are felsic dykes, locally as thick as 50 m, with a penetrative brittle shear fabric. The dykes compose a small swarm at or near the peak of the mountain and are associated with an airborne magnetic anomaly.

Nine samples of the dykes, in various stages of alteration, underwent detailed petrographic analysis described in a separate report. The dyke lithologies are all garnet-bearing and quartz - plagioclase phyric and include microgranodiorite, microtonalite and andesite compositions. Some of the samples contain biotite phenocrysts; the more strongly altered samples contain muscovite phenocrysts, possibly after biotite. Quartz is the most noticeable phenocryst phase in hand specimen, commonly less than 4 mm and anhedral in most cases but in some dykes the quartz phenocrysts are subhedral, with either trigonal or tetragonal outlines. The latter forms are pseudomorphs after cristobalite and evidence of high-temperature emplacement. Most significantly, the mode of less altered samples includes minor anhedral garnet, indicating that the dykes are peraluminous granitoids, possibly part of the Cretaceous gold metallogene present in the Yukon.

Analytical results from whole-rock analysis confirm that the fresh samples of the dykes are peraluminous potassic granitoids with normative compositions in the monzogranite field. They contain as much as 10% sulphide locally, the bulk of which appears to be pyrite but with a significant component of very fine-grained arsenopyrite; arsenic concentrations are as high as 450 ppm in the fresh rock. Au concentrations in the dykes are generally low but there are fair correlations ($R>0.93$) with As and Hg. When the single high As (and Au) value is eliminated, fair correlations between Au, Sb Tl and Se are also observed. These element correlations are also observed in soil and these elements should be treated as pathfinders for the gold mineralization, whatsoever its genesis.

Timing of intrusion

Thicker dykes have sheared margins and undeformed interiors, indicating a syn-to post-deformational crystallisation period. The shearing appears to be subparallel to the Secondary Fault, this in turn subparallel to the dextral Hess Fault, which has a Cretaceous history of

movement. However, movement on the Secondary Fault in the Saddle Zone appears to be mainly vertical (see below), in conflict with apparently dextral kinematic indicators in the shear fabric within the dykes. The number of measurements taken of the dykes' shear fabric is not statistically significant at the time of writing; future work may resolve the apparent conflict.

The shear fabric in the dykes is rotated about a vertical axis peripheral to the ENE trending fault across the saddle between the main trenches and the ridge to the ESE. The rotation gives explicit sinistral movement on this fault, which also appears to displace the Secondary Fault by as much as 100 m (best estimate 85 m). ENE to NE striking faults throughout the Canadian Cordillera typically moved in the Eocene (Murray Journeay pers. comm. *ca*. 2004), this suggests that the dykes' age is Cretaceous.

Structure

Folding

Three kilometres to the east of the main trench area, on a range dubbed "The Horseshoe" during 2011 fieldwork, Cecile and Abbott (1992) located an overturned syncline, plunging to the west. Subsequent work by Abbott (in prep.) confirmed that the syncline involved Devono-Mississippian Tischu Group rocks. The southern half of the same structure is observed in the northern half of the present study area; 2011 fieldwork confirmed the presence of Tischu Group from its basal member to the orthoquartzite, north of the area drilled by AGIP.

A significant loss of exposure occurs between the small knoll to the north of the trench area and the trench area itself. This is interpreted as the trace of the Secondary Fault (see below). To the south of the fault, bedding is homoclinal and vertical. The shale and siltstone at the peak of the mountain was initially interpreted as the Itsi member of the Portrait Lake Formation, with Fuller Lake shale upsection and downsection.

A limestone bed is exposed within the black shales just beyond the northern contact of the presumed Itsi Formation, at a location just below the north side of the mountain peak. A second exposure on this north side of the presumed Itsi Formation was discovered by Mr. Barber, in an identical stratigraphic location in trench I on the mountain's northwest side. A third "northern" limestone exposure was mapped by the author on the initial day of fieldwork but its significance was not realised at the time. The three limestone locations provide three points from the north

side of the putative Itsi Formation. A three-point solution gives a strike of 128 for the bed, dipping at 73 degrees to the south. If allowance is made for an inferred 16 m dextral displacement on a small fault near the peak, the limestone bed has a strike of 116 and is vertical. These calculations are consistent with all high-confidence measurements of bedding made in the area and are supportive of a northward-facing sequence in the upright or overturned limb of a north-vergent fold. They are inconsistent with the geological model (AGIP) hitherto proposed for the mountain. The sequence to the south of the fault was interpreted by this author as the upright/overturned limb of the same north vergent fold, albeit somewhat displaced.

There is a problem with this interpretation. Abbott (pers. comm. September 2011) noted that the unit presently defined as the Itsi Formation does not occur within the Portrait Lake Formation, but overlies the latter unconformably in this area. He further noted that the shale to the north of the putative Itsi Formation outcrop area did not resemble the typical basal Tischu Group to the north of the saddle. Colpron and Abbott therefore proposed that the synclinal axis in the southern block lies to the south of its previously mapped location, within the outcrop area of putative Itsi Formation south of the peak. Implicit in this hypothesis is the interpretation of the shale sequence to the north as the Fuller Lake member exposed in the northern limb of the syncline.

The latter hypothesis is preferable to that of a homoclinal sequence for two reasons. Firstly, the aforementioned limestone bed close to the "Saddle Shales' southern contact is mirrored by a thin limestone unit encountered in Trench H, just beneath the basal contact of the putative Itsi Formation. Secondly, the zone of disrupted ground of such a fold's axial plane is permissive both for the igneous intrusions encountered there and for mineralising fluids. A objection to the hypothesis lies in the disparity of thickness between the vertically dipping shale sequence in the Saddle Zone (roughly 200 m) and that of the black shale section on the south side of the mountain, near the Canol Zone (40 m). The increase in thickness could owe to replication of the shale section by isoclinal folding (Plate 1) or by fault replication along the Secondary Fault. The fold geometry is significant for a realistic depth estimate to the target Sapper Formation within the mineralized zone.

Testing of folding hypothesis by palæontological analysis

Sampling of the limestone units in the black shale sequences on either side of the peak was carried out by the author and by Mr. Barber in September 2011. Samples from locations PM11-853, PM11-969 and PM11-1022 were examined for microfossils by Dr. M. Orchard of the Geological Survey of Canada.

The ensuing report from the Geological Survey of Canada is pending at the time of writing. Conodonts were recovered from sample PM11-853, from Trench H south of the exposure of inferred Itsi Formation and from sample 1022, north of the exposure of inferred Itsi Formation.

The two sample populations are different; that from PM11-853 is Late Devonian (late Frasnian) in age based on common *Palmatolepis* and rare *Ancyrognathus* specimens. There are also radiolarians and sponge spicules in this collection and the Conodont Alteration Index (CAI) is a consistent 5 (M. Orchard pers. comm. to P. Metcalfe, January 2012).

PM11-1022 is confirmed as Early Carboniferous (Tournaisian) in age based especially on abundant specimens of *Siphonodella*. The CAI ranges from 5 (black) to 7 (white), implying some high heat flow thereabouts: variation like this has previously been related to hydrothermal alteration (M. Orchard pers. comm. to P. Metcalfe). This is consistent with the latter sample location's proximity to a quartz phyric dyke and its situation within the phyllic alteration halo.

On the basis of these analytical results both hypotheses can be rejected. The sequence to the south of the saddle zone is homoclinal rather than folded, but it does not consist entirely of Portrait Lake and Itsi formations; rather the sequence is complete between the basal part of the Portrait Lake Formation (Niddery Lake member) at the Canol Zone through MacMillan Pass and Fuller Lake members south of the peak, Itsi Formation at the peak and, overlying the Itsi Formation, the basal siliceous shales of the Devono-Mississippian Tischu Group, grading upsection into shale and siltstone in the Saddle Zone, adjacent to the Secondary Fault. This revision of the section has implications for the movement of the Secondary Fault, discussed below.

Faulting

All but one of the faults identified by AGIP (including the torsional fault on Cecile and Abbott's 1992 map) were deemed suspect because their displacements are not apparent and the drill data

(zones of core loss) from which they were derived do not stand up to a 3D treatment (Barber and Dunlop unpubl.). The Main Fault in particular retains no credible planar structure when viewed in 3D and has been discarded.

The exception is the Secondary Fault (Aupperle 1985) whose trace runs across the Saddle; the fault is inferred to be responsible for the poor exposure and intensely fractured rock at that location. Its 3D geometry constrains the fault to a strike of 131 and the dip to no less than 87 degrees to the southwest. The Secondary Fault is one of two linear structures that clearly juxtaposes one rock unit against another.

Neither the sense nor extent of movement on the Secondary Fault are known. Horizontal slickensides were located along the fault trace west of the Saddle Zone and the orientation of the fault parallel to the Hess Fault suggests at least some history of dextral movement. Moreover, shearing in the margins of the Cretaceous dykes is apparently dextral with a minor north-side-down component and indicates that timing of the dextral movement was syn and post intrusion. However, the number of in-situ outcrops available for structural measurements is small and by no means represents a statistical sample.

On the basis of the geophysics, Abbott suggested that the Secondary Fault may have a more profound vertical component of movement. Vertical slickensides found at a separate location are evidence for this hypothesis.

Abbott (pers.comm. to Metcalfe September 2011) noted that, if the sequence north of the peak were to be of Tischu Group, this removed the need for the Secondary Fault as a regional structure. Certainly the need for dextral movement on such a structure is removed, contradicting the limited structural data collected from the sheared dykes. However, the basal Tischu argillaceous chert immediately north of the peak passes northwards (upsection) to siliceous shale. Immediately north of the Saddle, the section is repeated, strongly suggesting fault replication. Moreover, the consistent, steep dips in bedding south of the Saddle are most easily rconciled with the overturned, north-facing and steeply south dipping strata north of the Saddle by vertical dislocation of an overturned fold as shown in Plate 1. This model is in agreement with the 2011 aeromagnetic data, which exhibit weakening of the magnetic anomaly to the north of the Secondary Fault, consistent with downthrow to the north.

A second fault became apparent in the last three days of fieldwork. This fault traces down the gully to the east of the trenches in a manner similar to the “Main Fault”, but does not loop northwestward over the peak of the mountain. Instead, its trace is along azimuth 250 up the gully and over the saddle between the trenched area and the exposures of chert pebble conglomerate to the southeast. Drag folding of foliation in a dyke displaced by the fault is about a vertical axis and clearly indicates at least one phase of sinistral movement. The throw is not known but the apparent displacement of the Secondary Fault across this Saddle Fault is estimated to be 85 m. This is consistent with the observed "bend" of rock units from east to west along the southern slope of the mountain. There is no evidence for any vertical component of throw, but the conglomerate facies of the MacMillan Pass Member has not been observed northwest of the Saddle Fault and the fault’s displacement might be more than presently inferred. The brittle nature of the displacement of the dykes and the Secondary Fault suggests post-Cretaceous movement.

The displaced southeastern section of the Secondary Fault is not exposed on the mountain, but deranged and subdued topography (with two or three landing sites on an otherwise unfavourable slope) suggest its approximate trace. It emerges on the western slopes of the Horseshoe, east of the mapped area, where it sets brown siltstone, inferred to be Tischu Group on its north side, against chert pebble conglomerate and blue-grey weathering black shale of the MacMillan Pass and Fuller Lake members to the south. At this point it may converge or be conjugate with the northerly trending structure mapped by Abbott along the western slope of the Horseshoe, but this is not immediately relevant to the structure and economic geology of the mountain itself. The Secondary Fault is possibly traceable some 12 km to the east, where it merges with the trace of the Hess Fault.

The continuity of the MacMillan Pass conglomerate unit from the eastern slopes of the mountain onto the western slopes of the Horseshoe precludes the presence of a north-striking fault along the valley bottom of the creek between. The necessary movement is along a fault trace along the western hillside of the Horseshoe, as noted by Abbott (in prep.).

Metamorphism and/or alteration

Aupperle (1985) records alteration near and in the dykes thus:

> *The most prominent alterations are bleaching (removal of carbonaceous-graphitic material) and silicification of the shales. Clay alteration is more restricted in extent.*
>
> *Bleaching occurs either as narrow bands adjacent to fractures and bedding planes or pervasively over intervals up to 3 meters. Pervasive weak silicification occurs throughout. Local zones of intense silicification also occurs (sic). In fault-gouge zones, clay alteration commonly reduces the shale to soft, massive clay.*
>
> *Almost all the monzonite intrusives (*sic*) exhibit weak to moderate sericitization, clay alteration, limonitization, bleaching and rarely silicification. The largest and most intense zone of bleached and silicified shale . . . . is spatially related to a swarm of weakly to strongly clay altered monzonite intrusives. Within this zone, unaltered shales have been observed in contact with the monzonite. These shales become bleached and silicified away from the intrusives. An increase in fracturing and faulting, both in shales and monzonites, appears to be the major control on alteration within this zone.*
>
> *Intense clay development in gouge zones, local silicification and rare bleaching occur in . . . . fault zones. Clay zones from 0.1 to 8.4 m in true thickness were intersected in all drill holes.*

Notwithstanding this excellent description, the zone surrounding the main area of dyke intrusion was subsequently described by Hulstein and Keyser (1989) as a zone of "hornfelsing". No hornfelsing whatsoever was observed during the course of 2011 fieldwork, although it is possible that such once existed and were overprinted by the pervasive alteration noted by Aupperle. Two addenda to Aupperle's description are: firstly, that the fine-grained muscovite alteration he describes is more widespread than assumed, much of it masquerading as clay alteration; secondly: that the expression of this alteration in the siliceous shales is far more subdued than in the siliciclastic rocks, being confined to (possibly) recrystallization of the silica and (certainly)

development of graphite on bedding-parallel and oblique cleavage surfaces. The graphite would have acted as a buffer for oxygen fugacity during alteration and probably through the mineralising process.

A further consequence of muscovite/sericite alteration of the siliciclastic units is the appearance of non-detrital dioctahedral mica (muscovite), masking the detrital component and confusing still further attempts at discriminating between Itsi Formation and the finer-grained facies of the MacMillan Pass member.

Mineralization

Two types of mineralization are present in the area mapped, neither associated with significant quantities of hydrothermal quartz. The first-formed is a fine grained dissemination of pyrite and minor arsenopyrite hosted by the relatively unaltered parts of the dykes and interpreted as a late magmatic or early deuteric event. Subsequent shearing and related tensional fracturing host locally abundant realgar, orpiment and stibnite, interpreted as a low temperature remobilization of the magmatogenic sulphide. The later phase appears supergene in nature but, while this can be true of orpiment, realgar does not form from water cooler than 100°C and more commonly 144-170°C. This late phase is therefore closer to epithermal in character.

As noted above, weak values of Au in the dykes exhibit fair covariance with As, Sb, Hg Se and Tl; these should be treated as pathfinder elements. Other elements will become apparent when the sample population exceeds 6.

A note on 2011 soil sampling

The 2011 soil survey covered an immense amount of ground and a commensurate length in line kilometres. The resulting sample output is, apparently, still in process at Acme. Both rapid coverage and pre-screening of the samples by X-ray fluorescence spectrometry were necessary in order to complete the project. Nevertheless, the results will be constrained both by natural and by anthropogenic processes.

Implications of sample depth

The author sampled a soil profile exposed at the northern end of Trench J. The reasons for the choice of location were:

1. The location exposed a complete section to the surface of a relatively unaltered arsenopyrite-bearing dyke;
2. Analysis tested the association of Au with the dykes and:
3. It was a lot easier than the author digging his own hole.

The sample location was on a hillside with an average slope of roughly 25°. Colluvium almost entirely composed of dark grey shale composed the upper 80 cm of the profile, underlain by clay and sericite altered dyke material. Six samples were taken from the profile, the upper three from the thin organic later and two washes of colluvium.

During the course of fieldwork, the maximum depth of soil hole encountered by the author was 75 cm. It is axiomatic that transported anomalies will be the rule rather than exceptions.

Implications of the sample sieving procedure

During the course of submitting samples for the normal screening procedure, the author observed the condition of the sample sieve between samples. A sharp rap on a hard surface dislodged between 50 gm and 100 gm of material from the screen. The field assistant carrying out the sieving had access neither to compressed air nor to ultrasonic cleaning. It is, consequently, not a question of whether samples were cross contaminated but by how much and in what sequence. Happily, the samples were sieved in numerical order, so the cross-contamination will present as blurring of an anomaly through a first-order rate law, down the line from the anomalous sample site(s). There will be a wild attractor in gold, owing to nugget effects, but the contamination is amenable to statistical treatment of base element values and further screening (this time by statistical methods).

CONCLUSIONS

Mapping in 2011 and subsequent analysis indicates that the area is underlain by a homoclinal sequence of Palæozoic clastic sedimentary rocks with minor limestone and exhalative units. This homoclinal sequence is north-facing, presented in the axis and overturned limb of a north-vergent syncline. The syncline is overthrust from the south by a panel containing Lower Palæozoic Road River Group and is open to the north to the limit of outcrop. Its axial plane dips

moderately to the south and its axial plunge appears near-horizontal, but was not determined accurately during 2011 fieldwork.

Rocks exposed in the syncline present a near-complete paraconformable sequence ranging in age from Lower Palæozoic Road River Group to Devono-Mississippian Tischu Group. At the base of this sequence is the Road River Group comprising siltstone of the Steel Formation overlain by argillaceous to silty limestone of the Sapper Formation. The overlying Devonian Earn Group (Portrait Lake Formation) includes basal siliceous shale and argillaceous chert of the Niddery Lake member, siliciclastic rocks of the MacMillan Pass member and siliceous and carbonaceous shale of the Fuller Lake member. North of the peak and extending to the Saddle, are basal argillaceous cherts and siliceous shale and siltstone of the Devono-Mississippian Tischu Group. Replication of the basal Tischu section on the other side of the Saddle confirms the presence of the Secondary Fault, but requires vertical rather than strike-slip movement, downthrowing that part of the syncline on the north side of the fault.

The sedimentary sequence is intruded, in the vicinity of the peak by a number of irregular, subvertical dykes with sheared margins, possibly with dextral sense. This sense of movement is inconsistent with the movement of the Secondary Fault and may predate the latter. The shearing, combined with previous bedding-parallel movement and parasitic folding associated with development of the syncline, will have optimised permeability for hydrothermal fluids. It is suggested here that elongation of the elevated gold zone subparallel to bedding and its coincidence with the location of the dykes implies involvement of the dykes as a heat source for the mineralizing system. A phyllic alteration halo occurs around the dykes and the formation of graphite on bedding and cleavage surfaces in the carbonaceous, siliceous shales is interpreted as a composition-specific response to this phyllic alteration. This might fulfil one requirement of a Carlin-type system, if calcareous units are in proximity. The limestone unit at the base of the Tischu Group is thin but may be responsible for locally elevated gold grades at or near surface in the area drill-tested to date.

Not one but two large calcareous units are available, excluding the Caribou Pass Limestone on the basis of its distance from the dykes. The Squirrel Pass calcareous member within the Tischu Group is much shallower and moreover explicitly in contact with a dyke of the quartz phyric

suite on the north side of the Secondary Fault. There is little alteration or mineralization in the vicinity, but the potential of this unit should be noted.

A far more prospective unit is the 150 m thick argillaceous limestone of the Sapper Formation, overlain by the siliceous and carbonaceous shale of the Niddery Lake member. Indeed the coincidence of the mineralization at surface with this contact on the southern slope of the mountain (the "Canol Zone") was noted by Hulstein and Keyser (1989). Garagan (1983) noted that the sycline's geometry required that the contact between the Sapper argillaceous limestone and the overlying siliceous and carbonaceous shale of the Niddery Lake member be present at between 300 and 500 m beneath the Saddle Zone. This author suggests a somewhat greater depth of 600 m or more beneath the peak of the mountain.

This author submits, with respect, that the encouragement encountered in the 1980s drilling records only the tip of the system and that the zone of more regular gold values lies, as Mr. Barber has suggested, at greater depth. It is recommended that deeper drilling be contemplated and that a closer study made of existing information on gold:silver ratios in the system. Exploration should make use of oriented core with particular attention to core-bedding angles and the location of the two limestone units above and below the Itsi Formation. The target zone for the gold mineralization should be tested from surface to the intersection of the dykes with the Sapper/Niddery Lake contact.

ACKNOWLEDGEMENTS

Mapping benefited greatly from the assistance of Nicholas L. Barber in the field; Mr. Barber continued with mapping of the trenches in the area. Maurice Colpron and Grant Abbott provided crucial help with their hypotheses regarding structure and regional geology, without which the structure would not have been resolved by the conodont expertise of Mike Orchard of the Geological Survey of Canada. Adam Travis, Mike Cathro, Linda Dandy and Dugald Dunlop provided much-needed support and advice.

REFERENCES

Abbott, J.G. and Turner, R.J., 1991: Character and Paleotectonic Setting of Devonian Stratiform Sediment - Hosted Zn, Pb, Ba Deposits, Macmillan Fold Belt, Yukon; *in*: Abbott, J.G. and Turner, R.J.W. (eds.); Mineral Deposits of the northern Canadian Cordillera, Yukon - northeastern British Columbia [Field Trip 14], Geological Survey of Canada, Open File 2169, pp. 99-136.

Aupperle, M.J., 1985: Assessment report, Brick 1-40, Neve 1-35 claims; Yukon Territory Mineral Assessment Report 091770, 256 p., 6 maps

Cecile, M.P., 2000: Geology of the northeastern Niddery Lake map area, east-central Yukon and adjacent Northwest Territories; Geological Survey of Canada, Bulletin 553,122p.

Cecile, M.P. and Abbott, J.G., 1992: Geology of the Niddery Lake map Area, Yukon Territory - Northwest Territories; Geological Survey of Canada, Open File, 2465.

Garagan, T., 1983: Brick/Neve Project, 1983 Exploration Activities; Private Report, Agip Canada Ltd.

Hulstein, R.W. and Keyser, H.J., 1989: Assessment Report on the 1988 exploration program on the Brick property; Yukon Territory Mineral Assessment Report 091770, 131 p., 1 map


Colorado Resources Ltd.

Figure 1: Oro Property Location Map

MacMillan Pass Area, Mayo Mining District, Yukon

NTS Mapsheets: 105O/02,03,06,07 Date: 2012-02-18




Colorado Resources Ltd.
ORO PROPERTY
Fig 2: Claim Map
MacMillan Pass Area, Mayo Mining District, Yukon
1:20,000
0 510 1,020 1,530 2,040
Meters
Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17
Legend
Greater Oro Property
Greater Oro Claim Groups
Greater Oro Claims
Mining Road
N
Limey Ridge
J.O. ZONE
SADDLE ZONE
CANOL ZONE
GOLDEN HINGE
GOLDEN RIDGE
NORTH STEEL AREA
Repeater Zone
West's Zone
Area 51

Colorado Resources Ltd.

ORO PROPERTY

Figure 3: Regional Geology Map

MacMillan Pass Area, Mayo Mining District, Yukon

Mapsheets:105O/02,3,6,7 Datum:NAD83 UTM Zone 9 Date:2012-02-18

Regional Geology

QUATERNARY

Q — Unconsolidated glacial, glaciofluvial and glaciolacustrine deposits

CARBONIFEROUS TO PERMIAN

CPMC — MOUNT CHRISTIE: shale, chert, slate, siltstone, quartzite, limestone, dolostone

MISSISSIPPIAN

MK — KENO HILL: quartz arenite, shale, phyllite

UPPER DEVONIAN TO LOWER MISSISSIPPIAN

DMEC1 — EARN - CASSIAR: slate, greywacke, grit, conglomerate, volcanidastic rocks

DMEC1? — EARN - CASSIAR: slate, greywacke, grit, conglomerate, felsic volcanidastic rocks

DMEC2 — EARN - CASSIAR: chert, cherty tuff, bedded barite

DMEC3 — EARN - CASSIAR: rhyolite-trachyte,andesite flows, breccias & tuffs, slate, cherty tuff, limestone, trachyte dykes

DEVONIAN AND MISSISSIPPIAN

DME1 — EARN: slate, arenite, wacke, conglomerate siltstone, barite, rare limestone

DME2 — EARN: shale, argillite, chert, barite, rare limestone

ORDOVICIAN TO LOWER DEVONIAN

ODR — ROAD RIVER - SELWYN: shale, chert, siltstone, limestone

ODR1 — ROAD RIVER - SELWYN: shale, chert, limestone

ODR2 — ROAD RIVER - SELWYN: argillite, dolomitic siltstone

ODR3 — ROAD RIVER - SELWYN: black & silty limestone

ODR4 — ROAD RIVER - SELWYN: black shale; limestone

UPPER CAMBRIAN AND ORDOVICIAN


COR1 — RABBITKETTLE: silty limestone, phyllite, conglomerate, siltstone, chert, mafic flows, breccia


CAMBRIAN TO SILURIAN

CSM — MARMOT: lower Paleozoic mostly mafic volcanics

LOWER CAMBRIAN

ICS — SEKWI: limestone, limestone conglomerate, breccia, dolostone, quartz sandstone, siltstone, dolostone





Legend

Minfile

- Deposit
- Drilled Prospect
- Prospect
- Showing
- Anomaly

Geology: Mining Yukon, Mining and Exploration Portal, 2011; Bedrock Geology of Yukon

YGS; Digital Bedrock Geology of the Yukon

ABBOTT, J.G.,2012; Bedrock Geology of the Macmillan Pass Area, Yukon
Yukon Geological Survey Geoscience Map 2012-1

Colorado Resources Ltd.
ORO PROPERTY

Fig 4: Property Geology Map

YGS; Yukon Regional Geology (West Half)
G. Abbott Geoscience Map 2012-1 (East Half)

MacMillan Pass Area, Mayo Mining District, Yukon
1:25,000
0 500 1,000 1,500 2,000 2,500
Meters
Mapsheets: 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-21

Limey Ridge

West's Zone

MINORCO

GOLDEN HINGE

GOLDEN RIDGE

NEVE

Repeater Zone

STROSHEIN

NORTH STEEL AREA

TRYALA

FAL

Area 51

Macmillan

Regional Geology

QUATERNARY
- Q — Unconsolidated glacial, glaciofluvial and glaciolacustrine deposits

CARBONIFEROUS TO PERMIAN
- CPMC — MOUNT CHRISTIE: shale, chert, slate, siltstone, quartzite, limestone, dolostone

MISSISSIPPIAN
- MK — KENO HILL: quartz arenite, shale, phyllite

UPPER DEVONIAN TO LOWER MISSISSIPPIAN
- DMEC1 — EARN - CASSIAR: slate, greywacke, grit, conglomerate, volcaniclastic rocks
- DMEC1? — EARN - CASSIAR: slate, greywacke, grit, conglomerate, felsic volcaniclastic rocks
- DMEC2 — EARN - CASSIAR: chert, cherty tuff, bedded barite
- DMEC3 — EARN - CASSIAR: rhyolite-trachyte,andesite flows, breccias & tuffs; slate, cherty tuff, limestone, trachyte dykes

DEVONIAN AND MISSISSIPPIAN
- DME1 — EARN: slate, arenite, wacke, conglomerate siltstone, barite, rare limestone
- DME2 — EARN: shale, argillite, chert, barite, rare limestone

ORDOVICIAN TO LOWER DEVONIAN
- ODR — ROAD RIVER - SELWYN: shale, chert, siltstone, limestone
- ODR1 — ROAD RIVER - SELWYN: shale, chert, limestone
- ODR2 — ROAD RIVER - SELWYN: argillite, dolomitic siltstone
- ODR3 — ROAD RIVER - SELWYN: black & silty limestone
- ODR4 — ROAD RIVER - SELWYN: black shale; limestone

UPPER CAMBRIAN AND ORDOVICIAN
- COR1 — RABBITKETTLE: silty limestone, phyllite, conglomerate, siltstone, chert, mafic flows, breccia

CAMBRIAN TO SILURIAN
- CSM — MARMOT: lower Paleozoic mostly mafic volcanics

LOWER CAMBRIAN
- ICS — SEKWI: limestone, limestone conglomerate, breccia, dolostone, quartz sandstone, siltstone, dolostone

REGIONAL CONTACTS
- INTRUSIVE: defined
- STRATIGRAPHIC: defined; approximate; assumed
- SURFICIAL: approximate

REGIONAL FAULTS
- NORMAL / REVERSE: defined; approximate; extrapolated
- THRUST UPRIGHT: defined; approximate; extrapolated
- MOVEMENT UNDEFINED: defined

ABBOTT GEOLOGY LEGEND

CRETACEOUS
- Kg — Rasayoni, blocky, grey weathering porphyritic to equigranular biotite quartz monzonite and biotite granite

TRIASSIC
- TJ — JONES LAKE FORMATION: recessive buff brown weathering thin bedded to thinly laminated calcareous sandstone and shale

PERMIAN
- MPMC — MOUNT CHRISTIE FORMATION: resistant dark orange-brown weathering, interbedded chert/mafic grey siliceous shale and recessive green shale

UPPER DEVONIAN AND MISSISSIPPIAN
- MDT — TSICHU GROUP
  - MDT — UNDIFFERENTIATED FORMATION: grey weathering thick bedded to massive bioclastic limestone. Minor sandy crinoidal and shale.
  - MTss — SANDSTONE FACIES: dark grey weathering massive to thick bedded quartz arenite; thin to medium bedded sandstone and quartz arenite with shale interbeds.
  - DMHs — SHALE FACIES: recessive brown, blue-brown and dark blue weathering silty shale, shale and siliceous shale with minor sand stone and quartz arenite. Commonly includes a basal bilateral of blue weathering siliceous shale.

UPPER DEVONIAN
- DI — ITSI FORMATION: resistant brown weathering, thick bedded, parallel laminated and rippled cross laminated arenitolime, siltstone and shale. In southeast 105O/1 and southwest 105O/2, brown weathering shale, siltstone and minor sandstone

LOWER (?) to UPPER DEVONIAN
- DFCHT — FORTYMILE LAKE FORMATION (chalcedony)
- DMCG — SHALE FACIES: black to dark blue weathering massive chert pebble conglomerate

MIDDLE(?) AND UPPER DEVONIAN
- DF — FORTYMILE LAKE FORMATION
  - FOOTWALL CHERT: recessive thinning blue-blue weathering platey siliceous shale, minor chert. Thin beds of coarse grained limestone and platey grey weathering barite in beds less than 1.0 m thick occur intermittently near the top of the unit.

MIDDLE DEVONIAN
- DMCG — MACMILLAN PASS MEMBER:
  - DMCG — CONGLOMERATIC FACIES:Resistant grey weathering massive chert pebble conglomerate with minor sandstone and grit
  - DMss — SANDSTONE FACIES: brown weathering coarse to medium grained sandstone, siltstone with brown chert pebble conglomerate and shale.
  - DMsh — SHALE FACIES: brown weathering thinly laminated grey shale and siltstone with lesser chert and quartz sandstone, grit and minor chert conglomerate.

LOWER AND MIDDLE DEVONIAN
- DN — ROSCOE FORMATION
  - ASSEMPY LAYE MEMBER: black to dark blue weathering thin bedded chert, cherty argillite, siliceous shale and minor limestone. Minor thin to medium bedded limestone beds up to 1.0 m thick near the base and intermittent barite up to 10 cm thick forms one of more horizons.

LOWER DEVONIAN
- DH — HAKONLAIN PASS VOLCANICS: orange weathering carbonate rich mafic volcaniclastic rocks and minor mafic siliceous sedimentary rocks. Local thinly, resistant dark grey weathering coarse crystal tuff.

ORDOVICIAN TO MIDDLE DEVONIAN
- ODN — SAWTOOTH, STEELE and DUVO LAKES FORMATIONS undivided

UPPER SILURIAN TO MIDDLE DEVONIAN
- SDS — SAWTOOTH FORMATION: buff to tan weathering platy silty limestone, calcareous black shale. Locally includes lenses of massive grey limestone at TOTZY.

UPPER SILURIAN TO MIDDLE DEVONIAN
- SDS — SAWTOOTH FORMATION: buff to tan weathering platy silty limestone, calcareous black shale. Locally includes lenses of massive grey limestone at TOTZY.

UPPER SILURIAN
- SS — STEEL FORMATION: orange to green weathering bioturbated, wispy laminated grain shale and mudstone

EARLY ORDOVICIAN TO MIDDLE SILURIAN
- ODV — DUVO LAKES MEMBER CREEK FORMATIONS: brown weathering medium bedded chert carbon ly silver to dark blue weathering thin bedded black chert and siliceous shale. Outcrops westward to claim at the Orvan Creek Formation at TOTZY north of the Rose/Mac/Fault zone.

UPPER CAMBRIAN TO MIDDLE ORDOVICIAN
- COR — RABBITKETTLE FORMATION: grey weathering thin bedded silty limestone with minor limestone and grey shale interbeds.

MIDDLE CAMBRIAN
- CH — HESS RIVER FORMATION: blue brown weathering siliceous shale with minor limestone and limestone conglomerate.

LOWER AND MIDDLE CAMBRIAN
- COG — GOWAY FORMATION: intercalated orange weathering thin bedded grey limestone and limestone conglomerate.

NEOPROTEROZOIC AND LOWER CAMBRIAN
- PCN — HAPPO FORMATION: dark brown and grey weathering grey shale, siltstone and minor sandstone

SYMBOLS

Geological contact: defined; approximate; inferred or covered
Fault, movement not known: defined; approximate; inferred or covered
Normal fault (symbol on hanging wall side): defined; approximate; inferred or covered
Strike-slip fault: defined; approximate; inferred or covered
Thrust fault (symbol on hanging wall side): defined; approximate; inferred or covered
Anticline: upright; overturned
Syncline: upright; overturned
Bedding: upright; vertical; overturned
Axial plane cleavage: inclined; vertical
Fossil locality
Limit of outcrop
Limit of mapping
Landslide
Boulder barrie
Gargleyer
Road; trail

Legend
- Oro Property
- Mining Road

Figure 5
Geological map of the showing area, Oro property

Scale:1:5,000

LEGEND

Layered rocks
Upper Devonian to Mississippian Tischu Group

- unnamed, upper quartzite: quartz cemented quartz arenite (quartzite)
- unnamed, middle shale: thinly bedded to thickly laminated shale
- Caribou Pass formation, undivided, mainly bioclastic limestone.
- Caribou Pass formation, upper bioclastic limestone: massive
- Caribou Pass formation, siltstone/shale member
- Caribou Pass formation, lower bioclastic limestone: massive
- unnamed, siltstone/shale/quartzite: thickly to thinly bedded.
- unnamed, calcareous fine siliciclastic (Squirrel Pass member)
- unnamed, siltstone/shale: siliceous and carbonaceous shale
- unnamed, basal siliceous shale: siliceous shale and carbonaceous chert

Devonian Earn Group
Unknown, possibly Itzi Formation

- brown weathering dark grey shale and siltstone

Devonian Portrait Lake Formation

- Fuller Lake member: siliceous and carbonaceous shale
- MacMillan Pass member, conglomerate facies: chert pebble conglomerate.
- MacMillan Pass member, shale facies: brown weathering shale and siltstone
- Niddery Lake member: siliceous and carbonaceous shale

Ordovician to Devonian Road River Group

- Sapper Formation: calcareous siltstone and argillaceous limestone
- undivided (Sapper/Steel Fms.):

Intrusive rocks
Cretaceous

- Garnet+quartz+biotite phyric dyke suite


Geological contacts


- Contact, stratigraphic, defined
- Contact, stratigraphic, approximate
- Contact, stratigraphic, inferred
- Contact, stratigraphic, possible
- Marker, quartzite bed, defined
- Marker, quartzite bed, approximate
- Marker, limestone bed, inferred
- Contact, stratigraphic/diagenetic, defined
- Contact, stratigraphic/diagenetic, approximate
- Contact, stratigraphic/diagenetic, inferred
- Contact, facies boundary, defined
- Contact, facies boundary, approximate
- Contact, facies boundary, inferred
- Contact, faulted, defined
- Contact, faulted, approximate
- Contact, faulted, inferred
- Contact, thrust faulted, inferred
- Limit, exposure, defined


- Contact, intrusive, defined
- Contact, intrusive, approximate
- Contact, intrusive, inferred


Structural and lithological samples

- Bedding, tops determined, inclined
- Bedding, tops determined, overturned
- Bedding, tops not determined, inclined
- Bedding, tops not determined, vertical
- Minor fold axial plane, inclined
- Minor fold axis, horizontal
- Minor fold axis, plunging
- Bedding^cleavage, angle
- Cleavage, unspecified generation, inclined
- Cleavage, unspecified generation, vertical
- Cleavage, generation n, inclined
- Cleavage, generation n+1, inclined
- Cleavage^cleavage, angle
- Shear fabric, inclined
- Fabric, not defined, inclined
- Tension fracture, inclined
- Tension fracture, vertical
- Contacts, felsic dyke, inclined
- Contacts, felsic dyke, vertical
- Quartz vein, inclined
- Sample, palæontological
- Sample, petrographic only
- Sample, petrographic and whole rock chemical analysis









Map projection: Universal Transverse Mercator (UTM) Zone 9. 1983 North American Datum (NAD'83).
Grid North (used in map): 358.24 True (i.e. west of True North)
2012 magnetic declination: 22.94 True
Azimuths calculated using the Geographic Magnetic Calculator (Geomag v.3.0; Petrie 2010).
Topographic vector data from the National Topgraphic Database.
Major contour (black) interval 100 m
Minor contour (brown) interval 20 m

Bedrock mapping carried out from 6th July, 2010 to 18th September, 2011
Geological mapping by Paul Metcalfe and Nicholas L. Barber.
Contributions from Grant Abbott, Maurice Colpron, Adam Travis, Linda Dandy,
Mike Cathro and Dugald Dunlop gratefully acknowledged.
Compilation date 30th November, 2011

Paul Metcalfe
30th November, 2011

Colorado Resources Ltd.

ORO PROPERTY

Fig 6: Prospecting Rock Sample Locations

MacMillan Pass Area, Mayo Mining District, Yukon

1:20,000

0 500 1,000 1,500 2,000

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-21

Legend

- Prospecting Rock Sample
- Mining Road
- Oro Property

N

Limey Ridge

GOLDEN HINGE

GOLDEN RIDGE

NORTH STEEL AREA

Repeater Zone

West's Zone

Area 51

Colorado Resources Ltd.

ORO PROPERTY

Fig 7A: Soil & Silt Sample Location Map (West Sheet)

MacMillan Pass Area, Mayo Mining District, Yukon

1:10,000

0 250 500 750 1,000 Meters


Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

N

Legend

- Oro Property
- Silt Sample Location
- Soil Sample Location

MAP KEY



Colorado Resources Ltd.

ORO PROPERTY

Fig 7B: Soil & Silt Sample Location Map

(Central Sheet)

MacMillan Pass Area, Mayo Mining District, Yukon

1:10,000

0 250 500 750 1,000

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

N

Legend

- Colorado Claims
- Silt Sample Location
- Soil Sample Location

Refer to Figure 7D for Soil Sample Numbers

JO-Saddle Zone

MAP KEY

105O06 105O07 105O03 105O02

JO-Saddle-Canol

JO-Saddle Zone

Canol Zone

West

Central

East

Canol

Mining Rd. To Mac Pass

0 2 4 8

Kilometers

Colorado Resources Ltd.

ORO PROPERTY

Fig 7C: Soil & Silt Sample Location Map

(East Sheet)

MacMillan Pass Area, Mayo Mining District, Yukon

1:10,000

0 250 500 750 1,000

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

N

Legend

- Oro Property
- Silt Sample Location
- Soil Sample Location

MAP KEY

105O06 105O07 105O02 105O03

JO-Saddle-Canol

JO-Saddle Zone

Canol Zone

West

Central

East

Winter Road

0 2.5 5 10

Kilometers

Mining Rd. To Mac Pass

N

Colorado Resources Ltd.

ORO PROPERTY

Fig 7D: Soil & Silt Sample Locations (J.O., Saddle & Canol Zones)

MacMillan Pass Area, Mayo Mining District, Yukon

1:1,500

0 50 100 150

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

Legend

- Colorado Claims
- Silt Sample Location
- Soil Sample Location

401000

7021000

7020000

7019000

1095648

1095651

1095707

1095714

1095512

1095511

1095516

1279201

JO-Saddle Zone

Canol Zone

ORO

MAP KEY

105O06

105O07

105O03

105O02

JO-Saddle-Canol

West

Central

East

Mining Rd

To Mac Pass

390000 400000 410000 420000

0 2.5 5 10

Kilometers

Colorado Resources Ltd.

ORO PROPERTY
2011 Soil & Silt Sample Results
Figure 8: Gold

MacMillan Pass Area, Mayo Mining District, Yukon

1:20,000

0 500 1,000 1,500 2,000

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

Legend

Oro Property

Silt Geochem Au (ppb)
(Values >95th Percentile Posted)
- <4
- 4 - 5 (50th Percentile)
- 6 - 8 (75th Percentile)
- 9 - 12 (90th Percentile)
- 13 - 15 (95th Percentile)
- >15 (98th Percentile)

Soil Geochem Au (ppb)
(Values >95th Percentile Posted)
- <4
- 4 - 6 (50th Percentile)
- 7 - 12 (75th Percentile)
- 13 - 20 (90th Percentile)
- 21 - 43 (95th Percentile)
- >43 (98th Percentile)

N

Limey Ridge

See Fig 20 for Geochem Detail

GOLDEN HINGE

GOLDEN RIDGE

NORTH STEEL AREA

Repeater Zone

West's Zone

Area 51

See Fig 20 for Geochem Detail

Mineral Claim

Mac

Colorado Resources Ltd.

ORO PROPERTY
2011 Soil & Silt Sample Results
Figure 9: Silver

MacMillan Pass Area, Mayo Mining District, Yukon

1:20,000

0 500 1,000 1,500 2,000

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

Legend

Oro Property

Silt Geochem Ag (ppm)

(Values >95th Percentile Posted)

- < 0.7
- 0.7 - 1.1 (50th Percentile)
- 1.1 - 1.7 (75th Percentile)
- 1.7 - 2.6 (90th Percentile)
- 2.6 - 3.3 (95th Percentile)
- > 3.3 (98th Percentile)

Soil Geochem Ag (ppm)

(Values >95th Percentile Posted)

- < 0.6
- 0.6 - 1.2 (50th Percentile)
- 1.2 - 2.2 (75th Percentile)
- 2.2 - 3.2 (90th Percentile)
- 3.2 - 4.9 (95th Percentile)
- > 4.9 (98th Percentile)

N

Limey Ridge

See Fig 21 for Geochem Detail

GOLDEN HINGE

GOLDEN RIDGE

NORTH STEEL AREA

See Fig 21 for Geochem Detail

Repeater Zone

West's Zone

Area 51

See Fig 20 for Geochem Detail

Colorado Resources Ltd.

ORO PROPERTY
2011 Soil & Silt Sample Results
Figure 10: Arsenic

MacMillan Pass Area, Mayo Mining District, Yukon

1:20,000

0 500 1,000 1,500 2,000

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

Legend

Oro Property

Silt Geochem As (ppm)
(Values >95th Percentile Posted)
- <30
- 31 - 40 (50th Percentile)
- 41 - 60 (75th Percentile)
- 61 - 93 (90th Percentile)
- 94 - 219 (95th Percentile)
- >219 (98th Percentile)

Soil Geochem As (ppm)
(Values >95th Percentile Posted)
- <20
- 21 - 37 (50th Percentile)
- 38 - 76 (75th Percentile)
- 77 - 125 (90th Percentile)
- 126 - 285 (95th Percentile)
- >285 (98th Percentile)

N

Limey Ridge

See Fig 21 for Geochem Detail

GOLDEN HINGE

GOLDEN RIDGE

NORTH STEEL AREA

See Fig 21 for Geochem Detail

Repeater Zone

West's Zone

Area 51

See Fig 20 for Geochem Detail

Colorado Resources Ltd.

ORO PROPERTY
2011 Soil & Silt Sample Results
Figure 11: Antimony

MacMillan Pass Area, Mayo Mining District, Yukon

1:20,000

0 500 1,000 1,500 2,000

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

Legend

Oro Property

Silt Geochem Sb (ppm)
(Values >95th Percentile Posted)
- <5
- 6 - 8 (50th Percentile)
- 9 - 13 (75th Percentile)
- 14 - 17 (90th Percentile)
- 18 - 27 (95th Percentile)
- >27 (98th Percentile)

Soil Geochem Sb (ppm)
(Values >95th Percentile Posted)
- <3
- 4 - 7 (50th Percentile)
- 8 - 14 (75th Percentile)
- 15 - 23 (90th Percentile)
- 24 - 41 (95th Percentile)
- >41 (98th Percentile)

N

Limey Ridge

See Fig 21 for Geochem Detail

GOLDEN HINGE

GOLDEN RIDGE

NORTH STEEL AREA

See Fig 21 for Geochem Detail

Repeater Zone

West's Zone

Area 51

See Fig 22 for Geochem Detail

Mine

Mine

Colorado Resources Ltd.

ORO PROPERTY
2011 Soil & Silt Sample Results
Figure 12: Mercury

MacMillan Pass Area, Mayo Mining District, Yukon

1:20,000

0 500 1,000 1,500 2,000

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

Legend

Oro Property

Silt Geochem Hg (ppm)
(Values >95th Percentile Posted)
- <0.31
- 0.31 - 0.58 (50th Percentile)
- 0.58 - 1.11 (75th Percentile)
- 1.11 - 1.70 (90th Percentile)
- 1.70 - 2.25 (95th Percentile)
- >2.25 (98th Percentile)

Soil Geochem Hg (ppm)
(Values >95th Percentile Posted)
- <0.16
- 0.16 - 0.42 (50th Percentile)
- 0.42 - 1.05 (75th Percentile)
- 1.05 - 2.00 (90th Percentile)
- 2.00 - 5.51 (95th Percentile)
- >5.51 (98th Percentile)

N

Limey Ridge

See Fig 20 for Geochem Detail

GOLDEN HINGE

GOLDEN RIDGE

See Fig 21 for Geochem Detail

NORTH STEEL AREA

Repeater Zone

West's Zone

Area 51

See Fig 22 for Geochem Detail

Colorado Resources Ltd.

ORO PROPERTY
2011 Soil & Silt Sample Results
Figure 13: Bismuth

MacMillan Pass Area, Mayo Mining District, Yukon

1:20,000

0 500 1,000 1,500 2,000

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

Legend

Oro Property

Silt Geochem Bi (ppm)
(Values >95th Percentile Posted)
- < 0.2
- 0.2 - 0.25 (50th Percentile)
- 0.25 - 0.30 (75th Percentile)
- 0.30 - 0.35 (90th Percentile)
- 0.35 - 0.40 (95th Percentile)
- >0.40 (98th Percentile)

Soil Geochem Bi (ppm)
(Values >95th Percentile Posted)
- < 0.2
- 0.2 - 0.3 (50th Percentile)
- 0.3 - 0.4 (75th Percentile)
- 0.4 - 0.5 (90th Percentile)
- 0.5 - 0.7 (95th Percentile)
- > 0.7 (98th Percentile)

N

Limey Ridge

See Fig 15 & 17 for Geochem Detail

GOLDEN HINGE

GOLDEN RIDGE

See Fig 21 for Geochem Detail

NORTH STEEL AREA

Repeater Zone

West's Zone

Area 51

See Fig 20 for Geochem Detail

Colorado Resources Ltd.

ORO PROPERTY
2011 Soil & Silt Sample Results
Figure 14: Thallium

MacMillan Pass Area, Mayo Mining District, Yukon

1:20,000

0 500 1,000 1,500 2,000

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

N

Legend

- Oro Property

Silt Geochem Tl (ppm)
(Values >95th Percentile Posted)

- < 0.5
- 0.5 - 0.9 (50th Percentile)
- 0.9 - 1.2 (75th Percentile)
- 1.2 - 1.7 (90th Percentile)
- 1.7 - 2.5 (95th Percentile)
- >2.5 (98th Percentile)

Soil Geochem Tl (ppm)
(Values >95th Percentile Posted)

- <0.2
- 0.2 - 0.5 (50th Percentile)
- 0.5 - 1.1 (75th Percentile)
- 1.1 - 1.78 (90th Percentile)
- 1.8 - 3.25 (95th Percentile)
- >3.25 (98th Percentile)

Limey Ridge

See Fig 21 for Geochem Detail

GOLDEN HINGE

GOLDEN RIDGE

NORTH STEEL AREA

See Fig 21 for Geochem Detail

Repeater Zone

West's Zone

Area 51

See Fig 20 for Geochem Detail

Mine

Colorado Resources Ltd.

ORO PROPERTY
2011 Soil & Silt Sample Results
Figure 15: Zinc

MacMillan Pass Area, Mayo Mining District, Yukon

1:20,000

0 500 1,000 1,500 2,000

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

Legend

Oro Property

Silt Geochem Zn (ppm)
(Values >95th Percentile Posted)

- < 596
- 597 - 1252 (50th Percentile)
- 1253 - 2627 (75th Percentile)
- 2628 - 5887 (90th Percentile)
- 5888 - 10000 (95th Percentile)
- 10001 - 15001 (98th Percentile)

Soil Geochem Zn (ppm)
(Values >95th Percentile Posted)

- <132
- 132 - 229 (50th Percentile)
- 230 - 461 (75th Percentile)
- 462 - 793 (90th Percentile)
- 794 - 1463 (95th Percentile)
- >1463 (98th Percentile)

N

Limey Ridge

See Fig 17 for Geochem Detail

GOLDEN HINGE

GOLDEN RIDGE

See Fig 21 for Geochem Detail

NORTH STEEL AREA

Repeater Zone

West's Zone

Area 51

See Fig 20 for Geochem Detail

N

401000

402000

7021000

7020000

Canol Zone

J.O.-Saddle zone

Colorado Resources Ltd.

ORO PROPERTY

2011 Rock, Silt & Soil Sample Results
J.O.-Saddle and Canol Area
Fig 16: Au in Rock, Silt & Soil over Contoured As is Soil

MacMillan Pass Area, Mayo Mining District, Yukon

1:2,500

0 50 100 150 200 250

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

Legend

Oro Property

Rock Geochem FA Au (ppb)
(Values >95th Percentile Posted)
- < 3ppb
- 3 - 17 (50th Percentile)
- 17 - 99 (75th Percentile)
- 99 - 190 (90th Percentile)
- 190 - 338 (95th Percentile)
- > 338 ppb (98th Percentile)

Silt Geochem Au (ppb)
(Values >95th Percentile Posted)
- 0 - 3
- 4 - 5 (50th Percentile)
- 6 - 8 (75th Percentile)
- 9 - 12 (90th Percentile)
- 13 - 15 (95th Percentile)
- >15 (98th Percentile)

Soil Geochem Au (ppb)
(Values >95th Percentile Posted)
- 0 - 3
- 4 - 6 (50th Percentile)
- 7 - 12 (75th Percentile)
- 13 - 20 (90th Percentile)
- 21 - 43 (95th Percentile)
- >43 (98th Percentile)

Contoured As in Soil
- >285ppm (98th Percentile)
- >126ppm (95th Percentile)
- >77ppm (90th Percentile)
- >38ppm (75th Percentile)
- >21ppm (50th Percentile)

N

401000

402000

7021000

7020000

Colorado Resources Ltd.

ORO PROPERTY

2011 Rock, Silt & Soil Sample Results
J.O.-Saddle and Canol Area
Fig 17: Tellurium in Rock, Silt & Soil over Contoured Arsenic in Soil

MacMillan Pass Area, Mayo Mining District, Yukon

1:2,500

0 50 100 150 200 250

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-21

Legend

Oro Property

Rock Geochem Tl (ppm)

(Values >95th Percentile Posted)

- <0.07
- 0.07 - 0.21 (50th Percentile)
- 0.21 - 0.60 (75th Percentile)
- 0.6 - 1.195 (90th Percentile)
- 1.195 - 2.5 (95th Percentile)
- >2.5 (98th Percentile)

Silt Geochem Tl (ppm)

(Values >95th Percentile Posted)

- < 0.5
- 0.5 - 0.9 (50th Percentile)
- 0.9 - 1.2 (75th Percentile)
- 1.2 - 1.7 (90th Percentile)
- 1.7 - 2.5 (95th Percentile)
- >2.5 (98th Percentile)

Soil Geochem Tl (ppm)

(Values >95th Percentile Posted)

- <0.2
- 0.2 - 0.5 (50th Percentile)
- 0.5 - 1.1 (75th Percentile)
- 1.1 - 1.78 (90th Percentile)
- 1.8 - 3.25 (95th Percentile)
- >3.25 (98th Percentile)


Contoured As in Soil


- >285ppm (98th Percentile)
- >126ppm (95th Percentile)
- >77ppm (90th Percentile)
- >38ppm (75th Percentile)
- >21ppm (50th Percentile)

J.O.-Saddle Zone

Canol Zone


T2011-14 INSET MAP
T2011-14
T2011-15
T2011-07 INSET MAP
T2011-07
Repeater Zone
T2011-08
T2011-11
T2011-09
T2011-02
T2011-03
J.O. ZONE
T2011-10
T2011-01
T2011-04
SADDLE ZONE
T2011-13
T2011-05
T2011-12
T2011-06
CANOL ZONE
ORO
TRENCH LOCATION MAP
T2011-14 INSET
J.O. Zone
Saddle Zone
Canol Zone
T2011-07 INSET
Repeater Zone
1:10,000
0 130 260 520 780 1,040 Meters
Colorado Resources Ltd.
ORO PROPERTY
Fig 18: Trench Locations and Sample Numbers
MacMillan Pass Area, Mayo Mining District, Yukon
1:500
0 10 20 30 40 50
Meters
Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17
Legend
Rock Sample Location
Trench
Colorado Claims


Metcalfe 2011 Geological Mapping
Dyke Contacts - Simple
Type, Subtype, Confidence
Contact, faulted, inferred
Contact, intrusive, approximate
Contact, intrusive, defined
Contact, intrusive, inferred
Contacts/Faults (Metcalfe)
Subtype, Confidence
facies boundary, defined
facies boundary, approximate
quartzite bed, approximate
quartzite bed, defined
limestone bed, inferred
exposure, defined
facies boundary, inferred
faulted, approximate
faulted, defined
faulted, inferred
intrusive, defined
stratigraphic, defined
stratigraphic, approximate
stratigraphic, inferred
stratigraphic/diagenetic, inferred
thrust faulted, inferred
Geological Units (Metcalfe)
Dykes
Upper Devonian and Mississippian - Tsichu Grp
MCP - Canbou Pass Formation
MTss - Sandstone Facies
DMTSP - Squirrel Pass Member
DMTsh - Shale Facies
DMTch - Siliceous shale and carb chert
MTsh - Shale Facies?
MTq - Upper Quartzite Member
Upper Devonian
DI? - Earn Group - Unknown poss Itzi Frm
Middle (?) and Upper Devonian
DF - Portrait Lake Form; Fuller Lake Member
DF? - Unknown, possibly Fuller Lake
Du - Portrait Lake Form; Undivided
Middle Devonian
DMcg - Macmillan Pass Member; Conglom Facies
DMsh - Shale Facies
Lower and Middle Devonian
DN - Niddery Lake Member
Road River Group
SD RR - Road River Group
Upper Silurian
Ss - Road River Group - Sapper Formation
Upper Silurian to Middle Devonian
ODu - Road River Group Sapper/Steel
T2011-14 INSET MAP
T2011-14
T2011-07 INSET MAP
T2011-07
Repeater Zone
J.O. ZONE
T2011-06
T2011-03
T2011-02
T2011-09
T2011-01
T2011-04
T2011-13
T2011-05
T2011-10
SADDLE ZONE
T2011-12
T2011-08
CANOL ZONE
T2011-16
TRENCH LOCATION MAP
T2011-14 INSET
T2011-07 INSET
J.O. Zone
Saddle Zone
Canol Zone
Repeater Zone
1:10,000
0 125 250 500 750 1,000
Meters
Colorado Resources Ltd.
ORO PROPERTY
Fig 19A: Trench Samples - Au (by Fire Assay)
MacMillan Pass Area, Mayo Mining District, Yukon
1:500
0 10 20 30 40 50
Meters
Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17
Legend
Rock Geochem FA Au (ppb)
< 3ppb
3 - 17 (50th Percentile)
17 - 99 (75th Percentile)
99 - 190 (90th Percentile)
190 - 338 (95th Percentile)
> 338 ppb (98th Percentile)
Trench


Metcalfe 2011 Geological Mapping
Dyke Contacts - Simple
Type, Subtype, Confidence
Contact, faulted, inferred
Contact, intrusive, approximate
Contact, intrusive, defined
Contact, intrusive, inferred
Contacts/Faults (Metcalfe)
Subtype, Confidence
facies boundary, defined
facies boundary, approximate
quartzite bed, approximate
quartzite bed, defined
limestone bed, inferred
exposure, defined
facies boundary, inferred
faulted, approximate
faulted, defined
faulted, inferred
intrusive, defined
stratigraphic, defined
stratigraphic, approximate
stratigraphic, inferred
stratigraphic/diagenetic, inferred
thrust faulted, inferred
Geological Units (Metcalfe)
Dykes
Upper Devonian and Mississippian - Tsichu Grp
MCP - Caribou Pass Formation
MTss - Sandstone Facies
DMTSP - Squirrel Pass Member
DMTsh - Shale Facies
DMTch - Siliceous shale and carb chert
MTsh - Shale Facies?
MTq - Upper Quartzite Member
Upper Devonian
DF? - Earn Group - Unknown poss Itzi Frm
Middle (?) and Upper Devonian
DF - Portrait Lake Form; Fuller Lake Member
DF? - Unknown, possibly Fuller Lake
Du - Portrait Lake Form; Undivided
Middle Devonian
DMcg - Macmillan Pass Member; Conglom Facies
DMsh - Shale Facies
Lower and Middle Devonian
DN - Niddery Lake Member
Road River Group
SD RR - Road River Group
Upper Silurian
Sa - Road River Group - Sapper Formation
Upper Silurian to Middle Devonian
OOu - Road River Group Sapper/Steel
T2011-14 INSET MAP
T2011-14
T2011-07 INSET MAP
T2011-07
Repeater Zone
TRENCH LOCATION MAP
T2011-14 INSET
J.O. Zone
Saddle Zone
Canol Zone
T2011-07 INSET
Repeater Zone
1:10,000
0 135 270 540 810 1,080
Meters
J.O. ZONE
T2011-03
T2011-02
T2011-06
T2011-09
T2011-10
T2011-01
T2011-04
SADDLE ZONE
T2011-13
T2011-05
T2011-12
T2011-08
CANOL ZONE
T2011-16
Colorado Resources Ltd.
ORO PROPERTY
Fig 19B: Trench Samples - Arsenic
MacMillan Pass Area, Mayo Mining District, Yukon
1:500
Meters
Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17
Legend
Rock Geochem As (ppm)
< 22
23 - 90 (50th Percentile)
91 - 303 (75th Percentile)
304 - 505 (90th Percentile)
506 - 689 (95th Percentile)
>689 (98th Percentile)
Trench

N

414000

415000

416000

7013000

Colorado Resources Ltd.

ORO PROPERTY

2011 Rock, Silt & Soil Sample Results
AREA 51
Fig 20: Au in Rock, Silt & Soil over Contoured As in Soil

MacMillan Pass Area, Mayo Mining District, Yukon

1:2,500

0 50 100 150 200 250

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

Legend

Oro Property

Rock Geochem FA Au (ppb)

- < 3ppb
- 3 - 17 (50th Percentile)
- 17 - 99 (75th Percentile)
- 99 - 190 (90th Percentile)
- 190 - 338 (95th Percentile)
- > 338 ppb (98th Percentile)

Silt Geochem Au (ppb)

- 0 - 3
- 4 - 5 (50th Percentile)
- 6 - 8 (75th Percentile)
- 9 - 12 (90th Percentile)
- 13 - 15 (95th Percentile)
- >15 (98th Percentile)

Soil Geochem Au (ppb)

- 0 - 3
- 4 - 6 (50th Percentile)
- 7 - 12 (75th Percentile)
- 13 - 20 (90th Percentile)
- 21 - 43 (95th Percentile)
- >43 (98th Percentile)

Contoured As in Soil

- >285ppm (98th Percentile)
- >126ppm (95th Percentile)
- >77ppm (90th Percentile)
- >38ppm (75th Percentile)
- >21ppm (50th Percentile)

Colorado Resources Ltd.

ORO PROPERTY

2011 Rock, Silt & Soil Sample Results

Golden Hinge, Golden Ridge & North Steel Areas

Fig 21: Gold in Rock, Silt & Soil over Contoured Silver in Soil

MacMillan Pass Area, Mayo Mining District, Yukon

1:10,000

0 200 400 600 800 1,000

Meters

Mapsheet(s): 105O/02,03,06,07 Datum: NAD83 UTM Zone 9 Date: 2012-02-17

Legend

- Oro Property

Rock Geochem FA Au (ppb)

- < 3ppb
- 3 - 17 (50th Percentile)
- 17 - 99 (75th Percentile)
- 99 - 190 (90th Percentile)
- 190 - 338 (95th Percentile)
- > 338 ppb (98th Percentile)

Silt Geochem Au (ppb)

- 0 - 3
- 4 - 5 (50th Percentile)
- 6 - 8 (75th Percentile)
- 9 - 12 (90th Percentile)
- 13 - 15 (95th Percentile)
- >15 (98th Percentile)

Soil Geochem Au (ppb)

- 0 - 3
- 4 - 6 (50th Percentile)
- 7 - 12 (75th Percentile)
- 13 - 20 (90th Percentile)
- 21 - 43 (95th Percentile)
- >43 (98th Percentile)

Contoured Ag in Soil

- > 4.9ppm (98th Percentile)
- >3.2ppm (95th Percentile)
- >2.2ppm (90th Percentile)
- >1.2ppm (75th Percentile)
- >0.6ppm (50th Percentile)

GOLDEN RIDGE

GOLDEN HINGE

NORTH STEEL AREA

404000 405000 406000 407000 408000 409000 410000 411000 412000 413000 414000

7025000 7024000 7023000 7022000 7021000 7020000 7019000 7018000 7017000 7016000 7015000

Colorado Resources Ltd.

ORO PROPERTY

2011 AIRBORNE GEOPHYSICAL SURVEY

Fig 22: Survey Flight Lines

MacMillan Pass Area, Mayo Mining District, Yukon

1:25,000

0 500 1,000 1,500 2,000 2,500

Meters

Mapsheet(s):105O/02,03,06,07 Datum:NAD83 UTM Zone 9 Date:2012-02-18

Legend

- Oro Property
- Mining Road

Airborne Geophysical Survey

- Flight Paths

Limey Ridge

GOLDEN HINGE

GOLDEN RIDGE

NORTH STEEL AREA

Area 51

West's Zone

Repeater Zone

Main Zone

Mining Rd. (To Mac Pass)

Colorado Resources Ltd.

ORO PROPERTY
2011 AIRBORNE GEOPHYSICAL SURVEY
Fig 23: Total Magnetic Intensity (TMI) with 95th Percentile Au & Pathfinders

MacMillan Pass Area, Mayo Mining District, Yukon

1:25,000

0 400 800 1,600 2,400 3,200

Meters

Mapsheet(s):105O/02,03,06,07 Datum:NAD83 UTM Zone 9 Date:2012-02-18

Legend

- 2011 Grid Lines
- DrillPad
- Oro Property
- Mining Road

95th Percentile Au and Pathfinders in Soil

- 20ppb Au (95th Percentile)
- 3.2ppm Ag (95th Percentile)
- 125ppm As (95th Percentile)
- 2ppm Hg (95th Percentile)
- 23ppm Sb (95th Percentile)
- 1.78ppm Tl (95th Percentile)

Total Magnetic Intensity (TMI)

Value

High : 941

Low : -658

Limey Ridge

GOLDEN HINGE

GOLDEN RIDGE

NORTH STEEL AREA

Repeater Zone

West's Zone

Area 51

Mining Rd.

Mac Pass

REGIONAL FAULTS & CONTACTS

REGIONAL CONTACTS

INTRUSIVE
- defined

STRATIGRAPHIC
- defined
- approximate
- assumed

SURFICIAL
- approximate

REGIONAL FAULTS

NORMAL / REVERSE
- defined
- approximate
- extrapolated

THRUST UPRIGHT
- defined
- approximate
- extrapolated

MOVEMENT UNDEFINED
- defined

Colorado Resources Ltd.

ORO PROPERTY
2011 AIRBORNE GEOPHYSICAL SURVEY
Fig 24: Tilt Derivative with 95th Percentile Au & Pathfinders

MacMillan Pass Area, Mayo Mining District, Yukon

1:25,000

0 500 1,000 1,500 2,000 2,500

Meters

Mapsheet(s):105O/02,03,06,07 Datum:NAD83 UTM Zone 9 Date:2012-02-18

Legend

- Soil Sample
- Oro Property
- Mining Road

95th Percentile Au and Pathfinders in Soil

- 20ppb Au (95th Percentile)
- 3.2ppm Ag (95th Percentile)
- 125ppm As (95th Percentile)
- 2ppm Hg (95th Percentile)
- 23ppm Sb (95th Percentile)
- 1.78ppm Tl (95th Percentile)

Tilt Derivative

Value

High : 1.57

Low : -1.57

Limey Ridge

GOLDEN HINGE

GOLDEN RIDGE

NORTH STEEL AREA

Repeater Zone

West's Zone

Area 51

Mining Rd. (To Mac Pass)

REGIONAL FAULTS & CONTACTS

REGIONAL CONTACTS

INTRUSIVE
- defined

STRATIGRAPHIC
- defined
- approximate
- assumed

SURFICIAL
- approximate

REGIONAL FAULTS

NORMAL / REVERSE
- defined
- approximate
- extrapolated

THRUST UPRIGHT
- defined
- approximate
- extrapolated

MOVEMENT UNDEFINED
- defined

Colorado Resources Ltd.

ORO PROPERTY
2011 AIRBORNE GEOPHYSICAL SURVEY
Fig 25: Resistivity (56K)
with 95th Percentile Au & Pathfinders

MacMillan Pass Area, Mayo Mining District, Yukon

1:25,000

0 400 800 1,600 2,400 3,200

Meters

Mapsheet(s):105O/02,03,06,07 Datum:NAD83 UTM Zone 9 Date:2012-02-18

Legend

- Oro Property
- Mining Road

95th Percentile Au and Pathfinders in Soil

- 20ppb Au (95th Percentile)
- 3.2ppm Ag (95th Percentile)
- 125ppm As (95th Percentile)
- 2ppm Hg (95th Percentile)
- 23ppm Sb (95th Percentile)
- 1.78ppm Tl (95th Percentile)

Resistivity (56K)

Value

High : 55489

Low : 0

Limey Ridge

GOLDEN HINGE

GOLDEN RIDGE

NORTH STEEL AREA

ORO Saddle Zone

Repeater Zone

West's Zone

Area 51

Mining Rd.

Mac Pass

REGIONAL FAULTS & CONTACTS

REGIONAL CONTACTS

INTRUSIVE

- defined

STRATIGRAPHIC

- defined
- approximate
- assumed

SURFICIAL

- approximate

REGIONAL FAULTS

NORMAL / REVERSE

- defined
- approximate
- extrapolated

THRUST UPRIGHT

- defined
- approximate
- extrapolated

MOVEMENT UNDEFINED

- defined

Colorado Resources Ltd.

ORO PROPERTY
2011 AIRBORNE GEOPHYSICAL SURVEY
Fig 26: Resistivity (7200) with 95th Percentile Au & Pathfinders

MacMillan Pass Area, Mayo Mining District, Yukon

1:25,000

0 400 800 1,600 2,400 3,200
Meters

Mapsheet(s):105O/02,03,06,07 Datum:NAD83 UTM Zone 9 Date:2012-02-18

Legend

- Oro Property
- Mining Road

95th Percentile Au and Pathfinders in Soil

- 20ppb Au (95th Percentile)
- 3.2ppm Ag (95th Percentile)
- 125ppm As (95th Percentile)
- 2ppm Hg (95th Percentile)
- 23ppm Sb (95th Percentile)
- 1.78ppm Tl (95th Percentile)

Resistivity (7200)

Value

High : 10750

Low : 0

Limey Ridge

GOLDEN HINGE

GOLDEN RIDGE

NORTH STEEL AREA

Repeater Zone

West's Zone

Area 51

Mining Rd.

Mac Pass

REGIONAL FAULTS & CONTACTS

REGIONAL CONTACTS

INTRUSIVE

defined

STRATIGRAPHIC

defined
approximate
assumed

SURFICIAL

approximate

REGIONAL FAULTS

NORMAL / REVERSE

defined
approximate
extrapolated

THRUST UPRIGHT

defined
approximate
extrapolated

MOVEMENT UNDEFINED

defined

Colorado Resources Ltd.

ORO PROPERTY
2011 AIRBORNE GEOPHYSICAL SURVEY
Fig 27: Interpretation

MacMillan Pass Area, Mayo Mining District, Yukon

1:25,000

0 490 980 1,470 1,960 2,450 Meters

Mapsheet(s):105O/02,03,06,07 Datum:NAD83 UTM Zone 9 Date:2012-02-22

Legend
- Oro Property
- Mining Road

TECHNICAL SUMMARY

Navigation	Differentially-corrected GPS
Data reduction grid interval	40 metres
Terrain clearance	Magnetometer 60 m Electromagnetic sensor 35 m Magnetometer 35 m
Data sampling interval	0.1 second
Magnetometer / sensitivity	Cesium / 0.01 nT
Electromagnetic system	DIGHEM

Frequency	Sensitivity	Coil Orientation
1000 Hz	02 ppm	Vertical coaxial
5500 Hz	01 ppm	Horizontal coplanar
900 Hz	12 ppm	Horizontal coplanar
7200 Hz	24 ppm	Horizontal coplanar
56000 Hz	60 ppm	Horizontal coplanar

ELECTROMAGNETIC ANOMALIES

Grade	Anomaly	Conductance
7	●	>100 siemens
6	◕	50–100 siemens
5	◑	20–50 siemens
4	◔	10–20 siemens
3	⊕	5–10 siemens
2	○	1–5 siemens
1	○	< 1 siemens
~	✱	Questionable anomaly

Anomaly Identifier

Interpretive symbol

Interpretive symbol		Conductor mode:
	B	Bedrock conductor
	D	Narrow bedrock conductor ("thin dike")
	S	Conductive cover ("flat conductive sheet")
	H	Broad conductive rock unit, deep conductive weathering, thick conductive cover ("half-moded")
	C	Multi-layered conductor ("edge of half space")
□	L	Culture, e.g. power line, metal building or fence
△	M	Magnetite

FLIGHT LINES WITH EM ANOMALIES

Flight direction
Flight number
Flight line number
11200
Retight Number
Line Number
Area Number
Fiducials identified on profiles
Dip direction
EM anomaly (see EM legend)
Conductor axis (on EM maps only)
Area indicate the conductor has a thickness > 10m
Magnetic correlation: in nT

INTERPRETATION LEGEND

Inferred structure/ breck

M — Magnetic zone

R — Conductive zone

Source: Fugro Airborne Surveys, 2011, Report #11406 Project Report of the Airborne Geophysical Survey

Limey Ridge
GOLDEN HINGE
GOLDEN RIDGE
NORTH STEEL AREA
Repeater Zone
West's Zone
Area 51
Mining Road
To Mac Pass

PETROGRAPHIC REPORT

9 HAND SAMPLES

ORO PROJECT:
MACMILLAN PASS AREA, YUKON

February 3, 2012

Prepared for:
Adam Travis,President, CEO & Director
& Linda Dandy, P.Geo., Exploration Manager
Colorado Resources Ltd.
110- 2300 Carrington Road,
West Kelowna, BC
Canada V4T 2N6

Prepared by:
Kathryn Dunne, M.Sc. P.Geo.
Bag 9000, # 207
190B Trans Can Hwy NE
Salmon Arm, BC
Canada V1E 1S3

phone: 250-804-0729
kgeo@telus.net

Background

Nine hand samples were received from Paul Metcalfe & Dugald Dunlop on behalf of Colorado Resources Ltd. in October, 2011 for petrographic analysis. The samples were taken from the Oro property, Macmillan Pass area, Yukon. The goal of the work was basic transmitted and reflected light observations, including description of lithologies, alteration and mineralization. Nine polished thin sections were prepared from the samples at Vancouver Petrographics Ltd. Kathryn Dunne, P.Geo. carried out the petrographic analysis at her office in Salmon Arm, B.C. All percentages in the descriptions are approximate based on visual estimation.

Summary

Lithology

Sample #	Lithology	Page #
PM11-908	Microgranodiorite porphyry [garnet-bearing, quartz-biotite-plagioclase phyric]	4
PM11-913	Microgranodiorite porphyry [garnet-bearing, quartz-biotite-plagioclase phyric]	8
PM11-925	Leucocratic microtonalite	15
PM11-926	Leucocratic microtonalite	21
PM11-930	Microgranodiorite porphyry [garnet-bearing, quartz-biotite-plagioclase phyric]	27
PM11-930A	Microgranodiorite porphyry [garnet-bearing, quartz-biotite-plagioclase phyric]	33
PM11-935	Andesite porphyry [quartz-biotite-plagioclase phyric]	38
PM11-937A	Leucocratic microtonalite porphyry [muscovite-quartz-plagioclase phyric]	44
PM11-980	Microgranodiorite porphyry [garnet-bearing, quartz-biotite-plagioclase phyric]	49

The samples in this suite of rocks comprise a variety of hypabyssal intrusive rocks including:

- Microgranodiorite porphyry [garnet-bearing, quartz-biotite-plagioclase phyric]
  The microgranodiorite porphyry comprises weakly altered fine to medium-grained plagioclase phenocrysts ~40%, biotite phenocrysts ~7% and quartz phenocrysts from 3-10% in a fine-grained matrix comprising dominantly orthoclase and quartz with minor plagioclase and altered biotite. In one sample quartz phenocrysts are surrounded by granophyric texture. Traces of fine-grained garnet occur disseminated.
- Leucocratic microtonalite and microtonalite porphyry
  -The microtonalite comprises moderately altered fine to medium-grained plagioclase (formerly ~50%), quartz (~30%) and platy muscovite (~15%) with minor sulphides and trace to minor K-feldspar (origin uncertain).
  -The microtonalite porphyry comprises moderately altered fine to medium-grained altered plagioclase phenocrysts (formerly ~30%), quartz phenocrysts (~15%) and platy muscovite phenocrysts (~7%) in a fine-grained matrix dominated by plagioclase and quartz
- Andesite porphyry
  The andesite porphyry comprises strongly altered fine to medium-grained plagioclase phenocrysts and glomerocrysts ~30%, biotite phenocrysts ~10% and resorbed quartz phenocrysts ~7% in a very fine-grained strongly carbonate-sericite altered feldspathic matrix

Alteration

- **Sericite** occurs in minor to major (2-8%) amounts as selective replacement of plagioclase in microgranodiorite porphyry samples and in major (25%) amounts as selective replacement of plagioclase in andesite porphyry. **Muscovite/sericite** occurs in major amounts (~30-35%) extensively replacing plagioclase in leucocratic microtonalite and microtonalite porphyry. *Note: sericite is defined in this report as a general term for a fine-grained member of the mica group, usually muscovite, but may include paragonite or illite.

Alteration cont.


- **Carbonate** typically occurs in trace to minor amounts selectively replacing plagioclase in microgranodiorite porphyry and in major amounts (~25%) as replacement of plagioclase and biotite phenocrysts and matrix in andesite porphyry. Carbonate occurs in major amounts (~5-8%) in leucocratic microtonalite.
- **Chlorite** occurs in minor to major amounts (1-5%) partly replacing biotite in microgranodiorite porphyry samples
- Trace amounts of **Ti-ox** aggregate occur partly replacing biotite or muscovite in all samples.
- Major amounts of red-brown **Fe-ox** occur extensively replacing carbonate and partly replacing pyrite and marcasite aggregates in sample PM11-925. Trace amounts of Fe-ox occur rimming and replacing sulphides in sample PM11-930. Minor amounts of Fe-ox occur in sample PM11-980 as fracture and cavity infill, partly replacing pyrite and staining rock adjacent to fractures.
- Major to minor **pyrite** occurs dissseminated and associated with platy muscovite in microtonalite and microtonalite porphyry samples. Minor pyrite occurs disseminated, as patchy aggregates associated with carbonate alteration, partly replacing biotite phenocrysts and as vug infill in sample PM11-935.
- Traces of **K-feldspar** occur as very fine aggregates (origin uncertain) and may be be an early ?replacement of plagioclase in leucocratic microtonalite samples.

Mineralization


- **Pyrite** occurs in major amounts (up to 7%) to rarely in all the samples as disseminated grains, partly replacing platy biotite or muscovite and as patchy aggregates. In some samples pyrite is intergrown with marcasite.
- **Pyrrhotite** occurs in minor amounts (up to 3%) as disseminated grains and associated with biotite in sample PM11-913. Pyrrhotite occurs rarely disseminated and partly replaced by pyrite in sample PM11-935. Pyrrhotite occurs rarely disseminated in sample PM11-980.
- **Marcasite** occurs in trace to minor amounts (~1%) intergrown with pyrite in samples PM11-925 and 926.
- **Arsenopyrite** occurs rarely disseminated in samples PM11-913, 925 and 930.
- **Sphalerite** occurs disseminated in trace amounts in sample PM11-926.
- **Chalcopyrite** occurs disseminated in trace amounts in sample PM11-980 and as inclusions in pyrrhotite in sample PM11-913.



Sample: PM11-908 **Offcut #: AT-1**



Rock sample; scale in cm


Etched and stained section offcut; scale in mm

Hand Sample and Stained Offcut Description:
Porphyry with approximately 40% plagioclase phenocrysts (< 3 mm), 3% quartz phenocrysts (< 3 mm) and 7% black biotite phenocrysts (typically < 2 mm) in a very fine K-feldspar-quartz dominant matrix (based on stain). No reaction to magnet. No reaction to cold, dilute HCl. Positive test for K-feldspar using etching by HF and sodium cobaltinitrate (~25%, yellow) stain.

Sample: PM11-908 **Offcut #: AT-1**

LITHOLOGY: Microgranodiorite porphyry
[garnet-bearing, quartz-biotite-plagioclase-phyric]
ALTERATION MINERALS (> 1%): Sericite, chlorite, carbonate
ALTERATION MINERALS (< 1%): Ti-ox
INTENSITY OF ALTERATION: Weak
MINERALIZATION: (Pyrite)

Polished Thin Section Description:
This section is a weakly sericite-chlorite-carbonate-(Ti-ox)-altered, quartz-biotite-plagioclase-phyric microgranodiorite porphyry. The microgranodiorite porphyry comprises weakly altered fine to medium-grained plagioclase phenocrysts ~40%, biotite phenocrysts ~7% and minor quartz phenocrysts ~3% in a fine-grained matrix comprising dominantly orthoclase and quartz with minor plagioclase and altered biotite. Traces of fine-grained garnet occur disseminated. Rare apatite, zircon and ?monazite occur as accessory phases. Plagioclase is commonly zoned and partly replaced by sericite and patchy colourless carbonate. Biotite is partly replaced by chlorite and Ti-ox aggregate. Traces of ilmenite occur locally associated with biotite along cleavage traces. Rare very fine-grained subhedral pyrite occurs disseminated.


MAJOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Plagioclase, (oligoclase-andesine)	38	-fine to medium-grained (0.2-3 mm), phenocrysts, strongly zoned, composition of An_{27-40} (based on 4 estimates), variably partly replaced by sericite and carbonate -fine-grained (0.05-0.1 mm), occurs in matrix, partly replaced by sericite and carbonate	*polysynthetic twinning A/C*
Quartz	25	-medium-grained (0.5-2.5 mm), resorbed phenocrysts (~3%) -fine-grained (0.05-0.1 mm), anhedral, occurs intergrown with orthoclase as matrix	
Orthoclase	25	fine-grained (0.05-0.1 mm), cloudy aggregates, incipient clay alteration, intergrown with quartz and altered mafic phases as matrix	
Biotite	7	-fine to medium-grained (0.2-2 mm), phenocrysts, locally zoned, variably partly replaced by chlorite and Ti-ox aggregate -fine-grained (< 0.2 mm), occurs as matrix, partly replaced by chlorite and Ti-ox	*red-brown*


MINOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Sericite	2	very fine-grained, flaky aggregates, partly replaces plagioclase	
Carbonate	1	very fine-grained, occurs replacing plagioclase	
Chlorite	1	very fine-grained, occurs replacing biotite	
Ti-ox	tr	very fine-grained aggregate, partly replaces biotite	
Ilmenite	tr	fine to very fine-grained (< 0.1 mm), associated with biotite	
Garnet	tr	fine-grained (0.2 - 0.3 mm), occurs disseminated	*colourless*
Pyrite	r.	very fine-grained 25 µm), subhedral, disseminated	
Apatite	r.	very fine-grained (< 0.25 µm), disseminated	*high relief*
Zircon	r.	fine-grained (< 0.15 mm), rare anhedral grains	*high relief*
?Monazite	r.	fine-grained (~0.8 mm), anhedral grains, pale yellow	*high relief*

*size ranges: coarse-grained > 5mm; medium-grained 1-5mm; fine-grained 0.05-1mm; very fine-grained <0.05mm




A




B

Sample: PM11-908

A & B) Representative view microgranodiorite porphyry with prominent plagioclase and biotite phenocrysts. Note quartz phenocrysts absent in this FOV. A) PPL, B) XPL, FOV = ~ 4.5 mm.



C




D


Sample: PM11-08

C) Plagioclase phenocryst partly replaced by sericite and patchy carbonate. XPL, FOV = ~ 1.3 mm. D) Biotite phenocrysts partly replaced by chlorite and Ti-ox aggregate. PPL, FOV = ~ 1.3 mm.

Sample: PM11-913 **Offcut #: AT-2**



Rock sample; scale in cm



Etched and stained section offcut; scale in mm

Hand Sample and Stained Offcut Description:
Porphyry with approximately 40% plagioclase phenocrysts (< 3 mm), 3% quartz phenocrysts (< 3 mm) and 7% black biotite phenocrysts (typically < 2 mm) in a very fine K-feldspar-quartz dominant matrix (based on stain). No reaction to magnet. Trace local reaction to cold, dilute HCl. Positive test for K-feldspar using etching by HF and sodium cobaltinitrate (~25%, yellow) stain.

Sample: PM11-913 **Offcut #: AT-2**

LITHOLOGY:	Microgranodiorite porphyry [garnet-bearing, quartz-biotite-plagioclase-phyric]
ALTERATION MINERALS (> 1%):	Sericite, chlorite, (carbonate)
ALTERATION MINERALS (< 1%):	Ti-ox
INTENSITY OF ALTERATION:	Weak
MINERALIZATION:	Pyrrhotite, (pyrite, arsenopyrite)

Polished Thin Section Description:
This section is a weakly sericite-chlorite-(carbonate-Ti-ox)-altered, garnet-bearing, quartz-biotite-plagioclase-phyric microgranodiorite porphyry. The microgranodiorite porphyry comprises weakly altered fine to medium-grained plagioclase phenocrysts ~40%, biotite phenocrysts ~7% and minor quartz phenocrysts ~3% in a fine-grained matrix comprising dominantly orthoclase and quartz with minor plagioclase and altered biotite. A few quartz phenocrysts are surrounded by granophyric texture. Minor muscovite occurs as radiating aggregates with quartz and locally carbonate as infill of cavities (?miarolitic). Traces of fine-grained garnet occur disseminated. Rare apatite and ?monazite occur as accessory phases. Plagioclase is commonly zoned and partly replaced by sericite and patchy colourless carbonate. Biotite is partly replaced by chlorite, Ti-ox aggregate and locally sericite. Traces of ilmenite occur locally associated with biotite along cleavage traces. Minor pyrrhotite occurs disseminated and associated with biotite phenocrysts. Rare very fine-grained subhedral pyrite occurs disseminated. Rare euhedral ?arsenopyrite occurs disseminated and locally enclosed by pyrrhotite.

Sample: PM11-913 **Offcut #: AT-2**


MAJOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Plagioclase, (oligoclase-andesine)	36	-fine to medium-grained (0.2-2.4 mm), phenocrysts, strongly zoned, composition of An $_{25-42}$ (based on 3 estimates), variably partly replaced by sericite and carbonate -fine-grained (0.05-0.1 mm), occurs in matrix, partly replaced by sericite and carbonate	*polysynthetic twinning A/C*
Quartz	25	-medium-grained (0.5-2 mm), resorbed phenocrysts (~3%), locally granophyric texture developed as phenocryst rims -fine-grained (0.05-0.1 mm), anhedral, occurs intergrown with orthoclase as matrix -fine-grained (< 0.2 mm), occurs with muscovite and locally carbonate and pyrrhotite as cavity infill (?miarolitic)	
Orthoclase	25	fine-grained (0.05-0.1 mm), cloudy aggregates, incipient clay alteration, intergrown with quartz and altered mafic phases as matrix	


MINOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Biotite	4	-fine to medium-grained (0.2-3 mm), phenocrysts, locally zoned, partly replaced by chlorite, Ti-ox aggregate and locally sericite -fine-grained (< 0.2 mm), occurs as matrix, partly replaced by chlorite and Ti-ox aggregate	*red-brown*
Chlorite	3	very fine-grained, occurs partly replacing biotite	
Pyrrhotite	3	fine to very fine-grained (< 0.65 mm), anhedral grains and aggregate, rare inclusions of chalcopyrite, disseminated and associated with biotite	
Sericite	2	very fine-grained, flaky aggregates, partly replaces plagioclase, partly replaces biotite	
Muscovite	1	fine-grained (< 0.4 mm), locally radiating aggregates, occurs with quartz as infill of cavities (?miarolitic)	
Carbonate	tr	-very fine-grained, occurs replacing plagioclase -fine-grained (< 0.6 mm), occurs as cavity infill (?miarolitic)	
Garnet	tr	fine-grained (<0.6 - 1.1 mm), occurs disseminated	*colourless*
Ti-ox	tr	very fine-grained aggregate, partly replaces biotite	
Ilmenite	r.	very fine-grained, associated with biotite	
Pyrite	r.	very fine-grained (30 µm), subhedral, disseminated	
?Arsenopyrite	r.	very fine-grained (~25 µm), subhedral, disseminated	
Apatite	r.	fine to very fine-grained (< 0.35 mm), disseminated	*high relief*
?Monazite	r.	fine-grained (< 0.5 mm), anhedral grains, pale yellow	*high relief*

*size ranges: coarse-grained > 5mm; medium-grained 1-5mm; fine-grained 0.05-1mm; very fine-grained <0.05mm




A




B

Sample: PM11-913

A & B) Representative view microgranodiorite porphyry with altered plagioclase and biotite phenocrysts and resorbed quartz phenocrysts (lower right). A) PPL, B) XPL, FOV = ~ 4.5 mm.




C




D

Sample: PM11-913
C) Plagioclase partly replaced by sericite and patchy carbonate. XPL, FOV = ~ 0.7 mm. D) Disseminated ragged garnet. PPL, FOV = ~ 2.6 mm.




E



F

Sample: PM11-913


E) Granophyric texture surrounding resorbed quartz phenocryst. XPL, FOV = ~ 2.6 mm. F) Disseminated pyrrhotite and pyrite. RL, FOV = ~ 1.3 mm.



G

Sample: PM11-913
G) Disseminated pyrrhotite and ?arsenopyrite. RL, FOV = ~ 0.2 mm.

Sample: PM11-925 **Offcut #: AT-3**



Rock sample; scale in cm



Etched and stained section offcut; scale in mm

Hand Sample and Stained Offcut Description:
Brownish-grey medium-grained leucocratic equigranular rock with approximately 50% plagioclase (< 3 mm), 30% quartz (< 3 mm) and 15% platy muscovite (typically < 2 mm). No reaction to magnet. Trace local reaction to cold, dilute HCl. Mostly negative test for K-feldspar using etching by HF and sodium cobaltinitrate (trace yellow stain).

Sample: PM11-925 **Offcut #: AT-3**

LITHOLOGY:	Leucocratic microtonalite
ALTERATION MINERALS (> 1%):	Muscovite/sericite, pyrite, carbonate, Fe-ox
ALTERATION MINERALS (< 1%):	?K-feldspar, Ti-ox
INTENSITY OF ALTERATION:	Moderate
MINERALIZATION:	Pyrite, marcasite, (arsenopyrite)

Polished Thin Section Description:
This section is a moderately muscovite/sericite-carbonate-pyrite altered fine to medium-grained, seriate inequigranular leucocratic microtonalite that has undergone weathering resulting in major red-brown Fe-ox staining of the rock. The microtonalite comprises fine to medium-grained plagioclase (formerly ~50%), quartz (~30%) and platy muscovite (~15%). Rare apatite and zircon occur as accessory phases. Plagioclase is extensively replaced by muscovite/sericite and rhombic to anhedral Fe-bearing carbonate. The carbonate is partly replaced by red-brown Fe-ox aggregate. Traces of K-feldspar occur as very fine aggregates (origin uncertain) and may be be an early ?replacement of plagioclase (based on stained offcut). Platy muscovite is locally partly replaced along cleavage traces by Ti-ox aggregate and pyrite ± marcasite aggregate. Minor pyrite and marcasite occur intergrown and are locally partly rimmed and replaced by Fe-ox aggregate. Rare arsenopyrite occurs disseminated as diamond-shaped grains.

Sample: PM11-925 **Offcut #: AT-3**


MAJOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Muscovite (sericite)	30	very fine-grained, platy radiating and flaky aggregates, selectively replaces plagioclase	
Quartz	30	fine to medium-grained (0.2-1.6 mm), intergrown with plagioclase and muscovite	
Muscovite	15	fine to medium-grained (0.2 to 1.6 mm), platy, intergrown with quartz and plagioclase, partly replaced along cleavages by Ti-ox, pyrite-marcasite and Fe-ox aggregates	
Plagioclase	10	fine to medium-grained (0.4-2 mm), intergrown with muscovite and quartz, extensively replaced by muscovite (sericite) and carbonate	*polysynthetic twinning A/C*
Carbonate, (Fe-bearing)	5	fine to very fine-grained (< 0.6 mm), rhombic to anhedral aggregates, occurs replacing plagioclase, extensively replaced by Fe-ox aggregate	
Fe-ox	5	very fine-grained, extensively replaces carbonate, partly replaces pyrite and marcasite aggregates	*red-brown*


MINOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Pyrite	3	fine to very fine-grained (< ~0.5 mm), anhedral aggregates, intergrown with marcasite, fracture and replaced by Fe-ox	
Marcasite	1	very fine-grained, intergrown with pyrite, partly replaced by Fe-ox	
K-feldspar	tr	very fine-grained, cloudy aggregates, origin uncertain, possibly secondary ?replacement of plagioclase, overprinted by muscovite (sericite)	
Ti-ox	tr	very fine-grained aggregate, locally partly replaces muscovite	
Arsenopyrite	r.	fine to very fine-grained (< 0.1 mm), euhedral, disseminated	
Apatite	r.	very fine-grained, disseminated	*high relief*
Zircon	r.	fine-grained (~ 0.1 mm), disseminated	*high relief*

*size ranges: coarse-grained > 5mm; medium-grained 1-5mm; fine-grained 0.05-1mm; very fine-grained <0.05mm




A




B

Sample: PM11-925
A & B) Representative view of leucocratic microtonalite. Note carbonate (brown) extensively replaced by Fe-ox aggregate. A) PPL, B) XPL, FOV = ~ 4.5 mm.




C




D

Sample: PM11-925

C) Detailed view of plagioclase replaced by muscovite/sericite and patchy carbonate replaced by Fe-ox. XPL, FOV = ~ 1.3 mm. D) Patchy K-feldspar ?replacement of plagioclase (yellow in this view of stained offcut). RL, FOV = ~ 1.3 mm.



E




F


Sample: PM11-925

E) Patchy pyrite-marcasite aggregate. RL, FOV = ~ 2.6 mm. F) Disseminated arsenopyrite. RL, FOV = ~ 0.7 mm.

Sample: PM11-926 **Offcut #: AT-4**



Rock sample; scale in cm


Etched and stained section offcut; scale in mm

Hand Sample and Stained Offcut Description:
Medium-grey medium-grained leucocratic equigranular rock with approximately 50% plagioclase (< 4 mm), 40% quartz (< 3 mm) and 7% platy muscovite (typically < 2 mm). No reaction to magnet. No reaction to cold, dilute HCl. Positive test for K-feldspar using etching by HF and sodium cobaltinitrate (minor yellow stain - rims plagioclase).

Sample: PM11-926 **Offcut #: AT-4**

LITHOLOGY:	Leucocratic microtonalite
ALTERATION MINERALS (> 1%):	Muscovite/sericite, carbonate, pyrite ?K-feldspar
ALTERATION MINERALS (< 1%):	Ti-ox
INTENSITY OF ALTERATION:	Moderate
MINERALIZATION:	Pyrite, (marcasite, sphalerite)

Polished Thin Section Description:
This section is a moderately muscovite/sericite-carbonate-pyrite altered fine to medium-grained, seriate inequigranular leucocratic microtonalite. The microtonalite comprises fine to medium-grained plagioclase (formerly ~50%), quartz (~30%) and platy muscovite (~15%). Rare apatite and zircon occur as accessory phases. Traces of an unknown mineral and acicular rutile occur as infill of fine cavities. Plagioclase is extensively replaced by muscovite/sericite and anhedral carbonate. Minor of K-feldspar occur as very fine aggregates (origin uncertain) possibly an early ?replacement of plagioclase (based on stained offcut) and/or primary orthoclase replaced by carbonate. Platy muscovite is locally partly replaced along cleavage traces by Ti-ox aggregate and pyrite aggregate. Minor pyrite occur disseminated; locally with traces of marcasite. Rare dark sphalerite occurs disseminated.

Sample: PM11-926 **Offcut #: AT-4**


MAJOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Muscovite (sericite)	30	very fine-grained, platy radiating and flaky aggregates, selectively replaces plagioclase	
Quartz	30	fine to medium-grained (0.1-1.5 mm), intergrown with plagioclase and muscovite	
Muscovite	15	fine to medium-grained (0.2 to 2.6 mm), platy, intergrown with quartz and plagioclase, partly replaced along cleavages by Ti-ox & pyrite aggregates	
Plagioclase	10	fine to medium-grained (0.4-2 mm), intergrown with muscovite and quartz, extensively replaced by muscovite (sericite) and carbonate	*polysynthetic twinning A/C*
Carbonate	8	very fine to medium-grained (< 2 mm), anhedral aggregates, occurs replacing plagioclase and intergrown with quartz	*cloudy*


MINOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Pyrite	4	fine to very fine-grained (< ~0.3 mm), anhedral aggregates, locally intergrown with marcasite, pitted	
K-feldspar	2	very fine-grained, cloudy aggregates, origin uncertain, possibly secondary ?replacement of plagioclase, overprinted by muscovite (sericite), fine-grained, possibly primary ?intergrown with fine quartz and replaced by carbonate	
Marcasite	tr	very fine-grained, intergrown with pyrite	
Ti-ox	tr	very fine-grained aggregate, locally partly replaces muscovite	
Unknown	tr	very fine-grained, low relief, vug infill	*1st order δ*
Rutile	tr	fine-grained (< 0.2 mm), acicular, occurs with unknown as vug infill	
Sphalerite	tr	fine-grained (~0.2 mm), anhedral, chalcopyrite disease, disseminated	*dark*
Apatite	r.	very fine-grained, disseminated	*high relief*
Zircon	r.	fine-grained (< 0.15 mm), disseminated	*high relief*

*size ranges: coarse-grained > 5mm; medium-grained 1-5mm; fine-grained 0.05-1mm; very fine-grained <0.05mm




A




B

Sample: PM11-926
A & B) Representative view of leucocratic microtonalite. A) PPL, B) XPL, FOV = ~ 4.5 mm.




C




D

Sample: PM11-926

C) Detailed view of plagioclase replaced by muscovite/sericite and patchy carbonate. XPL, FOV = ~ 2.6 mm. D) Patchy K-feldspar ?replacement of plagioclase (yellow in this view of stained offcut). RL, FOV = ~ 1.3 mm.



E




F

Sample: PM11-926
E) Disseminated pyrite. RL, FOV = ~ 2.6 mm. F) Disseminated sphalerite associated with pyrite. RL, FOV = ~ 0.7 mm.

Sample: PM11-930 **Offcut #: AT-5**



Rock sample; scale in cm


Etched and stained section offcut; scale in mm

Hand Sample and Stained Offcut Description:
Porphyry with approximately 45% plagioclase phenocrysts (< 2 mm), 7% quartz phenocrysts (< 1 mm) and 7% black biotite phenocrysts (typically < 3 mm) in a very fine K-feldspar-quartz dominant matrix (based on stain). Note two autoliths (< 1 cm size) of more mafic composition than host rock. No reaction to magnet. No reaction to cold, dilute HCl. Positive test for K-feldspar using etching by HF and sodium cobaltinitrate (~20%, yellow) stain.

Sample: PM11-930 **Offcut #: AT-5**

LITHOLOGY:	Microgranodiorite porphyry [garnet-bearing, quartz-biotite-plagioclase-phyric]
ALTERATION MINERALS (> 1%):	Sericite, chlorite
ALTERATION MINERALS (< 1%):	Carbonate, Ti-ox, Fe-ox
INTENSITY OF ALTERATION:	Weak
MINERALIZATION:	(pyrite, arsenopyrite)

Polished Thin Section Description:
This section is a weakly sericite-chlorite-(carbonate-Ti-ox-Fe-ox)-altered, garnet-bearing, quartz-biotite-plagioclase-phyric microgranodiorite porphyry with former biotite-rich autolith (~1 cm size). The microgranodiorite porphyry comprises weakly altered fine to medium-grained plagioclase phenocrysts ~40%, biotite phenocrysts ~7% and quartz phenocrysts ~10% in a fine-grained matrix comprising dominantly orthoclase and quartz with minor plagioclase and altered biotite. Traces of muscovite occur as radiating aggregates with quartz and chlorite as infill of cavities (?miarolitic). Traces of fine-grained garnet occur disseminated. Rare apatite and zircon occur as accessory phases. Plagioclase is commonly zoned and selectively replaced by sericite and carbonate aggregate. Biotite is selectively replaced by chlorite, Ti-ox aggregate and locally sericite. Traces of pyrite and rare arsenopyrite occur disseminated. The autolith comprises a fine-grained equigranular aggregate of biotite, plagioclase, quartz and traces of K-feldspar and pyrite. The feldspars are partly replaced by rhombic carbonate and sericite aggregate. Biotite is replaced by chlorite, rutile and sericite aggregate.

Sample: PM11-930 **Offcut #: AT-5**


MAJOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Plagioclase	40	-fine to medium-grained (0.4-2 mm), phenocrysts, strongly zoned, selectively replaced by sericite and carbonate -fine-grained (0.05-0.4 mm), occurs in matrix, partly replaced by sericite	*polysynthetic twinning*
Quartz	26	-fine-grained (0.3-1 mm), resorbed phenocrysts (~10%) -fine-grained (0.05-0.1 mm), anhedral, occurs intergrown with orthoclase as matrix -fine-grained (< 0.2 mm), occurs as cavity infill (?mairolitic)	
Orthoclase	20	fine-grained (0.05-0.1 mm), cloudy aggregates, incipient clay alteration, intergrown with quartz and altered mafic phases as matrix	
Sericite	5	very fine to fine-grained (< 0.1 mm), flaky aggregates, partly replaces plagioclase, partly replaces biotite	
Chlorite	5	-very fine-grained, occurs selectively replacing biotite -fine-grained (< 0.2 mm), anhedral to radiating aggregates, occurs with muscovite and quartz as cavity infill	


MINOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Biotite	1	fine to medium-grained (0.2 to 2 mm), phenocrysts, extensively replaced by chlorite, Ti-ox and sericite	
Pyrite	tr	fine to very fine-grained (< 0.4 mm), subhedral, disseminated, occurs also within autolith, locally partly replaced by Fe-ox	
Garnet	tr	fine to medium-grained (0.6- 1.4 mm), occurs disseminated	*colourless*
Carbonate	tr	-fine-grained (< 0.4 mm), rhombic to anhedral aggregates, partly replaces plagioclase -fine-grained (< 0.8 mm) occurs as cavity infill	
Muscovite	tr	fine-grained (< 0.2 mm), radiating, cavity infill with quartz	
Ti-ox	tr	very fine-grained aggregate, partly replaces biotite	
Zircon	r.	fine-grained (< 0.15 mm), disseminated	*high relief*
Ilmenite	r.	fine to very fine-grained (< 0.1 mm), associated with biotite	
Fe-ox	r.	very fine-grained, rims and replaces sulphides	*red-brown*
Arsenopyrite	r.	very fine-grained, subhedral, partly replaced by Fe-ox	
Apatite	r.	very fine-grained, hexagonal forms, disseminated	*high relief*

*size ranges: coarse-grained > 5mm; medium-grained 1-5mm; fine-grained 0.05-1mm; very fine-grained <0.05mm



A




B

Sample: PM11-930
A & B) Representative view microgranodiorite porphyry with altered plagioclase and biotite phenocrysts and resorbed quartz phenocrysts. A) PPL, B) XPL, FOV = ~ 4.5 mm.




C



D

Sample: PM11-930
C & D) Representative view fine-grained biotite-rich autolith partly replaced by chlorite, sericite-rutile and rhombic carbonate. A) PPL, B) XPL, FOV = ~ 4.5 mm.




E




F

Sample: PM11-930
E) Disseminated ragged garnet. PPL, FOV = ~ 2.6 mm. F) Disseminated arsenopyrite and pyrite. RL, FOV = ~ 0.7 mm.

Sample: PM11-930A **Offcut #: AT-6**



Rock sample; scale in cm


Etched and stained section offcut; scale in mm

Hand Sample and Stained Offcut Description:
Porphyry with approximately 45% plagioclase phenocrysts (< 2 mm), 7% quartz phenocrysts (< 1 mm) and 7% black biotite phenocrysts (typically < 3 mm) in a very fine K-feldspar-quartz dominant matrix (based on stain). No reaction to magnet. No reaction to cold, dilute HCl. Positive test for K-feldspar using etching by HF and sodium cobaltinitrate (~20%, yellow) stain.

Sample: PM11-930A **Offcut #: AT-6**

LITHOLOGY: Microgranodiorite porphyry
[garnet-bearing, quartz-biotite-plagioclase-phyric]
ALTERATION MINERALS (> 1%): Sericite, chlorite
ALTERATION MINERALS (< 1%): Carbonate, Ti-ox
INTENSITY OF ALTERATION: Weak
MINERALIZATION: (pyrite)

Polished Thin Section Description:
This section is a weakly sericite-chlorite-(carbonate-Ti-ox)-altered, garnet-bearing, quartz-biotite-plagioclase-phyric microgranodiorite porphyry. The microgranodiorite porphyry comprises weakly altered fine to medium-grained plagioclase phenocrysts ~40%, biotite phenocrysts ~7% and quartz phenocrysts ~10% in a fine-grained matrix comprising dominantly orthoclase and quartz with minor plagioclase and altered biotite. Traces of chlorite occur as infill of cavities (?miarolitic). Rare fine-grained garnet occur disseminated. Rare apatite and zircon occur as accessory phases. Plagioclase is commonly zoned and selectively replaced by sericite and carbonate aggregate. Biotite is selectively replaced by chlorite, Ti-ox aggregate and locally sericite. Rare pyrite occurs disseminated.


MAJOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Plagioclase	40	-fine to medium-grained (0.2-3 mm), phenocrysts, strongly zoned, selectively replaced by sericite and carbonate -fine-grained (0.05-0.2 mm), occurs in matrix, partly replaced by sericite	*polysynthetic twinning*
Quartz	28	-fine to medium-grained (0.2-1.4 mm), resorbed phenocrysts (~10%) -fine-grained (0.05-0.1 mm), anhedral, occurs intergrown with orthoclase as matrix	
Orthoclase	20	fine-grained (0.05-0.1 mm), cloudy aggregates, incipient clay alteration, intergrown with quartz and altered mafic phases as matrix	
Sericite	5	very fine to fine-grained (< 0.1 mm), flaky aggregates, partly replaces plagioclase, partly replaces biotite	
Chlorite	5	-very fine-grained, occurs selectively replacing biotite -fine-grained (< 0.2 mm), anhedral to radiating aggregates, occurs as cavity infill	


MINOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Biotite	1	fine to medium-grained (0.2 to 2 mm), phenocrysts, extensively replaced by chlorite, Ti-ox and sericite	
Carbonate	tr	-fine-grained (< 0.4 mm), rhombic to anhedral aggregates, partly replaces plagioclase	
Ti-ox	tr	very fine-grained aggregate, partly replaces biotite	
Garnet	r.	fine-grained (~0.7 mm), occurs disseminated	*colourless*
Zircon	r.	fine-grained (< 0.15 mm), disseminated	*high relief*
Pyrite	r.	fine-grained (< 0.1 mm), euhedral, disseminated	
Apatite	r.	fine-grained (< 0.1 mm), acicular, disseminated	*high relief*

*size ranges: coarse-grained > 5mm; medium-grained 1-5mm; fine-grained 0.05-1mm; very fine-grained <0.05mm




A




B

Sample: PM11-930A

A & B) Representative view microgranodiorite porphyry with altered plagioclase and biotite phenocrysts and resorbed quartz phenocrysts. A) PPL, B) XPL, FOV = ~ 4.5 mm.




C



D


Sample: PM11-930A
C) Plagioclase partly replaced by sericite and patchy carbonate. XPL, FOV = ~ 1.3 mm. D) Disseminated ragged garnet. PPL, FOV = ~ 2.6 mm.




E

Sample: PM11-930A
E) Disseminated euhedral pyrite. RL, FOV = ~ 1.3 mm.

Sample: PM11-935 **Offcut #: AT-7**



Rock sample; scale in cm



Etched and stained section offcut; scale in mm

Hand Sample and Stained Offcut Description:
Porphyry with approximately 30% plagioclase phenocrysts (< 3 mm), 7% quartz phenocrysts (1-2 mm) and 10% platy phenocrysts (1- 3 mm) in a very fine K-feldspar-bearing matrix (based on stain). No reaction to magnet. No reaction to cold, dilute HCl. Positive test for K-feldspar using etching by HF and sodium cobaltinitrate (~10%, yellow) stain.

Sample: PM11-935 **Offcut #: AT-7**

LITHOLOGY:	Andesite porphyry [quartz-biotite-plagioclase-phyric]
ALTERATION MINERALS (> 1%):	Sericite, carbonate, pyrite, muscovite
ALTERATION MINERALS (< 1%):	Ti-ox
INTENSITY OF ALTERATION:	Moderate
MINERALIZATION:	Pyrite, (pyrrhotite)

Polished Thin Section Description:
This section is a moderately sericite-carbonate-pyrite-muscovite-(Ti-ox)-altered, quartz-biotite-plagioclase-phyric andesite porphyry. The andesite porphyry comprises strongle altered fine to medium-grained plagioclase phenocrysts and glomerocrysts ~30%, biotite phenocrysts ~10% and resorbed quartz phenocrysts ~7% in a very fine-grained strongly carbonate-sericite altered feldspathic matrix. Traces of quartz, carbonate, muscovite and pyrite occur as infill of cavities. Traces of apatite and rare zircon occur as accessory phases. Plagioclase phenocrysts are selectively replaced by very fine sericite and carbonate aggregate. Biotite is selectively replaced by carbonate, Ti-ox aggregate and muscovite. Minor pyrite occurs disseminated and locally pyrite replaces biotite along cleavages. One grain of fine pyrrhotite occurs in matrix and is rimmed and partly replaced by very fine pyrite aggregate.

Sample: PM11-935 **Offcut #: AT-7**


MAJOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Plagioclase	25	-fine to medium-grained (0.2-2.2 mm), phenocrysts and glomerocrysts (composition An_{27-55}, based on 3 estimates), selectively replaced by sericite and carbonate -very fine-grained, occurs as matrix, partly replaced by sericite and carbonate	*polysynthetic twinning*
Sericite	25	very fine-grained, flaky aggregates, partly replaces plagioclase phenocrysts and matrix, partly replaces biotite phenocrysts	
Carbonate	25	-very fine-grained, anhedral aggregates, partly replaces plagioclase and biotite phenocrysts, occurs as patchy aggregates in the matrix -fine-grained (< 0.1 mm), occurs as vug infill	
K-feldspar	10	very fine-grained occurs with plagioclase as matrix	
Quartz	7	-fine to medium-grained (0.1-2 mm), resorbed phenocrysts -very fine-grained, occurs as vug infill with carbonate, muscovite	


MINOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Pyrite	4	fine to very fine-grained (< 0.1 mm), eu-anhedral, occurs disseminated, as patchy aggregates associated with carbonate alteration, partly replacing biotite phenocrysts and as vug infill	
Biotite	2	fine to medium-grained (0.2 to 2.2 mm), phenocrysts, partly replaced by carbonate, Ti-ox and muscovite aggregate, locally pyrite replaces biotite along cleavages	
Muscovite	1	fine to very fine-grained (< 0.1 mm), occurs replacing biotite, occurs as radiating aggregates infilling cavities	
Apatite	tr	very fine-grained, hexagonal forms, disseminated	*high relief*
Ti-ox	tr	fine to very fine-grained aggregate, partly replaces biotite, locally associated with disseminated pyrite	
Pyrrhotite	r.	fine-grained (~0.3 mm), rimmed and partly replaced by very fine pyrite aggregate	
Zircon	r.	fine-grained (< 0.25 mm), disseminated	*high relief*

*size ranges: coarse-grained > 5mm; medium-grained 1-5mm; fine-grained 0.05-1mm; very fine-grained <0.05mm




A




B

Sample: PM11-935
A & B) Representative view of andesite porphyry with altered plagioclase and biotite phenocrysts and resorbed quartz phenocrysts. A) PPL, B) XPL, FOV = ~ 4.5 mm.




C




D

Sample: PM11-935

C) Biotite phenocryst partly replaced by rutile and muscovite. XPL, FOV = ~ 1.3 mm. D) Carbonate and sericite alteration of very fine matrix. XPL, FOV = ~ 0.7 mm.



E



F


Sample: PM11-935

E) Pyrite disseminated and partly replacing platy biotite phenocrysts. RL, FOV = ~ 2.6 mm. F) Pyrrhotite rimmed and partly replaced by very fine pyrite aggregate. RL, FOV = ~ 0.5 mm.

Sample: PM11-937A **Offcut #: AT-8**



Rock sample; scale in cm


Etched and stained section offcut; scale in mm

Hand Sample and Stained Offcut Description:
Light-grey medium-grained leucocratic equigranular rock with approximately ?30% altered plagioclase phenocrysts (< 4 mm), ?15% quartz phenocrysts (< 3 mm) and 3% platy muscovite phenocrysts (typically < 2 mm) in a fine-grained matrix. Major disseminated fine to medium-grained pyrite (~5%). No reaction to magnet. No reaction to cold, dilute HCl. Negative test for K-feldspar using etching by HF and sodium cobaltinitrate (no yellow stain).

Sample: PM11-937A **Offcut #: AT-8**

LITHOLOGY: Leucocratic microtonalite porphyry
ALTERATION MINERALS (> 1%): Muscovite/sericite, pyrite
ALTERATION MINERALS (< 1%): Ti-ox
INTENSITY OF ALTERATION: Moderate
MINERALIZATION: Pyrite

Polished Thin Section Description:
This section is a moderately muscovite/sericite-pyrite-altered fine to medium-grained, leucocratic microtonalite porphyry. The porphyry comprises fine to medium-grained plagioclase phenocrysts (formerly ~30%), quartz phenocrysts (~15%) and platy muscovite (~7%) in a fine-grained matrix dominated by plagioclase and quartz. Rare zircon occur as an accessory phase. Traces of an unknown mineral and acicular rutile occur as cavity infill. Resorbed quartz phenocrysts are surrounded by granophyric texture. Plagioclase is extensively replaced by muscovite/sericite. Platy muscovite is locally partly replaced along cleavage traces by Ti-ox aggregate and pyrite aggregate. Major pyrite occur disseminated.


MAJOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Muscovite (sericite)	35	very fine-grained, platy radiating and flaky aggregates, selectively replaces plagioclase	
Quartz	30	-fine to medium-grained (0.6-2 mm), resorbed phenocrysts, granophyric texture developed as rims -fine-grained (0.1-0.5 mm), occurs with plagioclase as matrix	
Plagioclase	20	-medium-grained (1.4-3 mm), occurs as phenocrysts, virtually completely replaced by muscovite (sericite) -fine-grained (0.1-0.6 mm), occurs with quartz as matrix, extensively replaced by muscovite (sericite) -granophyric texture developed as quartz phenocryst rims, virtually completely replaced by sericite	*polysynthetic twinning*
Pyrite	7	fine to very fine-grained (< 0.8 mm), eu-anhedral aggregates, disseminated and associated with platy muscovite	
Muscovite	7	fine to medium-grained (0.2 to 1.6 mm), platy, intergrown with quartz and plagioclase, partly replaced along cleavages by Ti-ox & pyrite aggregates	


MINOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Ti-ox	tr	very fine-grained aggregate, locally partly replaces muscovite	
Unknown	tr	very fine-grained, low relief, vug infill	*1st order δ*
Rutile	tr	fine-grained (< 0.2 mm), acicular, occurs with unknown as vug infill	
Zircon	r.	fine-grained (< 0.15 mm), disseminated	*high relief*

*size ranges: coarse-grained > 5mm; medium-grained 1-5mm; fine-grained 0.05-1mm; very fine-grained <0.05mm




A




B

Sample: PM11-937A

A & B) Representative view of leucocratic microtonalite porphyry with resorbed quartz phenocryst (right) and platy muscovite (left). A) PPL, B) XPL, FOV = ~ 4.5 mm.




C




D

Sample: PM11-937A

C) Detailed view of plagioclase phenocryst virtually completely replaced by muscovite/sericite. XPL, FOV = ~ 4.5 mm. D) Resorbed quartz phenocryst with granophyric texture as rim. XPL, FOV = ~ 2.6 mm.



E




F


Sample: PM11-937A

E) Cavity (centre) filled with unknown material (low birefringence) and acicular rutile. XPL, FOV = ~ 1.3 mm. F) Fine pyrite as replacement of platy muscovite and as disseminated grains. RL, FOV = ~ 2.6 mm.

Sample: PM11-980 **Offcut #: AT-9**



Rock sample; scale in cm



Etched and stained section offcut; scale in mm

Hand Sample and Stained Offcut Description:
Porphyry with approximately 40% plagioclase phenocrysts (< 2 mm), 5-7% quartz phenocrysts (< 3 mm) and 7% black biotite phenocrysts (typically < 2 mm) in a very fine K-feldspar-quartz dominant matrix (based on stain). No reaction to magnet. No reaction to cold, dilute HCl. Positive test for K-feldspar using etching by HF and sodium cobaltinitrate (~25%, yellow) stain. Fractures infilled by red-brown Fe-ox and adjacent rock is stained red-brown.

Sample: PM11-980 **Offcut #: AT-9**

LITHOLOGY:	Microgranodiorite porphyry [garnet-bearing, quartz-?biotite-plagioclase-phyric]
ALTERATION MINERALS (> 1%):	Sericite, chlorite, Fe-ox
ALTERATION MINERALS (< 1%):	Ti-ox
INTENSITY OF ALTERATION:	Weak
MINERALIZATION:	Pyrite, (chalcopyrite, pyrrhotite)

Polished Thin Section Description:
This section is a weakly sericite-chlorite-(Ti-ox)-altered, garnet-bearing, quartz-?biotite-plagioclase-phyric microgranodiorite porphyry that has undergone surface weathering resulting in minor red-brown Fe-ox infill of fractures and staining. The microgranodiorite porphyry comprises weakly altered fine to medium-grained plagioclase phenocrysts ~40%, former platy likely ?biotite phenocrysts ~7% and quartz phenocrysts ~7% in a fine-grained matrix comprising dominantly orthoclase and quartz with minor plagioclase and altered platy phases. Traces of muscovite occur as radiating aggregates with quartz and locally chlorite as infill of cavities (?miarolitic). Traces of fine-grained garnet occur disseminated. Rare apatite and ?monazite occur as accessory phases. Plagioclase is commonly zoned and selectively replaced by sericite aggregate. Former platy phases (likely ?biotite) are replaced by chlorite, Ti-ox aggregate and locally sericite. Minor pyrite and traces of chalcopyrite and pyrrhotite occur disseminated and associated with former platy phenocrysts.

Sample: PM11-980 **Offcut #: AT-9**


MAJOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Plagioclase	30	-fine to medium-grained (0.5-2 mm), phenocrysts, strongly zoned, selectively replaced by sericite -fine-grained (0.05-0.5 mm), occurs in matrix, partly replaced by sericite	*polysynthetic twinning*
Quartz	30	-medium-grained (0.4-3 mm), resorbed phenocrysts (~7%) -fine-grained (0.05-0.2 mm), anhedral, occurs intergrown with orthoclase as matrix -fine-grained (< 0.2 mm), occurs with muscovite and chlorite as cavity infill (?mairolitic)	
Orthoclase	25	fine-grained (0.05-0.2 mm), cloudy aggregates, incipient clay alteration, intergrown with quartz and altered mafic phases as matrix	
Sericite	8	very fine to fine-grained (< 0.1 mm), flaky aggregates, partly replaces plagioclase, partly replaces biotite	


MINOR MINERALS

Mineral	%	Distribution & Characteristics*	Optical
Chlorite	4	-very fine-grained, occurs selectively replacing former platy phenocryst (likely ?biotite); -fine-grained (< 0.2 mm), anhedral to radiating aggregates, occurs with muscovite and quartz as cavity infill	
Fe-ox	1	very fine-grained, occurs as fracture and cavity infill, stains adjacent rock, rims and replaces pyrite	*red-brown*
Pyrite	1	fine to very fine-grained (< 0.3 m), subhedral, disseminated, locally partly replaced by Fe-ox aggregate	
Garnet	tr	fine-grained (< 0.8 mm), occurs disseminated	*colourless*
Muscovite	tr	fine-grained (< 0.1 mm), radiating, cavity infill with quartz	
Ti-ox	tr	very fine-grained aggregate, partly replaces former platy phenocryst (likely ?biotite)	
Chalcopyrite	tr	fine to very fine-grained (< 0.1 mm), subhedral, disseminated	
Pyrrhotite	r.	fine to very fine-grained (< 0.1 mm), disseminated, partly replaced by Fe-ox aggregate	
Apatite	r.	fine-grained (< 0.4 mm), acicular, disseminated	*high relief*
?Monazite	r.	fine-grained (< 0.7 mm), anhedral grains, pale yellow	*high relief*

*size ranges: coarse-grained > 5mm; medium-grained 1-5mm; fine-grained 0.05-1mm; very fine-grained <0.05mm




A




B

Sample: PM11-980

A & B) Representative view microgranodiorite porphyry with altered plagioclase and former platy phenocrysts and resorbed quartz phenocrysts. A) PPL, B) XPL, FOV = ~ 4.5 mm.




C




D

Sample: PM11-980

C) Plagioclase phenocryst (left) selectively replaced by sericite; platy phenocryst (right) replaced by chlorite, sericite and Ti-ox aggregate. XPL, FOV = ~ 1.3 mm. D) Former platy ?biotite phenocryst (left) and disseminated ragged garnet (centre). PPL, FOV = ~ 2.6 mm.




E



F

Sample: PM11-980

E) Former irregular cavity (centre) with infill by muscovite, quartz, chlorite and Fe-ox aggregate. PPL, FOV = ~ 2.6 mm. F) Disseminated chalcopyrite and pyrite. RL, FOV = ~ 2.6 mm.



G

Sample: PM11-980
G) Disseminated pyrrhotite (po) and chalcopyrite (cp). RL, FOV = ~1.3 mm.

Statement of qualifications: Kathryn P.E. Dunne

I, Kathryn P.E. Dunne, of the city of Salmon Arm, province of British Columbia, do hereby certify that:

1. I am an independent consulting geologist, with a business office at 4610 Lakeshore Road NE, Salmon Arm, B.C., Canada. My business mailing address is: Bag 9000, # 207, 190B Trans Can Hwy NE, Salmon Arm, BC, V1E 1S3.

2. I am a graduate in geology, with a BSc in geology from The University of British Columbia (1985).

3. I received my Masters degree in geology from The University of British Columbia, Vancouver, B.C. in 1988.

4. I am a registered member of the Association of Professional Engineers and Geoscientists of the Province of British Columbia (No. 18674).

5. I am a fellow of the Geological Association of Canada and a member of the Society of Economic Geologists and Mineralogical Association of Canada

6. I have practiced my profession as a geologist for approximately 22 years: 4 years as geologist with the British Columbia Geological Survey Branch, 3 years as research coordinator at the Mineral Deposit Research Unit housed within the Department of Earth and Ocean Sciences at the University of British Columbia, and 15 years as an independent consultant.

7. The petrographic data of this report was collected by me in January and February 2012.

……..……

Kathryn P.E. Dunne, M.Sc., P.Geo.
Consulting Geologist
February 3, 2012

TrenchID	Sample	From_m	To_m	Comment	Au_FA_ppb	Ag_ppm	As_ppm	Sb_ppm	Zn_ppm
T2011-01	1092501	0	3	Scree orange weathering , clay alt'd felsite Alt'd. porphyry. Loose	89	1.8	514.3	112.8	85
T2011-01	1092502	3	6	Scree buff-orange weathering clay alt'd felsite; blocks 2-15 cm;	264	1.9	436.2	31.6	56
T2011-01	1092503	6	9	Scree - buff-brown clay alt'd felsite blocks to 15 cm depth 60 cm	100	1.7	353.8	24.6	33
T2011-01	1092504	9	12	Scree- buff felsite clay alt'd blocks to 15 cm depth 50 cm. old	99	1.7	407.2	24.7	16
T2011-01	1092505	12	15	Scree - buff clay alt'd felsite ppy. Blocks to 15 cm, depth 50 cm	60	2	642.5	15.9	8
T2011-01	1092506	15	18	Scree - same as above. 50 cm depth	44	1.6	405.7	11.4	13
T2011-01	1092507	18	21	Scree - same as above. 60 cm depth. More fine grained. Clay	44	1.7	390.2	9.9	11
T2011-01	1092508	21	24	Scree - same as above. 60 cm depth. More fine grained. Clay	58	1.5	317.3	11.7	34
T2011-01	1092509	24	27	Scree - fine buff-grey clay alt'd felsite porphyry with some shale	189	4.5	106	41.8	23
T2011-01	1092510	27	30	'C' Horizon. Buff and greenish grey clay and rock fragments. 60 c	173	3	108	33.5	30
T2011-01	1092511	30	33	Brown and grey, sand and clay. - Shale chips and felsite. 90 cm	111	3.1	175.4	30.6	25
T2011-01	1092512	33	36	same as above. 90 cm depth.	137	3.9	136.7	49.5	26
T2011-01	1092513	36	39	Brown and grey C horizon. 90 cm depth. 38-40m blocks of felsite	91	1.7	114.2	31.6	22
T2011-01	1092514	39	42	Same as above. "C" Horizon. Depth 90 cm. Blocks of felsite at	152	8.7	291.1	29.8	115
T2011-01	1092515	42	45	Brown-grey fill from old trench. Old trench ends ~ 42 m. 60 cm	612	2.5	395.8	31	170
T2011-01	1092516	45	48	fill from old trench. Brown-grey.	172	3.2	191.8	21.1	88
T2011-01	1092517	48	51	Broken felsite subarge. 49 m new trench.	138	2.5	354.3	23.1	215
T2011-01	1092518	48	51	Field dupl of 1092517; same as a above	64	1.6	361	13.7	267
T2011-01	1092519	51	54	felsite buff-orange. Broken outcrop. 50 cm depth	342	11	224.6	23.1	176
T2011-01	1092520	54	57	brown - buff orange felsite. Outcrop. Becoming broken up. 50	172	3.3	193.4	14.8	92
T2011-01	1092521	57	60	same as above. 50 cm depth.	249	2.4	201.9	16.7	69
T2011-01	1092522	60	63	Grey mud - overburden. Transported. Slumped in. 50 cm depth	28	1.2	178.2	3.7	103
T2011-01	1092523	63	66	Same as above. 60 cm slumped in	16	1.3	221	5.4	143
T2011-01	1092524	66	69	Same as above. 60 cm depth. Slumped in	60	2.1	286.4	15	82
T2011-01	1092525	69	72	Black Shale. Subcrop. 70 cm depth. Very loosely packed.	260	3.4	266.6	49.6	8
T2011-01	1092526	72	75	Same as above; 70 cm depth.	278	1.2	167.4	19.4	3
T2011-01	1092527	75	78	Same as above; 70 cm depth. Dip ~ 60*S	251	1.9	112.8	19.5	3
T2011-01	1092528	78	81	Same as above; 60 cm depth.	403	2.3	104.9	18.1	4
T2011-01	1092529	81	84	Blake shale subcrop. 70 cm depth. Dips ~ 60*S	268	1.4	72.6	13.4	3
T2011-01	1092530	84	87	same as above some minor FE OX on fracture	47	0.6	57.7	7.9	4
T2011-01	1092531	87	90	same as above some minor FE OX on fracture	17	0.3	34.9	3.7	4
T2011-01	1092532	90	93	same as above some minor FE OX on fracture	5	0.3	25	3.4	3
T2011-01	1092533	93	96	same as above some minor FE OX on fracture	1	0.3	5.7	2.3	2
T2011-01	1092534	96	99	same as above some minor FE OX on fracture	1	0.4	26.6	2.7	20
T2011-01	1092535	99	102	same as above some minor FE OX on fracture	1	0.4	13.5	2.6	8
T2011-01	1092536	102	105	same as above some minor FE OX on fracture	6	0.3	42.4	3.1	37
T2011-01	1092537	105	108	same as above some minor FE OX on fracture	4	0.2	32.6	1.6	80
T2011-01	1092538	108	111	Black shale dips ~60*S. sub crop. 70 cm depth	4	0.2	42.7	1.4	33
T2011-01	1092539	111	114	Black shale dips ~60*S. sub crop. 70 cm depth	8	0.2	38.9	1.6	28
T2011-01	1092540	114	117	Black shale dips ~60*S. sub crop. 70 cm depth	8	0.2	17.4	1.5	10
T2011-01	1092541	117	120	Black shale dips ~60*S. sub crop. 70 cm depth	6	0.2	23.2	1.8	19
T2011-01	1092542			Standard	1669	0.4	7.9	0.9	44
T2011-01	1092543			Blank - quartzite					
T2011-01	1092544	120	123		1	0	0	0	0
T2011-01	1092545	123	126		1	0	0	0	0
T2011-01	1092546	126	129		1	0	0	0	0
T2011-01	1092547	129	132		1	0	0	0	0
T2011-01	1092548	132	135						
T2011-01	1092549	135	138	Black shale, thinly bedded, stike N31E and dip 90 S, smectite on	1	4.3	55.7	8.8	76
T2011-01	1092550	138	141	Black shale and black and dark brown clay with shale	1	2.2	39.9	10.5	225
T2011-01	1092575	141	144	Black shale, and black clay, dipping south, blocky cleavage, 1" qtz	4	1.2	11.4	7	37
T2011-01	1092576	144	147	Black silicious shale, Black clay, qtz veinlets (5%), dippin to the	16	1.9	10.4	12	15
T2011-01	1092577	147	150	Black silicious shale, Black clay, with oxidized layer	6	4	42.6	21.7	12
T2011-01	1092578	150	153	Black silicious shale, black clay, dip 78 S, strike N31E, blocky	3	4.4	24	10.3	12
T2011-01	1092579	153	156	Black silicious shale, dipping South	4	5	47	19.9	78
T2011-01	1092580	156	159	Black silicious shale, dipping South	3	3.8	30.8	14.3	37

TrenchID	Sample	From_m	To_m	Comment	Au_FA_ppb	Ag_ppm	As_ppm	Sb_ppm	Zn_ppm
T2011-01	1092581	159	162	Black silicious shale, Black clay, blocky cleavage, dipping south, 2	17	3.8	21	6.6	13
T2011-01	1092582	162	165	Black silicious shale, blocky cleavage, dipping south 2 1/2 feet	1	3.8	20.5	6.6	24
T2011-01	1092583	165	168	Black silicious shale, blocky cleavage, dipping south 2 1/2 feet	1	3.4	11.6	3.5	7
T2011-01	1092584	168	171	Black clay, black shale with qtz veinlets and clast of qtz, dip S, 2	1	3.4	13.7	3.5	7
T2011-01	1092585	171	174	Black clay, black silicious shale, less clay moving north, gouge	3	2.5	15.4	2	13
T2011-01	1092586	174	177	Black clay, gouge and shale fragments 3 ft depth	13	1.4	15.3	1.4	28
T2011-01	1092587	177	180	Black silicious shale, black clay gouge?	9	1.2	13.7	1.1	7
T2011-01	1092588	180	183	black clay gouge with fragment of black shale, 3ft depth	16	1.6	6.4	1.2	6
T2011-01	1092589	183	186	black clay with black shale fragments, dip south	3	1.2	6.6	0.9	4
T2011-01	1092590	186	189	black clay with black shale fragments, dip south	6	1.2	11.1	0.9	8
T2011-02	1092551	0	3		383	1.7	324	7.7	58
T2011-02	1092552	3	6		434	1.7	299.3	8	67
T2011-02	1092553	6	9		643	2.4	479.8	11.7	54
T2011-02	1092554	9	12		780	2.7	668.7	18.2	134
T2011-02	1092555	12	15		802	2.6	504.1	15.9	39
T2011-02	1092556	15	18		765	2.5	563.7	16.3	59
T2011-02	1092557	18	21		477	2.3	204.1	11	22
T2011-02	1092558	21	24		407	2	210.2	7.6	25
T2011-02	1092559	24	27		253	1.5	272.8	6.2	31
T2011-02	1092560	27	30		216	1.5	288.9	4.2	65
T2011-02	1092561	30	33		124	1	228.7	2.6	92
T2011-02	1092562	33	36		71	0.7	213.4	2.1	138
T2011-03	1092565	0	3		279	0	0	0	0
T2011-03	1092566	3	6		88	0	0	0	0
T2011-03	1092567	6	9		27	0	0	0	0
T2011-03	1092568	9	12		96	0	0	0	0
T2011-03	1092569	12	15		35	0	0	0	0
T2011-04	1277151	150	153	Strongly oxidized and sericitic altered felsic intrusive with	121	5.8	238.1	45.1	63
T2011-04	1277152	153	156	orange clay with clast of strongly oxidized felsic intrusive, gouge	34	15.3	137.1	280.9	24
T2011-04	1277153	156	159	Strongly oxidized and sericitic altered intrusive, dipping south, 3	108	6.6	187.8	37.1	72
T2011-04	1277154	159	162	Strongly oxidized and sericitic altered intrusive, dipping south, 3	127	17.4	134.6	54	39
T2011-04	1277155	162	165	grey clay with 3-5 cm fragments of felsic intursive, gouge, 3 ft	343	6.3	197.5	23	31
T2011-04	1277156	165	168	strongly oxidized and altered felsic intrusive, into grey clay with	132	10.6	181.2	30	28
T2011-04	1277157	168	171	Black clay with strongly oxidized black shale fragments, dipping	68	1.4	254.7	10.6	70
T2011-04	1277158	171	174	Black clay with strongly oxidized black shale fragments, dipping	89	2.4	523.4	5.8	183
T2011-04	1277159	174	177	Black clay with 1-3 cm clast of black shale, gouge (fault?), 3 ft	8	0.4	280.3	2.3	137
T2011-04	1277160	177	180	Black clay with 1-3 cm clast of black shale, gouge, increase in	5	0.3	111.3	1.7	131
T2011-04	1277161	180	183	Black clay with 1-3 cm clast of black shale, gouge, increase in	3	0.5	88.7	2.1	92
T2011-04	1277162	183	186	Black clay, black shale, and oxdized qtz clast, 5 ft	5	0.5	115.5	2.5	115
T2011-04	1277163	186	189	black clay with clast of black shale, 5 ft depth	5	0.6	103.9	3.6	110
T2011-04	1277164	189	192	Brown-grey silty shale, with tissue-folding, 2ft depth	5	0.4	101.4	3.5	94
T2011-04	1277165	192	195	Brown-grey silty shale, with tissue-folding, 1 1/2ft depth	1	0.1	68.7	1.2	182
T2011-04	1277166	195	198	Brown-grey silty shale, with tissue-folding, 1 ft depth	7	0.1	47.3	1.4	103
T2011-04	1277167	198	201	Brown-grey silty shale, with tissue-folding, 1 ft depth	1	0.2	64.1	1.9	94
T2011-04	1277168	201	204	Brown/orange clay with fragments of brown-weathering thinly	1	0.2	83.7	2.4	107
T2011-04	1277169	204	207	Brown/orange clay with fragments of brown-weathering thinly	1	0.2	126.4	2.3	89
T2011-04	1277170	207	210	Brown-weathering, thinly bedded, silty shale, 1 ft depth	3	0.1	112.7	1.9	145
T2011-04	1277171	210	213	Brown-weathering, thinly bedded, silty shale, 1 ft depth, END OF	11	0.2	154	2	142
T2011-04	1277172	213	216	Brown-weathering silty shale	1	0.1	87.4	1.4	144
T2011-04	1277173	216	219	Brown-weathering silty shale	1	0.05	24.2	0.6	143
T2011-04	1277174	219	222	Brown-weathering silty shale	1	0.05	19.2	0.3	115
T2011-04	1277175	222	225	Brown-weathering silty shale	1	0.05	13.9	0.4	131
T2011-04	1277176	225	228	Brown-weathering silty shale	1	0.05	16.7	0.4	153
T2011-04	1277177	228	231	Brown-weathering silty shale	1	0.05	15.5	0.4	157
T2011-04	1277501	0	3	Brown clay, Black silty shale, 1 1/2 ft depth	10	0.2	3.1	0.2	11
T2011-04	1277502	3	6	Brown clay, Black silty shale, 1 1/2 ft depth	11	0.2	4.4	0.2	27

TrenchID	Sample	From_m	To_m	Comment	Au_FA_ppb	Ag_ppm	As_ppm	Sb_ppm	Zn_ppm
T2011-04	1277503	6	9	Brown clay, Black shale, Black clay, shale has blocky cleavage, no	20	0.3	4.5	0.5	11
T2011-04	1277504	9	12	Black silicious shale, Black clay with Brown weathering shale	78	0.8	14.4	1.5	14
T2011-04	1277505	12	15	Black silicious shale, Black clay with Brown weathering shale	20	0.5	10.4	0.8	31
T2011-04	1277506	15	18	Black silicious shale, broken, black clay, no subcrop, 2 ft depth	24	0.6	10.7	0.8	20
T2011-04	1277507	18	21	Black silicious shale, broken, black clay, no subcrop, 2 ft depth	15	0.3	12	0.5	117
T2011-04	1277508	21	24	Black silicious shale, broken, black clay, no subcrop, 2 ft depth	11	0.5	11.2	0.5	20
T2011-04	1277509	24	27	Black silicious shale, broken, black clay, no subcrop, 2 ft depth	9	0.8	25.8	0.7	6
T2011-04	1277510	27	30	Black silicious shale, broken, black clay, no subcrop, dipping	10	0.5	13.1	0.9	70
T2011-04	1277511	30	33	Black clay, broken black silicious shale with 30% qtz fragments,	14	3.1	8.6	2.3	6
T2011-04	1277512	33	36	Black shale, dip 90 S 2ft depth	9	2.7	22.5	3.7	34
T2011-04	1277513	36	39	Broken black silicious shale with black clay, no subcrop, 2 ft	5	2.7	16.6	2.2	11
T2011-04	1277514	39	42	Broken black silicious shale with black clay, no subcrop, 2 ft	11	3.6	23.9	4.3	24
T2011-04	1277515	42	45	Broken black silicious shale with black clay, no subcrop, 2 ft	34	2.9	67.3	7.9	29
T2011-04	1277516	45	48	Broken black silicious shale with black clay, no subcrop, 2 ft	61	4.3	85	13.6	26
T2011-04	1277517	48	51	Broken black silicious shale with black clay, no subcrop, 2 ft	50	3.9	39.6	8.3	8
T2011-04	1277518	51	54	Black silicious shale, dip 20 S, strike N20E	7	4.9	58.2	15.1	166
T2011-04	1277519	54	57	broken black silicious shale with 1mm sized qtz veins 2 1/2 ft	5	1.9	22	9.3	74
T2011-04	1277520	57	60	Black silicious shale with druzzy qtz on fracs, weak oxidized,	9	1.7	52.1	8	47
T2011-04	1277521	60	63	Black silicious shale dipping sub-vertically to the south, thinly	14	2.8	38.3	7.9	18
T2011-04	1277522	63	66	Black clay with black shale fragments, gouge (fault?)	11	3.1	31.2	5.6	93
T2011-04	1277523	66	69		5	1.6	69.4	4.6	520
T2011-04	1277524	69	72	Black thinly bedded shale, dipping south, broken, 2 ft depth	2	0.2	17.2	1.4	7
T2011-04	1277525	72	75	Black thinly bedded shale, dipping south, broken, weakly	1	0.1	3.9	0.9	4
T2011-04	1277526	75	78	Black thinly bedded shale, dipping south, broken, weakly	3	0.1	6.8	0.8	10
T2011-04	1277527	78	81	Black thinly bedded shale with interlayers of black clay and	3	0.1	25.1	2.6	19
T2011-04	1277528	81	84	Black thinly bedded broken shale, weakly oxidized, dipping	5	0.2	28.7	2.3	44
T2011-04	1277529	84	87	Black thinly bedded broken shale, weakly oxidized, dipping	6	0.2	18	2.2	21
T2011-04	1277530	87	90	Black thinly bedded broken shale, weakly oxidized, dipping	6	0.2	4.8	1.4	4
T2011-04	1277531	90	93	Black thinly bedded broken shale, weakly oxidized, dipping	2	0.2	3.9	1.1	3
T2011-04	1277532	93	96	Black thinly bedded broken shale, weakly oxidized, dipping	1	0.2	7.6	1.7	8
T2011-04	1277533	96	99	Black thinly bedded shale, moderately oxidized, 2 1/2 ft depth	1	0.2	10.5	2.5	22
T2011-04	1277534	99	102	Black thinly bedded shale, moderately oxidized, 2 1/2 ft depth	6	0.3	9.1	2.3	6
T2011-04	1277535	102	105	Black thinly bedded shale, weakly oxidized, 2 ft depth	10	0.4	22.4	3.6	8
T2011-04	1277536	105	108	Black thinly bedded shale, weakly oxidized, 2 ft depth	11	0.3	13.7	3.6	6
T2011-04	1277537	108	111	Black thinly bedded shale, weakly oxidized, 2 ft depth	9	0.3	10.5	2.9	3
T2011-04	1277538	111	114	Black thinly bedded shale, weakly oxidized, 2 ft depth	11	0.4	13.2	3.4	7
T2011-04	1277539	114	117	Black thinly bedded shale, weakly oxidized, 2 ft depth	11	0.3	11.5	2.8	6
T2011-04	1277540	117	120	Black thinly bedded shale, weakly oxidized, tissue folded, 2 ft	44	0.8	27.1	4	13
T2011-04	1277541	120	123	Black thinly bedded shale weakly oxidized, dipping slight to the	176	1.3	49.8	8.5	19
T2011-04	1277542	123	126	Black thinly bedded shale, intruded by strong sericitic altered	125	1.9	89.7	10.6	73
T2011-04	1277543	126	129	Black thinly bedded shale with fragements of felsic intrusive,	79	2	141.6	10.4	79
T2011-04	1277544	129	132	Felsic intrusive strongly oxidized and strong sericitic alteration, 1-	128	2.1	231.1	20.2	93
T2011-04	1277545	132	135	Strongly argillic altered black shale and moderately sericitic	21	1.7	138.2	11.2	165
T2011-04	1277546	135	138	Strongly argillic altered black shale and moderately sericitic	129	2.8	195.6	19.2	36
T2011-04	1277547	138	141	Strongly argillic altered black shale and moderately sericitic	103	2.1	308.8	32.7	47
T2011-04	1277548	141	144	Strongly oxidized and sericitic altered felsic intrusive with	72	2.5	562.3	25.8	169
T2011-04	1277549	144	147	Strongly oxidized and sericitic altered felsic intrusive with	85	5.6	555.5	38	214
T2011-04	1277550	147	150	Strongly oxdized and altered felsic intrusive overlaying black	65	3.4	356.3	22.2	180
T2011-05	1277178	0	3	Moderately oxidized and sericitic altered felsic intrusive, 1 ft	108	8.5	141.7	31.5	42
T2011-05	1277179	3	6	Black/grey clay with fragments of Black shale and Felsic intrusive,	113	2.5	234	7	105
T2011-05	1277180	6	9	Black/grey clay with brown-weathering shale, 2 ft depth	67	2.4	483.1	7.2	98
T2011-05	1277181	9	12	Black/grey clay with brown-weathering shale, 2 ft depth	4	0.3	164.9	2.4	142
T2011-05	1277182	12	15	Black/grey clay with brown-weathering shale, 2 ft depth	4	0.4	142.9	2.7	102
T2011-05	1277183	15	18	Black/grey clay with brown-weathering shale, 2 ft depth	15	2.1	296.8	5.4	103
T2011-05	1277184	18	21	Black/grey clay with brown-weathering shale, 2 ft depth	108	11.6	177	11.2	105
T2011-05	1277185	21	24	Brown-weathering thinly bedded, silty shale, black clay, orange	378	52	229.5	30.2	82

TrenchID	Sample	From_m	To_m	Comment	Au_FA_ppb	Ag_ppm	As_ppm	Sb_ppm	Zn_ppm
T2011-05	1277186	24	27	Brown-weathering thinly bedded, silty shale, black clay, orange	182	69.3	250.5	58.5	87
T2011-05	1277187	27	30	Brown-weathering thinly bedded, silty shale, black clay, orange	1277	100	451	254.1	93
T2011-05	1277188	30	33	Brown-weathering thinly bedded, silty shale, black clay, orange	1160	64.7	274.1	50.7	92
T2011-05	1277189	33	36	Brown-weathering thinly bedded, silty shale, black clay, orange	164	5.3	300.5	10.6	161
T2011-05	1277190	36	39	Brown-weathering thinly bedded, silty shale, black clay, orange	38	5.2	197.5	20.2	112
T2011-05	1277191	39	42	Brown-weathering thinly bedded silty shale, with tissue folding	481	3	206.3	5.3	160
T2011-05	1277192	42	45	Brown-weathering silty shale, brown, black, then grey clay,	55	2.3	408.2	17.9	82
T2011-05	1277193	45	48	Brown-weathering silty shale, brown, black, then grey clay,	57	1.2	333.8	7.2	83
T2011-05	1277194	48	51	Brown-weathering silty shale, brown, black, then orange clay	39	1.3	220.1	4.4	50
T2011-05	1277195	51	54	Brown-weathering silty shale, brown, black, then orange clay	26	1	303.3	1.5	59
T2011-05	1277196	54	57	Brown-weathering silty shale, brown, black, then orange clay	21	1.3	198.9	1.4	51
T2011-05	1277197	57	60	Brown clay, grey clay with fragments of shale, then black clay	22	0.3	330.6	1.3	102
T2011-05	1277198	60	63		4	0.05	165.5	1.3	128
T2011-05	1277199	63	66		33	0.05	145.1	1.1	160
T2011-05	1277200	66	69		9	0.05	146.9	1.1	206
T2011-05	1278301	69	72		1	0.05	76.7	1.4	154
T2011-05	1278302	72	75		2	0.1	92.3	1.4	147
T2011-05	1278303	75	78		3	0.05	91.6	1.2	191
T2011-05	1278304	78	81		5	0.1	85.9	1	136
T2011-05	1278305	81	84		6	0.1	113.6	1.3	163
T2011-05	1278306	84	87		1	0.05	51.7	0.9	210
T2011-05	1278307	87	90		2	0.05	47.3	0.9	164
T2011-05	1278308	90	93		3	0.1	107.3	1.1	110
T2011-05	1278309	93	96		2	0.1	65.7	0.8	104
T2011-05	1278310	96	99		1	0.1	170.2	0.7	209
T2011-05	1278311	99	102		4	0.05	65.4	0.2	234
T2011-05	1278312	102	105		1	0.05	40.8	0.3	204
T2011-05	1278313	105	108		1	0.05	52	0.4	270
T2011-05	1278314	108	111		2	0.05	28	0.1	233
T2011-05	1278315	111	114		2	0.05	33.2	0.2	222
T2011-05	1278316	114	117		4	0.05	60.2	0.3	215
T2011-05	1278317	117	120		3	0.05	35.3	0.3	169
T2011-05	1278318	120	123		1	0.05	24.7	0.2	295
T2011-05	1278319	123	126		1	0.05	52	0.2	183
T2011-05	1278320	126	129		1	0.05	21.4	0.2	143
T2011-05	1278321	129	132		1	0.05	20	0.2	195
T2011-05	1278322	132	135		1	0.05	20.7	0.2	237
T2011-05	1278323	135	138		2	0.05	22.1	0.2	267
T2011-05	1278324	138	141		1	0.05	28.2	0.2	262
T2011-05	1278325	141	144		1	0.05	25.2	0.2	196
T2011-05	1278326	144	147		1	0.05	27.7	0.2	240
T2011-05	1278327	147	150		1	0.05	34	0.3	190
T2011-05	1278328	150	153		1	0.05	32.3	0.2	164
T2011-05	1278329	153	156		1	0.05	28.7	0.2	155
T2011-05	1278330	156	159		1	0.05	40.7	0.3	269
T2011-05	1278331	159	162		1	0.1	33.8	0.3	234
T2011-06	1278351	0	3		107	0.7	126.2	3.6	27
T2011-06	1278352	3	6		69	0.9	57.8	5.6	10
T2011-06	1278353	6	9		154	1.3	186.8	9.4	57
T2011-06	1278354	9	12		276	1.1	273.2	16.1	81
T2011-06	1278355	12	15		531	1	268.2	11.6	112
T2011-06	1278356	15	18		233	0.7	135.9	5.9	60
T2011-06	1278357	18	21		198	0.8	122.1	5.9	57
T2011-06	1278358	21	24		134	0.7	155.3	7.9	167
T2011-06	1278359	24	27		41	0.3	72.9	4.4	55
T2011-06	1278360	27	30		67	0.6	145.7	8	88

TrenchID	Sample	From_m	To_m	Comment	Au_FA_ppb	Ag_ppm	As_ppm	Sb_ppm	Zn_ppm
T2011-07	1285401	0	3		1	0.05	53.6	0.7	14
T2011-07	1285402	3	6		1	0.05	12.7	0.7	33
T2011-07	1285403	6	9		1	0.05	30	1	50
T2011-07	1285404	9	12		2	0.05	36.9	1.3	72
T2011-07	1285405	12	15		2	0.1	34.8	2.4	25
T2011-07	1285406	15	18		1	0.05	45.4	1.7	25
T2011-07	1285407	18	21		3	0.5	125.3	8.2	80
T2011-07	1285408	21	24		3	0.3	192.6	3.1	83
T2011-07	1285409	24	27		1	0.2	194.2	2.2	97
T2011-07	1285410	27	30		3	0.4	257	3.7	289
T2011-07	1285411	30	33		1	0.2	167.4	2.5	1269
T2011-07	1285412	33	36		1	0.2	105.7	2.7	638
T2011-07	1285413	36	39		1	0.05	30.7	0.9	1694
T2011-07	1285414	39	42		1	0.2	93.6	1.5	3560
T2011-07	1285415	42	45		1	0.2	123.1	1.3	10000
T2011-07	1285416	45	48		1	0.1	16.7	0.4	66
T2011-07	1285417	48	51		1	0.1	51.5	0.8	37
T2011-07	1285418	51	54		1	0.1	108.2	1.1	57
T2011-07	1285419	54	57		1	0.2	230.2	2.1	39
T2011-07	1285420	57	60		1	0.2	214.7	2.6	37
T2011-07	1285421	60	63		3	0.2	183.2	2.3	38
T2011-07	1285422	63	66		1	0.2	248.4	2	37
T2011-07	1285423	66	69		1	0.1	164.5	1.6	35
T2011-07	1285424	69	72		1	0.05	85.8	1.3	36
T2011-07	1285425	72	75		3	0.05	103.4	1.1	53
T2011-07	1285426	75	78		1	0.1	37.2	0.9	55
T2011-07	1285427	78	81		1	0.1	26.5	0.6	64
T2011-07	1285428	81	84		1	0.2	13.2	0.8	200
T2011-07	1285429	84	87		1	0.2	6.8	0.7	241
T2011-07	1285430	87	90		1	0.1	5	0.4	33
T2011-07	1285431	90	93		1	0.2	37.4	0.6	150
T2011-07	1285432	93	96		4	0.2	95.4	3	108
T2011-07	1285433	96	99		3	0.4	61.8	3.3	255
T2011-07	1285434	99	102		4	0.5	63.7	6.8	248
T2011-07	1285435	102	105		9	0.4	54	6.5	224
T2011-08	1093806	125	125		3	0.7	28.8	5.4	98
T2011-08	1093807	192	193		10	0.9	66.9	6.6	384
T2011-08	1093808	193	194		19	0.2	28.3	1.6	6
T2011-08	1093809	194	195		28	1.4	90.1	11.6	124
T2011-08	1278332	0	3		3	0.05	120.2	2.5	98
T2011-08	1278333	3	6		1	0.1	134.1	2.7	99
T2011-08	1278334	6	9		3	0.1	95.6	2.6	84
T2011-08	1278335	9	12		1	1.3	57.3	5.3	79
T2011-08	1278336	12	15		6	3.2	80.4	9	96
T2011-08	1278337	15	18		14	2.8	225.1	12.6	785
T2011-08	1278338	18	21		10	2.3	71.2	9.2	124
T2011-08	1278339	21	24		9	1.9	80.5	8.9	132
T2011-08	1278340	24	27		33	3.2	43.9	6.4	24
T2011-08	1278341	27	30	Originally shipped and processed as 1278441	112	3.3	97.5	15.9	121
T2011-08	1278342	30	33	Originally shipped and processed as 1278442	112	3.1	128.4	16	659
T2011-08	1278343	33	36	Originally shipped and processed as 1278443	91	3.8	88.3	9.1	371
T2011-08	1278344	36	39	Originally shipped and processed as 1278444	62	4	53.1	7.2	106
T2011-08	1278345	39	42	Originally shipped and processed as 1278445	48	3.9	43.9	5.7	94
T2011-08	1278346	42	45	Originally shipped and processed as 1278446	127	3.6	49.5	6.7	116
T2011-08	1278347	45	48	Originally shipped and processed as 1278447	66	3	41.8	4.9	40
T2011-08	1278348	48	51	Originally shipped and processed as 1278448	54	3.7	47.3	6.3	51

TrenchID	Sample	From_m	To_m	Comment	Au_FA_ppb	Ag_ppm	As_ppm	Sb_ppm	Zn_ppm
T2011-08	1278349	51	54	Originally shipped and processed as 1278449	39	2.4	55.5	5.5	82
T2011-08	1278350	54	57	Originally shipped and processed as 1278450	16	0.9	96.2	4.2	207
T2011-08	1279151	57	60		5	0.1	137.2	2.7	427
T2011-08	1279152	60	63		10	0.2	115	3.7	262
T2011-08	1279153	63	66		7	0.2	123.6	3.8	279
T2011-08	1279154	66	69		6	0.3	100.7	4.2	342
T2011-08	1279155	69	72		5	0.2	57.9	2.8	363
T2011-08	1279156	72	75		4	0.1	51.2	1.5	454
T2011-08	1279157	75	78		3	0.1	39.8	1	282
T2011-08	1279158	78	81		2	0.05	49.3	1.1	267
T2011-08	1279159	81	84		2	0.05	32.7	1	210
T2011-08	1279160	84	87		3	0.05	39.1	1.3	278
T2011-08	1279161	87	90		3	0.1	37.2	1.5	262
T2011-08	1279162	90	93		6	0.05	32.8	1.1	275
T2011-08	1279163	93	96		4	0.05	69.1	1.1	243
T2011-08	1279164	96	99		4	0.05	43.2	1.4	191
T2011-08	1279165	99	102		25	0.2	73	5.6	148
T2011-08	1279166	102	105		36	0.4	82.2	7.3	139
T2011-08	1279167	105	108		35	0.2	85.7	5	276
T2011-08	1279168	108	111		28	0.4	79.7	5.4	197
T2011-08	1279169	111	114		29	0.5	51.5	3.9	104
T2011-08	1279170	114	117		9	2.3	51.1	3.5	59
T2011-08	1279171	117	120		13	2.3	59.2	8.7	124
T2011-08	1279172	120	123		13	2.9	53.6	9.5	122
T2011-08	1279173	123	126		10	2.1	38.7	5.9	94
T2011-08	1279174	126	129		18	2.6	53	8.5	189
T2011-08	1279175	129	132		11	2	55.8	5.3	98
T2011-08	1279176	132	135		18	1.4	38.1	3.6	54
T2011-08	1279177	135	138		22	2	60.7	5.8	79
T2011-08	1279178	138	141		19	1.5	40.6	3.3	61
T2011-08	1279179	141	144		31	1.7	54.3	5.5	74
T2011-08	1279180	144	147		47	2.1	67.1	10.7	134
T2011-08	1279181	147	150		7	2.8	94.6	16.2	146
T2011-08	1279182	150	153		13	2	99.8	16.7	65
T2011-08	1279183	153	156		21	0.8	39	5.9	6
T2011-08	1279184	156	159		15	0.6	22	6.3	3
T2011-08	1279185	159	162		9	0.5	21.4	7	3
T2011-08	1279186	162	165		6	0.6	20.2	9.3	4
T2011-08	1279187	165	168		4	1	35.4	13.2	4
T2011-08	1279188	168	171		4	1.3	26.4	14.9	8
T2011-08	1279189	171	174		4	1	19.8	12.4	4
T2011-08	1279190	174	177		19	1.1	36.4	13.7	6
T2011-08	1279191	177	180		19	1.4	37.3	12.8	10
T2011-08	1279192	180	183		18	1.2	30	10.8	6
T2011-08	1279193	183	186		11	0.9	28.6	10.6	5
T2011-08	1279194	186	189		14	1.1	48.2	10.8	17
T2011-08	1279195	189	192		11	1.1	40.1	10.2	17
T2011-08	1279196	192	195		14	0.8	33	8.8	15
T2011-08	1279197	195	198		10	0.9	29.4	9.3	15
T2011-08	1279198	198	201		15	0.7	57.4	6.9	102
T2011-08	1279199	201	204		2	0.4	23	4.5	48
T2011-08	1279200	204	207		1	0.4	96.3	8.6	360
T2011-08	1279201	207	210	Returned from the lab as Silt - Susie checking					
T2011-08	1279202	210	213	Returned from the lab as Silt - Susie checking					
T2011-08	1279203	213	216		3	0.5	44.8	3.7	6
T2011-09	1279207	0	3		42	0.7	221.3	3.2	61

TrenchID	Sample	From_m	To_m	Comment	Au_FA_ppb	Ag_ppm	As_ppm	Sb_ppm	Zn_ppm
T2011-09	1279208	3	6		130	1.4	374.9	11.2	42
T2011-09	1279209	6	9		77	1.2	410.8	10.2	41
T2011-09	1279210	9	12		164	1.2	619	28.8	52
T2011-09	1279211	12	15		124	1.5	491.4	4.5	67
T2011-09	1279212	15	18		151	1.7	584.9	4.4	82
T2011-09	1279213	18	21		76	1.4	273.8	2.8	103
T2011-09	1279214	21	24		78	1.3	218.2	2.1	71
T2011-09	1279215	24	27		82	1.6	219.7	2.6	90
T2011-09	1279216	27	30		85	1.6	301.7	9.7	131
T2011-09	1279217	30	33		67	1.4	197.6	6.2	84
T2011-09	1279218	33	36		38	0.6	229.5	2.8	75
T2011-09	1279219	36	39		58	0.6	162.7	3.7	77
T2011-09	1279220	39	42		138	0.9	279	4.4	109
T2011-09	1279221	42	45		151	1.1	516.5	5	144
T2011-09	1279222	45	48		60	0.8	416.2	4.7	127
T2011-09	1279223	48	51		116	0.6	307	4.7	167
T2011-09	1279224	51	54		397	0.6	324.7	1.9	103
T2011-09	1279225	54	57		279	0.6	368.5	1.9	137
T2011-09	1279226	57	60		232	0.5	434.5	2.1	90
T2011-09	1279227	60	63		199	0.7	489.5	7.9	134
T2011-09	1279228	63	66		272	0.8	626.8	14.9	106
T2011-09	1279229	66	69		265	0.9	671	17.9	125
T2011-10	1278361	60	63		99	0.9	631.1	18.9	72
T2011-10	1278362	63	66		43	0.9	689.7	9.6	103
T2011-10	1278363	66	69		90	1	967.1	4.3	97
T2011-10	1278364	69	72		41	0.8	607.8	4.6	168
T2011-10	1278365	72	75		246	0.8	690.5	7.3	64
T2011-10	1278366	75	78		13	0.5	608.8	4.8	132
T2011-10	1278367	78	81		17	0.5	424.1	6.2	153
T2011-10	1278368	81	84		148	1.4	857.1	2.9	63
T2011-10	1278369	84	87		24	0.9	411.5	3.4	100
T2011-10	1278370	87	90		372	1.3	791.5	3.7	127
T2011-10	1278371	90	93		11	0.7	369.8	4.8	109
T2011-10	1278372	93	96		7	0.6	303	4.3	129
T2011-10	1278373	96	99		11	0.9	365.1	3.8	111
T2011-10	1278374	99	102		8	0.6	248.5	3.4	86
T2011-10	1278375	102	105		9	0.3	138.5	2.7	77
T2011-10	1278376	105	108		6	0.3	163.2	3.2	93
T2011-10	1278377	108	111		24	0.5	259.2	2.8	153
T2011-10	1278378	111	114		8	0.7	314.3	3.4	134
T2011-10	1278379	114	117		171	0.9	369.7	4	110
T2011-10	1278380	117	120		13	0.9	178.4	2.4	118
T2011-10	1278381	120	123		2	0.05	120.3	1.2	112
T2011-10	1278382	123	126		5	0.1	102.8	3.3	107
T2011-10	1278383	126	129		4	0.1	115.1	2.9	95
T2011-10	1278384	129	132		6	0.2	109.1	3.1	86
T2011-10	1278385	132	135		8	0.2	137.3	3.6	96
T2011-10	1279231	0	3		169	0.7	547.2	8.2	76
T2011-10	1279232	3	6		135	1.3	538.3	5.7	65
T2011-10	1279233	6	9		98	1.7	406.7	4.6	37
T2011-10	1279234	9	12		153	1.4	1223.4	7.1	59
T2011-10	1279235	12	15		111	0.9	711.6	3.9	68
T2011-10	1279236	15	18		136	0.7	372	2.4	44
T2011-10	1279237	18	21		278	0.9	581.5	6.7	40
T2011-10	1279238	21	24		656	2.4	385.8	37	34
T2011-10	1279239	24	27		195	1.5	1078.9	11.1	115

TrenchID	Sample	From_m	To_m	Comment	Au_FA_ppb	Ag_ppm	As_ppm	Sb_ppm	Zn_ppm
T2011-10	1279240	27	30		39	1.3	539.6	2.7	49
T2011-10	1279241	30	33		27	1.9	1119.4	8.2	43
T2011-10	1279242	33	36		40	1.6	530	5.3	31
T2011-10	1279243	36	39		30	1	441	6.9	66
T2011-10	1279244	39	42		23	1.1	658.4	4.6	22
T2011-10	1279245	42	45		19	1.2	505	3.4	28
T2011-10	1279246	45	48		41	1	440.5	3.6	33
T2011-10	1279247	48	51		64	1.5	654.5	13.8	24
T2011-10	1279248	51	54		145	1.2	571.3	14.7	56
T2011-10	1279249	54	57		338	1.9	215.1	69.1	29
T2011-10	1279250	57	60		354	1.5	251.1	31	56
T2011-11	1278391	0	3		92	1.1	114.6	8.8	21
T2011-11	1278392	3	6		254	1.3	481.5	12.2	54
T2011-11	1278393	6	9		209	1.2	234.8	10.6	67
T2011-11	1278394	9	12		195	2.3	251.8	17.4	96
T2011-11	1278395	12	15		103	1.6	181.6	13.2	70
T2011-11	1278396	15	18		73	1.7	137.4	7.2	129
T2011-11	1278397	18	21		101	1.3	161.5	6.3	116
T2011-11	1278398	21	24		132	0.9	221.6	14.1	33
T2011-11	1278399	24	27		549	2.4	324.2	30.2	50
T2011-11	1278400	27	30		1147	3	177.9	41	20
T2011-12	1285051	0	3		167	0.6	122.9	13.6	2
T2011-12	1285052	3	6		76	0.7	38.5	6.8	2
T2011-12	1285053	6	9		20	0.4	40.8	4.6	2
T2011-12	1285054	9	12		20	0.4	27.8	4.9	2
T2011-12	1285055	12	15		35	0.7	35.4	6.5	2
T2011-12	1285056	15	18		45	0.8	36.7	6.5	3
T2011-12	1285057	18	21		21	0.4	25.3	4.5	3
T2011-12	1285058	21	24		31	0.6	48.2	6.6	29
T2011-12	1285059	24	27		39	0.7	131.6	5.3	57
T2011-12	1285060	27	30		27	0.9	73.3	5.7	23
T2011-12	1285061	30	33		28	0.5	280.8	6.3	221
T2011-12	1285062	33	36		38	0.8	71.2	5.7	3
T2011-12	1285063	36	39		64	0.9	341.2	9	92
T2011-12	1285064	39	42		24	0.3	138.4	6.1	62
T2011-12	1285065	42	45		10	0.5	268.6	8.1	389
T2011-12	1285066	45	48		107	1	196	10.1	8
T2011-12	1285067	48	51		223	1.8	926.9	39.9	1464
T2011-12	1285068	51	54		24	1.2	187.4	19.8	2
T2011-12	1285069	54	57		4	1.4	135.5	21.4	4
T2011-13	1285151	0	3		4	2	97	13.5	760
T2011-13	1285152	3	6		3	0.3	3.7	1.6	4
T2011-13	1285153	6	9		1	0.1	3.4	1.4	2
T2011-13	1285154	9	12		3	0.1	3.5	0.9	2
T2011-13	1285155	12	15		2	0.1	21.4	2.5	3
T2011-13	1285156	15	18		1	0.05	10.9	2.2	2
T2011-13	1285157	18	21		4	0.05	12.8	2.7	2
T2011-13	1285158	21	24		4	0.2	5.6	1.4	2
T2011-13	1285159	24	27		5	0.3	19.1	3.6	6
T2011-13	1285160	27	30		4	0.3	12.3	3.8	5
T2011-13	1285161	30	33		4	0.3	8.9	2.8	1
T2011-13	1285162	33	36		8	0.4	12.2	1.9	3
T2011-13	1285163	36	39		11	0.3	9.1	3.7	3
T2011-13	1285164	39	42		12	0.3	29.7	8.8	6
T2011-13	1285165	42	45		9	0.5	28.9	4.3	3
T2011-13	1285166	45	48		86	2.1	58.1	7.8	15

TrenchID	Sample	From_m	To_m	Comment	Au_FA_ppb	Ag_ppm	As_ppm	Sb_ppm	Zn_ppm
T2011-13	1285167	48	51		11	2.7	54.7	6.6	80
T2011-13	1285168	51	54		19	1.6	59.3	3.8	63
T2011-13	1285169	54	57		4	0.8	135.1	3.5	155
T2011-13	1285170	57	60		6	0.7	139.9	1.9	164
T2011-13	1285171	60	63		7	0.5	61.1	1	64
T2011-13	1285172	63	66		20	1.3	133.7	2.2	51
T2011-13	1285173	66	69		91	3.3	142.6	13.7	64
T2011-13	1285174	69	72		190	1.8	256	12.7	53
T2011-13	1285175	72	75		669	9.8	218.4	13.6	18
T2011-13	1285176	75	78		301	9	195.1	9.1	91
T2011-13	1285177	78	81		15	1.7	60.3	2.7	216
T2011-13	1285178	81	84		9	4.6	144.3	4.4	219
T2011-13	1285179	84	87		11	1.1	53	0.7	153
T2011-13	1285180	87	90		6	0.2	141.7	1.3	120
T2011-13	1285181	90	93		11	0.2	129.8	2.6	87
T2011-13	1285182	93	96		65	0.5	139.9	3.1	166
T2011-13	1285183	96	99		22	0.3	181.9	1.7	128
T2011-13	1285184	99	102		10	0.1	102.2	1.4	181
T2011-13	1285185	102	105		1	0.05	49.4	0.9	236
T2011-13	1285186	105	108		6	0.1	129.1	1.5	184
T2011-13	1285187	108	111		7	0.2	191.2	4.4	105
T2011-13	1285188	111	114		11	0.3	293.9	6.5	158
T2011-13	1285189	114	117		8	0.3	189.3	5.3	113
T2011-13	1285190	117	120		9	0.2	147.8	4.1	93
T2011-13	1285191	117	120	Field duplicate of 1285190	8	0.2	143.7	4.1	93
T2011-14	1285070	0	3		2	0.7	12.1	0.6	186
T2011-14	1285071	3	6		14	1.7	10.9	1	207
T2011-14	1285072	6	9		15	1.2	8.9	0.8	201
T2011-14	1285073	9	12		5	0.4	6.2	0.3	107
T2011-14	1285074	12	15		16	0.7	11.4	0.6	154
T2011-14	1285075	15	18		4	0.4	8	0.3	115
T2011-14	1285076	18	21		4	0.5	11.1	0.3	137
T2011-14	1285077	21	24		3	0.3	11.5	0.2	137
T2011-14	1285078	24	27		3	0.2	11.1	0.2	140
T2011-14	1285079	27	30		3	0.2	9.8	0.6	112
T2011-14	1285080	30	33		3	0.3	13.4	1.2	119
T2011-14	1285081	33	36		6	0.2	10.3	0.6	177
T2011-14	1285082	36	39		1	0.1	8.1	0.1	123
T2011-14	1285083	39	42		5	0.3	9.6	0.2	135
T2011-14	1285084	42	45		2	0.1	10.6	0.1	170
T2011-14	1285085	45	48		3	0.2	11.5	0.2	168
T2011-14	1285086	48	51		5	0.6	10.6	0.5	132
T2011-14	1285087	51	54		8	0.4	9.6	0.4	149
T2011-14	1285088	54	57		7	0.05	9.3	0.3	144
T2011-14	1285089	57	60		12	0.4	13.8	0.6	161
T2011-14	1285090	60	63		5	0.2	8.4	0.3	110
T2011-14	1285091	63	66		7	0.1	8	0.4	113
T2011-14	1285092	66	69		7	0.2	9.3	0.4	125
T2011-14	1285093	69	72		5	0.3	14.5	0.7	127
T2011-14	1285094	72	75		3	0.2	14.2	0.8	116
T2011-14	1285095	75	78		8	0.1	18	0.2	139
T2011-14	1285096	78	81		8	0.1	8.5	0.4	110
T2011-14	1285097	81	84		5	0.05	1.7	0.2	60
T2011-15	1285201	0	3		292	3.4	1427.3	596.8	428
T2011-15	1285202	3	6		226	1.9	72.8	105.2	18
T2011-15	1285203	6	9		211	2.1	136.5	185.1	53

TrenchID	Sample	From_m	To_m	Comment	Au_FA_ppb	Ag_ppm	As_ppm	Sb_ppm	Zn_ppm
T2011-15	1285204	9	12		279	1.5	39.3	51.3	17
T2011-15	1285205	12	15		209	1.9	79.5	85.9	21
T2011-15	1285206	15	18		236	1.9	60.2	60.8	15
T2011-15	1285207	18	21		110	1.6	56.4	6.1	11
T2011-15	1285208	21	24		35	1.4	44.2	14.4	15
T2011-15	1285209	24	27		57	0.9	50.5	9.8	11
T2011-15	1285210	27	30		68	1.4	104	54	79
T2011-15	1285211	30	33		33	0.8	100.1	9.6	263
T2011-15	1285212	33	36		34	0.8	82.6	11.4	100
T2011-15	1285213	36	39		43	0.7	91.6	30.1	100
T2011-15	1285214	39	42		31	0.7	153.9	50.8	89
T2011-15	1285215	42	45		28	1.1	174	50.4	131
T2011-15	1285216	45	48		51	1.4	232.1	88.1	85
T2011-15	1285217	48	51	Missing					
T2011-15	1285218	51	54		59	1.6	106.8	34.8	53
T2011-15	1285219	54	57		46	1.5	168.2	40.8	28
T2011-15	1285220	57	60		28	1.1	199.3	45.2	37
T2011-15	1285221	60	63		21	0.7	134.8	33.4	34
T2011-15	1285222	63	66		12	0.9	72.8	43.2	44
T2011-15	1285223	66	69		1	1	42.4	21.2	10
T2011-15	1285224	69	72		7	1.3	62.8	45.1	17

Sample	Easting	Northing	Elevation	Rock Type	Mineralization	Description	Style	Source	Au_FA_ppb	Ag_ppm	As_ppm	Zn_ppm
1093501	401342.411	7018923.209	1481.277	GRAB	QUARTZ	FLOAT ON SLOPE NEAR TOP	Grab	Float	1	0.05	1.4	5
1093503	403986.316	7019796.045	1773.967	Limestone	minor dissem	Nubbley wethered surface, med grey lst,	Grab	Outcrop	1	0.05	1	19
1093504	404009.806	7019689.394	1800.557	Limestone	gossanous	Red brown gossanous bands ~2m wide,	Grab	Subcrop	1	0.2	2.1	59
1093505	403684.697	7019032.466	1710.388	Shale	possible realgar &	Possible realgar & orpioment on shale	Grab	Outcrop	3	0.2	3.8	3
1093507	403885.484	7019310.59	1806.132	QUARTZ	NONE	VUGGY WITH VIEN MATERIAL 5-cm	Grab	Float	1	0.05	1.6	4
1093509	403254.18	7019689.129	1732.975	COARSE QUARTZ	NONE	CG BRN STAIN FG SEDIMENTARY WALL	Grab	Float	4	0.05	1.5	21
1093510	403249.996	7019765.578	1705.856	Conglomerate	NONAPARENT	QTZ Conglomerate SEDIMENTARY	Grab	Float	1	1.3	1.6	3
1093511	403183.277	7019899.063	1694.227	QUARTITE	QUARTZ	QUARTITE & QUARTZ BRN COLOR	Grab	Float	1	0.05	54.4	19
1093512	403061.21	7020167.17	1593.339	SEDIMENTARY GREY	NONE	GREY SEDIMENTARY OUTCROP ON	Grab	Outcrop	1	0.05	0.6	4
1093513	402693.168	7020788.25	1408.142	SEDIMENTARY	REALGAR	SEDIMENTARY WITH REALGAR BLEBS	Grab	Float	1	0.05	1.5	23
1093514	402694.918	7020787.032	1403.753	OPRIMENT MIXED WITH QUARTZ	OPRIMENT ?	SEDIMENTARY WITH QUARTZ	Grab	Float	1	0.05	8.2	74
1093515	402703.214	7020791.032	1402.371	REALGAR OR CINNIABAR ?	QUARTZ	SAME AS ABOVE	Grab	Float	1	0.1	5.8	86
1093516	403857.421	7020268.992	1696.098	Limestone	QUARTZ VIEN		Grab	Outcrop	1	0.05	2.6	25
1093517	403826.815	7020295.742	1692.565	SEDIMENTARY WITH QUARTZ VIENLE		BLACK SEDIMENTARY WITH QUARTZ	Grab	Float	4	0.8	2.5	23
1093518	403751.229	7020399.245	1687.938	SEDIMENTARY		SEDIMENTARY WITH red blebs	Grab	Outcrop	4	0.05	2.4	21
1093519	403733.684	7020495.076	1672.448	DOLOMITE	CALCITE RED Blebs	From sEDIMENTARY oUTCROP	Grab	Outcrop	1	0.05	4.7	21
1093520	403691.909	7020723.496	1625.727	SEDIMENTARY		gREY SEDIMENTARY oUTCROP	Grab	Outcrop	44	0.3	30.1	31
1093521	403590.351	7020797.263	1576.998	SEDIMENTARY WITH QUARTZ VIENLE			Grab	Float	18	0.05	6.4	9
1093522	403844.328	7021236.121	1424.318	SEDIMENTARY		LARGE BOULDERS ON ESKER	Grab	Outcrop	15	0.9	6.3	2
1093523	403684.459	7021265.428	1427.697	CONGLOMERATE		QUARTZ MATRIX , RED & BLACK CLASTS	Grab	Float	5	0.4	1.8	1
1093524	399502.216	7022612.316	1361.52	LIMESTONE		LIMESTONE OUTCROP IN MEADOWS	Grab	Outcrop	1	0.05	2.1	31
1093525	399494.52	7022597.007	1366.113	INTRUSIVE	QUARTZ		Grab	Float	1	0.05	71.6	49
1093526	399748.623	7022316.85	1348.252	SEDIMENTARY Dark grey	QUARTZ		Grab	Float	1	0.05	1	15
1093527	399769.667	7022243.786	1343.521	CONGLOMERATE	NONE	QUARTZ SILTSTONE CONGLOMERATE	Grab	Float	4	0.5	0.25	3
1093528	399799.285	7022185.357	1321.975	Chert BRECCIA	RUSTY		Grab	Outcrop	3	0.6	2.4	5
1093529	401734.146	7019853.11	1545.152	QUARTZ	REALGAR orpioment	QUARTZ fLOAT fROM scree slOPE	Grab	Float	1	0.05	5.2	170
1093530	402020.291	7019792.807	1505.571	Chert pebble conglomerate		Rusty and yellow-stained conglomerate	Grab	Float	25	0.4	67.2	4
1093531	400621.099	7021002.35	1161.672	SHALE		SHALE OUTCROP AT RIVER	Grab	Outcrop	7	0.4	2.2	23
1093532	400646.572	7021021.185	1161.588	LIMESTONE OUTCROP			Grab	Outcrop	1	0.05	0.8	30
1093533	401983.053	7020027.721	1443.269	SEDIMENTARY			Grab	Outcrop	1	0.3	50.9	578
1093534	402425.817	7019940.389	1307.105	SEDIMENTARY			Grab	Float	1	0.1	9.4	376
1093535	402416.445	7019999.199	1304.924	Conglomerate		Weathered ,friable, black, conglomerate	Grab	Outcrop	6	0.6	39.1	405
1093536	402417.531	7020019.658	1301.618	QUARTITE		QUARTITE ,light brown , rusty fracture	Grab	Float	1	0.05	4.1	34
1093537	402420.797	7020032.085	1297.478	QUARTITE			Grab	Outcrop	16	0.1	24.7	50
1093538	401134.678	7020146.729	1488.278	QUARTZ fLOAT		VuGGY qUARTZ	Grab	Float	1	0.05	10	8
1093539	400985.635	7020258.23	1385.692	Felsite	Pyrite, epidoisite		Grab	Outcrop	51	1.6	545.1	12
1093540	400688.532	7020146.704	1339.686	SEDIMENTARY Chert	QUARTZ	Black SEDIMENTARY Chert VIENLETS	Grab	Outcrop	108	3	120.5	32
1093541	400677.609	7020210.377	1313.746	SEDIMENTARY	QUARTZ	SEDIMENTARY LIMONITE QUARTZ	Grab	Float	34	1	413.7	24
1093542	400602.566	7020234.518	1306.404	SEDIMENTARY	no	Grey SEDIMENTARY Rock	Grab	Outcrop	1	0.05	25.8	84
1093544	400523.383	7018633.272	1396.712	Grey shale	Pyrite dissem	Grey shale outcrop Strike 85 Dip 90	Grab	Outcrop	1	0.05	2.8	8
1093545	400682.39	7018578.839	1395.392	QUARTZ	Sulphides dissem	QUARTZ fLOAT with dissem sulphides	Grab	Float	1	0.05	3.7	28
1093546	401187.81	7018258.696	1445.114	QUARTZ		VuGGY , rusty, boxwork texture	Grab	Float	1	0.05	0.6	18
1093547	401541.055	7018150.481	1459.751	Shale - Grey	no	Grey shale outcrop	Grab	Outcrop	1	0.05	0.25	22
1093548	401702.519	7017902.995	1464.196	QUARTZ		QUARTZ with vugs , black viens, brown	Grab	Float	1	0.05	0.9	4
1093549	401522.033	7017725.719	1472.297	LIMESTONE OUTCROP			Grab	Outcrop	5	0.4	7.7	10
1093550	401354.318	7017625.967	1475.046	QUARTZ fLOAT in streambed		Cg VuGGY QUARTZ With red and brown	Grab	Outcrop	1	0.05	0.9	17
1093551	400500.734	7017796.752	1459.019	Porphyry		Dark grey porphyritic rock. Possible	Grab	Outcrop	1	0.2	15.3	109
1093552	407692.421	7015275.582	1771.735	Chert pebble conglomerate	Boronite	Rusty conglomerate outcrop o summit	Grab	Outcrop	5	0.6	3.2	144
1093553	407688.499	7015280.819	1773.646	SEDIMENTARY Mudstone	Dissem sulphides	Grey Mudstone	Grab	Outcrop	11	0.7	3.4	2
1093554	407696.227	7015252.638	1775.19	Decalc LiMESTONE ?	none	Grey , Sandstone Texture	Grab	Outcrop	6	0.7	8.2	37
1093555	407697.506	7015243.693	1775.233	Chert pebble conglomerate	Opriment	Very Cherty	Grab	Outcrop	4	0.4	3.3	3
1093556	407713.386	7015229.538	1775.152	SEDIMENTARY	LIMONITE	Cherty sedimentary rock with pervasive	Grab	Float	1	0.3	2.8	14
1093557	407745.98	7015236.413	1775.137	Sandstone	Hematite?	Brown sandstone with thick red viens	Grab	Float	4	0.1	13.4	2
1093558	407774.42	7015214.851	1749.952	Quartz	LIMONITE	Vuggy coarse grained vien material,	Grab	Float	1	0.05	3.7	3
1093559	408131.237	7015162.879	1704.033	Rhyolite	Hard, black blebs	Brown rhyolite with hard black inclusions	Grab	Float	4	0.1	7.7	127
1093560	408473.455	7015483.089	1643.781	Felsic carbonate volcanic	Minor pyrite	Felsic volcanic boulder on N ridge	Grab	Float	1	0.05	2.1	10
1093561	408467.178	7015503.318	1624.383	Felsic volcanic carbonate		Felsic volcanic carbonate rock with	Grab	Float	1	0.05	1.1	12
1093562	408474.916	7015556.978	1618.455	Felsic volcanic carbonate	Minor pyrite		Grab	Float	1	0.05	1.4	166
1093563	408055.096	7015361.775	1595.418	Chert pebble conglomerate			Grab	Float	1	0.6	3.5	2
1093564	408093.237	7015458.427	1582.609	Sedimentary	Two 2-cm round		Grab	Float	3	0.4	6.3	70
1093565	397654.351	7023282.196	1423.302	Sedimentary		Hard grey angular boulder with QUARTZ	Grab	Float	2.5	0.05	4.6	28
1093566	397648.504	7023284.047	1420.968	QUARTITE ?		Grey-brown granular texture, fizzes	Grab	Float	2.5	0.05	2	50
1093567	397695.017	7023259.815	1424.323	HEAVILY Weathered Quartzite ?	none		Grab	Float	2.5	0.05	4	33
1093568	397452.44	7022639.531	1546.497	Hornfels ?		Grey fine-grained, grey rock outcrop ,	Grab	Float	2.5	0.05	11.3	14
1093569	397447.453	7022643.755	1535.991	LiMESTONE		Medium grey limestone	Grab	Float	2.5	0.3	2.4	23
1093570	397356.789	7022115.627	1543.161	LiMESTONE OUTCROP	no	Grey LiMESTONE with 3cm Carbonate	Grab	Outcrop	2.5	0.2	3.6	32
1093571	397158.261	7022045.917	1558.028	LiMESTONE OUTCROP		Red limestone with carbonate viens	Grab	Outcrop	2.5	0.05	5.2	35
1093572	397200.501	7021985.628	1541.493	Limestone OUTCROP		Red and purple colored limestone	Grab	Outcrop	2.5	0.05	4.9	32
1093573	402447.559	7019838.428	1329.408	Chert Conglomerate		Dark Black QUARTZ Conglomerate	Grab	Outcrop	164	0.6	12.3	13

Sample	Easting	Northing	Elevation	Rock Type	Mineralization	Description	Style	Source	Au_FA_ppb	Ag_ppm	As_ppm	Zn_ppm
1093574	402445.505	7019720.198	1325.138	Chert pebble conglomerate			Grab	Float	78	0.7	15.4	4
1093575	402421.16	7019655.162	1344.102	Chert pebble conglomerate		Yellow Coating On Fractured Sufaces	Grab	Outcrop	31	1	13	3
1093576	402542.452	7019546.402	1352.547	QUARTITE		Rusty QUARTITE with QUARTZ VIENLETS	Grab	Float	2.5	0.05	15.8	171
1093577	402307.104	7019199.039	1371.016	QUARTITE		QUARTITE with drusy quarTZ VIENLETS	Grab	Float	12	0.1	59.9	25
1093578	402845.286	7018794.324	1440.893	Sedimentary Carbonate		Brown Weathered Limestone	Grab	Outcrop	2.5	0.3	6.8	21
1093579	402979.743	7018747.455	1478.762	Sedimentary	minor pyrite	Rusty Weathered Sedimentary Rock	Grab	Float	2.5	0.1	8.3	70
1093580	403359.012	7019314.433	1702.222	Limestone OUTCROP		Grey Limestone OUTCROP	Chip	Outcrop	11	0.1	17.4	18
1093581	403335.627	7019316.049	1697.873	Felsite		QUARTITE ? Ryholite ?	Chip	Outcrop	2.5	0.2	24.9	44
1093582	403057.204	7019355.603	1613.396	QUARTITE		Quartite? with QUARTZ VIENLETS ,rusty	Grab	Float	2.5	0.05	87.6	27
1093583	403072.277	7019416.436	1589.594	Sedimentary		Rusty grey sedimentary (no fizz) with	Grab	Outcrop	7	0.2	24.8	53
1093584	402825.385	7019302.12	1524.703	Chert pebble conglomerate		Unaltered Quartz Pebble conglomerate	Grab	Outcrop	8	0.5	5.7	2
1093585	402877.028	7019276.097	1537.458	QUARTZ VIEN		Quartz vein material with unknown dark	Grab	Float	2.5	0.2	3	1
1093586	402961.73	7019535.681	1556.655	Ryholite		Liight Brown Fine Grian Rock with Dark	Grab	Outcrop	2.5	0.05	32.1	9
1093587	402950.098	7019532.388	1555.102	Limestone OUTCROP		Grey Limestone OUTCROP	Grab	Outcrop	7	0.1	15.6	7
1093588	402916.297	7019735.399	1512.955	Ryholite ?		Felsic FineGrian Rock with QUARTZ	Grab	Subcrop	150	0.05	12.8	3
1093589	402877.85	7019760.779	1516.003	Quartite OUTCROP		Quartite	Grab	Outcrop	2.5	0.05	24.7	3
1093590	396313.245	7021728.42	1687.488	Shale		Black shale with minor dissem metallic	Grab	Outcrop	29	0.4	2.8	34
1093591	396552.731	7021682.567	1618.644	Quartite talus slope		Light Green ., Brown Weathered Quartite	Grab	Float	2.5	0.05	1.6	20
1093592	396520.668	7021522.598	1591.494	Quartite		Quartite With Thick Rusty VIENS	Grab	Float	2.5	0.05	3.7	28
1093593	402876.512	7016751.896	1727.602	Chert	Realgar,orpiment	Rusty chert with yellow fracture coating	Grab	Outcrop	2.5	0.6	6.5	5
1093594	402819.231	7016739.116	1725.967	Chert	Quartz	Black chert with vuggy quartz viensp	Grab	Float	2.5	0.05	3.5	5
1093595	402882.623	7016781.147	1710.655	Cherty shale		Black cherty shale with vuggy quartz	Grab	Outcrop	2.5	0.3	5	9
1093596	402858.132	7016809.689	1709.811	Grey Shale ,Brown Weathering	none	Steel shale	Grab	Outcrop	2.5	0.05	35.2	32
1093597	402841.706	7016905.433	1676.328	Brown Weathering Steel shale	Sulphide Button in	Shale FrAGMENT Contianing Sulphide	Grab	Outcrop	2.5	0.05	8.2	17
1093598	402862.902	7016962.022	1683.914	Shale		Grey shale outcrop ; orange weathered	Grab	Outcrop	2.5	0.05	11.4	19
1093599	402850.268	7017003.075	1691.088	Steel shale	Sulphide	Fractured rusty outcrop shale	Grab	Outcrop	2.5	0.5	2.5	37
1093600	400752.606	7020117.934	1363.849	Ryholite		Weathered rhyolite	Grab	Outcrop	2.5	1.1	30.9	6
1093601	400398.482	7019935.25	1309.658	Limestone		Silty limestone	Grab	Float	2.5	0.05	11.5	31
1093602	412998.415	7020558.1	1715.617	Quartz		Yellow orange cg quartz with white	Grab	Float	2.5	0.05	0.25	14
1093603	413000.327	7020557.772	1717.345	Quartz		Yellow orange weathered quartz breccia	Grab	Float	2.5	0.05	2.6	11
1093604	413032.603	7020566.229	1723.852	Q		CG yellow quartz with shale layers &	Grab	Outcrop	2.5	0.05	0.7	9
1093605	413062.137	7020706.539	1732.762	Shale outcrop		Rusty cherty shale outcrop on ridge	Grab	Outcrop	12	0.05	5.8	156
1093606	413080.799	7020722.839	1733.702	Chert		Grey chert with quartz vienlets	Grab	Outcrop	5	0.05	1.7	27
1093607	413033.465	7020655.764	1735.607	Conglomerate		Quartz carbonate breccia with cherty	Grab	Float	12	0.8	4	192
1093608	413029.801	7020653.219	1736.631	Chert	Carbonate	Black chert with carbonate vien	Grab	Float	2.5	0.2	1.7	43
1093609	413032.881	7020651.376	1720.692	Limestone	Calcite	Dark grey limestone with carbonate	Grab	Outcrop	2.5	0.05	3.1	25
1093610	412952.729	7020678.472	1692.966	Dolomite		Grey dolomite, quartz carbonate viens,	Grab	Outcrop	2.5	0.05	0.7	2
1093611	412946.134	7020679.351	1684.152	Limestone	Carbonate	Heavily weathered limestone, orange,	Grab	Float	2.5	0.05	3.8	51
1093612	412854.922	7020716.396	1654.16	Shale		Grey shale, brown rusty weathering	Grab	Outcrop	7	0.05	1.7	37
1093613	412808.469	7020713.564	1622.996	Dolomite	Quartz	Grey, orange weathered limestone with	Grab	Outcrop	2.5	0.05	1.3	8
1093614	409500.062	7019104.567	1434.142	Weathered Rock	unknown	Brown Weathered Rock	Grab	Float	6	0	0	0
1093615	409902.258	7018983.571	1551.769	Chert breccia	Minor pyrite	Rusty chert quartz breccia with quartz	Grab	Float	4	0	0	0
1093616	409874.138	7018920.364	1550.652	Sedimentary		Grey silicified sedimentary rock with	Grab	Float	1	0	0	0
1093617	409798.399	7018849.715	1543.643	Chert breccia		Chert breccia with pervasive red	Grab	Float	5	0	0	0
1093618	409692.795	7018860.014	1496.674	Chert breccia	Sulphide ;	Black chert with visible sulphide	Grab	Float	4	0	0	0
1093619	409539.854	7018928.763	1462.918	Conglomerate - Silvery Color	Unknown	Brown Conglomerate With Hematite ?	Grab	Float	2	0	0	0
1093620	409540.061	7018929.131	1461.004	Conglomerate			Grab	Outcrop	6	0	0	0
1093621	409606.299	7018722.807	1607.504	Chert conglomerate	Arsenopyrite	Presence of sulphide	Grab	Float	2	0	0	0
1093622	409492.148	7018668.083	1591.816	Chert conglomerate		Rusty chert conglomerate With vuggy	Grab	Float	1	0	0	0
1093623	410444.089	7018447.512	1955.53	Chert pebble conglomerate		Chert pebble conglomerate With vuggy	Grab	Outcrop	8	0	0	0
1093624	410471.626	7018329.773	1969.968	Shale		Rustr, baked shale with vuggy quartz	Grab	Float	3	0	0	0
1093625	410455.41	7018356.06	1968.708	Cherty shale		Black,baked cherty shale with green &	Grab	Float	12	0	0	0
1093626	410456.533	7018357.134	1967.944	Cherty shale		Weathered cherty shale with pervasive	Grab	Outcrop	1	0	0	0
1093627	410371.131	7018353.183	1927.805	Sedimentary		Dark grey bedded sedimentary rock with	Grab	Float	4	0	0	0
1093628	409695.792	7018320.141	1718.689	Chert breccia	Sulpher	Chert breccia with pervasive quartz viens	Grab	Outcrop	1	0	0	0
1093629	409263.414	7018719.007	1584.023	Quartz breccia		Quartz breccia with secondary quartz	Grab	Float	1	0	0	0
1093630	409071.979	7018824.381	1602.874	Unknown, yellow clump		Fist-sized yellow concretions	Grab	Float	1	0	0	0
1093631	409030.529	7018905.496	1607.873	Chert breccia	Pyrite	Black chert conglomerate with dissem	Grab	Float	14	0	0	0
1093632	409018.251	7018950.521	1604.662	Chert breccia	p	Felsic chert breccia with quartz vienlets &	Grab	Float	4	0	0	0
1093633	409093.231	7018837.871	1600.518	Quartz breccia		Quartz breccia with quartz vienlets	Grab	Outcrop	9	0	0	0
1093634	409378.065	7018670.487	1575.837	Quartz breccia		Felsic rock with quartz & clay alteration	Grab	Float	6	0	0	0
1093635	413811.729	7019270.235	1722.275	Limestone		Grey limestone with carbonate viens &	Grab	Outcrop	2	0	0	0
1093636	413792.855	7019284.632	1717.533	Chert		Chert with quartz vienlets with orange	Grab	Float	2	0	0	0
1093637	413886.62	7019304.571	1716.6	Quartz Breccia		Quartz Breccia with shale clasts	Grab	Outcrop	8	0	0	0
1093638	413712.125	7019131.812	1708.597	Shale outcrop on ridge	Disseminated pyrite	Shale outcrop on ridge	Grab	Outcrop	3	0	0	0
1093639	413806.782	7019172.015	1716.156	Shale	pyrite	Grey silicified shale with dissemenated	Grab	Outcrop	4	0	0	0
1093640	413818.773	7019182.362	1719.068	Dolomite	Minor pyrite	Grey dolostone with 3mm weathered	Grab	Outcrop	2	0	0	0
1093641	413821.479	7019121.474	1698.142	Silty Shale outcrop	minor pyrite	Grey fineGrian Silty Shale with brown	Grab	Outcrop	3	0	0	0
1093642	414130.469	7018758.927	1718.34	Limestone outcrop		Grey limestone with calcite viens	Grab	Outcrop	1	0	0	0

Sample	Easting	Northing	Elevation	Rock Type	Mineralization	Description	Style	Source	Au_FA_ppb	Ag_ppm	As_ppm	Zn_ppm
1093643	414026.614	7018681.635	1739.269	Chert		Rusty black chert	Grab	Outcrop	16	0	0	0
1093644	414025.298	7018682.812	1740.418	Quartz		Quartz with vugs	Grab	Float	5	0	0	0
1093645	413872.153	7018515.639	1743.858	Dolostone	Pyrite	Grey dolostone with dissem pyrite	Grab	Float	3	0	0	0
1093646	413976.764	7018543.822	1747.208	Shale	Pyrite	Grey shale with dissem pyrite	Grab	Outcrop	3	0	0	0
1093647	406520.706	7022494.809	1672.234	Shale Scree Finds	Unknown	Quartz and Shale finds	Grab	Float	8	0.05	5.7	46
1093648	406575.838	7022514.699	1655.847	Shale	unknown	Rusty cherty shale outcrop	Grab	Outcrop	4	0.1	1.7	28
1093649	406467.816	7022450.004	1668.224	Limestone		Grey limestone with carbonate viens &	Grab	Outcrop	1	0.05	4.8	161
1093650	406449.737	7022439.409	1666.034	Black Limestone outcrop	unknown	Black limestone with carbonate viens	Grab	Outcrop	1	0.05	1.5	12
1093651	406486.699	7022328.21	1639.141	Limestone		Grey limestone with carbonate viens &	Grab	Outcrop	1	0.05	1.7	10
1093652	406336.487	7022296.507	1653.732	Shale		Grey, cherty, brown-weathered shale	Grab	Outcrop	11	0.05	2.5	32
1093653	406381.344	7021865.03	1639.255	Shale		Black, rusty, cherty shale	Grab	Outcrop	26	0.05	3.9	66
1093654	406289.588	7021882.949	1641.478	Quartz	unknown	Quartz vien with brown alteration	Grab	Float	1	0.05	14.4	48
1093655	406256.138	7021884.764	1642.313	Shale	unknown	Vuggy Shale outcrop black	Grab	Outcrop	10	0.3	2.3	36
1093656	406279.068	7021881.564	1641.996	Dolomite	none	Grey Dolostone with orange coating	Grab	Outcrop	1	0.05	2.1	27
1093657	412278.326	7019070.66	1374.265	Blue shale	Pyrite	Silicified blue shale with dissem pyrite	Grab	Float	1	0.05	1.5	92
1093658	412279.392	7019069.161	1376.209	Black shale	Irridescence	Black shale with white & rusty coating &	Grab	Float	6	1.6	13.8	11
1093659	412259.041	7019017.479	1391.024	Shale outcrop	Stibnite	Black shale with metalic coating	Grab	Outcrop	1	0.7	8.8	88
1093660	412251.422	7019005.145	1399.108	Rusty Shale	unknown	Rusty shale wery weathered	Grab	Float	3	1.1	32	665
1093661	411864.163	7018466.347	1666.344	Shale		Rusty shale fragments from stream at	Grab	Outcrop	3	0.2	8	69
1093662	411860.685	7018470.914	1665.28	Chert		Mafic, cherty rock with quartz vienlets	Grab	Float	4	4.1	7.5	3
1093663	411782.422	7018558.348	1670.846	Felsic Chert conglomerate	unknown	Felsic Chert conglomerate with Quartz	Grab	Float	1	0.2	13.5	5
1093664	411747.399	7018593.545	1672.824	Shale		Black shale	Grab	Float	3	0.2	0.8	15
1093665	411746.063	7018594.475	1672.569	Rusty Conglomerate	unknown	Small Size rusty conglomerate	Grab	Float	4	1.8	122.9	148
1093666	412189.997	7019663.016	1390.161	Sedimentary	Pyrite	Grey fine grain sedimentary with pyrite	Grab	Subcrop	1	0.05	1	64
1093667	412137.334	7019669.306	1388.129	Sedimentary - argillite?	Pyrite	Grey fine grain sedimentary with pyrite	Grab	Subcrop	16	0.5	3.5	36
1093668	412026.593	7019623.295	1443.959	Quartz	Limonite	Quartz vien with yellow - brown stains	Grab	Float	1	0.05	5	120
1093669	411832.446	7019474.744	1496.501	Grey fine grain sedimentary	Pyrite	Grey fine grain sedimentary (argillite?)	Grab	Float	1	0.05	2.1	23
1093670	411823.048	7019320.519	1574.711	Chert	Dissminated pyrite	Black chert with few quartz vienlets	Grab	Subcrop	1	1	1.5	38
1093671	411489.637	7019365.06	1619.886	Sedimentary	Dissem pyrite	Fine grain grey argillite (?) with dissem	Grab	Outcrop	1	0.05	1	45
1093672	411489.238	7019363.816	1620.424	Shale		Black shale	Grab	Subcrop	1	0.05	0.25	71
1093673	411520.515	7019347.416	1622.888	Shale	Pyrite	Black shale with pyrite & metallic lustre	Grab	Float	1	0.8	23.8	38
1093674	411465.31	7019314.717	1624.332	Sedimentary		Black, fine grain, conch fracture, soft	Grab	Float	1	2.2	7.2	33
1093675	411462.277	7019311.786	1624.059	Quartz Breccia		Rusty quartz breccia with fine grain clasts	Grab	Float	1	1.2	16.2	98
1093676	411368.162	7019404.808	1548.896	Quartz breccia		Quartz breccia with angular clasts	Grab	Float	1	1.1	17.4	254
1093677	411351.428	7019419.124	1514.278	Shale		Black shale, friable, soft greasy graphite-	Grab	Outcrop	4	3.4	23	98
1093678	411297.862	7019415.722	1510.558	Scree assortment		Random selection of scree fragments	Grab	Float	1	0.9	6.7	88
1093679	411215.34	7019429.818	1465.548	Shale		Black shale with yellow sheen & large	Grab	Float	1	1.4	11.6	96
1093680	411211.994	7019428.383	1464.839	Intrusive		Coarse-grained granitic intrusive rock	Grab	Float	6	1.1	21.1	246
1093681	406427.091	7020941.504	1539.519	Secondary		Brown weathering grey sandstone with	Grab	Float	1	0.8	6.9	173
1093682	406437.351	7020954.172	1539.965	Shale		Black graphitic shale with yellow coating	Grab	Float	1	0.5	2.3	28
1093683	406519.292	7020800.97	1514.79	Sedimentary		Brown heavily weathered & corroded	Grab	Float	5	7.3	929.7	3645
1093684	406809.644	7020687.126	1537.645	Quartzite	Minor dissem pyrite	Brown weathered quartzite with dissem	Grab	Float	1	0.05	2.2	56
1093685	406780.009	7020666.816	1540.774	Sedimentary	Dissem pyrite	Grey fine grain, weak carbonate,	Grab	Float	1	0.1	1.8	21
1093686	406155.206	7020941.864	1533.321	Quartzite	Minor dissem pyrite	Felsic quartzite, brown weathered	Grab	Float	40	0.05	46.1	38
1093687	406219.601	7021022.471	1498.545	Rhyolite	Minor dissem pyrite	Brown weathered rhyolite	Grab	Float	53	0.05	131.7	29
1093688	406231.517	7016813.547	1457.786	Shale	Minor pyrite	Brown weathering grey shale with dissem	Grab	Subcrop	1	0.05	6.8	27
1093689	406610.801	7016819.95	1372.243	Quartz		Milky quartz coarse grained	Grab	Float	1	0.05	0.25	7
1093690	406612.606	7016830.255	1396.566	Quartzite		Greenish quartzite with 1cm heavily	Grab	Float	1	0.05	0.7	73
1093691	397028.517	7022132.79	1586.999	Limestone		Red limestone with carbonate viens	Grab	Float	1	0.05	1.9	39
1093692	397134.376	7021959.517	1490.195	Shale		Brown weathering grey shale	Grab	Outcrop	6	0.1	1.5	71
1093693	397138.313	7021956.697	1496.351	Limestone		Purple limestone with carbonate viens &	Grab	Outcrop	2	0.05	0.6	16
1093694	397112.122	7021879.637	1460.632	Quartz		Quartz breccia with drusy red vugs	Grab	Outcrop	4	0.1	1.3	74
1093695	413459.761	7016986.314	1472.843	Chert conglomerate		Weathered & heavily oxidized chert	Grab	Float	2	0.5	53.3	36
1093696	413255.5	7017083.345	1430.608	Chert conglomerate		Dark grey chert conglomerate with heavy	Grab	Float	1	1	0.25	1
1093697	412649.66	7017233.802	1515.826	Shale	Dissem pyrite	Brown weathering grey shale with dissem	Grab	Outcrop	4	0.5	2.7	8
1093698	412652.209	7017228.649	1516.693	Chert conglomerate		Grey chert conglomerate with secondary	Grab	Outcrop	7	0.6	1.6	1
1093699	416076.909	7015745.264	1661.441	Sedimentary		Thinly bedded heavy grey sedimentary	Grab	Outcrop	5	0.2	16.6	22
1093700	416067.137	7015746.568	1659.552	Sedimentary		Rusty cherty sedimentary outcrop with	Grab	Outcrop	17	0.6	30.3	146
1093701	416038.557	7015749.777	1647.135	Shale	Dissem pyrite	Silicified brown weathering grey shale	Grab	Subcrop	3	0.2	19.4	95
1093702	415957.047	7015623.893	1608.307	Quartz vien		Rusty vuggy quartz vien material	Grab	Outcrop	1	0.05	4.7	145
1093703	416602.762	7015506.312	1529.786	Sedimentary ??		Red-brown heavily oxidized very rotten	Grab	Subcrop	1	0.2	312.4	219
1093704	416556.393	7015433.693	1536.09	Rhyolite		Felsic clay-altered fine grain rock	Grab	Float	1	0.2	9	6
1093705	416568.501	7015374.132	1517.126	Chert conglomerate	Disseminated silvery-	Black chert conglomerate with quartz	Grab	Float	3	1.1	2.1	1
1093706	394258.739	7019896.064	1519.817	Sedimentary		Brown weathering grey shale, conch	Grab	Subcrop	1	0.05	1.8	11
1093707	394244.053	7019894.754	1519.436	Shale		Heavily foliated, brown weathering grey	Grab	Outcrop	1	0.05	1.2	11
1093708	394137.536	7019575.906	1481.398	Granite	Trace pyrite		Grab	Float	1	0.05	9.8	20
1093709	394067.435	7019837.997	1510.608	Shale		Black cherty graphitic shale	Grab	Outcrop	1	0.4	2	5
1093710	394139.724	7019838.482	1510.282	Limestone		Grey limestone	Grab	Float	1	0.05	0.25	9
1093711	394242.491	7019982.428	1493.769	Quartz vien	Carbonate	Quartz vien material with carbonate on	Grab	Float	1	0.05	0.6	7

Sample	Easting	Northing	Elevation	Rock Type	Mineralization	Description	Style	Source	Au_FA_ppb	Ag_ppm	As_ppm	Zn_ppm
1093712	394265.382	7020210.94	1503.779	Carbonate argillite	Pyrite	Grey carbonate sedimentary rock with	Grab	Subcrop	2	0.05	1.6	19
1093713	400261.84	7015997.928	1699.791	Shale		Brown weathering grey shale	Grab	Outcrop	1	0.05	11.2	103
1093714	400238.477	7015914.091	1677.725	Shale		Brown weathering grey shale with vuggy	Grab	Subcrop	1	0.05	4.1	130
1093715	400194.04	7015558.957	1610.425	Shale		Random selection from shale scree slope	Grab	Float	1	0.05	6.3	64
1093716	400206.09	7015575.315	1604.542	Sedimentary		Weakly silicified shale with vuggy quartz	Grab	Float	3	0.2	27.1	55
1093717	400178.292	7015637.422	1572.892	Quartz		Vuggy rusty quartz vien material	Grab	Float	1	0.05	2.8	47
1093718	400021.747	7015551.905	1521.672	Sedimentary		Silicified grey sedimentary rock	Grab	Float	4	0.2	14.2	23
1093719	399748.68	7015541.266	1451.029	Sedimentary		Grey sedimentary rock with 1cm quartz	Grab	Outcrop	1	0.05	1.2	11
1093720	403057.236	7019324.442	1606.2	Sedimentary	unknown	Dark grey fine grain sedimentary with	Grab	Float	2.5	0.15	6	36
1093721	403058.868	7019324.811	1606.005	Sandstone	unknown	Sandstone with quartz vienlets	Grab	Float	7	0.15	36	91
1093722	402907.033	7019733.674	1540.919	Quartzite		Felsic fine grain quartzite with quartz	Grab	Subcrop	114	0.15	11	2
1093723	402943.817	7019744.591	1537.44	Quartzite		Quartzite with moderate hematite	Grab	Subcrop	2.5	0.15	10	5
1093724	402942.422	7019776.657	1588.726	Rhyolite ?		Felsic arg altered rhyolite with quartz	Grab	Float	2.5	0.15	26	7
1093725	403132.635	7019887.025	1681.831	quartzite		quartzite with dark and white viens	Grab	Float	100	0.15	184	64
1093726	403134.764	7019879.58	1682.676	Quartzite		quartzite with red staining & quartz viens	Grab	Float	10	0.15	56	17
1093801	402173.256	7019625.785	1489.756	granular conglomerate	nickel/copper oxide		Grab	Outcrop	2.5	1.5	323.3	8
1093802	402044.432	7019611.529	1571.548	granular conglomerate	sulfide oxide		Grab	Outcrop	100	1.4	30.5	3
1093803	403197.141	7018869.774	1494.51	felsic intrusive	dissminated pyrite	strongly oxdized felsic intrusive with	Grab	Outcrop	1	0	0	0
1093804	401370.404	7020428.813	1464.439	Shale brown weathering breccia		brown weathering silicious shale breccia	Grab	Outcrop	13	0.05	43.7	569
1093851	399706.633	7021973.485	1291.019	limestone caribou pass	calcite veining	limestone with stockwork calcite veins	Grab	Outcrop	1	0.05	0.25	27
1093852	401955.182	7019540.485	1651.991	chert pebble conglomerate	quartz veins	oxdized chert pebble conglomerate	Grab	Outcrop	1	0.2	7.7	2
1093854	401787.446	7019589.097	1643.913	chert pebble conglomerate	scorodite	weak argillic altered chert pebble	Grab	Outcrop	2	0.5	37.6	2
1093855	401591.534	7019701.703	1612.781	quartz ans shale breccia		strongly oxdized quartz shale breccia	Grab	Float	129	0.7	825.5	5
1093856	401568.261	7019725.833	1594.837	conglomerate		oxdized fine gravel conglomerate	Grab	Outcrop	11	0.4	45.5	4
1093901	400924.943	7019959.258	1414.37	shale outcrop	strong yl orange	shear zone; carboniferous bk shale	Chip	Outcrop	11	1	3477.6	3188
1093902	400917.213	7019955.429	1420.273	shale outcrop black	yellow orange		Chip	Outcrop	155	1.9	526.1	4184
1093903	400991.988	7019955.062	1423.409	grphtic bk shale	scorodite		Chip	Outcrop	4	0.7	21.1	9
1093904	400994.287	7020287.592	1398.687	felsic dyke	trace pyrite	composite	Grab	Outcrop	51	1.4	154.6	47
1093905	401014.64	7019918.254	1452.587	grphtic shale	scorodite??		Grab	Subcrop	19	0.6	40.6	3
1093906	401608.858	7020132.812	1603.485	limestone			Grab	Subcrop	6	0.4	3	9
1093907	401096.565	7019812.314	1472.173	carboniferous shale	scorodite	composite	Grab	Subcrop	7	0.5	33.2	4
1093908	401085.711	7019819.592	1473.449	felssite			Grab	Subcrop	3	0.2	27.9	5
1093909	401096.856	7019805.188	1472.347	shale outcrop	scorodite		Grab	Outcrop	3	0.5	14.5	5
1093910	401132.546	7019845.703	1487.821	shale scree slope	scorodite ;		Grab	Outcrop	75	0.7	112.7	186
1093911	401130.618	7019853.407	1496.78	carboniferous shale	yellow orange		Grab	Outcrop	5	0.8	37.7	6
1093912	401137.19	7019849.46	1497.719	carboniferous shale		Au anomaly	Grab	Outcrop	5	0.6	17.5	4
1093913	401146.178	7019847.076	1496.089	carboniferous shale			Grab	Outcrop	9	0.7	50.8	4
1093914	402357.27	7015194.05	1501.726	quartzite		lt gy quartzite in 2m shear zone; 350/89	Grab	Outcrop	1	0.05	14.1	84
1093915	402764.503	7015557.302	1512.265	fissile bk gy shale outcrop			Grab	Outcrop	1	0.05	16.1	136
1093916	416068.789	7012051.996	1561.499	volcanic	0.5-1% vfg pyrite		Grab	Outcrop	1	0.2	152.5	113
1093917	415998.976	7012052.059	1572.487	VOLCANICS	PYRITE		Grab	Outcrop	1	0.05	71.5	70
1093918	416002.469	7012050.867	1579.796	quartz viens	limonite orange	white vuggy , drusy qtz with patchy	Grab	Float	4	0.1	99.1	17
1093919	416044.604	7012129.559	1588.098	gun steel shale		out crop forms prominant knoll	Grab	Outcrop	1	0.4	2.4	3
1093920	416139.283	7012196.018	1567.175	calcarious fg sandstone		wkly foliated grey brown with dull orange	Grab	Subcrop	1	0.05	4	29
1093921	416139.218	7012197.076	1567.29	shale	trace disseminated	fissile grey brown shale	Grab	Outcrop	1	0.2	3.7	29
1093922	415922.598	7012359.373	1566.495	quartz vein			Grab	Float	1	0.2	2.5	6
1093923	415496.329	7012318.543	1485.59	volcanic	talus very fine grain	orange weathering , medium graind grey	Grab	Outcrop	1	0.05	51.9	81
1093924	415468.694	7012333.511	1482.066	quartz vien	barren		Grab	Float	1	0.05	14.8	48
1093925	415467.213	7012327.177	1480.989	volcanic sill	trace very fine		Grab	Outcrop	1	0.05	35	60
1093926	415456.088	7012330.522	1485.24	volcanic sill	1% bleby py; 1%	grey orange weathered qtz serite pyrite	Grab	Subcrop	1	0.05	112	58
1093934	415981.153	7012070.513	1568.569	listwanite	tr-1% pyrite		Grab	Outcrop	2	0.05	21.2	50
1093935	416008.411	7012045.807	1559.037	quartz vien			Grab	Float	1	0.05	142.7	41
1093936	415948.902	7012012.462	1533.599	altered volcanic		grungy looking, siliceous orange float	Grab	Float	3	0.2	157.1	37
1093937	415949.033	7012013.212	1533.387	listwanite	5% pyrite blebs		Grab	Outcrop	17	0.2	1311.3	49
1093938	415954.618	7012017.379	1535.445	quartz vien		grungy looking qtz carbonate altered vn	Grab	Float	8	0.7	130.6	413
1093939	415959.713	7012019.284	1541.959	quartz		fist sized bull white quartz	Grab	Float	1	0.05	21.3	13
1093940	416012.086	7012072.237	1584.937	quartz vien		grab of qtz float from rusty shale	Grab	Float	1	0.05	2.4	44
1093941	402894.831	7016869.982	1667.552	shale		orange weathering grey shale	Grab	Subcrop	1	0.1	5.9	19
1093942	402879.178	7016844.754	1665.332	shale	2%pyrite blebs	orange weathering grey shale	Grab	Subcrop	3	0.05	3.4	10
1093943	402890.995	7016768.203	1684.714	gypsy-bk shale		grey black shale; qtz vienlets	Grab	Subcrop	1	0.5	2.9	5
1093944	402902.489	7016802.463	1677.319	quartz		qtz chips over 10m trends 060	Grab	Float	1	0.05	5	25
1093945	403154.416	7016702.393	1644.502	quartz		qtz sweat, vien material?	Grab	Float	1	0.2	5.6	26
1093946	403285.626	7016716.409	1612.601	dolomite		orange weathering grey massive Dolimite	Grab	Outcrop	1	0.05	18.5	125
1093947	402995.374	7016617.18	1655.756	quartz vien material		white quartz chips from scree slope	Grab	Float	1	0.05	3.4	34
1093948	403077.067	7016651.434	1618.029	qtz float		10x5x5cm float; white grey mottled	Grab	Float	1	0.05	1.6	12
1093949	403091.332	7016646.995	1618.054	qtz brsccia float		white brittle quartz breccia 30x20x15cm	Grab	Float	1	0.2	5.1	14
1093950	403114.76	7016631.459	1615.031	qtz float		from sw bank of creek	Grab	Float	1	0.2	3.5	32
1093951	403138.368	7016627.328	1611.489	quartz float	pervaisive orange	vuggy, porous qtz float	Grab	Float	1	0.1	7.1	175
1093952	403966	7021273	1393				Grab	Outcrop	24	1.9	76.9	25

Sample	Easting	Northing	Elevation	Rock Type	Mineralization	Description	Style	Source	Au_FA_ppb	Ag_ppm	As_ppm	Zn_ppm
1093953	403961	7021266	1403				Grab	Outcrop	26	2.5	4.3	2
1093954	403948	7021258	1400				Grab	Outcrop	26	2.3	24.2	3
1093955	403860	7021235	1429				Grab	Outcrop	7	0.6	4.4	0.5
1093956	403781	7021316	1410				Grab	Outcrop	16	1.4	14.6	2
1093957	406089.381	7016850.638	1394.673	shale	trace pyrite blebs		Grab	Subcrop	5	0.05	5	97
1093958	406491.63	7017344.274	1610.596	volcanic	1%pyrite blebs	orange weathering lt green mafic	Grab	Subcrop	1	0.05	3.9	14
1093959	406512.201	7017370.215	1626.629	volcanic	wk pyrite	2=3m wide carb alt dyke trends E-W	Grab	Outcrop	1	0.05	124.7	20
1093960	406513.212	7017376.458	1628.095	volcanic	tr vfg pyrite	orange weathering, lt gy gn; spheriolitic	Grab	Outcrop	1	0.05	16.7	149
1093961	418609.139	7014448.484	1625.334	quartz vien	orange limonite	tabular 10cm wide blocks trend 010	Grab	Float	1	0.05	2.9	5
1093962	418608.669	7014450.45	1624.317	quartz vien float	wk yellow orange		Grab	Float	3	0.05	6.1	11
1093963	418633.206	7014491.713	1605.11	quartz vien float	yellow orange	white grey dark qtz, pitted orange	Grab	Float	12	1.3	1.4	4
1093964	418639.78	7014515.129	1604.583	quartz float	wk yellow orange	20cm3 block intensely shattered vien	Grab	Float	1	0.05	1.2	4
1093965	418636.141	7014512.867	1604.604	qtz float	orange limonite	drusy, vuggy tx	Grab	Outcrop	1	0.05	4.6	10
1093966	418632.488	7014508.184	1607.769	quartz vien float		white, brittle, qtz with slicks on one face	Grab	Float	1	0.05	13.2	17
1093968	418634.203	7014488.273	1622.258	conglomerate?	yellow limonite in	white weathering block	Grab	Float	1	0.6	1.1	1
1093969	418625.611	7014499.956	1619.587	quartz vien float		white quartz wih slicks on on face	Grab	Float	1	0.05	10.9	5
1093970	418627.19	7014496.261	1620.48	quartz vien float	(		Grab	Float	1	0.05	36.5	58
1093971	418557.898	7014500.646	1613.004	qtz float	wk yellow limonite	brittle white quartz, vugs pitted surface	Grab	Float	1	0.05	0.25	5
1093972	418566.954	7014508.167	1606.777	quartz vien detritus		brittle white quartz; qtz brsccia float	Grab	Float	1	0.05	10.3	4
1093973	418569.447	7014522.062	1600.143	quartz vien detritus			Grab	Float	1	0.05	27.3	5
1093974	415851.754	7013336.83	1712.251	quartz vien float in volcanic	trace soft bk gy	white drusy, vuggy, brittle quartz	Grab	Float	2	0.05	3.1	141
1093975	415925.422	7013147.632	1689.278	volcanic dyke?	trace to 1% pyrite		Grab	Outcrop	1	0.05	2.8	78
1093976	415988.902	7013113.963	1668.976	intermediate volcanic (dyke?).	trace to 1% vfg		Grab	Outcrop	1	0.05	2.4	92
1093977	415980.525	7013112.099	1664.298	siliceous intermediate volcani	trace to 1%		Grab	Subcrop	1	0.05	3	66
1093978	415993.06	7013102.746	1672.182	quartz vien	trace dark sulphide		Grab	Outcrop	1	0.05	0.6	20
1093979	416030.109	7013101.485	1668.502	intermediate volcanic	trace to 1% pyrite;		Grab	Outcrop	1	0.05	2	74
1093980	415995.798	7013117.149	1669.583	intermediate volcanic	vfg diss py; 1%	orange brown weathering; lt gy siliceous	Grab	Outcrop	1	0.05	3.2	108
1093981	416036.214	7013099.921	1669.696	intermediate volcanic	tr-1%clustered	moderate fractures or gy weathering; fg	Grab	Outcrop	1	0.05	1.7	58
1093982	414599.68	7012596.246	1563.737	altered volcanic	strongly	Au in soil anomaly	Grab	Subcrop	141	0.4	5185	48
1093983	414601.91	7012599.913	1564.385	altered volcanic	3 % clustered pyrite;	orange weathering; lt gn-grey	Grab	Subcrop	143	0.2	3452.3	52
1093984	414601.268	7012599.197	1564.376	altered volcanic	trace to 1 %pyrite tr	orange grey weathering; dk green clots;	Grab	Subcrop	1	0.05	11.8	86
1093985	414603.792	7012603.265	1564.072	altered volcanic	3-5 %pyrite	more bleached looking with strong pyrite	Grab	Float	222	0.5	1447.7	51
1093986	414601.855	7012602.863	1564.384	altered volcanic	3 % smattered to	lt buff material, carb,sericite with tr	Grab	Float	430	0.9	1570.6	57
1093987	393731.873	7020399.319	1400.487	quartz vien float	barren	angular 15x2010cm float in creek	Grab	Float	1	0.05	1.7	68
1093988	394558.902	7020754.781	1508.661	quartz vien detritus	barren		Grab	Subcrop	1	0.4	29.6	26
1093989	394575.488	7020837.548	1498.291	grungy looking qtz float	none?	0.75x0.4 block dk grey black vuggy;	Grab	Float	1	0.1	36.2	147
1093990	394557.514	7020816.527	1503.058	barite		lt gy white weathering , grey fresh	Grab	Outcrop	4	0.05	0.5	5
1093991	394523.288	7020766.541	1512.393	quartz vien detritus	barren	white quartz,briilte, bk wispy stringers	Grab	Float	1	0.1	13.9	4
1093992	399518.845	7016557.484	1559.431	quartz vien		vuggy, porous to drusy qtz vn 4cm thick	Grab	Outcrop	1	0.05	11.8	5
1093993	398895.39	7016850.826	1396.682	gritty shale	fg weird white flaky	shear zone 360/90	Grab	Outcrop	1	0.05	7.1	144
1093994	398949.342	7016929.942	1392.218	sandstone		NW facing slope	Grab	Subcrop	1	0.1	91.2	89
1093995	401630.573	7020268.152	1587.521	quartz vien float	barren		Grab	Float	1	0.05	13.5	47
1093996	401628.35	7020327.145	1578.265	quartz vien float		8 pieces of varying sizes ~1cm thick	Grab	Float	1	0.05	7.4	217
1093997	401612.989	7020383.316	1572.525	shale			Grab	Outcrop	1	0.3	12.1	33
1093998	409574.759	7018959.918	1450.99	conglomerate	1 %pyrite		Grab	Float	35	2.1	36.7	18
1093999	409451.295	7018896.767	1475.807	barite flooding in shear?	barite vn detritus/	barite breccia zone in conglomerate	Grab	Outcrop	4	0.3	26.1	6
1094000	396589.157	7023130.112	1372.691	shale		siliceous black shale;	Grab	Float	1	0.05	0.7	16
1094001	401309.335	7020373.999	1440.134				Grab	Outcrop	10	0.5	184.3	262
1094002	401310	7020375	1440	Quartzite Dyke		Chip 1 meter across quartizite dyke	Chip	Outcrop	12	1.6	24.1	64
1094003	399369	7016791	1530.49	Rhyolite shale breccia	hematite, sericite,	On contact rhyolite & shale, qtz breccia	Chip	Outcrop	1	0.1	88.6	91
1094004	399354	7016879	1457.491	Rhyolite	dissem py	5m chip across rhyolite with diss pyrite	Chip	Outcrop	17	0.05	673.1	217
1094005	399402	7016916	1460.491	Shale	Limonitic	20 meter composite sample	Chip	Outcrop	5	0.2	12.6	135
1094006	399701	7017106	1339.488	Limestone breccia		Calcrete float, same location as soil	Grab	Outcrop	3	0.1	90.3	3599
1094007	400079	7017662	1371.488	Shale	Fine diss py		Chip	Outcrop	3	0.05	2.4	16
1094008	399976	7018034	1389.494	Shale		Composite sample 10m across hematitic	Chip	Outcrop	3	0.6	3	33
1094010	407639.907	7015128.036	1696.134	Silty Limey Shale	Hematitic	Silty, very hematitic limey shale with	Chip	Float	2.5	0.1	4	22
1094011	407640.001	7015130	1704	Chert pebble Congl	Hematite	Composite 25m sample accross boulder	Chip	Float	2.5	0.4	4.3	20
1094012	395024.87	7021570.223	1552.289		des pyrite/hem		Grab	Outcrop	2.5	0.1	3.9	90
1094013	395652	7021301	1572.539	Shale	Hem, diss py	Dark black shale, small dyke running at	Chip	Outcrop	2.5	1.4	70.6	154
1094014	395648	7021309	1576	Rhyolite Dyke		Small altered rhyolite dyke seems to run	Grab	Subcrop	2.5	0.05	7.9	127
1094015	395779.937	7021110.3	1493.336				Grab	Outcrop	2.5	0.1	6.7	5
1094017	395953.752	7021194.747	1450.856	QM	Pyrite		Grab	Outcrop	2.5	0.2	5.4	331
1094018	403057.932	7018388.734	1636.32				Grab	Outcrop	2.5	0.05	58.1	19
1094019	402950	7018354	1643.457	Ferricrete	diss py	Grey bubbly, calcareous, subcrop zone	Chip	Subcrop	2.5	0.5	63.2	11
1094020	403052	7018269	1609.454	Breccia	pyrite	Hematitic, almost breccia, calcareous,	Grab	Outcrop	2.5	0.1	192.1	14
1094021	403240	7018177	1574.451	Breccia	hem, diss py	Composite over 10m, grey, lots of calcite	Chip	Outcrop	2.5	0.1	16.5	87
1094022	403153.08	7018357.608	1636.847		HEM/DES Pyrite		Grab	Outcrop	2.5	0.05	114.1	29
1094023	402986.502	7018408.886	1627.59				Grab	Outcrop	2.5	1	38.7	1013
1094025	403138.678	7018714.372	1507.5	QTZ VEIN			Grab	Outcrop	2.5	0.05	5.5	109

Sample	Easting	Northing	Elevation	Rock Type	Mineralization	Description	Style	Source	Au_FA_ppb	Ag_ppm	As_ppm	Zn_ppm
1094026	403328	7018801	1532.459	Rhyolite	hem	Chip accross 1x10m small exposure of	Chip	Outcrop	2.5	0.2	35.5	471
1094027	403234.383	7018856.87	1501.211	RHYOLITE DYKE	hem		Chip	Outcrop	2.5	0.4	146.1	80
1094028	403196.538	7018901.749	1507.445		HEM	GOSSAN	Grab	Outcrop	20	0.8	73.4	1050
1094029	403182.221	7019064.77	1570.779	RHYOLITE FLOAT			Grab	Outcrop	2.5	0.4	20.2	28
1094031	402378.823	7019633.243	1365.753				Grab	Outcrop	2.5	0.5	59.1	15
1094032	402172.165	7019371.762	1515.371	QM DYKE			Grab	Outcrop	2.5	0.05	35.9	125
1094033	402171.441	7019369.726	1516.426	Grey-black Shale		Chip accross 2m of grey-black shale	Chip	Outcrop	2.5	0.7	35.3	187
1094034	402170	7019370	1516	Qtz-shale Breccia		On contact with qtz monzonite dyke,	Grab	Float	2.5	0.1	17.5	47
1094035	401924.598	7019376.095	1607.296	RHYOLITE DYKE			Grab	Outcrop	2.5	0.1	34.9	3
1094037	401788.192	7019476.94	1605.298	GREY SHALE/QTZ			Grab	Outcrop	7	1.5	79.2	8
1094038	401623.103	7019577.805	1609.623	RHYOLITE DYKE			Grab	Outcrop	2.5	0.1	265.3	39
1094039	401564.783	7019625.689	1610.673	RHYOLITE DYKE			Grab	Outcrop	2.5	0.2	278.4	6
1094040	400960.627	7019930.022	1440.041	RHYOLITE DYKE			Chip	Outcrop	23	0.4	345.1	5
1094042	411542.659	7019819.89	1623.382	SS	HEM		Grab	Outcrop	61	1.2	7.3	151
1094043	411542.308	7019857.093	1605.949	TAN GREY SS	Pyrite		Grab	Outcrop	2	0.1	5.5	36
1094044	411492.264	7019854.771	1589.642	BSontacr			Grab	Outcrop	9	1.2	6.3	114
1094045	411495	7019855	1590	Shale Siltstone	Minor diss py	Very cherty shale siltstone along contact	Chip	Outcrop	1	0.05	1.1	32
1094046	411476.374	7019979.729	1584.356				Grab	Outcrop	4	0.05	44.7	354
1094047	411380.016	7020007.987	1579.22				Grab	Outcrop	10	0.2	57.7	182
1094048	411119.153	7019850.983	1434.429				Grab	Outcrop	3	0.8	48.3	1574
1094050	407126.164	7020544.014	1466.529				Grab	Outcrop	7	0.2	2.5	50
1095351	415682	7013309.242	1694.794	SSS			Grab	Outcrop	1	0.05	2.4	40
1095352	415859.61	7013122.828	1698.958	BLACK SHALE			Grab	Outcrop	1	0.2	34.7	68
1095353	415869.371	7013116.811	1699.838	VOLCANICS			Grab	Outcrop	1	0.05	8.6	79
1095354	415841.139	7013366.642	1722.685	TAN WEATHERED BLACK SHALE			Grab	Outcrop	1	1.3	83.2	1792
1095355	400214.851	7015442.941	1618.41	CHERTY BLACK SHALE			Grab	Outcrop	4	0.4	24.5	165
1095356	400217.666	7015422.743	1609.616	SILTY SANDSTONE	DES PYRITE		Grab	Outcrop	1	0.05	4.6	45
1095357	400214.442	7015422.615	1603.286	BLACK SHALE			Grab	Outcrop	1	0.1	9.3	75
1095358	400131.495	7015279.787	1568.917	BLACK SHALE			Grab	Outcrop	3	0.2	13.7	89
1095359	400074.153	7015010.812	1520.549	BLACK SHALE			Grab	Outcrop	3	0.5	37.1	65
1095360	399328.341	7015559.607	1450.135	BLACK SHALE			Grab	Outcrop	14	0.4	18	217
1095361	400990.397	7019877.104	1436.715	RHYOLITE DYKE	POSS REG/ORP		Grab	Outcrop	7	0.3	15.9	2
1095362	400935.411	7019953.298	1421.596	BLACK SHALE	hem/des PYRITE		Grab	Outcrop	26	0.8	732.3	845
1095363	400957.537	7019846.965	1426.205	BLACK SHALE	hem/des PYRITE	SHEAR ZONEc	Grab	Outcrop	1	1	186.1	2519
1095364	400976.423	7019973.342	1418.497	RHYOLITE DYKE			Chip	Outcrop	1	0.3	49.3	14
1095365	400975.277	7019970.178	1418.1	QZT VEIN			Chip	Outcrop	26	1.5	386.7	48
1095366	400971.734	7020063.16	1398.729	BLACK SHALE			Chip	Outcrop	1	0.1	49.3	163
1095367	401005.511	7020216.945	1411.327	INTRUSIVE DYKE			Chip	Outcrop	9	0.9	433.6	37
1095368	401038.996	7020260.476	1413.807	BLACK SHALE			Chip	Outcrop	4	0.2	96.7	103
1095369	401063.343	7020274.469	1411.272	INTRUSIVE	Des PYRITE		Chip	Outcrop	17	0.4	264.3	109
1095370	401127.824	7020396.451	1396.843	bLACK SHALE	B		Chip	Outcrop	12	0.2	157	21
1095371	401265.561	7020505.535	1398.474	LIMESTONE			Grab	Subcrop	1	0.05	11.2	61
1095372	401277.976	7020501.517	1402.707	LIMESTONE			Grab	Subcrop	1	0.05	19.2	36
1095373	401286	7020560	1400.517	Limestone	Gossan	Small area of subcrop, very gossanous,	Grab	Subcrop	1	0.05	2.2	26
1095374	401520.811	7020553.789	1459.148	LIMESTONE			Grab	Subcrop	1	0.1	1.3	25
1095377	399529.771	7022538.496	1357.314	INTRUSIVE DYKE			Grab	Outcrop	1	0.05	2.8	141
1095378	399699.817	7022149.418	1327.564	GREY WEATHERED BLACK SHALE			Grab	Outcrop	5	0.05	2.8	101
1095379	399746	7022184	1333.559	Shale		Chip sample accross slope NE-SW of grey	Chip	Subcrop	5	0.05	4.2	65
1095380	401977.829	7019530.199	1644.889	QPC			Grab	Outcrop	3	0.1	64.7	14
1095381	401977.935	7019526.297	1645.466	RUSTY SHALE			Grab	Outcrop	4	0.2	21.2	608
1095382	401503.596	7019744.501	1559.29				Grab	Outcrop	249	1.2	14	2
1095383	401455.404	7019685.274	1540.6	RHYOLITE DYKE			Grab	Outcrop	320	0.9	288.1	9
1095384	401337.952	7019650.338	1489.726	TAN WEATHERED SHALE			Grab	Outcrop	8	0.8	138.1	5058
1095385	401337.848	7019650.092	1489.565	Q			Grab	Outcrop	199	1.2	743.5	8273
1095386	401387.521	7019751.177	1490.921	a BLACK SHALE			Grab	Outcrop	10	0.8	57.5	15
1095387	401110.556	7019753.17	1447.106	BLACK SHALE	DES PYRITE	ORANGE GOSSAN	Grab	Outcrop	99	0.5	319.8	1750
1095388	401016.847	7019792.667	1440.081	BLACK SHALE	DES PYRITE	ORANGE GOSSAN	Grab	Outcrop	421	0.2	63.9	328
1095389	400994.237	7019799.53	1436.1	BLACK SHALE	DES PYRITE	ORANGE GOSSAN	Grab	Outcrop	4	0.5	375	4614
1095390	400969.656	7019852.929	1468.664	BLACK SHALE	DES PYRITE	ORANGE GOSSAN	Grab	Outcrop	3	0.8	154	2281
1095391	400990.669	7019845.87	1442.278	BLACK SHALE	DES PYRITE	ORANGE GOSSAN	Grab	Outcrop	158	1.3	196.9	793
1095392	403283.9	7016714.788	1611.643	BLACK SHALE	DES PYRITE	ORANGE GOSSAN	Grab	Outcrop	1	0.05	19.6	258
1095395	403373.86	7016713.164	1622.448	WEART	DES PYRITE	ORANGE GOSSAN	Grab	Outcrop	1	0.05	2.6	12
1095396	403372.846	7016715.335	1623.308	BLACK SHALE	DES PYRITE	ORANGE GOSSAN	Grab	Outcrop	1	0.05	1.2	14
1095397	403243.246	7016722.175	1613.431	BLACK SHALE	DES PYRITE	ORANGE GOSSAN	Grab	Outcrop	1	0.7	5.8	65
1095398	416017.355	7012040.123	1556.436				Grab	Outcrop	1	0.05	97.8	48
1095399	416004.643	7012064.849	1573.329	BLACK SHALE	PYRITE		Grab	Outcrop	1	0.05	18.8	47
1095400	416008.621	7012061.484	1573.458	GREENISH qzt	PYRITE		Grab	Outcrop	1	0.05	27.6	13
1095401	414334	7012611	1301			Manually added from Adam's Garmin			2.5	0.05	3	57
1095408	396051	7022523	1339			Manually added from Adam's Garmin			25	0	0	0

Sample	Easting	Northing	Elevation	Rock Type	Mineralization	Description	Style	Source	Au_FA_ppb	Ag_ppm	As_ppm	Zn_ppm
1095451	402917.684	7018515.456	1569.379				Grab	Outcrop	12	0.05	13.4	28
1095452	402896.238	7018502.181	1567.862				Grab	Outcrop	11	0.05	26.4	10
1095453	402908.105	7018508.888	1566.141	VOLCANIC CLASTIC	HEM		Grab	Outcrop	2.5	0.05	27.3	71
1095454	402835.094	7018563.238	1551.304	VOLCANIC CLASTIC	DES Pyrite		Grab	Outcrop	2.5	0.05	5	19
1095455	402773.548	7018543.378	1541.482				Grab	Outcrop	2.5	0.05	5.4	17
1095456	402937.915	7018373.269	1634.584	GREY LIMY BRECIA	Y		Grab	Outcrop	2.5	0.1	19.7	9
1095458	402949.97	7018370.07	1640.381				Grab	Outcrop	2.5	0.3	70.6	29
1095459	403018.373	7018153.446	1612.172	GFEEN Calcite			Grab	Float	2.5	0.2	17.9	473
1095460	403045.055	7018152.371	1594.998	GREY LIMY	<A		Grab	Outcrop	2.5	1.5	11.2	40
1095461	403236.424	7018355.889	1578.924				Grab	Outcrop	2.5	0.6	38.5	523
1095462	407054.641	7017289.461	1679.074	DBS QZT STRINGERS			Grab	Outcrop	2.5	0.1	8.9	121
1095464	413180.403	7021228.65	1701.836	LIMESTONE			Chip	Outcrop	2.5	0.05	3.1	5
1095466	413154.72	7021205.352	1703.197	QZT VEIN			Grab	Outcrop	2.5	0.1	3.6	69
1095467	413134.054	7021169.074	1702.652	Black sHALE	HEM		Grab	Outcrop	6	0.2	6.6	12
1095468	413113.467	7021166.846	1693.896	VUGGY HEM QZT VEIN	des pyrite		Grab	Outcrop	2.5	0.1	7.6	99
1095469	412947.338	7021188.069	1637.435				Grab	Outcrop	2.5	0.05	2	5
1095470	412944.211	7021198.882	1636.386				Grab	Outcrop	2.5	0.05	2.6	6
1095471	412914.391	7021204.75	1615.067				Grab	Outcrop	20	0.9	6.1	117
1095472	412398.601	7020784.12	1398.638	LIMESTONE	HEM		Chip	Outcrop	2.5	0.05	3.1	7
1095473	412340.102	7021009.748	1387.204				Grab	Outcrop	2.5	0.2	7.9	58
1095475	414412.681	7012673.353	1563.947	QZT VEIN			Grab	Outcrop	5	0	0	0
1095476	414409.021	7012682.859	1563.217	CHERT			Grab	Outcrop	1	0	0	0
1095477	414407.242	7012685.453	1562.723	VOLCANICS			Grab	Outcrop	4	0	0	0
1095478	414274.276	7012821.928	1556.99	VOLCANIC			Grab	Outcrop	1	0	0	0
1095479	414277.573	7012766.167	1557.898	VOLCANICs			Grab	Outcrop	1	0	0	0
1095480	414335.912	7012632.723	1552.787	QZT			Grab	Outcrop	1	0	0	0
1095481	414347.252	7012630.315	1552.73				Grab	Outcrop	2	0	0	0
1095485	414601.455	7012589.372	1562.246	QZT VEIN	QZT VEIN		Grab	Outcrop	32	0	0	0
1095486	414604.753	7012607.142	1559.555				Grab	Outcrop	145	0	0	0
1095487	414712.377	7012723.874	1501.6				Grab	Outcrop	3	0	0	0
1095488	414724.261	7013060.836	1626.053				Grab	Outcrop	1	0	0	0
1095489	414868.245	7013129.455	1648.734	MIX			Grab	Outcrop	1	0	0	0
1095490	414811.449	7013066.177	1646.754	ORAMGD GOSSAN			Grab	Outcrop	1	0	0	0
1095491	414809.037	7013069.463	1639.03	Black sHALE	HEM		Grab	Outcrop	1	0	0	0
1095492	414137.304	7012817.723	1517.221	VOLCANIC FLOAT			Grab	Outcrop	1	0.05	1.4	116
1095493	414138.176	7012467.957	1517.564	SHALE			Grab	Outcrop	1	0.1	2	15
1095494	414880.758	7013413.232	1661.604				Grab	Outcrop	1	0.05	17	38
1095497	414929.466	7013359.551	1684.728	VOLCANICS			Grab	Outcrop	1	0.05	1.2	12
1095498	414972.004	7013319.152	1694.067				Grab	Outcrop	1	0.05	1.4	20
1095499	415512.605	7013166.994	1701.349	VOLCANICS			Grab	Outcrop	1	0.05	2.9	273
1095500	415571.706	7013184.936	1696.463	VOLCANICS ??			Grab	Outcrop	1	0.05	0.5	16
1095906	394268.598	7020868.824	1404.945	qtz arg kst	azurite		Grab	Outcrop	1	1.9	53.4	322
1095951	401445	7019118	9998.485	Qtz-carb	Qtz-carb, ankerite	Quartz-carb subcrop & abund ankerite.	Grab	Subcrop	8	0.1	27.7	19
1095952	401610	7019306	9998.486	Mudstone		Qtz vein in minor sil mudstone, minor	Chip	Subcrop	1	0.2	12.6	242
1095953	401610	7019306	9998.486	Limetstone		1m banded limestone adjacent to	Grab	Outcrop	1	0.4	22	292
1095954	401589	7019301	9998.486	Quartz Vein		Second qtz vein below 1095952, 50cm x	Chip	Outcrop	1	0.8	18.6	819
1095955	399529	7022543	1375.565	Intrusive		Altered intrusive	Grab	Outcrop	1	0.05	4.7	118
1095956	394979	7021257	1553.54	Intrusive		Rusty altered intrusive dyke in black	Grab	Outcrop	2	0.05	16.3	288
1095957	402918	7018323	9998.457	Conglomerate		Calcareous conglomerate, orange	Grab	Subcrop	1	0.05	139.1	21
1095958	399360	7016759	9998.489	Rhyolite	Trace grey sulphide	Buff qtz-bt rhyolite, clay altn & suggary	Grab	Subcrop	62	0.05	584	48
1095961	399294	7016956	9998.493	Rhyolite	Py?	Rusty weathering buff qtz-bt rhyolite	Grab	Outcrop	1	0.1	2101.1	200
1095962	396983.037	7018425.774	1028.16	SDs black silty limestone	rusty patch after	finally some rock with a bit of staining	Grab	Outcrop	14	0.05	33.1	164
1095963	396978.175	7018450.439	1033.137	BLACK SHALE	rusty stain	rusty stain layer 30cm wide	Grab	Outcrop	2.5	0.2	78.9	514
1095964	401375	7020210	1541.506	Breccia		Pale grey & green breccia, qtz veins,	Grab	Outcrop	35	1.1	1243.3	162
1095965	403226.175	7019791.39	1686.526	black shale conglomerate	hematite	float within limestone	Grab	Outcrop	2.5	4.4	78.4	1230
1095966	401375.593	7020216.961	1546.788	black silicious shale			Grab	Outcrop	2.5	0.4	22.2	5
1095967	401593.637	7021178.312	1216.253	felsite float		buff-orange felsite chips to 5 cm in talus	Grab	Float	6	0.3	80.4	75
1095968	401600.628	7021131.731	1228.866	felsite float			Grab	Float	3	0.2	231	71
1095969	401512.508	7020834.11	1318.668	quartzite, limey quartzite	iron staining, minor		Grab	Subcrop	1	0.05	12.4	4
1095970	401560.358	7020924.388	1308.617	quartzite, orange weathering	10% quartz	1.5 x 0.3 m exposure	Grab	Outcrop	1	0.05	1.6	27
1095971	401057.678	7019844.203	1472.249	quartz vein in scree	minor stibnite?	selected qtz frags in scree	Grab	Float	1	0.1	102.9	119
1095972	401058.228	7019844.637	1472.544	Felsite, clay altd	FeOx srn, minor	rusty felsite, white on fresh, qtz eyes,	Grab	Float	5	0.2	209.2	3
1095973	401058.836	7019884.264	1473.372	black shale with quartz veins	minor fx sulphides ?	selected quartz vein fragments in black	Grab	Float	142	1	32.2	4
1095974	401040.43	7019913	1462.569	black shale with quartz veins	FeOx & scorodite	shale very carbonaceous	Grab	Subcrop	64	0.7	55.3	5
1095975	400967.915	7019816.874	1433.663	porous buff orange siltstone		could be decalcified sapper formation ?	Grab	Float	3	0.9	88.9	8821
1095976	400995.202	7019792.92	1427.784	Rusty broken shale breccia	FeOx	selected from scree	Grab	Outcrop	31	0.6	313.2	1530
1095977	400991.905	7019780.447	1422.484	Orange weath porous siltstone			Grab	Float	4	0.5	207.2	4638
1095978	403806.274	7016504.408	1489.424	Limestone; buff orange	qtz veins 5%	fine grained, buff orange	Grab	Subcrop	2	0.05	2.2	22
1095979	403824.041	7016488.397	1483.823	dolomitic limestone; orange we		fine grained dolomitic limestone; 5%	Grab	Float	6	0.05	2.2	51

Sample	Easting	Northing	Elevation	Rock Type	Mineralization	Description	Style	Source	Au_FA_ppb	Ag_ppm	As_ppm	Zn_ppm
1104435	403166.735	7018632.813	1541.77	Quartz Vein	None	Qtz vein running 045 degrees rubble	Grab	Subcrop	1	0.05	4.7	3
1104436	403177.999	7018348	1616.698	Dv		Carbonate stained Dv with qtz veins	Grab	Outcrop	2	0.05	258.4	23
1104437	403343.999	7018596.001	1507.696	Shale		Rubbly grey weathering Sapper with	Grab	Subcrop	1	0.3	11.3	111
1277555	407338.696	7020590.765	1567.667	Silty Sandstone	Minor dissem py	Composite sample over 25m	Chip	Outcrop	4	0.05	0.25	32
1277556	407338.052	7020592.789	1567.937	Black Shale		Composite sample over 25m along	Chip	Outcrop	6	0.4	1.8	92
1277557	407325.619	7020729.596	1579.946				Grab	Outcrop	6	0.2	7	64
1277559	406907	7020813	9999	Rhyolite dyke		Small rhyolite dyke	Grab	Outcrop	17	0.05	73.4	40
1277560	406903	7020881	1451	Silty Sandstone		Orange rusty gossanous sandy siltstone	Chip	Outcrop	1	0.05	0.6	61
1277562	407007.681	7021090.673	1360.767				Grab	Outcrop	4	1.1	24.5	1833
1277569	406817.017	7017732.519	1613.87				Grab	Outcrop	1	0.05	14.5	97
1277570	412286.473	7016413.026	1474.157	CHERTY SHALE	HEM		Grab	Outcrop	6	0.7	95.5	60
1277571	412247.683	7016425.313	1476.594	Black sHALE	yellow /GREEN		Grab	Outcrop	37	1.1	307.2	7
1277572	412159.283	7016395.711	1518.43	GREY WEARTERD SH			Grab	Outcrop	10	1.2	23.9	6
1277573	412011.049	7016454.763	1558.151	GREY WEATHERED BLACK SHALE			Grab	Outcrop	6	1.8	59.7	21
1277574	411636.964	7016369.192	1557.256	GREY WEATHERED BLACK SHALE	hem		Grab	Outcrop	1	0.9	65.5	1283
1277575	411468.613	7015583.751	1594.228	SILTY SS			Grab	Outcrop	1	0.05	19.4	70
1277576	411806.497	7015564.534	1542.901	SILTY SS			Grab	Outcrop	1	0.05	4.6	21
1277577	411880.224	7015593.738	1518.11				Grab	Outcrop	1	0.05	5.3	13
1277578	411738.535	7015537.781	1532.825				Grab	Outcrop	1	0.05	5.1	102
1277579	411741.687	7015533.529	1532.317				Grab	Outcrop	1	0.05	17.1	62
1277586	416651.281	7012912.296	1820.109	ALT SS			Grab	Outcrop	1	0.05	22.3	480
1277587	416672.393	7012910.061	1825.377				Grab	Outcrop	1	0.1	4.8	8
1277588	416671.305	7012912.937	1826.541				Grab	Outcrop	3	0.1	21.1	364
1277589	416776.244	7012981.981	1876.238	SILTY SS			Grab	Outcrop	1	0.2	9.2	474
1277590	416765	7012975	1877	Black Shale	Hematite	Thinly foliated black shale	Chip	Subcrop	1	0.1	6.1	191
1277591	416888	7013137	1809.352	Shale	hem	Black shale o/c, very hematitic, some	Grab	Outcrop	3	0.3	10.1	96
1277592	416897.562	7013199.791	1766.421	SAPPER			Grab	Outcrop	1	0.05	7	136
1277593	416966.507	7013411.785	1726.889	SS			Grab	Outcrop	1	0.05	59.2	138
1277594	416950	7013525	1700	Qtz breccia	Hematitic	Thin band of hematitic qtz breccia	Chip	Subcrop	10	0.9	171.2	356
1277595	416955.398	7013527.191	1699.589	Shale		Grey shale cutting sandstone	Grab	Outcrop	1	0.05	1.5	30
1277596	416865.832	7013450.341	1647.435				Grab	Outcrop	18	0.9	10.3	40
1277597	416416.092	7013518.438	1490.355				Grab	Outcrop	3	0.1	20.1	47
1277598	414238.866	7012839.13	1543.646	VOLCANICS			Grab	Outcrop	1	0.05	52.1	114
1277599	414195.791	7012914.51	1525.938	VOLCANICS			Grab	Outcrop	1	0.05	27.8	59
1277600	414158.479	7012922.06	1510.007	VOLCANICS			Grab	Outcrop	1	0.05	129.7	68
1279051	415443.462	7012629.722	1458.766	TAN WEATHERED BLACK SHALE	DES PYRITE		Chip	Outcrop	2.5	0.15	12	202
1279052	415444.654	7012630.055	1454.334	TAN WEATHERED GREY SS	DES PYRITE		Grab	Outcrop	2.5	0.15	6	164
1279053	415427.379	7012621.896	1451.064	TAN WEATHERED GREY SS	DES PYRITE		Grab	Outcrop	20	0.15	3	169
1279054	415424.519	7012618.756	1449.473	TAN WEATHERED BLACK SHALE	DES PYRITE		Grab	Outcrop	2.5	0.15	1	102
1279055	415411.489	7012336.314	1454.499	VOLCANIC SILL/DYKE	DES PYRITE		Chip	Outcrop	2.5	0.15	168	84
1279056	415368.042	7012346.967	1445.447	VOLCANIC SILL/DYKE	DES PYRITE		Grab	Subcrop	2.5	0.15	22	69
1279057	415135.35	7012462.656	1405.54	VOLCANIC SILL/DYKE	DES PYRITE		Grab	Subcrop	2.5	0.15	101	59
1279058	415069.215	7012496.529	1414.69	VOLCANIC SILL/DYKE	DES PYRITE		Grab	Subcrop	6	0.15	102	94
1279059	415069.087	7012496.76	1422.855	QZT Veining			Grab	Subcrop	2.5	0.15	14	37
1279060	415054.085	7012405.571	1383.273	VOLCANICS		FLOAT?	Grab	Subcrop	2.5	0.15	178	68
1279061	415921.389	7012074.699	1545.206	LISTOMITE			Grab	Outcrop	1	0.05	150.4	74
1279062	415778.581	7012099.05	1496.849	LISTONITE	deS PYRITE		Grab	Subcrop	1	0.05	53.8	137
1279063	402907.272	7016884.373	1657.569	SHALE SaPPER	DeS PYRITE		Grab	Float	4	0.2	227.4	30
1279064	402832.977	7017040.002	1681.189	SHALE SaPPER	DeS PYRITE		Grab	Float	1	0.05	36.9	23
1279065	402782.287	7017110.844	1695.804	SHALE SaPPER	DeS PYRITE		Grab	Float	3	0.2	26.2	51
1279066	402693.61	7017219.339	1705.706	QZT	c		Grab	Float	1	0.05	7.5	11
1279067	402693.514	7017223.362	1707.31	BLACK SHALE	c		Grab	Float	1	0.1	6.3	26
1279068	402611.67	7017362.722	1704.969	BLACK SHALE	c		Grab	Float	1	0.1	9	55
1279069	402710.515	7017291.919	1675.794	BLACK SHALE	c		Grab	Float	2	0.4	9.9	36
1279070	402742.409	7017288.707	1643.664	BLACK SHALE	c		Grab	Float	4	0.6	13.2	50
1279071	402800.039	7017236.855	1636.786	BLACK SHALE	c		Grab	Float	4	1	41.3	171
1279072	402853.474	7017145.252	1614.72	BLACK SHALE	c		Grab	Float	3	0.3	9.6	43
1279073	402963.393	7017335.493	1612.484	GREY SHALE /QZT	c		Grab	Float	1	0.05	11.3	124
1279074	402900.196	7017354.419	1580.681	GREY SHALE /QZT	c		Grab	Float	3	0.2	10.1	587
1279075	402896.523	7017365.74	1582.237		GREY LIMESTONE		Grab	Float	1	0.05	2	92
1279076	402888.553	7017369.102	1566.182		GREY LIMESTONE		Grab	Float	1	0.05	1.4	76
1279077	402880.467	7017368.629	1578.496	GREY IIMESTONE /SHALE BRECCIA	GREY LIMESTONE		Grab	Float	1	0.05	2.7	162
1279079	402830.255	7017395.459	1551.402	BLACK SHALE	very HEM		Grab	Float	11	0.5	18.4	60
1279080	402822.825	7017400.858	1539.734	BLACK SHALE	very HEM		Grab	Float	12	0.7	78.2	180
1279081	402877.983	7017440.463	1511.143	CALCITe	very HEM		Grab	Float	2	0.05	16.8	64
1279082	404053.646	7021006.731	1436.917	SILTY SANDSTONE	minor des PYRITE	DYKE?	Grab	Float	16	0.4	112.5	272
1279083	404101.307	7021015.777	1432.974	SILTY SANDSTONE	minor des PYRITE	DYKE?	Grab	Float	3	0.3	31	491
1279084	404137.148	7020968.596	1425.15	SILTY SANDSTONE	minor des PYRITE	DYKE?	Grab	Float	6	0.2	35.7	154
1279085	404165.055	7020937.008	1422.469	BLACK SHALE			Grab	Float	8	0.7	16.7	129

Sample	Easting	Northing	Elevation	Rock Type	Mineralization	Description	Style	Source	Au_FA_ppb	Ag_ppm	As_ppm	Zn_ppm
1279086	404160.048	7020961.405	1447.632	SILTY SANDSTONE!			Grab	Float	4	0.2	11	207
1279087	404176.223	7020920.065	1419.149	SILTY SANDSTONE!			Grab	Float	30	0.2	45.7	92
1279088	403857.393	7020913.469	1491.965	SILTY SANDSTONE!			Grab	Float	1	0.05	18.1	72
1279089	403847.459	7020931.041	1492.397	SILTY SANDSTONE!			Grab	Float	4	0.2	273.2	76
1279090	403827.349	7020959.64	1491.501	SILTY SANDSTONE!			Grab	Float	1	0.1	6	79
1279091	403812.993	7020959.369	1491.625	BLACK SHALE			Grab	Float	12	0.8	8.1	88
1279092	403802.155	7020953.923	1492.231	SILTY SANDSTONE			Grab	Float	1	0.05	2.5	22
1279093	404011.106	7020809.581	1512.852	SILTY SANDSTONE			Grab	Float	7	0.3	8.7	93
1279094	404020.26	7020765.705	1503.025	SILTY SANDSTONE			Grab	Float	13	0.05	177.7	76
1279095	404029.615	7020883.576	1456.555	SILTY SANDSTONE			Grab	Float	5	0.2	217.1	49
1279096	407051.114	7017345.536	1694.611	VOLCANICS			Grab	Outcrop	1	0.05	3.8	43
1279097	407030.963	7017353.994	1707.542	VOLCANICS			Grab	Outcrop	1	0.05	11.6	48
1279098	406961.686	7017391.459	1725.331	VOLCANICS			Grab	Outcrop	1	0.05	3.6	16
1279099	406838.185	7017417.78	1754.5	VOLCANICS			Grab	Outcrop	1	0.05	2.7	14
1279100	406846.214	7017431.39	1755.658	BLACK SHALE	des PYRITE		Grab	Outcrop	1	0.3	34	82
1279205	401084.45	7019831.936	1476.338			T2011-08 207-210m	Chip	Outcrop	2	0.5	24.5	23
1279206	401081.873	7019830.089	1475.595			T2011-08 210-213m	Chip	Outcrop	1	0.5	42	5
1279302	396582.684	7023126.239	1374.101	qtz vien			Grab	Float	1	0.05	1.2	47
1279303	396569.986	7023122.444	1374.027	shale , weakly ferrugenous		fissile thinly bedded bk shale	Grab	Outcrop	1	0.05	15.2	46
1279304	396819.95	7023332.019	1274.381	qt carbonate ??		extremely vuggy.porous	Grab	Float	1	0.05	3.4	33
1279306	396608.999	7022436	1664.655	quartzite		gy-bn quartzite with wh qtz flooding;	Grab	Subcrop	1	0.05	151.1	25
1279307	396636	7024424	1688.664	quartzite		lt gy fg fresh quartzite joint set 282/80	Grab	Outcrop	36	0.05	349	62
1279308	396662.001	7022400.999	1681.656	quartzite		buff orange weathering; limonite	Grab	Float	35	0.05	139.6	14
1279309	396613.001	7022401	1685.655	quartzite		gy weathering-wh weathering	Grab	Outcrop	2	0.05	16.8	3
1279313	401384.321	7020023.389	1615.425	felsic intrusive dyke	realgar in vertical	at contact with bedded fissile shale	Grab	Outcrop	335	9.2	10000	121
1279315	401044.959	7016471.366	1650.266	conglomerate			Grab	Subcrop	1	0.3	5.4	3
1282451	401373.457	7019996.643	1598.533	Intrusive	Realgar & orpiment		Grab	Outcrop	908	38.8	1251.2	73
1282452	401375.455	7020218.044	1541.397	Qtz veined			Grab	Float	25	0.8	913.9	111
1283501	406752.332	7017486.655	1752.558	VOLCANICS	des PYRITE		Grab	Outcrop	1	0.05	2.2	30
1283502	406751.29	7017512.36	1761.236	VOLCANICS	des PYRITE		Grab	Outcrop	1	0.4	6.2	50
1283503	406715.357	7017521.654	1762.319	VOLCANICS	des PYRITE		Grab	Outcrop	1	0.05	2.1	67
1283504	406697.529	7017543.259	1762.314	VOLCANICS	des PYRITE		Grab	Outcrop	1	0.05	36.7	15
1283505	406634.109	7017562.708	1783.89	VOLCANICS	des PYRITE		Grab	Outcrop	1	0.05	1.7	22
1283506	406471.635	7017577.225	1740.182	QZT VEIN	des PYRITE		Grab	Outcrop	1	0.05	8.6	18
1283507	406445.501	7017580.797	1715.8	QZT VEIN	des PYRITE		Grab	Outcrop	1	0.05	3	44
1283508	406414.584	7017581.784	1708.854	QZT VEIN			Grab	Outcrop	1	0.05	1.2	5
1283509	406383.763	7017587.771	1690.011	VOLCANICS			Grab	Outcrop	1	0.05	9.1	33
1283510	406317.882	7017570.466	1665.95	QZT VEIN$			Grab	Outcrop	1	0.05	0.9	43
1283511	406253.039	7017560.139	1669.659	QZT VEIN$			Grab	Outcrop	1	0.05	3	23
1283512	417657.742	7014893.417	1770.522	GREY SHALE		QZT Veining	Grab	Float	1	0.5	4.9	267
1283513	417665.856	7014959.314	1787.04	BLACK SHALE	hem		Grab	Float	70	0.05	5.5	199
1283514	417686.056	7014956.756	1792.398	BLACK SHALE	hem		Grab	Float	6	0.5	12	346
1283515	417691.838	7015023.789	1802.958	QZT VEIN	hem		Grab	Float	1	0.05	2.4	105
1283516	417709.511	7015065.084	1809.363	QZT VEIN	hem	QZT VEIN	Grab	Float	1	0.2	13.4	67
1283517	417629.068	7014798.117	1771.138	VOLCANICS CPC		QZT VEIN	Grab	Float	1	0.05	4	170
1283518	417637.109	7014790.318	1770.195	VOLCANICS	DES PYRITE	QZT VEIN	Grab	Float	5	0.05	104.6	69
1283519	417611.569	7014777.073	1771.473	VOLCANICS	DES PYRITE	QZT VEIN	Grab	Float	1	0.05	5.4	68
1283520	417604.496	7014771.376	1770.927	VOLCANICS		QZT VEIN	Grab	Float	1	0.05	0.25	10
1283521	417600.44	7014770.042	1770.16	VOLCANICS		QZT VEIN	Grab	Float	1	0.05	0.25	7
1283522	417580.672	7014749.315	1770.404	VOLCANICS		QZT VEIN	Grab	Float	1	0.05	11.3	10
1283523	417647.354	7014795.508	1753.928	VOLCANICS		QZT VEIN	Grab	Float	1	0.05	3.3	64
1283524	417496.272	7014660.398	1724.696	LIMY	SHALE	QZT VEIN	Grab	Float	1	3.3	36.9	105
1283525	417644.487	7014536.303	1686.83	SHALE	HEM	QZT VEIN	Grab	Float	1	1.2	162.8	471
1283526	417665.173	7014524.023	1684.7	SHALE	HEM	QZT VEIN	Grab	Float	1	0.4	134.6	103
1283527	417620.856	7014459.656	1664.993	QZT VEIN	HEM	QZT VEIN	Grab	Float	1	0.05	5.3	18
1283528	417681.6	7014386.908	1661.765	QZT VEIN	HEM	QZT VEIN	Grab	Float	1	0.2	3.7	68
1283529	417691.176	7014374.618	1654.336	VOLCANICS		QZT VEIN	Grab	Float	1	0.1	0.7	84
1283530	417702.713	7014361.788	1645.067	VOLCANICS		QZT VEIN	Grab	Float	1	0.1	1.2	109
1283531	413914.357	7012822.606	1422.038	VOLCANICS	DES PYRITE		Grab	Outcrop	2.5	0.15	1	89
1283532	413880.776	7012838.76	1414.117	VOLCANICS	DES PYRITE		Grab	Outcrop	2.5	0.15	2	148
1283533	413784.166	7012921.478	1405.318	VOLCANICS			Grab	Outcrop	2.5	0.15	60	58
1283534	413784.899	7012921.614	1404.389	VOLCANICS	DES PYRITE		Grab	Outcrop	71	0.15	54	69
1283535	413765.099	7012923.059	1389.912	VOLCANICS	DES PYRITE		Grab	Outcrop	2.5	0.15	109	143
1283536	413688.75	7012848.177	1357.783	VOLCANICS	DES PYRITE		Grab	Outcrop	2.5	0.15	23	73
1283537	413750.573	7012854.094	1366.422	VOLCANICS	DES PYRITE		Grab	Outcrop	2.5	0.15	64	75
1283538	413723.876	7012869.692	1366.034	VOLCANICS	DES PYRITE		Grab	Outcrop	2.5	0.15	15	104
1283539	413775.542	7012752.414	1371.646	VOLCANICS	DES PYRITE		Grab	Outcrop	9	0.15	5	229
1283548	411392.616	7014675.163	1510.58	VOLCANICS			Grab	Outcrop	1	0.05	0.25	18
1283549	411385.675	7014728.467	1511.557	VOLCANICS		Hem	Grab	Outcrop	1	0.05	4	10

Sample	Easting	Northing	Elevation	Rock Type	Mineralization	Description	Style	Source	Au_FA_ppb	Ag_ppm	As_ppm	Zn_ppm
1285001	402772	7016822	1663.4	Chert	None	Talus At contact to N with buff-	Grab		1	0.3	11	38
1285002	402736	7016800	1662.2	Shales/Cherts	None	Still mostly in cherts but interbedded	Grab		2	0.4	6.9	83
1285003	402635	7016734	1641.1	Breccia	None	On a scree slope (shale & chert) there are	Grab		1	0.1	15.6	26
1285004	402629	7016731	1644	Breccia	None	Same loc'n but with graphitic shale. But	Grab		1	0.2	7.4	19
1285005	402621	7016593	1612.5	Quartz	None	Went along elevation looking for more	Grab		1	0.05	1.1	4
1285006	402504	7016457	1528.1	Limonite	None	Talus, previously a shale.	Grab		7	2.6	14.1	1359
1285007	404252	7020806	1406	Shales	None	Talus A lot of tan weathering soft seds	Grab		11	0.1	12.1	66
1285008	404144	7020512	1487.3	Shales	None	Talus Brown shales partially silicified	Grab		110	0.05	10.2	128
1285009	404061	7020490	1537.7	Agglomerate	Up to 5% hematite	seds Looks calcareous but isn't	Grab		2	0.05	187.5	20
1285010	404065	7020423	1553.1	Limonite	Barite	Grizzly bear there was interested in	Grab		1	0.2	736.5	10
1285011	406765	7018038	1575.7	Qtz-carb	None	O/C limestone with qtz-carb vein,	Grab		1	0.05	3.5	37
1285013	419158	7014158	1488.5	Dolomite(?	Very minor	Dug several angular pieces out of moss	Grab		1	0.05	33.5	124
1285014	419154	7014167	1486.1	Dolomite(?	Pyrite/pyrrhotite 1-	Right! Take a sample, thdrash through a	Grab		1	0.05	6.7	124
1285015	419468	7014009	1411.1	Siltstone	None	Dot-on-map sample Completely snoozy	Grab		1	0.1	9.5	216
1285016	419177	7013989	1461.8	Shales	None	Another dot Felsemer dug out of hillside	Grab		1	0.05	1	95
1285017	419124	7014052	1476.9	Shales/Qtz	None	Yet anotheer dot Bits and pieces of	Grab		1	0.1	5.1	113
1285018	415660	7013314	1684.1	Some sed	None	Weakly calcareous with calcite stringers	Grab		1	0.05	1.7	13
1285019	415517	7013225	1672.1	Volcs	approx 1% pyrite	Talus Dyke material	Grab		1	0.05	1.4	13
1285020	415286	7013149	1683.1	Breccia	None	Talus Lots of conglomerate here and	Grab		1	0.2	10.3	17
1285021	415214	7013217	1658.1	Quartz	None	Talus, locally common Quartz vein	Grab		2	0.8	13.4	456
1285022	415183	7013259	1658.6	Quartz	None	Talus Not much of it unfortunately Am	Grab		2	0.5	18.4	5635
1285023	414943	7013594	1580.5	Calc-silicate	None	Subcrop of seds width calc-sillicate vein	Grab		1	0.05	1.4	39
1285024	414917	7013616	1582.2	Dolomite	Sphalerite(?)	Talus Orange weathering grey dolomite	Grab		3	0.1	6	3208
1285025	414976	7013713	1576.4	Calc-silicate	None	Talus Most of white is plain calcite but	Grab		1	0.05	1	27
1285026	414950	7014010	1577.9	Shale	None	Subcrop Sheared shales 270 but variable	Grab		6	0.9	4.7	92
1285027	411513	7015482		Quartz	None	Felsemer Area is sheared shales,			1	0.05	7.8	42
1285028	411498	7015610		Quartz	None	Felsemer/talus			1	0.05	1	39
1285029	411586	7015840		Shale	None	Felsemer Shale with a stockwork of			2	0.05	1.4	38
1285030	411629	7015837		Shale	None	Felsemer Shale with a stockwork of			1	0.05	3.3	8
1285031	411316	7015750		Calc-silicate	None	Talus Vein material(?) Most of limey			1	0.05	9	28
1285032	411397	7015832		Conglomerate	None	Subcrop or float(?) Narrow (1-2 cms.			1	0.05	1.6	44
1285033	411474	7016002		Quartz	None	Talus Bits and pieces of quartz mixed in			1	0.05	8.6	88
1285034	400697	7020147		Dv	None	Volcanic dyke material from soil hole			12	0.3	36.7	3
1285035	400903	7019977		Shale	None	Talus beside soil hole 1091073 Weakly			113	1.2	344	2149
1285036	400897	7020648		Dv	Pyrite	Near soil 1091098 A narrow gulley (SE-			26	0.7	167.5	151
1285037	405846	7019208		Conglomerate	None	Felsemer Silicious, weakly limonitic			5	0.4	13.2	10
1285038	405674	7019191		Barite	None	O/C A narrow (10-15 cms. Wide) band of			1	0.05	6.2	28
1285039	405513	7019476		Chert	None	Graphitic, 5-7% quartz Very common in			1	1.8	1.1	5
1285040	405557	7019244		Barite	None	Subcrop 310/90 Weakly limonitic			4	0.8	12.3	27
1285041	405419	7019614		Shale	None	Subcrop Sheared graphitic shales with			1	0.2	2.7	2
1285042	400698	7020151		Conglomerate	None	Talus Cong. With qtz. Stringers			240	0.7	56.3	6
1285043	401373	7019783		Dyke	None	Subcrop Dyke material, small exposure			31	1.4	38.8	4
1285044	401466	7019760		Conglomerate	None	Talus Cong. With qtz stringers Weakly			20	0.7	10.7	3
1285045	401677	7019707		Conglomerate	None	Felsemer A little of it is rusty weathering			57	0.7	222.6	2
1285046	401846	7019621		Conglomerate	None	Talus although just below o/c Cong.			15	0.4	16.2	5
1285047	401925	7019603		Conglomerate	None	Something happening here Thought			49	0.3	22.8	6
1285048	401926	7019600		Conglomerate	None	Talus Moderately limonitic, minor clay			17	0.5	35.1	12
1285049	402000	7019558		Conglomerate	None	90% white quartz			38	0.5	8	0.5
1285050	401963	7019522		Conglomerate	None	Subcrop With qtz. Veinlets approx 1 cm.			3	0.2	21.9	174
1285251	411377.243	7014747.199	1511.82	VOLCANICS		Hem	Grab	Outcrop	1	0.05	10.4	18
1285252	411431.234	7014750.371	1509.093	BECCICA/CPC		Hem	Grab	Outcrop	1	0.05	9.8	13
1285253	411315.164	7014785.192	1503.29	VOLCANICS		Hem	Grab	Outcrop	3	0.05	51.5	37
1285254	411283.684	7014823.519	1497.9	VOLCANICS		Hem	Grab	Outcrop	1	0.05	0.6	6
1285256	411549.62	7014749.303	1489.173	VOLCANICS		Hem	Grab	Outcrop	1	0.05	2.2	44
1285257	411266.523	7014846.828	1472.36	VOLCANICS		Hem	Grab	Outcrop	1	0.05	3.4	47
1285258	411270.037	7014868.168	1469.57	VOLCANICS		Hem	Grab	Outcrop	1	0.05	0.8	84
1285259	403350.136	7019292.826	1692.377	SILTY LIMESTONE			Grab	Outcrop	39	0.1	25.6	17
1285260	403338.275	7019290.33	1692.37	BLACK SHALE	DES PYRITE		Grab	Outcrop	6	0.4	3.1	48
1285261	403406.445	7019288.988	1697.382	BLACK SHALE	DES PYRITE		Grab	Outcrop	10	0.5	3.1	53
1285262	403401.12	7019296.997	1700.304	BLACK SHALE/SILTY LIMESTONE	DES PYRITE		Grab	Outcrop	1	0.2	2.6	33
1285263	403287.618	7019318.483	1678.617	SILTY LIMESTONE			Grab	Outcrop	26	0.05	26.3	61
1285264	403284.639	7019320.657	1688.915	BLACK SHALE			Grab	Outcrop	18	0.8	3.5	35
1285265	402889.153	7019207.236	1513.361	CPC	DES PYRITE		Grab	Outcrop	1	0.4	65.3	18
1285266	402881.062	7019215.287	1511.981	CPC	DES PYRITE		Grab	Outcrop	2	0.3	58.6	56
1285267	402895.565	7019185.094	1519.487	CPC	DES PYRITE		Grab	Outcrop	11	0.3	37.6	18
1285268	402895.241	7019184.282	1520.27	BARITE			Grab	Outcrop	10	0.1	28.8	11
1285269	402912.279	7019199.126	1520.994	BLACK SHALE			Grab	Outcrop	3	0.9	39.8	51
1285270	402866.478	7019235.584	1522.936	Qzt vein			Grab	Outcrop	1	0.2	21	8
1285272	399878	7022867	1371	Felsic Dyke	Dissem Py	Limonitic	Grab	Outcrop	45	0.05	33.9	6

Sample	Easting	Northing	Elevation	Rock Type	Mineralization	Description	Style	Source	Au_FA_ppb	Ag_ppm	As_ppm	Zn_ppm
1285273	399850.664	7022878.813	1368.869	QZTITE	dES PYRITE		Grab	Outcrop	17	0.2	34.5	7
1285274	399839.754	7022876.963	1366.033	FELSIC DYKE	dES PYRITE		Grab	Outcrop	44	0.2	52.5	2
1285275	399823.351	7022880.991	1363.577	FELSIC DYKE	dES PYRITE		Grab	Outcrop	19	0.5	36.7	3
1285276	399866.891	7022876.072	1369.233	FELSIC DYKE	dES PYRITE		Grab	Outcrop	29	0.3	57.9	2
1285277	399871.3	7022872.659	1370.392	FELSIC DYKE	dES PYRITE		Grab	Outcrop	4	0.1	11	5
1285278	399878.453	7022865.692	1371.649	FELSIC DYKE	dES PYRITE		Grab	Outcrop	17	0.2	17.2	2
1285291	399667.241	7016671.785	1610.168	QZT VEIN FLOAT			Grab	Float	1	0.05	1.7	121
1285292	399531.585	7016809.362	1543.791	QZT VEIN FLOAT			Grab	Float	1	0.05	21.7	207
1285293	399355.569	7016764.112	1533.585	RHYOLITE			Grab	Outcrop	5	0.05	398.1	47
1285294	399321.202	7016877.277	1411.44	RHYOLITE			Grab	Outcrop	132	0.3	631.2	66
1285295	399311.849	7016918.276	1416.488	RHYOLITE/BLACK SHALE		CONTACT GRUNGE	Grab	Outcrop	8	1.2	117.5	106
1285296	399306.816	7016942.732	1408.298	RHYOLITE/			Chip	Outcrop	37	0.05	1276.8	145
1285297	399278.844	7016935.387	1406.346	RHYOLITE/	MAGANESE		Chip	Outcrop	10	0.3	258.3	240
1285298	399237.51	7016974.363	1420.723	RHYOLITE/	MAGANESE	HEM/LIMONITE	Chip	Outcrop	1	0.05	721.2	294
1285299	399028.138	7016905.694	1417.071	SILTY SANDSTONE		HEM/LIMONITE	Grab	Outcrop	55	0.4	3680.4	131
1285351	399059.661	7016858.881	1449.989	SILTY SANDSTONE	HEM	HEM/LIMONITE	Grab	Outcrop	4	2.3	22.3	145
1285352	399081.021	7016735.521	1442.771	BLACK SHALE	HEM	HEM/LIMONITE	Grab	Outcrop	2	0.1	132.5	462
1285353	401532.751	7020275.928	1557.82	SILTY SANDSTONE	LIMONITE		Grab	Float	8	0.7	287.8	388
1285354	401572.7	7020314.15	1572.063	SILTY SANDSTONE	LIMONITE		Grab	Float	4	0.2	180	161
1285355	401514.773	7020388.711	1545.224	SILTY SANDSTONE	Hemitite		Grab	Float	7	0.1	34.4	196
1285356	401487.709	7020364.153	1528.866	SILTY SANDSTONE	Hemitite		Grab	Outcrop	2	0.05	17.3	123
1285357	401399.228	7020409.38	1482.499	SILTY SANDSTONE	Hemitite		Grab	Outcrop	4	0.2	41.9	89
1285358	401343.285	7020339.158	1470.226	SILTY SANDSTONE	Hemitite		Grab	Outcrop	4	0.4	13.6	250
1285359	401335.413	7020299.45	1466.005	SILTY SANDSTONE	Hemitite		Grab	Outcrop	1	0.05	13.1	68
1285360	401340.096	7020363.485	1462.716	SILTY SANDSTONE/SHALE	Hemitite		Grab	Outcrop	4	1.6	154.4	1645
1285361	401280.682	7020399.269	1418.66	SILTY SANDSTONE	LIMONITE		Grab	Outcrop	2	0.3	31.4	56
1285378	409441.897	7018597.454	1600.453	CPC	HEM		Grab	Float	4	0.9	61	66
1285379	409588.89	7018689.995	1614.825	GREY SANDSTONE	HEM	VUGGY qzt st0ckwork	Grab	Float	11	0.4	98.4	126
1285380	409612.885	7018691.041	1614.817	GREY SANDSTONE	HEM	VUGGY qzt st0ckwork	Grab	Outcrop	25	0.3	99.4	140
1285381	409696.088	7018678.996	1655.39	GREY SANDSTONE	LIMONITE		Grab	Outcrop	1	0.5	9.7	105
1285382	409588.197	7018714.885	1611.846	BLACK SHALE			Grab	Outcrop	6	0.4	80.2	43
1285383	409557.651	7018746.441	1600.018	GREY SANDSTONE			Grab	Outcrop	1	0.4	23.9	8
1285384	409579.039	7018673.186	1583.784	GREY SANDSTONE		SELECT VUGGY QZT FLOAT	Grab	Outcrop	5	0.4	10.2	39
1285385	409056.609	7018802.223	1629.97	CPC		SELECT VUGGY QZT FLOAT	Grab	Outcrop	6	3.4	11.1	1
1285386	409056.744	7018810.507	1645.401	DARK GREY SANDSTONE	DES PYRITE		Grab	Outcrop	8	2	10.6	55
1285387	409031.094	7018814.521	1571.082	DARK GREY SANDSTONE	DES PYRITE		Grab	Outcrop	56	1.3	37.6	0.5
1285388	409028.401	7018777.186	1606.34	CPC			Grab	Outcrop	3	1.8	62.9	3
1285389	395754.774	7021922.719	1662.571	SILTY LIMESTONE	HEM		Grab	Subcrop	1	0.2	2.9	31
1285390	395701.956	7021951.357	1661.467	SILTY LIMESTONE	HEM		Grab	Subcrop	1	0.3	3.3	34
1285391	395711.785	7021887.769	1737.908	BLACK SHALE	T		Grab	Subcrop	1	0.05	1.5	30
1285392	395697.18	7021811.527	1766.44	Q UARTZITE/SS	T		Grab	Subcrop	1	0.2	3.3	36
1285393	395693.038	7021771.18	1775.316	SILTY SANDSTONE	T		Grab	Outcrop	1	0.05	3.8	67
1285394	395755.292	7021880.82	1727.67	SILTY SANDSTONE		HEM/ CALCITE	Grab	Outcrop	1	0.05	1.9	82
1285395	395858.011	7021901.134	1719.252	SILTY SANDSTONE		HEM/ CALCITE	Grab	Outcrop	1	0.2	1.1	30
1285436	401495	7019700		Quartz	None	Talus 8cm. Wide chunk of qtz with clasts			35	1	182.6	4
1285437	401453	7019685		Dv	None	Someone beat me to it (1095383) Rubbly			76	1.4	482.3	15
1285438	401460	7019819		Shale	None	A 'ferricrete' type rock of shale bits			4	0.1	24.7	1522
1285439	401353	7019841		Qtz-carb	None	Talus Probably from a vein			1	0.05	3	64
1285440	401246	7019941		Quartz	None	Talus Qtz. With shales			1	0.05	49.4	67
1285441	401138	7020157		Dv	None	Subcrop Break open a piece, see a bleb			20	0.4	493.9	92
1285442	401083	7020189		Dv	None	Subcrop Dvs thius low down have been			188	0.4	570	26
1285443	402203	7016135		Quartz	None	Vein 5cms. Wide X 20cms. Exposed in			1	0.05	1.4	64
1285444	402224	7016179		Dv	Pyrite	Subcrop Has/had few cubnes pyrite,			1	0.05	1.6	117
1285445	402244	7016180		Shale	None	Felsemer Larger pieces shale with qtz.			1	0.05	7.3	90
1285446	402181	7016228		Dv	None	Large talus boulders or area of subcrop?			1	0.05	0.25	55
1285447	401885	7016007		Quartz	None	Talus Piece. Thick with bit of shale			1	0.05	3	53
1285448	400796	7020698		Dv	None	Soil hole here ran 233ppb Au Some			1	0.2	179.6	38
1285449	400859	7020681		Dv	Pyrite	I've been here before Intrusive with			65	0.4	3228.5	76
1285451	400514.056	7016315.351	1575.787	BLACK SHALE			Grab	Float	1	0.05	5.2	149
1285452	400534.751	7016328.624	1580.742	BLACK SHALE			Grab	Float	16	0.2	35.9	42
1285453	400533.136	7016333.992	1571.46	INTRUSIVE			Grab	Outcrop	11	0.1	68.4	22
1285454	400517.921	7016350.253	1577.558	INTRUSIVE			Grab	Outcrop	1	0.1	83.8	86
1285455	400504.102	7016363.398	1593.035	INTRUSIVE			Grab	Outcrop	40	0.3	124.3	46
1285456	400456.303	7016377.624	1596.814	QZT/FLOAT /BLACK SHALE			Grab	Outcrop	12	0.05	9.3	361
1285457	400479.336	7016394.109	1616.233	INTRUSIVE			Grab	Float	1	0.5	12.9	438
1285458	400575.701	7016323.958	1514.53	INTRUSIVE			Grab	Outcrop	4	0.05	174.5	29
1285459	400656.211	7016248.235	1493.867	WEATHERED ALT SILTY SANDSTONE		qzt stockwork	Grab	Float	1	0.05	4.2	108
1285460	400727.339	7016206.652	1465.558	WEATHERED ALT SILTY SANDSTONE		qzt stockwork	Grab	Float	1	0.05	12.8	156
1285461	400933.82	7016297.062	1540.009	WEATHERED ALT SILTY SANDSTONE		qzt stockwork	Grab	Float	1	0.5	13	111

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 08, 2011
Report Date: August 22, 2011
Page: 1 of 4

CERTIFICATE OF ANALYSIS WHI11000515.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #2
P.O. Number
Number of Samples: 70

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	70	Crush, split and pulverize 250 g rock to 200 mesh			WHI
3B	70	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	70	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000515.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1092501	Rock	3.98	89	2.9	8.6	68.5	85	1.8	5.9	1.3	31	1.27	514.3	83.1	10.3	46	0.9	112.8	9.4	8	0.02
1092502	Rock	4.74	264	1.3	5.6	55.4	56	1.9	3.6	0.8	23	0.74	436.2	250.8	8.0	24	0.2	31.6	6.0	4	<0.01
1092503	Rock	5.10	100	0.9	3.7	47.0	33	1.7	3.0	0.6	26	0.70	353.8	83.4	7.3	15	0.2	24.6	4.4	3	<0.01
1092504	Rock	7.37	99	0.6	2.5	43.9	16	1.7	1.6	0.3	27	0.60	407.2	95.9	6.8	11	0.1	24.7	4.6	<2	<0.01
1092505	Rock	5.01	60	0.4	2.7	60.6	8	2.0	0.8	0.2	21	0.68	642.5	51.4	7.0	10	0.1	15.9	9.6	<2	<0.01
1092506	Rock	4.77	44	0.7	1.9	43.8	13	1.6	1.0	0.3	19	0.53	405.7	36.8	6.7	9	0.1	11.4	10.7	<2	<0.01
1092507	Rock	4.78	44	0.5	2.6	46.4	11	1.7	0.7	<0.1	19	0.54	390.2	36.2	5.6	10	0.1	9.9	9.4	2	<0.01
1092508	Rock	5.55	58	0.4	3.0	40.6	34	1.5	1.9	0.4	15	0.58	317.3	46.4	6.3	12	0.1	11.7	4.9	2	<0.01
1092509	Rock	4.37	189	2.0	2.5	39.2	23	4.5	1.7	0.4	21	0.49	106.0	60.0	7.7	24	0.3	41.8	6.5	8	<0.01
1092510	Rock	5.07	173	2.0	3.2	38.2	30	3.0	2.5	0.5	27	0.52	108.0	86.4	5.6	22	0.3	33.5	4.8	7	<0.01
1092511	Rock	4.56	111	1.7	5.4	20.5	25	3.1	2.7	0.7	30	0.65	175.4	35.8	2.8	25	1.2	30.6	4.3	5	0.01
1092512	Rock	5.07	137	2.5	4.3	60.5	26	3.9	2.7	0.5	34	0.63	136.7	48.7	5.2	28	1.5	49.5	5.5	17	0.02
1092513	Rock	4.26	91	1.2	3.3	59.5	22	1.7	1.1	0.5	28	0.47	114.2	77.5	5.5	12	0.2	31.6	3.3	7	<0.01
1092514	Rock	4.57	152	1.2	4.2	115.8	115	8.7	5.8	2.1	39	0.97	291.1	81.2	7.8	27	0.5	29.8	5.2	7	<0.01
1092515	Rock	4.78	612	1.6	6.6	123.8	170	2.5	10.1	2.9	49	1.43	395.8	412.8	8.6	50	0.3	31.0	2.6	14	<0.01
1092516	Rock	4.96	172	1.5	4.4	136.3	88	3.2	4.2	1.0	34	0.92	191.8	127.1	7.3	19	0.5	21.1	5.0	8	0.01
1092517	Rock	4.59	138	1.3	6.8	184.8	215	2.5	12.0	3.7	57	1.83	354.3	76.4	11.2	36	0.2	23.1	1.6	14	<0.01
1092518	Rock	4.75	64	1.3	6.8	162.4	267	1.6	14.8	4.5	66	1.95	361.0	44.8	11.8	31	0.2	13.7	1.7	15	<0.01
1092519	Rock	5.40	342	2.1	4.6	165.8	176	11.0	8.0	2.0	45	1.20	224.6	219.3	8.7	18	0.3	23.1	2.6	7	<0.01
1092520	Rock	4.92	172	1.4	4.0	175.4	92	3.3	6.9	1.8	37	0.90	193.4	78.6	9.0	15	0.2	14.8	1.0	6	<0.01
1092521	Rock	5.62	249	0.8	3.5	293.5	69	2.4	3.8	1.2	31	0.92	201.9	87.9	9.6	9	0.1	16.7	0.4	5	<0.01
1092522	Rock	4.29	28	3.4	16.9	59.2	103	1.2	11.6	3.3	34	2.65	178.2	6.2	7.3	17	0.3	3.7	1.4	24	<0.01
1092523	Rock	4.91	16	2.5	24.5	104.1	143	1.3	17.8	5.1	67	3.12	221.0	5.6	6.9	13	0.3	5.4	1.0	24	<0.01
1092524	Rock	5.26	60	1.5	7.6	152.5	82	2.1	5.0	1.6	29	1.67	286.4	11.3	8.2	12	0.2	15.0	0.7	12	<0.01
1092525	Rock	5.26	260	8.5	10.2	40.2	8	3.4	2.1	0.3	16	0.85	266.6	20.3	3.5	22	0.2	49.6	1.9	34	<0.01
1092526	Rock	4.79	278	6.2	4.4	14.9	3	1.2	1.1	<0.1	6	0.44	167.4	2.1	2.5	15	0.1	19.4	0.2	36	0.01
1092527	Rock	4.35	251	7.6	4.4	11.9	3	1.9	2.1	<0.1	12	0.50	112.8	4.2	2.6	15	0.1	19.5	0.2	33	<0.01
1092528	Rock	4.69	403	7.8	5.0	15.7	4	2.3	3.0	0.1	12	0.48	104.9	2.9	1.8	19	0.2	18.1	0.3	43	<0.01
1092529	Rock	7.67	268	8.9	7.6	14.1	3	1.4	3.4	<0.1	8	0.45	72.6	2.2	1.7	24	<0.1	13.4	0.2	60	0.01
1092530	Rock	5.65	47	7.4	7.4	14.1	4	0.6	3.2	<0.1	8	0.46	57.7	1.5	1.7	14	<0.1	7.9	0.1	48	0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000515.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1092501	Rock	0.036	20	2	0.03	1982	<0.001	<20	0.39	0.011	0.24	0.2	19.45	0.8	0.12	0.5	11.6	<1	<0.2
1092502	Rock	0.028	21	2	0.02	182	<0.001	<20	0.32	0.005	0.24	0.4	11.34	0.8	0.07	0.4	5.8	<1	<0.2
1092503	Rock	0.021	21	<1	0.01	124	<0.001	<20	0.30	0.004	0.21	0.4	11.20	0.8	0.06	0.4	7.0	<1	<0.2
1092504	Rock	0.023	22	5	0.01	176	<0.001	<20	0.34	0.003	0.26	0.5	13.47	0.7	0.07	0.4	6.9	<1	<0.2
1092505	Rock	0.044	20	<1	0.01	94	<0.001	<20	0.32	0.003	0.29	1.9	9.61	1.1	0.12	0.6	6.1	<1	<0.2
1092506	Rock	0.022	22	3	0.01	88	<0.001	<20	0.30	0.004	0.24	1.1	8.86	0.6	0.08	0.4	4.5	<1	<0.2
1092507	Rock	0.018	20	<1	0.01	78	<0.001	<20	0.29	0.004	0.23	0.8	7.31	0.5	0.07	0.4	5.1	<1	<0.2
1092508	Rock	0.017	21	4	0.01	69	<0.001	<20	0.25	0.002	0.19	0.3	11.52	0.5	<0.05	0.3	6.2	<1	<0.2
1092509	Rock	0.011	27	3	0.01	111	<0.001	<20	0.31	0.006	0.19	0.2	28.55	1.0	0.07	0.4	7.3	<1	<0.2
1092510	Rock	0.010	26	4	0.01	119	<0.001	<20	0.34	0.006	0.21	0.4	33.92	1.0	0.05	0.4	8.4	<1	<0.2
1092511	Rock	0.017	24	3	0.02	112	0.002	<20	0.35	0.031	0.16	0.4	>100	1.0	<0.05	0.4	31.0	<1	0.3
1092512	Rock	0.016	25	6	0.03	143	0.002	<20	0.42	0.045	0.22	0.2	>100	1.1	<0.05	1.0	20.5	1	0.5
1092513	Rock	0.017	25	2	0.02	92	0.002	27	0.34	0.045	0.23	0.1	46.05	0.6	<0.05	0.9	15.1	<1	<0.2
1092514	Rock	0.035	24	4	0.02	127	<0.001	<20	0.36	0.004	0.22	0.2	37.48	1.3	<0.05	0.8	9.4	<1	<0.2
1092515	Rock	0.048	27	3	0.02	107	<0.001	<20	0.40	0.003	0.23	0.2	16.33	1.3	0.07	0.7	6.1	1	<0.2
1092516	Rock	0.027	27	5	0.02	102	<0.001	<20	0.41	0.006	0.26	0.2	27.63	0.9	<0.05	0.9	7.7	1	<0.2
1092517	Rock	0.048	29	2	0.02	186	<0.001	<20	0.44	0.003	0.26	<0.1	11.62	1.2	0.10	0.7	8.4	<1	<0.2
1092518	Rock	0.046	30	4	0.02	133	<0.001	<20	0.52	0.004	0.31	<0.1	11.31	1.0	0.09	0.9	7.4	1	<0.2
1092519	Rock	0.023	26	2	0.02	80	<0.001	<20	0.40	0.003	0.25	<0.1	16.53	1.1	0.05	0.9	8.6	1	<0.2
1092520	Rock	0.024	28	3	0.02	108	<0.001	<20	0.45	0.003	0.29	0.1	15.14	0.9	0.06	1.1	8.5	1	<0.2
1092521	Rock	0.038	25	1	0.01	127	<0.001	<20	0.38	0.003	0.24	<0.1	15.24	1.0	0.09	0.9	7.2	<1	<0.2
1092522	Rock	0.030	26	8	0.01	242	<0.001	<20	0.48	0.007	0.23	<0.1	12.36	0.4	0.20	2.0	6.0	2	<0.2
1092523	Rock	0.038	26	8	0.01	130	<0.001	<20	0.43	0.004	0.18	<0.1	10.69	0.4	0.12	2.2	4.8	1	<0.2
1092524	Rock	0.036	26	5	0.01	179	<0.001	<20	0.36	0.004	0.22	<0.1	10.69	0.7	0.13	1.2	6.9	1	<0.2
1092525	Rock	0.018	18	4	0.01	169	<0.001	<20	0.32	0.042	0.18	<0.1	42.07	1.4	0.13	0.7	27.2	2	0.4
1092526	Rock	0.007	17	4	0.01	204	<0.001	<20	0.30	0.006	0.18	<0.1	32.97	0.8	0.11	0.8	11.0	1	0.2
1092527	Rock	0.007	16	3	0.01	126	<0.001	<20	0.28	0.004	0.15	<0.1	29.20	1.4	0.11	0.6	10.7	1	0.3
1092528	Rock	0.007	8	5	0.01	150	<0.001	<20	0.40	0.003	0.18	<0.1	28.59	1.3	0.11	1.0	14.7	1	0.4
1092529	Rock	0.007	5	4	<0.01	133	<0.001	<20	0.26	0.003	0.13	<0.1	16.15	1.1	0.09	1.0	16.7	1	<0.2
1092530	Rock	0.005	4	4	<0.01	602	<0.001	<20	0.33	0.003	0.15	<0.1	6.13	0.9	0.09	0.7	10.4	1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000515.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1092531	Rock	7.56	17	8.7	4.4	6.9	4	0.3	3.4	<0.1	7	0.30	34.9	1.4	1.6	11	<0.1	3.7	0.2	34	<0.01
1092532	Rock	6.56	5	8.3	5.2	5.7	3	0.3	2.9	<0.1	5	0.38	25.0	1.1	1.5	8	<0.1	3.4	0.2	29	<0.01
1092533	Rock	6.86	<2	6.7	3.2	8.0	2	0.3	2.5	<0.1	6	0.41	5.7	1.2	1.3	9	<0.1	2.3	0.2	32	0.01
1092534	Rock	7.32	<2	6.6	10.6	9.8	20	0.4	4.1	0.3	9	0.68	26.6	0.9	1.9	23	0.1	2.7	0.2	58	<0.01
1092535	Rock	7.17	<2	8.7	9.6	9.5	8	0.4	3.6	0.2	11	0.47	13.5	<0.5	1.8	37	<0.1	2.6	0.2	62	<0.01
1092536	Rock	6.28	6	11.4	13.7	12.1	37	0.3	8.3	0.5	7	0.67	42.4	<0.5	1.8	33	0.1	3.1	0.2	88	<0.01
1092537	Rock	5.90	4	8.2	14.1	11.7	80	0.2	9.9	1.1	11	0.78	32.6	<0.5	1.6	19	0.1	1.6	0.2	67	<0.01
1092538	Rock	5.98	4	8.9	9.6	8.0	33	0.2	6.1	0.5	7	0.56	42.7	<0.5	2.4	31	0.2	1.4	0.1	63	<0.01
1092539	Rock	6.53	8	13.9	10.7	8.5	28	0.2	6.3	0.5	7	0.47	38.9	<0.5	2.0	23	0.1	1.6	0.1	53	<0.01
1092540	Rock	6.75	8	7.9	10.1	6.2	10	0.2	3.5	0.2	7	0.34	17.4	<0.5	1.2	13	<0.1	1.5	0.1	35	<0.01
1092541	Rock	6.57	6	10.0	17.4	6.6	19	0.2	3.4	0.2	5	0.57	23.2	<0.5	1.6	11	<0.1	1.8	0.1	39	<0.01
1093501	Rock	1.45	<2	1.5	3.1	0.3	5	<0.1	3.2	0.4	62	0.19	1.4	<0.5	<0.1	575	0.2	0.2	<0.1	3	11.70
1093502	Rock	1.06	<2	0.5	14.4	1.8	12	0.1	4.6	0.6	22	0.46	7.9	<0.5	0.6	5	<0.1	0.3	<0.1	3	<0.01
1093503	Rock	0.82	<2	0.1	0.9	0.3	19	<0.1	2.5	0.3	30	0.19	1.0	<0.5	0.1	179	0.3	0.2	<0.1	4	8.04
1093504	Rock	1.15	<2	0.1	2.7	0.9	59	0.2	14.3	1.1	58	0.19	2.1	<0.5	0.4	566	1.0	0.6	<0.1	19	31.19
1093505	Rock	1.32	3	0.4	6.8	4.6	3	0.2	1.8	0.3	21	0.52	3.8	<0.5	0.3	35	<0.1	0.3	0.1	8	0.05
1093506	Rock	1.14	48	0.3	12.3	3.2	31	0.2	28.8	2.4	31	0.75	78.1	41.4	0.4	22	0.2	1.0	<0.1	5	0.01
1093507	Rock	0.77	<2	0.2	1.9	0.2	4	<0.1	2.3	0.3	36	0.32	1.6	1.5	<0.1	8	<0.1	0.1	<0.1	<2	0.01
1093508	Rock	0.92	12	0.7	55.7	4.1	47	0.4	12.4	1.6	11	1.54	3.7	0.8	1.3	32	0.1	<0.1	0.2	32	<0.01
1093509	Rock	1.07	4	<0.1	0.7	0.1	21	<0.1	1.3	0.4	23	0.12	1.5	1.4	<0.1	679	0.4	<0.1	<0.1	10	34.24
1093510	Rock	0.93	<2	0.9	10.1	4.2	3	1.3	2.6	0.3	30	0.46	1.6	0.5	0.1	14	<0.1	1.4	<0.1	20	0.04
1093511	Rock	0.97	<2	0.2	13.0	1.8	19	<0.1	13.4	0.8	24	0.55	54.4	1.2	0.8	6	<0.1	0.9	<0.1	2	<0.01
1093512	Rock	0.98	<2	<0.1	0.7	0.2	4	<0.1	<0.1	0.2	859	0.72	0.6	<0.5	0.2	721	0.2	<0.1	<0.1	13	29.18
1093513	Rock	1.11	<2	<0.1	1.1	0.4	23	<0.1	1.7	0.3	38	0.14	1.5	<0.5	0.1	575	0.4	0.2	<0.1	9	33.69
1093514	Rock	0.67	<2	0.1	3.4	0.7	74	<0.1	8.4	0.9	87	0.22	8.2	<0.5	0.2	303	4.8	0.6	<0.1	13	34.36
1093515	Rock	0.60	<2	<0.1	4.8	1.6	86	0.1	15.2	2.5	202	0.42	5.8	<0.5	0.4	226	1.5	0.5	<0.1	15	28.16
1093516	Rock	1.41	<2	0.2	0.6	0.3	25	<0.1	6.0	2.3	125	0.30	2.6	<0.5	<0.1	917	0.5	0.2	<0.1	15	32.98
1093517	Rock	0.77	4	1.4	6.6	1.3	23	0.8	7.5	0.5	35	0.49	2.5	<0.5	0.1	42	0.5	0.8	<0.1	28	0.37
1093518	Rock	1.41	4	<0.1	1.1	0.6	21	<0.1	2.4	1.0	67	0.16	2.4	<0.5	0.2	892	0.7	0.2	<0.1	9	32.07
1093519	Rock	1.39	<2	<0.1	0.5	0.4	21	<0.1	1.1	0.4	61	0.17	4.7	<0.5	0.2	816	0.7	0.2	<0.1	6	33.09

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000515.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1092531	Rock	0.003	2	4	<0.01	296	<0.001	<20	0.32	0.003	0.14	<0.1	2.00	0.5	<0.05	0.5	6.8	<1	<0.2
1092532	Rock	0.003	6	3	<0.01	218	<0.001	<20	0.31	0.004	0.13	<0.1	1.01	0.3	<0.05	0.5	8.1	<1	<0.2
1092533	Rock	0.003	4	3	<0.01	174	<0.001	<20	0.25	0.005	0.13	<0.1	0.59	0.4	0.10	0.6	4.1	<1	<0.2
1092534	Rock	0.012	4	5	0.01	175	<0.001	<20	0.29	0.005	0.14	<0.1	0.76	0.5	0.09	0.8	6.6	1	<0.2
1092535	Rock	0.013	3	5	0.01	205	<0.001	<20	0.31	0.004	0.13	<0.1	1.01	0.5	0.10	1.0	6.7	1	<0.2
1092536	Rock	0.034	2	8	0.01	231	<0.001	<20	0.33	0.005	0.13	<0.1	0.83	0.4	0.08	2.6	6.6	1	<0.2
1092537	Rock	0.019	2	7	0.01	238	<0.001	<20	0.35	0.005	0.14	<0.1	0.46	0.4	0.10	2.2	5.5	1	<0.2
1092538	Rock	0.022	2	8	0.01	206	<0.001	<20	0.33	0.005	0.14	<0.1	0.33	0.4	0.08	2.2	4.5	2	<0.2
1092539	Rock	0.014	2	6	0.02	241	<0.001	<20	0.36	0.006	0.15	<0.1	0.32	0.5	0.08	1.5	3.6	2	<0.2
1092540	Rock	0.012	1	5	0.02	199	<0.001	<20	0.34	0.006	0.14	<0.1	0.23	0.4	0.07	1.5	2.0	1	<0.2
1092541	Rock	0.024	1	6	0.01	197	<0.001	<20	0.32	0.006	0.13	<0.1	0.19	0.4	0.09	3.1	3.1	1	<0.2
1093501	Rock	0.002	1	1	0.12	75	<0.001	<20	0.02	0.002	<0.01	<0.1	0.02	<0.1	<0.05	0.2	<0.5	<1	<0.2
1093502	Rock	0.010	<1	3	<0.01	185	<0.001	<20	0.10	0.001	0.02	<0.1	0.07	<0.1	<0.05	0.7	0.6	<1	<0.2
1093503	Rock	0.018	1	3	0.05	54	<0.001	<20	0.02	0.002	<0.01	<0.1	0.02	<0.1	<0.05	0.2	<0.5	<1	<0.2
1093504	Rock	0.097	6	8	0.12	295	0.001	<20	0.07	0.005	0.02	<0.1	0.07	<0.1	0.13	0.6	<0.5	<1	<0.2
1093505	Rock	0.005	<1	4	<0.01	790	<0.001	<20	0.21	0.004	0.08	<0.1	0.71	<0.1	0.13	0.7	<0.5	<1	<0.2
1093506	Rock	0.019	2	5	<0.01	46	<0.001	<20	0.32	<0.001	0.01	<0.1	0.09	<0.1	<0.05	0.7	<0.5	<1	<0.2
1093507	Rock	0.006	<1	2	<0.01	16	<0.001	<20	0.06	0.003	<0.01	<0.1	0.02	<0.1	<0.05	0.1	<0.5	<1	<0.2
1093508	Rock	0.013	<1	26	0.17	1146	<0.001	<20	0.91	0.011	0.14	<0.1	0.09	<0.1	0.12	2.9	1.9	3	<0.2
1093509	Rock	0.026	9	2	0.13	79	<0.001	<20	<0.01	0.003	<0.01	<0.1	0.03	<0.1	0.18	0.5	<0.5	<1	<0.2
1093510	Rock	0.006	<1	6	<0.01	426	<0.001	<20	0.09	0.003	0.04	<0.1	0.23	0.1	0.08	0.3	3.1	<1	<0.2
1093511	Rock	0.007	2	4	<0.01	41	<0.001	<20	0.66	0.002	0.02	<0.1	0.07	<0.1	<0.05	0.5	<0.5	<1	<0.2
1093512	Rock	0.123	6	7	2.62	381	<0.001	<20	<0.01	0.007	<0.01	<0.1	<0.01	<0.1	0.11	0.4	<0.5	<1	<0.2
1093513	Rock	0.048	3	6	0.46	274	<0.001	<20	0.02	0.006	<0.01	<0.1	0.01	<0.1	0.18	0.3	<0.5	<1	<0.2
1093514	Rock	0.055	3	5	0.08	106	<0.001	<20	0.04	0.004	<0.01	<0.1	0.16	<0.1	0.19	0.8	<0.5	<1	<0.2
1093515	Rock	0.077	3	6	0.08	138	<0.001	<20	0.09	0.004	0.01	<0.1	0.09	<0.1	0.11	1.4	<0.5	<1	<0.2
1093516	Rock	0.046	3	4	0.33	227	<0.001	<20	0.01	0.004	<0.01	<0.1	0.03	<0.1	0.18	0.3	0.6	<1	<0.2
1093517	Rock	0.059	<1	6	<0.01	226	<0.001	<20	0.07	0.004	0.02	<0.1	0.02	<0.1	<0.05	0.2	2.0	<1	<0.2
1093518	Rock	0.064	4	9	0.15	474	<0.001	<20	0.03	0.005	<0.01	<0.1	0.15	<0.1	0.16	0.8	<0.5	<1	<0.2
1093519	Rock	0.063	3	7	0.13	3191	<0.001	<20	0.02	0.005	<0.01	<0.1	0.14	<0.1	0.22	0.4	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000515.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1093520	Rock	1.06	44	0.3	16.2	1.2	31	0.3	8.4	1.2	31	0.61	30.1	37.2	0.4	<1	<0.1	0.8	<0.1	4	0.15
1093521	Rock	0.92	18	0.2	4.6	3.5	9	<0.1	2.0	0.5	22	0.29	6.4	15.7	0.3	8	<0.1	0.4	<0.1	<2	0.12
1093522	Rock	0.92	15	0.9	4.9	3.9	2	0.9	2.1	0.3	30	0.54	6.3	6.7	0.3	9	<0.1	4.2	<0.1	8	<0.01
1093523	Rock	2.06	5	0.5	3.3	3.2	1	0.4	2.8	0.3	27	0.44	1.8	1.2	0.1	6	<0.1	2.1	<0.1	9	<0.01
1095953	Rock	1.02	<2	23.0	34.5	1.7	292	0.4	58.0	2.3	68	0.65	22.0	<0.5	0.5	30	3.6	9.5	<0.1	216	0.07
1095955	Rock	1.23	<2	0.5	0.8	36.0	118	<0.1	2.8	2.2	214	1.33	4.7	0.6	11.3	19	0.9	<0.1	0.7	<2	0.12
1095956	Rock	1.37	2	29.5	23.4	36.8	288	<0.1	36.5	2.2	40	2.65	16.3	<0.5	12.1	45	0.5	0.5	0.3	70	0.03
1094001	Rock	2.01	10	0.9	146.5	5.4	262	0.5	80.7	8.4	178	3.52	184.3	3.9	0.5	19	3.1	2.8	<0.1	10	0.39
1094002	Rock	2.30	12	0.8	52.5	11.3	64	1.6	18.7	2.6	76	1.44	24.1	3.1	0.9	34	1.5	0.7	0.3	15	0.40
1092542	Rock	0.11	1669	20.0	314.3	7.6	44	0.4	34.3	7.3	427	3.09	7.9	1346	1.0	35	0.1	0.9	0.4	51	0.72

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000515.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1093520	Rock	0.026	<1	5	<0.01	65	<0.001	<20	0.12	0.003	0.02	<0.1	0.43	<0.1	<0.05	0.7	1.0	<1	<0.2
1093521	Rock	0.003	<1	3	<0.01	75	<0.001	<20	0.09	0.004	0.02	<0.1	0.24	<0.1	<0.05	0.3	<0.5	<1	<0.2
1093522	Rock	0.005	<1	4	<0.01	930	<0.001	<20	0.11	0.002	0.06	<0.1	0.23	0.3	0.12	0.6	8.4	<1	<0.2
1093523	Rock	0.005	<1	3	<0.01	270	<0.001	<20	0.09	0.002	0.04	<0.1	0.09	<0.1	<0.05	0.2	1.3	<1	<0.2
1095953	Rock	0.015	3	12	0.04	80	0.002	<20	0.19	0.002	0.06	0.1	0.30	1.1	0.10	0.7	3.4	<1	<0.2
1095955	Rock	0.028	23	<1	0.03	249	<0.001	<20	0.39	0.024	0.19	0.1	0.05	0.1	<0.05	1.3	<0.5	<1	<0.2
1095956	Rock	0.061	21	3	0.02	1018	<0.001	<20	0.49	0.012	0.23	0.1	0.12	0.4	0.10	1.8	4.5	1	<0.2
1094001	Rock	0.037	2	7	0.05	471	<0.001	<20	0.55	0.003	0.03	<0.1	0.08	<0.1	0.10	2.6	4.1	<1	<0.2
1094002	Rock	0.012	2	7	0.04	1068	<0.001	<20	0.42	0.005	0.13	<0.1	0.23	0.1	0.17	1.2	3.4	1	<0.2
1092542	Rock	0.051	5	27	0.57	113	0.101	<20	1.23	0.081	0.10	0.2	0.08	<0.1	0.07	3.1	0.7	4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

QUALITY CONTROL REPORT WHI11000515.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1092503	Rock	5.10	100	0.9	3.7	47.0	33	1.7	3.0	0.6	26	0.70	353.8	83.4	7.3	15	0.2	24.6	4.4	3	<0.01
REP 1092503	QC		101																		
1092513	Rock	4.26	91	1.2	3.3	59.5	22	1.7	1.1	0.5	28	0.47	114.2	77.5	5.5	12	0.2	31.6	3.3	7	<0.01
REP 1092513	QC			1.3	3.8	61.8	21	1.8	2.4	0.4	29	0.47	121.8	62.7	5.7	12	<0.1	30.0	3.3	5	0.02
1093514	Rock	0.67	<2	0.1	3.4	0.7	74	<0.1	8.4	0.9	87	0.22	8.2	<0.5	0.2	303	4.8	0.6	<0.1	13	34.36
REP 1093514	QC		<2	0.1	3.2	0.7	75	0.1	9.2	1.1	88	0.23	9.0	<0.5	0.2	300	4.8	0.6	<0.1	14	34.51
Core Reject Duplicates																					
1092508	Rock	5.55	58	0.4	3.0	40.6	34	1.5	1.9	0.4	15	0.58	317.3	46.4	6.3	12	0.1	11.7	4.9	2	<0.01
DUP 1092508	QC		57	0.4	3.2	41.4	37	1.5	1.9	0.4	21	0.62	321.8	53.1	7.1	12	0.2	11.3	5.2	2	<0.01
1093502	Rock	1.06	<2	0.5	14.4	1.8	12	0.1	4.6	0.6	22	0.46	7.9	<0.5	0.6	5	<0.1	0.3	<0.1	3	<0.01
DUP 1093502	QC		<2	0.5	14.2	1.7	12	0.1	4.9	0.7	26	0.50	7.9	<0.5	0.5	12	<0.1	0.3	<0.1	3	<0.01
Reference Materials																					
STD DS8	Standard			12.9	102.7	123.0	303	1.6	38.8	7.2	602	2.37	24.5	103.4	6.5	69	2.2	3.6	6.0	39	0.68
STD DS8	Standard			12.4	111.6	130.6	318	2.0	37.5	7.6	606	2.45	25.8	101.2	6.0	65	2.4	4.7	6.3	40	0.67
STD DS8	Standard			12.7	110.7	120.2	319	1.9	38.2	7.5	612	2.54	26.7	108.5	6.6	63	2.4	3.6	6.4	40	0.63
STD OREAS45CA	Standard			0.7	481.3	17.8	57	0.2	227.9	80.6	850	14.12	3.4	37.4	6.0	13	<0.1	<0.1	0.2	191	0.40
STD OREAS45CA	Standard			0.7	484.3	18.3	57	0.3	225.4	84.6	885	14.35	3.7	40.5	6.5	15	<0.1	<0.1	0.4	198	0.41
STD OREAS45CA	Standard			0.8	498.9	20.7	63	0.3	237.0	88.5	910	16.88	3.9	42.5	7.0	18	0.1	<0.1	0.2	201	0.41
STD OXC88	Standard		219																		
STD OXC88	Standard		200																		
STD OXC88	Standard		204																		
STD OXH82	Standard		1264																		
STD OXH82	Standard		1341																		
STD OXH82 Expected			1278																		
STD OXC88 Expected			203																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank		<2																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

QUALITY CONTROL REPORT WHI11000515.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1092503	Rock	0.021	21	<1	0.01	124	<0.001	<20	0.30	0.004	0.21	0.4	11.20	0.8	0.06	0.4	7.0	<1	<0.2
REP 1092503	QC																		
1092513	Rock	0.017	25	2	0.02	92	0.002	27	0.34	0.045	0.23	0.1	46.05	0.6	<0.05	0.9	15.1	<1	<0.2
REP 1092513	QC	0.011	25	4	0.02	95	0.002	<20	0.34	0.041	0.23	0.2	42.67	0.7	<0.05	0.4	8.9	1	<0.2
1093514	Rock	0.055	3	5	0.08	106	<0.001	<20	0.04	0.004	<0.01	<0.1	0.16	<0.1	0.19	0.8	<0.5	<1	<0.2
REP 1093514	QC	0.054	3	5	0.08	104	<0.001	<20	0.04	0.004	<0.01	<0.1	0.15	<0.1	0.18	0.8	<0.5	<1	<0.2
Core Reject Duplicates																			
1092508	Rock	0.017	21	4	0.01	69	<0.001	<20	0.25	0.002	0.19	0.3	11.52	0.5	<0.05	0.3	6.2	<1	<0.2
DUP 1092508	QC	0.018	23	4	0.01	78	<0.001	<20	0.29	0.003	0.22	0.3	11.85	0.5	<0.05	0.3	5.6	<1	<0.2
1093502	Rock	0.010	<1	3	<0.01	185	<0.001	<20	0.10	0.001	0.02	<0.1	0.07	<0.1	<0.05	0.7	0.6	<1	<0.2
DUP 1093502	QC	0.010	<1	4	<0.01	187	<0.001	<20	0.10	0.002	0.02	<0.1	0.05	<0.1	<0.05	0.7	0.7	<1	<0.2
Reference Materials																			
STD DS8	Standard	0.079	14	113	0.58	288	0.109	<20	0.88	0.089	0.41	2.4	0.19	5.0	0.16	1.7	5.5	5	4.6
STD DS8	Standard	0.077	12	117	0.60	292	0.110	<20	0.86	0.082	0.39	3.2	0.19	5.3	0.16	1.7	4.4	5	5.7
STD DS8	Standard	0.080	13	119	0.61	291	0.112	<20	0.90	0.084	0.42	2.3	0.20	5.2	0.16	2.0	5.9	5	5.0
STD OREAS45CA	Standard	0.038	13	636	0.13	143	0.114	<20	3.55	0.013	0.07	<0.1	0.02	<0.1	<0.05	32.1	0.5	16	<0.2
STD OREAS45CA	Standard	0.033	14	638	0.12	147	0.115	<20	3.22	0.014	0.06	<0.1	0.04	<0.1	<0.05	33.5	0.6	17	<0.2
STD OREAS45CA	Standard	0.038	16	663	0.15	167	0.130	<20	3.54	0.014	0.07	<0.1	0.03	<0.1	<0.05	35.6	0.6	19	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82 Expected																			
STD OXC88 Expected																			
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

QUALITY CONTROL REPORT WHI11000515.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		<2	0.1	1.5	2.6	46	<0.1	3.6	4.2	544	1.83	1.2	0.8	4.8	60	<0.1	<0.1	<0.1	36	0.44
G1	Prep Blank		<2	<0.1	1.5	1.4	45	<0.1	3.5	4.1	552	1.87	0.7	<0.5	4.9	55	<0.1	<0.1	<0.1	35	0.44

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

QUALITY CONTROL REPORT WHI11000515.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																			
G1	Prep Blank	0.069	8	6	0.56	219	0.123	<20	0.99	0.096	0.43	<0.1	<0.01	0.3	<0.05	1.7	<0.5	5	<0.2
G1	Prep Blank	0.073	8	11	0.57	216	0.124	<20	0.92	0.072	0.43	<0.1	<0.01	0.3	<0.05	1.5	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 13, 2011
Report Date: August 23, 2011
Page: 1 of 4

CERTIFICATE OF ANALYSIS WHI11000567.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #3
P.O. Number
Number of Samples: 68

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	67	Crush, split and pulverize 250 g rock to 200 mesh			WHI
3B	67	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	67	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000567.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1093524	Rock	1.06	<2	0.3	1.3	0.7	31	<0.1	1.1	0.5	133	0.81	2.1	2.7	0.3	634	0.4	0.1	<0.1	11	27.25
1093525	Rock	0.91	<2	0.3	0.8	33.0	49	<0.1	1.3	1.6	114	1.27	71.6	2.4	13.7	18	<0.1	0.2	1.0	<2	0.17
1093526	Rock	0.55	<2	0.2	3.6	1.6	15	<0.1	2.7	1.3	225	0.26	1.0	2.3	0.2	152	0.5	0.1	<0.1	3	3.29
1093527	Rock	0.69	4	0.6	13.1	3.4	3	0.5	5.3	0.7	25	0.29	<0.5	1.3	0.2	13	<0.1	2.0	<0.1	21	0.03
1093528	Rock	0.76	3	0.8	6.5	4.3	5	0.6	10.8	1.4	31	0.55	2.4	1.2	0.2	14	<0.1	2.0	<0.1	6	0.05
1093529	Rock	0.93	<2	0.3	12.1	1.6	170	<0.1	51.3	9.3	664	2.54	5.2	2.0	0.2	27	2.8	0.3	<0.1	9	0.53
1093530	Rock	0.54	25	15.1	14.3	32.6	4	0.4	0.9	0.2	26	1.63	67.2	17.0	2.6	82	<0.1	6.6	<0.1	89	0.02
1093531	Rock	1.18	7	0.4	89.5	7.4	23	0.4	6.7	0.5	26	1.89	2.2	2.0	0.6	21	<0.1	0.2	0.3	20	0.02
1093532	Rock	1.09	<2	0.3	2.8	0.8	30	<0.1	5.3	1.4	288	0.52	0.8	1.6	0.2	1172	0.6	<0.1	<0.1	7	20.52
1093533	Rock	0.74	<2	1.4	196.6	4.7	578	0.3	74.0	9.5	239	17.21	50.9	3.9	2.2	<1	4.8	2.4	0.1	128	0.08
1093534	Rock	0.33	<2	2.3	102.7	4.3	376	0.1	550.1	78.3	1630	9.62	9.4	2.3	20.9	265	3.5	1.0	<0.1	286	1.31
1093535	Rock	1.24	6	18.3	282.6	11.9	405	0.6	158.8	79.7	1095	1.95	39.1	<0.5	2.8	44	3.3	2.3	0.1	126	0.18
1093536	Rock	0.60	<2	0.7	4.7	1.3	34	<0.1	14.4	2.8	62	0.87	4.1	0.7	0.8	4	0.1	0.3	<0.1	6	0.03
1093537	Rock	0.74	16	0.3	3.5	1.7	50	0.1	10.8	2.6	106	0.65	24.7	11.8	0.5	12	0.7	0.7	<0.1	4	0.17
1093538	Rock	1.10	<2	0.5	1.5	0.4	8	<0.1	2.3	0.5	38	0.38	10.0	1.7	<0.1	2	<0.1	0.3	<0.1	<2	<0.01
1093539	Rock	0.84	51	0.4	29.1	11.6	12	1.6	1.4	0.5	14	1.68	545.1	55.5	8.0	7	<0.1	2.8	9.2	<2	<0.01
1093540	Rock	0.92	108	18.5	78.0	6.7	32	3.0	6.0	0.2	27	0.64	120.5	36.9	0.9	138	1.3	75.4	1.9	126	0.01
1093541	Rock	0.89	34	66.3	27.1	62.2	24	1.0	5.8	0.4	55	2.25	413.7	3.3	3.6	275	0.8	109.4	0.3	171	0.05
1093542	Rock	0.74	<2	0.4	4.6	6.8	84	<0.1	37.2	17.1	693	3.77	25.8	<0.5	19.0	16	<0.1	0.5	0.3	32	0.13
1093543	Rock	1.00	3	0.3	6.6	8.7	57	<0.1	14.8	10.0	229	2.54	2.4	<0.5	19.0	69	0.3	0.1	<0.1	67	1.30
1093544	Rock	0.95	<2	0.2	7.9	3.7	8	<0.1	13.6	7.6	4923	3.04	2.8	1.1	2.0	318	<0.1	0.4	<0.1	7	8.68
1093545	Rock	0.17	<2	0.4	3.4	4.6	28	<0.1	5.1	1.4	187	1.01	3.7	<0.5	0.6	<1	<0.1	0.4	<0.1	5	0.07
1093546	Rock	1.43	<2	0.3	0.8	1.3	18	<0.1	2.8	1.1	433	0.71	0.6	<0.5	0.2	259	<0.1	0.1	<0.1	<2	2.04
1093547	Rock	0.97	<2	0.1	20.0	1.2	22	<0.1	5.6	1.5	458	1.32	<0.5	<0.5	6.4	123	0.2	<0.1	<0.1	9	1.80
1093548	Rock	0.95	<2	0.9	1.3	0.9	4	<0.1	1.7	0.3	34	0.27	0.9	<0.5	0.1	13	<0.1	0.3	<0.1	8	0.04
1093549	Rock	1.03	5	0.3	11.2	9.7	10	0.4	40.0	19.7	1335	4.43	7.7	<0.5	2.0	826	<0.1	0.5	<0.1	10	9.72
1093550	Rock	1.01	<2	0.3	4.8	1.5	17	<0.1	7.8	0.7	135	0.62	0.9	<0.5	0.2	3	0.1	0.1	<0.1	<2	0.07
1093551	Rock	0.90	<2	0.7	17.7	7.5	109	0.2	25.5	8.0	1207	4.39	15.3	<0.5	1.7	94	0.4	0.4	<0.1	24	4.63
1093552	Rock	1.09	5	0.6	32.0	13.1	144	0.6	15.9	2.6	57	1.75	3.2	<0.5	0.4	12	0.3	0.8	<0.1	22	0.14
1093553	Rock	0.94	11	1.8	31.5	14.7	2	0.7	3.5	0.2	22	0.29	3.4	<0.5	0.7	9	0.1	0.5	0.1	10	0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000567.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1093524	Rock	0.068	5	11	2.28	614	0.001	<20	0.04	0.007	<0.01	<0.1	0.02	<0.1	0.32	0.6	<0.5	<1	<0.2
1093525	Rock	0.024	22	<1	0.02	662	<0.001	<20	0.37	0.022	0.18	<0.1	0.11	<0.1	0.06	1.3	<0.5	1	<0.2
1093526	Rock	0.019	2	2	0.03	83	<0.001	<20	0.03	0.003	<0.01	<0.1	0.02	<0.1	<0.05	0.2	<0.5	<1	<0.2
1093527	Rock	0.002	<1	5	<0.01	907	<0.001	<20	0.17	<0.001	0.08	<0.1	0.41	<0.1	0.06	0.4	6.3	<1	<0.2
1093528	Rock	0.034	<1	4	<0.01	209	<0.001	<20	0.15	0.001	0.07	<0.1	0.20	<0.1	0.18	0.3	1.0	<1	<0.2
1093529	Rock	0.014	<1	2	0.13	177	<0.001	<20	0.11	<0.001	0.02	<0.1	0.06	<0.1	<0.05	2.7	<0.5	<1	<0.2
1093530	Rock	0.067	4	10	<0.01	561	<0.001	<20	0.15	<0.001	0.19	<0.1	2.12	0.8	0.33	1.4	4.2	2	<0.2
1093531	Rock	0.015	<1	33	0.27	393	<0.001	<20	0.68	0.005	0.09	<0.1	0.08	0.2	0.10	1.6	0.9	2	<0.2
1093532	Rock	0.065	3	6	0.39	579	<0.001	<20	0.06	0.004	<0.01	<0.1	0.04	<0.1	0.15	0.9	<0.5	<1	<0.2
1093533	Rock	0.269	1	60	<0.01	51	0.002	<20	0.45	<0.001	0.01	<0.1	0.23	<0.1	<0.05	3.9	6.2	<1	<0.2
1093534	Rock	0.648	114	525	6.82	1578	0.012	<20	4.86	<0.001	0.01	<0.1	0.06	0.4	0.07	23.0	<0.5	14	<0.2
1093535	Rock	0.115	9	8	0.06	2501	0.002	<20	2.16	<0.001	0.17	<0.1	1.37	0.3	0.16	4.6	2.8	1	<0.2
1093536	Rock	0.010	3	5	0.02	125	<0.001	<20	0.08	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	0.7	<0.5	<1	<0.2
1093537	Rock	0.015	3	4	0.02	374	<0.001	<20	0.07	<0.001	0.01	<0.1	0.38	<0.1	<0.05	0.4	<0.5	<1	<0.2
1093538	Rock	0.002	<1	2	<0.01	2556	<0.001	<20	0.01	0.001	<0.01	<0.1	0.02	<0.1	0.06	0.2	<0.5	<1	<0.2
1093539	Rock	0.021	12	<1	0.02	83	<0.001	<20	0.31	0.009	0.20	7.9	1.73	0.2	0.29	0.3	6.1	<1	<0.2
1093540	Rock	0.061	5	14	<0.01	269	0.002	83	0.32	<0.001	0.10	0.7	74.56	2.9	0.06	1.4	9.9	1	1.0
1093541	Rock	0.231	11	34	<0.01	253	0.003	<20	0.27	0.001	0.18	2.1	2.87	2.0	0.32	4.2	11.3	3	0.2
1093542	Rock	0.036	49	37	0.80	86	0.081	<20	3.63	0.074	0.71	0.1	0.37	0.6	<0.05	2.8	<0.5	9	<0.2
1093543	Rock	0.052	32	26	1.02	301	0.303	<20	3.15	0.310	0.96	0.2	0.10	0.5	<0.05	3.2	<0.5	10	<0.2
1093544	Rock	0.016	7	4	5.20	730	0.002	<20	0.22	0.008	0.14	<0.1	0.05	<0.1	0.44	2.7	<0.5	<1	<0.2
1093545	Rock	0.010	1	3	0.02	60	0.001	<20	0.12	0.001	0.06	<0.1	0.07	<0.1	<0.05	0.7	<0.5	<1	<0.2
1093546	Rock	0.006	3	1	0.05	69	<0.001	<20	0.05	<0.001	0.02	<0.1	0.04	<0.1	<0.05	0.4	<0.5	<1	<0.2
1093547	Rock	0.018	17	9	0.89	2732	0.002	<20	0.60	0.003	0.34	<0.1	0.02	<0.1	<0.05	3.7	<0.5	1	<0.2
1093548	Rock	0.028	<1	2	<0.01	45	<0.001	<20	0.03	<0.001	0.01	<0.1	0.04	<0.1	<0.05	0.2	<0.5	<1	<0.2
1093549	Rock	0.013	7	7	5.81	63	0.001	<20	0.28	0.009	0.16	<0.1	0.09	0.1	1.32	2.5	1.1	<1	<0.2
1093550	Rock	0.013	<1	2	0.02	118	<0.001	<20	0.04	<0.001	0.02	<0.1	0.02	<0.1	<0.05	0.2	<0.5	<1	<0.2
1093551	Rock	0.041	2	2	1.04	486	<0.001	<20	0.22	0.005	0.07	<0.1	0.05	<0.1	0.07	2.3	1.1	<1	<0.2
1093552	Rock	0.083	<1	7	<0.01	59	<0.001	<20	0.20	0.001	0.04	<0.1	0.05	<0.1	<0.05	1.3	0.7	<1	<0.2
1093553	Rock	0.011	1	5	<0.01	126	<0.001	<20	0.23	0.002	0.10	<0.1	0.12	<0.1	0.05	1.1	1.4	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000567.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1093554	Rock	0.85	6	1.6	64.7	10.7	37	0.7	60.3	0.8	19	1.18	8.2	0.8	0.9	14	0.2	0.9	<0.1	91	0.03
1093555	Rock	1.28	4	0.7	21.7	13.0	3	0.4	9.0	0.1	26	0.58	3.3	0.8	0.3	9	<0.1	0.7	<0.1	21	0.02
1093556	Rock	1.54	<2	0.6	48.1	9.9	14	0.3	24.7	1.1	185	0.98	2.8	<0.5	0.2	4	<0.1	0.4	<0.1	16	<0.01
1093557	Rock	1.08	4	4.1	6.1	8.2	2	0.1	2.2	0.2	20	2.54	13.4	1.3	0.5	16	<0.1	1.7	0.2	84	0.04
1093558	Rock	0.97	<2	0.4	20.6	1.2	3	<0.1	4.2	0.3	48	0.76	3.7	<0.5	<0.1	3	<0.1	0.2	<0.1	9	<0.01
1093559	Rock	0.74	4	1.8	51.8	10.0	127	0.1	43.2	14.6	468	6.91	7.7	<0.5	0.8	9	<0.1	0.6	0.2	83	0.10
1093560	Rock	1.20	<2	0.2	14.9	1.5	10	<0.1	269.8	31.4	857	3.59	2.1	<0.5	1.8	193	<0.1	<0.1	<0.1	85	16.99
1093561	Rock	1.07	<2	<0.1	32.6	1.5	12	<0.1	165.7	26.8	775	3.97	1.1	<0.5	2.6	161	<0.1	<0.1	<0.1	71	7.37
1093562	Rock	0.81	<2	0.5	74.9	1.8	166	<0.1	261.8	34.5	716	5.85	1.4	3.1	2.6	144	1.8	<0.1	<0.1	80	6.48
1093563	Rock	1.69	<2	0.6	5.6	17.1	2	0.6	3.4	0.8	31	0.59	3.5	4.8	0.2	7	<0.1	0.8	<0.1	8	0.05
1093564	Rock	0.37	3	0.8	31.3	8.9	70	0.4	50.1	16.5	955	7.41	6.3	3.0	2.2	34	0.2	0.4	<0.1	54	1.21
1094003	Rock	1.51	<2	8.2	22.2	57.6	91	0.1	10.7	1.2	31	0.87	88.6	4.0	1.3	26	0.3	0.1	3.3	20	0.09
1094004	Rock	1.86	17	5.4	22.2	58.2	217	<0.1	13.3	1.4	71	0.99	673.1	17.9	1.3	33	1.8	0.7	3.2	19	0.04
1094005	Rock	1.93	5	1.0	27.4	12.4	135	0.2	133.7	28.6	2203	18.51	12.6	1.5	1.7	149	1.0	0.3	0.2	192	2.29
1094007	Rock	2.08	3	0.1	20.1	1.9	16	<0.1	15.8	6.1	560	2.30	2.4	1.8	4.2	130	<0.1	<0.1	0.1	8	3.87
1094008	Rock	1.92	3	1.1	32.4	10.4	33	0.6	13.2	3.4	43	6.32	3.0	6.2	2.6	43	<0.1	0.4	0.2	11	0.03
1094016	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1095951	Rock	1.51	8	0.3	7.7	2.3	19	0.1	7.9	2.7	1372	3.29	27.7	8.4	0.1	982	0.6	0.9	<0.1	6	5.01
1095952	Rock	0.61	<2	8.5	17.0	0.7	242	0.2	39.9	1.4	74	0.41	12.6	3.4	0.2	2	2.7	4.8	<0.1	94	0.16
1095954	Rock	1.46	<2	7.1	55.2	1.1	819	0.8	28.8	0.6	68	0.35	18.6	2.9	0.1	96	12.6	12.9	<0.1	234	1.47
1095957	Rock	0.94	<2	0.6	62.0	3.9	21	<0.1	246.0	36.8	857	4.65	139.1	1.4	11.3	376	<0.1	0.6	<0.1	95	9.15
1095958	Rock	0.52	62	<0.1	1.0	75.3	48	<0.1	3.4	5.3	220	0.42	584.0	57.6	0.9	2	0.2	0.3	2.2	<2	0.06
1095959	Rock	0.76	<2	3.7	5.0	47.5	13	<0.1	3.0	0.4	14	0.46	179.7	3.9	0.8	18	<0.1	0.1	2.7	6	0.08
1095960	Rock	0.64	64	3.3	4.3	68.0	9	0.1	1.0	0.1	22	0.38	1100	57.6	0.9	42	0.9	0.6	1.5	8	0.02
1095961	Rock	0.78	<2	4.2	24.4	66.3	200	0.1	15.9	3.8	142	0.87	2101	6.4	1.3	16	2.2	1.3	2.7	32	0.04
1092551	Rock	7.81	383	12.9	27.0	16.5	58	1.7	10.6	1.4	20	1.12	324.0	18.6	3.2	50	0.4	7.7	0.5	116	0.07
1092552	Rock	9.29	434	15.0	29.6	15.9	67	1.7	12.9	1.9	21	1.11	299.3	16.5	3.5	32	0.4	8.0	0.5	96	0.08
1092553	Rock	7.18	643	14.0	38.0	23.5	54	2.4	10.9	1.5	24	1.18	479.8	41.5	3.1	41	0.4	11.7	0.6	126	0.29
1092554	Rock	6.26	780	12.8	48.5	22.4	134	2.7	17.8	2.5	56	1.26	668.7	20.2	2.2	39	0.7	18.2	0.4	149	0.22
1092555	Rock	7.88	802	10.9	34.4	28.0	39	2.6	7.3	0.7	25	0.85	504.1	48.8	2.3	52	0.5	15.9	0.5	164	0.54

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000567.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1093554	Rock	0.181	1	30	<0.01	72	0.002	<20	1.42	<0.001	0.05	<0.1	0.20	<0.1	0.08	12.6	2.3	1	<0.2
1093555	Rock	0.047	<1	7	<0.01	52	<0.001	<20	0.31	<0.001	0.04	<0.1	0.06	<0.1	<0.05	1.2	1.2	<1	<0.2
1093556	Rock	0.027	<1	6	<0.01	29	<0.001	<20	0.23	<0.001	0.02	<0.1	0.03	<0.1	<0.05	2.0	0.8	<1	<0.2
1093557	Rock	0.102	<1	18	0.02	87	0.002	<20	0.17	0.003	0.05	<0.1	0.12	<0.1	<0.05	15.0	2.4	<1	<0.2
1093558	Rock	0.020	<1	4	<0.01	9	<0.001	<20	0.07	0.002	<0.01	<0.1	<0.01	<0.1	<0.05	0.7	0.6	<1	<0.2
1093559	Rock	0.052	<1	21	0.07	120	<0.001	<20	0.41	0.002	0.07	<0.1	0.05	<0.1	<0.05	10.7	2.6	2	<0.2
1093560	Rock	0.123	8	163	2.07	262	0.001	<20	0.33	0.015	0.11	<0.1	<0.01	<0.1	0.50	11.1	<0.5	1	<0.2
1093561	Rock	0.175	3	112	3.15	349	0.001	<20	0.48	0.008	0.13	<0.1	<0.01	<0.1	0.08	13.5	<0.5	2	<0.2
1093562	Rock	0.215	2	182	3.11	166	0.002	<20	1.64	0.003	0.15	<0.1	<0.01	<0.1	0.12	9.1	0.5	5	<0.2
1093563	Rock	0.010	<1	3	<0.01	142	<0.001	<20	0.07	0.002	0.03	<0.1	0.05	<0.1	<0.05	0.4	0.9	<1	<0.2
1093564	Rock	0.053	2	23	0.86	265	<0.001	<20	0.42	0.005	0.08	<0.1	0.08	0.1	0.65	8.0	2.1	1	<0.2
1094003	Rock	0.023	2	2	0.04	1287	<0.001	<20	0.53	0.002	0.21	0.1	1.62	0.2	<0.05	0.9	1.3	1	<0.2
1094004	Rock	0.025	<1	2	0.02	252	<0.001	<20	0.48	0.003	0.23	<0.1	0.21	0.3	<0.05	0.8	0.7	<1	<0.2
1094005	Rock	0.063	2	27	3.06	539	<0.001	<20	1.37	0.005	0.07	<0.1	0.06	0.1	0.33	14.1	2.7	4	<0.2
1094007	Rock	0.022	10	5	1.75	613	0.001	<20	0.42	0.005	0.25	<0.1	<0.01	0.3	0.21	3.5	<0.5	<1	<0.2
1094008	Rock	0.028	7	7	0.04	43	0.001	<20	0.49	0.005	0.45	<0.1	0.06	0.2	1.08	3.0	2.0	2	<0.2
1094016	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1095951	Rock	0.010	<1	4	2.67	324	<0.001	<20	0.06	0.002	0.01	<0.1	0.30	<0.1	0.07	0.4	1.9	<1	<0.2
1095952	Rock	0.011	1	6	0.02	115	<0.001	<20	0.10	0.001	0.02	<0.1	0.06	0.2	<0.05	0.5	0.9	<1	<0.2
1095954	Rock	0.021	1	10	0.05	54	0.001	<20	0.09	0.001	0.03	<0.1	3.77	0.2	<0.05	1.0	1.4	<1	<0.2
1095957	Rock	0.349	49	119	4.17	700	0.006	22	0.66	0.007	0.21	<0.1	0.19	0.1	0.20	13.0	<0.5	2	<0.2
1095958	Rock	0.008	<1	<1	<0.01	120	<0.001	<20	0.44	0.002	0.23	<0.1	0.57	0.2	<0.05	0.2	<0.5	<1	<0.2
1095959	Rock	0.012	<1	2	0.03	267	<0.001	<20	0.35	0.002	0.21	<0.1	3.50	0.2	0.07	0.5	<0.5	<1	<0.2
1095960	Rock	0.013	<1	1	<0.01	164	<0.001	<20	0.36	<0.001	0.23	0.1	1.34	0.3	0.06	0.3	1.2	<1	<0.2
1095961	Rock	0.020	<1	2	<0.01	280	<0.001	<20	0.46	0.002	0.23	<0.1	1.02	0.3	<0.05	0.8	1.9	<1	<0.2
1092551	Rock	0.120	14	11	0.02	190	0.002	<20	0.42	0.008	0.15	0.4	18.86	1.4	0.05	1.4	11.1	2	<0.2
1092552	Rock	0.130	16	12	0.03	187	0.002	<20	0.45	0.007	0.16	0.5	18.70	1.5	<0.05	1.4	14.4	2	0.2
1092553	Rock	0.278	13	21	0.04	235	0.003	<20	0.59	0.007	0.18	0.9	29.15	2.2	<0.05	1.7	14.8	2	0.3
1092554	Rock	0.217	11	20	0.03	234	0.002	<20	0.48	0.004	0.15	0.6	49.46	1.7	0.06	1.6	15.9	2	0.3
1092555	Rock	0.364	11	20	0.03	243	0.003	<20	0.59	0.006	0.18	0.7	38.28	2.3	0.05	1.8	12.8	2	0.4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000567.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1092556	Rock	8.43	765	13.3	41.0	22.7	59	2.5	12.5	1.3	41	1.04	563.7	33.5	2.5	43	0.7	16.3	0.5	145	0.27
1092557	Rock	6.84	477	7.2	21.5	11.5	22	2.3	5.2	0.5	23	0.52	204.1	2.8	1.7	15	0.3	11.0	0.2	48	0.08
1092558	Rock	9.92	407	11.5	22.4	13.5	25	2.0	4.9	0.6	23	0.69	210.2	6.5	2.3	19	0.3	7.6	0.2	46	0.08
1092559	Rock	7.70	253	7.5	21.0	14.9	31	1.5	6.5	0.8	26	0.80	272.8	16.1	2.1	20	0.5	6.2	0.3	53	0.10
1092560	Rock	7.70	216	7.3	26.1	15.9	65	1.5	10.1	1.8	38	1.23	288.9	12.6	4.1	58	0.5	4.2	0.4	57	0.11
1092561	Rock	6.37	124	5.9	47.7	30.8	92	1.0	28.0	7.9	73	1.94	228.7	4.3	3.6	48	0.9	2.6	0.4	54	0.09
1092562	Rock	7.34	71	7.0	75.5	15.4	138	0.7	34.9	9.8	202	3.94	213.4	1.6	2.9	38	0.9	2.1	0.3	50	0.12
1094006	Rock	1.67	3	28.6	15.6	3.6	3599	0.1	133.5	27.8	240	1.69	90.3	1.9	1.0	258	8.5	2.7	<0.1	51	25.36

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000567.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1092556	Rock	0.248	12	21	0.03	231	0.003	<20	0.48	0.005	0.16	0.7	46.53	1.9	0.06	1.6	12.8	2	0.2
1092557	Rock	0.072	10	15	0.01	405	0.001	<20	0.25	0.002	0.09	0.2	13.01	0.4	<0.05	0.8	21.0	1	0.2
1092558	Rock	0.079	14	15	0.02	522	<0.001	<20	0.34	0.003	0.14	0.3	11.11	1.1	0.10	1.1	17.1	2	<0.2
1092559	Rock	0.129	13	13	0.02	577	0.001	<20	0.40	0.004	0.14	0.3	11.17	1.0	0.07	1.3	17.2	2	0.2
1092560	Rock	0.113	18	13	0.05	392	0.001	<20	0.49	0.006	0.18	0.2	9.02	0.7	0.12	1.4	12.2	2	<0.2
1092561	Rock	0.116	13	15	0.04	388	<0.001	<20	0.62	0.009	0.21	<0.1	7.53	0.4	0.10	2.4	9.7	2	<0.2
1092562	Rock	0.162	6	14	0.05	390	<0.001	<20	0.68	0.008	0.21	<0.1	4.32	0.3	0.10	3.0	10.5	2	<0.2
1094006	Rock	0.025	2	5	0.61	174	0.001	<20	0.17	0.005	0.08	<0.1	0.02	0.5	0.35	1.2	0.8	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000567.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1093525	Rock	0.91	<2	0.3	0.8	33.0	49	<0.1	1.3	1.6	114	1.27	71.6	2.4	13.7	18	<0.1	0.2	1.0	<2	0.17
REP 1093525	QC		<2																		
1093533	Rock	0.74	<2	1.4	196.6	4.7	578	0.3	74.0	9.5	239	17.21	50.9	3.9	2.2	<1	4.8	2.4	0.1	128	0.08
REP 1093533	QC		<2																		
1093537	Rock	0.74	16	0.3	3.5	1.7	50	0.1	10.8	2.6	106	0.65	24.7	11.8	0.5	12	0.7	0.7	<0.1	4	0.17
REP 1093537	QC			0.3	3.6	1.6	48	0.1	11.0	2.5	101	0.64	24.2	11.8	0.5	11	0.7	0.7	<0.1	4	0.16
1094007	Rock	2.08	3	0.1	20.1	1.9	16	<0.1	15.8	6.1	560	2.30	2.4	1.8	4.2	130	<0.1	<0.1	0.1	8	3.87
REP 1094007	QC			0.2	20.3	2.1	17	<0.1	16.0	6.2	564	2.35	2.4	4.7	4.4	136	<0.1	<0.1	0.1	9	3.91
1092552	Rock	9.29	434	15.0	29.6	15.9	67	1.7	12.9	1.9	21	1.11	299.3	16.5	3.5	32	0.4	8.0	0.5	96	0.08
REP 1092552	QC		454																		
Core Reject Duplicates																					
1093542	Rock	0.74	<2	0.4	4.6	6.8	84	<0.1	37.2	17.1	693	3.77	25.8	<0.5	19.0	16	<0.1	0.5	0.3	32	0.13
DUP 1093542	QC		<2	0.5	4.3	6.7	83	<0.1	37.1	18.9	674	3.65	28.8	<0.5	20.2	15	<0.1	0.6	0.3	31	0.13
1095960	Rock	0.64	64	3.3	4.3	68.0	9	0.1	1.0	0.1	22	0.38	1100	57.6	0.9	42	0.9	0.6	1.5	8	0.02
DUP 1095960	QC		62	3.4	4.3	69.1	8	0.1	0.9	0.1	22	0.38	1108	61.2	0.9	43	0.8	0.6	1.5	8	0.02
Reference Materials																					
STD DS8	Standard			12.5	104.7	115.5	299	1.5	37.4	7.3	587	2.37	24.9	111.7	6.2	62	2.0	3.8	6.1	40	0.69
STD DS8	Standard			13.7	115.9	140.2	318	1.8	40.0	7.8	628	2.53	27.3	113.6	7.4	70	2.5	4.9	6.3	42	0.73
STD OREAS45CA	Standard			0.7	478.1	20.6	58	0.3	233.5	84.0	874	15.23	3.3	35.3	6.7	14	<0.1	<0.1	0.2	195	0.39
STD OREAS45CA	Standard			0.9	513.9	23.7	60	0.3	257.2	96.1	917	16.36	3.8	40.8	8.1	16	0.2	<0.1	0.2	214	0.43
STD OXC88	Standard		200																		
STD OXC88	Standard		200																		
STD OXC88	Standard		190																		
STD OXC88	Standard		189																		
STD OXH82	Standard		1296																		
STD OXH82	Standard		1398																		
STD OXH82	Standard		1366																		
STD OXC88 Expected			203																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000567.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1093525	Rock	0.024	22	<1	0.02	662	<0.001	<20	0.37	0.022	0.18	<0.1	0.11	<0.1	0.06	1.3	<0.5	1	<0.2
REP 1093525	QC																		
1093533	Rock	0.269	1	60	<0.01	51	0.002	<20	0.45	<0.001	0.01	<0.1	0.23	<0.1	<0.05	3.9	6.2	<1	<0.2
REP 1093533	QC																		
1093537	Rock	0.015	3	4	0.02	374	<0.001	<20	0.07	<0.001	0.01	<0.1	0.38	<0.1	<0.05	0.4	<0.5	<1	<0.2
REP 1093537	QC	0.014	3	4	0.02	366	<0.001	<20	0.08	<0.001	0.01	<0.1	0.34	<0.1	<0.05	0.4	<0.5	<1	<0.2
1094007	Rock	0.022	10	5	1.75	613	0.001	<20	0.42	0.005	0.25	<0.1	<0.01	0.3	0.21	3.5	<0.5	<1	<0.2
REP 1094007	QC	0.024	10	7	1.79	631	0.001	<20	0.43	0.006	0.27	<0.1	<0.01	0.1	0.21	3.5	<0.5	1	<0.2
1092552	Rock	0.130	16	12	0.03	187	0.002	<20	0.45	0.007	0.16	0.5	18.70	1.5	<0.05	1.4	14.4	2	0.2
REP 1092552	QC																		
Core Reject Duplicates																			
1093542	Rock	0.036	49	37	0.80	86	0.081	<20	3.63	0.074	0.71	0.1	0.37	0.6	<0.05	2.8	<0.5	9	<0.2
DUP 1093542	QC	0.039	52	37	0.81	82	0.083	<20	3.61	0.064	0.71	0.1	0.11	0.5	<0.05	2.8	<0.5	9	<0.2
1095960	Rock	0.013	<1	1	<0.01	164	<0.001	<20	0.36	<0.001	0.23	0.1	1.34	0.3	0.06	0.3	1.2	<1	<0.2
DUP 1095960	QC	0.013	<1	1	<0.01	171	<0.001	<20	0.37	0.001	0.23	<0.1	1.47	0.3	0.06	0.3	1.0	<1	<0.2
Reference Materials																			
STD DS8	Standard	0.079	13	108	0.60	283	0.109	<20	0.90	0.086	0.39	2.7	0.16	4.9	0.17	1.9	5.0	4	5.2
STD DS8	Standard	0.083	15	116	0.64	295	0.117	<20	0.96	0.091	0.41	3.2	0.20	5.6	0.18	2.2	6.0	5	4.9
STD OREAS45CA	Standard	0.037	14	664	0.14	150	0.130	<20	3.43	0.010	0.07	<0.1	0.08	<0.1	<0.05	35.0	0.6	17	<0.2
STD OREAS45CA	Standard	0.039	17	709	0.14	164	0.140	<20	3.78	0.010	0.07	<0.1	0.03	<0.1	<0.05	36.8	0.5	19	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXC88 Expected																			

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000567.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
STD OXH82 Expected			1278																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		<2	0.1	2.3	3.6	53	<0.1	4.6	4.5	619	2.04	0.6	5.0	5.4	66	<0.1	0.1	0.2	38	0.49
G1	Prep Blank		<2	0.1	2.0	3.4	50	<0.1	4.0	4.2	585	2.03	0.8	4.0	5.5	63	<0.1	<0.1	0.2	37	0.54

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000567.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
STD OXH82 Expected																			
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																			
G1	Prep Blank	0.078	10	8	0.63	231	0.137	<20	1.02	0.080	0.51	<0.1	<0.01	0.4	<0.05	2.1	<0.5	5	<0.2
G1	Prep Blank	0.075	9	7	0.62	212	0.127	<20	0.97	0.077	0.48	<0.1	0.01	0.3	<0.05	1.9	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 19, 2011
Report Date: July 31, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11000649.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #4
P.O. Number
Number of Samples: 18

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	18	Crush, split and pulverize 250 g rock to 200 mesh			WHI
1DX3	18	1:1:1 Aqua Regia digestion ICP-MS analysis	30	Completed	VAN
G601	18	Fire Assay fusion Au by ICP-ES	30	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: July 31, 2011

CERTIFICATE OF ANALYSIS WHI11000649.1

Method		WGHT	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1095964	Rock	1.25	29.8	11.7	60.6	162	1.1	12.5	3.8	34	3.77	1243	9.4	1.4	27	0.5	48.4	0.5	19	0.02	1.031
1095965	Rock	1.32	46.1	330.1	38.1	1230	4.4	296.5	21.0	76	13.68	78.4	4.7	2.2	671	7.7	11.6	0.2	218	0.72	0.784
1095966	Rock	2.03	26.7	9.5	15.2	5	0.4	8.0	0.5	35	0.53	22.2	0.6	0.4	10	<0.1	7.5	<0.1	210	<0.01	0.019
1094010	Rock	1.99	1.0	14.9	4.8	22	0.1	21.1	6.6	1798	6.87	4.0	0.9	1.0	284	<0.1	0.4	<0.1	42	9.28	0.070
1094011	Rock	2.15	0.8	24.6	9.4	20	0.4	17.1	1.8	188	1.98	4.3	1.1	0.3	8	0.1	0.9	<0.1	16	0.06	0.034
1094012	Rock	1.82	0.5	35.3	1.6	90	0.1	37.9	5.5	274	3.98	3.9	<0.5	0.5	23	0.3	0.3	<0.1	11	1.91	0.021
1094013	Rock	1.47	10.9	10.5	8.8	154	1.4	13.4	2.8	57	3.80	70.6	0.7	2.5	31	0.3	2.8	0.1	25	0.05	0.529
1094014	Rock	1.46	0.8	8.5	32.9	127	<0.1	32.0	4.9	205	2.07	7.9	1.0	13.6	55	0.1	0.2	0.4	5	0.45	0.065
1094015	Rock	1.95	10.7	1.9	41.3	5	0.1	1.2	0.2	14	0.52	6.7	0.8	6.9	30	<0.1	4.7	0.7	18	0.04	0.025
1094017	Rock	1.32	0.7	22.0	34.0	331	0.2	46.2	10.9	419	2.74	5.4	0.6	13.0	36	0.6	0.1	0.6	6	0.32	0.061
1093565	Rock	2.21	0.6	2.7	5.7	28	<0.1	4.1	1.3	52	0.72	4.6	3.3	0.4	7	<0.1	0.3	<0.1	<2	<0.01	0.008
1093566	Rock	1.49	0.5	2.4	1.5	50	<0.1	9.1	4.2	225	1.89	2.0	0.9	0.5	4	0.1	0.2	<0.1	14	0.25	0.013
1093567	Rock	1.17	0.7	8.5	4.4	33	<0.1	7.3	1.4	107	0.91	4.0	0.9	0.4	60	<0.1	0.3	<0.1	18	0.11	0.068
1093568	Rock	1.18	0.6	2.1	3.8	14	<0.1	3.2	1.1	49	0.65	11.3	1.2	0.5	16	0.4	0.3	<0.1	6	0.06	0.010
1093569	Rock	1.00	0.3	1.4	0.6	23	0.3	3.5	0.7	118	0.18	2.4	<0.5	0.2	759	0.7	<0.1	<0.1	11	32.55	0.045
1093570	Rock	2.06	1.1	2.7	0.8	32	0.2	5.6	0.6	57	0.41	3.6	<0.5	0.2	897	1.0	0.4	<0.1	35	34.74	0.056
1093571	Rock	1.44	<0.1	3.5	<0.1	35	<0.1	4.7	0.7	59	0.20	5.2	<0.5	<0.1	198	0.5	<0.1	<0.1	<2	>40	0.037
1093572	Rock	1.26	<0.1	0.8	0.5	32	<0.1	4.9	0.5	65	0.17	4.9	<0.5	0.2	636	0.6	0.1	<0.1	6	>40	0.057

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: July 31, 2011

CERTIFICATE OF ANALYSIS WHI11000649.1

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	G6
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Au
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	gm/t
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.005
1095964	Rock	2	24	<0.01	784	0.005	5	0.25	0.001	0.08	2.1	1.76	5.2	0.9	0.13	2	>100	0.5	0.035
1095965	Rock	13	45	0.09	822	0.004	8	2.72	0.008	0.13	<0.1	0.36	7.8	0.2	0.14	2	21.6	<0.2	<0.005
1095966	Rock	1	11	<0.01	168	<0.001	3	0.12	<0.001	0.06	0.2	1.47	0.4	0.5	0.08	<1	8.9	<0.2	<0.005
1094010	Rock	2	18	2.36	355	0.001	2	0.45	0.013	0.04	<0.1	<0.01	5.6	<0.1	0.07	2	1.0	<0.2	<0.005
1094011	Rock	<1	9	<0.01	69	<0.001	2	0.23	0.002	0.05	<0.1	0.04	2.3	<0.1	0.06	<1	0.7	<0.2	<0.005
1094012	Rock	1	8	0.28	83	<0.001	2	0.24	0.001	0.01	<0.1	0.02	1.6	<0.1	0.06	<1	0.9	<0.2	<0.005
1094013	Rock	2	23	<0.01	560	0.003	3	0.21	0.004	0.09	<0.1	0.58	3.6	0.4	0.09	<1	11.1	<0.2	<0.005
1094014	Rock	33	2	0.10	442	<0.001	4	0.82	0.018	0.25	<0.1	0.33	1.5	0.1	<0.05	2	<0.5	<0.2	<0.005
1094015	Rock	25	3	<0.01	149	<0.001	7	0.49	0.002	0.25	<0.1	0.06	0.5	0.5	0.13	1	11.3	<0.2	<0.005
1094017	Rock	32	2	0.08	450	<0.001	3	0.82	0.012	0.24	<0.1	0.09	1.5	0.1	<0.05	1	1.2	<0.2	<0.005
1093565	Rock	1	5	<0.01	137	<0.001	3	0.08	<0.001	0.04	<0.1	0.08	0.2	<0.1	0.18	<1	<0.5	<0.2	<0.005
1093566	Rock	<1	6	0.16	42	0.001	1	0.22	<0.001	<0.01	<0.1	<0.01	0.9	<0.1	<0.05	<1	<0.5	<0.2	<0.005
1093567	Rock	2	10	0.04	2629	0.002	2	0.39	0.005	0.07	<0.1	<0.01	0.6	<0.1	0.06	1	<0.5	<0.2	<0.005
1093568	Rock	3	4	<0.01	159	<0.001	4	0.10	0.001	0.04	<0.1	0.33	0.2	<0.1	<0.05	<1	<0.5	<0.2	<0.005
1093569	Rock	5	10	0.14	588	<0.001	3	0.03	0.005	<0.01	<0.1	<0.01	0.7	<0.1	<0.05	<1	0.5	<0.2	<0.005
1093570	Rock	5	8	0.17	346	<0.001	3	0.06	0.004	0.02	<0.1	<0.01	0.7	<0.1	<0.05	<1	0.8	<0.2	<0.005
1093571	Rock	3	3	0.08	56	<0.001	<1	0.02	<0.001	<0.01	<0.1	<0.01	0.2	<0.1	0.09	<1	<0.5	<0.2	<0.005
1093572	Rock	8	5	0.15	129	<0.001	<1	0.03	<0.001	<0.01	<0.1	<0.01	0.5	<0.1	0.09	<1	<0.5	<0.2	<0.005

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: July 31, 2011

QUALITY CONTROL REPORT WHI11000649.1

	Method	WGHT	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1095965	Rock	1.32	46.1	330.1	38.1	1230	4.4	296.5	21.0	76	13.68	78.4	4.7	2.2	671	7.7	11.6	0.2	218	0.72	0.784
REP 1095965	QC		42.2	309.4	36.1	1164	4.1	280.4	19.9	72	12.88	72.9	6.3	2.0	622	7.4	11.5	0.1	206	0.68	0.729
1094013	Rock	1.47	10.9	10.5	8.8	154	1.4	13.4	2.8	57	3.80	70.6	0.7	2.5	31	0.3	2.8	0.1	25	0.05	0.529
REP 1094013	QC																				
Reference Materials																					
STD DS8	Standard		13.1	113.8	131.6	329	1.8	40.2	8.0	644	2.63	27.8	121.3	6.6	66	2.5	5.5	6.7	43	0.73	0.086
STD DS8	Standard		14.6	111.1	133.0	332	2.0	41.0	7.7	661	2.62	28.5	109.5	7.1	74	2.4	5.5	6.5	42	0.76	0.082
STD OXH82	Standard																				
STD OXH82	Standard																				
STD OXK79	Standard																				
STD OXK79	Standard																				
STD OXH82 Expected																					
STD OXK79 Expected																					
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
Prep Wash																					
G1	Prep Blank		0.2	2.4	3.6	51	<0.1	4.2	4.5	582	2.08	<0.5	2.6	5.0	64	<0.1	<0.1	0.1	37	0.52	0.071
G1	Prep Blank		0.2	2.1	3.0	49	<0.1	4.2	4.6	584	2.02	0.5	1.9	5.1	64	<0.1	<0.1	<0.1	38	0.56	0.082

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: July 31, 2011

QUALITY CONTROL REPORT WHI11000649.1

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	G6
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Au
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	gm/t
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.005
Pulp Duplicates																			
1095965	Rock	13	45	0.09	822	0.004	8	2.72	0.008	0.13	<0.1	0.36	7.8	0.2	0.14	2	21.6	<0.2	<0.005
REP 1095965	QC	12	44	0.08	738	0.004	8	2.54	0.008	0.13	<0.1	0.37	7.2	0.2	0.13	2	19.7	<0.2	
1094013	Rock	2	23	<0.01	560	0.003	3	0.21	0.004	0.09	<0.1	0.58	3.6	0.4	0.09	<1	11.1	<0.2	<0.005
REP 1094013	QC																		<0.005
Reference Materials																			
STD DS8	Standard	14	124	0.64	279	0.115	4	0.95	0.093	0.43	3.2	0.20	2.1	5.7	0.17	5	6.0	5.0	
STD DS8	Standard	17	122	0.64	298	0.120	3	1.00	0.106	0.44	3.0	0.20	2.3	5.5	0.16	5	6.7	5.5	
STD OXH82	Standard																		1.260
STD OXH82	Standard																		1.264
STD OXK79	Standard																		3.490
STD OXK79	Standard																		3.722
STD OXH82 Expected																			1.278
STD OXK79 Expected																			3.532
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	
BLK	Blank																		<0.005
BLK	Blank																		<0.005
BLK	Blank																		<0.005
BLK	Blank																		<0.005
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2	
Prep Wash																			
G1	Prep Blank	9	9	0.60	233	0.110	2	1.07	0.104	0.50	<0.1	<0.01	1.9	0.3	<0.05	5	<0.5	<0.2	<0.005
G1	Prep Blank	9	7	0.60	232	0.119	<1	1.12	0.125	0.48	<0.1	<0.01	2.0	0.3	<0.05	5	<0.5	<0.2	<0.005

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 20, 2011
Report Date: August 12, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11000675.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #5
P.O. Number
Number of Samples: 40

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
1DX3	40	1:1:1 Aqua Regia digestion ICP-MS analysis	30	Completed	VAN
G601	40	Fire Assay fusion Au by ICP-ES	30	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP	Store After 90 days Invoice for Storage
DISP-RJT	Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 12, 2011

CERTIFICATE OF ANALYSIS WHI11000675.1

Method		WGHT	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1094018	Rock	2.25	0.5	37.4	2.5	19	<0.1	208.8	31.0	1221	4.40	58.1	2.2	7.0	655	<0.1	0.8	<0.1	55	10.05	0.268
1094021	Rock	1.16	9.7	15.3	10.8	87	0.1	31.0	3.2	388	0.51	16.5	<0.5	0.6	815	0.8	2.5	<0.1	31	28.59	0.014
1094025	Rock	2.51	0.8	25.4	1.8	109	<0.1	7.2	1.4	606	2.32	5.5	0.6	0.4	1259	4.8	0.6	<0.1	15	13.07	0.022
1094026	Rock	1.14	5.2	10.7	36.9	471	0.2	27.8	3.2	73	2.33	35.5	1.7	14.3	<1	0.7	2.9	0.6	7	0.14	0.059
1094027	Rock	1.47	3.2	25.7	24.1	80	0.4	8.1	0.7	17	1.73	146.1	5.6	15.0	58	1.7	3.4	0.7	25	0.18	0.091
1094028	Rock	1.06	68.6	66.3	5.8	1050	0.8	75.8	8.7	133	8.27	73.4	2.0	1.8	14	8.7	16.7	0.1	118	0.19	0.047
1094029	Rock	1.55	2.0	19.8	40.7	28	0.4	2.9	0.4	11	1.59	20.2	1.9	14.6	216	0.4	1.4	0.6	19	0.05	0.205
1094031	Rock	1.22	27.8	26.8	14.4	15	0.5	4.4	0.3	30	2.10	59.1	2.3	2.3	406	<0.1	6.1	<0.1	47	0.05	0.125
1094032	Rock	0.90	2.6	78.7	52.5	125	<0.1	12.9	2.8	58	2.23	35.9	3.0	13.3	107	0.6	1.0	0.8	13	0.04	0.067
1094033	Rock	0.82	16.7	29.2	46.4	187	0.7	30.7	5.4	62	3.12	35.3	2.3	5.9	43	0.5	6.6	0.3	50	0.01	0.032
1094034	Rock	0.93	3.8	14.6	34.7	47	0.1	6.2	1.1	42	0.93	17.5	0.7	1.3	12	0.3	1.4	<0.1	11	0.03	0.014
1094035	Rock	1.14	2.7	1.5	33.7	3	0.1	0.5	0.2	20	0.77	34.9	<0.5	14.5	25	<0.1	2.0	0.5	3	<0.01	0.020
1094037	Rock	1.21	167.5	12.5	17.0	8	1.5	5.3	0.2	27	1.38	79.2	<0.5	2.8	23	0.3	16.7	<0.1	173	<0.01	0.014
1094038	Rock	1.24	16.3	5.4	52.0	39	0.1	1.3	0.2	18	2.28	265.3	3.5	14.5	25	<0.1	6.0	0.8	69	<0.01	0.056
1094039	Rock	1.15	51.5	3.2	50.6	6	0.2	0.6	<0.1	10	1.75	278.4	24.1	13.0	35	0.3	7.6	0.3	169	<0.01	0.060
1094040	Rock	1.20	32.8	6.9	38.5	5	0.4	1.4	<0.1	12	1.86	345.1	13.0	10.0	46	0.9	16.7	1.2	84	<0.01	0.064
1095962	Rock	0.81	24.5	34.3	8.7	164	<0.1	76.9	6.8	304	4.09	33.1	2.3	2.1	378	0.7	1.6	<0.1	33	12.45	0.054
1095963	Rock	0.68	51.8	43.8	11.0	514	0.2	99.4	7.7	357	6.68	78.9	2.8	1.2	91	3.0	24.8	<0.1	180	3.90	0.090
1093801	Rock	0.71	29.9	18.8	27.9	8	1.5	4.0	0.1	16	3.11	323.3	4.3	3.0	207	0.3	21.9	0.1	187	0.07	0.765
1093802	Rock	1.56	2.0	10.7	15.6	3	1.4	3.8	0.2	18	0.75	30.5	27.2	0.4	29	<0.1	9.3	<0.1	36	<0.01	0.033
1093573	Rock	0.92	2.2	3.1	6.9	13	0.6	3.4	0.3	26	0.44	12.3	2.5	0.3	15	0.2	2.2	<0.1	21	<0.01	0.004
1093574	Rock	0.80	1.1	5.2	14.5	4	0.7	3.1	0.2	29	0.43	15.4	5.4	0.3	13	<0.1	6.2	<0.1	23	<0.01	0.009
1093575	Rock	0.75	2.1	6.2	13.0	3	1.0	3.5	0.5	28	0.64	13.0	7.7	0.6	46	<0.1	3.5	<0.1	19	0.01	0.025
1093576	Rock	0.81	0.7	31.5	1.5	171	<0.1	54.1	11.8	184	1.87	15.8	5.7	0.6	19	1.7	0.7	<0.1	6	0.36	0.023
1093577	Rock	0.97	1.5	3.6	12.3	25	0.1	8.1	1.7	45	0.77	59.9	21.3	0.4	3	0.2	0.8	<0.1	8	<0.01	0.011
1093578	Rock	0.76	0.7	18.4	6.3	21	0.3	20.0	7.2	857	2.51	6.8	2.6	2.1	599	0.1	0.5	0.1	9	7.43	0.024
1093579	Rock	0.75	0.6	100.1	6.8	70	0.1	476.9	61.7	2063	10.31	8.3	3.3	11.5	500	1.0	0.2	<0.1	180	4.51	0.540
1093580	Rock	0.87	0.2	1.3	1.4	18	0.1	4.4	0.9	58	0.41	17.4	10.1	0.5	170	0.2	0.5	<0.1	2	7.87	0.011
1093581	Rock	0.78	0.5	4.7	6.4	44	0.2	14.4	2.3	75	0.71	24.9	6.2	0.7	49	0.4	0.8	<0.1	5	1.39	0.033
1093582	Rock	0.89	0.5	6.2	1.1	27	<0.1	10.1	1.7	39	0.92	87.6	6.7	0.4	2	<0.1	0.9	<0.1	4	0.02	0.016

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 12, 2011

CERTIFICATE OF ANALYSIS WHI11000675.1

Method		1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	G6
Analyte		La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Au
Unit		ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	gm/t
MDL		1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.005
1094018	Rock	31	91	5.30	2060	0.003	14	0.37	0.010	0.12	<0.1	0.11	9.6	<0.1	0.08	<1	<0.5	<0.2	<0.005
1094021	Rock	9	6	0.39	370	0.001	2	0.07	0.002	0.03	0.1	0.10	1.8	0.1	0.05	<1	0.8	<0.2	<0.005
1094025	Rock	2	8	4.29	299	0.001	4	0.06	0.003	0.03	<0.1	0.22	0.8	<0.1	<0.05	<1	<0.5	<0.2	<0.005
1094026	Rock	40	2	0.03	337	<0.001	14	0.59	<0.001	0.23	<0.1	0.38	1.3	0.3	<0.05	<1	6.2	<0.2	<0.005
1094027	Rock	39	14	0.06	619	<0.001	17	0.49	<0.001	0.24	<0.1	0.41	2.0	0.3	0.22	3	6.5	<0.2	<0.005
1094028	Rock	10	15	0.03	442	<0.001	9	0.53	<0.001	0.13	0.6	0.77	1.8	1.2	0.07	1	11.0	<0.2	0.020
1094029	Rock	39	12	0.01	328	<0.001	5	0.63	0.002	0.24	<0.1	0.07	2.1	0.3	0.10	1	2.2	<0.2	<0.005
1094031	Rock	4	18	<0.01	253	0.001	4	0.24	0.002	0.32	0.1	0.65	1.0	0.6	0.51	<1	13.7	<0.2	<0.005
1094032	Rock	36	6	0.01	2578	<0.001	6	0.53	0.003	0.24	0.1	0.37	2.5	<0.1	0.10	<1	1.4	<0.2	<0.005
1094033	Rock	23	10	0.02	228	<0.001	8	0.48	0.003	0.29	<0.1	0.29	3.5	0.4	0.13	1	6.6	<0.2	<0.005
1094034	Rock	1	21	<0.01	370	<0.001	3	0.11	0.002	0.06	<0.1	0.63	0.9	<0.1	<0.05	<1	1.0	<0.2	<0.005
1094035	Rock	30	4	<0.01	580	<0.001	14	0.42	0.002	0.23	<0.1	0.94	1.3	0.4	0.19	1	2.1	<0.2	<0.005
1094037	Rock	2	33	0.01	175	0.001	8	0.11	0.001	0.20	0.2	1.33	0.6	1.0	0.31	<1	33.6	0.2	0.007
1094038	Rock	30	8	<0.01	436	<0.001	12	0.42	0.002	0.25	0.1	0.59	0.7	1.3	0.28	2	10.6	<0.2	<0.005
1094039	Rock	30	9	<0.01	425	<0.001	11	0.40	0.001	0.20	0.2	1.76	0.7	1.2	0.17	2	19.6	<0.2	<0.005
1094040	Rock	29	6	<0.01	354	<0.001	10	0.49	0.003	0.19	1.3	5.71	0.8	1.0	0.17	3	33.1	<0.2	0.023
1095962	Rock	5	8	3.93	220	<0.001	7	0.19	0.007	0.09	<0.1	0.31	2.3	0.4	0.82	<1	3.3	<0.2	0.014
1095963	Rock	4	9	2.23	435	<0.001	7	0.20	0.004	0.09	<0.1	0.81	2.2	0.8	0.17	<1	24.2	<0.2	<0.005
1093801	Rock	7	60	0.01	324	0.004	10	0.45	0.001	0.21	0.3	4.56	10.1	0.7	0.32	3	18.5	0.2	<0.005
1093802	Rock	<1	20	<0.01	1209	<0.001	5	0.23	0.002	0.18	<0.1	1.54	1.0	0.1	0.16	1	4.9	<0.2	0.100
1093573	Rock	<1	29	<0.01	378	<0.001	3	0.13	<0.001	0.07	<0.1	1.54	0.2	<0.1	<0.05	<1	5.4	<0.2	0.164
1093574	Rock	<1	23	<0.01	380	<0.001	4	0.14	0.001	0.08	<0.1	1.70	0.4	<0.1	<0.05	<1	2.1	<0.2	0.078
1093575	Rock	<1	45	<0.01	741	0.001	9	0.22	<0.001	0.13	<0.1	2.08	0.9	0.1	0.18	<1	7.8	<0.2	0.031
1093576	Rock	2	23	0.03	128	<0.001	4	0.49	<0.001	0.02	<0.1	0.10	1.1	<0.1	0.08	<1	2.4	<0.2	<0.005
1093577	Rock	2	34	<0.01	26	<0.001	5	0.06	<0.001	0.01	<0.1	0.08	0.3	<0.1	<0.05	<1	<0.5	<0.2	0.012
1093578	Rock	8	7	3.69	1972	<0.001	7	0.26	0.004	0.15	<0.1	0.45	4.4	<0.1	0.15	<1	<0.5	<0.2	<0.005
1093579	Rock	54	606	4.83	2588	0.010	2	3.20	<0.001	0.05	<0.1	0.33	23.4	<0.1	0.10	8	<0.5	<0.2	<0.005
1093580	Rock	2	11	0.03	91	<0.001	2	0.03	<0.001	<0.01	<0.1	0.48	0.3	<0.1	<0.05	<1	<0.5	<0.2	0.011
1093581	Rock	4	24	0.05	109	<0.001	3	0.14	0.004	0.02	<0.1	0.44	0.8	<0.1	<0.05	<1	<0.5	<0.2	<0.005
1093582	Rock	3	32	<0.01	57	<0.001	7	0.08	0.004	0.01	<0.1	0.13	0.4	<0.1	<0.05	<1	<0.5	<0.2	<0.005

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 12, 2011

CERTIFICATE OF ANALYSIS WHI11000675.1

Method		WGHT	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093583	Rock	0.91	0.5	8.9	6.0	53	0.2	25.7	4.8	123	1.17	24.8	2.4	1.0	96	0.4	0.4	<0.1	12	1.43	0.053
1093584	Rock	1.26	1.9	1.9	7.0	2	0.5	1.2	0.2	20	0.36	5.7	2.3	0.2	4	<0.1	1.3	<0.1	13	<0.01	0.006
1093585	Rock	0.93	1.0	1.6	0.9	1	0.2	1.2	0.2	26	0.32	3.0	3.3	<0.1	3	<0.1	1.1	<0.1	6	<0.01	0.002
1093586	Rock	1.00	0.3	1.6	2.7	9	<0.1	5.5	1.3	153	1.64	32.1	1.0	0.6	67	0.1	0.4	<0.1	7	3.28	0.018
1093587	Rock	0.91	0.2	1.8	1.9	7	0.1	5.3	1.2	103	0.54	15.6	6.6	0.7	503	<0.1	1.0	<0.1	4	14.69	0.025
1093588	Rock	0.94	0.3	1.8	3.4	3	<0.1	1.3	0.3	34	0.38	12.8	170.4	0.7	8	<0.1	0.4	<0.1	<2	0.04	0.003
1093589	Rock	0.99	0.2	2.4	3.4	3	<0.1	1.3	0.3	23	0.38	24.7	3.1	0.5	16	<0.1	0.6	<0.1	3	<0.01	0.006
1093590	Rock	0.77	0.7	70.9	3.9	34	0.4	10.6	1.0	11	0.90	2.8	2.9	1.6	14	0.2	0.3	0.2	22	0.02	0.026
1093591	Rock	0.80	0.1	1.1	0.9	20	<0.1	4.3	1.2	241	3.89	1.6	<0.5	0.3	97	<0.1	<0.1	<0.1	3	6.68	0.007
1093592	Rock	1.13	0.4	15.1	2.0	28	<0.1	14.1	2.5	57	0.90	3.7	0.7	0.3	4	<0.1	0.2	<0.1	4	0.01	0.010

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 12, 2011

CERTIFICATE OF ANALYSIS WHI11000675.1

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	G6
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Au
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	gm/t
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.005
1093583	Rock	4	32	0.09	433	<0.001	8	0.18	<0.001	0.02	<0.1	0.29	1.6	<0.1	0.05	<1	<0.5	<0.2	0.007
1093584	Rock	<1	35	<0.01	259	<0.001	4	0.13	<0.001	0.07	<0.1	1.82	0.2	<0.1	<0.05	<1	3.4	<0.2	0.008
1093585	Rock	<1	20	<0.01	64	<0.001	3	0.02	0.002	<0.01	<0.1	0.14	<0.1	<0.1	<0.05	<1	1.4	<0.2	<0.005
1093586	Rock	4	32	0.39	120	<0.001	2	0.07	<0.001	<0.01	<0.1	0.08	0.5	<0.1	0.05	<1	<0.5	<0.2	<0.005
1093587	Rock	4	8	0.07	609	<0.001	4	0.07	0.003	0.02	<0.1	0.44	0.6	<0.1	<0.05	<1	<0.5	<0.2	0.007
1093588	Rock	3	25	<0.01	64	<0.001	3	0.07	<0.001	0.03	<0.1	0.24	<0.1	<0.1	<0.05	<1	0.5	<0.2	0.150
1093589	Rock	2	26	<0.01	82	<0.001	2	0.08	<0.001	0.04	<0.1	0.36	0.2	0.1	<0.05	<1	<0.5	<0.2	<0.005
1093590	Rock	1	22	0.10	556	<0.001	6	0.73	0.010	0.17	<0.1	0.07	3.5	<0.1	<0.05	2	1.3	<0.2	0.029
1093591	Rock	3	11	1.67	186	<0.001	2	0.03	0.003	<0.01	<0.1	0.02	0.5	<0.1	<0.05	<1	<0.5	<0.2	<0.005
1093592	Rock	<1	27	<0.01	609	<0.001	1	0.13	<0.001	0.01	<0.1	0.03	0.9	<0.1	<0.05	<1	0.7	<0.2	<0.005

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 12, 2011

QUALITY CONTROL REPORT WHI11000675.1

	Method	WGHT	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
REP 1094025	QC		0.7	25.0	1.8	106	<0.1	7.4	1.4	611	2.34	5.1	<0.5	0.4	1231	5.3	0.7	<0.1	16	12.98	0.023
1094029	Rock	1.55	2.0	19.8	40.7	28	0.4	2.9	0.4	11	1.59	20.2	1.9	14.6	216	0.4	1.4	0.6	19	0.05	0.205
REP 1094029	QC																				
1093591	Rock	0.80	0.1	1.1	0.9	20	<0.1	4.3	1.2	241	3.89	1.6	<0.5	0.3	97	<0.1	<0.1	<0.1	3	6.68	0.007
REP 1093591	QC																				
Core Reject Duplicates																					
1094025	Rock	2.51	0.8	25.4	1.8	109	<0.1	7.2	1.4	606	2.32	5.5	0.6	0.4	1259	4.8	0.6	<0.1	15	13.07	0.022
DUP 1094025	QC		0.8	25.4	14.2	106	0.1	6.8	1.3	576	2.25	5.4	<0.5	0.4	1241	5.0	0.7	<0.1	15	12.84	0.024
1093590	Rock	0.77	0.7	70.9	3.9	34	0.4	10.6	1.0	11	0.90	2.8	2.9	1.6	14	0.2	0.3	0.2	22	0.02	0.026
DUP 1093590	QC		0.8	70.7	4.1	34	0.4	10.3	1.1	13	0.92	3.0	2.2	1.6	15	0.1	0.3	0.2	25	<0.01	0.027
Reference Materials																					
STD DS8	Standard		13.6	108.8	110.4	323	1.9	37.5	7.7	610	2.62	28.4	114.3	6.6	64	2.2	5.3	6.3	42	0.76	0.082
STD DS8	Standard		13.6	111.2	112.2	319	1.8	37.8	7.5	624	2.58	27.8	125.6	6.4	67	2.7	5.1	6.3	42	0.77	0.083
STD DS8	Standard		14.6	123.8	118.9	354	2.0	42.8	8.7	699	2.80	30.0	132.8	6.3	62	2.5	4.5	6.6	46	0.76	0.093
STD DS8	Standard		12.9	114.3	129.9	312	1.7	38.8	7.7	609	2.47	25.4	112.5	7.1	67	2.1	5.7	7.3	44	0.71	0.078
STD OXH82	Standard																				
STD OXH82	Standard																				
STD OXH82	Standard																				
STD OXK79	Standard																				
STD OXK79	Standard																				
STD OXK79	Standard																				
STD OXH82 Expected																					
STD OXK79 Expected																					
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 12, 2011

QUALITY CONTROL REPORT WHI11000675.1

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	G6
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Au
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	gm/t
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.005
Pulp Duplicates																			
REP 1094025	QC	2	8	4.27	304	<0.001	4	0.07	0.003	0.03	<0.1	0.20	0.9	<0.1	<0.05	<1	<0.5	<0.2	
1094029	Rock	39	12	0.01	328	<0.001	5	0.63	0.002	0.24	<0.1	0.07	2.1	0.3	0.10	1	2.2	<0.2	<0.005
REP 1094029	QC																		<0.005
1093591	Rock	3	11	1.67	186	<0.001	2	0.03	0.003	<0.01	<0.1	0.02	0.5	<0.1	<0.05	<1	<0.5	<0.2	<0.005
REP 1093591	QC																		<0.005
Core Reject Duplicates																			
1094025	Rock	2	8	4.29	299	0.001	4	0.06	0.003	0.03	<0.1	0.22	0.8	<0.1	<0.05	<1	<0.5	<0.2	<0.005
DUP 1094025	QC	2	8	4.18	296	<0.001	3	0.07	0.002	0.03	<0.1	0.21	0.8	<0.1	<0.05	<1	<0.5	<0.2	<0.005
1093590	Rock	1	22	0.10	556	<0.001	6	0.73	0.010	0.17	<0.1	0.07	3.5	<0.1	<0.05	2	1.3	<0.2	0.029
DUP 1093590	QC	1	24	0.10	627	<0.001	6	0.80	0.011	0.20	<0.1	0.06	3.6	<0.1	<0.05	3	0.8	<0.2	0.028
Reference Materials																			
STD DS8	Standard	15	116	0.62	281	0.118	2	0.95	0.091	0.44	3.0	0.21	2.4	5.4	0.17	5	5.0	5.0	
STD DS8	Standard	16	116	0.63	291	0.115	3	0.97	0.094	0.43	2.9	0.24	2.4	5.6	0.16	5	5.5	4.9	
STD DS8	Standard	15	132	0.68	290	0.107	3	1.03	0.098	0.47	3.0	0.25	2.4	6.2	0.19	5	6.3	5.8	
STD DS8	Standard	15	120	0.61	275	0.122	3	0.94	0.091	0.41	3.1	0.21	2.2	5.4	0.17	4	5.2	5.0	
STD OXH82	Standard																		1.336
STD OXH82	Standard																		1.331
STD OXH82	Standard																		1.345
STD OXK79	Standard																		3.747
STD OXK79	Standard																		3.657
STD OXK79	Standard																		3.769
STD OXH82 Expected																			1.278
STD OXK79 Expected																			3.532
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2	
BLK	Blank																		<0.005
BLK	Blank																		<0.005
BLK	Blank																		<0.005

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 12, 2011

QUALITY CONTROL REPORT WHI11000675.1

		WGHT	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
BLK	Blank																				
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank																				
BLK	Blank																				
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
Prep Wash																					
G1	Prep Blank		0.1	1.9	3.1	58	<0.1	4.3	5.3	689	2.33	1.0	2.6	5.3	63	<0.1	<0.1	<0.1	45	0.59	0.093
G1	Prep Blank		0.1	3.1	53.5	73	0.2	4.5	4.9	655	2.31	1.5	4.7	5.0	63	0.8	0.1	<0.1	43	0.54	0.090

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
262 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 12, 2011

QUALITY CONTROL REPORT WHI11000675.1

		1DX30 La ppm 1	1DX30 Cr ppm 1	1DX30 Mg % 0.01	1DX30 Ba ppm 1	1DX30 Ti % 0.001	1DX30 B ppm 1	1DX30 Al % 0.01	1DX30 Na % 0.001	1DX30 K % 0.01	1DX30 W ppm 0.1	1DX30 Hg ppm 0.01	1DX30 Sc ppm 0.1	1DX30 Tl ppm 0.1	1DX30 S % 0.05	1DX30 Ga ppm 1	1DX30 Se ppm 0.5	1DX30 Te ppm 0.2	G6 Au gm/t 0.005
BLK	Blank																		<0.005
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2	
BLK	Blank																		<0.005
BLK	Blank																		<0.005
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2	
Prep Wash																			
G1	Prep Blank	11	17	0.69	268	0.128	2	1.26	0.132	0.61	<0.1	<0.01	2.5	0.3	<0.05	6	<0.5	<0.2	0.008
G1	Prep Blank	10	16	0.67	263	0.126	2	1.14	0.098	0.57	<0.1	<0.01	2.1	0.2	<0.05	6	<0.5	<0.2	<0.005

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 22, 2011
Report Date: September 04, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11000695.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #6
P.O. Number
Number of Samples: 56

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	56	Crush, split and pulverize 250 g rock to 200 mesh			WHI
G601	56	Fire Assay fusion Au by ICP-ES	30	Completed	VAN
1DX1	56	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 04, 2011

CERTIFICATE OF ANALYSIS WHI11000695.1

	Method	WGHT	G6	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.005	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1093593	Rock	0.78	<0.005	3.3	10.3	5.9	5	0.6	9.1	0.2	21	0.51	6.5	<0.5	0.6	25	0.2	1.1	0.3	62	0.02
1093594	Rock	1.56	<0.005	0.5	10.8	2.1	5	<0.1	3.8	0.2	26	0.40	3.5	<0.5	0.4	19	<0.1	0.3	<0.1	32	0.12
1093595	Rock	0.99	<0.005	5.5	13.2	9.1	9	0.3	9.8	0.2	28	0.46	5.0	0.7	0.3	19	<0.1	0.7	0.2	51	0.03
1093596	Rock	0.90	<0.005	0.2	7.2	2.0	32	<0.1	20.2	5.7	2031	4.30	35.2	<0.5	2.6	258	<0.1	<0.1	<0.1	10	10.33
1093597	Rock	0.94	<0.005	0.1	15.6	2.4	17	<0.1	16.2	5.5	155	2.08	8.2	1.1	6.4	50	<0.1	<0.1	0.3	10	0.95
1093598	Rock	1.00	<0.005	0.1	17.3	6.4	19	<0.1	20.6	7.5	995	3.50	11.4	<0.5	3.6	416	<0.1	0.1	0.1	9	7.55
1093599	Rock	1.15	<0.005	0.2	34.1	3.3	37	0.5	20.7	5.9	764	3.41	2.5	1.2	3.7	765	<0.1	0.1	0.2	14	4.40
1093600	Rock	0.65	<0.005	5.9	3.3	47.8	6	1.1	0.7	0.1	12	0.51	30.9	9.1	11.5	38	<0.1	8.2	0.6	18	0.02
1093601	Rock	0.84	<0.005	0.1	16.7	1.3	31	<0.1	21.2	6.5	1395	4.55	11.5	1.3	3.7	438	0.3	0.1	0.1	11	5.71
1090885	Rock	0.99	<0.005	1.6	47.7	5.7	139	0.2	28.3	5.2	144	4.26	66.7	2.1	9.2	16	1.4	2.3	0.2	58	0.02
1095401	Rock	1.29	<0.005	2.3	2.0	0.2	57	<0.1	11.7	3.0	150	0.66	3.0	2.9	0.4	43	0.2	3.3	0.2	9	2.14
1095402	Rock	1.40	<0.005	2.6	58.1	4.6	41	0.4	1.9	0.2	16	6.04	68.9	2.5	0.4	132	0.2	5.7	<0.1	343	0.03
1095403	Rock	1.21	<0.005	1.2	37.0	5.4	15	0.3	0.9	0.1	21	2.07	21.6	3.0	0.3	58	<0.1	2.8	0.2	70	0.01
1095404	Rock	1.07	<0.005	3.4	67.2	65.8	52	0.2	3.3	0.3	18	5.73	57.0	2.4	0.5	93	0.2	10.3	<0.1	234	0.02
1095405	Rock	1.24	<0.005	11.4	19.4	14.5	2	1.7	0.4	0.1	19	2.12	130.9	2.5	0.2	6	<0.1	7.9	0.3	32	<0.01
1095406	Rock	1.46	<0.005	0.3	10.1	2.2	2	0.3	0.8	0.1	20	0.74	5.5	0.9	0.1	10	<0.1	2.3	<0.1	16	<0.01
1095407	Rock	1.60	<0.005	25.8	31.6	2.3	22	0.9	4.0	0.2	20	1.73	164.5	4.2	0.3	65	0.1	11.8	<0.1	106	<0.01
1094020	Rock	1.22	<0.005	1.3	53.0	5.2	14	0.1	177.8	32.7	1288	3.77	192.1	<0.5	9.4	494	0.1	2.1	<0.1	80	13.33
1094022	Rock	1.86	<0.005	0.4	43.5	3.3	29	<0.1	235.8	35.5	1290	5.04	114.1	<0.5	8.1	1087	<0.1	1.1	<0.1	60	13.30
1094023	Rock	1.53	<0.005	38.2	81.5	19.8	1013	1.0	149.2	11.1	54	10.01	38.7	<0.5	5.4	124	6.5	5.6	<0.1	136	0.34
1094019	Rock	2.27	<0.005	6.0	70.1	31.2	11	0.5	392.8	47.3	754	6.61	63.2	<0.5	13.1	474	0.1	3.7	<0.1	58	18.90
1093602	Rock	0.96	<0.005	0.2	0.5	0.2	14	<0.1	4.6	1.9	941	5.82	<0.5	<0.5	<0.1	234	<0.1	<0.1	<0.1	<2	18.74
1093603	Rock	0.97	<0.005	0.2	0.9	0.8	11	<0.1	6.3	2.6	592	4.25	2.6	0.6	0.5	359	<0.1	0.3	<0.1	10	16.71
1093604	Rock	1.12	<0.005	0.2	5.7	0.6	9	<0.1	3.4	1.3	209	1.47	0.7	0.8	0.5	564	0.1	0.1	0.1	4	3.90
1093605	Rock	1.20	0.012	0.5	69.2	4.1	156	<0.1	28.2	6.5	120	1.62	5.8	6.6	1.0	8	<0.1	0.7	<0.1	8	0.03
1093606	Rock	1.00	0.005	0.5	26.0	0.9	27	<0.1	6.5	0.9	28	0.49	1.7	5.8	0.4	6	<0.1	0.2	<0.1	4	0.01
1093607	Rock	1.01	0.012	5.0	29.8	3.3	192	0.8	16.9	2.1	169	0.86	4.0	1.6	0.8	300	6.7	1.5	<0.1	66	23.11
1093608	Rock	1.16	<0.005	0.7	5.1	0.9	43	0.2	3.6	0.5	42	0.30	1.7	<0.5	0.1	50	0.9	0.3	<0.1	3	2.95
1093609	Rock	1.04	<0.005	1.2	4.3	1.1	25	<0.1	4.2	1.0	64	0.23	3.1	<0.5	0.3	712	<0.1	0.4	<0.1	8	37.46
1093610	Rock	1.12	<0.005	0.3	0.6	<0.1	2	<0.1	1.3	0.8	536	3.23	0.7	<0.5	0.2	133	<0.1	0.1	<0.1	5	18.54

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 04, 2011

CERTIFICATE OF ANALYSIS WHI11000695.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093593	Rock	0.045	1	11	0.01	694	<0.001	<20	0.10	<0.001	0.06	<0.1	0.15	0.2	<0.1	0.05	<1	2.5	<0.2
1093594	Rock	0.084	3	11	<0.01	54	<0.001	<20	0.08	0.002	0.03	<0.1	0.06	0.4	<0.1	<0.05	<1	<0.5	<0.2
1093595	Rock	0.016	<1	8	0.01	58	<0.001	<20	0.08	<0.001	0.04	<0.1	0.24	0.2	<0.1	<0.05	<1	1.1	<0.2
1093596	Rock	0.020	14	6	4.03	426	<0.001	<20	0.30	0.011	0.24	<0.1	0.02	3.2	<0.1	0.05	<1	<0.5	<0.2
1093597	Rock	0.014	18	7	0.50	1486	<0.001	<20	0.56	0.003	0.37	<0.1	0.02	3.4	0.1	0.12	2	<0.5	<0.2
1093598	Rock	0.011	11	8	3.23	563	0.001	<20	0.35	0.008	0.26	<0.1	0.04	3.6	<0.1	0.24	<1	<0.5	<0.2
1093599	Rock	0.045	14	10	2.09	165	0.001	<20	0.66	0.004	0.30	<0.1	0.03	4.8	0.1	0.58	2	1.1	<0.2
1093600	Rock	0.019	34	<1	0.02	975	<0.001	<20	0.29	<0.001	0.20	0.4	5.34	0.2	0.7	0.12	<1	7.6	<0.2
1093601	Rock	0.022	10	6	2.59	2694	0.001	<20	0.40	0.006	0.33	<0.1	<0.01	4.2	<0.1	0.12	1	<0.5	<0.2
1090885	Rock	0.042	27	23	0.69	176	0.005	<20	2.11	0.026	0.28	<0.1	0.22	2.6	0.5	0.21	6	1.9	<0.2
1095401	Rock	0.022	<1	5	0.23	129	<0.001	<20	0.09	0.002	0.04	<0.1	0.07	0.9	<0.1	<0.05	<1	<0.5	<0.2
1095402	Rock	0.225	3	87	<0.01	531	<0.001	<20	0.35	<0.001	0.09	<0.1	0.10	6.8	<0.1	0.11	3	3.8	<0.2
1095403	Rock	0.059	1	26	<0.01	239	<0.001	<20	0.19	0.002	0.08	<0.1	0.02	1.7	<0.1	0.06	2	2.6	<0.2
1095404	Rock	0.193	3	68	<0.01	306	<0.001	<20	0.30	0.001	0.07	<0.1	0.02	4.8	<0.1	0.10	4	3.0	<0.2
1095405	Rock	0.015	<1	8	<0.01	446	<0.001	<20	0.11	0.001	0.04	<0.1	0.66	0.4	<0.1	<0.05	2	9.4	<0.2
1095406	Rock	0.011	<1	18	<0.01	186	<0.001	<20	0.09	0.002	0.02	<0.1	0.16	0.4	<0.1	<0.05	<1	1.6	<0.2
1095407	Rock	0.083	<1	32	0.01	959	<0.001	<20	0.31	<0.001	0.09	<0.1	0.52	1.7	0.2	<0.05	1	18.8	<0.2
1094020	Rock	0.431	67	115	4.59	1638	0.003	<20	0.57	0.008	0.20	<0.1	1.84	14.2	0.2	<0.05	2	<0.5	<0.2
1094022	Rock	0.313	37	123	5.86	1105	0.003	<20	0.71	0.008	0.16	<0.1	0.06	11.0	<0.1	<0.05	2	<0.5	<0.2
1094023	Rock	0.313	12	40	0.05	235	0.010	<20	0.48	0.005	0.19	0.3	4.59	5.2	0.5	0.43	7	9.4	<0.2
1094019	Rock	0.416	48	94	0.95	18	0.003	<20	0.75	0.007	0.24	<0.1	18.97	12.2	0.6	5.70	2	2.4	<0.2
1093602	Rock	0.003	<1	2	7.82	129	<0.001	<20	0.02	0.015	0.01	<0.1	0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2
1093603	Rock	0.017	1	2	7.16	133	<0.001	<20	0.13	0.017	0.08	<0.1	0.06	1.3	<0.1	<0.05	<1	<0.5	<0.2
1093604	Rock	0.025	<1	7	1.81	41	<0.001	<20	0.07	0.002	0.04	<0.1	0.02	3.5	<0.1	<0.05	<1	<0.5	<0.2
1093605	Rock	0.021	6	6	0.03	84	<0.001	<20	0.24	<0.001	0.14	<0.1	0.11	1.6	<0.1	<0.05	1	2.6	<0.2
1093606	Rock	0.003	<1	16	0.01	40	<0.001	<20	0.08	<0.001	0.04	<0.1	0.02	0.5	<0.1	<0.05	<1	<0.5	<0.2
1093607	Rock	2.216	17	8	0.95	247	0.003	<20	0.43	0.005	0.29	<0.1	0.65	1.1	<0.1	<0.05	2	4.8	<0.2
1093608	Rock	0.004	<1	17	0.15	46	<0.001	<20	0.02	0.002	<0.01	<0.1	0.10	0.2	<0.1	<0.05	<1	1.0	<0.2
1093609	Rock	0.013	2	<1	0.45	416	<0.001	<20	0.03	0.007	0.02	<0.1	0.03	0.3	<0.1	0.11	<1	1.0	<0.2
1093610	Rock	0.003	1	3	8.27	53	<0.001	<20	0.04	0.012	0.01	<0.1	<0.01	0.3	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 04, 2011

CERTIFICATE OF ANALYSIS WHI11000695.1

Method		WGHT	G6	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	0.005	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1093611	Rock	0.85	<0.005	6.4	1.1	0.4	51	<0.1	298.1	22.8	2672	5.24	3.8	<0.5	0.2	41	0.2	1.1	<0.1	2	35.33
1093612	Rock	0.87	0.007	0.2	78.2	1.9	37	<0.1	14.1	2.7	30	0.76	1.7	6.7	0.6	8	<0.1	0.2	<0.1	5	0.09
1093613	Rock	0.87	<0.005	0.3	0.7	0.3	8	<0.1	3.0	1.6	782	5.11	1.3	<0.5	0.1	173	<0.1	0.2	<0.1	10	20.48
1095451	Rock	1.53	0.012	0.4	37.1	4.9	28	<0.1	184.3	27.0	738	3.22	13.4	0.7	5.6	325	<0.1	0.3	<0.1	82	5.41
1095452	Rock	1.57	0.011	0.1	3.4	1.4	10	<0.1	46.1	6.8	1157	3.93	26.4	<0.5	1.0	708	<0.1	0.3	<0.1	8	9.65
1095453	Rock	1.50	<0.005	0.6	67.1	6.6	71	<0.1	329.4	61.1	1234	6.15	27.3	<0.5	10.6	331	0.2	0.1	<0.1	149	5.19
1095454	Rock	1.34	<0.005	0.4	13.2	7.6	19	<0.1	109.9	17.5	1138	3.34	5.0	<0.5	3.0	1580	<0.1	<0.1	<0.1	45	6.95
1095455	Rock	1.25	<0.005	11.3	7.6	4.0	17	<0.1	57.5	3.9	576	1.84	5.4	<0.5	0.6	887	0.1	0.5	<0.1	101	10.67
1095456	Rock	1.63	<0.005	9.1	34.8	9.9	9	0.1	223.4	32.8	679	3.02	19.7	<0.5	9.7	576	0.1	1.2	<0.1	56	22.24
1095458	Rock	2.11	<0.005	37.0	124.9	44.5	29	0.3	300.1	25.2	482	18.05	70.6	<0.5	4.5	167	0.6	3.7	<0.1	38	6.71
1095459	Rock	0.97	<0.005	13.1	21.6	3.7	473	0.2	30.3	1.1	151	0.06	17.9	<0.5	0.4	1193	8.6	6.1	<0.1	390	30.43
1095460	Rock	0.60	<0.005	1.2	95.3	0.9	40	1.5	5.5	0.5	46	0.34	11.2	<0.5	0.2	686	1.6	46.4	<0.1	37	6.55
1095461	Rock	1.08	<0.005	26.3	29.5	1.9	523	0.6	76.0	1.7	69	0.39	38.5	<0.5	0.6	523	22.1	9.4	<0.1	350	10.06
1095462	Rock	0.94	<0.005	21.6	17.9	3.6	121	0.1	44.3	2.9	105	1.25	8.9	<0.5	0.4	89	0.5	2.5	<0.1	117	1.18
1095463	Rock	0.60	<0.005	0.7	42.2	3.7	73	<0.1	300.9	56.8	823	6.24	10.8	0.9	3.1	298	0.2	0.5	<0.1	131	6.05
1095464	Rock	1.51	<0.005	0.3	2.6	1.0	5	<0.1	3.2	0.3	139	0.10	3.1	<0.5	0.3	590	0.1	<0.1	<0.1	4	29.07
1095465	Rock	1.16	0.051	1.6	266.4	6.9	49	0.3	41.4	10.0	103	3.02	10.3	5.8	1.7	21	0.1	1.1	<0.1	21	0.16
1095466	Rock	1.10	<0.005	1.3	20.5	1.9	69	0.1	35.3	29.4	1303	2.20	3.6	2.2	0.6	8	0.2	0.4	<0.1	8	0.10
1095467	Rock	1.36	0.006	0.5	82.6	5.0	12	0.2	15.8	2.7	59	2.70	6.6	2.1	1.1	11	<0.1	0.7	0.1	24	<0.01
1095468	Rock	1.14	<0.005	0.9	47.4	2.2	99	0.1	48.3	5.5	77	1.96	7.6	1.7	0.7	6	0.2	0.8	<0.1	10	<0.01
1095469	Rock	2.11	<0.005	0.2	0.6	0.2	5	<0.1	3.7	0.6	366	2.60	2.0	0.7	0.1	230	<0.1	<0.1	<0.1	7	15.42
1095470	Rock	1.42	<0.005	0.2	1.2	0.5	6	<0.1	1.2	0.4	87	0.10	2.6	<0.5	0.3	546	<0.1	<0.1	<0.1	4	29.91
1095471	Rock	1.39	0.020	3.9	36.0	8.6	117	0.9	23.3	3.1	382	1.72	6.1	6.8	1.2	276	1.4	0.8	<0.1	38	13.47
1095472	Rock	1.33	<0.005	0.6	1.3	0.7	7	<0.1	3.2	0.8	489	3.30	3.1	0.5	0.5	272	<0.1	0.2	<0.1	13	14.91
1095473	Rock	1.31	<0.005	0.9	27.1	7.6	58	0.2	10.9	1.6	49	1.87	7.9	<0.5	0.6	9	0.4	0.8	0.1	15	0.17
1095474	Rock	1.47	0.006	0.7	46.3	8.2	65	0.3	14.7	3.0	47	1.69	6.4	0.9	0.8	13	0.6	0.9	0.1	13	0.19

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 04, 2011

CERTIFICATE OF ANALYSIS WHI11000695.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093611	Rock	0.025	1	1	0.28	91	0.002	<20	0.04	0.002	0.02	<0.1	0.01	0.5	0.2	0.06	<1	0.7	<0.2
1093612	Rock	0.008	1	14	0.06	87	<0.001	<20	0.22	<0.001	0.12	<0.1	0.06	1.7	<0.1	<0.05	<1	<0.5	<0.2
1093613	Rock	0.004	1	<1	7.51	59	<0.001	<20	0.06	0.008	0.01	<0.1	<0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2
1095451	Rock	0.220	43	198	3.74	994	0.005	<20	1.18	0.002	0.03	<0.1	0.04	8.6	<0.1	<0.05	4	<0.5	<0.2
1095452	Rock	0.049	6	13	5.68	141	<0.001	<20	0.09	0.003	0.03	<0.1	0.06	1.5	<0.1	<0.05	<1	<0.5	<0.2
1095453	Rock	0.419	60	390	8.56	838	0.006	<20	3.57	<0.001	0.03	<0.1	0.07	16.9	<0.1	0.17	8	<0.5	<0.2
1095454	Rock	0.103	16	89	5.21	444	0.002	<20	0.66	0.002	0.02	<0.1	0.04	8.3	<0.1	<0.05	2	0.5	<0.2
1095455	Rock	0.009	3	8	7.26	1727	0.001	<20	0.12	0.013	0.04	<0.1	0.12	1.2	<0.1	0.05	<1	1.9	<0.2
1095456	Rock	0.301	42	81	0.91	22	0.003	<20	0.38	0.009	0.12	<0.1	4.10	9.8	0.3	1.91	1	1.2	<0.2
1095458	Rock	0.168	16	47	0.75	9	0.004	<20	0.27	0.002	0.09	0.3	19.92	9.2	0.9	>10	<1	3.3	<0.2
1095459	Rock	0.013	5	10	0.24	500	0.001	<20	0.09	0.001	0.03	<0.1	0.25	0.7	0.1	<0.05	<1	<0.5	<0.2
1095460	Rock	0.004	2	6	0.07	124	<0.001	<20	0.03	0.001	0.01	<0.1	0.48	0.3	<0.1	0.11	<1	0.6	<0.2
1095461	Rock	0.040	5	18	0.33	907	0.007	<20	0.13	0.002	0.05	0.1	1.23	1.5	0.5	0.05	<1	3.1	<0.2
1095462	Rock	0.013	2	12	0.45	410	0.001	<20	0.13	0.002	0.06	<0.1	0.30	0.6	<0.1	0.05	<1	4.7	<0.2
1095463	Rock	0.219	24	373	3.89	17	0.027	<20	1.66	0.002	0.16	<0.1	0.03	12.9	<0.1	2.84	6	0.8	<0.2
1095464	Rock	0.008	2	<1	0.63	360	<0.001	<20	0.02	0.003	0.01	<0.1	0.02	0.3	<0.1	<0.05	<1	<0.5	<0.2
1095465	Rock	0.050	7	20	0.07	303	0.001	<20	0.43	0.001	0.18	<0.1	0.40	2.6	<0.1	0.06	1	2.1	<0.2
1095466	Rock	0.011	5	8	0.02	149	<0.001	<20	0.13	<0.001	0.06	<0.1	0.07	1.3	<0.1	<0.05	<1	<0.5	<0.2
1095467	Rock	0.016	3	26	0.04	140	0.001	<20	0.32	<0.001	0.14	<0.1	0.15	1.7	<0.1	0.05	2	1.2	<0.2
1095468	Rock	0.016	4	9	0.01	70	<0.001	<20	0.15	<0.001	0.06	<0.1	0.10	2.1	<0.1	<0.05	<1	0.8	<0.2
1095469	Rock	0.005	1	2	7.61	63	<0.001	<20	0.03	0.005	<0.01	<0.1	0.01	0.1	<0.1	<0.05	<1	<0.5	<0.2
1095470	Rock	0.004	2	<1	0.80	393	<0.001	<20	0.02	0.006	0.01	<0.1	0.02	0.2	<0.1	<0.05	<1	<0.5	<0.2
1095471	Rock	2.348	21	11	1.47	472	0.010	<20	0.61	0.006	0.29	<0.1	0.20	1.5	<0.1	<0.05	1	2.0	<0.2
1095472	Rock	0.005	2	2	7.46	154	<0.001	<20	0.08	0.010	0.02	<0.1	<0.01	0.5	<0.1	<0.05	<1	<0.5	<0.2
1095473	Rock	0.030	1	16	0.03	122	0.001	<20	0.24	0.002	0.13	<0.1	0.12	1.2	<0.1	0.11	<1	1.0	<0.2
1095474	Rock	0.015	1	8	0.09	133	0.001	<20	0.27	0.002	0.14	<0.1	0.12	1.7	<0.1	0.09	<1	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 04, 2011

QUALITY CONTROL REPORT WHI11000695.1

	Method	WGHT	G6	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.005	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1093602	Rock	0.96	<0.005	0.2	0.5	0.2	14	<0.1	4.6	1.9	941	5.82	<0.5	<0.5	<0.1	234	<0.1	<0.1	<0.1	<2	18.74
REP 1093602	QC			0.2	0.7	0.2	14	<0.1	5.1	1.2	934	5.73	1.3	<0.5	<0.1	240	<0.1	<0.1	<0.1	<2	18.79
1093611	Rock	0.85	<0.005	6.4	1.1	0.4	51	<0.1	298.1	22.8	2672	5.24	3.8	<0.5	0.2	41	0.2	1.1	<0.1	2	35.33
REP 1093611	QC		<0.005																		
1095468	Rock	1.14	<0.005	0.9	47.4	2.2	99	0.1	48.3	5.5	77	1.96	7.6	1.7	0.7	6	0.2	0.8	<0.1	10	<0.01
REP 1095468	QC			0.9	47.0	2.1	97	0.1	46.9	5.4	77	1.93	7.6	1.6	0.7	6	0.1	0.9	<0.1	10	<0.01
Core Reject Duplicates																					
1093604	Rock	1.12	<0.005	0.2	5.7	0.6	9	<0.1	3.4	1.3	209	1.47	0.7	0.8	0.5	564	0.1	0.1	0.1	4	3.90
DUP 1093604	QC		<0.005	0.2	6.2	0.6	8	<0.1	3.2	1.3	198	1.40	1.2	0.9	0.4	561	0.1	0.1	<0.1	3	3.77
Reference Materials																					
STD DS8	Standard			11.7	100.1	115.2	288	1.7	35.4	6.9	551	2.26	22.8	90.7	6.2	62	2.1	4.3	5.5	39	0.64
STD DS8	Standard			14.3	108.5	130.5	322	1.9	37.3	7.3	612	2.48	25.7	96.7	6.3	65	2.3	4.4	6.3	41	0.69
STD OREAS45CA	Standard			1.0	502.2	21.1	60	0.3	251.3	91.0	890	15.53	4.4	43.6	7.1	19	0.1	0.1	0.1	210	0.40
STD OREAS45CA	Standard			0.9	542.6	21.8	65	0.3	262.6	101.2	991	16.88	4.0	42.8	7.3	19	<0.1	<0.1	0.2	237	0.47
STD OXH82	Standard		1.239																		
STD OXH82	Standard		1.292																		
STD OXH82	Standard		1.244																		
STD OXK79	Standard		3.602																		
STD OXK79	Standard		3.581																		
STD OXK79	Standard		3.521																		
STD OXH82 Expected			1.278																		
STD OXK79 Expected			3.532																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 04, 2011

QUALITY CONTROL REPORT WHI11000695.1

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																				
1093602	Rock		0.003	<1	2	7.82	129	<0.001	<20	0.02	0.015	0.01	<0.1	0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2
REP 1093602	QC		0.003	<1	2	7.97	128	<0.001	<20	0.02	0.015	0.01	<0.1	0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2
1093611	Rock		0.025	1	1	0.28	91	0.002	<20	0.04	0.002	0.02	<0.1	0.01	0.5	0.2	0.06	<1	0.7	<0.2
REP 1093611	QC																			
1095468	Rock		0.016	4	9	0.01	70	<0.001	<20	0.15	<0.001	0.06	<0.1	0.10	2.1	<0.1	<0.05	<1	0.8	<0.2
REP 1095468	QC		0.017	4	8	0.01	68	<0.001	<20	0.15	<0.001	0.06	<0.1	0.09	2.1	<0.1	<0.05	<1	1.0	<0.2
Core Reject Duplicates																				
1093604	Rock		0.025	<1	7	1.81	41	<0.001	<20	0.07	0.002	0.04	<0.1	0.02	3.5	<0.1	<0.05	<1	<0.5	<0.2
DUP 1093604	QC		0.024	<1	7	1.72	37	<0.001	<20	0.07	0.001	0.04	<0.1	0.01	3.2	<0.1	<0.05	<1	<0.5	<0.2
Reference Materials																				
STD DS8	Standard		0.072	13	107	0.56	265	0.103	<20	0.83	0.081	0.37	2.2	0.20	1.9	4.6	0.15	4	5.7	4.5
STD DS8	Standard		0.083	15	116	0.62	289	0.107	<20	0.92	0.091	0.41	2.6	0.18	2.0	5.8	0.16	5	5.6	5.0
STD OREAS45CA	Standard		0.037	15	737	0.14	163	0.128	<20	3.66	0.006	0.07	<0.1	0.03	36.7	<0.1	<0.05	18	0.7	<0.2
STD OREAS45CA	Standard		0.043	17	768	0.15	171	0.145	<20	4.03	0.007	0.09	<0.1	0.03	38.8	0.1	<0.05	21	<0.5	<0.2
STD OXH82	Standard																			
STD OXH82	Standard																			
STD OXH82	Standard																			
STD OXK79	Standard																			
STD OXK79	Standard																			
STD OXK79	Standard																			
STD OXH82 Expected																				
STD OXK79 Expected																				
STD DS8 Expected			0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 04, 2011

QUALITY CONTROL REPORT WHI11000695.1

		WGHT	G6	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		kg	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		0.01	0.005	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		<0.005	0.1	1.6	3.0	48	<0.1	3.8	4.3	567	2.06	0.7	2.1	5.2	73	<0.1	<0.1	0.8	37	0.66
G1	Prep Blank		<0.005	<0.1	1.3	2.9	48	<0.1	3.2	4.0	563	1.89	<0.5	1.9	5.6	72	<0.1	<0.1	<0.1	37	0.56

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 04, 2011

QUALITY CONTROL REPORT WHI11000695.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	0.005	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
Prep Wash																			
G1	Prep Blank	0.082	11	8	0.66	215	0.131	<20	1.05	0.106	0.49	<0.1	<0.01	1.8	0.3	<0.05	5	<0.5	<0.2
G1	Prep Blank	0.080	11	7	0.60	213	0.129	<20	1.07	0.107	0.48	<0.1	<0.01	1.9	0.3	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 28, 2011
Report Date: September 20, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11000776.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #7
P.O. Number
Number of Samples: 60

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	60	Crush, split and pulverize 250 g rock to 200 mesh			WHI
1DX	60	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN
3B	60	Fire assay fusion Au by ICP-ES	30	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

CERTIFICATE OF ANALYSIS WHI11000776.1

Method		WGHT	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093614	Rock	0.24	0.7	68.7	2.0	52	0.1	0.7	0.3	13	>40	9.0	2.4	0.1	2	<0.1	1.1	<0.1	192	<0.01	0.013
1093615	Rock	0.78	0.6	78.4	2.6	68	0.9	59.6	5.1	158	0.93	12.4	<0.5	0.4	9	0.4	2.9	<0.1	11	0.02	0.012
1093616	Rock	0.86	2.5	12.2	0.7	11	1.3	5.1	0.3	25	0.51	1.3	1.0	0.3	27	<0.1	1.5	<0.1	51	0.02	0.052
1093617	Rock	0.91	1.2	8.4	3.0	8	2.8	1.8	0.2	28	0.93	21.0	5.1	0.2	15	<0.1	3.6	<0.1	32	<0.01	0.025
1093618	Rock	1.39	2.6	34.4	10.2	53	1.4	28.6	14.4	43	1.55	28.3	0.8	0.2	59	0.7	2.7	<0.1	20	0.14	0.107
1093619	Rock	0.72	23.9	32.4	2.9	22	0.2	3.2	0.3	27	2.02	75.4	2.0	0.3	15	<0.1	11.6	<0.1	106	<0.01	0.038
1093620	Rock	0.83	4.5	24.0	2.3	7	4.8	4.8	0.1	21	0.59	12.3	1.2	0.3	12	0.1	2.4	<0.1	44	<0.01	0.018
1093621	Rock	1.04	1.2	8.5	2.5	5	0.5	2.8	0.4	22	0.39	1.4	<0.5	0.3	6	<0.1	0.6	<0.1	18	<0.01	0.004
1093622	Rock	0.64	0.4	65.3	4.9	99	1.6	32.6	3.9	105	3.89	9.2	1.8	0.4	6	0.1	5.4	<0.1	83	<0.01	0.034
1093623	Rock	0.94	2.6	46.8	6.1	1	1.9	42.4	6.0	31	0.92	8.1	1.5	0.2	37	<0.1	1.8	<0.1	27	0.09	0.068
1093624	Rock	0.60	35.6	12.6	7.1	55	0.6	27.2	2.1	66	4.38	42.0	<0.5	1.5	39	<0.1	1.9	0.2	211	0.01	0.324
1093625	Rock	0.86	42.5	64.6	9.0	45	0.8	21.1	1.6	37	7.91	180.8	0.8	6.1	221	0.4	4.9	0.4	587	0.36	3.081
1093626	Rock	1.50	23.7	113.7	5.8	231	0.7	35.3	4.7	172	8.82	146.5	<0.5	4.5	262	0.5	2.9	0.3	831	0.41	2.699
1093627	Rock	0.85	1.6	7.1	4.0	<1	0.5	4.3	0.6	13	0.75	2.3	<0.5	0.7	20	<0.1	0.6	<0.1	17	<0.01	0.011
1093628	Rock	0.90	1.5	5.5	4.7	<1	0.7	3.8	0.6	25	1.02	5.9	<0.5	0.4	14	<0.1	2.8	<0.1	8	<0.01	0.017
1093629	Rock	1.08	1.0	25.0	4.5	7	1.6	0.8	0.2	26	1.12	10.6	3.1	0.2	25	<0.1	3.0	0.1	30	<0.01	0.024
1093630	Rock	0.45	178.6	83.6	10.3	17	0.3	0.7	0.1	6	29.85	1291	1.4	1.0	536	0.3	8.4	<0.1	343	0.04	2.949
1093631	Rock	0.94	46.9	84.5	10.3	108	9.8	65.4	12.4	22	1.27	192.5	1.0	0.3	11	2.6	8.7	<0.1	111	<0.01	0.007
1093632	Rock	0.99	3.5	3.6	2.8	2	1.2	0.4	<0.1	17	0.57	9.5	1.7	0.5	27	<0.1	2.5	<0.1	44	<0.01	0.045
1093633	Rock	0.73	0.8	20.6	6.1	281	1.6	40.0	3.9	62	3.78	17.1	1.2	0.3	17	<0.1	8.2	<0.1	56	<0.01	0.072
1093634	Rock	0.51	1.1	3.9	5.9	<1	2.4	1.0	0.4	78	0.79	3.6	2.2	0.2	6	<0.1	3.1	<0.1	5	<0.01	0.009
1093635	Rock	0.92	0.9	6.2	1.4	9	0.1	6.9	0.8	780	4.86	3.1	<0.5	0.4	116	<0.1	1.9	<0.1	15	13.47	0.008
1093636	Rock	1.24	0.3	19.8	0.8	21	<0.1	5.1	1.4	116	0.87	5.0	1.6	0.3	3	0.2	0.6	<0.1	5	0.24	0.013
1093637	Rock	1.23	0.8	164.4	1.7	54	0.2	18.4	2.4	31	0.82	29.4	2.1	0.4	4	<0.1	12.6	<0.1	6	<0.01	0.012
1093638	Rock	1.21	0.2	87.0	6.8	75	0.3	29.7	10.8	131	2.15	1.6	<0.5	2.7	30	0.2	0.2	0.2	20	0.48	0.028
1093639	Rock	1.05	<0.1	30.7	3.5	48	0.1	20.7	5.2	127	1.92	<0.5	<0.5	1.5	57	<0.1	<0.1	0.1	10	0.94	0.013
1093640	Rock	0.91	<0.1	10.3	2.0	25	<0.1	7.4	1.9	535	2.92	<0.5	<0.5	1.9	461	<0.1	<0.1	<0.1	10	8.85	0.041
1093641	Rock	0.69	0.1	38.1	6.5	58	0.1	22.2	6.7	598	3.03	<0.5	0.9	1.7	293	0.2	0.2	0.1	15	5.67	0.023
1093642	Rock	1.00	0.6	1.9	1.5	8	<0.1	4.2	0.6	684	3.32	4.1	<0.5	0.3	309	<0.1	1.5	<0.1	9	16.40	0.006
1093643	Rock	1.02	0.5	46.3	2.7	15	<0.1	6.3	1.9	80	1.27	10.6	4.2	0.6	3	<0.1	1.6	<0.1	7	0.12	0.003

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

CERTIFICATE OF ANALYSIS WHI11000776.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb
	MDL	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2
1093614	Rock	<1	7	<0.01	66	<0.001	<20	0.10	0.003	0.02	<0.1	0.04	<0.1	2.14	0.3	0.6	<1	<0.2	6
1093615	Rock	<1	13	<0.01	189	<0.001	<20	0.27	0.002	0.06	<0.1	0.37	0.1	0.25	0.6	1.1	<1	<0.2	4
1093616	Rock	<1	14	<0.01	440	<0.001	<20	0.18	0.002	0.06	<0.1	0.08	<0.1	<0.05	0.8	2.7	<1	<0.2	<2
1093617	Rock	<1	26	<0.01	1088	<0.001	<20	0.17	0.001	0.06	<0.1	0.79	<0.1	<0.05	0.5	8.3	<1	<0.2	5
1093618	Rock	<1	11	0.05	134	0.001	<20	0.22	0.002	0.03	<0.1	0.42	0.1	1.12	0.8	4.5	1	<0.2	4
1093619	Rock	<1	33	<0.01	378	<0.001	<20	0.19	0.001	0.05	<0.1	0.21	<0.1	<0.05	0.6	8.6	2	0.2	2
1093620	Rock	<1	19	<0.01	596	<0.001	<20	0.22	0.002	0.07	<0.1	1.48	<0.1	<0.05	0.5	12.7	2	<0.2	6
1093621	Rock	<1	18	<0.01	237	<0.001	<20	0.15	0.004	0.06	<0.1	0.03	<0.1	<0.05	0.3	1.5	<1	<0.2	2
1093622	Rock	<1	27	0.03	82	<0.001	<20	0.27	0.005	0.03	<0.1	0.13	<0.1	0.29	3.7	4.7	<1	<0.2	<2
1093623	Rock	<1	28	0.02	417	<0.001	<20	0.26	0.007	0.07	<0.1	0.13	0.1	0.55	0.3	4.5	<1	<0.2	8
1093624	Rock	2	73	0.36	883	0.001	<20	0.96	0.003	0.08	<0.1	0.14	0.2	0.19	2.6	13.7	5	0.2	3
1093625	Rock	5	123	0.54	429	0.012	<20	1.90	0.003	0.18	0.2	0.15	2.8	0.38	24.3	28.6	7	0.6	12
1093626	Rock	5	173	0.81	442	0.010	<20	2.43	0.006	0.22	0.1	0.13	1.1	0.47	21.0	14.9	10	<0.2	<2
1093627	Rock	<1	10	<0.01	735	<0.001	<20	0.22	0.004	0.19	<0.1	0.10	0.1	0.29	0.5	1.1	<1	<0.2	4
1093628	Rock	<1	12	<0.01	234	<0.001	<20	0.13	0.013	0.13	<0.1	0.11	0.2	0.35	0.2	1.1	<1	<0.2	<2
1093629	Rock	<1	21	<0.01	258	<0.001	<20	0.15	0.004	0.06	<0.1	0.29	0.1	0.05	0.8	2.8	1	<0.2	<2
1093630	Rock	2	97	<0.01	37	0.010	<20	0.09	0.029	3.66	<0.1	0.02	34.6	7.49	63.7	6.8	4	<0.2	<2
1093631	Rock	<1	18	0.01	35	0.001	<20	0.29	0.004	0.10	<0.1	0.88	1.9	1.33	1.1	44.7	<1	0.2	14
1093632	Rock	2	9	<0.01	990	<0.001	<20	0.16	0.004	0.09	<0.1	0.08	0.4	0.13	0.7	7.5	<1	<0.2	4
1093633	Rock	<1	17	<0.01	143	<0.001	<20	0.11	0.004	0.05	<0.1	0.11	0.1	0.06	5.8	15.2	1	<0.2	9
1093634	Rock	<1	8	<0.01	412	<0.001	24	0.10	0.004	0.04	<0.1	0.88	<0.1	<0.05	0.5	1.3	<1	<0.2	6
1093635	Rock	1	4	6.02	46	<0.001	<20	0.09	0.010	0.03	<0.1	0.03	<0.1	<0.05	0.4	1.1	<1	<0.2	2
1093636	Rock	2	5	0.02	86	<0.001	<20	0.09	0.003	0.05	<0.1	0.02	<0.1	<0.05	1.7	<0.5	<1	<0.2	2
1093637	Rock	<1	8	<0.01	63	<0.001	<20	0.13	0.002	0.06	<0.1	0.13	<0.1	<0.05	1.5	1.1	<1	<0.2	8
1093638	Rock	5	15	0.30	1836	0.002	<20	0.79	0.005	0.39	<0.1	0.26	<0.1	<0.05	4.2	0.8	2	<0.2	3
1093639	Rock	3	7	1.01	308	0.002	<20	0.46	0.006	0.23	<0.1	0.10	<0.1	0.29	3.4	<0.5	1	<0.2	4
1093640	Rock	5	9	5.10	599	0.002	<20	0.37	0.013	0.18	<0.1	0.02	<0.1	0.09	3.0	0.5	<1	<0.2	2
1093641	Rock	8	9	2.91	54	0.001	<20	0.36	0.008	0.21	<0.1	0.04	<0.1	0.53	4.1	0.9	1	<0.2	3
1093642	Rock	1	2	8.00	167	<0.001	<20	0.08	0.012	0.02	<0.1	0.02	<0.1	<0.05	0.4	<0.5	<1	<0.2	<2
1093643	Rock	3	9	0.03	325	0.001	<20	0.22	0.003	0.09	<0.1	0.17	<0.1	<0.05	1.1	<0.5	<1	<0.2	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

CERTIFICATE OF ANALYSIS WHI11000776.1

Method		WGHT	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093644	Rock	0.45	0.8	55.0	0.7	60	<0.1	11.4	1.4	55	0.99	18.9	0.9	0.4	2	<0.1	15.2	<0.1	6	0.09	0.009
1093645	Rock	1.16	0.5	12.9	6.3	20	<0.1	17.7	5.7	1215	3.88	1.9	<0.5	1.5	346	<0.1	0.2	<0.1	12	9.00	0.015
1093646	Rock	0.93	<0.1	21.8	1.7	46	0.1	10.8	3.2	404	2.11	<0.5	<0.5	1.8	256	<0.1	<0.1	<0.1	14	5.55	0.010
1093803	Rock	1.50	1.3	12.1	28.9	1137	<0.1	59.7	8.8	229	2.54	32.8	<0.5	15.1	19	7.4	0.3	0.6	<2	0.34	0.046
1095408	Rock	1.69	1.4	61.9	10.0	65	1.5	93.1	10.7	80	25.40	6.1	<0.5	0.3	22	<0.1	0.3	<0.1	12	0.17	0.007
1095475	Rock	1.36	0.7	1.8	0.3	19	<0.1	9.9	2.9	351	1.61	10.4	4.3	0.4	94	<0.1	1.0	<0.1	63	3.42	0.008
1095476	Rock	1.30	3.1	1.7	0.5	17	<0.1	18.1	6.0	417	2.04	19.9	0.6	1.8	104	<0.1	0.8	<0.1	143	4.23	0.026
1095477	Rock	1.44	0.5	70.7	1.8	139	0.1	99.7	39.0	1126	5.33	161.4	3.7	0.3	239	0.9	2.9	<0.1	25	5.78	0.054
1095478	Rock	1.62	0.3	79.6	0.9	115	<0.1	29.8	34.2	1079	6.36	9.2	<0.5	0.3	247	0.3	0.5	<0.1	120	3.45	0.080
1095479	Rock	1.20	1.5	76.0	0.9	44	<0.1	69.2	22.7	790	4.71	16.9	<0.5	0.3	97	<0.1	4.6	<0.1	64	7.00	0.064
1095480	Rock	1.69	56.7	99.7	6.3	1072	<0.1	147.4	23.7	992	5.42	426.1	<0.5	0.1	116	1.6	62.5	<0.1	56	12.80	0.031
1095481	Rock	1.59	2.2	6.4	2.1	37	<0.1	5.7	0.5	363	0.10	2.0	<0.5	0.2	2161	0.4	1.2	<0.1	19	30.15	0.003
1095482	Rock	0.98	23.0	11.7	12.2	228	0.1	57.7	3.7	273	1.07	15.0	<0.5	1.4	376	0.6	5.2	<0.1	54	15.46	0.028
1095483	Rock	1.29	0.5	59.9	1.0	60	<0.1	58.0	29.3	939	4.64	447.9	9.4	0.2	463	0.1	4.6	<0.1	19	6.15	0.053
1095485	Rock	1.41	0.4	10.0	2.0	40	<0.1	25.5	14.8	679	3.18	72.4	27.0	<0.1	368	0.1	24.1	<0.1	11	6.07	0.019
1095486	Rock	1.33	0.1	51.4	0.9	45	0.2	42.2	23.0	959	4.28	392.6	108.7	0.1	306	0.2	5.1	<0.1	26	5.88	0.042
1095487	Rock	0.94	0.2	29.8	6.8	23	0.5	20.8	6.5	867	4.20	18.1	8.1	2.0	1462	<0.1	4.1	0.1	15	8.17	0.020
1095488	Rock	1.07	0.3	12.9	4.6	92	0.1	28.0	8.8	840	3.55	3.1	2.7	1.9	155	0.3	0.3	<0.1	18	5.27	0.015
1095489	Rock	1.86	42.8	11.6	73.3	4	1.5	3.7	0.3	23	2.62	46.7	0.9	2.1	63	0.7	9.0	<0.1	221	0.05	0.048
1095490	Rock	1.34	0.3	10.5	3.2	376	<0.1	138.7	26.0	1845	7.57	8.5	<0.5	0.2	634	1.6	1.3	<0.1	126	13.03	0.038
1092544	Rock	3.80	10.7	11.7	9.7	5	0.2	3.1	0.1	6	0.41	12.9	<0.5	1.6	14	<0.1	0.9	0.1	58	0.03	0.009
1092545	Rock	5.06	17.0	15.5	13.8	10	0.2	4.9	0.3	25	0.62	13.5	<0.5	2.5	25	0.1	1.2	0.1	88	0.06	0.012
1092546	Rock	4.57	19.2	16.8	15.5	7	0.2	3.3	<0.1	7	0.57	18.7	<0.5	1.6	18	<0.1	1.5	0.1	40	<0.01	0.022
1092547	Rock	4.46	20.4	17.9	12.2	12	0.4	3.6	0.3	17	1.02	45.7	<0.5	2.3	48	0.2	1.9	0.1	89	0.02	0.038
1092565	Rock	5.53	9.5	26.5	19.7	24	2.6	3.9	0.5	15	1.08	293.8	10.5	3.2	34	0.2	7.7	0.4	57	0.09	0.147
1092566	Rock	5.34	6.0	60.4	16.6	150	1.2	35.3	8.9	737	8.37	189.4	2.7	3.5	46	1.8	5.5	0.4	55	0.17	0.215
1092567	Rock	5.49	5.1	63.7	15.8	198	0.6	41.4	10.1	364	5.54	143.0	1.0	3.0	42	1.7	3.2	0.3	48	0.10	0.182
1092568	Rock	4.59	5.3	49.4	26.7	93	0.9	29.6	8.0	56	2.04	183.3	3.5	2.3	29	0.3	4.2	0.3	37	0.02	0.103
1092569	Rock	5.40	5.6	77.8	20.4	142	0.5	47.0	12.7	536	5.18	164.5	<0.5	2.9	36	1.7	2.8	0.3	53	0.06	0.174
1095491	Rock	1.87	3.9	24.5	11.3	349	0.2	87.4	12.6	142	3.49	34.8	<0.5	1.7	23	2.0	1.6	0.2	40	0.24	0.037

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

CERTIFICATE OF ANALYSIS WHI11000776.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B
Analyte		La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au
Unit		ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb
MDL		1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2
1093644	Rock	2	7	0.04	44	<0.001	<20	0.07	0.003	0.03	<0.1	0.08	<0.1	<0.05	1.5	<0.5	<1	<0.2	5
1093645	Rock	4	8	5.39	30	0.002	<20	0.26	0.010	0.15	<0.1	0.02	<0.1	1.42	2.6	0.8	<1	<0.2	3
1093646	Rock	6	10	3.33	650	0.003	<20	0.40	0.011	0.19	<0.1	0.03	<0.1	0.44	3.8	<0.5	<1	<0.2	3
1093803	Rock	37	<1	0.10	219	<0.001	<20	0.59	0.002	0.29	<0.1	0.87	0.5	0.89	2.0	0.6	1	<0.2	<2
1095408	Rock	<1	7	0.22	2	0.001	<20	0.41	0.003	0.07	<0.1	0.19	<0.1	>10	1.1	7.3	1	<0.2	25
1095475	Rock	<1	8	0.88	336	<0.001	<20	0.11	0.004	0.05	<0.1	<0.01	<0.1	<0.05	2.1	<0.5	<1	<0.2	5
1095476	Rock	3	12	1.42	236	<0.001	<20	0.22	0.006	0.09	<0.1	0.02	<0.1	0.06	3.5	<0.5	<1	<0.2	<2
1095477	Rock	5	34	1.91	551	<0.001	<20	0.58	0.004	0.30	<0.1	0.07	0.1	0.07	16.3	<0.5	1	<0.2	4
1095478	Rock	6	45	2.47	601	0.166	<20	2.99	0.031	0.17	<0.1	0.01	0.1	0.09	16.3	<0.5	11	<0.2	<2
1095479	Rock	3	53	0.29	578	<0.001	<20	0.86	0.007	0.26	<0.1	<0.01	0.4	<0.05	19.2	<0.5	2	<0.2	<2
1095480	Rock	4	20	0.75	204	0.005	<20	1.76	0.001	0.11	<0.1	<0.01	<0.1	<0.05	19.7	0.5	4	<0.2	<2
1095481	Rock	3	1	0.30	108	<0.001	<20	0.02	0.003	<0.01	<0.1	<0.01	<0.1	0.20	0.6	0.5	<1	<0.2	2
1095482	Rock	3	9	3.97	218	0.001	<20	0.22	0.010	0.09	<0.1	0.07	0.4	0.14	2.3	1.3	<1	<0.2	<2
1095483	Rock	4	20	2.70	386	<0.001	<20	0.43	0.003	0.26	<0.1	0.06	0.1	0.17	16.6	<0.5	<1	<0.2	14
1095485	Rock	1	10	2.29	245	<0.001	<20	0.12	0.002	0.08	<0.1	0.02	<0.1	0.09	6.6	<0.5	<1	<0.2	32
1095486	Rock	3	39	2.01	328	<0.001	<20	0.63	0.001	0.24	<0.1	0.10	<0.1	0.32	18.4	0.5	1	<0.2	145
1095487	Rock	8	10	4.17	2131	0.001	<20	0.30	0.008	0.16	<0.1	0.06	<0.1	0.15	3.9	1.4	<1	<0.2	3
1095488	Rock	5	8	2.16	710	0.001	<20	0.33	0.006	0.14	<0.1	0.03	<0.1	0.09	5.3	0.6	<1	<0.2	<2
1095489	Rock	2	7	0.01	145	<0.001	<20	0.17	0.002	0.55	<0.1	0.15	3.2	0.94	1.1	43.3	<1	0.3	<2
1095490	Rock	<1	72	5.80	319	<0.001	<20	0.22	0.009	0.02	<0.1	<0.01	<0.1	0.22	10.3	0.5	<1	<0.2	<2
1092544	Rock	1	6	0.01	217	<0.001	<20	0.39	0.006	0.18	<0.1	0.16	0.5	0.11	1.1	3.1	2	<0.2	<2
1092545	Rock	3	11	0.04	360	<0.001	<20	0.59	0.009	0.29	<0.1	0.23	0.7	0.14	1.8	2.8	3	<0.2	<2
1092546	Rock	2	7	0.01	384	<0.001	<20	0.39	0.006	0.21	<0.1	0.68	0.5	0.18	1.5	6.4	2	<0.2	<2
1092547	Rock	3	13	0.02	382	<0.001	<20	0.61	0.009	0.30	<0.1	0.66	0.8	0.21	1.8	6.4	3	<0.2	<2
1092565	Rock	15	19	0.02	530	0.001	<20	0.55	0.007	0.26	<0.1	15.27	1.1	0.15	2.0	25.7	2	0.4	279
1092566	Rock	8	16	0.12	511	0.001	<20	0.86	0.011	0.22	<0.1	7.30	0.4	0.08	3.4	10.4	2	<0.2	88
1092567	Rock	7	15	0.05	396	<0.001	<20	0.99	0.013	0.23	<0.1	2.08	0.3	0.06	4.1	7.7	2	<0.2	27
1092568	Rock	4	12	0.02	352	<0.001	<20	0.65	0.010	0.21	<0.1	4.55	0.2	<0.05	2.5	8.9	2	<0.2	96
1092569	Rock	6	16	0.05	458	<0.001	<20	0.96	0.012	0.21	<0.1	2.09	0.3	<0.05	3.7	6.2	2	<0.2	35
1095491	Rock	3	9	0.04	386	<0.001	<20	0.32	0.004	0.09	<0.1	0.11	0.5	<0.05	1.0	0.6	1	<0.2	<2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

QUALITY CONTROL REPORT WHI11000776.1

	Method	WGHT	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1093622	Rock	0.64	0.4	65.3	4.9	99	1.6	32.6	3.9	105	3.89	9.2	1.8	0.4	6	0.1	5.4	<0.1	83	<0.01	0.034
REP 1093622	QC																				
1093623	Rock	0.94	2.6	46.8	6.1	1	1.9	42.4	6.0	31	0.92	8.1	1.5	0.2	37	<0.1	1.8	<0.1	27	0.09	0.068
REP 1093623	QC		2.8	45.7	6.2	2	2.0	42.1	5.9	30	0.92	7.8	1.9	0.2	37	<0.1	1.6	<0.1	27	0.08	0.067
1092567	Rock	5.49	5.1	63.7	15.8	198	0.6	41.4	10.1	364	5.54	143.0	1.0	3.0	42	1.7	3.2	0.3	48	0.10	0.182
REP 1092567	QC		5.1	61.3	15.4	192	0.6	39.4	9.9	358	5.48	137.8	<0.5	3.0	41	1.8	3.4	0.2	47	0.09	0.189
1092569	Rock	5.40	5.6	77.8	20.4	142	0.5	47.0	12.7	536	5.18	164.5	<0.5	2.9	36	1.7	2.8	0.3	53	0.06	0.174
REP 1092569	QC		5.5	72.3	19.9	136	0.5	46.6	12.3	524	5.17	163.6	<0.5	2.8	35	1.8	2.4	0.3	53	0.06	0.168
Core Reject Duplicates																					
1093636	Rock	1.24	0.3	19.8	0.8	21	<0.1	5.1	1.4	116	0.87	5.0	1.6	0.3	3	0.2	0.6	<0.1	5	0.24	0.013
DUP 1093636	QC		0.2	19.8	0.8	21	<0.1	5.7	1.6	130	0.96	4.4	<0.5	0.3	3	0.2	0.5	<0.1	5	0.30	0.011
1092568	Rock	4.59	5.3	49.4	26.7	93	0.9	29.6	8.0	56	2.04	183.3	3.5	2.3	29	0.3	4.2	0.3	37	0.02	0.103
DUP 1092568	QC		5.0	51.3	27.2	91	1.0	29.8	8.3	55	2.07	190.1	2.0	2.4	30	0.3	3.6	0.3	39	0.02	0.104
Reference Materials																					
STD DS8	Standard		13.5	110.2	128.3	321	1.8	38.3	7.6	623	2.47	25.0	97.3	6.8	65	2.4	3.8	5.7	42	0.68	0.078
STD DS8	Standard		13.3	116.3	124.3	311	1.8	40.1	7.8	603	2.48	26.4	167.4	5.7	62	2.4	3.7	5.7	42	0.70	0.076
STD DS8	Standard		13.1	111.4	120.1	295	1.6	39.8	7.5	605	2.43	24.7	84.4	7.2	69	2.3	3.8	5.4	42	0.70	0.080
STD DS8	Standard		13.6	114.2	119.7	306	1.8	40.2	7.8	619	2.52	25.0	82.5	7.0	61	2.2	3.6	5.6	42	0.73	0.079
STD OREAS45CA	Standard		0.7	516.3	21.3	62	0.3	253.7	94.7	946	15.88	3.5	39.9	7.5	13	<0.1	<0.1	0.2	215	0.46	0.039
STD OREAS45CA	Standard		0.9	490.2	22.0	59	0.3	245.1	93.0	937	15.67	4.0	84.7	6.6	18	0.1	0.1	0.2	211	0.41	0.035
STD OREAS45CA	Standard		0.7	525.9	22.1	61	0.3	261.1	92.6	939	16.29	3.7	35.0	7.7	17	<0.1	<0.1	0.2	215	0.42	0.040
STD OREAS45CA	Standard		0.8	512.0	20.4	60	0.3	250.9	92.2	899	15.69	3.5	36.7	6.8	14	<0.1	<0.1	0.2	206	0.43	0.037
STD OXC88	Standard																				
STD OXC88	Standard																				
STD OXC88	Standard																				
STD OXH82	Standard																				
STD OXH82	Standard																				
STD OXH82	Standard																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

QUALITY CONTROL REPORT WHI11000776.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb
	MDL	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2
Pulp Duplicates																			
1093622	Rock	<1	27	0.03	82	<0.001	<20	0.27	0.005	0.03	<0.1	0.13	<0.1	0.29	3.7	4.7	<1	<0.2	<2
REP 1093622	QC																		<2
1093623	Rock	<1	28	0.02	417	<0.001	<20	0.26	0.007	0.07	<0.1	0.13	0.1	0.55	0.3	4.5	<1	<0.2	8
REP 1093623	QC	<1	26	0.02	322	<0.001	<20	0.26	0.006	0.07	<0.1	0.11	0.1	0.53	0.3	4.4	<1	<0.2	
1092567	Rock	7	15	0.05	396	<0.001	<20	0.99	0.013	0.23	<0.1	2.08	0.3	0.06	4.1	7.7	2	<0.2	27
REP 1092567	QC	6	14	0.04	391	<0.001	<20	0.95	0.011	0.22	<0.1	1.96	0.2	0.06	4.3	7.4	2	<0.2	
1092569	Rock	6	16	0.05	458	<0.001	<20	0.96	0.012	0.21	<0.1	2.09	0.3	<0.05	3.7	6.2	2	<0.2	35
REP 1092569	QC	6	16	0.06	435	<0.001	<20	0.96	0.012	0.21	<0.1	2.07	0.3	<0.05	3.6	5.9	2	<0.2	
Core Reject Duplicates																			
1093636	Rock	2	5	0.02	86	<0.001	<20	0.09	0.003	0.05	<0.1	0.02	<0.1	<0.05	1.7	<0.5	<1	<0.2	2
DUP 1093636	QC	2	7	0.04	92	<0.001	<20	0.10	0.003	0.05	<0.1	0.01	<0.1	<0.05	1.7	0.6	<1	<0.2	2
1092568	Rock	4	12	0.02	352	<0.001	<20	0.65	0.010	0.21	<0.1	4.55	0.2	<0.05	2.5	8.9	2	<0.2	96
DUP 1092568	QC	4	13	0.02	371	<0.001	<20	0.67	0.010	0.22	<0.1	4.44	0.3	0.07	2.7	10.2	2	0.2	107
Reference Materials																			
STD DS8	Standard	12	116	0.61	290	0.109	<20	0.89	0.083	0.42	2.2	0.20	5.8	0.17	1.7	4.9	5	4.9	
STD DS8	Standard	13	119	0.63	291	0.101	<20	0.88	0.081	0.38	2.4	0.21	5.2	0.17	2.0	5.9	5	5.2	
STD DS8	Standard	15	116	0.62	286	0.110	<20	0.89	0.083	0.40	2.1	0.18	5.2	0.17	1.8	5.1	5	5.2	
STD DS8	Standard	14	121	0.62	288	0.115	<20	0.94	0.095	0.42	2.3	0.19	5.0	0.17	2.0	4.8	5	4.4	
STD OREAS45CA	Standard	16	699	0.14	164	0.135	<20	3.61	0.006	0.08	<0.1	0.03	<0.1	<0.05	37.3	<0.5	19	<0.2	
STD OREAS45CA	Standard	16	793	0.13	174	0.130	<20	3.58	0.010	0.07	<0.1	0.03	0.1	<0.05	37.5	0.9	18	<0.2	
STD OREAS45CA	Standard	17	714	0.14	164	0.127	<20	3.87	0.010	0.08	<0.1	0.03	<0.1	<0.05	38.2	0.8	19	<0.2	
STD OREAS45CA	Standard	16	727	0.14	161	0.133	<20	3.85	0.009	0.07	<0.1	0.03	<0.1	<0.05	36.4	1.0	18	<0.2	
STD OXC88	Standard																		200
STD OXC88	Standard																		199
STD OXC88	Standard																		202
STD OXH82	Standard																		1284
STD OXH82	Standard																		1337
STD OXH82	Standard																		1310

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

QUALITY CONTROL REPORT WHI11000776.1

		WGHT	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
STD OXC88 Expected																					
STD OXH82 Expected																					
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08
STD OREAS45CA Expected			1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.04	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
Prep Wash																					
G1	Prep Blank		<0.1	1.4	3.1	50	<0.1	3.6	4.4	608	2.05	<0.5	<0.5	5.7	72	<0.1	<0.1	<0.1	40	0.54	0.085
G1	Prep Blank		0.1	1.6	3.0	50	<0.1	4.1	4.6	599	2.07	<0.5	<0.5	5.0	66	<0.1	<0.1	<0.1	40	0.50	0.081

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

QUALITY CONTROL REPORT WHI11000776.1

		1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2	3B Au ppb 2
STD OXC88 Expected																			203
STD OXH82 Expected																			1278
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5	
STD OREAS45CA Expected		15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4		
BLK	Blank																		<2
BLK	Blank																		<2
BLK	Blank																		<2
BLK	Blank																		<2
BLK	Blank																		<2
BLK	Blank																		<2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2	
BLK	Blank	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2	
BLK	Blank	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2	
BLK	Blank	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2	
Prep Wash																			
G1	Prep Blank	10	10	0.62	230	0.135	<20	1.08	0.103	0.52	<0.1	<0.01	0.3	<0.05	1.8	<0.5	5	<0.2	<2
G1	Prep Blank	10	13	0.60	221	0.129	<20	1.02	0.085	0.50	<0.1	<0.01	0.3	<0.05	1.7	<0.5	5	<0.2	<2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 08, 2011
Report Date: September 21, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11000897.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #8
P.O. Number
Number of Samples: 42

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-500	42	Crush, split and pulverize 500 g rock to 200 mesh			VAN
1DX	42	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN
3B	42	Fire assay fusion Au by ICP-ES	30	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 21, 2011

CERTIFICATE OF ANALYSIS WHI11000897.1

	Method	WGHT	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093647	Rock	1.01	0.2	48.0	6.0	46	<0.1	11.1	3.1	77	1.40	5.7	4.7	0.9	4	<0.1	0.5	0.1	11	0.01	0.010
1093648	Rock	0.77	0.4	34.1	4.7	28	0.1	16.9	3.6	144	1.55	1.7	3.6	0.7	6	0.2	0.2	0.1	7	0.15	0.009
1093649	Rock	1.01	0.6	73.2	1.1	161	<0.1	8.5	1.0	895	5.44	4.8	3.9	0.2	174	3.1	0.9	<0.1	8	16.61	0.048
1093650	Rock	0.90	0.2	1.5	1.1	12	<0.1	3.3	0.6	131	0.20	1.5	3.9	0.3	724	<0.1	0.5	<0.1	4	30.19	0.006
1093651	Rock	1.02	0.6	1.9	0.7	10	<0.1	10.1	1.3	1226	6.34	1.7	2.2	0.2	117	<0.1	0.2	<0.1	8	14.48	0.002
1093652	Rock	0.74	0.1	29.4	1.8	32	<0.1	7.1	2.1	131	0.62	2.5	6.4	0.5	6	0.2	0.2	<0.1	4	0.18	0.003
1093653	Rock	0.94	0.1	47.3	2.3	66	<0.1	12.0	2.9	163	2.26	3.9	4.8	0.2	2	0.1	0.2	<0.1	20	0.07	0.003
1093654	Rock	0.60	0.6	60.5	0.9	48	<0.1	11.9	2.0	60	1.27	14.4	3.2	0.3	3	0.7	0.2	0.1	42	0.01	0.033
1093655	Rock	0.82	0.3	11.7	8.9	36	0.3	7.3	2.0	25	1.02	2.3	2.9	0.4	4	<0.1	0.2	0.1	13	<0.01	0.007
1093656	Rock	1.22	<0.1	17.8	3.4	27	<0.1	15.1	4.3	1388	5.00	2.1	1.3	1.1	321	0.3	0.2	<0.1	24	11.11	0.008
1093657	Rock	1.05	0.1	38.0	4.4	92	<0.1	25.7	7.8	172	2.25	1.5	<0.5	2.4	28	0.4	0.2	0.2	10	0.22	0.033
1093658	Rock	1.23	10.5	18.7	7.6	11	1.6	9.7	0.4	41	0.94	13.8	4.7	1.8	151	<0.1	5.4	0.2	76	0.18	0.122
1093659	Rock	0.85	23.5	18.9	3.5	88	0.7	20.6	0.5	64	0.76	8.8	3.0	0.7	8	1.0	7.2	<0.1	739	0.02	0.012
1093660	Rock	0.93	58.0	147.1	6.9	665	1.1	70.5	3.8	72	14.40	32.0	3.9	1.8	110	1.9	12.0	0.1	138	0.22	0.432
1093661	Rock	1.13	1.3	34.8	17.5	69	0.2	13.2	4.6	146	2.59	8.0	2.9	1.8	25	<0.1	0.7	0.3	21	0.04	0.032
1093662	Rock	1.12	15.6	4.3	8.9	3	4.1	1.2	0.2	29	0.52	7.5	2.7	0.6	21	<0.1	7.7	<0.1	91	0.01	0.009
1093663	Rock	0.67	1.4	6.3	1.5	5	0.2	0.9	0.1	33	0.78	13.5	3.0	0.3	10	<0.1	2.7	<0.1	26	<0.01	0.012
1093664	Rock	0.72	25.9	9.0	6.0	15	0.2	8.3	0.2	34	0.50	0.8	0.7	1.0	29	0.6	7.4	<0.1	309	0.02	0.003
1093665	Rock	0.28	135.1	136.1	5.3	148	1.8	36.7	0.3	36	11.18	122.9	3.0	1.7	488	5.7	65.2	0.1	944	0.08	0.669
1093666	Rock	0.69	0.2	9.5	1.8	64	<0.1	20.7	7.9	443	2.82	1.0	0.8	2.3	76	0.3	<0.1	0.1	9	1.05	0.016
1093667	Rock	0.81	0.3	42.8	8.7	36	0.5	25.2	9.6	777	4.06	3.5	2.6	1.8	313	0.1	0.5	<0.1	11	7.47	0.018
1093668	Rock	1.00	0.2	5.4	0.6	120	<0.1	9.5	1.0	387	2.03	5.0	1.7	0.2	265	0.6	0.2	<0.1	4	4.47	0.016
1093669	Rock	0.91	<0.1	15.1	11.1	23	<0.1	25.8	6.4	1109	5.47	2.1	1.4	1.3	475	0.1	0.1	<0.1	18	11.74	0.015
1093670	Rock	0.92	0.7	7.9	2.4	38	1.0	5.7	0.8	54	0.93	1.5	<0.5	0.5	4	0.2	0.2	<0.1	4	0.05	0.005
1093671	Rock	0.65	<0.1	25.0	4.0	45	<0.1	13.7	5.0	1892	2.84	1.0	0.8	2.0	338	<0.1	<0.1	<0.1	11	5.54	0.005
1093672	Rock	0.52	<0.1	10.5	0.6	71	<0.1	8.3	1.6	172	0.44	<0.5	<0.5	1.7	43	0.3	<0.1	<0.1	5	0.30	0.019
1093673	Rock	0.67	13.0	43.6	3.2	38	0.8	21.3	0.2	46	0.58	23.8	<0.5	0.6	34	3.6	37.0	<0.1	1353	0.04	0.030
1093674	Rock	0.64	16.1	50.4	7.0	33	2.2	24.3	0.3	46	0.57	7.2	0.7	1.5	16	13.0	15.4	<0.1	1450	0.01	0.013
1093675	Rock	0.81	13.4	90.0	1.6	98	1.2	17.9	0.4	48	0.67	16.2	1.9	0.6	26	3.7	16.6	<0.1	390	0.01	0.026
1093676	Rock	0.76	6.5	103.7	1.5	254	1.1	32.7	1.9	57	0.66	17.4	<0.5	0.7	99	11.1	11.0	<0.1	178	0.72	0.322

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 21, 2011

CERTIFICATE OF ANALYSIS WHI11000897.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb
	MDL	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2
1093647	Rock	<1	6	0.06	94	<0.001	<20	0.23	<0.001	0.12	<0.1	0.18	<0.1	0.06	1.3	1.2	<1	<0.2	8
1093648	Rock	<1	10	0.06	119	<0.001	<20	0.20	<0.001	0.09	<0.1	0.09	<0.1	<0.05	1.2	0.7	<1	<0.2	4
1093649	Rock	3	2	5.49	88	<0.001	<20	0.05	0.002	0.02	<0.1	0.57	<0.1	<0.05	0.2	0.9	<1	<0.2	<2
1093650	Rock	2	<1	1.39	299	<0.001	<20	0.04	0.006	0.02	<0.1	<0.01	<0.1	<0.05	0.3	<0.5	<1	<0.2	<2
1093651	Rock	<1	<1	5.81	50	<0.001	<20	0.07	0.008	0.01	<0.1	<0.01	<0.1	<0.05	0.1	<0.5	<1	<0.2	<2
1093652	Rock	1	1	<0.01	143	<0.001	<20	0.11	<0.001	0.06	<0.1	0.05	<0.1	<0.05	0.7	<0.5	<1	<0.2	11
1093653	Rock	<1	6	0.04	53	<0.001	<20	0.11	<0.001	0.06	<0.1	0.10	<0.1	<0.05	1.5	<0.5	<1	<0.2	26
1093654	Rock	1	5	<0.01	25	<0.001	<20	0.17	<0.001	0.03	<0.1	0.02	<0.1	<0.05	1.0	<0.5	<1	<0.2	<2
1093655	Rock	<1	5	0.03	160	0.001	<20	0.38	<0.001	0.21	<0.1	0.32	<0.1	<0.05	1.0	0.9	1	<0.2	10
1093656	Rock	4	7	5.59	712	0.001	<20	0.18	0.013	0.11	<0.1	0.04	<0.1	<0.05	2.2	<0.5	<1	<0.2	<2
1093657	Rock	4	7	0.53	85	0.002	<20	0.54	0.003	0.28	<0.1	0.01	<0.1	0.79	3.6	<0.5	1	<0.2	<2
1093658	Rock	8	10	0.03	320	0.002	<20	0.21	0.002	0.11	<0.1	0.11	0.4	0.36	0.9	8.3	<1	<0.2	6
1093659	Rock	5	22	0.03	409	0.004	<20	0.22	<0.001	0.08	<0.1	0.25	0.4	0.14	0.7	10.9	2	<0.2	<2
1093660	Rock	9	53	0.03	129	0.003	<20	0.88	<0.001	0.09	0.2	0.10	0.5	0.45	4.9	10.9	2	<0.2	3
1093661	Rock	2	7	0.06	772	<0.001	<20	0.52	0.003	0.25	<0.1	0.04	0.1	0.24	2.3	0.9	1	<0.2	3
1093662	Rock	<1	10	0.01	535	<0.001	<20	0.19	<0.001	0.11	<0.1	0.47	0.4	0.10	0.5	32.2	<1	<0.2	4
1093663	Rock	<1	7	<0.01	316	<0.001	<20	0.17	0.002	0.05	<0.1	0.03	<0.1	<0.05	0.5	7.8	<1	<0.2	<2
1093664	Rock	5	6	0.02	1022	0.002	<20	0.19	0.002	0.10	<0.1	0.17	0.3	0.26	0.5	42.1	1	0.3	3
1093665	Rock	4	127	0.13	58	0.011	<20	1.44	0.003	0.35	0.3	0.11	5.0	1.22	3.6	>100	8	1.2	4
1093666	Rock	5	4	0.61	218	0.001	<20	0.54	0.003	0.27	<0.1	0.03	<0.1	0.26	3.6	<0.5	1	<0.2	<2
1093667	Rock	7	6	4.20	33	0.001	<20	0.25	0.006	0.17	<0.1	0.11	<0.1	1.33	3.3	1.5	<1	<0.2	16
1093668	Rock	<1	2	2.06	372	<0.001	<20	0.06	<0.001	0.01	<0.1	0.04	<0.1	0.11	0.8	<0.5	<1	<0.2	<2
1093669	Rock	6	5	6.16	100	0.003	<20	0.16	0.013	0.09	<0.1	<0.01	<0.1	0.54	1.8	<0.5	<1	<0.2	<2
1093670	Rock	1	8	<0.01	304	<0.001	<20	0.09	<0.001	0.06	<0.1	0.08	<0.1	0.40	0.3	2.6	<1	<0.2	<2
1093671	Rock	7	4	2.77	153	0.001	<20	0.28	0.004	0.19	<0.1	0.03	<0.1	0.47	3.7	0.8	<1	<0.2	<2
1093672	Rock	4	4	0.17	789	0.001	<20	0.41	0.003	0.25	<0.1	<0.01	<0.1	<0.05	2.3	<0.5	1	<0.2	<2
1093673	Rock	3	30	0.03	273	0.006	<20	0.25	<0.001	0.08	<0.1	0.21	0.2	0.11	1.0	7.8	2	<0.2	<2
1093674	Rock	15	35	0.04	1407	0.009	<20	0.42	<0.001	0.13	0.2	1.27	0.5	0.12	1.5	13.3	2	0.2	<2
1093675	Rock	4	29	0.01	567	0.002	<20	0.16	0.001	0.03	<0.1	0.25	0.3	<0.05	0.6	5.8	<1	<0.2	<2
1093676	Rock	5	36	0.04	290	0.002	<20	0.14	<0.001	0.04	<0.1	0.38	<0.1	<0.05	0.8	6.2	<1	<0.2	<2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 21, 2011

CERTIFICATE OF ANALYSIS WHI11000897.1

Method		WGHT	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093677	Rock	0.58	22.7	23.1	5.2	98	3.4	33.8	0.6	28	0.75	23.0	<0.5	2.5	21	0.7	8.3	<0.1	282	0.03	0.141
1093678	Rock	0.98	14.8	30.7	6.1	88	0.9	22.4	0.4	47	0.74	6.7	0.9	1.2	48	3.9	9.2	<0.1	437	0.20	0.066
1093679	Rock	0.86	2.0	26.1	2.3	96	1.4	11.5	0.6	58	0.61	11.6	<0.5	0.6	493	0.9	2.6	<0.1	78	4.59	1.747
1093680	Rock	0.85	1.0	18.2	3.3	246	1.1	52.3	8.5	113	1.36	21.1	2.0	0.9	11	2.8	2.9	<0.1	12	0.03	0.026
1094042	Rock	1.21	0.9	99.2	27.0	151	1.2	54.3	20.9	330	7.60	7.3	14.7	1.4	15	0.2	0.7	0.2	11	0.08	0.029
1094043	Rock	1.26	0.4	21.3	7.1	36	0.1	20.8	5.6	655	3.86	5.5	1.6	1.5	294	<0.1	0.3	<0.1	10	8.12	0.013
1094044	Rock	1.62	3.2	73.8	14.0	114	1.2	38.8	9.5	122	2.52	6.3	<0.5	3.3	124	0.4	0.5	0.2	19	1.39	0.123
1094045	Rock	1.35	0.1	14.8	4.8	32	<0.1	15.4	6.2	549	3.18	1.1	<0.5	1.8	351	0.1	0.1	<0.1	10	9.09	0.022
1094046	Rock	1.70	3.4	106.6	3.2	354	<0.1	75.9	15.2	319	4.27	44.7	1.6	0.4	5	2.2	1.2	0.1	13	0.03	0.029
1094047	Rock	1.14	0.7	63.8	5.6	182	0.2	47.5	10.7	221	3.14	57.7	4.0	0.5	7	0.2	1.5	<0.1	13	0.02	0.026
1094048	Rock	0.92	61.0	110.2	9.6	1574	0.8	84.3	4.3	150	1.20	48.3	<0.5	2.8	220	21.5	16.4	0.1	358	8.30	0.042
1095906	Rock	0.55	19.4	187.4	2.7	322	1.9	35.1	1.0	260	0.33	53.4	0.5	0.6	1752	10.4	44.5	<0.1	443	19.53	0.022

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 21, 2011

CERTIFICATE OF ANALYSIS WHI11000897.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb
	MDL	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2
1093677	Rock	21	61	0.03	726	0.003	<20	0.27	<0.001	0.12	<0.1	0.83	<0.1	0.12	2.2	31.9	1	<0.2	4
1093678	Rock	6	18	0.03	1065	0.003	<20	0.33	<0.001	0.14	<0.1	1.81	0.2	0.23	1.0	28.6	2	0.2	<2
1093679	Rock	15	52	0.07	669	0.010	<20	0.28	0.021	0.13	<0.1	0.37	<0.1	0.17	2.0	7.3	<1	<0.2	<2
1093680	Rock	3	9	0.01	421	<0.001	<20	0.15	<0.001	0.05	<0.1	0.08	<0.1	0.07	1.0	1.3	<1	<0.2	6
1094042	Rock	2	8	0.06	780	0.001	<20	0.39	0.002	0.20	<0.1	0.41	<0.1	0.10	3.4	3.8	<1	<0.2	61
1094043	Rock	6	9	3.74	173	0.002	<20	0.28	0.006	0.15	<0.1	0.08	<0.1	0.22	3.1	0.6	<1	<0.2	2
1094044	Rock	9	13	0.65	635	0.002	<20	0.69	0.003	0.30	<0.1	0.23	<0.1	0.05	3.4	1.3	2	<0.2	9
1094045	Rock	5	8	4.37	188	0.002	<20	0.33	0.008	0.19	<0.1	0.03	<0.1	0.68	4.0	<0.5	<1	<0.2	<2
1094046	Rock	1	8	0.02	392	<0.001	<20	0.27	<0.001	0.09	<0.1	0.09	<0.1	<0.05	3.3	1.1	<1	<0.2	4
1094047	Rock	<1	12	0.02	1432	<0.001	<20	0.25	<0.001	0.06	<0.1	0.11	<0.1	0.07	3.6	0.9	<1	<0.2	10
1094048	Rock	8	20	4.40	344	0.002	<20	0.23	0.008	0.13	0.1	3.10	0.5	0.50	3.5	19.7	<1	<0.2	3
1095906	Rock	5	18	1.98	687	0.009	<20	0.09	0.006	0.04	0.1	0.31	0.2	<0.05	1.0	2.2	<1	<0.2	<2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 21, 2011

QUALITY CONTROL REPORT WHI11000897.1

	Method	WGHT	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1093648	Rock	0.77	0.4	34.1	4.7	28	0.1	16.9	3.6	144	1.55	1.7	3.6	0.7	6	0.2	0.2	0.1	7	0.15	0.009
REP 1093648	QC																				
1093656	Rock	1.22	<0.1	17.8	3.4	27	<0.1	15.1	4.3	1388	5.00	2.1	1.3	1.1	321	0.3	0.2	<0.1	24	11.11	0.008
REP 1093656	QC		<0.1	18.0	3.4	28	<0.1	15.7	4.5	1390	5.00	2.2	1.9	1.1	324	0.3	0.2	<0.1	24	11.11	0.007
1093667	Rock	0.81	0.3	42.8	8.7	36	0.5	25.2	9.6	777	4.06	3.5	2.6	1.8	313	0.1	0.5	<0.1	11	7.47	0.018
REP 1093667	QC																				
Core Reject Duplicates																					
1093665	Rock	0.28	135.1	136.1	5.3	148	1.8	36.7	0.3	36	11.18	122.9	3.0	1.7	488	5.7	65.2	0.1	944	0.08	0.669
DUP 1093665	QC		138.8	138.7	5.9	147	1.9	38.7	0.3	47	11.61	121.2	<0.5	1.9	556	6.2	66.7	<0.1	959	0.08	0.699
Reference Materials																					
STD DS8	Standard		13.5	118.0	126.8	326	1.6	39.1	7.8	647	2.65	28.6	90.0	7.0	66	2.4	4.1	6.8	44	0.66	0.086
STD DS8	Standard		14.6	111.3	132.5	304	1.8	38.5	7.6	598	2.45	26.3	86.3	7.5	71	2.4	4.5	6.7	42	0.71	0.083
STD OREAS45CA	Standard		0.7	483.4	20.1	63	0.3	231.5	88.5	889	15.16	3.3	39.1	7.0	15	<0.1	<0.1	0.2	192	0.39	0.034
STD OREAS45CA	Standard		1.0	513.9	22.8	60	0.3	251.1	89.0	901	15.81	3.7	40.7	7.9	14	<0.1	<0.1	0.2	202	0.43	0.039
STD OXC88	Standard																				
STD OXC88	Standard																				
STD OXH82	Standard																				
STD OXH82	Standard																				
STD OXC88 Expected																					
STD OXH82 Expected																					
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08
STD OREAS45CA Expected			1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 21, 2011

QUALITY CONTROL REPORT WHI11000897.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb
	MDL	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2
Pulp Duplicates																			
1093648	Rock	<1	10	0.06	119	<0.001	<20	0.20	<0.001	0.09	<0.1	0.09	<0.1	<0.05	1.2	0.7	<1	<0.2	4
REP 1093648	QC																		4
1093656	Rock	4	7	5.59	712	0.001	<20	0.18	0.013	0.11	<0.1	0.04	<0.1	<0.05	2.2	<0.5	<1	<0.2	<2
REP 1093656	QC	4	7	5.60	722	0.001	<20	0.18	0.013	0.12	<0.1	0.06	<0.1	<0.05	2.2	0.6	<1	<0.2	
1093667	Rock	7	6	4.20	33	0.001	<20	0.25	0.006	0.17	<0.1	0.11	<0.1	1.33	3.3	1.5	<1	<0.2	16
REP 1093667	QC																		21
Core Reject Duplicates																			
1093665	Rock	4	127	0.13	58	0.011	<20	1.44	0.003	0.35	0.3	0.11	5.0	1.22	3.6	>100	8	1.2	4
DUP 1093665	QC	5	130	0.13	33	0.010	<20	1.45	0.003	0.36	0.3	0.14	6.5	1.28	3.7	>100	8	1.2	3
Reference Materials																			
STD DS8	Standard	16	125	0.65	293	0.123	<20	0.99	0.094	0.45	2.9	0.19	5.6	0.18	2.3	5.4	5	5.0	
STD DS8	Standard	15	109	0.60	295	0.128	<20	0.93	0.094	0.42	2.7	0.18	5.0	0.16	1.9	4.7	5	4.7	
STD OREAS45CA	Standard	16	717	0.13	156	0.126	<20	3.69	0.013	0.08	<0.1	0.04	<0.1	<0.05	33.8	0.6	18	<0.2	
STD OREAS45CA	Standard	18	640	0.16	173	0.149	<20	3.72	0.008	0.07	<0.1	0.03	<0.1	<0.05	35.0	<0.5	18	<0.2	
STD OXC88	Standard																		201
STD OXC88	Standard																		205
STD OXH82	Standard																		1299
STD OXH82	Standard																		1377
STD OXC88 Expected																			203
STD OXH82 Expected																			1278
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5	
STD OREAS45CA Expected		15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4		
BLK	Blank																		<2
BLK	Blank																		<2
BLK	Blank																		<2
BLK	Blank																		<2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2	
BLK	Blank	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 21, 2011

QUALITY CONTROL REPORT WHI11000897.1

		WGHT Wgt kg 0.01	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001
Prep Wash																					
G1	Prep Blank		0.4	3.2	4.2	43	<0.1	5.9	3.9	518	1.95	3.8	5.9	5.9	64	<0.1	0.2	0.1	36	0.48	0.079
G1	Prep Blank		0.4	3.5	3.6	44	<0.1	6.2	4.0	551	2.01	0.5	5.3	5.9	60	<0.1	<0.1	0.1	37	0.47	0.077

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 21, 2011

QUALITY CONTROL REPORT WHI11000897.1

		1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2	3B Au ppb 2
Prep Wash																			
G1	Prep Blank	12	9	0.48	161	0.128	<20	0.88	0.086	0.46	<0.1	<0.01	0.2	<0.05	1.8	<0.5	4	<0.2	<2
G1	Prep Blank	13	9	0.49	160	0.135	<20	0.88	0.086	0.46	<0.1	<0.01	0.2	<0.05	1.8	<0.5	4	<0.2	<2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 05, 2011
Report Date: September 20, 2011
Page: 1 of 5

CERTIFICATE OF ANALYSIS WHI11001019.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #10
P.O. Number
Number of Samples: 116

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-500	116	Crush, split and pulverize 500 g rock to 200 mesh			VAN
3B	116	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	116	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

CERTIFICATE OF ANALYSIS WHI11001019.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1095351	Rock	1.79	<2	1.1	55.3	15.4	40	<0.1	118.2	31.2	1174	4.80	2.4	5.0	8.7	473	0.2	0.2	<0.1	129	9.44
1095352	Rock	1.41	<2	17.2	35.5	9.1	68	0.2	181.9	17.7	355	2.41	34.7	6.1	1.1	180	0.1	1.8	<0.1	70	3.44
1095353	Rock	1.66	<2	0.8	48.9	1.1	79	<0.1	199.0	37.2	1325	6.22	8.6	4.9	1.1	483	0.2	0.1	<0.1	111	9.31
1095354	Rock	1.16	<2	170.4	139.6	18.4	1792	1.3	259.6	4.1	84	3.45	83.2	6.3	1.6	327	14.4	56.4	0.2	367	9.32
1095355	Rock	1.57	4	1.3	36.8	49.9	165	0.4	33.9	15.9	436	10.51	24.5	4.9	2.2	25	0.2	0.2	<0.1	44	0.04
1095356	Rock	1.45	<2	0.4	6.9	11.8	45	<0.1	11.9	4.3	75	1.30	4.6	5.5	0.6	17	<0.1	0.5	<0.1	12	<0.01
1095357	Rock	1.53	<2	0.7	19.3	13.9	75	0.1	26.4	6.1	64	3.29	9.3	3.6	2.7	10	<0.1	<0.1	0.1	41	<0.01
1095358	Rock	1.33	3	0.7	18.3	16.1	89	0.2	23.9	6.1	57	3.47	13.7	3.8	2.4	15	<0.1	<0.1	0.1	43	0.02
1095359	Rock	1.23	3	0.5	15.3	20.1	65	0.5	30.5	21.6	2888	34.10	37.1	4.2	1.6	47	0.1	0.5	<0.1	56	0.07
1095360	Rock	1.39	14	1.1	35.0	23.0	217	0.4	42.0	17.0	510	13.71	18.0	4.7	2.2	40	0.1	0.2	0.1	51	0.14
1094050	Rock	2.07	7	0.2	53.9	8.0	50	0.2	24.7	7.6	75	2.22	2.5	6.5	0.8	60	0.1	0.2	0.2	11	1.22
1095492	Rock	1.77	<2	2.8	76.8	2.9	116	<0.1	34.7	30.7	862	5.97	1.4	3.1	0.3	52	0.7	0.3	<0.1	119	2.17
1095493	Rock	1.01	<2	0.1	15.1	2.9	15	0.1	11.4	6.1	805	4.10	2.0	3.3	3.1	544	<0.1	0.3	<0.1	11	7.74
1095494	Rock	1.16	<2	0.2	52.6	1.0	38	<0.1	238.9	36.9	1686	8.85	17.0	4.3	1.0	481	0.1	<0.1	<0.1	142	9.53
1095497	Rock	1.29	<2	0.7	35.8	2.1	12	<0.1	137.2	29.4	1098	5.33	1.2	3.5	1.4	310	<0.1	0.2	<0.1	112	8.76
1095498	Rock	1.11	<2	1.6	30.3	3.5	20	<0.1	214.9	34.9	1287	5.42	1.4	2.8	2.7	669	<0.1	<0.1	<0.1	94	14.80
1095499	Rock	1.37	<2	1.7	58.9	4.7	273	<0.1	213.7	43.2	1375	4.45	2.9	2.6	1.6	778	1.6	0.4	<0.1	98	16.10
1095500	Rock	1.24	<2	<0.1	37.2	1.0	16	<0.1	199.4	33.1	1679	6.80	0.5	3.9	1.1	656	<0.1	<0.1	<0.1	129	9.97
1277586	Rock	1.46	<2	31.3	13.7	10.6	480	<0.1	60.7	7.6	441	1.56	22.3	3.2	2.4	157	3.3	3.9	<0.1	170	7.08
1277587	Rock	1.13	<2	0.8	12.1	4.6	8	0.1	3.2	0.3	30	0.55	4.8	3.6	0.7	27	<0.1	0.3	0.1	20	0.06
1277588	Rock	1.33	3	1.7	341.1	9.3	364	0.1	89.6	21.1	645	9.05	21.1	4.6	1.1	43	1.5	0.7	0.1	163	0.07
1277589	Rock	1.36	<2	0.7	726.7	4.5	474	0.2	163.4	31.4	887	10.89	9.2	3.3	0.8	67	2.0	0.6	<0.1	81	0.51
1277569	Rock	3.58	<2	1.0	45.3	2.2	97	<0.1	182.6	40.7	1081	5.03	14.5	3.7	4.2	321	1.5	0.3	<0.1	62	9.63
1277562	Rock	1.46	4	33.9	53.3	8.3	1833	1.1	160.9	18.9	850	11.50	24.5	5.2	1.2	64	13.6	6.0	0.1	143	0.38
1277590	Rock	1.35	<2	1.7	161.4	5.6	191	0.1	150.7	37.3	1024	7.82	6.1	2.9	1.9	26	2.9	0.4	0.1	57	0.05
1277591	Rock	1.53	3	1.9	60.7	8.1	96	0.3	65.8	6.0	170	3.81	10.1	3.6	1.9	54	0.6	0.5	0.3	106	0.07
1277592	Rock	1.29	<2	21.2	27.3	5.7	136	<0.1	55.0	4.0	384	1.47	7.0	3.0	1.1	328	1.6	1.7	<0.1	68	20.29
1277593	Rock	1.60	<2	2.7	31.2	1.8	138	<0.1	61.6	24.3	1452	6.46	59.2	5.3	4.3	677	0.2	1.4	<0.1	58	9.65
1277594	Rock	2.15	10	84.4	125.7	69.4	356	0.9	117.7	19.3	120	22.71	171.2	6.8	4.3	81	0.2	33.8	<0.1	101	3.58
1277595	Rock	1.40	<2	4.7	21.3	0.6	30	<0.1	17.6	1.9	303	1.13	1.5	2.6	0.8	100	0.1	2.2	<0.1	54	2.81

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

CERTIFICATE OF ANALYSIS WHI11001019.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1095351	Rock	0.281	35	173	4.26	194	0.002	<20	1.64	0.004	0.03	<0.1	0.02	0.1	<0.05	16.3	1.4	5	<0.2
1095352	Rock	0.130	2	53	1.07	330	0.001	<20	0.48	0.004	0.04	<0.1	0.06	0.4	<0.05	4.7	2.5	1	<0.2
1095353	Rock	0.125	2	225	3.96	321	<0.001	<20	1.20	0.013	0.03	<0.1	<0.01	0.1	<0.05	13.8	1.2	3	<0.2
1095354	Rock	0.035	5	14	0.79	165	0.001	<20	0.19	0.003	0.08	<0.1	0.62	0.4	0.05	1.8	32.4	<1	0.3
1095355	Rock	0.173	3	24	0.25	316	<0.001	<20	1.36	0.004	0.06	<0.1	0.16	<0.1	0.05	3.5	2.8	4	<0.2
1095356	Rock	0.010	<1	11	0.05	2585	<0.001	<20	0.27	<0.001	<0.01	<0.1	0.03	<0.1	0.10	0.9	0.9	<1	<0.2
1095357	Rock	0.036	2	27	0.38	194	<0.001	<20	1.66	0.005	0.09	<0.1	0.05	<0.1	<0.05	3.1	1.1	5	<0.2
1095358	Rock	0.037	2	25	0.31	2091	<0.001	<20	1.59	0.003	0.08	<0.1	0.11	<0.1	0.07	2.9	1.3	5	<0.2
1095359	Rock	0.371	4	22	0.12	1359	0.002	<20	0.81	0.004	0.05	<0.1	0.22	<0.1	0.21	4.0	2.3	2	<0.2
1095360	Rock	0.231	3	29	0.23	1069	0.001	<20	1.58	0.007	0.10	<0.1	0.17	<0.1	0.09	5.1	2.3	4	<0.2
1094050	Rock	0.023	2	13	0.66	49	0.001	<20	0.63	0.004	0.31	<0.1	0.16	0.1	1.77	3.3	1.2	2	<0.2
1095492	Rock	0.075	5	31	2.20	211	0.276	<20	3.32	0.043	0.07	<0.1	0.03	<0.1	<0.05	8.8	0.8	13	<0.2
1095493	Rock	0.019	11	9	3.69	1210	<0.001	<20	0.25	0.008	0.17	<0.1	0.02	<0.1	0.06	3.2	1.1	<1	<0.2
1095494	Rock	0.125	2	256	4.01	165	<0.001	<20	1.57	0.007	0.01	<0.1	<0.01	<0.1	<0.05	18.2	0.9	5	<0.2
1095497	Rock	0.191	2	149	3.16	137	0.001	<20	0.16	0.010	0.02	<0.1	0.03	<0.1	<0.05	10.2	1.1	1	<0.2
1095498	Rock	0.122	8	129	4.46	670	<0.001	<20	0.19	0.023	0.03	<0.1	0.03	<0.1	<0.05	11.1	1.2	<1	<0.2
1095499	Rock	0.231	4	160	2.01	973	0.001	<20	0.37	0.017	0.05	<0.1	0.03	0.1	<0.05	15.6	1.4	2	<0.2
1095500	Rock	0.144	1	179	3.94	87	<0.001	<20	0.34	0.010	<0.01	<0.1	0.02	<0.1	0.10	17.8	1.1	2	<0.2
1277586	Rock	0.031	3	12	3.71	223	<0.001	<20	0.24	0.009	0.10	<0.1	0.25	0.1	<0.05	3.3	3.2	<1	<0.2
1277587	Rock	0.032	1	<1	0.02	92	<0.001	<20	0.23	0.002	0.09	<0.1	0.04	<0.1	<0.05	3.9	1.2	<1	<0.2
1277588	Rock	0.143	2	39	0.25	92	<0.001	<20	1.25	<0.001	0.06	<0.1	0.05	<0.1	0.06	7.9	7.0	4	<0.2
1277589	Rock	0.148	2	25	0.06	88	<0.001	<20	1.83	<0.001	0.06	<0.1	0.04	<0.1	0.21	5.4	2.5	<1	<0.2
1277569	Rock	0.178	32	99	2.97	132	0.005	<20	0.74	0.006	0.21	<0.1	0.01	<0.1	0.30	12.8	0.8	2	<0.2
1277562	Rock	0.288	4	21	0.04	4074	0.001	<20	0.43	0.001	0.13	<0.1	0.76	0.5	0.10	2.2	5.9	1	<0.2
1277590	Rock	0.062	4	24	0.12	115	<0.001	<20	0.89	0.002	0.12	<0.1	0.05	<0.1	<0.05	7.4	2.3	2	<0.2
1277591	Rock	0.100	4	34	0.28	142	<0.001	<20	1.73	<0.001	0.12	<0.1	0.06	0.1	0.07	4.5	1.7	3	<0.2
1277592	Rock	0.027	2	11	2.01	144	<0.001	<20	0.13	0.007	0.05	<0.1	0.10	0.2	<0.05	2.6	3.1	<1	<0.2
1277593	Rock	0.236	31	43	3.67	261	0.002	<20	0.72	0.003	0.13	<0.1	0.02	0.1	0.05	9.5	1.2	2	<0.2
1277594	Rock	0.283	10	42	0.16	292	0.002	<20	0.27	0.003	0.14	<0.1	0.31	1.2	0.25	6.6	20.3	1	<0.2
1277595	Rock	0.011	1	8	1.09	101	<0.001	<20	0.11	<0.001	0.05	<0.1	0.02	<0.1	<0.05	0.8	0.8	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

CERTIFICATE OF ANALYSIS WHI11001019.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1277596	Rock	2.28	18	1.8	52.7	23.1	40	0.9	57.6	36.8	432	9.67	10.3	7.6	2.8	50	<0.1	1.1	0.4	10	2.05
1277597	Rock	1.10	3	1.1	27.9	5.0	47	0.1	25.4	8.9	311	2.98	20.1	5.5	4.2	219	0.2	1.9	0.2	9	2.22
1277598	Rock	1.35	<2	1.8	78.5	0.9	114	<0.1	26.8	25.3	976	4.96	52.1	3.2	0.2	505	0.2	2.3	<0.1	31	7.08
1277599	Rock	1.91	<2	0.6	71.6	1.1	59	<0.1	41.6	26.8	951	4.66	27.8	5.0	0.3	243	0.4	2.7	<0.1	31	6.73
1277600	Rock	1.90	<2	1.0	66.9	1.1	68	<0.1	54.2	32.3	975	4.85	129.7	3.3	0.2	463	0.3	7.7	<0.1	33	6.14
1277570	Rock	1.56	6	61.3	30.1	17.4	60	0.7	10.0	0.9	41	2.02	95.5	7.6	2.0	22	0.1	18.1	0.2	207	0.02
1277571	Rock	1.13	37	87.6	24.3	19.3	7	1.1	2.9	0.1	22	3.55	307.2	4.7	5.2	38	1.2	13.5	0.2	178	0.04
1277572	Rock	1.30	10	33.9	58.8	46.1	6	1.2	3.5	<0.1	20	0.87	23.9	1.2	1.3	31	0.1	8.7	<0.1	207	<0.01
1277573	Rock	1.15	6	165.0	56.1	64.6	21	1.8	5.8	0.2	19	3.06	59.7	2.3	1.6	513	0.9	91.5	<0.1	1424	7.31
1277574	Rock	0.98	<2	62.8	87.8	5.7	1283	0.9	131.2	2.4	46	3.66	65.5	2.1	1.2	17	2.2	23.7	<0.1	844	0.03
1277575	Rock	1.08	<2	1.5	41.5	5.9	70	<0.1	207.5	49.8	1996	8.41	19.4	2.5	4.0	203	0.2	0.6	<0.1	116	8.40
1277576	Rock	1.38	<2	1.3	1.8	2.7	21	<0.1	13.3	2.5	1135	4.16	4.6	1.0	0.3	163	<0.1	0.5	<0.1	5	18.67
1277577	Rock	1.16	<2	0.6	1.8	1.4	13	<0.1	9.6	1.9	703	2.73	5.3	2.0	0.2	93	<0.1	0.8	<0.1	7	12.04
1277578	Rock	1.96	<2	0.4	15.6	204.6	102	<0.1	63.9	29.5	2972	23.94	5.1	1.1	0.5	1	<0.1	0.2	<0.1	14	0.09
1277579	Rock	1.25	<2	0.5	25.5	11.5	62	<0.1	25.5	20.5	384	4.53	17.1	<0.5	5.8	7	0.1	0.4	0.4	5	0.07
1277555	Rock	2.08	4	<0.1	17.1	3.5	32	<0.1	12.9	4.4	545	3.20	<0.5	0.7	1.7	285	<0.1	0.1	<0.1	12	8.80
1277556	Rock	1.77	6	0.5	44.6	5.7	92	0.4	41.4	13.0	176	2.07	1.8	1.0	1.9	71	0.2	0.4	0.1	20	1.69
1277557	Rock	1.56	6	0.5	63.3	5.2	64	0.2	24.6	4.5	80	2.17	7.0	1.1	0.4	25	0.5	0.4	0.1	12	0.02
1277559	Rock	1.56	17	0.3	1.5	35.8	40	<0.1	2.6	0.6	129	0.61	73.4	13.7	6.3	46	0.3	0.3	0.4	<2	0.28
1277560	Rock	1.36	<2	<0.1	21.1	1.6	61	<0.1	14.0	4.5	314	1.90	0.6	1.5	2.1	64	<0.1	<0.1	0.1	9	0.62
1093701	Rock	0.97	3	2.9	31.4	7.9	95	0.2	57.2	10.7	75	2.83	19.4	<0.5	0.6	35	0.9	2.7	0.1	19	0.03
1093702	Rock	1.04	<2	0.5	20.7	10.3	145	<0.1	43.1	3.8	69	3.20	4.7	0.6	0.8	5	<0.1	0.2	0.1	27	0.01
1093703	Rock	0.59	<2	5.0	109.1	1.6	219	0.2	0.6	0.2	7	>40	312.4	1.3	0.3	2	0.1	12.3	<0.1	2976	<0.01
1093704	Rock	0.79	<2	1.0	4.0	52.5	6	0.2	0.6	<0.1	21	0.70	9.0	1.3	10.0	14	0.1	0.3	1.8	13	<0.01
1093705	Rock	0.87	3	1.4	10.0	9.7	1	1.1	4.9	0.5	49	0.67	2.1	1.0	0.5	9	<0.1	0.9	<0.1	14	<0.01
1093706	Rock	0.74	<2	0.1	7.2	2.3	11	<0.1	7.4	4.0	1673	3.99	1.8	<0.5	2.5	540	<0.1	<0.1	<0.1	11	14.52
1093707	Rock	0.64	<2	0.2	23.1	2.4	11	<0.1	8.5	3.5	353	1.38	1.2	<0.5	4.2	47	<0.1	0.1	<0.1	8	1.45
1093708	Rock	0.69	<2	2.0	3.1	19.4	20	<0.1	3.5	1.9	149	0.79	9.8	<0.5	6.2	11	0.2	0.1	0.1	5	0.22
1093709	Rock	0.88	<2	5.1	6.5	17.3	5	0.4	6.8	<0.1	36	0.40	2.0	<0.5	1.0	3	<0.1	1.6	0.1	145	0.02
1093710	Rock	0.92	<2	0.2	0.6	0.4	9	<0.1	1.2	0.2	51	0.18	<0.5	<0.5	0.1	290	0.2	<0.1	<0.1	3	11.66

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

CERTIFICATE OF ANALYSIS WHI11001019.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1277596	Rock	0.025	3	10	0.74	18	<0.001	<20	0.38	0.005	0.19	<0.1	0.16	0.2	2.28	3.6	2.3	<1	0.2
1277597	Rock	0.025	9	9	0.83	1423	<0.001	<20	0.47	0.003	0.21	<0.1	0.04	<0.1	0.21	3.6	0.5	1	<0.2
1277598	Rock	0.060	5	23	1.56	419	0.001	<20	0.46	0.007	0.21	<0.1	0.07	0.1	0.05	17.0	1.0	1	<0.2
1277599	Rock	0.062	5	74	1.71	334	0.002	<20	0.81	0.002	0.24	<0.1	0.02	<0.1	0.05	18.7	<0.5	2	<0.2
1277600	Rock	0.056	5	43	2.60	326	<0.001	<20	0.64	0.002	0.23	<0.1	0.03	0.1	0.06	15.5	<0.5	1	<0.2
1277570	Rock	0.197	3	22	0.02	290	0.003	<20	0.19	<0.001	0.12	0.2	0.77	0.8	0.16	5.7	29.2	1	<0.2
1277571	Rock	1.159	6	102	0.02	492	0.011	<20	0.50	<0.001	0.18	0.6	2.80	3.3	0.36	26.4	38.1	4	<0.2
1277572	Rock	0.049	6	25	0.02	1107	0.003	<20	0.28	<0.001	0.11	0.1	0.72	0.4	0.12	1.4	13.6	2	<0.2
1277573	Rock	3.152	15	46	0.07	2007	0.025	25	0.97	<0.001	0.24	0.4	2.12	0.9	0.07	2.9	46.9	4	0.6
1277574	Rock	0.082	5	34	0.03	460	0.003	<20	0.48	<0.001	0.07	<0.1	1.13	0.9	0.10	3.5	14.2	3	<0.2
1277575	Rock	0.237	29	181	4.13	88	0.007	<20	2.32	<0.001	0.03	<0.1	0.04	<0.1	<0.05	12.6	<0.5	9	<0.2
1277576	Rock	0.004	2	2	7.24	43	<0.001	<20	0.04	0.005	0.01	<0.1	0.03	<0.1	<0.05	0.4	<0.5	<1	<0.2
1277577	Rock	0.010	2	3	4.67	39	<0.001	<20	0.05	0.003	0.01	<0.1	0.02	<0.1	<0.05	0.2	<0.5	<1	<0.2
1277578	Rock	0.043	1	10	0.15	42	<0.001	<20	0.22	0.001	0.02	<0.1	0.03	<0.1	<0.05	3.3	<0.5	<1	<0.2
1277579	Rock	0.051	8	5	0.06	61	<0.001	<20	0.51	0.004	0.17	<0.1	0.05	<0.1	<0.05	4.4	<0.5	1	<0.2
1277555	Rock	0.019	5	9	4.18	370	0.001	<20	0.33	0.008	0.19	<0.1	0.04	<0.1	0.17	3.7	<0.5	<1	<0.2
1277556	Rock	0.053	4	9	0.84	282	0.001	<20	0.52	0.002	0.27	<0.1	0.18	<0.1	0.10	3.5	<0.5	1	<0.2
1277557	Rock	0.016	1	8	0.02	1271	<0.001	<20	0.26	0.002	0.11	<0.1	0.16	<0.1	0.08	2.3	<0.5	<1	<0.2
1277559	Rock	0.005	7	1	0.03	380	<0.001	<20	0.33	0.023	0.29	<0.1	0.02	0.1	<0.05	0.2	<0.5	<1	<0.2
1277560	Rock	0.020	3	6	0.48	645	0.001	<20	0.56	0.001	0.29	<0.1	0.07	<0.1	0.11	3.4	<0.5	1	<0.2
1093701	Rock	0.032	1	9	<0.01	19	<0.001	<20	3.14	<0.001	0.12	<0.1	0.41	0.6	1.28	3.4	1.2	4	<0.2
1093702	Rock	0.022	1	15	0.47	216	<0.001	<20	1.23	<0.001	0.04	<0.1	0.02	<0.1	<0.05	4.0	<0.5	4	<0.2
1093703	Rock	1.003	<1	68	<0.01	388	0.006	<20	0.59	<0.001	<0.01	<0.1	0.09	<0.1	0.36	1.1	4.3	<1	<0.2
1093704	Rock	0.020	14	3	0.02	231	<0.001	<20	0.37	0.013	0.24	0.1	<0.01	0.3	0.15	0.2	1.2	2	<0.2
1093705	Rock	0.035	2	9	<0.01	253	<0.001	<20	0.08	0.001	0.05	<0.1	0.25	<0.1	0.13	0.4	4.5	<1	<0.2
1093706	Rock	0.007	11	6	5.90	1565	0.002	<20	0.23	0.008	0.14	<0.1	0.03	<0.1	<0.05	2.3	<0.5	<1	<0.2
1093707	Rock	0.012	6	6	0.62	612	<0.001	<20	0.38	0.004	0.24	<0.1	0.01	<0.1	<0.05	2.2	<0.5	<1	<0.2
1093708	Rock	0.014	11	6	0.15	115	0.030	<20	0.41	0.031	0.23	<0.1	<0.01	0.1	<0.05	1.4	<0.5	2	<0.2
1093709	Rock	0.006	4	8	0.02	61	0.001	<20	0.13	<0.001	0.07	<0.1	0.31	<0.1	<0.05	0.4	<0.5	<1	<0.2
1093710	Rock	0.026	1	5	0.18	57	<0.001	<20	0.02	0.002	<0.01	<0.1	<0.01	<0.1	<0.05	0.2	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

CERTIFICATE OF ANALYSIS WHI11001019.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1093711	Rock	0.94	<2	1.4	3.0	0.3	7	<0.1	3.1	0.2	132	0.29	0.6	<0.5	0.2	739	0.1	<0.1	<0.1	3	13.44
1093712	Rock	0.91	2	0.2	18.0	10.0	19	<0.1	34.2	12.0	1849	6.05	1.6	<0.5	2.0	318	<0.1	0.3	<0.1	18	7.61
1093713	Rock	0.64	<2	0.4	21.6	6.9	103	<0.1	53.3	19.2	863	3.48	11.2	<0.5	4.4	13	<0.1	0.1	0.1	25	0.18
1093714	Rock	0.63	<2	0.4	20.9	8.7	130	<0.1	52.7	16.2	773	3.60	4.1	<0.5	3.2	19	0.1	<0.1	0.1	26	0.13
1093715	Rock	0.89	<2	0.5	12.3	10.9	64	<0.1	21.1	4.5	59	3.11	6.3	<0.5	1.9	7	<0.1	<0.1	<0.1	35	0.01
1093716	Rock	0.78	3	0.2	13.3	9.2	55	0.2	8.2	2.7	52	2.02	27.1	<0.5	1.6	5	<0.1	0.2	<0.1	15	0.01
1093717	Rock	0.68	<2	0.1	5.9	8.0	47	<0.1	20.8	3.6	79	3.55	2.8	<0.5	0.5	4	<0.1	<0.1	<0.1	30	0.01
1093718	Rock	0.75	4	0.5	6.4	18.6	23	0.2	16.2	3.0	51	2.23	14.2	<0.5	1.2	4	<0.1	0.5	<0.1	19	<0.01
1093719	Rock	1.11	<2	0.3	3.5	0.7	11	<0.1	5.6	0.5	41	0.53	1.2	6.1	0.5	8	<0.1	0.2	<0.1	5	<0.01
1093681	Rock	0.80	<2	2.1	23.0	6.9	173	0.8	20.7	4.5	198	1.64	6.9	5.6	0.3	159	1.6	1.5	<0.1	31	0.95
1093682	Rock	0.72	<2	9.8	26.2	1.6	28	0.5	7.1	0.3	51	0.61	2.3	4.3	1.7	422	5.7	6.4	<0.1	244	3.77
1093683	Rock	0.45	5	112.6	1268	6.9	3645	7.3	588.4	35.8	410	4.34	929.7	5.7	2.7	7777	91.4	117.7	<0.1	2598	1.23
1093684	Rock	0.88	<2	0.4	1.5	43.7	56	<0.1	2.5	0.9	166	0.57	2.2	2.7	6.3	171	0.3	0.1	0.1	7	1.03
1093685	Rock	0.90	<2	0.1	18.0	5.2	21	0.1	11.3	5.2	652	3.56	1.8	3.3	1.4	430	<0.1	0.3	<0.1	13	9.10
1093686	Rock	0.82	40	0.5	0.3	38.0	38	<0.1	1.0	0.3	96	0.56	46.1	34.6	7.2	181	<0.1	0.5	<0.1	<2	1.19
1093687	Rock	0.72	53	0.4	1.1	36.1	29	<0.1	1.5	0.3	60	0.59	131.7	44.8	4.8	38	0.1	0.6	0.1	<2	0.07
1093688	Rock	0.90	<2	<0.1	23.0	1.1	27	<0.1	17.0	4.7	446	2.54	6.8	5.9	4.9	146	<0.1	0.3	0.2	8	1.42
1093689	Rock	0.96	<2	0.2	0.5	0.4	7	<0.1	1.1	0.1	154	0.27	<0.5	4.7	<0.1	1133	0.2	<0.1	<0.1	3	13.78
1093690	Rock	1.00	<2	0.6	25.4	2.3	73	<0.1	126.7	28.8	897	4.93	0.7	6.0	7.5	283	1.7	<0.1	0.1	64	9.00
1093691	Rock	0.68	<2	<0.1	2.5	0.7	39	<0.1	7.5	0.4	145	0.58	1.9	3.1	0.2	116	0.8	0.3	<0.1	5	34.34
1093692	Rock	0.70	6	1.0	34.8	5.7	71	0.1	14.8	2.5	30	1.65	1.5	4.5	1.4	22	<0.1	0.2	0.1	30	0.20
1093693	Rock	0.84	2	<0.1	0.6	0.3	16	<0.1	2.3	<0.1	64	0.12	0.6	1.3	0.2	391	0.5	0.2	<0.1	4	34.59
1093694	Rock	0.94	4	0.3	36.0	1.7	74	0.1	20.3	3.9	58	1.22	1.3	4.9	0.4	9	0.2	0.2	<0.1	13	0.14
1093695	Rock	0.72	2	1.5	70.5	9.2	36	0.5	3.5	0.6	59	3.02	53.3	4.4	0.3	13	0.5	13.9	<0.1	186	0.13
1093696	Rock	0.85	<2	0.5	1.9	2.3	1	1.0	1.2	0.2	38	0.35	<0.5	2.4	0.1	11	<0.1	0.6	<0.1	10	<0.01
1093697	Rock	0.77	4	3.1	30.5	3.9	8	0.5	15.5	2.4	26	0.85	2.7	2.2	1.0	84	<0.1	0.6	0.1	29	<0.01
1093698	Rock	0.78	7	0.5	2.2	2.9	1	0.6	1.3	0.1	36	0.37	1.6	2.7	0.2	12	<0.1	0.8	<0.1	13	<0.01
1093699	Rock	1.13	5	5.2	32.6	3.3	22	0.2	33.9	2.2	21	0.71	16.6	3.6	1.6	129	0.1	1.8	<0.1	91	<0.01
1093700	Rock	0.90	17	2.4	58.5	6.9	146	0.6	63.8	4.3	60	2.56	30.3	<0.5	4.3	48	0.4	2.7	0.1	227	<0.01
1277501	Rock	11.63	10	0.4	5.1	9.0	11	0.2	1.5	0.4	24	0.46	3.1	2.2	0.8	23	0.1	0.2	0.1	11	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

CERTIFICATE OF ANALYSIS WHI11001019.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1093711	Rock	0.004	1	3	0.67	149	<0.001	<20	0.02	0.002	<0.01	<0.1	<0.01	<0.1	<0.05	0.1	<0.5	<1	<0.2
1093712	Rock	0.016	6	13	3.42	33	0.002	<20	0.95	0.004	0.20	<0.1	0.05	<0.1	2.43	3.2	<0.5	3	<0.2
1093713	Rock	0.065	3	24	0.39	236	<0.001	<20	1.40	0.003	0.13	<0.1	0.02	<0.1	<0.05	3.8	<0.5	3	<0.2
1093714	Rock	0.059	2	23	0.41	924	<0.001	<20	1.34	0.004	0.08	<0.1	0.01	<0.1	<0.05	3.2	<0.5	3	<0.2
1093715	Rock	0.019	1	21	0.37	125	<0.001	<20	1.49	0.003	0.06	<0.1	0.08	<0.1	<0.05	2.4	<0.5	5	<0.2
1093716	Rock	0.010	1	12	0.11	333	<0.001	<20	0.55	0.001	0.02	<0.1	0.08	<0.1	<0.05	1.3	<0.5	2	<0.2
1093717	Rock	0.015	<1	17	0.57	47	<0.001	<20	2.00	<0.001	0.02	<0.1	0.02	<0.1	<0.05	2.3	<0.5	5	<0.2
1093718	Rock	0.012	<1	12	0.17	192	<0.001	<20	0.70	<0.001	0.02	<0.1	0.08	<0.1	0.39	1.1	<0.5	2	<0.2
1093719	Rock	0.016	<1	6	0.02	77	<0.001	<20	0.15	<0.001	<0.01	<0.1	0.01	<0.1	<0.05	0.6	<0.5	<1	<0.2
1093681	Rock	0.046	<1	10	0.29	1200	<0.001	<20	0.14	0.002	0.05	<0.1	0.19	<0.1	0.14	2.0	4.0	<1	<0.2
1093682	Rock	1.829	6	28	0.03	1174	0.012	27	0.43	0.005	0.13	0.1	0.32	<0.1	0.08	1.3	11.0	2	<0.2
1093683	Rock	>5	16	251	0.03	736	0.031	<20	>10	<0.001	0.11	0.2	0.61	0.6	0.19	26.4	93.6	7	0.8
1093684	Rock	0.011	8	2	0.06	472	<0.001	<20	0.40	0.022	0.27	<0.1	0.02	0.1	0.05	0.4	<0.5	<1	<0.2
1093685	Rock	0.012	4	11	5.43	119	0.002	<20	0.24	0.012	0.14	<0.1	0.02	<0.1	1.27	3.2	<0.5	<1	<0.2
1093686	Rock	0.004	7	2	0.06	337	<0.001	<20	0.37	0.023	0.27	<0.1	0.05	<0.1	0.10	0.5	<0.5	<1	<0.2
1093687	Rock	0.005	5	1	0.06	1808	<0.001	<20	0.36	0.008	0.23	<0.1	0.13	<0.1	0.11	0.3	0.8	<1	<0.2
1093688	Rock	0.022	9	6	0.91	2361	0.001	<20	0.54	0.003	0.28	<0.1	0.02	<0.1	0.15	3.3	<0.5	1	<0.2
1093689	Rock	0.002	14	3	0.12	58	<0.001	<20	0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	0.9	<0.5	<1	<0.2
1093690	Rock	0.164	49	93	3.48	1584	0.004	<20	0.75	0.009	0.18	<0.1	<0.01	0.2	0.05	10.3	0.6	2	<0.2
1093691	Rock	0.040	5	7	0.12	49	0.002	<20	0.04	<0.001	<0.01	<0.1	0.02	<0.1	<0.05	0.7	<0.5	<1	<0.2
1093692	Rock	0.029	<1	20	0.28	358	<0.001	<20	0.90	0.004	0.14	<0.1	0.03	<0.1	0.15	2.0	0.5	2	<0.2
1093693	Rock	0.057	4	6	0.12	160	0.001	<20	0.03	0.005	<0.01	<0.1	<0.01	<0.1	0.06	0.2	<0.5	<1	<0.2
1093694	Rock	0.016	<1	10	0.17	95	<0.001	<20	0.44	0.002	0.03	<0.1	0.07	<0.1	0.08	0.9	1.4	2	<0.2
1093695	Rock	0.046	<1	31	0.02	1409	0.002	<20	0.19	0.005	0.04	<0.1	0.28	<0.1	0.06	0.6	35.8	3	<0.2
1093696	Rock	0.007	<1	7	0.01	254	<0.001	<20	0.07	0.001	0.03	<0.1	0.03	<0.1	<0.05	0.2	0.9	<1	<0.2
1093697	Rock	0.033	2	9	0.04	482	<0.001	<20	0.31	0.005	0.10	<0.1	0.01	<0.1	0.43	1.0	2.4	1	<0.2
1093698	Rock	0.008	<1	7	0.01	228	<0.001	<20	0.09	0.002	0.04	<0.1	0.08	<0.1	<0.05	0.3	0.7	<1	<0.2
1093699	Rock	0.042	3	15	0.01	>10000	<0.001	<20	1.65	<0.001	0.04	<0.1	0.28	0.2	<0.05	2.2	2.0	2	<0.2
1093700	Rock	0.076	14	35	0.01	>10000	0.019	<20	4.58	<0.001	0.13	<0.1	0.40	0.5	<0.05	4.1	5.7	9	<0.2
1277501	Rock	0.010	<1	6	0.03	1672	<0.001	<20	0.33	0.004	0.15	<0.1	0.11	<0.1	0.12	1.1	<0.5	1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

CERTIFICATE OF ANALYSIS WHI11001019.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1277502	Rock	10.88	11	0.8	8.0	9.2	27	0.2	3.5	0.8	38	0.97	4.4	2.4	1.0	23	0.1	0.2	0.1	14	<0.01
1277503	Rock	11.77	20	0.6	8.1	5.5	11	0.3	2.7	0.6	49	0.69	4.5	3.7	0.7	33	0.3	0.5	<0.1	11	<0.01
1277504	Rock	9.05	78	1.9	12.4	7.5	14	0.8	3.2	0.6	56	0.92	14.4	16.6	0.8	26	<0.1	1.5	0.1	21	<0.01
1277505	Rock	11.06	20	2.0	13.7	9.0	31	0.5	4.7	0.8	47	1.00	10.4	4.3	1.0	48	0.2	0.8	0.1	16	<0.01
1277506	Rock	10.09	24	2.3	15.0	10.7	20	0.6	3.3	0.6	45	0.99	10.7	6.9	1.1	43	0.3	0.8	0.1	17	0.02
1277507	Rock	9.70	15	1.3	13.4	8.4	117	0.3	12.1	2.1	73	1.29	12.0	4.5	1.0	34	0.2	0.5	0.1	19	0.01
1277508	Rock	8.91	11	2.6	17.7	6.6	20	0.5	4.4	0.5	38	0.81	11.2	2.8	1.0	34	0.2	0.5	<0.1	19	0.04
1277509	Rock	10.10	9	10.0	21.8	11.0	6	0.8	2.5	0.3	22	1.13	25.8	2.1	1.7	28	<0.1	0.7	0.2	26	0.05
1277510	Rock	5.74	10	2.4	23.2	7.6	70	0.5	10.4	1.9	61	1.32	13.1	2.7	0.9	28	0.2	0.9	0.1	33	0.04
1277511	Rock	7.86	14	9.3	37.1	9.0	6	3.1	12.3	0.3	29	0.72	8.6	2.0	0.8	27	0.2	2.3	0.1	88	0.03
1277512	Rock	5.98	9	19.5	43.4	7.3	34	2.7	13.9	0.5	32	1.29	22.5	2.2	1.4	44	0.4	3.7	<0.1	175	0.47
1277513	Rock	8.16	5	4.9	43.7	5.4	11	2.7	9.0	0.3	32	1.02	16.6	0.8	1.2	41	0.7	2.2	<0.1	112	0.44
1277514	Rock	7.31	11	9.0	65.9	8.8	24	3.6	7.2	0.3	25	1.43	23.9	2.2	1.6	42	0.6	4.3	<0.1	112	0.20
1277515	Rock	7.71	34	19.1	66.0	8.7	29	2.9	7.7	0.5	31	1.61	67.3	4.6	1.1	98	0.8	7.9	0.1	191	0.37
1277516	Rock	8.60	61	23.3	110.8	12.0	26	4.3	8.9	0.4	27	1.51	85.0	6.1	1.0	88	1.4	13.6	0.1	253	0.41
1277517	Rock	7.65	50	19.8	100.3	12.1	8	3.9	4.4	0.1	21	0.81	39.6	5.3	1.3	42	0.8	8.3	<0.1	256	0.83
1277518	Rock	8.42	7	28.4	62.2	10.9	166	4.9	11.6	0.6	39	1.22	58.2	<0.5	0.7	30	0.3	15.1	<0.1	311	0.01
1277519	Rock	7.92	5	14.6	43.1	10.6	74	1.9	8.2	0.6	38	0.79	22.0	<0.5	0.6	13	0.1	9.3	<0.1	201	<0.01
1277520	Rock	8.49	9	13.6	35.2	20.6	47	1.7	9.9	1.0	44	1.17	52.1	<0.5	1.5	72	0.4	8.0	0.2	155	0.02
1277521	Rock	7.89	14	20.1	34.1	12.1	18	2.8	6.6	0.3	20	0.95	38.3	0.5	0.9	78	0.6	7.9	0.1	169	<0.01
1277522	Rock	7.99	11	12.9	22.4	13.8	93	3.1	12.5	1.4	22	1.23	31.2	0.6	1.1	84	0.2	5.6	0.1	102	<0.01
1277523	Rock	7.77	5	11.9	24.3	13.4	520	1.6	44.0	7.4	67	2.42	69.4	0.7	2.4	51	0.1	4.6	0.2	89	<0.01
1277524	Rock	7.60	2	8.9	6.6	9.4	7	0.2	2.7	0.1	8	0.45	17.2	<0.5	1.1	5	<0.1	1.4	0.1	51	<0.01
1277525	Rock	7.98	<2	5.6	7.0	7.0	4	0.1	2.8	0.1	7	0.28	3.9	<0.5	1.1	5	<0.1	0.9	0.1	33	<0.01
1277526	Rock	6.81	3	5.8	7.6	6.9	10	0.1	2.8	0.2	8	0.35	6.8	<0.5	0.8	8	<0.1	0.8	0.1	36	<0.01
1277527	Rock	8.15	3	19.6	9.1	8.8	19	0.1	4.0	0.4	10	0.71	25.1	<0.5	1.3	8	<0.1	2.6	0.2	48	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

CERTIFICATE OF ANALYSIS WHI11001019.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1277502	Rock	0.013	1	10	0.03	1176	<0.001	<20	0.36	0.004	0.19	<0.1	0.09	<0.1	0.20	0.7	0.5	2	<0.2
1277503	Rock	0.011	<1	9	0.02	934	<0.001	<20	0.22	0.003	0.11	<0.1	0.29	<0.1	0.12	0.5	1.4	<1	<0.2
1277504	Rock	0.077	2	13	0.02	799	0.001	<20	0.34	0.004	0.14	<0.1	0.89	<0.1	0.11	1.6	2.9	1	<0.2
1277505	Rock	0.046	2	11	0.02	1671	0.001	<20	0.27	0.004	0.14	<0.1	0.25	<0.1	0.16	1.1	2.0	1	<0.2
1277506	Rock	0.073	2	11	0.03	1354	0.001	<20	0.28	0.003	0.14	<0.1	0.32	0.1	0.16	1.8	2.3	1	<0.2
1277507	Rock	0.047	2	10	0.03	1258	0.001	<20	0.32	0.004	0.15	<0.1	0.14	<0.1	0.16	1.1	1.8	1	<0.2
1277508	Rock	0.135	2	12	0.02	1201	0.001	<20	0.27	0.002	0.11	<0.1	0.19	<0.1	0.09	2.0	2.9	1	<0.2
1277509	Rock	0.409	2	16	0.02	1341	0.002	<20	0.36	0.004	0.16	<0.1	0.24	0.2	0.11	5.0	4.2	2	<0.2
1277510	Rock	0.078	3	10	0.04	754	0.001	<20	0.38	0.003	0.12	<0.1	0.25	<0.1	0.07	1.2	1.7	1	0.2
1277511	Rock	0.147	3	19	0.02	356	0.001	<20	0.26	0.003	0.11	<0.1	0.19	0.1	0.09	1.1	9.1	1	<0.2
1277512	Rock	0.717	4	38	0.03	453	0.004	<20	0.56	0.004	0.17	0.2	0.16	<0.1	0.07	2.5	12.7	2	0.2
1277513	Rock	0.613	3	38	0.02	337	0.004	<20	0.48	0.003	0.14	<0.1	0.10	<0.1	0.06	2.1	5.9	1	<0.2
1277514	Rock	0.574	4	31	0.02	340	0.003	<20	0.45	0.004	0.16	0.2	0.14	0.2	0.16	2.6	10.8	1	<0.2
1277515	Rock	0.583	4	33	0.02	319	0.002	<20	0.57	0.004	0.14	0.3	0.30	0.4	0.10	3.1	10.8	2	<0.2
1277516	Rock	0.447	4	39	0.02	305	0.002	<20	0.65	0.004	0.16	0.3	0.63	0.6	0.14	3.1	9.6	3	<0.2
1277517	Rock	0.520	4	37	0.02	282	0.002	<20	0.57	0.003	0.18	0.3	0.44	0.5	0.08	3.3	9.6	2	<0.2
1277518	Rock	0.133	2	21	<0.01	213	<0.001	<20	0.35	0.002	0.11	0.1	0.48	0.3	0.08	2.2	27.1	2	<0.2
1277519	Rock	0.031	1	14	0.01	132	<0.001	<20	0.31	0.001	0.08	0.1	0.35	0.2	<0.05	1.4	9.8	1	<0.2
1277520	Rock	0.095	7	17	0.02	165	0.001	<20	0.44	0.003	0.12	0.1	0.85	0.4	0.10	1.7	11.1	2	<0.2
1277521	Rock	0.094	3	15	<0.01	159	<0.001	<20	0.37	0.003	0.15	0.1	0.28	0.7	0.16	1.9	18.8	2	<0.2
1277522	Rock	0.105	4	12	0.01	275	<0.001	<20	0.42	0.005	0.16	<0.1	0.24	0.5	0.18	2.0	19.0	2	<0.2
1277523	Rock	0.159	3	15	0.01	300	<0.001	<20	0.48	0.006	0.19	<0.1	0.20	0.4	0.20	3.1	13.3	2	<0.2
1277524	Rock	0.007	1	5	<0.01	147	<0.001	<20	0.33	0.005	0.12	<0.1	0.10	0.2	<0.05	0.7	4.2	2	<0.2
1277525	Rock	0.004	1	4	<0.01	169	<0.001	<20	0.33	0.005	0.13	<0.1	0.13	0.2	0.06	0.8	1.9	1	<0.2
1277526	Rock	0.005	1	4	0.01	134	<0.001	<20	0.31	0.005	0.11	<0.1	0.17	0.3	<0.05	0.7	1.5	1	<0.2
1277527	Rock	0.013	2	5	0.02	134	<0.001	30	0.35	0.007	0.12	<0.1	0.35	0.3	<0.05	1.0	5.5	2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

QUALITY CONTROL REPORT WHI11001019.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1095494	Rock	1.16	<2	0.2	52.6	1.0	38	<0.1	238.9	36.9	1686	8.85	17.0	4.3	1.0	481	0.1	<0.1	<0.1	142	9.53
REP 1095494	QC			0.2	50.9	1.0	34	<0.1	235.8	36.1	1627	8.53	17.2	3.4	1.0	484	0.1	<0.1	<0.1	139	9.32
1095497	Rock	1.29	<2	0.7	35.8	2.1	12	<0.1	137.2	29.4	1098	5.33	1.2	3.5	1.4	310	<0.1	0.2	<0.1	112	8.76
REP 1095497	QC		<2																		
1277591	Rock	1.53	3	1.9	60.7	8.1	96	0.3	65.8	6.0	170	3.81	10.1	3.6	1.9	54	0.6	0.5	0.3	106	0.07
REP 1277591	QC		3																		
1277573	Rock	1.15	6	165.0	56.1	64.6	21	1.8	5.8	0.2	19	3.06	59.7	2.3	1.6	513	0.9	91.5	<0.1	1424	7.31
REP 1277573	QC			162.9	55.7	62.1	20	1.7	6.9	0.1	19	3.03	59.6	4.0	1.7	505	1.1	88.8	<0.1	1397	7.20
1093681	Rock	0.80	<2	2.1	23.0	6.9	173	0.8	20.7	4.5	198	1.64	6.9	5.6	0.3	159	1.6	1.5	<0.1	31	0.95
REP 1093681	QC		<2																		
1093690	Rock	1.00	<2	0.6	25.4	2.3	73	<0.1	126.7	28.8	897	4.93	0.7	6.0	7.5	283	1.7	<0.1	0.1	64	9.00
REP 1093690	QC			0.6	26.5	2.5	75	<0.1	125.2	28.2	879	4.90	0.9	4.4	7.4	284	1.4	<0.1	<0.1	64	9.04
1277503	Rock	11.77	20	0.6	8.1	5.5	11	0.3	2.7	0.6	49	0.69	4.5	3.7	0.7	33	0.3	0.5	<0.1	11	<0.01
REP 1277503	QC		20																		
Core Reject Duplicates																					
1095499	Rock	1.37	<2	1.7	58.9	4.7	273	<0.1	213.7	43.2	1375	4.45	2.9	2.6	1.6	778	1.6	0.4	<0.1	98	16.10
DUP 1095499	QC		<2	1.7	57.0	4.7	275	<0.1	206.1	42.8	1351	4.42	3.1	4.0	1.5	780	1.6	0.4	<0.1	97	15.71
1093702	Rock	1.04	<2	0.5	20.7	10.3	145	<0.1	43.1	3.8	69	3.20	4.7	0.6	0.8	5	<0.1	0.2	0.1	27	0.01
DUP 1093702	QC		<2	0.6	22.3	10.6	157	<0.1	48.4	4.2	73	3.43	5.4	0.9	0.8	6	<0.1	0.3	<0.1	29	0.01
1093698	Rock	0.78	7	0.5	2.2	2.9	1	0.6	1.3	0.1	36	0.37	1.6	2.7	0.2	12	<0.1	0.8	<0.1	13	<0.01
DUP 1093698	QC		4	0.3	2.1	2.9	2	0.6	1.6	0.2	42	0.44	1.1	1.8	0.2	14	<0.1	0.8	<0.1	14	<0.01
Reference Materials																					
STD DS8	Standard			12.6	103.4	122.5	296	1.7	36.3	7.0	586	2.33	24.2	94.7	6.8	73	2.3	3.9	5.7	40	0.68
STD DS8	Standard			12.0	104.0	121.8	290	1.6	36.1	7.2	577	2.34	22.0	97.2	7.2	63	2.2	4.5	6.2	38	0.68
STD DS8	Standard			12.4	105.6	120.5	302	1.7	36.7	7.1	588	2.39	24.1	93.2	7.1	59	2.1	4.9	6.2	42	0.71
STD DS8	Standard			13.2	105.8	121.5	309	1.6	37.3	7.5	591	2.43	25.4	99.8	6.5	66	2.3	3.9	6.5	40	0.70
STD OREAS45CA	Standard			0.7	504.2	21.9	64	0.3	248.8	86.7	923	15.38	3.8	38.5	7.4	16	<0.1	<0.1	0.2	208	0.40
STD OREAS45CA	Standard			0.9	503.0	23.0	63	0.3	260.6	92.8	936	15.68	3.2	38.5	8.1	17	0.1	0.1	0.2	219	0.42

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

QUALITY CONTROL REPORT WHI11001019.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1095494	Rock	0.125	2	256	4.01	165	<0.001	<20	1.57	0.007	0.01	<0.1	<0.01	<0.1	<0.05	18.2	0.9	5	<0.2
REP 1095494	QC	0.126	2	246	3.89	163	<0.001	<20	1.52	0.007	0.01	<0.1	0.01	<0.1	<0.05	18.2	1.1	5	<0.2
1095497	Rock	0.191	2	149	3.16	137	0.001	<20	0.16	0.010	0.02	<0.1	0.03	<0.1	<0.05	10.2	1.1	1	<0.2
REP 1095497	QC																		
1277591	Rock	0.100	4	34	0.28	142	<0.001	<20	1.73	<0.001	0.12	<0.1	0.06	0.1	0.07	4.5	1.7	3	<0.2
REP 1277591	QC																		
1277573	Rock	3.152	15	46	0.07	2007	0.025	25	0.97	<0.001	0.24	0.4	2.12	0.9	0.07	2.9	46.9	4	0.6
REP 1277573	QC	3.088	15	45	0.07	1852	0.025	<20	0.99	<0.001	0.24	0.4	2.12	0.8	0.07	2.8	45.0	3	0.4
1093681	Rock	0.046	<1	10	0.29	1200	<0.001	<20	0.14	0.002	0.05	<0.1	0.19	<0.1	0.14	2.0	4.0	<1	<0.2
REP 1093681	QC																		
1093690	Rock	0.164	49	93	3.48	1584	0.004	<20	0.75	0.009	0.18	<0.1	<0.01	0.2	0.05	10.3	0.6	2	<0.2
REP 1093690	QC	0.164	49	92	3.45	1610	0.004	<20	0.75	0.009	0.17	<0.1	<0.01	<0.1	0.05	10.0	<0.5	2	<0.2
1277503	Rock	0.011	<1	9	0.02	934	<0.001	<20	0.22	0.003	0.11	<0.1	0.29	<0.1	0.12	0.5	1.4	<1	<0.2
REP 1277503	QC																		
Core Reject Duplicates																			
1095499	Rock	0.231	4	160	2.01	973	0.001	<20	0.37	0.017	0.05	<0.1	0.03	0.1	<0.05	15.6	1.4	2	<0.2
DUP 1095499	QC	0.224	4	158	2.02	928	0.001	<20	0.36	0.015	0.05	<0.1	0.03	0.1	<0.05	15.0	1.1	2	<0.2
1093702	Rock	0.022	1	15	0.47	216	<0.001	<20	1.23	<0.001	0.04	<0.1	0.02	<0.1	<0.05	4.0	<0.5	4	<0.2
DUP 1093702	QC	0.023	1	16	0.51	275	<0.001	<20	1.34	<0.001	0.04	<0.1	0.04	<0.1	<0.05	4.2	0.6	4	<0.2
1093698	Rock	0.008	<1	7	0.01	228	<0.001	<20	0.09	0.002	0.04	<0.1	0.08	<0.1	<0.05	0.3	0.7	<1	<0.2
DUP 1093698	QC	0.009	<1	8	0.01	260	<0.001	<20	0.10	0.002	0.04	<0.1	0.09	<0.1	<0.05	0.4	<0.5	<1	<0.2
Reference Materials																			
STD DS8	Standard	0.077	16	110	0.59	282	0.115	<20	0.89	0.085	0.39	2.2	0.27	5.1	0.16	2.0	6.2	4	4.8
STD DS8	Standard	0.069	14	113	0.58	268	0.108	<20	0.87	0.084	0.39	2.3	0.20	5.0	0.15	1.7	4.3	4	4.4
STD DS8	Standard	0.074	14	115	0.58	288	0.107	<20	0.89	0.092	0.40	2.3	0.27	5.0	0.16	1.8	5.2	4	4.7
STD DS8	Standard	0.076	15	116	0.60	279	0.117	<20	0.90	0.091	0.40	2.2	0.19	5.3	0.16	2.1	5.3	4	4.8
STD OREAS45CA	Standard	0.041	17	660	0.14	163	0.139	<20	3.77	0.007	0.07	<0.1	0.06	<0.1	<0.05	37.2	<0.5	18	<0.2
STD OREAS45CA	Standard	0.036	17	739	0.16	163	0.136	<20	3.90	0.007	0.07	<0.1	0.03	<0.1	<0.05	36.9	<0.5	19	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

QUALITY CONTROL REPORT WHI11001019.1

		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
STD OREAS45CA	Standard			0.8	506.5	21.3	59	0.3	248.7	91.5	914	15.63	3.5	39.8	7.9	19	0.1	<0.1	0.2	201	0.39
STD OREAS45CA	Standard			0.7	535.0	23.3	66	0.3	263.0	94.5	947	16.24	3.9	48.6	7.0	14	0.1	<0.1	0.2	209	0.45
STD OXC88	Standard		194																		
STD OXC88	Standard		197																		
STD OXC88	Standard		202																		
STD OXC88	Standard		198																		
STD OXH82	Standard		1271																		
STD OXH82	Standard		1327																		
STD OXH82	Standard		1271																		
STD OXH82	Standard		1279																		
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		<2	0.1	2.1	2.9	46	<0.1	2.8	3.9	568	2.04	0.6	6.6	5.6	63	<0.1	<0.1	<0.1	37	0.49
G1	Prep Blank		<2	0.1	2.0	2.8	46	<0.1	2.7	3.9	552	1.98	<0.5	6.3	5.5	61	<0.1	<0.1	<0.1	37	0.49

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 20, 2011

QUALITY CONTROL REPORT WHI11001019.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
STD OREAS45CA	Standard	0.036	17	732	0.16	166	0.128	<20	3.69	0.009	0.08	<0.1	0.03	<0.1	<0.05	35.7	<0.5	18	<0.2
STD OREAS45CA	Standard	0.041	16	706	0.17	166	0.134	<20	4.01	0.010	0.08	<0.1	0.04	<0.1	<0.05	40.5	1.0	19	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXC88 Expected																			
STD OXH82 Expected																			
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																			
G1	Prep Blank	0.077	13	9	0.50	159	0.128	<20	0.90	0.083	0.46	<0.1	<0.01	0.3	<0.05	2.1	<0.5	5	<0.2
G1	Prep Blank	0.077	13	9	0.50	154	0.124	<20	0.89	0.080	0.46	<0.1	<0.01	0.3	<0.05	1.9	0.5	4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 08, 2011
Report Date: January 24, 2012
Page: 1 of 6

CERTIFICATE OF ANALYSIS WHI11001055.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #11
P.O. Number
Number of Samples: 126

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-500	126	Crush, split and pulverize 500 g rock to 200 mesh			VAN
3B	126	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	126	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: Revised Sample ID's - Samples 1227151 to 1227165 revised to 1277151 to 1277165

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

CERTIFICATE OF ANALYSIS WHI11001055.2

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1093901	Rock	0.73	11	695.1	335.1	12.9	3188	1.0	200.1	12.7	75	16.98	3478	<0.5	1.6	179	2.5	102.7	0.2	3855	0.05
1093902	Rock	1.42	155	147.8	404.4	11.9	4184	1.9	617.1	52.3	620	12.78	526.1	1.0	1.5	20	5.6	73.3	0.3	1588	0.03
1093903	Rock	0.85	4	37.9	20.7	16.9	9	0.7	11.7	0.4	44	0.68	21.1	2.4	0.9	15	0.5	11.3	1.3	372	0.03
1093904	Rock	1.08	51	1.2	20.7	28.5	47	1.4	4.7	1.5	30	0.71	154.6	37.6	7.7	20	0.2	6.6	15.0	6	<0.01
1093905	Rock	0.76	19	27.1	10.3	14.9	3	0.6	8.0	0.2	58	0.68	40.6	2.4	0.9	39	<0.1	8.7	0.4	335	<0.01
1093906	Rock	1.49	6	0.4	7.0	1.2	9	0.4	4.3	0.9	341	0.31	3.0	3.1	0.4	679	0.1	0.2	0.2	13	28.61
1093907	Rock	1.74	7	46.4	11.2	2.7	4	0.5	3.8	0.1	56	0.73	33.2	0.6	0.3	18	0.1	10.8	<0.1	352	0.38
1093908	Rock	1.27	3	4.2	1.2	36.3	5	0.2	0.9	<0.1	10	0.71	27.9	1.7	10.3	31	0.1	1.0	0.2	17	0.02
1093909	Rock	1.73	3	24.9	22.1	3.0	5	0.5	4.7	0.2	43	0.50	14.5	1.7	0.3	17	<0.1	6.8	0.1	345	0.03
1093910	Rock	2.18	75	71.7	36.3	18.8	186	0.7	28.4	3.3	101	3.00	112.7	2.2	2.3	174	0.9	16.3	0.2	342	0.04
1093911	Rock	1.68	5	50.5	10.7	21.2	6	0.8	11.6	0.2	49	1.35	37.7	1.4	2.1	304	0.3	15.7	<0.1	474	0.03
1093912	Rock	1.62	5	36.5	8.5	17.6	4	0.6	8.6	0.2	51	0.82	17.5	<0.5	1.3	46	0.2	8.2	<0.1	294	0.01
1093913	Rock	2.21	9	44.8	11.9	19.3	4	0.7	7.2	0.2	61	1.39	50.8	3.1	1.7	47	<0.1	11.2	0.1	267	<0.01
1093914	Rock	1.16	<2	2.9	5.9	2.2	84	<0.1	14.0	1.0	39	1.25	14.1	2.8	0.5	3	0.1	1.1	<0.1	12	<0.01
1093915	Rock	1.06	<2	0.7	19.3	9.8	136	<0.1	40.6	8.6	96	3.87	16.1	0.5	2.3	20	0.2	0.2	0.1	33	0.05
1093851	Rock	1.44	<2	0.5	1.1	3.1	27	<0.1	2.2	0.3	808	0.40	<0.5	<0.5	1.0	1586	0.7	0.2	0.1	21	24.69
1093852	Rock	1.42	<2	0.6	6.1	8.2	2	0.2	1.3	0.3	22	0.55	7.7	2.0	0.2	14	0.1	0.7	<0.1	13	0.02
1093854	Rock	1.47	2	4.2	1.6	10.8	2	0.5	1.0	0.2	39	1.68	37.6	<0.5	1.1	364	<0.1	2.0	<0.1	71	0.06
1093855	Rock	2.12	129	6.2	44.1	5.3	5	0.7	1.4	0.3	41	4.74	825.5	52.6	0.7	26	0.4	5.1	0.2	193	0.02
1093856	Rock	1.82	11	7.7	8.0	25.0	4	0.4	1.9	0.3	46	0.92	45.5	<0.5	0.3	14	0.3	2.9	0.2	24	0.02
1095361	Rock	0.98	7	2.9	1.5	32.8	2	0.3	0.9	0.2	11	0.61	15.9	7.4	9.0	21	0.2	0.8	0.6	9	0.02
1095362	Rock	1.26	26	58.2	58.4	4.2	845	0.8	35.3	4.2	62	4.15	732.3	2.6	1.2	99	0.9	30.2	0.1	853	0.04
1095363	Rock	1.42	<2	73.8	150.9	4.4	2519	1.0	217.3	17.0	155	6.31	186.1	<0.5	1.4	28	3.5	28.7	<0.1	1304	0.03
1095364	Rock	1.05	<2	1.5	4.1	33.3	14	0.3	4.1	0.2	10	0.82	49.3	1.3	8.2	60	0.1	1.9	0.6	47	0.03
1095365	Rock	1.19	26	10.2	40.7	12.4	48	1.5	23.6	0.4	25	2.34	386.7	<0.5	3.7	678	1.5	40.3	0.1	623	0.89
1095366	Rock	1.25	<2	1.8	74.6	10.7	163	0.1	33.4	10.6	200	4.10	49.3	0.9	6.0	24	1.0	0.4	0.3	37	0.03
1095367	Rock	0.97	9	0.9	31.3	26.0	37	0.9	2.2	1.2	36	2.17	433.6	7.1	10.7	14	0.2	2.6	10.4	2	0.02
1095368	Rock	1.00	4	1.3	33.0	3.4	103	0.2	23.0	3.1	462	6.84	96.7	<0.5	5.3	11	0.2	1.2	2.8	78	0.06
1095369	Rock	0.85	17	0.6	29.5	27.2	109	0.4	14.6	5.3	89	2.43	264.3	12.7	11.5	10	0.2	1.8	2.5	9	<0.01
1095370	Rock	1.01	12	1.5	19.7	5.4	21	0.2	3.2	0.6	39	1.81	157.0	<0.5	1.1	14	0.2	2.5	0.1	20	0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

CERTIFICATE OF ANALYSIS WHI11001055.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1093901	Rock	0.357	9	91	0.06	180	0.004	<20	2.81	<0.001	0.12	1.9	6.26	<0.1	0.19	10.8	22.5	3	0.2
1093902	Rock	0.124	8	58	0.11	1237	0.006	<20	1.74	<0.001	0.15	0.5	24.72	1.0	0.15	4.6	29.1	3	0.3
1093903	Rock	0.013	6	14	0.02	1205	0.003	<20	0.23	<0.001	0.11	<0.1	0.76	0.3	0.15	1.1	10.9	2	<0.2
1093904	Rock	0.013	31	<1	0.02	108	0.003	<20	0.46	0.004	0.27	1.3	35.29	0.4	<0.05	0.4	4.6	1	<0.2
1093905	Rock	0.007	<1	13	<0.01	253	0.002	<20	0.17	<0.001	0.06	<0.1	3.29	0.3	0.09	0.3	7.4	<1	<0.2
1093906	Rock	0.049	1	3	0.19	2489	<0.001	<20	0.08	0.005	0.02	0.1	0.33	<0.1	<0.05	0.6	<0.5	<1	<0.2
1093907	Rock	0.020	2	20	0.02	1909	0.002	<20	0.12	<0.001	0.05	0.1	1.76	0.4	0.08	0.7	9.6	1	<0.2
1093908	Rock	0.026	32	2	<0.01	465	<0.001	<20	0.45	0.002	0.18	<0.1	2.09	0.4	0.16	0.5	3.8	1	<0.2
1093909	Rock	0.014	2	21	0.02	143	0.002	<20	0.13	0.005	0.05	<0.1	1.61	0.5	0.05	0.6	6.8	<1	<0.2
1093910	Rock	0.153	3	17	0.09	754	0.001	<20	0.55	<0.001	0.15	0.2	12.85	0.8	0.22	3.0	30.9	2	<0.2
1093911	Rock	0.099	4	19	0.02	348	0.002	<20	0.33	<0.001	0.19	0.3	1.25	0.8	0.26	1.0	14.6	1	<0.2
1093912	Rock	0.027	3	12	0.01	378	0.001	<20	0.22	<0.001	0.12	0.1	1.77	0.6	0.15	0.6	12.2	<1	0.3
1093913	Rock	0.037	7	3	0.02	390	0.002	<20	0.20	<0.001	0.13	0.1	2.27	0.4	0.18	1.2	17.3	<1	0.3
1093914	Rock	0.017	<1	5	<0.01	120	<0.001	<20	0.12	0.002	0.02	<0.1	0.04	<0.1	<0.05	0.4	1.4	<1	<0.2
1093915	Rock	0.037	2	28	0.43	372	<0.001	<20	1.49	0.011	0.16	<0.1	0.11	<0.1	<0.05	2.6	0.7	4	<0.2
1093851	Rock	0.072	6	7	2.35	962	<0.001	<20	0.08	0.005	0.03	<0.1	0.07	<0.1	<0.05	0.6	<0.5	<1	<0.2
1093852	Rock	0.014	<1	<1	<0.01	186	<0.001	<20	0.09	0.002	0.05	<0.1	0.16	<0.1	<0.05	0.3	1.0	<1	<0.2
1093854	Rock	0.104	3	11	<0.01	644	<0.001	<20	0.22	<0.001	0.31	<0.1	0.61	0.7	0.44	1.3	2.7	1	<0.2
1093855	Rock	0.126	<1	25	<0.01	937	<0.001	<20	0.17	<0.001	0.11	<0.1	3.66	0.3	0.24	2.3	23.0	2	<0.2
1093856	Rock	0.015	<1	6	0.01	1359	<0.001	<20	0.12	0.003	0.09	<0.1	2.12	0.3	0.15	0.5	6.3	<1	<0.2
1095361	Rock	0.024	33	3	0.01	547	<0.001	<20	0.46	0.001	0.16	0.1	2.34	0.4	0.19	0.4	8.1	3	<0.2
1095362	Rock	0.110	3	39	0.03	1179	0.002	<20	0.38	0.003	0.08	0.2	13.15	0.7	0.15	2.4	25.2	2	0.3
1095363	Rock	0.101	5	42	0.08	181	0.004	<20	1.02	<0.001	0.12	0.2	1.19	0.2	0.05	3.5	17.6	3	<0.2
1095364	Rock	0.110	26	3	0.01	204	<0.001	<20	0.51	<0.001	0.22	<0.1	2.89	0.2	0.17	0.5	3.2	1	<0.2
1095365	Rock	1.544	8	58	0.01	1168	0.005	<20	2.40	<0.001	0.12	0.3	2.28	0.1	0.19	9.4	20.3	3	0.2
1095366	Rock	0.082	25	12	0.09	388	<0.001	<20	0.78	0.005	0.15	<0.1	0.13	<0.1	0.07	4.5	1.2	2	<0.2
1095367	Rock	0.042	24	2	0.02	143	<0.001	<20	0.35	0.005	0.22	1.7	4.73	0.1	0.10	0.4	2.6	<1	<0.2
1095368	Rock	0.078	15	42	1.57	101	0.004	<20	2.71	<0.001	0.11	<0.1	0.14	<0.1	0.08	6.2	1.4	7	<0.2
1095369	Rock	0.046	27	4	0.17	156	<0.001	<20	0.65	0.001	0.22	0.2	8.57	0.2	0.06	1.0	2.3	1	<0.2
1095370	Rock	0.034	7	6	0.01	314	<0.001	<20	0.19	0.003	0.08	<0.1	0.54	0.2	<0.05	0.4	1.7	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

CERTIFICATE OF ANALYSIS WHI11001055.2

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1095371	Rock	1.28	<2	0.3	5.9	2.3	61	<0.1	11.2	2.2	194	1.98	11.2	1.1	0.6	40	0.6	0.7	<0.1	6	1.85
1095372	Rock	0.94	<2	<0.1	<0.1	1.1	36	<0.1	3.6	1.1	196	1.58	19.2	<0.5	0.3	34	0.2	0.3	<0.1	5	1.85
1095373	Rock	0.93	<2	0.1	1.3	1.0	26	<0.1	5.9	1.9	207	2.66	2.2	<0.5	0.4	33	0.3	0.2	<0.1	6	2.01
1095374	Rock	1.72	<2	0.3	1.6	1.3	25	0.1	5.0	0.8	140	1.72	1.3	2.5	0.3	728	0.5	0.2	<0.1	9	27.98
1095375	Rock	1.67	<2	0.1	8.0	0.7	27	<0.1	112.3	24.1	1382	6.65	<0.5	<0.5	0.3	950	0.1	0.1	<0.1	46	16.38
1095376	Rock	0.97	<2	0.5	19.9	1.9	15	<0.1	38.9	11.8	649	0.56	0.6	0.5	0.5	2976	0.2	0.2	<0.1	18	26.90
1095377	Rock	1.99	<2	0.4	0.9	36.7	141	<0.1	5.4	3.2	257	1.51	2.8	2.1	14.4	<1	0.9	0.1	1.3	<2	0.18
1095378	Rock	1.17	5	0.3	30.5	6.5	101	<0.1	31.3	6.5	310	2.27	2.8	2.8	2.9	32	0.2	0.2	0.2	27	0.08
1095379	Rock	1.16	5	0.6	84.3	9.2	65	<0.1	24.1	4.1	193	2.44	4.2	1.1	2.3	50	<0.1	0.2	0.2	32	0.11
1095380	Rock	1.27	3	4.9	18.5	9.4	14	0.1	1.5	0.2	29	3.28	64.7	1.3	1.1	60	<0.1	8.1	<0.1	133	0.02
1095381	Rock	1.04	4	2.1	146.6	10.6	608	0.2	72.7	11.4	241	8.67	21.2	0.7	1.8	25	0.8	0.6	0.2	135	0.02
1095382	Rock	0.97	249	8.9	9.7	18.5	2	1.2	2.2	0.1	34	0.69	14.0	5.9	0.6	12	<0.1	6.6	<0.1	35	<0.01
1095383	Rock	0.99	320	55.0	8.7	39.2	9	0.9	1.1	<0.1	16	1.87	288.1	85.2	16.4	61	0.3	10.7	0.4	150	<0.01
1095384	Rock	0.61	8	98.8	157.2	9.1	5058	0.8	596.8	46.1	902	6.53	138.1	14.3	3.3	63	104.8	36.7	<0.1	555	1.31
1095385	Rock	0.85	199	192.4	278.5	11.1	8273	1.2	801.1	57.9	833	14.66	743.5	38.5	2.0	100	60.0	136.9	0.1	909	0.45
1095386	Rock	1.13	10	83.9	29.7	6.3	15	0.8	12.5	0.2	39	1.07	57.5	<0.5	1.7	31	0.6	34.6	<0.1	302	0.01
1095387	Rock	1.41	99	97.8	133.8	5.3	1750	0.5	145.4	13.8	85	7.04	319.8	1.7	1.1	49	1.4	83.7	<0.1	991	0.01
1095388	Rock	0.92	421	15.5	18.5	1.2	328	0.2	46.1	2.6	13	0.92	63.9	7.4	0.2	42	0.3	23.7	<0.1	129	<0.01
1095389	Rock	1.05	4	92.6	68.4	4.3	4614	0.5	569.9	42.8	624	10.51	375.0	<0.5	2.1	6	4.0	23.5	<0.1	369	<0.01
1095390	Rock	1.47	3	43.1	108.1	3.9	2281	0.8	181.8	14.6	242	5.74	154.0	<0.5	1.8	106	8.0	30.3	<0.1	690	0.14
1095391	Rock	1.02	158	92.7	181.7	2.5	793	1.3	323.3	4.9	38	4.09	196.9	9.2	1.1	141	2.1	89.3	<0.1	800	0.09
1095392	Rock	1.50	<2	1.3	8.4	1.4	258	<0.1	24.5	8.5	888	3.94	19.6	<0.5	1.9	403	0.8	0.2	<0.1	26	16.12
1095393	Rock	1.67	<2	0.2	29.3	0.8	32	<0.1	8.0	3.2	396	1.82	10.3	<0.5	3.4	122	0.2	0.2	<0.1	12	3.95
1095394	Rock	1.74	3	1.2	75.0	5.8	26	<0.1	197.3	58.5	827	4.27	198.4	<0.5	7.7	223	<0.1	0.5	<0.1	133	14.02
1095395	Rock	2.05	<2	0.1	13.2	2.8	12	<0.1	11.3	5.5	1476	3.09	2.6	<0.5	2.4	222	<0.1	<0.1	<0.1	9	8.11
1095396	Rock	1.14	<2	<0.1	33.0	1.8	14	<0.1	12.7	5.4	196	1.24	1.2	0.6	3.7	67	<0.1	<0.1	0.1	11	1.35
1095397	Rock	1.21	<2	5.2	44.0	4.5	65	0.7	34.0	0.5	56	0.70	5.8	<0.5	0.8	105	1.3	1.4	<0.1	223	1.58
1095967	Rock	0.62	6	17.5	13.7	38.5	75	0.3	9.2	1.3	63	1.41	80.4	6.6	10.8	149	0.5	7.8	0.8	50	0.02
1095968	Rock	0.68	3	7.6	19.6	24.3	71	0.2	12.7	1.9	113	3.18	231.0	2.3	8.8	53	0.6	7.0	0.3	60	0.02
1095969	Rock	1.32	<2	0.3	2.4	6.3	4	<0.1	1.8	0.3	40	0.61	12.4	<0.5	0.7	7	<0.1	0.3	<0.1	3	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

CERTIFICATE OF ANALYSIS WHI11001055.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1095371	Rock	0.021	2	8	0.50	73	<0.001	<20	0.09	0.001	<0.01	<0.1	0.46	<0.1	<0.05	0.6	<0.5	<1	<0.2
1095372	Rock	0.021	<1	6	0.58	45	<0.001	<20	0.03	0.001	<0.01	<0.1	0.12	<0.1	<0.05	0.4	<0.5	<1	<0.2
1095373	Rock	0.011	<1	6	0.48	66	<0.001	<20	0.05	0.002	<0.01	<0.1	0.05	<0.1	<0.05	0.9	<0.5	<1	<0.2
1095374	Rock	0.069	6	9	1.85	461	<0.001	<20	0.04	0.005	<0.01	<0.1	<0.01	<0.1	<0.05	0.6	<0.5	<1	<0.2
1095375	Rock	0.042	<1	31	4.69	27	<0.001	<20	0.06	0.002	<0.01	<0.1	<0.01	<0.1	<0.05	11.4	0.6	<1	<0.2
1095376	Rock	0.073	2	20	0.18	122	<0.001	<20	0.05	0.002	<0.01	<0.1	<0.01	<0.1	<0.05	6.0	0.6	<1	<0.2
1095377	Rock	0.031	25	1	0.05	136	<0.001	<20	0.34	0.021	0.16	<0.1	<0.01	<0.1	<0.05	1.6	<0.5	<1	<0.2
1095378	Rock	0.034	4	35	0.55	1492	0.002	<20	1.30	0.005	0.19	<0.1	<0.01	<0.1	<0.05	3.5	<0.5	4	<0.2
1095379	Rock	0.035	4	30	0.45	1084	0.002	<20	1.08	0.008	0.17	<0.1	<0.01	<0.1	0.05	2.6	<0.5	3	<0.2
1095380	Rock	0.098	1	9	<0.01	276	<0.001	<20	0.13	0.001	0.05	<0.1	0.08	<0.1	<0.05	1.9	8.0	1	<0.2
1095381	Rock	0.067	2	25	0.19	170	<0.001	<20	1.39	0.003	0.14	<0.1	0.04	<0.1	<0.05	8.6	1.6	4	<0.2
1095382	Rock	0.010	<1	7	<0.01	1076	0.001	<20	0.12	0.001	0.10	<0.1	4.81	0.2	0.16	0.5	8.8	<1	<0.2
1095383	Rock	0.095	31	12	<0.01	783	<0.001	<20	0.37	<0.001	0.19	0.2	2.77	2.6	0.27	1.5	31.2	4	<0.2
1095384	Rock	0.099	12	27	0.69	592	0.006	<20	0.64	0.001	0.13	0.3	0.98	2.6	<0.05	4.4	10.0	2	<0.2
1095385	Rock	0.154	13	40	0.31	1235	0.005	<20	1.53	<0.001	0.13	0.5	29.60	2.9	0.09	5.2	26.9	2	0.9
1095386	Rock	0.097	5	24	0.02	387	0.002	<20	0.25	0.001	0.12	0.3	1.69	0.8	0.17	2.4	18.5	3	<0.2
1095387	Rock	0.121	6	30	0.04	428	0.002	<20	0.50	<0.001	0.09	0.6	16.97	0.4	0.06	3.2	19.1	1	0.4
1095388	Rock	0.021	<1	5	<0.01	25	<0.001	<20	0.44	<0.001	0.01	<0.1	7.34	<0.1	<0.05	1.0	3.0	<1	<0.2
1095389	Rock	0.058	5	16	0.03	1190	0.001	<20	0.87	<0.001	0.06	0.4	2.56	0.4	0.12	3.6	5.0	<1	<0.2
1095390	Rock	0.220	7	41	0.04	398	0.003	<20	0.96	<0.001	0.08	0.1	2.35	0.2	<0.05	3.4	54.7	2	<0.2
1095391	Rock	0.376	2	34	0.01	997	0.001	<20	1.75	<0.001	0.03	0.7	24.99	0.3	0.15	7.7	32.6	1	0.2
1095392	Rock	0.028	20	23	6.02	284	<0.001	<20	0.18	0.017	0.10	<0.1	0.29	<0.1	<0.05	4.1	<0.5	<1	<0.2
1095393	Rock	0.013	9	6	1.52	206	<0.001	<20	0.31	0.004	0.19	<0.1	0.03	<0.1	<0.05	4.2	<0.5	<1	<0.2
1095394	Rock	0.308	36	176	2.89	403	0.002	<20	0.54	0.012	0.24	<0.1	0.04	<0.1	<0.05	17.9	0.5	2	<0.2
1095395	Rock	0.023	10	5	3.46	571	0.001	<20	0.30	0.008	0.24	<0.1	0.03	<0.1	0.32	3.6	<0.5	<1	<0.2
1095396	Rock	0.019	5	8	0.61	1511	0.001	<20	0.59	0.004	0.36	<0.1	<0.01	<0.1	0.05	4.4	<0.5	1	<0.2
1095397	Rock	0.666	10	30	0.05	251	0.005	<20	0.34	0.001	0.15	<0.1	0.29	<0.1	<0.05	1.1	1.5	1	<0.2
1095967	Rock	0.062	27	8	0.02	343	<0.001	<20	0.39	0.002	0.23	0.3	1.26	0.9	0.16	1.1	12.2	1	<0.2
1095968	Rock	0.308	21	14	0.02	181	0.001	<20	0.30	0.001	0.15	0.4	0.38	0.7	0.11	2.2	7.1	1	<0.2
1095969	Rock	0.006	2	6	<0.01	46	<0.001	<20	0.07	0.001	0.02	<0.1	0.18	<0.1	<0.05	0.1	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

CERTIFICATE OF ANALYSIS WHI11001055.2

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1095970	Rock	1.31	<2	0.7	4.5	3.8	27	<0.1	6.8	2.0	1603	1.91	1.6	<0.5	1.0	196	<0.1	0.2	<0.1	6	1.23
1095971	Rock	0.58	<2	0.7	14.0	3.2	119	0.1	14.9	2.5	137	1.48	102.9	<0.5	0.9	13	0.3	4.3	0.7	19	<0.01
1095972	Rock	0.77	5	1.2	7.4	42.9	3	0.2	0.7	0.3	23	1.11	209.2	6.6	15.8	51	<0.1	1.6	0.2	10	0.01
1095973	Rock	0.69	142	8.6	4.5	24.6	4	1.0	4.2	0.2	58	0.65	32.2	3.7	0.5	62	0.1	12.7	<0.1	104	0.01
1095974	Rock	0.83	64	16.6	16.3	16.3	5	0.7	8.8	0.2	61	1.01	55.3	1.0	0.9	10	<0.1	14.5	<0.1	349	<0.01
1095975	Rock	0.31	3	20.2	73.6	8.4	8821	0.9	825.5	71.9	1480	14.43	88.9	1.7	4.3	139	168.1	18.4	0.1	416	0.97
1095976	Rock	0.73	31	88.5	134.9	3.8	1530	0.6	150.8	11.1	187	4.39	313.2	2.2	0.8	96	2.9	77.5	<0.1	918	0.05
1095977	Rock	0.43	4	69.0	122.5	7.8	4638	0.5	460.7	46.6	526	13.73	207.2	1.9	2.9	14	27.4	18.4	0.1	536	0.19
1095978	Rock	0.80	2	0.3	1.0	1.2	22	<0.1	6.6	0.8	353	1.05	2.2	2.4	<0.1	106	0.2	0.6	<0.1	2	6.78
1095979	Rock	1.10	6	0.4	1.0	2.7	51	<0.1	7.6	0.9	597	1.46	2.2	1.8	0.2	339	0.4	0.5	<0.1	3	19.03
1277528	Rock	7.57	5	11.4	13.1	9.4	44	0.2	13.9	1.3	19	0.75	28.7	2.2	1.5	8	<0.1	2.3	0.2	53	0.06
1277529	Rock	7.59	6	9.5	11.3	7.5	21	0.2	5.7	0.6	15	0.69	18.0	2.0	1.2	9	<0.1	2.2	0.2	49	0.12
1277530	Rock	8.54	6	6.3	12.3	5.3	4	0.2	2.6	0.1	6	0.40	4.8	1.4	0.9	6	<0.1	1.4	0.2	54	0.04
1277531	Rock	8.32	2	5.0	12.9	6.6	3	0.2	3.0	<0.1	8	0.39	3.9	1.5	1.1	6	<0.1	1.1	0.2	57	0.05
1277532	Rock	8.73	<2	5.8	14.3	7.0	8	0.2	4.3	0.2	13	0.46	7.6	1.5	1.6	8	<0.1	1.7	0.1	62	0.06
1277533	Rock	9.07	<2	6.7	16.1	8.0	22	0.2	4.6	0.4	16	0.64	10.5	0.7	1.7	14	<0.1	2.5	0.1	59	0.06
1277534	Rock	8.37	6	5.8	9.0	7.4	6	0.3	3.7	0.2	8	0.48	9.1	1.2	1.9	13	<0.1	2.3	0.2	53	0.06
1277535	Rock	8.13	10	6.0	10.0	8.1	8	0.4	3.9	0.2	10	0.61	22.4	<0.5	2.6	19	<0.1	3.6	0.2	50	0.06
1277536	Rock	8.81	11	6.3	6.7	7.9	6	0.3	3.4	0.2	11	0.47	13.7	1.1	1.8	13	<0.1	3.6	0.2	56	0.06
1277537	Rock	10.25	9	5.9	7.0	7.8	3	0.3	3.7	0.1	7	0.37	10.5	<0.5	2.3	15	<0.1	2.9	0.2	54	0.05
1277538	Rock	8.82	11	6.8	7.7	8.0	7	0.4	4.2	0.2	8	0.42	13.2	<0.5	1.9	13	<0.1	3.4	0.2	63	0.04
1277539	Rock	9.62	11	5.0	7.3	6.6	6	0.3	4.6	0.1	9	0.43	11.5	<0.5	2.2	12	<0.1	2.8	0.2	77	0.05
1277540	Rock	9.75	44	4.5	12.9	11.6	13	0.8	6.7	0.3	14	0.50	27.1	0.9	2.0	16	<0.1	4.0	0.2	81	0.05
1277541	Rock	9.57	176	7.1	15.8	9.8	19	1.3	5.8	0.4	16	0.69	49.8	6.6	1.7	14	0.1	8.5	0.2	78	0.06
1277542	Rock	10.78	125	7.3	21.6	32.9	73	1.9	9.9	1.5	31	1.20	89.7	6.0	4.6	33	0.1	10.6	0.7	69	0.06
1277543	Rock	8.86	79	4.9	25.5	98.2	79	2.0	9.0	1.5	40	1.73	141.6	3.0	7.5	66	0.2	10.4	1.1	63	0.08
1277544	Rock	8.75	128	6.5	29.0	55.8	93	2.1	10.0	1.3	26	1.97	231.1	7.1	7.2	89	0.4	20.2	0.6	88	0.05
1277545	Rock	9.09	21	2.0	8.4	133.4	165	1.7	11.3	2.5	43	1.63	138.2	7.1	9.4	51	0.4	11.2	1.2	25	0.06
1277546	Rock	8.56	129	3.4	12.4	140.4	36	2.8	3.4	0.7	35	1.08	195.6	18.4	7.5	56	0.3	19.2	1.0	30	0.06
1277547	Rock	10.84	103	3.9	11.2	151.7	47	2.1	4.9	0.8	30	1.27	308.8	9.3	9.5	104	0.7	32.7	4.7	35	0.05

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

CERTIFICATE OF ANALYSIS WHI11001055.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1095970	Rock	0.022	2	7	0.18	73	<0.001	<20	0.09	0.017	<0.01	<0.1	0.01	<0.1	<0.05	1.0	<0.5	<1	<0.2
1095971	Rock	0.018	2	7	0.14	102	<0.001	<20	0.21	0.002	0.03	0.3	0.59	<0.1	<0.05	1.1	1.5	<1	<0.2
1095972	Rock	0.071	36	4	<0.01	530	<0.001	<20	0.49	0.002	0.17	<0.1	1.65	0.4	0.28	4.1	1.3	1	<0.2
1095973	Rock	0.017	3	10	<0.01	893	<0.001	<20	0.12	<0.001	0.04	0.2	5.83	0.5	0.06	0.3	1.7	<1	<0.2
1095974	Rock	0.024	2	16	<0.01	467	0.002	<20	0.16	<0.001	0.07	0.2	7.12	0.1	0.08	0.9	15.2	<1	<0.2
1095975	Rock	0.386	14	54	0.25	410	0.004	<20	0.72	0.001	0.16	<0.1	0.39	0.7	<0.05	5.2	36.6	2	<0.2
1095976	Rock	0.136	2	23	0.03	1238	0.003	<20	0.79	<0.001	0.06	0.6	11.87	0.4	0.07	3.0	14.8	2	0.3
1095977	Rock	0.057	11	21	0.14	1077	0.002	<20	0.84	<0.001	0.11	0.2	0.40	1.4	0.06	3.6	13.5	1	<0.2
1095978	Rock	0.004	<1	3	2.85	26	<0.001	<20	0.03	0.002	0.01	<0.1	0.04	<0.1	<0.05	0.6	<0.5	<1	<0.2
1095979	Rock	0.004	2	2	6.48	49	<0.001	<20	0.04	0.009	0.02	<0.1	0.05	<0.1	<0.05	1.0	<0.5	<1	<0.2
1277528	Rock	0.010	2	7	0.03	132	<0.001	<20	0.44	0.004	0.12	<0.1	0.35	0.4	<0.05	1.5	4.6	1	<0.2
1277529	Rock	0.007	3	6	0.06	154	<0.001	<20	0.45	0.004	0.12	<0.1	0.87	0.2	<0.05	1.2	4.4	2	<0.2
1277530	Rock	0.004	1	5	0.02	163	<0.001	<20	0.38	0.005	0.12	<0.1	0.29	0.2	<0.05	1.5	3.6	1	<0.2
1277531	Rock	0.005	1	5	0.02	171	<0.001	<20	0.41	0.004	0.14	<0.1	0.28	0.3	<0.05	1.6	1.9	1	<0.2
1277532	Rock	0.007	3	6	0.02	149	<0.001	<20	0.40	0.003	0.12	<0.1	0.39	0.2	<0.05	1.5	2.9	1	<0.2
1277533	Rock	0.012	8	6	0.02	185	<0.001	<20	0.40	0.002	0.13	<0.1	0.41	0.2	0.06	1.2	4.5	1	<0.2
1277534	Rock	0.008	13	5	0.01	138	<0.001	<20	0.37	0.004	0.14	<0.1	1.81	0.3	0.05	0.7	3.5	1	<0.2
1277535	Rock	0.012	11	7	0.02	149	<0.001	<20	0.42	0.003	0.14	<0.1	1.38	0.3	<0.05	1.2	4.3	2	<0.2
1277536	Rock	0.007	9	6	0.01	122	<0.001	<20	0.37	0.003	0.13	<0.1	1.13	0.3	<0.05	0.9	4.3	1	<0.2
1277537	Rock	0.006	10	5	0.01	134	<0.001	<20	0.39	0.003	0.14	<0.1	0.90	0.3	<0.05	1.0	3.7	1	<0.2
1277538	Rock	0.006	6	5	0.01	117	<0.001	<20	0.38	0.003	0.13	<0.1	2.15	0.3	<0.05	1.1	4.6	1	<0.2
1277539	Rock	0.005	5	5	0.01	117	<0.001	<20	0.39	0.003	0.14	<0.1	2.30	0.3	<0.05	1.2	5.0	1	<0.2
1277540	Rock	0.007	6	7	0.02	157	<0.001	<20	0.50	0.004	0.16	<0.1	8.68	0.4	<0.05	1.5	5.4	1	<0.2
1277541	Rock	0.009	4	7	0.01	113	<0.001	<20	0.39	0.002	0.12	<0.1	16.60	0.4	<0.05	1.7	17.6	1	0.3
1277542	Rock	0.033	17	8	0.04	140	<0.001	<20	0.54	0.003	0.17	<0.1	20.31	0.7	0.05	2.9	18.4	1	0.3
1277543	Rock	0.042	22	9	0.06	151	<0.001	<20	0.57	0.003	0.20	0.1	19.07	0.7	0.09	2.4	24.4	2	0.4
1277544	Rock	0.087	19	12	0.03	152	0.001	<20	0.54	<0.001	0.17	0.1	31.03	0.7	0.11	3.6	24.1	2	0.4
1277545	Rock	0.037	31	6	0.03	109	<0.001	<20	0.53	<0.001	0.26	<0.1	7.54	0.6	0.15	1.2	8.7	1	<0.2
1277546	Rock	0.035	28	7	0.02	111	<0.001	<20	0.46	<0.001	0.21	0.1	40.07	1.3	0.10	1.8	22.1	1	0.4
1277547	Rock	0.064	30	8	0.03	118	<0.001	<20	0.50	<0.001	0.24	<0.1	32.69	1.7	0.15	1.7	23.2	2	0.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

CERTIFICATE OF ANALYSIS WHI11001055.2

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1277548	Rock	12.19	72	2.8	13.3	105.8	169	2.5	14.8	2.9	50	2.09	562.3	12.6	10.5	81	0.3	25.8	0.8	36	0.07
1277549	Rock	10.41	85	0.9	13.7	180.7	214	5.6	18.0	4.5	64	2.15	555.5	89.0	10.4	69	0.4	38.0	0.8	22	0.06
1277550	Rock	8.96	65	1.0	10.0	127.8	180	3.4	13.6	3.5	47	1.69	356.3	68.9	11.0	39	0.2	22.2	0.5	17	0.09
1092575	Rock	6.25	4	13.3	57.1	7.5	37	1.2	12.0	0.4	36	0.68	11.4	<0.5	0.8	17	<0.1	7.0	<0.1	201	0.03
1092576	Rock	7.00	16	13.6	47.4	10.9	15	1.9	8.7	0.3	41	0.70	10.4	<0.5	0.7	17	0.3	12.0	<0.1	218	0.01
1092577	Rock	5.94	6	32.6	63.6	12.3	12	4.0	11.0	0.2	40	1.21	42.6	<0.5	0.9	42	0.4	21.7	0.1	405	0.13
1092578	Rock	5.63	3	16.0	74.0	13.0	12	4.4	9.4	0.2	32	1.01	24.0	<0.5	1.1	40	1.1	10.3	0.1	513	0.32
1092579	Rock	6.38	4	28.3	72.4	14.0	78	5.0	10.9	0.7	34	1.89	47.0	1.3	1.7	86	1.2	19.9	0.1	362	0.96
1092580	Rock	6.41	3	17.8	62.8	7.7	37	3.8	14.5	0.4	33	1.64	30.8	<0.5	2.0	78	1.0	14.3	0.1	241	1.04
1092581	Rock	5.41	17	10.0	54.3	8.8	13	3.8	13.1	0.2	36	1.25	21.0	0.7	1.3	54	0.5	6.6	<0.1	178	0.43
1092582	Rock	5.92	<2	8.4	48.0	8.0	24	3.8	11.9	0.2	37	1.33	20.5	<0.5	1.4	63	0.6	6.6	<0.1	115	0.40
1092583	Rock	5.71	<2	6.9	55.6	6.0	7	3.4	11.3	0.2	35	1.12	11.6	<0.5	1.3	49	0.5	3.5	<0.1	165	0.36
1092584	Rock	5.80	<2	8.6	49.1	6.6	7	3.4	10.3	0.2	32	1.15	13.7	<0.5	1.4	73	0.4	3.5	<0.1	139	0.30
1092585	Rock	5.81	3	7.0	34.2	7.7	13	2.5	8.7	0.5	36	1.15	15.4	2.5	0.7	33	0.3	2.0	0.1	79	0.07
1092586	Rock	5.44	13	3.3	23.0	9.1	28	1.4	6.9	1.0	48	1.14	15.3	3.1	0.5	24	0.2	1.4	0.2	28	0.03
1092587	Rock	6.87	9	2.5	17.7	6.8	7	1.2	2.9	0.2	33	0.83	13.7	2.0	0.8	26	0.2	1.1	0.1	22	0.09
1092588	Rock	5.80	16	3.4	18.8	8.8	6	1.6	4.6	0.2	34	0.69	6.4	1.1	0.9	18	<0.1	1.2	0.2	21	0.04
1092589	Rock	6.43	3	11.6	26.8	9.3	4	1.2	5.7	0.2	28	0.76	6.6	<0.5	1.4	19	<0.1	0.9	0.2	30	0.06
1092590	Rock	10.36	6	7.0	28.9	10.8	8	1.2	6.4	0.2	23	0.83	11.1	0.6	1.9	21	<0.1	0.9	0.2	40	0.11
1092549	Rock	5.33	<2	28.0	38.9	20.9	76	4.3	12.2	0.7	14	1.67	55.7	0.7	1.9	99	0.3	8.8	0.1	165	0.02
1092550	Rock	4.44	<2	20.4	64.0	10.4	225	2.2	24.2	3.0	53	1.28	39.9	0.5	1.2	51	0.2	10.5	0.1	219	0.02
1277151	Rock	9.57	121	3.4	11.8	125.4	63	5.8	6.6	1.2	30	1.39	238.1	21.3	7.1	20	0.4	45.1	0.7	32	0.01
1277152	Rock	10.93	34	0.8	6.0	106.4	24	15.3	2.3	0.5	30	0.79	137.1	22.4	6.9	16	0.8	280.9	0.7	6	<0.01
1277153	Rock	10.57	108	1.4	8.2	199.5	72	6.6	4.0	0.8	30	1.14	187.8	15.9	9.5	11	0.4	37.1	1.1	9	<0.01
1277154	Rock	9.13	127	0.2	2.8	281.1	39	17.4	0.9	0.2	27	0.77	134.6	107.5	7.8	8	1.2	54.0	2.3	<2	0.01
1277155	Rock	9.82	343	2.8	5.0	157.8	31	6.3	3.1	0.5	26	1.02	197.5	19.2	7.7	18	0.3	23.0	0.6	19	<0.01
1277156	Rock	8.87	132	1.6	8.2	135.0	28	10.6	4.3	0.8	13	1.46	181.2	23.2	4.6	19	0.6	30.0	2.0	13	0.02
1277157	Rock	8.30	68	1.6	11.9	112.9	70	1.4	9.4	3.2	57	2.47	254.7	28.4	6.0	35	0.4	10.6	1.5	16	<0.01
1277158	Rock	9.14	89	1.1	26.1	27.3	183	2.4	18.0	8.2	203	3.73	523.4	2.2	6.0	49	0.1	5.8	0.3	26	<0.01
1277159	Rock	7.53	8	4.8	18.0	42.7	137	0.4	14.8	5.5	75	2.99	280.3	<0.5	6.3	21	<0.1	2.3	0.3	17	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

CERTIFICATE OF ANALYSIS WHI11001055.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1277548	Rock	0.068	30	8	0.03	128	<0.001	<20	0.49	0.002	0.27	<0.1	22.86	1.3	0.19	1.9	11.9	1	0.3
1277549	Rock	0.057	28	6	0.02	100	<0.001	<20	0.50	0.003	0.30	<0.1	7.56	1.1	0.19	1.3	11.1	1	<0.2
1277550	Rock	0.040	31	5	0.03	125	<0.001	<20	0.49	0.002	0.30	<0.1	5.60	0.9	0.19	1.0	7.6	<1	<0.2
1092575	Rock	0.016	1	16	0.01	193	<0.001	<20	0.29	0.001	0.11	<0.1	0.19	0.2	0.07	1.0	6.8	1	<0.2
1092576	Rock	0.014	2	17	0.01	189	<0.001	<20	0.28	<0.001	0.10	<0.1	0.28	0.3	0.07	0.8	6.5	1	<0.2
1092577	Rock	0.232	3	32	0.02	220	0.002	<20	0.43	<0.001	0.13	0.2	0.38	0.2	0.09	2.1	18.7	2	<0.2
1092578	Rock	0.282	3	30	0.02	363	0.002	<20	0.61	0.002	0.19	0.2	0.39	0.2	0.10	2.5	9.3	2	<0.2
1092579	Rock	0.762	5	41	0.03	507	0.004	<20	0.85	0.006	0.27	0.3	0.26	0.4	0.22	3.4	15.2	3	<0.2
1092580	Rock	0.878	5	48	0.03	467	0.005	<20	0.79	0.005	0.24	0.2	0.15	0.3	0.16	2.9	10.3	2	<0.2
1092581	Rock	0.542	4	42	0.02	432	0.003	<20	0.65	0.004	0.20	0.1	0.13	0.2	0.10	2.6	10.4	2	<0.2
1092582	Rock	0.601	4	44	0.02	391	0.003	<20	0.50	0.002	0.15	0.2	0.09	0.1	0.08	2.2	10.9	2	<0.2
1092583	Rock	0.516	4	45	0.02	393	0.003	<20	0.60	0.003	0.18	<0.1	0.17	0.1	0.07	1.8	6.5	2	<0.2
1092584	Rock	0.498	5	40	0.02	344	0.003	<20	0.52	0.002	0.15	0.1	0.19	0.1	0.07	1.9	7.8	2	<0.2
1092585	Rock	0.318	3	23	0.02	411	0.002	31	0.37	0.006	0.11	0.2	0.22	0.2	0.07	1.4	8.4	1	<0.2
1092586	Rock	0.146	3	16	0.03	1069	0.002	<20	0.35	0.003	0.10	<0.1	0.36	0.2	0.08	1.4	4.9	1	<0.2
1092587	Rock	0.212	2	15	0.02	2556	0.002	<20	0.30	0.005	0.11	<0.1	0.31	0.2	0.11	1.7	11.3	1	<0.2
1092588	Rock	0.078	2	16	<0.01	706	<0.001	<20	0.20	0.002	0.09	<0.1	1.31	<0.1	0.09	1.2	6.4	<1	<0.2
1092589	Rock	0.120	2	16	0.01	654	0.001	<20	0.24	0.002	0.13	<0.1	0.40	0.2	0.11	2.2	8.2	1	<0.2
1092590	Rock	0.238	1	12	0.02	1449	0.001	<20	0.36	0.005	0.15	<0.1	0.32	0.2	0.08	3.0	5.5	2	<0.2
1092549	Rock	0.096	4	17	0.01	313	<0.001	<20	0.41	0.009	0.25	<0.1	0.46	0.7	0.40	2.7	20.3	2	<0.2
1092550	Rock	0.055	2	18	0.01	435	<0.001	<20	0.34	0.003	0.14	<0.1	0.28	0.3	0.14	1.8	18.2	2	<0.2
1277151	Rock	0.032	26	5	0.02	128	<0.001	<20	0.46	0.005	0.26	<0.1	20.08	1.1	0.20	0.9	14.3	1	0.3
1277152	Rock	0.024	26	4	0.02	68	<0.001	<20	0.39	0.002	0.25	<0.1	7.17	0.8	0.12	0.5	18.4	<1	<0.2
1277153	Rock	0.040	25	3	0.02	71	<0.001	<20	0.41	0.002	0.26	<0.1	40.70	1.1	0.13	0.7	24.4	<1	<0.2
1277154	Rock	0.035	25	2	0.02	59	<0.001	87	0.38	<0.001	0.25	<0.1	>100	1.6	0.14	0.9	92.1	1	0.4
1277155	Rock	0.039	26	4	0.02	107	<0.001	<20	0.39	0.003	0.24	<0.1	25.08	1.0	0.17	0.7	12.0	1	<0.2
1277156	Rock	0.022	28	<1	<0.01	249	<0.001	67	0.42	<0.001	0.20	<0.1	>100	2.2	0.16	0.9	56.2	1	1.3
1277157	Rock	0.030	26	6	0.02	200	<0.001	53	0.43	<0.001	0.20	<0.1	>100	1.0	0.25	1.6	48.6	1	1.0
1277158	Rock	0.040	21	9	0.02	145	<0.001	<20	0.49	0.002	0.19	<0.1	15.14	1.4	0.21	3.2	7.9	1	<0.2
1277159	Rock	0.040	27	7	0.01	148	<0.001	<20	0.42	0.003	0.18	<0.1	4.53	0.3	0.17	2.1	1.5	1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

CERTIFICATE OF ANALYSIS WHI11001055.2

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1277160	Rock	7.97	5	4.2	21.1	35.4	131	0.3	21.0	7.1	108	3.34	111.3	<0.5	6.7	8	<0.1	1.7	0.3	17	<0.01
1277161	Rock	9.60	3	2.5	22.9	29.5	92	0.5	14.5	3.8	49	2.62	88.7	<0.5	7.5	22	<0.1	2.1	0.3	19	<0.01
1277162	Rock	9.17	5	2.7	42.5	32.9	115	0.5	18.1	5.1	91	3.52	115.5	<0.5	7.3	19	<0.1	2.5	0.3	21	<0.01
1277163	Rock	11.34	5	3.5	27.1	45.7	110	0.6	14.8	4.6	67	2.99	103.9	<0.5	7.4	35	<0.1	3.6	0.3	17	<0.01
1277164	Rock	8.99	5	3.3	20.2	117.0	94	0.4	15.8	3.9	50	3.10	101.4	<0.5	8.3	16	<0.1	3.5	0.3	21	<0.01
1277165	Rock	7.23	<2	1.5	28.5	14.5	182	0.1	26.4	5.3	111	4.11	68.7	<0.5	8.3	26	0.3	1.2	0.3	29	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

CERTIFICATE OF ANALYSIS WHI11001055.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1277160	Rock	0.036	32	8	0.02	130	<0.001	<20	0.44	0.002	0.14	<0.1	1.91	0.2	0.05	2.4	1.6	1	<0.2
1277161	Rock	0.040	33	7	0.01	126	<0.001	<20	0.44	0.002	0.15	<0.1	1.59	0.2	0.07	1.8	1.5	1	<0.2
1277162	Rock	0.041	29	8	0.02	112	<0.001	<20	0.45	0.002	0.15	<0.1	1.27	0.2	0.08	2.3	2.0	1	<0.2
1277163	Rock	0.042	27	7	0.01	744	<0.001	<20	0.40	0.002	0.15	<0.1	1.00	0.2	0.15	1.9	1.8	<1	<0.2
1277164	Rock	0.045	33	9	0.03	86	<0.001	<20	0.49	0.002	0.15	<0.1	0.94	0.2	0.06	2.0	1.6	2	<0.2
1277165	Rock	0.056	32	15	0.20	100	<0.001	<20	0.83	0.002	0.16	<0.1	0.51	0.1	0.07	4.6	1.9	2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

QUALITY CONTROL REPORT WHI11001055.2

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1093904	Rock	1.08	51	1.2	20.7	28.5	47	1.4	4.7	1.5	30	0.71	154.6	37.6	7.7	20	0.2	6.6	15.0	6	<0.01
REP 1093904	QC			1.0	20.3	28.7	44	1.4	5.0	1.5	31	0.70	152.0	41.8	7.7	20	0.1	6.1	14.7	5	<0.01
1095378	Rock	1.17	5	0.3	30.5	6.5	101	<0.1	31.3	6.5	310	2.27	2.8	2.8	2.9	32	0.2	0.2	0.2	27	0.08
REP 1095378	QC		5																		
1095967	Rock	0.62	6	17.5	13.7	38.5	75	0.3	9.2	1.3	63	1.41	80.4	6.6	10.8	149	0.5	7.8	0.8	50	0.02
REP 1095967	QC			18.3	13.4	39.1	74	0.4	9.0	1.4	63	1.41	78.0	7.1	11.1	151	0.6	7.2	0.9	50	0.02
1095969	Rock	1.32	<2	0.3	2.4	6.3	4	<0.1	1.8	0.3	40	0.61	12.4	<0.5	0.7	7	<0.1	0.3	<0.1	3	<0.01
REP 1095969	QC		<2																		
1092583	Rock	5.71	<2	6.9	55.6	6.0	7	3.4	11.3	0.2	35	1.12	11.6	<0.5	1.3	49	0.5	3.5	<0.1	165	0.36
REP 1092583	QC			7.1	55.1	6.3	8	3.3	11.8	0.2	35	1.12	11.6	<0.5	1.2	49	0.5	3.6	<0.1	161	0.37
1092586	Rock	5.44	13	3.3	23.0	9.1	28	1.4	6.9	1.0	48	1.14	15.3	3.1	0.5	24	0.2	1.4	0.2	28	0.03
REP 1092586	QC		12																		
1277151	Rock	9.57	121	3.4	11.8	125.4	63	5.8	6.6	1.2	30	1.39	238.1	21.3	7.1	20	0.4	45.1	0.7	32	0.01
REP 1277151	QC			3.3	11.3	122.9	62	5.7	7.1	1.2	30	1.38	234.8	25.4	6.9	20	0.3	52.0	0.7	32	<0.01
Core Reject Duplicates																					
1095362	Rock	1.26	26	58.2	58.4	4.2	845	0.8	35.3	4.2	62	4.15	732.3	2.6	1.2	99	0.9	30.2	0.1	853	0.04
DUP 1095362	QC		24	60.4	55.9	4.2	703	0.8	30.3	3.6	57	3.84	763.3	<0.5	0.7	100	0.6	31.3	<0.1	877	0.02
1095397	Rock	1.21	<2	5.2	44.0	4.5	65	0.7	34.0	0.5	56	0.70	5.8	<0.5	0.8	105	1.3	1.4	<0.1	223	1.58
DUP 1095397	QC		<2	4.6	41.4	4.3	62	0.6	31.0	0.7	53	0.68	5.7	<0.5	0.8	99	1.1	1.4	<0.1	211	1.48
1277549	Rock	10.41	85	0.9	13.7	180.7	214	5.6	18.0	4.5	64	2.15	555.5	89.0	10.4	69	0.4	38.0	0.8	22	0.06
DUP 1277549	QC		100	1.0	14.8	205.3	228	6.7	19.5	4.5	58	2.28	614.4	101.1	11.7	80	0.3	38.0	0.9	25	0.06
Reference Materials																					
STD DS8	Standard			12.6	103.4	122.5	296	1.7	36.3	7.0	586	2.33	24.2	94.7	6.8	73	2.3	3.9	5.7	40	0.68
STD DS8	Standard			12.7	114.6	131.2	306	1.6	37.4	7.3	584	2.41	24.9	87.2	7.7	67	2.2	4.6	6.8	41	0.67
STD DS8	Standard			12.4	100.9	111.3	297	1.6	34.3	6.8	606	2.39	23.1	93.8	6.0	64	2.4	3.8	6.0	40	0.69
STD DS8	Standard			15.2	109.2	136.5	320	1.7	38.0	7.7	628	2.49	23.7	98.2	7.4	70	2.4	4.3	7.2	42	0.70
STD OREAS45CA	Standard			0.7	504.2	21.9	64	0.3	248.8	86.7	923	15.38	3.8	38.5	7.4	16	<0.1	<0.1	0.2	208	0.40
STD OREAS45CA	Standard			0.8	502.6	21.1	62	0.3	238.1	86.4	892	15.09	3.7	38.4	7.7	17	0.1	<0.1	0.2	193	0.41

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

QUALITY CONTROL REPORT WHI11001055.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1093904	Rock	0.013	31	<1	0.02	108	0.003	<20	0.46	0.004	0.27	1.3	35.29	0.4	<0.05	0.4	4.6	1	<0.2
REP 1093904	QC	0.012	30	1	0.02	106	0.002	<20	0.46	0.003	0.27	1.2	32.65	0.4	<0.05	0.3	4.6	<1	<0.2
1095378	Rock	0.034	4	35	0.55	1492	0.002	<20	1.30	0.005	0.19	<0.1	<0.01	<0.1	<0.05	3.5	<0.5	4	<0.2
REP 1095378	QC																		
1095967	Rock	0.062	27	8	0.02	343	<0.001	<20	0.39	0.002	0.23	0.3	1.26	0.9	0.16	1.1	12.2	1	<0.2
REP 1095967	QC	0.063	27	8	0.02	334	<0.001	<20	0.38	0.002	0.23	0.3	1.29	0.9	0.16	1.2	13.0	1	<0.2
1095969	Rock	0.006	2	6	<0.01	46	<0.001	<20	0.07	0.001	0.02	<0.1	0.18	<0.1	<0.05	0.1	<0.5	<1	<0.2
REP 1095969	QC																		
1092583	Rock	0.516	4	45	0.02	393	0.003	<20	0.60	0.003	0.18	<0.1	0.17	0.1	0.07	1.8	6.5	2	<0.2
REP 1092583	QC	0.518	4	46	0.02	393	0.003	<20	0.59	0.003	0.18	<0.1	0.14	0.1	0.07	1.7	7.3	2	<0.2
1092586	Rock	0.146	3	16	0.03	1069	0.002	<20	0.35	0.003	0.10	<0.1	0.36	0.2	0.08	1.4	4.9	1	<0.2
REP 1092586	QC																		
1277151	Rock	0.032	26	5	0.02	128	<0.001	<20	0.46	0.005	0.26	<0.1	20.08	1.1	0.20	0.9	14.3	1	0.3
REP 1277151	QC	0.032	26	4	0.02	124	<0.001	<20	0.45	0.004	0.26	<0.1	19.28	1.1	0.20	0.8	14.3	1	0.2
Core Reject Duplicates																			
1095362	Rock	0.110	3	39	0.03	1179	0.002	<20	0.38	0.003	0.08	0.2	13.15	0.7	0.15	2.4	25.2	2	0.3
DUP 1095362	QC	0.114	4	39	0.02	1042	0.002	<20	0.37	<0.001	0.08	0.3	14.05	0.7	0.15	2.5	25.9	2	0.2
1095397	Rock	0.666	10	30	0.05	251	0.005	<20	0.34	0.001	0.15	<0.1	0.29	<0.1	<0.05	1.1	1.5	1	<0.2
DUP 1095397	QC	0.613	10	28	0.05	258	0.005	<20	0.33	0.002	0.14	<0.1	0.31	<0.1	<0.05	1.2	1.4	1	<0.2
1277549	Rock	0.057	28	6	0.02	100	<0.001	<20	0.50	0.003	0.30	<0.1	7.56	1.1	0.19	1.3	11.1	1	<0.2
DUP 1277549	QC	0.064	29	6	0.02	106	<0.001	<20	0.49	0.003	0.30	<0.1	7.42	1.3	0.22	1.4	13.5	1	<0.2
Reference Materials																			
STD DS8	Standard	0.077	16	110	0.59	282	0.115	<20	0.89	0.085	0.39	2.2	0.27	5.1	0.16	2.0	6.2	4	4.8
STD DS8	Standard	0.080	15	114	0.58	277	0.119	<20	0.87	0.083	0.39	2.6	0.19	5.2	0.16	2.2	5.1	4	4.5
STD DS8	Standard	0.076	13	109	0.60	283	0.103	<20	0.91	0.088	0.40	2.3	0.27	5.1	0.16	1.9	5.5	5	4.5
STD DS8	Standard	0.075	18	119	0.61	302	0.133	<20	0.98	0.101	0.43	2.5	0.21	5.9	0.16	2.1	5.6	5	4.7
STD OREAS45CA	Standard	0.041	17	660	0.14	163	0.139	<20	3.77	0.007	0.07	<0.1	0.06	<0.1	<0.05	37.2	<0.5	18	<0.2
STD OREAS45CA	Standard	0.038	16	631	0.15	157	0.138	<20	3.69	0.013	0.07	<0.1	0.01	<0.1	<0.05	40.3	0.5	18	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

QUALITY CONTROL REPORT WHI11001055.2

		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
STD OREAS45CA	Standard			0.8	523.3	20.2	60	0.2	262.5	90.5	942	15.55	3.4	35.2	7.0	18	0.1	0.1	0.2	223	0.44
STD OREAS45CA	Standard			0.8	522.3	19.4	61	0.3	247.8	87.9	898	15.37	3.2	39.1	6.0	16	0.1	<0.1	0.2	196	0.37
STD OXC88	Standard		194																		
STD OXC88	Standard		204																		
STD OXC88	Standard		214																		
STD OXC88	Standard		197																		
STD OXC88	Standard		198																		
STD OXH82	Standard		1271																		
STD OXH82	Standard		1312																		
STD OXH82	Standard		1299																		
STD OXH82	Standard		1285																		
STD OXH82	Standard		1314																		
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

QUALITY CONTROL REPORT WHI11001055.2

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
STD OREAS45CA	Standard	0.039	16	624	0.17	154	0.167	<20	3.90	0.005	0.07	<0.1	0.04	<0.1	<0.05	38.0	<0.5	19	<0.2
STD OREAS45CA	Standard	0.034	16	677	0.15	163	0.161	<20	3.99	0.013	0.08	<0.1	0.04	<0.1	<0.05	36.1	0.9	18	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXC88 Expected																			
STD OXH82 Expected																			
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

QUALITY CONTROL REPORT WHI11001055.2

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		<2	0.1	2.1	4.1	45	<0.1	2.7	3.7	572	2.06	0.6	2.8	5.1	65	0.3	0.4	0.2	37	0.47
G1	Prep Blank		<2	0.1	2.8	3.3	46	<0.1	2.3	3.6	566	2.01	<0.5	0.7	6.3	61	0.4	0.3	0.2	37	0.48

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 24, 2012

QUALITY CONTROL REPORT WHI11001055.2

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																			
G1	Prep Blank	0.074	14	6	0.49	159	0.119	<20	0.92	0.089	0.45	<0.1	<0.01	0.3	<0.05	1.8	<0.5	5	<0.2
G1	Prep Blank	0.068	12	5	0.49	164	0.115	<20	0.93	0.090	0.45	<0.1	<0.01	0.3	<0.05	1.6	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 10, 2011
Report Date: September 25, 2011
Page: 1 of 4

CERTIFICATE OF ANALYSIS WHI11001079.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #12
P.O. Number
Number of Samples: 90

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-500	90	Crush, split and pulverize 500 g rock to 200 mesh			WHI
3B	90	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	90	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

CERTIFICATE OF ANALYSIS WHI11001079.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1277166	Rock	7.47	7	1.9	22.0	21.5	103	0.1	14.7	2.6	37	3.19	47.3	2.3	7.4	24	<0.1	1.4	0.3	22	<0.01
1277167	Rock	9.17	<2	3.4	19.4	25.8	94	0.2	16.4	3.5	55	3.39	64.1	1.4	7.5	8	<0.1	1.9	0.3	18	<0.01
1277168	Rock	10.04	<2	3.9	33.1	35.3	107	0.2	20.5	5.7	93	4.14	83.7	1.6	7.2	9	<0.1	2.4	0.3	20	<0.01
1277169	Rock	8.10	<2	2.7	29.3	28.7	89	0.2	19.5	5.2	74	3.81	126.4	1.7	4.8	8	<0.1	2.3	0.2	13	<0.01
1277170	Rock	11.00	3	1.4	34.1	16.2	145	0.1	36.2	6.7	113	4.13	112.7	2.1	5.0	13	<0.1	1.9	0.2	19	<0.01
1277171	Rock	10.01	11	1.0	46.0	12.1	142	0.2	36.1	7.0	157	4.03	154.0	2.9	6.8	25	0.2	2.0	0.3	21	0.03
1277172	Rock	10.06	<2	1.0	38.5	9.1	144	0.1	35.3	6.7	277	4.18	87.4	1.7	6.5	22	0.6	1.4	0.3	23	0.17
1277173	Rock	7.32	<2	0.6	29.8	5.7	143	<0.1	50.9	10.3	1078	6.87	24.2	0.8	6.1	28	1.4	0.6	0.3	40	0.57
1277174	Rock	6.03	<2	0.6	33.2	6.7	115	<0.1	42.1	7.6	484	4.40	19.2	0.8	7.1	9	2.4	0.3	0.3	33	0.04
1277175	Rock	7.06	<2	0.7	28.6	4.9	131	<0.1	45.3	9.0	894	5.59	13.9	3.5	6.4	17	1.2	0.4	0.2	29	0.31
1277176	Rock	7.05	<2	1.1	32.5	6.7	153	<0.1	47.3	10.1	529	4.95	16.7	<0.5	7.0	7	0.8	0.4	0.3	36	0.04
1277177	Rock	7.20	<2	1.3	35.3	7.8	157	<0.1	43.4	7.5	304	4.48	15.5	1.3	6.8	7	0.4	0.4	0.2	37	0.06
1277178	Rock	8.41	108	0.9	3.7	172.2	42	8.5	3.9	1.1	39	1.13	141.7	46.8	6.4	18	<0.1	31.5	1.1	5	<0.01
1277179	Rock	8.40	113	0.9	7.3	114.4	105	2.5	71.5	3.8	188	2.75	234.0	204.7	6.9	57	<0.1	7.0	1.2	<2	<0.01
1277180	Rock	7.77	67	2.5	14.4	33.2	98	2.4	11.8	4.4	61	2.85	483.1	1.9	5.2	59	<0.1	7.2	0.4	22	<0.01
1277181	Rock	8.68	4	4.1	20.8	27.8	142	0.3	18.1	5.9	77	3.38	164.9	1.1	5.7	11	<0.1	2.4	0.3	17	<0.01
1277182	Rock	8.42	4	3.1	21.9	31.6	102	0.4	16.5	4.9	64	2.93	142.9	0.6	5.9	14	<0.1	2.7	0.3	19	<0.01
1277183	Rock	9.47	15	2.8	16.8	38.0	103	2.1	15.5	4.8	53	2.73	296.8	<0.5	5.4	39	<0.1	5.4	0.4	20	<0.01
1277184	Rock	10.85	108	2.1	23.9	69.0	105	11.6	14.4	4.1	62	2.45	177.0	3.4	6.0	27	0.3	11.2	0.6	16	<0.01
1277185	Rock	9.57	378	0.7	9.6	141.1	82	52.0	6.4	2.8	47	1.28	229.5	104.6	10.3	36	0.4	30.2	1.6	4	<0.01
1277186	Rock	7.30	182	2.4	20.7	157.9	87	69.3	10.8	3.2	48	2.12	250.5	8.6	7.4	69	0.7	58.5	4.6	13	<0.01
1277187	Rock	10.34	1277	0.7	18.8	495.3	93	>100	11.6	2.5	59	1.54	451.0	335.8	10.4	44	6.1	254.1	16.3	9	<0.01
1277188	Rock	10.40	1160	1.4	26.7	125.1	92	64.7	19.0	5.5	105	2.33	274.1	563.0	8.6	34	2.6	50.7	3.2	9	<0.01
1277189	Rock	10.87	164	1.2	66.0	58.2	161	5.3	41.3	9.3	400	4.47	300.5	49.1	9.8	25	2.4	10.6	0.4	17	0.03
1277190	Rock	9.52	38	1.1	65.1	32.6	112	5.2	28.4	6.5	222	3.85	197.5	10.9	9.0	25	0.6	20.2	0.6	14	0.02
1277191	Rock	8.89	481	1.6	85.0	21.1	160	3.0	41.9	9.6	342	4.87	206.3	9.7	7.3	34	1.3	5.3	0.3	22	0.02
1277192	Rock	8.78	55	0.9	45.7	42.6	82	2.3	23.1	4.6	128	2.66	408.2	79.1	12.0	27	0.5	17.9	0.4	11	0.01
1277193	Rock	8.22	57	1.4	44.1	37.8	83	1.2	21.5	4.5	143	3.06	333.8	8.3	9.5	36	0.3	7.2	0.4	17	0.01
1277194	Rock	8.64	39	3.0	15.3	31.3	50	1.3	9.5	2.6	59	1.74	220.1	4.1	4.7	56	0.1	4.4	1.7	13	<0.01
1277195	Rock	3.98	26	3.4	14.4	20.2	59	1.0	9.2	2.7	47	2.05	303.3	2.2	3.4	41	0.1	1.5	0.3	25	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

CERTIFICATE OF ANALYSIS WHI11001079.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1277166	Rock	0.049	27	11	0.13	91	<0.001	<20	0.59	0.003	0.13	<0.1	0.43	0.1	0.05	3.0	1.4	2	<0.2
1277167	Rock	0.042	29	10	0.10	94	<0.001	<20	0.54	0.002	0.12	<0.1	0.34	0.1	<0.05	2.0	1.2	2	<0.2
1277168	Rock	0.048	28	13	0.18	116	<0.001	<20	0.73	0.002	0.13	<0.1	0.37	<0.1	0.06	3.1	1.2	2	<0.2
1277169	Rock	0.041	14	6	0.03	97	<0.001	<20	0.37	0.001	0.09	<0.1	0.31	0.1	0.05	2.9	<0.5	<1	<0.2
1277170	Rock	0.053	14	11	0.19	60	<0.001	<20	0.90	<0.001	0.10	<0.1	0.38	<0.1	0.06	5.0	1.9	2	<0.2
1277171	Rock	0.057	27	13	0.26	224	<0.001	<20	1.03	0.002	0.13	<0.1	0.34	0.1	0.06	5.6	0.8	2	<0.2
1277172	Rock	0.049	27	14	0.38	108	<0.001	<20	1.16	0.001	0.13	<0.1	0.16	<0.1	<0.05	5.0	1.0	2	<0.2
1277173	Rock	0.048	25	26	1.00	88	<0.001	<20	2.11	0.002	0.13	<0.1	0.06	<0.1	<0.05	6.0	<0.5	5	<0.2
1277174	Rock	0.054	30	22	0.71	80	<0.001	<20	1.83	0.002	0.16	<0.1	0.06	<0.1	<0.05	4.7	0.6	4	<0.2
1277175	Rock	0.048	27	21	0.69	83	<0.001	<20	1.65	0.002	0.15	<0.1	0.10	<0.1	<0.05	4.9	0.6	4	<0.2
1277176	Rock	0.055	27	26	0.79	86	<0.001	<20	2.05	0.003	0.16	<0.1	0.13	<0.1	<0.05	5.1	0.5	5	<0.2
1277177	Rock	0.056	28	27	0.84	89	<0.001	<20	2.13	0.003	0.16	<0.1	0.09	<0.1	<0.05	5.2	<0.5	5	<0.2
1277178	Rock	0.022	28	<1	0.02	122	<0.001	<20	0.42	<0.001	0.24	0.1	>100	0.7	0.14	0.7	99.8	<1	1.7
1277179	Rock	0.141	29	41	0.11	569	<0.001	<20	0.36	<0.001	0.24	<0.1	>100	1.1	0.22	5.3	>100	<1	13.1
1277180	Rock	0.047	20	8	0.01	433	<0.001	<20	0.39	0.003	0.18	<0.1	16.72	0.9	0.26	2.0	7.4	1	0.2
1277181	Rock	0.035	27	7	0.01	121	<0.001	<20	0.43	0.002	0.14	<0.1	2.30	0.2	<0.05	2.4	0.7	1	<0.2
1277182	Rock	0.035	28	8	0.02	152	<0.001	<20	0.45	0.003	0.15	<0.1	2.44	0.3	<0.05	1.9	2.1	1	<0.2
1277183	Rock	0.040	25	7	0.02	268	<0.001	<20	0.41	0.003	0.17	<0.1	4.73	0.4	0.11	1.8	3.5	<1	<0.2
1277184	Rock	0.029	24	7	0.02	215	<0.001	<20	0.43	0.003	0.17	<0.1	4.29	0.4	0.07	2.2	4.3	1	<0.2
1277185	Rock	0.025	30	2	0.03	289	<0.001	<20	0.45	0.003	0.26	<0.1	14.06	0.9	0.20	0.9	10.4	<1	<0.2
1277186	Rock	0.038	24	7	0.03	635	<0.001	<20	0.49	0.003	0.20	<0.1	16.50	1.3	0.21	2.4	12.8	2	0.3
1277187	Rock	0.052	28	5	0.03	325	<0.001	<20	0.45	<0.001	0.24	<0.1	49.59	1.6	0.21	1.9	36.6	<1	0.5
1277188	Rock	0.060	31	10	0.05	205	0.001	<20	0.48	<0.001	0.22	<0.1	95.08	0.9	0.16	2.6	36.9	1	0.6
1277189	Rock	0.062	28	10	0.07	396	<0.001	<20	0.75	0.003	0.19	<0.1	7.04	0.5	0.17	4.3	4.6	1	<0.2
1277190	Rock	0.051	30	9	0.04	332	<0.001	<20	0.55	0.002	0.17	<0.1	5.07	0.6	0.06	3.5	3.4	<1	<0.2
1277191	Rock	0.056	29	13	0.05	362	<0.001	<20	0.67	0.002	0.16	<0.1	5.27	0.4	0.09	5.0	2.9	1	<0.2
1277192	Rock	0.054	30	8	0.02	119	<0.001	<20	0.54	0.003	0.22	<0.1	10.05	0.7	0.13	4.8	4.3	1	<0.2
1277193	Rock	0.055	29	11	0.06	204	<0.001	<20	0.67	0.003	0.20	<0.1	9.26	0.9	0.14	3.6	4.0	1	<0.2
1277194	Rock	0.024	15	6	0.03	698	<0.001	<20	0.48	0.004	0.20	<0.1	9.09	0.7	0.20	2.0	7.4	1	<0.2
1277195	Rock	0.021	11	8	0.02	216	<0.001	<20	0.47	0.003	0.16	<0.1	6.65	0.6	0.10	2.2	4.8	2	0.4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

CERTIFICATE OF ANALYSIS WHI11001079.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1277196	Rock	5.44	21	1.9	19.0	18.2	51	1.3	11.8	2.8	100	1.90	198.9	2.8	3.2	36	0.1	1.4	0.3	16	<0.01
1277197	Rock	4.23	22	2.9	15.3	19.8	102	0.3	22.2	6.8	110	3.14	330.6	1.8	3.4	19	<0.1	1.3	0.3	21	<0.01
1277198	Rock	4.99	4	1.5	30.4	15.2	128	<0.1	27.4	6.6	94	3.32	165.5	1.6	3.4	14	0.4	1.3	0.2	21	0.01
1277199	Rock	4.45	33	1.4	35.3	15.8	160	<0.1	37.1	9.1	104	3.20	145.1	<0.5	3.6	15	0.6	1.1	0.3	20	0.05
1277200	Rock	6.60	9	1.2	47.1	13.7	206	<0.1	42.9	11.7	398	5.19	146.9	0.6	3.2	11	0.9	1.1	0.3	24	0.04
1278301	Rock	6.96	<2	1.6	34.9	16.9	154	<0.1	31.5	10.1	165	3.20	76.7	1.5	2.3	9	0.8	1.4	0.3	17	0.04
1278302	Rock	5.65	2	1.9	33.8	22.8	147	0.1	37.5	9.4	130	3.15	92.3	1.3	2.5	11	0.4	1.4	0.3	20	0.05
1278303	Rock	5.64	3	1.8	52.2	20.5	191	<0.1	46.2	12.6	203	3.96	91.6	1.4	3.0	9	0.5	1.2	0.3	24	0.03
1278304	Rock	6.19	5	1.5	67.0	16.8	136	0.1	35.2	9.9	105	3.19	85.9	0.7	2.6	9	0.4	1.0	0.3	19	0.03
1278305	Rock	6.09	6	1.4	52.7	19.8	163	0.1	31.9	10.3	124	3.51	113.6	0.8	2.4	8	0.2	1.3	0.3	22	0.04
1278306	Rock	7.46	<2	1.3	67.2	12.5	210	<0.1	47.0	12.0	374	6.02	51.7	<0.5	2.6	11	0.6	0.9	0.3	29	0.04
1278307	Rock	7.30	2	1.4	41.1	14.9	164	<0.1	40.3	7.9	350	4.09	47.3	<0.5	2.2	13	1.0	0.9	0.3	26	0.06
1278308	Rock	6.44	3	2.8	29.5	28.2	110	0.1	23.4	6.7	175	3.41	107.3	0.7	2.2	14	1.3	1.1	0.3	25	0.04
1278309	Rock	7.32	2	2.7	34.2	25.7	104	0.1	27.3	4.1	79	3.22	65.7	<0.5	2.3	12	0.5	0.8	0.3	30	0.04
1278310	Rock	6.37	<2	2.3	63.5	22.7	209	0.1	47.8	11.9	203	6.35	170.2	<0.5	3.7	20	0.6	0.7	0.4	31	0.04
1278311	Rock	7.70	4	0.7	63.7	7.8	234	<0.1	54.2	18.5	532	4.67	65.4	<0.5	2.6	11	1.9	0.2	0.3	19	0.06
1278312	Rock	8.15	<2	0.8	52.7	6.7	204	<0.1	65.2	22.1	970	6.60	40.8	<0.5	2.6	9	2.8	0.3	0.3	23	0.07
1093916	Rock	1.00	<2	0.3	68.7	2.1	113	0.2	86.7	32.4	876	4.76	152.5	<0.5	0.4	248	0.3	8.6	<0.1	19	5.33
1093917	Rock	1.91	<2	0.2	66.7	1.1	70	<0.1	146.7	42.7	947	5.63	71.5	<0.5	0.3	162	0.2	0.8	<0.1	78	3.93
1093918	Rock	1.18	4	0.2	4.4	0.5	17	0.1	9.1	2.2	395	1.01	99.1	2.4	<0.1	23	0.2	3.1	<0.1	<2	1.62
1093919	Rock	1.19	<2	2.8	14.8	4.7	3	0.4	5.4	0.3	48	0.54	2.4	<0.5	0.7	21	<0.1	3.5	<0.1	71	0.09
1093920	Rock	1.42	<2	0.1	29.4	24.1	29	<0.1	15.4	6.6	1145	7.44	4.0	1.0	2.0	270	<0.1	0.4	0.1	14	8.64
1093921	Rock	1.20	<2	0.2	42.8	6.7	29	0.2	22.4	7.0	234	3.56	3.7	0.7	2.3	69	<0.1	0.3	0.2	10	1.81
1093922	Rock	1.37	<2	1.4	4.9	3.8	6	0.2	2.3	0.2	46	0.45	2.5	0.6	0.1	30	<0.1	2.8	<0.1	37	0.03
1093923	Rock	1.15	<2	0.2	57.5	0.8	81	<0.1	105.8	40.0	996	5.21	51.9	<0.5	0.2	398	0.7	3.2	<0.1	25	3.68
1093924	Rock	1.46	<2	0.1	3.9	12.1	48	<0.1	2.1	1.0	715	0.85	14.8	<0.5	<0.1	215	0.2	1.8	<0.1	<2	5.79
1093925	Rock	1.66	<2	0.2	82.6	0.9	60	<0.1	47.2	32.8	979	4.91	35.0	<0.5	0.1	233	0.3	2.0	<0.1	74	4.23
1093926	Rock	1.92	<2	0.2	82.9	2.0	58	<0.1	52.0	33.5	1043	5.06	112.0	<0.5	0.1	228	0.3	2.9	<0.1	59	4.48
1095398	Rock	1.17	<2	0.2	24.0	1.8	48	<0.1	45.2	18.8	941	3.92	97.8	12.6	0.1	221	0.1	11.4	<0.1	16	7.76
1095399	Rock	1.60	<2	0.1	13.2	4.6	47	<0.1	20.5	7.7	785	3.88	18.8	<0.5	3.0	203	<0.1	0.8	<0.1	16	7.58

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

CERTIFICATE OF ANALYSIS WHI11001079.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1277196	Rock	0.019	11	8	0.03	143	<0.001	<20	0.49	0.003	0.17	<0.1	5.88	0.6	0.13	2.7	2.8	2	<0.2
1277197	Rock	0.025	12	9	0.02	833	<0.001	<20	0.47	0.003	0.14	<0.1	1.97	0.2	0.07	2.2	1.5	1	<0.2
1277198	Rock	0.040	9	<1	0.04	248	<0.001	<20	0.54	0.003	0.14	<0.1	0.52	0.1	<0.05	3.1	1.6	1	<0.2
1277199	Rock	0.047	10	8	0.04	302	<0.001	<20	0.56	0.002	0.13	<0.1	0.54	0.1	0.05	4.2	0.9	1	<0.2
1277200	Rock	0.037	9	10	0.06	115	<0.001	<20	0.61	0.002	0.13	<0.1	0.53	0.1	0.05	5.9	0.7	1	<0.2
1278301	Rock	0.046	4	6	0.04	139	<0.001	<20	0.52	0.003	0.14	<0.1	0.52	0.2	<0.05	4.3	1.0	<1	<0.2
1278302	Rock	0.042	4	8	0.05	177	<0.001	<20	0.49	0.002	0.14	<0.1	0.41	0.1	<0.05	4.8	1.4	1	<0.2
1278303	Rock	0.046	4	12	0.07	204	<0.001	<20	0.60	0.003	0.15	<0.1	0.38	0.1	<0.05	6.6	1.1	1	<0.2
1278304	Rock	0.041	4	6	0.02	169	<0.001	<20	0.45	0.003	0.14	<0.1	0.51	0.1	<0.05	4.7	1.4	<1	<0.2
1278305	Rock	0.041	4	8	0.04	102	<0.001	<20	0.53	0.003	0.14	<0.1	0.48	0.1	<0.05	4.3	1.3	1	<0.2
1278306	Rock	0.042	4	16	0.26	163	<0.001	<20	1.09	0.002	0.13	<0.1	0.33	0.1	<0.05	6.4	1.1	3	<0.2
1278307	Rock	0.036	4	14	0.29	180	<0.001	<20	0.98	0.002	0.14	<0.1	0.37	0.1	<0.05	5.3	0.7	2	<0.2
1278308	Rock	0.044	3	11	0.13	128	<0.001	<20	0.64	0.002	0.12	<0.1	0.52	0.1	<0.05	3.5	1.7	2	<0.2
1278309	Rock	0.042	4	7	0.19	130	<0.001	<20	0.80	0.003	0.14	<0.1	0.43	0.1	<0.05	4.0	1.6	2	<0.2
1278310	Rock	0.078	5	16	0.10	199	<0.001	<20	0.91	0.004	0.19	<0.1	0.47	0.1	0.08	11.4	1.1	2	<0.2
1278311	Rock	0.048	4	8	0.09	109	<0.001	<20	0.53	0.004	0.14	<0.1	0.19	<0.1	<0.05	7.8	0.9	<1	<0.2
1278312	Rock	0.050	4	11	0.14	119	<0.001	<20	0.54	0.004	0.14	<0.1	0.13	0.1	<0.05	8.5	<0.5	1	<0.2
1093916	Rock	0.056	5	26	1.99	577	<0.001	<20	0.41	0.003	0.30	<0.1	0.77	0.2	0.10	14.6	<0.5	<1	<0.2
1093917	Rock	0.046	5	187	4.25	803	0.026	<20	3.12	<0.001	0.18	<0.1	0.06	<0.1	0.18	15.7	<0.5	7	<0.2
1093918	Rock	0.003	<1	1	0.09	74	<0.001	<20	0.05	0.003	0.02	<0.1	0.03	<0.1	<0.05	1.4	<0.5	<1	<0.2
1093919	Rock	0.065	4	8	0.01	164	0.001	<20	0.13	0.002	0.05	<0.1	0.07	<0.1	<0.05	0.5	<0.5	<1	<0.2
1093920	Rock	0.008	7	8	4.21	570	<0.001	<20	0.20	0.020	0.11	<0.1	0.04	<0.1	0.21	3.8	<0.5	<1	<0.2
1093921	Rock	0.020	3	8	0.59	491	<0.001	<20	0.35	0.005	0.20	<0.1	0.04	0.1	0.05	3.3	<0.5	<1	<0.2
1093922	Rock	0.012	<1	4	0.01	3418	<0.001	<20	0.05	0.002	0.02	<0.1	0.09	<0.1	0.09	0.3	<0.5	<1	<0.2
1093923	Rock	0.053	4	60	2.48	413	<0.001	<20	1.12	0.001	0.26	<0.1	<0.01	<0.1	<0.05	15.2	<0.5	2	<0.2
1093924	Rock	0.002	<1	3	0.63	60	<0.001	<20	0.07	0.003	0.04	<0.1	0.02	<0.1	<0.05	0.9	<0.5	<1	<0.2
1093925	Rock	0.046	4	141	3.30	535	0.045	<20	1.72	0.001	0.21	<0.1	<0.01	<0.1	0.06	25.0	<0.5	5	<0.2
1093926	Rock	0.050	4	153	2.71	470	0.002	<20	1.45	0.005	0.21	<0.1	<0.01	<0.1	0.12	24.7	<0.5	4	<0.2
1095398	Rock	0.021	2	14	3.13	227	<0.001	<20	0.20	0.003	0.14	<0.1	0.02	<0.1	<0.05	10.3	<0.5	<1	<0.2
1095399	Rock	0.015	9	10	3.36	479	<0.001	<20	0.26	0.017	0.18	<0.1	0.02	<0.1	0.25	5.2	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

CERTIFICATE OF ANALYSIS WHI11001079.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1095400	Rock	1.44	<2	0.1	12.6	2.2	13	<0.1	12.4	5.6	566	4.04	27.6	<0.5	3.3	198	<0.1	1.3	<0.1	27	7.82
1278313	Rock	5.15	<2	1.3	65.7	10.8	270	<0.1	65.8	16.6	606	4.45	52.0	<0.5	2.5	26	5.9	0.4	0.3	20	0.16
1278314	Rock	5.25	2	0.6	44.4	6.3	233	<0.1	71.4	20.2	951	6.81	28.0	<0.5	2.4	19	4.3	0.1	0.3	18	0.13
1278315	Rock	6.34	2	1.0	52.0	6.6	222	<0.1	59.9	15.3	531	4.52	33.2	<0.5	2.5	15	1.3	0.2	0.3	19	0.12
1278316	Rock	3.95	4	1.3	51.7	12.7	215	<0.1	46.6	13.4	231	3.74	60.2	<0.5	2.4	13	1.0	0.3	0.3	25	0.04
1278317	Rock	6.22	3	1.3	46.1	16.1	169	<0.1	37.7	11.4	209	3.77	35.3	<0.5	2.3	13	0.9	0.3	0.3	22	0.05
1278318	Rock	5.92	<2	0.9	60.5	13.0	295	<0.1	73.8	17.7	597	5.91	24.7	<0.5	2.5	17	2.6	0.2	0.3	21	0.06
1278319	Rock	4.83	<2	1.4	43.6	14.5	183	<0.1	50.1	11.9	397	4.11	52.0	<0.5	2.7	20	1.7	0.2	0.3	21	0.06
1278320	Rock	5.51	<2	1.1	38.4	11.2	143	<0.1	34.8	9.8	229	2.71	21.4	<0.5	2.2	18	0.4	0.2	0.3	16	0.05
1278321	Rock	4.88	<2	0.8	49.8	7.3	195	<0.1	40.1	13.5	388	3.72	20.0	0.7	2.2	15	0.8	0.2	0.3	20	0.03
1278322	Rock	5.56	<2	1.1	48.2	8.7	237	<0.1	52.6	23.8	670	5.20	20.7	0.7	2.0	10	0.9	0.2	0.3	22	0.01
1278323	Rock	5.73	2	3.4	47.9	12.3	267	<0.1	63.1	24.1	705	5.59	22.1	<0.5	2.1	9	1.1	0.2	0.2	24	0.01
1278324	Rock	5.20	<2	2.1	42.4	13.1	262	<0.1	58.4	23.1	618	4.46	28.2	0.6	2.0	13	0.8	0.2	0.2	21	0.02
1278325	Rock	5.69	<2	3.7	36.9	16.6	196	<0.1	43.9	17.1	383	3.94	25.2	<0.5	1.7	11	0.6	0.2	0.2	23	<0.01
1278326	Rock	4.95	<2	2.0	43.7	20.2	240	<0.1	58.7	23.1	648	5.60	27.7	<0.5	1.9	12	0.7	0.2	0.3	22	0.02
1278327	Rock	3.82	<2	2.0	39.3	28.3	190	<0.1	46.7	19.9	574	5.09	34.0	0.7	1.5	15	0.4	0.3	0.3	21	0.76
1278328	Rock	5.01	<2	3.1	36.2	29.6	164	<0.1	47.6	17.4	499	4.08	32.3	0.6	1.7	13	0.9	0.2	0.3	19	0.05
1278329	Rock	4.36	<2	5.2	41.0	27.0	155	<0.1	53.9	21.0	442	4.86	28.7	0.7	1.9	9	0.3	0.2	0.3	22	0.02
1278330	Rock	5.36	<2	1.5	48.2	15.2	269	<0.1	78.7	24.8	483	4.70	40.7	<0.5	2.1	19	0.4	0.3	0.3	28	0.04
1278331	Rock	5.19	<2	3.5	42.7	14.4	234	0.1	56.0	18.4	365	3.68	33.8	<0.5	2.0	18	0.6	0.3	0.3	30	0.03
1278351	Rock	7.61	107	3.9	8.2	12.6	27	0.7	2.3	0.7	19	0.88	126.2	8.1	2.5	18	<0.1	3.6	0.2	22	<0.01
1278352	Rock	8.58	69	5.7	5.1	12.8	10	0.9	3.0	0.3	23	0.61	57.8	5.4	1.8	10	<0.1	5.6	0.2	25	<0.01
1278353	Rock	8.35	154	7.7	17.8	19.2	57	1.3	8.1	1.2	33	1.41	186.8	20.0	1.9	52	0.1	9.4	0.3	41	0.01
1278354	Rock	7.32	276	4.8	18.3	12.3	81	1.1	12.5	2.0	45	1.49	273.2	24.9	1.6	103	0.2	16.1	0.2	52	0.13
1278355	Rock	3.75	531	3.5	20.8	9.0	112	1.0	18.0	2.7	57	1.56	268.2	134.3	1.3	85	0.2	11.6	0.2	30	0.02
1278356	Rock	5.59	233	3.0	16.7	9.0	60	0.7	11.4	1.8	55	1.18	135.9	50.9	0.9	18	0.1	5.9	0.2	28	0.02
1278357	Rock	5.96	198	4.0	18.5	10.9	57	0.8	11.6	1.8	52	1.13	122.1	33.0	0.8	16	<0.1	5.9	0.2	34	0.02
1278358	Rock	7.03	134	6.7	60.4	13.1	167	0.7	32.7	5.9	322	1.87	155.3	32.1	2.2	159	2.1	7.9	0.3	55	5.16
1278359	Rock	5.78	41	2.6	12.7	12.5	55	0.3	8.4	1.6	78	1.11	72.9	2.4	2.9	22	0.4	4.4	0.2	22	0.04
1278360	Rock	4.70	67	2.9	16.1	7.4	88	0.6	13.0	1.9	59	1.10	145.7	2.0	1.5	25	0.3	8.0	0.1	32	0.05

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

CERTIFICATE OF ANALYSIS WHI11001079.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1095400	Rock	0.020	23	20	3.55	269	<0.001	<20	0.30	0.013	0.16	<0.1	<0.01	<0.1	<0.05	5.9	<0.5	<1	<0.2
1278313	Rock	0.052	4	8	0.10	110	<0.001	<20	0.64	0.005	0.14	<0.1	0.17	<0.1	0.07	6.5	<0.5	1	<0.2
1278314	Rock	0.041	4	8	0.15	149	<0.001	<20	0.48	0.005	0.15	<0.1	0.10	<0.1	<0.05	8.7	<0.5	1	<0.2
1278315	Rock	0.054	4	8	0.14	141	<0.001	<20	0.70	0.005	0.15	<0.1	0.10	<0.1	<0.05	7.2	<0.5	1	<0.2
1278316	Rock	0.045	4	10	0.13	110	<0.001	<20	0.85	0.004	0.14	<0.1	0.17	<0.1	<0.05	6.0	<0.5	2	<0.2
1278317	Rock	0.041	4	9	0.10	97	<0.001	<20	0.68	0.004	0.13	<0.1	0.18	0.1	<0.05	5.1	0.7	1	<0.2
1278318	Rock	0.048	4	10	0.14	111	<0.001	<20	0.73	0.004	0.13	<0.1	0.15	0.1	<0.05	7.8	<0.5	1	<0.2
1278319	Rock	0.053	3	11	0.14	266	<0.001	<20	0.76	0.004	0.13	<0.1	0.14	0.1	0.07	6.0	<0.5	2	<0.2
1278320	Rock	0.040	3	8	0.11	139	<0.001	<20	0.60	0.004	0.14	<0.1	0.15	<0.1	<0.05	4.4	<0.5	1	<0.2
1278321	Rock	0.039	4	9	0.15	114	<0.001	<20	0.74	0.004	0.13	<0.1	0.13	0.1	<0.05	5.6	<0.5	1	<0.2
1278322	Rock	0.044	3	10	0.14	80	<0.001	<20	0.72	0.005	0.13	<0.1	0.15	<0.1	<0.05	6.3	0.5	1	<0.2
1278323	Rock	0.054	3	11	0.14	71	<0.001	<20	0.71	0.003	0.11	<0.1	0.19	<0.1	<0.05	7.3	1.0	1	<0.2
1278324	Rock	0.052	4	11	0.10	95	<0.001	<20	0.63	0.003	0.11	<0.1	0.30	0.1	<0.05	6.9	<0.5	1	<0.2
1278325	Rock	0.043	3	10	0.10	83	<0.001	<20	0.63	0.004	0.11	<0.1	0.41	<0.1	<0.05	5.6	0.6	1	<0.2
1278326	Rock	0.046	3	11	0.08	112	<0.001	<20	0.59	0.004	0.13	<0.1	0.66	<0.1	<0.05	7.4	0.6	1	<0.2
1278327	Rock	0.048	3	12	0.14	315	<0.001	<20	0.62	0.003	0.11	<0.1	0.97	<0.1	<0.05	7.1	<0.5	1	<0.2
1278328	Rock	0.040	3	6	0.06	118	<0.001	<20	0.57	0.004	0.13	<0.1	1.03	0.2	<0.05	4.9	<0.5	1	<0.2
1278329	Rock	0.046	3	11	0.08	109	<0.001	<20	0.58	0.004	0.12	<0.1	0.96	<0.1	<0.05	6.6	0.9	1	<0.2
1278330	Rock	0.043	4	11	0.17	865	<0.001	<20	0.87	0.004	0.14	<0.1	0.36	0.2	<0.05	7.5	<0.5	2	<0.2
1278331	Rock	0.044	3	10	0.10	1084	<0.001	<20	0.65	0.004	0.14	<0.1	0.46	0.2	<0.05	6.5	1.5	1	<0.2
1278351	Rock	0.037	22	<1	0.01	554	<0.001	<20	0.35	0.004	0.18	<0.1	3.60	0.6	0.13	1.1	9.4	2	<0.2
1278352	Rock	0.027	15	9	0.01	504	0.002	<20	0.30	0.003	0.14	<0.1	5.18	0.4	0.08	0.9	7.7	1	<0.2
1278353	Rock	0.098	19	16	0.02	661	0.002	<20	0.38	0.004	0.17	<0.1	8.71	2.0	0.17	1.9	8.3	2	<0.2
1278354	Rock	0.171	14	20	0.02	729	0.003	<20	0.44	0.003	0.14	<0.1	8.74	1.9	0.14	1.8	6.2	2	0.2
1278355	Rock	0.120	12	19	0.01	459	0.002	<20	0.33	0.002	0.11	<0.1	6.54	2.4	0.12	1.5	7.8	1	<0.2
1278356	Rock	0.039	10	18	0.01	408	0.001	<20	0.28	0.003	0.09	<0.1	6.87	1.1	0.11	0.9	2.9	1	<0.2
1278357	Rock	0.043	10	15	0.01	332	0.001	<20	0.26	0.003	0.09	0.2	8.09	0.9	0.12	0.8	3.3	1	<0.2
1278358	Rock	0.103	12	19	0.11	1329	0.002	<20	0.63	0.004	0.14	0.1	6.90	0.8	0.19	2.1	5.2	2	<0.2
1278359	Rock	0.034	19	9	0.04	839	0.001	<20	0.40	0.002	0.16	<0.1	2.81	0.8	0.12	1.1	2.8	1	<0.2
1278360	Rock	0.048	10	18	0.01	537	0.001	<20	0.31	0.002	0.10	<0.1	4.05	0.9	0.12	1.0	4.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

QUALITY CONTROL REPORT WHI11001079.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1277169	Rock	8.10	<2	2.7	29.3	28.7	89	0.2	19.5	5.2	74	3.81	126.4	1.7	4.8	8	<0.1	2.3	0.2	13	<0.01
REP 1277169	QC		<2																		
1277181	Rock	8.68	4	4.1	20.8	27.8	142	0.3	18.1	5.9	77	3.38	164.9	1.1	5.7	11	<0.1	2.4	0.3	17	<0.01
REP 1277181	QC			4.3	20.9	28.7	146	0.4	17.5	5.9	83	3.47	174.4	0.9	5.8	12	<0.1	1.9	0.3	18	<0.01
1278308	Rock	6.44	3	2.8	29.5	28.2	110	0.1	23.4	6.7	175	3.41	107.3	0.7	2.2	14	1.3	1.1	0.3	25	0.04
REP 1278308	QC			2.7	29.5	26.9	109	0.1	24.0	6.7	172	3.38	107.2	0.8	2.2	13	1.2	1.0	0.3	25	0.04
1093917	Rock	1.91	<2	0.2	66.7	1.1	70	<0.1	146.7	42.7	947	5.63	71.5	<0.5	0.3	162	0.2	0.8	<0.1	78	3.93
REP 1093917	QC		<2																		
1278315	Rock	6.34	2	1.0	52.0	6.6	222	<0.1	59.9	15.3	531	4.52	33.2	<0.5	2.5	15	1.3	0.2	0.3	19	0.12
REP 1278315	QC		<2																		
1278326	Rock	4.95	<2	2.0	43.7	20.2	240	<0.1	58.7	23.1	648	5.60	27.7	<0.5	1.9	12	0.7	0.2	0.3	22	0.02
REP 1278326	QC			1.7	43.5	20.9	234	<0.1	57.0	23.2	653	5.51	27.0	<0.5	1.9	12	0.7	0.2	0.3	22	0.01
Core Reject Duplicates																					
1277180	Rock	7.77	67	2.5	14.4	33.2	98	2.4	11.8	4.4	61	2.85	483.1	1.9	5.2	59	<0.1	7.2	0.4	22	<0.01
DUP 1277180	QC		66	2.1	15.1	32.5	95	2.3	12.2	4.2	61	2.78	474.1	1.6	5.0	57	0.1	7.5	0.4	21	<0.01
1093918	Rock	1.18	4	0.2	4.4	0.5	17	0.1	9.1	2.2	395	1.01	99.1	2.4	<0.1	23	0.2	3.1	<0.1	<2	1.62
DUP 1093918	QC		4	0.3	4.7	0.6	18	<0.1	10.2	2.3	402	0.99	104.6	3.9	<0.1	23	0.2	3.1	<0.1	2	1.58
1278355	Rock	3.75	531	3.5	20.8	9.0	112	1.0	18.0	2.7	57	1.56	268.2	134.3	1.3	85	0.2	11.6	0.2	30	0.02
DUP 1278355	QC		556	3.5	20.3	9.8	111	1.0	17.4	3.0	56	1.52	263.1	110.2	1.4	85	0.2	11.3	0.2	29	0.02
Reference Materials																					
STD DS8	Standard			12.6	104.6	119.7	307	1.7	38.1	7.1	622	2.47	25.6	98.1	6.9	66	2.3	4.4	6.5	40	0.71
STD DS8	Standard			12.3	93.5	112.8	283	1.9	31.7	6.4	556	2.27	22.4	89.5	5.6	62	2.3	4.5	6.4	37	0.64
STD DS8	Standard			13.1	113.2	128.3	316	1.8	38.4	7.9	609	2.45	24.6	122.9	6.6	66	2.4	4.3	6.5	42	0.70
STD OREAS45CA	Standard			0.9	540.8	20.1	66	0.3	267.0	91.8	921	16.51	3.9	42.0	6.9	15	0.1	<0.1	0.2	230	0.45
STD OREAS45CA	Standard			0.7	510.1	18.5	55	0.3	239.1	85.4	834	14.93	3.0	42.6	6.2	15	<0.1	<0.1	0.2	191	0.40
STD OREAS45CA	Standard			0.9	538.7	21.7	65	0.3	266.7	95.8	959	16.91	3.4	42.4	7.6	16	<0.1	<0.1	0.2	220	0.45
STD OXC88	Standard		196																		
STD OXC88	Standard		200																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

QUALITY CONTROL REPORT WHI11001079.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1277169	Rock	0.041	14	6	0.03	97	<0.001	<20	0.37	0.001	0.09	<0.1	0.31	0.1	0.05	2.9	<0.5	<1	<0.2
REP 1277169	QC																		
1277181	Rock	0.035	27	7	0.01	121	<0.001	<20	0.43	0.002	0.14	<0.1	2.30	0.2	<0.05	2.4	0.7	1	<0.2
REP 1277181	QC	0.036	27	8	0.01	126	<0.001	<20	0.44	0.003	0.15	<0.1	3.16	0.2	<0.05	2.4	1.9	1	<0.2
1278308	Rock	0.044	3	11	0.13	128	<0.001	<20	0.64	0.002	0.12	<0.1	0.52	0.1	<0.05	3.5	1.7	2	<0.2
REP 1278308	QC	0.042	3	11	0.13	127	<0.001	<20	0.64	0.002	0.12	<0.1	0.49	0.1	<0.05	3.4	1.3	2	<0.2
1093917	Rock	0.046	5	187	4.25	803	0.026	<20	3.12	<0.001	0.18	<0.1	0.06	<0.1	0.18	15.7	<0.5	7	<0.2
REP 1093917	QC																		
1278315	Rock	0.054	4	8	0.14	141	<0.001	<20	0.70	0.005	0.15	<0.1	0.10	<0.1	<0.05	7.2	<0.5	1	<0.2
REP 1278315	QC																		
1278326	Rock	0.046	3	11	0.08	112	<0.001	<20	0.59	0.004	0.13	<0.1	0.66	<0.1	<0.05	7.4	0.6	1	<0.2
REP 1278326	QC	0.044	3	10	0.08	112	<0.001	<20	0.60	0.004	0.12	<0.1	0.63	0.1	<0.05	7.5	<0.5	1	<0.2
Core Reject Duplicates																			
1277180	Rock	0.047	20	8	0.01	433	<0.001	<20	0.39	0.003	0.18	<0.1	16.72	0.9	0.26	2.0	7.4	1	0.2
DUP 1277180	QC	0.044	20	7	0.01	429	<0.001	<20	0.38	0.003	0.18	<0.1	18.27	0.9	0.25	2.0	9.0	1	0.3
1093918	Rock	0.003	<1	1	0.09	74	<0.001	<20	0.05	0.003	0.02	<0.1	0.03	<0.1	<0.05	1.4	<0.5	<1	<0.2
DUP 1093918	QC	0.003	<1	4	0.11	77	<0.001	<20	0.06	0.003	0.02	<0.1	0.04	<0.1	<0.05	1.5	<0.5	<1	<0.2
1278355	Rock	0.120	12	19	0.01	459	0.002	<20	0.33	0.002	0.11	<0.1	6.54	2.4	0.12	1.5	7.8	1	<0.2
DUP 1278355	QC	0.113	12	18	0.01	434	0.002	<20	0.30	0.002	0.10	<0.1	6.47	2.6	0.12	1.6	6.7	1	0.2
Reference Materials																			
STD DS8	Standard	0.078	15	117	0.63	289	0.117	<20	0.94	0.093	0.41	2.4	0.17	5.2	0.15	2.4	4.1	5	4.8
STD DS8	Standard	0.070	13	101	0.55	276	0.099	<20	0.82	0.079	0.37	2.3	0.17	4.7	0.15	1.9	4.3	4	4.9
STD DS8	Standard	0.077	14	118	0.61	288	0.120	<20	0.90	0.085	0.41	2.8	0.18	5.2	0.16	2.0	4.8	5	4.8
STD OREAS45CA	Standard	0.038	16	771	0.16	162	0.155	<20	4.23	0.007	0.08	<0.1	<0.01	<0.1	<0.05	38.8	0.7	19	<0.2
STD OREAS45CA	Standard	0.034	16	689	0.14	145	0.136	<20	3.77	0.013	0.07	<0.1	0.07	<0.1	<0.05	35.6	1.1	16	<0.2
STD OREAS45CA	Standard	0.038	17	736	0.16	170	0.158	<20	3.88	0.008	0.07	<0.1	0.03	<0.1	<0.05	41.2	<0.5	20	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

QUALITY CONTROL REPORT WHI11001079.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
STD OXC88	Standard		194																		
STD OXC88	Standard		201																		
STD OXH82	Standard		1308																		
STD OXH82	Standard		1295																		
STD OXH82	Standard		1313																		
STD OXH82	Standard		1288																		
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank	<0.01	<2	0.2	2.3	3.6	43	<0.1	2.4	3.3	510	1.83	1.1	3.0	4.7	51	<0.1	<0.1	<0.1	32	0.39
G1	Prep Blank	<0.01	<2	0.1	2.0	2.5	42	<0.1	2.3	3.2	519	1.90	<0.5	1.6	4.9	55	<0.1	<0.1	<0.1	33	0.46

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

QUALITY CONTROL REPORT WHI11001079.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXC88 Expected																			
STD OXH82 Expected																			
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																			
G1	Prep Blank	0.068	10	5	0.45	150	0.100	<20	0.76	0.056	0.40	<0.1	0.04	0.2	<0.05	1.6	<0.5	4	<0.2
G1	Prep Blank	0.073	13	5	0.46	152	0.105	<20	0.77	0.064	0.40	0.4	0.05	0.3	<0.05	1.7	<0.5	4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 18, 2011
Report Date: January 19, 2012
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001237.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #14
P.O. Number
Number of Samples: 24

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	24	Crush, split and pulverize 250 g rock to 200 mesh			WHI
G603	24	Lead collection fire assay fusion - ICP-ES finish + 7AR Ag	30	Completed	VAN
1D02	24	1:1:1 Aqua Regia digestion ICP-ES analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: Sample ID Revisions - Samples 1093727 to 1093733 revised to 1093927 to 1093933

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001237.2

	Method	7AR	G6	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
	Analyte	Ag	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	gm/t	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	2	0.005	1	1	3	1	0.3	1	1	2	0.01	2	2	2	1	0.5	3	3	1	0.01
1093720	Rock	<2	<0.005	<1	7	4	36	<0.3	13	2	34	1.13	6	<2	<2	6	<0.5	<3	<3	9	0.02
1093721	Rock	<2	0.007	<1	10	3	91	<0.3	27	6	139	1.41	36	<2	<2	4	<0.5	<3	<3	6	0.01
1093722	Rock	<2	0.114	<1	<1	<3	2	<0.3	<1	<1	27	0.32	11	<2	<2	12	<0.5	<3	<3	1	<0.01
1093723	Rock	<2	<0.005	<1	1	<3	5	<0.3	2	<1	31	0.42	10	<2	<2	4	<0.5	<3	<3	1	<0.01
1093724	Rock	<2	<0.005	<1	3	<3	7	<0.3	3	<1	24	0.43	26	<2	<2	8	<0.5	<3	<3	2	<0.01
1093725	Rock	<2	0.100	<1	9	<3	64	<0.3	19	2	103	5.21	184	<2	<2	4	<0.5	<3	<3	2	<0.01
1093726	Rock	<2	0.010	<1	4	<3	17	<0.3	5	<1	24	0.81	56	<2	<2	4	<0.5	<3	<3	1	<0.01
1093927	Rock	<2	<0.005	<1	21	<3	103	<0.3	14	2	73	0.68	<2	<2	<2	10	<0.5	<3	<3	6	0.03
1093928	Rock	<2	<0.005	<1	<1	13	3	0.5	1	<1	23	0.33	6	<2	<2	12	<0.5	3	<3	6	<0.01
1093929	Rock	<2	<0.005	<1	50	5	49	<0.3	81	34	919	5.28	314	<2	<2	316	<0.5	11	<3	32	4.54
1093930	Rock	<2	<0.005	<1	42	4	42	<0.3	61	31	806	4.74	<2	<2	<2	319	<0.5	<3	<3	87	6.14
1093931	Rock	<2	<0.005	<1	24	<3	68	<0.3	9	4	441	1.28	103	<2	<2	26	<0.5	7	<3	4	0.52
1093932	Rock	<2	0.070	<1	46	<3	28	<0.3	57	27	960	4.27	3569	<2	<2	673	0.6	23	<3	15	6.98
1093933	Rock	<2	0.833	<1	1	<3	195	<0.3	16	6	788	1.85	492	<2	<2	116	1.1	29	<3	13	3.70
1279051	Rock	<2	<0.005	<1	14	6	202	<0.3	31	8	796	3.61	12	<2	<2	411	6.4	<3	<3	15	5.75
1279052	Rock	<2	<0.005	<1	19	10	164	<0.3	25	8	968	4.24	6	<2	<2	476	4.0	<3	<3	16	6.62
1279053	Rock	<2	0.020	<1	12	11	169	<0.3	24	8	1077	4.65	3	<2	2	523	5.6	<3	<3	13	8.42
1279054	Rock	<2	<0.005	<1	11	12	102	<0.3	18	5	960	4.64	<2	<2	<2	467	2.7	<3	5	15	8.12
1279055	Rock	<2	<0.005	<1	77	6	84	<0.3	51	35	1179	5.76	168	<2	<2	254	1.2	<3	<3	94	3.94
1279056	Rock	<2	<0.005	<1	68	<3	69	<0.3	76	36	982	5.58	22	<2	<2	164	0.7	<3	5	106	2.77
1279057	Rock	<2	<0.005	<1	25	6	59	<0.3	41	17	784	3.74	101	<2	<2	225	0.9	6	<3	14	4.93
1279058	Rock	<2	0.006	2	152	<3	94	<0.3	71	31	1002	4.52	102	<2	<2	454	1.2	7	<3	21	6.09
1279059	Rock	<2	<0.005	<1	6	<3	37	<0.3	30	10	1285	4.80	14	<2	<2	982	0.8	5	5	12	9.69
1279060	Rock	<2	<0.005	2	42	<3	68	<0.3	61	31	1342	5.66	178	<2	<2	206	1.1	8	<3	35	6.66

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001237.2

	Method	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5
1093720	Rock	0.010	1	9	0.07	335	<0.001	<20	0.32	<0.01	0.03	<2	<0.05	<1	<5	<5	<5
1093721	Rock	0.015	1	6	<0.01	231	<0.001	<20	0.11	<0.01	0.02	<2	<0.05	<1	<5	<5	<5
1093722	Rock	0.003	3	3	<0.01	64	<0.001	<20	0.07	<0.01	0.04	<2	<0.05	<1	<5	<5	<5
1093723	Rock	0.004	1	4	<0.01	46	<0.001	<20	0.07	<0.01	0.03	<2	<0.05	<1	<5	<5	<5
1093724	Rock	0.004	1	4	<0.01	51	<0.001	<20	0.08	<0.01	0.03	<2	<0.05	<1	<5	<5	<5
1093725	Rock	0.029	3	4	<0.01	127	<0.001	<20	0.12	<0.01	0.03	<2	<0.05	<1	<5	<5	<5
1093726	Rock	0.007	2	4	<0.01	147	<0.001	<20	0.11	<0.01	0.04	<2	<0.05	<1	<5	<5	<5
1093927	Rock	0.023	<1	3	<0.01	33	<0.001	<20	0.11	<0.01	0.02	<2	<0.05	<1	<5	<5	<5
1093928	Rock	0.009	<1	3	<0.01	105	<0.001	<20	0.10	<0.01	0.04	<2	<0.05	<1	<5	<5	<5
1093929	Rock	0.056	5	37	2.61	432	<0.001	<20	0.76	<0.01	0.27	<2	0.33	<1	<5	16	6
1093930	Rock	0.050	5	178	2.45	331	0.002	<20	2.76	0.01	0.24	<2	<0.05	<1	<5	17	10
1093931	Rock	0.002	<1	4	0.19	150	<0.001	<20	0.07	<0.01	0.04	<2	<0.05	<1	<5	<5	<5
1093932	Rock	0.044	3	18	3.09	187	<0.001	<20	0.45	<0.01	0.25	<2	1.41	<1	<5	16	<5
1093933	Rock	0.181	2	11	0.68	142	<0.001	<20	0.20	<0.01	0.09	<2	0.07	<1	<5	10	<5
1279051	Rock	0.019	8	9	2.94	961	<0.001	<20	0.43	<0.01	0.22	<2	<0.05	<1	<5	5	<5
1279052	Rock	0.017	9	8	3.45	852	<0.001	<20	0.35	<0.01	0.19	<2	0.14	<1	<5	6	<5
1279053	Rock	0.015	9	9	4.42	710	<0.001	<20	0.31	0.01	0.15	<2	0.06	<1	<5	<5	<5
1279054	Rock	0.018	11	11	4.39	852	0.001	<20	0.32	0.01	0.17	<2	<0.05	<1	<5	<5	<5
1279055	Rock	0.073	6	158	2.92	910	0.014	<20	2.78	0.04	0.21	<2	0.12	<1	<5	26	9
1279056	Rock	0.056	5	131	3.61	441	0.085	<20	3.74	<0.01	0.16	<2	<0.05	<1	<5	18	11
1279057	Rock	0.030	3	19	1.50	318	<0.001	<20	0.39	<0.01	0.20	<2	<0.05	<1	<5	10	<5
1279058	Rock	0.052	5	23	2.57	444	<0.001	<20	0.49	<0.01	0.27	<2	0.06	<1	<5	13	<5
1279059	Rock	0.005	3	2	5.05	267	<0.001	<20	0.07	<0.01	0.03	<2	<0.05	<1	<5	<5	<5
1279060	Rock	0.049	4	27	2.04	515	<0.001	<20	0.43	<0.01	0.23	<2	<0.05	<1	<5	20	<5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001237.2

	Method	7AR	G6	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
	Analyte	Ag	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	gm/t	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	2	0.005	1	1	3	1	0.3	1	1	2	0.01	2	2	2	1	0.5	3	3	1	0.01
Pulp Duplicates																					
1093722	Rock	<2	0.114	<1	<1	<3	2	<0.3	<1	<1	27	0.32	11	<2	<2	12	<0.5	<3	<3	1	<0.01
REP 1093722	QC	<2																			
1279053	Rock	<2	0.020	<1	12	11	169	<0.3	24	8	1077	4.65	3	<2	2	523	5.6	<3	<3	13	8.42
REP 1279053	QC		0.005																		
Reference Materials																					
STD DS8	Standard			13	104	123	318	1.6	36	7	599	2.41	27	<2	7	64	2.1	6	7	39	0.69
STD DS8	Standard			13	100	118	305	1.4	36	6	583	2.36	25	<2	6	63	2.4	5	7	39	0.68
STD OREAS153AR	Standard	<2																			
STD OREAS131B-A	Standard	34																			
STD OREAS45CA	Standard			1	511	15	58	<0.3	248	90	923	15.69	3	3	6	15	<0.5	<3	<3	206	0.43
STD OREAS45CA	Standard			3	491	18	54	<0.3	243	87	875	16.04	<2	<2	6	15	<0.5	<3	<3	198	0.41
STD OXH82	Standard		1.293																		
STD OXH82	Standard		1.300																		
STD OXH82	Standard		1.297																		
STD OXK79	Standard		3.514																		
STD OXK79	Standard		3.823																		
STD OXK79	Standard		3.630																		
STD OREAS131B-A		33.3																			
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	0.107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	0.043	7	15	0.1	0.13	0.19	215	0.4265
STD OXH82 Expected			1.278																		
STD OXK79 Expected			3.532																		
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank			<1	<1	<3	<1	<0.3	<1	<1	<2	<0.01	<2	<2	<2	<1	<0.5	<3	<3	<1	<0.01
BLK	Blank	<2																			

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001237.2

		Method	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
		Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga
		Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm
		MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5
Pulp Duplicates																		
1093722	Rock		0.003	3	3	<0.01	64	<0.001	<20	0.07	<0.01	0.04	<2	<0.05	<1	<5	<5	<5
REP 1093722	QC																	
1279053	Rock		0.015	9	9	4.42	710	<0.001	<20	0.31	0.01	0.15	<2	0.06	<1	<5	<5	<5
REP 1279053	QC																	
Reference Materials																		
STD DS8	Standard		0.078	13	109	0.60	287	0.103	<20	0.88	0.08	0.41	2	0.16	<1	<5	<5	<5
STD DS8	Standard		0.074	14	109	0.58	280	0.102	<20	0.87	0.09	0.40	<2	0.16	<1	5	<5	<5
STD OREAS153AR	Standard																	
STD OREAS131B-A	Standard																	
STD OREAS45CA	Standard		0.037	16	719	0.13	160	0.119	<20	3.60	<0.01	0.07	<2	<0.05	<1	<5	46	11
STD OREAS45CA	Standard		0.037	15	702	0.13	155	0.119	<20	3.70	<0.01	0.07	<2	<0.05	<1	<5	45	<5
STD OXH82	Standard																	
STD OXH82	Standard																	
STD OXH82	Standard																	
STD OXK79	Standard																	
STD OXK79	Standard																	
STD OXK79	Standard																	
STD OREAS131B-A																		
STD DS8 Expected			0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.1679	0.192	5.4	2.3	4.7
STD OREAS45CA Expected			0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.021	0.03	0.07		
STD OXH82 Expected																		
STD OXK79 Expected																		
BLK	Blank																	
BLK	Blank																	
BLK	Blank																	
BLK	Blank																	
BLK	Blank		<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5
BLK	Blank																	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001237.2

		7AR Ag gm/t 2	G6 Au gm/t 0.005	1D Mo ppm 1	1D Cu ppm 1	1D Pb ppm 3	1D Zn ppm 1	1D Ag ppm 0.3	1D Ni ppm 1	1D Co ppm 1	1D Mn ppm 2	1D Fe % 0.01	1D As ppm 2	1D Au ppm 2	1D Th ppm 2	1D Sr ppm 1	1D Cd ppm 0.5	1D Sb ppm 3	1D Bi ppm 3	1D V ppm 1	1D Ca % 0.01
BLK	Blank			<1	<1	<3	<1	<0.3	<1	<1	<2	<0.01	<2	<2	<2	<1	<0.5	<3	<3	<1	<0.01
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
Prep Wash																					
G1	Prep Blank	<2	0.007	<1	1	<3	46	<0.3	2	4	542	2.00	<2	<2	5	69	<0.5	<3	<3	36	0.51
G1	Prep Blank	<2	<0.005	<1	<1	<3	43	<0.3	2	3	516	1.81	<2	<2	5	57	<0.5	<3	<3	34	0.46

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001237.2

		1D P % 0.001	1D La ppm 1	1D Cr ppm 1	1D Mg % 0.01	1D Ba ppm 1	1D Ti % 0.001	1D B ppm 20	1D Al % 0.01	1D Na % 0.01	1D K % 0.01	1D W ppm 2	1D S % 0.05	1D Hg ppm 1	1D Tl ppm 5	1D Sc ppm 5	1D Ga ppm 5
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5
BLK	Blank																
BLK	Blank																
Prep Wash																	
G1	Prep Blank	0.069	13	5	0.48	161	0.117	<20	0.93	0.10	0.48	<2	<0.05	<1	<5	<5	<5
G1	Prep Blank	0.067	11	4	0.45	147	0.107	<20	0.82	0.07	0.43	<2	<0.05	<1	<5	<5	<5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 25, 2011
Report Date: October 18, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11001281.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #16
P.O. Number
Number of Samples: 43

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-500	43	Crush, split and pulverize 500 g rock to 200 mesh			WHI
3B	43	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	43	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 18, 2011

CERTIFICATE OF ANALYSIS WHI11001281.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1278332	Rock	5.91	3	1.3	27.9	13.1	98	<0.1	11.4	3.0	213	3.98	120.2	0.6	8.5	15	0.5	2.5	0.6	39	0.01
1278333	Rock	5.70	<2	1.4	31.2	13.7	99	0.1	12.5	3.2	189	4.31	134.1	<0.5	9.1	16	0.4	2.7	0.6	43	0.01
1278334	Rock	6.44	3	1.5	27.8	11.7	84	0.1	10.1	2.6	167	3.70	95.6	1.0	9.1	13	0.4	2.6	0.6	38	0.02
1278335	Rock	6.39	<2	5.5	39.0	18.1	79	1.3	19.6	2.8	61	1.81	57.3	<0.5	2.7	44	0.4	5.3	0.2	75	0.16
1278336	Rock	5.60	6	15.5	68.4	25.9	96	3.2	31.1	3.3	38	2.48	80.4	<0.5	3.2	37	0.3	9.0	0.3	88	0.10
1278337	Rock	5.64	14	8.0	89.0	24.7	785	2.8	73.3	25.1	173	6.10	225.1	<0.5	2.8	55	0.5	12.6	0.2	57	0.01
1278338	Rock	6.13	10	8.4	31.5	20.5	124	2.3	16.7	2.3	27	1.55	71.2	<0.5	2.4	58	0.4	9.2	0.2	112	0.03
1278339	Rock	7.34	9	5.2	50.2	12.7	132	1.9	20.9	2.9	41	1.72	80.5	<0.5	2.2	112	0.4	8.9	0.1	112	0.12
1278340	Rock	5.56	33	2.9	40.3	13.8	24	3.2	8.3	0.5	24	1.30	43.9	<0.5	2.5	78	0.4	6.4	0.1	123	0.33
1278441	Rock	6.43	112	4.1	48.9	14.4	121	3.3	19.7	1.6	39	2.18	97.5	<0.5	2.6	98	0.6	15.9	0.1	103	0.21
1278442	Rock	6.58	112	3.5	216.6	13.1	659	3.1	88.8	29.0	357	4.41	128.4	1.1	2.4	222	8.5	16.0	0.1	188	5.61
1278443	Rock	6.27	91	3.8	94.2	14.5	371	3.8	59.7	13.8	177	3.15	88.3	1.3	2.7	138	2.4	9.1	0.1	150	1.02
1278444	Rock	6.12	62	3.7	54.5	14.4	106	4.0	20.2	3.3	59	1.85	53.1	1.7	2.8	92	0.9	7.2	0.1	116	0.38
1278445	Rock	5.85	48	3.6	48.0	14.5	94	3.9	20.1	3.1	66	1.69	43.9	0.8	2.7	70	0.8	5.7	0.1	105	0.35
1278446	Rock	6.18	127	3.7	47.9	15.2	116	3.6	23.5	3.6	77	1.75	49.5	2.8	2.7	83	1.0	6.7	0.1	102	0.55
1278447	Rock	6.85	66	3.0	41.0	11.6	40	3.0	9.4	0.9	33	1.34	41.8	2.2	2.3	68	0.6	4.9	0.1	107	0.37
1278448	Rock	5.94	54	3.5	45.2	14.4	51	3.7	12.3	1.4	40	1.68	47.3	5.7	2.8	76	0.7	6.3	0.2	82	0.42
1278449	Rock	6.34	39	2.5	43.6	11.0	82	2.4	21.9	2.8	53	1.64	55.5	4.6	2.1	77	0.5	5.5	0.1	70	0.32
1278450	Rock	6.33	16	1.9	42.0	12.9	207	0.9	38.5	9.8	205	3.47	96.2	2.7	2.4	71	0.5	4.2	0.2	36	0.05
1279151	Rock	5.36	5	1.4	50.0	10.2	427	0.1	77.3	25.0	755	7.07	137.2	0.8	1.9	25	1.7	2.7	0.3	31	0.04
1279152	Rock	5.32	10	1.4	36.6	16.3	262	0.2	50.2	16.0	230	4.18	115.0	1.1	1.8	21	0.3	3.7	0.3	21	<0.01
1279153	Rock	5.90	7	1.6	31.4	13.1	279	0.2	44.6	13.0	191	3.79	123.6	1.6	2.0	37	0.4	3.8	0.3	21	0.02
1279154	Rock	5.68	6	5.8	51.0	14.1	342	0.3	63.4	21.0	336	4.44	100.7	0.7	2.1	43	2.1	4.2	0.3	73	0.04
1279155	Rock	5.07	5	4.9	46.5	23.0	363	0.2	63.4	21.2	508	4.69	57.9	0.9	1.8	29	2.7	2.8	0.3	58	0.06
1279156	Rock	5.66	4	3.0	41.3	16.2	454	0.1	61.3	19.3	386	5.01	51.2	0.6	1.7	25	1.5	1.5	0.3	39	0.04
1279157	Rock	5.64	3	2.6	48.0	23.5	282	0.1	51.4	14.2	292	4.73	39.8	<0.5	1.6	21	1.0	1.0	0.4	26	0.06
1279158	Rock	5.15	2	2.3	48.6	25.2	267	<0.1	58.5	16.2	375	4.80	49.3	0.7	1.8	25	1.7	1.1	0.4	22	0.05
1279159	Rock	5.29	2	1.9	45.2	19.5	210	<0.1	51.2	14.8	338	4.24	32.7	<0.5	1.5	19	1.4	1.0	0.3	21	0.03
1279160	Rock	5.24	3	2.2	37.8	16.8	278	<0.1	48.5	14.1	254	4.31	39.1	0.7	1.4	19	0.8	1.3	0.3	26	0.02
1279161	Rock	7.76	3	1.9	35.0	14.6	262	0.1	47.1	13.2	269	4.05	37.2	1.7	1.3	21	0.8	1.5	0.3	24	0.04

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 18, 2011

CERTIFICATE OF ANALYSIS WHI11001281.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1278332	Rock	0.056	31	27	0.81	159	0.005	<20	1.86	0.007	0.26	<0.1	1.23	0.2	0.13	3.4	0.9	5	<0.2
1278333	Rock	0.063	31	27	0.74	176	0.007	<20	1.95	0.009	0.34	<0.1	0.74	0.3	0.14	3.8	1.7	5	0.2
1278334	Rock	0.055	33	23	0.70	136	0.006	<20	1.79	0.007	0.28	<0.1	0.61	0.3	0.08	3.4	1.3	4	<0.2
1278335	Rock	0.174	14	13	0.10	2065	0.003	<20	0.72	0.004	0.11	<0.1	1.97	0.2	0.10	2.0	8.3	2	<0.2
1278336	Rock	0.161	13	13	0.04	1244	0.002	<20	0.96	0.003	0.11	0.1	2.01	0.5	0.09	2.7	15.5	2	<0.2
1278337	Rock	0.113	6	12	0.01	470	<0.001	<20	0.91	0.002	0.04	0.2	5.47	0.4	0.15	4.2	9.3	1	<0.2
1278338	Rock	0.202	8	14	0.01	2072	0.002	<20	0.50	0.003	0.11	<0.1	4.68	0.3	0.11	3.6	17.8	2	<0.2
1278339	Rock	0.301	7	15	0.01	2199	0.002	<20	0.50	0.004	0.09	0.1	4.53	0.2	0.11	2.6	13.1	1	<0.2
1278340	Rock	0.430	8	27	0.02	1649	0.003	<20	0.58	0.006	0.16	<0.1	6.47	0.2	0.15	3.1	7.6	2	<0.2
1278441	Rock	0.520	7	26	0.01	1351	0.003	<20	0.46	0.003	0.12	0.4	12.98	0.2	0.19	5.8	15.2	2	<0.2
1278442	Rock	0.544	6	27	0.05	2390	0.003	<20	0.79	0.005	0.13	0.2	10.57	0.2	0.17	5.3	9.8	2	0.2
1278443	Rock	0.461	8	29	0.02	1815	0.003	<20	0.61	0.005	0.17	0.2	7.92	0.2	0.18	4.2	9.9	2	<0.2
1278444	Rock	0.523	10	33	0.02	1970	0.003	<20	0.57	0.005	0.17	0.1	6.13	0.2	0.12	3.7	8.1	2	<0.2
1278445	Rock	0.465	11	35	0.02	1644	0.003	<20	0.57	0.006	0.18	0.1	4.44	0.2	0.12	3.5	8.4	2	<0.2
1278446	Rock	0.472	10	35	0.02	2423	0.003	<20	0.56	0.005	0.16	0.1	4.08	0.2	0.10	3.3	6.9	2	<0.2
1278447	Rock	0.475	9	29	0.02	1752	0.003	<20	0.55	0.006	0.16	<0.1	3.21	0.2	0.10	3.1	6.8	2	<0.2
1278448	Rock	0.579	11	28	0.01	1480	0.003	<20	0.48	0.003	0.15	0.1	3.02	0.2	0.14	3.1	6.6	2	<0.2
1278449	Rock	0.391	10	22	0.02	1533	0.002	<20	0.45	0.002	0.13	<0.1	1.95	0.1	0.09	3.4	6.2	1	<0.2
1278450	Rock	0.150	7	15	0.02	1512	<0.001	<20	0.41	0.003	0.12	<0.1	1.19	0.2	0.10	5.4	3.1	1	<0.2
1279151	Rock	0.094	4	14	0.05	552	<0.001	<20	0.60	0.005	0.16	<0.1	0.22	0.2	<0.05	9.1	1.0	1	<0.2
1279152	Rock	0.050	3	10	0.02	421	<0.001	<20	0.48	0.004	0.14	<0.1	0.20	0.2	<0.05	3.8	1.6	<1	<0.2
1279153	Rock	0.047	5	8	0.02	486	<0.001	<20	0.42	0.004	0.13	<0.1	0.22	0.2	<0.05	4.0	1.4	<1	<0.2
1279154	Rock	0.059	5	13	0.03	901	<0.001	<20	0.52	0.005	0.15	<0.1	1.19	0.3	0.06	5.8	2.3	1	<0.2
1279155	Rock	0.055	4	12	0.04	523	<0.001	<20	0.47	0.004	0.13	<0.1	0.99	0.2	<0.05	6.1	1.8	<1	<0.2
1279156	Rock	0.055	3	13	0.03	540	<0.001	<20	0.49	0.006	0.14	<0.1	0.42	0.2	<0.05	5.6	1.6	<1	<0.2
1279157	Rock	0.053	3	10	0.03	746	<0.001	<20	0.43	0.006	0.13	<0.1	0.24	0.2	<0.05	5.7	1.0	<1	<0.2
1279158	Rock	0.050	3	11	0.03	737	<0.001	<20	0.52	0.007	0.16	<0.1	0.14	0.3	0.05	6.3	0.7	<1	<0.2
1279159	Rock	0.046	3	11	0.03	423	<0.001	<20	0.40	0.005	0.12	<0.1	0.12	0.2	<0.05	5.3	0.7	<1	<0.2
1279160	Rock	0.050	3	11	0.03	547	<0.001	<20	0.50	0.006	0.14	<0.1	0.20	0.2	<0.05	4.7	0.9	1	<0.2
1279161	Rock	0.049	3	10	0.03	636	<0.001	<20	0.46	0.005	0.13	<0.1	0.19	0.1	<0.05	4.6	0.8	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 18, 2011

CERTIFICATE OF ANALYSIS WHI11001281.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1279162	Rock	5.47	6	1.9	38.0	16.1	275	<0.1	51.8	13.9	302	4.32	32.8	0.9	1.3	20	1.1	1.1	0.3	23	0.05
1279163	Rock	5.00	4	2.1	41.4	14.8	243	<0.1	50.4	14.1	344	4.48	69.1	1.4	1.7	29	1.5	1.1	0.3	23	0.05
1279164	Rock	5.48	4	2.6	33.3	17.3	191	<0.1	38.3	9.8	205	3.78	43.2	1.7	1.0	23	1.1	1.4	0.3	26	0.04
1279165	Rock	6.19	25	4.8	13.8	15.3	148	0.2	18.7	5.1	53	2.41	73.0	2.6	1.7	60	0.4	5.6	0.2	37	0.01
1279166	Rock	5.48	36	4.1	16.8	14.7	139	0.4	23.6	5.2	44	2.60	82.2	2.0	2.0	81	0.4	7.3	0.2	46	<0.01
1279167	Rock	4.68	35	5.6	11.6	13.6	276	0.2	31.5	6.3	64	2.48	85.7	1.1	2.0	65	0.3	5.0	0.2	40	<0.01
1279168	Rock	5.96	28	3.8	17.9	15.7	197	0.4	25.6	6.5	66	3.27	79.7	1.3	2.2	60	0.4	5.4	0.3	35	<0.01
1279169	Rock	4.85	29	3.1	12.3	16.2	104	0.5	17.8	4.3	45	2.31	51.5	<0.5	1.9	30	0.1	3.9	0.2	28	<0.01
1279170	Rock	6.88	9	4.7	10.1	16.0	59	2.3	12.2	1.8	23	1.86	51.1	0.9	2.2	49	0.2	3.5	0.2	29	0.06
1279171	Rock	6.67	13	4.9	31.3	15.1	124	2.3	27.8	2.9	44	2.14	59.2	0.7	2.2	174	0.7	8.7	0.2	131	0.49
1279172	Rock	6.46	13	4.6	33.6	16.5	122	2.9	26.1	2.8	38	2.10	53.6	<0.5	2.6	202	0.8	9.5	0.2	146	0.78
1279173	Rock	6.23	10	4.5	25.4	14.8	94	2.1	19.2	2.3	52	2.18	38.7	1.3	2.1	141	0.4	5.9	0.2	79	0.30
1279174	Rock	6.31	18	4.9	43.1	15.6	189	2.6	29.2	3.6	61	2.56	53.0	0.9	2.8	219	0.7	8.5	0.2	121	0.62

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 18, 2011

CERTIFICATE OF ANALYSIS WHI11001281.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1279162	Rock	0.045	3	10	0.03	553	<0.001	<20	0.45	0.006	0.13	<0.1	0.13	0.1	<0.05	5.0	0.8	<1	<0.2
1279163	Rock	0.047	4	10	0.03	485	<0.001	<20	0.49	0.006	0.14	<0.1	0.44	0.2	<0.05	5.3	1.1	<1	<0.2
1279164	Rock	0.051	3	10	0.03	536	<0.001	<20	0.46	0.005	0.13	<0.1	0.39	0.2	<0.05	3.9	0.7	1	<0.2
1279165	Rock	0.046	4	8	0.01	2712	<0.001	<20	0.40	0.005	0.14	<0.1	8.96	0.3	0.17	2.1	3.4	1	<0.2
1279166	Rock	0.072	5	10	<0.01	2408	<0.001	<20	0.43	0.005	0.14	<0.1	13.96	0.6	0.18	3.3	3.9	1	<0.2
1279167	Rock	0.049	4	9	<0.01	2137	<0.001	<20	0.43	0.005	0.14	<0.1	15.09	0.4	0.17	2.7	4.4	1	<0.2
1279168	Rock	0.068	4	11	<0.01	2275	<0.001	<20	0.42	0.003	0.13	<0.1	12.16	0.4	0.17	3.6	4.3	1	<0.2
1279169	Rock	0.034	3	10	0.01	1795	<0.001	<20	0.40	0.006	0.19	<0.1	9.51	0.5	0.24	2.4	4.2	1	<0.2
1279170	Rock	0.092	5	7	0.01	429	<0.001	<20	0.43	0.006	0.21	<0.1	3.64	0.7	0.35	1.8	5.2	1	<0.2
1279171	Rock	0.503	6	21	0.02	1439	0.003	23	0.84	0.003	0.21	<0.1	3.42	0.3	0.19	3.4	16.9	2	<0.2
1279172	Rock	0.728	5	25	0.02	2457	0.004	28	0.71	0.003	0.22	0.1	3.84	0.2	0.18	4.2	18.7	2	<0.2
1279173	Rock	0.419	4	16	0.02	1654	0.003	25	0.52	0.005	0.22	<0.1	2.26	0.3	0.26	3.5	16.8	2	<0.2
1279174	Rock	0.712	7	20	0.02	3018	0.003	21	0.68	0.003	0.18	<0.1	3.68	0.3	0.15	4.8	22.1	2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 18, 2011

QUALITY CONTROL REPORT WHI11001281.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1279153	Rock	5.90	7	1.6	31.4	13.1	279	0.2	44.6	13.0	191	3.79	123.6	1.6	2.0	37	0.4	3.8	0.3	21	0.02
REP 1279153	QC		6																		
1279170	Rock	6.88	9	4.7	10.1	16.0	59	2.3	12.2	1.8	23	1.86	51.1	0.9	2.2	49	0.2	3.5	0.2	29	0.06
REP 1279170	QC			4.9	10.3	16.0	62	2.3	12.7	1.9	23	1.93	53.2	0.7	2.3	49	0.2	3.5	0.2	30	0.06
Core Reject Duplicates																					
1279160	Rock	5.24	3	2.2	37.8	16.8	278	<0.1	48.5	14.1	254	4.31	39.1	0.7	1.4	19	0.8	1.3	0.3	26	0.02
DUP 1279160	QC		4	2.3	37.1	16.6	268	<0.1	48.1	13.7	250	4.24	38.9	0.9	1.4	19	1.0	1.4	0.3	25	0.02
Reference Materials																					
STD DS8	Standard			12.7	114.9	125.1	323	2.0	38.1	7.9	609	2.51	27.4	154.5	6.5	63	2.6	5.1	7.2	40	0.68
STD DS8	Standard			15.5	106.7	130.4	326	2.1	37.5	7.6	635	2.50	26.1	108.1	7.0	69	2.5	3.4	6.5	43	0.72
STD DS8	Standard			13.7	117.0	125.5	320	1.9	38.6	8.2	614	2.61	26.9	107.9	6.9	64	2.6	4.4	6.4	44	0.77
STD OREAS45CA	Standard			0.8	500.4	21.7	62	0.3	243.0	90.6	928	15.72	4.1	39.4	7.5	17	0.1	0.1	0.2	205	0.44
STD OREAS45CA	Standard			0.8	533.6	20.9	61	0.3	250.0	86.3	909	15.28	3.9	42.6	7.3	16	0.1	<0.1	0.2	200	0.43
STD OREAS45CA	Standard			0.8	408.2	21.1	55	0.3	206.7	80.8	804	16.08	3.1	32.4	6.1	13	<0.1	0.1	0.2	200	0.38
STD OXC88	Standard		212																		
STD OXC88	Standard		209																		
STD OXC88	Standard		193																		
STD OXC88	Standard		186																		
STD OXC88	Standard		188																		
STD OXH82	Standard		1299																		
STD OXH82	Standard		1313																		
STD OXH82	Standard		1257																		
STD OXH82	Standard		1301																		
STD OXH82	Standard		1248																		
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 18, 2011

QUALITY CONTROL REPORT WHI11001281.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1279153	Rock	0.047	5	8	0.02	486	<0.001	<20	0.42	0.004	0.13	<0.1	0.22	0.2	<0.05	4.0	1.4	<1	<0.2
REP 1279153	QC																		
1279170	Rock	0.092	5	7	0.01	429	<0.001	<20	0.43	0.006	0.21	<0.1	3.64	0.7	0.35	1.8	5.2	1	<0.2
REP 1279170	QC	0.096	5	8	0.01	366	<0.001	<20	0.44	0.006	0.21	<0.1	3.71	0.7	0.35	1.7	5.0	1	<0.2
Core Reject Duplicates																			
1279160	Rock	0.050	3	11	0.03	547	<0.001	<20	0.50	0.006	0.14	<0.1	0.20	0.2	<0.05	4.7	0.9	1	<0.2
DUP 1279160	QC	0.047	3	10	0.03	535	<0.001	<20	0.47	0.006	0.14	<0.1	0.27	0.2	<0.05	4.6	0.8	1	<0.2
Reference Materials																			
STD DS8	Standard	0.087	13	114	0.61	306	0.103	<20	0.87	0.085	0.42	3.0	0.19	5.6	0.17	2.2	5.2	5	5.4
STD DS8	Standard	0.083	16	120	0.63	312	0.106	<20	0.93	0.092	0.42	1.9	0.19	5.7	0.17	2.2	5.5	5	5.4
STD DS8	Standard	0.080	16	121	0.64	286	0.120	<20	0.99	0.090	0.44	2.9	0.15	5.4	0.15	2.1	5.2	5	5.1
STD OREAS45CA	Standard	0.041	19	700	0.14	172	0.121	<20	3.59	0.006	0.07	<0.1	0.07	<0.1	<0.05	37.4	<0.5	18	<0.2
STD OREAS45CA	Standard	0.039	16	727	0.15	168	0.117	<20	4.07	0.014	0.08	<0.1	0.03	<0.1	<0.05	36.7	1.0	19	<0.2
STD OREAS45CA	Standard	0.033	15	636	0.13	145	0.127	<20	3.72	0.012	0.05	<0.1	0.05	<0.1	<0.05	33.9	0.5	16	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXC88 Expected																			
STD OXH82 Expected																			
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 18, 2011

QUALITY CONTROL REPORT WHI11001281.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		<2	0.1	2.5	3.1	45	<0.1	2.4	3.8	577	2.12	0.7	1.4	5.7	65	<0.1	<0.1	<0.1	40	0.54
G1	Prep Blank		<2	<0.1	2.1	2.8	45	<0.1	2.6	3.8	555	2.05	<0.5	<0.5	5.8	62	<0.1	<0.1	<0.1	38	0.52

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 18, 2011

QUALITY CONTROL REPORT WHI11001281.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																			
G1	Prep Blank	0.074	15	4	0.52	160	0.120	<20	0.93	0.090	0.47	<0.1	<0.01	0.3	<0.05	2.0	<0.5	5	<0.2
G1	Prep Blank	0.076	14	5	0.50	155	0.115	<20	0.90	0.073	0.44	<0.1	<0.01	0.3	<0.05	1.9	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 27, 2011
Report Date: October 14, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001490.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #19
P.O. Number
Number of Samples: 18

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-500	18	Crush, split and pulverize 500 g rock to 200 mesh			VAN
3B	18	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	18	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 14, 2011

CERTIFICATE OF ANALYSIS WHI11001490.1

	Method	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1279186	Rock	6	20.1	15.9	27.3	4	0.6	6.9	0.1	33	0.87	20.2	<0.5	1.9	196	<0.1	9.3	<0.1	143	0.04	0.083
1279187	Rock	4	34.1	13.8	35.2	4	1.0	9.5	0.2	29	1.03	35.4	<0.5	2.7	154	<0.1	13.2	0.1	199	0.02	0.078
1279188	Rock	4	23.7	15.6	33.1	8	1.3	12.6	0.3	43	1.04	26.4	<0.5	2.2	241	0.2	14.9	0.1	417	0.05	0.106
1279189	Rock	4	20.4	15.9	25.5	4	1.0	13.0	0.2	45	0.90	19.8	<0.5	1.3	66	0.1	12.4	<0.1	405	0.01	0.035
1279190	Rock	19	22.6	13.9	35.0	6	1.1	15.0	0.3	42	0.94	36.4	<0.5	1.9	90	0.1	13.7	<0.1	616	0.02	0.069
1279191	Rock	19	22.9	15.0	30.9	10	1.4	7.6	0.3	40	1.11	37.3	<0.5	1.4	162	0.2	12.8	0.1	421	0.04	0.139
1279192	Rock	18	20.8	16.4	34.6	6	1.2	10.3	0.2	33	0.82	30.0	<0.5	1.9	105	0.2	10.8	<0.1	634	0.02	0.094
1279193	Rock	11	25.4	15.7	35.5	5	0.9	11.1	0.2	39	0.84	28.6	<0.5	1.7	90	0.1	10.6	<0.1	522	0.02	0.075
1279194	Rock	14	13.9	12.0	17.0	17	1.1	4.6	0.4	30	1.12	48.2	1.2	2.0	264	0.1	10.8	0.2	177	0.06	0.174
1279195	Rock	11	15.4	12.3	18.2	17	1.1	5.6	0.4	33	1.03	40.1	<0.5	1.9	179	0.1	10.2	0.1	177	0.04	0.141
1279196	Rock	14	19.2	13.4	18.1	15	0.8	6.7	0.5	41	1.00	33.0	<0.5	1.3	123	0.1	8.8	0.1	220	0.02	0.105
1279197	Rock	10	21.3	11.9	20.2	15	0.9	7.4	0.5	51	1.01	29.4	<0.5	0.8	98	<0.1	9.3	0.1	225	0.02	0.081
1279198	Rock	15	14.0	21.6	18.8	102	0.7	14.7	2.5	59	1.73	57.4	1.6	2.2	102	0.2	6.9	0.2	141	0.02	0.098
1279199	Rock	2	5.1	8.9	28.1	48	0.4	3.4	0.4	16	1.44	23.0	<0.5	5.2	17	<0.1	4.5	0.3	48	<0.01	0.035
1279200	Rock	<2	8.8	20.3	33.7	360	0.4	17.4	2.9	34	3.18	96.3	<0.5	5.7	46	0.2	8.6	0.3	117	<0.01	0.120
1279203	Rock	3	5.6	8.4	31.1	6	0.5	1.0	0.2	16	2.20	44.8	0.6	5.7	21	<0.1	3.7	0.3	38	<0.01	0.089
1279205	Rock	2	4.2	5.3	30.9	23	0.5	1.5	0.3	14	1.40	24.5	<0.5	4.5	18	<0.1	4.1	0.2	30	<0.01	0.034
1279206	Rock	<2	3.7	6.4	31.7	5	0.5	0.9	0.2	11	1.82	42.0	<0.5	5.2	20	<0.1	4.0	0.3	34	<0.01	0.072

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 14, 2011

CERTIFICATE OF ANALYSIS WHI11001490.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1279186	Rock	5	7	0.02	515	0.001	<20	0.34	0.002	0.19	0.3	0.76	0.6	0.24	1.9	7.2	1	<0.2
1279187	Rock	5	13	0.02	526	0.002	<20	0.37	0.003	0.23	0.3	1.08	0.8	0.28	2.7	13.4	1	<0.2
1279188	Rock	11	29	0.03	890	0.002	<20	0.52	0.002	0.21	0.3	1.96	0.5	0.24	1.9	12.7	2	0.2
1279189	Rock	6	17	0.02	1123	0.002	<20	0.27	<0.001	0.15	0.3	1.53	0.4	0.20	1.2	11.6	1	<0.2
1279190	Rock	9	31	0.03	1226	0.003	<20	0.45	0.002	0.20	0.2	2.70	0.5	0.21	2.0	12.0	2	<0.2
1279191	Rock	8	22	0.02	1131	0.002	<20	0.47	<0.001	0.18	0.3	2.27	0.9	0.20	1.7	9.5	2	0.2
1279192	Rock	10	26	0.03	1196	0.003	<20	0.53	0.001	0.19	0.2	2.60	0.7	0.16	1.9	8.6	2	<0.2
1279193	Rock	9	23	0.02	1089	0.003	<20	0.40	<0.001	0.16	0.2	1.58	0.8	0.17	1.8	7.5	2	<0.2
1279194	Rock	10	20	0.02	467	0.005	<20	0.53	0.002	0.16	0.2	1.47	0.9	0.18	1.9	6.9	2	<0.2
1279195	Rock	9	15	0.02	837	0.003	<20	0.40	0.001	0.15	0.2	1.07	0.7	0.18	1.9	6.1	1	<0.2
1279196	Rock	7	18	0.02	1003	0.002	<20	0.37	0.002	0.15	0.2	1.09	0.6	0.17	1.5	6.8	1	<0.2
1279197	Rock	7	25	0.02	1469	0.002	<20	0.33	0.001	0.12	0.2	1.33	0.5	0.15	1.0	8.3	1	<0.2
1279198	Rock	8	14	0.03	716	0.001	<20	0.47	0.002	0.22	<0.1	1.47	0.7	0.20	1.7	6.8	2	<0.2
1279199	Rock	10	11	0.02	365	0.001	<20	0.38	0.002	0.32	<0.1	1.33	0.8	0.39	1.4	2.8	2	<0.2
1279200	Rock	9	16	0.04	437	0.001	<20	0.62	0.003	0.41	<0.1	0.69	1.2	0.45	2.4	8.5	3	<0.2
1279203	Rock	9	11	0.03	309	0.002	<20	0.36	0.003	0.44	<0.1	1.20	0.9	0.72	1.4	3.1	2	<0.2
1279205	Rock	10	8	0.03	335	0.001	<20	0.35	0.003	0.34	<0.1	1.20	0.6	0.45	0.9	3.1	2	<0.2
1279206	Rock	9	10	0.03	320	0.001	<20	0.36	0.003	0.42	<0.1	1.30	0.8	0.61	1.8	3.6	2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 14, 2011

QUALITY CONTROL REPORT WHI11001490.1

	Method	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1279200	Rock	<2	8.8	20.3	33.7	360	0.4	17.4	2.9	34	3.18	96.3	<0.5	5.7	46	0.2	8.6	0.3	117	<0.01	0.120
REP 1279200	QC	2																			
Reference Materials																					
STD DS8	Standard		12.9	105.4	122.8	298	1.6	37.9	7.7	590	2.43	24.5	94.2	6.5	63	2.4	4.3	6.5	42	0.71	0.082
STD OREAS45CA	Standard		0.8	514.9	21.9	61	0.2	258.9	89.2	922	15.85	3.6	43.8	7.2	15	0.1	<0.1	0.2	205	0.41	0.040
STD OXC88	Standard	209																			
STD OXC88	Standard	193																			
STD OXH82	Standard	1340																			
STD OXH82	Standard	1257																			
STD OXC88 Expected		203																			
STD OXH82 Expected		1278																			
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08
STD OREAS45CA Expected			1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385
BLK	Blank	<2																			
BLK	Blank	<2																			
BLK	Blank	<2																			
BLK	Blank	<2																			
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
Prep Wash																					
G1	Prep Blank	<2	0.1	2.3	3.3	45	<0.1	4.5	4.3	575	2.16	1.4	<0.5	5.5	67	<0.1	<0.1	<0.1	38	0.56	0.078
G1	Prep Blank	<2	0.1	2.0	3.0	44	<0.1	2.5	3.8	587	2.10	<0.5	<0.5	5.5	65	<0.1	<0.1	<0.1	38	0.53	0.079

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 14, 2011

QUALITY CONTROL REPORT WHI11001490.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																		
1279200	Rock	9	16	0.04	437	0.001	<20	0.62	0.003	0.41	<0.1	0.69	1.2	0.45	2.4	8.5	3	<0.2
REP 1279200	QC																	
Reference Materials																		
STD DS8	Standard	16	112	0.60	279	0.106	<20	0.92	0.090	0.41	2.2	0.17	5.6	0.16	2.0	4.7	5	4.8
STD OREAS45CA	Standard	16	739	0.15	160	0.118	<20	4.04	0.010	0.08	<0.1	0.03	<0.1	<0.05	36.1	0.9	19	<0.2
STD OXC88	Standard																	
STD OXC88	Standard																	
STD OXH82	Standard																	
STD OXH82	Standard																	
STD OXC88 Expected																		
STD OXH82 Expected																		
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																	
BLK	Blank																	
BLK	Blank																	
BLK	Blank																	
BLK	Blank	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																		
G1	Prep Blank	13	13	0.54	174	0.124	<20	1.02	0.100	0.51	<0.1	<0.01	0.3	<0.05	2.0	<0.5	5	<0.2
G1	Prep Blank	13	10	0.51	156	0.115	<20	0.95	0.091	0.47	<0.1	<0.01	0.3	<0.05	1.9	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 27, 2011
Report Date: October 24, 2011
Page: 1 of 5

CERTIFICATE OF ANALYSIS WHI11001491.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #20
P.O. Number
Number of Samples: 93

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-500	93	Crush, split and pulverize 500 g rock to 200 mesh			VAN
3B	93	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	93	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001491.1

	Method	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1278361	Rock	99	1.8	38.8	29.8	72	0.9	17.7	4.4	148	4.22	631.1	88.4	11.2	25	1.4	18.9	2.1	38	0.03	0.088
1278362	Rock	43	2.9	46.7	28.5	103	0.9	20.4	6.2	121	3.90	689.7	19.2	10.3	21	2.8	9.6	1.5	36	0.02	0.078
1278363	Rock	90	3.2	32.8	34.0	97	1.0	18.8	4.0	117	4.61	967.1	46.7	10.3	19	0.4	4.3	1.5	39	0.01	0.086
1278364	Rock	41	1.3	38.4	13.9	168	0.8	38.6	10.3	234	4.31	607.8	20.7	9.8	19	1.8	4.6	1.3	38	0.05	0.067
1278365	Rock	246	1.8	21.7	13.9	64	0.8	10.4	4.0	45	3.02	690.5	84.1	8.0	15	0.2	7.3	0.9	18	<0.01	0.051
1278366	Rock	13	1.1	47.9	15.7	132	0.5	26.8	6.1	179	5.11	608.8	1.4	9.2	12	1.1	4.8	0.7	39	0.02	0.089
1278367	Rock	17	2.1	42.0	12.5	153	0.5	29.1	7.3	307	4.59	424.1	5.1	9.0	11	1.4	6.2	0.8	48	0.02	0.051
1278368	Rock	148	1.0	42.1	16.8	63	1.4	11.4	3.1	102	3.93	857.1	13.1	10.5	18	0.5	2.9	0.7	35	0.01	0.069
1278369	Rock	24	1.3	50.2	13.7	100	0.9	17.9	3.7	159	4.69	411.5	0.7	9.1	10	0.7	3.4	0.6	47	0.02	0.060
1278370	Rock	372	1.3	37.9	13.5	127	1.3	23.1	5.7	121	4.26	791.5	5.5	10.6	18	0.7	3.7	0.5	52	0.02	0.059
1278371	Rock	11	1.8	44.2	11.7	109	0.7	14.9	3.6	149	4.22	369.8	<0.5	10.1	12	2.1	4.8	0.5	47	0.01	0.063
1278372	Rock	7	0.9	51.7	8.6	129	0.6	30.9	6.7	144	4.08	303.0	<0.5	10.0	15	1.8	4.3	0.4	53	0.04	0.054
1279207	Rock	42	2.2	42.0	23.7	61	0.7	8.6	2.2	57	3.25	221.3	39.5	9.6	13	<0.1	3.2	1.2	33	0.02	0.047
1279208	Rock	130	1.8	17.5	39.5	42	1.4	5.4	1.4	45	2.57	374.9	126.7	9.6	21	<0.1	11.2	1.8	17	<0.01	0.047
1279209	Rock	77	1.6	15.4	37.4	41	1.2	5.1	1.3	37	2.44	410.8	82.6	9.7	20	0.1	10.2	1.4	15	<0.01	0.044
1279210	Rock	164	2.9	23.9	37.3	52	1.2	7.8	1.9	50	2.98	619.0	184.4	10.3	28	0.2	28.8	1.7	20	0.02	0.049
1279211	Rock	124	3.9	26.4	39.6	67	1.5	8.7	2.2	54	2.83	491.4	124.7	9.7	24	0.2	4.5	1.5	18	0.02	0.051
1279212	Rock	151	6.2	29.2	52.2	82	1.7	9.2	2.3	58	3.53	584.9	159.2	10.6	37	0.2	4.4	1.5	16	0.03	0.072
1279213	Rock	76	5.5	23.8	34.4	103	1.4	12.1	3.1	72	2.56	273.8	76.7	10.1	22	0.2	2.8	1.3	15	0.03	0.046
1279214	Rock	78	5.7	23.0	26.6	71	1.3	8.4	2.0	61	2.31	218.2	89.7	10.0	20	0.1	2.1	1.2	13	0.04	0.044
1279215	Rock	82	5.4	22.1	30.0	90	1.6	10.5	2.5	65	2.34	219.7	90.9	10.5	21	0.1	2.6	1.2	15	0.03	0.043
1279216	Rock	85	2.6	43.1	60.1	131	1.6	14.2	4.3	130	3.87	301.7	95.3	11.9	34	0.2	9.7	2.6	13	0.04	0.074
1279217	Rock	67	1.8	26.2	39.4	84	1.4	8.7	2.3	66	2.30	197.6	77.5	10.5	10	<0.1	6.2	1.8	11	0.02	0.034
1279231	Rock	169	1.4	16.1	29.4	76	0.7	10.5	2.6	67	2.43	547.2	121.7	9.1	23	0.1	8.2	1.2	11	0.03	0.045
1279232	Rock	135	2.1	16.4	27.6	65	1.3	8.3	2.0	51	2.93	538.3	130.1	9.0	26	<0.1	5.7	1.0	19	<0.01	0.058
1279233	Rock	98	2.0	11.7	29.6	37	1.7	4.2	0.9	34	2.40	406.7	99.3	9.7	33	<0.1	4.6	1.2	26	<0.01	0.052
1279234	Rock	153	1.6	15.2	34.5	59	1.4	7.3	2.1	79	3.01	1223	95.1	10.0	20	0.2	7.1	1.1	11	0.02	0.057
1279235	Rock	111	0.7	12.2	40.5	68	0.9	7.3	1.9	60	2.17	711.6	116.4	9.9	30	<0.1	3.9	2.0	3	0.08	0.038
1279236	Rock	136	2.2	17.0	27.8	44	0.7	6.3	1.8	74	2.52	372.0	116.5	8.9	17	0.1	2.4	1.0	11	0.08	0.050
1279237	Rock	278	0.9	15.2	35.8	40	0.9	4.3	1.1	37	2.32	581.5	264.0	10.8	9	0.1	6.7	1.4	6	<0.01	0.050

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001491.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1278361	Rock	25	18	0.51	446	0.006	<20	1.45	0.016	0.51	0.2	5.65	2.1	0.50	2.6	8.3	4	<0.2
1278362	Rock	26	15	0.42	429	0.004	<20	1.46	0.017	0.51	<0.1	2.65	1.2	0.40	2.0	7.2	4	<0.2
1278363	Rock	25	16	0.37	449	0.004	<20	1.16	0.010	0.34	0.1	2.99	1.1	0.32	2.3	5.4	3	<0.2
1278364	Rock	28	19	0.70	283	0.008	<20	1.72	0.012	0.42	<0.1	2.32	0.8	0.46	3.1	3.3	4	<0.2
1278365	Rock	28	8	0.10	380	0.002	<20	0.62	0.008	0.23	0.1	2.75	0.5	0.13	1.5	2.9	2	<0.2
1278366	Rock	25	18	0.65	251	0.011	<20	1.54	0.007	0.32	<0.1	1.16	0.6	0.31	3.3	3.4	4	<0.2
1278367	Rock	27	25	1.16	206	0.022	<20	1.98	0.004	0.36	<0.1	1.40	0.8	0.33	3.7	3.6	5	<0.2
1278368	Rock	32	20	0.42	276	0.007	<20	1.40	0.010	0.34	<0.1	1.56	0.7	0.34	3.2	3.1	3	0.2
1278369	Rock	25	26	0.78	186	0.024	<20	1.85	0.004	0.39	<0.1	1.16	0.6	0.38	4.2	2.0	5	<0.2
1278370	Rock	32	28	0.52	240	0.021	<20	1.83	0.007	0.46	<0.1	1.56	0.6	0.20	4.6	1.8	4	<0.2
1278371	Rock	33	24	0.66	196	0.013	<20	1.82	0.006	0.33	<0.1	1.28	0.4	0.16	3.7	2.0	4	<0.2
1278372	Rock	34	25	0.70	207	0.018	<20	2.08	0.008	0.41	<0.1	1.33	0.4	0.16	4.4	1.6	5	<0.2
1279207	Rock	30	15	0.20	223	0.003	<20	0.93	0.013	0.40	0.2	3.85	1.0	0.13	2.9	6.0	3	<0.2
1279208	Rock	28	9	0.08	217	0.002	<20	0.74	0.011	0.38	0.4	11.16	1.4	0.14	1.0	7.8	2	<0.2
1279209	Rock	27	8	0.07	180	0.002	<20	0.63	0.011	0.33	0.2	8.15	1.4	0.14	0.9	4.5	2	<0.2
1279210	Rock	26	10	0.08	244	0.002	<20	0.80	0.014	0.40	0.2	8.62	1.7	0.21	1.5	11.7	2	<0.2
1279211	Rock	24	9	0.09	188	0.002	<20	0.77	0.015	0.35	0.2	8.28	1.8	0.21	1.4	5.8	2	<0.2
1279212	Rock	24	8	0.06	241	0.001	<20	0.81	0.017	0.38	0.3	7.87	2.2	0.31	1.5	7.0	2	<0.2
1279213	Rock	25	7	0.08	174	0.002	<20	0.75	0.013	0.32	0.2	6.53	1.3	0.19	1.3	4.3	2	<0.2
1279214	Rock	24	7	0.10	145	0.002	<20	0.79	0.015	0.31	0.2	5.95	1.3	0.13	1.3	3.6	2	<0.2
1279215	Rock	27	8	0.09	186	0.002	<20	0.90	0.017	0.39	0.2	6.47	1.4	0.14	1.4	4.0	3	<0.2
1279216	Rock	21	7	0.14	196	0.003	<20	0.86	0.015	0.28	0.4	6.58	1.8	0.28	1.9	5.5	3	<0.2
1279217	Rock	29	8	0.09	145	0.002	<20	0.70	0.009	0.34	0.2	6.19	0.7	0.08	1.2	3.8	2	<0.2
1279231	Rock	23	7	0.08	206	0.001	<20	0.52	0.007	0.29	0.3	6.55	1.0	0.32	0.9	2.7	1	<0.2
1279232	Rock	28	10	0.09	255	0.002	<20	0.78	0.011	0.40	0.4	11.67	1.4	0.23	1.1	4.9	2	<0.2
1279233	Rock	32	11	0.11	290	0.002	<20	0.88	0.018	0.46	0.2	11.57	1.5	0.19	1.3	5.1	2	<0.2
1279234	Rock	24	8	0.08	257	0.001	<20	0.55	0.007	0.28	15.9	10.67	1.3	0.25	0.9	3.2	1	<0.2
1279235	Rock	22	4	0.04	171	<0.001	<20	0.47	0.006	0.33	<0.1	21.30	1.1	0.35	0.5	4.1	1	<0.2
1279236	Rock	22	9	0.08	273	0.001	<20	0.58	0.008	0.32	0.2	8.03	1.0	0.34	0.9	3.5	1	<0.2
1279237	Rock	26	5	0.03	572	<0.001	<20	0.50	0.004	0.32	0.2	16.97	1.0	0.17	0.7	5.9	1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001491.1

	Method	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1279238	Rock	656	1.2	18.7	54.5	34	2.4	5.6	1.7	49	2.59	385.8	547.4	8.6	30	0.2	37.0	2.1	13	<0.01	0.047
1279239	Rock	195	3.6	28.6	18.4	115	1.5	8.6	2.1	41	4.74	1079	208.0	9.7	25	0.2	11.1	0.8	31	0.01	0.069
1279240	Rock	39	6.1	33.9	19.9	49	1.3	2.8	0.7	35	4.67	539.6	46.0	8.0	11	<0.1	2.7	0.7	31	<0.01	0.060
1279241	Rock	27	4.6	50.9	25.8	43	1.9	3.0	0.9	40	7.37	1119	30.4	8.1	10	<0.1	8.2	1.1	36	0.02	0.096
1279242	Rock	40	4.0	25.8	25.6	31	1.6	2.4	0.9	45	3.64	530.0	40.9	9.0	11	<0.1	5.3	1.2	18	0.01	0.043
1279243	Rock	30	2.4	39.5	18.5	66	1.0	7.6	2.1	113	3.94	441.0	25.7	9.2	15	0.4	6.9	0.8	34	0.02	0.047
1279244	Rock	23	1.9	22.6	30.2	22	1.1	2.5	0.7	49	2.83	658.4	26.1	10.5	18	<0.1	4.6	0.6	22	0.02	0.048
1279245	Rock	19	1.1	37.9	37.6	28	1.2	2.6	1.0	40	3.32	505.0	19.9	10.2	20	<0.1	3.4	0.5	8	0.02	0.049
1279246	Rock	41	1.2	21.4	32.7	33	1.0	4.1	1.3	43	2.75	440.5	36.2	11.0	15	<0.1	3.6	1.8	18	0.01	0.037
1279247	Rock	64	1.2	16.6	72.8	24	1.5	2.4	0.6	30	3.03	654.5	73.4	12.7	17	<0.1	13.8	1.6	5	0.02	0.066
1279248	Rock	145	1.7	14.2	59.6	56	1.2	4.8	1.5	38	2.77	571.3	158.4	12.1	18	<0.1	14.7	1.3	6	0.02	0.057
1279249	Rock	338	0.7	12.7	59.0	29	1.9	2.3	0.7	26	1.46	215.1	358.0	11.0	11	0.1	69.1	1.3	3	<0.01	0.029
1279250	Rock	354	1.2	15.7	46.3	56	1.5	6.3	1.7	46	1.91	251.1	388.7	12.0	17	0.3	31.0	1.7	8	0.02	0.038
1093934	Rock	2	<0.1	6.2	0.8	50	<0.1	15.9	5.7	534	3.18	21.2	2.6	3.1	153	0.2	1.1	<0.1	21	5.79	0.025
1093935	Rock	<2	0.3	7.0	27.1	41	<0.1	9.4	2.0	306	1.33	142.7	3.8	0.9	22	0.4	4.7	<0.1	3	1.70	0.006
1093936	Rock	3	<0.1	20.1	6.1	37	0.2	24.5	8.2	1639	4.67	157.1	<0.5	<0.1	102	0.2	7.0	0.1	30	14.90	0.010
1093937	Rock	17	0.3	45.6	1.0	49	0.2	61.4	29.0	801	4.42	1311	9.1	0.2	391	0.2	13.3	<0.1	15	5.28	0.063
1093938	Rock	8	0.5	30.4	103.4	413	0.7	21.7	3.6	1066	2.86	130.6	5.9	<0.1	73	2.6	64.4	<0.1	8	4.31	0.008
1093939	Rock	<2	0.2	1.4	0.7	13	<0.1	6.1	1.5	89	0.63	21.3	1.8	<0.1	<1	<0.1	2.3	<0.1	<2	0.02	<0.001
1093940	Rock	<2	0.4	2.5	95.0	44	<0.1	5.7	0.9	311	1.49	2.4	0.8	0.2	246	0.1	0.8	<0.1	2	4.33	0.009
1093941	Rock	<2	0.1	18.6	3.0	19	0.1	14.5	5.7	679	2.98	5.9	0.9	3.7	173	<0.1	0.1	0.1	7	5.81	0.022
1093942	Rock	3	<0.1	28.1	2.0	10	<0.1	12.6	4.2	416	2.12	3.4	<0.5	5.0	123	<0.1	<0.1	0.2	7	3.41	0.023
1093943	Rock	<2	1.2	19.2	3.8	5	0.5	7.7	0.3	62	0.74	2.9	<0.5	0.7	20	0.3	0.7	<0.1	44	0.05	0.059
1093944	Rock	<2	0.9	8.6	3.2	25	<0.1	5.6	1.0	184	1.09	5.0	1.1	0.2	32	<0.1	0.4	<0.1	3	0.88	0.005
1093945	Rock	<2	3.8	21.8	0.9	26	0.2	4.6	0.3	55	0.69	5.6	<0.5	0.2	89	0.4	0.8	<0.1	79	0.28	0.136
1093946	Rock	<2	1.3	5.8	0.9	125	<0.1	21.9	7.6	829	3.46	18.5	0.5	1.7	434	0.3	0.2	<0.1	20	15.60	0.023
1093947	Rock	<2	0.5	17.9	0.7	34	<0.1	13.5	1.1	134	0.61	3.4	1.0	0.2	189	0.2	0.3	<0.1	6	2.22	0.025
1093948	Rock	<2	0.7	5.0	0.2	12	<0.1	6.3	0.6	73	0.59	1.6	1.4	<0.1	10	0.3	0.3	<0.1	5	0.05	0.011
1093949	Rock	<2	2.3	6.2	1.0	14	0.2	4.6	0.4	58	0.70	5.1	1.2	0.3	22	0.1	1.2	<0.1	29	0.05	0.037
1093950	Rock	<2	3.5	14.3	0.9	32	0.2	9.5	0.6	56	0.64	3.5	1.8	0.2	45	0.9	1.5	<0.1	99	0.32	0.152

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001491.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1279238	Rock	23	9	0.07	993	0.001	<20	0.56	0.006	0.30	0.1	10.92	1.4	0.24	1.3	8.1	2	<0.2
1279239	Rock	25	13	0.16	415	0.002	<20	1.04	0.017	0.48	0.2	22.52	2.4	0.21	1.9	11.8	3	<0.2
1279240	Rock	20	10	0.10	294	0.002	<20	0.74	0.013	0.36	<0.1	3.98	1.0	0.22	1.1	5.8	2	<0.2
1279241	Rock	14	11	0.10	247	0.002	<20	0.49	0.008	0.24	0.6	3.76	0.6	0.28	1.1	8.2	2	<0.2
1279242	Rock	22	10	0.12	307	0.003	<20	0.59	0.012	0.31	0.2	7.20	0.8	0.19	1.0	8.1	2	<0.2
1279243	Rock	24	19	0.31	265	0.011	<20	1.17	0.014	0.47	0.1	5.79	0.9	0.25	2.9	3.7	3	<0.2
1279244	Rock	28	12	0.14	304	0.002	<20	0.83	0.017	0.40	0.1	5.70	0.9	0.19	1.4	6.6	2	<0.2
1279245	Rock	19	6	0.07	337	0.001	<20	0.66	0.014	0.33	0.3	10.35	0.6	0.25	0.8	5.5	2	<0.2
1279246	Rock	28	9	0.11	288	0.003	<20	0.75	0.012	0.41	<0.1	11.73	0.9	0.20	1.2	4.4	2	<0.2
1279247	Rock	25	5	0.04	275	0.001	<20	0.44	0.003	0.29	0.3	27.21	1.3	0.21	0.6	7.8	1	<0.2
1279248	Rock	25	7	0.04	261	<0.001	<20	0.45	0.004	0.27	0.7	19.29	2.1	0.18	0.7	7.0	1	<0.2
1279249	Rock	29	3	0.04	190	<0.001	<20	0.44	0.003	0.28	0.2	25.82	2.3	0.11	0.4	12.2	1	<0.2
1279250	Rock	32	8	0.10	231	0.001	<20	0.63	0.006	0.33	0.3	16.49	2.5	0.13	0.7	8.7	2	<0.2
1093934	Rock	6	17	1.83	269	<0.001	<20	0.27	0.003	0.15	<0.1	0.15	<0.1	<0.05	8.4	0.5	<1	<0.2
1093935	Rock	2	13	0.18	79	<0.001	<20	0.12	<0.001	0.06	<0.1	0.12	<0.1	<0.05	1.2	0.5	<1	<0.2
1093936	Rock	4	19	5.30	94	<0.001	<20	0.11	0.007	0.06	<0.1	0.05	<0.1	<0.05	5.8	<0.5	<1	<0.2
1093937	Rock	4	17	2.22	447	<0.001	<20	0.47	<0.001	0.31	<0.1	0.07	0.1	1.10	13.8	1.1	<1	<0.2
1093938	Rock	2	9	0.58	69	<0.001	<20	0.05	<0.001	0.03	<0.1	0.14	<0.1	<0.05	5.7	0.5	<1	<0.2
1093939	Rock	<1	15	<0.01	13	<0.001	<20	0.01	<0.001	<0.01	<0.1	0.02	<0.1	<0.05	0.3	<0.5	<1	<0.2
1093940	Rock	12	15	1.83	40	<0.001	<20	0.03	<0.001	0.02	<0.1	0.05	<0.1	<0.05	0.7	0.7	<1	<0.2
1093941	Rock	11	7	2.71	397	<0.001	<20	0.32	0.005	0.24	<0.1	0.07	<0.1	0.27	4.4	0.9	<1	<0.2
1093942	Rock	10	7	1.55	370	0.001	<20	0.41	0.003	0.28	<0.1	0.03	<0.1	0.24	4.6	0.7	<1	<0.2
1093943	Rock	2	20	0.01	103	0.001	<20	0.11	<0.001	0.05	<0.1	0.16	<0.1	<0.05	0.4	1.8	<1	<0.2
1093944	Rock	2	17	0.32	268	<0.001	<20	0.05	<0.001	0.03	<0.1	0.15	<0.1	<0.05	0.3	<0.5	<1	<0.2
1093945	Rock	2	21	<0.01	41	0.001	<20	0.09	<0.001	0.03	<0.1	0.17	<0.1	<0.05	0.3	<0.5	<1	<0.2
1093946	Rock	22	18	6.36	314	<0.001	<20	0.19	0.016	0.12	<0.1	0.15	<0.1	<0.05	3.2	<0.5	<1	<0.2
1093947	Rock	2	12	0.36	67	<0.001	<20	0.07	<0.001	0.02	<0.1	0.08	<0.1	<0.05	0.4	0.8	<1	<0.2
1093948	Rock	<1	20	<0.01	22	<0.001	<20	0.04	<0.001	<0.01	<0.1	0.02	<0.1	<0.05	0.3	0.9	<1	<0.2
1093949	Rock	2	21	<0.01	92	<0.001	<20	0.08	<0.001	0.03	<0.1	0.10	<0.1	<0.05	0.7	1.0	<1	<0.2
1093950	Rock	2	19	<0.01	82	0.002	<20	0.11	0.002	0.03	<0.1	0.15	<0.1	<0.05	0.4	2.0	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001491.1

		Method	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093951	Rock		<2	1.6	7.7	3.4	175	0.1	37.0	3.3	375	1.55	7.1	1.1	0.4	17	4.3	1.2	<0.1	13	0.29	0.023
1285001	Rock		<2	5.7	25.0	2.4	38	0.3	15.9	1.0	58	0.79	11.0	<0.5	0.6	12	0.4	1.4	<0.1	71	0.04	0.028
1285002	Rock		2	5.5	37.9	2.3	83	0.4	25.0	1.8	77	0.82	6.9	<0.5	0.7	132	1.4	2.2	<0.1	61	0.69	0.051
1285003	Rock		<2	2.7	26.4	1.7	26	0.1	15.5	1.1	63	0.94	15.6	<0.5	0.7	14	0.1	1.8	<0.1	65	0.09	0.087
1285004	Rock		<2	1.2	31.1	2.6	19	0.2	12.3	0.6	52	0.76	7.4	0.5	0.8	23	<0.1	1.2	<0.1	26	0.08	0.051
1285005	Rock		<2	0.8	1.8	0.6	4	<0.1	1.6	0.2	48	0.47	1.1	<0.5	<0.1	5	<0.1	0.4	<0.1	11	<0.01	0.003
1285006	Rock		7	4.2	244.9	21.4	1359	2.6	128.1	25.7	73	19.53	14.1	1.3	3.6	119	2.5	1.0	0.2	25	0.06	0.325
1279075	Rock		<2	0.4	3.3	2.8	92	<0.1	3.7	0.8	186	0.22	2.0	<0.5	0.3	426	1.1	0.3	<0.1	8	32.60	0.145
1279076	Rock		<2	0.4	2.6	2.2	76	<0.1	2.5	0.4	303	0.50	1.4	<0.5	0.2	372	1.3	0.2	<0.1	6	30.32	0.008
1279077	Rock		<2	0.7	4.5	2.2	162	<0.1	4.0	0.8	473	0.70	2.7	<0.5	0.3	371	2.2	0.7	<0.1	26	26.91	0.814
1279078	Rock		<2	0.8	9.1	3.8	211	<0.1	5.9	1.2	509	1.19	3.0	<0.5	0.3	311	2.5	0.6	<0.1	25	20.61	0.453
1279079	Rock		11	1.6	55.0	41.9	60	0.5	23.6	3.3	32	1.81	18.4	<0.5	2.7	10	<0.1	1.6	0.1	29	0.17	0.055
1279080	Rock		12	12.3	43.3	19.5	180	0.7	20.7	1.8	49	2.71	78.2	<0.5	2.3	10	0.3	1.7	<0.1	131	0.17	0.157
1279081	Rock		2	1.5	3.3	2.7	64	<0.1	6.9	1.1	1088	2.22	16.8	<0.5	0.4	76	0.2	1.3	<0.1	9	13.68	0.063
1279063	Rock		4	0.2	24.8	5.1	30	0.2	19.3	12.3	308	3.36	227.4	0.6	3.7	135	<0.1	0.2	0.1	11	2.25	0.019
1279064	Rock		<2	<0.1	31.1	2.6	23	<0.1	29.5	15.4	502	3.52	36.9	0.9	3.5	136	<0.1	0.2	0.1	12	2.57	0.024
1279065	Rock		3	<0.1	29.0	12.8	51	0.2	43.3	34.8	851	5.54	26.2	2.4	4.1	162	<0.1	0.4	0.1	16	3.35	0.015
1279066	Rock		<2	0.2	5.3	2.8	11	<0.1	20.7	2.0	207	0.70	7.5	<0.5	0.5	110	<0.1	0.3	<0.1	4	1.32	0.008
1279067	Rock		<2	0.3	19.9	4.1	26	0.1	21.6	6.9	786	2.02	6.3	<0.5	3.9	77	<0.1	0.2	0.1	13	3.12	0.025
1279068	Rock		<2	0.9	38.5	10.4	55	0.1	21.8	5.9	98	5.58	9.0	<0.5	3.4	5	0.2	0.3	0.2	13	0.02	0.024
1279069	Rock		2	3.5	26.0	5.9	36	0.4	13.4	0.6	53	0.67	9.9	<0.5	0.7	27	0.3	1.1	<0.1	79	0.27	0.106
1279070	Rock		4	8.5	46.2	9.0	50	0.6	34.6	0.4	40	0.58	13.2	<0.5	0.7	47	1.3	2.2	<0.1	437	1.07	0.463
1279071	Rock		4	23.3	57.6	13.0	171	1.0	58.1	1.9	56	1.36	41.3	1.3	0.8	50	2.3	5.7	0.1	519	1.15	0.505
1279072	Rock		3	4.8	16.9	5.7	43	0.3	34.6	1.6	287	0.65	9.6	<0.5	0.4	26	0.9	1.0	<0.1	103	0.36	0.164
1279073	Rock		<2	3.9	19.8	5.7	124	<0.1	17.1	1.4	61	0.81	11.3	2.1	0.8	8	0.3	0.7	<0.1	14	0.19	0.101
1279074	Rock		3	1.5	33.3	10.0	587	0.2	12.9	1.8	473	1.54	10.1	<0.5	0.5	292	6.6	1.4	<0.1	48	15.51	2.684
1093804	Rock		13	0.5	19.0	3.5	569	<0.1	129.6	15.0	127	4.15	43.7	14.7	0.5	<1	0.5	1.2	<0.1	7	0.02	0.023
1093806	Rock		3	2.5	15.2	3.8	98	0.7	16.5	2.2	57	1.33	28.8	0.7	0.8	81	0.2	5.4	<0.1	42	0.13	0.241
1093807	Rock		10	2.4	25.5	4.6	384	0.9	39.0	6.4	92	2.89	66.9	5.4	1.0	76	0.5	6.6	0.1	83	0.15	0.295
1093808	Rock		19	1.8	2.6	16.7	6	0.2	1.9	0.2	22	1.28	28.3	<0.5	1.7	32	<0.1	1.6	0.2	18	<0.01	0.010

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001491.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1093951	Rock	3	10	0.09	63	<0.001	<20	0.12	<0.001	0.03	<0.1	0.18	<0.1	<0.05	0.5	0.8	<1	<0.2
1285001	Rock	<1	23	<0.01	48	<0.001	<20	0.09	<0.001	0.03	<0.1	0.20	<0.1	<0.05	0.6	0.8	<1	<0.2
1285002	Rock	2	23	0.03	87	<0.001	<20	0.12	<0.001	0.04	<0.1	0.06	<0.1	<0.05	0.4	1.3	<1	<0.2
1285003	Rock	4	21	<0.01	59	<0.001	<20	0.11	<0.001	0.04	<0.1	0.09	<0.1	<0.05	2.3	1.8	<1	<0.2
1285004	Rock	4	16	<0.01	98	<0.001	<20	0.12	<0.001	0.06	<0.1	0.13	<0.1	<0.05	0.9	1.3	<1	<0.2
1285005	Rock	<1	16	<0.01	18	<0.001	<20	0.01	<0.001	<0.01	<0.1	0.05	<0.1	<0.05	<0.1	0.6	<1	<0.2
1285006	Rock	7	11	0.03	3926	0.002	<20	0.95	0.001	0.21	<0.1	0.56	<0.1	0.12	4.5	14.1	1	<0.2
1279075	Rock	3	2	0.54	187	<0.001	<20	0.07	0.002	0.03	<0.1	0.04	<0.1	<0.05	0.7	<0.5	<1	<0.2
1279076	Rock	3	2	2.65	432	<0.001	<20	0.04	0.006	<0.01	<0.1	0.14	<0.1	<0.05	0.4	<0.5	<1	<0.2
1279077	Rock	5	3	2.31	852	0.003	<20	0.12	0.004	0.04	<0.1	0.13	<0.1	0.06	0.4	0.5	<1	<0.2
1279078	Rock	4	5	4.15	515	0.002	<20	0.14	0.005	0.06	<0.1	0.35	<0.1	<0.05	0.6	<0.5	<1	<0.2
1279079	Rock	7	15	0.05	329	0.001	<20	0.48	<0.001	0.27	<0.1	0.86	<0.1	0.22	2.9	2.3	1	<0.2
1279080	Rock	5	16	0.04	194	0.002	<20	0.40	0.001	0.21	<0.1	1.82	0.1	0.30	1.8	2.3	2	<0.2
1279081	Rock	4	4	7.64	68	<0.001	<20	0.09	0.012	0.03	<0.1	0.04	<0.1	<0.05	0.8	<0.5	<1	<0.2
1279063	Rock	6	7	1.01	704	0.001	<20	0.46	0.004	0.29	<0.1	0.07	<0.1	0.41	4.5	<0.5	1	<0.2
1279064	Rock	8	8	1.27	1153	0.001	<20	0.68	0.004	0.32	<0.1	0.02	<0.1	0.17	3.9	<0.5	1	<0.2
1279065	Rock	9	9	1.80	564	0.001	<20	0.44	0.005	0.27	<0.1	0.09	<0.1	0.38	5.9	0.8	1	<0.2
1279066	Rock	2	14	0.05	649	<0.001	<20	0.09	<0.001	0.04	<0.1	0.02	<0.1	<0.05	0.6	<0.5	<1	<0.2
1279067	Rock	12	8	1.11	459	0.002	<20	0.49	0.004	0.26	<0.1	0.04	<0.1	<0.05	4.1	<0.5	1	<0.2
1279068	Rock	10	7	0.04	478	0.001	<20	0.45	0.002	0.25	<0.1	0.06	<0.1	0.08	3.0	<0.5	1	<0.2
1279069	Rock	3	16	0.02	126	0.001	<20	0.17	<0.001	0.07	<0.1	0.18	<0.1	<0.05	0.5	1.8	<1	<0.2
1279070	Rock	8	31	0.04	140	0.005	<20	0.36	<0.001	0.15	0.1	0.23	<0.1	<0.05	1.1	1.3	1	<0.2
1279071	Rock	5	32	0.05	200	0.005	<20	0.40	<0.001	0.17	0.2	0.32	<0.1	0.06	1.1	2.5	1	<0.2
1279072	Rock	5	16	0.03	94	0.001	<20	0.23	<0.001	0.07	<0.1	0.12	<0.1	<0.05	0.7	0.8	<1	<0.2
1279073	Rock	2	15	0.01	78	0.001	<20	0.15	0.001	0.07	<0.1	0.53	<0.1	<0.05	0.7	0.8	<1	<0.2
1279074	Rock	13	11	4.00	851	0.010	80	0.27	0.019	0.12	<0.1	1.52	<0.1	<0.05	0.8	1.7	1	<0.2
1093804	Rock	2	14	<0.01	124	<0.001	<20	0.59	<0.001	0.02	<0.1	0.32	<0.1	<0.05	0.8	1.4	<1	<0.2
1093806	Rock	2	8	0.01	847	0.001	<20	0.24	0.002	0.06	<0.1	1.44	0.1	<0.05	2.1	6.7	<1	<0.2
1093807	Rock	2	18	<0.01	982	0.001	<20	0.35	0.001	0.07	<0.1	2.09	0.2	0.06	2.2	15.2	1	<0.2
1093808	Rock	5	8	0.01	999	<0.001	<20	0.40	0.007	0.21	<0.1	9.89	0.3	0.23	0.9	2.7	1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001491.1

Method		3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093809	Rock	28	4.3	36.4	9.3	124	1.4	14.2	1.7	41	1.89	90.1	<0.5	1.4	86	0.3	11.6	0.1	78	0.08	0.329
1279061	Rock	<2	0.3	67.8	0.9	74	<0.1	85.3	33.3	931	5.74	150.4	<0.5	0.2	362	0.1	2.2	<0.1	47	4.21	0.053
1279062	Rock	<2	0.2	62.8	2.5	137	<0.1	127.2	46.6	1110	6.14	53.8	<0.5	0.3	153	3.0	2.9	<0.1	64	2.17	0.060

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001491.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1093809	Rock	4	11	<0.01	2598	0.001	<20	0.30	<0.001	0.07	0.2	8.05	0.2	0.16	3.1	13.6	<1	<0.2
1279061	Rock	5	75	2.93	497	<0.001	<20	1.15	0.003	0.23	<0.1	0.11	<0.1	<0.05	17.1	0.5	3	<0.2
1279062	Rock	6	112	2.57	994	0.006	<20	2.08	<0.001	0.25	<0.1	0.05	0.1	<0.05	16.5	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

QUALITY CONTROL REPORT WHI11001491.1

	Method	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1278367	Rock	17	2.1	42.0	12.5	153	0.5	29.1	7.3	307	4.59	424.1	5.1	9.0	11	1.4	6.2	0.8	48	0.02	0.051
REP 1278367	QC		2.0	43.9	13.2	164	0.5	29.4	7.3	316	4.66	429.1	2.8	9.2	11	1.2	5.4	0.8	48	0.02	0.052
1279215	Rock	82	5.4	22.1	30.0	90	1.6	10.5	2.5	65	2.34	219.7	90.9	10.5	21	0.1	2.6	1.2	15	0.03	0.043
REP 1279215	QC	80																			
1093945	Rock	<2	3.8	21.8	0.9	26	0.2	4.6	0.3	55	0.69	5.6	<0.5	0.2	89	0.4	0.8	<0.1	79	0.28	0.136
REP 1093945	QC		3.8	21.9	1.0	27	0.2	4.8	0.3	55	0.68	5.5	1.0	0.2	90	0.4	0.7	<0.1	78	0.29	0.135
1279075	Rock	<2	0.4	3.3	2.8	92	<0.1	3.7	0.8	186	0.22	2.0	<0.5	0.3	426	1.1	0.3	<0.1	8	32.60	0.145
REP 1279075	QC	<2																			
1093804	Rock	13	0.5	19.0	3.5	569	<0.1	129.6	15.0	127	4.15	43.7	14.7	0.5	<1	0.5	1.2	<0.1	7	0.02	0.023
REP 1093804	QC		0.5	18.9	3.6	581	<0.1	129.7	15.1	125	4.13	42.8	10.4	0.4	3	0.5	1.1	<0.1	7	0.02	0.028
Core Reject Duplicates																					
1279213	Rock	76	5.5	23.8	34.4	103	1.4	12.1	3.1	72	2.56	273.8	76.7	10.1	22	0.2	2.8	1.3	15	0.03	0.046
DUP 1279213	QC	71	5.1	23.7	33.0	99	1.4	12.4	3.0	77	2.58	269.1	78.6	9.6	22	0.2	3.0	1.3	14	0.03	0.045
1093944	Rock	<2	0.9	8.6	3.2	25	<0.1	5.6	1.0	184	1.09	5.0	1.1	0.2	32	<0.1	0.4	<0.1	3	0.88	0.005
DUP 1093944	QC	<2	1.2	10.3	3.9	28	<0.1	8.2	1.1	206	1.23	5.9	<0.5	0.3	37	<0.1	0.5	<0.1	2	0.93	0.006
1093807	Rock	10	2.4	25.5	4.6	384	0.9	39.0	6.4	92	2.89	66.9	5.4	1.0	76	0.5	6.6	0.1	83	0.15	0.295
DUP 1093807	QC	9	2.2	24.0	4.3	352	0.9	35.2	6.0	96	2.61	63.5	1.2	1.1	76	0.4	6.5	<0.1	81	0.14	0.275
Reference Materials																					
STD DS8	Standard		13.5	113.9	127.1	327	1.7	38.6	7.8	596	2.51	25.2	98.4	6.4	68	2.3	2.6	6.3	42	0.73	0.078
STD DS8	Standard		13.6	116.7	121.3	335	1.7	37.9	8.2	638	2.58	24.9	100.3	5.9	68	2.7	3.0	6.5	45	0.75	0.081
STD DS8	Standard		14.5	116.0	127.0	324	1.9	39.2	7.9	617	2.54	26.2	86.5	6.7	75	2.3	4.3	6.9	42	0.72	0.081
STD OREAS45CA	Standard		0.8	517.8	21.2	61	0.3	258.8	91.6	935	16.71	4.0	46.4	7.1	15	0.1	<0.1	0.2	205	0.45	0.040
STD OREAS45CA	Standard		0.7	532.3	19.4	64	0.3	264.1	96.5	925	16.46	4.1	43.9	6.6	16	0.1	<0.1	0.2	210	0.41	0.037
STD OREAS45CA	Standard		0.6	527.4	20.0	62	0.3	243.1	88.9	914	15.41	4.1	42.6	7.0	16	<0.1	<0.1	0.2	198	0.42	0.039
STD OREAS45CA	Standard		0.9	532.9	22.3	66	0.3	269.8	90.7	952	16.40	4.1	44.0	7.7	18	<0.1	0.1	0.2	231	0.46	0.041
STD OXC88	Standard	193																			
STD OXC88	Standard	191																			
STD OXC88	Standard	185																			

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

QUALITY CONTROL REPORT WHI11001491.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																		
1278367	Rock	27	25	1.16	206	0.022	<20	1.98	0.004	0.36	<0.1	1.40	0.8	0.33	3.7	3.6	5	<0.2
REP 1278367	QC	27	24	1.18	214	0.022	<20	2.03	0.004	0.36	<0.1	1.52	0.8	0.33	3.6	2.4	5	<0.2
1279215	Rock	27	8	0.09	186	0.002	<20	0.90	0.017	0.39	0.2	6.47	1.4	0.14	1.4	4.0	3	<0.2
REP 1279215	QC																	
1093945	Rock	2	21	<0.01	41	0.001	<20	0.09	<0.001	0.03	<0.1	0.17	<0.1	<0.05	0.3	<0.5	<1	<0.2
REP 1093945	QC	2	22	<0.01	40	0.001	<20	0.09	0.001	0.02	<0.1	0.17	<0.1	<0.05	0.3	0.8	<1	<0.2
1279075	Rock	3	2	0.54	187	<0.001	<20	0.07	0.002	0.03	<0.1	0.04	<0.1	<0.05	0.7	<0.5	<1	<0.2
REP 1279075	QC																	
1093804	Rock	2	14	<0.01	124	<0.001	<20	0.59	<0.001	0.02	<0.1	0.32	<0.1	<0.05	0.8	1.4	<1	<0.2
REP 1093804	QC	2	14	0.01	124	<0.001	<20	0.59	<0.001	0.02	<0.1	0.29	<0.1	<0.05	0.8	1.5	<1	<0.2
Core Reject Duplicates																		
1279213	Rock	25	7	0.08	174	0.002	<20	0.75	0.013	0.32	0.2	6.53	1.3	0.19	1.3	4.3	2	<0.2
DUP 1279213	QC	24	8	0.08	170	0.002	<20	0.75	0.013	0.32	0.2	6.84	1.4	0.19	1.3	5.6	2	<0.2
1093944	Rock	2	17	0.32	268	<0.001	<20	0.05	<0.001	0.03	<0.1	0.15	<0.1	<0.05	0.3	<0.5	<1	<0.2
DUP 1093944	QC	2	18	0.34	298	0.001	<20	0.06	<0.001	0.03	<0.1	0.16	<0.1	<0.05	0.3	<0.5	<1	<0.2
1093807	Rock	2	18	<0.01	982	0.001	<20	0.35	0.001	0.07	<0.1	2.09	0.2	0.06	2.2	15.2	1	<0.2
DUP 1093807	QC	2	23	<0.01	1052	0.002	<20	0.38	0.002	0.08	<0.1	1.87	0.1	0.06	2.3	13.2	1	<0.2
Reference Materials																		
STD DS8	Standard	15	118	0.62	294	0.101	<20	0.97	0.101	0.44	1.9	0.15	5.5	0.17	2.0	5.0	5	4.7
STD DS8	Standard	15	120	0.64	292	0.112	<20	0.98	0.099	0.45	1.8	0.24	5.1	0.17	2.3	5.4	5	4.7
STD DS8	Standard	16	117	0.62	299	0.120	<20	0.97	0.100	0.43	2.0	0.19	5.0	0.16	2.3	5.0	5	5.3
STD OREAS45CA	Standard	16	733	0.15	160	0.123	<20	3.94	0.004	0.08	<0.1	0.06	<0.1	<0.05	38.4	<0.5	19	<0.2
STD OREAS45CA	Standard	17	726	0.15	163	0.125	<20	4.05	0.005	0.08	<0.1	0.08	0.1	<0.05	38.1	0.9	19	<0.2
STD OREAS45CA	Standard	16	633	0.17	155	0.124	<20	3.95	0.015	0.08	<0.1	0.02	<0.1	<0.05	39.6	0.8	18	<0.2
STD OREAS45CA	Standard	18	693	0.17	174	0.144	<20	4.04	0.009	0.09	<0.1	0.02	<0.1	<0.05	41.8	0.6	20	<0.2
STD OXC88	Standard																	
STD OXC88	Standard																	
STD OXC88	Standard																	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

QUALITY CONTROL REPORT WHI11001491.1

		3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001
STD OXC88	Standard	198																			
STD OXH82	Standard	1280																			
STD OXH82	Standard	1292																			
STD OXH82	Standard	1256																			
STD OXH82	Standard	1306																			
STD OXC88 Expected		203																			
STD OXH82 Expected		1278																			
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08
STD OREAS45CA Expected			1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385
BLK	Blank	<2																			
BLK	Blank	<2																			
BLK	Blank	<2																			
BLK	Blank	<2																			
BLK	Blank	<2																			
BLK	Blank	<2																			
BLK	Blank	<2																			
BLK	Blank	<2																			
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
Prep Wash																					
G1	Prep Blank	<2	0.1	2.0	3.3	50	<0.1	3.6	4.3	587	2.12	<0.5	1.0	5.4	77	<0.1	<0.1	<0.1	40	0.60	0.079
G1	Prep Blank	<2	0.2	2.1	3.4	51	<0.1	4.1	4.4	594	2.19	<0.5	<0.5	6.2	79	<0.1	<0.1	<0.1	41	0.58	0.076

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

QUALITY CONTROL REPORT WHI11001491.1

		1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
STD OXC88	Standard																	
STD OXH82	Standard																	
STD OXH82	Standard																	
STD OXH82	Standard																	
STD OXH82	Standard																	
STD OXC88 Expected																		
STD OXH82 Expected																		
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																	
BLK	Blank																	
BLK	Blank																	
BLK	Blank																	
BLK	Blank																	
BLK	Blank																	
BLK	Blank																	
BLK	Blank																	
BLK	Blank	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																		
G1	Prep Blank	13	10	0.58	214	0.138	<20	1.09	0.108	0.52	<0.1	0.05	0.3	<0.05	2.3	<0.5	5	<0.2
G1	Prep Blank	13	11	0.59	214	0.138	<20	1.11	0.107	0.53	0.2	0.04	0.3	<0.05	2.2	<0.5	6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 26, 2011
Report Date: November 04, 2011
Page: 1 of 6

CERTIFICATE OF ANALYSIS WHI11001510.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #22
P.O. Number
Number of Samples: 141

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
1DX	125	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN
3B	125	Fire assay fusion Au by ICP-ES	30	Completed	VAN
R200-500	125	Crush, split and pulverize 500 g rock to 200 mesh			VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001510.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1285051	Rock	51.5	39.8	10.2	2	0.6	3.2	<0.1	23	0.83	122.9	6.8	2.4	52	0.2	13.6	1.4	200	<0.01	0.052	7
1285052	Rock	12.7	5.7	24.0	2	0.7	0.6	<0.1	11	1.09	38.5	2.9	4.4	17	<0.1	6.8	1.0	32	<0.01	0.015	14
1285053	Rock	8.1	4.4	61.7	2	0.4	0.7	<0.1	8	1.13	40.8	0.8	5.5	15	<0.1	4.6	0.3	21	<0.01	0.021	9
1285054	Rock	6.9	4.2	38.7	2	0.4	0.6	<0.1	8	1.00	27.8	<0.5	4.8	11	<0.1	4.9	0.2	20	<0.01	0.011	9
1285055	Rock	13.8	6.2	38.0	2	0.7	0.6	<0.1	9	1.30	35.4	<0.5	5.3	22	<0.1	6.5	0.3	22	<0.01	0.016	7
1285056	Rock	10.9	13.0	35.4	3	0.8	0.8	<0.1	11	1.48	36.7	1.9	5.8	58	<0.1	6.5	0.3	29	<0.01	0.035	8
1285057	Rock	8.0	5.1	25.4	3	0.4	0.9	<0.1	14	1.26	25.3	1.0	4.6	27	<0.1	4.5	0.2	22	<0.01	0.021	9
1285058	Rock	16.6	11.3	52.2	29	0.6	3.9	0.4	15	1.46	48.2	3.1	4.0	35	<0.1	6.6	0.2	61	<0.01	0.027	7
1285059	Rock	18.1	17.1	36.1	57	0.7	2.7	0.4	13	1.79	131.6	2.9	6.9	126	0.2	5.3	0.3	51	0.01	0.100	8
1285060	Rock	15.2	18.7	92.4	23	0.9	2.3	0.3	12	1.40	73.3	2.0	7.5	164	0.2	5.7	0.3	55	0.02	0.061	9
1285061	Rock	8.4	23.6	30.8	221	0.5	14.6	2.6	39	2.26	280.8	3.4	3.5	78	0.2	6.3	0.3	89	<0.01	0.047	7
1285062	Rock	11.3	11.5	59.0	3	0.8	1.2	0.1	8	1.27	71.2	<0.5	4.3	61	<0.1	5.7	0.3	37	<0.01	0.024	6
1285063	Rock	12.5	15.0	40.4	92	0.9	9.3	1.7	19	1.96	341.2	1.8	3.8	57	0.2	9.0	0.3	59	<0.01	0.052	6
1285064	Rock	3.0	9.1	12.2	62	0.3	4.1	0.6	10	0.90	138.4	1.3	2.2	50	<0.1	6.1	0.3	27	<0.01	0.019	5
1285065	Rock	4.4	15.3	13.0	389	0.5	19.7	3.3	29	2.20	268.6	0.6	2.9	117	<0.1	8.1	0.3	91	0.01	0.045	7
1285066	Rock	19.5	26.5	35.5	8	1.0	4.2	0.2	20	1.28	196.0	3.2	3.7	134	0.3	10.1	0.2	121	0.03	0.081	8
1285067	Rock	91.9	61.9	23.2	1464	1.8	104.1	15.0	227	5.73	926.9	4.2	2.5	113	0.4	39.9	0.1	595	0.02	0.150	7
1285068	Rock	56.0	36.1	41.4	2	1.2	10.6	0.1	30	1.00	187.4	<0.5	1.5	55	0.1	19.8	<0.1	432	0.02	0.051	7
1285069	Rock	76.4	39.9	401.9	4	1.4	5.7	0.1	28	1.07	135.5	1.5	1.9	32	0.2	21.4	<0.1	343	0.01	0.034	6
1285070	Rock	2.2	42.6	16.4	186	0.7	72.4	15.3	548	3.80	12.1	1.4	3.4	81	0.5	0.6	0.2	32	0.37	0.174	5
1285071	Rock	4.7	93.3	12.3	207	1.7	70.1	11.7	378	3.59	10.9	4.3	2.5	47	0.6	1.0	0.2	34	0.15	0.093	4
1285072	Rock	3.5	142.5	11.8	201	1.2	74.3	11.8	261	3.28	8.9	4.6	2.5	44	0.3	0.8	0.2	34	0.07	0.059	2
1285073	Rock	1.3	68.5	8.2	107	0.4	34.5	5.1	56	2.25	6.2	1.0	2.3	22	0.4	0.3	0.2	25	0.05	0.036	1
1285074	Rock	2.0	79.0	16.6	154	0.7	62.5	10.8	136	3.44	11.4	1.3	2.9	51	0.5	0.6	0.2	29	0.06	0.067	3
1285075	Rock	1.2	55.0	11.8	115	0.4	40.0	8.3	427	4.07	8.0	1.1	3.6	26	0.5	0.3	0.2	37	0.10	0.076	3
1285076	Rock	1.0	61.4	16.6	137	0.5	43.2	10.6	154	3.16	11.1	0.6	4.2	31	0.6	0.3	0.3	29	0.09	0.067	3
1285077	Rock	1.0	44.8	13.4	137	0.3	43.0	11.6	256	3.02	11.5	0.9	4.1	25	0.7	0.2	0.2	27	0.11	0.056	3
1285078	Rock	1.3	52.7	13.3	140	0.2	45.5	10.2	186	3.44	11.1	0.9	3.6	27	0.5	0.2	0.3	30	0.10	0.055	3
1285079	Rock	1.8	51.6	12.3	112	0.2	34.6	6.7	130	2.64	9.8	1.6	2.7	22	0.3	0.6	0.2	37	0.06	0.050	3
1285080	Rock	4.2	31.8	12.2	119	0.3	30.5	6.2	154	2.45	13.4	3.5	2.0	19	0.4	1.2	0.2	57	0.10	0.062	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001510.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B	WGHT
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au	Wgt
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb	kg
	MDL	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2	0.01
1285051	Rock	18	<0.01	2586	<0.001	<20	0.22	<0.001	0.09	0.7	8.37	0.8	0.14	1.4	9.8	2	0.3	167	6.54
1285052	Rock	7	0.02	585	<0.001	<20	0.31	0.003	0.25	0.4	8.74	0.6	0.37	0.6	8.3	2	<0.2	76	7.04
1285053	Rock	10	0.01	462	<0.001	<20	0.27	0.002	0.27	0.1	1.92	0.6	0.38	1.0	5.8	1	<0.2	20	7.39
1285054	Rock	8	0.02	272	<0.001	<20	0.32	0.003	0.28	<0.1	1.87	0.6	0.35	0.9	7.3	1	<0.2	20	6.62
1285055	Rock	7	0.01	351	<0.001	<20	0.26	0.002	0.31	<0.1	2.95	0.8	0.48	0.9	10.8	1	<0.2	35	6.67
1285056	Rock	13	0.01	391	<0.001	<20	0.27	0.003	0.31	0.2	3.36	0.9	0.47	1.1	9.5	1	0.2	45	5.98
1285057	Rock	13	0.01	378	<0.001	<20	0.27	0.002	0.29	0.1	2.94	0.4	0.43	0.8	4.7	1	<0.2	21	6.78
1285058	Rock	10	0.01	456	0.001	<20	0.28	0.002	0.28	<0.1	2.31	0.4	0.43	1.1	8.1	1	<0.2	31	6.07
1285059	Rock	13	0.01	336	<0.001	<20	0.35	0.002	0.27	0.1	2.19	0.9	0.46	2.4	6.9	2	<0.2	39	6.68
1285060	Rock	12	0.02	539	<0.001	<20	0.37	0.002	0.26	<0.1	2.36	0.9	0.38	1.8	6.8	2	<0.2	27	7.53
1285061	Rock	14	0.04	814	<0.001	<20	0.41	0.002	0.21	<0.1	4.71	0.6	0.28	2.6	5.5	2	<0.2	28	8.57
1285062	Rock	9	0.02	242	<0.001	<20	0.31	0.003	0.32	<0.1	4.85	0.8	0.48	1.2	10.6	2	<0.2	38	8.09
1285063	Rock	12	0.01	328	<0.001	<20	0.31	0.002	0.28	0.1	11.02	0.7	0.46	2.7	9.5	2	<0.2	64	6.49
1285064	Rock	8	0.01	394	<0.001	<20	0.33	0.002	0.20	<0.1	4.66	0.5	0.21	1.1	2.3	1	<0.2	24	6.87
1285065	Rock	11	0.01	308	<0.001	<20	0.38	<0.001	0.19	<0.1	1.96	0.4	0.17	2.2	2.6	1	<0.2	10	7.93
1285066	Rock	18	0.01	663	<0.001	<20	0.38	0.002	0.17	0.1	11.28	1.0	0.23	2.2	8.0	2	0.2	107	6.04
1285067	Rock	36	0.02	409	0.001	<20	0.55	<0.001	0.14	0.4	15.91	1.5	0.18	9.3	20.4	3	0.3	223	6.80
1285068	Rock	24	0.01	267	<0.001	<20	0.34	<0.001	0.12	0.3	6.22	0.9	0.13	2.1	20.2	2	<0.2	24	6.82
1285069	Rock	19	0.01	439	<0.001	<20	0.31	<0.001	0.14	0.3	2.96	0.9	0.19	1.5	18.9	2	<0.2	4	6.96
1285070	Rock	35	0.45	682	0.002	<20	1.47	0.003	0.14	<0.1	0.12	<0.1	<0.05	4.3	3.8	3	<0.2	2	4.76
1285071	Rock	31	0.26	2070	0.001	<20	1.01	0.005	0.13	<0.1	0.36	0.1	0.07	5.3	7.2	2	<0.2	14	6.26
1285072	Rock	40	0.31	706	<0.001	<20	1.15	0.004	0.13	<0.1	0.24	<0.1	<0.05	6.3	2.8	3	<0.2	15	5.62
1285073	Rock	35	0.35	911	0.001	<20	1.25	0.006	0.19	<0.1	0.12	<0.1	<0.05	3.3	1.3	3	<0.2	5	5.60
1285074	Rock	46	0.29	589	0.001	<20	1.26	0.008	0.17	<0.1	0.21	<0.1	0.05	4.6	4.7	3	<0.2	16	5.10
1285075	Rock	44	0.51	535	0.001	<20	1.68	0.004	0.17	<0.1	0.10	<0.1	<0.05	4.1	1.5	4	<0.2	4	6.96
1285076	Rock	41	0.46	666	0.002	<20	1.59	0.005	0.20	<0.1	0.12	<0.1	<0.05	4.6	1.3	4	<0.2	4	7.05
1285077	Rock	34	0.47	624	0.001	<20	1.56	0.004	0.19	<0.1	0.07	<0.1	<0.05	4.4	0.7	3	<0.2	3	6.03
1285078	Rock	37	0.51	671	0.001	<20	1.70	0.003	0.18	<0.1	0.08	<0.1	<0.05	4.2	1.4	4	<0.2	3	6.12
1285079	Rock	30	0.32	654	0.001	<20	1.31	0.004	0.16	<0.1	0.08	<0.1	<0.05	2.9	1.1	3	<0.2	3	4.19
1285080	Rock	24	0.26	699	0.003	<20	1.11	0.003	0.11	<0.1	0.09	0.1	<0.05	2.1	1.5	3	<0.2	3	5.20

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001510.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1285081	Rock	2.5	74.0	16.2	177	0.2	47.6	8.9	164	3.32	10.3	<0.5	3.0	18	0.5	0.6	0.2	34	0.05	0.054	3
1285082	Rock	1.2	46.4	9.2	123	0.1	38.8	6.4	93	2.59	8.1	1.7	3.4	20	0.4	0.1	0.2	26	0.07	0.059	3
1285083	Rock	1.7	54.9	15.2	135	0.3	42.2	9.1	505	4.43	9.6	2.0	3.6	34	0.4	0.2	0.2	32	0.07	0.078	4
1285084	Rock	1.0	52.4	12.6	170	0.1	47.0	10.5	182	3.53	10.6	1.2	3.9	26	0.4	0.1	0.2	28	0.09	0.067	3
1285085	Rock	1.1	58.5	14.4	168	0.2	53.7	10.0	149	3.33	11.5	1.0	3.7	41	0.6	0.2	0.3	28	0.34	0.065	2
1285086	Rock	2.6	61.1	10.9	132	0.6	44.7	8.8	278	2.72	10.6	2.3	2.2	164	0.6	0.5	0.2	37	4.50	0.069	4
1285087	Rock	2.0	72.4	11.1	149	0.4	59.4	11.2	188	3.06	9.6	1.1	2.8	62	0.4	0.4	0.2	34	0.83	0.054	4
1285088	Rock	1.6	61.6	10.6	144	<0.1	47.8	10.7	286	3.51	9.3	2.5	2.7	15	0.2	0.3	0.2	37	0.04	0.050	4
1285089	Rock	3.7	57.3	16.2	161	0.4	47.9	13.0	742	4.65	13.8	4.2	2.5	26	0.7	0.6	0.2	62	0.07	0.076	5
1285090	Rock	2.3	46.1	10.5	110	0.2	37.9	9.5	667	3.83	8.4	2.6	2.2	19	0.2	0.3	0.2	42	0.06	0.055	3
1285091	Rock	1.9	55.6	10.7	113	0.1	35.1	8.2	599	2.78	8.0	2.0	2.3	20	0.4	0.4	0.2	37	0.05	0.040	3
1285092	Rock	2.1	58.4	10.9	125	0.2	38.2	8.5	250	2.61	9.3	1.7	2.2	26	0.3	0.4	0.2	41	0.05	0.043	4
1285093	Rock	4.4	41.2	11.2	127	0.3	33.8	9.2	329	2.58	14.5	1.9	2.5	33	0.4	0.7	0.2	61	0.06	0.053	7
1285094	Rock	3.8	26.0	11.3	116	0.2	26.7	7.5	334	2.69	14.2	0.5	3.1	29	0.4	0.8	0.2	68	0.08	0.075	9
1285095	Rock	2.3	59.8	11.1	139	0.1	57.1	15.4	508	2.62	18.0	1.1	3.7	44	0.3	0.2	0.2	30	0.05	0.056	7
1285096	Rock	1.9	71.0	10.1	110	0.1	35.0	9.1	253	2.17	8.5	3.0	2.1	28	0.2	0.4	0.2	43	0.04	0.043	5
1285097	Rock	0.4	27.0	3.5	60	<0.1	21.7	4.1	220	2.40	1.7	1.1	1.1	36	0.1	0.2	0.1	34	0.05	0.020	2
1278373	Rock	1.1	46.7	10.6	111	0.9	21.6	5.5	146	4.37	365.1	<0.5	10.2	13	0.6	3.8	0.6	40	0.02	0.067	32
1278374	Rock	1.1	46.2	9.8	86	0.6	13.1	3.2	170	4.03	248.5	<0.5	9.4	12	0.4	3.4	0.7	37	0.02	0.062	34
1278375	Rock	1.5	33.1	14.0	77	0.3	8.8	2.5	160	3.70	138.5	<0.5	10.3	13	0.5	2.7	0.7	38	0.02	0.059	34
1278376	Rock	1.4	40.8	15.3	93	0.3	14.7	3.7	144	3.88	163.2	<0.5	9.4	15	0.8	3.2	0.6	34	0.01	0.061	33
1278377	Rock	1.9	74.0	17.6	153	0.5	32.8	9.6	142	4.58	259.2	<0.5	9.5	20	1.2	2.8	0.5	31	0.07	0.075	26
1278378	Rock	1.6	70.2	15.0	134	0.7	30.5	8.2	102	4.28	314.3	<0.5	8.1	13	0.7	3.4	0.6	31	0.02	0.057	26
1278379	Rock	2.4	42.1	15.9	110	0.9	24.2	7.0	81	3.68	369.7	<0.5	6.8	22	0.8	4.0	1.7	15	0.02	0.058	25
1278380	Rock	1.4	44.6	14.5	118	0.9	23.3	5.8	142	3.80	178.4	<0.5	8.3	20	0.4	2.4	0.8	31	<0.01	0.057	32
1278381	Rock	1.7	38.3	10.6	112	<0.1	16.5	3.9	201	4.50	120.3	<0.5	9.3	17	0.8	1.2	0.6	43	0.01	0.068	31
1278382	Rock	1.7	29.1	9.1	107	0.1	14.4	3.6	228	3.94	102.8	<0.5	8.3	16	0.8	3.3	0.5	41	0.02	0.056	29
1278383	Rock	1.4	27.4	9.6	95	0.1	12.7	2.9	222	3.84	115.1	<0.5	8.4	14	0.5	2.9	0.6	36	0.04	0.055	28
1278384	Rock	1.4	29.8	12.0	86	0.2	12.2	2.8	177	3.82	109.1	<0.5	8.7	12	0.4	3.1	0.9	36	0.02	0.050	27
1278385	Rock	1.5	31.8	12.0	96	0.2	13.3	3.2	195	4.18	137.3	<0.5	9.8	13	0.4	3.6	0.8	39	0.04	0.056	32

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001510.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B	WGHT
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au	Wgt
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb	kg
	MDL	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2	0.01
1285081	Rock	35	0.34	502	0.001	<20	1.34	0.004	0.18	<0.1	0.13	<0.1	<0.05	4.7	1.8	3	<0.2	6	5.79
1285082	Rock	18	0.38	496	<0.001	<20	1.45	0.004	0.18	<0.1	0.10	<0.1	<0.05	3.7	<0.5	3	<0.2	<2	6.08
1285083	Rock	32	0.50	537	<0.001	<20	1.73	0.002	0.16	<0.1	0.11	<0.1	<0.05	3.9	1.6	3	<0.2	5	6.26
1285084	Rock	32	0.49	618	<0.001	<20	1.79	0.003	0.20	<0.1	0.05	<0.1	<0.05	4.5	0.6	4	<0.2	2	5.68
1285085	Rock	29	0.47	1334	<0.001	<20	1.67	0.004	0.19	<0.1	0.07	<0.1	<0.05	4.6	0.7	3	<0.2	3	5.77
1285086	Rock	29	0.42	3293	0.001	<20	1.13	0.008	0.15	<0.1	0.20	<0.1	0.08	3.4	<0.5	3	<0.2	5	6.21
1285087	Rock	31	0.49	2959	0.001	<20	1.58	0.004	0.17	<0.1	0.20	<0.1	<0.05	4.4	0.7	4	<0.2	8	5.75
1285088	Rock	34	0.56	732	0.001	<20	1.80	0.002	0.19	<0.1	0.05	<0.1	<0.05	3.8	0.6	4	<0.2	7	4.52
1285089	Rock	43	0.51	863	0.002	<20	1.88	0.002	0.15	<0.1	0.09	0.1	<0.05	4.6	1.7	5	<0.2	12	5.27
1285090	Rock	31	0.52	668	0.003	<20	1.67	0.004	0.17	<0.1	0.03	<0.1	<0.05	3.5	0.8	4	<0.2	5	4.39
1285091	Rock	29	0.41	733	0.002	<20	1.39	0.003	0.17	<0.1	0.04	0.1	<0.05	2.6	<0.5	3	<0.2	7	4.77
1285092	Rock	29	0.39	1668	0.002	<20	1.46	0.003	0.18	<0.1	0.05	0.1	<0.05	2.6	<0.5	4	<0.2	7	5.55
1285093	Rock	28	0.26	2527	0.002	<20	1.27	0.005	0.12	<0.1	0.15	0.2	<0.05	2.4	0.8	3	<0.2	5	4.97
1285094	Rock	30	0.32	1335	0.008	<20	1.52	0.010	0.22	<0.1	0.13	0.2	<0.05	2.4	<0.5	4	<0.2	3	4.89
1285095	Rock	28	0.41	3171	0.001	<20	1.56	0.003	0.22	<0.1	0.03	0.1	<0.05	3.3	<0.5	3	<0.2	8	5.23
1285096	Rock	28	0.34	1252	0.002	<20	1.30	0.004	0.19	<0.1	0.07	<0.1	<0.05	2.5	<0.5	3	<0.2	8	5.24
1285097	Rock	32	0.65	2101	0.002	<20	1.46	0.003	0.14	<0.1	<0.01	<0.1	0.07	2.4	<0.5	4	<0.2	5	5.28
1278373	Rock	20	0.63	211	0.008	<20	1.66	0.007	0.24	<0.1	1.50	0.2	0.25	3.7	2.1	4	<0.2	11	6.96
1278374	Rock	17	0.66	136	0.005	<20	1.55	0.007	0.22	<0.1	1.73	0.3	0.16	3.1	1.2	4	<0.2	8	7.47
1278375	Rock	21	0.69	136	0.009	<20	1.66	0.008	0.27	<0.1	0.77	0.3	0.25	3.0	1.6	4	<0.2	9	5.54
1278376	Rock	20	0.58	242	0.006	<20	1.53	0.006	0.25	<0.1	1.68	0.3	0.21	3.3	0.8	4	<0.2	6	5.60
1278377	Rock	18	0.30	366	0.003	<20	1.24	0.006	0.23	<0.1	4.56	0.3	0.29	4.3	1.7	3	<0.2	24	5.79
1278378	Rock	17	0.33	209	0.004	<20	1.05	0.005	0.24	<0.1	4.01	0.2	0.50	3.4	2.0	2	<0.2	8	6.35
1278379	Rock	13	0.08	195	<0.001	<20	0.56	<0.001	0.19	<0.1	>100	0.5	0.24	1.1	50.1	<1	0.2	171	6.17
1278380	Rock	18	0.39	179	0.002	<20	1.23	0.006	0.23	<0.1	16.84	0.3	0.20	3.3	3.9	3	0.2	13	6.64
1278381	Rock	30	0.90	223	0.005	<20	2.00	0.005	0.24	<0.1	2.08	0.2	0.20	4.1	0.9	5	<0.2	2	7.14
1278382	Rock	26	0.86	196	0.007	<20	1.85	0.003	0.24	<0.1	2.73	0.2	0.17	3.6	1.6	5	<0.2	5	6.56
1278383	Rock	23	0.81	124	0.005	<20	1.69	0.004	0.20	<0.1	1.95	0.2	0.16	3.1	1.3	4	<0.2	4	6.62
1278384	Rock	19	0.72	105	0.004	<20	1.53	0.004	0.21	0.1	1.23	0.2	0.14	2.9	1.1	4	<0.2	6	6.10
1278385	Rock	22	0.74	134	0.008	<20	1.75	0.005	0.27	<0.1	1.17	0.3	0.13	3.5	1.0	4	<0.2	8	5.60

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001510.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278391	Rock	8.8	11.2	20.5	21	1.1	3.2	0.4	14	0.82	114.6	3.6	4.0	9	<0.1	8.8	1.1	38	0.02	0.023	19
1278392	Rock	12.6	16.0	28.0	54	1.3	8.2	1.2	29	1.26	481.5	10.4	4.5	25	0.3	12.2	0.9	73	<0.01	0.048	15
1278393	Rock	10.8	17.4	27.7	67	1.2	10.2	1.3	20	1.14	234.8	6.7	4.1	17	0.2	10.6	1.1	60	0.03	0.044	15
1278394	Rock	14.7	17.7	46.2	96	2.3	10.2	1.3	31	1.16	251.8	6.9	3.7	24	0.4	17.4	2.1	112	0.03	0.073	14
1278395	Rock	11.7	13.2	40.9	70	1.6	7.3	0.9	28	1.12	181.6	2.7	4.2	20	0.2	13.2	1.3	95	0.02	0.039	15
1278396	Rock	5.3	16.0	76.2	129	1.7	8.9	1.4	30	1.33	137.4	6.5	7.5	27	0.2	7.2	2.4	58	0.02	0.041	19
1278397	Rock	5.6	17.4	56.7	116	1.3	9.2	1.4	37	1.59	161.5	14.6	9.4	48	0.3	6.3	1.2	59	0.04	0.055	20
1278398	Rock	3.2	5.4	86.0	33	0.9	3.0	0.5	25	1.08	221.6	65.5	8.3	30	0.3	14.1	1.7	14	0.02	0.078	22
1278399	Rock	13.1	12.1	60.5	50	2.4	5.2	0.8	22	1.24	324.2	3.9	7.3	39	0.3	30.2	1.3	94	0.02	0.073	20
1278400	Rock	13.7	12.1	94.8	20	3.0	2.6	0.6	31	0.64	177.9	18.6	2.5	20	0.1	41.0	2.2	153	0.02	0.022	8
1279175	Rock	3.4	35.3	16.1	98	2.0	17.7	2.5	34	3.81	55.8	<0.5	2.3	135	0.2	5.3	0.2	104	0.22	0.371	4
1279176	Rock	4.4	14.3	13.3	54	1.4	12.9	1.8	35	1.69	38.1	<0.5	1.7	99	0.2	3.6	0.2	53	0.22	0.205	5
1279177	Rock	7.2	23.8	16.4	79	2.0	16.8	2.2	44	2.08	60.7	1.4	2.7	153	0.3	5.8	0.2	73	0.35	0.332	6
1279178	Rock	5.7	15.9	13.9	61	1.5	14.4	1.9	38	1.83	40.6	1.9	1.2	105	0.3	3.3	0.2	65	0.22	0.230	5
1279179	Rock	6.9	25.4	17.1	74	1.7	15.7	2.0	40	1.94	54.3	2.2	1.6	102	0.4	5.5	0.2	80	0.18	0.350	6
1279180	Rock	4.6	60.0	15.8	134	2.1	20.1	2.7	52	2.11	67.1	0.9	2.9	253	0.8	10.7	0.2	159	0.55	0.751	8
1279181	Rock	5.3	66.8	16.9	146	2.8	18.8	2.0	30	2.63	94.6	<0.5	3.2	509	0.8	16.2	0.1	232	0.57	0.962	10
1279182	Rock	6.8	33.4	14.3	65	2.0	9.5	0.8	31	1.92	99.8	<0.5	2.5	479	0.7	16.7	0.1	263	0.34	0.695	9
1279183	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1279184	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1279185	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1279218	Rock	4.4	22.6	20.4	75	0.6	10.8	2.2	78	1.58	229.5	22.3	9.3	14	0.3	2.8	0.5	32	0.06	0.039	24
1279219	Rock	6.5	19.3	26.4	77	0.6	10.5	2.2	58	1.35	162.7	38.4	8.5	19	0.4	3.7	0.8	44	0.06	0.030	24
1279220	Rock	4.6	26.6	42.8	109	0.9	12.5	2.9	76	1.61	279.0	114.2	9.2	24	0.6	4.4	1.0	38	0.05	0.037	23
1279221	Rock	1.7	29.3	78.1	144	1.1	14.7	3.3	97	2.08	516.5	164.0	10.8	31	0.7	5.0	1.5	18	0.06	0.044	26
1279222	Rock	0.8	19.2	75.0	127	0.8	11.4	3.2	140	1.45	416.2	64.9	12.9	19	1.1	4.7	0.3	8	0.27	0.042	18
1279223	Rock	0.7	24.3	81.0	167	0.6	12.1	3.1	77	1.73	307.0	134.7	9.5	22	0.5	4.7	0.5	13	0.04	0.049	27
1279224	Rock	1.3	14.6	61.1	103	0.6	8.0	1.6	32	1.29	324.7	431.7	11.0	23	0.3	1.9	0.5	9	0.02	0.048	24
1279225	Rock	0.7	15.7	56.5	137	0.6	9.6	1.8	34	1.51	368.5	311.3	11.3	27	0.2	1.9	0.7	14	<0.01	0.045	28
1279226	Rock	0.9	15.7	53.9	90	0.5	5.9	1.5	41	1.22	434.5	263.5	12.5	27	0.4	2.1	0.9	12	0.04	0.047	24

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001510.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B	WGHT
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au	Wgt
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb	kg
	MDL	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2	0.01
1278391	Rock	6	0.02	158	<0.001	<20	0.36	0.006	0.18	0.4	4.09	0.8	0.07	0.9	8.9	1	<0.2	92	7.76
1278392	Rock	8	0.04	164	0.001	<20	0.40	0.008	0.18	0.4	5.20	1.2	0.11	1.1	5.4	1	<0.2	254	7.01
1278393	Rock	9	0.05	167	0.001	<20	0.40	0.006	0.19	0.3	3.69	1.2	0.09	1.3	7.8	1	<0.2	209	8.19
1278394	Rock	9	0.03	196	0.002	<20	0.37	0.005	0.16	0.4	6.00	1.9	0.09	1.2	8.3	1	<0.2	195	7.40
1278395	Rock	7	0.03	168	0.001	<20	0.40	0.006	0.19	0.5	5.42	1.7	0.08	0.8	8.4	1	<0.2	103	7.41
1278396	Rock	4	0.03	189	<0.001	<20	0.45	0.010	0.24	0.4	5.19	2.2	0.08	0.5	7.9	1	<0.2	73	6.63
1278397	Rock	5	0.04	212	<0.001	<20	0.53	0.010	0.24	0.2	3.06	2.9	0.14	0.5	7.5	1	<0.2	101	6.42
1278398	Rock	3	0.03	195	<0.001	<20	0.44	0.003	0.30	0.1	9.09	7.3	0.16	0.4	14.8	1	0.2	132	6.14
1278399	Rock	8	0.02	255	0.001	<20	0.40	0.007	0.21	0.4	27.37	7.0	0.17	0.8	17.8	2	<0.2	549	5.99
1278400	Rock	7	0.02	227	<0.001	<20	0.33	<0.001	0.14	0.8	49.81	3.6	0.12	0.4	13.0	1	0.4	1147	6.91
1279175	Rock	19	0.02	1798	0.002	<20	0.60	0.003	0.17	<0.1	3.02	0.2	0.15	3.3	24.7	2	<0.2	11	5.33
1279176	Rock	12	0.02	1109	0.001	<20	0.67	0.006	0.20	<0.1	2.90	0.4	0.17	1.9	7.1	2	<0.2	18	9.40
1279177	Rock	16	0.02	614	0.002	<20	0.82	0.006	0.21	0.1	3.34	0.5	0.17	3.0	9.5	2	<0.2	22	5.54
1279178	Rock	13	0.02	916	0.002	<20	0.76	0.006	0.20	<0.1	2.27	0.4	0.13	1.8	5.9	2	<0.2	19	5.75
1279179	Rock	16	0.02	1052	0.002	<20	0.62	0.004	0.16	0.1	5.54	0.4	0.13	2.1	9.1	2	<0.2	31	6.10
1279180	Rock	28	0.02	2470	0.004	<20	0.82	<0.001	0.19	0.2	8.97	0.4	0.10	3.5	15.9	3	0.3	47	7.20
1279181	Rock	47	0.02	432	0.013	23	0.92	0.003	0.22	0.3	6.67	0.3	0.29	5.5	23.4	3	<0.2	7	7.09
1279182	Rock	40	0.01	262	0.025	<20	0.68	<0.001	0.11	0.4	5.78	0.5	0.17	4.5	14.3	2	0.2	13	7.20
1279183	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1279184	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1279185	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1279218	Rock	8	0.12	184	0.005	<20	0.80	0.025	0.26	0.1	6.25	0.4	0.06	1.1	3.0	2	<0.2	38	6.86
1279219	Rock	9	0.10	200	0.006	<20	0.71	0.019	0.26	0.2	5.11	0.5	0.09	1.1	3.1	2	<0.2	58	7.26
1279220	Rock	7	0.08	175	0.003	<20	0.70	0.015	0.25	0.6	7.27	1.1	0.12	1.0	4.8	2	<0.2	138	5.51
1279221	Rock	5	0.09	235	0.004	<20	0.82	0.016	0.26	0.1	4.69	1.5	0.15	1.0	6.5	3	<0.2	151	5.97
1279222	Rock	4	0.16	261	0.018	<20	0.92	0.022	0.26	0.1	2.72	1.0	0.09	1.1	3.0	3	<0.2	60	8.47
1279223	Rock	4	0.04	150	<0.001	<20	0.53	0.010	0.22	<0.1	7.25	2.0	0.09	0.5	3.5	1	<0.2	116	5.37
1279224	Rock	4	0.02	200	<0.001	<20	0.53	0.005	0.25	<0.1	8.64	3.5	0.09	0.5	4.1	1	<0.2	397	6.93
1279225	Rock	6	0.02	139	<0.001	<20	0.51	0.005	0.25	<0.1	6.89	3.8	0.10	0.4	3.3	1	<0.2	279	6.51
1279226	Rock	4	0.03	181	<0.001	<20	0.51	0.006	0.27	<0.1	9.14	3.6	0.11	0.6	4.1	1	<0.2	232	6.42

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001510.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279227	Rock	2.9	28.9	50.3	134	0.7	12.0	2.6	67	1.49	489.5	157.4	7.8	33	0.5	7.9	1.3	30	0.01	0.045	24
1279228	Rock	7.4	23.1	37.9	106	0.8	14.1	2.9	49	1.41	626.8	65.0	7.5	29	0.5	14.9	1.7	36	0.01	0.048	23
1279229	Rock	10.8	26.1	35.7	125	0.9	19.0	3.3	37	1.58	671.0	39.4	6.4	28	0.6	17.9	1.9	41	<0.01	0.042	21
1093961	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093962	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093963	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093964	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093965	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093966	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093967	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093968	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093969	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093970	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093971	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093972	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093973	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093974	Rock	6.5	2.7	0.8	141	<0.1	24.8	2.6	106	0.67	3.1	<0.5	0.2	16	0.2	0.5	<0.1	3	0.19	0.004	1
1093975	Rock	3.8	50.3	2.2	78	<0.1	268.6	44.1	1162	5.92	2.8	<0.5	5.2	800	0.3	0.3	<0.1	113	6.61	0.211	39
1093976	Rock	1.0	58.8	2.7	92	<0.1	317.2	52.3	946	6.12	2.4	1.8	4.9	474	0.2	0.2	<0.1	139	5.63	0.231	35
1093977	Rock	1.6	37.2	1.1	66	<0.1	264.5	46.9	1070	5.27	3.0	<0.5	3.3	1266	<0.1	0.2	<0.1	106	8.63	0.170	24
1093978	Rock	0.2	3.6	0.5	20	<0.1	15.3	6.4	299	3.43	0.6	<0.5	<0.1	506	<0.1	0.2	<0.1	22	7.83	0.002	<1
1093979	Rock	0.8	48.1	1.2	74	<0.1	227.0	38.0	1497	5.20	2.0	<0.5	4.9	423	<0.1	0.2	<0.1	122	7.96	0.229	32
1093980	Rock	2.2	43.4	1.9	108	<0.1	232.3	39.0	1463	5.54	3.2	0.6	4.8	603	0.1	0.3	<0.1	123	7.56	0.213	34
1093981	Rock	0.9	57.6	1.6	58	<0.1	205.6	35.6	860	4.96	1.7	<0.5	5.1	751	<0.1	0.3	<0.1	117	6.43	0.225	32
1285018	Rock	1.3	46.8	1.9	13	<0.1	123.2	48.4	1252	5.01	1.7	<0.5	9.5	273	<0.1	0.1	<0.1	109	10.20	0.263	17
1285019	Rock	0.1	41.7	1.2	13	<0.1	149.2	32.5	1314	3.83	1.4	0.8	0.9	861	<0.1	0.1	<0.1	87	10.03	0.142	1
1285020	Rock	0.7	9.2	10.2	17	0.2	4.5	0.6	51	1.03	10.3	<0.5	0.2	7	<0.1	2.3	<0.1	8	0.09	0.020	<1
1285021	Rock	23.2	151.1	64.5	456	0.8	25.2	2.2	66	4.69	13.4	<0.5	0.6	26	0.2	6.1	<0.1	196	0.05	0.128	<1
1285022	Rock	41.5	549.9	57.5	5635	0.5	286.1	17.3	160	15.22	18.4	<0.5	0.7	39	10.8	9.1	<0.1	497	0.03	0.345	2
1285023	Rock	1.0	8.9	1.3	39	<0.1	14.2	4.3	440	0.63	1.4	<0.5	0.8	1568	0.4	0.6	<0.1	17	21.91	0.027	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001510.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B	WGHT
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au	Wgt
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb	kg
	MDL	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2	0.01
1279227	Rock	7	0.05	147	<0.001	<20	0.51	0.005	0.22	0.2	14.80	3.2	0.09	0.7	7.1	1	<0.2	199	5.72
1279228	Rock	8	0.03	158	0.001	<20	0.49	0.005	0.21	0.3	7.70	2.7	0.08	0.8	8.1	1	<0.2	272	6.73
1279229	Rock	7	0.03	131	0.001	<20	0.41	0.005	0.18	0.5	7.15	2.5	0.08	1.0	8.2	1	0.4	265	8.06
1093961	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093962	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093963	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093964	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093965	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093966	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093967	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093968	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093969	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093970	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093971	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093972	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093973	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093974	Rock	28	0.02	18	<0.001	<20	0.03	0.002	<0.01	<0.1	0.05	<0.1	<0.05	0.4	<0.5	<1	<0.2	2	0.36
1093975	Rock	306	6.23	176	0.010	<20	3.50	0.003	0.01	<0.1	0.02	<0.1	0.07	12.5	1.2	11	<0.2	<2	0.63
1093976	Rock	399	6.57	104	0.011	<20	3.68	0.003	<0.01	<0.1	0.02	<0.1	0.08	12.6	<0.5	12	<0.2	<2	0.49
1093977	Rock	345	5.92	61	0.006	<20	2.66	0.002	<0.01	<0.1	0.02	<0.1	<0.05	10.2	<0.5	9	<0.2	<2	0.75
1093978	Rock	3	3.28	18	<0.001	<20	0.03	0.001	<0.01	<0.1	0.02	<0.1	<0.05	0.6	<0.5	<1	<0.2	<2	0.45
1093979	Rock	314	6.43	55	0.005	<20	3.19	0.003	<0.01	<0.1	0.01	<0.1	<0.05	11.5	<0.5	10	<0.2	<2	0.93
1093980	Rock	306	6.81	147	0.009	<20	3.38	0.004	<0.01	<0.1	<0.01	<0.1	0.17	11.6	<0.5	11	<0.2	<2	1.25
1093981	Rock	283	6.06	191	0.005	<20	3.38	0.006	<0.01	<0.1	<0.01	<0.1	0.21	10.6	<0.5	11	<0.2	<2	1.51
1285018	Rock	203	3.19	194	0.002	<20	0.83	0.013	0.05	<0.1	0.02	<0.1	<0.05	16.1	<0.5	2	<0.2	<2	0.74
1285019	Rock	200	2.08	102	0.001	<20	1.56	0.002	<0.01	<0.1	0.01	<0.1	0.22	12.3	0.6	5	<0.2	<2	0.86
1285020	Rock	13	0.06	87	<0.001	<20	0.09	0.002	0.02	<0.1	0.02	<0.1	<0.05	0.6	1.7	<1	<0.2	<2	0.94
1285021	Rock	13	0.04	63	<0.001	<20	0.31	0.002	0.02	<0.1	0.39	0.2	0.05	1.9	32.0	1	<0.2	2	1.10
1285022	Rock	43	0.01	69	0.001	<20	0.67	0.001	0.02	<0.1	0.40	<0.1	<0.05	9.2	23.0	2	<0.2	2	0.83
1285023	Rock	22	0.31	21	<0.001	<20	0.05	0.002	<0.01	<0.1	0.03	<0.1	<0.05	4.3	0.6	<1	<0.2	<2	0.88

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001510.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1285024	Rock	20.6	25.0	4.1	3208	0.1	16.2	2.5	920	3.72	6.0	<0.5	1.3	460	61.4	3.2	<0.1	161	12.27	0.028	4
1285025	Rock	2.5	2.0	1.5	27	<0.1	13.5	0.9	302	0.86	1.0	1.5	0.2	645	0.1	0.2	<0.1	13	12.86	0.018	1
1285026	Rock	0.4	51.7	6.1	92	0.9	24.2	8.5	100	3.47	4.7	<0.5	5.4	27	0.4	0.5	0.3	8	0.09	0.040	13
1283512	Rock	3.4	11.5	3.8	267	0.5	13.3	0.7	140	0.33	4.9	<0.5	0.3	241	2.4	4.5	<0.1	110	5.36	0.034	2
1283513	Rock	1.3	24.6	11.9	199	<0.1	16.3	3.6	291	2.35	5.5	45.2	0.4	5	0.5	0.3	<0.1	5	0.02	0.023	<1
1283514	Rock	3.9	80.4	18.4	346	0.5	79.2	16.7	1342	27.73	12.0	1.3	1.4	6	1.1	1.0	0.2	43	<0.01	0.111	2
1283515	Rock	0.7	27.4	19.6	105	<0.1	23.6	7.1	365	2.00	2.4	<0.5	0.4	13	0.5	0.2	<0.1	4	0.02	0.023	<1
1283516	Rock	1.0	51.8	5.1	67	0.2	30.4	6.0	171	2.30	13.4	1.0	0.9	27	0.2	1.0	<0.1	20	0.04	0.053	4
1283517	Rock	0.7	56.1	4.2	170	<0.1	115.8	34.3	783	4.29	4.0	0.8	4.8	135	0.5	0.3	<0.1	53	15.75	0.250	35
1283518	Rock	0.4	73.5	3.4	69	<0.1	85.2	29.7	727	4.09	104.6	0.6	3.2	211	0.3	0.8	<0.1	30	10.82	0.207	21
1283519	Rock	0.6	57.4	3.4	68	<0.1	112.9	32.3	837	4.49	5.4	<0.5	3.3	177	0.2	0.4	<0.1	35	14.12	0.224	26
1283520	Rock	0.3	72.8	0.5	10	<0.1	69.9	10.8	1358	7.58	<0.5	2.1	0.2	338	<0.1	<0.1	<0.1	8	21.92	0.011	19
1283521	Rock	0.5	52.3	2.3	7	<0.1	152.6	28.3	679	2.13	<0.5	1.8	4.1	207	<0.1	<0.1	<0.1	47	19.56	0.254	36
1283522	Rock	0.4	48.8	3.0	10	<0.1	87.4	24.9	918	3.79	11.3	1.3	4.7	363	<0.1	0.2	<0.1	60	14.17	0.243	36
1283523	Rock	0.7	56.0	5.2	64	<0.1	125.9	35.6	861	5.28	3.3	0.9	4.2	235	0.1	0.4	<0.1	42	11.14	0.262	28
1283524	Rock	3.2	199.5	2.9	105	3.3	12.5	0.5	71	0.43	36.9	<0.5	0.1	594	1.9	54.3	<0.1	77	9.12	0.049	3
1283525	Rock	50.8	234.6	29.3	471	1.2	466.0	116.5	580	19.99	162.8	0.5	13.1	120	1.7	17.9	<0.1	153	0.77	1.005	26
1283526	Rock	64.3	62.5	17.9	103	0.4	162.5	12.5	111	8.83	134.6	1.2	19.2	48	0.2	11.5	0.2	66	0.38	0.361	6
1283527	Rock	17.1	61.9	2.9	18	<0.1	32.0	3.0	925	2.64	5.3	2.1	0.3	287	<0.1	1.9	<0.1	22	21.56	0.011	2
1283528	Rock	4.3	16.2	1.5	68	0.2	25.8	1.8	55	0.87	3.7	<0.5	0.2	8	0.2	1.2	<0.1	20	0.06	0.042	2
1283529	Rock	1.2	49.6	1.9	84	0.1	204.2	38.7	835	5.19	0.7	1.3	3.3	481	0.3	0.1	<0.1	38	5.69	0.176	25

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001510.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B	WGHT
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au	Wgt
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb	kg
	MDL	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2	0.01
1285024	Rock	20	4.09	178	<0.001	<20	0.33	0.011	0.01	<0.1	1.17	<0.1	<0.05	3.9	0.7	3	<0.2	3	1.01
1285025	Rock	2	1.09	32	<0.001	<20	0.03	0.002	0.01	<0.1	<0.01	<0.1	<0.05	0.6	<0.5	<1	<0.2	<2	0.79
1285026	Rock	<1	0.04	3301	<0.001	<20	1.05	0.002	0.16	<0.1	0.09	<0.1	0.08	3.3	1.3	2	<0.2	6	0.71
1283512	Rock	15	2.22	1161	<0.001	<20	0.06	0.006	0.02	<0.1	0.16	<0.1	<0.05	0.5	0.8	<1	<0.2	<2	1.50
1283513	Rock	3	0.05	60	<0.001	<20	0.17	0.001	0.03	<0.1	0.16	<0.1	<0.05	1.0	1.7	<1	<0.2	70	1.29
1283514	Rock	16	0.04	103	<0.001	<20	0.31	0.003	0.12	<0.1	0.09	<0.1	0.06	5.6	6.0	<1	<0.2	6	1.26
1283515	Rock	3	0.05	35	<0.001	<20	0.15	0.003	0.04	<0.1	0.05	<0.1	<0.05	1.3	0.9	<1	<0.2	<2	1.93
1283516	Rock	18	0.02	243	<0.001	<20	0.20	0.003	0.05	<0.1	0.07	<0.1	<0.05	2.2	0.5	<1	<0.2	<2	1.79
1283517	Rock	71	0.87	395	0.002	<20	1.23	0.004	0.15	<0.1	0.02	<0.1	<0.05	11.9	0.9	3	<0.2	<2	1.59
1283518	Rock	28	2.24	413	0.002	<20	0.41	0.005	0.19	<0.1	0.03	0.1	0.67	10.3	0.6	1	<0.2	5	1.82
1283519	Rock	35	1.57	385	0.002	<20	0.62	0.004	0.17	<0.1	0.02	<0.1	0.09	12.0	1.4	2	<0.2	<2	0.70
1283520	Rock	2	4.07	94	<0.001	<20	0.04	0.004	0.01	<0.1	<0.01	<0.1	0.07	1.2	0.6	<1	<0.2	<2	1.70
1283521	Rock	31	1.08	553	0.002	<20	0.59	0.008	0.22	<0.1	<0.01	<0.1	0.10	10.7	0.8	1	<0.2	<2	1.26
1283522	Rock	41	2.97	640	0.003	<20	0.46	0.011	0.20	<0.1	0.01	<0.1	0.13	12.4	<0.5	1	<0.2	<2	1.57
1283523	Rock	36	2.55	102	0.003	<20	0.72	0.006	0.22	<0.1	<0.01	0.1	1.01	12.6	1.3	2	<0.2	<2	1.44
1283524	Rock	11	0.14	176	<0.001	<20	0.07	0.001	0.02	<0.1	0.38	<0.1	<0.05	0.4	1.5	<1	<0.2	<2	1.23
1283525	Rock	116	0.15	486	0.004	<20	0.67	0.003	0.20	<0.1	0.26	0.9	0.10	9.2	13.5	2	<0.2	<2	1.41
1283526	Rock	17	0.07	568	0.002	<20	0.33	0.002	0.13	0.1	0.14	0.7	0.07	4.5	11.7	1	<0.2	<2	1.22
1283527	Rock	5	3.54	59	<0.001	<20	0.05	0.004	0.02	<0.1	0.06	<0.1	0.29	0.7	2.7	<1	<0.2	<2	1.04
1283528	Rock	16	<0.01	38	<0.001	<20	0.07	0.001	0.03	<0.1	0.10	<0.1	<0.05	0.6	2.0	<1	<0.2	<2	1.95
1283529	Rock	75	4.56	233	0.002	<20	0.73	0.002	0.19	<0.1	<0.01	<0.1	0.11	11.1	0.5	2	<0.2	<2	2.00

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

QUALITY CONTROL REPORT WHI11001510.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1285065	Rock	4.4	15.3	13.0	389	0.5	19.7	3.3	29	2.20	268.6	0.6	2.9	117	<0.1	8.1	0.3	91	0.01	0.045	7
REP 1285065	QC	4.4	15.7	13.1	402	0.5	19.6	3.4	30	2.20	264.3	<0.5	2.9	122	<0.1	7.7	0.3	89	0.01	0.049	7
1285069	Rock	76.4	39.9	401.9	4	1.4	5.7	0.1	28	1.07	135.5	1.5	1.9	32	0.2	21.4	<0.1	343	0.01	0.034	6
REP 1285069	QC																				
1285096	Rock	1.9	71.0	10.1	110	0.1	35.0	9.1	253	2.17	8.5	3.0	2.1	28	0.2	0.4	0.2	43	0.04	0.043	5
REP 1285096	QC																				
1279179	Rock	6.9	25.4	17.1	74	1.7	15.7	2.0	40	1.94	54.3	2.2	1.6	102	0.4	5.5	0.2	80	0.18	0.350	6
REP 1279179	QC	7.0	23.8	16.3	71	1.6	15.5	2.1	40	1.90	52.4	3.7	1.5	99	0.4	5.6	0.2	80	0.17	0.329	6
1279222	Rock	0.8	19.2	75.0	127	0.8	11.4	3.2	140	1.45	416.2	64.9	12.9	19	1.1	4.7	0.3	8	0.27	0.042	18
REP 1279222	QC	0.8	18.7	72.0	121	0.8	10.4	2.8	138	1.40	403.3	59.9	12.4	19	1.3	3.2	0.3	8	0.27	0.042	17
1093974	Rock	6.5	2.7	0.8	141	<0.1	24.8	2.6	106	0.67	3.1	<0.5	0.2	16	0.2	0.5	<0.1	3	0.19	0.004	1
REP 1093974	QC																				
1283518	Rock	0.4	73.5	3.4	69	<0.1	85.2	29.7	727	4.09	104.6	0.6	3.2	211	0.3	0.8	<0.1	30	10.82	0.207	21
REP 1283518	QC	0.5	76.9	3.6	74	<0.1	85.2	29.2	731	4.18	107.1	2.2	3.4	218	0.3	0.9	<0.1	28	10.97	0.219	23
1283525	Rock	50.8	234.6	29.3	471	1.2	466.0	116.5	580	19.99	162.8	0.5	13.1	120	1.7	17.9	<0.1	153	0.77	1.005	26
REP 1283525	QC																				
Core Reject Duplicates																					
1285059	Rock	18.1	17.1	36.1	57	0.7	2.7	0.4	13	1.79	131.6	2.9	6.9	126	0.2	5.3	0.3	51	0.01	0.100	8
DUP 1285059	QC	20.5	17.8	36.9	65	0.6	3.2	0.4	14	1.94	148.2	4.5	7.2	132	0.2	5.7	0.3	53	0.01	0.106	8
1285094	Rock	3.8	26.0	11.3	116	0.2	26.7	7.5	334	2.69	14.2	0.5	3.1	29	0.4	0.8	0.2	68	0.08	0.075	9
DUP 1285094	QC	3.4	26.6	10.3	100	0.2	26.0	7.4	310	2.60	12.7	1.0	3.2	30	0.3	0.8	0.1	61	0.09	0.071	9
1279183	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
DUP 1279183	QC	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093981	Rock	0.9	57.6	1.6	58	<0.1	205.6	35.6	860	4.96	1.7	<0.5	5.1	751	<0.1	0.3	<0.1	117	6.43	0.225	32
DUP 1093981	QC	0.8	55.3	1.7	57	<0.1	212.1	34.8	895	5.01	1.3	<0.5	5.0	766	<0.1	0.3	<0.1	120	6.50	0.234	32
Reference Materials																					
STD DS8	Standard	14.8	116.2	127.2	324	2.0	39.7	7.9	629	2.55	27.6	88.2	7.4	70	2.4	4.3	6.7	43	0.76	0.082	16
STD DS8	Standard	14.8	117.5	125.5	319	1.8	39.3	7.8	605	2.49	26.2	93.6	6.6	67	2.4	4.4	6.1	42	0.72	0.073	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

QUALITY CONTROL REPORT WHI11001510.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B	WGHT
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au	Wgt
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb	kg
	MDL	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2	0.01
Pulp Duplicates																			
1285065	Rock	11	0.01	308	<0.001	<20	0.38	<0.001	0.19	<0.1	1.96	0.4	0.17	2.2	2.6	1	<0.2	10	7.93
REP 1285065	QC	11	0.01	321	<0.001	<20	0.41	0.001	0.19	<0.1	2.01	0.4	0.17	2.2	2.7	1	<0.2		
1285069	Rock	19	0.01	439	<0.001	<20	0.31	<0.001	0.14	0.3	2.96	0.9	0.19	1.5	18.9	2	<0.2	4	6.96
REP 1285069	QC																	5	
1285096	Rock	28	0.34	1252	0.002	<20	1.30	0.004	0.19	<0.1	0.07	<0.1	<0.05	2.5	<0.5	3	<0.2	8	5.24
REP 1285096	QC																	12	
1279179	Rock	16	0.02	1052	0.002	<20	0.62	0.004	0.16	0.1	5.54	0.4	0.13	2.1	9.1	2	<0.2	31	6.10
REP 1279179	QC	16	0.02	1081	0.002	<20	0.62	0.004	0.16	0.1	5.25	0.4	0.13	2.1	8.2	2	0.2		
1279222	Rock	4	0.16	261	0.018	<20	0.92	0.022	0.26	0.1	2.72	1.0	0.09	1.1	3.0	3	<0.2	60	8.47
REP 1279222	QC	4	0.15	251	0.016	<20	0.89	0.022	0.25	0.2	2.64	0.9	0.09	1.0	3.5	3	<0.2		
1093974	Rock	28	0.02	18	<0.001	<20	0.03	0.002	<0.01	<0.1	0.05	<0.1	<0.05	0.4	<0.5	<1	<0.2	2	0.36
REP 1093974	QC																	3	
1283518	Rock	28	2.24	413	0.002	<20	0.41	0.005	0.19	<0.1	0.03	0.1	0.67	10.3	0.6	1	<0.2	5	1.82
REP 1283518	QC	27	2.24	442	0.002	<20	0.37	0.004	0.18	<0.1	0.03	0.1	0.67	10.7	1.2	1	<0.2		
1283525	Rock	116	0.15	486	0.004	<20	0.67	0.003	0.20	<0.1	0.26	0.9	0.10	9.2	13.5	2	<0.2	<2	1.41
REP 1283525	QC																	<2	
Core Reject Duplicates																			
1285059	Rock	13	0.01	336	<0.001	<20	0.35	0.002	0.27	0.1	2.19	0.9	0.46	2.4	6.9	2	<0.2	39	6.68
DUP 1285059	QC	15	0.01	340	<0.001	<20	0.33	0.003	0.28	0.1	2.16	0.9	0.49	2.7	6.5	2	<0.2	45	
1285094	Rock	30	0.32	1335	0.008	<20	1.52	0.010	0.22	<0.1	0.13	0.2	<0.05	2.4	<0.5	4	<0.2	3	4.89
DUP 1285094	QC	28	0.33	1428	0.013	<20	1.52	0.011	0.23	<0.1	0.14	0.2	0.06	2.3	0.9	4	<0.2	3	
1279183	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
DUP 1279183	QC	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093981	Rock	283	6.06	191	0.005	<20	3.38	0.006	<0.01	<0.1	<0.01	<0.1	0.21	10.6	<0.5	11	<0.2	<2	1.51
DUP 1093981	QC	294	6.19	196	0.005	<20	3.42	0.007	<0.01	<0.1	<0.01	<0.1	0.22	11.1	0.7	11	<0.2	<2	
Reference Materials																			
STD DS8	Standard	116	0.64	303	0.118	<20	0.99	0.097	0.43	2.6	0.16	5.1	0.17	2.2	4.5	5	5.1		
STD DS8	Standard	116	0.62	302	0.113	<20	0.95	0.090	0.41	2.3	0.24	5.1	0.17	2.1	5.2	5	5.1		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

QUALITY CONTROL REPORT WHI11001510.1

		1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1
STD DS8	Standard	12.9	100.1	121.6	300	1.7	35.3	6.9	581	2.40	24.3	91.0	6.8	70	2.1	4.5	7.9	39	0.69	0.074	14
STD DS8	Standard	14.9	116.2	130.6	323	1.8	38.2	7.7	637	2.58	25.4	103.8	6.8	59	2.2	4.2	6.6	42	0.52	0.082	16
STD DS8	Standard	13.4	109.8	119.3	309	1.8	39.0	7.7	608	2.53	25.4	115.3	6.9	72	2.5	4.6	6.3	43	0.74	0.082	15
STD DS8	Standard	14.1	120.3	130.9	319	1.7	41.7	8.1	619	2.55	26.6	97.2	7.1	70	2.6	5.4	7.2	43	0.72	0.078	15
STD OREAS45CA	Standard	0.7	540.4	21.1	67	0.3	272.6	94.9	956	15.71	4.1	43.9	7.2	17	<0.1	<0.1	0.2	211	0.44	0.040	17
STD OREAS45CA	Standard	0.8	511.3	20.3	68	0.2	258.6	91.8	905	15.09	3.7	38.1	7.1	16	<0.1	<0.1	0.2	210	0.41	0.036	16
STD OREAS45CA	Standard	0.8	509.1	20.5	61	0.3	250.3	85.4	910	14.59	4.0	45.8	7.4	17	<0.1	<0.1	0.2	205	0.41	0.037	16
STD OREAS45CA	Standard	0.9	493.3	19.8	60	0.3	235.9	86.9	848	15.43	3.6	40.1	7.0	11	<0.1	<0.1	0.2	197	0.41	0.039	16
STD OREAS45CA	Standard	0.6	525.9	22.4	63	0.3	264.7	93.7	943	17.07	2.8	48.6	7.8	15	0.1	<0.1	0.2	205	0.45	0.040	17
STD OREAS45CA	Standard	0.9	517.2	20.5	61	0.3	254.2	91.9	925	16.19	4.4	40.4	7.0	16	0.1	0.1	0.2	213	0.42	0.036	16
STD OXC88	Standard																				
STD OXC88	Standard																				
STD OXC88	Standard																				
STD OXC88	Standard																				
STD OXC88	Standard																				
STD OXC88	Standard																				
STD OXH82	Standard																				
STD OXH82	Standard																				
STD OXH82	Standard																				
STD OXH82	Standard																				
STD OXH82	Standard																				
STD OXC88 Expected																					
STD OXH82 Expected																					
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected		1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

QUALITY CONTROL REPORT WHI11001510.1

		1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2	3B Au ppb 2	WGHT Wgt kg 0.01
STD DS8	Standard	106	0.60	281	0.100	<20	0.92	0.083	0.40	2.6	0.21	5.2	0.16	1.8	4.6	4	4.4		
STD DS8	Standard	118	0.63	296	0.117	<20	0.97	0.098	0.43	2.4	0.22	5.5	0.17	2.1	5.0	5	5.2		
STD DS8	Standard	116	0.62	290	0.118	<20	0.97	0.102	0.43	2.5	0.15	5.4	0.17	2.0	4.1	5	5.1		
STD DS8	Standard	124	0.63	298	0.132	<20	0.96	0.097	0.43	3.0	0.21	5.4	0.17	2.0	5.6	5	5.0		
STD OREAS45CA	Standard	732	0.15	170	0.126	<20	4.21	0.009	0.08	<0.1	<0.01	<0.1	<0.05	39.9	<0.5	19	<0.2		
STD OREAS45CA	Standard	682	0.15	169	0.129	<20	3.88	0.008	0.07	<0.1	0.06	<0.1	<0.05	37.9	0.5	19	<0.2		
STD OREAS45CA	Standard	599	0.17	161	0.123	<20	3.81	0.008	0.07	<0.1	0.06	0.1	<0.05	36.9	<0.5	19	<0.2		
STD OREAS45CA	Standard	635	0.15	152	0.141	<20	3.71	0.013	0.08	<0.1	0.04	<0.1	<0.05	35.1	<0.5	18	<0.2		
STD OREAS45CA	Standard	704	0.15	171	0.125	<20	3.98	0.010	0.08	<0.1	<0.01	<0.1	<0.05	37.5	1.8	20	<0.2		
STD OREAS45CA	Standard	667	0.16	156	0.154	<20	3.68	0.008	0.07	<0.1	0.03	<0.1	<0.05	37.2	0.8	18	<0.2		
STD OXC88	Standard																	210	
STD OXC88	Standard																	197	
STD OXC88	Standard																	206	
STD OXC88	Standard																	204	
STD OXC88	Standard																	194	
STD OXC88	Standard																	193	
STD OXH82	Standard																	1281	
STD OXH82	Standard																	1312	
STD OXH82	Standard																	1276	
STD OXH82	Standard																	1333	
STD OXH82	Standard																	1326	
STD OXC88 Expected																		203	
STD OXH82 Expected																		1278	
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5		
STD OREAS45CA Expected		709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4			
BLK	Blank																	<2	
BLK	Blank																	<2	
BLK	Blank																	<2	
BLK	Blank																	<2	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

QUALITY CONTROL REPORT WHI11001510.1

		1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
Prep Wash																					
G1	Prep Blank	<0.1	2.4	3.0	46	<0.1	2.5	4.0	558	1.95	<0.5	1.1	5.5	56	<0.1	<0.1	<0.1	35	0.45	0.076	10
G1	Prep Blank	0.2	5.0	3.2	43	<0.1	2.5	3.8	545	1.89	<0.5	2.1	4.9	52	<0.1	<0.1	<0.1	35	0.47	0.069	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

QUALITY CONTROL REPORT WHI11001510.1

		1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2	3B Au ppb 2	WGHT Wgt kg 0.01
BLK	Blank																	<2	
BLK	Blank																	<2	
BLK	Blank																	<2	
BLK	Blank																	<2	
BLK	Blank																	<2	
BLK	Blank																	<2	
BLK	Blank																	<2	
BLK	Blank																	<2	
BLK	Blank	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2		
BLK	Blank	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2		
BLK	Blank	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2		
BLK	Blank	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2		
BLK	Blank	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2		
Prep Wash																			
G1	Prep Blank	9	0.52	169	0.116	<20	0.90	0.065	0.45	<0.1	<0.01	0.2	<0.05	1.8	<0.5	4	<0.2	<2	
G1	Prep Blank	8	0.51	160	0.107	<20	0.84	0.060	0.44	<0.1	<0.01	0.3	<0.05	1.6	<0.5	4	<0.2	<2	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: October 25, 2011
Report Date: November 03, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001510A.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #22
P.O. Number
Number of Samples: 1

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
1DX	1	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN
3B	1	Fire assay fusion Au by ICP-ES	30	Completed	VAN
R200-500	1	Crush, split and pulverize 500 g rock to 200 mesh			VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001510A.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283530	Rock	1.4	61.9	7.0	109	0.1	287.1	48.3	898	6.14	1.2	<0.5	4.8	413	<0.1	0.1	<0.1	79	5.55	0.230	33

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001510A.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B	WGHT
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au	Wgt
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb	kg
MDL		1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2	0.01
1283530	Rock	173	5.51	256	0.004	<20	2.26	<0.001	0.18	<0.1	0.05	<0.1	0.09	14.2	<0.5	6	<0.2	<2	1.97

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

QUALITY CONTROL REPORT WHI11001510A.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Reference Materials																					
STD DS8	Standard	12.9	100.1	121.6	300	1.7	35.3	6.9	581	2.40	24.3	91.0	6.8	70	2.1	4.5	7.9	39	0.69	0.074	14
STD OREAS45CA	Standard	0.8	509.1	20.5	61	0.3	250.3	85.4	910	14.59	4.0	45.8	7.4	17	<0.1	<0.1	0.2	205	0.41	0.037	16
STD OXC88	Standard																				
STD OXH82	Standard																				
STD OXC88 Expected																					
STD OXH82 Expected																					
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected		1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
Prep Wash																					
G1	Prep Blank	0.2	2.5	16.2	43	<0.1	4.1	3.8	553	2.07	<0.5	<0.5	5.5	68	<0.1	<0.1	<0.1	36	0.55	0.071	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

QUALITY CONTROL REPORT WHI11001510A.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B	WGHT
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au	Wgt
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb	kg
	MDL	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2	0.01
Reference Materials																			
STD DS8	Standard	106	0.60	281	0.100	<20	0.92	0.083	0.40	2.6	0.21	5.2	0.16	1.8	4.6	4	4.4		
STD OREAS45CA	Standard	599	0.17	161	0.123	<20	3.81	0.008	0.07	<0.1	0.06	0.1	<0.05	36.9	<0.5	19	<0.2		
STD OXC88	Standard																	217	
STD OXH82	Standard																	1387	
STD OXC88 Expected																		203	
STD OXH82 Expected																		1278	
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5		
STD OREAS45CA Expected		709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4			
BLK	Blank																	<2	
BLK	Blank																	<2	
BLK	Blank	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2		
Prep Wash																			
G1	Prep Blank	10	0.52	160	0.113	<20	0.99	0.097	0.47	<0.1	0.05	0.2	<0.05	1.7	<0.5	4	<0.2	<2	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: October 27, 2011
Report Date: November 09, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001510B.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #22
P.O. Number
Number of Samples: 25

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
1DX	25	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN
3B	25	Fire assay fusion Au by ICP-ES	30	Completed	VAN
R200-500	25	Crush, split and pulverize 500 g rock to 200 mesh			VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001510B.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279183	Rock	4.7	10.0	12.7	6	0.8	2.1	0.1	23	0.98	39.0	<0.5	2.1	233	0.2	5.9	0.2	110	0.05	0.185	7
1279184	Rock	5.5	7.6	16.4	3	0.6	1.3	0.2	26	1.11	22.0	<0.5	3.8	116	<0.1	6.3	0.3	44	0.02	0.077	9
1279185	Rock	7.0	7.0	14.2	3	0.5	2.0	0.1	28	1.17	21.4	<0.5	3.7	104	<0.1	7.0	0.3	46	0.02	0.065	9
1093952	Rock	24.0	43.4	8.3	25	1.9	4.8	0.4	48	1.86	76.9	20.0	0.9	83	<0.1	44.0	<0.1	58	0.03	0.057	3
1093953	Rock	1.5	4.6	4.5	2	2.5	1.6	0.2	51	0.57	4.3	16.5	0.2	6	<0.1	2.1	<0.1	9	0.01	0.004	1
1093954	Rock	3.6	12.6	3.5	3	2.3	5.8	0.3	50	0.62	24.2	4.4	0.4	12	<0.1	4.3	<0.1	16	<0.01	0.012	3
1093955	Rock	0.6	3.6	3.6	<1	0.6	2.3	0.3	46	0.68	4.4	1.9	0.2	9	<0.1	2.6	<0.1	5	0.01	0.003	<1
1093956	Rock	4.2	10.0	4.1	2	1.4	9.9	0.7	43	0.54	14.6	2.3	0.2	9	<0.1	5.6	<0.1	17	<0.01	0.006	<1
1093957	Rock	0.1	39.5	1.8	97	<0.1	17.5	7.0	408	2.08	5.0	1.1	4.7	47	0.5	0.3	0.1	8	0.55	0.029	17
1093958	Rock	1.1	56.6	2.5	14	<0.1	219.7	37.0	1024	5.27	3.9	<0.5	6.6	345	<0.1	0.2	<0.1	98	11.84	0.204	45
1093959	Rock	0.3	40.1	2.6	20	<0.1	128.1	23.7	836	2.94	124.7	<0.5	6.8	360	<0.1	0.3	<0.1	35	21.60	0.146	41
1093960	Rock	0.5	38.9	5.1	149	<0.1	177.8	36.1	863	3.90	16.7	<0.5	6.2	441	0.4	0.2	<0.1	38	17.32	0.133	44
1093961	Rock	0.3	1.5	0.9	5	<0.1	10.4	1.1	65	0.53	2.9	<0.5	0.1	4	<0.1	0.4	<0.1	4	0.16	0.004	<1
1093962	Rock	0.3	17.0	1.7	11	<0.1	22.3	2.4	99	0.64	6.1	<0.5	0.3	18	<0.1	0.3	<0.1	4	0.32	0.006	2
1093963	Rock	1.1	3.2	3.8	4	1.3	3.4	0.4	50	0.57	1.4	<0.5	0.6	8	0.1	6.0	<0.1	6	0.06	0.006	3
1093964	Rock	0.2	5.2	1.0	4	<0.1	34.4	5.3	152	0.64	1.2	<0.5	0.5	132	<0.1	0.1	<0.1	3	2.28	0.039	3
1093965	Rock	0.3	3.1	3.4	10	<0.1	21.0	3.3	190	0.96	4.6	<0.5	0.3	22	0.2	0.3	<0.1	3	1.06	0.030	2
1093966	Rock	0.4	2.9	9.8	17	<0.1	23.2	2.8	131	0.84	13.2	<0.5	0.6	15	<0.1	0.4	<0.1	10	0.25	0.044	4
1093967	Rock	0.4	2.6	1.8	14	<0.1	43.0	5.2	226	1.07	7.7	<0.5	0.6	24	0.2	0.5	<0.1	6	1.09	0.053	3
1093968	Rock	0.8	1.7	4.1	1	0.6	1.5	0.3	44	0.50	1.1	<0.5	0.4	15	<0.1	1.2	<0.1	7	0.02	0.006	2
1093969	Rock	0.3	16.8	0.6	5	<0.1	15.1	2.8	170	0.98	10.9	<0.5	1.2	79	<0.1	1.0	<0.1	7	1.14	0.059	4
1093970	Rock	2.9	2.8	22.1	58	<0.1	57.1	6.6	143	0.88	36.5	<0.5	0.8	22	0.1	2.3	<0.1	6	0.41	0.052	5
1093971	Rock	0.1	1.0	0.3	5	<0.1	17.0	1.6	139	0.57	<0.5	<0.5	0.5	338	<0.1	0.2	<0.1	2	2.52	0.037	3
1093972	Rock	0.5	1.5	1.0	4	<0.1	54.0	4.4	215	1.00	10.3	<0.5	1.3	380	<0.1	0.6	<0.1	9	2.62	0.079	8
1093973	Rock	0.4	0.9	0.7	5	<0.1	30.0	3.2	198	0.98	27.3	<0.5	1.2	59	<0.1	0.7	<0.1	6	1.42	0.076	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001510B.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B	WGHT
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au	Wgt
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb	kg
	MDL	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2	0.01
1279183	Rock	13	0.01	313	0.004	<20	0.42	0.001	0.14	0.2	3.09	0.6	0.19	1.5	6.6	1	0.3	21	9.75
1279184	Rock	10	0.02	339	0.001	<20	0.43	0.001	0.26	<0.1	2.41	0.6	0.32	1.5	7.4	1	<0.2	15	8.91
1279185	Rock	9	0.02	717	0.001	<20	0.40	0.002	0.27	<0.1	1.72	0.6	0.35	1.3	6.6	2	<0.2	9	9.04
1093952	Rock	18	<0.01	375	0.002	<20	0.21	<0.001	0.05	0.2	0.19	0.3	0.05	0.8	22.1	2	0.3	24	1.28
1093953	Rock	4	<0.01	438	<0.001	<20	0.08	<0.001	0.02	<0.1	0.50	<0.1	<0.05	0.3	2.2	<1	<0.2	26	1.64
1093954	Rock	23	<0.01	339	<0.001	<20	0.13	<0.001	0.04	0.3	1.28	0.2	<0.05	0.5	4.0	<1	<0.2	26	1.59
1093955	Rock	3	<0.01	238	<0.001	<20	0.10	<0.001	0.06	<0.1	0.12	0.2	0.11	0.4	9.6	<1	<0.2	7	1.88
1093956	Rock	23	<0.01	1081	<0.001	<20	0.13	<0.001	0.04	0.4	0.32	0.2	0.08	0.4	4.7	<1	<0.2	16	1.75
1093957	Rock	7	0.22	884	0.001	<20	0.42	0.002	0.24	<0.1	0.07	<0.1	0.20	3.1	0.9	1	<0.2	5	0.93
1093958	Rock	146	4.62	681	0.002	<20	0.88	0.006	0.17	<0.1	0.01	<0.1	0.27	12.8	0.9	2	<0.2	<2	1.91
1093959	Rock	50	1.79	1550	0.002	<20	0.43	0.008	0.18	<0.1	0.01	<0.1	0.12	9.5	0.6	1	<0.2	<2	1.81
1093960	Rock	67	3.53	1021	0.002	<20	0.45	0.013	0.16	<0.1	0.05	0.1	0.29	9.1	<0.5	1	<0.2	<2	1.57
1093961	Rock	3	0.03	142	<0.001	<20	0.08	0.002	0.04	0.4	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2	<2	2.14
1093962	Rock	15	0.08	249	<0.001	<20	0.08	0.001	0.03	<0.1	<0.01	<0.1	<0.05	0.2	<0.5	<1	<0.2	3	1.85
1093963	Rock	4	<0.01	284	<0.001	<20	0.11	0.002	0.04	0.3	0.03	<0.1	<0.05	0.2	1.4	<1	<0.2	12	1.86
1093964	Rock	16	0.19	308	<0.001	<20	0.05	0.002	0.01	<0.1	<0.01	<0.1	<0.05	0.7	<0.5	<1	<0.2	<2	1.88
1093965	Rock	7	0.06	255	0.001	<20	0.05	0.002	0.01	0.3	<0.01	<0.1	<0.05	0.4	<0.5	<1	<0.2	<2	1.97
1093966	Rock	18	0.02	302	0.001	<20	0.18	0.003	0.07	<0.1	<0.01	<0.1	<0.05	0.5	<0.5	<1	<0.2	<2	1.88
1093967	Rock	12	0.05	148	<0.001	<20	0.09	0.003	0.03	0.4	<0.01	<0.1	<0.05	0.6	<0.5	<1	<0.2	<2	1.54
1093968	Rock	16	<0.01	489	<0.001	<20	0.14	0.004	0.05	<0.1	0.03	<0.1	<0.05	0.2	<0.5	<1	<0.2	<2	1.75
1093969	Rock	10	0.27	201	0.001	<20	0.16	0.002	0.06	0.6	<0.01	<0.1	<0.05	0.5	<0.5	<1	<0.2	<2	1.60
1093970	Rock	22	0.03	384	0.001	<20	0.10	0.002	0.04	<0.1	<0.01	<0.1	<0.05	0.5	<0.5	<1	<0.2	<2	2.23
1093971	Rock	5	0.11	3486	<0.001	<20	0.27	0.005	0.12	0.2	<0.01	0.1	<0.05	1.1	<0.5	<1	<0.2	<2	1.62
1093972	Rock	33	0.25	615	0.001	<20	0.13	0.002	0.04	<0.1	<0.01	<0.1	<0.05	1.7	0.7	<1	<0.2	<2	1.77
1093973	Rock	17	0.27	387	0.001	<20	0.17	0.002	0.04	0.2	<0.01	<0.1	<0.05	1.1	<0.5	<1	<0.2	<2	2.09

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 09, 2011

QUALITY CONTROL REPORT WHI11001510B.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1093966	Rock	0.4	2.9	9.8	17	<0.1	23.2	2.8	131	0.84	13.2	<0.5	0.6	15	<0.1	0.4	<0.1	10	0.25	0.044	4
REP 1093966	QC																				
1093969	Rock	0.3	16.8	0.6	5	<0.1	15.1	2.8	170	0.98	10.9	<0.5	1.2	79	<0.1	1.0	<0.1	7	1.14	0.059	4
REP 1093969	QC	0.4	17.0	0.5	4	<0.1	14.8	2.8	169	0.96	10.4	<0.5	1.1	76	<0.1	1.1	<0.1	7	1.12	0.057	5
Core Reject Duplicates																					
1093958	Rock	1.1	56.6	2.5	14	<0.1	219.7	37.0	1024	5.27	3.9	<0.5	6.6	345	<0.1	0.2	<0.1	98	11.84	0.204	45
DUP 1093958	QC	0.9	57.7	2.8	16	<0.1	206.9	35.3	978	5.14	3.8	<0.5	7.0	339	<0.1	0.1	<0.1	97	11.84	0.194	43
Reference Materials																					
STD DS8	Standard	13.7	108.6	118.0	302	1.6	36.3	7.2	579	2.41	23.5	86.4	6.7	66	2.4	3.4	6.3	40	0.66	0.071	14
STD OREAS45CA	Standard	0.7	498.1	18.8	62	0.3	244.2	86.3	900	15.20	3.9	40.1	6.4	15	0.1	0.1	0.1	214	0.41	0.036	16
STD OXC88	Standard																				
STD OXC88	Standard																				
STD OXH82	Standard																				
STD OXH82	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected		1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9
STD OXC88 Expected																					
STD OXH82 Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
Prep Wash																					
G1	Prep Blank	0.8	13.0	3.8	45	<0.1	3.0	3.7	569	2.10	1.2	<0.5	5.2	72	<0.1	0.2	<0.1	38	0.52	0.073	13
G1	Prep Blank	0.2	6.2	3.1	44	<0.1	2.7	3.9	545	2.03	<0.5	1.0	5.1	70	<0.1	<0.1	<0.1	37	0.53	0.074	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 09, 2011

QUALITY CONTROL REPORT WHI11001510B.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	3B	WGHT
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te	Au	Wgt
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppb	kg
	MDL	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2	2	0.01
Pulp Duplicates																			
1093966	Rock	18	0.02	302	0.001	<20	0.18	0.003	0.07	<0.1	<0.01	<0.1	<0.05	0.5	<0.5	<1	<0.2	<2	1.88
REP 1093966	QC																	<2	
1093969	Rock	10	0.27	201	0.001	<20	0.16	0.002	0.06	0.6	<0.01	<0.1	<0.05	0.5	<0.5	<1	<0.2	<2	1.60
REP 1093969	QC	11	0.27	208	0.001	<20	0.16	0.002	0.06	0.3	<0.01	<0.1	<0.05	0.5	<0.5	<1	<0.2		
Core Reject Duplicates																			
1093958	Rock	146	4.62	681	0.002	<20	0.88	0.006	0.17	<0.1	0.01	<0.1	0.27	12.8	0.9	2	<0.2	<2	1.91
DUP 1093958	QC	139	4.52	682	0.002	<20	0.89	0.006	0.18	<0.1	<0.01	<0.1	0.27	12.8	1.2	2	<0.2	<2	
Reference Materials																			
STD DS8	Standard	109	0.59	264	0.111	<20	0.91	0.088	0.40	2.0	0.17	5.1	0.15	1.8	4.3	4	4.8		
STD OREAS45CA	Standard	624	0.15	149	0.125	<20	3.80	0.008	0.08	<0.1	0.01	<0.1	<0.05	35.1	0.5	17	<0.2		
STD OXC88	Standard																	198	
STD OXC88	Standard																	204	
STD OXH82	Standard																	1287	
STD OXH82	Standard																	1304	
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5		
STD OREAS45CA Expected		709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4			
STD OXC88 Expected																		203	
STD OXH82 Expected																		1278	
BLK	Blank	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2		
BLK	Blank																	<2	
BLK	Blank																	<2	
BLK	Blank																	<2	
BLK	Blank																	<2	
Prep Wash																			
G1	Prep Blank	5	0.51	156	0.136	<20	0.93	0.081	0.46	<0.1	<0.01	0.3	<0.05	1.9	<0.5	4	<0.2	<2	
G1	Prep Blank	7	0.50	152	0.130	<20	0.97	0.085	0.45	0.2	<0.01	0.3	<0.05	1.7	<0.5	5	<0.2	<2	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 05, 2011
Report Date: November 03, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11001563.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #21
P.O. Number
Number of Samples: 45

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-500	45	Crush, split and pulverize 500 g rock to 200 mesh			SMI
3B	45	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	45	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001563.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1279082	Rock	1.25	16	1.1	53.8	3.4	272	0.4	65.2	10.8	211	6.34	112.5	8.8	0.6	19	0.1	1.8	<0.1	14	0.01
1279083	Rock	1.06	3	1.2	27.5	5.1	491	0.3	137.0	17.0	1372	35.82	31.0	<0.5	0.4	6	0.7	0.4	<0.1	53	<0.01
1279084	Rock	1.00	6	0.8	93.9	2.4	154	0.2	45.8	7.2	136	2.68	35.7	4.7	0.3	5	<0.1	1.1	<0.1	8	<0.01
1279085	Rock	1.26	8	1.2	53.5	9.2	129	0.7	24.0	3.0	89	3.17	16.7	<0.5	1.0	11	0.2	0.7	0.1	20	0.01
1279086	Rock	1.25	4	0.6	76.2	1.6	207	0.2	47.4	6.8	164	4.03	11.0	1.3	0.5	11	0.2	0.6	<0.1	11	<0.01
1279087	Rock	0.89	30	0.7	26.9	1.1	92	0.2	26.4	2.6	60	1.71	45.7	23.8	0.3	6	0.3	1.6	<0.1	5	<0.01
1279088	Rock	0.99	<2	0.3	26.6	1.2	72	<0.1	23.0	4.0	51	1.52	18.1	4.3	0.6	5	0.2	0.5	<0.1	6	<0.01
1279089	Rock	0.97	4	0.5	39.7	2.0	76	0.2	31.6	5.1	125	1.29	273.2	2.9	0.4	19	0.3	3.0	<0.1	7	0.01
1279090	Rock	1.25	<2	0.4	32.9	2.0	79	0.1	26.2	4.5	102	1.61	6.0	1.1	0.4	7	0.2	0.3	<0.1	6	0.13
1279091	Rock	1.35	12	1.0	68.7	7.7	88	0.8	30.1	5.3	69	1.87	8.1	2.3	1.2	20	0.3	0.4	0.2	16	0.04
1279092	Rock	1.49	<2	0.4	7.6	1.2	22	<0.1	11.9	2.1	218	2.67	2.5	0.5	0.5	44	<0.1	0.2	<0.1	6	3.79
1279093	Rock	1.04	7	0.9	6.8	4.4	93	0.3	64.1	9.2	343	4.03	8.7	3.4	0.9	20	0.4	0.5	<0.1	9	0.73
1279094	Rock	1.11	13	0.6	31.7	1.6	76	<0.1	41.8	6.3	94	1.99	177.7	9.5	0.3	2	0.2	2.2	<0.1	5	0.01
1279095	Rock	1.17	5	0.5	27.7	2.2	49	0.2	24.3	3.5	150	1.67	217.1	3.2	0.5	11	0.3	5.1	<0.1	6	<0.01
1279096	Rock	2.01	<2	0.4	16.1	0.9	43	<0.1	71.4	10.6	633	2.39	3.8	<0.5	2.9	916	0.3	<0.1	<0.1	23	24.71
1279097	Rock	1.56	<2	0.8	51.6	3.7	48	<0.1	162.2	27.1	694	3.52	11.6	0.9	9.6	296	0.2	0.2	<0.1	42	12.30
1279098	Rock	1.91	<2	0.6	39.1	3.4	16	<0.1	162.1	31.7	842	4.41	3.6	1.3	9.7	349	<0.1	0.1	<0.1	45	14.85
1279099	Rock	2.10	<2	2.2	34.9	2.7	14	<0.1	77.8	26.6	756	2.34	2.7	<0.5	7.5	334	<0.1	0.2	<0.1	27	22.15
1279100	Rock	1.77	<2	12.0	94.9	5.7	82	0.3	424.6	58.2	299	8.08	34.0	<0.5	1.3	5	0.3	2.2	<0.1	28	1.15
1283501	Rock	2.14	<2	0.4	36.5	1.8	30	<0.1	175.0	35.1	759	3.58	2.2	0.6	1.6	390	<0.1	0.2	<0.1	109	17.72
1283502	Rock	1.22	<2	6.9	76.0	14.8	50	0.4	162.4	21.8	588	17.01	6.2	<0.5	0.9	191	0.4	0.2	<0.1	41	11.85
1283503	Rock	1.48	<2	0.5	42.4	1.5	67	<0.1	163.1	27.2	815	3.51	2.1	0.9	2.3	345	0.1	0.2	<0.1	64	20.60
1283504	Rock	1.33	<2	1.0	45.1	2.0	15	<0.1	169.5	29.7	1154	4.83	36.7	<0.5	3.1	310	<0.1	0.4	<0.1	52	9.29
1283505	Rock	1.57	<2	1.0	45.1	2.1	22	<0.1	228.1	40.5	1064	4.64	1.7	<0.5	2.5	411	<0.1	<0.1	<0.1	81	10.60
1283506	Rock	2.54	<2	0.8	21.3	1.3	18	<0.1	57.3	15.8	690	1.63	8.6	0.8	1.3	791	<0.1	0.2	<0.1	21	14.65
1283507	Rock	1.17	<2	1.9	56.2	1.9	44	<0.1	58.4	26.6	1152	3.11	3.0	0.8	2.4	389	0.2	0.3	<0.1	67	13.51
1283508	Rock	2.04	<2	0.2	12.0	0.3	5	<0.1	30.5	6.7	332	1.80	1.2	0.9	0.3	258	<0.1	<0.1	<0.1	7	4.75
1283509	Rock	1.40	<2	0.9	75.7	2.5	33	<0.1	170.8	46.1	762	4.55	9.1	1.0	4.5	195	0.2	0.3	<0.1	59	6.38
1283510	Rock	1.47	<2	1.6	25.0	0.9	43	<0.1	49.8	5.2	957	3.86	0.9	0.7	0.1	831	0.5	0.1	<0.1	10	19.03
1283511	Rock	1.44	<2	0.4	15.5	1.4	23	<0.1	43.9	10.8	950	3.04	3.0	<0.5	2.4	319	<0.1	0.3	<0.1	21	19.46

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001563.1

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
		Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
		MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1279082	Rock		0.057	1	7	0.01	3528	<0.001	<20	0.27	0.001	0.03	<0.1	0.37	<0.1	0.12	2.5	17.1	<1	<0.2
1279083	Rock		0.086	3	8	0.06	3334	<0.001	<20	0.40	0.002	0.01	<0.1	0.15	<0.1	0.11	4.1	12.9	<1	<0.2
1279084	Rock		0.022	<1	5	0.01	173	<0.001	<20	0.36	<0.001	0.03	<0.1	0.17	<0.1	<0.05	2.5	2.4	<1	<0.2
1279085	Rock		0.022	1	10	0.03	525	<0.001	<20	0.44	0.005	0.09	<0.1	0.46	<0.1	<0.05	2.3	2.6	2	<0.2
1279086	Rock		0.028	<1	5	0.02	450	<0.001	<20	0.22	0.002	<0.01	<0.1	0.11	<0.1	<0.05	2.7	1.5	<1	<0.2
1279087	Rock		0.020	<1	5	<0.01	1407	<0.001	<20	0.17	0.001	<0.01	<0.1	0.13	<0.1	<0.05	1.3	0.5	<1	<0.2
1279088	Rock		0.018	<1	6	<0.01	181	<0.001	<20	0.15	0.001	<0.01	<0.1	0.07	<0.1	<0.05	1.6	1.0	<1	<0.2
1279089	Rock		0.020	<1	6	0.01	2106	<0.001	<20	0.36	0.001	0.02	<0.1	0.39	<0.1	0.08	1.3	0.8	<1	<0.2
1279090	Rock		0.016	<1	4	0.01	516	<0.001	<20	0.20	0.001	0.01	<0.1	0.09	<0.1	<0.05	1.4	0.9	<1	<0.2
1279091	Rock		0.023	1	13	0.06	794	<0.001	<20	0.52	0.008	0.11	<0.1	0.28	<0.1	<0.05	2.8	3.3	2	<0.2
1279092	Rock		0.018	2	5	0.28	93	<0.001	<20	0.13	0.001	<0.01	<0.1	0.09	<0.1	<0.05	0.9	0.7	<1	<0.2
1279093	Rock		0.068	2	8	0.03	181	<0.001	<20	0.13	0.003	0.02	<0.1	0.19	<0.1	<0.05	1.4	1.6	<1	<0.2
1279094	Rock		0.013	<1	5	0.01	40	<0.001	<20	0.18	<0.001	0.01	<0.1	0.30	<0.1	<0.05	0.5	1.3	<1	<0.2
1279095	Rock		0.023	<1	7	<0.01	3309	<0.001	<20	0.14	0.002	0.01	<0.1	0.76	<0.1	0.11	1.2	1.3	<1	<0.2
1279096	Rock		0.060	30	35	1.30	1354	0.002	<20	0.26	0.005	0.06	<0.1	0.01	<0.1	0.13	4.7	<0.5	<1	<0.2
1279097	Rock		0.175	44	65	2.86	3665	0.003	<20	0.47	0.009	0.20	<0.1	0.03	<0.1	0.12	11.6	<0.5	1	<0.2
1279098	Rock		0.162	56	70	2.91	608	0.004	<20	0.68	0.007	0.22	<0.1	0.02	<0.1	0.25	10.3	<0.5	1	<0.2
1279099	Rock		0.166	42	42	0.67	45	0.002	<20	0.78	0.010	0.14	<0.1	0.02	<0.1	0.87	9.1	<0.5	1	<0.2
1279100	Rock		0.268	5	46	0.06	14	0.003	<20	2.78	0.001	0.22	<0.1	0.57	0.3	5.21	5.9	2.8	2	<0.2
1283501	Rock		0.152	18	252	2.04	1254	0.003	<20	2.34	0.002	0.04	<0.1	<0.01	<0.1	0.11	10.0	<0.5	7	<0.2
1283502	Rock		0.067	8	85	0.83	8	0.003	<20	0.91	0.004	0.05	<0.1	0.35	0.3	>10	3.5	<0.5	3	<0.2
1283503	Rock		0.122	26	174	1.67	281	0.003	<20	1.71	0.006	0.11	<0.1	<0.01	<0.1	0.40	9.3	<0.5	5	<0.2
1283504	Rock		0.130	24	81	2.67	972	0.003	<20	0.68	0.006	0.18	<0.1	0.01	<0.1	0.14	10.3	<0.5	2	<0.2
1283505	Rock		0.168	23	145	2.39	281	0.004	<20	1.53	0.004	0.20	<0.1	<0.01	<0.1	0.48	10.3	<0.5	4	<0.2
1283506	Rock		0.082	18	28	0.22	2631	0.002	<20	0.28	0.005	0.08	<0.1	0.02	<0.1	0.15	7.9	<0.5	<1	<0.2
1283507	Rock		0.141	18	105	0.94	1789	0.004	<20	0.97	0.008	0.17	<0.1	0.02	<0.1	0.17	9.4	<0.5	3	<0.2
1283508	Rock		0.058	6	6	0.91	1110	<0.001	<20	0.20	0.004	0.04	<0.1	<0.01	<0.1	<0.05	2.4	<0.5	<1	<0.2
1283509	Rock		0.220	35	91	1.73	913	0.004	<20	1.03	0.004	0.36	<0.1	0.04	<0.1	0.16	11.7	<0.5	2	<0.2
1283510	Rock		0.008	13	5	1.93	684	<0.001	<20	0.03	0.004	0.01	<0.1	<0.01	<0.1	0.09	1.6	<0.5	<1	<0.2
1283511	Rock		0.048	24	22	4.27	980	0.001	<20	0.17	0.010	0.07	<0.1	0.01	<0.1	0.09	4.1	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001563.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285007	Rock	0.80	11	0.4	6.2	1.4	66	0.1	14.5	2.2	33	0.60	12.1	4.0	0.1	67	<0.1	0.4	<0.1	4	0.15
1285008	Rock	0.94	110	0.3	55.6	0.3	128	<0.1	35.2	2.3	43	1.41	10.2	16.8	0.3	9	0.2	0.3	<0.1	5	0.07
1285009	Rock	0.96	2	0.5	1.9	0.9	20	<0.1	2.8	0.4	4	1.05	187.5	1.2	0.2	28	1.0	55.9	<0.1	19	0.01
1285010	Rock	1.01	<2	1.2	7.1	1.1	10	0.2	1.5	0.2	16	1.34	736.5	2.2	0.6	62	0.3	21.3	<0.1	21	0.06
1285011	Rock	0.71	<2	1.0	5.5	1.0	37	<0.1	4.1	0.4	161	0.16	3.5	<0.5	<0.1	904	0.8	2.6	<0.1	31	11.41
1285012	Rock	0.93	2	0.5	34.0	2.7	71	<0.1	20.0	5.7	843	1.89	32.1	<0.5	1.4	1	0.5	0.3	0.2	6	0.04
1285101	Rock	1.87	123	11.5	38.2	9.3	271	0.8	68.4	6.5	132	1.03	88.1	<0.5	3.9	24	4.3	6.2	0.6	60	0.26
1285102	Rock	0.98	622	9.6	25.8	14.6	207	3.5	21.0	1.9	24	0.71	413.6	<0.5	1.8	48	2.9	35.9	0.1	185	1.29
1285103	Rock	1.46	351	14.5	38.4	24.8	1829	2.5	36.5	2.6	28	1.51	219.9	<0.5	0.9	55	27.1	18.4	0.2	248	0.05
1285104	Rock	2.23	246	1.1	14.3	29.3	81	1.4	5.8	1.8	20	0.58	237.9	158.0	8.2	12	0.5	1176	3.5	3	0.04
1285105	Rock	1.52	421	10.1	46.5	42.7	1537	1.8	73.8	6.5	223	1.86	225.0	7.7	0.8	13	17.5	23.7	1.2	210	0.24
1285106	Rock	1.70	1004	8.4	55.3	11.5	199	4.5	28.2	3.8	54	3.06	284.6	7.3	1.4	21	3.2	50.8	0.4	35	0.43
1285107	Rock	2.44	32	17.2	66.5	30.9	98	1.0	74.7	9.1	27	1.76	166.8	3.7	6.0	23	2.0	8.0	1.0	54	0.10
1285108	Rock	1.76	197	22.9	39.0	19.3	1205	1.4	52.3	4.5	188	0.84	117.0	<0.5	0.7	14	11.2	19.7	0.1	133	0.23
1285109	Rock	1.74	90	86.4	32.2	7.8	37	2.2	13.9	0.2	17	0.37	129.2	1.9	1.4	138	2.0	31.5	<0.1	1184	0.04

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001563.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285007	Rock	0.008	<1	3	0.02	3323	<0.001	<20	0.08	0.002	0.02	<0.1	0.26	<0.1	0.11	0.6	0.5	<1	<0.2
1285008	Rock	0.013	<1	4	0.02	3301	<0.001	<20	0.13	0.002	<0.01	<0.1	0.06	<0.1	0.11	0.9	0.7	<1	<0.2
1285009	Rock	0.023	1	5	<0.01	425	<0.001	<20	0.06	<0.001	<0.01	<0.1	6.30	<0.1	<0.05	0.2	<0.5	<1	<0.2
1285010	Rock	0.369	3	24	<0.01	846	0.002	<20	0.13	0.001	0.02	0.1	7.45	<0.1	0.09	3.0	1.3	<1	<0.2
1285011	Rock	0.010	4	2	1.93	540	<0.001	<20	0.03	0.003	<0.01	<0.1	0.04	<0.1	<0.05	0.4	<0.5	<1	<0.2
1285012	Rock	0.012	8	4	0.11	1002	<0.001	<20	0.25	<0.001	0.10	0.2	0.07	<0.1	<0.05	1.3	0.6	<1	<0.2
1285101	Rock	0.034	10	4	0.10	118	0.001	<20	0.37	0.007	0.16	0.2	6.22	1.9	0.89	0.9	8.5	<1	<0.2
1285102	Rock	0.574	7	35	0.05	223	0.004	<20	0.67	0.016	0.17	0.5	33.02	0.2	0.52	1.8	33.5	2	0.3
1285103	Rock	0.035	2	6	0.02	89	<0.001	<20	0.31	0.002	0.08	0.5	6.56	0.2	1.62	0.7	42.6	1	<0.2
1285104	Rock	0.019	21	<1	0.02	111	<0.001	<20	0.30	0.006	0.23	<0.1	16.42	0.7	0.12	0.8	19.9	<1	<0.2
1285105	Rock	0.099	2	9	0.02	28	0.001	<20	0.37	0.007	0.08	0.4	12.30	0.6	1.37	1.7	26.4	1	<0.2
1285106	Rock	0.192	5	12	0.03	33	0.002	<20	0.45	0.009	0.14	0.5	27.32	3.7	3.42	1.3	28.5	1	0.3
1285107	Rock	0.039	11	6	0.07	133	0.002	<20	0.73	0.009	0.26	0.2	7.28	0.9	1.53	1.6	4.9	1	<0.2
1285108	Rock	0.021	2	4	0.10	162	<0.001	<20	0.18	0.004	0.06	0.6	23.16	0.5	0.56	0.9	13.5	<1	<0.2
1285109	Rock	0.083	11	62	0.08	406	0.005	<20	0.53	<0.001	0.17	0.3	35.63	1.0	0.10	3.1	28.2	3	0.6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

QUALITY CONTROL REPORT WHI11001563.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1279082	Rock	1.25	16	1.1	53.8	3.4	272	0.4	65.2	10.8	211	6.34	112.5	8.8	0.6	19	0.1	1.8	<0.1	14	0.01
REP 1279082	QC			1.0	55.1	3.5	274	0.3	65.3	10.5	206	6.13	110.8	9.3	0.5	20	0.1	1.8	<0.1	13	0.01
1279086	Rock	1.25	4	0.6	76.2	1.6	207	0.2	47.4	6.8	164	4.03	11.0	1.3	0.5	11	0.2	0.6	<0.1	11	<0.01
REP 1279086	QC		3																		
1285107	Rock	2.44	32	17.2	66.5	30.9	98	1.0	74.7	9.1	27	1.76	166.8	3.7	6.0	23	2.0	8.0	1.0	54	0.10
REP 1285107	QC		32																		
Core Reject Duplicates																					
1283504	Rock	1.33	<2	1.0	45.1	2.0	15	<0.1	169.5	29.7	1154	4.83	36.7	<0.5	3.1	310	<0.1	0.4	<0.1	52	9.29
DUP 1283504	QC		<2	1.1	45.6	1.9	14	<0.1	168.9	29.0	1124	4.74	36.8	0.5	3.0	308	<0.1	0.5	<0.1	52	9.31
Reference Materials																					
STD DS8	Standard			14.4	111.3	128.4	319	1.9	39.3	7.3	611	2.57	24.3	103.4	7.2	73	2.3	5.1	7.0	43	0.73
STD DS8	Standard			12.9	100.1	121.6	300	1.7	35.3	6.9	581	2.40	24.3	91.0	6.8	70	2.1	4.5	7.9	39	0.69
STD OREAS45CA	Standard			0.9	504.4	21.0	64	0.3	261.9	86.4	943	16.41	4.2	46.1	7.6	18	<0.1	0.1	0.2	211	0.44
STD OREAS45CA	Standard			0.8	509.1	20.5	61	0.3	250.3	85.4	910	14.59	4.0	45.8	7.4	17	<0.1	<0.1	0.2	205	0.41
STD OXC88	Standard		210																		
STD OXC88	Standard		201																		
STD OXH82	Standard		1326																		
STD OXH82	Standard		1312																		
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

QUALITY CONTROL REPORT WHI11001563.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1279082	Rock	0.057	1	7	0.01	3528	<0.001	<20	0.27	0.001	0.03	<0.1	0.37	<0.1	0.12	2.5	17.1	<1	<0.2
REP 1279082	QC	0.061	1	7	0.01	3752	<0.001	<20	0.27	0.001	0.03	<0.1	0.40	<0.1	0.12	2.5	17.0	<1	<0.2
1279086	Rock	0.028	<1	5	0.02	450	<0.001	<20	0.22	0.002	<0.01	<0.1	0.11	<0.1	<0.05	2.7	1.5	<1	<0.2
REP 1279086	QC																		
1285107	Rock	0.039	11	6	0.07	133	0.002	<20	0.73	0.009	0.26	0.2	7.28	0.9	1.53	1.6	4.9	1	<0.2
REP 1285107	QC																		
Core Reject Duplicates																			
1283504	Rock	0.130	24	81	2.67	972	0.003	<20	0.68	0.006	0.18	<0.1	0.01	<0.1	0.14	10.3	<0.5	2	<0.2
DUP 1283504	QC	0.134	23	83	2.60	2573	0.004	<20	0.69	0.005	0.18	<0.1	0.02	<0.1	0.14	10.4	<0.5	2	<0.2
Reference Materials																			
STD DS8	Standard	0.079	15	118	0.63	310	0.110	<20	0.95	0.094	0.44	2.8	0.20	5.3	0.17	2.0	5.7	5	5.2
STD DS8	Standard	0.074	14	106	0.60	281	0.100	<20	0.92	0.083	0.40	2.6	0.21	5.2	0.16	1.8	4.6	4	4.4
STD OREAS45CA	Standard	0.038	16	646	0.18	163	0.138	<20	3.84	0.010	0.08	<0.1	0.03	<0.1	<0.05	38.7	<0.5	19	0.2
STD OREAS45CA	Standard	0.037	16	599	0.17	161	0.123	<20	3.81	0.008	0.07	<0.1	0.06	0.1	<0.05	36.9	<0.5	19	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXC88 Expected																			
STD OXH82 Expected																			
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

QUALITY CONTROL REPORT WHI11001563.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
Prep Wash																					
G1	Prep Blank		<2	<0.1	2.1	3.2	43	<0.1	1.9	3.4	507	1.82	1.3	2.7	7.4	60	<0.1	<0.1	0.3	36	0.43
G1	Prep Blank		<2	0.1	1.7	3.1	44	<0.1	1.9	3.4	515	1.87	0.7	1.6	5.3	57	<0.1	<0.1	<0.1	37	0.44

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

QUALITY CONTROL REPORT WHI11001563.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
Prep Wash																			
G1	Prep Blank	0.065	12	4	0.49	157	0.114	<20	0.88	0.083	0.49	0.2	<0.01	0.2	<0.05	1.7	<0.5	4	<0.2
G1	Prep Blank	0.073	12	4	0.50	156	0.116	<20	0.83	0.077	0.46	<0.1	<0.01	0.2	<0.05	1.8	<0.5	4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 14, 2011
Report Date: November 14, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11001690.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #26
P.O. Number
Number of Samples: 39

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-500	37	Crush, split and pulverize 500 g rock to 200 mesh			VAN
3B	37	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	37	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001690.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285165	Rock	6.75	9	7.9	13.1	7.9	3	0.5	4.4	<0.1	11	0.51	28.9	<0.5	1.1	9	<0.1	4.3	0.1	64	<0.01
1285166	Rock	7.18	86	10.7	14.7	7.9	15	2.1	5.7	0.2	16	0.82	58.1	<0.5	1.3	23	0.3	7.8	0.1	78	<0.01
1285167	Rock	7.94	11	9.9	23.4	10.0	80	2.7	13.9	0.9	23	1.35	54.7	0.6	2.4	29	0.2	6.6	0.3	87	0.03
1093992	Rock	1.63	<2	0.3	14.7	1.8	5	<0.1	7.4	1.6	65	0.81	11.8	<0.5	0.1	3	<0.1	0.3	<0.1	4	<0.01
1093993	Rock	1.57	<2	0.7	16.2	4.0	144	<0.1	38.9	10.9	218	1.97	7.1	<0.5	2.2	28	2.3	0.2	0.1	17	0.10
1093994	Rock	1.81	<2	0.5	11.6	10.3	89	0.1	20.7	4.5	633	3.26	91.2	<0.5	1.0	57	0.2	1.0	<0.1	17	4.19
1093995	Rock	1.11	<2	0.2	11.3	2.5	47	<0.1	18.5	2.3	83	1.05	13.5	<0.5	<0.1	24	0.1	0.9	<0.1	<2	0.03
1093996	Rock	1.73	<2	0.2	47.6	0.5	217	<0.1	52.4	10.8	244	2.97	7.4	<0.5	0.2	3	<0.1	0.4	<0.1	8	<0.01
1093997	Rock	1.32	<2	0.4	22.8	3.0	33	0.3	15.3	1.6	50	0.98	12.1	<0.5	0.6	68	<0.1	0.4	<0.1	3	<0.01
1285042	Rock	0.93	240	8.7	11.9	9.6	6	0.7	1.3	0.2	45	0.72	56.3	16.6	2.6	131	0.6	22.2	0.1	91	0.03
1285043	Rock	0.98	31	5.1	2.5	30.5	4	1.4	1.1	0.1	12	0.85	38.8	25.1	8.6	49	<0.1	16.5	0.3	64	0.02
1285044	Rock	1.03	20	1.4	4.4	23.6	3	0.7	1.3	0.2	37	0.81	10.7	3.4	0.5	8	<0.1	3.7	<0.1	12	<0.01
1285045	Rock	0.97	57	5.2	20.4	10.5	2	0.7	1.5	0.1	27	1.45	222.6	8.8	0.5	46	0.2	6.9	<0.1	116	<0.01
1285046	Rock	0.83	15	1.1	4.3	13.1	5	0.4	2.7	0.3	47	0.70	16.2	2.7	0.4	9	0.4	2.5	0.4	12	<0.01
1285047	Rock	0.90	49	2.6	12.0	6.6	6	0.3	1.9	0.3	40	1.71	22.8	11.1	0.4	16	<0.1	7.8	<0.1	24	<0.01
1285048	Rock	1.00	17	4.9	5.9	10.4	12	0.5	1.8	0.1	28	1.68	35.1	3.2	0.9	180	<0.1	3.7	<0.1	74	0.03
1285049	Rock	0.88	38	0.4	1.5	10.7	<1	0.5	0.9	0.1	40	0.45	8.0	10.7	0.5	25	<0.1	1.9	<0.1	11	<0.01
1285050	Rock	1.08	3	1.9	11.8	7.2	174	0.2	9.0	0.8	37	1.60	21.9	<0.5	0.4	39	<0.1	1.0	<0.1	31	<0.01
1285051	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1285052	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1285168	Rock	6.68	19	17.6	11.5	21.3	63	1.6	9.7	0.8	23	1.81	59.3	<0.5	3.3	29	0.2	3.8	0.2	55	<0.01
1285170	Rock	9.48	6	4.2	13.8	55.9	164	0.7	18.4	3.6	34	1.90	139.9	<0.5	9.2	65	0.1	1.9	0.8	35	<0.01
1285171	Rock	7.36	7	8.5	16.5	24.3	64	0.5	12.1	1.5	19	1.92	61.1	<0.5	5.2	42	0.1	1.0	0.3	46	<0.01
1285172	Rock	7.29	20	5.0	15.4	34.2	51	1.3	8.4	1.9	28	2.36	133.7	<0.5	6.0	39	0.1	2.2	0.4	28	<0.01
1285291	Rock	1.54	<2	0.9	13.2	4.2	121	<0.1	27.8	4.8	392	2.57	1.7	<0.5	0.2	4	0.2	0.2	<0.1	16	0.01
1285292	Rock	1.68	<2	1.2	31.6	7.6	207	<0.1	23.4	4.8	413	2.53	21.7	<0.5	0.3	74	0.5	0.6	<0.1	11	1.87
1285293	Rock	1.17	5	0.1	1.0	50.2	47	<0.1	3.8	0.7	49	0.48	398.1	3.4	1.1	4	<0.1	0.3	1.6	<2	<0.01
1285294	Rock	1.45	132	5.3	11.0	60.0	66	0.3	7.4	0.4	44	0.78	631.2	75.6	1.3	38	1.0	1.4	2.1	29	0.03
1285295	Rock	1.28	8	10.3	39.0	51.3	106	1.2	23.2	0.4	37	0.75	117.5	3.8	1.1	95	2.2	1.7	1.4	147	0.20
1285296	Rock	1.12	37	2.6	22.4	69.5	145	<0.1	7.6	0.7	24	0.63	1277	29.1	1.1	59	1.3	0.4	2.1	15	0.02

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001690.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285165	Rock	0.009	1	4	0.01	156	0.001	<20	0.29	0.003	0.13	<0.1	2.03	0.3	0.08	0.9	5.6	1	<0.2
1285166	Rock	0.059	3	5	0.01	185	<0.001	<20	0.30	0.002	0.13	<0.1	13.39	0.4	0.13	1.4	12.6	1	<0.2
1285167	Rock	0.101	7	6	0.01	191	0.001	<20	0.35	0.001	0.13	<0.1	4.50	0.4	0.13	3.5	17.3	1	<0.2
1093992	Rock	0.011	<1	3	<0.01	19	<0.001	<20	0.06	<0.001	0.01	0.3	0.04	<0.1	<0.05	0.4	<0.5	<1	<0.2
1093993	Rock	0.047	3	9	0.03	1090	<0.001	<20	0.42	0.005	0.12	<0.1	0.03	<0.1	<0.05	3.0	1.1	<1	<0.2
1093994	Rock	0.030	1	10	0.69	552	<0.001	<20	0.14	0.003	0.05	0.2	0.03	<0.1	0.06	2.3	0.6	<1	<0.2
1093995	Rock	0.006	<1	3	<0.01	2368	<0.001	<20	0.14	<0.001	<0.01	0.3	0.01	<0.1	0.07	0.3	<0.5	<1	<0.2
1093996	Rock	0.023	<1	7	0.01	216	<0.001	<20	0.21	<0.001	<0.01	<0.1	0.02	<0.1	<0.05	1.3	1.2	<1	<0.2
1093997	Rock	0.017	1	4	<0.01	312	<0.001	<20	0.12	<0.001	0.01	0.1	0.26	<0.1	<0.05	0.9	2.1	<1	<0.2
1285042	Rock	0.067	8	12	<0.01	56	<0.001	<20	0.22	<0.001	0.09	0.8	10.57	0.9	0.09	0.6	4.5	2	<0.2
1285043	Rock	0.033	32	2	0.03	437	<0.001	<20	0.57	<0.001	0.18	<0.1	6.28	2.0	0.21	0.9	9.7	2	<0.2
1285044	Rock	0.005	<1	4	<0.01	1850	<0.001	<20	0.12	<0.001	0.05	<0.1	3.45	0.1	0.10	0.3	5.1	<1	<0.2
1285045	Rock	0.048	<1	15	<0.01	398	<0.001	<20	0.17	<0.001	0.11	0.1	1.11	0.3	0.16	1.2	10.3	2	<0.2
1285046	Rock	0.005	<1	4	<0.01	447	<0.001	<20	0.13	0.002	0.09	<0.1	1.00	<0.1	0.12	0.3	1.5	<1	<0.2
1285047	Rock	0.036	<1	7	<0.01	2984	<0.001	<20	0.16	<0.001	0.05	0.1	0.90	<0.1	0.07	1.3	5.0	<1	<0.2
1285048	Rock	0.102	1	11	<0.01	1225	<0.001	<20	0.24	<0.001	0.08	<0.1	1.22	<0.1	0.10	1.5	6.0	2	<0.2
1285049	Rock	0.012	3	4	<0.01	517	<0.001	<20	0.13	0.001	0.05	0.3	1.00	<0.1	<0.05	0.4	1.7	<1	<0.2
1285050	Rock	0.044	<1	8	<0.01	91	<0.001	<20	0.21	0.001	0.06	<0.1	0.08	<0.1	<0.05	2.6	1.9	<1	<0.2
1285051	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1285052	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1285168	Rock	0.045	14	6	0.01	207	<0.001	<20	0.32	0.006	0.19	<0.1	3.92	0.6	0.27	1.8	11.3	1	<0.2
1285170	Rock	0.062	27	4	0.02	331	<0.001	<20	0.48	0.004	0.24	<0.1	4.71	0.4	0.13	2.4	5.8	1	<0.2
1285171	Rock	0.028	29	7	0.01	191	<0.001	<20	0.44	0.006	0.21	<0.1	4.76	0.9	0.20	1.5	5.9	1	<0.2
1285172	Rock	0.030	32	<1	0.01	195	<0.001	<20	0.44	0.005	0.20	<0.1	7.23	0.8	0.20	1.6	5.0	2	<0.2
1285291	Rock	0.011	<1	6	0.03	24	<0.001	<20	0.15	<0.001	0.01	0.2	0.03	<0.1	<0.05	1.3	<0.5	<1	<0.2
1285292	Rock	0.019	<1	6	0.39	57	<0.001	<20	0.11	0.001	0.03	<0.1	0.07	<0.1	<0.05	1.6	0.8	<1	<0.2
1285293	Rock	0.007	<1	<1	<0.01	97	<0.001	<20	0.46	0.001	0.22	0.1	0.29	0.1	<0.05	0.2	<0.5	<1	<0.2
1285294	Rock	0.041	1	2	0.01	934	<0.001	<20	0.44	0.002	0.25	0.1	2.94	0.5	0.06	1.0	5.8	<1	<0.2
1285295	Rock	0.102	2	7	0.02	146	<0.001	<20	0.49	<0.001	0.25	0.2	4.71	0.6	0.07	0.9	9.4	1	<0.2
1285296	Rock	0.019	1	2	<0.01	2267	<0.001	<20	0.44	0.002	0.24	<0.1	1.14	0.4	0.08	0.7	1.7	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001690.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285297	Rock	1.76	10	9.1	32.0	61.1	240	0.3	16.9	1.5	72	1.09	258.3	3.1	1.5	46	1.0	1.0	2.1	55	0.05
1285298	Rock	1.93	<2	5.3	14.4	63.4	294	<0.1	19.4	5.5	432	0.89	721.2	1.9	1.1	47	4.9	0.6	1.8	17	0.07
1285299	Rock	1.02	55	3.4	102.2	9.7	131	0.4	50.8	15.6	180	3.73	3680	5.3	7.7	26	0.3	2.1	0.6	88	0.46
1285300	Rock	1.72	<2	0.6	13.9	7.4	185	<0.1	43.0	15.5	809	3.33	33.1	1.7	0.5	18	0.4	0.3	<0.1	13	1.33
1285162	Rock	6.94	8	6.0	11.1	12.4	3	0.4	3.9	0.1	10	0.45	12.2	<0.5	1.6	18	<0.1	1.9	0.2	45	<0.01
1285163	Rock	6.49	11	5.5	11.6	12.3	3	0.3	3.7	<0.1	10	0.45	9.1	1.8	1.0	9	<0.1	3.7	0.2	48	<0.01
1285164	Rock	7.48	12	9.4	12.6	10.1	6	0.3	5.0	0.2	11	0.65	29.7	1.6	1.2	8	<0.1	8.8	0.2	78	<0.01
1285351	Rock	1.02	4	21.4	176.9	11.9	145	2.3	74.0	1.3	23	3.06	22.3	<0.5	1.0	80	0.7	15.9	0.1	146	0.09
1285352	Rock	1.26	2	0.7	20.4	8.3	462	0.1	17.8	5.3	520	2.79	132.5	<0.5	0.5	29	1.4	1.6	<0.1	17	1.75

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001690.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285297	Rock	0.040	2	2	0.01	142	<0.001	<20	0.54	0.001	0.27	0.1	1.43	0.4	<0.05	0.6	5.0	1	<0.2
1285298	Rock	0.025	<1	2	0.01	358	<0.001	<20	0.50	0.002	0.24	<0.1	0.53	0.4	<0.05	0.5	0.9	<1	<0.2
1285299	Rock	0.059	7	47	0.98	204	0.076	<20	2.31	0.034	0.75	0.1	0.03	0.4	0.86	3.0	3.5	7	<0.2
1285300	Rock	0.021	<1	8	0.12	234	<0.001	<20	0.13	0.001	0.03	<0.1	0.04	<0.1	<0.05	1.7	0.6	<1	<0.2
1285162	Rock	0.008	2	5	0.01	197	<0.001	<20	0.40	0.004	0.16	<0.1	0.64	0.5	0.10	1.0	2.3	1	<0.2
1285163	Rock	0.004	<1	<1	0.01	213	<0.001	<20	0.34	0.005	0.14	<0.1	0.65	0.3	0.09	1.0	2.0	1	<0.2
1285164	Rock	0.006	1	5	<0.01	170	<0.001	<20	0.35	0.003	0.12	<0.1	1.31	0.3	<0.05	1.0	9.2	1	<0.2
1285351	Rock	0.204	2	11	<0.01	293	<0.001	<20	3.71	<0.001	0.05	<0.1	2.09	0.2	0.16	3.6	61.1	2	<0.2
1285352	Rock	0.033	<1	17	0.13	655	<0.001	<20	0.16	0.002	0.04	<0.1	0.16	<0.1	<0.05	2.4	1.1	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

QUALITY CONTROL REPORT WHI11001690.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1093996	Rock	1.73	<2	0.2	47.6	0.5	217	<0.1	52.4	10.8	244	2.97	7.4	<0.5	0.2	3	<0.1	0.4	<0.1	8	<0.01
REP 1093996	QC			0.2	48.4	0.6	219	<0.1	51.3	10.6	242	3.01	8.4	<0.5	0.2	4	<0.1	0.4	<0.1	8	<0.01
1285171	Rock	7.36	7	8.5	16.5	24.3	64	0.5	12.1	1.5	19	1.92	61.1	<0.5	5.2	42	0.1	1.0	0.3	46	<0.01
REP 1285171	QC		5																		
Core Reject Duplicates																					
1093993	Rock	1.57	<2	0.7	16.2	4.0	144	<0.1	38.9	10.9	218	1.97	7.1	<0.5	2.2	28	2.3	0.2	0.1	17	0.10
DUP 1093993	QC		<2	0.7	16.7	3.7	145	<0.1	38.7	11.2	220	2.02	7.1	<0.5	2.1	28	2.0	<0.1	<0.1	18	0.10
Reference Materials																					
STD DS8	Standard			14.0	112.7	112.4	313	1.9	37.4	7.7	624	2.51	25.4	82.6	6.6	70	2.4	5.3	7.1	41	0.72
STD DS8	Standard			14.5	110.3	129.3	309	1.8	37.0	7.2	599	2.53	26.9	107.3	7.1	74	2.5	5.4	6.3	41	0.73
STD OREAS45CA	Standard			0.8	531.7	21.4	63	0.3	270.6	89.9	921	15.33	3.0	39.5	7.2	17	0.1	<0.1	0.2	209	0.41
STD OREAS45CA	Standard			0.7	501.9	20.6	61	0.3	272.2	89.2	956	15.18	4.0	47.0	7.0	17	<0.1	0.1	0.2	207	0.43
STD OXC88	Standard		198																		
STD OXC88	Standard		193																		
STD OXH82	Standard		1271																		
STD OXH82	Standard		1277																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
Prep Wash																					
G1	Prep Blank		<2	0.2	4.4	3.6	49	<0.1	3.3	4.1	610	2.20	<0.5	1.2	5.7	66	<0.1	<0.1	<0.1	40	0.48

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

QUALITY CONTROL REPORT WHI11001690.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1093996	Rock	0.023	<1	7	0.01	216	<0.001	<20	0.21	<0.001	<0.01	<0.1	0.02	<0.1	<0.05	1.3	1.2	<1	<0.2
REP 1093996	QC	0.024	<1	7	0.02	217	<0.001	<20	0.21	<0.001	<0.01	<0.1	0.02	<0.1	<0.05	1.3	1.3	<1	<0.2
1285171	Rock	0.028	29	7	0.01	191	<0.001	<20	0.44	0.006	0.21	<0.1	4.76	0.9	0.20	1.5	5.9	1	<0.2
REP 1285171	QC																		
Core Reject Duplicates																			
1093993	Rock	0.047	3	9	0.03	1090	<0.001	<20	0.42	0.005	0.12	<0.1	0.03	<0.1	<0.05	3.0	1.1	<1	<0.2
DUP 1093993	QC	0.044	3	9	0.03	1021	<0.001	<20	0.40	0.005	0.12	<0.1	0.02	<0.1	<0.05	3.0	<0.5	<1	<0.2
Reference Materials																			
STD DS8	Standard	0.079	15	112	0.62	279	0.122	<20	0.92	0.082	0.41	2.5	0.24	4.5	0.16	2.3	4.7	5	4.7
STD DS8	Standard	0.081	16	110	0.61	299	0.112	<20	0.94	0.087	0.41	2.5	0.20	5.6	0.16	2.0	4.7	5	4.6
STD OREAS45CA	Standard	0.037	18	650	0.18	168	0.146	<20	3.95	0.006	0.07	<0.1	0.03	<0.1	<0.05	39.7	<0.5	18	<0.2
STD OREAS45CA	Standard	0.039	17	623	0.17	167	0.121	<20	3.83	0.006	0.08	<0.1	0.03	<0.1	<0.05	36.8	<0.5	19	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
STD OXC88 Expected																			
STD OXH82 Expected																			
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
Prep Wash																			
G1	Prep Blank	0.079	14	6	0.55	164	0.149	<20	0.94	0.077	0.50	0.1	<0.01	0.3	<0.05	1.9	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

QUALITY CONTROL REPORT WHI11001690.1

		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
G1	Prep Blank		<2	0.2	4.3	3.7	51	<0.1	3.2	3.9	586	2.11	0.9	<0.5	5.8	64	<0.1	<0.1	<0.1	40	0.49

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

QUALITY CONTROL REPORT WHI11001690.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
G1	Prep Blank	0.074	14	6	0.53	160	0.143	<20	0.92	0.077	0.48	0.2	<0.01	0.3	<0.05	2.0	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 15, 2011
Report Date: November 21, 2011
Page: 1 of 5

CERTIFICATE OF ANALYSIS WHI11001691.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #25
P.O. Number
Number of Samples: 113

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	112	Crush, split and pulverize 250 g rock to 200 mesh			VAN
3B	112	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	112	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

CERTIFICATE OF ANALYSIS WHI11001691.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285158	Rock	8.49	4	7.0	5.9	8.9	2	0.2	1.9	<0.1	17	0.50	5.6	<0.5	0.9	9	<0.1	1.4	0.1	41	<0.01
1285156	Rock	7.71	<2	11.7	7.6	11.3	2	<0.1	1.7	<0.1	7	0.49	10.9	1.3	1.0	8	<0.1	2.2	0.2	37	<0.01
1282451	Rock	0.61	908	0.9	113.6	30.6	73	38.8	1.9	1.0	31	0.80	1251	612.6	<0.1	8	3.9	>2000	4.9	<2	<0.01
1093987	Rock	1.12	<2	0.8	2.9	0.7	68	<0.1	6.6	0.8	77	0.79	1.7	<0.5	<0.1	31	0.5	16.3	<0.1	<2	0.07
1093988	Rock	1.48	<2	3.1	23.2	2.1	26	0.4	5.6	0.3	57	0.78	29.6	1.3	0.2	97	0.2	35.6	<0.1	23	0.05
1093989	Rock	1.71	<2	22.1	21.7	7.3	147	0.1	27.1	0.4	50	0.96	36.2	<0.5	0.5	140	1.1	9.2	<0.1	321	0.02
1093990	Rock	2.88	4	0.4	1.6	0.5	5	<0.1	1.1	<0.1	4	0.02	0.5	2.2	<0.1	276	0.1	1.5	<0.1	50	0.01
1093991	Rock	1.60	<2	0.9	11.2	0.8	4	0.1	1.0	0.1	64	0.61	13.9	0.7	<0.1	20	<0.1	4.8	<0.1	4	<0.01
1285201	Rock	5.20	292	312.4	51.1	11.8	428	3.4	78.5	2.5	36	4.56	1427	144.8	2.2	186	5.7	596.8	0.3	258	<0.01
1285202	Rock	7.66	226	16.8	55.1	8.8	18	1.9	3.5	0.4	24	0.90	72.8	96.6	1.2	21	1.0	105.2	0.2	204	0.02
1285203	Rock	8.89	211	27.8	57.8	9.8	53	2.1	8.4	0.8	40	1.30	136.5	31.9	0.9	97	1.0	185.1	0.4	197	0.01
1285204	Rock	7.00	279	5.9	30.5	14.7	17	1.5	2.2	0.2	21	0.45	39.3	148.0	1.3	31	0.6	51.3	0.4	115	<0.01
1285205	Rock	6.68	209	29.7	44.3	15.4	21	1.9	4.1	0.5	37	1.20	79.5	41.9	1.6	97	0.6	85.9	0.3	200	0.02
1285206	Rock	6.93	236	20.7	35.7	14.7	15	1.9	3.8	0.3	32	1.02	60.2	53.5	1.9	80	0.8	60.8	0.3	182	0.03
1285220	Rock	6.93	28	73.5	69.9	11.6	37	1.1	4.7	0.4	32	1.84	199.3	7.4	1.1	7	0.7	45.2	<0.1	351	<0.01
1285221	Rock	5.95	21	45.3	64.8	8.3	34	0.7	5.3	0.6	37	2.25	134.8	2.1	1.0	17	0.4	33.4	0.1	342	<0.01
1285222	Rock	6.45	12	32.4	59.0	10.8	44	0.9	5.4	0.4	22	2.04	72.8	5.4	1.4	60	0.3	43.2	<0.1	284	<0.01
1285151	Rock	6.08	4	16.2	50.2	16.2	760	2.0	62.0	9.3	44	3.98	97.0	0.8	2.3	31	0.4	13.5	0.2	196	<0.01
1285152	Rock	8.03	3	11.3	10.6	12.1	4	0.3	3.2	0.1	5	0.46	3.7	<0.5	1.4	7	<0.1	1.6	0.1	40	<0.01
1285153	Rock	7.53	<2	7.1	4.2	11.8	2	0.1	2.6	<0.1	5	0.28	3.4	<0.5	1.1	7	<0.1	1.4	0.1	28	<0.01
1285213	Rock	7.11	43	25.1	55.0	9.9	100	0.7	21.2	2.1	53	1.23	91.6	5.1	1.8	54	1.4	30.1	0.2	153	0.08
1285214	Rock	6.97	31	46.7	71.5	9.7	89	0.7	18.9	1.3	40	1.70	153.9	5.1	1.2	47	1.4	50.8	<0.1	193	0.06
1285215	Rock	7.06	28	52.9	50.9	11.0	131	1.1	27.6	1.5	46	1.54	174.0	11.2	1.6	88	1.2	50.4	0.1	177	0.09
1285223	Rock	8.13	<2	7.1	33.0	12.8	10	1.0	2.7	0.1	15	0.75	42.4	1.2	1.2	99	0.3	21.2	<0.1	200	0.02
1285224	Rock	6.39	7	19.1	52.1	17.2	17	1.3	5.3	0.2	30	1.44	62.8	<0.5	1.4	81	0.3	45.1	<0.1	285	<0.01
1285225	Rock	6.37	64	45.0	66.3	14.5	226	1.0	48.1	3.3	65	1.70	150.3	27.3	2.1	46	3.0	46.2	0.1	257	0.06
1285210	Rock	6.14	68	37.1	116.2	19.5	79	1.4	13.9	1.1	27	1.72	104.0	23.8	2.4	135	1.3	54.0	0.2	211	0.08
1285211	Rock	6.25	33	32.9	71.7	16.8	263	0.8	54.0	5.0	99	1.92	100.1	9.8	2.7	52	2.1	9.6	0.4	218	0.13
1285212	Rock	7.40	34	21.6	50.6	12.8	100	0.8	22.9	2.4	64	1.14	82.6	11.4	1.6	39	1.4	11.4	0.1	182	0.07
1285207	Rock	6.17	110	11.6	23.7	33.7	11	1.6	2.5	0.2	18	0.67	56.4	36.0	8.2	85	0.6	6.1	0.5	96	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

CERTIFICATE OF ANALYSIS WHI11001691.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285158	Rock	0.003	1	3	<0.01	162	<0.001	<20	0.33	0.006	0.15	<0.1	0.27	0.4	0.11	0.8	1.1	1	<0.2
1285156	Rock	0.007	<1	4	0.02	185	<0.001	<20	0.38	0.005	0.13	<0.1	0.13	0.4	<0.05	0.8	1.0	2	<0.2
1282451	Rock	0.008	1	5	0.01	73	<0.001	56	0.28	<0.001	0.17	<0.1	65.51	1.9	1.39	<0.1	52.8	<1	<0.2
1093987	Rock	0.028	<1	5	<0.01	108	<0.001	<20	0.10	0.003	0.05	<0.1	0.06	<0.1	<0.05	0.3	<0.5	<1	<0.2
1093988	Rock	0.087	<1	5	<0.01	56	<0.001	<20	0.16	<0.001	0.02	<0.1	2.06	0.2	<0.05	0.2	0.7	<1	<0.2
1093989	Rock	0.029	1	16	<0.01	2001	0.002	32	0.18	<0.001	0.03	0.1	0.13	0.6	0.10	1.2	2.5	<1	<0.2
1093990	Rock	<0.001	<1	<1	<0.01	1187	0.003	<20	0.01	<0.001	<0.01	<0.1	0.14	0.1	0.08	<0.1	<0.5	<1	<0.2
1093991	Rock	0.016	<1	5	<0.01	1062	<0.001	<20	0.04	0.002	<0.01	<0.1	0.78	<0.1	<0.05	<0.1	0.9	<1	<0.2
1285201	Rock	0.076	9	16	0.02	744	0.001	47	0.43	<0.001	0.17	2.0	96.00	3.5	0.20	1.8	36.6	1	0.5
1285202	Rock	0.010	11	14	0.02	482	0.002	36	0.40	<0.001	0.11	0.6	98.96	0.9	<0.05	0.2	6.9	<1	1.0
1285203	Rock	0.040	5	18	0.02	510	0.002	<20	0.35	<0.001	0.13	1.0	>100	1.3	0.11	3.2	7.2	1	0.3
1285204	Rock	0.013	11	17	0.02	725	0.002	62	0.43	<0.001	0.11	0.3	98.20	1.0	<0.05	1.8	8.3	1	<0.2
1285205	Rock	0.040	9	18	0.02	1007	0.001	33	0.43	<0.001	0.14	3.3	38.53	0.8	0.11	1.2	7.4	2	<0.2
1285206	Rock	0.024	9	15	0.02	545	0.001	38	0.43	<0.001	0.12	2.1	49.75	1.3	0.08	1.0	11.6	2	0.2
1285220	Rock	0.027	6	17	0.02	179	0.001	<20	0.35	<0.001	0.10	0.4	3.61	1.1	<0.05	0.8	20.4	1	<0.2
1285221	Rock	0.039	6	14	0.02	242	0.001	<20	0.30	<0.001	0.11	0.4	2.47	1.4	<0.05	0.8	35.0	1	0.3
1285222	Rock	0.058	7	20	0.02	179	0.001	<20	0.28	<0.001	0.11	0.5	1.60	2.7	<0.05	1.0	13.3	1	0.3
1285151	Rock	0.185	4	29	0.02	522	<0.001	<20	0.62	0.008	0.21	<0.1	0.22	0.9	0.21	6.5	20.2	2	<0.2
1285152	Rock	0.008	1	8	0.01	227	<0.001	<20	0.35	0.006	0.15	<0.1	0.10	0.3	0.09	0.8	4.7	1	<0.2
1285153	Rock	0.004	1	4	<0.01	193	<0.001	<20	0.32	0.005	0.11	<0.1	0.14	0.3	0.08	0.6	0.8	1	<0.2
1285213	Rock	0.050	9	10	0.04	926	0.001	<20	0.35	0.001	0.09	0.4	6.65	1.0	<0.05	1.2	5.4	1	<0.2
1285214	Rock	0.044	5	9	0.02	786	0.001	<20	0.27	0.001	0.08	0.4	5.87	1.7	<0.05	0.8	9.2	1	0.2
1285215	Rock	0.043	8	9	0.03	555	0.001	<20	0.32	0.001	0.10	0.8	4.70	2.6	0.09	1.3	10.1	1	<0.2
1285223	Rock	0.061	7	13	0.01	477	<0.001	<20	0.26	<0.001	0.09	0.4	2.19	2.2	<0.05	0.8	4.6	1	0.2
1285224	Rock	0.060	7	19	0.02	163	0.001	<20	0.27	<0.001	0.10	0.6	2.58	2.9	0.05	0.9	6.8	1	0.2
1285225	Rock	0.049	11	21	0.05	1205	0.003	<20	0.53	<0.001	0.10	0.6	6.46	1.1	<0.05	1.9	14.3	2	0.3
1285210	Rock	0.076	10	19	0.03	591	0.001	<20	0.40	0.003	0.16	1.2	3.20	2.2	0.16	1.9	9.6	2	0.3
1285211	Rock	0.082	13	19	0.07	934	0.002	<20	0.57	<0.001	0.13	0.2	5.16	1.1	0.06	2.0	5.8	1	<0.2
1285212	Rock	0.051	10	15	0.04	974	0.001	<20	0.38	<0.001	0.10	0.4	4.16	1.0	0.05	1.3	5.5	1	<0.2
1285207	Rock	0.033	25	10	0.01	366	<0.001	<20	0.38	0.002	0.16	0.4	11.34	1.1	0.12	0.8	5.3	2	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

CERTIFICATE OF ANALYSIS WHI11001691.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285208	Rock	6.92	35	13.4	78.8	10.2	15	1.4	4.4	0.2	23	0.56	44.2	17.4	2.0	235	0.8	14.4	0.1	271	0.11
1285209	Rock	5.61	57	17.2	63.9	8.2	11	0.9	2.5	0.2	15	0.71	50.5	20.9	1.3	71	0.7	9.8	<0.1	164	0.01
1285154	Rock	8.26	3	7.6	4.8	10.4	2	0.1	2.6	<0.1	5	0.31	3.5	<0.5	1.0	7	<0.1	0.9	0.1	32	<0.01
1285155	Rock	7.52	2	11.3	6.3	13.1	3	0.1	3.4	0.1	5	0.58	21.4	<0.5	1.2	10	<0.1	2.5	0.1	46	<0.01
1285157	Rock	7.84	4	10.8	6.3	8.3	2	<0.1	2.6	<0.1	7	0.50	12.8	<0.5	1.1	13	<0.1	2.7	<0.1	40	<0.01
1283548	Rock	1.17	<2	0.3	37.0	2.0	18	<0.1	54.5	12.5	961	3.17	<0.5	<0.5	1.3	399	<0.1	<0.1	<0.1	47	28.68
1285251	Rock	1.39	<2	0.8	21.7	2.4	18	<0.1	40.1	13.3	988	3.29	10.4	<0.5	1.4	411	<0.1	0.1	<0.1	92	25.00
1285252	Rock	1.10	<2	1.0	28.6	5.7	13	<0.1	99.8	32.4	608	2.87	9.8	<0.5	3.6	181	<0.1	0.2	0.1	59	16.95
1285253	Rock	1.18	3	0.6	17.2	2.4	37	<0.1	58.5	23.0	1126	4.38	51.5	<0.5	1.4	487	0.1	0.2	<0.1	101	17.75
1285254	Rock	1.72	<2	0.1	322.0	0.5	6	<0.1	16.1	3.8	613	1.21	0.6	<0.5	0.2	271	<0.1	<0.1	<0.1	29	33.61
1285255	Rock	1.38	2	1.5	47.6	5.4	36	0.1	129.5	34.2	1081	5.18	8.5	<0.5	5.2	198	<0.1	0.2	<0.1	84	13.75
1285256	Rock	1.23	<2	0.9	102.2	2.5	44	<0.1	101.1	26.8	1216	5.27	2.2	<0.5	1.6	140	0.1	0.3	<0.1	90	10.00
1285257	Rock	1.72	<2	0.7	8.5	0.6	47	<0.1	55.2	10.1	672	3.59	3.4	<0.5	0.5	145	<0.1	0.2	<0.1	38	8.67
1285258	Rock	1.12	<2	0.4	14.2	1.4	84	<0.1	103.7	19.2	1580	7.84	0.8	<0.5	1.1	227	<0.1	0.3	<0.1	88	16.53
1285216	Rock	7.37	51	113.9	54.0	11.8	85	1.4	26.7	1.0	36	2.26	232.1	4.7	2.1	170	1.4	88.1	<0.1	278	0.15
1285218	Rock	5.13	59	39.6	65.1	21.4	53	1.6	15.1	1.0	28	1.52	106.8	15.6	1.8	70	0.8	34.8	<0.1	250	0.09
1285219	Rock	7.34	46	76.1	63.1	13.1	28	1.5	9.2	0.5	21	1.58	168.2	12.3	1.2	25	0.6	40.8	<0.1	292	0.02
1093810	Rock	1.58	4	2.5	16.6	72.9	42	3.0	2.4	0.8	15	1.61	130.0	5.5	8.4	10	<0.1	2.2	9.0	5	<0.01
1093982	Rock	2.20	141	0.3	76.5	1.2	48	0.4	64.2	39.5	929	4.54	5185	117.8	0.2	504	0.2	9.0	<0.1	14	6.79
1093983	Rock	2.14	143	0.2	62.5	1.3	52	0.2	49.4	29.0	897	4.26	3452	119.7	0.2	504	0.3	9.4	<0.1	16	6.71
1093984	Rock	1.54	<2	0.2	80.9	0.4	86	<0.1	70.9	39.1	1060	5.54	11.8	4.0	0.2	66	0.3	0.2	<0.1	119	2.85
1093985	Rock	1.73	222	0.2	75.4	0.8	51	0.5	43.4	27.9	987	4.76	1448	191.3	0.2	497	0.2	22.7	<0.1	25	7.66
1093986	Rock	1.90	430	0.3	53.4	0.7	57	0.9	48.6	29.6	957	5.06	1571	374.3	0.1	415	0.3	34.4	<0.1	17	8.08
1104435	Rock	0.89	<2	0.2	2.7	0.5	3	<0.1	2.3	0.6	63	0.65	4.7	1.2	0.1	1	<0.1	0.3	<0.1	<2	0.03
1285281	Rock	1.18	29	0.3	5.3	1.2	24	<0.1	11.4	2.6	106	0.89	24.5	30.7	0.6	641	<0.1	0.7	<0.1	4	4.80
1285282	Rock	1.21	3	0.9	89.8	1.6	61	0.2	21.0	1.9	17	1.38	2.4	3.3	1.6	24	0.2	0.1	0.2	33	0.12
1285280	Rock	1.09	11	13.3	30.7	10.6	24	2.1	19.7	0.6	25	1.78	37.5	0.6	2.8	13	0.2	11.7	0.1	427	0.05
1285279	Rock	1.02	<2	1.1	6.0	1.1	59	<0.1	31.6	5.5	118	2.09	9.1	0.8	0.3	3	<0.1	1.9	<0.1	17	<0.01
1285259	Rock	1.80	39	0.4	12.5	1.4	17	0.1	7.2	1.1	57	0.87	25.6	22.7	0.5	42	<0.1	0.7	<0.1	5	0.02
1285260	Rock	1.74	6	0.5	19.5	3.6	48	0.4	14.9	3.2	99	1.29	3.1	<0.5	1.4	292	0.5	0.2	<0.1	19	10.28

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

CERTIFICATE OF ANALYSIS WHI11001691.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285208	Rock	0.190	11	26	0.02	2079	0.002	<20	0.62	<0.001	0.12	1.1	6.32	1.0	0.07	1.9	4.5	2	0.2
1285209	Rock	0.032	5	15	0.02	310	<0.001	<20	0.27	<0.001	0.13	0.7	2.96	1.3	0.11	1.0	6.4	1	<0.2
1285154	Rock	0.003	1	7	0.02	187	<0.001	<20	0.32	0.004	0.11	<0.1	0.22	0.5	0.06	0.7	1.0	<1	<0.2
1285155	Rock	0.015	1	12	0.01	183	<0.001	<20	0.33	0.005	0.13	<0.1	0.17	0.8	0.08	0.7	1.5	1	<0.2
1285157	Rock	0.008	1	8	0.02	123	<0.001	<20	0.32	0.004	0.11	<0.1	0.15	0.8	<0.05	0.7	1.1	1	<0.2
1283548	Rock	0.077	5	37	0.97	256	<0.001	<20	0.28	0.011	0.05	<0.1	0.04	<0.1	<0.05	6.6	3.4	1	<0.2
1285251	Rock	0.112	3	65	1.13	199	0.002	<20	0.24	0.011	0.07	<0.1	0.03	<0.1	<0.05	11.2	2.2	<1	<0.2
1285252	Rock	0.198	3	69	0.20	319	<0.001	<20	0.48	0.008	0.19	<0.1	0.02	<0.1	<0.05	11.9	1.3	1	<0.2
1285253	Rock	0.109	6	81	1.91	208	<0.001	<20	0.26	0.011	0.08	<0.1	0.02	<0.1	<0.05	11.0	1.4	<1	<0.2
1285254	Rock	0.024	<1	18	0.23	46	<0.001	<20	0.06	0.005	0.01	<0.1	<0.01	<0.1	0.06	4.1	2.0	<1	<0.2
1285255	Rock	0.158	9	132	2.59	470	0.001	<20	0.43	0.017	0.17	<0.1	0.03	<0.1	0.06	10.7	0.8	1	<0.2
1285256	Rock	0.105	2	180	1.51	240	0.001	<20	0.75	0.008	0.08	<0.1	0.01	<0.1	<0.05	13.3	1.7	2	<0.2
1285257	Rock	0.030	1	72	1.39	106	0.001	<20	0.15	0.005	0.02	<0.1	<0.01	<0.1	<0.05	4.6	0.7	<1	<0.2
1285258	Rock	0.044	2	162	5.35	172	0.001	<20	0.28	0.024	0.04	<0.1	0.02	<0.1	0.21	7.8	0.9	<1	<0.2
1285216	Rock	0.076	9	12	0.03	619	0.001	<20	0.34	<0.001	0.16	1.6	5.61	3.3	0.16	0.9	30.5	2	0.2
1285218	Rock	0.049	9	18	0.04	517	0.001	<20	0.37	<0.001	0.11	0.5	5.12	2.3	<0.05	0.9	>100	2	0.3
1285219	Rock	0.038	6	19	0.02	187	0.001	<20	0.31	<0.001	0.10	0.4	4.62	1.9	<0.05	0.8	41.6	1	0.2
1093810	Rock	0.014	18	<1	0.02	174	<0.001	<20	0.30	0.004	0.21	1.3	1.66	0.3	0.61	0.2	3.6	<1	0.7
1093982	Rock	0.047	3	27	2.39	119	<0.001	<20	0.49	0.003	0.33	<0.1	0.11	0.1	1.53	15.8	0.9	<1	<0.2
1093983	Rock	0.044	3	29	2.30	417	<0.001	<20	0.49	0.002	0.33	<0.1	0.11	0.1	0.79	15.7	1.0	<1	<0.2
1093984	Rock	0.050	4	159	3.95	369	0.142	<20	3.64	<0.001	0.13	<0.1	0.01	<0.1	<0.05	16.3	0.8	9	<0.2
1093985	Rock	0.037	3	44	2.79	517	<0.001	<20	0.93	0.002	0.38	<0.1	0.14	0.1	0.73	20.1	0.6	2	<0.2
1093986	Rock	0.038	3	24	2.26	452	<0.001	<20	0.43	0.002	0.29	0.2	0.18	0.1	0.82	22.1	0.7	<1	<0.2
1104435	Rock	0.003	<1	11	<0.01	1765	<0.001	<20	0.05	0.001	0.02	<0.1	0.01	<0.1	<0.05	0.2	<0.5	<1	<0.2
1285281	Rock	0.019	2	9	0.04	186	<0.001	<20	0.09	0.002	0.02	<0.1	0.18	<0.1	<0.05	0.6	<0.5	<1	<0.2
1285282	Rock	0.021	2	32	0.30	772	<0.001	<20	1.26	0.019	0.15	<0.1	0.07	<0.1	<0.05	2.7	0.9	3	<0.2
1285280	Rock	0.114	4	50	0.02	4045	0.002	<20	1.51	<0.001	0.09	<0.1	0.62	0.7	0.06	3.2	18.3	5	<0.2
1285279	Rock	0.021	<1	11	0.01	360	<0.001	<20	0.08	0.002	<0.01	<0.1	0.05	<0.1	<0.05	0.6	1.2	<1	<0.2
1285259	Rock	0.023	2	9	<0.01	477	<0.001	<20	0.12	0.002	0.02	<0.1	0.07	<0.1	<0.05	1.2	0.5	<1	<0.2
1285260	Rock	0.036	5	19	0.20	1032	<0.001	<20	0.46	0.011	0.10	<0.1	0.08	<0.1	0.21	2.1	1.1	1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

CERTIFICATE OF ANALYSIS WHI11001691.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285261	Rock	1.36	10	0.9	61.4	3.9	53	0.5	15.2	1.6	23	1.36	3.1	<0.5	1.6	27	0.2	0.2	0.2	29	0.10
1285262	Rock	1.00	<2	0.5	4.9	3.7	33	0.2	9.5	2.2	145	1.07	2.6	<0.5	1.1	339	0.2	0.2	<0.1	8	12.80
1285263	Rock	1.71	26	0.7	7.5	1.0	61	<0.1	23.6	4.0	128	1.49	26.3	14.3	0.5	19	0.2	0.5	<0.1	5	0.90
1285264	Rock	1.24	18	0.7	61.4	6.7	35	0.8	12.4	1.6	28	1.46	3.5	3.7	1.2	43	<0.1	0.3	0.2	27	0.07
1285265	Rock	1.74	<2	5.6	32.8	12.5	18	0.4	5.1	0.5	57	1.55	65.3	<0.5	0.9	81	0.1	4.9	<0.1	96	0.03
1285266	Rock	1.68	2	16.7	61.3	12.9	56	0.3	7.5	0.8	65	2.40	58.6	<0.5	0.8	93	0.6	6.6	<0.1	114	0.03
1285267	Rock	1.59	11	3.5	17.8	9.1	18	0.3	4.2	0.4	53	1.15	37.6	2.1	1.0	114	<0.1	2.9	<0.1	40	0.02
1285268	Rock	1.67	10	1.9	11.9	5.2	11	0.1	2.9	0.2	20	0.59	28.8	0.9	1.0	97	<0.1	2.2	<0.1	32	0.02
1285269	Rock	1.18	3	26.9	38.8	7.3	51	0.9	65.5	1.0	24	1.81	39.8	<0.5	2.7	17	0.3	9.9	<0.1	374	0.03
1285270	Rock	1.65	<2	6.5	8.1	14.3	8	0.2	2.0	0.2	58	1.25	21.0	<0.5	0.7	67	<0.1	3.6	<0.1	31	<0.01
1285271	Rock	1.11	5	17.2	21.5	16.5	24	0.5	3.0	0.3	60	2.36	99.4	<0.5	1.3	194	0.3	9.5	<0.1	128	0.03
1285027	Rock	0.99	<2	0.2	3.8	51.6	42	<0.1	6.7	2.4	194	2.16	7.8	<0.5	0.3	<1	<0.1	0.2	<0.1	4	0.01
1285028	Rock	0.79	<2	0.3	2.6	17.2	39	<0.1	11.2	5.8	917	3.50	1.0	<0.5	0.2	3	<0.1	<0.1	<0.1	10	0.09
1285029	Rock	0.89	2	0.8	41.4	1.4	38	<0.1	10.6	0.9	380	1.35	1.4	<0.5	0.5	29	0.2	0.2	<0.1	25	2.19
1285030	Rock	0.83	<2	1.9	24.7	0.8	8	<0.1	4.0	0.5	53	0.56	3.3	<0.5	0.5	4	<0.1	1.2	<0.1	20	0.19
1285031	Rock	0.82	<2	0.6	11.0	3.2	28	<0.1	9.9	3.4	1439	2.37	9.0	<0.5	0.4	81	1.0	2.3	<0.1	6	23.78
1285032	Rock	0.91	<2	2.4	34.2	1.1	44	<0.1	17.0	1.7	367	1.44	1.6	<0.5	0.9	43	0.8	0.2	<0.1	58	2.58
1285033	Rock	0.77	<2	17.2	10.3	1.7	88	<0.1	23.0	1.5	64	0.77	8.6	<0.5	0.7	<1	0.2	2.5	<0.1	76	0.03
1285034	Rock	0.78	12	3.9	11.8	45.4	3	0.3	0.9	<0.1	15	0.37	36.7	10.7	10.7	95	0.2	6.2	0.1	28	0.01
1285035	Rock	0.74	113	75.5	294.1	13.1	2149	1.2	346.3	23.2	446	7.17	344.0	5.3	1.4	120	3.2	63.7	<0.1	1312	0.02
1285036	Rock	1.20	26	1.8	37.4	65.7	151	0.7	8.1	5.4	141	1.55	167.5	24.4	15.0	55	1.6	2.5	0.9	5	0.91
1285037	Rock	1.07	5	1.3	8.1	1.8	10	0.4	8.8	0.7	64	0.80	13.2	2.9	0.4	18	<0.1	2.7	<0.1	10	<0.01
1285038	Rock	1.35	<2	3.8	7.7	3.7	28	<0.1	13.0	1.6	66	0.89	6.2	<0.5	0.3	152	0.1	0.4	<0.1	11	0.02
1285039	Rock	0.95	<2	0.5	2.0	3.1	5	1.8	2.6	0.3	56	0.61	1.1	<0.5	0.1	7	<0.1	4.6	<0.1	7	<0.01
1285040	Rock	1.37	4	6.3	11.5	3.7	27	0.8	2.9	0.3	24	0.58	12.3	<0.5	0.8	198	0.4	5.0	<0.1	69	0.57
1285041	Rock	0.95	<2	2.1	2.7	6.2	2	0.2	1.9	0.2	50	0.72	2.7	<0.5	0.3	3	<0.1	0.6	<0.1	16	<0.01
1285272	Rock	1.79	45	1.0	3.6	32.7	6	<0.1	0.5	0.1	25	0.43	33.9	45.1	1.7	13	<0.1	0.8	0.6	9	<0.01
1285273	Rock	1.81	17	1.2	11.2	41.1	7	0.2	0.5	0.1	21	0.62	34.5	20.5	1.8	5	<0.1	1.3	0.6	8	<0.01
1285274	Rock	1.44	44	3.6	6.7	43.4	2	0.2	1.6	0.1	21	0.70	52.5	47.8	1.6	11	<0.1	1.2	0.7	24	<0.01
1285275	Rock	2.10	19	2.2	3.6	40.4	3	0.5	0.5	<0.1	22	0.49	36.7	18.8	1.9	10	<0.1	0.9	2.7	11	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

CERTIFICATE OF ANALYSIS WHI11001691.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285261	Rock	0.018	2	29	0.20	884	<0.001	<20	1.04	0.016	0.15	<0.1	0.16	<0.1	0.07	2.6	1.9	3	<0.2
1285262	Rock	0.039	5	11	0.16	881	<0.001	<20	0.28	0.013	0.04	<0.1	0.06	<0.1	0.07	1.6	0.8	<1	<0.2
1285263	Rock	0.022	1	8	0.03	87	<0.001	<20	0.16	0.003	0.01	<0.1	0.09	<0.1	<0.05	0.8	1.2	<1	<0.2
1285264	Rock	0.015	1	25	0.13	1923	<0.001	<20	0.80	0.010	0.15	<0.1	0.28	<0.1	0.05	2.6	3.4	2	<0.2
1285265	Rock	0.093	1	20	<0.01	2542	<0.001	<20	0.30	0.001	0.06	<0.1	0.99	0.3	0.15	1.1	3.4	<1	<0.2
1285266	Rock	0.096	1	33	<0.01	2052	<0.001	<20	0.20	0.002	0.09	<0.1	0.97	0.4	0.25	1.5	5.9	<1	<0.2
1285267	Rock	0.058	2	18	<0.01	3037	<0.001	<20	0.20	0.002	0.05	<0.1	1.04	0.3	0.15	1.3	2.6	<1	<0.2
1285268	Rock	0.053	<1	16	<0.01	1509	<0.001	<20	0.17	<0.001	0.02	<0.1	0.37	0.1	0.08	1.7	0.9	<1	<0.2
1285269	Rock	0.091	5	24	0.02	1144	0.002	<20	1.37	<0.001	0.09	0.1	0.54	0.8	0.16	2.3	13.9	4	<0.2
1285270	Rock	0.058	<1	21	<0.01	703	<0.001	<20	0.10	0.003	0.06	<0.1	1.41	0.3	0.11	0.6	4.0	<1	<0.2
1285271	Rock	0.164	2	18	<0.01	492	<0.001	<20	0.25	0.002	0.14	<0.1	2.13	0.6	0.24	0.9	3.5	1	<0.2
1285027	Rock	0.020	<1	15	0.05	25	<0.001	<20	0.20	0.002	<0.01	<0.1	0.07	<0.1	<0.05	1.8	<0.5	<1	<0.2
1285028	Rock	0.032	<1	8	0.03	72	<0.001	<20	0.08	0.002	0.01	<0.1	0.04	<0.1	<0.05	1.8	<0.5	<1	<0.2
1285029	Rock	0.286	4	17	0.40	96	0.002	<20	0.17	0.003	0.07	<0.1	0.03	<0.1	<0.05	0.9	<0.5	<1	<0.2
1285030	Rock	0.092	2	12	<0.01	54	<0.001	<20	0.13	0.002	0.06	<0.1	0.04	<0.1	<0.05	0.3	0.6	<1	<0.2
1285031	Rock	0.008	2	4	0.75	211	<0.001	<20	0.06	0.002	0.02	<0.1	0.04	<0.1	<0.05	1.0	<0.5	<1	<0.2
1285032	Rock	0.282	5	<1	0.63	89	0.002	<20	0.20	0.002	0.10	<0.1	<0.01	<0.1	<0.05	1.3	1.1	<1	<0.2
1285033	Rock	0.004	2	14	0.01	53	<0.001	<20	0.11	<0.001	0.04	<0.1	0.30	<0.1	<0.05	0.4	1.2	<1	<0.2
1285034	Rock	0.028	34	4	0.02	53	<0.001	<20	0.49	<0.001	0.17	<0.1	4.54	0.8	<0.05	0.4	2.9	2	<0.2
1285035	Rock	0.112	6	57	0.11	2487	0.005	<20	1.45	<0.001	0.14	0.4	22.55	1.2	0.11	3.7	27.2	2	<0.2
1285036	Rock	0.038	26	5	0.15	203	0.023	<20	0.83	0.047	0.33	0.2	0.15	0.4	0.16	1.1	1.3	3	<0.2
1285037	Rock	0.006	<1	26	<0.01	1224	<0.001	<20	0.16	0.002	0.05	<0.1	0.32	<0.1	<0.05	0.2	0.8	<1	<0.2
1285038	Rock	0.013	<1	5	<0.01	2413	<0.001	<20	0.31	<0.001	<0.01	<0.1	0.06	<0.1	0.06	0.8	0.8	<1	<0.2
1285039	Rock	0.006	<1	24	<0.01	1048	<0.001	<20	0.10	0.003	0.04	<0.1	0.43	<0.1	<0.05	0.1	1.3	<1	<0.2
1285040	Rock	0.292	<1	8	<0.01	1028	0.002	22	0.32	0.001	0.07	<0.1	1.80	<0.1	0.11	1.2	6.9	1	<0.2
1285041	Rock	0.002	<1	19	0.02	567	<0.001	<20	0.23	0.002	0.07	<0.1	0.13	0.1	0.12	0.2	1.1	<1	<0.2
1285272	Rock	0.009	2	4	<0.01	1335	<0.001	22	0.38	0.003	0.19	<0.1	1.89	0.2	0.07	0.6	0.9	1	<0.2
1285273	Rock	0.006	2	7	<0.01	336	<0.001	<20	0.36	0.002	0.20	<0.1	1.53	0.2	0.35	0.6	1.9	<1	<0.2
1285274	Rock	0.019	2	11	<0.01	1217	<0.001	<20	0.36	0.001	0.17	<0.1	2.83	0.3	0.22	0.7	1.8	1	<0.2
1285275	Rock	0.010	2	5	<0.01	740	<0.001	<20	0.32	0.002	0.20	<0.1	2.00	0.3	0.11	0.6	2.5	1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

CERTIFICATE OF ANALYSIS WHI11001691.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285276	Rock	1.68	29	1.0	3.6	43.4	2	0.3	0.5	<0.1	26	0.53	57.9	34.0	1.8	11	<0.1	0.7	1.1	8	<0.01
1285277	Rock	1.78	4	1.2	1.9	44.7	5	0.1	0.4	<0.1	24	0.47	11.0	5.7	1.8	12	<0.1	0.7	0.8	5	<0.01
1285278	Rock	1.51	17	3.6	2.1	32.0	2	0.2	0.6	<0.1	22	0.49	17.2	19.1	1.3	11	<0.1	1.4	0.7	9	<0.01
1104480	Rock	0.68	2850	1.2	2.9	78.5	2	5.8	3.2	12.4	52	3.65	>10000	2721	0.6	<1	<0.1	17.8	203.0	<2	0.03
1104481	Rock	1.02	<2	0.3	12.6	31.4	41	0.5	5.8	7.2	338	2.92	9959	5.0	15.6	36	<0.1	2.5	1.7	24	0.53
1104482	Rock	1.08	2	0.3	23.2	9.4	38	<0.1	5.3	7.8	324	2.74	53.8	2.6	13.9	62	<0.1	0.2	0.8	32	1.00
1104483	Rock	1.00	<2	0.2	13.1	8.7	43	0.1	5.8	7.5	389	2.90	313.6	1.7	13.7	69	<0.1	0.4	0.6	50	0.98
1104484	Rock	0.88	<2	0.4	9.2	7.2	41	<0.1	5.4	5.8	334	2.57	20.0	<0.5	14.8	43	<0.1	0.2	0.4	30	0.70
1104485	Rock	1.47	6	3.1	132.6	9.1	26	0.2	48.3	7.4	197	3.48	3666	5.5	5.8	8	<0.1	1.8	2.0	73	0.42
1104486	Rock	1.09	12	2.5	98.9	26.5	31	0.7	54.1	14.3	216	3.18	6658	12.4	7.8	10	0.2	2.5	2.8	103	0.34
1104487	Rock	1.37	229	1.2	36.9	7.5	11	1.2	24.9	17.1	111	4.47	>10000	171.4	8.2	13	<0.1	22.4	11.0	18	0.32
1104488	Rock	0.89	<2	0.3	8.4	8.8	16	<0.1	1.9	0.7	143	1.10	1014	3.0	12.8	12	<0.1	0.4	0.6	6	0.13
1104325	Rock	1.98	<2	0.4	92.7	16.5	41	0.2	8.9	6.6	205	2.43	43.3	1.9	15.8	57	0.2	0.3	0.3	12	1.19
1104326	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1285283	Rock	2.11	<2	1.1	78.7	5.4	17	0.2	31.5	3.0	146	2.16	35.1	3.5	2.4	113	<0.1	0.3	0.4	36	0.70
1285284	Rock	1.39	734	2.0	23.3	22.0	7	0.6	38.4	17.9	120	6.78	>10000	487.6	4.8	7	<0.1	35.4	18.2	31	0.32
1285285	Rock	1.56	17	0.7	21.0	16.2	43	0.1	13.9	4.4	193	1.90	2873	28.2	12.3	20	0.4	1.3	0.8	24	0.30
1285286	Rock	1.23	6	2.3	68.3	18.1	78	0.3	42.2	9.0	294	3.34	78.7	5.1	6.4	38	0.3	0.4	0.3	118	0.71
1285287	Rock	1.61	58	0.2	4.6	202.4	22	3.2	4.7	2.7	172	1.30	3752	62.6	4.8	17	0.5	2.1	9.4	9	0.25
1285288	Rock	2.48	2	0.3	18.7	16.0	105	0.2	24.6	4.7	174	1.43	328.5	6.3	12.2	20	0.4	0.5	0.3	7	0.47
1285289	Rock	1.87	<2	0.2	21.5	14.2	47	0.2	7.8	3.7	118	1.67	147.6	1.9	9.4	12	0.2	0.3	0.2	4	0.31
1285290	Rock	2.20	25	0.2	15.5	11.7	64	0.1	14.3	5.7	143	1.26	1598	8.6	10.4	18	0.3	0.8	0.2	6	0.50
1104324	Rock	1.89	22	1.0	22.3	20.2	87	0.4	18.5	6.9	175	1.63	610.6	6.6	2.8	15	0.6	0.8	0.4	9	0.24

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

CERTIFICATE OF ANALYSIS WHI11001691.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285276	Rock	0.012	2	4	<0.01	742	<0.001	<20	0.31	0.002	0.19	<0.1	1.52	0.2	0.07	0.4	1.2	<1	<0.2
1285277	Rock	0.013	3	8	<0.01	1304	<0.001	<20	0.32	0.001	0.24	<0.1	1.34	0.3	0.10	0.3	0.7	<1	<0.2
1285278	Rock	0.022	3	<1	<0.01	523	<0.001	<20	0.27	0.001	0.18	<0.1	1.13	0.3	0.09	0.5	2.9	2	<0.2
1104480	Rock	0.002	<1	10	<0.01	18	0.001	<20	0.04	0.004	0.02	>100	<0.01	<0.1	1.48	<0.1	1.6	<1	4.4
1104481	Rock	0.049	23	17	0.84	129	0.139	<20	1.89	0.116	0.56	0.6	<0.01	0.3	0.49	4.5	0.8	7	<0.2
1104482	Rock	0.045	20	26	0.86	205	0.233	<20	2.71	0.204	0.96	0.8	<0.01	0.5	0.47	7.3	<0.5	9	<0.2
1104483	Rock	0.053	28	28	1.01	217	0.267	<20	2.82	0.276	1.01	0.2	<0.01	0.4	0.48	7.5	<0.5	9	<0.2
1104484	Rock	0.047	20	24	0.82	139	0.199	<20	2.09	0.170	0.65	0.2	<0.01	0.3	0.36	6.1	<0.5	8	<0.2
1104485	Rock	0.036	5	40	0.52	171	0.075	<20	1.31	0.058	0.56	0.5	<0.01	0.4	1.47	2.3	1.8	4	<0.2
1104486	Rock	0.054	8	54	0.67	223	0.101	<20	1.48	0.064	0.75	2.5	<0.01	0.5	0.78	3.1	1.6	6	<0.2
1104487	Rock	0.038	9	14	0.21	45	0.025	28	0.83	0.101	0.24	8.4	<0.01	0.2	2.18	1.1	8.0	3	1.0
1104488	Rock	0.016	10	12	0.19	43	0.062	<20	0.65	0.061	0.32	12.0	<0.01	0.1	0.07	1.4	<0.5	3	<0.2
1104325	Rock	0.038	25	11	0.41	105	0.058	<20	1.61	0.211	0.41	<0.1	<0.01	0.2	0.84	3.5	1.2	6	<0.2
1104326	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1285283	Rock	0.023	3	35	0.27	160	0.043	<20	1.25	0.010	0.20	0.4	<0.01	0.1	0.61	1.3	1.3	4	<0.2
1285284	Rock	0.035	5	19	0.24	166	0.025	20	0.68	0.016	0.34	10.3	<0.01	0.2	3.31	1.4	13.5	2	1.0
1285285	Rock	0.040	13	25	0.45	109	0.070	<20	1.31	0.086	0.52	0.2	<0.01	0.3	0.18	2.3	<0.5	5	<0.2
1285286	Rock	0.054	8	63	0.80	472	0.108	<20	2.25	0.022	0.73	0.2	<0.01	0.5	0.65	3.8	2.4	7	<0.2
1285287	Rock	0.012	7	32	0.28	57	0.048	<20	0.80	0.079	0.30	39.5	<0.01	0.2	0.14	1.8	<0.5	3	<0.2
1285288	Rock	0.038	13	8	0.30	66	0.031	<20	0.98	0.077	0.41	<0.1	<0.01	0.3	0.20	1.1	<0.5	3	<0.2
1285289	Rock	0.034	15	13	0.19	57	0.010	23	0.65	0.042	0.29	0.1	<0.01	0.1	0.22	0.7	1.3	2	<0.2
1285290	Rock	0.038	16	6	0.18	66	0.006	<20	0.66	0.027	0.27	<0.1	<0.01	<0.1	0.24	0.7	<0.5	2	<0.2
1104324	Rock	0.030	9	20	0.11	172	0.001	<20	0.27	0.003	0.14	<0.1	<0.01	<0.1	0.35	0.8	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

QUALITY CONTROL REPORT WHI11001691.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1285153	Rock	7.53	<2	7.1	4.2	11.8	2	0.1	2.6	<0.1	5	0.28	3.4	<0.5	1.1	7	<0.1	1.4	0.1	28	<0.01
REP 1285153	QC		<2																		
REP 1285214	QC		36																		
1285223	Rock	8.13	<2	7.1	33.0	12.8	10	1.0	2.7	0.1	15	0.75	42.4	1.2	1.2	99	0.3	21.2	<0.1	200	0.02
REP 1285223	QC			7.5	40.0	11.5	15	1.0	3.7	0.1	22	0.92	50.1	3.0	1.1	95	0.5	8.8	<0.1	254	0.04
1104435	Rock	0.89	<2	0.2	2.7	0.5	3	<0.1	2.3	0.6	63	0.65	4.7	1.2	0.1	1	<0.1	0.3	<0.1	<2	0.03
REP 1104435	QC		<2																		
1285260	Rock	1.74	6	0.5	19.5	3.6	48	0.4	14.9	3.2	99	1.29	3.1	<0.5	1.4	292	0.5	0.2	<0.1	19	10.28
REP 1285260	QC			0.4	18.9	4.1	48	0.4	15.0	3.0	95	1.30	3.4	<0.5	1.4	291	0.5	0.2	<0.1	19	10.27
1285033	Rock	0.77	<2	17.2	10.3	1.7	88	<0.1	23.0	1.5	64	0.77	8.6	<0.5	0.7	<1	0.2	2.5	<0.1	76	0.03
REP 1285033	QC		<2																		
1285274	Rock	1.44	44	3.6	6.7	43.4	2	0.2	1.6	0.1	21	0.70	52.5	47.8	1.6	11	<0.1	1.2	0.7	24	<0.01
REP 1285274	QC			3.7	6.6	44.5	3	0.2	0.6	<0.1	20	0.70	52.7	45.3	1.6	12	<0.1	1.1	0.7	24	0.01
Core Reject Duplicates																					
1285214	Rock	6.97	31	46.7	71.5	9.7	89	0.7	18.9	1.3	40	1.70	153.9	5.1	1.2	47	1.4	50.8	<0.1	193	0.06
DUP 1285214	QC		30	49.0	74.4	10.8	92	0.8	19.8	1.4	40	1.75	158.7	4.7	1.2	49	1.6	51.7	<0.1	217	0.06
1285280	Rock	1.09	11	13.3	30.7	10.6	24	2.1	19.7	0.6	25	1.78	37.5	0.6	2.8	13	0.2	11.7	0.1	427	0.05
DUP 1285280	QC		12	13.0	30.1	10.5	23	2.2	19.2	0.6	23	1.68	35.3	<0.5	2.7	11	<0.1	11.2	0.2	448	0.04
1285277	Rock	1.78	4	1.2	1.9	44.7	5	0.1	0.4	<0.1	24	0.47	11.0	5.7	1.8	12	<0.1	0.7	0.8	5	<0.01
DUP 1285277	QC		4	1.2	1.9	45.1	3	0.2	0.5	<0.1	26	0.49	11.9	6.8	1.9	12	<0.1	0.6	0.8	5	<0.01
Reference Materials																					
STD DS8	Standard			13.4	107.9	119.5	308	1.9	37.1	7.4	583	2.45	24.8	96.9	6.5	65	2.1	5.4	6.3	41	0.70
STD DS8	Standard			12.4	107.6	119.2	286	1.7	37.8	7.4	550	2.36	23.4	106.2	6.2	65	2.1	3.0	5.7	39	0.68
STD DS8	Standard			12.2	108.5	121.2	309	1.7	37.2	7.5	598	2.47	25.6	112.0	6.4	68	2.0	4.6	6.4	42	0.70
STD DS8	Standard			12.8	108.2	117.2	297	1.6	36.9	7.6	601	2.49	24.7	92.0	6.3	71	2.3	2.5	6.5	41	0.71
STD DS8	Standard			13.5	106.3	128.9	319	1.8	38.3	7.7	621	2.46	25.4	117.2	7.1	74	2.2	5.3	7.5	41	0.73
STD DS8	Standard			12.4	100.1	119.2	283	1.6	32.9	6.6	546	2.28	23.3	105.7	6.5	65	2.3	4.9	6.2	33	0.64
STD OREAS45CA	Standard			1.1	486.8	20.1	59	0.3	238.4	88.4	838	15.06	4.0	35.6	7.0	15	<0.1	0.2	0.2	209	0.41

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

QUALITY CONTROL REPORT WHI11001691.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1285153	Rock	0.004	1	4	<0.01	193	<0.001	<20	0.32	0.005	0.11	<0.1	0.14	0.3	0.08	0.6	0.8	1	<0.2
REP 1285153	QC																		
REP 1285214	QC																		
1285223	Rock	0.061	7	13	0.01	477	<0.001	<20	0.26	<0.001	0.09	0.4	2.19	2.2	<0.05	0.8	4.6	1	0.2
REP 1285223	QC	0.083	7	15	0.02	385	<0.001	<20	0.32	<0.001	0.11	0.3	1.95	2.6	<0.05	1.0	7.0	1	0.2
1104435	Rock	0.003	<1	11	<0.01	1765	<0.001	<20	0.05	0.001	0.02	<0.1	0.01	<0.1	<0.05	0.2	<0.5	<1	<0.2
REP 1104435	QC																		
1285260	Rock	0.036	5	19	0.20	1032	<0.001	<20	0.46	0.011	0.10	<0.1	0.08	<0.1	0.21	2.1	1.1	1	<0.2
REP 1285260	QC	0.039	5	18	0.18	1005	<0.001	<20	0.49	0.012	0.10	<0.1	0.07	<0.1	0.21	2.0	0.7	1	<0.2
1285033	Rock	0.004	2	14	0.01	53	<0.001	<20	0.11	<0.001	0.04	<0.1	0.30	<0.1	<0.05	0.4	1.2	<1	<0.2
REP 1285033	QC																		
1285274	Rock	0.019	2	11	<0.01	1217	<0.001	<20	0.36	0.001	0.17	<0.1	2.83	0.3	0.22	0.7	1.8	1	<0.2
REP 1285274	QC	0.019	2	8	<0.01	1003	<0.001	<20	0.36	0.002	0.16	<0.1	2.89	0.2	0.21	0.7	1.4	1	<0.2
Core Reject Duplicates																			
1285214	Rock	0.044	5	9	0.02	786	0.001	<20	0.27	0.001	0.08	0.4	5.87	1.7	<0.05	0.8	9.2	1	0.2
DUP 1285214	QC	0.045	6	10	0.02	859	0.001	<20	0.30	0.001	0.08	0.5	6.49	1.9	0.05	0.9	9.1	1	0.2
1285280	Rock	0.114	4	50	0.02	4045	0.002	<20	1.51	<0.001	0.09	<0.1	0.62	0.7	0.06	3.2	18.3	5	<0.2
DUP 1285280	QC	0.110	4	47	0.01	4680	0.002	21	1.48	<0.001	0.10	<0.1	0.58	0.9	0.07	3.0	17.7	5	<0.2
1285277	Rock	0.013	3	8	<0.01	1304	<0.001	<20	0.32	0.001	0.24	<0.1	1.34	0.3	0.10	0.3	0.7	<1	<0.2
DUP 1285277	QC	0.013	3	7	<0.01	1312	<0.001	24	0.32	0.003	0.24	<0.1	1.30	0.3	0.10	0.3	0.9	<1	<0.2
Reference Materials																			
STD DS8	Standard	0.068	14	115	0.61	311	0.121	<20	0.92	0.086	0.41	2.2	0.18	4.9	0.16	2.1	4.8	5	4.1
STD DS8	Standard	0.071	14	113	0.58	269	0.110	<20	0.92	0.090	0.40	1.8	0.22	4.9	0.15	1.8	5.0	4	4.0
STD DS8	Standard	0.081	13	116	0.61	294	0.123	<20	0.90	0.084	0.41	2.6	0.21	5.1	0.17	2.1	4.5	4	4.1
STD DS8	Standard	0.071	15	116	0.62	267	0.117	<20	0.99	0.104	0.43	2.1	0.16	5.0	0.15	2.1	4.6	5	4.8
STD DS8	Standard	0.084	16	108	0.62	291	0.142	<20	1.03	0.119	0.45	2.8	0.18	5.7	0.16	2.0	3.7	5	5.2
STD DS8	Standard	0.068	13	105	0.56	267	0.118	<20	0.86	0.087	0.39	2.2	0.20	5.1	0.14	2.0	4.5	4	4.2
STD OREAS45CA	Standard	0.033	16	632	0.15	155	0.136	<20	3.77	0.006	0.07	<0.1	0.03	<0.1	<0.05	35.9	0.9	16	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

QUALITY CONTROL REPORT WHI11001691.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
STD OREAS45CA	Standard			0.6	522.1	20.3	60	0.2	246.2	92.9	900	15.62	4.1	40.5	7.1	17	<0.1	<0.1	0.2	214	0.41
STD OREAS45CA	Standard			0.9	502.4	19.2	64	0.3	249.3	91.2	938	16.01	3.9	41.8	6.8	16	<0.1	<0.1	0.2	212	0.44
STD OREAS45CA	Standard			1.0	532.5	20.2	62	0.3	262.2	94.8	967	16.80	3.7	38.7	7.2	18	<0.1	0.1	0.2	225	0.44
STD OREAS45CA	Standard			0.8	549.8	21.2	61	0.3	273.8	89.1	898	15.37	3.1	46.0	7.2	18	<0.1	<0.1	0.2	212	0.43
STD OREAS45CA	Standard			0.8	465.2	22.0	57	0.3	230.1	84.7	884	15.32	4.0	63.3	7.3	16	0.1	<0.1	0.2	166	0.40
STD OXC88	Standard		197																		
STD OXC88	Standard		198																		
STD OXC88	Standard		196																		
STD OXC88	Standard		215																		
STD OXC88	Standard		195																		
STD OXC88	Standard		189																		
STD OXH82	Standard		1311																		
STD OXH82	Standard		1287																		
STD OXH82	Standard		1270																		
STD OXH82	Standard		1226																		
STD OXH82	Standard		1261																		
STD OXH82	Standard		1288																		
STD OXH82	Standard		1247																		
STD OXH82	Standard		1299																		
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

QUALITY CONTROL REPORT WHI11001691.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
STD OREAS45CA	Standard	0.036	15	688	0.16	155	0.113	<20	3.79	0.007	0.08	<0.1	0.03	<0.1	<0.05	34.3	1.0	17	<0.2
STD OREAS45CA	Standard	0.038	16	642	0.17	160	0.148	<20	3.63	0.008	0.07	<0.1	0.03	<0.1	<0.05	36.6	<0.5	18	<0.2
STD OREAS45CA	Standard	0.039	16	679	0.18	155	0.149	<20	4.11	0.006	0.08	<0.1	0.05	<0.1	<0.05	41.5	0.8	19	<0.2
STD OREAS45CA	Standard	0.038	17	569	0.19	167	0.154	<20	3.94	0.011	0.08	<0.1	0.03	0.1	<0.05	38.4	1.1	19	<0.2
STD OREAS45CA	Standard	0.033	17	566	0.15	159	0.118	<20	3.49	0.007	0.06	<0.1	0.03	0.1	<0.05	36.9	0.7	18	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXC88 Expected																			
STD OXH82 Expected																			
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

QUALITY CONTROL REPORT WHI11001691.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank	<0.01	<2	<0.1	2.5	2.9	46	<0.1	2.2	3.8	595	2.07	<0.5	<0.5	5.9	72	<0.1	<0.1	<0.1	37	0.49
G1	Prep Blank	<0.01	<2	0.1	2.2	3.3	44	<0.1	2.3	3.7	580	2.09	<0.5	2.6	6.2	69	<0.1	<0.1	<0.1	37	0.56

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

QUALITY CONTROL REPORT WHI11001691.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																			
G1	Prep Blank	0.076	15	<1	0.52	164	0.154	<20	1.04	0.123	0.52	<0.1	<0.01	0.3	<0.05	1.8	<0.5	5	<0.2
G1	Prep Blank	0.071	15	5	0.52	157	0.152	<20	1.03	0.128	0.51	<0.1	<0.01	0.3	<0.05	1.7	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Email Distribution List
Receiving Lab: Canada-Whitehorse
Received: September 19, 2011
Report Date: November 21, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11001723.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #27
P.O. Number
Number of Samples: 56

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-500	55	Crush, split and pulverize 500 g rock to 200 mesh			VAN
3B	56	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	56	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

CERTIFICATE OF ANALYSIS WHI11001723.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285110	Rock	1.17	784	9.3	33.4	12.3	356	2.8	72.8	11.6	104	1.45	195.6	4.5	4.1	44	6.3	16.4	0.9	31	0.31
1285111	Rock	1.24	244	10.7	20.2	18.4	108	1.0	45.1	6.9	211	2.56	217.7	<0.5	1.9	138	0.7	7.6	1.1	38	3.65
1285112	Rock	1.10	76	2.7	75.9	20.3	1392	0.8	125.2	17.4	694	3.96	127.9	<0.5	1.8	62	8.0	19.5	0.1	21	2.18
1285113	Rock	1.50	343	0.3	35.1	6.0	10	0.6	21.0	3.5	71	1.89	59.7	2.5	1.2	6	<0.1	3.8	0.1	9	0.01
1285114	Rock	0.36	396	4.2	12.5	4.8	51	1.7	14.1	1.0	47	1.14	40.8	<0.5	0.6	12	1.0	6.6	0.1	36	0.18
1285115	Rock	1.02	331	1.2	6.1	57.8	157	1.2	7.7	1.9	34	1.10	170.4	244.4	8.5	43	0.2	44.8	3.0	7	<0.01
1285116	Rock	0.91	429	11.0	42.9	6.0	1879	2.5	50.1	4.5	136	0.93	188.0	9.0	0.9	18	23.3	30.5	0.1	216	0.40
1285117	Drill Core	0.85	229	1.1	24.8	85.4	362	2.1	37.5	8.5	257	1.96	147.2	32.7	11.9	34	10.5	18.8	2.0	4	0.43
1285118	Rock	0.49	1008	1.9	30.8	14.6	130	2.0	40.3	7.8	270	3.51	703.9	20.3	4.5	118	0.6	8.2	0.5	11	0.59
1285119	Rock	1.17	7	1.5	34.5	22.1	186	0.6	60.3	17.4	1686	12.57	32.3	0.6	2.5	28	0.6	0.3	0.3	37	0.26
1285120	Rock	1.68	85	10.1	23.7	8.1	70	0.6	31.9	5.9	251	2.71	51.8	<0.5	1.4	17	0.4	8.9	0.1	15	0.50
1285121	Rock	0.67	476	19.7	45.7	23.6	2173	4.1	35.2	4.1	68	1.88	129.7	4.6	1.4	6	28.2	29.5	0.6	114	0.05
1285122	Drill Core	2.09	167	0.8	81.8	24.3	188	0.8	7.8	6.9	88	3.13	627.5	151.0	11.0	61	2.2	5.2	1.5	<2	0.81
1285123	Drill Core	1.65	93	8.4	34.3	5.1	125	0.4	64.4	8.6	51	1.38	136.0	6.9	3.4	43	0.9	3.1	0.8	40	0.31
1285124	Drill Core	1.49	524	0.6	32.0	31.1	242	1.1	25.3	5.8	342	2.17	297.0	483.2	11.5	65	3.5	3.7	0.8	7	0.92
1285125	Drill Core	1.61	192	1.4	15.5	67.4	230	1.5	1.5	5.4	383	2.40	998.2	203.0	8.2	217	1.9	18.5	0.3	5	2.22
1285126	Drill Core	0.86	8	13.9	16.2	8.4	255	0.5	22.0	3.2	71	1.04	31.5	14.8	1.2	13	3.6	3.7	0.2	67	0.14
1285127	Drill Core	1.81	905	0.6	16.1	38.5	205	7.7	42.7	6.2	80	1.65	199.1	866.1	12.7	36	13.4	11.0	0.8	6	0.12
1285128	Drill Core	1.60	113	5.1	31.5	33.9	1273	2.7	55.0	8.6	222	2.19	134.1	4.5	7.0	92	23.2	13.7	0.5	38	0.38
1285129	Rock	1.08	27	9.0	34.4	27.4	361	0.4	82.2	15.1	187	2.71	245.4	1.2	4.2	99	3.8	4.0	0.2	31	0.97
1285130	Rock	0.78	297	79.3	22.8	3.6	100	0.6	3.7	0.2	22	0.76	561.0	40.5	1.0	18	<0.1	19.2	0.2	345	<0.01
1285131	Drill Core	0.68	170	11.9	25.1	8.0	254	0.9	52.2	6.4	67	1.14	404.2	2.2	3.5	52	4.0	15.5	0.5	35	0.26
1285013	Rock	0.67	<2	1.5	73.8	0.8	124	<0.1	304.6	49.4	1212	7.08	33.5	<0.5	5.8	161	3.7	1.5	<0.1	137	4.23
1285014	Rock	0.81	<2	1.0	103.4	2.1	124	<0.1	220.5	38.5	1302	5.20	6.7	1.8	3.3	623	0.5	0.3	<0.1	178	5.89
1285015	Rock	0.73	<2	2.3	31.4	12.2	216	0.1	68.2	19.9	93	2.01	9.5	1.8	13.7	135	0.7	0.2	0.3	14	0.50
1285016	Rock	0.79	<2	7.4	2.9	1.1	95	<0.1	22.7	2.6	957	3.80	1.0	<0.5	0.7	708	0.3	0.7	<0.1	76	20.27
1285017	Rock	0.78	<2	9.5	8.4	2.1	113	0.1	37.0	1.1	80	0.90	5.1	<0.5	0.6	55	0.6	1.0	<0.1	69	0.40
1285412	Rock	3.24	<2	3.8	81.0	7.6	638	0.2	295.4	60.2	1172	4.67	105.7	<0.5	13.0	469	4.0	2.7	<0.1	101	12.91
1285413	Rock	2.43	<2	1.4	99.5	6.1	1694	<0.1	259.5	46.1	1288	3.84	30.7	1.2	19.2	551	9.5	0.9	<0.1	107	12.87
1285414	Rock	3.59	<2	2.0	109.6	8.5	3560	0.2	240.8	62.7	1075	3.76	93.6	2.1	24.4	436	42.6	1.5	<0.1	124	10.97

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

CERTIFICATE OF ANALYSIS WHI11001723.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285110	Rock	0.033	13	<1	0.15	121	<0.001	<20	0.41	0.010	0.15	0.4	26.51	7.8	1.42	0.6	15.8	<1	0.4
1285111	Rock	0.020	3	4	0.12	27	<0.001	<20	0.38	0.007	0.16	0.2	11.14	5.6	2.99	0.8	5.3	<1	<0.2
1285112	Rock	0.017	5	10	0.80	78	0.002	<20	0.43	0.006	0.14	0.2	6.44	1.3	2.92	2.1	10.2	2	<0.2
1285113	Rock	0.004	8	6	<0.01	113	<0.001	<20	0.23	0.004	0.09	<0.1	2.57	0.9	1.69	0.5	2.6	<1	<0.2
1285114	Rock	0.090	4	14	0.01	175	0.001	<20	0.32	0.010	0.10	0.1	5.74	1.2	0.79	0.7	8.8	<1	<0.2
1285115	Rock	0.020	23	5	0.02	61	<0.001	<20	0.29	0.003	0.25	<0.1	5.80	0.7	0.07	0.3	14.0	<1	<0.2
1285116	Rock	0.179	3	19	0.02	115	0.001	<20	0.38	0.003	0.09	0.3	31.56	0.2	0.44	0.9	22.7	<1	<0.2
1285117	Drill Core	0.044	22	5	0.18	76	<0.001	<20	0.63	0.007	0.24	<0.1	13.57	0.8	1.82	1.2	5.7	<1	<0.2
1285118	Rock	0.017	6	9	0.27	64	<0.001	<20	0.39	0.020	0.20	<0.1	13.03	0.7	3.64	2.4	5.9	<1	<0.2
1285119	Rock	0.041	6	16	1.20	148	<0.001	<20	0.93	0.013	0.14	<0.1	0.20	<0.1	0.53	4.0	2.1	2	<0.2
1285120	Rock	0.006	6	10	0.35	43	0.001	<20	0.33	0.004	0.11	0.2	7.16	1.5	2.54	0.7	7.4	<1	<0.2
1285121	Rock	0.008	7	7	0.03	104	<0.001	<20	0.31	0.010	0.12	0.2	41.39	3.1	1.95	0.7	48.3	1	<0.2
1285122	Drill Core	0.043	12	1	0.04	76	0.001	<20	0.45	0.007	0.28	0.2	24.19	3.7	3.33	0.3	11.7	1	0.7
1285123	Drill Core	0.022	12	4	0.17	115	<0.001	<20	0.34	0.010	0.15	0.1	4.57	1.1	1.32	0.9	7.3	<1	<0.2
1285124	Drill Core	0.043	24	3	0.26	127	0.008	<20	1.27	0.050	0.35	0.3	6.07	4.1	1.31	2.0	3.7	4	<0.2
1285125	Drill Core	0.043	17	9	0.35	113	0.011	<20	0.87	0.048	0.29	0.3	4.22	2.8	2.06	1.8	4.6	2	<0.2
1285126	Drill Core	0.017	2	6	0.08	135	<0.001	<20	0.35	0.004	0.14	<0.1	1.33	0.2	0.95	1.2	4.3	<1	<0.2
1285127	Drill Core	0.050	23	<1	0.03	59	<0.001	<20	0.77	0.003	0.29	<0.1	7.06	1.0	1.55	1.0	4.9	<1	<0.2
1285128	Drill Core	0.035	12	7	0.18	63	<0.001	<20	0.49	0.008	0.20	0.1	26.26	0.4	1.97	1.3	16.6	1	0.3
1285129	Rock	0.030	6	6	0.41	83	<0.001	<20	0.40	0.015	0.18	<0.1	2.06	0.2	2.79	2.5	4.8	<1	<0.2
1285130	Rock	0.033	5	<1	0.03	209	0.001	<20	0.33	0.042	0.10	<0.1	66.71	0.4	0.09	0.6	11.2	1	0.2
1285131	Drill Core	0.022	12	4	0.18	114	<0.001	<20	0.38	0.011	0.14	0.2	29.84	4.0	1.02	0.6	7.2	<1	<0.2
1285013	Rock	0.235	40	409	7.97	868	0.026	<20	2.84	<0.001	0.30	<0.1	0.13	0.4	0.11	16.0	<0.5	8	<0.2
1285014	Rock	0.190	22	481	8.68	218	0.008	<20	3.40	<0.001	0.05	<0.1	0.08	0.1	1.12	20.3	1.3	10	<0.2
1285015	Rock	0.291	27	5	0.16	901	0.002	<20	1.29	0.005	0.35	<0.1	0.07	0.6	<0.05	3.7	3.1	3	<0.2
1285016	Rock	0.007	4	7	6.91	1009	0.002	<20	0.18	0.050	0.06	<0.1	0.05	0.2	<0.05	4.8	<0.5	<1	<0.2
1285017	Rock	0.009	6	8	0.07	143	<0.001	<20	0.20	<0.001	0.05	<0.1	0.07	0.1	<0.05	0.5	0.6	<1	<0.2
1285412	Rock	0.410	63	149	3.56	391	0.005	<20	0.99	0.007	0.31	<0.1	8.83	0.2	0.30	16.3	0.7	3	<0.2
1285413	Rock	0.566	78	182	3.30	1257	0.006	30	1.17	0.006	0.36	<0.1	13.54	0.2	0.16	19.4	<0.5	3	<0.2
1285414	Rock	0.654	81	227	2.59	1728	0.006	30	1.29	0.006	0.42	<0.1	24.17	0.2	0.13	20.5	0.7	4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

CERTIFICATE OF ANALYSIS WHI11001723.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285415	Rock	2.71	<2	3.4	105.8	10.6	>10000	0.2	333.5	62.2	986	3.92	123.1	0.6	18.8	690	136.6	1.3	<0.1	111	13.98
1285416	Rock	2.39	<2	4.0	68.7	8.3	66	0.1	405.4	55.9	1078	4.16	16.7	0.7	15.0	721	0.6	0.4	<0.1	98	15.58
1285417	Rock	2.52	<2	5.9	92.6	9.9	37	0.1	543.1	73.0	1168	4.38	51.5	<0.5	20.6	645	0.1	0.8	<0.1	109	14.63
1093727	Rock	2.20	<2	10.8	74.9	15.9	31	0.1	486.5	64.0	1063	7.01	80.6	0.6	12.5	465	0.2	2.4	<0.1	77	18.03
1093728	Rock	1.78	<2	12.1	73.7	16.5	64	0.1	480.7	58.1	1090	7.35	28.8	1.2	12.9	447	0.5	1.8	<0.1	77	17.46
1093729	Rock	1.63	17	15.1	73.9	13.5	66	<0.1	474.0	60.3	986	6.36	26.2	<0.5	12.9	438	0.4	1.4	<0.1	68	18.95
1093730	Rock	1.50	<2	11.0	74.6	12.7	58	0.2	508.3	65.6	1095	6.71	31.5	<0.5	12.4	403	0.5	1.7	<0.1	75	14.68
1093731	Rock	1.56	<2	13.5	77.0	17.4	57	0.3	589.8	66.4	1194	7.65	57.3	1.9	12.8	454	0.7	3.8	<0.1	75	14.89
1093732	Rock	1.53	4	9.6	86.1	14.1	76	0.5	701.0	83.5	1181	6.47	172.6	2.1	17.1	440	0.9	6.4	<0.1	86	14.20
1093733	Rock	1.32	<2	13.6	89.2	13.3	97	0.5	687.2	97.5	1422	6.62	194.9	1.7	17.3	372	0.9	6.5	<0.1	106	9.49
1093734	Rock	1.53	2	9.0	97.2	11.6	168	0.5	672.8	86.1	1375	6.65	194.7	3.5	17.2	422	1.8	6.2	<0.1	109	9.98
1093735	Rock	1.28	<2	8.8	125.3	16.5	500	0.5	652.1	99.1	1582	7.52	232.9	3.4	23.6	238	5.7	3.8	<0.1	155	4.48
1093736	Rock	1.31	<2	8.6	136.3	21.3	438	0.6	689.8	106.8	1313	7.12	264.1	3.5	23.6	218	5.2	4.7	<0.1	151	3.84
1093737	Rock	1.24	5	8.3	117.0	17.9	377	0.3	690.4	99.8	1137	5.42	133.1	2.3	19.9	372	4.1	2.9	<0.1	143	7.55
1093738	Rock	1.27	<2	4.5	120.7	15.8	429	0.3	547.0	98.5	1473	7.19	74.5	1.6	21.3	329	3.0	2.3	<0.1	148	6.14
1093739	Rock	1.53	<2	2.0	112.3	17.8	2118	0.4	538.4	83.9	1501	8.78	82.6	2.2	18.4	360	19.5	3.1	<0.1	125	7.75
1093740	Rock	1.36	<2	5.0	148.3	15.1	3007	0.2	535.3	110.8	1324	5.38	42.7	1.2	23.9	350	26.9	1.5	<0.1	177	5.52
1093741	Rock	1.25	<2	4.7	140.5	18.4	9107	0.3	649.2	108.2	1381	5.82	100.7	0.7	23.2	374	84.0	1.6	<0.1	168	5.92
1093742	Rock	0.97	<2	3.4	117.9	18.1	90	0.2	725.6	103.9	1450	6.33	32.6	2.6	24.2	352	0.7	0.7	0.1	171	5.20
1093743	Rock	1.15	<2	3.5	111.2	17.3	67	0.2	664.6	100.2	1496	7.85	109.6	1.3	20.7	284	0.4	1.3	<0.1	159	4.60
1095980	Rock	0.59	10	1.5	50.5	12.8	981	0.1	133.5	27.2	816	10.83	46.2	2.7	1.5	14	9.4	3.6	0.2	33	<0.01
1285189	Rock	8.04	8	0.6	10.8	49.0	113	0.3	15.3	4.8	47	2.50	189.3	7.3	14.2	36	0.1	5.3	0.3	2	0.02
1285190	Rock	6.42	9	0.8	9.5	53.0	93	0.2	11.3	3.4	41	2.30	147.8	6.3	12.1	33	0.1	4.1	0.3	4	<0.01
1285191	Rock	6.37	8	0.6	8.3	46.9	93	0.2	9.5	3.3	36	2.21	143.7	6.4	13.2	32	0.1	4.1	0.3	2	<0.01
1285192	Rock Pulp	0.15	1674	19.4	322.0	7.4	47	0.4	34.4	7.3	420	3.11	8.9	820.5	1.1	37	0.1	1.3	0.3	53	0.72
1285193	Rock	0.40	<2	0.1	0.3	1.2	10	<0.1	0.8	1.2	213	0.43	0.6	1.0	<0.1	41	<0.1	<0.1	<0.1	<2	20.66

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

CERTIFICATE OF ANALYSIS WHI11001723.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285415	Rock	0.506	67	180	2.35	2037	0.005	23	1.04	0.006	0.34	<0.1	32.66	0.1	0.13	16.9	<0.5	4	<0.2
1285416	Rock	0.451	73	151	2.86	1331	0.004	22	0.97	0.008	0.32	<0.1	1.16	0.1	0.16	15.6	<0.5	3	<0.2
1285417	Rock	0.538	74	184	2.31	1083	0.005	23	1.12	0.007	0.37	<0.1	0.88	0.1	0.19	18.9	0.5	3	<0.2
1093727	Rock	0.393	56	126	0.47	326	0.005	<20	0.75	0.007	0.22	<0.1	3.70	0.4	0.22	13.9	1.2	3	<0.2
1093728	Rock	0.462	61	129	0.24	912	0.005	<20	0.82	0.007	0.22	<0.1	2.65	0.3	0.12	14.9	0.9	2	<0.2
1093729	Rock	0.436	53	120	0.67	226	0.005	<20	0.74	0.009	0.23	<0.1	0.95	0.4	0.24	13.7	1.3	2	<0.2
1093730	Rock	0.398	57	116	0.82	483	0.004	<20	0.89	0.008	0.21	<0.1	1.27	0.3	0.13	14.2	1.3	2	<0.2
1093731	Rock	0.465	64	106	0.52	845	0.004	<20	1.12	0.012	0.28	<0.1	3.67	0.4	0.11	14.9	1.9	3	<0.2
1093732	Rock	0.540	71	142	0.72	1842	0.005	<20	1.02	0.005	0.27	<0.1	5.82	0.3	0.15	16.5	2.1	3	<0.2
1093733	Rock	0.588	85	151	1.73	1565	0.004	<20	1.06	0.005	0.25	<0.1	5.94	0.3	0.14	17.4	1.8	3	<0.2
1093734	Rock	0.621	95	188	2.71	2721	0.006	<20	1.15	0.006	0.30	<0.1	7.84	0.3	0.17	21.3	3.0	3	<0.2
1093735	Rock	0.784	116	238	0.85	3361	0.006	<20	1.64	0.003	0.35	0.1	14.33	0.3	0.09	25.9	2.9	5	<0.2
1093736	Rock	0.795	121	258	0.57	3434	0.006	<20	1.73	0.003	0.40	<0.1	19.63	0.4	0.13	25.0	2.2	6	<0.2
1093737	Rock	0.719	94	220	1.35	3380	0.006	21	1.43	0.004	0.36	<0.1	10.02	0.3	0.10	21.5	2.3	5	<0.2
1093738	Rock	0.731	94	240	1.47	2436	0.008	20	1.58	0.004	0.40	<0.1	9.20	0.4	0.12	25.6	2.3	6	<0.2
1093739	Rock	0.654	84	226	1.88	1765	0.007	<20	1.39	0.004	0.39	<0.1	15.28	0.3	0.19	24.1	2.3	5	<0.2
1093740	Rock	0.833	101	272	1.08	4437	0.008	24	1.66	0.004	0.44	<0.1	5.19	0.3	0.09	25.5	2.1	6	<0.2
1093741	Rock	0.756	112	240	0.80	3898	0.006	<20	1.58	0.003	0.42	0.1	18.91	0.3	0.09	24.6	2.6	7	<0.2
1093742	Rock	0.784	145	256	0.61	3431	0.007	21	1.73	0.004	0.41	0.1	1.02	0.3	0.07	25.7	1.2	7	<0.2
1093743	Rock	0.701	118	236	0.77	3566	0.006	<20	1.57	0.003	0.34	0.2	1.05	0.3	0.09	24.2	1.9	6	<0.2
1095980	Rock	0.056	2	5	0.05	955	<0.001	<20	1.01	0.002	0.08	<0.1	5.83	0.3	0.27	12.9	5.0	<1	<0.2
1285189	Rock	0.053	30	2	0.04	301	<0.001	<20	0.55	0.020	0.27	<0.1	2.99	0.3	0.34	1.4	2.1	1	<0.2
1285190	Rock	0.042	30	2	0.04	204	<0.001	<20	0.55	0.037	0.27	<0.1	2.01	0.3	0.28	1.2	1.2	1	<0.2
1285191	Rock	0.042	30	2	0.04	183	<0.001	<20	0.53	0.032	0.27	<0.1	1.78	0.2	0.25	1.1	0.8	1	<0.2
1285192	Rock Pulp	0.053	6	28	0.58	115	0.118	<20	1.26	0.083	0.11	0.2	0.10	<0.1	0.06	3.5	<0.5	5	<0.2
1285193	Rock	0.012	<1	<1	11.99	9	<0.001	<20	<0.01	0.002	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

QUALITY CONTROL REPORT WHI11001723.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
REP 1285122	QC		524																		
1285412	Rock	3.24	<2	3.8	81.0	7.6	638	0.2	295.4	60.2	1172	4.67	105.7	<0.5	13.0	469	4.0	2.7	<0.1	101	12.91
REP 1285412	QC			3.7	79.5	7.8	635	0.2	293.3	60.0	1161	4.66	109.1	<0.5	13.4	459	3.9	2.7	<0.1	99	12.82
1093743	Rock	1.15	<2	3.5	111.2	17.3	67	0.2	664.6	100.2	1496	7.85	109.6	1.3	20.7	284	0.4	1.3	<0.1	159	4.60
REP 1093743	QC			3.2	108.8	17.1	64	0.2	657.9	96.8	1479	7.78	107.5	0.5	19.9	280	0.5	1.1	<0.1	159	4.57
1285191	Rock	6.37	8	0.6	8.3	46.9	93	0.2	9.5	3.3	36	2.21	143.7	6.4	13.2	32	0.1	4.1	0.3	2	<0.01
REP 1285191	QC		8																		
Core Reject Duplicates																					
1285122	Drill Core	2.09	167	0.8	81.8	24.3	188	0.8	7.8	6.9	88	3.13	627.5	151.0	11.0	61	2.2	5.2	1.5	<2	0.81
DUP 1285122	QC		186	0.9	81.3	24.2	172	0.8	7.3	6.9	87	3.11	701.8	170.2	10.7	59	2.0	5.1	1.5	<2	0.78
1093741	Rock	1.25	<2	4.7	140.5	18.4	9107	0.3	649.2	108.2	1381	5.82	100.7	0.7	23.2	374	84.0	1.6	<0.1	168	5.92
DUP 1093741	QC		<2	4.6	147.3	18.7	9465	0.2	659.9	111.3	1435	5.97	103.6	1.4	23.4	383	85.3	1.7	<0.1	172	6.14
Reference Materials																					
STD DS8	Standard			13.3	105.4	121.0	317	1.9	37.1	7.3	620	2.47	26.1	111.2	7.0	71	2.4	5.3	6.7	41	0.72
STD DS8	Standard			13.7	108.6	118.0	302	1.6	36.3	7.2	579	2.41	23.5	86.4	6.7	66	2.4	3.4	6.3	40	0.66
STD DS8	Standard			14.4	107.6	120.4	299	1.6	35.7	7.4	593	2.50	24.0	112.3	7.3	77	2.3	5.6	7.4	40	0.74
STD DS8	Standard			14.2	110.4	131.8	318	1.8	38.8	7.6	616	2.54	26.7	112.2	7.0	83	2.3	5.5	7.6	42	0.74
STD OREAS45CA	Standard			0.7	523.0	21.2	61	0.3	248.2	88.9	935	16.10	3.8	49.2	7.0	14	0.1	<0.1	0.2	222	0.42
STD OREAS45CA	Standard			0.7	498.1	18.8	62	0.3	244.2	86.3	900	15.20	3.9	40.1	6.4	15	0.1	0.1	0.1	214	0.41
STD OREAS45CA	Standard			0.9	521.8	19.8	62	0.3	251.3	89.3	940	16.34	3.8	38.5	7.4	18	<0.1	0.1	0.2	228	0.45
STD OREAS45CA	Standard			0.6	540.6	21.1	64	0.3	264.9	93.5	973	16.49	4.9	59.7	7.2	19	<0.1	<0.1	0.2	225	0.45
STD OXC88	Standard		192																		
STD OXC88	Standard		195																		
STD OXC88	Standard		207																		
STD OXH82	Standard		1226																		
STD OXH82	Standard		1332																		
STD OXH82	Standard		1288																		
STD OXH82	Standard		1247																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

QUALITY CONTROL REPORT WHI11001723.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
REP 1285122	QC																		
1285412	Rock	0.410	63	149	3.56	391	0.005	<20	0.99	0.007	0.31	<0.1	8.83	0.2	0.30	16.3	0.7	3	<0.2
REP 1285412	QC	0.452	63	157	3.59	288	0.005	21	0.96	0.007	0.30	<0.1	9.03	0.2	0.29	16.6	<0.5	3	<0.2
1093743	Rock	0.701	118	236	0.77	3566	0.006	<20	1.57	0.003	0.34	0.2	1.05	0.3	0.09	24.2	1.9	6	<0.2
REP 1093743	QC	0.696	115	234	0.76	3381	0.006	<20	1.59	0.003	0.34	0.1	1.06	0.3	0.09	24.0	1.4	6	<0.2
1285191	Rock	0.042	30	2	0.04	183	<0.001	<20	0.53	0.032	0.27	<0.1	1.78	0.2	0.25	1.1	0.8	1	<0.2
REP 1285191	QC																		
Core Reject Duplicates																			
1285122	Drill Core	0.043	12	1	0.04	76	0.001	<20	0.45	0.007	0.28	0.2	24.19	3.7	3.33	0.3	11.7	1	0.7
DUP 1285122	QC	0.044	12	2	0.04	76	<0.001	<20	0.44	0.007	0.28	0.2	22.62	3.7	3.30	0.3	14.3	1	1.0
1093741	Rock	0.756	112	240	0.80	3898	0.006	<20	1.58	0.003	0.42	0.1	18.91	0.3	0.09	24.6	2.6	7	<0.2
DUP 1093741	QC	0.779	116	251	0.82	4185	0.007	<20	1.67	0.004	0.43	0.1	19.92	0.4	0.09	25.3	2.9	7	<0.2
Reference Materials																			
STD DS8	Standard	0.080	15	110	0.61	294	0.123	<20	0.95	0.093	0.42	2.5	0.15	5.5	0.16	2.1	5.1	5	5.0
STD DS8	Standard	0.071	14	109	0.59	264	0.111	<20	0.91	0.088	0.40	2.0	0.17	5.1	0.15	1.8	4.3	4	4.8
STD DS8	Standard	0.081	16	115	0.63	286	0.114	<20	0.94	0.088	0.42	2.3	0.35	5.2	0.16	1.9	5.0	4	4.9
STD DS8	Standard	0.085	17	113	0.63	298	0.144	<20	0.98	0.098	0.43	2.6	0.26	5.6	0.16	2.2	4.8	5	5.2
STD OREAS45CA	Standard	0.037	17	656	0.17	163	0.145	<20	3.83	0.006	0.08	<0.1	0.05	<0.1	<0.05	38.9	1.0	19	<0.2
STD OREAS45CA	Standard	0.036	16	624	0.15	149	0.125	<20	3.80	0.008	0.08	<0.1	0.01	<0.1	<0.05	35.1	0.5	17	<0.2
STD OREAS45CA	Standard	0.037	16	602	0.16	155	0.142	<20	4.00	0.006	0.08	<0.1	0.20	<0.1	<0.05	37.5	1.0	19	<0.2
STD OREAS45CA	Standard	0.038	18	592	0.15	171	0.133	<20	3.99	0.005	0.08	<0.1	0.03	<0.1	<0.05	42.8	0.7	19	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

QUALITY CONTROL REPORT WHI11001723.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
STD OXH82	Standard		1361																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
Prep Wash																					
G1	Prep Blank	<0.01	<2	0.2	2.1	3.1	41	<0.1	2.0	3.4	538	1.95	<0.5	<0.5	5.4	63	<0.1	<0.1	<0.1	36	0.47
G1	Prep Blank	<0.01	11	0.1	2.2	2.6	41	<0.1	2.1	3.5	537	1.96	<0.5	<0.5	4.9	65	<0.1	<0.1	<0.1	36	0.46

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 21, 2011

QUALITY CONTROL REPORT WHI11001723.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
STD OXH82	Standard																		
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
STD OXC88 Expected																			
STD OXH82 Expected																			
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
Prep Wash																			
G1	Prep Blank	0.071	14	5	0.47	141	0.123	<20	0.87	0.077	0.43	<0.1	<0.01	0.3	<0.05	1.7	<0.5	4	<0.2
G1	Prep Blank	0.070	13	5	0.46	135	0.122	<20	0.86	0.076	0.43	<0.1	<0.01	0.2	<0.05	1.7	<0.5	4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Email Distribution List
Receiving Lab: Canada-Whitehorse
Received: September 19, 2011
Report Date: November 17, 2011
Page: 1 of 6

CERTIFICATE OF ANALYSIS WHI11001732.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #28
P.O. Number
Number of Samples: 143

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-500	143	Crush, split and pulverize 500 g rock to 200 mesh			VAN
3B	143	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	143	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

CERTIFICATE OF ANALYSIS WHI11001732.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1279315	Rock	1.49	<2	0.5	4.4	5.2	3	0.3	3.4	0.7	51	0.75	5.4	<0.5	0.2	17	<0.1	0.7	<0.1	8	<0.01
1285443	Rock	0.95	<2	0.3	3.7	7.3	64	<0.1	14.0	22.5	590	1.77	1.4	<0.5	0.5	6	<0.1	0.2	<0.1	9	0.02
1285444	Rock	1.05	<2	<0.1	0.5	67.1	117	<0.1	75.6	11.0	1241	0.40	1.6	2.4	2.2	11	0.5	<0.1	2.6	<2	0.03
1285445	Rock	1.02	<2	0.8	21.4	5.8	90	<0.1	27.6	5.3	117	3.61	7.3	<0.5	2.5	8	<0.1	0.4	0.1	20	<0.01
1285446	Rock	0.94	<2	<0.1	0.3	62.1	55	<0.1	6.7	1.8	235	0.41	<0.5	<0.5	2.5	127	0.2	<0.1	3.8	<2	0.48
1285447	Rock	0.81	<2	0.2	5.4	3.8	53	<0.1	16.7	4.7	187	2.01	3.0	<0.5	1.1	27	<0.1	<0.1	<0.1	15	0.07
1285451	Rock	1.55	<2	0.9	18.4	3.1	149	<0.1	49.0	15.1	714	4.69	5.2	<0.5	1.0	6	0.5	0.2	<0.1	21	0.02
1285452	Rock	1.36	16	2.5	11.6	46.6	42	0.2	4.3	0.8	49	0.68	35.9	<0.5	1.1	25	0.3	0.3	6.2	10	0.09
1285453	Rock	1.15	11	0.2	12.6	81.4	22	0.1	2.4	0.4	30	0.70	68.4	10.3	1.0	25	<0.1	0.8	1.7	<2	0.03
1285454	Rock	1.83	<2	0.1	4.5	48.4	86	0.1	15.5	2.6	161	0.66	83.8	<0.5	1.3	21	0.5	0.2	2.6	<2	0.15
1285455	Rock	1.90	40	0.4	3.9	78.1	46	0.3	8.6	1.7	754	0.56	124.3	39.2	1.2	10	0.6	2.1	0.7	<2	0.02
1285456	Rock	1.22	12	0.8	18.7	3.4	361	<0.1	40.1	7.9	524	4.67	9.3	2.5	0.4	5	0.5	0.5	<0.1	20	0.02
1285457	Rock	1.17	<2	10.5	30.9	47.5	438	0.5	54.0	4.8	233	4.25	12.9	0.6	2.0	42	1.6	1.6	0.7	26	0.08
1285458	Rock	1.26	4	0.1	1.2	55.3	29	<0.1	2.7	0.4	81	0.34	174.5	6.8	2.2	25	0.3	0.2	0.8	<2	0.15
1285459	Rock	2.32	<2	1.3	18.6	1.8	108	<0.1	49.7	10.6	1574	7.42	4.2	0.5	0.9	46	0.5	0.3	<0.1	16	0.96
1285460	Rock	1.26	<2	1.0	20.4	3.4	156	<0.1	76.7	17.0	1496	9.87	12.8	<0.5	1.7	45	1.1	0.2	<0.1	25	0.48
1285461	Rock	1.46	<2	2.0	55.4	13.4	111	0.5	57.4	8.3	238	2.91	13.0	<0.5	0.4	11	0.5	1.7	<0.1	45	0.01
1285431	Rock	5.41	<2	9.4	94.7	17.1	150	0.2	519.5	78.4	1136	4.87	37.4	<0.5	18.8	765	1.1	0.6	<0.1	179	15.78
1285433	Rock	5.35	3	8.6	72.1	18.6	255	0.4	461.6	66.0	1298	6.71	61.8	<0.5	16.3	714	2.1	3.3	<0.1	120	16.67
1285425	Rock	5.21	3	4.7	60.3	5.4	53	<0.1	445.5	58.1	1359	6.60	103.4	<0.5	12.3	532	0.2	1.1	<0.1	114	13.03
1279306	Rock	1.57	<2	0.4	5.8	1.2	25	<0.1	16.9	2.5	81	1.19	151.1	<0.5	0.7	10	0.1	0.4	<0.1	6	0.25
1279307	Rock	1.32	36	0.3	10.1	1.8	62	<0.1	14.9	2.6	97	1.43	349.0	31.4	0.6	7	0.2	1.2	<0.1	5	0.03
1279308	Rock	1.58	35	0.3	7.7	1.4	14	<0.1	5.4	0.8	50	0.93	139.6	28.5	0.5	8	0.1	0.9	<0.1	3	0.06
1279309	Rock	1.71	2	0.2	1.3	1.0	3	<0.1	1.7	0.3	52	0.52	16.8	1.1	0.4	6	<0.1	<0.1	<0.1	<2	0.01
1279311	Rock	1.69	4	0.4	6.9	1.6	45	<0.1	17.6	3.7	102	1.54	178.7	1.5	1.0	3	0.3	0.7	<0.1	5	0.03
1279312	Rock	2.07	2	0.4	1.1	1.6	4	<0.1	3.2	0.6	51	0.61	6.4	<0.5	<0.1	3	<0.1	<0.1	<0.1	<2	<0.01
1279314	Rock	1.70	5	0.2	175.2	30.2	83	0.3	9.8	7.0	259	3.64	5.5	3.2	15.6	12	0.7	0.3	0.3	<2	1.31
1104436	Rock	1.08	2	0.7	28.9	2.2	23	<0.1	188.3	26.9	667	4.12	258.4	<0.5	4.7	481	<0.1	0.9	<0.1	57	5.10
1104437	Rock	0.62	<2	13.1	30.5	2.7	111	0.3	37.2	1.2	235	0.43	11.3	<0.5	0.4	594	1.1	7.4	<0.1	250	19.70
1285436	Rock	1.17	35	65.1	8.7	85.8	4	1.0	1.9	0.3	62	4.05	182.6	2.0	7.0	48	<0.1	6.4	0.2	31	0.02

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

CERTIFICATE OF ANALYSIS WHI11001732.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1279315	Rock	0.008	<1	7	<0.01	89	<0.001	<20	0.07	0.002	0.06	<0.1	0.02	<0.1	<0.05	0.2	<0.5	<1	<0.2
1285443	Rock	0.017	<1	19	0.19	15	<0.001	<20	0.42	<0.001	0.02	<0.1	0.02	0.1	<0.05	1.0	<0.5	1	<0.2
1285444	Rock	0.009	2	<1	0.10	294	<0.001	<20	0.66	0.035	0.22	<0.1	0.18	0.1	<0.05	0.2	<0.5	1	<0.2
1285445	Rock	0.049	1	26	0.45	68	0.001	<20	1.35	<0.001	0.11	<0.1	0.04	<0.1	<0.05	3.3	<0.5	3	<0.2
1285446	Rock	0.008	2	<1	0.04	171	<0.001	<20	0.40	0.035	0.24	<0.1	0.05	0.1	<0.05	0.1	<0.5	<1	<0.2
1285447	Rock	0.035	<1	16	0.36	30	0.001	<20	0.81	0.001	0.05	<0.1	<0.01	<0.1	<0.05	0.8	<0.5	2	<0.2
1285451	Rock	0.030	1	17	0.08	135	<0.001	<20	0.35	0.002	0.04	<0.1	0.02	0.1	<0.05	3.6	0.7	<1	<0.2
1285452	Rock	0.008	3	2	0.02	1349	<0.001	<20	0.42	0.002	0.20	<0.1	0.27	0.1	0.10	0.5	0.8	<1	<0.2
1285453	Rock	0.010	1	2	0.01	1893	<0.001	<20	0.41	0.002	0.20	<0.1	0.49	<0.1	0.07	0.2	1.3	<1	<0.2
1285454	Rock	0.010	1	<1	0.02	385	<0.001	<20	0.42	0.002	0.24	<0.1	0.17	0.2	<0.05	0.3	<0.5	<1	<0.2
1285455	Rock	0.007	1	1	<0.01	577	<0.001	<20	0.40	0.003	0.25	0.1	0.95	0.2	<0.05	0.2	<0.5	<1	<0.2
1285456	Rock	0.020	<1	8	0.03	3934	<0.001	<20	0.20	0.002	0.03	<0.1	0.12	<0.1	0.11	2.4	<0.5	<1	<0.2
1285457	Rock	0.033	3	3	0.03	4109	<0.001	<20	0.46	0.007	0.18	0.4	0.58	0.3	0.12	1.8	2.8	<1	<0.2
1285458	Rock	0.009	2	1	0.04	140	<0.001	<20	0.47	0.007	0.22	<0.1	0.06	0.1	<0.05	0.2	<0.5	<1	<0.2
1285459	Rock	0.032	1	17	0.38	151	<0.001	<20	0.44	0.003	0.05	<0.1	0.02	0.2	<0.05	3.0	<0.5	1	<0.2
1285460	Rock	0.049	2	16	0.49	180	<0.001	<20	0.68	0.003	0.08	<0.1	0.03	<0.1	<0.05	4.5	<0.5	2	<0.2
1285461	Rock	0.039	<1	19	0.01	141	<0.001	<20	0.36	0.002	0.05	<0.1	0.04	<0.1	<0.05	2.5	1.6	<1	<0.2
1285431	Rock	0.594	84	194	1.36	3059	0.007	<20	0.97	0.005	0.30	<0.1	5.93	0.3	0.06	18.3	1.1	3	<0.2
1285433	Rock	0.506	69	160	0.96	2255	0.008	<20	0.92	0.004	0.28	<0.1	9.12	0.6	0.11	18.2	3.0	3	<0.2
1285425	Rock	0.416	77	148	4.16	2073	0.006	<20	0.70	0.006	0.22	<0.1	0.47	0.1	0.05	15.1	<0.5	2	<0.2
1279306	Rock	0.022	3	31	0.11	72	<0.001	<20	0.26	<0.001	0.01	<0.1	0.42	<0.1	<0.05	0.6	<0.5	<1	<0.2
1279307	Rock	0.048	1	10	0.02	56	<0.001	<20	0.17	0.001	0.03	<0.1	0.12	<0.1	<0.05	1.0	<0.5	<1	<0.2
1279308	Rock	0.013	<1	18	<0.01	44	<0.001	<20	0.09	0.002	0.03	<0.1	0.09	<0.1	<0.05	0.5	<0.5	<1	<0.2
1279309	Rock	0.004	1	7	<0.01	48	<0.001	<20	0.07	0.001	0.03	<0.1	0.05	<0.1	<0.05	0.1	<0.5	<1	<0.2
1279311	Rock	0.013	2	29	0.09	28	<0.001	<20	0.32	<0.001	0.01	<0.1	0.11	<0.1	<0.05	0.7	0.6	<1	<0.2
1279312	Rock	0.002	<1	6	<0.01	23	<0.001	<20	0.03	<0.001	<0.01	<0.1	0.02	<0.1	<0.05	<0.1	<0.5	<1	<0.2
1279314	Rock	0.067	26	2	0.33	78	0.063	<20	2.22	0.015	0.29	2.6	0.08	0.2	0.39	0.7	4.9	4	<0.2
1104436	Rock	0.236	19	110	3.52	335	0.002	<20	0.54	0.002	0.08	<0.1	0.28	<0.1	0.57	7.5	<0.5	2	<0.2
1104437	Rock	0.020	3	12	0.50	219	0.001	<20	0.08	<0.001	0.03	<0.1	0.15	0.3	<0.05	0.9	1.0	<1	<0.2
1285436	Rock	0.087	3	15	0.01	204	0.001	<20	0.18	0.001	0.51	<0.1	2.24	1.2	0.82	0.8	38.1	1	0.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

CERTIFICATE OF ANALYSIS WHI11001732.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285437	Rock	0.96	76	112.4	19.6	27.0	15	1.4	2.0	0.1	25	3.17	482.3	11.7	13.7	102	0.5	9.6	0.6	373	0.03
1285438	Rock	0.95	4	2.9	82.6	13.1	1522	0.1	649.0	259.8	7217	11.26	24.7	<0.5	3.7	12	6.2	0.2	0.4	30	0.04
1285439	Rock	1.03	<2	0.5	8.7	1.8	64	<0.1	17.5	2.7	1771	7.15	3.0	<0.5	0.2	207	1.5	0.2	<0.1	17	8.26
1285440	Rock	1.13	<2	0.5	16.0	8.1	67	<0.1	19.3	2.6	226	4.01	49.4	2.7	4.5	10	0.5	2.9	0.2	55	0.06
1285441	Rock	0.96	20	0.5	29.2	38.1	92	0.4	5.6	3.7	137	2.12	493.9	25.0	13.0	112	1.3	2.5	0.2	<2	0.96
1285442	Rock	0.79	188	0.4	24.6	32.3	26	0.4	2.1	0.7	27	1.57	570.0	212.0	11.3	44	<0.1	4.7	0.2	<2	0.16
1285422	Rock	4.41	<2	4.9	80.2	9.5	37	0.2	498.8	61.6	1126	4.72	248.4	<0.5	20.4	497	0.2	2.0	<0.1	110	9.39
1285423	Rock	5.35	<2	5.3	73.9	8.8	35	0.1	538.1	70.2	1078	4.91	164.5	2.0	18.3	455	<0.1	1.6	<0.1	109	9.06
1285424	Rock	5.22	<2	3.8	59.1	6.3	36	<0.1	435.0	54.2	1247	5.44	85.8	1.9	14.0	515	0.1	1.3	<0.1	98	10.02
1285175	Rock	8.28	669	<0.1	5.8	53.3	18	9.8	<0.1	<0.1	<1	0.93	218.4	285.3	10.0	<1	0.1	13.6	0.4	3	0.10
1285176	Rock	6.32	301	1.4	17.4	35.8	91	9.0	15.4	5.4	65	2.15	195.1	12.6	6.8	13	0.3	9.1	0.5	15	0.02
1285428	Rock	6.30	<2	13.3	91.7	12.0	200	0.2	560.3	69.5	1380	6.22	13.2	2.1	20.7	387	1.5	0.8	<0.1	177	9.06
1285429	Rock	6.15	<2	18.6	79.1	12.4	241	0.2	467.1	57.2	1215	5.15	6.8	1.3	16.8	494	2.2	0.7	<0.1	195	9.85
1285430	Rock	4.73	<2	5.0	66.4	8.6	33	0.1	384.4	57.3	1252	5.46	5.0	1.6	17.5	472	0.2	0.4	<0.1	135	10.63
1285185	Rock	6.80	<2	1.7	42.7	17.6	236	<0.1	55.5	16.4	275	4.59	49.4	1.4	8.2	13	2.9	0.9	0.3	22	0.05
1285186	Rock	6.63	6	1.8	29.0	27.1	184	0.1	38.4	10.5	229	3.72	129.1	1.4	9.7	30	1.9	1.5	0.3	17	0.34
1285353	Rock	1.26	8	0.4	82.9	550.8	388	0.7	74.9	16.9	645	7.56	287.8	8.2	0.7	55	1.5	6.3	<0.1	12	0.08
1285354	Rock	1.23	4	0.4	102.8	11.9	161	0.2	17.8	5.1	56	15.23	180.0	2.8	2.1	55	<0.1	4.5	<0.1	229	0.01
1285355	Rock	1.02	7	0.5	20.2	3.6	196	0.1	41.8	6.2	82	1.84	34.4	11.6	0.4	3	0.2	0.7	<0.1	3	0.01
1285356	Rock	1.26	2	0.5	16.5	1.2	123	<0.1	24.2	2.4	53	0.99	17.3	5.7	0.5	10	0.2	0.7	<0.1	3	0.03
1285357	Rock	1.42	4	0.4	18.1	5.3	89	0.2	38.3	5.6	92	1.75	41.9	4.4	0.5	5	0.4	1.5	<0.1	3	0.03
1285358	Rock	1.57	4	0.7	55.9	4.3	250	0.4	49.5	5.6	83	2.91	13.6	4.0	0.6	6	0.2	0.7	<0.1	18	0.01
1285359	Rock	1.43	<2	0.5	13.2	1.2	68	<0.1	26.4	4.8	196	1.78	13.1	3.1	0.3	6	0.5	0.7	<0.1	5	0.34
1285360	Rock	2.12	4	7.6	791.3	17.9	1645	1.6	384.4	39.6	457	23.32	154.4	4.0	3.5	23	2.6	5.4	<0.1	68	0.04
1285361	Rock	2.55	2	0.7	34.8	2.6	56	0.3	19.2	1.9	84	1.29	31.4	2.3	0.5	30	0.9	1.6	<0.1	8	0.13
1285362	Rock	2.19	24	0.3	4.3	14.0	47	0.1	17.4	10.2	192	2.38	>10000	26.9	15.7	29	0.2	5.7	1.4	23	0.46
1285363	Rock	1.57	607	1.1	4.8	256.4	8	9.0	12.7	30.8	45	20.49	>10000	787.0	2.4	1	0.2	145.6	149.5	<2	<0.01
1285364	Rock	2.13	11	0.2	52.1	4322	1505	12.2	23.7	5.0	289	4.22	520.9	6.1	10.6	25	11.6	3.7	6.1	7	0.56
1285365	Rock	1.51	5	0.1	26.2	4832	306	25.7	4.4	1.2	56	4.25	2091	10.8	10.3	18	0.6	12.9	13.8	9	0.04
1285366	Rock	1.67	10	0.2	12.4	716.2	151	7.0	8.1	2.8	70	2.72	6177	15.7	13.2	17	1.0	3.2	6.2	9	0.10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

CERTIFICATE OF ANALYSIS WHI11001732.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285437	Rock	0.158	29	29	0.01	278	0.001	<20	0.51	<0.001	0.28	0.2	6.07	5.5	0.36	2.8	55.6	6	0.2
1285438	Rock	0.076	6	13	0.10	260	<0.001	<20	0.96	0.004	0.14	<0.1	0.16	0.7	<0.05	13.3	1.5	2	<0.2
1285439	Rock	0.006	<1	4	2.12	87	<0.001	<20	0.13	0.003	<0.01	<0.1	0.05	<0.1	<0.05	3.1	<0.5	<1	<0.2
1285440	Rock	0.043	12	33	1.02	98	0.017	<20	1.86	<0.001	0.24	<0.1	0.12	0.4	0.13	4.2	0.9	5	<0.2
1285441	Rock	0.046	19	2	0.15	119	0.001	<20	0.62	0.018	0.27	0.1	2.26	0.3	1.02	0.8	3.7	2	<0.2
1285442	Rock	0.023	23	3	0.02	146	<0.001	<20	0.47	0.004	0.29	0.2	10.87	0.3	0.41	0.3	8.5	<1	0.2
1285422	Rock	0.575	81	170	2.76	2776	0.005	<20	0.89	0.006	0.30	<0.1	2.36	0.2	0.13	19.8	0.5	2	<0.2
1285423	Rock	0.535	74	162	2.85	2306	0.005	<20	0.85	0.006	0.29	<0.1	1.45	0.2	0.15	19.1	1.2	2	<0.2
1285424	Rock	0.416	76	137	3.63	2371	0.007	<20	0.73	0.006	0.24	<0.1	0.62	0.2	0.10	15.0	0.6	2	<0.2
1285175	Rock	0.024	28	<1	<0.01	54	<0.001	<20	0.44	0.039	0.28	<0.1	64.80	0.9	0.12	0.5	20.5	<1	<0.2
1285176	Rock	0.025	28	6	0.02	94	<0.001	<20	0.45	0.001	0.21	<0.1	8.02	0.4	0.07	1.6	4.0	1	<0.2
1285428	Rock	0.561	82	175	1.69	2624	0.006	<20	1.04	0.005	0.34	<0.1	3.87	0.3	0.14	19.2	1.7	3	<0.2
1285429	Rock	0.499	71	137	1.74	3177	0.005	<20	0.89	0.006	0.29	<0.1	4.24	0.3	0.10	16.4	2.2	2	<0.2
1285430	Rock	0.455	75	164	3.09	3410	0.005	<20	0.81	0.007	0.26	<0.1	0.81	0.2	0.10	17.0	1.1	2	<0.2
1285185	Rock	0.049	31	11	0.08	136	<0.001	<20	0.74	0.004	0.21	<0.1	1.94	0.3	0.06	6.3	0.8	2	<0.2
1285186	Rock	0.050	29	8	0.15	142	<0.001	<20	0.66	0.004	0.24	<0.1	2.41	0.2	0.09	4.6	1.9	1	<0.2
1285353	Rock	0.161	2	10	0.04	1863	<0.001	<20	0.47	0.001	0.02	<0.1	0.60	<0.1	0.11	2.2	4.8	<1	<0.2
1285354	Rock	0.277	3	38	<0.01	382	0.001	<20	0.19	0.005	0.34	<0.1	0.33	<0.1	0.71	2.0	16.6	2	<0.2
1285355	Rock	0.015	2	11	0.03	2377	<0.001	<20	0.19	<0.001	<0.01	<0.1	0.81	<0.1	0.07	0.4	1.8	<1	<0.2
1285356	Rock	0.016	2	32	<0.01	68	<0.001	<20	0.15	0.001	0.01	<0.1	0.19	<0.1	<0.05	0.3	<0.5	<1	<0.2
1285357	Rock	0.018	2	10	0.02	122	<0.001	<20	0.16	<0.001	0.01	<0.1	1.22	<0.1	<0.05	0.4	1.1	<1	<0.2
1285358	Rock	0.021	3	23	0.06	84	<0.001	<20	0.45	<0.001	0.01	<0.1	0.40	<0.1	<0.05	2.7	2.1	<1	<0.2
1285359	Rock	0.016	<1	8	0.05	287	<0.001	<20	0.16	0.001	<0.01	<0.1	0.03	<0.1	<0.05	0.6	0.7	<1	<0.2
1285360	Rock	0.111	4	34	0.09	3336	<0.001	<20	3.78	<0.001	0.08	<0.1	0.56	<0.1	0.14	22.3	47.9	2	<0.2
1285361	Rock	0.017	1	11	0.02	211	<0.001	<20	0.20	0.002	0.03	<0.1	0.33	<0.1	<0.05	1.3	1.1	<1	<0.2
1285362	Rock	0.036	27	35	0.71	133	0.060	<20	1.65	0.155	0.69	0.2	<0.01	0.4	0.61	4.0	1.4	7	<0.2
1285363	Rock	0.001	2	3	0.01	17	0.003	<20	0.10	0.006	0.06	2.4	<0.01	<0.1	7.25	0.3	23.0	<1	1.0
1285364	Rock	0.037	11	10	0.22	36	0.005	<20	0.34	0.072	0.15	0.3	<0.01	0.1	2.00	4.1	1.4	1	<0.2
1285365	Rock	0.032	14	14	0.15	44	0.015	<20	0.40	0.078	0.21	0.6	0.10	0.2	0.48	2.7	2.0	2	<0.2
1285366	Rock	0.036	20	11	0.20	59	0.025	<20	0.62	0.081	0.24	<0.1	<0.01	0.1	0.28	2.7	1.3	2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

CERTIFICATE OF ANALYSIS WHI11001732.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285367	Rock	2.35	24	0.7	7.9	36.6	36	0.8	20.8	10.4	137	2.86	>10000	10.7	13.0	22	0.2	8.8	25.1	20	0.28
1285183	Rock	6.88	22	2.1	28.7	34.8	128	0.3	31.2	8.7	101	3.24	181.9	0.7	7.4	23	0.3	1.7	0.3	16	<0.01
1285184	Rock	6.78	10	1.4	33.7	24.8	181	0.1	45.2	10.2	180	4.19	102.2	1.1	8.6	19	0.8	1.4	0.3	22	<0.01
1285179	Rock	7.65	11	1.9	33.1	33.5	153	1.1	33.6	10.0	120	3.51	53.0	0.8	7.3	13	0.5	0.7	0.3	21	<0.01
1285180	Rock	7.12	6	2.1	23.5	15.9	120	0.2	23.1	7.9	111	3.14	141.7	0.7	5.3	21	0.2	1.3	0.3	21	<0.01
1285408	Rock	4.21	3	4.9	72.2	7.5	83	0.3	606.1	56.0	1366	4.36	192.6	2.0	16.6	445	1.3	3.1	<0.1	93	12.32
1285409	Rock	3.99	<2	4.6	84.2	9.2	97	0.2	502.2	58.5	1200	3.86	194.2	1.9	16.0	533	1.1	2.2	<0.1	93	10.81
1285410	Rock	4.03	3	4.8	98.9	13.5	289	0.4	427.9	64.8	1074	4.05	257.0	1.4	21.5	456	2.2	3.7	<0.1	108	10.21
1285411	Rock	4.12	<2	3.8	58.9	3.9	1269	0.2	201.4	46.7	979	3.71	167.4	<0.5	9.0	518	11.5	2.5	<0.1	88	12.45
1285369	Rock	1.36	6	3.0	75.5	17.0	226	0.6	51.7	9.3	232	3.26	11.3	0.7	7.4	43	1.0	0.8	0.2	175	0.61
1285370	Rock	1.62	<2	0.3	21.6	29.6	13	0.4	2.5	1.1	48	1.93	47.6	1.2	7.9	8	<0.1	0.3	0.4	2	0.06
1285371	Rock	1.28	<2	0.4	17.6	17.4	95	0.3	9.9	4.0	137	1.50	78.5	<0.5	10.2	18	0.3	2.7	0.4	5	0.33
1285372	Rock	1.84	18	0.2	26.2	10.2	81	0.2	24.4	7.9	252	1.51	442.9	16.8	10.0	34	0.6	0.6	0.2	2	0.97
1285373	Rock	1.06	196	0.2	9.4	6.5	47	0.1	12.5	5.2	185	2.09	>10000	178.6	9.5	27	0.4	5.8	1.2	12	0.27
1285374	Rock	1.58	239	0.4	9.4	44.9	26	1.6	8.3	6.8	142	2.97	>10000	219.0	11.4	26	0.2	13.1	89.3	12	0.35
1285375	Rock	1.23	13	1.7	25.9	10.7	27	0.2	34.6	11.6	146	1.88	6044	14.5	9.0	28	<0.1	3.8	1.6	35	0.42
1285376	Rock	1.14	144	0.5	18.2	15.9	13	1.0	11.5	13.2	98	3.04	>10000	155.3	11.2	14	0.2	16.5	32.4	7	0.24
1285377	Rock	3.47	72	0.4	34.0	202.9	26	5.2	22.9	16.0	141	5.25	>10000	74.3	10.6	20	0.2	23.2	21.5	19	0.22
1285378	Rock	1.37	4	3.5	13.5	4.2	66	0.9	8.3	1.2	87	2.16	61.0	<0.5	0.4	34	<0.1	6.4	0.1	34	<0.01
1285379	Rock	1.74	11	1.7	27.1	4.2	126	0.4	32.1	4.9	118	2.31	98.4	1.1	0.8	32	0.3	2.1	0.1	51	0.05
1285380	Rock	2.89	25	1.8	32.7	3.0	140	0.3	44.0	5.2	66	3.26	99.4	6.3	0.7	92	0.2	3.6	<0.1	94	0.10
1285381	Rock	1.58	<2	1.2	14.4	2.9	105	0.5	16.5	3.7	253	1.72	9.7	<0.5	0.4	31	0.3	0.9	<0.1	28	0.02
1285382	Rock	2.77	6	1.5	31.0	2.6	43	0.4	22.5	2.3	99	3.68	80.2	<0.5	1.0	169	0.1	4.2	<0.1	136	0.09
1285383	Rock	2.61	<2	2.1	6.9	2.9	8	0.4	6.6	0.2	42	1.42	23.9	<0.5	0.8	116	<0.1	1.9	<0.1	66	0.06
1285384	Rock	2.23	5	1.5	8.0	3.1	39	0.4	10.6	1.5	54	1.02	10.2	<0.5	0.5	48	<0.1	1.4	<0.1	37	0.04
1285385	Rock	1.55	6	2.0	2.4	4.7	1	3.4	0.9	<0.1	35	0.51	11.1	2.0	0.8	16	<0.1	7.0	0.1	34	<0.01
1285386	Rock	1.59	8	2.6	64.8	6.8	55	2.0	48.0	3.9	24	1.25	10.6	1.3	0.8	50	0.6	4.4	0.2	97	0.02
1104489	Rock	0.96	3	0.1	64.8	68.7	87	1.7	7.1	5.9	1075	3.08	171.3	2.7	11.6	54	0.3	0.7	2.6	5	1.68
1104490	Rock	1.07	138	0.3	7.0	10.4	18	0.2	10.2	13.6	214	2.69	>10000	134.7	13.2	28	<0.1	9.1	5.7	17	0.46
1104491	Rock	1.11	15	0.2	8.4	14.5	24	0.3	13.1	5.9	108	1.79	1923	12.9	15.7	15	0.1	1.4	0.8	18	0.33

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

CERTIFICATE OF ANALYSIS WHI11001732.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285367	Rock	0.036	21	17	0.38	120	0.047	<20	1.19	0.093	0.43	0.4	0.21	0.3	0.85	2.7	3.1	4	<0.2
1285183	Rock	0.035	24	7	0.02	220	<0.001	<20	0.56	0.004	0.20	<0.1	29.82	0.3	0.09	2.4	6.9	1	<0.2
1285184	Rock	0.048	30	12	0.13	174	<0.001	<20	0.78	0.004	0.20	<0.1	4.82	0.2	0.06	4.9	1.7	2	<0.2
1285179	Rock	0.042	30	8	0.02	160	<0.001	<20	0.57	0.004	0.20	<0.1	2.04	0.2	0.07	3.2	2.2	1	<0.2
1285180	Rock	0.029	21	8	0.02	149	<0.001	<20	0.54	0.003	0.18	<0.1	4.24	0.3	0.06	2.4	2.6	1	<0.2
1285408	Rock	0.486	79	156	3.04	2741	0.005	<20	0.85	0.007	0.26	<0.1	5.10	0.3	0.12	18.1	1.3	2	<0.2
1285409	Rock	0.490	72	152	2.98	2155	0.004	<20	0.83	0.007	0.26	<0.1	7.02	0.2	0.13	19.4	1.3	2	<0.2
1285410	Rock	0.582	83	192	2.20	3082	0.006	<20	1.08	0.005	0.32	<0.1	9.23	0.3	0.13	20.9	1.3	3	<0.2
1285411	Rock	0.395	62	104	3.99	2619	0.005	<20	0.47	0.007	0.19	<0.1	13.05	0.1	0.08	15.6	2.2	2	0.2
1285369	Rock	0.048	6	81	0.92	324	0.129	<20	2.86	0.040	0.90	<0.1	0.04	0.6	0.49	4.7	3.0	8	<0.2
1285370	Rock	0.036	14	2	0.10	60	0.003	<20	0.39	0.021	0.19	<0.1	0.05	<0.1	0.10	0.5	2.3	1	<0.2
1285371	Rock	0.038	13	8	0.23	56	0.025	<20	0.85	0.070	0.35	<0.1	0.02	0.2	0.36	0.8	0.8	3	<0.2
1285372	Rock	0.035	14	3	0.19	67	0.004	<20	0.64	0.033	0.21	<0.1	<0.01	0.1	0.43	0.7	1.9	2	<0.2
1285373	Rock	0.031	12	19	0.49	60	0.067	<20	1.39	0.083	0.54	3.3	0.01	0.4	0.59	1.8	1.9	4	0.3
1285374	Rock	0.033	18	13	0.39	101	0.070	<20	1.28	0.113	0.44	0.5	0.03	0.3	1.00	2.7	3.6	4	0.4
1285375	Rock	0.052	15	30	0.56	149	0.091	<20	1.45	0.116	0.62	0.2	<0.01	0.4	0.39	2.7	0.7	5	<0.2
1285376	Rock	0.036	18	31	0.19	57	0.033	<20	0.72	0.071	0.23	1.8	<0.01	0.1	1.24	1.2	4.0	3	0.5
1285377	Rock	0.032	14	31	0.65	81	0.079	<20	1.24	0.079	0.57	0.1	<0.01	0.3	2.15	3.0	7.8	5	0.3
1285378	Rock	0.033	<1	25	<0.01	410	<0.001	<20	0.14	0.005	0.06	<0.1	0.12	<0.1	0.11	1.5	5.1	1	<0.2
1285379	Rock	0.087	<1	18	0.19	1190	<0.001	<20	0.84	<0.001	0.05	<0.1	0.05	<0.1	0.08	2.1	1.5	2	<0.2
1285380	Rock	0.159	<1	30	0.23	141	<0.001	<20	1.14	<0.001	0.03	<0.1	0.07	<0.1	0.07	3.3	1.5	2	<0.2
1285381	Rock	0.028	<1	10	0.06	626	<0.001	<20	0.29	0.005	0.12	<0.1	0.10	0.1	0.21	1.1	1.1	<1	<0.2
1285382	Rock	0.244	1	42	0.51	1378	0.002	<20	1.44	<0.001	0.07	<0.1	0.06	<0.1	0.15	7.0	4.5	4	<0.2
1285383	Rock	0.154	<1	24	0.19	221	0.001	<20	0.59	0.003	0.10	<0.1	0.06	0.1	0.11	3.7	1.8	4	<0.2
1285384	Rock	0.058	<1	23	0.11	318	<0.001	<20	0.42	0.002	0.07	<0.1	0.08	<0.1	0.05	1.4	1.3	2	<0.2
1285385	Rock	0.013	6	11	<0.01	1084	<0.001	<20	0.14	<0.001	0.06	<0.1	0.34	0.1	0.06	0.6	23.1	<1	<0.2
1285386	Rock	0.040	2	21	0.02	276	0.001	<20	0.48	0.004	0.18	<0.1	1.20	0.3	0.96	1.5	6.7	2	0.3
1104489	Rock	0.056	9	2	0.26	46	0.001	<20	0.32	0.076	0.04	<0.1	<0.01	<0.1	0.44	6.1	<0.5	<1	<0.2
1104490	Rock	0.040	19	24	0.61	51	0.060	<20	1.44	0.164	0.56	9.1	<0.01	0.4	1.04	2.8	4.5	6	0.8
1104491	Rock	0.044	30	22	0.70	19	0.073	<20	1.18	0.106	0.48	0.2	<0.01	0.4	0.57	3.6	0.8	7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

CERTIFICATE OF ANALYSIS WHI11001732.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1104492	Rock	1.03	11	4.3	63.3	24.4	255	0.8	19.8	5.2	153	2.21	358.5	1.4	5.9	35	3.3	1.9	0.5	89	0.26
1104493	Rock	0.77	3	0.3	7.7	11.0	91	0.4	8.0	8.2	354	3.35	158.2	3.3	12.2	91	0.3	0.6	1.0	45	1.48
1104494	Rock	0.97	39	0.3	4.6	21.3	30	0.4	5.8	6.3	242	2.58	>10000	40.1	13.4	44	0.2	8.7	3.5	23	0.61
1104495	Rock	1.07	23	0.3	12.8	49.9	34	0.8	6.8	13.2	174	2.45	>10000	21.0	11.8	24	0.3	7.9	2.5	12	0.40
1285159	Rock	7.83	5	7.2	9.4	8.0	6	0.3	3.2	<0.1	9	0.49	19.1	<0.5	1.0	10	<0.1	3.6	0.1	49	<0.01
1285160	Rock	7.68	4	6.0	9.0	8.1	5	0.3	2.6	<0.1	5	0.46	12.3	<0.5	1.1	10	<0.1	3.8	0.1	39	<0.01
1285161	Rock	9.61	4	7.3	10.0	11.7	1	0.3	3.1	<0.1	4	0.46	8.9	<0.5	1.2	10	<0.1	2.8	0.2	34	<0.01
1285181	Rock	7.10	11	2.7	18.6	21.4	87	0.2	14.4	5.5	74	2.52	129.8	<0.5	4.3	29	<0.1	2.6	0.4	16	<0.01
1285182	Rock	6.89	65	1.6	34.1	27.0	166	0.5	28.9	10.1	137	3.45	139.9	1.2	6.7	28	0.4	3.1	0.3	16	<0.01
1285404	Rock	3.97	2	6.6	52.6	8.6	72	<0.1	349.0	50.6	716	4.72	36.9	<0.5	10.2	459	0.5	1.3	<0.1	60	17.78
1285405	Rock	4.30	2	12.4	45.5	10.5	25	0.1	314.7	39.2	756	4.98	34.8	<0.5	5.5	458	0.2	2.4	<0.1	39	21.40
1285406	Rock	3.77	<2	6.8	41.6	8.6	25	<0.1	326.6	40.6	756	4.54	45.4	<0.5	5.4	386	0.2	1.7	<0.1	38	19.40
1285407	Rock	4.23	3	5.4	73.5	9.8	80	0.5	381.1	49.7	1172	4.58	125.3	<0.5	11.8	658	1.4	8.2	<0.1	76	20.64
1285187	Rock	7.34	7	2.1	25.5	37.9	105	0.2	17.1	5.0	44	2.46	191.2	<0.5	9.7	24	0.3	4.4	0.4	9	0.02
1285188	Rock	8.06	11	0.7	14.0	49.3	158	0.3	20.7	7.5	92	2.75	293.9	8.9	14.7	24	0.4	6.5	0.5	2	0.02
1285177	Rock	6.22	15	2.1	33.9	29.3	216	1.7	41.5	13.0	237	3.46	60.3	<0.5	6.7	11	1.7	2.7	0.4	20	0.02
1285178	Rock	7.83	9	1.5	45.2	25.9	219	4.6	35.1	12.8	176	3.92	144.3	<0.5	6.4	12	0.7	4.4	0.5	20	0.01
1104334	Rock	1.69	5	0.5	20.0	5.3	18	0.2	11.9	5.0	555	1.47	1.7	<0.5	1.8	349	<0.1	0.4	<0.1	22	26.68
1104336	Rock	1.60	<2	0.2	8.6	3.8	33	0.1	3.2	1.4	56	0.55	177.7	1.2	0.3	1	0.3	0.6	<0.1	3	0.08
1104337	Rock	1.94	<2	0.5	17.6	1.9	13	<0.1	3.6	1.3	96	1.01	17.7	<0.5	0.3	5	<0.1	0.2	<0.1	4	0.12
1093998	Rock	1.43	35	0.7	16.6	4.5	18	2.1	19.4	1.8	43	1.50	36.7	5.6	1.1	8	<0.1	5.4	<0.1	7	0.05
1093999	Rock	1.54	4	0.5	8.2	2.6	6	0.3	1.0	0.1	23	0.55	26.1	3.5	0.1	40	<0.1	5.4	<0.1	8	<0.01
1285387	Rock	2.06	56	0.5	2.7	2.9	<1	1.3	1.4	0.1	32	0.60	37.6	15.6	0.7	21	<0.1	4.5	<0.1	7	<0.01
1285388	Rock	1.36	3	3.1	6.0	1.8	3	1.8	1.5	0.1	34	0.69	62.9	1.2	0.6	38	<0.1	8.3	<0.1	16	0.01
1283549	Rock	1.65	<2	0.4	19.1	3.0	10	<0.1	52.8	20.5	891	2.79	4.0	<0.5	2.0	280	<0.1	0.3	<0.1	84	21.10
1282452	Rock	1.21	25	20.1	7.3	50.1	111	0.8	8.8	2.6	53	2.86	913.9	3.8	0.9	17	0.6	31.9	0.3	10	0.02
1285389	Rock	1.55	<2	0.1	1.8	1.1	31	0.2	7.8	1.1	86	0.55	2.9	<0.5	0.4	385	1.4	0.3	<0.1	11	29.62
1285390	Rock	1.57	<2	0.3	3.1	1.4	34	0.3	10.8	1.3	73	0.50	3.3	<0.5	0.6	483	0.7	0.2	<0.1	14	21.12
1285391	Rock	1.76	<2	<0.1	0.5	0.5	30	<0.1	5.6	0.7	93	0.30	1.5	<0.5	0.2	425	0.8	0.1	<0.1	5	37.39
1285392	Rock	1.39	<2	0.6	4.6	2.3	36	0.2	10.5	1.8	509	1.00	3.3	<0.5	0.5	1325	0.7	0.2	<0.1	8	20.66

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

CERTIFICATE OF ANALYSIS WHI11001732.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1104492	Rock	0.056	7	47	0.67	240	0.056	<20	1.55	0.029	0.53	<0.1	0.03	0.3	0.58	2.6	7.8	6	<0.2
1104493	Rock	0.046	25	25	1.18	225	0.265	<20	3.68	0.328	1.17	<0.1	<0.01	0.5	0.79	10.1	1.0	11	<0.2
1104494	Rock	0.042	22	27	0.75	111	0.083	<20	1.78	0.172	0.63	0.2	<0.01	0.3	0.85	4.9	5.9	6	3.1
1104495	Rock	0.049	27	9	0.45	40	0.075	<20	0.96	0.096	0.30	0.2	<0.01	0.2	0.80	2.1	5.4	4	1.5
1285159	Rock	0.006	2	5	<0.01	173	<0.001	<20	0.30	0.003	0.11	<0.1	0.49	0.2	0.06	0.7	3.3	1	<0.2
1285160	Rock	0.005	1	<1	0.01	145	<0.001	<20	0.26	0.004	0.11	<0.1	0.25	0.2	0.07	0.6	3.7	1	<0.2
1285161	Rock	0.005	1	4	<0.01	269	<0.001	<20	0.31	0.006	0.15	<0.1	0.26	0.4	0.14	0.8	2.6	1	<0.2
1285181	Rock	0.026	17	6	0.01	175	<0.001	<20	0.44	0.004	0.17	<0.1	7.89	0.3	0.06	1.6	2.5	1	<0.2
1285182	Rock	0.036	22	7	0.02	270	<0.001	<20	0.47	0.003	0.18	<0.1	11.54	0.3	0.09	2.9	4.0	1	<0.2
1285404	Rock	0.314	39	113	2.27	34	0.005	<20	0.64	0.009	0.21	<0.1	0.20	0.2	3.37	12.1	1.2	2	<0.2
1285405	Rock	0.278	29	58	0.85	23	0.004	<20	0.70	0.012	0.20	<0.1	0.99	0.3	4.66	11.0	1.7	2	<0.2
1285406	Rock	0.252	24	44	0.84	26	0.004	<20	0.79	0.012	0.21	<0.1	2.94	0.2	3.84	9.5	1.5	2	<0.2
1285407	Rock	0.421	54	122	1.22	697	0.005	<20	0.69	0.005	0.21	<0.1	8.97	0.2	0.39	15.0	2.7	2	<0.2
1285187	Rock	0.053	28	5	0.02	171	<0.001	<20	0.49	0.003	0.20	<0.1	3.85	0.2	0.13	2.5	1.3	<1	<0.2
1285188	Rock	0.061	29	2	0.05	226	<0.001	<20	0.67	0.026	0.28	<0.1	2.21	0.2	0.21	1.6	1.2	1	<0.2
1285177	Rock	0.043	33	7	0.02	160	<0.001	<20	0.53	0.002	0.16	<0.1	2.73	0.2	<0.05	3.9	3.0	<1	<0.2
1285178	Rock	0.049	26	9	0.02	166	<0.001	<20	0.49	0.002	0.16	<0.1	1.97	0.2	0.06	3.5	1.9	1	<0.2
1104334	Rock	0.018	7	10	1.51	255	0.079	<20	1.54	0.018	0.72	0.1	0.04	0.1	0.55	3.2	0.5	4	<0.2
1104336	Rock	0.013	1	15	0.05	18	0.002	<20	0.08	0.002	0.02	<0.1	0.05	<0.1	<0.05	0.3	<0.5	<1	<0.2
1104337	Rock	0.011	<1	7	0.06	11	0.003	<20	0.10	<0.001	0.01	<0.1	0.02	<0.1	<0.05	0.3	1.4	<1	<0.2
1093998	Rock	0.043	4	8	<0.01	276	<0.001	<20	0.16	<0.001	0.05	<0.1	0.35	0.1	0.68	1.0	6.3	<1	<0.2
1093999	Rock	0.014	<1	6	<0.01	2216	<0.001	<20	0.05	<0.001	0.01	<0.1	0.06	<0.1	0.07	0.6	2.1	<1	<0.2
1285387	Rock	0.017	4	4	<0.01	385	<0.001	<20	0.12	<0.001	0.05	<0.1	0.21	0.2	0.06	0.5	5.0	<1	<0.2
1285388	Rock	0.032	3	8	<0.01	878	<0.001	<20	0.13	<0.001	0.05	<0.1	0.20	0.3	0.10	0.7	15.6	1	<0.2
1283549	Rock	0.143	5	63	0.21	236	0.002	<20	0.28	0.006	0.06	<0.1	0.03	<0.1	<0.05	11.2	<0.5	1	<0.2
1282452	Rock	0.736	1	18	<0.01	1893	0.006	<20	0.15	<0.001	0.04	1.4	1.07	0.6	0.14	4.1	88.9	1	0.3
1285389	Rock	0.083	6	7	0.11	200	0.002	<20	0.06	0.003	0.01	<0.1	0.04	<0.1	<0.05	0.9	<0.5	<1	<0.2
1285390	Rock	0.084	7	10	0.13	302	0.001	<20	0.14	0.005	0.03	<0.1	0.03	<0.1	<0.05	1.0	0.6	<1	<0.2
1285391	Rock	0.072	6	4	0.11	113	<0.001	<20	0.03	0.003	<0.01	<0.1	0.02	<0.1	<0.05	0.5	<0.5	<1	<0.2
1285392	Rock	0.062	7	8	0.26	345	<0.001	<20	0.10	0.005	0.03	<0.1	0.03	<0.1	0.05	1.2	0.7	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

CERTIFICATE OF ANALYSIS WHI11001732.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285393	Rock	1.37	<2	0.4	9.2	1.7	67	<0.1	15.5	3.4	94	1.52	3.8	<0.5	0.5	<1	0.2	<0.1	<0.1	9	0.19
1285394	Rock	1.64	<2	0.3	12.0	1.7	82	<0.1	31.9	6.1	174	1.66	1.9	<0.5	0.8	32	0.7	<0.1	<0.1	9	0.38
1285395	Rock	1.57	<2	0.3	1.9	0.9	30	0.2	6.4	0.7	72	0.31	1.1	<0.5	0.5	524	2.3	0.2	<0.1	17	31.91
1285396	Rock	1.56	<2	<0.1	1.6	0.7	43	<0.1	9.6	0.9	81	0.17	1.4	<0.5	0.2	132	1.0	0.3	<0.1	3	38.37
1094000	Rock	1.69	<2	0.3	7.7	0.9	16	<0.1	7.0	1.5	64	0.60	0.7	<0.5	0.4	<1	<0.1	<0.1	<0.1	<2	0.04
1285194	Rock	1.15	2	1.6	50.7	9.9	121	1.1	20.7	4.8	29	4.69	0.9	<0.5	3.2	11	<0.1	0.7	0.2	26	0.06
1279302	Rock	1.95	<2	0.2	5.4	1.7	47	<0.1	15.6	7.3	742	1.44	1.2	<0.5	0.5	7	<0.1	<0.1	<0.1	7	0.06
1279303	Rock	1.51	<2	1.6	16.0	22.8	46	<0.1	16.5	3.7	112	3.90	15.2	<0.5	3.0	18	<0.1	<0.1	0.3	23	0.06
1279304	Rock	1.22	<2	0.2	2.4	0.6	33	<0.1	9.1	1.2	113	0.38	3.4	<0.5	0.1	120	0.5	0.1	<0.1	3	35.90
1285169	Rock	9.05	4	3.0	11.7	57.9	155	0.8	16.2	3.2	29	1.88	135.1	<0.5	11.0	55	0.1	3.5	1.0	28	0.02
1285173	Rock	6.38	91	3.7	14.6	49.5	64	3.3	4.8	1.3	29	1.52	142.6	9.0	3.7	22	0.4	13.7	0.6	33	0.03
1285174	Rock	7.08	190	1.5	10.0	69.2	53	1.8	5.2	2.0	40	1.62	256.0	37.3	4.5	28	0.5	12.7	0.5	16	0.01
1104326	Rock	1.37	3	12.0	163.0	9.2	955	1.9	151.6	18.8	183	1.79	4.6	<0.5	4.2	40	11.1	2.9	0.1	318	2.16
1104327	Rock	2.03	<2	0.4	12.1	48.7	367	0.6	36.2	17.5	282	2.43	165.3	<0.5	15.1	45	1.3	1.1	0.6	29	0.69
1104328	Rock	1.78	3	31.9	11.0	161.1	5	1.6	0.9	0.1	31	1.85	38.2	<0.5	3.2	6	<0.1	4.0	0.3	66	<0.01
1104329	Rock	1.36	5	277.6	40.8	863.1	28	2.2	1.7	0.1	33	3.00	98.0	<0.5	7.3	193	3.1	60.5	0.3	276	0.03
1104330	Rock	1.88	<2	23.4	13.5	56.1	12	0.5	1.5	0.2	44	0.49	8.7	<0.5	0.8	9	0.3	3.7	0.3	74	0.02
1104331	Rock	1.35	3	73.3	31.4	13.4	549	0.8	91.2	2.9	155	1.07	30.3	<0.5	2.0	369	10.8	9.9	0.1	659	18.78
1104332	Rock	1.38	3	2.4	5.2	74.6	10	1.2	0.9	0.2	19	1.15	444.8	2.8	7.6	25	0.2	0.7	0.7	12	0.05
1104333	Rock	2.09	19	2.4	99.1	14.5	76	0.5	30.6	12.3	131	3.59	2.1	3.3	1.8	70	0.4	1.0	0.2	46	3.99
1285195	Rock	2.13	<2	1.2	5.1	1.3	168	0.1	11.4	3.3	740	2.21	1.2	<0.5	1.5	1196	0.8	0.2	0.1	13	17.57
1285426	Rock	6.73	<2	10.1	94.1	8.4	55	0.1	515.9	73.6	1146	4.61	37.2	0.9	17.3	433	0.3	0.9	0.1	170	10.57
1285427	Rock	5.22	<2	7.0	93.0	8.7	64	0.1	513.0	73.3	1337	5.06	26.5	1.3	17.6	411	0.5	0.6	<0.1	152	11.42

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

CERTIFICATE OF ANALYSIS WHI11001732.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285393	Rock	0.022	<1	6	0.06	852	<0.001	<20	0.28	<0.001	0.02	<0.1	0.03	<0.1	<0.05	0.9	1.0	<1	<0.2
1285394	Rock	0.020	2	6	0.12	77	<0.001	<20	0.39	<0.001	<0.01	<0.1	0.03	<0.1	<0.05	1.1	0.5	<1	<0.2
1285395	Rock	0.093	8	8	0.38	299	0.001	<20	0.06	0.006	0.01	<0.1	0.04	<0.1	<0.05	0.8	<0.5	<1	<0.2
1285396	Rock	0.081	4	4	0.06	97	0.001	<20	0.05	0.002	0.01	<0.1	0.08	<0.1	0.07	0.4	<0.5	<1	<0.2
1094000	Rock	0.009	<1	4	<0.01	48	<0.001	<20	0.10	0.012	<0.01	<0.1	<0.01	<0.1	<0.05	0.6	<0.5	<1	<0.2
1285194	Rock	0.022	8	13	0.03	472	0.001	<20	0.71	0.005	0.46	<0.1	0.13	<0.1	0.25	2.3	11.3	2	<0.2
1279302	Rock	0.034	<1	8	0.27	48	<0.001	<20	0.55	0.006	0.03	<0.1	<0.01	<0.1	<0.05	1.2	<0.5	2	<0.2
1279303	Rock	0.134	2	25	0.51	164	0.002	<20	1.39	0.018	0.17	<0.1	0.05	<0.1	0.13	3.3	<0.5	5	<0.2
1279304	Rock	0.025	3	3	0.06	36	<0.001	<20	0.05	<0.001	<0.01	<0.1	<0.01	<0.1	0.06	0.3	<0.5	<1	<0.2
1285169	Rock	0.061	28	3	0.03	142	<0.001	<20	0.45	0.012	0.25	<0.1	3.02	0.3	0.18	2.0	3.7	<1	<0.2
1285173	Rock	0.037	18	<1	0.02	120	<0.001	<20	0.34	0.002	0.17	<0.1	53.42	0.5	0.14	1.0	13.8	<1	<0.2
1285174	Rock	0.039	27	2	0.03	173	<0.001	<20	0.47	0.003	0.20	<0.1	>100	0.8	0.16	0.9	56.9	1	1.2
1104326	Rock	0.702	11	53	0.49	112	0.035	<20	1.81	<0.001	0.51	0.7	0.24	0.2	<0.05	2.4	5.3	5	<0.2
1104327	Rock	0.049	25	29	0.92	154	0.162	<20	2.20	0.169	0.63	<0.1	0.26	0.4	0.77	6.7	1.5	8	<0.2
1104328	Rock	0.028	4	6	0.01	161	0.008	<20	0.12	<0.001	0.37	0.2	0.07	0.6	0.56	0.4	7.2	<1	<0.2
1104329	Rock	0.321	24	64	0.01	435	0.030	<20	0.21	0.001	0.53	0.9	0.14	1.7	0.84	3.2	39.3	8	0.9
1104330	Rock	0.013	5	7	<0.01	69	0.002	<20	0.11	<0.001	0.07	0.1	0.10	0.2	<0.05	0.4	2.3	<1	<0.2
1104331	Rock	0.074	9	43	1.47	96	0.047	<20	0.96	<0.001	0.41	0.2	0.13	0.3	0.70	2.2	7.3	3	<0.2
1104332	Rock	0.045	24	6	0.01	146	<0.001	<20	0.30	0.002	0.27	0.1	<0.01	0.4	0.31	1.0	1.4	2	<0.2
1104333	Rock	0.309	9	30	1.45	241	0.068	<20	2.72	0.114	0.90	<0.1	0.01	0.3	1.17	5.0	2.4	9	<0.2
1285195	Rock	0.017	7	4	8.86	975	0.002	<20	0.16	0.011	0.09	<0.1	0.06	0.1	0.07	1.7	0.8	<1	<0.2
1285426	Rock	0.617	83	181	2.35	2772	0.006	<20	1.18	0.005	0.38	<0.1	1.02	0.2	0.09	18.7	0.9	4	<0.2
1285427	Rock	0.590	81	177	2.26	2583	0.005	<20	1.13	0.005	0.37	<0.1	1.28	0.2	0.09	19.1	0.7	3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

QUALITY CONTROL REPORT WHI11001732.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1285459	Rock	2.32	<2	1.3	18.6	1.8	108	<0.1	49.7	10.6	1574	7.42	4.2	0.5	0.9	46	0.5	0.3	<0.1	16	0.96
REP 1285459	QC		<2																		
1279314	Rock	1.70	5	0.2	175.2	30.2	83	0.3	9.8	7.0	259	3.64	5.5	3.2	15.6	12	0.7	0.3	0.3	<2	1.31
REP 1279314	QC			0.2	177.7	30.9	85	0.3	10.1	7.4	270	3.80	5.1	2.2	15.4	13	0.9	0.2	0.3	3	1.33
1285186	Rock	6.63	6	1.8	29.0	27.1	184	0.1	38.4	10.5	229	3.72	129.1	1.4	9.7	30	1.9	1.5	0.3	17	0.34
REP 1285186	QC			1.8	29.5	26.5	180	0.1	38.0	10.5	232	3.75	125.2	0.8	9.6	30	1.9	1.7	0.3	17	0.33
1285381	Rock	1.58	<2	1.2	14.4	2.9	105	0.5	16.5	3.7	253	1.72	9.7	<0.5	0.4	31	0.3	0.9	<0.1	28	0.02
REP 1285381	QC			1.5	14.7	3.0	107	0.4	16.2	3.9	260	1.76	9.5	<0.5	0.5	32	0.4	0.9	<0.1	28	0.01
1285383	Rock	2.61	<2	2.1	6.9	2.9	8	0.4	6.6	0.2	42	1.42	23.9	<0.5	0.8	116	<0.1	1.9	<0.1	66	0.06
REP 1285383	QC		23																		
1104492	Rock	1.03	11	4.3	63.3	24.4	255	0.8	19.8	5.2	153	2.21	358.5	1.4	5.9	35	3.3	1.9	0.5	89	0.26
REP 1104492	QC		9																		
1285407	Rock	4.23	3	5.4	73.5	9.8	80	0.5	381.1	49.7	1172	4.58	125.3	<0.5	11.8	658	1.4	8.2	<0.1	76	20.64
REP 1285407	QC		2																		
1104327	Rock	2.03	<2	0.4	12.1	48.7	367	0.6	36.2	17.5	282	2.43	165.3	<0.5	15.1	45	1.3	1.1	0.6	29	0.69
REP 1104327	QC			0.4	12.6	46.4	361	0.5	36.0	17.6	278	2.40	170.9	<0.5	15.2	44	1.3	1.1	0.6	28	0.70
Core Reject Duplicates																					
1285443	Rock	0.95	<2	0.3	3.7	7.3	64	<0.1	14.0	22.5	590	1.77	1.4	<0.5	0.5	6	<0.1	0.2	<0.1	9	0.02
DUP 1285443	QC		<2	0.3	3.9	1.9	66	<0.1	14.0	22.5	633	1.96	1.4	0.7	0.5	7	<0.1	<0.1	<0.1	10	0.02
1285422	Rock	4.41	<2	4.9	80.2	9.5	37	0.2	498.8	61.6	1126	4.72	248.4	<0.5	20.4	497	0.2	2.0	<0.1	110	9.39
DUP 1285422	QC		<2	5.1	78.6	9.3	36	0.2	495.6	61.6	1140	4.76	236.7	<0.5	19.6	495	<0.1	1.8	<0.1	108	9.49
1285371	Rock	1.28	<2	0.4	17.6	17.4	95	0.3	9.9	4.0	137	1.50	78.5	<0.5	10.2	18	0.3	2.7	0.4	5	0.33
DUP 1285371	QC		<2	0.2	17.6	17.2	56	0.3	8.8	3.8	130	1.46	89.3	0.8	10.2	16	0.2	1.0	0.4	5	0.32
1285178	Rock	7.83	9	1.5	45.2	25.9	219	4.6	35.1	12.8	176	3.92	144.3	<0.5	6.4	12	0.7	4.4	0.5	20	0.01
DUP 1285178	QC		9	1.6	46.1	24.6	218	3.7	36.1	13.3	178	3.97	147.6	<0.5	6.3	12	0.7	4.1	0.5	19	<0.01
1285426	Rock	6.73	<2	10.1	94.1	8.4	55	0.1	515.9	73.6	1146	4.61	37.2	0.9	17.3	433	0.3	0.9	0.1	170	10.57
DUP 1285426	QC		<2	9.6	94.0	8.1	52	0.1	502.2	70.4	1136	4.52	35.5	1.3	17.4	438	0.3	0.7	<0.1	169	10.49
Reference Materials																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

QUALITY CONTROL REPORT WHI11001732.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1285459	Rock	0.032	1	17	0.38	151	<0.001	<20	0.44	0.003	0.05	<0.1	0.02	0.2	<0.05	3.0	<0.5	1	<0.2
REP 1285459	QC																		
1279314	Rock	0.067	26	2	0.33	78	0.063	<20	2.22	0.015	0.29	2.6	0.08	0.2	0.39	0.7	4.9	4	<0.2
REP 1279314	QC	0.068	27	3	0.33	82	0.066	<20	2.21	0.015	0.29	2.5	0.05	0.2	0.40	0.8	5.0	5	<0.2
1285186	Rock	0.050	29	8	0.15	142	<0.001	<20	0.66	0.004	0.24	<0.1	2.41	0.2	0.09	4.6	1.9	1	<0.2
REP 1285186	QC	0.052	29	8	0.14	142	<0.001	<20	0.66	0.004	0.24	<0.1	2.38	0.2	0.09	4.4	1.9	1	<0.2
1285381	Rock	0.028	<1	10	0.06	626	<0.001	<20	0.29	0.005	0.12	<0.1	0.10	0.1	0.21	1.1	1.1	<1	<0.2
REP 1285381	QC	0.028	<1	10	0.06	630	<0.001	<20	0.29	0.004	0.12	<0.1	0.08	0.1	0.22	1.0	1.6	1	<0.2
1285383	Rock	0.154	<1	24	0.19	221	0.001	<20	0.59	0.003	0.10	<0.1	0.06	0.1	0.11	3.7	1.8	4	<0.2
REP 1285383	QC																		
1104492	Rock	0.056	7	47	0.67	240	0.056	<20	1.55	0.029	0.53	<0.1	0.03	0.3	0.58	2.6	7.8	6	<0.2
REP 1104492	QC																		
1285407	Rock	0.421	54	122	1.22	697	0.005	<20	0.69	0.005	0.21	<0.1	8.97	0.2	0.39	15.0	2.7	2	<0.2
REP 1285407	QC																		
1104327	Rock	0.049	25	29	0.92	154	0.162	<20	2.20	0.169	0.63	<0.1	0.26	0.4	0.77	6.7	1.5	8	<0.2
REP 1104327	QC	0.049	24	29	0.91	151	0.160	<20	2.21	0.169	0.63	<0.1	0.26	0.4	0.77	6.5	1.4	8	<0.2
Core Reject Duplicates																			
1285443	Rock	0.017	<1	19	0.19	15	<0.001	<20	0.42	<0.001	0.02	<0.1	0.02	0.1	<0.05	1.0	<0.5	1	<0.2
DUP 1285443	QC	0.019	<1	20	0.20	13	<0.001	<20	0.43	<0.001	0.02	<0.1	0.02	<0.1	<0.05	1.0	<0.5	1	<0.2
1285422	Rock	0.575	81	170	2.76	2776	0.005	<20	0.89	0.006	0.30	<0.1	2.36	0.2	0.13	19.8	0.5	2	<0.2
DUP 1285422	QC	0.566	78	163	2.80	2780	0.006	<20	0.87	0.006	0.29	<0.1	2.33	0.2	0.13	19.6	0.9	2	<0.2
1285371	Rock	0.038	13	8	0.23	56	0.025	<20	0.85	0.070	0.35	<0.1	0.02	0.2	0.36	0.8	0.8	3	<0.2
DUP 1285371	QC	0.037	12	6	0.24	52	0.024	<20	0.87	0.070	0.35	0.1	<0.01	0.3	0.36	0.9	<0.5	3	<0.2
1285178	Rock	0.049	26	9	0.02	166	<0.001	<20	0.49	0.002	0.16	<0.1	1.97	0.2	0.06	3.5	1.9	1	<0.2
DUP 1285178	QC	0.046	26	8	0.02	161	<0.001	<20	0.46	0.002	0.15	<0.1	2.14	0.2	0.06	3.5	2.0	1	<0.2
1285426	Rock	0.617	83	181	2.35	2772	0.006	<20	1.18	0.005	0.38	<0.1	1.02	0.2	0.09	18.7	0.9	4	<0.2
DUP 1285426	QC	0.611	82	177	2.33	2774	0.005	<20	1.17	0.002	0.38	<0.1	1.03	0.2	0.09	18.6	0.7	3	<0.2
Reference Materials																			

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

QUALITY CONTROL REPORT WHI11001732.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
STD DS8	Standard			13.6	116.8	131.4	328	1.8	40.1	7.7	646	2.63	27.5	99.6	7.6	78	2.5	5.3	7.4	46	0.75
STD DS8	Standard			14.0	106.1	128.9	297	1.8	35.8	7.2	611	2.48	24.1	102.7	7.0	60	2.3	4.5	5.9	42	0.69
STD DS8	Standard			13.6	110.0	122.6	319	1.8	39.7	7.4	605	2.51	25.1	100.4	6.1	69	2.1	5.1	6.8	41	0.70
STD DS8	Standard			14.7	111.9	127.1	302	1.7	38.5	7.5	611	2.52	26.2	97.6	7.1	67	2.3	4.7	6.0	42	0.75
STD DS8	Standard			12.8	109.9	120.5	322	1.8	37.2	7.4	630	2.53	27.2	100.2	6.6	70	2.7	5.0	6.8	41	0.74
STD OREAS45CA	Standard			0.8	556.9	23.6	79	0.3	280.4	101.4	991	18.40	4.6	45.0	8.0	19	0.1	<0.1	0.2	234	0.46
STD OREAS45CA	Standard			1.1	539.5	24.7	68	0.3	273.1	96.1	979	17.04	5.7	48.6	8.6	17	<0.1	0.1	0.2	216	0.42
STD OREAS45CA	Standard			1.1	523.8	20.4	62	0.3	257.6	92.1	949	16.27	4.9	41.6	7.1	17	<0.1	<0.1	0.2	226	0.42
STD OREAS45CA	Standard			0.9	546.4	22.6	69	0.3	270.0	99.1	955	17.30	3.9	46.6	8.6	16	<0.1	<0.1	0.2	233	0.49
STD OREAS45CA	Standard			0.9	539.2	23.4	66	0.3	255.6	89.0	985	16.36	4.3	42.1	7.4	17	0.1	0.1	0.2	228	0.43
STD OXC88	Standard		202																		
STD OXC88	Standard		193																		
STD OXC88	Standard		199																		
STD OXC88	Standard		193																		
STD OXC88	Standard		197																		
STD OXC88	Standard		193																		
STD OXC88	Standard		187																		
STD OXH82	Standard		1296																		
STD OXH82	Standard		1260																		
STD OXH82	Standard		1359																		
STD OXH82	Standard		1263																		
STD OXH82	Standard		1337																		
STD OXH82	Standard		1277																		
STD OXH82	Standard		1264																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

QUALITY CONTROL REPORT WHI11001732.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
STD DS8	Standard	0.081	15	126	0.64	300	0.133	<20	0.96	0.092	0.44	2.6	0.22	5.4	0.18	2.0	4.8	5	5.3
STD DS8	Standard	0.079	14	115	0.60	289	0.115	<20	0.91	0.090	0.42	2.6	0.18	5.2	0.17	2.1	5.1	4	5.4
STD DS8	Standard	0.080	14	116	0.62	289	0.124	<20	0.93	0.087	0.42	3.2	0.18	5.2	0.16	2.1	6.5	5	4.9
STD DS8	Standard	0.080	17	116	0.63	290	0.119	<20	0.96	0.091	0.43	3.1	0.19	5.3	0.16	2.2	5.0	5	4.6
STD DS8	Standard	0.086	16	114	0.63	321	0.123	<20	0.98	0.093	0.43	2.5	0.23	5.4	0.16	2.3	4.6	5	5.2
STD OREAS45CA	Standard	0.039	19	717	0.17	169	0.160	<20	4.27	0.005	0.08	<0.1	0.04	<0.1	<0.05	40.7	0.7	20	<0.2
STD OREAS45CA	Standard	0.036	19	776	0.17	188	0.147	<20	4.03	0.007	0.08	<0.1	<0.01	<0.1	<0.05	40.3	0.8	20	<0.2
STD OREAS45CA	Standard	0.039	17	676	0.18	164	0.166	<20	4.02	0.007	0.08	<0.1	0.02	<0.1	<0.05	39.9	1.0	20	<0.2
STD OREAS45CA	Standard	0.043	19	828	0.17	175	0.155	<20	4.33	0.005	0.09	<0.1	0.03	0.1	<0.05	41.1	0.6	19	<0.2
STD OREAS45CA	Standard	0.040	18	717	0.15	187	0.157	<20	4.08	0.005	0.08	<0.1	0.04	0.1	<0.05	41.4	0.6	20	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
STD OXC88 Expected																			
STD OXH82 Expected																			
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

QUALITY CONTROL REPORT WHI11001732.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
Prep Wash																					
G1	Prep Blank		<2	0.2	2.6	3.4	44	<0.1	2.7	3.9	580	2.20	<0.5	1.4	6.0	74	<0.1	0.1	<0.1	42	0.54
G1	Prep Blank		<2	0.2	2.4	3.0	43	<0.1	2.6	3.9	571	2.10	<0.5	<0.5	6.1	65	<0.1	0.3	0.1	41	0.47

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 17, 2011

QUALITY CONTROL REPORT WHI11001732.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	0.007	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
Prep Wash																			
G1	Prep Blank	0.072	13	6	0.53	153	0.143	<20	0.97	0.090	0.48	<0.1	0.03	0.3	<0.05	1.7	<0.5	5	<0.2
G1	Prep Blank	0.074	14	10	0.52	176	0.143	<20	0.94	0.085	0.48	<0.1	0.03	0.3	<0.05	1.8	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 25, 2011
Report Date: November 25, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001746.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #28
P.O. Number
Number of Samples: 6

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	6	Crush, split and pulverize 250 g rock to 200 mesh			WHI
4X4B	6	XRF Whole Rock & ICP-MS Trace Elements		Completed	VAN

SAMPLE DISPOSAL

STOR-PLP	Store After 90 days Invoice for Storage
STOR-RJT	Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 25, 2011

CERTIFICATE OF ANALYSIS WHI11001746.1

	Method	WGHT	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	2A Leco	2A Leco	4B	4B	4B
	Analyte	Wgt	SiO2	Al2O3	Fe2O3	CaO	MgO	Na2O	K2O	MnO	TiO2	P2O5	Cr2O3	Ba	LOI	SUM	TOT/C	TOT/S	Ba	Be	Co
	Unit	kg	%	%	%	%	%	%	%	%	%	%	%	%	%	%	%	%	ppm	ppm	ppm
	MDL	0.01	0.1	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.001	0.01	-5.11	0.01	0.02	0.02	1	1	0.2
PM11-913	Rock	1.09	66.9	15.58	3.44	3.05	0.93	1.96	4.13	0.05	0.38	0.12	0.006	0.18	3.08	99.80	0.22	0.55	1941	3	5.2
PM11-925	Rock	0.58	65.3	15.24	3.58	3.20	0.72	1.13	4.17	0.05	0.42	0.13	0.004	0.13	5.02	99.11	0.60	1.08	1339	<1	5.1
PM11-926	Rock	1.36	64.1	15.26	3.55	3.30	0.87	0.54	4.15	0.04	0.37	0.12	0.005	0.15	6.22	98.66	0.83	2.10	1498	1	6.1
PM11-930	Rock	1.60	67.4	15.78	3.77	3.24	0.95	2.74	3.85	0.07	0.40	0.13	<0.001	0.10	1.84	100.2	0.08	<0.02	1063	4	6.0
PM11-935	Rock	2.13	67.1	15.14	2.11	2.99	0.63	2.73	3.56	0.03	0.34	0.10	0.003	0.14	4.72	99.56	0.68	0.80	1516	4	3.8
PM11-937A	Rock	0.58	72.4	15.76	2.17	0.02	0.61	0.07	3.99	<0.01	0.32	0.03	0.002	0.12	3.89	99.41	<0.02	1.32	1175	3	2.4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 25, 2011

CERTIFICATE OF ANALYSIS WHI11001746.1

	Method	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B
	Analyte	Cs	Ga	Hf	Nb	Rb	Sn	Sr	Ta	Th	U	V	W	Zr	Y	La	Ce	Pr	Nd	Sm	Eu
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	0.1	0.5	0.1	0.1	0.1	1	0.5	0.1	0.2	0.1	8	0.5	0.1	0.1	0.1	0.1	0.02	0.3	0.05	0.02
PM11-913	Rock	21.8	18.5	3.9	13.2	182.9	3	284.2	1.3	17.4	4.8	22	3.4	149.8	10.3	42.4	79.6	8.83	30.1	5.10	1.07
PM11-925	Rock	19.3	17.9	3.6	11.1	184.0	4	218.4	1.1	16.0	4.2	19	5.9	137.2	12.0	38.7	74.5	8.30	29.1	4.77	1.02
PM11-926	Rock	18.5	17.7	3.6	11.2	188.2	3	264.7	1.0	15.1	4.0	19	4.4	150.9	12.1	37.8	71.3	7.87	27.2	4.54	1.07
PM11-930	Rock	7.3	18.8	4.1	12.3	159.6	4	301.3	1.4	16.4	4.2	20	1.2	154.3	13.7	41.0	78.1	8.77	31.7	5.09	1.05
PM11-935	Rock	15.1	18.5	3.7	9.9	144.3	<1	353.7	1.2	16.0	4.5	14	2.5	134.2	6.4	36.4	70.5	7.53	25.6	4.07	0.98
PM11-937A	Rock	12.1	20.1	3.9	12.1	206.3	14	14.8	1.2	12.0	4.5	14	2.4	147.9	4.5	43.7	83.6	9.03	28.6	4.72	0.98

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 25, 2011

CERTIFICATE OF ANALYSIS WHI11001746.1

	Method	4B	4B	4B	4B	4B	4B	4B	4B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Gd	Tb	Dy	Ho	Er	Tm	Yb	Lu	Mo	Cu	Pb	Zn	Ni	As	Cd	Sb	Bi	Ag	Au	Hg
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppb	ppm
	MDL	0.05	0.01	0.05	0.02	0.03	0.01	0.05	0.01	0.1	0.1	0.1	1	0.1	0.5	0.1	0.1	0.1	0.1	0.5	0.01
PM11-913	Rock	3.04	0.39	2.12	0.33	0.86	0.14	0.84	0.12	0.7	6.2	27.3	56	3.2	24.2	0.3	0.6	0.4	<0.1	1.4	0.38
PM11-925	Rock	3.23	0.41	2.02	0.38	1.02	0.15	1.01	0.15	0.9	16.0	39.7	53	3.4	65.5	0.3	0.9	1.1	0.1	1.2	1.24
PM11-926	Rock	3.21	0.42	2.38	0.38	1.07	0.19	1.18	0.16	0.8	12.5	39.3	47	4.9	456.6	0.2	1.6	0.9	0.2	36.7	6.30
PM11-930	Rock	3.47	0.48	2.48	0.43	1.05	0.18	1.08	0.17	0.4	2.2	13.1	65	3.3	15.0	0.1	0.5	0.2	<0.1	1.7	<0.01
PM11-935	Rock	2.52	0.28	1.41	0.16	0.45	0.07	0.43	0.06	0.7	10.5	48.8	87	5.4	164.6	1.3	0.6	0.2	0.4	7.2	0.34
PM11-937A	Rock	2.54	0.24	1.01	0.10	0.26	0.04	0.30	0.03	0.6	10.9	64.8	32	0.8	139.7	0.5	6.3	0.5	0.4	19.7	5.34

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 25, 2011

CERTIFICATE OF ANALYSIS WHI11001746.1

Method		1DX	1DX
Analyte		Tl	Se
Unit		ppm	ppm
MDL		0.1	0.5
PM11-913	Rock	0.2	0.8
PM11-925	Rock	0.4	0.7
PM11-926	Rock	0.6	3.9
PM11-930	Rock	<0.1	<0.5
PM11-935	Rock	0.8	3.1
PM11-937A	Rock	2.5	11.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 25, 2011

QUALITY CONTROL REPORT WHI11001746.1

	Method	WGHT	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	4X	2A Leco	2A Leco	4B	4B	4B
	Analyte	Wgt	SiO2	Al2O3	Fe2O3	CaO	MgO	Na2O	K2O	MnO	TiO2	P2O5	Cr2O3	Ba	LOI	SUM	TOT/C	TOT/S	Ba	Be	Co
	Unit	kg	%	%	%	%	%	%	%	%	%	%	%	%	%	%	%	%	ppm	ppm	ppm
	MDL	0.01	0.1	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.001	0.01	-5.11	0.01	0.02	0.02	1	1	0.2
Pulp Duplicates																					
PM11-926	Rock	1.36	64.1	15.26	3.55	3.30	0.87	0.54	4.15	0.04	0.37	0.12	0.005	0.15	6.22	98.66	0.83	2.10	1498	1	6.1
REP PM11-926	QC																				
Reference Materials																					
STD CSC	Standard																2.82	4.25			
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD OREAS76A	Standard																0.15	17.20			
STD SO-18	Standard																		520	<1	27.7
STD SO-18	Standard																		526	<1	27.0
STD SO-18	Standard		58.6	14.14	7.67	6.31	3.46	3.88	2.14	0.40	0.72	0.81	0.572	0.05	1.90	100.9					
STD SY-4(D)	Standard		50.2	20.92	6.27	7.96	0.54	7.31	1.63	0.11	0.27	0.12	0.002	0.05	4.56	100.3					
STD CSC Expected																	2.94	4.25			
STD OREAS76A Expected																	0.16	18			
STD DS8 Expected																					
STD OREAS45CA Expected																					
STD SY-4(D) Expected			49.9	20.69	6.21	8.05	0.54	7.1	1.66	0.108	0.287	0.131		0.034	4.56						
STD SO-18 Expected			58.47		7.67	6.42	3.35	3.71	2.17	0.39	0.69	0.83		0.0514					514	1	26.2
BLK	Blank																<0.02	<0.02			
BLK	Blank																				
BLK	Blank																		<1	<1	<0.2
BLK	Blank		<0.1	0.03	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.01	<0.001	<0.01	0.00	0.05					
Prep Wash																					
G1	Prep Blank		68.0	15.46	3.49	3.40	1.25	3.69	3.72	0.10	0.42	0.19	0.010	0.11	0.81	100.6	0.04	<0.02	1044	2	4.8
G1	Prep Blank		68.0	15.43	3.55	3.39	1.28	3.64	3.76	0.11	0.48	0.20	0.005	0.10	0.82	100.8	0.03	<0.02	1060	<1	4.8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 25, 2011

QUALITY CONTROL REPORT WHI11001746.1

	Method	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B	4B
	Analyte	Cs	Ga	Hf	Nb	Rb	Sn	Sr	Ta	Th	U	V	W	Zr	Y	La	Ce	Pr	Nd	Sm	Eu
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	0.1	0.5	0.1	0.1	0.1	1	0.5	0.1	0.2	0.1	8	0.5	0.1	0.1	0.1	0.1	0.02	0.3	0.05	0.02
Pulp Duplicates																					
PM11-926	Rock	18.5	17.7	3.6	11.2	188.2	3	264.7	1.0	15.1	4.0	19	4.4	150.9	12.1	37.8	71.3	7.87	27.2	4.54	1.07
REP PM11-926	QC																				
Reference Materials																					
STD CSC	Standard																				
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD OREAS76A	Standard																				
STD SO-18	Standard	6.8	17.4	9.2	19.4	28.0	14	422.8	6.6	9.5	16.3	208	13.3	285.4	31.5	12.5	26.3	3.29	12.8	2.75	0.84
STD SO-18	Standard	6.9	16.9	8.5	19.2	27.4	15	422.3	6.9	9.2	15.8	208	12.5	281.6	31.4	12.0	26.1	3.30	14.2	2.91	0.84
STD SO-18	Standard																				
STD SY-4(D)	Standard																				
STD CSC Expected																					
STD OREAS76A Expected																					
STD DS8 Expected																					
STD OREAS45CA Expected																					
STD SY-4(D) Expected																					
STD SO-18 Expected		7.1	17.6	9.8	21.3	28.7	15	407.4	7.4	9.9	16.4	200	14.8	280	31	12.3	27.1	3.45	14	3	0.89
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.5	<0.1	<0.1	<0.1	<1	<0.5	<0.1	<0.2	<0.1	<8	<0.5	<0.1	<0.1	<0.1	<0.1	<0.02	<0.3	<0.05	<0.02
BLK	Blank																				
Prep Wash																					
G1	Prep Blank	4.7	18.0	3.4	23.3	131.8	1	775.1	1.6	8.4	3.5	56	<0.5	137.1	18.4	31.2	61.5	6.88	25.2	4.24	1.11
G1	Prep Blank	4.6	18.3	3.6	25.6	132.8	<1	765.0	1.5	10.0	3.7	56	<0.5	136.7	19.4	35.6	67.5	7.58	26.4	4.47	1.15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 25, 2011

QUALITY CONTROL REPORT WHI11001746.1

	Method	4B	4B	4B	4B	4B	4B	4B	4B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Gd	Tb	Dy	Ho	Er	Tm	Yb	Lu	Mo	Cu	Pb	Zn	Ni	As	Cd	Sb	Bi	Ag	Au	Hg
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppb	ppm
	MDL	0.05	0.01	0.05	0.02	0.03	0.01	0.05	0.01	0.1	0.1	0.1	1	0.1	0.5	0.1	0.1	0.1	0.1	0.5	0.01
Pulp Duplicates																					
PM11-926	Rock	3.21	0.42	2.38	0.38	1.07	0.19	1.18	0.16	0.8	12.5	39.3	47	4.9	456.6	0.2	1.6	0.9	0.2	36.7	6.30
REP PM11-926	QC									1.0	12.7	39.1	50	5.0	455.3	0.3	1.6	0.9	0.2	32.9	6.11
Reference Materials																					
STD CSC	Standard																				
STD DS8	Standard									13.4	103.2	122.1	286	37.1	21.4	2.2	4.5	5.9	1.6	107.6	0.18
STD OREAS45CA	Standard									0.8	539.3	21.4	66	262.9	1.8	<0.1	<0.1	0.2	0.3	52.6	0.02
STD OREAS76A	Standard																				
STD SO-18	Standard	2.82	0.47	2.95	0.58	1.80	0.25	1.65	0.26												
STD SO-18	Standard	2.81	0.46	2.77	0.63	1.74	0.27	1.66	0.25												
STD SO-18	Standard																				
STD SY-4(D)	Standard																				
STD CSC Expected																					
STD OREAS76A Expected																					
STD DS8 Expected										13.44	110	123	312	38.1	26	2.38	4.8	6.67	1.69	107	0.192
STD OREAS45CA Expected										1	494	20	60	240	3.8	0.1	0.13	0.19	0.275	43	0.03
STD SY-4(D) Expected																					
STD SO-18 Expected		2.93	0.53	3	0.62	1.84	0.27	1.79	0.27												
BLK	Blank																				
BLK	Blank									<0.1	<0.1	<0.1	<1	<0.1	<0.5	<0.1	<0.1	<0.1	<0.1	<0.5	<0.01
BLK	Blank	<0.05	<0.01	<0.05	<0.02	<0.03	<0.01	<0.05	<0.01												
BLK	Blank																				
Prep Wash																					
G1	Prep Blank	3.33	0.48	2.99	0.55	1.51	0.27	1.86	0.29	0.1	2.5	3.4	51	3.3	<0.5	<0.1	0.1	<0.1	<0.1	<0.5	<0.01
G1	Prep Blank	3.54	0.51	3.22	0.54	1.71	0.29	1.95	0.32	0.2	2.1	3.2	52	4.0	<0.5	<0.1	0.2	<0.1	<0.1	0.8	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 25, 2011

QUALITY CONTROL REPORT WHI11001746.1

	Method	1DX	1DX
	Analyte	Tl	Se
	Unit	ppm	ppm
	MDL	0.1	0.5
Pulp Duplicates			
PM11-926	Rock	0.6	3.9
REP PM11-926	QC	0.5	4.1
Reference Materials			
STD CSC	Standard		
STD DS8	Standard	5.4	4.9
STD OREAS45CA	Standard	0.1	<0.5
STD OREAS76A	Standard		
STD SO-18	Standard		
STD SO-18	Standard		
STD SO-18	Standard		
STD SY-4(D)	Standard		
STD CSC Expected			
STD OREAS76A Expected			
STD DS8 Expected		5.4	5.23
STD OREAS45CA Expected		0.07	0.5
STD SY-4(D) Expected			
STD SO-18 Expected			
BLK	Blank		
BLK	Blank	<0.1	<0.5
BLK	Blank		
BLK	Blank		
Prep Wash			
G1	Prep Blank	0.3	<0.5
G1	Prep Blank	0.3	<0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 25, 2011
Report Date: November 14, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001754.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #31
P.O. Number
Number of Samples: 17

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	17	Crush, split and pulverize 250 g rock to 200 mesh			WHI
3B	17	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	17	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001754.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285418	Rock	3.23	<2	5.2	83.8	10.5	57	0.1	579.9	67.4	1324	5.72	108.2	<0.5	18.7	508	0.2	1.1	<0.1	121	10.83
1285419	Rock	3.43	<2	7.4	83.7	10.1	39	0.2	619.9	77.9	1205	5.41	230.2	<0.5	17.8	306	0.2	2.1	<0.1	137	9.15
1285420	Rock	4.05	<2	8.2	82.2	10.2	37	0.2	592.2	76.9	1274	5.40	214.7	4.4	18.8	328	0.1	2.6	<0.1	111	11.52
1279130	Rock	2.13	4	2.0	55.3	9.2	100	0.2	29.4	5.1	121	3.56	77.4	3.7	6.8	17	0.3	1.4	0.3	32	0.03
1279131	Rock	1.99	6	3.7	65.4	10.5	202	0.2	40.4	7.8	186	4.29	43.3	4.0	5.9	18	0.5	1.4	0.2	47	0.06
1279132	Rock	1.67	8	3.0	31.0	16.6	103	0.2	17.4	3.8	104	2.64	48.9	2.9	2.5	18	0.3	1.5	0.3	40	0.02
1279133	Rock	1.95	18	4.7	67.3	22.9	236	0.6	46.4	8.3	146	4.04	297.6	5.2	7.1	40	0.6	2.7	0.3	53	0.03
1279134	Rock	2.16	4	2.0	44.3	12.3	175	<0.1	34.0	7.3	144	3.60	35.5	2.8	7.1	15	0.5	0.8	0.3	37	0.02
1279135	Rock	2.32	3	2.6	58.3	19.0	197	0.2	46.7	9.3	136	4.11	69.2	2.6	7.1	19	0.6	1.4	0.3	41	0.02
1285421	Rock	4.14	3	7.7	78.4	10.2	38	0.2	571.6	72.0	1331	4.93	183.2	1.9	18.3	447	0.1	2.3	<0.1	95	12.17
1285432	Rock	5.87	4	7.3	72.0	13.2	108	0.2	392.2	61.3	1322	3.92	95.4	2.8	16.3	846	1.0	3.0	<0.1	127	16.65
1279313	Rock	2.58	335	0.8	24.2	86.3	121	9.2	13.7	4.7	82	1.68	>10000	350.3	7.4	<1	1.4	>2000	2.9	2	0.04
1285434	Rock	4.95	4	16.4	57.2	19.1	248	0.5	361.8	56.0	1445	3.79	63.7	0.8	13.3	638	3.6	6.8	<0.1	130	14.30
1285435	Rock	4.74	9	18.8	30.5	8.9	224	0.4	41.0	1.9	45	0.55	54.0	0.9	1.3	99	8.9	6.5	<0.1	131	0.43
1285448	Rock	0.69	<2	2.3	42.1	3.5	38	0.2	11.8	2.0	18	1.53	179.6	<0.5	7.2	8	0.1	3.7	0.4	20	0.04
1285449	Rock	0.99	65	0.7	9.3	42.0	76	0.4	4.9	5.2	204	1.11	3228	63.4	10.5	227	1.7	2.5	0.8	2	2.07
1289316	Rock	0.69	541	0.5	11.5	87.8	82	10.9	7.3	2.4	34	1.52	>10000	567.1	8.5	2	0.7	408.3	2.4	<2	0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001754.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285418	Rock	0.580	73	180	2.66	1023	0.007	<20	0.97	0.009	0.31	<0.1	0.85	0.2	0.22	19.6	1.4	3	<0.2
1285419	Rock	0.572	64	186	1.94	2710	0.007	<20	1.03	0.008	0.33	<0.1	2.58	0.2	0.11	20.6	1.0	4	<0.2
1285420	Rock	0.547	60	168	1.91	2336	0.008	<20	0.80	0.005	0.27	<0.1	2.24	0.2	0.11	19.2	0.6	2	<0.2
1279130	Rock	0.059	24	8	0.40	143	0.001	<20	1.30	0.004	0.13	<0.1	0.09	<0.1	<0.05	3.1	1.1	3	<0.2
1279131	Rock	0.057	21	20	0.58	226	<0.001	<20	1.61	0.004	0.14	<0.1	0.31	0.2	<0.05	4.5	0.6	4	<0.2
1279132	Rock	0.055	24	11	0.17	138	0.002	<20	0.86	0.009	0.12	<0.1	0.04	0.1	<0.05	1.6	<0.5	3	<0.2
1279133	Rock	0.076	20	18	0.45	1960	<0.001	<20	1.40	0.004	0.14	<0.1	2.38	0.2	0.09	4.0	3.1	3	<0.2
1279134	Rock	0.052	28	15	0.31	181	<0.001	<20	1.29	0.006	0.15	<0.1	0.06	<0.1	<0.05	2.9	1.0	3	<0.2
1279135	Rock	0.065	24	18	0.37	215	<0.001	<20	1.47	0.006	0.14	<0.1	0.19	0.1	<0.05	3.5	1.1	3	<0.2
1285421	Rock	0.569	69	152	2.35	2647	0.007	<20	0.74	0.005	0.25	<0.1	1.49	0.2	0.10	20.2	<0.5	2	<0.2
1285432	Rock	0.532	66	150	0.73	2509	0.005	<20	0.74	0.005	0.24	<0.1	11.81	0.4	0.06	15.9	0.8	2	<0.2
1279313	Rock	0.034	16	2	0.02	107	<0.001	<20	0.29	0.004	0.21	<0.1	37.90	0.5	0.88	0.8	24.3	<1	<0.2
1285434	Rock	0.448	55	115	1.21	2250	0.006	<20	0.66	0.005	0.21	<0.1	4.43	0.8	0.06	12.3	3.1	2	<0.2
1285435	Rock	0.033	6	10	0.03	681	0.001	<20	0.18	0.001	0.07	0.2	2.83	1.4	<0.05	0.8	2.1	<1	<0.2
1285448	Rock	0.080	25	9	0.03	156	<0.001	<20	0.33	0.007	0.16	<0.1	0.44	0.2	<0.05	0.9	1.7	1	<0.2
1285449	Rock	0.043	15	<1	0.16	152	<0.001	<20	0.37	0.024	0.23	0.1	0.30	0.4	0.78	0.7	5.0	<1	0.6
1289316	Rock	0.031	19	2	0.01	95	<0.001	<20	0.28	0.004	0.20	0.1	27.14	0.5	0.62	0.6	17.0	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

QUALITY CONTROL REPORT WHI11001754.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1285421	Rock	4.14	3	7.7	78.4	10.2	38	0.2	571.6	72.0	1331	4.93	183.2	1.9	18.3	447	0.1	2.3	<0.1	95	12.17
REP 1285421	QC		3																		
Core Reject Duplicates																					
1285432	Rock	5.87	4	7.3	72.0	13.2	108	0.2	392.2	61.3	1322	3.92	95.4	2.8	16.3	846	1.0	3.0	<0.1	127	16.65
DUP 1285432	QC		3	7.8	72.7	12.7	107	0.2	382.1	58.3	1339	3.81	91.9	1.3	15.5	845	0.8	2.8	<0.1	129	17.00
Reference Materials																					
STD DS8	Standard			14.8	116.0	131.9	321	1.8	39.8	7.8	637	2.63	26.6	106.9	7.3	75	2.6	4.7	7.5	43	0.75
STD DS8	Standard			11.9	102.2	116.3	296	1.8	35.9	7.0	580	2.32	22.6	103.3	5.8	61	2.1	4.6	6.0	37	0.66
STD OREAS45CA	Standard			0.6	532.6	21.5	64	0.3	268.4	94.8	991	17.32	4.6	37.0	7.0	17	0.1	<0.1	0.2	216	0.46
STD OREAS45CA	Standard			0.9	492.3	20.6	55	0.2	240.9	87.3	905	14.89	4.2	48.0	7.1	12	<0.1	<0.1	0.2	203	0.42
STD OXC88	Standard		208																		
STD OXC88	Standard		211																		
STD OXH82	Standard		1307																		
STD OXH82	Standard		1304																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
Prep Wash																					
G1	Prep Blank		<2	0.1	2.5	3.3	46	<0.1	3.0	4.1	562	2.01	1.2	<0.5	6.8	63	<0.1	<0.1	<0.1	41	0.58
G1	Prep Blank		<2	0.2	3.2	3.5	45	<0.1	3.5	4.2	586	2.08	1.0	<0.5	7.0	69	<0.1	<0.1	0.1	43	0.61

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

QUALITY CONTROL REPORT WHI11001754.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1285421	Rock	0.569	69	152	2.35	2647	0.007	<20	0.74	0.005	0.25	<0.1	1.49	0.2	0.10	20.2	<0.5	2	<0.2
REP 1285421	QC																		
Core Reject Duplicates																			
1285432	Rock	0.532	66	150	0.73	2509	0.005	<20	0.74	0.005	0.24	<0.1	11.81	0.4	0.06	15.9	0.8	2	<0.2
DUP 1285432	QC	0.502	67	146	0.74	2487	0.006	<20	0.73	0.005	0.24	<0.1	11.50	0.4	0.06	15.4	0.6	2	<0.2
Reference Materials																			
STD DS8	Standard	0.082	17	120	0.64	321	0.125	<20	0.99	0.100	0.44	2.8	0.20	5.8	0.17	2.3	5.7	5	5.2
STD DS8	Standard	0.076	12	106	0.57	259	0.101	<20	0.85	0.080	0.39	2.5	0.19	5.0	0.15	1.8	4.6	4	4.9
STD OREAS45CA	Standard	0.041	17	689	0.18	167	0.137	<20	4.06	0.009	0.08	<0.1	0.03	<0.1	<0.05	41.6	1.3	20	<0.2
STD OREAS45CA	Standard	0.036	15	682	0.13	150	0.117	<20	3.64	0.008	0.07	<0.1	0.03	<0.1	<0.05	37.3	<0.5	19	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
STD OXC88 Expected																			
STD OXH82 Expected																			
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
Prep Wash																			
G1	Prep Blank	0.080	16	3	0.55	181	0.142	<20	0.96	0.092	0.52	<0.1	<0.01	0.3	<0.05	2.2	<0.5	5	<0.2
G1	Prep Blank	0.091	18	9	0.57	189	0.149	<20	0.99	0.097	0.54	<0.1	<0.01	0.3	<0.05	2.3	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 22, 2011
Report Date: November 09, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001836.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #30
P.O. Number
Number of Samples: 3

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT Store After 90 days Invoice for Storage

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-500	3	Crush, split and pulverize 500 g rock to 200 mesh			VAN
3B	3	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	3	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001836.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1285401	Rock	3.54	<2	2.1	33.9	4.8	14	<0.1	183.0	28.1	928	3.17	53.6	<0.5	7.5	536	<0.1	0.7	<0.1	60	20.71
1285402	Rock	4.88	<2	3.6	48.8	9.7	33	<0.1	334.7	46.0	806	4.98	12.7	<0.5	11.2	596	0.2	0.7	<0.1	71	20.30
1285403	Rock	5.12	<2	7.4	47.5	7.9	50	<0.1	317.0	39.7	762	4.40	30.0	<0.5	8.2	405	0.3	1.0	<0.1	61	19.24

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001836.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1285401	Rock	0.288	37	108	2.16	55	0.004	24	0.43	0.011	0.15	<0.1	0.86	0.2	1.29	10.1	<0.5	2	<0.2
1285402	Rock	0.351	49	120	1.27	24	0.005	25	0.66	0.011	0.21	<0.1	1.33	0.2	3.87	12.3	0.8	2	<0.2
1285403	Rock	0.322	34	97	1.09	19	0.005	<20	0.57	0.010	0.18	<0.1	0.31	0.2	3.47	10.4	<0.5	2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 09, 2011

QUALITY CONTROL REPORT WHI11001836.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Reference Materials																					
STD DS8	Standard			12.2	108.5	121.2	309	1.7	37.2	7.5	598	2.47	25.6	112.0	6.4	68	2.0	4.6	6.4	42	0.70
STD OREAS45CA	Standard			0.9	502.4	19.2	64	0.3	249.3	91.2	938	16.01	3.9	41.8	6.8	16	<0.1	<0.1	0.2	212	0.44
STD OXC88	Standard		198																		
STD OXH82	Standard		1353																		
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		<2	0.1	2.2	5.2	54	<0.1	3.3	4.2	599	2.13	1.7	<0.5	5.9	69	<0.1	<0.1	<0.1	41	0.56

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 09, 2011

QUALITY CONTROL REPORT WHI11001836.1

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
		Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
		MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Reference Materials																				
STD DS8	Standard		0.081	13	116	0.61	294	0.123	<20	0.90	0.084	0.41	2.6	0.21	5.1	0.17	2.1	4.5	4	4.1
STD OREAS45CA	Standard		0.038	16	642	0.17	160	0.148	<20	3.63	0.008	0.07	<0.1	0.03	<0.1	<0.05	36.6	<0.5	18	<0.2
STD OXC88	Standard																			
STD OXH82	Standard																			
STD OXC88 Expected																				
STD OXH82 Expected																				
STD DS8 Expected			0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected			0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																			
BLK	Blank																			
BLK	Blank		<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																				
G1	Prep Blank		0.085	13	9	0.58	230	0.146	20	1.02	0.091	0.51	<0.1	<0.01	0.3	<0.05	2.0	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 07, 2011
Report Date: September 01, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11000491.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #1
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

RTRN-PLP Return
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	313	Dry at 60C			WHI
SS80	313	Dry at 60C sieve 100g to -80 mesh			WHI
1DX3	311	1:1:1 Aqua Regia digestion ICP-MS analysis	30	Completed	VAN
1DX1	2	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090001	Soil	16.0	33.8	37.2	102	2.9	17.2	3.1	57	2.93	98.5	16.3	2.0	172	0.4	16.0	0.4	94	0.11	0.375	7
1090002	Soil	14.9	27.6	25.8	69	2.0	11.8	1.7	26	2.17	72.5	9.6	0.5	410	0.3	22.3	0.3	175	0.14	0.428	9
1090003	Soil	65.4	23.5	139.5	54	4.2	9.2	1.3	31	2.06	131.1	67.4	0.9	234	0.3	43.7	0.4	240	0.05	0.177	8
1090004	Soil	257.6	222.7	24.4	43	8.5	21.9	0.4	15	2.17	197.9	1.3	2.1	268	3.4	98.3	0.3	2199	0.07	0.347	12
1090005	Soil	467.0	320.7	28.4	225	10.0	68.9	2.1	21	3.72	1035	72.7	4.3	440	2.3	471.8	0.4	1996	0.16	0.576	16
1090006	Soil	401.3	335.6	22.8	2070	2.7	401.9	30.2	180	10.99	2601	114.8	4.9	183	2.4	200.0	0.3	2560	0.04	0.654	17
1090007	Soil	250.6	321.8	22.3	2767	3.3	469.3	39.1	396	10.27	949.5	59.0	4.0	114	7.3	115.9	0.3	1460	0.08	0.416	13
1090008	Soil	110.4	269.6	20.0	1173	4.3	219.0	16.5	234	4.38	347.1	67.2	1.4	104	11.2	54.0	0.2	924	0.45	0.199	13
1090009	Soil	117.3	334.4	22.2	5267	3.9	566.3	28.4	663	4.08	243.6	12.4	0.9	218	45.1	47.8	0.2	1249	4.06	0.237	16
1090010	Soil	15.4	48.0	14.1	316	0.4	53.7	6.7	103	2.49	64.9	6.7	0.4	23	4.5	7.6	0.3	208	0.11	0.104	10
1090011	Soil	23.5	78.0	21.2	223	0.9	46.2	7.4	85	3.26	113.2	9.1	2.4	36	1.5	11.5	0.3	216	0.06	0.098	10
1090012	Soil	12.2	30.2	13.2	237	0.3	36.1	5.3	90	2.37	102.2	4.0	1.0	25	3.3	6.3	0.4	117	0.04	0.049	10
1090013	Soil	10.6	21.6	10.9	167	0.5	30.3	3.9	81	1.51	52.6	3.7	<0.1	18	2.2	4.3	0.2	99	0.02	0.070	8
1090014	Soil	159.8	116.3	15.5	3449	0.4	1102	190.3	5261	3.90	62.2	4.7	4.4	180	23.7	9.2	0.2	91	5.18	0.220	12
1090015	Soil	14.0	25.1	3.6	116	0.1	56.0	2.8	123	0.56	13.4	1.6	0.2	116	2.4	2.6	<0.1	40	2.83	0.059	4
1090016	Soil	83.4	128.4	11.9	1010	1.9	243.8	7.7	168	1.87	65.8	4.0	0.8	85	13.4	21.1	0.2	315	1.61	0.122	17
1090017	Soil	58.1	91.1	10.3	633	1.0	242.3	14.6	817	2.10	55.5	3.1	1.1	219	6.4	15.7	0.1	209	5.90	0.121	12
1090018	Soil	63.0	40.4	10.1	382	0.2	157.2	9.6	208	2.03	36.5	1.4	1.1	18	3.2	5.7	0.1	125	0.35	0.061	11
1090019	Soil	99.2	59.9	14.1	527	<0.1	185.4	9.3	69	2.81	58.0	2.2	1.1	6	1.3	5.3	0.2	95	0.07	0.055	16
1090020	Soil	72.5	15.7	6.2	269	<0.1	130.4	5.8	28	1.62	22.4	1.3	0.5	5	0.7	5.9	0.1	123	0.06	0.035	12
1090021	Soil	5.8	138.6	63.4	288	1.0	54.0	11.8	163	13.50	621.4	35.5	12.8	18	0.5	38.7	2.3	52	0.02	0.233	29
1090022	Soil	8.2	130.0	79.7	261	1.6	38.5	9.4	119	15.16	942.1	73.3	15.1	29	0.5	54.4	4.0	60	0.02	0.305	21
1090023	Soil	7.5	81.8	203.0	187	3.2	21.8	5.6	77	11.32	835.8	109.6	17.8	84	0.2	44.0	3.7	33	0.03	0.217	29
1090024	Soil	12.8	84.5	158.7	213	9.9	26.3	6.4	76	11.40	974.1	288.2	12.1	48	4.2	114.1	7.1	45	0.02	0.225	22
1090025	Soil	34.5	95.0	311.3	183	19.0	14.5	3.0	34	16.61	1426	495.4	13.9	68	2.7	592.5	28.0	49	0.01	0.227	14
1090026	Soil	8.9	80.0	143.7	192	14.4	19.2	5.0	72	8.21	658.8	323.5	10.7	47	0.7	135.1	9.9	27	0.02	0.142	21
1090027	Soil	25.9	115.7	104.9	269	4.9	31.1	6.3	79	9.03	3074	928.1	13.2	89	1.7	148.0	6.1	51	0.02	0.195	25
1090028	Soil	7.3	127.5	218.1	328	3.2	39.6	26.8	1044	6.01	2014	297.8	7.7	51	2.8	34.8	3.4	50	0.07	0.131	30
1090029	Soil	10.8	104.3	123.0	309	3.2	43.2	9.7	234	5.37	1020	219.5	7.5	76	1.2	58.0	6.6	72	0.06	0.168	25
1090030	Soil	58.0	109.6	83.7	922	6.2	132.7	21.1	185	8.88	2729	971.6	10.9	159	0.8	156.7	4.9	233	0.04	0.315	27

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090001	Soil	17	0.02	962	0.002	6	0.47	0.005	0.16	0.3	1.64	3.1	1.1	0.28	2	12.7	0.3	N.A.	N.A.	N.A.	N.A.
1090002	Soil	26	0.01	477	0.004	7	0.50	0.004	0.13	0.5	1.22	2.0	1.3	0.27	2	12.7	0.3	N.A.	N.A.	N.A.	N.A.
1090003	Soil	23	0.01	640	0.001	6	0.38	0.003	0.20	0.8	4.23	1.7	2.8	0.42	2	20.7	0.4	N.A.	N.A.	N.A.	N.A.
1090004	Soil	168	0.08	554	0.009	11	0.85	0.002	0.33	1.0	16.55	7.3	16.9	0.47	9	72.9	0.5	N.A.	N.A.	N.A.	N.A.
1090005	Soil	118	0.07	572	0.006	8	1.92	0.002	0.24	1.4	>50	10.6	17.3	0.48	9	56.3	4.7	N.A.	N.A.	N.A.	N.A.
1090006	Soil	99	0.06	507	0.004	5	1.49	0.001	0.17	1.9	>50	10.3	8.6	0.26	4	62.8	2.8	N.A.	N.A.	N.A.	N.A.
1090007	Soil	68	0.09	577	0.005	6	2.68	0.002	0.15	1.2	20.56	7.2	9.2	0.20	3	35.5	1.3	N.A.	N.A.	N.A.	N.A.
1090008	Soil	61	0.18	738	0.004	6	1.90	0.004	0.12	0.8	10.96	4.2	6.7	0.09	4	17.0	0.7	N.A.	N.A.	N.A.	N.A.
1090009	Soil	62	0.68	831	0.008	12	1.07	0.005	0.19	0.7	2.52	3.9	9.2	0.09	4	19.4	0.4	N.A.	N.A.	N.A.	N.A.
1090010	Soil	19	0.12	306	0.004	2	0.93	0.004	0.05	0.2	1.48	0.9	0.5	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090011	Soil	24	0.08	413	0.002	1	0.92	0.003	0.07	0.2	1.91	2.6	1.3	<0.05	3	4.9	0.2	N.A.	N.A.	N.A.	N.A.
1090012	Soil	13	0.08	363	0.007	1	0.77	0.008	0.06	0.2	0.58	1.3	0.5	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090013	Soil	11	0.05	312	0.005	1	0.59	0.009	0.05	0.3	0.47	0.3	0.4	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090014	Soil	22	1.01	554	0.003	8	1.50	0.004	0.09	0.6	1.27	5.1	16.3	<0.05	1	4.1	0.3	N.A.	N.A.	N.A.	N.A.
1090015	Soil	8	0.49	227	0.008	5	0.37	0.020	0.03	0.1	0.35	0.8	0.6	0.08	<1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090016	Soil	38	0.28	520	0.005	5	0.62	0.013	0.09	0.4	1.22	5.8	3.3	<0.05	1	5.7	0.2	N.A.	N.A.	N.A.	N.A.
1090017	Soil	23	2.55	282	0.002	7	0.39	0.005	0.07	0.3	0.84	4.2	2.6	0.05	<1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090018	Soil	21	0.15	379	0.002	4	0.64	0.004	0.07	0.4	0.45	2.7	1.4	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090019	Soil	15	0.06	248	0.002	3	0.46	0.004	0.06	0.4	0.20	1.4	0.8	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090020	Soil	9	0.03	75	0.001	3	0.32	0.003	0.04	0.2	0.08	0.5	0.5	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090021	Soil	32	0.29	147	0.007	3	1.25	0.005	0.13	0.6	>50	5.4	1.2	0.33	4	41.9	1.0	N.A.	N.A.	N.A.	N.A.
1090022	Soil	33	0.26	176	0.008	2	1.23	0.013	0.16	1.4	12.90	4.8	2.4	0.57	6	24.6	0.6	N.A.	N.A.	N.A.	N.A.
1090023	Soil	17	0.09	133	0.007	2	0.95	0.087	0.31	2.4	20.92	2.8	3.7	1.13	5	25.1	0.4	N.A.	N.A.	N.A.	N.A.
1090024	Soil	17	0.06	207	0.007	3	0.75	0.010	0.20	2.6	>50	2.1	4.1	0.34	4	>100	3.4	N.A.	N.A.	N.A.	N.A.
1090025	Soil	18	0.02	199	0.007	3	0.32	0.007	0.29	2.5	>50	2.2	6.9	0.68	3	>100	1.2	N.A.	N.A.	N.A.	N.A.
1090026	Soil	13	0.08	147	0.007	3	0.42	0.011	0.17	2.3	30.75	3.0	3.0	0.45	2	24.9	0.5	N.A.	N.A.	N.A.	N.A.
1090027	Soil	17	0.11	256	0.005	2	0.83	0.026	0.32	4.1	14.50	4.6	2.1	0.74	4	23.8	0.4	N.A.	N.A.	N.A.	N.A.
1090028	Soil	9	0.15	192	0.005	3	1.65	0.013	0.15	1.3	4.14	1.9	1.7	0.22	4	12.2	0.5	N.A.	N.A.	N.A.	N.A.
1090029	Soil	10	0.10	237	0.005	2	1.37	0.015	0.16	1.1	6.53	1.8	1.7	0.28	3	9.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090030	Soil	29	0.12	330	0.007	3	1.62	0.008	0.17	11.8	>50	7.4	7.3	0.36	4	59.1	0.6	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090017	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090019	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090021	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090022	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090023	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090025	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090026	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090027	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090028	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090029	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090030	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090017	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090019	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090021	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090022	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090023	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090025	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090026	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090027	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090028	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090029	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090030	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090031	Soil	45.2	160.9	137.3	501	9.2	70.8	11.3	261	4.54	1687	200.8	11.6	216	3.4	86.8	3.1	181	0.16	0.280	32
1090032	Soil	57.0	69.2	104.7	215	6.4	31.7	3.7	57	3.30	850.6	580.5	4.1	332	0.7	71.0	2.8	254	0.27	0.444	31
1090033	Soil	31.5	39.8	82.9	92	9.2	13.0	1.6	21	1.96	625.4	604.4	0.8	124	0.4	52.5	1.4	137	0.08	0.355	24
1090034	Soil	29.8	45.8	88.4	84	5.6	13.3	2.4	41	2.06	739.1	300.0	1.2	59	0.4	55.4	1.1	105	0.05	0.331	18
1090035	Soil	12.1	30.4	51.1	48	3.9	8.8	1.7	43	1.29	421.0	461.4	0.3	33	0.3	33.1	0.7	56	0.04	0.168	12
1090036	Soil	18.7	30.8	71.6	44	4.9	8.9	1.5	38	1.37	399.0	584.5	0.3	50	0.3	39.5	1.0	72	0.03	0.214	15
1090037	Soil	15.2	48.1	52.2	74	4.3	14.9	3.1	93	1.89	450.1	434.3	0.9	63	0.5	36.4	0.8	81	0.07	0.244	14
1090038	Soil	8.0	58.4	28.9	183	1.9	54.5	6.2	66	2.97	76.3	60.8	1.2	98	0.7	6.6	0.4	44	0.03	0.110	8
1090039	Soil	2.1	22.8	10.7	67	0.5	21.8	4.0	38	1.31	16.2	11.1	0.2	8	0.3	1.5	0.2	32	0.01	0.038	3
1090040	Soil	2.5	16.6	11.1	84	0.3	23.3	4.0	55	1.30	29.4	12.1	0.2	19	0.5	4.9	0.2	34	0.03	0.052	4
1090041	Soil	3.0	21.4	15.6	97	0.8	28.6	5.0	76	2.10	44.3	7.6	0.3	21	0.4	3.2	0.3	46	0.12	0.052	6
1090042	Soil	5.6	25.0	17.3	83	0.6	20.7	3.6	40	1.65	43.7	4.2	0.6	17	0.1	3.4	0.3	73	0.02	0.041	10
1090043	Soil	5.5	34.5	19.6	124	0.5	35.1	5.7	55	2.26	46.7	7.7	0.9	24	0.2	3.7	0.3	58	<0.01	0.060	8
1090044	Soil	5.7	40.0	20.7	151	0.7	38.3	8.4	250	3.14	74.9	9.0	1.5	31	0.4	4.7	0.5	58	0.03	0.089	8
1090045	Soil	3.4	19.0	8.0	47	0.3	10.0	2.1	34	0.91	21.9	0.9	<0.1	10	0.1	1.8	0.3	37	0.02	0.044	8
1090046	Soil	2.0	22.8	11.4	45	2.4	15.3	2.1	29	1.05	16.3	8.4	0.2	27	0.3	1.3	0.2	26	0.09	0.074	3
1090047	Soil	5.2	41.4	22.9	128	1.0	38.8	7.1	124	2.58	45.3	8.6	1.2	35	0.5	3.3	0.4	53	0.09	0.070	8
1090048	Soil	0.1	4.1	1.1	19	<0.1	2.2	1.1	28	0.34	1.6	0.7	<0.1	22	0.1	<0.1	<0.1	12	0.46	0.034	2
1090049	Soil	2.2	27.5	9.9	64	0.3	14.7	3.6	38	1.19	13.5	18.2	0.6	7	0.2	1.4	0.2	48	0.04	0.040	3
1090050	Soil	1.0	22.6	11.9	70	1.1	18.5	2.8	110	1.36	8.3	3.9	0.5	96	0.6	0.7	0.2	25	2.06	0.119	8
1090051	Soil	1.6	15.0	5.2	118	0.5	14.5	2.6	224	0.82	6.9	2.0	0.3	111	1.4	1.2	0.2	31	3.60	0.208	13
1090052	Soil	0.1	3.9	0.9	6	<0.1	1.1	0.8	36	0.21	0.9	<0.5	0.1	16	0.1	<0.1	<0.1	7	0.33	0.044	2
1090053	Soil	2.1	34.2	14.6	123	1.5	38.5	4.2	117	1.48	14.2	2.7	0.9	89	1.0	1.5	0.2	36	1.86	0.136	10
1090054	Soil	9.1	26.2	22.4	58	1.0	19.9	5.5	416	1.26	42.9	17.2	0.6	67	0.4	5.3	0.3	65	1.41	0.076	7
1090055	Soil	4.3	38.8	14.8	119	1.0	34.7	6.6	497	1.13	32.3	14.6	0.7	66	1.8	4.8	0.2	59	1.23	0.066	6
1090056	Soil	9.8	32.7	45.0	90	4.4	14.1	2.9	52	2.51	136.8	11.1	1.9	30	0.3	30.8	0.6	65	0.01	0.069	18
1090057	Soil	11.3	19.0	21.1	45	1.3	10.1	2.1	38	1.43	73.7	10.5	1.6	15	0.2	20.2	0.4	53	<0.01	0.030	12
1090058	Soil	17.8	19.8	12.8	40	0.6	11.6	1.4	16	1.21	50.9	2.5	0.6	12	0.1	14.2	0.3	70	<0.01	0.025	3
1090059	Soil	16.6	19.7	19.7	91	2.2	10.8	2.0	21	1.00	24.9	1.2	0.4	24	0.3	11.8	0.2	87	0.01	0.054	4
1090060	Soil	45.2	58.2	24.2	15	6.1	3.8	0.4	10	1.69	37.0	2.8	0.7	65	0.4	16.7	0.2	89	0.06	0.478	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090031	Soil	21	0.06	724	0.003	3	1.06	0.009	0.16	2.7	39.09	4.7	5.4	0.30	3	32.5	0.5	N.A.	N.A.	N.A.	N.A.
1090032	Soil	33	0.05	476	0.004	2	0.89	0.011	0.18	2.9	46.15	4.8	4.5	0.33	5	40.6	0.6	N.A.	N.A.	N.A.	N.A.
1090033	Soil	28	0.02	329	0.002	3	0.52	0.004	0.12	2.5	>50	1.3	4.0	0.18	4	25.5	0.7	N.A.	N.A.	N.A.	N.A.
1090034	Soil	24	0.02	275	0.002	3	0.40	0.004	0.11	1.3	>50	2.5	3.6	0.16	3	27.6	0.5	N.A.	N.A.	N.A.	N.A.
1090035	Soil	14	0.02	181	0.003	2	0.42	0.011	0.08	0.8	26.02	0.8	2.1	0.09	2	15.6	0.5	N.A.	N.A.	N.A.	N.A.
1090036	Soil	18	0.02	182	0.002	4	0.43	0.008	0.07	1.0	>50	0.3	3.0	0.20	2	22.1	0.5	N.A.	N.A.	N.A.	N.A.
1090037	Soil	20	0.03	245	0.002	4	0.48	0.006	0.08	1.2	43.72	0.9	2.7	0.18	2	18.6	0.5	N.A.	N.A.	N.A.	N.A.
1090038	Soil	20	0.04	618	0.001	5	0.63	0.005	0.07	0.2	4.23	2.1	0.5	0.17	2	5.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090039	Soil	10	0.02	88	0.003	3	0.39	0.010	0.02	0.1	0.66	0.5	0.1	0.08	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090040	Soil	9	0.03	118	0.003	2	0.45	0.006	0.03	<0.1	1.84	0.4	0.1	0.09	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090041	Soil	12	0.04	205	0.004	2	0.57	0.008	0.04	0.1	1.35	0.6	0.2	0.08	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090042	Soil	14	0.02	170	0.003	3	0.37	0.004	0.05	0.2	0.39	0.8	0.1	0.09	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090043	Soil	12	0.02	130	0.006	2	0.37	0.005	0.06	0.2	0.55	1.3	0.1	<0.05	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090044	Soil	19	0.08	207	0.002	2	0.77	0.004	0.07	0.2	1.13	1.9	0.3	0.09	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090045	Soil	6	0.02	90	0.003	2	0.43	0.012	0.03	0.1	0.36	0.1	0.1	0.10	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090046	Soil	8	0.03	555	0.002	2	0.64	0.016	0.04	<0.1	0.64	0.8	0.2	0.11	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090047	Soil	20	0.10	597	0.002	3	0.73	0.005	0.07	0.1	0.97	2.7	0.2	0.10	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090048	Soil	2	0.04	75	0.016	1	0.32	0.034	0.02	<0.1	0.05	0.2	<0.1	0.07	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090049	Soil	11	0.03	117	0.005	3	0.46	0.007	0.05	0.1	0.30	1.4	0.1	0.11	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090050	Soil	18	0.25	446	0.002	5	0.48	0.013	0.06	<0.1	0.25	1.9	0.1	0.18	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090051	Soil	20	0.88	309	0.010	6	0.57	0.014	0.03	<0.1	0.16	0.7	0.2	<0.05	<1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090052	Soil	1	0.03	51	0.016	1	0.41	0.040	0.02	<0.1	0.03	0.3	<0.1	0.09	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090053	Soil	21	0.13	616	0.002	8	0.67	0.008	0.06	<0.1	0.44	2.2	0.2	0.27	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090054	Soil	14	0.07	585	0.002	2	0.66	0.010	0.04	0.2	1.86	1.2	0.3	0.13	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090055	Soil	15	0.08	581	0.002	3	0.63	0.010	0.05	0.2	1.77	1.6	0.3	0.13	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090056	Soil	14	0.04	127	0.002	2	0.70	0.003	0.07	0.2	15.33	2.6	0.8	0.17	3	12.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090057	Soil	10	0.04	110	0.002	2	0.46	0.002	0.06	<0.1	10.35	1.5	0.5	0.09	2	6.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090058	Soil	9	0.01	66	<0.001	1	0.35	0.002	0.05	<0.1	0.67	0.9	0.7	0.05	2	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090059	Soil	12	<0.01	162	0.001	2	0.30	0.003	0.07	0.1	0.72	0.7	0.5	0.13	2	8.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090060	Soil	23	<0.01	274	0.003	3	0.36	0.003	0.11	0.7	0.35	1.5	1.0	0.21	1	13.1	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090031	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090032	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090033	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090034	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090035	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090036	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090037	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090038	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090039	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090040	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090041	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090042	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090043	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090044	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090045	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090046	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090047	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090048	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090049	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090050	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090051	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090052	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090053	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090054	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090055	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090056	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090057	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090058	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090059	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090060	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090031	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090032	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090033	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090034	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090035	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090036	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090037	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090038	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090039	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090040	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090041	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090042	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090043	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090044	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090045	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090046	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090047	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090048	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090049	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090050	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090051	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090052	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090053	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090054	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090055	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090056	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090058	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090061	Soil	9.5	29.5	13.2	5	1.7	4.1	0.2	5	0.74	13.8	2.0	1.5	25	<0.1	2.1	0.2	18	0.09	0.181	3
1090062	Soil	22.9	195.0	30.3	975	4.3	187.4	35.1	826	7.26	60.9	22.7	3.3	223	8.8	5.1	0.6	117	0.14	0.255	8
1090063	Soil	5.4	47.4	28.9	111	1.7	18.6	3.7	92	3.75	63.0	20.4	1.6	161	0.4	4.5	0.5	81	0.05	0.132	7
1090064	Soil	6.8	53.7	26.1	97	1.4	15.2	2.8	50	2.91	100.2	10.9	0.8	101	0.2	4.0	0.4	87	0.02	0.095	7
1090065	Soil	4.0	89.8	29.9	197	1.7	29.9	3.8	53	4.14	80.6	6.7	0.7	223	0.5	2.0	0.3	56	0.04	0.169	5
1090066	Soil	2.6	34.9	16.2	87	0.7	12.6	2.9	58	1.72	25.8	2.8	0.3	25	0.2	1.1	0.2	36	0.02	0.078	4
1090067	Soil	2.2	32.0	36.2	57	0.5	11.1	2.6	47	1.91	35.2	1.5	1.5	30	0.1	0.9	0.3	24	0.01	0.059	3
1090068	Soil	3.3	47.3	30.0	66	1.8	13.2	2.8	60	2.62	38.9	2.5	0.4	39	<0.1	1.8	0.3	53	0.02	0.106	5
1090069	Soil	3.4	43.1	18.9	43	2.5	8.7	2.1	53	2.32	37.0	5.5	0.7	64	<0.1	2.6	0.2	45	0.06	0.085	4
1090070	Soil	10.0	54.9	24.2	91	4.1	23.9	3.0	35	2.76	47.3	10.2	0.6	23	<0.1	3.7	0.3	45	<0.01	0.061	2
1090071	Soil	7.9	126.2	20.5	228	3.0	131.4	10.6	91	5.69	125.1	16.3	1.3	53	0.3	9.4	0.4	41	<0.01	0.112	3
1090072	Soil	4.6	98.2	22.9	168	2.6	55.4	7.2	68	4.35	33.7	11.4	1.5	49	0.3	2.7	0.3	30	0.02	0.104	3
1090073	Soil	3.9	49.0	15.0	177	2.4	58.2	18.6	463	2.85	15.4	3.4	0.3	33	1.1	1.8	0.2	29	0.25	0.121	5
1090074	Soil	4.2	71.1	18.0	195	2.3	71.9	10.3	146	3.54	37.8	4.8	0.5	52	0.6	3.0	0.3	33	0.06	0.123	4
1090075	Soil	4.2	60.6	24.5	170	2.1	50.9	10.3	261	3.52	89.5	10.1	1.1	96	0.4	3.7	0.3	33	0.15	0.104	4
1090076	Soil	4.2	74.3	22.1	156	1.3	50.2	9.4	168	3.54	37.3	4.4	1.0	59	0.5	2.5	0.3	30	0.06	0.100	4
1090077	Soil	2.7	53.0	23.5	151	1.4	44.9	12.2	215	4.08	25.5	3.7	1.6	43	0.4	1.6	0.3	23	0.04	0.074	2
1090078	Soil	2.5	36.5	15.7	82	0.9	23.0	6.9	207	2.28	17.0	4.0	0.5	33	0.2	1.4	0.2	20	0.05	0.074	2
1090079	Soil	2.6	34.2	16.3	100	1.4	29.2	7.2	156	2.52	14.0	2.7	0.5	30	0.2	1.0	0.2	20	0.02	0.078	2
1090080	Soil	0.6	14.5	3.9	84	0.4	13.5	2.6	212	0.96	4.5	1.1	0.1	58	0.6	0.7	<0.1	19	1.40	0.141	11
1090081	Soil	0.2	8.4	2.3	41	0.2	10.5	1.9	64	0.47	2.2	1.0	<0.1	22	0.2	0.3	<0.1	11	0.43	0.061	3
1090082	Soil	2.4	38.0	15.8	162	1.8	48.5	5.3	165	1.97	16.0	9.4	1.1	80	0.8	1.9	0.2	34	1.12	0.139	9
1090083	Soil	3.0	30.7	18.1	150	0.9	46.5	6.8	156	2.20	28.2	5.7	0.7	64	1.0	2.3	0.2	41	1.02	0.119	8
1090084	Soil	1.5	39.4	14.2	201	1.7	60.0	8.4	232	2.17	16.2	5.0	1.0	106	1.2	2.6	0.2	37	2.27	0.220	12
1090085	Soil	2.3	36.9	17.4	133	1.0	38.0	6.3	220	2.16	30.6	11.8	0.7	66	1.4	2.5	0.2	32	1.23	0.126	10
1090086	Soil	1.7	38.1	14.1	200	1.5	58.0	8.5	266	2.19	16.0	6.6	1.3	107	1.3	2.5	0.2	37	1.83	0.255	13
1090087	Soil	1.7	42.0	17.0	232	2.4	63.6	9.2	298	2.36	19.5	13.0	1.3	93	1.6	2.3	0.2	38	1.50	0.198	12
1090088	Soil	9.7	103.5	25.4	283	3.6	90.3	7.3	74	9.22	94.8	7.3	1.4	23	0.4	3.2	0.3	65	0.16	0.142	2
1090089	Soil	2.4	22.6	11.6	50	1.0	11.9	2.6	54	1.81	13.8	2.8	0.2	10	<0.1	1.2	0.2	31	0.02	0.050	3
1090090	Soil	3.8	24.6	11.7	60	0.6	14.1	2.8	50	1.78	18.0	2.7	<0.1	17	0.1	2.0	0.2	51	0.02	0.059	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090061	Soil	10	<0.01	617	0.002	4	0.11	0.002	0.08	0.2	0.35	2.3	0.6	0.16	<1	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090062	Soil	44	0.03	289	0.004	4	1.32	0.005	0.13	0.2	0.60	7.3	0.5	0.28	2	5.0	0.3	N.A.	N.A.	N.A.	N.A.
1090063	Soil	23	0.08	514	0.010	2	0.59	0.005	0.13	0.2	0.33	2.3	0.2	0.30	3	5.0	0.3	N.A.	N.A.	N.A.	N.A.
1090064	Soil	20	0.03	421	0.006	2	0.44	0.003	0.09	0.1	0.22	1.9	0.1	0.15	3	3.2	0.2	N.A.	N.A.	N.A.	N.A.
1090065	Soil	23	0.05	389	0.003	2	0.99	0.006	0.09	<0.1	0.28	3.4	0.1	0.14	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090066	Soil	12	0.03	134	0.002	2	0.59	0.006	0.05	<0.1	0.13	0.6	0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090067	Soil	13	0.03	278	<0.001	1	0.60	0.006	0.10	<0.1	0.17	1.4	0.1	0.10	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090068	Soil	21	0.03	402	0.003	2	0.62	0.008	0.09	<0.1	0.33	1.0	0.1	0.15	3	4.4	0.3	N.A.	N.A.	N.A.	N.A.
1090069	Soil	23	0.04	679	0.004	5	0.48	0.013	0.12	<0.1	0.45	2.8	0.1	0.20	2	6.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090070	Soil	36	0.02	730	<0.001	5	0.63	0.004	0.10	<0.1	0.49	1.8	0.1	0.10	2	10.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090071	Soil	31	0.02	318	<0.001	1	0.85	0.002	0.05	<0.1	1.38	3.4	<0.1	0.06	2	8.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090072	Soil	28	0.01	298	<0.001	3	0.63	0.004	0.09	<0.1	0.52	3.9	0.2	0.13	2	6.8	0.2	N.A.	N.A.	N.A.	N.A.
1090073	Soil	20	0.02	454	0.002	1	0.47	0.004	0.04	<0.1	0.32	2.7	0.1	0.08	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090074	Soil	22	0.03	375	0.002	1	0.63	0.004	0.05	<0.1	0.40	1.9	0.1	0.09	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090075	Soil	21	0.06	545	<0.001	<1	0.71	0.005	0.07	<0.1	1.06	2.4	0.2	0.10	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090076	Soil	27	0.06	345	<0.001	2	0.78	0.005	0.06	<0.1	0.22	2.8	0.1	0.07	2	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090077	Soil	21	0.07	281	<0.001	1	0.70	0.006	0.06	<0.1	0.16	3.7	<0.1	0.05	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090078	Soil	17	0.05	186	0.003	2	0.65	0.013	0.05	<0.1	0.12	1.7	<0.1	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090079	Soil	22	0.05	161	0.001	1	0.62	0.010	0.06	<0.1	0.15	1.9	<0.1	0.09	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090080	Soil	17	0.06	145	0.010	1	0.46	0.029	0.03	<0.1	0.12	0.8	<0.1	0.09	<1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090081	Soil	4	0.03	90	0.016	<1	0.45	0.030	0.03	<0.1	0.06	0.4	<0.1	0.07	<1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090082	Soil	24	0.06	533	0.001	4	0.73	0.009	0.08	<0.1	0.55	2.9	0.1	0.16	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090083	Soil	25	0.09	581	0.002	1	0.93	0.011	0.05	<0.1	0.81	2.0	0.1	0.13	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090084	Soil	25	0.15	685	0.002	4	0.84	0.011	0.06	<0.1	0.57	2.6	0.1	0.13	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090085	Soil	19	0.08	544	0.002	2	0.79	0.014	0.07	<0.1	0.87	2.3	0.1	0.14	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090086	Soil	24	0.21	616	0.002	5	0.73	0.010	0.08	0.1	0.55	2.9	0.2	0.12	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090087	Soil	28	0.10	654	0.001	5	0.90	0.011	0.09	0.1	0.80	3.5	0.2	0.15	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090088	Soil	108	0.11	471	<0.001	1	0.75	0.004	0.06	<0.1	0.71	4.4	0.2	0.11	3	17.8	0.2	N.A.	N.A.	N.A.	N.A.
1090089	Soil	13	0.07	96	0.004	<1	0.52	0.007	0.03	<0.1	0.62	0.7	0.1	0.06	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090090	Soil	14	0.03	114	0.007	<1	0.42	0.006	0.04	0.1	0.07	0.6	0.1	0.06	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090062	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090063	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090071	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090075	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090081	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090085	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090087	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090062	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090063	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090071	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090075	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090081	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090085	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090087	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090091	Soil	3.9	60.1	16.8	105	0.3	27.2	8.9	207	2.19	18.6	7.6	0.6	22	0.2	2.3	0.4	42	0.13	0.053	5
1090092	Soil	1.4	29.6	13.7	180	1.6	43.6	6.8	246	1.88	20.2	12.3	0.9	75	0.9	1.6	0.2	35	1.15	0.156	7
1090093	Soil	19.4	29.7	20.5	174	0.9	42.9	3.9	61	1.67	56.4	18.7	0.9	75	1.2	14.0	0.2	108	0.54	0.103	6
1090094	Soil	32.5	42.9	25.0	166	1.7	48.0	3.0	46	1.73	95.5	19.5	1.4	62	0.5	24.4	0.2	231	0.06	0.170	11
1090095	Soil	31.4	52.2	47.2	223	1.5	58.9	4.7	110	2.02	85.9	21.5	1.9	93	0.7	26.7	0.2	182	0.13	0.227	12
1090096	Soil	42.0	80.4	45.2	316	2.2	84.6	9.2	248	2.27	125.2	22.3	1.8	100	4.0	33.5	0.3	210	0.19	0.233	12
1090097	Soil	16.0	21.9	31.1	128	1.2	28.1	3.5	67	1.89	60.6	11.3	1.3	45	0.2	11.5	0.4	135	0.02	0.137	12
1090098	Soil	20.8	44.4	63.9	187	1.4	38.4	5.9	190	1.52	77.2	31.4	1.2	80	0.7	22.3	0.2	121	0.08	0.178	10
1090099	Soil	20.0	26.5	44.8	145	1.0	34.9	3.2	61	1.61	67.1	21.0	0.8	63	0.3	16.4	0.3	137	0.03	0.105	12
1090100	Soil	22.7	40.0	48.9	141	1.7	35.1	2.4	49	1.20	65.7	34.1	0.5	71	1.3	24.5	0.2	126	0.03	0.074	10
1090101	Soil	23.9	30.3	44.9	155	1.2	35.2	2.1	33	1.15	63.7	24.0	0.1	79	1.2	23.0	0.2	130	0.05	0.064	9
1090102	Soil	17.1	45.8	26.1	136	1.5	28.0	3.4	78	1.30	57.9	24.7	0.6	71	2.1	20.5	0.3	108	0.14	0.107	10
1090103	Soil	3.7	16.4	77.4	94	3.5	14.0	4.3	58	2.89	321.3	10.8	3.5	45	0.2	39.1	0.7	20	<0.01	0.046	30
1090104	Soil	2.2	20.0	23.9	66	0.6	13.8	3.4	71	1.79	128.6	97.1	1.3	16	<0.1	9.9	0.2	22	0.05	0.065	14
1090105	Soil	4.1	18.5	29.3	85	0.3	15.3	3.9	30	2.24	205.0	10.7	2.9	24	0.1	13.9	0.3	12	<0.01	0.049	26
1090106	Soil	1.4	43.2	12.4	235	<0.1	60.2	15.2	689	4.69	154.7	2.3	2.1	12	1.5	6.7	0.3	15	0.03	0.060	3
1090107	Soil	3.0	32.3	13.5	186	<0.1	36.6	16.5	203	3.45	57.0	2.4	0.8	7	0.3	1.6	0.3	29	0.01	0.046	3
1090108	Soil	2.5	28.8	15.3	140	<0.1	32.8	12.1	204	2.85	42.1	1.0	0.7	7	0.2	1.4	0.2	18	<0.01	0.038	2
1090109	Soil	3.8	35.4	37.8	114	0.1	33.7	9.5	95	1.94	53.3	2.0	1.4	20	0.4	1.6	0.2	12	0.01	0.040	3
1090110	Soil	3.5	34.2	22.2	160	0.2	36.0	11.3	128	2.66	74.0	4.9	1.1	21	1.0	2.3	0.3	19	0.03	0.047	3
1090111	Soil	4.4	39.3	23.1	203	0.2	37.5	11.4	96	3.43	97.7	4.2	1.9	34	0.8	2.2	0.3	23	0.02	0.054	3
1090112	Soil	19.6	20.0	54.9	23	1.6	5.5	0.9	12	1.45	51.1	12.2	1.7	116	0.2	9.0	0.3	59	0.02	0.062	3
1090113	Soil	4.1	8.5	19.3	19	0.5	3.9	0.8	25	0.78	37.3	11.7	1.3	23	<0.1	5.0	0.4	25	<0.01	0.034	4
1090114	Soil	3.8	8.4	17.5	9	0.6	2.7	0.5	26	0.63	54.5	14.6	0.7	21	<0.1	4.8	0.3	21	0.01	0.032	2
1090115	Soil	4.6	43.7	15.8	63	0.6	13.0	3.5	52	1.94	174.8	9.1	1.7	24	0.1	5.4	0.3	43	<0.01	0.047	4
1090116	Soil	25.4	12.3	74.9	9	1.0	2.0	0.3	14	1.03	54.9	6.8	4.9	23	<0.1	6.8	0.4	23	0.01	0.029	4
1090117	Soil	9.0	11.1	35.9	24	0.7	3.5	0.6	17	0.96	44.1	6.3	2.0	15	<0.1	4.9	0.3	24	0.01	0.028	3
1090118	Soil	9.0	4.8	40.2	9	0.6	1.4	0.1	4	1.11	32.0	6.7	1.7	8	<0.1	6.1	0.3	21	<0.01	0.022	3
1090119	Soil	102.5	32.8	43.6	16	4.2	4.1	0.3	15	2.19	189.0	46.2	1.2	33	0.2	57.9	0.4	348	0.01	0.060	7
1090120	Soil	121.5	170.9	36.3	492	5.8	86.5	2.2	42	2.08	199.8	50.9	1.0	91	6.1	79.2	0.3	804	0.17	0.136	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090091	Soil	22	0.11	156	0.005	1	0.54	0.003	0.04	0.1	0.99	2.0	<0.1	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090092	Soil	20	0.09	548	<0.001	2	0.83	0.012	0.05	<0.1	0.57	2.3	0.1	0.12	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090093	Soil	19	0.02	378	<0.001	2	0.43	0.006	0.07	0.4	3.59	1.5	0.9	0.14	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090094	Soil	21	0.02	244	0.002	2	0.45	0.003	0.06	0.6	5.43	1.3	1.6	0.07	2	7.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090095	Soil	18	0.02	360	0.002	1	0.51	0.003	0.09	0.6	5.46	1.9	1.8	0.10	2	9.5	0.2	N.A.	N.A.	N.A.	N.A.
1090096	Soil	30	0.05	720	0.002	3	0.61	0.004	0.11	0.7	5.63	2.6	2.0	0.09	2	12.3	0.3	N.A.	N.A.	N.A.	N.A.
1090097	Soil	14	0.03	248	0.012	1	0.53	0.003	0.06	0.4	0.78	1.2	1.1	<0.05	5	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090098	Soil	14	0.01	297	0.002	2	0.44	0.002	0.06	0.6	6.07	1.2	1.6	0.06	1	8.8	0.2	N.A.	N.A.	N.A.	N.A.
1090099	Soil	14	0.02	224	0.003	<1	0.38	0.003	0.07	0.5	2.36	0.8	1.4	0.06	3	7.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090100	Soil	12	<0.01	333	<0.001	2	0.23	0.003	0.06	0.6	4.07	1.0	1.8	0.06	1	8.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090101	Soil	13	0.01	437	0.001	2	0.23	0.003	0.07	0.5	2.49	0.6	1.7	0.07	1	9.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090102	Soil	13	0.04	1258	0.002	1	0.39	0.001	0.06	0.5	3.01	1.3	1.4	0.10	1	6.1	0.2	N.A.	N.A.	N.A.	N.A.
1090103	Soil	6	0.01	240	<0.001	2	0.32	0.003	0.11	<0.1	>50	1.5	1.0	0.22	1	20.3	0.3	N.A.	N.A.	N.A.	N.A.
1090104	Soil	10	0.11	91	0.003	<1	0.68	0.011	0.06	<0.1	6.80	1.3	0.3	<0.05	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090105	Soil	6	0.01	144	<0.001	<1	0.35	0.003	0.09	<0.1	4.19	2.3	0.3	0.10	1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090106	Soil	7	0.07	85	<0.001	3	0.54	0.001	0.05	<0.1	0.35	6.7	0.2	0.09	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090107	Soil	8	0.05	44	0.001	2	0.54	0.001	0.03	<0.1	0.12	3.0	0.1	0.06	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090108	Soil	6	0.03	71	<0.001	1	0.35	0.002	0.04	<0.1	0.81	3.3	<0.1	0.06	<1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090109	Soil	4	0.01	105	<0.001	<1	0.25	0.001	0.05	<0.1	0.37	4.4	0.3	0.08	<1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090110	Soil	8	0.02	452	<0.001	1	0.27	0.002	0.05	<0.1	0.47	3.9	0.3	0.08	<1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090111	Soil	10	0.01	406	<0.001	2	0.27	0.002	0.07	<0.1	3.02	4.8	0.5	0.11	<1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090112	Soil	12	<0.01	646	0.001	4	0.20	0.003	0.14	0.1	1.36	1.6	1.3	0.35	2	8.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090113	Soil	7	0.02	442	0.002	3	0.30	0.002	0.09	<0.1	0.48	1.1	0.3	0.15	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090114	Soil	8	<0.01	456	0.001	3	0.25	0.003	0.09	<0.1	1.09	1.7	0.3	0.17	2	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090115	Soil	13	0.01	439	0.001	13	0.32	0.001	0.08	<0.1	0.41	2.7	0.3	0.12	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090116	Soil	6	<0.01	440	0.001	4	0.19	<0.001	0.13	<0.1	3.49	1.4	0.6	0.24	1	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090117	Soil	7	<0.01	388	<0.001	3	0.23	0.001	0.10	<0.1	0.45	1.0	0.4	0.17	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090118	Soil	5	<0.01	318	0.001	3	0.15	0.002	0.16	<0.1	0.65	0.6	0.4	0.33	1	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090119	Soil	28	0.01	368	0.002	5	0.31	0.002	0.26	0.8	>50	1.3	5.2	0.61	4	28.1	0.9	N.A.	N.A.	N.A.	N.A.
1090120	Soil	43	0.05	606	0.004	5	0.77	0.002	0.18	0.9	46.54	1.6	6.4	0.39	4	23.2	0.7	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090121	Soil	88.1	260.8	26.2	3329	7.5	319.1	6.2	118	1.79	210.8	70.3	1.0	173	63.5	83.7	0.2	1227	2.07	0.171	10
1090122	Soil	25.2	43.1	28.0	275	0.9	65.1	5.5	63	2.04	77.6	12.7	1.3	61	1.4	16.2	0.2	130	0.24	0.091	11
1090123	Soil	3.3	62.5	16.2	159	1.5	57.3	8.1	201	2.00	32.0	13.7	0.9	67	1.1	4.8	0.2	55	1.29	0.089	4
1090124	Soil	3.3	40.1	7.5	113	0.2	30.6	6.0	68	2.01	10.8	6.8	1.1	18	0.3	2.2	0.2	35	0.16	0.039	3
1090125	Soil	2.9	67.2	14.5	111	0.1	40.5	7.7	99	2.99	14.0	16.5	1.6	17	0.2	2.0	0.3	33	0.06	0.041	4
1090126	Soil	4.3	67.2	14.7	132	0.2	37.3	8.1	185	3.24	19.0	8.5	1.4	20	0.2	3.1	0.3	40	0.07	0.060	3
1090127	Soil	4.3	68.9	17.9	118	0.3	32.9	13.2	268	2.73	19.0	4.9	1.5	19	0.3	2.3	0.3	42	0.08	0.057	5
1090128	Soil	5.9	92.8	19.4	215	0.3	54.7	14.5	224	3.34	28.5	18.1	2.1	29	0.4	4.2	0.4	45	0.12	0.070	5
1090129	Soil	2.4	58.4	9.4	102	0.6	29.0	5.8	96	2.32	10.1	7.3	0.9	13	0.2	1.2	0.2	31	0.07	0.040	3
1090130	Soil	3.0	84.7	14.8	139	0.4	40.1	10.5	188	3.08	13.4	14.0	1.4	24	0.3	1.8	0.3	38	0.18	0.049	4
1090131	Soil	5.1	98.3	15.9	197	1.1	46.0	9.1	212	2.81	20.6	13.2	1.3	54	0.5	2.5	0.3	55	0.38	0.090	4
1090132	Soil	52.6	19.0	5.3	254	0.2	97.6	4.8	45	1.21	25.2	1.6	0.2	23	2.3	4.2	<0.1	68	0.40	0.060	6
1090133	Soil	27.8	24.6	7.1	167	0.1	82.8	6.7	237	1.40	14.7	1.0	0.7	39	1.3	2.5	<0.1	37	0.61	0.080	6
1090134	Soil	38.3	46.1	10.0	382	0.4	87.9	8.8	396	1.81	33.8	3.0	0.6	42	5.0	5.8	0.2	188	0.48	0.133	10
1090136	Soil	60.1	77.1	15.8	1185	1.0	181.0	12.3	370	2.55	73.1	5.9	1.7	57	12.0	13.3	0.2	289	0.72	0.163	14
1090137	Soil	36.8	58.9	14.3	553	0.8	100.6	7.3	213	2.05	71.0	8.2	1.5	59	7.8	11.5	0.2	257	0.83	0.166	13
1090138	Soil	10.2	28.7	18.0	170	0.4	36.3	7.0	236	3.28	38.6	3.3	0.6	24	0.5	3.4	0.2	86	0.16	0.281	12
1090139	Soil	15.2	31.0	22.4	179	0.5	51.0	6.8	95	2.82	40.4	3.5	0.4	24	0.3	3.3	0.3	97	0.05	0.159	13
1090140	Soil	18.2	42.0	18.5	234	0.6	61.6	7.2	82	2.25	40.7	2.2	0.3	27	0.6	4.2	0.2	70	0.05	0.141	12
1090141	Soil	13.1	37.4	10.8	234	0.3	57.0	8.3	179	2.08	35.9	3.3	1.3	50	1.7	4.2	0.2	106	0.78	0.158	11
1090142	Soil	10.0	27.8	3.7	50	0.1	39.5	2.6	163	0.65	8.1	5.2	0.2	54	1.1	1.0	0.7	24	1.29	0.080	5
1090143	Soil	4.9	98.3	66.3	197	0.5	33.0	8.2	153	10.25	421.8	22.7	11.2	14	0.3	32.0	2.3	43	0.01	0.175	24
1090144	Soil	4.0	71.8	48.2	178	0.8	31.1	8.0	139	7.51	320.1	12.4	9.5	16	0.3	22.1	1.4	34	0.01	0.118	30
1090145	Soil	3.9	67.2	54.3	241	0.7	55.9	38.6	1430	8.23	244.8	12.0	8.6	8	0.4	12.4	1.1	32	<0.01	0.130	23
1090146	Soil	2.7	60.7	41.7	128	0.9	21.7	5.8	189	6.36	255.0	17.2	7.5	11	0.2	18.2	1.1	33	0.02	0.121	28
1090147	Soil	3.9	48.0	36.8	112	2.0	21.8	5.6	123	5.18	339.5	26.3	3.4	10	0.3	30.9	1.4	30	0.04	0.117	19
1090148	Soil	1.3	8.8	7.9	28	1.0	4.4	1.3	34	0.89	46.4	9.3	0.1	7	0.1	6.4	0.4	20	0.03	0.047	4
1090149	Soil	4.3	68.3	33.1	172	1.7	31.2	7.5	73	6.35	850.8	52.7	2.0	15	0.3	35.4	4.4	43	0.02	0.125	19
1090150	Soil	110.9	60.2	22.8	166	3.4	36.0	4.1	91	3.85	194.2	15.8	1.3	101	2.2	63.7	0.4	600	0.16	0.213	12
1090151	Soil	28.6	28.0	13.3	121	0.5	27.0	3.0	40	1.46	64.9	8.7	0.1	29	0.2	12.3	0.4	225	0.03	0.095	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090121	Soil	79	0.24	872	0.016	9	1.17	0.002	0.15	0.6	16.09	3.9	6.4	0.19	3	13.6	0.5	N.A.	N.A.	N.A.	N.A.
1090122	Soil	12	0.03	425	0.003	2	0.39	0.003	0.06	0.5	1.53	1.4	1.0	<0.05	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090123	Soil	20	0.24	1243	0.001	5	0.91	0.007	0.05	<0.1	1.61	1.8	0.2	0.09	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090124	Soil	36	0.35	361	0.001	2	1.00	0.005	0.04	<0.1	0.28	1.6	0.1	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090125	Soil	41	0.42	501	<0.001	<1	1.22	0.003	0.04	<0.1	0.17	1.8	<0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090126	Soil	37	0.38	375	<0.001	1	1.22	0.003	0.04	<0.1	0.24	1.6	0.1	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090127	Soil	37	0.30	458	0.002	<1	1.05	0.004	0.05	<0.1	0.21	1.8	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090128	Soil	45	0.43	602	0.001	2	1.22	0.003	0.05	<0.1	0.23	2.3	0.2	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090129	Soil	39	0.33	531	0.001	<1	1.00	0.007	0.03	<0.1	0.14	1.5	<0.1	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090130	Soil	50	0.48	801	0.001	<1	1.46	0.006	0.05	<0.1	0.35	2.5	<0.1	<0.05	4	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090131	Soil	39	0.34	1312	0.001	3	1.33	0.005	0.06	<0.1	0.69	2.8	0.3	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090132	Soil	6	0.04	145	0.002	1	0.32	0.008	0.04	0.2	0.15	0.5	0.4	<0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090133	Soil	8	0.07	237	0.004	2	0.37	0.010	0.03	0.1	0.13	1.3	0.3	<0.05	<1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090134	Soil	17	0.10	450	0.006	2	0.64	0.007	0.07	0.2	0.35	1.6	0.7	0.07	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090136	Soil	21	0.13	499	0.004	6	0.56	0.003	0.10	0.2	1.33	3.2	1.8	0.08	1	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090137	Soil	18	0.11	433	0.004	5	0.39	0.003	0.11	0.2	1.77	2.8	1.3	0.10	1	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090138	Soil	22	0.19	310	0.009	3	0.99	0.004	0.09	0.2	0.10	0.9	0.3	<0.05	4	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090139	Soil	14	0.06	215	0.004	2	0.74	0.003	0.08	0.1	0.39	0.8	0.3	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090140	Soil	11	0.03	448	0.002	4	0.43	0.003	0.08	0.1	0.11	0.6	0.3	0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090141	Soil	18	0.12	965	0.004	4	0.58	0.004	0.10	0.1	0.23	2.3	0.4	0.06	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090142	Soil	7	0.15	267	0.008	2	0.45	0.022	0.03	<0.1	0.19	0.5	0.5	0.06	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090143	Soil	24	0.33	108	0.031	2	1.15	0.003	0.11	0.6	31.04	4.3	1.0	0.21	4	14.5	0.3	N.A.	N.A.	N.A.	N.A.
1090144	Soil	21	0.34	121	0.003	1	1.03	0.003	0.11	0.5	4.01	3.6	0.6	0.20	3	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090145	Soil	16	0.23	72	0.001	2	0.92	0.002	0.07	0.2	10.66	3.7	0.3	0.12	3	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090146	Soil	19	0.34	92	0.002	2	1.07	0.003	0.09	0.3	25.72	3.4	0.6	0.14	3	9.3	0.2	N.A.	N.A.	N.A.	N.A.
1090147	Soil	14	0.14	85	0.005	1	0.86	0.008	0.08	0.5	20.89	1.6	0.7	0.10	3	10.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090148	Soil	4	0.03	33	0.009	1	0.21	0.016	0.04	0.1	3.38	0.2	0.2	0.08	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090149	Soil	15	0.13	97	0.006	<1	0.80	0.007	0.07	3.9	3.15	1.4	0.4	0.13	3	8.4	0.4	N.A.	N.A.	N.A.	N.A.
1090150	Soil	54	0.12	366	0.007	3	0.86	0.004	0.23	0.7	8.27	3.6	6.8	0.63	4	16.5	0.4	N.A.	N.A.	N.A.	N.A.
1090151	Soil	17	0.03	191	0.001	1	0.49	0.004	0.07	0.2	1.99	0.2	1.3	0.05	3	4.2	0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090141	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090142	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090143	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090144	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090145	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090146	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090147	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090148	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090149	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090150	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090151	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090141	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090142	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090143	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090144	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090145	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090146	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090147	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090148	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090149	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090150	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090151	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090152	Soil	68.1	121.2	17.5	516	3.6	114.2	12.1	348	2.69	301.3	96.8	0.5	126	3.2	56.1	0.3	458	0.07	0.163	12
1090153	Soil	64.8	63.4	15.2	406	2.3	85.6	9.7	231	2.73	286.7	63.3	0.3	110	1.8	58.7	0.2	491	0.07	0.156	13
1090154	Soil	86.4	61.4	16.0	719	0.8	151.5	7.6	74	2.54	167.3	31.6	0.2	40	1.0	36.7	0.2	541	0.04	0.085	12
1090155	Soil	86.7	218.0	21.9	1632	4.2	352.4	75.6	1722	2.43	205.6	70.6	0.5	73	33.6	50.5	0.2	906	0.20	0.183	11
1090156	Soil	73.9	151.9	20.1	2615	5.0	265.5	13.2	462	1.37	90.3	22.1	0.4	120	62.1	40.7	0.3	1284	1.25	0.242	12
1090157	Soil	64.3	83.3	19.3	849	1.7	149.3	12.7	378	2.63	114.9	17.4	1.6	48	5.7	22.7	0.2	509	0.16	0.137	19
1090158	Soil	31.8	50.5	24.2	369	0.2	93.3	12.3	151	3.90	147.3	5.7	0.5	18	0.9	10.4	0.3	199	0.01	0.079	21
1090159	Soil	22.0	75.7	118.8	301	0.9	74.8	9.4	169	4.55	111.8	9.5	0.4	104	2.0	10.4	0.9	226	0.22	0.411	21
1090160	Soil	238.0	207.7	29.4	1362	3.6	392.0	18.1	217	4.20	197.9	12.0	1.8	149	34.8	41.8	0.4	901	0.12	0.120	27
1090161	Soil	141.9	322.8	31.9	3947	3.9	550.0	14.4	175	2.18	241.1	5.7	3.9	539	44.6	91.6	0.3	2658	8.66	0.246	21
1090162	Soil	146.6	315.0	34.4	4435	4.3	539.5	12.6	201	2.27	220.4	5.4	2.2	390	40.4	85.8	0.3	2292	7.33	0.174	18
1090163	Soil	115.0	274.2	27.1	3944	3.5	476.1	12.0	255	1.74	142.5	4.4	1.2	367	43.0	61.9	0.2	2212	5.40	0.176	19
1090164	Soil	80.5	100.2	17.7	1668	1.4	264.7	9.3	194	1.79	78.2	9.5	1.1	133	18.5	29.0	0.2	811	1.96	0.128	18
1090165	Soil	37.1	67.8	9.4	511	0.8	137.5	6.9	199	1.39	39.8	4.7	0.7	56	6.1	7.7	0.1	296	0.68	0.109	13
1090166	Soil	4.6	24.1	2.6	1273	0.1	169.4	1.3	66	0.30	7.9	7.3	<0.1	257	14.3	1.5	0.1	23	22.74	0.044	2
1090167	Soil	57.4	46.3	12.3	212	0.2	128.6	9.5	234	1.94	28.8	3.0	1.6	21	1.4	5.8	0.1	72	0.33	0.097	22
1090168	Soil	45.0	46.7	12.9	216	0.4	105.6	8.8	282	2.16	31.8	2.2	0.6	24	1.3	4.8	0.2	77	0.40	0.098	13
1090169	Soil	12.3	15.3	8.8	93	0.7	29.2	2.9	31	0.94	15.6	4.1	<0.1	10	0.3	2.0	<0.1	55	0.05	0.074	6
1090170	Soil	14.2	28.1	17.4	136	0.3	42.2	5.9	55	1.75	30.4	3.6	0.2	17	0.3	3.3	0.2	57	0.03	0.059	12
1090171	Soil	18.8	15.6	5.2	66	0.3	29.3	3.3	25	0.92	13.9	2.9	0.2	3	<0.1	1.6	0.1	61	<0.01	0.035	13
1090172	Soil	9.0	56.0	7.0	90	0.2	55.0	16.5	124	2.76	35.0	6.8	1.4	6	0.6	3.4	0.3	58	0.03	0.061	21
1090173	Soil	12.1	35.5	14.1	165	0.3	58.9	8.6	108	2.20	36.6	2.5	0.3	8	0.3	2.7	0.2	35	0.02	0.077	10
1090174	Soil	19.2	65.3	35.2	386	0.7	98.2	8.6	75	2.79	82.9	6.7	0.6	66	1.1	7.5	0.3	56	0.10	0.171	17
1090175	Soil	11.8	39.6	31.5	142	0.5	44.5	8.1	88	2.41	119.5	3.3	0.1	22	0.5	3.5	0.3	71	0.01	0.095	16
1090176	Soil	5.5	78.3	89.7	132	1.1	44.6	4.9	157	1.89	29.9	4.4	0.7	126	0.3	2.5	0.5	39	0.43	0.299	17
1090177	Soil	23.4	60.7	20.1	352	0.3	75.6	14.8	359	4.04	277.8	15.9	0.2	14	0.8	12.6	0.3	84	0.05	0.142	17
1090178	Soil	16.4	43.4	23.2	207	0.2	54.6	12.7	1488	3.44	209.9	<0.5	0.2	13	0.9	7.0	0.3	66	0.02	0.150	20
1090179	Soil	3.5	18.5	12.9	90	0.2	17.8	4.3	371	1.44	64.9	15.5	0.1	6	0.2	10.4	0.1	18	0.03	0.049	15
1090180	Soil	16.3	65.9	37.7	321	0.3	74.4	24.4	918	5.42	127.9	1.6	1.8	7	0.3	6.5	0.4	37	0.02	0.093	39
1090181	Soil	4.8	31.7	7.5	97	0.3	28.2	7.5	223	2.49	340.7	3.6	0.3	9	0.4	6.2	0.3	38	0.05	0.051	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090152	Soil	37	0.09	362	0.005	3	0.92	0.004	0.11	0.9	10.32	1.5	5.0	0.15	3	12.6	0.7	N.A.	N.A.	N.A.	N.A.
1090153	Soil	34	0.08	446	0.004	2	0.72	0.003	0.09	0.5	32.80	0.6	3.5	0.13	3	9.9	0.8	N.A.	N.A.	N.A.	N.A.
1090154	Soil	26	0.05	241	0.002	1	0.57	0.003	0.07	0.5	10.82	0.2	2.9	<0.05	3	8.3	0.6	N.A.	N.A.	N.A.	N.A.
1090155	Soil	43	0.10	533	0.010	5	1.45	0.007	0.09	0.3	8.29	1.8	8.6	<0.05	3	7.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090156	Soil	60	0.21	801	0.011	10	0.76	0.007	0.16	0.4	4.02	2.0	6.5	0.06	3	10.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090157	Soil	33	0.13	450	0.009	4	0.75	0.002	0.09	0.3	2.97	2.8	2.3	<0.05	2	6.9	0.4	N.A.	N.A.	N.A.	N.A.
1090158	Soil	13	0.04	176	0.003	2	0.50	0.002	0.08	0.2	0.26	0.8	0.6	0.06	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090159	Soil	18	0.05	557	0.003	3	0.59	0.004	0.22	<0.1	1.44	0.6	1.4	0.37	2	4.0	0.2	N.A.	N.A.	N.A.	N.A.
1090160	Soil	39	0.06	843	0.004	3	0.83	0.002	0.15	0.7	9.62	4.8	7.3	0.17	3	13.7	0.4	N.A.	N.A.	N.A.	N.A.
1090161	Soil	126	1.50	843	0.058	16	0.90	0.004	0.28	0.9	1.33	3.9	9.8	<0.05	5	12.2	0.4	N.A.	N.A.	N.A.	N.A.
1090162	Soil	105	1.20	660	0.050	13	0.86	0.005	0.23	1.0	1.07	3.7	8.6	<0.05	4	11.7	0.3	N.A.	N.A.	N.A.	N.A.
1090163	Soil	106	1.04	644	0.046	14	0.85	0.006	0.25	0.7	0.48	3.2	7.9	<0.05	4	11.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090164	Soil	52	0.45	400	0.024	4	0.58	0.005	0.11	0.6	0.78	3.5	5.1	<0.05	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090165	Soil	31	0.11	441	0.004	4	0.63	0.006	0.07	0.3	0.58	2.3	1.9	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090166	Soil	6	0.23	212	0.004	3	0.19	0.010	0.02	<0.1	0.30	0.7	2.9	0.12	<1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090167	Soil	12	0.07	271	0.003	3	0.27	0.002	0.05	0.1	0.40	2.0	0.7	<0.05	<1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090168	Soil	12	0.10	560	0.003	1	0.41	0.003	0.06	0.1	0.36	1.5	0.6	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090169	Soil	14	0.03	268	0.001	1	0.36	0.008	0.05	<0.1	0.13	0.1	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090170	Soil	10	0.03	737	0.002	2	0.38	0.003	0.07	0.1	0.10	0.4	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090171	Soil	10	0.03	104	0.003	3	0.35	0.004	0.05	0.1	0.06	0.2	0.3	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090172	Soil	10	0.04	123	0.004	2	0.58	0.004	0.08	0.1	0.09	1.1	0.3	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090173	Soil	9	0.03	625	0.002	2	0.52	0.005	0.07	<0.1	0.12	0.5	0.2	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090174	Soil	12	0.03	298	0.002	3	0.37	0.002	0.09	0.1	0.17	0.7	0.5	0.10	1	3.0	0.2	N.A.	N.A.	N.A.	N.A.
1090175	Soil	13	0.03	214	0.002	<1	0.41	0.003	0.07	<0.1	0.10	0.2	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090176	Soil	15	0.06	689	0.002	5	0.44	0.005	0.15	<0.1	0.52	0.8	0.2	0.13	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090177	Soil	16	0.05	308	0.002	4	0.60	0.004	0.11	0.2	1.51	0.5	0.7	0.08	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090178	Soil	18	0.05	359	0.003	<1	0.56	0.007	0.16	0.1	0.40	0.3	0.4	0.09	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090179	Soil	7	0.03	169	0.002	4	0.32	0.014	0.09	0.1	2.27	0.2	0.4	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090180	Soil	13	0.05	251	0.002	4	0.54	0.004	0.16	<0.1	0.40	3.0	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090181	Soil	10	0.04	153	0.006	<1	0.62	0.014	0.08	<0.1	0.43	0.7	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090152	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090153	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090154	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090155	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090156	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090157	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090158	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090159	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090160	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090161	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090162	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090163	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090164	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090165	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090174	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090175	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090176	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090178	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090180	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090152	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090153	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090154	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090155	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090156	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090157	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090158	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090159	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090160	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090161	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090162	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090163	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090164	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090165	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090174	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090175	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090176	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090178	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090180	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090183	Soil	6.0	23.4	123.1	165	4.3	23.9	5.7	94	3.37	486.0	111.4	5.3	47	0.5	101.0	5.8	40	0.05	0.066	31
1090184	Soil	4.4	10.8	76.8	57	5.7	10.0	2.2	35	1.34	244.9	144.6	4.0	23	0.5	111.1	4.8	24	0.01	0.049	30
1090185	Soil	5.2	13.8	66.1	85	3.3	12.7	2.7	33	1.63	336.9	175.6	2.8	30	0.4	125.7	6.1	27	0.01	0.050	26
1090186	Soil	12.1	16.1	27.7	33	1.8	5.2	0.8	14	0.55	197.2	9.6	1.2	15	0.2	44.7	1.0	29	<0.01	0.016	17
1090187	Soil	27.0	24.5	41.3	76	3.3	11.0	1.5	20	1.51	487.4	66.0	4.2	47	0.4	59.5	1.7	76	0.03	0.065	23
1090188	Soil	19.6	39.6	41.6	140	2.7	20.9	4.0	56	2.38	515.2	99.1	3.4	43	0.6	67.6	2.2	94	0.06	0.079	25
1090189	Soil	15.1	34.8	48.1	123	2.8	19.3	3.9	62	2.28	451.0	88.6	4.0	40	0.5	69.3	2.1	75	0.04	0.074	26
1090190	Soil	6.4	40.4	21.0	84	1.4	19.2	3.4	74	2.32	80.7	19.7	0.2	57	0.3	7.9	0.4	61	0.05	0.122	10
1090191	Soil	4.0	97.2	28.7	166	1.2	31.4	8.0	210	4.29	84.4	7.3	1.5	72	0.7	3.4	0.3	60	0.06	0.171	6
1090192	Soil	2.9	52.5	22.6	127	0.8	25.5	6.5	154	2.76	39.5	3.9	0.6	36	0.3	2.6	0.3	39	0.06	0.122	6
1090193	Soil	4.0	32.8	17.9	68	1.5	14.6	3.0	62	1.98	38.9	2.6	0.7	27	0.2	3.6	<0.1	30	0.02	0.061	3
1090194	Soil	7.5	40.1	18.7	94	2.7	23.7	3.4	47	2.36	50.0	7.3	0.7	35	0.3	3.9	<0.1	31	0.10	0.049	2
1090195	Soil	4.0	50.7	16.8	126	1.0	38.4	5.8	86	2.69	33.8	7.6	1.6	29	0.2	2.9	0.2	49	0.03	0.100	7
1090196	Soil	4.1	60.6	36.7	276	1.8	92.8	12.9	133	3.36	74.4	78.4	1.0	23	1.0	4.1	0.4	64	0.03	0.097	6
1090197	Soil	1.5	31.3	10.4	347	1.4	106.2	14.9	126	2.73	13.0	4.1	0.9	28	0.9	1.3	<0.1	19	0.03	0.090	6
1090198	Soil	5.0	89.1	16.4	266	2.5	85.8	13.2	167	3.39	37.6	7.9	1.1	49	0.9	3.7	0.2	39	0.07	0.094	6
1090199	Soil	3.9	36.5	15.1	185	0.9	62.5	11.3	329	2.91	96.2	26.2	0.5	68	1.7	3.9	0.2	43	0.65	0.146	7
1090200	Soil	2.7	55.4	17.3	168	1.3	52.8	9.6	177	3.11	51.4	10.5	1.3	47	0.8	2.2	0.2	24	0.10	0.077	3
1090201	Soil	2.0	36.2	12.8	98	0.7	31.1	5.4	79	2.26	33.6	7.3	0.4	26	0.2	1.8	0.2	23	0.03	0.083	2
1090202	Soil	1.5	22.1	7.3	48	0.5	14.8	3.0	90	1.66	14.0	3.2	0.1	19	0.2	1.2	<0.1	18	0.07	0.064	2
1090203	Soil	4.8	27.1	18.1	125	0.6	33.8	6.0	95	2.79	42.9	8.3	1.1	33	0.3	2.8	0.2	67	0.35	0.057	6
1090204	Soil	0.9	10.8	5.2	129	0.4	13.6	2.6	123	0.74	5.3	2.1	0.2	103	6.3	0.8	<0.1	17	3.82	0.122	4
1090205	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090206	Soil	2.6	33.8	9.6	117	2.3	50.7	6.5	176	1.93	13.9	4.7	0.5	199	0.9	2.1	<0.1	32	3.81	0.221	11
1090207	Soil	12.4	70.1	21.3	536	2.7	163.0	13.2	168	3.12	31.9	3.8	3.1	279	3.3	6.8	0.2	156	8.84	0.506	13
1090208	Soil	2.9	19.9	17.3	77	1.8	23.3	2.5	66	1.71	15.6	4.9	0.9	66	0.7	1.1	0.2	25	1.01	0.097	5
1090209	Soil	0.3	9.0	3.0	55	0.1	4.4	1.1	94	0.35	1.9	1.7	<0.1	57	0.7	0.3	<0.1	7	1.74	0.071	3
1090210	Soil	3.9	50.2	18.7	201	1.7	59.4	7.4	146	2.35	22.3	6.5	1.1	91	1.4	1.8	0.2	43	1.75	0.162	8
1090211	Soil	2.1	38.2	10.9	144	1.3	37.6	5.0	102	1.84	15.0	5.8	0.6	74	1.0	1.4	0.1	33	1.61	0.128	8
1090212	Soil	1.9	23.9	9.3	125	0.8	27.7	4.7	104	1.41	9.4	4.4	0.4	60	0.9	0.9	<0.1	25	1.27	0.112	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

		Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090183	Soil		19	0.12	187	0.003	1	0.73	0.004	0.11	0.8	>50	1.6	1.4	0.15	3	11.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090184	Soil		13	0.02	88	0.004	5	0.44	0.005	0.09	1.0	>50	0.9	0.6	<0.05	2	15.1	0.4	N.A.	N.A.	N.A.	N.A.
1090185	Soil		11	0.02	92	0.004	1	0.46	0.005	0.07	2.2	41.61	0.7	0.8	0.07	2	13.1	0.3	N.A.	N.A.	N.A.	N.A.
1090186	Soil		7	0.02	162	<0.001	1	0.27	0.004	0.08	0.5	24.84	0.5	1.5	<0.05	1	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090187	Soil		11	0.02	240	<0.001	2	0.29	0.006	0.15	0.7	37.29	1.8	2.4	0.30	2	22.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090188	Soil		14	0.11	225	0.001	1	0.56	0.006	0.11	0.7	25.77	1.9	1.4	0.15	2	14.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090189	Soil		14	0.11	191	0.002	1	0.57	0.005	0.11	0.5	32.97	2.2	1.3	0.12	2	12.1	0.2	N.A.	N.A.	N.A.	N.A.
1090190	Soil		24	0.09	395	0.003	3	0.66	0.007	0.12	0.2	3.76	0.7	0.3	0.19	3	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090191	Soil		23	0.08	354	0.003	1	1.06	0.009	0.12	0.1	0.56	3.2	0.1	0.13	3	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090192	Soil		19	0.08	237	0.003	<1	0.98	0.015	0.09	<0.1	0.79	1.3	<0.1	0.06	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090193	Soil		19	0.04	542	0.002	3	0.53	0.004	0.07	<0.1	0.67	1.4	<0.1	0.16	2	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090194	Soil		29	0.02	948	0.001	6	0.47	0.005	0.09	<0.1	0.98	2.3	<0.1	0.18	1	11.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090195	Soil		21	0.07	260	0.013	5	1.00	0.004	0.10	0.2	1.14	2.3	<0.1	0.48	3	4.1	0.2	N.A.	N.A.	N.A.	N.A.
1090196	Soil		36	0.04	251	0.002	<1	1.28	0.004	0.05	0.1	>50	1.5	0.2	0.06	3	35.3	0.2	N.A.	N.A.	N.A.	N.A.
1090197	Soil		15	0.01	118	0.001	<1	0.45	0.003	0.02	<0.1	1.88	1.7	<0.1	<0.05	<1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090198	Soil		20	0.07	286	0.003	<1	0.68	0.005	0.07	<0.1	3.52	3.2	0.2	0.09	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090199	Soil		25	0.07	454	0.003	<1	0.79	0.006	0.05	0.1	1.33	1.3	0.1	0.09	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090200	Soil		22	0.04	416	<0.001	<1	0.60	0.006	0.09	<0.1	1.70	3.8	<0.1	0.11	2	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090201	Soil		17	0.02	141	0.002	1	0.50	0.011	0.06	<0.1	0.43	1.5	<0.1	0.09	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090202	Soil		14	0.03	87	0.006	<1	0.42	0.016	0.04	<0.1	0.54	0.9	<0.1	0.07	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090203	Soil		23	0.04	357	0.003	<1	0.75	0.006	0.05	0.1	2.32	1.9	0.1	<0.05	4	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090204	Soil		13	0.06	336	0.005	4	0.29	0.007	0.02	<0.1	0.27	0.9	<0.1	0.29	<1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090205	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.7	19.3	8.1	69
1090206	Soil		35	0.14	968	0.002	9	0.79	0.012	0.10	<0.1	0.39	1.4	0.4	0.28	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090207	Soil		42	0.25	1886	0.003	14	1.62	0.010	0.15	0.1	0.41	3.8	0.4	0.07	2	6.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090208	Soil		19	0.08	447	<0.001	4	0.40	0.008	0.13	<0.1	0.42	1.6	0.1	0.22	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090209	Soil		6	0.07	124	0.008	2	0.38	0.023	0.02	<0.1	0.09	0.2	<0.1	0.09	<1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090210	Soil		31	0.18	527	0.002	4	0.82	0.007	0.09	<0.1	0.60	2.7	0.1	0.10	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090211	Soil		20	0.11	427	0.002	2	0.74	0.012	0.07	<0.1	0.39	1.7	<0.1	0.07	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090212	Soil		17	0.08	307	0.003	3	0.56	0.017	0.05	<0.1	0.16	1.4	<0.1	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090205	Soil	0.5	21.6	5.0	244	1.11	6.3	4.7	0.1	49	0.4	0.8	0.1	16	1.33	0.087	5	19	0.06	274	0.011
1090206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090205	Soil	<20	0.59	0.027	0.03	<0.1	0.16	1.0	<0.1	0.09	1	1.3	<0.2
1090206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090213	Soil	1.4	29.6	11.4	140	1.0	35.6	5.8	165	1.86	11.8	3.5	0.7	82	0.9	1.0	0.2	28	1.81	0.141	7
1090214	Soil	0.8	22.6	14.4	57	0.7	13.2	3.3	268	1.34	24.6	29.6	0.6	80	0.5	1.1	0.3	22	1.76	0.084	4
1090215	Soil	0.8	26.7	16.4	61	0.9	17.0	4.8	329	1.74	31.0	19.0	0.4	96	0.5	1.3	0.3	24	2.24	0.095	4
1090216	Soil	1.4	33.1	14.7	88	1.0	26.8	7.1	188	1.88	19.3	15.2	0.8	65	0.4	1.0	0.2	27	1.33	0.092	4
1090217	Soil	0.8	38.1	5.9	53	0.8	29.6	6.2	192	0.79	4.5	2.4	0.2	65	0.4	0.7	<0.1	13	1.30	0.070	4
1090218	Soil	1.5	59.6	6.6	73	1.4	31.2	7.2	284	0.90	8.5	5.1	0.2	87	0.7	1.2	0.1	19	1.83	0.120	5
1090219	Soil	1.8	53.8	11.5	101	2.4	49.5	7.6	395	1.51	10.3	3.9	0.4	95	0.6	1.4	0.1	19	1.07	0.096	5
1090220	Soil	1.3	110.0	6.9	100	1.6	40.6	4.0	68	1.21	8.6	8.3	0.4	160	0.4	1.6	0.2	19	1.09	0.086	6
1090231	Soil	1.9	5.8	82.0	35	3.6	3.3	1.1	16	1.86	265.7	20.2	2.6	23	0.1	43.4	2.8	15	<0.01	0.033	30
1090232	Soil	3.5	15.6	266.9	274	2.9	31.3	8.3	79	5.20	1031	16.6	7.8	46	0.4	73.2	3.8	27	0.03	0.114	33
1090233	Soil	3.5	12.7	64.2	70	0.6	10.9	3.2	48	2.37	80.4	3.2	4.9	27	<0.1	12.3	0.5	17	<0.01	0.041	39
1090234	Soil	3.4	215.7	33.4	406	0.4	136.9	28.6	1030	6.00	131.3	1.0	11.6	46	4.1	7.1	0.5	32	0.10	0.123	39
1090235	Soil	2.8	40.2	24.8	156	0.2	41.6	7.8	228	3.85	47.4	1.4	6.6	11	0.5	3.0	0.3	34	<0.01	0.067	37
1090236	Soil	2.6	30.2	22.9	116	0.2	25.7	5.2	80	3.28	63.3	1.5	4.9	10	0.3	2.3	0.3	35	<0.01	0.054	24
1090237	Soil	2.7	25.8	28.1	104	0.3	31.7	5.3	103	3.10	38.5	<0.5	5.6	13	0.2	2.4	0.3	30	<0.01	0.054	26
1090238	Soil	3.3	33.4	26.5	177	0.1	32.6	10.4	291	3.80	42.0	<0.5	1.6	13	0.3	2.4	0.3	27	<0.01	0.064	5
1090239	Soil	3.8	27.7	20.1	136	<0.1	33.3	11.4	193	2.84	157.4	2.7	0.6	10	0.2	2.6	0.2	21	<0.01	0.048	3
1090240	Soil	2.1	26.7	15.4	141	<0.1	32.8	11.7	194	2.34	54.7	1.4	0.8	18	0.4	1.2	0.3	15	0.03	0.041	3
1090241	Soil	4.4	38.5	23.0	156	0.3	33.9	9.2	248	2.37	54.9	3.4	0.7	27	1.1	2.4	0.4	30	0.03	0.057	4
1090242	Soil	10.2	19.6	36.0	14	1.5	4.2	0.5	18	1.06	63.8	39.7	0.9	53	<0.1	9.2	0.4	64	0.01	0.061	4
1090243	Soil	11.1	7.9	68.6	11	2.2	2.8	0.6	16	0.79	42.2	83.8	0.1	19	<0.1	8.0	0.3	41	0.01	0.044	3
1090244	Soil	14.4	9.9	46.0	7	1.2	1.9	0.3	10	0.66	40.9	11.0	3.4	24	<0.1	11.3	0.3	34	<0.01	0.028	5
1090247	Soil	30.9	17.0	25.0	34	2.4	9.9	1.1	18	0.93	55.5	19.6	0.5	34	0.2	12.1	0.3	201	0.01	0.067	13
1090248	Soil	86.6	31.9	21.2	32	4.7	11.3	1.1	35	1.55	123.9	20.6	0.6	59	0.1	32.4	0.2	433	0.02	0.096	15
1090249	Soil	223.7	91.0	25.4	25	4.0	34.4	0.5	14	2.38	806.2	1.1	3.9	114	0.6	111.1	0.3	1160	0.01	0.185	14
1090250	Soil	127.0	214.7	26.5	1289	4.4	181.1	3.3	121	2.22	440.5	9.8	2.7	158	53.2	84.9	0.3	1307	1.00	0.190	16
1090251	Soil	123.4	348.1	26.7	4845	6.3	642.5	8.5	199	2.51	256.3	15.8	1.5	243	48.0	78.7	0.2	2108	3.13	0.236	21
1090252	Soil	118.3	118.3	21.6	311	3.1	75.7	1.7	38	1.92	253.1	24.7	0.8	174	4.8	48.4	0.2	1178	0.59	0.140	16
1090253	Soil	97.0	207.1	26.9	1819	4.4	312.5	7.3	220	1.92	202.8	18.1	0.7	175	37.2	60.3	0.2	1513	0.74	0.257	17
1090254	Soil	37.7	25.1	31.5	138	1.4	30.1	1.9	32	1.33	50.1	34.8	0.3	27	0.8	13.4	0.3	335	0.03	0.060	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090213	Soil	17	0.15	459	0.001	5	0.79	0.010	0.07	<0.1	0.27	2.0	0.1	0.09	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090214	Soil	14	0.08	463	0.002	7	0.72	0.010	0.07	0.1	1.12	1.4	0.1	0.11	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090215	Soil	13	0.13	457	0.002	4	0.83	0.010	0.05	<0.1	1.68	1.4	<0.1	0.13	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090216	Soil	15	0.14	357	0.002	3	0.89	0.009	0.06	<0.1	0.76	2.1	0.1	0.10	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090217	Soil	7	0.09	434	0.010	3	0.66	0.025	0.03	<0.1	0.20	0.9	<0.1	0.09	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090218	Soil	9	0.10	504	0.009	3	0.84	0.018	0.03	<0.1	0.56	1.2	0.1	0.14	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090219	Soil	16	0.13	349	0.010	4	0.71	0.017	0.04	<0.1	0.71	2.0	0.1	0.08	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090220	Soil	10	0.17	341	0.005	3	0.77	0.021	0.04	<0.1	0.79	1.8	0.2	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090231	Soil	5	0.01	171	<0.001	5	0.32	0.004	0.17	0.5	35.62	0.8	1.7	0.36	1	11.5	0.2	N.A.	N.A.	N.A.	N.A.
1090232	Soil	12	0.03	171	0.001	3	0.58	0.005	0.16	0.3	16.63	4.2	1.1	0.24	2	10.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090233	Soil	7	0.02	127	<0.001	4	0.47	0.003	0.10	<0.1	1.36	1.2	0.3	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090234	Soil	14	0.22	201	<0.001	1	1.76	0.002	0.09	<0.1	0.84	10.6	0.2	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090235	Soil	19	0.27	99	<0.001	2	1.26	0.003	0.08	<0.1	0.31	3.2	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090236	Soil	16	0.13	69	<0.001	<1	0.97	0.002	0.06	<0.1	0.33	2.4	0.2	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090237	Soil	17	0.27	82	<0.001	2	0.96	0.002	0.07	<0.1	0.33	2.6	0.2	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090238	Soil	10	0.11	66	0.001	1	0.75	0.003	0.07	<0.1	0.44	3.1	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090239	Soil	7	0.03	58	0.001	<1	0.47	0.004	0.05	<0.1	1.11	2.6	0.1	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090240	Soil	7	0.03	191	<0.001	<1	0.36	0.002	0.05	<0.1	0.23	2.5	0.2	<0.05	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090241	Soil	10	0.04	327	0.001	2	0.49	0.004	0.08	<0.1	0.33	2.7	0.4	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090242	Soil	12	0.01	1057	0.001	6	0.33	0.003	0.13	<0.1	4.36	1.3	0.7	0.16	2	9.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090243	Soil	7	0.01	443	0.003	2	0.24	0.008	0.09	0.1	2.48	0.2	0.5	0.12	2	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090244	Soil	6	0.01	516	0.001	3	0.22	0.002	0.10	<0.1	4.15	1.0	0.5	0.05	1	8.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090247	Soil	18	0.02	649	0.003	4	0.33	0.002	0.09	0.3	8.09	0.7	0.8	<0.05	3	7.0	0.2	N.A.	N.A.	N.A.	N.A.
1090248	Soil	34	0.04	1047	0.006	3	0.46	0.002	0.14	0.5	13.12	1.1	1.9	0.14	5	23.9	0.4	N.A.	N.A.	N.A.	N.A.
1090249	Soil	94	0.05	970	0.009	10	0.52	0.004	0.28	1.0	35.25	5.9	4.8	0.27	6	62.8	1.5	N.A.	N.A.	N.A.	N.A.
1090250	Soil	80	0.11	1050	0.012	9	0.93	0.003	0.23	0.8	24.56	6.1	5.9	0.26	5	46.6	1.5	N.A.	N.A.	N.A.	N.A.
1090251	Soil	120	0.78	1101	0.036	20	1.24	0.005	0.25	0.6	6.17	6.1	9.5	0.05	5	27.2	0.7	N.A.	N.A.	N.A.	N.A.
1090252	Soil	82	0.09	818	0.009	8	0.75	0.005	0.22	0.6	7.41	2.7	6.9	0.20	5	57.1	0.8	N.A.	N.A.	N.A.	N.A.
1090253	Soil	86	0.18	1197	0.022	15	1.29	0.005	0.21	0.6	11.31	3.3	7.6	<0.05	5	22.9	0.6	N.A.	N.A.	N.A.	N.A.
1090254	Soil	21	0.03	376	0.003	7	0.33	0.003	0.13	0.2	12.88	0.3	1.8	<0.05	3	6.8	0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090213	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090214	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090215	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090216	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090217	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090218	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090219	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090220	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090231	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090232	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090233	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090234	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090235	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090236	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090237	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090238	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090239	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090240	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090241	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090242	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090243	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090244	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090247	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090248	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090249	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090250	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090251	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090252	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090253	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090254	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090218	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090231	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090232	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090233	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090234	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090235	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090236	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090237	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090238	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090239	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090240	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090241	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090242	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090243	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090244	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090247	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090249	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090250	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090254	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

		Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090255	Soil		12.0	37.6	24.4	157	1.0	36.1	5.4	91	2.14	52.0	9.9	0.3	26	1.1	6.5	0.2	94	0.07	0.138	8
1090256	Soil		91.0	55.7	29.6	448	1.5	82.5	4.7	93	2.44	104.2	11.7	0.5	126	3.3	23.0	0.3	484	0.05	0.135	23
1090257	Soil		85.6	159.9	21.8	1757	3.5	284.1	11.0	238	2.40	104.3	6.6	2.3	128	19.4	32.8	0.2	1757	3.32	0.097	26
1090258	Soil		71.5	58.5	22.6	626	0.9	142.2	7.3	359	2.16	75.2	2.6	0.5	73	7.8	20.1	0.3	996	0.69	0.124	18
1090259	Soil		50.8	74.3	18.8	1057	1.4	177.2	17.0	767	2.05	69.6	1.9	0.6	48	17.9	22.1	0.2	1031	0.38	0.215	21
1090260	Soil		71.4	87.2	10.8	418	0.5	179.8	8.2	183	2.07	55.8	2.1	2.2	104	5.1	11.3	0.2	191	2.37	0.130	20
1090262	Soil		11.8	17.8	3.6	58	0.1	30.8	2.6	231	0.59	9.0	2.4	0.1	34	1.1	1.1	0.1	28	0.67	0.069	5
1090263	Soil		36.8	29.1	6.5	114	<0.1	56.4	4.2	54	1.46	29.6	1.5	0.1	22	0.6	2.8	0.1	60	0.36	0.049	7
1090265	Soil		28.7	86.7	14.7	743	1.7	118.8	8.5	79	1.46	29.6	2.3	5.1	25	8.9	12.8	0.2	107	0.48	0.128	14
1090266	Soil		6.9	24.2	11.7	88	0.3	22.2	3.3	50	1.63	31.0	1.2	0.8	8	0.4	2.9	0.3	38	0.10	0.065	11
1090267	Soil		9.1	48.8	21.5	221	0.6	55.8	8.6	59	2.80	159.9	3.4	0.1	54	0.3	4.3	0.3	37	0.05	0.136	8
1090268	Soil		40.1	15.0	6.4	98	<0.1	48.5	2.7	16	0.92	20.1	1.4	0.1	6	0.1	3.8	0.1	107	0.07	0.052	11
1090269	Soil		56.8	48.5	9.6	134	0.2	112.5	7.3	206	1.95	26.2	2.0	0.8	31	1.2	3.6	0.1	36	0.66	0.103	11
1090270	Soil		60.8	48.3	11.6	212	<0.1	113.5	7.5	116	2.14	29.8	2.3	0.4	28	1.3	3.5	0.2	48	1.11	0.069	14
1090271	Soil		58.0	69.6	11.6	171	0.2	142.2	8.4	225	2.03	35.3	2.6	0.4	34	2.1	4.2	0.2	46	0.56	0.102	12
1090272	Soil		68.9	79.4	11.8	221	0.4	174.8	8.9	271	2.11	39.7	1.8	0.8	54	3.4	5.5	0.1	50	1.83	0.098	12
1090273	Soil		74.6	81.2	12.1	304	0.5	199.7	9.4	303	2.20	49.7	1.3	1.0	67	3.9	6.7	0.2	69	2.07	0.108	15
1090274	Soil		74.2	70.9	10.1	344	0.4	175.0	10.1	280	2.08	47.2	2.3	2.0	161	3.2	6.4	0.1	70	5.60	0.105	12
1090275	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090276	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090285	Soil		19.0	26.4	21.1	243	0.5	43.1	4.9	64	2.36	101.2	7.8	2.0	25	0.9	8.2	0.4	190	0.03	0.091	13
1090223	Soil		2.9	50.0	15.1	119	0.7	32.1	6.3	141	1.89	23.1	14.5	1.5	90	0.4	3.2	0.2	58	0.45	0.071	6
1090310	Soil		0.3	2.3	0.9	7	<0.1	1.6	0.9	16	0.34	<0.5	<0.5	<0.1	6	<0.1	0.1	<0.1	12	0.04	0.017	<1
1090314	Soil		0.5	2.6	1.8	6	0.9	1.3	0.6	11	0.23	1.4	1.9	<0.1	8	<0.1	0.2	<0.1	10	0.03	0.013	<1
1090225	Soil		3.7	86.9	17.3	100	0.7	26.7	6.3	98	1.94	17.8	24.5	1.3	56	0.3	2.7	0.3	51	0.26	0.069	4
1090226	Soil		2.4	98.6	14.1	138	0.5	34.6	8.0	156	2.49	15.3	19.6	1.4	139	0.2	1.9	0.3	40	0.28	0.055	4
1090227	Soil		2.1	95.0	10.4	149	0.5	40.3	7.5	126	2.45	11.9	16.6	1.2	282	0.4	1.4	0.3	36	0.37	0.051	3
1090228	Soil		1.6	74.3	9.7	141	0.5	40.0	7.1	85	2.70	8.7	14.8	1.5	117	0.2	1.2	0.3	35	0.27	0.041	3
1090229	Soil		4.6	59.7	14.8	137	0.8	34.4	4.6	75	1.69	29.2	19.0	1.4	47	0.7	4.5	0.2	67	0.38	0.074	7
1090230	Soil		2.2	65.9	12.5	97	1.2	22.3	3.8	73	1.66	23.9	21.2	0.7	43	0.4	2.4	0.2	44	0.49	0.085	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090255	Soil	11	0.05	391	0.003	5	0.47	0.009	0.16	0.1	2.96	0.3	0.7	0.07	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090256	Soil	26	0.05	355	0.007	5	0.57	0.003	0.16	0.5	7.45	0.7	2.9	<0.05	3	8.2	0.4	N.A.	N.A.	N.A.	N.A.
1090257	Soil	94	1.58	647	0.008	13	1.06	0.006	0.21	0.4	1.57	4.8	4.0	<0.05	4	9.7	0.3	N.A.	N.A.	N.A.	N.A.
1090258	Soil	52	0.17	555	0.008	7	0.86	0.012	0.16	0.4	0.50	1.2	2.5	<0.05	4	7.0	0.2	N.A.	N.A.	N.A.	N.A.
1090259	Soil	86	0.17	686	0.013	10	1.05	0.012	0.17	0.4	0.75	1.5	2.0	<0.05	4	7.0	0.3	N.A.	N.A.	N.A.	N.A.
1090260	Soil	21	1.11	393	0.004	7	0.40	0.005	0.09	0.3	0.49	4.0	2.3	0.08	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090262	Soil	6	0.06	225	0.008	3	0.50	0.026	0.03	0.1	0.13	0.7	0.5	0.08	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090263	Soil	9	0.05	166	0.004	3	0.41	0.012	0.03	0.2	0.06	0.4	0.9	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090265	Soil	11	0.06	311	0.001	7	0.24	0.002	0.09	<0.1	0.51	3.7	0.3	<0.05	<1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090266	Soil	8	0.06	218	0.001	3	0.38	<0.001	0.04	<0.1	0.10	1.0	0.2	<0.05	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090267	Soil	8	0.03	452	0.001	2	0.45	0.004	0.09	<0.1	0.11	0.2	0.3	0.16	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090268	Soil	8	0.04	115	0.001	2	0.39	0.003	0.05	0.1	0.15	0.1	0.7	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090269	Soil	14	0.13	446	0.003	4	0.45	0.003	0.06	0.2	0.39	2.5	0.9	0.05	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090270	Soil	14	0.07	364	0.005	5	0.40	0.005	0.07	0.3	0.20	1.3	1.5	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090271	Soil	14	0.11	455	0.003	3	0.49	0.009	0.06	0.3	0.37	1.6	1.9	<0.05	1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090272	Soil	15	0.36	404	0.004	5	0.42	0.009	0.07	0.3	0.54	3.3	3.0	<0.05	1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090273	Soil	17	0.72	385	0.005	4	0.45	0.008	0.08	0.3	0.64	4.1	3.4	<0.05	1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090274	Soil	13	1.76	331	0.003	6	0.28	0.006	0.06	0.2	0.48	3.6	2.0	<0.05	<1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090275	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090276	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090285	Soil	15	0.05	218	0.005	3	0.61	0.003	0.07	0.3	0.72	1.7	0.6	<0.05	4	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090223	Soil	25	0.30	780	0.001	3	0.92	0.005	0.05	0.1	1.49	2.1	0.3	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090310	Soil	2	0.02	16	0.012	<1	0.11	0.018	0.02	<0.1	0.02	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090314	Soil	2	0.02	65	0.007	2	0.15	0.020	0.02	<0.1	0.17	0.3	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090225	Soil	30	0.26	761	0.002	4	1.01	0.007	0.06	0.1	0.88	2.2	0.2	0.09	3	1.9	0.2	N.A.	N.A.	N.A.	N.A.
1090226	Soil	36	0.40	748	0.001	3	1.26	0.006	0.05	<0.1	0.59	2.5	0.1	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090227	Soil	38	0.41	1328	0.001	3	1.23	0.006	0.04	<0.1	0.37	2.4	0.1	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090228	Soil	44	0.52	828	<0.001	3	1.37	0.005	0.05	<0.1	0.38	2.6	<0.1	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090229	Soil	25	0.17	767	0.002	4	0.85	0.006	0.08	0.2	1.37	2.2	0.4	0.07	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090230	Soil	21	0.13	585	0.002	3	0.89	0.014	0.05	0.1	1.38	1.9	0.3	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090258	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090259	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090271	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090272	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090273	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090274	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090275	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090276	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090310	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090226	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090227	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090258	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090259	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090271	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090272	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090273	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090274	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090275	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090276	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090310	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090226	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090227	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090401	Soil	105.4	214.5	17.1	3389	6.6	299.0	5.2	148	1.63	116.3	5.8	0.3	200	58.4	50.7	0.2	1461	3.64	0.169	21
1090402	Soil	49.8	38.4	18.6	302	1.3	84.2	5.5	61	2.27	101.9	16.0	0.2	22	0.7	20.4	0.2	421	0.03	0.078	14
1090403	Soil	13.2	9.2	7.5	30	10.2	6.2	0.8	15	0.72	14.8	18.4	<0.1	14	0.4	5.6	0.1	70	0.03	0.128	4
1090404	Soil	7.0	23.2	35.3	115	1.1	14.2	3.6	46	2.20	37.1	8.9	3.9	32	0.1	5.6	0.4	52	0.02	0.035	7
1090405	Soil	5.2	15.1	21.1	79	1.0	8.8	2.1	33	1.48	33.3	9.2	1.5	19	<0.1	4.6	0.4	26	0.03	0.046	5
1090407	Soil	5.0	43.0	18.6	181	0.5	27.9	9.5	457	2.92	81.5	14.9	1.1	56	0.5	5.6	0.4	29	0.03	0.060	3
1090408	Soil	6.8	49.5	17.4	186	0.5	39.1	13.7	271	3.41	27.1	3.9	0.3	17	0.4	3.1	0.4	43	0.01	0.087	4
1090409	Soil	6.0	65.5	24.0	369	0.7	78.1	26.8	1183	5.37	61.7	3.6	0.4	43	0.7	5.1	0.4	47	0.02	0.114	5
1090411	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090412	Soil	3.6	5.5	66.0	7	4.5	1.3	0.3	12	0.87	36.9	94.3	1.5	145	<0.1	12.6	0.4	31	0.04	0.073	12
1090413	Soil	8.2	19.5	34.4	66	0.9	12.6	2.8	49	1.77	46.2	9.2	0.2	85	0.1	5.5	0.3	69	0.05	0.072	5
1090414	Soil	14.4	32.3	44.9	95	1.3	20.7	4.4	149	2.40	44.6	20.9	1.1	218	<0.1	8.0	0.4	85	0.06	0.141	5
1090415	Soil	9.1	17.4	40.0	44	0.9	8.8	1.9	48	1.35	27.4	5.0	0.2	81	<0.1	4.5	0.3	55	0.04	0.077	3
1090416	Soil	12.6	27.8	32.4	121	0.5	25.3	5.0	78	1.81	40.5	3.8	0.4	35	0.2	5.0	0.3	79	0.02	0.066	6
1090417	Soil	14.3	27.4	49.9	91	1.1	17.6	3.7	80	1.94	34.8	5.9	0.2	61	0.3	5.1	0.4	79	0.03	0.097	4
1090418	Soil	13.3	28.3	46.4	91	1.1	20.0	4.6	131	2.16	40.8	7.3	0.4	63	0.2	5.7	0.4	73	0.06	0.097	7
1090419	Soil	17.1	30.0	53.2	75	1.4	16.1	3.7	124	2.00	40.3	7.6	0.4	75	0.2	6.1	0.3	84	0.05	0.121	6
1090420	Soil	10.1	30.9	30.0	94	0.5	21.9	5.3	209	2.31	33.0	6.5	0.2	37	0.2	4.4	0.3	70	0.04	0.091	7
1090451	Soil	28.2	47.2	30.3	331	1.4	50.9	2.2	75	1.40	82.7	45.4	0.5	49	4.8	17.4	0.3	273	0.23	0.097	7
1090452	Soil	12.0	92.0	24.6	523	0.5	66.0	15.6	361	4.36	95.2	7.1	0.5	10	2.0	6.6	0.2	41	0.10	0.153	15
1090453	Soil	15.1	76.3	20.1	438	0.3	61.4	13.7	365	3.62	84.5	8.7	0.4	20	3.1	6.5	0.3	55	0.16	0.156	12
1090454	Soil	42.5	44.1	13.4	423	0.1	84.7	7.3	477	2.20	89.7	6.6	0.2	23	3.0	8.4	0.2	318	0.21	0.133	10
1090455	Soil	23.4	64.6	21.0	453	0.7	89.0	6.4	198	1.82	59.3	8.2	0.5	70	3.3	6.7	0.2	106	0.69	0.166	8
1090456	Soil	230.3	175.6	25.4	1513	2.6	375.0	26.3	509	3.78	244.0	0.9	1.1	70	15.4	123.2	0.3	908	0.21	0.222	21
1090457	Soil	139.7	182.1	10.2	1709	1.0	372.9	15.7	325	2.39	156.0	4.4	2.7	114	31.7	49.0	0.2	356	3.27	0.106	15
1090458	Soil	101.0	100.1	12.0	464	0.5	241.2	11.5	257	2.28	55.8	<0.5	2.8	191	4.4	10.1	0.2	98	6.61	0.128	12
1090459	Soil	8.6	62.8	28.8	90	1.1	31.6	4.8	78	2.49	43.1	6.0	0.9	57	1.0	8.7	0.3	52	0.16	0.132	12
1090460	Soil	7.3	200.3	46.6	335	4.0	122.4	13.3	162	8.56	95.5	2.0	4.3	123	1.4	7.3	0.4	29	0.58	0.490	10
1090428	Soil	4.8	12.8	12.2	48	0.3	11.3	2.7	53	1.16	22.4	1.3	0.2	17	0.2	1.8	0.2	42	0.02	0.042	6
1090443	Soil	3.9	75.3	15.1	131	0.8	43.8	6.5	91	3.03	30.0	5.1	0.7	57	0.2	2.2	0.2	38	0.02	0.086	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090401	Soil	68	1.23	767	0.022	18	0.80	0.009	0.18	0.6	2.00	3.7	7.5	<0.05	3	10.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090402	Soil	19	0.03	162	0.003	4	0.45	0.003	0.08	0.3	0.98	0.3	1.8	0.08	3	6.6	0.3	N.A.	N.A.	N.A.	N.A.
1090403	Soil	8	0.02	114	0.004	4	0.27	0.009	0.04	0.1	2.61	0.3	0.7	0.08	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090404	Soil	7	0.01	183	0.007	3	0.25	0.002	0.12	0.1	0.63	1.3	0.4	0.14	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090405	Soil	6	0.01	186	0.002	3	0.23	0.002	0.12	<0.1	3.17	2.0	0.3	0.16	1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090407	Soil	9	0.02	276	0.001	3	0.33	0.001	0.08	<0.1	0.13	2.6	0.2	<0.05	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090408	Soil	11	0.03	107	0.002	2	0.33	0.002	0.07	<0.1	0.11	1.9	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090409	Soil	17	0.08	199	0.004	2	0.60	0.002	0.06	<0.1	0.12	2.4	0.3	0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090411	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.9	94.7	30.1	345
1090412	Soil	7	<0.01	738	<0.001	3	0.20	0.002	0.14	<0.1	4.11	2.8	0.5	0.26	2	9.0	0.2	N.A.	N.A.	N.A.	N.A.
1090413	Soil	10	0.02	724	0.005	1	0.35	0.005	0.11	0.2	0.15	0.8	0.3	0.19	3	4.3	0.2	N.A.	N.A.	N.A.	N.A.
1090414	Soil	22	0.10	1422	0.007	5	0.56	0.007	0.18	0.1	0.34	3.2	0.7	0.22	3	6.6	0.3	N.A.	N.A.	N.A.	N.A.
1090415	Soil	10	0.03	767	0.004	4	0.35	0.007	0.10	<0.1	0.25	1.0	0.4	0.19	2	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090416	Soil	13	0.01	280	0.007	4	0.28	0.003	0.07	0.2	0.21	1.2	0.2	0.09	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090417	Soil	16	0.03	624	0.003	3	0.48	0.003	0.09	0.1	0.35	0.6	0.4	0.16	2	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090418	Soil	14	0.09	835	0.006	4	0.58	0.003	0.10	0.1	0.32	1.3	0.6	0.15	3	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090419	Soil	17	0.07	774	0.006	3	0.56	0.007	0.12	0.1	0.28	1.7	0.6	0.18	3	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090420	Soil	17	0.09	569	0.008	2	0.67	0.004	0.08	0.1	0.30	0.9	0.4	0.11	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090451	Soil	23	0.03	794	0.004	6	0.35	0.004	0.16	0.2	10.06	1.2	1.4	0.28	2	6.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090452	Soil	7	0.06	339	0.002	4	0.54	0.003	0.09	0.1	0.37	1.3	0.5	<0.05	1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090453	Soil	7	0.05	293	0.002	4	0.43	0.003	0.09	<0.1	1.26	1.4	0.6	0.06	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090454	Soil	17	0.05	333	0.002	5	0.49	0.005	0.08	0.3	0.54	0.4	1.3	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090455	Soil	11	0.07	393	0.005	4	0.69	0.012	0.07	0.2	1.96	1.3	1.0	0.10	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090456	Soil	49	0.13	588	0.004	9	0.75	0.002	0.18	0.8	0.27	2.4	4.6	<0.05	3	18.0	0.5	N.A.	N.A.	N.A.	N.A.
1090457	Soil	23	1.51	241	<0.001	2	0.30	0.003	0.05	0.7	5.70	3.7	4.8	<0.05	1	7.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090458	Soil	14	1.83	305	0.003	5	0.27	0.005	0.07	0.3	0.11	3.6	2.2	<0.05	<1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090459	Soil	12	0.05	953	0.003	5	0.39	0.004	0.14	0.1	1.57	1.7	0.7	0.32	3	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090460	Soil	11	0.09	67	0.002	3	1.22	0.010	0.45	<0.1	1.78	8.7	0.5	1.09	1	15.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090428	Soil	8	0.03	220	0.006	2	0.48	0.010	0.04	<0.1	0.11	0.3	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090443	Soil	19	0.02	391	0.002	3	0.61	0.005	0.07	<0.1	0.12	1.7	0.2	0.07	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090401	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090402	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090403	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090404	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090405	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090407	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090408	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090409	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090411	Soil		0.6	55.7	11.9	314	4.08	41.1	4.7	1.2	85	0.3	1.9	0.4	57	0.04	0.132	5	24	0.05	236	0.002
1090412	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090413	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090414	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090415	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090416	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090417	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090418	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090419	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090420	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090451	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090452	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090453	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090454	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090455	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090456	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090457	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090458	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090459	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090460	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090428	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090443	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090401	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090402	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090403	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090404	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090405	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090407	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090408	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090409	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090411	Soil	<20	0.71	0.004	0.10	<0.1	0.07	8.0	0.4	<0.05	2	2.9	<0.2
1090412	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090413	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090414	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090415	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090416	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090417	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090418	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090419	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090420	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090451	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090452	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090453	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090454	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090455	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090456	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090457	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090458	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090459	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090460	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090428	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090443	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090447	Soil	4.2	117.7	13.5	386	1.4	127.3	19.3	225	4.68	17.3	2.6	1.3	52	1.2	1.4	0.2	22	0.05	0.115	5
1090450	Soil	0.9	5.6	5.0	43	<0.1	6.8	1.6	88	0.48	2.6	<0.5	<0.1	25	0.9	0.4	<0.1	17	0.68	0.059	3
1090420	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090421	Soil	20.0	65.5	43.9	296	0.7	49.6	6.5	65	3.30	53.5	1.3	0.9	37	0.5	6.1	0.3	63	0.09	0.201	13
1090422	Soil	13.7	32.3	38.3	75	0.9	19.3	4.8	139	1.97	39.8	15.4	0.9	60	0.3	7.6	0.2	79	0.07	0.095	6
1090423	Soil	11.7	29.3	29.1	89	0.5	21.1	5.1	168	2.18	40.5	5.6	0.1	47	0.2	5.1	0.3	79	0.03	0.095	6
1090426	Soil	8.5	36.6	25.6	131	0.2	33.8	10.4	415	2.90	77.6	4.3	0.2	35	0.9	3.6	0.4	73	0.03	0.136	8
1090427	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090428	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090429	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090430	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090431	Soil	10.8	66.9	25.0	188	1.1	42.1	11.0	282	3.03	69.2	18.7	1.5	57	0.9	7.5	0.3	68	0.07	0.122	10
1090438	Soil	3.3	30.8	13.6	135	0.8	47.3	7.4	85	2.51	13.1	2.8	0.7	20	0.4	0.9	0.2	35	0.01	0.055	4
1090439	Soil	2.6	18.8	12.1	124	1.1	27.4	6.3	226	1.85	9.5	3.2	0.4	22	2.1	1.0	0.2	41	0.18	0.092	6
1090441	Soil	3.1	26.3	12.9	137	0.4	52.2	9.1	181	2.08	18.7	1.9	0.8	33	0.9	1.1	0.2	33	0.40	0.065	5
1090442	Soil	2.3	77.2	33.0	76	2.2	29.5	5.5	121	3.55	42.3	9.3	2.8	297	0.3	1.5	0.5	23	0.27	0.101	4
1090444	Soil	1.5	24.6	7.5	67	0.3	23.5	4.1	64	1.63	8.9	1.6	<0.1	21	0.2	0.9	0.1	26	0.07	0.059	3
1090462	Soil	65.7	75.8	18.3	399	1.0	159.0	10.7	149	2.79	90.7	4.4	1.4	44	3.6	12.7	0.2	147	1.00	0.163	12
1090463	Soil	105.9	98.4	16.4	212	0.6	236.2	14.0	250	2.88	115.3	5.9	2.5	56	0.9	8.8	0.2	71	1.81	0.171	14
1090465	Soil	121.1	210.9	19.8	2358	4.2	355.5	8.6	185	2.24	121.5	3.0	1.7	174	68.9	42.6	0.2	1360	3.76	0.207	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090447	Soil	22	0.09	317	0.001	2	1.14	0.004	0.05	<0.1	0.22	3.5	<0.1	<0.05	2	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090450	Soil	4	0.02	92	0.011	4	0.44	0.020	0.02	<0.1	0.08	0.4	<0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090420	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090421	Soil	7	0.04	353	0.006	3	0.52	0.002	0.08	0.1	0.13	2.0	0.2	<0.05	2	6.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090422	Soil	16	0.11	917	0.009	1	0.55	0.004	0.12	0.2	1.16	2.2	0.6	0.20	3	6.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090423	Soil	16	0.04	774	0.006	2	0.63	0.006	0.08	0.1	0.19	0.6	0.4	0.13	4	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090426	Soil	16	0.06	1958	0.003	3	1.03	0.004	0.07	0.2	0.29	0.7	0.4	0.08	4	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090427	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090428	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090429	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090430	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090431	Soil	17	0.13	474	0.005	3	0.80	0.003	0.09	0.2	4.37	3.2	0.6	0.10	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090438	Soil	14	0.04	137	0.003	1	0.53	0.003	0.04	<0.1	0.05	1.2	<0.1	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090439	Soil	15	0.08	350	0.004	3	0.72	0.004	0.05	0.1	0.14	1.3	0.1	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090441	Soil	12	0.04	391	0.002	4	0.57	0.003	0.06	<0.1	0.08	1.7	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090442	Soil	19	0.03	342	<0.001	3	0.61	0.013	0.22	<0.1	0.64	3.6	0.4	0.50	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090444	Soil	8	0.03	113	0.010	3	0.43	0.014	0.04	<0.1	0.04	0.5	<0.1	0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090462	Soil	11	0.21	1409	0.002	4	0.36	0.003	0.09	0.1	0.70	3.5	0.6	0.13	<1	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090463	Soil	15	0.57	642	0.002	6	0.29	0.003	0.07	0.2	0.51	4.3	1.6	0.08	<1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090465	Soil	81	1.11	575	0.010	11	0.74	0.005	0.20	0.5	1.30	4.6	5.4	0.13	3	16.2	0.3	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090447	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090450	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090420	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090421	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090422	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090423	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090426	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090427	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090428	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090429	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090430	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090431	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090438	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090439	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090441	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090442	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090444	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090462	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090463	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090465	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000491.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090447	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090450	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090420	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090421	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090422	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090423	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090426	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090427	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090428	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090429	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090430	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090431	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090438	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090439	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090441	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090442	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090444	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090462	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090463	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090465	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1090014	Soil	159.8	116.3	15.5	3449	0.4	1102	190.3	5261	3.90	62.2	4.7	4.4	180	23.7	9.2	0.2	91	5.18	0.220	12
REP 1090014	QC	160.9	115.2	16.1	3413	0.4	1075	185.5	5161	3.93	61.2	3.2	4.6	182	24.2	9.2	0.2	88	5.24	0.221	12
1090020	Soil	72.5	15.7	6.2	269	<0.1	130.4	5.8	28	1.62	22.4	1.3	0.5	5	0.7	5.9	0.1	123	0.06	0.035	12
REP 1090020	QC	72.1	15.1	6.1	263	<0.1	130.9	5.9	28	1.60	22.5	1.0	0.4	5	0.8	6.0	<0.1	127	0.06	0.036	12
1090043	Soil	5.5	34.5	19.6	124	0.5	35.1	5.7	55	2.26	46.7	7.7	0.9	24	0.2	3.7	0.3	58	<0.01	0.060	8
REP 1090043	QC	5.5	33.6	19.3	122	0.6	32.6	5.5	54	2.08	45.4	2.0	1.7	24	0.2	3.8	0.3	55	<0.01	0.063	9
1090050	Soil	1.0	22.6	11.9	70	1.1	18.5	2.8	110	1.36	8.3	3.9	0.5	96	0.6	0.7	0.2	25	2.06	0.119	8
REP 1090050	QC	0.8	22.3	11.8	68	1.1	18.6	2.9	111	1.38	8.3	5.8	0.6	102	0.6	0.7	0.2	24	2.12	0.120	9
1090061	Soil	9.5	29.5	13.2	5	1.7	4.1	0.2	5	0.74	13.8	2.0	1.5	25	<0.1	2.1	0.2	18	0.09	0.181	3
REP 1090061	QC	9.9	29.4	12.7	6	1.6	4.2	0.2	5	0.72	13.7	1.8	1.5	26	<0.1	2.0	0.2	18	0.09	0.173	3
1090080	Soil	0.6	14.5	3.9	84	0.4	13.5	2.6	212	0.96	4.5	1.1	0.1	58	0.6	0.7	<0.1	19	1.40	0.141	11
REP 1090080	QC	0.6	14.4	3.9	86	0.4	13.9	2.4	214	0.93	4.4	0.5	<0.1	58	0.7	0.7	<0.1	18	1.43	0.142	11
1090093	Soil	19.4	29.7	20.5	174	0.9	42.9	3.9	61	1.67	56.4	18.7	0.9	75	1.2	14.0	0.2	108	0.54	0.103	6
REP 1090093	QC	20.7	30.3	20.7	182	0.9	44.9	3.8	62	1.77	58.0	20.1	1.1	81	1.3	15.5	0.2	115	0.55	0.101	8
1090116	Soil	25.4	12.3	74.9	9	1.0	2.0	0.3	14	1.03	54.9	6.8	4.9	23	<0.1	6.8	0.4	23	0.01	0.029	4
REP 1090116	QC	25.2	12.9	77.0	10	1.0	2.1	0.4	15	1.05	57.8	7.2	5.1	24	<0.1	7.0	0.4	23	<0.01	0.031	4
1090133	Soil	27.8	24.6	7.1	167	0.1	82.8	6.7	237	1.40	14.7	1.0	0.7	39	1.3	2.5	<0.1	37	0.61	0.080	6
REP 1090133	QC	29.4	25.3	6.9	176	0.1	84.1	6.8	243	1.46	14.8	0.9	0.8	38	1.3	2.6	<0.1	38	0.62	0.079	6
1090144	Soil	4.0	71.8	48.2	178	0.8	31.1	8.0	139	7.51	320.1	12.4	9.5	16	0.3	22.1	1.4	34	0.01	0.118	30
REP 1090144	QC	3.5	74.4	48.7	180	0.8	33.8	8.3	142	7.67	324.1	15.2	9.9	16	0.4	22.9	1.5	34	<0.01	0.118	30
1090170	Soil	14.2	28.1	17.4	136	0.3	42.2	5.9	55	1.75	30.4	3.6	0.2	17	0.3	3.3	0.2	57	0.03	0.059	12
REP 1090170	QC	15.6	29.7	18.3	143	0.3	46.5	6.2	57	1.83	31.8	4.0	0.2	18	0.2	3.5	0.2	60	0.03	0.061	12
1090184	Soil	4.4	10.8	76.8	57	5.7	10.0	2.2	35	1.34	244.9	144.6	4.0	23	0.5	111.1	4.8	24	0.01	0.049	30
REP 1090184	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090202	Soil	1.5	22.1	7.3	48	0.5	14.8	3.0	90	1.66	14.0	3.2	0.1	19	0.2	1.2	<0.1	18	0.07	0.064	2
REP 1090202	QC	1.5	22.8	7.4	50	0.5	14.9	3.1	91	1.61	13.7	2.5	0.2	19	0.2	1.3	<0.1	20	0.07	0.068	2
1090216	Soil	1.4	33.1	14.7	88	1.0	26.8	7.1	188	1.88	19.3	15.2	0.8	65	0.4	1.0	0.2	27	1.33	0.092	4
REP 1090216	QC	1.4	33.5	15.3	92	0.9	27.0	7.4	202	2.00	19.4	12.8	0.9	66	0.4	1.1	0.2	28	1.36	0.089	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000491.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1090014	Soil	22	1.01	554	0.003	8	1.50	0.004	0.09	0.6	1.27	5.1	16.3	<0.05	1	4.1	0.3	N.A.	N.A.	N.A.	N.A.
REP 1090014	QC	21	1.03	553	0.003	10	1.41	0.004	0.09	0.5	1.29	5.3	16.4	0.05	1	5.3	0.3				
1090020	Soil	9	0.03	75	0.001	3	0.32	0.003	0.04	0.2	0.08	0.5	0.5	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090020	QC	9	0.03	74	0.001	1	0.30	0.003	0.04	0.2	0.08	0.6	0.5	<0.05	1	0.7	<0.2				
1090043	Soil	12	0.02	130	0.006	2	0.37	0.005	0.06	0.2	0.55	1.3	0.1	<0.05	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090043	QC	13	0.02	137	0.010	3	0.38	0.006	0.06	0.2	0.26	1.4	0.1	<0.05	3	1.5	<0.2				
1090050	Soil	18	0.25	446	0.002	5	0.48	0.013	0.06	<0.1	0.25	1.9	0.1	0.18	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090050	QC	19	0.26	471	0.003	7	0.50	0.013	0.07	<0.1	0.22	2.1	0.1	0.28	2	1.5	<0.2				
1090061	Soil	10	<0.01	617	0.002	4	0.11	0.002	0.08	0.2	0.35	2.3	0.6	0.16	<1	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090061	QC	10	<0.01	616	0.002	3	0.11	0.002	0.08	0.2	0.32	2.3	0.6	0.15	<1	5.9	<0.2				
1090080	Soil	17	0.06	145	0.010	1	0.46	0.029	0.03	<0.1	0.12	0.8	<0.1	0.09	<1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090080	QC	17	0.06	148	0.010	<1	0.45	0.025	0.03	<0.1	0.11	0.7	<0.1	0.09	<1	1.3	<0.2				
1090093	Soil	19	0.02	378	<0.001	2	0.43	0.006	0.07	0.4	3.59	1.5	0.9	0.14	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090093	QC	19	0.02	424	0.001	1	0.46	0.006	0.08	0.4	3.32	2.0	0.9	0.18	2	5.6	0.2				
1090116	Soil	6	<0.01	440	0.001	4	0.19	<0.001	0.13	<0.1	3.49	1.4	0.6	0.24	1	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090116	QC	7	<0.01	442	0.001	3	0.20	0.001	0.13	<0.1	3.56	1.4	0.6	0.26	2	4.7	<0.2				
1090133	Soil	8	0.07	237	0.004	2	0.37	0.010	0.03	0.1	0.13	1.3	0.3	<0.05	<1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090133	QC	8	0.07	243	0.004	1	0.37	0.011	0.03	0.1	0.12	1.3	0.3	0.05	<1	1.4	<0.2				
1090144	Soil	21	0.34	121	0.003	1	1.03	0.003	0.11	0.5	4.01	3.6	0.6	0.20	3	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090144	QC	22	0.36	121	0.004	2	1.05	0.003	0.11	0.3	5.12	3.5	0.6	0.23	3	5.1	0.2				
1090170	Soil	10	0.03	737	0.002	2	0.38	0.003	0.07	0.1	0.10	0.4	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090170	QC	10	0.03	745	0.003	2	0.40	0.003	0.07	0.1	0.12	0.4	0.2	<0.05	2	0.8	<0.2				
1090184	Soil	13	0.02	88	0.004	5	0.44	0.005	0.09	1.0	>50	0.9	0.6	<0.05	2	15.1	0.4	N.A.	N.A.	N.A.	N.A.
REP 1090184	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1090202	Soil	14	0.03	87	0.006	<1	0.42	0.016	0.04	<0.1	0.54	0.9	<0.1	0.07	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090202	QC	15	0.03	94	0.009	<1	0.43	0.019	0.04	<0.1	0.55	1.1	<0.1	0.08	2	1.5	<0.2				
1090216	Soil	15	0.14	357	0.002	3	0.89	0.009	0.06	<0.1	0.76	2.1	0.1	0.10	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090216	QC	16	0.14	358	0.002	4	0.87	0.010	0.07	<0.1	0.77	2.3	0.1	0.07	2	2.9	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000491.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																					
1090014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090014	QC																				
1090020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090020	QC																				
1090043	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090043	QC																				
1090050	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090050	QC																				
1090061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090061	QC																				
1090080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090080	QC																				
1090093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090093	QC																				
1090116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090116	QC																				
1090133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090133	QC																				
1090144	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090144	QC																				
1090170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090170	QC																				
1090184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090184	QC																				
1090202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090202	QC																				
1090216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090216	QC																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000491.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1090014	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090014	QC													
1090020	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090020	QC													
1090043	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090043	QC													
1090050	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090050	QC													
1090061	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090061	QC													
1090080	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090080	QC													
1090093	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090093	QC													
1090116	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090116	QC													
1090133	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090133	QC													
1090144	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090144	QC													
1090170	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090170	QC													
1090184	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090184	QC													
1090202	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090202	QC													
1090216	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090216	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000491.2

		1DX30 Mo ppm 0.1	1DX30 Cu ppm 0.1	1DX30 Pb ppm 0.1	1DX30 Zn ppm 1	1DX30 Ag ppm 0.1	1DX30 Ni ppm 0.1	1DX30 Co ppm 0.1	1DX30 Mn ppm 1	1DX30 Fe % 0.01	1DX30 As ppm 0.5	1DX30 Au ppb 0.5	1DX30 Th ppm 0.1	1DX30 Sr ppm 1	1DX30 Cd ppm 0.1	1DX30 Sb ppm 0.1	1DX30 Bi ppm 0.1	1DX30 V ppm 2	1DX30 Ca % 0.01	1DX30 P % 0.001	1DX30 La ppm 1
1090248	Soil	86.6	31.9	21.2	32	4.7	11.3	1.1	35	1.55	123.9	20.6	0.6	59	0.1	32.4	0.2	433	0.02	0.096	15
REP 1090248	QC	91.2	32.4	21.7	34	4.7	10.3	1.1	36	1.59	125.4	25.4	0.7	62	0.3	33.7	0.3	504	0.02	0.096	19
1090263	Soil	36.8	29.1	6.5	114	<0.1	56.4	4.2	54	1.46	29.6	1.5	0.1	22	0.6	2.8	0.1	60	0.36	0.049	7
REP 1090263	QC	34.9	28.2	6.2	113	<0.1	55.5	4.2	54	1.47	28.1	1.4	0.1	22	0.6	2.8	0.1	58	0.37	0.046	7
1090407	Soil	5.0	43.0	18.6	181	0.5	27.9	9.5	457	2.92	81.5	14.9	1.1	56	0.5	5.6	0.4	29	0.03	0.060	3
REP 1090407	QC	5.1	44.6	19.1	190	0.5	29.1	9.6	452	2.92	84.1	13.6	1.3	58	0.5	5.7	0.5	29	0.01	0.063	3
1090418	Soil	13.3	28.3	46.4	91	1.1	20.0	4.6	131	2.16	40.8	7.3	0.4	63	0.2	5.7	0.4	73	0.06	0.097	7
REP 1090418	QC	13.5	28.4	47.5	92	1.1	20.2	4.9	130	2.19	40.6	6.9	0.4	65	0.2	5.8	0.3	72	0.06	0.095	7
1090438	Soil	3.3	30.8	13.6	135	0.8	47.3	7.4	85	2.51	13.1	2.8	0.7	20	0.4	0.9	0.2	35	0.01	0.055	4
REP 1090438	QC	3.1	31.3	13.7	133	0.8	49.6	7.6	86	2.55	13.0	1.9	0.7	20	0.3	0.9	0.2	34	0.01	0.058	4
Reference Materials																					
STD DS8	Standard	12.7	109.3	127.6	325	1.8	36.3	7.5	623	2.52	27.7	111.7	6.3	64	2.6	5.0	6.3	43	0.69	0.083	13
STD DS8	Standard	12.2	108.4	121.0	323	1.8	37.5	7.3	629	2.53	28.1	114.8	6.2	64	2.3	4.9	6.3	41	0.65	0.080	13
STD DS8	Standard	12.3	107.3	128.2	300	1.7	37.9	7.2	602	2.41	26.0	107.0	6.6	62	2.2	5.2	6.2	41	0.66	0.078	14
STD DS8	Standard	12.4	113.0	126.7	306	1.7	38.7	7.7	627	2.50	26.8	110.4	6.5	61	2.2	5.3	6.2	42	0.68	0.080	13
STD DS8	Standard	13.2	114.4	129.7	318	1.7	39.8	7.8	631	2.51	27.0	106.5	6.8	64	2.5	5.3	6.6	43	0.68	0.085	14
STD DS8	Standard	13.7	119.4	130.2	334	1.9	41.1	7.9	668	2.60	28.8	114.1	6.6	66	2.5	5.4	6.6	45	0.72	0.087	14
STD DS8	Standard	13.8	116.6	125.4	317	1.7	38.5	7.6	635	2.51	28.2	113.1	6.4	65	2.5	5.5	6.4	46	0.68	0.084	14
STD DS8	Standard	13.6	113.4	123.2	317	1.7	38.6	7.4	630	2.48	28.5	122.6	6.8	67	2.5	5.3	6.4	43	0.70	0.085	16
STD DS8	Standard	13.7	112.0	130.6	317	1.8	39.7	7.6	617	2.43	26.6	113.4	6.5	69	2.3	5.7	6.1	45	0.71	0.077	15
STD DS8	Standard	14.0	113.7	131.5	310	1.9	40.0	7.8	610	2.42	25.9	117.9	7.0	68	2.1	5.3	6.2	43	0.70	0.080	14
STD DS8	Standard	14.2	121.1	128.4	327	1.8	40.3	8.0	606	2.47	27.2	118.9	7.4	68	2.4	5.8	6.6	45	0.70	0.080	16
STD DS8	Standard	14.0	118.0	129.3	319	1.7	40.0	7.9	629	2.49	26.9	120.9	7.3	67	2.4	5.6	6.9	45	0.70	0.085	16
STD DS8	Standard	15.6	125.9	141.9	353	1.9	44.0	8.5	694	2.77	30.0	125.4	7.8	77	2.7	5.8	6.9	49	0.80	0.090	19
STD DS8	Standard	13.7	115.7	125.7	326	1.8	40.4	7.9	622	2.48	27.1	119.6	6.6	65	2.2	5.1	6.3	44	0.71	0.083	14
STD DS8	Standard	13.6	110.8	141.2	326	1.9	40.5	8.0	663	2.71	27.9	117.7	7.4	79	2.5	5.6	6.9	44	0.76	0.089	17
STD DS8	Standard	13.0	110.8	138.7	323	1.8	41.4	7.9	631	2.61	27.3	110.0	7.5	78	2.4	5.8	7.0	44	0.74	0.084	16
STD DS8	Standard	13.5	120.3	134.2	343	2.1	41.3	7.9	673	2.67	28.6	126.3	7.2	75	2.4	6.2	7.6	44	0.72	0.087	15
STD DS8	Standard	12.8	109.7	126.1	327	2.0	38.9	7.5	637	2.49	28.6	122.3	6.4	76	2.5	6.2	7.7	40	0.71	0.084	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000491.2

		1DX30 Cr ppm 1	1DX30 Mg % 0.01	1DX30 Ba ppm 1	1DX30 Ti % 0.001	1DX30 B ppm 1	1DX30 Al % 0.01	1DX30 Na % 0.001	1DX30 K % 0.01	1DX30 W ppm 0.1	1DX30 Hg ppm 0.01	1DX30 Sc ppm 0.1	1DX30 Tl ppm 0.1	1DX30 S % 0.05	1DX30 Ga ppm 1	1DX30 Se ppm 0.5	1DX30 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1090248	Soil	34	0.04	1047	0.006	3	0.46	0.002	0.14	0.5	13.12	1.1	1.9	0.14	5	23.9	0.4	N.A.	N.A.	N.A.	N.A.
REP 1090248	QC	38	0.04	1191	0.009	4	0.48	0.002	0.17	0.8	11.74	1.3	2.2	0.08	5	25.0	0.8				
1090263	Soil	9	0.05	166	0.004	3	0.41	0.012	0.03	0.2	0.06	0.4	0.9	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090263	QC	8	0.05	164	0.004	1	0.39	0.013	0.03	0.2	0.06	0.5	0.8	<0.05	2	1.6	<0.2				
1090407	Soil	9	0.02	276	0.001	3	0.33	0.001	0.08	<0.1	0.13	2.6	0.2	<0.05	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090407	QC	7	0.02	290	0.002	2	0.35	0.001	0.10	<0.1	0.16	2.8	0.3	<0.05	2	0.9	<0.2				
1090418	Soil	14	0.09	835	0.006	4	0.58	0.003	0.10	0.1	0.32	1.3	0.6	0.15	3	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090418	QC	15	0.09	836	0.007	3	0.60	0.004	0.10	0.2	0.32	1.3	0.5	0.15	3	4.7	<0.2				
1090438	Soil	14	0.04	137	0.003	1	0.53	0.003	0.04	<0.1	0.05	1.2	<0.1	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090438	QC	14	0.04	140	0.003	1	0.55	0.003	0.04	<0.1	0.07	1.3	<0.1	<0.05	3	1.9	<0.2				
Reference Materials																					
STD DS8	Standard	115	0.64	262	0.110	4	0.89	0.090	0.42	3.0	0.21	2.1	5.6	0.15	5	5.2	5.0				
STD DS8	Standard	113	0.59	260	0.102	4	0.85	0.089	0.43	2.8	0.22	2.1	5.4	0.14	5	5.8	5.3				
STD DS8	Standard	114	0.59	267	0.111	3	0.87	0.090	0.40	3.0	0.21	2.2	5.3	0.17	5	5.6	4.9				
STD DS8	Standard	116	0.59	265	0.109	3	0.87	0.087	0.41	2.8	0.23	2.1	5.3	0.16	5	4.7	5.1				
STD DS8	Standard	119	0.62	289	0.113	5	0.89	0.090	0.41	3.0	0.17	2.1	5.6	0.17	5	5.5	5.3				
STD DS8	Standard	127	0.64	293	0.119	5	0.95	0.093	0.44	3.0	0.11	2.2	5.7	0.16	5	5.3	5.4				
STD DS8	Standard	118	0.59	269	0.111	3	0.90	0.088	0.42	3.1	0.23	2.2	5.4	0.14	5	5.7	5.3				
STD DS8	Standard	116	0.62	276	0.114	3	0.93	0.098	0.42	2.8	0.23	2.2	5.5	0.18	5	5.5	5.3				
STD DS8	Standard	121	0.64	281	0.122	2	0.95	0.077	0.42	3.0	0.20	1.8	5.3	0.17	5	5.8	4.5				
STD DS8	Standard	120	0.63	283	0.120	3	0.93	0.075	0.42	3.0	0.22	1.8	5.5	0.15	4	5.5	4.4				
STD DS8	Standard	124	0.64	274	0.133	3	0.92	0.089	0.40	3.0	0.23	2.1	5.4	0.21	5	5.0	4.8				
STD DS8	Standard	123	0.63	264	0.131	3	0.94	0.084	0.40	2.8	0.18	2.2	5.3	0.19	5	4.7	5.1				
STD DS8	Standard	134	0.70	284	0.131	3	1.08	0.104	0.47	3.2	0.19	2.5	5.9	0.18	5	6.2	5.6				
STD DS8	Standard	123	0.63	260	0.113	<1	0.92	0.087	0.42	3.0	0.20	2.1	5.5	0.15	5	4.5	5.5				
STD DS8	Standard	126	0.66	301	0.132	3	1.00	0.101	0.45	2.8	0.21	2.1	5.6	0.11	5	6.3	5.8				
STD DS8	Standard	122	0.65	295	0.124	2	0.99	0.096	0.44	2.9	0.25	2.0	5.3	0.11	5	6.3	5.8				
STD DS8	Standard	125	0.66	307	0.136	3	0.93	0.090	0.44	3.3	0.21	2.2	6.3	0.22	5	6.2	5.7				
STD DS8	Standard	113	0.62	307	0.123	2	0.90	0.088	0.42	3.1	0.19	2.2	6.2	0.20	5	6.4	5.4				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000491.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1090248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090248	QC																				
1090263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090263	QC																				
1090407	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090407	QC																				
1090418	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090418	QC																				
1090438	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090438	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000491.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1090248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090248	QC												
1090263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090263	QC												
1090407	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090407	QC												
1090418	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090418	QC												
1090438	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090438	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000491.2

		1DX30 Mo ppm 0.1	1DX30 Cu ppm 0.1	1DX30 Pb ppm 0.1	1DX30 Zn ppm 1	1DX30 Ag ppm 0.1	1DX30 Ni ppm 0.1	1DX30 Co ppm 0.1	1DX30 Mn ppm 1	1DX30 Fe % 0.01	1DX30 As ppm 0.5	1DX30 Au ppb 0.5	1DX30 Th ppm 0.1	1DX30 Sr ppm 1	1DX30 Cd ppm 0.1	1DX30 Sb ppm 0.1	1DX30 Bi ppm 0.1	1DX30 V ppm 2	1DX30 Ca % 0.01	1DX30 P % 0.001	1DX30 La ppm 1
STD DS8	Standard	13.8	113.1	126.6	322	1.9	39.9	8.1	630	2.49	28.2	120.6	6.6	64	2.3	5.7	6.9	43	0.70	0.085	14
STD DS8	Standard	13.4	111.0	124.0	318	1.9	39.9	7.9	626	2.52	28.6	112.7	6.5	62	2.5	5.4	6.5	43	0.70	0.086	14
STD DS8	Standard	11.6	104.5	131.8	288	1.7	37.2	7.4	591	2.36	24.2	107.4	6.1	66	2.1	5.4	6.0	40	0.67	0.072	13
STD DS8	Standard	12.2	105.7	135.4	303	1.7	38.2	7.5	592	2.44	24.7	104.7	6.6	68	2.3	5.9	6.5	42	0.67	0.079	14
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.03	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000491.2

		1DX30 Cr ppm 1	1DX30 Mg % 0.01	1DX30 Ba ppm 1	1DX30 Ti % 0.001	1DX30 B ppm 1	1DX30 Al % 0.01	1DX30 Na % 0.001	1DX30 K % 0.01	1DX30 W ppm 0.1	1DX30 Hg ppm 0.01	1DX30 Sc ppm 0.1	1DX30 Tl ppm 0.1	1DX30 S % 0.05	1DX30 Ga ppm 1	1DX30 Se ppm 0.5	1DX30 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
STD DS8	Standard	122	0.64	289	0.112	3	0.92	0.089	0.44	3.2	0.23	2.1	5.6	0.13	5	5.6	5.1				
STD DS8	Standard	121	0.64	278	0.112	2	0.92	0.087	0.45	3.0	0.20	2.2	5.3	0.15	5	5.6	4.8				
STD DS8	Standard	117	0.56	259	0.116	2	0.82	0.080	0.39	2.9	0.22	1.8	5.2	0.15	4	4.9	4.7				
STD DS8	Standard	120	0.57	265	0.124	2	0.86	0.080	0.40	2.9	0.19	2.0	4.9	0.23	4	5.6	5.1				
STD DS8	Standard																	14.0	117.3	126.8	318
STD OREAS45CA	Standard																	0.9	488.6	19.7	59
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000491.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.8	39.4	8.1	635	2.63	26.5	96.8	6.8	71	2.4	4.8	6.4	45	0.75	0.089	15	116	0.65	304	0.118
STD OREAS45CA	Standard	0.3	244.6	87.8	897	16.02	4.1	39.3	6.6	15	<0.1	<0.1	0.2	187	0.41	0.039	15	659	0.15	151	0.144
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000491.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.99	0.096	0.44	3.0	0.21	2.4	5.5	0.17	5	6.3	5.3
STD OREAS45CA	Standard	<20	4.00	0.013	0.07	<0.1	0.01	39.0	<0.1	<0.05	18	0.6	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 07, 2011
Report Date: August 19, 2011
Page: 1 of 4

CERTIFICATE OF ANALYSIS WHI11000492.3

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #1
P.O. Number
Number of Samples: 73

SAMPLE DISPOSAL

RTRN-PLP Return
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	69	Dry at 60C			WHI
SS80	69	Dry at 60C sieve 100g to -80 mesh			WHI
1DX3	69	1:1:1 Aqua Regia digestion ICP-MS analysis	30	Completed	VAN
3B01	19	Fire assay fusion Au by ICP-ES	30	Completed	VAN

ADDITIONAL COMMENTS

Version 2: Includes corrected Shipment #

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 19, 2011

CERTIFICATE OF ANALYSIS WHI11000492.3

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090466	Soil	104.4	178.2	19.2	2449	4.6	372.6	9.8	174	2.34	121.3	3.7	1.7	108	46.8	54.5	0.2	1070	2.52	0.159	15
1090468	Soil	43.5	36.1	24.9	167	1.6	26.4	1.2	20	1.15	43.4	8.2	0.3	33	2.2	11.2	0.3	171	0.06	0.095	7
1090470	Soil	42.7	27.8	31.7	51	1.3	6.4	0.9	16	1.94	64.1	17.3	1.2	50	0.4	13.2	0.4	135	0.01	0.071	6
1090471	Soil	47.6	20.2	31.3	42	1.6	6.0	0.6	18	1.94	63.1	15.6	0.6	43	0.3	10.5	0.3	142	0.01	0.079	5
1090472	Soil	18.6	9.6	24.8	36	0.9	5.6	0.6	10	1.06	30.7	18.6	0.8	21	0.2	5.4	0.3	79	0.01	0.045	4
1090473	Soil	10.3	17.1	23.6	66	0.6	8.5	2.1	37	1.47	24.9	9.5	1.4	24	0.3	5.0	0.2	51	<0.01	0.045	3
1090474	Soil	9.6	22.8	34.1	63	0.7	9.3	2.2	33	1.78	29.4	6.4	2.5	41	0.4	5.4	0.3	35	0.01	0.034	3
1090477	Soil	7.9	41.1	27.1	157	0.8	27.6	7.0	211	2.26	44.5	3.8	0.7	23	0.5	4.7	0.3	54	0.02	0.101	3
1091001	Soil	7.7	22.4	23.8	160	1.0	25.9	5.7	64	3.90	86.5	13.9	0.7	49	0.7	10.2	0.4	50	0.01	0.114	5
1091002	Soil	6.8	18.2	28.4	145	0.6	19.3	4.6	85	2.77	347.2	17.9	0.9	62	0.3	11.8	0.3	46	0.02	0.076	7
1091003	Soil	3.6	27.7	22.1	165	0.3	27.4	6.9	141	3.22	99.3	4.6	1.3	57	0.7	6.3	0.3	27	<0.01	0.065	7
1091004	Soil	4.0	42.3	33.5	209	0.9	26.6	8.5	137	4.10	49.9	4.2	0.9	26	0.6	3.2	0.3	29	<0.01	0.084	5
1091005	Soil	3.0	18.8	14.8	98	0.5	17.1	4.4	80	1.82	36.4	5.7	0.3	28	0.6	3.3	0.2	29	0.03	0.071	7
1091006	Soil	5.7	47.9	55.3	108	2.7	15.5	4.8	45	7.94	1456	244.2	3.5	24	0.1	51.5	8.3	33	<0.01	0.134	16
1091007	Soil	12.1	95.8	70.3	154	4.4	15.9	3.8	65	11.16	1441	168.7	3.0	23	0.5	78.4	4.0	63	0.01	0.195	19
1091008	Soil	3.3	32.7	21.9	63	0.6	8.0	2.3	95	4.23	392.5	12.2	1.5	14	0.2	11.4	0.6	45	0.02	0.122	18
1091009	Soil	6.3	65.1	50.4	114	1.4	19.0	4.4	122	6.36	663.6	32.2	4.5	31	0.4	22.3	1.2	53	0.02	0.146	20
1091010	Soil	5.8	59.8	57.9	112	2.3	12.9	3.6	186	7.56	447.3	16.5	4.7	26	0.5	15.7	0.9	62	0.01	0.146	18
1091011	Soil	8.0	118.4	44.7	126	2.1	15.0	3.6	220	13.62	1470	30.1	12.0	42	0.7	31.3	3.1	93	0.01	0.328	16
1091012	Soil	9.8	49.1	34.8	124	0.8	24.2	6.2	166	4.65	353.2	23.6	2.3	49	0.6	13.2	0.6	73	0.02	0.106	13
1091013	Soil	7.3	251.5	49.5	116	1.8	17.1	3.6	114	17.44	1023	47.6	3.7	30	0.9	32.1	5.7	165	0.01	0.282	11
1091014	Soil	6.8	143.4	29.2	119	0.9	24.0	6.3	144	9.24	677.9	45.5	4.8	38	0.3	14.2	2.6	90	0.03	0.209	14
1091015	Soil	5.3	90.5	50.1	101	1.7	18.4	4.6	106	8.43	1078	154.5	4.5	100	0.3	35.6	6.6	132	0.02	0.253	14
1091016	Soil	7.2	73.7	30.8	127	0.9	24.3	6.9	189	5.35	454.9	31.8	2.9	60	0.5	18.7	3.5	72	0.03	0.126	18
1091017	Soil	5.4	47.2	29.6	80	0.6	14.0	3.7	103	3.01	314.0	21.2	1.7	34	0.5	8.6	2.2	42	0.04	0.081	14
1091018	Soil	6.7	56.8	32.4	87	1.1	15.1	3.5	75	3.21	410.2	39.1	1.4	33	0.6	12.8	4.9	52	0.04	0.118	14
1091019	Soil	15.5	62.5	73.7	126	3.0	14.7	3.6	65	4.50	798.3	202.8	1.5	71	0.6	39.5	3.2	64	0.04	0.162	18
1091020	Soil	6.5	27.0	17.2	91	0.7	18.7	3.0	41	1.52	76.7	15.9	0.7	27	<0.1	6.5	0.3	48	0.01	0.055	13
1091031	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1091032	Soil	11.1	39.2	21.7	188	0.8	45.6	10.9	312	2.12	61.9	12.1	2.0	38	0.5	6.8	0.4	81	0.34	0.101	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 19, 2011

CERTIFICATE OF ANALYSIS WHI11000492.3

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	3B
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Au
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppb
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	2
1090466	Soil	74	1.15	572	0.005	9	0.69	0.005	0.17	0.5	1.20	4.3	5.2	<0.05	3	18.4	0.3	N.A.
1090468	Soil	15	0.03	372	0.002	5	0.32	0.001	0.10	0.3	4.15	0.8	1.7	0.12	2	5.5	<0.2	N.A.
1090470	Soil	11	0.01	379	0.001	3	0.26	0.003	0.17	0.3	6.58	0.7	1.3	0.32	2	8.6	<0.2	N.A.
1090471	Soil	12	0.01	373	0.001	4	0.20	0.003	0.18	0.3	4.78	0.5	1.6	0.36	2	10.1	0.2	N.A.
1090472	Soil	7	0.01	178	<0.001	3	0.18	0.002	0.12	0.1	2.63	0.3	0.7	0.19	1	4.2	<0.2	N.A.
1090473	Soil	7	0.01	166	<0.001	2	0.23	0.002	0.09	<0.1	0.99	0.8	0.5	0.13	1	3.3	<0.2	N.A.
1090474	Soil	7	<0.01	199	<0.001	2	0.24	0.001	0.10	<0.1	0.37	1.3	0.4	0.13	<1	3.8	<0.2	N.A.
1090477	Soil	14	0.02	186	0.002	4	0.48	0.006	0.09	<0.1	0.30	1.9	0.3	0.06	2	1.4	<0.2	N.A.
1091001	Soil	9	0.01	974	0.003	3	0.40	0.002	0.09	<0.1	3.81	1.5	0.7	0.14	1	6.3	<0.2	N.A.
1091002	Soil	8	0.01	726	<0.001	4	0.28	0.002	0.08	0.1	1.37	1.3	0.6	0.14	<1	2.2	0.2	N.A.
1091003	Soil	9	0.02	516	0.002	2	0.35	0.002	0.07	<0.1	0.97	2.2	0.3	<0.05	<1	1.6	<0.2	12
1091004	Soil	10	0.02	272	<0.001	2	0.39	0.003	0.06	<0.1	0.25	3.3	0.3	0.06	<1	0.8	<0.2	7
1091005	Soil	6	0.02	445	0.002	2	0.39	0.007	0.05	<0.1	1.47	1.0	0.2	0.05	1	1.3	<0.2	6
1091006	Soil	11	0.03	156	0.003	2	0.42	0.004	0.10	1.2	7.92	1.1	1.7	0.15	2	14.1	0.2	455
1091007	Soil	24	0.09	195	0.007	2	0.87	0.005	0.11	1.9	20.06	1.6	1.2	0.17	4	18.3	0.4	217
1091008	Soil	16	0.10	122	0.006	1	0.69	0.007	0.07	0.3	1.17	1.0	0.2	0.14	3	1.1	0.2	35
1091009	Soil	20	0.16	229	0.004	3	1.05	0.003	0.08	0.2	2.89	1.8	0.5	0.17	4	4.5	0.2	52
1091010	Soil	26	0.20	184	0.006	<1	1.41	0.002	0.07	0.3	2.43	1.8	0.4	0.16	4	3.8	<0.2	20
1091011	Soil	41	0.34	164	0.005	1	1.65	0.004	0.07	1.5	1.86	3.6	0.7	0.32	6	7.6	0.4	38
1091012	Soil	16	0.13	266	0.004	2	0.81	0.004	0.08	0.3	5.15	1.5	0.6	0.18	2	5.7	<0.2	39
1091013	Soil	52	0.26	185	0.014	2	1.26	0.005	0.12	0.9	3.51	4.6	0.9	0.44	6	18.3	0.4	57
1091014	Soil	28	0.22	190	0.008	2	1.12	0.012	0.12	3.3	1.97	3.2	0.9	0.30	4	6.3	<0.2	58
1091015	Soil	40	0.24	243	0.017	1	0.80	0.014	0.23	5.8	4.52	2.9	1.7	0.51	5	9.6	0.3	177
1091016	Soil	22	0.24	251	0.008	2	1.01	0.005	0.13	1.8	6.51	2.1	1.1	0.26	3	5.6	0.3	55
1091017	Soil	10	0.14	194	0.004	2	1.07	0.009	0.08	0.7	2.81	0.9	0.4	0.17	3	2.5	<0.2	34
1091018	Soil	13	0.11	186	0.007	<1	0.96	0.008	0.09	1.6	4.17	1.3	0.6	0.26	3	3.2	<0.2	46
1091019	Soil	15	0.08	277	0.003	4	0.72	0.011	0.15	1.5	13.78	1.0	2.8	0.40	2	10.9	<0.2	287
1091020	Soil	8	0.02	175	0.003	2	0.29	0.004	0.05	0.3	1.73	0.8	0.5	0.11	2	2.1	0.2	16
1091031	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1091032	Soil	18	0.10	494	0.003	7	0.59	0.006	0.08	0.2	1.88	2.4	0.3	<0.05	2	4.5	0.2	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 19, 2011

CERTIFICATE OF ANALYSIS WHI11000492.3

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091033	Soil	2.1	50.7	13.4	158	1.3	39.3	8.4	209	2.58	20.9	10.5	1.6	59	0.8	2.3	0.3	36	1.02	0.091	5
1091034	Soil	2.6	23.2	11.6	126	0.8	25.7	5.1	137	1.55	34.5	10.7	0.8	56	0.6	3.5	0.2	51	1.24	0.092	5
1091035	Soil	4.3	43.6	13.4	138	0.9	32.9	8.0	150	2.42	25.0	7.6	1.9	54	0.4	3.3	0.2	50	0.70	0.074	6
1091036	Soil	2.0	15.9	8.0	85	0.2	20.0	6.4	139	1.62	10.3	3.6	1.6	32	0.3	1.2	0.1	28	0.36	0.047	5
1091037	Soil	3.3	34.0	10.1	121	1.0	28.8	5.6	124	1.62	18.2	7.8	1.3	31	1.5	2.1	0.2	41	0.32	0.054	6
1091038	Soil	13.7	22.8	24.1	137	0.4	29.5	2.9	37	1.23	26.2	2.4	0.1	23	0.3	4.9	0.3	125	0.06	0.057	12
1091039	Soil	13.4	17.9	18.4	126	0.4	28.1	3.2	38	1.30	31.7	2.7	0.7	12	0.2	5.5	0.3	137	0.01	0.079	8
1091040	Soil	10.7	33.9	17.0	183	0.8	35.7	5.6	125	1.70	35.1	5.6	0.3	34	1.6	5.4	0.3	93	0.07	0.103	10
1091051	Soil	1.4	4.9	2.8	19	0.7	3.9	1.0	18	0.41	5.3	1.3	<0.1	7	0.2	0.6	<0.1	22	0.03	0.058	2
1091058	Soil	16.8	24.0	21.2	237	0.7	44.8	4.4	62	1.79	69.4	7.7	0.2	29	1.6	8.5	0.5	136	0.03	0.096	12
1091072	Soil	132.7	232.3	10.7	2341	0.6	442.1	26.1	242	6.51	215.5	7.3	3.9	40	50.8	31.5	0.2	227	0.15	0.133	13
1091075	Soil	31.5	40.0	56.5	68	3.6	12.3	1.7	46	2.16	199.7	47.1	3.0	194	0.5	31.8	0.4	211	0.12	0.355	13
1091021	Soil	4.2	21.6	7.4	33	1.1	5.0	1.0	21	1.39	120.4	1.9	<0.1	5	0.3	5.9	0.2	44	0.03	0.047	12
1091022	Soil	2.5	77.7	14.8	83	0.8	14.1	3.3	23	1.61	61.8	2.0	0.5	15	0.4	2.2	0.3	32	0.01	0.073	7
1091023	Soil	4.1	23.0	18.2	93	0.3	17.9	4.6	59	1.92	53.4	1.9	0.2	14	0.2	3.3	0.4	62	0.02	0.059	6
1091025	Soil	3.6	59.4	19.4	172	0.8	40.1	8.9	259	4.15	67.9	7.4	1.1	22	0.2	3.2	0.4	30	0.01	0.090	4
1091027	Soil	8.2	29.4	26.0	108	1.9	21.6	3.3	46	1.74	131.9	59.6	0.6	31	0.6	27.6	0.8	41	0.04	0.086	9
1091028	Soil	1.0	41.5	8.4	31	1.6	20.1	3.6	191	1.07	14.0	8.4	0.5	62	0.3	1.6	0.2	16	1.30	0.078	4
1091029	Soil	2.5	46.7	7.1	59	2.2	19.9	9.3	124	0.92	29.0	19.8	0.6	46	0.4	3.5	0.2	22	0.72	0.078	4
1091031	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1091151	Soil	23.4	39.9	20.3	256	0.5	60.9	7.1	111	2.91	113.9	9.9	2.1	52	0.8	14.1	0.8	105	0.16	0.156	13
1091152	Soil	45.9	17.1	7.1	170	<0.1	62.3	3.7	25	1.15	21.2	1.7	0.3	6	0.2	4.4	0.1	101	0.02	0.026	12
1091153	Soil	21.7	20.3	10.2	168	0.2	45.0	3.6	52	1.22	31.9	3.1	0.1	21	0.5	5.3	0.2	68	0.11	0.067	8
1091154	Soil	37.4	67.3	14.9	448	0.5	127.9	11.1	244	2.82	35.0	2.2	2.1	25	3.2	7.4	0.2	72	0.26	0.127	15
1091155	Soil	20.2	20.6	6.2	153	0.1	42.1	3.6	50	1.05	15.7	1.1	0.1	16	0.7	3.5	0.1	53	0.34	0.042	7
1091156	Soil	38.8	63.0	15.5	434	1.2	142.8	10.6	279	2.88	44.9	3.2	1.4	49	5.0	7.6	0.2	89	0.89	0.143	12
1091157	Soil	17.9	26.0	7.2	188	0.3	52.3	4.8	102	1.31	20.2	1.3	0.9	36	1.8	4.6	0.1	60	0.73	0.052	7
1091158	Soil	14.7	35.7	16.2	773	0.9	96.7	13.8	654	2.81	57.2	12.8	1.0	29	3.9	6.8	0.5	109	0.14	0.138	11
1091159	Soil	5.4	28.8	7.9	1438	0.6	148.5	6.3	319	1.30	34.8	6.8	0.7	57	22.3	4.0	0.3	56	1.00	0.090	6
1091171	Soil	26.0	32.0	19.1	322	0.3	75.3	6.7	97	2.50	87.6	8.0	0.3	43	0.7	10.6	0.5	122	0.03	0.077	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 19, 2011

CERTIFICATE OF ANALYSIS WHI11000492.3

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	3B
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Au
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppb
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	2
1091033	Soil	32	0.25	1155	0.003	6	1.16	0.007	0.12	<0.1	0.60	3.2	0.1	<0.05	3	1.4	<0.2	7
1091034	Soil	19	0.10	556	0.002	4	0.75	0.006	0.05	0.2	1.04	1.6	0.2	<0.05	2	1.5	<0.2	N.A.
1091035	Soil	24	0.27	877	0.002	4	1.05	0.006	0.06	<0.1	0.56	2.7	0.2	<0.05	3	1.5	<0.2	N.A.
1091036	Soil	19	0.30	1050	0.003	3	0.88	0.010	0.05	<0.1	0.16	1.3	<0.1	<0.05	2	1.3	<0.2	N.A.
1091037	Soil	18	0.20	833	0.002	3	0.93	0.011	0.06	<0.1	0.42	1.9	0.2	<0.05	2	1.1	<0.2	N.A.
1091038	Soil	13	0.03	238	0.005	3	0.44	0.002	0.07	0.2	0.29	0.4	0.6	<0.05	4	1.8	<0.2	N.A.
1091039	Soil	11	0.02	139	0.004	1	0.36	0.004	0.05	0.2	0.11	0.8	0.6	<0.05	3	1.8	<0.2	N.A.
1091040	Soil	17	0.07	510	0.004	3	0.68	0.007	0.08	0.2	0.43	0.9	0.6	<0.05	3	1.9	<0.2	N.A.
1091051	Soil	3	0.02	68	0.002	1	0.20	0.015	0.02	<0.1	0.22	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.
1091058	Soil	12	0.04	299	0.005	3	0.52	0.005	0.08	0.4	0.35	0.3	0.5	<0.05	3	2.8	<0.2	N.A.
1091072	Soil	20	0.05	784	0.003	4	1.18	0.001	0.06	0.8	19.28	4.0	3.5	<0.05	<1	48.0	<0.2	N.A.
1091075	Soil	27	0.01	730	0.003	6	0.44	0.004	0.14	0.6	8.64	3.9	1.5	0.17	2	17.8	0.4	N.A.
1091021	Soil	5	0.01	67	0.003	2	0.17	0.007	0.03	0.1	0.30	0.1	0.2	<0.05	1	1.8	<0.2	N.A.
1091022	Soil	8	<0.01	126	0.002	3	0.43	0.006	0.04	0.1	0.44	1.1	0.2	<0.05	2	1.1	<0.2	N.A.
1091023	Soil	8	0.02	77	0.004	1	0.43	0.005	0.04	0.2	0.27	0.5	0.1	<0.05	5	0.8	<0.2	N.A.
1091025	Soil	9	0.02	145	0.001	3	0.45	0.003	0.05	<0.1	0.23	1.7	0.1	<0.05	2	3.0	<0.2	N.A.
1091027	Soil	12	0.02	213	0.002	2	0.35	0.006	0.07	0.3	14.48	0.9	0.6	0.05	2	7.4	<0.2	N.A.
1091028	Soil	7	0.06	393	0.004	3	0.52	0.015	0.03	<0.1	0.55	2.0	<0.1	0.06	1	3.2	<0.2	N.A.
1091029	Soil	8	0.09	352	0.002	2	0.47	0.011	0.04	0.1	1.29	2.1	0.1	0.05	1	2.5	<0.2	N.A.
1091031	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1091151	Soil	14	0.09	262	0.003	2	0.62	0.003	0.08	0.4	0.82	1.8	0.7	0.08	2	2.9	<0.2	N.A.
1091152	Soil	6	0.02	70	0.003	1	0.29	0.003	0.04	0.2	0.06	0.5	0.4	<0.05	2	1.1	<0.2	N.A.
1091153	Soil	9	0.04	197	0.003	2	0.39	0.005	0.05	0.2	0.15	0.4	0.5	<0.05	2	1.7	<0.2	N.A.
1091154	Soil	14	0.05	311	0.002	2	0.45	0.001	0.05	0.1	0.27	2.9	0.6	<0.05	<1	2.7	<0.2	N.A.
1091155	Soil	7	0.05	377	0.002	1	0.36	0.006	0.04	<0.1	0.06	0.5	0.4	<0.05	2	1.0	<0.2	N.A.
1091156	Soil	23	0.27	454	0.003	3	0.52	0.004	0.06	0.1	0.49	4.9	1.0	<0.05	<1	3.0	<0.2	N.A.
1091157	Soil	10	0.12	403	0.003	2	0.41	0.006	0.04	<0.1	0.10	1.6	0.3	<0.05	1	1.2	<0.2	N.A.
1091158	Soil	21	0.14	561	0.003	1	0.97	0.003	0.06	0.3	1.97	2.1	1.2	<0.05	3	1.9	<0.2	N.A.
1091159	Soil	12	0.15	558	0.005	3	0.60	0.010	0.05	0.1	1.13	1.3	0.4	<0.05	2	1.6	<0.2	N.A.
1091171	Soil	13	0.04	240	0.003	2	0.46	0.002	0.07	0.3	0.37	0.7	0.6	<0.05	2	2.7	<0.2	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 19, 2011

CERTIFICATE OF ANALYSIS WHI11000492.3

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091174	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1091175	Soil	9.7	23.7	24.7	204	0.6	39.7	3.8	35	1.99	42.2	3.5	0.5	118	0.3	5.8	0.3	38	0.01	0.089	12
1091176	Soil	14.6	31.1	17.4	221	0.9	47.3	4.3	51	2.00	41.4	2.7	0.1	46	0.5	5.1	0.3	78	0.02	0.080	9
1091178	Soil	49.1	36.6	86.0	118	5.6	19.6	2.1	29	3.17	34.0	4.7	0.2	144	1.0	5.9	0.5	141	0.02	0.140	8
1091179	Soil	9.6	41.1	10.1	374	0.7	74.5	9.1	253	2.84	27.4	4.1	0.9	10	1.4	5.0	0.2	28	0.09	0.092	12
1091180	Soil	4.9	70.6	16.4	1479	1.4	166.7	27.5	468	5.50	41.3	4.5	2.5	5	1.3	5.7	0.3	15	0.03	0.068	15
1091185	Soil	185.2	172.7	22.0	2301	3.0	490.7	9.2	159	2.86	115.1	11.6	1.9	122	20.7	46.0	0.3	1457	2.41	0.204	26
1091188	Soil	32.9	38.7	25.1	419	0.7	98.2	8.8	151	3.71	77.0	11.3	1.0	43	0.7	14.1	0.3	181	0.10	0.145	13
1091189	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1091190	Soil	86.0	45.0	28.1	168	2.2	36.7	3.1	50	2.77	118.2	11.2	2.0	235	4.2	49.0	0.4	256	0.08	0.097	13
1091191	Soil	43.9	32.0	15.9	79	1.6	20.4	1.5	16	1.09	53.9	8.2	0.3	91	0.6	28.3	0.2	183	0.02	0.081	10
1091199	Soil	22.4	34.9	30.0	206	0.8	41.6	4.8	107	1.86	92.0	30.4	1.4	46	0.7	21.9	0.3	110	0.03	0.081	12
1091186	Soil	88.9	152.1	13.6	2157	2.2	328.7	14.9	411	2.87	87.6	13.3	1.1	78	43.7	16.8	0.2	349	1.38	0.118	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 19, 2011

CERTIFICATE OF ANALYSIS WHI11000492.3

Method		1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	3B
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Au
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppb
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	2
1091174	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1091175	Soil	7	0.02	363	0.003	1	0.34	0.002	0.10	<0.1	0.06	1.0	0.3	0.09	1	2.5	<0.2	N.A.
1091176	Soil	10	0.02	396	0.002	1	0.40	0.004	0.09	0.1	0.21	0.3	0.4	0.12	2	2.4	<0.2	N.A.
1091178	Soil	20	0.02	125	0.004	2	0.29	0.006	0.46	0.3	0.25	0.3	3.0	0.89	2	7.5	0.4	N.A.
1091179	Soil	9	0.03	293	0.002	1	0.32	0.001	0.04	<0.1	0.18	1.9	0.2	<0.05	<1	2.7	<0.2	N.A.
1091180	Soil	11	0.02	507	<0.001	2	0.32	<0.001	0.05	<0.1	0.67	4.4	0.4	<0.05	<1	8.9	<0.2	N.A.
1091185	Soil	89	0.87	563	0.006	11	1.12	0.005	0.22	0.5	1.34	5.1	3.7	0.10	4	8.7	<0.2	N.A.
1091188	Soil	20	0.06	179	0.004	2	0.54	0.003	0.06	0.3	0.23	1.1	1.1	0.07	2	5.6	<0.2	N.A.
1091189	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1091190	Soil	29	0.03	604	0.003	1	0.44	0.005	0.16	2.1	3.38	1.8	12.1	0.41	3	20.1	0.4	N.A.
1091191	Soil	18	0.02	258	0.002	2	0.32	0.004	0.07	1.0	2.00	0.4	3.2	0.14	2	26.4	<0.2	N.A.
1091199	Soil	11	0.02	233	0.002	1	0.33	0.002	0.05	0.4	3.84	1.0	1.1	0.06	1	5.2	<0.2	N.A.
1091186	Soil	32	0.31	757	0.005	3	1.36	0.009	0.05	0.6	1.15	3.4	2.2	0.08	1	4.7	<0.2	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 19, 2011

QUALITY CONTROL REPORT WHI11000492.3

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1091014	Soil	6.8	143.4	29.2	119	0.9	24.0	6.3	144	9.24	677.9	45.5	4.8	38	0.3	14.2	2.6	90	0.03	0.209	14
REP 1091014	QC																				
1091017	Soil	5.4	47.2	29.6	80	0.6	14.0	3.7	103	3.01	314.0	21.2	1.7	34	0.5	8.6	2.2	42	0.04	0.081	14
REP 1091017	QC	5.3	48.1	29.1	83	0.6	14.7	3.6	99	2.79	311.6	24.4	1.8	33	0.4	9.1	2.2	43	0.05	0.078	14
1091040	Soil	10.7	33.9	17.0	183	0.8	35.7	5.6	125	1.70	35.1	5.6	0.3	34	1.6	5.4	0.3	93	0.07	0.103	10
REP 1091040	QC	10.8	35.8	17.4	187	0.8	35.7	5.7	128	1.81	35.2	6.1	0.6	35	1.5	5.7	0.3	93	0.07	0.105	10
1091159	Soil	5.4	28.8	7.9	1438	0.6	148.5	6.3	319	1.30	34.8	6.8	0.7	57	22.3	4.0	0.3	56	1.00	0.090	6
REP 1091159	QC	5.5	28.7	8.6	1481	0.6	151.8	6.8	337	1.37	37.1	10.2	0.9	58	21.4	4.3	0.3	56	1.00	0.094	7
1091188	Soil	32.9	38.7	25.1	419	0.7	98.2	8.8	151	3.71	77.0	11.3	1.0	43	0.7	14.1	0.3	181	0.10	0.145	13
REP 1091188	QC	32.3	39.2	24.8	430	0.7	102.6	8.7	154	3.77	78.3	9.1	1.0	43	0.6	13.7	0.3	184	0.10	0.147	13
Reference Materials																					
STD DS8	Standard	12.3	98.9	121.4	290	1.9	35.0	6.6	564	2.24	24.8	143.5	5.9	62	2.0	5.7	5.9	32	0.62	0.075	13
STD DS8	Standard	12.0	101.8	123.9	308	1.8	34.7	7.1	582	2.29	24.5	115.9	6.1	63	1.9	5.6	6.0	40	0.64	0.075	13
STD DS8	Standard	12.6	112.8	121.2	332	2.0	40.1	7.7	622	2.51	27.2	126.8	6.6	63	2.3	5.9	6.9	42	0.69	0.083	13
STD DS8	Standard	11.3	98.9	106.1	310	1.8	34.3	6.9	578	2.34	26.4	127.9	5.7	62	2.2	5.6	6.6	37	0.65	0.080	12
STD DS8	Standard	14.5	116.0	140.7	325	1.6	42.1	8.4	670	2.82	28.9	111.0	7.4	70	2.4	5.5	6.5	45	0.72	0.086	15
STD DS8	Standard	14.2	115.1	137.2	309	1.5	41.2	7.4	628	2.62	26.7	106.3	7.3	65	2.4	5.2	6.5	44	0.69	0.085	15
STD OXC88	Standard																				
STD OXC88	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OXC88 Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 19, 2011

QUALITY CONTROL REPORT WHI11000492.3

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	3B
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Au
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppb
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	2
Pulp Duplicates																		
1091014	Soil	28	0.22	190	0.008	2	1.12	0.012	0.12	3.3	1.97	3.2	0.9	0.30	4	6.3	<0.2	58
REP 1091014	QC																	67
1091017	Soil	10	0.14	194	0.004	2	1.07	0.009	0.08	0.7	2.81	0.9	0.4	0.17	3	2.5	<0.2	34
REP 1091017	QC	10	0.14	192	0.007	2	1.06	0.009	0.10	0.7	2.91	1.4	0.5	0.25	3	1.0	<0.2	
1091040	Soil	17	0.07	510	0.004	3	0.68	0.007	0.08	0.2	0.43	0.9	0.6	<0.05	3	1.9	<0.2	N.A.
REP 1091040	QC	17	0.07	503	0.005	4	0.70	0.007	0.08	0.2	0.40	1.5	0.6	<0.05	3	2.0	<0.2	
1091159	Soil	12	0.15	558	0.005	3	0.60	0.010	0.05	0.1	1.13	1.3	0.4	<0.05	2	1.6	<0.2	N.A.
REP 1091159	QC	12	0.16	573	0.007	5	0.62	0.011	0.05	0.2	1.15	1.5	0.4	<0.05	2	4.0	<0.2	
1091188	Soil	20	0.06	179	0.004	2	0.54	0.003	0.06	0.3	0.23	1.1	1.1	0.07	2	5.6	<0.2	N.A.
REP 1091188	QC	21	0.07	184	0.006	3	0.54	0.003	0.07	0.3	0.27	1.0	1.0	0.08	2	4.9	0.3	
Reference Materials																		
STD DS8	Standard	105	0.59	255	0.103	2	0.83	0.068	0.39	3.0	0.20	1.7	5.0	0.10	4	4.3	4.3	
STD DS8	Standard	110	0.59	253	0.111	3	0.88	0.075	0.40	2.9	0.22	1.9	5.1	0.13	4	4.9	4.5	
STD DS8	Standard	120	0.61	260	0.111	2	0.92	0.073	0.44	3.1	0.25	2.2	5.8	0.14	5	5.7	5.3	
STD DS8	Standard	106	0.58	252	0.103	2	0.86	0.073	0.42	3.1	0.19	2.1	5.3	0.14	5	5.2	4.9	
STD DS8	Standard	128	0.60	286	0.125	3	0.95	0.086	0.41	2.9	0.17	1.9	5.9	0.19	5	4.9	5.1	
STD DS8	Standard	121	0.57	269	0.120	2	0.93	0.072	0.39	3.0	0.16	1.9	5.6	0.16	5	4.8	4.9	
STD OXC88	Standard																	203
STD OXC88	Standard																	198
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	
STD OXC88 Expected																		203
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2	
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2	
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2	
BLK	Blank																	<2
BLK	Blank																	<2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 15, 2011
Report Date: September 01, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11000601.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #3
P.O. Number
Number of Samples: 322

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve to 230 mesh			WHI
1DX2	310	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	10	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090521	Soil	19.7	10.9	5.4	82	0.5	15.9	1.2	31	0.58	9.2	1.7	0.3	22	1.3	4.7	<0.1	43	0.50	0.055	4
1090522	Soil	90.9	12.4	6.1	1391	0.2	54.0	34.8	1794	17.27	181.9	0.6	0.3	9	1.1	14.8	<0.1	64	0.14	0.119	2
1090523	Soil	43.8	28.0	16.9	662	2.0	82.7	3.5	312	7.06	85.2	5.6	0.9	48	2.5	10.1	0.2	108	0.21	0.136	3
1090524	Soil	18.4	18.0	13.2	158	0.2	42.3	3.0	35	1.20	23.4	0.5	0.5	20	0.4	3.7	0.2	80	0.14	0.048	11
1090525	Soil	25.5	27.4	21.5	357	0.7	41.2	8.5	383	5.99	117.1	10.2	2.4	37	0.7	8.7	0.3	119	0.06	0.113	11
1090526	Soil	8.6	17.8	10.8	69	1.2	12.9	2.0	116	1.83	27.7	6.9	0.2	20	0.4	2.7	0.1	57	0.05	0.086	4
1090527	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090528	Soil	14.5	48.1	12.9	265	0.6	46.2	5.9	106	2.04	34.0	7.9	0.6	56	2.0	6.7	0.2	106	0.20	0.121	7
1090529	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090530	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090601	Soil	6.4	16.7	5.4	103	0.3	18.8	1.7	52	0.57	17.5	2.5	0.2	39	1.1	2.4	0.1	105	0.67	0.061	4
1090602	Soil	24.4	31.5	8.5	211	0.2	40.4	2.0	25	0.82	20.6	1.6	0.8	40	3.5	5.0	0.2	371	0.65	0.040	12
1090603	Soil	8.9	34.0	5.5	180	0.6	38.0	2.1	46	0.76	18.0	2.4	0.2	54	3.2	2.8	<0.1	120	0.99	0.064	6
1090604	Soil	9.5	17.9	7.1	122	0.5	26.4	1.8	24	0.69	18.0	0.9	0.4	34	1.1	2.5	0.1	89	0.52	0.043	7
1090605	Soil	19.9	23.1	12.0	171	0.2	41.7	4.0	59	1.58	41.0	2.5	0.4	23	0.8	4.0	0.2	96	0.23	0.068	12
1090606	Soil	23.0	37.7	15.6	322	0.6	65.4	7.5	144	2.50	60.6	4.4	2.4	32	1.3	6.5	0.3	138	0.27	0.126	14
1090607	Soil	12.5	13.5	6.5	103	0.4	23.1	2.1	26	0.82	22.0	1.0	0.2	11	0.6	3.0	0.1	75	0.12	0.047	9
1090608	Soil	13.5	55.0	16.2	295	0.9	60.0	7.3	147	2.63	41.7	5.1	1.6	30	2.8	3.7	0.3	137	0.23	0.109	12
1090609	Soil	13.4	26.3	11.9	129	0.4	31.1	4.3	77	1.95	30.6	4.2	0.9	16	0.3	3.6	0.2	89	0.05	0.074	10
1090610	Soil	31.5	13.4	12.5	77	1.5	15.6	2.1	30	1.11	31.0	0.9	0.2	24	0.3	7.0	0.1	125	0.02	0.049	14
1090611	Soil	24.7	24.4	12.2	150	2.0	33.6	3.8	66	2.23	40.6	2.4	1.2	19	0.7	5.3	0.2	208	0.01	0.085	11
1090612	Soil	6.4	12.6	6.3	41	0.7	8.9	1.4	21	0.67	10.0	1.4	0.4	7	0.4	1.3	0.1	59	0.02	0.051	9
1090613	Soil	6.7	10.5	6.3	52	0.5	12.0	2.0	34	0.94	12.6	1.3	1.0	8	0.2	1.3	0.1	56	0.02	0.064	9
1090614	Soil	19.5	18.7	14.8	133	1.6	32.2	4.7	91	2.58	31.5	<0.5	2.1	14	0.4	4.6	0.3	127	<0.01	0.102	9
1090615	Soil	13.3	18.1	4.5	35	5.5	10.2	1.5	27	0.65	5.9	<0.5	0.2	7	0.4	3.2	0.2	54	0.02	0.020	15
1090616	Soil	29.2	20.1	74.5	77	3.9	17.7	2.2	35	1.54	30.9	2.5	0.3	59	0.5	9.0	0.4	158	0.02	0.101	15
1090617	Soil	43.2	16.5	62.8	48	1.2	11.1	1.7	31	1.28	68.6	3.7	0.2	17	0.2	11.6	0.3	119	0.02	0.039	11
1090618	Soil	19.0	16.1	22.0	93	0.6	20.0	2.6	72	1.65	43.8	2.8	0.3	18	0.3	9.3	0.2	106	0.03	0.078	9
1090619	Soil	10.3	24.6	11.2	75	0.5	16.3	2.0	45	1.03	22.0	<0.5	0.2	15	0.6	3.0	0.2	62	0.04	0.055	13
1090620	Soil	24.8	37.4	21.3	198	0.8	37.8	4.0	116	2.04	68.1	4.3	0.6	26	1.3	8.4	0.3	133	0.06	0.087	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090521	Soil	10	0.03	230	0.004	2	0.27	0.009	0.03	0.1	0.28	0.7	0.4	0.07	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090522	Soil	8	0.02	221	0.009	3	0.24	0.013	0.05	0.1	0.23	0.7	0.7	0.06	<1	8.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090523	Soil	14	0.03	1620	0.005	6	0.50	0.013	0.34	0.2	1.44	1.7	0.8	0.53	3	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090524	Soil	12	0.03	227	0.004	3	0.34	0.004	0.06	0.2	0.08	0.6	0.5	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090525	Soil	23	0.09	527	0.003	3	0.75	0.003	0.08	0.2	0.83	2.0	0.5	<0.05	3	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090526	Soil	11	0.03	341	0.003	3	0.46	0.012	0.05	0.1	0.85	0.7	0.4	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090527	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	31.3	67.4	7.6	873
1090528	Soil	21	0.05	2249	0.002	4	0.49	0.003	0.08	0.2	0.46	1.8	0.5	0.08	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090529	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090530	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090601	Soil	10	0.07	528	0.005	2	0.47	0.025	0.06	<0.1	0.26	0.6	0.2	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090602	Soil	26	0.10	905	0.004	2	0.72	0.007	0.07	0.2	0.24	1.2	0.6	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090603	Soil	13	0.10	767	0.004	3	0.67	0.021	0.06	0.1	0.41	1.1	0.4	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090604	Soil	12	0.08	487	0.003	2	0.61	0.018	0.06	0.1	0.33	1.0	0.3	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090605	Soil	12	0.05	447	0.003	2	0.55	0.005	0.06	0.2	0.15	0.8	0.4	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090606	Soil	21	0.12	588	0.004	3	0.86	0.003	0.09	0.2	0.37	2.0	0.5	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090607	Soil	9	0.05	267	0.003	2	0.45	0.009	0.04	<0.1	0.13	0.4	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090608	Soil	29	0.17	2258	0.003	2	1.50	0.005	0.09	0.2	0.77	2.9	0.4	<0.05	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090609	Soil	15	0.08	402	0.003	1	0.68	0.003	0.06	0.2	0.16	1.0	0.3	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090610	Soil	11	0.03	161	0.005	2	0.38	0.006	0.05	0.4	0.15	0.3	1.2	<0.05	3	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090611	Soil	16	0.05	259	0.004	2	0.62	0.004	0.07	0.3	0.22	1.2	1.2	<0.05	4	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090612	Soil	8	0.03	305	0.004	2	0.58	0.007	0.05	0.1	0.05	0.5	0.3	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090613	Soil	9	0.04	289	0.004	2	0.55	0.009	0.05	0.1	0.06	0.8	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090614	Soil	12	0.08	170	0.003	2	0.75	0.002	0.05	0.2	0.06	1.3	0.4	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090615	Soil	8	0.01	94	0.005	2	0.22	0.009	0.02	0.2	0.07	0.4	0.3	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090616	Soil	18	0.02	725	0.003	2	0.39	0.005	0.08	0.7	0.68	0.5	3.5	0.06	5	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090617	Soil	12	0.02	254	0.003	3	0.39	0.005	0.08	0.5	0.54	0.3	1.3	0.13	4	7.0	0.2	N.A.	N.A.	N.A.	N.A.
1090618	Soil	12	0.07	318	0.004	2	0.55	0.007	0.06	0.3	0.35	0.5	0.7	<0.05	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090619	Soil	10	0.04	331	0.003	3	0.54	0.006	0.06	0.2	0.19	0.5	0.4	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090620	Soil	19	0.07	557	0.002	3	0.90	0.005	0.10	0.3	0.59	1.1	0.9	<0.05	4	1.8	0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090521	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090522	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090523	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090524	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090525	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090526	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090527	Soil	0.4	199.1	133.7	8616	6.95	129.7	4.6	0.3	16	10.0	3.5	0.1	53	0.11	0.107	3	13	0.04	586	0.006
1090528	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090529	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090530	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090601	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090602	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090603	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090604	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090605	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090606	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090607	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090608	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090609	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090610	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090611	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090612	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090613	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090614	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090615	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090616	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090617	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090618	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090619	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090620	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090521	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090522	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090523	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090524	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090525	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090526	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090527	Soil	<20	0.61	0.016	0.07	<0.1	0.23	1.2	5.9	<0.05	2	5.5	<0.2
1090528	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090529	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090530	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090601	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090602	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090603	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090604	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090605	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090606	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090607	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090608	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090609	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090610	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090611	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090612	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090613	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090614	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090615	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090616	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090617	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090618	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090619	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090620	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090621	Soil	11.6	25.7	17.6	159	0.5	28.5	4.0	110	2.19	57.0	1.3	1.2	65	0.6	4.7	0.2	110	0.06	0.116	8
1090622	Soil	8.4	9.5	13.3	74	0.2	17.9	2.6	61	1.80	25.1	<0.5	1.6	11	0.4	3.5	0.3	107	0.02	0.034	12
1090623	Soil	9.7	20.5	13.0	124	0.4	25.7	3.8	89	1.48	24.9	2.2	0.6	27	0.5	3.6	0.2	73	0.04	0.051	8
1090624	Soil	16.1	32.9	18.5	212	1.0	37.8	7.0	228	2.23	33.7	1.5	1.9	59	2.2	6.5	0.2	98	0.32	0.104	9
1090625	Soil	15.4	58.1	31.1	325	2.4	44.6	4.9	113	2.00	32.3	3.3	2.2	78	3.1	8.6	0.3	130	0.18	0.102	10
1090626	Soil	17.5	33.6	23.6	218	0.3	36.2	3.2	44	1.87	42.3	0.9	0.4	31	0.5	8.2	0.4	148	0.02	0.057	7
1090627	Soil	10.6	16.2	15.7	106	0.5	22.2	2.6	62	1.79	39.0	1.8	0.2	32	0.2	5.7	0.3	140	0.03	0.108	8
1090628	Soil	3.6	8.0	7.8	36	0.3	6.5	0.9	18	0.53	7.7	<0.5	0.3	10	0.1	1.6	0.2	44	0.01	0.028	14
1090629	Soil	4.8	8.5	12.5	60	0.2	11.2	1.4	30	0.92	13.6	<0.5	0.4	19	<0.1	2.1	0.2	71	0.02	0.044	8
1090630	Soil	6.1	48.4	33.1	207	0.2	33.9	7.6	200	2.91	50.1	2.8	0.5	18	0.7	3.0	0.4	60	0.04	0.098	5
1090631	Soil	5.2	63.1	20.2	71	1.0	45.9	16.4	540	4.23	75.8	3.3	0.6	13	0.2	2.6	0.4	70	0.04	0.103	3
1090632	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090633	Soil	5.4	100.2	25.9	160	0.8	60.6	24.3	664	4.21	64.6	2.4	0.7	35	0.8	3.9	0.5	55	0.21	0.094	5
1090634	Soil	4.4	144.3	41.7	369	0.8	75.2	18.6	576	5.98	104.9	4.6	2.3	111	6.3	5.0	0.6	83	0.22	0.109	3
1090635	Soil	41.3	180.1	695.1	603	1.3	55.1	5.3	235	4.80	5118	75.9	5.4	1667	21.5	71.6	11.7	266	0.60	0.474	6
1090636	Soil	57.0	113.7	37.7	962	2.0	284.7	5.8	113	1.60	108.2	0.9	1.8	275	14.3	24.0	0.4	261	0.68	0.128	7
1090637	Soil	111.3	93.7	33.8	885	2.0	219.8	4.7	110	2.00	91.4	<0.5	2.0	113	10.9	27.3	0.2	373	2.67	0.095	4
1090638	Soil	131.4	130.3	17.3	1338	2.2	274.3	4.7	114	1.82	64.4	2.2	3.1	311	18.9	27.6	0.2	463	10.82	0.077	11
1090639	Soil	27.8	44.5	17.0	213	0.3	60.4	9.9	259	2.52	31.3	2.1	2.4	20	0.7	4.2	0.2	74	0.14	0.094	9
1090640	Soil	17.3	15.4	7.0	105	0.2	26.1	3.2	47	1.16	21.3	<0.5	0.6	6	0.2	2.5	0.2	76	0.02	0.027	8
1090641	Soil	9.6	9.3	7.9	55	0.2	13.5	1.4	20	0.61	8.0	<0.5	0.6	7	0.2	1.0	0.1	63	0.02	0.029	11
1090642	Soil	9.2	15.3	7.7	82	0.5	22.6	2.5	44	0.87	12.8	<0.5	0.2	9	0.5	1.9	0.1	37	0.04	0.065	4
1090643	Soil	15.5	15.5	10.2	104	<0.1	36.0	3.0	101	0.79	13.7	<0.5	0.6	34	1.1	1.8	0.1	48	0.75	0.044	7
1090644	Soil	57.1	82.2	58.4	579	1.5	156.9	7.4	199	2.11	182.4	1.9	2.0	168	5.8	16.3	0.5	259	2.12	0.129	7
1090645	Soil	48.1	51.8	17.1	435	0.6	122.2	6.6	162	1.85	61.5	1.0	2.3	133	4.9	8.2	0.2	126	3.63	0.110	7
1090646	Soil	49.7	48.9	12.8	410	0.4	110.7	6.3	146	1.85	29.2	0.5	3.1	127	3.7	7.7	0.1	93	4.15	0.086	8
1090647	Soil	9.6	27.7	4.3	322	0.5	45.9	3.1	123	1.01	9.5	1.1	0.8	58	5.0	5.0	0.1	69	1.70	0.075	6
1090648	Soil	11.3	28.7	3.7	504	0.2	58.3	2.4	96	0.63	10.1	1.3	0.3	48	11.9	5.5	<0.1	65	1.76	0.041	2
1090649	Soil	42.2	19.6	10.3	179	<0.1	63.2	4.0	42	1.37	19.9	0.6	0.5	8	0.2	4.8	0.2	96	0.04	0.048	5
1090650	Soil	7.6	12.3	5.1	94	0.2	19.0	2.1	50	0.68	6.9	1.2	0.2	15	0.5	2.1	<0.1	45	0.23	0.037	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090621	Soil	18	0.09	388	0.003	3	0.87	0.006	0.07	0.2	0.11	1.4	0.4	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090622	Soil	12	0.05	171	0.006	2	0.65	0.003	0.05	0.2	<0.01	1.1	0.3	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090623	Soil	11	0.05	676	0.004	4	0.48	0.009	0.06	0.1	0.11	1.0	0.3	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090624	Soil	17	0.13	1037	0.002	3	0.67	0.007	0.08	0.2	0.54	2.3	0.4	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090625	Soil	22	0.12	1433	0.004	4	0.73	0.003	0.07	0.2	1.06	2.6	0.6	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090626	Soil	16	0.03	243	0.002	2	0.35	0.003	0.07	0.2	0.16	1.0	0.5	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090627	Soil	15	0.03	214	0.003	2	0.49	0.002	0.06	0.2	0.13	0.4	0.4	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090628	Soil	7	0.02	110	0.005	2	0.35	0.003	0.04	<0.1	0.06	0.5	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090629	Soil	8	0.03	173	0.004	2	0.38	0.002	0.04	0.1	0.07	0.5	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090630	Soil	19	0.04	119	0.004	3	0.43	0.007	0.08	<0.1	0.09	2.3	0.3	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090631	Soil	20	0.06	212	0.002	3	0.49	0.005	0.07	<0.1	0.10	4.3	0.2	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090632	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.7	66.5	41.4	86
1090633	Soil	17	0.10	410	0.004	3	0.73	0.009	0.07	<0.1	0.11	4.4	0.3	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090634	Soil	23	0.07	773	<0.001	3	0.48	0.003	0.12	<0.1	0.20	10.3	0.4	0.17	1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090635	Soil	33	0.13	1012	0.002	3	0.81	0.006	0.31	0.4	1.92	7.4	1.8	0.51	3	11.4	0.3	N.A.	N.A.	N.A.	N.A.
1090636	Soil	20	0.06	564	0.001	8	0.46	0.002	0.12	0.2	2.34	2.9	2.2	0.06	1	14.4	0.7	N.A.	N.A.	N.A.	N.A.
1090637	Soil	19	0.90	278	0.001	6	0.29	0.003	0.09	0.2	3.11	2.7	1.5	<0.05	1	11.7	0.4	N.A.	N.A.	N.A.	N.A.
1090638	Soil	23	3.07	272	0.003	5	0.23	0.006	0.10	0.3	1.39	3.0	2.0	0.05	<1	6.7	0.3	N.A.	N.A.	N.A.	N.A.
1090639	Soil	14	0.07	779	0.003	2	0.62	0.003	0.08	<0.1	0.11	2.3	0.4	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090640	Soil	8	0.03	74	0.003	2	0.36	0.005	0.05	<0.1	0.02	0.5	0.3	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090641	Soil	12	0.05	184	0.004	3	0.56	0.004	0.09	<0.1	0.02	0.6	0.4	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090642	Soil	7	0.05	173	0.002	1	0.34	0.016	0.05	<0.1	0.16	0.3	0.2	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090643	Soil	11	0.15	260	0.006	6	0.40	0.015	0.06	0.1	0.07	1.1	0.5	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090644	Soil	22	0.96	530	0.001	6	0.39	0.006	0.12	0.1	1.53	3.5	1.2	0.11	1	7.9	0.3	N.A.	N.A.	N.A.	N.A.
1090645	Soil	14	1.91	366	0.002	5	0.24	0.005	0.08	0.1	0.66	2.9	0.6	0.06	<1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090646	Soil	13	2.05	415	0.002	8	0.23	0.006	0.09	<0.1	0.40	3.1	0.6	<0.05	<1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090647	Soil	11	0.31	960	0.005	5	0.55	0.014	0.07	<0.1	0.11	1.6	0.2	0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090648	Soil	6	0.27	215	0.004	3	0.35	0.030	0.04	<0.1	0.13	1.1	0.1	<0.05	<1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090649	Soil	13	0.03	249	0.003	4	0.40	0.005	0.05	0.2	0.13	0.9	0.5	0.07	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090650	Soil	7	0.08	406	0.005	2	0.33	0.020	0.04	<0.1	0.08	0.6	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090621	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090622	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090623	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090624	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090625	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090626	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090627	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090628	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090629	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090630	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090631	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090632	Soil	0.7	50.8	18.6	848	3.54	54.9	4.3	0.6	21	0.3	1.2	0.4	53	0.13	0.085	4	33	0.08	225	0.004
1090633	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090634	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090635	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090636	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090637	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090638	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090639	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090640	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090641	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090642	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090643	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090644	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090645	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090646	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090647	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090648	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090649	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090650	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090621	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090622	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090623	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090624	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090625	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090626	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090627	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090628	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090629	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090630	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090631	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090632	Soil	<20	0.48	0.014	0.07	<0.1	0.07	4.5	0.3	<0.05	2	1.7	<0.2
1090633	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090634	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090635	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090636	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090637	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090638	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090639	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090640	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090641	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090642	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090643	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090644	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090645	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090646	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090647	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090648	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090649	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090650	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090651	Soil	22.7	43.7	18.0	335	0.5	71.2	8.7	173	2.60	43.2	4.5	2.2	59	1.5	6.7	0.2	96	0.23	0.140	17
1090652	Soil	8.8	24.0	9.6	107	0.2	24.7	2.4	37	1.14	15.1	1.7	0.5	21	0.8	2.6	0.1	50	0.21	0.050	8
1090653	Soil	21.1	46.7	16.7	306	0.5	76.6	9.7	227	2.97	43.8	3.7	1.8	32	1.4	5.7	0.3	94	0.30	0.123	17
1090654	Soil	16.0	28.3	18.4	212	0.1	49.4	7.1	114	3.29	43.2	2.7	0.5	13	0.3	5.5	0.4	96	0.02	0.125	15
1090655	Soil	13.2	29.5	14.0	144	0.2	38.6	5.5	106	3.13	33.1	1.3	3.5	9	0.2	4.0	0.3	64	0.01	0.053	16
1090656	Soil	10.0	15.3	12.5	92	0.1	21.2	3.3	76	1.45	20.1	1.2	1.1	11	0.2	2.7	0.2	69	0.02	0.028	15
1090657	Soil	35.0	44.8	15.3	398	0.2	98.3	8.0	73	2.94	39.8	1.3	1.1	12	0.7	6.5	0.2	69	0.10	0.074	14
1090658	Soil	10.3	30.6	16.8	214	0.2	47.7	8.9	197	3.15	25.5	3.5	2.1	24	0.7	2.9	0.2	70	0.14	0.080	11
1090659	Soil	6.5	24.3	17.8	130	0.3	28.7	6.5	132	3.57	21.8	1.7	1.2	21	0.3	2.1	0.3	64	0.03	0.112	6
1090660	Soil	7.6	17.1	14.1	103	0.3	21.6	4.5	71	2.02	19.6	0.8	0.8	14	0.2	2.2	0.3	61	0.03	0.051	9
1090661	Soil	5.2	16.2	14.3	88	0.2	19.3	4.9	89	2.40	20.2	0.6	2.1	13	0.2	2.1	0.2	61	0.02	0.039	9
1090662	Soil	8.2	30.7	12.7	154	0.5	38.1	7.1	188	1.98	17.7	3.8	1.0	32	0.7	2.7	0.2	56	0.29	0.077	9
1090663	Soil	14.8	31.7	13.5	262	0.4	45.1	8.4	314	1.90	23.1	1.5	1.2	32	2.8	4.1	0.2	117	0.30	0.113	11
1090664	Soil	13.7	40.0	12.7	276	0.9	64.6	6.7	146	2.02	33.4	4.0	1.3	45	1.4	5.0	0.2	71	0.54	0.097	10
1090665	Soil	8.3	33.0	8.3	174	0.7	40.5	4.1	125	1.28	19.5	3.5	0.8	68	1.7	3.4	0.1	77	1.14	0.109	7
1090666	Soil	12.1	202.3	158.7	354	7.1	64.5	14.3	156	17.85	3127	266.4	22.4	76	0.6	111.2	32.3	88	0.03	0.325	28
1090667	Soil	17.0	240.5	135.2	366	5.9	65.9	13.6	170	16.23	3185	334.9	26.4	104	0.8	110.4	13.7	110	0.04	0.380	35
1090668	Soil	39.2	322.2	58.4	330	5.6	73.3	11.9	279	13.36	2059	131.8	14.3	58	0.8	83.9	6.2	129	0.10	0.260	27
1090669	Soil	14.8	220.5	58.7	1500	3.4	262.5	40.5	1892	12.64	707.0	136.9	5.0	81	16.5	53.2	2.2	297	1.64	0.164	16
1090670	Soil	9.9	171.1	100.6	336	2.2	48.1	7.7	195	12.35	3958	199.6	25.9	278	2.4	117.9	12.8	350	0.06	0.428	34
1090671	Soil	5.4	129.3	109.7	337	3.0	41.9	15.2	384	7.75	2352	523.3	11.9	344	3.5	73.1	10.7	113	0.06	0.245	43
1090672	Soil	11.9	114.7	85.9	258	3.0	35.4	13.1	384	5.58	1491	304.3	6.4	207	2.5	45.5	9.1	92	0.08	0.208	29
1090673	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090674	Soil	26.2	58.8	73.1	40	9.9	5.2	0.8	23	1.68	1356	9.8	2.0	52	0.6	224.0	1.3	81	0.03	0.233	21
1090675	Soil	28.4	77.0	66.9	46	15.1	8.1	0.9	21	1.81	1171	70.1	0.7	88	0.8	217.3	1.4	97	0.08	0.312	20
1090676	Soil	29.6	68.9	73.7	51	13.4	7.6	0.8	13	1.86	1236	53.1	0.5	67	0.7	187.3	1.3	95	0.04	0.271	20
1090677	Soil	18.0	52.0	46.8	87	5.1	17.8	4.2	145	2.79	655.2	120.1	1.0	66	0.6	77.9	1.0	76	0.07	0.267	18
1090678	Soil	9.7	45.3	30.9	123	1.9	25.6	6.1	190	2.56	247.8	71.8	2.5	41	0.7	36.4	0.6	58	0.14	0.147	18
1090679	Soil	8.6	48.2	29.7	135	2.1	31.9	6.5	172	2.71	192.2	54.3	3.3	52	0.9	29.2	0.6	50	0.22	0.137	16
1090680	Soil	6.2	31.6	19.3	104	0.7	23.2	4.2	79	2.61	98.6	18.4	0.9	27	0.2	6.1	0.5	64	0.03	0.078	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090651	Soil	16	0.10	664	0.004	4	0.67	0.004	0.10	0.2	0.32	2.1	0.4	0.08	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090652	Soil	9	0.04	556	0.004	1	0.47	0.009	0.05	0.1	0.18	0.9	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090653	Soil	17	0.11	889	0.003	3	0.82	0.004	0.09	0.2	0.35	2.0	0.5	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090654	Soil	12	0.04	183	0.003	2	0.51	0.003	0.07	0.2	0.08	0.8	0.4	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090655	Soil	10	0.04	282	0.002	3	0.75	0.003	0.06	0.1	0.05	1.5	0.3	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090656	Soil	9	0.06	149	0.007	1	0.56	0.003	0.04	0.2	0.03	0.8	0.2	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090657	Soil	12	0.04	329	0.002	3	0.45	0.004	0.06	<0.1	0.06	1.9	0.3	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090658	Soil	19	0.20	762	0.003	2	0.96	0.004	0.07	0.1	0.11	2.3	0.2	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090659	Soil	20	0.16	284	0.002	2	1.06	0.004	0.06	<0.1	0.06	1.7	0.2	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090660	Soil	10	0.06	220	0.002	<1	0.61	0.003	0.05	0.1	0.01	1.1	0.2	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090661	Soil	11	0.08	154	0.005	2	0.64	0.003	0.05	0.1	<0.01	1.6	0.2	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090662	Soil	16	0.20	1054	0.004	2	0.80	0.012	0.07	0.1	0.17	2.1	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090663	Soil	16	0.11	835	0.004	2	0.93	0.008	0.06	0.2	0.31	2.3	0.4	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090664	Soil	13	0.11	802	0.002	2	0.71	0.016	0.08	0.1	0.55	2.3	0.5	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090665	Soil	13	0.23	1032	0.005	4	0.70	0.015	0.05	0.2	0.41	1.7	0.3	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090666	Soil	34	0.48	427	0.021	3	1.68	0.015	0.24	24.1	3.28	9.9	2.0	0.57	7	38.3	2.4	N.A.	N.A.	N.A.	N.A.
1090667	Soil	41	0.43	549	0.034	3	1.71	0.030	0.25	37.5	1.49	10.2	1.4	0.57	8	38.2	0.8	N.A.	N.A.	N.A.	N.A.
1090668	Soil	47	0.47	340	0.051	3	2.27	0.013	0.16	7.0	3.00	8.9	1.8	0.37	12	27.0	0.7	N.A.	N.A.	N.A.	N.A.
1090669	Soil	22	7.31	362	0.028	33	2.54	0.007	0.08	4.5	6.70	5.7	1.3	0.18	5	8.8	0.3	N.A.	N.A.	N.A.	N.A.
1090670	Soil	30	0.17	472	0.007	3	1.94	0.069	0.21	3.8	5.20	5.7	1.2	0.67	4	22.7	0.7	N.A.	N.A.	N.A.	N.A.
1090671	Soil	11	0.15	533	0.004	8	1.36	0.067	0.26	2.0	2.52	2.2	1.3	0.73	2	15.6	0.5	N.A.	N.A.	N.A.	N.A.
1090672	Soil	11	0.11	366	0.004	6	1.24	0.050	0.17	2.1	4.25	1.8	1.0	0.45	2	12.6	0.2	N.A.	N.A.	N.A.	N.A.
1090673	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	33.9	104.3	133.3	150
1090674	Soil	21	0.02	418	0.003	5	0.30	0.005	0.16	1.3	>50	1.7	6.9	0.32	3	98.3	1.4	N.A.	N.A.	N.A.	N.A.
1090675	Soil	33	0.02	365	0.002	5	0.42	0.006	0.14	1.6	>50	1.4	7.4	0.27	3	62.4	1.4	N.A.	N.A.	N.A.	N.A.
1090676	Soil	27	0.02	427	0.002	5	0.40	0.004	0.15	1.6	>50	1.0	6.5	0.31	3	70.0	1.4	N.A.	N.A.	N.A.	N.A.
1090677	Soil	26	0.08	412	0.003	3	0.62	0.005	0.14	0.9	>50	1.8	2.9	0.23	3	29.0	0.6	N.A.	N.A.	N.A.	N.A.
1090678	Soil	18	0.19	364	0.009	2	0.61	0.005	0.09	0.3	14.41	2.9	1.1	0.10	2	8.9	0.4	N.A.	N.A.	N.A.	N.A.
1090679	Soil	18	0.17	591	0.006	1	0.58	0.005	0.10	0.3	10.00	3.2	0.9	0.12	2	8.9	0.3	N.A.	N.A.	N.A.	N.A.
1090680	Soil	14	0.07	209	0.003	2	0.73	0.004	0.07	0.2	1.15	1.1	0.4	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090651	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090652	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090653	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090654	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090655	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090656	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090657	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090658	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090659	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090660	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090661	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090662	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090663	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090664	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090665	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090666	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090667	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090668	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090669	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090670	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090671	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090672	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090673	Soil	23.3	20.7	4.0	136	4.08	1539	241.9	1.4	243	1.8	57.4	3.2	284	0.61	0.851	30	53	0.08	519	0.006
1090674	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090675	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090676	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090677	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090678	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090679	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090680	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090651	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090652	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090653	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090654	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090655	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090656	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090657	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090658	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090659	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090660	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090661	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090662	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090663	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090664	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090665	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090666	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090667	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090668	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090669	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090670	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090671	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090672	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090673	Soil	<20	0.92	0.014	0.25	2.0	>50	2.7	5.7	0.42	6	54.7	0.8
1090674	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090675	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090676	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090677	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090678	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090679	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090680	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090681	Soil	2.2	23.9	29.1	62	0.9	13.4	3.3	48	1.51	46.1	5.8	1.4	17	<0.1	2.5	0.3	24	0.03	0.044	16
1090682	Soil	7.8	219.3	52.2	281	2.9	56.8	9.5	273	10.14	414.6	57.7	4.1	132	0.9	26.7	0.6	129	0.05	0.325	20
1090683	Soil	13.8	91.3	111.3	456	4.4	97.1	12.3	297	6.63	522.3	111.0	3.8	165	1.5	56.9	0.9	104	0.10	0.308	27
1090684	Soil	51.9	38.0	229.0	127	7.2	13.6	1.9	42	3.53	864.9	322.4	3.5	172	0.6	94.2	5.1	165	0.13	0.429	26
1090685	Soil	44.1	60.9	114.8	183	5.1	34.7	5.1	133	4.34	1180	433.4	3.5	91	0.6	73.9	3.6	132	0.04	0.197	23
1090686	Soil	21.2	86.8	111.5	154	4.4	20.4	6.0	112	9.30	1030	380.3	14.8	88	0.4	72.4	4.7	31	0.02	0.193	28
1090687	Soil	11.3	68.4	136.3	103	5.2	14.4	3.2	56	10.26	1717	451.0	8.6	112	0.3	112.4	5.9	43	0.01	0.192	20
1090688	Soil	3.3	48.2	37.6	65	1.0	9.2	3.0	80	3.40	467.7	157.7	1.0	20	0.2	21.1	2.1	24	0.04	0.099	12
1090689	Soil	5.1	54.5	44.8	92	1.4	13.7	4.0	119	5.38	648.9	135.9	2.1	23	0.2	28.4	2.5	38	0.03	0.121	16
1090690	Soil	6.2	89.5	86.2	142	1.5	18.3	9.8	468	6.84	636.8	200.0	3.4	50	0.3	29.0	4.8	41	0.03	0.143	25
1090701	Soil	156.0	192.3	27.7	3110	5.8	308.5	6.3	200	1.73	154.5	5.9	1.4	332	55.4	54.1	0.3	1556	5.46	0.190	27
1090702	Soil	67.1	65.1	14.2	973	1.3	167.7	8.1	157	1.99	76.6	4.5	1.9	76	7.4	18.3	0.2	382	1.22	0.109	13
1090703	Soil	12.5	19.4	5.5	149	0.4	26.5	2.0	37	0.71	15.4	0.7	0.2	46	2.2	4.2	0.1	65	0.77	0.045	5
1090704	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090705	Soil	23.2	48.2	20.9	306	0.7	76.3	7.9	113	2.96	95.4	9.4	3.3	30	0.9	11.9	0.4	97	0.10	0.125	15
1090706	Soil	18.1	75.4	31.9	303	1.0	103.0	9.2	165	2.79	57.3	6.4	1.8	52	2.1	9.0	0.3	86	0.53	0.153	9
1090707	Soil	42.7	80.3	25.9	357	2.7	93.7	9.4	124	3.29	118.9	4.5	0.7	145	4.2	12.3	0.4	131	0.07	0.142	10
1090708	Soil	93.3	32.1	10.8	670	0.8	170.6	4.5	54	2.10	68.0	<0.5	1.3	21	1.6	12.8	0.2	315	0.02	0.070	15
1090709	Soil	46.3	34.5	16.7	223	3.8	45.7	4.0	64	2.79	83.2	3.0	2.2	75	1.0	13.6	0.2	274	0.05	0.118	13
1090710	Soil	16.0	25.6	17.2	138	1.6	25.2	3.9	108	2.55	49.7	3.3	2.6	26	0.4	5.7	0.2	139	0.03	0.084	10
1090711	Soil	42.4	29.8	104.8	39	10.9	9.1	1.0	16	1.79	17.0	<0.5	0.5	206	0.8	7.8	0.3	154	0.02	0.100	6
1090712	Soil	12.1	17.3	17.2	97	0.4	20.6	3.2	62	2.23	41.8	3.5	2.4	15	0.5	8.1	0.2	110	0.03	0.058	11
1090713	Soil	13.9	27.8	21.4	139	0.6	33.2	4.8	89	2.53	44.0	3.7	2.2	20	0.6	9.2	0.3	102	0.03	0.083	10
1090714	Soil	12.2	8.2	13.6	36	0.4	8.1	1.3	19	0.60	9.2	<0.5	0.2	8	0.1	3.5	0.2	58	<0.01	0.020	13
1090715	Soil	15.7	39.6	18.6	125	1.1	38.0	2.7	57	1.13	24.6	2.7	0.3	28	3.0	11.2	0.2	87	0.18	0.055	8
1090716	Soil	21.6	64.4	24.9	629	1.0	85.1	13.5	507	3.74	58.1	6.3	1.7	70	2.9	12.8	0.3	127	0.18	0.119	8
1090717	Soil	15.5	46.3	19.3	640	0.8	81.2	12.4	234	2.65	44.7	3.9	2.3	68	2.7	11.8	0.2	94	0.27	0.125	9
1090718	Soil	14.4	34.5	18.1	241	1.0	40.8	4.8	128	2.08	38.9	7.1	1.2	71	1.2	8.4	0.2	101	0.19	0.127	6
1090719	Soil	6.7	38.0	16.7	193	0.9	34.7	6.5	194	2.08	22.8	7.8	1.4	109	1.8	3.5	0.3	92	0.49	0.111	6
1090720	Soil	3.3	7.2	34.3	27	<0.1	7.0	0.8	24	0.71	4.9	0.8	1.1	11	1.2	1.3	0.2	13	0.02	0.009	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090681	Soil	9	0.03	209	<0.001	<1	0.54	0.007	0.05	<0.1	0.59	1.0	0.1	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090682	Soil	37	0.26	338	0.008	2	1.30	0.006	0.11	0.2	1.67	5.2	2.3	0.21	6	7.0	0.3	N.A.	N.A.	N.A.	N.A.
1090683	Soil	33	0.19	499	0.008	3	1.05	0.008	0.22	0.4	5.28	4.5	6.2	0.44	5	12.7	0.5	N.A.	N.A.	N.A.	N.A.
1090684	Soil	29	0.04	420	0.004	2	0.55	0.010	0.20	2.6	35.01	1.8	12.0	0.48	4	30.4	0.6	N.A.	N.A.	N.A.	N.A.
1090685	Soil	26	0.07	350	0.005	2	0.68	0.012	0.17	2.5	13.62	1.8	5.6	0.40	3	23.4	0.5	N.A.	N.A.	N.A.	N.A.
1090686	Soil	14	0.09	333	0.006	4	0.96	0.024	0.22	2.4	11.93	3.1	5.0	0.59	3	17.5	0.2	N.A.	N.A.	N.A.	N.A.
1090687	Soil	16	0.11	332	0.005	3	0.76	0.021	0.34	2.1	23.06	2.4	6.4	0.88	4	23.7	0.4	N.A.	N.A.	N.A.	N.A.
1090688	Soil	8	0.08	100	0.006	2	0.77	0.015	0.06	0.5	4.92	0.8	1.0	0.11	3	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090689	Soil	13	0.12	126	0.009	2	0.77	0.012	0.08	0.7	6.29	1.2	1.3	0.15	3	7.6	0.3	N.A.	N.A.	N.A.	N.A.
1090690	Soil	16	0.17	197	0.006	2	0.95	0.005	0.13	0.6	9.20	1.7	1.7	0.28	3	6.6	0.3	N.A.	N.A.	N.A.	N.A.
1090701	Soil	107	1.03	608	0.011	10	1.17	0.006	0.17	0.8	4.55	4.5	4.0	0.06	2	10.5	0.3	N.A.	N.A.	N.A.	N.A.
1090702	Soil	28	0.37	455	0.005	3	0.64	0.008	0.07	0.4	1.39	3.4	1.2	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090703	Soil	6	0.07	422	0.005	2	0.45	0.022	0.04	0.1	0.27	0.6	0.2	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090704	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	167.4	259.6	335.0	708
1090705	Soil	16	0.09	285	0.003	2	0.57	0.002	0.07	0.2	0.64	2.1	0.3	<0.05	1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090706	Soil	16	0.10	610	0.003	3	0.57	0.009	0.07	0.1	0.89	3.0	0.3	<0.05	1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090707	Soil	20	0.03	640	0.006	2	0.56	0.006	0.15	0.2	0.69	1.6	1.4	0.34	2	4.4	0.2	N.A.	N.A.	N.A.	N.A.
1090708	Soil	18	0.05	175	0.003	2	0.59	0.003	0.07	0.5	0.10	1.4	1.7	<0.05	2	8.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090709	Soil	22	0.06	334	0.004	3	0.81	0.005	0.09	0.4	3.05	1.6	3.1	0.10	3	6.1	0.2	N.A.	N.A.	N.A.	N.A.
1090710	Soil	22	0.12	312	0.003	1	1.17	0.003	0.06	0.2	0.35	1.5	0.7	<0.05	4	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090711	Soil	27	0.01	453	0.010	2	0.33	0.008	0.13	0.4	0.16	0.5	3.2	0.49	4	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090712	Soil	16	0.11	246	0.006	<1	0.84	0.003	0.05	0.5	0.27	1.0	0.6	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090713	Soil	17	0.10	322	0.003	1	0.90	0.004	0.05	0.2	0.24	1.5	0.6	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090714	Soil	8	0.02	79	0.008	<1	0.29	0.004	0.04	0.2	0.07	0.1	0.6	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090715	Soil	17	0.04	1182	0.006	2	0.57	0.010	0.06	0.3	0.75	0.9	1.1	0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090716	Soil	26	0.11	1525	0.004	2	0.72	0.004	0.07	0.2	0.46	2.7	0.7	0.07	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090717	Soil	22	0.19	2542	0.005	2	0.79	0.003	0.07	0.2	0.51	2.8	0.5	0.08	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090718	Soil	20	0.10	1630	0.003	4	0.55	0.003	0.07	0.2	0.69	2.1	0.5	0.10	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090719	Soil	22	0.16	928	0.003	3	0.86	0.006	0.06	0.1	0.74	2.3	0.3	0.06	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090720	Soil	3	0.01	554	<0.001	4	0.19	0.002	0.05	<0.1	0.07	0.7	0.2	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090681	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090682	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090683	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090684	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090685	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090686	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090687	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090688	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090689	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090690	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090701	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090702	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090703	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090704	Soil	7.7	268.8	13.1	99	5.93	242.7	13.1	2.9	167	2.3	22.0	1.1	344	0.40	0.284	14	29	0.05	365	0.002
1090705	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090706	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090707	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090708	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090709	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090710	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090711	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090712	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090713	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090714	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090715	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090716	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090717	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090718	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090719	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090720	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090681	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090682	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090683	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090684	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090685	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090686	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090687	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090688	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090689	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090690	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090701	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090702	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090703	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090704	Soil	<20	0.58	0.006	0.13	0.6	3.35	4.0	2.4	0.27	2	13.6	1.0
1090705	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090706	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090707	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090708	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090709	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090710	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090711	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090712	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090713	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090714	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090715	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090716	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090717	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090718	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090719	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090720	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090721	Soil	6.0	34.5	27.6	73	0.6	28.1	7.2	134	2.38	22.1	2.6	0.6	15	0.2	3.2	0.4	44	0.02	0.067	4
1090722	Soil	3.8	101.5	13.4	83	0.6	45.1	14.3	481	4.29	17.4	1.3	1.1	21	0.5	2.6	0.3	40	0.03	0.162	3
1090723	Soil	4.1	39.3	11.9	128	0.1	31.0	9.0	203	2.00	17.2	1.3	0.3	7	0.2	2.6	0.3	37	0.03	0.052	3
1090724	Soil	19.7	43.7	16.4	204	0.5	62.3	5.4	123	1.53	70.7	3.0	0.9	54	1.1	4.0	0.2	59	0.75	0.073	6
1090725	Soil	74.8	68.3	13.9	729	0.7	156.2	5.4	143	1.63	36.4	1.7	1.0	61	5.4	14.0	0.2	157	1.17	0.065	9
1090726	Soil	73.3	69.5	11.7	419	0.5	154.7	6.9	182	1.66	75.2	1.4	1.4	195	4.9	13.5	0.1	135	6.39	0.121	8
1090727	Soil	78.1	52.2	9.3	149	0.1	149.7	9.1	201	2.20	38.1	1.1	1.4	121	0.8	2.0	0.1	40	2.43	0.079	9
1090728	Soil	8.5	13.1	11.1	74	<0.1	18.9	4.4	113	2.02	12.8	<0.5	1.3	11	0.2	1.3	0.2	60	0.06	0.033	7
1090729	Soil	60.4	56.2	7.5	201	0.4	140.2	6.0	143	1.39	24.0	<0.5	1.4	165	2.5	5.5	0.1	74	4.93	0.093	7
1090730	Soil	70.5	76.4	9.1	224	0.4	199.0	6.9	113	1.75	23.9	1.1	1.8	201	2.3	3.7	0.1	90	3.86	0.112	9
1090731	Soil	51.1	54.3	9.1	177	0.2	138.9	7.0	160	1.70	22.2	2.9	2.5	181	1.6	2.9	0.1	59	5.90	0.108	8
1090732	Soil	28.8	70.3	13.7	230	0.5	112.7	7.3	207	1.69	17.7	3.9	2.1	103	2.5	3.4	0.2	62	2.77	0.111	10
1090733	Soil	5.3	18.5	9.4	107	0.3	29.7	4.4	143	1.54	11.4	2.0	1.2	42	0.5	1.2	0.2	31	0.46	0.041	4
1090734	Soil	5.9	19.1	14.4	82	0.7	23.0	9.3	372	1.90	12.5	<0.5	0.9	25	0.5	1.3	0.2	44	0.23	0.068	4
1090735	Soil	6.4	26.2	16.7	143	0.1	35.6	8.6	162	2.67	19.0	<0.5	2.2	17	0.6	2.0	0.3	43	0.10	0.049	7
1090736	Soil	3.1	17.3	9.8	68	0.5	18.3	6.7	259	2.03	7.3	0.6	1.5	14	0.3	1.0	0.2	28	0.16	0.030	8
1090737	Soil	60.1	54.2	23.7	862	0.5	113.5	9.7	121	3.63	123.7	3.9	1.5	6	4.6	23.4	0.2	115	0.03	0.061	10
1090738	Soil	18.1	22.6	10.6	198	0.3	40.3	6.9	163	1.68	13.1	<0.5	2.3	39	1.1	3.5	0.2	40	0.67	0.096	8
1090739	Soil	11.1	10.2	5.3	73	<0.1	21.7	1.9	43	0.63	7.2	<0.5	0.1	9	1.0	1.9	<0.1	22	0.12	0.031	3
1090740	Soil	7.8	22.1	10.8	123	<0.1	36.0	5.1	69	2.01	15.2	1.5	2.8	7	0.3	3.0	0.2	50	0.03	0.026	11
1090741	Soil	10.7	43.7	11.8	212	0.3	55.6	6.9	114	1.97	16.3	1.8	2.6	19	1.0	5.3	0.2	43	0.23	0.066	14
1090742	Soil	3.4	49.0	20.6	313	0.8	56.2	7.4	133	1.88	13.0	0.6	3.9	67	3.4	3.2	0.2	52	0.75	0.091	12
1090743	Soil	8.4	28.8	9.7	171	0.6	40.4	21.0	1770	2.24	13.0	1.7	1.3	77	3.0	3.0	0.2	38	0.99	0.105	7
1090744	Soil	12.5	36.7	18.2	224	0.3	58.8	11.1	259	2.75	22.7	4.5	3.2	24	1.1	4.2	0.3	86	0.11	0.072	12
1090745	Soil	4.5	25.4	10.7	103	0.7	32.0	5.1	291	1.51	10.1	5.1	1.5	47	0.4	1.8	0.2	36	0.68	0.055	6
1090746	Soil	13.4	17.1	28.0	97	0.8	25.8	3.8	77	1.98	19.2	1.4	0.1	35	0.2	3.4	0.3	82	0.08	0.086	9
1090747	Soil	4.2	52.7	13.2	96	1.3	42.1	5.4	294	1.41	15.0	4.3	1.0	77	1.7	2.5	0.2	55	0.39	0.104	9
1090748	Soil	9.1	19.9	17.2	122	0.3	29.4	4.7	105	1.83	20.9	0.8	0.9	22	0.5	3.2	0.2	74	0.05	0.094	11
1090749	Soil	8.6	48.0	22.3	209	0.3	56.5	12.4	254	3.13	29.2	0.6	3.4	39	1.5	4.2	0.3	51	0.22	0.138	12
1090750	Soil	10.1	28.7	12.0	134	0.4	31.3	6.1	225	1.70	17.3	0.6	2.1	39	0.9	3.1	0.2	50	0.34	0.104	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090721	Soil	12	0.03	671	0.003	2	0.36	0.003	0.06	<0.1	0.12	1.5	0.4	0.06	1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090722	Soil	21	0.03	754	0.002	1	0.78	0.005	0.05	<0.1	0.07	6.8	0.2	0.08	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090723	Soil	14	0.02	126	0.002	<1	0.37	0.006	0.04	<0.1	0.03	1.3	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090724	Soil	15	0.11	1724	0.004	2	0.45	0.006	0.05	0.1	0.26	2.4	0.4	0.08	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090725	Soil	14	0.29	422	0.004	2	0.42	0.008	0.04	0.2	0.51	2.5	1.0	0.07	1	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090726	Soil	16	2.52	457	0.003	5	0.18	0.006	0.05	0.2	0.65	3.0	1.4	0.06	<1	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090727	Soil	13	1.14	474	0.004	3	0.36	0.005	0.04	0.2	0.34	2.9	0.6	<0.05	<1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090728	Soil	14	0.13	160	0.004	1	0.84	0.005	0.03	0.1	0.03	1.2	0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090729	Soil	17	2.29	391	0.002	3	0.36	0.005	0.04	0.2	0.31	3.2	1.2	<0.05	<1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090730	Soil	23	1.44	277	0.003	7	0.32	0.004	0.07	0.3	0.28	3.7	1.6	<0.05	<1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090731	Soil	16	2.39	228	0.003	6	0.26	0.005	0.07	0.2	0.21	3.0	1.3	<0.05	<1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090732	Soil	19	1.10	594	0.003	6	0.41	0.006	0.07	0.2	0.42	3.5	1.0	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090733	Soil	12	0.13	618	0.002	2	0.69	0.015	0.04	<0.1	0.10	1.6	0.1	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090734	Soil	14	0.13	1093	0.001	2	0.79	0.011	0.05	<0.1	0.19	1.6	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090735	Soil	16	0.18	409	0.001	1	0.79	0.003	0.04	<0.1	0.05	1.9	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090736	Soil	11	0.08	295	0.004	2	0.68	0.011	0.04	0.1	0.05	1.7	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090737	Soil	11	0.02	113	0.001	1	0.31	0.002	0.05	0.1	1.08	2.0	0.6	<0.05	<1	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090738	Soil	12	0.16	686	0.003	2	0.52	0.006	0.05	0.1	0.34	2.0	0.3	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090739	Soil	6	0.03	163	0.004	2	0.19	0.015	0.04	0.2	0.05	0.3	0.2	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090740	Soil	9	0.04	182	0.002	2	0.45	0.002	0.04	0.1	0.03	1.1	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090741	Soil	12	0.07	487	0.002	3	0.48	0.003	0.06	<0.1	0.15	2.0	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090742	Soil	18	0.14	1349	0.003	9	0.70	0.005	0.10	0.1	0.40	3.5	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090743	Soil	12	0.12	1062	0.004	5	0.67	0.011	0.06	0.1	0.23	2.0	0.2	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090744	Soil	21	0.15	466	0.004	2	1.12	0.004	0.06	0.1	0.19	2.3	0.3	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090745	Soil	12	0.15	661	0.003	2	0.78	0.015	0.06	<0.1	0.26	2.2	0.2	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090746	Soil	14	0.08	172	0.005	2	0.48	0.006	0.06	0.2	0.07	0.2	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090747	Soil	15	0.09	924	0.003	5	0.79	0.011	0.09	<0.1	0.45	2.5	0.4	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090748	Soil	12	0.06	228	0.002	2	0.59	0.002	0.05	0.1	0.04	0.9	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090749	Soil	14	0.11	597	0.003	2	0.53	0.003	0.06	<0.1	0.22	3.1	0.1	<0.05	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090750	Soil	12	0.12	560	0.003	3	0.55	0.010	0.07	<0.1	0.21	1.9	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090721	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090722	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090723	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090724	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090725	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090726	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090727	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090728	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090729	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090730	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090731	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090732	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090733	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090734	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090735	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090736	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090737	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090738	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090739	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090740	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090741	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090742	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090743	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090744	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090745	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090746	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090747	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090748	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090749	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090750	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090721	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090722	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090723	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090724	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090725	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090726	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090727	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090728	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090729	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090730	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090731	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090732	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090733	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090734	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090735	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090736	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090737	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090738	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090739	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090740	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090741	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090742	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090743	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090744	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090745	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090746	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090747	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090748	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090749	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090750	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090751	Soil		2.4	59.7	19.0	179	1.7	34.9	10.0	82	3.55	9.3	2.8	1.7	36	0.2	3.1	0.4	25	0.02	0.071	7
1090752	Soil		3.5	23.7	10.2	47	1.0	39.4	7.4	62	3.32	4.9	1.0	3.1	4	0.1	1.3	0.2	34	<0.01	0.033	15
1090753	Soil		2.9	83.8	27.5	141	0.5	40.9	5.9	80	4.42	13.2	0.8	2.3	33	<0.1	2.6	0.4	27	<0.01	0.064	14
1090754	Soil		1.8	12.4	5.2	35	<0.1	17.3	5.6	56	1.32	5.6	1.1	0.9	3	<0.1	0.9	0.2	25	0.01	0.013	6
1090755	Soil		3.0	42.8	8.5	39	<0.1	39.9	12.4	202	2.93	8.6	2.3	0.4	3	<0.1	2.3	0.3	33	0.01	0.039	14
1090756	Soil		9.7	49.1	29.8	162	1.0	66.4	16.9	371	4.18	15.7	4.8	1.7	16	0.2	3.9	0.3	20	0.32	0.050	12
1090757	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090758	Soil		0.6	12.7	4.4	14	0.3	8.0	1.4	77	0.43	1.5	<0.5	0.2	43	<0.1	0.5	<0.1	5	0.96	0.049	3
1090759	Soil		8.0	34.6	15.7	162	0.9	43.2	5.5	121	1.84	23.8	5.7	0.5	26	0.8	4.0	0.2	49	0.20	0.058	7
1090760	Soil		11.9	43.0	22.6	234	0.5	51.3	10.0	327	2.67	34.7	6.9	2.8	32	1.6	5.0	0.3	76	0.21	0.075	11
1090761	Soil		4.9	12.3	9.5	67	0.5	15.5	2.9	72	0.97	14.8	4.3	1.8	17	0.4	1.7	0.2	42	0.14	0.039	9
1090762	Soil		2.4	5.5	4.8	44	<0.1	7.1	1.0	21	0.46	5.6	<0.5	<0.1	6	0.1	0.8	<0.1	25	0.02	0.030	3
1090763	Soil		8.9	20.6	18.6	147	0.2	33.6	5.5	134	2.50	28.1	3.7	2.0	18	0.3	3.3	0.3	74	0.05	0.070	11
1090764	Soil		24.9	24.9	12.0	307	0.9	69.9	6.8	58	2.27	48.2	1.2	1.6	7	0.6	4.4	0.2	146	0.01	0.044	20
1090765	Soil		9.3	54.2	16.8	210	0.3	51.6	11.1	210	2.88	29.0	5.0	4.3	39	0.8	3.8	0.3	54	0.20	0.129	18
1090766	Soil		1.8	6.2	5.8	19	0.3	5.3	0.9	13	0.33	4.0	0.9	<0.1	6	<0.1	0.5	<0.1	16	0.01	0.028	4
1090767	Soil		10.5	36.1	21.5	183	0.6	41.2	7.4	162	2.72	40.0	2.7	1.3	43	0.5	4.0	0.3	77	0.15	0.178	14
1090768	Soil		11.6	30.5	12.6	239	0.7	47.9	7.5	261	1.99	24.0	3.5	2.7	55	1.9	4.0	0.2	66	0.66	0.136	16
1090769	Soil		9.8	34.1	19.2	390	1.0	50.6	17.4	510	2.76	31.0	4.3	1.7	49	2.0	2.6	0.2	84	0.41	0.132	10
1090770	Soil		12.1	26.8	17.0	225	0.5	37.6	9.9	469	2.16	25.1	2.8	1.8	48	1.5	2.6	0.2	79	0.56	0.112	11
1090771	Soil		9.2	16.7	9.1	153	1.7	31.9	2.9	48	1.23	12.7	2.7	0.6	44	0.6	2.4	<0.1	122	0.42	0.055	4
1090772	Soil		7.5	14.5	12.1	102	0.5	21.4	3.7	80	1.86	19.3	1.6	0.9	11	0.2	2.5	0.2	70	0.02	0.039	10
1090773	Soil		7.1	27.3	11.3	117	0.2	27.5	6.2	91	2.37	17.1	1.0	0.7	14	0.2	1.8	0.2	38	0.07	0.057	14
1090774	Soil		10.7	28.5	12.4	234	0.7	46.0	7.1	212	1.92	23.1	4.0	3.3	52	1.6	3.8	0.2	70	0.59	0.141	20
1090775	Soil		4.9	15.7	6.1	125	0.4	24.4	3.0	89	0.98	12.2	2.5	0.3	30	0.6	2.0	<0.1	49	0.28	0.054	3
1090776	Soil		2.2	8.3	5.7	25	0.3	5.2	0.9	20	0.38	3.9	2.3	<0.1	7	0.2	0.6	<0.1	24	0.03	0.047	6
1090777	Soil		4.0	7.4	6.5	39	0.2	7.5	1.3	27	0.60	8.5	1.7	0.6	7	0.1	1.1	<0.1	46	0.02	0.031	11
1090778	Soil		2.7	7.0	4.7	47	0.2	9.1	3.2	76	1.20	4.0	<0.5	1.3	3	0.1	0.6	<0.1	16	0.01	0.022	10
1090779	Soil		9.6	19.8	14.4	207	0.3	30.5	5.2	146	2.35	24.3	4.5	1.5	19	0.5	3.3	0.2	98	0.08	0.075	14
1090780	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090751	Soil	18	0.09	731	0.008	2	1.17	0.011	0.23	<0.1	0.09	2.3	0.2	0.30	4	5.4	0.3	N.A.	N.A.	N.A.	N.A.
1090752	Soil	9	0.04	635	0.005	2	0.73	0.004	0.05	<0.1	0.02	2.4	0.2	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090753	Soil	9	0.03	962	0.002	2	0.52	0.004	0.09	<0.1	0.04	1.0	0.2	0.09	3	7.6	0.3	N.A.	N.A.	N.A.	N.A.
1090754	Soil	7	0.02	54	0.006	<1	0.26	0.012	0.03	<0.1	<0.01	0.5	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090755	Soil	8	0.03	68	0.005	6	0.29	0.008	0.05	<0.1	<0.01	0.8	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090756	Soil	9	0.10	331	0.003	3	0.53	0.010	0.09	<0.1	0.18	3.4	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090757	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	9.1	57.5	24.9	171
1090758	Soil	4	0.12	236	0.009	3	0.37	0.029	0.03	<0.1	0.06	0.7	<0.1	0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090759	Soil	15	0.09	675	0.003	2	0.67	0.015	0.08	0.1	0.48	1.4	0.3	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090760	Soil	19	0.16	989	0.003	3	0.90	0.004	0.08	0.2	0.52	2.4	0.3	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090761	Soil	13	0.09	509	0.002	4	0.55	0.006	0.06	0.1	0.36	1.1	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090762	Soil	5	0.02	84	0.003	1	0.26	0.013	0.03	<0.1	0.07	0.4	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090763	Soil	18	0.12	191	0.003	2	0.85	0.004	0.06	0.1	0.09	1.3	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090764	Soil	14	0.03	68	0.008	2	0.35	0.005	0.04	0.1	0.04	1.3	0.2	<0.05	3	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090765	Soil	17	0.19	735	0.010	3	0.73	0.003	0.07	0.1	0.17	3.3	0.1	0.05	2	1.7	0.2	N.A.	N.A.	N.A.	N.A.
1090766	Soil	4	0.01	44	0.001	1	0.19	0.016	0.03	<0.1	0.02	<0.1	<0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090767	Soil	19	0.14	352	0.004	3	0.75	0.003	0.08	0.2	0.19	1.6	0.2	0.07	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090768	Soil	16	0.15	1076	0.003	4	0.63	0.006	0.09	0.2	0.38	2.8	0.3	0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090769	Soil	21	0.19	997	0.002	2	1.21	0.009	0.08	0.2	0.81	2.8	0.8	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090770	Soil	18	0.18	875	0.003	1	0.97	0.006	0.07	0.2	0.31	2.3	0.3	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090771	Soil	21	0.16	1810	0.003	2	1.27	0.026	0.08	0.2	0.37	1.7	0.4	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090772	Soil	12	0.08	168	0.008	1	0.66	0.007	0.05	0.1	0.05	1.0	0.2	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090773	Soil	7	0.04	602	0.005	2	0.38	0.006	0.05	<0.1	0.08	1.1	0.2	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090774	Soil	15	0.14	1118	0.003	4	0.64	0.006	0.10	0.1	0.39	2.7	0.3	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090775	Soil	9	0.07	666	0.005	2	0.71	0.031	0.06	0.1	0.23	0.9	0.2	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090776	Soil	5	0.02	113	0.002	<1	0.29	0.013	0.03	<0.1	0.03	<0.1	<0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090777	Soil	7	0.04	135	0.004	<1	0.44	0.009	0.04	0.1	0.03	0.5	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090778	Soil	5	0.04	78	0.004	1	0.44	0.016	0.04	<0.1	<0.01	0.7	0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090779	Soil	23	0.21	319	0.010	3	1.08	0.006	0.09	0.2	0.11	1.5	0.3	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090780	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	14.5	13.3	10.5	225

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090751	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090752	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090753	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090754	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090755	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090756	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090757	Soil		0.2	71.5	19.8	348	4.58	19.3	4.3	2.7	7	0.2	2.2	0.4	22	0.12	0.056	14	13	0.09	220	0.002
1090758	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090759	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090760	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090761	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090762	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090763	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090764	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090765	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090766	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090767	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090768	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090769	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090770	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090771	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090772	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090773	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090774	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090775	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090776	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090777	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090778	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090779	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090780	Soil		0.8	30.3	2.3	111	0.97	14.5	3.2	0.1	23	4.9	2.5	0.1	82	0.16	0.099	4	14	0.07	359	0.004

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090751	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090752	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090753	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090754	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090755	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090756	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090757	Soil	<20	0.69	0.006	0.09	<0.1	0.15	4.1	0.2	<0.05	2	1.4	<0.2
1090758	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090759	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090760	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090761	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090762	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090763	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090764	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090765	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090766	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090767	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090768	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090769	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090770	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090771	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090772	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090773	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090774	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090775	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090776	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090777	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090778	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090779	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090780	Soil	<20	0.60	0.014	0.04	0.2	0.27	0.7	0.5	<0.05	2	2.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090781	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090782	Soil		2.4	11.0	4.4	34	0.5	8.1	0.8	18	0.42	3.6	1.2	<0.1	9	0.8	0.9	<0.1	40	0.04	0.065	3
1090783	Soil		12.0	27.4	10.9	161	0.2	30.2	3.1	80	1.32	19.8	3.5	0.8	20	0.8	3.7	0.1	124	0.06	0.078	13
1090784	Soil		0.7	2.3	2.1	9	0.2	2.7	0.5	11	0.19	0.8	0.6	<0.1	5	<0.1	0.2	<0.1	10	0.03	0.010	1
1090785	Soil		4.4	6.8	9.6	45	0.2	7.9	1.9	66	1.49	12.6	2.0	0.7	10	0.2	1.3	0.2	92	0.04	0.036	14
1090786	Soil		3.2	8.3	4.6	44	0.3	10.1	1.2	23	0.47	4.7	2.4	0.1	13	0.7	1.1	<0.1	38	0.11	0.047	4
1090787	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090788	Soil		16.4	23.0	13.4	185	0.4	30.3	7.0	413	1.71	21.3	3.8	1.8	42	1.2	4.5	0.2	119	0.38	0.108	12
1090789	Soil		7.7	23.5	9.0	119	0.7	21.5	4.0	127	1.32	12.9	3.8	0.6	25	0.8	2.5	0.2	68	0.14	0.058	6
1090790	Soil		19.8	60.8	25.7	238	1.5	49.4	6.9	150	2.87	38.9	8.8	1.3	61	1.0	6.9	0.3	123	0.06	0.110	12
1090791	Soil		15.8	77.6	25.3	386	1.4	82.3	10.9	270	2.98	34.8	7.3	0.9	74	4.1	6.8	0.3	84	0.34	0.145	12
1090792	Soil		14.6	47.9	22.4	189	0.9	40.6	5.2	105	2.53	33.7	5.7	1.1	93	1.3	6.1	0.2	114	0.13	0.115	9
1090793	Soil		10.8	27.9	17.8	190	0.2	36.7	5.9	159	3.15	29.3	4.9	2.0	39	0.7	3.4	0.3	134	0.27	0.052	11
1090794	Soil		2.9	18.9	10.9	104	0.2	15.2	4.1	134	2.20	10.2	4.9	1.4	16	0.3	0.9	0.2	54	0.06	0.028	7
1090795	Soil		2.2	40.1	9.5	130	0.6	28.0	4.7	174	1.90	9.6	5.6	1.2	47	0.8	1.0	0.2	39	0.42	0.039	5
1090796	Soil		3.5	70.5	16.1	156	1.0	41.1	6.8	195	2.21	11.9	8.4	0.8	88	1.4	1.8	0.2	41	1.00	0.075	5
1090797	Soil		0.9	23.3	4.3	15	0.5	6.1	0.7	13	0.35	1.6	1.6	<0.1	10	0.8	0.3	<0.1	11	0.07	0.021	1
1090798	Soil		1.2	23.7	5.3	48	1.0	16.1	3.1	139	0.82	4.2	2.7	0.3	85	1.2	0.8	<0.1	25	1.14	0.062	5
1090799	Soil		1.9	16.7	6.3	49	0.4	8.7	1.5	36	0.67	5.7	1.0	0.5	13	0.7	0.9	0.2	22	0.08	0.023	4
1090800	Soil		2.3	119.3	12.8	94	0.9	24.1	2.6	33	1.29	10.7	3.1	0.3	52	1.0	1.8	0.2	23	0.43	0.042	4
1090801	Soil		12.3	20.2	10.4	97	0.3	22.4	5.9	233	1.76	19.2	2.3	1.4	25	0.5	2.4	0.2	54	0.21	0.079	8
1090802	Soil		15.1	35.4	15.1	177	0.4	40.0	9.6	226	2.39	21.5	2.4	2.4	30	1.1	3.4	0.2	66	0.22	0.099	11
1090803	Soil		15.2	41.3	10.3	223	0.6	69.7	7.2	279	1.85	23.1	2.1	1.4	33	1.2	3.6	0.2	69	0.32	0.090	9
1090804	Soil		34.0	44.6	12.1	248	0.5	102.5	8.1	176	2.02	35.4	1.7	2.4	70	1.7	4.7	0.2	70	1.39	0.117	13
1090805	Soil		29.3	54.5	12.4	497	0.8	107.7	8.2	203	2.27	38.3	3.1	2.1	88	3.6	9.7	0.2	103	1.17	0.145	11
1090806	Soil		13.9	93.8	8.3	423	0.7	112.4	5.4	247	1.42	21.5	3.0	0.8	117	7.1	5.7	0.1	76	2.12	0.084	6
1090807	Soil		12.4	47.6	14.2	317	0.4	68.5	11.0	232	2.70	30.4	3.1	2.0	37	3.0	5.0	0.2	96	0.22	0.119	15
1090808	Soil		12.0	26.8	43.6	160	0.3	35.7	5.2	71	2.13	28.9	1.4	0.5	31	0.7	4.2	0.3	80	0.08	0.129	11
1090809	Soil		9.5	31.0	18.1	185	0.4	40.9	7.1	135	3.23	32.1	1.5	1.7	22	0.5	3.5	0.2	90	0.06	0.099	9
1090810	Soil		17.5	56.0	15.7	505	0.2	96.4	9.2	122	2.85	63.8	4.2	2.3	15	0.8	8.4	0.2	81	0.13	0.076	22

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090781	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	13.6	34.9	20.5	114
1090782	Soil	7	0.03	304	0.002	<1	0.31	0.023	0.04	<0.1	0.08	0.2	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090783	Soil	18	0.10	416	0.005	1	0.68	0.008	0.08	0.2	0.11	1.2	0.4	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090784	Soil	4	0.01	24	0.006	<1	0.11	0.024	0.02	<0.1	<0.01	0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090785	Soil	14	0.09	106	0.015	1	0.70	0.005	0.04	0.1	0.01	0.7	0.2	<0.05	5	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090786	Soil	8	0.03	299	0.006	<1	0.25	0.022	0.04	<0.1	0.09	0.5	0.2	<0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090787	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.6	34.7	13.8	155
1090788	Soil	19	0.13	809	0.004	1	0.66	0.010	0.09	0.2	0.26	2.0	0.4	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090789	Soil	12	0.08	592	0.002	1	0.56	0.019	0.06	<0.1	0.30	1.5	0.4	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090790	Soil	25	0.12	772	0.003	3	0.80	0.005	0.10	0.2	0.61	2.3	0.5	0.05	3	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090791	Soil	18	0.10	1746	0.003	3	0.57	0.006	0.10	0.1	0.75	2.3	0.6	0.06	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090792	Soil	23	0.09	1068	0.003	3	0.63	0.005	0.10	0.2	0.34	2.1	0.5	0.08	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090793	Soil	27	0.21	603	0.004	<1	1.17	0.005	0.09	0.2	0.07	2.1	0.3	<0.05	4	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090794	Soil	20	0.17	391	0.005	<1	0.89	0.009	0.07	<0.1	0.04	1.4	0.2	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090795	Soil	27	0.25	1275	0.003	<1	1.01	0.016	0.06	<0.1	0.15	1.9	0.1	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090796	Soil	24	0.29	1782	0.003	2	1.01	0.010	0.05	<0.1	0.23	2.1	0.1	0.08	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090797	Soil	6	0.02	127	0.007	<1	0.23	0.023	0.02	<0.1	0.04	0.2	<0.1	<0.05	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090798	Soil	10	0.09	2297	0.006	<1	0.79	0.029	0.03	<0.1	0.15	1.0	0.1	0.07	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090799	Soil	8	0.03	321	0.006	3	0.29	0.012	0.04	<0.1	0.03	0.6	<0.1	0.08	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090800	Soil	10	0.07	810	0.006	2	0.58	0.012	0.03	0.1	0.07	1.2	<0.1	0.08	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090801	Soil	12	0.12	550	0.002	3	0.60	0.009	0.07	0.1	0.24	1.5	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090802	Soil	17	0.17	755	0.003	2	0.81	0.005	0.08	0.1	0.34	2.8	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090803	Soil	15	0.14	904	0.003	2	0.83	0.011	0.07	0.1	0.33	2.6	0.3	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090804	Soil	15	0.40	611	0.003	3	0.55	0.007	0.08	0.2	0.38	3.2	0.5	0.07	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090805	Soil	16	0.21	926	0.003	4	0.62	0.006	0.08	0.2	0.37	2.9	0.5	0.09	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090806	Soil	12	0.26	751	0.005	6	0.55	0.013	0.07	0.1	0.43	2.4	0.8	0.13	1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090807	Soil	19	0.20	829	0.004	2	0.91	0.003	0.07	0.2	0.20	2.4	0.4	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090808	Soil	12	0.05	189	0.005	1	0.42	0.003	0.07	0.2	0.03	0.8	0.3	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090809	Soil	19	0.14	292	0.003	1	0.99	0.004	0.07	0.2	0.13	2.0	0.3	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090810	Soil	15	0.07	286	0.002	3	0.54	0.002	0.07	<0.1	0.22	2.1	0.3	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090781	Soil		1.0	24.1	2.4	43	1.17	16.1	3.2	<0.1	17	3.3	1.5	0.2	120	0.04	0.061	8	18	0.04	445	0.002
1090782	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090783	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090784	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090785	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090786	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090787	Soil		0.6	41.7	5.8	263	1.10	11.5	10.2	0.6	51	5.9	1.8	0.2	64	0.62	0.095	7	26	0.10	1555	0.003
1090788	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090789	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090790	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090791	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090792	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090793	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090794	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090795	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090796	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090797	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090798	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090799	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090800	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090801	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090802	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090803	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090804	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090805	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090806	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090807	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090808	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090809	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090810	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090781	Soil	<20	0.77	0.009	0.06	0.2	0.29	0.5	0.5	<0.05	3	1.6	<0.2
1090782	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090783	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090784	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090785	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090786	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090787	Soil	<20	0.76	0.010	0.06	0.2	0.61	1.9	0.3	0.06	2	2.8	<0.2
1090788	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090789	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090790	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090791	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090792	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090793	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090794	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090795	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090796	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090797	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090798	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090799	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090800	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090801	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090802	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090803	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090804	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090805	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090806	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090807	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090808	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090809	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090810	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090811	Soil	33.6	20.9	9.6	258	0.3	67.1	6.7	335	2.14	56.7	1.5	1.9	123	0.9	2.8	0.1	90	1.81	0.045	10
1090812	Soil	26.7	36.0	11.0	305	0.3	85.8	9.8	176	2.27	38.9	2.2	2.5	55	1.6	4.1	0.2	144	0.73	0.085	15
1090813	Soil	20.7	31.7	14.7	222	0.1	56.6	5.9	120	2.67	42.6	2.1	1.2	21	0.5	4.6	0.2	131	0.10	0.158	16
1090814	Soil	11.7	28.5	10.4	165	0.1	42.8	6.1	125	1.86	25.4	2.8	1.0	20	0.8	3.1	0.1	79	0.10	0.097	12
1090815	Soil	9.7	22.1	12.2	143	0.2	35.6	6.1	130	2.11	25.0	1.8	1.0	24	1.0	2.8	0.2	74	0.21	0.079	13
1090816	Soil	7.0	32.7	12.8	136	0.4	30.1	7.5	258	3.07	24.6	1.8	1.5	11	0.5	2.3	0.3	52	0.04	0.079	18
1090817	Soil	17.0	49.5	19.4	274	0.8	55.6	8.2	189	2.84	18.3	2.9	0.5	22	0.7	2.6	0.3	63	0.09	0.141	16
1090818	Soil	14.5	31.3	12.7	132	0.6	38.7	5.6	214	1.54	17.4	3.0	1.8	77	1.1	2.3	0.2	61	1.11	0.112	10
1090819	Soil	13.7	46.0	15.0	269	0.5	61.0	9.3	207	2.48	26.0	2.4	2.6	46	2.0	4.4	0.2	78	0.42	0.132	15
1090820	Soil	19.1	33.4	13.4	582	1.1	95.5	9.0	190	2.31	26.0	3.0	2.4	68	3.1	4.1	0.2	75	0.73	0.128	15
1090821	Soil	10.3	28.7	14.4	162	0.4	32.1	5.1	110	2.08	23.0	2.1	0.4	21	1.0	2.8	0.2	86	0.06	0.091	10
1090822	Soil	9.7	31.4	17.2	238	0.8	53.1	7.6	160	2.59	27.2	2.3	1.4	25	1.4	3.5	0.3	90	0.08	0.097	11
1090823	Soil	11.1	49.7	16.4	287	0.4	55.4	8.5	176	2.65	26.1	2.1	2.5	44	2.3	4.3	0.3	78	0.21	0.116	14
1090824	Soil	28.9	69.8	16.5	609	0.8	123.1	6.8	110	2.42	32.1	3.6	2.2	142	9.2	9.2	0.2	136	0.30	0.160	13
1090825	Soil	23.1	46.2	17.0	168	0.8	38.3	4.9	129	2.41	32.8	5.4	0.8	47	1.2	7.9	0.2	107	0.10	0.119	10
1090826	Soil	49.8	36.7	21.7	125	1.1	31.4	2.5	49	1.86	29.7	3.1	2.0	74	0.8	8.9	0.2	131	0.07	0.100	16
1090827	Soil	13.5	58.1	17.4	308	1.1	76.1	17.9	463	3.15	60.4	11.0	2.1	69	4.3	7.5	0.2	95	0.40	0.158	12
1090828	Soil	9.6	60.2	18.0	427	1.4	79.5	11.0	333	2.44	53.9	10.0	1.9	93	4.1	6.4	0.3	95	0.53	0.154	11
1090829	Soil	10.8	58.7	17.5	443	0.9	81.1	11.3	208	1.84	33.1	6.4	1.5	85	6.4	9.1	0.2	135	0.34	0.175	8
1090830	Soil	9.2	22.4	15.0	125	0.5	25.6	3.0	95	1.70	29.5	4.7	1.0	78	1.2	5.7	0.2	118	0.29	0.136	8
1090832	Soil	8.6	38.2	17.6	222	0.4	41.4	10.1	249	2.81	29.5	4.7	2.1	45	1.6	4.2	0.3	98	0.12	0.094	12
1090833	Soil	9.2	33.4	18.1	204	0.5	42.6	7.6	165	2.65	28.7	3.2	2.8	32	1.2	3.7	0.3	94	0.05	0.064	12
1090834	Soil	9.1	42.8	18.3	226	0.9	55.3	10.1	202	3.39	28.5	4.6	2.7	34	1.6	3.7	0.3	81	0.11	0.096	9
1090835	Soil	1.0	7.4	3.6	24	0.1	4.5	1.0	21	0.91	2.9	2.8	0.2	4	<0.1	0.5	0.1	31	0.02	0.014	3
1090836	Soil	0.7	6.4	3.2	18	0.2	3.9	1.0	32	0.63	2.1	2.6	0.2	4	0.2	0.3	<0.1	14	0.02	0.017	<1
1090837	Soil	0.5	5.1	2.6	13	0.6	3.1	0.6	16	0.27	1.9	1.0	<0.1	12	0.2	0.4	<0.1	10	0.08	0.021	1
1090838	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090839	Soil	4.4	23.9	9.9	60	0.2	25.3	6.5	231	1.72	10.3	2.0	0.3	6	0.1	1.5	0.3	32	0.02	0.051	13
1090840	Soil	2.4	47.1	12.7	40	<0.1	32.3	10.9	269	2.57	7.3	1.1	0.4	5	<0.1	0.9	0.2	10	0.03	0.047	10
1091301	Soil	3.2	34.4	9.7	131	<0.1	39.5	18.1	197	4.47	11.2	<0.5	2.3	5	0.3	1.5	0.4	32	0.03	0.028	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090811	Soil	17	0.89	545	0.002	1	0.62	0.004	0.05	0.2	0.14	1.9	0.4	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090812	Soil	23	0.21	552	0.002	3	0.89	0.006	0.07	0.2	0.15	2.7	0.5	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090813	Soil	18	0.08	270	0.004	3	0.70	0.003	0.09	0.2	0.06	1.3	0.5	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090814	Soil	14	0.08	395	0.002	1	0.69	0.006	0.06	0.1	0.14	1.2	0.3	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090815	Soil	14	0.11	416	0.006	1	0.71	0.005	0.07	0.1	0.09	1.2	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090816	Soil	16	0.12	196	0.004	2	0.92	0.006	0.07	0.1	0.06	1.4	0.2	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090817	Soil	12	0.06	346	0.003	4	0.59	0.008	0.10	<0.1	0.20	1.1	0.5	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090818	Soil	17	0.21	875	0.004	3	0.71	0.009	0.07	0.1	0.31	2.7	0.3	0.06	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090819	Soil	20	0.24	963	0.006	2	0.86	0.006	0.09	0.2	0.30	3.2	0.3	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090820	Soil	18	0.15	889	0.002	3	0.68	0.004	0.09	0.1	0.44	3.3	0.4	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090821	Soil	16	0.10	554	0.004	<1	0.78	0.007	0.07	0.1	0.12	0.9	0.3	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090822	Soil	19	0.14	361	0.004	1	1.06	0.005	0.07	0.1	0.13	1.8	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090823	Soil	20	0.19	1102	0.005	2	0.82	0.003	0.07	0.1	0.25	3.0	0.3	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090824	Soil	24	0.14	1340	0.003	2	0.72	0.003	0.08	0.2	0.55	3.2	1.3	0.05	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090825	Soil	21	0.11	1212	0.004	2	0.79	0.005	0.08	0.2	0.52	1.7	0.7	<0.05	3	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090826	Soil	20	0.09	838	0.003	3	0.53	0.003	0.08	0.4	0.91	1.6	2.5	0.06	3	6.6	0.4	N.A.	N.A.	N.A.	N.A.
1090827	Soil	27	0.16	2438	0.001	4	0.86	0.003	0.08	0.1	2.26	3.7	0.5	0.05	2	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090828	Soil	25	0.16	2193	0.002	4	0.83	0.004	0.08	0.1	2.12	3.6	0.4	0.07	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090829	Soil	25	0.10	1959	0.002	2	0.66	0.002	0.07	0.1	1.17	3.0	0.5	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090830	Soil	22	0.06	1670	0.002	4	0.51	0.003	0.09	0.1	0.22	1.2	0.4	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090832	Soil	23	0.17	1977	0.004	3	1.07	0.005	0.08	0.1	0.21	2.2	0.3	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090833	Soil	21	0.15	858	0.004	2	1.08	0.004	0.07	0.1	0.15	2.2	0.4	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090834	Soil	21	0.17	7574	0.003	3	1.60	0.005	0.09	0.1	0.33	3.4	0.5	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090835	Soil	8	0.03	110	0.005	<1	0.34	0.008	0.02	<0.1	0.01	0.3	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090836	Soil	5	0.02	196	0.007	<1	0.22	0.014	0.02	<0.1	0.03	0.4	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090837	Soil	3	0.01	402	0.004	<1	0.19	0.017	0.02	<0.1	0.05	0.4	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090838	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.2	24.0	10.7	86
1090839	Soil	12	0.03	143	0.003	2	0.43	0.006	0.05	0.1	0.04	0.4	0.1	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090840	Soil	10	0.02	143	0.004	<1	0.20	0.011	0.04	<0.1	0.03	1.3	<0.1	<0.05	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091301	Soil	10	0.07	707	0.004	1	0.83	0.009	0.06	0.1	0.02	2.3	0.1	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090811	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090812	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090813	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090814	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090815	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090816	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090817	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090818	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090819	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090820	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090821	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090822	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090823	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090824	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090825	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090826	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090827	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090828	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090829	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090830	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090832	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090833	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090834	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090835	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090836	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090837	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090838	Soil	0.4	15.3	2.5	75	1.33	12.3	2.6	0.2	14	0.5	0.8	0.2	60	0.04	0.052	7	14	0.06	496	0.003
1090839	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090840	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091301	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090811	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090812	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090813	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090814	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090815	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090816	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090817	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090818	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090819	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090820	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090821	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090822	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090823	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090824	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090825	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090826	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090827	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090828	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090829	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090830	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090832	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090833	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090834	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090835	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090836	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090837	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090838	Soil	<20	0.64	0.006	0.06	0.1	0.19	0.6	0.2	<0.05	3	0.9	<0.2
1090839	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090840	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091301	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091302	Soil	5.5	31.1	11.6	147	<0.1	31.9	9.9	111	2.55	16.9	1.2	1.0	9	0.2	2.0	0.3	53	0.06	0.042	12
1091303	Soil	2.6	14.5	5.3	26	0.5	7.8	1.3	23	0.52	4.0	0.9	0.1	8	0.6	0.5	<0.1	18	0.04	0.073	5
1091304	Soil	9.4	31.6	22.6	167	0.3	44.1	7.3	88	3.08	25.0	1.9	1.3	15	0.3	3.0	0.3	67	0.03	0.080	8
1091305	Soil	8.3	16.9	15.2	85	0.5	22.9	3.5	51	1.25	14.6	0.9	0.1	16	0.1	1.9	0.2	49	0.01	0.063	4
1091306	Soil	4.3	18.9	12.1	124	1.1	30.1	7.7	836	5.24	9.3	2.4	1.2	48	0.5	2.9	0.1	26	0.57	0.063	8
1091307	Soil	5.4	37.3	13.7	145	1.2	41.3	7.9	111	3.69	11.1	1.2	2.1	9	0.1	1.7	0.3	53	0.03	0.080	20
1091308	Soil	3.8	32.4	11.5	149	1.0	40.6	7.3	189	2.51	7.4	1.7	0.4	13	0.2	1.3	0.2	45	0.06	0.120	8
1091309	Soil	4.8	31.0	19.4	143	0.6	33.9	6.3	166	2.26	18.3	3.2	1.2	30	0.2	2.0	0.3	40	0.15	0.159	13
1091310	Soil	3.3	42.0	11.9	159	0.1	48.3	13.0	151	4.23	44.7	1.1	1.1	5	0.1	2.6	0.3	29	0.03	0.071	9
1091311	Soil	9.8	61.2	17.3	156	0.8	66.6	13.4	267	3.37	23.6	7.2	3.0	25	0.8	3.0	0.3	22	0.26	0.061	15
1091312	Soil	9.7	34.1	16.9	187	0.5	49.0	9.8	222	2.77	26.3	2.5	1.9	13	0.3	4.2	0.3	46	0.04	0.078	22
1091313	Soil	3.9	41.1	10.0	119	1.3	35.1	9.6	173	2.75	16.1	2.2	0.9	18	0.7	2.2	0.2	31	0.13	0.087	8
1091314	Soil	9.8	24.6	5.2	278	0.2	59.6	4.9	154	1.00	16.5	3.2	0.5	46	1.4	1.6	<0.1	21	1.31	0.057	4
1091315	Soil	16.0	28.0	12.9	239	0.4	54.1	6.1	80	2.53	52.8	6.1	2.0	33	1.8	5.0	0.2	82	0.35	0.060	10
1091316	Soil	18.6	22.9	15.8	168	0.6	44.8	4.3	58	2.08	49.4	6.0	0.8	14	0.3	4.6	0.3	97	0.03	0.063	11
1091317	Soil	7.0	46.1	20.8	89	0.4	21.7	2.9	63	2.57	31.0	5.0	1.5	26	0.3	4.3	0.2	120	0.04	0.056	7
1091318	Soil	13.3	37.8	19.8	89	2.8	23.4	3.4	62	2.51	59.9	11.5	0.1	17	0.9	5.6	0.3	204	0.03	0.135	6
1091319	Soil	9.0	55.7	14.0	197	1.1	48.0	6.6	125	2.75	25.3	6.5	1.0	58	1.4	4.0	0.2	93	0.49	0.128	6
1091320	Soil	9.2	28.1	17.7	90	0.9	23.2	4.8	156	2.84	25.4	4.0	0.2	36	0.4	4.0	0.3	95	0.06	0.113	7
1091321	Soil	4.8	13.0	10.4	41	2.4	9.6	2.2	35	1.06	10.7	4.7	0.4	9	<0.1	1.8	0.2	77	0.02	0.021	15
1091322	Soil	3.2	11.0	12.2	50	0.8	9.1	2.3	68	1.32	12.7	1.0	0.2	12	<0.1	1.0	0.2	54	0.03	0.034	12
1091323	Soil	3.4	19.4	10.9	76	0.8	20.1	3.4	37	1.57	12.5	0.8	0.2	18	0.1	1.3	0.2	50	<0.01	0.039	7
1091324	Soil	3.4	23.1	10.6	103	0.6	23.3	3.9	41	1.76	12.9	0.9	0.1	13	0.2	1.3	0.2	42	0.01	0.061	6
1091325	Soil	4.4	27.2	14.4	110	0.7	20.1	4.1	118	2.02	17.8	1.8	0.3	12	0.5	1.9	0.3	61	0.02	0.076	9
1091326	Soil	4.8	35.6	13.8	143	1.0	35.1	6.7	212	2.20	15.0	6.8	1.2	51	1.1	1.8	0.2	55	0.91	0.089	8
1091327	Soil	3.3	39.1	10.1	124	1.0	30.7	9.1	480	1.78	18.6	7.7	0.8	86	1.6	2.0	0.2	52	2.00	0.113	7
1091328	Soil	3.7	23.1	10.0	104	0.4	21.0	3.2	86	1.56	12.4	3.2	0.9	31	1.9	1.5	0.2	42	0.46	0.055	5
1091329	Soil	1.7	22.0	6.9	49	0.8	16.5	2.4	121	1.00	7.5	2.3	0.3	55	0.8	1.2	0.1	31	1.43	0.080	5
1091330	Soil	3.9	17.3	18.0	83	0.3	15.5	3.2	149	2.63	15.4	2.0	0.5	10	0.6	1.4	0.3	74	0.02	0.079	7
1091331	Soil	5.1	19.8	16.9	80	0.5	16.9	4.2	97	2.43	17.3	2.2	0.2	13	0.3	1.6	0.3	74	0.03	0.076	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091302	Soil	10	0.05	250	0.005	<1	0.62	0.003	0.06	0.1	0.03	1.4	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091303	Soil	8	0.02	480	0.002	1	0.55	0.011	0.02	<0.1	0.07	0.3	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091304	Soil	14	0.05	682	0.004	2	0.69	0.003	0.07	0.1	0.04	1.7	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091305	Soil	8	0.02	489	0.001	2	0.45	0.005	0.05	<0.1	0.03	0.3	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091306	Soil	12	0.14	3724	0.004	2	1.00	0.008	0.05	<0.1	0.14	2.8	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091307	Soil	12	0.05	680	0.007	2	0.83	0.002	0.07	0.1	0.04	1.3	0.2	<0.05	5	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091308	Soil	11	0.05	1209	0.004	<1	0.89	0.009	0.06	<0.1	0.05	0.7	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091309	Soil	15	0.07	1113	0.008	2	0.80	0.005	0.09	0.2	0.09	1.3	0.3	0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091310	Soil	14	0.04	182	0.008	2	0.61	0.015	0.05	0.1	0.07	2.3	0.2	0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091311	Soil	6	0.07	1167	0.002	4	0.48	0.004	0.11	<0.1	0.33	3.6	0.2	<0.05	1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091312	Soil	12	0.07	325	0.006	2	0.48	0.002	0.09	0.2	0.09	2.2	0.3	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091313	Soil	9	0.05	2147	0.006	<1	1.39	0.010	0.05	0.1	0.17	2.4	0.2	0.06	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091314	Soil	7	0.09	228	0.005	3	0.42	0.020	0.03	<0.1	0.36	1.4	0.7	0.09	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091315	Soil	17	0.14	540	0.002	<1	0.72	0.004	0.06	0.2	0.41	1.6	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091316	Soil	16	0.06	163	0.005	<1	0.61	0.004	0.05	0.2	0.32	1.2	0.4	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091317	Soil	21	0.11	454	0.002	1	1.03	0.002	0.06	0.1	0.87	1.8	0.4	<0.05	3	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091318	Soil	28	0.06	379	0.003	1	0.92	0.007	0.08	0.2	1.69	0.3	0.7	0.05	5	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091319	Soil	21	0.14	2738	0.002	4	0.97	0.005	0.10	0.2	0.47	2.7	0.4	0.11	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091320	Soil	18	0.10	600	0.004	<1	0.88	0.005	0.07	0.2	0.13	0.6	0.4	0.10	4	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091321	Soil	9	0.03	118	0.016	<1	0.53	0.004	0.03	0.2	0.04	0.5	0.2	<0.05	5	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091322	Soil	11	0.05	146	0.011	<1	0.55	0.004	0.05	0.1	0.02	0.4	0.2	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091323	Soil	8	0.02	146	0.005	1	0.43	0.006	0.06	0.1	0.06	0.7	0.1	0.06	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091324	Soil	11	0.02	154	0.003	1	0.39	0.004	0.05	<0.1	0.08	0.6	0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091325	Soil	15	0.04	445	0.003	1	0.65	0.003	0.06	0.1	0.10	0.6	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091326	Soil	28	0.18	2154	0.004	4	1.00	0.007	0.06	0.2	0.39	3.0	0.2	0.06	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091327	Soil	20	0.16	2575	0.005	2	1.12	0.008	0.06	0.1	0.53	2.3	0.2	0.12	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091328	Soil	14	0.11	1039	0.003	2	0.61	0.006	0.06	0.1	0.13	1.3	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091329	Soil	11	0.07	2246	0.006	<1	0.68	0.011	0.03	0.1	0.19	1.1	0.1	0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091330	Soil	16	0.07	261	0.007	<1	1.02	0.003	0.03	0.1	0.06	0.8	0.1	<0.05	4	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091331	Soil	17	0.11	335	0.005	<1	1.02	0.003	0.03	0.2	0.06	0.5	0.2	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091302	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091303	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091304	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091305	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091306	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091307	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091308	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091309	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091310	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091311	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091320	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091323	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091326	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091327	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091328	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091329	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091330	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091331	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091302	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091303	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091304	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091305	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091306	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091307	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091308	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091309	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091310	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091311	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091320	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091323	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091326	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091327	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091328	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091329	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091330	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091331	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091332	Soil	2.4	5.9	10.9	5	0.5	2.9	0.2	6	0.35	2.6	0.6	0.7	36	<0.1	2.1	0.2	20	0.02	0.023	<1
1091333	Soil	3.5	16.9	11.8	35	2.2	9.4	2.4	65	1.49	14.4	1.4	<0.1	17	<0.1	1.4	0.2	62	0.04	0.090	6
1091334	Soil	9.5	28.2	18.4	139	1.3	23.4	3.9	124	3.06	41.5	9.6	0.6	39	0.4	5.8	0.3	126	0.02	0.124	7
1091335	Soil	9.4	34.2	20.6	103	1.9	19.6	3.5	115	2.31	37.1	9.6	<0.1	39	0.5	9.3	0.3	149	0.04	0.147	6
1091336	Soil	9.2	49.5	14.6	267	0.7	43.8	7.8	196	3.09	22.5	5.1	0.8	24	0.8	4.2	0.2	99	0.06	0.129	12
1091337	Soil	6.0	29.1	11.3	132	0.4	19.1	3.3	85	1.53	12.7	2.2	0.1	27	0.8	2.4	0.2	80	0.05	0.088	7
1091338	Soil	5.4	18.8	10.7	49	1.2	9.5	1.7	31	1.05	7.8	0.9	<0.1	18	4.1	2.2	0.2	71	0.02	0.067	6
1091339	Soil	8.9	24.0	15.6	66	0.3	12.5	2.4	28	1.40	22.6	1.8	0.3	34	0.6	2.7	0.2	81	0.02	0.067	6
1091340	Soil	4.1	8.6	12.8	27	3.7	9.8	0.7	15	0.69	6.3	8.5	<0.1	48	0.2	4.0	0.2	29	0.19	0.054	3
1091341	Soil	13.1	57.4	19.8	242	0.7	51.8	5.4	76	4.21	46.7	4.1	1.5	48	0.7	2.1	0.3	79	0.04	0.097	4
1091342	Soil	4.6	26.6	13.1	120	1.0	24.7	4.2	102	2.50	19.6	4.8	0.7	11	0.1	2.5	0.2	69	0.02	0.046	7
1091343	Soil	3.9	23.5	11.0	84	0.2	15.4	2.7	52	1.83	12.5	1.7	0.2	10	0.3	1.3	0.2	53	0.03	0.088	6
1091344	Soil	3.8	28.3	12.0	152	0.5	29.6	4.5	106	2.04	15.1	3.1	0.5	27	0.9	2.2	0.2	57	0.24	0.071	7
1091345	Soil	3.7	37.6	12.1	187	0.8	41.9	6.7	160	2.24	15.7	5.3	1.4	58	1.4	2.7	0.2	57	0.73	0.090	7
1091346	Soil	8.9	37.7	12.6	379	0.3	47.7	8.2	302	2.91	16.4	1.4	0.4	35	2.3	2.5	0.2	56	0.35	0.198	7
1091347	Soil	4.8	25.1	16.7	153	0.1	29.9	5.4	163	3.01	23.3	1.8	1.4	25	0.7	3.0	0.3	82	0.08	0.093	9
1091348	Soil	4.2	14.5	11.8	104	<0.1	17.2	3.6	119	1.99	16.1	1.0	1.0	12	0.4	2.0	0.2	66	0.04	0.046	9
1091349	Soil	4.1	24.7	13.3	158	0.2	26.8	4.9	130	2.38	16.2	3.3	1.6	23	0.8	2.3	0.2	70	0.11	0.041	10
1091350	Soil	12.9	67.3	58.4	245	0.7	72.4	8.9	404	8.51	56.9	3.2	1.4	27	0.5	5.5	0.4	139	0.05	0.260	5
1091351	Soil	0.6	2.9	1.6	8	0.1	2.3	0.7	13	0.27	1.3	<0.5	<0.1	3	<0.1	0.3	<0.1	9	0.01	0.020	3
1091352	Soil	15.8	42.4	16.3	207	0.2	65.6	12.0	198	3.96	36.0	2.4	2.8	17	0.4	5.6	0.4	86	0.04	0.043	14
1091353	Soil	3.9	23.7	7.0	58	0.1	19.3	4.7	79	1.86	8.1	1.4	3.0	6	<0.1	1.6	0.2	43	0.03	0.022	14
1091354	Soil	4.7	39.9	15.8	115	0.2	40.9	12.2	200	4.10	17.7	0.6	4.8	13	0.2	2.6	0.4	40	0.03	0.039	17
1091355	Soil	4.9	41.6	17.1	130	1.1	37.3	12.2	413	3.13	18.6	3.5	2.7	60	0.3	3.1	0.3	18	0.85	0.068	10
1091356	Soil	1.8	13.9	5.7	25	<0.1	13.7	3.3	57	1.09	2.2	<0.5	0.8	6	0.2	0.6	0.2	17	0.04	0.037	6
1091357	Soil	6.7	47.2	14.8	190	1.1	50.1	10.2	316	3.07	18.2	5.5	2.8	44	0.9	3.5	0.2	32	0.41	0.089	12
1091358	Soil	11.1	54.3	22.6	161	1.0	38.8	21.4	968	3.45	32.8	4.7	1.6	28	0.8	5.3	0.3	59	0.16	0.115	16
1091359	Soil	6.3	52.0	21.4	134	0.8	45.9	10.1	224	2.26	12.3	3.1	1.1	39	0.7	2.3	0.2	32	0.23	0.189	14
1091360	Soil	6.5	30.4	19.9	131	0.5	40.4	7.6	153	2.50	13.2	3.3	1.3	20	0.2	2.2	0.3	32	0.08	0.140	14
1091361	Soil	8.1	60.2	27.4	193	1.0	67.4	12.0	374	2.88	18.0	4.8	1.0	56	0.9	3.4	0.3	42	0.52	0.225	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091332	Soil	6	<0.01	406	<0.001	1	0.24	0.002	0.05	<0.1	0.16	0.6	0.3	0.07	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091333	Soil	13	0.08	278	0.002	<1	0.84	0.007	0.03	0.1	0.08	0.1	0.2	<0.05	5	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091334	Soil	21	0.09	373	0.006	2	0.71	0.004	0.08	0.3	0.21	1.2	0.6	0.08	4	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091335	Soil	26	0.10	623	0.004	2	0.92	0.007	0.10	0.3	0.11	0.4	0.9	0.09	5	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091336	Soil	19	0.18	423	0.003	1	1.12	0.004	0.07	0.2	0.14	0.9	0.2	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091337	Soil	13	0.06	358	0.001	<1	0.60	0.007	0.06	0.2	0.06	0.2	0.2	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091338	Soil	9	0.02	355	0.002	<1	0.52	0.007	0.04	0.1	0.05	0.2	0.3	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091339	Soil	10	0.02	4024	0.004	<1	0.42	0.003	0.05	0.2	0.04	0.5	0.4	0.09	3	1.5	0.3	N.A.	N.A.	N.A.	N.A.
1091340	Soil	13	0.03	821	0.002	4	0.35	0.021	0.05	0.3	0.48	0.4	0.2	0.09	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091341	Soil	49	0.07	842	0.001	2	0.98	0.004	0.08	<0.1	0.10	3.4	0.1	0.11	3	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091342	Soil	15	0.06	230	0.003	1	0.64	0.003	0.05	0.1	0.09	1.2	0.1	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091343	Soil	14	0.05	259	0.003	<1	0.71	0.005	0.04	0.1	0.06	0.4	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091344	Soil	18	0.15	1002	0.003	1	0.96	0.008	0.06	<0.1	0.17	1.1	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091345	Soil	23	0.20	1788	0.003	2	0.96	0.007	0.07	0.1	0.63	2.4	0.2	0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091346	Soil	26	0.21	649	0.004	2	1.13	0.005	0.06	0.2	0.16	0.9	0.2	0.06	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091347	Soil	22	0.18	515	0.004	1	0.97	0.003	0.06	0.1	0.09	1.6	0.2	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091348	Soil	13	0.09	200	0.007	2	0.61	0.005	0.05	0.2	0.05	1.0	0.1	<0.05	4	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091349	Soil	19	0.15	1026	0.004	1	1.05	0.005	0.06	0.1	0.11	1.6	0.2	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091350	Soil	38	0.14	259	0.009	2	1.18	0.004	0.08	0.1	0.08	3.0	0.2	<0.05	7	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091351	Soil	3	0.01	39	0.006	<1	0.19	0.018	0.02	<0.1	0.03	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091352	Soil	18	0.15	653	0.004	2	1.01	0.003	0.09	0.2	0.09	2.5	0.4	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091353	Soil	11	0.04	531	0.008	<1	0.70	0.007	0.06	0.1	0.05	1.2	0.1	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091354	Soil	15	0.16	503	0.008	2	0.89	0.003	0.10	0.1	0.05	2.5	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091355	Soil	7	0.18	1015	0.003	2	0.52	0.008	0.07	<0.1	0.21	3.7	0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091356	Soil	12	0.04	417	0.007	3	0.36	0.015	0.04	<0.1	0.03	1.1	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091357	Soil	15	0.12	2757	0.004	2	0.63	0.009	0.12	<0.1	0.34	4.1	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091358	Soil	15	0.10	1467	0.003	3	0.79	0.004	0.11	<0.1	0.48	2.8	0.4	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091359	Soil	11	0.07	1613	0.003	3	0.63	0.007	0.10	0.1	0.22	2.1	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091360	Soil	15	0.07	751	0.002	4	0.56	0.003	0.09	<0.1	0.12	1.6	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091361	Soil	15	0.12	1911	0.004	4	0.62	0.006	0.12	<0.1	0.23	2.0	0.2	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091332	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091333	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091334	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091335	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091336	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091337	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091338	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091339	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091340	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091341	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091342	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091343	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091344	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091345	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091346	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091347	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091348	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091349	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091350	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091351	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091352	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091353	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091354	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091355	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091356	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091357	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091358	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091359	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091360	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091361	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091332	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091333	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091334	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091335	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091336	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091338	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091340	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091341	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091342	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091343	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091344	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091345	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091346	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091347	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091348	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091349	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091350	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091351	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091352	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091353	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091354	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091355	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091356	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091357	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091358	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091359	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091360	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091361	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091362	Soil	5.3	18.1	18.3	93	0.1	22.9	4.2	66	1.54	14.5	1.7	0.1	13	0.1	2.3	0.3	59	0.02	0.061	10
1091363	Soil	6.0	16.7	6.1	85	0.1	20.9	3.8	50	1.19	13.3	0.9	0.9	6	<0.1	1.9	0.1	62	0.02	0.038	9
1091364	Soil	3.7	35.0	15.4	146	0.6	42.9	10.5	317	2.39	11.4	2.3	2.5	38	0.3	1.9	0.2	35	0.37	0.148	17
1091365	Soil	10.5	147.6	113.5	196	2.0	80.1	8.6	239	3.46	38.7	10.2	4.0	212	0.5	8.0	0.7	96	0.94	0.854	36
1091366	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091367	Soil	5.4	15.9	13.2	45	0.6	9.0	2.0	30	0.86	24.2	1.0	0.2	17	0.1	2.5	0.3	96	0.01	0.030	13
1091368	Soil	6.4	18.3	14.7	74	0.3	16.2	3.7	66	2.48	21.5	2.8	1.4	18	0.1	2.3	0.3	97	0.03	0.056	9
1091369	Soil	13.1	23.5	24.8	61	4.1	11.3	2.5	36	1.88	32.2	2.3	0.7	38	0.2	8.4	0.4	103	0.01	0.046	7
1091370	Soil	12.7	35.6	27.4	89	1.0	15.1	3.5	59	2.13	57.9	3.2	0.2	22	0.3	13.0	0.4	169	0.02	0.070	11
1091371	Soil	7.4	16.8	14.5	83	<0.1	14.4	3.1	42	1.31	16.0	1.3	0.3	21	0.5	2.2	0.3	109	0.03	0.029	10
1091372	Soil	3.4	9.7	8.5	35	0.3	6.1	1.5	30	0.88	11.3	1.6	1.2	24	<0.1	1.3	0.3	52	0.10	0.017	11
1091373	Soil	8.9	92.0	18.2	141	1.4	37.6	7.6	208	5.15	26.2	6.7	1.6	39	0.6	3.9	0.3	75	0.03	0.199	6
1091374	Soil	6.1	23.9	19.9	95	0.5	18.8	3.5	78	2.89	34.0	30.4	0.4	19	0.2	2.2	0.3	87	0.03	0.111	6
1091375	Soil	3.8	38.5	14.7	56	1.0	11.1	2.4	94	1.96	12.7	3.2	0.7	20	0.2	1.3	0.2	52	0.03	0.065	7
1091376	Soil	4.0	18.7	9.0	123	0.5	48.9	9.0	111	2.62	12.0	3.0	0.6	6	0.3	1.3	0.2	61	0.01	0.053	6
1091377	Soil	4.5	14.3	12.3	59	0.4	11.9	2.6	67	1.41	11.2	0.5	1.0	13	0.2	1.4	0.2	70	0.03	0.051	10
1091378	Soil	6.9	54.5	18.6	186	0.4	53.0	9.7	228	3.30	24.3	6.3	2.6	31	0.6	3.7	0.3	75	0.08	0.076	8
1091379	Soil	7.1	27.3	18.6	158	0.4	34.1	6.6	236	4.01	26.5	2.3	2.5	17	0.4	3.2	0.3	104	0.04	0.142	9
1091380	Soil	3.5	47.9	14.4	156	0.9	59.4	10.6	454	2.54	14.9	3.9	1.0	55	5.8	2.1	0.4	58	1.27	0.126	9
1091381	Soil	4.9	43.9	15.8	147	0.9	44.9	9.3	248	3.36	20.6	6.8	3.5	23	0.5	2.3	0.3	69	0.10	0.090	9
1091382	Soil	7.3	22.3	17.1	137	0.3	26.3	5.6	183	3.61	22.1	2.9	2.8	13	0.9	2.6	0.3	103	0.03	0.075	11
1091383	Soil	4.5	23.6	14.3	127	0.7	15.5	4.9	165	2.52	8.9	1.5	1.4	9	0.5	1.5	0.3	71	0.02	0.054	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091362	Soil	13	0.04	233	0.005	2	0.45	0.003	0.06	0.2	0.04	0.3	0.2	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091363	Soil	9	0.04	336	0.003	3	0.40	0.005	0.06	0.1	0.03	1.0	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091364	Soil	16	0.28	1607	0.014	2	0.76	0.004	0.11	0.1	0.09	2.5	0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091365	Soil	29	0.10	2272	0.009	11	1.07	0.005	0.27	<0.1	0.35	4.2	0.5	0.27	2	4.1	0.3	N.A.	N.A.	N.A.	N.A.
1091366	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.3	51.3	19.7	85
1091367	Soil	10	0.02	274	0.006	2	0.41	0.002	0.03	0.2	0.50	0.2	0.3	<0.05	5	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091368	Soil	19	0.11	317	0.006	2	0.95	0.003	0.05	0.2	0.05	1.3	0.2	<0.05	5	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091369	Soil	13	0.02	360	0.008	1	0.45	0.006	0.13	0.2	0.17	0.7	1.0	0.23	4	13.1	0.3	N.A.	N.A.	N.A.	N.A.
1091370	Soil	26	0.02	195	0.006	<1	0.40	0.002	0.05	0.2	0.51	0.4	0.4	0.05	6	9.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091371	Soil	11	0.02	1235	0.004	2	0.46	0.003	0.04	0.2	0.02	0.5	0.2	0.07	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091372	Soil	8	0.03	5282	0.014	<1	0.47	0.004	0.03	0.1	0.03	0.6	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091373	Soil	40	0.10	523	0.004	1	1.34	0.005	0.08	0.2	0.17	2.5	0.2	0.10	4	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091374	Soil	18	0.09	294	0.005	2	0.88	0.004	0.06	0.1	0.07	0.9	0.2	<0.05	4	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091375	Soil	21	0.08	311	0.004	1	0.88	0.007	0.06	0.1	0.08	1.8	0.2	0.06	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091376	Soil	11	0.03	143	0.003	1	0.62	0.005	0.03	0.1	0.03	1.4	0.1	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091377	Soil	12	0.05	290	0.005	1	0.76	0.004	0.05	0.1	0.01	0.9	0.2	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091378	Soil	29	0.24	1092	0.001	2	1.16	0.004	0.06	<0.1	0.17	2.3	0.2	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091379	Soil	30	0.22	581	0.004	2	1.26	0.003	0.07	0.1	0.04	2.3	0.2	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091380	Soil	27	0.26	1932	0.007	3	1.24	0.005	0.06	0.2	0.32	2.4	0.2	0.11	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091381	Soil	34	0.25	675	0.003	2	1.72	0.004	0.06	<0.1	0.19	2.4	0.2	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091382	Soil	23	0.12	542	0.005	2	1.09	0.003	0.06	0.2	0.03	1.6	0.2	<0.05	5	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091383	Soil	19	0.07	648	0.007	2	1.14	0.009	0.06	0.1	0.03	1.3	0.1	<0.05	5	0.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091362	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091363	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091364	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091365	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091366	Soil	0.8	54.0	20.3	347	4.73	17.5	6.5	1.1	39	0.3	1.5	0.4	25	0.33	0.101	11	18	0.11	2512	0.003
1091367	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091368	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091369	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091370	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091371	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091372	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091373	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091374	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091375	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091376	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091377	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091378	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091379	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091380	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091381	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091382	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091383	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000601.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091362	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091363	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091364	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091365	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091366	Soil	<20	0.73	0.005	0.09	0.1	0.24	4.0	0.2	<0.05	2	2.3	<0.2
1091367	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091368	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091369	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091370	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091371	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091372	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091373	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091374	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091375	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091376	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091377	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091378	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091379	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091380	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091381	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091382	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091383	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1090603	Soil	8.9	34.0	5.5	180	0.6	38.0	2.1	46	0.76	18.0	2.4	0.2	54	3.2	2.8	<0.1	120	0.99	0.064	6
REP 1090603	QC	9.7	34.6	5.8	189	0.6	40.0	2.2	49	0.85	18.7	2.7	0.3	56	3.5	2.9	<0.1	121	1.03	0.066	6
1090621	Soil	11.6	25.7	17.6	159	0.5	28.5	4.0	110	2.19	57.0	1.3	1.2	65	0.6	4.7	0.2	110	0.06	0.116	8
REP 1090621	QC	13.4	27.7	19.2	181	0.6	32.6	4.5	122	2.47	64.5	1.2	1.5	73	0.9	5.4	0.3	127	0.05	0.136	10
1090647	Soil	9.6	27.7	4.3	322	0.5	45.9	3.1	123	1.01	9.5	1.1	0.8	58	5.0	5.0	0.1	69	1.70	0.075	6
REP 1090647	QC	10.7	28.0	5.3	313	0.5	47.7	3.2	122	1.00	9.0	<0.5	1.0	59	4.3	5.0	0.1	66	1.71	0.077	6
1090651	Soil	22.7	43.7	18.0	335	0.5	71.2	8.7	173	2.60	43.2	4.5	2.2	59	1.5	6.7	0.2	96	0.23	0.140	17
REP 1090651	QC	21.9	42.2	17.8	331	0.5	69.1	8.6	173	2.57	43.5	3.9	2.2	60	1.5	6.7	0.2	90	0.22	0.136	16
1090681	Soil	2.2	23.9	29.1	62	0.9	13.4	3.3	48	1.51	46.1	5.8	1.4	17	<0.1	2.5	0.3	24	0.03	0.044	16
REP 1090681	QC	2.1	23.9	28.7	60	0.9	13.6	3.2	48	1.48	46.9	4.8	1.4	18	0.2	2.3	0.4	25	0.03	0.045	16
1090687	Soil	11.3	68.4	136.3	103	5.2	14.4	3.2	56	10.26	1717	451.0	8.6	112	0.3	112.4	5.9	43	0.01	0.192	20
REP 1090687	QC	11.0	64.3	135.6	99	5.2	13.0	2.9	56	9.94	1662	434.1	8.5	105	0.3	109.0	5.9	42	0.02	0.183	20
1090712	Soil	12.1	17.3	17.2	97	0.4	20.6	3.2	62	2.23	41.8	3.5	2.4	15	0.5	8.1	0.2	110	0.03	0.058	11
REP 1090712	QC	12.8	17.5	17.6	98	0.4	21.9	3.2	65	2.25	42.3	4.1	2.4	17	0.5	8.7	0.2	110	0.02	0.059	11
1090733	Soil	5.3	18.5	9.4	107	0.3	29.7	4.4	143	1.54	11.4	2.0	1.2	42	0.5	1.2	0.2	31	0.46	0.041	4
REP 1090733	QC	5.5	18.9	9.4	110	0.3	30.3	4.5	146	1.58	11.2	1.2	1.2	43	0.6	1.2	0.2	32	0.45	0.043	4
1090750	Soil	10.1	28.7	12.0	134	0.4	31.3	6.1	225	1.70	17.3	0.6	2.1	39	0.9	3.1	0.2	50	0.34	0.104	9
REP 1090750	QC	9.3	25.4	10.9	121	0.3	29.1	5.5	207	1.56	15.7	1.4	1.8	37	0.8	3.0	0.2	46	0.30	0.093	9
1090780	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1090780	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090785	Soil	4.4	6.8	9.6	45	0.2	7.9	1.9	66	1.49	12.6	2.0	0.7	10	0.2	1.3	0.2	92	0.04	0.036	14
REP 1090785	QC	4.6	6.8	9.8	46	0.2	8.4	1.9	69	1.52	12.8	0.9	0.7	10	0.2	1.3	0.2	91	0.04	0.036	14
1090814	Soil	11.7	28.5	10.4	165	0.1	42.8	6.1	125	1.86	25.4	2.8	1.0	20	0.8	3.1	0.1	79	0.10	0.097	12
REP 1090814	QC	11.8	28.9	10.5	170	0.1	41.4	6.2	128	1.92	26.7	2.6	1.1	20	0.9	3.2	0.2	80	0.11	0.105	13
1090830	Soil	9.2	22.4	15.0	125	0.5	25.6	3.0	95	1.70	29.5	4.7	1.0	78	1.2	5.7	0.2	118	0.29	0.136	8
REP 1090830	QC	8.9	22.2	14.6	122	0.4	24.2	2.9	96	1.71	28.9	3.9	0.9	79	1.2	5.9	0.2	116	0.29	0.129	8
1091306	Soil	4.3	18.9	12.1	124	1.1	30.1	7.7	836	5.24	9.3	2.4	1.2	48	0.5	2.9	0.1	26	0.57	0.063	8
REP 1091306	QC	4.2	20.1	12.2	137	1.1	31.4	8.1	874	5.38	9.7	2.7	1.4	51	0.6	3.2	0.1	29	0.64	0.070	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000601.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1090603	Soil	13	0.10	767	0.004	3	0.67	0.021	0.06	0.1	0.41	1.1	0.4	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090603	QC	13	0.10	795	0.003	3	0.65	0.023	0.06	0.1	0.45	1.0	0.4	<0.05	2	1.2	<0.2				
1090621	Soil	18	0.09	388	0.003	3	0.87	0.006	0.07	0.2	0.11	1.4	0.4	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090621	QC	20	0.10	429	0.005	6	0.97	0.006	0.08	0.2	0.13	1.3	0.6	<0.05	3	1.9	<0.2				
1090647	Soil	11	0.31	960	0.005	5	0.55	0.014	0.07	<0.1	0.11	1.6	0.2	0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090647	QC	11	0.31	953	0.004	5	0.56	0.012	0.06	<0.1	0.13	1.7	0.2	0.07	1	2.2	<0.2				
1090651	Soil	16	0.10	664	0.004	4	0.67	0.004	0.10	0.2	0.32	2.1	0.4	0.08	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090651	QC	15	0.10	661	0.004	3	0.65	0.004	0.10	0.2	0.28	2.0	0.4	0.07	2	1.7	<0.2				
1090681	Soil	9	0.03	209	<0.001	<1	0.54	0.007	0.05	<0.1	0.59	1.0	0.1	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090681	QC	9	0.03	213	<0.001	1	0.56	0.007	0.06	<0.1	0.61	1.0	0.1	<0.05	2	1.6	<0.2				
1090687	Soil	16	0.11	332	0.005	3	0.76	0.021	0.34	2.1	23.06	2.4	6.4	0.88	4	23.7	0.4	N.A.	N.A.	N.A.	N.A.
REP 1090687	QC	16	0.11	324	0.005	3	0.73	0.020	0.33	2.1	23.33	2.3	6.4	0.84	4	22.5	0.3				
1090712	Soil	16	0.11	246	0.006	<1	0.84	0.003	0.05	0.5	0.27	1.0	0.6	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090712	QC	16	0.11	255	0.007	2	0.87	0.004	0.05	0.2	0.26	1.2	0.6	<0.05	4	1.8	<0.2				
1090733	Soil	12	0.13	618	0.002	2	0.69	0.015	0.04	<0.1	0.10	1.6	0.1	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090733	QC	12	0.13	614	0.002	2	0.69	0.015	0.04	<0.1	0.11	1.7	0.1	<0.05	2	0.7	<0.2				
1090750	Soil	12	0.12	560	0.003	3	0.55	0.010	0.07	<0.1	0.21	1.9	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090750	QC	10	0.11	522	0.003	3	0.50	0.008	0.06	0.1	0.18	1.8	0.1	<0.05	2	<0.5	<0.2				
1090780	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	14.5	13.3	10.5	225
REP 1090780	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1090785	Soil	14	0.09	106	0.015	1	0.70	0.005	0.04	0.1	0.01	0.7	0.2	<0.05	5	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090785	QC	14	0.09	104	0.014	<1	0.69	0.005	0.04	0.1	0.01	0.8	0.2	<0.05	5	0.8	<0.2				
1090814	Soil	14	0.08	395	0.002	1	0.69	0.006	0.06	0.1	0.14	1.2	0.3	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090814	QC	14	0.09	401	0.002	2	0.76	0.006	0.06	0.1	0.15	1.2	0.3	<0.05	3	1.2	<0.2				
1090830	Soil	22	0.06	1670	0.002	4	0.51	0.003	0.09	0.1	0.22	1.2	0.4	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090830	QC	21	0.06	1665	0.002	3	0.48	0.003	0.09	0.2	0.19	1.2	0.4	<0.05	2	1.5	<0.2				
1091306	Soil	12	0.14	3724	0.004	2	1.00	0.008	0.05	<0.1	0.14	2.8	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091306	QC	13	0.14	3582	0.006	2	1.05	0.009	0.06	<0.1	0.13	3.4	0.1	<0.05	2	0.8	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000601.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																					
1090603	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090603	QC																				
1090621	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090621	QC																				
1090647	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090647	QC																				
1090651	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090651	QC																				
1090681	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090681	QC																				
1090687	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090687	QC																				
1090712	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090712	QC																				
1090733	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090733	QC																				
1090750	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090750	QC																				
1090780	Soil	0.8	30.3	2.3	111	0.97	14.5	3.2	0.1	23	4.9	2.5	0.1	82	0.16	0.099	4	14	0.07	359	0.004
REP 1090780	QC																				
1090785	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090785	QC																				
1090814	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090814	QC																				
1090830	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090830	QC																				
1091306	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091306	QC																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000601.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1090603	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090603	QC													
1090621	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090621	QC													
1090647	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090647	QC													
1090651	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090651	QC													
1090681	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090681	QC													
1090687	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090687	QC													
1090712	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090712	QC													
1090733	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090733	QC													
1090750	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090750	QC													
1090780	Soil		<20	0.60	0.014	0.04	0.2	0.27	0.7	0.5	<0.05	2	2.0	<0.2
REP 1090780	QC													
1090785	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090785	QC													
1090814	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090814	QC													
1090830	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090830	QC													
1091306	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091306	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000601.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1091312	Soil	9.7	34.1	16.9	187	0.5	49.0	9.8	222	2.77	26.3	2.5	1.9	13	0.3	4.2	0.3	46	0.04	0.078	22
REP 1091312	QC	9.4	31.4	16.4	175	0.5	46.7	9.2	212	2.63	24.3	2.5	1.7	13	0.3	3.9	0.3	42	0.04	0.079	20
1091339	Soil	8.9	24.0	15.6	66	0.3	12.5	2.4	28	1.40	22.6	1.8	0.3	34	0.6	2.7	0.2	81	0.02	0.067	6
REP 1091339	QC	8.1	23.5	15.8	70	0.3	13.1	2.3	28	1.39	22.8	1.3	0.4	37	0.5	2.6	0.2	83	0.03	0.066	6
1091357	Soil	6.7	47.2	14.8	190	1.1	50.1	10.2	316	3.07	18.2	5.5	2.8	44	0.9	3.5	0.2	32	0.41	0.089	12
REP 1091357	QC	6.8	48.5	15.3	199	1.1	51.8	10.9	325	3.15	19.4	6.0	2.9	46	0.8	3.7	0.2	33	0.44	0.093	12
1091366	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1091366	QC																				
1091372	Soil	3.4	9.7	8.5	35	0.3	6.1	1.5	30	0.88	11.3	1.6	1.2	24	<0.1	1.3	0.3	52	0.10	0.017	11
REP 1091372	QC	3.5	9.8	8.5	35	0.3	6.9	1.5	30	0.89	11.7	1.8	1.1	24	<0.1	1.3	0.3	51	0.10	0.017	12
Reference Materials																					
STD DS8	Standard	14.6	124.1	134.2	335	2.0	43.1	8.3	647	2.62	28.4	124.0	7.4	72	2.6	6.3	6.9	47	0.73	0.086	15
STD DS8	Standard	13.9	116.0	128.6	317	2.0	39.8	7.9	671	2.52	26.7	117.8	7.6	74	2.3	6.4	7.3	48	0.73	0.086	16
STD DS8	Standard	12.4	100.4	123.0	294	1.7	35.2	6.8	587	2.29	26.2	106.2	7.0	72	2.2	5.4	6.7	39	0.67	0.074	15
STD DS8	Standard	12.7	97.6	123.0	296	1.7	34.0	6.7	563	2.23	25.2	97.8	6.9	73	2.5	5.6	6.8	38	0.67	0.072	15
STD DS8	Standard	12.8	107.2	105.7	289	1.7	36.0	7.1	583	2.29	25.0	107.5	5.9	58	2.2	4.7	5.7	41	0.67	0.070	14
STD DS8	Standard	13.3	111.0	103.5	299	1.7	38.3	7.6	611	2.40	26.2	106.7	6.3	62	2.4	5.1	5.9	44	0.69	0.075	15
STD DS8	Standard	12.8	118.4	123.3	323	1.8	39.0	7.9	611	2.45	27.3	110.9	6.2	66	2.4	5.7	7.0	45	0.68	0.080	13
STD DS8	Standard	13.3	114.4	123.9	313	1.7	38.9	8.0	623	2.51	27.0	107.0	6.5	69	2.3	6.1	7.0	45	0.66	0.078	13
STD DS8	Standard	13.2	110.8	135.2	315	1.8	38.3	7.7	621	2.50	27.0	115.1	7.5	73	2.7	6.1	7.4	43	0.71	0.084	15
STD DS8	Standard	12.4	105.2	126.9	293	1.7	37.8	7.2	597	2.35	24.6	110.0	7.1	70	2.2	5.9	6.9	41	0.64	0.073	14
STD DS8	Standard	14.0	116.0	125.3	333	1.8	41.4	7.9	672	2.62	28.5	105.5	7.4	74	2.4	6.1	7.2	45	0.77	0.085	17
STD DS8	Standard	13.5	108.1	119.4	316	1.8	37.6	7.8	621	2.46	27.9	111.7	6.7	70	2.4	5.6	6.7	43	0.69	0.080	15
STD DS8	Standard	13.2	109.2	125.1	314	1.8	38.2	7.8	604	2.44	27.2	108.0	6.4	60	2.3	5.5	6.4	43	0.66	0.075	14
STD DS8	Standard	13.9	113.2	125.2	316	1.9	40.9	8.1	639	2.53	27.9	116.7	6.6	65	2.5	5.3	6.5	43	0.71	0.078	15
STD DS8	Standard	13.7	114.3	123.6	314	1.8	38.6	7.7	622	2.51	26.4	111.9	6.5	67	2.4	5.7	6.7	42	0.70	0.081	14
STD DS8	Standard	14.2	117.0	128.2	329	1.9	40.8	8.1	652	2.59	27.7	109.3	7.0	71	2.4	6.1	6.9	45	0.72	0.083	15
STD DS8	Standard	13.8	110.2	123.2	308	1.8	37.5	7.3	621	2.47	25.5	104.8	7.0	73	2.3	5.9	6.7	42	0.70	0.079	17
STD DS8	Standard	13.7	107.2	122.0	308	1.8	36.9	7.4	615	2.44	25.5	112.1	7.0	73	2.2	5.6	6.6	43	0.72	0.078	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000601.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1091312	Soil	12	0.07	325	0.006	2	0.48	0.002	0.09	0.2	0.09	2.2	0.3	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091312	QC	11	0.06	315	0.006	2	0.48	0.002	0.08	0.2	0.09	1.9	0.3	<0.05	2	1.0	<0.2				
1091339	Soil	10	0.02	4024	0.004	<1	0.42	0.003	0.05	0.2	0.04	0.5	0.4	0.09	3	1.5	0.3	N.A.	N.A.	N.A.	N.A.
REP 1091339	QC	10	0.02	4335	0.005	3	0.43	0.004	0.05	0.2	0.04	0.7	0.4	0.10	3	1.7	<0.2				
1091357	Soil	15	0.12	2757	0.004	2	0.63	0.009	0.12	<0.1	0.34	4.1	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091357	QC	15	0.12	2897	0.004	3	0.66	0.010	0.13	<0.1	0.34	4.1	0.2	<0.05	2	1.3	<0.2				
1091366	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.3	51.3	19.7	85
REP 1091366	QC																	3.0	50.0	20.2	86
1091372	Soil	8	0.03	5282	0.014	<1	0.47	0.004	0.03	0.1	0.03	0.6	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091372	QC	8	0.03	5231	0.015	1	0.47	0.004	0.03	0.1	0.02	0.6	0.1	<0.05	3	1.2	<0.2				
Reference Materials																					
STD DS8	Standard	129	0.64	296	0.122	3	0.96	0.092	0.44	3.1	0.22	2.2	5.7	0.18	5	5.9	5.2				
STD DS8	Standard	128	0.66	304	0.127	3	0.97	0.092	0.45	3.0	0.22	2.3	5.2	0.18	5	6.2	5.6				
STD DS8	Standard	110	0.57	281	0.109	3	0.89	0.096	0.44	2.6	0.17	2.3	5.1	0.09	4	5.3	4.3				
STD DS8	Standard	108	0.57	267	0.109	2	0.88	0.101	0.42	2.6	0.17	2.2	5.0	0.08	4	4.8	4.6				
STD DS8	Standard	112	0.57	279	0.110	3	0.87	0.089	0.41	2.7	0.17	2.4	5.1	0.14	4	5.1	4.6				
STD DS8	Standard	119	0.60	280	0.116	3	0.91	0.094	0.41	2.7	0.19	2.5	5.3	0.15	5	5.0	4.7				
STD DS8	Standard	123	0.60	264	0.125	2	0.88	0.090	0.42	2.9	0.19	1.8	5.5	0.16	5	5.2	4.9				
STD DS8	Standard	124	0.58	277	0.126	2	0.88	0.082	0.41	3.0	0.19	2.0	5.6	0.15	4	5.8	4.7				
STD DS8	Standard	118	0.63	286	0.127	3	0.94	0.090	0.43	2.9	0.22	1.9	5.5	0.13	5	5.0	5.5				
STD DS8	Standard	113	0.61	264	0.120	4	0.86	0.084	0.40	2.8	0.18	1.8	5.1	0.12	4	4.2	4.3				
STD DS8	Standard	122	0.66	304	0.142	3	0.99	0.097	0.45	3.2	0.21	2.4	5.7	0.17	5	5.4	5.1				
STD DS8	Standard	118	0.60	285	0.130	2	0.89	0.092	0.41	3.0	0.20	2.3	5.3	0.15	5	5.2	4.7				
STD DS8	Standard	116	0.61	261	0.111	3	0.89	0.084	0.40	2.8	0.21	2.3	5.3	0.15	5	5.2	5.4				
STD DS8	Standard	121	0.63	277	0.120	2	0.95	0.091	0.43	3.0	0.21	2.5	5.3	0.15	5	5.9	5.2				
STD DS8	Standard	120	0.62	272	0.127	2	0.90	0.085	0.43	3.0	0.21	2.1	5.5	0.16	5	5.4	4.7				
STD DS8	Standard	125	0.64	289	0.131	2	0.93	0.093	0.43	3.1	0.21	2.3	5.7	0.15	5	6.3	5.7				
STD DS8	Standard	118	0.60	291	0.133	3	0.92	0.088	0.42	3.1	0.20	2.3	5.6	0.12	5	5.7	5.4				
STD DS8	Standard	119	0.61	288	0.134	1	0.93	0.087	0.42	3.1	0.20	2.3	5.5	0.12	5	4.7	5.0				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000601.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1091312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091312	QC																				
1091339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091339	QC																				
1091357	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091357	QC																				
1091366	Soil	0.8	54.0	20.3	347	4.73	17.5	6.5	1.1	39	0.3	1.5	0.4	25	0.33	0.101	11	18	0.11	2512	0.003
REP 1091366	QC	0.8	51.7	19.6	337	4.72	17.3	3.0	1.2	38	0.3	1.5	0.5	24	0.33	0.100	10	13	0.10	2419	0.003
1091372	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091372	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000601.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1091312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091312	QC												
1091339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091339	QC												
1091357	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091357	QC												
1091366	Soil	<20	0.73	0.005	0.09	0.1	0.24	4.0	0.2	<0.05	2	2.3	<0.2
REP 1091366	QC	<20	0.69	0.005	0.09	<0.1	0.21	3.9	0.3	<0.05	2	2.3	<0.2
1091372	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091372	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000601.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	12.6	108.4	121.2	297	1.7	35.1	7.0	584	2.36	26.1	116.4	7.4	68	2.3	5.7	6.7	41	0.67	0.077	16
STD DS8	Standard	13.4	109.4	123.2	312	1.8	37.9	7.4	620	2.50	25.3	114.4	6.5	69	2.4	5.5	6.4	42	0.69	0.079	14
STD DS8	Standard	13.3	108.5	126.1	308	1.8	37.9	7.6	621	2.50	25.4	104.4	6.8	68	2.1	5.7	6.7	41	0.70	0.077	14
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000601.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
STD DS8	Standard	111	0.60	280	0.118	2	0.88	0.084	0.41	2.8	0.20	2.1	5.3	0.13	5	4.7	5.1				
STD DS8	Standard	118	0.62	266	0.127	2	0.90	0.085	0.41	3.0	0.22	2.1	5.3	0.17	5	6.3	5.1				
STD DS8	Standard	117	0.61	271	0.126	3	0.89	0.082	0.41	2.9	0.20	2.2	5.6	0.15	5	5.2	4.8				
STD DS8	Standard																	14.0	117.3	126.8	318
STD OREAS45CA	Standard																	0.9	488.6	19.7	59
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000601.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.8	39.4	8.1	635	2.63	26.5	96.8	6.8	71	2.4	4.8	6.4	45	0.75	0.089	15	116	0.65	304	0.118
STD OREAS45CA	Standard	0.3	244.6	87.8	897	16.02	4.1	39.3	6.6	15	<0.1	<0.1	0.2	187	0.41	0.039	15	659	0.15	151	0.144
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000601.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.99	0.096	0.44	3.0	0.21	2.4	5.5	0.17	5	6.3	5.3
STD OREAS45CA	Standard	<20	4.00	0.013	0.07	<0.1	0.01	39.0	<0.1	<0.05	18	0.6	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 15, 2011
Report Date: August 22, 2011
Page: 1 of 8

CERTIFICATE OF ANALYSIS WHI11000621.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #3
P.O. Number
Number of Samples: 206

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	206	Sieve to 230 mesh			WHI
1DX2	202	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	4	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091384	Soil		11.1	94.7	103.2	121	6.3	12.4	2.9	91	14.99	1965	488.7	8.2	97	0.4	157.0	6.0	74	0.02	0.347	18
1091385	Soil		5.7	41.8	14.3	167	0.1	37.9	6.5	174	2.88	23.2	3.5	2.0	39	0.6	3.3	0.3	61	0.17	0.086	8
1090691	Soil		2.1	17.4	6.7	47	0.4	7.6	1.6	55	0.94	7.4	1.8	0.1	10	0.4	0.9	0.1	37	0.05	0.071	5
1090692	Soil		8.1	57.9	167.1	121	6.5	13.1	3.5	65	11.08	1144	240.3	10.1	71	1.2	128.8	16.1	40	0.02	0.226	23
1090693	Soil		5.9	100.5	83.9	151	3.4	21.8	5.2	174	12.77	1497	145.2	10.1	24	0.1	67.1	3.6	54	0.02	0.256	21
1091401	Soil		8.2	28.1	13.0	241	0.9	33.5	7.4	291	1.73	19.9	2.4	2.1	60	2.0	4.0	0.3	88	0.80	0.112	10
1091402	Soil		5.7	38.1	12.9	172	1.8	39.7	5.3	75	1.90	12.3	1.9	0.7	37	0.8	2.7	0.2	41	0.32	0.090	9
1091403	Soil		4.1	28.8	12.4	78	1.3	36.6	4.6	66	1.59	7.5	<0.5	0.5	10	0.3	2.5	0.1	32	0.13	0.053	9
1091404	Soil		1.6	7.8	5.5	37	0.4	9.4	1.3	15	0.52	2.9	<0.5	0.4	2	0.1	1.3	0.1	28	0.02	0.031	6
1091405	Soil		8.8	19.3	14.3	170	0.3	35.0	4.5	84	1.84	24.5	<0.5	2.2	13	0.3	4.5	0.2	78	0.03	0.065	13
1091406	Soil		3.3	13.4	7.0	83	0.8	20.9	1.9	16	0.70	5.3	<0.5	1.1	3	<0.1	1.9	0.1	41	<0.01	0.021	10
1091407	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091408	Soil		6.3	27.6	13.4	197	0.9	36.7	6.4	116	2.04	17.1	2.3	3.0	40	1.1	2.8	0.2	60	0.48	0.076	10
1091409	Soil		5.1	14.0	7.7	83	0.4	16.5	2.4	50	0.99	10.0	<0.5	1.2	28	0.4	1.8	0.1	40	0.38	0.039	7
1091410	Soil		5.9	20.3	14.6	126	0.9	27.0	5.2	110	2.20	18.7	0.6	1.8	13	0.2	2.5	0.2	53	0.04	0.047	10
1091411	Soil		3.7	9.2	8.0	44	0.1	9.2	2.1	51	0.81	8.6	<0.5	0.5	17	0.3	1.0	0.2	39	0.13	0.025	10
1091412	Soil		4.2	12.8	10.8	66	<0.1	14.4	3.7	91	1.80	14.8	<0.5	2.2	10	0.2	1.2	0.2	51	0.02	0.024	8
1091413	Soil		8.5	22.2	13.4	148	0.7	32.3	6.3	164	2.79	21.3	0.9	1.6	9	0.3	2.9	0.3	61	0.02	0.052	8
1091414	Soil		12.6	42.5	18.3	129	0.4	43.3	7.2	79	2.16	13.2	4.1	2.1	15	0.5	2.6	0.3	27	0.11	0.060	20
1091415	Soil		28.0	34.9	104.8	79	1.1	23.9	2.7	35	1.42	13.7	<0.5	0.3	69	0.6	6.6	0.6	191	0.04	0.075	14
1091416	Soil		3.9	26.8	11.3	43	0.7	24.3	5.9	47	1.20	7.6	0.6	<0.1	18	0.3	1.5	<0.1	42	0.25	0.078	6
1091417	Soil		2.4	11.1	7.0	45	0.6	12.7	2.1	33	0.81	6.3	<0.5	<0.1	16	0.2	0.9	0.1	22	0.10	0.053	3
1091418	Soil		5.2	23.5	13.5	69	0.8	20.7	3.2	46	1.10	10.3	1.4	0.3	16	0.2	1.5	0.1	37	0.06	0.060	7
1091419	Soil		10.2	52.3	21.2	218	0.5	55.8	13.2	371	2.89	24.7	2.4	2.5	35	1.0	3.7	0.3	51	0.18	0.117	15
1091420	Soil		10.5	45.8	16.5	193	0.5	47.8	8.9	187	2.33	22.2	2.1	4.1	46	0.9	3.8	0.2	50	0.38	0.136	16
1091421	Soil		10.3	24.2	13.6	90	0.6	24.3	9.3	415	1.81	15.3	1.4	1.6	21	0.4	2.4	0.2	45	0.12	0.082	9
1091422	Soil		12.7	39.8	16.5	228	0.8	54.3	10.1	539	2.41	23.8	1.1	2.7	41	0.8	3.3	0.3	60	0.42	0.113	12
1091423	Soil		19.5	49.1	15.0	285	0.8	71.8	8.6	180	2.42	39.2	4.4	2.9	58	2.0	6.2	0.2	81	0.62	0.131	13
1091424	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091425	Soil		12.0	29.4	22.7	168	0.3	39.9	7.1	149	3.10	31.2	2.8	2.8	13	0.2	4.1	0.3	63	0.03	0.092	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091384	Soil	33	0.18	400	0.009	2	1.00	0.013	0.30	2.2	10.13	3.9	3.9	0.66	5	26.4	0.4	N.A.	N.A.	N.A.	N.A.
1091385	Soil	23	0.25	1796	0.006	2	0.96	0.002	0.05	0.1	0.08	1.9	0.2	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090691	Soil	10	0.04	271	0.004	1	0.49	0.010	0.04	<0.1	0.03	0.5	<0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090692	Soil	18	0.08	296	0.008	2	0.85	0.023	0.35	2.0	43.16	1.9	4.9	0.75	5	32.5	0.4	N.A.	N.A.	N.A.	N.A.
1090693	Soil	33	0.29	169	0.010	3	1.43	0.007	0.13	0.7	8.13	5.1	1.5	0.26	5	12.1	0.4	N.A.	N.A.	N.A.	N.A.
1091401	Soil	17	0.25	1103	0.004	3	0.80	0.006	0.09	0.1	0.61	2.8	0.3	0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091402	Soil	9	0.08	4137	0.003	2	0.57	0.010	0.11	0.1	0.46	1.4	0.2	0.08	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091403	Soil	10	0.05	306	0.003	2	0.37	0.011	0.07	<0.1	0.16	1.0	<0.1	<0.05	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091404	Soil	7	0.03	106	0.003	2	0.38	0.011	0.05	<0.1	0.06	0.5	0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091405	Soil	15	0.07	225	0.003	4	0.66	0.002	0.08	0.1	0.08	1.6	0.3	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091406	Soil	8	0.02	98	0.003	2	0.42	0.004	0.05	<0.1	0.02	0.6	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091407	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	27.0	36.0	36.4	752
1091408	Soil	20	0.23	1140	0.003	2	0.81	0.004	0.08	<0.1	0.28	3.2	0.2	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091409	Soil	8	0.13	1331	0.003	3	0.45	0.008	0.07	<0.1	0.04	1.0	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091410	Soil	15	0.12	288	0.005	2	0.72	0.005	0.07	0.1	0.05	1.4	0.2	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091411	Soil	8	0.06	548	0.004	2	0.46	0.004	0.05	<0.1	0.01	0.7	<0.1	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091412	Soil	10	0.06	154	0.003	1	0.62	0.003	0.06	<0.1	0.05	1.4	<0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091413	Soil	18	0.10	280	0.003	2	1.03	0.006	0.07	0.1	0.23	1.7	0.3	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091414	Soil	6	0.04	427	0.002	4	0.48	0.005	0.12	<0.1	0.25	2.2	0.2	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091415	Soil	22	0.03	404	0.003	2	0.39	0.007	0.12	0.3	0.09	0.3	0.6	0.13	3	1.8	0.3	N.A.	N.A.	N.A.	N.A.
1091416	Soil	10	0.07	202	0.001	2	0.36	0.018	0.05	<0.1	0.06	0.3	0.1	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091417	Soil	5	0.04	284	0.003	2	0.43	0.019	0.05	<0.1	0.09	0.4	0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091418	Soil	11	0.05	318	0.003	3	0.69	0.012	0.07	<0.1	0.14	0.6	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091419	Soil	14	0.10	828	0.003	4	0.73	0.005	0.11	0.1	0.28	2.9	0.2	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091420	Soil	13	0.10	874	0.003	4	0.61	0.004	0.12	<0.1	0.33	3.0	0.2	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091421	Soil	11	0.07	522	0.002	3	0.57	0.009	0.08	<0.1	0.23	1.8	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091422	Soil	14	0.13	1051	0.003	6	0.76	0.009	0.11	<0.1	0.35	3.1	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091423	Soil	16	0.15	959	0.003	5	0.76	0.006	0.10	0.1	0.46	3.0	0.4	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091424	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	10.8	47.5	25.4	186
1091425	Soil	12	0.06	176	0.005	3	0.61	0.004	0.09	0.3	0.03	2.1	0.3	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091384	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091385	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090691	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090692	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090693	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091401	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091402	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091403	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091404	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091405	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091406	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091407	Soil		1.0	82.4	6.2	117	1.76	24.5	2.5	0.4	20	13.5	9.5	0.3	119	0.48	0.073	7	34	0.09	323	0.002
1091408	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091409	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091410	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091411	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091412	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091413	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091414	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091415	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091416	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091417	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091418	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091419	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091420	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091421	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091422	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091423	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091424	Soil		1.0	60.0	5.8	152	1.78	21.2	4.2	0.6	43	1.7	2.4	0.2	58	0.48	0.084	6	27	0.14	1659	0.002
1091425	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091384	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091385	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090691	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090692	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090693	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091401	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091402	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091403	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091404	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091405	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091406	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091407	Soil	<20	0.45	0.006	0.04	<0.1	0.28	1.8	0.3	0.08	1	3.0	<0.2
1091408	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091409	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091410	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091411	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091412	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091413	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091414	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091415	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091416	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091417	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091418	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091419	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091420	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091421	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091422	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091423	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091424	Soil	<20	0.88	0.009	0.07	0.2	0.40	2.0	0.2	0.08	2	1.5	<0.2
1091425	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091426	Soil	8.2	35.9	16.1	196	0.6	43.9	11.2	190	2.46	22.6	1.8	3.9	38	0.5	3.3	0.2	48	0.18	0.109	15
1091427	Soil	9.9	23.2	14.2	154	0.6	30.1	8.1	285	2.22	21.3	1.3	2.9	46	0.6	2.9	0.2	56	0.32	0.091	10
1091428	Soil	11.4	58.2	17.6	291	2.1	65.9	8.0	268	2.39	36.6	6.6	1.0	57	2.4	4.9	0.2	115	0.20	0.167	10
1091429	Soil	2.1	13.2	12.9	24	1.5	6.9	0.7	15	0.50	5.5	<0.5	<0.1	60	0.6	0.8	0.2	25	0.03	0.077	5
1091430	Soil	8.4	39.7	17.0	332	0.2	68.9	13.5	551	3.97	266.1	1.8	3.0	8	0.6	5.5	0.4	37	0.02	0.063	35
1091431	Soil	2.6	7.9	2.6	35	<0.1	8.2	1.9	30	0.58	8.1	1.1	0.3	4	<0.1	0.7	<0.1	23	<0.01	0.021	8
1091432	Soil	19.5	11.9	5.7	69	<0.1	22.0	2.3	27	0.75	25.7	<0.5	0.4	5	0.4	1.8	0.1	44	0.02	0.028	10
1091433	Soil	10.8	14.8	9.1	104	0.2	22.4	3.2	105	1.22	22.2	2.0	0.4	10	0.5	2.0	0.2	70	0.05	0.044	10
1091434	Soil	9.2	17.3	11.7	108	0.3	24.7	4.1	102	1.57	23.0	3.0	0.8	12	0.4	2.5	0.2	62	0.04	0.053	10
1091435	Soil	13.0	47.7	14.1	252	0.6	62.1	7.9	175	2.51	34.0	3.9	2.1	41	1.6	4.1	0.2	73	0.41	0.082	11
1091436	Soil	10.7	16.7	12.5	117	<0.1	21.2	4.8	87	1.58	22.5	1.3	0.6	10	0.8	3.7	0.2	208	0.03	0.033	9
1091437	Soil	17.6	25.6	10.9	224	0.2	49.8	4.6	101	1.61	24.9	2.5	0.9	21	1.4	3.9	0.2	133	0.17	0.066	13
1091438	Soil	9.1	11.5	8.5	76	0.2	18.5	2.6	68	1.19	16.3	1.8	0.2	10	0.3	1.7	0.1	74	0.04	0.043	9
1091439	Soil	18.7	15.4	12.3	157	<0.1	39.1	3.7	87	1.43	20.6	1.8	0.4	10	0.7	2.6	0.1	122	0.03	0.043	14
1091440	Soil	15.2	24.4	13.9	206	0.2	40.6	5.4	140	2.06	25.8	3.0	0.9	20	1.6	2.9	0.2	131	0.12	0.076	13
1091441	Soil	10.9	14.7	8.8	140	0.4	27.5	3.2	68	1.32	16.4	1.8	0.5	11	0.6	2.4	0.1	148	0.03	0.059	10
1091442	Soil	18.4	11.3	9.2	161	0.5	46.0	3.2	44	1.26	18.1	0.5	0.7	8	0.3	3.5	0.1	151	0.02	0.059	12
1091443	Soil	20.5	20.8	19.1	249	0.4	43.3	4.8	114	3.26	32.6	3.2	0.7	21	0.6	5.2	0.2	151	0.08	0.172	11
1091444	Soil	16.3	16.6	15.1	152	0.3	35.3	4.0	59	1.50	32.6	3.4	0.8	16	0.3	6.4	0.1	191	0.04	0.064	8
1091445	Soil	4.0	26.3	13.1	98	0.6	21.6	3.7	150	1.15	20.8	6.4	0.9	56	1.2	3.1	0.3	48	0.87	0.058	6
1091446	Soil	8.5	45.2	15.2	243	1.1	52.4	7.4	188	2.40	49.0	9.8	1.6	58	1.4	5.4	0.2	82	0.28	0.127	8
1091447	Soil	2.4	14.1	5.2	98	0.5	19.9	2.9	116	0.60	7.1	3.3	0.2	29	1.7	1.7	<0.1	31	0.27	0.053	2
1091448	Soil	8.8	19.9	14.0	95	1.4	19.4	2.2	31	1.32	24.6	4.6	1.0	28	0.4	3.4	0.1	100	0.02	0.072	6
1091449	Soil	4.4	9.2	6.6	36	0.3	8.1	1.5	24	0.74	8.2	<0.5	0.2	12	0.2	1.2	<0.1	44	0.01	0.024	4
1091450	Soil	13.6	46.7	19.9	198	0.4	40.9	5.6	95	2.60	35.4	7.9	2.0	49	0.6	6.3	0.2	98	0.05	0.088	9
1091451	Soil	3.8	44.4	14.6	198	1.0	43.0	6.8	174	2.73	15.6	5.0	1.9	30	0.9	2.7	0.2	60	0.18	0.074	9
1091452	Soil	5.1	18.6	14.7	97	0.2	17.1	3.4	78	1.60	17.5	1.4	0.3	15	0.3	2.4	0.2	77	0.02	0.043	10
1091453	Soil	6.0	21.3	17.9	121	0.2	22.2	4.4	127	2.64	23.3	2.3	0.9	15	0.4	3.3	0.2	91	0.03	0.075	9
1091454	Soil	4.6	39.8	11.9	227	0.7	36.4	6.3	111	2.14	14.4	5.1	1.9	91	1.0	3.0	0.2	75	0.59	0.068	9
1091455	Soil	3.8	18.2	11.7	107	0.6	19.4	5.7	144	1.49	11.8	1.9	1.0	38	0.8	1.9	0.2	65	0.24	0.056	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091426	Soil	13	0.14	2327	0.008	3	0.70	0.004	0.10	<0.1	0.22	2.4	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091427	Soil	14	0.16	1360	0.002	3	0.70	0.006	0.09	0.1	0.35	2.3	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091428	Soil	19	0.11	959	0.002	4	1.27	0.009	0.13	0.2	0.86	2.1	0.5	0.06	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091429	Soil	6	0.02	229	0.002	2	0.34	0.013	0.05	<0.1	0.09	0.1	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091430	Soil	10	0.05	349	0.002	4	0.67	0.006	0.09	0.1	0.19	2.2	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091431	Soil	3	0.01	49	0.004	<1	0.18	0.009	0.03	0.1	<0.01	0.3	<0.1	<0.05	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091432	Soil	6	0.02	132	0.004	1	0.50	0.005	0.03	0.2	0.02	0.5	0.2	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091433	Soil	12	0.07	386	0.004	<1	0.75	0.004	0.03	0.2	0.09	0.8	0.3	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091434	Soil	11	0.07	221	0.004	2	0.57	0.004	0.05	0.2	0.06	0.9	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091435	Soil	16	0.13	1150	0.003	2	0.76	0.004	0.06	0.1	0.42	2.8	0.3	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091436	Soil	13	0.05	243	0.004	<1	0.59	0.002	0.04	0.2	0.02	1.0	0.2	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091437	Soil	16	0.09	772	0.003	2	0.81	0.004	0.07	0.2	0.12	1.1	0.5	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091438	Soil	9	0.04	157	0.005	<1	0.47	0.006	0.04	0.1	0.02	0.5	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091439	Soil	12	0.05	224	0.004	1	0.60	0.003	0.05	0.2	<0.01	0.7	0.3	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091440	Soil	16	0.08	723	0.003	2	0.89	0.003	0.07	0.2	0.10	1.1	0.3	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091441	Soil	12	0.06	194	0.003	1	0.66	0.005	0.05	0.1	0.03	0.8	0.3	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091442	Soil	11	0.04	132	0.005	<1	0.53	0.005	0.04	0.1	<0.01	0.8	0.4	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091443	Soil	21	0.08	238	0.007	2	0.95	0.004	0.09	0.2	0.06	1.0	0.6	<0.05	4	2.9	0.3	N.A.	N.A.	N.A.	N.A.
1091444	Soil	14	0.05	162	0.003	<1	0.59	0.005	0.05	0.5	0.14	1.0	0.8	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091445	Soil	12	0.14	396	0.005	2	0.52	0.009	0.06	0.1	0.58	1.5	0.2	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091446	Soil	22	0.10	1916	0.002	2	0.70	0.003	0.05	0.1	2.16	2.5	0.3	<0.05	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091447	Soil	6	0.03	1290	0.006	<1	0.42	0.025	0.03	0.1	0.33	0.7	0.1	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091448	Soil	14	0.03	465	0.003	<1	0.56	0.005	0.05	0.1	0.41	1.1	0.3	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091449	Soil	6	0.02	1589	0.008	<1	0.43	0.014	0.03	0.2	0.09	0.5	0.3	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091450	Soil	19	0.09	886	0.004	2	0.72	0.003	0.07	0.2	0.45	2.1	0.4	<0.05	2	3.0	0.2	N.A.	N.A.	N.A.	N.A.
1091451	Soil	24	0.17	2258	0.003	2	1.31	0.004	0.07	0.2	0.39	2.4	0.2	<0.05	3	1.5	0.2	N.A.	N.A.	N.A.	N.A.
1091452	Soil	12	0.05	461	0.006	<1	0.51	0.003	0.05	0.2	0.06	0.7	0.1	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091453	Soil	15	0.09	282	0.009	1	0.73	0.003	0.06	0.2	0.04	1.2	0.2	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091454	Soil	24	0.22	2213	0.004	2	0.93	0.004	0.08	0.1	0.44	2.9	0.2	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091455	Soil	17	0.11	958	0.005	<1	0.94	0.008	0.05	0.2	0.07	1.4	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091426	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091427	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091428	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091429	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091430	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091431	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091432	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091433	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091434	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091435	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091436	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091437	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091438	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091439	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091440	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091441	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091442	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091443	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091444	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091445	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091446	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091447	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091448	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091449	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091450	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091451	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091452	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091453	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091454	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091455	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091426	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091427	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091428	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091429	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091430	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091431	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091432	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091433	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091434	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091435	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091436	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091437	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091438	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091439	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091440	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091441	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091442	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091443	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091444	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091445	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091446	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091447	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091448	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091449	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091450	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091451	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091452	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091453	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091454	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091455	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091456	Soil		4.4	47.1	12.0	158	1.4	36.8	6.8	263	1.92	12.3	7.3	1.1	84	0.9	2.5	0.2	82	1.17	0.082	8
1091457	Soil		3.5	12.3	9.9	60	0.2	11.6	2.2	48	1.26	10.0	1.6	1.0	7	0.1	1.6	0.2	65	0.02	0.031	11
1091458	Soil		10.9	45.8	19.9	277	0.4	47.5	7.2	168	3.64	30.0	5.3	1.7	54	0.7	4.5	0.3	88	0.04	0.124	8
1091459	Soil		5.9	60.2	13.0	229	0.5	43.8	7.5	213	2.72	20.6	6.7	2.7	64	1.5	3.7	0.2	65	0.30	0.125	10
1091460	Soil		5.4	74.2	16.9	235	0.4	46.7	9.8	236	3.02	25.8	5.1	2.5	35	0.8	3.6	0.2	69	0.13	0.084	8
1091461	Soil		4.8	37.4	12.7	171	0.4	37.2	5.9	150	2.44	18.7	7.2	2.2	29	0.7	3.1	0.2	57	0.08	0.081	7
1091462	Soil		3.9	16.0	13.4	91	0.6	13.4	2.6	80	1.58	11.3	1.4	0.7	14	0.5	1.7	0.2	162	0.07	0.084	10
1091463	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091464	Soil		5.0	48.5	13.6	217	0.6	38.2	6.8	153	2.12	13.8	3.6	1.8	26	1.4	2.6	0.1	77	0.06	0.086	8
1091465	Soil		5.6	83.9	17.6	223	0.5	51.2	9.3	190	3.00	28.2	9.7	2.3	23	0.9	3.9	0.2	57	0.06	0.059	7
1091466	Soil		6.8	45.2	18.0	144	0.3	31.2	5.3	131	2.67	23.3	10.8	1.2	26	0.6	2.9	0.4	85	0.06	0.069	6
1091467	Soil		5.9	62.0	15.8	226	1.2	47.5	7.6	283	2.23	23.5	8.3	1.5	148	1.6	3.6	0.3	86	1.02	0.113	7
1091468	Soil		7.8	41.1	14.3	203	0.8	38.6	6.5	194	2.28	22.3	4.9	1.7	103	1.3	3.6	0.2	81	0.56	0.115	8
1091469	Soil		4.3	81.5	15.7	202	0.9	44.8	8.6	215	2.66	18.4	8.6	1.4	89	0.9	2.2	0.3	62	0.81	0.089	6
1091470	Soil		4.1	55.9	12.0	145	0.8	34.4	6.0	96	1.99	12.7	6.8	1.0	76	1.0	2.0	0.2	50	0.91	0.089	5
1091471	Soil		1.9	58.2	11.1	114	1.5	38.0	7.2	246	1.73	9.7	5.6	0.8	134	2.2	1.6	0.2	35	1.73	0.105	7
1091472	Soil		3.0	39.3	11.7	105	0.8	35.4	7.4	218	1.99	11.6	2.4	1.1	72	1.5	1.3	0.2	56	0.92	0.095	10
1091473	Soil		4.4	15.7	6.8	72	<0.1	12.8	2.6	64	1.18	16.0	1.1	1.2	10	0.4	1.8	0.2	62	0.05	0.020	11
1091474	Soil		4.3	29.3	16.4	127	0.9	29.4	6.1	137	3.73	14.5	1.1	2.3	10	0.3	1.6	0.3	65	0.03	0.066	11
1091475	Soil		2.0	43.2	15.5	25	0.7	10.6	1.7	20	1.19	4.8	0.5	0.3	24	1.8	0.6	0.3	30	0.10	0.033	11
1091476	Soil		7.7	108.9	29.3	404	3.4	127.3	17.6	170	7.36	27.9	7.1	4.8	26	4.3	3.1	0.4	45	0.20	0.142	12
1091477	Soil		3.0	37.3	12.9	148	0.8	31.6	9.2	156	2.21	10.2	2.9	1.5	69	1.9	1.5	0.3	42	1.23	0.051	6
1091478	Soil		2.1	45.1	12.1	83	1.0	21.9	10.8	504	1.55	7.1	2.7	0.5	86	2.0	1.1	0.2	38	1.80	0.096	8
1091479	Soil		2.5	25.5	9.7	219	2.0	33.9	4.8	1148	2.11	12.2	2.0	0.6	86	3.8	1.1	0.2	66	1.67	0.212	16
1091480	Soil		2.7	27.4	12.8	102	3.4	15.3	3.6	164	1.48	8.8	3.7	0.3	58	1.4	1.0	0.2	46	0.96	0.084	9
1091481	Soil		7.7	20.0	14.1	112	0.2	21.3	4.3	128	2.03	19.3	1.8	1.5	19	0.6	2.7	0.3	87	0.13	0.032	12
1091482	Soil		2.3	16.1	7.4	41	0.3	7.8	2.0	44	0.93	5.8	<0.5	<0.1	6	0.3	1.0	0.2	32	0.02	0.041	7
1091483	Soil		4.3	81.5	52.7	81	3.1	72.7	14.2	785	5.61	258.2	2.6	0.5	55	0.4	6.0	0.3	61	0.23	0.203	6
1091484	Soil		5.1	84.7	40.2	50	2.4	30.1	6.0	200	3.29	355.3	8.3	1.0	56	0.2	7.5	0.3	39	0.05	0.140	3
1091485	Soil		7.0	134.4	49.4	31	3.3	48.7	9.9	350	4.47	200.0	8.5	0.9	109	0.2	5.8	0.4	60	0.03	0.158	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091456	Soil	26	0.16	2424	0.007	2	1.30	0.007	0.07	0.1	0.33	3.0	0.2	<0.05	4	2.2	0.2	N.A.	N.A.	N.A.	N.A.
1091457	Soil	11	0.04	332	0.006	<1	0.64	0.003	0.04	0.1	0.02	1.0	0.1	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091458	Soil	29	0.17	2017	0.003	2	1.04	0.005	0.08	0.1	0.06	2.0	0.3	<0.05	3	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091459	Soil	25	0.22	2538	0.004	1	0.87	0.003	0.07	0.1	0.33	2.6	0.2	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091460	Soil	26	0.23	780	0.003	<1	0.99	0.003	0.07	0.1	0.24	2.2	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091461	Soil	23	0.19	1072	0.003	2	0.89	0.005	0.06	<0.1	0.14	1.8	0.1	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091462	Soil	28	0.43	422	0.033	<1	1.17	0.005	0.13	0.2	0.07	1.9	0.2	<0.05	8	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091463	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.8	43.0	19.2	240
1091464	Soil	26	0.16	986	0.005	2	1.14	0.005	0.11	0.2	0.25	2.2	0.2	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091465	Soil	32	0.24	884	0.002	<1	1.00	0.003	0.04	0.1	0.27	2.3	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091466	Soil	25	0.16	422	0.003	3	0.89	0.003	0.07	<0.1	0.13	1.6	0.2	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091467	Soil	24	0.21	1448	0.003	4	0.98	0.006	0.08	0.1	0.91	2.9	0.3	0.09	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091468	Soil	22	0.20	1492	0.004	3	0.86	0.005	0.07	0.2	0.60	2.7	0.3	0.06	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091469	Soil	32	0.30	1129	0.002	2	1.20	0.005	0.06	<0.1	0.45	2.9	0.2	0.06	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091470	Soil	26	0.21	1061	0.002	3	0.95	0.006	0.06	0.1	0.33	2.2	0.2	0.10	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091471	Soil	18	0.19	1420	0.004	3	0.86	0.009	0.05	<0.1	0.46	3.0	0.1	0.12	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091472	Soil	23	0.22	2670	0.007	2	1.17	0.005	0.05	0.1	0.35	2.8	0.1	0.08	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091473	Soil	9	0.02	204	0.006	2	0.34	0.002	0.04	0.1	0.12	0.7	<0.1	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091474	Soil	21	0.13	1284	0.006	2	1.16	0.003	0.06	0.1	0.05	2.1	0.1	<0.05	5	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091475	Soil	18	0.01	1795	0.011	2	0.92	0.004	0.02	<0.1	0.04	1.0	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091476	Soil	46	0.46	3669	0.001	2	1.68	0.004	0.05	<0.1	0.43	6.5	0.2	0.05	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091477	Soil	21	0.22	1546	0.004	2	0.93	0.006	0.04	0.1	0.12	2.2	<0.1	0.07	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091478	Soil	17	0.10	2559	0.005	3	0.81	0.013	0.04	<0.1	0.22	1.8	0.1	0.10	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091479	Soil	31	0.18	2030	0.005	2	1.15	0.007	0.03	0.1	0.26	1.9	<0.1	0.07	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091480	Soil	17	0.08	2456	0.004	1	1.04	0.006	0.04	0.1	0.16	0.9	0.1	0.06	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091481	Soil	14	0.06	545	0.004	2	0.72	0.003	0.05	0.2	0.04	1.2	0.2	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091482	Soil	7	0.02	157	0.006	1	0.45	0.010	0.03	<0.1	0.04	0.2	<0.1	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091483	Soil	26	0.14	360	0.006	3	1.18	0.006	0.07	0.1	0.20	3.0	0.3	0.15	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091484	Soil	11	0.03	169	0.004	2	0.36	0.011	0.06	<0.1	0.14	4.2	0.2	0.11	1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091485	Soil	20	0.03	262	0.002	2	0.57	0.011	0.13	<0.1	0.15	7.5	0.4	0.31	2	5.7	0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091456	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091457	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091458	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091459	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091460	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091461	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091462	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091463	Soil		0.9	46.8	9.3	265	3.23	24.3	7.2	1.7	31	1.1	2.2	0.3	81	0.07	0.110	6	27	0.22	827	0.003
1091464	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091465	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091466	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091467	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091468	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091469	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091470	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091471	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091472	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091473	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091474	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091475	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091476	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091477	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091478	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091479	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091480	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091481	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091482	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091483	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091484	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091485	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091456	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091457	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091458	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091459	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091460	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091461	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091462	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091463	Soil	<20	1.02	0.004	0.07	0.1	0.19	2.3	0.2	<0.05	3	1.6	<0.2
1091464	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091465	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091466	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091467	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091468	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091469	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091470	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091471	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091472	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091473	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091474	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091475	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091476	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091477	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091478	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091479	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091480	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091481	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091482	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091483	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091484	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091485	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091486	Soil	6.5	99.5	39.1	29	2.0	36.1	7.1	158	3.52	208.3	6.9	0.7	94	0.1	5.6	0.4	47	0.03	0.161	5
1091487	Soil	8.4	123.0	32.1	322	1.4	78.8	24.1	649	4.73	239.3	3.8	2.3	34	1.1	10.4	0.5	67	0.31	0.115	5
1091488	Soil	82.1	101.7	16.7	913	1.0	227.8	10.2	240	3.15	43.0	2.8	2.9	79	11.1	12.0	0.2	149	2.95	0.110	13
1091489	Soil	42.4	74.5	17.3	371	0.7	123.5	9.4	224	2.68	30.4	2.1	1.6	109	3.3	5.1	0.2	71	2.51	0.110	8
1091490	Soil	20.7	59.2	16.4	200	0.6	57.5	9.1	210	2.35	24.5	3.4	1.3	27	0.9	4.7	0.3	60	0.26	0.094	8
1091491	Soil	11.2	43.6	17.8	117	0.2	38.4	8.8	284	2.44	21.5	2.3	0.2	19	0.3	4.1	0.4	54	0.16	0.096	7
1091492	Soil	35.4	72.1	16.9	390	0.7	84.6	7.6	196	2.47	29.5	3.2	0.8	41	3.2	9.8	0.3	111	0.48	0.110	9
1091493	Soil	27.9	23.9	10.6	242	<0.1	45.8	5.2	59	1.83	23.3	<0.5	0.3	8	0.3	7.4	0.2	116	0.05	0.056	10
1091494	Soil	30.1	22.0	15.5	291	<0.1	52.2	5.0	139	3.11	18.2	<0.5	0.3	4	0.3	13.4	0.1	180	0.01	0.069	7
1091495	Soil	2.3	10.6	7.7	18	0.8	3.8	0.7	16	0.49	5.5	1.3	0.5	12	<0.1	0.9	0.2	32	0.02	0.056	10
1091496	Soil	8.4	23.9	19.4	115	0.5	19.8	4.0	113	2.65	29.2	1.7	2.1	33	0.3	4.1	0.3	133	0.03	0.146	10
1091497	Soil	6.9	35.4	15.9	112	0.9	21.1	3.1	66	1.99	18.9	3.7	1.2	34	0.6	3.3	0.3	89	0.03	0.156	10
1091498	Soil	4.0	28.8	9.0	104	1.3	18.8	2.8	84	1.50	12.8	1.1	0.3	33	0.9	2.4	0.1	56	0.21	0.137	6
1091499	Soil	8.2	60.6	20.0	187	1.2	32.6	4.7	149	3.00	28.0	7.3	0.9	57	2.0	4.5	0.3	144	0.09	0.170	9
1091500	Soil	4.7	36.1	14.1	132	2.3	27.6	3.2	105	2.10	17.6	6.1	0.5	62	0.8	3.7	0.2	96	0.43	0.141	6
1091501	Soil	5.6	38.3	17.0	214	1.0	44.2	6.8	183	3.03	21.3	7.7	1.8	33	1.1	4.1	0.3	77	0.05	0.122	8
1091502	Soil	4.1	34.0	14.7	132	0.5	23.9	4.4	204	2.86	15.1	1.8	0.5	18	1.5	1.9	0.2	54	0.04	0.163	8
1091503	Soil	4.9	34.1	19.5	119	0.4	22.0	5.0	185	3.01	20.4	2.3	0.4	13	1.4	2.1	0.3	54	0.04	0.202	8
1091504	Soil	4.9	30.8	16.2	244	0.2	47.2	7.5	173	3.38	22.7	3.9	1.8	22	0.9	3.0	0.3	71	0.13	0.096	10
1091505	Soil	7.1	32.1	16.8	167	0.6	36.3	5.7	162	3.13	21.8	3.1	1.6	17	0.7	3.0	0.2	60	0.03	0.056	8
1091506	Soil	3.9	59.9	21.2	259	1.2	72.7	11.3	99	3.67	21.2	3.3	1.0	32	0.3	1.5	0.3	32	0.01	0.113	2
1091507	Soil	2.7	37.9	11.4	87	3.0	28.4	3.7	58	1.39	7.1	4.6	0.6	44	0.8	1.2	0.1	33	0.70	0.087	4
1091508	Soil	4.3	26.7	13.8	227	0.3	37.4	8.7	249	2.62	17.9	3.1	1.3	45	2.0	2.3	0.2	70	0.61	0.077	8
1091509	Soil	7.4	69.1	18.9	300	0.6	72.9	11.8	318	3.52	28.3	5.7	2.8	44	2.3	4.7	0.3	70	0.21	0.122	13
1091510	Soil	4.7	18.5	11.5	73	0.4	13.5	2.4	50	1.46	12.2	1.5	0.2	14	0.4	1.2	0.2	78	0.07	0.081	8
1091511	Soil	3.6	31.2	12.0	98	0.3	23.5	3.9	94	1.91	12.6	1.4	0.3	11	0.5	1.8	0.3	48	0.04	0.073	10
1091512	Soil	6.1	32.4	19.6	176	0.9	29.3	10.1	392	3.19	17.6	2.5	0.8	20	2.3	2.4	0.3	87	0.21	0.136	8
1091513	Soil	4.9	18.8	13.3	99	0.1	18.0	3.6	99	2.20	17.3	0.7	1.3	14	0.3	2.0	0.3	81	0.05	0.036	11
1091514	Soil	5.6	36.6	13.1	268	2.8	57.7	7.7	442	3.29	18.5	5.9	2.6	89	2.9	2.0	0.2	76	1.95	0.151	21
1091515	Soil	5.6	26.8	15.7	198	0.1	35.5	6.9	224	2.88	22.7	3.3	2.1	22	0.8	2.8	0.2	97	0.11	0.060	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091486	Soil	18	0.02	236	0.003	2	0.43	0.004	0.09	<0.1	0.10	4.7	0.3	0.18	2	5.0	0.3	N.A.	N.A.	N.A.	N.A.
1091487	Soil	18	0.19	892	0.002	2	0.78	0.004	0.09	<0.1	0.19	5.7	0.4	0.05	3	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091488	Soil	21	1.43	415	0.003	4	0.43	0.006	0.09	0.2	0.41	5.0	2.1	0.07	1	6.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091489	Soil	17	0.96	670	0.002	3	0.40	0.005	0.07	0.1	0.27	4.0	0.6	0.09	1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091490	Soil	15	0.10	526	0.005	2	0.56	0.003	0.07	<0.1	0.11	2.9	0.4	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091491	Soil	17	0.07	249	0.003	<1	0.49	0.002	0.07	0.2	0.04	0.7	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091492	Soil	18	0.08	623	0.002	2	0.52	0.004	0.07	0.2	0.25	2.5	0.6	0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091493	Soil	11	0.03	176	0.003	1	0.46	0.003	0.06	<0.1	0.03	0.4	0.3	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091494	Soil	13	0.04	97	0.003	1	0.49	0.001	0.06	<0.1	0.03	0.6	0.4	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091495	Soil	9	0.03	182	0.004	2	0.71	0.004	0.04	<0.1	0.10	0.3	0.3	<0.05	5	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091496	Soil	21	0.08	788	0.005	<1	1.00	0.003	0.08	0.2	0.06	1.6	0.5	<0.05	5	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091497	Soil	20	0.07	776	0.003	1	1.01	0.004	0.08	0.1	0.21	1.4	0.3	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091498	Soil	15	0.08	793	0.003	1	0.75	0.015	0.06	<0.1	0.24	0.5	0.2	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091499	Soil	35	0.16	1423	0.003	3	1.56	0.005	0.14	0.2	0.56	1.6	0.5	0.06	5	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091500	Soil	22	0.12	2154	0.003	3	1.30	0.017	0.09	<0.1	0.97	1.0	0.4	0.07	4	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091501	Soil	25	0.15	605	0.002	2	1.10	0.004	0.07	0.2	1.06	1.8	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091502	Soil	21	0.09	490	0.003	2	1.03	0.004	0.07	<0.1	0.13	0.7	0.2	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091503	Soil	20	0.06	645	0.003	1	0.81	0.004	0.05	<0.1	0.13	0.4	0.2	0.07	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091504	Soil	28	0.18	1185	0.002	1	1.29	0.003	0.07	0.2	1.04	2.3	0.2	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091505	Soil	22	0.16	705	0.002	2	0.94	0.004	0.07	<0.1	0.09	1.7	0.2	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091506	Soil	16	0.06	208	0.002	1	0.85	0.005	0.06	<0.1	0.10	4.0	<0.1	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091507	Soil	15	0.08	2117	0.002	2	0.94	0.019	0.07	<0.1	0.84	2.5	0.2	0.08	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091508	Soil	26	0.23	1109	0.004	2	1.28	0.005	0.07	<0.1	0.12	2.6	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091509	Soil	25	0.22	2723	0.002	3	1.25	0.004	0.08	<0.1	0.25	3.0	0.3	0.07	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091510	Soil	15	0.06	718	0.003	3	0.90	0.004	0.06	0.1	0.08	0.5	0.2	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091511	Soil	17	0.10	638	0.003	2	0.77	0.006	0.04	0.1	0.09	0.6	0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091512	Soil	24	0.05	658	0.004	1	1.09	0.007	0.06	<0.1	0.09	1.4	0.1	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091513	Soil	17	0.12	561	0.007	2	0.95	0.003	0.06	0.2	0.04	1.2	0.2	<0.05	5	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091514	Soil	40	0.13	3434	0.002	4	1.25	0.005	0.06	<0.1	0.64	6.9	0.2	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091515	Soil	28	0.19	3139	0.003	3	1.33	0.004	0.08	<0.1	0.11	2.0	0.2	0.05	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091486	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091487	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091488	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091489	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091490	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091491	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091492	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091493	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091494	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091495	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091496	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091497	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091498	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091499	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091500	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091501	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091502	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091503	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091504	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091505	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091506	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091507	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091508	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091509	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091510	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091511	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091512	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091513	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091514	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091515	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091486	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091487	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091488	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091489	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091490	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091491	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091492	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091493	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091494	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091495	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091496	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091497	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091498	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091499	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091500	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091501	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091502	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091503	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091504	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091505	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091506	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091507	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091508	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091509	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091510	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091511	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091512	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091513	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091514	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091515	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091516	Soil	4.9	41.6	12.1	156	1.0	48.1	9.0	264	2.52	16.1	5.1	2.3	81	0.9	3.6	0.2	45	1.36	0.179	11
1091517	Soil	4.6	50.4	12.7	151	1.0	45.9	7.4	175	2.17	16.4	6.8	1.5	75	1.2	2.6	0.2	71	0.96	0.096	9
1091518	Soil	4.6	16.7	10.5	91	0.3	16.3	3.1	67	1.31	16.9	<0.5	1.0	37	0.9	2.0	0.2	59	0.33	0.031	8
1091519	Soil	7.4	35.1	17.5	129	0.3	27.9	4.6	98	3.07	24.0	4.3	0.8	23	0.4	3.4	0.3	95	0.05	0.080	8
1091520	Soil	8.2	55.2	22.8	242	1.3	54.9	12.6	467	3.66	38.8	6.3	2.4	47	1.4	5.4	0.3	91	0.16	0.218	9
1091521	Soil	9.2	34.6	20.0	145	0.7	31.2	4.3	74	1.93	22.8	3.1	0.4	51	0.6	3.4	0.2	101	0.17	0.063	9
1091522	Soil	17.4	35.6	27.5	141	0.6	31.5	4.1	60	2.66	38.5	6.9	1.7	72	0.4	5.5	0.3	155	0.03	0.073	10
1091523	Soil	8.0	54.1	17.7	212	0.6	46.2	12.6	345	2.81	49.6	7.3	2.3	52	1.6	6.4	0.2	69	0.19	0.122	10
1091524	Soil	10.2	22.2	22.2	101	0.8	21.9	3.5	64	2.40	28.6	<0.5	1.3	38	0.3	3.8	0.3	132	0.03	0.079	8
1091525	Soil	4.4	18.6	12.6	88	1.2	16.3	3.3	68	2.00	14.6	<0.5	0.2	17	0.5	2.1	0.2	69	0.02	0.064	5
1091526	Soil	7.5	57.3	16.3	253	0.8	51.4	10.1	253	2.68	32.0	5.9	1.5	50	1.8	5.0	0.3	86	0.22	0.101	9
1091527	Soil	10.2	40.3	18.3	180	0.8	31.4	7.1	127	2.61	29.1	4.7	2.2	56	1.1	4.5	0.3	97	0.17	0.115	10
1091528	Soil	23.0	39.1	21.8	326	0.2	58.6	9.2	150	3.56	33.6	1.1	1.2	12	0.6	6.6	0.3	172	0.04	0.062	13
1091529	Soil	30.7	22.0	8.2	343	0.3	42.6	3.1	23	1.15	21.2	<0.5	0.4	3	0.2	12.3	0.1	277	0.04	0.037	11
1091530	Soil	7.2	34.4	10.9	137	0.2	35.4	4.5	67	1.94	12.5	0.8	1.4	12	0.4	3.3	0.2	48	0.11	0.063	16
1091531	Soil	23.7	63.4	14.7	611	1.1	80.2	8.4	143	2.14	24.1	2.6	4.9	65	6.4	9.9	0.2	165	3.49	0.074	10
1091532	Soil	6.2	62.0	23.1	222	0.5	63.8	16.3	350	3.77	32.9	1.7	2.5	54	0.5	3.3	0.3	45	0.27	0.198	15
1091533	Soil	2.9	13.3	4.9	52	0.8	13.0	2.2	19	0.73	5.8	<0.5	0.2	5	<0.1	0.8	<0.1	20	0.02	0.051	6
1091534	Soil	6.0	32.3	14.2	145	0.6	32.7	6.3	102	3.28	18.5	<0.5	0.5	8	<0.1	2.2	0.2	53	0.02	0.068	16
1091535	Soil	6.8	89.0	25.6	328	2.6	69.1	14.8	315	4.10	42.9	2.5	2.1	50	0.9	3.7	0.5	45	0.22	0.214	16
1091536	Soil	6.8	45.3	21.8	176	0.3	50.7	9.4	95	3.91	35.2	3.9	0.2	17	0.3	2.6	0.4	45	0.02	0.170	9
1091537	Soil	5.1	26.7	13.4	93	0.5	27.5	5.7	81	1.78	34.8	3.5	0.2	15	0.6	1.8	0.2	39	0.01	0.073	11
1091538	Soil	3.2	22.0	14.9	82	0.7	18.8	3.8	53	1.49	23.4	1.7	0.2	14	0.1	1.4	0.3	33	0.02	0.081	8
1091539	Soil	3.5	23.2	6.5	76	0.1	21.1	5.3	153	1.74	36.1	<0.5	0.1	6	0.1	1.5	0.2	35	0.01	0.059	6
1091540	Soil	7.1	29.3	25.5	144	0.7	38.8	5.7	141	3.21	61.0	<0.5	0.6	29	0.3	3.0	0.4	55	0.18	0.254	12
1091541	Soil	1.9	8.8	6.2	30	0.3	8.5	2.3	32	0.80	18.8	3.0	<0.1	5	<0.1	0.6	0.2	22	<0.01	0.039	10
1091542	Soil	2.9	15.0	8.5	66	0.2	14.9	4.4	387	2.10	8.5	0.6	0.7	13	0.2	0.9	0.3	43	0.08	0.035	11
1091543	Soil	3.0	11.6	4.5	39	<0.1	14.2	3.9	62	1.30	14.3	1.1	0.2	4	<0.1	0.9	0.1	31	<0.01	0.033	11
1091544	Soil	5.6	45.1	24.4	129	0.9	44.9	15.5	326	4.95	29.1	4.9	2.4	15	0.3	3.1	0.3	24	0.09	0.112	16
1091545	Soil	4.4	29.5	18.4	103	0.1	32.4	9.3	228	3.26	20.9	1.3	0.6	11	0.2	2.0	0.3	33	0.05	0.071	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091516	Soil	18	0.21	3664	0.003	5	1.00	0.006	0.08	<0.1	0.34	3.9	0.2	0.06	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091517	Soil	26	0.26	2401	0.004	4	1.16	0.006	0.07	<0.1	0.56	2.8	0.2	0.06	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091518	Soil	12	0.11	497	0.008	2	0.55	0.006	0.04	0.1	0.05	1.0	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091519	Soil	22	0.11	482	0.003	2	0.95	0.004	0.07	0.1	0.14	1.3	0.3	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091520	Soil	28	0.20	1386	0.004	4	1.25	0.004	0.10	0.1	0.63	2.6	0.5	<0.05	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091521	Soil	18	0.07	1605	0.004	2	0.90	0.009	0.07	0.1	0.25	1.0	0.4	<0.05	4	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091522	Soil	24	0.06	545	0.003	2	0.83	0.003	0.08	0.2	0.23	1.9	0.6	0.06	3	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091523	Soil	29	0.22	1863	0.003	2	0.76	0.002	0.06	0.1	0.22	2.3	0.3	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091524	Soil	21	0.08	355	0.004	2	0.81	0.004	0.06	0.1	0.05	1.4	0.4	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091525	Soil	19	0.07	182	0.006	1	0.62	0.009	0.06	0.1	0.09	0.8	0.2	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091526	Soil	23	0.17	1922	0.003	2	0.88	0.005	0.08	0.1	0.43	2.1	0.3	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091527	Soil	31	0.21	1882	0.004	3	0.99	0.003	0.08	0.1	0.63	2.3	0.3	<0.05	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091528	Soil	21	0.09	155	0.008	1	0.97	0.003	0.09	0.1	0.04	1.6	0.4	<0.05	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091529	Soil	13	0.04	130	0.003	3	0.39	0.004	0.09	<0.1	0.04	0.5	0.3	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091530	Soil	14	0.04	353	0.002	2	0.47	0.002	0.07	<0.1	0.05	1.4	0.2	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091531	Soil	11	1.83	472	0.002	7	0.25	0.004	0.10	<0.1	0.38	4.1	0.4	<0.05	<1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091532	Soil	15	0.08	2965	0.003	5	0.79	0.002	0.14	<0.1	0.11	3.0	0.2	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091533	Soil	5	0.02	265	0.004	2	0.27	0.012	0.05	<0.1	0.05	0.3	<0.1	<0.05	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091534	Soil	14	0.06	849	0.004	3	0.79	0.002	0.06	0.1	0.06	0.7	0.2	<0.05	4	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091535	Soil	16	0.15	2102	0.006	4	0.97	0.003	0.12	0.1	0.39	2.7	0.2	0.05	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091536	Soil	13	0.04	730	0.002	4	0.67	0.003	0.10	<0.1	0.05	0.2	0.3	0.10	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091537	Soil	8	0.02	379	0.002	4	0.43	0.006	0.06	<0.1	0.03	0.3	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091538	Soil	8	0.02	263	0.004	3	0.46	0.007	0.05	0.1	0.02	0.1	0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091539	Soil	7	0.02	150	0.003	3	0.31	0.009	0.05	0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091540	Soil	18	0.09	187	0.009	4	0.93	0.004	0.09	0.1	0.07	1.0	0.3	<0.05	3	1.8	0.2	N.A.	N.A.	N.A.	N.A.
1091541	Soil	7	0.02	92	0.005	4	0.35	0.008	0.05	<0.1	0.01	0.2	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091542	Soil	13	0.06	731	0.010	3	0.86	0.008	0.07	0.2	0.04	1.1	0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091543	Soil	9	0.03	907	0.003	3	0.35	0.007	0.06	<0.1	0.01	0.4	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091544	Soil	12	0.13	201	0.007	4	0.75	0.003	0.09	0.2	0.16	2.7	0.2	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091545	Soil	10	0.06	353	0.005	4	0.60	0.004	0.10	<0.1	0.06	1.1	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091516	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091517	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091518	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091519	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091520	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091521	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091522	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091523	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091524	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091525	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091526	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091527	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091528	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091529	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091530	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091531	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091532	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091533	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091534	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091535	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091536	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091537	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091538	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091539	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091540	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091541	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091542	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091543	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091544	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091545	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091516	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091517	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091518	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091519	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091520	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091521	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091522	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091523	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091524	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091525	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091526	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091527	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091528	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091529	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091530	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091531	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091532	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091533	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091534	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091535	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091536	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091537	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091538	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091539	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091540	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091541	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091542	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091543	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091544	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091545	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091546	Soil	1.9	20.1	12.9	49	0.5	17.3	4.8	80	1.68	7.9	1.0	0.3	4	<0.1	1.2	0.2	13	0.01	0.072	4
1091547	Soil	5.0	38.6	21.1	158	0.3	46.5	14.3	349	4.03	19.7	3.7	2.2	19	0.1	2.6	0.3	30	0.26	0.085	15
1091548	Soil	5.4	21.8	8.0	95	0.1	25.8	6.4	83	1.83	24.4	<0.5	0.4	4	<0.1	1.8	0.1	42	0.01	0.048	7
1091549	Soil	16.7	23.3	7.5	110	<0.1	31.3	5.3	55	1.60	53.9	1.8	0.8	5	<0.1	2.9	0.2	82	<0.01	0.029	10
1091550	Soil	12.9	19.8	17.1	95	0.4	31.1	4.6	93	1.56	24.8	2.3	0.8	9	<0.1	2.6	0.2	72	0.02	0.088	8
1091551	Soil	5.1	33.3	15.5	127	0.2	35.8	9.2	161	3.11	28.7	2.5	1.8	11	0.2	2.4	0.3	38	0.03	0.066	16
1091552	Soil	7.5	35.4	20.8	148	0.3	41.8	9.3	117	3.52	35.2	1.6	1.9	17	0.3	2.7	0.4	62	0.05	0.055	14
1091553	Soil	5.7	29.5	17.1	125	0.3	32.0	9.3	243	2.80	21.1	0.7	1.3	16	0.2	2.5	0.2	54	0.07	0.114	13
1091554	Soil	0.4	3.5	1.6	17	0.1	3.0	1.3	72	0.34	1.6	1.0	<0.1	7	0.2	0.2	<0.1	5	0.07	0.026	1
1091555	Soil	4.4	49.5	21.7	152	0.6	43.0	18.5	487	5.52	27.1	1.8	3.5	5	0.4	2.5	0.3	22	0.04	0.053	15
1091556	Soil	4.0	74.7	18.8	120	0.1	57.7	35.1	1145	8.05	41.2	3.2	5.4	10	0.2	2.4	0.8	31	0.10	0.070	36
1091557	Soil	6.4	28.6	12.8	81	0.5	27.3	7.3	113	2.52	11.8	1.0	1.4	4	0.1	2.2	0.2	41	<0.01	0.034	15
1091558	Soil	2.5	27.3	9.1	55	0.2	24.6	8.1	187	2.89	8.6	2.6	1.7	5	<0.1	1.2	0.3	39	0.01	0.030	14
1091559	Soil	1.4	12.3	4.6	27	<0.1	13.9	4.9	515	2.07	4.5	<0.5	1.1	7	<0.1	1.0	0.2	28	0.07	0.030	12
1091560	Soil	2.2	32.6	7.2	29	0.2	40.2	8.4	249	2.69	9.3	1.1	0.4	3	<0.1	1.5	0.2	25	0.01	0.046	12
1091561	Soil	0.7	9.1	3.0	13	0.2	6.7	2.2	92	0.70	1.7	<0.5	<0.1	16	0.1	0.4	0.1	11	0.35	0.035	4
1091562	Soil	3.7	14.7	4.4	58	0.4	16.4	4.5	51	1.30	23.2	3.3	0.1	5	0.1	1.6	0.1	31	0.03	0.038	7
1091563	Soil	20.3	96.2	17.8	660	1.3	128.3	13.1	248	3.92	69.2	4.0	5.6	40	5.9	11.8	0.2	118	0.64	0.148	24
1091564	Soil	9.2	56.8	11.9	281	0.6	63.0	9.2	172	2.38	23.8	<0.5	4.8	20	1.8	5.6	0.2	56	0.37	0.086	29
1091565	Soil	8.7	40.5	9.9	203	0.6	43.2	5.9	108	2.01	18.3	2.2	2.5	21	1.0	4.9	0.2	37	0.25	0.071	12
1091566	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091567	Soil	19.7	53.8	18.7	332	0.6	80.7	8.2	118	3.51	63.3	7.4	3.2	29	0.9	7.9	0.5	147	0.15	0.096	18
1091568	Soil	8.7	29.6	10.1	166	0.8	35.7	4.7	76	1.78	22.9	3.4	0.6	18	0.8	3.2	0.2	62	0.17	0.068	12
1091569	Soil	30.0	41.1	10.5	169	0.3	91.7	5.9	204	1.08	33.6	1.8	0.4	76	1.6	3.3	0.1	26	2.15	0.080	7
1091570	Soil	7.1	81.7	23.7	129	1.0	47.2	14.2	104	3.14	17.7	5.1	0.5	14	0.4	3.6	0.4	37	0.03	0.103	3
1091571	Soil	5.9	45.0	12.0	105	0.2	29.1	7.7	293	2.00	13.7	1.7	0.2	8	0.3	2.4	0.2	43	0.03	0.083	5
1091572	Soil	5.6	66.6	24.3	193	0.5	58.1	17.9	651	4.17	16.1	1.8	0.8	18	0.6	2.8	0.3	43	0.05	0.090	6
1091573	Soil	4.1	38.6	15.2	114	0.6	30.4	15.6	740	2.47	11.4	2.7	0.2	10	0.5	2.0	0.3	41	0.05	0.089	6
1091574	Soil	2.5	17.8	6.0	38	0.1	10.9	3.0	54	1.10	7.5	1.9	0.2	6	<0.1	1.1	0.1	36	0.03	0.031	6
1091575	Soil	41.5	48.4	21.2	273	2.0	61.7	5.9	104	2.07	21.7	2.3	0.5	149	4.0	10.0	0.2	110	0.07	0.112	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091546	Soil	6	0.03	127	0.003	3	0.42	0.014	0.06	<0.1	0.09	0.9	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091547	Soil	14	0.14	434	0.006	4	0.72	0.002	0.11	<0.1	0.10	2.8	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091548	Soil	7	0.02	109	0.002	6	0.34	0.006	0.08	<0.1	0.02	0.7	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091549	Soil	8	0.02	129	0.002	4	0.29	0.002	0.06	0.1	0.02	0.8	0.2	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091550	Soil	15	0.03	208	0.005	5	0.48	0.007	0.07	0.2	0.05	1.1	0.3	<0.05	3	1.7	0.4	N.A.	N.A.	N.A.	N.A.
1091551	Soil	12	0.07	809	0.004	4	0.62	0.003	0.10	<0.1	0.08	2.1	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091552	Soil	14	0.08	477	0.004	3	0.76	0.002	0.09	<0.1	0.05	2.2	0.3	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091553	Soil	15	0.09	311	0.007	4	0.64	0.005	0.09	0.1	0.07	1.5	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091554	Soil	2	0.02	61	0.005	2	0.10	0.026	0.03	<0.1	0.03	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091555	Soil	15	0.06	267	0.005	4	0.60	0.002	0.17	<0.1	0.08	4.3	0.3	<0.05	2	<0.5	0.2	N.A.	N.A.	N.A.	N.A.
1091556	Soil	12	0.09	322	0.005	4	0.73	0.002	0.18	<0.1	0.04	4.1	0.3	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091557	Soil	9	0.04	147	0.006	3	0.62	0.004	0.08	<0.1	0.03	1.1	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091558	Soil	9	0.04	143	0.009	2	0.54	0.005	0.07	0.1	0.05	1.4	0.2	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091559	Soil	10	0.07	284	0.004	3	0.75	0.009	0.05	0.1	0.03	1.0	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091560	Soil	8	0.03	89	0.004	3	0.31	0.008	0.07	<0.1	0.03	0.7	<0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091561	Soil	4	0.05	280	0.005	1	0.31	0.025	0.04	<0.1	0.02	0.5	0.1	0.06	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091562	Soil	6	0.02	166	0.002	2	0.29	0.014	0.04	<0.1	0.04	0.4	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091563	Soil	19	0.10	1143	0.003	8	0.59	0.004	0.15	<0.1	0.46	5.6	0.3	<0.05	1	2.7	0.3	N.A.	N.A.	N.A.	N.A.
1091564	Soil	11	0.07	728	0.002	3	0.39	0.003	0.10	<0.1	0.31	3.8	0.2	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091565	Soil	8	0.06	911	0.002	2	0.36	0.004	0.06	<0.1	0.26	3.0	0.1	<0.05	<1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091566	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	9.1	42.7	12.9	222
1091567	Soil	29	0.16	362	0.005	6	1.02	0.003	0.10	0.3	0.99	2.4	0.6	<0.05	3	2.8	0.2	N.A.	N.A.	N.A.	N.A.
1091568	Soil	13	0.07	656	0.003	2	0.61	0.012	0.07	<0.1	0.37	1.2	0.3	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091569	Soil	16	0.15	277	0.005	4	0.35	0.013	0.05	0.2	0.46	1.4	0.8	0.12	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091570	Soil	15	0.02	148	0.001	2	0.46	0.003	0.07	<0.1	0.09	1.7	0.3	0.07	2	1.3	0.2	N.A.	N.A.	N.A.	N.A.
1091571	Soil	13	0.02	67	0.002	1	0.52	0.005	0.05	0.1	<0.01	0.4	0.2	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091572	Soil	22	0.10	158	0.003	2	0.80	0.003	0.06	<0.1	0.04	2.4	0.3	0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091573	Soil	15	0.11	105	0.005	1	0.73	0.009	0.06	0.1	0.05	1.1	0.2	0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091574	Soil	8	0.02	49	0.008	<1	0.36	0.011	0.03	0.1	0.01	0.4	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091575	Soil	16	0.02	464	0.003	2	0.50	0.012	0.09	0.1	0.16	1.4	1.2	0.15	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091546	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091547	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091548	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091549	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091550	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091551	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091552	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091553	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091554	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091555	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091556	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091557	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091558	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091559	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091560	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091561	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091562	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091563	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091564	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091565	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091566	Soil	0.5	49.9	7.0	168	2.09	20.3	2.7	1.9	18	1.1	3.8	0.2	31	0.24	0.070	10	12	0.05	683	0.002
1091567	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091568	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091569	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091570	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091571	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091572	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091573	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091574	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091575	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091546	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091547	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091548	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091549	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091550	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091551	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091552	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091553	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091554	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091555	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091556	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091557	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091558	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091559	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091560	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091561	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091562	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091563	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091564	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091565	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091566	Soil	<20	0.30	0.004	0.04	<0.1	0.25	2.6	0.1	<0.05	<1	1.5	<0.2
1091567	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091568	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091569	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091570	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091571	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091572	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091573	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091574	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091575	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091576	Soil	24.6	84.4	16.9	362	1.1	119.7	11.7	91	2.52	18.0	2.9	2.7	29	2.9	6.5	0.2	64	0.35	0.129	16
1091577	Soil	0.6	3.3	2.7	6	0.2	2.4	1.0	206	0.27	1.0	8.9	<0.1	6	<0.1	0.2	<0.1	7	0.04	0.038	<1
1091578	Soil	3.9	3.5	4.4	23	<0.1	8.3	0.8	14	0.31	3.6	7.6	<0.1	5	<0.1	0.8	<0.1	26	0.02	0.047	2
1091579	Soil	14.3	19.9	12.9	215	0.2	30.6	4.0	71	1.87	21.4	3.1	0.2	9	0.8	5.9	0.2	107	0.03	0.060	6
1091580	Soil	15.3	12.2	8.8	209	0.1	23.7	3.3	68	1.25	15.1	4.1	0.2	9	0.6	6.1	0.1	124	0.05	0.083	7
1091581	Soil	7.7	32.5	13.5	164	0.2	44.2	7.2	59	2.20	19.3	4.0	0.1	11	<0.1	2.5	0.2	54	<0.01	0.093	9
1091582	Soil	4.9	14.0	8.7	81	0.2	21.0	3.4	34	1.12	8.0	3.9	<0.1	9	0.1	1.1	0.1	31	0.02	0.098	5
1091583	Soil	19.8	48.4	63.0	194	1.5	40.5	4.8	57	2.51	26.8	3.4	0.2	115	0.4	5.9	0.4	169	0.03	0.147	13
1091584	Soil	6.1	39.4	17.2	157	0.6	55.1	7.4	142	2.59	15.2	11.2	0.2	32	0.3	2.0	0.2	41	0.27	0.323	13
1091585	Soil	7.5	39.8	27.3	135	0.5	44.8	13.7	387	4.13	18.1	5.7	0.9	9	0.2	1.3	0.3	17	0.05	0.056	7
1091586	Soil	4.2	32.6	28.5	82	1.6	16.9	2.7	32	2.40	12.1	4.8	0.3	35	<0.1	1.4	0.3	40	0.02	0.163	9
1091587	Soil	3.7	77.8	23.9	247	2.8	69.0	14.9	406	4.38	12.9	9.2	1.3	13	0.4	2.0	0.3	32	0.08	0.131	10
1091588	Soil	6.3	85.4	28.3	326	3.5	97.2	12.5	181	3.64	32.1	11.0	4.3	51	0.9	4.5	0.3	27	0.47	0.091	15
1091589	Soil	6.0	242.3	30.0	842	1.0	251.6	29.9	202	6.19	53.9	12.2	4.3	49	0.6	5.6	1.0	35	0.37	0.372	23
1091590	Soil	6.6	38.8	19.8	172	0.4	41.5	6.2	96	1.81	11.3	3.6	<0.1	18	0.4	2.6	0.2	46	0.08	0.134	10
1091591	Soil	12.6	80.1	22.2	267	1.0	107.3	12.7	216	3.25	22.5	8.0	1.3	29	0.8	4.8	0.3	46	0.37	0.182	16
1091592	Soil	10.1	78.8	38.3	281	1.3	115.9	16.4	422	5.08	28.9	7.6	1.9	83	0.5	4.5	0.3	131	0.27	0.342	21
1091593	Soil	5.3	20.3	14.3	82	0.5	27.7	5.4	397	1.21	7.8	5.5	<0.1	26	0.1	1.6	0.1	41	0.05	0.111	5
1091594	Soil	5.1	37.3	13.9	162	0.4	47.5	6.5	198	1.92	10.7	1.8	0.3	25	0.6	1.8	0.2	36	0.17	0.219	10
1091595	Soil	3.9	35.1	12.1	108	0.4	33.2	8.3	94	3.04	13.2	3.2	1.0	13	0.2	1.7	0.2	29	0.03	0.074	9
1091596	Soil	2.3	12.1	4.4	41	<0.1	13.2	3.0	33	0.94	8.1	<0.5	0.1	4	<0.1	0.9	<0.1	29	<0.01	0.029	9
1091597	Soil	3.0	17.0	5.4	50	<0.1	17.9	5.3	62	1.74	9.7	0.8	0.2	5	<0.1	1.1	0.2	32	0.02	0.045	9
1091598	Soil	9.5	20.3	6.4	115	<0.1	27.8	5.3	52	1.51	21.7	<0.5	0.2	6	0.1	2.6	0.1	81	0.03	0.051	8
1091599	Soil	5.5	41.4	13.7	173	1.0	51.5	13.1	165	2.72	50.8	3.6	0.4	22	0.5	2.5	0.1	19	0.07	0.113	9
1091600	Soil	3.5	16.8	9.1	77	0.3	20.1	3.5	41	1.22	18.6	<0.5	0.1	7	<0.1	1.3	0.1	31	0.02	0.073	6
1090831	Soil	6.6	11.4	15.3	68	0.5	13.7	1.7	24	0.87	15.8	0.7	0.7	27	0.3	2.5	0.2	73	0.08	0.033	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091576	Soil	19	0.04	266	0.002	3	0.30	0.002	0.07	<0.1	0.17	3.8	0.4	<0.05	<1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091577	Soil	4	0.02	28	0.008	1	0.28	0.027	0.02	<0.1	0.07	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091578	Soil	11	0.01	45	0.004	2	0.19	0.015	0.03	<0.1	0.07	0.2	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091579	Soil	12	0.05	108	0.004	1	0.46	0.010	0.05	<0.1	0.06	0.4	0.3	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091580	Soil	10	0.03	170	0.002	2	0.47	0.004	0.06	<0.1	0.04	0.2	0.3	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091581	Soil	13	0.03	195	0.002	4	0.46	0.003	0.09	<0.1	0.05	0.2	0.2	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091582	Soil	9	0.03	209	0.001	3	0.34	0.011	0.08	<0.1	0.04	0.1	0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091583	Soil	22	0.03	423	0.004	4	0.49	0.008	0.15	0.2	0.05	0.2	0.5	0.21	3	3.6	0.4	N.A.	N.A.	N.A.	N.A.
1091584	Soil	17	0.06	884	0.003	7	0.65	0.004	0.17	<0.1	0.17	0.5	0.3	0.14	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091585	Soil	8	0.04	497	0.003	3	0.48	0.009	0.11	<0.1	0.12	2.2	0.2	<0.05	1	1.6	0.2	N.A.	N.A.	N.A.	N.A.
1091586	Soil	15	0.03	723	0.006	3	0.56	0.004	0.18	0.1	0.09	0.5	0.3	0.36	3	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091587	Soil	15	0.11	2055	0.008	4	0.94	0.013	0.13	<0.1	0.33	2.8	0.2	0.10	2	9.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091588	Soil	17	0.10	751	0.004	3	0.38	0.002	0.10	0.2	0.65	5.6	0.1	0.11	1	4.5	0.2	N.A.	N.A.	N.A.	N.A.
1091589	Soil	17	0.04	604	0.003	6	0.58	0.002	0.19	<0.1	0.31	5.7	0.2	0.07	2	14.0	0.7	N.A.	N.A.	N.A.	N.A.
1091590	Soil	11	0.02	268	0.001	2	0.50	0.012	0.07	<0.1	0.10	0.2	0.1	0.05	2	2.3	0.2	N.A.	N.A.	N.A.	N.A.
1091591	Soil	12	0.05	728	0.002	7	0.57	0.003	0.16	<0.1	0.44	2.6	0.2	<0.05	2	3.4	0.3	N.A.	N.A.	N.A.	N.A.
1091592	Soil	22	0.05	917	0.004	6	0.62	0.003	0.15	<0.1	0.20	3.1	0.2	0.10	2	6.1	0.2	N.A.	N.A.	N.A.	N.A.
1091593	Soil	12	0.02	478	0.001	3	0.31	0.016	0.06	<0.1	0.09	0.3	0.1	0.06	1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091594	Soil	12	0.04	719	0.003	3	0.52	0.010	0.09	0.1	0.06	0.5	0.2	0.07	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091595	Soil	11	0.08	2361	0.007	2	0.95	0.010	0.07	0.1	0.13	1.5	0.2	0.09	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091596	Soil	7	0.02	118	0.005	2	0.29	0.009	0.05	0.1	<0.01	0.2	<0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091597	Soil	8	0.03	267	0.005	2	0.61	0.009	0.06	0.1	0.01	0.4	0.2	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091598	Soil	11	0.04	444	0.003	2	0.48	0.009	0.07	<0.1	<0.01	0.4	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091599	Soil	7	0.04	1848	0.003	2	0.46	0.012	0.06	<0.1	0.09	1.1	0.2	0.06	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091600	Soil	7	0.02	176	0.002	2	0.34	0.010	0.05	<0.1	<0.01	0.1	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090831	Soil	11	0.02	293	0.004	3	0.32	0.002	0.06	0.1	0.08	0.6	0.3	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091576	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091577	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091578	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091579	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091580	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091581	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091582	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091583	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091584	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091585	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091586	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091587	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091588	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091589	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091590	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091591	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091592	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091593	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091594	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091595	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091596	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091597	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091598	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091599	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091600	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090831	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

CERTIFICATE OF ANALYSIS WHI11000621.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091576	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091577	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091578	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091579	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091580	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091581	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091582	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091583	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091584	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091585	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091586	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091587	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091588	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091589	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091590	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091591	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091592	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091593	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091594	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091595	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091596	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091597	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091598	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091599	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091600	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090831	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

QUALITY CONTROL REPORT WHI11000621.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1091412	Soil	4.2	12.8	10.8	66	<0.1	14.4	3.7	91	1.80	14.8	<0.5	2.2	10	0.2	1.2	0.2	51	0.02	0.024	8
REP 1091412	QC	3.9	12.7	11.2	65	<0.1	14.0	3.6	91	1.83	14.5	<0.5	2.1	10	0.2	1.2	0.2	50	0.03	0.025	8
1091426	Soil	8.2	35.9	16.1	196	0.6	43.9	11.2	190	2.46	22.6	1.8	3.9	38	0.5	3.3	0.2	48	0.18	0.109	15
REP 1091426	QC	7.7	34.9	15.9	199	0.5	42.7	10.8	188	2.46	22.9	2.1	4.1	38	0.5	3.5	0.2	46	0.19	0.108	14
1091441	Soil	10.9	14.7	8.8	140	0.4	27.5	3.2	68	1.32	16.4	1.8	0.5	11	0.6	2.4	0.1	148	0.03	0.059	10
REP 1091441	QC	10.6	14.1	8.8	134	0.3	25.7	3.0	67	1.25	15.2	<0.5	0.7	11	0.5	2.5	0.1	143	0.03	0.059	9
1091454	Soil	4.6	39.8	11.9	227	0.7	36.4	6.3	111	2.14	14.4	5.1	1.9	91	1.0	3.0	0.2	75	0.59	0.068	9
REP 1091454	QC	4.0	40.1	11.3	229	0.7	35.5	6.4	111	2.21	14.0	7.5	2.0	92	1.0	2.9	0.1	73	0.62	0.073	8
1091468	Soil	7.8	41.1	14.3	203	0.8	38.6	6.5	194	2.28	22.3	4.9	1.7	103	1.3	3.6	0.2	81	0.56	0.115	8
REP 1091468	QC	7.6	39.2	13.5	193	0.7	37.3	6.4	190	2.22	21.6	6.7	1.6	100	1.1	3.5	0.2	78	0.53	0.112	8
1091480	Soil	2.7	27.4	12.8	102	3.4	15.3	3.6	164	1.48	8.8	3.7	0.3	58	1.4	1.0	0.2	46	0.96	0.084	9
REP 1091480	QC	2.4	27.1	12.7	102	3.3	16.1	3.7	161	1.49	9.1	3.2	0.2	59	1.4	1.0	0.2	47	0.94	0.084	9
1091502	Soil	4.1	34.0	14.7	132	0.5	23.9	4.4	204	2.86	15.1	1.8	0.5	18	1.5	1.9	0.2	54	0.04	0.163	8
REP 1091502	QC	4.4	33.4	15.3	132	0.6	23.9	4.4	208	2.86	15.3	1.6	0.6	18	1.8	1.9	0.2	56	0.04	0.165	8
1091529	Soil	30.7	22.0	8.2	343	0.3	42.6	3.1	23	1.15	21.2	<0.5	0.4	3	0.2	12.3	0.1	277	0.04	0.037	11
REP 1091529	QC	29.4	21.9	8.0	344	0.2	42.2	3.2	24	1.14	21.0	1.4	0.4	3	0.2	12.2	0.1	274	0.04	0.037	11
1091538	Soil	3.2	22.0	14.9	82	0.7	18.8	3.8	53	1.49	23.4	1.7	0.2	14	0.1	1.4	0.3	33	0.02	0.081	8
REP 1091538	QC	3.1	22.6	14.8	81	0.7	18.5	3.8	54	1.50	23.7	<0.5	<0.1	14	0.2	1.2	0.3	34	0.01	0.080	8
1091558	Soil	2.5	27.3	9.1	55	0.2	24.6	8.1	187	2.89	8.6	2.6	1.7	5	<0.1	1.2	0.3	39	0.01	0.030	14
REP 1091558	QC	2.1	27.5	9.3	60	0.2	24.9	8.4	184	2.81	8.6	3.2	1.8	5	<0.1	1.3	0.3	39	0.01	0.033	15
1091576	Soil	24.6	84.4	16.9	362	1.1	119.7	11.7	91	2.52	18.0	2.9	2.7	29	2.9	6.5	0.2	64	0.35	0.129	16
REP 1091576	QC	23.4	79.6	16.3	346	1.0	114.0	10.9	91	2.46	16.5	3.8	2.7	29	2.8	6.4	0.2	63	0.34	0.126	16
1091597	Soil	3.0	17.0	5.4	50	<0.1	17.9	5.3	62	1.74	9.7	0.8	0.2	5	<0.1	1.1	0.2	32	0.02	0.045	9
REP 1091597	QC	3.1	17.1	5.3	51	<0.1	18.1	5.5	62	1.76	9.6	0.5	0.3	5	<0.1	1.3	0.2	33	0.01	0.044	9
Reference Materials																					
STD DS8	Standard	12.4	107.2	124.2	304	1.7	37.1	7.4	592	2.44	25.7	112.7	7.2	72	2.4	5.9	6.9	39	0.70	0.080	16
STD DS8	Standard	13.3	109.8	129.1	305	1.9	37.8	7.6	625	2.50	26.1	111.2	7.5	73	2.3	6.1	7.3	36	0.69	0.082	16
STD DS8	Standard	12.9	96.9	104.7	297	1.7	37.7	7.5	603	2.39	27.0	113.6	6.2	59	2.2	5.0	6.1	42	0.68	0.077	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

QUALITY CONTROL REPORT WHI11000621.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																						
1091412	Soil		10	0.06	154	0.003	1	0.62	0.003	0.06	<0.1	0.05	1.4	<0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091412	QC		10	0.06	155	0.003	<1	0.62	0.003	0.06	<0.1	0.08	1.2	0.1	<0.05	4	<0.5	<0.2				
1091426	Soil		13	0.14	2327	0.008	3	0.70	0.004	0.10	<0.1	0.22	2.4	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091426	QC		13	0.14	2196	0.007	3	0.67	0.004	0.09	0.1	0.22	2.4	0.2	<0.05	2	2.1	<0.2				
1091441	Soil		12	0.06	194	0.003	1	0.66	0.005	0.05	0.1	0.03	0.8	0.3	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091441	QC		11	0.05	186	0.002	1	0.64	0.005	0.05	0.2	0.04	0.7	0.2	<0.05	2	1.3	<0.2				
1091454	Soil		24	0.22	2213	0.004	2	0.93	0.004	0.08	0.1	0.44	2.9	0.2	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091454	QC		23	0.23	2142	0.006	2	0.95	0.004	0.07	0.1	0.46	2.7	0.2	<0.05	3	1.7	<0.2				
1091468	Soil		22	0.20	1492	0.004	3	0.86	0.005	0.07	0.2	0.60	2.7	0.3	0.06	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091468	QC		22	0.20	1395	0.004	2	0.85	0.005	0.07	0.1	0.57	2.4	0.2	0.06	2	1.8	<0.2				
1091480	Soil		17	0.08	2456	0.004	1	1.04	0.006	0.04	0.1	0.16	0.9	0.1	0.06	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091480	QC		17	0.08	2433	0.005	1	1.03	0.006	0.03	<0.1	0.21	0.8	0.1	<0.05	3	1.2	<0.2				
1091502	Soil		21	0.09	490	0.003	2	1.03	0.004	0.07	<0.1	0.13	0.7	0.2	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091502	QC		22	0.10	497	0.003	2	1.03	0.004	0.06	<0.1	0.09	0.7	0.2	<0.05	3	0.9	<0.2				
1091529	Soil		13	0.04	130	0.003	3	0.39	0.004	0.09	<0.1	0.04	0.5	0.3	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091529	QC		13	0.04	125	0.002	5	0.38	0.004	0.08	<0.1	0.04	0.4	0.3	<0.05	2	2.9	<0.2				
1091538	Soil		8	0.02	263	0.004	3	0.46	0.007	0.05	0.1	0.02	0.1	0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091538	QC		9	0.02	264	0.002	4	0.45	0.007	0.06	<0.1	0.03	0.2	0.2	<0.05	2	0.9	<0.2				
1091558	Soil		9	0.04	143	0.009	2	0.54	0.005	0.07	0.1	0.05	1.4	0.2	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091558	QC		9	0.04	146	0.009	3	0.56	0.005	0.07	0.1	0.03	1.3	0.1	<0.05	3	<0.5	<0.2				
1091576	Soil		19	0.04	266	0.002	3	0.30	0.002	0.07	<0.1	0.17	3.8	0.4	<0.05	<1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091576	QC		19	0.04	270	0.002	4	0.31	0.002	0.07	<0.1	0.19	3.7	0.4	<0.05	<1	3.4	<0.2				
1091597	Soil		8	0.03	267	0.005	2	0.61	0.009	0.06	0.1	0.01	0.4	0.2	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091597	QC		7	0.03	263	0.004	1	0.59	0.009	0.05	0.2	<0.01	0.5	0.1	<0.05	3	0.7	<0.2				
Reference Materials																						
STD DS8	Standard		116	0.60	289	0.116	2	0.98	0.120	0.41	2.9	0.20	2.8	5.5	0.13	5	4.5	4.6				
STD DS8	Standard		120	0.61	286	0.119	2	0.92	0.103	0.44	2.9	0.20	2.7	5.4	0.16	5	5.8	5.2				
STD DS8	Standard		116	0.59	274	0.110	3	0.87	0.088	0.41	3.0	0.24	1.9	5.3	0.17	5	4.7	5.0				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

QUALITY CONTROL REPORT WHI11000621.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1091412	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091412	QC																					
1091426	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091426	QC																					
1091441	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091441	QC																					
1091454	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091454	QC																					
1091468	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091468	QC																					
1091480	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091480	QC																					
1091502	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091502	QC																					
1091529	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091529	QC																					
1091538	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091538	QC																					
1091558	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091558	QC																					
1091576	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091576	QC																					
1091597	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091597	QC																					
Reference Materials																						
STD DS8	Standard																					
STD DS8	Standard																					
STD DS8	Standard																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

QUALITY CONTROL REPORT WHI11000621.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1091412	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091412	QC													
1091426	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091426	QC													
1091441	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091441	QC													
1091454	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091454	QC													
1091468	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091468	QC													
1091480	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091480	QC													
1091502	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091502	QC													
1091529	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091529	QC													
1091538	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091538	QC													
1091558	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091558	QC													
1091576	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091576	QC													
1091597	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091597	QC													
Reference Materials														
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

QUALITY CONTROL REPORT WHI11000621.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	12.8	97.0	105.1	295	1.7	36.8	7.2	580	2.32	26.7	105.2	5.9	63	2.2	4.8	5.7	41	0.68	0.074	15
STD DS8	Standard	12.7	110.6	115.6	318	1.8	35.5	7.2	617	2.44	26.6	99.9	6.6	63	2.3	5.5	6.4	42	0.68	0.077	14
STD DS8	Standard	12.6	106.3	116.8	309	1.8	37.6	7.3	607	2.42	25.9	111.2	6.5	63	2.3	5.4	6.2	42	0.65	0.080	13
STD DS8	Standard	13.5	105.1	124.8	305	1.8	37.5	7.8	620	2.80	26.4	113.1	7.1	67	2.2	5.3	6.3	42	0.71	0.079	16
STD DS8	Standard	13.9	107.9	128.9	313	1.7	37.7	7.7	613	2.78	26.2	111.9	7.4	72	2.2	5.3	6.5	44	0.69	0.079	16
STD DS8	Standard	12.8	105.0	130.1	311	1.9	35.3	7.3	621	2.53	27.9	112.0	7.4	79	2.4	6.1	7.0	43	0.68	0.082	15
STD DS8	Standard	12.9	100.8	128.9	302	1.8	32.3	7.0	596	2.40	26.5	154.1	7.4	75	2.3	5.8	7.3	41	0.71	0.076	16
STD DS8	Standard	14.1	112.4	127.0	305	1.9	38.4	7.5	610	2.48	26.9	113.4	6.7	69	2.4	5.3	6.2	44	0.72	0.080	15
STD DS8	Standard	13.7	110.3	128.5	299	1.8	38.1	7.3	608	2.41	25.8	100.3	6.7	64	2.5	5.3	6.3	42	0.68	0.079	15
STD DS8	Standard	13.3	112.2	123.3	317	1.8	38.9	7.7	608	2.49	27.1	112.3	6.6	72	2.2	5.5	6.6	42	0.68	0.080	15
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

QUALITY CONTROL REPORT WHI11000621.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
STD DS8	Standard	115	0.58	274	0.113	2	0.86	0.088	0.40	2.8	0.17	1.9	5.1	0.16	5	5.1	5.0				
STD DS8	Standard	116	0.62	268	0.116	1	0.87	0.086	0.41	2.9	0.20	2.2	5.3	0.14	4	5.8	4.4				
STD DS8	Standard	114	0.56	275	0.109	2	0.88	0.084	0.39	3.0	0.22	2.0	5.2	0.13	5	5.3	5.0				
STD DS8	Standard	118	0.54	286	0.120	4	0.94	0.103	0.42	2.9	0.20	2.4	5.5	0.17	5	4.4	5.2				
STD DS8	Standard	118	0.55	292	0.121	3	0.94	0.101	0.43	2.8	0.22	2.5	5.5	0.15	5	4.8	5.1				
STD DS8	Standard	115	0.63	285	0.119	3	0.95	0.109	0.43	3.0	0.23	3.0	5.4	0.15	5	5.6	4.8				
STD DS8	Standard	107	0.61	279	0.117	2	0.95	0.104	0.44	2.8	0.20	2.7	5.3	0.12	5	4.8	5.1				
STD DS8	Standard	117	0.63	291	0.122	2	0.92	0.099	0.42	2.9	0.20	2.3	5.4	0.14	5	5.1	5.0				
STD DS8	Standard	114	0.60	278	0.114	2	0.91	0.093	0.41	3.0	0.20	2.2	5.3	0.15	5	5.0	4.9				
STD DS8	Standard	116	0.59	284	0.124	3	0.92	0.099	0.44	2.9	0.21	2.6	5.5	0.12	5	4.9	5.0				
STD DS8	Standard																	13.0	110.6	118.2	315
STD OREAS45CA	Standard																	0.9	474.9	19.7	53
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

QUALITY CONTROL REPORT WHI11000621.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.8	37.9	7.2	591	2.42	24.9	120.0	5.9	60	2.1	5.0	5.3	40	0.61	0.078	12	110	0.58	266	0.100
STD OREAS45CA	Standard	0.2	228.3	84.9	866	15.22	3.3	41.2	7.0	14	<0.1	0.1	0.2	201	0.41	0.035	15	667	0.14	151	0.119
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 22, 2011

QUALITY CONTROL REPORT WHI11000621.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.83	0.073	0.40	2.7	0.23	2.0	5.0	0.15	4	4.5	4.8
STD OREAS45CA	Standard	<20	3.26	0.012	0.06	<0.1	0.03	34.9	<0.1	<0.05	17	0.7	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 15, 2011
Report Date: August 23, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11000627.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #2
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	319	Dry at 60C			WHI
SS80	319	Dry at 60C sieve 100g to -80 mesh			WHI
1DX3	281	1:1:1 Aqua Regia digestion ICP-MS analysis	30	Completed	VAN
1DX1	33	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090135	Soil	12.8	40.5	12.1	366	0.4	64.4	9.7	265	2.23	34.9	9.1	3.1	33	1.9	4.7	0.2	84	0.33	0.097	15
1090182	Soil	66.3	80.2	11.6	651	1.0	152.9	5.2	186	1.29	71.1	4.2	0.8	58	10.4	19.8	0.1	781	1.06	0.109	15
1090221	Soil	2.2	55.3	10.8	131	1.1	38.9	5.9	277	2.05	19.4	8.3	1.1	82	0.6	1.7	0.2	31	0.71	0.083	4
1090222	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090224	Soil	3.4	74.4	15.6	109	0.6	29.1	6.3	94	2.06	17.7	33.1	1.1	84	0.4	2.7	0.2	49	0.53	0.059	4
1090245	Soil	13.4	7.3	34.5	12	0.9	2.6	0.3	12	0.52	23.6	15.6	1.4	15	<0.1	7.1	0.3	34	0.01	0.024	5
1090246	Soil	12.6	6.1	38.0	14	0.6	3.2	0.3	9	0.53	31.5	17.5	1.9	15	0.1	8.8	0.3	24	0.01	0.019	6
1090264	Soil	24.1	66.1	26.8	630	1.8	116.1	11.6	308	4.05	32.0	3.4	2.3	24	7.7	13.7	0.1	97	0.65	0.111	13
1090261	Soil	43.0	53.2	7.6	216	0.3	107.5	5.7	107	1.42	28.0	1.1	0.7	43	2.2	4.3	<0.1	71	0.94	0.109	11
1090275	Soil	4.4	14.0	3.1	24	<0.1	16.7	1.5	69	0.39	1.9	1.8	0.1	47	0.6	0.5	<0.1	12	1.33	0.059	3
1090276	Soil	9.9	25.8	5.3	159	0.2	35.6	3.2	105	0.75	8.4	2.2	0.3	52	1.2	2.9	<0.1	36	1.40	0.068	5
1090277	Soil	3.7	9.8	2.4	36	<0.1	11.9	1.7	78	0.41	4.3	2.5	0.1	28	0.6	0.6	<0.1	16	0.63	0.072	3
1090278	Soil	35.3	37.2	12.3	474	0.2	60.6	6.8	154	2.02	29.4	2.5	1.7	15	3.9	9.8	<0.1	127	0.19	0.097	13
1090279	Soil	39.4	64.2	13.8	519	0.7	109.5	7.8	202	2.07	83.0	12.7	2.1	56	6.4	10.5	0.1	178	1.13	0.135	13
1090280	Soil	14.8	20.8	8.4	131	<0.1	28.5	4.9	36	1.48	79.3	4.0	1.3	6	0.1	4.5	0.2	94	0.02	0.026	16
1090281	Soil	13.7	75.8	19.0	301	0.7	81.3	16.5	335	3.59	179.8	9.8	3.6	34	1.1	7.3	0.3	69	0.17	0.163	16
1090282	Soil	17.9	60.0	22.6	290	1.0	68.6	10.5	132	3.23	154.7	7.7	0.9	49	0.7	8.6	0.3	83	0.18	0.176	14
1090283	Soil	14.5	34.2	8.7	3052	0.3	337.4	4.2	81	1.14	26.8	11.1	0.6	161	35.4	5.2	0.2	33	7.34	0.078	5
1090284	Soil	14.7	61.7	21.2	299	0.3	53.9	8.5	173	3.07	101.0	16.5	3.2	32	1.2	9.7	0.3	122	0.12	0.091	14
1090286	Soil	1.3	16.3	5.9	41	0.2	18.4	1.0	16	0.50	3.3	5.8	0.2	25	0.7	4.4	<0.1	18	0.22	0.072	2
1090287	Soil	5.5	12.1	7.2	42	0.5	15.3	1.4	12	0.40	8.6	5.5	0.1	20	0.5	3.5	<0.1	35	0.07	0.042	5
1090288	Soil	6.2	17.3	10.7	49	0.7	15.1	1.4	12	0.49	11.9	10.5	0.5	28	0.7	5.2	<0.1	46	0.08	0.047	7
1090289	Soil	1.4	14.9	1.4	13	0.9	5.2	2.1	14	0.32	1.8	2.7	<0.1	8	0.3	0.8	<0.1	13	0.03	0.042	1
1090290	Soil	20.8	149.7	21.1	333	2.0	75.1	21.5	841	4.44	160.0	16.5	2.0	44	6.2	15.0	0.2	148	0.10	0.129	9
1090291	Soil	8.7	71.0	15.3	333	0.9	61.2	11.4	173	2.54	157.0	11.2	1.9	32	2.8	9.1	0.2	58	0.10	0.077	10
1090292	Soil	4.6	79.9	13.3	392	1.6	92.4	49.1	3440	3.03	299.4	12.6	1.3	31	10.6	6.8	0.2	52	0.17	0.091	6
1090293	Soil	9.7	54.5	16.9	342	0.7	64.0	43.2	2380	2.67	260.8	6.3	1.3	28	5.3	9.7	0.2	62	0.10	0.072	7
1090294	Soil	14.0	53.5	16.2	1210	0.8	170.2	65.9	2186	9.28	384.9	10.2	2.2	44	3.9	12.7	0.2	66	0.27	0.077	8
1090295	Soil	11.8	54.6	14.7	1537	1.0	185.6	127.0	2802	8.84	135.8	12.0	1.8	34	15.2	8.8	0.3	70	0.28	0.092	7
1090301	Soil	6.9	17.8	6.7	75	0.4	18.4	3.0	41	1.03	29.3	3.3	0.3	8	0.2	3.1	0.1	63	0.02	0.049	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

		Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090135	Soil		23	0.32	445	0.019	3	0.83	0.006	0.06	0.2	0.81	2.5	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090182	Soil		42	0.20	782	0.011	9	0.66	0.011	0.10	0.4	1.04	2.2	2.5	0.07	3	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090221	Soil		23	0.28	457	0.002	3	0.95	0.010	0.05	<0.1	1.14	2.3	0.1	0.08	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090222	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090224	Soil		30	0.31	714	0.001	3	0.97	0.008	0.05	0.1	0.84	1.8	0.2	0.07	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090245	Soil		7	0.01	349	0.001	3	0.24	0.003	0.08	<0.1	1.50	0.5	0.4	0.07	1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090246	Soil		6	0.01	504	0.001	3	0.18	0.002	0.08	<0.1	4.31	0.5	0.3	0.08	<1	5.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090264	Soil		16	0.22	219	0.003	4	0.24	0.007	0.05	<0.1	0.58	4.6	0.2	<0.05	<1	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090261	Soil		16	0.13	379	0.005	4	0.50	0.016	0.06	0.2	0.30	2.2	1.2	0.07	1	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090275	Soil		6	0.09	133	0.014	4	0.32	0.035	0.02	<0.1	0.09	0.4	<0.1	0.07	<1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090276	Soil		8	0.09	232	0.009	5	0.38	0.027	0.04	<0.1	0.17	0.9	0.1	0.09	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090277	Soil		4	0.06	125	0.013	1	0.31	0.029	0.02	<0.1	0.08	0.3	<0.1	0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090278	Soil		11	0.03	253	0.002	2	0.27	0.003	0.05	<0.1	0.16	2.2	0.2	<0.05	<1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090279	Soil		18	0.38	419	0.003	5	0.36	0.005	0.09	0.2	3.94	3.2	1.2	0.06	1	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090280	Soil		7	0.03	112	0.005	3	0.40	0.003	0.05	0.1	0.07	0.9	0.3	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090281	Soil		19	0.18	718	0.007	3	1.00	0.004	0.08	0.2	0.74	3.3	0.3	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090282	Soil		15	0.09	905	0.004	4	0.66	0.003	0.09	0.1	0.40	1.5	0.5	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090283	Soil		14	0.25	393	0.007	6	0.45	0.016	0.04	0.1	1.23	1.8	2.4	0.22	<1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090284	Soil		23	0.21	329	0.009	2	0.96	0.005	0.06	0.3	1.91	2.1	0.4	<0.05	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090286	Soil		9	0.02	357	0.013	3	0.28	0.021	0.03	<0.1	0.75	1.0	<0.1	0.13	<1	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090287	Soil		9	0.02	189	0.005	1	0.16	0.013	0.03	<0.1	1.04	0.7	0.2	<0.05	<1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090288	Soil		7	0.02	258	0.004	1	0.21	0.009	0.03	0.2	1.73	0.9	0.5	<0.05	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090289	Soil		4	0.01	47	0.006	<1	0.15	0.022	0.02	<0.1	0.51	0.4	0.1	<0.05	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090290	Soil		20	0.07	427	0.004	4	0.84	0.006	0.08	0.4	3.19	3.6	0.7	0.11	2	6.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090291	Soil		19	0.12	638	0.001	2	0.73	0.003	0.06	0.2	1.66	2.6	0.5	<0.05	2	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090292	Soil		21	0.11	536	0.001	4	1.19	0.012	0.10	0.1	1.59	3.1	0.4	0.05	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090293	Soil		16	0.06	589	0.004	3	0.58	0.006	0.06	0.2	0.87	1.7	0.4	0.06	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090294	Soil		18	0.12	611	<0.001	2	0.68	0.004	0.07	0.2	1.80	3.0	0.4	<0.05	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090295	Soil		15	0.09	353	0.002	2	0.75	0.007	0.06	0.2	1.69	2.6	0.6	0.05	2	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090301	Soil		10	0.02	103	0.004	2	0.28	0.008	0.03	0.1	0.13	0.6	0.1	0.08	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090222	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090224	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090245	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090275	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090276	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090277	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090278	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090279	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090280	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090281	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090282	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090283	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090284	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090286	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090287	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090288	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090289	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090290	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090291	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090292	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090293	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090294	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090295	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090301	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090222	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090224	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090245	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090275	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090276	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090277	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090278	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090279	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090280	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090281	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090282	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090283	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090284	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090286	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090287	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090288	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090289	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090290	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090291	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090292	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090293	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090294	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090295	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090301	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090302	Soil	7.2	22.9	15.2	130	0.3	33.0	5.3	78	2.08	61.2	17.4	1.2	21	0.7	4.6	0.2	77	0.04	0.073	8
1090303	Soil	4.1	26.7	9.3	64	1.2	19.1	2.7	63	0.99	18.7	8.6	0.4	28	1.2	1.5	<0.1	36	0.33	0.082	7
1090304	Soil	13.3	27.3	20.0	133	0.3	40.2	5.3	82	2.37	84.4	9.1	0.8	26	0.2	5.6	0.2	97	0.02	0.088	8
1090305	Soil	2.1	11.8	4.3	45	0.2	11.6	2.3	27	0.74	12.4	<0.5	0.1	6	<0.1	0.7	<0.1	24	0.03	0.035	3
1090306	Soil	2.5	38.3	12.3	73	1.5	22.4	3.0	58	1.51	11.5	8.3	0.9	52	0.2	1.2	0.2	20	0.58	0.063	3
1090307	Soil	14.5	33.9	14.3	151	0.6	45.9	6.0	114	2.45	91.3	9.5	1.1	18	0.3	6.9	0.2	84	0.02	0.096	7
1090308	Soil	17.7	40.2	18.3	209	0.7	60.6	8.0	133	2.77	133.6	22.7	0.8	31	0.8	10.1	0.2	98	0.03	0.123	8
1090309	Soil	1.4	38.0	8.8	56	0.8	15.9	2.8	55	1.20	9.5	7.1	0.5	62	0.3	1.1	0.2	17	0.41	0.055	2
1090311	Soil	3.7	46.9	9.6	175	0.4	46.7	7.7	50	2.19	19.4	2.6	0.3	13	0.5	2.0	0.2	52	0.02	0.078	3
1090312	Soil	2.3	22.7	4.9	65	0.3	15.5	2.7	55	1.06	13.2	2.5	<0.1	5	0.2	1.5	0.1	37	0.03	0.047	3
1090313	Soil	2.9	65.9	7.8	140	0.2	51.3	6.4	51	2.26	9.7	2.3	0.4	13	0.5	0.9	0.1	41	0.02	0.049	3
1090314	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090315	Soil	4.5	18.7	10.3	102	0.4	24.0	4.7	62	1.70	28.2	3.2	1.0	10	0.2	2.9	0.2	60	0.01	0.033	6
1090316	Soil	6.3	60.8	20.9	136	2.1	29.3	7.5	121	3.05	65.6	11.2	1.3	43	0.7	4.2	0.3	31	0.05	0.065	3
1090317	Soil	4.6	45.0	28.6	140	2.4	15.9	7.5	143	3.94	393.9	11.7	1.3	89	0.3	7.4	0.3	40	0.02	0.141	2
1090318	Soil	9.9	80.7	34.9	290	1.3	31.6	5.0	44	6.72	373.8	22.8	3.7	249	0.6	13.5	0.4	50	0.03	0.276	11
1090319	Soil	10.2	14.2	17.4	83	0.5	11.2	2.9	38	1.39	35.2	2.8	0.4	26	0.1	7.1	0.3	89	0.01	0.041	7
1090320	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090321	Soil	10.2	13.3	8.3	64	0.8	9.7	3.5	44	1.38	21.2	1.5	<0.1	10	0.1	2.8	0.1	49	<0.01	0.045	5
1090322	Soil	4.8	24.9	15.9	102	0.4	22.1	6.3	74	2.65	52.7	4.7	0.4	12	0.2	2.6	0.2	42	<0.01	0.072	4
1090323	Soil	9.3	20.0	56.2	17	1.2	3.9	0.8	20	0.97	46.7	16.1	0.4	61	0.1	11.1	0.2	75	0.01	0.054	4
1090324	Soil	11.0	20.0	32.0	57	0.8	11.2	2.6	69	1.55	43.2	43.2	0.2	56	<0.1	8.9	0.3	76	0.02	0.078	5
1090325	Soil	23.4	25.4	130.1	28	0.6	4.0	0.8	14	1.39	89.1	89.0	0.7	219	0.1	45.5	0.3	197	0.03	0.130	9
1090326	Soil	27.5	32.9	68.5	53	1.8	9.7	2.5	76	1.67	92.7	43.7	0.8	106	0.2	27.1	0.4	110	0.03	0.102	7
1090327	Soil	13.9	29.8	46.4	59	1.6	11.8	3.3	134	2.08	49.8	37.8	0.4	92	0.2	10.1	0.4	62	0.03	0.101	5
1090328	Soil	6.7	21.2	21.7	24	0.8	5.1	1.3	34	0.82	18.8	27.9	<0.1	40	0.1	5.3	0.2	41	0.02	0.059	3
1090329	Soil	9.9	28.3	31.0	46	0.8	11.3	2.5	63	1.28	26.4	17.6	0.3	65	0.2	7.5	0.2	71	0.03	0.082	6
1090330	Soil	6.0	28.6	18.3	103	0.5	19.8	6.0	148	1.71	24.9	8.0	0.6	32	0.3	4.0	0.3	45	0.02	0.069	4
1090331	Soil	10.4	28.1	37.9	83	1.1	17.3	4.8	105	2.18	34.8	19.9	0.2	78	0.2	6.9	0.3	55	0.03	0.086	4
1090332	Soil	22.8	41.2	31.4	48	2.8	13.8	4.0	156	1.74	46.6	12.4	1.1	95	0.6	29.1	0.3	104	0.02	0.087	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090302	Soil	17	0.05	253	0.004	7	0.60	0.007	0.05	0.1	0.94	1.7	0.2	0.09	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090303	Soil	13	0.04	1560	0.006	3	0.64	0.017	0.05	<0.1	0.90	1.6	0.2	0.12	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090304	Soil	15	0.03	271	0.003	2	0.50	0.004	0.06	0.1	0.29	1.1	0.4	<0.05	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090305	Soil	6	0.01	104	0.003	2	0.22	0.007	0.03	<0.1	0.03	0.4	<0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090306	Soil	17	0.04	839	0.001	1	0.71	0.009	0.06	<0.1	0.41	2.2	<0.1	0.07	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090307	Soil	14	0.03	794	0.004	3	0.37	0.006	0.05	0.2	0.67	1.5	0.4	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090308	Soil	16	0.03	604	0.002	3	0.43	0.004	0.06	0.2	3.37	1.3	0.5	0.08	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090309	Soil	10	0.03	601	0.003	4	0.47	0.013	0.06	<0.1	0.24	1.6	<0.1	0.07	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090311	Soil	13	0.02	159	0.002	4	0.40	0.005	0.04	<0.1	0.13	1.1	<0.1	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090312	Soil	10	0.02	120	0.006	5	0.21	0.007	0.04	<0.1	0.08	0.6	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090313	Soil	12	0.01	160	0.002	4	0.35	0.004	0.03	<0.1	0.05	1.7	<0.1	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090314	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090315	Soil	10	0.02	138	0.003	3	0.38	0.004	0.03	0.1	0.54	1.2	<0.1	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090316	Soil	20	0.04	659	<0.001	2	0.42	0.004	0.07	<0.1	11.38	3.2	0.2	0.11	2	10.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090317	Soil	16	0.04	257	0.002	2	0.62	0.006	0.06	<0.1	0.46	1.6	0.1	0.09	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090318	Soil	18	0.02	374	0.003	3	0.58	0.005	0.08	<0.1	0.36	3.5	0.2	0.12	2	3.9	0.3	N.A.	N.A.	N.A.	N.A.
1090319	Soil	8	0.01	245	0.003	2	0.26	0.003	0.03	0.1	0.10	0.7	0.1	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090320	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.5	4.2	3.7	30
1090321	Soil	7	0.01	99	0.002	2	0.23	0.005	0.03	0.2	0.09	0.3	0.1	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090322	Soil	8	0.02	160	0.003	2	0.48	0.006	0.04	<0.1	0.30	1.3	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090323	Soil	11	0.02	738	0.002	3	0.26	0.003	0.09	0.1	3.80	1.0	1.2	0.14	2	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090324	Soil	13	0.02	540	0.003	2	0.38	0.003	0.07	0.1	1.22	0.6	0.6	0.08	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090325	Soil	18	<0.01	1386	0.003	2	0.33	0.003	0.06	0.4	0.89	1.2	0.7	0.05	3	9.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090326	Soil	15	0.02	836	0.002	2	0.33	0.003	0.11	0.2	4.02	1.7	1.6	0.20	3	12.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090327	Soil	17	0.05	829	0.004	2	0.52	0.005	0.13	0.1	3.14	1.5	0.9	0.23	3	5.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090328	Soil	9	0.02	933	0.004	1	0.39	0.010	0.05	<0.1	0.99	0.4	0.5	0.07	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090329	Soil	13	0.03	645	0.003	2	0.47	0.004	0.06	0.1	0.54	0.8	0.5	0.07	2	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090330	Soil	11	0.02	337	0.004	3	0.24	0.003	0.06	0.1	0.26	1.5	0.2	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090331	Soil	13	0.04	611	0.003	2	0.32	0.004	0.10	0.1	0.40	0.9	0.4	0.18	2	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090332	Soil	18	0.03	1076	0.003	3	0.40	0.003	0.13	0.2	1.22	2.5	1.0	0.24	2	7.8	0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090302	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090303	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090304	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090305	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090306	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090307	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090308	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090309	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090311	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090314	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090320	Soil	0.1	4.5	0.7	15	0.49	7.9	2.0	0.1	5	<0.1	2.2	0.1	30	0.02	0.025	1	4	<0.01	164	0.001
1090321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090323	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090326	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090327	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090328	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090329	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090330	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090331	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090332	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090302	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090303	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090304	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090305	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090306	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090307	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090308	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090309	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090311	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090314	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1090315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090320	Soil	<20	0.23	0.003	0.03	<0.1	0.08	0.6	<0.1	<0.05	2	<0.5	<0.2
1090321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090323	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090326	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090327	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090328	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090329	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090330	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090331	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090332	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090333	Soil	73.1	42.2	85.4	35	4.3	6.6	0.3	9	3.00	240.0	6.7	6.0	427	0.6	63.7	0.4	359	0.11	0.459	9
1090334	Soil	10.1	28.5	39.8	87	1.3	17.7	4.5	90	2.20	55.6	23.4	1.1	74	0.2	9.9	0.3	54	0.03	0.071	5
1090335	Soil	15.9	27.8	58.3	80	1.9	17.0	4.7	139	2.89	74.2	41.7	0.8	125	0.2	13.3	0.4	81	0.04	0.109	6
1090336	Soil	9.1	19.5	46.4	47	1.2	8.9	2.2	72	1.94	52.6	33.3	0.6	96	0.1	9.1	0.2	71	0.03	0.081	3
1090337	Soil	8.3	17.1	56.7	64	1.3	9.5	2.0	55	1.66	48.7	23.9	0.9	73	<0.1	7.6	0.4	54	0.01	0.067	3
1090338	Soil	7.4	24.3	44.1	106	1.7	17.5	4.4	134	2.15	35.7	8.6	1.0	35	0.1	5.7	0.4	37	0.02	0.059	3
1090339	Soil	7.0	99.7	26.1	360	0.6	84.0	26.6	438	5.37	90.8	3.3	0.7	41	1.0	5.3	0.5	50	0.01	0.109	5
1090340	Soil	7.7	50.0	18.7	182	0.2	43.0	14.9	302	3.11	32.4	2.4	0.7	15	0.3	3.7	0.4	64	0.01	0.063	8
1090341	Soil	8.1	55.9	23.9	185	0.3	44.2	16.6	293	3.48	33.7	1.6	0.5	20	0.2	4.1	0.5	52	0.01	0.075	8
1090342	Soil	8.0	32.2	21.9	133	0.4	22.2	7.3	281	2.04	19.5	1.4	0.8	11	0.4	2.9	0.3	41	<0.01	0.043	7
1090343	Soil	11.4	19.7	30.4	57	0.9	6.4	1.4	40	0.87	18.6	4.2	1.5	26	0.1	6.5	0.3	22	<0.01	0.027	2
1090344	Soil	28.2	64.5	86.9	207	2.5	25.6	5.5	73	6.52	83.9	3.4	3.2	257	0.6	15.2	0.6	75	0.02	0.154	6
1090345	Soil	6.9	24.8	25.3	55	1.1	12.7	3.3	123	1.66	35.2	2.4	0.2	40	0.1	3.2	0.4	41	0.02	0.082	4
1090346	Soil	5.6	7.5	7.9	30	1.5	4.8	1.3	80	0.70	10.6	2.4	0.1	4	<0.1	2.1	0.1	32	0.02	0.030	4
1090347	Soil	16.1	7.5	7.4	26	1.0	4.9	1.0	52	0.53	11.1	2.7	0.3	7	0.1	3.0	0.1	51	0.02	0.040	5
1090348	Soil	9.7	15.0	23.2	39	2.6	7.4	1.6	34	0.90	16.3	7.8	0.6	19	0.2	2.8	0.2	27	0.02	0.055	3
1090349	Soil	32.5	24.2	14.5	95	0.9	27.0	1.9	44	0.89	40.5	18.5	0.2	14	1.1	12.6	0.1	116	0.02	0.058	8
1090350	Soil	73.6	41.7	11.8	345	0.3	56.6	3.9	56	2.07	80.2	13.0	0.2	7	0.4	37.3	0.2	416	<0.01	0.051	13
1090351	Soil	9.0	44.0	21.2	124	2.3	46.4	11.7	488	3.13	123.4	122.2	0.3	22	0.7	30.1	0.2	12	0.06	0.065	10
1090352	Soil	1.4	54.3	12.8	102	0.1	48.5	16.7	266	5.40	83.8	2.5	3.9	4	<0.1	6.9	0.4	10	0.01	0.050	13
1090353	Soil	7.5	77.4	16.2	325	0.3	77.0	23.8	354	7.12	504.9	3.3	2.7	14	0.1	8.4	<0.1	17	0.02	0.100	40
1090354	Soil	8.3	35.5	41.0	170	0.6	34.2	10.6	60	2.80	72.5	2.4	1.2	84	0.2	9.3	0.5	45	0.02	0.136	30
1090355	Soil	18.7	118.7	45.5	304	0.4	39.4	7.3	106	3.44	62.5	3.0	<0.1	105	0.5	5.7	0.5	166	0.03	0.226	13
1090356	Soil	14.5	38.5	13.3	166	0.1	47.0	7.6	83	2.44	125.7	1.6	0.4	7	0.3	4.6	0.3	54	0.01	0.094	12
1090357	Soil	8.0	25.9	9.5	855	0.3	87.9	5.0	122	1.39	64.9	4.1	0.6	28	10.7	3.8	<0.1	42	0.32	0.081	8
1090358	Soil	25.7	66.1	26.3	282	1.4	86.2	13.5	332	4.62	196.1	5.1	0.6	28	0.8	8.0	0.3	111	0.07	0.266	20
1090359	Soil	29.6	78.4	31.3	421	0.8	113.9	11.9	328	2.46	67.8	6.5	1.9	82	3.1	9.9	0.2	74	0.89	0.255	14
1090360	Soil	23.7	29.1	15.5	124	1.5	34.9	1.7	40	0.81	35.6	21.1	0.4	29	1.4	10.9	0.1	81	0.28	0.081	8
1090361	Soil	33.1	25.9	19.3	143	0.4	38.1	4.0	53	1.65	59.3	5.9	<0.1	23	0.2	9.5	0.3	154	0.01	0.047	9
1090362	Soil	67.5	56.1	46.6	289	2.5	68.5	5.3	59	3.67	121.2	10.1	0.8	81	0.6	27.4	0.4	367	0.02	0.186	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090333	Soil	85	<0.01	293	0.003	6	0.53	0.004	0.24	0.6	5.15	28.7	2.6	0.52	11	42.2	0.6	N.A.	N.A.	N.A.	N.A.
1090334	Soil	13	0.06	608	0.005	2	0.32	0.004	0.13	<0.1	0.54	2.9	0.5	0.19	2	9.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090335	Soil	19	0.09	770	0.009	3	0.55	0.008	0.19	0.2	0.68	2.2	0.8	0.33	3	19.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090336	Soil	15	0.04	748	0.007	2	0.47	0.009	0.11	0.1	0.69	1.6	0.3	0.18	3	6.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090337	Soil	13	0.03	415	0.002	2	0.36	0.004	0.12	<0.1	0.30	3.0	0.4	0.16	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090338	Soil	11	0.02	176	0.002	2	0.34	0.003	0.08	<0.1	0.37	2.5	0.3	<0.05	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090339	Soil	15	0.03	215	0.003	2	0.49	0.003	0.06	<0.1	0.14	5.2	0.3	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090340	Soil	13	0.03	96	0.005	2	0.43	0.003	0.06	0.1	0.35	2.3	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090341	Soil	12	0.03	120	0.004	2	0.36	0.003	0.06	0.1	0.10	2.1	0.2	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090342	Soil	8	0.02	88	0.003	1	0.52	0.006	0.05	0.1	0.06	1.4	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090343	Soil	5	<0.01	94	<0.001	2	0.20	0.002	0.08	<0.1	0.76	1.6	0.4	<0.05	1	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090344	Soil	13	0.01	104	0.004	2	0.29	0.007	0.49	<0.1	0.25	2.6	1.9	1.24	3	9.2	0.2	N.A.	N.A.	N.A.	N.A.
1090345	Soil	5	0.01	107	0.002	2	0.16	0.004	0.08	<0.1	0.17	0.6	0.4	0.14	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090346	Soil	3	0.01	55	0.003	2	0.19	0.004	0.04	<0.1	0.20	0.2	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090347	Soil	6	0.01	77	0.008	3	0.18	0.003	0.06	0.1	0.16	0.5	0.5	<0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090348	Soil	5	0.01	91	0.003	5	0.23	0.006	0.06	<0.1	1.58	1.1	0.5	0.08	1	1.8	0.2	N.A.	N.A.	N.A.	N.A.
1090349	Soil	11	0.02	212	0.002	2	0.23	0.003	0.05	0.2	4.59	0.6	0.6	0.06	1	4.3	0.2	N.A.	N.A.	N.A.	N.A.
1090350	Soil	16	0.02	98	0.002	1	0.34	0.002	0.04	0.4	0.61	0.4	0.9	<0.05	2	5.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090351	Soil	5	0.03	853	0.003	2	0.40	0.010	0.05	<0.1	12.84	1.3	0.5	0.05	2	3.9	0.3	N.A.	N.A.	N.A.	N.A.
1090352	Soil	6	0.04	625	0.001	1	0.41	0.002	0.07	<0.1	0.07	3.2	0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090353	Soil	7	0.05	213	0.010	<1	0.49	0.009	0.18	<0.1	0.20	3.9	<0.1	0.33	1	3.2	0.6	N.A.	N.A.	N.A.	N.A.
1090354	Soil	6	0.02	720	0.003	1	0.31	0.004	0.15	<0.1	0.12	1.1	0.4	0.32	1	8.9	0.3	N.A.	N.A.	N.A.	N.A.
1090355	Soil	12	0.03	309	0.002	2	0.52	0.006	0.12	<0.1	0.32	0.2	0.4	0.24	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090356	Soil	9	0.04	210	0.002	<1	0.54	0.002	0.05	<0.1	0.35	0.6	0.3	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090357	Soil	9	0.08	369	0.003	1	0.24	0.003	0.04	<0.1	0.64	1.4	0.5	0.09	<1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090358	Soil	22	0.08	517	0.005	3	0.98	0.013	0.09	0.2	1.17	1.0	0.6	0.14	4	2.7	0.2	N.A.	N.A.	N.A.	N.A.
1090359	Soil	12	0.19	517	0.003	4	0.32	0.003	0.10	0.2	1.92	2.8	0.8	0.14	<1	2.7	0.2	N.A.	N.A.	N.A.	N.A.
1090360	Soil	10	0.05	255	0.002	2	0.24	0.002	0.05	0.2	5.59	1.0	0.6	0.09	1	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090361	Soil	10	0.02	119	0.003	1	0.28	0.003	0.07	0.2	2.43	0.3	0.9	0.11	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090362	Soil	26	0.03	433	0.003	3	0.36	0.005	0.13	0.5	1.80	1.1	2.7	0.29	4	10.3	0.4	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090333	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090334	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090335	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090336	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090338	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090340	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090341	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090342	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090343	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090344	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090345	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090346	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090347	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090348	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090349	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090350	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090351	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090352	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090353	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090354	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090355	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090356	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090357	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090358	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090359	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090360	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090361	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090362	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090333	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090334	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090335	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090336	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090338	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090340	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090341	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090342	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090343	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090344	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090345	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090346	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090347	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090348	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090349	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090350	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090351	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090352	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090353	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090354	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090355	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090356	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090357	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090358	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090359	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090360	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090361	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090362	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090363	Soil	14.8	11.0	15.2	81	0.3	13.5	1.7	22	0.79	23.7	2.8	<0.1	11	0.1	3.3	0.1	101	<0.01	0.041	11
1090364	Soil	6.7	15.7	5.6	70	0.4	9.8	2.2	25	1.05	18.6	2.0	<0.1	3	<0.1	2.4	0.1	44	<0.01	0.036	6
1090365	Soil	15.1	50.4	17.8	146	0.6	35.9	5.9	92	2.43	75.7	2.3	0.9	11	0.2	4.7	0.3	78	<0.01	0.051	12
1090366	Soil	6.8	74.2	16.3	281	0.2	33.1	8.7	186	3.02	28.7	3.8	1.0	10	0.6	3.5	0.4	26	<0.01	0.057	2
1090367	Soil	2.4	17.9	4.3	89	0.3	16.7	5.3	79	1.26	15.7	<0.5	<0.1	4	0.1	1.0	<0.1	22	0.01	0.031	2
1090368	Soil	9.9	40.3	22.3	183	0.5	39.1	12.3	349	2.81	56.1	5.6	0.7	18	0.7	4.1	0.3	42	0.01	0.061	5
1090369	Soil	5.4	33.0	6.5	165	0.3	38.4	12.4	142	2.63	34.1	<0.5	0.4	4	0.2	2.3	0.2	45	<0.01	0.046	4
1090370	Soil	4.0	35.8	10.5	110	0.3	22.0	9.5	295	2.69	24.8	15.8	<0.1	64	0.2	2.8	0.2	48	0.02	0.092	3
1090371	Soil	1.8	18.0	5.0	45	0.2	10.1	4.0	149	1.06	10.0	1.0	<0.1	6	0.1	0.9	0.1	29	0.02	0.082	2
1090372	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090373	Soil	7.8	28.3	17.8	60	0.5	15.3	3.6	53	1.22	38.5	8.9	1.0	33	<0.1	5.1	0.2	50	0.01	0.031	1
1090374	Soil	2.0	4.5	6.0	13	1.3	2.5	0.7	16	0.30	5.5	10.3	<0.1	16	<0.1	1.2	<0.1	23	0.02	0.036	1
1090375	Soil	16.1	18.8	25.0	24	1.2	4.3	0.5	9	1.13	40.9	13.1	0.1	17	<0.1	9.0	<0.1	91	0.01	0.039	3
1090376	Soil	6.4	24.9	32.4	7	0.8	2.8	0.1	3	0.57	14.3	8.8	0.9	49	<0.1	4.8	0.1	44	0.01	0.031	1
1090377	Soil	7.4	13.2	28.8	21	0.7	3.8	0.5	10	0.70	24.7	3.6	1.0	64	<0.1	4.2	0.3	30	0.01	0.041	2
1090378	Soil	3.3	13.5	21.1	8	1.1	3.6	0.3	5	0.26	11.5	31.5	0.9	33	<0.1	13.9	0.2	35	0.01	0.016	3
1090379	Soil	18.5	34.1	21.1	23	1.7	6.4	0.6	21	1.23	46.8	12.1	0.6	118	0.3	20.5	0.2	125	0.02	0.111	5
1090380	Soil	22.0	9.2	76.9	32	1.8	5.9	1.1	25	1.19	25.5	0.9	0.2	20	<0.1	11.0	0.1	113	0.02	0.051	5
1090381	Soil	24.2	15.5	14.1	12	1.5	3.7	0.3	7	1.02	31.9	51.2	0.2	62	0.1	20.8	0.2	89	0.02	0.066	2
1090382	Soil	16.1	9.5	16.0	21	0.9	4.3	0.7	15	0.80	24.5	71.6	0.4	67	<0.1	13.9	0.2	80	0.02	0.066	3
1090383	Soil	11.4	18.7	17.7	63	0.5	21.0	2.9	40	1.36	48.7	10.3	0.2	36	0.3	6.1	0.2	74	0.01	0.075	6
1090384	Soil	4.0	3.8	9.8	12	0.6	2.1	0.4	7	0.23	4.3	3.8	<0.1	32	<0.1	3.5	0.1	44	0.01	0.043	3
1090385	Soil	12.5	34.0	24.2	127	0.8	22.5	5.3	72	2.11	47.6	22.4	0.3	63	0.4	7.6	0.3	72	0.02	0.105	4
1090386	Soil	5.7	23.9	19.3	86	0.7	23.6	4.1	153	2.38	27.8	11.6	0.7	37	0.2	3.5	0.2	48	0.05	0.084	3
1090387	Soil	13.0	25.9	21.0	77	0.9	17.4	3.5	57	1.91	36.1	25.5	0.7	78	0.2	14.1	0.2	98	0.02	0.095	5
1090388	Soil	9.8	29.8	27.3	143	1.0	30.9	4.9	111	3.08	48.3	20.6	0.9	72	0.3	7.8	0.3	67	0.21	0.110	4
1090389	Soil	6.4	26.0	26.2	188	2.2	64.7	5.4	267	2.17	25.9	38.4	0.2	65	1.6	5.4	0.3	54	0.28	0.147	4
1090390	Soil	8.2	36.2	16.5	165	0.6	35.5	4.2	73	1.81	25.2	6.9	1.6	51	0.7	3.8	0.3	63	0.16	0.092	10
1090391	Soil	10.2	36.5	27.7	256	0.9	41.9	17.8	755	5.05	64.7	24.1	0.8	60	0.8	9.2	0.3	78	0.03	0.180	5
1090392	Soil	10.9	31.4	23.7	193	1.3	34.3	22.7	762	5.36	76.0	25.1	0.7	56	0.6	10.3	0.3	67	0.04	0.206	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090363	Soil	8	0.01	101	0.003	1	0.28	0.005	0.05	0.1	0.25	0.2	0.7	0.06	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090364	Soil	5	<0.01	38	0.002	2	0.17	0.003	0.04	<0.1	0.07	0.2	0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090365	Soil	10	0.02	115	0.004	2	0.43	0.002	0.05	0.2	0.19	1.2	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090366	Soil	8	0.02	36	<0.001	1	0.20	0.002	0.04	<0.1	0.29	2.7	0.2	<0.05	<1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090367	Soil	4	0.01	22	0.005	<1	0.13	0.010	0.03	<0.1	0.04	0.5	<0.1	<0.05	<1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090368	Soil	10	0.02	151	0.002	<1	0.34	0.003	0.04	<0.1	0.35	2.1	0.3	0.06	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090369	Soil	8	0.02	55	0.004	<1	0.28	0.005	0.04	<0.1	0.07	1.5	0.1	0.05	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090370	Soil	12	0.03	93	0.006	<1	0.33	0.006	0.05	<0.1	0.14	1.4	0.1	0.09	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090371	Soil	8	0.02	36	0.006	<1	0.35	0.016	0.03	<0.1	0.05	0.4	<0.1	0.13	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090372	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.8	15.0	10.2	63
1090373	Soil	7	<0.01	249	<0.001	1	0.18	0.002	0.08	<0.1	0.32	1.8	0.2	0.12	<1	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090374	Soil	5	0.01	161	0.005	<1	0.16	0.013	0.03	<0.1	0.08	0.2	0.3	0.09	<1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090375	Soil	7	<0.01	273	0.003	<1	0.15	0.002	0.03	<0.1	0.22	0.5	0.2	0.11	<1	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090376	Soil	6	<0.01	513	<0.001	2	0.17	0.002	0.06	<0.1	1.13	1.5	0.3	0.15	<1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090377	Soil	6	<0.01	371	<0.001	2	0.18	0.002	0.08	<0.1	0.28	0.9	0.2	0.14	1	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090378	Soil	6	<0.01	421	<0.001	2	0.16	0.001	0.05	<0.1	5.89	0.7	0.5	0.09	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090379	Soil	18	<0.01	1018	0.002	5	0.28	0.002	0.10	0.2	4.00	1.7	0.9	0.19	2	8.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090380	Soil	7	0.01	196	0.004	3	0.19	0.005	0.05	0.2	0.12	0.5	0.3	<0.05	1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090381	Soil	7	<0.01	951	0.001	3	0.22	0.003	0.11	0.3	5.38	0.6	1.3	0.18	1	6.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090382	Soil	7	0.01	2399	0.003	4	0.24	0.005	0.06	0.2	2.15	0.8	1.0	0.06	2	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090383	Soil	9	0.02	609	0.003	4	0.34	0.006	0.06	0.1	0.26	0.7	0.5	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090384	Soil	6	<0.01	622	0.002	3	0.25	0.002	0.03	<0.1	0.06	0.3	0.4	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090385	Soil	11	0.03	1013	0.003	3	0.41	0.005	0.06	<0.1	0.67	1.2	0.6	0.08	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090386	Soil	11	0.12	1459	0.003	2	0.78	0.007	0.06	<0.1	0.50	3.2	0.3	0.08	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090387	Soil	12	0.02	2801	0.002	4	0.40	0.003	0.08	0.1	1.29	1.5	0.8	0.12	2	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090388	Soil	17	0.13	1908	0.001	2	0.79	0.004	0.06	0.1	6.30	2.6	0.5	0.06	3	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090389	Soil	11	0.08	1127	0.005	4	0.70	0.022	0.07	0.2	3.52	1.6	0.5	<0.05	3	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090390	Soil	13	0.09	2071	0.003	2	0.50	0.002	0.06	<0.1	1.30	3.2	0.3	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090391	Soil	16	0.04	1850	0.003	6	0.68	0.006	0.09	0.2	1.39	2.9	0.6	0.12	2	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090392	Soil	16	0.03	1944	0.003	5	0.57	0.005	0.07	0.1	2.04	1.8	0.5	0.13	2	5.0	0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090363	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090364	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090365	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090366	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090367	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090368	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090369	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090370	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090371	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090372	Soil		1.7	11.6	2.8	85	0.85	14.3	1.9	<0.1	15	0.2	2.2	0.1	45	0.06	0.047	2	5	0.01	170	0.003
1090373	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090374	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090375	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090376	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090377	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090378	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090379	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090380	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090381	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090382	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090383	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090384	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090385	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090386	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090387	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090388	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090389	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090390	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090391	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090392	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090363	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090364	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090365	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090366	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090367	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090368	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090369	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090370	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090371	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090372	Soil	<20	0.17	0.006	0.02	<0.1	0.13	0.4	<0.1	<0.05	1	0.9	<0.2
1090373	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090374	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090375	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090376	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090377	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090378	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090379	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090380	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090381	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090382	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090383	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090384	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090385	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090386	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090387	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090388	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090389	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090390	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090391	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090392	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090393	Soil	3.5	12.2	5.3	75	0.4	12.1	4.6	149	1.96	11.2	3.5	<0.1	15	0.2	1.6	0.2	32	0.04	0.075	2
1090394	Soil	16.9	46.9	16.5	259	0.5	54.3	9.0	257	3.31	58.5	8.9	0.7	32	0.9	7.2	0.2	82	0.04	0.105	9
1090395	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090396	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090397	Soil	6.1	74.5	18.7	226	1.7	52.4	10.8	210	3.04	77.6	8.2	1.3	44	1.5	5.6	0.3	29	0.07	0.063	4
1090398	Soil	7.9	38.6	17.5	149	0.9	33.3	7.3	416	2.66	54.1	12.1	0.5	38	1.2	6.8	0.2	57	0.05	0.124	4
1090399	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090400	Soil	7.2	37.0	17.4	154	0.6	40.2	6.6	124	2.97	34.8	5.3	1.0	34	0.4	4.6	0.2	45	0.03	0.083	4
1090406	Soil	10.8	33.8	36.6	131	0.5	19.4	4.4	101	2.26	22.1	2.4	1.5	77	0.3	6.9	0.3	34	0.01	0.042	2
1090410	Soil	5.9	96.9	28.2	353	0.7	73.6	25.1	1001	4.96	52.6	3.8	0.8	76	0.7	5.6	0.5	51	0.03	0.151	5
1090421	Soil	9.6	20.9	29.6	57	0.5	12.3	3.1	124	1.61	24.9	5.3	0.2	48	0.2	5.9	0.3	60	0.03	0.076	5
1090475	Soil	8.6	30.5	21.8	99	0.7	15.3	3.4	86	1.95	28.0	1.9	2.8	62	0.8	5.8	0.3	39	0.08	0.043	2
1090476	Soil	6.6	79.3	23.4	332	1.4	92.5	33.2	1761	4.92	56.5	3.1	1.6	36	1.3	5.4	0.5	47	0.06	0.122	4
1090478	Soil	8.8	12.6	33.4	190	1.3	9.4	1.7	51	1.92	117.1	7.0	0.7	27	<0.1	7.2	0.4	43	0.01	0.040	2
1090479	Soil	6.3	11.8	32.6	17	1.1	5.1	0.8	46	1.10	41.0	13.7	0.8	29	<0.1	7.9	0.4	36	0.01	0.044	2
1090480	Soil	14.2	20.2	52.7	64	1.1	13.1	2.6	68	1.76	64.2	18.7	1.6	65	0.1	13.8	0.3	66	0.03	0.074	5
1090424	Soil	11.2	18.5	25.4	68	0.4	15.8	3.8	80	1.69	30.1	6.1	0.1	57	0.1	5.9	0.2	67	0.03	0.061	6
1090425	Soil	1.3	3.7	4.3	12	<0.1	2.9	1.1	22	0.55	<0.5	<0.5	<0.1	10	<0.1	0.7	<0.1	25	0.04	0.028	2
1090427	Soil	5.0	16.5	16.9	61	0.3	14.4	3.9	79	1.65	26.9	3.0	<0.1	24	0.1	2.8	0.3	47	0.02	0.060	4
1090429	Soil	9.7	23.5	25.0	84	0.6	21.5	5.0	224	2.58	39.3	19.3	0.3	51	0.2	6.7	0.3	76	0.03	0.074	7
1090430	Soil	4.1	16.2	14.1	81	0.2	15.8	4.0	82	1.73	24.6	1.8	0.3	21	0.1	2.4	0.3	45	0.02	0.060	6
1090432	Soil	2.9	81.8	23.4	69	0.9	12.4	2.4	60	3.13	36.9	3.6	0.4	24	0.3	1.5	0.5	68	0.01	0.118	3
1090433	Soil	3.4	17.1	15.3	32	1.0	6.0	1.2	24	1.32	17.8	4.0	0.2	15	<0.1	1.4	0.3	42	0.02	0.060	3
1090435	Soil	6.8	53.4	21.8	87	2.9	19.6	3.0	58	2.95	36.1	8.5	1.0	47	0.2	2.3	0.3	44	0.01	0.080	4
1090436	Soil	4.5	23.9	18.0	94	0.3	26.2	4.9	91	2.21	41.1	2.8	0.2	24	0.2	2.5	0.3	47	0.02	0.079	9
1090437	Soil	2.7	43.4	16.1	142	0.7	55.9	7.9	96	2.78	12.2	3.4	0.9	18	0.3	1.3	0.2	31	0.01	0.075	3
1090440	Soil	2.2	29.8	11.7	164	1.0	81.7	13.4	451	2.74	8.9	4.0	1.3	34	0.7	0.8	0.2	18	0.59	0.065	7
1090445	Soil	2.3	22.6	11.9	83	0.2	24.6	4.5	145	1.61	13.3	3.7	0.1	25	0.2	1.6	0.2	32	0.09	0.056	4
1090446	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090448	Soil	1.6	19.9	8.3	179	0.6	33.6	4.0	392	1.46	11.0	6.4	0.2	95	3.5	1.8	0.3	24	2.83	0.265	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090393	Soil	1	0.02	600	0.005	1	0.35	0.015	0.04	<0.1	0.31	0.8	0.2	<0.05	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090394	Soil	13	0.04	1537	0.004	5	0.46	0.006	0.06	0.1	0.47	1.7	0.5	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090395	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	7.5	30.8	18.9	183
1090396	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.0	39.6	21.0	215
1090397	Soil	17	0.05	701	<0.001	2	0.61	0.004	0.07	<0.1	2.36	2.9	0.2	<0.05	1	8.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090398	Soil	14	0.04	710	0.002	1	0.53	0.006	0.06	<0.1	1.08	1.2	0.2	0.09	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090399	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.6	32.0	22.0	129
1090400	Soil	16	0.05	1608	0.002	4	0.53	0.004	0.06	<0.1	0.51	2.0	0.2	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090406	Soil	7	0.03	165	0.002	2	0.32	0.002	0.07	<0.1	0.08	1.4	0.3	0.06	1	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090410	Soil	20	0.10	182	0.003	3	0.83	0.003	0.06	<0.1	0.10	4.5	0.4	<0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090421	Soil	10	0.05	711	0.004	1	0.51	0.007	0.08	0.1	0.37	0.4	0.4	0.14	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090475	Soil	7	0.02	563	<0.001	2	0.21	0.002	0.07	<0.1	0.32	1.7	0.3	0.17	<1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090476	Soil	16	0.08	452	0.001	2	0.60	0.002	0.06	<0.1	0.26	4.3	0.3	0.08	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090478	Soil	8	<0.01	224	<0.001	3	0.27	0.002	0.08	<0.1	0.70	1.7	0.3	0.09	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090479	Soil	12	0.01	377	0.001	4	0.26	0.004	0.09	<0.1	1.34	1.2	0.4	0.08	2	7.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090480	Soil	12	0.06	812	0.005	3	0.33	0.004	0.12	0.1	2.57	1.9	0.6	0.25	2	10.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090424	Soil	9	0.05	839	0.006	1	0.39	0.003	0.07	0.1	0.43	0.4	0.4	0.13	3	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090425	Soil	3	0.02	129	0.009	<1	0.29	0.022	0.02	<0.1	<0.01	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090427	Soil	9	0.04	251	0.004	2	0.52	0.011	0.04	<0.1	0.35	0.3	0.3	0.07	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090429	Soil	14	0.09	334	0.006	2	0.76	0.004	0.06	0.1	0.48	0.5	0.5	0.09	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090430	Soil	9	0.05	225	0.003	2	0.55	0.004	0.04	0.1	0.14	0.5	0.2	0.06	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090432	Soil	21	0.02	324	0.002	2	0.75	0.004	0.06	<0.1	0.13	0.7	<0.1	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090433	Soil	16	0.02	407	0.005	4	0.36	0.010	0.07	<0.1	0.02	0.6	0.1	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090435	Soil	30	0.04	1306	0.002	6	0.63	0.007	0.12	<0.1	0.32	2.2	0.2	0.12	2	9.8	0.2	N.A.	N.A.	N.A.	N.A.
1090436	Soil	12	0.04	208	0.006	<1	0.46	0.005	0.07	0.1	<0.01	0.7	0.3	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090437	Soil	26	0.07	151	0.003	2	0.67	0.005	0.04	<0.1	0.03	1.8	<0.1	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090440	Soil	18	0.11	502	<0.001	2	0.81	0.005	0.04	<0.1	0.08	3.0	<0.1	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090445	Soil	13	0.03	205	0.005	<1	0.45	0.012	0.05	0.1	0.05	0.6	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090446	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.3	19.9	9.5	100
1090448	Soil	25	0.04	344	0.008	1	0.69	0.014	0.04	0.1	0.89	1.1	<0.1	0.13	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090393	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090394	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090395	Soil		1.6	55.3	7.8	221	2.07	34.3	14.2	0.2	45	1.9	1.9	0.3	48	0.25	0.105	5	13	0.05	1955	0.001
1090396	Soil		0.9	61.3	9.1	173	2.67	67.4	14.0	0.6	44	1.8	3.9	0.2	28	0.26	0.068	4	13	0.09	714	<0.001
1090397	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090398	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090399	Soil		0.9	27.0	4.5	148	2.66	40.8	11.1	0.3	45	0.6	1.1	0.3	47	0.08	0.156	3	19	0.03	787	0.001
1090400	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090406	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090410	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090421	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090475	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090476	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090478	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090479	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090480	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090424	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090425	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090427	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090429	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090430	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090432	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090433	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090435	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090436	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090437	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090440	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090445	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090446	Soil		0.5	25.7	5.0	202	1.29	12.7	3.8	0.1	43	1.1	1.2	0.1	18	0.59	0.091	3	10	0.05	325	0.003
1090448	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090393	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090394	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090395	Soil	<20	0.66	0.007	0.04	0.1	1.50	0.9	0.4	0.05	2	2.5	<0.2
1090396	Soil	<20	0.43	0.006	0.05	<0.1	2.22	2.3	0.2	0.08	1	4.8	<0.2
1090397	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090398	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090399	Soil	<20	0.79	0.006	0.06	<0.1	0.76	1.1	0.2	0.10	3	1.9	<0.2
1090400	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090406	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090410	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090421	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090475	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090476	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090478	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090479	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090480	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090424	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090425	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090427	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090429	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090430	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090432	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090433	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090435	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090436	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090437	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090440	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090445	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090446	Soil	<20	0.41	0.017	0.05	<0.1	0.32	0.6	<0.1	0.11	2	1.4	<0.2
1090448	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090449	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090461	Soil	53.6	49.0	17.7	249	0.7	105.3	8.2	210	2.20	78.7	4.0	1.1	112	1.8	13.8	0.1	111	3.09	0.143	9
1090464	Soil	79.3	137.9	18.2	1900	2.9	317.4	8.5	265	2.45	128.2	4.5	2.7	93	26.2	40.2	0.3	607	2.31	0.257	22
1090467	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090469	Soil	19.4	24.2	31.1	130	0.7	17.6	1.7	54	1.22	26.5	7.4	0.6	31	1.2	5.8	0.2	81	0.05	0.050	3
1090481	Soil	12.3	28.6	44.1	86	0.8	18.7	3.5	91	1.89	60.0	21.6	2.5	63	0.2	11.7	0.3	67	0.05	0.075	7
1090482	Soil	20.1	20.6	70.6	17	1.6	4.9	0.6	23	1.08	39.8	30.0	0.4	103	<0.1	16.1	0.3	91	0.02	0.107	3
1090483	Soil	9.6	19.4	36.2	53	1.0	10.7	2.2	44	1.24	37.4	36.8	0.3	55	0.1	9.2	0.2	48	0.02	0.068	4
1090484	Soil	8.2	26.7	31.7	101	0.7	21.4	7.0	135	1.81	45.0	26.0	0.6	46	0.3	7.6	0.3	47	0.02	0.063	5
1090485	Soil	6.3	28.7	32.6	91	0.8	17.2	4.1	78	1.59	56.2	46.7	0.6	66	0.1	8.6	0.3	51	0.02	0.071	4
1090486	Soil	3.1	33.8	24.4	132	0.3	30.9	12.5	237	2.63	41.0	10.1	1.1	36	0.5	3.8	0.3	27	0.02	0.049	3
1090487	Soil	3.6	40.7	26.8	185	0.3	45.6	18.5	262	3.42	51.5	7.3	1.1	44	0.3	3.7	0.3	29	0.02	0.057	4
1090488	Soil	3.0	35.5	27.8	180	0.3	46.6	16.8	271	2.84	81.1	13.8	1.5	40	0.8	4.3	0.3	23	0.02	0.047	4
1090489	Soil	3.7	32.2	43.3	149	0.5	36.9	12.7	260	2.65	89.0	31.1	1.4	51	0.9	6.5	0.3	32	0.03	0.052	3
1090490	Soil	8.3	13.2	13.3	51	0.9	8.7	1.6	65	0.96	16.0	1.5	<0.1	22	0.3	2.9	0.2	50	0.02	0.063	4
1090491	Soil	8.6	117.3	23.3	440	2.1	62.9	12.4	477	5.91	79.9	17.3	1.0	212	2.8	4.9	0.4	77	0.07	0.310	8
1090492	Soil	5.0	17.9	59.1	40	2.7	8.5	1.7	33	2.83	63.0	18.0	1.3	58	0.2	4.3	0.6	51	0.01	0.098	3
1090493	Soil	2.8	28.4	33.2	75	2.2	13.9	2.6	54	3.16	38.6	7.8	1.3	38	0.2	2.0	0.3	45	0.01	0.070	3
1090494	Soil	4.5	65.6	37.7	134	1.2	23.1	3.8	85	3.91	45.8	5.6	0.4	58	0.4	2.9	0.5	59	0.03	0.132	5
1090495	Soil	2.5	34.6	18.8	54	0.7	9.5	2.0	61	2.24	26.2	1.8	0.7	24	0.1	1.0	0.3	28	0.01	0.067	2
1090496	Soil	3.1	54.5	33.3	88	1.0	17.6	3.5	86	3.54	38.1	1.5	1.6	66	0.2	1.3	0.4	31	0.02	0.104	4
1090497	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090498	Soil	3.4	48.6	31.0	79	2.4	14.4	2.7	51	3.74	39.5	8.1	1.7	70	0.1	1.9	0.4	42	0.01	0.094	4
1090499	Soil	6.9	55.6	23.4	82	2.9	16.6	2.3	42	2.71	34.9	6.1	1.3	45	0.1	2.8	0.3	45	0.02	0.064	3
1090500	Soil	11.7	53.9	15.6	120	3.0	23.5	2.4	35	2.38	27.6	7.0	0.6	12	0.4	2.8	0.2	63	0.02	0.052	2
1090501	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090502	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090503	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090504	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090505	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090449	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	0.5	5.6	2.0	22
1090461	Soil	10	1.58	890	0.001	3	0.22	0.006	0.07	<0.1	0.43	1.5	0.4	0.13	<1	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090464	Soil	59	0.95	599	0.003	4	0.62	0.006	0.13	0.5	1.84	4.6	2.4	<0.05	3	11.7	0.3	N.A.	N.A.	N.A.	N.A.
1090467	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090469	Soil	7	0.02	207	<0.001	<1	0.27	0.002	0.06	<0.1	1.23	0.9	0.7	<0.05	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090481	Soil	15	0.08	718	0.008	2	0.45	0.003	0.12	<0.1	3.65	2.4	0.5	0.17	2	8.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090482	Soil	21	0.02	1498	0.003	3	0.40	0.003	0.11	0.1	12.69	1.7	0.8	0.14	3	10.6	0.3	N.A.	N.A.	N.A.	N.A.
1090483	Soil	12	0.03	703	0.002	<1	0.39	0.005	0.06	<0.1	6.15	1.1	0.5	<0.05	2	6.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090484	Soil	11	0.04	546	0.002	<1	0.42	0.003	0.06	<0.1	3.11	1.7	0.5	<0.05	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090485	Soil	13	0.02	677	0.002	1	0.37	0.002	0.07	<0.1	3.82	2.0	0.6	0.08	2	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090486	Soil	8	0.03	367	<0.001	<1	0.32	0.002	0.06	<0.1	1.43	3.1	0.3	0.05	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090487	Soil	9	0.05	281	0.001	<1	0.42	0.003	0.07	<0.1	0.80	3.7	0.3	0.08	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090488	Soil	8	0.03	350	<0.001	<1	0.29	0.002	0.05	<0.1	0.93	3.6	0.3	0.07	<1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090489	Soil	8	0.03	602	<0.001	<1	0.31	0.002	0.05	<0.1	1.42	3.6	0.3	0.06	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090490	Soil	11	0.01	173	0.002	<1	0.26	0.009	0.06	0.1	0.11	0.2	0.3	0.10	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090491	Soil	37	0.03	798	0.005	2	1.09	0.007	0.16	0.1	0.59	4.4	0.2	0.37	4	7.6	0.3	N.A.	N.A.	N.A.	N.A.
1090492	Soil	14	<0.01	839	0.005	1	0.28	0.008	0.26	<0.1	0.48	4.2	0.2	0.52	3	7.3	0.4	N.A.	N.A.	N.A.	N.A.
1090493	Soil	14	0.03	580	0.002	2	0.48	0.005	0.16	<0.1	0.11	1.5	0.1	0.22	3	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090494	Soil	23	0.03	327	0.007	2	0.71	0.005	0.09	0.2	0.20	1.5	0.1	0.10	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090495	Soil	15	0.03	112	0.004	1	0.60	0.010	0.05	<0.1	0.08	0.8	<0.1	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090496	Soil	18	0.05	274	0.002	<1	0.88	0.006	0.09	<0.1	0.14	1.7	0.2	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090497	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.3	34.4	18.1	63
1090498	Soil	25	0.03	1603	0.002	6	0.61	0.007	0.17	<0.1	0.42	2.2	0.1	0.25	3	7.4	0.4	N.A.	N.A.	N.A.	N.A.
1090499	Soil	29	0.02	938	0.001	6	0.45	0.006	0.12	<0.1	0.32	2.4	0.2	0.14	2	11.0	0.2	N.A.	N.A.	N.A.	N.A.
1090500	Soil	35	0.02	687	0.002	4	0.62	0.005	0.07	<0.1	0.16	1.9	0.2	<0.05	2	9.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090501	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.9	52.7	11.9	833
1090502	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.9	17.1	14.0	144
1090503	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.9	37.4	12.8	190
1090504	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.1	19.5	6.9	53
1090505	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.4	29.2	11.0	87

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090449	Soil	<0.1	4.6	1.1	45	0.32	1.6	<0.5	<0.1	24	0.5	0.2	<0.1	9	0.71	0.054	2	5	0.02	66	0.010
1090461	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090464	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090467	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090469	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090481	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090482	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090483	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090484	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090485	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090486	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090487	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090488	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090489	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090490	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090491	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090492	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090493	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090494	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090495	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090496	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090497	Soil	1.1	12.1	1.8	48	2.13	20.7	2.7	0.3	24	<0.1	0.8	0.2	41	0.03	0.065	3	17	0.01	343	0.002
1090498	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090499	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090500	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090501	Soil	0.8	243.8	8.0	210	2.61	44.6	9.9	1.0	89	2.4	5.5	0.4	40	2.15	0.333	16	26	0.06	509	0.003
1090502	Soil	0.5	22.6	4.1	159	1.38	27.4	17.6	0.5	53	1.8	2.5	0.3	22	1.14	0.094	5	12	0.06	263	0.003
1090503	Soil	0.6	54.3	3.5	102	1.24	30.5	20.2	0.4	89	1.3	3.5	0.3	24	2.81	0.158	5	16	0.08	723	0.002
1090504	Soil	0.3	14.1	2.7	245	0.69	12.4	8.1	0.2	81	1.3	1.7	0.2	12	2.82	0.108	3	8	0.06	632	0.004
1090505	Soil	0.4	24.0	3.5	145	1.13	17.4	12.9	0.3	76	1.0	1.8	0.2	21	2.61	0.095	4	14	0.07	570	0.003

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090449	Soil	<20	0.35	0.038	0.02	<0.1	0.07	0.4	<0.1	<0.05	<1	<0.5	<0.2
1090461	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090464	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090467	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090469	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090481	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090482	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090483	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090484	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090485	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090486	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090487	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090488	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090489	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090490	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090491	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090492	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090493	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090494	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090495	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090496	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090497	Soil	<20	0.42	0.008	0.06	<0.1	0.10	0.8	<0.1	0.10	3	2.3	0.2
1090498	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090499	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090500	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090501	Soil	<20	0.70	0.014	0.07	0.3	0.59	2.7	0.3	0.11	2	1.6	<0.2
1090502	Soil	<20	0.41	0.011	0.04	0.1	1.19	1.2	0.2	0.11	1	1.3	<0.2
1090503	Soil	<20	0.47	0.029	0.04	0.9	1.19	0.9	0.2	0.23	1	2.6	<0.2
1090504	Soil	<20	0.43	0.023	0.02	0.1	0.49	0.5	<0.1	0.22	1	0.9	<0.2
1090505	Soil	<20	0.44	0.029	0.05	1.0	0.58	0.9	<0.1	0.33	1	2.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090506	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090507	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090508	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090509	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090510	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090511	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090512	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090513	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090514	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090515	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090516	Soil	3.2	54.5	16.9	91	0.6	28.5	9.1	224	1.98	32.9	20.7	0.8	32	0.6	5.3	0.1	41	0.24	0.070	3
1090517	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090518	Soil	11.0	47.8	16.6	175	0.7	56.1	9.5	153	2.33	55.3	12.4	2.3	47	0.8	5.4	0.1	51	0.34	0.131	10
1090519	Soil	18.6	29.1	11.4	154	0.3	39.0	4.3	30	1.29	35.0	2.2	0.4	7	0.3	8.7	0.1	119	0.01	0.035	10
1090520	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090541	Soil	59.4	69.7	15.1	3091	0.6	158.4	11.1	355	2.04	34.1	<0.5	1.8	66	70.1	6.2	0.1	85	1.65	0.118	8
1090542	Soil	52.6	55.6	12.3	458	0.6	127.7	7.1	189	1.56	22.0	<0.5	1.4	169	7.3	5.8	<0.1	100	4.86	0.107	7
1090543	Soil	29.7	26.4	9.2	642	0.2	62.8	5.5	195	1.38	15.8	<0.5	2.2	41	8.8	12.5	<0.1	153	1.91	0.076	5
1090544	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090545	Soil	4.9	48.8	18.6	165	0.4	59.3	15.5	199	4.20	8.6	2.8	3.1	9	0.9	2.0	0.2	22	0.05	0.066	8
1090546	Soil	7.5	31.2	14.1	167	0.6	35.9	6.0	82	2.48	12.0	<0.5	0.6	8	0.6	2.0	0.2	33	0.04	0.086	8
1090547	Soil	5.7	15.7	10.7	110	0.3	21.4	3.9	45	1.43	11.8	1.2	0.2	7	0.5	1.6	0.2	47	0.01	0.046	9
1090548	Soil	5.9	27.5	11.9	139	0.1	33.9	7.0	58	2.20	11.7	0.6	1.2	6	0.5	2.0	0.2	47	0.03	0.038	9
1090549	Soil	4.1	26.7	12.2	95	0.6	22.9	5.1	46	1.76	5.6	0.8	0.3	14	0.3	1.0	0.2	26	0.06	0.069	8
1090550	Soil	4.4	45.9	16.0	237	1.0	55.3	9.7	60	2.98	7.3	1.4	2.4	17	0.4	1.8	0.2	22	0.04	0.077	10
1090551	Soil	7.4	45.3	19.3	153	1.4	29.5	4.5	50	2.30	88.0	18.5	1.3	33	0.8	10.3	0.3	25	0.09	0.066	5
1090552	Soil	6.1	32.9	17.3	149	1.0	25.0	13.6	543	2.12	49.9	14.9	1.8	25	1.2	4.2	0.3	49	0.18	0.081	6
1090553	Soil	3.6	40.4	16.3	171	0.8	35.8	6.4	192	2.21	38.7	11.8	1.2	44	0.9	2.8	0.2	38	0.65	0.099	5
1090554	Soil	3.1	39.9	15.6	169	1.4	42.5	7.9	193	2.41	33.9	8.8	1.3	53	0.8	2.4	0.2	37	0.92	0.101	5
1090555	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090506	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.7	28.9	11.2	141
1090507	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090508	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090509	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.4	16.0	13.6	64
1090510	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.8	30.2	5.4	91
1090511	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.9	29.4	23.3	141
1090512	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.4	5.3	2.4	30
1090513	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.1	12.6	7.3	48
1090514	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.6	27.3	5.7	28
1090515	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090516	Soil	26	0.17	877	0.004	3	0.72	0.009	0.03	0.2	1.97	1.6	0.1	0.08	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090517	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.7	29.2	16.1	61
1090518	Soil	19	0.06	1439	0.003	3	0.39	0.004	0.06	0.1	1.45	2.0	0.2	<0.05	1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090519	Soil	10	0.02	161	0.004	3	0.28	0.002	0.04	0.4	0.29	0.6	0.3	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090520	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.0	19.6	3.2	24
1090541	Soil	16	0.54	348	0.003	4	0.22	0.006	0.07	0.2	0.24	3.4	1.4	0.19	<1	13.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090542	Soil	15	1.90	314	0.002	5	0.14	0.006	0.05	0.2	0.37	2.4	0.7	0.10	<1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090543	Soil	10	0.80	300	0.002	4	0.17	0.005	0.06	<0.1	0.11	1.9	0.2	0.08	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090544	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	18.2	17.5	9.6	392
1090545	Soil	11	0.05	1653	0.003	2	0.46	0.003	0.07	<0.1	0.08	2.5	<0.1	0.05	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090546	Soil	10	0.04	446	0.003	1	0.47	0.003	0.06	<0.1	0.03	0.7	0.1	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090547	Soil	7	0.03	131	0.003	1	0.38	0.003	0.04	0.1	<0.01	0.4	0.1	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090548	Soil	10	0.04	117	0.004	2	0.39	0.005	0.05	0.1	0.02	1.1	<0.1	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090549	Soil	8	0.03	840	0.003	2	0.42	0.005	0.07	0.2	0.04	0.5	<0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090550	Soil	10	0.05	3575	0.003	<1	0.58	0.003	0.09	<0.1	0.04	1.6	<0.1	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090551	Soil	14	0.04	435	<0.001	2	0.35	0.004	0.06	0.2	6.94	1.9	0.2	<0.05	1	6.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090552	Soil	18	0.11	607	0.004	3	0.65	0.007	0.06	0.3	1.45	2.1	0.2	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090553	Soil	21	0.13	528	0.002	4	0.78	0.007	0.08	0.1	0.91	2.7	<0.1	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090554	Soil	22	0.16	513	0.001	3	0.83	0.007	0.05	0.1	1.22	3.1	0.1	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090555	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.0	30.4	12.0	130

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090506	Soil	0.7	23.5	5.1	189	1.37	17.6	12.5	0.3	93	1.6	1.5	0.2	24	2.41	0.124	5	16	0.12	398	0.003
1090507	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090508	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090509	Soil	0.2	10.3	1.8	68	0.58	8.5	11.6	0.2	71	0.9	1.2	0.2	13	1.71	0.059	2	10	0.05	368	0.010
1090510	Soil	0.2	24.3	2.8	305	0.55	8.3	6.1	0.2	131	1.1	2.6	0.1	13	3.11	0.097	3	20	0.08	618	0.006
1090511	Soil	0.5	40.0	4.7	150	1.42	25.5	16.9	0.6	68	1.0	3.0	0.2	38	0.93	0.093	7	28	0.07	983	0.004
1090512	Soil	0.6	6.1	1.3	19	0.46	8.4	1.7	<0.1	5	0.1	1.2	<0.1	25	0.03	0.013	4	4	0.01	50	0.006
1090513	Soil	0.5	13.8	1.6	22	0.58	13.0	2.5	<0.1	13	0.3	2.0	<0.1	40	0.20	0.022	5	12	0.01	89	0.004
1090514	Soil	0.5	17.8	1.8	57	0.56	6.8	6.1	0.2	66	0.5	3.1	0.1	23	1.64	0.092	3	14	0.05	1230	0.012
1090515	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090516	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090517	Soil	0.5	36.4	4.3	138	1.14	20.9	17.5	0.4	37	0.6	4.3	0.1	36	0.45	0.073	4	50	0.08	852	0.006
1090518	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090519	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090520	Soil	1.1	9.2	2.1	21	0.39	5.4	5.5	<0.1	11	0.7	1.2	<0.1	17	0.05	0.063	1	<1	0.02	314	0.003
1090541	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090542	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090543	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090544	Soil	0.1	35.3	2.9	40	0.92	12.0	<0.5	0.7	18	6.1	7.7	<0.1	103	0.38	0.047	4	10	0.07	223	0.003
1090545	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090546	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090547	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090548	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090549	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090550	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090551	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090552	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090553	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090554	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090555	Soil	0.5	31.7	4.7	79	1.85	34.8	7.6	0.8	41	0.9	3.3	0.2	34	0.74	0.068	5	13	0.10	439	0.002

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090506	Soil	<20	0.57	0.017	0.04	<0.1	0.68	1.2	<0.1	0.22	1	1.9	<0.2
1090507	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090508	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090509	Soil	<20	0.36	0.019	0.02	0.1	0.39	0.5	<0.1	0.29	1	1.0	<0.2
1090510	Soil	<20	0.41	0.017	0.02	0.2	0.29	0.4	<0.1	0.22	<1	2.2	<0.2
1090511	Soil	<20	0.49	0.012	0.04	0.2	1.07	1.3	0.2	0.13	1	1.2	<0.2
1090512	Soil	<20	0.10	0.011	0.01	0.2	0.51	0.2	<0.1	<0.05	<1	<0.5	<0.2
1090513	Soil	<20	0.17	0.009	0.02	0.2	0.18	0.3	<0.1	<0.05	1	0.6	<0.2
1090514	Soil	<20	0.38	0.021	0.02	0.5	1.03	0.6	0.2	0.14	1	2.2	<0.2
1090515	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090516	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090517	Soil	<20	0.41	0.013	0.03	1.8	1.18	0.9	0.2	0.10	2	2.5	<0.2
1090518	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090519	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090520	Soil	<20	0.20	0.015	0.01	<0.1	1.21	0.2	0.1	<0.05	<1	0.7	<0.2
1090541	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090542	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090543	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090544	Soil	<20	0.22	0.007	0.03	<0.1	0.07	0.9	0.2	0.06	1	1.8	<0.2
1090545	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090546	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090547	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090548	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090549	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090550	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090551	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090552	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090553	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090554	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090555	Soil	<20	0.53	0.008	0.04	0.1	0.51	1.5	0.2	0.08	2	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090556	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090557	Soil	3.3	39.9	12.9	111	1.0	35.4	7.4	143	1.86	22.1	9.7	1.0	52	0.7	2.7	0.2	44	0.75	0.084	4
1090558	Soil	5.2	50.5	16.6	141	0.8	33.9	6.9	199	2.52	20.2	2.6	1.3	27	0.7	2.5	0.2	36	0.15	0.065	5
1090559	Soil	5.8	55.1	15.4	187	0.2	42.0	8.8	234	3.01	37.1	1.3	1.7	16	0.7	3.3	0.2	36	0.04	0.059	7
1090560	Soil	6.7	43.3	27.2	142	1.7	29.6	6.6	190	2.23	150.9	101.3	1.6	51	0.7	17.9	0.5	46	0.39	0.099	9
1090561	Soil	4.7	44.4	17.1	169	1.1	35.9	6.7	180	2.11	60.8	13.7	1.2	55	1.2	6.4	0.3	49	0.61	0.088	7
1090562	Soil	5.2	47.6	19.1	129	1.6	27.4	4.3	58	2.40	116.4	37.6	1.1	37	0.7	12.2	0.4	34	0.13	0.067	6
1090563	Soil	6.3	45.9	26.3	115	1.7	26.3	3.5	45	2.11	134.9	46.2	1.3	55	0.6	16.8	0.7	33	0.37	0.074	8
1090564	Soil	8.5	19.5	17.1	619	1.1	77.2	2.3	108	0.88	20.9	5.2	0.2	40	12.5	5.9	<0.1	76	0.34	0.064	3
1090565	Soil	14.6	42.5	12.6	1695	1.0	223.4	8.2	318	1.98	30.1	6.8	1.3	79	9.5	6.2	0.2	89	1.13	0.078	7
1090566	Soil	13.6	63.7	15.4	1758	0.9	259.6	8.4	181	2.25	37.4	5.7	1.7	76	18.1	7.4	0.2	93	1.18	0.113	11
1090567	Soil	22.3	63.9	12.7	1941	1.0	237.3	13.3	472	2.61	35.0	4.8	2.3	42	19.8	7.8	0.2	112	0.51	0.111	16
1090568	Soil	5.6	56.2	13.7	107	2.5	24.0	8.1	328	1.83	20.9	4.0	0.4	20	1.2	2.3	0.2	50	0.06	0.128	10
1090569	Soil	8.0	114.8	31.1	261	1.1	54.2	12.1	276	7.63	74.6	6.5	3.4	116	1.9	8.1	0.3	36	0.10	0.296	13
1090570	Soil	9.3	20.0	5.9	120	<0.1	21.8	3.1	42	1.19	14.6	<0.5	0.6	5	0.7	2.2	0.1	55	0.02	0.025	17
1090571	Soil	12.0	36.5	20.7	209	0.3	47.9	6.0	82	2.68	37.3	1.4	2.5	22	0.4	3.6	0.3	73	0.04	0.158	15
1090572	Soil	12.8	37.4	24.7	114	0.9	27.6	4.5	55	2.22	21.6	4.7	1.3	12	0.5	2.8	0.2	26	0.03	0.061	22
1090573	Soil	11.7	23.6	19.3	109	0.6	23.9	2.7	38	1.19	14.9	<0.5	<0.1	25	1.0	3.7	0.1	61	0.08	0.121	10
1090574	Soil	8.4	24.9	10.2	77	0.5	13.9	1.9	26	0.78	11.9	<0.5	0.1	10	0.3	2.0	<0.1	57	0.06	0.056	11
1090575	Soil	18.8	16.3	4.6	158	0.3	39.9	2.7	69	0.68	12.9	0.8	0.3	19	1.9	3.5	<0.1	133	0.25	0.033	8
1090576	Soil	28.6	27.0	4.9	121	0.1	57.2	3.5	45	0.91	17.2	<0.5	0.7	39	1.6	1.7	<0.1	88	0.66	0.042	10
1090577	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090578	Soil	12.5	35.7	4.6	103	0.3	53.3	4.6	182	0.97	12.9	1.2	0.4	54	1.1	2.7	<0.1	51	1.10	0.081	5
1090579	Soil	66.2	36.7	10.8	271	0.2	80.6	4.6	64	1.95	35.1	1.9	0.4	16	1.1	13.4	0.1	330	0.14	0.054	26
1090580	Soil	36.7	19.7	7.3	128	<0.1	43.1	2.8	29	1.08	18.3	<0.5	0.2	9	0.3	6.4	<0.1	207	0.03	0.029	25
1090531	Soil	7.6	105.1	30.9	374	0.7	92.4	21.3	282	3.77	70.2	6.0	2.4	61	0.6	5.1	0.4	35	0.35	0.145	6
1090532	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090533	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090534	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090535	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090556	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	10.7	56.8	20.9	208
1090557	Soil	17	0.12	835	0.002	4	0.92	0.010	0.06	<0.1	0.77	2.2	0.2	0.07	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090558	Soil	21	0.23	440	0.002	3	0.78	0.006	0.05	<0.1	0.14	1.7	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090559	Soil	26	0.28	818	0.001	3	0.83	0.003	0.06	<0.1	0.23	1.7	0.1	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090560	Soil	17	0.09	511	0.002	5	0.57	0.008	0.08	0.4	11.42	2.4	0.7	0.07	2	7.1	0.4	N.A.	N.A.	N.A.	N.A.
1090561	Soil	18	0.13	684	0.002	3	0.72	0.006	0.06	0.1	2.77	2.3	0.4	0.07	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090562	Soil	14	0.05	526	<0.001	3	0.44	0.003	0.06	0.1	7.31	1.8	0.3	0.06	1	6.4	0.2	N.A.	N.A.	N.A.	N.A.
1090563	Soil	13	0.06	542	0.001	3	0.48	0.004	0.06	0.3	25.15	1.8	0.5	0.09	1	9.4	0.3	N.A.	N.A.	N.A.	N.A.
1090564	Soil	9	0.05	485	0.008	4	0.53	0.022	0.05	0.2	0.62	0.8	0.8	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090565	Soil	12	0.11	1148	0.004	4	0.69	0.011	0.07	0.2	0.52	2.4	1.0	0.06	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090566	Soil	13	0.08	1567	0.002	4	0.63	0.004	0.07	0.2	0.88	2.9	0.8	0.09	1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090567	Soil	16	0.08	1069	0.002	5	0.46	0.002	0.07	0.2	0.99	3.6	1.4	<0.05	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090568	Soil	9	0.03	1183	0.003	2	0.77	0.006	0.06	0.1	0.60	1.2	0.4	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090569	Soil	10	0.03	247	0.004	3	0.75	0.006	0.26	0.1	0.22	3.1	0.4	0.48	2	5.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090570	Soil	6	0.02	107	0.005	2	0.38	0.004	0.05	0.1	0.03	0.6	0.3	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090571	Soil	13	0.05	192	0.002	3	0.78	0.002	0.11	<0.1	0.02	1.5	0.3	<0.05	2	2.2	0.2	N.A.	N.A.	N.A.	N.A.
1090572	Soil	5	0.03	244	0.002	3	0.56	0.004	0.09	<0.1	0.22	1.4	0.2	<0.05	1	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090573	Soil	7	0.02	198	0.004	2	0.31	0.006	0.06	0.1	0.10	0.2	0.3	0.06	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090574	Soil	7	0.04	182	0.002	1	0.44	0.004	0.05	0.1	0.16	0.2	0.3	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090575	Soil	13	0.06	139	0.004	1	0.46	0.017	0.04	0.1	0.36	0.7	0.5	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090576	Soil	15	0.12	404	0.003	<1	0.68	0.008	0.05	0.2	0.09	1.1	0.7	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090577	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	59.8	35.8	5.6	198
1090578	Soil	10	0.11	510	0.008	3	0.60	0.022	0.04	0.1	0.35	1.4	0.4	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090579	Soil	17	0.06	184	0.007	5	0.48	0.005	0.07	0.3	0.09	0.8	1.1	<0.05	3	4.5	0.3	N.A.	N.A.	N.A.	N.A.
1090580	Soil	14	0.04	97	0.005	3	0.43	0.004	0.05	0.3	0.02	0.3	0.7	<0.05	4	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090531	Soil	9	0.02	222	<0.001	<1	0.38	0.003	0.06	<0.1	0.11	3.8	0.1	<0.05	1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090532	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.3	57.8	23.7	164
1090533	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.8	63.9	23.5	179
1090534	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.6	108.6	50.8	539
1090535	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.8	73.9	26.9	226

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090556	Soil	1.8	49.8	11.2	245	2.23	36.6	15.6	0.8	84	1.1	3.8	0.2	72	0.52	0.111	6	20	0.11	1207	0.001
1090557	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090558	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090559	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090560	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090561	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090562	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090563	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090564	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090565	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090566	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090567	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090568	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090569	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090570	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090571	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090572	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090573	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090574	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090575	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090576	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090577	Soil	<0.1	131.0	7.2	56	1.41	31.2	1.8	0.6	16	1.1	2.8	<0.1	47	0.29	0.031	6	10	0.09	143	0.002
1090578	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090579	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090580	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090531	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090532	Soil	0.7	50.9	13.4	324	2.42	45.4	5.6	0.9	29	0.3	1.3	0.3	32	0.27	0.078	4	17	0.04	422	<0.001
1090533	Soil	0.7	48.8	14.4	353	2.62	49.8	7.0	1.0	31	0.4	1.9	0.4	37	0.26	0.083	5	16	0.05	535	0.001
1090534	Soil	1.7	101.3	38.9	903	5.74	48.3	10.9	2.9	20	1.0	3.9	0.5	35	0.23	0.069	3	12	0.12	1091	<0.001
1090535	Soil	1.5	46.5	19.6	549	2.47	19.8	9.3	1.0	34	0.6	2.0	0.4	27	0.53	0.069	5	9	0.11	637	0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090556	Soil	<20	0.77	0.007	0.06	0.2	1.40	2.5	0.4	0.10	2	4.1	<0.2
1090557	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090558	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090559	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090560	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090561	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090562	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090563	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090564	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090565	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090566	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090567	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090568	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090569	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090570	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090571	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090572	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090573	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090574	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090575	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090576	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090577	Soil	<20	0.29	0.007	0.04	0.3	0.10	1.2	0.8	<0.05	1	1.8	<0.2
1090578	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090579	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090580	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090531	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090532	Soil	<20	0.39	0.005	0.05	<0.1	0.11	2.9	0.1	0.08	1	1.1	<0.2
1090533	Soil	<20	0.48	0.005	0.09	<0.1	0.09	2.8	0.2	0.10	2	1.1	<0.2
1090534	Soil	<20	0.56	0.003	0.11	<0.1	0.16	6.5	0.5	<0.05	2	3.2	<0.2
1090535	Soil	<20	0.48	0.009	0.08	<0.1	0.17	3.7	0.3	0.05	2	2.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090536	Soil	3.8	71.2	25.8	178	0.6	43.5	21.7	888	2.30	20.4	4.7	0.9	24	0.7	2.0	0.3	31	0.26	0.071	5
1090537	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090538	Soil	6.5	23.4	10.5	55	0.5	18.0	5.0	142	0.92	8.6	<0.5	<0.1	20	0.4	1.1	<0.1	27	0.16	0.101	3
1090539	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090540	Soil	53.4	58.5	11.0	251	0.5	116.1	7.7	185	1.46	29.4	4.2	1.8	212	3.0	5.9	<0.1	92	6.59	0.112	8
1090581	Soil	87.2	38.3	7.5	300	0.5	76.7	2.6	30	1.58	25.8	1.3	<0.1	7	0.9	16.2	<0.1	442	0.08	0.055	28
1090582	Soil	4.8	7.9	3.3	68	0.7	12.2	1.2	26	0.60	7.3	4.7	<0.1	16	3.4	1.4	0.3	56	0.14	0.042	2
1090583	Soil	20.5	19.2	6.6	115	<0.1	31.9	2.3	31	0.94	15.8	2.5	<0.1	9	1.4	3.6	0.3	91	0.06	0.044	12
1090584	Soil	41.5	43.3	14.4	279	<0.1	126.3	9.3	199	3.63	43.0	0.7	1.5	7	0.8	4.1	0.2	189	0.04	0.039	16
1090585	Soil	6.0	8.9	6.4	43	<0.1	10.1	1.2	19	0.63	15.4	3.6	0.2	8	0.2	1.8	0.2	40	0.01	0.036	17
1090586	Soil	4.1	21.9	6.2	82	0.4	39.4	4.3	45	1.67	15.8	2.9	0.6	4	0.2	1.9	0.2	27	0.02	0.030	13
1090587	Soil	5.9	30.6	10.3	121	1.9	30.2	3.5	55	1.85	70.6	11.8	<0.1	55	1.2	6.7	0.4	49	0.57	0.115	6
1090588	Soil	16.1	46.8	16.6	324	0.6	65.1	7.0	109	2.89	119.7	22.7	1.1	60	1.7	16.5	0.4	136	0.09	0.121	16
1090589	Soil	3.2	12.2	4.0	42	0.8	10.6	1.6	22	0.81	17.7	4.6	<0.1	11	0.6	1.8	0.2	39	0.04	0.044	5
1090590	Soil	8.6	18.6	11.5	107	0.4	22.3	3.1	65	1.71	50.8	7.8	0.2	19	0.6	5.2	0.4	91	0.05	0.055	14
1090591	Soil	13.3	25.9	16.0	210	0.3	44.9	5.5	118	2.66	79.4	8.2	1.5	24	0.8	7.6	0.4	92	0.07	0.074	13
1090592	Soil	13.9	33.6	15.3	287	0.4	52.3	6.5	140	2.94	128.0	16.4	2.2	36	1.3	11.0	0.9	115	0.11	0.087	16
1090593	Soil	12.0	31.5	15.3	211	0.5	42.4	5.0	99	2.47	82.1	11.1	1.0	25	1.1	7.4	0.5	89	0.05	0.087	12
1090594	Soil	8.2	13.3	7.4	54	0.5	11.1	1.6	32	0.96	17.6	2.5	0.1	9	0.2	2.2	0.1	64	0.03	0.027	13
1090595	Soil	11.7	12.5	17.5	77	0.4	15.2	2.0	26	1.25	31.7	5.1	0.4	16	0.2	5.7	0.2	103	<0.01	0.039	13
1090596	Soil	4.5	12.6	9.3	30	1.2	6.2	0.9	18	0.64	8.2	1.8	0.2	7	0.4	1.3	0.3	46	0.01	0.030	19
1090597	Soil	11.3	13.0	13.8	123	0.5	22.8	3.2	173	2.06	31.6	2.5	2.0	16	0.3	3.8	0.2	136	0.03	0.086	16
1090598	Soil	7.0	9.2	8.0	45	1.0	9.4	1.3	20	0.68	9.9	2.1	0.1	8	0.2	2.4	0.2	61	0.01	0.021	15
1090599	Soil	21.3	16.0	16.0	138	0.2	36.0	2.8	35	1.32	30.4	4.3	1.0	20	0.2	7.6	0.2	122	0.01	0.037	14
1090600	Soil	9.9	12.6	12.9	84	0.4	17.1	2.3	49	1.40	22.9	2.7	0.4	18	0.6	4.1	0.2	81	0.03	0.052	13
1091041	Soil	3.6	72.8	16.4	221	0.6	53.4	10.3	234	3.34	26.4	6.4	2.5	76	1.1	4.1	0.3	35	0.28	0.109	5
1091042	Soil	14.1	33.4	19.5	155	0.7	37.4	6.2	207	1.99	49.1	14.8	1.2	63	0.4	7.9	0.3	82	0.61	0.097	9
1091043	Soil	16.4	28.3	36.1	174	3.6	39.1	4.8	128	2.62	77.8	20.5	0.9	62	0.5	10.3	0.7	138	0.28	0.195	8
1091044	Soil	13.8	24.4	18.1	192	0.4	40.1	4.8	93	2.06	51.0	13.8	0.8	28	0.8	7.6	0.6	104	0.15	0.080	8
1091045	Soil	16.3	28.2	49.8	182	0.5	38.2	4.6	45	2.04	88.3	20.6	0.8	52	0.3	10.7	1.0	117	0.02	0.074	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090536	Soil	11	0.07	461	0.002	1	0.45	0.006	0.09	<0.1	0.11	3.9	0.2	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090537	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.4	18.7	8.6	44
1090538	Soil	8	0.04	302	0.006	2	0.45	0.016	0.04	<0.1	0.03	0.7	0.2	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090539	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	23.9	47.9	17.0	208
1090540	Soil	12	1.98	327	0.002	4	0.21	0.006	0.06	0.2	0.84	2.9	0.8	<0.05	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090581	Soil	20	0.03	81	0.003	3	0.34	0.007	0.06	0.3	0.06	0.3	0.6	<0.05	3	6.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090582	Soil	7	0.03	177	0.008	3	0.39	0.019	0.03	<0.1	0.14	0.4	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090583	Soil	11	0.03	208	0.004	2	0.50	0.006	0.03	0.2	0.06	0.2	0.5	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090584	Soil	14	0.06	238	0.003	3	0.81	0.003	0.03	0.2	0.06	0.9	0.7	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090585	Soil	7	0.02	154	0.003	3	0.56	0.002	0.03	<0.1	0.09	0.2	0.2	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090586	Soil	7	0.02	84	0.002	3	0.29	0.006	0.04	<0.1	0.06	0.7	0.2	<0.05	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090587	Soil	10	0.11	820	0.002	4	0.56	0.018	0.07	0.1	1.43	0.4	0.3	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090588	Soil	17	0.08	497	0.003	3	0.60	0.004	0.07	0.3	2.33	1.4	0.4	<0.05	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090589	Soil	6	0.02	442	0.004	1	0.35	0.013	0.03	<0.1	0.41	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090590	Soil	12	0.07	389	0.003	1	0.65	0.004	0.04	0.2	0.37	0.5	0.3	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090591	Soil	15	0.12	323	0.004	3	0.62	0.004	0.06	0.2	0.30	1.5	0.3	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090592	Soil	16	0.13	713	0.003	3	0.76	0.004	0.06	0.4	1.42	1.7	0.3	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090593	Soil	15	0.10	321	0.002	2	0.72	0.004	0.06	0.3	0.52	1.5	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090594	Soil	8	0.02	122	0.006	2	0.48	0.006	0.03	0.2	0.08	0.3	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090595	Soil	8	0.02	140	0.005	2	0.42	0.003	0.04	0.2	0.08	0.6	0.4	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090596	Soil	7	0.02	135	0.006	1	0.52	0.003	0.04	0.1	0.05	0.3	0.3	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090597	Soil	14	0.08	251	0.006	1	0.73	0.003	0.05	0.2	0.05	1.0	0.4	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090598	Soil	7	0.02	75	0.005	1	0.35	0.004	0.03	0.1	0.14	0.2	0.3	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090599	Soil	10	0.03	96	0.003	2	0.39	0.003	0.06	0.2	0.07	0.8	0.4	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090600	Soil	10	0.04	442	0.006	1	0.59	0.004	0.04	0.2	0.14	0.7	0.4	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091041	Soil	28	0.42	2128	0.001	3	1.03	0.003	0.06	<0.1	0.72	2.7	<0.1	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091042	Soil	13	0.09	931	0.004	1	0.70	0.009	0.05	0.2	1.21	1.5	0.4	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091043	Soil	24	0.04	929	0.003	1	0.68	0.005	0.06	0.4	2.02	1.5	0.6	<0.05	4	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091044	Soil	9	0.03	336	0.005	3	0.44	0.007	0.05	0.2	0.75	1.3	0.4	0.05	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091045	Soil	11	0.02	261	0.002	2	0.36	0.004	0.07	0.5	2.05	1.1	0.5	0.08	3	4.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090536	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090537	Soil	0.5	11.3	3.3	92	0.82	7.1	2.9	<0.1	17	0.4	0.8	0.2	26	0.11	0.073	2	6	0.04	287	0.003
1090538	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090539	Soil	0.6	64.7	9.1	242	1.64	39.6	10.5	1.0	90	1.8	3.9	0.2	56	2.31	0.086	6	11	0.72	452	0.001
1090540	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090581	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090582	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090583	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090584	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090585	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090586	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090587	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090588	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090589	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090590	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090591	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090592	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090593	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090594	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090595	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090596	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090597	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090598	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090599	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090600	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091041	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091042	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091043	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091044	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091045	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090536	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090537	Soil	<20	0.45	0.021	0.04	<0.1	0.05	0.2	0.2	0.07	2	0.5	<0.2
1090538	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090539	Soil	<20	0.33	0.011	0.07	<0.1	0.96	1.9	0.5	0.11	1	2.4	<0.2
1090540	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090581	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090582	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090583	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090584	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090585	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090586	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090587	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090588	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090589	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090590	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090591	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090592	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090593	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090594	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090595	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090596	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090597	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090598	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090599	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090600	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091041	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091042	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091043	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091044	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091045	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091046	Soil	16.8	35.0	63.2	177	0.9	38.7	4.9	87	2.90	117.5	38.5	1.6	71	0.4	14.8	0.8	126	0.04	0.094	10
1091047	Soil	9.2	15.3	15.2	91	<0.1	17.3	2.3	25	1.25	38.8	9.4	1.0	18	<0.1	6.9	0.2	93	0.01	0.031	11
1091048	Soil	5.0	27.8	15.3	191	1.2	44.2	7.4	233	2.62	45.9	10.4	1.4	57	2.6	4.7	0.3	63	0.58	0.175	12
1091049	Soil	4.5	38.6	15.8	199	1.7	42.8	10.2	365	3.49	83.3	26.7	1.3	57	1.5	6.2	0.4	57	0.61	0.150	9
1091050	Soil	8.1	15.9	9.1	77	0.1	15.3	3.0	38	1.20	25.4	4.3	0.4	20	<0.1	3.4	0.2	73	0.02	0.045	7
1091062	Soil	11.7	76.0	35.6	353	3.8	79.8	13.3	208	5.39	119.4	12.6	3.6	105	0.5	9.8	0.6	124	0.06	0.175	15
1091063	Soil	11.3	132.5	29.5	1061	1.4	221.3	34.9	342	11.85	82.2	7.8	5.8	45	0.9	11.7	0.5	36	0.05	0.160	17
1091064	Soil	4.6	35.6	32.6	170	1.2	32.5	6.4	103	3.73	34.0	7.2	0.7	40	0.1	4.0	0.4	54	0.03	0.088	9
1091065	Soil	6.6	34.7	11.5	176	1.6	42.7	6.8	113	2.05	18.3	4.7	0.4	26	0.5	3.6	0.3	40	0.28	0.097	13
1091066	Soil	54.3	37.9	7.6	1259	0.7	248.7	16.1	377	2.74	81.8	2.1	1.3	53	7.0	16.7	0.2	112	1.58	0.084	12
1091067	Soil	31.1	35.1	11.7	508	0.1	117.6	9.6	174	3.21	63.9	5.1	2.6	16	0.6	12.7	0.3	111	0.09	0.096	21
1091068	Soil	83.5	53.7	8.2	1001	0.5	252.1	13.2	164	3.36	45.3	2.6	2.1	6	7.1	11.6	0.2	102	0.02	0.050	15
1091069	Soil	23.0	17.0	8.2	285	0.3	64.2	4.4	47	1.99	43.8	2.6	0.8	6	0.2	10.7	0.2	146	0.01	0.037	16
1091070	Soil	97.0	131.1	18.7	966	3.2	167.4	6.8	84	3.99	99.8	13.2	0.6	38	2.0	44.5	0.4	803	0.03	0.116	19
1091071	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091073	Soil	125.5	343.2	18.5	1795	3.4	423.7	20.4	193	5.67	533.9	224.0	2.7	70	4.0	143.0	0.2	838	0.09	0.196	13
1091074	Soil	33.6	126.3	8.2	242	8.2	60.0	3.0	47	1.62	220.2	7.6	0.5	67	0.6	19.0	0.1	489	0.07	0.221	5
1091076	Soil	28.8	38.1	59.8	78	3.3	15.1	2.1	50	2.49	157.3	28.9	2.1	228	0.6	32.7	0.4	205	0.14	0.390	14
1091077	Soil	6.6	49.2	28.2	155	0.7	27.6	7.8	146	3.74	339.0	27.1	3.3	39	0.8	17.2	0.5	33	0.03	0.107	17
1091078	Soil	0.4	6.2	1.5	9	0.2	2.0	1.0	18	0.50	2.9	0.9	<0.1	6	0.1	0.2	<0.1	13	0.02	0.014	1
1091079	Soil	9.2	70.2	56.3	125	0.8	25.5	4.5	96	4.51	130.7	6.0	6.5	74	0.6	6.9	0.7	133	0.04	0.117	18
1091080	Soil	10.3	71.2	45.3	158	1.3	34.9	5.7	63	4.59	537.8	11.6	4.7	48	0.4	12.4	0.6	127	0.02	0.079	22
1091081	Soil	10.8	69.3	84.2	152	1.5	32.8	5.7	140	5.85	107.5	5.1	5.0	49	0.4	9.2	0.7	82	0.02	0.109	17
1091082	Soil	11.0	42.3	60.5	114	1.9	25.1	4.0	89	3.79	141.4	12.3	1.4	31	0.4	8.9	1.5	95	0.02	0.087	16
1091083	Soil	3.8	18.8	12.9	55	0.5	8.4	1.9	13	1.85	122.6	2.0	2.2	6	0.1	6.8	0.5	32	<0.01	0.043	29
1091084	Soil	2.5	19.4	8.7	34	1.1	6.3	1.4	18	1.21	87.8	0.9	0.4	8	0.4	2.7	0.7	25	0.02	0.038	18
1091085	Soil	7.9	59.9	25.9	85	1.1	18.6	3.8	45	2.69	240.1	6.8	1.1	23	0.4	8.3	1.4	61	0.01	0.062	19
1091086	Soil	3.7	29.4	11.2	69	0.5	16.8	5.3	44	2.41	141.2	1.3	1.6	13	0.2	4.3	1.3	44	0.02	0.060	23
1091087	Soil	5.7	30.9	17.8	52	0.9	10.5	2.5	42	1.47	70.5	4.6	0.8	12	0.4	4.8	1.0	55	0.01	0.034	22
1091088	Soil	2.1	23.6	15.6	22	1.9	4.6	1.3	18	0.79	49.7	27.1	0.1	16	0.2	3.1	1.7	17	0.02	0.042	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091046	Soil	18	0.04	307	0.002	6	0.56	0.006	0.07	0.6	3.78	1.6	0.8	0.08	4	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091047	Soil	8	0.01	216	0.001	2	0.31	0.004	0.04	0.3	0.67	0.7	0.2	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091048	Soil	24	0.06	545	0.002	2	0.97	0.006	0.06	0.1	1.05	2.6	0.3	0.06	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091049	Soil	21	0.09	783	0.002	2	1.02	0.007	0.06	0.2	1.57	2.5	0.3	0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091050	Soil	8	0.02	191	0.002	2	0.31	0.004	0.05	<0.1	0.16	0.4	0.2	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091062	Soil	19	0.11	1155	0.004	3	1.54	0.006	0.19	0.2	0.65	2.9	0.4	0.26	4	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091063	Soil	13	0.03	1603	0.003	2	2.03	0.003	0.09	0.1	0.31	8.7	0.2	0.07	1	3.0	0.3	N.A.	N.A.	N.A.	N.A.
1091064	Soil	9	0.03	1081	0.007	3	0.57	0.011	0.25	0.1	0.28	1.2	0.4	0.48	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091065	Soil	8	0.09	998	0.003	3	0.64	0.014	0.05	<0.1	0.30	0.9	0.2	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091066	Soil	19	0.67	487	0.003	3	0.48	0.011	0.04	0.3	2.01	3.7	0.8	0.06	1	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091067	Soil	15	0.07	220	0.002	3	0.63	0.002	0.06	0.2	0.64	1.8	0.6	<0.05	2	6.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091068	Soil	18	0.04	393	0.002	3	0.54	0.002	0.05	0.4	0.32	2.5	3.7	0.06	<1	9.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091069	Soil	9	0.03	90	0.006	2	0.41	0.002	0.04	0.2	0.10	0.6	0.4	<0.05	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091070	Soil	50	0.08	386	0.005	4	0.85	0.003	0.09	0.5	3.45	1.3	3.0	<0.05	4	26.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091071	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	110.0	198.9	11.6	8078
1091073	Soil	45	0.09	1100	0.003	4	1.95	0.002	0.09	0.8	>50	3.8	4.3	<0.05	3	30.5	0.8	N.A.	N.A.	N.A.	N.A.
1091074	Soil	27	0.05	520	0.010	1	1.27	0.016	0.05	0.2	3.07	1.7	1.1	0.07	2	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091076	Soil	27	0.01	724	0.005	6	0.47	0.004	0.12	0.5	7.91	3.3	1.5	0.24	2	13.5	0.3	N.A.	N.A.	N.A.	N.A.
1091077	Soil	10	0.08	239	0.002	2	0.46	0.003	0.07	0.2	3.26	2.9	0.5	0.08	1	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091078	Soil	2	0.02	22	0.016	<1	0.27	0.021	0.02	<0.1	0.16	0.3	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091079	Soil	29	0.08	159	0.003	<1	0.95	0.005	0.07	0.1	0.41	2.9	0.4	0.10	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091080	Soil	19	0.03	135	0.003	1	0.70	0.002	0.05	0.2	0.36	2.0	0.3	0.05	4	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091081	Soil	26	0.13	188	0.005	2	1.17	0.004	0.07	0.2	0.80	3.2	0.4	0.07	4	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091082	Soil	15	0.07	147	0.006	2	0.76	0.005	0.06	0.3	0.76	1.2	0.3	<0.05	4	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091083	Soil	6	0.01	47	0.002	1	0.41	0.002	0.03	<0.1	0.10	0.6	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091084	Soil	5	0.02	42	0.004	<1	0.39	0.008	0.03	0.2	0.09	0.4	<0.1	<0.05	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091085	Soil	11	0.04	128	0.005	1	0.59	0.004	0.04	0.2	0.96	1.0	0.2	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091086	Soil	8	0.03	80	0.004	<1	0.49	0.008	0.04	0.2	0.25	0.7	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091087	Soil	11	0.05	86	0.007	<1	0.75	0.003	0.03	0.3	1.87	0.7	0.2	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091088	Soil	4	0.02	77	0.007	<1	0.39	0.014	0.03	0.3	2.27	0.3	0.2	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091046	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091047	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091048	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091049	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091050	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091062	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091063	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091064	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091065	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091066	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091067	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091068	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091069	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091070	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091071	Soil		1.4	509.6	29.2	440	6.54	250.3	12.3	2.6	58	194.3	15.2	0.2	170	0.70	0.134	8	36	0.11	862	0.002
1091073	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091074	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091076	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091077	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091078	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091079	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091080	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091081	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091082	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091083	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091084	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091085	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091086	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091087	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091088	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091046	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091047	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091048	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091049	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091050	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091062	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091063	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091071	Soil	<20	1.38	0.004	0.08	0.4	3.82	8.8	4.5	0.09	1	15.2	<0.2
1091073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091081	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091085	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091087	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091089	Soil	4.2	38.9	23.2	221	0.8	42.6	12.0	87	4.12	346.0	8.2	4.8	28	0.5	7.8	1.2	39	<0.01	0.061	27
1091090	Soil	2.6	13.7	9.0	29	0.8	4.0	1.0	15	0.71	27.8	0.9	0.2	6	<0.1	1.9	0.2	20	0.02	0.033	8
1091091	Soil	10.0	55.0	39.4	123	1.3	24.7	6.1	162	3.42	227.0	17.4	4.2	45	0.3	9.9	1.1	60	0.06	0.094	17
1091092	Soil	4.3	11.1	10.5	29	0.9	6.0	1.3	19	0.65	30.3	5.1	0.3	13	0.3	3.1	0.4	29	0.03	0.050	6
1091093	Soil	13.3	28.6	27.6	62	1.8	10.1	1.3	20	1.45	65.8	11.4	1.2	32	0.6	13.0	0.4	66	0.02	0.072	9
1091094	Soil	12.3	35.0	23.7	68	1.1	12.0	1.9	26	1.41	112.3	9.2	1.0	60	0.4	10.3	0.3	57	0.03	0.058	14
1091095	Soil	9.8	40.6	27.7	67	1.2	13.0	2.1	32	1.37	101.9	29.1	1.1	42	0.4	11.1	0.4	43	0.04	0.064	12
1091096	Soil	3.9	30.6	16.0	55	1.2	11.6	1.7	24	0.77	32.2	17.4	0.7	29	0.4	3.6	0.4	36	0.05	0.065	6
1091097	Soil	17.3	59.7	86.6	155	2.6	20.6	4.3	68	5.26	955.8	191.5	4.1	86	0.5	53.7	3.8	69	0.04	0.173	22
1091098	Soil	17.0	80.3	75.1	137	2.6	22.1	3.9	68	3.63	590.0	164.8	4.2	81	0.9	39.6	2.6	65	0.04	0.149	21
1091099	Soil	7.8	47.6	20.4	121	2.7	28.7	4.5	75	2.26	88.0	19.9	1.4	32	0.7	14.5	0.4	33	0.03	0.093	7
1091100	Soil	7.6	50.9	28.6	132	1.5	30.4	5.4	84	2.48	134.6	36.5	1.5	41	0.7	25.9	0.7	38	0.07	0.076	10
1091101	Soil	15.5	97.5	17.3	214	7.6	47.6	5.3	46	3.94	32.8	7.3	1.5	75	0.3	2.8	0.2	49	0.02	0.097	4
1091102	Soil	13.7	57.4	15.4	85	4.3	20.5	3.0	33	2.67	27.9	5.7	0.7	27	0.1	2.0	0.2	62	0.01	0.061	3
1091103	Soil	12.0	113.7	24.7	350	3.5	129.4	15.7	146	5.13	23.6	8.8	2.4	114	0.7	2.8	0.3	41	0.05	0.135	6
1091104	Soil	8.5	65.9	20.3	226	2.1	83.3	13.6	313	4.11	19.4	6.4	1.5	48	0.7	2.1	0.3	48	0.10	0.107	6
1091105	Soil	2.8	33.7	12.5	113	2.2	42.4	6.8	181	2.10	23.5	15.3	0.9	67	0.6	1.9	0.2	24	0.41	0.096	6
1091106	Soil	3.3	43.6	15.2	139	1.5	46.5	9.6	205	2.41	56.0	21.1	1.1	109	0.6	3.7	0.3	22	0.27	0.100	5
1091107	Soil	3.6	39.5	17.2	120	0.6	38.0	8.5	150	3.20	30.5	4.6	1.3	29	0.2	2.4	0.3	34	0.03	0.059	4
1091108	Soil	3.4	38.7	14.6	136	1.6	52.2	7.6	91	2.58	29.5	8.2	0.7	51	0.6	1.7	0.2	23	0.12	0.099	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091089	Soil	14	0.21	77	0.002	<1	0.73	0.004	0.05	0.2	0.56	2.0	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091090	Soil	4	0.01	45	0.004	<1	0.25	0.011	0.02	<0.1	0.14	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091091	Soil	23	0.26	191	0.006	2	0.93	0.007	0.06	0.3	2.42	2.0	0.4	<0.05	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091092	Soil	5	0.02	104	0.007	1	0.27	0.013	0.03	0.1	0.60	0.6	0.3	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091093	Soil	7	0.02	196	0.003	2	0.37	0.007	0.06	0.1	0.87	1.3	0.6	<0.05	1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091094	Soil	7	0.02	184	0.002	2	0.30	0.008	0.05	0.1	0.93	1.1	0.7	0.06	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091095	Soil	8	0.03	187	0.003	2	0.37	0.008	0.06	0.2	1.15	1.2	0.5	<0.05	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091096	Soil	8	0.04	184	0.003	3	0.47	0.012	0.06	0.1	0.82	1.1	0.5	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091097	Soil	16	0.10	303	0.004	3	0.62	0.011	0.17	2.1	20.52	1.5	3.0	0.37	3	12.9	0.3	N.A.	N.A.	N.A.	N.A.
1091098	Soil	14	0.07	240	0.003	3	0.55	0.007	0.13	1.3	18.11	1.6	2.3	0.28	2	9.1	0.3	N.A.	N.A.	N.A.	N.A.
1091099	Soil	15	0.05	339	0.001	2	0.45	0.003	0.07	0.1	3.77	2.2	0.3	0.06	1	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091100	Soil	15	0.07	456	0.001	2	0.44	0.003	0.08	0.2	10.57	2.1	0.4	0.10	1	7.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091101	Soil	52	0.02	694	0.002	7	0.77	0.005	0.11	<0.1	0.45	4.8	0.2	0.16	2	11.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091102	Soil	39	0.02	607	0.002	4	0.63	0.004	0.08	<0.1	0.29	1.6	0.1	<0.05	3	7.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091103	Soil	35	0.13	517	0.002	2	1.20	0.005	0.09	<0.1	0.57	4.9	0.2	0.10	2	6.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091104	Soil	34	0.12	634	0.004	4	1.01	0.005	0.07	<0.1	0.22	3.4	0.2	<0.05	3	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091105	Soil	18	0.06	839	0.001	2	0.75	0.006	0.05	<0.1	0.80	2.4	0.1	0.08	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091106	Soil	17	0.04	556	0.002	3	0.76	0.007	0.07	0.1	1.36	2.4	0.2	0.10	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091107	Soil	21	0.09	226	0.002	4	0.76	0.004	0.05	<0.1	0.18	2.5	0.2	<0.05	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091108	Soil	17	0.04	528	0.002	3	0.59	0.004	0.05	<0.1	0.29	2.0	0.1	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

CERTIFICATE OF ANALYSIS WHI11000627.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1090282	Soil	17.9	60.0	22.6	290	1.0	68.6	10.5	132	3.23	154.7	7.7	0.9	49	0.7	8.6	0.3	83	0.18	0.176	14
REP 1090282	QC	17.3	59.3	23.1	285	1.1	69.2	10.6	136	3.20	155.9	10.1	1.2	48	0.6	8.6	0.3	82	0.17	0.181	14
1090288	Soil	6.2	17.3	10.7	49	0.7	15.1	1.4	12	0.49	11.9	10.5	0.5	28	0.7	5.2	<0.1	46	0.08	0.047	7
REP 1090288	QC	6.1	17.3	10.4	49	0.7	15.8	1.5	12	0.49	12.2	9.8	0.5	29	0.7	5.2	<0.1	49	0.09	0.049	7
1090321	Soil	10.2	13.3	8.3	64	0.8	9.7	3.5	44	1.38	21.2	1.5	<0.1	10	0.1	2.8	0.1	49	<0.01	0.045	5
REP 1090321	QC	10.0	13.1	8.8	64	0.7	9.9	3.5	45	1.38	19.8	0.6	0.2	11	<0.1	3.0	0.1	50	<0.01	0.051	5
1090339	Soil	7.0	99.7	26.1	360	0.6	84.0	26.6	438	5.37	90.8	3.3	0.7	41	1.0	5.3	0.5	50	0.01	0.109	5
REP 1090339	QC	6.6	96.6	25.5	347	0.6	79.8	25.6	417	5.08	84.1	3.5	0.9	40	1.0	5.3	0.4	46	0.01	0.108	5
1090348	Soil	9.7	15.0	23.2	39	2.6	7.4	1.6	34	0.90	16.3	7.8	0.6	19	0.2	2.8	0.2	27	0.02	0.055	3
REP 1090348	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090353	Soil	7.5	77.4	16.2	325	0.3	77.0	23.8	354	7.12	504.9	3.3	2.7	14	0.1	8.4	<0.1	17	0.02	0.100	40
REP 1090353	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090354	Soil	8.3	35.5	41.0	170	0.6	34.2	10.6	60	2.80	72.5	2.4	1.2	84	0.2	9.3	0.5	45	0.02	0.136	30
REP 1090354	QC	8.3	35.3	40.4	173	0.6	34.1	10.8	61	2.77	71.8	2.9	1.3	85	0.2	9.2	0.5	44	0.02	0.134	27
1090378	Soil	3.3	13.5	21.1	8	1.1	3.6	0.3	5	0.26	11.5	31.5	0.9	33	<0.1	13.9	0.2	35	0.01	0.016	3
REP 1090378	QC	3.4	13.5	20.4	8	1.1	3.5	0.2	5	0.26	11.5	32.7	0.9	34	<0.1	14.3	0.2	34	0.01	0.016	3
1090390	Soil	8.2	36.2	16.5	165	0.6	35.5	4.2	73	1.81	25.2	6.9	1.6	51	0.7	3.8	0.3	63	0.16	0.092	10
REP 1090390	QC	7.9	35.8	16.0	163	0.5	34.1	4.1	68	1.79	24.8	8.3	1.5	53	0.7	3.7	0.3	58	0.15	0.082	9
1090424	Soil	11.2	18.5	25.4	68	0.4	15.8	3.8	80	1.69	30.1	6.1	0.1	57	0.1	5.9	0.2	67	0.03	0.061	6
REP 1090424	QC	10.7	18.8	26.3	68	0.4	15.3	3.6	76	1.65	30.1	5.4	0.1	55	0.2	6.0	0.3	65	0.02	0.059	6
1090481	Soil	12.3	28.6	44.1	86	0.8	18.7	3.5	91	1.89	60.0	21.6	2.5	63	0.2	11.7	0.3	67	0.05	0.075	7
REP 1090481	QC	12.1	29.2	46.3	89	0.8	19.2	3.7	96	1.97	61.1	20.0	2.4	58	0.3	11.7	0.3	64	0.04	0.076	6
1090489	Soil	3.7	32.2	43.3	149	0.5	36.9	12.7	260	2.65	89.0	31.1	1.4	51	0.9	6.5	0.3	32	0.03	0.052	3
REP 1090489	QC	3.4	32.1	44.9	148	0.6	37.0	12.3	245	2.65	85.8	32.0	1.4	51	0.9	6.1	0.3	32	0.03	0.052	3
1090504	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1090504	QC																				
1090510	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1090510	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1090282	Soil	15	0.09	905	0.004	4	0.66	0.003	0.09	0.1	0.40	1.5	0.5	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090282	QC	15	0.09	885	0.004	3	0.65	0.004	0.09	0.1	0.36	1.5	0.5	0.05	2	3.1	<0.2				
1090288	Soil	7	0.02	258	0.004	1	0.21	0.009	0.03	0.2	1.73	0.9	0.5	<0.05	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090288	QC	7	0.02	263	0.004	1	0.22	0.010	0.04	0.2	1.74	0.9	0.5	<0.05	1	2.4	<0.2				
1090321	Soil	7	0.01	99	0.002	2	0.23	0.005	0.03	0.2	0.09	0.3	0.1	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090321	QC	8	0.01	107	0.007	2	0.23	0.006	0.04	0.2	0.09	0.6	<0.1	<0.05	2	1.7	<0.2				
1090339	Soil	15	0.03	215	0.003	2	0.49	0.003	0.06	<0.1	0.14	5.2	0.3	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090339	QC	16	0.03	216	0.004	2	0.48	0.003	0.07	<0.1	0.15	5.6	0.3	<0.05	2	1.4	<0.2				
1090348	Soil	5	0.01	91	0.003	5	0.23	0.006	0.06	<0.1	1.58	1.1	0.5	0.08	1	1.8	0.2	N.A.	N.A.	N.A.	N.A.
REP 1090348	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1090353	Soil	7	0.05	213	0.010	<1	0.49	0.009	0.18	<0.1	0.20	3.9	<0.1	0.33	1	3.2	0.6	N.A.	N.A.	N.A.	N.A.
REP 1090353	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1090354	Soil	6	0.02	720	0.003	1	0.31	0.004	0.15	<0.1	0.12	1.1	0.4	0.32	1	8.9	0.3	N.A.	N.A.	N.A.	N.A.
REP 1090354	QC	6	0.01	696	0.003	1	0.30	0.004	0.16	<0.1	0.12	1.1	0.5	0.36	1	8.8	0.5				
1090378	Soil	6	<0.01	421	<0.001	2	0.16	0.001	0.05	<0.1	5.89	0.7	0.5	0.09	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090378	QC	6	<0.01	432	<0.001	2	0.16	0.001	0.06	<0.1	5.88	0.6	0.5	0.09	1	1.8	<0.2				
1090390	Soil	13	0.09	2071	0.003	2	0.50	0.002	0.06	<0.1	1.30	3.2	0.3	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090390	QC	12	0.08	2021	0.002	4	0.47	0.002	0.06	<0.1	1.33	3.1	0.3	<0.05	2	1.5	<0.2				
1090424	Soil	9	0.05	839	0.006	1	0.39	0.003	0.07	0.1	0.43	0.4	0.4	0.13	3	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090424	QC	12	0.05	808	0.006	1	0.39	0.003	0.06	0.1	0.36	0.4	0.4	0.14	2	3.3	<0.2				
1090481	Soil	15	0.08	718	0.008	2	0.45	0.003	0.12	<0.1	3.65	2.4	0.5	0.17	2	8.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090481	QC	15	0.08	665	0.007	2	0.42	0.003	0.11	0.1	3.54	2.3	0.5	0.19	2	7.7	0.2				
1090489	Soil	8	0.03	602	<0.001	<1	0.31	0.002	0.05	<0.1	1.42	3.6	0.3	0.06	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090489	QC	8	0.03	609	<0.001	<1	0.32	0.002	0.05	<0.1	1.42	3.8	0.4	0.05	<1	2.5	<0.2				
1090504	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.1	19.5	6.9	53
REP 1090504	QC																	1.2	19.1	6.3	48
1090510	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.8	30.2	5.4	91
REP 1090510	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1090282	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090282	QC																					
1090288	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090288	QC																					
1090321	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090321	QC																					
1090339	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090339	QC																					
1090348	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090348	QC																					
1090353	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090353	QC																					
1090354	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090354	QC																					
1090378	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090378	QC																					
1090390	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090390	QC																					
1090424	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090424	QC																					
1090481	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090481	QC																					
1090489	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090489	QC																					
1090504	Soil		0.3	14.1	2.7	245	0.69	12.4	8.1	0.2	81	1.3	1.7	0.2	12	2.82	0.108	3	8	0.06	632	0.004
REP 1090504	QC		0.3	12.9	2.6	234	0.61	11.2	7.3	0.1	80	1.1	1.6	0.1	11	2.76	0.105	3	7	0.05	598	0.004
1090510	Soil		0.2	24.3	2.8	305	0.55	8.3	6.1	0.2	131	1.1	2.6	0.1	13	3.11	0.097	3	20	0.08	618	0.006
REP 1090510	QC																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1090282	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090282	QC													
1090288	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090288	QC													
1090321	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090321	QC													
1090339	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090339	QC													
1090348	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090348	QC													
1090353	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090353	QC													
1090354	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090354	QC													
1090378	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090378	QC													
1090390	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090390	QC													
1090424	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090424	QC													
1090481	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090481	QC													
1090489	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090489	QC													
1090504	Soil		<20	0.43	0.023	0.02	0.1	0.49	0.5	<0.1	0.22	1	0.9	<0.2
REP 1090504	QC		<20	0.40	0.021	0.02	0.2	0.45	0.5	<0.1	0.23	1	1.6	<0.2
1090510	Soil		<20	0.41	0.017	0.02	0.2	0.29	0.4	<0.1	0.22	<1	2.2	<0.2
REP 1090510	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		1DX30 Mo ppm 0.1	1DX30 Cu ppm 0.1	1DX30 Pb ppm 0.1	1DX30 Zn ppm 1	1DX30 Ag ppm 0.1	1DX30 Ni ppm 0.1	1DX30 Co ppm 0.1	1DX30 Mn ppm 1	1DX30 Fe % 0.01	1DX30 As ppm 0.5	1DX30 Au ppb 0.5	1DX30 Th ppm 0.1	1DX30 Sr ppm 1	1DX30 Cd ppm 0.1	1DX30 Sb ppm 0.1	1DX30 Bi ppm 0.1	1DX30 V ppm 2	1DX30 Ca % 0.01	1DX30 P % 0.001	1DX30 La ppm 1
1090552	Soil	6.1	32.9	17.3	149	1.0	25.0	13.6	543	2.12	49.9	14.9	1.8	25	1.2	4.2	0.3	49	0.18	0.081	6
REP 1090552	QC	6.1	30.0	15.6	134	0.9	24.2	12.6	526	2.00	50.7	13.9	1.7	24	1.4	4.2	0.2	45	0.17	0.078	6
1090564	Soil	8.5	19.5	17.1	619	1.1	77.2	2.3	108	0.88	20.9	5.2	0.2	40	12.5	5.9	<0.1	76	0.34	0.064	3
REP 1090564	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090535	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1090535	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090594	Soil	8.2	13.3	7.4	54	0.5	11.1	1.6	32	0.96	17.6	2.5	0.1	9	0.2	2.2	0.1	64	0.03	0.027	13
REP 1090594	QC	7.5	12.6	7.2	51	0.5	11.1	1.6	33	0.96	17.1	4.1	<0.1	10	0.2	2.3	0.2	66	0.03	0.025	13
1091041	Soil	3.6	72.8	16.4	221	0.6	53.4	10.3	234	3.34	26.4	6.4	2.5	76	1.1	4.1	0.3	35	0.28	0.109	5
REP 1091041	QC	3.5	73.1	16.1	221	0.5	54.7	10.0	233	3.39	26.4	6.3	2.5	75	1.1	4.3	0.3	33	0.27	0.107	5
1091083	Soil	3.8	18.8	12.9	55	0.5	8.4	1.9	13	1.85	122.6	2.0	2.2	6	0.1	6.8	0.5	32	<0.01	0.043	29
REP 1091083	QC	3.5	19.1	12.9	54	0.5	9.2	2.1	13	1.88	127.0	1.4	2.3	6	0.1	6.5	0.5	34	<0.01	0.043	30
1091090	Soil	2.6	13.7	9.0	29	0.8	4.0	1.0	15	0.71	27.8	0.9	0.2	6	<0.1	1.9	0.2	20	0.02	0.033	8
REP 1091090	QC	2.8	14.3	9.5	29	0.8	4.7	1.2	16	0.76	29.3	1.9	0.1	7	<0.1	1.9	0.2	25	0.02	0.035	9
Reference Materials																					
STD DS8	Standard	11.8	100.2	117.9	286	1.6	35.6	6.8	565	2.33	24.1	105.8	5.9	64	2.3	4.4	6.7	31	0.62	0.068	12
STD DS8	Standard	12.3	108.1	121.6	309	1.7	36.9	7.5	575	2.40	25.2	121.7	6.4	77	2.2	5.6	7.0	39	0.64	0.073	13
STD DS8	Standard	11.4	111.5	123.1	296	1.8	39.4	7.6	565	2.39	26.0	113.1	6.2	59	2.2	5.1	6.0	40	0.68	0.079	12
STD DS8	Standard	11.8	109.2	119.9	304	1.8	38.2	7.3	583	2.37	26.5	110.6	5.8	58	2.2	5.0	5.7	39	0.64	0.077	11
STD DS8	Standard	11.9	106.0	127.3	311	1.9	36.8	7.5	604	2.42	27.0	111.3	6.6	62	2.5	5.7	6.7	41	0.66	0.082	13
STD DS8	Standard	12.9	102.3	125.6	290	1.8	36.3	7.1	572	2.30	24.2	111.2	7.1	62	2.3	5.6	6.6	40	0.64	0.078	14
STD DS8	Standard	13.9	113.9	127.5	309	1.7	38.9	7.8	614	2.46	28.6	104.3	6.8	62	2.3	5.8	6.7	44	0.66	0.079	14
STD DS8	Standard	13.1	106.9	120.3	289	1.6	36.3	7.2	575	2.29	26.6	97.0	6.4	58	2.1	5.4	6.3	42	0.62	0.073	13
STD DS8	Standard	13.2	112.9	125.4	319	1.9	38.2	7.6	610	2.48	26.0	120.2	6.8	62	2.4	5.2	6.1	43	0.73	0.083	14
STD DS8	Standard	13.5	112.9	118.6	319	1.8	39.0	7.9	629	2.49	26.2	113.8	6.3	60	2.1	5.0	5.7	43	0.68	0.077	14
STD DS8	Standard	14.3	126.0	134.7	339	1.9	43.1	8.7	661	2.62	28.8	120.4	7.5	71	2.5	6.7	7.0	46	0.72	0.084	15
STD DS8	Standard	13.3	117.1	129.1	312	1.8	41.2	8.1	603	2.43	27.4	119.7	7.1	66	2.3	6.1	6.8	44	0.68	0.078	15
STD DS8	Standard	12.9	104.9	118.6	319	1.9	39.0	7.3	611	2.45	26.7	113.5	6.3	80	2.2	6.4	7.0	44	0.73	0.084	14
STD DS8	Standard	14.0	114.5	137.5	344	2.0	39.9	8.0	670	2.66	30.1	120.3	7.2	85	2.4	7.1	8.0	45	0.75	0.086	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		1DX30 Cr ppm 1	1DX30 Mg % 0.01	1DX30 Ba ppm 1	1DX30 Ti % 0.001	1DX30 B ppm 1	1DX30 Al % 0.01	1DX30 Na % 0.001	1DX30 K % 0.01	1DX30 W ppm 0.1	1DX30 Hg ppm 0.01	1DX30 Sc ppm 0.1	1DX30 Tl ppm 0.1	1DX30 S % 0.05	1DX30 Ga ppm 1	1DX30 Se ppm 0.5	1DX30 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1090552	Soil	18	0.11	607	0.004	3	0.65	0.007	0.06	0.3	1.45	2.1	0.2	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090552	QC	18	0.10	567	0.002	3	0.61	0.007	0.06	0.2	1.49	2.0	0.2	<0.05	2	2.6	0.2				
1090564	Soil	9	0.05	485	0.008	4	0.53	0.022	0.05	0.2	0.62	0.8	0.8	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090564	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1090535	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.8	73.9	26.9	226
REP 1090535	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1090594	Soil	8	0.02	122	0.006	2	0.48	0.006	0.03	0.2	0.08	0.3	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090594	QC	8	0.03	124	0.007	2	0.52	0.007	0.03	0.2	0.05	0.4	0.2	<0.05	2	1.3	<0.2				
1091041	Soil	28	0.42	2128	0.001	3	1.03	0.003	0.06	<0.1	0.72	2.7	<0.1	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091041	QC	28	0.41	2197	0.001	4	1.02	0.003	0.06	<0.1	0.75	2.6	<0.1	<0.05	3	3.6	<0.2				
1091083	Soil	6	0.01	47	0.002	1	0.41	0.002	0.03	<0.1	0.10	0.6	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091083	QC	6	0.01	49	0.002	<1	0.42	0.003	0.04	<0.1	0.13	0.6	0.1	<0.05	2	<0.5	<0.2				
1091090	Soil	4	0.01	45	0.004	<1	0.25	0.011	0.02	<0.1	0.14	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091090	QC	5	0.02	51	0.004	<1	0.28	0.013	0.02	<0.1	0.15	0.3	<0.1	<0.05	1	<0.5	<0.2				
Reference Materials																					
STD DS8	Standard	110	0.55	243	0.102	3	0.82	0.068	0.41	2.7	0.17	2.0	5.0	0.07	4	5.1	4.5				
STD DS8	Standard	115	0.57	268	0.106	2	0.96	0.070	0.46	2.8	0.22	2.2	5.3	0.11	5	5.7	5.1				
STD DS8	Standard	115	0.57	243	0.099	4	0.86	0.101	0.41	3.0	0.21	3.0	5.2	0.12	4	5.5	4.3				
STD DS8	Standard	113	0.57	233	0.096	2	0.84	0.100	0.40	2.6	0.18	3.0	5.2	0.10	4	5.3	5.0				
STD DS8	Standard	116	0.60	266	0.111	3	0.87	0.082	0.42	2.9	0.22	2.0	5.4	0.15	5	5.3	4.8				
STD DS8	Standard	110	0.59	270	0.116	2	0.84	0.080	0.39	3.0	0.25	2.1	5.2	0.12	4	4.9	5.1				
STD DS8	Standard	119	0.60	280	0.121	2	0.89	0.081	0.40	3.0	0.21	2.2	5.2	0.20	4	5.3	5.1				
STD DS8	Standard	112	0.57	259	0.115	2	0.83	0.076	0.37	2.8	0.23	2.1	4.9	0.19	4	5.0	4.7				
STD DS8	Standard	117	0.63	281	0.117	3	0.94	0.093	0.44	3.2	0.17	2.3	5.5	0.19	5	5.6	5.5				
STD DS8	Standard	117	0.59	273	0.112	3	0.86	0.084	0.42	2.8	0.17	2.1	5.1	0.15	5	5.8	4.9				
STD DS8	Standard	133	0.65	285	0.143	3	0.93	0.089	0.43	3.2	0.30	2.4	5.5	0.19	5	5.6	5.0				
STD DS8	Standard	125	0.60	267	0.133	2	0.89	0.081	0.40	2.9	0.22	2.2	5.4	0.18	5	5.2	4.8				
STD DS8	Standard	119	0.68	280	0.111	3	0.91	0.096	0.45	3.1	0.17	2.4	5.3	0.16	5	5.9	4.9				
STD DS8	Standard	128	0.73	290	0.118	3	0.98	0.105	0.46	3.0	0.21	2.2	5.6	0.10	5	6.7	5.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1090552	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090552	QC																				
1090564	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090564	QC																				
1090535	Soil	1.5	46.5	19.6	549	2.47	19.8	9.3	1.0	34	0.6	2.0	0.4	27	0.53	0.069	5	9	0.11	637	0.001
REP 1090535	QC																				
1090594	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090594	QC																				
1091041	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091041	QC																				
1091083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091083	QC																				
1091090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091090	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1090552	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090552	QC												
1090564	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090564	QC												
1090535	Soil	<20	0.48	0.009	0.08	<0.1	0.17	3.7	0.3	0.05	2	2.0	<0.2
REP 1090535	QC												
1090594	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090594	QC												
1091041	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091041	QC												
1091083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091083	QC												
1091090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091090	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		1DX30 Mo ppm 0.1	1DX30 Cu ppm 0.1	1DX30 Pb ppm 0.1	1DX30 Zn ppm 1	1DX30 Ag ppm 0.1	1DX30 Ni ppm 0.1	1DX30 Co ppm 0.1	1DX30 Mn ppm 1	1DX30 Fe % 0.01	1DX30 As ppm 0.5	1DX30 Au ppb 0.5	1DX30 Th ppm 0.1	1DX30 Sr ppm 1	1DX30 Cd ppm 0.1	1DX30 Sb ppm 0.1	1DX30 Bi ppm 0.1	1DX30 V ppm 2	1DX30 Ca % 0.01	1DX30 P % 0.001	1DX30 La ppm 1
STD DS8	Standard	13.7	107.4	127.3	330	2.0	40.0	7.6	625	2.62	28.3	126.1	6.5	81	2.3	7.1	7.9	43	0.72	0.086	14
STD DS8	Standard	13.0	107.2	137.8	305	1.8	37.7	7.4	616	2.42	24.6	104.3	6.5	74	2.1	5.9	6.7	41	0.67	0.072	15
STD DS8	Standard	12.3	106.0	134.0	300	1.8	37.8	7.2	588	2.35	25.1	104.3	6.4	70	2.1	6.0	7.1	39	0.66	0.075	14
STD DS8	Standard	14.1	119.5	123.7	316	1.8	40.9	7.9	614	2.47	27.9	114.1	6.6	64	2.5	5.6	6.7	49	0.72	0.082	14
STD DS8	Standard	14.0	121.3	123.7	323	1.9	41.8	8.2	607	2.52	28.6	112.8	6.9	64	2.5	5.7	6.7	48	0.69	0.085	14
STD DS8	Standard	11.8	103.4	121.6	301	1.8	37.4	7.0	576	2.36	25.7	98.1	6.0	59	2.2	5.1	5.9	39	0.63	0.077	12
STD DS8	Standard	12.0	103.6	124.7	301	1.7	36.8	7.2	582	2.38	25.6	105.0	6.1	58	2.3	4.9	6.2	41	0.62	0.082	12
STD DS8	Standard	13.2	111.4	125.8	311	1.7	38.1	7.6	585	2.40	26.0	102.0	6.9	55	2.2	4.5	5.3	44	0.67	0.078	13
STD DS8	Standard	12.8	113.7	127.3	313	1.8	39.3	7.9	612	2.45	26.0	109.6	6.7	53	2.4	4.7	5.6	45	0.68	0.078	13
STD DS8	Standard	11.6	113.0	125.1	319	2.0	38.0	7.6	588	2.42	26.6	106.7	6.0	55	2.4	4.5	5.5	39	0.65	0.081	11
STD DS8	Standard	11.8	110.5	125.8	314	1.9	37.6	7.2	550	2.32	24.4	100.2	6.3	57	2.3	4.5	5.3	39	0.64	0.076	11
STD DS8	Standard	13.5	117.1	122.9	312	1.7	38.6	8.1	602	2.37	26.2	114.0	6.7	66	2.4	4.0	6.2	44	0.69	0.081	15
STD DS8	Standard	14.1	118.1	119.1	315	1.7	38.3	8.0	612	2.47	27.2	102.8	6.3	63	2.6	4.4	6.0	45	0.67	0.078	15
STD DS8	Standard	14.1	119.5	123.7	316	1.8	40.9	7.9	614	2.47	27.9	114.1	6.6	64	2.5	5.6	6.7	49	0.72	0.082	14
STD DS8	Standard	14.0	121.3	123.7	323	1.9	41.8	8.2	607	2.52	28.6	112.8	6.9	64	2.5	5.7	6.7	48	0.69	0.085	14
STD DS8	Standard	12.9	104.9	118.6	319	1.9	39.0	7.3	611	2.45	26.7	113.5	6.3	80	2.2	6.4	7.0	44	0.73	0.084	14
STD DS8	Standard	12.3	97.1	122.6	292	1.7	34.2	6.9	571	2.37	23.2	107.5	6.4	72	2.1	6.1	7.2	42	0.65	0.076	14
STD DS8	Standard																				
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		1DX30 Cr ppm 1	1DX30 Mg % 0.01	1DX30 Ba ppm 1	1DX30 Ti % 0.001	1DX30 B ppm 1	1DX30 Al % 0.01	1DX30 Na % 0.001	1DX30 K % 0.01	1DX30 W ppm 0.1	1DX30 Hg ppm 0.01	1DX30 Sc ppm 0.1	1DX30 Tl ppm 0.1	1DX30 S % 0.05	1DX30 Ga ppm 1	1DX30 Se ppm 0.5	1DX30 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
STD DS8	Standard	121	0.70	290	0.113	3	0.90	0.095	0.44	3.1	0.23	2.3	5.4	0.15	5	5.9	5.5				
STD DS8	Standard	112	0.61	277	0.128	2	0.89	0.090	0.39	2.8	0.18	2.0	5.4	0.11	4	5.3	5.1				
STD DS8	Standard	108	0.60	270	0.122	2	0.88	0.082	0.40	2.9	0.20	1.9	5.4	0.14	4	5.6	4.5				
STD DS8	Standard	131	0.61	287	0.126	2	0.87	0.083	0.43	3.1	0.22	2.4	5.4	0.17	5	5.1	5.1				
STD DS8	Standard	125	0.62	290	0.126	3	0.88	0.082	0.42	3.1	0.20	2.3	5.3	0.16	5	5.3	5.0				
STD DS8	Standard	111	0.57	256	0.104	2	0.83	0.067	0.39	2.9	0.20	1.8	5.0	0.21	4	6.3	4.9				
STD DS8	Standard	113	0.59	256	0.106	2	0.84	0.066	0.40	2.8	0.21	1.7	5.1	0.19	4	5.4	4.7				
STD DS8	Standard	119	0.59	257	0.108	2	0.87	0.081	0.40	2.6	0.22	1.9	5.2	0.17	4	4.5	4.9				
STD DS8	Standard	123	0.60	259	0.110	2	0.88	0.085	0.40	2.9	0.19	2.0	5.0	0.17	4	4.9	5.2				
STD DS8	Standard	113	0.58	270	0.094	3	0.86	0.092	0.42	2.9	0.22	2.2	5.3	0.14	5	5.9	4.4				
STD DS8	Standard	107	0.57	261	0.094	2	0.87	0.110	0.43	2.8	0.19	2.3	5.2	0.07	4	4.9	4.8				
STD DS8	Standard	113	0.61	253	0.115	3	0.90	0.086	0.37	2.7	0.21	2.5	5.4	0.15	5	4.7	4.6				
STD DS8	Standard	119	0.59	261	0.116	2	0.88	0.081	0.38	2.6	0.19	2.4	5.2	0.15	5	5.4	4.7				
STD DS8	Standard	131	0.61	287	0.126	2	0.87	0.083	0.43	3.1	0.22	2.4	5.4	0.17	5	5.1	5.1				
STD DS8	Standard	125	0.62	290	0.126	3	0.88	0.082	0.42	3.1	0.20	2.3	5.3	0.16	5	5.3	5.0				
STD DS8	Standard	119	0.68	280	0.111	3	0.91	0.096	0.45	3.1	0.17	2.4	5.3	0.16	5	5.9	4.9				
STD DS8	Standard	108	0.67	275	0.106	3	0.88	0.093	0.42	2.9	0.18	1.9	5.4	0.17	4	4.8	4.5				
STD DS8	Standard																	13.0	110.6	118.2	315
STD DS8	Standard																	13.3	108.0	122.0	317
STD OREAS45CA	Standard																	0.9	474.9	19.7	53
STD OREAS45CA	Standard																	1.0	462.6	21.0	55
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.8	37.9	7.2	591	2.42	24.9	120.0	5.9	60	2.1	5.0	5.3	40	0.61	0.078	12	110	0.58	266	0.100
STD DS8	Standard	1.6	36.7	7.5	602	2.40	26.4	121.3	7.7	71	2.6	5.2	5.9	43	0.70	0.081	16	112	0.61	308	0.116
STD OREAS45CA	Standard	0.2	228.3	84.9	866	15.22	3.3	41.2	7.0	14	<0.1	0.1	0.2	201	0.41	0.035	15	667	0.14	151	0.119
STD OREAS45CA	Standard	0.2	223.7	83.6	873	15.59	4.3	47.2	7.1	15	0.1	0.1	0.2	202	0.39	0.036	15	688	0.13	163	0.134
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.83	0.073	0.40	2.7	0.23	2.0	5.0	0.15	4	4.5	4.8
STD DS8	Standard	<20	0.94	0.099	0.46	2.8	0.20	2.1	5.4	0.14	5	5.6	5.3
STD OREAS45CA	Standard	<20	3.26	0.012	0.06	<0.1	0.03	34.9	<0.1	<0.05	17	0.7	<0.2
STD OREAS45CA	Standard	<20	3.61	0.010	0.07	<0.1	<0.01	33.3	<0.1	<0.05	18	0.7	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		1DX30 Mo ppm 0.1	1DX30 Cu ppm 0.1	1DX30 Pb ppm 0.1	1DX30 Zn ppm 1	1DX30 Ag ppm 0.1	1DX30 Ni ppm 0.1	1DX30 Co ppm 0.1	1DX30 Mn ppm 1	1DX30 Fe % 0.01	1DX30 As ppm 0.5	1DX30 Au ppb 0.5	1DX30 Th ppm 0.1	1DX30 Sr ppm 1	1DX30 Cd ppm 0.1	1DX30 Sb ppm 0.1	1DX30 Bi ppm 0.1	1DX30 V ppm 2	1DX30 Ca % 0.01	1DX30 P % 0.001	1DX30 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	2.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		1DX30 Cr ppm 1	1DX30 Mg % 0.01	1DX30 Ba ppm 1	1DX30 Ti % 0.001	1DX30 B ppm 1	1DX30 Al % 0.01	1DX30 Na % 0.001	1DX30 K % 0.01	1DX30 W ppm 0.1	1DX30 Hg ppm 0.01	1DX30 Sc ppm 0.1	1DX30 Tl ppm 0.1	1DX30 S % 0.05	1DX30 Ga ppm 1	1DX30 Se ppm 0.5	1DX30 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 23, 2011

QUALITY CONTROL REPORT WHI11000627.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 15, 2011
Report Date: September 02, 2011
Page: 1 of 8

CERTIFICATE OF ANALYSIS WHI11000628.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #2
P.O. Number
Number of Samples: 190

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	190	Sieve to 230 mesh			WHI
1DX3	159	1:1:1 Aqua Regia digestion ICP-MS analysis	30	Completed	VAN
1DX1	31	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091109	Soil																				
1091110	Soil	3.5	47.3	21.7	224	2.3	71.4	15.5	459	3.39	20.5	8.0	1.9	72	0.9	1.9	0.3	35	0.56	0.147	9
1091111	Soil	2.6	42.1	17.8	216	2.1	67.1	10.0	194	3.23	17.0	7.7	1.8	79	0.9	1.5	0.2	35	0.71	0.162	11
1091112	Soil	3.8	45.7	18.2	208	2.0	67.3	11.6	212	3.35	19.5	9.5	1.8	68	0.8	1.9	0.3	34	0.59	0.127	8
1091113	Soil	3.8	47.2	19.1	214	1.7	70.3	12.5	167	3.21	18.7	12.3	2.2	61	0.7	1.8	0.6	28	0.59	0.092	8
1091114	Soil	2.3	35.9	11.1	131	1.2	41.4	5.7	91	1.90	10.9	33.2	0.6	77	0.6	1.0	1.3	34	1.65	0.136	7
1091115	Soil	2.8	33.5	14.3	131	1.3	45.8	6.7	178	2.06	17.6	12.6	1.5	82	0.3	1.3	0.4	53	1.36	0.152	11
1091116	Soil	4.0	44.2	16.7	178	1.9	60.4	7.5	89	2.56	15.6	<0.5	1.4	73	0.4	1.0	0.3	35	1.08	0.116	6
1091117	Soil	3.0	46.3	17.2	170	1.9	60.5	9.4	142	2.74	14.9	9.1	1.5	68	0.7	1.2	0.2	31	0.95	0.116	5
1091118	Soil	2.4	32.4	13.8	137	1.4	43.2	6.1	103	2.13	14.6	15.3	1.4	53	0.2	0.7	0.3	30	0.76	0.081	5
1091119	Soil	3.8	43.0	17.5	173	1.6	58.5	9.5	126	2.78	17.7	10.4	2.5	64	0.3	1.6	0.1	39	0.85	0.105	5
1091120	Soil	2.6	40.4	14.8	131	1.2	44.2	6.6	116	2.17	15.8	4.9	1.0	55	0.2	1.2	<0.1	33	0.85	0.094	5
1091121	Soil	2.7	38.3	15.1	188	1.3	53.8	7.4	85	2.45	14.6	5.7	1.6	56	1.1	1.1	0.1	20	0.73	0.077	5
1091122	Soil	15.0	21.2	37.7	99	0.7	21.2	2.7	32	1.29	46.3	23.3	0.9	51	0.4	14.3	0.3	104	0.13	0.059	14
1091123	Soil	5.8	51.3	24.5	103	5.6	39.1	7.1	242	2.63	112.7	47.9	1.2	128	2.0	9.7	0.3	120	1.74	0.256	10
1091124	Soil	2.5	39.8	13.6	124	1.0	29.9	5.0	193	1.70	19.4	13.2	1.1	64	0.7	2.1	0.2	32	0.86	0.086	5
1091125	Soil	10.7	20.0	19.5	135	0.6	31.3	3.7	44	1.42	45.8	11.9	0.9	23	0.2	9.1	0.3	109	0.03	0.042	12
1091126	Soil	15.5	23.3	21.3	199	0.4	43.6	4.9	50	1.65	56.8	12.1	0.5	23	0.2	12.1	0.3	154	0.04	0.054	13
1091127	Soil	11.2	16.2	22.0	105	<0.1	22.8	3.0	41	1.19	44.8	8.2	0.9	20	0.1	7.9	0.3	112	0.03	0.025	16
1091128	Soil	25.7	32.5	63.7	198	0.9	47.0	5.4	57	2.24	104.3	34.0	2.3	69	0.2	20.3	0.4	177	0.02	0.096	15
1091129	Soil	3.7	21.1	13.3	101	1.4	21.0	4.3	136	1.48	33.1	21.3	0.8	36	0.9	5.3	0.3	55	0.12	0.121	9
1091130	Soil	15.0	43.3	20.3	412	1.3	83.2	16.8	300	3.17	76.7	12.5	2.3	74	4.7	6.2	0.1	94	0.44	0.236	19
1091131	Soil	11.8	34.1	19.0	314	0.9	67.7	15.3	360	2.57	57.6	15.7	2.2	79	2.0	6.0	0.2	80	0.41	0.210	16
1091132	Soil	17.4	73.0	22.1	451	1.6	103.8	13.9	372	3.23	76.6	17.0	2.6	83	4.9	7.3	<0.1	85	0.62	0.166	15
1091133	Soil	11.6	41.6	20.6	423	1.1	83.5	5.2	1659	2.22	25.3	4.0	0.9	102	8.0	4.8	0.2	38	0.34	0.105	10
1091134	Soil	34.7	48.5	10.1	488	0.9	105.2	6.7	247	1.77	34.5	0.8	1.1	96	11.5	8.5	0.2	112	2.04	0.134	11
1091135	Soil	18.2	68.6	22.5	383	1.4	70.2	10.4	209	3.17	60.9	9.3	0.8	71	2.2	10.3	0.2	56	0.81	0.162	9
1091136	Soil	11.9	35.4	17.7	155	0.6	30.0	4.8	103	2.11	75.5	8.9	1.8	32	1.1	7.7	0.2	89	0.08	0.081	11
1091137	Soil	21.5	17.3	10.4	156	2.5	30.9	2.5	32	1.31	24.0	1.5	0.6	27	1.2	6.9	0.2	194	0.02	0.044	16
1091138	Soil	48.4	48.2	11.9	553	0.9	119.5	6.0	136	2.25	53.5	4.5	0.7	44	4.8	13.9	0.2	285	0.56	0.119	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091109	Soil																	N.A.	N.A.	N.A.	N.A.
1091110	Soil	29	0.10	675	0.003	4	0.92	0.006	0.09	<0.1	0.34	4.6	0.2	<0.05	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091111	Soil	27	0.10	560	0.003	6	0.93	0.009	0.10	<0.1	0.27	4.6	0.2	0.10	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091112	Soil	26	0.10	576	0.003	7	0.90	0.008	0.09	<0.1	0.26	4.3	0.2	0.05	2	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091113	Soil	28	0.16	635	0.006	8	0.95	0.009	0.15	<0.1	0.32	4.4	0.2	0.13	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091114	Soil	16	0.08	800	0.005	15	0.95	0.012	0.08	0.2	0.26	2.3	0.7	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091115	Soil	29	0.10	902	0.004	6	0.90	0.010	0.11	0.1	0.33	3.3	0.3	<0.05	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091116	Soil	34	0.10	907	0.005	20	1.09	0.013	0.15	0.1	0.32	5.2	0.2	<0.05	3	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091117	Soil	27	0.09	870	0.004	9	0.99	0.012	0.12	<0.1	0.30	4.5	0.1	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091118	Soil	24	0.11	707	0.005	8	0.80	0.008	0.14	<0.1	0.23	4.2	0.2	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091119	Soil	26	0.12	744	0.004	12	0.91	0.015	0.15	<0.1	0.23	5.2	0.2	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091120	Soil	24	0.12	641	0.004	7	0.87	0.011	0.11	0.2	0.39	3.2	0.1	<0.05	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091121	Soil	25	0.12	488	0.002	7	0.75	0.007	0.11	0.2	0.17	4.1	0.1	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091122	Soil	14	0.02	289	0.005	2	0.26	0.005	0.07	0.7	5.25	0.9	0.9	0.08	2	4.0	0.4	N.A.	N.A.	N.A.	N.A.
1091123	Soil	41	0.06	1631	0.009	4	1.25	0.005	0.06	0.3	8.46	3.1	0.7	0.10	3	5.9	0.3	N.A.	N.A.	N.A.	N.A.
1091124	Soil	22	0.24	946	0.003	2	0.86	0.007	0.06	0.1	1.07	1.9	0.2	0.12	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091125	Soil	11	0.02	168	0.007	1	0.32	0.003	0.05	0.3	1.40	0.9	0.6	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091126	Soil	16	0.02	260	0.004	2	0.34	0.003	0.06	0.4	1.03	0.7	0.7	<0.05	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091127	Soil	10	0.02	142	0.006	<1	0.37	0.002	0.04	0.3	0.43	0.6	0.5	<0.05	4	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091128	Soil	19	0.02	439	0.007	7	0.43	0.004	0.12	1.0	6.63	1.5	1.5	<0.05	4	6.9	0.4	N.A.	N.A.	N.A.	N.A.
1091129	Soil	24	0.11	853	0.003	3	0.66	0.005	0.06	0.1	2.34	1.5	0.5	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091130	Soil	32	0.09	4244	0.002	3	0.76	0.006	0.11	0.1	1.99	4.1	0.6	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091131	Soil	27	0.10	3263	0.003	5	0.63	0.004	0.09	0.2	1.61	3.0	0.5	0.06	2	3.0	0.3	N.A.	N.A.	N.A.	N.A.
1091132	Soil	26	0.18	3354	0.004	3	0.59	0.004	0.14	0.2	3.20	4.1	0.6	<0.05	2	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091133	Soil	8	0.03	526	0.002	4	0.41	0.005	0.21	<0.1	0.71	1.2	0.5	0.38	1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091134	Soil	22	0.83	818	0.004	3	0.61	0.007	0.06	0.2	0.68	4.2	0.7	<0.05	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091135	Soil	9	0.10	538	0.004	2	0.49	0.011	0.07	0.1	0.64	2.7	0.4	0.06	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091136	Soil	15	0.10	664	0.002	1	0.75	0.005	0.07	0.1	0.45	1.8	0.6	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091137	Soil	12	0.03	173	0.008	2	0.33	0.005	0.07	0.2	0.20	0.7	1.4	0.05	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091138	Soil	21	0.11	524	0.002	2	0.69	0.006	0.08	0.3	1.11	1.8	0.8	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091139	Soil	68.0	35.2	7.4	307	0.2	132.2	6.3	63	1.69	45.7	1.0	0.3	30	1.1	8.3	0.1	75	0.49	0.074	9
1091140	Soil	54.0	41.2	12.9	429	0.3	127.0	8.6	221	2.31	47.2	2.0	2.2	47	2.7	13.5	0.2	114	0.84	0.106	10
1091141	Soil	16.2	17.3	5.4	154	0.1	39.6	2.6	38	0.88	14.2	0.6	0.3	19	1.5	2.8	<0.1	87	0.31	0.051	10
1091142	Soil	24.2	38.4	10.6	371	0.5	82.0	6.7	134	2.00	37.6	3.1	1.9	41	2.8	9.2	0.2	119	0.52	0.120	12
1091143	Soil	23.9	24.3	9.1	300	0.3	59.9	4.9	117	1.32	29.4	0.7	1.4	31	2.0	10.8	<0.1	110	0.45	0.094	9
1091144	Soil	59.7	67.0	10.0	548	1.1	173.8	7.9	161	2.10	75.0	4.0	1.8	152	6.8	10.0	0.2	80	2.74	0.094	12
1091145	Soil	54.7	56.0	10.7	459	0.5	155.7	9.4	238	2.45	47.6	2.6	1.6	20	3.5	5.8	0.2	84	0.18	0.112	10
1091146	Soil	20.3	41.7	18.8	335	0.6	66.2	7.8	135	2.43	84.5	6.7	2.8	34	1.7	9.1	0.4	114	0.22	0.107	14
1091147	Soil	12.9	19.0	13.6	172	0.2	33.0	3.5	66	1.32	56.9	4.2	0.3	17	0.8	5.4	0.2	80	0.09	0.056	7
1091148	Soil	8.5	12.9	12.7	100	0.1	18.6	3.0	67	1.46	26.2	1.1	0.6	12	0.2	2.6	0.3	74	0.02	0.043	10
1091149	Soil	11.4	10.8	13.4	111	0.3	19.4	2.4	63	1.38	25.4	1.1	1.2	12	0.3	3.1	0.2	108	0.03	0.054	10
1091150	Soil	154.6	94.0	13.8	1344	3.0	241.3	6.5	150	1.79	108.8	1.2	2.2	102	9.7	34.0	0.2	735	2.45	0.094	17
1091201	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091202	Soil	8.2	58.2	16.9	224	1.6	59.6	11.9	205	2.89	38.0	8.2	1.8	44	0.8	3.8	0.3	38	0.12	0.104	5
1091203	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091204	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091205	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091206	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091207	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091208	Soil	14.4	46.4	19.3	276	1.1	66.2	9.2	182	2.25	75.1	14.5	1.0	62	1.7	7.6	0.2	61	0.44	0.109	7
1091209	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091210	Soil	23.4	74.0	23.0	483	1.2	100.6	10.4	136	2.96	88.1	21.4	3.6	84	3.9	11.7	0.3	80	0.45	0.135	8
1091211	Soil	14.3	51.1	17.7	179	1.4	49.1	6.1	171	1.74	81.6	23.0	2.6	67	2.3	9.7	0.2	69	0.40	0.101	9
1091212	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091213	Soil	53.6	36.2	10.3	174	0.1	132.0	6.7	69	1.62	57.6	0.7	0.5	36	1.5	5.7	0.1	44	0.73	0.082	7
1091214	Soil	87.9	98.3	16.0	766	1.1	194.9	6.9	170	2.13	118.8	4.7	2.3	65	12.8	34.3	0.2	359	1.12	0.126	21
1091215	Soil	30.1	45.9	7.4	306	0.4	89.0	3.4	135	1.14	43.7	1.0	0.5	82	3.4	11.1	0.1	141	2.33	0.082	7
1091216	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091217	Soil	7.2	30.6	10.2	256	0.4	41.6	6.9	147	2.37	38.3	6.7	1.8	39	1.9	3.7	0.3	47	0.38	0.092	7
1091218	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091139	Soil	13	0.10	470	0.002	2	0.47	0.010	0.05	0.5	0.08	0.9	0.7	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091140	Soil	16	0.11	487	0.005	2	0.46	0.004	0.07	0.3	0.25	3.2	0.7	<0.05	1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091141	Soil	10	0.09	352	0.003	1	0.47	0.009	0.04	0.2	0.07	0.6	0.4	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091142	Soil	16	0.10	571	0.003	4	0.64	0.004	0.06	0.2	0.53	2.4	0.4	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091143	Soil	11	0.09	316	0.006	<1	0.54	0.009	0.07	0.2	0.52	2.0	0.3	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091144	Soil	29	0.88	608	0.003	5	0.57	0.004	0.04	0.4	0.84	6.2	0.9	<0.05	1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091145	Soil	24	0.05	380	0.002	2	0.63	0.002	0.04	0.2	0.55	3.7	0.9	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091146	Soil	15	0.10	711	0.005	3	0.77	0.003	0.06	0.3	0.98	2.2	0.3	0.06	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091147	Soil	7	0.03	305	0.003	2	0.36	0.007	0.04	0.1	0.27	0.6	0.2	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091148	Soil	8	0.05	141	0.005	1	0.52	0.002	0.03	0.2	0.04	0.6	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091149	Soil	9	0.05	182	0.005	1	0.52	0.003	0.04	0.2	0.07	0.7	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091150	Soil	42	0.98	622	0.005	3	0.83	0.005	0.07	0.7	1.67	4.4	1.5	<0.05	2	5.7	0.3	N.A.	N.A.	N.A.	N.A.
1091201	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	8.5	39.0	20.2	176
1091202	Soil	17	0.10	3271	0.002	3	0.69	0.003	0.06	0.1	0.87	3.5	0.2	0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091203	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.9	31.0	14.4	126
1091204	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	19.1	52.0	23.3	249
1091205	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	9.6	49.6	20.0	200
1091206	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.5	35.5	7.4	73
1091207	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	11.6	29.5	13.2	140
1091208	Soil	13	0.07	1677	0.006	2	0.50	0.009	0.06	0.2	1.40	2.1	0.5	0.10	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091209	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	11.0	36.5	19.9	169
1091210	Soil	13	0.06	1711	0.002	3	0.40	0.003	0.06	0.2	1.67	3.9	0.6	0.09	1	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091211	Soil	11	0.06	1988	0.002	3	0.31	0.003	0.06	0.2	2.97	3.4	0.5	0.09	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091212	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	14.2	43.5	14.6	218
1091213	Soil	9	0.09	331	0.004	4	0.43	0.010	0.04	0.2	0.21	1.7	0.5	0.06	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091214	Soil	26	0.25	480	0.005	4	0.61	0.006	0.07	0.5	1.15	4.4	1.2	<0.05	1	5.3	0.3	N.A.	N.A.	N.A.	N.A.
1091215	Soil	11	0.58	369	0.007	4	0.44	0.017	0.04	0.2	0.36	1.3	0.5	<0.05	1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091216	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	10.5	40.2	13.0	289
1091217	Soil	18	0.18	775	0.003	1	0.71	0.003	0.05	0.3	0.42	1.8	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091218	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.6	26.0	8.6	242

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091141	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091142	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091143	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091144	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091145	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091146	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091147	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091148	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091149	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091150	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091201	Soil	0.4	34.7	5.3	81	2.67	40.9	6.2	0.4	32	0.9	1.3	0.2	73	0.04	0.094	5	19	0.04	1404	0.001
1091202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091203	Soil	1.1	28.1	4.2	81	1.68	25.8	7.6	0.1	24	0.5	0.8	0.2	47	0.06	0.089	5	16	0.04	859	0.001
1091204	Soil	0.5	60.0	13.8	519	3.01	95.3	12.1	0.7	42	1.6	4.9	0.2	113	0.12	0.151	12	19	0.05	1826	0.003
1091205	Soil	1.0	52.7	11.7	234	2.93	55.2	14.5	1.0	42	1.4	3.4	0.2	60	0.20	0.115	9	9	0.11	2161	0.002
1091206	Soil	1.2	31.4	3.7	111	1.09	18.0	5.9	0.2	28	2.0	1.7	0.1	38	0.35	0.108	6	11	0.04	1699	0.003
1091207	Soil	0.5	39.0	4.3	62	1.47	52.0	11.4	0.2	29	0.8	3.7	0.2	68	0.17	0.068	8	12	0.04	1115	0.002
1091208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091209	Soil	0.5	45.0	5.8	144	1.96	62.6	11.3	0.3	38	1.7	2.7	0.3	76	0.17	0.090	8	17	0.03	1533	0.002
1091210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091212	Soil	1.1	52.9	6.9	140	1.72	67.7	18.6	0.4	37	1.9	4.4	0.2	86	0.21	0.107	10	15	0.04	2416	0.002
1091213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091216	Soil	0.6	51.5	7.0	124	2.20	41.0	9.9	1.2	41	3.2	2.2	0.3	77	0.37	0.092	8	21	0.16	829	0.002
1091217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091218	Soil	1.0	31.7	3.3	69	1.29	29.8	8.0	0.1	30	2.6	1.4	0.2	64	0.37	0.065	5	15	0.10	888	0.002

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091141	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091142	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091143	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091144	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091145	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091146	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091147	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091148	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091149	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091150	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091201	Soil	<20	0.72	0.005	0.08	<0.1	0.22	1.3	0.4	<0.05	3	2.2	<0.2
1091202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091203	Soil	<20	0.61	0.009	0.06	<0.1	0.42	0.5	0.3	<0.05	2	1.6	<0.2
1091204	Soil	<20	0.62	0.004	0.09	0.1	0.56	1.5	0.6	<0.05	2	3.0	<0.2
1091205	Soil	<20	0.75	0.004	0.09	<0.1	0.65	2.4	0.3	0.05	2	2.6	<0.2
1091206	Soil	<20	0.67	0.018	0.04	<0.1	0.66	0.9	0.2	<0.05	2	1.1	<0.2
1091207	Soil	<20	0.39	0.012	0.06	<0.1	0.43	0.5	0.4	<0.05	2	1.6	<0.2
1091208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091209	Soil	<20	0.45	0.004	0.09	0.1	0.56	0.7	0.4	0.06	2	1.8	<0.2
1091210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091212	Soil	<20	0.45	0.007	0.08	0.1	1.13	1.2	0.6	<0.05	2	2.0	<0.2
1091213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091216	Soil	<20	0.82	0.008	0.09	0.1	0.44	2.0	0.3	<0.05	2	1.7	<0.2
1091217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091218	Soil	<20	0.69	0.021	0.08	0.1	0.59	0.7	0.3	<0.05	2	1.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091219	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091220	Soil	3.6	14.1	6.5	97	0.6	17.7	2.1	32	0.96	31.5	5.3	0.6	17	0.8	2.7	0.3	28	0.08	0.039	4
1091221	Soil	11.4	26.2	14.6	212	0.6	39.2	4.6	82	2.20	86.0	9.9	1.6	27	0.9	6.6	0.6	89	0.05	0.060	11
1091222	Soil	15.9	40.7	21.0	374	0.7	73.2	7.9	112	3.26	97.5	12.3	2.3	49	2.0	8.8	0.6	90	0.12	0.134	12
1091223	Soil	20.5	46.4	17.0	576	0.8	88.1	8.7	135	2.84	91.5	8.1	1.7	51	3.7	9.1	0.5	88	0.33	0.104	14
1091224	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091225	Soil	22.9	28.3	7.4	148	0.2	44.4	3.0	37	1.01	26.3	1.8	0.8	31	3.0	3.2	0.2	72	0.47	0.061	8
1091226	Soil	41.7	61.3	10.9	471	0.7	142.2	9.0	294	1.89	49.0	2.0	1.5	61	5.5	5.4	0.2	108	1.14	0.102	17
1091227	Soil	16.9	26.2	8.1	213	0.3	52.8	4.4	118	1.40	36.4	1.5	0.7	44	2.3	6.5	0.2	101	0.73	0.065	7
1091228	Soil	11.3	23.1	7.1	121	0.3	34.6	3.0	58	1.08	26.0	1.4	0.4	32	1.5	3.8	0.2	71	0.52	0.049	8
1091229	Soil	14.4	31.5	15.9	225	0.4	48.0	5.3	101	2.44	56.2	4.3	1.0	32	1.1	6.4	0.4	88	0.21	0.077	13
1091230	Soil	15.9	29.1	19.4	176	0.4	40.0	4.0	74	1.82	52.2	12.1	1.2	27	0.6	10.2	0.3	79	0.08	0.068	11
1091231	Soil	19.4	77.7	43.5	329	0.8	66.4	8.3	209	3.14	68.3	27.1	2.7	43	1.0	10.9	1.5	79	0.35	0.146	16
1091232	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091233	Soil	12.7	33.2	17.1	185	0.8	37.9	4.6	91	1.97	64.2	10.5	0.2	31	0.8	8.6	0.4	69	0.09	0.089	10
1091234	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091235	Soil	14.2	81.7	30.2	340	3.0	51.1	6.5	121	2.81	44.4	2.2	1.9	32	0.4	11.5	0.3	95	0.05	0.124	10
1091236	Soil	6.8	18.4	15.5	78	0.4	15.0	1.6	30	0.89	17.0	1.5	0.3	9	<0.1	2.6	0.2	43	0.02	0.042	12
1091237	Soil	12.9	31.7	31.3	141	0.9	38.0	4.5	75	1.99	39.4	1.0	0.2	48	0.3	5.6	0.4	80	0.03	0.093	12
1091238	Soil	16.7	36.8	30.3	202	0.6	52.8	6.1	166	2.56	34.2	2.7	1.1	19	0.2	6.4	0.4	54	0.04	0.072	11
1091239	Soil	8.1	27.5	11.4	140	<0.1	33.3	5.9	125	3.62	36.9	1.0	1.4	7	0.3	5.0	0.7	36	0.02	0.048	13
1091240	Soil	5.1	16.8	7.6	62	0.2	15.2	2.7	62	1.16	22.3	2.7	0.3	4	<0.1	2.3	0.2	25	0.03	0.025	6
1091241	Soil	12.1	32.3	15.8	127	0.3	31.6	4.2	99	1.94	31.8	6.5	1.6	9	0.6	5.2	0.5	60	0.06	0.031	15
1091242	Soil	7.2	20.6	12.4	88	0.7	23.8	4.0	65	1.37	26.4	1.0	0.2	14	<0.1	2.4	0.2	27	0.18	0.038	8
1091243	Soil	4.4	18.1	8.6	63	0.8	19.7	3.0	45	1.09	13.7	<0.5	0.2	13	<0.1	2.7	<0.1	15	0.16	0.037	5
1091244	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091245	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091246	Soil	39.2	54.8	53.8	221	1.9	48.4	5.3	105	2.87	237.0	40.5	3.2	145	1.6	54.4	0.4	188	0.15	0.164	16
1091247	Soil	40.8	61.1	17.0	404	0.6	80.1	3.3	48	1.79	38.4	1.4	0.3	8	1.0	14.8	0.2	221	0.03	0.075	11
1091248	Soil	22.8	16.0	7.2	290	0.2	44.2	1.6	40	0.94	17.3	1.6	0.1	2	0.8	8.0	0.1	120	0.02	0.032	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091219	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	9.2	30.5	12.8	210
1091220	Soil	8	0.05	321	0.004	1	0.40	0.017	0.04	0.2	0.51	0.9	0.1	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091221	Soil	14	0.10	382	0.005	<1	0.71	0.004	0.06	0.4	0.76	1.4	0.4	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091222	Soil	16	0.11	673	0.003	2	0.75	0.004	0.08	0.3	0.82	2.3	0.4	0.06	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091223	Soil	15	0.13	640	0.002	<1	0.58	0.003	0.06	0.3	0.96	2.3	0.4	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091224	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	11.3	47.4	11.0	195
1091225	Soil	11	0.07	420	0.005	2	0.52	0.006	0.05	0.3	0.14	1.2	0.5	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091226	Soil	36	0.16	643	0.005	4	0.72	0.003	0.07	0.3	0.57	6.3	1.1	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091227	Soil	10	0.10	509	0.004	1	0.44	0.012	0.04	0.2	0.22	1.2	0.6	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091228	Soil	9	0.09	473	0.004	<1	0.50	0.012	0.04	0.2	0.20	0.9	0.5	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091229	Soil	16	0.13	1150	0.005	3	0.79	0.005	0.07	0.2	0.68	1.4	0.4	0.25	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091230	Soil	14	0.07	324	0.007	3	0.52	0.009	0.06	0.4	1.27	1.3	0.6	0.27	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091231	Soil	31	0.17	575	0.023	4	0.60	0.026	0.16	0.7	1.66	2.0	1.4	0.25	3	3.3	0.9	N.A.	N.A.	N.A.	N.A.
1091232	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.6	10.4	7.9	71
1091233	Soil	13	0.08	587	0.002	2	0.63	0.008	0.06	0.3	2.33	0.7	0.4	0.15	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091234	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	10.6	37.3	21.6	246
1091235	Soil	8	0.03	240	0.009	2	0.51	0.006	0.07	0.2	0.71	1.3	0.3	0.16	4	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091236	Soil	6	0.03	115	0.006	2	0.40	0.005	0.05	0.1	0.24	0.4	0.2	0.10	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091237	Soil	11	0.05	291	0.004	2	0.55	0.004	0.09	0.2	0.29	0.5	0.4	0.12	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091238	Soil	9	0.04	262	0.006	4	0.39	0.005	0.09	0.2	0.23	1.1	0.5	0.11	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091239	Soil	8	0.04	316	0.011	2	0.50	0.004	0.09	0.1	0.10	1.1	0.2	0.10	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091240	Soil	5	0.03	122	0.006	2	0.24	0.012	0.04	0.2	0.09	0.3	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091241	Soil	12	0.05	414	0.013	2	0.51	0.009	0.07	0.3	0.18	0.8	0.5	0.10	3	1.2	0.2	N.A.	N.A.	N.A.	N.A.
1091242	Soil	5	0.07	1016	0.003	3	0.37	0.013	0.05	<0.1	0.18	0.5	0.1	0.16	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091243	Soil	3	0.03	989	0.004	2	0.26	0.025	0.04	<0.1	0.21	0.6	0.1	0.13	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091244	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	19.5	44.2	13.1	403
1091245	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	11.1	29.6	19.9	78
1091246	Soil	23	0.07	857	0.001	3	0.69	0.003	0.13	1.2	7.83	2.5	2.1	0.25	2	11.7	0.2	N.A.	N.A.	N.A.	N.A.
1091247	Soil	16	0.03	182	0.007	3	0.60	0.007	0.04	0.4	0.38	0.6	1.5	0.05	3	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091248	Soil	7	0.02	123	0.005	2	0.27	0.009	0.03	0.2	0.14	0.4	0.5	0.06	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091219	Soil	0.5	37.3	4.7	77	1.99	58.3	8.6	0.5	42	1.7	2.5	0.4	88	0.41	0.065	10	18	0.12	703	0.002
1091220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091222	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091224	Soil	0.2	84.4	11.1	129	3.56	37.1	2.2	0.4	10	0.8	6.7	0.3	39	0.07	0.077	13	9	0.04	172	0.003
1091225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091226	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091227	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091231	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091232	Soil	0.2	14.9	1.9	37	0.84	23.5	4.1	<0.1	12	0.3	2.9	0.1	44	0.05	0.036	6	8	0.03	123	0.004
1091233	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091234	Soil	1.4	41.0	4.3	101	1.92	42.4	8.8	0.2	34	0.8	3.2	0.3	101	0.09	0.119	12	19	0.09	421	0.003
1091235	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091236	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091237	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091238	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091239	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091240	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091241	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091242	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091243	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091244	Soil	0.7	92.0	8.7	398	1.88	34.9	4.4	0.5	42	4.0	4.6	0.1	79	0.71	0.074	8	16	0.19	2781	0.002
1091245	Soil	1.0	23.3	1.9	38	1.03	61.9	20.1	0.7	77	1.2	9.7	0.2	111	1.17	0.097	5	15	0.05	634	0.002
1091246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091247	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091219	Soil	<20	0.72	0.010	0.09	0.1	0.56	1.1	0.4	<0.05	3	1.5	<0.2
1091220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091222	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091224	Soil	<20	0.45	0.006	0.09	<0.1	0.04	1.1	0.3	<0.05	2	2.4	<0.2
1091225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091226	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091227	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091231	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091232	Soil	<20	0.29	0.013	0.05	<0.1	0.24	0.3	0.3	<0.05	2	0.7	<0.2
1091233	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091234	Soil	<20	0.85	0.006	0.10	0.1	1.65	0.6	0.6	0.08	3	1.8	<0.2
1091235	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091236	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091237	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091238	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091239	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091240	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091241	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091242	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091243	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091244	Soil	<20	0.55	0.008	0.08	0.2	0.87	1.8	0.7	<0.05	2	1.8	<0.2
1091245	Soil	<20	0.80	0.015	0.07	0.4	1.48	1.3	0.9	0.15	2	4.1	<0.2
1091246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091247	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091249	Soil	8.5	12.4	10.4	79	0.5	14.4	1.2	28	0.58	9.5	1.8	0.2	6	0.4	3.2	0.2	51	0.04	0.026	11
1091250	Soil	27.0	25.4	27.5	185	1.1	38.3	3.5	71	1.60	49.9	3.7	0.6	26	1.2	13.3	0.5	166	0.07	0.041	13
1091251	Soil	13.9	17.1	25.0	73	1.6	12.8	1.3	34	0.73	12.7	2.4	0.2	12	0.7	4.9	0.3	58	0.04	0.023	11
1091252	Soil	86.8	34.2	194.4	144	4.3	24.3	2.1	23	2.27	52.1	9.1	1.8	81	0.2	23.7	0.2	334	0.02	0.090	14
1091253	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091254	Soil	36.4	27.3	34.3	347	1.0	65.9	5.3	85	2.78	68.9	1.8	5.8	30	0.5	15.9	0.2	418	0.04	0.165	17
1091255	Soil	31.8	26.3	23.2	206	0.3	48.6	5.0	40	1.59	39.2	<0.5	0.4	14	0.7	11.3	0.1	218	0.02	0.046	18
1091256	Soil	13.9	15.2	15.3	97	0.9	24.4	2.0	20	0.80	19.0	0.6	<0.1	12	1.1	7.5	0.2	124	0.02	0.022	11
1091257	Soil	14.9	22.5	9.3	154	0.3	38.3	4.2	48	1.38	19.0	<0.5	0.4	5	0.4	4.8	0.2	72	0.03	0.034	11
1091258	Soil	8.6	24.6	13.3	133	1.2	27.5	1.7	32	0.83	10.5	4.3	0.6	15	3.1	7.2	0.2	53	0.08	0.054	5
1091259	Soil	11.5	45.8	15.7	197	1.2	49.6	2.6	87	1.40	42.8	4.6	0.5	24	5.4	21.2	0.3	74	0.16	0.106	8
1091260	Soil	26.5	43.1	31.3	460	1.0	82.4	5.1	116	1.83	32.6	10.0	2.2	42	6.1	19.0	0.5	101	0.31	0.108	14
1091160	Soil	9.3	59.2	24.8	3085	1.0	336.4	10.6	726	1.95	37.5	13.8	1.1	70	75.8	5.9	0.5	67	2.23	0.101	8
1091161	Soil	11.6	46.1	14.3	612	1.1	86.3	10.5	335	2.82	47.4	11.4	1.6	44	4.0	4.7	0.4	72	0.30	0.121	10
1091162	Soil	13.2	40.6	20.3	353	0.5	60.6	8.8	199	3.20	84.6	7.2	1.4	29	2.6	6.6	0.7	86	0.13	0.087	12
1091163	Soil	10.8	39.6	16.9	296	0.6	56.2	9.1	211	3.29	90.2	17.2	1.4	32	2.1	6.3	0.6	90	0.12	0.103	9
1091164	Soil	19.5	40.9	16.9	451	0.6	81.2	8.4	152	3.02	80.3	10.6	1.3	33	2.8	7.5	0.5	116	0.17	0.117	13
1091165	Soil	29.8	36.3	13.4	537	0.6	101.8	8.1	92	2.57	64.3	9.8	1.9	30	1.9	8.1	0.4	118	0.16	0.097	15
1091166	Soil	36.2	45.6	17.3	806	0.3	133.8	14.1	124	4.32	54.3	8.3	2.4	12	2.1	9.4	0.4	29	0.15	0.082	10
1091167	Soil	50.3	28.7	6.7	389	0.2	96.2	7.5	134	1.87	28.7	5.9	1.0	28	4.5	4.0	0.2	89	0.47	0.063	9
1091168	Soil	21.7	46.9	11.6	521	0.6	96.8	10.8	127	2.50	48.8	5.0	2.9	48	4.0	7.4	0.3	107	0.45	0.125	15
1091169	Soil	46.6	173.1	12.6	1302	3.4	329.3	10.2	189	2.28	117.4	6.1	2.9	95	16.0	34.5	0.3	623	2.40	0.439	24
1091192	Soil	58.4	21.4	17.7	45	4.9	8.6	0.5	11	1.52	188.6	53.1	1.0	118	1.4	29.6	0.3	252	0.02	0.185	12
1091193	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091194	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091195	Soil	29.5	19.2	30.5	112	1.7	25.4	2.7	52	2.17	176.0	52.6	1.1	65	0.3	39.2	0.3	282	0.03	0.103	15
1091196	Soil	32.4	24.3	42.9	152	4.4	34.0	3.7	105	2.85	193.3	67.5	2.2	72	0.4	39.2	0.4	285	0.06	0.186	14
1091197	Soil	48.9	44.5	44.6	199	3.2	43.4	3.5	68	2.53	200.4	45.9	2.5	87	1.1	49.2	0.3	225	0.08	0.219	14
1091198	Soil	22.8	14.8	41.2	97	1.8	21.9	2.1	37	1.24	75.6	38.7	0.4	47	0.3	21.2	0.3	135	0.02	0.057	14
1091200	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091249	Soil	7	0.02	153	0.004	1	0.31	0.005	0.03	0.2	0.15	0.2	0.5	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091250	Soil	12	0.03	264	0.011	1	0.33	0.006	0.06	0.7	0.33	0.6	1.3	0.07	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091251	Soil	10	0.02	183	0.006	1	0.24	0.005	0.04	0.5	0.22	0.2	0.8	0.08	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091252	Soil	29	0.02	600	0.007	14	0.41	0.006	0.33	1.0	0.12	1.3	5.4	0.06	5	20.8	0.3	N.A.	N.A.	N.A.	N.A.
1091253	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	22.4	18.9	69.9	61
1091254	Soil	27	0.10	385	0.016	9	0.97	0.003	0.18	0.4	0.27	2.1	1.5	<0.05	5	5.7	0.2	N.A.	N.A.	N.A.	N.A.
1091255	Soil	13	0.02	445	0.007	8	0.37	0.003	0.08	0.5	0.10	0.8	0.7	<0.05	3	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091256	Soil	8	0.01	324	0.003	2	0.27	0.006	0.04	0.2	0.20	<0.1	0.6	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091257	Soil	7	0.02	161	0.003	2	0.29	0.002	0.05	0.1	0.12	0.4	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091258	Soil	9	0.03	822	0.004	3	0.33	0.011	0.06	0.1	0.74	0.9	0.4	0.07	1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091259	Soil	12	0.05	771	0.006	3	0.44	0.011	0.05	0.1	1.12	1.2	0.4	0.10	1	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091260	Soil	20	0.10	864	0.010	4	0.59	0.009	0.11	0.4	0.81	1.7	0.9	0.19	2	5.4	0.5	N.A.	N.A.	N.A.	N.A.
1091160	Soil	21	0.24	1039	0.009	5	0.78	0.012	0.08	0.3	1.68	1.8	1.3	0.20	2	2.2	0.3	N.A.	N.A.	N.A.	N.A.
1091161	Soil	28	0.22	1973	0.003	3	1.07	0.006	0.08	0.2	1.08	2.3	0.4	0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091162	Soil	23	0.20	652	0.004	2	0.95	0.003	0.07	0.3	0.58	1.6	0.3	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091163	Soil	25	0.18	667	0.003	4	0.94	0.004	0.07	0.2	0.70	1.9	0.4	0.06	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091164	Soil	20	0.13	519	0.004	3	0.77	0.003	0.08	0.3	0.47	1.8	0.6	<0.05	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091165	Soil	19	0.12	303	0.005	7	0.69	0.003	0.08	0.3	0.54	1.8	0.7	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091166	Soil	8	0.05	160	0.003	5	0.40	0.002	0.08	0.1	0.14	2.0	0.8	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091167	Soil	12	0.09	381	0.006	3	0.51	0.004	0.05	0.3	0.22	1.4	0.6	0.06	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091168	Soil	17	0.20	409	0.009	3	0.62	0.003	0.07	0.2	0.41	2.3	0.5	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091169	Soil	110	0.87	728	0.008	9	0.93	0.006	0.17	0.4	1.00	6.4	1.6	0.06	3	11.8	0.3	N.A.	N.A.	N.A.	N.A.
1091192	Soil	20	0.02	275	0.004	4	0.45	0.002	0.09	1.8	9.45	1.0	3.4	0.16	4	5.8	0.3	N.A.	N.A.	N.A.	N.A.
1091193	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	58.5	65.0	69.8	65
1091194	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	22.3	18.9	34.7	92
1091195	Soil	19	0.05	270	0.006	3	0.50	0.002	0.08	1.0	15.38	0.8	1.5	0.09	4	6.9	0.3	N.A.	N.A.	N.A.	N.A.
1091196	Soil	21	0.08	359	0.008	6	0.70	0.002	0.09	1.0	16.78	1.4	1.7	0.09	4	7.4	0.4	N.A.	N.A.	N.A.	N.A.
1091197	Soil	26	0.05	391	0.005	4	0.54	0.003	0.12	1.4	13.69	2.4	2.3	0.20	2	14.5	0.3	N.A.	N.A.	N.A.	N.A.
1091198	Soil	11	0.02	218	0.005	2	0.38	0.002	0.06	0.6	8.29	0.6	1.2	0.06	4	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091200	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	18.1	81.0	21.4	327

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091249	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091250	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091251	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091252	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091253	Soil		1.8	12.2	1.5	18	0.77	13.8	0.9	<0.1	9	0.4	6.6	0.2	94	0.02	0.033	14	15	0.01	158	0.002
1091254	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091255	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091256	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091257	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091258	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091259	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091260	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091160	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091161	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091162	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091163	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091164	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091165	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091166	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091167	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091168	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091169	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091192	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091193	Soil		6.6	9.3	0.6	64	2.28	631.4	1490	15.1	1067	9.5	97.6	0.9	246	0.20	0.452	72	47	0.02	365	0.003
1091194	Soil		4.5	17.6	1.7	18	0.87	41.3	49.6	0.2	50	0.4	26.1	0.3	150	0.03	0.040	19	15	0.01	209	0.004
1091195	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091196	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091197	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091198	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091200	Soil		1.2	49.3	8.2	249	5.15	80.5	31.1	1.9	52	6.5	10.1	0.2	163	0.10	0.130	10	20	0.05	760	0.004

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091249	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091250	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091253	Soil	<20	0.37	0.005	0.05	0.2	0.04	<0.1	0.8	<0.05	2	4.1	<0.2
1091254	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091258	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091259	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091160	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091161	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091162	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091163	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091164	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091165	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091193	Soil	<20	0.81	0.004	0.21	2.8	>50	2.7	15.1	0.41	7	19.9	1.8
1091194	Soil	<20	0.42	0.002	0.07	0.8	5.37	0.3	1.4	<0.05	3	5.3	0.3
1091195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091200	Soil	<20	0.70	0.009	0.08	0.5	3.75	2.5	1.1	<0.05	3	5.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091170	Soil	44.4	48.2	13.6	859	3.0	139.0	6.6	117	2.02	77.4	4.6	1.3	25	12.4	17.0	0.2	359	0.33	0.075	14
1091172	Soil	33.9	42.2	18.9	394	0.3	108.5	9.4	161	2.80	83.8	8.0	1.2	41	2.5	8.4	0.3	201	0.18	0.092	16
1091173	Soil	21.1	21.4	11.4	278	1.0	59.4	3.8	75	1.76	37.6	4.4	0.2	24	1.5	5.4	0.2	190	0.18	0.096	16
1091177	Soil	19.1	45.3	24.8	299	0.7	72.7	7.8	98	3.19	56.3	5.8	0.7	78	0.5	6.6	0.4	118	0.10	0.176	15
1091181	Soil	9.1	43.0	14.4	354	0.8	75.3	12.1	222	3.80	43.7	5.8	3.3	15	1.0	3.9	0.3	52	0.07	0.090	20
1091182	Soil	35.6	32.1	11.7	269	<0.1	78.0	7.1	74	2.26	47.3	4.4	0.6	9	0.3	4.0	0.2	77	0.01	0.067	17
1091183	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091184	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091187	Soil	58.8	32.6	15.2	490	0.6	120.4	5.7	67	2.15	67.1	4.4	0.5	18	1.3	16.2	0.3	486	0.05	0.056	16
1091189	Soil	31.2	22.3	16.4	165	0.9	34.9	3.8	42	1.60	47.3	6.2	0.9	24	0.3	17.7	0.3	145	0.02	0.043	19
1091024	Soil	1.4	3.3	3.8	22	0.6	4.8	0.5	9	0.23	2.1	4.3	0.1	6	0.2	0.5	<0.1	12	0.04	0.025	2
1091026	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091030	Soil	6.5	22.9	15.0	75	0.7	19.0	3.3	65	1.74	86.2	12.4	2.1	33	0.2	5.1	0.4	47	0.26	0.056	9
1091052	Soil	9.9	35.9	11.0	232	0.3	52.9	7.3	141	2.59	59.0	10.6	4.1	43	1.5	5.8	0.3	62	0.35	0.113	16
1091053	Soil	9.5	23.8	12.3	178	0.6	34.2	7.1	178	1.85	41.9	13.0	0.9	38	1.5	4.3	0.3	78	0.23	0.101	14
1091054	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091055	Soil	6.7	12.9	7.7	83	0.5	16.9	1.8	21	0.66	22.4	5.7	<0.1	11	0.8	2.7	0.1	61	0.02	0.051	5
1091056	Soil	13.2	25.2	25.6	168	0.5	34.8	4.0	56	1.70	60.3	5.7	0.2	21	1.3	5.5	0.3	108	0.02	0.065	11
1091057	Soil	13.0	26.1	22.0	156	0.7	32.1	3.7	43	1.55	52.7	5.5	0.2	17	1.1	5.2	0.4	106	0.02	0.101	11
1091059	Soil	13.9	19.3	74.3	91	1.4	15.8	2.7	44	2.02	125.9	9.1	0.4	47	0.8	11.0	0.3	122	0.02	0.092	9
1090529	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090530	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090296	Soil	3.3	8.7	14.0	33	0.6	9.3	0.9	15	0.54	57.4	62.3	0.2	17	0.3	5.6	0.6	15	0.10	0.041	4
1090297	Soil	3.4	35.1	17.0	132	0.4	37.8	6.0	36	2.37	17.4	3.5	0.9	26	0.1	2.1	0.2	26	<0.01	0.056	1
1090298	Soil	0.9	12.8	2.8	40	0.4	11.2	1.9	89	0.42	3.3	7.4	0.2	40	0.1	1.0	0.3	11	0.86	0.040	2
1090299	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090300	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090434	Soil	9.6	64.6	19.9	117	3.0	26.2	3.8	66	3.17	39.8	3.0	1.2	54	0.3	2.4	0.3	35	0.01	0.069	3
1091060	Soil	8.7	23.5	12.9	219	2.5	30.2	3.8	56	1.37	47.0	14.5	0.3	21	2.1	7.5	0.2	81	0.03	0.070	6
1091061	Soil	34.4	26.0	23.2	250	2.0	47.2	3.9	49	2.18	151.3	36.0	2.2	108	0.8	29.3	0.3	504	0.04	0.117	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091170	Soil	33	0.12	709	0.003	4	0.65	0.007	0.10	0.2	0.93	2.9	1.5	0.05	2	9.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091172	Soil	24	0.12	651	0.004	4	0.98	0.004	0.09	0.3	0.53	1.9	0.9	<0.05	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091173	Soil	18	0.10	293	0.009	3	0.88	0.009	0.07	0.2	0.42	0.8	0.7	0.07	4	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091177	Soil	17	0.06	421	0.007	4	0.64	0.003	0.11	0.2	0.17	1.3	0.5	0.10	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091181	Soil	18	0.10	418	0.005	3	0.89	0.002	0.07	0.1	0.42	2.9	0.3	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091182	Soil	12	0.04	135	0.005	3	0.56	0.003	0.06	0.3	0.12	1.1	0.5	0.06	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091183	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	40.6	31.3	13.8	405
1091184	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	58.9	58.8	13.8	668
1091187	Soil	23	0.05	169	0.005	3	0.46	0.003	0.08	0.4	0.20	0.9	1.5	<0.05	3	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091189	Soil	11	0.02	208	0.007	5	0.31	0.002	0.07	0.6	0.42	0.8	2.1	0.08	3	6.6	0.2	N.A.	N.A.	N.A.	N.A.
1091024	Soil	4	0.01	37	0.006	<1	0.14	0.015	0.02	<0.1	0.17	0.4	<0.1	<0.05	<1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091026	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.2	36.0	15.6	110
1091030	Soil	12	0.11	287	0.001	2	0.48	0.005	0.05	0.3	1.88	1.5	0.2	0.06	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091052	Soil	19	0.31	620	0.024	2	0.80	0.008	0.06	0.3	1.01	2.8	0.2	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091053	Soil	20	0.26	549	0.013	3	0.86	0.007	0.07	0.3	1.23	1.8	0.4	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091054	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	12.1	28.8	17.5	481
1091055	Soil	8	0.02	333	0.002	3	0.32	0.011	0.03	0.1	0.64	0.2	0.2	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091056	Soil	12	0.03	429	0.003	2	0.52	0.004	0.05	0.3	0.39	0.3	0.4	0.06	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091057	Soil	14	0.02	440	0.004	3	0.48	0.007	0.07	0.2	0.36	0.4	0.3	0.08	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091059	Soil	13	0.02	369	0.005	2	0.36	0.006	0.07	0.3	0.46	0.8	0.4	0.10	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090529	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.1	78.2	23.7	70
1090530	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.7	45.7	17.4	96
1090296	Soil	6	0.02	76	0.004	1	0.17	0.015	0.04	0.3	3.73	0.6	0.6	0.07	<1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090297	Soil	11	0.03	133	<0.001	2	0.42	0.007	0.06	<0.1	0.07	2.3	0.2	0.07	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090298	Soil	5	0.03	270	0.007	2	0.38	0.026	0.03	<0.1	0.17	0.7	<0.1	<0.05	<1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090299	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.0	40.2	9.1	190
1090300	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	9.2	77.5	4.9	>10000
1090434	Soil	30	0.03	914	0.001	5	0.50	0.004	0.11	<0.1	0.42	3.2	0.2	0.16	2	13.7	0.2	N.A.	N.A.	N.A.	N.A.
1091060	Soil	8	0.04	310	0.005	2	0.54	0.012	0.05	0.1	1.69	0.6	0.3	0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091061	Soil	26	0.05	768	0.009	3	0.67	0.004	0.12	0.5	5.54	1.6	1.9	0.15	4	5.8	0.4	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091183	Soil	0.2	138.6	10.0	179	2.23	29.8	2.5	0.3	15	0.9	3.0	0.2	82	0.13	0.058	16	18	0.05	263	0.003
1091184	Soil	2.1	218.4	12.3	308	2.48	59.5	5.2	1.2	32	7.9	4.8	0.2	132	0.46	0.084	15	34	0.12	819	0.003
1091187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091026	Soil	1.5	32.9	6.3	298	1.62	31.0	14.1	0.5	52	0.7	0.8	0.3	31	0.72	0.082	6	18	0.08	1217	0.002
1091030	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091052	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091053	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091054	Soil	0.9	62.7	4.9	109	1.97	53.5	27.0	0.3	37	1.7	3.7	0.4	223	0.08	0.096	13	30	0.17	434	0.004
1091055	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091056	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090529	Soil	0.4	50.1	15.7	147	2.68	24.5	4.2	0.3	16	0.6	1.7	0.4	43	0.04	0.074	4	17	0.02	468	<0.001
1090530	Soil	0.2	27.3	6.9	91	1.77	21.5	2.3	0.2	10	0.4	1.1	0.3	49	0.04	0.076	4	16	0.02	105	0.001
1090296	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090297	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090298	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090299	Soil	0.5	38.0	4.5	264	1.18	40.8	9.2	0.3	103	2.5	6.5	0.1	26	2.61	0.110	3	16	0.09	528	0.002
1090300	Soil	0.8	665.3	15.5	300	1.34	81.8	3.8	0.2	74	>2000	49.5	<0.1	581	3.87	0.185	2	12	0.07	27	0.004
1090434	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091183	Soil	<20	0.45	0.003	0.07	0.2	0.23	0.8	1.7	<0.05	2	3.2	<0.2
1091184	Soil	<20	0.93	0.002	0.09	0.2	0.76	4.4	3.4	<0.05	2	2.9	<0.2
1091187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091026	Soil	<20	1.06	0.017	0.08	<0.1	0.86	1.9	0.2	<0.05	3	1.5	<0.2
1091030	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091052	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091053	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091054	Soil	<20	1.09	0.005	0.09	0.2	4.60	0.9	3.6	<0.05	4	1.5	<0.2
1091055	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091056	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090529	Soil	<20	0.39	0.003	0.07	<0.1	0.13	2.0	0.4	<0.05	2	1.3	<0.2
1090530	Soil	<20	0.44	0.005	0.08	<0.1	0.10	1.3	0.1	<0.05	2	0.9	<0.2
1090296	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090297	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090298	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090299	Soil	<20	0.52	0.009	0.05	0.2	0.89	0.9	0.7	0.14	1	3.2	<0.2
1090300	Soil	<20	0.50	0.006	0.02	0.2	0.88	0.6	36.1	6.26	<1	>100	<0.2
1090434	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091261	Soil	6.0	23.4	19.8	527	0.9	87.2	2.7	98	1.06	26.4	9.7	0.7	49	13.3	20.9	0.2	82	0.33	0.113	7
1091262	Soil	590.1	16.7	3.6	1759	0.2	170.5	24.1	2981	24.44	540.1	2.5	0.6	26	38.3	394.8	<0.1	931	0.27	0.478	2
1091263	Soil	70.4	12.2	2.7	929	0.3	188.2	6.9	713	3.13	61.7	<0.5	<0.1	19	21.1	50.2	<0.1	85	0.21	0.103	2
1091264	Soil	267.6	29.8	18.8	2846	0.9	582.6	54.0	4920	11.74	294.9	11.0	1.0	75	66.2	141.4	0.2	288	0.77	0.298	5
1091265	Soil	80.5	18.2	10.4	1331	0.7	219.3	12.5	1443	4.48	146.1	7.2	0.4	43	20.3	51.6	0.1	155	0.33	0.182	3
1091266	Soil	129.0	52.1	28.6	1372	1.9	265.1	12.0	1136	6.17	319.4	28.6	1.9	80	16.2	104.7	0.3	245	0.70	0.289	10
1091267	Soil	11.5	64.3	15.1	226	1.1	43.2	4.8	89	2.03	33.6	9.0	2.1	83	5.5	8.4	0.2	110	0.20	0.151	6
1091268	Soil	14.8	58.2	21.2	183	0.6	41.0	5.4	102	2.35	43.7	7.9	1.7	59	0.5	8.8	0.3	104	0.05	0.092	8
1091269	Soil	11.5	37.0	14.8	127	0.5	28.3	3.2	72	2.00	35.5	5.4	1.0	50	0.6	7.5	0.2	96	0.05	0.131	6
1091270	Soil	10.3	37.5	15.9	109	0.7	24.0	2.8	52	1.75	32.4	7.4	0.9	49	0.6	6.4	0.2	84	0.07	0.091	7
1091271	Soil	6.5	37.6	29.6	200	2.0	33.5	5.2	198	1.61	106.4	93.9	1.6	38	2.2	15.5	1.0	38	0.20	0.077	13
1091272	Soil	10.2	37.9	14.4	104	0.5	22.3	2.6	39	1.71	30.8	7.4	1.0	42	0.2	6.4	0.2	82	0.06	0.074	6
1091273	Soil	8.1	46.1	16.0	301	0.9	65.8	13.6	528	1.93	86.3	9.8	1.7	46	3.1	7.6	0.2	72	0.37	0.090	8
1091274	Soil	10.7	40.8	20.2	196	1.2	38.6	11.0	479	1.87	92.2	17.3	1.6	41	2.4	10.3	0.3	83	0.26	0.095	7
1091275	Soil	13.7	41.8	22.6	222	0.7	42.4	12.3	299	2.46	129.5	9.5	2.7	51	2.1	12.2	0.3	82	0.18	0.109	9
1091276	Soil	10.6	32.9	16.2	191	1.3	33.7	9.8	387	1.66	66.5	11.4	1.7	35	1.6	9.3	0.2	79	0.13	0.078	8
1091277	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091278	Soil	30.4	45.5	36.7	665	1.2	112.5	7.9	337	3.59	310.6	51.9	2.3	78	8.7	35.2	0.7	98	0.36	0.168	15
1091279	Soil	4.7	53.1	21.6	178	0.3	48.8	12.9	172	3.10	62.7	3.1	0.2	11	0.3	3.9	0.4	39	0.04	0.090	5
1091280	Soil	4.8	70.7	25.8	146	0.6	34.2	11.4	84	1.86	8.8	1.6	1.6	18	<0.1	3.1	0.3	24	0.04	0.096	3
1091281	Soil	8.0	54.2	16.3	229	0.2	40.2	11.0	148	2.50	219.9	2.3	0.6	13	0.3	4.6	0.3	45	0.15	0.086	2
1091282	Soil	4.0	31.6	15.6	106	1.1	23.2	7.8	285	1.46	45.1	2.6	0.4	12	0.5	1.9	0.2	25	0.15	0.084	3
1091283	Soil	6.8	126.4	33.9	183	1.2	85.3	35.5	897	6.42	47.7	5.2	3.8	63	1.4	4.8	0.5	50	0.17	0.107	4
1091284	Soil	77.2	137.6	67.0	904	2.2	195.7	28.3	583	5.06	98.8	5.1	3.9	109	9.4	14.4	0.4	221	0.34	0.143	8
1091285	Soil	93.7	140.1	14.7	1808	3.4	349.1	11.5	195	2.13	56.4	2.9	2.4	316	17.4	23.5	0.2	454	8.02	0.190	14
1091286	Soil	78.8	47.8	7.4	128	0.1	176.3	8.7	138	1.83	26.3	<0.5	2.4	226	1.4	2.7	0.1	38	10.70	0.045	5
1091287	Soil	80.9	54.8	23.2	1076	0.5	160.3	10.6	203	2.94	64.0	<0.5	4.7	92	8.8	19.8	0.2	165	4.06	0.069	5
1091288	Soil	109.6	89.4	14.8	354	0.4	213.6	10.3	147	2.69	70.6	0.6	3.4	134	2.4	6.4	0.2	54	4.58	0.099	6
1091289	Soil	87.6	78.3	11.2	404	0.2	210.3	8.7	144	1.85	30.5	0.8	2.9	169	4.4	4.7	0.1	60	6.01	0.068	6
1091290	Soil	69.2	46.4	6.6	142	0.1	140.3	6.6	124	1.53	18.0	1.1	2.7	267	1.7	2.3	<0.1	40	10.68	0.066	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091261	Soil	14	0.06	639	0.003	3	0.72	0.009	0.06	0.1	2.20	1.5	1.8	0.08	2	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091262	Soil	8	0.02	446	0.008	4	0.57	0.006	0.04	0.1	0.47	1.1	1.9	<0.05	1	19.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091263	Soil	3	0.02	179	0.008	2	0.36	0.022	0.02	<0.1	0.21	0.3	0.8	0.06	1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091264	Soil	14	0.07	486	0.007	5	0.61	0.005	0.07	0.3	2.06	2.0	5.0	0.11	2	19.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091265	Soil	9	0.05	394	0.006	3	0.73	0.018	0.07	0.1	1.08	0.9	1.7	0.07	2	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091266	Soil	20	0.11	617	0.005	7	0.77	0.006	0.11	0.4	4.35	2.8	2.7	0.11	2	10.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091267	Soil	20	0.05	2017	0.002	4	0.42	0.002	0.08	<0.1	1.08	3.0	0.5	0.09	1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091268	Soil	20	0.08	676	0.003	3	0.64	0.004	0.07	0.1	1.15	2.5	0.5	0.09	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091269	Soil	18	0.04	784	0.002	2	0.44	0.002	0.06	0.1	0.36	1.5	0.4	0.06	1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091270	Soil	17	0.05	1191	0.002	2	0.52	0.002	0.05	0.2	0.54	1.5	0.3	0.06	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091271	Soil	13	0.09	354	0.001	3	0.58	0.005	0.07	0.4	13.84	1.7	0.6	0.05	2	4.7	0.2	N.A.	N.A.	N.A.	N.A.
1091272	Soil	15	0.05	770	0.002	<1	0.52	0.003	0.04	0.1	0.50	1.4	0.3	<0.05	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091273	Soil	16	0.14	971	0.001	4	0.74	0.004	0.07	0.2	1.50	2.5	0.5	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091274	Soil	16	0.12	902	0.002	3	0.71	0.005	0.07	0.2	1.56	2.3	0.5	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091275	Soil	16	0.13	858	0.003	1	0.63	0.003	0.06	0.2	1.08	2.2	0.6	0.06	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091276	Soil	17	0.11	740	0.002	3	0.67	0.005	0.06	0.2	1.52	1.7	0.6	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091277	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	14.9	32.6	13.4	218
1091278	Soil	14	0.08	545	0.003	4	0.62	0.005	0.08	0.3	4.67	2.5	1.1	0.11	2	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091279	Soil	11	0.02	82	0.003	1	0.38	0.002	0.05	<0.1	0.05	0.8	0.3	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091280	Soil	9	0.03	91	0.005	5	0.37	0.006	0.13	<0.1	0.03	3.2	0.5	0.42	2	1.4	0.3	N.A.	N.A.	N.A.	N.A.
1091281	Soil	11	0.05	120	0.003	4	0.27	0.003	0.08	<0.1	0.05	3.1	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091282	Soil	8	0.05	277	0.004	2	0.38	0.013	0.07	<0.1	0.08	2.7	0.3	0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091283	Soil	18	0.09	750	0.002	2	0.51	0.003	0.11	<0.1	0.16	9.7	0.4	0.14	1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091284	Soil	21	0.08	1048	0.002	4	0.42	0.002	0.13	0.1	0.53	8.1	1.2	0.19	2	11.8	0.4	N.A.	N.A.	N.A.	N.A.
1091285	Soil	39	3.33	439	0.003	7	0.27	0.007	0.09	0.3	1.02	3.2	1.8	<0.05	<1	10.7	0.3	N.A.	N.A.	N.A.	N.A.
1091286	Soil	10	1.77	132	0.002	5	0.09	0.005	0.04	0.2	0.29	2.9	0.8	<0.05	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091287	Soil	11	1.94	323	0.002	5	0.15	0.005	0.05	0.1	0.58	3.9	0.6	0.07	<1	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091288	Soil	11	1.73	229	0.002	5	0.14	0.003	0.05	0.2	0.52	4.1	1.2	<0.05	<1	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091289	Soil	15	1.97	144	0.002	5	0.12	0.005	0.04	0.2	0.27	3.6	1.6	<0.05	<1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091290	Soil	11	3.08	174	0.002	6	0.12	0.006	0.05	0.2	0.16	2.5	1.2	<0.05	<1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091271	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091272	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091273	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091274	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091275	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091276	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091277	Soil	1.0	33.1	3.0	41	1.21	37.9	13.6	0.4	28	4.1	3.5	0.3	86	0.13	0.100	6	16	0.07	746	0.002
1091278	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091279	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091280	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091281	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091282	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091283	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091284	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091286	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091287	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091288	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091289	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091290	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091271	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091272	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091273	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091274	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091275	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091276	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091277	Soil	<20	0.80	0.011	0.08	0.1	1.00	0.9	0.7	<0.05	3	2.1	<0.2
1091278	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091279	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091280	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091281	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091282	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091283	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091284	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091286	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091287	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091288	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091289	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091290	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091291	Soil	73.1	54.2	6.6	179	0.1	162.5	7.0	116	1.32	19.7	<0.5	2.7	248	1.8	2.2	0.1	38	8.41	0.080	6
1091292	Soil	71.4	49.4	6.1	137	0.1	151.6	6.8	135	1.42	20.5	0.6	2.5	272	1.5	2.4	<0.1	38	10.51	0.074	6
1091293	Soil	72.5	55.4	7.5	135	0.2	149.4	7.4	137	1.63	24.7	<0.5	2.4	229	1.5	4.1	<0.1	33	7.88	0.088	6
1091294	Soil	57.7	39.7	7.6	125	0.1	109.8	7.3	161	1.61	20.1	<0.5	3.2	237	1.4	3.4	<0.1	32	9.13	0.080	6
1091295	Soil	32.6	78.9	18.1	852	1.1	152.2	22.6	279	2.83	33.1	0.9	6.6	75	9.0	17.5	0.2	152	3.02	0.182	16
1091296	Soil	27.8	57.0	17.8	461	0.5	95.2	10.2	114	2.80	29.4	1.7	2.1	21	2.5	8.5	0.2	95	0.29	0.105	11
1091297	Soil	17.5	53.2	12.9	318	0.8	71.2	8.8	176	2.38	22.0	1.7	2.0	98	2.7	6.1	0.2	74	3.54	0.094	7
1091298	Soil	8.7	39.0	16.7	103	1.0	47.3	10.3	222	3.05	17.4	2.7	1.6	45	0.4	2.3	0.2	3	0.77	0.065	9
1091299	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091300	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

Method		1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091291	Soil	11	1.99	205	0.002	5	0.13	0.005	0.05	0.2	0.16	2.9	1.1	0.06	<1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091292	Soil	11	2.23	176	0.001	4	0.13	0.005	0.05	0.2	0.24	2.6	1.1	<0.05	<1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091293	Soil	11	2.22	168	0.002	5	0.14	0.005	0.06	0.2	0.26	2.8	1.0	0.07	<1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091294	Soil	10	3.06	202	0.002	5	0.12	0.006	0.05	0.1	0.25	3.1	0.7	0.06	<1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091295	Soil	24	1.23	274	0.002	6	0.25	0.004	0.09	<0.1	0.32	5.1	0.3	<0.05	<1	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091296	Soil	15	0.09	597	0.002	2	0.37	0.002	0.06	<0.1	0.11	3.3	0.4	<0.05	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091297	Soil	10	1.68	799	0.003	5	0.23	0.005	0.06	<0.1	0.25	3.5	0.2	0.05	<1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091298	Soil	7	0.12	2218	0.005	4	0.53	0.014	0.07	<0.1	0.30	4.1	0.2	0.08	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091299	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.8	25.6	6.3	55
1091300	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.3	24.9	13.2	87

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091291	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091292	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091293	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091294	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091295	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091296	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091297	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091298	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091299	Soil	1.2	20.0	3.5	129	0.86	4.0	4.2	0.1	107	0.4	1.0	0.2	10	1.60	0.073	4	5	0.22	4160	0.004
1091300	Soil	0.6	22.5	11.1	565	3.01	8.0	1.9	0.6	8	0.4	1.3	0.2	28	0.05	0.052	7	10	0.06	677	0.009

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000628.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091291	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091292	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091293	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091294	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091295	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091296	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091297	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091298	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091299	Soil	<20	0.47	0.024	0.05	<0.1	0.24	0.9	0.2	0.11	<1	1.3	<0.2
1091300	Soil	<20	0.68	0.012	0.07	<0.1	0.06	1.5	0.1	<0.05	3	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1091129	Soil	3.7	21.1	13.3	101	1.4	21.0	4.3	136	1.48	33.1	21.3	0.8	36	0.9	5.3	0.3	55	0.12	0.121	9
REP 1091129	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091146	Soil	20.3	41.7	18.8	335	0.6	66.2	7.8	135	2.43	84.5	6.7	2.8	34	1.7	9.1	0.4	114	0.22	0.107	14
REP 1091146	QC	20.4	41.4	19.4	331	0.6	66.5	8.1	134	2.39	84.7	9.6	2.8	33	1.9	9.3	0.3	115	0.21	0.109	14
1091218	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1091218	QC																				
1091226	Soil	41.7	61.3	10.9	471	0.7	142.2	9.0	294	1.89	49.0	2.0	1.5	61	5.5	5.4	0.2	108	1.14	0.102	17
REP 1091226	QC	39.7	59.6	11.0	456	0.7	139.5	9.0	288	1.86	47.0	3.5	1.5	60	5.5	5.6	0.2	104	1.11	0.101	16
1091241	Soil	12.1	32.3	15.8	127	0.3	31.6	4.2	99	1.94	31.8	6.5	1.6	9	0.6	5.2	0.5	60	0.06	0.031	15
REP 1091241	QC	11.4	29.5	11.2	108	0.1	29.9	4.2	81	1.95	34.8	4.2	1.3	7	0.3	4.6	0.2	62	0.05	0.034	16
1091250	Soil	27.0	25.4	27.5	185	1.1	38.3	3.5	71	1.60	49.9	3.7	0.6	26	1.2	13.3	0.5	166	0.07	0.041	13
REP 1091250	QC	28.0	25.5	30.0	188	1.2	39.6	3.7	73	1.66	48.4	5.5	0.6	28	1.2	13.1	0.5	164	0.07	0.041	13
1091196	Soil	32.4	24.3	42.9	152	4.4	34.0	3.7	105	2.85	193.3	67.5	2.2	72	0.4	39.2	0.4	285	0.06	0.186	14
REP 1091196	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091024	Soil	1.4	3.3	3.8	22	0.6	4.8	0.5	9	0.23	2.1	4.3	0.1	6	0.2	0.5	<0.1	12	0.04	0.025	2
REP 1091024	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090296	Soil	3.3	8.7	14.0	33	0.6	9.3	0.9	15	0.54	57.4	62.3	0.2	17	0.3	5.6	0.6	15	0.10	0.041	4
REP 1090296	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091272	Soil	10.2	37.9	14.4	104	0.5	22.3	2.6	39	1.71	30.8	7.4	1.0	42	0.2	6.4	0.2	82	0.06	0.074	6
REP 1091272	QC	10.2	38.2	15.0	106	0.4	23.1	2.8	41	1.86	31.6	5.5	1.0	45	0.4	6.8	0.2	77	0.05	0.076	6
1091291	Soil	73.1	54.2	6.6	179	0.1	162.5	7.0	116	1.32	19.7	<0.5	2.7	248	1.8	2.2	0.1	38	8.41	0.080	6
REP 1091291	QC	74.2	55.3	6.8	177	0.1	167.4	7.3	115	1.37	19.9	<0.5	2.9	244	1.8	2.4	<0.1	41	8.46	0.082	6
Reference Materials																					
STD DS8	Standard	11.4	111.5	123.1	296	1.8	39.4	7.6	565	2.39	26.0	113.1	6.2	59	2.2	5.1	6.0	40	0.68	0.079	12
STD DS8	Standard	11.8	109.2	119.9	304	1.8	38.2	7.3	583	2.37	26.5	110.6	5.8	58	2.2	5.0	5.7	39	0.64	0.077	11
STD DS8	Standard	13.1	108.8	125.2	306	1.8	39.1	7.3	593	2.38	25.1	107.3	6.3	68	2.0	5.4	6.5	41	0.65	0.079	14
STD DS8	Standard	13.5	109.0	128.8	312	1.7	38.0	7.7	600	2.46	25.9	106.7	6.6	68	2.6	5.6	6.9	42	0.67	0.081	14
STD DS8	Standard	13.2	111.4	125.8	311	1.7	38.1	7.6	585	2.40	26.0	102.0	6.9	55	2.2	4.5	5.3	44	0.67	0.078	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000628.2

	Method	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX30	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1091129	Soil	24	0.11	853	0.003	3	0.66	0.005	0.06	0.1	2.34	1.5	0.5	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091129	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1091146	Soil	15	0.10	711	0.005	3	0.77	0.003	0.06	0.3	0.98	2.2	0.3	0.06	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091146	QC	16	0.10	713	0.004	2	0.74	0.003	0.06	0.2	0.82	2.2	0.3	<0.05	2	2.1	0.2				
1091218	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.6	26.0	8.6	242
REP 1091218	QC																	6.4	25.2	8.4	235
1091226	Soil	36	0.16	643	0.005	4	0.72	0.003	0.07	0.3	0.57	6.3	1.1	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091226	QC	34	0.16	617	0.005	2	0.69	0.003	0.07	0.3	0.57	6.3	1.1	<0.05	2	3.3	<0.2				
1091241	Soil	12	0.05	414	0.013	2	0.51	0.009	0.07	0.3	0.18	0.8	0.5	0.10	3	1.2	0.2	N.A.	N.A.	N.A.	N.A.
REP 1091241	QC	9	0.04	467	0.011	2	0.59	0.008	0.06	0.2	0.11	1.4	0.2	0.29	3	1.6	<0.2				
1091250	Soil	12	0.03	264	0.011	1	0.33	0.006	0.06	0.7	0.33	0.6	1.3	0.07	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091250	QC	13	0.04	271	0.011	3	0.30	0.007	0.06	0.7	0.36	0.6	1.3	0.09	3	2.6	0.3				
1091196	Soil	21	0.08	359	0.008	6	0.70	0.002	0.09	1.0	16.78	1.4	1.7	0.09	4	7.4	0.4	N.A.	N.A.	N.A.	N.A.
REP 1091196	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1091024	Soil	4	0.01	37	0.006	<1	0.14	0.015	0.02	<0.1	0.17	0.4	<0.1	<0.05	<1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091024	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1090296	Soil	6	0.02	76	0.004	1	0.17	0.015	0.04	0.3	3.73	0.6	0.6	0.07	<1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090296	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1091272	Soil	15	0.05	770	0.002	<1	0.52	0.003	0.04	0.1	0.50	1.4	0.3	<0.05	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091272	QC	15	0.05	719	0.002	2	0.52	0.003	0.04	0.1	0.57	1.4	0.3	<0.05	2	2.8	<0.2				
1091291	Soil	11	1.99	205	0.002	5	0.13	0.005	0.05	0.2	0.16	2.9	1.1	0.06	<1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091291	QC	12	2.06	208	0.002	5	0.14	0.005	0.06	0.2	0.14	2.8	1.1	0.06	<1	1.7	<0.2				
Reference Materials																					
STD DS8	Standard	115	0.57	243	0.099	4	0.86	0.101	0.41	3.0	0.21	3.0	5.2	0.12	4	5.5	4.3				
STD DS8	Standard	113	0.57	233	0.096	2	0.84	0.100	0.40	2.6	0.18	3.0	5.2	0.10	4	5.3	5.0				
STD DS8	Standard	114	0.61	268	0.113	2	0.91	0.089	0.40	2.8	0.17	2.3	5.1	0.16	4	5.9	4.7				
STD DS8	Standard	116	0.62	283	0.115	3	0.93	0.094	0.41	2.8	0.22	2.5	5.4	0.13	5	6.0	5.5				
STD DS8	Standard	119	0.59	257	0.108	2	0.87	0.081	0.40	2.6	0.22	1.9	5.2	0.17	4	4.5	4.9				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000628.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1091129	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091129	QC																					
1091146	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091146	QC																					
1091218	Soil		1.0	31.7	3.3	69	1.29	29.8	8.0	0.1	30	2.6	1.4	0.2	64	0.37	0.065	5	15	0.10	888	0.002
REP 1091218	QC		0.9	30.9	3.3	66	1.26	29.3	11.7	0.1	31	2.6	1.4	0.2	61	0.36	0.062	5	14	0.10	860	0.002
1091226	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091226	QC																					
1091241	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091241	QC																					
1091250	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091250	QC																					
1091196	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091196	QC																					
1091024	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091024	QC																					
1090296	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090296	QC																					
1091272	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091272	QC																					
1091291	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091291	QC																					
Reference Materials																						
STD DS8	Standard																					
STD DS8	Standard																					
STD DS8	Standard																					
STD DS8	Standard																					
STD DS8	Standard																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000628.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1091129	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091129	QC													
1091146	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091146	QC													
1091218	Soil		<20	0.69	0.021	0.08	0.1	0.59	0.7	0.3	<0.05	2	1.0	<0.2
REP 1091218	QC		<20	0.68	0.020	0.08	0.1	0.59	0.6	0.3	<0.05	2	0.9	<0.2
1091226	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091226	QC													
1091241	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091241	QC													
1091250	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091250	QC													
1091196	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091196	QC													
1091024	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091024	QC													
1090296	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090296	QC													
1091272	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091272	QC													
1091291	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091291	QC													
Reference Materials														
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000628.2

		1DX30 Mo ppm 0.1	1DX30 Cu ppm 0.1	1DX30 Pb ppm 0.1	1DX30 Zn ppm 1	1DX30 Ag ppm 0.1	1DX30 Ni ppm 0.1	1DX30 Co ppm 0.1	1DX30 Mn ppm 1	1DX30 Fe % 0.01	1DX30 As ppm 0.5	1DX30 Au ppb 0.5	1DX30 Th ppm 0.1	1DX30 Sr ppm 1	1DX30 Cd ppm 0.1	1DX30 Sb ppm 0.1	1DX30 Bi ppm 0.1	1DX30 V ppm 2	1DX30 Ca % 0.01	1DX30 P % 0.001	1DX30 La ppm 1
STD DS8	Standard	12.8	113.7	127.3	313	1.8	39.3	7.9	612	2.45	26.0	109.6	6.7	53	2.4	4.7	5.6	45	0.68	0.078	13
STD DS8	Standard	13.5	115.3	130.5	323	1.9	41.0	8.0	633	2.58	26.8	119.3	6.6	62	2.6	5.5	6.4	43	0.69	0.082	14
STD DS8	Standard	13.5	120.1	130.2	333	1.8	42.0	8.2	640	2.59	27.5	120.0	6.7	64	2.5	5.5	6.4	46	0.70	0.086	14
STD DS8	Standard	13.2	107.5	122.1	318	1.8	36.4	7.2	626	2.52	26.1	121.4	6.7	69	2.3	5.2	6.9	42	0.70	0.081	15
STD DS8	Standard	12.4	107.6	121.2	313	1.8	37.5	7.3	643	2.55	25.9	115.6	6.9	70	2.1	4.9	6.8	42	0.70	0.081	15
STD DS8	Standard	11.2	104.4	118.9	315	1.9	36.7	7.4	619	2.47	27.3	108.0	5.9	65	2.4	5.3	7.1	39	0.66	0.082	11
STD DS8	Standard	11.3	109.3	123.9	328	1.8	35.7	7.4	621	2.52	27.8	125.2	6.2	65	2.4	5.1	7.2	40	0.67	0.083	12
STD DS8	Standard	12.7	100.0	114.7	296	1.7	35.9	6.9	553	2.35	25.7	110.5	6.2	58	2.2	5.6	6.3	35	0.62	0.069	13
STD DS8	Standard	14.2	101.0	112.3	370	1.7	44.2	7.1	545	2.26	24.7	93.8	5.8	59	3.8	6.0	5.8	39	0.66	0.072	13
STD DS8	Standard	12.9	109.2	131.1	306	1.8	37.2	7.4	626	2.47	26.7	103.9	7.0	73	2.4	5.2	5.4	42	0.71	0.078	15
STD DS8	Standard																				
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000628.2

		1DX30 Cr ppm 1	1DX30 Mg % 0.01	1DX30 Ba ppm 1	1DX30 Ti % 0.001	1DX30 B ppm 1	1DX30 Al % 0.01	1DX30 Na % 0.001	1DX30 K % 0.01	1DX30 W ppm 0.1	1DX30 Hg ppm 0.01	1DX30 Sc ppm 0.1	1DX30 Tl ppm 0.1	1DX30 S % 0.05	1DX30 Ga ppm 1	1DX30 Se ppm 0.5	1DX30 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
STD DS8	Standard	123	0.60	259	0.110	2	0.88	0.085	0.40	2.9	0.19	2.0	5.0	0.17	4	4.9	5.2				
STD DS8	Standard	119	0.62	271	0.117	2	0.92	0.087	0.42	3.1	0.23	2.3	5.6	0.17	5	4.8	5.1				
STD DS8	Standard	124	0.64	284	0.117	3	0.95	0.088	0.44	3.0	0.24	2.5	5.4	0.19	5	5.3	5.2				
STD DS8	Standard	118	0.61	270	0.105	3	0.90	0.088	0.42	2.6	0.17	2.3	5.3	0.14	5	5.6	5.7				
STD DS8	Standard	117	0.63	265	0.113	2	0.91	0.094	0.42	2.7	0.20	2.3	5.4	0.14	5	5.2	5.1				
STD DS8	Standard	112	0.60	263	0.096	3	0.88	0.090	0.42	2.9	0.23	2.2	5.5	0.13	5	5.6	5.2				
STD DS8	Standard	114	0.63	279	0.105	2	0.91	0.097	0.44	3.0	0.21	2.4	5.9	0.14	5	5.8	5.3				
STD DS8	Standard	104	0.55	297	0.097	3	0.80	0.085	0.38	2.8	0.22	2.0	4.8	0.22	4	4.9	4.6				
STD DS8	Standard	101	0.52	297	0.094	3	0.83	0.081	0.37	2.5	0.24	1.8	4.6	0.18	4	5.3	4.2				
STD DS8	Standard	113	0.61	299	0.115	2	0.95	0.115	0.43	3.1	0.19	2.8	5.1	0.08	5	5.4	5.2				
STD DS8	Standard																	13.3	108.0	122.0	317
STD DS8	Standard																	14.0	117.3	126.8	318
STD OREAS45CA	Standard																	1.0	462.6	21.0	55
STD OREAS45CA	Standard																	0.9	488.6	19.7	59
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000628.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.6	36.7	7.5	602	2.40	26.4	121.3	7.7	71	2.6	5.2	5.9	43	0.70	0.081	16	112	0.61	308	0.116
STD DS8	Standard	1.8	39.4	8.1	635	2.63	26.5	96.8	6.8	71	2.4	4.8	6.4	45	0.75	0.089	15	116	0.65	304	0.118
STD OREAS45CA	Standard	0.2	223.7	83.6	873	15.59	4.3	47.2	7.1	15	0.1	0.1	0.2	202	0.39	0.036	15	688	0.13	163	0.134
STD OREAS45CA	Standard	0.3	244.6	87.8	897	16.02	4.1	39.3	6.6	15	<0.1	<0.1	0.2	187	0.41	0.039	15	659	0.15	151	0.144
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000628.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.94	0.099	0.46	2.8	0.20	2.1	5.4	0.14	5	5.6	5.3
STD DS8	Standard	<20	0.99	0.096	0.44	3.0	0.21	2.4	5.5	0.17	5	6.3	5.3
STD OREAS45CA	Standard	<20	3.61	0.010	0.07	<0.1	<0.01	33.3	<0.1	<0.05	18	0.7	<0.2
STD OREAS45CA	Standard	<20	4.00	0.013	0.07	<0.1	0.01	39.0	<0.1	<0.05	18	0.6	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 20, 2011
Report Date: September 02, 2011
Page: 1 of 11

CERTIFICATE OF ANALYSIS WHI11000671.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #4
P.O. Number
Number of Samples: 279

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	279	Sieve to 230 mesh			WHI
1DX2	265	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	14	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: Includes 1DX analysis and Corrected sample ID's (1090841 - 1090850)

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090841	Soil	1.7	65.1	12.7	36	0.3	55.0	19.5	477	4.86	10.7	1.9	3.0	6	0.2	1.5	0.6	15	0.07	0.035	22
1090842	Soil	12.4	45.3	28.7	154	1.2	57.9	13.2	799	4.03	27.9	6.3	2.4	37	0.9	4.3	0.4	18	0.99	0.078	11
1090843	Soil	3.6	35.2	15.3	78	0.2	38.2	13.7	453	3.43	20.2	2.9	1.9	17	0.2	2.7	0.4	16	0.32	0.047	7
1090844	Soil	4.4	30.6	7.6	243	1.0	41.3	4.7	102	1.55	6.7	<0.5	1.9	30	2.2	4.6	0.3	26	1.05	0.071	7
1090845	Soil	2.7	16.6	5.4	51	0.1	15.9	2.3	11	0.88	7.9	1.4	0.4	2	<0.1	1.5	0.2	22	0.02	0.044	9
1090846	Soil	3.4	97.0	12.6	407	1.0	92.3	10.2	65	2.91	14.9	2.4	1.3	38	0.4	3.3	0.3	26	0.20	0.177	20
1090847	Soil	6.3	17.9	3.7	133	0.9	18.6	2.2	59	0.68	10.2	1.1	0.5	36	2.3	2.5	0.3	28	0.65	0.054	4
1090848	Soil	17.9	26.9	10.6	471	0.2	51.3	8.4	166	1.71	25.1	3.0	1.7	24	7.8	9.9	0.2	104	0.34	0.052	10
1090849	Soil	47.9	26.8	24.7	886	0.3	77.1	11.2	1159	4.83	21.8	0.5	1.3	71	4.9	12.3	0.2	107	1.14	0.119	13
1090850	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090901	Soil	6.5	51.2	14.3	94	0.9	18.7	2.9	87	1.62	18.5	8.3	1.2	185	2.2	2.6	0.3	102	0.09	0.155	6
1090902	Soil	5.8	25.6	16.2	86	0.6	14.3	2.8	85	3.05	22.8	4.1	1.3	35	1.1	2.4	0.3	94	0.04	0.085	8
1090903	Soil	6.7	11.6	18.7	152	7.7	15.2	1.7	24	1.22	16.0	2.7	<0.1	27	0.1	7.6	0.3	71	0.02	0.051	5
1090904	Soil	21.8	58.6	13.0	282	2.0	62.6	6.6	307	2.10	23.7	4.6	0.4	151	6.7	7.9	0.3	78	1.31	0.225	6
1090905	Soil	1.0	9.4	2.8	8	1.8	5.6	0.4	9	0.42	2.6	8.4	<0.1	12	0.5	0.5	<0.1	9	0.11	0.053	1
1090906	Soil	5.8	53.9	14.6	117	1.6	23.4	3.4	73	1.81	16.1	5.0	0.3	51	1.5	2.5	0.2	77	0.16	0.092	7
1090907	Soil	1.8	17.3	5.6	53	0.8	9.3	1.5	18	0.85	4.9	1.5	0.2	6	1.1	0.5	0.1	36	0.02	0.027	4
1090908	Soil	6.7	23.8	12.7	137	0.5	26.4	4.4	82	2.09	21.9	2.9	1.5	23	0.4	3.0	0.2	92	0.05	0.056	8
1090909	Soil	2.5	26.0	16.7	1643	1.1	147.8	15.7	818	4.61	24.2	5.7	0.8	56	6.2	5.5	0.3	92	2.03	0.211	26
1090910	Soil	0.6	21.7	2.9	50	0.5	16.5	2.3	267	0.53	3.6	1.8	0.1	67	1.0	0.7	0.1	24	1.76	0.053	3
1090911	Soil	0.8	10.4	2.9	71	0.2	12.0	1.7	53	0.50	4.4	1.4	0.2	82	1.7	0.9	0.1	10	2.53	0.056	3
1090912	Soil	1.8	35.9	8.9	158	0.6	53.0	7.1	254	1.65	11.2	6.0	0.5	76	1.3	1.7	0.2	25	1.90	0.063	4
1090913	Soil	2.0	36.6	8.1	64	0.7	26.8	3.1	82	1.55	9.3	5.4	0.8	67	0.4	1.7	0.2	27	1.26	0.047	4
1090914	Soil	1.3	153.0	10.2	105	0.7	43.4	7.5	295	1.46	7.9	4.8	0.4	139	0.8	1.5	0.2	22	2.59	0.066	4
1090915	Soil	1.0	170.6	8.3	167	0.8	49.3	4.8	159	1.42	5.7	6.8	0.2	119	1.7	1.0	0.2	23	1.69	0.085	4
1090916	Soil	1.4	22.1	6.0	69	0.3	11.2	2.0	78	0.94	4.3	1.5	0.3	65	0.5	0.9	0.1	22	0.98	0.058	3
1090917	Soil	4.5	15.3	14.7	84	0.6	17.0	3.6	110	2.80	19.0	1.9	0.9	13	0.2	1.5	0.2	69	0.03	0.058	8
1090918	Soil	1.4	64.9	10.9	149	0.8	49.4	9.0	976	3.93	10.5	7.4	0.9	142	1.1	1.0	0.2	30	1.32	0.105	4
1090919	Soil	2.6	84.2	11.8	61	0.5	48.2	7.9	295	5.30	27.1	8.3	1.1	80	0.5	1.6	0.2	44	0.31	0.134	4
1090920	Soil	2.3	43.0	10.7	147	0.8	36.1	7.3	224	2.39	11.1	4.9	1.0	54	0.4	1.2	0.2	40	0.32	0.089	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090841	Soil	9	0.05	218	0.004	6	0.42	0.006	0.09	<0.1	0.03	2.9	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090842	Soil	9	0.16	387	0.002	8	0.43	0.007	0.10	<0.1	0.40	5.6	0.2	<0.05	<1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090843	Soil	7	0.07	466	0.004	7	0.49	0.007	0.09	<0.1	0.06	2.7	0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090844	Soil	6	0.36	224	0.003	4	0.22	0.011	0.04	<0.1	0.14	2.2	<0.1	<0.05	<1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090845	Soil	6	0.02	90	0.001	2	0.34	0.001	0.04	<0.1	0.04	0.3	<0.1	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090846	Soil	8	0.02	138	0.002	3	0.29	0.001	0.07	<0.1	0.09	1.4	<0.1	<0.05	<1	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090847	Soil	4	0.10	1150	0.006	3	0.34	0.020	0.03	<0.1	0.18	1.4	<0.1	<0.05	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090848	Soil	12	0.07	546	0.004	2	0.44	0.006	0.06	<0.1	0.12	2.2	0.2	<0.05	1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090849	Soil	23	0.21	2088	0.008	3	0.79	0.005	0.05	0.2	0.14	3.4	0.2	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090850	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	9.4	18.8	10.0	351
1090901	Soil	19	0.09	1034	0.004	3	0.82	0.003	0.09	0.1	0.53	2.0	0.5	0.06	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090902	Soil	19	0.12	362	0.006	2	0.92	0.004	0.07	0.2	0.24	1.3	0.3	<0.05	4	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090903	Soil	11	0.02	231	0.003	2	0.34	0.003	0.06	0.2	0.04	0.3	0.6	0.08	3	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090904	Soil	18	0.10	943	0.004	3	0.82	0.005	0.10	0.3	0.66	1.3	1.4	0.24	2	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090905	Soil	3	0.01	167	0.001	1	0.32	0.024	0.02	<0.1	0.30	0.2	<0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090906	Soil	17	0.09	2386	0.004	4	0.84	0.006	0.08	0.2	0.41	0.9	0.3	0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090907	Soil	8	0.01	117	0.003	2	0.31	0.007	0.04	<0.1	0.04	0.6	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090908	Soil	15	0.06	1074	0.003	2	0.56	0.003	0.06	0.1	0.15	1.2	0.2	0.06	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090909	Soil	59	0.15	903	0.009	5	1.86	0.007	0.07	0.3	1.98	3.2	0.1	<0.05	4	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090910	Soil	6	0.04	789	0.006	2	0.47	0.024	0.03	<0.1	0.16	0.5	<0.1	0.05	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090911	Soil	7	0.05	545	0.011	3	0.51	0.020	0.02	<0.1	0.09	0.4	<0.1	0.10	<1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090912	Soil	15	0.11	1952	0.003	3	0.78	0.009	0.04	<0.1	0.33	1.3	<0.1	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090913	Soil	14	0.08	1911	0.005	6	0.67	0.010	0.06	<0.1	0.19	1.8	0.1	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090914	Soil	14	0.15	1239	0.006	3	0.79	0.011	0.04	<0.1	0.24	1.5	0.1	0.08	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090915	Soil	21	0.17	1009	0.009	2	0.96	0.010	0.05	<0.1	0.32	1.6	<0.1	<0.05	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090916	Soil	10	0.10	463	0.004	2	0.53	0.017	0.04	<0.1	0.10	0.8	<0.1	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090917	Soil	16	0.09	198	0.006	<1	0.80	0.004	0.05	0.1	0.05	1.0	0.2	<0.05	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090918	Soil	22	0.25	886	0.002	3	1.05	0.006	0.04	<0.1	0.37	2.5	0.1	0.11	2	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090919	Soil	23	0.18	777	0.002	4	0.95	0.005	0.04	<0.1	0.28	2.6	0.2	0.22	2	13.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090920	Soil	16	0.15	1316	0.003	2	1.16	0.012	0.05	<0.1	0.38	2.0	0.2	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090841	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090842	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090843	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090844	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090845	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090846	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090847	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090848	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090849	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090850	Soil	0.4	40.1	5.3	499	2.11	17.3	2.3	0.5	93	4.6	6.5	<0.1	119	2.08	0.096	8	17	0.82	798	0.006
1090901	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090902	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090903	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090904	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090905	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090906	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090907	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090908	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090909	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090910	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090911	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090912	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090913	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090914	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090915	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090916	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090917	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090918	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090919	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090920	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090841	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090842	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090843	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090844	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090845	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090846	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090847	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090848	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090849	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090850	Soil	<20	0.50	0.021	0.04	<0.1	0.17	2.8	0.1	0.06	1	1.9	<0.2
1090901	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090902	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090903	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090904	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090905	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090906	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090907	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090908	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090909	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090910	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090911	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090912	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090913	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090914	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090915	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090916	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090917	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090918	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090919	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090920	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090921	Soil	4.4	33.4	14.0	112	0.6	27.3	5.3	102	3.18	17.2	1.5	1.8	12	0.4	1.4	0.3	64	0.03	0.033	7
1090922	Soil	11.8	43.5	17.9	181	0.8	37.7	5.1	116	2.46	32.7	5.3	0.4	51	0.6	5.4	0.2	82	0.12	0.111	9
1090923	Soil	11.5	29.4	21.8	223	0.6	39.6	5.5	96	2.50	28.8	3.7	1.2	34	0.6	4.0	0.2	89	0.04	0.073	9
1090924	Soil	0.6	6.1	1.5	9	0.8	1.4	0.5	11	0.27	1.6	<0.5	<0.1	5	<0.1	0.3	<0.1	9	0.03	0.019	2
1090925	Soil	5.6	21.2	12.6	81	0.6	16.9	3.6	81	2.24	21.9	3.2	0.5	10	0.2	2.1	0.4	90	0.02	0.045	9
1090926	Soil	3.2	13.8	6.5	25	1.3	7.2	1.3	25	0.90	9.4	2.8	<0.1	6	0.2	2.4	0.2	61	0.02	0.043	3
1090927	Soil	10.9	43.4	19.9	198	1.9	32.7	5.3	125	3.26	23.9	4.4	0.2	52	1.3	5.2	<0.1	147	0.05	0.226	10
1090928	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090929	Soil	18.9	48.9	26.0	121	2.9	29.3	3.4	124	1.66	18.5	7.4	0.8	153	1.6	11.3	<0.1	83	0.11	0.128	5
1090930	Soil	3.3	9.9	6.2	35	0.4	8.4	1.9	30	1.04	8.2	<0.5	0.4	5	<0.1	0.9	<0.1	44	0.01	0.025	6
1090931	Soil	6.3	17.8	12.4	79	0.3	18.5	3.3	76	2.24	14.5	0.6	1.6	8	0.3	1.7	<0.1	69	0.01	0.051	8
1090932	Soil	3.7	19.4	8.9	39	0.3	8.6	1.7	32	0.95	9.3	<0.5	0.1	10	0.3	0.7	<0.1	42	0.02	0.041	7
1090933	Soil	5.1	80.6	10.3	79	1.1	13.6	2.6	61	3.09	10.3	4.6	0.2	10	0.6	1.3	<0.1	45	0.02	0.090	4
1090934	Soil	5.3	49.8	16.6	91	2.4	16.2	3.7	66	1.69	14.1	5.4	0.7	18	0.7	1.1	<0.1	61	0.03	0.107	6
1090935	Soil	1.9	18.1	5.3	60	0.5	15.5	2.2	43	0.92	5.7	2.0	0.2	21	0.6	1.0	<0.1	24	0.29	0.059	3
1090936	Soil	1.4	23.5	5.9	67	0.5	18.2	3.5	125	1.05	8.3	<0.5	0.4	57	0.2	1.1	<0.1	37	2.27	0.104	4
1090937	Soil	3.2	19.2	6.8	84	0.5	13.8	2.2	44	1.17	8.1	3.4	0.3	16	1.0	1.4	0.1	37	0.19	0.093	4
1090938	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090939	Soil	1.6	12.5	5.0	33	0.5	7.5	1.2	21	0.59	2.5	2.3	0.3	7	0.3	0.5	<0.1	23	0.03	0.049	2
1090940	Soil	3.1	78.6	9.6	277	0.6	49.6	7.9	246	1.95	11.9	5.9	1.0	57	3.2	2.0	0.2	50	0.99	0.141	7
1090941	Soil	6.4	45.1	17.6	163	0.4	37.1	4.5	67	3.42	19.4	<0.5	1.6	14	0.8	2.5	<0.1	55	0.02	0.041	6
1090942	Soil	3.7	66.9	11.1	246	0.6	51.1	7.2	196	2.22	10.6	6.1	1.0	74	1.9	1.8	<0.1	45	1.02	0.110	7
1090943	Soil	0.6	5.1	3.5	30	1.1	4.0	3.8	146	0.81	1.7	<0.5	0.2	19	0.8	0.3	<0.1	15	0.26	0.040	2
1090944	Soil	2.4	25.9	10.3	107	0.5	25.1	6.8	245	1.92	7.3	2.5	1.0	69	1.3	1.1	<0.1	32	1.58	0.068	4
1090945	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090946	Soil	4.5	28.6	10.0	125	0.5	24.4	3.8	74	1.79	10.2	2.5	0.4	38	1.0	1.6	<0.1	44	0.52	0.045	6
1090947	Soil	5.9	23.9	15.2	99	0.3	21.4	3.8	73	2.06	14.7	<0.5	0.7	13	0.3	2.2	<0.1	72	0.02	0.075	4
1090948	Soil	5.0	22.2	11.9	76	0.5	16.2	2.5	45	1.14	10.2	<0.5	0.3	15	0.4	1.8	<0.1	52	0.01	0.077	4
1090949	Soil	6.5	42.8	16.2	234	<0.1	45.7	12.7	375	2.90	19.2	3.0	2.4	29	0.8	2.8	<0.1	69	0.09	0.087	8
1090950	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090921	Soil	21	0.13	689	0.003	1	1.09	0.003	0.05	<0.1	0.05	1.6	0.2	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090922	Soil	17	0.10	1365	0.003	3	0.71	0.004	0.06	0.2	0.43	1.0	0.4	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090923	Soil	13	0.06	613	0.004	1	0.68	0.004	0.05	0.1	0.09	1.4	0.4	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090924	Soil	2	0.01	61	0.004	<1	0.33	0.018	0.02	<0.1	0.31	<0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090925	Soil	11	0.05	300	0.004	1	0.72	0.002	0.06	0.1	0.19	0.8	0.3	<0.05	4	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090926	Soil	8	0.02	139	0.008	2	0.36	0.010	0.03	<0.1	0.08	0.2	0.2	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090927	Soil	24	0.09	669	0.003	3	0.83	0.003	0.08	0.2	0.14	0.2	0.5	0.08	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090928	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.0	35.4	20.9	136
1090929	Soil	16	0.06	2747	0.002	2	1.16	0.003	0.06	0.3	0.67	2.2	1.3	<0.05	3	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090930	Soil	6	0.03	311	0.004	1	0.44	0.005	0.02	<0.1	0.02	0.3	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090931	Soil	13	0.06	367	0.003	1	0.77	0.003	0.04	<0.1	0.06	0.9	0.2	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090932	Soil	8	0.03	213	0.003	<1	0.66	0.005	0.03	<0.1	0.02	0.2	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090933	Soil	21	0.05	239	0.003	3	0.65	0.005	0.04	<0.1	0.11	0.4	<0.1	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090934	Soil	17	0.04	484	0.003	3	0.68	0.003	0.06	0.2	0.63	1.5	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090935	Soil	9	0.07	874	0.005	3	0.54	0.013	0.03	<0.1	0.15	0.5	<0.1	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090936	Soil	13	0.12	846	0.006	3	0.86	0.011	0.03	0.1	0.29	0.7	<0.1	0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090937	Soil	10	0.05	554	0.003	2	0.53	0.008	0.04	<0.1	0.07	0.6	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090938	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090939	Soil	9	0.03	357	0.005	2	0.38	0.011	0.03	<0.1	0.06	0.7	<0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090940	Soil	23	0.23	1415	0.005	6	1.13	0.006	0.07	0.1	0.78	3.4	0.3	0.11	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090941	Soil	13	0.04	1949	0.003	<1	0.60	0.002	0.05	0.1	0.06	1.9	0.1	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090942	Soil	21	0.19	2535	0.004	3	1.03	0.006	0.05	0.1	0.41	2.6	0.2	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090943	Soil	8	0.02	313	0.007	<1	0.41	0.027	0.02	<0.1	0.07	0.5	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090944	Soil	19	0.23	2516	0.002	2	0.85	0.006	0.04	<0.1	0.14	1.5	0.1	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090945	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.1	26.1	8.2	91
1090946	Soil	11	0.04	2653	0.004	2	0.51	0.006	0.05	<0.1	0.04	0.9	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090947	Soil	25	0.07	124	0.005	<1	0.58	0.005	0.04	0.1	0.05	0.9	0.2	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090948	Soil	11	0.04	198	0.004	<1	0.46	0.009	0.04	<0.1	0.11	0.5	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090949	Soil	24	0.20	854	0.002	3	0.91	0.002	0.05	0.1	0.07	2.1	0.2	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090950	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.2	46.9	9.7	231

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090921	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090922	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090923	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090924	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090925	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090926	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090927	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090928	Soil	0.1	28.1	7.1	173	4.68	37.2	2.1	0.5	17	0.4	0.8	0.3	34	0.03	0.090	3	9	0.03	244	0.001
1090929	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090930	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090931	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090932	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090933	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090934	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090935	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090936	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090937	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090938	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090939	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090940	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090941	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090942	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090943	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090944	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090945	Soil	0.4	21.4	3.5	49	1.31	5.5	3.7	0.5	46	1.3	0.7	0.2	29	0.60	0.075	7	16	0.13	2560	0.002
1090946	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090947	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090948	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090949	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090950	Soil	0.6	45.6	5.4	193	1.78	14.2	4.1	0.7	126	3.2	2.0	0.2	62	1.27	0.090	5	17	0.17	861	0.002

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090921	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090922	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090923	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090924	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090925	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090926	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090927	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090928	Soil	<20	0.38	0.004	0.05	<0.1	0.04	3.8	0.3	<0.05	1	2.3	<0.2
1090929	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090930	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090931	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090932	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090933	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090934	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090935	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090936	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090937	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090938	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090939	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090940	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090941	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090942	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090943	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090944	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090945	Soil	<20	0.78	0.006	0.04	<0.1	0.17	1.5	0.1	0.09	2	1.4	<0.2
1090946	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090947	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090948	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090949	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090950	Soil	<20	0.86	0.010	0.07	0.1	0.35	2.0	0.2	0.09	2	2.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090951	Soil	5.0	29.5	15.4	134	0.2	25.3	7.0	221	3.58	23.9	4.9	3.0	18	0.5	2.2	<0.1	88	0.10	0.148	10
1090952	Soil	3.8	18.4	13.1	70	0.2	14.1	3.2	79	1.43	13.7	4.0	0.7	17	0.7	1.7	<0.1	61	0.16	0.057	11
1090953	Soil	7.7	47.3	14.2	215	0.5	45.3	7.1	187	2.89	28.2	6.3	2.1	38	1.2	3.2	<0.1	70	0.33	0.133	7
1090954	Soil	4.4	43.1	12.7	183	0.3	41.4	10.8	258	2.97	21.9	3.1	2.6	52	0.7	2.0	<0.1	59	0.40	0.101	8
1090955	Soil	5.2	27.7	7.5	68	<0.1	15.0	4.5	75	1.48	20.7	2.6	0.5	12	0.3	2.2	<0.1	72	0.05	0.028	5
1090956	Soil	4.0	37.7	15.1	85	0.2	19.3	4.7	125	3.64	13.5	2.7	2.4	8	0.3	1.3	<0.1	61	0.02	0.042	6
1090957	Soil	4.9	21.7	15.5	81	0.3	19.2	4.4	134	3.01	17.1	3.2	2.5	12	0.3	1.7	<0.1	76	0.03	0.051	8
1090958	Soil	5.4	40.4	16.2	117	0.5	28.1	5.4	91	2.62	19.1	5.8	2.4	20	0.4	2.2	<0.1	51	0.03	0.047	7
1090959	Soil	5.3	46.2	16.7	113	0.4	27.3	4.8	98	2.50	17.9	8.1	1.9	25	0.4	2.0	<0.1	50	0.06	0.066	7
1090960	Soil	5.5	44.5	16.6	102	1.1	24.0	3.7	69	2.42	17.1	6.4	1.0	32	0.3	2.0	<0.1	53	0.06	0.097	5
1090961	Soil	7.9	47.9	20.5	135	0.5	32.9	4.7	121	2.70	22.2	3.5	1.9	35	0.4	3.1	0.6	50	0.05	0.071	8
1090962	Soil	5.1	36.6	18.0	140	0.9	44.7	10.8	438	3.19	20.4	8.2	2.6	41	0.6	2.0	0.4	56	0.22	0.098	9
1090963	Soil	5.3	40.1	17.0	142	0.3	29.1	5.5	140	2.87	26.3	6.5	3.0	21	0.6	2.6	0.4	44	0.10	0.087	8
1090964	Soil	5.7	19.9	17.4	99	0.2	20.1	3.8	92	2.80	27.6	1.5	2.1	16	0.3	2.2	0.4	70	0.04	0.107	7
1090965	Soil	3.2	47.5	18.4	199	0.3	65.3	12.1	340	3.55	14.0	1.3	1.5	7	0.5	1.3	0.4	22	0.02	0.091	2
1090966	Soil	4.8	20.2	16.7	94	0.3	18.9	3.8	94	2.54	21.5	1.9	1.7	14	0.3	2.0	0.3	59	0.03	0.101	6
1090967	Soil	4.2	35.6	15.1	94	0.6	20.1	6.2	202	3.04	13.5	3.2	1.5	12	<0.1	1.3	0.2	43	0.02	0.041	4
1090968	Soil	3.1	29.0	12.1	38	1.3	5.5	1.1	20	5.04	28.9	<0.5	1.1	16	0.1	2.6	0.3	63	0.01	0.085	3
1090969	Soil	5.9	15.9	14.8	100	<0.1	19.6	4.0	109	2.46	22.8	5.4	1.4	12	0.3	1.9	0.3	72	0.03	0.049	10
1090970	Soil	5.8	18.1	13.6	121	0.2	22.7	4.6	90	2.28	19.8	3.8	1.9	16	0.2	1.9	0.2	50	0.04	0.030	8
1090971	Soil	3.9	15.3	15.6	152	0.4	28.9	5.4	73	2.50	21.8	2.7	2.4	15	0.5	1.5	0.2	74	0.06	0.037	10
1090972	Soil	4.7	25.6	16.9	116	0.7	25.4	3.5	78	2.08	34.5	6.9	1.1	49	0.5	2.5	0.2	42	0.34	0.072	4
1090973	Soil	5.7	49.4	14.4	160	0.4	37.0	7.8	203	2.91	21.9	7.4	1.9	51	1.4	3.4	0.2	64	0.19	0.109	9
1090974	Soil	7.4	53.0	16.1	242	0.6	50.7	8.6	221	2.96	27.4	5.8	1.9	50	2.2	3.9	0.2	65	0.24	0.118	10
1090975	Soil	10.9	66.3	21.3	290	0.4	64.9	15.7	320	3.66	34.6	6.5	3.7	38	2.2	4.0	0.3	77	0.11	0.122	10
1090976	Soil	4.5	18.6	10.1	40	0.6	6.7	1.9	29	0.77	7.8	0.8	<0.1	17	0.4	1.3	0.2	44	0.02	0.046	7
1090977	Soil	2.1	13.1	4.1	46	1.1	9.1	1.4	29	0.65	4.3	<0.5	0.1	25	0.3	1.2	<0.1	26	0.34	0.053	2
1090979	Soil	6.2	11.4	11.1	65	0.2	22.5	1.6	22	0.72	6.5	<0.5	0.4	48	3.3	1.4	0.2	17	0.53	0.049	2
1090980	Soil	13.3	32.3	13.9	41	5.8	10.6	1.9	24	1.08	9.0	<0.5	<0.1	20	0.5	2.9	0.2	115	0.02	0.046	7
1090981	Soil	15.2	7.1	8.9	25	1.5	3.9	0.8	13	0.63	6.8	<0.5	<0.1	14	<0.1	3.8	<0.1	76	0.02	0.022	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090951	Soil	23	0.21	422	0.004	1	1.30	0.003	0.09	0.2	0.07	1.8	0.3	<0.05	4	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090952	Soil	14	0.09	960	0.004	<1	0.83	0.004	0.06	0.1	0.04	0.7	0.2	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090953	Soil	21	0.23	1451	0.002	1	0.83	0.003	0.06	0.2	0.22	2.2	0.3	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090954	Soil	27	0.36	1679	0.005	2	1.15	0.004	0.07	0.2	0.17	2.2	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090955	Soil	7	0.03	2435	0.003	<1	0.31	0.003	0.03	0.1	0.09	0.7	0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090956	Soil	28	0.22	464	0.004	2	1.39	0.003	0.05	0.1	0.09	1.9	0.2	<0.05	5	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090957	Soil	19	0.15	329	0.007	<1	1.11	0.003	0.05	0.1	0.03	1.4	0.2	<0.05	5	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090958	Soil	21	0.16	830	0.003	<1	0.93	0.004	0.05	0.1	0.10	1.6	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090959	Soil	20	0.16	882	0.002	1	0.97	0.004	0.06	0.1	0.20	1.6	0.2	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090960	Soil	20	0.15	1431	0.002	2	0.90	0.004	0.06	0.1	0.32	1.2	0.3	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090961	Soil	21	0.15	629	0.002	1	0.75	0.003	0.06	<0.1	0.37	2.1	0.2	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090962	Soil	26	0.23	1476	0.002	3	1.17	0.004	0.06	0.1	0.53	3.2	0.2	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090963	Soil	19	0.17	204	0.002	2	0.98	0.002	0.05	0.1	0.14	1.9	0.2	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090964	Soil	18	0.10	162	0.003	3	0.87	0.003	0.05	0.1	0.04	1.2	0.2	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090965	Soil	23	0.14	196	0.004	2	0.70	0.005	0.04	<0.1	0.02	3.1	<0.1	<0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090966	Soil	14	0.08	139	0.003	3	0.57	0.002	0.05	0.1	0.02	1.2	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090967	Soil	20	0.12	252	0.002	1	0.90	0.005	0.05	0.1	<0.01	1.6	<0.1	<0.05	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090968	Soil	23	0.03	145	0.003	1	0.57	0.005	0.05	<0.1	0.05	0.8	<0.1	<0.05	4	6.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090969	Soil	16	0.10	135	0.010	1	0.69	0.003	0.04	0.1	0.02	0.9	0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090970	Soil	15	0.12	194	0.005	<1	0.68	0.005	0.04	0.2	0.01	1.2	0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090971	Soil	18	0.14	206	0.007	2	0.94	0.002	0.05	0.1	0.04	1.4	0.2	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090972	Soil	20	0.06	558	0.001	3	0.55	0.007	0.07	<0.1	0.09	1.3	0.1	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090973	Soil	23	0.21	2563	0.003	3	0.89	0.003	0.07	0.1	0.20	2.0	0.2	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090974	Soil	20	0.14	4329	0.004	2	0.90	0.002	0.06	0.1	0.35	2.3	0.3	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090975	Soil	21	0.13	4201	0.002	3	1.07	0.002	0.07	0.1	0.59	3.8	0.3	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090976	Soil	11	0.01	381	0.002	<1	0.33	0.002	0.03	<0.1	0.06	0.2	0.2	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090977	Soil	9	0.04	813	0.004	2	0.49	0.019	0.05	<0.1	0.31	0.7	0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090979	Soil	10	0.03	317	0.005	<1	0.31	0.008	0.04	<0.1	0.06	1.1	<0.1	<0.05	1	<0.5	0.2	N.A.	N.A.	N.A.	N.A.
1090980	Soil	18	0.01	320	0.004	3	0.50	0.004	0.05	0.3	0.08	0.2	0.2	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090981	Soil	6	0.01	212	0.003	2	0.30	0.003	0.03	0.2	<0.01	0.3	0.3	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090951	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090952	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090953	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090954	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090955	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090956	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090957	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090958	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090959	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090960	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090961	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090962	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090963	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090964	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090965	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090966	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090967	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090968	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090969	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090970	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090971	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090972	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090973	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090974	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090975	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090976	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090977	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090979	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090980	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090981	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090951	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090952	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090953	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090954	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090955	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090956	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090957	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090958	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090959	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090960	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090961	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090962	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090963	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090964	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090965	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090966	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090967	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090968	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090969	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090970	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090971	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090972	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090973	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090974	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090975	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090976	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090977	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090979	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090980	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090981	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090982	Soil	8.3	18.3	14.1	113	2.9	12.4	1.4	16	0.91	9.7	<0.5	0.1	186	0.3	2.8	0.1	47	0.14	0.184	8
1090983	Soil	4.0	23.1	9.5	78	0.3	12.8	2.2	35	1.40	11.4	0.9	0.4	17	0.6	1.4	0.1	41	0.18	0.036	7
1090984	Soil	2.6	37.5	8.9	133	0.4	42.1	5.9	84	2.88	15.0	3.3	0.1	10	0.5	0.8	0.2	30	0.03	0.074	2
1090985	Soil	2.2	25.6	12.0	384	1.9	59.5	8.5	285	2.57	19.4	6.9	0.9	73	3.2	1.6	0.1	43	1.39	0.142	12
1090986	Soil	3.0	19.5	10.7	288	0.5	39.5	9.0	315	2.84	11.9	2.9	0.9	66	0.8	1.3	0.2	70	1.48	0.095	7
1090987	Soil	1.7	22.2	9.9	157	0.5	20.0	6.2	264	1.70	8.6	3.0	0.4	68	7.0	1.0	0.2	51	1.98	0.105	12
1090988	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1090989	Soil	2.4	19.1	9.4	74	0.6	15.2	4.3	174	1.44	8.8	3.6	0.8	22	0.4	1.2	<0.1	31	0.03	0.055	4
1090990	Soil	5.7	27.2	17.9	148	0.4	29.5	6.5	216	4.01	25.3	2.3	1.4	16	0.5	2.7	0.2	82	0.03	0.100	8
1090991	Soil	2.0	25.7	5.8	85	0.8	19.5	3.4	123	1.07	5.7	2.9	0.5	68	1.0	1.3	0.1	25	0.95	0.060	5
1090992	Soil	1.8	25.0	5.4	45	0.8	15.9	3.8	111	1.07	5.0	2.5	0.2	46	1.1	0.6	<0.1	16	0.54	0.058	2
1090993	Soil	3.0	23.6	11.1	135	0.2	23.3	6.5	139	2.56	10.7	1.3	1.3	13	0.6	1.0	0.1	46	0.07	0.034	7
1090994	Soil	1.8	47.9	8.7	93	1.0	39.9	7.2	165	1.83	8.6	4.1	1.3	72	0.7	1.0	0.1	24	0.74	0.046	7
1090995	Soil	1.9	25.5	25.6	108	<0.1	24.8	11.1	295	4.71	24.6	<0.5	2.4	9	0.1	2.9	0.2	33	0.02	0.057	4
1090996	Soil	2.0	18.9	9.0	40	<0.1	9.6	6.1	408	2.14	7.2	1.4	<0.1	7	<0.1	0.9	<0.1	24	0.04	0.094	4
1090997	Soil	0.7	5.3	4.1	12	<0.1	3.6	1.3	36	0.49	3.9	<0.5	<0.1	5	<0.1	0.2	<0.1	12	0.03	0.071	1
1090998	Soil	2.1	14.4	9.7	51	0.3	14.0	5.5	144	1.66	30.0	1.5	0.1	6	0.1	1.3	0.1	23	0.02	0.073	2
1090999	Soil	0.7	5.8	53.5	38	<0.1	5.8	1.9	151	0.81	132.9	0.9	0.2	5	<0.1	1.1	1.7	10	0.03	0.052	1
1091000	Soil	87.2	94.0	13.7	727	0.6	240.6	9.8	192	2.45	40.9	0.6	1.1	46	8.9	9.0	0.2	189	0.60	0.125	14
1091701	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091702	Soil	3.4	15.9	7.5	56	0.3	14.3	2.4	31	1.14	14.5	0.7	<0.1	12	0.2	1.0	<0.1	32	0.03	0.121	5
1091703	Soil	7.2	39.1	10.5	191	1.7	44.9	6.0	103	2.22	25.9	3.4	1.0	40	1.6	2.1	0.2	72	0.24	0.193	10
1091704	Soil	6.0	38.7	15.8	180	0.4	46.5	9.2	104	3.12	32.5	2.0	0.7	22	0.3	3.0	0.2	49	0.07	0.105	10
1091705	Soil	5.9	29.8	12.7	111	0.3	38.0	9.5	85	2.98	32.8	1.5	0.5	8	0.2	2.4	0.3	68	0.02	0.083	10
1091706	Soil	2.7	10.8	2.9	41	0.1	9.9	2.4	24	0.68	9.5	1.6	0.6	4	<0.1	0.9	<0.1	36	0.01	0.028	12
1091707	Soil	2.7	72.5	39.2	100	0.7	91.0	50.8	1175	10.44	37.9	9.2	3.2	14	<0.1	3.5	0.5	33	0.05	0.147	9
1091708	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091709	Soil	3.5	21.5	6.4	76	0.4	23.3	6.0	93	2.01	18.8	<0.5	0.7	13	<0.1	1.6	0.1	25	0.15	0.049	8
1091710	Soil	2.7	23.5	5.5	113	0.8	26.8	4.7	71	1.38	8.9	<0.5	0.4	16	0.3	1.4	0.1	25	0.15	0.096	4
1091711	Soil	8.5	35.4	6.9	337	<0.1	67.8	8.6	38	1.78	21.4	1.4	0.7	5	<0.1	2.9	0.1	47	0.01	0.058	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090982	Soil	18	0.01	473	0.003	3	0.46	0.008	0.05	0.2	0.03	0.3	0.2	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090983	Soil	11	0.03	400	0.009	<1	0.39	0.006	0.05	0.2	0.03	0.7	0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090984	Soil	10	0.01	234	0.002	<1	0.36	0.006	0.03	<0.1	0.11	1.1	<0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090985	Soil	26	0.08	578	0.005	2	1.00	0.009	0.05	<0.1	1.98	2.8	<0.1	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090986	Soil	35	0.16	931	0.003	2	1.18	0.004	0.04	0.1	0.27	2.2	<0.1	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090987	Soil	30	0.10	899	0.005	1	0.90	0.007	0.04	<0.1	0.19	1.5	<0.1	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090988	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.8	36.5	9.2	193
1090989	Soil	16	0.08	2410	0.007	1	0.52	0.007	0.05	0.1	0.08	1.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090990	Soil	26	0.18	379	0.006	<1	1.11	0.003	0.07	0.2	0.05	1.6	0.2	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090991	Soil	12	0.10	2392	0.004	<1	0.71	0.014	0.04	<0.1	0.15	1.2	<0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090992	Soil	11	0.06	845	0.004	2	0.48	0.015	0.03	<0.1	0.17	1.0	<0.1	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090993	Soil	21	0.22	553	0.003	<1	1.05	0.003	0.06	<0.1	0.04	1.6	0.1	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090994	Soil	16	0.15	2424	0.003	2	0.74	0.010	0.05	<0.1	0.19	3.6	<0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090995	Soil	24	0.18	63	0.006	2	1.18	0.002	0.05	<0.1	0.02	2.4	0.3	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090996	Soil	17	0.07	89	0.009	<1	0.71	0.013	0.04	<0.1	0.05	0.3	<0.1	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090997	Soil	6	0.03	25	0.004	<1	0.35	0.017	0.02	<0.1	<0.01	<0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090998	Soil	10	0.05	72	0.003	<1	0.49	0.010	0.04	<0.1	0.04	0.4	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090999	Soil	2	0.04	54	0.001	<1	0.59	0.008	0.04	<0.1	0.08	0.1	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091000	Soil	24	0.12	569	0.002	3	0.46	0.003	0.08	0.3	0.57	3.2	1.8	<0.05	1	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091701	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	7.2	63.9	24.8	234
1091702	Soil	7	0.02	361	0.001	1	0.64	0.012	0.04	<0.1	0.04	<0.1	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091703	Soil	20	0.17	5308	0.006	3	1.13	0.005	0.10	0.1	0.41	2.1	0.3	<0.05	3	1.6	0.2	N.A.	N.A.	N.A.	N.A.
1091704	Soil	13	0.07	1674	0.006	1	0.54	0.005	0.07	0.1	0.03	1.0	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091705	Soil	10	0.06	471	0.006	3	0.64	0.004	0.07	0.1	<0.01	0.9	0.2	<0.05	3	0.7	0.2	N.A.	N.A.	N.A.	N.A.
1091706	Soil	7	0.03	188	0.004	2	0.41	0.005	0.04	<0.1	0.01	0.3	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091707	Soil	14	0.22	1067	0.004	2	1.03	0.005	0.08	<0.1	0.10	3.7	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091708	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.2	18.7	3.9	30
1091709	Soil	8	0.05	595	0.007	<1	0.30	0.010	0.06	0.1	0.03	1.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091710	Soil	9	0.05	507	0.005	2	0.35	0.011	0.06	<0.1	0.11	1.6	<0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091711	Soil	10	0.03	195	0.004	4	0.32	0.005	0.07	<0.1	0.02	0.8	<0.1	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090982	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090983	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090984	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090985	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090986	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090987	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090988	Soil	0.7	32.3	5.1	159	1.67	10.3	4.1	0.7	80	2.0	1.6	0.2	54	1.63	0.105	5	21	0.19	2422	0.002
1090989	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090990	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090991	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090992	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090993	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090994	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090995	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090996	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090997	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090998	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090999	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091000	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091701	Soil	0.7	74.5	15.1	278	3.81	34.5	1.4	0.7	24	0.8	2.3	0.3	35	0.16	0.152	15	15	0.07	1872	0.002
1091702	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091703	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091704	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091705	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091706	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091707	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091708	Soil	<0.1	16.2	4.8	82	1.51	8.6	1.9	<0.1	4	<0.1	0.8	0.1	15	0.02	0.036	7	7	0.02	172	0.003
1091709	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091710	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091711	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090982	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090983	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090984	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090985	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090986	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090987	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090988	Soil	<20	0.92	0.008	0.06	0.1	0.27	2.0	0.1	0.09	2	1.7	<0.2
1090989	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090990	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090991	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090992	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090993	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090994	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090995	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090996	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090997	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090998	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090999	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091000	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091701	Soil	<20	0.53	0.003	0.10	<0.1	0.11	2.5	0.2	0.09	1	2.8	<0.2
1091702	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091703	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091704	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091705	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091706	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091707	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091708	Soil	<20	0.28	0.011	0.04	<0.1	0.01	0.4	<0.1	<0.05	2	0.5	<0.2
1091709	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091710	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091711	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091712	Soil	23.5	81.1	20.7	503	0.8	105.6	12.7	158	4.32	44.9	1.7	2.4	24	1.8	6.9	0.3	109	0.14	0.152	15
1091713	Soil	13.9	71.2	13.0	1552	0.8	144.9	9.6	215	2.90	29.3	4.3	1.6	73	14.0	5.5	0.2	44	3.20	0.114	11
1091714	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091715	Soil	7.8	22.9	6.1	116	0.1	28.1	3.0	27	1.12	16.1	2.1	<0.1	9	0.6	2.1	<0.1	39	0.08	0.076	7
1091716	Soil	15.3	28.4	11.1	278	0.7	45.4	4.7	76	1.94	31.9	1.4	0.3	36	4.1	5.2	0.2	98	0.81	0.093	8
1091717	Soil	34.5	51.9	17.2	915	0.3	116.5	11.2	97	2.97	63.6	<0.5	1.9	11	4.5	11.0	0.3	118	0.09	0.078	8
1091718	Soil	4.7	27.6	8.2	193	1.0	31.1	4.7	234	1.96	28.7	2.3	0.5	33	2.0	2.7	<0.1	33	0.74	0.104	6
1091719	Soil	10.3	24.8	2.8	56	<0.1	36.7	2.2	115	0.45	8.1	<0.5	0.1	60	0.8	1.1	<0.1	14	1.87	0.093	3
1091720	Soil	39.3	25.0	4.9	115	0.1	61.4	3.5	42	1.34	18.7	<0.5	<0.1	4	0.3	1.6	<0.1	52	0.05	0.045	5
1091721	Soil	51.9	100.8	29.0	209	0.5	188.6	11.6	599	6.26	60.4	0.9	1.6	88	1.9	4.3	0.1	119	2.60	0.086	17
1091722	Soil	73.3	100.7	12.6	265	0.4	218.7	11.9	262	2.59	42.6	2.3	1.4	71	3.3	4.4	0.1	47	2.48	0.152	12
1091723	Soil	67.5	94.2	13.2	335	0.4	212.5	10.6	209	2.80	51.3	0.7	1.6	49	3.2	5.0	0.2	55	1.62	0.160	14
1091724	Soil	1.5	22.9	17.4	62	<0.1	20.1	8.7	119	1.75	17.8	2.7	0.6	22	0.2	0.5	0.3	14	0.05	0.052	3
1091725	Soil	1.9	21.9	11.5	69	<0.1	23.5	13.1	120	1.84	20.6	<0.5	0.4	11	<0.1	0.5	0.3	22	0.02	0.055	3
1091726	Soil	1.8	23.9	17.6	78	<0.1	21.3	11.6	248	1.88	18.2	<0.5	0.8	30	0.2	0.6	0.3	18	0.06	0.077	4
1091727	Soil	2.4	33.9	24.3	152	0.2	35.6	22.9	724	3.37	25.5	<0.5	0.8	40	0.3	0.9	0.4	20	0.13	0.097	5
1091728	Soil	2.9	22.7	18.2	33	0.6	22.8	3.4	74	1.31	8.5	<0.5	<0.1	29	0.2	1.6	0.2	34	0.03	0.128	2
1091729	Soil	6.3	60.5	36.1	50	1.2	34.3	5.7	124	2.85	20.0	3.4	0.3	109	0.2	3.9	0.3	63	0.04	0.127	3
1091730	Soil	6.0	36.1	25.9	54	0.8	22.9	4.8	66	2.22	21.5	1.0	0.2	39	<0.1	2.8	0.3	53	0.01	0.074	4
1091731	Soil	8.7	87.6	50.6	129	2.4	64.1	12.1	297	5.36	42.5	7.1	1.0	101	0.3	6.3	0.4	69	0.02	0.198	3
1091732	Soil	6.8	47.6	25.7	72	1.2	34.9	7.1	108	3.59	23.2	3.3	0.4	26	0.1	4.0	0.3	61	0.01	0.116	3
1091733	Soil	7.1	44.4	17.7	62	1.3	23.9	4.8	80	2.52	20.6	2.9	0.2	13	<0.1	3.5	0.3	54	0.03	0.081	5
1091734	Soil	6.7	30.2	23.6	50	0.7	17.9	3.5	80	2.26	19.0	3.5	0.2	16	<0.1	3.4	0.4	52	0.01	0.089	4
1091735	Soil	6.4	115.5	32.7	268	3.2	78.3	27.4	926	4.39	28.7	5.6	1.1	52	0.7	4.4	0.4	59	0.07	0.153	3
1091736	Soil	6.3	92.1	29.0	231	1.7	70.4	18.9	673	4.05	27.4	5.6	1.0	45	0.7	4.6	0.4	56	0.12	0.142	4
1091737	Soil	7.6	112.2	43.5	226	2.1	92.1	34.8	1356	5.09	35.1	5.3	1.3	32	0.9	6.0	0.5	58	0.16	0.137	5
1091738	Soil	99.5	88.2	10.8	494	0.7	239.6	9.3	189	2.28	34.5	<0.5	3.5	162	7.3	8.8	0.1	107	6.85	0.130	8
1091739	Soil	66.8	52.1	16.1	738	0.6	147.8	8.4	191	2.22	38.4	0.9	2.9	108	7.0	20.1	0.1	211	4.53	0.095	7
1091740	Soil	54.8	39.1	16.7	1036	0.3	111.0	7.9	220	2.15	40.5	0.6	4.8	110	9.1	22.1	0.1	205	4.79	0.075	7
1091741	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091712	Soil	18	0.07	1485	0.004	3	0.54	0.003	0.11	0.2	0.11	3.4	0.4	<0.05	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091713	Soil	16	0.43	305	0.002	3	0.35	0.005	0.06	<0.1	0.48	3.6	0.4	<0.05	<1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091714	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	13.7	92.5	23.6	508
1091715	Soil	9	0.04	316	0.001	3	0.41	0.006	0.05	<0.1	0.02	0.2	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091716	Soil	14	0.14	702	0.004	1	0.54	0.006	0.05	0.1	0.19	0.9	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091717	Soil	13	0.04	336	0.002	1	0.45	0.002	0.05	<0.1	0.11	2.1	0.3	<0.05	1	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091718	Soil	10	0.11	372	0.003	2	0.34	0.021	0.04	<0.1	0.14	1.5	<0.1	<0.05	<1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091719	Soil	6	0.09	178	0.006	3	0.46	0.029	0.03	<0.1	0.13	0.4	0.3	<0.05	1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091720	Soil	9	0.04	68	0.005	<1	0.41	0.009	0.04	0.2	0.02	0.2	0.6	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091721	Soil	23	1.28	374	0.003	5	0.57	0.004	0.06	0.2	0.68	4.1	1.9	<0.05	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091722	Soil	16	1.01	243	0.004	4	0.38	0.007	0.07	0.3	0.51	4.2	2.1	<0.05	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091723	Soil	17	0.49	241	0.004	4	0.41	0.005	0.07	0.3	0.46	4.3	1.4	<0.05	<1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091724	Soil	7	0.06	319	<0.001	<1	0.49	0.003	0.05	<0.1	0.02	1.5	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091725	Soil	5	0.03	130	<0.001	<1	0.43	0.005	0.04	<0.1	0.03	1.3	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091726	Soil	7	0.06	276	<0.001	<1	0.50	0.005	0.05	<0.1	<0.01	1.2	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091727	Soil	10	0.11	309	0.002	<1	0.55	0.007	0.07	<0.1	0.05	2.0	0.3	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091728	Soil	8	0.02	565	0.004	2	0.27	0.011	0.07	<0.1	0.06	0.5	0.2	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091729	Soil	14	0.02	363	0.002	1	0.44	0.005	0.08	<0.1	0.06	1.4	0.4	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091730	Soil	9	0.01	172	0.004	1	0.28	0.005	0.06	<0.1	0.02	0.7	0.2	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091731	Soil	16	0.02	388	0.002	<1	0.57	0.005	0.09	<0.1	0.11	4.6	0.5	<0.05	2	8.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091732	Soil	14	0.02	196	0.002	2	0.42	0.003	0.06	<0.1	0.05	1.7	0.3	0.08	3	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091733	Soil	11	0.03	97	0.003	2	0.40	0.003	0.04	0.1	0.07	0.8	0.2	0.06	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091734	Soil	12	0.02	149	0.003	2	0.41	0.004	0.07	<0.1	0.03	0.5	0.2	0.09	3	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091735	Soil	18	0.08	160	0.003	1	0.98	0.008	0.07	<0.1	0.12	5.1	0.5	0.11	3	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091736	Soil	17	0.08	253	0.004	2	0.95	0.009	0.08	<0.1	0.10	4.2	0.4	0.07	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091737	Soil	18	0.08	500	0.003	2	0.72	0.006	0.10	<0.1	0.25	6.1	0.8	<0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091738	Soil	15	2.44	411	0.002	6	0.29	0.004	0.09	0.2	0.95	3.7	2.0	<0.05	<1	7.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091739	Soil	13	2.11	337	0.002	4	0.27	0.007	0.08	0.1	1.08	3.7	0.8	<0.05	<1	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091740	Soil	11	2.49	302	0.002	5	0.21	0.005	0.07	<0.1	1.01	3.8	0.5	<0.05	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091741	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	36.1	64.8	18.1	294

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091712	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091713	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091714	Soil	0.6	101.4	30.2	440	6.52	65.5	8.6	0.3	18	1.3	3.8	0.5	61	0.16	0.140	9	15	0.07	959	0.004
1091715	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091716	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091717	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091718	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091719	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091720	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091721	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091722	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091723	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091724	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091725	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091726	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091727	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091728	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091729	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091730	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091731	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091732	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091733	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091734	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091735	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091736	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091737	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091738	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091739	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091740	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091741	Soil	1.1	106.4	9.9	246	2.23	25.5	4.9	0.9	57	2.1	5.2	0.2	80	1.12	0.142	7	16	0.31	514	0.002

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091712	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091713	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091714	Soil	<20	0.65	0.006	0.10	0.1	0.11	1.6	0.4	0.09	3	3.2	0.2
1091715	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091716	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091717	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091718	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091719	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091720	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091721	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091722	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091723	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091724	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091725	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091726	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091727	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091728	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091729	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091730	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091731	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091732	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091733	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091734	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091735	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091736	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091737	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091738	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091739	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091740	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091741	Soil	<20	0.67	0.007	0.09	<0.1	0.48	2.8	0.7	0.10	2	3.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091742	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091743	Soil	17.7	75.8	66.7	176	3.2	44.6	4.5	109	2.37	38.7	4.7	0.5	248	1.4	7.4	0.4	187	0.38	0.495	18
1091744	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091745	Soil	27.4	141.2	85.7	290	3.2	81.1	6.4	128	4.20	77.8	5.5	1.7	396	1.8	13.2	0.6	288	0.91	1.074	32
1091746	Soil	45.1	216.3	103.6	579	3.4	168.9	15.1	343	6.85	112.7	6.6	2.1	714	5.9	21.7	0.6	463	0.65	1.112	37
1091747	Soil	112.0	208.5	143.5	454	8.7	129.0	5.8	63	5.06	146.1	5.6	0.9	708	6.5	29.9	0.6	798	0.45	0.724	27
1091748	Soil	24.2	96.2	27.9	270	2.1	75.6	6.6	132	3.44	73.5	4.5	1.2	135	4.2	10.3	0.2	262	0.60	0.790	23
1091749	Soil	10.7	107.0	14.6	94	1.8	44.8	2.2	66	1.59	27.7	4.1	0.7	82	0.7	4.3	0.3	63	0.16	0.227	20
1091750	Soil	39.0	99.6	34.9	110	5.3	33.0	2.1	41	2.98	44.5	4.8	0.5	178	0.9	13.0	0.4	152	0.03	0.179	17
1091751	Soil	14.0	22.2	14.8	30	2.1	12.0	1.2	28	1.03	13.3	3.0	0.2	38	0.2	3.6	0.2	79	0.04	0.106	7
1091752	Soil	8.4	80.0	25.9	193	1.0	63.6	6.1	160	3.44	33.9	4.6	0.3	173	1.2	4.6	0.3	135	0.37	0.381	19
1091753	Soil	16.6	80.5	26.7	250	3.5	92.2	7.2	112	3.74	37.1	3.5	0.7	214	4.8	9.3	0.3	325	0.73	0.846	19
1091754	Soil	25.0	87.1	40.5	126	3.5	22.9	1.9	44	1.78	13.3	1.2	0.5	665	1.3	12.1	0.4	341	0.27	0.371	35
1091755	Soil	28.5	107.6	121.3	55	4.2	19.2	2.2	55	2.47	21.7	3.1	0.6	80	1.2	5.5	0.4	279	0.43	0.590	25
1091756	Soil	45.8	83.0	118.6	83	8.3	38.5	3.9	115	3.30	26.3	4.3	0.9	140	1.0	18.0	0.7	340	0.18	0.235	24
1091757	Soil	23.9	139.7	58.8	247	5.7	82.4	9.9	344	4.43	62.1	2.6	4.2	236	2.1	13.2	0.7	279	0.62	0.643	25
1091758	Soil	27.0	155.9	147.3	290	6.2	116.2	9.8	284	5.73	74.9	5.6	3.4	329	2.3	8.7	0.7	354	1.19	1.196	29
1091759	Soil	2.8	104.7	34.0	404	2.4	208.4	48.1	1925	11.00	1482	29.6	7.4	25	0.2	6.5	0.6	30	0.31	0.086	21
1091760	Soil	3.4	186.9	37.1	285	1.9	149.0	54.6	1326	11.79	1196	20.5	6.9	22	0.2	5.2	0.9	26	0.13	0.110	54
1092001	Soil	4.4	13.2	8.3	50	0.7	10.3	1.6	23	0.78	12.1	1.3	0.3	7	0.3	1.3	0.1	44	0.02	0.054	7
1092002	Soil	7.5	15.8	11.6	105	0.3	19.8	3.1	67	1.77	31.9	<0.5	1.1	8	0.4	2.8	0.2	112	<0.01	0.063	9
1092003	Soil	2.7	7.7	5.1	31	0.2	6.3	1.3	18	0.51	5.3	2.0	0.2	5	<0.1	0.8	0.1	39	0.01	0.020	13
1092004	Soil	1.5	29.5	5.3	46	1.3	13.0	4.2	89	1.11	4.9	4.5	0.3	19	0.4	0.7	<0.1	23	0.20	0.049	3
1092005	Soil	3.6	10.8	13.4	67	<0.1	11.2	2.5	82	1.79	13.8	0.9	1.0	15	0.2	1.6	0.2	99	0.05	0.038	12
1092006	Soil	1.5	9.6	9.0	141	0.1	10.3	3.7	119	1.02	3.8	1.2	0.3	15	1.2	0.9	0.2	55	0.07	0.049	6
1092007	Soil	0.9	18.5	7.9	22	0.8	9.1	2.4	135	0.73	4.2	1.5	0.4	60	0.7	0.6	0.1	30	1.89	0.091	4
1092008	Soil	2.2	5.8	7.4	25	0.1	4.5	1.0	20	0.48	5.5	0.7	0.4	8	<0.1	0.7	0.1	36	0.02	0.035	8
1092009	Soil	3.3	9.0	9.0	39	0.3	6.5	1.4	26	0.64	7.5	0.5	<0.1	12	0.1	0.9	0.1	48	0.03	0.049	7
1092010	Soil	7.2	27.0	12.8	149	0.4	26.2	4.9	121	2.30	22.4	3.6	1.6	46	1.0	3.3	0.2	102	0.13	0.120	8
1092011	Soil	2.9	33.7	7.2	151	0.9	27.7	4.1	163	1.33	9.5	3.9	1.0	91	1.1	2.4	0.1	51	1.30	0.083	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091742	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	48.8	149.1	81.2	351
1091743	Soil	23	0.06	523	0.006	6	0.71	0.013	0.17	0.2	0.20	0.8	0.6	0.21	3	6.9	0.3	N.A.	N.A.	N.A.	N.A.
1091744	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	43.1	138.7	100.0	241
1091745	Soil	38	0.06	970	0.010	9	0.87	0.006	0.31	0.3	0.45	2.6	0.7	0.30	3	13.7	0.4	N.A.	N.A.	N.A.	N.A.
1091746	Soil	39	0.06	793	0.011	8	1.28	0.007	0.26	0.4	0.46	3.3	0.8	0.25	3	17.0	0.6	N.A.	N.A.	N.A.	N.A.
1091747	Soil	43	0.05	719	0.009	6	0.84	0.006	0.28	0.9	0.80	2.3	1.3	0.36	3	14.1	0.7	N.A.	N.A.	N.A.	N.A.
1091748	Soil	28	0.19	551	0.011	2	1.16	0.005	0.10	0.4	0.48	1.4	0.4	0.11	4	5.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091749	Soil	12	0.03	640	0.003	3	0.44	0.005	0.15	0.1	1.44	1.3	0.6	0.21	<1	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091750	Soil	22	0.02	280	0.004	3	0.44	0.004	0.31	0.4	1.04	0.8	3.4	0.65	2	8.2	0.5	N.A.	N.A.	N.A.	N.A.
1091751	Soil	16	0.04	270	0.004	1	0.58	0.014	0.10	0.2	0.43	0.2	0.8	0.16	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091752	Soil	24	0.15	601	0.005	2	0.86	0.005	0.18	0.3	0.24	0.5	0.5	0.31	4	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091753	Soil	28	0.13	1351	0.008	5	1.21	0.004	0.17	0.3	1.16	1.6	0.6	0.17	3	9.2	0.3	N.A.	N.A.	N.A.	N.A.
1091754	Soil	31	0.03	745	0.005	3	0.59	0.004	0.15	0.3	0.28	0.6	0.6	0.23	3	5.2	0.7	N.A.	N.A.	N.A.	N.A.
1091755	Soil	43	0.09	587	0.009	5	0.68	0.005	0.18	0.5	0.63	1.0	0.6	0.27	4	8.8	0.6	N.A.	N.A.	N.A.	N.A.
1091756	Soil	36	0.16	253	0.014	4	0.71	0.009	0.31	0.5	0.86	1.7	1.2	0.62	4	6.1	0.7	N.A.	N.A.	N.A.	N.A.
1091757	Soil	37	0.13	657	0.017	9	0.77	0.010	0.28	0.3	0.45	4.3	0.9	0.42	3	7.7	0.6	N.A.	N.A.	N.A.	N.A.
1091758	Soil	63	0.09	183	0.010	13	0.86	0.009	0.44	0.2	0.70	4.2	0.7	0.75	3	10.6	0.6	N.A.	N.A.	N.A.	N.A.
1091759	Soil	13	0.14	1079	0.001	3	0.62	0.002	0.12	<0.1	0.51	16.0	0.4	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091760	Soil	11	0.09	970	0.002	3	0.53	0.003	0.12	<0.1	0.22	10.7	0.4	<0.05	2	2.6	0.4	N.A.	N.A.	N.A.	N.A.
1092001	Soil	8	0.02	233	0.002	2	0.40	0.006	0.04	<0.1	0.08	0.4	0.2	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092002	Soil	11	0.05	447	0.003	2	0.64	0.003	0.05	0.1	0.04	1.0	0.3	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092003	Soil	8	0.02	127	0.004	2	0.31	0.002	0.03	<0.1	0.01	0.2	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092004	Soil	7	0.05	859	0.005	1	0.49	0.020	0.04	<0.1	0.22	1.2	<0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092005	Soil	16	0.10	288	0.010	1	0.93	0.003	0.05	0.1	0.04	1.1	0.2	<0.05	5	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092006	Soil	15	0.10	336	0.005	2	0.73	0.009	0.06	<0.1	0.10	0.5	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092007	Soil	10	0.06	1294	0.005	2	0.64	0.009	0.02	<0.1	0.18	0.8	<0.1	0.09	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092008	Soil	5	0.02	160	0.003	1	0.39	0.004	0.03	0.1	0.04	0.3	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092009	Soil	8	0.03	167	0.003	1	0.38	0.004	0.04	0.1	0.03	0.2	0.1	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092010	Soil	17	0.11	2149	0.002	2	0.79	0.002	0.06	0.2	0.16	1.4	0.3	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092011	Soil	12	0.12	2395	0.004	3	0.74	0.017	0.07	0.1	0.44	1.7	0.2	0.09	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091742	Soil	5.1	107.1	8.3	174	3.79	88.5	7.0	2.7	517	3.9	14.8	0.5	417	0.71	0.929	23	40	0.11	733	0.013
1091743	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091744	Soil	4.9	66.8	5.3	113	3.22	63.7	6.4	1.1	382	3.1	15.4	0.5	421	0.71	0.775	29	42	0.05	935	0.007
1091745	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091746	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091747	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091748	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091749	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091750	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091751	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091752	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091753	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091754	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091755	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091756	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091757	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091758	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091759	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091760	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091742	Soil	<20	1.08	0.010	0.24	0.6	0.35	3.8	0.9	0.25	3	15.2	0.6
1091743	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091744	Soil	<20	0.85	0.006	0.30	0.4	0.60	1.3	1.0	0.33	3	14.2	0.5
1091745	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091746	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091747	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091748	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091749	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091750	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091751	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091752	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091753	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091754	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091755	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091756	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091757	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091758	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091759	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091760	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092012	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092013	Soil	6.3	33.3	13.8	130	0.3	24.5	4.9	86	2.19	22.9	4.5	0.8	47	1.4	2.4	0.3	69	0.64	0.064	5
1092014	Soil	1.2	22.3	4.5	44	1.1	13.0	1.7	31	0.68	4.7	3.1	0.2	24	0.6	0.6	<0.1	19	0.32	0.050	2
1092015	Soil	5.9	52.0	25.3	57	0.8	32.2	5.7	88	3.10	149.9	1.7	0.1	22	0.2	3.3	0.2	81	0.02	0.081	8
1092016	Soil	5.8	91.3	26.1	112	2.7	47.8	14.4	499	3.23	100.5	6.2	1.1	25	0.4	3.8	0.3	53	0.10	0.139	7
1092017	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092018	Soil	6.6	109.4	32.0	278	1.1	76.6	20.5	802	4.87	80.7	2.8	0.6	29	1.4	4.6	0.3	66	0.15	0.161	5
1092019	Soil	2.6	48.5	16.1	83	0.8	32.7	12.0	433	2.31	22.4	1.0	0.2	13	0.1	1.7	0.2	30	0.09	0.076	3
1092020	Soil	4.8	87.0	23.4	133	0.7	66.9	18.8	603	4.08	63.3	3.6	0.8	21	0.5	3.1	0.3	44	0.12	0.099	4
1092021	Soil	6.1	60.1	18.4	133	0.6	52.1	14.2	378	3.06	26.6	3.0	0.4	23	0.5	2.7	0.3	49	0.16	0.104	4
1092022	Soil	5.0	25.1	6.4	76	0.4	24.6	4.3	91	1.08	8.9	<0.5	<0.1	14	0.3	1.8	0.1	36	0.08	0.058	2
1092023	Soil	25.7	26.3	16.9	177	0.3	47.5	3.9	64	1.26	13.1	1.4	0.1	38	0.6	6.2	0.1	117	0.10	0.073	5
1092024	Soil	15.0	33.5	11.8	225	0.6	49.2	2.9	128	0.87	11.4	2.7	0.2	46	5.5	4.1	0.1	121	0.30	0.134	5
1092025	Soil	9.7	10.8	6.4	70	0.2	13.5	1.9	65	0.88	8.9	0.7	0.3	10	0.6	1.4	0.1	58	0.09	0.079	6
1092026	Soil	2.4	13.5	6.1	52	0.1	13.5	3.0	58	0.99	6.2	<0.5	0.1	6	0.1	0.6	<0.1	13	0.02	0.064	4
1092027	Soil	4.1	31.0	18.3	140	0.4	30.8	6.4	76	2.60	19.2	3.1	0.3	19	0.2	1.6	0.2	39	0.02	0.142	10
1092028	Soil	3.7	29.6	8.9	108	0.2	28.4	6.4	89	2.35	37.9	0.8	0.2	10	0.1	1.4	0.2	27	0.02	0.090	7
1092029	Soil	1.8	11.5	4.2	29	<0.1	9.4	2.9	53	1.25	8.9	<0.5	<0.1	4	<0.1	0.5	<0.1	17	0.02	0.047	3
1092030	Soil	3.9	27.7	11.6	89	0.1	29.0	6.3	77	2.55	15.1	2.5	0.3	7	<0.1	1.2	0.2	35	0.02	0.086	10
1092031	Soil	3.0	31.1	8.3	98	0.2	26.4	5.1	69	1.82	10.3	0.7	0.4	8	0.1	1.0	0.2	26	0.04	0.090	7
1092032	Soil	3.9	39.1	10.6	269	1.2	65.7	6.4	91	1.96	10.4	2.8	0.5	28	1.2	1.5	0.2	34	0.38	0.120	12
1092033	Soil	5.3	110.7	27.9	380	1.7	108.5	11.7	96	3.19	42.8	4.2	1.9	73	0.6	2.7	0.3	44	0.50	0.373	17
1092034	Soil	5.9	81.6	34.7	335	1.1	102.3	8.9	27	2.56	22.5	4.1	1.4	51	0.6	2.6	0.4	63	0.50	0.380	21
1092035	Soil	6.4	42.8	41.9	269	0.8	64.7	5.4	50	2.50	15.8	<0.5	0.6	212	0.2	2.8	0.6	59	0.30	0.427	28
1092036	Soil	26.5	50.9	70.7	296	1.3	76.6	7.1	43	2.46	27.0	2.9	1.2	157	0.6	7.1	0.3	178	0.04	0.130	17
1092037	Soil	17.3	33.1	50.2	147	0.7	40.1	4.3	51	1.97	19.2	1.8	0.5	99	0.3	4.1	0.3	125	0.11	0.177	15
1092038	Soil	11.8	40.7	31.3	139	0.6	40.7	6.2	140	2.30	21.0	1.5	0.4	74	0.4	3.9	0.3	127	0.16	0.233	14
1092039	Soil	5.9	28.2	20.6	105	0.3	25.8	6.2	176	2.57	18.6	19.6	0.4	32	0.4	2.1	0.3	87	0.16	0.204	15
1092040	Soil	4.9	50.1	19.0	161	0.9	44.4	9.3	148	2.57	15.0	5.9	1.0	30	0.6	2.2	0.2	47	0.21	0.148	17
1092041	Soil	3.9	36.7	19.3	93	0.3	41.2	12.5	329	3.20	14.5	3.9	1.3	15	0.2	1.8	0.2	36	0.10	0.090	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092012	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.5	12.2	4.1	53
1092013	Soil	14	0.08	362	0.005	1	0.44	0.005	0.04	0.2	0.07	1.3	0.2	0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092014	Soil	9	0.07	569	0.003	1	0.42	0.016	0.02	<0.1	0.18	0.8	<0.1	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092015	Soil	17	0.02	115	0.006	<1	0.43	0.003	0.04	0.1	0.06	0.8	0.2	0.06	4	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092016	Soil	19	0.18	203	0.017	3	0.87	0.015	0.09	0.2	0.15	4.2	0.3	<0.05	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092017	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.0	86.2	25.1	170
1092018	Soil	22	0.09	324	0.003	1	0.74	0.004	0.07	<0.1	0.12	3.2	0.2	<0.05	2	2.9	0.2	N.A.	N.A.	N.A.	N.A.
1092019	Soil	10	0.06	201	0.005	<1	0.59	0.016	0.05	<0.1	0.03	2.0	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092020	Soil	14	0.09	319	0.003	<1	0.61	0.007	0.06	<0.1	0.07	3.9	0.2	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092021	Soil	14	0.07	283	0.002	2	0.59	0.009	0.08	<0.1	0.05	2.2	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092022	Soil	7	0.03	125	0.003	<1	0.33	0.019	0.04	<0.1	0.04	0.5	0.1	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092023	Soil	11	0.03	130	0.002	2	0.32	0.015	0.06	<0.1	0.03	0.3	0.5	<0.05	1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092024	Soil	11	0.06	291	0.003	2	0.55	0.015	0.06	<0.1	0.12	0.6	0.6	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092025	Soil	9	0.05	239	0.002	2	0.47	0.006	0.05	<0.1	0.03	0.5	0.3	<0.05	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092026	Soil	4	0.02	583	0.002	2	0.27	0.016	0.05	<0.1	0.03	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092027	Soil	11	0.04	503	0.004	4	0.55	0.004	0.11	0.1	0.04	0.4	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092028	Soil	7	0.03	470	0.003	2	0.47	0.007	0.07	<0.1	0.02	0.3	0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092029	Soil	4	0.02	142	0.003	1	0.37	0.015	0.03	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092030	Soil	11	0.05	478	0.003	2	0.81	0.003	0.06	<0.1	0.05	0.4	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092031	Soil	9	0.06	491	0.004	2	0.88	0.012	0.06	<0.1	0.03	0.3	0.1	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092032	Soil	18	0.20	2370	0.004	4	0.98	0.009	0.09	<0.1	0.20	1.6	0.2	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092033	Soil	13	0.05	2823	0.003	4	0.67	0.004	0.18	<0.1	0.40	3.2	0.2	0.13	1	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092034	Soil	22	0.05	415	0.003	5	0.61	0.003	0.21	<0.1	0.30	1.9	0.1	0.07	2	7.7	0.2	N.A.	N.A.	N.A.	N.A.
1092035	Soil	20	0.04	551	0.005	7	0.54	0.004	0.18	0.1	0.08	1.0	0.3	0.07	2	6.7	0.2	N.A.	N.A.	N.A.	N.A.
1092036	Soil	16	0.03	386	0.011	3	0.41	0.003	0.10	0.3	0.10	1.2	0.5	0.08	3	4.4	0.2	N.A.	N.A.	N.A.	N.A.
1092037	Soil	16	0.05	228	0.011	2	0.41	0.003	0.08	0.3	0.04	0.7	0.3	<0.05	4	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092038	Soil	18	0.09	214	0.006	2	0.84	0.005	0.07	0.1	0.05	0.3	0.3	<0.05	4	3.0	0.2	N.A.	N.A.	N.A.	N.A.
1092039	Soil	25	0.30	164	0.007	1	1.20	0.005	0.07	0.2	0.04	0.4	0.2	<0.05	5	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092040	Soil	19	0.29	839	0.015	2	1.23	0.005	0.08	0.2	0.13	1.6	0.2	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092041	Soil	14	0.14	381	0.009	2	0.72	0.004	0.07	0.1	0.06	1.7	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092012	Soil	0.4	12.2	1.2	19	0.47	4.0	3.0	0.2	37	1.9	1.0	<0.1	33	0.27	0.047	2	8	0.02	605	0.003
1092013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092017	Soil	0.7	60.2	14.5	494	3.91	118.6	3.5	0.2	25	0.5	2.4	0.3	66	0.05	0.121	5	23	0.06	221	0.004
1092018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092019	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092021	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092022	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092023	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092025	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092026	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092027	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092028	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092029	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092030	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092031	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092032	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092033	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092034	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092035	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092036	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092037	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092038	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092039	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092040	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092041	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092012	Soil	<20	0.28	0.013	0.03	0.2	0.15	0.7	0.1	0.06	1	1.1	<0.2
1092013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092017	Soil	<20	0.68	0.009	0.06	<0.1	0.05	2.2	0.2	0.06	3	2.6	<0.2
1092018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092019	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092021	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092022	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092023	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092025	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092026	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092027	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092028	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092029	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092030	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092031	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092032	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092033	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092034	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092035	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092036	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092037	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092038	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092039	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092040	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092041	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092042	Soil	3.0	15.1	5.6	40	<0.1	14.7	4.1	68	1.39	6.5	1.4	0.1	3	<0.1	0.9	0.1	25	0.01	0.032	7
1092043	Soil	5.3	104.4	26.7	132	1.9	99.0	34.5	1592	11.58	26.3	10.0	2.7	11	<0.1	2.7	0.5	21	0.12	0.064	26
1092044	Soil	1.6	20.5	4.8	31	0.3	17.9	5.1	118	1.68	6.6	<0.5	0.2	3	<0.1	0.8	0.1	11	0.02	0.043	6
1092045	Soil	1.7	16.5	4.5	37	0.3	15.5	4.5	100	1.26	8.7	0.7	0.1	8	<0.1	0.9	<0.1	12	0.07	0.034	6
1092046	Soil	2.8	19.6	6.5	86	0.5	22.1	4.1	72	1.46	5.1	0.8	0.3	18	0.2	0.8	0.1	15	0.21	0.085	6
1092047	Soil	2.7	13.1	6.5	49	0.1	13.1	2.3	28	1.15	8.3	<0.5	0.3	5	<0.1	0.9	<0.1	37	0.02	0.035	7
1092048	Soil	6.4	26.7	18.8	116	1.2	28.0	4.8	70	2.20	24.5	<0.5	0.4	13	0.2	2.2	0.2	54	0.03	0.080	9
1092049	Soil	6.4	50.3	20.3	210	1.0	60.4	11.2	277	3.16	23.6	3.8	1.8	56	1.1	3.0	0.2	33	0.54	0.168	17
1092050	Soil	4.4	24.7	10.6	100	0.1	27.4	6.0	91	2.02	18.1	0.8	0.5	3	0.1	1.7	0.1	26	0.01	0.048	9
1092051	Soil	11.3	38.9	12.0	226	0.7	43.7	6.6	169	1.94	20.9	4.1	2.3	48	1.9	3.7	0.1	97	0.35	0.119	12
1092052	Soil	1.9	12.3	3.5	34	0.4	13.0	1.9	102	0.51	3.9	<0.5	<0.1	11	0.3	0.6	<0.1	15	0.14	0.075	2
1092053	Soil	6.5	19.5	9.4	96	0.1	17.2	4.1	189	1.45	10.4	<0.5	0.1	10	1.0	1.7	0.2	55	0.03	0.120	7
1092054	Soil	8.8	29.5	10.1	144	0.1	23.5	5.6	95	2.07	13.1	<0.5	0.2	9	0.4	2.8	0.2	76	0.04	0.094	8
1092055	Soil	13.8	28.8	9.9	135	0.1	26.5	5.2	73	1.85	16.6	<0.5	0.1	7	0.3	3.3	0.2	83	0.02	0.077	7
1092056	Soil	10.5	19.5	8.4	87	0.1	19.5	3.9	60	1.45	13.1	<0.5	0.1	6	<0.1	2.3	0.2	62	<0.01	0.040	11
1092057	Soil	20.0	23.3	14.2	116	0.3	25.1	4.3	520	1.55	13.6	<0.5	0.1	14	0.2	4.9	0.2	109	0.03	0.090	8
1092058	Soil	7.7	8.0	3.3	38	0.3	9.2	1.3	25	0.53	4.8	<0.5	<0.1	5	0.3	0.8	<0.1	43	0.02	0.048	7
1092059	Soil	11.7	12.2	6.5	111	0.2	22.4	2.8	67	1.04	8.3	<0.5	<0.1	6	0.2	1.9	<0.1	53	0.03	0.070	6
1092060	Soil	0.9	3.7	2.8	12	0.1	2.8	0.6	12	0.40	1.9	<0.5	<0.1	4	<0.1	0.2	<0.1	13	0.02	0.057	2
1092061	Soil	7.5	12.3	8.2	82	0.2	16.9	2.4	41	1.30	12.2	<0.5	0.1	7	0.1	1.9	0.2	64	0.02	0.094	8
1092062	Soil	6.4	20.2	9.5	175	0.7	35.8	6.1	611	1.65	9.6	1.2	0.5	56	1.6	1.4	0.1	45	0.45	0.103	8
1092063	Soil	5.4	20.6	7.8	83	1.5	22.6	4.0	51	1.32	4.9	<0.5	0.1	7	0.4	1.1	<0.1	28	0.01	0.080	5
1092064	Soil	1.6	8.0	3.9	28	<0.1	6.9	3.5	442	0.73	2.0	<0.5	<0.1	9	0.1	0.4	<0.1	14	0.04	0.136	3
1092065	Soil	0.8	5.4	2.8	11	<0.1	6.8	3.3	177	0.57	1.0	<0.5	<0.1	6	0.1	0.2	<0.1	8	0.05	0.040	1
1092066	Soil	3.9	37.4	8.0	151	<0.1	45.4	12.2	227	4.14	20.2	0.6	0.6	4	<0.1	1.7	0.2	42	<0.01	0.044	23
1092067	Soil	13.9	44.3	49.5	297	0.4	78.4	7.1	39	2.44	14.4	<0.5	0.3	52	0.2	3.9	0.4	113	0.01	0.148	13
1092068	Soil	14.4	25.4	24.4	127	0.9	32.2	3.4	33	1.43	10.8	1.5	<0.1	37	<0.1	3.2	0.2	159	0.02	0.066	11
1092069	Soil	3.8	21.7	32.8	91	0.3	21.2	3.4	84	1.72	11.7	1.2	0.1	73	0.1	1.5	0.3	45	0.08	0.220	15
1092070	Soil	1.4	4.5	2.5	17	0.2	4.4	1.4	26	0.52	3.8	<0.5	<0.1	3	<0.1	0.3	<0.1	10	0.01	0.031	2
1092071	Soil	2.4	44.6	15.1	92	0.1	44.4	32.3	763	4.08	146.1	1.7	1.3	10	0.2	2.3	0.3	30	0.04	0.061	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092042	Soil	5	0.02	58	0.004	<1	0.30	0.007	0.04	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092043	Soil	16	0.08	367	0.002	3	0.29	0.002	0.07	<0.1	0.45	7.3	0.1	<0.05	<1	0.8	0.3	N.A.	N.A.	N.A.	N.A.
1092044	Soil	4	0.02	87	0.004	<1	0.32	0.015	0.03	<0.1	0.03	0.5	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092045	Soil	4	0.02	547	0.002	<1	0.35	0.016	0.03	<0.1	0.04	0.4	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092046	Soil	5	0.06	1431	0.003	<1	0.46	0.011	0.05	<0.1	0.07	0.5	<0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092047	Soil	9	0.04	158	0.004	<1	0.50	0.007	0.03	<0.1	0.02	0.4	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092048	Soil	10	0.04	577	0.006	<1	0.69	0.007	0.05	<0.1	0.08	1.2	0.3	0.06	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092049	Soil	11	0.10	1766	0.003	2	0.53	0.004	0.09	<0.1	0.32	3.6	0.1	0.09	1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092050	Soil	7	0.03	199	0.002	<1	0.45	0.006	0.07	<0.1	0.02	0.8	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092051	Soil	19	0.15	1395	0.003	<1	0.77	0.004	0.10	0.1	0.48	2.5	0.4	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092052	Soil	4	0.03	140	0.003	<1	0.40	0.023	0.03	<0.1	0.08	0.1	<0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092053	Soil	13	0.03	141	0.003	<1	0.53	0.005	0.08	0.1	0.03	0.4	0.2	0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092054	Soil	15	0.04	113	0.004	<1	0.43	0.003	0.07	<0.1	0.02	0.9	0.2	0.06	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092055	Soil	12	0.02	85	0.007	<1	0.44	0.003	0.06	0.1	<0.01	0.3	0.2	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092056	Soil	10	0.02	79	0.004	<1	0.37	0.003	0.05	<0.1	<0.01	0.3	0.2	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092057	Soil	10	0.03	130	0.004	<1	0.46	0.010	0.06	0.1	0.02	0.4	0.7	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092058	Soil	7	0.02	118	0.003	<1	0.36	0.009	0.05	<0.1	0.02	0.3	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092059	Soil	9	0.03	76	0.005	<1	0.34	0.009	0.05	0.2	0.02	0.4	0.3	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092060	Soil	3	0.01	68	0.002	<1	0.29	0.018	0.02	<0.1	<0.01	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092061	Soil	12	0.04	103	0.005	<1	0.50	0.007	0.06	<0.1	0.02	0.3	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092062	Soil	14	0.13	3707	0.004	1	1.31	0.017	0.05	<0.1	0.24	1.6	0.3	0.07	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092063	Soil	7	0.03	1234	0.002	<1	0.53	0.013	0.06	<0.1	0.06	0.3	0.1	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092064	Soil	5	0.02	420	0.004	<1	0.52	0.018	0.04	<0.1	0.01	0.3	<0.1	<0.05	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092065	Soil	3	0.02	382	0.007	<1	0.22	0.024	0.05	<0.1	<0.01	0.6	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092066	Soil	9	0.04	159	0.005	1	0.44	0.004	0.08	<0.1	0.03	1.5	0.1	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092067	Soil	21	0.06	289	0.003	2	0.69	0.004	0.13	0.1	0.04	1.1	0.2	<0.05	3	9.4	0.3	N.A.	N.A.	N.A.	N.A.
1092068	Soil	14	0.04	186	0.006	2	0.44	0.007	0.09	0.2	0.02	0.4	0.2	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092069	Soil	18	0.12	331	0.002	<1	0.81	0.005	0.10	<0.1	0.04	<0.1	0.2	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092070	Soil	3	0.02	43	0.003	<1	0.21	0.017	0.03	<0.1	0.02	0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092071	Soil	9	0.08	616	0.011	<1	0.77	0.008	0.09	0.1	0.05	3.4	0.2	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092042	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092043	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092044	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092045	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092046	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092047	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092048	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092049	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092050	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092051	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092052	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092053	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092054	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092055	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092056	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092058	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092062	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092063	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092071	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092042	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092043	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092044	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092045	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092046	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092047	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092048	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092049	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092050	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092051	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092052	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092053	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092054	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092055	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092056	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092058	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092062	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092063	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092071	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092072	Soil	3.2	43.8	17.7	126	0.6	33.6	7.1	163	2.63	13.1	0.6	0.3	25	0.3	1.5	0.2	30	0.05	0.166	8
1092073	Soil	7.3	140.9	21.2	497	2.5	123.5	18.7	239	5.91	15.5	3.4	5.4	78	1.8	3.5	0.3	35	1.36	0.166	16
1092074	Soil	0.3	2.4	1.0	4	<0.1	1.6	0.5	9	0.20	<0.5	<0.5	<0.1	5	<0.1	0.1	<0.1	5	0.05	0.028	<1
1092075	Soil	3.6	17.8	7.9	47	0.5	20.8	3.8	73	1.59	7.0	<0.5	<0.1	9	0.1	1.2	<0.1	34	0.13	0.060	4
1092076	Soil	2.0	7.6	3.0	27	0.3	8.2	1.0	37	0.46	1.9	<0.5	<0.1	8	0.1	0.9	<0.1	10	0.15	0.053	2
1092077	Soil	7.7	44.9	12.8	151	0.1	47.9	8.1	86	2.67	22.3	1.3	0.3	6	<0.1	2.6	0.2	44	0.02	0.092	8
1092078	Soil	3.4	27.1	11.3	84	0.1	26.3	7.3	132	2.72	26.1	1.5	0.3	7	<0.1	1.5	0.2	30	0.02	0.074	8
1092079	Soil	2.8	30.9	14.1	56	0.2	31.2	8.7	126	3.05	13.7	0.7	2.6	6	<0.1	1.2	0.2	21	0.02	0.045	9
1092080	Soil	4.3	24.0	11.5	88	0.1	22.4	5.9	76	2.13	21.7	<0.5	0.3	9	<0.1	1.6	0.2	43	0.02	0.049	9
1092081	Soil	3.9	17.9	7.5	55	0.2	15.7	3.5	48	1.35	16.1	0.8	0.2	10	<0.1	1.3	0.1	35	0.04	0.117	7
1092082	Soil	0.3	4.0	1.2	4	0.5	1.3	0.4	7	0.18	0.6	<0.5	<0.1	5	<0.1	<0.1	<0.1	4	0.04	0.032	1
1092083	Soil	1.6	12.8	5.0	26	<0.1	8.3	2.6	52	0.93	11.2	0.7	<0.1	6	<0.1	0.6	0.1	26	0.03	0.056	6
1092084	Soil	2.2	17.2	5.8	43	<0.1	12.6	4.0	125	1.39	16.0	1.3	0.1	6	<0.1	1.0	0.2	26	0.03	0.065	6
1092085	Soil	4.0	17.2	6.7	79	<0.1	18.3	4.3	136	1.32	14.6	1.1	0.3	8	0.3	1.4	0.1	32	0.04	0.080	4
1092086	Soil	6.8	24.6	8.7	117	0.2	26.1	5.3	303	1.70	16.8	0.9	0.2	16	0.2	2.2	0.1	47	0.04	0.135	7
1092087	Soil	2.8	30.7	5.4	95	2.9	28.0	3.7	98	1.09	12.1	3.3	0.4	59	0.8	1.5	0.1	24	0.75	0.332	7
1092088	Soil	4.0	14.3	5.4	58	<0.1	19.7	3.9	61	0.93	17.3	<0.5	0.1	7	<0.1	1.3	<0.1	34	0.05	0.047	9
1092089	Soil	4.4	10.8	3.9	43	0.1	11.1	2.4	28	0.69	9.1	<0.5	0.2	4	<0.1	0.9	<0.1	36	0.01	0.041	7
1092090	Soil	5.3	10.5	4.2	57	<0.1	14.9	2.5	23	0.66	8.9	<0.5	0.1	3	<0.1	1.4	<0.1	46	<0.01	0.024	7
1092091	Soil	2.3	50.5	17.5	65	0.9	70.7	19.2	146	7.76	9.3	11.9	4.1	22	0.2	2.2	0.5	15	0.18	0.113	10
1092092	Soil	4.2	39.4	14.5	187	0.8	59.1	9.7	109	2.46	24.0	3.1	2.6	36	0.4	5.2	0.2	29	0.52	0.109	9
1092093	Soil	1.8	18.5	4.8	72	0.5	22.3	3.4	35	0.80	8.1	0.5	0.6	16	0.1	1.7	<0.1	16	0.26	0.038	3
1092094	Soil	3.3	33.6	9.6	154	1.0	40.8	6.6	136	1.78	16.6	0.6	0.4	17	0.6	3.4	<0.1	24	0.24	0.101	6
1092095	Soil	0.8	6.3	1.9	31	0.5	6.6	1.1	27	0.35	3.5	<0.5	<0.1	18	0.5	0.4	<0.1	13	0.33	0.076	2
1092096	Soil	16.6	25.6	7.7	321	0.1	58.1	5.5	111	1.64	25.0	1.6	0.5	7	1.1	4.6	0.1	55	0.06	0.082	7
1092097	Soil	3.6	36.6	4.4	98	2.9	39.8	5.3	42	1.62	14.5	0.5	0.3	2	<0.1	2.2	<0.1	16	<0.01	0.031	7
1092098	Soil	20.2	37.1	11.8	288	<0.1	66.9	7.6	62	2.18	35.2	<0.5	0.2	5	0.2	6.0	0.1	89	<0.01	0.041	12
1092099	Soil	26.7	20.0	7.2	329	0.2	74.7	4.2	48	1.28	14.6	<0.5	0.3	21	1.7	2.6	<0.1	36	0.72	0.125	7
1092100	Soil	36.2	34.0	9.0	216	0.2	105.4	5.0	65	1.54	17.0	<0.5	0.3	22	1.4	2.4	0.1	36	0.39	0.118	8
1091761	Soil	1.9	194.9	21.9	245	1.5	146.6	58.5	1147	10.26	592.4	15.4	6.4	14	0.1	4.1	0.6	22	0.13	0.068	24

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092072	Soil	15	0.11	1025	0.005	<1	1.18	0.009	0.07	0.1	0.11	0.6	0.3	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092073	Soil	15	0.58	4982	0.004	3	0.59	0.004	0.20	<0.1	0.67	6.4	0.2	0.06	1	8.2	0.3	N.A.	N.A.	N.A.	N.A.
1092074	Soil	2	0.02	128	0.003	<1	0.17	0.026	0.02	<0.1	0.02	0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092075	Soil	6	0.04	1230	0.002	<1	0.40	0.018	0.03	<0.1	0.12	0.5	<0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092076	Soil	2	0.03	97	0.004	<1	0.29	0.027	0.02	<0.1	0.12	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092077	Soil	9	0.03	268	0.002	<1	0.66	0.005	0.04	<0.1	0.02	0.4	0.2	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092078	Soil	10	0.06	229	0.005	2	0.66	0.004	0.06	<0.1	0.03	0.6	0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092079	Soil	8	0.05	1052	0.003	1	0.88	0.003	0.05	<0.1	0.09	2.1	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092080	Soil	9	0.04	295	0.005	<1	0.61	0.003	0.05	0.1	0.01	0.6	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092081	Soil	9	0.03	760	0.003	2	0.52	0.007	0.06	0.1	0.02	0.4	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092082	Soil	<1	0.01	168	0.004	<1	0.38	0.021	0.01	<0.1	0.02	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092083	Soil	7	0.03	124	0.004	<1	0.59	0.007	0.03	<0.1	0.02	0.2	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092084	Soil	6	0.03	193	0.006	<1	0.50	0.011	0.05	<0.1	0.02	0.3	<0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092085	Soil	6	0.03	417	0.002	1	0.39	0.013	0.04	<0.1	0.02	0.3	0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092086	Soil	9	0.03	416	0.003	2	0.51	0.006	0.07	<0.1	0.03	0.5	0.2	0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092087	Soil	10	0.19	1476	0.006	5	0.96	0.014	0.07	0.1	0.40	1.9	0.2	0.14	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092088	Soil	8	0.03	107	0.004	2	0.23	0.006	0.05	<0.1	0.05	0.3	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092089	Soil	6	0.02	89	0.005	2	0.30	0.008	0.05	<0.1	0.02	0.6	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092090	Soil	6	0.02	67	0.003	2	0.31	0.006	0.04	<0.1	0.01	0.4	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092091	Soil	12	0.11	797	0.004	2	1.39	0.006	0.11	<0.1	0.14	4.6	0.2	0.15	2	1.0	0.2	N.A.	N.A.	N.A.	N.A.
1092092	Soil	8	0.08	881	0.003	1	0.40	0.004	0.05	<0.1	0.24	3.5	0.2	<0.05	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092093	Soil	5	0.05	493	0.003	<1	0.31	0.017	0.03	<0.1	0.09	1.2	<0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092094	Soil	7	0.05	279	0.003	1	0.44	0.012	0.04	<0.1	0.19	1.4	<0.1	<0.05	1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092095	Soil	4	0.07	325	0.003	<1	0.41	0.030	0.02	<0.1	0.09	0.2	<0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092096	Soil	11	0.02	267	0.002	2	0.32	0.006	0.05	<0.1	0.05	0.7	0.3	<0.05	1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092097	Soil	7	0.02	51	0.002	2	0.24	0.005	0.05	<0.1	0.03	0.7	0.2	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092098	Soil	11	0.03	78	0.002	1	0.37	0.002	0.05	<0.1	0.03	0.5	0.3	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092099	Soil	8	0.05	197	0.004	2	0.53	0.011	0.05	<0.1	0.12	1.0	0.8	<0.05	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092100	Soil	9	0.05	254	0.003	1	0.51	0.009	0.05	0.1	0.24	1.3	0.7	<0.05	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091761	Soil	11	0.12	1016	0.003	2	0.69	0.003	0.11	<0.1	0.16	11.1	0.3	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092075	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092081	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092085	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092087	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091761	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092075	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092081	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092085	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092087	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091761	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091762	Soil	2.2	66.1	18.9	92	0.4	69.0	28.1	996	5.60	209.9	6.0	3.4	12	0.2	2.1	0.4	22	0.10	0.093	19
1091763	Soil	8.5	87.2	23.1	241	0.8	73.9	16.8	251	4.25	78.1	1.8	3.8	28	0.5	4.0	0.3	60	0.17	0.133	12
1091764	Soil	1.9	47.1	18.2	48	0.4	52.3	24.7	794	4.09	20.2	6.0	2.3	24	0.1	1.8	0.4	17	0.21	0.081	13
1091765	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091766	Soil	2.0	82.6	23.7	76	1.0	76.1	31.6	1054	6.38	35.6	9.6	2.6	14	0.1	1.8	0.5	19	0.15	0.080	13
1091767	Soil	1.9	118.0	30.0	102	1.6	103.0	49.4	1022	8.39	29.9	18.5	3.5	19	0.2	2.7	0.6	17	0.17	0.091	20
1091768	Soil	10.1	80.2	40.1	178	1.3	87.2	29.5	978	5.92	27.5	6.3	3.9	18	0.3	3.0	0.4	16	0.16	0.067	21
1091769	Soil	7.5	71.2	30.9	152	1.0	69.6	25.3	777	5.31	188.6	4.9	3.8	16	0.3	2.9	0.4	19	0.12	0.076	17
1091770	Soil	10.4	55.3	20.3	161	0.7	76.4	15.4	509	3.38	31.9	4.3	2.9	46	0.4	3.0	0.3	37	0.54	0.210	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091762	Soil	11	0.09	1053	0.003	3	0.57	0.003	0.09	<0.1	0.10	7.0	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091763	Soil	11	0.04	978	0.001	1	0.42	0.001	0.07	<0.1	0.15	4.8	0.2	<0.05	1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091764	Soil	7	0.08	2210	0.005	3	0.60	0.007	0.12	<0.1	0.07	6.1	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091765	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.8	85.0	34.0	164
1091766	Soil	7	0.09	1032	0.003	2	0.60	0.006	0.08	<0.1	0.11	5.8	0.3	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091767	Soil	8	0.10	1432	0.004	3	0.68	0.006	0.11	<0.1	0.15	7.3	0.3	<0.05	1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091768	Soil	6	0.08	1094	0.002	2	0.43	0.004	0.11	<0.1	0.29	6.8	0.3	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091769	Soil	6	0.07	1823	0.003	2	0.45	0.005	0.10	<0.1	0.12	5.9	0.3	<0.05	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091770	Soil	10	0.08	969	0.003	7	0.55	0.003	0.17	<0.1	0.15	4.3	0.2	<0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091762	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091763	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091764	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091765	Soil	1.3	75.7	32.4	1231	6.01	58.4	4.5	1.4	34	0.5	2.7	0.5	36	0.18	0.139	15	14	0.12	1430	0.005
1091766	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091767	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091768	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091769	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091770	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000671.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091762	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091763	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091764	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091765	Soil	<20	0.79	0.007	0.13	<0.1	0.11	6.2	0.4	0.09	2	3.0	<0.2
1091766	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091767	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091768	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091769	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091770	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1090847	Soil	6.3	17.9	3.7	133	0.9	18.6	2.2	59	0.68	10.2	1.1	0.5	36	2.3	2.5	0.3	28	0.65	0.054	4
REP 1090847	QC	6.8	19.4	4.0	143	1.0	22.2	2.3	63	0.72	10.6	2.0	0.5	38	2.0	2.7	0.2	29	0.71	0.062	5
1090909	Soil	2.5	26.0	16.7	1643	1.1	147.8	15.7	818	4.61	24.2	5.7	0.8	56	6.2	5.5	0.3	92	2.03	0.211	26
REP 1090909	QC	2.6	26.4	16.0	1645	1.1	148.6	15.1	813	4.78	23.5	5.7	0.9	56	6.3	5.6	0.3	93	2.05	0.221	26
1090931	Soil	6.3	17.8	12.4	79	0.3	18.5	3.3	76	2.24	14.5	0.6	1.6	8	0.3	1.7	<0.1	69	0.01	0.051	8
REP 1090931	QC	5.6	17.9	12.2	76	0.3	18.6	3.3	75	2.15	13.9	2.4	1.5	8	0.2	1.5	<0.1	72	0.02	0.051	7
1090948	Soil	5.0	22.2	11.9	76	0.5	16.2	2.5	45	1.14	10.2	<0.5	0.3	15	0.4	1.8	<0.1	52	0.01	0.077	4
REP 1090948	QC	4.3	22.4	11.6	76	0.5	15.7	2.6	45	1.13	9.8	8.4	0.3	15	0.4	1.6	<0.1	51	0.02	0.071	4
1090974	Soil	7.4	53.0	16.1	242	0.6	50.7	8.6	221	2.96	27.4	5.8	1.9	50	2.2	3.9	0.2	65	0.24	0.118	10
REP 1090974	QC	8.2	52.5	16.1	235	0.7	48.8	8.4	218	2.94	27.5	3.3	1.8	50	2.0	3.7	0.2	64	0.23	0.115	10
1090983	Soil	4.0	23.1	9.5	78	0.3	12.8	2.2	35	1.40	11.4	0.9	0.4	17	0.6	1.4	0.1	41	0.18	0.036	7
REP 1090983	QC	4.6	23.0	9.7	81	0.4	14.4	2.3	38	1.51	12.0	1.5	0.5	18	0.7	1.4	0.1	44	0.19	0.037	8
1090997	Soil	0.7	5.3	4.1	12	<0.1	3.6	1.3	36	0.49	3.9	<0.5	<0.1	5	<0.1	0.2	<0.1	12	0.03	0.071	1
REP 1090997	QC	0.7	6.5	4.0	13	0.1	3.8	1.4	43	0.59	4.7	<0.5	<0.1	6	<0.1	0.2	<0.1	14	0.03	0.093	1
1091730	Soil	6.0	36.1	25.9	54	0.8	22.9	4.8	66	2.22	21.5	1.0	0.2	39	<0.1	2.8	0.3	53	0.01	0.074	4
REP 1091730	QC	6.1	35.9	25.6	54	0.8	22.6	4.8	67	2.19	20.5	2.2	0.2	40	<0.1	3.0	0.3	54	0.01	0.075	4
1091736	Soil	6.3	92.1	29.0	231	1.7	70.4	18.9	673	4.05	27.4	5.6	1.0	45	0.7	4.6	0.4	56	0.12	0.142	4
REP 1091736	QC	6.2	92.9	28.9	230	1.7	70.5	18.6	655	4.03	27.8	6.5	1.0	46	0.8	4.5	0.4	55	0.12	0.142	4
1091756	Soil	45.8	83.0	118.6	83	8.3	38.5	3.9	115	3.30	26.3	4.3	0.9	140	1.0	18.0	0.7	340	0.18	0.235	24
REP 1091756	QC	45.7	83.0	121.8	83	8.4	39.7	4.1	119	3.31	25.0	4.1	1.0	140	0.9	18.5	0.6	328	0.17	0.236	26
1092010	Soil	7.2	27.0	12.8	149	0.4	26.2	4.9	121	2.30	22.4	3.6	1.6	46	1.0	3.3	0.2	102	0.13	0.120	8
REP 1092010	QC	6.8	26.3	12.8	146	0.4	26.0	4.7	120	2.28	20.9	5.7	1.6	46	0.8	3.2	0.2	102	0.13	0.122	8
1092036	Soil	26.5	50.9	70.7	296	1.3	76.6	7.1	43	2.46	27.0	2.9	1.2	157	0.6	7.1	0.3	178	0.04	0.130	17
REP 1092036	QC	26.4	52.5	73.9	310	1.3	76.2	7.4	45	2.46	27.3	3.2	1.5	140	0.6	7.9	0.4	181	0.04	0.134	18
1092042	Soil	3.0	15.1	5.6	40	<0.1	14.7	4.1	68	1.39	6.5	1.4	0.1	3	<0.1	0.9	0.1	25	0.01	0.032	7
REP 1092042	QC	2.4	16.3	5.5	40	<0.1	15.0	4.5	72	1.47	7.0	<0.5	0.1	3	<0.1	0.9	<0.1	27	0.01	0.031	8
1092060	Soil	0.9	3.7	2.8	12	0.1	2.8	0.6	12	0.40	1.9	<0.5	<0.1	4	<0.1	0.2	<0.1	13	0.02	0.057	2
REP 1092060	QC	1.0	3.7	2.9	12	0.1	2.6	0.7	12	0.40	2.1	0.6	<0.1	4	<0.1	0.2	<0.1	12	0.01	0.058	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000671.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1090847	Soil	4	0.10	1150	0.006	3	0.34	0.020	0.03	<0.1	0.18	1.4	<0.1	<0.05	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090847	QC	5	0.11	1194	0.006	3	0.35	0.021	0.03	<0.1	0.18	1.5	<0.1	<0.05	<1	1.1	<0.2				
1090909	Soil	59	0.15	903	0.009	5	1.86	0.007	0.07	0.3	1.98	3.2	0.1	<0.05	4	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090909	QC	60	0.15	929	0.009	5	1.88	0.007	0.07	0.3	2.01	3.2	0.1	<0.05	4	1.7	<0.2				
1090931	Soil	13	0.06	367	0.003	1	0.77	0.003	0.04	<0.1	0.06	0.9	0.2	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090931	QC	13	0.07	360	0.003	<1	0.78	0.003	0.04	0.1	0.02	0.8	0.2	<0.05	3	1.0	<0.2				
1090948	Soil	11	0.04	198	0.004	<1	0.46	0.009	0.04	<0.1	0.11	0.5	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090948	QC	11	0.04	190	0.004	1	0.45	0.008	0.04	0.2	0.10	0.5	0.2	<0.05	2	0.6	<0.2				
1090974	Soil	20	0.14	4329	0.004	2	0.90	0.002	0.06	0.1	0.35	2.3	0.3	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090974	QC	20	0.14	4309	0.003	<1	0.89	0.002	0.07	0.1	0.38	2.3	0.2	<0.05	2	2.8	<0.2				
1090983	Soil	11	0.03	400	0.009	<1	0.39	0.006	0.05	0.2	0.03	0.7	0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090983	QC	14	0.03	402	0.012	<1	0.41	0.007	0.05	0.3	0.04	1.2	<0.1	<0.05	2	1.1	<0.2				
1090997	Soil	6	0.03	25	0.004	<1	0.35	0.017	0.02	<0.1	<0.01	<0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090997	QC	8	0.03	29	0.008	<1	0.41	0.021	0.03	<0.1	0.01	0.2	<0.1	<0.05	1	<0.5	<0.2				
1091730	Soil	9	0.01	172	0.004	1	0.28	0.005	0.06	<0.1	0.02	0.7	0.2	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091730	QC	8	0.01	173	0.003	1	0.29	0.005	0.06	<0.1	0.01	0.7	0.3	<0.05	2	2.0	<0.2				
1091736	Soil	17	0.08	253	0.004	2	0.95	0.009	0.08	<0.1	0.10	4.2	0.4	0.07	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091736	QC	18	0.08	257	0.003	1	0.98	0.009	0.08	0.1	0.07	4.0	0.4	0.09	3	2.9	<0.2				
1091756	Soil	36	0.16	253	0.014	4	0.71	0.009	0.31	0.5	0.86	1.7	1.2	0.62	4	6.1	0.7	N.A.	N.A.	N.A.	N.A.
REP 1091756	QC	37	0.17	668	0.016	4	0.69	0.009	0.31	0.7	0.79	1.9	1.3	0.64	4	6.1	0.6				
1092010	Soil	17	0.11	2149	0.002	2	0.79	0.002	0.06	0.2	0.16	1.4	0.3	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092010	QC	18	0.11	2074	0.002	3	0.80	0.002	0.06	0.2	0.15	1.4	0.3	<0.05	2	2.3	<0.2				
1092036	Soil	16	0.03	386	0.011	3	0.41	0.003	0.10	0.3	0.10	1.2	0.5	0.08	3	4.4	0.2	N.A.	N.A.	N.A.	N.A.
REP 1092036	QC	17	0.03	395	0.014	3	0.41	0.003	0.11	0.4	0.10	1.4	0.5	<0.05	3	4.6	<0.2				
1092042	Soil	5	0.02	58	0.004	<1	0.30	0.007	0.04	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092042	QC	5	0.02	71	0.004	<1	0.32	0.008	0.04	0.1	0.02	0.4	<0.1	<0.05	2	<0.5	<0.2				
1092060	Soil	3	0.01	68	0.002	<1	0.29	0.018	0.02	<0.1	<0.01	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092060	QC	3	0.01	65	0.003	<1	0.29	0.019	0.02	<0.1	<0.01	0.1	<0.1	<0.05	1	<0.5	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000671.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1090847	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090847	QC																					
1090909	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090909	QC																					
1090931	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090931	QC																					
1090948	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090948	QC																					
1090974	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090974	QC																					
1090983	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090983	QC																					
1090997	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090997	QC																					
1091730	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091730	QC																					
1091736	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091736	QC																					
1091756	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091756	QC																					
1092010	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092010	QC																					
1092036	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092036	QC																					
1092042	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092042	QC																					
1092060	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092060	QC																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000671.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1090847	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090847	QC													
1090909	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090909	QC													
1090931	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090931	QC													
1090948	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090948	QC													
1090974	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090974	QC													
1090983	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090983	QC													
1090997	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090997	QC													
1091730	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091730	QC													
1091736	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091736	QC													
1091756	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091756	QC													
1092010	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092010	QC													
1092036	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092036	QC													
1092042	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092042	QC													
1092060	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092060	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000671.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1092098	Soil	20.2	37.1	11.8	288	<0.1	66.9	7.6	62	2.18	35.2	<0.5	0.2	5	0.2	6.0	0.1	89	<0.01	0.041	12
REP 1092098	QC	21.8	38.5	12.7	288	0.1	69.2	7.9	63	2.30	36.7	1.7	0.4	5	0.2	6.9	0.2	88	0.01	0.043	12
Reference Materials																					
STD DS8	Standard	11.5	96.6	111.3	277	1.6	33.1	6.7	545	2.14	23.1	100.7	6.0	53	1.8	4.3	5.2	37	0.63	0.069	13
STD DS8	Standard	12.1	98.3	113.8	280	1.6	33.0	6.7	551	2.17	23.0	99.4	6.0	53	2.0	4.3	5.2	36	0.63	0.068	13
STD DS8	Standard	12.9	92.8	113.6	274	1.5	31.9	6.4	551	2.14	23.2	110.8	6.3	56	2.2	4.4	5.0	37	0.63	0.072	14
STD DS8	Standard	12.4	93.9	114.6	277	1.6	31.7	6.7	550	2.24	22.6	93.4	6.7	55	1.9	4.5	5.1	37	0.65	0.070	15
STD DS8	Standard	12.3	108.2	119.5	299	1.8	36.5	7.5	582	2.41	25.9	105.4	6.6	55	2.3	4.8	5.4	43	0.67	0.077	13
STD DS8	Standard	12.7	108.5	126.3	302	1.7	37.3	7.5	571	2.33	25.5	105.1	6.8	56	2.2	4.3	5.4	42	0.66	0.075	14
STD DS8	Standard	13.0	109.6	126.3	320	1.8	38.1	7.2	610	2.47	25.6	114.0	6.6	61	2.1	5.3	5.9	38	0.65	0.076	14
STD DS8	Standard	12.1	104.9	125.8	307	1.8	38.7	7.3	600	2.60	25.1	120.7	7.1	60	2.2	5.1	5.9	37	0.63	0.074	14
STD DS8	Standard	12.8	105.6	123.1	321	1.9	37.4	7.2	620	2.49	27.2	119.4	6.9	68	2.3	5.7	6.9	41	0.69	0.080	15
STD DS8	Standard	12.5	104.1	123.3	317	2.0	37.1	7.2	607	2.45	27.1	107.7	6.9	67	2.6	5.6	7.0	41	0.68	0.080	14
STD DS8	Standard	13.3	116.3	129.2	333	2.0	40.8	7.9	651	2.63	31.9	112.1	6.7	63	2.5	4.6	6.2	47	0.73	0.086	14
STD DS8	Standard	13.3	116.7	128.3	340	1.8	40.6	7.9	655	2.65	31.2	119.5	6.6	69	2.8	4.7	7.1	44	0.77	0.099	14
STD DS8	Standard	11.8	104.3	121.9	303	1.7	36.0	7.2	602	2.46	24.7	117.8	6.1	62	2.2	5.1	5.8	42	0.69	0.073	13
STD DS8	Standard	13.3	105.5	121.1	308	1.9	38.9	7.6	639	2.54	25.4	104.6	6.7	68	2.1	5.2	6.1	40	0.70	0.077	16
STD DS8	Standard	13.3	106.7	123.8	303	1.8	38.6	7.7	603	2.43	24.9	110.8	7.1	61	2.3	5.2	5.4	41	0.70	0.080	14
STD DS8	Standard	13.4	110.6	121.1	306	1.8	37.9	8.1	589	2.39	25.0	104.1	6.5	63	2.3	5.9	6.3	41	0.67	0.078	14
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000671.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1092098	Soil	11	0.03	78	0.002	1	0.37	0.002	0.05	<0.1	0.03	0.5	0.3	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092098	QC	11	0.03	85	0.003	2	0.38	0.002	0.05	<0.1	0.03	0.5	0.3	<0.05	2	2.0	<0.2				
Reference Materials																					
STD DS8	Standard	101	0.54	239	0.097	3	0.84	0.084	0.37	2.6	0.17	2.3	4.9	0.11	4	5.0	4.4				
STD DS8	Standard	102	0.53	247	0.096	2	0.83	0.079	0.37	2.5	0.16	2.1	5.0	0.11	4	4.9	4.5				
STD DS8	Standard	101	0.58	254	0.107	<1	0.84	0.076	0.37	2.8	0.19	1.9	5.1	0.11	4	5.6	4.6				
STD DS8	Standard	101	0.58	267	0.109	<1	0.84	0.077	0.38	2.8	0.17	2.0	4.9	0.09	4	4.8	4.7				
STD DS8	Standard	113	0.59	259	0.104	3	0.86	0.081	0.41	2.8	0.21	1.9	5.1	0.15	5	4.9	4.8				
STD DS8	Standard	113	0.59	259	0.106	3	0.85	0.083	0.40	2.8	0.18	2.0	5.3	0.12	4	5.3	4.4				
STD DS8	Standard	114	0.54	275	0.109	3	0.84	0.070	0.40	2.9	0.20	1.8	5.3	0.08	4	5.6	4.8				
STD DS8	Standard	114	0.54	274	0.108	3	0.85	0.068	0.39	3.2	0.22	1.9	5.4	0.06	5	4.6	5.0				
STD DS8	Standard	115	0.60	291	0.110	3	0.90	0.088	0.42	3.0	0.19	2.2	5.5	0.14	5	4.8	4.9				
STD DS8	Standard	114	0.60	290	0.108	2	0.88	0.085	0.43	3.0	0.18	2.1	5.5	0.14	5	5.8	5.3				
STD DS8	Standard	122	0.64	297	0.109	3	0.95	0.088	0.46	2.9	0.22	2.0	5.5	<0.05	5	5.4	5.3				
STD DS8	Standard	121	0.67	326	0.107	3	0.97	0.103	0.48	3.1	0.22	2.2	5.4	0.08	5	5.1	5.7				
STD DS8	Standard	115	0.59	252	0.106	3	0.86	0.080	0.41	2.8	0.22	1.9	5.4	0.09	4	4.9	4.9				
STD DS8	Standard	120	0.61	284	0.114	2	0.92	0.088	0.41	2.8	0.20	1.9	5.7	0.11	5	5.4	4.8				
STD DS8	Standard	115	0.56	271	0.120	2	0.90	0.070	0.41	2.9	0.18	2.1	5.4	0.06	5	5.4	5.6				
STD DS8	Standard	117	0.58	280	0.119	2	0.87	0.082	0.42	3.0	0.20	2.1	5.2	0.16	5	5.3	5.4				
STD DS8	Standard																	14.0	117.3	126.8	318
STD OREAS45CA	Standard																	0.9	488.6	19.7	59
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000671.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1092098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092098	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.8	39.4	8.1	635	2.63	26.5	96.8	6.8	71	2.4	4.8	6.4	45	0.75	0.089	15	116	0.65	304	0.118
STD OREAS45CA	Standard	0.3	244.6	87.8	897	16.02	4.1	39.3	6.6	15	<0.1	<0.1	0.2	187	0.41	0.039	15	659	0.15	151	0.144
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000671.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1092098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092098	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.99	0.096	0.44	3.0	0.21	2.4	5.5	0.17	5	6.3	5.3
STD OREAS45CA	Standard	<20	4.00	0.013	0.07	<0.1	0.01	39.0	<0.1	<0.05	18	0.6	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000671.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000671.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000671.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000671.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 26, 2011
Report Date: August 30, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11000746.3

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #5
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve to 230 mesh			WHI
1DX2	310	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	10	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 3: Includes 1DX analysis

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090881	Soil	7.0	53.5	42.4	68	4.2	13.2	2.3	62	5.02	80.7	7.1	0.9	14	<0.1	5.4	0.5	82	<0.01	0.180	1
1090882	Soil	9.6	88.8	17.9	158	2.6	58.9	5.1	118	3.19	38.0	1.9	1.0	68	0.6	2.0	0.2	28	0.11	0.070	3
1090883	Soil	2.1	19.0	12.0	21	1.2	5.7	0.9	20	1.13	23.6	1.2	0.3	6	<0.1	1.2	0.2	26	0.02	0.064	<1
1090884	Soil	2.8	37.3	18.0	81	0.9	16.6	3.0	50	2.46	32.4	2.5	0.5	15	<0.1	2.0	0.3	55	0.02	0.094	1
1090885	Soil	1.5	14.1	5.0	32	1.1	7.8	1.5	29	0.89	10.0	<0.5	0.1	6	<0.1	0.8	0.1	23	0.02	0.045	1
1090886	Soil	2.2	29.6	14.8	56	0.3	16.0	2.8	35	1.48	22.5	1.2	0.3	10	<0.1	1.3	0.3	47	0.02	0.065	2
1090887	Soil	1.3	18.4	5.2	37	0.6	9.4	2.0	26	1.00	11.3	2.2	<0.1	7	<0.1	0.6	0.1	27	0.01	0.043	1
1090888	Soil	0.7	4.4	3.1	9	0.2	2.6	0.6	18	0.47	3.4	<0.5	<0.1	6	<0.1	0.3	<0.1	12	0.02	0.037	<1
1090889	Soil	33.5	46.1	25.4	49	5.1	13.0	2.0	91	1.82	43.3	4.1	0.2	88	0.5	25.7	0.3	314	0.07	0.239	4
1090890	Soil	48.3	37.2	28.7	82	2.6	14.7	1.3	49	2.51	56.1	2.0	0.7	118	0.9	36.4	0.3	298	0.05	0.139	3
1090891	Soil	10.3	9.9	9.4	14	0.3	3.4	0.3	5	0.65	10.9	<0.5	0.3	37	<0.1	2.8	0.2	81	0.01	0.040	2
1090892	Soil	7.0	12.8	15.4	17	1.7	4.0	0.4	8	0.55	7.8	<0.5	0.2	15	0.3	7.5	0.2	64	0.01	0.054	2
1090893	Soil	15.5	20.4	12.3	23	1.3	5.0	0.4	7	1.05	11.4	0.7	0.3	17	<0.1	5.7	0.2	58	<0.01	0.046	2
1090894	Soil	8.6	9.4	11.1	75	0.7	9.7	1.4	16	0.60	10.7	<0.5	0.2	9	<0.1	6.1	0.2	57	<0.01	0.065	3
1090895	Soil	7.0	33.0	25.0	114	0.2	23.6	6.4	87	3.25	21.3	<0.5	0.5	14	0.2	1.8	0.3	46	0.01	0.093	3
1090896	Soil	6.0	10.9	6.7	18	2.6	3.3	0.5	10	0.73	6.7	<0.5	<0.1	27	<0.1	2.5	<0.1	29	0.02	0.117	2
1090897	Soil	5.0	22.9	14.8	130	0.3	27.0	8.3	81	2.47	14.0	<0.5	0.2	13	0.2	1.6	0.2	40	0.02	0.085	4
1090898	Soil	9.9	30.5	14.7	118	0.9	28.4	4.7	69	2.40	32.3	4.4	0.6	28	0.4	4.4	0.2	73	0.04	0.094	4
1090899	Soil	21.9	35.2	28.1	225	0.3	35.5	4.4	66	2.49	41.5	2.3	0.6	21	0.3	6.6	0.2	106	<0.01	0.081	6
1090900	Soil	3.4	3.8	2.3	19	0.2	3.3	0.6	11	0.25	3.5	1.1	0.2	4	<0.1	0.8	<0.1	24	0.01	0.015	9
1090851	Soil	1.6	30.0	8.1	266	0.9	47.6	4.0	117	1.53	11.5	4.2	0.4	76	1.6	1.4	0.1	40	1.98	0.187	10
1090852	Soil	2.5	35.5	14.5	205	1.6	55.5	8.7	308	2.67	22.3	9.3	1.0	86	1.0	2.9	0.2	61	1.55	0.243	19
1090853	Soil	0.8	9.5	4.0	31	0.7	8.8	1.9	35	0.68	4.6	1.4	<0.1	12	0.1	0.7	<0.1	10	0.10	0.048	1
1090854	Soil	2.3	63.9	23.3	202	2.1	86.2	18.3	132	4.21	17.9	2.8	1.7	18	0.4	1.0	0.3	22	0.23	0.056	2
1090879	Soil	3.3	14.0	5.6	32	0.4	8.3	1.2	28	1.24	41.2	4.8	<0.1	5	<0.1	2.9	0.1	31	0.02	0.062	2
1090880	Soil	4.1	20.3	8.8	51	1.2	18.5	1.5	25	1.06	14.7	1.3	<0.1	39	0.2	0.8	0.1	19	0.04	0.040	1
1091391	Soil	1.6	19.5	11.6	58	0.5	18.0	3.6	57	1.52	32.5	0.8	0.3	30	0.1	1.4	0.2	24	0.03	0.097	2
1091392	Soil	2.3	31.6	21.1	126	1.2	42.0	6.8	119	2.38	41.2	5.7	1.5	94	0.3	2.1	0.2	28	0.88	0.107	6
1091393	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091394	Soil	1.4	30.4	15.5	146	1.0	44.0	7.1	128	2.33	18.3	4.6	0.8	71	0.7	1.2	0.2	30	1.60	0.123	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090881	Soil	13	0.02	283	0.002	1	0.44	0.004	0.08	<0.1	0.24	1.6	0.2	0.11	2	5.7	0.4	N.A.	N.A.	N.A.	N.A.
1090882	Soil	21	0.03	1081	<0.001	3	0.43	0.004	0.07	<0.1	0.45	4.0	0.1	<0.05	1	6.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090883	Soil	7	0.01	101	0.003	3	0.25	0.009	0.04	<0.1	0.10	0.6	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090884	Soil	12	0.02	137	0.003	<1	0.46	0.007	0.04	<0.1	0.08	1.1	<0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090885	Soil	8	0.01	70	0.005	1	0.19	0.012	0.03	<0.1	0.04	0.6	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090886	Soil	12	0.01	149	0.002	2	0.40	0.007	0.06	<0.1	0.03	0.6	<0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1090887	Soil	6	0.01	78	0.002	1	0.23	0.011	0.03	<0.1	0.03	0.3	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090888	Soil	4	0.01	51	0.003	<1	0.18	0.017	0.02	<0.1	0.03	<0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090889	Soil	22	0.04	564	0.005	<1	0.66	0.012	0.10	0.6	0.51	0.8	1.2	0.20	4	14.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090890	Soil	24	0.02	1539	0.002	<1	0.37	0.009	0.17	0.8	0.23	1.2	2.0	0.45	3	20.4	0.3	N.A.	N.A.	N.A.	N.A.
1090891	Soil	9	<0.01	376	0.001	<1	0.27	0.005	0.05	0.2	0.02	0.4	0.4	0.10	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090892	Soil	8	<0.01	243	0.001	<1	0.26	0.005	0.07	0.2	0.03	0.3	0.8	0.12	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090893	Soil	7	<0.01	367	<0.001	3	0.24	0.007	0.08	0.3	0.05	0.5	0.7	0.20	1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090894	Soil	8	0.01	117	0.002	2	0.34	0.005	0.04	0.2	0.02	0.3	0.3	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090895	Soil	12	0.04	68	0.001	<1	0.60	0.004	0.04	<0.1	0.02	1.4	0.2	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090896	Soil	11	<0.01	125	0.002	1	0.19	0.016	0.06	0.1	0.03	0.2	0.3	0.12	1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090897	Soil	10	0.02	77	0.004	<1	0.46	0.006	0.04	<0.1	0.02	0.8	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090898	Soil	15	0.03	502	0.002	2	0.48	0.003	0.07	0.1	0.11	1.1	0.3	0.06	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090899	Soil	11	0.01	138	0.002	<1	0.36	0.003	0.05	<0.1	0.04	0.9	0.3	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090900	Soil	4	0.01	99	0.004	<1	0.16	0.007	0.03	<0.1	0.01	0.2	0.3	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090851	Soil	30	0.08	416	0.003	2	0.82	0.011	0.05	<0.1	0.56	1.7	0.2	0.14	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090852	Soil	45	0.20	747	0.007	4	1.06	0.006	0.08	0.1	0.75	3.2	0.2	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090853	Soil	6	0.02	187	0.003	<1	0.28	0.021	0.03	<0.1	0.14	0.4	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090854	Soil	27	0.24	555	<0.001	1	1.12	0.003	0.06	<0.1	0.28	6.5	<0.1	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090879	Soil	6	0.01	86	0.005	<1	0.29	0.018	0.03	0.1	0.07	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090880	Soil	11	0.02	327	0.002	3	0.26	0.019	0.05	<0.1	0.19	0.4	<0.1	<0.05	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091391	Soil	14	0.03	122	0.004	2	0.46	0.009	0.06	0.1	0.10	0.9	<0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091392	Soil	18	0.08	628	0.001	4	0.54	0.006	0.14	<0.1	0.34	2.7	0.2	0.20	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091393	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.9	38.2	17.1	182
1091394	Soil	19	0.08	523	<0.001	4	0.60	0.005	0.09	<0.1	0.22	1.9	0.1	0.16	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090881	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090882	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090883	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090884	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090885	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090886	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090887	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090888	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090889	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090890	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090891	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090892	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090893	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090894	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090895	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090896	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090897	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090898	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090899	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090900	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090851	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090852	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090853	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090854	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090879	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090880	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091391	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091392	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091393	Soil	1.4	57.6	8.4	118	2.43	18.1	10.2	0.8	87	0.8	1.3	0.3	32	1.12	0.137	6	19	0.07	535	<0.001
1091394	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090881	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090882	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090883	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090884	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090885	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090886	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090887	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090888	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090889	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090890	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090891	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090892	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090893	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090894	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090895	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090896	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090897	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090898	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090899	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090900	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090851	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090852	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090853	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090854	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090879	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090880	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091391	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091392	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091393	Soil	<20	0.55	0.004	0.08	<0.1	0.21	2.3	0.1	0.14	1	3.1	<0.2
1091394	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091395	Soil	3.5	51.4	14.3	258	1.2	66.1	8.1	227	2.51	14.4	5.4	1.0	90	2.1	2.6	0.2	49	1.20	0.194	11
1091396	Soil	1.4	32.7	11.5	405	0.9	92.1	11.8	550	2.02	14.0	4.2	0.8	140	4.9	3.5	0.2	58	4.79	0.436	24
1091397	Soil	1.2	44.2	15.5	369	0.6	102.5	8.5	101	3.00	22.4	1.1	2.3	65	1.4	3.4	0.2	55	1.45	0.314	12
1091398	Soil	4.0	66.3	23.1	196	2.2	63.9	14.7	307	4.08	23.1	2.1	2.5	36	0.5	1.5	0.3	34	0.37	0.122	5
1091399	Soil	3.5	48.1	22.8	128	1.1	43.7	11.3	250	3.72	32.8	4.5	1.6	29	0.2	1.4	0.3	35	0.04	0.096	5
1091400	Soil	3.3	42.3	16.7	92	0.8	28.1	6.3	164	2.67	21.8	4.0	1.3	21	0.2	1.4	0.2	35	0.05	0.076	6
1091601	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091602	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091603	Soil	3.4	39.1	21.9	118	0.6	36.0	9.2	182	3.24	19.2	4.7	1.8	23	0.2	1.1	0.4	32	0.05	0.118	4
1091604	Soil	3.1	96.8	16.1	196	1.1	80.6	30.3	3982	4.59	13.7	10.6	3.1	84	0.3	1.3	0.3	35	0.02	0.123	6
1091605	Soil	1.9	51.7	17.0	161	2.4	60.5	10.5	705	4.50	13.6	7.5	1.6	69	0.6	0.9	0.2	43	0.90	0.157	12
1091606	Soil	0.6	21.7	4.0	24	0.3	5.4	1.7	32	0.78	3.1	2.9	<0.1	21	<0.1	0.2	<0.1	18	0.23	0.092	3
1091607	Soil	2.1	58.6	21.3	138	0.8	38.2	10.1	78	3.58	21.9	6.6	3.5	178	0.1	0.7	0.3	25	0.02	0.092	2
1091608	Soil	16.6	11.2	21.9	6	4.8	4.9	0.7	41	0.56	4.4	7.5	0.8	18	0.2	3.2	0.3	48	0.01	0.027	1
1091609	Soil	3.1	38.6	12.9	176	2.3	61.6	7.9	116	2.42	18.8	7.6	1.0	88	1.1	2.1	0.2	47	1.19	0.170	8
1091610	Soil	3.6	45.5	19.5	168	0.8	46.1	9.2	110	3.66	24.7	1.4	0.6	24	0.2	2.4	0.2	40	0.04	0.098	4
1091611	Soil	2.7	56.7	13.8	81	1.3	25.7	4.1	105	1.76	16.5	5.7	0.6	28	0.2	1.2	0.2	29	0.05	0.088	3
1091612	Soil	3.0	37.7	23.7	77	2.2	24.3	4.6	44	2.46	84.9	18.0	1.4	78	0.2	3.8	0.3	23	0.26	0.061	2
1091613	Soil	23.1	29.0	30.7	84	5.2	18.0	1.7	26	3.30	59.7	13.8	0.8	78	<0.1	12.2	0.4	169	0.02	0.201	4
1091614	Soil	69.6	64.2	13.5	291	0.3	144.6	8.6	189	2.02	18.4	1.2	1.8	74	2.4	2.8	0.1	60	3.36	0.096	6
1091615	Soil	43.1	69.8	27.4	998	1.8	123.4	8.4	126	2.57	45.3	3.5	2.0	50	17.2	21.7	0.2	249	2.21	0.076	4
1091616	Soil	28.1	102.3	28.3	634	1.2	141.2	13.5	240	3.18	45.6	5.1	1.9	73	5.7	11.5	0.2	131	2.64	0.104	4
1091617	Soil	46.4	101.1	38.6	2182	2.3	211.4	15.2	348	4.44	64.7	3.2	1.8	68	16.9	15.5	0.2	215	1.81	0.134	4
1091618	Soil	33.8	64.6	25.1	383	0.4	100.7	15.0	333	3.21	28.9	4.6	0.2	25	1.4	6.9	0.2	127	0.16	0.129	4
1091619	Soil	6.6	48.4	14.9	191	0.6	28.1	11.8	798	2.69	9.5	2.5	0.1	14	1.0	1.8	0.2	55	0.19	0.125	3
1091620	Soil	0.5	2.8	1.7	12	<0.1	1.8	0.4	10	0.16	0.6	<0.5	<0.1	7	<0.1	0.1	<0.1	6	0.03	0.030	<1
1091621	Soil	8.0	33.1	11.9	130	0.2	26.6	6.8	325	1.86	9.5	1.4	0.2	11	0.5	1.8	0.2	62	0.11	0.129	4
1091622	Soil	3.0	23.6	6.7	78	<0.1	11.5	3.7	141	1.44	5.7	2.1	0.1	6	0.1	1.0	0.1	34	0.04	0.071	2
1091623	Soil	11.0	79.8	50.5	299	<0.1	76.0	15.5	1254	11.04	27.1	2.2	0.6	12	1.1	4.1	0.3	68	0.03	0.137	3
1091624	Soil	5.1	50.1	20.2	95	0.1	35.6	11.5	421	3.58	12.8	2.4	0.2	7	0.2	2.2	0.3	47	0.03	0.101	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091395	Soil	25	0.11	494	0.002	5	0.69	0.008	0.10	<0.1	0.22	2.8	0.1	0.13	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091396	Soil	39	0.14	607	0.008	12	0.94	0.012	0.10	0.1	0.17	2.7	0.2	0.16	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091397	Soil	30	0.09	654	0.004	9	0.77	0.008	0.13	0.2	0.13	3.8	0.1	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091398	Soil	31	0.16	494	0.002	3	1.12	0.008	0.10	<0.1	0.15	5.4	0.2	<0.05	3	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091399	Soil	29	0.12	336	0.002	2	1.03	0.009	0.09	<0.1	0.11	3.5	0.2	<0.05	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091400	Soil	25	0.11	326	0.004	3	0.85	0.010	0.09	<0.1	0.07	2.3	0.1	0.05	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091601	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	24.9	25.9	64.2	203
1091602	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	16.6	141.0	29.6	389
1091603	Soil	28	0.16	310	0.005	4	1.14	0.008	0.09	<0.1	0.10	3.3	<0.1	0.08	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091604	Soil	28	0.11	993	0.005	<1	1.72	0.007	0.04	<0.1	0.28	6.1	0.1	0.10	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091605	Soil	31	0.21	2342	0.005	3	1.09	0.007	0.04	<0.1	0.34	4.8	<0.1	0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091606	Soil	6	0.03	1806	0.005	<1	0.64	0.018	0.02	<0.1	0.06	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091607	Soil	36	0.33	199	<0.001	1	1.57	0.003	0.06	<0.1	0.08	2.7	0.1	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091608	Soil	13	<0.01	217	<0.001	2	0.37	0.004	0.08	<0.1	0.27	1.2	0.4	0.06	1	11.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091609	Soil	26	0.07	765	0.002	3	0.71	0.003	0.06	<0.1	0.41	3.4	0.2	<0.05	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091610	Soil	23	0.06	384	0.002	1	0.84	0.004	0.06	<0.1	0.28	2.3	0.1	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091611	Soil	17	0.07	255	0.007	2	0.75	0.013	0.06	<0.1	0.23	1.9	<0.1	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091612	Soil	17	0.03	605	<0.001	1	0.43	0.003	0.10	<0.1	1.10	4.0	<0.1	0.12	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091613	Soil	20	0.02	1599	0.003	5	0.41	0.004	0.12	0.3	0.91	1.4	1.7	0.25	3	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091614	Soil	18	1.70	170	0.005	5	0.33	0.004	0.05	0.2	0.25	4.1	1.1	<0.05	<1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091615	Soil	17	1.09	252	0.002	4	0.23	0.005	0.07	<0.1	1.07	5.9	0.4	<0.05	<1	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091616	Soil	23	1.26	342	0.002	3	0.25	0.005	0.07	<0.1	0.81	5.8	0.4	<0.05	<1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091617	Soil	31	0.76	317	0.002	2	0.33	0.003	0.07	<0.1	2.21	8.0	0.7	<0.05	1	5.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091618	Soil	33	0.06	186	0.003	2	0.45	0.004	0.06	<0.1	0.23	1.8	0.5	<0.05	2	3.0	0.2	N.A.	N.A.	N.A.	N.A.
1091619	Soil	22	0.10	159	0.005	2	0.65	0.012	0.04	<0.1	0.13	1.4	0.2	0.09	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091620	Soil	2	0.01	21	0.006	<1	0.15	0.024	0.02	<0.1	0.03	0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091621	Soil	21	0.06	109	0.005	3	0.57	0.009	0.05	0.1	0.06	0.8	0.1	0.09	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091622	Soil	12	0.03	51	0.004	<1	0.45	0.012	0.03	<0.1	0.04	0.6	<0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091623	Soil	21	0.07	107	0.005	1	0.49	0.003	0.03	<0.1	0.04	4.6	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091624	Soil	20	0.05	61	0.007	2	0.62	0.007	0.05	<0.1	0.03	1.0	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091395	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091396	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091397	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091398	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091399	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091400	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091601	Soil	7.5	44.6	4.3	48	3.69	40.2	7.4	2.0	13	0.2	3.1	0.4	40	0.03	0.041	2	47	0.02	954	<0.001
1091602	Soil	1.7	70.6	10.4	142	9.43	134.2	5.4	2.5	35	0.2	5.2	0.3	53	0.02	0.161	4	50	0.08	726	0.004
1091603	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091604	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091605	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091606	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091607	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091608	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091609	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091610	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091611	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091612	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091613	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091614	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091615	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091616	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091617	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091618	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091619	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091620	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091621	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091622	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091623	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091624	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091395	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091396	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091397	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091398	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091399	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091400	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091601	Soil	<20	0.44	0.004	0.12	<0.1	1.54	2.6	0.3	0.16	2	20.0	<0.2
1091602	Soil	<20	1.00	0.004	0.09	<0.1	0.29	5.5	0.2	0.16	4	14.3	<0.2
1091603	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091604	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091605	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091606	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091607	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091608	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091609	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091610	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091611	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091612	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091613	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091614	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091615	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091616	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091617	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091618	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091619	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091620	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091621	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091622	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091623	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091624	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091625	Soil	7.0	38.0	19.9	114	0.2	37.2	11.2	543	4.30	15.2	3.3	0.2	14	0.3	2.3	0.4	74	0.14	0.123	7
1091626	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091627	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091628	Soil	26.7	69.1	14.0	537	1.1	103.3	4.7	102	1.74	25.7	3.0	0.7	45	8.5	6.9	0.2	282	0.67	0.109	7
1091629	Soil	49.1	110.9	15.7	1059	2.3	280.5	20.2	238	3.52	37.6	3.3	1.8	244	15.8	13.7	0.1	455	6.49	0.344	6
1091630	Soil	66.7	125.6	14.6	1172	1.7	253.9	21.3	349	3.91	50.6	3.4	1.7	141	13.8	21.8	0.1	417	4.94	0.257	12
1091631	Soil	59.6	60.3	11.8	236	0.3	158.4	7.7	211	2.11	19.4	1.6	1.8	96	2.6	3.1	0.1	75	5.94	0.077	4
1091632	Soil	84.5	62.2	14.3	251	0.3	134.0	7.4	107	2.40	31.3	3.0	1.7	39	1.9	6.4	0.1	120	0.79	0.098	4
1091633	Soil	15.0	80.5	31.0	396	1.6	95.7	11.8	272	3.36	50.0	2.9	1.7	55	4.5	7.6	0.2	91	0.45	0.191	3
1091634	Soil	53.3	72.4	22.7	940	0.7	135.5	20.0	261	3.37	43.7	2.5	3.2	65	12.6	13.4	0.2	252	1.79	0.128	8
1091635	Soil	77.2	66.2	15.3	279	0.3	181.1	10.0	172	2.94	27.3	3.0	1.5	60	3.0	6.3	0.1	82	2.06	0.095	5
1091636	Soil	95.2	61.0	23.0	348	0.1	209.5	14.1	786	4.59	32.0	2.9	1.0	21	3.1	8.6	0.2	225	0.51	0.078	7
1091637	Soil	77.7	83.3	16.5	276	0.2	203.0	9.9	204	2.45	25.2	1.7	2.4	127	2.7	4.4	0.1	54	5.24	0.077	3
1091638	Soil	58.6	49.1	15.4	272	<0.1	121.9	10.0	206	3.06	25.2	1.6	0.3	15	1.6	4.9	0.2	96	0.32	0.092	6
1091639	Soil	49.1	39.6	10.0	193	<0.1	97.6	6.6	204	2.04	17.9	1.4	0.2	8	1.2	3.0	0.1	56	0.11	0.100	3
1091771	Soil	10.1	77.3	29.5	183	0.2	88.5	23.7	1532	5.57	43.8	4.7	1.4	25	0.5	3.9	0.4	33	0.16	0.131	20
1091772	Soil	9.3	89.3	29.2	296	0.9	112.4	11.8	317	3.04	33.0	4.2	1.9	113	0.8	3.8	0.4	70	0.89	0.403	18
1091773	Soil	16.0	117.6	21.2	324	2.8	138.6	7.5	322	3.03	61.5	4.7	1.2	94	1.7	8.8	0.3	157	1.18	0.421	17
1091774	Soil	13.2	114.9	17.2	341	3.3	133.6	6.8	200	2.79	73.6	6.6	1.1	94	1.7	8.2	0.2	168	1.20	0.549	15
1091775	Soil	7.2	114.0	16.5	256	2.0	116.4	7.2	158	2.16	59.6	7.5	0.7	59	0.7	5.2	0.2	91	0.65	0.280	15
1091776	Soil	9.4	117.2	23.2	178	2.3	61.2	4.0	86	2.21	63.9	3.9	0.8	80	0.8	4.6	0.3	86	0.23	0.322	21
1091777	Soil	27.8	80.2	14.8	228	2.5	124.5	4.7	74	1.69	62.9	4.1	0.5	87	4.1	8.7	0.2	134	0.39	0.151	12
1091778	Soil	40.5	84.5	27.4	311	4.4	115.1	6.9	132	2.62	80.6	3.8	0.9	127	4.6	12.6	0.3	170	0.15	0.138	15
1091779	Soil	45.6	108.7	29.6	392	4.8	177.3	8.5	195	2.86	114.2	2.9	1.7	147	5.3	15.7	0.3	228	0.51	0.207	14
1091780	Soil	19.2	564.3	175.1	7094	2.7	282.8	36.6	752	7.30	205.9	9.2	2.9	24	37.7	35.2	0.4	91	0.57	0.297	9
1091781	Soil	10.9	317.0	70.5	2909	2.2	148.2	21.4	1086	7.16	65.6	11.3	1.8	70	28.6	9.2	0.2	86	3.94	0.410	10
1091782	Soil	8.9	270.2	53.7	1100	1.6	123.3	20.4	565	5.43	80.7	10.0	3.6	33	9.0	10.9	0.3	61	1.51	0.194	8
1091783	Soil	13.7	147.4	69.0	1187	1.4	117.7	24.7	1274	9.02	175.4	16.4	3.5	75	10.7	44.0	0.2	64	4.67	0.321	11
1091784	Soil	16.3	175.7	56.6	807	2.2	144.0	17.0	748	4.98	121.3	7.4	2.4	87	5.9	12.9	0.4	112	0.81	0.358	18
1091785	Soil	2.9	24.6	12.4	113	0.3	18.1	3.8	396	2.04	19.4	3.3	0.2	18	0.6	3.5	0.1	28	0.28	0.137	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091625	Soil	33	0.07	181	0.007	1	0.83	0.005	0.06	<0.1	0.04	0.8	0.2	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091626	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	9.2	110.9	69.9	207
1091627	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	11.4	113.5	88.8	245
1091628	Soil	32	0.06	289	0.002	1	0.66	0.003	0.05	0.1	0.39	3.3	0.9	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091629	Soil	88	3.26	407	0.004	8	0.51	0.007	0.10	0.1	0.66	7.1	0.8	<0.05	1	12.8	0.2	N.A.	N.A.	N.A.	N.A.
1091630	Soil	57	1.89	369	0.004	7	0.53	0.006	0.09	0.2	0.64	6.7	1.1	0.06	1	8.1	0.2	N.A.	N.A.	N.A.	N.A.
1091631	Soil	16	3.03	201	0.004	4	0.23	0.007	0.05	0.1	0.21	3.5	0.9	<0.05	<1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091632	Soil	18	0.20	182	0.003	2	0.29	0.002	0.05	<0.1	0.31	3.6	1.0	<0.05	<1	6.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091633	Soil	25	0.08	384	0.003	2	0.38	0.002	0.07	<0.1	0.41	4.5	0.4	<0.05	1	7.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091634	Soil	17	0.83	301	0.003	4	0.33	0.005	0.07	<0.1	0.68	5.6	0.6	<0.05	1	7.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091635	Soil	18	0.92	254	0.004	5	0.34	0.007	0.06	<0.1	0.30	4.3	1.2	<0.05	<1	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091636	Soil	26	0.13	219	0.006	2	0.34	0.003	0.05	0.1	0.15	4.6	1.5	<0.05	1	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091637	Soil	14	2.12	139	0.002	5	0.15	0.005	0.04	<0.1	0.37	3.9	1.5	0.09	<1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091638	Soil	23	0.09	156	0.002	2	0.35	0.002	0.03	0.1	0.07	1.3	0.7	<0.05	1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091639	Soil	14	0.04	99	0.002	2	0.43	0.006	0.02	0.1	0.05	0.7	0.9	0.05	1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091771	Soil	10	0.05	821	0.002	3	0.53	0.002	0.10	<0.1	0.11	2.8	0.2	0.09	2	1.8	0.3	N.A.	N.A.	N.A.	N.A.
1091772	Soil	20	0.10	1009	0.004	11	0.69	0.002	0.22	<0.1	0.34	3.2	0.2	0.07	2	2.8	0.2	N.A.	N.A.	N.A.	N.A.
1091773	Soil	31	0.99	791	0.004	6	1.08	0.004	0.15	0.2	0.80	3.1	0.6	0.22	3	7.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091774	Soil	32	0.48	676	0.004	6	0.94	0.004	0.16	0.2	1.09	2.7	0.6	0.19	3	6.6	0.3	N.A.	N.A.	N.A.	N.A.
1091775	Soil	19	0.19	446	0.002	3	0.64	0.005	0.11	0.2	0.95	1.9	0.4	0.18	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091776	Soil	19	0.08	462	0.005	5	0.58	0.004	0.16	0.2	0.60	1.7	0.6	0.36	1	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091777	Soil	17	0.04	275	0.002	4	0.33	0.003	0.14	0.4	0.70	1.4	1.3	0.20	<1	2.3	0.3	N.A.	N.A.	N.A.	N.A.
1091778	Soil	22	0.04	396	0.003	3	0.41	0.004	0.19	0.5	0.57	1.8	2.2	0.37	1	5.4	0.2	N.A.	N.A.	N.A.	N.A.
1091779	Soil	28	0.06	308	0.003	6	0.42	0.003	0.23	0.6	1.24	3.0	2.2	0.43	1	6.2	0.3	N.A.	N.A.	N.A.	N.A.
1091780	Soil	27	0.09	321	0.003	4	0.67	0.002	0.09	<0.1	4.92	7.2	0.3	0.42	3	12.9	0.3	N.A.	N.A.	N.A.	N.A.
1091781	Soil	21	1.71	651	0.004	10	0.60	0.003	0.15	<0.1	2.85	6.1	0.4	0.17	2	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091782	Soil	16	0.69	510	0.002	5	0.56	0.002	0.12	<0.1	1.05	6.8	0.4	0.18	2	2.9	0.2	N.A.	N.A.	N.A.	N.A.
1091783	Soil	14	1.99	545	0.002	6	0.48	0.003	0.10	<0.1	1.88	6.3	0.5	0.09	1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091784	Soil	23	0.15	794	0.004	7	0.67	0.003	0.20	0.1	1.33	5.1	0.5	0.17	2	5.1	0.2	N.A.	N.A.	N.A.	N.A.
1091785	Soil	7	0.06	180	0.003	3	0.69	0.019	0.05	<0.1	0.17	0.5	0.2	0.06	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091625	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091626	Soil		1.4	84.9	30.8	1046	4.21	35.9	4.7	0.7	30	0.7	3.5	0.6	47	0.21	0.105	5	49	0.12	243	0.003
1091627	Soil		1.5	101.6	34.9	1272	4.02	33.9	5.4	1.0	31	1.1	4.0	0.6	45	0.21	0.102	5	64	0.11	329	0.003
1091628	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091629	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091630	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091631	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091632	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091633	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091634	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091635	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091636	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091637	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091638	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091639	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091771	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091772	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091773	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091774	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091775	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091776	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091777	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091778	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091779	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091780	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091781	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091782	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091783	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091784	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091785	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091625	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091626	Soil	<20	0.50	0.004	0.09	<0.1	0.14	3.7	0.3	0.07	2	2.9	<0.2
1091627	Soil	<20	0.48	0.005	0.09	0.1	0.23	4.2	0.3	0.09	2	2.8	<0.2
1091628	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091629	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091630	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091631	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091632	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091633	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091634	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091635	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091636	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091637	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091638	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091639	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091771	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091772	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091773	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091774	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091775	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091776	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091777	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091778	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091779	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091780	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091781	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091782	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091783	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091784	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091785	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091786	Soil	6.7	24.9	12.2	121	0.2	22.4	4.1	470	1.27	14.1	2.0	0.2	14	0.3	2.0	0.1	37	0.04	0.101	5
1091787	Soil	11.1	125.1	20.4	299	0.1	63.8	11.9	168	3.57	24.8	3.4	0.2	10	0.4	3.9	0.2	54	0.02	0.133	6
1091788	Soil	59.4	46.9	15.6	308	0.2	91.5	7.4	360	2.62	52.1	2.0	0.2	16	0.7	15.7	0.2	193	0.02	0.137	8
1091789	Soil	23.6	55.0	37.5	146	2.7	29.5	2.7	91	2.97	58.1	3.4	<0.1	82	1.4	4.5	0.5	133	0.15	0.379	16
1091790	Soil	5.7	32.2	16.4	93	0.2	35.5	8.3	301	2.41	25.2	2.1	0.4	10	0.3	1.9	0.3	36	0.03	0.097	12
1091791	Soil	3.8	22.4	10.1	55	<0.1	20.7	6.2	337	1.49	18.6	1.5	0.4	13	<0.1	1.2	0.2	26	0.06	0.067	11
1091792	Soil	1.1	7.7	2.7	15	<0.1	5.1	1.5	64	0.49	2.3	0.7	<0.1	15	0.1	0.4	<0.1	10	0.10	0.042	2
1091793	Soil	7.3	86.6	39.7	240	1.9	84.2	42.6	1722	4.55	44.3	3.7	1.7	90	1.1	4.3	0.4	46	0.54	0.193	17
1091794	Soil	6.4	128.6	42.6	212	1.7	131.9	70.2	2046	8.95	508.6	13.8	4.3	43	0.4	9.1	0.8	29	0.37	0.156	19
1091795	Soil	5.6	190.8	40.5	309	1.9	183.3	87.6	1334	13.89	92.4	26.4	6.4	23	0.4	4.7	1.2	22	0.18	0.117	23
1091796	Soil	8.5	157.7	49.9	382	4.3	178.3	77.9	1527	12.26	51.4	25.7	5.0	43	0.5	5.3	1.1	41	0.16	0.190	19
1091797	Soil	7.8	160.6	52.0	605	4.3	186.4	56.2	990	10.08	56.9	7.6	5.4	111	1.3	5.8	0.7	35	0.32	0.254	15
1091798	Soil	22.0	96.7	28.5	221	2.2	104.9	15.2	344	4.76	48.5	2.2	4.1	142	0.7	6.4	0.3	32	1.39	0.166	13
1091799	Soil	86.8	49.2	14.4	648	0.3	159.2	10.6	188	2.44	40.9	2.1	4.7	73	4.6	13.8	0.2	171	2.44	0.082	8
1091800	Soil	76.1	60.5	13.1	595	0.6	151.3	9.7	171	2.46	37.3	1.7	4.0	25	4.2	14.6	0.1	173	0.54	0.085	14
1091801	Soil	15.1	37.7	18.2	118	1.7	23.9	2.6	38	2.22	33.2	2.8	1.2	37	0.3	5.5	0.3	204	0.01	0.068	8
1091802	Soil	17.3	42.0	18.4	150	0.8	32.9	3.0	43	2.24	34.2	2.4	0.3	36	0.3	6.2	0.3	208	0.02	0.082	8
1091803	Soil	3.1	44.3	20.1	117	2.1	46.8	8.1	154	2.93	89.5	26.8	4.0	139	0.7	3.0	0.2	26	0.31	0.099	12
1091804	Soil	1.5	17.6	9.2	82	0.6	22.8	4.7	259	1.39	42.8	9.6	0.4	69	0.6	1.4	0.1	14	1.11	0.123	9
1091805	Soil	2.4	63.5	21.2	150	1.7	56.4	12.6	329	3.45	18.7	7.3	1.0	29	0.3	1.1	0.2	25	0.11	0.087	4
1091806	Soil	2.8	50.3	14.4	102	0.4	35.7	6.3	127	2.90	20.1	3.5	0.6	18	0.2	1.3	0.2	35	0.02	0.079	4
1091807	Soil	3.9	75.2	19.5	153	2.3	54.3	9.7	194	3.44	20.0	7.9	1.5	29	0.4	1.3	0.2	26	0.02	0.069	4
1091808	Soil	3.5	67.7	22.8	107	1.6	32.0	5.5	148	3.20	26.2	4.5	0.8	25	0.1	1.4	0.2	33	0.02	0.079	3
1091809	Soil	2.4	62.0	17.7	87	1.2	21.4	7.8	418	3.17	21.8	1.8	0.5	14	0.1	0.9	0.2	31	0.03	0.079	3
1091810	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091811	Soil	3.3	83.6	24.1	112	3.1	27.0	5.6	119	3.93	39.3	5.9	0.4	22	<0.1	1.4	0.2	32	0.04	0.123	3
1091812	Soil	10.3	31.5	18.8	71	3.6	14.2	2.2	39	2.28	46.3	12.4	0.2	47	0.1	5.1	0.2	48	0.01	0.168	5
1091813	Soil	2.5	13.2	7.0	33	0.4	6.8	1.5	71	0.90	12.1	1.3	<0.1	10	<0.1	0.9	<0.1	24	0.02	0.082	2
1091814	Soil	4.9	20.1	11.2	57	0.5	13.6	2.2	34	1.07	20.2	3.0	0.2	13	0.1	1.5	0.1	60	0.01	0.058	4
1091815	Soil	12.3	20.7	9.4	86	0.5	16.3	2.2	29	1.27	21.6	1.4	<0.1	13	0.1	3.1	0.1	102	0.01	0.069	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091786	Soil	8	0.02	187	0.003	1	0.44	0.011	0.07	<0.1	0.08	0.2	0.2	0.09	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091787	Soil	10	0.03	144	0.002	4	0.45	0.004	0.09	<0.1	0.10	0.6	0.2	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091788	Soil	16	0.03	135	0.004	3	0.52	0.005	0.10	0.2	0.07	0.2	1.0	0.07	2	2.8	0.3	N.A.	N.A.	N.A.	N.A.
1091789	Soil	32	0.03	420	0.001	5	0.42	0.004	0.18	<0.1	0.21	<0.1	1.1	0.40	2	3.6	0.4	N.A.	N.A.	N.A.	N.A.
1091790	Soil	10	0.03	180	0.003	2	0.57	0.009	0.10	<0.1	0.07	0.5	0.2	0.07	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091791	Soil	9	0.07	146	0.005	4	0.55	0.020	0.07	<0.1	0.05	1.2	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091792	Soil	3	0.03	207	0.007	1	0.50	0.020	0.02	<0.1	0.04	0.3	<0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091793	Soil	18	0.17	4548	0.008	5	0.93	0.008	0.17	0.1	0.36	5.1	0.5	0.20	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091794	Soil	13	0.16	2737	0.003	3	0.94	0.004	0.15	<0.1	0.24	9.5	0.4	0.13	2	3.7	0.3	N.A.	N.A.	N.A.	N.A.
1091795	Soil	16	0.24	1621	0.003	4	1.54	0.003	0.17	<0.1	0.18	9.9	0.5	0.17	3	2.3	0.4	N.A.	N.A.	N.A.	N.A.
1091796	Soil	21	0.21	3348	0.005	3	1.87	0.005	0.17	<0.1	0.36	9.5	0.7	0.19	3	3.5	0.4	N.A.	N.A.	N.A.	N.A.
1091797	Soil	18	0.12	1968	0.003	3	1.60	0.006	0.30	<0.1	0.37	7.6	0.5	0.20	2	8.3	0.5	N.A.	N.A.	N.A.	N.A.
1091798	Soil	11	0.52	3155	0.002	4	0.56	0.003	0.15	<0.1	0.61	5.6	0.4	0.12	<1	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091799	Soil	11	0.97	1037	0.002	5	0.24	0.003	0.08	<0.1	0.40	3.4	0.8	0.07	<1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091800	Soil	9	0.15	2264	0.002	3	0.30	0.001	0.07	0.1	0.42	4.6	0.7	0.05	<1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091801	Soil	28	0.03	2065	0.003	2	0.67	0.003	0.08	0.1	0.28	1.7	0.6	0.11	4	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091802	Soil	29	0.03	1245	0.005	2	0.48	0.003	0.07	0.3	0.17	0.9	0.5	0.12	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091803	Soil	19	0.09	663	0.002	3	0.82	0.009	0.13	<0.1	0.45	4.1	0.2	0.29	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091804	Soil	13	0.03	404	0.003	3	0.82	0.013	0.04	<0.1	0.26	0.9	<0.1	0.21	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091805	Soil	21	0.11	526	0.002	2	0.84	0.006	0.06	<0.1	0.10	3.5	0.1	0.09	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091806	Soil	21	0.10	174	0.003	2	0.85	0.004	0.05	<0.1	0.06	1.4	<0.1	0.07	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091807	Soil	21	0.09	526	<0.001	2	0.75	0.003	0.06	<0.1	0.12	3.9	0.1	0.08	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091808	Soil	20	0.06	249	0.003	2	0.67	0.008	0.07	<0.1	0.12	2.7	<0.1	0.05	2	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091809	Soil	17	0.09	251	0.003	3	0.74	0.011	0.07	<0.1	0.10	1.8	0.1	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091810	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.8	102.1	46.2	110
1091811	Soil	19	0.06	349	0.002	3	0.89	0.007	0.08	<0.1	0.27	2.3	0.1	0.06	3	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091812	Soil	18	0.02	514	0.002	2	0.47	0.004	0.10	0.1	1.65	0.6	0.5	0.13	3	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091813	Soil	6	0.02	158	0.002	1	0.35	0.012	0.04	<0.1	0.15	0.1	<0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091814	Soil	11	0.02	221	0.002	3	0.37	0.006	0.04	<0.1	0.06	0.2	0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091815	Soil	10	0.02	133	0.003	2	0.37	0.005	0.05	<0.1	0.10	0.3	0.3	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091786	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091787	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091788	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091789	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091790	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091791	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091792	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091793	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091794	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091795	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091796	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091797	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091798	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091799	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091800	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091801	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091802	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091803	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091804	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091805	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091806	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091807	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091808	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091809	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091810	Soil		7.8	28.5	7.9	336	4.36	38.4	6.1	1.0	29	0.2	1.5	0.4	39	0.03	0.125	5	30	0.10	353	0.003
1091811	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091812	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091813	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091814	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091815	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091786	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091787	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091788	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091789	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091790	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091791	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091792	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091793	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091794	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091795	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091796	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091797	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091798	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091799	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091800	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091801	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091802	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091803	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091804	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091805	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091806	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091807	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091808	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091809	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091810	Soil	<20	1.10	0.007	0.08	<0.1	0.34	4.6	0.1	0.10	3	4.5	<0.2
1091811	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091812	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091813	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091814	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091815	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091816	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091817	Soil	11.7	74.3	21.4	404	0.8	78.4	26.9	714	4.86	39.7	4.0	3.3	28	4.3	3.6	0.4	64	0.12	0.108	13
1091818	Soil	11.7	24.1	10.5	125	0.2	25.0	3.9	39	1.51	27.9	0.5	0.1	11	0.3	2.7	0.1	100	0.02	0.070	7
1091819	Soil	14.3	19.8	10.6	140	0.5	27.8	2.7	32	1.23	21.8	1.7	0.2	15	0.2	3.3	0.1	125	0.01	0.069	5
1091820	Soil	12.2	17.9	14.1	108	0.7	21.9	2.6	44	1.72	25.6	3.6	0.3	23	0.3	3.2	0.2	110	0.03	0.090	9
1091821	Soil	22.7	20.7	7.8	247	0.2	26.4	1.4	19	0.81	19.4	0.7	<0.1	5	0.4	7.7	<0.1	478	0.01	0.043	7
1091822	Soil	14.4	16.9	9.1	135	0.5	30.7	2.6	26	0.98	18.4	1.0	<0.1	14	0.3	3.2	0.1	92	0.02	0.069	6
1091823	Soil	17.3	28.0	13.1	271	0.4	44.1	4.4	61	1.80	24.4	1.8	0.2	21	1.7	3.4	0.1	107	0.10	0.066	9
1091824	Soil	19.6	28.6	14.2	248	0.6	56.9	5.1	58	1.93	25.7	1.5	0.2	13	0.6	4.3	0.1	114	0.03	0.082	9
1091825	Soil	5.6	127.0	28.4	225	1.3	56.9	11.4	77	3.31	23.9	5.6	4.7	25	0.3	3.6	0.3	13	0.08	0.084	19
1091826	Soil	3.3	39.9	11.7	97	1.1	26.7	3.2	20	1.27	12.4	3.9	2.3	12	0.1	1.8	0.2	22	0.04	0.082	18
1091827	Soil	9.6	65.5	14.4	286	0.9	68.9	9.8	157	2.52	17.1	3.5	1.7	14	1.9	4.8	0.2	46	0.14	0.055	15
1091828	Soil	3.6	27.8	8.8	74	0.7	31.0	4.5	45	1.39	12.3	0.9	0.5	7	0.4	2.2	0.1	28	0.06	0.065	9
1091829	Soil	24.5	16.5	6.5	91	<0.1	41.9	2.4	25	0.79	15.8	<0.5	0.2	3	0.2	1.2	<0.1	53	0.02	0.044	9
1091830	Soil	66.2	41.4	24.6	302	0.2	141.2	9.2	233	1.91	38.7	0.9	1.2	16	1.0	4.2	<0.1	95	0.57	0.075	11
1091831	Soil	2.3	47.4	23.2	48	2.2	13.5	2.5	37	2.34	38.4	11.0	2.2	50	<0.1	1.8	0.2	28	0.02	0.056	4
1091832	Soil	2.0	56.7	15.8	92	1.7	29.2	5.2	150	2.70	107.4	56.1	1.4	47	0.2	3.0	0.2	24	0.11	0.059	3
1091833	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091834	Soil	1.1	19.4	5.1	32	0.6	10.2	2.5	85	0.79	7.3	3.7	0.1	10	<0.1	0.4	<0.1	10	0.04	0.056	2
1091835	Soil	4.1	51.8	19.4	146	2.0	48.6	12.9	259	3.05	30.5	2.3	0.9	24	0.4	1.2	0.2	25	0.06	0.112	3
1091836	Soil	2.9	49.4	18.5	203	1.2	68.0	11.5	141	3.08	16.5	3.3	2.1	59	0.8	1.5	0.2	31	0.61	0.121	5
1091837	Soil	1.4	31.6	11.2	300	0.5	82.9	6.6	132	1.99	12.1	3.9	1.1	52	2.2	1.6	0.1	35	0.91	0.189	10
1091838	Soil	1.9	48.6	17.3	259	1.1	77.9	7.8	74	2.80	18.4	6.2	2.2	103	1.1	2.6	0.2	48	1.53	0.188	6
1091839	Soil	1.6	40.1	14.3	236	0.8	69.7	7.7	75	2.60	17.7	5.0	1.6	99	1.3	2.1	0.2	41	1.77	0.178	5
1091840	Soil	1.1	36.4	11.1	212	0.8	58.8	8.3	111	2.13	14.7	3.0	1.2	134	1.3	2.1	0.2	32	3.43	0.187	5
1091841	Soil	1.6	25.0	13.3	133	1.4	34.2	4.8	124	1.81	11.3	5.9	0.7	76	1.1	1.5	0.2	37	1.49	0.149	9
1091842	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091843	Soil	1.5	29.5	12.1	176	0.9	47.5	7.4	154	1.87	12.6	4.5	1.2	71	1.1	1.7	0.2	35	0.96	0.172	7
1091844	Soil	2.3	51.8	13.9	266	1.0	74.1	10.8	216	2.94	20.6	5.6	1.3	72	1.7	2.6	0.2	38	1.06	0.218	10
1091845	Soil	5.0	11.1	13.1	45	1.1	9.1	1.5	42	0.93	9.9	1.2	<0.1	20	0.2	2.1	0.2	57	0.03	0.053	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091816	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	13.7	117.7	25.1	779
1091817	Soil	15	0.10	657	0.004	3	0.87	0.002	0.11	<0.1	0.37	4.1	0.4	0.05	2	2.3	0.2	N.A.	N.A.	N.A.	N.A.
1091818	Soil	11	0.03	139	0.002	3	0.37	0.007	0.05	0.2	0.11	0.3	0.3	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091819	Soil	11	0.02	200	0.001	3	0.33	0.007	0.05	0.1	0.16	0.2	0.3	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091820	Soil	17	0.05	239	0.005	2	0.48	0.004	0.05	0.1	0.26	0.4	0.4	0.05	4	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091821	Soil	20	0.03	100	0.003	2	0.45	0.007	0.05	0.1	0.05	0.2	0.5	<0.05	4	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091822	Soil	11	0.03	256	0.003	2	0.33	0.012	0.04	0.1	0.08	0.4	0.3	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091823	Soil	13	0.03	1139	0.002	2	0.51	0.006	0.06	0.1	0.29	0.6	0.5	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091824	Soil	13	0.03	280	0.002	<1	0.43	0.006	0.06	0.1	0.31	0.4	0.5	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091825	Soil	6	0.02	3687	0.001	5	0.27	0.001	0.06	<0.1	1.72	3.3	0.1	0.10	<1	5.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091826	Soil	7	0.02	328	<0.001	2	0.31	0.001	0.06	<0.1	0.63	0.8	<0.1	<0.05	<1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091827	Soil	10	0.03	242	0.001	2	0.34	0.002	0.07	<0.1	1.28	2.9	0.2	<0.05	<1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091828	Soil	9	0.03	187	0.002	2	0.39	0.004	0.06	<0.1	0.16	0.8	<0.1	<0.05	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091829	Soil	9	0.03	159	0.002	2	0.48	0.005	0.05	0.1	0.04	0.4	0.9	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091830	Soil	24	0.33	258	0.003	6	0.78	0.004	0.07	0.3	0.13	2.6	1.1	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091831	Soil	19	0.06	519	<0.001	4	0.59	0.008	0.15	<0.1	0.43	4.0	0.2	0.21	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091832	Soil	17	0.04	539	<0.001	4	0.64	0.006	0.11	<0.1	0.47	3.0	0.1	0.15	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091833	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.0	58.0	18.8	141
1091834	Soil	10	0.02	295	0.003	1	0.48	0.020	0.05	<0.1	0.09	0.4	<0.1	0.08	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091835	Soil	25	0.07	601	0.002	6	0.79	0.009	0.10	<0.1	0.36	4.3	0.2	0.11	2	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091836	Soil	21	0.08	1085	<0.001	4	0.68	0.008	0.12	<0.1	0.17	4.3	0.1	0.17	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091837	Soil	21	0.05	457	0.004	5	0.70	0.018	0.08	0.1	0.12	2.8	0.1	0.09	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091838	Soil	24	0.04	1061	0.002	7	0.78	0.011	0.13	0.1	0.24	3.9	0.3	0.28	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091839	Soil	22	0.04	710	0.001	3	0.62	0.007	0.11	<0.1	0.21	3.1	0.1	0.20	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091840	Soil	16	0.14	570	0.002	4	0.46	0.005	0.06	<0.1	0.17	2.6	<0.1	0.08	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091841	Soil	24	0.10	467	0.002	3	0.57	0.004	0.04	<0.1	0.34	2.0	<0.1	0.08	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091842	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.1	39.7	14.0	250
1091843	Soil	20	0.09	454	0.003	4	0.64	0.006	0.05	0.1	0.20	2.6	<0.1	0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091844	Soil	25	0.08	461	0.002	2	0.64	0.004	0.07	<0.1	0.24	3.5	<0.1	<0.05	1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091845	Soil	9	0.02	132	0.005	1	0.32	0.003	0.03	0.1	0.06	0.2	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091816	Soil	0.9	140.3	15.8	259	4.52	32.2	5.1	0.8	27	4.1	4.2	0.3	68	0.05	0.123	9	17	0.04	294	0.002
1091817	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091818	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091819	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091820	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091821	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091822	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091823	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091824	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091825	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091826	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091827	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091828	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091829	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091830	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091831	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091832	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091833	Soil	1.9	54.4	9.3	240	2.76	33.7	8.7	0.4	54	0.3	1.2	0.3	32	0.41	0.143	5	26	0.09	806	0.002
1091834	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091835	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091836	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091837	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091838	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091839	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091840	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091841	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091842	Soil	1.2	60.1	6.9	151	1.96	13.0	5.8	0.9	98	2.2	2.0	0.2	45	1.37	0.201	9	25	0.07	534	0.002
1091843	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091844	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091845	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091816	Soil	<20	0.63	0.003	0.06	<0.1	0.42	1.8	0.5	0.07	1	4.3	<0.2
1091817	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091818	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091819	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091820	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091821	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091822	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091823	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091824	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091825	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091826	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091827	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091828	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091829	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091830	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091831	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091832	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091833	Soil	<20	0.96	0.010	0.07	<0.1	0.26	1.5	0.2	0.14	3	3.2	<0.2
1091834	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091835	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091836	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091837	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091838	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091839	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091840	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091841	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091842	Soil	<20	0.68	0.006	0.07	<0.1	0.24	2.2	0.1	0.12	2	2.8	<0.2
1091843	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091844	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091845	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091846	Soil	8.3	18.5	7.7	58	0.5	11.6	1.2	20	0.69	8.8	1.1	0.2	32	0.2	5.4	0.1	106	0.02	0.035	6
1091847	Soil	7.6	25.8	17.8	97	0.6	28.3	3.1	67	1.64	22.9	0.9	0.3	30	0.3	4.8	0.2	85	0.02	0.071	4
1091848	Soil	6.1	28.4	15.9	90	0.7	28.0	2.9	57	1.62	24.3	1.1	0.2	30	0.3	5.7	0.2	80	0.03	0.065	3
1091849	Soil	0.9	4.1	3.5	11	0.9	3.2	0.5	11	0.23	2.7	<0.5	<0.1	5	<0.1	0.6	<0.1	15	0.02	0.024	5
1091850	Soil	4.4	14.8	6.3	48	0.4	17.9	1.6	31	0.89	12.2	<0.5	<0.1	11	0.2	3.4	0.1	63	0.01	0.030	3
1091851	Soil	61.6	71.4	12.4	488	0.2	194.0	14.0	266	2.63	22.5	1.4	3.5	134	4.0	5.6	0.1	96	6.45	0.167	12
1091852	Soil	22.0	62.3	39.9	824	1.7	163.7	60.1	1067	5.72	36.6	0.6	3.2	517	2.2	13.7	0.2	84	9.26	0.079	5
1091853	Soil	82.5	65.0	35.9	639	0.5	192.6	12.7	299	3.20	30.1	1.7	2.1	68	3.5	7.0	0.2	118	2.78	0.108	4
1091854	Soil	123.0	51.7	30.0	678	0.2	206.0	10.4	213	2.76	33.3	<0.5	2.5	54	4.1	11.0	0.2	196	2.05	0.066	2
1091855	Soil	64.9	67.8	27.4	1943	1.1	180.7	18.2	430	3.42	55.4	<0.5	2.3	90	17.8	15.4	0.2	280	2.17	0.107	4
1091856	Soil	84.5	64.5	25.5	919	0.9	168.3	14.0	319	3.66	44.5	2.7	1.9	45	8.9	11.2	0.2	294	0.69	0.095	4
1091857	Soil	102.1	73.8	17.3	586	0.8	244.9	17.3	199	3.76	37.0	3.3	1.1	39	2.6	8.0	0.3	181	0.34	0.115	3
1091858	Soil	69.8	100.3	24.8	313	0.8	169.8	20.7	435	3.25	26.7	4.1	1.4	74	2.3	4.4	0.2	72	3.11	0.101	3
1091859	Soil	81.5	95.6	37.6	172	0.3	190.4	10.5	204	3.27	32.9	2.2	2.2	99	1.9	5.4	0.1	56	5.05	0.043	3
1091860	Soil	80.1	69.0	10.2	299	0.3	210.1	7.9	183	1.77	26.0	<0.5	2.3	152	2.4	6.0	0.1	106	8.55	0.059	4
1091861	Soil	50.1	42.3	13.6	298	0.3	89.0	6.8	333	1.85	16.5	2.0	0.2	7	1.6	4.3	0.1	66	0.10	0.069	5
1091862	Soil	74.4	91.5	21.6	1042	0.6	253.1	13.4	705	5.25	46.9	1.1	2.8	150	6.3	17.4	0.1	339	7.18	0.133	6
1091863	Soil	123.5	126.4	25.8	1531	1.5	221.5	6.4	140	2.01	54.0	3.2	0.8	128	18.2	25.2	0.2	347	4.73	0.104	7
1091864	Soil	63.7	58.3	15.7	469	0.3	148.8	6.6	218	1.68	22.1	0.8	2.0	166	3.8	7.2	0.1	128	9.44	0.078	4
1091865	Soil	60.4	58.1	17.1	304	0.5	127.8	8.8	301	2.28	18.8	1.9	1.1	84	2.9	3.7	0.2	70	4.38	0.093	3
1091866	Soil	55.5	50.6	12.5	208	0.2	155.9	7.1	186	1.60	19.8	1.5	2.0	214	2.5	3.5	0.1	76	9.67	0.082	3
1091867	Soil	42.2	77.9	26.9	340	0.8	118.0	15.6	386	2.99	23.4	<0.5	1.9	80	3.9	4.2	0.2	68	3.84	0.074	3
1091869	Soil	68.5	70.8	24.0	514	0.9	153.4	11.8	415	2.97	25.5	1.8	1.4	56	3.5	5.3	0.2	105	2.93	0.097	3
1091870	Soil	55.5	79.7	28.5	363	0.8	167.5	21.0	601	3.31	24.8	1.4	1.3	41	3.4	4.4	0.2	98	0.65	0.163	7
1091871	Soil	32.9	34.5	11.6	176	0.2	69.0	5.8	246	1.39	10.2	1.3	0.2	19	1.3	2.2	0.1	49	0.37	0.116	3
1091872	Soil	70.4	48.7	19.6	263	0.2	90.2	8.2	169	2.59	21.4	0.6	0.1	7	0.9	3.3	0.2	86	0.02	0.094	3
1091873	Soil	83.9	62.7	34.0	265	0.4	100.1	10.7	178	3.89	42.0	1.1	0.2	16	1.1	6.7	0.3	169	0.03	0.093	2
1091874	Soil	55.2	46.9	19.5	304	0.2	78.1	9.2	215	2.87	21.5	2.5	0.1	7	0.3	4.1	0.3	99	0.02	0.093	3
1091875	Soil	32.1	40.8	20.7	170	0.1	46.1	7.8	193	2.79	21.1	0.7	0.2	11	0.2	3.3	0.3	85	0.04	0.102	4
1091876	Soil	15.6	30.7	12.8	98	0.1	24.9	5.8	156	1.82	10.8	1.9	0.1	11	<0.1	2.0	0.2	46	0.02	0.071	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091846	Soil	14	<0.01	134	0.003	2	0.16	0.003	0.03	<0.1	0.05	0.4	0.3	<0.05	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091847	Soil	12	0.02	233	0.005	4	0.29	0.003	0.04	0.2	0.09	1.1	0.2	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091848	Soil	11	0.01	146	0.002	1	0.24	0.004	0.04	<0.1	0.07	0.7	0.2	<0.05	2	2.4	0.2	N.A.	N.A.	N.A.	N.A.
1091849	Soil	4	<0.01	81	0.003	<1	0.18	0.005	0.02	<0.1	0.03	0.2	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091850	Soil	7	<0.01	98	0.003	1	0.18	0.004	0.02	<0.1	0.04	0.3	0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091851	Soil	18	3.23	174	0.003	4	0.20	0.006	0.04	0.1	0.29	4.7	0.8	<0.05	<1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091852	Soil	24	4.74	1611	0.003	4	0.20	0.013	0.04	<0.1	0.45	4.6	0.3	0.08	<1	9.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091853	Soil	19	1.27	380	0.004	3	0.25	0.006	0.05	<0.1	0.51	5.7	0.9	0.07	<1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091854	Soil	12	0.87	201	0.001	3	0.13	0.003	0.03	<0.1	0.64	4.7	0.9	<0.05	<1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091855	Soil	15	1.05	473	0.003	3	0.23	0.006	0.05	<0.1	1.87	7.0	0.6	0.07	<1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091856	Soil	20	0.22	432	0.002	2	0.34	0.004	0.05	<0.1	1.01	7.3	1.0	0.08	<1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091857	Soil	30	0.04	248	0.001	2	0.35	0.002	0.06	0.1	0.48	6.3	1.2	<0.05	<1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091858	Soil	18	1.20	270	0.001	3	0.34	0.004	0.05	<0.1	0.25	4.5	1.0	<0.05	<1	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091859	Soil	18	1.63	113	<0.001	4	0.11	0.005	0.04	0.2	0.53	3.9	2.1	<0.05	<1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091860	Soil	13	2.61	150	0.001	4	0.13	0.005	0.04	0.2	0.33	3.0	1.4	<0.05	<1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091861	Soil	14	0.05	90	0.005	<1	0.41	0.005	0.03	0.1	0.10	0.9	0.5	<0.05	1	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091862	Soil	22	1.86	223	0.002	6	0.25	0.004	0.04	0.1	0.39	5.3	1.4	<0.05	<1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091863	Soil	21	1.78	186	0.002	4	0.29	0.006	0.04	0.4	0.92	3.1	0.9	0.07	<1	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091864	Soil	14	3.47	179	0.001	4	0.13	0.006	0.04	0.1	0.27	3.2	1.0	<0.05	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091865	Soil	15	2.09	231	0.001	4	0.22	0.005	0.04	<0.1	0.41	3.9	0.7	0.06	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091866	Soil	13	2.82	225	0.001	5	0.13	0.005	0.04	0.1	0.27	3.2	0.8	<0.05	<1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091867	Soil	14	1.72	205	<0.001	3	0.18	0.004	0.05	<0.1	0.60	4.5	0.5	0.08	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091869	Soil	18	1.46	211	0.002	4	0.23	0.004	0.05	<0.1	0.55	5.2	0.8	0.07	<1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091870	Soil	30	0.12	709	0.002	3	0.32	0.003	0.06	<0.1	0.23	7.2	0.8	0.07	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091871	Soil	13	0.04	431	0.004	3	0.62	0.013	0.03	<0.1	0.09	1.2	0.5	0.06	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091872	Soil	17	0.02	156	0.002	2	0.33	0.003	0.05	<0.1	0.03	0.9	0.6	<0.05	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091873	Soil	26	0.02	596	0.002	2	0.42	0.002	0.06	<0.1	0.09	2.8	0.6	0.07	1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091874	Soil	15	0.03	98	0.002	1	0.40	0.003	0.04	0.1	0.04	0.8	0.5	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091875	Soil	17	0.03	82	0.002	1	0.46	0.002	0.05	<0.1	0.03	0.5	0.4	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091876	Soil	11	0.02	96	0.003	2	0.41	0.005	0.04	<0.1	0.02	0.4	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091846	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091847	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091848	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091849	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091850	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091851	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091852	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091853	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091854	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091855	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091856	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091857	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091858	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091859	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091860	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091861	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091862	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091863	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091864	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091865	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091866	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091867	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091869	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091870	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091871	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091872	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091873	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091874	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091875	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091876	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091846	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091847	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091848	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091849	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091850	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091851	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091852	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091853	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091854	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091855	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091856	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091857	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091858	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091859	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091860	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091861	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091862	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091863	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091864	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091865	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091866	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091867	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091869	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091870	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091871	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091872	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091873	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091874	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091875	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091876	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091877	Soil	21.1	45.9	22.6	83	0.2	42.1	9.7	248	3.46	21.2	<0.5	0.2	11	0.2	4.1	0.5	59	0.02	0.082	4
1091878	Soil	49.8	40.6	18.9	473	0.2	76.8	9.8	257	3.20	26.4	1.1	0.1	6	0.7	8.1	0.3	188	0.03	0.095	3
1091879	Soil	6.3	37.3	13.4	97	0.1	26.2	7.6	159	2.29	17.4	1.5	<0.1	8	0.1	2.0	0.3	47	0.01	0.076	5
1091901	Soil	2.7	7.5	7.5	24	0.9	7.2	1.0	15	0.46	5.0	1.5	<0.1	9	<0.1	1.3	0.1	37	0.01	0.023	6
1091902	Soil	6.6	21.3	12.0	68	0.7	43.9	4.7	115	2.30	20.1	1.1	0.2	15	0.2	5.1	0.2	137	0.01	0.047	6
1091903	Soil	2.1	10.3	6.5	14	1.0	5.0	0.6	10	0.38	4.3	1.1	<0.1	19	<0.1	1.0	<0.1	23	0.02	0.044	4
1091904	Soil	11.7	47.9	17.4	80	2.1	27.5	2.4	58	2.25	37.2	4.5	0.1	103	0.5	7.0	0.3	117	0.04	0.155	4
1091905	Soil	5.8	10.7	6.6	43	0.5	8.4	1.2	15	0.72	8.3	<0.5	<0.1	12	<0.1	1.9	<0.1	58	0.05	0.039	5
1091906	Soil	49.6	26.4	58.1	91	2.3	20.3	1.9	35	2.74	45.0	5.1	0.2	41	0.2	16.2	0.6	178	0.06	0.130	4
1091907	Soil	7.3	16.5	12.9	56	0.4	12.3	2.3	45	1.34	13.0	1.1	0.1	16	<0.1	2.5	0.3	88	0.01	0.045	7
1091908	Soil	4.9	52.1	18.0	148	1.9	40.8	6.1	116	3.24	55.2	14.7	0.7	27	0.4	2.5	0.3	33	0.09	0.119	4
1091909	Soil	8.0	19.1	20.6	66	1.0	17.5	2.7	46	2.11	28.0	1.6	0.1	30	0.1	3.0	0.3	73	0.01	0.104	6
1091910	Soil	10.2	21.0	6.9	71	0.8	16.1	2.2	40	1.93	40.0	14.0	<0.1	5	<0.1	5.4	0.2	139	0.01	0.060	4
1091911	Soil	3.3	8.1	8.0	28	1.9	6.9	1.1	20	0.65	9.6	1.9	<0.1	7	<0.1	1.4	0.1	35	0.02	0.035	3
1091912	Soil	5.9	15.2	12.1	48	0.4	12.1	2.6	42	1.46	11.2	2.5	<0.1	16	0.1	1.4	0.2	48	0.02	0.063	4
1091913	Soil	2.6	36.9	12.4	93	0.9	25.6	5.6	62	2.52	22.2	12.8	<0.1	7	<0.1	1.4	0.2	37	0.02	0.067	<1
1091914	Soil	4.5	160.2	50.7	274	2.8	86.3	28.2	387	8.88	58.4	25.1	1.3	29	0.3	2.6	0.5	48	0.05	0.173	2
1091915	Soil	4.6	24.1	9.7	97	1.7	18.7	3.5	30	1.86	27.5	2.9	0.2	5	0.1	1.8	0.2	78	0.01	0.051	4
1091916	Soil	8.7	33.0	18.2	115	0.9	34.9	3.3	33	2.64	48.6	7.8	0.4	25	0.1	4.3	0.2	48	<0.01	0.071	2
1091917	Soil	1.5	5.7	3.6	15	0.3	3.8	0.6	9	0.33	7.1	1.3	<0.1	5	<0.1	0.3	<0.1	17	<0.01	0.043	2
1091918	Soil	7.2	41.1	17.1	131	1.3	42.5	5.0	56	2.82	63.1	18.5	0.7	29	0.2	3.4	0.2	39	0.01	0.081	2
1091919	Soil	5.2	18.6	8.9	79	0.2	20.4	2.8	29	1.42	29.6	4.1	0.2	12	<0.1	1.9	0.2	44	<0.01	0.041	3
1091920	Soil	6.9	43.8	16.4	142	0.6	43.7	6.7	150	3.22	51.2	11.9	0.6	36	0.2	3.1	0.2	40	0.02	0.084	4
1091921	Soil	8.5	53.7	13.9	146	1.2	45.1	4.6	45	2.81	49.4	11.8	1.1	29	0.3	3.4	0.2	33	0.02	0.070	4
1091922	Soil	5.7	48.2	17.6	168	0.6	54.9	7.2	57	3.86	164.9	67.5	1.3	24	0.3	4.7	0.3	41	0.01	0.065	2
1091923	Soil	4.7	43.5	17.5	138	0.6	42.0	7.7	77	3.28	77.6	25.5	1.7	26	0.3	3.3	0.3	31	0.03	0.050	3
1091924	Soil	3.8	35.1	19.7	119	0.2	32.1	6.3	69	3.39	98.9	22.2	1.0	15	<0.1	3.8	0.3	43	0.01	0.055	2
1091925	Soil	3.6	17.7	20.5	77	0.5	17.9	4.7	146	2.73	19.5	2.4	0.4	14	0.2	1.7	0.4	65	0.04	0.050	9
1091926	Soil	2.8	13.0	6.0	46	0.1	10.8	2.3	49	1.23	8.3	3.4	0.1	6	<0.1	0.8	0.2	44	0.01	0.032	10
1091927	Soil	4.7	27.2	19.3	93	0.3	27.4	4.0	91	2.47	33.5	9.1	0.2	25	0.2	1.7	0.3	41	0.03	0.078	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091877	Soil	15	0.03	81	0.003	1	0.34	0.002	0.04	0.2	0.03	0.8	0.3	0.07	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091878	Soil	16	0.02	62	0.002	2	0.37	0.002	0.04	<0.1	0.06	0.7	0.4	<0.05	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091879	Soil	12	0.02	56	0.002	3	0.31	0.001	0.05	<0.1	0.03	0.2	0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091901	Soil	7	<0.01	100	0.003	<1	0.22	0.003	0.02	<0.1	0.04	0.2	0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091902	Soil	19	0.02	131	0.005	2	0.25	0.003	0.03	0.2	0.06	0.4	0.2	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091903	Soil	5	<0.01	179	0.003	1	0.25	0.007	0.03	<0.1	0.09	0.3	0.2	0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091904	Soil	18	0.02	997	0.002	3	0.33	0.005	0.09	0.1	0.36	0.4	0.7	0.22	2	5.0	0.2	N.A.	N.A.	N.A.	N.A.
1091905	Soil	7	0.01	284	0.002	1	0.19	0.006	0.03	<0.1	0.03	0.1	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091906	Soil	20	0.03	1827	0.005	3	0.40	0.004	0.08	0.4	0.71	0.6	1.3	0.26	3	5.9	0.3	N.A.	N.A.	N.A.	N.A.
1091907	Soil	14	0.02	222	0.007	1	0.48	0.005	0.04	0.1	0.03	0.3	0.3	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091908	Soil	19	0.05	679	0.001	2	0.69	0.004	0.05	<0.1	0.50	2.4	0.1	0.07	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091909	Soil	16	0.02	289	0.005	2	0.47	0.004	0.05	0.1	0.09	0.2	0.3	0.09	4	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091910	Soil	12	0.01	184	0.003	3	0.31	0.004	0.03	0.2	0.16	0.3	0.1	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091911	Soil	12	<0.01	131	0.003	2	0.14	0.009	0.03	0.2	0.44	0.2	<0.1	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091912	Soil	10	0.02	1484	0.002	2	0.29	0.008	0.04	0.1	0.05	0.1	0.1	0.08	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091913	Soil	10	0.02	111	0.003	2	0.22	0.010	0.03	<0.1	0.04	0.7	<0.1	<0.05	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091914	Soil	14	0.05	1029	0.002	2	0.71	0.004	0.08	<0.1	0.24	5.9	0.2	0.15	2	4.9	0.3	N.A.	N.A.	N.A.	N.A.
1091915	Soil	12	0.01	145	0.002	3	0.37	0.004	0.04	0.1	0.09	0.6	<0.1	<0.05	2	2.0	0.2	N.A.	N.A.	N.A.	N.A.
1091916	Soil	13	0.01	241	0.002	1	0.40	0.003	0.04	<0.1	0.10	1.0	0.1	0.06	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091917	Soil	7	0.01	117	0.003	2	0.35	0.008	0.02	<0.1	0.04	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091918	Soil	18	0.02	230	0.001	2	0.49	0.004	0.05	<0.1	0.21	1.6	0.1	0.06	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091919	Soil	11	0.01	146	0.002	2	0.34	0.003	0.03	<0.1	0.05	0.5	0.1	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091920	Soil	21	0.06	258	0.002	1	0.61	0.003	0.05	0.1	0.15	1.4	0.1	0.07	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091921	Soil	16	0.02	293	0.001	3	0.49	0.003	0.05	<0.1	0.22	1.9	0.1	0.07	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091922	Soil	18	0.02	324	<0.001	2	0.62	0.003	0.06	<0.1	0.15	2.3	0.1	0.06	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091923	Soil	18	0.05	547	<0.001	1	0.71	0.003	0.05	<0.1	0.20	2.9	0.1	0.06	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091924	Soil	13	0.02	137	0.001	1	0.45	0.002	0.04	<0.1	0.05	1.7	<0.1	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091925	Soil	21	0.19	140	0.019	1	1.09	0.004	0.04	0.2	0.08	0.9	0.2	0.05	7	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091926	Soil	9	0.02	108	0.006	1	0.41	0.005	0.03	0.1	0.03	0.3	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091927	Soil	19	0.04	299	0.003	2	0.71	0.009	0.05	0.1	0.05	0.5	0.2	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091877	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091878	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091879	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091901	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091902	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091903	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091904	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091905	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091906	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091907	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091908	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091909	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091910	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091911	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091912	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091913	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091914	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091915	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091916	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091917	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091918	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091919	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091920	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091921	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091922	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091923	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091924	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091925	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091926	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091927	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091877	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091878	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091879	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091901	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091902	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091903	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091904	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091905	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091906	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091907	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091908	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091909	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091910	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091911	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091912	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091913	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091914	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091915	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091916	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091917	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091918	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091919	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091920	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091921	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091922	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091923	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091924	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091925	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091926	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091927	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091928	Soil		3.7	22.9	18.4	87	0.3	20.5	5.2	215	3.44	21.3	3.0	0.3	18	0.2	1.5	0.3	53	0.06	0.073	8
1091929	Soil		3.6	27.6	16.2	114	0.4	30.0	5.7	138	2.63	22.0	3.3	0.5	33	0.2	1.4	0.3	35	0.13	0.075	6
1091930	Soil		4.6	25.2	21.5	87	0.4	20.4	4.5	155	2.94	24.6	1.6	0.2	16	0.1	1.6	0.4	50	0.03	0.071	6
1091931	Soil		43.0	90.8	36.6	563	12.9	147.6	7.6	148	6.39	37.4	7.1	1.1	205	5.3	6.5	0.3	77	0.06	0.226	8
1091932	Soil		4.3	112.8	23.6	205	4.4	48.8	6.2	66	7.78	31.0	7.2	2.5	15	0.2	2.0	0.4	55	<0.01	0.093	2
1091933	Soil		4.2	60.8	37.3	134	2.9	34.3	8.3	215	3.65	35.1	6.7	1.3	23	0.2	1.4	0.4	35	0.03	0.075	3
1091934	Soil		3.3	108.8	45.0	204	1.8	51.9	7.3	139	4.99	59.8	4.2	1.7	26	0.1	2.3	0.5	62	0.03	0.090	4
1091935	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091936	Soil		1.8	58.1	23.9	105	1.1	23.6	4.4	172	3.53	171.0	3.8	0.5	39	0.2	1.4	0.4	37	0.05	0.162	3
1091937	Soil		2.6	208.3	28.2	177	1.4	36.4	6.2	132	8.33	223.0	16.6	2.3	219	0.1	3.5	0.6	128	0.04	0.284	6
1091938	Soil		2.3	58.6	16.3	136	0.5	29.4	6.3	112	3.63	77.9	3.6	0.2	34	<0.1	1.7	0.3	55	0.01	0.082	5
1091939	Soil		5.2	80.8	25.0	105	0.8	23.5	4.5	126	3.93	54.8	11.0	0.6	38	<0.1	2.1	0.4	40	0.02	0.105	4
1091940	Soil		2.8	38.6	17.8	91	0.3	18.2	3.4	74	2.44	42.4	3.5	0.1	28	<0.1	1.9	0.3	47	0.02	0.098	4
1091941	Soil		2.8	28.0	12.5	69	0.4	15.1	3.3	80	2.20	31.6	8.6	0.2	21	0.1	1.7	0.2	31	0.02	0.074	5
1091942	Soil		13.8	18.8	44.5	3	1.0	2.5	0.2	7	0.62	14.0	2.7	1.6	29	<0.1	6.7	0.2	51	<0.01	0.032	7
1091943	Soil		0.5	4.8	1.7	7	0.3	2.0	0.4	11	0.18	0.5	0.6	<0.1	6	<0.1	0.1	<0.1	6	0.03	0.039	<1
1091944	Soil		5.0	10.4	11.2	23	0.3	5.7	1.3	48	1.01	19.0	2.0	<0.1	17	<0.1	1.5	0.1	37	0.02	0.058	4
1091945	Soil		6.1	31.6	12.5	82	0.1	17.9	3.8	68	1.62	17.9	<0.5	<0.1	10	0.1	2.1	0.2	58	0.02	0.075	9
1091946	Soil		111.2	50.5	49.6	91	1.7	19.4	1.8	108	2.66	108.2	2.9	0.9	22	0.3	26.2	0.3	415	0.03	0.300	7
1091947	Soil		52.2	26.5	20.7	57	0.4	8.6	0.9	12	1.13	20.4	0.6	<0.1	7	0.2	8.3	0.2	188	<0.01	0.079	4
1091948	Soil		45.2	32.7	7.5	500	0.5	124.5	5.3	33	2.00	29.6	0.8	0.1	4	1.1	5.4	0.1	169	0.01	0.054	6
1091949	Soil		22.8	17.1	6.3	169	0.3	34.2	3.1	30	1.20	11.8	<0.5	<0.1	6	0.2	4.0	0.1	107	<0.01	0.049	8
1091950	Soil		12.0	26.6	17.2	72	0.6	13.4	2.1	89	2.20	37.6	3.3	<0.1	13	0.1	9.5	0.4	86	0.01	0.097	3
1091951	Soil		11.0	42.1	38.7	312	2.0	114.8	4.9	418	1.83	23.7	6.1	0.7	59	4.3	3.2	0.3	82	0.42	0.165	4
1091952	Soil		38.4	50.9	16.8	1084	1.1	290.2	14.1	1788	10.70	65.4	3.2	0.8	38	9.6	10.2	0.2	145	0.44	0.180	4
1091953	Soil		42.3	15.5	9.8	160	0.8	25.9	2.0	19	1.43	29.7	6.3	0.1	10	0.2	11.2	0.1	227	0.01	0.058	8
1091954	Soil		21.2	35.9	13.7	240	1.1	52.1	3.9	89	1.57	20.0	2.5	0.6	35	5.3	4.9	0.2	121	0.15	0.130	7
1091955	Soil		34.5	62.3	12.6	925	1.0	141.1	6.5	98	2.65	32.3	3.8	2.5	50	9.1	10.4	0.2	115	0.46	0.134	11
1091956	Soil		12.7	41.8	8.7	1233	1.1	282.2	3.0	80	1.37	19.9	1.8	0.3	38	34.5	4.1	0.1	116	0.45	0.089	7
1091957	Soil		27.0	30.5	15.8	251	0.5	47.0	2.7	28	1.29	21.2	1.7	0.4	24	1.0	6.7	0.1	277	0.02	0.072	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091928	Soil	26	0.14	326	0.011	1	0.94	0.005	0.06	0.2	0.05	0.7	0.1	0.06	5	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091929	Soil	17	0.09	307	0.004	2	0.70	0.004	0.05	0.1	0.07	1.0	0.1	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091930	Soil	20	0.08	156	0.009	1	0.65	0.004	0.05	0.1	0.05	0.6	0.1	0.08	4	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091931	Soil	47	0.02	884	0.001	4	0.43	0.007	0.13	<0.1	0.76	5.0	0.4	0.27	2	13.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091932	Soil	36	0.03	388	0.002	3	0.72	0.006	0.06	<0.1	0.22	7.3	0.2	0.06	4	12.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091933	Soil	23	0.10	317	0.003	4	0.72	0.011	0.08	<0.1	0.21	4.2	0.1	0.06	3	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091934	Soil	27	0.17	289	0.003	2	1.16	0.004	0.07	<0.1	0.11	3.0	0.1	0.08	4	3.6	0.3	N.A.	N.A.	N.A.	N.A.
1091935	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.1	102.3	48.5	184
1091936	Soil	13	0.02	480	0.002	3	0.51	0.005	0.13	<0.1	0.13	1.4	0.1	0.12	2	2.7	0.2	N.A.	N.A.	N.A.	N.A.
1091937	Soil	66	0.04	570	0.003	3	1.13	0.003	0.12	<0.1	0.36	10.5	0.2	0.13	4	6.2	0.3	N.A.	N.A.	N.A.	N.A.
1091938	Soil	11	0.02	317	0.004	2	0.49	0.006	0.08	<0.1	0.14	0.7	<0.1	0.07	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091939	Soil	17	0.06	724	0.004	3	0.67	0.005	0.11	0.1	0.11	2.2	0.2	0.13	3	2.5	0.3	N.A.	N.A.	N.A.	N.A.
1091940	Soil	11	0.02	345	0.002	2	0.47	0.004	0.07	<0.1	0.09	0.4	0.1	0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091941	Soil	11	0.06	275	0.003	2	0.60	0.007	0.05	<0.1	0.42	0.4	0.1	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091942	Soil	11	<0.01	464	0.001	3	0.20	0.002	0.11	0.1	0.42	1.2	0.7	0.14	2	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091943	Soil	3	<0.01	48	0.003	<1	0.16	0.019	0.02	<0.1	0.04	0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091944	Soil	8	0.02	134	0.004	<1	0.49	0.013	0.06	<0.1	0.06	<0.1	0.2	0.06	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091945	Soil	13	0.02	118	0.003	3	0.42	0.005	0.06	<0.1	0.03	0.1	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091946	Soil	31	0.04	560	0.004	3	1.40	0.005	0.11	0.4	0.22	1.1	1.9	0.06	4	18.0	0.3	N.A.	N.A.	N.A.	N.A.
1091947	Soil	14	0.02	269	0.002	4	0.36	0.007	0.06	0.2	0.04	0.2	0.5	<0.05	2	7.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091948	Soil	12	0.03	101	0.004	2	0.56	0.008	0.04	0.2	0.06	0.2	0.6	<0.05	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091949	Soil	6	0.01	78	0.005	2	0.26	0.008	0.04	0.1	0.04	<0.1	0.4	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091950	Soil	9	0.02	578	0.002	2	0.46	0.006	0.05	0.2	0.11	0.3	0.2	<0.05	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091951	Soil	16	0.06	718	0.003	4	0.98	0.011	0.09	<0.1	0.77	1.7	1.4	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091952	Soil	14	0.04	485	0.004	2	0.58	0.004	0.06	0.2	0.72	1.9	1.3	0.06	2	5.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091953	Soil	11	0.02	199	0.003	2	0.31	0.004	0.06	0.3	1.75	0.3	1.2	<0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091954	Soil	17	0.06	903	0.004	3	0.77	0.005	0.08	0.2	0.63	1.3	1.8	0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091955	Soil	14	0.04	1825	0.003	4	0.53	0.003	0.08	0.2	1.00	2.9	1.0	<0.05	1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091956	Soil	12	0.05	458	0.003	5	0.48	0.012	0.06	0.1	1.28	1.1	1.6	<0.05	1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091957	Soil	17	0.04	235	0.001	5	0.65	0.002	0.07	0.2	0.30	0.6	0.7	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091928	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091929	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091930	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091931	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091932	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091933	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091934	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091935	Soil		3.7	53.3	12.6	416	5.54	68.5	11.1	2.4	35	0.2	1.1	0.4	46	0.04	0.096	3	29	0.13	634	0.001
1091936	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091937	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091938	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091939	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091940	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091941	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091942	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091943	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091944	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091945	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091946	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091947	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091948	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091949	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091950	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091951	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091952	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091953	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091954	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091955	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091956	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091957	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091928	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091929	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091930	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091931	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091932	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091933	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091934	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091935	Soil	<20	1.04	0.005	0.11	<0.1	0.19	5.4	0.2	0.12	3	3.9	0.2
1091936	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091937	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091938	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091939	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091940	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091941	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091942	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091943	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091944	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091945	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091946	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091947	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091948	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091949	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091950	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091951	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091952	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091953	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091954	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091955	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091956	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091957	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091958	Soil	33.4	110.9	19.6	1942	1.7	286.9	7.9	225	2.94	41.0	6.9	1.6	52	39.4	14.5	0.2	320	0.47	0.174	16
1091959	Soil	10.1	21.3	11.8	218	0.9	32.3	2.3	48	1.20	15.3	2.5	0.4	29	2.7	2.5	0.1	113	0.17	0.100	9
1091960	Soil	19.9	35.2	9.7	319	0.7	54.2	2.5	36	1.91	28.8	3.2	0.3	21	2.0	6.4	0.1	165	0.12	0.104	8
1091961	Soil	22.6	46.2	11.2	581	0.6	104.3	6.0	98	1.59	18.8	0.6	1.2	55	3.6	4.4	0.1	126	0.92	0.126	10
1091962	Soil	161.7	69.1	7.0	1200	0.5	354.0	56.1	2932	8.81	48.4	2.4	2.1	60	16.3	9.4	<0.1	228	0.82	0.156	22
1091963	Soil	168.4	186.9	16.4	467	0.5	371.2	26.1	170	3.17	55.5	0.5	2.8	134	5.1	6.9	0.2	46	3.90	0.111	5
1091964	Soil	27.0	34.4	12.8	156	0.5	60.4	5.0	77	2.21	19.7	2.4	0.8	17	1.4	2.8	0.1	76	0.11	0.091	10
1091965	Soil	7.2	16.9	7.6	101	0.5	23.8	3.1	119	1.11	8.4	1.3	0.5	39	1.7	1.2	0.1	71	0.45	0.109	7
1091966	Soil	9.5	26.2	18.8	123	0.2	27.5	4.8	80	2.37	23.2	1.1	0.6	15	0.3	2.4	0.3	90	0.02	0.097	11
1091967	Soil	9.9	28.8	13.5	147	0.2	36.0	5.0	64	2.30	21.4	1.3	0.3	13	0.5	3.2	0.2	110	0.03	0.075	9
1091968	Soil	12.2	30.3	11.0	153	0.3	32.7	3.6	41	1.69	18.9	<0.5	0.5	13	0.5	3.9	0.1	89	0.02	0.065	10
1091969	Soil	10.2	35.3	12.8	219	1.9	43.2	6.0	191	2.46	21.8	4.4	0.6	35	1.3	3.4	0.2	138	0.21	0.118	7
1091970	Soil	55.5	66.5	10.5	826	0.5	171.1	10.4	194	2.15	34.9	1.4	2.5	54	9.6	10.2	0.1	278	0.50	0.165	19
1091971	Soil	53.1	114.0	22.9	983	0.8	163.6	13.3	303	3.03	52.1	2.0	4.1	31	10.8	20.2	0.2	249	0.34	0.224	9
1091972	Soil	19.9	74.9	16.9	301	<0.1	93.1	21.1	446	6.13	28.1	2.5	2.5	19	1.4	4.6	0.2	136	0.17	0.236	23
1091973	Soil	15.7	21.1	15.4	139	0.1	38.3	6.4	88	1.91	18.5	1.5	0.1	10	0.3	3.1	0.2	139	0.02	0.082	9
1091974	Soil	36.7	37.0	11.2	937	0.3	93.8	7.4	653	2.16	24.0	1.8	0.4	39	6.7	7.6	0.2	260	0.38	0.188	10
1091975	Soil	25.6	26.5	10.3	235	0.7	62.9	6.6	65	1.76	21.2	1.0	0.3	6	0.3	5.7	0.2	233	0.02	0.039	13
1091976	Soil	22.1	19.4	12.3	149	0.2	41.6	3.7	34	1.18	15.5	0.7	0.3	15	0.4	3.8	0.1	181	0.02	0.073	14
1091977	Soil	25.4	25.4	9.2	201	0.2	72.8	7.5	61	1.70	20.3	1.1	0.4	5	0.2	4.9	0.2	185	0.01	0.051	14
1091978	Soil	24.8	19.0	19.6	169	0.1	41.7	4.5	124	2.37	26.8	1.0	0.4	15	0.3	4.2	0.3	201	0.04	0.083	12
1091979	Soil	19.3	21.9	10.1	134	0.2	37.7	4.3	58	1.47	13.6	1.0	0.1	7	0.2	2.7	0.2	116	0.02	0.079	10
1091980	Soil	19.7	41.1	21.6	313	0.4	73.2	9.1	165	2.62	30.8	3.1	0.7	38	2.0	5.8	0.2	117	0.13	0.088	9
1091981	Soil	13.1	117.9	10.9	227	0.3	515.0	149.6	1383	11.09	36.6	1.9	4.4	95	1.4	2.6	<0.1	184	1.58	0.262	45
1091982	Soil	17.0	89.0	11.6	409	0.7	359.2	76.4	1062	9.67	25.3	0.9	4.0	540	4.2	7.6	<0.1	194	3.56	0.202	20
1091983	Soil	68.8	158.5	16.5	2062	3.0	422.5	50.9	798	6.86	66.8	0.8	4.8	299	25.2	27.0	0.2	839	4.95	0.324	37
1091984	Soil	66.8	89.0	13.0	310	0.4	178.6	10.2	271	2.49	32.7	<0.5	2.9	244	4.6	6.7	0.1	186	9.26	0.070	10
1091985	Soil	94.4	67.6	11.2	173	0.2	176.0	10.3	124	2.10	33.6	<0.5	4.2	85	0.8	4.1	0.1	48	3.76	0.083	10
1091986	Soil	79.5	65.1	11.9	208	0.2	187.9	8.3	161	2.08	30.4	0.7	3.4	144	1.8	4.6	0.1	60	5.79	0.095	6
1091987	Soil	56.7	70.2	19.8	146	0.3	168.1	7.7	352	3.30	26.7	0.8	3.0	209	1.6	6.6	0.1	87	8.60	0.090	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091958	Soil	23	0.09	861	0.005	8	0.69	0.003	0.12	0.2	1.53	3.4	2.1	<0.05	2	6.9	0.2	N.A.	N.A.	N.A.	N.A.
1091959	Soil	13	0.06	971	0.002	2	0.67	0.006	0.05	<0.1	0.40	0.8	0.7	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091960	Soil	13	0.04	984	0.002	3	0.41	0.003	0.06	0.1	0.33	0.6	0.6	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091961	Soil	18	0.14	765	0.003	4	0.52	0.006	0.07	0.1	1.05	2.3	0.7	0.06	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091962	Soil	48	0.17	1750	0.011	7	0.70	0.006	0.08	0.2	0.42	7.4	0.6	<0.05	2	3.5	0.2	N.A.	N.A.	N.A.	N.A.
1091963	Soil	10	0.55	333	0.002	5	0.24	0.002	0.09	0.6	0.85	2.9	1.9	0.53	<1	6.9	0.3	N.A.	N.A.	N.A.	N.A.
1091964	Soil	13	0.04	492	0.003	2	0.62	0.004	0.05	0.1	0.26	1.4	0.5	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091965	Soil	15	0.09	838	0.003	3	0.74	0.010	0.06	<0.1	0.20	1.1	0.5	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091966	Soil	14	0.04	249	0.005	3	0.67	0.004	0.07	<0.1	0.04	0.2	0.3	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091967	Soil	16	0.05	598	0.004	5	0.72	0.003	0.06	0.1	0.14	0.7	0.3	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091968	Soil	9	0.02	496	0.002	3	0.36	0.002	0.06	0.1	0.15	0.7	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091969	Soil	25	0.10	2453	0.002	4	0.81	0.007	0.11	<0.1	0.97	2.2	0.5	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091970	Soil	32	0.11	1243	0.004	5	0.57	0.003	0.08	0.2	0.41	3.9	1.0	<0.05	1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091971	Soil	18	0.03	710	0.002	3	0.33	0.002	0.07	0.1	0.86	5.1	0.4	<0.05	<1	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091972	Soil	24	0.06	1349	0.005	2	0.68	0.003	0.05	0.1	0.11	4.6	0.3	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091973	Soil	17	0.04	165	0.002	2	0.55	0.004	0.05	0.1	0.05	0.2	0.3	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091974	Soil	27	0.14	962	0.004	4	0.87	0.007	0.08	0.2	0.22	0.8	1.1	0.08	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091975	Soil	16	0.04	102	0.004	2	0.40	0.004	0.05	0.1	0.03	0.5	0.5	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091976	Soil	17	0.04	233	0.002	3	0.48	0.002	0.07	0.1	0.06	0.5	0.5	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091977	Soil	19	0.03	136	0.003	4	0.35	0.004	0.06	0.1	0.04	0.7	0.4	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091978	Soil	20	0.08	126	0.010	2	0.65	0.004	0.07	0.2	0.04	0.7	0.4	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091979	Soil	14	0.04	132	0.002	2	0.47	0.005	0.05	<0.1	0.04	0.2	0.4	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091980	Soil	18	0.09	359	0.003	1	0.55	0.005	0.07	0.1	0.07	1.3	0.5	0.06	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091981	Soil	199	0.91	152	0.004	6	1.55	0.007	0.16	<0.1	0.07	19.3	0.4	0.73	6	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091982	Soil	84	1.72	184	0.004	10	0.87	0.012	0.19	<0.1	0.08	14.7	0.6	0.60	2	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091983	Soil	104	1.70	332	0.011	17	0.83	0.005	0.21	0.2	0.55	10.3	2.7	0.49	3	15.7	0.3	N.A.	N.A.	N.A.	N.A.
1091984	Soil	23	3.70	455	0.004	8	0.43	0.007	0.12	0.1	0.18	3.6	2.9	0.10	1	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091985	Soil	11	1.48	243	0.002	8	0.23	0.003	0.07	0.2	0.19	3.0	0.8	<0.05	<1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091986	Soil	12	2.25	296	0.002	5	0.21	0.004	0.07	0.2	0.39	3.4	1.3	0.06	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091987	Soil	17	4.88	252	0.002	6	0.25	0.008	0.08	0.1	0.41	4.0	1.6	0.07	<1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091958	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091959	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091960	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091961	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091962	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091963	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091964	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091965	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091966	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091967	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091968	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091969	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091970	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091971	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091972	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091973	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091974	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091975	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091976	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091977	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091978	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091979	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091980	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091981	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091982	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091983	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091984	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091985	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091986	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091987	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091958	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091959	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091960	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091961	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091962	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091963	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091964	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091965	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091966	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091967	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091968	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091969	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091970	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091971	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091972	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091973	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091974	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091975	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091976	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091977	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091978	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091979	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091980	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091981	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091982	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091983	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091984	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091985	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091986	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091987	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091988	Soil	63.2	189.7	15.4	1431	2.9	301.0	5.1	122	1.78	103.0	5.1	1.8	134	25.7	30.8	0.2	783	4.86	0.376	18
1091989	Soil	69.2	172.0	22.2	1017	2.8	218.9	4.4	86	1.74	81.1	3.6	1.4	82	13.8	24.1	0.2	1219	1.64	0.202	14
1091990	Soil	34.8	56.6	12.9	842	1.3	112.8	4.2	153	2.13	48.0	3.8	1.2	43	8.1	14.1	0.2	391	0.78	0.131	12
1091991	Soil	55.0	45.7	13.1	341	1.1	70.6	4.9	151	1.78	40.0	1.2	0.3	17	1.6	18.4	0.2	498	0.06	0.101	15
1091992	Soil	30.7	34.6	17.9	376	0.4	62.7	9.8	371	2.73	43.8	1.8	0.4	18	1.0	9.6	0.3	399	0.10	0.101	16
1091993	Soil	9.8	239.6	58.7	510	0.8	40.1	11.3	666	4.81	20.1	9.2	0.7	12	0.8	3.5	0.5	32	0.16	0.308	7
1091994	Soil	15.9	137.6	64.4	328	1.2	52.5	8.0	115	3.23	24.1	8.0	0.2	59	0.5	6.4	0.4	79	0.14	0.222	9
1091995	Soil	5.6	75.6	17.0	104	0.2	47.1	16.6	668	4.54	29.9	2.4	0.7	8	0.2	2.5	0.4	33	0.03	0.113	33
1091996	Soil	4.5	39.1	12.7	90	0.2	45.1	25.1	1657	4.27	13.4	2.9	2.7	35	0.5	1.5	0.6	32	0.75	0.123	12
1091997	Soil	7.5	85.7	33.3	156	1.9	60.0	16.5	339	4.19	12.3	5.5	6.4	81	0.3	2.0	0.4	15	0.35	0.113	16
1091998	Soil	10.9	106.5	25.4	304	1.7	89.4	17.7	256	5.03	23.0	3.2	5.6	49	0.9	3.3	0.4	40	0.38	0.154	21
1091999	Soil	109.8	168.2	42.7	2713	2.7	383.1	9.4	282	2.13	111.6	2.1	4.0	183	26.2	42.8	0.2	800	4.41	0.179	12
1092000	Soil	120.3	262.2	38.1	3550	4.4	381.5	9.9	286	2.49	125.6	3.7	2.1	113	47.2	50.0	0.3	1244	1.52	0.182	19
1092101	Soil	53.0	68.4	28.3	651	0.8	134.1	12.5	279	2.39	76.0	1.7	1.1	98	9.0	15.0	0.5	291	0.37	0.172	11
1092102	Soil	4.2	11.5	6.5	44	<0.1	9.8	2.2	56	1.16	7.9	0.7	0.2	5	0.1	1.0	0.2	36	0.02	0.069	3
1092103	Soil	53.7	56.5	26.3	474	0.7	132.5	10.5	220	2.69	91.8	2.5	1.5	70	4.5	11.9	0.4	156	0.44	0.111	10
1092104	Soil	4.9	21.7	11.2	96	0.3	22.2	4.4	106	1.48	11.2	1.4	0.2	19	0.5	1.4	0.2	44	0.08	0.090	10
1092105	Soil	4.9	29.9	14.3	134	0.3	33.3	6.3	80	2.03	9.2	1.8	<0.1	20	0.2	1.6	0.2	28	0.04	0.138	5
1092106	Soil	6.8	107.1	62.0	498	3.4	88.4	19.8	801	6.60	29.4	3.2	1.8	140	0.4	3.1	0.3	32	0.30	0.341	7
1092107	Soil	7.0	28.1	14.1	110	0.1	30.1	6.5	89	2.35	18.4	1.3	<0.1	13	0.2	1.7	0.2	64	0.03	0.121	7
1092108	Soil	8.3	99.7	27.2	396	0.4	179.2	36.7	566	6.94	37.0	2.6	1.8	11	0.4	2.8	0.5	33	0.03	0.150	38
1092109	Soil	5.1	15.7	10.8	77	0.3	20.1	3.8	155	1.17	7.6	<0.5	0.1	13	0.2	1.0	0.1	41	0.03	0.117	7
1092110	Soil	8.3	20.8	15.1	91	0.5	23.7	3.2	58	1.59	14.1	0.5	<0.1	23	0.2	1.7	0.2	66	0.02	0.127	8
1092111	Soil	8.6	121.8	29.1	344	1.8	119.9	21.7	428	6.58	74.2	15.4	3.9	40	1.2	3.8	0.3	47	0.29	0.156	17
1092112	Soil	6.4	28.2	19.8	117	0.2	26.9	5.8	113	2.93	22.6	0.8	0.2	18	0.2	1.8	0.3	68	0.02	0.131	8
1092113	Soil	3.3	14.8	13.8	56	0.2	13.9	2.9	47	1.38	11.0	5.0	<0.1	16	<0.1	0.9	0.2	48	0.02	0.108	9
1092114	Soil	6.3	44.3	22.7	170	0.3	50.0	10.1	273	3.10	41.3	1.1	0.4	34	0.3	2.4	0.3	61	0.09	0.206	12
1092115	Soil	5.4	48.7	20.5	161	0.3	51.1	12.9	406	3.27	33.5	<0.5	0.8	32	0.4	2.2	0.2	55	0.20	0.322	15
1092116	Soil	3.5	22.1	10.7	82	0.2	21.8	5.7	137	2.23	22.5	2.4	0.2	13	0.2	1.1	0.1	40	0.05	0.175	11
1092117	Soil	4.3	115.1	22.2	117	1.3	96.2	36.9	888	8.01	56.6	10.4	1.1	29	0.5	2.3	0.4	39	0.28	0.138	29

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091988	Soil	108	2.26	824	0.006	12	0.73	0.006	0.20	0.4	4.19	4.5	1.5	0.07	2	14.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091989	Soil	81	0.52	1696	0.010	8	0.85	0.012	0.18	0.4	1.41	3.4	2.0	0.13	3	12.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091990	Soil	35	0.13	595	0.004	3	0.66	0.013	0.08	0.2	1.46	2.9	0.7	<0.05	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091991	Soil	29	0.09	214	0.003	4	0.69	0.004	0.10	0.2	0.12	0.5	1.9	0.05	3	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091992	Soil	33	0.19	296	0.007	2	1.14	0.004	0.10	0.2	0.11	0.9	1.5	<0.05	4	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091993	Soil	6	0.02	286	0.003	3	0.43	0.004	0.08	<0.1	0.20	0.8	0.2	<0.05	1	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091994	Soil	21	0.06	408	0.004	5	0.59	0.005	0.25	<0.1	0.10	0.3	0.5	0.39	2	5.1	0.2	N.A.	N.A.	N.A.	N.A.
1091995	Soil	11	0.04	303	0.005	4	0.52	0.006	0.12	<0.1	0.03	1.5	0.2	0.06	2	0.9	0.2	N.A.	N.A.	N.A.	N.A.
1091996	Soil	14	0.20	1920	0.005	6	0.91	0.005	0.15	<0.1	0.07	4.5	0.2	0.11	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091997	Soil	9	0.06	2710	0.002	5	0.43	0.003	0.15	<0.1	0.39	5.0	0.2	0.12	<1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091998	Soil	13	0.07	1123	0.002	4	0.41	0.002	0.11	<0.1	0.25	5.8	0.2	0.05	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1091999	Soil	54	1.65	810	0.006	12	0.58	0.005	0.17	0.4	0.56	4.0	3.5	0.07	2	7.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092000	Soil	72	0.73	964	0.007	14	0.84	0.004	0.21	0.4	0.94	5.3	4.7	0.07	3	7.7	0.2	N.A.	N.A.	N.A.	N.A.
1092101	Soil	28	0.07	777	0.002	2	0.60	0.003	0.11	0.1	0.65	2.9	1.3	0.08	2	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092102	Soil	9	0.03	62	0.002	1	0.53	0.009	0.03	<0.1	0.03	0.2	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092103	Soil	15	0.07	994	0.002	3	0.39	0.002	0.09	0.1	0.62	3.1	1.0	0.07	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092104	Soil	12	0.06	800	0.002	2	0.71	0.004	0.06	<0.1	0.04	0.3	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092105	Soil	9	0.03	959	0.001	2	0.53	0.006	0.07	<0.1	0.05	0.1	0.2	0.09	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092106	Soil	16	0.06	814	0.005	3	1.12	0.008	0.41	<0.1	0.16	5.9	0.3	0.56	2	10.4	0.2	N.A.	N.A.	N.A.	N.A.
1092107	Soil	11	0.04	391	0.001	2	0.55	0.004	0.08	0.1	0.02	0.2	0.2	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092108	Soil	12	0.10	1006	0.003	3	0.69	0.003	0.08	<0.1	0.06	5.5	0.1	<0.05	2	3.2	0.2	N.A.	N.A.	N.A.	N.A.
1092109	Soil	8	0.04	112	0.002	2	0.48	0.013	0.06	<0.1	0.03	0.2	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092110	Soil	12	0.04	149	0.001	2	0.58	0.008	0.08	<0.1	0.05	0.1	0.4	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092111	Soil	19	0.20	4825	0.010	3	0.88	0.007	0.15	<0.1	0.57	7.0	0.3	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092112	Soil	16	0.05	143	0.003	<1	0.70	0.003	0.07	<0.1	0.01	0.2	0.2	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092113	Soil	12	0.05	181	0.001	1	0.65	0.004	0.06	<0.1	0.02	<0.1	0.2	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092114	Soil	16	0.06	424	0.004	2	0.60	0.003	0.09	0.1	0.07	0.7	0.2	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092115	Soil	17	0.13	548	0.006	3	0.88	0.004	0.11	0.1	0.06	1.1	0.2	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092116	Soil	17	0.12	252	0.002	1	0.94	0.004	0.07	<0.1	0.05	0.3	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092117	Soil	22	0.25	1158	0.006	2	1.30	0.007	0.09	0.1	0.24	4.1	0.2	<0.05	3	1.8	0.3	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091988	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091989	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091990	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091991	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091992	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091993	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091994	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091995	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091996	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091997	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091998	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091999	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092000	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091988	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091989	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091990	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091991	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091992	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091993	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091994	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091995	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091996	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091997	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091998	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091999	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092000	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092118	Soil	4.6	57.3	20.7	183	0.5	58.9	13.7	162	4.67	49.7	2.9	1.2	33	0.4	2.6	0.2	52	0.10	0.315	13
1092119	Soil	2.5	74.9	35.5	221	2.2	53.0	43.3	1078	6.88	16.9	6.7	1.3	20	0.3	2.1	0.4	22	0.09	0.142	10
1092120	Soil	6.9	35.5	14.3	98	0.1	39.7	18.6	146	3.78	41.1	2.4	0.9	12	0.1	3.0	0.4	47	0.03	0.056	11
1092121	Soil	2.3	21.5	4.8	42	<0.1	13.8	4.9	106	1.77	17.5	<0.5	0.1	5	<0.1	1.0	0.2	30	0.02	0.053	7
1092122	Soil	5.4	30.0	13.9	93	0.1	34.1	7.5	87	2.32	34.3	1.6	1.0	16	<0.1	1.9	0.3	52	0.04	0.045	11
1092123	Soil	3.4	21.6	7.1	51	0.2	20.1	5.6	120	1.50	13.2	1.3	0.4	45	0.1	1.3	0.1	34	0.53	0.114	8
1092124	Soil	2.3	23.5	11.2	37	0.1	18.4	7.2	229	2.50	11.2	<0.5	1.6	8	0.1	1.0	0.2	25	0.04	0.047	8
1092125	Soil	3.5	39.0	15.8	97	0.3	30.1	17.7	882	2.96	38.3	3.6	1.2	12	0.2	1.5	0.3	40	0.08	0.106	12
1092126	Soil	5.4	35.5	18.6	91	0.4	34.6	13.1	377	2.48	58.1	<0.5	0.5	15	0.2	1.9	0.3	49	0.05	0.147	10
1092127	Soil	1.7	14.5	5.2	29	<0.1	9.9	3.2	78	0.99	43.5	<0.5	<0.1	6	0.1	0.7	<0.1	19	0.04	0.056	3
1092128	Soil	2.1	52.1	14.2	88	0.8	38.2	13.9	664	3.96	145.8	4.3	1.0	31	0.3	1.7	0.3	30	0.39	0.170	15
1092129	Soil	0.9	35.5	7.6	28	0.6	17.8	9.4	365	1.64	94.2	3.0	0.2	15	<0.1	0.7	0.1	11	0.23	0.065	6
1092130	Soil	0.4	11.6	3.6	12	0.4	5.2	4.6	191	0.59	35.5	2.6	0.2	12	<0.1	0.3	<0.1	9	0.19	0.052	3
1092131	Soil	2.9	41.3	14.7	106	0.8	43.5	12.9	355	3.03	94.0	4.8	1.1	28	0.2	1.6	0.2	30	0.36	0.084	9
1092132	Soil	5.8	112.6	22.7	252	1.2	111.5	14.8	349	3.84	46.8	3.8	3.3	21	0.9	7.0	0.2	32	0.29	0.098	17
1092133	Soil	13.8	65.2	14.6	419	0.7	75.2	10.1	278	3.22	47.8	3.7	1.4	24	1.8	5.8	0.2	82	0.32	0.111	12
1092134	Soil	12.9	62.7	14.9	433	1.1	66.4	9.3	219	2.80	43.0	2.0	2.2	35	2.4	5.8	0.2	95	0.43	0.117	14
1092135	Soil	9.9	54.6	24.4	263	0.8	69.9	14.3	260	3.51	109.9	2.4	1.8	28	0.7	4.2	0.2	32	0.37	0.097	12
1092136	Soil	11.1	58.8	32.2	250	1.1	79.1	18.2	456	4.64	132.3	2.8	1.8	25	0.9	5.1	0.2	36	0.39	0.076	9
1092137	Soil	18.8	24.7	10.9	204	0.9	43.0	5.0	83	1.89	22.2	<0.5	0.1	8	0.5	3.7	0.1	128	0.03	0.110	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092118	Soil	18	0.14	2113	0.007	2	1.17	0.005	0.10	0.1	0.12	2.4	0.2	0.10	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092119	Soil	11	0.09	2285	0.008	2	1.22	0.010	0.12	<0.1	0.10	2.8	0.3	0.13	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092120	Soil	9	0.04	712	0.011	1	0.46	0.005	0.08	0.1	0.02	1.3	0.2	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092121	Soil	8	0.03	174	0.006	2	0.57	0.012	0.07	<0.1	0.02	0.4	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092122	Soil	10	0.04	1052	0.009	2	0.43	0.003	0.08	0.1	0.03	1.8	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092123	Soil	12	0.13	1838	0.009	4	0.61	0.006	0.10	0.2	0.04	2.1	0.1	0.09	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092124	Soil	9	0.05	833	0.006	2	0.67	0.008	0.09	<0.1	0.05	1.6	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092125	Soil	15	0.16	289	0.016	3	1.04	0.011	0.08	0.2	0.05	2.3	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092126	Soil	16	0.06	1892	0.010	6	0.55	0.004	0.13	0.2	0.07	2.0	0.1	0.09	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092127	Soil	7	0.04	176	0.007	1	0.46	0.022	0.05	<0.1	0.03	0.4	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092128	Soil	16	0.12	2056	0.009	2	0.86	0.003	0.12	<0.1	0.27	6.9	0.1	0.07	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092129	Soil	6	0.07	516	0.011	2	0.68	0.024	0.05	<0.1	0.09	1.6	<0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092130	Soil	2	0.04	164	0.016	<1	0.66	0.033	0.04	<0.1	0.03	1.0	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092131	Soil	13	0.17	963	0.007	3	0.77	0.014	0.09	<0.1	0.17	4.3	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092132	Soil	16	0.08	499	0.002	2	0.34	0.002	0.09	<0.1	0.38	6.5	0.2	<0.05	<1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092133	Soil	14	0.08	1076	0.002	3	0.48	0.003	0.07	<0.1	0.33	3.2	0.2	<0.05	1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092134	Soil	12	0.08	845	0.003	3	0.40	0.003	0.08	<0.1	0.47	4.3	0.2	<0.05	1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092135	Soil	9	0.09	576	0.002	3	0.48	0.003	0.11	<0.1	0.25	4.3	0.2	<0.05	1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092136	Soil	9	0.11	848	0.002	4	0.51	0.004	0.12	<0.1	0.37	5.1	0.2	<0.05	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092137	Soil	17	0.06	313	0.002	2	0.60	0.005	0.08	<0.1	0.10	0.2	0.3	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

CERTIFICATE OF ANALYSIS WHI11000746.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

QUALITY CONTROL REPORT WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1090897	Soil	5.0	22.9	14.8	130	0.3	27.0	8.3	81	2.47	14.0	<0.5	0.2	13	0.2	1.6	0.2	40	0.02	0.085	4
REP 1090897	QC	5.1	24.3	15.5	138	0.3	26.2	8.2	81	2.47	14.3	<0.5	0.2	14	0.2	1.8	0.2	37	0.01	0.085	4
1090852	Soil	2.5	35.5	14.5	205	1.6	55.5	8.7	308	2.67	22.3	9.3	1.0	86	1.0	2.9	0.2	61	1.55	0.243	19
REP 1090852	QC	2.6	34.7	14.2	209	1.5	57.6	8.6	322	2.90	22.9	9.2	0.9	85	0.8	3.0	0.2	61	1.58	0.239	18
1091393	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1091393	QC																				
1091604	Soil	3.1	96.8	16.1	196	1.1	80.6	30.3	3982	4.59	13.7	10.6	3.1	84	0.3	1.3	0.3	35	0.02	0.123	6
REP 1091604	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091630	Soil	66.7	125.6	14.6	1172	1.7	253.9	21.3	349	3.91	50.6	3.4	1.7	141	13.8	21.8	0.1	417	4.94	0.257	12
REP 1091630	QC	67.3	127.2	14.6	1168	1.6	262.0	21.5	342	3.88	49.3	3.2	1.6	142	14.0	21.5	0.1	413	4.85	0.253	12
1091784	Soil	16.3	175.7	56.6	807	2.2	144.0	17.0	748	4.98	121.3	7.4	2.4	87	5.9	12.9	0.4	112	0.81	0.358	18
REP 1091784	QC	16.2	178.5	58.0	821	2.1	146.7	16.8	769	5.05	124.0	7.7	2.3	88	6.0	12.9	0.4	110	0.82	0.366	19
1091790	Soil	5.7	32.2	16.4	93	0.2	35.5	8.3	301	2.41	25.2	2.1	0.4	10	0.3	1.9	0.3	36	0.03	0.097	12
REP 1091790	QC	6.4	33.2	17.1	96	0.2	35.1	8.5	325	2.55	25.6	1.0	0.4	11	0.3	1.9	0.3	36	0.03	0.100	12
1091815	Soil	12.3	20.7	9.4	86	0.5	16.3	2.2	29	1.27	21.6	1.4	<0.1	13	0.1	3.1	0.1	102	0.01	0.069	6
REP 1091815	QC	12.7	21.2	10.0	86	0.4	16.0	2.2	28	1.23	20.1	2.0	0.1	13	0.1	3.1	0.1	97	<0.01	0.070	6
1091825	Soil	5.6	127.0	28.4	225	1.3	56.9	11.4	77	3.31	23.9	5.6	4.7	25	0.3	3.6	0.3	13	0.08	0.084	19
REP 1091825	QC	5.1	130.3	28.8	229	1.3	56.7	11.1	75	3.36	25.0	5.5	5.2	26	0.3	3.6	0.3	12	0.08	0.083	20
1091840	Soil	1.1	36.4	11.1	212	0.8	58.8	8.3	111	2.13	14.7	3.0	1.2	134	1.3	2.1	0.2	32	3.43	0.187	5
REP 1091840	QC	1.2	37.4	10.8	215	0.8	60.8	8.8	111	2.22	15.1	5.1	1.2	134	1.3	2.2	0.2	33	3.40	0.185	5
1091864	Soil	63.7	58.3	15.7	469	0.3	148.8	6.6	218	1.68	22.1	0.8	2.0	166	3.8	7.2	0.1	128	9.44	0.078	4
REP 1091864	QC	65.2	61.0	16.1	486	0.3	156.2	6.8	230	1.76	22.3	1.8	2.2	172	3.9	7.3	0.1	136	10.12	0.080	4
1091901	Soil	2.7	7.5	7.5	24	0.9	7.2	1.0	15	0.46	5.0	1.5	<0.1	9	<0.1	1.3	0.1	37	0.01	0.023	6
REP 1091901	QC	2.7	7.4	7.3	23	0.9	7.0	1.0	15	0.45	5.1	<0.5	0.1	10	<0.1	1.2	0.1	37	0.01	0.024	6
1091916	Soil	8.7	33.0	18.2	115	0.9	34.9	3.3	33	2.64	48.6	7.8	0.4	25	0.1	4.3	0.2	48	<0.01	0.071	2
REP 1091916	QC	8.7	33.6	18.4	116	0.9	34.1	3.3	32	2.66	49.4	5.6	0.5	25	0.1	4.3	0.3	49	<0.01	0.069	2
1091934	Soil	3.3	108.8	45.0	204	1.8	51.9	7.3	139	4.99	59.8	4.2	1.7	26	0.1	2.3	0.5	62	0.03	0.090	4
REP 1091934	QC	3.0	107.2	41.4	200	1.7	50.3	7.2	134	4.96	57.8	3.4	1.6	24	0.2	2.2	0.5	59	0.02	0.085	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

QUALITY CONTROL REPORT WHI11000746.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1090897	Soil	10	0.02	77	0.004	<1	0.46	0.006	0.04	<0.1	0.02	0.8	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090897	QC	10	0.02	68	0.004	<1	0.44	0.006	0.04	<0.1	0.02	0.9	0.2	<0.05	2	0.6	<0.2				
1090852	Soil	45	0.20	747	0.007	4	1.06	0.006	0.08	0.1	0.75	3.2	0.2	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090852	QC	46	0.21	748	0.007	5	1.07	0.006	0.08	0.1	0.70	3.3	0.1	0.07	3	1.5	<0.2				
1091393	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.9	38.2	17.1	182
REP 1091393	QC																	3.0	39.8	17.3	185
1091604	Soil	28	0.11	993	0.005	<1	1.72	0.007	0.04	<0.1	0.28	6.1	0.1	0.10	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091604	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1091630	Soil	57	1.89	369	0.004	7	0.53	0.006	0.09	0.2	0.64	6.7	1.1	0.06	1	8.1	0.2	N.A.	N.A.	N.A.	N.A.
REP 1091630	QC	57	1.86	365	0.004	7	0.53	0.006	0.08	0.1	0.60	6.7	1.1	<0.05	1	7.6	<0.2				
1091784	Soil	23	0.15	794	0.004	7	0.67	0.003	0.20	0.1	1.33	5.1	0.5	0.17	2	5.1	0.2	N.A.	N.A.	N.A.	N.A.
REP 1091784	QC	23	0.15	823	0.004	8	0.71	0.003	0.20	0.1	1.36	5.2	0.6	0.16	2	3.9	0.2				
1091790	Soil	10	0.03	180	0.003	2	0.57	0.009	0.10	<0.1	0.07	0.5	0.2	0.07	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091790	QC	10	0.03	178	0.003	2	0.56	0.008	0.09	<0.1	0.08	0.6	0.2	0.09	2	1.1	<0.2				
1091815	Soil	10	0.02	133	0.003	2	0.37	0.005	0.05	<0.1	0.10	0.3	0.3	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091815	QC	10	0.02	129	0.002	2	0.37	0.005	0.05	0.1	0.09	0.2	0.2	<0.05	2	1.3	<0.2				
1091825	Soil	6	0.02	3687	0.001	5	0.27	0.001	0.06	<0.1	1.72	3.3	0.1	0.10	<1	5.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091825	QC	6	0.02	4074	0.001	4	0.29	0.001	0.06	<0.1	1.76	3.4	0.2	0.12	<1	5.3	<0.2				
1091840	Soil	16	0.14	570	0.002	4	0.46	0.005	0.06	<0.1	0.17	2.6	<0.1	0.08	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091840	QC	18	0.14	625	0.002	4	0.47	0.006	0.06	<0.1	0.18	2.6	<0.1	0.09	1	2.5	<0.2				
1091864	Soil	14	3.47	179	0.001	4	0.13	0.006	0.04	0.1	0.27	3.2	1.0	<0.05	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091864	QC	14	3.46	178	0.001	4	0.13	0.007	0.04	0.1	0.28	3.4	1.0	0.07	<1	2.4	<0.2				
1091901	Soil	7	<0.01	100	0.003	<1	0.22	0.003	0.02	<0.1	0.04	0.2	0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091901	QC	8	<0.01	107	0.005	1	0.24	0.004	0.03	<0.1	0.04	0.1	0.2	<0.05	2	<0.5	<0.2				
1091916	Soil	13	0.01	241	0.002	1	0.40	0.003	0.04	<0.1	0.10	1.0	0.1	0.06	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091916	QC	14	0.01	251	0.001	2	0.42	0.003	0.05	<0.1	0.09	1.0	0.2	0.06	2	3.0	<0.2				
1091934	Soil	27	0.17	289	0.003	2	1.16	0.004	0.07	<0.1	0.11	3.0	0.1	0.08	4	3.6	0.3	N.A.	N.A.	N.A.	N.A.
REP 1091934	QC	27	0.15	275	0.002	2	1.15	0.004	0.07	<0.1	0.11	2.8	0.1	<0.05	4	3.6	0.3				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

QUALITY CONTROL REPORT WHI11000746.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1090897	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090897	QC																					
1090852	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090852	QC																					
1091393	Soil		1.4	57.6	8.4	118	2.43	18.1	10.2	0.8	87	0.8	1.3	0.3	32	1.12	0.137	6	19	0.07	535	<0.001
REP 1091393	QC		1.4	59.9	8.4	122	2.45	18.0	6.9	0.8	88	0.8	1.2	0.3	32	1.14	0.137	6	20	0.07	543	<0.001
1091604	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091604	QC																					
1091630	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091630	QC																					
1091784	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091784	QC																					
1091790	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091790	QC																					
1091815	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091815	QC																					
1091825	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091825	QC																					
1091840	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091840	QC																					
1091864	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091864	QC																					
1091901	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091901	QC																					
1091916	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091916	QC																					
1091934	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091934	QC																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

QUALITY CONTROL REPORT WHI11000746.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1090897	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090897	QC													
1090852	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090852	QC													
1091393	Soil		<20	0.55	0.004	0.08	<0.1	0.21	2.3	0.1	0.14	1	3.1	<0.2
REP 1091393	QC		<20	0.54	0.004	0.09	<0.1	0.21	2.3	0.1	0.13	1	3.1	<0.2
1091604	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091604	QC													
1091630	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091630	QC													
1091784	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091784	QC													
1091790	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091790	QC													
1091815	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091815	QC													
1091825	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091825	QC													
1091840	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091840	QC													
1091864	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091864	QC													
1091901	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091901	QC													
1091916	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091916	QC													
1091934	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091934	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

QUALITY CONTROL REPORT WHI11000746.3

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1091958	Soil	33.4	110.9	19.6	1942	1.7	286.9	7.9	225	2.94	41.0	6.9	1.6	52	39.4	14.5	0.2	320	0.47	0.174	16
REP 1091958	QC	32.4	114.6	19.8	1972	1.8	291.7	8.3	220	2.98	41.8	6.4	1.6	50	39.2	13.5	0.2	320	0.52	0.191	17
1091986	Soil	79.5	65.1	11.9	208	0.2	187.9	8.3	161	2.08	30.4	0.7	3.4	144	1.8	4.6	0.1	60	5.79	0.095	6
REP 1091986	QC	79.7	64.9	11.4	206	0.2	178.5	7.9	160	2.01	29.8	<0.5	3.4	144	1.8	4.8	0.1	62	5.78	0.094	7
1091994	Soil	15.9	137.6	64.4	328	1.2	52.5	8.0	115	3.23	24.1	8.0	0.2	59	0.5	6.4	0.4	79	0.14	0.222	9
REP 1091994	QC	15.5	138.3	64.3	326	1.1	52.8	8.1	113	3.25	23.5	7.3	0.2	58	0.5	5.9	0.3	76	0.16	0.221	9
1092133	Soil	13.8	65.2	14.6	419	0.7	75.2	10.1	278	3.22	47.8	3.7	1.4	24	1.8	5.8	0.2	82	0.32	0.111	12
REP 1092133	QC	13.2	64.8	14.3	412	0.7	73.0	9.9	269	3.13	47.4	2.1	1.2	23	1.8	6.1	0.2	79	0.31	0.107	11
Reference Materials																					
STD DS8	Standard	14.2	114.9	121.9	317	1.9	39.8	7.9	624	2.54	27.0	112.4	6.9	59	2.4	4.9	5.5	45	0.70	0.082	15
STD DS8	Standard	13.5	107.5	119.6	300	1.8	35.6	7.5	580	2.39	24.8	110.3	6.4	61	2.2	5.6	6.4	42	0.64	0.074	13
STD DS8	Standard	13.1	113.3	119.0	309	1.8	39.3	8.1	622	2.51	27.7	116.0	7.2	63	2.5	5.1	6.0	43	0.70	0.082	14
STD DS8	Standard	13.6	114.5	125.6	312	1.8	41.2	7.9	637	2.51	26.6	119.3	6.8	62	2.2	5.8	6.6	44	0.70	0.080	14
STD DS8	Standard	11.9	107.5	125.7	295	1.7	37.0	7.4	559	2.31	25.1	106.9	6.4	59	2.3	5.7	6.6	39	0.62	0.076	12
STD DS8	Standard	12.7	111.4	126.2	305	1.7	38.0	7.7	600	2.41	27.7	107.7	6.9	56	2.1	4.9	5.3	42	0.68	0.077	13
STD DS8	Standard	13.1	106.6	115.6	279	1.7	35.9	7.2	593	2.29	25.3	102.3	6.7	63	2.1	5.3	6.2	41	0.65	0.072	15
STD DS8	Standard	12.9	111.4	115.9	310	1.9	39.6	7.3	598	2.45	28.6	113.1	6.5	63	2.3	5.6	6.5	41	0.66	0.079	14
STD DS8	Standard	12.0	104.3	131.8	302	1.8	39.3	7.9	607	2.48	24.8	106.0	6.2	58	2.3	5.3	6.7	43	0.66	0.078	11
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

QUALITY CONTROL REPORT WHI11000746.3

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1091958	Soil	23	0.09	861	0.005	8	0.69	0.003	0.12	0.2	1.53	3.4	2.1	<0.05	2	6.9	0.2	N.A.	N.A.	N.A.	N.A.
REP 1091958	QC	24	0.09	860	0.005	5	0.71	0.003	0.13	0.2	1.58	3.3	2.0	<0.05	2	7.0	0.2				
1091986	Soil	12	2.25	296	0.002	5	0.21	0.004	0.07	0.2	0.39	3.4	1.3	0.06	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091986	QC	13	2.28	313	0.002	5	0.24	0.004	0.08	0.2	0.37	3.2	1.4	0.06	<1	2.1	<0.2				
1091994	Soil	21	0.06	408	0.004	5	0.59	0.005	0.25	<0.1	0.10	0.3	0.5	0.39	2	5.1	0.2	N.A.	N.A.	N.A.	N.A.
REP 1091994	QC	19	0.05	393	0.003	4	0.57	0.005	0.24	<0.1	0.09	0.3	0.4	0.39	2	4.3	<0.2				
1092133	Soil	14	0.08	1076	0.002	3	0.48	0.003	0.07	<0.1	0.33	3.2	0.2	<0.05	1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092133	QC	13	0.08	1053	0.002	2	0.48	0.003	0.07	<0.1	0.30	3.3	0.2	<0.05	1	3.0	<0.2				
Reference Materials																					
STD DS8	Standard	122	0.63	285	0.116	3	0.97	0.091	0.44	3.0	0.18	2.4	5.3	0.14	5	5.3	4.2				
STD DS8	Standard	116	0.57	262	0.112	4	0.85	0.080	0.39	2.9	0.21	2.2	5.3	0.17	4	5.6	4.9				
STD DS8	Standard	117	0.53	289	0.119	2	0.94	0.102	0.43	2.8	0.20	2.2	5.2	0.16	5	5.3	5.1				
STD DS8	Standard	122	0.61	276	0.122	2	0.87	0.086	0.41	3.1	0.21	2.0	5.4	0.17	5	5.5	5.4				
STD DS8	Standard	109	0.56	261	0.100	2	0.81	0.086	0.40	2.9	0.19	2.1	5.2	0.14	4	4.7	4.5				
STD DS8	Standard	118	0.59	258	0.108	3	0.90	0.095	0.42	2.8	0.19	2.2	4.9	0.16	5	4.6	4.8				
STD DS8	Standard	115	0.57	265	0.118	3	0.85	0.083	0.38	3.0	0.19	2.0	5.0	0.14	4	4.8	4.5				
STD DS8	Standard	112	0.61	290	0.107	3	0.91	0.085	0.42	3.2	0.21	2.0	5.0	0.15	5	4.7	4.7				
STD DS8	Standard	117	0.63	259	0.098	3	0.92	0.089	0.42	3.1	0.22	1.9	5.8	0.16	5	5.1	4.7				
STD DS8	Standard																	13.4	105.2	127.2	302
STD OREAS45CA	Standard																	1.1	529.5	22.3	62
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

QUALITY CONTROL REPORT WHI11000746.3

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1091958	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091958	QC																				
1091986	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091986	QC																				
1091994	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091994	QC																				
1092133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092133	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	2.0	36.0	7.3	594	2.38	24.2	90.5	7.0	66	2.4	5.5	6.7	40	0.68	0.078	15	110	0.56	287	0.111
STD OREAS45CA	Standard	0.3	239.8	88.1	941	16.80	4.3	40.2	7.6	17	0.1	0.1	0.2	210	0.44	0.040	17	700	0.14	164	0.144
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

QUALITY CONTROL REPORT WHI11000746.3

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1091958	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091958	QC												
1091986	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091986	QC												
1091994	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091994	QC												
1092133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092133	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.86	0.083	0.39	2.5	0.18	1.9	5.4	0.15	5	5.2	4.6
STD OREAS45CA	Standard	<20	3.86	0.012	0.07	<0.1	0.03	38.2	<0.1	<0.05	19	0.8	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

QUALITY CONTROL REPORT WHI11000746.3

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

QUALITY CONTROL REPORT WHI11000746.3

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

QUALITY CONTROL REPORT WHI11000746.3

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 30, 2011

QUALITY CONTROL REPORT WHI11000746.3

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 26, 2011
Report Date: October 06, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11000747.3

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #5
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve to 230 mesh			VAN
1DX2	307	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	13	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 3: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092138	Soil	14.9	16.4	8.9	144	0.1	27.4	3.6	50	1.13	17.4	<0.5	0.2	6	<0.1	3.3	0.1	94	0.01	0.059	11
1092139	Soil	21.1	40.8	16.3	318	0.5	69.1	7.6	101	3.15	58.0	0.9	0.4	5	0.5	6.7	0.2	158	0.02	0.126	9
1092140	Soil	10.7	15.2	7.0	164	0.5	27.5	3.4	220	0.95	14.6	2.9	0.2	17	0.7	3.0	<0.1	73	0.17	0.066	6
1092201	Soil	65.7	74.7	12.9	1034	1.1	195.2	9.3	164	2.03	69.3	1.1	2.0	112	13.8	16.7	<0.1	546	4.11	0.217	23
1092202	Soil	62.3	89.9	11.2	818	0.9	215.7	11.9	210	1.95	61.4	<0.5	1.5	150	10.2	12.9	0.2	318	5.19	0.194	17
1092203	Soil	50.3	63.1	13.5	428	0.2	170.0	12.1	71	2.46	64.8	<0.5	0.4	11	1.4	8.1	0.2	320	0.10	0.092	18
1092204	Soil	34.4	31.3	7.5	197	0.3	94.1	7.3	265	1.54	23.6	<0.5	0.2	43	1.4	3.2	0.2	110	1.04	0.090	9
1092205	Soil	52.3	41.3	7.8	221	0.1	114.8	7.2	134	1.68	26.7	<0.5	0.2	12	1.4	3.7	0.2	96	0.09	0.093	14
1092206	Soil	35.4	26.1	4.8	201	0.1	82.0	4.2	84	1.16	18.5	1.4	0.2	18	1.2	2.7	0.1	65	0.31	0.125	6
1092207	Soil	53.8	41.7	8.4	201	0.1	106.2	5.4	37	1.56	26.3	<0.5	0.2	8	0.9	3.6	0.3	142	0.08	0.101	11
1092208	Soil	60.7	44.5	9.0	215	<0.1	121.7	6.9	67	1.81	28.9	<0.5	0.4	10	1.2	3.5	0.2	107	0.10	0.099	14
1092209	Soil	38.7	96.4	21.9	298	0.4	355.3	45.4	720	5.41	61.9	0.9	4.4	112	2.4	6.0	0.2	220	2.35	0.358	39
1092210	Soil	42.7	109.8	16.8	453	0.7	349.2	43.4	687	6.42	103.6	<0.5	3.6	98	4.7	7.3	0.2	275	1.91	0.348	38
1092211	Soil	76.5	119.2	15.1	1382	1.4	234.4	9.1	192	1.97	61.4	0.6	1.0	161	10.8	19.4	0.2	558	5.36	0.139	17
1092212	Soil	54.8	122.1	12.7	1335	2.3	259.9	7.0	111	2.21	85.6	2.6	0.9	100	13.4	19.9	0.3	678	1.33	0.378	24
1092213	Soil	85.2	149.9	14.2	1465	2.7	235.8	7.1	137	1.66	84.3	1.0	1.4	138	22.1	23.0	0.2	1203	5.74	0.217	17
1092214	Soil	97.4	154.9	15.6	1798	3.5	262.8	6.8	179	1.53	77.8	<0.5	1.2	205	20.0	24.9	0.2	1496	6.46	0.197	16
1092215	Soil	124.6	166.5	18.1	2164	3.4	363.2	10.2	235	1.83	79.9	<0.5	1.7	157	19.2	27.1	0.2	1326	6.39	0.190	16
1092216	Soil	87.3	174.1	18.0	2057	3.9	329.7	7.2	171	1.66	110.2	4.0	1.6	198	22.3	29.9	0.3	1377	6.90	0.246	16
1092217	Soil	53.1	215.5	12.8	1973	4.5	424.2	7.2	149	1.89	140.1	3.5	2.4	271	16.3	40.7	0.3	906	6.10	0.789	29
1092218	Soil	69.9	117.2	22.1	1709	3.0	311.2	12.2	258	2.64	118.0	1.1	3.7	245	15.7	28.3	0.2	749	9.55	0.202	13
1092219	Soil	149.5	130.6	15.2	3116	2.8	441.3	16.4	238	2.59	190.4	0.6	4.7	181	41.5	38.5	0.2	1180	2.82	0.176	18
1092220	Soil	108.5	112.5	13.6	1676	3.8	394.4	23.9	266	3.77	303.4	8.1	2.9	101	23.2	28.6	0.2	954	1.05	0.275	37
1092221	Soil	25.7	127.5	19.3	345	0.6	456.6	72.9	1255	7.85	782.6	2.2	11.4	147	2.7	11.5	0.1	292	1.52	0.475	96
1092222	Soil	18.4	66.0	13.3	387	1.0	137.1	18.8	332	3.57	199.3	5.0	2.2	62	2.9	8.0	0.2	115	0.59	0.159	20
1092223	Soil	8.8	137.2	15.5	202	0.5	546.2	95.2	1359	8.91	795.8	7.2	12.3	295	1.5	11.5	0.2	142	2.35	0.552	83
1092224	Soil	49.5	65.1	26.8	578	0.8	142.5	8.4	83	3.44	100.6	5.2	1.0	21	1.1	15.7	0.4	523	0.03	0.135	12
1092225	Soil	7.6	119.1	20.0	358	4.1	107.1	16.7	233	5.23	83.8	5.8	1.3	35	0.9	5.3	0.3	53	0.28	0.128	14
1092226	Soil	139.2	231.7	23.3	4698	4.0	347.7	7.1	144	1.95	135.1	2.7	1.1	228	44.9	49.9	0.2	1562	4.60	0.276	26
1092227	Soil	71.0	79.4	15.0	426	2.7	205.8	12.1	604	2.39	33.0	2.0	1.6	42	0.7	6.8	0.1	114	1.97	0.120	18

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092138	Soil	11	0.03	123	0.002	3	0.42	0.003	0.07	<0.1	0.01	0.2	0.3	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092139	Soil	23	0.04	129	0.002	2	0.50	0.003	0.06	<0.1	0.07	0.5	0.3	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092140	Soil	10	0.05	396	0.002	2	0.40	0.012	0.04	<0.1	0.06	0.5	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092201	Soil	46	1.75	643	0.006	11	0.56	0.005	0.14	0.3	0.60	4.3	1.9	<0.05	2	6.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092202	Soil	35	2.26	413	0.004	10	0.35	0.005	0.09	0.3	0.62	3.5	1.8	0.15	<1	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092203	Soil	38	0.09	279	0.002	5	0.51	0.003	0.07	0.3	0.16	0.8	1.2	0.07	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092204	Soil	19	0.11	388	0.002	5	0.44	0.009	0.05	0.2	0.10	0.5	0.9	0.08	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092205	Soil	15	0.07	443	0.002	3	0.42	0.002	0.07	0.2	0.06	0.2	1.1	<0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092206	Soil	12	0.06	273	0.002	4	0.63	0.008	0.04	0.1	0.04	0.4	0.9	0.06	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092207	Soil	20	0.08	202	0.004	5	0.67	0.005	0.09	0.3	0.02	0.4	2.0	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092208	Soil	21	0.07	486	0.003	3	0.52	0.002	0.07	0.3	0.06	0.8	1.7	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092209	Soil	87	0.92	1311	0.004	7	0.94	0.007	0.14	0.4	0.19	8.9	1.1	0.07	3	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092210	Soil	108	0.65	846	0.003	7	0.84	0.004	0.11	0.4	0.33	10.9	1.3	0.05	3	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092211	Soil	34	1.59	731	0.007	8	0.58	0.007	0.10	0.4	0.55	2.7	2.3	0.08	2	6.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092212	Soil	102	0.22	956	0.005	7	0.93	0.005	0.15	0.4	1.63	2.4	1.8	<0.05	3	11.6	0.2	N.A.	N.A.	N.A.	N.A.
1092213	Soil	80	2.66	1001	0.006	10	0.63	0.007	0.14	0.5	1.30	3.5	1.9	0.06	3	10.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092214	Soil	88	2.07	1688	0.007	15	0.78	0.006	0.18	0.5	1.24	3.0	4.2	0.07	3	9.1	0.3	N.A.	N.A.	N.A.	N.A.
1092215	Soil	77	3.27	906	0.006	11	0.60	0.009	0.14	0.5	0.69	3.8	4.9	0.08	3	12.0	0.2	N.A.	N.A.	N.A.	N.A.
1092216	Soil	89	3.04	524	0.009	16	0.64	0.010	0.16	0.5	9.29	3.7	4.0	0.08	3	12.8	0.3	N.A.	N.A.	N.A.	N.A.
1092217	Soil	198	2.10	848	0.011	18	0.79	0.007	0.21	0.5	9.43	5.2	2.5	0.09	3	24.7	0.3	N.A.	N.A.	N.A.	N.A.
1092218	Soil	70	4.66	723	0.008	15	0.52	0.008	0.15	0.3	5.07	4.5	2.5	0.11	2	12.1	0.2	N.A.	N.A.	N.A.	N.A.
1092219	Soil	65	1.00	1971	0.027	12	0.53	0.003	0.15	0.6	5.44	5.9	4.0	0.06	2	17.3	0.3	N.A.	N.A.	N.A.	N.A.
1092220	Soil	116	0.40	3564	0.014	10	0.90	0.002	0.16	0.6	5.74	9.8	2.2	<0.05	3	11.0	0.3	N.A.	N.A.	N.A.	N.A.
1092221	Soil	283	2.59	1210	0.004	11	1.93	0.004	0.11	0.4	1.60	26.6	0.6	0.06	6	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092222	Soil	53	0.38	1130	0.002	4	0.65	0.004	0.06	0.1	24.47	5.2	0.3	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092223	Soil	181	0.79	3155	0.005	15	0.88	0.003	0.23	0.3	2.08	22.9	0.3	<0.05	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092224	Soil	40	0.05	360	0.003	3	0.60	0.002	0.08	0.3	5.37	1.3	1.0	<0.05	3	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092225	Soil	14	0.08	2126	0.002	3	0.71	0.002	0.08	<0.1	3.11	2.6	0.4	<0.05	2	3.8	0.2	N.A.	N.A.	N.A.	N.A.
1092226	Soil	78	1.34	562	0.007	13	0.92	0.005	0.22	0.6	2.82	4.2	5.3	0.08	3	7.9	0.3	N.A.	N.A.	N.A.	N.A.
1092227	Soil	43	0.75	470	0.002	7	0.77	0.003	0.08	0.3	0.62	8.7	1.7	<0.05	1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092218	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092222	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092224	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092226	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092227	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092218	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092222	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092224	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092226	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092227	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092228	Soil	105.0	135.2	10.5	1293	1.4	256.1	5.5	154	1.24	57.6	<0.5	2.0	299	10.3	20.7	0.2	933	9.57	0.112	16
1092229	Soil	14.1	61.1	21.5	140	1.1	62.4	11.7	225	4.18	42.1	2.1	0.3	32	1.2	2.4	0.3	53	0.33	0.145	11
1092230	Soil	8.1	62.7	16.0	127	0.2	49.4	16.7	493	5.32	135.0	2.8	1.8	12	0.9	4.5	0.7	50	0.12	0.132	19
1092231	Soil	24.0	58.6	18.5	244	0.3	70.6	23.9	1721	4.76	176.1	1.5	3.9	10	0.8	4.4	0.4	112	0.05	0.064	21
1092232	Soil	92.7	107.5	13.5	1321	1.2	215.9	7.2	139	1.96	69.0	1.3	1.2	37	19.2	15.9	0.2	560	0.49	0.098	18
1092233	Soil	115.6	178.2	15.4	1775	4.7	288.4	11.9	76	2.22	149.9	14.7	1.2	67	13.2	41.9	0.3	921	0.98	0.271	23
1092234	Soil	83.1	82.7	13.2	678	0.6	216.3	7.2	41	2.23	110.6	3.5	0.3	35	11.0	11.4	0.2	417	0.44	0.078	13
1092235	Soil	21.2	22.8	148.2	46	2.5	7.6	1.5	42	4.30	102.2	45.9	2.3	101	0.9	11.1	0.7	73	0.02	0.221	11
1092236	Soil	101.6	93.3	25.5	394	1.3	87.4	4.4	128	3.52	97.6	6.0	0.8	25	0.4	18.0	0.3	366	0.04	0.124	9
1092237	Soil	41.1	15.1	15.9	91	0.7	15.7	2.2	132	2.63	84.0	9.5	0.1	43	0.3	15.1	0.3	215	0.11	0.092	5
1092238	Soil	32.0	12.3	25.8	56	1.2	10.2	1.1	27	1.92	67.4	15.0	0.2	21	<0.1	15.5	0.3	147	0.06	0.060	7
1092239	Soil	27.0	15.1	29.1	72	1.7	14.9	2.6	101	2.21	66.5	14.7	0.5	26	0.2	15.7	0.3	139	0.09	0.069	7
1092240	Soil	2.8	5.1	4.6	17	0.2	4.1	0.9	83	0.53	9.8	2.5	<0.1	8	0.2	1.2	<0.1	17	0.03	0.077	2
1092401	Soil	25.7	40.3	8.6	504	1.0	118.5	8.0	220	1.66	52.4	5.6	0.6	52	5.7	7.6	<0.1	107	1.27	0.136	12
1092402	Soil	39.1	52.6	16.7	503	0.3	146.8	15.0	122	3.62	131.7	3.3	0.4	11	1.2	13.0	0.2	222	0.07	0.149	14
1092403	Soil	7.1	24.4	5.1	157	0.3	67.4	9.1	200	2.36	66.8	2.0	0.3	16	1.2	3.3	<0.1	57	0.12	0.187	14
1092404	Soil	6.9	40.1	12.1	209	0.2	112.8	18.3	346	3.19	95.5	2.7	1.2	9	0.5	5.7	0.1	56	0.06	0.135	21
1092405	Soil	3.9	79.6	20.7	123	1.5	95.6	15.8	196	4.74	19.9	3.0	3.5	7	0.3	6.1	0.2	31	0.16	0.071	26
1092406	Soil	91.9	51.5	8.1	207	<0.1	156.3	7.6	51	2.03	32.5	3.4	0.5	3	0.6	6.1	0.2	55	0.02	0.047	10
1092407	Soil	64.6	67.8	14.0	219	0.2	201.4	8.5	334	3.33	48.8	4.3	1.9	136	2.1	5.0	0.1	74	5.47	0.075	12
1092408	Soil	67.4	58.6	10.9	346	0.2	167.0	8.3	123	2.11	83.9	3.4	1.3	33	1.9	9.8	0.1	45	0.55	0.097	14
1092409	Soil	8.0	27.5	8.3	129	2.0	38.4	5.4	62	1.78	53.6	3.1	0.3	9	<0.1	3.5	0.2	35	0.10	0.070	7
1092410	Soil	10.1	89.5	20.6	364	0.9	94.3	21.5	260	7.65	540.8	7.4	1.2	9	0.1	12.8	0.5	51	0.04	0.120	16
1092411	Soil	59.6	112.7	19.9	495	0.9	375.1	46.3	744	5.79	203.7	7.1	3.9	118	4.2	26.0	0.2	208	0.58	0.365	52
1092412	Soil	5.0	121.5	28.4	297	3.5	101.9	21.6	235	4.77	72.0	8.5	5.3	79	1.1	6.6	0.5	18	0.28	0.229	20
1092413	Soil	8.1	53.3	17.4	153	1.3	63.6	10.3	101	3.45	35.7	3.7	0.9	11	0.2	4.6	0.3	26	0.02	0.108	13
1092414	Soil	11.6	31.4	13.5	189	0.3	47.0	8.7	207	2.68	87.2	4.6	0.6	17	0.3	4.7	0.2	52	0.07	0.127	14
1092415	Soil	14.6	88.7	22.3	366	0.2	65.2	14.2	185	4.97	45.9	2.5	1.5	26	1.1	3.9	0.3	23	0.30	0.459	10
1092416	Soil	5.2	47.9	31.7	87	0.9	35.5	7.6	180	3.44	26.7	3.4	0.3	82	0.2	3.7	0.3	49	0.03	0.128	6
1092417	Soil	3.7	53.4	8.9	42	0.1	28.3	6.4	111	1.96	12.2	2.6	0.3	6	<0.1	2.2	0.2	35	0.02	0.063	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092228	Soil	42	2.79	457	0.006	13	0.52	0.006	0.17	0.4	0.51	2.6	2.4	0.10	2	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092229	Soil	9	0.04	1752	0.001	3	0.79	0.009	0.08	<0.1	0.28	0.6	0.3	0.17	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092230	Soil	16	0.08	1105	0.007	4	0.83	0.002	0.12	<0.1	0.14	2.7	0.2	0.08	3	1.0	0.2	N.A.	N.A.	N.A.	N.A.
1092231	Soil	22	0.08	199	0.003	3	0.93	0.002	0.09	0.1	0.16	2.5	0.6	<0.05	3	2.3	0.2	N.A.	N.A.	N.A.	N.A.
1092232	Soil	39	0.12	495	0.003	5	0.77	0.002	0.10	0.4	0.92	3.2	2.3	<0.05	3	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092233	Soil	102	0.18	798	0.003	6	0.70	0.002	0.14	0.5	6.10	4.0	3.2	<0.05	4	11.7	0.2	N.A.	N.A.	N.A.	N.A.
1092234	Soil	27	0.08	2078	0.002	3	0.49	0.002	0.06	0.4	2.30	1.5	2.9	<0.05	2	7.1	0.2	N.A.	N.A.	N.A.	N.A.
1092235	Soil	18	0.02	78	0.003	4	0.33	0.005	0.53	0.2	5.18	1.7	2.2	1.12	3	10.8	0.2	N.A.	N.A.	N.A.	N.A.
1092236	Soil	28	0.11	209	0.007	4	0.79	0.010	0.11	0.3	0.42	1.7	1.1	0.05	4	8.5	0.3	N.A.	N.A.	N.A.	N.A.
1092237	Soil	12	0.05	368	0.003	3	0.32	0.008	0.14	0.2	1.18	0.1	1.4	0.24	3	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092238	Soil	8	0.01	486	0.002	3	0.27	0.003	0.15	0.2	2.07	0.2	1.5	0.30	2	7.9	0.2	N.A.	N.A.	N.A.	N.A.
1092239	Soil	10	0.08	412	0.006	3	0.35	0.003	0.15	0.2	1.43	0.5	1.4	0.30	2	7.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092240	Soil	4	0.02	105	0.003	<1	0.33	0.016	0.03	<0.1	0.14	<0.1	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092401	Soil	25	0.54	298	0.005	3	0.34	0.020	0.05	0.2	0.73	2.8	0.5	<0.05	<1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092402	Soil	35	0.08	224	0.003	3	0.58	0.003	0.05	0.1	0.13	0.7	0.7	<0.05	2	2.9	0.2	N.A.	N.A.	N.A.	N.A.
1092403	Soil	40	0.08	493	0.002	2	0.59	0.008	0.05	<0.1	0.07	0.9	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092404	Soil	44	0.07	358	0.003	1	0.55	0.005	0.04	<0.1	0.10	2.7	0.2	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092405	Soil	20	0.05	606	0.002	2	0.33	0.001	0.04	<0.1	0.25	5.8	<0.1	<0.05	<1	13.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092406	Soil	14	0.03	149	0.004	2	0.39	0.002	0.03	0.2	0.24	0.9	1.1	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092407	Soil	15	2.69	168	0.005	4	0.28	0.007	0.03	0.1	0.60	4.0	1.3	<0.05	<1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092408	Soil	14	0.07	244	0.003	2	0.33	0.003	0.04	0.2	0.85	3.1	0.8	<0.05	<1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092409	Soil	7	0.07	291	0.002	1	0.37	0.007	0.03	<0.1	0.40	0.4	0.2	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092410	Soil	13	0.04	250	0.004	2	0.65	0.003	0.05	0.1	1.55	1.9	0.3	<0.05	3	2.9	0.4	N.A.	N.A.	N.A.	N.A.
1092411	Soil	74	0.09	2500	0.005	5	0.73	0.003	0.09	0.4	1.64	9.1	1.1	<0.05	2	6.2	0.3	N.A.	N.A.	N.A.	N.A.
1092412	Soil	6	0.05	2430	0.001	<1	0.78	0.002	0.09	<0.1	2.34	5.6	0.3	0.06	<1	4.9	0.3	N.A.	N.A.	N.A.	N.A.
1092413	Soil	8	0.03	876	0.002	1	0.45	0.003	0.05	<0.1	0.32	1.3	0.1	<0.05	1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092414	Soil	17	0.12	206	0.004	1	0.80	0.003	0.06	0.1	0.56	0.8	0.3	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092415	Soil	9	0.06	350	0.005	3	0.61	0.002	0.09	<0.1	0.22	2.9	0.3	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092416	Soil	17	0.11	193	0.004	<1	0.70	0.005	0.08	<0.1	0.07	1.3	0.3	0.11	3	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092417	Soil	10	0.01	77	0.003	<1	0.37	0.005	0.04	<0.1	0.03	1.5	0.1	<0.05	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092231	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092232	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092233	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092234	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092235	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092236	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092237	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092238	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092239	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092240	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092401	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092402	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092403	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092404	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092405	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092406	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092407	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092408	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092409	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092410	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092411	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092412	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092413	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092414	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092415	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092416	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092417	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092228	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092229	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092230	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092231	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092232	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092233	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092234	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092235	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092236	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092237	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092238	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092239	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092240	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092401	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092402	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092403	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092404	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092405	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092406	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092407	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092408	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092409	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092410	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092411	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092412	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092413	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092414	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092415	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092416	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092417	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092418	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092419	Soil	3.4	46.3	12.0	88	0.5	31.7	7.1	155	2.09	15.6	3.0	<0.1	9	0.2	2.5	0.2	33	0.02	0.112	2
1092420	Soil	5.2	74.7	17.4	125	0.7	62.6	13.5	316	3.17	23.5	3.6	0.2	20	0.3	3.0	0.3	44	0.03	0.121	3
1092421	Soil	16.7	26.6	9.4	190	0.7	42.7	4.9	123	1.47	15.8	1.5	0.2	24	1.5	4.7	0.1	79	0.10	0.129	7
1092423	Soil	10.9	90.7	21.1	229	0.9	114.7	13.5	303	3.09	20.9	1.7	5.7	43	2.3	5.9	0.2	51	1.32	0.079	9
1092424	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092425	Soil	11.3	31.9	17.4	165	0.5	41.0	5.4	136	2.29	26.5	1.3	<0.1	28	0.4	4.3	0.3	69	0.03	0.104	7
1092426	Soil	29.4	190.8	27.4	1140	2.4	287.3	25.9	639	4.91	63.1	3.6	1.3	107	7.0	9.6	0.3	112	0.51	0.268	14
1092427	Soil	17.8	36.9	16.3	241	0.3	62.4	6.6	164	2.56	25.3	<0.5	0.2	27	0.4	4.8	0.2	82	0.02	0.130	8
1092428	Soil	16.8	68.7	32.1	199	1.3	68.1	13.0	367	3.68	28.4	1.7	0.4	86	1.0	5.0	0.4	84	0.14	0.149	13
1092429	Soil	5.2	55.3	9.0	86	0.1	50.0	15.8	220	4.11	12.5	1.1	0.4	4	<0.1	1.8	0.3	26	0.01	0.066	14
1092430	Soil	4.9	35.4	10.9	91	<0.1	32.5	9.5	154	2.77	17.7	<0.5	0.2	6	0.1	2.1	0.3	41	0.02	0.050	10
1092431	Soil	5.5	60.2	20.4	101	0.3	57.7	20.9	693	4.98	58.4	3.8	1.0	25	0.2	2.5	0.5	32	0.30	0.128	13
1092432	Soil	4.7	150.5	40.8	257	2.4	181.1	68.2	958	13.06	456.4	22.4	3.1	27	0.4	4.9	1.1	27	0.13	0.111	12
1092433	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092434	Soil	1.7	31.6	14.5	77	1.5	25.8	11.4	332	1.96	14.2	0.7	0.1	35	0.2	1.1	0.2	12	0.25	0.124	4
1092435	Soil	2.9	24.6	11.9	105	1.0	27.8	6.0	192	2.07	11.5	2.2	0.3	34	0.2	0.8	0.2	13	0.23	0.093	3
1092436	Soil	2.1	19.1	9.3	54	1.3	18.0	4.4	95	1.52	10.7	0.7	0.2	26	0.1	0.6	0.1	11	0.16	0.068	4
1092437	Soil	2.3	28.1	8.6	82	0.7	33.2	6.0	146	1.38	75.5	8.0	0.4	26	0.3	1.1	0.1	11	0.27	0.101	4
1092438	Soil	8.6	86.9	37.9	433	1.7	106.9	13.8	231	4.48	84.4	5.4	1.7	59	1.5	3.5	0.4	56	0.50	0.252	15
1092439	Soil	10.7	104.3	30.7	627	1.7	128.2	20.2	294	5.52	44.5	7.3	3.5	54	2.6	4.5	0.4	48	0.41	0.183	17
1092440	Soil	8.8	59.8	21.0	413	2.0	67.3	7.4	289	1.70	21.9	4.1	0.5	50	2.9	2.9	0.2	53	0.42	0.174	10
1092441	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092442	Soil	4.7	25.1	27.7	114	0.2	28.7	7.7	113	2.62	17.9	<0.5	0.3	13	0.1	1.6	0.4	39	0.02	0.129	6
1092443	Soil	2.3	26.2	17.9	75	<0.1	31.8	17.6	512	4.32	21.6	<0.5	1.4	5	<0.1	2.3	0.8	19	0.01	0.063	3
1092444	Soil	9.3	32.5	14.5	140	0.1	36.9	8.4	101	2.63	23.0	<0.5	0.7	7	0.2	3.4	0.4	73	0.01	0.078	8
1092445	Soil	3.0	16.1	16.3	67	<0.1	19.2	7.5	143	3.51	17.0	2.8	0.8	6	<0.1	3.3	0.7	27	0.02	0.073	8
1092446	Soil	14.7	65.3	25.3	543	0.2	47.0	10.6	292	4.14	44.2	<0.5	0.2	20	0.7	9.7	0.3	68	0.23	0.309	8
1092447	Soil	9.5	157.2	21.0	249	0.2	66.7	16.3	132	4.52	32.0	<0.5	0.2	4	0.1	4.6	0.3	62	0.01	0.085	6
1092448	Soil	2.5	70.8	20.8	329	0.6	37.5	4.4	144	2.32	20.1	2.2	1.2	21	1.4	3.2	0.2	19	0.22	0.079	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092418	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.4	62.3	12.5	80
1092419	Soil	12	0.02	66	0.002	<1	0.40	0.008	0.04	<0.1	0.07	0.8	0.2	0.06	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092420	Soil	14	0.05	137	0.003	<1	0.63	0.007	0.05	<0.1	0.06	1.8	0.2	0.06	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092421	Soil	14	0.05	593	0.002	2	0.60	0.012	0.04	<0.1	0.29	0.7	0.5	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092423	Soil	21	0.64	336	0.001	2	0.21	0.002	0.06	<0.1	0.56	6.3	0.2	<0.05	<1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092424	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	44.0	168.6	36.5	829
1092425	Soil	12	0.04	153	0.004	<1	0.52	0.006	0.06	0.1	0.04	0.2	0.5	0.06	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092426	Soil	22	0.07	506	0.004	<1	0.60	0.003	0.10	0.2	1.07	4.9	1.2	0.13	1	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092427	Soil	13	0.02	158	0.003	<1	0.35	0.004	0.07	0.2	0.04	0.4	0.4	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092428	Soil	14	0.04	702	0.004	<1	0.30	0.002	0.12	0.2	0.18	1.6	0.9	0.14	1	2.1	0.4	N.A.	N.A.	N.A.	N.A.
1092429	Soil	8	0.03	85	0.003	<1	0.37	0.004	0.06	0.1	0.08	1.1	<0.1	<0.05	2	0.8	0.3	N.A.	N.A.	N.A.	N.A.
1092430	Soil	11	0.03	134	0.005	<1	0.40	0.003	0.05	0.1	0.02	0.6	0.1	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092431	Soil	11	0.12	1835	0.005	<1	0.64	0.004	0.08	<0.1	0.07	4.5	0.2	0.08	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092432	Soil	13	0.09	1210	0.005	1	0.81	0.004	0.13	<0.1	0.16	9.8	0.4	0.12	1	2.5	0.3	N.A.	N.A.	N.A.	N.A.
1092433	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.8	56.6	21.8	135
1092434	Soil	7	0.07	1568	0.008	2	0.71	0.022	0.06	<0.1	0.14	0.9	0.2	0.08	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092435	Soil	7	0.06	1808	0.005	2	0.43	0.016	0.05	<0.1	0.15	1.2	0.1	0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092436	Soil	5	0.05	2850	0.006	2	0.53	0.019	0.04	<0.1	0.20	1.1	<0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092437	Soil	4	0.06	1290	0.009	2	0.50	0.023	0.04	<0.1	0.17	1.3	<0.1	0.06	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092438	Soil	13	0.11	1817	0.003	4	0.59	0.005	0.10	<0.1	0.63	3.8	0.2	<0.05	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092439	Soil	12	0.07	4224	0.003	4	0.68	0.002	0.13	<0.1	0.61	5.4	0.4	<0.05	1	4.2	0.2	N.A.	N.A.	N.A.	N.A.
1092440	Soil	11	0.05	1185	0.004	2	0.63	0.011	0.07	0.1	0.48	1.4	0.4	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092441	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.9	30.0	30.5	109
1092442	Soil	10	0.04	141	0.002	1	0.62	0.004	0.06	<0.1	0.03	0.3	0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092443	Soil	10	0.11	122	0.004	2	0.65	0.008	0.06	<0.1	0.02	3.1	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092444	Soil	13	0.04	153	0.006	2	0.40	0.003	0.09	0.2	0.03	1.6	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092445	Soil	9	0.05	92	0.005	2	0.33	0.002	0.08	<0.1	0.02	1.8	<0.1	<0.05	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092446	Soil	12	0.03	201	0.005	2	0.45	0.006	0.07	<0.1	0.04	0.8	0.3	0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092447	Soil	10	0.05	96	0.004	3	0.46	0.003	0.09	<0.1	0.02	1.1	0.2	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092448	Soil	10	0.05	192	0.001	3	0.27	<0.001	0.06	<0.1	0.29	2.9	0.2	<0.05	<1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092418	Soil		0.2	53.1	11.4	121	2.70	17.8	16.2	0.2	3	0.2	1.7	0.3	53	0.03	0.090	4	20	0.02	78	0.002
1092419	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092420	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092421	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092423	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092424	Soil		3.6	209.6	18.1	499	4.33	62.4	5.4	2.3	84	11.5	15.3	0.3	364	0.77	0.304	16	49	0.16	1167	0.003
1092425	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092426	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092427	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092428	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092429	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092430	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092431	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092432	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092433	Soil		1.7	50.5	20.8	537	4.07	31.9	4.8	0.3	45	0.2	1.7	0.4	22	0.37	0.168	6	10	0.09	2545	0.005
1092434	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092435	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092436	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092437	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092438	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092439	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092440	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092441	Soil		0.2	30.2	13.2	198	3.51	14.7	0.9	0.8	12	0.3	0.4	0.5	20	0.03	0.081	8	9	0.04	457	0.001
1092442	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092443	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092444	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092445	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092446	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092447	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092448	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092418	Soil	<20	0.43	0.004	0.08	<0.1	0.06	1.1	0.2	0.05	2	1.2	0.2
1092419	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092420	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092421	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092423	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092424	Soil	<20	0.72	0.006	0.15	0.1	1.05	6.1	0.9	0.06	2	7.0	0.3
1092425	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092426	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092427	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092428	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092429	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092430	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092431	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092432	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092433	Soil	<20	0.72	0.018	0.11	<0.1	0.16	1.9	0.2	0.19	1	2.6	<0.2
1092434	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092435	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092436	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092437	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092438	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092439	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092440	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092441	Soil	<20	0.56	0.004	0.09	<0.1	0.06	1.2	0.1	<0.05	2	0.9	<0.2
1092442	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092443	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092444	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092445	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092446	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092447	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092448	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092449	Soil	12.8	67.1	23.1	575	2.3	107.4	12.3	128	4.30	44.2	7.6	2.3	50	2.2	4.6	0.4	27	0.72	0.114	9
1092450	Soil	10.4	59.3	21.4	411	2.0	103.3	8.6	263	2.48	22.7	4.2	2.4	82	4.0	3.1	0.3	37	0.58	0.157	12
1092451	Soil	19.1	81.7	18.4	725	1.9	124.0	12.7	193	3.90	35.3	1.2	4.0	58	8.4	17.7	0.2	101	1.98	0.101	10
1092452	Soil	7.3	36.9	11.5	261	0.5	51.1	7.6	130	2.15	16.5	1.9	1.5	34	3.2	5.5	0.2	46	0.60	0.096	7
1092453	Soil	60.2	58.6	12.8	114	0.2	120.5	9.1	229	2.62	17.9	<0.5	2.1	133	1.2	1.8	0.1	27	4.84	0.100	11
1092454	Soil	7.8	42.9	18.4	196	0.2	47.5	9.1	166	3.67	29.8	1.9	0.3	10	0.5	3.4	0.3	57	0.03	0.174	7
1092455	Soil	13.1	40.8	13.2	212	0.4	57.6	10.1	256	2.92	32.5	0.5	0.2	10	0.5	4.3	0.3	74	0.04	0.163	8
1092456	Soil	9.2	47.6	14.9	223	0.2	58.3	10.7	189	3.50	27.0	1.1	0.1	14	0.6	3.2	0.3	59	0.05	0.212	6
1092457	Soil	37.5	81.0	25.0	457	0.8	120.0	18.0	301	5.03	85.7	3.1	0.9	26	1.2	10.9	0.4	170	0.10	0.179	16
1092458	Soil	3.4	25.1	14.3	94	0.2	18.1	4.7	225	2.06	49.5	<0.5	0.4	10	<0.1	1.9	0.3	44	0.04	0.091	5
1092459	Soil	5.9	40.4	19.9	102	0.2	36.1	9.0	172	3.17	254.7	1.9	0.6	11	0.2	3.8	0.4	67	0.02	0.078	5
1092460	Soil	29.0	61.0	25.9	360	0.5	80.7	12.6	292	4.35	290.0	2.8	1.4	10	0.7	10.4	0.4	210	0.04	0.078	8
1092461	Soil	1.0	7.4	1.5	16	<0.1	4.4	0.7	30	0.34	13.7	<0.5	0.1	14	0.1	0.4	<0.1	13	0.15	0.031	2
1092462	Soil	60.6	87.8	19.0	939	1.2	170.4	8.4	150	2.91	93.7	2.5	1.9	69	9.6	18.3	0.3	324	0.82	0.151	12
1092463	Soil	9.1	50.1	17.8	244	0.3	57.5	9.9	254	3.39	18.4	0.8	0.6	13	0.5	3.7	0.3	66	0.09	0.159	9
1092464	Soil	10.6	51.6	22.6	226	0.3	64.9	12.0	205	4.06	25.4	1.6	0.2	28	0.5	3.5	0.4	63	0.16	0.230	9
1092465	Soil	12.0	62.1	29.6	947	0.6	166.7	21.7	660	7.24	51.9	4.4	1.6	8	2.2	3.2	0.4	22	0.05	0.112	20
1092466	Soil	6.8	112.4	33.7	476	1.5	142.2	9.9	117	3.26	16.6	5.3	2.1	93	1.0	4.3	0.4	114	1.43	0.547	17
1092467	Soil	33.5	61.6	46.0	330	1.0	87.1	5.3	112	3.07	58.8	1.2	0.2	238	0.6	10.6	0.4	208	0.09	0.188	19
1092468	Soil	62.8	66.9	66.5	416	7.3	103.6	6.0	50	4.13	83.8	1.4	0.5	239	0.9	19.5	0.5	354	0.09	0.359	13
1092469	Soil	45.6	310.6	36.8	863	5.7	327.0	9.2	165	4.47	144.7	<0.5	2.7	456	6.9	21.1	0.5	363	1.29	0.931	24
1092470	Soil	63.2	161.2	32.6	673	4.4	229.9	11.2	204	4.39	98.7	2.4	2.1	177	8.4	17.9	0.5	203	1.04	0.369	18
1092471	Soil	33.7	114.3	17.4	736	5.2	218.0	6.6	84	2.53	50.9	5.5	1.2	105	7.4	10.5	0.4	112	1.00	0.198	12
1092472	Soil	43.5	98.7	21.3	502	4.5	132.7	6.6	83	3.22	58.7	4.7	0.8	87	4.9	12.0	0.3	139	0.09	0.194	15
1092473	Soil	37.1	75.4	21.4	405	3.4	107.6	5.5	44	2.76	50.5	<0.5	0.7	77	5.1	9.6	0.4	118	0.07	0.184	13
1092474	Soil	19.3	132.1	40.4	269	3.0	91.2	6.7	121	3.61	44.4	4.0	1.0	155	1.4	8.2	0.4	172	0.50	0.632	22
1092475	Soil	3.4	18.4	6.7	54	<0.1	18.3	4.2	165	1.36	30.2	<0.5	0.2	9	<0.1	1.3	0.2	24	0.02	0.076	6
1092476	Soil	4.1	38.6	12.8	110	0.2	40.6	11.8	584	3.17	292.4	0.6	0.3	13	0.1	3.3	0.3	34	0.01	0.132	11
1092477	Soil	4.0	58.2	19.6	143	0.5	48.1	13.4	172	4.41	99.5	1.0	0.8	50	0.3	2.8	0.4	34	0.03	0.226	12
1092478	Soil	4.8	64.8	26.3	169	0.6	67.3	20.0	337	5.86	62.2	3.5	1.1	22	0.3	2.8	0.4	47	0.02	0.221	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092449	Soil	11	0.10	1531	0.003	4	0.68	0.009	0.08	<0.1	0.47	4.7	0.3	0.09	1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092450	Soil	11	0.09	4355	0.003	2	0.87	0.007	0.12	<0.1	0.50	3.4	0.3	0.06	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092451	Soil	20	0.86	276	0.003	4	0.27	0.004	0.07	<0.1	0.43	5.6	0.2	0.05	<1	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092452	Soil	10	0.07	365	0.004	1	0.46	0.005	0.05	<0.1	0.17	2.4	0.1	0.06	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092453	Soil	12	2.39	212	0.005	2	0.26	0.009	0.04	0.1	0.24	3.9	1.3	<0.05	<1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092454	Soil	20	0.06	372	0.003	<1	0.78	0.003	0.06	<0.1	0.05	0.5	0.2	0.08	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092455	Soil	15	0.05	316	0.004	1	0.47	0.008	0.09	0.1	0.06	0.7	0.3	0.11	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092456	Soil	16	0.04	544	0.002	2	0.74	0.005	0.09	<0.1	0.05	0.3	0.2	0.13	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092457	Soil	23	0.08	1757	0.004	2	0.82	0.002	0.10	0.1	0.17	2.3	0.6	0.07	2	4.2	0.2	N.A.	N.A.	N.A.	N.A.
1092458	Soil	13	0.04	258	0.006	<1	0.51	0.003	0.09	<0.1	0.05	1.0	0.1	0.06	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092459	Soil	18	0.07	121	0.003	<1	0.74	0.003	0.06	0.1	0.06	1.4	0.2	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092460	Soil	26	0.08	470	0.004	<1	0.87	0.003	0.08	0.1	0.11	2.3	0.5	<0.05	4	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092461	Soil	2	0.03	100	0.017	<1	0.49	0.060	0.04	<0.1	0.06	0.8	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092462	Soil	31	0.21	684	0.005	4	0.72	0.006	0.09	0.1	0.86	4.8	0.9	<0.05	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092463	Soil	19	0.08	209	0.004	1	0.71	0.006	0.07	<0.1	0.09	0.7	0.2	0.07	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092464	Soil	18	0.11	525	0.003	2	0.58	0.004	0.11	<0.1	0.06	0.4	0.2	0.10	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092465	Soil	12	0.06	443	0.002	2	0.53	0.003	0.08	<0.1	0.86	4.8	0.2	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092466	Soil	21	0.06	584	0.005	7	0.62	0.004	0.19	<0.1	0.47	4.0	0.2	0.25	2	7.0	0.3	N.A.	N.A.	N.A.	N.A.
1092467	Soil	21	0.03	332	0.005	2	0.41	0.003	0.12	0.2	0.07	0.4	0.4	0.17	3	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092468	Soil	20	0.05	332	0.009	3	0.62	0.002	0.09	0.5	0.30	1.0	0.7	0.16	4	7.6	0.3	N.A.	N.A.	N.A.	N.A.
1092469	Soil	34	0.20	917	0.007	8	0.90	0.004	0.21	0.6	3.37	5.6	0.8	0.27	2	12.3	0.6	N.A.	N.A.	N.A.	N.A.
1092470	Soil	20	0.05	443	0.003	5	0.42	0.003	0.20	0.7	1.63	3.5	2.8	0.38	1	6.0	0.3	N.A.	N.A.	N.A.	N.A.
1092471	Soil	13	0.05	414	0.002	5	0.37	0.003	0.10	0.5	2.36	3.2	1.5	0.14	<1	3.5	0.3	N.A.	N.A.	N.A.	N.A.
1092472	Soil	13	0.03	494	0.003	3	0.41	0.002	0.15	0.6	1.04	1.8	2.1	0.27	<1	4.0	0.3	N.A.	N.A.	N.A.	N.A.
1092473	Soil	10	0.03	462	0.002	2	0.36	0.002	0.13	0.5	0.86	1.4	1.9	0.23	1	4.2	0.3	N.A.	N.A.	N.A.	N.A.
1092474	Soil	26	0.07	709	0.006	6	0.71	0.005	0.24	0.5	0.74	2.1	1.4	0.50	2	5.0	0.4	N.A.	N.A.	N.A.	N.A.
1092475	Soil	9	0.03	104	0.004	4	0.44	0.012	0.06	<0.1	0.03	0.7	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092476	Soil	15	0.05	450	0.004	6	0.63	0.005	0.10	0.1	0.07	1.6	0.1	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092477	Soil	11	0.05	499	0.004	3	0.56	0.004	0.09	0.1	0.07	1.5	0.2	0.10	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092478	Soil	17	0.06	615	0.008	2	1.15	0.004	0.07	<0.1	0.10	1.9	0.2	0.08	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092449	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092450	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092451	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092452	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092453	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092454	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092455	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092456	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092457	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092458	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092459	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092460	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092461	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092462	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092463	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092464	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092465	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092466	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092467	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092468	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092469	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092470	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092471	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092472	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092473	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092474	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092475	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092476	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092477	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092478	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092449	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092450	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092451	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092452	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092453	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092454	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092455	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092456	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092457	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092458	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092459	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092460	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092461	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092462	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092463	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092464	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092465	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092466	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092467	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092468	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092469	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092470	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092471	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092472	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092473	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092474	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092475	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092476	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092477	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092478	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092479	Soil	3.6	23.4	6.6	66	<0.1	23.4	6.7	198	1.99	31.1	<0.5	0.3	10	<0.1	1.6	0.2	33	0.01	0.115	9
1092480	Soil	5.1	46.4	11.7	111	<0.1	54.4	18.8	254	5.58	49.9	3.5	0.5	19	0.2	2.9	0.4	41	0.09	0.104	14
1092481	Soil	12.0	86.1	76.3	839	2.8	143.8	27.3	757	5.77	173.9	9.6	2.0	37	1.0	11.8	0.3	92	0.35	0.133	9
1092482	Soil	9.0	52.8	28.4	177	0.7	55.1	7.7	201	2.69	25.8	4.4	0.7	54	0.6	3.6	0.3	42	0.26	0.228	12
1092483	Soil	6.8	29.2	13.3	113	0.3	39.3	8.7	553	2.13	14.2	1.6	0.4	38	0.4	1.9	0.2	25	0.34	0.190	9
1092484	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092485	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092486	Soil	10.8	60.0	31.4	145	1.0	82.2	26.2	719	5.42	37.4	12.2	2.5	33	0.2	4.3	0.4	21	0.32	0.066	12
1092487	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092488	Soil	12.2	106.2	35.6	323	1.1	144.0	35.7	1041	5.77	69.4	5.9	4.5	64	0.8	6.9	0.5	33	0.66	0.205	20
1092489	Soil	9.8	43.8	18.7	142	1.1	63.0	11.5	332	2.94	34.1	5.3	1.7	40	0.5	5.2	0.3	23	0.36	0.077	7
1092490	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092491	Soil	11.8	102.5	24.9	399	2.4	128.1	14.0	481	4.47	49.2	2.8	5.3	220	4.2	11.7	0.2	98	4.96	0.162	9
1092492	Soil	24.3	86.3	27.8	849	2.0	130.8	13.0	382	4.30	46.7	<0.5	5.2	110	13.1	16.7	0.2	184	2.35	0.157	10
1092493	Soil	16.7	61.3	17.6	881	1.5	105.2	9.7	387	3.76	45.9	<0.5	3.6	213	16.9	14.6	0.2	115	4.54	0.094	7
1092494	Soil	9.6	91.3	20.9	753	3.9	129.7	10.1	695	4.53	24.6	1.2	3.7	218	7.9	11.8	0.2	68	4.66	0.105	8
1092495	Soil	14.7	57.2	16.1	611	1.3	91.2	8.5	236	2.84	30.5	<0.5	2.4	71	11.1	10.1	0.2	99	1.47	0.116	8
1092496	Soil	26.3	80.9	18.8	883	1.8	118.0	10.1	206	3.71	47.2	<0.5	4.5	42	10.3	16.7	0.2	163	0.53	0.137	11
1092497	Soil	43.3	52.2	10.9	825	0.6	113.5	8.5	172	1.88	47.8	<0.5	3.1	88	7.8	17.7	0.1	164	3.10	0.097	11
1092498	Soil	33.4	23.0	8.9	404	0.1	57.7	4.9	66	1.91	27.6	1.2	0.3	6	1.1	11.1	0.2	170	0.02	0.102	10
1092499	Soil	35.6	35.9	10.8	590	0.2	77.8	7.1	51	2.59	47.5	<0.5	0.4	7	0.8	12.9	0.2	218	0.04	0.064	10
1092500	Soil	44.7	49.1	15.3	539	0.6	109.3	8.7	248	2.59	58.8	2.3	0.6	16	2.1	15.2	0.2	245	0.08	0.119	14
1092601	Soil	77.5	104.5	12.3	912	0.8	240.2	9.8	230	2.07	66.1	1.2	0.9	144	8.2	18.5	0.1	365	5.19	0.125	15
1092602	Soil	76.2	78.8	10.8	390	0.4	207.8	9.3	189	2.06	61.9	1.0	1.5	116	4.1	10.2	0.1	147	4.54	0.112	12
1092603	Soil	49.2	47.5	6.0	104	0.2	145.3	7.5	148	1.72	55.8	1.5	2.6	188	1.7	5.0	<0.1	41	8.39	0.045	8
1092604	Soil	67.6	118.9	9.6	956	1.0	255.8	12.2	199	2.12	79.7	3.0	2.2	308	8.4	22.0	0.1	566	11.45	0.127	16
1092605	Soil	87.3	129.0	10.8	1342	1.5	267.5	7.6	156	1.77	83.2	1.8	1.5	290	10.2	28.0	0.1	629	10.32	0.101	12
1092606	Soil	96.4	149.4	13.0	1664	1.8	288.9	7.9	156	1.59	89.3	2.2	1.5	257	12.9	31.1	0.1	887	8.73	0.116	15
1092607	Soil	69.2	113.1	9.9	909	1.3	223.5	7.2	178	1.73	93.5	1.5	1.1	204	7.6	23.0	0.1	619	8.16	0.095	14
1092608	Soil	65.0	98.9	10.6	645	1.0	237.4	8.9	287	1.80	80.9	1.5	0.7	164	6.3	17.7	0.1	461	6.66	0.092	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092479	Soil		9	0.03	224	0.004	2	0.44	0.007	0.06	0.1	0.03	0.8	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092480	Soil		14	0.11	1264	0.008	5	0.76	0.003	0.09	0.1	0.03	2.0	0.1	<0.05	3	<0.5	0.2	N.A.	N.A.	N.A.	N.A.
1092481	Soil		19	0.10	556	0.005	5	0.60	0.005	0.12	<0.1	1.31	6.9	0.3	<0.05	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092482	Soil		11	0.07	870	0.004	5	0.58	0.005	0.13	<0.1	0.31	1.7	0.2	0.09	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092483	Soil		8	0.07	636	0.003	5	0.47	0.011	0.08	<0.1	0.13	1.1	0.2	0.07	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092484	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	8.6	45.0	25.7	159
1092485	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.5	54.7	28.7	123
1092486	Soil		8	0.13	715	0.003	5	0.46	0.002	0.13	<0.1	0.33	5.6	0.3	0.07	1	1.1	0.2	N.A.	N.A.	N.A.	N.A.
1092487	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.1	212.7	40.8	297
1092488	Soil		14	0.18	890	0.003	9	0.49	0.002	0.17	<0.1	0.62	6.5	0.4	0.11	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092489	Soil		7	0.10	837	0.003	4	0.36	0.007	0.09	<0.1	0.64	3.8	0.4	0.05	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092490	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	11.5	108.0	45.1	547
1092491	Soil		23	2.40	784	0.006	7	0.35	0.007	0.11	<0.1	0.65	5.4	0.6	0.06	<1	10.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092492	Soil		22	1.15	626	0.005	5	0.36	0.006	0.10	<0.1	0.53	5.4	0.3	<0.05	1	9.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092493	Soil		20	2.32	1013	0.003	5	0.26	0.009	0.07	<0.1	0.43	4.9	0.3	<0.05	<1	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092494	Soil		20	2.39	1703	0.006	4	0.35	0.015	0.06	<0.1	0.71	5.9	0.3	<0.05	<1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092495	Soil		15	0.54	515	0.005	4	0.39	0.011	0.07	<0.1	0.46	3.9	0.2	<0.05	<1	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092496	Soil		21	0.11	483	0.003	5	0.38	0.002	0.08	<0.1	0.74	6.1	0.3	<0.05	<1	6.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092497	Soil		13	1.59	325	0.003	5	0.25	0.004	0.07	<0.1	0.51	3.5	0.5	<0.05	<1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092498	Soil		15	0.04	193	0.005	3	0.47	0.003	0.07	<0.1	0.06	0.9	0.3	<0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092499	Soil		16	0.06	142	0.004	3	0.39	0.002	0.07	<0.1	0.04	0.7	0.4	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092500	Soil		23	0.07	400	0.004	3	0.51	0.004	0.08	0.2	0.17	1.2	0.8	<0.05	2	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092601	Soil		26	2.28	364	0.004	9	0.44	0.007	0.13	0.3	0.22	2.6	2.3	<0.05	1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092602	Soil		19	2.30	407	0.003	6	0.37	0.007	0.09	0.3	0.26	3.3	1.6	<0.05	<1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092603	Soil		11	3.66	196	0.002	5	0.17	0.006	0.06	0.2	0.27	3.0	1.0	0.11	<1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092604	Soil		38	3.03	354	0.005	12	0.44	0.007	0.16	0.3	0.73	3.2	3.5	0.14	1	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092605	Soil		33	2.32	310	0.004	8	0.40	0.006	0.14	0.3	0.72	2.8	4.3	0.17	1	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092606	Soil		45	1.74	324	0.005	11	0.51	0.005	0.17	0.4	0.56	3.0	4.8	0.13	2	6.2	0.2	N.A.	N.A.	N.A.	N.A.
1092607	Soil		35	2.46	420	0.005	9	0.44	0.007	0.13	0.4	0.62	2.6	4.7	0.15	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092608	Soil		35	2.64	353	0.005	11	0.48	0.008	0.14	0.3	0.48	2.8	4.6	0.16	1	4.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092479	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092480	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092481	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092482	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092483	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092484	Soil		0.4	59.8	16.4	430	4.06	27.7	3.2	1.0	21	0.3	2.4	0.3	22	0.19	0.093	10	12	0.08	910	0.002
1092485	Soil		0.3	63.4	32.8	1314	4.37	30.1	2.9	1.6	53	0.3	2.7	0.4	25	0.62	0.153	10	16	0.15	1920	0.003
1092486	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092487	Soil		1.6	210.9	76.3	2167	11.57	44.9	7.7	7.0	88	0.3	2.3	0.9	19	2.21	0.057	32	10	0.61	541	0.001
1092488	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092489	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092490	Soil		1.5	196.2	54.0	2345	7.44	50.6	11.6	2.5	27	1.2	3.7	0.6	25	0.24	0.100	26	14	0.09	683	0.002
1092491	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092492	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092493	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092494	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092495	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092496	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092497	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092498	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092499	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092500	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092601	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092602	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092603	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092604	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092605	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092606	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092607	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092608	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092479	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092480	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092481	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092482	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092483	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092484	Soil	<20	0.50	0.005	0.12	0.2	0.11	3.5	0.2	0.07	1	1.5	<0.2
1092485	Soil	<20	0.56	0.005	0.13	0.2	0.12	6.0	0.3	0.16	1	1.2	<0.2
1092486	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092487	Soil	<20	0.31	0.003	0.13	<0.1	0.29	9.4	0.3	0.17	<1	2.5	0.6
1092488	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092489	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092490	Soil	<20	0.56	0.004	0.14	<0.1	0.45	7.6	0.5	0.10	2	2.3	0.4
1092491	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092492	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092493	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092494	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092495	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092496	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092497	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092498	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092499	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092500	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092601	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092602	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092603	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092604	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092605	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092606	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092607	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092608	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092609	Soil		73.0	107.0	13.1	898	0.8	250.2	11.2	243	2.09	382.0	8.0	2.2	83	7.5	27.9	0.2	457	3.06	0.143	19
1092610	Soil		77.3	160.7	15.7	1464	2.2	255.2	8.6	139	2.22	384.4	17.3	2.4	99	21.0	27.8	0.2	932	3.32	0.165	22
1092611	Soil		79.5	92.0	18.5	1395	1.6	153.5	6.7	205	1.57	86.1	3.6	1.1	75	19.1	20.9	0.1	391	2.23	0.100	17
1092612	Soil		99.3	109.5	17.6	2208	2.8	229.0	8.8	129	2.23	87.5	3.8	2.0	106	17.4	24.1	0.2	477	3.60	0.142	17
1092613	Soil		58.5	156.2	14.5	1442	2.7	208.6	5.0	143	1.75	79.3	5.2	1.9	217	19.0	20.9	0.2	510	7.97	0.271	18
1092614	Soil		75.2	149.2	12.9	1645	3.8	225.5	5.5	110	1.95	96.2	3.1	2.9	129	33.3	40.1	0.2	771	7.03	0.120	13
1092615	Soil		99.6	134.1	14.4	1254	2.2	218.0	3.8	109	1.21	102.0	1.7	1.3	128	22.5	28.2	0.1	994	5.06	0.114	18
1092616	Soil		130.7	96.9	13.5	1034	3.9	291.9	8.1	43	2.53	124.9	8.3	1.3	76	23.2	41.1	0.2	892	0.53	0.164	21
1092617	Soil		88.7	134.9	13.4	2193	4.1	243.4	4.6	114	1.90	106.1	4.9	1.7	100	38.8	32.7	0.2	660	4.92	0.138	16
1092618	Soil		62.3	70.6	39.7	448	2.4	94.2	4.8	35	2.68	59.9	3.4	0.2	22	4.1	29.2	0.1	1074	0.09	0.145	16
1092619	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092620	Soil		18.5	142.9	17.7	388	0.5	752.2	100.6	688	6.91	57.4	1.6	18.2	218	2.3	2.9	0.1	239	2.59	0.863	111
1092621	Soil		14.7	152.4	19.7	245	0.5	801.9	119.7	1047	7.24	263.2	5.5	21.2	295	1.2	5.5	0.1	202	3.87	0.931	114
1092622	Soil		14.5	154.9	21.5	270	0.3	797.9	117.7	1306	9.39	172.8	2.7	21.6	311	2.0	6.6	<0.1	176	4.29	0.833	96
1092623	Soil		12.4	146.4	28.1	158	0.3	832.2	117.2	1194	11.17	139.3	1.6	22.0	198	1.6	6.8	<0.1	134	3.97	0.783	98
1092624	Soil		12.8	126.6	33.0	68	0.3	781.9	110.9	891	11.88	83.7	2.1	18.6	150	0.6	4.2	<0.1	96	4.11	0.668	79
1092625	Soil		10.9	95.5	13.7	197	0.4	517.0	71.7	921	6.59	666.5	5.8	11.1	146	1.0	9.2	<0.1	172	1.90	0.493	58
1092626	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092627	Soil		8.3	147.9	15.9	241	0.4	588.7	104.6	1420	9.42	1939	18.1	15.2	204	1.6	19.1	<0.1	161	3.10	0.680	120
1092628	Soil		5.3	136.4	12.9	226	0.2	506.6	91.3	1670	8.93	1261	5.6	13.3	156	0.8	15.5	<0.1	149	2.31	0.550	135
1092629	Soil		9.8	116.1	12.7	247	0.3	477.2	78.6	1096	8.55	763.6	6.7	8.8	95	1.0	9.0	<0.1	161	1.17	0.373	90
1092630	Soil		47.9	87.8	14.2	581	1.1	244.1	26.3	354	4.25	52.2	2.3	7.4	39	4.1	14.2	0.2	237	0.44	0.186	29
1092631	Soil		45.2	73.3	12.2	722	0.8	157.2	19.1	404	3.30	72.6	3.0	3.9	33	6.2	14.0	0.2	195	0.37	0.135	25
1092632	Soil		25.4	124.2	13.0	355	0.6	427.2	71.1	994	8.19	353.5	6.5	10.2	120	2.3	14.9	0.1	279	1.11	0.436	89
1092633	Soil		19.8	126.2	13.8	384	0.5	418.7	60.4	1146	6.80	283.7	2.9	15.6	140	3.6	8.2	0.1	189	1.12	0.532	88
1092634	Soil		4.6	120.1	27.5	337	3.3	123.8	18.8	272	5.85	103.2	5.3	6.3	23	2.0	4.4	0.5	26	0.19	0.097	26
1092635	Soil		18.7	83.6	12.8	387	1.0	158.8	21.6	394	3.63	94.4	3.8	7.3	60	3.0	5.7	0.2	84	0.45	0.210	30
1092636	Soil		7.6	46.4	15.8	202	2.8	123.9	14.9	206	2.82	63.0	6.6	1.1	62	0.9	3.8	0.3	42	0.45	0.181	19
1092637	Soil		23.2	60.3	19.7	348	0.3	88.4	14.3	376	4.09	65.7	8.2	2.3	19	0.9	8.1	0.3	119	0.06	0.140	16
1092638	Soil		13.6	34.0	7.8	179	0.2	50.1	7.6	110	2.63	30.0	1.7	0.3	7	0.2	4.0	0.2	76	0.02	0.068	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092609	Soil	42	1.30	433	0.008	13	0.62	0.006	0.17	0.6	1.76	5.2	2.8	0.19	2	5.3	0.2	N.A.	N.A.	N.A.	N.A.
1092610	Soil	72	1.24	509	0.009	11	0.79	0.006	0.17	0.4	4.84	6.2	2.2	0.12	3	8.1	0.2	N.A.	N.A.	N.A.	N.A.
1092611	Soil	28	0.76	255	0.005	7	0.50	0.006	0.11	0.3	0.70	3.2	1.4	0.12	1	8.3	0.2	N.A.	N.A.	N.A.	N.A.
1092612	Soil	34	1.47	245	0.006	6	0.54	0.005	0.11	0.3	1.50	4.7	3.1	0.11	2	8.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092613	Soil	68	2.99	458	0.007	12	0.63	0.008	0.17	0.3	1.36	5.3	2.5	0.12	2	8.6	0.2	N.A.	N.A.	N.A.	N.A.
1092614	Soil	65	3.16	631	0.005	11	0.56	0.006	0.19	0.2	1.28	3.8	2.4	0.12	2	11.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092615	Soil	49	1.59	465	0.007	14	0.54	0.006	0.20	0.4	1.11	2.9	2.7	0.18	2	12.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092616	Soil	55	0.11	2903	0.020	7	0.64	0.003	0.14	0.6	2.39	3.2	4.6	0.07	2	15.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092617	Soil	48	2.46	545	0.004	11	0.47	0.006	0.14	0.7	2.18	3.5	1.4	0.08	1	8.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092618	Soil	55	0.05	625	0.003	5	0.50	0.004	0.12	0.4	0.86	0.6	2.4	0.16	3	8.4	0.2	N.A.	N.A.	N.A.	N.A.
1092619	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	19.4	142.8	23.3	384
1092620	Soil	255	0.24	2638	0.008	41	1.52	0.008	0.37	0.2	4.77	23.8	0.7	<0.05	5	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092621	Soil	249	0.32	2354	0.008	31	1.35	0.008	0.35	0.2	3.06	26.2	0.6	<0.05	5	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092622	Soil	259	0.77	2128	0.008	41	1.30	0.008	0.37	0.1	2.88	23.5	0.7	0.40	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092623	Soil	237	0.52	1275	0.008	35	1.20	0.007	0.34	0.2	4.98	25.1	0.8	0.69	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092624	Soil	208	0.23	253	0.006	28	1.04	0.007	0.26	0.2	8.93	20.0	0.8	0.59	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092625	Soil	190	0.36	3225	0.004	13	1.38	0.015	0.15	0.1	2.29	16.7	0.6	<0.05	4	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092626	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	12.2	100.3	14.1	205
1092627	Soil	272	1.53	2938	0.006	22	1.54	0.008	0.21	0.2	1.56	24.2	0.6	<0.05	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092628	Soil	268	2.27	1779	0.007	16	1.84	0.010	0.15	0.2	0.77	26.9	0.4	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092629	Soil	222	1.14	2148	0.005	9	1.60	0.013	0.11	0.1	0.50	23.4	0.4	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092630	Soil	52	0.11	1173	0.002	8	0.52	0.002	0.14	0.3	1.35	8.1	0.7	<0.05	2	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092631	Soil	41	0.19	751	0.004	6	0.55	0.002	0.09	0.2	2.63	6.5	0.3	<0.05	1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092632	Soil	273	1.62	2158	0.007	17	1.92	0.004	0.14	0.3	0.75	23.9	0.8	<0.05	6	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092633	Soil	165	0.28	3980	0.004	13	1.25	0.003	0.15	0.2	1.97	19.5	0.5	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092634	Soil	17	0.06	2431	0.001	4	0.55	0.002	0.12	<0.1	5.22	10.0	0.3	<0.05	<1	4.4	0.3	N.A.	N.A.	N.A.	N.A.
1092635	Soil	32	0.11	3598	0.005	7	0.55	0.002	0.12	<0.1	1.50	6.2	0.3	<0.05	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092636	Soil	23	0.09	1640	0.004	4	0.49	0.012	0.06	0.1	1.71	2.7	0.2	0.07	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092637	Soil	30	0.12	537	0.006	2	0.92	0.002	0.07	0.2	1.43	3.2	0.5	<0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092638	Soil	12	0.04	354	0.004	<1	0.62	0.004	0.04	0.2	0.12	0.6	0.3	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092609	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092610	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092611	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092612	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092613	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092614	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092615	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092616	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092617	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092618	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092619	Soil		0.5	712.4	97.8	868	6.26	17.1	1.1	18.5	298	2.8	2.1	0.1	301	5.05	0.823	89	239	0.39	2308	0.010
1092620	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092621	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092622	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092623	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092624	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092625	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092626	Soil		0.3	511.8	67.7	812	6.22	982.6	15.3	9.4	167	0.7	7.7	<0.1	147	2.47	0.412	63	149	0.76	1540	0.004
1092627	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092628	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092629	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092630	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092631	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092632	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092633	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092634	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092635	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092636	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092637	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092638	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092609	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092610	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092611	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092612	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092613	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092614	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092615	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092616	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092617	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092618	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092619	Soil	32	1.41	0.008	0.40	<0.1	4.65	21.3	0.7	0.10	5	3.1	<0.2
1092620	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092621	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092622	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092623	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092624	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092625	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092626	Soil	<20	1.07	0.019	0.16	<0.1	1.22	15.1	0.5	0.07	3	1.9	<0.2
1092627	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092628	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092629	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092630	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092631	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092632	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092633	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092634	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092635	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092636	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092637	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092638	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092639	Soil	22.8	86.8	16.5	535	1.2	132.9	14.9	440	3.58	45.2	5.0	3.8	23	4.8	8.8	0.2	71	0.21	0.132	25
1092640	Soil	41.0	16.0	4.5	443	<0.1	89.8	7.4	50	1.70	15.7	1.2	0.7	3	0.2	2.3	<0.1	57	0.03	0.036	5
1092641	Soil	31.0	29.9	10.4	302	0.4	76.3	7.6	81	2.22	38.6	1.3	0.3	9	0.5	5.8	0.2	190	0.02	0.054	13
1092642	Soil	21.0	28.3	7.3	261	0.3	81.6	7.9	87	1.90	45.8	2.5	0.5	11	1.0	6.0	0.1	140	0.07	0.087	11
1092643	Soil	36.0	64.3	14.2	1026	2.2	128.9	7.3	156	2.21	76.8	65.9	0.7	46	8.4	19.6	0.2	333	0.37	0.152	12
1092644	Soil	11.7	13.5	13.2	669	0.6	51.6	1.6	43	0.81	17.6	3.6	<0.1	34	5.3	6.7	0.1	81	0.27	0.038	5
1092645	Soil	124.0	113.6	15.4	2077	0.6	281.1	16.1	270	3.11	107.4	11.3	1.0	38	17.9	30.9	0.1	1243	0.26	0.106	16
1092646	Soil	19.4	22.9	14.7	197	0.7	41.6	3.9	41	1.69	43.9	2.7	0.2	17	0.3	7.4	0.2	148	0.02	0.056	11
1092647	Soil	16.2	17.2	10.2	180	0.3	33.4	2.9	26	1.23	30.1	3.1	0.4	19	0.3	6.0	0.1	138	0.03	0.040	7
1092648	Soil	18.9	20.2	10.4	136	0.2	28.9	3.1	35	1.43	28.5	1.8	<0.1	17	0.2	4.3	0.2	122	<0.01	0.040	9
1092649	Soil	16.6	30.0	30.9	70	1.4	21.4	2.9	53	2.11	56.2	32.9	0.7	102	0.4	10.7	0.2	97	0.04	0.122	6
1092650	Soil	26.1	70.8	34.2	134	3.1	52.1	2.0	33	2.10	112.7	11.2	2.0	239	0.2	17.9	0.3	201	0.04	0.207	10
1092661	Soil	7.9	59.9	20.9	121	1.2	31.5	5.6	151	3.01	84.5	1.5	1.3	61	0.4	5.3	0.2	42	0.06	0.076	2
1092662	Soil	5.3	52.9	19.8	149	2.7	51.4	7.1	82	2.89	70.4	7.5	0.9	92	0.4	2.6	0.2	28	0.10	0.073	4
1092663	Soil	6.6	43.2	17.0	132	2.6	46.1	5.0	83	2.33	76.9	13.9	0.8	98	0.4	2.7	0.2	20	0.30	0.071	3
1092664	Soil	2.4	49.5	18.3	136	1.7	41.6	9.0	109	3.15	25.5	4.2	1.3	39	0.3	1.5	0.2	23	0.09	0.086	2
1092665	Soil	2.7	45.2	18.7	160	1.6	42.1	8.5	193	2.79	78.4	13.8	1.4	71	0.7	2.3	0.2	22	0.32	0.088	3
1092666	Soil	3.3	15.2	16.4	74	1.5	25.9	4.8	64	2.25	43.6	20.5	1.4	42	0.4	1.7	0.2	21	0.13	0.060	4
1092667	Soil	4.1	61.7	37.7	146	3.8	67.5	8.6	170	4.37	219.1	32.1	2.6	176	0.4	6.0	0.4	30	0.27	0.098	5
1092668	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092669	Soil	3.3	18.9	11.0	82	0.6	23.5	3.9	53	1.51	48.5	4.7	0.9	22	<0.1	1.9	<0.1	40	0.04	0.043	5
1092670	Soil	2.6	32.9	23.4	109	0.8	42.1	6.2	80	3.27	285.3	35.7	2.7	200	0.2	7.1	0.3	20	0.05	0.076	3
1092671	Soil	2.5	23.7	15.9	89	1.0	21.1	3.3	37	2.04	72.3	11.0	1.0	27	<0.1	2.7	<0.1	33	0.03	0.063	2
1092672	Soil	3.0	35.3	16.1	95	0.7	27.0	5.6	87	2.73	86.0	7.5	1.0	36	0.2	3.1	0.2	29	0.15	0.061	3
1092673	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092674	Soil	1.5	21.6	14.3	56	0.4	15.6	3.1	43	1.77	74.8	10.1	1.0	95	0.1	1.6	0.1	18	0.02	0.071	3
1092675	Soil	1.5	13.5	17.1	38	0.4	10.3	2.2	36	1.05	56.9	13.3	1.3	67	<0.1	3.2	0.1	22	0.04	0.035	6
1092676	Soil	2.9	44.4	21.0	91	3.7	27.7	4.9	74	3.71	23.1	7.2	1.4	230	0.1	1.5	0.2	33	0.02	0.100	4
1092677	Soil	3.6	44.5	23.4	169	3.7	53.6	15.8	292	3.85	25.5	8.4	2.0	33	0.2	1.8	0.1	32	0.02	0.076	5
1092678	Soil	2.6	25.6	14.6	70	0.9	19.3	4.6	104	2.41	13.7	2.9	1.1	38	<0.1	1.0	0.2	36	0.02	0.059	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092639	Soil	14	0.05	613	0.003	<1	0.39	0.003	0.07	<0.1	0.57	5.3	0.5	<0.05	<1	0.9	0.3	N.A.	N.A.	N.A.	N.A.
1092640	Soil	10	0.03	48	0.005	2	0.30	0.009	0.03	<0.1	0.04	1.0	0.5	<0.05	2	1.0	0.2	N.A.	N.A.	N.A.	N.A.
1092641	Soil	15	0.03	142	0.003	3	0.30	0.002	0.04	0.2	0.08	0.6	0.4	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092642	Soil	21	0.04	168	0.004	2	0.31	0.010	0.06	0.1	0.38	0.8	0.5	<0.05	2	1.2	0.3	N.A.	N.A.	N.A.	N.A.
1092643	Soil	29	0.10	898	0.004	2	0.71	0.008	0.07	0.3	6.07	1.9	1.5	<0.05	2	5.9	0.3	N.A.	N.A.	N.A.	N.A.
1092644	Soil	7	0.03	470	0.003	<1	0.28	0.008	0.05	0.1	0.38	0.4	0.7	<0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092645	Soil	64	0.17	769	0.010	6	0.85	0.003	0.12	0.6	1.11	2.7	3.6	<0.05	3	10.8	0.3	N.A.	N.A.	N.A.	N.A.
1092646	Soil	10	0.02	206	0.005	3	0.31	0.003	0.05	0.3	0.26	0.6	0.6	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092647	Soil	11	0.02	211	0.005	1	0.27	0.008	0.05	0.2	0.28	0.7	0.4	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092648	Soil	9	0.02	109	0.003	<1	0.24	0.003	0.04	0.2	0.05	0.2	0.3	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092649	Soil	20	0.03	866	0.003	2	0.36	0.003	0.12	0.3	2.99	1.4	1.7	0.08	2	8.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092650	Soil	23	0.02	776	0.002	1	1.26	0.004	0.08	0.3	2.52	2.0	2.1	0.10	3	12.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092661	Soil	11	0.04	758	<0.001	1	0.48	0.003	0.07	<0.1	0.49	2.6	0.3	<0.05	1	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092662	Soil	17	0.03	557	<0.001	3	0.48	0.005	0.09	0.2	0.80	2.8	0.2	<0.05	1	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092663	Soil	16	0.02	858	<0.001	2	0.42	0.004	0.07	<0.1	1.11	3.1	0.1	<0.05	1	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092664	Soil	26	0.08	768	0.001	2	0.80	0.007	0.10	0.1	0.37	4.6	<0.1	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092665	Soil	19	0.07	496	<0.001	1	0.65	0.005	0.09	<0.1	0.56	4.0	<0.1	<0.05	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092666	Soil	14	0.02	1054	0.001	4	0.50	0.008	0.12	<0.1	0.98	1.9	0.2	0.09	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092667	Soil	21	0.06	622	<0.001	4	0.77	0.007	0.18	<0.1	2.00	4.6	0.3	0.34	2	5.1	0.2	N.A.	N.A.	N.A.	N.A.
1092668	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.9	31.8	12.5	120
1092669	Soil	14	0.02	273	0.003	5	0.36	0.004	0.06	0.2	0.14	1.2	<0.1	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092670	Soil	12	0.02	602	<0.001	2	0.47	0.006	0.17	<0.1	0.96	2.5	0.2	0.20	1	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092671	Soil	17	0.02	295	0.001	2	0.42	0.005	0.09	0.1	0.85	1.7	0.1	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092672	Soil	16	0.05	545	0.001	2	0.66	0.004	0.08	0.1	0.55	2.3	<0.1	<0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092673	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.9	37.6	16.0	178
1092674	Soil	14	0.02	288	0.002	<1	0.49	0.006	0.07	<0.1	0.36	2.2	0.1	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092675	Soil	10	0.02	188	0.002	3	0.45	0.007	0.07	0.2	0.28	1.0	0.2	<0.05	3	2.8	0.3	N.A.	N.A.	N.A.	N.A.
1092676	Soil	22	0.04	165	0.004	<1	0.71	0.004	0.08	0.2	0.35	2.3	0.1	<0.05	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092677	Soil	23	0.20	188	0.004	<1	1.07	0.003	0.06	<0.1	0.22	2.6	0.1	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092678	Soil	19	0.05	121	0.003	<1	0.75	0.004	0.05	0.2	0.12	1.5	0.1	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
Unit		ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
MDL		0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092639	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092640	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092641	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092642	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092643	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092644	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092645	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092646	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092647	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092648	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092649	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092650	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092661	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092662	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092663	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092664	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092665	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092666	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092667	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092668	Soil	1.1	39.9	5.5	78	2.13	71.7	23.4	0.7	106	0.5	1.4	0.2	27	1.57	0.088	4	19	0.17	738	<0.001
1092669	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092670	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092671	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092672	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092673	Soil	1.2	56.2	7.5	114	2.53	25.3	6.9	1.4	58	0.8	0.6	0.2	36	0.75	0.102	7	29	0.11	706	0.001
1092674	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092675	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092676	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092677	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092678	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092639	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092640	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092641	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092642	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092643	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092644	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092645	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092646	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092647	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092648	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092649	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092650	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092661	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092662	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092663	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092664	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092665	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092666	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092667	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092668	Soil	<20	0.63	0.007	0.09	<0.1	1.53	2.3	<0.1	0.13	1	2.9	<0.2
1092669	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092670	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092671	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092672	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092673	Soil	<20	0.83	0.007	0.10	<0.1	0.31	3.8	0.1	<0.05	2	3.3	<0.2
1092674	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092675	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092676	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092677	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092678	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092679	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092680	Soil	2.2	25.8	10.7	58	0.4	13.7	3.5	156	1.91	9.4	1.4	0.4	22	<0.1	0.9	0.1	33	0.02	0.056	4
1092691	Soil	2.8	50.5	16.8	152	2.1	52.1	8.1	156	3.04	13.4	9.7	1.6	137	0.2	1.0	0.2	28	0.73	0.119	4
1092692	Soil	3.9	52.1	18.6	96	1.2	30.8	3.9	96	2.89	16.2	6.3	0.7	137	0.2	1.4	0.3	44	0.83	0.196	4
1092693	Soil	5.7	65.4	22.6	71	2.0	20.5	3.5	102	2.63	15.8	9.6	1.2	184	0.3	1.9	0.4	41	0.44	0.128	4
1092694	Soil	6.3	50.2	18.9	89	0.7	20.5	3.9	73	2.37	18.1	3.5	1.3	104	0.3	2.2	0.3	61	0.05	0.063	7
1092695	Soil	3.1	47.6	26.8	142	1.1	52.0	12.1	180	4.40	18.0	6.9	2.2	70	0.3	1.3	0.3	43	0.14	0.109	4
1092696	Soil	1.4	20.5	9.7	78	0.7	32.5	6.7	128	1.65	3.8	4.9	0.7	38	0.2	0.6	0.2	17	0.15	0.075	2
1092697	Soil	2.2	19.8	11.1	46	0.3	11.7	2.2	71	1.20	6.6	1.4	0.1	56	<0.1	1.0	0.2	31	0.31	0.064	6
1092698	Soil	2.1	28.9	17.3	120	0.2	41.5	13.5	606	2.37	9.1	1.4	1.0	22	0.3	1.4	0.2	32	0.08	0.072	6
1092699	Soil	4.3	48.7	19.2	136	0.2	42.8	7.9	198	4.35	16.9	3.1	2.7	23	0.1	2.1	0.3	46	0.02	0.060	7
1092700	Soil	4.8	52.4	17.6	137	0.4	34.4	7.8	171	3.76	14.1	1.1	1.2	9	0.1	2.0	0.4	64	0.02	0.082	10
1092701	Soil	10.9	69.3	19.2	515	1.4	105.5	13.5	339	2.85	43.0	5.7	2.1	79	5.1	6.8	0.2	81	0.60	0.166	11
1092702	Soil	6.3	56.2	14.1	192	1.4	49.3	4.4	119	1.58	16.9	7.7	0.6	67	3.0	4.2	0.2	88	0.44	0.136	6
1092703	Soil	16.2	66.2	19.9	295	0.8	66.6	8.9	202	2.76	38.6	9.1	3.1	69	2.4	8.6	0.3	89	0.25	0.143	14
1092704	Soil	6.5	41.8	14.3	238	0.6	44.1	7.5	238	2.19	19.8	7.5	1.6	62	2.0	5.6	0.2	84	0.53	0.109	6
1092705	Soil	5.2	32.3	10.1	186	1.0	33.2	5.4	323	1.62	15.3	7.3	0.5	69	2.4	3.8	0.2	69	1.10	0.130	4
1092706	Soil	6.2	45.1	14.9	252	1.0	40.3	8.6	383	2.51	16.0	10.4	1.9	51	2.3	5.9	0.2	96	0.19	0.119	7
1092707	Soil	4.0	27.7	11.4	108	3.2	22.1	2.6	69	1.34	11.4	11.2	0.5	41	1.3	3.1	0.2	83	0.11	0.132	6
1092708	Soil	5.8	63.3	14.2	240	1.8	45.5	7.0	463	2.34	17.1	9.4	1.0	63	2.3	4.4	0.2	114	0.33	0.176	9
1092709	Soil	7.6	46.8	16.3	255	0.6	39.8	17.6	1416	2.56	25.1	8.0	1.0	74	5.7	6.3	0.2	151	0.21	0.178	9
1092710	Soil	3.4	27.0	7.3	104	1.8	18.3	2.4	74	1.38	7.9	5.9	0.2	29	1.1	2.3	0.1	61	0.09	0.111	5
1092751	Soil	2.9	32.0	12.4	86	1.0	19.6	7.2	765	4.16	9.3	1.9	2.3	11	<0.1	1.3	0.3	53	0.02	0.061	5
1092752	Soil	2.6	56.4	21.3	124	1.1	28.6	6.8	92	3.78	12.3	3.2	1.7	90	0.1	1.3	0.3	48	0.02	0.071	4
1092753	Soil	3.3	44.3	18.1	138	0.8	32.7	8.3	265	4.20	14.0	3.1	1.3	37	0.1	1.5	0.3	54	0.04	0.112	6
1092754	Soil	3.3	28.8	19.5	95	0.3	23.0	5.6	182	3.55	14.9	2.8	0.5	18	0.2	1.8	0.3	47	0.03	0.105	6
1092755	Soil	4.8	42.2	23.4	104	1.7	26.0	6.4	101	3.12	14.1	7.0	1.0	59	0.1	1.5	0.3	52	0.02	0.094	6
1092756	Soil	2.9	18.5	14.0	117	0.4	45.8	14.4	500	5.09	10.9	2.3	1.1	11	0.3	1.2	0.3	48	0.01	0.073	7
1092757	Soil	3.9	23.6	21.0	187	1.5	56.8	12.4	897	7.49	15.6	2.3	0.7	88	1.4	1.6	0.2	113	2.02	0.229	16
1092758	Soil	2.4	15.7	10.5	300	0.3	48.1	9.6	199	2.88	11.8	3.7	1.9	67	3.6	1.8	0.2	50	1.56	0.200	19

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092679	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.7	45.9	23.0	102
1092680	Soil		14	0.04	112	0.004	<1	0.54	0.005	0.05	<0.1	0.05	0.9	<0.1	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092691	Soil		28	0.20	1789	0.002	1	1.03	0.010	0.05	<0.1	0.33	2.9	0.1	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092692	Soil		31	0.14	2096	0.003	5	1.12	0.009	0.06	<0.1	0.28	1.5	0.1	0.14	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092693	Soil		30	0.12	1197	0.004	5	0.90	0.018	0.08	0.3	0.23	2.1	0.2	0.13	3	3.7	0.2	N.A.	N.A.	N.A.	N.A.
1092694	Soil		21	0.06	378	0.007	4	0.56	0.010	0.07	0.4	0.05	1.6	0.2	0.06	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092695	Soil		39	0.28	825	0.004	8	1.41	0.009	0.08	<0.1	0.25	3.5	0.2	0.06	4	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092696	Soil		13	0.08	1580	0.005	6	0.75	0.020	0.05	<0.1	0.15	1.9	0.1	0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092697	Soil		13	0.04	2861	0.003	6	0.50	0.011	0.06	<0.1	0.05	0.4	0.1	0.06	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092698	Soil		22	0.22	2577	0.004	<1	0.71	0.003	0.05	<0.1	0.07	2.4	<0.1	0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092699	Soil		25	0.15	593	0.009	3	0.99	0.004	0.05	0.1	0.05	2.6	0.2	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092700	Soil		23	0.08	252	0.008	<1	0.87	0.003	0.06	0.1	0.05	2.3	0.2	<0.05	5	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092701	Soil		22	0.15	1626	0.002	6	0.65	0.005	0.09	<0.1	2.34	3.8	0.4	0.09	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092702	Soil		21	0.07	1808	0.003	4	0.66	0.007	0.07	0.1	0.84	2.1	0.4	0.08	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092703	Soil		19	0.15	1691	0.007	5	0.62	0.005	0.11	0.2	0.71	3.1	0.6	0.07	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092704	Soil		21	0.11	1871	0.003	9	0.72	0.005	0.13	<0.1	0.68	2.6	0.4	0.07	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092705	Soil		17	0.10	1155	0.003	5	0.74	0.012	0.08	<0.1	0.84	1.5	0.3	0.09	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092706	Soil		21	0.13	1612	0.004	<1	0.83	0.004	0.13	0.1	0.63	2.7	0.3	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092707	Soil		21	0.13	868	0.003	7	0.98	0.012	0.11	0.1	1.29	1.6	0.4	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092708	Soil		28	0.20	1876	0.003	6	1.35	0.008	0.16	<0.1	0.86	2.6	0.4	<0.05	4	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092709	Soil		27	0.18	877	0.003	5	0.99	0.005	0.14	0.1	0.50	2.3	0.4	<0.05	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092710	Soil		12	0.09	478	0.003	5	0.64	0.013	0.07	<0.1	0.51	0.6	0.2	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092751	Soil		20	0.11	394	0.002	1	1.06	0.003	0.08	<0.1	0.09	2.4	0.2	<0.05	5	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092752	Soil		23	0.12	202	0.002	5	1.05	0.006	0.08	<0.1	0.08	2.1	0.2	<0.05	6	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092753	Soil		30	0.19	232	0.008	5	1.16	0.006	0.07	<0.1	0.09	2.2	0.2	<0.05	5	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092754	Soil		26	0.18	159	0.006	3	1.20	0.004	0.07	0.1	0.06	0.8	0.2	0.06	5	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092755	Soil		28	0.13	214	0.004	4	1.08	0.005	0.06	<0.1	0.15	1.3	0.2	<0.05	4	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092756	Soil		16	0.07	154	0.004	3	0.71	0.005	0.06	<0.1	0.06	2.1	0.1	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092757	Soil		40	0.13	932	0.004	4	0.92	0.005	0.05	0.1	0.25	5.8	<0.1	0.11	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092758	Soil		50	0.09	300	0.006	1	2.60	0.004	0.04	<0.1	0.12	3.5	0.1	0.07	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092679	Soil		1.7	32.8	10.2	352	3.07	16.4	4.3	0.5	45	0.3	0.6	0.3	44	0.03	0.100	6	34	0.17	315	0.003
1092680	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092691	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092692	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092693	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092694	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092695	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092696	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092697	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092698	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092699	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092700	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092701	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092702	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092703	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092704	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092705	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092706	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092707	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092708	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092709	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092710	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092751	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092752	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092753	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092754	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092755	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092756	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092757	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092758	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092679	Soil	<20	1.12	0.006	0.09	<0.1	0.20	1.6	0.2	<0.05	4	1.2	<0.2
1092680	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092691	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092692	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092693	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092694	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092695	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092696	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092697	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092698	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092699	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092700	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092701	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092702	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092703	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092704	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092705	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092706	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092707	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092708	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092709	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092710	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092751	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092752	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092753	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092754	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092755	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092756	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092757	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092758	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092759	Soil	1.5	15.5	10.6	147	0.7	28.2	3.9	260	1.56	7.9	6.5	0.5	51	1.2	1.2	0.2	36	1.07	0.157	14
1092760	Soil	1.6	18.7	10.1	160	0.8	32.2	5.1	191	1.70	11.6	7.3	0.5	51	2.6	1.4	0.2	41	1.53	0.150	10
1092761	Soil	1.9	20.2	11.6	131	4.6	57.2	6.5	168	2.61	14.3	5.2	1.6	89	2.7	2.7	0.2	55	1.14	0.202	26
1092762	Soil	1.1	8.0	17.5	15	1.7	7.9	0.8	10	0.43	4.7	3.1	0.5	15	<0.1	0.5	0.3	12	0.24	0.012	<1
1092763	Soil	0.4	9.3	4.9	95	0.2	16.5	1.9	136	0.78	4.9	1.4	0.2	40	1.0	1.1	<0.1	22	1.43	0.134	6
1092764	Soil	0.5	15.1	7.6	208	0.4	22.6	3.9	427	1.27	5.6	1.5	0.2	111	3.1	1.2	0.1	40	3.98	0.282	19
1092765	Soil	0.2	9.3	1.9	25	<0.1	3.1	1.1	62	0.33	<0.5	1.0	0.1	25	0.3	0.2	<0.1	7	0.54	0.048	3
1092766	Soil	2.2	27.7	17.2	239	0.7	52.2	7.5	278	2.81	17.0	3.2	0.9	84	3.0	2.5	0.3	63	1.89	0.273	14
1092767	Soil	0.4	10.8	2.9	35	<0.1	4.6	1.4	85	0.47	1.2	0.6	<0.1	44	0.8	0.2	0.1	9	1.09	0.056	3
1092768	Soil	1.2	35.2	10.6	251	0.6	54.4	6.5	157	1.96	13.9	3.7	1.0	58	1.1	2.1	0.2	42	1.08	0.200	11
1092769	Soil	0.3	9.3	3.8	24	<0.1	4.5	1.7	82	0.51	1.4	1.0	<0.1	24	0.1	0.3	<0.1	12	0.53	0.053	3
1092770	Soil	0.3	6.8	3.5	40	0.2	6.5	1.6	91	0.56	2.8	2.4	0.1	21	0.3	0.4	<0.1	11	0.47	0.062	3
1092771	Soil	0.5	12.1	3.7	46	0.2	7.7	1.8	142	0.67	2.7	1.2	0.1	50	0.4	0.4	<0.1	13	1.49	0.086	4
1092772	Soil	0.1	4.3	1.2	20	<0.1	2.1	0.8	46	0.22	0.6	<0.5	<0.1	19	0.2	0.1	<0.1	6	0.40	0.045	2
1092773	Soil	0.3	6.1	2.4	38	<0.1	6.3	1.1	55	0.44	2.0	1.1	<0.1	31	0.3	0.3	<0.1	13	0.90	0.064	3
1092774	Soil	1.7	37.6	11.4	222	1.1	56.7	6.7	175	2.03	13.5	4.3	1.1	72	0.6	2.5	0.2	52	1.46	0.202	11
1092775	Soil	1.3	45.1	14.2	164	0.8	47.1	12.0	305	2.33	20.4	6.3	1.4	64	1.9	1.7	0.2	53	0.90	0.123	12
1092776	Soil	8.5	19.9	12.3	116	0.3	28.1	4.2	76	1.91	39.6	5.0	0.6	14	0.3	3.5	0.2	81	0.04	0.076	5
1092777	Soil	2.6	67.9	20.3	239	1.0	72.7	14.1	400	3.42	17.2	4.3	2.5	102	0.8	1.5	0.2	28	0.96	0.114	4
1092778	Soil	7.1	44.2	14.6	186	0.6	51.4	7.3	89	2.77	44.5	15.9	2.2	27	0.7	5.7	0.3	62	0.07	0.059	7
1092779	Soil	6.0	27.0	22.0	122	0.6	28.1	4.9	109	2.83	53.2	5.2	0.6	18	0.2	5.0	0.3	79	0.03	0.108	7
1092780	Soil	5.1	19.6	17.1	89	0.6	20.0	2.9	81	2.06	32.4	2.5	0.7	15	<0.1	3.1	0.3	72	0.02	0.131	6
1092681	Soil	3.2	41.4	20.3	104	0.5	28.5	7.6	384	3.64	15.2	5.3	1.5	20	0.1	1.4	0.3	40	0.03	0.057	6
1092682	Soil	2.8	50.4	26.1	121	0.3	31.2	17.1	1163	3.58	13.9	5.0	1.3	31	0.3	1.4	0.3	41	0.03	0.110	4
1092683	Soil	3.7	44.7	24.4	118	0.3	30.5	16.7	1183	3.19	14.6	3.0	0.7	35	0.2	1.7	0.3	43	0.03	0.110	5
1092684	Soil	3.8	55.9	26.7	125	0.4	36.3	14.9	578	3.20	16.4	2.7	0.5	32	0.2	1.9	0.3	38	0.02	0.106	5
1092685	Soil	3.4	78.6	36.0	215	1.0	79.0	33.1	1774	3.72	16.7	6.9	3.0	50	0.3	2.1	0.4	26	0.15	0.083	6
1092686	Soil	2.2	55.9	28.1	131	0.9	57.1	25.9	1625	3.09	8.9	5.6	1.5	41	0.1	1.2	0.2	22	0.13	0.083	5
1092687	Soil	2.3	51.9	22.1	139	1.9	54.5	14.7	832	2.99	10.0	8.0	1.6	97	0.3	1.1	0.3	22	0.41	0.092	5
1092688	Soil	2.8	33.7	17.5	67	1.7	18.4	3.7	77	2.31	9.9	3.5	1.1	49	0.3	1.1	0.3	34	0.03	0.104	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092759	Soil	21	0.05	928	0.006	1	0.76	0.003	0.02	<0.1	0.39	1.1	<0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092760	Soil	27	0.05	754	0.005	2	0.85	0.003	0.02	<0.1	1.18	1.3	<0.1	0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092761	Soil	52	0.10	351	0.005	2	1.76	0.003	0.03	0.1	0.89	4.0	0.1	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092762	Soil	4	0.01	927	<0.001	2	0.19	0.003	0.03	<0.1	0.23	0.6	0.2	<0.05	<1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092763	Soil	15	0.04	160	0.008	1	0.53	0.020	0.02	<0.1	0.23	0.5	<0.1	0.06	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092764	Soil	44	0.05	339	0.005	3	0.61	0.005	0.01	<0.1	0.40	0.6	<0.1	0.21	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092765	Soil	4	0.03	68	0.010	<1	0.48	0.031	0.02	<0.1	0.05	0.4	<0.1	0.06	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092766	Soil	40	0.18	454	0.006	<1	1.21	0.005	0.04	0.2	0.51	2.1	0.1	0.11	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092767	Soil	4	0.03	142	0.011	<1	0.72	0.029	0.02	<0.1	0.05	0.2	<0.1	0.10	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092768	Soil	27	0.13	502	0.006	2	1.06	0.015	0.05	<0.1	0.46	2.2	0.1	0.07	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092769	Soil	6	0.05	101	0.010	1	0.66	0.030	0.03	<0.1	0.04	0.3	<0.1	0.06	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092770	Soil	7	0.04	108	0.009	<1	0.50	0.030	0.03	<0.1	0.07	0.4	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092771	Soil	9	0.04	187	0.009	<1	0.56	0.025	0.02	<0.1	0.08	0.5	<0.1	0.08	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092772	Soil	4	0.02	48	0.010	<1	0.37	0.037	0.03	<0.1	0.03	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092773	Soil	6	0.03	104	0.004	<1	0.44	0.024	0.03	<0.1	0.06	0.3	<0.1	0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092774	Soil	30	0.13	625	0.003	3	0.97	0.011	0.06	<0.1	0.38	2.4	0.1	0.08	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092775	Soil	27	0.15	1063	0.003	<1	1.11	0.006	0.05	<0.1	0.78	3.0	0.1	0.09	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092776	Soil	14	0.03	182	0.003	1	0.51	0.007	0.03	0.1	0.36	0.9	0.2	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092777	Soil	27	0.39	1053	0.001	<1	1.03	0.006	0.07	<0.1	0.32	3.4	0.1	0.06	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092778	Soil	23	0.16	910	<0.001	1	0.93	0.002	0.04	<0.1	1.08	2.6	0.2	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092779	Soil	17	0.06	125	0.004	<1	0.52	0.004	0.04	0.2	0.47	0.9	0.2	<0.05	4	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092780	Soil	15	0.04	121	0.005	<1	0.45	0.004	0.04	0.1	0.18	0.9	0.2	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092681	Soil	27	0.22	141	0.005	2	1.08	0.003	0.06	0.1	0.07	1.5	0.1	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092682	Soil	30	0.24	235	0.005	2	1.19	0.004	0.09	<0.1	0.07	2.0	0.1	<0.05	4	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092683	Soil	28	0.17	291	0.005	2	1.09	0.004	0.08	0.1	0.09	1.2	0.2	0.06	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092684	Soil	28	0.21	438	0.006	<1	1.07	0.004	0.06	0.1	0.06	1.2	0.1	0.07	4	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092685	Soil	27	0.37	1074	0.004	1	1.15	0.006	0.06	<0.1	0.17	4.4	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092686	Soil	21	0.28	1262	0.005	<1	1.15	0.013	0.05	<0.1	0.13	2.9	0.1	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092687	Soil	24	0.26	2298	0.003	2	1.08	0.011	0.06	<0.1	0.35	3.2	0.1	0.08	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092688	Soil	23	0.05	695	0.004	<1	0.87	0.005	0.06	0.1	0.14	1.2	0.1	0.09	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092759	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092760	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092761	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092762	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092763	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092764	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092765	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092766	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092767	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092768	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092769	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092770	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092771	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092772	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092773	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092774	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092775	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092776	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092777	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092778	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092779	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092780	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092681	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092682	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092683	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092684	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092685	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092686	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092687	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092688	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092759	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092760	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092761	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092762	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092763	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092764	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092765	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092766	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092767	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092768	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092769	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092770	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092771	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092772	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092773	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092774	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092775	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092776	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092777	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092778	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092779	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092780	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092681	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092682	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092683	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092684	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092685	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092686	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092687	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092688	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092689	Soil		2.8	57.3	27.3	205	3.1	83.3	16.6	234	4.09	18.8	9.3	2.6	127	0.5	1.5	0.3	34	0.50	0.100	4
1092690	Soil		3.9	42.4	15.9	160	2.0	62.2	10.8	366	3.50	11.6	7.6	0.8	124	0.8	1.0	0.2	29	1.81	0.132	9
1092801	Soil		8.4	67.6	170.5	122	2.2	57.9	5.7	244	2.68	73.0	15.7	4.9	190	0.3	7.2	0.7	43	1.77	0.216	14
1092802	Soil		2.0	159.8	36.6	251	1.3	111.3	34.8	1459	8.96	170.8	32.1	9.2	52	0.8	12.8	0.9	16	0.05	0.141	30
1092803	Soil		3.0	47.6	13.2	99	0.1	43.2	14.3	214	4.03	137.3	2.5	0.5	16	0.1	10.2	0.4	22	0.02	0.096	9
1092804	Soil		2.3	16.8	6.9	55	0.2	14.8	3.2	37	1.22	12.0	1.0	0.2	11	<0.1	1.3	0.1	17	0.01	0.094	5
1092805	Soil		23.1	28.1	10.6	206	0.2	51.4	5.0	168	1.58	28.4	3.3	0.2	29	0.9	5.7	0.1	115	0.50	0.111	8
1092806	Soil		51.2	85.8	14.4	347	0.5	194.6	10.3	362	2.07	33.4	2.2	1.4	104	5.2	8.4	0.1	100	4.51	0.100	14
1092807	Soil		7.6	42.2	13.1	200	0.7	32.6	5.4	134	1.97	16.9	5.7	0.7	42	1.2	4.5	0.2	78	0.14	0.081	7
1092808	Soil		6.9	34.6	16.0	84	1.6	15.5	2.5	93	1.52	12.2	13.6	0.5	64	0.5	4.6	0.2	80	0.10	0.118	5
1092809	Soil		5.0	21.9	16.3	126	0.6	26.7	4.6	145	2.92	21.0	4.0	1.1	23	0.5	2.5	0.3	69	0.05	0.083	8
1092810	Soil		4.5	25.9	16.6	144	0.5	27.7	4.5	131	2.73	19.5	2.3	2.3	24	0.4	2.1	0.3	74	0.04	0.100	8
1092811	Soil		5.1	32.5	15.8	198	0.6	37.4	5.2	135	3.46	22.6	6.1	1.6	22	0.5	3.0	0.2	68	0.04	0.115	5
1092812	Soil		4.3	30.4	15.0	78	0.6	12.9	1.9	57	1.73	18.2	3.0	0.4	25	0.8	1.4	0.2	55	0.02	0.127	4
1092813	Soil		5.4	50.9	16.7	168	1.4	30.8	4.5	122	2.45	24.9	9.6	1.0	48	2.1	2.4	0.3	62	0.23	0.111	6
1092814	Soil		2.8	43.4	9.4	115	2.8	36.6	3.7	112	1.48	10.4	9.3	0.7	55	2.3	1.6	0.2	34	1.08	0.099	3
1092815	Soil		2.1	41.6	9.6	95	2.5	46.3	4.4	128	1.54	11.3	10.0	0.7	66	0.9	1.4	0.2	36	1.17	0.096	3
1092816	Soil		4.6	59.7	11.8	181	1.3	38.3	5.3	130	2.39	28.3	8.1	1.6	42	3.2	2.8	0.2	55	0.25	0.084	6
1092817	Soil		4.5	17.4	16.2	79	0.2	15.1	3.4	106	1.85	17.9	4.3	0.2	17	0.3	2.0	0.3	66	0.03	0.053	11
1092818	Soil		3.7	20.6	10.3	86	0.3	16.5	2.8	74	1.35	13.2	4.0	1.2	38	0.3	1.6	0.2	54	0.21	0.032	9
1092819	Soil		3.6	10.8	10.2	57	0.2	10.0	2.3	50	1.59	12.5	1.7	1.0	10	0.3	1.5	0.2	52	0.02	0.029	8
1092820	Soil		2.8	14.5	9.6	67	0.3	13.7	2.5	83	1.78	12.5	2.3	1.8	11	<0.1	1.4	0.2	47	0.01	0.052	8
1092851	Soil		9.6	15.4	9.0	72	0.2	19.9	2.8	38	0.89	14.3	2.2	0.2	9	0.3	2.2	0.1	44	0.03	0.100	7
1092852	Soil		7.6	61.7	80.8	122	1.3	37.2	4.5	92	2.58	28.7	10.6	1.0	106	0.7	3.1	0.4	76	0.15	0.251	14
1092853	Soil		49.9	31.4	9.7	497	0.2	70.5	5.6	90	2.09	36.6	1.7	0.6	5	0.6	14.6	0.2	208	0.02	0.056	14
1092854	Soil		24.9	27.2	12.9	355	0.3	66.3	4.4	90	1.91	28.1	0.9	0.3	16	3.7	7.2	0.2	170	0.06	0.103	11
1092855	Soil		69.6	24.6	12.4	397	0.3	120.6	4.6	29	1.85	39.1	1.1	0.4	9	1.2	12.0	0.1	424	0.04	0.069	19
1092856	Soil		74.4	32.5	10.6	531	0.3	155.1	6.1	43	2.01	49.5	<0.5	0.7	16	2.0	8.2	0.1	219	0.20	0.101	12
1092857	Soil		42.1	20.5	6.0	178	0.1	90.8	4.6	55	1.23	14.8	1.0	0.3	31	1.1	2.4	<0.1	29	0.65	0.085	7
1092858	Soil		40.5	35.7	6.3	228	0.2	97.6	4.7	140	1.37	14.4	1.5	0.9	28	2.2	3.3	<0.1	37	0.44	0.096	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092689	Soil	33	0.26	1311	0.001	<1	1.24	0.008	0.07	<0.1	0.50	3.9	0.2	0.08	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092690	Soil	26	0.21	1195	0.002	2	0.94	0.006	0.04	<0.1	0.35	2.7	<0.1	0.16	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092801	Soil	12	0.86	588	0.002	8	0.30	0.003	0.20	0.1	2.87	1.8	0.5	0.39	<1	2.9	0.4	N.A.	N.A.	N.A.	N.A.
1092802	Soil	13	0.07	1515	0.001	<1	1.24	0.002	0.12	<0.1	1.50	11.2	0.3	0.23	1	3.0	0.4	N.A.	N.A.	N.A.	N.A.
1092803	Soil	8	0.04	154	0.003	<1	0.58	0.008	0.06	<0.1	0.18	0.7	0.2	0.07	2	0.6	0.2	N.A.	N.A.	N.A.	N.A.
1092804	Soil	4	0.02	387	0.002	<1	0.31	0.011	0.05	<0.1	0.11	0.2	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092805	Soil	14	0.08	650	0.004	2	0.57	0.015	0.06	0.2	0.16	0.4	0.7	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092806	Soil	19	2.25	462	0.006	5	0.50	0.011	0.08	0.2	0.36	3.3	2.6	0.09	1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092807	Soil	15	0.08	494	0.002	2	0.59	0.008	0.08	0.1	0.23	1.3	0.2	0.08	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092808	Soil	17	0.06	1529	0.007	2	0.52	0.003	0.08	<0.1	0.45	1.0	0.3	0.09	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092809	Soil	20	0.15	411	0.003	<1	0.98	0.003	0.06	0.1	0.07	1.1	0.2	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092810	Soil	23	0.15	371	0.003	1	1.27	0.004	0.06	0.2	0.09	1.8	0.2	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092811	Soil	26	0.15	489	0.002	4	1.12	0.005	0.06	<0.1	0.12	1.8	0.2	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092812	Soil	14	0.03	338	0.003	4	0.55	0.006	0.06	<0.1	0.03	0.5	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092813	Soil	21	0.14	617	0.002	3	0.91	0.005	0.08	0.1	0.42	2.0	0.2	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092814	Soil	16	0.13	1432	0.002	6	0.76	0.014	0.06	<0.1	0.64	2.3	0.1	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092815	Soil	17	0.12	2205	0.002	10	1.00	0.015	0.06	<0.1	0.58	2.3	0.1	<0.05	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092816	Soil	21	0.16	809	0.002	2	0.81	0.003	0.06	0.1	0.48	2.4	0.2	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092817	Soil	15	0.12	464	0.008	2	0.79	0.003	0.05	0.2	0.09	0.5	0.2	<0.05	4	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092818	Soil	11	0.10	1302	0.004	5	0.76	0.005	0.04	0.1	0.10	1.2	0.2	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092819	Soil	11	0.07	234	0.006	<1	0.71	0.005	0.04	<0.1	0.05	0.9	0.1	<0.05	4	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092820	Soil	13	0.09	158	0.006	4	0.79	0.006	0.04	0.1	0.06	0.9	0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092851	Soil	9	0.03	153	0.002	7	0.31	0.008	0.06	<0.1	0.17	0.2	0.3	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092852	Soil	15	0.04	611	0.004	14	0.48	0.005	0.22	0.1	0.82	1.3	0.3	0.31	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092853	Soil	10	0.03	228	0.003	6	0.30	0.002	0.07	0.1	0.21	0.9	0.3	<0.05	<1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092854	Soil	17	0.05	249	0.003	6	0.54	0.004	0.06	<0.1	0.24	0.3	0.6	<0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092855	Soil	29	0.07	230	0.005	3	0.54	0.002	0.07	0.3	0.11	0.6	1.1	<0.05	2	2.6	0.2	N.A.	N.A.	N.A.	N.A.
1092856	Soil	27	0.09	439	0.005	13	0.61	0.004	0.07	0.3	0.16	1.4	1.2	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092857	Soil	7	0.06	257	0.003	5	0.29	0.014	0.04	0.2	0.13	1.0	0.4	<0.05	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092858	Soil	8	0.06	254	0.005	6	0.34	0.013	0.04	0.1	0.19	2.2	0.5	<0.05	<1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092689	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092690	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092801	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092802	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092803	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092804	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092805	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092806	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092807	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092808	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092809	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092810	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092811	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092812	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092813	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092814	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092815	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092816	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092817	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092818	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092819	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092820	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092851	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092852	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092853	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092854	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092855	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092856	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092857	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092858	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092689	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092690	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092801	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092802	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092803	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092804	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092805	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092806	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092807	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092808	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092809	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092810	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092811	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092812	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092813	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092814	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092815	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092816	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092817	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092818	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092819	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092820	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092851	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092852	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092853	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092854	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092855	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092856	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092857	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092858	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092859	Soil	3.7	50.8	17.2	133	1.2	45.8	11.1	274	3.01	27.2	6.3	0.9	34	0.5	2.0	0.3	37	0.10	0.120	7
1092860	Soil	1.9	27.5	13.5	74	1.2	24.5	4.4	118	1.85	22.2	6.8	1.5	40	0.3	1.2	0.2	19	0.24	0.072	6
1092861	Soil	2.8	34.9	17.0	122	1.7	43.5	7.9	170	2.51	18.7	10.6	2.4	38	0.7	1.1	0.2	22	0.30	0.089	7
1092862	Soil	3.9	55.2	21.8	137	1.6	53.0	9.5	208	3.99	16.7	5.7	1.4	54	0.3	1.7	0.2	26	0.03	0.098	4
1092863	Soil	14.5	117.3	24.9	181	4.5	40.7	4.7	51	6.56	42.4	6.6	2.5	23	0.1	3.3	0.3	55	<0.01	0.111	2
1092864	Soil	2.9	69.0	29.1	100	1.5	19.7	3.7	60	5.05	58.1	6.2	2.3	44	<0.1	2.0	0.4	45	0.01	0.099	2
1092865	Soil	1.4	31.8	13.1	47	1.2	10.3	2.3	75	2.49	23.9	4.8	1.5	41	<0.1	0.8	0.3	13	0.09	0.058	2
1092866	Soil	2.5	78.8	42.3	114	2.7	27.9	9.8	310	5.93	55.9	6.0	2.4	41	<0.1	1.8	0.4	40	<0.01	0.141	3
1092867	Soil	5.1	86.0	30.8	135	1.5	30.9	8.3	354	5.36	39.6	12.4	2.2	21	0.2	1.9	0.5	43	<0.01	0.102	2
1092868	Soil	5.5	28.1	21.0	49	2.9	10.9	2.9	144	2.40	29.1	7.7	0.7	32	<0.1	5.6	0.3	31	0.01	0.086	3
1092869	Soil	6.5	48.4	28.9	149	0.7	26.2	6.9	164	4.31	31.2	1.7	0.8	19	0.2	2.5	0.3	34	<0.01	0.098	3
1092870	Soil	7.5	21.1	24.4	64	1.1	11.8	2.7	109	2.01	21.9	1.5	0.2	22	0.1	4.0	0.3	58	<0.01	0.162	3
1092871	Soil	12.2	20.7	35.3	8	0.7	2.3	0.4	10	0.84	26.3	5.4	0.8	20	<0.1	4.1	0.2	72	<0.01	0.040	6
1092872	Soil	30.9	27.6	62.0	86	1.1	12.6	2.3	68	2.72	78.5	6.7	0.6	167	0.5	10.7	0.5	86	0.02	0.143	9
1092873	Soil	33.6	271.0	67.0	1114	5.5	99.3	14.9	203	4.33	84.1	20.1	1.6	100	20.2	26.9	0.3	54	0.16	0.225	9
1092874	Soil	1.3	13.5	2.7	19	<0.1	6.6	2.3	310	0.63	9.5	<0.5	<0.1	6	<0.1	0.6	<0.1	19	0.03	0.064	2
1092875	Soil	24.7	29.3	7.5	323	0.2	57.9	2.4	60	1.07	24.5	<0.5	<0.1	18	0.8	11.9	0.1	160	0.05	0.106	5
1092876	Soil	71.9	44.1	12.5	559	0.5	100.2	4.3	306	1.34	37.8	1.1	0.4	27	5.6	18.0	0.1	584	0.08	0.134	12
1092877	Soil	38.4	17.3	5.5	169	<0.1	54.0	2.6	20	0.86	18.4	<0.5	<0.1	4	0.2	3.2	0.1	142	0.01	0.075	7
1092878	Soil	3.5	73.2	12.3	143	0.4	70.2	13.7	135	5.60	19.0	0.8	0.6	3	0.1	1.8	0.3	31	<0.01	0.086	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092859	Soil	25	0.15	389	0.004	8	0.92	0.006	0.08	<0.1	0.12	1.8	0.2	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092860	Soil	14	0.09	547	0.002	7	0.71	0.009	0.08	<0.1	0.30	2.3	0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092861	Soil	21	0.19	388	0.003	5	0.86	0.007	0.06	<0.1	0.17	3.8	0.1	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092862	Soil	24	0.13	366	0.003	3	0.79	0.005	0.07	<0.1	0.17	3.1	0.2	<0.05	2	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092863	Soil	45	0.04	727	0.001	11	0.60	0.005	0.08	<0.1	0.16	4.6	0.2	0.09	3	18.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092864	Soil	22	0.09	930	0.002	6	0.78	0.004	0.08	<0.1	0.10	3.4	<0.1	0.09	2	5.7	0.4	N.A.	N.A.	N.A.	N.A.
1092865	Soil	6	0.01	968	<0.001	9	0.49	0.003	0.06	<0.1	0.27	1.9	<0.1	0.12	1	2.2	0.2	N.A.	N.A.	N.A.	N.A.
1092866	Soil	20	0.10	1023	0.002	6	0.94	0.006	0.09	<0.1	0.10	3.5	0.2	0.11	3	3.6	0.4	N.A.	N.A.	N.A.	N.A.
1092867	Soil	16	0.08	1132	0.004	11	0.82	0.006	0.09	0.1	0.09	3.7	0.2	0.08	3	3.3	0.2	N.A.	N.A.	N.A.	N.A.
1092868	Soil	15	0.06	562	0.001	3	0.56	0.004	0.11	<0.1	1.27	1.3	0.3	0.21	2	4.1	0.3	N.A.	N.A.	N.A.	N.A.
1092869	Soil	12	0.08	152	0.003	5	0.65	0.004	0.05	<0.1	0.15	2.4	0.3	0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092870	Soil	10	0.03	190	0.002	5	0.39	0.003	0.06	<0.1	0.04	0.2	0.3	0.10	2	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092871	Soil	9	0.02	340	0.002	8	0.29	0.004	0.08	0.1	0.63	0.4	0.7	0.13	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092872	Soil	18	0.05	761	0.005	5	0.42	0.004	0.18	0.2	0.54	0.9	2.0	0.34	5	10.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092873	Soil	7	0.04	388	0.003	5	0.58	0.002	0.11	<0.1	12.23	2.6	1.2	0.15	1	7.2	0.2	N.A.	N.A.	N.A.	N.A.
1092874	Soil	2	0.02	36	0.003	<1	0.50	0.021	0.03	<0.1	0.08	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092875	Soil	16	0.03	205	0.001	2	0.34	0.011	0.06	0.1	0.14	<0.1	0.7	<0.05	2	6.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092876	Soil	33	0.06	1475	0.003	8	0.52	0.004	0.10	0.4	0.18	0.6	2.4	0.06	3	7.3	0.3	N.A.	N.A.	N.A.	N.A.
1092877	Soil	14	0.03	91	0.002	2	0.49	0.003	0.04	0.2	0.13	0.2	0.8	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1092878	Soil	9	0.03	98	0.004	2	0.49	0.004	0.06	<0.1	0.03	1.3	0.2	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092859	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092860	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092861	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092862	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092863	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092864	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092865	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092866	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092867	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092868	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092869	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092870	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092871	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092872	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092873	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092874	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092875	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092876	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092877	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092878	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000747.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092859	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092860	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092861	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092862	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092863	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092864	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092865	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092866	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092867	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092868	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092869	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092870	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092871	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092872	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092873	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092874	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092875	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092876	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092877	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092878	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1092210	Soil	42.7	109.8	16.8	453	0.7	349.2	43.4	687	6.42	103.6	<0.5	3.6	98	4.7	7.3	0.2	275	1.91	0.348	38
REP 1092210	QC	43.2	101.5	16.0	443	0.7	350.7	44.8	728	6.66	102.2	<0.5	3.5	102	4.5	8.1	0.2	286	1.91	0.378	38
1092223	Soil	8.8	137.2	15.5	202	0.5	546.2	95.2	1359	8.91	795.8	7.2	12.3	295	1.5	11.5	0.2	142	2.35	0.552	83
REP 1092223	QC	9.1	136.3	15.9	208	0.5	535.7	93.9	1340	8.95	792.7	6.6	12.3	311	1.6	8.6	0.1	164	2.36	0.558	73
1092237	Soil	41.1	15.1	15.9	91	0.7	15.7	2.2	132	2.63	84.0	9.5	0.1	43	0.3	15.1	0.3	215	0.11	0.092	5
REP 1092237	QC	41.0	15.7	16.1	94	0.8	16.6	2.2	137	2.66	85.8	12.9	0.1	44	0.4	15.7	0.3	227	0.07	0.105	6
1092421	Soil	16.7	26.6	9.4	190	0.7	42.7	4.9	123	1.47	15.8	1.5	0.2	24	1.5	4.7	0.1	79	0.10	0.129	7
REP 1092421	QC	16.9	26.8	9.3	194	0.7	43.5	4.8	122	1.46	15.9	2.8	0.2	24	1.5	4.6	0.1	83	0.10	0.128	7
1092448	Soil	2.5	70.8	20.8	329	0.6	37.5	4.4	144	2.32	20.1	2.2	1.2	21	1.4	3.2	0.2	19	0.22	0.079	11
REP 1092448	QC	2.8	71.0	21.3	336	0.6	37.7	4.4	144	2.27	19.6	3.3	1.2	22	1.6	3.3	0.2	19	0.21	0.075	11
1092462	Soil	60.6	87.8	19.0	939	1.2	170.4	8.4	150	2.91	93.7	2.5	1.9	69	9.6	18.3	0.3	324	0.82	0.151	12
REP 1092462	QC	59.0	87.8	18.8	928	1.3	166.5	8.2	147	2.90	94.4	1.9	1.9	66	9.2	18.2	0.3	308	0.81	0.153	12
1092480	Soil	5.1	46.4	11.7	111	<0.1	54.4	18.8	254	5.58	49.9	3.5	0.5	19	0.2	2.9	0.4	41	0.09	0.104	14
REP 1092480	QC	4.5	48.5	10.7	110	0.1	52.8	19.1	247	5.41	49.9	<0.5	0.5	18	0.3	2.7	0.3	41	0.09	0.106	13
1092601	Soil	77.5	104.5	12.3	912	0.8	240.2	9.8	230	2.07	66.1	1.2	0.9	144	8.2	18.5	0.1	365	5.19	0.125	15
REP 1092601	QC	75.6	103.7	12.4	933	0.8	233.9	9.9	230	2.05	66.4	<0.5	0.9	143	8.8	18.7	0.2	370	5.10	0.133	15
1092604	Soil	67.6	118.9	9.6	956	1.0	255.8	12.2	199	2.12	79.7	3.0	2.2	308	8.4	22.0	0.1	566	11.45	0.127	16
REP 1092604	QC	68.0	111.4	9.5	919	0.9	244.2	11.9	191	2.04	77.9	3.1	2.2	309	7.6	20.6	0.1	505	11.11	0.128	15
1092631	Soil	45.2	73.3	12.2	722	0.8	157.2	19.1	404	3.30	72.6	3.0	3.9	33	6.2	14.0	0.2	195	0.37	0.135	25
REP 1092631	QC	44.1	74.9	12.4	704	0.7	159.2	19.8	429	3.30	74.1	3.3	3.9	33	5.9	14.1	0.1	192	0.37	0.139	23
1092642	Soil	21.0	28.3	7.3	261	0.3	81.6	7.9	87	1.90	45.8	2.5	0.5	11	1.0	6.0	0.1	140	0.07	0.087	11
REP 1092642	QC	21.2	27.4	7.3	260	0.4	82.4	8.1	86	1.92	46.4	5.5	0.2	11	0.9	5.7	0.1	147	0.07	0.088	12
1092664	Soil	2.4	49.5	18.3	136	1.7	41.6	9.0	109	3.15	25.5	4.2	1.3	39	0.3	1.5	0.2	23	0.09	0.086	2
REP 1092664	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092673	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1092673	QC																				
1092700	Soil	4.8	52.4	17.6	137	0.4	34.4	7.8	171	3.76	14.1	1.1	1.2	9	0.1	2.0	0.4	64	0.02	0.082	10
REP 1092700	QC	4.7	53.3	16.4	138	0.4	32.3	8.0	174	3.72	12.4	2.1	1.3	7	0.2	2.2	0.4	63	0.02	0.086	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000747.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1092210	Soil	108	0.65	846	0.003	7	0.84	0.004	0.11	0.4	0.33	10.9	1.3	0.05	3	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092210	QC	108	0.67	852	0.003	7	0.87	0.004	0.12	0.4	0.32	10.8	1.2	0.06	2	5.3	<0.2				
1092223	Soil	181	0.79	3155	0.005	15	0.88	0.003	0.23	0.3	2.08	22.9	0.3	<0.05	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092223	QC	187	0.78	2798	0.004	17	0.95	0.004	0.22	0.2	2.46	22.0	0.3	<0.05	3	2.3	<0.2				
1092237	Soil	12	0.05	368	0.003	3	0.32	0.008	0.14	0.2	1.18	0.1	1.4	0.24	3	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092237	QC	13	0.05	384	0.004	5	0.34	0.009	0.15	0.3	1.19	0.2	1.5	0.26	3	5.6	<0.2				
1092421	Soil	14	0.05	593	0.002	2	0.60	0.012	0.04	<0.1	0.29	0.7	0.5	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092421	QC	15	0.05	588	0.002	<1	0.61	0.012	0.04	<0.1	0.27	0.8	0.5	<0.05	2	1.5	<0.2				
1092448	Soil	10	0.05	192	0.001	3	0.27	<0.001	0.06	<0.1	0.29	2.9	0.2	<0.05	<1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092448	QC	9	0.05	192	0.001	3	0.27	0.001	0.06	<0.1	0.26	2.7	0.1	<0.05	<1	2.1	<0.2				
1092462	Soil	31	0.21	684	0.005	4	0.72	0.006	0.09	0.1	0.86	4.8	0.9	<0.05	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092462	QC	29	0.21	665	0.006	3	0.67	0.005	0.09	0.2	0.84	4.7	0.9	<0.05	2	4.5	<0.2				
1092480	Soil	14	0.11	1264	0.008	5	0.76	0.003	0.09	0.1	0.03	2.0	0.1	<0.05	3	<0.5	0.2	N.A.	N.A.	N.A.	N.A.
REP 1092480	QC	12	0.11	1254	0.005	3	0.74	0.002	0.08	<0.1	0.06	2.2	0.2	<0.05	3	<0.5	0.5				
1092601	Soil	26	2.28	364	0.004	9	0.44	0.007	0.13	0.3	0.22	2.6	2.3	<0.05	1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092601	QC	27	2.23	364	0.005	9	0.44	0.007	0.13	0.3	0.26	2.8	2.6	<0.05	1	4.2	<0.2				
1092604	Soil	38	3.03	354	0.005	12	0.44	0.007	0.16	0.3	0.73	3.2	3.5	0.14	1	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092604	QC	35	3.02	338	0.004	8	0.41	0.006	0.14	0.3	0.72	3.1	3.4	0.12	1	3.2	<0.2				
1092631	Soil	41	0.19	751	0.004	6	0.55	0.002	0.09	0.2	2.63	6.5	0.3	<0.05	1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092631	QC	41	0.19	724	0.004	7	0.53	0.002	0.09	0.2	2.66	6.8	0.3	<0.05	2	4.5	<0.2				
1092642	Soil	21	0.04	168	0.004	2	0.31	0.010	0.06	0.1	0.38	0.8	0.5	<0.05	2	1.2	0.3	N.A.	N.A.	N.A.	N.A.
REP 1092642	QC	22	0.04	174	0.005	1	0.33	0.011	0.06	0.2	0.37	0.9	0.5	<0.05	2	1.8	<0.2				
1092664	Soil	26	0.08	768	0.001	2	0.80	0.007	0.10	0.1	0.37	4.6	<0.1	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092664	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1092673	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.9	37.6	16.0	178
REP 1092673	QC																	2.9	36.3	15.8	178
1092700	Soil	23	0.08	252	0.008	<1	0.87	0.003	0.06	0.1	0.05	2.3	0.2	<0.05	5	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092700	QC	21	0.08	256	0.012	5	0.85	0.002	0.07	0.1	0.06	2.5	0.2	0.05	5	1.7	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000747.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1092210	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092210	QC																					
1092223	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092223	QC																					
1092237	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092237	QC																					
1092421	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092421	QC																					
1092448	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092448	QC																					
1092462	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092462	QC																					
1092480	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092480	QC																					
1092601	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092601	QC																					
1092604	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092604	QC																					
1092631	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092631	QC																					
1092642	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092642	QC																					
1092664	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092664	QC																					
1092673	Soil		1.2	56.2	7.5	114	2.53	25.3	6.9	1.4	58	0.8	0.6	0.2	36	0.75	0.102	7	29	0.11	706	0.001
REP 1092673	QC		1.2	54.7	7.3	113	2.49	24.2	6.4	1.2	57	0.7	0.3	0.2	35	0.73	0.102	7	29	0.11	694	0.001
1092700	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092700	QC																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000747.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1092210	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092210	QC													
1092223	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092223	QC													
1092237	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092237	QC													
1092421	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092421	QC													
1092448	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092448	QC													
1092462	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092462	QC													
1092480	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092480	QC													
1092601	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092601	QC													
1092604	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092604	QC													
1092631	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092631	QC													
1092642	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092642	QC													
1092664	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092664	QC													
1092673	Soil		<20	0.83	0.007	0.10	<0.1	0.31	3.8	0.1	<0.05	2	3.3	<0.2
REP 1092673	QC		<20	0.85	0.006	0.10	<0.1	0.31	3.9	0.1	0.06	2	2.6	<0.2
1092700	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092700	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000747.3

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1092706	Soil	6.2	45.1	14.9	252	1.0	40.3	8.6	383	2.51	16.0	10.4	1.9	51	2.3	5.9	0.2	96	0.19	0.119	7
REP 1092706	QC	6.5	45.9	15.1	254	0.9	41.8	9.2	390	2.43	18.0	28.7	1.8	52	1.9	6.0	0.3	97	0.21	0.122	7
1092760	Soil	1.6	18.7	10.1	160	0.8	32.2	5.1	191	1.70	11.6	7.3	0.5	51	2.6	1.4	0.2	41	1.53	0.150	10
REP 1092760	QC	1.5	19.7	10.3	167	0.8	32.5	5.1	194	1.73	11.7	8.7	0.5	54	2.7	1.5	0.2	45	1.62	0.160	11
1092773	Soil	0.3	6.1	2.4	38	<0.1	6.3	1.1	55	0.44	2.0	1.1	<0.1	31	0.3	0.3	<0.1	13	0.90	0.064	3
REP 1092773	QC	0.3	6.0	2.5	39	<0.1	6.7	1.3	54	0.44	1.8	1.6	<0.1	33	0.3	0.3	<0.1	12	0.87	0.062	3
1092807	Soil	7.6	42.2	13.1	200	0.7	32.6	5.4	134	1.97	16.9	5.7	0.7	42	1.2	4.5	0.2	78	0.14	0.081	7
REP 1092807	QC	7.7	40.0	12.6	199	0.7	33.5	5.4	135	2.02	17.2	5.7	0.7	43	1.1	4.4	0.2	83	0.15	0.080	7
1092852	Soil	7.6	61.7	80.8	122	1.3	37.2	4.5	92	2.58	28.7	10.6	1.0	106	0.7	3.1	0.4	76	0.15	0.251	14
REP 1092852	QC	6.9	57.4	76.2	116	1.3	35.0	4.0	87	2.48	27.6	10.6	0.9	103	0.8	2.9	0.4	71	0.16	0.244	13
1092867	Soil	5.1	86.0	30.8	135	1.5	30.9	8.3	354	5.36	39.6	12.4	2.2	21	0.2	1.9	0.5	43	<0.01	0.102	2
REP 1092867	QC	5.0	83.4	31.5	133	1.6	30.8	8.2	358	5.30	39.7	12.8	2.2	22	0.1	2.0	0.5	39	0.01	0.101	2
Reference Materials																					
STD DS8	Standard	12.4	105.3	125.7	310	1.8	34.5	7.3	591	2.40	26.4	111.1	6.9	58	2.1	5.1	5.7	40	0.68	0.078	14
STD DS8	Standard	13.1	103.7	128.4	309	1.8	34.1	7.0	600	2.40	26.5	120.1	7.2	59	2.6	4.7	5.7	40	0.69	0.078	14
STD DS8	Standard	11.9	108.9	123.5	315	1.8	38.2	7.4	603	2.47	26.8	113.3	6.3	63	2.5	5.9	7.0	41	0.67	0.082	13
STD DS8	Standard	12.7	108.7	125.8	314	1.7	38.0	7.6	610	2.48	26.7	115.3	6.7	65	2.5	6.0	6.9	40	0.68	0.079	13
STD DS8	Standard	14.6	122.4	138.7	337	2.0	42.6	8.4	676	2.73	28.9	115.0	7.5	73	2.4	6.3	7.5	48	0.76	0.084	15
STD DS8	Standard	14.3	118.3	133.8	331	1.9	41.1	8.1	662	2.66	29.7	106.8	7.2	72	2.5	6.1	7.6	46	0.76	0.083	16
STD DS8	Standard	13.4	111.5	121.2	302	1.9	39.3	7.9	619	2.43	28.4	118.7	6.5	68	2.4	5.4	6.9	45	0.68	0.085	15
STD DS8	Standard	13.3	122.1	122.1	309	1.7	44.4	8.0	609	2.45	26.5	108.1	6.2	65	2.5	5.0	6.3	47	0.72	0.079	15
STD DS8	Standard	15.0	114.1	130.6	324	1.8	41.2	7.9	594	2.34	26.2	110.9	5.6	58	2.4	5.6	7.3	39	0.61	0.082	14
STD DS8	Standard	15.0	119.1	101.8	328	1.8	39.3	8.1	639	2.60	28.8	114.8	5.9	63	2.5	5.3	5.9	45	0.73	0.085	15
STD DS8	Standard	12.0	99.0	124.6	285	1.7	35.2	6.9	550	2.20	23.9	128.7	6.3	61	2.5	5.6	7.0	39	0.60	0.072	13
STD DS8	Standard	13.8	116.3	113.7	321	1.9	42.0	8.3	629	2.50	29.1	124.3	6.2	58	2.4	5.6	6.2	42	0.68	0.077	13
STD DS8	Standard	12.8	105.3	124.0	298	1.7	36.1	6.9	588	2.39	26.2	102.9	6.6	65	2.3	5.7	6.4	40	0.64	0.077	14
STD DS8	Standard	12.8	108.2	134.0	312	1.8	36.8	7.2	607	2.46	26.0	105.8	7.2	71	2.2	5.9	7.0	42	0.67	0.073	15
STD DS8	Standard	14.0	112.6	129.5	319	1.8	38.2	7.6	616	2.53	24.8	120.4	7.4	72	2.4	6.2	7.0	41	0.75	0.082	16
STD DS8	Standard	13.3	107.6	125.5	316	1.7	36.7	7.1	607	2.49	23.9	116.5	6.2	70	2.1	6.1	6.6	42	0.67	0.080	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000747.3

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1092706	Soil	21	0.13	1612	0.004	<1	0.83	0.004	0.13	0.1	0.63	2.7	0.3	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092706	QC	23	0.14	1694	0.004	<1	0.88	0.005	0.14	0.2	0.58	3.0	0.4	0.06	2	2.7	<0.2				
1092760	Soil	27	0.05	754	0.005	2	0.85	0.003	0.02	<0.1	1.18	1.3	<0.1	0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092760	QC	28	0.06	766	0.005	2	0.89	0.003	0.02	<0.1	1.22	1.4	<0.1	0.06	2	1.1	<0.2				
1092773	Soil	6	0.03	104	0.004	<1	0.44	0.024	0.03	<0.1	0.06	0.3	<0.1	0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092773	QC	6	0.03	105	0.005	<1	0.43	0.025	0.02	<0.1	0.07	0.3	<0.1	<0.05	1	<0.5	<0.2				
1092807	Soil	15	0.08	494	0.002	2	0.59	0.008	0.08	0.1	0.23	1.3	0.2	0.08	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092807	QC	16	0.09	494	0.002	3	0.60	0.008	0.09	0.1	0.20	1.3	0.3	0.06	3	2.4	<0.2				
1092852	Soil	15	0.04	611	0.004	14	0.48	0.005	0.22	0.1	0.82	1.3	0.3	0.31	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092852	QC	14	0.04	594	0.003	15	0.48	0.004	0.21	<0.1	0.81	1.3	0.2	0.27	1	1.7	<0.2				
1092867	Soil	16	0.08	1132	0.004	11	0.82	0.006	0.09	0.1	0.09	3.7	0.2	0.08	3	3.3	0.2	N.A.	N.A.	N.A.	N.A.
REP 1092867	QC	16	0.09	1168	0.003	16	0.84	0.006	0.09	0.1	0.08	3.7	0.2	0.06	3	2.1	0.5				
Reference Materials																					
STD DS8	Standard	108	0.58	274	0.100	3	0.86	0.082	0.42	3.0	0.22	2.3	5.4	0.15	5	5.7	5.5				
STD DS8	Standard	110	0.56	277	0.106	3	0.87	0.085	0.42	2.8	0.21	2.4	5.3	0.14	5	5.2	5.1				
STD DS8	Standard	115	0.61	273	0.105	2	0.88	0.083	0.42	3.1	0.22	2.0	5.5	0.13	5	5.2	5.1				
STD DS8	Standard	114	0.60	277	0.109	3	0.87	0.083	0.41	3.0	0.18	2.1	5.5	0.15	5	4.9	4.8				
STD DS8	Standard	132	0.65	293	0.137	2	0.97	0.095	0.45	3.3	0.21	2.4	5.7	0.17	5	6.1	5.4				
STD DS8	Standard	131	0.65	290	0.136	2	0.97	0.097	0.44	3.1	0.20	2.7	5.6	0.17	5	4.8	5.3				
STD DS8	Standard	116	0.63	274	0.111	4	0.92	0.090	0.41	3.0	0.18	2.1	5.4	0.17	5	4.8	5.0				
STD DS8	Standard	120	0.62	281	0.111	3	0.92	0.091	0.43	2.9	0.19	2.0	5.3	0.15	5	5.3	5.4				
STD DS8	Standard	118	0.63	235	0.092	3	0.80	0.072	0.39	2.9	0.19	1.5	5.5	0.12	4	4.1	4.7				
STD DS8	Standard	122	0.62	298	0.122	3	0.96	0.094	0.43	3.2	0.20	2.0	5.6	0.19	5	5.0	5.3				
STD DS8	Standard	105	0.57	263	0.100	2	0.79	0.072	0.36	3.0	0.20	1.8	5.5	<0.05	5	5.2	5.3				
STD DS8	Standard	128	0.59	273	0.118	2	0.91	0.087	0.42	3.1	0.22	2.3	5.4	0.16	5	5.8	4.5				
STD DS8	Standard	113	0.61	287	0.113	5	0.87	0.095	0.40	3.1	0.18	2.2	5.2	0.09	4	4.9	5.1				
STD DS8	Standard	114	0.62	272	0.113	2	0.93	0.099	0.42	2.8	0.21	2.1	5.4	0.14	5	6.2	4.8				
STD DS8	Standard	120	0.68	297	0.124	3	0.97	0.103	0.44	3.1	0.21	2.4	5.6	0.18	5	5.4	4.3				
STD DS8	Standard	112	0.61	289	0.112	4	0.90	0.109	0.44	3.1	0.21	2.1	5.5	0.13	5	4.0	5.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000747.3

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1092706	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092706	QC																				
1092760	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092760	QC																				
1092773	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092773	QC																				
1092807	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092807	QC																				
1092852	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092852	QC																				
1092867	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092867	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000747.3

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1092706	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092706	QC												
1092760	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092760	QC												
1092773	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092773	QC												
1092807	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092807	QC												
1092852	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092852	QC												
1092867	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092867	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000747.3

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	12.1	105.8	122.1	307	1.6	36.8	7.1	608	2.39	23.7	115.8	6.1	71	2.1	5.7	6.4	39	0.66	0.078	14
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	1.2	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	2.7	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000747.3

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
STD DS8	Standard	110	0.61	287	0.111	3	0.90	0.108	0.46	3.0	0.21	2.2	5.3	0.14	5	5.6	5.8				
STD DS8	Standard																	13.8	114.4	130.1	309
STD OREAS45CA	Standard																	1.0	536.7	20.0	62
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	7	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000747.3

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
STD DS8	Standard																				
STD DS8	Standard	1.9	38.8	8.0	635	2.50	23.9	99.5	7.4	73	2.4	5.4	7.0	45	0.72	0.076	16	122	0.60	297	0.123
STD OREAS45CA	Standard	0.3	252.6	88.8	895	16.54	4.1	45.8	6.9	16	0.1	0.1	0.2	203	0.42	0.036	16	732	0.16	165	0.149
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000747.3

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
STD DS8	Standard												
STD DS8	Standard	<20	0.94	0.096	0.42	3.3	0.18	2.4	5.5	0.15	5	5.2	4.8
STD OREAS45CA	Standard	<20	3.78	0.013	0.07	<0.1	0.03	36.8	<0.1	<0.05	18	0.8	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 26, 2011
Report Date: August 26, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11000748.3

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #5
P.O. Number
Number of Samples: 43

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	42	Sieve to 230 mesh			WHI
1DX2	42	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Version 3: Correction of sample ID's (1092879 to 1092885)

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis



This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 26, 2011

CERTIFICATE OF ANALYSIS WHI11000748.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092879	Soil	30.0	15.5	5.7	53	0.1	24.1	1.4	13	1.00	15.1	<0.5	0.4	3	<0.1	1.3	0.1	70	<0.01	0.071	11
1092880	Soil	50.1	29.6	10.0	139	0.2	83.3	5.9	74	1.81	26.8	<0.5	0.3	4	0.2	3.1	0.2	67	0.01	0.073	12
1092881	Soil	5.8	32.6	10.8	72	1.4	29.2	3.4	49	1.61	13.2	1.9	0.4	7	0.4	2.4	0.2	25	0.04	0.072	7
1092882	Soil	11.4	41.4	13.7	195	0.7	43.8	9.7	368	2.61	34.8	1.6	1.0	16	1.5	4.7	0.2	55	0.11	0.120	13
1092883	Soil	9.2	33.0	12.7	125	0.2	42.7	6.0	88	2.44	23.0	0.7	0.2	7	0.3	3.5	0.2	78	0.01	0.072	9
1092884	Soil	8.0	26.4	45.7	135	0.7	52.4	5.1	70	1.56	14.4	1.7	<0.1	8	3.3	2.3	0.2	32	0.04	0.086	4
1092885	Soil	18.8	26.9	12.4	203	0.5	45.1	4.5	67	1.94	25.8	2.6	0.1	17	0.9	4.7	0.2	141	0.02	0.085	9
1092886	Soil	2.8	54.2	29.4	240	0.7	91.9	18.9	189	4.62	29.6	1.7	1.7	23	0.4	1.4	0.3	26	0.20	0.068	4
1092887	Soil	10.1	42.8	20.6	159	2.0	57.7	5.3	53	2.44	29.1	6.6	0.9	80	0.6	2.7	0.2	34	0.12	0.085	4
1092888	Soil	1.6	20.6	9.8	70	0.7	19.8	3.3	32	1.37	13.6	1.5	<0.1	15	0.3	1.1	0.1	20	0.02	0.061	2
1092889	Soil	2.4	33.5	11.7	104	0.7	32.0	5.4	49	2.22	26.8	2.2	0.5	25	0.2	1.9	0.2	29	0.01	0.068	2
1092890	Soil	18.2	21.4	22.6	85	2.4	22.9	2.3	45	2.30	21.6	4.7	0.9	78	0.7	7.8	0.3	191	0.71	0.074	3
1093371	Soil	2.7	32.6	14.3	129	1.0	42.0	5.7	119	2.24	17.4	6.4	1.1	67	0.6	1.2	0.2	27	0.78	0.092	4
1093372	Soil	1.5	20.6	7.1	84	0.6	27.7	4.0	90	1.54	23.9	3.2	0.3	45	0.6	1.4	<0.1	19	1.00	0.084	3
1093373	Soil	1.2	8.3	4.4	34	0.3	8.1	2.0	181	0.74	8.8	<0.5	0.1	17	0.2	0.6	<0.1	17	0.20	0.083	1
1093374	Soil	2.2	33.9	13.4	157	1.1	40.3	5.9	183	2.15	68.5	9.3	0.8	63	0.6	2.7	0.2	42	0.64	0.151	7
1093375	Soil	1.4	14.7	7.6	57	0.9	14.7	1.6	104	0.88	17.2	2.1	0.2	40	0.3	1.0	<0.1	19	0.57	0.122	3
1093376	Soil	0.1	2.5	1.2	3	0.2	1.0	0.5	25	0.22	1.6	<0.5	<0.1	11	<0.1	<0.1	<0.1	4	0.18	0.044	2
1093377	Soil	2.4	22.7	7.4	90	0.7	22.7	2.3	71	1.39	32.4	3.4	0.3	48	0.6	1.6	0.1	23	0.41	0.115	4
1093378	Soil	6.9	43.8	16.0	204	1.6	62.2	4.9	97	2.39	48.5	5.6	0.8	98	0.7	2.7	0.2	31	0.50	0.112	4
1093379	Soil	4.7	42.2	16.2	142	0.5	34.6	4.5	67	2.66	37.5	4.5	0.7	21	0.2	2.2	0.2	46	0.01	0.075	2
1093380	Soil	2.2	15.2	4.1	51	0.3	11.0	1.5	23	1.06	22.1	<0.5	0.3	5	<0.1	1.4	0.1	44	<0.01	0.022	2
1093381	Soil	2.0	9.3	2.5	33	0.3	6.4	0.8	13	0.68	10.0	<0.5	0.5	5	<0.1	0.7	<0.1	31	<0.01	0.017	4
1093382	Soil	8.1	32.1	21.5	89	2.4	17.6	2.0	35	2.39	44.5	1.7	0.7	71	0.1	5.3	0.3	91	<0.01	0.075	3
1093383	Soil	3.8	20.5	21.4	43	2.6	11.7	1.1	16	1.65	92.6	17.2	1.2	96	<0.1	9.4	0.4	17	0.05	0.029	1
1093384	Soil	3.5	55.8	15.9	107	3.4	41.3	4.2	73	2.55	39.2	22.4	0.7	82	0.4	2.7	0.3	24	0.50	0.089	2
1093385	Soil	13.1	81.7	13.3	92	4.0	48.9	1.5	12	2.20	34.6	7.3	1.2	89	0.1	3.2	0.2	28	0.03	0.091	4
1093386	Soil	1.3	6.7	2.9	20	0.7	4.4	0.7	9	0.58	14.0	<0.5	<0.1	6	<0.1	1.0	<0.1	16	0.01	0.022	<1
1093387	Soil	8.9	30.2	16.1	93	4.4	30.1	1.5	16	2.17	29.1	6.2	0.4	63	<0.1	2.4	0.2	27	0.02	0.066	2
1093388	Soil	4.8	19.6	14.6	28	4.5	9.3	0.6	10	1.37	17.5	33.6	0.3	41	<0.1	0.9	0.2	26	0.11	0.107	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 26, 2011

CERTIFICATE OF ANALYSIS WHI11000748.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092879	Soil	13	0.06	151	0.003	2	0.69	0.003	0.05	0.1	0.04	0.3	0.8	<0.05	2	0.7	<0.2
1092880	Soil	12	0.04	93	0.004	3	0.47	0.002	0.05	0.1	0.07	0.4	0.5	<0.05	2	1.5	<0.2
1092881	Soil	7	0.02	150	0.004	2	0.40	0.009	0.04	<0.1	0.45	0.8	0.1	<0.05	1	0.6	<0.2
1092882	Soil	10	0.03	307	0.001	2	0.41	0.001	0.05	<0.1	1.09	2.3	0.2	<0.05	<1	0.6	<0.2
1092883	Soil	14	0.05	106	0.002	3	0.52	0.002	0.05	<0.1	0.06	0.3	0.2	<0.05	3	0.9	<0.2
1092884	Soil	40	0.03	189	<0.001	2	0.33	0.010	0.06	<0.1	0.14	0.2	0.2	<0.05	2	1.0	<0.2
1092885	Soil	15	0.05	317	0.001	2	0.50	0.003	0.06	0.1	0.26	0.3	0.3	<0.05	2	2.3	<0.2
1092886	Soil	28	0.25	530	<0.001	2	1.22	0.004	0.06	<0.1	0.20	5.1	<0.1	<0.05	3	3.1	<0.2
1092887	Soil	29	0.04	444	0.001	2	0.54	0.006	0.08	<0.1	0.36	2.5	0.1	0.06	2	6.2	<0.2
1092888	Soil	9	0.02	139	0.001	2	0.32	0.013	0.04	<0.1	0.07	0.4	<0.1	<0.05	2	<0.5	<0.2
1092889	Soil	13	0.03	186	0.001	2	0.53	0.006	0.06	<0.1	0.13	1.6	<0.1	<0.05	2	2.1	<0.2
1092890	Soil	16	0.03	716	0.002	4	0.38	0.013	0.18	0.2	0.21	1.5	0.9	0.38	1	7.5	<0.2
1093371	Soil	20	0.06	456	<0.001	3	0.54	0.007	0.07	<0.1	0.40	2.6	<0.1	0.07	1	1.5	<0.2
1093372	Soil	9	0.03	475	0.003	3	0.54	0.024	0.03	<0.1	0.26	1.2	<0.1	0.06	1	1.7	<0.2
1093373	Soil	7	0.03	206	0.003	1	0.37	0.021	0.04	<0.1	0.05	0.4	<0.1	0.06	2	<0.5	<0.2
1093374	Soil	25	0.08	872	0.002	2	0.85	0.007	0.06	<0.1	0.83	2.4	0.1	<0.05	2	1.5	<0.2
1093375	Soil	12	0.03	764	0.004	3	0.68	0.023	0.04	<0.1	0.38	0.7	<0.1	0.07	2	1.4	<0.2
1093376	Soil	1	0.02	82	0.012	<1	0.34	0.040	0.03	<0.1	0.03	0.4	<0.1	<0.05	1	<0.5	<0.2
1093377	Soil	13	0.05	713	0.003	3	0.73	0.019	0.05	<0.1	0.70	1.0	<0.1	0.05	2	2.5	<0.2
1093378	Soil	23	0.04	1321	0.001	3	0.68	0.009	0.07	<0.1	1.29	2.7	0.1	<0.05	2	4.3	<0.2
1093379	Soil	17	0.02	268	<0.001	1	0.54	0.004	0.06	<0.1	0.11	1.6	0.1	<0.05	2	2.1	<0.2
1093380	Soil	8	0.02	231	0.001	2	0.38	0.005	0.04	<0.1	0.06	0.7	<0.1	<0.05	3	0.8	<0.2
1093381	Soil	6	0.01	169	0.002	2	0.32	0.005	0.04	<0.1	0.02	0.5	<0.1	<0.05	3	<0.5	<0.2
1093382	Soil	16	0.02	596	0.002	1	0.42	0.004	0.09	0.1	0.08	1.4	0.4	0.09	3	4.6	<0.2
1093383	Soil	10	0.02	642	<0.001	3	0.26	0.003	0.12	<0.1	1.90	2.2	0.2	0.15	1	6.6	<0.2
1093384	Soil	16	0.04	767	<0.001	5	0.56	0.007	0.09	<0.1	1.55	3.8	0.1	0.09	2	5.2	<0.2
1093385	Soil	28	0.01	475	<0.001	2	0.59	0.004	0.08	<0.1	0.78	4.0	0.1	<0.05	1	7.1	<0.2
1093386	Soil	5	0.01	92	0.002	2	0.19	0.020	0.03	<0.1	0.03	0.4	<0.1	<0.05	1	<0.5	<0.2
1093387	Soil	25	0.01	481	<0.001	3	0.36	0.005	0.08	<0.1	0.37	1.5	0.1	0.07	1	5.5	<0.2
1093388	Soil	20	0.02	496	0.002	4	0.82	0.015	0.06	<0.1	0.60	0.8	0.1	<0.05	2	3.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 26, 2011

CERTIFICATE OF ANALYSIS WHI11000748.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1093389	Soil	0.8	3.8	2.7	5	1.0	3.2	0.2	5	0.12	1.8	0.9	<0.1	7	<0.1	0.2	<0.1	8	0.04	0.042	2
1093390	Soil	2.8	6.5	2.4	19	0.5	3.9	0.8	15	0.47	5.5	<0.5	<0.1	4	<0.1	0.7	<0.1	34	0.01	0.024	6
1091641	Soil	73.1	80.3	15.7	1012	0.7	154.2	11.2	288	3.05	52.0	<0.5	0.3	43	10.0	21.9	0.1	414	0.75	0.137	9
1091643	Soil	17.5	74.4	39.7	162	1.6	226.3	36.1	452	4.39	27.9	1.7	1.5	82	2.0	7.9	0.2	148	0.77	0.232	12
1091644	Soil	16.7	115.1	39.1	358	1.5	334.2	61.7	610	5.15	28.2	1.6	4.5	80	3.5	9.8	0.2	149	0.86	0.316	16
1091645	Soil	14.2	101.4	37.9	503	1.5	366.3	69.8	1008	6.22	19.4	2.6	2.2	88	3.5	7.2	0.2	157	1.18	0.235	14
1091646	Soil	20.5	114.9	41.6	544	1.5	448.8	85.2	882	7.21	35.7	4.3	3.4	100	4.4	9.7	0.2	179	1.06	0.269	16
1091386	Soil	4.1	35.7	15.7	84	1.6	20.1	3.4	49	2.12	19.0	7.6	0.6	62	0.1	1.7	0.3	41	0.02	0.088	4
1091387	Soil	2.5	30.8	19.5	98	1.3	34.0	9.6	347	3.64	17.9	2.1	1.1	40	0.3	1.1	0.3	25	0.03	0.123	3
1091388	Soil	2.2	31.5	24.8	115	0.9	41.7	10.0	230	3.32	29.4	1.2	2.1	58	0.2	1.2	0.3	29	0.03	0.073	5
1091389	Soil	2.5	37.5	24.1	123	0.7	43.2	14.7	353	3.67	19.2	1.8	1.8	26	0.3	1.0	0.3	35	0.05	0.105	6
1091390	Soil	2.8	28.3	23.7	86	0.6	26.9	6.9	273	3.56	25.4	3.3	0.5	20	0.1	1.4	0.3	43	0.02	0.123	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 26, 2011

CERTIFICATE OF ANALYSIS WHI11000748.3

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093389	Soil	3	0.01	97	0.004	<1	0.40	0.026	0.03	<0.1	0.14	0.1	<0.1	<0.05	2	1.3	<0.2
1093390	Soil	6	0.01	161	0.003	2	0.28	0.009	0.04	<0.1	0.03	0.1	<0.1	<0.05	2	<0.5	<0.2
1091641	Soil	37	0.16	260	0.003	2	0.59	0.013	0.06	0.1	0.18	1.9	1.0	<0.05	2	6.8	<0.2
1091643	Soil	94	0.08	359	0.003	4	0.57	0.015	0.10	<0.1	0.44	10.2	0.6	0.09	2	3.6	<0.2
1091644	Soil	90	0.08	380	0.005	4	0.52	0.011	0.13	<0.1	0.40	17.5	0.5	0.09	2	5.4	<0.2
1091645	Soil	98	0.24	481	0.006	6	0.59	0.012	0.09	<0.1	0.33	15.1	0.6	0.40	1	4.5	<0.2
1091646	Soil	113	0.12	407	0.004	3	0.60	0.008	0.11	<0.1	0.30	16.8	0.7	0.29	2	4.2	<0.2
1091386	Soil	15	0.02	291	0.005	4	0.42	0.006	0.09	<0.1	0.28	1.2	0.1	0.23	3	4.4	<0.2
1091387	Soil	22	0.09	175	0.003	2	0.78	0.008	0.07	<0.1	0.16	1.9	0.1	0.19	2	1.8	<0.2
1091388	Soil	20	0.13	242	0.002	<1	0.84	0.006	0.09	<0.1	0.15	2.4	0.1	0.18	3	1.0	<0.2
1091389	Soil	26	0.20	195	0.003	<1	1.05	0.006	0.08	<0.1	0.09	2.9	0.2	0.16	3	1.1	<0.2
1091390	Soil	27	0.08	116	0.005	1	0.89	0.005	0.07	0.1	0.12	1.3	0.1	0.21	4	1.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 26, 2011

QUALITY CONTROL REPORT WHI11000748.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1092887	Soil	10.1	42.8	20.6	159	2.0	57.7	5.3	53	2.44	29.1	6.6	0.9	80	0.6	2.7	0.2	34	0.12	0.085	4
REP 1092887	QC	10.1	42.9	21.3	157	1.9	56.7	5.2	54	2.41	29.6	8.3	0.9	80	0.6	2.8	0.2	34	0.11	0.085	4
1091644	Soil	16.7	115.1	39.1	358	1.5	334.2	61.7	610	5.15	28.2	1.6	4.5	80	3.5	9.8	0.2	149	0.86	0.316	16
REP 1091644	QC	17.7	114.8	39.5	353	1.5	329.6	61.1	593	5.11	29.2	0.8	4.5	81	3.6	9.3	0.2	143	0.81	0.311	16
1091387	Soil	2.5	30.8	19.5	98	1.3	34.0	9.6	347	3.64	17.9	2.1	1.1	40	0.3	1.1	0.3	25	0.03	0.123	3
REP 1091387	QC	2.3	31.1	18.7	98	1.3	34.7	9.8	365	3.80	16.8	3.4	1.2	40	0.2	1.0	0.3	27	0.03	0.125	3
Reference Materials																					
STD DS8	Standard	15.5	123.4	134.4	336	1.8	41.0	8.1	631	2.53	29.2	108.7	7.4	71	2.4	5.9	7.3	51	0.75	0.079	16
STD DS8	Standard	15.2	119.2	132.1	322	1.9	41.8	7.9	647	2.60	30.3	122.2	7.3	72	2.4	5.8	7.4	50	0.73	0.079	16
STD DS8	Standard	13.3	105.2	121.7	306	1.7	37.7	7.4	598	2.40	25.1	100.2	6.6	69	2.0	5.4	6.6	41	0.65	0.071	14
STD DS8	Standard	13.0	99.2	117.4	293	1.7	34.3	7.0	580	2.32	24.3	127.5	6.4	69	2.1	5.2	6.6	40	0.67	0.075	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 26, 2011

QUALITY CONTROL REPORT WHI11000748.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1092887	Soil	29	0.04	444	0.001	2	0.54	0.006	0.08	<0.1	0.36	2.5	0.1	0.06	2	6.2	<0.2
REP 1092887	QC	31	0.04	436	0.001	4	0.53	0.005	0.08	<0.1	0.36	2.3	0.2	<0.05	2	5.8	<0.2
1091644	Soil	90	0.08	380	0.005	4	0.52	0.011	0.13	<0.1	0.40	17.5	0.5	0.09	2	5.4	<0.2
REP 1091644	QC	86	0.09	364	0.003	3	0.51	0.011	0.13	<0.1	0.40	16.8	0.6	0.10	2	3.7	0.3
1091387	Soil	22	0.09	175	0.003	2	0.78	0.008	0.07	<0.1	0.16	1.9	0.1	0.19	2	1.8	<0.2
REP 1091387	QC	22	0.09	179	0.003	5	0.78	0.008	0.08	<0.1	0.14	2.2	0.2	0.32	3	2.1	<0.2
Reference Materials																	
STD DS8	Standard	129	0.67	281	0.128	4	0.96	0.093	0.43	3.0	0.24	2.5	5.4	0.26	5	5.9	5.0
STD DS8	Standard	130	0.65	286	0.133	4	0.96	0.095	0.43	3.2	0.21	2.7	5.3	0.25	5	5.3	5.0
STD DS8	Standard	118	0.64	253	0.113	3	0.87	0.089	0.40	2.6	0.20	2.1	5.1	0.13	5	4.7	5.0
STD DS8	Standard	113	0.63	263	0.112	3	0.88	0.094	0.39	2.9	0.20	2.1	4.9	0.13	4	5.2	5.3
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 28, 2011
Report Date: September 01, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11000766.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #6
P.O. Number
Number of Samples: 309

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	309	Sieve soil to 230 mesh			WHI
1DX2	280	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	28	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 3: Corrected sample ID's (1091647 - 1091649)

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1091647	Soil		16.7	226.9	94.1	794	1.5	511.3	51.2	692	6.53	166.6	7.1	1.4	166	0.6	6.9	0.7	107	1.21	0.707
1091648	Soil		3.8	136.1	27.8	184	2.1	134.8	37.5	1085	8.94	366.5	7.9	4.2	21	<0.1	4.1	0.5	24	0.34	0.064
1091649	Soil		20.1	112.2	52.5	514	0.9	170.9	18.3	178	3.55	47.6	4.0	0.3	27	0.8	5.9	0.5	77	0.20	0.207
1092141	Soil		4.4	16.1	5.3	51	1.2	21.1	2.8	26	0.81	18.4	0.9	0.1	5	0.5	1.6	<0.1	29	0.04	0.105
1092142	Soil		8.6	53.8	14.7	342	0.7	108.7	12.6	84	2.84	59.3	2.1	0.7	4	0.3	6.9	0.2	56	0.05	0.124
1092143	Soil		2.8	69.1	16.5	222	0.7	74.6	14.8	187	2.90	18.3	1.5	1.7	12	0.7	3.5	0.2	20	0.19	0.069
1092144	Soil		22.2	25.0	11.3	131	0.3	41.1	4.9	143	1.68	20.1	1.6	<0.1	23	0.6	2.9	0.2	57	0.21	0.176
1092145	Soil		17.4	13.0	9.2	70	<0.1	21.6	2.7	35	0.91	11.8	1.2	<0.1	12	0.2	1.6	0.2	39	0.12	0.064
1092146	Soil		45.0	51.2	13.5	181	0.2	156.5	14.4	110	3.11	81.9	1.3	0.6	30	0.6	6.4	0.2	82	0.48	0.151
1092147	Soil		48.4	53.4	21.2	159	0.4	163.0	8.6	233	3.07	34.5	1.6	1.4	82	1.6	4.7	0.1	78	4.93	0.084
1092148	Soil		4.9	58.5	13.6	140	0.1	40.4	11.3	139	2.91	10.1	1.3	0.1	4	<0.1	1.7	0.3	48	0.01	0.070
1092149	Soil		5.1	37.5	9.9	108	0.2	28.0	7.4	93	1.87	27.1	1.4	0.1	6	0.1	2.1	0.3	47	0.02	0.050
1092150	Soil		63.0	200.1	17.7	1514	3.7	336.3	8.7	292	2.68	56.3	3.6	1.1	93	23.2	27.4	0.3	440	2.15	0.254
1092151	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092152	Soil		7.3	22.3	8.6	78	<0.1	30.6	5.9	66	1.52	11.6	1.7	<0.1	8	0.2	1.8	0.1	63	0.02	0.056
1092153	Soil		4.5	11.6	8.5	42	0.4	14.9	2.5	29	0.70	8.4	0.7	<0.1	7	<0.1	1.1	0.1	36	0.01	0.034
1092154	Soil		12.6	53.3	27.7	222	0.4	82.2	12.5	165	3.25	49.7	1.3	0.2	38	0.7	4.0	0.3	59	0.08	0.181
1092155	Soil		9.2	75.2	43.4	269	1.8	82.7	11.4	214	3.40	53.6	7.2	1.9	94	0.5	4.4	0.4	34	0.54	0.308
1092156	Soil		12.5	32.2	14.7	230	0.1	45.5	5.9	67	2.05	20.8	0.7	0.2	8	0.9	5.0	0.2	102	0.02	0.061
1092157	Soil		2.3	4.8	2.8	37	0.3	8.1	1.0	15	0.36	2.0	<0.5	<0.1	4	0.2	1.0	<0.1	16	0.04	0.035
1092158	Soil		13.0	24.6	6.6	118	0.3	40.7	2.9	84	0.99	10.0	0.5	0.2	34	1.0	2.4	<0.1	46	0.73	0.066
1092159	Soil		19.4	18.2	8.7	131	0.1	40.8	3.2	40	0.97	17.8	1.3	0.2	8	0.6	3.7	<0.1	145	0.04	0.074
1092160	Soil		2.7	9.5	2.5	51	0.8	17.3	2.1	30	0.45	3.6	0.6	<0.1	12	0.8	0.8	<0.1	28	0.09	0.040
1092161	Soil		4.0	10.4	6.2	40	1.1	11.3	1.3	24	0.67	5.1	1.1	<0.1	6	0.4	0.9	<0.1	67	0.02	0.075
1092162	Soil		6.2	10.5	9.0	43	0.2	11.2	2.1	34	0.71	7.0	<0.5	0.2	6	0.1	1.0	0.1	55	0.01	0.038
1092163	Soil		22.5	87.8	18.9	420	1.3	188.5	25.5	526	4.97	30.0	2.9	3.6	59	2.1	8.1	0.2	237	0.40	0.258
1092164	Soil		1.2	10.9	2.2	20	0.3	10.3	1.4	73	0.36	3.9	<0.5	0.2	62	1.2	0.6	<0.1	10	1.25	0.066
1092165	Soil		22.1	23.9	12.2	160	0.1	45.6	4.6	51	1.62	21.1	1.0	0.7	12	0.4	3.9	0.1	114	0.02	0.043
1092166	Soil		23.0	21.8	13.0	131	0.2	40.6	4.7	57	1.42	19.4	1.9	0.2	9	0.2	3.1	0.2	113	0.01	0.041
1092167	Soil		22.9	24.6	15.6	148	0.1	47.0	4.9	46	1.55	19.0	0.9	0.1	9	0.1	3.3	0.2	100	0.01	0.071

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1091647	Soil	30	67	0.09	708	0.006	6	0.57	0.003	0.17	0.2	1.72	4.8	0.6	0.29	2	4.8	0.4	N.A.	N.A.	N.A.
1091648	Soil	49	20	0.22	699	0.003	3	0.75	0.003	0.06	<0.1	0.24	9.8	0.2	0.05	2	1.5	<0.2	N.A.	N.A.	N.A.
1091649	Soil	17	15	0.03	375	0.002	2	0.36	0.003	0.07	<0.1	0.40	0.6	0.2	0.08	1	4.9	0.5	N.A.	N.A.	N.A.
1092141	Soil	6	14	0.03	178	0.001	2	0.38	0.009	0.03	<0.1	0.12	0.3	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1092142	Soil	13	24	0.03	117	0.002	2	0.41	0.002	0.04	<0.1	0.06	0.8	0.1	<0.05	2	5.8	<0.2	N.A.	N.A.	N.A.
1092143	Soil	10	17	0.06	365	0.002	2	0.43	0.005	0.04	<0.1	0.11	3.4	0.2	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.
1092144	Soil	7	12	0.06	529	0.001	1	0.52	0.007	0.06	<0.1	0.12	0.2	0.4	0.06	2	1.1	<0.2	N.A.	N.A.	N.A.
1092145	Soil	10	8	0.05	171	0.002	2	0.32	0.003	0.05	<0.1	0.04	0.2	0.4	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1092146	Soil	15	25	0.10	334	0.003	3	0.41	0.002	0.05	0.2	0.17	0.8	0.5	<0.05	1	2.7	<0.2	N.A.	N.A.	N.A.
1092147	Soil	12	18	2.52	343	0.003	5	0.31	0.007	0.04	0.1	0.26	4.0	0.9	0.06	<1	3.5	<0.2	N.A.	N.A.	N.A.
1092148	Soil	3	12	0.02	79	0.002	2	0.42	0.004	0.04	<0.1	0.03	0.6	0.1	0.09	3	1.1	<0.2	N.A.	N.A.	N.A.
1092149	Soil	3	10	0.02	119	0.002	1	0.38	0.009	0.03	<0.1	0.02	0.6	0.1	0.05	2	0.8	<0.2	N.A.	N.A.	N.A.
1092150	Soil	16	79	0.77	559	0.004	5	0.51	0.003	0.12	0.2	1.46	4.0	1.3	0.08	1	25.6	0.3	N.A.	N.A.	N.A.
1092151	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	8.8	49.0	28.9
1092152	Soil	11	12	0.03	162	0.005	3	0.34	0.006	0.05	0.1	0.02	0.2	0.1	0.08	2	<0.5	<0.2	N.A.	N.A.	N.A.
1092153	Soil	7	7	0.02	64	0.003	<1	0.23	0.009	0.03	<0.1	0.02	0.1	0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.
1092154	Soil	12	19	0.05	511	0.004	3	0.52	0.007	0.09	0.1	0.09	0.5	0.2	0.09	2	2.0	<0.2	N.A.	N.A.	N.A.
1092155	Soil	16	11	0.06	1896	0.004	3	0.58	0.005	0.08	<0.1	0.55	3.0	0.2	0.08	1	3.0	0.2	N.A.	N.A.	N.A.
1092156	Soil	8	11	0.03	152	0.002	2	0.46	0.003	0.04	<0.1	0.04	0.3	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.
1092157	Soil	2	4	0.02	60	0.002	1	0.14	0.016	0.02	<0.1	0.05	0.3	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.
1092158	Soil	4	8	0.08	246	0.003	2	0.37	0.018	0.03	<0.1	0.12	0.7	0.2	0.09	1	0.7	<0.2	N.A.	N.A.	N.A.
1092159	Soil	11	18	0.04	159	0.003	4	0.35	0.005	0.06	0.1	0.15	0.4	0.5	0.09	2	1.6	<0.2	N.A.	N.A.	N.A.
1092160	Soil	3	6	0.03	473	0.005	<1	0.32	0.020	0.02	<0.1	0.12	0.3	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.
1092161	Soil	4	17	0.07	111	0.003	<1	0.55	0.014	0.03	<0.1	0.11	0.1	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1092162	Soil	11	9	0.04	94	0.005	<1	0.61	0.004	0.03	<0.1	0.02	0.2	0.3	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.
1092163	Soil	35	154	1.28	455	0.026	4	1.80	0.003	0.08	0.1	0.19	4.6	1.1	<0.05	5	3.6	<0.2	N.A.	N.A.	N.A.
1092164	Soil	2	2	0.11	880	0.010	1	0.30	0.026	0.02	<0.1	0.11	0.5	<0.1	0.10	<1	<0.5	<0.2	N.A.	N.A.	N.A.
1092165	Soil	12	10	0.04	447	0.003	1	0.39	0.005	0.05	0.1	0.06	0.8	0.3	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.
1092166	Soil	14	11	0.04	102	0.005	1	0.49	0.004	0.04	0.1	0.05	0.5	0.4	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.
1092167	Soil	10	10	0.04	88	0.002	2	0.49	0.002	0.04	0.1	0.03	<0.1	0.3	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1091647	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091648	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091649	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092141	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092142	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092143	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092144	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092145	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092146	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092147	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092148	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092149	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092150	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092151	Soil		223	0.2	89.7	21.7	945	3.85	136.6	1.5	0.5	34	0.4	2.2	0.4	46	0.07	0.103	15	24	0.05	474
1092152	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092153	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092154	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092155	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092156	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092157	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092158	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092159	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092160	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092161	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092162	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092163	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092164	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092165	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092166	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092167	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091647	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091648	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091649	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092141	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092142	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092143	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092144	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092145	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092146	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092147	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092148	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092149	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092150	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092151	Soil	0.003	<20	0.53	0.004	0.07	<0.1	0.03	1.6	0.2	0.08	2	2.0	<0.2
1092152	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092153	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092154	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092155	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092156	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092157	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092158	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092159	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092160	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092161	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092162	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092163	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092164	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092165	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092168	Soil		9.2	33.7	12.3	123	0.3	45.4	7.1	65	2.19	16.1	2.4	0.3	10	0.2	3.1	0.2	53	0.03	0.066
1092169	Soil		10.5	35.5	14.7	125	0.4	48.8	7.3	100	2.42	14.7	1.7	0.4	7	0.2	2.9	0.2	51	0.01	0.073
1092170	Soil		4.6	51.4	32.1	49	1.6	55.4	13.1	83	3.38	40.3	6.8	2.3	12	<0.1	4.5	0.4	14	0.03	0.052
1092171	Soil		7.9	88.7	30.7	70	0.9	65.0	12.8	118	4.09	45.5	6.8	1.9	42	0.2	6.8	0.6	26	0.02	0.129
1092172	Soil		8.2	18.3	8.6	71	1.2	21.9	3.6	39	1.24	12.8	1.6	0.2	7	0.1	2.3	0.2	52	0.01	0.065
1092173	Soil		5.3	7.6	3.8	15	<0.1	15.4	1.7	17	0.57	5.4	1.7	0.1	3	<0.1	2.0	<0.1	38	0.01	0.035
1092174	Soil		12.1	7.7	5.6	42	<0.1	11.7	1.2	17	0.57	5.5	1.5	<0.1	6	0.1	1.2	0.1	63	<0.01	0.053
1092175	Soil		3.1	5.4	5.3	25	0.3	5.7	0.6	13	0.43	2.7	3.6	0.2	6	0.2	0.6	0.1	41	0.02	0.147
1092176	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092177	Soil		26.1	20.7	11.0	182	0.2	37.7	3.8	50	1.51	17.5	1.2	0.5	13	0.3	5.4	0.2	205	0.01	0.065
1092178	Soil		3.7	104.8	12.8	283	0.2	362.1	95.1	751	9.63	15.4	3.2	4.4	138	1.2	2.4	<0.1	73	4.36	0.270
1092179	Soil		5.2	75.8	7.4	148	0.1	314.5	60.8	792	6.91	20.4	0.7	2.1	70	0.8	1.7	<0.1	125	1.99	0.138
1092180	Soil		3.9	121.4	9.4	178	0.2	491.1	102.8	916	7.20	27.8	3.0	2.4	46	0.7	1.6	<0.1	117	1.35	0.167
1092181	Soil		12.9	113.3	19.0	97	0.2	355.1	87.5	870	9.81	48.0	2.6	13.5	72	0.4	1.5	<0.1	66	1.81	0.308
1092182	Soil		1.6	112.6	17.4	189	0.2	428.6	90.0	838	8.72	334.0	3.4	15.4	115	0.5	3.7	<0.1	61	4.74	0.329
1092183	Soil		4.2	127.3	23.6	35	0.3	700.6	127.0	1999	13.78	167.9	3.8	6.5	335	0.2	4.3	<0.1	94	5.42	0.332
1092184	Soil		25.7	102.0	19.6	331	0.5	439.2	69.0	1639	11.50	47.2	4.3	4.9	264	1.9	9.0	0.1	312	2.58	0.279
1092185	Soil		51.8	68.3	23.5	1057	0.6	135.8	9.5	399	2.89	55.7	4.8	1.3	63	19.8	17.6	0.2	729	1.18	0.209
1092186	Soil		57.1	33.2	11.5	609	0.3	105.1	9.2	424	1.92	36.9	3.8	0.4	21	4.6	14.1	0.1	460	0.24	0.160
1092187	Soil		34.5	70.5	10.7	688	0.7	189.7	19.0	279	3.41	37.2	3.3	2.0	46	5.8	8.5	0.1	339	0.72	0.248
1092188	Soil		22.8	36.3	12.8	337	0.3	81.2	12.4	341	2.75	24.0	3.0	0.4	23	4.4	5.6	0.2	155	0.16	0.165
1092189	Soil		19.7	36.4	12.5	338	0.7	83.3	10.5	301	2.52	21.8	2.4	0.4	23	2.6	5.1	0.1	107	0.16	0.155
1092190	Soil		5.7	19.4	4.3	474	0.2	58.5	4.3	133	1.13	6.4	2.3	0.7	38	3.0	1.6	0.2	71	0.67	0.165
1092191	Soil		5.7	19.1	3.6	540	0.2	63.9	4.9	138	1.15	6.6	1.4	0.5	42	3.2	1.7	<0.1	72	0.75	0.179
1092192	Soil		17.2	34.6	17.8	229	0.2	58.5	7.0	89	1.98	24.9	1.4	0.2	12	0.4	4.0	0.2	74	0.03	0.091
1092193	Soil		4.7	12.4	10.6	64	0.2	16.6	3.0	40	0.87	10.5	1.2	<0.1	14	0.2	1.3	0.1	31	0.06	0.081
1092194	Soil		3.6	20.9	9.3	129	0.1	19.7	7.8	75	1.52	12.0	<0.5	0.2	3	0.1	1.0	0.3	26	0.01	0.035
1092195	Soil		5.4	20.0	10.6	83	0.4	20.3	3.6	35	1.03	13.6	2.0	<0.1	12	0.2	1.5	0.1	34	0.12	0.073
1092196	Soil		10.2	45.2	18.4	153	0.2	40.0	7.6	75	2.14	26.0	1.7	0.3	8	0.1	4.0	0.2	66	0.02	0.102
1092197	Soil		0.4	1.7	2.3	5	0.4	1.8	0.4	10	0.22	0.7	1.6	<0.1	4	0.1	0.2	<0.1	5	0.02	0.036

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092168	Soil	14	7	0.03	415	0.002	1	0.48	0.005	0.05	<0.1	0.12	0.4	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.
1092169	Soil	13	11	0.04	442	0.002	2	0.48	0.005	0.04	<0.1	0.16	0.6	0.2	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.
1092170	Soil	18	8	0.03	1339	0.002	2	0.46	0.002	0.04	<0.1	1.04	3.4	0.2	<0.05	1	1.4	<0.2	N.A.	N.A.	N.A.
1092171	Soil	16	6	0.02	300	0.002	2	0.48	0.001	0.04	<0.1	1.01	1.7	0.2	<0.05	1	5.2	<0.2	N.A.	N.A.	N.A.
1092172	Soil	10	7	0.03	150	0.003	2	0.37	0.005	0.04	<0.1	0.07	0.2	0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.
1092173	Soil	3	4	0.01	39	0.003	2	0.20	0.012	0.03	<0.1	0.05	0.1	<0.1	<0.05	1	0.7	<0.2	N.A.	N.A.	N.A.
1092174	Soil	9	7	0.03	90	0.003	1	0.36	0.006	0.03	<0.1	0.06	0.1	0.3	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.
1092175	Soil	3	6	0.02	181	0.003	2	0.27	0.012	0.03	<0.1	0.17	0.2	0.3	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.
1092176	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	32.3	32.3	16.3
1092177	Soil	13	16	0.03	119	0.006	2	0.47	0.004	0.06	0.1	0.06	0.2	0.5	<0.05	4	2.5	<0.2	N.A.	N.A.	N.A.
1092178	Soil	36	109	0.57	510	0.004	11	1.00	0.004	0.18	<0.1	0.23	13.2	0.1	0.37	3	1.3	<0.2	N.A.	N.A.	N.A.
1092179	Soil	43	188	1.02	4081	0.009	10	1.76	0.005	0.10	0.1	0.11	13.0	0.2	0.07	6	0.8	<0.2	N.A.	N.A.	N.A.
1092180	Soil	60	246	1.32	4592	0.014	9	2.17	0.005	0.14	0.1	0.16	18.1	<0.1	<0.05	7	1.2	<0.2	N.A.	N.A.	N.A.
1092181	Soil	132	117	0.51	2657	0.007	8	1.16	0.007	0.16	0.2	0.14	16.1	0.2	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.
1092182	Soil	81	103	0.28	1549	0.007	11	0.73	0.006	0.14	<0.1	0.18	18.3	0.2	0.07	2	<0.5	<0.2	N.A.	N.A.	N.A.
1092183	Soil	40	137	1.40	2069	0.006	10	0.75	0.009	0.13	<0.1	0.24	17.4	0.2	0.07	2	1.4	<0.2	N.A.	N.A.	N.A.
1092184	Soil	41	166	1.09	3860	0.005	10	1.24	0.007	0.13	0.2	0.28	17.3	0.7	<0.05	4	3.2	<0.2	N.A.	N.A.	N.A.
1092185	Soil	13	71	0.27	1340	0.006	6	1.03	0.009	0.11	0.2	0.11	2.7	0.9	0.08	3	10.8	0.2	N.A.	N.A.	N.A.
1092186	Soil	15	43	0.20	431	0.007	7	0.68	0.009	0.12	0.3	0.05	0.9	1.3	<0.05	2	3.9	<0.2	N.A.	N.A.	N.A.
1092187	Soil	41	106	0.53	1735	0.008	5	1.31	0.008	0.12	0.2	0.19	6.3	1.1	<0.05	4	3.2	<0.2	N.A.	N.A.	N.A.
1092188	Soil	15	48	0.28	589	0.005	3	1.00	0.007	0.08	0.1	0.06	0.9	0.6	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.
1092189	Soil	14	37	0.22	573	0.004	3	0.73	0.007	0.08	0.1	0.18	0.6	0.4	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.
1092190	Soil	11	44	0.35	271	0.010	3	0.87	0.024	0.05	0.1	0.07	1.3	1.5	0.09	3	1.4	<0.2	N.A.	N.A.	N.A.
1092191	Soil	11	47	0.40	316	0.008	3	0.87	0.020	0.05	<0.1	0.08	1.3	1.5	0.09	3	1.1	<0.2	N.A.	N.A.	N.A.
1092192	Soil	9	15	0.05	121	0.003	3	0.34	0.005	0.05	0.1	0.10	0.3	0.3	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.
1092193	Soil	8	10	0.03	151	0.002	2	0.39	0.006	0.05	<0.1	0.02	0.3	0.2	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.
1092194	Soil	4	10	0.02	56	0.003	3	0.36	0.008	0.04	<0.1	0.01	0.7	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.
1092195	Soil	6	8	0.05	102	0.002	1	0.29	0.009	0.05	<0.1	0.05	0.3	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.
1092196	Soil	8	12	0.04	118	0.004	3	0.57	0.005	0.06	<0.1	0.04	0.9	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.
1092197	Soil	<1	2	0.01	31	0.004	<1	0.14	0.020	0.02	<0.1	0.08	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092168	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092169	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092170	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092171	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092172	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092173	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092174	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092175	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092176	Soil		361	1.3	61.6	4.7	64	2.03	29.5	1.1	<0.1	15	0.9	7.7	0.2	337	0.01	0.076	8	21	0.04	425
1092177	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092178	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092179	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092180	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092181	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092182	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092183	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092184	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092185	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092186	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092187	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092188	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092189	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092190	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092191	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092192	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092193	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092194	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092195	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092196	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092197	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092174	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092175	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092176	Soil	0.001	<20	0.48	0.006	0.07	0.1	0.23	0.1	0.8	0.07	2	5.3	<0.2
1092177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092178	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092180	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092198	Soil		0.4	2.3	1.8	6	0.4	2.5	0.5	9	0.23	0.7	2.1	<0.1	8	<0.1	0.2	<0.1	5	0.08	0.064
1092199	Soil		0.6	2.6	2.9	9	0.4	2.6	0.7	11	0.34	1.1	0.8	<0.1	6	<0.1	0.4	<0.1	7	0.03	0.088
1092200	Soil		7.6	26.3	13.2	100	0.4	38.9	5.2	77	1.64	14.9	0.9	<0.1	16	0.4	2.4	0.2	48	0.07	0.177
1092241	Soil		27.5	41.8	28.9	242	2.2	38.7	6.3	315	3.46	53.6	1.4	1.0	42	1.8	14.9	0.3	133	0.09	0.119
1092242	Soil		18.4	53.2	29.9	218	2.4	32.2	5.6	78	3.84	47.5	2.4	0.7	37	0.4	14.2	0.4	133	0.02	0.139
1092243	Soil		23.0	27.7	26.9	108	1.8	17.4	2.6	72	2.68	43.1	2.3	0.7	35	0.2	10.6	0.3	98	0.08	0.142
1092244	Soil		15.0	54.7	20.1	217	3.6	26.5	5.7	111	4.51	61.4	6.9	2.1	99	0.6	8.9	0.3	96	0.29	0.555
1092245	Soil		3.9	24.0	12.8	49	0.6	11.9	2.0	68	1.79	17.0	1.7	0.2	17	0.1	1.4	0.2	38	0.02	0.086
1092246	Soil		6.3	30.8	18.4	82	0.5	19.4	5.2	231	3.31	26.6	1.4	0.2	24	0.1	2.7	0.3	48	0.03	0.098
1092247	Soil		4.3	30.4	16.3	69	0.4	15.4	3.6	244	2.63	20.3	1.5	0.3	19	0.2	1.6	0.3	43	0.03	0.104
1092248	Soil		4.9	49.6	23.0	92	1.1	23.7	5.6	197	3.09	31.0	3.4	2.0	28	0.1	2.2	0.3	41	0.04	0.081
1092249	Soil		6.1	37.8	17.5	85	1.9	21.8	3.8	156	2.44	22.2	6.3	0.4	37	0.3	1.5	0.2	35	0.04	0.070
1092250	Soil		4.8	18.1	9.5	69	0.2	17.3	3.1	207	1.35	15.0	<0.5	<0.1	13	0.2	1.7	0.2	41	0.03	0.068
1092261	Soil		20.5	24.9	7.9	204	1.0	49.2	2.3	25	0.85	9.5	<0.5	0.3	42	2.6	4.9	<0.1	114	0.69	0.075
1092262	Soil		3.9	13.5	2.9	57	0.9	14.3	1.0	17	0.33	3.2	<0.5	<0.1	16	1.3	1.2	<0.1	44	0.22	0.042
1092263	Soil		5.0	109.5	11.9	320	0.1	409.4	75.6	672	6.63	99.0	<0.5	10.8	43	0.5	2.8	<0.1	90	1.28	0.314
1092264	Soil		4.7	123.8	18.5	260	0.3	690.8	193.7	1699	9.47	299.4	0.5	18.1	71	1.1	6.4	<0.1	77	2.65	0.385
1092265	Soil		2.6	97.8	10.5	98	0.2	233.8	80.5	766	6.32	13.8	<0.5	5.6	93	0.3	0.9	<0.1	61	3.76	0.277
1092266	Soil		6.4	118.6	15.5	188	0.2	345.3	100.4	736	7.18	32.7	<0.5	7.7	99	0.5	1.6	0.1	86	2.87	0.284
1092267	Soil		31.4	134.1	23.2	434	0.7	435.5	76.2	637	7.11	37.0	3.6	8.1	193	2.4	6.8	0.2	164	2.26	0.297
1092268	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092269	Soil		8.4	68.1	5.7	190	0.2	289.2	52.5	1114	7.39	21.4	<0.5	1.9	71	1.5	2.1	<0.1	109	1.19	0.179
1092270	Soil		10.7	71.0	7.6	360	0.2	281.2	51.9	966	7.06	28.2	<0.5	2.4	57	2.2	2.7	<0.1	125	0.96	0.206
1092271	Soil		31.4	82.3	9.3	927	0.8	234.5	25.4	285	3.98	43.4	0.7	1.7	74	11.7	11.9	<0.1	415	1.21	0.223
1092272	Soil		64.6	104.0	12.1	1116	1.5	246.4	16.1	220	2.69	50.4	<0.5	1.9	138	15.0	17.1	0.1	598	3.99	0.162
1092273	Soil		22.6	22.9	5.1	214	0.4	44.1	2.8	59	0.89	12.5	<0.5	<0.1	8	2.7	4.7	0.1	547	0.10	0.121
1092274	Soil		36.2	38.2	10.0	379	0.4	75.3	2.7	36	1.35	27.2	<0.5	0.3	8	2.7	8.1	0.1	538	0.07	0.108
1092275	Soil		63.9	74.7	15.5	1033	0.4	151.7	7.2	160	2.05	46.7	<0.5	2.3	32	13.1	19.6	0.1	494	0.42	0.145
1092276	Soil		13.5	20.2	8.7	139	<0.1	25.0	4.0	74	1.44	14.5	<0.5	0.1	9	0.4	4.3	0.1	96	0.02	0.064
1092277	Soil		1.3	4.9	6.1	16	<0.1	4.3	0.8	41	0.39	<0.5	<0.5	<0.1	6	0.1	0.4	<0.1	17	0.03	0.042

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092198	Soil	<1	2	0.02	79	0.002	<1	0.14	0.021	0.02	<0.1	0.07	0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.
1092199	Soil	1	3	0.01	56	0.005	2	0.17	0.019	0.02	<0.1	0.02	0.5	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.
1092200	Soil	7	20	0.04	371	0.003	4	0.41	0.007	0.07	<0.1	0.10	0.4	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.
1092241	Soil	2	14	0.03	589	0.001	2	0.46	0.004	0.10	0.1	0.22	1.9	1.1	0.23	2	7.4	<0.2	N.A.	N.A.	N.A.
1092242	Soil	4	15	0.03	183	0.002	3	0.53	0.003	0.09	<0.1	0.41	1.3	0.7	0.11	2	10.6	<0.2	N.A.	N.A.	N.A.
1092243	Soil	4	16	0.04	330	0.002	2	0.53	0.004	0.10	0.2	0.16	1.1	0.9	0.19	2	6.0	<0.2	N.A.	N.A.	N.A.
1092244	Soil	9	44	0.08	848	0.006	3	0.76	0.006	0.14	0.2	0.36	4.0	0.6	0.25	3	6.8	0.3	N.A.	N.A.	N.A.
1092245	Soil	4	16	0.06	365	0.004	3	0.69	0.010	0.05	0.1	0.08	0.5	0.2	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.
1092246	Soil	6	21	0.11	205	0.005	1	0.80	0.005	0.06	0.1	0.08	0.5	0.2	0.07	3	1.7	<0.2	N.A.	N.A.	N.A.
1092247	Soil	5	18	0.08	221	0.004	3	0.87	0.006	0.06	<0.1	0.07	0.5	0.1	0.09	3	1.3	<0.2	N.A.	N.A.	N.A.
1092248	Soil	6	19	0.16	334	0.007	4	0.91	0.008	0.08	0.1	0.37	2.7	0.2	0.07	3	3.4	<0.2	N.A.	N.A.	N.A.
1092249	Soil	5	20	0.10	420	0.004	3	0.79	0.006	0.06	0.1	0.23	1.5	0.2	<0.05	2	4.5	<0.2	N.A.	N.A.	N.A.
1092250	Soil	7	16	0.02	159	0.003	2	0.37	0.006	0.06	0.1	0.04	0.2	<0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.
1092261	Soil	5	16	0.07	274	0.004	3	0.33	0.016	0.05	0.1	0.21	1.2	0.8	0.06	1	2.6	<0.2	N.A.	N.A.	N.A.
1092262	Soil	2	5	0.03	95	0.003	2	0.26	0.023	0.03	<0.1	0.15	0.2	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.
1092263	Soil	94	155	0.28	2773	0.004	8	1.52	0.007	0.20	<0.1	0.04	20.5	0.1	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.
1092264	Soil	117	126	0.49	1233	0.005	12	1.32	0.006	0.21	0.1	0.14	20.9	0.2	0.20	3	0.9	<0.2	N.A.	N.A.	N.A.
1092265	Soil	93	101	0.63	2381	0.003	12	0.94	0.005	0.14	0.1	0.09	13.2	<0.1	0.15	3	0.5	<0.2	N.A.	N.A.	N.A.
1092266	Soil	112	178	1.01	4248	0.003	12	1.48	0.006	0.16	0.1	0.12	18.1	0.2	0.12	5	0.6	<0.2	N.A.	N.A.	N.A.
1092267	Soil	38	109	0.75	1915	0.004	12	0.76	0.008	0.21	0.1	0.17	17.0	1.1	0.13	2	5.8	<0.2	N.A.	N.A.	N.A.
1092268	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	15.3	114.7	16.3
1092269	Soil	33	116	0.42	6507	0.006	12	1.31	0.015	0.10	0.1	0.08	14.9	0.1	0.05	4	2.1	<0.2	N.A.	N.A.	N.A.
1092270	Soil	37	112	0.37	5870	0.005	5	1.45	0.007	0.10	<0.1	0.11	14.8	0.2	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.
1092271	Soil	25	67	0.23	3474	0.004	5	0.88	0.010	0.12	0.2	0.36	7.7	0.7	<0.05	2	4.2	<0.2	N.A.	N.A.	N.A.
1092272	Soil	18	51	1.90	1737	0.006	13	0.62	0.008	0.15	0.3	0.48	5.2	1.6	0.06	2	6.2	<0.2	N.A.	N.A.	N.A.
1092273	Soil	12	47	0.08	550	0.001	3	0.77	0.009	0.10	0.1	0.46	0.3	1.2	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.
1092274	Soil	20	46	0.10	625	0.001	4	0.81	0.003	0.12	0.2	0.16	0.5	1.2	<0.05	3	4.3	<0.2	N.A.	N.A.	N.A.
1092275	Soil	23	40	0.12	915	0.004	7	0.62	0.003	0.15	0.2	0.53	3.7	1.1	<0.05	2	8.8	<0.2	N.A.	N.A.	N.A.
1092276	Soil	8	11	0.02	187	0.004	17	0.36	0.007	0.06	0.1	0.11	0.5	0.2	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.
1092277	Soil	2	5	0.02	44	0.009	1	0.38	0.023	0.03	<0.1	0.05	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092198	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092199	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092200	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092241	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092242	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092243	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092244	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092245	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092246	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092247	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092248	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092249	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092250	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092261	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092262	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092263	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092264	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092265	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092266	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092267	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092268	Soil		271	0.3	504.0	90.9	992	8.39	70.6	3.1	4.5	76	1.4	3.3	0.1	113	1.35	0.238	47	116	0.35	1917
1092269	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092270	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092271	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092272	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092273	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092274	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092275	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092276	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092277	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092241	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092242	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092243	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092244	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092245	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092247	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092249	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092250	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092268	Soil	0.002	<20	1.03	0.007	0.13	0.1	0.17	16.6	0.5	0.17	3	3.1	<0.2
1092269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092271	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092272	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092273	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092274	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092275	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092276	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092277	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092278	Soil		6.3	86.4	27.9	270	1.3	71.1	18.0	501	4.98	32.5	3.2	2.0	26	0.7	3.7	0.3	35	0.09	0.147
1092279	Soil		12.1	93.0	32.8	289	2.2	90.7	21.2	497	5.58	36.0	4.2	1.7	22	0.9	5.3	0.3	54	0.05	0.147
1092280	Soil		15.2	71.1	22.3	385	0.8	78.3	8.5	157	2.97	17.3	1.6	2.5	50	1.6	4.9	0.2	83	0.51	0.261
1092301	Soil		8.5	69.0	18.7	27	2.8	14.3	1.7	62	2.69	43.9	12.2	0.5	164	0.2	8.5	0.4	97	0.04	0.269
1092302	Soil		9.0	83.8	20.9	29	3.8	13.0	1.5	56	3.51	66.7	15.0	0.7	210	0.3	13.4	0.4	110	0.04	0.322
1092303	Soil		2.0	12.0	6.8	18	1.0	13.1	1.3	34	0.69	10.2	<0.5	<0.1	21	<0.1	2.5	<0.1	30	0.04	0.053
1092304	Soil		22.8	47.3	25.8	149	4.4	28.6	1.3	24	1.57	24.6	<0.5	0.7	111	0.5	19.5	0.3	274	0.06	0.235
1092305	Soil		6.0	9.3	7.2	41	0.2	8.3	1.1	18	0.64	6.7	<0.5	0.8	11	<0.1	2.5	<0.1	83	<0.01	0.018
1092306	Soil		0.2	1.1	1.2	3	0.2	1.2	0.3	8	0.12	<0.5	<0.5	<0.1	4	<0.1	0.1	<0.1	4	0.02	0.010
1092307	Soil		19.6	19.1	11.8	113	0.6	21.3	2.4	39	4.40	39.6	<0.5	<0.1	32	0.4	5.7	0.1	199	0.02	0.142
1092308	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092309	Soil		7.5	35.1	13.2	88	1.3	28.7	1.2	49	1.66	14.2	3.9	0.3	114	0.9	3.2	0.2	133	0.35	0.199
1092310	Soil		1.5	3.0	1.7	10	<0.1	2.4	0.2	5	0.22	0.6	<0.5	0.2	3	<0.1	1.2	<0.1	17	<0.01	0.011
1092311	Soil		3.3	8.2	4.6	14	0.8	4.3	0.6	15	0.35	1.8	<0.5	<0.1	7	<0.1	2.1	<0.1	33	0.02	0.025
1092312	Soil		23.8	19.9	25.8	52	1.7	17.0	1.8	50	2.04	20.0	0.8	0.3	60	0.2	11.0	0.3	164	0.02	0.108
1092313	Soil		9.0	12.1	6.1	25	1.3	6.6	1.2	20	0.66	6.3	<0.5	<0.1	5	<0.1	2.9	0.1	87	<0.01	0.040
1092314	Soil		30.8	28.4	17.0	298	1.4	57.8	4.5	196	2.53	35.9	1.4	0.2	26	1.1	12.5	0.3	268	0.08	0.174
1092315	Soil		11.3	11.9	3.8	27	1.4	7.5	1.1	22	0.88	10.7	0.5	<0.1	3	0.1	1.8	0.1	58	0.01	0.028
1092316	Soil		8.3	17.6	5.0	65	0.2	15.4	2.7	28	1.02	9.2	1.0	<0.1	13	0.1	2.2	0.1	69	0.01	0.029
1092317	Soil		22.9	26.5	11.6	231	0.3	60.4	5.2	46	1.74	20.6	1.3	0.2	7	0.2	4.8	0.2	163	<0.01	0.058
1092318	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092319	Soil		22.4	53.2	17.4	409	0.6	95.0	7.3	81	2.80	35.9	2.1	0.7	22	1.2	7.3	0.2	105	0.07	0.133
1092320	Soil		20.4	21.7	16.9	173	0.2	43.9	4.2	40	1.48	19.5	<0.5	0.1	11	0.1	4.8	0.2	138	<0.01	0.042
1092321	Soil		23.2	23.4	13.7	214	0.7	53.4	5.3	84	1.91	22.6	1.9	0.2	10	0.3	5.4	0.2	135	0.01	0.064
1092322	Soil		16.3	15.7	5.8	115	0.3	33.8	2.8	22	0.93	11.2	<0.5	<0.1	6	0.4	2.9	<0.1	81	<0.01	0.056
1092323	Soil		130.2	155.9	20.7	1036	2.6	187.1	18.7	341	5.20	104.2	1.5	2.3	21	5.4	28.7	0.2	286	0.11	0.192
1092324	Soil		7.8	12.1	6.0	71	0.2	16.9	2.1	26	0.79	8.4	0.9	<0.1	6	0.1	2.0	0.1	61	<0.01	0.034
1092325	Soil		22.6	17.2	9.4	176	<0.1	47.6	3.6	58	1.34	18.5	<0.5	0.7	7	0.4	4.2	0.2	180	0.02	0.052
1092326	Soil		15.5	33.9	13.9	158	0.4	36.0	3.0	57	1.92	24.4	4.6	1.1	37	0.7	5.9	0.1	101	0.13	0.172
1092327	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092278	Soil	16	12	0.06	1564	0.004	3	0.83	0.007	0.11	<0.1	0.15	3.7	0.4	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.
1092279	Soil	17	14	0.05	1610	0.003	2	0.79	0.004	0.10	<0.1	0.32	3.6	0.5	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.
1092280	Soil	25	16	0.06	1168	0.004	7	0.57	0.002	0.15	0.1	0.41	3.1	0.3	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.
1092301	Soil	1	26	0.02	1048	0.002	4	0.61	0.005	0.20	0.1	0.27	3.7	0.7	0.34	2	7.3	0.2	N.A.	N.A.	N.A.
1092302	Soil	2	34	0.03	476	0.002	3	0.66	0.004	0.22	<0.1	0.32	3.3	0.8	0.42	3	10.0	0.4	N.A.	N.A.	N.A.
1092303	Soil	2	7	0.02	749	0.006	1	0.22	0.016	0.03	<0.1	0.12	0.6	0.2	<0.05	<1	1.5	<0.2	N.A.	N.A.	N.A.
1092304	Soil	8	29	0.05	3507	0.004	4	0.94	0.007	0.09	0.3	0.32	1.3	1.3	0.08	4	11.9	<0.2	N.A.	N.A.	N.A.
1092305	Soil	8	9	0.01	228	0.004	2	0.24	0.004	0.04	<0.1	0.06	0.5	0.2	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.
1092306	Soil	<1	2	<0.01	26	0.006	<1	0.05	0.020	0.02	<0.1	0.02	0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.
1092307	Soil	5	19	0.02	357	0.005	2	0.34	0.008	0.06	0.2	0.11	0.4	0.4	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.
1092308	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	12.5	42.0	11.4
1092309	Soil	3	25	0.04	1446	0.003	4	0.48	0.005	0.11	0.1	0.34	1.9	0.6	0.11	2	3.7	<0.2	N.A.	N.A.	N.A.
1092310	Soil	4	5	<0.01	90	0.003	1	0.20	0.002	0.02	<0.1	0.11	0.2	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.
1092311	Soil	2	7	<0.01	170	0.002	1	0.21	0.011	0.03	<0.1	0.07	0.1	<0.1	<0.05	1	0.5	<0.2	N.A.	N.A.	N.A.
1092312	Soil	4	15	0.03	351	0.002	1	0.39	0.006	0.09	0.1	0.74	0.6	1.0	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.
1092313	Soil	5	13	0.01	264	0.004	5	0.36	0.005	0.05	0.2	0.01	0.4	0.6	<0.05	3	<0.5	0.2	N.A.	N.A.	N.A.
1092314	Soil	7	17	0.04	333	0.003	3	0.45	0.009	0.09	0.3	0.26	0.6	1.4	0.12	2	3.9	<0.2	N.A.	N.A.	N.A.
1092315	Soil	3	5	<0.01	110	0.003	2	0.18	0.012	0.03	0.1	0.01	0.1	0.3	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.
1092316	Soil	13	12	0.02	2862	0.004	2	0.36	0.004	0.04	0.1	0.02	0.2	0.4	0.08	3	1.2	<0.2	N.A.	N.A.	N.A.
1092317	Soil	11	16	0.04	492	0.002	2	0.52	0.004	0.06	0.1	0.07	0.4	0.5	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.
1092318	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	20.7	29.6	17.3
1092319	Soil	15	14	0.04	369	0.002	3	0.38	0.002	0.06	<0.1	0.69	1.0	0.6	<0.05	1	2.7	<0.2	N.A.	N.A.	N.A.
1092320	Soil	12	12	0.03	124	0.003	2	0.35	0.003	0.06	0.1	0.03	0.3	0.4	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.
1092321	Soil	11	14	0.05	153	0.004	3	0.43	0.004	0.06	<0.1	0.05	0.3	0.4	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.
1092322	Soil	6	10	0.03	122	0.002	2	0.29	0.010	0.05	<0.1	0.05	0.1	0.2	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.
1092323	Soil	8	33	0.05	445	0.002	3	0.64	0.004	0.08	0.4	0.49	4.5	3.9	0.07	2	26.2	<0.2	N.A.	N.A.	N.A.
1092324	Soil	8	9	0.02	91	0.003	2	0.28	0.007	0.05	<0.1	0.02	0.1	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.
1092325	Soil	8	16	0.38	158	0.001	2	0.90	0.005	0.04	0.2	0.01	0.9	0.7	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.
1092326	Soil	10	14	0.04	358	0.002	3	0.40	0.002	0.07	0.1	0.66	1.4	0.5	<0.05	1	2.3	<0.2	N.A.	N.A.	N.A.
1092327	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	10.4	148.1	17.0

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092278	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092279	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092280	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092301	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092302	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092303	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092304	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092305	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092306	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092307	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092308	Soil		62	2.4	36.9	2.2	31	1.82	11.8	9.4	<0.1	76	1.3	2.8	0.2	85	0.30	0.183	7	19	0.03	1163
1092309	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092310	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092311	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092312	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092313	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092314	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092315	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092316	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092317	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092318	Soil		234	0.5	61.3	5.4	82	2.01	23.7	1.4	<0.1	14	0.4	3.5	0.2	137	0.02	0.080	9	16	0.04	379
1092319	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092320	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092321	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092322	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092323	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092324	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092325	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092326	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092327	Soil		206	0.2	370.1	94.2	741	7.47	139.4	1.8	13.5	82	0.6	2.0	<0.1	192	2.10	0.334	85	315	2.19	2393

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092278	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092279	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092280	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092301	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092302	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092303	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092304	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092305	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092306	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092307	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092308	Soil		0.002	<20	1.18	0.006	0.05	0.1	0.73	0.3	1.0	0.22	3	3.5	<0.2
1092309	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092310	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092311	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092312	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092313	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092314	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092315	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092316	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092317	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092318	Soil		0.003	<20	0.46	0.004	0.05	0.1	0.22	0.2	0.4	0.05	3	2.5	<0.2
1092319	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092320	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092321	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092322	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092323	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092324	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092325	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092326	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092327	Soil		0.001	<20	2.99	0.004	0.07	<0.1	0.08	22.8	0.2	0.08	9	0.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092328	Soil		9.9	150.2	24.0	146	0.2	361.2	83.2	782	8.83	100.9	1.9	7.5	53	0.5	2.2	<0.1	169	1.23	0.177
1092329	Soil		9.1	136.6	21.2	157	0.2	378.8	76.6	700	7.71	87.8	3.0	6.8	60	0.6	1.8	<0.1	162	1.16	0.235
1092330	Soil		6.6	51.3	7.8	131	0.2	210.4	43.1	581	4.49	30.6	<0.5	1.5	70	0.9	1.7	<0.1	54	1.18	0.158
1092331	Soil		2.9	44.4	6.7	67	<0.1	120.7	28.8	426	2.72	25.8	1.3	1.5	47	0.2	0.9	<0.1	36	1.17	0.114
1092332	Soil		11.4	128.8	21.5	171	0.2	404.5	104.0	862	9.06	94.4	1.7	17.1	145	0.5	1.9	<0.1	94	3.85	0.317
1092333	Soil		10.8	136.2	21.2	218	0.2	430.1	98.9	791	8.12	56.5	2.9	15.4	124	0.9	2.4	<0.1	105	2.20	0.327
1092334	Soil		46.6	89.4	13.7	747	0.7	247.9	29.2	435	4.49	39.3	1.8	4.4	99	6.7	10.3	0.1	225	2.08	0.191
1092335	Soil		54.2	44.2	10.3	632	0.7	132.8	10.9	225	3.07	29.9	1.8	1.9	43	6.4	9.9	0.1	274	0.41	0.188
1092336	Soil		58.8	55.6	11.9	669	0.3	139.1	8.1	264	1.82	30.8	<0.5	2.7	195	6.8	9.0	0.1	171	5.71	0.117
1092337	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092338	Soil		22.9	55.8	18.0	501	0.7	90.7	15.6	386	4.34	22.5	1.8	4.8	63	2.7	7.4	0.2	185	0.28	0.191
1092339	Soil		7.6	12.2	5.1	90	0.3	17.9	3.1	51	1.19	6.8	<0.5	0.2	4	0.2	1.6	<0.1	71	0.02	0.065
1092340	Soil		7.4	29.2	15.5	117	0.7	20.4	5.3	51	1.66	10.3	2.7	0.1	8	0.3	1.7	0.1	46	0.04	0.088
1092341	Soil		3.0	12.9	5.0	33	<0.1	11.1	4.4	40	0.99	4.4	0.6	<0.1	5	0.1	1.0	<0.1	33	0.01	0.039
1092342	Soil		9.9	48.3	11.9	204	0.7	32.2	11.6	459	2.59	12.9	<0.5	0.4	13	0.2	3.7	0.2	57	0.01	0.103
1092343	Soil		8.5	40.9	17.8	131	0.2	24.6	6.2	58	1.95	14.0	1.4	0.2	17	<0.1	2.8	0.2	63	0.02	0.082
1092344	Soil		6.0	55.4	19.1	130	<0.1	43.6	12.0	160	3.81	14.8	1.0	2.5	7	<0.1	2.3	0.4	31	<0.01	0.066
1092345	Soil		7.6	20.1	14.2	92	0.3	20.2	3.5	38	1.29	11.7	0.8	0.1	22	0.2	2.3	0.1	83	0.01	0.080
1092346	Soil		29.9	68.7	24.0	1092	0.8	128.4	5.6	126	1.94	30.8	0.9	1.6	73	9.2	8.3	0.1	191	0.67	0.160
1092347	Soil		2.6	18.8	6.3	41	0.2	17.9	5.3	57	1.87	14.6	<0.5	<0.1	5	0.1	1.3	0.2	29	0.02	0.050
1092348	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092349	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092350	Soil		4.8	27.8	17.0	94	0.3	29.4	4.9	414	1.52	17.2	3.3	0.1	27	0.4	2.3	0.3	29	0.14	0.176
1092351	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092352	Soil		60.3	62.6	17.3	442	0.5	137.1	12.0	295	2.52	27.2	2.9	2.0	42	2.6	6.2	0.2	62	0.40	0.161
1092353	Soil		16.0	14.2	11.1	97	0.2	20.8	1.8	29	1.17	11.4	1.8	0.3	7	0.3	1.9	0.2	51	0.01	0.054
1092354	Soil		9.0	15.0	8.6	3143	0.3	360.5	2.1	37	0.63	5.7	2.0	1.8	41	23.2	1.9	0.1	122	0.34	0.071
1092355	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092356	Soil		72.1	76.0	11.3	759	0.6	195.9	8.8	190	1.83	33.9	1.8	1.2	38	7.7	10.3	0.1	252	0.33	0.130
1092357	Soil		23.0	28.9	13.4	138	0.3	26.9	2.8	64	1.80	22.4	3.9	0.8	12	0.5	7.3	0.2	124	0.09	0.103

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092328	Soil	114	330	1.66	6720	0.006	7	2.33	0.015	0.08	<0.1	0.10	18.5	0.1	0.13	7	1.0	<0.2	N.A.	N.A.	N.A.
1092329	Soil	99	324	1.65	4647	0.005	6	2.41	0.011	0.09	<0.1	0.05	20.5	0.1	0.06	8	1.2	<0.2	N.A.	N.A.	N.A.
1092330	Soil	35	55	0.24	2146	0.006	8	0.83	0.020	0.09	<0.1	0.06	7.3	0.2	0.13	2	0.9	<0.2	N.A.	N.A.	N.A.
1092331	Soil	40	52	0.25	2208	0.006	7	0.70	0.032	0.07	<0.1	0.05	5.0	<0.1	0.12	2	<0.5	<0.2	N.A.	N.A.	N.A.
1092332	Soil	103	163	1.00	411	0.004	10	1.55	0.008	0.18	<0.1	0.12	17.4	0.3	0.28	4	0.9	<0.2	N.A.	N.A.	N.A.
1092333	Soil	122	188	0.96	4895	0.005	13	1.53	0.008	0.20	<0.1	0.09	21.3	0.2	0.27	5	0.6	<0.2	N.A.	N.A.	N.A.
1092334	Soil	36	60	0.93	2232	0.004	10	0.69	0.007	0.13	0.2	0.40	9.9	0.9	0.10	2	4.3	<0.2	N.A.	N.A.	N.A.
1092335	Soil	24	41	0.17	2264	0.005	6	0.83	0.004	0.11	0.2	0.26	5.8	0.9	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.
1092336	Soil	11	18	2.49	692	0.003	8	0.32	0.008	0.10	0.1	0.39	3.4	1.0	0.05	<1	3.2	<0.2	N.A.	N.A.	N.A.
1092337	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	64.4	56.9	13.6
1092338	Soil	25	30	0.06	>10000	0.003	3	1.77	0.007	0.16	0.2	0.22	4.6	0.5	<0.05	4	2.8	<0.2	N.A.	N.A.	N.A.
1092339	Soil	5	10	0.03	36	0.003	2	0.43	0.021	0.05	<0.1	0.03	0.3	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.
1092340	Soil	8	6	0.03	245	0.001	2	0.40	0.011	0.06	<0.1	0.09	0.2	0.2	<0.05	1	1.4	<0.2	N.A.	N.A.	N.A.
1092341	Soil	6	7	0.04	90	0.003	2	0.39	0.014	0.05	<0.1	<0.01	0.2	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.
1092342	Soil	10	12	0.08	100	0.005	5	0.59	0.010	0.15	<0.1	0.08	0.8	0.4	0.06	3	1.8	<0.2	N.A.	N.A.	N.A.
1092343	Soil	11	11	0.06	90	0.005	4	0.54	0.008	0.10	<0.1	0.03	0.4	0.3	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.
1092344	Soil	20	9	0.05	163	0.002	5	0.54	0.003	0.12	<0.1	0.02	2.1	0.3	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.
1092345	Soil	8	13	0.04	121	0.005	4	0.38	0.014	0.09	<0.1	0.03	0.4	0.3	0.05	2	1.2	<0.2	N.A.	N.A.	N.A.
1092346	Soil	18	21	0.12	795	0.003	7	0.52	0.004	0.09	0.2	0.39	2.8	0.9	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.
1092347	Soil	7	8	0.03	417	0.011	2	0.41	0.015	0.05	<0.1	0.06	0.6	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1092348	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.4	28.9	10.4
1092349	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.7	18.8	11.4
1092350	Soil	6	8	0.03	301	0.003	1	0.26	0.011	0.07	<0.1	0.04	0.4	0.2	0.12	<1	0.6	<0.2	N.A.	N.A.	N.A.
1092351	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	7.2	71.0	43.1
1092352	Soil	12	12	0.08	395	0.004	3	0.29	0.003	0.06	0.2	0.36	2.8	0.7	<0.05	<1	1.8	<0.2	N.A.	N.A.	N.A.
1092353	Soil	8	9	0.03	88	0.004	1	0.50	0.003	0.04	0.1	0.04	0.3	0.4	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.
1092354	Soil	8	21	0.14	922	0.004	2	0.76	0.003	0.04	0.1	0.19	1.8	1.0	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.
1092355	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	25.8	19.5	9.9
1092356	Soil	17	22	0.09	253	0.004	3	0.43	0.003	0.07	0.3	0.35	2.2	1.2	<0.05	1	3.2	<0.2	N.A.	N.A.	N.A.
1092357	Soil	15	16	0.04	116	0.003	1	0.42	0.002	0.05	0.1	0.24	1.2	0.4	<0.05	1	1.3	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092328	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092329	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092330	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092331	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092332	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092333	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092334	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092335	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092336	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092337	Soil		647	0.4	162.1	11.0	221	2.33	34.4	1.4	1.2	41	8.2	9.9	0.2	296	0.46	0.136	19	34	0.14	964
1092338	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092339	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092340	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092341	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092342	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092343	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092344	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092345	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092346	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092347	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092348	Soil		86	0.2	39.1	10.5	225	3.06	35.9	1.6	<0.1	10	0.1	1.7	0.3	19	0.04	0.063	6	8	0.04	1019
1092349	Soil		91	0.2	22.9	4.7	346	1.24	12.3	1.4	<0.1	20	0.5	1.3	0.2	16	0.13	0.099	5	8	0.03	417
1092350	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092351	Soil		221	1.6	65.2	8.5	270	2.91	38.1	7.2	1.7	92	0.9	2.5	0.4	60	0.85	0.460	20	23	0.08	1055
1092352	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092353	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092354	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092355	Soil		356	0.2	55.4	4.1	85	1.58	21.7	<0.5	0.1	19	2.4	4.9	0.1	234	0.17	0.073	12	30	0.08	299
1092356	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092357	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092328	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092329	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092330	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092331	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092332	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092333	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092334	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092335	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092336	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092337	Soil		0.003	<20	0.50	0.003	0.09	0.2	0.26	3.5	1.1	<0.05	1	3.6	<0.2
1092338	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092339	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092340	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092341	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092342	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092343	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092344	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092345	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092346	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092347	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092348	Soil		0.002	<20	0.33	0.009	0.06	<0.1	0.05	0.5	0.1	0.07	1	0.7	<0.2
1092349	Soil		<0.001	<20	0.32	0.012	0.06	<0.1	0.04	<0.1	<0.1	0.05	1	0.9	<0.2
1092350	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092351	Soil		0.003	<20	0.74	0.005	0.16	<0.1	0.61	2.7	0.2	0.08	2	2.5	0.3
1092352	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092353	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092354	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092355	Soil		0.003	<20	0.58	0.009	0.06	0.1	0.05	0.4	0.6	<0.05	2	3.1	<0.2
1092356	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092357	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092358	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092359	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092360	Soil		0.4	5.1	1.8	6	0.7	2.4	0.6	11	0.33	0.8	2.0	<0.1	8	0.2	0.2	<0.1	8	0.04	0.027
1092361	Soil		7.2	9.6	10.6	119	0.7	19.5	1.1	24	0.66	9.0	2.0	<0.1	8	0.4	3.0	<0.1	80	0.02	0.105
1092362	Soil		32.4	23.3	16.3	306	0.6	49.9	2.8	38	1.40	16.8	2.2	<0.1	13	0.4	10.0	0.1	240	0.01	0.098
1092363	Soil		70.2	86.2	54.3	1216	0.8	156.8	8.1	131	3.48	66.9	13.5	0.3	30	2.8	32.5	0.2	413	0.05	0.151
1092364	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092365	Soil		23.7	32.6	27.4	418	0.2	53.9	5.8	97	2.20	26.6	2.2	<0.1	16	0.5	10.2	0.3	184	0.01	0.062
1092366	Soil		12.1	14.9	21.4	90	0.9	13.9	2.1	86	1.75	34.5	3.4	<0.1	37	0.2	6.4	0.2	85	0.01	0.112
1092367	Soil		3.8	15.7	12.4	172	0.1	23.1	7.3	70	2.15	19.8	2.2	0.2	11	0.1	2.1	0.2	30	0.02	0.053
1092368	Soil		5.4	25.4	16.7	243	0.3	39.3	13.8	141	2.76	19.0	1.7	0.2	10	0.2	2.4	0.3	37	<0.01	0.049
1092369	Soil		7.4	43.4	40.6	222	0.3	48.9	29.9	710	3.56	34.4	3.1	0.6	43	0.7	2.3	0.5	22	0.02	0.088
1092370	Soil		7.3	31.1	30.5	78	2.0	16.9	3.0	105	2.17	26.7	10.6	1.0	48	0.2	13.4	0.3	70	0.03	0.093
1092371	Soil		7.4	33.8	33.7	101	2.0	18.1	3.2	93	2.18	24.7	7.9	1.3	51	0.3	12.6	0.3	71	0.02	0.084
1092372	Soil		7.5	33.0	32.4	95	2.2	17.3	3.2	105	2.30	27.2	10.1	1.3	55	0.3	14.2	0.3	76	0.03	0.098
1092373	Soil		2.7	25.7	20.6	48	0.8	13.4	4.8	166	1.93	11.8	4.2	0.4	25	<0.1	6.9	0.3	43	0.03	0.039
1092374	Soil		2.4	46.4	26.6	69	0.7	22.4	10.0	363	2.75	9.7	4.3	0.7	53	0.3	3.0	0.4	35	0.03	0.050
1092375	Soil		4.2	23.8	31.0	37	3.4	10.0	3.1	119	2.57	30.3	13.5	0.9	44	0.1	11.6	0.4	44	0.02	0.069
1092376	Soil		5.7	21.8	28.2	30	2.5	8.5	1.6	55	3.07	36.7	13.0	1.3	55	<0.1	14.8	0.5	46	0.02	0.066
1092377	Soil		2.7	71.6	21.1	168	1.5	93.4	20.2	1099	5.08	24.9	12.9	0.9	15	0.9	8.4	0.3	54	0.03	0.136
1092378	Soil		8.6	35.7	29.6	105	1.9	18.8	3.0	98	2.15	25.2	7.5	1.2	56	0.3	11.8	0.3	74	0.02	0.087
1092379	Soil		14.1	38.8	22.4	108	2.0	21.7	2.8	106	2.25	22.4	9.1	0.9	75	0.4	10.9	0.3	100	0.02	0.100
1092380	Soil		11.4	28.5	15.2	51	1.7	10.4	2.6	113	1.87	19.1	6.5	1.6	57	0.3	8.1	0.2	82	0.05	0.092
1092281	Soil		70.4	66.7	20.2	558	0.5	192.9	6.8	112	1.81	33.4	1.1	1.8	35	7.7	8.9	0.2	126	0.41	0.091
1092282	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092283	Soil		34.7	99.7	23.1	357	4.0	67.2	3.3	46	2.40	48.1	7.4	1.2	213	3.1	37.4	0.3	213	0.16	0.179
1092284	Soil		14.0	21.0	9.9	56	0.8	10.3	1.8	35	1.27	19.7	2.4	<0.1	29	0.3	6.0	0.2	73	0.02	0.097
1092285	Soil		19.1	18.1	19.8	104	2.4	19.3	2.3	66	1.35	32.9	0.8	0.3	116	0.3	14.7	0.3	151	0.02	0.083
1092286	Soil		40.7	33.5	17.0	95	3.5	21.3	3.4	91	2.76	63.0	29.0	0.5	114	1.4	18.7	0.3	197	0.08	0.169
1092287	Soil		10.4	21.1	16.9	59	1.7	14.4	3.5	128	2.21	25.3	3.9	0.2	52	0.2	6.7	0.3	102	0.06	0.094

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092358	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	38.5	77.4	21.9
1092359	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	33.8	38.2	22.2
1092360	Soil	1	3	0.02	21	0.013	<1	0.46	0.025	0.02	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1092361	Soil	4	10	0.02	67	<0.001	1	0.33	0.014	0.03	<0.1	0.06	0.2	0.4	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.
1092362	Soil	7	15	0.02	114	0.004	2	0.34	0.006	0.06	0.2	0.02	0.3	0.9	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.
1092363	Soil	11	27	0.04	229	0.004	4	0.46	0.004	0.08	0.4	0.30	1.3	1.6	0.07	2	11.8	<0.2	N.A.	N.A.	N.A.
1092364	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	47.1	52.9	26.4
1092365	Soil	10	14	0.02	108	0.006	2	0.24	0.002	0.07	0.1	0.04	0.5	0.5	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.
1092366	Soil	4	11	0.02	190	0.004	<1	0.29	0.005	0.07	0.1	0.19	0.4	0.7	0.08	2	2.7	0.3	N.A.	N.A.	N.A.
1092367	Soil	3	7	0.02	1057	0.002	<1	0.35	0.004	0.05	<0.1	0.05	1.3	0.2	<0.05	1	1.3	<0.2	N.A.	N.A.	N.A.
1092368	Soil	3	5	0.01	45	<0.001	<1	0.25	0.003	0.03	<0.1	0.05	1.8	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.
1092369	Soil	3	7	0.03	351	0.002	1	0.34	0.006	0.08	<0.1	0.12	4.4	0.4	0.05	1	0.9	<0.2	N.A.	N.A.	N.A.
1092370	Soil	4	16	0.05	703	0.003	2	0.44	0.005	0.10	<0.1	0.43	2.6	0.9	0.16	2	4.8	<0.2	N.A.	N.A.	N.A.
1092371	Soil	4	15	0.03	781	0.002	2	0.41	0.004	0.10	<0.1	0.43	3.2	1.0	0.18	2	5.1	<0.2	N.A.	N.A.	N.A.
1092372	Soil	4	16	0.05	756	0.003	2	0.47	0.005	0.10	0.1	0.46	3.1	1.0	0.18	2	6.0	<0.2	N.A.	N.A.	N.A.
1092373	Soil	3	10	0.04	259	0.002	1	0.36	0.004	0.07	<0.1	0.10	2.5	0.3	0.08	2	1.9	<0.2	N.A.	N.A.	N.A.
1092374	Soil	2	10	0.03	303	0.001	<1	0.40	0.007	0.10	<0.1	0.10	3.7	0.3	0.13	2	1.9	<0.2	N.A.	N.A.	N.A.
1092375	Soil	3	13	0.05	451	0.003	2	0.33	0.008	0.14	<0.1	0.52	2.4	0.8	0.29	2	5.2	<0.2	N.A.	N.A.	N.A.
1092376	Soil	4	20	0.03	622	0.002	3	0.36	0.012	0.22	<0.1	0.21	2.4	0.8	0.45	4	3.9	<0.2	N.A.	N.A.	N.A.
1092377	Soil	2	20	0.05	102	0.002	1	0.39	0.002	0.03	<0.1	0.98	9.3	0.7	<0.05	<1	2.5	<0.2	N.A.	N.A.	N.A.
1092378	Soil	5	15	0.03	820	0.002	2	0.42	0.004	0.10	<0.1	0.46	2.9	1.2	0.18	2	5.9	<0.2	N.A.	N.A.	N.A.
1092379	Soil	8	15	0.04	865	0.003	2	0.54	0.004	0.11	0.1	0.13	2.2	1.6	0.23	2	9.8	<0.2	N.A.	N.A.	N.A.
1092380	Soil	10	12	0.07	781	0.007	1	0.50	0.009	0.12	0.1	0.16	1.9	1.7	0.25	2	6.5	<0.2	N.A.	N.A.	N.A.
1092281	Soil	15	13	0.03	409	0.002	2	0.28	0.002	0.05	0.4	0.93	2.8	0.8	<0.05	<1	2.0	<0.2	N.A.	N.A.	N.A.
1092282	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	50.7	53.4	25.5
1092283	Soil	7	22	0.03	903	0.002	2	0.54	0.003	0.09	0.2	2.56	2.8	1.3	0.19	2	10.5	0.3	N.A.	N.A.	N.A.
1092284	Soil	5	8	0.02	333	0.002	1	0.42	0.011	0.05	0.1	0.27	0.2	0.6	0.11	2	2.3	<0.2	N.A.	N.A.	N.A.
1092285	Soil	3	13	0.01	569	0.005	2	0.29	0.002	0.08	0.2	0.28	0.5	1.0	0.14	3	6.1	<0.2	N.A.	N.A.	N.A.
1092286	Soil	5	16	0.05	324	0.004	2	0.38	0.003	0.16	0.6	5.62	0.7	4.5	0.45	2	13.5	0.2	N.A.	N.A.	N.A.
1092287	Soil	9	24	0.12	633	0.013	2	0.72	0.004	0.09	0.1	0.30	0.7	0.7	0.12	4	3.8	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092358	Soil		1218	1.2	174.5	17.4	309	3.43	69.8	3.2	3.1	77	10.8	10.6	0.2	218	1.09	0.167	18	38	0.47	1404
1092359	Soil		539	1.0	118.8	6.2	84	2.24	115.3	7.0	0.2	43	27.4	8.8	0.3	186	0.10	0.099	5	17	0.03	1085
1092360	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092361	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092362	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092363	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092364	Soil		545	1.2	80.9	5.4	87	2.19	35.7	8.6	<0.1	27	1.0	13.4	0.2	221	0.02	0.088	6	10	0.02	162
1092365	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092366	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092367	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092368	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092369	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092370	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092371	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092372	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092373	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092374	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092375	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092376	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092377	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092378	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092379	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092380	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092281	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092282	Soil		291	3.1	67.8	2.2	51	1.58	33.8	3.9	<0.1	127	3.6	12.7	0.3	274	0.22	0.114	6	25	0.04	1525
1092283	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092284	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092285	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092286	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092287	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092358	Soil	0.003	<20	0.51	0.004	0.09	0.1	1.46	4.8	0.7	0.08	2	6.0	<0.2
1092359	Soil	0.002	<20	0.38	0.002	0.06	0.1	0.48	0.8	1.3	0.17	2	6.6	<0.2
1092360	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092361	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092362	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092363	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092364	Soil	0.001	<20	0.29	0.004	0.07	0.1	0.37	0.2	1.1	0.08	2	7.3	<0.2
1092365	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092366	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092367	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092368	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092369	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092370	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092371	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092372	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092373	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092374	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092375	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092376	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092377	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092378	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092379	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092380	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092281	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092282	Soil	<0.001	<20	0.48	0.004	0.08	0.5	0.88	0.3	1.8	0.18	2	6.4	<0.2
1092283	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092284	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092286	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092287	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092288	Soil		10.0	5.9	9.1	27	0.3	5.8	0.8	25	0.68	15.2	0.6	<0.1	13	0.2	2.9	0.3	73	0.01	0.056
1092289	Soil		17.9	11.9	13.5	46	0.9	9.1	1.6	28	1.22	22.9	0.9	<0.1	39	<0.1	7.8	0.2	107	0.01	0.060
1092290	Soil		8.3	20.2	17.9	123	0.6	21.8	4.4	62	2.36	20.1	<0.5	0.2	17	0.2	3.8	0.3	70	0.02	0.053
1092291	Soil		6.9	10.1	6.2	72	0.1	12.2	2.4	24	1.00	10.0	<0.5	0.1	8	<0.1	1.6	0.2	52	<0.01	0.034
1092292	Soil		18.6	19.9	14.8	249	0.3	35.9	4.1	51	1.50	20.6	<0.5	<0.1	13	0.2	5.6	0.3	167	0.02	0.126
1092293	Soil		13.3	18.8	14.6	200	1.1	21.4	3.0	171	1.19	15.1	<0.5	<0.1	13	2.4	3.4	0.2	155	0.11	0.089
1092294	Soil		14.1	9.6	12.5	139	0.2	20.9	1.7	30	0.69	10.5	<0.5	<0.1	10	0.3	3.0	0.1	112	0.02	0.072
1092295	Soil		27.3	40.6	26.1	574	0.7	70.6	7.2	384	2.08	28.4	<0.5	0.4	22	4.5	8.0	0.3	189	0.07	0.091
1092296	Soil		1.7	3.3	4.6	22	0.6	3.7	0.5	12	0.20	1.9	1.5	<0.1	6	0.3	0.3	<0.1	39	0.03	0.060
1092297	Soil		9.5	24.9	12.9	319	0.1	47.4	6.8	76	2.18	9.6	<0.5	0.1	6	0.7	1.7	0.2	48	<0.01	0.108
1092298	Soil		3.2	10.6	5.9	51	0.1	9.9	2.0	33	0.69	6.1	<0.5	0.1	5	<0.1	0.8	<0.1	37	0.02	0.060
1092299	Soil		8.5	23.9	15.1	158	0.2	28.6	4.4	60	1.73	19.1	1.1	0.3	12	0.2	2.5	0.2	75	0.02	0.073
1092300	Soil		6.4	14.8	10.8	108	0.5	16.7	3.3	111	1.02	10.9	<0.5	0.3	13	0.6	2.3	0.1	60	0.03	0.132
1092651	Soil		33.9	121.9	27.7	139	3.3	98.0	2.4	85	3.09	221.4	2.1	4.2	242	0.4	18.4	0.3	432	0.08	0.427
1092652	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092653	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092654	Soil		17.7	14.8	31.4	40	1.9	8.3	1.1	20	1.25	39.0	15.3	0.2	21	0.1	10.3	0.3	117	0.02	0.055
1092655	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092656	Soil		10.9	27.9	41.1	36	4.6	11.9	0.8	11	1.23	36.1	12.2	0.5	40	0.2	10.0	0.3	101	0.05	0.134
1092657	Soil		19.2	44.2	37.3	17	4.9	16.7	0.4	8	1.18	23.1	<0.5	1.5	80	0.2	14.2	0.3	89	0.04	0.153
1092658	Soil		15.3	69.7	67.7	166	9.7	31.9	4.8	72	4.72	105.8	<0.5	6.0	138	1.0	11.7	0.4	174	0.09	1.002
1092659	Soil		5.5	45.7	25.8	166	0.5	43.3	15.2	227	3.32	35.8	1.1	2.0	34	0.9	3.7	0.2	39	0.07	0.056
1092660	Soil		11.5	43.4	31.3	125	2.5	65.5	8.4	87	2.64	171.8	3.9	2.3	70	1.2	9.7	0.2	98	0.10	0.136
1092711	Soil		6.0	50.3	13.6	144	2.2	25.8	3.5	101	1.99	20.3	5.9	0.3	48	1.3	3.9	0.1	132	0.08	0.157
1092712	Soil		4.5	18.1	15.7	88	0.8	18.7	3.3	113	2.27	18.8	1.1	1.1	19	0.3	1.9	0.2	98	0.03	0.074
1092713	Soil		6.0	16.4	16.6	79	0.7	16.2	2.6	72	1.73	14.9	<0.5	0.7	19	0.6	2.0	0.2	99	0.03	0.053
1092714	Soil		4.6	14.8	14.0	70	1.6	15.1	3.0	79	1.51	16.1	1.3	0.2	14	0.4	1.3	0.2	72	0.04	0.051
1092715	Soil		4.3	22.8	13.0	83	1.5	19.4	2.8	58	1.51	13.7	0.7	0.6	18	0.3	1.5	0.1	65	0.03	0.062
1092716	Soil		3.6	37.5	11.3	139	0.8	33.4	4.5	108	1.88	14.1	3.4	0.8	23	1.0	1.9	<0.1	59	0.09	0.070
1092717	Soil		17.3	56.0	25.6	305	0.9	73.8	12.1	220	3.97	46.6	5.6	4.0	38	0.9	6.6	0.2	139	0.09	0.104

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092288	Soil		4	6	0.01	459	0.005	2	0.26	0.006	0.05	0.1	0.08	0.1	0.9	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.
1092289	Soil		4	11	<0.01	736	0.003	<1	0.20	0.003	0.06	<0.1	0.08	0.1	0.7	0.11	3	3.3	<0.2	N.A.	N.A.	N.A.
1092290	Soil		6	12	0.02	158	0.007	1	0.42	0.003	0.04	<0.1	0.14	0.5	0.2	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.
1092291	Soil		6	8	0.02	91	0.003	1	0.36	0.002	0.03	<0.1	0.02	0.2	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.
1092292	Soil		7	15	0.02	161	0.002	2	0.48	0.005	0.06	0.1	0.12	<0.1	0.6	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.
1092293	Soil		5	12	0.04	623	0.004	4	0.66	0.015	0.04	<0.1	0.19	0.2	0.4	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.
1092294	Soil		5	12	0.03	131	0.002	1	0.39	0.010	0.05	<0.1	0.03	<0.1	0.5	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.
1092295	Soil		12	20	0.07	632	0.006	1	0.67	0.003	0.08	0.2	0.21	1.2	0.6	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.
1092296	Soil		5	7	0.02	168	0.004	2	0.40	0.013	0.03	<0.1	0.03	<0.1	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1092297	Soil		9	9	0.03	101	0.004	2	0.42	0.009	0.06	<0.1	0.03	0.3	0.2	<0.05	2	0.7	0.2	N.A.	N.A.	N.A.
1092298	Soil		8	6	0.02	107	0.002	1	0.32	0.010	0.04	<0.1	0.02	<0.1	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1092299	Soil		15	10	0.03	267	0.003	2	0.52	0.002	0.08	<0.1	0.05	0.2	0.3	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.
1092300	Soil		7	11	0.04	204	0.003	2	0.54	0.008	0.07	<0.1	0.06	0.3	0.3	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.
1092651	Soil		13	59	0.03	552	0.004	<1	2.70	0.002	0.09	0.4	1.43	5.4	1.8	0.11	5	18.8	0.2	N.A.	N.A.	N.A.
1092652	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	29.8	33.0	63.1
1092653	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	31.8	36.1	36.6
1092654	Soil		6	16	0.01	447	0.002	5	0.24	0.002	0.13	0.1	0.56	0.4	0.9	0.21	3	11.8	0.3	N.A.	N.A.	N.A.
1092655	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	16.8	24.9	47.0
1092656	Soil		4	16	0.02	702	0.002	4	0.30	0.002	0.14	0.2	6.34	0.9	1.4	0.35	2	6.5	<0.2	N.A.	N.A.	N.A.
1092657	Soil		4	25	0.01	568	0.001	6	0.31	0.003	0.17	0.3	7.96	1.6	1.8	0.41	2	8.2	<0.2	N.A.	N.A.	N.A.
1092658	Soil		9	33	0.06	578	0.005	6	0.71	0.005	0.19	<0.1	4.61	7.2	0.9	0.32	3	45.5	0.4	N.A.	N.A.	N.A.
1092659	Soil		4	14	0.08	522	<0.001	2	0.69	0.002	0.07	<0.1	0.28	3.3	0.3	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.
1092660	Soil		3	15	0.04	811	<0.001	2	0.40	0.003	0.08	<0.1	2.06	4.0	1.0	0.06	2	13.2	<0.2	N.A.	N.A.	N.A.
1092711	Soil		8	23	0.09	567	0.002	4	0.87	0.004	0.09	0.1	0.73	0.6	0.4	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.
1092712	Soil		7	19	0.08	320	0.004	1	0.95	0.004	0.07	0.1	0.08	1.2	0.3	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.
1092713	Soil		9	18	0.06	389	0.006	1	0.79	0.004	0.07	0.2	0.07	0.9	0.3	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.
1092714	Soil		10	17	0.08	299	0.008	2	0.69	0.004	0.07	<0.1	0.09	0.4	0.2	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.
1092715	Soil		7	18	0.06	263	0.004	2	0.69	0.005	0.07	<0.1	0.12	0.9	0.2	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.
1092716	Soil		5	22	0.09	731	0.002	2	0.90	0.009	0.08	<0.1	0.48	1.7	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.
1092717	Soil		14	27	0.18	403	0.005	3	1.21	0.003	0.10	0.2	0.40	2.7	0.5	<0.05	3	2.9	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
	Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
	MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092288	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092289	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092290	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092291	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092292	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092293	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092294	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092295	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092296	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092297	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092298	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092299	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092300	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092651	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092652	Soil	54	5.8	13.0	1.0	19	2.13	108.9	120.4	0.6	61	0.3	26.6	0.4	187	0.03	0.119	6	23	0.02	996
1092653	Soil	168	2.7	50.5	2.3	33	2.41	86.9	23.7	0.5	62	0.7	23.7	0.3	221	0.04	0.149	11	29	0.02	1087
1092654	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092655	Soil	70	4.6	13.6	1.4	27	1.88	42.9	13.7	0.2	49	0.2	11.5	0.4	120	0.03	0.171	3	21	0.02	484
1092656	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092657	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092658	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092659	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092660	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092711	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092712	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092713	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092714	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092715	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092716	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092717	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092288	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092289	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092290	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092291	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092292	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092293	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092294	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092295	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092296	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092297	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092298	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092299	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092300	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092651	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092652	Soil	0.002	<20	0.36	0.001	0.13	0.3	9.96	1.0	2.5	0.29	4	24.6	0.3
1092653	Soil	0.002	<20	0.59	0.003	0.09	0.3	2.16	0.9	1.8	0.28	4	24.5	0.3
1092654	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092655	Soil	0.002	<20	0.33	0.002	0.09	0.2	8.78	0.8	1.1	0.18	2	14.6	0.2
1092656	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092657	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092658	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092659	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092660	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092711	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092712	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092713	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092714	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092715	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092716	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092717	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092718	Soil		4.8	60.0	14.0	99	1.5	28.4	6.1	97	2.79	12.9	3.3	1.1	18	0.1	1.3	<0.1	46	0.04	0.071
1092719	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092720	Soil		3.7	44.3	17.4	106	1.5	40.4	6.3	77	2.85	12.4	0.9	1.8	29	0.2	0.9	0.1	27	0.02	0.063
1092721	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092722	Soil		2.3	24.6	11.7	131	1.5	47.1	6.5	138	2.09	6.6	5.8	0.3	104	0.6	1.1	0.6	28	2.59	0.127
1092723	Soil		2.3	40.0	15.3	159	1.4	53.1	8.1	134	2.54	10.5	7.5	0.6	93	1.0	1.3	0.2	28	1.74	0.151
1092724	Soil		3.6	42.0	19.2	209	2.0	55.6	7.9	165	2.80	14.2	6.4	1.2	116	1.3	2.0	0.2	51	1.61	0.268
1092725	Soil		2.5	31.2	17.6	153	1.6	44.5	5.2	74	2.54	12.4	4.7	1.8	61	0.9	1.4	0.2	42	0.77	0.181
1092726	Soil		2.3	28.1	13.0	137	1.4	40.7	3.9	59	1.98	10.2	3.6	1.0	63	0.8	1.7	0.2	39	1.28	0.195
1092727	Soil		3.0	44.3	16.7	182	1.5	59.5	7.0	97	2.54	16.6	2.4	2.4	138	1.7	2.8	0.2	43	5.07	0.263
1092728	Soil		3.7	50.0	28.0	185	2.0	67.4	13.0	92	3.15	28.2	7.4	1.0	72	0.9	1.8	0.2	27	1.29	0.130
1092729	Soil		2.6	41.4	34.2	89	2.0	31.7	4.8	66	2.88	46.8	6.6	2.3	102	0.3	1.5	0.2	23	0.74	0.115
1092730	Soil		2.1	69.0	18.9	118	1.2	49.4	6.8	104	2.32	54.6	19.0	1.4	74	0.7	2.4	0.5	25	0.70	0.102
1092731	Soil		3.5	78.7	54.0	141	2.8	49.0	25.5	529	5.76	92.3	16.0	4.7	111	0.3	2.2	0.3	28	0.05	0.158
1092732	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092733	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092734	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092735	Soil		2.9	94.9	25.6	164	1.5	55.0	13.8	258	4.43	25.6	7.1	3.1	76	0.2	1.5	0.3	31	0.03	0.112
1092736	Soil		5.0	143.0	65.7	245	2.2	94.8	63.8	8241	14.13	33.8	18.7	3.8	159	0.2	2.4	0.3	34	0.34	0.135
1092737	Soil		3.0	127.5	39.1	219	1.3	84.2	51.6	1620	5.16	19.9	13.6	4.2	77	0.2	1.4	0.3	27	0.13	0.109
1092738	Soil		3.3	110.2	32.4	168	1.2	54.3	22.8	533	4.55	23.5	5.8	4.0	85	0.2	1.4	0.2	32	0.04	0.115
1092739	Soil		3.4	119.6	33.3	164	1.0	54.9	27.6	700	4.71	23.6	9.3	4.1	88	0.1	1.5	0.3	29	0.04	0.114
1092740	Soil		3.0	110.0	34.6	149	1.3	50.7	25.5	691	4.57	24.8	6.7	4.3	77	<0.1	1.3	0.3	29	0.03	0.120
1092741	Soil		3.6	137.5	30.6	159	1.4	54.9	23.1	790	4.35	24.4	9.0	3.2	67	0.2	1.5	0.3	34	0.10	0.109
1092742	Soil		2.4	105.1	24.3	145	1.1	50.8	19.2	510	3.57	17.6	10.3	3.6	64	0.1	1.1	0.3	30	0.08	0.089
1092743	Soil		2.3	99.9	23.1	142	0.8	49.2	19.5	535	3.68	17.2	6.0	3.4	60	0.2	1.1	0.2	26	0.06	0.086
1092744	Soil		2.2	110.3	23.5	159	0.8	54.6	21.5	634	3.94	16.4	9.0	3.5	64	0.2	1.1	0.2	26	0.08	0.074
1092745	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092746	Soil		3.0	100.4	25.1	231	1.4	95.3	22.2	605	3.97	16.5	9.9	4.1	68	0.4	1.3	0.3	25	0.39	0.095
1092747	Soil		3.7	113.7	31.2	272	1.9	105.5	25.9	580	4.91	20.7	11.0	4.9	76	0.5	1.5	0.4	28	0.35	0.109

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092718	Soil		4	33	0.09	359	0.005	3	0.85	0.015	0.10	<0.1	0.14	3.2	0.2	<0.05	3	4.7	<0.2	N.A.	N.A.	N.A.
1092719	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.8	26.4	16.7
1092720	Soil		3	24	0.08	821	0.001	5	0.81	0.008	0.09	<0.1	0.18	3.8	0.1	0.07	2	5.0	<0.2	N.A.	N.A.	N.A.
1092721	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.7	29.7	10.9
1092722	Soil		7	20	0.11	625	0.005	8	0.54	0.007	0.05	<0.1	0.30	1.0	0.1	0.21	1	1.5	0.2	N.A.	N.A.	N.A.
1092723	Soil		9	22	0.20	590	0.002	7	0.61	0.005	0.07	<0.1	0.23	2.0	0.2	0.08	1	3.1	<0.2	N.A.	N.A.	N.A.
1092724	Soil		16	32	0.16	757	0.003	8	0.77	0.007	0.10	<0.1	0.21	2.9	0.3	0.10	2	2.1	<0.2	N.A.	N.A.	N.A.
1092725	Soil		11	25	0.08	558	0.002	6	0.66	0.007	0.11	<0.1	0.11	2.9	0.2	0.13	2	2.4	<0.2	N.A.	N.A.	N.A.
1092726	Soil		11	23	0.08	539	0.003	6	0.68	0.009	0.08	<0.1	0.12	2.0	0.2	0.09	2	2.9	<0.2	N.A.	N.A.	N.A.
1092727	Soil		10	22	0.08	583	0.002	4	0.72	0.008	0.12	<0.1	0.24	2.9	0.2	0.13	2	2.7	<0.2	N.A.	N.A.	N.A.
1092728	Soil		5	21	0.10	541	0.001	5	0.69	0.004	0.08	<0.1	0.30	3.3	0.2	0.06	2	3.1	0.2	N.A.	N.A.	N.A.
1092729	Soil		9	16	0.05	797	0.001	7	0.55	0.006	0.19	<0.1	0.56	3.0	0.3	0.32	1	3.8	<0.2	N.A.	N.A.	N.A.
1092730	Soil		7	16	0.05	592	0.001	5	0.59	0.004	0.10	<0.1	0.87	2.7	0.2	0.09	1	2.7	0.4	N.A.	N.A.	N.A.
1092731	Soil		4	35	0.11	488	0.001	3	1.06	0.009	0.15	<0.1	0.45	8.0	0.3	0.31	3	7.8	<0.2	N.A.	N.A.	N.A.
1092732	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.8	61.8	32.3
1092733	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.2	77.2	33.3
1092734	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.8	81.0	29.6
1092735	Soil		3	41	0.33	330	0.001	2	1.44	0.005	0.08	<0.1	0.13	4.3	0.2	0.12	3	3.0	<0.2	N.A.	N.A.	N.A.
1092736	Soil		5	38	0.79	725	0.002	3	2.01	0.005	0.06	<0.1	0.29	6.5	0.2	0.16	8	4.8	0.2	N.A.	N.A.	N.A.
1092737	Soil		3	35	0.52	1539	0.002	3	1.66	0.006	0.09	<0.1	0.17	5.6	0.2	0.08	4	2.2	<0.2	N.A.	N.A.	N.A.
1092738	Soil		3	38	0.38	690	0.002	3	1.46	0.008	0.09	<0.1	0.24	5.1	0.2	0.12	3	2.0	<0.2	N.A.	N.A.	N.A.
1092739	Soil		3	39	0.39	1380	0.002	4	1.45	0.010	0.11	<0.1	0.17	5.1	0.2	0.12	3	4.7	<0.2	N.A.	N.A.	N.A.
1092740	Soil		3	37	0.41	672	0.002	2	1.47	0.012	0.10	<0.1	0.10	5.4	0.2	0.12	4	2.3	<0.2	N.A.	N.A.	N.A.
1092741	Soil		4	37	0.41	1439	0.004	3	1.40	0.011	0.09	<0.1	0.16	5.6	0.2	0.07	4	2.2	0.2	N.A.	N.A.	N.A.
1092742	Soil		3	36	0.48	538	0.002	5	1.59	0.007	0.08	<0.1	0.17	4.2	0.1	0.07	3	1.0	<0.2	N.A.	N.A.	N.A.
1092743	Soil		2	33	0.45	638	0.002	1	1.49	0.007	0.09	<0.1	0.11	4.0	0.1	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.
1092744	Soil		2	34	0.47	731	0.002	<1	1.46	0.006	0.08	<0.1	0.11	4.1	0.1	<0.05	3	1.5	0.2	N.A.	N.A.	N.A.
1092745	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.1	76.5	23.3
1092746	Soil		5	35	0.43	1727	0.001	3	1.12	0.007	0.07	<0.1	0.27	5.8	0.1	0.09	2	3.0	<0.2	N.A.	N.A.	N.A.
1092747	Soil		5	37	0.44	1467	0.001	4	1.22	0.010	0.07	<0.1	0.41	6.1	0.1	0.11	2	2.3	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092718	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092719	Soil		69	0.8	22.0	8.9	246	2.09	9.8	1.3	0.3	19	0.2	0.4	0.2	21	0.11	0.098	4	24	0.12	352
1092720	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092721	Soil		168	1.5	56.1	7.8	180	2.65	9.8	4.8	0.4	104	0.7	1.0	0.2	31	1.85	0.128	8	22	0.11	567
1092722	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092723	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092724	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092725	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092726	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092727	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092728	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092729	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092730	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092731	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092732	Soil		101	1.9	33.1	10.7	255	3.73	62.8	8.5	0.8	75	0.2	1.5	0.2	23	0.07	0.128	4	27	0.09	467
1092733	Soil		147	2.9	40.0	13.7	305	4.07	42.3	7.8	2.9	86	0.2	0.9	0.3	27	0.06	0.121	4	34	0.20	425
1092734	Soil		143	2.2	45.6	20.2	364	4.04	31.2	8.3	3.7	78	0.2	1.1	0.3	26	0.06	0.112	3	35	0.33	385
1092735	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092736	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092737	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092738	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092739	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092740	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092741	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092742	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092743	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092744	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092745	Soil		148	1.4	53.4	17.0	870	3.25	12.3	7.9	1.4	168	0.2	0.9	0.2	22	0.58	0.101	4	32	0.37	685
1092746	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092747	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092718	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092719	Soil	0.003	<20	0.92	0.017	0.07	<0.1	0.11	1.6	0.1	0.07	2	1.9	<0.2
1092720	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092721	Soil	0.002	<20	0.59	0.006	0.05	<0.1	0.27	1.6	<0.1	0.18	2	3.7	<0.2
1092722	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092723	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092724	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092725	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092726	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092727	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092728	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092729	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092730	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092731	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092732	Soil	0.001	<20	0.86	0.006	0.12	<0.1	0.31	3.5	0.2	0.24	2	4.5	<0.2
1092733	Soil	<0.001	<20	1.14	0.006	0.11	<0.1	0.24	4.9	0.2	0.14	3	4.8	<0.2
1092734	Soil	<0.001	<20	1.31	0.005	0.10	<0.1	0.13	4.8	0.2	0.07	3	3.8	<0.2
1092735	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092736	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092737	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092738	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092739	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092740	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092741	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092742	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092743	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092744	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092745	Soil	0.002	<20	1.34	0.017	0.08	<0.1	0.19	3.1	0.1	0.12	3	2.9	<0.2
1092746	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092747	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092748	Soil		3.5	110.3	30.2	252	1.8	99.8	22.7	587	4.58	19.9	9.5	3.3	86	0.7	1.5	0.4	26	0.55	0.128
1092749	Soil		2.6	51.1	17.5	204	1.6	62.5	7.1	115	2.64	36.7	9.0	1.2	74	1.0	4.4	0.2	44	1.37	0.143
1092750	Soil		2.7	38.6	12.7	306	1.5	68.8	7.2	166	2.26	21.5	6.1	0.7	98	2.6	3.2	0.2	61	1.49	0.297
1092781	Soil		7.8	34.9	18.1	175	0.2	41.5	8.9	240	3.41	46.1	6.5	2.2	32	0.6	4.6	0.3	73	0.12	0.155
1092782	Soil		9.3	38.0	19.2	137	2.0	36.4	4.9	198	2.74	40.7	16.0	0.9	56	1.2	3.7	0.3	98	0.39	0.136
1092783	Soil		5.9	29.7	13.0	109	2.2	33.3	5.4	313	1.98	30.0	17.5	0.5	55	0.5	2.8	0.2	66	0.68	0.123
1092784	Soil		5.6	21.4	21.5	107	0.4	25.3	4.6	85	2.92	46.1	2.1	1.1	23	0.3	2.7	0.3	77	0.04	0.145
1092785	Soil		5.2	18.4	11.4	256	2.2	38.8	13.1	333	2.42	30.7	4.5	1.6	26	3.3	3.3	0.2	102	0.32	0.088
1092786	Soil		4.5	13.3	13.2	66	0.2	13.6	2.8	85	1.60	23.7	5.2	0.4	15	0.2	1.7	0.3	71	0.03	0.049
1092787	Soil		5.7	15.9	17.2	97	0.2	19.9	3.4	82	1.99	27.1	<0.5	1.0	23	0.5	2.6	0.3	79	0.03	0.049
1092788	Soil		7.3	20.3	16.2	116	2.1	23.6	3.6	50	2.02	37.0	4.5	0.8	21	0.3	12.0	0.3	81	0.01	0.044
1092789	Soil		2.8	8.8	6.1	22	0.4	5.5	0.9	12	0.43	6.0	<0.5	<0.1	31	<0.1	1.1	0.2	41	0.02	0.043
1092790	Soil		5.4	21.1	12.8	91	0.3	17.2	3.0	45	1.57	21.5	0.8	0.7	18	0.1	3.2	0.2	63	<0.01	0.031
1092791	Soil		6.6	24.2	16.0	100	0.4	26.7	5.3	134	2.53	34.4	4.6	1.2	28	0.2	3.7	0.3	69	0.05	0.081
1092792	Soil		7.7	16.3	11.0	81	0.1	20.0	3.2	37	0.99	19.4	<0.5	0.1	9	0.2	2.5	0.2	77	0.01	0.038
1092793	Soil		12.0	25.7	14.1	118	0.2	28.1	4.1	53	1.74	35.2	2.4	0.2	15	0.2	3.6	0.2	93	0.02	0.057
1092794	Soil		7.3	28.4	8.4	60	0.8	12.8	1.6	31	1.15	11.0	<0.5	<0.1	20	0.3	2.1	0.2	83	0.03	0.104
1092795	Soil		13.7	27.4	12.7	154	1.7	29.5	2.1	31	1.80	30.1	2.8	0.7	25	0.4	6.1	0.2	162	0.02	0.091
1092796	Soil		9.6	24.8	11.8	85	0.5	21.4	2.4	79	2.51	41.1	<0.5	0.2	60	0.2	5.5	0.2	161	0.07	0.233
1092797	Soil		17.4	46.2	15.3	240	0.7	45.9	3.5	108	2.59	42.2	2.7	<0.1	28	0.8	7.8	0.2	166	0.03	0.188
1092798	Soil		14.3	35.9	16.3	170	0.5	37.9	3.1	62	2.69	33.4	<0.5	<0.1	37	0.3	5.1	0.3	172	0.03	0.166
1092799	Soil		18.8	63.0	20.8	277	0.7	51.5	4.2	104	4.76	52.6	1.0	0.1	39	0.5	9.8	0.3	216	0.04	0.279
1092800	Soil		11.1	35.5	13.0	139	0.3	29.4	4.0	162	2.47	28.9	<0.5	0.2	39	0.4	5.1	0.2	154	0.04	0.168
1092821	Soil		2.0	8.7	5.5	39	0.6	7.8	2.1	63	1.02	6.4	<0.5	0.2	6	0.1	0.9	0.1	46	0.02	0.032
1092822	Soil		3.1	12.6	6.8	57	<0.1	10.0	2.2	45	0.96	16.2	<0.5	0.3	7	<0.1	1.4	0.1	57	0.01	0.031
1092823	Soil		5.2	22.7	11.6	120	0.3	20.5	3.9	134	2.78	24.3	0.6	1.6	14	0.3	2.5	0.2	79	0.02	0.069
1092824	Soil		0.3	4.1	0.9	5	0.2	3.1	0.6	34	0.17	<0.5	<0.5	<0.1	47	0.1	0.2	<0.1	4	0.59	0.028
1092825	Soil		6.3	75.1	19.3	230	0.8	48.5	8.2	141	4.96	25.5	<0.5	2.2	17	0.4	3.3	0.4	66	0.04	0.078
1092826	Soil		7.0	35.9	16.3	224	0.3	38.0	5.6	119	4.58	32.6	<0.5	1.9	14	0.6	3.6	0.3	110	0.02	0.094
1092827	Soil		7.6	43.2	19.1	221	1.0	38.3	7.4	171	4.05	26.9	<0.5	1.7	28	1.1	3.3	0.3	94	0.03	0.090

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092748	Soil	4	37	0.41	1186	0.002	4	1.20	0.009	0.06	<0.1	0.36	5.8	0.1	0.13	2	1.7	0.3	N.A.	N.A.	N.A.
1092749	Soil	6	33	0.17	661	0.001	4	0.94	0.006	0.08	<0.1	1.77	3.0	0.2	0.09	2	1.6	<0.2	N.A.	N.A.	N.A.
1092750	Soil	14	32	0.10	608	0.004	4	0.93	0.010	0.08	0.1	0.66	2.6	0.2	0.07	2	1.7	<0.2	N.A.	N.A.	N.A.
1092781	Soil	8	25	0.16	242	0.004	3	0.99	0.003	0.06	0.2	0.37	1.9	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.
1092782	Soil	4	25	0.08	1442	0.001	1	0.89	0.005	0.08	0.1	1.80	2.7	0.5	<0.05	3	3.7	<0.2	N.A.	N.A.	N.A.
1092783	Soil	3	17	0.06	1119	0.002	3	0.75	0.011	0.06	0.1	1.83	1.8	0.4	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.
1092784	Soil	4	18	0.05	260	0.002	2	0.78	0.004	0.07	<0.1	0.14	1.2	0.2	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.
1092785	Soil	19	34	0.03	316	0.004	3	1.66	0.004	0.03	0.2	0.86	2.5	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.
1092786	Soil	9	15	0.07	144	0.007	1	0.73	0.004	0.04	0.2	0.09	0.5	0.2	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.
1092787	Soil	8	16	0.05	369	0.008	2	0.68	0.003	0.06	0.1	0.07	1.2	0.3	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.
1092788	Soil	7	11	0.02	1016	0.009	1	0.40	0.003	0.06	0.2	0.12	0.9	0.4	0.06	4	4.6	<0.2	N.A.	N.A.	N.A.
1092789	Soil	6	8	<0.01	158	0.002	3	0.29	0.006	0.04	<0.1	0.02	0.4	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.
1092790	Soil	5	8	0.02	139	0.002	2	0.39	0.002	0.05	<0.1	0.12	1.3	0.2	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.
1092791	Soil	9	19	0.12	223	0.008	1	0.84	0.005	0.06	0.1	0.14	1.3	0.3	<0.05	4	1.6	<0.2	N.A.	N.A.	N.A.
1092792	Soil	9	9	0.02	118	0.003	2	0.37	0.004	0.05	0.1	0.07	0.4	0.2	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.
1092793	Soil	9	14	0.02	163	0.003	2	0.45	0.005	0.06	0.2	0.18	0.4	0.3	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.
1092794	Soil	4	22	0.01	491	0.001	1	0.57	0.010	0.04	<0.1	0.05	<0.1	0.2	0.05	2	1.8	<0.2	N.A.	N.A.	N.A.
1092795	Soil	4	15	0.02	759	0.003	3	0.45	0.008	0.06	0.1	0.22	1.1	0.6	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.
1092796	Soil	3	26	0.04	432	0.003	3	0.56	0.004	0.08	0.1	0.10	0.5	0.5	0.06	2	2.4	<0.2	N.A.	N.A.	N.A.
1092797	Soil	5	21	0.02	653	0.002	2	0.56	0.004	0.06	0.1	0.33	0.1	0.5	0.10	2	4.2	<0.2	N.A.	N.A.	N.A.
1092798	Soil	5	31	0.03	529	0.002	3	0.62	0.004	0.08	0.1	0.15	0.2	0.5	0.09	3	3.0	<0.2	N.A.	N.A.	N.A.
1092799	Soil	5	38	0.03	1571	0.002	3	0.60	0.003	0.07	0.1	0.58	0.5	0.7	0.11	3	6.4	0.2	N.A.	N.A.	N.A.
1092800	Soil	6	32	0.04	365	0.004	2	0.61	0.005	0.07	0.1	0.13	0.4	0.5	<0.05	3	3.0	<0.2	N.A.	N.A.	N.A.
1092821	Soil	7	9	0.03	97	0.013	1	0.35	0.011	0.03	0.1	0.02	0.3	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.
1092822	Soil	10	7	0.02	175	0.004	<1	0.50	0.003	0.04	0.1	0.05	0.4	0.1	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.
1092823	Soil	8	17	0.07	380	0.007	3	0.73	0.003	0.07	<0.1	0.06	1.4	0.2	<0.05	5	1.3	<0.2	N.A.	N.A.	N.A.
1092824	Soil	1	2	0.03	246	0.008	<1	0.24	0.035	0.02	<0.1	0.03	0.3	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.
1092825	Soil	7	34	0.20	984	0.007	4	1.44	0.005	0.08	0.1	0.08	2.6	0.2	<0.05	5	1.5	0.3	N.A.	N.A.	N.A.
1092826	Soil	7	29	0.14	408	0.003	3	1.38	0.003	0.08	<0.1	0.09	2.3	0.2	<0.05	5	1.1	<0.2	N.A.	N.A.	N.A.
1092827	Soil	7	29	0.13	430	0.004	3	1.13	0.005	0.11	0.1	0.06	1.9	0.3	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
	Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
	MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092748	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092749	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092750	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092781	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092782	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092783	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092784	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092785	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092786	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092787	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092788	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092789	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092790	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092791	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092792	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092793	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092794	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092795	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092796	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092797	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092798	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092799	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092800	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092821	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092822	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092823	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092824	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092825	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092826	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092827	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092748	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092749	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092750	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092781	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092782	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092783	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092784	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092785	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092786	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092787	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092788	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092789	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092790	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092791	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092792	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092793	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092794	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092795	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092796	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092797	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092798	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092799	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092800	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092821	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092822	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092823	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092824	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092825	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092826	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092827	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092828	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092829	Soil		5.6	61.1	14.8	131	0.4	43.6	12.0	422	3.48	23.1	<0.5	0.5	8	0.1	2.9	0.3	51	0.01	0.069
1092830	Soil		6.0	23.8	6.7	60	0.2	19.5	4.5	59	1.17	9.4	<0.5	<0.1	5	0.2	1.5	0.1	50	0.01	0.074
1092831	Soil		1.7	8.8	3.5	27	0.4	6.5	1.7	34	0.51	1.7	<0.5	<0.1	5	0.1	0.6	<0.1	17	0.02	0.059
1092832	Soil		61.3	93.0	28.9	383	0.7	269.1	33.1	539	4.99	67.9	<0.5	1.4	75	3.6	11.2	0.1	371	0.70	0.264
1092833	Soil		14.7	32.5	11.8	115	0.3	62.0	9.0	156	2.01	15.6	<0.5	0.1	17	0.4	2.5	0.1	79	0.12	0.102
1092834	Soil		107.5	70.9	11.9	1023	1.1	266.1	7.3	160	2.07	37.3	0.6	2.9	86	10.1	12.4	0.2	526	2.42	0.119
1092835	Soil		67.6	92.6	20.5	892	1.2	231.7	17.7	419	3.49	56.4	<0.5	2.3	216	9.7	15.0	0.2	303	6.74	0.204
1092836	Soil		9.8	116.7	43.6	169	0.8	105.4	32.7	819	7.80	49.2	4.2	3.0	17	0.6	4.8	0.5	24	0.35	0.094
1092837	Soil		1.2	10.0	5.0	57	0.8	7.8	1.1	37	0.50	4.3	<0.5	<0.1	5	0.1	0.7	<0.1	12	0.03	0.063
1092838	Soil		1.8	48.4	29.9	177	0.3	35.8	6.2	1228	5.63	32.4	15.0	0.4	79	1.5	35.1	0.2	18	8.06	0.056
1092839	Soil		2.2	124.6	34.7	432	0.3	58.2	8.1	1160	7.68	49.8	41.2	0.5	173	3.9	88.8	<0.1	13	13.84	0.043
1092840	Soil		18.1	106.5	35.5	194	2.3	97.1	20.8	366	5.18	59.8	1.7	0.9	139	0.9	7.4	0.3	150	0.43	0.463
1092841	Soil		11.1	92.4	34.1	292	0.9	84.8	14.5	386	3.67	26.7	3.4	1.0	62	0.7	4.2	0.4	56	0.79	0.471
1092842	Soil		3.0	11.2	3.4	44	0.2	11.6	2.2	139	0.75	3.3	<0.5	0.1	11	0.2	0.7	<0.1	12	0.08	0.197
1092843	Soil		5.4	24.0	13.0	105	0.2	28.7	7.2	755	2.12	10.8	1.9	0.3	14	0.2	1.2	0.2	17	0.09	0.135
1092844	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092845	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092846	Soil		9.4	67.1	33.7	263	1.0	97.0	29.4	1047	5.87	21.2	5.3	2.2	17	0.3	1.9	0.4	16	0.13	0.078
1092847	Soil		12.8	73.0	32.5	444	0.7	119.8	14.7	203	3.17	29.4	3.7	2.1	145	2.3	3.9	0.3	52	0.59	0.277
1092848	Soil		6.0	71.0	18.8	306	0.9	97.8	14.9	282	3.15	19.2	3.6	2.0	84	0.6	2.3	0.3	32	0.70	0.223
1092849	Soil		19.8	42.6	22.9	181	0.8	47.5	4.9	51	2.20	23.7	0.7	0.3	70	0.3	4.5	0.3	89	0.03	0.173
1092850	Soil		6.2	222.1	33.3	645	1.4	162.0	17.3	286	6.66	109.1	6.1	2.2	180	5.8	20.9	0.5	46	0.26	0.251
1092891	Soil		1.9	21.8	13.7	120	2.1	36.3	5.4	79	1.85	13.1	8.4	1.1	38	0.7	2.6	0.2	28	0.74	0.085
1092892	Soil		2.5	33.0	13.6	269	1.6	51.3	6.2	191	2.17	18.0	5.7	0.4	87	2.8	4.1	0.2	37	2.10	0.201
1092893	Soil		<0.1	4.3	1.3	13	<0.1	2.1	0.7	34	0.21	1.0	<0.5	<0.1	16	0.2	0.1	<0.1	5	0.38	0.044
1092894	Soil		2.2	29.6	12.8	138	1.4	37.6	5.0	215	1.94	17.2	4.8	0.5	73	0.9	2.0	0.2	32	1.76	0.194
1092895	Soil		4.8	32.1	15.5	85	2.3	27.1	3.5	73	2.26	43.2	9.3	0.9	50	0.5	1.9	0.3	21	0.49	0.080
1092896	Soil		5.0	34.4	14.9	91	1.8	30.1	4.3	114	2.04	29.6	13.2	0.9	50	0.3	2.9	0.2	33	0.43	0.091
1092897	Soil		5.4	13.8	6.9	47	0.8	11.8	1.6	26	0.95	16.2	1.7	0.3	10	<0.1	3.4	<0.1	64	<0.01	0.027

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092828	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.8	41.5	6.0
1092829	Soil	4	19	0.02	109	0.004	3	0.48	0.004	0.08	<0.1	<0.01	2.5	0.2	<0.05	3	0.8	0.3	N.A.	N.A.	N.A.
1092830	Soil	3	8	0.02	52	0.003	<1	0.41	0.009	0.04	<0.1	0.01	0.2	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.
1092831	Soil	2	5	0.01	37	0.004	3	0.19	0.016	0.03	<0.1	<0.01	0.3	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.
1092832	Soil	26	61	0.06	694	0.002	5	0.68	0.003	0.14	0.2	0.38	8.3	1.1	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.
1092833	Soil	7	22	0.03	296	0.002	1	0.44	0.016	0.06	<0.1	0.12	0.7	0.3	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.
1092834	Soil	12	25	0.10	488	0.003	7	0.44	0.002	0.16	0.3	0.53	4.4	2.3	<0.05	1	6.4	0.3	N.A.	N.A.	N.A.
1092835	Soil	14	30	2.44	613	0.002	6	0.40	0.005	0.11	0.1	0.75	5.0	1.1	0.09	1	6.5	<0.2	N.A.	N.A.	N.A.
1092836	Soil	20	18	0.10	613	0.002	5	0.60	0.003	0.15	<0.1	0.23	7.0	0.3	0.10	2	1.8	0.2	N.A.	N.A.	N.A.
1092837	Soil	1	4	0.01	27	0.002	<1	0.22	0.019	0.02	<0.1	0.05	0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.
1092838	Soil	5	5	4.55	130	0.006	4	0.40	0.009	0.02	<0.1	0.30	1.1	0.1	0.10	1	0.6	<0.2	N.A.	N.A.	N.A.
1092839	Soil	3	8	7.23	145	0.003	6	0.18	0.010	0.03	<0.1	1.83	1.9	<0.1	0.33	<1	1.6	<0.2	N.A.	N.A.	N.A.
1092840	Soil	27	36	0.11	383	0.012	4	0.71	0.005	0.26	0.2	0.85	2.8	1.5	0.45	2	6.2	0.2	N.A.	N.A.	N.A.
1092841	Soil	18	16	0.11	806	0.004	7	0.67	0.003	0.20	<0.1	0.25	2.1	0.2	0.13	2	4.3	0.3	N.A.	N.A.	N.A.
1092842	Soil	3	5	0.03	213	0.004	3	0.27	0.015	0.07	<0.1	0.04	0.5	<0.1	0.10	<1	1.2	<0.2	N.A.	N.A.	N.A.
1092843	Soil	7	7	0.03	310	0.001	<1	0.35	0.005	0.07	<0.1	0.03	0.5	0.1	0.05	1	1.2	<0.2	N.A.	N.A.	N.A.
1092844	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.4	73.9	33.3
1092845	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.1	37.8	17.5
1092846	Soil	12	11	0.10	671	0.007	2	0.55	0.005	0.13	<0.1	0.18	5.4	0.2	<0.05	1	2.6	<0.2	N.A.	N.A.	N.A.
1092847	Soil	19	13	0.06	639	0.003	5	0.50	0.002	0.16	<0.1	0.26	3.1	0.2	0.06	1	4.1	0.2	N.A.	N.A.	N.A.
1092848	Soil	17	10	0.08	799	0.003	5	0.50	0.005	0.11	<0.1	0.23	3.3	0.2	0.08	1	2.7	<0.2	N.A.	N.A.	N.A.
1092849	Soil	11	11	0.03	254	0.002	<1	0.54	0.005	0.08	0.2	0.09	0.4	0.7	0.17	2	4.3	<0.2	N.A.	N.A.	N.A.
1092850	Soil	13	28	0.05	330	0.002	3	0.48	0.004	0.22	<0.1	0.41	4.9	0.6	0.46	2	2.8	<0.2	N.A.	N.A.	N.A.
1092891	Soil	5	16	0.03	805	0.001	4	0.36	0.004	0.06	<0.1	0.40	2.8	0.1	0.07	1	1.0	<0.2	N.A.	N.A.	N.A.
1092892	Soil	10	30	0.07	616	0.002	3	0.67	0.006	0.05	0.1	0.94	1.8	<0.1	0.10	2	2.5	<0.2	N.A.	N.A.	N.A.
1092893	Soil	2	3	0.02	46	0.008	<1	0.41	0.027	0.02	<0.1	0.03	0.3	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.
1092894	Soil	10	29	0.07	872	0.002	2	0.76	0.010	0.05	0.2	1.57	1.9	<0.1	0.08	2	4.4	<0.2	N.A.	N.A.	N.A.
1092895	Soil	3	15	0.04	627	<0.001	5	0.33	0.004	0.08	<0.1	1.22	2.2	<0.1	0.09	1	2.9	<0.2	N.A.	N.A.	N.A.
1092896	Soil	4	22	0.05	1181	0.002	<1	0.58	0.005	0.07	<0.1	1.82	2.6	0.2	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.
1092897	Soil	3	7	<0.01	146	0.002	2	0.17	0.002	0.03	0.1	0.06	0.6	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
	Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
	MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092828	Soil	175	1.2	53.2	4.3	201	0.99	7.4	5.1	0.5	404	3.3	1.8	0.1	30	1.48	0.081	3	11	0.12	2179
1092829	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092830	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092831	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092832	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092833	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092834	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092835	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092836	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092837	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092838	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092839	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092840	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092841	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092842	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092843	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092844	Soil	214	2.8	59.2	11.6	190	3.72	20.9	3.2	<0.1	72	0.5	2.5	0.3	23	0.20	0.231	6	10	0.07	2116
1092845	Soil	110	0.4	48.8	24.4	1239	2.55	13.3	5.7	0.4	26	0.8	1.3	0.3	25	0.24	0.111	10	18	0.13	871
1092846	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092847	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092848	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092849	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092850	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092891	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092892	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092893	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092894	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092895	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092896	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092897	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092828	Soil	0.004	<20	0.74	0.017	0.04	<0.1	0.40	1.3	0.2	0.11	2	3.1	<0.2
1092829	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092830	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092831	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092832	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092833	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092834	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092835	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092836	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092837	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092838	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092839	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092840	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092841	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092842	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092843	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092844	Soil	0.001	<20	1.01	0.006	0.14	<0.1	0.18	0.3	0.2	0.28	2	4.7	<0.2
1092845	Soil	0.010	<20	0.61	0.019	0.10	<0.1	0.11	2.4	0.2	0.09	2	1.0	<0.2
1092846	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092847	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092848	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092849	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092850	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092891	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092892	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092893	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092894	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092895	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092896	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092897	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092898	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092899	Soil		8.6	21.1	16.5	64	1.0	17.8	2.3	30	1.52	62.1	4.6	0.3	30	<0.1	11.9	0.2	89	0.02	0.066
1092900	Soil		2.0	7.4	3.6	27	0.1	6.6	1.8	26	0.56	6.7	1.4	<0.1	3	<0.1	0.6	<0.1	21	0.01	0.025
1092901	Soil		5.4	99.5	44.2	289	4.3	67.3	11.8	276	4.52	43.4	5.8	1.4	105	1.0	4.7	0.4	33	0.41	0.408
1092902	Soil		6.5	252.9	40.7	491	3.1	162.5	33.9	1555	8.80	69.9	5.6	5.1	110	1.9	4.8	0.4	54	0.68	0.496
1092903	Soil		3.7	91.4	33.8	160	2.7	92.8	22.1	405	5.92	32.1	5.9	3.2	68	0.4	3.7	0.3	16	0.32	0.143
1092904	Soil		3.4	84.8	26.6	130	2.1	86.3	19.5	334	6.11	24.2	4.5	4.9	40	0.4	3.3	0.3	16	0.22	0.125
1092905	Soil		83.2	54.3	31.0	997	0.3	118.9	13.0	558	3.91	42.6	1.2	0.7	14	11.5	19.4	0.2	185	0.17	0.135
1092906	Soil		90.3	73.8	10.2	304	0.3	195.4	8.3	178	2.16	30.1	1.1	1.0	47	3.9	5.0	0.1	84	1.32	0.104

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
Analyte		La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
Unit		ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092898	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.6	20.1	12.3
1092899	Soil	2	14	0.01	207	0.001	2	0.27	0.002	0.05	<0.1	0.26	1.0	0.6	0.06	3	4.1	<0.2	N.A.	N.A.	N.A.
1092900	Soil	6	5	0.01	40	0.002	<1	0.21	0.007	0.03	<0.1	0.03	0.1	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1092901	Soil	14	17	0.10	2973	0.004	2	1.17	0.005	0.16	<0.1	0.63	2.4	0.2	0.15	2	8.6	<0.2	N.A.	N.A.	N.A.
1092902	Soil	15	21	0.09	1933	0.004	2	1.01	0.005	0.19	<0.1	0.87	8.0	0.3	0.14	1	6.4	<0.2	N.A.	N.A.	N.A.
1092903	Soil	13	9	0.08	3472	0.003	2	0.58	0.008	0.10	<0.1	0.64	7.3	0.2	0.13	<1	3.1	<0.2	N.A.	N.A.	N.A.
1092904	Soil	19	9	0.07	6773	0.001	1	0.77	0.002	0.07	<0.1	0.54	7.8	0.2	0.06	1	2.4	<0.2	N.A.	N.A.	N.A.
1092905	Soil	11	22	0.07	482	0.003	1	0.51	0.003	0.07	0.1	0.17	2.2	0.7	<0.05	1	4.5	<0.2	N.A.	N.A.	N.A.
1092906	Soil	14	19	0.48	376	0.002	2	0.44	0.004	0.08	0.3	0.15	3.0	1.4	0.05	1	3.8	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
	Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
	MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092898	Soil	62	2.1	23.9	3.0	58	1.42	15.9	2.8	0.2	15	0.2	2.0	0.2	89	0.04	0.044	14	35	0.02	504
1092899	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092900	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092901	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092902	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092903	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092904	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092905	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092906	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000766.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092898	Soil	0.006	<20	0.31	0.004	0.06	0.1	0.11	0.6	0.2	<0.05	2	1.5	<0.2
1092899	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092900	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092901	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092902	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092903	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092904	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092905	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092906	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000766.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1092150	Soil		63.0	200.1	17.7	1514	3.7	336.3	8.7	292	2.68	56.3	3.6	1.1	93	23.2	27.4	0.3	440	2.15	0.254
REP 1092150	QC		65.1	202.5	17.6	1514	3.7	331.4	8.8	286	2.65	57.2	3.0	1.1	92	22.6	27.6	0.3	446	2.20	0.260
1092166	Soil		23.0	21.8	13.0	131	0.2	40.6	4.7	57	1.42	19.4	1.9	0.2	9	0.2	3.1	0.2	113	0.01	0.041
REP 1092166	QC		22.6	21.1	12.5	123	0.2	37.9	4.5	56	1.37	18.2	0.9	0.3	9	0.2	3.2	0.2	109	0.01	0.040
1092179	Soil		5.2	75.8	7.4	148	0.1	314.5	60.8	792	6.91	20.4	0.7	2.1	70	0.8	1.7	<0.1	125	1.99	0.138
REP 1092179	QC		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092191	Soil		5.7	19.1	3.6	540	0.2	63.9	4.9	138	1.15	6.6	1.4	0.5	42	3.2	1.7	<0.1	72	0.75	0.179
REP 1092191	QC		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092267	Soil		31.4	134.1	23.2	434	0.7	435.5	76.2	637	7.11	37.0	3.6	8.1	193	2.4	6.8	0.2	164	2.26	0.297
REP 1092267	QC		31.1	134.3	22.8	437	0.8	449.9	76.5	636	7.09	36.6	1.5	8.2	193	2.6	6.8	0.2	170	2.25	0.310
1092270	Soil		10.7	71.0	7.6	360	0.2	281.2	51.9	966	7.06	28.2	<0.5	2.4	57	2.2	2.7	<0.1	125	0.96	0.206
REP 1092270	QC		10.7	71.2	7.8	367	0.2	284.8	52.3	983	7.02	28.1	<0.5	2.4	56	2.2	2.6	<0.1	128	0.93	0.203
1092319	Soil		22.4	53.2	17.4	409	0.6	95.0	7.3	81	2.80	35.9	2.1	0.7	22	1.2	7.3	0.2	105	0.07	0.133
REP 1092319	QC		22.4	52.9	17.1	408	0.6	94.4	7.2	81	2.83	35.9	4.8	0.8	22	1.1	7.6	0.2	104	0.07	0.144
1092348	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1092348	QC		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1092361	Soil		7.2	9.6	10.6	119	0.7	19.5	1.1	24	0.66	9.0	2.0	<0.1	8	0.4	3.0	<0.1	80	0.02	0.105
REP 1092361	QC		7.0	9.4	11.0	120	0.7	19.3	1.0	19	0.64	8.7	2.1	<0.1	9	0.3	3.1	<0.1	78	0.02	0.099
1092373	Soil		2.7	25.7	20.6	48	0.8	13.4	4.8	166	1.93	11.8	4.2	0.4	25	<0.1	6.9	0.3	43	0.03	0.039
REP 1092373	QC		2.9	25.6	20.9	49	0.8	13.8	5.1	172	1.91	11.9	5.3	0.4	26	<0.1	6.9	0.3	44	0.03	0.041
1092289	Soil		17.9	11.9	13.5	46	0.9	9.1	1.6	28	1.22	22.9	0.9	<0.1	39	<0.1	7.8	0.2	107	0.01	0.060
REP 1092289	QC		18.1	11.1	12.9	45	0.9	8.3	1.5	27	1.19	23.1	<0.5	<0.1	39	0.1	7.6	0.2	104	0.01	0.059
1092717	Soil		17.3	56.0	25.6	305	0.9	73.8	12.1	220	3.97	46.6	5.6	4.0	38	0.9	6.6	0.2	139	0.09	0.104
REP 1092717	QC		18.1	56.7	25.9	308	1.0	75.2	12.2	218	3.96	47.5	6.7	4.0	37	1.0	6.5	0.2	145	0.09	0.100
1092723	Soil		2.3	40.0	15.3	159	1.4	53.1	8.1	134	2.54	10.5	7.5	0.6	93	1.0	1.3	0.2	28	1.74	0.151
REP 1092723	QC		2.4	40.6	15.2	165	1.4	51.2	8.6	138	2.55	8.9	4.0	0.9	93	0.9	1.1	0.1	31	1.76	0.157
1092781	Soil		7.8	34.9	18.1	175	0.2	41.5	8.9	240	3.41	46.1	6.5	2.2	32	0.6	4.6	0.3	73	0.12	0.155
REP 1092781	QC		8.3	34.7	18.5	173	0.3	42.0	8.8	240	3.39	48.2	6.7	2.1	33	0.5	4.7	0.3	70	0.11	0.163

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000766.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
Pulp Duplicates																					
1092150	Soil	16	79	0.77	559	0.004	5	0.51	0.003	0.12	0.2	1.46	4.0	1.3	0.08	1	25.6	0.3	N.A.	N.A.	N.A.
REP 1092150	QC	17	81	0.78	576	0.005	6	0.53	0.003	0.12	0.2	1.57	3.9	1.3	<0.05	1	26.4	0.4			
1092166	Soil	14	11	0.04	102	0.005	1	0.49	0.004	0.04	0.1	0.05	0.5	0.4	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.
REP 1092166	QC	13	11	0.04	96	0.004	<1	0.47	0.004	0.04	0.1	0.05	0.4	0.3	<0.05	4	0.9	<0.2			
1092179	Soil	43	188	1.02	4081	0.009	10	1.76	0.005	0.10	0.1	0.11	13.0	0.2	0.07	6	0.8	<0.2	N.A.	N.A.	N.A.
REP 1092179	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.			
1092191	Soil	11	47	0.40	316	0.008	3	0.87	0.020	0.05	<0.1	0.08	1.3	1.5	0.09	3	1.1	<0.2	N.A.	N.A.	N.A.
REP 1092191	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.			
1092267	Soil	38	109	0.75	1915	0.004	12	0.76	0.008	0.21	0.1	0.17	17.0	1.1	0.13	2	5.8	<0.2	N.A.	N.A.	N.A.
REP 1092267	QC	39	114	0.77	2042	0.006	13	0.83	0.009	0.22	0.1	0.21	17.1	1.0	0.14	3	4.3	<0.2			
1092270	Soil	37	112	0.37	5870	0.005	5	1.45	0.007	0.10	<0.1	0.11	14.8	0.2	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.
REP 1092270	QC	37	115	0.37	5893	0.003	5	1.47	0.007	0.10	0.1	0.11	14.8	0.2	<0.05	4	1.5	<0.2			
1092319	Soil	15	14	0.04	369	0.002	3	0.38	0.002	0.06	<0.1	0.69	1.0	0.6	<0.05	1	2.7	<0.2	N.A.	N.A.	N.A.
REP 1092319	QC	18	14	0.04	385	0.003	2	0.40	0.003	0.07	<0.1	0.74	1.6	0.6	0.06	1	2.8	<0.2			
1092348	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.4	28.9	10.4
REP 1092348	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.			
1092361	Soil	4	10	0.02	67	<0.001	1	0.33	0.014	0.03	<0.1	0.06	0.2	0.4	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.
REP 1092361	QC	4	10	0.02	68	<0.001	<1	0.33	0.014	0.03	<0.1	0.06	<0.1	0.4	<0.05	1	<0.5	<0.2			
1092373	Soil	3	10	0.04	259	0.002	1	0.36	0.004	0.07	<0.1	0.10	2.5	0.3	0.08	2	1.9	<0.2	N.A.	N.A.	N.A.
REP 1092373	QC	3	10	0.04	263	0.003	<1	0.37	0.004	0.07	<0.1	0.09	2.7	0.3	0.09	2	2.2	<0.2			
1092289	Soil	4	11	<0.01	736	0.003	<1	0.20	0.003	0.06	<0.1	0.08	0.1	0.7	0.11	3	3.3	<0.2	N.A.	N.A.	N.A.
REP 1092289	QC	4	11	<0.01	763	0.004	3	0.19	0.003	0.06	<0.1	0.06	<0.1	0.7	0.09	3	3.7	0.2			
1092717	Soil	14	27	0.18	403	0.005	3	1.21	0.003	0.10	0.2	0.40	2.7	0.5	<0.05	3	2.9	<0.2	N.A.	N.A.	N.A.
REP 1092717	QC	14	27	0.18	399	0.005	2	1.24	0.003	0.11	0.2	0.38	3.0	0.5	<0.05	3	2.8	<0.2			
1092723	Soil	9	22	0.20	590	0.002	7	0.61	0.005	0.07	<0.1	0.23	2.0	0.2	0.08	1	3.1	<0.2	N.A.	N.A.	N.A.
REP 1092723	QC	9	23	0.21	614	0.002	6	0.65	0.006	0.07	<0.1	0.24	2.3	0.1	0.11	1	3.0	<0.2			
1092781	Soil	8	25	0.16	242	0.004	3	0.99	0.003	0.06	0.2	0.37	1.9	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.
REP 1092781	QC	8	25	0.16	235	0.004	2	0.99	0.003	0.06	0.1	0.34	1.8	0.3	<0.05	2	2.3	<0.2			

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000766.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
	Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
	MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
Pulp Duplicates																					
1092150	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092150	QC																				
1092166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092166	QC																				
1092179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092179	QC																				
1092191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092191	QC																				
1092267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092267	QC																				
1092270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092270	QC																				
1092319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092319	QC																				
1092348	Soil	86	0.2	39.1	10.5	225	3.06	35.9	1.6	<0.1	10	0.1	1.7	0.3	19	0.04	0.063	6	8	0.04	1019
REP 1092348	QC																				
1092361	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092361	QC																				
1092373	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092373	QC																				
1092289	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092289	QC																				
1092717	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092717	QC																				
1092723	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092723	QC																				
1092781	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092781	QC																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000766.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates															
1092150	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092150	QC														
1092166	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092166	QC														
1092179	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092179	QC														
1092191	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092191	QC														
1092267	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092267	QC														
1092270	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092270	QC														
1092319	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092319	QC														
1092348	Soil		0.002	<20	0.33	0.009	0.06	<0.1	0.05	0.5	0.1	0.07	1	0.7	<0.2
REP 1092348	QC														
1092361	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092361	QC														
1092373	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092373	QC														
1092289	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092289	QC														
1092717	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092717	QC														
1092723	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092723	QC														
1092781	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092781	QC														

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000766.2

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092794	Soil		7.3	28.4	8.4	60	0.8	12.8	1.6	31	1.15	11.0	<0.5	<0.1	20	0.3	2.1	0.2	83	0.03	0.104
REP 1092794	QC		6.7	27.6	8.1	58	0.8	12.4	1.6	30	1.05	11.1	0.8	<0.1	20	0.3	2.1	0.1	83	0.03	0.105
1092824	Soil		0.3	4.1	0.9	5	0.2	3.1	0.6	34	0.17	<0.5	<0.5	<0.1	47	0.1	0.2	<0.1	4	0.59	0.028
REP 1092824	QC		0.3	4.3	0.8	5	0.1	2.8	0.5	35	0.18	0.6	<0.5	<0.1	47	<0.1	0.2	<0.1	5	0.60	0.028
1092904	Soil		3.4	84.8	26.6	130	2.1	86.3	19.5	334	6.11	24.2	4.5	4.9	40	0.4	3.3	0.3	16	0.22	0.125
REP 1092904	QC		3.2	84.7	26.0	125	2.1	83.0	19.8	341	6.22	23.4	7.1	4.8	40	0.5	3.3	0.3	16	0.21	0.125
Reference Materials																					
STD DS8	Standard		12.0	102.2	123.3	304	1.9	35.3	7.0	568	2.35	24.9	114.0	6.5	66	2.1	5.2	6.1	39	0.67	0.075
STD DS8	Standard		14.8	105.9	118.7	328	1.9	44.1	8.7	653	2.60	27.1	112.7	7.8	69	2.4	5.9	7.3	46	0.72	0.081
STD DS8	Standard		12.2	110.5	117.5	311	1.8	40.3	7.7	613	2.47	26.6	109.2	6.5	65	2.6	5.6	6.3	40	0.70	0.081
STD DS8	Standard		15.1	117.2	126.4	328	1.9	41.2	8.2	644	2.61	27.4	113.1	7.3	71	2.4	6.0	6.8	45	0.78	0.081
STD DS8	Standard		13.6	109.9	121.2	315	1.8	37.7	7.4	621	2.51	24.6	105.0	6.7	66	2.1	5.3	6.2	42	0.71	0.077
STD DS8	Standard		13.4	106.4	133.7	308	1.7	36.8	7.3	613	2.46	25.1	112.6	7.3	77	2.3	6.5	7.6	43	0.70	0.077
STD DS8	Standard		14.1	106.0	128.9	314	1.8	37.6	7.7	637	2.50	27.4	147.1	7.1	74	2.3	5.6	7.3	43	0.69	0.077
STD DS8	Standard		13.5	122.4	133.6	342	1.9	40.1	8.2	624	2.58	25.9	119.1	7.3	68	2.6	6.2	7.5	47	0.72	0.084
STD DS8	Standard		13.5	115.2	117.2	314	1.8	39.9	7.7	614	2.49	25.1	114.2	6.2	69	2.3	5.2	6.5	41	0.71	0.079
STD DS8	Standard		14.1	118.8	132.6	314	1.7	42.1	8.2	644	2.59	26.1	110.9	7.1	66	2.2	5.4	6.1	46	0.74	0.081
STD DS8	Standard		13.4	110.2	130.8	303	1.8	38.9	7.5	608	2.40	24.6	107.8	6.6	61	2.4	5.2	6.1	46	0.71	0.073
STD DS8	Standard		13.9	112.0	118.8	318	1.7	38.0	7.6	639	2.52	26.1	125.6	6.6	64	2.1	5.4	6.3	43	0.73	0.076
STD DS8	Standard																				
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08
STD OREAS45CA Expected																					
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000766.2

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1
1092794	Soil	4	22	0.01	491	0.001	1	0.57	0.010	0.04	<0.1	0.05	<0.1	0.2	0.05	2	1.8	<0.2	N.A.	N.A.	N.A.
REP 1092794	QC	4	22	0.01	486	0.001	2	0.57	0.011	0.05	<0.1	0.05	0.2	0.2	<0.05	2	1.9	<0.2			
1092824	Soil	1	2	0.03	246	0.008	<1	0.24	0.035	0.02	<0.1	0.03	0.3	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.
REP 1092824	QC	1	2	0.02	237	0.007	<1	0.24	0.037	0.02	<0.1	0.02	0.3	<0.1	<0.05	<1	1.0	<0.2			
1092904	Soil	19	9	0.07	6773	0.001	1	0.77	0.002	0.07	<0.1	0.54	7.8	0.2	0.06	1	2.4	<0.2	N.A.	N.A.	N.A.
REP 1092904	QC	19	8	0.07	6579	0.002	2	0.76	0.002	0.07	<0.1	0.55	7.9	0.2	0.05	<1	2.5	<0.2			
Reference Materials																					
STD DS8	Standard	13	114	0.62	259	0.103	2	0.89	0.099	0.42	2.9	0.18	2.1	5.1	0.19	4	5.4	4.7			
STD DS8	Standard	15	133	0.65	278	0.140	2	0.95	0.081	0.42	3.1	0.21	2.2	5.9	0.15	5	5.6	5.1			
STD DS8	Standard	14	115	0.61	273	0.109	2	0.90	0.086	0.43	3.0	0.21	2.1	5.4	0.14	5	4.3	5.0			
STD DS8	Standard	16	126	0.63	287	0.126	2	0.95	0.089	0.44	3.3	0.21	2.1	5.5	0.14	5	5.5	5.3			
STD DS8	Standard	15	118	0.58	279	0.122	3	0.94	0.091	0.42	2.9	0.20	2.4	5.2	0.15	5	4.4	4.5			
STD DS8	Standard	16	115	0.64	281	0.119	3	0.92	0.090	0.41	3.1	0.21	2.1	5.4	0.16	5	5.8	5.1			
STD DS8	Standard	16	123	0.63	286	0.120	2	0.94	0.093	0.42	2.9	0.19	2.2	5.3	0.15	5	6.3	5.3			
STD DS8	Standard	14	120	0.63	275	0.116	2	0.92	0.091	0.43	3.2	0.23	2.0	5.7	0.15	5	5.2	5.2			
STD DS8	Standard	14	113	0.61	289	0.111	2	0.91	0.105	0.44	3.0	0.20	2.5	5.4	0.16	5	5.3	5.5			
STD DS8	Standard	16	126	0.57	272	0.127	2	0.94	0.090	0.41	2.9	0.21	2.2	5.6	0.12	5	3.9	4.9			
STD DS8	Standard	14	121	0.56	262	0.118	4	0.90	0.083	0.38	2.9	0.19	2.1	5.4	0.13	5	4.2	5.3			
STD DS8	Standard	15	120	0.64	272	0.116	3	0.94	0.095	0.40	3.1	0.19	2.1	5.6	0.15	5	6.4	4.9			
STD DS8	Standard																		13.4	105.2	127.2
STD DS8	Standard																		14.5	109.9	131.7
STD OREAS45CA	Standard																		1.1	529.5	22.3
STD OREAS45CA	Standard																		0.8	496.7	21.1
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123
STD OREAS45CA Expected																			1	494	20
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000766.2

		1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1
1092794	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092794	QC																				
1092824	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092824	QC																				
1092904	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092904	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	302	2.0	36.0	7.3	594	2.38	24.2	90.5	7.0	66	2.4	5.5	6.7	40	0.68	0.078	15	110	0.56	287
STD DS8	Standard	314	2.2	37.8	7.7	617	2.46	24.9	130.9	7.8	77	2.4	5.0	7.1	42	0.68	0.078	17	117	0.66	311
STD OREAS45CA	Standard	62	0.3	239.8	88.1	941	16.80	4.3	40.2	7.6	17	0.1	0.1	0.2	210	0.44	0.040	17	700	0.14	164
STD OREAS45CA	Standard	59	0.3	235.8	85.1	893	16.13	3.5	44.8	7.4	17	<0.1	<0.1	0.2	197	0.41	0.038	16	637	0.16	161
STD DS8 Expected		312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279
STD OREAS45CA Expected		60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000766.2

		1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1092794	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092794	QC													
1092824	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092824	QC													
1092904	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092904	QC													
Reference Materials														
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard	0.111	<20	0.86	0.083	0.39	2.5	0.18	1.9	5.4	0.15	5	5.2	4.6
STD DS8	Standard	0.117	<20	0.92	0.088	0.40	3.1	0.23	2.2	5.7	0.14	5	4.7	4.9
STD OREAS45CA	Standard	0.144	<20	3.86	0.012	0.07	<0.1	0.03	38.2	<0.1	<0.05	19	0.8	<0.2
STD OREAS45CA	Standard	0.130	<20	3.81	0.013	0.07	<0.1	0.03	40.2	<0.1	<0.05	18	0.8	<0.2
STD DS8 Expected		0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected		0.128		3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank													
BLK	Blank													
BLK	Blank													
BLK	Blank													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000766.2

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000766.2

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank																		<0.1	<0.1	<0.1
BLK	Blank																		<0.1	<0.1	<0.1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000766.2

		1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1
BLK	Blank	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000766.2

		1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank													
BLK	Blank													
BLK	Blank													
BLK	Blank													
BLK	Blank													
BLK	Blank													
BLK	Blank													
BLK	Blank													
BLK	Blank	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 28, 2011
Report Date: September 01, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11000767.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #6
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve soil to 230 mesh			WHI
1DX2	309	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	11	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: Includes 1DX1 analysis

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092907	Soil		67.0	71.7	13.4	325	0.7	180.6	7.6	203	2.07	34.0	4.0	1.2	74	4.6	10.3	0.2	128	2.27	0.093
1092908	Soil		74.8	77.7	13.1	503	0.6	209.9	8.7	275	1.76	39.6	0.7	2.7	144	4.0	13.8	0.2	179	5.87	0.091
1092909	Soil		59.6	70.7	15.3	375	0.6	184.4	8.2	303	2.08	38.6	<0.5	3.1	170	4.2	11.3	0.2	176	6.71	0.080
1092910	Soil		44.3	62.6	13.0	256	0.4	139.6	6.2	256	2.03	27.9	<0.5	2.9	213	2.6	8.4	0.2	129	8.92	0.072
1092911	Soil		68.3	87.7	14.5	814	0.8	197.2	9.2	319	1.75	46.9	<0.5	3.1	201	7.3	21.2	0.2	231	7.04	0.105
1092912	Soil		146.2	224.9	27.0	2972	2.8	340.2	6.6	177	1.74	125.2	2.5	2.4	240	36.0	69.5	0.3	1389	7.06	0.154
1092913	Soil		29.0	21.9	6.2	286	<0.1	58.1	5.3	143	1.75	26.6	<0.5	0.5	30	1.6	6.8	0.2	388	0.45	0.102
1092914	Soil		25.9	73.9	21.2	647	1.5	132.1	11.7	222	2.40	28.5	0.9	6.3	91	6.4	15.0	0.2	142	2.69	0.118
1092915	Soil		17.2	23.2	14.3	360	0.1	43.8	5.3	202	2.40	22.3	0.9	0.5	4	0.4	7.8	0.2	98	0.04	0.094
1092916	Soil		21.3	26.2	17.8	300	0.1	56.5	5.8	68	2.09	32.4	2.5	<0.1	13	0.3	7.9	0.3	144	0.02	0.102
1092917	Soil		46.1	88.5	18.7	933	0.7	283.7	41.6	776	5.61	86.7	<0.5	4.8	80	8.6	14.4	0.1	224	1.14	0.213
1092918	Soil		19.1	15.1	10.8	114	<0.1	23.8	3.4	38	1.32	16.1	<0.5	<0.1	12	0.1	3.5	0.1	79	0.01	0.044
1092919	Soil		42.3	50.4	21.1	498	0.4	93.7	7.4	138	2.60	58.6	2.8	0.4	14	2.9	16.7	0.2	533	0.04	0.098
1092920	Soil		14.0	13.9	14.6	147	0.2	18.3	2.6	102	1.30	15.0	1.8	0.1	20	0.9	3.2	0.2	88	0.06	0.088
1092921	Soil		13.0	17.3	11.1	152	0.3	25.0	3.2	128	1.35	18.8	1.5	0.1	13	0.3	5.7	0.2	132	0.04	0.078
1092922	Soil		12.7	56.1	25.1	238	1.0	29.4	7.1	405	2.29	35.6	10.9	0.4	28	0.8	7.2	0.3	89	0.19	0.182
1092923	Soil		10.4	11.6	20.9	89	0.3	15.2	3.2	40	1.36	22.9	1.4	<0.1	18	<0.1	4.8	0.2	70	<0.01	0.055
1092924	Soil		3.5	5.3	6.8	30	0.3	4.9	1.4	62	0.75	8.9	1.1	<0.1	7	<0.1	1.3	0.1	28	0.01	0.068
1092925	Soil		32.0	14.6	47.7	50	2.1	8.4	1.5	72	2.59	125.5	29.3	0.3	74	0.3	26.4	0.3	134	0.02	0.168
1092926	Soil		4.2	35.7	23.3	429	0.2	28.6	64.6	1178	17.82	28.3	4.3	1.7	8	0.3	2.0	0.2	28	<0.01	0.046
1092927	Soil		4.1	32.7	15.4	75	0.8	18.6	13.0	348	2.02	14.9	1.8	0.2	19	0.3	3.1	0.3	40	0.03	0.081
1092928	Soil		4.5	25.7	12.2	40	1.2	12.2	2.0	58	1.74	22.7	1.2	<0.1	40	0.1	7.5	0.2	58	0.02	0.084
1092929	Soil		5.5	33.6	16.0	43	2.0	13.3	2.2	58	2.44	37.1	4.1	0.1	63	0.1	13.4	0.3	66	0.02	0.108
1092930	Soil		6.4	45.1	19.0	68	2.4	20.8	4.0	198	3.11	41.0	8.1	0.4	72	0.2	13.3	0.3	83	0.03	0.132
1092931	Soil		5.4	46.7	17.0	62	2.5	19.9	3.8	162	3.13	40.3	8.3	0.4	75	0.2	14.3	0.3	76	0.04	0.126
1092932	Soil		3.6	27.0	13.2	44	1.3	11.8	3.0	186	2.07	21.9	6.5	0.6	41	<0.1	6.9	0.2	57	0.07	0.126
1092933	Soil		9.8	44.6	43.5	56	5.0	18.6	3.3	134	3.91	57.8	17.4	1.3	120	0.2	27.5	0.4	133	0.07	0.329
1092934	Soil		7.1	48.3	21.5	60	2.7	21.0	4.3	217	3.05	45.1	8.4	0.7	101	0.2	13.4	0.4	75	0.05	0.131
1092935	Soil		7.1	45.0	22.2	47	3.1	14.9	2.6	109	2.78	45.4	6.2	0.5	108	0.2	15.2	0.4	70	0.04	0.134
1092936	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092907	Soil	14	18	1.07	342	0.003	5	0.41	0.004	0.06	0.3	0.31	3.2	2.0	<0.05	1	3.6	<0.2	N.A.	N.A.	N.A.
1092908	Soil	13	18	2.87	204	0.004	7	0.31	0.008	0.08	0.3	0.21	3.8	3.1	<0.05	<1	4.7	<0.2	N.A.	N.A.	N.A.
1092909	Soil	11	21	3.61	227	0.004	7	0.38	0.008	0.10	0.3	0.29	3.6	2.6	0.06	1	3.5	<0.2	N.A.	N.A.	N.A.
1092910	Soil	9	15	4.31	206	0.003	6	0.23	0.010	0.06	0.2	0.20	2.8	1.9	0.08	<1	3.8	<0.2	N.A.	N.A.	N.A.
1092911	Soil	13	19	3.21	409	0.003	7	0.27	0.009	0.06	0.3	0.31	3.2	2.9	0.05	<1	4.3	0.2	N.A.	N.A.	N.A.
1092912	Soil	18	73	1.50	400	0.011	10	0.60	0.008	0.17	0.6	0.85	4.0	4.6	0.05	3	11.7	0.4	N.A.	N.A.	N.A.
1092913	Soil	12	50	0.14	704	0.005	3	0.92	0.004	0.06	0.2	0.03	1.1	1.1	<0.05	4	1.6	<0.2	N.A.	N.A.	N.A.
1092914	Soil	8	21	1.17	514	0.002	5	0.22	0.003	0.07	<0.1	0.63	4.2	0.5	<0.05	<1	7.4	<0.2	N.A.	N.A.	N.A.
1092915	Soil	10	17	0.04	104	0.002	2	0.41	0.002	0.05	<0.1	0.05	0.6	0.2	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.
1092916	Soil	8	13	0.03	123	0.001	2	0.35	0.002	0.05	0.1	0.18	0.1	0.4	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.
1092917	Soil	38	58	0.38	1171	0.003	6	0.53	0.004	0.12	0.1	0.71	10.3	0.8	0.06	2	4.2	<0.2	N.A.	N.A.	N.A.
1092918	Soil	10	10	0.02	164	0.002	3	0.24	0.002	0.06	0.1	0.02	0.2	0.3	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.
1092919	Soil	17	38	0.07	433	0.003	2	0.71	0.003	0.08	0.2	0.11	0.7	1.5	<0.05	3	3.7	0.3	N.A.	N.A.	N.A.
1092920	Soil	9	13	0.05	216	0.003	3	0.53	0.004	0.07	0.1	0.04	0.2	0.5	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.
1092921	Soil	8	12	0.03	173	0.003	2	0.46	0.010	0.05	<0.1	0.19	0.2	0.4	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.
1092922	Soil	7	10	0.03	364	0.003	3	0.40	0.006	0.08	<0.1	2.22	0.8	0.5	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.
1092923	Soil	4	7	0.01	113	0.002	2	0.23	0.003	0.05	0.1	0.19	0.3	0.4	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.
1092924	Soil	2	5	0.02	55	0.002	1	0.33	0.014	0.04	<0.1	0.10	0.2	0.2	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.
1092925	Soil	5	11	0.02	448	0.003	2	0.35	0.005	0.19	0.2	7.25	0.6	2.5	0.42	2	10.2	0.3	N.A.	N.A.	N.A.
1092926	Soil	2	9	0.02	120	0.004	3	0.44	0.004	0.07	<0.1	0.17	2.8	2.9	0.28	2	1.6	<0.2	N.A.	N.A.	N.A.
1092927	Soil	4	15	0.16	132	0.007	1	0.79	0.011	0.05	<0.1	0.11	0.9	0.5	0.06	3	1.6	<0.2	N.A.	N.A.	N.A.
1092928	Soil	4	13	0.02	216	0.003	1	0.46	0.010	0.07	0.1	0.13	0.3	0.3	0.13	3	4.2	<0.2	N.A.	N.A.	N.A.
1092929	Soil	4	17	0.03	329	0.002	2	0.34	0.005	0.10	<0.1	0.19	0.5	0.4	0.24	3	6.5	<0.2	N.A.	N.A.	N.A.
1092930	Soil	7	25	0.11	363	0.007	3	0.64	0.006	0.12	0.1	0.19	1.4	0.5	0.21	4	6.7	0.3	N.A.	N.A.	N.A.
1092931	Soil	6	24	0.11	365	0.005	2	0.58	0.005	0.12	0.1	0.25	1.3	0.4	0.25	3	7.1	0.2	N.A.	N.A.	N.A.
1092932	Soil	7	18	0.12	233	0.017	2	0.71	0.014	0.08	0.1	0.10	1.2	0.4	0.11	4	4.1	<0.2	N.A.	N.A.	N.A.
1092933	Soil	10	42	0.13	684	0.018	2	0.66	0.006	0.16	0.3	0.62	3.3	1.1	0.28	6	16.6	0.3	N.A.	N.A.	N.A.
1092934	Soil	6	23	0.12	443	0.007	2	0.62	0.007	0.15	0.1	0.19	2.2	0.4	0.27	3	6.9	0.2	N.A.	N.A.	N.A.
1092935	Soil	4	22	0.07	516	0.003	2	0.54	0.007	0.16	<0.1	0.24	2.2	0.6	0.33	3	6.6	0.4	N.A.	N.A.	N.A.
1092936	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	8.3	75.2	25.1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092907	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092908	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092909	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092910	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092911	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092912	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092913	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092914	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092915	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092916	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092917	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092918	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092919	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092920	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092921	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092922	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092923	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092924	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092925	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092926	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092927	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092928	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092929	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092930	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092931	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092932	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092933	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092934	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092935	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092936	Soil		65	3.7	32.9	4.8	207	2.86	35.6	9.9	0.8	85	0.3	5.0	0.3	85	0.08	0.141	4	31	0.11	366

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092907	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092908	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092909	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092910	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092911	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092912	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092913	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092914	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092915	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092916	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092917	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092918	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092919	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092920	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092921	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092922	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092923	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092924	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092925	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092926	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092927	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092928	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092929	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092930	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092931	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092932	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092933	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092934	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092935	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092936	Soil	0.006	<20	0.75	0.016	0.14	<0.1	0.20	3.1	0.5	0.25	3	5.9	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092937	Soil		30.9	11.5	19.5	12	2.4	5.0	1.0	80	1.15	15.5	3.2	0.2	13	<0.1	7.0	0.2	106	0.03	0.041
1092938	Soil		37.9	17.2	28.1	26	2.1	7.6	1.8	121	1.81	35.1	2.7	1.5	20	<0.1	8.6	0.3	103	0.03	0.071
1092939	Soil		4.7	26.7	24.4	37	0.3	9.3	1.6	121	1.70	23.6	2.7	<0.1	21	<0.1	2.5	0.2	39	0.04	0.159
1092940	Soil		5.6	21.3	53.1	20	1.4	4.4	0.8	21	1.62	46.8	9.9	0.5	18	<0.1	10.5	0.2	31	0.02	0.194
1092941	Soil		4.1	177.7	41.7	61	1.8	14.1	3.4	186	1.94	26.2	11.7	0.4	39	0.8	7.7	0.2	38	0.06	0.403
1092942	Soil		6.6	709.9	61.5	570	1.7	75.5	8.2	1221	6.38	84.5	10.8	2.5	176	16.3	10.8	0.2	82	3.07	0.460
1092943	Soil		13.0	105.5	71.6	323	0.8	62.0	6.1	131	3.74	50.2	3.9	0.2	71	1.5	7.3	0.4	67	0.10	0.274
1092944	Soil		8.8	194.3	63.0	982	1.4	106.6	19.1	1493	8.24	75.9	13.4	3.1	27	4.0	10.4	0.4	47	0.42	0.211
1092945	Soil		12.5	26.8	58.5	37	2.2	7.0	0.9	25	1.41	15.7	1.3	<0.1	66	0.2	3.5	0.4	68	0.11	0.255
1092946	Soil		11.2	57.1	69.4	43	1.4	13.1	2.3	68	2.01	16.6	1.7	<0.1	63	0.3	3.9	0.6	101	0.11	0.365
1092947	Soil		4.2	62.5	117.1	33	2.0	12.2	1.2	30	1.35	8.3	4.1	0.5	106	0.2	2.3	0.7	53	0.18	0.390
1092948	Soil		7.7	20.0	51.2	54	0.5	13.0	2.8	106	1.39	10.6	0.5	0.1	44	0.1	2.2	0.5	66	0.02	0.076
1092949	Soil		8.2	143.5	42.8	525	3.3	165.7	23.6	225	6.58	61.2	4.9	4.9	132	2.2	6.3	0.6	38	0.32	0.318
1092950	Soil		11.6	89.1	42.4	286	2.8	86.9	15.5	314	4.82	40.5	5.4	1.1	93	1.2	5.9	0.4	30	0.25	0.286
1092951	Soil		9.0	21.1	11.6	106	0.9	33.8	5.4	103	2.37	15.4	1.2	0.2	9	0.3	3.1	0.3	98	0.02	0.096
1092952	Soil		21.2	45.8	16.7	306	0.2	129.1	16.4	178	4.13	28.5	0.9	0.3	8	0.8	6.4	0.2	233	0.02	0.166
1092953	Soil		7.0	30.6	9.0	121	0.2	110.4	20.5	349	3.68	13.0	<0.5	0.8	26	0.6	1.8	0.2	72	0.30	0.201
1092954	Soil		3.8	47.1	7.7	118	0.2	217.8	30.0	658	6.05	3.7	<0.5	1.9	30	0.9	0.7	0.1	56	0.33	0.232
1092955	Soil		6.7	44.4	8.8	159	<0.1	179.1	29.9	555	5.30	10.8	<0.5	0.7	9	1.1	1.9	0.1	63	0.06	0.232
1092956	Soil		3.3	53.9	13.5	106	<0.1	99.8	30.1	476	5.47	19.2	1.0	4.0	11	0.3	1.2	0.1	75	0.11	0.155
1092957	Soil		3.1	101.4	9.5	167	0.2	216.3	52.4	1152	6.94	41.0	1.5	10.0	92	0.5	1.3	<0.1	108	2.37	0.234
1092958	Soil		3.8	107.4	22.6	109	0.2	207.6	62.1	1708	7.33	21.1	0.8	8.2	91	0.5	1.1	<0.1	210	2.92	0.255
1092959	Soil		4.2	105.5	20.6	124	0.2	189.6	56.4	1154	6.12	17.1	2.3	10.0	137	0.5	1.2	0.1	188	2.80	0.222
1092960	Soil		2.9	67.6	11.3	112	0.1	167.1	44.6	838	4.45	9.8	0.8	1.6	56	0.6	0.9	0.1	113	1.31	0.214
1092961	Soil		8.0	47.6	12.7	193	0.1	154.0	39.6	1062	5.20	15.1	1.0	2.7	40	1.4	2.3	0.1	164	0.51	0.283
1092962	Soil		11.3	57.3	13.2	257	0.5	145.7	29.6	942	4.48	19.1	1.6	3.2	50	2.4	3.7	0.1	196	0.82	0.267
1092963	Soil		46.8	46.6	10.2	670	0.5	139.1	14.1	306	3.05	45.9	0.7	0.3	31	6.6	18.1	0.2	626	0.30	0.224
1092964	Soil		37.5	35.8	8.9	628	0.6	106.6	9.6	266	2.07	30.2	0.7	0.2	33	4.3	13.8	0.2	718	0.36	0.198
1092965	Soil		4.7	10.0	2.8	88	0.2	25.4	3.4	79	0.86	5.5	0.5	0.1	8	0.9	2.0	<0.1	62	0.08	0.103
1092966	Soil		25.3	32.8	8.1	406	0.8	85.0	5.6	151	1.64	26.7	0.6	<0.1	27	2.3	10.8	0.1	284	0.22	0.175

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092937	Soil	6	12	0.03	254	0.008	2	0.49	0.012	0.10	0.1	0.34	0.5	0.9	0.15	2	2.6	<0.2	N.A.	N.A.	N.A.
1092938	Soil	9	13	0.08	357	0.014	2	0.41	0.012	0.16	0.1	0.12	1.8	1.1	0.29	2	4.6	<0.2	N.A.	N.A.	N.A.
1092939	Soil	8	15	0.03	151	<0.001	2	0.49	0.011	0.07	<0.1	0.09	0.2	0.2	0.12	2	1.6	<0.2	N.A.	N.A.	N.A.
1092940	Soil	6	10	0.02	323	0.004	2	0.21	0.002	0.14	<0.1	0.73	1.1	0.2	0.27	2	6.4	<0.2	N.A.	N.A.	N.A.
1092941	Soil	8	16	0.06	193	0.003	2	0.53	0.012	0.09	<0.1	0.33	1.3	0.4	0.11	2	2.5	<0.2	N.A.	N.A.	N.A.
1092942	Soil	12	20	1.29	241	0.010	3	0.98	0.013	0.08	<0.1	1.28	7.3	0.3	0.12	1	4.8	0.3	N.A.	N.A.	N.A.
1092943	Soil	11	21	0.04	343	0.002	3	0.51	0.006	0.14	<0.1	0.35	0.6	0.3	0.25	2	4.6	<0.2	N.A.	N.A.	N.A.
1092944	Soil	11	13	0.12	927	0.003	4	0.40	0.003	0.06	<0.1	1.23	9.8	0.3	<0.05	1	4.6	<0.2	N.A.	N.A.	N.A.
1092945	Soil	13	17	0.02	536	0.002	2	0.44	0.007	0.10	0.2	0.12	0.2	0.8	0.22	2	5.1	0.2	N.A.	N.A.	N.A.
1092946	Soil	20	22	0.04	525	0.003	2	0.85	0.009	0.07	0.2	0.09	0.2	0.5	0.19	3	3.6	0.3	N.A.	N.A.	N.A.
1092947	Soil	26	18	0.03	852	0.003	3	0.48	0.004	0.10	0.1	0.23	0.5	0.3	0.16	2	3.3	0.2	N.A.	N.A.	N.A.
1092948	Soil	13	13	0.02	245	0.008	2	0.36	0.005	0.07	0.2	0.02	0.3	0.2	0.09	3	2.2	<0.2	N.A.	N.A.	N.A.
1092949	Soil	16	19	0.03	1398	0.003	2	0.65	0.003	0.12	<0.1	0.61	6.3	0.4	0.13	<1	5.9	<0.2	N.A.	N.A.	N.A.
1092950	Soil	12	11	0.05	2227	0.003	2	0.69	0.007	0.10	<0.1	0.53	2.5	0.3	0.17	1	3.8	<0.2	N.A.	N.A.	N.A.
1092951	Soil	10	22	0.07	232	0.005	1	0.72	0.003	0.05	0.2	0.04	0.3	0.3	0.05	4	1.9	<0.2	N.A.	N.A.	N.A.
1092952	Soil	10	47	0.06	396	0.003	2	0.69	0.003	0.05	0.1	0.03	0.7	0.4	<0.05	4	3.2	<0.2	N.A.	N.A.	N.A.
1092953	Soil	12	47	0.10	2798	0.004	2	0.83	0.004	0.05	0.1	0.04	2.4	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.
1092954	Soil	33	72	0.10	2290	0.004	3	0.67	0.011	0.04	0.1	0.04	7.6	<0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.
1092955	Soil	10	51	0.08	760	0.005	2	0.63	0.008	0.05	0.1	0.04	2.1	0.1	0.07	2	0.8	<0.2	N.A.	N.A.	N.A.
1092956	Soil	28	109	0.37	956	0.005	2	1.74	0.002	0.04	0.2	0.03	5.2	0.1	<0.05	4	0.7	<0.2	N.A.	N.A.	N.A.
1092957	Soil	69	216	1.41	1236	0.004	4	1.94	0.006	0.08	0.1	0.05	23.1	<0.1	<0.05	6	<0.5	<0.2	N.A.	N.A.	N.A.
1092958	Soil	105	405	4.25	3127	0.014	5	3.52	0.007	0.07	0.3	0.04	24.9	0.1	0.11	12	<0.5	<0.2	N.A.	N.A.	N.A.
1092959	Soil	73	319	4.19	3270	0.025	3	3.06	0.007	0.05	0.2	0.03	20.8	0.2	<0.05	11	0.6	<0.2	N.A.	N.A.	N.A.
1092960	Soil	48	200	1.33	1662	0.010	3	1.92	0.012	0.04	0.1	0.05	10.2	0.1	0.11	7	0.7	<0.2	N.A.	N.A.	N.A.
1092961	Soil	36	228	1.56	1721	0.010	2	2.22	0.007	0.05	0.2	0.03	7.3	0.2	0.08	7	1.7	<0.2	N.A.	N.A.	N.A.
1092962	Soil	54	222	1.91	2284	0.010	3	2.18	0.007	0.06	0.2	0.11	9.2	0.4	0.07	7	5.9	<0.2	N.A.	N.A.	N.A.
1092963	Soil	20	115	0.40	1545	0.003	4	1.18	0.006	0.10	0.2	0.08	0.7	1.2	0.09	5	12.9	0.3	N.A.	N.A.	N.A.
1092964	Soil	19	101	0.46	867	0.003	5	1.23	0.008	0.14	0.3	0.09	0.8	1.5	<0.05	5	4.7	<0.2	N.A.	N.A.	N.A.
1092965	Soil	5	22	0.09	268	0.002	1	0.48	0.016	0.03	<0.1	0.03	0.3	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.
1092966	Soil	11	56	0.13	632	0.002	2	0.75	0.011	0.07	0.1	0.05	0.2	0.7	<0.05	3	7.1	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092937	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092938	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092939	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092940	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092941	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092942	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092943	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092944	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092945	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092946	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092947	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092948	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092949	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092950	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092951	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092952	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092953	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092954	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092955	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092956	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092957	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092958	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092959	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092960	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092961	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092962	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092963	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092964	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092965	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092966	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092937	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092938	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092939	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092940	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092941	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092942	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092943	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092944	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092945	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092946	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092947	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092948	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092949	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092950	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092951	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092952	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092953	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092954	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092955	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092956	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092957	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092958	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092959	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092960	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092961	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092962	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092963	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092964	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092965	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092966	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092967	Soil		12.5	14.3	3.6	168	0.3	38.2	4.7	97	1.20	10.9	1.2	0.2	12	2.0	3.2	<0.1	132	0.09	0.126
1092968	Soil		12.3	38.2	22.7	173	0.3	54.7	9.6	125	2.71	74.6	<0.5	0.3	18	0.1	5.6	0.4	70	0.02	0.070
1092969	Soil		5.1	12.4	20.2	48	0.1	12.6	2.8	52	1.09	18.8	<0.5	0.1	14	0.1	1.9	0.2	52	0.01	0.042
1092970	Soil		9.0	65.1	46.2	382	0.6	94.7	8.9	79	3.46	23.3	2.4	1.1	92	0.4	5.5	0.6	44	0.08	0.258
1092971	Soil		9.6	36.3	28.0	127	0.5	43.5	6.8	143	2.28	27.6	2.3	0.2	29	0.3	3.8	0.3	31	0.15	0.192
1092972	Soil		75.4	92.6	31.6	558	2.7	150.5	10.7	122	5.24	140.4	3.1	1.1	84	1.6	19.6	0.4	201	0.02	0.222
1092973	Soil		9.7	78.2	26.9	403	0.3	134.7	11.8	103	3.99	85.0	3.2	1.6	30	0.7	8.4	0.3	37	0.12	0.140
1092974	Soil		3.3	113.4	15.4	156	0.3	34.4	8.2	124	2.60	10.5	3.2	0.4	2	0.4	2.2	0.2	22	<0.01	0.041
1092975	Soil		10.1	60.0	25.6	376	0.2	51.9	10.3	263	4.13	31.9	3.1	1.3	11	0.9	7.3	0.2	50	0.14	0.172
1092976	Soil		8.7	96.3	22.0	470	0.4	117.0	31.8	502	6.81	35.5	2.5	3.4	19	2.1	4.6	0.2	46	0.44	0.172
1092977	Soil		4.3	299.3	43.0	209	1.0	105.9	35.2	367	5.52	55.3	13.2	3.6	11	1.7	6.5	0.4	18	0.40	0.069
1092978	Soil		2.0	41.1	15.3	77	0.4	15.3	4.2	94	1.20	11.1	3.1	0.5	21	0.4	2.6	0.2	16	0.73	0.071
1092979	Soil		10.8	26.9	14.2	146	0.2	42.7	5.7	108	2.11	17.8	1.4	0.3	12	0.4	3.8	0.3	73	0.12	0.141
1092980	Soil		4.9	33.4	14.3	98	0.1	22.5	4.4	150	1.72	11.8	1.7	0.4	26	0.4	2.3	0.2	32	0.46	0.079
1092981	Soil		4.3	131.0	23.2	107	<0.1	49.7	12.6	158	3.35	17.2	7.1	0.8	8	0.3	3.5	0.3	26	0.19	0.066
1092982	Soil		13.6	149.1	38.1	595	0.4	67.7	7.9	72	3.45	40.4	4.9	0.2	12	1.4	8.0	0.3	66	<0.01	0.097
1092983	Soil		4.3	49.5	15.5	569	0.5	28.4	3.9	427	2.54	17.5	5.9	0.4	34	6.4	7.5	0.2	46	1.04	0.113
1092984	Soil		8.9	40.0	15.7	146	0.4	55.4	9.0	153	2.26	15.2	3.9	0.6	21	0.4	3.4	0.3	37	0.19	0.204
1092985	Soil		6.9	65.3	46.5	66	0.2	68.0	20.1	372	6.35	33.6	6.0	2.2	8	0.2	4.6	0.6	28	0.06	0.135
1092986	Soil		9.0	15.0	11.3	70	0.2	22.0	4.7	102	1.83	26.2	0.7	1.0	5	0.2	2.9	0.3	72	0.01	0.032
1092987	Soil		5.8	16.1	11.9	77	0.1	20.0	4.0	87	1.43	13.3	1.9	0.6	12	0.4	1.9	0.2	41	0.02	0.037
1092988	Soil		8.3	31.6	21.6	146	0.3	43.0	8.2	182	3.05	24.0	2.4	0.6	16	0.5	3.3	0.3	51	0.02	0.103
1092989	Soil		5.8	39.7	20.3	120	0.9	38.6	10.5	227	2.96	9.4	5.0	1.3	83	1.2	1.9	0.3	28	0.68	0.183
1092990	Soil		31.0	29.0	22.3	241	0.2	62.1	6.5	120	2.54	28.9	2.0	0.6	15	0.5	6.9	0.3	154	0.03	0.103
1092991	Soil		10.3	16.8	15.9	125	0.1	23.2	3.8	67	1.76	17.6	1.5	0.4	11	0.3	3.8	0.2	87	0.02	0.058
1092992	Soil		43.6	38.7	21.5	756	0.1	86.4	8.4	199	2.72	24.6	1.0	2.5	21	2.2	14.3	0.2	191	0.29	0.057
1092993	Soil		10.9	15.8	8.6	108	<0.1	24.7	3.2	51	1.13	8.7	1.3	0.2	12	0.3	2.0	0.1	55	0.14	0.032
1092994	Soil		29.1	41.6	16.3	277	0.4	97.2	10.6	287	2.63	15.8	2.6	1.4	49	1.2	3.3	0.2	76	0.38	0.128
1092995	Soil		2.1	10.9	9.3	41	<0.1	8.1	3.0	72	1.11	7.5	1.9	<0.1	6	<0.1	0.8	0.2	24	0.01	0.056
1092996	Soil		1.6	10.1	11.5	39	0.3	10.5	4.3	87	1.06	6.4	<0.5	<0.1	6	<0.1	0.6	0.1	12	0.02	0.056

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092967	Soil		6	37	0.09	293	0.002	2	0.46	0.013	0.05	<0.1	0.03	0.3	0.4	0.06	3	2.7	<0.2	N.A.	N.A.	N.A.
1092968	Soil		14	12	0.03	145	0.005	2	0.33	0.002	0.06	0.1	0.02	0.7	0.2	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.
1092969	Soil		10	8	0.03	88	0.004	1	0.40	0.005	0.04	0.1	0.01	0.3	0.2	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.
1092970	Soil		19	13	0.04	360	0.003	3	0.47	0.003	0.10	<0.1	0.05	1.4	0.2	0.06	2	18.5	<0.2	N.A.	N.A.	N.A.
1092971	Soil		13	8	0.03	460	0.002	3	0.33	0.007	0.08	<0.1	0.14	0.6	0.2	<0.05	1	2.1	<0.2	N.A.	N.A.	N.A.
1092972	Soil		16	31	0.06	305	0.005	2	0.50	0.003	0.10	0.4	0.36	2.4	1.4	0.13	2	7.6	<0.2	N.A.	N.A.	N.A.
1092973	Soil		23	13	0.02	154	0.002	2	0.24	0.001	0.05	<0.1	0.17	3.2	0.2	<0.05	<1	2.1	0.2	N.A.	N.A.	N.A.
1092974	Soil		3	4	0.02	57	0.003	2	0.35	0.006	0.04	<0.1	0.06	1.4	0.1	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.
1092975	Soil		11	21	0.05	153	0.003	2	0.58	0.005	0.05	<0.1	0.14	3.4	0.2	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.
1092976	Soil		19	27	0.10	547	0.002	4	0.60	0.002	0.08	<0.1	0.36	12.3	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.
1092977	Soil		11	10	0.07	338	0.001	4	0.51	0.003	0.08	<0.1	0.28	14.7	0.2	<0.05	1	5.7	0.3	N.A.	N.A.	N.A.
1092978	Soil		7	6	0.07	368	0.004	2	0.55	0.017	0.05	<0.1	0.09	1.5	<0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.
1092979	Soil		9	22	0.07	831	0.002	<1	0.48	0.005	0.04	0.1	0.07	0.2	0.2	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.
1092980	Soil		6	9	0.11	266	0.005	<1	0.48	0.009	0.04	0.1	0.03	1.0	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.
1092981	Soil		2	6	0.05	165	0.002	3	0.34	0.003	0.06	<0.1	0.06	2.4	0.1	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.
1092982	Soil		3	8	0.02	101	0.002	1	0.30	0.002	0.05	<0.1	0.06	0.7	0.2	<0.05	2	4.2	<0.2	N.A.	N.A.	N.A.
1092983	Soil		7	11	0.17	269	0.005	2	0.61	0.012	0.03	<0.1	0.52	1.0	0.2	0.05	2	1.8	<0.2	N.A.	N.A.	N.A.
1092984	Soil		11	13	0.03	238	0.002	3	0.39	0.005	0.06	<0.1	0.13	0.7	0.2	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.
1092985	Soil		14	14	0.06	166	0.002	2	0.46	0.002	0.07	<0.1	0.11	2.5	0.2	<0.05	1	1.5	0.2	N.A.	N.A.	N.A.
1092986	Soil		11	9	0.03	122	0.006	1	0.46	0.002	0.04	0.1	0.02	0.7	0.2	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.
1092987	Soil		9	8	0.03	244	0.004	<1	0.28	0.004	0.05	<0.1	0.02	0.6	0.2	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.
1092988	Soil		11	13	0.05	348	0.007	3	0.49	0.005	0.07	0.2	0.03	1.2	0.2	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.
1092989	Soil		8	14	0.09	7193	0.005	3	0.77	0.008	0.06	<0.1	0.34	3.1	0.2	0.11	1	1.5	<0.2	N.A.	N.A.	N.A.
1092990	Soil		6	20	0.06	257	0.003	3	0.61	0.003	0.06	0.2	0.04	1.0	0.5	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.
1092991	Soil		7	13	0.05	105	0.003	<1	0.47	0.003	0.05	<0.1	0.03	0.5	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.
1092992	Soil		6	16	0.07	309	0.002	2	0.53	0.003	0.05	0.1	0.13	2.5	0.4	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.
1092993	Soil		5	9	0.04	385	0.003	2	0.41	0.008	0.04	<0.1	0.05	0.7	0.3	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.
1092994	Soil		7	21	0.10	476	0.003	3	0.80	0.006	0.06	0.1	0.19	2.1	0.7	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.
1092995	Soil		4	8	0.02	40	0.003	<1	0.34	0.011	0.04	<0.1	0.02	0.1	<0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.
1092996	Soil		2	6	0.02	78	0.002	<1	0.36	0.015	0.03	<0.1	0.05	0.2	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092967	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092968	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092969	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092970	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092971	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092972	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092973	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092974	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092975	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092976	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092977	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092978	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092979	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092980	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092981	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092982	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092983	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092984	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092985	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092986	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092987	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092988	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092989	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092990	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092991	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092992	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092993	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092994	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092995	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092996	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092967	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092968	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092969	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092970	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092971	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092972	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092973	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092974	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092975	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092976	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092977	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092978	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092979	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092980	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092981	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092982	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092983	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092984	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092985	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092986	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092987	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092988	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092989	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092990	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092991	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092992	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092993	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092994	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092995	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092996	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1092997	Soil		7.9	29.1	21.9	124	0.3	37.0	8.2	173	3.54	17.3	2.1	0.8	17	0.3	2.9	0.2	46	0.02	0.067
1092998	Soil		7.2	21.0	19.7	77	0.2	20.7	4.5	183	3.23	15.6	<0.5	0.2	12	0.3	2.2	0.3	64	0.03	0.081
1092999	Soil		1.5	51.2	20.9	231	1.4	56.1	19.9	723	5.17	32.1	5.7	1.2	13	0.6	2.7	0.3	20	0.04	0.110
1093000	Soil		2.1	58.2	25.1	259	1.6	52.8	17.6	961	4.34	29.5	3.7	0.7	17	0.9	2.8	0.3	27	0.08	0.158
1093001	Soil		15.2	217.7	56.2	534	0.6	79.9	13.2	360	5.44	58.6	9.9	0.7	32	1.9	4.8	0.4	79	0.11	0.345
1093002	Soil		4.5	37.3	22.2	22	0.4	6.5	1.0	126	1.70	17.2	3.6	<0.1	23	<0.1	1.7	0.1	38	0.06	0.308
1093003	Soil		1.7	5.0	3.9	8	<0.1	2.6	0.8	231	0.28	2.5	0.7	0.1	2	<0.1	0.7	0.2	10	0.01	0.038
1093004	Soil		20.1	28.9	56.0	64	1.1	19.6	2.8	67	1.99	18.0	1.7	0.1	31	0.2	4.1	0.4	142	0.04	0.184
1093005	Soil		21.4	17.0	47.7	30	1.0	10.9	1.2	54	1.16	8.8	2.2	<0.1	25	0.2	2.7	0.3	68	0.05	0.244
1093006	Soil		4.4	4.7	11.0	13	0.3	5.8	0.9	21	0.46	2.8	<0.5	<0.1	8	<0.1	0.5	<0.1	34	0.02	0.099
1093007	Soil		7.8	22.4	69.6	37	0.9	12.7	1.7	26	1.66	13.4	<0.5	<0.1	57	0.1	1.4	0.4	48	0.02	0.281
1093008	Soil		12.3	28.1	71.9	78	1.1	24.0	2.5	36	1.88	19.4	<0.5	0.1	71	0.2	3.2	0.5	79	0.02	0.286
1093009	Soil		0.5	2.6	1.8	5	<0.1	2.6	0.9	160	0.31	0.5	0.8	<0.1	6	<0.1	0.1	<0.1	4	0.02	0.032
1093010	Soil		15.9	41.4	20.5	184	0.2	69.6	12.0	393	3.36	24.5	2.2	0.4	23	1.2	7.6	0.2	79	0.15	0.129
1093011	Soil		7.9	16.3	7.4	72	0.4	23.6	3.1	35	1.04	10.2	0.8	<0.1	4	<0.1	2.6	<0.1	39	0.02	0.063
1093012	Soil		13.2	38.0	17.0	228	0.3	59.9	7.3	83	2.63	24.8	0.9	0.3	6	0.3	6.9	0.2	81	<0.01	0.122
1093013	Soil		60.5	53.4	11.9	140	0.1	137.9	9.0	281	2.19	21.0	1.1	2.4	173	1.5	3.3	0.1	38	6.03	0.095
1093014	Soil		86.9	93.2	14.3	194	0.3	195.0	9.4	234	2.59	27.1	1.6	0.8	64	2.6	3.4	0.2	45	1.81	0.091
1093015	Soil		25.8	12.8	5.4	94	0.2	45.2	3.4	107	1.17	7.7	<0.5	<0.1	9	0.4	1.8	0.2	31	0.07	0.084
1093016	Soil		63.3	87.7	17.3	1110	0.9	160.8	6.5	157	2.00	46.9	<0.5	1.1	61	11.5	23.5	0.2	205	0.72	0.131
1093017	Soil		57.3	92.4	40.0	1055	1.3	162.4	12.1	317	3.83	53.7	<0.5	1.3	93	9.5	16.2	0.4	181	2.34	0.109
1093018	Soil		31.0	107.6	41.2	723	1.3	156.3	19.3	507	4.82	92.4	1.0	3.0	158	3.6	12.2	0.3	101	3.30	0.154
1093019	Soil		32.0	39.9	30.5	290	0.9	67.1	6.4	126	2.68	36.0	<0.5	2.1	60	4.4	16.3	0.2	190	0.31	0.083
1093020	Soil		85.1	23.8	22.1	196	0.2	54.6	3.8	412	3.08	30.0	<0.5	0.6	40	2.7	7.6	0.2	190	0.09	0.091
1093021	Soil		63.6	49.6	14.5	164	0.2	131.2	9.1	115	2.10	21.7	<0.5	2.2	34	1.7	5.3	0.2	47	1.18	0.067
1093022	Soil		76.6	70.8	28.0	656	0.6	208.4	15.0	327	4.08	34.2	2.9	1.8	46	5.7	8.1	0.2	82	1.84	0.126
1093023	Soil		107.2	88.1	20.1	707	0.9	210.2	7.5	230	2.04	46.1	<0.5	2.2	233	7.5	20.3	0.2	326	8.87	0.102
1093024	Soil		61.2	57.5	13.1	391	0.4	147.8	7.8	308	1.76	20.5	1.6	1.7	150	3.9	6.0	0.1	112	5.77	0.117
1093025	Soil		52.2	33.6	9.7	264	0.2	70.5	4.5	183	1.53	16.3	<0.5	0.1	17	2.1	6.5	0.2	84	0.34	0.126
1093026	Soil		61.5	72.3	14.8	619	0.6	144.2	6.3	156	1.98	28.9	1.6	0.8	105	6.5	12.2	0.2	146	3.38	0.155

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1092997	Soil	4	20	0.13	78	0.004	1	0.80	0.004	0.04	<0.1	0.04	1.4	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.
1092998	Soil	8	23	0.14	88	0.008	1	0.84	0.004	0.05	0.1	0.06	0.4	0.2	<0.05	5	0.7	<0.2	N.A.	N.A.	N.A.
1092999	Soil	10	9	0.06	1500	0.009	2	0.83	0.016	0.07	<0.1	0.14	3.8	0.2	0.09	2	2.0	0.2	N.A.	N.A.	N.A.
1093000	Soil	10	11	0.05	708	0.004	2	0.69	0.012	0.07	<0.1	0.18	2.0	0.2	0.06	2	2.3	<0.2	N.A.	N.A.	N.A.
1093001	Soil	14	26	0.09	203	0.004	2	0.64	0.003	0.08	0.1	0.27	0.9	0.5	0.08	2	6.3	<0.2	N.A.	N.A.	N.A.
1093002	Soil	7	16	0.04	140	0.002	<1	0.48	0.017	0.06	<0.1	0.10	<0.1	0.2	0.10	2	1.2	<0.2	N.A.	N.A.	N.A.
1093003	Soil	3	7	<0.01	33	0.004	2	0.37	0.008	0.05	<0.1	0.04	<0.1	<0.1	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.
1093004	Soil	13	23	0.02	192	0.003	1	0.27	0.004	0.09	0.3	0.06	0.3	0.4	0.13	3	1.5	0.2	N.A.	N.A.	N.A.
1093005	Soil	10	17	0.02	168	0.002	1	0.34	0.008	0.08	0.3	0.09	0.1	0.3	0.17	2	2.4	<0.2	N.A.	N.A.	N.A.
1093006	Soil	3	9	0.01	49	0.001	<1	0.21	0.014	0.04	<0.1	0.02	0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.
1093007	Soil	12	16	0.02	232	0.001	3	0.47	0.008	0.11	<0.1	0.07	<0.1	0.3	0.19	2	2.6	<0.2	N.A.	N.A.	N.A.
1093008	Soil	11	18	0.02	449	0.002	3	0.34	0.007	0.14	0.2	0.07	0.3	0.3	0.24	2	3.2	0.3	N.A.	N.A.	N.A.
1093009	Soil	1	3	0.01	34	0.007	<1	0.34	0.023	0.02	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1093010	Soil	5	16	0.04	385	0.003	3	0.28	0.002	0.07	0.1	0.06	1.8	0.2	<0.05	<1	2.0	0.2	N.A.	N.A.	N.A.
1093011	Soil	2	10	0.02	49	<0.001	2	0.24	0.011	0.04	<0.1	0.04	0.1	0.1	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.
1093012	Soil	3	16	0.03	89	0.002	1	0.34	0.002	0.05	<0.1	0.04	0.5	0.2	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.
1093013	Soil	6	14	2.91	356	0.003	4	0.16	0.009	0.05	0.1	0.40	3.7	1.0	<0.05	<1	2.0	<0.2	N.A.	N.A.	N.A.
1093014	Soil	8	16	0.62	140	0.003	2	0.26	0.006	0.04	0.2	0.40	3.3	1.6	<0.05	<1	3.3	<0.2	N.A.	N.A.	N.A.
1093015	Soil	4	11	0.03	103	0.004	5	0.29	0.007	0.04	0.1	0.01	0.4	0.3	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.
1093016	Soil	11	19	0.08	308	0.004	5	0.30	0.003	0.04	0.2	0.89	2.8	1.1	0.06	<1	5.2	<0.2	N.A.	N.A.	N.A.
1093017	Soil	5	18	1.06	404	0.001	3	0.21	0.006	0.05	<0.1	1.09	3.6	0.9	0.22	<1	5.8	<0.2	N.A.	N.A.	N.A.
1093018	Soil	4	20	1.32	605	0.001	4	0.22	0.004	0.06	<0.1	0.62	5.1	0.5	0.23	<1	6.1	<0.2	N.A.	N.A.	N.A.
1093019	Soil	2	19	0.10	443	0.002	3	0.21	0.004	0.16	<0.1	0.33	3.2	0.8	0.47	<1	4.9	<0.2	N.A.	N.A.	N.A.
1093020	Soil	3	17	0.03	848	0.004	9	0.29	0.005	0.19	0.2	0.30	1.9	2.4	0.57	1	4.0	<0.2	N.A.	N.A.	N.A.
1093021	Soil	2	14	0.60	111	<0.001	3	0.18	0.002	0.05	0.1	0.20	4.3	1.4	0.07	<1	3.0	<0.2	N.A.	N.A.	N.A.
1093022	Soil	4	23	0.88	252	0.001	7	0.23	0.003	0.04	0.1	0.33	4.6	1.5	0.07	<1	3.6	<0.2	N.A.	N.A.	N.A.
1093023	Soil	5	19	2.18	154	0.002	6	0.20	0.006	0.05	0.2	0.41	3.6	0.9	0.07	<1	5.1	0.3	N.A.	N.A.	N.A.
1093024	Soil	5	14	1.78	174	0.003	4	0.23	0.005	0.05	0.2	0.28	3.3	0.6	<0.05	<1	3.3	<0.2	N.A.	N.A.	N.A.
1093025	Soil	3	15	0.08	139	0.003	2	0.25	0.006	0.06	0.1	0.04	0.9	0.4	0.08	1	1.6	<0.2	N.A.	N.A.	N.A.
1093026	Soil	5	17	1.50	169	0.003	5	0.26	0.006	0.04	0.2	0.41	2.9	0.5	0.10	<1	4.5	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
	Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
	MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1092997	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092998	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092999	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093000	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093017	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093019	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093021	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093022	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093023	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093025	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093026	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092997	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092998	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092999	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093000	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093017	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093019	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093021	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093022	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093023	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093025	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093026	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093027	Soil		120.8	68.3	24.0	850	0.3	233.2	13.7	296	3.15	38.3	<0.5	4.8	72	6.5	23.8	0.2	219	2.89	0.071
1093028	Soil		54.9	59.7	23.3	231	0.2	153.7	8.4	183	2.44	23.8	<0.5	1.2	36	2.0	4.9	0.2	63	0.80	0.105
1093029	Soil		79.6	77.4	16.8	753	0.8	194.6	9.7	281	2.39	39.0	1.5	1.1	99	7.2	16.4	0.2	184	2.89	0.128
1093030	Soil		125.8	153.2	33.6	1469	1.7	346.2	15.4	320	2.58	55.8	0.6	0.8	118	23.2	25.2	0.3	583	1.27	0.146
1093031	Soil		80.4	71.3	14.9	1356	2.0	221.7	9.1	233	1.73	50.1	0.9	3.2	174	14.0	24.6	0.2	377	9.59	0.072
1093032	Soil		89.7	76.5	29.6	771	1.3	326.1	23.1	397	3.53	34.6	1.1	3.9	129	6.2	14.4	0.2	317	2.35	0.127
1093033	Soil		50.6	85.8	119.5	234	5.4	101.3	8.9	204	3.78	39.3	2.5	3.8	130	1.7	47.8	0.4	325	0.74	0.264
1093034	Soil		7.9	153.8	69.5	525	2.2	121.4	67.0	1643	6.53	29.3	6.6	3.2	51	1.6	6.6	0.7	53	0.28	0.133
1093035	Soil		7.3	161.7	74.9	558	2.2	123.5	68.2	1563	6.48	32.6	10.2	3.3	70	1.6	7.1	0.8	46	0.34	0.146
1093036	Soil		6.5	18.8	17.2	52	<0.1	12.6	3.0	93	1.67	11.3	<0.5	0.2	12	<0.1	2.6	0.3	55	0.01	0.038
1093037	Soil		3.9	24.4	16.9	41	0.2	10.7	2.8	91	2.09	13.0	<0.5	0.2	16	<0.1	1.8	0.3	34	0.04	0.080
1093038	Soil		6.7	44.7	21.4	90	0.3	22.4	6.6	170	3.63	30.6	4.3	0.7	22	0.2	3.5	0.3	42	0.05	0.090
1093039	Soil		4.6	19.6	16.4	46	0.3	11.4	3.0	91	1.77	11.9	2.3	<0.1	16	0.1	2.0	0.2	36	0.03	0.056
1093040	Soil		8.4	15.1	6.3	75	<0.1	17.0	3.0	50	1.22	7.2	0.7	<0.1	5	<0.1	1.9	0.1	46	0.01	0.036
1093041	Soil		3.1	12.6	5.9	47	0.2	9.8	3.1	94	1.09	5.5	<0.5	<0.1	5	<0.1	1.0	0.1	26	0.02	0.038
1093042	Soil		0.5	4.6	3.4	9	0.3	4.0	1.0	40	0.44	1.0	<0.5	<0.1	8	0.1	0.2	<0.1	9	0.08	0.055
1093043	Soil		7.0	111.1	5.1	178	<0.1	734.0	83.8	695	8.38	6.8	1.0	6.4	24	0.5	1.9	<0.1	72	0.34	0.338
1093044	Soil		4.4	86.3	11.1	90	0.3	250.4	80.2	1069	7.61	6.1	<0.5	2.3	49	0.6	1.6	<0.1	73	0.87	0.257
1093045	Soil		5.4	10.4	7.4	171	0.1	24.6	2.7	88	0.74	4.1	<0.5	<0.1	15	1.1	1.4	0.1	49	0.21	0.092
1093046	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093047	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093048	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093049	Soil		5.5	4.5	3.7	94	<0.1	13.1	1.2	36	0.48	2.6	<0.5	<0.1	8	0.6	2.2	<0.1	25	0.05	0.066
1093050	Soil		37.4	36.8	13.4	427	0.1	90.7	7.1	130	2.38	18.1	<0.5	0.2	11	1.5	7.2	0.2	95	0.05	0.125
1093051	Soil		49.6	28.2	11.2	294	<0.1	67.8	7.1	167	2.17	20.7	2.2	<0.1	6	0.4	5.5	0.2	145	0.02	0.098
1093052	Soil		29.4	33.3	16.3	383	<0.1	58.7	8.3	139	3.17	26.4	1.4	0.2	7	0.7	8.7	0.2	191	0.02	0.060
1093053	Soil		24.5	28.0	12.1	229	0.2	49.3	7.0	257	2.03	17.3	1.9	0.1	7	0.7	3.8	0.1	133	0.03	0.084
1093054	Soil		4.3	47.2	18.7	112	0.2	27.1	13.1	706	2.16	13.1	1.9	0.2	12	<0.1	1.9	0.4	38	0.01	0.059
1093055	Soil		3.8	58.9	16.3	125	0.3	31.7	13.9	446	2.41	12.0	2.8	0.2	10	0.2	2.0	0.3	35	0.03	0.074
1093056	Soil		3.5	104.0	20.1	187	1.3	54.1	21.3	675	3.58	15.7	4.5	0.5	14	0.9	2.9	0.4	42	0.07	0.103

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1093027	Soil		6	14	1.42	176	0.002	5	0.17	0.005	0.05	0.2	0.75	5.0	1.7	0.05	<1	3.1	<0.2	N.A.	N.A.	N.A.
1093028	Soil		8	17	0.11	145	0.003	3	0.35	0.004	0.04	0.2	0.21	3.3	1.0	0.08	<1	3.2	<0.2	N.A.	N.A.	N.A.
1093029	Soil		14	20	1.16	205	0.003	4	0.33	0.006	0.06	0.3	0.35	2.8	1.5	0.09	<1	4.5	<0.2	N.A.	N.A.	N.A.
1093030	Soil		19	32	0.11	346	0.004	4	0.48	0.004	0.08	0.3	0.81	4.1	1.9	0.07	1	7.4	0.2	N.A.	N.A.	N.A.
1093031	Soil		7	23	5.21	152	0.002	5	0.19	0.009	0.07	0.2	1.04	3.5	3.3	0.07	<1	9.1	<0.2	N.A.	N.A.	N.A.
1093032	Soil		12	25	0.18	356	0.001	6	0.27	0.002	0.09	0.2	0.31	5.6	1.9	0.16	<1	6.0	<0.2	N.A.	N.A.	N.A.
1093033	Soil		8	22	0.10	292	0.002	5	0.45	0.004	0.16	<0.1	0.68	4.9	1.1	0.26	2	41.8	0.5	N.A.	N.A.	N.A.
1093034	Soil		5	21	0.28	133	0.003	2	1.00	0.004	0.07	<0.1	0.18	9.1	0.6	0.05	3	4.7	0.2	N.A.	N.A.	N.A.
1093035	Soil		5	19	0.23	121	0.002	2	0.87	0.004	0.07	<0.1	0.19	7.6	0.5	0.06	3	4.1	<0.2	N.A.	N.A.	N.A.
1093036	Soil		9	11	0.01	74	0.013	2	0.33	0.006	0.04	0.1	0.04	0.5	0.1	<0.05	3	2.8	<0.2	N.A.	N.A.	N.A.
1093037	Soil		5	13	0.08	56	0.008	<1	0.52	0.008	0.04	<0.1	0.03	1.0	0.1	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.
1093038	Soil		6	17	0.15	80	0.010	1	0.65	0.003	0.04	<0.1	0.04	2.6	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.
1093039	Soil		5	12	0.07	67	0.007	<1	0.58	0.007	0.03	<0.1	0.03	0.4	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.
1093040	Soil		5	9	0.01	36	0.003	<1	0.26	0.009	0.03	<0.1	<0.01	0.1	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1093041	Soil		4	7	0.02	32	0.005	1	0.38	0.013	0.03	<0.1	0.02	0.2	<0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.
1093042	Soil		3	4	0.02	21	0.012	<1	0.46	0.020	0.02	<0.1	0.03	0.3	<0.1	<0.05	2	0.5	<0.2	N.A.	N.A.	N.A.
1093043	Soil		61	192	0.51	161	0.002	2	1.52	0.003	0.06	<0.1	0.03	19.1	0.2	<0.05	4	0.7	<0.2	N.A.	N.A.	N.A.
1093044	Soil		20	91	0.52	475	0.003	6	1.17	0.009	0.06	0.1	0.07	12.0	0.2	0.30	3	2.7	<0.2	N.A.	N.A.	N.A.
1093045	Soil		4	12	0.07	118	0.003	1	0.58	0.013	0.05	<0.1	0.04	0.3	0.6	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.
1093046	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.2	17.7	8.2
1093047	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	7.0	23.2	12.3
1093048	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	13.2	28.3	12.6
1093049	Soil		<1	6	0.01	58	0.004	<1	0.14	0.015	0.03	<0.1	0.02	0.4	<0.1	<0.05	<1	1.0	<0.2	N.A.	N.A.	N.A.
1093050	Soil		6	18	0.03	129	0.003	2	0.36	0.004	0.05	0.1	0.03	0.4	0.6	<0.05	2	4.1	<0.2	N.A.	N.A.	N.A.
1093051	Soil		3	14	0.02	99	0.002	<1	0.31	0.003	0.04	0.1	0.02	0.4	0.4	<0.05	1	2.9	<0.2	N.A.	N.A.	N.A.
1093052	Soil		5	16	0.02	75	0.006	<1	0.24	0.003	0.04	0.2	0.02	1.0	0.2	<0.05	2	3.4	<0.2	N.A.	N.A.	N.A.
1093053	Soil		2	12	0.02	88	0.002	<1	0.37	0.010	0.03	<0.1	0.07	0.6	0.2	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.
1093054	Soil		4	12	0.03	82	0.003	<1	0.52	0.008	0.06	<0.1	0.03	1.0	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.
1093055	Soil		3	12	0.03	80	0.003	<1	0.51	0.008	0.05	<0.1	0.03	1.0	0.2	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.
1093056	Soil		5	19	0.09	98	0.004	<1	0.69	0.004	0.05	<0.1	0.12	3.1	0.3	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1093027	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093028	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093029	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093030	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093031	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093032	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093033	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093034	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093035	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093036	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093037	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093038	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093039	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093040	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093041	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093042	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093043	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093044	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093045	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093046	Soil		58	0.2	24.0	5.1	117	1.14	4.5	2.3	<0.1	7	0.2	1.0	0.1	31	0.07	0.069	3	17	0.05	67
1093047	Soil		82	0.2	25.1	5.8	350	1.45	7.5	1.2	<0.1	9	0.2	1.4	0.1	34	0.05	0.087	3	17	0.03	83
1093048	Soil		159	0.2	33.0	5.4	197	1.75	11.3	2.7	<0.1	9	0.3	2.0	0.2	64	0.03	0.097	3	17	0.03	83
1093049	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093050	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093051	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093052	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093053	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093054	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093055	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093056	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093027	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093028	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093029	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093030	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093031	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093032	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093033	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093034	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093035	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093036	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093037	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093038	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093039	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093040	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093041	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093042	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093043	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093044	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093045	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093046	Soil		0.001	<20	0.40	0.019	0.04	<0.1	0.03	<0.1	0.1	<0.05	1	0.7	<0.2
1093047	Soil		0.001	<20	0.47	0.013	0.05	<0.1	0.04	<0.1	0.1	0.07	2	1.0	<0.2
1093048	Soil		<0.001	<20	0.37	0.009	0.05	<0.1	0.04	<0.1	0.2	0.06	2	1.1	<0.2
1093049	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093050	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093051	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093052	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093053	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093054	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093055	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093056	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093057	Soil		5.7	87.3	21.2	265	0.5	53.1	14.8	377	3.56	19.9	3.4	0.2	11	0.5	3.2	0.4	63	0.04	0.166
1093058	Soil		5.1	130.8	35.7	318	1.9	112.7	51.5	1551	5.91	16.6	4.9	2.0	29	1.2	4.3	0.5	65	0.21	0.131
1093059	Soil		5.2	141.0	42.7	181	2.0	80.6	40.3	802	3.54	27.0	5.7	2.1	37	0.5	4.1	0.6	35	0.28	0.096
1093060	Soil		7.0	138.6	39.7	136	1.2	73.0	25.0	588	3.29	45.2	3.3	1.1	42	0.4	5.6	0.6	37	0.21	0.087
1093061	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093062	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093063	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093064	Soil		21.3	83.3	32.1	421	2.1	234.9	21.2	199	4.03	25.6	1.7	1.6	87	4.1	8.6	0.2	204	0.66	0.237
1093065	Soil		55.3	92.7	12.8	968	1.3	219.4	12.5	239	2.58	36.9	0.8	1.0	77	10.6	17.3	0.1	379	1.94	0.155
1093066	Soil		65.5	115.7	17.0	1365	1.5	261.2	12.6	240	3.54	45.3	1.6	1.2	84	14.5	19.7	0.2	468	1.39	0.206
1093067	Soil		6.1	20.1	5.3	81	<0.1	19.8	2.2	80	1.02	8.0	0.6	0.2	6	0.2	1.2	0.1	24	0.06	0.070
1093068	Soil		8.9	55.2	19.5	178	0.4	51.4	5.3	158	2.91	19.8	0.6	0.4	13	0.3	2.5	0.3	45	0.04	0.160
1093069	Soil		1.3	5.8	4.2	36	0.1	8.4	1.3	41	0.58	6.2	<0.5	<0.1	27	<0.1	0.4	<0.1	19	0.24	0.076
1093070	Soil		0.4	9.5	2.6	13	0.5	13.2	0.7	28	0.39	5.3	1.5	0.1	14	0.2	0.4	<0.1	7	0.20	0.065
1093071	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093072	Soil		3.6	24.6	12.4	78	0.2	23.2	5.9	207	1.39	20.7	<0.5	<0.1	10	<0.1	1.4	0.2	28	0.03	0.084
1093073	Soil		3.9	38.2	18.0	104	0.2	29.1	8.2	192	1.88	31.5	<0.5	0.1	15	0.2	2.4	0.3	32	0.03	0.086
1093074	Soil		1.4	10.1	4.9	25	<0.1	8.4	2.3	92	0.58	8.4	<0.5	<0.1	8	<0.1	0.4	<0.1	11	0.03	0.040
1093075	Soil		3.0	34.3	12.9	64	0.2	23.0	6.9	101	1.54	42.7	<0.5	<0.1	8	<0.1	1.6	0.2	29	0.01	0.076
1093076	Soil		9.1	53.2	17.6	261	0.3	72.2	9.4	199	2.54	24.1	<0.5	0.2	14	0.8	5.2	0.2	75	0.08	0.162
1093077	Soil		6.6	14.6	11.8	200	0.2	34.7	4.5	154	1.93	17.3	<0.5	<0.1	11	1.0	6.1	<0.1	99	0.15	0.098
1093078	Soil		60.4	29.1	17.7	649	0.1	89.8	7.6	125	2.62	32.5	<0.5	0.2	10	1.6	13.0	0.2	224	0.07	0.074
1093079	Soil		29.2	16.3	6.6	159	0.2	42.3	3.2	53	0.98	10.7	<0.5	<0.1	4	0.4	3.7	<0.1	75	0.03	0.076
1093080	Soil		18.8	15.8	6.8	132	0.2	40.5	3.4	546	0.68	15.2	<0.5	0.1	10	1.3	3.1	<0.1	60	0.14	0.072
1093201	Soil		9.2	20.8	12.1	203	0.3	31.3	3.1	101	1.34	24.4	1.9	0.2	16	1.6	4.6	0.2	230	0.09	0.117
1093202	Soil		42.5	22.3	29.2	132	1.1	20.1	2.9	264	2.74	59.4	28.0	1.0	46	2.3	16.0	0.3	191	0.15	0.088
1093203	Soil		32.3	34.8	31.1	195	1.1	49.1	5.9	272	2.76	46.8	21.7	0.4	41	1.4	12.1	0.3	218	0.17	0.122
1093204	Soil		38.0	52.3	21.4	459	0.7	100.0	6.9	118	2.96	52.0	3.9	0.3	17	2.3	11.0	0.2	554	0.06	0.131
1093205	Soil		37.2	64.5	13.9	1139	0.7	188.4	18.9	819	2.76	43.0	0.7	1.9	106	14.0	10.3	0.1	329	2.74	0.176
1093206	Soil		14.4	44.4	24.5	246	0.8	55.1	8.0	167	3.18	28.4	2.0	0.4	27	0.7	5.2	0.3	97	0.09	0.141

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1093057	Soil	4	24	0.05	90	0.004	2	0.80	0.003	0.06	<0.1	0.10	2.1	0.3	0.05	3	2.7	<0.2	N.A.	N.A.	N.A.
1093058	Soil	5	23	0.12	306	0.005	<1	0.69	0.006	0.06	<0.1	0.21	10.5	0.5	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.
1093059	Soil	5	16	0.07	364	0.002	<1	0.45	0.005	0.08	<0.1	0.17	5.3	0.3	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.
1093060	Soil	5	16	0.04	236	0.003	<1	0.37	0.006	0.10	<0.1	0.18	4.1	0.2	0.08	1	1.1	0.2	N.A.	N.A.	N.A.
1093061	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.2	121.0	33.2
1093062	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	8.6	92.7	39.8
1093063	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	18.6	56.3	35.2
1093064	Soil	10	84	0.07	378	0.003	3	0.78	0.011	0.06	<0.1	0.43	8.3	0.6	<0.05	2	5.8	<0.2	N.A.	N.A.	N.A.
1093065	Soil	7	49	0.72	252	0.006	4	0.53	0.019	0.06	0.1	0.43	4.1	0.8	<0.05	1	7.0	<0.2	N.A.	N.A.	N.A.
1093066	Soil	11	61	0.32	344	0.004	3	0.71	0.007	0.06	0.2	0.62	5.5	0.9	<0.05	2	8.0	<0.2	N.A.	N.A.	N.A.
1093067	Soil	3	6	0.02	82	0.004	<1	0.42	0.015	0.03	<0.1	0.03	0.4	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1093068	Soil	7	12	0.03	174	0.004	2	0.41	0.006	0.05	<0.1	0.06	0.5	0.2	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.
1093069	Soil	3	6	0.10	153	0.006	<1	0.60	0.026	0.03	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1093070	Soil	3	3	0.05	69	0.014	1	0.88	0.034	0.02	<0.1	0.07	0.8	<0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.
1093071	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.5	44.5	13.5
1093072	Soil	3	13	0.02	78	0.004	1	0.32	0.009	0.05	<0.1	0.04	0.5	<0.1	<0.05	2	<0.5	0.2	N.A.	N.A.	N.A.
1093073	Soil	5	14	0.02	71	0.004	<1	0.30	0.004	0.06	0.1	0.01	0.6	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.
1093074	Soil	2	7	0.02	35	0.003	<1	0.19	0.021	0.03	<0.1	0.02	0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.
1093075	Soil	2	12	0.02	50	0.005	5	0.32	0.011	0.06	<0.1	0.03	0.9	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.
1093076	Soil	3	20	0.03	173	0.004	1	0.37	0.003	0.06	0.2	0.05	1.2	0.2	<0.05	1	2.7	<0.2	N.A.	N.A.	N.A.
1093077	Soil	2	12	0.03	105	0.004	1	0.32	0.016	0.03	<0.1	0.04	0.7	0.2	<0.05	1	1.2	<0.2	N.A.	N.A.	N.A.
1093078	Soil	4	19	0.03	198	0.004	4	0.31	0.003	0.05	0.1	0.05	1.1	0.5	<0.05	1	1.4	<0.2	N.A.	N.A.	N.A.
1093079	Soil	3	11	0.02	64	0.001	1	0.23	0.009	0.04	<0.1	0.03	0.1	0.5	<0.05	<1	0.7	<0.2	N.A.	N.A.	N.A.
1093080	Soil	2	16	0.05	114	0.005	2	0.17	0.023	0.05	<0.1	0.06	0.7	0.4	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.
1093201	Soil	10	19	0.07	405	0.005	3	0.52	0.008	0.09	0.1	0.23	0.5	0.6	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.
1093202	Soil	8	15	0.04	1128	0.003	3	0.33	0.004	0.14	0.2	3.34	0.9	0.9	0.20	1	4.9	<0.2	N.A.	N.A.	N.A.
1093203	Soil	9	27	0.08	1190	0.005	7	0.60	0.007	0.11	0.2	3.58	1.1	0.8	0.10	2	4.2	<0.2	N.A.	N.A.	N.A.
1093204	Soil	18	42	0.10	633	0.009	6	0.70	0.005	0.10	0.3	0.28	1.0	1.0	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.
1093205	Soil	17	35	1.17	1022	0.007	4	0.50	0.006	0.10	0.2	0.77	3.5	0.9	0.15	1	5.2	<0.2	N.A.	N.A.	N.A.
1093206	Soil	14	19	0.08	474	0.006	1	0.56	0.004	0.09	0.1	0.21	0.7	0.4	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
	Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
	MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1093057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093058	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093061	Soil	225	1.2	75.4	26.2	780	3.78	36.9	5.1	1.4	42	0.8	2.0	0.4	41	0.30	0.123	5	25	0.07	359
1093062	Soil	257	1.5	74.0	25.1	1028	3.27	34.1	4.6	0.8	51	1.5	2.6	0.4	56	0.26	0.118	5	32	0.07	506
1093063	Soil	329	0.8	134.2	22.8	726	3.76	21.1	1.7	0.3	63	3.5	4.0	0.2	133	0.36	0.169	7	62	0.09	397
1093064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093071	Soil	121	0.4	64.0	11.8	220	1.90	18.8	3.6	<0.1	14	0.3	1.5	0.3	37	0.06	0.101	6	24	0.05	100
1093072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093075	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093058	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093061	Soil	0.002	<20	0.40	0.005	0.09	<0.1	0.13	4.8	0.3	0.06	1	2.2	<0.2
1093062	Soil	0.001	<20	0.41	0.007	0.09	<0.1	0.19	3.6	0.4	0.07	1	2.7	<0.2
1093063	Soil	0.002	<20	0.55	0.012	0.09	<0.1	0.13	2.9	0.6	0.11	2	5.0	<0.2
1093064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093071	Soil	0.001	<20	0.35	0.005	0.08	<0.1	0.10	0.8	0.2	0.06	2	1.1	<0.2
1093072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093075	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093207	Soil		8.1	21.5	19.4	107	0.6	19.9	3.4	93	2.15	18.0	2.8	0.3	22	0.3	2.6	0.3	88	0.04	0.154
1093208	Soil		9.5	23.7	22.9	120	0.8	25.1	3.7	68	1.83	16.1	0.9	0.2	25	0.3	2.8	0.2	81	0.03	0.151
1093209	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093210	Soil		7.0	17.4	15.4	90	0.3	17.4	3.0	53	1.17	14.4	2.4	0.2	16	<0.1	2.8	0.2	48	0.01	0.070
1093251	Soil		12.0	21.8	21.7	59	1.3	13.1	1.4	24	1.69	38.4	8.4	0.3	39	<0.1	5.4	0.4	96	0.02	0.086
1093252	Soil		6.0	23.2	13.3	70	0.8	17.8	2.1	28	1.57	31.1	2.9	0.4	22	0.1	3.5	0.2	66	<0.01	0.043
1093253	Soil		23.0	54.3	27.6	160	3.3	29.6	2.9	82	5.34	91.1	17.7	1.2	95	0.3	15.2	0.4	180	0.12	0.384
1093254	Soil		10.7	15.6	19.9	50	1.8	11.0	1.0	14	1.48	30.4	2.1	0.5	50	<0.1	6.1	0.3	113	0.01	0.085
1093255	Soil		3.6	10.8	5.8	21	1.6	5.5	0.9	15	0.84	9.8	2.2	<0.1	11	<0.1	1.5	0.1	37	0.01	0.047
1093256	Soil		16.3	34.2	12.1	30	2.7	11.5	1.4	28	1.51	58.0	25.8	0.2	37	<0.1	11.4	0.2	70	0.02	0.111
1093257	Soil		24.6	27.5	7.9	265	0.4	69.0	4.3	38	1.15	17.1	2.9	0.6	26	2.5	5.4	<0.1	120	0.26	0.063
1093258	Soil		25.7	45.7	9.7	287	0.5	99.6	7.1	211	1.58	16.9	4.0	0.7	53	5.6	5.9	0.2	119	0.92	0.113
1093259	Soil		1.6	22.3	20.5	57	<0.1	23.3	13.5	188	2.51	13.0	1.2	1.2	8	0.2	1.0	0.4	9	0.02	0.049
1093260	Soil		18.3	49.5	24.3	283	0.5	83.9	10.5	171	3.22	32.1	5.5	1.2	43	0.7	5.2	0.3	119	0.18	0.218
1093261	Soil		2.6	9.7	9.6	43	0.2	10.1	1.9	29	0.73	6.5	<0.5	<0.1	10	0.1	0.8	0.1	32	0.02	0.074
1093262	Soil		5.1	34.1	10.6	177	0.2	36.9	4.5	134	2.03	13.0	3.2	0.3	9	0.6	1.4	0.1	39	0.08	0.155
1093263	Soil		6.1	32.2	17.4	518	0.3	23.4	4.2	350	2.66	14.5	2.8	0.4	8	1.4	1.9	0.2	52	0.06	0.107
1093264	Soil		7.2	94.8	27.2	174	0.2	47.7	10.6	193	3.38	22.7	1.8	0.6	11	0.3	2.7	0.3	52	0.03	0.088
1093265	Soil		29.9	59.7	39.0	229	0.9	109.4	12.8	79	2.58	33.1	1.4	0.1	30	0.5	6.4	0.3	156	<0.01	0.118
1093266	Soil		10.6	52.7	39.4	76	0.7	84.0	19.7	4182	10.86	49.2	7.5	3.0	22	0.7	9.7	0.2	102	2.30	0.269
1093267	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093268	Soil		2.2	10.8	5.8	34	0.4	14.0	1.0	32	0.34	3.4	1.1	<0.1	62	0.5	0.6	0.1	12	0.17	0.070
1093269	Soil		9.5	67.4	24.2	206	0.7	137.4	15.5	145	3.29	50.6	6.0	1.3	76	0.4	5.2	0.3	94	0.11	0.179
1093270	Soil		17.2	22.9	18.5	101	1.0	40.1	4.5	39	1.27	21.1	1.0	0.2	29	0.2	3.6	0.2	92	0.01	0.051
1093271	Soil		16.8	27.4	25.9	118	0.5	45.3	4.8	38	1.33	21.3	1.7	0.1	35	0.7	3.4	0.3	94	0.02	0.070
1093272	Soil		3.1	39.0	9.6	108	0.5	49.5	15.5	273	4.46	25.0	<0.5	2.6	3	<0.1	1.9	0.2	26	<0.01	0.051
1093273	Soil		6.6	48.2	18.9	151	0.3	44.1	12.1	237	2.78	16.1	3.0	1.6	14	0.3	3.1	0.3	43	0.05	0.076
1093274	Soil		5.1	24.0	16.1	87	0.3	20.3	5.2	125	1.76	12.3	2.2	0.3	12	0.2	2.1	0.3	49	0.02	0.061
1093275	Soil		6.5	28.4	13.7	107	0.1	27.7	6.5	122	1.97	16.2	1.0	0.4	11	0.2	2.5	0.3	49	0.02	0.051
1093276	Soil		6.8	23.3	8.4	89	1.1	29.6	4.0	126	1.01	7.0	3.1	0.3	22	0.7	2.1	0.2	35	0.18	0.059

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1093207	Soil	10	19	0.11	212	0.005	2	0.92	0.004	0.07	0.1	0.14	0.4	0.4	0.07	4	2.0	<0.2	N.A.	N.A.	N.A.
1093208	Soil	8	16	0.06	274	0.003	2	0.83	0.006	0.07	0.1	0.14	0.3	0.5	0.07	3	2.0	<0.2	N.A.	N.A.	N.A.
1093209	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.6	40.5	26.4
1093210	Soil	5	9	0.02	141	0.003	1	0.34	0.011	0.04	0.1	0.03	0.2	0.3	0.06	2	1.3	<0.2	N.A.	N.A.	N.A.
1093251	Soil	4	14	0.02	360	0.002	3	0.35	0.003	0.07	0.2	0.17	0.6	0.6	0.12	2	3.2	0.3	N.A.	N.A.	N.A.
1093252	Soil	4	12	0.01	235	0.002	3	0.39	0.003	0.05	<0.1	0.24	1.0	0.2	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.
1093253	Soil	5	31	0.03	1678	0.004	3	0.62	0.005	0.13	0.3	1.25	2.0	1.6	0.29	3	8.6	0.2	N.A.	N.A.	N.A.
1093254	Soil	4	17	0.02	892	0.002	3	0.38	0.002	0.09	0.2	0.25	0.9	0.7	0.16	3	2.4	<0.2	N.A.	N.A.	N.A.
1093255	Soil	4	8	0.02	201	0.003	<1	0.51	0.013	0.03	<0.1	0.22	0.2	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.
1093256	Soil	3	16	0.03	513	0.004	1	0.71	0.012	0.06	0.1	1.11	0.5	1.3	0.14	3	6.4	<0.2	N.A.	N.A.	N.A.
1093257	Soil	7	15	0.04	180	0.004	2	0.36	0.013	0.04	0.1	0.29	1.5	0.4	0.05	1	2.2	<0.2	N.A.	N.A.	N.A.
1093258	Soil	9	20	0.09	574	0.004	3	0.79	0.007	0.05	0.2	0.42	2.2	0.6	0.11	2	4.0	<0.2	N.A.	N.A.	N.A.
1093259	Soil	9	5	0.03	112	<0.001	2	0.33	0.002	0.05	<0.1	0.04	2.0	<0.1	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.
1093260	Soil	15	27	0.19	292	0.008	3	1.11	0.003	0.09	0.2	0.06	2.1	0.4	<0.05	4	2.4	<0.2	N.A.	N.A.	N.A.
1093261	Soil	8	10	0.03	111	0.002	2	0.39	0.005	0.04	0.1	0.01	0.1	0.2	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.
1093262	Soil	5	10	0.03	215	0.004	1	0.37	0.012	0.05	<0.1	0.06	1.1	0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.
1093263	Soil	5	14	0.05	156	0.008	3	0.61	0.010	0.05	0.1	0.05	1.1	<0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.
1093264	Soil	7	12	0.05	107	0.006	2	0.52	0.002	0.07	0.1	0.04	1.6	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.
1093265	Soil	12	16	0.02	109	0.002	1	0.40	0.002	0.05	0.1	0.03	0.5	0.3	<0.05	2	5.0	0.2	N.A.	N.A.	N.A.
1093266	Soil	27	32	0.89	432	0.003	3	1.15	0.004	0.04	<0.1	0.18	5.2	0.3	0.08	2	2.3	<0.2	N.A.	N.A.	N.A.
1093267	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	117.4	51.3	57.2
1093268	Soil	4	6	0.02	97	0.003	1	0.18	0.023	0.04	<0.1	0.04	0.2	<0.1	0.06	<1	0.7	<0.2	N.A.	N.A.	N.A.
1093269	Soil	23	49	0.07	291	0.004	4	0.61	0.003	0.11	0.1	0.07	3.1	0.4	0.15	3	3.0	<0.2	N.A.	N.A.	N.A.
1093270	Soil	15	16	0.02	112	0.004	2	0.28	0.005	0.06	0.2	0.04	0.3	0.5	0.08	3	1.7	<0.2	N.A.	N.A.	N.A.
1093271	Soil	13	17	0.02	153	0.003	3	0.31	0.003	0.08	0.2	0.03	0.3	0.3	0.08	3	2.3	0.2	N.A.	N.A.	N.A.
1093272	Soil	13	10	0.06	113	0.002	3	0.77	0.002	0.08	<0.1	0.05	2.0	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.
1093273	Soil	5	16	0.08	109	0.002	1	0.53	0.003	0.07	<0.1	0.03	2.7	0.3	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.
1093274	Soil	9	13	0.04	113	0.005	1	0.51	0.005	0.06	0.1	0.03	0.8	0.2	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.
1093275	Soil	9	14	0.06	129	0.003	1	0.51	0.003	0.05	0.1	0.02	0.9	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.
1093276	Soil	3	9	0.05	400	0.002	1	0.59	0.017	0.06	<0.1	0.16	1.2	0.4	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1093207	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093208	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093209	Soil		226	1.6	79.2	7.0	130	1.45	19.1	5.3	<0.1	36	1.5	2.7	0.2	62	0.28	0.219	7	27	0.11	438
1093210	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093251	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093252	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093253	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093254	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093255	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093256	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093257	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093258	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093259	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093260	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093261	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093262	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093263	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093264	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093265	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093266	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093267	Soil		230	0.3	49.3	4.7	78	1.68	39.6	1.2	<0.1	14	0.2	11.8	0.4	408	0.03	0.048	12	15	0.02	74
1093268	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093269	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093270	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093271	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093272	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093273	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093274	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093275	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093276	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093207	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093208	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093209	Soil		0.002	<20	0.75	0.014	0.10	0.1	1.40	0.2	0.7	0.15	3	3.9	<0.2
1093210	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093251	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093252	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093253	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093254	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093255	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093256	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093257	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093258	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093259	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093260	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093261	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093262	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093263	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093264	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093265	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093266	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093267	Soil		0.002	<20	0.28	0.005	0.05	0.3	0.03	0.2	0.1	<0.05	2	3.7	0.3
1093268	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093269	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093270	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093271	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093272	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093273	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093274	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093275	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093276	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093277	Soil		6.5	17.9	10.1	78	0.2	20.2	3.9	82	1.29	10.3	<0.5	0.5	11	0.2	1.8	0.2	45	0.02	0.064
1093278	Soil		17.1	32.6	10.9	179	0.1	43.9	6.7	116	1.92	14.9	1.8	0.7	14	0.9	3.4	0.2	64	0.07	0.060
1093279	Soil		10.7	27.7	10.2	249	0.4	49.3	6.2	159	1.62	17.5	1.6	0.7	49	1.3	3.7	0.2	76	0.77	0.119
1093280	Soil		19.2	35.4	10.8	348	0.7	81.0	7.1	170	1.95	18.0	2.9	0.9	44	2.4	4.9	0.1	82	0.52	0.132
1093281	Soil		26.2	45.8	12.4	457	0.8	107.0	9.1	190	2.21	24.4	4.3	1.2	54	3.6	6.4	0.2	115	0.56	0.205
1093282	Soil		15.5	13.3	5.1	118	<0.1	23.5	2.4	25	0.76	9.7	1.4	0.2	5	0.4	3.1	<0.1	72	0.02	0.038
1093283	Soil		16.1	43.7	15.1	1739	1.0	168.8	7.8	177	2.49	31.3	4.6	1.5	44	5.4	6.7	0.2	100	1.84	0.159
1093284	Soil		26.2	53.4	13.8	662	1.0	106.4	11.9	316	2.34	35.0	4.1	1.8	62	5.7	7.4	0.2	133	0.61	0.199
1093285	Soil		28.7	47.2	15.6	628	0.7	100.5	12.9	340	2.67	42.4	4.5	1.9	64	4.1	8.3	0.2	148	0.49	0.218
1093286	Soil		21.7	26.3	5.7	231	<0.1	76.9	6.7	57	1.69	19.8	<0.5	<0.1	5	0.8	5.0	<0.1	165	0.02	0.123
1093287	Soil		28.3	35.6	9.3	438	0.2	98.2	7.9	167	1.83	21.5	0.9	0.5	16	3.3	6.5	0.1	214	0.16	0.136
1093288	Soil		60.6	117.4	15.9	1449	1.7	269.5	16.1	306	3.18	55.6	2.3	2.6	91	14.5	18.6	0.2	616	1.51	0.302
1093289	Soil		16.4	16.2	5.5	115	<0.1	32.4	3.4	34	0.89	11.9	<0.5	0.2	6	0.7	2.8	<0.1	144	0.05	0.076
1093290	Soil		15.0	21.1	11.9	144	<0.1	34.9	5.2	73	1.86	22.2	5.5	0.3	13	0.6	3.3	0.2	82	0.03	0.067
1093291	Soil		10.8	20.9	12.8	149	0.2	36.9	5.3	118	1.87	18.2	<0.5	0.2	25	1.5	2.7	0.2	66	0.27	0.095
1093292	Soil		12.4	24.0	16.0	178	0.1	43.9	6.2	104	2.13	25.1	<0.5	0.4	19	0.7	3.6	0.3	91	0.18	0.067
1093293	Soil		20.4	31.9	8.7	421	0.4	94.0	8.0	198	1.94	19.1	0.9	1.2	65	2.4	4.4	0.1	134	0.95	0.186
1093294	Soil		16.5	25.3	11.9	409	0.2	67.8	5.1	80	1.64	17.7	<0.5	1.0	33	1.7	3.7	0.2	90	0.36	0.059
1093295	Soil		28.0	55.7	10.9	1495	0.7	160.9	12.4	320	2.62	26.1	1.5	2.2	81	12.9	6.8	0.1	269	0.87	0.314
1093296	Soil		30.5	25.9	6.1	575	0.6	84.5	3.9	33	1.46	25.6	<0.5	0.7	27	2.5	10.4	0.1	536	0.43	0.068
1093297	Soil		12.6	62.2	7.7	1478	0.8	261.8	4.5	65	1.41	13.5	<0.5	0.6	83	11.7	5.0	0.1	113	1.93	0.129
1093298	Soil		10.0	36.2	10.4	430	1.0	90.2	6.7	128	2.28	19.9	3.8	1.5	62	15.6	4.4	0.2	108	0.63	0.142
1093299	Soil		10.2	27.3	10.0	133	0.3	31.0	3.8	47	1.69	21.9	2.9	0.3	17	1.0	4.5	0.2	79	0.04	0.068
1093300	Soil		7.7	15.4	6.7	82	0.5	19.3	2.6	28	0.92	11.3	<0.5	<0.1	39	0.3	2.1	0.1	69	0.30	0.089
1093301	Soil		57.2	109.7	17.2	757	0.8	305.0	40.6	859	6.36	39.7	0.8	4.0	168	7.4	14.6	0.1	396	1.82	0.368
1093302	Soil		68.2	70.8	11.1	415	0.4	196.4	10.5	249	2.41	28.3	1.2	1.8	60	5.3	7.7	0.1	138	1.40	0.116
1093303	Soil		39.2	45.2	7.1	305	0.3	101.2	6.4	109	1.46	17.7	<0.5	0.7	52	3.3	5.9	0.1	119	0.95	0.076
1093304	Soil		58.8	74.6	16.5	527	0.7	172.5	14.2	272	3.02	40.3	1.1	1.9	51	5.3	10.0	0.2	151	0.42	0.161
1093305	Soil		42.4	64.3	17.7	676	0.9	147.3	12.9	319	2.78	38.5	2.2	2.2	83	8.1	12.2	0.2	164	0.84	0.217
1093306	Soil		9.2	58.7	25.0	357	0.4	71.7	10.2	316	3.08	29.2	4.6	1.3	33	2.4	4.9	0.2	57	0.36	0.133

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1093277	Soil		6	14	0.04	187	0.004	2	0.45	0.008	0.06	0.2	0.06	1.1	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.
1093278	Soil		8	13	0.05	316	0.002	1	0.42	0.003	0.07	0.1	0.03	1.4	0.3	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.
1093279	Soil		6	15	0.15	507	0.004	3	0.63	0.012	0.06	0.1	0.27	1.5	0.2	0.05	2	2.6	<0.2	N.A.	N.A.	N.A.
1093280	Soil		10	18	0.11	564	0.004	2	0.68	0.010	0.06	0.1	0.36	2.6	0.4	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.
1093281	Soil		15	22	0.09	497	0.003	4	0.56	0.004	0.09	<0.1	0.26	3.3	0.6	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.
1093282	Soil		8	10	0.02	106	0.002	3	0.31	0.004	0.06	<0.1	0.02	0.4	0.3	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.
1093283	Soil		10	20	0.08	467	0.002	<1	0.71	0.004	0.03	<0.1	0.62	3.6	0.3	0.06	1	1.0	<0.2	N.A.	N.A.	N.A.
1093284	Soil		13	19	0.10	1842	0.003	1	0.55	0.005	0.06	0.2	1.15	3.5	0.5	<0.05	1	2.3	<0.2	N.A.	N.A.	N.A.
1093285	Soil		14	22	0.10	1963	0.003	2	0.57	0.003	0.07	0.1	1.13	3.2	0.5	<0.05	1	2.3	<0.2	N.A.	N.A.	N.A.
1093286	Soil		5	26	0.05	428	0.001	1	0.50	0.008	0.04	0.1	0.03	0.2	0.5	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.
1093287	Soil		11	33	0.13	861	0.003	1	0.57	0.006	0.05	0.2	0.10	0.9	0.9	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.
1093288	Soil		24	79	0.64	2217	0.005	4	0.87	0.004	0.13	0.3	0.65	5.8	1.4	<0.05	3	6.3	<0.2	N.A.	N.A.	N.A.
1093289	Soil		7	21	0.05	296	0.004	2	0.46	0.007	0.04	0.1	0.04	0.5	0.4	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.
1093290	Soil		8	14	0.04	247	0.003	<1	0.40	0.003	0.04	0.1	0.03	0.6	0.3	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.
1093291	Soil		7	17	0.11	380	0.005	1	0.50	0.005	0.05	0.1	0.05	0.6	0.3	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.
1093292	Soil		7	16	0.07	303	0.004	<1	0.44	0.004	0.05	0.2	0.02	1.0	0.3	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.
1093293	Soil		11	37	0.16	761	0.005	3	0.65	0.007	0.07	0.1	0.13	2.3	0.7	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.
1093294	Soil		7	19	0.11	405	0.005	1	0.42	0.006	0.05	0.2	0.07	1.2	0.5	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.
1093295	Soil		25	52	0.26	1309	0.006	3	0.84	0.004	0.11	0.2	0.39	3.7	1.3	<0.05	2	4.2	<0.2	N.A.	N.A.	N.A.
1093296	Soil		10	47	0.17	461	0.004	<1	0.71	0.009	0.08	0.2	0.14	1.5	1.3	<0.05	3	5.1	<0.2	N.A.	N.A.	N.A.
1093297	Soil		11	60	0.21	445	0.007	4	0.67	0.016	0.06	<0.1	0.77	3.2	1.7	0.07	2	3.2	<0.2	N.A.	N.A.	N.A.
1093298	Soil		12	25	0.14	1164	0.004	1	0.71	0.009	0.07	0.1	0.49	3.0	0.8	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.
1093299	Soil		7	9	0.02	695	0.002	<1	0.34	0.002	0.04	<0.1	0.12	0.6	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.
1093300	Soil		8	10	0.08	743	0.004	<1	0.51	0.009	0.04	0.1	0.17	0.3	0.3	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1093301	Soil		54	106	0.78	689	0.007	7	0.96	0.009	0.13	0.2	0.39	11.1	1.5	<0.05	3	10.5	<0.2	N.A.	N.A.	N.A.
1093302	Soil		13	23	0.46	438	0.004	1	0.37	0.007	0.07	0.2	0.31	4.3	1.2	<0.05	1	3.3	<0.2	N.A.	N.A.	N.A.
1093303	Soil		10	19	0.14	379	0.005	1	0.56	0.021	0.05	0.1	0.18	2.3	0.6	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.
1093304	Soil		16	29	0.13	647	0.004	<1	0.56	0.002	0.07	0.2	0.32	4.1	0.9	<0.05	1	3.5	<0.2	N.A.	N.A.	N.A.
1093305	Soil		14	28	0.19	889	0.005	<1	0.39	0.005	0.10	0.1	0.58	4.2	0.9	0.05	1	4.1	<0.2	N.A.	N.A.	N.A.
1093306	Soil		10	17	0.20	216	0.009	<1	0.62	0.008	0.06	0.1	0.19	2.2	0.2	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1093277	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093278	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093279	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093280	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093281	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093282	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093283	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093284	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093285	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093286	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093287	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093288	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093289	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093290	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093291	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093292	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093293	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093294	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093295	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093296	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093297	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093298	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093299	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093300	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093301	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093302	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093303	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093304	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093305	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093306	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093277	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093278	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093279	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093280	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093281	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093282	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093283	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093284	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093286	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093287	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093288	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093289	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093290	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093291	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093292	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093293	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093294	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093295	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093296	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093297	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093298	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093299	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093300	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093301	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093302	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093303	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093304	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093305	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093306	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093307	Soil		11.1	110.0	46.6	1058	0.3	52.9	15.3	179	2.77	47.9	2.9	0.3	25	5.6	22.2	0.2	47	0.65	0.096
1093308	Soil		9.6	116.4	18.6	946	0.2	46.7	5.7	49	2.64	65.5	2.5	<0.1	4	0.9	26.1	0.2	51	0.03	0.083
1093309	Soil		8.5	116.0	49.4	666	0.9	59.6	11.8	914	5.96	39.5	11.4	1.4	19	5.0	25.4	0.2	39	0.45	0.195
1093310	Soil		6.2	110.0	39.5	535	0.7	46.2	10.2	802	4.50	38.5	15.8	0.5	16	3.6	13.8	0.2	30	0.43	0.247
1093311	Soil		3.6	117.7	22.2	199	0.1	39.2	8.9	119	3.04	20.2	5.2	0.2	6	0.4	2.7	0.3	19	0.04	0.110
1093312	Soil		7.2	167.8	28.6	237	0.1	61.8	15.8	113	4.94	23.4	2.3	0.2	5	0.2	3.2	0.2	31	<0.01	0.107
1093313	Soil		3.9	202.5	18.2	117	0.3	59.6	13.6	70	4.36	31.7	5.1	0.1	3	<0.1	5.2	0.3	21	<0.01	0.099
1093314	Soil		17.2	78.9	41.0	62	0.2	39.2	8.0	409	4.07	31.1	<0.5	0.5	15	0.3	8.5	0.3	48	0.19	0.165
1093315	Soil		5.1	24.7	18.0	111	<0.1	30.3	12.5	281	4.11	102.0	<0.5	0.6	4	0.1	2.5	0.6	27	0.02	0.067
1093316	Soil		3.3	43.8	25.3	96	<0.1	40.2	22.1	460	5.06	58.4	<0.5	1.2	10	0.1	2.0	0.5	25	0.11	0.093
1093317	Soil		2.5	12.8	8.0	77	<0.1	19.6	6.1	112	3.31	7.5	<0.5	0.7	4	0.2	0.9	0.3	27	<0.01	0.067
1093318	Soil		2.0	16.7	13.3	69	<0.1	19.1	11.3	425	3.10	8.3	<0.5	1.0	6	0.2	0.7	0.4	15	0.01	0.063
1093319	Soil		12.5	34.0	21.2	241	0.8	63.2	4.1	33	1.69	33.8	0.8	0.1	24	0.3	4.9	0.4	111	0.03	0.088
1093320	Soil		6.7	16.6	10.9	86	0.7	27.9	3.3	34	1.10	21.9	<0.5	0.2	8	<0.1	2.3	0.2	55	<0.01	0.030
1093321	Soil		9.7	25.4	23.6	133	0.3	39.9	4.6	48	1.54	30.6	1.3	0.1	29	0.1	3.2	0.3	69	0.01	0.066
1093322	Soil		12.6	37.1	33.1	177	0.5	54.5	5.4	82	2.08	32.1	<0.5	0.2	48	0.4	4.8	0.3	78	0.04	0.141
1093323	Soil		6.3	38.5	13.2	144	0.8	47.5	11.4	517	2.59	20.7	3.6	0.3	7	0.3	2.5	0.2	24	0.01	0.105
1093324	Soil		6.0	35.6	14.5	148	1.1	46.5	6.1	117	2.02	19.9	2.8	0.2	26	0.6	2.4	0.2	38	0.27	0.175
1093325	Soil		5.8	22.2	15.2	119	0.4	31.2	3.7	58	1.47	18.5	1.3	0.1	23	0.3	2.3	0.2	46	0.07	0.129
1093326	Soil		5.4	19.1	9.9	93	0.3	25.9	3.3	36	1.07	13.7	<0.5	0.2	10	0.2	1.7	0.1	34	0.02	0.079
1093327	Soil		13.2	41.9	16.4	304	0.5	61.2	7.5	125	2.60	27.6	1.5	0.6	24	1.1	5.7	0.2	78	0.14	0.239
1093328	Soil		15.8	61.8	14.0	510	0.8	91.1	9.0	188	2.65	27.0	3.6	3.8	53	4.5	6.5	0.2	77	1.13	0.157
1093329	Soil		29.4	56.4	9.3	295	0.3	123.4	8.1	170	1.72	20.1	<0.5	1.0	81	2.1	4.5	0.1	39	2.66	0.097
1093330	Soil		16.5	17.0	8.3	167	0.3	39.1	3.0	84	1.07	13.9	<0.5	0.3	22	1.6	2.5	0.1	197	0.19	0.103
1093331	Soil		41.6	40.7	11.0	507	1.1	137.9	6.0	105	1.73	30.0	<0.5	0.3	40	4.6	7.7	0.1	253	0.44	0.125
1093332	Soil		38.4	55.2	10.0	516	0.9	109.4	5.2	70	1.69	27.6	1.5	0.5	30	7.4	9.1	0.2	395	0.37	0.084
1093333	Soil		30.2	25.3	8.6	218	0.3	60.9	4.0	87	1.32	19.9	0.9	0.7	25	1.5	3.9	0.1	122	0.36	0.067
1093334	Soil		1.8	24.2	20.6	93	0.5	22.5	5.2	52	2.22	18.2	1.7	1.6	27	0.2	0.8	0.2	15	0.31	0.071
1093335	Soil		2.3	19.6	13.1	47	0.9	13.8	1.3	23	1.36	8.6	3.6	0.6	53	0.2	1.1	0.2	19	0.21	0.037
1093336	Soil		1.7	39.4	18.0	437	1.5	123.0	8.9	172	3.74	19.6	5.6	2.6	237	2.3	22.7	0.3	256	5.58	0.865

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1093307	Soil	6	10	0.09	130	0.005	<1	0.39	0.016	0.04	<0.1	0.86	1.3	0.2	<0.05	3	3.6	<0.2	N.A.	N.A.	N.A.
1093308	Soil	4	10	0.02	52	0.003	<1	0.18	0.007	0.04	<0.1	0.37	0.4	<0.1	<0.05	3	4.4	<0.2	N.A.	N.A.	N.A.
1093309	Soil	11	12	0.09	258	0.003	1	0.43	0.003	0.06	<0.1	0.44	4.5	0.2	<0.05	1	3.0	<0.2	N.A.	N.A.	N.A.
1093310	Soil	7	11	0.11	228	0.004	<1	0.49	0.010	0.06	<0.1	0.26	2.0	0.1	<0.05	2	3.7	<0.2	N.A.	N.A.	N.A.
1093311	Soil	4	7	0.02	202	0.003	<1	0.31	0.008	0.05	<0.1	0.06	0.7	0.1	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.
1093312	Soil	3	8	0.04	84	0.002	<1	0.36	0.004	0.06	<0.1	0.03	1.2	0.2	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.
1093313	Soil	2	8	0.03	71	0.014	<1	0.34	0.005	0.07	<0.1	0.06	0.8	0.2	<0.05	2	3.9	<0.2	N.A.	N.A.	N.A.
1093314	Soil	7	7	0.04	460	0.003	<1	0.34	0.002	0.05	<0.1	0.03	1.6	0.6	<0.05	1	4.2	<0.2	N.A.	N.A.	N.A.
1093315	Soil	4	9	0.04	115	0.003	<1	0.33	0.003	0.07	<0.1	0.03	1.9	0.1	<0.05	1	1.3	<0.2	N.A.	N.A.	N.A.
1093316	Soil	8	10	0.05	115	0.002	<1	0.32	0.002	0.05	<0.1	0.02	3.4	0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.
1093317	Soil	5	10	0.05	55	0.002	<1	0.40	0.002	0.05	<0.1	0.02	1.5	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1093318	Soil	6	9	0.04	84	0.003	<1	0.37	0.006	0.07	<0.1	0.02	2.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.
1093319	Soil	7	15	0.02	98	0.003	2	0.30	0.003	0.04	0.1	0.06	0.4	0.1	0.07	2	3.6	0.2	N.A.	N.A.	N.A.
1093320	Soil	10	8	0.01	65	0.004	2	0.22	0.004	0.04	<0.1	0.01	0.3	0.1	0.07	2	1.1	<0.2	N.A.	N.A.	N.A.
1093321	Soil	9	11	0.02	94	0.003	1	0.30	0.004	0.04	0.1	<0.01	0.3	0.2	0.07	2	1.9	<0.2	N.A.	N.A.	N.A.
1093322	Soil	8	13	0.02	155	0.003	2	0.31	0.005	0.05	<0.1	0.02	0.2	0.2	0.06	2	2.9	0.2	N.A.	N.A.	N.A.
1093323	Soil	12	8	0.03	189	0.002	2	0.38	0.009	0.06	<0.1	0.06	0.8	0.2	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.
1093324	Soil	10	10	0.07	673	0.003	2	0.55	0.013	0.07	<0.1	0.21	0.8	0.2	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.
1093325	Soil	8	12	0.03	284	0.003	1	0.34	0.009	0.05	<0.1	0.05	0.2	0.2	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.
1093326	Soil	7	9	0.02	359	0.004	1	0.31	0.009	0.05	<0.1	0.03	0.4	0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.
1093327	Soil	13	15	0.04	464	0.005	1	0.51	0.002	0.07	<0.1	0.17	1.1	0.2	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.
1093328	Soil	13	16	0.48	1675	0.004	3	0.42	0.003	0.09	<0.1	1.50	4.7	0.3	0.06	1	3.1	<0.2	N.A.	N.A.	N.A.
1093329	Soil	7	10	0.97	544	0.004	3	0.36	0.015	0.06	<0.1	0.39	2.3	0.6	0.10	<1	2.1	<0.2	N.A.	N.A.	N.A.
1093330	Soil	8	20	0.08	399	0.003	2	0.66	0.007	0.07	0.1	0.09	0.8	0.6	0.08	3	1.3	<0.2	N.A.	N.A.	N.A.
1093331	Soil	11	20	0.09	823	0.004	3	0.67	0.014	0.09	0.2	0.49	1.4	1.2	0.05	2	4.3	<0.2	N.A.	N.A.	N.A.
1093332	Soil	14	25	0.09	1121	0.003	3	0.64	0.007	0.09	0.2	0.50	1.5	1.0	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.
1093333	Soil	12	16	0.10	805	0.003	2	0.66	0.003	0.07	0.2	0.11	1.1	1.0	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.
1093334	Soil	2	14	0.05	303	<0.001	2	0.51	0.004	0.10	<0.1	0.14	4.4	0.1	0.11	2	2.2	<0.2	N.A.	N.A.	N.A.
1093335	Soil	2	9	0.01	507	<0.001	2	0.30	0.004	0.07	<0.1	0.14	1.2	0.2	0.10	1	2.7	<0.2	N.A.	N.A.	N.A.
1093336	Soil	15	71	0.10	1298	0.011	16	1.14	0.009	0.19	0.2	6.29	3.5	0.2	<0.05	3	2.6	0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1093307	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093308	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093309	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093310	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093311	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093312	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093313	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093314	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093315	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093316	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093317	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093318	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093319	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093320	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093321	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093322	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093323	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093324	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093325	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093326	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093327	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093328	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093329	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093330	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093331	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093332	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093333	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093334	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093335	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093336	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093307	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093308	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093309	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093310	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093311	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093320	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093323	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093326	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093327	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093328	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093329	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093330	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093331	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093332	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093333	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093334	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093335	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093336	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093337	Soil		1.3	14.6	13.5	61	0.7	14.4	1.9	71	1.23	17.9	8.7	0.6	42	0.3	2.0	0.2	13	0.75	0.061
1093338	Soil		1.2	46.6	17.6	348	0.9	101.7	21.2	229	3.66	25.8	2.2	1.5	142	1.0	5.1	0.2	41	2.41	0.228
1093339	Soil		4.2	43.0	14.3	241	1.7	65.6	7.7	146	2.67	29.1	3.2	1.0	165	1.3	5.8	0.2	69	3.61	0.247
1093340	Soil		4.4	46.7	12.5	219	2.3	63.7	6.5	119	2.65	22.0	2.6	0.7	93	1.2	2.4	0.2	26	1.45	0.159
1093341	Soil		2.7	43.2	16.9	135	1.0	47.3	7.9	157	2.78	68.6	6.0	0.7	63	0.4	5.8	0.2	23	0.20	0.096
1093342	Soil		3.6	38.1	12.2	89	1.6	26.0	3.1	36	2.01	45.1	7.1	1.1	40	0.3	2.7	0.2	23	0.06	0.066
1093343	Soil		3.7	133.4	17.8	149	2.0	65.7	9.4	126	4.18	60.8	22.0	1.6	61	0.3	4.6	0.3	28	0.01	0.115
1093344	Soil		2.6	80.8	16.7	135	1.3	54.7	7.4	59	2.79	44.3	15.4	0.9	46	0.4	3.6	0.2	30	0.02	0.084
1093345	Soil		2.0	32.8	13.6	88	1.1	25.9	4.3	35	2.13	43.0	6.6	0.4	43	<0.1	2.2	0.2	20	0.03	0.061
1093346	Soil		2.4	37.6	23.5	39	1.5	12.6	1.5	17	2.27	102.7	18.7	0.8	57	0.1	7.8	0.3	23	0.03	0.060
1093347	Soil		2.0	47.2	16.8	87	0.6	27.1	6.0	88	2.37	57.2	6.8	0.7	28	0.2	2.4	0.2	25	0.04	0.072
1093348	Soil		2.6	45.1	18.4	108	0.9	32.6	8.2	136	2.75	38.0	4.4	0.8	35	0.3	2.3	0.3	22	0.06	0.068
1093349	Soil		2.9	36.8	15.8	83	0.8	23.1	5.1	127	2.20	23.7	5.6	0.4	35	0.1	1.6	0.2	26	0.07	0.075
1093350	Soil		5.2	12.5	9.5	44	1.2	10.5	1.7	27	1.01	18.4	3.6	0.4	9	<0.1	3.0	0.2	64	<0.01	0.024
1093351	Soil		7.5	43.1	21.7	302	0.3	39.6	5.0	143	2.12	23.2	2.2	0.2	18	0.3	4.5	0.2	60	0.06	0.102
1093352	Soil		10.1	73.5	36.3	425	0.3	74.3	10.3	307	3.77	44.3	5.7	0.4	10	0.6	5.2	0.3	65	0.09	0.209
1093353	Soil		15.8	31.7	16.7	206	0.3	49.6	6.4	65	2.16	27.6	2.0	0.2	30	0.3	4.7	0.3	93	0.01	0.082
1093354	Soil		1.9	12.1	4.9	52	1.1	13.2	1.3	26	0.49	6.0	0.9	<0.1	22	0.5	0.9	<0.1	10	0.11	0.066
1093355	Soil		7.4	18.6	10.4	84	0.2	22.7	3.7	39	1.22	25.8	<0.5	<0.1	10	0.1	2.0	0.2	65	<0.01	0.080
1093356	Soil		5.5	25.8	10.5	78	1.1	25.1	4.8	85	1.71	37.8	1.1	0.3	7	0.1	3.9	0.2	53	0.02	0.081
1093357	Soil		1.2	6.0	3.8	13	0.5	5.9	1.6	71	0.55	28.3	0.7	<0.1	5	<0.1	1.2	<0.1	11	0.02	0.042
1093358	Soil		2.7	12.2	7.0	42	0.5	12.7	2.3	57	0.72	30.2	<0.5	<0.1	20	0.3	1.2	0.1	27	0.15	0.067
1093359	Soil		3.5	9.4	6.5	34	0.3	9.1	1.5	17	0.52	8.2	<0.5	0.2	8	<0.1	0.9	<0.1	31	0.02	0.040
1093360	Soil		5.9	37.9	12.3	155	1.6	28.7	4.4	77	2.19	19.1	3.7	0.8	25	1.7	2.6	0.3	65	0.16	0.366
1093361	Soil		9.8	92.7	18.2	341	1.0	79.1	8.1	159	2.42	29.0	4.5	1.9	48	2.9	4.2	0.2	70	0.47	0.187
1093362	Soil		31.0	29.2	10.0	101	0.3	47.6	4.2	85	1.32	15.0	1.5	0.4	11	1.2	3.6	0.1	82	0.09	0.092
1093363	Soil		60.2	42.0	12.0	251	<0.1	107.0	7.7	66	2.24	30.7	1.6	0.8	10	0.6	7.0	0.1	128	0.09	0.095
1093364	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093365	Soil		26.6	23.8	11.5	182	0.2	50.6	4.3	44	1.45	24.2	1.3	<0.1	11	0.3	4.4	0.2	176	0.05	0.077
1093366	Soil		49.1	27.1	9.0	245	0.3	69.8	5.4	38	1.63	40.5	<0.5	0.3	6	0.4	7.5	0.2	293	0.05	0.055

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1093337	Soil	3	12	0.02	500	<0.001	2	0.39	0.005	0.10	<0.1	0.27	1.7	0.2	0.19	1	1.4	<0.2	N.A.	N.A.	N.A.
1093338	Soil	6	26	0.06	2780	0.003	3	0.68	0.006	0.08	<0.1	1.39	4.5	0.1	0.08	2	1.3	<0.2	N.A.	N.A.	N.A.
1093339	Soil	9	32	0.10	1135	0.003	6	0.78	0.007	0.10	0.1	1.33	3.2	0.3	0.10	2	3.8	<0.2	N.A.	N.A.	N.A.
1093340	Soil	7	25	0.06	763	0.002	3	0.70	0.006	0.06	<0.1	0.64	3.1	0.1	0.12	1	4.9	<0.2	N.A.	N.A.	N.A.
1093341	Soil	3	18	0.03	467	0.002	3	0.60	0.006	0.10	0.1	0.34	2.3	0.1	0.11	2	3.5	<0.2	N.A.	N.A.	N.A.
1093342	Soil	4	18	0.04	878	<0.001	1	0.54	0.003	0.06	<0.1	0.99	2.9	<0.1	<0.05	2	3.5	<0.2	N.A.	N.A.	N.A.
1093343	Soil	4	20	0.02	304	0.001	2	0.96	0.003	0.08	<0.1	0.60	4.7	0.2	0.10	2	3.2	<0.2	N.A.	N.A.	N.A.
1093344	Soil	3	20	0.02	316	0.001	1	0.51	0.004	0.10	<0.1	0.32	3.8	0.2	0.09	2	3.5	<0.2	N.A.	N.A.	N.A.
1093345	Soil	2	12	0.01	450	<0.001	2	0.41	0.008	0.09	<0.1	0.44	2.2	0.1	0.08	2	3.6	<0.2	N.A.	N.A.	N.A.
1093346	Soil	2	16	0.01	508	<0.001	<1	0.55	0.003	0.14	<0.1	0.83	1.8	0.2	0.18	2	4.8	<0.2	N.A.	N.A.	N.A.
1093347	Soil	2	14	0.04	372	0.001	<1	0.61	0.007	0.07	<0.1	0.15	2.2	<0.1	<0.05	2	3.5	<0.2	N.A.	N.A.	N.A.
1093348	Soil	3	16	0.06	400	0.001	<1	0.60	0.005	0.08	<0.1	0.26	3.0	<0.1	0.05	2	3.2	<0.2	N.A.	N.A.	N.A.
1093349	Soil	4	15	0.06	342	0.002	<1	0.74	0.009	0.07	<0.1	0.21	1.6	0.1	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.
1093350	Soil	9	10	0.02	132	0.005	2	0.42	0.002	0.04	0.1	0.33	0.6	0.1	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.
1093351	Soil	9	13	0.04	124	0.004	4	0.40	0.006	0.06	0.1	0.07	0.5	0.2	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.
1093352	Soil	7	12	0.03	163	0.002	<1	0.41	0.002	0.07	<0.1	0.15	2.3	0.4	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.
1093353	Soil	11	14	0.03	210	0.004	2	0.42	0.003	0.09	0.1	0.03	0.4	0.4	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.
1093354	Soil	2	3	0.02	281	0.002	<1	0.23	0.023	0.04	<0.1	0.07	0.1	0.1	<0.05	<1	0.7	<0.2	N.A.	N.A.	N.A.
1093355	Soil	9	12	0.03	112	0.001	1	0.49	0.003	0.06	<0.1	0.02	0.1	0.3	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.
1093356	Soil	8	12	0.03	186	0.003	2	0.35	0.007	0.06	0.1	0.05	0.5	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.
1093357	Soil	2	4	0.02	82	0.003	<1	0.26	0.023	0.03	0.1	0.05	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.
1093358	Soil	5	7	0.04	504	0.004	<1	0.40	0.017	0.05	<0.1	0.08	0.5	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1093359	Soil	9	7	0.03	93	0.002	1	0.31	0.006	0.05	<0.1	0.02	0.2	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1093360	Soil	9	30	0.10	1031	0.007	<1	1.16	0.004	0.07	0.1	0.68	2.1	0.2	0.12	4	1.7	<0.2	N.A.	N.A.	N.A.
1093361	Soil	13	17	0.17	1693	0.006	2	0.68	0.004	0.10	0.1	0.58	3.4	0.3	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.
1093362	Soil	9	11	0.04	388	0.002	2	0.52	0.004	0.05	<0.1	0.23	0.7	0.5	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.
1093363	Soil	14	12	0.04	120	0.005	1	0.44	0.002	0.05	0.1	0.13	1.1	0.5	<0.05	1	3.2	<0.2	N.A.	N.A.	N.A.
1093364	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	49.7	64.1	12.0
1093365	Soil	13	17	0.04	147	0.002	2	0.48	0.004	0.07	0.1	0.07	0.3	0.5	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.
1093366	Soil	19	21	0.05	191	0.003	3	0.50	0.002	0.07	0.2	0.09	0.5	0.8	<0.05	3	2.9	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
		Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
		MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1093337	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093338	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093339	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093340	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093341	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093342	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093343	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093344	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093345	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093346	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093347	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093348	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093349	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093350	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093351	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093352	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093353	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093354	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093355	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093356	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093357	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093358	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093359	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093360	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093361	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093362	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093363	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093364	Soil		441	0.7	138.6	7.6	244	1.66	38.6	1.8	0.9	189	6.4	6.9	0.1	160	6.22	0.160	12	20	1.95	814
1093365	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093366	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093338	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093340	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093341	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093342	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093343	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093344	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093345	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093346	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093347	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093348	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093349	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093350	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093351	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093352	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093353	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093354	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093355	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093356	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093357	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093358	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093359	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093360	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093361	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093362	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093363	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093364	Soil	0.003	<20	0.29	0.004	0.08	0.2	0.47	2.8	1.2	0.06	<1	3.1	<0.2
1093365	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093366	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093367	Soil		57.8	49.8	18.2	464	0.3	124.5	7.5	95	2.79	74.4	2.1	1.3	9	0.9	13.9	0.2	579	0.01	0.105
1093368	Soil		3.8	6.4	2.6	31	1.2	8.7	0.7	11	0.41	4.2	0.7	0.1	6	0.3	0.8	<0.1	46	0.03	0.070
1093369	Soil		7.6	10.3	6.6	64	0.3	16.0	1.5	22	0.74	11.1	0.7	<0.1	8	0.4	1.6	<0.1	101	0.02	0.087
1093370	Soil		2.6	24.8	12.3	171	0.9	35.9	5.0	163	2.61	16.4	2.6	1.1	64	0.9	1.5	0.2	54	0.69	0.176
1093391	Soil		5.0	13.7	14.3	32	2.3	7.7	1.1	27	1.27	22.4	4.1	0.7	61	<0.1	6.8	0.3	71	0.05	0.048
1093392	Soil		8.6	24.0	23.1	66	1.1	29.3	2.7	42	1.78	39.2	2.1	0.1	42	<0.1	8.5	0.3	124	0.02	0.062
1093393	Soil		4.2	20.3	13.4	80	0.1	16.2	15.1	1692	2.25	9.8	<0.5	0.1	11	0.3	1.2	0.2	47	0.07	0.102
1093394	Soil		3.6	46.9	43.3	254	0.1	65.6	77.6	1753	4.67	24.0	0.5	1.8	13	0.3	1.6	0.3	39	0.07	0.098
1093395	Soil		2.5	25.5	22.0	83	0.1	27.3	12.8	256	2.52	17.6	1.0	0.7	19	0.2	1.0	0.3	23	0.02	0.088
1093396	Soil		6.0	7.6	42.1	6	0.4	2.6	0.5	10	0.36	4.8	3.3	0.9	19	<0.1	2.1	0.2	20	<0.01	0.007
1093397	Soil		6.8	52.6	21.9	76	0.4	44.3	10.1	138	2.59	11.6	1.1	0.3	11	0.1	2.7	0.2	42	0.01	0.055
1093398	Soil		39.8	109.3	21.1	846	0.9	340.4	46.6	508	4.86	38.0	1.8	4.0	148	9.7	11.4	0.2	350	5.21	0.261
1093399	Soil		70.8	125.5	25.3	1254	1.5	342.6	25.3	335	3.47	82.2	2.5	2.8	122	12.5	17.2	0.2	550	3.49	0.203
1093400	Soil		4.5	10.8	2.3	52	0.1	17.8	2.1	36	0.30	3.1	<0.5	0.2	47	1.7	1.2	<0.1	14	0.99	0.042
1093401	Soil		1.7	5.2	3.7	19	0.2	4.6	1.2	20	0.43	4.1	0.6	0.1	5	<0.1	0.5	<0.1	26	0.01	0.020
1093402	Soil		8.2	22.4	22.2	123	0.2	32.0	7.5	124	3.39	25.4	0.6	0.5	13	0.2	2.4	0.3	77	0.03	0.081
1093403	Soil		12.2	14.9	6.8	54	0.6	27.3	2.8	32	0.87	5.8	1.1	0.1	7	0.3	1.0	<0.1	32	0.05	0.060
1093404	Soil		14.0	13.9	7.5	50	<0.1	20.5	2.1	40	0.84	6.3	<0.5	0.2	5	0.3	0.8	<0.1	35	0.03	0.050
1093405	Soil		10.6	7.9	6.4	50	<0.1	14.1	2.1	28	0.78	8.2	1.1	0.1	5	<0.1	1.0	0.1	39	0.02	0.045
1093406	Soil		34.5	33.8	16.1	473	0.2	74.2	5.5	104	2.10	20.8	1.3	1.9	14	1.5	12.7	0.1	135	0.11	0.083

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
1093367	Soil	19	42	0.09	226	0.005	3	0.82	0.002	0.09	0.3	0.46	1.3	1.3	<0.05	3	4.2	<0.2	N.A.	N.A.	N.A.
1093368	Soil	2	6	0.02	147	0.002	<1	0.24	0.020	0.03	<0.1	0.27	0.2	0.2	<0.05	<1	0.5	<0.2	N.A.	N.A.	N.A.
1093369	Soil	4	13	0.04	218	0.002	<1	0.50	0.014	0.05	<0.1	0.28	0.2	0.3	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.
1093370	Soil	11	33	0.13	591	0.005	<1	1.13	0.008	0.07	<0.1	0.17	3.5	0.2	0.05	3	1.4	<0.2	N.A.	N.A.	N.A.
1093391	Soil	3	11	0.02	507	0.002	<1	0.33	0.002	0.11	<0.1	0.16	0.7	0.4	0.16	2	3.1	<0.2	N.A.	N.A.	N.A.
1093392	Soil	3	14	0.02	301	0.003	1	0.44	0.003	0.06	0.1	0.05	0.6	0.4	<0.05	4	2.4	<0.2	N.A.	N.A.	N.A.
1093393	Soil	5	19	0.05	208	0.005	<1	0.65	0.008	0.07	<0.1	0.05	0.3	0.2	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.
1093394	Soil	4	30	0.41	395	0.003	<1	1.54	0.003	0.09	<0.1	0.02	4.8	0.6	<0.05	5	1.0	<0.2	N.A.	N.A.	N.A.
1093395	Soil	3	16	0.10	102	0.002	<1	0.76	0.003	0.06	<0.1	0.03	1.4	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.
1093396	Soil	2	6	<0.01	1708	<0.001	4	0.27	0.002	0.05	<0.1	1.20	1.1	0.7	0.08	1	3.9	<0.2	N.A.	N.A.	N.A.
1093397	Soil	2	9	0.02	112	0.001	<1	0.30	0.005	0.04	<0.1	0.05	1.6	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.
1093398	Soil	31	69	2.47	445	0.003	9	0.56	0.005	0.18	0.1	0.39	9.0	1.1	0.06	2	3.8	<0.2	N.A.	N.A.	N.A.
1093399	Soil	23	53	1.40	520	0.003	10	0.64	0.010	0.16	0.2	0.93	6.2	1.5	0.05	2	5.1	<0.2	N.A.	N.A.	N.A.
1093400	Soil	2	5	0.13	119	0.009	<1	0.22	0.026	0.02	<0.1	0.07	0.7	<0.1	0.12	<1	1.5	<0.2	N.A.	N.A.	N.A.
1093401	Soil	12	6	0.02	66	0.006	<1	0.38	0.007	0.04	<0.1	0.02	<0.1	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.
1093402	Soil	6	20	0.11	166	0.004	<1	1.01	0.006	0.07	<0.1	0.03	1.3	0.3	<0.05	5	0.9	<0.2	N.A.	N.A.	N.A.
1093403	Soil	3	10	0.04	259	0.002	<1	0.56	0.017	0.03	<0.1	0.12	0.7	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.
1093404	Soil	5	8	0.03	128	0.003	<1	0.53	0.014	0.04	<0.1	0.08	0.4	0.3	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.
1093405	Soil	5	6	0.02	65	0.002	<1	0.35	0.005	0.03	<0.1	0.02	0.3	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.
1093406	Soil	10	12	0.04	147	0.002	1	0.43	0.002	0.03	<0.1	0.18	2.1	0.3	<0.05	1	2.0	<0.2	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
	Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
	MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
1093367	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093368	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093369	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093370	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093391	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093392	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093393	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093394	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093395	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093396	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093397	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093398	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093399	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093400	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093401	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093402	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093403	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093404	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093405	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093406	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

CERTIFICATE OF ANALYSIS WHI11000767.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093367	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093368	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093369	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093370	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093391	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093392	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093393	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093394	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093395	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093396	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093397	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093398	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093399	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093400	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093401	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093402	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093403	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093404	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093405	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093406	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000767.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1092920	Soil		14.0	13.9	14.6	147	0.2	18.3	2.6	102	1.30	15.0	1.8	0.1	20	0.9	3.2	0.2	88	0.06	0.088
REP 1092920	QC		14.0	14.1	15.2	147	0.2	20.4	2.9	104	1.31	14.5	<0.5	0.1	19	0.8	3.2	0.2	88	0.06	0.087
1092932	Soil		3.6	27.0	13.2	44	1.3	11.8	3.0	186	2.07	21.9	6.5	0.6	41	<0.1	6.9	0.2	57	0.07	0.126
REP 1092932	QC		3.7	27.1	13.5	46	1.4	12.9	3.0	186	2.07	21.2	5.4	0.6	43	0.1	7.3	0.2	59	0.07	0.126
1092957	Soil		3.1	101.4	9.5	167	0.2	216.3	52.4	1152	6.94	41.0	1.5	10.0	92	0.5	1.3	<0.1	108	2.37	0.234
REP 1092957	QC		3.0	100.0	9.4	165	0.2	213.6	52.7	1142	6.95	40.4	1.9	9.7	91	0.5	1.3	<0.1	108	2.35	0.234
1092967	Soil		12.5	14.3	3.6	168	0.3	38.2	4.7	97	1.20	10.9	1.2	0.2	12	2.0	3.2	<0.1	132	0.09	0.126
REP 1092967	QC		11.5	13.3	3.4	157	0.3	36.8	4.3	93	1.15	10.2	0.6	<0.1	12	1.8	3.3	<0.1	128	0.08	0.122
1092992	Soil		43.6	38.7	21.5	756	0.1	86.4	8.4	199	2.72	24.6	1.0	2.5	21	2.2	14.3	0.2	191	0.29	0.057
REP 1092992	QC		45.6	39.3	22.9	790	0.1	87.3	8.6	196	2.76	24.9	<0.5	2.7	20	1.9	14.7	0.2	198	0.30	0.062
1092999	Soil		1.5	51.2	20.9	231	1.4	56.1	19.9	723	5.17	32.1	5.7	1.2	13	0.6	2.7	0.3	20	0.04	0.110
REP 1092999	QC		1.4	50.1	19.4	222	1.4	54.9	19.5	689	5.03	30.7	4.2	1.2	13	0.5	2.5	0.3	19	0.04	0.102
1093032	Soil		89.7	76.5	29.6	771	1.3	326.1	23.1	397	3.53	34.6	1.1	3.9	129	6.2	14.4	0.2	317	2.35	0.127
REP 1093032	QC		89.7	77.7	29.7	804	1.4	337.8	23.7	399	3.57	34.9	1.6	4.1	129	6.3	14.2	0.2	329	2.30	0.127
1093036	Soil		6.5	18.8	17.2	52	<0.1	12.6	3.0	93	1.67	11.3	<0.5	0.2	12	<0.1	2.6	0.3	55	0.01	0.038
REP 1093036	QC		5.7	17.9	17.4	52	<0.1	12.0	3.9	106	1.64	10.4	<0.5	0.2	14	0.2	2.5	0.3	54	0.01	0.040
1093047	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1093047	QC																				
1093058	Soil		5.1	130.8	35.7	318	1.9	112.7	51.5	1551	5.91	16.6	4.9	2.0	29	1.2	4.3	0.5	65	0.21	0.131
REP 1093058	QC		5.0	123.8	34.2	314	1.9	105.5	48.5	1491	5.62	14.4	6.6	2.1	28	1.1	4.2	0.4	64	0.21	0.122
1093202	Soil		42.5	22.3	29.2	132	1.1	20.1	2.9	264	2.74	59.4	28.0	1.0	46	2.3	16.0	0.3	191	0.15	0.088
REP 1093202	QC		39.0	22.5	29.3	134	1.1	21.7	3.2	263	2.71	58.3	29.7	1.0	46	2.1	15.7	0.3	194	0.13	0.083
1093260	Soil		18.3	49.5	24.3	283	0.5	83.9	10.5	171	3.22	32.1	5.5	1.2	43	0.7	5.2	0.3	119	0.18	0.218
REP 1093260	QC		18.1	50.9	23.8	289	0.5	84.5	10.5	171	3.28	32.4	5.0	1.3	43	0.7	5.1	0.3	116	0.19	0.214
1093282	Soil		15.5	13.3	5.1	118	<0.1	23.5	2.4	25	0.76	9.7	1.4	0.2	5	0.4	3.1	<0.1	72	0.02	0.038
REP 1093282	QC		15.0	13.5	5.5	122	<0.1	23.6	2.4	26	0.74	10.0	<0.5	0.2	5	0.3	3.1	<0.1	71	0.02	0.039
1093291	Soil		10.8	20.9	12.8	149	0.2	36.9	5.3	118	1.87	18.2	<0.5	0.2	25	1.5	2.7	0.2	66	0.27	0.095
REP 1093291	QC		10.2	20.9	13.3	153	0.2	36.1	5.3	115	1.86	18.3	2.0	0.2	25	1.5	2.6	0.2	67	0.27	0.098

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000767.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1
Pulp Duplicates																					
1092920	Soil	9	13	0.05	216	0.003	3	0.53	0.004	0.07	0.1	0.04	0.2	0.5	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.
REP 1092920	QC	9	13	0.05	213	0.005	2	0.52	0.004	0.06	0.1	0.02	0.2	0.5	<0.05	3	1.3	<0.2			
1092932	Soil	7	18	0.12	233	0.017	2	0.71	0.014	0.08	0.1	0.10	1.2	0.4	0.11	4	4.1	<0.2	N.A.	N.A.	N.A.
REP 1092932	QC	8	18	0.12	242	0.016	2	0.73	0.013	0.08	0.1	0.10	1.3	0.4	0.10	4	4.1	<0.2			
1092957	Soil	69	216	1.41	1236	0.004	4	1.94	0.006	0.08	0.1	0.05	23.1	<0.1	<0.05	6	<0.5	<0.2	N.A.	N.A.	N.A.
REP 1092957	QC	70	217	1.42	1238	0.004	4	2.01	0.007	0.08	0.1	0.05	23.1	0.1	<0.05	6	1.1	<0.2			
1092967	Soil	6	37	0.09	293	0.002	2	0.46	0.013	0.05	<0.1	0.03	0.3	0.4	0.06	3	2.7	<0.2	N.A.	N.A.	N.A.
REP 1092967	QC	6	35	0.08	277	0.002	2	0.45	0.013	0.05	<0.1	0.02	0.3	0.4	<0.05	3	2.3	<0.2			
1092992	Soil	6	16	0.07	309	0.002	2	0.53	0.003	0.05	0.1	0.13	2.5	0.4	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.
REP 1092992	QC	6	16	0.08	315	0.003	1	0.56	0.003	0.06	0.1	0.14	2.4	0.4	<0.05	2	2.1	<0.2			
1092999	Soil	10	9	0.06	1500	0.009	2	0.83	0.016	0.07	<0.1	0.14	3.8	0.2	0.09	2	2.0	0.2	N.A.	N.A.	N.A.
REP 1092999	QC	10	8	0.06	1462	0.009	1	0.77	0.013	0.07	<0.1	0.15	3.5	0.1	0.05	2	1.6	<0.2			
1093032	Soil	12	25	0.18	356	0.001	6	0.27	0.002	0.09	0.2	0.31	5.6	1.9	0.16	<1	6.0	<0.2	N.A.	N.A.	N.A.
REP 1093032	QC	12	25	0.20	380	0.002	5	0.28	0.002	0.09	0.2	0.34	5.6	1.9	0.14	<1	5.6	<0.2			
1093036	Soil	9	11	0.01	74	0.013	2	0.33	0.006	0.04	0.1	0.04	0.5	0.1	<0.05	3	2.8	<0.2	N.A.	N.A.	N.A.
REP 1093036	QC	9	10	0.02	75	0.014	3	0.32	0.005	0.04	0.2	0.02	0.6	0.1	<0.05	3	1.4	<0.2			
1093047	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	7.0	23.2	12.3
REP 1093047	QC																		7.6	23.7	12.7
1093058	Soil	5	23	0.12	306	0.005	<1	0.69	0.006	0.06	<0.1	0.21	10.5	0.5	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.
REP 1093058	QC	5	23	0.11	290	0.004	<1	0.64	0.006	0.05	<0.1	0.22	10.7	0.5	<0.05	2	3.3	<0.2			
1093202	Soil	8	15	0.04	1128	0.003	3	0.33	0.004	0.14	0.2	3.34	0.9	0.9	0.20	1	4.9	<0.2	N.A.	N.A.	N.A.
REP 1093202	QC	9	16	0.03	1142	0.004	2	0.32	0.004	0.15	0.2	3.33	1.2	0.8	0.24	1	4.4	<0.2			
1093260	Soil	15	27	0.19	292	0.008	3	1.11	0.003	0.09	0.2	0.06	2.1	0.4	<0.05	4	2.4	<0.2	N.A.	N.A.	N.A.
REP 1093260	QC	15	27	0.20	289	0.006	2	1.08	0.004	0.08	0.2	0.06	2.1	0.4	<0.05	4	2.1	<0.2			
1093282	Soil	8	10	0.02	106	0.002	3	0.31	0.004	0.06	<0.1	0.02	0.4	0.3	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.
REP 1093282	QC	8	10	0.02	105	0.002	2	0.32	0.004	0.06	<0.1	0.02	0.4	0.3	<0.05	2	1.1	<0.2			
1093291	Soil	7	17	0.11	380	0.005	1	0.50	0.005	0.05	0.1	0.05	0.6	0.3	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.
REP 1093291	QC	7	16	0.11	383	0.005	<1	0.52	0.005	0.05	0.1	0.04	0.6	0.3	<0.05	3	0.7	<0.2			

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000767.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba
	Unit	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm
	MDL	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1
Pulp Duplicates																					
1092920	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092920	QC																				
1092932	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092932	QC																				
1092957	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092957	QC																				
1092967	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092967	QC																				
1092992	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092992	QC																				
1092999	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092999	QC																				
1093032	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093032	QC																				
1093036	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093036	QC																				
1093047	Soil	82	0.2	25.1	5.8	350	1.45	7.5	1.2	<0.1	9	0.2	1.4	0.1	34	0.05	0.087	3	17	0.03	83
REP 1093047	QC	85	0.2	25.3	5.8	353	1.47	7.8	1.3	<0.1	9	0.2	1.4	0.2	36	0.05	0.083	3	17	0.03	83
1093058	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093058	QC																				
1093202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093202	QC																				
1093260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093260	QC																				
1093282	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093282	QC																				
1093291	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093291	QC																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000767.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates															
1092920	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092920	QC														
1092932	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092932	QC														
1092957	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092957	QC														
1092967	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092967	QC														
1092992	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092992	QC														
1092999	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092999	QC														
1093032	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093032	QC														
1093036	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093036	QC														
1093047	Soil		0.001	<20	0.47	0.013	0.05	<0.1	0.04	<0.1	0.1	0.07	2	1.0	<0.2
REP 1093047	QC		0.001	<20	0.48	0.014	0.04	<0.1	0.05	<0.1	0.1	0.06	2	0.7	<0.2
1093058	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093058	QC														
1093202	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093202	QC														
1093260	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093260	QC														
1093282	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093282	QC														
1093291	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093291	QC														

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000767.2

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1093315	Soil		5.1	24.7	18.0	111	<0.1	30.3	12.5	281	4.11	102.0	<0.5	0.6	4	0.1	2.5	0.6	27	0.02	0.067
REP 1093315	QC		5.0	24.6	18.1	108	<0.1	31.4	12.8	286	4.26	99.9	<0.5	0.6	5	0.1	2.5	0.6	26	0.02	0.068
1093334	Soil		1.8	24.2	20.6	93	0.5	22.5	5.2	52	2.22	18.2	1.7	1.6	27	0.2	0.8	0.2	15	0.31	0.071
REP 1093334	QC		2.3	24.7	20.8	93	0.5	23.6	5.2	53	2.25	18.1	3.6	1.7	27	0.3	0.7	0.2	17	0.32	0.071
1093337	Soil		1.3	14.6	13.5	61	0.7	14.4	1.9	71	1.23	17.9	8.7	0.6	42	0.3	2.0	0.2	13	0.75	0.061
REP 1093337	QC		1.3	13.9	13.7	60	0.6	14.8	1.8	72	1.26	17.9	6.5	0.5	44	0.3	2.1	0.2	16	0.76	0.063
1093362	Soil		31.0	29.2	10.0	101	0.3	47.6	4.2	85	1.32	15.0	1.5	0.4	11	1.2	3.6	0.1	82	0.09	0.092
REP 1093362	QC		31.7	29.1	10.2	101	0.3	49.4	4.3	86	1.33	15.1	1.5	0.4	12	1.1	3.6	0.1	81	0.09	0.090
1093397	Soil		6.8	52.6	21.9	76	0.4	44.3	10.1	138	2.59	11.6	1.1	0.3	11	0.1	2.7	0.2	42	0.01	0.055
REP 1093397	QC		7.2	53.2	22.3	74	0.4	43.9	10.2	140	2.65	11.4	1.2	0.3	10	0.1	2.6	0.3	43	0.01	0.055
Reference Materials																					
STD DS8	Standard		11.4	101.2	122.1	308	1.8	37.4	7.0	577	2.34	25.3	113.8	6.0	61	2.2	5.4	6.5	39	0.66	0.080
STD DS8	Standard		13.0	108.6	122.9	315	1.8	38.2	8.0	620	2.51	26.0	106.8	6.7	68	2.5	5.2	6.7	41	0.72	0.081
STD DS8	Standard		13.0	110.3	140.0	322	1.9	35.9	7.5	618	2.52	27.0	113.1	7.7	74	2.3	6.7	7.9	41	0.69	0.083
STD DS8	Standard		11.9	106.2	136.3	306	1.8	36.3	7.1	592	2.39	25.4	106.7	7.2	71	2.2	5.9	7.5	42	0.69	0.076
STD DS8	Standard		11.9	103.8	134.4	296	1.7	34.0	7.0	587	2.37	25.2	101.8	7.2	68	2.3	5.9	7.3	39	0.65	0.075
STD DS8	Standard		12.0	103.5	132.2	302	1.7	36.7	7.1	583	2.35	26.0	114.6	7.2	68	2.1	5.9	7.5	39	0.64	0.077
STD DS8	Standard		13.6	110.6	123.8	311	1.7	36.0	7.3	627	2.48	27.1	103.8	6.7	68	2.2	4.6	6.4	44	0.70	0.079
STD DS8	Standard		13.6	116.3	132.2	308	1.6	39.9	7.7	580	2.37	29.0	107.2	7.0	71	2.5	5.6	7.1	43	0.72	0.080
STD DS8	Standard		12.2	109.7	125.3	317	1.8	38.2	7.8	590	2.45	27.6	123.1	6.6	66	2.5	5.8	6.8	40	0.66	0.083
STD DS8	Standard		13.1	111.5	123.2	315	1.8	37.3	7.6	596	2.48	25.6	117.7	6.7	68	2.4	5.5	6.4	43	0.71	0.077
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08
STD OREAS45CA Expected																					
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000767.2

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1
1093315	Soil	4	9	0.04	115	0.003	<1	0.33	0.003	0.07	<0.1	0.03	1.9	0.1	<0.05	1	1.3	<0.2	N.A.	N.A.	N.A.
REP 1093315	QC	4	9	0.04	120	0.003	<1	0.34	0.003	0.08	<0.1	0.03	2.0	0.1	<0.05	1	1.4	<0.2			
1093334	Soil	2	14	0.05	303	<0.001	2	0.51	0.004	0.10	<0.1	0.14	4.4	0.1	0.11	2	2.2	<0.2	N.A.	N.A.	N.A.
REP 1093334	QC	2	14	0.05	315	<0.001	2	0.51	0.005	0.10	<0.1	0.12	4.1	0.1	0.11	2	3.2	<0.2			
1093337	Soil	3	12	0.02	500	<0.001	2	0.39	0.005	0.10	<0.1	0.27	1.7	0.2	0.19	1	1.4	<0.2	N.A.	N.A.	N.A.
REP 1093337	QC	3	13	0.02	521	0.001	2	0.41	0.005	0.11	<0.1	0.31	1.6	0.2	0.21	1	1.7	<0.2			
1093362	Soil	9	11	0.04	388	0.002	2	0.52	0.004	0.05	<0.1	0.23	0.7	0.5	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.
REP 1093362	QC	9	11	0.04	397	0.002	1	0.52	0.004	0.05	<0.1	0.23	0.9	0.5	<0.05	2	1.7	<0.2			
1093397	Soil	2	9	0.02	112	0.001	<1	0.30	0.005	0.04	<0.1	0.05	1.6	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.
REP 1093397	QC	2	9	0.01	112	0.001	<1	0.29	0.005	0.04	<0.1	0.04	1.8	0.1	<0.05	2	1.8	<0.2			
Reference Materials																					
STD DS8	Standard	13	111	0.59	251	0.101	2	0.86	0.082	0.40	2.9	0.20	1.9	5.4	0.13	5	5.8	4.9			
STD DS8	Standard	14	116	0.61	276	0.114	3	0.92	0.091	0.43	2.9	0.19	2.4	5.4	0.15	5	5.4	4.8			
STD DS8	Standard	14	118	0.62	275	0.123	3	0.89	0.086	0.42	2.9	0.23	2.1	5.7	0.14	5	5.6	5.2			
STD DS8	Standard	14	113	0.60	277	0.119	2	0.87	0.085	0.41	2.9	0.16	2.1	5.5	0.16	4	4.3	4.8			
STD DS8	Standard	13	114	0.59	253	0.105	3	0.83	0.082	0.39	2.6	0.18	1.9	5.2	0.14	4	4.6	4.8			
STD DS8	Standard	13	112	0.60	260	0.106	3	0.86	0.082	0.40	2.9	0.19	2.0	5.4	0.17	4	5.9	5.0			
STD DS8	Standard	15	118	0.58	275	0.115	2	0.90	0.092	0.42	3.0	0.18	2.2	5.4	0.14	5	6.1	5.8			
STD DS8	Standard	14	119	0.65	264	0.125	2	0.94	0.101	0.40	3.0	0.19	2.5	5.5	0.14	5	5.4	4.6			
STD DS8	Standard	13	113	0.60	291	0.113	1	0.88	0.090	0.43	3.1	0.21	2.0	5.4	0.13	4	4.7	5.2			
STD DS8	Standard	16	118	0.62	280	0.122	3	0.94	0.091	0.42	3.1	0.19	2.7	5.3	0.17	5	5.9	5.2			
STD DS8	Standard																		14.5	109.9	131.7
STD OREAS45CA	Standard																		0.8	496.7	21.1
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123
STD OREAS45CA Expected																			1	494	20
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000767.2

		1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1
1093315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093315	QC																				
1093334	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093334	QC																				
1093337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093337	QC																				
1093362	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093362	QC																				
1093397	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093397	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	314	2.2	37.8	7.7	617	2.46	24.9	130.9	7.8	77	2.4	5.0	7.1	42	0.68	0.078	17	117	0.66	311
STD OREAS45CA	Standard	59	0.3	235.8	85.1	893	16.13	3.5	44.8	7.4	17	<0.1	<0.1	0.2	197	0.41	0.038	16	637	0.16	161
STD DS8 Expected		312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279
STD OREAS45CA Expected		60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000767.2

		1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1093315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093315	QC													
1093334	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093334	QC													
1093337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093337	QC													
1093362	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093362	QC													
1093397	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093397	QC													
Reference Materials														
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard	0.117	<20	0.92	0.088	0.40	3.1	0.23	2.2	5.7	0.14	5	4.7	4.9
STD OREAS45CA	Standard	0.130	<20	3.81	0.013	0.07	<0.1	0.03	40.2	<0.1	<0.05	18	0.8	<0.2
STD DS8 Expected		0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected		0.128		3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank													
BLK	Blank													
BLK	Blank													
BLK	Blank													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000767.2

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000767.2

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2			
BLK	Blank																		<0.1	<0.1	<0.1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000767.2

		1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 01, 2011

QUALITY CONTROL REPORT WHI11000767.2

		1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank													
BLK	Blank													
BLK	Blank													
BLK	Blank													
BLK	Blank													
BLK	Blank													
BLK	Blank	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: July 28, 2011
Report Date: September 02, 2011
Page: 1 of 9

CERTIFICATE OF ANALYSIS WHI11000768.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #6
P.O. Number
Number of Samples: 224

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	214	Sieve soil to 230 mesh			WHI
1DX2	209	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	5	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: Includes 1DX1 analysis

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1093407	Soil	5.9	23.6	12.5	189	0.5	30.5	5.0	197	2.18	13.1	2.6	0.7	28	0.9	2.6	0.2	56	0.36	0.139	4
1093408	Soil	6.0	18.1	10.5	93	0.7	21.1	3.9	68	1.57	11.3	1.4	0.2	4	0.1	2.0	0.2	50	0.01	0.061	6
1093409	Soil	4.8	15.9	14.6	93	0.2	20.1	4.4	92	2.55	17.0	1.9	0.9	7	0.2	2.0	0.2	54	0.01	0.052	6
1093410	Soil	2.9	14.1	5.8	62	0.5	14.8	2.3	68	0.90	5.2	2.7	0.2	16	0.6	1.1	0.1	27	0.17	0.078	3
1093411	Soil	2.9	20.8	9.1	106	0.6	25.1	4.9	170	1.76	9.6	2.4	0.9	78	0.8	1.4	0.2	34	0.90	0.107	6
1093412	Soil	3.6	19.7	7.6	98	0.7	24.8	5.1	188	1.40	8.7	2.8	0.7	50	0.3	1.5	0.1	31	0.43	0.078	4
1093413	Soil	7.0	24.1	12.8	173	0.9	35.6	6.1	324	1.95	13.5	2.3	0.5	16	1.0	2.4	0.2	60	0.05	0.107	5
1093414	Soil	9.6	36.4	17.0	221	0.2	53.0	9.0	212	3.04	25.8	2.9	1.6	26	0.9	3.8	0.2	67	0.17	0.129	8
1093415	Soil	7.3	23.5	12.1	84	1.1	23.2	3.4	54	1.42	12.1	3.5	0.2	13	0.3	1.8	0.2	51	0.07	0.103	5
1093416	Soil	9.1	40.7	17.1	204	0.2	52.4	12.7	397	3.02	24.2	3.0	0.9	25	1.0	3.8	0.2	59	0.15	0.125	10
1093417	Soil	8.5	27.1	10.0	177	0.3	43.4	6.1	160	1.68	16.7	2.2	0.2	22	1.0	3.2	0.1	64	0.15	0.101	8
1093418	Soil	4.9	23.0	13.7	143	0.6	25.5	6.1	433	1.93	12.8	1.5	0.6	21	1.1	1.7	0.2	49	0.35	0.163	9
1093419	Soil	11.4	48.3	20.8	301	0.8	60.7	10.4	315	2.74	23.8	3.8	1.5	40	2.4	4.7	0.2	60	0.75	0.215	13
1093420	Soil	1.9	6.3	3.9	16	<0.1	4.7	1.2	13	0.39	2.4	1.3	<0.1	4	0.1	0.4	<0.1	18	0.02	0.070	4
1093421	Soil	2.7	12.7	11.2	35	<0.1	7.9	1.9	34	0.81	6.6	0.6	0.1	11	0.2	0.8	0.2	32	0.03	0.058	9
1093422	Soil	1.9	8.1	7.6	59	0.1	10.3	3.0	227	1.59	8.8	2.3	0.2	8	0.3	1.3	<0.1	26	0.20	0.053	5
1093423	Soil	3.3	20.6	11.4	118	0.8	19.2	3.6	96	1.27	8.7	<0.5	0.2	17	0.7	1.6	0.1	34	0.22	0.107	7
1093424	Soil	4.1	48.3	9.7	72	0.2	17.7	4.9	52	1.62	9.6	0.8	<0.1	3	<0.1	1.4	0.1	33	0.01	0.064	5
1093425	Soil	1.5	6.6	4.1	30	<0.1	4.1	0.9	22	0.46	3.7	<0.5	<0.1	4	<0.1	0.4	0.1	22	0.02	0.063	6
1093426	Soil	4.7	16.3	7.8	62	0.6	17.5	2.5	23	0.69	6.6	0.7	0.2	12	0.7	1.2	<0.1	41	0.09	0.049	7
1093427	Soil	1.7	21.8	3.3	51	0.8	17.8	1.1	19	0.38	2.6	<0.5	<0.1	24	1.7	0.7	<0.1	10	0.38	0.062	4
1093428	Soil	4.0	14.0	3.1	40	0.6	9.1	1.2	14	0.42	4.1	1.0	<0.1	12	0.7	0.6	<0.1	23	0.14	0.035	7
1093429	Soil	16.5	29.6	6.0	254	0.3	68.6	5.4	143	1.05	9.3	1.3	0.4	68	1.4	1.6	<0.1	42	1.53	0.125	6
1093430	Soil	14.4	26.6	5.7	240	0.2	77.9	9.2	175	1.71	11.4	2.7	0.7	70	1.1	2.5	<0.1	88	1.72	0.135	11
1093431	Soil	34.7	73.7	12.2	712	0.9	222.5	26.4	423	4.28	36.8	1.0	2.9	78	6.3	11.2	0.1	475	1.39	0.236	33
1093432	Soil	32.9	85.1	9.9	709	1.0	157.4	12.2	455	2.59	42.3	1.3	0.8	167	11.8	12.8	<0.1	517	4.65	0.115	14
1093433	Soil	36.0	25.2	6.7	328	0.2	70.5	3.6	28	0.96	21.9	1.5	0.2	22	2.2	10.0	0.1	471	0.46	0.038	10
1093434	Soil	7.6	43.4	8.3	175	<0.1	179.1	33.0	388	5.27	21.7	<0.5	2.1	39	0.9	1.9	<0.1	106	0.48	0.186	18
1093435	Soil	3.8	28.9	4.8	104	<0.1	125.0	29.8	600	3.88	14.6	<0.5	1.6	26	0.5	0.9	<0.1	56	0.30	0.143	20
1093436	Soil	3.2	24.1	5.1	101	0.1	103.0	21.4	478	3.28	8.4	0.8	0.6	25	0.8	0.8	<0.1	33	0.34	0.204	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1093407	Soil	14	0.10	1224	0.003	2	0.77	0.007	0.04	<0.1	0.13	1.5	0.1	0.07	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1093408	Soil	8	0.03	142	0.002	2	0.43	0.003	0.04	<0.1	0.02	0.3	0.1	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093409	Soil	12	0.07	120	0.003	3	0.69	0.003	0.04	<0.1	0.03	1.1	0.1	<0.05	4	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093410	Soil	7	0.05	1404	0.003	1	0.46	0.011	0.04	<0.1	0.09	0.7	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093411	Soil	15	0.22	1333	0.004	2	0.77	0.009	0.04	<0.1	0.18	1.9	0.1	0.11	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093412	Soil	10	0.12	763	0.003	3	0.68	0.011	0.04	<0.1	0.13	1.6	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093413	Soil	18	0.10	497	0.002	2	0.78	0.007	0.06	0.1	0.36	1.4	0.3	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1093414	Soil	21	0.19	367	0.002	1	0.78	0.003	0.05	0.1	0.06	2.0	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1093415	Soil	14	0.05	292	0.002	<1	0.62	0.005	0.05	0.1	0.26	0.5	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093416	Soil	17	0.16	330	0.004	1	0.74	0.003	0.04	0.1	0.08	1.6	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1093417	Soil	16	0.08	527	0.003	1	0.54	0.010	0.05	0.1	0.13	0.6	0.3	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1093418	Soil	18	0.11	905	0.004	3	0.88	0.009	0.04	0.2	0.21	1.6	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093419	Soil	22	0.14	1268	0.004	3	0.58	0.005	0.06	<0.1	0.26	3.5	0.2	0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093420	Soil	7	0.02	124	0.002	<1	0.26	0.009	0.02	<0.1	0.02	0.1	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093421	Soil	9	0.02	137	0.004	<1	0.51	0.002	0.03	<0.1	0.01	0.2	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093422	Soil	7	0.06	151	0.004	1	0.52	0.013	0.02	<0.1	0.03	0.7	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093423	Soil	11	0.05	768	0.004	2	0.93	0.014	0.03	<0.1	0.20	0.7	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093424	Soil	6	0.02	77	0.001	2	0.33	0.002	0.05	<0.1	0.02	0.2	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093425	Soil	4	0.02	53	0.002	<1	0.26	0.006	0.03	<0.1	<0.01	<0.1	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093426	Soil	11	0.02	326	0.004	<1	0.33	0.007	0.04	<0.1	0.05	0.4	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093427	Soil	4	0.03	465	0.004	<1	0.25	0.021	0.02	<0.1	0.12	0.5	<0.1	0.07	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093428	Soil	7	0.02	133	0.004	<1	0.22	0.006	0.03	<0.1	0.04	0.2	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093429	Soil	15	0.18	599	0.006	4	0.57	0.013	0.04	<0.1	0.13	1.3	0.4	0.13	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1093430	Soil	35	0.26	1525	0.009	6	0.72	0.012	0.05	0.2	0.07	2.4	0.5	0.13	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093431	Soil	89	0.31	2368	0.005	8	0.99	0.006	0.13	0.2	0.33	6.8	1.0	0.05	3	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093432	Soil	53	1.96	1411	0.004	3	0.69	0.017	0.07	0.2	0.40	2.5	0.9	0.08	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093433	Soil	27	0.07	341	0.004	1	0.52	0.010	0.05	0.2	0.06	0.5	1.0	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093434	Soil	98	0.23	1432	0.005	3	0.89	0.009	0.06	0.2	0.06	7.6	0.2	0.11	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093435	Soil	58	0.09	2312	0.005	4	0.60	0.015	0.04	<0.1	0.04	6.4	<0.1	0.06	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093436	Soil	34	0.06	1585	0.004	<1	0.68	0.013	0.04	0.1	0.04	1.9	<0.1	0.10	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1093407	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093408	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093409	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093410	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093411	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093412	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093413	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093414	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093415	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093416	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093417	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093418	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093419	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093420	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093421	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093422	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093423	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093424	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093425	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093426	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093427	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093428	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093429	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093430	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093431	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093432	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093433	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093434	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093435	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093436	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093407	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093408	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093409	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093410	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093411	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093412	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093413	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093414	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093415	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093416	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093417	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093418	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093419	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093420	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093421	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093422	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093423	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093424	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093425	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093426	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093427	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093428	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093429	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093430	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093431	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093432	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093433	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093434	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093435	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093436	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1093437	Soil		5.0	37.5	7.2	134	0.1	163.7	26.1	558	4.57	18.2	<0.5	0.8	28	0.6	1.1	<0.1	50	0.35	0.276	15
1093438	Soil		7.4	51.3	9.7	175	<0.1	234.5	47.2	998	6.32	16.1	<0.5	2.2	33	0.6	1.6	<0.1	68	0.54	0.273	22
1093439	Soil		6.2	42.7	8.0	174	0.2	182.1	31.5	734	4.52	11.6	<0.5	1.2	40	1.4	1.7	<0.1	68	0.76	0.269	17
1093440	Soil		8.8	63.2	10.6	202	0.1	244.5	47.6	935	7.46	13.1	<0.5	1.8	29	0.7	2.2	0.1	87	0.46	0.324	23
1093441	Soil		7.5	88.1	14.1	201	0.2	346.1	68.9	1089	8.16	14.9	1.5	4.9	50	1.1	2.0	<0.1	106	0.88	0.319	48
1093442	Soil		12.0	89.8	15.8	253	0.3	365.9	66.8	1184	8.66	23.5	<0.5	4.7	54	1.9	3.4	<0.1	108	0.80	0.341	47
1093443	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093444	Soil		4.2	70.3	26.5	119	1.9	156.8	18.0	1484	7.55	125.3	51.4	2.0	61	0.5	13.7	0.4	85	0.42	0.137	7
1093445	Soil		6.1	60.7	13.7	222	0.9	193.7	26.8	843	5.37	57.6	12.0	1.7	27	0.8	14.0	0.2	71	0.15	0.070	8
1093446	Soil		6.1	78.0	35.3	191	1.2	146.7	16.8	408	4.65	80.0	12.8	1.8	25	0.5	10.6	0.3	102	0.05	0.080	8
1093447	Soil		7.1	172.5	68.3	235	3.8	205.8	15.3	281	5.59	130.5	40.0	2.0	35	0.8	18.2	0.3	128	0.05	0.109	7
1093448	Soil		4.3	54.0	14.5	72	1.1	44.9	4.7	116	2.20	33.8	8.4	<0.1	44	0.2	6.3	0.2	72	0.04	0.082	5
1093449	Soil		13.4	113.9	20.3	113	4.4	55.2	8.1	177	3.77	87.5	21.6	0.9	286	0.7	21.9	0.3	137	0.08	0.181	4
1093450	Soil		10.6	104.7	18.5	70	2.0	45.6	8.5	128	3.38	48.0	7.2	0.9	151	0.2	12.4	0.5	120	0.05	0.198	2
1093451	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093452	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093453	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093454	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093455	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093456	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093457	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093458	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093459	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093460	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1094051	Soil		122.8	210.2	35.4	3961	4.1	351.7	7.4	292	1.95	106.1	0.7	2.2	170	38.7	47.6	0.2	852	3.31	0.180	13
1094052	Soil		102.8	222.4	23.7	3583	4.2	344.8	6.5	174	1.91	96.8	2.6	1.5	240	36.4	50.0	0.2	1073	2.46	0.338	14
1094053	Soil		13.2	15.5	8.0	98	0.2	20.6	2.1	35	0.84	15.2	<0.5	<0.1	9	0.4	3.6	0.2	112	0.03	0.044	8
1094054	Soil		76.3	65.2	56.9	723	3.5	123.4	8.2	164	5.42	150.6	14.6	1.7	74	3.0	32.3	0.4	267	0.12	0.223	9
1094055	Soil		16.5	43.8	17.4	308	0.3	51.6	5.8	85	3.11	33.9	<0.5	0.1	21	0.6	6.8	0.3	113	0.01	0.072	6
1094056	Soil		19.1	27.8	21.9	160	0.8	36.6	4.0	149	2.37	28.8	12.7	0.6	44	0.5	6.3	0.3	103	0.03	0.129	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1093437	Soil	57	0.09	2569	0.003	2	0.67	0.007	0.07	0.1	0.04	2.4	0.1	0.10	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093438	Soil	70	0.11	5522	0.004	2	0.86	0.007	0.06	0.1	0.03	6.9	0.1	0.09	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093439	Soil	54	0.14	3264	0.004	2	0.83	0.010	0.05	0.1	0.04	3.6	0.1	0.13	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093440	Soil	67	0.12	3503	0.004	1	0.82	0.006	0.05	0.1	0.05	5.3	0.2	0.08	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093441	Soil	101	0.21	6527	0.004	4	1.05	0.005	0.07	0.1	0.06	14.9	0.2	0.08	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1093442	Soil	89	0.21	4927	0.004	<1	0.86	0.004	0.08	0.2	0.09	14.6	0.2	0.07	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093443	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.2	42.1	19.0	150
1093444	Soil	31	0.17	1002	0.005	3	0.70	0.005	0.09	0.1	0.61	5.3	0.3	0.09	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093445	Soil	28	0.22	373	0.010	<1	0.92	0.003	0.04	0.2	0.44	3.7	0.2	<0.05	3	6.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093446	Soil	26	0.16	192	0.014	2	0.88	0.003	0.07	0.2	0.17	2.8	0.3	<0.05	4	7.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093447	Soil	25	0.14	160	0.013	<1	0.92	0.004	0.04	0.2	0.67	4.3	0.2	<0.05	3	15.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093448	Soil	14	0.05	259	0.005	1	0.72	0.009	0.04	0.1	0.11	0.4	0.4	0.07	3	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1093449	Soil	29	0.05	851	0.004	2	0.60	0.003	0.15	0.1	0.71	3.2	1.0	0.33	2	12.2	0.3	N.A.	N.A.	N.A.	N.A.
1093450	Soil	30	0.03	881	0.003	3	0.49	0.005	0.19	<0.1	0.19	7.9	0.6	0.37	2	9.3	0.4	N.A.	N.A.	N.A.	N.A.
1093451	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093452	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093453	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093454	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093455	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093456	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093457	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093458	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093459	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093460	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1094051	Soil	41	1.41	680	0.006	6	0.51	0.006	0.11	0.5	0.80	4.1	4.3	0.09	2	8.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094052	Soil	68	0.86	1214	0.008	11	0.70	0.006	0.16	0.4	0.82	4.2	4.0	0.08	3	13.8	0.3	N.A.	N.A.	N.A.	N.A.
1094053	Soil	10	0.02	144	0.004	<1	0.45	0.005	0.04	0.1	0.04	0.1	0.5	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094054	Soil	24	0.09	615	0.004	2	0.72	0.010	0.12	0.4	9.76	2.0	3.0	0.27	2	10.3	0.6	N.A.	N.A.	N.A.	N.A.
1094055	Soil	14	0.03	2719	0.005	<1	0.55	0.002	0.05	0.2	0.07	0.5	0.6	0.06	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094056	Soil	21	0.05	2497	0.003	2	0.91	0.003	0.09	0.1	0.93	1.7	0.8	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1093437	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093438	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093439	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093440	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093441	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093442	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093443	Soil		0.7	131.5	11.2	576	5.05	60.4	4.8	0.3	28	0.2	4.0	0.3	97	0.11	0.105	6	24	0.07	275	0.003
1093444	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093445	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093446	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093447	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093448	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093449	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093450	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093451	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093452	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093453	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093454	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093455	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093456	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093457	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093458	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093459	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093460	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1094051	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094052	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094053	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094054	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094055	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094056	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093437	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093438	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093439	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093440	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093441	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093442	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093443	Soil	<20	0.50	0.003	0.09	<0.1	0.16	1.9	0.3	0.07	3	3.3	<0.2
1093444	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093445	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093446	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093447	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093448	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093449	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093450	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093451	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093452	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093453	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093454	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093455	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093456	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093457	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093458	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093459	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1093460	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1094051	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094052	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094053	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094054	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094055	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094056	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094057	Soil		10.8	14.3	9.7	62	0.6	15.3	1.4	25	0.75	9.7	0.9	<0.1	12	0.2	2.0	<0.1	59	0.03	0.064	5
1094058	Soil		41.7	25.8	10.3	217	0.4	66.4	4.6	37	1.36	20.5	<0.5	<0.1	8	0.2	5.8	0.1	184	<0.01	0.039	9
1094059	Soil		57.0	96.7	29.9	551	1.6	139.7	13.9	511	2.91	45.1	3.6	2.0	36	5.0	10.5	0.2	169	0.21	0.190	13
1094060	Soil		7.8	37.6	8.4	78	1.1	27.8	2.5	60	1.46	19.8	4.3	<0.1	28	0.4	3.3	0.1	69	0.17	0.069	2
1094061	Soil		18.2	63.4	12.8	152	1.3	45.5	4.1	77	4.53	34.8	10.5	0.7	54	0.6	7.3	0.2	123	0.01	0.129	2
1094062	Soil		5.4	13.2	7.1	40	0.8	11.8	1.4	21	0.74	9.7	1.2	0.1	20	<0.1	1.7	0.1	82	<0.01	0.042	3
1094063	Soil		5.7	17.0	7.8	61	0.5	18.1	1.9	37	0.70	7.6	1.2	<0.1	20	0.2	1.9	0.1	73	0.02	0.057	3
1094064	Soil		4.6	17.7	9.6	36	0.6	11.4	1.3	26	1.09	7.2	2.5	<0.1	35	<0.1	1.7	0.2	86	0.02	0.086	3
1094065	Soil		8.0	34.4	8.7	52	0.5	18.7	1.8	22	1.25	8.8	1.4	0.3	43	<0.1	2.4	0.1	72	0.01	0.067	2
1094066	Soil		10.4	67.3	11.8	108	1.0	45.9	4.7	77	2.62	22.2	5.8	0.3	83	0.4	5.1	0.2	93	0.07	0.121	6
1094067	Soil		5.1	54.4	12.0	103	0.9	43.7	5.9	126	2.31	23.5	9.3	0.6	43	0.6	4.1	0.2	73	0.10	0.076	11
1094068	Soil		4.1	67.7	10.5	98	0.9	39.5	7.9	209	2.17	21.6	7.8	0.5	29	0.5	2.7	0.2	63	0.11	0.086	11
1094069	Soil		2.7	33.4	9.8	35	0.6	19.8	1.8	45	1.12	21.4	19.1	<0.1	27	0.2	3.0	0.1	33	0.03	0.070	4
1094070	Soil		5.0	69.8	14.6	82	1.7	48.5	7.2	339	2.27	32.5	28.9	0.5	47	0.3	5.0	0.2	68	0.11	0.133	6
1094071	Soil		6.3	21.3	10.9	31	1.3	12.7	1.5	28	0.92	12.1	2.6	<0.1	46	<0.1	3.5	0.2	86	0.01	0.060	3
1094072	Soil		7.5	43.3	11.4	32	1.5	8.6	1.0	20	1.28	10.6	3.6	0.5	84	0.3	2.4	0.2	86	0.05	0.126	5
1094073	Soil		3.9	10.9	5.7	30	0.7	8.5	1.3	17	0.49	5.8	0.5	<0.1	13	<0.1	1.4	<0.1	59	<0.01	0.032	4
1094074	Soil		8.7	55.5	8.5	59	0.9	20.7	2.3	72	1.21	10.0	1.6	0.4	59	0.6	2.6	0.1	75	0.19	0.100	2
1094075	Soil		27.0	37.3	20.3	69	3.0	28.9	1.7	31	1.82	31.5	2.5	0.4	120	0.8	9.3	0.3	159	0.25	0.101	11
1094076	Soil		16.6	28.0	13.8	61	1.2	15.2	1.5	14	1.21	49.0	47.7	0.1	51	0.2	9.7	0.2	113	0.01	0.088	5
1094077	Soil		10.0	14.5	7.4	63	0.8	18.3	1.7	22	0.72	9.7	<0.5	0.2	20	<0.1	2.4	<0.1	109	0.02	0.085	5
1094078	Soil		22.3	23.6	22.3	120	0.5	28.2	3.5	37	1.49	38.2	2.2	<0.1	44	0.3	4.7	0.2	216	0.02	0.068	8
1094079	Soil		8.4	20.9	11.2	83	0.5	19.2	2.2	33	0.98	10.1	<0.5	0.1	21	0.2	2.3	0.2	63	0.01	0.072	6
1094080	Soil		11.1	21.3	8.5	93	0.2	21.6	4.2	47	1.33	11.6	<0.5	0.2	9	<0.1	2.2	0.2	89	0.01	0.065	10
1094081	Soil		6.9	16.1	10.5	65	0.3	16.6	2.0	30	1.00	9.3	1.6	0.2	20	0.1	2.3	0.2	98	0.01	0.063	5
1094082	Soil		4.2	9.0	6.5	46	0.2	10.5	1.6	26	0.64	5.6	<0.5	0.1	8	<0.1	1.1	<0.1	40	<0.01	0.026	6
1094083	Soil		10.7	11.6	7.4	165	0.2	17.2	2.0	24	1.04	13.3	<0.5	0.1	6	<0.1	4.2	0.2	86	0.02	0.053	4
1094084	Soil		18.9	17.2	7.3	131	0.9	26.2	3.6	38	1.18	13.4	<0.5	0.1	6	0.1	4.0	0.2	138	<0.01	0.040	12
1094085	Soil		17.1	24.5	15.6	218	0.6	42.3	4.1	57	1.99	24.5	0.7	0.4	14	0.4	5.7	0.2	152	0.02	0.115	10
1094086	Soil		11.5	28.0	27.0	173	4.5	34.4	2.2	177	1.45	26.5	11.9	0.2	65	3.3	4.6	0.3	132	0.25	0.214	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094057	Soil	9	0.03	261	0.003	1	0.40	0.012	0.03	<0.1	0.12	0.2	0.4	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094058	Soil	13	0.02	111	0.004	2	0.28	0.003	0.05	0.2	0.05	0.2	0.5	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094059	Soil	20	0.05	565	0.003	3	0.49	0.002	0.07	0.3	1.98	3.9	1.2	<0.05	1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094060	Soil	11	0.02	278	0.002	2	0.39	0.008	0.06	<0.1	0.27	0.8	0.4	<0.05	1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094061	Soil	20	0.02	746	0.002	3	0.47	0.002	0.08	<0.1	0.49	2.1	0.6	0.10	2	5.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094062	Soil	9	0.01	247	0.002	2	0.26	0.003	0.05	<0.1	0.04	0.4	0.3	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094063	Soil	11	0.01	248	0.002	2	0.27	0.003	0.05	<0.1	0.08	0.5	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094064	Soil	15	0.02	295	0.002	2	0.47	0.003	0.05	<0.1	0.08	0.4	0.3	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094065	Soil	14	0.01	347	0.002	2	0.32	0.002	0.05	<0.1	0.10	0.9	0.4	0.07	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094066	Soil	22	0.08	416	0.006	3	0.73	0.003	0.07	0.1	0.86	1.4	0.6	0.11	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094067	Soil	21	0.18	272	0.017	2	0.83	0.004	0.06	0.2	2.20	1.4	0.3	<0.05	3	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094068	Soil	22	0.25	217	0.018	1	1.13	0.007	0.05	0.2	2.71	1.6	0.3	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094069	Soil	8	0.03	101	0.003	2	0.64	0.013	0.04	<0.1	0.32	0.3	0.2	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094070	Soil	17	0.11	150	0.012	3	0.86	0.012	0.06	0.2	0.50	1.6	0.5	<0.05	3	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094071	Soil	15	0.01	365	0.002	2	0.30	0.004	0.06	<0.1	0.10	0.3	0.3	0.06	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094072	Soil	21	0.03	1352	0.002	2	0.48	0.002	0.07	<0.1	0.30	1.7	0.5	0.10	1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094073	Soil	10	<0.01	220	0.003	2	0.30	0.003	0.03	<0.1	0.02	0.3	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094074	Soil	17	0.02	1143	0.001	2	0.33	0.002	0.07	<0.1	0.23	2.0	0.4	0.10	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094075	Soil	20	0.03	1178	0.003	4	0.32	0.005	0.13	0.2	0.52	0.8	2.3	0.31	2	7.5	0.2	N.A.	N.A.	N.A.	N.A.
1094076	Soil	14	0.01	981	0.001	3	0.46	0.005	0.08	0.2	5.28	0.3	1.7	0.19	2	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094077	Soil	14	0.02	229	0.005	4	0.36	0.008	0.04	0.1	0.21	0.8	0.6	0.06	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094078	Soil	14	0.02	431	0.003	2	0.40	0.003	0.07	0.1	0.23	0.3	1.4	0.07	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094079	Soil	11	0.02	166	0.003	2	0.34	0.012	0.05	0.1	0.04	0.3	0.3	0.06	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094080	Soil	10	0.03	93	0.002	2	0.41	0.003	0.05	<0.1	0.02	0.3	0.3	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094081	Soil	12	0.03	194	0.002	1	0.48	0.004	0.04	<0.1	0.03	0.3	0.3	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094082	Soil	7	0.02	60	0.004	<1	0.19	0.010	0.04	<0.1	<0.01	0.2	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094083	Soil	8	0.04	59	0.002	3	0.33	0.003	0.04	0.1	0.02	0.4	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094084	Soil	10	0.02	78	0.003	4	0.32	0.004	0.07	0.1	0.03	0.3	0.4	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094085	Soil	15	0.04	132	0.003	3	0.42	0.006	0.06	0.1	0.08	0.5	0.6	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094086	Soil	20	0.07	1587	0.002	4	0.99	0.013	0.09	0.1	2.41	0.8	1.2	0.13	4	3.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094058	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094062	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094063	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094071	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094075	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094081	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094085	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094058	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094062	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094063	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094071	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094075	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094081	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094085	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094087	Soil	13.2	18.9	10.5	121	0.6	25.8	2.9	52	1.21	15.6	<0.5	0.2	10	0.2	3.4	0.1	107	0.01	0.070	8
1094088	Soil	25.5	32.1	18.8	250	0.3	47.5	5.2	65	2.06	29.6	<0.5	0.3	15	0.3	8.7	0.3	250	0.01	0.077	12
1094089	Soil	16.4	20.3	9.4	129	<0.1	24.9	4.1	48	1.43	19.3	<0.5	0.4	8	0.2	3.4	0.2	145	<0.01	0.035	15
1094090	Soil	3.8	104.0	9.1	153	0.1	330.8	73.6	764	6.59	42.4	0.6	8.4	72	0.5	1.7	<0.1	68	2.10	0.304	109
1094091	Soil	4.9	88.4	12.8	104	0.2	343.7	67.3	1089	7.08	47.9	0.5	5.6	55	0.4	2.2	<0.1	62	1.93	0.237	98
1094092	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094093	Soil	11.8	59.8	10.9	182	0.2	201.4	39.7	827	5.09	21.9	1.1	2.6	26	1.5	2.6	<0.1	96	0.29	0.216	53
1094094	Soil	29.7	73.5	14.6	617	0.3	203.3	19.8	316	4.48	37.7	<0.5	1.1	77	2.3	10.5	0.2	161	0.77	0.439	32
1094095	Soil	63.6	56.9	17.7	673	0.2	165.7	9.1	126	2.64	42.9	0.6	0.7	18	3.6	11.1	0.2	342	0.24	0.106	19
1094096	Soil	50.9	32.4	12.7	254	<0.1	100.4	5.8	132	2.02	21.4	<0.5	0.3	10	0.5	3.7	0.1	129	0.06	0.096	10
1094097	Soil	60.9	44.5	13.4	255	<0.1	123.5	6.6	81	2.20	23.9	0.9	0.7	8	1.3	3.8	0.1	90	0.03	0.107	10
1094098	Soil	33.8	19.2	7.6	103	<0.1	59.0	3.7	74	1.19	11.4	<0.5	0.3	9	0.4	1.8	<0.1	38	0.10	0.088	5
1094099	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094100	Soil	28.6	50.5	19.8	272	0.5	80.7	10.6	262	3.57	29.3	2.6	0.8	15	0.8	6.1	0.2	107	0.04	0.157	14
1094101	Soil	6.2	35.8	21.6	84	1.6	49.2	18.9	1034	5.71	20.1	3.9	4.2	14	0.5	2.6	0.2	35	0.04	0.135	25
1094102	Soil	6.4	76.8	32.5	246	1.1	56.5	11.0	146	3.62	20.0	4.0	1.0	86	0.4	3.3	0.4	33	0.08	0.298	15
1094103	Soil	15.6	28.0	15.1	163	0.3	48.1	6.7	137	2.44	21.8	0.6	0.5	13	0.5	4.0	0.2	63	0.04	0.125	6
1094104	Soil	19.8	50.7	35.7	215	0.4	74.2	18.4	458	4.56	16.6	3.0	2.3	12	0.3	2.6	0.4	16	0.10	0.065	19
1094105	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094106	Soil	15.7	30.3	11.1	121	0.4	41.7	6.8	336	2.13	15.7	<0.5	0.1	7	0.2	3.3	0.2	78	0.01	0.057	13
1094107	Soil	14.5	17.9	8.1	135	<0.1	32.3	4.3	52	1.28	15.2	<0.5	0.1	4	0.1	2.4	0.1	61	0.01	0.046	9
1094108	Soil	9.6	20.5	17.5	140	0.3	40.7	4.5	94	1.43	17.7	<0.5	0.2	15	<0.1	2.3	0.2	47	0.02	0.064	9
1094109	Soil	6.7	93.5	25.6	426	0.5	126.8	30.3	1464	7.01	407.1	40.1	2.4	22	2.0	5.2	0.5	25	<0.01	0.150	32
1094110	Soil	2.1	41.8	15.0	123	0.3	41.9	10.9	284	2.90	401.0	21.8	1.7	58	0.1	3.9	0.4	16	0.03	0.076	10
1094111	Soil	9.3	32.7	24.4	167	0.1	55.0	12.1	200	3.16	215.6	1.8	0.8	9	<0.1	3.7	0.3	23	<0.01	0.083	12
1094112	Soil	5.9	19.8	20.2	101	0.5	29.8	4.7	70	1.41	17.7	<0.5	0.1	24	0.2	1.7	0.2	36	0.04	0.109	8
1094113	Soil	9.2	35.9	39.1	148	0.6	42.8	7.0	171	2.70	22.7	0.5	0.9	57	0.6	3.1	0.3	78	0.22	0.349	16
1094114	Soil	13.6	53.3	41.0	226	0.7	66.6	9.0	163	3.22	32.7	<0.5	0.6	71	0.5	4.2	0.4	94	0.06	0.282	17
1094115	Soil	1.2	4.9	5.8	16	0.3	5.1	0.9	13	0.33	2.3	<0.5	<0.1	8	<0.1	0.5	<0.1	11	0.03	0.041	2
1094116	Soil	11.6	34.0	26.9	137	0.4	46.2	6.6	88	2.11	19.7	1.4	0.2	39	0.3	3.6	0.4	109	0.03	0.079	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094087	Soil	9	0.03	114	0.003	2	0.34	0.007	0.05	<0.1	0.08	0.3	0.4	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094088	Soil	15	0.04	128	0.002	2	0.44	0.003	0.07	0.2	0.04	0.5	0.7	<0.05	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094089	Soil	11	0.03	86	0.004	3	0.41	0.004	0.06	0.1	0.02	0.5	0.5	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094090	Soil	116	0.49	2935	0.004	12	1.18	0.005	0.22	<0.1	0.06	17.7	<0.1	0.13	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094091	Soil	92	0.36	3313	0.005	11	0.95	0.007	0.18	0.1	0.05	15.0	<0.1	0.13	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094092	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.7	73.5	10.0	88
1094093	Soil	79	0.21	2247	0.010	5	0.96	0.013	0.14	0.2	0.03	7.4	0.3	0.11	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094094	Soil	67	0.14	1096	0.005	5	0.81	0.008	0.12	0.2	0.07	2.0	1.0	0.09	3	9.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094095	Soil	41	0.14	718	0.004	3	0.75	0.004	0.11	0.2	0.09	1.4	1.6	<0.05	2	6.3	0.2	N.A.	N.A.	N.A.	N.A.
1094096	Soil	21	0.14	293	0.003	3	0.71	0.006	0.09	0.3	0.03	0.6	1.4	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094097	Soil	18	0.16	335	0.003	3	0.59	0.003	0.07	0.2	0.05	1.4	1.8	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094098	Soil	9	0.05	179	0.002	2	0.32	0.013	0.05	<0.1	0.03	0.4	0.7	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094099	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	37.5	26.6	11.2	258
1094100	Soil	16	0.06	510	0.004	3	0.60	0.005	0.07	0.1	0.22	0.9	0.5	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094101	Soil	16	0.06	2668	0.003	2	1.50	0.002	0.06	<0.1	0.39	6.9	0.2	<0.05	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094102	Soil	12	0.03	1403	0.003	2	1.13	0.004	0.11	<0.1	0.13	1.0	0.2	0.13	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094103	Soil	10	0.04	489	0.004	2	0.70	0.012	0.06	<0.1	0.05	0.5	0.4	0.09	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094104	Soil	9	0.10	739	0.002	3	0.55	0.003	0.14	<0.1	0.09	3.2	0.2	<0.05	1	0.9	<0.2	18.9	51.5	37.2	223
1094105	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	N.A.	N.A.	N.A.	N.A.
1094106	Soil	10	0.03	118	0.004	2	0.28	0.010	0.07	0.2	0.02	0.3	0.3	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094107	Soil	8	0.02	73	0.010	2	0.28	0.008	0.06	0.1	<0.01	0.1	0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094108	Soil	9	0.02	115	0.004	3	0.37	0.011	0.07	0.1	<0.01	0.2	0.2	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094109	Soil	8	0.04	151	0.003	2	0.39	0.004	0.07	<0.1	0.22	5.5	0.2	<0.05	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094110	Soil	9	0.03	123	0.003	2	0.39	0.004	0.10	<0.1	0.02	2.4	0.1	<0.05	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094111	Soil	6	0.03	119	0.002	2	0.39	0.005	0.09	<0.1	0.01	1.2	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094112	Soil	10	0.03	167	0.004	2	0.30	0.012	0.07	<0.1	0.03	0.2	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094113	Soil	21	0.08	413	0.008	3	0.67	0.005	0.12	0.2	0.06	0.6	0.3	0.08	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094114	Soil	17	0.03	398	0.004	2	0.44	0.004	0.12	0.1	0.04	1.2	0.3	0.10	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094115	Soil	4	0.01	61	0.003	3	0.12	0.020	0.03	<0.1	0.02	0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094116	Soil	18	0.04	314	0.007	6	0.40	0.007	0.10	0.2	0.04	0.8	0.3	0.09	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094087	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094088	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094089	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094090	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094091	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094092	Soil		0.1	282.8	58.3	1000	6.26	36.2	2.2	5.3	57	0.5	1.0	<0.1	66	1.86	0.295	96	100	0.32	2339	0.003
1094093	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094094	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094095	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094096	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094097	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094098	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094099	Soil		0.1	75.8	5.6	230	1.75	19.8	2.3	<0.1	12	1.0	3.5	0.1	89	0.08	0.083	7	14	0.05	310	0.001
1094100	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094101	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094102	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094103	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094104	Soil		0.4	73.5	18.9	490	4.89	17.2	5.0	1.8	15	0.3	2.6	0.4	16	0.09	0.069	19	10	0.10	799	0.002
1094105	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094106	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094107	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094108	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094109	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094110	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094111	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094112	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094113	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094114	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094115	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094116	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094087	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094092	Soil	<20	1.04	0.006	0.16	<0.1	0.06	15.6	0.1	0.11	3	<0.5	<0.2
1094093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094099	Soil	<20	0.35	0.008	0.07	<0.1	0.03	<0.1	0.6	<0.05	1	2.2	<0.2
1094100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094104	Soil	<20	0.62	<0.001	0.17	<0.1	0.11	3.2	0.3	<0.05	1	1.3	<0.2
1094105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094117	Soil	6.2	16.1	9.0	54	0.2	21.9	3.8	50	1.08	9.2	<0.5	0.1	6	<0.1	1.4	0.1	52	0.01	0.034	6
1094118	Soil	14.1	34.6	19.3	103	0.1	34.5	6.0	60	1.63	14.2	0.9	0.2	7	<0.1	2.4	0.2	84	<0.01	0.042	12
1094119	Soil	5.1	43.6	20.4	92	0.5	54.5	13.2	350	3.30	17.0	1.6	0.9	9	0.1	2.4	0.4	20	0.02	0.108	19
1094120	Soil	2.1	45.2	15.3	77	0.3	54.4	17.6	1349	5.34	28.1	3.4	1.0	4	<0.1	2.0	0.5	13	0.01	0.099	13
1094121	Soil	3.0	38.5	12.8	47	0.2	35.2	9.9	465	1.87	21.7	1.0	0.4	7	0.4	1.5	0.3	25	0.02	0.067	9
1094122	Soil	3.4	15.6	5.9	47	0.2	15.0	3.8	176	1.13	8.9	<0.5	0.1	10	0.2	1.1	0.1	28	0.07	0.091	4
1094123	Soil	16.9	114.7	34.1	299	1.6	123.6	17.2	320	4.89	32.8	2.7	1.3	72	0.6	6.2	0.4	79	0.29	0.269	10
1094124	Soil	4.2	12.9	5.0	45	0.1	14.0	2.0	64	0.70	8.2	<0.5	0.1	19	1.1	0.9	0.1	24	0.07	0.094	4
1094125	Soil	17.4	50.8	21.3	252	0.4	81.4	10.0	155	3.35	38.1	3.5	0.7	65	1.0	5.8	0.3	130	0.20	0.196	14
1094126	Soil	127.8	68.1	28.4	1270	0.5	262.2	22.2	421	3.32	65.4	<0.5	2.5	31	9.2	24.2	0.3	323	0.59	0.090	8
1094127	Soil	90.5	68.0	17.0	252	0.3	222.4	10.0	192	3.44	41.7	1.3	3.2	43	1.6	9.1	0.2	80	0.56	0.128	7
1094128	Soil	111.2	82.5	19.3	508	0.3	229.5	9.4	142	2.42	29.5	1.0	2.1	39	3.1	6.2	0.2	111	2.83	0.055	3
1094129	Soil	72.3	68.4	14.1	594	0.3	204.0	11.0	184	2.28	23.1	3.1	0.7	41	3.6	7.3	0.1	107	0.82	0.099	6
1094130	Soil	72.2	80.3	16.8	846	0.9	211.5	10.3	246	2.16	39.2	<0.5	2.0	156	8.3	13.3	0.1	334	5.85	0.117	8
1094131	Soil	88.3	92.8	28.6	580	2.1	247.0	14.3	384	3.93	55.3	5.2	2.0	86	6.9	19.1	0.3	383	0.37	0.164	18
1094132	Soil	81.2	82.1	21.4	465	0.2	178.8	11.5	229	3.15	33.4	1.6	1.9	17	3.8	8.6	0.2	157	0.13	0.111	14
1094133	Soil	74.8	53.4	20.4	355	0.3	121.5	5.9	81	2.24	27.9	<0.5	0.6	19	1.2	11.1	0.2	466	0.05	0.060	10
1094134	Soil	60.6	39.5	13.2	133	1.5	23.9	1.4	16	1.34	25.0	1.4	0.2	43	0.3	16.0	0.2	671	0.02	0.057	11
1094135	Soil	14.9	17.7	16.3	48	0.8	11.4	2.9	63	1.29	13.1	<0.5	0.1	10	<0.1	3.6	0.2	79	0.02	0.047	6
1094136	Soil	1.7	17.9	7.3	41	0.1	13.1	6.4	230	1.90	11.6	<0.5	0.2	8	0.1	0.9	0.2	14	0.05	0.112	3
1094137	Soil	2.0	19.7	8.8	48	<0.1	14.2	7.8	188	1.76	11.6	0.8	0.1	7	<0.1	0.8	0.2	22	0.03	0.099	4
1094138	Soil	2.0	29.7	16.9	80	0.2	30.0	25.1	1267	2.56	14.5	<0.5	0.3	12	0.2	1.0	0.3	25	0.07	0.093	5
1094139	Soil	13.2	27.3	49.8	48	0.8	21.4	9.9	300	2.15	20.8	1.0	0.6	88	0.3	2.6	0.3	68	0.07	0.071	3
1094140	Soil	9.6	33.1	53.5	28	1.9	9.6	2.4	112	1.93	52.4	6.3	0.3	144	0.1	5.2	0.3	47	0.04	0.100	3
1094141	Soil	5.2	32.9	29.9	97	0.3	38.4	17.9	542	2.63	22.7	1.4	0.8	49	0.2	1.7	0.3	33	0.13	0.067	4
1094142	Soil	5.8	26.6	29.4	65	0.3	22.1	10.0	314	2.23	18.1	0.7	0.5	39	0.3	1.6	0.3	33	0.04	0.060	4
1094143	Soil	2.7	18.2	19.8	49	0.4	15.8	6.0	104	1.38	15.7	<0.5	0.3	21	0.1	1.1	0.2	22	0.06	0.055	3
1094144	Soil	1.6	9.7	11.3	21	0.3	9.3	2.7	62	0.73	10.5	<0.5	<0.1	15	<0.1	0.5	<0.1	16	0.10	0.056	2
1094145	Soil	1.2	8.1	3.8	12	0.1	3.3	0.9	34	0.51	5.1	0.5	<0.1	6	<0.1	0.4	<0.1	13	0.03	0.038	1
1094146	Soil	97.5	74.0	32.4	505	0.7	193.0	11.7	214	3.49	82.8	5.9	0.7	11	3.7	9.6	0.2	205	0.09	0.057	18

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094117	Soil		8	0.02	90	0.004	3	0.23	0.014	0.06	0.1	0.02	0.3	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094118	Soil		10	0.02	96	0.004	3	0.28	0.005	0.06	0.1	0.02	0.2	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094119	Soil		8	0.03	94	0.003	3	0.35	0.007	0.06	<0.1	0.03	1.3	0.1	<0.05	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094120	Soil		18	0.04	162	0.008	2	0.63	0.006	0.08	0.1	0.07	2.5	0.2	<0.05	2	0.8	0.2	N.A.	N.A.	N.A.	N.A.
1094121	Soil		8	0.03	189	0.005	3	0.44	0.009	0.10	<0.1	0.04	1.2	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094122	Soil		7	0.03	159	0.004	3	0.40	0.014	0.06	<0.1	0.03	0.3	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094123	Soil		20	0.05	1261	0.005	3	0.53	0.003	0.12	<0.1	0.21	3.5	0.3	<0.05	1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094124	Soil		6	0.02	302	0.004	3	0.46	0.021	0.04	<0.1	0.03	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094125	Soil		22	0.09	924	0.009	2	0.57	0.004	0.10	0.1	0.10	1.7	0.4	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094126	Soil		21	0.19	257	0.004	4	0.33	0.004	0.10	0.2	0.56	5.2	2.1	<0.05	1	5.6	0.2	N.A.	N.A.	N.A.	N.A.
1094127	Soil		21	0.11	193	0.005	8	0.35	0.005	0.08	0.3	0.32	5.8	1.6	<0.05	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094128	Soil		19	1.43	128	0.002	1	0.20	0.004	0.06	0.2	0.33	4.3	1.3	<0.05	<1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094129	Soil		19	0.11	196	0.003	3	0.38	0.005	0.07	0.4	0.30	3.7	1.0	0.07	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094130	Soil		31	2.13	613	0.004	7	0.38	0.006	0.13	0.2	0.66	3.9	1.5	0.12	1	5.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094131	Soil		34	0.09	482	0.004	7	0.64	0.004	0.17	0.2	0.88	5.1	3.7	0.16	2	7.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094132	Soil		22	0.06	213	0.004	5	0.46	0.002	0.06	0.2	0.22	4.1	1.3	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094133	Soil		33	0.08	165	0.006	2	0.58	0.006	0.10	0.3	0.08	1.6	1.8	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094134	Soil		38	0.05	219	0.008	5	0.43	0.011	0.14	0.3	0.26	0.6	4.1	0.07	3	11.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094135	Soil		9	0.03	63	0.005	<1	0.51	0.015	0.06	0.1	0.03	0.4	0.6	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094136	Soil		15	0.04	65	0.005	<1	0.63	0.016	0.04	<0.1	0.06	0.7	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094137	Soil		14	0.03	39	0.005	<1	0.57	0.016	0.04	<0.1	0.07	0.7	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094138	Soil		15	0.09	78	0.007	1	0.69	0.016	0.05	<0.1	0.04	2.2	0.3	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094139	Soil		13	0.04	468	0.002	<1	0.39	0.009	0.15	<0.1	0.11	2.4	0.8	0.32	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094140	Soil		15	0.04	586	0.005	<1	0.42	0.016	0.12	<0.1	0.08	1.3	0.5	0.20	2	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094141	Soil		15	0.06	205	0.002	<1	0.54	0.007	0.08	<0.1	0.06	4.2	0.5	0.10	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094142	Soil		13	0.06	178	0.002	<1	0.46	0.006	0.08	<0.1	0.04	2.7	0.4	0.11	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094143	Soil		10	0.03	96	0.004	<1	0.36	0.010	0.05	<0.1	0.05	2.0	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094144	Soil		7	0.03	64	0.010	2	0.47	0.026	0.04	<0.1	0.07	1.1	<0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094145	Soil		5	0.02	21	0.005	1	0.37	0.024	0.03	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094146	Soil		15	0.07	189	0.003	<1	0.59	0.005	0.09	0.1	0.09	2.4	2.7	<0.05	2	4.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094141	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094142	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094143	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094144	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094145	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094146	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094141	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094142	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094143	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094144	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094145	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094146	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094147	Soil		6.6	25.8	27.3	38	0.4	12.4	4.0	101	1.60	25.5	0.7	<0.1	39	0.2	2.0	0.2	46	0.03	0.052	4
1094148	Soil		11.5	32.6	11.8	142	<0.1	31.7	6.8	156	2.37	18.5	<0.5	<0.1	8	0.2	2.8	0.3	90	0.02	0.055	8
1094149	Soil		53.1	76.3	23.9	352	0.4	173.1	18.0	317	3.14	30.7	2.5	1.0	50	1.9	4.6	0.1	106	0.62	0.175	13
1094150	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094151	Soil		28.4	19.0	6.5	166	0.2	46.1	3.5	125	1.29	12.0	<0.5	0.1	10	0.4	3.8	0.1	78	0.04	0.117	4
1094152	Soil		29.1	24.6	11.1	116	<0.1	40.2	4.6	110	1.76	10.9	2.7	<0.1	6	0.3	2.5	0.2	67	0.02	0.090	4
1094153	Soil		21.1	21.6	9.4	81	<0.1	28.6	3.7	80	1.56	9.3	1.8	<0.1	7	0.1	1.8	0.2	55	0.03	0.085	3
1094154	Soil		34.9	36.7	15.4	139	0.2	42.8	6.3	179	2.18	23.2	<0.5	0.4	10	0.5	2.9	0.2	95	0.06	0.096	2
1094155	Soil		32.2	27.2	16.0	94	0.4	40.2	4.7	105	1.73	15.2	1.9	0.1	10	0.8	2.8	0.4	68	0.04	0.082	2
1094156	Soil		3.1	50.8	11.9	25	0.2	21.8	8.1	351	2.55	7.0	1.0	0.3	9	0.1	1.6	0.4	38	0.04	0.083	3
1094157	Soil		6.2	140.0	31.8	166	1.4	72.0	38.2	1221	4.38	19.3	7.2	1.0	28	1.0	3.7	0.5	68	0.22	0.165	5
1094158	Soil		9.2	82.7	62.8	64	1.8	21.1	4.4	211	5.76	60.4	4.3	0.4	37	0.2	6.2	0.4	165	0.05	0.340	8
1094159	Soil		8.2	130.5	52.3	63	2.0	35.8	4.0	212	3.70	57.4	2.9	2.0	47	0.2	6.4	0.4	149	0.10	0.494	7
1094160	Soil		4.1	144.4	22.7	207	1.7	96.5	36.1	2090	5.50	15.3	5.0	1.4	18	3.9	2.3	0.3	91	0.10	0.157	4
1094161	Soil		1.5	32.3	8.7	67	0.6	15.4	10.3	400	1.42	4.3	2.2	<0.1	12	0.3	0.9	0.1	30	0.11	0.072	2
1094162	Soil		4.2	96.9	22.5	126	1.2	51.5	22.7	1022	5.26	13.0	4.2	0.5	11	0.6	2.3	0.5	102	0.10	0.108	3
1094163	Soil		6.4	153.0	48.9	371	3.0	88.6	44.5	1736	8.16	22.2	5.6	2.8	21	1.7	4.2	0.6	142	0.13	0.150	5
1094164	Soil		3.7	20.3	7.9	62	0.2	10.9	4.9	389	1.08	4.4	1.5	<0.1	7	0.3	1.0	0.2	28	0.03	0.063	2
1094165	Soil		4.8	17.0	7.0	59	0.1	11.3	3.1	71	1.06	48.2	3.4	0.1	6	0.4	3.4	0.1	33	0.04	0.075	2
1094166	Soil		5.8	25.5	8.3	68	0.1	13.9	3.3	101	1.23	7.7	2.9	<0.1	9	0.2	1.5	0.3	36	0.03	0.080	3
1094167	Soil		3.1	29.7	8.7	26	<0.1	14.1	5.7	214	1.23	7.0	<0.5	0.1	7	<0.1	1.5	0.2	22	0.02	0.062	2
1094168	Soil		27.5	81.5	28.1	678	1.0	116.9	10.2	248	2.87	39.9	2.1	1.8	72	6.8	11.8	0.2	120	1.84	0.129	5
1094169	Soil		36.3	34.2	10.7	619	<0.1	67.0	6.2	68	2.09	31.8	0.6	0.3	4	0.6	16.6	0.2	255	0.02	0.048	3
1094170	Soil		11.3	52.7	15.8	191	0.2	67.3	10.0	162	2.99	17.4	2.6	0.4	17	0.3	4.1	0.2	59	0.06	0.153	5
1094171	Soil		4.9	57.1	20.9	139	1.6	62.6	10.2	116	2.52	21.4	4.4	1.8	95	<0.1	4.4	0.3	36	0.39	0.150	4
1094172	Soil		4.8	35.0	14.3	82	<0.1	39.2	8.8	167	2.88	25.6	1.2	1.0	16	0.2	3.6	0.3	39	0.09	0.062	7
1094173	Soil		11.2	56.7	28.7	38	0.6	75.9	21.2	572	4.39	33.4	3.2	1.4	14	<0.1	3.9	0.4	21	0.15	0.056	7
1094174	Soil		4.2	48.8	20.3	66	0.2	50.2	17.7	967	3.80	20.4	3.2	1.2	6	0.2	2.6	0.3	20	0.02	0.062	17
1094175	Soil		5.9	57.9	19.7	136	0.1	63.7	16.6	298	4.60	21.7	1.7	0.6	8	0.2	3.5	0.4	27	0.02	0.086	28
1094176	Soil		23.4	35.9	34.8	41	1.4	13.8	2.6	143	2.39	35.5	3.8	0.6	88	0.2	5.1	0.3	153	0.11	0.449	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094147	Soil	14	0.05	169	0.008	<1	0.42	0.012	0.07	<0.1	0.05	0.9	0.4	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094148	Soil	15	0.03	70	0.006	1	0.51	0.004	0.05	0.1	0.02	0.5	0.2	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094149	Soil	33	0.09	343	0.005	2	0.43	0.004	0.07	0.2	0.38	4.9	0.7	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094150	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	49.0	45.5	15.1	308
1094151	Soil	12	0.03	120	0.007	<1	0.36	0.011	0.04	0.2	0.03	0.7	0.4	0.11	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094152	Soil	14	0.03	57	0.008	<1	0.32	0.007	0.05	0.2	0.02	0.8	0.2	0.07	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094153	Soil	13	0.03	62	0.007	1	0.32	0.011	0.05	<0.1	0.01	0.7	0.2	0.09	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094154	Soil	20	0.04	261	0.010	<1	0.32	0.008	0.07	0.1	0.02	2.6	0.3	0.14	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094155	Soil	13	0.02	474	0.004	2	0.34	0.012	0.04	0.1	0.08	1.4	0.4	0.08	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094156	Soil	12	0.03	51	0.005	2	0.51	0.011	0.04	<0.1	0.07	2.6	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094157	Soil	27	0.09	344	0.002	1	0.97	0.004	0.06	<0.1	0.13	7.0	0.5	0.06	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094158	Soil	54	0.13	112	0.006	3	0.94	0.005	0.06	0.2	0.09	3.5	0.3	0.08	4	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094159	Soil	53	0.10	96	0.008	2	1.93	0.010	0.06	<0.1	0.07	15.1	0.2	<0.05	3	4.3	0.2	N.A.	N.A.	N.A.	N.A.
1094160	Soil	25	0.14	158	0.011	1	1.00	0.017	0.04	<0.1	0.12	9.7	0.4	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094161	Soil	9	0.04	96	0.009	1	0.62	0.021	0.03	<0.1	0.03	1.1	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094162	Soil	26	0.09	122	0.004	1	0.64	0.010	0.04	<0.1	0.10	6.6	0.5	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094163	Soil	41	0.15	269	0.003	1	0.92	0.005	0.06	<0.1	0.15	15.7	0.6	<0.05	3	2.3	0.2	N.A.	N.A.	N.A.	N.A.
1094164	Soil	8	0.03	54	0.004	2	0.58	0.019	0.03	<0.1	0.05	0.4	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094165	Soil	8	0.03	52	0.010	<1	0.28	0.015	0.04	<0.1	0.04	1.4	<0.1	0.06	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094166	Soil	10	0.03	57	0.003	1	0.50	0.014	0.05	<0.1	0.03	0.3	0.1	0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094167	Soil	6	0.02	39	0.003	2	0.36	0.014	0.04	<0.1	0.02	0.4	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094168	Soil	19	0.82	231	0.002	3	0.25	0.004	0.06	<0.1	0.72	4.9	0.5	<0.05	<1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094169	Soil	13	0.02	101	0.002	1	0.34	0.002	0.05	<0.1	0.10	0.9	0.2	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094170	Soil	13	0.03	187	0.003	3	0.40	0.005	0.06	<0.1	0.04	1.1	0.2	<0.05	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094171	Soil	10	0.03	719	0.004	7	0.36	0.004	0.10	<0.1	0.26	3.8	0.1	<0.05	1	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094172	Soil	12	0.04	218	0.006	3	0.34	0.004	0.06	<0.1	0.05	2.5	<0.1	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094173	Soil	8	0.04	319	0.002	1	0.25	0.003	0.06	<0.1	0.17	4.0	0.1	<0.05	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094174	Soil	7	0.03	184	0.003	2	0.40	0.005	0.06	<0.1	0.06	2.5	0.1	<0.05	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094175	Soil	9	0.03	98	0.005	3	0.31	0.004	0.07	<0.1	0.07	1.7	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094176	Soil	31	0.09	647	0.008	2	0.67	0.005	0.15	0.3	0.14	1.5	0.5	0.19	4	5.8	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094147	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094148	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094149	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094150	Soil		0.2	96.1	7.3	206	2.09	21.5	1.4	0.1	18	1.8	3.9	0.2	116	0.15	0.095	6	18	0.04	305	0.002
1094151	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094152	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094153	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094154	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094155	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094156	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094157	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094158	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094159	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094160	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094161	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094162	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094163	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094164	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094165	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094166	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094167	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094168	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094169	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094170	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094171	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094172	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094173	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094174	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094175	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094176	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094147	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094148	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094149	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094150	Soil	<20	0.50	0.003	0.05	0.1	0.05	0.4	0.7	<0.05	2	2.6	<0.2
1094151	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094152	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094153	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094154	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094155	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094156	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094157	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094158	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094159	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094160	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094161	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094162	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094163	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094164	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094165	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094174	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094175	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094176	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094177	Soil		8.3	16.4	49.9	18	0.6	4.8	1.3	92	1.71	47.2	7.2	1.5	43	<0.1	4.6	0.3	41	0.04	0.320	13
1094178	Soil		18.1	8.6	16.9	15	1.0	4.9	1.0	62	0.86	11.9	1.7	0.1	15	<0.1	4.1	0.2	50	0.02	0.055	6
1094179	Soil		11.6	20.4	51.7	46	0.9	10.2	2.1	75	1.71	15.8	2.5	<0.1	116	0.2	4.1	0.4	105	0.05	0.252	20
1094180	Soil		20.7	50.9	49.7	44	1.9	10.6	1.6	60	1.96	17.1	2.9	<0.1	130	0.5	6.9	0.3	169	0.24	0.544	22
1094181	Soil		10.8	18.3	21.8	36	0.7	9.2	2.2	92	1.57	12.9	9.3	<0.1	33	0.1	2.8	0.3	91	0.06	0.235	12
1094182	Soil		9.3	15.4	13.6	9	0.8	3.2	0.8	37	0.84	6.2	4.2	0.1	21	<0.1	2.6	0.1	57	0.03	0.118	9
1094183	Soil		6.7	37.7	14.4	164	0.7	31.5	2.8	89	1.51	12.6	3.5	2.2	22	1.6	2.2	0.1	45	0.08	0.054	7
1094184	Soil		33.0	55.7	22.9	228	1.5	41.3	3.0	80	2.36	31.3	3.1	0.7	131	1.0	7.4	0.2	294	0.10	0.266	19
1094185	Soil		2.5	100.7	31.2	118	0.5	16.9	2.9	87	1.44	27.9	4.3	0.2	83	1.1	4.1	0.1	48	0.15	0.253	10
1094186	Soil		13.9	71.2	35.4	342	0.5	47.2	7.7	164	3.31	34.7	2.0	0.4	31	0.5	7.8	0.3	122	0.03	0.169	10
1094187	Soil		5.5	23.1	18.4	126	<0.1	24.0	6.9	168	2.42	13.6	<0.5	0.2	10	0.1	2.6	0.4	39	0.02	0.059	8
1094188	Soil		5.3	16.4	16.5	85	<0.1	16.2	4.5	114	1.83	11.1	<0.5	0.1	9	0.2	1.8	0.3	45	0.01	0.094	8
1094189	Soil		6.5	23.1	18.6	106	0.1	23.5	6.7	115	2.19	12.4	1.5	0.1	10	0.2	2.3	0.3	46	0.02	0.090	7
1094190	Soil		8.6	44.5	26.9	230	0.4	48.5	11.4	339	3.56	22.9	<0.5	1.6	20	0.5	3.6	0.3	72	0.06	0.137	11
1094191	Soil		8.5	21.7	22.3	131	<0.1	28.5	6.4	105	1.85	15.5	<0.5	0.1	12	0.3	3.3	0.3	49	0.03	0.064	5
1094192	Soil		5.1	14.2	10.3	76	<0.1	16.1	3.7	64	1.18	8.8	<0.5	0.1	8	0.2	1.8	0.1	33	0.01	0.046	4
1094193	Soil		8.5	47.2	26.6	428	1.4	62.6	11.3	247	3.20	21.5	2.5	1.8	51	2.6	4.2	0.3	79	0.61	0.238	11
1094194	Soil		8.8	43.7	23.8	220	0.3	43.4	7.9	168	2.87	34.3	4.4	0.4	30	0.8	5.6	0.2	65	0.15	0.148	8
1094195	Soil		5.2	26.8	12.1	175	0.6	29.7	5.9	165	1.94	16.8	<0.5	0.3	24	1.1	2.5	0.2	51	0.17	0.225	5
1094196	Soil		6.8	50.7	14.1	266	1.9	64.1	4.6	106	2.04	17.0	4.8	0.4	24	1.4	3.2	0.2	65	0.18	0.122	5
1094197	Soil		15.0	33.6	29.6	219	0.7	43.3	5.6	155	2.86	26.4	<0.5	0.3	37	0.6	5.0	0.3	115	0.04	0.196	9
1094198	Soil		32.6	64.5	20.4	569	0.9	119.5	15.7	410	3.43	47.5	0.7	0.9	60	5.5	7.9	0.2	148	0.43	0.277	8
1094199	Soil		17.4	42.8	11.8	507	0.9	80.5	6.0	182	1.67	21.8	1.8	0.5	31	3.8	4.8	0.1	132	0.36	0.114	11
1094200	Soil		14.3	22.9	13.6	766	0.2	87.2	6.2	304	2.37	38.9	<0.5	0.5	40	9.8	5.6	0.2	265	0.51	0.145	10
1093221	Soil		19.7	54.5	22.9	180	0.3	50.9	5.7	210	2.58	24.7	0.9	0.1	23	0.5	4.2	0.2	109	0.04	0.211	9
1093222	Soil		10.7	32.1	10.2	142	0.2	43.4	5.6	261	1.78	16.9	<0.5	0.1	20	1.0	2.8	0.2	47	0.09	0.175	5
1093223	Soil		7.0	39.8	18.7	140	0.1	44.6	5.6	111	2.03	19.4	2.5	<0.1	27	0.4	3.0	0.2	48	0.06	0.191	9
1093224	Soil		8.7	32.1	12.4	120	0.2	36.9	5.2	148	1.81	16.9	<0.5	<0.1	18	0.6	2.5	0.2	47	0.10	0.179	7
1093225	Soil		4.0	62.9	18.2	79	0.4	32.6	15.9	746	2.68	24.2	<0.5	0.5	18	0.5	2.6	0.3	38	0.07	0.106	5
1093226	Soil		3.4	40.6	14.1	58	0.3	23.1	8.6	366	1.77	19.3	1.3	0.2	16	0.2	2.0	0.3	27	0.05	0.066	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094177	Soil	18	0.04	638	0.009	4	0.42	0.007	0.13	<0.1	0.04	4.7	0.3	0.16	3	4.6	0.2	N.A.	N.A.	N.A.	N.A.
1094178	Soil	11	0.03	318	0.006	3	0.29	0.011	0.08	<0.1	0.11	0.4	0.3	0.11	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094179	Soil	18	0.05	269	0.001	2	0.65	0.005	0.08	0.1	0.03	<0.1	0.3	0.11	5	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094180	Soil	25	0.07	505	0.002	5	0.60	0.007	0.12	0.3	0.17	<0.1	0.5	0.18	3	6.1	0.3	N.A.	N.A.	N.A.	N.A.
1094181	Soil	19	0.09	184	0.001	3	0.69	0.007	0.07	0.2	0.12	<0.1	0.4	0.06	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094182	Soil	15	0.03	189	0.003	2	0.46	0.017	0.07	<0.1	0.12	<0.1	0.4	0.07	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094183	Soil	12	0.02	247	0.002	2	0.23	0.002	0.07	<0.1	0.24	2.8	0.4	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094184	Soil	41	0.04	859	0.006	4	1.00	0.009	0.12	0.1	0.09	2.5	0.9	0.10	4	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094185	Soil	21	0.04	499	0.005	3	0.66	0.021	0.05	<0.1	0.06	1.0	0.4	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094186	Soil	18	0.04	194	0.003	<1	0.77	0.003	0.07	<0.1	0.05	0.4	0.4	<0.05	4	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094187	Soil	8	0.03	77	0.004	3	0.43	0.005	0.04	0.1	<0.01	0.5	0.2	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094188	Soil	9	0.03	63	0.003	3	0.40	0.005	0.04	0.1	<0.01	0.2	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094189	Soil	7	0.03	122	0.001	2	0.48	0.004	0.04	<0.1	0.02	0.2	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094190	Soil	22	0.22	293	0.007	2	1.12	0.004	0.08	0.1	0.13	2.7	0.3	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094191	Soil	8	0.02	124	0.003	2	0.27	0.007	0.04	<0.1	<0.01	0.5	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094192	Soil	6	0.02	95	0.003	2	0.30	0.011	0.04	<0.1	0.03	0.3	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094193	Soil	21	0.16	657	0.003	5	0.76	0.006	0.11	<0.1	0.60	3.8	0.4	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094194	Soil	14	0.08	311	0.004	3	0.51	0.004	0.06	<0.1	0.08	0.9	0.3	0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094195	Soil	14	0.09	358	0.004	4	0.79	0.012	0.06	<0.1	0.13	0.8	0.3	0.09	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094196	Soil	15	0.09	496	0.004	4	0.96	0.018	0.10	0.1	1.02	1.5	0.6	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094197	Soil	19	0.08	301	0.006	2	0.82	0.004	0.08	0.2	0.05	0.6	0.7	0.08	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094198	Soil	29	0.07	693	0.004	3	0.55	0.003	0.07	<0.1	0.48	2.2	0.8	0.07	1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094199	Soil	16	0.09	407	0.004	4	0.96	0.010	0.05	0.1	0.60	1.4	0.5	0.06	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094200	Soil	27	0.19	418	0.006	5	0.97	0.007	0.09	0.2	0.06	0.9	0.6	0.06	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093221	Soil	23	0.04	292	0.002	2	0.71	0.004	0.07	0.1	0.06	0.3	0.8	0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1093222	Soil	13	0.05	442	0.002	3	0.60	0.012	0.09	<0.1	0.04	0.3	0.4	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093223	Soil	13	0.02	114	0.002	9	0.43	0.011	0.05	<0.1	0.03	0.3	0.2	0.07	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093224	Soil	14	0.05	522	0.001	2	0.78	0.006	0.07	<0.1	<0.01	0.2	0.4	0.06	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093225	Soil	14	0.10	95	0.010	2	0.56	0.015	0.08	<0.1	0.03	2.4	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093226	Soil	9	0.05	69	0.006	1	0.47	0.014	0.05	<0.1	0.01	1.1	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094177	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094178	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094179	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094180	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094181	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094182	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094183	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094184	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094185	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094186	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094187	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094188	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094189	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094190	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094191	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094192	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094193	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094194	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094195	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094196	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094197	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094198	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094199	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094200	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093221	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093222	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093223	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093224	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093225	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093226	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094178	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094180	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093222	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093224	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093226	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1093227	Soil	2.1	26.1	9.2	39	0.1	16.3	5.7	285	1.41	10.2	<0.5	<0.1	7	<0.1	1.3	0.2	24	0.03	0.060	3
1093228	Soil	1.6	24.8	9.7	25	0.4	14.6	8.7	378	1.31	4.6	0.7	0.2	10	0.1	1.2	0.2	17	0.11	0.061	2
1093229	Soil	10.7	111.8	27.5	153	0.7	375.6	62.5	1386	11.10	16.5	0.6	2.5	44	1.7	3.8	0.1	198	0.66	0.325	30
1093230	Soil	140.4	234.1	32.8	4580	2.5	445.9	11.6	713	7.09	101.3	4.2	1.9	180	38.9	47.1	0.2	955	6.12	0.145	6
1092251	Soil	6.9	64.1	33.3	198	0.8	81.9	13.9	361	3.93	178.2	25.8	0.7	68	0.7	9.6	0.4	56	0.38	0.223	13
1092252	Soil	2.7	42.2	22.1	154	0.8	34.5	8.6	112	3.35	287.3	48.6	0.6	48	0.5	8.5	0.3	21	0.19	0.103	5
1092253	Soil	8.4	59.4	34.7	242	1.2	58.8	9.7	74	2.84	61.2	1.3	0.6	130	0.2	8.9	0.3	49	0.04	0.103	7
1092254	Soil	6.6	65.1	14.7	259	0.3	115.3	13.8	119	3.02	58.4	0.5	0.2	3	0.3	5.4	0.2	82	0.01	0.100	9
1092255	Soil	1.7	17.0	6.3	44	<0.1	13.0	4.9	83	1.70	15.9	1.4	0.4	4	0.1	0.9	0.2	23	0.01	0.063	7
1092256	Soil	4.1	84.7	18.6	47	0.3	69.1	19.2	315	6.60	44.7	8.6	2.6	11	0.2	5.2	0.6	21	0.15	0.077	33
1092257	Soil	4.4	26.2	9.4	68	0.7	28.3	6.4	137	1.73	14.0	7.7	0.5	14	0.4	2.5	0.1	24	0.16	0.059	6
1092258	Soil	45.8	67.8	17.0	694	0.6	160.9	9.7	199	2.33	32.1	<0.5	1.2	55	5.8	10.2	0.2	176	1.28	0.113	6
1092259	Soil	103.0	106.0	11.6	757	0.5	252.3	8.7	219	2.22	40.3	<0.5	3.6	246	7.2	15.9	0.2	200	8.49	0.101	12
1092260	Soil	45.9	44.3	9.6	589	0.2	139.6	8.1	221	1.98	16.5	4.1	0.9	58	3.1	4.1	0.1	57	1.23	0.083	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1093227	Soil	7	0.02	43	0.005	1	0.38	0.017	0.04	<0.1	0.01	0.8	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093228	Soil	8	0.05	58	0.008	2	0.35	0.023	0.05	<0.1	0.03	1.1	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093229	Soil	222	0.16	372	0.005	6	0.65	0.005	0.10	<0.1	0.12	15.4	0.3	0.08	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093230	Soil	48	2.37	547	0.003	4	0.37	0.007	0.06	0.2	1.74	6.1	1.8	0.06	1	8.9	0.3	N.A.	N.A.	N.A.	N.A.
1092251	Soil	16	0.09	824	0.004	5	0.46	0.005	0.10	0.1	0.20	2.2	0.2	0.09	2	3.6	0.2	N.A.	N.A.	N.A.	N.A.
1092252	Soil	8	0.05	649	0.002	3	0.26	0.005	0.09	<0.1	0.12	2.1	0.1	0.10	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092253	Soil	10	0.03	319	0.003	3	0.36	0.004	0.09	<0.1	0.05	1.4	0.3	0.11	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092254	Soil	17	0.03	77	0.003	3	0.42	0.007	0.04	<0.1	0.04	0.5	0.1	<0.05	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092255	Soil	8	0.04	289	0.002	2	0.60	0.005	0.06	<0.1	0.03	0.7	0.1	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1092256	Soil	12	0.06	358	0.003	9	0.55	0.003	0.09	<0.1	0.06	4.3	0.2	0.06	1	1.9	0.3	N.A.	N.A.	N.A.	N.A.
1092257	Soil	8	0.07	562	0.003	3	0.27	0.018	0.06	<0.1	0.11	1.8	0.1	<0.05	<1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092258	Soil	17	0.41	317	0.003	5	0.37	0.005	0.06	0.2	0.50	2.8	0.6	0.07	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1092259	Soil	17	2.33	418	0.003	8	0.27	0.006	0.09	0.2	0.43	4.8	1.7	<0.05	<1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1092260	Soil	16	0.11	316	0.004	4	0.58	0.011	0.06	0.2	0.20	3.3	1.3	0.09	1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1093227	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092254	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092258	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092259	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000768.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093227	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092254	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092258	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092259	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000768.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1093423	Soil	3.3	20.6	11.4	118	0.8	19.2	3.6	96	1.27	8.7	<0.5	0.2	17	0.7	1.6	0.1	34	0.22	0.107	7
REP 1093423	QC	3.0	21.3	11.1	119	0.7	19.1	3.5	96	1.25	8.5	2.5	0.2	17	0.8	1.5	0.1	34	0.22	0.099	7
1093431	Soil	34.7	73.7	12.2	712	0.9	222.5	26.4	423	4.28	36.8	1.0	2.9	78	6.3	11.2	0.1	475	1.39	0.236	33
REP 1093431	QC	35.4	75.5	13.2	758	1.0	229.0	28.2	443	4.53	38.5	2.4	3.2	81	7.4	12.1	0.1	497	1.42	0.245	36
1094055	Soil	16.5	43.8	17.4	308	0.3	51.6	5.8	85	3.11	33.9	<0.5	0.1	21	0.6	6.8	0.3	113	0.01	0.072	6
REP 1094055	QC	16.5	43.5	17.5	320	0.3	53.0	6.0	86	3.19	34.4	<0.5	0.2	25	0.6	6.8	0.3	118	0.02	0.077	6
1094077	Soil	10.0	14.5	7.4	63	0.8	18.3	1.7	22	0.72	9.7	<0.5	0.2	20	<0.1	2.4	<0.1	109	0.02	0.085	5
REP 1094077	QC	10.1	16.2	7.4	63	0.8	16.5	1.7	22	0.73	9.6	1.5	0.2	21	0.2	2.4	<0.1	109	0.02	0.081	5
1094081	Soil	6.9	16.1	10.5	65	0.3	16.6	2.0	30	1.00	9.3	1.6	0.2	20	0.1	2.3	0.2	98	0.01	0.063	5
REP 1094081	QC	7.0	16.0	10.4	63	0.3	15.8	2.0	29	1.00	9.2	<0.5	0.1	20	<0.1	2.6	0.2	98	0.01	0.069	5
1094101	Soil	6.2	35.8	21.6	84	1.6	49.2	18.9	1034	5.71	20.1	3.9	4.2	14	0.5	2.6	0.2	35	0.04	0.135	25
REP 1094101	QC	5.7	33.9	20.9	81	1.5	46.9	18.6	1006	5.55	19.8	3.7	4.1	14	0.6	2.5	0.3	35	0.04	0.131	24
1094120	Soil	2.1	45.2	15.3	77	0.3	54.4	17.6	1349	5.34	28.1	3.4	1.0	4	<0.1	2.0	0.5	13	0.01	0.099	13
REP 1094120	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094137	Soil	2.0	19.7	8.8	48	<0.1	14.2	7.8	188	1.76	11.6	0.8	0.1	7	<0.1	0.8	0.2	22	0.03	0.099	4
REP 1094137	QC	2.1	20.5	8.8	48	<0.1	13.6	8.2	182	1.69	12.6	<0.5	<0.1	7	<0.1	0.7	0.2	24	0.03	0.097	4
1094173	Soil	11.2	56.7	28.7	38	0.6	75.9	21.2	572	4.39	33.4	3.2	1.4	14	<0.1	3.9	0.4	21	0.15	0.056	7
REP 1094173	QC	11.4	53.2	29.7	36	0.6	71.9	19.6	563	4.26	33.7	4.0	1.5	13	<0.1	4.0	0.4	21	0.15	0.060	7
1094189	Soil	6.5	23.1	18.6	106	0.1	23.5	6.7	115	2.19	12.4	1.5	0.1	10	0.2	2.3	0.3	46	0.02	0.090	7
REP 1094189	QC	6.1	22.7	19.4	107	0.1	23.3	6.6	124	2.21	12.3	<0.5	0.1	11	0.2	2.2	0.3	46	0.02	0.088	7
1092259	Soil	103.0	106.0	11.6	757	0.5	252.3	8.7	219	2.22	40.3	<0.5	3.6	246	7.2	15.9	0.2	200	8.49	0.101	12
REP 1092259	QC	102.8	104.6	11.4	742	0.6	245.7	8.7	220	2.16	40.0	4.3	3.6	235	7.6	16.1	0.2	205	8.48	0.099	13
Reference Materials																					
STD DS8	Standard	12.7	108.3	125.8	300	1.7	37.0	7.4	599	2.36	25.2	108.9	6.8	61	2.3	5.4	5.9	42	0.67	0.076	14
STD DS8	Standard	13.0	117.0	116.5	319	1.8	39.0	7.8	618	2.46	27.5	118.3	6.2	63	2.3	5.2	6.3	44	0.67	0.078	13
STD DS8	Standard	12.9	107.2	125.8	304	1.8	36.8	7.2	616	2.45	26.2	107.7	6.6	63	2.4	5.5	6.4	40	0.65	0.079	13
STD DS8	Standard	13.4	114.2	130.2	325	1.9	39.2	7.8	631	2.55	27.1	114.9	7.1	69	2.5	5.8	7.1	43	0.74	0.081	14
STD DS8	Standard	14.2	112.1	132.5	314	1.8	39.2	7.7	624	2.52	27.4	96.3	7.0	70	2.3	6.2	6.1	46	0.69	0.082	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000768.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1093423	Soil	11	0.05	768	0.004	2	0.93	0.014	0.03	<0.1	0.20	0.7	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1093423	QC	11	0.05	762	0.003	<1	0.91	0.013	0.03	<0.1	0.19	0.7	0.2	<0.05	3	0.9	<0.2				
1093431	Soil	89	0.31	2368	0.005	8	0.99	0.006	0.13	0.2	0.33	6.8	1.0	0.05	3	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1093431	QC	88	0.34	2220	0.007	10	1.00	0.007	0.14	0.3	0.33	7.4	1.1	0.09	3	4.7	<0.2				
1094055	Soil	14	0.03	2719	0.005	<1	0.55	0.002	0.05	0.2	0.07	0.5	0.6	0.06	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094055	QC	16	0.03	2585	0.007	<1	0.56	0.002	0.05	0.2	0.08	0.7	0.6	0.10	3	2.5	<0.2				
1094077	Soil	14	0.02	229	0.005	4	0.36	0.008	0.04	0.1	0.21	0.8	0.6	0.06	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094077	QC	14	0.02	228	0.005	3	0.35	0.008	0.04	<0.1	0.29	0.6	0.6	<0.05	2	1.5	<0.2				
1094081	Soil	12	0.03	194	0.002	1	0.48	0.004	0.04	<0.1	0.03	0.3	0.3	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094081	QC	13	0.03	198	0.002	1	0.50	0.004	0.04	<0.1	0.03	0.2	0.3	<0.05	3	1.2	<0.2				
1094101	Soil	16	0.06	2668	0.003	2	1.50	0.002	0.06	<0.1	0.39	6.9	0.2	<0.05	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094101	QC	16	0.06	2590	0.004	2	1.46	0.002	0.06	<0.1	0.37	6.5	0.2	<0.05	1	1.3	<0.2				
1094120	Soil	18	0.04	162	0.008	2	0.63	0.006	0.08	0.1	0.07	2.5	0.2	<0.05	2	0.8	0.2	N.A.	N.A.	N.A.	N.A.
REP 1094120	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1094137	Soil	14	0.03	39	0.005	<1	0.57	0.016	0.04	<0.1	0.07	0.7	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094137	QC	13	0.03	41	0.005	<1	0.56	0.015	0.04	<0.1	0.07	0.6	0.1	<0.05	2	<0.5	<0.2				
1094173	Soil	8	0.04	319	0.002	1	0.25	0.003	0.06	<0.1	0.17	4.0	0.1	<0.05	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094173	QC	7	0.04	320	0.002	<1	0.25	0.003	0.05	<0.1	0.18	4.3	0.1	<0.05	1	<0.5	0.2				
1094189	Soil	7	0.03	122	0.001	2	0.48	0.004	0.04	<0.1	0.02	0.2	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094189	QC	9	0.03	125	0.002	1	0.50	0.005	0.04	<0.1	<0.01	0.3	0.2	<0.05	3	<0.5	<0.2				
1092259	Soil	17	2.33	418	0.003	8	0.27	0.006	0.09	0.2	0.43	4.8	1.7	<0.05	<1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1092259	QC	18	2.35	444	0.003	7	0.30	0.006	0.10	0.2	0.47	4.8	1.8	0.07	<1	3.7	<0.2				
Reference Materials																					
STD DS8	Standard	118	0.54	274	0.116	3	0.87	0.089	0.40	3.1	0.19	2.0	5.2	0.15	4	5.4	4.7				
STD DS8	Standard	120	0.61	280	0.109	2	0.88	0.085	0.41	3.2	0.22	2.0	5.4	0.14	5	5.0	5.1				
STD DS8	Standard	113	0.59	274	0.111	1	0.87	0.076	0.41	2.9	0.21	1.9	5.3	0.17	4	5.5	4.3				
STD DS8	Standard	119	0.63	279	0.114	3	0.93	0.101	0.43	3.2	0.21	2.2	5.6	0.18	5	5.3	4.7				
STD DS8	Standard	118	0.61	270	0.123	3	0.87	0.081	0.41	3.0	0.20	2.0	5.5	0.12	5	4.9	5.0				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000768.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																					
1093423	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093423	QC																				
1093431	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093431	QC																				
1094055	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094055	QC																				
1094077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094077	QC																				
1094081	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094081	QC																				
1094101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094101	QC																				
1094120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094120	QC																				
1094137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094137	QC																				
1094173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094173	QC																				
1094189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094189	QC																				
1092259	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092259	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000768.1

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1093423	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093423	QC													
1093431	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093431	QC													
1094055	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094055	QC													
1094077	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094077	QC													
1094081	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094081	QC													
1094101	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094101	QC													
1094120	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094120	QC													
1094137	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094137	QC													
1094173	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094173	QC													
1094189	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094189	QC													
1092259	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092259	QC													
Reference Materials														
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000768.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	14.6	121.5	132.0	325	1.8	41.8	8.4	648	2.62	29.1	120.5	7.5	73	2.7	6.0	7.0	46	0.76	0.078	17
STD DS8	Standard	12.9	112.4	124.4	321	1.9	38.2	8.1	632	2.57	25.3	109.4	6.9	72	2.3	5.9	6.9	43	0.70	0.083	14
STD DS8	Standard	13.5	114.3	127.7	315	1.8	40.9	7.2	599	2.54	25.8	110.9	6.7	70	2.6	6.1	7.0	42	0.75	0.084	13
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	0.6	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000768.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
STD DS8	Standard	131	0.66	281	0.138	1	1.00	0.098	0.43	2.8	0.21	2.9	5.5	0.18	5	5.2	4.9				
STD DS8	Standard	119	0.64	290	0.119	1	0.99	0.099	0.45	3.3	0.21	2.9	5.6	0.15	5	5.2	5.2				
STD DS8	Standard	117	0.64	270	0.112	4	0.92	0.089	0.42	3.1	0.19	2.2	5.7	0.16	5	4.3	5.7				
STD DS8	Standard																	14.5	109.9	131.7	314
STD OREAS45CA	Standard																	0.8	496.7	21.1	59
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000768.1

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	2.2	37.8	7.7	617	2.46	24.9	130.9	7.8	77	2.4	5.0	7.1	42	0.68	0.078	17	117	0.66	311	0.117
STD OREAS45CA	Standard	0.3	235.8	85.1	893	16.13	3.5	44.8	7.4	17	<0.1	<0.1	0.2	197	0.41	0.038	16	637	0.16	161	0.130
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000768.1

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.92	0.088	0.40	3.1	0.23	2.2	5.7	0.14	5	4.7	4.9
STD OREAS45CA	Standard	<20	3.81	0.013	0.07	<0.1	0.03	40.2	<0.1	<0.05	18	0.8	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 01, 2011
Report Date: October 11, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11000982.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #8
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve to 230 mesh			WHI
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	302	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	18	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090875	Soil	8.4	56.0	16.2	245	0.4	60.9	9.4	140	2.94	18.3	1.4	0.6	33	0.4	8.8	0.3	52	0.28	0.101	5
1090876	Soil	3.0	11.9	6.9	34	0.6	13.2	2.8	109	0.82	5.1	<0.5	0.2	15	0.1	1.6	0.1	14	0.23	0.055	3
1090877	Soil	5.3	37.9	11.5	54	<0.1	46.3	11.9	169	3.14	12.1	<0.5	0.9	5	<0.1	2.7	0.3	29	0.01	0.076	21
1090878	Soil	10.1	22.6	21.8	102	0.2	21.6	5.9	90	1.98	15.0	<0.5	0.4	13	0.1	4.3	0.3	100	0.01	0.083	8
1090855	Soil	24.7	32.5	16.5	288	1.0	59.7	6.0	119	2.12	28.6	5.4	1.5	74	1.2	8.4	0.2	170	0.38	0.121	11
1090856	Soil	17.7	21.4	16.8	148	0.9	33.7	3.2	42	1.26	18.0	<0.5	0.2	41	1.0	4.8	0.2	126	0.15	0.078	9
1090857	Soil	17.0	24.2	13.0	126	1.8	30.9	2.6	29	1.06	15.5	0.5	0.2	30	1.3	4.2	0.1	120	0.05	0.092	7
1090858	Soil	21.9	35.4	21.1	197	1.1	54.3	4.3	58	1.56	21.3	4.1	0.5	44	2.0	5.3	0.2	153	0.07	0.124	10
1090859	Soil	17.3	34.2	14.9	173	0.6	48.4	4.8	63	1.63	22.6	<0.5	0.3	28	0.9	5.3	0.2	115	0.04	0.096	11
1090860	Soil	22.5	59.1	17.3	334	2.0	81.4	7.9	221	2.54	28.8	4.8	1.0	46	2.4	6.0	0.2	177	0.33	0.149	11
1090864	Soil	7.9	5.6	6.2	31	0.2	6.0	0.9	14	0.42	7.1	<0.5	0.2	12	<0.1	1.6	<0.1	80	0.02	0.040	12
1090865	Soil	7.4	56.5	17.5	311	0.8	87.8	10.2	142	2.61	18.7	<0.5	0.3	38	0.9	7.2	0.2	68	0.15	0.122	4
1090866	Soil	14.1	48.6	19.8	203	0.3	72.6	11.8	210	3.22	26.0	<0.5	0.3	26	0.8	5.4	0.2	107	0.09	0.130	6
1090867	Soil	6.1	27.0	10.8	86	1.7	24.4	3.1	36	1.19	8.2	<0.5	0.1	24	0.2	2.1	0.1	30	0.05	0.076	2
1090868	Soil	7.0	55.1	27.7	206	2.3	49.8	7.6	117	3.24	22.2	1.0	0.4	133	0.3	5.5	0.3	52	0.27	0.164	5
1090869	Soil	9.6	22.3	9.7	84	0.5	28.1	5.6	61	1.53	17.3	<0.5	0.3	51	0.2	3.4	0.1	84	0.24	0.066	7
1090870	Soil	23.5	28.9	24.0	147	0.1	33.2	6.4	65	2.12	31.8	1.3	0.3	18	0.1	6.7	0.2	170	<0.01	0.053	8
1090871	Soil	0.7	2.2	1.6	8	0.4	2.2	0.5	9	0.19	0.8	<0.5	<0.1	6	<0.1	0.2	<0.1	9	0.01	0.029	<1
1090872	Soil	7.7	37.5	65.5	135	1.2	42.7	2.9	21	1.41	10.7	4.2	0.7	302	0.6	2.8	0.5	40	0.21	0.291	9
1090873	Soil	8.6	21.9	12.4	95	0.9	42.3	4.7	86	1.07	10.4	<0.5	<0.1	69	1.7	2.7	<0.1	65	0.52	0.114	4
1091651	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091652	Soil	20.2	77.7	24.2	247	0.9	103.2	16.0	2076	13.64	72.5	6.0	2.0	38	1.0	19.6	0.2	100	2.21	0.143	11
1091653	Soil	4.8	73.2	19.9	186	1.0	59.9	14.3	216	3.94	20.9	4.2	1.0	18	0.8	2.8	0.3	14	0.11	0.053	8
1091654	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091655	Soil	7.0	45.1	20.9	213	0.9	40.1	6.2	338	1.81	25.0	4.3	0.6	89	1.7	6.7	0.2	61	2.35	0.130	12
1091656	Soil	18.7	109.8	12.4	545	2.3	141.3	6.3	383	2.02	130.2	3.2	0.8	291	3.9	15.4	0.2	141	7.10	0.138	11
1091657	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091658	Soil	4.4	57.1	38.9	152	0.9	66.2	19.6	1485	7.24	8.4	12.9	2.2	145	0.4	1.6	0.3	24	1.84	0.098	14
1091659	Soil	6.0	128.9	47.0	174	0.4	47.7	22.6	1387	6.33	17.3	7.1	3.2	45	0.8	2.6	0.4	77	0.13	0.162	17
1091660	Soil	4.2	37.4	8.0	191	0.4	23.6	3.7	1702	9.38	15.2	9.8	0.9	127	1.0	2.4	<0.1	41	11.77	0.113	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090875	Soil	11	0.07	962	0.002	4	0.37	0.004	0.04	<0.1	0.05	1.8	0.1	0.06	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090876	Soil	4	0.05	217	0.005	3	0.33	0.025	0.03	<0.1	0.12	0.7	<0.1	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090877	Soil	6	0.03	59	0.007	4	0.31	0.002	0.04	0.1	0.02	1.3	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090878	Soil	10	0.03	73	0.003	3	0.45	0.002	0.04	0.1	0.02	0.8	0.2	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1090855	Soil	17	0.08	851	0.005	3	0.51	0.004	0.08	0.2	0.36	2.3	0.7	0.12	2	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090856	Soil	12	0.04	586	0.003	3	0.37	0.008	0.06	0.1	0.13	0.8	0.5	0.08	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090857	Soil	11	0.03	564	0.003	4	0.37	0.007	0.06	0.1	0.24	1.0	0.5	0.12	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090858	Soil	16	0.04	727	0.003	4	0.57	0.006	0.08	0.2	0.31	1.1	0.6	0.11	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090859	Soil	15	0.03	358	0.003	3	0.40	0.005	0.06	0.2	0.21	0.7	0.5	0.07	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1090860	Soil	25	0.10	1787	0.003	4	1.02	0.007	0.11	0.2	0.65	3.0	0.6	0.09	3	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090864	Soil	8	0.02	126	0.005	2	0.32	0.004	0.04	<0.1	0.02	0.4	0.4	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1090865	Soil	22	0.02	165	0.005	2	0.35	0.007	0.05	<0.1	0.19	1.3	0.1	0.05	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1090866	Soil	27	0.06	431	0.003	2	0.51	0.008	0.06	0.1	0.09	1.6	0.3	0.06	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090867	Soil	6	0.02	967	0.003	2	0.32	0.013	0.03	<0.1	0.20	1.1	<0.1	0.09	<1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1090868	Soil	15	0.05	3477	0.003	2	0.72	0.006	0.06	<0.1	0.30	1.7	0.2	0.13	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090869	Soil	14	0.05	3090	0.007	3	0.43	0.010	0.07	0.1	0.07	1.6	0.3	0.14	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1090870	Soil	11	0.02	140	0.002	<1	0.31	0.002	0.05	0.1	0.03	0.8	0.3	0.11	4	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1090871	Soil	2	<0.01	19	0.004	<1	0.12	0.017	0.02	<0.1	0.02	0.5	<0.1	0.06	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090872	Soil	10	0.02	2091	0.004	5	0.39	0.011	0.06	<0.1	0.19	1.0	0.2	0.19	2	1.8	0.3	N.A.	N.A.	N.A.	N.A.
1090873	Soil	14	0.04	776	0.003	2	0.37	0.019	0.04	<0.1	0.13	0.6	0.2	0.15	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091651	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	10.3	73.8	33.2	481
1091652	Soil	17	0.62	388	0.006	5	0.57	0.004	0.07	<0.1	0.20	3.8	0.3	0.13	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091653	Soil	8	0.08	752	0.002	3	0.51	0.003	0.09	<0.1	0.42	4.9	0.2	<0.05	<1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091654	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.2	61.9	63.3	164
1091655	Soil	16	0.15	465	0.007	6	0.58	0.006	0.07	0.2	0.25	1.6	0.2	0.27	1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091656	Soil	42	3.28	1086	0.004	8	0.36	0.013	0.08	0.2	1.44	2.0	0.3	0.11	<1	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091657	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	36.6	104.2	28.4	419
1091658	Soil	22	0.79	2562	0.006	6	0.67	0.006	0.12	<0.1	0.21	8.2	0.2	0.24	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091659	Soil	31	0.75	534	0.013	3	2.01	0.004	0.18	0.2	0.11	6.0	0.2	0.14	6	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1091660	Soil	7	3.16	209	0.003	6	0.33	0.003	0.05	<0.1	0.18	1.4	<0.1	0.07	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090875	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090876	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090877	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090878	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090855	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090856	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090857	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090858	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090859	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090860	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090864	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090865	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090866	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090867	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090868	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090869	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090870	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090871	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090872	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090873	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091651	Soil	0.5	98.0	24.7	561	6.39	23.4	6.7	2.0	21	1.7	3.4	0.2	28	0.22	0.166	17	13	0.20	1080	0.003
1091652	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091653	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091654	Soil	0.4	53.5	17.9	1315	4.14	42.6	9.0	0.7	24	0.8	3.8	0.4	60	0.16	0.137	11	33	0.18	551	0.011
1091655	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091656	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091657	Soil	1.6	135.2	15.4	446	3.31	32.8	2.1	4.2	69	2.2	6.8	0.3	127	0.49	0.107	22	25	0.16	1774	0.003
1091658	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091659	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091660	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090875	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090876	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090877	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090878	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090855	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090856	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090857	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090858	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090859	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090860	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090864	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090865	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090866	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090867	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090868	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090869	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090870	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090871	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090872	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090873	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091651	Soil	<20	1.01	0.002	0.10	<0.1	0.13	4.5	0.3	0.06	2	2.9	<0.2
1091652	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091653	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091654	Soil	<20	0.91	0.011	0.09	0.3	0.12	3.3	0.2	0.08	3	1.7	<0.2
1091655	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091656	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091657	Soil	<20	0.57	0.005	0.13	0.1	0.39	5.1	0.4	<0.05	1	4.4	0.2
1091658	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091659	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091660	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091661	Soil	4.4	109.1	19.8	189	0.3	35.8	14.2	303	3.84	12.7	9.2	2.0	33	0.6	2.0	0.2	67	0.21	0.204	9
1091662	Soil	12.7	498.0	27.8	106	2.3	104.6	14.5	352	4.34	34.1	22.4	1.4	46	0.3	6.8	0.3	74	0.87	0.343	10
1091663	Soil	5.6	350.1	33.8	21	1.3	85.1	7.8	185	3.69	22.2	48.1	3.3	38	0.2	4.2	0.3	76	1.24	0.281	8
1091664	Soil	19.0	114.7	50.4	398	4.2	92.9	10.9	217	3.64	49.4	18.5	2.0	222	5.0	11.9	0.4	241	0.36	0.296	10
1091665	Soil	6.4	78.8	27.2	347	0.5	77.6	20.1	539	3.90	15.3	5.9	1.6	12	1.3	2.7	0.2	28	0.04	0.052	6
1091666	Soil	40.7	356.2	24.1	1528	3.7	208.9	23.4	434	3.63	66.3	4.0	4.0	130	46.4	31.4	0.3	470	0.50	0.330	20
1091667	Soil	99.7	120.0	23.5	89	6.8	18.0	1.3	29	3.76	38.3	7.6	0.4	102	3.1	36.7	0.5	385	0.06	0.401	17
1091668	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1091669	Soil	51.2	183.0	19.8	370	2.6	62.0	2.4	53	2.20	61.1	1.9	1.1	71	5.2	39.7	0.3	1251	0.13	0.225	34
1091670	Soil	79.9	297.4	40.9	1462	11.0	254.6	18.5	546	3.80	104.1	7.7	2.1	174	41.8	67.8	0.4	1305	0.74	0.441	35
1093081	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093082	Soil	3.6	6.2	4.0	45	0.1	8.6	1.5	263	0.40	2.9	<0.5	<0.1	8	0.9	1.0	0.1	18	0.06	0.156	1
1093083	Soil	2.9	5.0	5.5	33	<0.1	7.8	1.1	27	0.51	3.4	<0.5	<0.1	6	0.1	0.8	0.1	15	0.04	0.071	2
1093084	Soil	2.8	12.6	6.5	59	0.4	13.0	1.9	62	0.40	3.3	0.5	0.1	9	0.5	1.0	0.1	39	0.10	0.097	6
1093085	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093086	Soil	36.9	39.9	20.1	619	0.7	139.0	7.4	410	2.58	23.8	2.7	1.1	74	3.4	12.3	0.2	297	1.66	0.129	8
1093087	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093088	Soil	0.6	3.9	4.2	15	0.2	3.0	1.4	17	0.38	1.9	<0.5	<0.1	4	<0.1	0.2	<0.1	7	0.02	0.039	<1
1093089	Soil	0.8	3.8	2.3	17	<0.1	4.0	1.4	20	0.39	2.0	<0.5	<0.1	4	<0.1	0.2	<0.1	10	0.02	0.027	1
1093090	Soil	0.6	2.2	2.0	5	0.4	1.6	0.4	8	0.21	<0.5	1.0	<0.1	5	<0.1	0.2	<0.1	9	0.02	0.035	1
1093091	Soil	1.3	5.9	2.9	11	1.0	3.7	0.6	12	0.25	1.0	1.0	<0.1	13	<0.1	0.3	<0.1	10	0.14	0.040	2
1093092	Soil	3.3	11.7	4.9	49	1.1	14.4	1.7	28	0.59	3.6	1.8	0.1	23	0.4	1.1	<0.1	28	0.25	0.053	2
1093093	Soil	10.7	18.7	12.2	115	0.4	30.5	5.0	128	1.60	15.2	1.2	0.1	7	0.4	3.0	0.2	85	0.03	0.074	7
1093094	Soil	10.9	34.2	13.1	179	1.1	46.0	6.0	96	1.92	16.9	4.0	0.6	42	1.4	4.3	0.2	80	0.34	0.128	7
1093095	Soil	8.3	13.9	7.2	83	0.2	20.4	3.6	41	1.02	9.8	<0.5	0.1	5	0.2	2.6	0.1	71	0.02	0.026	10
1093096	Soil	7.0	28.0	18.0	104	0.6	29.4	6.6	337	1.78	11.8	2.5	0.3	43	1.1	3.0	0.2	53	0.19	0.162	7
1093097	Soil	8.1	15.1	10.5	86	0.2	22.6	3.1	41	0.96	7.7	3.2	0.1	7	0.4	2.1	0.1	53	0.02	0.057	9
1093098	Soil	10.0	19.1	10.6	101	0.2	25.4	4.5	63	1.40	11.1	2.6	0.1	7	0.4	2.8	0.2	66	0.02	0.051	9
1093099	Soil	2.0	10.0	7.6	27	2.1	9.5	1.4	24	0.53	2.5	3.5	<0.1	10	0.6	0.6	<0.1	18	0.06	0.115	2
1093100	Soil	82.8	73.7	22.8	881	1.9	352.6	19.7	218	3.45	40.5	4.2	2.1	116	11.8	13.6	0.2	232	1.84	0.166	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091661	Soil	21	0.32	176	0.004	3	1.28	0.003	0.18	<0.1	0.13	2.1	0.3	0.07	4	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091662	Soil	27	0.10	279	0.007	6	0.65	0.003	0.18	<0.1	0.33	4.3	0.3	0.07	2	8.2	0.5	N.A.	N.A.	N.A.	N.A.
1091663	Soil	32	0.29	135	0.003	5	1.05	0.002	0.20	<0.1	0.34	4.8	<0.1	<0.05	3	4.3	0.3	N.A.	N.A.	N.A.	N.A.
1091664	Soil	29	0.03	476	0.003	3	0.47	0.003	0.17	<0.1	1.63	3.9	0.8	0.25	2	6.3	0.2	N.A.	N.A.	N.A.	N.A.
1091665	Soil	10	0.08	484	0.003	2	0.71	0.008	0.11	<0.1	0.39	4.2	0.3	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091666	Soil	77	0.10	949	0.005	7	0.80	0.004	0.16	0.4	1.22	5.5	2.0	0.13	3	19.0	0.4	N.A.	N.A.	N.A.	N.A.
1091667	Soil	84	0.09	545	0.005	8	0.43	0.014	0.13	0.5	0.55	1.5	3.1	0.44	4	51.8	0.5	N.A.	N.A.	N.A.	N.A.
1091668	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.2	165.4	52.9	175
1091669	Soil	88	0.06	282	0.006	7	0.77	0.007	0.09	0.3	0.59	1.2	2.4	0.16	3	22.9	0.3	N.A.	N.A.	N.A.	N.A.
1091670	Soil	140	0.20	4230	0.011	13	1.04	0.006	0.18	0.5	2.15	4.8	4.6	0.23	4	53.8	0.7	N.A.	N.A.	N.A.	N.A.
1093081	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	32.3	23.1	25.6	189
1093082	Soil	5	0.01	114	0.003	2	0.22	0.015	0.04	<0.1	0.01	0.2	<0.1	0.13	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093083	Soil	5	0.03	34	0.003	3	0.33	0.020	0.02	<0.1	0.02	<0.1	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093084	Soil	9	0.05	93	0.005	3	0.76	0.017	0.03	<0.1	0.06	0.3	0.4	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093085	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	39.9	60.1	33.4	708
1093086	Soil	21	0.23	608	0.004	5	0.62	0.007	0.05	0.1	0.21	2.4	0.8	0.10	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1093087	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.6	22.8	7.6	92
1093088	Soil	3	<0.01	16	0.003	2	0.15	0.014	0.02	<0.1	0.03	0.3	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093089	Soil	3	<0.01	14	0.004	2	0.11	0.014	0.03	<0.1	0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093090	Soil	2	<0.01	59	0.003	2	0.14	0.018	0.02	<0.1	0.02	0.2	<0.1	<0.05	<1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093091	Soil	3	0.02	118	0.003	2	0.22	0.024	0.02	<0.1	0.04	<0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093092	Soil	7	0.04	250	0.003	3	0.28	0.018	0.03	<0.1	0.09	0.7	0.2	<0.05	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093093	Soil	13	0.02	82	0.004	4	0.31	0.006	0.03	<0.1	0.04	0.3	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093094	Soil	16	0.10	477	0.004	4	0.59	0.009	0.05	0.1	0.14	1.6	0.3	0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093095	Soil	8	0.02	101	0.005	2	0.23	0.004	0.03	<0.1	0.01	0.2	0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093096	Soil	12	0.06	286	0.003	2	0.62	0.007	0.04	<0.1	0.09	0.9	0.3	0.07	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1093097	Soil	8	0.02	173	0.002	3	0.33	0.003	0.04	<0.1	0.03	0.2	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093098	Soil	10	0.02	176	0.003	3	0.35	0.004	0.04	0.1	0.04	0.3	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093099	Soil	7	0.02	272	<0.001	2	0.34	0.017	0.03	<0.1	0.32	0.1	0.2	0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093100	Soil	32	0.33	359	0.001	9	0.33	0.003	0.11	0.1	0.54	5.4	1.8	<0.05	1	9.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091661	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091662	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091663	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091664	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091665	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091666	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091667	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091668	Soil	1.3	34.4	11.7	406	18.06	45.4	11.3	3.5	46	0.4	6.3	0.4	74	0.05	0.187	3	53	0.07	659	0.003
1091669	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091670	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093081	Soil	0.2	50.1	4.3	380	1.10	13.2	1.7	<0.1	7	1.4	4.1	0.1	83	0.06	0.105	3	15	0.02	143	<0.001
1093082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093085	Soil	0.7	127.0	6.7	154	2.70	29.2	2.9	0.9	84	9.7	9.8	0.1	462	1.51	0.120	6	36	0.21	603	0.003
1093086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093087	Soil	<0.1	100.5	11.8	97	1.80	6.8	2.4	0.5	37	0.5	1.3	<0.1	45	1.37	0.129	5	49	0.09	366	0.002
1093088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091661	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091662	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091663	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091664	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091665	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091666	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091667	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091668	Soil	<20	0.91	0.005	0.11	<0.1	0.16	10.3	0.4	0.48	2	6.8	<0.2
1091669	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091670	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093081	Soil	<20	0.27	0.009	0.05	<0.1	0.03	<0.1	0.9	0.07	1	1.4	<0.2
1093082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093085	Soil	<20	0.71	0.007	0.05	0.2	0.20	2.5	0.6	0.12	2	5.0	<0.2
1093086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093087	Soil	<20	0.45	0.014	0.05	<0.1	0.03	2.7	0.2	0.11	2	<0.5	<0.2
1093088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1093101	Soil	17.9	19.8	14.4	119	0.4	41.2	3.4	45	1.15	9.6	1.2	<0.1	29	0.7	3.0	0.2	87	0.35	0.075	5
1093102	Soil	5.2	11.4	6.7	49	1.0	13.7	1.8	27	0.63	4.2	1.8	<0.1	10	0.6	1.2	<0.1	37	0.05	0.079	3
1093103	Soil	9.0	17.1	9.1	138	0.4	30.3	4.6	97	1.20	6.5	3.2	0.3	25	1.5	2.3	0.1	50	0.24	0.088	5
1093104	Soil	10.6	31.2	14.4	243	0.6	50.8	8.8	197	2.20	12.4	2.3	1.7	46	1.3	3.5	0.3	62	0.58	0.111	8
1093105	Soil	2.5	17.6	8.0	206	0.5	33.6	7.5	881	1.19	5.7	5.1	0.9	195	4.8	1.3	0.2	28	14.19	0.060	4
1093106	Soil	3.4	23.7	12.6	186	0.8	34.8	6.3	229	1.74	8.7	4.7	0.9	56	1.8	1.6	0.2	45	0.94	0.087	6
1093107	Soil	5.8	35.7	16.3	324	0.9	49.5	7.8	241	2.63	15.4	6.1	1.5	66	1.7	2.7	0.2	68	0.61	0.125	9
1093108	Soil	6.7	19.8	14.5	123	0.3	24.2	5.4	125	1.62	14.3	2.8	0.1	21	0.4	2.7	0.2	51	0.22	0.071	6
1093109	Soil	9.7	31.7	16.2	194	1.7	46.2	12.6	509	2.30	13.1	9.3	0.9	29	0.8	3.5	0.3	104	0.23	0.146	6
1093110	Soil	4.0	30.9	11.1	102	0.7	37.0	4.2	221	1.42	8.7	5.2	0.5	43	1.3	1.8	0.2	52	0.62	0.110	5
1093111	Soil	7.2	24.6	13.6	176	0.2	32.9	6.9	154	1.92	16.5	6.1	0.4	23	1.1	3.2	0.2	57	0.10	0.109	8
1093112	Soil	3.0	11.2	5.0	77	0.7	12.5	2.2	93	0.73	4.2	3.7	0.1	18	0.7	1.1	0.1	32	0.12	0.076	3
1093113	Soil	15.2	42.1	19.4	303	0.4	54.7	10.9	233	3.24	22.4	5.9	0.4	28	1.2	5.0	0.3	92	0.10	0.103	11
1093114	Soil	20.2	58.1	21.9	437	0.6	75.0	15.7	392	3.57	28.1	7.5	2.3	39	2.8	7.0	0.3	104	0.13	0.110	14
1093115	Soil	13.3	46.2	19.9	382	0.7	70.1	14.5	289	3.24	24.8	6.2	0.9	38	3.1	5.2	0.2	86	0.30	0.107	11
1093116	Soil	5.5	15.6	9.1	167	0.8	26.6	5.8	391	1.43	11.5	4.2	0.3	21	1.5	1.8	0.1	65	0.20	0.112	6
1093117	Soil	21.9	53.1	18.2	747	0.7	127.4	14.4	459	3.27	35.5	1.9	1.7	50	6.6	7.0	0.2	170	0.58	0.209	15
1093118	Soil	27.7	63.3	17.2	756	0.5	175.3	24.1	582	4.03	48.9	2.0	3.2	50	6.3	8.1	0.2	183	0.55	0.210	28
1093119	Soil	29.3	65.9	19.4	1148	0.9	186.4	19.0	535	3.56	47.1	3.3	2.0	60	10.1	8.7	0.2	227	0.97	0.192	18
1093120	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093121	Soil	8.7	35.0	14.5	323	0.6	48.7	6.5	236	1.78	14.7	5.4	0.3	43	4.6	3.5	0.2	70	0.81	0.106	7
1093122	Soil	5.3	5.4	9.0	39	0.2	6.8	1.2	18	0.49	5.5	3.4	<0.1	5	<0.1	1.0	<0.1	47	0.02	0.041	6
1093123	Soil	11.6	21.3	15.7	151	1.0	26.2	3.1	54	1.74	19.5	4.2	0.2	17	0.3	3.6	0.1	102	0.04	0.093	8
1093124	Soil	11.5	34.5	17.4	308	0.9	48.6	6.8	243	2.33	19.0	6.9	0.5	23	1.3	4.0	0.2	103	0.13	0.117	7
1093125	Soil	4.6	7.5	6.6	50	0.3	8.8	1.4	24	0.59	5.3	3.7	<0.1	7	<0.1	1.3	<0.1	34	0.02	0.048	3
1093126	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093127	Soil	11.4	38.3	9.3	936	0.8	133.3	7.4	270	1.63	21.0	6.0	0.3	29	13.0	4.3	0.1	98	0.23	0.104	7
1093128	Soil	11.3	24.9	11.9	338	0.7	53.2	5.7	140	1.77	15.1	8.3	0.7	37	2.8	2.7	0.2	99	0.64	0.114	6
1093129	Soil	1.5	4.3	3.3	22	0.3	4.9	0.5	11	0.34	2.4	2.0	<0.1	8	0.2	0.4	<0.1	19	0.09	0.061	1
1093130	Soil	12.8	35.8	16.5	295	1.6	60.0	6.6	199	2.65	21.6	6.9	0.8	39	2.0	3.5	0.2	132	0.59	0.143	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1093101	Soil	12	0.06	663	0.002	3	0.54	0.012	0.04	<0.1	0.04	0.5	0.4	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093102	Soil	7	0.02	193	0.001	1	0.33	0.013	0.04	<0.1	0.08	0.2	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093103	Soil	12	0.06	419	0.003	3	0.47	0.013	0.05	<0.1	0.12	1.3	0.2	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093104	Soil	15	0.13	478	0.004	3	0.60	0.005	0.05	0.1	0.20	3.1	0.3	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093105	Soil	10	0.25	369	0.005	5	0.43	0.007	0.04	<0.1	0.15	2.1	0.3	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093106	Soil	14	0.16	387	0.004	4	0.66	0.016	0.06	0.1	0.21	2.1	0.2	0.08	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093107	Soil	19	0.20	504	0.005	4	0.85	0.005	0.07	<0.1	0.26	3.5	0.2	0.07	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093108	Soil	10	0.07	264	0.003	2	0.38	0.004	0.04	<0.1	0.05	0.4	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093109	Soil	21	0.10	1209	0.006	7	1.35	0.015	0.08	0.2	0.85	2.6	0.5	0.10	4	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1093110	Soil	10	0.09	954	0.004	4	0.85	0.020	0.04	<0.1	0.46	1.6	0.2	0.11	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093111	Soil	12	0.08	184	0.004	2	0.59	0.008	0.05	<0.1	0.09	0.7	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1093112	Soil	7	0.05	547	0.005	3	0.51	0.020	0.03	<0.1	0.17	0.5	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093113	Soil	18	0.13	415	0.007	5	0.82	0.005	0.08	0.1	0.24	1.2	0.4	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093114	Soil	19	0.18	643	0.012	4	0.83	0.004	0.08	0.1	0.38	3.1	0.4	<0.05	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1093115	Soil	18	0.19	533	0.005	5	0.85	0.009	0.08	<0.1	0.27	2.4	0.4	<0.05	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093116	Soil	11	0.07	345	0.003	3	0.81	0.014	0.04	<0.1	0.16	0.9	0.3	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1093117	Soil	23	0.14	1087	0.003	4	0.63	0.005	0.08	0.1	0.58	3.2	0.8	0.08	2	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1093118	Soil	36	0.15	1619	0.003	6	0.65	0.003	0.10	0.1	0.51	5.3	0.6	<0.05	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1093119	Soil	29	0.39	1134	0.003	5	0.75	0.004	0.09	0.1	0.74	4.2	0.9	0.08	2	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093120	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	10.4	42.7	23.2	473
1093121	Soil	17	0.18	846	0.006	3	0.81	0.014	0.05	<0.1	0.37	1.3	0.3	0.11	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093122	Soil	6	0.02	60	0.002	<1	0.34	0.009	0.03	<0.1	0.02	0.4	0.1	0.07	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093123	Soil	14	0.07	172	0.002	2	0.65	0.006	0.05	0.1	0.19	0.5	0.4	0.06	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093124	Soil	18	0.13	607	0.004	3	0.97	0.012	0.07	0.1	0.37	1.6	0.4	0.08	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093125	Soil	5	0.02	70	0.002	<1	0.23	0.012	0.03	<0.1	0.05	0.3	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093126	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	13.9	27.6	28.8	1462
1093127	Soil	10	0.07	469	0.005	2	0.88	0.017	0.04	0.1	0.51	1.2	1.4	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1093128	Soil	15	0.14	547	0.007	4	1.36	0.016	0.04	0.1	0.25	1.8	0.4	0.09	2	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1093129	Soil	4	0.03	103	0.002	<1	0.26	0.021	0.02	<0.1	0.05	0.3	<0.1	0.06	<1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093130	Soil	22	0.18	941	0.005	3	1.53	0.014	0.08	0.1	0.74	2.6	0.5	0.06	4	3.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1093101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093120	Soil	1.0	74.1	13.2	1009	2.82	20.5	4.9	1.0	52	4.1	3.6	0.2	81	1.01	0.194	9	19	0.24	869	0.008
1093121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093126	Soil	0.7	120.6	5.6	271	1.59	19.3	4.4	0.6	86	7.2	4.3	0.1	146	1.15	0.129	9	20	0.17	834	0.003
1093127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093120	Soil	<20	0.82	0.008	0.07	0.1	0.38	2.5	0.4	0.12	2	2.6	<0.2
1093121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093126	Soil	<20	0.53	0.008	0.06	0.1	0.38	1.4	0.7	0.12	2	3.8	<0.2
1093127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1093131	Soil	15.2	23.0	14.6	177	0.8	31.3	5.2	130	2.05	18.3	3.6	0.3	20	1.2	3.4	0.2	125	0.09	0.134	7
1093132	Soil	9.5	32.1	10.5	216	1.7	46.0	4.8	183	1.50	12.5	4.5	0.4	43	4.7	3.4	0.1	98	0.86	0.137	6
1093133	Soil	12.0	38.6	19.5	430	1.6	73.0	8.8	512	2.10	22.0	9.6	0.7	54	5.8	4.9	0.2	172	0.82	0.141	8
1093134	Soil	1.9	4.6	3.7	41	0.3	5.9	0.4	11	0.22	1.1	6.3	0.1	23	0.9	0.5	<0.1	19	0.44	0.044	1
1093135	Soil	2.8	45.2	17.3	23	1.3	4.7	1.2	55	2.87	28.4	10.0	1.0	14	<0.1	6.7	0.2	131	0.03	0.066	4
1093136	Soil	5.7	87.7	21.1	129	2.1	25.3	4.1	229	6.89	72.0	8.3	1.3	43	0.6	11.8	0.3	229	0.05	0.159	6
1093137	Soil	5.1	16.6	15.8	28	1.0	6.0	1.3	46	1.80	14.0	8.3	1.1	70	<0.1	3.9	0.3	56	0.03	0.068	3
1093138	Soil	7.3	19.7	19.6	29	1.6	8.4	2.0	96	1.72	12.4	9.3	1.1	45	<0.1	3.4	0.3	56	0.04	0.066	6
1093139	Soil	10.3	23.5	22.1	32	1.2	6.8	1.5	32	2.51	29.7	4.8	0.3	35	<0.1	8.5	0.3	161	0.02	0.082	7
1093140	Soil	6.4	25.5	38.1	33	1.2	10.2	2.0	80	2.41	34.0	7.8	0.8	49	<0.1	7.2	0.2	110	0.06	0.129	7
1093141	Soil	122.8	92.4	48.9	16	6.7	7.6	0.4	15	5.84	45.1	7.8	4.5	156	<0.1	60.8	0.5	366	0.03	0.649	18
1093142	Soil	41.2	35.5	45.4	10	2.7	3.0	0.4	12	5.08	23.7	5.4	2.1	52	<0.1	15.7	0.4	166	0.02	0.164	6
1093143	Soil	10.0	24.3	26.0	24	2.2	8.2	0.9	36	2.01	20.2	7.4	0.2	36	<0.1	6.9	0.2	91	0.04	0.103	5
1093144	Soil	6.0	29.2	16.5	44	0.8	10.3	2.0	52	2.62	27.0	5.3	0.3	20	0.1	5.4	0.2	115	0.02	0.062	8
1093145	Soil	2.5	30.9	8.9	41	0.8	11.4	2.8	110	1.51	12.7	5.8	0.4	14	0.1	2.6	0.1	54	0.07	0.071	6
1093146	Soil	3.5	39.7	11.4	73	1.1	18.2	5.3	200	2.17	21.9	7.2	1.4	24	0.3	3.9	0.1	91	0.13	0.103	10
1093147	Soil	5.0	35.8	18.2	63	2.1	16.3	3.8	86	2.25	16.3	6.5	0.3	24	0.2	3.6	0.2	79	0.06	0.064	8
1093148	Soil	0.8	4.3	4.4	8	0.4	3.0	0.5	11	0.30	1.3	2.7	<0.1	5	<0.1	0.4	<0.1	10	0.02	0.023	2
1093149	Soil	3.9	14.6	10.1	78	0.2	14.6	4.0	119	1.50	8.6	<0.5	<0.1	8	<0.1	1.6	0.2	35	0.02	0.062	4
1093150	Soil	2.2	4.7	5.8	28	<0.1	5.8	1.4	19	0.53	3.6	<0.5	<0.1	5	<0.1	0.7	0.1	20	0.01	0.054	3
1093151	Soil	2.4	11.3	10.2	59	0.3	12.2	3.6	31	1.13	5.7	4.3	0.2	5	<0.1	0.8	0.1	22	0.02	0.048	2
1093152	Soil	1.4	5.2	8.0	13	1.0	4.2	0.6	10	0.58	2.6	4.4	<0.1	4	<0.1	0.3	0.1	12	0.01	0.040	2
1093153	Soil	1.4	1.7	2.8	11	1.2	2.1	0.5	8	0.23	2.0	<0.5	<0.1	3	<0.1	0.3	<0.1	12	0.01	0.038	1
1093154	Soil	5.0	4.1	18.7	26	0.2	4.1	0.6	11	0.49	9.5	2.7	<0.1	32	<0.1	1.3	0.1	38	0.01	0.039	9
1093155	Soil	10.3	5.5	9.6	34	0.6	7.9	0.9	14	0.54	10.1	3.1	<0.1	10	<0.1	1.8	<0.1	55	0.03	0.046	10
1093156	Soil	17.5	20.5	35.2	90	1.0	17.5	1.8	36	1.86	23.4	3.9	0.3	37	1.1	6.1	0.2	104	0.14	0.082	5
1093157	Soil	8.9	17.0	21.9	122	0.4	23.3	3.1	47	1.37	11.9	<0.5	0.1	23	0.3	2.4	0.2	49	0.02	0.092	6
1093158	Soil	2.8	5.8	6.0	33	0.7	8.0	0.8	13	0.43	1.7	<0.5	<0.1	11	0.2	0.8	<0.1	27	0.03	0.075	2
1093159	Soil	1.7	3.2	2.8	14	0.4	3.0	0.5	8	0.29	1.6	<0.5	<0.1	5	<0.1	0.4	<0.1	18	0.02	0.048	2
1093160	Soil	0.1	1.0	0.5	3	0.2	1.1	0.2	6	0.11	<0.5	<0.5	<0.1	4	<0.1	0.1	<0.1	5	0.02	0.020	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1093131	Soil	16	0.08	705	0.004	2	0.98	0.008	0.06	0.2	0.23	1.0	0.4	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093132	Soil	13	0.18	979	0.005	3	1.20	0.019	0.05	<0.1	0.74	1.4	0.3	0.08	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1093133	Soil	22	0.22	781	0.003	2	1.11	0.010	0.08	0.2	0.86	2.1	0.6	0.05	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1093134	Soil	3	0.06	183	0.007	<1	0.23	0.027	0.02	<0.1	0.11	0.7	0.1	<0.05	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093135	Soil	32	0.05	237	0.004	1	0.46	0.009	0.06	0.1	0.12	1.9	0.2	<0.05	5	8.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093136	Soil	55	0.09	577	0.010	2	0.68	0.009	0.12	0.1	0.21	4.5	0.3	0.23	7	17.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093137	Soil	21	0.05	305	0.004	1	0.30	0.005	0.13	<0.1	0.05	2.8	0.6	0.22	3	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093138	Soil	18	0.09	411	0.008	2	0.48	0.009	0.14	0.1	0.07	1.6	0.5	0.23	4	4.6	0.2	N.A.	N.A.	N.A.	N.A.
1093139	Soil	23	0.02	358	0.007	<1	0.40	0.005	0.08	0.2	0.11	0.9	0.4	0.08	6	6.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093140	Soil	28	0.10	351	0.019	<1	0.60	0.013	0.08	0.2	0.15	2.1	0.4	0.08	5	5.4	0.2	N.A.	N.A.	N.A.	N.A.
1093141	Soil	58	0.02	122	0.009	5	0.49	0.010	0.38	0.6	0.45	7.0	4.8	0.85	8	63.1	0.8	N.A.	N.A.	N.A.	N.A.
1093142	Soil	32	0.02	319	0.004	4	0.30	0.008	0.22	0.2	0.30	3.0	1.7	0.46	7	20.9	0.4	N.A.	N.A.	N.A.	N.A.
1093143	Soil	27	0.05	886	0.006	3	0.46	0.009	0.13	0.2	0.21	1.6	0.7	0.18	4	8.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093144	Soil	22	0.05	244	0.010	2	0.39	0.005	0.07	0.1	0.10	0.9	0.2	0.11	5	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1093145	Soil	15	0.10	145	0.018	1	0.70	0.015	0.05	0.1	0.21	1.3	0.2	0.10	3	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093146	Soil	21	0.18	211	0.024	2	0.82	0.010	0.07	0.2	0.50	2.1	0.2	0.08	4	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1093147	Soil	21	0.16	328	0.010	2	0.88	0.013	0.07	0.1	1.09	1.4	0.5	0.09	4	5.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093148	Soil	5	0.02	100	0.004	<1	0.36	0.017	0.02	<0.1	0.09	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093149	Soil	12	0.02	118	0.005	3	0.33	0.008	0.04	0.2	0.04	0.4	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093150	Soil	6	0.01	40	0.003	<1	0.21	0.009	0.02	<0.1	<0.01	0.2	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093151	Soil	9	0.01	37	0.003	1	0.32	0.007	0.03	<0.1	<0.01	0.8	<0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1093152	Soil	6	0.01	32	0.003	2	0.33	0.011	0.02	<0.1	0.03	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093153	Soil	3	<0.01	22	0.002	<1	0.11	0.014	0.02	<0.1	0.03	0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093154	Soil	5	0.01	290	0.003	2	0.23	0.003	0.06	<0.1	0.01	0.1	0.3	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093155	Soil	11	0.01	107	0.002	2	0.18	0.006	0.04	<0.1	0.02	0.2	0.3	<0.05	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093156	Soil	18	0.02	1756	0.003	2	0.25	0.005	0.07	0.1	0.41	1.0	1.0	0.12	3	8.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093157	Soil	10	0.03	248	0.003	1	0.44	0.007	0.05	0.1	0.03	0.3	0.3	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093158	Soil	7	0.01	165	0.005	<1	0.22	0.012	0.02	<0.1	<0.01	0.5	0.2	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093159	Soil	4	0.01	47	0.002	<1	0.19	0.013	0.02	<0.1	0.03	0.3	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093160	Soil	2	<0.01	15	0.004	<1	0.08	0.017	0.01	<0.1	<0.01	0.4	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1093131	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093132	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093133	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093134	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093135	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093136	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093137	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093138	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093139	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093140	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093141	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093142	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093143	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093144	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093145	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093146	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093147	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093148	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093149	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093150	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093151	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093152	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093153	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093154	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093155	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093156	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093157	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093158	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093159	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093160	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093141	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093142	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093143	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093144	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093145	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093146	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093147	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093148	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093149	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093150	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093151	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093152	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093153	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093154	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093155	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093156	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093157	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093158	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093159	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093160	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1093161	Soil	2.3	4.1	4.2	23	0.3	4.6	0.8	11	0.34	3.0	<0.5	<0.1	6	<0.1	0.5	<0.1	26	0.01	0.038	5
1093162	Soil	3.0	4.5	3.3	28	0.1	5.6	1.0	15	0.36	3.0	<0.5	<0.1	5	<0.1	0.8	<0.1	27	0.01	0.040	3
1093163	Soil	1.6	2.2	2.7	28	0.2	5.9	0.5	8	0.25	1.6	<0.5	<0.1	7	0.1	0.5	<0.1	37	0.02	0.037	1
1093164	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093165	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093166	Soil	4.9	17.8	8.6	222	1.0	41.0	1.3	28	0.57	7.4	1.6	0.1	23	2.5	2.3	<0.1	80	0.30	0.097	4
1093167	Soil	14.7	21.0	22.8	46	3.0	11.9	2.6	82	2.64	45.3	2.7	0.3	211	0.5	12.4	0.2	109	0.07	0.163	9
1093168	Soil	6.0	30.3	14.4	67	1.4	17.9	4.7	155	2.51	36.8	4.8	0.6	58	0.3	5.7	0.2	96	0.13	0.169	11
1093169	Soil	14.6	20.0	31.0	28	7.9	5.8	1.0	34	4.40	92.5	8.2	0.7	296	0.1	23.0	0.4	137	0.03	0.272	8
1093170	Soil	5.5	25.4	11.7	39	1.2	8.3	2.6	91	3.41	43.6	2.0	1.5	102	0.1	7.7	0.1	100	0.08	0.175	8
1093171	Soil	9.1	15.1	20.3	19	1.1	3.6	0.7	23	3.81	53.4	3.1	1.0	182	<0.1	10.2	0.2	139	0.01	0.148	10
1093172	Soil	3.9	3.0	11.8	11	0.2	5.4	0.7	14	0.44	4.0	2.0	<0.1	5	<0.1	0.8	<0.1	26	0.02	0.028	4
1093173	Soil	1.0	1.7	4.2	4	0.3	1.3	0.4	7	0.25	1.5	0.8	<0.1	9	<0.1	0.4	<0.1	12	0.02	0.037	1
1093174	Soil	5.3	2.2	4.1	10	0.2	4.8	0.4	7	0.28	5.9	<0.5	<0.1	5	<0.1	0.8	0.1	16	0.03	0.035	<1
1093175	Soil	17.6	3.1	4.5	11	0.5	1.8	0.4	8	0.79	8.3	0.6	<0.1	14	<0.1	4.4	<0.1	77	0.01	0.028	4
1093176	Soil	5.5	7.7	11.0	7	2.3	2.2	0.3	8	0.53	5.5	7.9	<0.1	16	<0.1	1.4	0.1	38	0.02	0.088	2
1093177	Soil	9.4	7.4	11.9	23	0.5	6.3	1.0	20	1.56	19.2	2.1	0.4	9	0.1	2.3	0.1	75	0.02	0.088	2
1093178	Soil	11.4	23.0	10.4	27	1.4	5.8	1.0	16	4.26	27.9	9.8	0.2	15	0.2	8.3	0.1	136	0.02	0.121	3
1093179	Soil	6.6	11.8	24.9	60	0.4	17.2	4.7	109	1.78	14.4	<0.5	<0.1	11	0.2	2.3	<0.1	49	0.03	0.071	3
1093180	Soil	15.6	23.8	17.9	97	0.8	19.0	8.5	349	2.27	41.6	4.0	1.0	35	0.3	6.2	0.2	99	0.06	0.092	8
1093181	Soil	2.3	15.2	6.5	73	<0.1	17.6	6.9	60	1.46	8.8	<0.5	0.3	6	0.2	1.0	0.1	22	0.01	0.033	3
1093182	Soil	8.8	4.0	14.9	16	0.5	3.0	0.4	9	0.38	7.0	<0.5	0.2	11	<0.1	3.6	<0.1	51	0.01	0.031	6
1093183	Soil	4.8	4.9	10.6	15	0.2	2.7	0.8	15	0.35	3.3	1.2	<0.1	6	<0.1	1.1	<0.1	39	0.02	0.024	4
1093184	Soil	104.3	20.4	68.2	39	1.6	8.4	1.5	31	2.33	76.3	4.3	0.5	92	<0.1	26.4	0.4	210	0.02	0.160	12
1093185	Soil	8.6	8.1	11.3	20	0.2	4.7	1.1	38	0.85	7.9	0.9	<0.1	8	<0.1	1.9	0.2	71	0.02	0.029	8
1093186	Soil	20.9	11.3	19.3	29	1.7	6.3	1.1	20	0.77	11.4	2.3	0.1	21	<0.1	7.4	0.2	141	0.01	0.036	10
1093187	Soil	8.3	4.9	47.7	12	1.0	4.2	0.5	8	0.77	5.1	0.7	0.1	8	<0.1	4.2	0.1	35	0.01	0.033	4
1093188	Soil	5.2	10.2	14.9	19	2.3	5.6	0.6	9	0.45	3.3	0.5	<0.1	9	0.1	1.1	0.1	67	0.01	0.060	6
1093189	Soil	9.5	6.1	8.9	34	0.4	12.6	0.8	7	0.29	5.1	0.6	<0.1	5	<0.1	1.0	<0.1	36	0.01	0.035	5
1093190	Soil	37.5	16.4	25.6	104	0.5	26.2	2.2	24	1.12	30.0	2.5	<0.1	22	0.2	8.1	0.2	161	0.01	0.056	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1093161	Soil	4	0.01	48	0.003	<1	0.22	0.010	0.02	<0.1	<0.01	0.4	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093162	Soil	4	<0.01	35	0.006	<1	0.15	0.011	0.02	<0.1	<0.01	0.3	0.1	<0.05	1	0.7	0.2	N.A.	N.A.	N.A.	N.A.
1093163	Soil	6	0.01	74	0.003	<1	0.16	0.013	0.02	<0.1	0.04	0.3	0.2	<0.05	<1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093164	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	18.2	40.5	18.2	671
1093165	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	19.4	58.1	20.4	678
1093166	Soil	11	0.06	363	0.006	<1	0.52	0.024	0.04	<0.1	0.27	0.6	0.4	0.07	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093167	Soil	21	0.09	704	0.008	1	0.66	0.012	0.14	0.1	0.33	0.9	1.3	0.17	4	7.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093168	Soil	24	0.21	313	0.015	1	0.92	0.007	0.08	0.2	0.21	1.4	0.6	0.06	5	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093169	Soil	34	0.03	268	0.004	2	0.44	0.013	0.23	0.2	0.34	1.6	1.9	0.27	5	16.8	0.2	N.A.	N.A.	N.A.	N.A.
1093170	Soil	17	0.10	744	0.017	<1	0.52	0.014	0.13	0.1	0.17	2.0	0.7	0.11	4	6.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093171	Soil	23	0.03	236	0.006	<1	0.29	0.006	0.32	0.2	0.17	0.7	1.0	0.26	3	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093172	Soil	8	<0.01	441	0.003	<1	0.15	0.016	0.02	<0.1	<0.01	0.1	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093173	Soil	3	<0.01	375	0.003	<1	0.17	0.017	0.02	<0.1	0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093174	Soil	7	<0.01	105	0.002	<1	0.10	0.016	0.01	<0.1	<0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093175	Soil	5	<0.01	51	0.005	<1	0.09	0.016	0.02	0.1	0.01	0.3	<0.1	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093176	Soil	7	0.01	171	0.002	<1	0.35	0.013	0.03	<0.1	0.99	0.4	1.3	<0.05	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093177	Soil	11	0.02	115	0.002	<1	0.36	0.007	0.03	<0.1	0.22	0.4	1.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093178	Soil	9	0.02	128	0.003	<1	0.49	0.008	0.02	0.1	0.99	0.5	1.4	<0.05	2	16.8	0.3	N.A.	N.A.	N.A.	N.A.
1093179	Soil	11	0.02	148	0.004	<1	0.15	0.009	0.03	<0.1	0.07	1.0	0.8	<0.05	1	1.8	0.4	N.A.	N.A.	N.A.	N.A.
1093180	Soil	20	0.09	598	0.007	<1	0.45	0.003	0.06	0.1	0.49	2.3	0.7	<0.05	2	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1093181	Soil	8	0.02	36	0.003	<1	0.27	0.007	0.03	<0.1	<0.01	1.3	0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1093182	Soil	4	0.01	139	0.003	<1	0.18	0.005	0.04	<0.1	0.07	0.4	0.8	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093183	Soil	5	0.01	54	0.004	<1	0.19	0.015	0.02	0.2	<0.01	0.3	0.3	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093184	Soil	25	0.01	664	0.011	<1	0.29	0.003	0.15	0.5	0.16	1.9	1.7	0.16	5	30.4	0.4	N.A.	N.A.	N.A.	N.A.
1093185	Soil	10	0.04	118	0.009	1	0.59	0.008	0.03	<0.1	0.04	0.2	0.3	<0.05	5	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093186	Soil	11	0.02	291	0.008	2	0.44	0.008	0.05	0.1	0.08	0.3	0.8	0.06	3	5.0	0.2	N.A.	N.A.	N.A.	N.A.
1093187	Soil	8	<0.01	163	0.003	1	0.18	0.007	0.13	<0.1	0.02	0.1	0.4	0.24	1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093188	Soil	13	0.02	78	0.003	<1	0.67	0.011	0.03	<0.1	0.04	0.2	0.4	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093189	Soil	7	0.02	57	0.004	4	0.34	0.008	0.03	<0.1	0.01	<0.1	0.5	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093190	Soil	14	0.02	224	0.002	1	0.37	0.004	0.07	0.2	0.08	0.2	1.0	0.07	3	3.8	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1093161	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093162	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093163	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093164	Soil	1.3	111.2	4.9	131	1.42	19.1	7.1	0.5	77	6.7	5.6	0.2	247	0.63	0.180	13	37	0.15	1826	0.004
1093165	Soil	1.5	146.7	5.0	304	1.58	26.6	7.9	0.3	87	13.7	6.4	0.2	259	1.08	0.185	7	35	0.20	1772	0.003
1093166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093174	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093175	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093176	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093178	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093180	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093161	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093162	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093163	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093164	Soil	<20	0.80	0.008	0.11	0.2	0.66	1.7	1.3	0.12	2	3.9	<0.2
1093165	Soil	<20	0.84	0.011	0.11	0.2	0.73	1.2	1.2	0.18	2	6.0	<0.2
1093166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093174	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093175	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093176	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093178	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093180	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1093191	Soil		52.7	34.7	28.8	233	0.7	64.6	4.1	41	2.02	45.4	5.5	0.5	39	0.9	14.9	0.2	222	0.02	0.085	11
1093192	Soil		26.1	58.8	43.9	121	0.4	31.3	1.8	18	0.94	38.8	2.6	<0.1	59	0.3	9.2	0.2	172	0.04	0.089	16
1093193	Soil		6.3	4.8	10.9	29	0.5	8.3	0.6	8	0.26	3.0	<0.5	<0.1	5	0.1	1.2	<0.1	69	0.01	0.048	8
1093194	Soil		1.9	3.2	12.0	11	0.3	5.8	0.4	7	0.16	1.3	1.2	<0.1	5	0.2	0.5	<0.1	25	0.02	0.043	<1
1093195	Soil		49.7	57.3	30.2	600	0.8	115.2	5.4	107	2.19	47.7	3.9	0.4	32	5.1	19.3	0.2	440	0.16	0.095	23
1093196	Soil		8.3	44.9	9.7	426	0.2	154.9	36.3	581	4.97	104.2	1.6	1.2	76	4.0	5.4	<0.1	225	0.88	0.142	24
1093197	Soil		91.3	113.5	16.0	975	1.3	198.8	15.5	112	2.97	89.1	3.2	1.5	51	10.5	22.0	0.2	501	0.48	0.089	27
1093198	Soil		65.6	80.8	27.6	1281	1.2	210.4	14.9	216	3.45	87.9	3.9	0.6	55	8.1	18.7	0.2	390	0.42	0.212	22
1093199	Soil		29.9	34.4	35.0	407	0.5	66.8	3.5	31	1.17	32.3	2.8	0.1	6	0.8	9.7	0.1	182	0.03	0.053	7
1093200	Soil		7.5	47.6	48.7	45	0.9	31.0	1.8	23	0.76	13.2	8.2	<0.1	8	<0.1	3.7	0.2	33	0.04	0.084	3
1093211	Soil		12.8	38.3	33.9	180	0.2	37.7	6.1	94	2.31	35.8	1.4	0.3	34	0.2	6.4	0.3	128	0.02	0.105	10
1093212	Soil		4.1	13.4	27.1	48	1.4	9.9	1.4	45	0.94	11.5	5.0	<0.1	37	0.1	1.5	0.2	42	0.03	0.166	6
1093213	Soil		2.0	16.7	13.7	160	1.5	21.2	2.1	69	0.83	6.1	1.6	<0.1	19	<0.1	1.0	<0.1	28	0.17	0.152	4
1093214	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093215	Soil		2.1	7.1	5.0	32	0.7	8.0	1.3	143	0.43	2.7	1.1	0.1	11	0.5	0.5	<0.1	21	0.07	0.146	3
1093216	Soil		25.1	93.8	25.0	322	1.4	110.0	35.3	516	6.38	47.3	2.7	1.7	49	0.8	8.9	0.2	187	0.13	0.287	11
1093217	Soil		8.0	19.3	11.5	26	0.5	20.4	1.0	12	30.10	32.3	1.0	1.2	9	0.3	5.7	<0.1	127	0.06	0.064	3
1093218	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1093219	Soil		4.4	14.9	5.9	75	1.0	22.4	1.4	50	0.71	4.6	<0.5	<0.1	13	0.8	1.3	<0.1	37	0.18	0.108	4
1093220	Soil		3.8	24.2	4.2	25	0.7	10.1	1.0	37	0.54	5.2	<0.5	<0.1	8	0.5	0.8	<0.1	40	0.05	0.208	2
1093231	Soil		15.4	18.2	9.2	139	0.3	39.0	4.4	255	1.06	14.5	0.8	0.1	9	1.1	2.6	<0.1	69	0.06	0.111	3
1093232	Soil		21.7	54.7	15.9	388	0.4	145.9	16.4	216	3.37	49.6	0.7	0.3	27	2.9	6.7	0.1	162	0.22	0.194	6
1093233	Soil		29.5	42.0	17.8	277	0.2	97.3	13.7	176	3.25	20.4	1.6	0.2	9	0.7	5.3	0.2	132	0.05	0.126	7
1093234	Soil		26.0	25.7	13.2	283	0.1	60.2	6.4	116	2.17	18.5	1.2	0.2	8	0.8	6.4	0.2	131	0.03	0.077	5
1093235	Soil		25.7	66.0	25.6	617	0.9	102.6	10.2	146	2.70	30.1	3.5	1.8	52	4.6	10.1	0.2	142	0.49	0.139	7
1093236	Soil		8.6	39.1	14.9	157	0.6	38.9	4.4	109	1.77	14.8	2.0	0.4	11	0.6	3.6	0.2	53	0.09	0.131	3
1093237	Soil		38.7	41.1	115.5	25	4.5	9.0	0.7	44	0.75	9.0	11.2	0.8	15	0.4	13.8	0.5	163	0.03	0.034	49
1093238	Soil		6.4	98.0	48.9	178	1.2	78.2	21.2	672	4.15	41.1	6.6	0.9	47	0.7	5.2	0.4	50	0.07	0.113	8
1093239	Soil		64.3	119.4	41.4	1263	3.1	293.2	9.4	262	2.78	49.0	1.7	3.6	174	14.9	23.5	0.2	463	6.68	0.285	9
1093240	Soil		65.6	114.8	48.0	1286	2.6	242.4	9.0	297	2.59	43.6	2.4	2.9	226	17.1	19.7	0.2	492	7.02	0.264	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1093191	Soil		16	0.02	535	0.003	3	0.32	0.003	0.10	0.2	0.51	1.2	1.5	0.18	2	6.4	0.2	N.A.	N.A.	N.A.	N.A.
1093192	Soil		31	0.02	186	0.002	2	0.45	0.003	0.04	<0.1	0.42	0.1	0.8	<0.05	3	4.5	0.2	N.A.	N.A.	N.A.	N.A.
1093193	Soil		10	0.01	86	0.002	<1	0.22	0.010	0.03	<0.1	0.03	0.1	0.4	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093194	Soil		8	<0.01	46	0.002	<1	0.14	0.015	0.03	<0.1	0.06	0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093195	Soil		43	0.05	562	0.008	3	0.45	0.003	0.08	1.3	0.45	1.1	1.0	0.05	2	9.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093196	Soil		167	2.77	1168	0.086	4	2.77	0.015	0.08	<0.1	0.10	9.4	0.7	0.06	9	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1093197	Soil		37	0.16	744	0.002	2	0.91	0.006	0.09	0.1	0.52	3.2	1.5	<0.05	3	6.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093198	Soil		52	0.24	685	0.006	2	0.93	0.007	0.10	0.2	0.60	2.5	1.6	<0.05	3	6.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093199	Soil		33	0.02	103	0.002	2	0.31	0.008	0.06	0.1	0.21	0.4	0.4	<0.05	2	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1093200	Soil		33	0.02	80	0.004	2	0.22	0.017	0.04	<0.1	0.04	0.1	0.2	<0.05	1	2.5	0.2	N.A.	N.A.	N.A.	N.A.
1093211	Soil		18	0.03	361	0.005	1	0.61	0.003	0.06	<0.1	0.08	0.4	0.4	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093212	Soil		15	0.03	471	0.002	2	0.68	0.012	0.07	<0.1	0.55	<0.1	0.8	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093213	Soil		12	0.05	314	0.006	3	0.48	0.022	0.05	<0.1	0.20	0.5	0.2	0.06	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093214	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.0	14.8	11.1	48
1093215	Soil		7	0.03	157	0.004	2	0.68	0.021	0.04	<0.1	0.17	0.4	0.2	0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093216	Soil		42	0.04	1510	0.005	6	0.97	0.005	0.16	<0.1	0.79	5.0	1.2	0.11	2	5.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093217	Soil		12	0.01	176	0.002	2	0.29	0.003	0.04	<0.1	0.27	1.9	0.1	0.71	<1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093218	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	9.2	35.2	16.4	170
1093219	Soil		9	0.05	302	0.004	2	0.64	0.021	0.04	<0.1	0.16	0.2	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093220	Soil		7	0.02	167	0.003	1	0.59	0.017	0.04	<0.1	0.12	0.3	0.5	0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093231	Soil		19	0.03	77	0.004	<1	0.32	0.015	0.04	<0.1	0.03	0.4	0.2	<0.05	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093232	Soil		67	0.05	179	0.006	4	0.64	0.010	0.06	<0.1	0.18	2.2	0.5	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1093233	Soil		47	0.04	94	0.006	<1	0.50	0.004	0.06	<0.1	0.03	0.8	0.3	<0.05	2	1.7	0.2	N.A.	N.A.	N.A.	N.A.
1093234	Soil		18	0.03	96	0.004	1	0.42	0.007	0.05	<0.1	0.04	0.3	0.3	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093235	Soil		18	0.08	280	0.003	2	0.32	0.004	0.06	<0.1	0.56	4.1	0.3	<0.05	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093236	Soil		15	0.02	94	0.004	<1	0.40	0.007	0.04	<0.1	0.08	1.1	0.1	<0.05	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093237	Soil		28	0.01	269	0.017	3	0.33	0.002	0.08	0.3	1.48	0.7	0.9	0.06	1	10.6	0.6	N.A.	N.A.	N.A.	N.A.
1093238	Soil		17	0.10	214	0.005	1	0.69	0.004	0.07	<0.1	0.07	3.0	0.3	0.09	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093239	Soil		59	3.50	313	0.005	7	0.39	0.008	0.11	0.1	0.54	4.3	0.8	0.05	1	14.5	0.2	N.A.	N.A.	N.A.	N.A.
1093240	Soil		46	3.52	256	0.006	8	0.43	0.008	0.11	0.1	0.48	4.0	0.8	<0.05	1	8.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1093191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093214	Soil	0.9	13.4	1.4	46	0.85	10.4	3.6	<0.1	15	0.8	1.6	<0.1	43	0.11	0.117	3	15	0.04	385	0.002
1093215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093218	Soil	2.8	56.0	7.6	376	1.68	13.0	4.6	0.1	30	2.4	2.4	0.2	70	0.41	0.162	7	21	0.09	591	0.004
1093219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093231	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093232	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093233	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093234	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093235	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093236	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093237	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093238	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093239	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093240	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093214	Soil	<20	0.37	0.020	0.03	0.1	0.48	<0.1	0.2	0.08	1	1.4	<0.2
1093215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093218	Soil	<20	1.17	0.019	0.07	<0.1	0.67	0.5	0.4	0.12	4	2.5	<0.2
1093219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093231	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093232	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093233	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093234	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093235	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093236	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093237	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093238	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093239	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093240	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1093241	Soil	59.7	104.8	42.8	1299	2.2	221.1	8.6	170	2.79	39.5	4.2	1.6	180	16.0	18.6	0.2	388	4.23	0.286	9
1093242	Soil	56.5	75.1	23.1	848	1.2	183.6	8.9	187	2.41	31.9	2.3	0.7	80	10.1	19.4	0.2	275	0.86	0.214	11
1093243	Soil	63.3	116.2	42.8	1280	1.9	299.8	20.3	428	4.05	37.9	4.9	1.6	157	14.0	17.3	0.2	326	2.98	0.288	12
1093244	Soil	17.8	36.9	21.5	197	0.2	52.0	8.1	90	2.41	23.7	1.7	<0.1	13	0.3	6.7	0.2	87	0.03	0.091	6
1093245	Soil	15.4	22.4	11.6	113	<0.1	33.0	5.8	64	1.62	14.5	0.6	<0.1	9	0.3	3.4	0.2	69	0.02	0.070	7
1093246	Soil	28.4	32.0	19.4	225	0.1	49.1	7.9	121	2.48	21.1	3.2	<0.1	11	0.3	6.9	0.2	121	0.02	0.080	8
1093247	Soil	9.8	17.1	7.4	213	1.1	24.7	2.5	50	0.64	7.1	0.8	<0.1	11	4.2	4.5	<0.1	60	0.17	0.052	2
1093248	Soil	9.2	35.4	16.4	249	0.3	52.4	7.5	172	2.38	14.3	1.5	0.2	25	1.0	4.3	0.2	70	0.23	0.128	6
1093249	Soil	6.1	32.4	15.0	141	0.5	34.4	6.2	96	1.90	8.8	1.4	0.3	35	0.7	2.5	0.2	40	0.22	0.120	7
1093250	Soil	5.9	39.1	13.8	143	0.4	30.1	6.4	78	1.95	8.3	1.9	0.2	34	<0.1	2.4	0.2	38	0.06	0.116	7
1093451	Soil	2.9	25.4	15.5	69	0.4	21.0	3.6	74	1.92	11.1	3.7	0.1	16	0.2	1.1	0.2	32	0.11	0.100	5
1093452	Soil	1.9	23.8	7.4	51	0.9	15.2	2.1	57	1.10	5.6	4.0	<0.1	30	0.3	0.7	0.1	17	0.34	0.124	4
1093453	Soil	2.7	31.7	17.1	126	2.6	46.3	6.8	128	2.61	14.6	8.7	1.3	51	0.7	1.1	0.2	24	0.57	0.127	7
1093454	Soil	3.0	28.8	11.6	118	1.6	34.8	5.1	113	1.96	47.7	140.1	1.3	84	0.7	2.5	0.2	34	0.86	0.108	8
1093455	Soil	4.2	36.3	27.2	96	0.7	25.9	4.0	64	2.06	17.2	4.2	0.3	15	0.2	1.9	0.2	53	0.05	0.082	7
1093456	Soil	3.1	52.0	31.0	102	1.6	32.6	5.1	61	1.97	59.7	9.6	0.9	76	0.4	2.2	0.3	25	0.13	0.134	4
1093457	Soil	4.2	55.5	24.5	121	1.9	40.1	5.1	77	3.35	98.3	29.2	0.6	48	0.3	2.3	0.3	45	0.03	0.115	6
1093458	Soil	3.8	12.2	4.2	31	0.1	11.7	3.5	38	1.04	5.1	6.1	0.2	4	<0.1	1.1	0.1	36	<0.01	0.022	14
1093459	Soil	37.7	54.2	35.9	114	0.6	133.5	10.7	364	2.94	17.2	2.4	3.1	195	0.4	7.7	0.2	59	8.88	0.076	6
1093460	Soil	1.1	5.4	3.9	12	0.2	6.1	1.4	17	0.36	1.0	<0.5	<0.1	6	<0.1	0.4	<0.1	7	0.05	0.034	2
1094201	Soil	4.6	66.7	39.9	167	1.0	37.9	15.8	389	3.76	20.6	3.1	3.8	32	0.3	4.4	0.5	42	0.05	0.097	6
1094202	Soil	4.2	71.6	54.5	168	1.7	37.8	35.6	1340	3.36	15.3	4.2	4.1	23	0.6	3.1	0.4	33	0.07	0.131	6
1094203	Soil	4.1	82.0	32.7	200	1.2	39.1	17.8	557	3.33	17.9	2.7	1.9	30	0.4	4.6	0.4	43	0.02	0.106	4
1094204	Soil	5.1	81.1	35.2	222	0.8	48.7	18.8	558	4.55	26.6	4.9	1.4	38	0.6	8.7	0.4	58	0.02	0.113	4
1094205	Soil	5.1	81.5	26.7	230	1.3	41.6	17.8	534	3.37	17.1	3.8	2.1	41	0.8	5.0	0.3	48	0.02	0.075	3
1094206	Soil	9.3	154.7	26.5	131	3.1	61.4	15.7	713	4.26	212.6	24.0	0.9	192	2.2	17.0	0.4	111	0.04	0.222	4
1094207	Soil	4.5	78.7	17.0	166	1.9	103.2	13.4	1663	9.19	61.3	7.1	1.2	89	2.7	5.0	0.2	152	0.63	0.236	4
1094208	Soil	36.1	129.7	35.1	89	11.8	15.9	1.9	87	1.72	79.1	21.7	2.0	372	0.2	17.4	0.4	164	0.07	0.456	7
1094209	Soil	22.0	54.6	23.4	24	5.2	5.3	0.6	30	2.60	206.2	12.6	1.9	431	<0.1	19.0	0.4	182	0.04	0.486	6
1094210	Soil	11.8	122.1	31.5	169	2.9	113.5	14.3	666	10.22	137.8	18.9	1.5	86	1.3	17.2	0.3	121	0.05	0.223	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1093241	Soil	39	1.84	361	0.004	6	0.47	0.010	0.08	0.1	0.39	4.1	0.6	<0.05	1	8.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093242	Soil	37	0.10	370	0.005	4	0.56	0.009	0.06	0.2	0.22	2.8	0.6	<0.05	2	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093243	Soil	57	1.01	361	0.004	8	0.50	0.008	0.06	0.2	0.42	7.0	0.5	<0.05	1	8.2	<0.2	N.A.	N.A.	N.A.	N.A.
1093244	Soil	15	0.02	96	0.002	1	0.36	0.003	0.04	0.1	0.03	0.2	0.2	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093245	Soil	13	0.02	120	0.004	<1	0.36	0.006	0.03	0.1	0.02	0.2	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1093246	Soil	18	0.03	114	0.004	<1	0.40	0.004	0.04	0.1	0.02	0.3	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1093247	Soil	7	0.03	89	0.003	1	0.23	0.023	0.03	<0.1	0.24	0.4	0.2	<0.05	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093248	Soil	19	0.08	415	0.004	2	0.54	0.008	0.04	<0.1	0.04	0.9	0.2	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1093249	Soil	12	0.05	1101	0.006	3	0.40	0.010	0.05	<0.1	0.06	1.4	0.1	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093250	Soil	9	0.02	2303	0.005	1	0.43	0.009	0.05	<0.1	0.06	0.8	0.1	0.07	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1093451	Soil	16	0.06	201	0.003	2	0.64	0.007	0.04	<0.1	0.07	0.4	<0.1	0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1093452	Soil	10	0.04	642	0.004	2	0.65	0.019	0.04	<0.1	0.14	0.6	<0.1	0.06	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1093453	Soil	20	0.14	361	0.002	2	0.74	0.006	0.06	<0.1	0.38	3.9	0.1	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093454	Soil	20	0.11	839	0.002	4	0.67	0.006	0.07	<0.1	1.10	2.7	0.1	0.08	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1093455	Soil	21	0.03	193	0.004	2	0.41	0.004	0.07	0.2	0.11	1.0	0.1	0.06	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093456	Soil	17	0.04	850	0.001	4	0.83	0.007	0.12	<0.1	0.42	2.2	0.2	0.25	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1093457	Soil	31	0.07	268	0.004	2	0.80	0.005	0.08	0.1	0.21	1.4	0.2	0.13	3	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093458	Soil	6	0.01	74	0.005	2	0.25	0.003	0.04	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1093459	Soil	24	2.61	313	0.001	3	0.18	0.005	0.05	<0.1	0.30	4.4	0.6	<0.05	<1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093460	Soil	4	0.01	69	0.004	1	0.18	0.028	0.02	<0.1	0.02	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094201	Soil	18	0.23	246	0.007	3	0.85	0.010	0.14	0.2	0.10	5.8	0.3	0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094202	Soil	18	0.12	504	0.003	4	0.89	0.005	0.13	0.1	0.19	5.5	0.4	0.07	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094203	Soil	14	0.07	194	0.003	2	0.73	0.006	0.11	<0.1	0.07	3.7	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094204	Soil	18	0.09	235	0.004	1	0.91	0.006	0.10	<0.1	0.09	4.7	0.4	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094205	Soil	11	0.06	316	0.004	2	0.54	0.011	0.10	<0.1	0.11	5.3	0.3	0.08	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094206	Soil	30	0.06	702	0.003	3	0.84	0.006	0.16	0.1	0.20	7.4	0.9	0.39	4	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094207	Soil	52	0.23	642	0.006	4	0.91	0.009	0.07	0.1	0.23	9.3	0.3	0.09	2	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094208	Soil	52	0.08	5287	0.009	6	1.01	0.005	0.14	0.2	5.38	4.3	1.5	0.27	5	15.4	0.4	N.A.	N.A.	N.A.	N.A.
1094209	Soil	53	0.04	624	0.005	9	0.65	0.008	0.30	<0.1	1.13	7.5	1.7	0.85	4	32.5	0.3	N.A.	N.A.	N.A.	N.A.
1094210	Soil	37	0.07	1415	0.003	2	0.87	0.006	0.09	0.1	0.21	6.6	0.6	0.09	3	6.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1093241	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093242	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093243	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093244	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093245	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093247	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093249	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093250	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093451	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093452	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093453	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093454	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093455	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093456	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093457	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093458	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093459	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093460	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093241	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093242	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093243	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093244	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093245	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093247	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093249	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093250	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093451	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093452	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093453	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093454	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093455	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093456	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093457	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093458	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093459	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093460	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094211	Soil	22.5	65.6	27.4	51	9.4	14.9	1.5	84	3.26	184.3	36.3	1.6	370	0.3	23.0	0.5	228	0.08	0.457	5
1094212	Soil	22.5	61.5	29.9	55	9.4	16.2	1.5	58	3.65	188.8	22.3	2.0	382	0.3	24.0	0.5	231	0.08	0.519	7
1094213	Soil	4.7	119.1	14.6	265	2.5	224.4	16.6	2319	15.82	74.2	15.4	1.8	79	4.7	9.8	0.2	103	0.80	0.122	2
1094214	Soil	20.6	49.1	29.3	42	3.0	12.5	1.2	69	3.45	98.8	1.8	1.3	92	0.1	14.6	0.3	156	0.03	0.212	2
1094215	Soil	8.5	82.3	42.7	18	3.9	5.7	0.7	35	5.31	98.5	8.0	1.3	86	0.1	15.4	0.3	273	0.02	0.176	2
1094216	Soil	6.5	70.8	31.7	21	4.1	8.8	0.7	49	4.68	87.2	7.0	0.8	53	0.3	15.2	0.2	196	0.02	0.128	2
1094217	Soil	5.8	64.2	32.3	73	2.6	14.3	3.2	83	4.64	53.3	10.3	1.4	67	0.2	10.6	0.4	105	0.01	0.108	2
1094218	Soil	5.6	67.7	35.9	70	3.0	13.7	3.3	78	4.89	55.6	10.7	1.4	73	0.2	9.8	0.4	112	0.01	0.110	2
1094219	Soil	5.5	65.9	37.3	66	3.0	13.3	3.4	82	4.65	50.7	9.1	1.4	73	0.2	9.5	0.4	107	0.02	0.115	2
1094220	Soil	5.1	60.5	33.0	66	2.5	12.6	3.2	74	4.16	47.2	9.1	1.2	63	0.2	8.5	0.3	94	0.01	0.092	2
1094221	Soil	5.5	62.9	37.3	65	2.8	12.5	3.3	75	4.45	51.1	7.2	1.2	69	0.2	8.6	0.4	99	0.01	0.102	2
1094222	Soil	20.0	40.1	26.4	35	2.3	10.9	1.0	30	2.33	53.6	2.2	0.4	62	0.2	10.3	0.3	132	0.02	0.139	2
1094223	Soil	5.8	101.4	41.2	181	1.9	39.9	24.5	733	4.66	30.9	7.6	3.5	41	0.4	5.6	0.4	46	0.02	0.117	5
1094224	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094225	Soil	5.0	94.3	41.2	201	1.3	45.8	34.1	1034	4.46	27.4	7.2	3.1	35	0.5	5.9	0.4	40	0.03	0.098	4
1094226	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094227	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094228	Soil	3.7	69.1	57.7	169	0.7	41.5	41.7	1674	4.26	32.8	4.0	1.0	28	0.4	4.6	0.4	32	0.03	0.106	5
1094229	Soil	4.5	78.6	69.2	200	0.7	49.5	57.8	2434	4.94	22.3	6.4	2.4	20	0.5	3.8	0.5	48	0.03	0.121	6
1094230	Soil	6.4	63.5	64.2	194	0.5	31.6	51.2	3969	6.52	21.8	3.2	3.7	21	0.5	3.8	0.5	66	0.02	0.137	7
1094231	Soil	3.9	39.2	38.8	94	0.4	19.8	23.6	1995	3.79	13.4	2.6	0.3	17	0.3	2.6	0.3	47	0.03	0.148	4
1094232	Soil	4.7	36.8	24.5	85	0.4	20.2	6.2	209	3.63	20.1	5.0	0.7	16	0.2	2.9	0.4	71	0.05	0.066	11
1094233	Soil	6.3	45.4	29.1	110	0.2	20.4	6.0	207	4.27	18.8	2.5	0.5	18	0.2	3.5	0.4	80	0.03	0.083	10
1094234	Soil	3.0	33.6	10.5	98	1.5	19.4	3.7	128	1.73	5.5	2.0	0.2	22	0.3	1.1	0.2	33	0.10	0.090	5
1094235	Soil	25.8	66.3	32.3	168	2.4	27.6	5.3	125	3.14	42.7	6.5	0.6	136	0.7	8.7	0.3	80	0.07	0.229	16
1094236	Soil	33.7	89.3	33.8	218	4.8	42.9	5.5	123	3.24	47.1	4.1	2.5	259	2.3	14.4	0.4	109	0.35	0.288	24
1094237	Soil	2.6	32.9	20.9	59	0.3	11.7	8.5	414	2.22	9.2	2.6	0.3	12	0.1	1.7	0.3	32	0.06	0.083	5
1094238	Soil	7.6	39.4	18.1	83	0.1	15.3	4.1	126	4.10	14.6	3.2	0.3	17	0.2	2.6	0.4	81	0.05	0.093	11
1094239	Soil	4.1	63.0	26.6	141	0.4	24.9	12.0	479	4.70	15.5	3.8	2.5	14	0.3	2.8	0.4	54	0.03	0.127	13
1094240	Soil	4.6	83.5	34.2	175	0.6	35.5	23.7	910	4.72	19.8	4.4	1.9	20	0.5	3.0	0.4	52	0.06	0.122	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094211	Soil	52	0.04	697	0.005	8	0.90	0.012	0.26	<0.1	1.18	6.4	1.9	0.71	4	28.6	0.7	N.A.	N.A.	N.A.	N.A.
1094212	Soil	51	0.04	475	0.004	8	0.79	0.008	0.27	<0.1	1.51	6.4	1.7	0.79	4	32.1	0.6	N.A.	N.A.	N.A.	N.A.
1094213	Soil	40	0.33	851	0.002	2	0.49	0.004	0.04	<0.1	0.25	8.9	0.5	0.14	1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094214	Soil	30	0.02	763	0.002	3	0.29	0.006	0.18	0.1	0.72	6.2	1.1	0.63	3	16.4	0.2	N.A.	N.A.	N.A.	N.A.
1094215	Soil	47	0.02	608	0.003	3	0.23	0.008	0.17	<0.1	0.50	6.8	0.8	0.48	7	34.5	0.2	N.A.	N.A.	N.A.	N.A.
1094216	Soil	35	0.02	635	0.003	3	0.18	0.006	0.14	<0.1	0.28	4.5	0.4	0.49	9	28.7	0.2	N.A.	N.A.	N.A.	N.A.
1094217	Soil	27	0.01	494	0.001	4	0.27	0.004	0.16	<0.1	0.30	5.9	0.4	0.46	4	7.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094218	Soil	30	0.01	577	0.001	5	0.29	0.004	0.18	<0.1	0.48	6.1	0.4	0.43	4	7.6	0.2	N.A.	N.A.	N.A.	N.A.
1094219	Soil	29	0.02	578	0.001	4	0.31	0.006	0.19	<0.1	0.47	5.9	0.4	0.45	4	6.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094220	Soil	25	0.01	502	0.001	4	0.27	0.004	0.16	<0.1	0.41	4.9	0.3	0.39	4	7.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094221	Soil	26	0.01	562	0.001	4	0.29	0.005	0.18	<0.1	0.55	5.3	0.4	0.43	4	6.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094222	Soil	21	0.01	762	0.003	2	0.22	0.004	0.13	0.1	0.84	2.9	1.1	0.38	2	15.1	0.2	N.A.	N.A.	N.A.	N.A.
1094223	Soil	15	0.09	267	0.003	3	0.73	0.005	0.10	<0.1	0.16	5.7	0.4	0.15	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094224	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.0	130.6	49.2	200
1094225	Soil	14	0.10	384	0.003	2	0.71	0.004	0.10	<0.1	0.12	5.0	0.3	0.12	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094226	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	4.0	77.7	126.0	136
1094227	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.0	56.0	68.3	124
1094228	Soil	16	0.13	321	0.004	2	0.94	0.004	0.10	<0.1	0.06	2.9	0.3	0.13	3	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094229	Soil	22	0.21	312	0.007	2	1.22	0.004	0.11	<0.1	0.07	4.3	0.4	0.07	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094230	Soil	32	0.12	314	0.006	2	1.24	0.002	0.12	<0.1	0.06	3.7	0.3	0.06	6	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094231	Soil	19	0.09	195	0.008	2	0.92	0.008	0.08	<0.1	0.07	0.9	0.3	0.11	5	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094232	Soil	26	0.19	228	0.017	3	1.28	0.004	0.06	0.2	0.05	1.4	0.3	<0.05	5	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094233	Soil	20	0.10	152	0.020	2	0.85	0.004	0.07	0.2	0.02	1.3	0.3	0.06	6	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094234	Soil	12	0.11	377	0.010	1	1.06	0.013	0.05	<0.1	0.19	1.3	0.2	0.10	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094235	Soil	21	0.08	1035	0.002	2	0.94	0.005	0.09	0.2	0.54	0.9	0.8	0.18	3	7.7	0.3	N.A.	N.A.	N.A.	N.A.
1094236	Soil	22	0.15	620	0.002	4	0.90	0.004	0.14	0.3	1.26	3.4	1.2	0.26	2	16.6	0.4	N.A.	N.A.	N.A.	N.A.
1094237	Soil	12	0.10	136	0.012	1	0.88	0.017	0.05	0.1	0.04	0.9	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094238	Soil	22	0.08	223	0.009	1	0.98	0.004	0.07	0.2	0.06	0.6	0.3	<0.05	5	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094239	Soil	26	0.30	178	0.005	2	1.52	0.006	0.09	<0.1	0.05	2.7	0.2	<0.05	5	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094240	Soil	22	0.22	210	0.007	2	1.21	0.007	0.09	0.1	0.09	2.9	0.3	<0.05	4	2.7	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094218	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094222	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094224	Soil	1.9	44.9	29.7	827	5.25	74.7	11.4	3.3	45	0.6	5.7	0.4	43	0.06	0.147	6	19	0.11	926	0.003
1094225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094226	Soil	1.2	43.1	74.6	3505	3.46	15.9	3.5	1.6	25	0.9	2.0	0.4	35	0.11	0.153	7	27	0.29	493	0.004
1094227	Soil	0.7	38.1	44.1	2994	3.30	13.8	1.7	0.9	17	0.5	2.3	0.3	26	0.09	0.140	5	13	0.11	387	0.004
1094228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094231	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094232	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094233	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094234	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094235	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094236	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094237	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094238	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094239	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094240	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094218	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094222	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094224	Soil	<20	0.83	0.005	0.12	<0.1	0.17	6.2	0.5	0.14	2	3.8	<0.2
1094225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094226	Soil	<20	1.41	0.006	0.13	<0.1	0.23	3.9	0.4	0.09	4	2.7	<0.2
1094227	Soil	<20	0.82	0.007	0.09	<0.1	0.15	2.1	0.4	0.10	2	2.8	<0.2
1094228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094231	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094232	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094233	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094234	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094235	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094236	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094237	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094238	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094239	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094240	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094241	Soil	5.1	109.6	49.8	186	0.8	42.4	41.1	1566	6.13	25.1	5.0	3.1	21	0.8	4.1	0.5	53	0.08	0.153	15
1094242	Soil	13.6	67.2	23.9	76	5.5	16.5	2.4	73	3.28	37.7	10.1	0.4	180	0.2	8.5	0.4	174	0.05	0.218	5
1094243	Soil	12.1	76.9	21.7	54	4.5	9.5	1.3	56	4.01	78.4	16.8	1.1	321	<0.1	16.6	0.4	216	0.05	0.217	8
1094244	Soil	11.9	53.7	20.2	44	4.4	8.0	1.5	62	2.56	38.6	7.9	0.6	254	<0.1	10.6	0.4	182	0.05	0.186	7
1094245	Soil	9.3	95.5	21.0	47	5.4	13.2	2.2	65	3.27	27.4	10.6	0.2	72	0.2	5.0	0.3	100	0.04	0.210	4
1094246	Soil	14.3	38.5	27.8	56	4.4	13.7	1.4	55	2.52	64.7	7.6	0.6	96	0.2	12.9	0.4	172	0.02	0.158	2
1094247	Soil	27.4	56.0	44.8	142	5.6	31.2	3.3	85	4.29	34.4	2.8	1.1	181	0.2	10.6	0.4	275	0.04	0.332	3
1094248	Soil	3.5	11.9	6.5	48	1.1	10.1	1.6	95	0.99	5.0	3.0	0.2	14	<0.1	2.0	<0.1	63	0.06	0.067	1
1094249	Soil	25.7	60.1	26.1	197	2.1	37.1	4.0	109	3.93	23.3	7.5	0.8	66	0.4	9.3	0.3	230	0.03	0.235	2
1094250	Soil	13.6	73.4	39.6	51	5.2	11.5	2.0	45	5.08	80.6	7.9	1.6	232	0.1	18.6	0.4	185	0.04	0.304	4
1094251	Soil	13.0	51.6	33.1	44	2.4	6.8	1.4	24	3.20	38.8	2.2	1.7	69	<0.1	8.6	0.3	110	0.01	0.092	3
1094252	Soil	7.7	97.6	30.4	64	4.7	17.9	2.1	92	6.87	92.3	7.8	1.3	338	0.2	30.6	0.3	230	0.05	0.425	2
1094253	Soil	9.0	104.0	26.5	51	5.5	13.8	1.7	83	7.71	114.8	9.1	1.6	510	0.3	35.0	0.4	259	0.07	0.604	3
1094254	Soil	8.1	105.9	32.8	113	6.9	40.8	4.6	218	7.26	147.7	9.4	1.7	434	0.5	30.9	0.4	232	0.06	0.479	3
1094255	Soil	5.1	154.9	26.6	204	5.2	81.9	8.9	413	8.00	123.5	10.0	2.0	290	1.5	32.2	0.3	245	0.04	0.377	2
1094256	Soil	14.4	89.1	29.1	22	6.4	4.5	0.5	26	6.36	112.0	9.0	2.0	878	0.1	30.5	0.4	254	0.15	0.924	3
1094257	Soil	11.1	36.6	31.5	15	3.0	6.2	0.7	32	4.01	238.5	3.6	0.3	183	0.1	13.4	0.2	321	0.03	0.813	3
1094258	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094259	Soil	15.3	40.0	37.6	29	6.9	9.0	2.0	67	2.41	63.7	16.5	2.0	118	<0.1	31.1	0.3	99	0.04	0.219	5
1094260	Soil	12.5	34.8	28.7	53	6.2	7.6	1.8	57	2.66	66.9	10.1	1.6	278	0.1	31.6	0.2	188	0.07	0.456	6
1094261	Soil	7.8	27.2	26.6	24	3.9	5.4	1.4	70	1.79	24.3	10.9	0.7	123	<0.1	14.4	0.2	88	0.07	0.171	4
1094262	Soil	72.4	82.7	28.9	94	2.3	13.2	1.0	14	3.06	77.3	13.7	0.8	101	0.2	18.4	0.3	365	0.01	0.188	2
1094263	Soil	44.6	65.4	14.1	46	1.0	7.4	0.6	11	1.88	48.0	2.7	0.4	117	0.2	12.1	0.2	182	0.02	0.165	2
1094264	Soil	49.2	54.7	23.8	81	2.2	12.2	2.3	101	3.26	73.3	5.1	0.2	212	0.2	17.4	0.3	286	0.03	0.213	4
1094265	Soil	10.3	24.3	16.4	49	1.8	10.9	2.7	69	2.06	25.6	10.2	0.2	84	0.1	10.8	0.2	107	0.05	0.107	6
1094266	Soil	4.4	62.2	19.0	164	0.6	28.9	11.9	323	3.64	9.9	2.4	0.2	9	0.4	2.1	0.2	53	0.03	0.104	4
1094267	Soil	4.8	16.7	5.0	54	0.2	12.1	3.9	46	0.80	5.3	0.9	0.3	4	<0.1	1.3	<0.1	38	<0.01	0.023	9
1094268	Soil	4.3	31.4	8.3	90	0.3	19.8	6.3	73	1.31	8.7	1.6	<0.1	4	<0.1	2.5	0.1	27	0.01	0.051	2
1094269	Soil	4.8	17.9	7.1	63	0.4	17.1	4.4	95	0.62	3.6	<0.5	0.1	6	0.2	1.3	<0.1	24	0.02	0.035	2
1094270	Soil	27.6	34.4	8.9	248	0.6	72.3	5.8	101	1.23	10.8	2.0	0.3	29	1.8	5.3	<0.1	109	0.37	0.075	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094241	Soil	28	0.30	294	0.006	2	1.62	0.009	0.10	<0.1	0.12	3.3	0.3	<0.05	5	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094242	Soil	36	0.08	1518	0.004	3	0.73	0.010	0.15	<0.1	0.67	2.1	0.6	0.29	4	10.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094243	Soil	40	0.04	2710	0.005	4	0.74	0.006	0.10	<0.1	0.92	2.2	0.5	0.09	4	14.2	0.4	N.A.	N.A.	N.A.	N.A.
1094244	Soil	30	0.04	1912	0.004	3	0.73	0.009	0.11	<0.1	0.55	1.6	0.5	0.18	4	9.7	0.3	N.A.	N.A.	N.A.	N.A.
1094245	Soil	25	0.09	454	0.005	1	0.88	0.013	0.08	0.1	0.68	1.0	0.4	0.20	4	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094246	Soil	28	0.07	603	0.002	<1	0.59	0.006	0.10	<0.1	0.45	1.9	0.8	0.18	3	6.7	0.2	N.A.	N.A.	N.A.	N.A.
1094247	Soil	46	0.09	612	0.005	2	0.60	0.011	0.23	0.1	0.28	4.7	1.5	0.52	4	9.5	0.3	N.A.	N.A.	N.A.	N.A.
1094248	Soil	10	0.05	80	0.008	<1	0.33	0.017	0.03	<0.1	0.05	0.6	0.3	<0.05	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094249	Soil	33	0.10	332	0.002	1	0.48	0.003	0.09	0.2	0.45	2.9	1.9	0.16	2	7.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094250	Soil	55	0.06	576	0.005	4	0.45	0.012	0.23	0.2	0.66	8.1	1.1	0.54	4	14.0	0.3	N.A.	N.A.	N.A.	N.A.
1094251	Soil	28	0.01	320	0.004	4	0.24	0.006	0.23	<0.1	0.24	3.7	1.1	0.49	3	7.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094252	Soil	71	0.03	528	0.003	2	0.42	0.011	0.15	0.1	0.26	9.3	0.9	0.37	3	16.7	0.2	N.A.	N.A.	N.A.	N.A.
1094253	Soil	83	0.02	488	0.004	2	0.47	0.013	0.17	0.2	0.58	13.3	1.1	0.51	4	20.5	0.3	N.A.	N.A.	N.A.	N.A.
1094254	Soil	79	0.04	623	0.003	3	0.80	0.011	0.18	0.1	0.48	13.8	1.1	0.45	4	16.3	0.2	N.A.	N.A.	N.A.	N.A.
1094255	Soil	93	0.02	364	0.002	3	1.14	0.005	0.09	<0.1	0.35	18.8	0.7	0.17	4	13.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094256	Soil	102	0.01	253	0.005	2	0.58	0.018	0.28	0.1	0.85	19.4	2.0	0.72	6	22.5	0.4	N.A.	N.A.	N.A.	N.A.
1094257	Soil	44	0.02	896	0.005	<1	0.27	0.005	0.14	0.2	0.13	1.9	1.0	0.34	4	16.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094258	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	8.9	33.8	34.6	12
1094259	Soil	34	0.07	908	0.008	2	0.40	0.007	0.16	0.2	0.63	7.4	2.0	0.28	4	13.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094260	Soil	45	0.06	1769	0.009	1	0.71	0.006	0.15	0.2	0.57	6.6	2.0	0.23	7	13.9	0.3	N.A.	N.A.	N.A.	N.A.
1094261	Soil	26	0.04	1544	0.020	<1	0.49	0.012	0.12	0.1	0.23	3.0	1.1	0.22	4	10.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094262	Soil	28	<0.01	425	0.003	1	0.25	0.003	0.19	0.4	0.68	5.5	2.2	0.45	3	29.5	0.3	N.A.	N.A.	N.A.	N.A.
1094263	Soil	19	0.01	650	0.002	<1	0.27	0.003	0.11	0.2	0.08	2.2	1.7	0.23	2	13.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094264	Soil	36	0.05	1005	0.006	<1	0.54	0.007	0.18	0.3	0.18	1.3	2.5	0.38	5	12.1	0.2	N.A.	N.A.	N.A.	N.A.
1094265	Soil	23	0.11	767	0.013	<1	0.56	0.006	0.09	0.1	0.18	0.7	0.7	0.16	4	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094266	Soil	17	0.06	91	0.004	<1	0.68	0.006	0.05	<0.1	0.06	1.4	0.2	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094267	Soil	5	0.01	42	0.003	<1	0.23	0.002	0.03	<0.1	<0.01	0.4	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094268	Soil	5	0.01	30	0.003	<1	0.33	0.011	0.03	<0.1	0.02	0.5	0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094269	Soil	4	0.01	51	0.003	<1	0.16	0.012	0.03	<0.1	0.05	0.6	0.2	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094270	Soil	12	0.03	119	0.006	1	0.27	0.020	0.04	0.1	0.15	1.4	0.4	<0.05	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094241	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094242	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094243	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094244	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094245	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094247	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094249	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094250	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094254	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094258	Soil	5.0	4.6	0.7	23	0.99	18.2	10.8	0.6	39	<0.1	13.3	0.2	40	0.02	0.081	1	18	0.02	364	0.002
1094259	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094241	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094242	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094243	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094244	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094245	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094247	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094249	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094250	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094254	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094258	Soil	<20	0.18	0.007	0.09	<0.1	0.51	2.4	0.7	0.18	2	9.1	<0.2
1094259	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094271	Soil		35.7	61.6	27.6	361	0.2	100.2	11.3	221	3.86	32.4	1.8	0.3	11	0.6	7.4	0.2	129	0.04	0.181	7
1094272	Soil		21.3	42.7	20.5	218	0.8	51.5	7.1	84	2.13	42.7	1.2	0.2	10	0.3	5.0	0.2	81	0.02	0.102	5
1094273	Soil		32.9	28.3	6.9	451	0.8	68.6	2.4	54	0.61	14.6	1.2	1.3	38	8.1	8.5	<0.1	163	3.86	0.030	2
1094274	Soil		99.1	38.2	9.8	258	0.2	120.4	8.3	58	1.98	16.3	1.7	0.2	12	1.0	5.1	<0.1	143	0.35	0.064	5
1094275	Soil		84.0	35.7	20.8	762	<0.1	131.4	9.3	78	2.88	33.7	2.3	0.6	4	1.8	24.9	0.1	383	0.03	0.057	2
1094276	Soil		8.9	19.2	10.5	121	0.4	26.2	3.6	73	1.22	7.9	2.8	<0.1	10	1.0	2.1	<0.1	67	0.06	0.078	5
1094277	Soil		7.7	27.4	9.2	120	0.3	34.7	6.5	74	1.42	9.1	0.9	0.1	6	0.2	2.4	<0.1	49	0.01	0.062	4
1094278	Soil		14.8	57.2	16.2	391	0.4	89.4	17.7	378	3.40	17.8	1.8	0.4	29	3.2	4.8	<0.1	96	0.18	0.205	4
1094279	Soil		16.6	96.9	29.0	137	0.6	197.4	35.7	333	7.98	89.0	9.0	1.5	27	0.7	7.7	0.3	50	0.22	0.098	6
1094280	Soil		14.6	44.2	9.5	223	<0.1	66.1	12.3	84	2.63	30.4	0.7	<0.1	8	0.7	3.6	<0.1	71	0.01	0.082	2
1094281	Soil		51.3	62.8	20.8	461	0.2	118.1	13.7	154	4.15	36.8	2.2	0.2	9	0.8	9.5	0.2	258	0.02	0.126	7
1094282	Soil		90.5	89.5	18.9	1257	1.8	250.3	10.8	235	2.34	39.2	2.5	1.2	154	17.0	18.9	<0.1	535	10.19	0.106	4
1094283	Soil		113.7	95.6	19.7	867	0.1	210.8	12.4	155	3.15	46.2	2.0	0.4	16	5.8	19.7	0.2	465	0.18	0.142	9
1094284	Soil		153.9	112.2	24.7	1110	0.3	307.9	23.0	279	5.72	67.1	1.0	0.9	19	2.3	27.6	0.1	726	0.04	0.134	9
1094285	Soil		120.6	127.0	16.4	810	0.6	261.6	16.9	257	3.90	53.5	2.2	0.8	72	11.2	12.1	<0.1	339	0.51	0.202	7
1094286	Soil		98.0	51.4	9.3	351	<0.1	152.6	8.0	38	2.02	22.1	1.1	0.5	3	0.7	7.4	<0.1	106	0.01	0.037	5
1094287	Soil		79.6	50.7	15.6	368	<0.1	151.6	8.7	90	2.97	24.9	1.7	0.2	4	0.7	5.1	<0.1	135	0.02	0.055	7
1094288	Soil		77.4	50.7	15.7	265	<0.1	148.0	9.7	225	3.14	19.4	1.6	0.3	9	0.9	3.8	<0.1	75	0.06	0.089	7
1094289	Soil		69.6	42.0	12.1	238	<0.1	122.7	9.2	101	2.19	15.5	<0.5	0.3	7	0.6	4.5	0.1	47	0.07	0.070	5
1094290	Soil		87.8	105.0	15.3	977	1.1	243.0	11.9	211	2.32	43.2	<0.5	1.8	139	9.8	18.0	0.1	337	5.47	0.166	9
1094291	Soil		59.2	99.9	21.1	757	1.0	232.4	24.7	420	3.97	43.7	3.8	2.4	92	7.7	11.8	0.2	252	2.22	0.239	9
1094292	Soil		1.8	10.5	3.4	33	0.1	13.9	4.7	79	1.05	2.0	0.7	0.3	4	0.1	0.6	<0.1	7	0.03	0.055	8
1094293	Soil		1.3	11.8	3.0	24	<0.1	9.4	3.0	41	0.81	2.8	<0.5	<0.1	4	0.1	0.6	0.1	14	0.02	0.025	4
1094294	Soil		9.8	22.4	8.5	99	0.1	32.0	7.3	116	2.66	9.0	<0.5	0.2	3	<0.1	1.2	0.2	25	0.01	0.055	8
1094295	Soil		4.1	5.9	5.0	15	0.6	2.9	0.9	23	0.48	3.3	1.5	<0.1	6	<0.1	0.5	<0.1	29	0.01	0.090	5
1094296	Soil		17.0	7.9	4.9	29	0.5	6.7	1.3	22	0.69	6.7	1.8	<0.1	4	<0.1	2.4	0.2	71	<0.01	0.024	9
1094297	Soil		16.3	25.2	16.3	101	0.2	15.8	2.3	29	1.08	15.8	<0.5	<0.1	9	0.2	2.8	0.2	74	0.03	0.055	8
1094298	Soil		4.7	31.9	23.9	75	0.5	12.5	1.8	45	2.07	33.8	2.5	0.5	69	0.7	4.8	0.2	68	0.08	0.323	13
1094299	Soil		2.1	17.1	9.4	64	<0.1	8.2	1.7	33	0.99	8.3	<0.5	<0.1	6	0.1	1.6	0.1	21	0.02	0.072	3
1094300	Soil		9.8	62.3	30.4	619	0.6	65.4	9.0	575	6.32	39.9	4.9	0.2	19	1.6	8.5	0.2	70	0.07	0.346	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094271	Soil	18	0.03	136	0.005	1	0.44	0.002	0.05	0.1	0.03	0.6	0.4	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094272	Soil	11	0.02	95	0.002	1	0.40	0.004	0.05	<0.1	0.03	0.3	0.3	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094273	Soil	9	2.03	151	0.001	2	0.07	0.003	0.02	<0.1	0.37	1.5	0.4	0.06	<1	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094274	Soil	11	0.17	194	0.003	1	0.30	0.003	0.04	0.2	0.07	0.6	0.9	0.06	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094275	Soil	17	0.02	129	0.002	1	0.27	0.002	0.06	<0.1	0.08	2.5	1.0	0.06	1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094276	Soil	12	0.02	118	0.002	<1	0.41	0.010	0.04	<0.1	0.11	0.4	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094277	Soil	10	0.02	57	0.003	<1	0.23	0.008	0.04	<0.1	0.02	0.2	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094278	Soil	34	0.03	454	0.005	<1	0.43	0.008	0.07	<0.1	0.03	1.9	0.3	0.07	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094279	Soil	17	0.06	630	0.003	<1	0.49	0.002	0.07	<0.1	0.19	7.2	0.3	<0.05	1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094280	Soil	15	0.02	64	0.003	<1	0.25	0.011	0.04	<0.1	0.02	0.8	0.2	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094281	Soil	28	0.04	114	0.007	1	0.69	0.002	0.05	0.1	0.03	0.5	0.5	<0.05	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094282	Soil	33	5.61	310	0.003	5	0.25	0.010	0.07	<0.1	1.05	3.8	1.5	0.11	<1	6.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094283	Soil	44	0.06	242	0.004	2	0.49	0.003	0.05	0.2	0.06	1.4	0.9	0.06	2	8.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094284	Soil	55	0.03	159	0.007	1	0.58	0.003	0.05	0.2	0.05	2.2	1.1	0.06	2	10.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094285	Soil	38	0.04	307	0.004	2	0.43	0.003	0.06	0.1	0.24	3.4	1.2	<0.05	1	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094286	Soil	14	0.02	98	0.002	<1	0.40	0.001	0.04	0.1	0.02	1.0	0.8	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094287	Soil	17	0.03	62	0.002	<1	0.32	0.003	0.03	0.1	0.03	0.5	0.8	<0.05	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094288	Soil	18	0.03	140	0.003	<1	0.32	0.004	0.04	<0.1	0.08	1.1	0.9	<0.05	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094289	Soil	13	0.03	128	0.004	3	0.25	0.006	0.04	0.1	0.03	1.5	0.9	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094290	Soil	35	2.54	174	0.004	7	0.27	0.008	0.08	0.2	0.35	5.2	1.1	0.26	<1	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094291	Soil	54	0.83	360	0.006	5	0.38	0.005	0.09	0.2	0.45	7.4	0.9	0.25	1	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094292	Soil	4	0.03	139	0.006	2	0.23	0.010	0.05	<0.1	<0.01	1.2	<0.1	0.22	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094293	Soil	3	0.01	24	0.005	3	0.20	0.015	0.02	<0.1	0.02	0.3	<0.1	<0.05	1	<0.5	0.2	N.A.	N.A.	N.A.	N.A.
1094294	Soil	6	0.03	56	0.002	3	0.38	0.007	0.04	0.1	0.02	0.6	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094295	Soil	9	0.01	50	0.002	2	0.32	0.010	0.03	<0.1	0.03	0.2	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094296	Soil	9	<0.01	43	0.004	3	0.24	0.006	0.03	0.2	0.02	0.3	0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094297	Soil	9	0.02	72	0.003	2	0.29	0.004	0.04	<0.1	0.02	0.3	0.3	0.08	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094298	Soil	32	0.02	433	0.004	3	0.51	0.006	0.11	<0.1	0.05	0.7	0.8	0.21	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094299	Soil	5	0.01	53	0.003	2	0.36	0.015	0.03	<0.1	0.03	0.3	<0.1	0.07	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094300	Soil	19	0.04	217	0.004	5	0.79	0.005	0.07	0.1	0.07	1.5	0.4	0.10	3	1.9	0.4	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094271	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094272	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094273	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094274	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094275	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094276	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094277	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094278	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094279	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094280	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094281	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094282	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094283	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094284	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094285	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094286	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094287	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094288	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094289	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094290	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094291	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094292	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094293	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094294	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094295	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094296	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094297	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094298	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094299	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094300	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094271	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094272	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094273	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094274	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094275	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094276	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094277	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094278	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094279	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094280	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094281	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094282	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094283	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094284	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094286	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094287	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094288	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094289	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094290	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094291	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094292	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094293	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094294	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094295	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094296	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094297	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094298	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094299	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094300	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094301	Soil	6.0	40.5	25.9	214	0.2	33.0	9.5	227	4.87	21.6	1.7	0.4	12	0.5	4.0	0.3	47	0.03	0.112	8
1094302	Soil	4.4	29.7	18.2	140	0.1	23.6	6.9	177	3.30	14.5	<0.5	0.2	10	0.2	2.6	0.2	39	0.02	0.096	7
1094303	Soil	3.2	15.5	13.3	76	<0.1	12.8	3.5	81	1.87	9.6	<0.5	<0.1	10	0.1	1.6	0.2	41	0.02	0.067	8
1094304	Soil	4.9	17.9	15.1	94	0.1	16.2	4.1	97	2.14	10.8	<0.5	0.2	11	0.2	2.1	0.2	41	0.03	0.107	8
1094305	Soil	4.2	27.1	18.2	129	0.2	20.5	6.5	215	2.92	11.3	<0.5	0.3	10	0.5	2.3	0.2	39	0.02	0.150	7
1094306	Soil	5.4	32.8	47.4	194	<0.1	37.3	17.6	1047	5.47	19.1	<0.5	1.3	13	0.5	2.9	0.4	43	0.06	0.128	10
1094307	Soil	3.7	23.3	24.8	122	0.2	27.0	10.2	305	2.94	9.0	<0.5	1.0	17	0.4	1.7	0.3	33	0.11	0.105	9
1094308	Soil	6.9	39.6	30.4	193	0.3	41.4	18.2	596	4.14	14.7	3.4	2.9	23	1.0	3.2	0.3	39	0.21	0.147	11
1094309	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094310	Soil	32.5	32.7	18.9	474	0.2	76.8	10.1	266	4.13	50.7	1.5	1.2	37	1.4	9.1	0.2	352	0.38	0.183	17
1094311	Soil	12.2	27.2	18.6	420	0.2	58.5	8.6	278	2.70	29.1	<0.5	1.1	43	5.5	5.4	0.2	135	0.41	0.253	11
1094312	Soil	13.8	370.0	28.5	239	2.7	66.4	6.9	147	21.19	118.1	19.6	2.4	66	1.0	27.6	0.3	362	0.02	0.343	3
1094313	Soil	11.9	209.9	25.6	387	3.9	145.1	20.1	1423	16.79	74.1	14.5	2.3	51	4.6	26.4	0.3	183	0.02	0.192	2
1094314	Soil	13.4	113.6	17.8	194	2.6	65.9	9.0	643	8.15	38.8	6.9	1.0	35	1.3	17.7	0.2	130	0.02	0.131	3
1094315	Soil	23.9	38.1	15.5	71	2.4	13.9	1.6	58	1.69	11.9	1.6	0.2	26	0.4	10.8	0.2	122	0.02	0.047	3
1094316	Soil	27.3	38.9	18.2	17	3.2	4.0	0.4	13	1.40	19.3	5.2	0.3	71	0.2	14.2	0.2	113	0.01	0.089	2
1094317	Soil	20.5	27.4	16.4	44	1.2	9.6	1.7	79	2.59	32.3	1.4	0.2	66	0.1	8.9	0.2	141	0.02	0.088	5
1094318	Soil	13.9	22.4	13.2	53	0.5	12.0	2.3	65	1.78	17.1	<0.5	<0.1	30	0.1	6.2	0.2	117	0.02	0.075	4
1094319	Soil	48.6	64.4	28.6	36	4.1	8.6	1.4	46	4.37	76.9	4.3	1.2	182	0.1	21.4	0.3	268	0.03	0.315	4
1094320	Soil	6.8	26.6	7.9	9	1.0	2.6	0.7	48	0.83	12.9	0.7	<0.1	22	<0.1	2.8	0.1	47	0.05	0.079	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094301	Soil	20	0.16	116	0.006	3	0.99	0.004	0.06	0.1	0.05	1.0	0.2	0.08	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094302	Soil	12	0.07	85	0.007	2	0.71	0.005	0.04	<0.1	0.03	0.6	0.2	0.07	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094303	Soil	11	0.04	67	0.004	2	0.58	0.007	0.04	<0.1	0.05	0.5	0.2	0.07	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094304	Soil	13	0.06	86	0.003	2	0.66	0.005	0.05	<0.1	0.04	0.3	0.2	0.11	3	<0.5	0.3	N.A.	N.A.	N.A.	N.A.
1094305	Soil	16	0.09	123	0.005	2	0.84	0.007	0.06	<0.1	0.07	1.0	0.2	0.13	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094306	Soil	19	0.16	116	0.005	1	0.79	0.003	0.06	0.1	0.04	2.0	0.1	0.07	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094307	Soil	19	0.14	257	0.006	3	0.97	0.009	0.06	0.1	0.08	2.1	0.2	0.08	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094308	Soil	15	0.17	266	0.004	1	0.79	0.004	0.07	<0.1	0.11	3.3	0.2	0.06	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094309	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	7.2	58.2	36.3	470
1094310	Soil	39	0.11	940	0.004	2	0.82	0.005	0.08	0.2	0.28	2.2	0.8	0.09	2	2.6	0.2	N.A.	N.A.	N.A.	N.A.
1094311	Soil	29	0.16	721	0.008	2	0.92	0.005	0.11	0.4	0.28	2.4	0.4	0.13	2	1.6	0.3	N.A.	N.A.	N.A.	N.A.
1094312	Soil	117	0.03	210	0.003	3	1.32	0.005	0.05	0.1	0.19	13.2	0.3	0.17	6	12.3	0.3	N.A.	N.A.	N.A.	N.A.
1094313	Soil	75	0.08	233	0.002	1	1.68	0.006	0.05	<0.1	0.42	12.6	0.4	0.07	3	7.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094314	Soil	39	0.06	210	0.006	3	0.99	0.010	0.06	0.2	0.12	5.6	0.6	0.14	3	7.4	0.2	N.A.	N.A.	N.A.	N.A.
1094315	Soil	15	0.02	315	0.004	1	0.54	0.008	0.07	0.2	0.12	1.5	1.2	0.16	2	11.5	0.3	N.A.	N.A.	N.A.	N.A.
1094316	Soil	21	0.01	624	0.002	2	0.31	0.005	0.13	0.2	0.44	1.6	1.8	0.37	2	13.6	0.3	N.A.	N.A.	N.A.	N.A.
1094317	Soil	21	0.02	423	0.006	<1	0.48	0.006	0.09	0.2	0.06	0.7	1.0	0.21	4	7.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094318	Soil	15	0.02	202	0.008	1	0.33	0.011	0.06	0.1	0.07	0.5	0.3	0.14	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094319	Soil	41	0.05	363	0.009	<1	0.47	0.010	0.24	0.2	0.35	4.7	2.2	0.57	4	21.8	0.3	N.A.	N.A.	N.A.	N.A.
1094320	Soil	12	0.03	151	0.007	<1	0.65	0.019	0.05	<0.1	0.13	0.6	0.4	0.15	3	3.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094301	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094302	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094303	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094304	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094305	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094306	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094307	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094308	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094309	Soil	0.6	98.2	28.6	1031	4.47	46.6	3.0	1.1	33	7.7	2.6	0.3	52	0.35	0.282	10	19	0.16	431	0.003
1094310	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094311	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094320	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

CERTIFICATE OF ANALYSIS WHI11000982.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094301	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094302	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094303	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094304	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094305	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094306	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094307	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094308	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094309	Soil	<20	0.82	0.007	0.08	0.2	0.21	2.3	0.9	<0.05	2	2.4	<0.2
1094310	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094311	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094320	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

QUALITY CONTROL REPORT WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1090869	Soil	9.6	22.3	9.7	84	0.5	28.1	5.6	61	1.53	17.3	<0.5	0.3	51	0.2	3.4	0.1	84	0.24	0.066	7
REP 1090869	QC	9.2	22.3	9.9	89	0.4	30.1	5.8	61	1.49	15.8	<0.5	0.3	54	0.4	3.2	0.1	83	0.25	0.068	7
1091652	Soil	20.2	77.7	24.2	247	0.9	103.2	16.0	2076	13.64	72.5	6.0	2.0	38	1.0	19.6	0.2	100	2.21	0.143	11
REP 1091652	QC	22.5	79.4	24.6	241	1.0	106.2	16.1	2145	13.93	70.3	5.3	2.2	40	1.3	19.9	0.2	101	2.24	0.145	11
1093084	Soil	2.8	12.6	6.5	59	0.4	13.0	1.9	62	0.40	3.3	0.5	0.1	9	0.5	1.0	0.1	39	0.10	0.097	6
REP 1093084	QC	2.8	11.7	6.1	55	0.4	12.5	1.7	60	0.38	3.1	0.7	0.1	9	0.5	1.0	0.1	35	0.10	0.090	5
1093111	Soil	7.2	24.6	13.6	176	0.2	32.9	6.9	154	1.92	16.5	6.1	0.4	23	1.1	3.2	0.2	57	0.10	0.109	8
REP 1093111	QC	7.2	24.2	12.9	170	0.2	32.3	7.0	147	1.90	16.6	5.2	0.3	23	1.0	3.1	0.1	56	0.10	0.103	8
1093119	Soil	29.3	65.9	19.4	1148	0.9	186.4	19.0	535	3.56	47.1	3.3	2.0	60	10.1	8.7	0.2	227	0.97	0.192	18
REP 1093119	QC	29.1	65.5	19.2	1142	1.0	186.6	18.9	536	3.60	46.4	4.5	2.0	60	9.7	8.5	0.2	237	1.00	0.198	18
1093136	Soil	5.7	87.7	21.1	129	2.1	25.3	4.1	229	6.89	72.0	8.3	1.3	43	0.6	11.8	0.3	229	0.05	0.159	6
REP 1093136	QC	6.3	83.3	20.7	126	2.0	23.1	3.8	217	6.20	67.2	12.8	1.2	41	0.4	11.4	0.3	222	0.05	0.149	6
1093154	Soil	5.0	4.1	18.7	26	0.2	4.1	0.6	11	0.49	9.5	2.7	<0.1	32	<0.1	1.3	0.1	38	0.01	0.039	9
REP 1093154	QC	4.5	3.8	19.6	23	0.3	4.2	0.6	11	0.46	9.3	<0.5	0.1	30	<0.1	1.2	0.2	37	0.01	0.037	9
1093169	Soil	14.6	20.0	31.0	28	7.9	5.8	1.0	34	4.40	92.5	8.2	0.7	296	0.1	23.0	0.4	137	0.03	0.272	8
REP 1093169	QC	15.9	19.0	29.9	27	7.9	5.2	1.1	35	4.48	90.0	8.0	0.8	288	<0.1	23.4	0.3	133	0.03	0.273	8
1093191	Soil	52.7	34.7	28.8	233	0.7	64.6	4.1	41	2.02	45.4	5.5	0.5	39	0.9	14.9	0.2	222	0.02	0.085	11
REP 1093191	QC	52.7	33.6	28.9	229	0.8	61.6	4.0	41	2.06	44.0	5.1	0.6	39	0.9	14.6	0.2	221	0.02	0.087	11
1093211	Soil	12.8	38.3	33.9	180	0.2	37.7	6.1	94	2.31	35.8	1.4	0.3	34	0.2	6.4	0.3	128	0.02	0.105	10
REP 1093211	QC	12.1	34.6	33.3	168	0.2	34.0	5.8	86	2.13	33.2	1.8	0.3	31	0.3	6.2	0.3	119	0.02	0.100	10
1093245	Soil	15.4	22.4	11.6	113	<0.1	33.0	5.8	64	1.62	14.5	0.6	<0.1	9	0.3	3.4	0.2	69	0.02	0.070	7
REP 1093245	QC	16.5	22.1	11.8	113	<0.1	34.5	5.8	65	1.61	14.7	<0.5	<0.1	9	0.3	3.5	0.2	70	0.02	0.068	7
1094211	Soil	22.5	65.6	27.4	51	9.4	14.9	1.5	84	3.26	184.3	36.3	1.6	370	0.3	23.0	0.5	228	0.08	0.457	5
REP 1094211	QC	22.3	66.4	27.0	52	9.4	14.8	1.4	84	3.22	184.9	36.9	1.5	368	0.2	23.5	0.5	222	0.08	0.457	5
1094219	Soil	5.5	65.9	37.3	66	3.0	13.3	3.4	82	4.65	50.7	9.1	1.4	73	0.2	9.5	0.4	107	0.02	0.115	2
REP 1094219	QC	5.6	65.9	34.1	65	3.1	13.8	3.4	78	4.65	51.4	7.3	1.3	73	0.2	9.3	0.4	108	0.01	0.109	2
1094243	Soil	12.1	76.9	21.7	54	4.5	9.5	1.3	56	4.01	78.4	16.8	1.1	321	<0.1	16.6	0.4	216	0.05	0.217	8
REP 1094243	QC	11.9	79.8	21.1	59	4.5	9.1	1.3	56	3.95	81.2	13.0	1.1	305	0.1	16.6	0.4	213	0.04	0.215	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

QUALITY CONTROL REPORT WHI11000982.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1090869	Soil	14	0.05	3090	0.007	3	0.43	0.010	0.07	0.1	0.07	1.6	0.3	0.14	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090869	QC	14	0.05	3076	0.007	2	0.42	0.014	0.07	0.1	0.06	1.4	0.2	0.16	2	1.3	<0.2				
1091652	Soil	17	0.62	388	0.006	5	0.57	0.004	0.07	<0.1	0.20	3.8	0.3	0.13	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1091652	QC	16	0.67	406	0.003	4	0.59	0.003	0.07	<0.1	0.21	4.0	0.4	0.13	1	4.1	0.3				
1093084	Soil	9	0.05	93	0.005	3	0.76	0.017	0.03	<0.1	0.06	0.3	0.4	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1093084	QC	9	0.04	85	0.002	3	0.70	0.015	0.03	<0.1	0.06	0.2	0.3	<0.05	2	<0.5	<0.2				
1093111	Soil	12	0.08	184	0.004	2	0.59	0.008	0.05	<0.1	0.09	0.7	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1093111	QC	12	0.08	181	0.004	3	0.55	0.008	0.04	<0.1	0.10	0.6	0.2	<0.05	2	1.6	<0.2				
1093119	Soil	29	0.39	1134	0.003	5	0.75	0.004	0.09	0.1	0.74	4.2	0.9	0.08	2	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1093119	QC	30	0.40	1189	0.004	6	0.83	0.004	0.09	0.1	0.76	4.0	0.9	0.05	2	6.3	<0.2				
1093136	Soil	55	0.09	577	0.010	2	0.68	0.009	0.12	0.1	0.21	4.5	0.3	0.23	7	17.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1093136	QC	51	0.09	586	0.010	1	0.65	0.009	0.11	0.2	0.18	4.3	0.3	0.16	7	15.3	<0.2				
1093154	Soil	5	0.01	290	0.003	2	0.23	0.003	0.06	<0.1	0.01	0.1	0.3	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1093154	QC	5	0.01	287	0.003	2	0.22	0.003	0.06	0.1	0.01	0.2	0.3	<0.05	2	1.4	<0.2				
1093169	Soil	34	0.03	268	0.004	2	0.44	0.013	0.23	0.2	0.34	1.6	1.9	0.27	5	16.8	0.2	N.A.	N.A.	N.A.	N.A.
REP 1093169	QC	33	0.03	278	0.004	2	0.42	0.013	0.23	0.2	0.32	1.4	1.9	0.26	5	14.3	0.2				
1093191	Soil	16	0.02	535	0.003	3	0.32	0.003	0.10	0.2	0.51	1.2	1.5	0.18	2	6.4	0.2	N.A.	N.A.	N.A.	N.A.
REP 1093191	QC	17	0.02	532	0.003	2	0.32	0.003	0.11	0.2	0.55	1.2	1.5	0.16	2	5.8	<0.2				
1093211	Soil	18	0.03	361	0.005	1	0.61	0.003	0.06	<0.1	0.08	0.4	0.4	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1093211	QC	17	0.03	346	0.005	<1	0.56	0.002	0.06	<0.1	0.05	0.3	0.4	<0.05	3	1.5	<0.2				
1093245	Soil	13	0.02	120	0.004	<1	0.36	0.006	0.03	0.1	0.02	0.2	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1093245	QC	14	0.02	125	0.003	2	0.38	0.007	0.04	0.1	0.02	0.3	0.2	<0.05	3	1.2	<0.2				
1094211	Soil	52	0.04	697	0.005	8	0.90	0.012	0.26	<0.1	1.18	6.4	1.9	0.71	4	28.6	0.7	N.A.	N.A.	N.A.	N.A.
REP 1094211	QC	51	0.04	704	0.005	7	0.87	0.012	0.25	<0.1	1.15	6.3	1.9	0.72	4	29.3	0.6				
1094219	Soil	29	0.02	578	0.001	4	0.31	0.006	0.19	<0.1	0.47	5.9	0.4	0.45	4	6.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094219	QC	29	0.01	562	0.001	4	0.31	0.005	0.19	<0.1	0.49	5.9	0.4	0.44	4	6.5	<0.2				
1094243	Soil	40	0.04	2710	0.005	4	0.74	0.006	0.10	<0.1	0.92	2.2	0.5	0.09	4	14.2	0.4	N.A.	N.A.	N.A.	N.A.
REP 1094243	QC	39	0.04	2583	0.004	4	0.76	0.006	0.11	<0.1	0.87	2.2	0.5	0.11	4	14.4	0.3				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

QUALITY CONTROL REPORT WHI11000982.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1090869	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090869	QC																					
1091652	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091652	QC																					
1093084	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093084	QC																					
1093111	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093111	QC																					
1093119	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093119	QC																					
1093136	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093136	QC																					
1093154	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093154	QC																					
1093169	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093169	QC																					
1093191	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093191	QC																					
1093211	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093211	QC																					
1093245	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093245	QC																					
1094211	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094211	QC																					
1094219	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094219	QC																					
1094243	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094243	QC																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

QUALITY CONTROL REPORT WHI11000982.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1090869	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090869	QC													
1091652	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1091652	QC													
1093084	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093084	QC													
1093111	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093111	QC													
1093119	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093119	QC													
1093136	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093136	QC													
1093154	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093154	QC													
1093169	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093169	QC													
1093191	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093191	QC													
1093211	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093211	QC													
1093245	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1093245	QC													
1094211	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094211	QC													
1094219	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094219	QC													
1094243	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094243	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

QUALITY CONTROL REPORT WHI11000982.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1094253	Soil	9.0	104.0	26.5	51	5.5	13.8	1.7	83	7.71	114.8	9.1	1.6	510	0.3	35.0	0.4	259	0.07	0.604	3
REP 1094253	QC	9.5	108.8	26.9	53	5.6	14.5	1.8	84	7.82	114.0	8.2	1.6	509	0.2	35.3	0.3	256	0.07	0.588	3
1094285	Soil	120.6	127.0	16.4	810	0.6	261.6	16.9	257	3.90	53.5	2.2	0.8	72	11.2	12.1	<0.1	339	0.51	0.202	7
REP 1094285	QC	119.3	125.8	16.6	836	0.7	259.3	17.8	266	3.87	53.4	2.0	0.8	71	11.0	11.6	0.1	361	0.53	0.198	7
1094314	Soil	13.4	113.6	17.8	194	2.6	65.9	9.0	643	8.15	38.8	6.9	1.0	35	1.3	17.7	0.2	130	0.02	0.131	3
REP 1094314	QC	13.6	111.2	17.8	201	2.6	64.9	8.6	652	8.41	41.7	6.5	0.9	35	1.5	17.6	0.2	130	0.02	0.130	3
Reference Materials																					
STD DS8	Standard	13.6	112.8	126.8	312	1.8	40.3	7.7	622	2.43	25.5	106.6	6.9	62	2.3	4.7	6.7	38	0.71	0.080	15
STD DS8	Standard	13.3	109.8	125.7	315	1.9	39.9	8.1	621	2.51	24.7	116.3	7.2	70	2.4	5.5	6.3	43	0.69	0.078	16
STD DS8	Standard	13.2	108.2	132.5	326	1.8	38.8	7.5	631	2.50	24.8	118.3	6.8	70	2.4	5.1	6.6	45	0.70	0.078	14
STD DS8	Standard	14.1	119.2	129.2	327	1.8	41.2	8.2	643	2.57	25.3	128.2	7.6	74	2.4	6.1	6.9	47	0.75	0.083	17
STD DS8	Standard	13.5	109.0	124.3	307	1.7	37.8	7.5	615	2.44	24.3	114.6	6.5	67	2.3	5.6	6.7	42	0.69	0.082	14
STD DS8	Standard	12.7	117.1	122.3	313	1.8	40.5	7.7	588	2.34	23.8	107.1	6.3	59	2.3	5.4	6.3	39	0.66	0.079	14
STD DS8	Standard	13.7	114.6	129.2	343	2.1	39.7	8.0	659	2.88	27.9	118.3	6.9	70	2.5	6.3	6.7	46	0.75	0.086	17
STD DS8	Standard	13.3	110.2	125.7	325	1.7	37.1	7.5	611	2.77	25.3	115.3	6.7	65	2.6	5.6	6.5	43	0.71	0.082	17
STD DS8	Standard	12.2	101.1	120.6	300	1.9	35.7	7.0	557	2.33	23.0	111.6	6.1	63	2.1	5.1	5.7	39	0.65	0.076	14
STD DS8	Standard																				
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

QUALITY CONTROL REPORT WHI11000982.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1094253	Soil	83	0.02	488	0.004	2	0.47	0.013	0.17	0.2	0.58	13.3	1.1	0.51	4	20.5	0.3	N.A.	N.A.	N.A.	N.A.
REP 1094253	QC	82	0.02	530	0.004	2	0.47	0.012	0.17	0.1	0.60	13.3	1.1	0.46	4	20.6	0.3				
1094285	Soil	38	0.04	307	0.004	2	0.43	0.003	0.06	0.1	0.24	3.4	1.2	<0.05	1	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094285	QC	40	0.04	302	0.004	2	0.44	0.003	0.06	0.1	0.23	3.4	1.2	<0.05	1	5.5	<0.2				
1094314	Soil	39	0.06	210	0.006	3	0.99	0.010	0.06	0.2	0.12	5.6	0.6	0.14	3	7.4	0.2	N.A.	N.A.	N.A.	N.A.
REP 1094314	QC	40	0.06	211	0.006	2	0.98	0.010	0.06	0.1	0.11	5.5	0.6	0.17	3	8.3	<0.2				
Reference Materials																					
STD DS8	Standard	121	0.56	269	0.122	<1	0.92	0.097	0.40	3.0	0.22	2.7	5.4	0.17	4	5.4	5.2				
STD DS8	Standard	116	0.61	281	0.117	4	0.92	0.092	0.42	3.0	0.20	2.1	5.8	0.16	5	5.0	5.3				
STD DS8	Standard	125	0.60	282	0.111	3	0.96	0.095	0.45	2.8	0.21	3.2	5.3	0.18	5	6.1	5.5				
STD DS8	Standard	128	0.65	299	0.132	3	1.00	0.115	0.45	3.0	0.20	2.7	5.5	0.15	5	5.7	4.8				
STD DS8	Standard	115	0.61	280	0.116	3	0.90	0.091	0.41	2.9	0.21	2.3	5.2	0.14	5	5.1	4.9				
STD DS8	Standard	113	0.61	276	0.113	2	0.89	0.088	0.38	3.2	0.21	1.9	5.5	0.10	4	4.1	4.7				
STD DS8	Standard	125	0.64	309	0.126	3	0.98	0.096	0.48	3.1	0.22	2.8	5.6	0.23	5	4.6	5.2				
STD DS8	Standard	119	0.59	270	0.120	3	0.94	0.090	0.42	3.1	0.18	2.7	5.7	0.18	5	5.9	5.7				
STD DS8	Standard	110	0.52	258	0.106	<1	0.82	0.085	0.38	3.1	0.24	2.4	5.4	<0.05	5	6.6	4.1				
STD DS8	Standard																	13.5	118.3	126.9	318
STD DS8	Standard																	13.4	111.3	123.9	307
STD OREAS45CA	Standard																	1.0	491.7	20.8	63
STD OREAS45CA	Standard																	0.9	492.3	20.7	61
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

QUALITY CONTROL REPORT WHI11000982.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1094253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094253	QC																				
1094285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094285	QC																				
1094314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094314	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.8	39.3	7.6	629	2.54	26.3	158.6	6.9	67	2.2	5.4	6.8	45	0.68	0.075	15	120	0.62	311	0.117
STD DS8	Standard	2.0	36.7	7.7	597	2.44	24.8	106.2	5.9	65	2.4	4.9	6.1	41	0.69	0.081	15	117	0.61	299	0.113
STD OREAS45CA	Standard	0.2	232.6	87.6	891	15.73	4.1	44.7	7.0	15	<0.1	0.1	0.3	199	0.41	0.036	16	662	0.14	162	0.130
STD OREAS45CA	Standard	0.3	239.5	87.2	925	16.38	4.3	45.1	6.3	15	<0.1	0.1	0.2	200	0.41	0.040	15	702	0.16	159	0.137
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

QUALITY CONTROL REPORT WHI11000982.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1094253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094253	QC												
1094285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094285	QC												
1094314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094314	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.91	0.091	0.42	3.0	0.18	2.0	5.6	0.13	5	4.8	5.4
STD DS8	Standard	<20	0.91	0.091	0.41	2.7	0.17	2.1	5.7	0.15	5	4.6	4.8
STD OREAS45CA	Standard	<20	3.56	0.011	0.07	<0.1	0.02	35.5	<0.1	<0.05	17	0.7	<0.2
STD OREAS45CA	Standard	<20	3.72	0.014	0.07	<0.1	0.03	36.8	<0.1	<0.05	19	1.3	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

QUALITY CONTROL REPORT WHI11000982.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

QUALITY CONTROL REPORT WHI11000982.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

QUALITY CONTROL REPORT WHI11000982.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 11, 2011

QUALITY CONTROL REPORT WHI11000982.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 01, 2011
Report Date: January 12, 2012
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11000983.3

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #8
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve to 230 mesh			WHI
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	313	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	7	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 3: Revised sample ID's for 1276076 to 1276080

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094321	Soil		14.6	19.6	14.3	14	0.7	3.6	0.6	17	1.71	25.4	2.4	0.1	26	<0.1	5.9	0.2	124	0.02	0.085	2
1094322	Soil		16.3	25.0	17.7	90	1.1	21.6	3.3	86	2.16	26.7	4.4	0.2	57	0.6	6.8	0.2	119	0.13	0.122	8
1094323	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094324	Soil		12.8	12.9	8.4	98	0.3	17.6	2.6	44	1.00	8.7	<0.5	0.3	17	0.2	3.0	<0.1	80	0.04	0.060	5
1094325	Soil		11.6	27.2	17.8	189	0.2	37.2	7.3	158	3.09	24.0	4.0	0.1	15	0.2	4.3	0.3	105	0.03	0.067	10
1094326	Soil		5.8	10.6	11.3	81	<0.1	14.5	3.2	39	1.29	14.7	4.0	<0.1	8	<0.1	2.3	0.2	53	0.01	0.038	4
1094327	Soil		8.7	17.7	17.9	37	0.5	9.3	1.8	43	2.14	22.5	1.9	0.3	26	<0.1	2.6	0.2	102	0.02	0.051	9
1094328	Soil		4.3	7.2	4.0	21	0.4	4.0	1.0	13	0.45	8.7	0.6	<0.1	13	<0.1	0.9	<0.1	31	0.02	0.026	3
1094329	Soil		9.7	8.7	32.4	32	0.6	5.3	0.9	15	0.82	18.7	<0.5	0.2	24	0.1	3.2	0.3	44	<0.01	0.060	7
1094330	Soil		44.5	25.9	9.3	663	0.2	115.0	9.9	106	2.32	22.1	<0.5	<0.1	8	0.4	5.4	0.1	187	0.01	0.083	8
1094331	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094332	Soil		10.9	13.7	19.0	137	0.1	21.5	2.3	32	1.09	13.4	<0.5	<0.1	23	0.2	2.1	0.2	102	0.03	0.186	10
1094333	Soil		25.8	28.9	19.6	259	0.3	37.1	4.4	50	1.81	20.6	1.1	<0.1	19	0.2	9.6	0.2	269	0.02	0.079	11
1094334	Soil		17.9	34.2	18.9	316	0.8	48.4	6.1	106	1.91	19.7	3.5	0.5	20	0.8	6.2	0.2	173	0.03	0.120	13
1094335	Soil		22.7	30.0	20.9	280	0.8	46.1	5.0	63	1.97	23.9	1.0	0.2	17	0.3	7.4	0.2	190	0.02	0.078	14
1094336	Soil		21.8	27.9	15.5	265	0.5	41.7	4.6	58	1.71	21.9	0.6	0.2	17	1.3	6.8	0.2	258	0.05	0.055	15
1094337	Soil		7.7	16.0	5.4	155	0.7	23.6	2.1	55	0.74	8.7	<0.5	<0.1	9	2.3	2.6	<0.1	117	0.06	0.063	4
1094338	Soil		17.6	31.7	13.5	378	0.9	53.6	6.0	160	1.95	20.5	2.8	0.8	24	4.4	4.9	0.2	210	0.15	0.156	10
1094339	Soil		10.1	21.0	21.8	196	0.7	24.5	3.5	89	1.57	17.0	1.1	0.4	27	2.9	2.4	0.3	131	0.10	0.209	9
1094340	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094341	Soil		4.4	19.0	52.1	34	0.4	10.3	2.4	42	1.04	18.0	0.8	<0.1	51	<0.1	3.1	0.2	41	0.03	0.067	6
1094342	Soil		6.7	24.8	54.2	54	1.0	24.0	6.9	107	2.12	32.8	1.5	0.4	50	0.1	3.5	0.3	41	0.03	0.063	4
1094343	Soil		1.6	10.7	9.8	21	0.6	11.3	5.0	43	0.81	7.0	<0.5	0.1	7	<0.1	0.9	0.1	16	0.02	0.024	2
1094344	Soil		5.0	18.0	40.0	19	0.4	25.9	5.1	62	1.41	15.8	<0.5	0.7	32	<0.1	2.2	0.2	17	0.02	0.046	2
1094345	Soil		10.2	49.8	29.3	191	0.3	58.0	10.2	180	2.86	41.8	4.1	0.7	28	0.7	6.2	0.7	53	0.18	0.138	12
1094346	Soil		15.7	31.1	9.9	268	0.3	71.6	12.4	197	1.53	10.4	1.4	0.8	20	1.6	2.9	<0.1	74	0.16	0.083	6
1094347	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094348	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094349	Soil		1.7	18.4	11.6	53	0.1	16.0	6.8	120	1.47	9.0	<0.5	0.4	6	0.2	0.7	0.2	20	0.03	0.076	3
1094350	Soil		1.5	12.0	11.6	68	<0.1	16.9	10.8	106	1.21	11.2	1.5	0.4	8	<0.1	0.5	0.2	13	0.02	0.053	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094321	Soil	13	0.02	307	0.004	2	0.23	0.005	0.09	0.1	0.06	0.6	0.7	0.23	2	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094322	Soil	25	0.15	550	0.007	3	0.59	0.006	0.10	0.2	0.18	0.6	1.0	0.21	3	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094323	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	10.9	16.5	31.8	123
1094324	Soil	12	0.01	278	0.005	3	0.17	0.007	0.06	0.1	<0.01	0.5	0.3	0.11	1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094325	Soil	20	0.10	151	0.008	1	0.77	0.004	0.05	0.2	0.06	0.5	0.3	<0.05	4	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094326	Soil	7	0.01	83	0.004	<1	0.26	0.006	0.03	<0.1	0.02	0.3	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094327	Soil	16	0.07	380	0.006	2	0.70	0.002	0.07	0.1	0.20	0.5	0.3	0.09	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094328	Soil	4	<0.01	42	0.004	1	0.16	0.014	0.02	<0.1	0.02	<0.1	<0.1	<0.05	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094329	Soil	7	0.01	235	0.003	3	0.24	0.004	0.09	<0.1	0.03	0.3	0.4	0.10	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094330	Soil	11	0.02	83	0.005	2	0.36	0.006	0.04	0.3	<0.01	0.2	0.5	<0.05	3	4.8	0.2	N.A.	N.A.	N.A.	N.A.
1094331	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	30.3	28.4	27.4	411
1094332	Soil	15	0.04	246	0.003	3	0.65	0.004	0.07	0.1	0.01	0.2	0.6	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094333	Soil	14	0.02	985	0.003	2	0.32	0.003	0.06	0.2	0.04	0.1	0.8	<0.05	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094334	Soil	16	0.04	882	0.005	3	0.44	0.004	0.08	0.2	0.14	1.0	0.7	<0.05	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094335	Soil	14	0.03	210	0.003	2	0.47	0.003	0.07	0.1	0.04	0.4	0.6	<0.05	3	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094336	Soil	16	0.03	436	0.004	2	0.39	0.002	0.06	0.2	0.08	0.4	0.6	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094337	Soil	9	0.03	422	0.004	2	0.44	0.016	0.03	<0.1	0.14	0.3	0.3	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094338	Soil	24	0.13	866	0.005	3	0.91	0.005	0.07	0.1	0.37	1.5	0.6	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094339	Soil	19	0.06	1027	0.006	2	0.92	0.007	0.06	0.1	0.39	1.1	0.4	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094340	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.5	69.4	16.8	110
1094341	Soil	8	0.01	108	0.004	<1	0.32	0.010	0.03	0.1	0.02	<0.1	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094342	Soil	12	0.03	183	0.002	<1	0.39	0.003	0.07	<0.1	0.03	1.7	0.3	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094343	Soil	4	0.01	55	0.003	<1	0.17	0.010	0.02	<0.1	<0.01	0.9	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094344	Soil	8	0.01	192	<0.001	2	0.31	0.003	0.04	<0.1	0.05	2.1	0.2	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094345	Soil	20	0.15	158	0.006	2	0.58	0.006	0.06	0.1	0.06	1.6	0.2	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094346	Soil	16	0.05	215	0.004	2	0.37	0.013	0.04	<0.1	0.09	2.5	0.4	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094347	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.6	12.5	10.3	55
1094348	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.8	25.6	25.5	153
1094349	Soil	10	0.04	87	0.004	2	0.56	0.013	0.04	<0.1	0.04	1.3	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094350	Soil	6	0.02	34	0.002	2	0.31	0.008	0.04	<0.1	0.01	1.4	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094323	Soil	1.2	35.9	2.1	92	1.43	25.1	6.0	0.2	55	0.7	6.0	0.2	92	0.48	0.117	6	22	0.11	432	0.007
1094324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094326	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094327	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094328	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094329	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094330	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094331	Soil	0.3	71.5	4.9	65	2.05	22.9	<0.5	0.1	47	0.5	3.4	0.2	184	0.04	0.154	7	22	0.05	278	0.003
1094332	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094333	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094334	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094335	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094336	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094338	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094340	Soil	0.5	50.2	11.7	413	2.72	17.6	1.8	0.1	16	0.4	2.8	0.3	68	0.04	0.085	5	18	0.04	139	0.005
1094341	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094342	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094343	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094344	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094345	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094346	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094347	Soil	0.1	15.9	4.4	80	1.19	6.5	1.3	0.1	8	0.1	0.7	0.1	27	0.04	0.043	3	11	0.06	90	0.003
1094348	Soil	0.2	32.8	14.0	214	3.89	13.6	<0.5	0.9	8	0.1	0.8	0.3	29	0.03	0.073	4	19	0.11	40	0.002
1094349	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094350	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094323	Soil	<20	0.62	0.015	0.08	0.2	0.51	0.7	0.9	0.17	2	4.8	<0.2
1094324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094326	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094327	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094328	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094329	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094330	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094331	Soil	<20	0.71	0.008	0.09	0.1	0.04	0.2	1.9	0.05	3	2.5	<0.2
1094332	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094333	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094334	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094335	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094336	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094338	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094340	Soil	<20	0.50	0.007	0.06	<0.1	0.07	0.5	0.2	<0.05	2	1.6	<0.2
1094341	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094342	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094343	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094344	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094345	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094346	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094347	Soil	<20	0.38	0.016	0.04	0.2	0.03	0.7	0.1	<0.05	2	0.9	<0.2
1094348	Soil	<20	0.75	0.005	0.04	<0.1	0.03	3.0	0.1	<0.05	3	0.6	<0.2
1094349	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094350	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094351	Soil	3.2	34.7	21.7	137	0.1	33.5	23.2	282	3.03	31.9	<0.5	1.6	5	0.3	1.5	0.4	22	0.03	0.067	3
1094352	Soil	6.1	13.9	8.1	92	0.2	16.9	2.4	29	0.79	9.0	0.7	0.1	8	0.8	1.8	<0.1	44	0.02	0.066	5
1094353	Soil	11.3	22.6	14.7	157	0.3	32.9	5.1	81	2.24	22.8	0.8	0.7	8	0.3	3.4	0.2	91	0.02	0.080	7
1094354	Soil	1.6	28.3	20.6	23	0.2	39.8	8.2	93	1.54	11.7	0.9	1.4	11	0.2	0.9	0.3	8	0.07	0.021	2
1094355	Soil	2.5	11.3	8.3	28	0.3	9.1	1.8	32	0.60	3.9	<0.5	0.2	10	0.2	0.8	<0.1	18	0.04	0.052	3
1094356	Soil	2.8	9.1	3.1	34	0.4	8.0	2.1	33	0.57	4.3	<0.5	0.3	5	0.1	0.9	<0.1	26	0.03	0.022	3
1094357	Soil	3.3	11.5	5.8	57	0.3	10.9	2.8	42	0.78	7.2	0.8	<0.1	15	0.2	1.3	0.1	32	0.14	0.027	5
1094358	Soil	6.3	34.2	13.5	159	0.5	35.8	7.9	149	2.24	13.9	3.6	0.8	24	0.6	2.5	0.2	46	0.18	0.052	7
1094359	Soil	5.1	14.2	6.2	64	0.4	12.9	3.3	46	1.00	7.5	3.4	<0.1	4	<0.1	1.5	0.2	52	0.01	0.028	7
1094360	Soil	44.2	22.4	11.1	90	<0.1	59.5	4.0	49	1.01	13.3	1.5	0.6	11	1.0	1.9	<0.1	39	0.11	0.044	3
1094361	Soil	111.3	175.1	24.7	2009	2.8	213.2	7.0	181	2.80	126.2	2.2	2.2	309	20.3	62.3	0.2	592	10.13	0.130	8
1094362	Soil	15.9	19.1	5.4	131	0.1	35.4	3.1	66	0.78	9.6	0.6	0.4	28	1.0	2.8	<0.1	48	0.71	0.063	4
1094363	Soil	15.4	32.2	13.8	193	0.2	60.9	10.9	199	2.53	18.4	1.3	0.8	45	1.3	4.7	0.1	82	0.81	0.110	6
1094364	Soil	13.6	18.6	11.9	133	0.4	38.3	6.9	202	1.46	12.0	1.2	0.2	35	0.6	2.8	<0.1	56	0.29	0.114	5
1094365	Soil	4.4	15.2	7.2	80	0.3	17.4	4.0	145	0.91	6.3	<0.5	<0.1	20	1.4	1.8	<0.1	46	0.34	0.063	4
1094366	Soil	9.1	35.1	11.8	144	<0.1	54.7	8.2	64	2.12	15.5	2.8	0.2	8	0.2	5.3	0.1	86	0.03	0.055	6
1094367	Soil	21.8	68.1	15.0	588	1.5	87.9	6.8	100	1.74	17.6	5.6	0.7	29	5.4	7.6	0.2	125	0.52	0.088	5
1094368	Soil	12.4	47.7	21.0	262	0.9	64.6	11.4	494	2.78	18.6	8.0	0.7	34	0.9	5.0	0.2	90	0.29	0.180	10
1094369	Soil	4.4	21.4	12.1	65	0.4	25.5	5.9	74	1.64	9.8	1.6	<0.1	11	0.4	2.2	0.1	43	0.04	0.055	6
1094370	Soil	10.7	53.8	14.4	131	<0.1	55.8	13.5	125	3.73	21.3	2.2	0.2	6	0.2	5.0	0.4	87	0.02	0.064	13
1094371	Soil	4.0	84.0	19.3	43	0.6	98.5	26.0	1068	10.45	9.9	6.0	5.6	4	0.4	2.9	0.5	36	0.01	0.083	22
1094372	Soil	6.3	23.5	10.7	80	0.3	30.3	8.9	141	1.90	8.8	4.4	0.4	11	1.3	2.1	0.2	42	0.13	0.073	4
1094373	Soil	6.0	99.8	30.0	252	0.3	123.4	13.1	178	3.65	28.2	7.1	0.6	12	0.5	7.7	0.2	33	0.10	0.066	3
1094374	Soil	14.9	92.1	26.1	457	1.0	103.4	12.8	221	3.39	19.7	3.2	0.9	47	4.1	9.7	0.2	123	0.42	0.115	5
1094375	Soil	8.1	90.7	31.9	160	1.4	84.8	15.1	236	4.16	35.4	6.0	0.8	69	0.4	12.7	0.3	35	0.20	0.140	5
1094376	Soil	2.5	102.9	28.9	125	2.0	109.0	44.0	1124	8.69	29.4	26.8	1.2	30	0.2	5.2	0.4	21	0.35	0.097	7
1094377	Soil	1.4	52.8	14.8	62	1.0	55.5	22.7	560	4.27	14.5	14.3	0.6	15	0.1	2.4	0.3	10	0.18	0.051	4
1094378	Soil	7.4	23.5	33.1	87	0.3	27.2	5.3	59	1.68	12.9	1.6	<0.1	78	0.1	3.0	0.3	106	0.03	0.060	10
1094379	Soil	6.3	58.3	13.5	69	0.2	100.2	24.0	401	4.63	12.3	4.9	0.2	17	0.3	1.9	<0.1	66	0.09	0.206	6
1094380	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094351	Soil	11	0.04	51	0.002	1	0.48	0.004	0.06	<0.1	0.03	3.8	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094352	Soil	7	0.02	112	0.002	1	0.27	0.008	0.03	<0.1	0.03	0.1	0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094353	Soil	12	0.03	87	0.008	<1	0.44	0.006	0.04	0.1	0.04	1.2	0.3	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094354	Soil	4	0.02	309	<0.001	3	0.21	0.002	0.04	<0.1	0.09	3.7	0.2	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094355	Soil	6	0.01	148	0.006	2	0.20	0.012	0.03	<0.1	0.05	0.7	0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094356	Soil	5	0.01	44	0.005	<1	0.18	0.010	0.02	<0.1	0.01	0.6	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094357	Soil	5	0.02	104	0.004	2	0.23	0.012	0.02	<0.1	<0.01	0.3	<0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094358	Soil	12	0.10	309	0.003	2	0.58	0.005	0.04	<0.1	0.07	2.0	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094359	Soil	8	0.01	57	0.003	1	0.31	0.005	0.03	<0.1	<0.01	0.2	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094360	Soil	10	0.02	169	0.003	2	0.28	0.008	0.02	0.2	0.06	1.1	0.5	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094361	Soil	26	2.74	427	0.003	6	0.32	0.011	0.08	0.3	1.79	3.6	3.1	0.08	<1	9.4	0.2	N.A.	N.A.	N.A.	N.A.
1094362	Soil	8	0.08	245	0.009	3	0.53	0.021	0.03	0.2	0.11	0.9	0.4	0.11	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094363	Soil	24	0.11	431	0.004	2	0.53	0.014	0.04	0.2	0.08	2.2	0.2	0.09	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094364	Soil	14	0.06	228	0.003	<1	0.55	0.013	0.03	0.1	0.06	0.6	0.2	0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094365	Soil	9	0.06	322	0.004	2	0.44	0.022	0.02	<0.1	0.03	0.5	0.1	0.07	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094366	Soil	16	0.02	96	0.001	1	0.27	0.006	0.04	<0.1	0.02	0.5	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094367	Soil	15	0.07	470	0.003	2	0.40	0.012	0.06	<0.1	0.34	3.0	0.4	0.10	1	2.8	0.3	N.A.	N.A.	N.A.	N.A.
1094368	Soil	23	0.06	1238	0.003	2	0.69	0.005	0.05	0.1	0.18	2.2	0.2	0.06	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094369	Soil	8	0.02	779	0.003	<1	0.31	0.009	0.04	<0.1	0.02	0.6	<0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094370	Soil	13	0.03	95	0.002	2	0.32	0.003	0.04	<0.1	0.01	0.8	0.2	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094371	Soil	9	0.06	130	<0.001	1	0.40	0.002	0.04	0.1	0.19	11.3	0.1	<0.05	<1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094372	Soil	7	0.04	248	0.006	<1	0.40	0.014	0.04	0.2	0.05	1.3	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094373	Soil	20	0.06	195	0.001	1	0.28	0.003	0.03	0.1	0.05	3.5	0.2	<0.05	<1	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094374	Soil	17	0.07	266	0.001	2	0.28	0.002	0.06	0.1	0.41	4.3	0.2	<0.05	<1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094375	Soil	14	0.03	835	0.001	2	0.35	0.002	0.05	<0.1	0.32	4.2	0.2	<0.05	<1	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094376	Soil	14	0.11	505	0.003	5	0.46	0.004	0.09	<0.1	0.23	10.0	0.3	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094377	Soil	7	0.05	261	0.001	2	0.22	0.002	0.05	<0.1	0.12	4.9	0.2	<0.05	<1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094378	Soil	13	0.03	157	0.003	<1	0.46	0.005	0.04	<0.1	0.01	<0.1	0.2	<0.05	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094379	Soil	35	0.04	139	0.003	2	0.56	0.012	0.03	0.1	0.04	1.3	<0.1	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094380	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094351	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094352	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094353	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094354	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094355	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094356	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094357	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094358	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094359	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094360	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094361	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094362	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094363	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094364	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094365	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094366	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094367	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094368	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094369	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094370	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094371	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094372	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094373	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094374	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094375	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094376	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094377	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094378	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094379	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094380	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094351	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094352	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094353	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094354	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094355	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094356	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094357	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094358	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094359	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094360	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094361	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094362	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094363	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094364	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094365	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094366	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094367	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094368	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094369	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094370	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094371	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094372	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094373	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094374	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094375	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094376	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094377	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094378	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094379	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094380	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094381	Soil	9.4	49.7	20.4	109	0.4	187.4	39.5	1439	17.54	11.2	7.9	0.9	16	0.4	3.1	0.1	219	0.16	0.223	12
1094382	Soil	32.9	26.6	11.3	247	0.2	68.1	6.9	298	3.80	19.1	5.9	0.3	18	0.5	5.7	0.2	163	0.33	0.135	7
1094383	Soil	13.5	15.8	8.9	70	0.2	16.8	3.1	58	1.13	10.8	2.1	<0.1	13	0.1	2.0	0.2	62	0.06	0.106	7
1094384	Soil	61.7	71.8	17.7	158	0.3	153.4	9.4	331	3.49	23.2	2.7	0.8	104	1.6	3.4	0.1	64	5.41	0.096	5
1094385	Soil	25.8	19.8	10.4	88	0.1	42.3	4.2	121	1.84	12.8	1.0	<0.1	17	0.8	2.6	0.2	54	0.36	0.118	5
1094386	Soil	28.9	42.4	26.6	681	0.9	78.6	13.2	309	3.57	41.8	3.2	0.5	19	6.0	15.0	0.2	182	0.17	0.113	5
1094387	Soil	10.0	27.4	19.2	108	0.1	32.4	5.6	67	2.00	22.0	1.8	<0.1	11	0.2	4.4	0.2	84	0.02	0.090	9
1094388	Soil	18.8	84.3	26.0	211	0.9	81.8	4.7	34	2.26	42.3	1.7	<0.1	53	0.4	11.3	0.2	128	0.03	0.153	8
1094389	Soil	0.8	7.1	3.3	32	<0.1	5.1	1.0	20	0.38	2.1	1.4	<0.1	4	0.1	0.6	<0.1	8	0.02	0.065	<1
1094390	Soil	8.3	44.2	25.1	253	0.1	26.8	5.8	180	2.34	16.8	3.0	<0.1	8	0.2	5.1	0.1	41	0.03	0.221	5
1094391	Soil	3.6	11.0	10.0	42	<0.1	10.7	3.1	68	1.07	5.7	0.9	<0.1	6	<0.1	1.3	0.1	28	0.02	0.055	4
1094392	Soil	10.5	36.6	37.5	194	0.1	49.2	23.4	525	4.63	26.8	2.5	1.3	14	0.3	4.2	0.4	67	0.03	0.066	12
1094393	Soil	4.6	21.6	24.3	80	0.2	19.1	7.9	368	4.06	10.7	2.3	0.2	10	0.3	1.5	0.4	36	0.03	0.130	7
1094394	Soil	8.7	41.2	30.5	171	0.1	45.4	15.4	343	4.44	25.0	1.3	1.3	11	0.3	3.9	0.4	57	0.03	0.064	8
1094395	Soil	9.9	36.5	27.4	232	0.1	55.2	17.7	393	3.86	73.2	2.3	1.0	11	0.5	3.8	0.3	80	0.03	0.093	11
1094396	Soil	0.7	20.4	26.4	85	<0.1	29.2	19.9	472	3.63	34.1	<0.5	2.6	8	<0.1	2.0	0.4	6	0.03	0.035	7
1094397	Soil	5.9	26.5	53.5	114	0.1	30.5	15.2	779	3.41	16.4	1.6	1.2	9	0.2	2.0	0.3	35	0.03	0.055	9
1094398	Soil	2.2	24.8	30.3	79	0.1	30.1	16.8	472	3.20	12.7	2.3	0.9	11	0.2	1.7	0.4	21	0.04	0.102	10
1094399	Soil	2.0	33.1	57.1	91	0.2	44.0	33.5	1648	4.55	10.6	0.9	1.8	8	<0.1	1.0	0.4	15	0.03	0.126	10
1094400	Soil	1.1	16.6	16.8	38	0.1	13.7	10.7	642	1.92	4.4	<0.5	0.5	6	<0.1	0.5	0.2	9	0.03	0.088	4
1094501	Soil	2.1	81.5	9.8	171	0.7	65.2	28.5	840	7.71	6188	389.9	0.7	76	0.9	135.4	<0.1	33	0.78	0.104	7
1094502	Soil	1.5	218.1	13.5	159	0.8	205.4	91.8	1063	13.68	8880	364.3	0.4	93	1.9	82.2	<0.1	43	2.21	0.090	6
1094503	Soil	13.8	90.2	23.7	621	0.3	124.6	13.9	116	3.36	50.2	3.6	0.3	11	0.9	19.4	0.2	97	0.06	0.145	5
1094504	Soil	50.5	31.9	15.2	211	0.2	154.8	11.3	333	3.36	33.1	1.6	3.1	131	0.3	9.7	0.2	86	5.41	0.057	10
1094505	Soil	5.9	116.8	6.5	371	0.4	137.6	52.6	1045	8.81	1400	98.5	0.5	46	0.9	47.9	<0.1	44	1.08	0.104	7
1094506	Soil	2.3	117.7	23.2	38	0.8	76.4	27.4	550	7.42	23.3	3.5	6.5	26	<0.1	6.4	0.6	19	1.13	0.048	28
1094507	Soil	81.1	64.8	11.2	221	0.3	173.1	7.6	166	1.90	29.4	1.1	1.6	201	0.7	18.3	0.1	74	11.64	0.074	3
1094601	Soil	3.5	41.0	17.3	35	1.0	7.7	1.8	39	2.28	21.7	1.7	<0.1	17	0.1	3.3	0.2	91	0.03	0.089	6
1094602	Soil	5.0	36.4	17.7	55	1.0	13.5	3.2	91	2.95	39.7	5.7	0.5	21	0.1	6.6	0.3	112	0.05	0.102	9
1094603	Soil	4.0	33.5	22.0	39	1.6	10.4	2.7	116	2.59	38.2	12.8	0.8	23	<0.1	5.7	0.2	71	0.08	0.116	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094381	Soil		190	0.17	218	0.004	<1	1.04	0.005	0.03	0.2	0.11	13.3	0.2	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094382	Soil		23	0.08	246	0.004	<1	0.82	0.012	0.04	0.1	<0.01	1.5	0.4	<0.05	3	7.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094383	Soil		9	0.03	151	<0.001	<1	0.70	0.007	0.04	<0.1	<0.01	0.1	0.4	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094384	Soil		16	1.93	199	0.001	3	0.26	0.007	0.03	0.1	0.32	2.6	0.9	<0.05	<1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094385	Soil		13	0.07	214	0.002	<1	0.46	0.008	0.05	0.1	0.06	0.5	0.4	0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094386	Soil		19	0.03	295	0.002	1	0.56	0.004	0.05	<0.1	0.30	2.4	0.4	<0.05	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094387	Soil		13	0.02	108	0.007	2	0.41	0.004	0.05	<0.1	0.02	0.2	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094388	Soil		18	<0.01	114	<0.001	<1	0.31	0.006	0.05	<0.1	0.04	0.1	0.4	0.06	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094389	Soil		3	0.01	26	0.001	<1	0.22	0.022	0.02	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094390	Soil		13	0.02	110	<0.001	<1	0.49	0.007	0.06	<0.1	0.01	0.2	0.3	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094391	Soil		7	0.02	46	0.002	1	0.38	0.017	0.04	<0.1	0.02	0.2	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094392	Soil		23	0.21	129	0.004	1	1.26	0.004	0.07	<0.1	0.02	2.0	0.4	<0.05	4	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094393	Soil		22	0.09	77	0.006	4	1.02	0.007	0.05	<0.1	0.08	0.7	0.1	<0.05	5	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094394	Soil		24	0.23	103	0.004	1	1.10	0.004	0.05	<0.1	0.03	2.3	0.2	<0.05	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094395	Soil		24	0.15	128	0.004	<1	1.04	0.006	0.06	<0.1	0.05	2.2	0.3	<0.05	4	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094396	Soil		7	0.08	68	<0.001	<1	0.39	0.002	0.03	<0.1	0.06	3.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094397	Soil		17	0.19	71	0.007	1	1.02	0.005	0.04	0.1	0.06	1.7	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094398	Soil		15	0.11	98	0.007	3	0.67	0.009	0.06	0.1	0.08	2.2	<0.1	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094399	Soil		15	0.14	130	0.002	2	0.69	0.005	0.06	<0.1	0.13	3.6	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094400	Soil		9	0.06	44	0.005	1	0.65	0.014	0.04	<0.1	0.06	0.8	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094501	Soil		29	0.20	563	0.002	2	0.69	0.005	0.09	0.2	0.11	21.2	0.1	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094502	Soil		50	0.47	674	<0.001	7	0.44	0.003	0.21	0.1	0.36	46.6	0.3	0.09	<1	1.5	0.3	N.A.	N.A.	N.A.	N.A.
1094503	Soil		24	0.03	100	0.002	<1	0.40	0.002	0.05	<0.1	0.11	1.3	0.2	<0.05	2	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094504	Soil		14	2.76	453	0.006	5	0.26	0.011	0.06	0.1	0.12	4.5	0.6	0.08	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094505	Soil		43	0.24	461	0.002	5	0.74	0.004	0.15	0.2	0.11	29.8	0.1	0.11	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094506	Soil		12	0.50	789	0.001	5	0.30	0.003	0.11	<0.1	0.19	7.9	0.2	0.17	<1	4.0	0.4	N.A.	N.A.	N.A.	N.A.
1094507	Soil		13	3.97	188	0.002	6	0.19	0.007	0.05	0.2	0.33	3.2	1.2	0.05	<1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094601	Soil		19	0.01	289	0.005	2	0.52	0.005	0.06	0.1	0.13	0.5	0.3	0.12	4	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094602	Soil		27	0.10	272	0.016	2	0.63	0.006	0.09	0.2	0.16	2.6	0.4	0.12	5	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094603	Soil		19	0.11	270	0.021	2	0.62	0.017	0.09	0.3	0.12	2.7	0.3	0.07	4	4.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094381	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094382	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094383	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094384	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094385	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094386	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094387	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094388	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094389	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094390	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094391	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094392	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094393	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094394	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094395	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094396	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094397	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094398	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094399	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094400	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094501	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094502	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094503	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094504	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094505	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094506	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094507	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094601	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094602	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094603	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094381	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094382	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094383	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094384	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094385	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094386	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094387	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094388	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094389	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094390	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094391	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094392	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094393	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094394	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094395	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094396	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094397	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094398	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094399	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094400	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094501	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094502	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094503	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094504	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094505	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094506	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094507	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094601	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094602	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094603	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094604	Soil	6.0	48.0	19.7	74	1.1	20.4	4.9	241	4.22	59.1	11.1	1.0	27	0.2	6.5	0.2	101	0.06	0.114	10
1094605	Soil	4.9	79.8	44.2	116	1.5	25.7	9.0	236	5.30	23.5	5.8	2.9	20	0.4	3.5	0.5	62	0.01	0.102	3
1094606	Soil	22.8	62.9	45.8	174	1.6	18.7	3.3	73	3.09	24.0	4.5	3.8	81	0.2	7.8	0.4	162	0.02	0.155	11
1094607	Soil	12.6	37.4	52.3	70	2.8	9.9	2.0	62	2.61	29.6	10.6	1.6	66	0.2	11.0	0.4	96	0.02	0.095	6
1094608	Soil	12.7	36.2	43.8	53	4.9	6.9	1.7	54	2.52	26.7	8.7	2.2	61	0.2	16.2	0.4	94	0.01	0.088	5
1094609	Soil	10.8	57.9	32.5	19	3.8	2.9	0.6	22	3.80	53.7	21.0	1.1	50	<0.1	11.3	0.3	118	<0.01	0.090	2
1094610	Soil	17.7	21.6	27.3	24	2.0	4.8	1.0	45	2.73	57.0	3.0	0.1	118	0.1	11.5	0.3	148	0.02	0.193	6
1094611	Soil	11.4	45.8	25.8	36	2.3	8.3	1.3	38	2.51	26.9	9.0	0.9	66	<0.1	7.4	0.3	89	0.01	0.102	2
1094612	Soil	6.1	16.4	10.6	14	1.5	3.4	1.0	50	0.91	12.5	3.1	<0.1	27	<0.1	4.0	0.1	53	0.05	0.076	3
1094613	Soil	16.5	31.6	18.6	28	1.3	5.2	0.5	17	0.83	14.8	6.5	0.3	42	<0.1	5.4	0.2	106	0.02	0.054	13
1094614	Soil	9.2	8.4	8.4	17	0.4	3.6	0.7	21	0.53	6.5	2.9	<0.1	10	<0.1	3.1	0.1	52	0.02	0.041	7
1094615	Soil	21.8	17.9	13.3	45	0.9	8.1	1.6	46	1.26	23.8	6.2	0.2	25	0.1	7.4	0.2	149	0.02	0.043	11
1094616	Soil	9.3	11.8	11.4	33	0.6	5.5	1.0	26	0.90	20.8	4.1	0.2	14	<0.1	4.7	0.2	76	0.02	0.037	5
1094617	Soil	8.3	7.8	12.8	23	0.2	3.7	0.6	28	0.60	15.5	1.6	0.1	10	<0.1	3.5	0.2	56	0.01	0.038	3
1094618	Soil	3.2	14.4	10.9	56	<0.1	8.4	1.9	24	1.06	10.9	<0.5	0.4	7	<0.1	1.0	0.2	30	0.01	0.042	4
1094619	Soil	5.0	11.6	5.4	55	0.1	6.8	1.8	19	0.90	7.9	1.5	<0.1	8	<0.1	1.7	<0.1	36	0.02	0.035	3
1094620	Soil	2.3	9.7	3.4	20	0.1	3.3	1.2	22	0.57	3.0	0.7	<0.1	9	<0.1	0.6	<0.1	22	0.03	0.036	2
1094621	Soil	7.6	19.6	11.3	11	0.6	2.6	0.4	11	0.74	7.1	3.1	0.7	23	<0.1	3.8	0.1	59	0.01	0.043	9
1094622	Soil	17.4	24.2	32.1	51	0.8	7.8	1.7	32	1.87	42.0	18.4	0.2	84	0.2	7.8	0.3	105	0.03	0.118	11
1094623	Soil	15.8	81.5	79.1	191	1.2	27.7	8.4	257	4.03	47.3	5.9	5.3	51	1.1	8.7	0.4	81	0.02	0.130	5
1094624	Soil	15.6	73.0	63.1	159	1.0	22.3	6.6	200	2.95	37.9	4.5	3.2	46	0.5	7.7	0.4	63	0.02	0.108	5
1094625	Soil	9.8	36.8	33.1	87	0.5	11.3	2.2	58	1.33	13.0	2.4	0.2	26	0.2	3.5	0.2	45	0.02	0.095	3
1094626	Soil	7.0	29.4	22.7	330	0.6	39.7	6.3	128	3.06	12.5	1.1	0.4	4	0.3	2.5	0.2	43	0.02	0.091	11
1094627	Soil	5.2	35.0	26.0	157	0.2	32.4	6.4	82	2.22	14.1	<0.5	0.1	14	<0.1	1.9	0.2	38	0.01	0.074	15
1094628	Soil	12.3	31.6	50.7	163	0.8	33.7	4.4	54	2.11	18.3	0.9	0.1	87	0.2	3.0	0.3	82	0.02	0.121	12
1094629	Soil	9.4	20.2	29.3	68	1.0	14.0	1.8	31	1.13	10.9	<0.5	<0.1	59	0.1	1.6	0.2	69	0.02	0.087	7
1094630	Soil	6.0	39.3	16.2	137	0.4	25.6	4.1	38	1.39	10.2	1.6	<0.1	32	0.3	2.2	0.1	31	0.03	0.094	5
1094631	Soil	12.2	95.9	47.9	453	1.0	77.4	10.9	258	4.12	30.4	8.3	1.7	33	3.2	4.2	0.3	48	0.43	0.309	14
1094632	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094633	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094604	Soil	27	0.16	294	0.019	2	0.87	0.008	0.10	0.2	0.09	4.2	0.3	0.12	5	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094605	Soil	21	0.03	309	0.003	1	0.58	0.006	0.10	<0.1	0.10	7.0	0.6	0.08	3	3.8	0.2	N.A.	N.A.	N.A.	N.A.
1094606	Soil	30	0.03	1133	0.002	4	0.65	0.005	0.17	0.1	0.06	10.8	1.6	0.25	4	9.8	0.3	N.A.	N.A.	N.A.	N.A.
1094607	Soil	24	0.05	764	0.003	4	0.52	0.010	0.19	0.1	0.27	6.8	1.1	0.35	4	9.0	0.3	N.A.	N.A.	N.A.	N.A.
1094608	Soil	22	0.03	738	0.002	2	0.47	0.010	0.20	<0.1	0.35	5.5	1.0	0.40	4	12.9	0.5	N.A.	N.A.	N.A.	N.A.
1094609	Soil	26	0.02	617	0.002	3	0.32	0.007	0.17	<0.1	0.47	3.6	0.5	0.36	5	11.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094610	Soil	23	0.03	650	0.004	1	0.72	0.007	0.13	0.2	0.10	0.5	1.0	0.29	5	6.7	0.2	N.A.	N.A.	N.A.	N.A.
1094611	Soil	20	0.02	606	0.002	2	0.32	0.005	0.12	<0.1	0.37	3.8	0.6	0.23	3	9.5	0.3	N.A.	N.A.	N.A.	N.A.
1094612	Soil	14	0.05	205	0.009	1	0.54	0.017	0.06	0.1	0.14	0.5	0.3	0.10	3	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094613	Soil	13	0.02	375	0.003	2	0.38	0.003	0.06	0.1	0.20	0.7	1.1	0.10	2	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094614	Soil	7	0.01	152	0.006	<1	0.36	0.013	0.04	0.1	0.08	0.2	0.4	0.06	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094615	Soil	13	0.07	282	0.007	1	0.49	0.003	0.06	0.2	0.31	0.6	0.9	0.07	3	7.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094616	Soil	7	0.02	254	0.003	2	0.51	0.009	0.05	0.2	0.76	0.6	0.4	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094617	Soil	6	0.01	113	0.002	<1	0.33	0.004	0.05	<0.1	0.06	0.4	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094618	Soil	7	0.02	92	0.002	<1	0.53	0.005	0.05	<0.1	0.06	0.9	0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094619	Soil	4	0.01	319	0.006	<1	0.29	0.018	0.02	<0.1	0.04	0.3	<0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094620	Soil	4	0.02	617	0.011	<1	0.46	0.024	0.03	<0.1	0.06	0.2	<0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094621	Soil	11	0.02	870	0.002	4	0.36	0.003	0.10	<0.1	0.40	0.6	0.5	0.11	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094622	Soil	13	0.02	698	0.007	3	0.32	0.003	0.11	0.3	0.39	0.4	0.6	0.26	2	5.9	0.2	N.A.	N.A.	N.A.	N.A.
1094623	Soil	15	0.03	482	0.004	3	0.45	0.004	0.13	<0.1	0.20	4.1	0.8	0.22	2	5.3	0.3	N.A.	N.A.	N.A.	N.A.
1094624	Soil	12	0.04	313	0.003	3	0.49	0.004	0.12	<0.1	0.09	3.3	0.7	0.17	2	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094625	Soil	7	0.02	148	0.004	4	0.42	0.010	0.07	<0.1	0.04	0.6	0.4	0.11	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094626	Soil	13	0.03	96	0.002	3	0.42	0.004	0.05	<0.1	0.08	0.7	0.2	<0.05	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094627	Soil	8	0.02	142	0.002	2	0.31	0.004	0.05	0.1	<0.01	0.3	0.2	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094628	Soil	11	0.02	277	0.003	2	0.32	0.004	0.09	0.1	0.03	0.3	0.4	0.14	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094629	Soil	11	0.01	233	0.001	2	0.30	0.007	0.09	<0.1	0.03	<0.1	0.3	0.15	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094630	Soil	6	0.02	178	0.001	2	0.27	0.010	0.06	<0.1	0.04	0.2	0.1	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094631	Soil	11	0.05	404	0.004	5	0.38	0.003	0.10	<0.1	0.88	4.1	0.3	0.07	<1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094632	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	13.8	30.4	10.7	273
1094633	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	13.4	35.7	25.4	673

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094604	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094605	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094606	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094607	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094608	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094609	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094610	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094611	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094612	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094613	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094614	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094615	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094616	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094617	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094618	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094619	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094620	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094621	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094622	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094623	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094624	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094625	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094626	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094627	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094628	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094629	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094630	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094631	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094632	Soil		0.4	71.5	8.6	4842	3.20	21.7	2.6	0.3	34	4.3	2.4	0.1	64	0.58	0.232	5	13	0.10	738	0.008
1094633	Soil		0.4	67.9	5.4	288	1.78	36.9	2.6	0.6	42	12.4	7.2	0.2	513	0.71	0.204	11	33	0.23	527	0.007

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094604	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094605	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094606	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094607	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094608	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094609	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094610	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094611	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094612	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094613	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094614	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094615	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094616	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094617	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094618	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094619	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094620	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094621	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094622	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094623	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094624	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094625	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094626	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094627	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094628	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094629	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094630	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094631	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094632	Soil	<20	0.86	0.030	0.05	0.2	0.32	0.7	0.2	0.09	3	3.2	<0.2
1094633	Soil	<20	0.91	0.011	0.15	0.1	0.30	1.1	1.2	0.06	3	3.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094634	Soil	12.7	16.7	10.2	286	0.1	33.5	4.1	109	1.61	34.9	2.5	0.1	17	2.3	3.9	0.1	143	0.18	0.073	8
1094635	Soil	13.1	72.7	41.7	82	3.9	21.3	5.1	322	6.06	71.3	4.3	0.8	280	0.3	20.9	0.5	249	0.08	0.575	12
1094636	Soil	11.3	45.0	22.0	27	4.0	6.1	1.5	94	3.69	62.6	8.6	0.4	221	0.1	9.7	0.3	181	0.04	0.372	4
1094637	Soil	36.1	51.1	17.3	14	3.0	5.7	0.6	27	1.34	21.2	2.5	0.9	45	0.2	13.0	0.2	130	0.02	0.069	3
1094638	Soil	10.9	30.5	17.5	41	2.5	10.1	2.5	113	2.41	21.2	5.1	0.3	39	0.1	5.8	0.3	126	0.04	0.102	7
1094639	Soil	10.4	29.5	12.9	49	1.3	12.6	3.3	120	2.05	19.1	5.8	0.5	31	0.2	5.2	0.2	105	0.06	0.076	7
1094640	Soil	3.9	25.9	7.3	35	0.9	9.4	2.6	82	1.35	10.4	2.9	0.2	16	0.1	2.0	0.1	56	0.06	0.054	6
1094641	Soil	7.5	30.6	10.7	48	1.0	11.0	3.2	130	1.99	18.6	4.4	0.3	20	0.2	4.0	0.2	91	0.05	0.069	7
1094642	Soil	5.8	30.2	10.2	36	1.2	9.7	3.0	212	1.46	13.6	1.7	0.1	19	0.2	3.0	0.2	65	0.05	0.080	5
1094643	Soil	23.3	55.3	19.7	43	2.4	11.7	3.2	148	2.66	28.6	7.1	0.9	49	0.2	8.9	0.2	177	0.06	0.119	7
1094644	Soil	18.2	40.2	18.4	50	1.8	13.4	4.1	196	2.67	26.6	4.2	1.0	48	0.2	7.6	0.3	152	0.06	0.110	8
1094645	Soil	8.9	22.7	12.8	16	1.5	4.4	1.1	28	1.18	11.4	2.7	<0.1	28	<0.1	3.1	0.1	78	0.02	0.069	4
1094646	Soil	10.8	19.4	15.0	92	0.8	17.1	3.5	73	2.03	18.6	<0.5	0.1	15	0.1	3.8	0.2	133	0.01	0.047	9
1094647	Soil	0.3	1.8	1.5	3	<0.1	0.7	0.4	8	0.13	<0.5	<0.5	<0.1	3	<0.1	<0.1	<0.1	6	0.02	0.015	<1
1094648	Soil	9.1	17.3	9.6	16	1.5	3.6	0.6	15	1.16	10.5	0.8	<0.1	20	<0.1	2.5	0.1	75	0.02	0.075	1
1094649	Soil	1.2	8.0	2.3	6	1.4	1.2	0.4	7	0.21	1.2	<0.5	<0.1	6	<0.1	0.2	<0.1	9	0.02	0.043	<1
1094650	Soil	3.8	5.3	4.0	9	0.6	1.8	0.3	10	0.39	3.5	<0.5	<0.1	10	<0.1	1.0	<0.1	27	0.02	0.045	1
1094651	Soil	10.6	6.5	7.9	40	0.3	5.9	1.2	20	0.58	8.0	<0.5	<0.1	9	0.1	1.7	<0.1	40	0.01	0.035	5
1094652	Soil	3.6	6.0	9.8	82	0.6	15.8	1.3	27	0.72	6.1	2.7	<0.1	16	1.8	0.9	0.1	37	0.13	0.125	6
1094653	Soil	1.5	2.6	1.5	10	0.3	1.7	0.4	8	0.28	1.5	<0.5	<0.1	6	<0.1	0.3	<0.1	16	0.02	0.040	<1
1094654	Soil	19.4	17.7	13.2	200	0.1	29.9	3.1	42	2.52	19.0	1.0	0.1	10	0.3	5.8	0.2	238	0.01	0.058	10
1094655	Soil	22.0	36.7	31.6	608	0.2	88.3	7.6	76	2.91	30.7	1.0	0.2	12	1.0	4.2	0.2	173	0.01	0.072	9
1094656	Soil	0.6	1.5	2.5	11	0.3	1.6	0.3	6	0.15	1.0	<0.5	<0.1	4	<0.1	0.2	<0.1	14	0.02	0.025	3
1094657	Soil	5.4	4.2	3.6	33	1.0	4.7	0.7	11	0.31	2.6	1.3	<0.1	5	<0.1	0.8	<0.1	60	0.01	0.045	9
1094658	Soil	22.4	16.7	13.2	175	0.6	29.2	2.7	47	1.21	19.9	0.7	<0.1	9	0.2	6.8	0.1	212	0.01	0.068	5
1094659	Soil	23.3	15.7	8.6	159	0.2	30.5	3.0	36	1.02	15.3	0.7	<0.1	6	0.2	4.2	0.1	109	0.01	0.047	7
1094660	Soil	8.8	9.7	7.2	83	0.3	14.4	1.8	25	0.72	7.8	0.6	<0.1	7	0.2	1.7	0.1	43	0.01	0.048	6
1094661	Soil	29.4	36.9	19.1	418	0.3	73.9	8.5	207	3.41	28.3	2.1	0.3	20	1.0	6.7	0.3	137	0.05	0.111	9
1094662	Soil	6.0	7.8	5.3	86	0.3	12.4	1.6	24	0.58	7.5	<0.5	<0.1	4	0.1	1.7	<0.1	41	0.01	0.040	3
1094663	Soil	13.8	24.4	15.9	248	0.3	38.2	5.3	95	2.32	21.6	2.5	0.3	17	0.9	4.6	0.1	97	0.04	0.103	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094634	Soil		13	0.06	262	0.003	2	0.61	0.010	0.06	0.1	0.04	0.4	0.5	0.07	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094635	Soil		76	0.15	917	0.024	4	1.03	0.018	0.25	0.3	0.21	6.8	1.3	0.56	7	12.6	0.4	N.A.	N.A.	N.A.	N.A.
1094636	Soil		42	0.06	766	0.006	3	0.76	0.020	0.19	0.1	0.39	4.5	1.1	0.45	5	11.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094637	Soil		25	0.03	461	0.004	2	0.30	0.006	0.10	0.2	0.34	2.0	0.7	0.24	2	11.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094638	Soil		28	0.11	408	0.010	1	0.63	0.008	0.09	0.1	0.13	1.2	0.6	0.18	5	10.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094639	Soil		21	0.14	280	0.014	2	0.67	0.008	0.07	0.2	0.10	1.2	0.5	0.13	4	6.4	0.2	N.A.	N.A.	N.A.	N.A.
1094640	Soil		15	0.14	143	0.017	2	0.97	0.015	0.05	0.1	0.07	1.0	0.3	0.06	4	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094641	Soil		22	0.15	192	0.013	2	0.88	0.008	0.06	0.2	0.06	1.0	0.4	0.11	4	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094642	Soil		18	0.13	172	0.014	2	0.72	0.015	0.06	0.1	0.10	0.9	0.3	0.08	3	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094643	Soil		33	0.13	513	0.012	2	0.61	0.007	0.13	0.1	0.16	2.7	1.1	0.23	4	8.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094644	Soil		31	0.16	524	0.015	2	0.63	0.005	0.12	0.1	0.14	2.5	1.0	0.20	5	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094645	Soil		17	0.05	368	0.004	1	0.58	0.014	0.06	<0.1	0.09	0.4	0.6	0.11	4	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094646	Soil		16	0.03	176	0.007	<1	0.55	0.003	0.05	0.2	0.03	0.5	0.3	<0.05	5	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094647	Soil		1	<0.01	19	0.004	<1	0.06	0.018	0.02	<0.1	0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094648	Soil		14	0.02	266	0.002	1	0.22	0.014	0.06	<0.1	0.06	0.4	0.3	0.11	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094649	Soil		3	0.01	96	0.002	<1	0.28	0.021	0.02	<0.1	0.06	0.2	<0.1	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094650	Soil		5	<0.01	112	0.002	<1	0.12	0.015	0.04	<0.1	0.02	0.2	0.2	<0.05	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094651	Soil		5	<0.01	92	0.002	<1	0.13	0.011	0.04	<0.1	0.03	<0.1	0.2	<0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094652	Soil		9	0.07	263	0.003	1	0.70	0.012	0.05	<0.1	0.18	0.1	0.7	0.07	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094653	Soil		2	<0.01	81	0.002	<1	0.09	0.019	0.02	<0.1	0.02	<0.1	0.2	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094654	Soil		11	0.02	137	0.004	2	0.25	0.006	0.05	0.2	0.03	0.3	0.5	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094655	Soil		15	0.05	159	0.002	3	0.65	0.006	0.05	0.1	0.03	0.4	0.6	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094656	Soil		3	0.01	31	0.004	1	0.15	0.016	0.03	<0.1	0.01	0.1	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094657	Soil		5	0.01	58	0.002	2	0.20	0.013	0.04	<0.1	0.02	<0.1	0.3	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094658	Soil		11	0.02	82	0.002	1	0.41	0.006	0.04	0.1	0.03	0.1	0.8	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094659	Soil		6	0.01	60	0.002	1	0.25	0.005	0.03	0.1	0.02	0.1	0.4	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094660	Soil		5	0.01	79	0.003	<1	0.22	0.006	0.03	0.1	0.02	0.1	0.2	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094661	Soil		15	0.07	305	0.004	3	0.60	0.003	0.05	0.2	0.07	0.8	0.5	<0.05	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094662	Soil		3	<0.01	38	0.002	<1	0.19	0.006	0.02	<0.1	0.02	0.1	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094663	Soil		12	0.05	426	0.003	1	0.46	0.004	0.04	0.1	0.07	0.7	0.3	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094634	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094635	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094636	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094637	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094638	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094639	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094640	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094641	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094642	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094643	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094644	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094645	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094646	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094647	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094648	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094649	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094650	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094651	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094652	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094653	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094654	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094655	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094656	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094657	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094658	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094659	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094660	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094661	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094662	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094663	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094634	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094635	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094636	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094637	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094638	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094639	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094640	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094641	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094642	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094643	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094644	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094645	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094646	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094647	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094648	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094649	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094650	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094651	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094652	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094653	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094654	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094655	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094656	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094657	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094658	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094659	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094660	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094661	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094662	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094663	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094664	Soil	14.5	21.1	20.6	239	0.4	30.2	5.1	129	2.30	21.8	5.2	0.5	20	0.9	3.8	0.2	132	0.03	0.136	7
1094665	Soil	7.4	18.8	14.7	224	1.0	23.2	3.1	99	2.00	21.6	5.1	0.4	23	2.1	4.2	0.2	86	0.05	0.071	3
1094666	Soil	1.3	2.0	1.7	11	0.2	1.4	0.3	4	0.13	1.7	<0.5	<0.1	3	<0.1	0.4	<0.1	15	<0.01	0.020	5
1094667	Soil	7.9	18.4	11.0	45	0.4	5.4	0.8	16	1.37	21.6	<0.5	<0.1	18	0.4	4.3	0.1	92	0.02	0.055	3
1094668	Soil	10.5	14.0	11.6	117	<0.1	18.0	2.7	33	1.06	13.9	1.2	<0.1	10	0.2	2.8	0.2	89	0.01	0.039	10
1094669	Soil	10.9	16.5	13.2	184	0.2	25.7	5.7	158	1.80	16.0	1.6	0.3	22	1.0	2.7	0.2	80	0.16	0.125	6
1094670	Soil	17.2	42.1	20.6	363	0.5	56.7	10.4	290	2.88	29.9	2.5	0.5	27	1.3	6.2	0.2	99	0.16	0.159	10
1094671	Soil	19.8	49.2	15.8	682	1.0	91.9	9.8	193	2.51	35.2	2.6	1.5	57	8.2	6.6	0.2	181	0.65	0.210	14
1094672	Soil	3.8	22.9	17.7	92	0.9	20.7	5.0	79	1.58	7.6	1.4	0.3	9	0.5	1.4	0.2	23	0.06	0.111	5
1094673	Soil	3.6	12.4	11.9	66	<0.1	13.3	4.1	92	1.70	7.4	<0.5	<0.1	5	0.1	1.2	0.2	35	0.03	0.068	4
1094674	Soil	13.3	35.6	29.5	237	0.2	49.5	11.0	236	3.36	22.5	3.0	0.5	15	0.4	4.7	0.3	76	0.03	0.070	7
1094675	Soil	1.7	7.4	8.0	37	<0.1	8.0	2.6	46	0.76	3.7	<0.5	<0.1	3	<0.1	0.6	<0.1	12	0.01	0.036	3
1094676	Soil	0.7	2.3	1.3	11	<0.1	2.0	0.7	11	0.20	1.3	<0.5	<0.1	3	<0.1	0.2	<0.1	8	0.02	0.025	2
1094677	Soil	2.2	8.6	4.9	47	<0.1	10.5	4.2	62	1.09	5.4	<0.5	0.3	4	<0.1	0.8	0.2	28	0.01	0.019	6
1094678	Soil	2.1	42.0	7.5	110	0.7	14.1	3.0	83	1.27	7.3	4.0	0.1	9	0.3	1.3	<0.1	12	0.30	0.126	4
1094679	Soil	5.1	305.1	31.3	733	0.6	124.1	23.4	213	7.62	133.3	15.5	1.4	2	0.6	7.5	0.3	14	<0.01	0.130	4
1094680	Soil	2.0	37.0	6.5	96	0.7	17.7	3.6	34	0.97	8.3	<0.5	<0.1	3	<0.1	1.8	<0.1	16	0.01	0.043	2
1094681	Soil	1.3	26.2	4.1	58	<0.1	12.1	2.7	23	0.70	5.1	<0.5	<0.1	3	<0.1	1.0	<0.1	11	0.01	0.036	1
1094682	Soil	1.1	15.0	3.6	46	1.5	9.8	1.6	19	0.59	3.7	1.5	<0.1	8	0.1	0.6	<0.1	13	0.17	0.078	2
1094683	Soil	6.1	49.6	18.6	196	0.7	54.6	7.4	98	2.19	19.9	1.3	<0.1	7	0.2	3.2	0.2	44	0.04	0.102	7
1094684	Soil	2.5	24.0	7.8	75	0.5	17.4	3.5	32	0.89	6.4	<0.5	<0.1	8	0.5	0.9	0.1	22	0.07	0.104	4
1094685	Soil	11.8	37.8	73.9	56	1.7	13.0	1.6	25	1.62	8.8	4.5	0.2	54	0.8	2.8	0.4	64	0.05	0.249	11
1094686	Soil	1.5	17.9	5.1	48	0.2	20.9	4.7	69	1.23	5.7	0.7	<0.1	8	<0.1	1.1	0.1	18	0.01	0.048	4
1094687	Soil	3.9	63.7	18.2	100	0.9	57.1	8.5	91	2.93	11.4	1.0	0.5	38	0.1	2.1	0.2	25	0.10	0.139	8
1094688	Soil	0.3	6.2	1.1	10	0.6	4.2	0.6	12	0.22	0.5	<0.5	<0.1	14	<0.1	0.1	<0.1	3	0.19	0.033	1
1094689	Soil	8.8	12.4	6.0	180	0.2	18.9	2.6	29	0.72	7.6	<0.5	0.4	20	1.7	4.1	<0.1	57	0.37	0.051	2
1094690	Soil	28.7	48.5	20.1	1694	0.5	159.2	18.2	407	4.59	26.8	<0.5	1.8	59	14.8	16.4	0.2	264	1.11	0.099	9
1094691	Soil	27.5	33.0	16.3	646	0.4	77.7	10.2	149	2.31	24.9	1.3	1.9	16	5.9	18.1	0.1	150	0.19	0.050	4
1094692	Soil	6.2	76.3	24.7	113	1.9	44.1	2.7	39	1.49	11.1	4.4	0.2	108	0.7	3.8	0.2	78	0.10	0.183	5
1094693	Soil	12.6	117.4	35.0	172	2.5	53.7	4.0	58	2.48	21.2	5.3	1.8	212	1.6	7.5	0.3	163	0.19	0.311	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094664	Soil	17	0.07	430	0.003	2	0.80	0.003	0.06	0.2	0.42	1.0	0.5	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094665	Soil	17	0.04	488	0.003	1	0.52	0.004	0.04	<0.1	0.28	1.2	0.6	0.08	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094666	Soil	2	<0.01	34	0.003	1	0.11	0.004	0.02	<0.1	0.02	0.1	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094667	Soil	12	<0.01	210	0.003	1	0.18	0.002	0.04	0.1	0.07	0.4	0.3	0.07	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094668	Soil	7	0.01	107	0.004	2	0.27	0.002	0.03	0.1	0.02	0.2	0.3	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094669	Soil	14	0.10	538	0.004	2	0.72	0.007	0.06	0.1	0.07	0.8	0.3	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094670	Soil	17	0.09	409	0.004	2	0.54	0.002	0.05	0.1	0.15	1.0	0.4	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094671	Soil	25	0.11	1173	0.003	3	0.50	0.003	0.06	0.1	0.74	3.4	0.6	0.05	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094672	Soil	9	0.07	154	0.003	1	0.67	0.009	0.04	<0.1	0.22	0.9	0.2	0.06	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094673	Soil	12	0.03	36	0.004	<1	0.33	0.008	0.03	0.1	0.03	0.3	<0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094674	Soil	18	0.12	115	0.006	1	0.81	0.003	0.04	0.1	0.11	1.4	0.3	0.06	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094675	Soil	4	0.02	31	0.003	<1	0.23	0.009	0.02	<0.1	0.03	0.3	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094676	Soil	2	<0.01	16	0.003	<1	0.12	0.012	0.02	<0.1	0.02	0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094677	Soil	4	0.01	34	0.003	<1	0.29	0.006	0.02	<0.1	<0.01	0.5	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094678	Soil	4	0.03	166	0.006	1	0.30	0.023	0.02	<0.1	0.12	0.8	<0.1	<0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094679	Soil	7	0.04	90	0.001	2	0.36	<0.001	0.05	<0.1	0.07	6.9	0.1	<0.05	<1	8.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094680	Soil	3	0.01	29	0.003	<1	0.15	0.010	0.02	<0.1	0.03	0.4	<0.1	<0.05	1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094681	Soil	2	<0.01	34	0.003	1	0.12	0.010	0.02	<0.1	0.02	0.4	<0.1	<0.05	<1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094682	Soil	4	0.02	95	0.002	<1	0.30	0.020	0.03	<0.1	0.13	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094683	Soil	10	0.02	83	0.002	2	0.33	0.004	0.04	<0.1	0.03	0.3	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094684	Soil	10	0.04	137	0.002	<1	0.55	0.012	0.03	<0.1	0.11	0.3	0.1	0.06	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094685	Soil	19	0.01	397	0.003	2	0.22	0.010	0.10	<0.1	0.24	0.7	0.4	0.21	2	1.9	0.2	N.A.	N.A.	N.A.	N.A.
1094686	Soil	4	0.01	55	0.002	<1	0.16	0.009	0.03	<0.1	0.02	0.4	<0.1	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094687	Soil	9	0.03	295	0.003	2	0.22	0.007	0.05	<0.1	0.08	1.4	0.1	0.05	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094688	Soil	1	0.04	64	0.005	<1	0.17	0.027	0.02	<0.1	0.05	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094689	Soil	5	0.03	223	0.004	1	0.31	0.010	0.02	<0.1	0.06	0.8	<0.1	0.07	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094690	Soil	28	0.15	448	0.002	2	0.44	0.003	0.03	<0.1	0.35	6.7	0.2	0.07	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094691	Soil	10	0.02	233	<0.001	1	0.30	0.002	0.03	<0.1	0.21	3.3	0.2	<0.05	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094692	Soil	13	0.01	556	0.002	2	0.32	0.008	0.06	<0.1	0.42	0.8	0.3	0.11	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094693	Soil	16	0.02	903	0.004	2	0.40	0.003	0.11	0.2	0.48	2.4	0.4	0.27	1	4.4	0.4	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094664	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094665	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094666	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094667	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094668	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094669	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094670	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094671	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094672	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094673	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094674	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094675	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094676	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094677	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094678	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094679	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094680	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094681	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094682	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094683	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094684	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094685	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094686	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094687	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094688	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094689	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094690	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094691	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094692	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094693	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094664	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094665	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094666	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094667	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094668	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094669	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094670	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094671	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094672	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094673	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094674	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094675	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094676	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094677	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094678	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094679	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094680	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094681	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094682	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094683	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094684	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094685	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094686	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094687	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094688	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094689	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094690	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094691	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094692	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094693	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094694	Soil		0.3	1.8	1.3	4	0.2	1.2	0.3	6	0.11	<0.5	<0.5	<0.1	5	<0.1	<0.1	<0.1	7	0.02	0.025	<1
1094695	Soil		8.0	13.6	18.0	42	0.7	12.0	2.1	23	0.72	7.2	<0.5	<0.1	18	0.1	1.5	0.2	103	0.01	0.037	12
1094696	Soil		0.6	1.7	1.5	5	0.2	1.5	0.4	6	0.14	<0.5	<0.5	<0.1	3	<0.1	0.1	<0.1	8	0.01	0.019	1
1094697	Soil		4.2	29.1	14.3	78	1.7	28.3	4.2	50	1.52	7.2	3.1	0.2	48	0.2	1.4	0.2	38	0.31	0.096	6
1094698	Soil		8.4	102.0	23.8	317	1.3	102.5	14.6	159	4.44	13.1	2.8	2.9	91	0.9	3.7	0.3	57	0.28	0.193	12
1094699	Soil		8.2	51.3	15.3	294	1.1	70.7	10.2	173	2.44	12.3	1.8	2.1	96	1.4	4.3	0.2	53	0.64	0.178	6
1094700	Soil		14.4	78.3	23.6	386	1.5	100.8	13.2	262	3.65	18.3	2.4	2.8	81	2.6	6.6	0.2	82	0.59	0.161	9
1094701	Soil		12.6	67.4	12.6	219	0.2	44.4	8.3	219	2.41	25.4	2.2	<0.1	14	0.2	4.2	0.1	59	0.06	0.186	6
1094702	Soil		16.6	153.0	12.6	297	0.2	68.5	9.0	89	2.84	17.4	2.2	0.2	13	0.4	3.8	0.2	94	0.02	0.116	12
1094703	Soil		19.6	145.5	15.3	277	0.1	89.8	11.3	94	2.76	28.1	1.9	0.1	17	0.3	4.9	0.2	117	0.02	0.112	10
1094704	Soil		12.6	52.0	21.3	221	0.6	81.2	4.8	39	1.99	60.5	<0.5	<0.1	57	0.5	7.8	0.3	91	0.05	0.204	14
1094705	Soil		29.3	29.4	151.9	91	1.4	24.6	2.2	51	2.58	35.5	0.8	<0.1	73	1.1	5.3	0.6	114	0.05	0.316	16
1094706	Soil		126.1	43.1	52.5	505	<0.1	175.1	9.7	46	2.40	62.4	1.1	0.4	7	0.9	13.5	0.2	211	0.04	0.062	12
1094707	Soil		85.5	64.2	37.9	277	0.1	173.5	8.8	72	1.71	45.5	5.2	0.8	20	2.1	11.4	0.1	122	0.05	0.057	28
1094708	Soil		139.5	154.7	114.0	658	0.2	237.3	9.8	49	2.15	49.2	2.0	1.5	30	4.4	13.1	0.2	157	0.02	0.086	18
1094709	Soil		114.5	169.4	58.6	621	0.6	170.7	4.8	51	1.84	62.2	1.8	0.5	63	14.0	27.8	0.2	1123	0.16	0.125	29
1094710	Soil		50.4	26.1	35.3	134	1.6	30.5	2.7	76	2.52	72.7	4.6	0.3	177	1.6	13.4	0.3	480	0.10	0.218	25
1094711	Soil		13.1	28.4	57.2	71	1.2	15.4	2.4	36	1.55	18.3	4.5	0.4	115	0.4	3.3	0.3	77	0.05	0.184	20
1094712	Soil		114.6	59.6	16.7	298	<0.1	180.5	9.4	60	2.69	36.3	<0.5	0.4	3	0.7	3.9	0.2	74	0.01	0.060	8
1094713	Soil		81.8	56.5	19.8	677	0.3	130.7	4.4	36	1.86	55.9	<0.5	0.2	16	3.2	17.6	0.2	488	0.10	0.102	13
1094714	Soil		70.4	196.7	42.3	846	2.7	154.0	5.5	139	2.52	76.3	10.8	0.2	80	8.4	18.5	0.2	842	0.19	0.334	14
1094715	Soil		181.6	53.1	44.8	184	3.4	28.1	1.9	48	4.70	179.4	2.3	0.8	115	0.7	37.0	0.3	663	0.04	0.443	8
1094716	Soil		56.0	48.9	59.2	161	3.4	20.3	1.3	23	2.36	44.6	5.3	<0.1	58	0.6	15.9	0.3	261	0.03	0.330	6
1094717	Soil		32.3	14.5	24.5	69	0.6	10.2	1.9	30	1.08	12.4	0.7	<0.1	16	0.3	5.3	0.2	140	0.02	0.059	8
1094718	Soil		32.4	21.9	21.3	70	0.7	12.3	2.0	59	1.67	27.5	1.6	<0.1	40	0.4	8.2	0.2	171	0.04	0.150	7
1094719	Soil		54.7	53.0	41.6	37	3.9	11.1	0.4	12	0.78	11.7	2.0	0.3	27	0.7	20.7	0.2	197	0.02	0.096	9
1094720	Soil		102.9	78.8	42.5	183	6.1	34.5	1.7	31	2.82	49.6	9.9	1.2	73	1.3	31.1	0.3	373	0.09	0.416	8
1094721	Soil		47.6	38.7	79.0	69	2.9	20.4	0.4	7	1.11	21.1	<0.5	0.4	28	1.9	24.2	0.2	344	0.02	0.102	6
1094722	Soil		51.4	42.6	72.4	90	2.9	19.9	0.6	7	0.74	11.9	23.3	0.2	83	0.5	17.3	0.3	387	0.02	0.118	8
1094723	Soil		3.9	26.2	14.9	107	0.1	25.3	8.4	134	2.78	16.6	1.2	1.5	13	0.4	1.9	0.2	37	0.03	0.035	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094694	Soil	1	<0.01	37	0.002	<1	0.08	0.016	0.02	<0.1	0.04	<0.1	<0.1	0.06	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094695	Soil	9	0.01	144	0.004	2	0.25	0.004	0.04	<0.1	0.03	0.2	0.1	0.08	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094696	Soil	2	<0.01	31	0.003	1	0.10	0.015	0.02	<0.1	0.02	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094697	Soil	8	0.06	1866	0.002	3	0.58	0.012	0.06	<0.1	0.25	0.8	0.1	0.08	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094698	Soil	18	0.04	4501	0.002	3	0.64	0.002	0.09	<0.1	0.27	4.2	0.1	<0.05	1	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094699	Soil	15	0.07	1955	0.002	4	0.38	0.003	0.07	<0.1	0.30	3.6	0.1	0.09	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094700	Soil	15	0.07	1561	0.002	4	0.42	0.003	0.07	<0.1	0.44	5.5	0.2	0.06	<1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094701	Soil	9	0.03	220	0.002	2	0.54	0.008	0.08	<0.1	0.06	0.3	0.2	0.11	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094702	Soil	15	0.02	98	0.003	<1	0.55	0.006	0.05	<0.1	0.03	0.4	0.2	<0.05	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094703	Soil	18	0.03	109	0.002	1	0.57	0.006	0.06	0.1	0.03	0.2	0.4	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094704	Soil	13	0.02	251	0.001	2	0.39	0.006	0.09	0.2	0.06	0.1	0.3	0.09	2	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094705	Soil	20	0.02	460	0.002	2	0.54	0.006	0.12	0.2	0.18	0.1	1.0	0.28	3	3.0	0.5	N.A.	N.A.	N.A.	N.A.
1094706	Soil	12	0.04	181	0.002	<1	0.52	0.004	0.05	0.3	0.14	0.9	0.8	<0.05	2	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094707	Soil	12	0.03	92	0.002	<1	0.35	0.003	0.03	0.6	0.76	1.6	1.0	<0.05	1	6.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094708	Soil	18	0.02	149	0.002	1	0.63	0.001	0.05	0.3	1.37	2.5	1.7	<0.05	<1	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094709	Soil	58	0.09	340	0.004	6	0.78	0.004	0.12	0.4	0.42	1.0	2.9	<0.05	2	11.5	0.2	N.A.	N.A.	N.A.	N.A.
1094710	Soil	38	0.06	1192	0.004	2	0.79	0.003	0.10	0.3	2.44	0.4	2.2	0.15	4	5.6	0.2	N.A.	N.A.	N.A.	N.A.
1094711	Soil	18	0.03	2134	0.002	2	0.69	0.003	0.08	<0.1	0.40	0.4	0.5	0.11	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094712	Soil	13	0.03	119	0.002	<1	0.34	0.003	0.05	0.4	0.04	0.8	1.3	<0.05	1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094713	Soil	24	0.05	457	0.002	2	0.57	0.004	0.08	0.4	0.09	0.5	3.1	<0.05	2	7.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094714	Soil	55	0.08	506	0.003	4	1.52	0.007	0.10	0.3	1.87	0.3	4.0	0.06	3	12.9	0.2	N.A.	N.A.	N.A.	N.A.
1094715	Soil	40	0.05	491	0.005	2	0.54	0.006	0.24	0.6	1.42	1.4	6.6	0.45	3	29.3	0.5	N.A.	N.A.	N.A.	N.A.
1094716	Soil	37	0.03	944	0.003	3	0.62	0.004	0.14	0.3	0.69	0.2	2.0	0.23	3	17.1	0.4	N.A.	N.A.	N.A.	N.A.
1094717	Soil	12	0.02	212	0.003	1	0.32	0.010	0.07	0.2	0.09	0.1	1.2	0.06	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094718	Soil	19	0.06	262	0.003	<1	0.69	0.009	0.06	0.3	0.53	0.2	1.7	0.09	4	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094719	Soil	23	0.03	1058	0.003	3	0.49	0.007	0.10	0.6	1.79	0.6	4.3	0.16	2	10.3	0.3	N.A.	N.A.	N.A.	N.A.
1094720	Soil	42	0.05	1074	0.007	2	0.79	0.003	0.13	0.9	2.40	2.1	4.7	0.26	5	18.5	0.2	N.A.	N.A.	N.A.	N.A.
1094721	Soil	22	0.02	598	0.004	3	0.31	0.002	0.14	0.4	4.75	1.0	2.0	0.25	1	13.2	0.2	N.A.	N.A.	N.A.	N.A.
1094722	Soil	40	0.03	597	0.001	3	0.52	0.002	0.09	0.5	11.38	0.3	3.8	0.10	4	8.5	0.3	N.A.	N.A.	N.A.	N.A.
1094723	Soil	11	0.10	124	0.006	<1	0.46	0.002	0.04	<0.1	0.09	2.5	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094694	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094695	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094696	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094697	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094698	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094699	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094700	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094701	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094702	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094703	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094704	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094705	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094706	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094707	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094708	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094709	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094710	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094711	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094712	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094713	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094714	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094715	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094716	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094717	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094718	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094719	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094720	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094721	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094722	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094723	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094694	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094695	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094696	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094697	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094698	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094699	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094700	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094701	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094702	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094703	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094704	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094705	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094706	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094707	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094708	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094709	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094710	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094711	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094712	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094713	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094714	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094715	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094716	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094717	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094718	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094719	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094720	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094721	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094722	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094723	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094724	Soil		4.8	12.2	14.9	56	0.2	12.4	3.6	42	1.23	9.3	<0.5	<0.1	7	<0.1	1.3	0.1	36	0.02	0.045	3
1094725	Soil		4.2	17.4	11.7	45	0.4	9.7	2.6	55	1.44	9.4	2.1	<0.1	11	0.1	1.9	0.2	51	0.03	0.052	7
1094726	Soil		6.8	14.7	11.5	39	0.3	6.8	1.8	40	2.10	15.5	1.5	0.2	11	<0.1	3.4	0.2	102	0.02	0.047	9
1094727	Soil		4.0	20.4	11.6	55	0.4	11.7	3.8	162	2.07	12.6	1.5	0.4	12	0.1	2.2	0.2	64	0.04	0.063	8
1094728	Soil		3.8	27.9	10.3	85	0.4	18.8	4.0	90	2.53	13.1	2.8	1.5	15	0.4	2.4	0.2	75	0.08	0.062	12
1094729	Soil		5.1	49.0	13.7	102	1.0	21.6	5.1	116	2.74	16.3	3.4	2.2	21	0.3	3.4	0.2	95	0.07	0.083	14
1094730	Soil		6.8	61.6	19.4	86	1.3	19.4	4.2	117	2.50	17.9	7.9	0.8	26	0.3	4.2	0.3	119	0.05	0.080	11
1274001	Soil		3.1	19.2	6.6	117	0.5	21.8	4.7	214	0.99	4.6	3.7	0.3	30	0.9	1.3	0.1	22	0.37	0.086	3
1274002	Soil		11.8	26.9	17.3	147	0.2	35.0	7.4	97	2.46	12.4	<0.5	0.5	5	0.2	3.8	0.2	64	0.02	0.044	6
1274003	Soil		5.0	22.3	9.2	118	0.6	29.7	5.2	120	1.34	7.1	2.0	0.6	26	0.3	2.3	0.1	31	0.23	0.050	3
1274004	Soil		9.8	21.7	10.6	135	0.9	31.5	4.0	69	1.34	7.5	4.2	0.4	13	0.3	2.2	0.1	60	0.15	0.077	3
1274005	Soil		76.4	23.3	9.5	233	<0.1	88.1	7.2	61	2.28	17.1	<0.5	0.1	4	0.1	2.8	0.1	95	0.03	0.047	6
1274006	Soil		17.7	31.8	13.5	313	1.0	60.9	7.7	319	2.21	13.8	2.1	0.5	19	1.4	3.7	0.2	81	0.16	0.128	6
1274007	Soil		38.5	38.9	14.4	291	0.5	87.4	7.8	93	2.11	16.6	0.6	0.2	28	0.8	6.1	0.2	97	0.24	0.052	8
1274008	Soil		7.4	44.2	19.1	180	0.9	47.3	13.8	371	2.93	16.2	4.2	1.1	13	0.8	3.2	0.2	39	0.08	0.076	6
1274009	Soil		0.7	6.6	2.1	6	0.2	2.2	0.3	6	0.17	0.6	<0.5	<0.1	4	<0.1	0.1	<0.1	5	0.02	0.027	1
1274010	Soil		5.7	26.6	16.0	113	<0.1	28.5	8.8	140	3.51	15.9	2.7	0.4	6	0.1	2.7	0.3	50	<0.01	0.052	5
1274011	Soil		10.7	60.1	49.6	197	2.7	68.4	6.5	127	2.96	54.8	8.3	0.5	65	1.1	4.8	0.3	68	0.29	0.230	5
1274012	Soil		5.6	11.3	11.1	57	0.4	11.2	2.2	35	0.92	11.4	<0.5	0.1	7	<0.1	2.0	0.1	56	0.03	0.030	8
1274013	Soil		0.6	6.3	2.7	8	0.5	4.0	0.6	7	0.18	<0.5	1.4	<0.1	9	0.2	0.2	<0.1	9	0.07	0.030	<1
1274014	Soil		9.3	29.2	19.7	157	0.5	46.1	8.3	131	2.33	16.3	3.5	1.0	26	0.6	2.9	0.2	59	0.27	0.074	7
1274015	Soil		9.2	25.8	26.0	125	0.9	34.2	5.0	126	1.56	14.4	1.8	0.3	26	0.5	3.0	0.2	63	0.23	0.076	5
1274016	Soil		9.3	12.9	10.3	82	0.2	16.7	2.7	38	1.02	15.3	<0.5	<0.1	9	<0.1	3.0	0.1	69	0.01	0.036	9
1274017	Soil		34.4	104.9	51.7	891	2.2	141.4	8.7	172	2.63	38.4	6.7	1.4	106	13.9	13.6	0.2	304	0.60	0.283	11
1274018	Soil		45.2	65.9	20.5	928	0.8	169.9	6.7	158	1.65	30.5	3.3	1.7	104	8.0	11.1	0.1	166	3.62	0.107	9
1274019	Soil		49.0	17.0	5.5	157	0.1	52.2	2.6	21	0.85	11.5	<0.5	0.2	13	0.7	2.8	0.2	60	0.20	0.033	5
1274020	Soil		40.3	26.7	15.4	173	<0.1	67.0	5.8	80	1.82	19.2	1.1	0.2	9	0.4	3.4	0.1	71	0.04	0.039	9
1274021	Soil		27.0	36.5	12.9	753	0.2	131.2	5.9	122	1.68	16.3	2.9	1.7	44	3.3	4.8	0.1	89	0.58	0.108	8
1274022	Soil		16.0	35.0	16.3	584	0.5	91.1	8.2	166	2.13	13.8	3.5	1.5	63	4.0	4.7	0.1	77	1.29	0.132	7
1274023	Soil		12.6	51.9	23.2	324	1.0	84.4	13.4	198	3.40	23.2	5.7	1.8	52	1.9	6.6	0.2	106	0.52	0.138	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094724	Soil	5	0.02	204	0.002	<1	0.51	0.013	0.04	<0.1	0.07	0.4	0.3	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094725	Soil	10	0.03	168	0.007	<1	0.83	0.010	0.04	<0.1	0.14	0.4	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094726	Soil	12	0.03	206	0.012	<1	0.50	0.002	0.03	0.1	0.07	0.5	0.2	<0.05	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094727	Soil	15	0.09	173	0.023	<1	0.73	0.007	0.04	0.2	0.07	0.7	0.2	<0.05	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094728	Soil	21	0.22	193	0.027	<1	1.00	0.005	0.05	0.2	0.09	1.6	0.3	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094729	Soil	25	0.23	282	0.030	<1	1.18	0.004	0.07	0.2	0.18	2.6	0.5	<0.05	5	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094730	Soil	25	0.21	468	0.016	3	1.16	0.005	0.06	0.2	0.19	1.6	0.7	<0.05	5	3.2	0.2	N.A.	N.A.	N.A.	N.A.
1274001	Soil	6	0.06	593	0.004	1	0.38	0.016	0.03	<0.1	0.10	1.0	0.1	0.06	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274002	Soil	7	0.03	113	0.002	2	0.53	0.003	0.04	0.1	0.03	1.0	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274003	Soil	6	0.04	820	0.004	2	0.41	0.013	0.03	<0.1	0.10	1.2	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274004	Soil	12	0.08	356	0.002	2	0.73	0.012	0.05	<0.1	0.25	1.4	0.3	0.06	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274005	Soil	7	0.02	63	0.002	2	0.25	0.002	0.03	0.2	0.02	0.3	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274006	Soil	16	0.12	471	0.003	3	0.95	0.008	0.05	0.1	0.22	1.8	0.4	0.06	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274007	Soil	12	0.07	286	0.002	2	0.42	0.005	0.04	0.1	0.09	0.8	0.5	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274008	Soil	14	0.11	195	0.003	2	0.64	0.003	0.05	<0.1	0.09	2.6	0.2	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274009	Soil	1	<0.01	31	0.003	<1	0.17	0.018	0.02	<0.1	0.02	<0.1	<0.1	<0.05	<1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274010	Soil	11	0.04	76	0.004	<1	0.56	0.003	0.04	0.1	<0.01	1.7	0.1	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274011	Soil	17	0.10	1613	0.003	2	1.12	0.012	0.10	0.2	0.35	1.7	0.4	0.12	3	4.3	0.2	N.A.	N.A.	N.A.	N.A.
1274012	Soil	6	0.02	110	0.004	<1	0.27	0.006	0.03	<0.1	0.02	0.5	<0.1	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274013	Soil	2	0.01	174	0.003	<1	0.13	0.014	0.02	<0.1	0.03	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274014	Soil	13	0.10	837	0.002	<1	0.70	0.005	0.05	0.2	0.21	3.2	0.2	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274015	Soil	13	0.07	695	0.004	2	0.65	0.010	0.05	0.1	0.11	1.2	0.2	0.05	2	2.2	0.3	N.A.	N.A.	N.A.	N.A.
1274016	Soil	7	0.01	111	0.004	1	0.24	0.005	0.03	0.1	0.03	0.3	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274017	Soil	36	0.04	582	0.002	2	0.60	0.002	0.08	0.1	0.90	3.5	1.0	<0.05	2	4.3	0.2	N.A.	N.A.	N.A.	N.A.
1274018	Soil	15	1.29	264	0.002	3	0.32	0.005	0.05	0.2	0.55	2.8	0.8	0.08	<1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274019	Soil	5	0.04	181	0.002	2	0.29	0.007	0.03	0.1	0.04	0.7	0.4	<0.05	1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274020	Soil	10	0.04	159	0.004	2	0.48	0.003	0.04	0.2	0.02	0.4	0.4	<0.05	3	2.0	0.3	N.A.	N.A.	N.A.	N.A.
1274021	Soil	15	0.07	409	0.003	2	0.52	0.004	0.04	<0.1	0.25	2.4	0.5	<0.05	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274022	Soil	19	0.17	469	0.004	3	0.56	0.007	0.05	0.1	0.23	2.8	0.3	0.06	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274023	Soil	30	0.11	940	0.003	3	0.65	0.004	0.08	0.1	0.32	4.1	0.3	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094724	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094725	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094726	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094727	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094728	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094729	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094730	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274001	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274002	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274003	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274004	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274005	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274006	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274007	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274008	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274009	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274010	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274011	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274012	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274013	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274014	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274015	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274016	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274017	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274018	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274019	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274020	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274021	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274022	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274023	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094724	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094725	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094726	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094727	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094728	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094729	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094730	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274017	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274019	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274021	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274022	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274023	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274024	Soil	12.9	38.7	23.0	227	0.6	60.6	8.8	115	3.08	25.7	1.9	2.5	27	0.7	6.4	0.2	109	0.06	0.114	11
1274025	Soil	4.0	9.7	7.0	47	0.1	14.2	2.4	30	0.75	6.1	1.4	<0.1	6	0.2	1.5	<0.1	35	0.02	0.035	4
1274026	Soil	7.1	55.6	20.1	260	1.0	73.1	9.5	182	3.00	16.8	4.8	1.0	73	1.2	6.0	0.2	63	0.61	0.155	7
1274027	Soil	7.2	39.6	13.9	182	1.6	61.0	7.2	123	1.99	13.8	5.9	0.1	47	1.5	4.1	0.1	87	0.15	0.112	4
1274028	Soil	10.5	37.7	17.2	164	0.3	55.0	10.5	197	3.06	16.7	1.6	0.2	16	0.7	4.3	0.2	78	0.04	0.102	7
1274029	Soil	8.4	19.2	10.5	74	0.1	26.2	4.2	51	1.53	13.5	<0.5	<0.1	6	0.2	2.7	0.2	50	0.01	0.049	6
1274030	Soil	1.6	19.7	14.2	35	0.1	30.7	8.1	144	3.72	6.2	0.8	0.1	7	<0.1	1.7	0.1	22	0.02	0.073	5
1274051	Soil	4.3	7.4	5.6	30	0.2	7.4	1.6	22	0.51	3.2	<0.5	<0.1	5	<0.1	1.1	<0.1	40	0.02	0.018	5
1274052	Soil	5.2	26.0	20.6	123	0.7	34.1	3.9	72	1.40	11.3	2.7	<0.1	67	1.6	2.2	0.2	68	0.35	0.219	5
1274053	Soil	6.7	46.7	26.7	179	0.8	69.0	14.5	561	3.87	12.6	0.7	0.7	32	1.6	3.6	0.1	75	0.77	0.192	9
1274054	Soil	6.8	76.0	27.7	104	0.3	141.5	32.7	387	7.21	15.8	<0.5	1.3	85	0.4	3.0	0.1	107	0.99	0.203	6
1274055	Soil	2.0	71.3	20.5	56	0.2	125.7	41.2	641	7.78	7.0	<0.5	1.0	123	0.2	1.6	<0.1	102	1.08	0.253	6
1274056	Soil	2.7	55.1	23.3	46	0.1	152.3	29.2	443	4.75	13.3	2.1	0.4	50	0.2	2.0	0.1	58	1.10	0.156	6
1274057	Soil	2.7	19.9	19.7	82	0.2	25.9	10.7	471	3.08	7.8	1.5	0.8	19	0.2	1.8	0.2	66	0.44	0.128	5
1274058	Soil	5.5	11.2	14.6	55	<0.1	17.7	3.3	94	1.07	5.8	1.4	<0.1	8	<0.1	2.3	0.1	29	0.05	0.052	3
1274059	Soil	9.6	12.5	12.4	67	<0.1	21.9	3.4	102	1.16	7.2	4.5	0.1	14	0.3	1.8	0.1	32	0.16	0.061	5
1274060	Soil	4.5	10.3	5.4	34	<0.1	16.0	2.1	63	0.67	2.9	1.1	0.1	19	0.4	0.8	<0.1	18	0.31	0.060	3
1274061	Soil	10.7	40.3	25.3	228	0.3	68.8	9.1	77	2.39	35.1	1.1	0.1	10	0.2	3.9	0.3	43	0.04	0.103	6
1274062	Soil	1.8	4.4	4.4	19	0.4	4.6	1.0	17	0.35	2.6	0.6	<0.1	4	<0.1	0.6	<0.1	10	0.02	0.032	2
1274063	Soil	10.8	45.7	17.5	225	0.3	43.7	10.0	210	2.92	15.5	2.5	0.6	10	0.9	3.4	0.3	47	0.09	0.139	7
1274064	Soil	6.8	61.0	30.5	211	0.2	32.0	6.8	114	2.17	10.3	2.9	0.2	8	0.4	3.3	0.2	32	0.06	0.097	6
1274065	Soil	3.3	47.2	9.4	109	0.2	34.9	7.4	67	1.83	8.2	1.1	<0.1	9	0.5	2.1	0.2	30	0.20	0.060	6
1274066	Soil	0.9	19.1	3.9	18	0.2	5.9	1.3	16	0.46	1.5	1.2	0.1	7	0.4	0.4	<0.1	11	0.14	0.049	3
1274067	Soil	6.2	36.8	19.5	100	0.1	28.5	10.4	133	2.81	12.7	1.5	<0.1	9	0.2	2.4	0.3	51	0.03	0.140	8
1274068	Soil	10.7	33.4	45.1	151	0.4	21.8	6.0	178	2.93	15.3	1.6	<0.1	12	0.4	3.1	0.3	53	0.02	0.154	7
1274069	Soil	3.4	19.1	13.1	48	<0.1	10.7	5.0	123	2.77	8.0	1.5	0.3	7	<0.1	1.3	0.3	40	0.02	0.086	7
1274070	Soil	4.6	23.7	19.3	71	<0.1	15.9	5.5	102	2.26	14.0	1.7	0.4	9	0.1	2.9	0.3	48	0.03	0.085	9
1274071	Soil	8.4	55.3	31.5	139	0.3	37.1	12.3	329	3.81	27.0	3.8	0.6	13	0.3	6.5	0.3	42	0.12	0.228	9
1274072	Soil	5.4	35.5	24.2	117	0.1	27.9	9.4	203	2.81	24.2	2.1	0.2	9	0.3	4.5	0.2	33	0.05	0.135	6
1274073	Soil	0.4	3.2	8.0	9	<0.1	2.1	1.5	26	0.43	5.0	<0.5	<0.1	4	<0.1	0.2	<0.1	4	0.02	0.034	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1274024	Soil	19	0.07	608	0.005	2	0.71	0.004	0.05	0.1	0.05	2.3	0.3	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274025	Soil	6	0.02	125	0.003	<1	0.27	0.013	0.03	<0.1	0.04	0.2	0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274026	Soil	20	0.10	483	0.003	3	0.47	0.005	0.05	<0.1	0.24	3.7	0.1	<0.05	1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274027	Soil	25	0.05	859	0.002	1	0.59	0.015	0.07	0.2	0.32	1.1	0.2	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274028	Soil	15	0.03	228	0.002	2	0.44	0.002	0.05	<0.1	0.02	0.6	0.1	<0.05	2	1.2	0.2	N.A.	N.A.	N.A.	N.A.
1274029	Soil	7	0.02	135	0.003	2	0.33	0.004	0.04	<0.1	0.02	0.4	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274030	Soil	7	0.03	102	0.002	<1	0.37	0.007	0.02	<0.1	0.04	0.6	<0.1	<0.05	2	1.2	0.2	N.A.	N.A.	N.A.	N.A.
1274051	Soil	4	<0.01	49	0.004	<1	0.13	0.012	0.02	0.1	0.01	0.1	<0.1	<0.05	1	<0.5	0.2	N.A.	N.A.	N.A.	N.A.
1274052	Soil	13	0.08	457	0.001	2	0.69	0.011	0.06	<0.1	0.22	0.1	0.3	0.09	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274053	Soil	47	0.08	402	0.002	1	0.84	0.013	0.05	<0.1	0.18	4.4	0.2	0.06	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274054	Soil	62	0.07	393	0.002	2	0.70	0.007	0.04	<0.1	0.10	7.7	0.1	0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274055	Soil	78	0.05	265	0.003	<1	0.62	0.013	0.02	<0.1	0.08	10.6	<0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274056	Soil	44	0.05	204	0.003	1	0.60	0.014	0.01	<0.1	0.09	4.0	0.1	0.18	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274057	Soil	38	0.08	216	0.003	<1	0.88	0.010	0.02	0.1	0.03	2.9	0.1	0.12	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274058	Soil	7	0.02	46	0.002	1	0.29	0.009	0.02	<0.1	0.02	0.2	0.1	0.07	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274059	Soil	8	0.04	126	0.004	1	0.40	0.009	0.03	0.1	0.03	0.3	0.2	0.06	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274060	Soil	5	0.03	148	0.005	<1	0.56	0.018	0.02	<0.1	0.04	0.4	0.1	0.09	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274061	Soil	9	0.02	85	0.001	1	0.35	0.004	0.03	<0.1	0.03	0.3	0.1	0.06	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274062	Soil	2	<0.01	19	0.002	<1	0.14	0.013	0.02	<0.1	0.02	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274063	Soil	12	0.05	133	0.001	2	0.55	0.004	0.05	<0.1	0.03	1.4	0.4	0.12	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274064	Soil	9	0.03	87	0.001	2	0.36	0.004	0.06	<0.1	0.03	0.4	0.2	0.09	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274065	Soil	8	0.04	76	0.002	1	0.34	0.010	0.03	<0.1	0.01	0.4	0.1	0.13	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274066	Soil	3	0.02	72	0.003	<1	0.22	0.017	0.03	<0.1	0.03	0.2	<0.1	0.10	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274067	Soil	12	0.03	96	<0.001	1	0.57	0.005	0.04	<0.1	0.03	0.2	0.2	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274068	Soil	13	0.05	115	0.001	1	0.59	0.005	0.05	<0.1	0.04	0.1	0.9	0.08	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274069	Soil	12	0.03	48	0.003	<1	0.59	0.004	0.03	<0.1	0.02	0.3	0.1	<0.05	5	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274070	Soil	12	0.05	66	0.004	<1	0.58	0.003	0.04	0.1	0.02	0.2	0.2	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274071	Soil	14	0.09	99	0.003	1	0.56	0.003	0.05	0.1	0.05	0.7	0.2	0.07	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274072	Soil	11	0.06	104	0.001	<1	0.49	0.007	0.05	<0.1	0.03	0.4	0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274073	Soil	2	0.01	23	0.003	<1	0.14	0.017	0.02	<0.1	0.02	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1274024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274025	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274026	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274027	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274028	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274029	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274030	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274051	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274052	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274053	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274054	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274055	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274056	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274058	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274062	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274063	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274071	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274025	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274026	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274027	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274028	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274029	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274030	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274051	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274052	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274053	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274054	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274055	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274056	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274058	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274062	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274063	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274071	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274074	Soil	5.6	24.6	17.2	63	<0.1	14.7	5.7	83	2.30	8.6	0.6	0.1	5	0.1	1.7	0.2	52	0.02	0.067	7
1274075	Soil	3.0	10.9	9.2	43	<0.1	10.5	3.4	53	0.95	6.2	<0.5	<0.1	4	<0.1	1.0	0.1	35	0.02	0.047	5
1276076	Soil	11.2	68.8	21.6	294	0.6	86.5	13.6	178	3.16	20.7	3.0	2.7	102	1.1	6.3	0.2	72	0.31	0.159	8
1276077	Soil	14.5	59.5	17.7	340	1.0	84.2	12.7	208	3.08	24.0	3.0	1.5	87	1.4	6.3	0.2	85	0.43	0.145	7
1276078	Soil	15.7	33.7	14.2	243	0.5	60.8	10.0	233	2.59	21.3	3.8	0.9	42	1.2	4.9	0.2	114	0.20	0.128	9
1276079	Soil	12.9	30.3	14.8	123	0.4	38.6	7.6	154	2.43	14.6	1.4	0.5	25	0.4	3.3	0.3	74	0.54	0.089	12
1276080	Soil	40.6	57.3	14.3	264	0.6	134.9	13.0	390	3.33	22.6	2.5	1.6	52	1.9	5.7	0.1	100	0.76	0.116	8
1276001	Soil	19.3	36.4	21.9	200	<0.1	50.1	10.4	139	2.79	33.5	1.8	0.2	9	0.3	5.7	0.3	157	0.02	0.072	11
1276002	Soil	2.0	9.6	16.0	39	<0.1	8.6	5.3	123	1.26	4.0	0.5	0.2	4	<0.1	0.6	0.2	13	0.01	0.043	6
1276003	Soil	25.9	27.4	23.8	234	0.1	55.2	7.3	112	2.84	50.2	0.6	0.2	17	0.3	6.9	0.3	221	0.02	0.065	10
1276004	Soil	8.7	9.0	10.3	54	<0.1	11.9	3.0	48	1.22	13.0	<0.5	<0.1	6	<0.1	1.8	0.2	74	0.01	0.042	9
1276005	Soil	1.9	2.7	3.0	13	<0.1	2.9	0.6	8	0.24	3.9	<0.5	<0.1	4	<0.1	0.4	<0.1	20	0.01	0.021	3
1276006	Soil	6.3	11.9	9.6	56	0.3	14.2	3.3	57	1.22	15.8	0.6	0.1	7	0.1	1.5	0.1	53	0.03	0.078	6
1276007	Soil	17.0	23.3	23.8	117	<0.1	33.8	6.4	124	3.40	15.5	0.6	0.5	7	0.2	3.0	0.3	104	0.01	0.077	9
1276008	Soil	14.9	20.1	10.2	88	<0.1	26.4	4.3	48	1.22	11.0	0.7	<0.1	6	0.1	2.5	0.1	98	0.02	0.072	7
1276009	Soil	17.2	37.2	17.7	149	<0.1	39.4	6.0	68	1.71	20.4	1.3	0.1	10	0.2	5.0	0.2	128	<0.01	0.045	12
1276010	Soil	0.6	6.8	2.4	17	<0.1	3.5	1.0	140	0.35	1.5	<0.5	<0.1	11	0.4	0.3	<0.1	8	0.37	0.051	3
1276011	Soil	8.3	53.2	10.2	118	1.4	30.2	8.9	574	1.21	11.3	7.4	0.2	18	1.8	2.6	0.1	167	0.21	0.138	10
1276012	Soil	1.7	2.6	3.8	8	0.5	2.2	0.4	11	0.20	1.9	<0.5	<0.1	5	<0.1	0.3	<0.1	27	0.02	0.063	6
1276013	Soil	17.1	27.5	9.9	97	0.2	35.0	4.1	33	1.09	17.1	<0.5	<0.1	8	0.2	3.6	0.1	109	0.01	0.047	15
1276014	Soil	33.2	46.0	20.5	264	0.6	73.2	5.9	82	2.01	31.1	2.4	0.2	31	0.8	8.4	0.2	191	0.05	0.103	19
1276015	Soil	26.3	56.9	20.6	318	0.9	94.4	12.0	178	3.62	34.0	3.1	5.8	72	2.0	6.6	0.3	90	0.59	0.304	32
1276016	Soil	33.0	13.8	6.9	116	0.3	36.4	2.0	18	0.72	13.8	<0.5	0.1	5	0.1	5.4	<0.1	152	0.02	0.057	11
1276017	Soil	79.4	26.5	14.0	414	0.3	81.5	2.4	17	1.15	41.2	1.3	0.2	7	0.3	21.7	0.2	822	0.01	0.044	15
1276018	Soil	46.8	173.3	13.5	1244	3.0	340.2	9.6	254	2.99	59.8	2.6	3.0	227	17.0	16.6	0.2	622	7.11	0.500	26
1276019	Soil	96.1	79.6	18.4	1573	1.2	270.7	9.3	193	2.37	58.0	<0.5	0.8	69	12.6	23.6	0.2	515	1.07	0.160	21
1276020	Soil	10.9	12.8	9.1	88	1.3	23.9	1.4	21	0.74	8.7	3.4	<0.1	15	1.1	3.4	0.3	74	0.08	0.099	3
1276021	Soil	27.3	16.7	13.2	127	0.2	32.5	2.8	32	1.29	15.1	2.6	0.2	16	0.2	4.6	0.2	118	0.01	0.067	13
1276022	Soil	19.6	14.9	15.6	99	0.3	23.6	3.0	44	1.38	18.3	2.1	<0.1	18	0.2	3.8	0.3	102	0.01	0.074	9
1276023	Soil	11.5	9.5	9.9	71	0.3	12.9	1.9	26	0.86	11.2	2.8	<0.1	13	0.1	2.8	0.2	79	0.01	0.035	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1274074	Soil	11	0.03	47	0.003	<1	0.63	0.005	0.03	<0.1	0.03	0.2	0.1	<0.05	4	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274075	Soil	6	0.02	44	0.002	<1	0.25	0.012	0.02	<0.1	<0.01	0.1	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276076	Soil	17	0.06	2090	0.003	3	0.48	0.002	0.06	<0.1	0.16	4.0	0.2	0.07	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276077	Soil	17	0.10	2108	0.004	3	0.58	0.005	0.07	0.1	0.31	3.3	0.3	0.12	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276078	Soil	25	0.10	1341	0.003	2	0.66	0.004	0.06	0.1	0.13	2.3	0.4	0.11	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276079	Soil	12	0.07	317	0.003	1	0.49	0.008	0.04	<0.1	0.07	1.3	0.3	0.14	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276080	Soil	33	0.12	471	0.004	2	0.51	0.008	0.05	<0.1	0.36	4.9	0.5	0.12	1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276001	Soil	14	0.03	89	0.002	1	0.47	0.003	0.04	<0.1	0.02	0.4	0.4	0.06	5	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276002	Soil	4	0.01	39	0.002	<1	0.29	0.009	0.03	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276003	Soil	24	0.04	184	0.003	1	0.60	0.003	0.06	0.1	0.03	0.5	0.6	<0.05	5	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276004	Soil	9	0.02	65	0.003	<1	0.38	0.007	0.03	<0.1	0.03	0.1	0.2	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276005	Soil	3	0.01	32	0.004	<1	0.18	0.013	0.02	<0.1	0.03	<0.1	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276006	Soil	12	0.07	76	0.003	<1	0.65	0.012	0.03	<0.1	0.04	0.2	0.2	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276007	Soil	18	0.06	68	0.003	<1	0.73	0.004	0.04	0.1	0.03	0.8	0.3	<0.05	5	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276008	Soil	9	0.03	84	0.001	<1	0.44	0.005	0.03	<0.1	0.02	0.1	0.3	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276009	Soil	10	0.02	90	0.003	<1	0.36	0.003	0.04	0.1	0.02	0.3	0.3	<0.05	4	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276010	Soil	2	0.02	170	0.009	<1	0.53	0.030	0.02	<0.1	0.03	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276011	Soil	18	0.06	1223	0.002	2	1.02	0.013	0.05	0.1	0.65	0.9	0.5	0.11	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276012	Soil	5	0.01	42	0.002	1	0.22	0.013	0.03	<0.1	0.04	0.3	0.3	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276013	Soil	10	0.02	64	0.004	2	0.33	0.003	0.04	0.1	0.02	0.4	0.3	0.08	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276014	Soil	18	0.05	206	0.007	2	0.46	0.003	0.07	0.2	0.12	0.6	0.7	0.08	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276015	Soil	12	0.04	599	0.004	6	0.49	0.002	0.15	<0.1	0.34	3.5	0.6	0.06	1	3.0	0.3	N.A.	N.A.	N.A.	N.A.
1276016	Soil	10	0.02	78	0.003	2	0.25	0.008	0.04	0.2	0.03	0.2	0.9	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276017	Soil	39	0.05	136	0.008	2	0.60	0.006	0.08	0.3	0.14	0.4	2.2	<0.05	4	5.2	0.4	N.A.	N.A.	N.A.	N.A.
1276018	Soil	146	3.83	1144	0.006	8	0.84	0.010	0.11	0.4	1.45	5.8	1.1	0.08	2	8.3	0.2	N.A.	N.A.	N.A.	N.A.
1276019	Soil	42	0.18	555	0.006	4	0.68	0.005	0.11	0.5	0.61	2.4	1.7	<0.05	2	7.0	0.3	N.A.	N.A.	N.A.	N.A.
1276020	Soil	8	0.03	580	0.002	2	0.56	0.017	0.04	0.1	0.18	0.1	0.4	0.19	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276021	Soil	10	0.02	143	0.002	2	0.36	0.002	0.05	0.2	0.03	0.1	0.6	0.13	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276022	Soil	10	0.02	157	0.002	1	0.41	0.003	0.05	0.1	0.05	0.1	0.5	0.12	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276023	Soil	8	0.02	144	0.003	1	0.41	0.003	0.03	0.1	0.03	0.1	0.3	0.06	5	1.0	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1274074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274075	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276017	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276019	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276021	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276022	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276023	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274075	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276017	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276019	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276021	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276022	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276023	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276024	Soil	7.0	11.2	14.7	52	0.2	11.8	2.6	51	1.90	17.0	1.7	0.1	15	0.1	2.4	0.3	88	0.02	0.051	9
1276025	Soil	1.1	2.5	6.5	8	0.2	1.7	0.4	8	0.25	2.2	0.7	<0.1	6	<0.1	0.3	<0.1	9	0.02	0.039	1
1276026	Soil	26.5	19.0	11.5	158	1.0	34.3	4.1	152	1.51	26.1	1.6	<0.1	24	2.0	5.1	0.2	115	0.06	0.076	5
1276027	Soil	2.2	31.5	21.8	91	<0.1	27.1	9.0	188	3.03	16.5	2.4	0.8	11	<0.1	2.7	0.3	12	<0.01	0.042	3
1276028	Soil	3.4	24.9	20.4	103	<0.1	32.4	10.0	147	2.77	20.1	1.5	0.8	9	<0.1	1.4	0.3	13	<0.01	0.031	3
1276029	Soil	3.8	51.6	24.5	165	0.1	42.8	14.7	328	3.17	16.6	1.2	0.7	13	0.7	1.4	0.3	17	<0.01	0.045	3
1276030	Soil	17.7	14.3	27.4	59	0.7	7.9	1.5	40	1.75	41.2	11.9	0.1	34	0.1	8.3	0.2	78	0.02	0.085	8
1276031	Soil	24.4	17.7	51.4	70	1.0	16.7	4.3	129	3.38	16.4	4.7	1.3	35	0.2	7.8	0.3	111	0.04	0.056	10
1276032	Soil	21.6	35.1	35.1	116	0.7	22.7	3.3	102	3.41	32.4	3.3	0.6	64	0.3	7.2	0.3	113	0.03	0.095	10
1276033	Soil	18.6	16.4	31.4	50	0.3	10.2	2.4	42	1.99	36.1	2.8	0.1	37	0.2	4.9	0.2	90	0.02	0.074	9
1276034	Soil	18.4	19.4	41.2	58	0.4	12.4	2.6	57	1.99	25.7	2.7	0.2	22	0.1	5.6	0.3	100	0.02	0.074	11
1276035	Soil	6.9	7.6	11.2	30	0.6	5.7	1.2	24	0.58	5.9	<0.5	<0.1	7	<0.1	1.9	0.1	56	0.02	0.038	5
1276036	Soil	70.2	32.4	29.8	194	1.0	39.4	2.4	36	1.95	33.3	1.8	0.1	41	0.5	18.8	0.3	560	0.02	0.093	15
1276037	Soil	121.7	33.8	19.6	492	0.4	161.6	3.3	49	1.59	30.1	0.5	0.2	10	0.4	26.6	0.2	870	0.03	0.085	10
1276038	Soil	13.1	6.7	8.0	46	0.3	8.1	0.9	15	0.54	5.7	1.0	<0.1	8	<0.1	2.3	<0.1	148	0.01	0.039	16
1276039	Soil	18.3	12.1	11.3	61	0.4	11.7	1.9	28	1.04	15.0	1.5	<0.1	10	<0.1	4.1	0.1	168	<0.01	0.036	11
1276040	Soil	14.0	9.6	10.4	52	0.4	8.7	1.8	26	0.84	10.8	1.2	<0.1	14	0.1	2.5	<0.1	96	0.01	0.042	7
1276041	Soil	5.7	128.6	24.4	110	1.4	46.2	7.4	459	7.39	23.7	5.8	1.7	36	0.7	6.8	0.3	200	0.04	0.189	7
1276042	Soil	8.6	19.7	37.7	54	1.0	8.6	1.7	71	1.84	10.7	3.9	0.4	58	0.1	3.8	0.3	47	0.02	0.058	4
1276043	Soil	4.1	3.5	4.3	9	0.3	2.0	0.5	21	0.33	1.8	0.8	<0.1	10	<0.1	0.8	<0.1	30	0.01	0.024	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276024	Soil	12	0.06	142	0.007	1	0.64	0.004	0.04	0.1	0.03	0.4	0.3	0.08	5	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276025	Soil	2	<0.01	44	0.001	<1	0.14	0.014	0.02	<0.1	0.02	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276026	Soil	8	0.03	232	0.002	1	0.49	0.009	0.04	0.1	0.23	0.2	1.4	0.07	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276027	Soil	4	0.02	65	<0.001	<1	0.36	0.003	0.04	<0.1	0.14	2.9	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276028	Soil	4	0.02	86	<0.001	<1	0.30	0.002	0.05	<0.1	0.40	2.6	0.2	<0.05	<1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276029	Soil	5	0.03	72	<0.001	<1	0.34	0.002	0.05	<0.1	0.07	4.3	0.4	0.05	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276030	Soil	11	0.08	193	0.002	1	0.57	0.004	0.07	<0.1	3.24	0.3	0.7	0.14	2	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276031	Soil	19	0.16	442	0.016	1	0.80	0.003	0.16	0.2	0.22	1.4	1.1	0.40	5	8.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276032	Soil	19	0.10	529	0.008	2	0.78	0.004	0.17	0.2	0.20	1.2	1.1	0.50	4	9.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276033	Soil	13	0.03	546	0.003	1	0.54	0.006	0.10	0.2	0.10	0.2	0.7	0.24	4	7.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276034	Soil	12	0.03	661	0.003	2	0.43	0.004	0.11	0.2	0.07	0.2	0.7	0.26	4	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276035	Soil	6	0.02	149	0.002	2	0.20	0.013	0.04	<0.1	0.05	<0.1	0.3	0.08	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276036	Soil	35	0.04	373	0.003	3	0.52	0.003	0.11	0.3	0.06	0.2	3.8	0.18	5	8.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276037	Soil	28	0.04	229	0.001	3	0.55	0.005	0.08	0.2	0.06	0.1	2.2	<0.05	4	10.3	0.3	N.A.	N.A.	N.A.	N.A.
1276038	Soil	8	0.02	102	0.003	2	0.29	0.007	0.05	<0.1	0.03	<0.1	0.9	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276039	Soil	8	0.02	97	0.003	<1	0.28	0.003	0.04	0.1	0.04	<0.1	0.6	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276040	Soil	7	0.01	1069	0.002	1	0.17	0.009	0.04	<0.1	0.03	<0.1	0.6	0.07	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276041	Soil	108	0.16	186	0.014	1	1.07	0.007	0.06	0.2	0.16	11.3	0.5	0.14	6	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276042	Soil	13	0.04	473	0.003	1	0.31	0.007	0.11	0.1	0.13	1.4	0.6	0.27	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276043	Soil	5	0.01	98	0.003	<1	0.27	0.013	0.03	<0.1	0.03	<0.1	0.3	0.06	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276025	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276026	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276027	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276028	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276029	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276030	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276031	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276032	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276033	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276034	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276035	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276036	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276037	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276038	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276039	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276040	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276041	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276042	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276043	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11000983.3

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276025	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276026	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276027	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276028	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276029	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276030	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276031	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276032	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276033	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276034	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276035	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276036	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276037	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276038	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276039	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276040	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276041	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276042	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276043	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11000983.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1094327	Soil	8.7	17.7	17.9	37	0.5	9.3	1.8	43	2.14	22.5	1.9	0.3	26	<0.1	2.6	0.2	102	0.02	0.051	9
REP 1094327	QC	9.4	17.9	18.3	36	0.5	9.1	1.8	43	2.20	23.6	3.1	0.3	26	0.1	2.6	0.2	106	0.02	0.053	10
1094337	Soil	7.7	16.0	5.4	155	0.7	23.6	2.1	55	0.74	8.7	<0.5	<0.1	9	2.3	2.6	<0.1	117	0.06	0.063	4
REP 1094337	QC	6.9	14.9	5.1	149	0.7	21.3	2.0	53	0.70	8.5	1.9	<0.1	9	2.2	2.5	<0.1	115	0.06	0.059	4
1094361	Soil	111.3	175.1	24.7	2009	2.8	213.2	7.0	181	2.80	126.2	2.2	2.2	309	20.3	62.3	0.2	592	10.13	0.130	8
REP 1094361	QC	111.4	171.7	24.8	1971	2.6	216.2	6.9	177	2.69	125.4	5.0	2.1	300	19.7	61.5	0.2	571	10.54	0.129	8
1094384	Soil	61.7	71.8	17.7	158	0.3	153.4	9.4	331	3.49	23.2	2.7	0.8	104	1.6	3.4	0.1	64	5.41	0.096	5
REP 1094384	QC	64.0	72.8	18.5	164	0.3	161.3	9.9	341	3.55	24.1	2.8	0.8	111	2.0	3.7	0.1	65	5.84	0.104	5
1094397	Soil	5.9	26.5	53.5	114	0.1	30.5	15.2	779	3.41	16.4	1.6	1.2	9	0.2	2.0	0.3	35	0.03	0.055	9
REP 1094397	QC	6.3	27.4	51.7	122	<0.1	33.8	15.7	771	3.45	20.9	0.8	1.2	10	0.2	2.2	0.3	39	0.03	0.056	9
1094618	Soil	3.2	14.4	10.9	56	<0.1	8.4	1.9	24	1.06	10.9	<0.5	0.4	7	<0.1	1.0	0.2	30	0.01	0.042	4
REP 1094618	QC	3.4	14.3	10.6	57	<0.1	9.0	1.9	24	1.07	11.2	0.5	0.4	7	<0.1	1.1	0.2	28	0.01	0.045	4
1094623	Soil	15.8	81.5	79.1	191	1.2	27.7	8.4	257	4.03	47.3	5.9	5.3	51	1.1	8.7	0.4	81	0.02	0.130	5
REP 1094623	QC	16.7	81.6	80.9	193	1.3	27.3	8.4	263	4.16	48.1	8.6	5.4	52	1.0	9.1	0.4	84	0.02	0.132	6
1094653	Soil	1.5	2.6	1.5	10	0.3	1.7	0.4	8	0.28	1.5	<0.5	<0.1	6	<0.1	0.3	<0.1	16	0.02	0.040	<1
REP 1094653	QC	1.2	2.6	1.6	10	0.2	1.6	0.4	8	0.27	1.4	<0.5	<0.1	5	<0.1	0.3	<0.1	14	0.02	0.036	<1
1094667	Soil	7.9	18.4	11.0	45	0.4	5.4	0.8	16	1.37	21.6	<0.5	<0.1	18	0.4	4.3	0.1	92	0.02	0.055	3
REP 1094667	QC	7.4	18.1	11.3	44	0.4	5.5	0.9	16	1.42	22.0	0.7	<0.1	18	0.4	4.3	0.1	92	0.02	0.054	3
1094691	Soil	27.5	33.0	16.3	646	0.4	77.7	10.2	149	2.31	24.9	1.3	1.9	16	5.9	18.1	0.1	150	0.19	0.050	4
REP 1094691	QC	26.4	31.9	16.3	621	0.4	75.9	9.7	146	2.27	23.6	0.6	1.9	16	5.7	17.5	0.1	149	0.19	0.051	4
1094696	Soil	0.6	1.7	1.5	5	0.2	1.5	0.4	6	0.14	<0.5	<0.5	<0.1	3	<0.1	0.1	<0.1	8	0.01	0.019	1
REP 1094696	QC	0.5	1.6	1.5	5	0.2	1.6	0.4	6	0.14	0.5	<0.5	<0.1	3	<0.1	0.1	<0.1	9	0.02	0.019	1
1094728	Soil	3.8	27.9	10.3	85	0.4	18.8	4.0	90	2.53	13.1	2.8	1.5	15	0.4	2.4	0.2	75	0.08	0.062	12
REP 1094728	QC	3.7	28.1	10.3	83	0.4	19.4	4.0	90	2.50	13.0	3.3	1.6	15	0.2	2.5	0.2	75	0.08	0.061	13
1274002	Soil	11.8	26.9	17.3	147	0.2	35.0	7.4	97	2.46	12.4	<0.5	0.5	5	0.2	3.8	0.2	64	0.02	0.044	6
REP 1274002	QC	13.1	28.4	17.3	145	0.2	36.5	8.0	100	2.55	12.5	2.5	0.4	5	0.2	3.8	0.2	69	0.02	0.045	6
1274019	Soil	49.0	17.0	5.5	157	0.1	52.2	2.6	21	0.85	11.5	<0.5	0.2	13	0.7	2.8	0.2	60	0.20	0.033	5
REP 1274019	QC	50.8	16.8	5.6	161	0.1	53.3	2.8	23	0.84	11.1	<0.5	0.2	14	0.8	2.6	<0.1	59	0.20	0.037	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11000983.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1094327	Soil	16	0.07	380	0.006	2	0.70	0.002	0.07	0.1	0.20	0.5	0.3	0.09	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094327	QC	16	0.07	396	0.007	2	0.74	0.002	0.08	0.1	0.21	0.5	0.4	0.08	3	2.0	<0.2				
1094337	Soil	9	0.03	422	0.004	2	0.44	0.016	0.03	<0.1	0.14	0.3	0.3	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094337	QC	9	0.03	406	0.004	1	0.42	0.016	0.03	0.1	0.13	0.3	0.3	<0.05	2	1.4	<0.2				
1094361	Soil	26	2.74	427	0.003	6	0.32	0.011	0.08	0.3	1.79	3.6	3.1	0.08	<1	9.4	0.2	N.A.	N.A.	N.A.	N.A.
REP 1094361	QC	25	2.70	412	0.003	6	0.31	0.011	0.07	0.3	1.76	3.6	3.2	0.10	<1	10.0	<0.2				
1094384	Soil	16	1.93	199	0.001	3	0.26	0.007	0.03	0.1	0.32	2.6	0.9	<0.05	<1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094384	QC	17	2.08	208	0.002	3	0.29	0.007	0.04	0.1	0.33	2.9	0.9	0.05	<1	2.7	<0.2				
1094397	Soil	17	0.19	71	0.007	1	1.02	0.005	0.04	0.1	0.06	1.7	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094397	QC	18	0.20	74	0.006	2	1.06	0.005	0.04	<0.1	0.04	1.9	0.2	<0.05	3	1.1	<0.2				
1094618	Soil	7	0.02	92	0.002	<1	0.53	0.005	0.05	<0.1	0.06	0.9	0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094618	QC	7	0.02	89	0.002	<1	0.56	0.005	0.05	<0.1	0.04	1.0	0.2	<0.05	2	1.6	<0.2				
1094623	Soil	15	0.03	482	0.004	3	0.45	0.004	0.13	<0.1	0.20	4.1	0.8	0.22	2	5.3	0.3	N.A.	N.A.	N.A.	N.A.
REP 1094623	QC	16	0.03	523	0.004	3	0.48	0.004	0.14	<0.1	0.17	4.3	0.8	0.22	2	5.2	<0.2				
1094653	Soil	2	<0.01	81	0.002	<1	0.09	0.019	0.02	<0.1	0.02	<0.1	0.2	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094653	QC	2	<0.01	79	0.002	<1	0.08	0.017	0.02	<0.1	0.02	<0.1	0.1	<0.05	<1	<0.5	<0.2				
1094667	Soil	12	<0.01	210	0.003	1	0.18	0.002	0.04	0.1	0.07	0.4	0.3	0.07	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094667	QC	12	<0.01	207	0.003	1	0.18	0.002	0.04	<0.1	0.06	0.4	0.4	0.07	3	4.1	<0.2				
1094691	Soil	10	0.02	233	<0.001	1	0.30	0.002	0.03	<0.1	0.21	3.3	0.2	<0.05	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094691	QC	9	0.02	227	<0.001	<1	0.30	0.001	0.03	<0.1	0.21	3.3	0.2	<0.05	<1	1.7	<0.2				
1094696	Soil	2	<0.01	31	0.003	1	0.10	0.015	0.02	<0.1	0.02	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094696	QC	2	<0.01	31	0.003	<1	0.10	0.015	0.02	<0.1	<0.01	0.1	<0.1	<0.05	<1	<0.5	<0.2				
1094728	Soil	21	0.22	193	0.027	<1	1.00	0.005	0.05	0.2	0.09	1.6	0.3	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094728	QC	21	0.22	195	0.027	<1	0.99	0.005	0.04	0.2	0.09	1.5	0.3	<0.05	4	1.7	<0.2				
1274002	Soil	7	0.03	113	0.002	2	0.53	0.003	0.04	0.1	0.03	1.0	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274002	QC	7	0.03	115	0.002	2	0.54	0.003	0.04	0.1	0.05	0.9	0.2	<0.05	3	1.9	<0.2				
1274019	Soil	5	0.04	181	0.002	2	0.29	0.007	0.03	0.1	0.04	0.7	0.4	<0.05	1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274019	QC	6	0.04	185	0.004	1	0.29	0.007	0.03	0.1	0.05	0.6	0.4	<0.05	1	1.3	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11000983.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1094327	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094327	QC																					
1094337	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094337	QC																					
1094361	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094361	QC																					
1094384	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094384	QC																					
1094397	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094397	QC																					
1094618	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094618	QC																					
1094623	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094623	QC																					
1094653	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094653	QC																					
1094667	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094667	QC																					
1094691	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094691	QC																					
1094696	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094696	QC																					
1094728	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094728	QC																					
1274002	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274002	QC																					
1274019	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274019	QC																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11000983.3

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1094327	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094327	QC													
1094337	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094337	QC													
1094361	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094361	QC													
1094384	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094384	QC													
1094397	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094397	QC													
1094618	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094618	QC													
1094623	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094623	QC													
1094653	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094653	QC													
1094667	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094667	QC													
1094691	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094691	QC													
1094696	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094696	QC													
1094728	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094728	QC													
1274002	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274002	QC													
1274019	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274019	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11000983.3

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1274073	Soil	0.4	3.2	8.0	9	<0.1	2.1	1.5	26	0.43	5.0	<0.5	<0.1	4	<0.1	0.2	<0.1	4	0.02	0.034	<1
REP 1274073	QC	0.3	2.9	6.9	8	<0.1	2.0	1.4	24	0.39	4.3	<0.5	<0.1	4	<0.1	0.2	<0.1	5	0.02	0.032	<1
1276076	Soil	11.2	68.8	21.6	294	0.6	86.5	13.6	178	3.16	20.7	3.0	2.7	102	1.1	6.3	0.2	72	0.31	0.159	8
REP 1276076	QC	11.4	70.7	21.7	303	0.6	86.9	13.8	181	3.24	20.6	3.0	2.8	98	1.1	6.2	0.2	71	0.30	0.162	8
1276018	Soil	46.8	173.3	13.5	1244	3.0	340.2	9.6	254	2.99	59.8	2.6	3.0	227	17.0	16.6	0.2	622	7.11	0.500	26
REP 1276018	QC	43.3	171.1	13.3	1222	2.8	333.8	9.3	247	2.94	58.0	5.4	3.0	226	17.5	16.0	0.2	583	6.79	0.479	26
1276020	Soil	10.9	12.8	9.1	88	1.3	23.9	1.4	21	0.74	8.7	3.4	<0.1	15	1.1	3.4	0.3	74	0.08	0.099	3
REP 1276020	QC	11.0	12.9	9.0	89	1.3	24.4	1.4	21	0.74	9.1	3.3	<0.1	15	1.1	3.2	0.2	73	0.08	0.100	4
Reference Materials																					
STD DS8	Standard	13.7	114.6	129.2	343	2.1	39.7	8.0	659	2.88	27.9	118.3	6.9	70	2.5	6.3	6.7	46	0.75	0.086	17
STD DS8	Standard	13.3	109.0	127.4	314	1.8	40.8	8.0	603	2.42	22.9	111.2	6.5	56	2.1	4.8	6.4	43	0.67	0.073	14
STD DS8	Standard	14.1	107.4	123.5	315	1.7	39.4	7.4	627	2.39	22.7	115.1	6.6	63	2.1	5.4	6.1	46	0.71	0.077	16
STD DS8	Standard	13.7	117.1	122.5	316	1.8	39.6	8.1	624	2.52	24.8	116.9	6.7	63	2.2	5.2	6.4	45	0.70	0.082	15
STD DS8	Standard	13.2	113.0	123.9	307	1.8	38.5	7.5	607	2.45	25.2	100.0	6.7	63	2.2	5.2	6.6	42	0.69	0.078	16
STD DS8	Standard	12.0	104.3	121.6	313	1.7	38.2	7.2	616	2.62	25.9	111.5	6.5	62	2.1	5.5	5.9	42	0.70	0.079	14
STD DS8	Standard	14.7	121.7	134.8	343	2.1	43.7	8.1	668	2.72	27.8	126.2	7.5	69	2.6	5.8	6.8	47	0.77	0.085	17
STD DS8	Standard	13.0	107.8	127.6	318	1.9	37.9	7.3	659	2.55	26.2	121.7	6.2	67	2.4	5.4	6.4	43	0.73	0.084	16
STD DS8	Standard	12.7	111.1	124.9	317	1.9	38.2	7.4	597	2.46	25.0	122.6	6.2	58	2.5	5.4	6.4	41	0.68	0.082	13
STD DS8	Standard	14.0	107.8	125.1	307	1.9	38.2	7.6	615	2.46	23.7	104.4	6.9	60	2.4	5.3	6.6	44	0.71	0.077	16
STD DS8	Standard	13.1	110.1	124.3	324	1.8	36.7	7.5	598	2.48	24.7	106.2	6.6	59	2.6	5.5	5.8	41	0.70	0.079	14
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11000983.3

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1274073	Soil	2	0.01	23	0.003	<1	0.14	0.017	0.02	<0.1	0.02	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274073	QC	2	0.01	21	0.002	<1	0.13	0.016	0.02	<0.1	0.02	0.2	<0.1	<0.05	<1	<0.5	<0.2				
1276076	Soil	17	0.06	2090	0.003	3	0.48	0.002	0.06	<0.1	0.16	4.0	0.2	0.07	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276076	QC	18	0.06	2132	0.003	3	0.50	0.002	0.08	<0.1	0.16	4.0	0.2	0.07	1	2.0	<0.2				
1276018	Soil	146	3.83	1144	0.006	8	0.84	0.010	0.11	0.4	1.45	5.8	1.1	0.08	2	8.3	0.2	N.A.	N.A.	N.A.	N.A.
REP 1276018	QC	139	3.61	1159	0.006	7	0.80	0.010	0.11	0.5	1.39	5.7	1.1	<0.05	2	8.5	0.3				
1276020	Soil	8	0.03	580	0.002	2	0.56	0.017	0.04	0.1	0.18	0.1	0.4	0.19	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276020	QC	8	0.03	590	0.001	2	0.55	0.017	0.04	<0.1	0.17	<0.1	0.4	0.16	2	2.3	<0.2				
Reference Materials																					
STD DS8	Standard	125	0.64	309	0.126	3	0.98	0.096	0.48	3.1	0.22	2.8	5.6	0.23	5	4.6	5.2				
STD DS8	Standard	123	0.59	250	0.111	3	0.87	0.074	0.36	3.1	0.18	1.9	5.6	0.23	5	5.2	5.1				
STD DS8	Standard	128	0.65	278	0.125	2	0.94	0.079	0.39	3.1	0.21	2.2	5.5	0.29	5	5.1	5.0				
STD DS8	Standard	125	0.62	292	0.112	3	0.92	0.084	0.41	3.1	0.19	2.0	5.5	0.17	5	5.1	5.6				
STD DS8	Standard	122	0.61	286	0.112	1	0.91	0.085	0.41	3.0	0.20	2.3	5.7	0.15	5	5.1	4.6				
STD DS8	Standard	120	0.56	281	0.114	2	0.91	0.085	0.40	3.0	0.19	2.1	5.4	0.18	4	6.1	5.4				
STD DS8	Standard	132	0.66	308	0.134	2	0.97	0.089	0.43	3.3	0.22	2.4	5.6	0.17	5	5.3	5.5				
STD DS8	Standard	121	0.63	292	0.123	2	0.95	0.093	0.46	2.9	0.20	2.2	5.5	0.13	5	5.5	4.8				
STD DS8	Standard	117	0.61	267	0.105	2	0.89	0.080	0.41	3.2	0.22	2.0	5.5	0.19	5	5.0	5.0				
STD DS8	Standard	121	0.60	283	0.113	2	0.88	0.082	0.39	3.0	0.20	2.2	5.5	0.15	5	5.3	5.2				
STD DS8	Standard	110	0.58	269	0.111	2	0.91	0.085	0.40	2.8	0.20	2.5	5.3	0.06	5	5.2	5.4				
STD DS8	Standard																	13.8	114.4	130.1	309
STD OREAS45CA	Standard																	1.0	536.7	20.0	62
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11000983.3

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1274073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274073	QC																				
1276076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276076	QC																				
1276018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276018	QC																				
1276020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276020	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.9	38.8	8.0	635	2.50	23.9	99.5	7.4	73	2.4	5.4	7.0	45	0.72	0.076	16	122	0.60	297	0.123
STD OREAS45CA	Standard	0.3	252.6	88.8	895	16.54	4.1	45.8	6.9	16	0.1	0.1	0.2	203	0.42	0.036	16	732	0.16	165	0.149
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11000983.3

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1274073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274073	QC												
1276076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276076	QC												
1276018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276018	QC												
1276020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276020	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.94	0.096	0.42	3.3	0.18	2.4	5.5	0.15	5	5.2	4.8
STD OREAS45CA	Standard	<20	3.78	0.013	0.07	<0.1	0.03	36.8	<0.1	<0.05	18	0.8	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11000983.3

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11000983.3

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11000983.3

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11000983.3

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 01, 2011
Report Date: August 29, 2011
Page: 1 of 4

CERTIFICATE OF ANALYSIS WHI11000984.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #8
P.O. Number
Number of Samples: 77

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	77	Sieve to 230 mesh			WHI
RJSV	77	Saving all or part of Soil Reject			WHI
1DX2	77	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 29, 2011

CERTIFICATE OF ANALYSIS WHI11000984.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276044	Soil		8.8	13.1	12.2	50	0.6	9.8	2.8	83	2.26	14.3	6.8	0.4	9	<0.1	2.1	0.3	73	0.03	0.038	10
1276045	Soil		10.3	27.7	18.0	93	0.2	22.0	8.0	173	2.72	18.8	3.6	0.9	10	<0.1	5.1	0.3	60	0.02	0.044	6
1276046	Soil		10.6	23.3	15.1	75	0.2	15.3	5.7	96	2.78	18.9	1.9	0.1	13	<0.1	3.8	0.2	108	0.02	0.070	4
1276047	Soil		3.9	6.2	11.0	24	0.2	5.0	1.4	27	0.97	8.1	2.5	<0.1	8	<0.1	1.1	0.2	48	0.02	0.029	8
1276048	Soil		6.9	14.5	13.1	60	0.2	11.2	3.6	125	1.58	12.6	2.9	<0.1	13	<0.1	2.6	0.2	61	0.01	0.045	6
1276049	Soil		10.3	11.4	11.8	40	0.3	7.2	1.7	29	0.95	16.5	1.3	0.1	10	<0.1	3.0	0.2	57	0.01	0.056	5
1276050	Soil		4.2	5.3	5.9	21	0.1	3.8	0.9	41	0.55	5.9	3.2	<0.1	6	<0.1	1.1	<0.1	23	0.02	0.035	2
1276051	Soil		3.5	56.8	20.4	127	0.3	25.5	9.7	206	2.46	16.1	3.1	0.1	5	0.2	2.3	0.3	32	0.02	0.088	2
1276052	Soil		4.2	66.9	37.4	131	0.8	46.3	18.1	567	3.25	21.4	4.0	0.6	40	0.6	3.6	0.4	36	0.07	0.088	4
1276053	Soil		5.4	46.7	18.3	100	<0.1	30.2	10.7	208	2.74	10.9	3.6	0.3	8	0.2	2.5	0.3	44	0.03	0.060	5
1276054	Soil		3.2	31.1	10.3	66	0.2	19.3	7.4	368	2.65	6.5	2.5	0.2	6	0.1	1.5	0.2	30	0.03	0.099	2
1276055	Soil		4.9	33.0	13.1	106	0.6	30.3	9.4	288	1.74	7.5	4.1	0.1	10	0.2	2.1	0.2	27	0.07	0.080	4
1276056	Soil		2.0	12.8	4.9	48	0.5	13.5	3.1	82	0.69	2.6	1.9	<0.1	5	0.9	0.7	<0.1	12	0.04	0.052	1
1276057	Soil		32.4	40.4	24.0	410	0.3	169.9	16.8	143	2.97	16.9	3.3	0.6	31	1.4	7.0	0.1	75	0.18	0.096	6
1276058	Soil		133.3	57.2	11.9	793	0.1	167.1	4.8	25	2.22	42.8	2.9	0.4	7	2.1	25.5	0.2	420	0.05	0.058	7
1276059	Soil		90.2	45.9	9.9	592	1.0	133.7	3.9	72	1.22	27.6	2.7	0.3	36	4.6	14.3	0.1	265	0.56	0.058	7
1276060	Soil		102.6	70.4	7.9	749	0.3	208.2	9.2	187	1.66	23.5	1.9	2.2	99	5.3	5.1	0.1	79	2.93	0.094	5
1276061	Soil		29.3	58.0	24.5	428	1.4	150.0	8.6	90	2.29	18.1	5.4	0.8	81	4.1	7.4	0.2	104	1.56	0.220	6
1276062	Soil		15.1	15.3	9.7	116	0.3	26.4	3.3	86	1.28	10.1	1.3	0.2	14	0.8	2.4	0.1	65	0.11	0.129	6
1276063	Soil		19.8	43.3	18.0	274	0.5	63.4	9.9	175	2.79	25.7	3.1	0.7	34	1.1	6.2	0.2	93	0.21	0.122	9
1276064	Soil		13.4	40.8	19.7	251	0.8	52.8	9.2	197	2.81	19.5	4.1	1.0	32	1.1	4.7	0.2	81	0.31	0.119	9
1276065	Soil		6.5	14.5	7.4	65	0.3	17.4	3.0	44	0.93	10.5	2.1	0.1	15	0.2	2.0	<0.1	45	0.16	0.050	5
1276066	Soil		12.8	35.0	14.4	150	0.3	43.3	8.9	95	2.73	20.4	2.3	1.2	20	0.5	4.4	0.2	61	0.13	0.071	8
1276067	Soil		9.0	27.4	13.6	120	0.3	30.4	5.5	70	1.65	16.8	2.2	0.1	9	0.2	3.2	0.2	55	0.02	0.053	7
1276068	Soil		10.3	24.8	14.4	129	0.1	31.7	6.2	80	2.16	17.0	2.0	0.1	11	0.1	3.4	0.2	77	0.03	0.055	8
1276069	Soil		8.0	16.6	9.1	88	0.3	22.1	3.9	49	1.26	13.4	0.9	<0.1	8	0.3	2.1	0.2	60	0.02	0.091	7
1276070	Soil		17.3	29.7	15.0	232	0.9	49.5	7.1	220	2.58	18.4	4.5	0.4	15	1.1	4.1	0.2	114	0.05	0.140	5
1276081	Soil		11.5	41.5	24.4	242	0.4	49.2	13.7	507	3.23	21.4	5.4	1.5	26	1.2	4.9	0.2	72	0.23	0.129	8
1276082	Soil		12.2	37.1	22.1	205	0.6	42.6	9.2	242	2.98	17.8	4.0	1.2	15	0.8	4.6	0.2	73	0.07	0.080	8
1276083	Soil		8.0	30.2	18.8	179	0.5	35.8	11.1	255	2.97	15.1	2.5	1.7	16	1.0	4.1	0.2	49	0.08	0.093	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 29, 2011

CERTIFICATE OF ANALYSIS WHI11000984.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276044	Soil	18	0.12	227	0.014	3	0.90	0.003	0.04	0.2	0.29	0.9	0.2	<0.05	5	2.6	0.2
1276045	Soil	10	0.07	69	0.006	2	0.42	0.002	0.05	<0.1	0.12	2.1	0.2	<0.05	2	4.8	<0.2
1276046	Soil	9	0.02	282	0.003	3	0.37	0.003	0.04	0.1	0.04	0.8	0.3	0.07	2	2.7	0.2
1276047	Soil	8	0.05	157	0.006	2	0.55	0.002	0.03	<0.1	0.05	0.3	0.2	<0.05	4	1.0	<0.2
1276048	Soil	9	0.03	251	0.005	2	0.50	0.006	0.05	0.1	0.02	0.4	0.3	<0.05	4	1.5	<0.2
1276049	Soil	6	0.01	116	0.003	2	0.37	0.005	0.03	<0.1	0.21	0.3	0.4	<0.05	2	2.5	<0.2
1276050	Soil	4	0.01	53	0.003	2	0.25	0.013	0.02	<0.1	0.13	0.5	0.2	<0.05	2	1.7	<0.2
1276051	Soil	11	0.03	53	0.002	1	0.43	0.007	0.04	<0.1	0.08	1.4	0.1	<0.05	2	1.9	0.2
1276052	Soil	12	0.05	137	0.002	5	0.44	0.004	0.05	<0.1	0.06	2.7	0.2	<0.05	2	2.7	<0.2
1276053	Soil	14	0.04	65	0.004	1	0.51	0.004	0.03	0.1	0.02	1.1	0.1	<0.05	3	1.6	<0.2
1276054	Soil	11	0.06	45	0.005	<1	0.70	0.011	0.03	<0.1	0.06	1.2	0.1	<0.05	3	1.1	<0.2
1276055	Soil	11	0.06	101	0.005	1	0.64	0.011	0.03	<0.1	0.06	0.8	0.2	<0.05	2	1.3	<0.2
1276056	Soil	4	0.02	53	0.003	<1	0.28	0.016	0.02	<0.1	0.05	0.2	<0.1	<0.05	1	0.5	<0.2
1276057	Soil	33	0.01	187	0.003	2	0.34	0.009	0.03	<0.1	0.05	3.1	0.3	<0.05	<1	3.9	<0.2
1276058	Soil	23	0.02	178	0.002	2	0.41	0.002	0.05	0.3	0.07	0.8	1.4	<0.05	2	5.9	<0.2
1276059	Soil	17	0.05	175	0.003	2	0.43	0.010	0.04	0.3	0.39	1.3	1.1	<0.05	1	3.2	<0.2
1276060	Soil	12	0.82	185	0.002	3	0.28	0.003	0.04	0.4	0.36	3.6	1.0	<0.05	<1	3.8	<0.2
1276061	Soil	42	0.10	406	0.004	5	0.63	0.007	0.05	0.1	0.32	3.1	0.4	0.18	1	6.0	<0.2
1276062	Soil	12	0.04	320	0.004	<1	0.66	0.005	0.04	<0.1	0.02	0.5	0.3	<0.05	3	1.1	<0.2
1276063	Soil	16	0.08	422	0.003	2	0.52	0.005	0.06	0.1	0.13	1.8	0.3	<0.05	2	2.5	<0.2
1276064	Soil	20	0.13	580	0.003	2	0.84	0.005	0.06	0.1	0.28	2.4	0.3	<0.05	3	2.3	<0.2
1276065	Soil	7	0.03	404	0.002	<1	0.29	0.009	0.03	0.1	0.06	0.4	0.1	<0.05	2	1.4	<0.2
1276066	Soil	10	0.04	430	0.003	<1	0.32	0.004	0.05	<0.1	0.05	2.0	0.2	<0.05	1	1.8	<0.2
1276067	Soil	8	0.02	250	0.002	1	0.31	0.003	0.04	<0.1	0.07	0.6	0.2	<0.05	2	1.8	<0.2
1276068	Soil	10	0.03	219	0.003	1	0.42	0.004	0.05	0.1	0.01	0.5	0.2	<0.05	3	1.4	<0.2
1276069	Soil	11	0.03	173	0.002	<1	0.49	0.003	0.03	0.1	0.04	0.4	0.2	<0.05	3	1.6	<0.2
1276070	Soil	19	0.07	609	0.002	2	0.83	0.009	0.08	0.1	0.30	1.9	0.5	0.07	3	2.3	<0.2
1276081	Soil	15	0.15	637	0.002	1	0.83	0.003	0.06	0.1	0.18	2.5	0.3	<0.05	2	2.7	<0.2
1276082	Soil	14	0.11	291	0.002	1	0.67	0.004	0.06	0.1	0.15	2.0	0.3	<0.05	3	1.9	<0.2
1276083	Soil	14	0.16	276	0.003	1	0.82	0.003	0.05	<0.1	0.16	2.3	0.2	<0.05	2	1.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 29, 2011

CERTIFICATE OF ANALYSIS WHI11000984.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276084	Soil		4.3	15.5	13.9	70	0.9	16.2	4.0	87	1.38	7.5	4.0	0.3	10	0.6	1.6	0.2	32	0.05	0.076	4
1276085	Soil		8.1	24.3	22.6	151	0.5	33.4	11.6	277	2.77	16.4	1.9	1.4	21	0.7	2.6	0.2	52	0.28	0.086	8
1276086	Soil		14.2	25.3	20.7	173	0.2	39.1	10.0	166	3.10	18.4	3.0	2.0	21	1.4	3.9	0.2	83	0.08	0.080	10
1276087	Soil		8.4	16.2	11.8	84	1.3	21.7	4.8	59	1.26	7.8	3.4	0.4	13	0.4	1.7	0.1	62	0.06	0.071	3
1276088	Soil		11.1	42.6	18.4	258	0.8	44.8	9.4	235	2.55	18.9	4.6	1.4	31	0.7	3.7	0.2	78	0.39	0.159	10
1276089	Soil		93.0	42.4	72.7	118	2.7	40.2	1.1	23	3.16	44.5	7.3	2.6	106	0.2	29.5	0.4	601	<0.01	0.122	10
1276090	Soil		61.5	85.5	26.9	369	4.6	37.3	3.0	35	3.33	25.2	3.4	1.4	122	0.3	27.7	0.4	581	0.04	0.118	21
1276091	Soil		33.0	56.3	17.6	30	2.5	5.3	0.5	16	1.46	18.6	4.9	1.2	52	<0.1	16.4	0.2	147	0.03	0.060	15
1276092	Soil		62.0	37.4	9.2	18	2.4	2.5	0.2	5	1.36	20.9	2.8	0.2	27	<0.1	11.8	0.2	187	0.01	0.048	9
1276093	Soil		41.3	70.0	19.2	80	2.9	13.3	1.8	47	2.06	31.6	6.2	1.4	82	0.2	14.3	0.3	217	0.05	0.070	22
1276094	Soil		16.0	11.0	12.3	27	0.8	4.2	0.7	13	0.84	9.6	1.2	<0.1	31	<0.1	6.1	0.2	100	0.01	0.052	12
1276095	Soil		3.3	14.4	6.5	16	0.8	4.0	1.4	118	1.01	12.6	2.1	<0.1	14	<0.1	2.1	0.1	52	0.02	0.069	2
1276096	Soil		1.9	6.0	3.2	13	0.4	1.9	0.6	10	0.59	6.9	1.0	<0.1	9	<0.1	1.5	<0.1	36	0.01	0.036	2
1276097	Soil		16.5	68.7	23.6	174	1.9	28.9	42.5	1937	8.92	33.9	25.2	1.0	30	0.6	8.8	0.3	153	0.02	0.077	6
1276098	Soil		58.4	33.4	21.2	61	1.8	14.0	3.1	77	6.60	100.3	6.0	0.3	32	0.1	11.7	0.2	427	0.02	0.207	4
1276099	Soil		5.4	11.5	14.7	47	0.3	9.0	2.7	43	1.31	12.5	1.0	<0.1	17	<0.1	1.6	0.2	54	0.01	0.052	5
1276100	Soil		3.4	9.7	15.5	65	0.6	7.6	1.9	41	0.97	13.0	1.0	<0.1	37	0.3	1.6	0.2	32	0.02	0.084	5
1276101	Soil		5.7	11.7	19.9	32	0.3	7.3	2.2	58	1.22	11.6	0.9	<0.1	14	0.1	1.3	0.2	45	0.03	0.068	6
1276102	Soil		37.5	25.2	18.9	108	0.7	23.6	3.0	61	2.24	34.2	8.4	0.2	55	0.3	9.4	0.2	184	0.03	0.091	9
1276103	Soil		23.9	15.0	13.3	77	0.8	16.5	2.9	50	1.93	27.5	3.0	<0.1	21	<0.1	5.3	0.2	212	0.02	0.052	9
1276104	Soil		28.2	7.9	12.0	40	0.2	6.6	1.0	18	0.61	9.7	0.6	0.1	11	<0.1	5.6	0.1	110	<0.01	0.033	14
1276105	Soil		57.8	27.2	17.7	265	0.9	44.2	2.1	25	1.42	26.0	5.5	0.1	40	0.5	8.9	0.2	260	0.01	0.094	8
1276106	Soil		11.8	15.4	15.0	103	0.3	21.3	2.7	56	1.47	14.2	1.5	<0.1	13	0.5	2.8	0.2	100	0.02	0.065	8
1276107	Soil		40.4	45.4	23.9	549	0.2	94.0	7.4	80	2.75	36.8	2.7	0.4	19	2.1	11.8	0.2	241	<0.01	0.064	9
1276108	Soil		4.3	64.5	7.8	151	0.2	41.7	5.7	80	1.99	9.8	0.8	0.1	8	1.0	1.6	0.2	45	0.01	0.044	10
1276109	Soil		9.1	33.0	8.6	179	0.2	33.7	5.9	93	2.13	13.3	1.8	0.3	7	0.5	2.3	0.2	72	<0.01	0.037	18
1276110	Soil		13.7	16.9	13.0	126	0.6	19.2	3.1	44	1.18	11.4	2.4	0.1	13	0.2	2.5	0.2	87	0.01	0.034	18
1276451	Soil		17.3	14.9	19.5	47	0.4	9.5	1.9	39	1.63	39.3	3.6	0.2	27	0.1	6.8	0.3	101	<0.01	0.078	4
1276452	Soil		55.7	10.1	64.9	12	0.9	3.1	0.7	23	2.10	26.0	6.2	<0.1	3	<0.1	18.6	0.3	184	0.02	0.037	7
1276453	Soil		38.5	44.6	31.5	105	1.4	17.6	2.5	104	2.22	34.8	4.7	0.3	44	0.5	11.3	0.2	360	0.06	0.141	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 29, 2011

CERTIFICATE OF ANALYSIS WHI11000984.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276084	Soil	9	0.07	189	0.003	<1	0.68	0.012	0.04	0.1	0.22	0.9	0.1	<0.05	3	1.2	<0.2
1276085	Soil	16	0.29	275	0.003	<1	0.91	0.004	0.04	<0.1	0.15	2.4	0.2	<0.05	4	1.3	<0.2
1276086	Soil	18	0.21	373	0.003	<1	0.94	0.003	0.05	0.1	0.11	2.3	0.3	<0.05	4	2.4	<0.2
1276087	Soil	11	0.07	396	0.003	1	0.74	0.013	0.06	<0.1	0.25	1.4	0.3	<0.05	3	1.5	<0.2
1276088	Soil	14	0.14	918	0.003	1	0.89	0.004	0.06	<0.1	0.34	2.4	0.3	<0.05	2	2.4	<0.2
1276089	Soil	51	<0.01	119	0.006	4	0.34	0.004	0.27	0.3	0.60	3.3	3.5	0.54	8	35.2	0.6
1276090	Soil	38	<0.01	811	0.004	3	0.39	0.003	0.10	0.3	1.60	3.0	1.8	0.26	4	23.7	0.3
1276091	Soil	18	0.01	693	0.005	4	0.21	0.002	0.11	0.2	0.51	1.7	2.0	0.27	3	9.2	<0.2
1276092	Soil	14	<0.01	1018	0.002	2	0.17	0.002	0.05	0.3	0.24	0.5	1.5	0.16	2	12.1	<0.2
1276093	Soil	26	0.06	785	0.008	3	0.44	0.003	0.12	0.3	0.50	2.2	3.0	0.29	4	17.3	0.2
1276094	Soil	9	0.01	286	0.002	3	0.25	0.006	0.05	0.2	0.06	0.1	0.9	0.11	3	5.9	<0.2
1276095	Soil	11	0.04	197	0.008	<1	0.46	0.014	0.04	<0.1	0.16	0.3	0.2	0.11	3	2.1	<0.2
1276096	Soil	5	<0.01	85	0.004	<1	0.15	0.013	0.02	<0.1	0.07	<0.1	0.1	0.07	1	1.4	<0.2
1276097	Soil	19	0.05	690	0.005	2	0.85	0.002	0.07	0.1	3.76	3.4	3.0	0.14	3	10.4	<0.2
1276098	Soil	25	0.05	320	0.004	2	0.42	0.005	0.07	0.1	1.00	1.3	1.3	0.21	3	11.5	<0.2
1276099	Soil	6	0.01	96	0.004	<1	0.37	0.007	0.04	<0.1	0.05	0.2	0.2	0.11	2	1.7	<0.2
1276100	Soil	9	0.03	96	0.003	<1	0.41	0.012	0.03	<0.1	0.99	0.2	0.2	0.10	2	1.9	<0.2
1276101	Soil	12	0.06	113	0.007	<1	0.65	0.006	0.05	<0.1	0.06	0.2	0.3	0.08	3	2.3	<0.2
1276102	Soil	22	0.10	219	0.006	1	0.91	0.005	0.06	0.2	1.24	0.4	1.4	0.15	4	7.2	<0.2
1276103	Soil	14	0.04	119	0.007	2	0.61	0.003	0.04	0.2	0.28	0.2	0.5	0.08	4	3.5	<0.2
1276104	Soil	8	0.02	88	0.003	1	0.25	0.004	0.04	0.2	0.03	<0.1	0.8	0.06	3	2.4	<0.2
1276105	Soil	16	0.03	239	0.002	2	0.68	0.003	0.06	0.3	0.90	0.3	1.3	0.11	3	5.9	<0.2
1276106	Soil	12	0.04	94	0.006	1	0.62	0.006	0.04	0.1	0.02	0.2	0.3	0.06	4	1.8	<0.2
1276107	Soil	14	0.03	122	0.004	<1	0.54	0.002	0.03	0.2	0.09	0.9	0.6	0.06	3	5.7	<0.2
1276108	Soil	7	0.02	539	0.007	<1	0.38	0.007	0.03	<0.1	0.01	0.3	0.1	0.08	3	1.5	<0.2
1276109	Soil	6	0.02	90	0.005	1	0.32	0.002	0.04	0.1	0.02	0.5	0.2	0.07	3	1.2	<0.2
1276110	Soil	8	0.02	155	0.005	1	0.20	0.002	0.04	0.1	0.02	0.2	0.2	0.07	2	1.5	<0.2
1276451	Soil	8	0.02	228	0.003	1	0.33	0.002	0.08	0.1	0.15	0.2	1.0	0.19	2	3.9	<0.2
1276452	Soil	6	0.02	199	0.005	<1	0.28	0.003	0.10	0.3	0.40	0.2	0.6	0.23	2	9.9	<0.2
1276453	Soil	26	0.11	448	0.005	2	0.62	0.006	0.11	0.2	0.81	0.4	1.8	0.29	4	9.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 29, 2011

CERTIFICATE OF ANALYSIS WHI11000984.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276454	Soil	18.2	21.9	50.2	13	1.7	2.2	0.3	9	0.85	14.4	2.7	0.2	27	<0.1	10.0	0.2	62	0.02	0.098	8
1276455	Soil	35.2	31.8	44.5	39	2.0	6.3	0.7	24	1.55	45.2	6.3	0.3	46	0.2	10.1	0.2	90	0.02	0.255	5
1276456	Soil	46.0	12.3	76.1	5	2.7	1.3	0.1	8	1.95	23.1	6.5	0.6	16	<0.1	10.7	0.2	117	0.03	0.051	6
1276457	Soil	41.9	37.6	45.1	92	1.6	11.8	0.6	9	1.11	14.4	3.5	<0.1	54	0.4	8.7	0.2	131	0.02	0.150	4
1276458	Soil	122.2	34.4	172.5	56	4.2	8.8	0.6	22	1.57	28.9	1.5	2.0	38	<0.1	52.8	0.3	298	0.02	0.059	9
1276459	Soil	39.7	24.8	27.7	60	1.2	8.2	1.2	35	1.39	19.2	4.5	0.3	44	0.2	10.4	0.2	191	0.02	0.105	6
1276460	Soil	60.3	55.7	17.4	683	0.4	108.9	4.1	49	1.30	37.6	3.1	0.2	93	8.5	17.7	0.1	914	0.04	0.111	7
1276461	Soil	87.9	22.6	9.6	551	0.1	99.2	2.6	30	1.25	32.4	0.8	<0.1	5	0.8	21.4	0.1	526	0.01	0.051	15
1276462	Soil	85.9	31.8	11.1	534	0.3	93.3	2.6	18	1.20	42.2	0.7	0.1	8	1.8	21.9	0.2	494	0.02	0.040	23
1276463	Soil	12.1	14.3	7.1	85	0.2	20.3	2.1	31	0.82	14.3	1.1	<0.1	7	0.1	3.0	0.1	96	<0.01	0.049	6
1276464	Soil	71.3	47.8	13.7	451	0.1	143.8	15.0	101	2.63	35.1	<0.5	0.2	11	0.3	8.4	0.2	181	0.01	0.081	9
1276465	Soil	25.5	26.5	12.2	198	0.3	47.3	3.7	64	1.67	22.4	<0.5	0.3	14	0.4	3.6	0.2	136	0.04	0.155	7
1276466	Soil	62.2	35.9	10.9	338	<0.1	90.7	4.8	37	1.54	32.6	<0.5	0.2	6	0.2	10.5	0.2	295	<0.01	0.047	13
1276467	Soil	36.6	36.2	14.5	201	0.2	58.1	4.2	47	1.48	27.1	1.2	0.1	9	0.3	8.2	0.2	173	0.01	0.059	9
1276468	Soil	42.9	17.3	6.7	271	0.3	42.1	1.4	10	0.70	27.8	0.9	0.1	4	0.2	13.3	0.1	295	0.02	0.032	10
1276469	Soil	83.9	45.7	18.3	414	0.1	144.0	7.9	66	2.32	46.3	0.8	0.2	11	0.5	14.1	0.2	330	0.01	0.075	10
1276470	Soil	2.1	8.4	6.1	37	0.2	8.7	2.5	258	0.80	9.5	1.1	0.3	18	0.4	2.5	<0.1	14	0.63	0.072	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 29, 2011

CERTIFICATE OF ANALYSIS WHI11000984.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276454	Soil	13	0.02	622	0.002	1	0.39	0.008	0.06	0.2	1.54	0.3	1.5	0.16	2	6.1	<0.2
1276455	Soil	25	0.04	623	0.003	1	0.52	0.007	0.10	0.3	1.85	0.6	2.2	0.28	3	9.0	<0.2
1276456	Soil	10	<0.01	180	0.008	1	0.14	0.002	0.23	0.3	2.14	0.3	1.6	0.61	1	14.8	<0.2
1276457	Soil	20	0.01	765	<0.001	1	0.49	0.004	0.07	0.2	0.22	<0.1	1.6	0.20	2	9.8	0.2
1276458	Soil	26	0.04	436	0.009	3	0.36	0.003	0.14	0.7	0.24	4.7	1.5	0.29	5	47.7	0.8
1276459	Soil	17	0.04	236	0.003	<1	0.68	0.007	0.06	0.2	0.14	0.2	1.3	0.10	3	7.0	<0.2
1276460	Soil	46	0.06	427	0.003	3	0.71	0.008	0.07	0.2	0.07	0.4	2.6	<0.05	3	5.6	<0.2
1276461	Soil	26	0.03	132	0.002	<1	0.42	0.005	0.05	0.3	0.01	0.2	3.0	<0.05	3	3.6	<0.2
1276462	Soil	22	0.03	155	0.003	2	0.35	0.003	0.05	0.3	0.05	0.2	2.7	<0.05	3	4.3	<0.2
1276463	Soil	9	0.02	243	0.003	<1	0.39	0.010	0.03	<0.1	0.02	<0.1	0.4	<0.05	3	1.2	<0.2
1276464	Soil	13	0.05	73	0.002	2	0.60	0.003	0.03	0.3	0.01	0.5	0.6	<0.05	3	6.0	<0.2
1276465	Soil	21	0.08	134	0.007	1	0.67	0.005	0.05	0.1	0.05	0.5	0.9	0.05	3	2.2	<0.2
1276466	Soil	14	0.03	76	0.002	2	0.51	0.003	0.02	0.3	0.03	0.2	1.2	<0.05	4	2.8	<0.2
1276467	Soil	13	0.03	65	0.004	<1	0.40	0.004	0.03	0.1	0.03	<0.1	1.2	<0.05	4	1.8	<0.2
1276468	Soil	18	0.02	61	0.002	3	0.24	0.007	0.03	0.3	0.02	<0.1	1.1	<0.05	2	2.9	<0.2
1276469	Soil	17	0.03	101	0.001	<1	0.37	0.002	0.04	0.3	0.02	0.1	1.2	<0.05	3	4.1	<0.2
1276470	Soil	3	0.03	146	0.005	<1	0.34	0.022	0.02	<0.1	0.05	0.5	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 29, 2011

QUALITY CONTROL REPORT WHI11000984.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1276057	Soil	32.4	40.4	24.0	410	0.3	169.9	16.8	143	2.97	16.9	3.3	0.6	31	1.4	7.0	0.1	75	0.18	0.096	6
REP 1276057	QC	31.2	40.1	23.1	405	0.3	165.6	16.6	138	2.91	16.0	2.0	0.6	30	1.6	7.2	0.1	74	0.18	0.093	6
1276063	Soil	19.8	43.3	18.0	274	0.5	63.4	9.9	175	2.79	25.7	3.1	0.7	34	1.1	6.2	0.2	93	0.21	0.122	9
REP 1276063	QC	19.7	41.3	17.9	259	0.4	62.6	9.7	172	2.79	25.1	5.0	0.7	32	1.4	6.1	0.2	95	0.21	0.123	8
1276104	Soil	28.2	7.9	12.0	40	0.2	6.6	1.0	18	0.61	9.7	0.6	0.1	11	<0.1	5.6	0.1	110	<0.01	0.033	14
REP 1276104	QC	28.9	8.2	12.0	39	0.2	7.2	1.0	17	0.60	9.6	0.8	<0.1	11	<0.1	5.6	0.1	112	<0.01	0.033	14
1276452	Soil	55.7	10.1	64.9	12	0.9	3.1	0.7	23	2.10	26.0	6.2	<0.1	3	<0.1	18.6	0.3	184	0.02	0.037	7
REP 1276452	QC	53.8	9.8	64.0	11	0.9	2.9	0.6	23	2.04	25.1	6.2	<0.1	4	<0.1	18.0	0.3	178	0.01	0.036	6
Reference Materials																					
STD DS8	Standard	12.4	121.5	131.4	334	1.9	41.2	8.2	627	2.58	26.4	110.9	6.4	65	2.5	5.8	7.3	44	0.67	0.083	13
STD DS8	Standard	12.1	109.9	117.5	303	1.7	37.9	7.6	578	2.37	23.6	105.1	6.2	60	2.2	5.0	6.2	42	0.64	0.072	11
STD DS8	Standard	11.5	111.2	123.4	316	1.7	37.7	7.7	591	2.53	24.3	123.7	6.1	57	2.2	5.3	6.0	42	0.63	0.076	13
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: August 29, 2011

QUALITY CONTROL REPORT WHI11000984.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1276057	Soil	33	0.01	187	0.003	2	0.34	0.009	0.03	<0.1	0.05	3.1	0.3	<0.05	<1	3.9	<0.2
REP 1276057	QC	31	0.01	178	0.002	1	0.32	0.009	0.03	<0.1	0.04	3.0	0.4	<0.05	<1	3.9	<0.2
1276063	Soil	16	0.08	422	0.003	2	0.52	0.005	0.06	0.1	0.13	1.8	0.3	<0.05	2	2.5	<0.2
REP 1276063	QC	16	0.08	408	0.010	2	0.52	0.005	0.06	<0.1	0.11	1.8	0.3	<0.05	2	2.8	<0.2
1276104	Soil	8	0.02	88	0.003	1	0.25	0.004	0.04	0.2	0.03	<0.1	0.8	0.06	3	2.4	<0.2
REP 1276104	QC	8	0.02	91	0.007	<1	0.26	0.004	0.04	0.2	0.03	<0.1	0.8	0.06	3	2.5	<0.2
1276452	Soil	6	0.02	199	0.005	<1	0.28	0.003	0.10	0.3	0.40	0.2	0.6	0.23	2	9.9	<0.2
REP 1276452	QC	6	0.02	196	0.005	<1	0.27	0.003	0.09	0.3	0.36	0.2	0.5	0.23	1	9.5	<0.2
Reference Materials																	
STD DS8	Standard	126	0.69	262	0.111	<1	0.89	0.074	0.42	3.0	0.19	2.0	5.5	0.16	5	5.6	5.3
STD DS8	Standard	112	0.56	243	0.112	4	0.83	0.083	0.39	2.6	0.18	2.2	5.0	0.19	4	5.5	4.5
STD DS8	Standard	113	0.58	258	0.107	2	0.84	0.078	0.38	3.0	0.20	2.3	5.1	0.10	5	6.3	5.1
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 03, 2011
Report Date: October 26, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11000996.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #9
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve to 230 mesh			WHI
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	317	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	3	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1090861	Soil	5.0	15.4	10.4	57	0.6	10.4	1.7	28	0.93	10.9	1.6	0.1	17	0.2	2.1	0.2	44	0.01	0.072	4
1090862	Soil	18.5	75.6	21.1	330	0.8	68.5	8.1	144	3.14	43.0	3.3	1.8	70	1.6	8.3	0.3	138	0.26	0.238	14
1090863	Soil	22.2	41.2	21.9	247	1.6	55.6	4.8	68	2.65	46.6	4.9	0.6	54	1.1	7.1	0.3	161	0.09	0.198	10
1091671	Soil	76.8	226.2	24.3	2170	6.7	330.4	7.7	195	3.08	69.5	3.7	2.1	164	24.0	31.8	0.3	625	1.00	0.394	31
1091672	Soil	14.0	97.4	22.3	566	3.4	116.3	5.8	89	2.98	26.6	1.3	0.6	145	1.7	9.2	0.4	195	0.37	0.357	23
1091673	Soil	13.4	82.4	22.4	360	1.2	81.4	16.3	437	4.33	22.2	5.7	2.0	40	1.8	5.0	0.3	65	0.42	0.089	11
1091674	Soil	84.3	152.4	15.3	4960	3.6	324.0	12.9	273	1.90	58.6	0.9	1.2	136	36.9	32.7	0.2	490	4.49	0.106	26
1091675	Soil	67.8	55.6	14.1	478	0.5	188.4	14.3	288	2.73	31.0	2.0	1.7	40	2.7	5.1	0.2	111	0.41	0.136	19
1091676	Soil	47.2	95.5	24.7	753	3.3	180.5	17.0	532	4.55	40.8	2.9	2.2	38	7.1	9.9	0.3	162	0.45	0.167	25
1091677	Soil	45.3	71.9	21.8	641	1.3	151.6	10.4	333	4.29	34.6	0.8	2.5	32	5.7	8.8	0.3	155	0.40	0.167	27
1091678	Soil	2.6	111.0	18.0	225	2.1	84.8	10.4	146	2.90	11.6	5.9	1.5	149	1.4	1.4	0.3	40	1.55	0.177	10
1091679	Soil	4.0	74.1	24.1	305	1.7	104.5	25.5	466	3.78	20.2	3.0	2.3	57	1.1	1.8	0.3	37	0.56	0.117	6
1091680	Soil	22.1	13.5	3.9	378	1.8	7.5	0.8	13	>40	260.8	3.7	0.4	3	0.1	14.4	<0.1	1875	0.02	0.192	<1
1091681	Soil	8.3	32.8	27.1	42	1.2	10.6	3.1	253	2.29	21.6	4.5	0.2	55	0.1	4.2	0.6	96	0.03	0.108	6
1094731	Soil	5.1	42.9	13.6	111	1.0	27.3	7.2	229	2.22	17.2	4.7	3.3	29	0.4	3.4	0.2	72	0.17	0.128	13
1094732	Soil	3.5	25.7	10.1	88	0.4	23.9	6.6	190	2.49	15.5	3.6	1.7	16	0.4	1.9	0.2	64	0.10	0.058	13
1094733	Soil	4.1	33.7	10.6	93	0.7	24.6	6.4	180	2.44	16.1	4.3	3.7	21	0.5	2.6	0.2	65	0.13	0.100	12
1094734	Soil	14.5	24.7	19.4	35	1.9	11.1	1.3	40	1.45	14.4	3.5	0.3	65	0.3	5.1	0.3	76	0.02	0.077	5
1094735	Soil	14.8	25.6	18.3	48	1.6	12.8	2.0	75	1.52	15.2	2.7	0.4	63	0.2	5.0	0.2	80	0.02	0.072	6
1094736	Soil	4.0	14.7	12.5	42	0.4	8.9	2.5	96	1.55	14.8	1.4	0.1	15	<0.1	2.0	0.3	64	0.02	0.059	8
1094737	Soil	6.9	26.3	16.1	22	2.4	5.7	1.5	54	2.10	22.4	4.4	0.4	45	<0.1	5.1	0.3	82	0.03	0.105	5
1094738	Soil	7.1	25.1	16.8	31	2.0	8.0	2.0	61	2.00	21.5	7.8	0.4	34	<0.1	4.7	0.2	87	0.04	0.107	6
1094739	Soil	3.2	21.2	13.0	62	0.2	14.7	4.1	132	2.43	14.0	2.5	0.6	13	0.1	1.6	0.2	60	0.06	0.071	11
1094740	Soil	1.6	10.0	4.7	15	0.3	3.6	1.1	72	0.60	3.7	0.6	<0.1	7	<0.1	0.9	0.1	25	0.02	0.045	2
1094741	Soil	2.9	21.5	10.8	65	0.3	14.8	5.1	220	2.12	12.9	1.6	0.5	13	0.2	1.7	0.3	62	0.05	0.079	10
1094742	Soil	1.5	21.5	7.9	76	<0.1	13.9	8.4	253	1.82	7.1	<0.5	<0.1	8	0.2	0.8	0.2	24	0.02	0.095	4
1094743	Soil	2.1	25.7	7.9	90	<0.1	13.3	7.8	171	1.72	9.2	0.8	0.1	5	0.3	0.9	0.3	26	0.02	0.117	4
1094744	Soil	1.9	27.4	12.4	90	0.1	21.0	11.3	236	2.89	14.6	1.6	0.2	7	<0.1	1.0	0.3	29	0.03	0.069	5
1094745	Soil	2.0	27.8	15.9	74	<0.1	19.2	11.3	175	2.22	9.3	1.1	0.1	9	0.1	0.9	0.3	25	0.03	0.089	4
1094746	Soil	2.0	22.6	12.6	78	<0.1	18.9	9.2	182	2.31	11.8	1.0	0.2	11	0.2	0.9	0.2	28	0.06	0.078	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1090861	Soil		7	0.02	427	0.003	2	0.28	0.012	0.04	<0.1	0.08	0.4	0.2	0.06	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1090862	Soil		22	0.10	854	0.006	3	0.62	0.003	0.09	0.1	0.19	2.6	0.4	0.11	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1090863	Soil		22	0.07	997	0.004	3	0.68	0.004	0.08	0.2	0.46	1.2	0.5	0.10	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091671	Soil		84	0.17	693	0.006	9	0.71	0.006	0.18	0.3	1.94	4.5	2.4	0.34	3	35.2	0.6	N.A.	N.A.	N.A.	N.A.
1091672	Soil		46	0.04	1563	0.005	4	0.62	0.003	0.08	0.2	0.24	1.4	0.6	0.14	3	15.5	0.3	N.A.	N.A.	N.A.	N.A.
1091673	Soil		16	0.20	609	0.002	4	0.41	0.004	0.08	<0.1	0.28	5.7	0.4	0.07	1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091674	Soil		27	2.40	660	0.003	8	0.29	0.007	0.08	0.2	2.59	2.8	0.9	0.10	1	14.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091675	Soil		21	0.13	357	0.005	3	0.49	0.003	0.07	0.2	0.23	3.3	1.1	<0.05	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091676	Soil		38	0.16	1617	0.003	4	0.66	0.003	0.08	0.1	0.95	7.2	0.9	<0.05	1	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1091677	Soil		29	0.08	1069	0.003	3	0.51	0.002	0.07	0.1	0.44	5.9	0.9	0.06	<1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091678	Soil		26	0.11	554	0.002	5	1.05	0.005	0.11	<0.1	0.36	3.9	0.2	0.11	2	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091679	Soil		27	0.21	660	0.002	2	1.21	0.005	0.08	<0.1	0.28	5.5	0.2	0.16	3	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1091680	Soil		58	<0.01	95	0.003	<1	1.68	0.002	<0.01	<0.1	0.29	7.8	<0.1	1.40	<1	12.5	<0.2	N.A.	N.A.	N.A.	N.A.
1091681	Soil		15	0.06	300	0.007	1	0.69	0.008	0.08	0.1	0.04	0.7	0.3	0.05	4	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094731	Soil		22	0.29	319	0.029	2	0.99	0.006	0.06	0.3	0.25	2.9	0.4	<0.05	4	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094732	Soil		24	0.35	183	0.029	2	1.23	0.005	0.05	0.2	0.07	1.8	0.2	<0.05	4	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094733	Soil		20	0.29	234	0.042	2	0.99	0.005	0.06	0.2	0.15	2.9	0.3	<0.05	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094734	Soil		12	0.03	600	0.002	2	0.37	0.005	0.10	<0.1	0.17	1.0	1.1	0.23	2	7.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094735	Soil		14	0.05	469	0.003	3	0.38	0.006	0.10	<0.1	0.10	1.4	1.0	0.23	2	8.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094736	Soil		13	0.04	125	0.014	1	0.47	0.006	0.05	0.1	0.05	0.5	0.2	0.09	5	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094737	Soil		23	0.08	321	0.006	2	0.47	0.010	0.15	<0.1	0.14	1.3	0.5	0.31	5	6.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094738	Soil		24	0.11	326	0.009	2	0.52	0.009	0.11	0.1	0.17	1.4	0.4	0.17	4	7.4	0.2	N.A.	N.A.	N.A.	N.A.
1094739	Soil		22	0.27	98	0.024	2	1.26	0.010	0.05	0.2	0.03	1.2	0.2	<0.05	5	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094740	Soil		6	0.02	63	0.008	1	0.38	0.015	0.03	<0.1	0.06	0.2	<0.1	0.09	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094741	Soil		20	0.21	116	0.023	<1	1.35	0.009	0.06	0.1	0.04	1.1	0.2	<0.05	5	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094742	Soil		10	0.03	84	0.003	<1	0.54	0.007	0.04	<0.1	0.03	0.3	<0.1	<0.05	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094743	Soil		8	0.03	57	0.003	1	0.55	0.007	0.04	<0.1	0.03	0.6	<0.1	0.11	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094744	Soil		12	0.07	46	0.004	<1	0.46	0.002	0.03	<0.1	0.05	1.5	0.1	0.06	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094745	Soil		13	0.08	48	0.004	<1	0.63	0.010	0.05	<0.1	0.05	1.0	0.1	0.07	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094746	Soil		13	0.14	52	0.006	<1	0.74	0.005	0.03	<0.1	0.03	0.9	0.1	0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1090861	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090862	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090863	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091671	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091672	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091673	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091674	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091675	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091676	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091677	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091678	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091679	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091680	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091681	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094731	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094732	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094733	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094734	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094735	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094736	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094737	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094738	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094739	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094740	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094741	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094742	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094743	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094744	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094745	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094746	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1090861	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090862	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1090863	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091671	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091672	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091673	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091674	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091675	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091676	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091677	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091678	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091679	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091680	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091681	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094731	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094732	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094733	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094734	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094735	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094736	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094737	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094738	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094739	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094740	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094741	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094742	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094743	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094744	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094745	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094746	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094747	Soil	2.8	27.1	12.6	106	<0.1	19.6	9.5	158	2.18	12.2	1.2	0.1	9	0.1	1.3	0.2	30	0.02	0.075	6
1094748	Soil	3.0	22.3	17.5	89	<0.1	19.6	9.9	300	2.38	15.2	1.4	0.1	9	<0.1	1.9	0.2	27	0.03	0.074	5
1094749	Soil	2.1	18.0	9.1	65	<0.1	13.8	6.9	324	1.61	12.6	1.0	<0.1	5	0.1	1.0	0.1	18	0.01	0.070	3
1094750	Soil	113.6	105.0	18.1	906	1.1	228.9	8.3	191	2.19	92.3	5.6	2.9	85	7.0	31.5	0.2	301	2.83	0.112	8
1094759	Soil	2.1	18.8	13.0	65	<0.1	15.6	4.0	98	1.64	8.7	1.0	0.2	11	0.2	0.6	0.2	37	0.03	0.078	4
1094760	Soil	1.3	7.5	7.0	30	0.2	7.2	1.8	49	1.00	4.4	0.8	0.2	8	<0.1	0.4	0.2	32	0.03	0.036	6
1094761	Soil	1.9	23.7	18.3	97	0.1	29.1	7.6	147	3.26	17.4	2.5	1.4	19	0.2	0.9	0.3	29	0.03	0.058	3
1094762	Soil	1.4	15.8	10.6	45	0.4	11.3	2.3	48	1.10	6.3	1.3	0.1	15	0.2	0.4	0.1	22	0.05	0.096	3
1094763	Soil	2.1	23.1	19.5	100	0.1	26.7	6.3	120	3.29	17.4	1.0	0.9	21	0.2	0.8	0.3	37	0.02	0.086	3
1094764	Soil	0.7	4.4	3.1	10	0.3	2.6	0.6	10	0.35	2.1	1.6	<0.1	5	<0.1	0.2	<0.1	8	0.02	0.053	1
1094765	Soil	1.2	26.6	18.9	103	0.3	31.8	7.4	227	2.84	17.1	2.8	1.2	42	0.4	0.7	0.2	26	0.10	0.082	4
1094766	Soil	1.7	23.5	13.0	115	0.4	28.7	5.9	170	2.48	13.0	2.5	0.7	23	0.4	0.7	0.2	28	0.04	0.087	4
1094767	Soil	1.9	30.6	17.3	167	1.0	47.4	7.3	199	2.10	28.0	8.3	1.0	74	0.9	1.0	0.2	28	1.00	0.111	7
1094768	Soil	1.4	23.4	11.3	126	0.8	33.4	5.9	324	2.10	10.5	2.8	0.5	71	1.2	0.7	0.1	22	1.71	0.125	7
1094769	Soil	2.1	26.6	19.5	239	1.0	46.8	10.4	422	2.82	24.5	11.2	0.9	37	1.7	1.4	0.2	36	0.34	0.122	9
1094770	Soil	1.4	33.6	13.4	144	1.2	40.7	7.0	205	1.97	10.1	6.9	0.7	64	1.0	1.1	0.2	29	1.48	0.118	8
1094771	Soil	0.2	8.0	1.5	20	<0.1	3.6	1.2	79	0.41	1.3	<0.5	<0.1	19	0.2	0.1	<0.1	8	0.49	0.057	3
1094772	Soil	3.2	37.0	16.0	181	1.3	46.6	7.0	220	2.41	10.6	4.5	0.6	66	1.2	1.2	0.2	37	1.68	0.125	9
1094773	Soil	0.4	7.6	2.7	68	0.1	4.8	1.3	130	0.42	1.5	1.4	<0.1	46	1.1	0.2	<0.1	9	1.36	0.069	3
1094774	Soil	0.9	11.3	5.4	48	0.6	13.0	3.0	238	0.86	2.8	2.4	<0.1	17	0.4	0.3	<0.1	13	0.25	0.088	3
1094775	Soil	1.5	15.4	7.1	101	0.3	17.9	3.0	84	1.18	5.3	1.3	0.2	33	0.7	0.5	0.1	26	0.58	0.130	5
1094776	Soil	2.4	17.2	6.8	84	0.6	19.6	4.2	35	1.31	10.3	1.1	0.2	5	<0.1	0.7	0.1	32	<0.01	0.059	4
1094777	Soil	1.6	16.7	10.0	96	0.4	20.1	4.5	147	1.79	5.9	<0.5	0.5	33	0.5	0.5	0.2	29	0.54	0.159	7
1094778	Soil	2.1	30.6	15.1	139	0.8	37.9	6.6	137	2.39	9.9	5.6	0.6	54	1.0	0.7	0.2	28	0.93	0.137	6
1094779	Soil	2.3	28.1	18.9	113	0.3	30.3	9.2	141	2.99	15.9	3.8	1.1	29	0.3	0.9	0.3	32	0.07	0.073	6
1094780	Soil	2.2	23.0	11.1	123	0.5	46.5	7.6	71	2.79	10.5	0.7	0.5	18	0.4	0.9	0.2	35	0.13	0.048	3
1094781	Soil	1.3	30.2	8.9	66	1.4	29.8	4.6	85	2.00	6.5	5.0	0.6	56	0.4	0.5	0.1	20	1.15	0.100	3
1094782	Soil	2.5	25.4	15.9	82	0.7	21.7	4.9	66	1.80	10.8	3.4	0.5	14	0.4	1.1	0.2	33	0.04	0.068	7
1094783	Soil	2.3	18.5	8.7	67	0.9	17.5	3.7	63	1.33	8.8	2.0	0.2	17	0.4	1.1	0.1	23	0.11	0.053	3
1094784	Soil	1.8	38.2	12.5	105	1.7	37.4	7.2	113	2.24	8.4	6.7	0.7	51	0.4	0.7	0.2	21	1.01	0.073	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094747	Soil		10	0.06	53	0.003	1	0.43	0.004	0.05	<0.1	0.01	0.6	<0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094748	Soil		11	0.08	45	0.004	<1	0.55	0.006	0.04	<0.1	0.03	0.4	0.1	0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094749	Soil		5	0.03	43	0.002	1	0.38	0.011	0.03	<0.1	0.02	0.5	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094750	Soil		19	1.16	249	0.003	4	0.30	0.004	0.06	0.2	0.88	5.2	1.3	0.07	<1	6.8	0.3	N.A.	N.A.	N.A.	N.A.
1094759	Soil		12	0.04	115	0.002	1	0.73	0.005	0.05	0.1	0.03	0.6	0.2	0.07	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094760	Soil		10	0.08	83	0.004	<1	0.72	0.008	0.04	0.1	0.03	0.4	0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094761	Soil		18	0.21	180	0.001	1	1.07	0.003	0.04	<0.1	0.06	2.2	0.1	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094762	Soil		12	0.06	386	<0.001	2	0.84	0.007	0.04	<0.1	0.08	0.5	0.1	0.06	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094763	Soil		18	0.15	148	0.002	1	1.03	0.005	0.05	<0.1	0.06	1.6	0.1	<0.05	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094764	Soil		3	0.01	30	0.002	<1	0.25	0.011	0.02	<0.1	0.03	0.2	<0.1	<0.05	<1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094765	Soil		20	0.20	357	0.002	2	0.92	0.007	0.07	<0.1	0.10	2.6	0.1	0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094766	Soil		18	0.13	150	0.002	1	0.91	0.006	0.05	<0.1	0.06	1.4	0.1	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094767	Soil		20	0.08	760	0.002	7	0.73	0.005	0.10	<0.1	0.32	2.9	0.1	0.05	2	3.2	0.2	N.A.	N.A.	N.A.	N.A.
1094768	Soil		15	0.16	546	0.002	3	0.64	0.011	0.06	<0.1	0.15	1.4	0.1	0.10	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094769	Soil		21	0.09	477	0.002	2	0.97	0.006	0.07	<0.1	0.24	2.7	0.1	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094770	Soil		21	0.10	556	<0.001	4	0.65	0.004	0.07	<0.1	0.27	1.9	0.1	0.07	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094771	Soil		3	0.03	78	0.010	1	0.48	0.032	0.02	<0.1	0.02	0.7	<0.1	<0.05	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094772	Soil		20	0.09	540	0.002	6	0.70	0.004	0.09	<0.1	0.24	2.2	0.1	0.16	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094773	Soil		5	0.03	169	0.009	3	0.59	0.024	0.02	<0.1	0.06	0.6	<0.1	0.09	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094774	Soil		7	0.04	170	0.002	2	0.53	0.015	0.03	<0.1	0.06	0.3	<0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094775	Soil		12	0.04	279	0.004	2	0.58	0.008	0.05	<0.1	0.03	0.6	<0.1	0.07	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094776	Soil		9	0.02	101	0.002	2	0.40	0.003	0.04	<0.1	0.06	0.6	<0.1	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094777	Soil		17	0.08	489	0.004	2	0.76	0.005	0.04	<0.1	0.06	1.5	0.2	0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094778	Soil		23	0.13	418	0.003	3	0.77	0.006	0.05	0.1	0.14	2.1	0.1	0.10	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094779	Soil		21	0.15	529	0.005	2	0.92	0.006	0.07	0.1	0.05	2.7	0.1	0.09	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094780	Soil		10	0.02	312	0.002	2	0.48	0.005	0.05	<0.1	0.04	1.9	0.1	0.07	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094781	Soil		18	0.10	600	0.001	2	0.81	0.006	0.06	<0.1	0.44	3.5	<0.1	0.15	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094782	Soil		12	0.04	451	0.002	1	0.81	0.005	0.05	<0.1	0.08	1.6	0.1	0.08	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094783	Soil		10	0.04	226	0.004	2	0.49	0.010	0.04	<0.1	0.06	0.9	<0.1	0.08	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094784	Soil		17	0.13	588	0.001	2	0.81	0.006	0.05	<0.1	0.45	4.1	<0.1	0.11	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094747	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094748	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094749	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094750	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094759	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094760	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094761	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094762	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094763	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094764	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094765	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094766	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094767	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094768	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094769	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094770	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094771	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094772	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094773	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094774	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094775	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094776	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094777	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094778	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094779	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094780	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094781	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094782	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094783	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094784	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094747	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094748	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094749	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094750	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094759	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094760	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094761	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094762	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094763	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094764	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094765	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094766	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094767	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094768	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094769	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094770	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094771	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094772	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094773	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094774	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094775	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094776	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094777	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094778	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094779	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094780	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094781	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094782	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094783	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094784	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094785	Soil	3.0	36.2	16.3	78	0.8	17.4	3.8	87	1.74	10.1	2.3	0.1	13	1.1	1.3	0.2	49	0.03	0.067	5
1094786	Soil	2.1	21.8	5.2	32	0.4	7.7	1.6	21	0.88	5.0	2.7	<0.1	6	0.4	0.7	0.1	41	0.03	0.038	7
1094787	Soil	1.5	16.7	6.3	20	0.7	5.5	0.8	13	0.60	11.1	2.0	<0.1	8	0.6	1.4	<0.1	20	0.02	0.060	2
1094788	Soil	3.2	24.3	10.5	53	0.5	11.1	1.9	30	0.99	8.5	2.3	0.1	11	0.9	0.9	0.2	46	0.02	0.067	5
1094789	Soil	5.8	18.2	12.7	76	0.2	16.9	3.4	52	1.56	16.4	1.6	0.5	11	0.2	1.7	0.2	55	0.02	0.042	7
1094790	Soil	2.0	13.2	9.3	33	1.4	10.5	1.8	148	4.46	12.9	5.5	0.2	5	0.2	2.2	<0.1	24	0.01	0.087	2
1094791	Soil	4.3	11.5	7.0	43	0.5	10.4	2.2	28	1.09	10.8	2.6	0.6	6	<0.1	1.3	0.1	45	0.03	0.040	6
1094792	Soil	1.8	28.9	10.0	85	0.7	22.2	4.4	94	1.51	7.8	3.5	0.7	50	0.9	0.9	0.1	28	1.20	0.073	3
1094793	Soil	3.3	35.1	12.0	109	0.9	29.1	5.6	128	1.95	10.2	4.5	1.5	36	0.7	1.3	0.2	39	0.74	0.093	6
1094794	Soil	4.7	47.5	16.8	148	2.0	44.3	6.0	156	2.53	19.6	8.4	1.3	47	1.0	1.4	0.2	38	0.39	0.122	5
1094795	Soil	6.7	15.8	13.1	51	0.5	10.8	2.0	53	0.97	11.7	2.8	<0.1	18	0.2	1.8	0.2	56	0.03	0.066	9
1094796	Soil	23.3	43.4	34.0	65	1.9	22.0	2.3	39	1.17	23.7	5.1	0.5	26	0.8	6.7	0.2	201	0.10	0.117	9
1094797	Soil	9.2	15.6	6.7	31	0.4	8.2	1.3	16	0.51	5.8	1.2	<0.1	8	0.4	1.1	<0.1	28	0.05	0.063	5
1094798	Soil	20.4	24.4	11.0	69	1.4	15.4	2.2	36	1.22	13.8	1.8	0.1	8	0.6	2.6	0.2	51	0.03	0.078	7
1094799	Soil	35.6	36.2	11.2	61	1.0	15.7	2.1	32	0.96	12.0	8.9	<0.1	8	0.6	7.2	0.2	83	0.02	0.068	5
1094800	Soil	26.3	50.6	19.8	230	0.8	65.9	8.6	248	2.18	17.4	7.3	1.0	20	1.3	6.3	0.2	116	0.05	0.094	5
1095151	Soil	4.6	31.1	5.8	68	0.4	11.5	2.5	17	0.83	15.5	2.3	<0.1	6	0.1	2.0	0.1	27	<0.01	0.048	3
1095152	Soil	3.5	24.5	14.8	89	0.1	25.2	5.2	117	2.10	22.9	3.7	1.0	16	0.3	3.2	0.1	21	0.20	0.097	10
1095153	Soil	1.3	6.4	3.8	15	1.3	4.4	0.9	12	0.26	2.9	0.6	<0.1	4	<0.1	0.5	<0.1	8	0.02	0.054	1
1095154	Soil	3.6	27.0	6.8	68	0.4	9.6	2.5	25	0.64	14.1	1.1	<0.1	12	0.2	2.1	<0.1	21	0.02	0.064	3
1095155	Soil	3.7	20.9	20.1	51	0.5	11.1	2.9	58	1.64	17.6	2.1	<0.1	10	0.2	3.3	0.2	35	0.02	0.105	4
1095156	Soil	3.0	31.7	26.9	83	0.3	26.7	12.6	218	2.91	26.9	6.0	0.8	14	0.7	4.3	0.3	19	0.16	0.116	9
1095157	Soil	3.0	12.4	14.1	51	0.4	11.1	4.2	69	1.51	11.0	1.5	<0.1	9	0.1	1.5	0.2	27	0.04	0.057	4
1095158	Soil	4.7	13.7	21.1	62	0.1	13.3	4.9	107	2.41	13.2	1.2	0.2	9	0.1	2.2	0.2	44	0.02	0.044	6
1095159	Soil	0.6	3.5	2.7	12	<0.1	2.8	1.4	31	0.43	1.9	<0.5	<0.1	3	<0.1	0.3	<0.1	7	0.02	0.026	2
1095160	Soil	1.5	10.4	6.0	18	<0.1	5.4	2.4	37	0.64	3.0	1.4	<0.1	4	<0.1	0.4	0.1	14	0.01	0.036	4
1095161	Soil	1.6	4.3	7.4	12	<0.1	3.7	1.2	16	0.34	1.8	1.1	0.1	4	<0.1	0.3	<0.1	17	0.01	0.048	2
1095162	Soil	7.2	37.4	18.5	207	1.0	35.0	7.9	355	2.40	13.8	2.1	0.8	22	1.2	3.3	0.2	30	0.52	0.188	8
1095163	Soil	6.3	82.9	14.9	196	0.8	34.8	10.1	180	2.88	14.2	5.3	0.4	9	0.6	3.0	0.2	43	0.13	0.142	9
1095164	Soil	3.7	26.0	120.6	472	1.8	33.1	6.5	3991	10.08	15.6	3.6	1.2	33	2.1	5.6	0.1	35	1.47	0.139	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094785	Soil	15	0.04	221	0.004	2	0.68	0.007	0.05	0.1	0.04	0.7	0.1	0.08	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094786	Soil	11	0.02	284	0.003	1	0.34	0.005	0.03	<0.1	0.01	0.3	<0.1	0.06	3	0.9	0.2	N.A.	N.A.	N.A.	N.A.
1094787	Soil	7	0.01	117	0.003	2	0.26	0.011	0.03	<0.1	0.06	0.5	<0.1	0.07	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094788	Soil	11	0.03	174	0.002	2	0.60	0.007	0.05	<0.1	0.02	0.6	0.1	0.09	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094789	Soil	9	0.03	104	0.005	2	0.39	0.003	0.05	0.2	0.02	1.0	0.2	0.08	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094790	Soil	16	0.02	83	0.002	2	0.32	0.005	0.02	<0.1	0.09	0.6	0.1	0.10	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094791	Soil	7	0.02	109	0.002	1	0.42	0.004	0.05	<0.1	0.02	0.9	0.1	0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094792	Soil	15	0.12	800	0.002	3	0.73	0.008	0.06	<0.1	0.11	2.0	<0.1	0.14	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094793	Soil	14	0.13	470	0.002	3	0.70	0.004	0.06	<0.1	0.30	2.6	0.2	0.10	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094794	Soil	19	0.08	788	0.001	3	0.71	0.005	0.09	<0.1	0.86	2.7	0.5	0.14	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094795	Soil	11	0.04	226	0.003	2	0.55	0.004	0.06	0.2	0.10	0.3	0.3	0.08	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094796	Soil	18	0.06	316	0.002	2	0.66	0.005	0.08	0.4	0.70	0.9	3.0	0.07	3	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094797	Soil	4	0.01	154	0.002	2	0.23	0.005	0.03	<0.1	0.03	0.2	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094798	Soil	8	0.02	146	0.003	2	0.39	0.003	0.03	0.1	0.08	0.3	0.4	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094799	Soil	7	0.02	154	0.002	2	0.39	0.005	0.04	0.1	0.11	0.3	1.0	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094800	Soil	21	0.14	470	0.002	4	0.95	0.004	0.08	0.2	0.25	2.3	0.7	<0.05	3	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095151	Soil	4	0.01	112	0.002	2	0.31	0.004	0.03	<0.1	0.01	0.3	<0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1095152	Soil	10	0.03	226	0.003	2	0.25	0.004	0.02	<0.1	0.05	1.5	0.1	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095153	Soil	3	<0.01	30	0.001	<1	0.16	0.012	0.01	<0.1	0.02	0.3	<0.1	<0.05	<1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095154	Soil	4	0.01	164	<0.001	1	0.32	0.005	0.03	<0.1	0.03	0.3	0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095155	Soil	8	0.02	105	0.002	1	0.36	0.005	0.04	<0.1	0.03	0.3	0.1	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095156	Soil	10	0.13	176	0.002	<1	0.50	0.003	0.03	<0.1	0.09	1.8	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095157	Soil	9	0.06	178	0.003	1	0.39	0.006	0.02	<0.1	0.03	0.3	<0.1	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095158	Soil	10	0.06	74	0.005	<1	0.56	0.003	0.03	0.1	0.02	0.7	0.1	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095159	Soil	3	<0.01	19	0.003	<1	0.11	0.010	0.02	<0.1	0.01	0.3	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095160	Soil	4	<0.01	37	0.002	<1	0.30	0.007	0.02	<0.1	<0.01	0.4	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095161	Soil	4	0.01	48	0.002	<1	0.26	0.010	0.03	<0.1	0.02	0.5	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095162	Soil	10	0.09	380	0.006	2	0.59	0.008	0.04	<0.1	0.16	2.1	0.3	<0.05	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095163	Soil	8	0.03	97	0.004	3	0.37	0.005	0.03	<0.1	0.08	1.9	0.2	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095164	Soil	17	0.39	552	0.004	1	1.12	0.005	0.02	<0.1	0.34	3.8	<0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094785	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094786	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094787	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094788	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094789	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094790	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094791	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094792	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094793	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094794	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094795	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094796	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094797	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094798	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094799	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094800	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095151	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095152	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095153	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095154	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095155	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095156	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095157	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095158	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095159	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095160	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095161	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095162	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095163	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095164	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094785	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094786	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094787	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094788	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094789	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094790	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094791	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094792	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094793	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094794	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094795	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094796	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094797	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094798	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094799	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094800	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095151	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095152	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095153	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095154	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095155	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095156	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095157	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095158	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095159	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095160	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095161	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095162	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095163	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095164	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1095165	Soil	4.1	15.4	22.6	113	0.2	18.9	2.5	95	1.37	8.7	0.6	<0.1	6	0.3	2.0	0.1	31	0.04	0.065	3
1095166	Soil	53.6	45.9	32.0	144	1.5	49.1	3.4	61	1.85	22.3	0.7	0.3	26	0.6	11.7	0.3	99	0.03	0.084	7
1095167	Soil	2.3	11.3	7.9	31	0.2	5.9	1.4	31	0.49	4.3	<0.5	<0.1	5	0.1	1.0	<0.1	20	0.02	0.040	2
1095168	Soil	42.9	51.8	30.8	563	0.5	98.6	10.8	105	3.57	39.2	1.4	0.5	16	0.7	9.4	0.2	86	0.01	0.117	8
1095169	Soil	12.8	26.3	17.2	176	1.1	37.3	4.2	60	1.86	19.0	<0.5	0.1	11	0.4	3.9	0.2	95	0.02	0.080	10
1095170	Soil	2.0	7.0	3.6	22	1.3	4.7	0.9	14	0.32	3.0	0.7	<0.1	4	<0.1	0.6	<0.1	16	0.01	0.031	3
1095171	Soil	1.4	4.2	1.8	14	<0.1	3.3	0.8	13	0.29	2.6	<0.5	0.1	3	<0.1	0.4	<0.1	15	0.01	0.014	5
1095172	Soil	5.4	22.6	10.4	107	0.6	28.1	3.1	43	0.89	8.1	1.0	0.4	46	0.6	2.7	0.1	44	1.10	0.094	4
1095173	Soil	10.1	37.4	19.7	147	0.4	67.6	13.9	238	2.45	37.1	2.4	1.1	51	0.4	8.9	0.2	104	0.79	0.146	6
1095174	Soil	3.3	20.6	6.7	81	0.4	20.5	4.3	239	0.84	8.1	1.4	0.2	44	1.2	2.3	<0.1	33	1.48	0.122	4
1095175	Soil	9.6	33.7	14.0	114	0.2	84.6	8.2	440	1.94	44.1	1.4	0.3	42	1.2	4.5	0.1	98	0.89	0.098	4
1095176	Soil	2.9	12.5	5.5	69	0.4	18.5	2.0	44	0.63	5.8	0.7	0.1	25	0.4	1.6	<0.1	24	0.48	0.055	3
1095177	Soil	2.4	12.6	4.2	45	0.7	9.4	1.2	22	0.51	4.5	1.3	<0.1	28	0.6	1.1	<0.1	25	0.58	0.062	2
1095178	Soil	10.6	43.5	12.9	268	0.6	58.0	11.3	1126	1.89	19.1	3.6	1.3	66	5.3	5.2	0.2	77	0.45	0.114	8
1095179	Soil	14.6	38.5	15.7	244	0.6	46.8	7.3	98	2.33	25.4	2.2	1.4	43	1.6	6.0	0.2	80	0.21	0.100	10
1095180	Soil	11.6	29.2	15.8	137	1.3	30.4	4.6	70	1.88	18.7	4.6	0.6	25	1.0	4.0	0.2	89	0.07	0.095	6
1095181	Soil	16.6	35.4	17.8	235	0.5	44.3	9.3	207	2.39	28.3	6.2	0.7	31	1.1	6.3	0.2	99	0.09	0.107	9
1095182	Soil	13.6	34.4	14.8	172	0.9	33.7	4.8	67	1.92	22.9	2.9	0.3	20	0.9	4.9	0.2	89	0.05	0.083	7
1095183	Soil	9.4	24.4	11.0	103	0.5	18.1	3.1	54	1.39	19.4	1.7	0.2	19	0.6	3.9	0.3	81	0.03	0.070	7
1095184	Soil	10.5	34.9	14.7	169	0.4	30.1	4.9	82	2.22	31.1	3.4	1.0	33	0.9	6.1	0.3	82	0.09	0.115	11
1095185	Soil	11.6	50.3	13.1	265	0.6	45.6	6.8	121	2.64	32.7	3.7	2.9	60	2.5	7.4	0.2	91	0.23	0.147	13
1095186	Soil	11.0	48.9	18.1	171	2.8	38.9	12.0	86	2.58	21.6	6.0	0.3	33	1.5	4.6	0.3	119	0.07	0.221	7
1095187	Soil	8.0	50.2	16.4	362	0.8	72.0	10.3	183	2.54	17.1	2.6	1.8	88	2.8	4.6	0.2	89	0.90	0.154	9
1095188	Soil	10.8	18.0	12.3	234	0.2	33.9	5.5	109	2.40	15.7	1.4	0.4	17	0.8	3.2	0.2	96	0.05	0.109	9
1095189	Soil	13.5	28.1	11.2	404	0.7	62.0	6.5	244	1.79	14.9	2.7	0.8	47	3.1	3.4	0.2	93	0.60	0.107	7
1095190	Soil	30.2	65.8	20.6	725	0.5	133.9	9.1	171	2.57	28.1	4.7	1.6	59	4.2	8.9	0.2	171	0.31	0.176	14
1095191	Soil	18.7	40.3	16.9	499	0.4	83.9	8.7	127	2.77	23.5	3.1	0.6	26	1.6	5.9	0.2	135	0.13	0.115	10
1095192	Soil	19.3	28.5	9.3	387	2.7	55.4	4.0	36	1.93	17.4	3.3	0.1	16	1.1	4.9	0.1	96	0.06	0.056	5
1095193	Soil	28.3	70.7	20.8	1085	1.2	187.8	20.5	429	3.89	35.5	3.8	2.0	51	7.7	11.4	0.2	136	0.41	0.204	9
1095194	Soil	24.2	64.6	20.6	538	1.0	113.0	13.6	328	3.34	42.6	2.0	2.0	89	3.5	11.0	0.2	114	1.27	0.194	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1095165	Soil	7	0.02	58	0.002	2	0.25	0.006	0.03	<0.1	0.02	0.4	<0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095166	Soil	14	0.01	158	0.002	2	0.24	0.002	0.05	0.3	0.04	0.7	1.1	<0.05	2	2.3	0.2	N.A.	N.A.	N.A.	N.A.
1095167	Soil	4	<0.01	33	0.002	<1	0.19	0.010	0.02	<0.1	0.01	0.3	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095168	Soil	10	0.02	114	0.002	1	0.32	0.002	0.04	0.2	0.07	1.1	0.2	<0.05	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1095169	Soil	14	0.03	107	0.003	2	0.40	0.003	0.04	0.1	0.04	0.4	0.2	<0.05	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095170	Soil	3	<0.01	45	0.002	1	0.17	0.009	0.02	<0.1	0.01	0.3	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095171	Soil	3	<0.01	42	0.004	<1	0.15	0.010	0.02	<0.1	0.01	0.3	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095172	Soil	15	0.07	523	0.005	3	0.48	0.008	0.03	<0.1	0.08	1.2	0.2	0.14	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095173	Soil	32	0.08	562	0.004	2	0.61	0.005	0.03	0.1	0.13	4.4	0.2	0.06	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095174	Soil	8	0.07	605	0.004	2	0.57	0.011	0.02	<0.1	0.09	0.9	<0.1	0.14	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095175	Soil	19	0.05	776	0.003	2	0.77	0.010	0.03	<0.1	0.13	1.8	0.3	0.11	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095176	Soil	6	0.04	387	0.005	1	0.30	0.014	0.02	<0.1	0.08	0.7	<0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1095177	Soil	5	0.05	609	0.004	1	0.36	0.017	0.02	<0.1	0.08	0.5	<0.1	0.07	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1095178	Soil	18	0.08	2039	0.005	2	0.60	0.007	0.06	0.1	0.31	3.0	0.2	0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095179	Soil	13	0.09	2112	0.004	2	0.34	0.003	0.05	0.1	0.13	2.0	0.3	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1095180	Soil	14	0.06	1250	0.002	2	0.59	0.005	0.05	0.1	0.31	1.6	0.3	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095181	Soil	15	0.06	1736	0.003	2	0.43	0.002	0.05	0.1	0.12	1.5	0.3	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095182	Soil	13	0.03	929	0.002	1	0.39	0.003	0.05	0.1	0.18	0.9	0.2	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095183	Soil	11	0.03	439	0.002	2	0.40	0.006	0.05	<0.1	0.09	0.4	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095184	Soil	12	0.05	1665	0.003	2	0.43	0.002	0.06	<0.1	0.08	1.4	0.2	0.07	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1095185	Soil	14	0.07	1961	0.010	2	0.35	0.003	0.06	<0.1	0.19	2.5	0.2	0.06	1	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095186	Soil	21	0.07	1362	0.002	4	1.07	0.006	0.12	<0.1	0.42	1.5	0.4	0.11	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095187	Soil	23	0.16	1235	0.004	3	0.66	0.006	0.07	<0.1	0.27	3.4	0.2	0.08	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095188	Soil	19	0.06	300	0.002	1	0.71	0.003	0.07	<0.1	0.08	0.9	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095189	Soil	16	0.14	490	0.003	2	0.67	0.009	0.06	<0.1	0.23	1.9	0.4	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1095190	Soil	26	0.10	420	0.006	2	0.65	0.003	0.08	0.1	0.39	3.2	0.5	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1095191	Soil	24	0.07	325	0.003	2	0.70	0.004	0.07	0.1	0.11	1.5	0.4	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095192	Soil	11	0.03	293	0.004	1	0.60	0.014	0.03	<0.1	0.13	0.6	0.3	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095193	Soil	22	0.07	1018	0.004	2	0.70	0.003	0.06	0.1	0.42	3.9	0.7	<0.05	1	15.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095194	Soil	20	0.49	1318	0.004	3	0.54	0.004	0.07	<0.1	0.40	3.6	0.5	0.08	1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1095165	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095174	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095175	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095176	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095178	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095180	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1095165	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095174	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095175	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095176	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095178	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095180	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1095195	Soil	24.0	59.4	18.8	959	0.9	121.9	12.1	219	3.08	36.7	1.8	1.5	83	4.6	10.4	0.2	119	1.07	0.198	9
1095196	Soil	19.7	73.4	17.0	2410	0.8	166.2	14.9	176	3.17	28.7	1.1	2.4	82	16.6	9.2	0.2	95	0.88	0.161	10
1095197	Soil	10.5	45.8	11.7	579	0.7	62.9	6.3	102	1.97	17.3	2.8	0.8	59	3.6	4.8	0.2	57	0.88	0.089	4
1095198	Soil	19.9	86.8	17.0	1697	0.9	129.4	9.5	132	2.91	29.6	1.4	1.7	56	6.5	8.3	0.2	88	0.39	0.118	9
1095199	Soil	29.2	130.5	21.4	1840	1.1	171.0	19.1	240	4.03	38.7	1.9	3.7	75	11.3	11.1	0.2	116	0.51	0.166	13
1095200	Soil	31.9	59.8	9.8	2228	0.8	190.2	14.7	150	2.49	19.1	4.2	1.1	55	15.7	8.4	0.2	74	0.62	0.119	5
1095201	Soil	24.6	32.5	16.4	187	0.2	62.6	7.2	141	2.48	19.4	1.4	<0.1	16	0.3	6.1	0.2	101	0.04	0.097	7
1095202	Soil	6.1	30.6	17.9	86	0.3	34.7	7.5	137	2.95	12.4	2.8	0.2	15	0.2	3.4	0.2	40	0.02	0.096	8
1095203	Soil	7.3	43.4	19.4	65	0.6	51.5	11.0	132	2.88	10.9	3.2	0.2	65	0.2	3.4	0.3	32	0.32	0.115	6
1095204	Soil	18.6	15.8	11.4	91	0.2	30.1	4.2	44	1.17	15.8	0.6	<0.1	7	<0.1	6.0	0.1	54	0.01	0.049	6
1095205	Soil	7.6	28.4	13.8	85	0.1	40.6	8.4	81	1.90	12.8	<0.5	0.2	9	<0.1	3.7	0.2	46	<0.01	0.043	16
1095206	Soil	58.2	88.7	20.0	516	4.8	179.5	11.5	98	3.59	56.6	2.3	0.4	25	1.3	12.5	0.2	157	0.03	0.190	13
1095207	Soil	10.2	66.4	24.1	241	0.2	119.1	25.1	480	7.36	45.2	3.5	0.4	8	0.5	7.0	0.2	91	0.04	0.263	12
1095208	Soil	15.0	265.3	27.1	765	1.0	87.5	24.2	395	5.19	48.9	19.2	1.8	14	1.6	9.0	0.3	50	0.27	0.276	14
1095209	Soil	14.5	176.5	28.1	285	2.1	145.0	26.9	771	7.27	134.6	12.0	2.5	55	1.4	8.1	0.2	69	1.06	0.371	21
1095210	Soil	13.6	111.5	24.2	340	1.8	148.3	33.7	453	6.84	43.4	3.4	1.8	79	2.2	6.2	0.2	77	1.02	0.400	31
1095211	Soil	3.5	23.4	6.4	60	1.7	13.0	2.3	25	0.83	6.2	2.2	<0.1	8	0.2	1.7	<0.1	18	0.09	0.104	4
1095212	Soil	14.5	147.5	19.2	288	1.8	50.6	7.6	106	2.77	34.2	9.5	0.3	20	1.0	6.8	0.2	53	0.28	0.213	9
1095213	Soil	6.4	100.1	14.3	266	1.9	60.2	20.2	696	2.96	21.5	10.2	1.4	43	2.4	4.3	0.2	35	1.23	0.232	18
1095214	Soil	4.8	25.0	5.6	87	0.6	13.6	3.8	59	0.86	6.4	1.2	0.1	11	0.5	2.0	<0.1	19	0.16	0.080	6
1095215	Soil	14.4	87.7	24.8	343	0.8	59.1	11.1	199	3.19	29.6	7.3	1.4	31	0.8	7.3	0.2	55	0.55	0.220	10
1095216	Soil	13.2	83.0	21.0	280	1.3	54.0	10.8	429	2.84	29.4	5.3	0.8	41	2.0	6.7	0.2	63	0.57	0.260	11
1095217	Soil	7.3	57.5	15.0	202	0.9	42.1	7.7	254	2.75	33.6	6.4	0.8	37	0.7	5.5	0.2	61	0.65	0.249	10
1095218	Soil	11.5	121.2	22.0	339	1.2	79.1	10.7	209	3.84	42.3	8.3	1.9	39	2.3	9.5	0.2	65	0.65	0.247	15
1095219	Soil	6.8	40.2	12.0	148	0.2	38.5	6.0	115	2.26	20.0	3.0	0.2	25	0.5	4.1	0.2	41	0.46	0.145	7
1095220	Soil	42.2	69.6	17.5	725	0.9	159.6	13.1	496	3.21	26.5	3.6	1.5	143	4.8	9.1	0.2	130	4.63	0.194	8
1095221	Soil	7.7	27.5	16.0	89	1.1	24.9	6.7	485	3.22	45.3	5.1	0.4	50	0.6	4.7	0.6	58	0.40	0.075	9
1095222	Soil	5.9	12.0	16.8	35	1.4	8.5	1.1	21	0.97	18.5	7.1	0.2	27	0.1	2.3	0.5	42	0.03	0.050	4
1095223	Soil	2.2	7.6	5.8	12	0.8	3.3	0.5	10	0.35	5.4	2.0	0.2	8	<0.1	0.9	0.1	17	0.03	0.039	5
1095224	Soil	4.9	14.4	11.0	28	0.8	5.6	0.9	24	0.68	12.8	2.5	0.4	20	0.1	1.7	0.3	37	0.03	0.040	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1095195	Soil	29	0.21	1422	0.003	5	0.57	0.005	0.06	0.1	0.36	3.1	0.5	0.08	1	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1095196	Soil	19	0.16	1575	0.006	5	1.01	0.007	0.07	0.1	0.34	2.9	1.0	<0.05	2	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095197	Soil	12	0.14	837	0.005	4	0.71	0.021	0.06	<0.1	0.23	1.6	0.3	0.08	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095198	Soil	17	0.13	1657	0.006	2	1.00	0.012	0.07	<0.1	0.35	2.7	0.4	<0.05	2	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095199	Soil	23	0.17	2278	0.008	4	1.16	0.005	0.10	0.1	0.45	3.9	0.5	0.05	2	6.8	<0.2	N.A.	N.A.	N.A.	N.A.
1095200	Soil	14	0.11	607	0.004	2	1.22	0.017	0.04	<0.1	0.29	2.2	1.4	<0.05	1	6.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095201	Soil	15	0.03	285	0.002	<1	0.33	0.004	0.05	<0.1	0.02	0.2	0.3	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095202	Soil	13	0.06	835	0.003	1	0.55	0.006	0.05	<0.1	0.05	0.4	0.2	0.08	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095203	Soil	73	0.09	891	0.002	2	0.42	0.008	0.07	0.2	0.04	0.4	0.2	0.08	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095204	Soil	6	0.02	88	0.002	1	0.35	0.008	0.04	<0.1	0.01	0.2	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095205	Soil	8	0.02	85	0.002	1	0.25	0.004	0.04	<0.1	<0.01	0.4	0.1	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095206	Soil	27	0.03	112	0.004	3	0.48	0.004	0.07	0.2	0.16	1.1	0.9	0.06	2	4.0	0.2	N.A.	N.A.	N.A.	N.A.
1095207	Soil	36	0.05	183	0.004	<1	0.72	0.004	0.05	<0.1	0.02	1.9	0.3	<0.05	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095208	Soil	13	0.05	282	0.002	2	0.53	0.002	0.10	<0.1	0.17	4.1	0.2	<0.05	2	5.8	<0.2	N.A.	N.A.	N.A.	N.A.
1095209	Soil	70	0.15	2143	0.005	3	0.73	0.006	0.08	0.2	0.34	9.3	0.2	<0.05	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1095210	Soil	33	0.10	2890	0.005	4	0.68	0.009	0.07	<0.1	0.33	7.9	0.2	0.09	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095211	Soil	6	0.03	221	0.002	1	0.30	0.016	0.04	<0.1	0.13	0.2	<0.1	0.08	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1095212	Soil	12	0.05	554	0.003	2	0.46	0.005	0.09	<0.1	0.23	1.3	0.2	0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095213	Soil	12	0.07	1137	0.005	3	0.63	0.008	0.06	<0.1	0.43	5.0	0.2	0.10	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095214	Soil	5	0.03	243	0.002	<1	0.26	0.011	0.03	<0.1	0.05	0.4	<0.1	0.07	1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095215	Soil	14	0.07	809	0.003	2	0.59	0.002	0.10	<0.1	0.21	2.6	0.2	0.08	2	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1095216	Soil	15	0.07	574	0.004	3	0.71	0.007	0.12	<0.1	0.34	2.4	0.3	0.08	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1095217	Soil	16	0.10	787	0.005	2	0.77	0.009	0.09	<0.1	0.22	2.3	0.3	0.09	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1095218	Soil	16	0.09	1563	0.005	3	0.67	0.007	0.10	<0.1	0.27	4.0	0.3	0.07	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095219	Soil	9	0.08	482	0.002	2	0.54	0.007	0.05	0.1	0.03	0.5	0.2	0.16	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095220	Soil	17	1.95	1204	0.002	5	0.37	0.005	0.06	<0.1	0.36	2.8	0.6	0.17	<1	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095221	Soil	10	0.06	1965	0.003	3	0.48	0.004	0.07	0.1	0.11	0.7	0.4	0.19	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1095222	Soil	9	0.03	1131	0.002	4	0.54	0.013	0.10	<0.1	0.27	0.4	0.4	0.11	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095223	Soil	4	0.01	401	0.004	3	0.24	0.011	0.04	<0.1	0.09	0.3	0.2	0.27	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095224	Soil	7	0.02	1563	0.002	3	0.39	0.006	0.06	<0.1	0.15	0.4	0.3	0.14	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1095195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095218	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095222	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095224	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1095195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095218	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095222	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095224	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1095225	Soil	6.4	14.3	12.0	50	0.8	9.1	1.7	37	1.23	19.9	3.2	0.4	26	0.1	3.3	0.3	47	0.02	0.040	11
1095226	Soil	2.0	13.3	9.4	21	0.7	6.0	0.6	14	0.58	7.1	4.4	<0.1	15	0.2	0.9	0.2	22	0.05	0.045	3
1095227	Soil	5.8	66.4	42.3	197	2.5	74.7	4.2	458	2.55	45.1	18.0	0.7	69	0.8	4.4	0.4	44	0.32	0.092	8
1095228	Soil	3.9	9.9	10.9	39	0.5	6.4	1.1	25	0.87	16.5	2.3	0.5	16	0.1	2.4	0.2	37	0.01	0.033	13
1095229	Soil	7.2	15.7	17.1	74	0.4	11.1	2.0	32	1.77	34.2	3.8	0.8	17	0.1	4.4	0.4	84	0.01	0.040	15
1095230	Soil	5.1	11.8	13.0	46	0.6	7.6	1.0	19	1.13	29.2	2.1	0.2	19	0.1	2.8	0.2	45	0.02	0.053	7
1095231	Soil	8.9	13.7	20.0	50	0.2	8.8	1.6	28	1.60	50.9	1.7	0.2	13	<0.1	3.7	0.3	108	0.02	0.041	13
1095232	Soil	5.2	5.3	15.1	10	1.0	1.6	0.7	49	0.81	11.2	15.5	<0.1	13	<0.1	1.8	0.1	19	0.02	0.041	6
1095233	Soil	20.8	14.4	22.2	69	1.8	21.3	1.6	73	2.44	49.7	11.1	0.4	25	0.3	7.3	0.2	96	0.11	0.142	12
1095234	Soil	18.6	16.7	38.6	39	1.6	29.5	0.7	14	1.37	62.9	24.8	0.3	30	0.3	6.1	0.4	93	0.17	0.127	11
1095235	Soil	6.8	4.8	9.6	8	1.7	1.9	0.2	6	0.60	18.8	8.8	<0.1	10	<0.1	2.5	0.1	32	0.02	0.072	5
1095236	Soil	15.4	10.0	19.9	23	1.5	6.1	0.6	20	1.10	22.3	12.9	0.3	30	<0.1	7.5	0.2	51	0.03	0.078	14
1095237	Soil	11.9	14.5	26.3	26	2.2	5.8	0.8	16	1.27	19.3	15.3	0.2	34	<0.1	7.0	0.2	59	0.03	0.106	9
1095238	Soil	3.9	9.2	16.0	15	1.8	4.8	0.7	9	0.73	8.6	3.5	<0.1	13	0.1	1.3	0.1	22	0.02	0.084	3
1095239	Soil	6.0	9.6	27.9	30	1.6	6.8	1.1	16	1.01	13.2	3.0	<0.1	21	0.2	2.9	0.2	43	0.03	0.122	12
1095240	Soil	8.8	10.0	6.3	43	0.3	8.0	2.1	31	1.16	9.8	0.7	<0.1	7	0.2	3.5	<0.1	39	0.01	0.036	9
1095241	Soil	16.1	12.9	3.7	26	0.4	5.8	1.3	23	0.86	8.2	1.9	<0.1	6	<0.1	4.4	0.1	61	0.02	0.026	14
1095242	Soil	6.4	10.0	12.6	51	0.3	6.9	1.8	53	1.05	6.3	1.6	<0.1	12	<0.1	1.7	0.2	52	0.02	0.061	8
1095243	Soil	1.9	41.4	10.8	105	0.8	26.9	6.7	303	1.94	6.0	7.1	0.8	147	0.5	0.9	0.2	47	1.58	0.085	6
1095244	Soil	2.9	61.0	11.6	133	0.8	42.4	6.8	336	2.15	7.0	7.9	0.7	181	0.6	1.3	0.2	38	1.61	0.086	6
1095245	Soil	4.5	17.6	10.4	69	0.1	16.0	3.5	96	2.02	11.8	3.4	1.1	7	0.2	1.6	0.2	54	0.02	0.034	8
1095246	Soil	3.6	34.9	9.6	155	0.8	40.5	6.7	188	2.54	11.2	6.2	1.6	80	0.7	1.9	0.2	32	0.91	0.064	12
1095247	Soil	5.3	62.8	18.7	135	0.2	30.4	8.9	312	3.42	15.7	6.9	1.7	15	0.2	1.9	0.2	68	0.07	0.080	8
1095248	Soil	3.8	30.5	9.7	55	0.4	15.1	3.1	91	1.26	7.2	2.9	0.3	12	0.3	0.9	0.1	49	0.05	0.057	9
1095249	Soil	3.9	16.0	10.9	62	0.2	16.3	3.5	111	2.21	11.1	2.3	1.3	7	0.2	1.3	0.2	55	0.02	0.036	8
1095250	Soil	3.8	15.4	11.4	52	<0.1	12.4	2.5	67	1.60	9.5	1.5	0.5	8	0.2	1.1	0.2	54	0.02	0.045	11
1095251	Soil	4.0	13.5	11.5	55	0.2	13.9	3.3	139	1.77	9.8	1.7	0.8	8	0.1	1.1	0.2	62	0.02	0.034	10
1095252	Soil	5.9	39.1	15.6	127	0.4	35.6	5.8	202	2.89	17.6	6.0	2.0	28	0.3	2.3	0.2	58	0.14	0.091	8
1095253	Soil	5.2	22.0	20.2	51	1.7	16.1	3.5	127	2.56	22.0	4.7	1.0	66	0.1	8.3	0.2	62	0.08	0.092	12
1095254	Soil	5.2	17.9	22.3	38	1.7	9.7	2.2	80	2.43	16.7	4.7	0.2	42	<0.1	7.0	0.2	75	0.04	0.073	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1095225	Soil	8	0.03	1966	0.003	3	0.29	0.003	0.05	<0.1	0.10	0.5	0.3	0.14	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095226	Soil	5	0.02	500	0.002	2	0.39	0.020	0.06	<0.1	0.17	0.4	0.3	0.07	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1095227	Soil	12	0.12	1387	0.002	5	0.97	0.015	0.12	<0.1	0.63	1.9	0.6	0.16	3	8.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095228	Soil	6	0.01	2075	0.002	2	0.25	0.003	0.05	<0.1	0.06	0.4	0.2	0.10	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1095229	Soil	10	0.02	1056	0.004	3	0.45	0.002	0.08	0.1	0.04	0.7	0.4	0.07	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095230	Soil	7	0.01	279	0.003	2	0.31	0.009	0.07	<0.1	0.04	0.4	0.4	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095231	Soil	7	0.02	179	0.007	2	0.37	0.003	0.05	0.2	0.02	0.3	0.4	<0.05	5	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095232	Soil	3	<0.01	153	0.003	1	0.17	0.016	0.03	<0.1	0.07	<0.1	0.6	<0.05	<1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095233	Soil	10	0.03	1816	0.002	3	0.45	0.003	0.06	0.1	1.90	0.6	1.3	0.11	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095234	Soil	9	0.04	1524	0.001	4	0.55	0.004	0.09	0.2	3.85	0.7	2.6	0.14	2	7.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095235	Soil	4	0.01	202	0.002	2	0.28	0.018	0.05	<0.1	0.95	<0.1	0.5	<0.05	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095236	Soil	5	0.01	605	<0.001	2	0.25	0.003	0.09	0.1	1.48	0.3	1.1	0.13	1	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095237	Soil	10	0.02	527	<0.001	2	0.37	0.006	0.09	<0.1	3.29	0.2	1.2	0.12	2	5.8	<0.2	N.A.	N.A.	N.A.	N.A.
1095238	Soil	5	0.01	258	0.001	1	0.42	0.021	0.05	<0.1	0.28	0.2	0.5	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095239	Soil	9	0.02	506	<0.001	3	0.48	0.008	0.08	<0.1	0.27	0.2	0.7	<0.05	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095240	Soil	5	0.01	96	0.003	1	0.21	0.007	0.04	<0.1	0.04	0.2	0.3	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095241	Soil	7	0.01	92	0.003	2	0.27	0.005	0.04	<0.1	0.02	<0.1	0.4	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095242	Soil	9	0.03	220	0.003	1	0.57	0.008	0.06	<0.1	0.04	0.2	0.4	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095243	Soil	21	0.32	687	0.003	5	1.17	0.008	0.09	<0.1	0.37	2.1	0.2	0.18	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1095244	Soil	21	0.37	726	0.003	5	1.28	0.009	0.08	<0.1	0.33	2.0	0.2	0.21	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1095245	Soil	13	0.10	137	0.003	1	0.74	0.006	0.05	0.1	0.04	0.9	0.2	0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095246	Soil	18	0.25	1066	0.002	2	0.97	0.006	0.06	0.1	0.30	3.0	0.1	0.12	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1095247	Soil	24	0.25	219	0.002	3	1.23	0.004	0.09	0.1	0.12	2.0	0.3	0.06	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095248	Soil	12	0.07	660	0.003	2	0.86	0.007	0.06	<0.1	0.09	0.6	0.2	<0.05	4	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095249	Soil	17	0.12	170	0.003	2	0.98	0.005	0.06	0.1	0.07	1.0	0.2	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095250	Soil	12	0.07	179	0.004	2	0.67	0.004	0.05	0.1	0.03	0.5	0.2	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095251	Soil	15	0.09	201	0.004	2	0.93	0.004	0.05	0.1	0.04	0.8	0.2	<0.05	5	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095252	Soil	23	0.27	1520	0.002	2	1.04	0.004	0.08	0.1	0.20	1.8	0.2	0.08	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095253	Soil	21	0.19	700	0.016	2	0.70	0.009	0.11	0.2	0.37	1.0	0.5	0.21	4	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095254	Soil	17	0.08	539	0.010	1	0.57	0.006	0.08	0.2	0.21	0.3	0.4	0.18	4	3.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1095225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095226	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095227	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095231	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095232	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095233	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095234	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095235	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095236	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095237	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095238	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095239	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095240	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095241	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095242	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095243	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095244	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095245	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095247	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095249	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095250	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095254	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1095225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095226	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095227	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095231	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095232	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095233	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095234	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095235	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095236	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095237	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095238	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095239	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095240	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095241	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095242	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095243	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095244	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095245	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095247	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095249	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095250	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095254	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1095255	Soil	4.2	20.0	20.5	38	1.6	10.1	2.5	78	2.41	17.5	14.0	0.3	45	<0.1	6.6	0.2	57	0.04	0.089	8
1095256	Soil	15.2	31.8	14.0	41	1.7	11.2	1.1	21	1.44	14.9	3.7	0.3	36	<0.1	5.8	0.2	109	0.02	0.095	13
1095257	Soil	5.4	9.4	12.7	19	0.8	4.5	0.9	20	0.95	7.1	1.0	<0.1	23	<0.1	4.5	0.1	47	0.02	0.046	6
1095258	Soil	7.7	14.6	21.1	27	1.6	6.0	1.2	31	1.48	15.9	4.8	0.1	40	<0.1	7.0	0.2	71	0.02	0.065	8
1095259	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1095260	Soil	4.3	32.6	19.6	116	0.2	31.5	11.6	132	3.20	13.3	2.2	0.2	10	0.1	1.8	0.3	32	0.02	0.077	4
1095261	Soil	3.7	7.2	5.0	21	0.1	7.8	1.3	19	0.59	4.0	<0.5	<0.1	7	0.1	0.7	0.1	30	0.01	0.037	6
1095262	Soil	45.7	75.9	42.2	58	2.3	19.2	1.8	25	3.23	59.8	12.1	0.3	65	0.3	13.5	0.3	174	0.04	0.239	19
1095263	Soil	7.6	8.4	8.1	25	0.8	7.5	1.6	90	0.77	19.7	3.0	<0.1	15	0.2	1.3	0.1	37	0.03	0.119	6
1095264	Soil	15.0	8.6	15.9	26	0.6	7.2	0.9	23	0.81	13.1	2.5	0.1	15	<0.1	3.2	0.2	63	<0.01	0.041	13
1095265	Soil	14.0	8.7	8.9	32	0.2	9.0	1.3	17	0.69	8.1	1.7	<0.1	13	<0.1	2.7	0.2	93	0.01	0.037	20
1095266	Soil	7.7	9.9	15.9	58	0.3	11.6	1.8	33	1.35	15.2	<0.5	<0.1	19	<0.1	2.4	0.2	81	0.02	0.044	13
1095267	Soil	14.4	13.6	24.0	18	0.3	5.2	0.5	11	1.24	21.0	3.8	1.1	54	0.1	2.4	0.3	37	0.01	0.038	23
1095268	Soil	6.2	10.1	14.7	37	0.6	9.1	1.5	24	1.00	59.7	<0.5	<0.1	28	<0.1	4.5	0.2	63	0.01	0.040	15
1095269	Soil	13.8	19.3	19.8	76	0.2	19.2	2.7	46	1.74	59.2	0.7	0.1	38	<0.1	3.9	0.3	126	0.02	0.075	11
1095270	Soil	15.2	15.0	14.8	100	0.2	26.5	2.7	35	1.17	26.7	3.0	0.1	16	0.1	3.6	0.2	82	0.02	0.058	13
1095271	Soil	29.4	35.7	20.9	508	0.3	72.8	4.9	42	2.27	39.6	0.9	0.8	3	0.5	14.2	0.2	67	0.03	0.092	9
1095272	Soil	32.8	56.2	16.6	607	0.8	98.2	7.5	59	3.01	31.5	3.2	1.2	9	0.9	14.6	0.2	113	0.12	0.171	11
1095273	Soil	43.0	70.7	22.9	306	0.4	94.0	9.2	91	3.45	48.3	6.6	0.5	21	0.8	9.1	0.2	213	0.03	0.134	13
1095274	Soil	16.6	64.3	15.1	191	0.2	40.1	7.1	31	2.17	18.7	<0.5	<0.1	6	0.3	4.8	0.2	76	0.02	0.093	7
1095275	Soil	17.3	66.4	20.9	345	0.8	96.6	15.5	492	4.89	34.8	5.1	0.8	22	2.2	6.0	0.3	93	0.15	0.198	16
1095276	Soil	22.0	36.7	11.7	218	0.3	62.5	4.5	55	1.85	29.6	<0.5	<0.1	9	1.2	5.6	0.1	113	0.04	0.129	8
1095277	Soil	11.2	58.1	23.8	285	0.6	87.3	15.0	211	5.71	31.1	5.1	1.3	19	0.9	4.1	0.3	88	0.07	0.168	14
1095278	Soil	6.3	21.2	10.2	149	0.2	41.3	5.7	57	1.64	14.3	1.3	0.1	5	0.2	1.8	0.1	32	0.02	0.075	9
1095279	Soil	5.7	10.7	4.1	53	0.1	16.6	2.2	119	0.67	5.1	<0.5	<0.1	12	0.7	1.2	<0.1	21	0.18	0.096	3
1095281	Soil	1.9	22.6	5.6	71	0.2	27.0	4.0	87	0.96	7.4	2.7	0.1	21	0.7	1.2	<0.1	19	0.47	0.108	5
1095282	Soil	19.9	134.4	26.8	418	1.7	87.7	14.8	312	3.50	38.2	9.1	1.9	54	3.2	10.9	0.3	52	0.87	0.438	16
1095283	Soil	1.5	31.7	3.4	53	0.7	17.5	1.9	92	0.37	2.8	1.9	<0.1	25	1.1	0.9	<0.1	7	0.53	0.080	4
1095284	Soil	3.6	25.0	8.2	135	0.5	30.5	4.3	81	1.20	6.0	1.2	0.4	27	0.5	1.4	0.1	32	0.47	0.144	8
1095285	Soil	0.9	12.3	5.2	29	0.4	10.4	2.0	56	0.54	2.1	<0.5	<0.1	20	0.4	0.5	<0.1	12	0.45	0.145	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1095255	Soil	18	0.10	534	0.012	2	0.67	0.008	0.07	0.2	0.21	0.6	0.3	0.11	4	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095256	Soil	14	0.03	743	0.005	2	0.69	0.008	0.06	0.2	0.27	0.6	1.1	0.16	3	8.2	<0.2	N.A.	N.A.	N.A.	N.A.
1095257	Soil	8	0.02	575	0.004	2	0.27	0.013	0.04	<0.1	0.06	<0.1	0.2	<0.05	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1095258	Soil	13	0.02	630	0.006	2	0.31	0.008	0.07	0.2	0.10	0.3	0.4	0.10	4	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095259	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.6	29.5	22.2	138
1095260	Soil	19	0.04	140	0.002	<1	0.45	0.004	0.04	<0.1	0.04	1.2	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095261	Soil	10	0.01	76	0.004	2	0.28	0.010	0.02	<0.1	0.03	<0.1	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095262	Soil	33	0.02	548	0.003	4	0.52	0.005	0.13	0.1	0.89	0.3	2.1	0.14	5	6.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095263	Soil	13	0.03	263	0.002	1	0.59	0.013	0.03	<0.1	0.14	<0.1	0.5	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095264	Soil	9	<0.01	204	0.004	2	0.33	0.006	0.05	<0.1	0.02	0.3	0.5	0.05	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1095265	Soil	12	0.01	127	0.004	2	0.25	0.004	0.03	0.1	0.02	0.1	0.3	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095266	Soil	15	0.02	237	0.008	1	0.47	0.007	0.04	0.1	0.02	0.2	0.2	<0.05	5	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095267	Soil	8	0.01	288	0.002	2	0.27	0.002	0.11	<0.1	0.21	0.5	0.6	0.21	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095268	Soil	10	0.02	196	0.005	1	0.57	0.007	0.05	<0.1	0.03	0.3	0.3	<0.05	4	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095269	Soil	19	0.03	229	0.003	1	0.55	0.004	0.07	0.1	0.02	0.3	0.4	0.09	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095270	Soil	15	0.03	113	0.003	2	0.42	0.004	0.05	<0.1	0.04	0.3	0.4	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1095271	Soil	9	<0.01	39	0.002	1	0.21	0.002	0.03	<0.1	0.21	0.5	0.4	<0.05	<1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095272	Soil	15	0.02	72	0.002	2	0.33	0.002	0.05	<0.1	0.18	1.2	0.4	<0.05	<1	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1095273	Soil	26	0.03	127	0.004	2	0.46	0.003	0.06	0.1	0.12	0.8	0.6	<0.05	3	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095274	Soil	12	0.02	74	<0.001	2	0.30	0.005	0.05	<0.1	0.03	0.1	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095275	Soil	30	0.08	937	0.004	2	0.71	0.004	0.08	<0.1	0.16	2.1	0.4	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095276	Soil	14	0.02	138	<0.001	2	0.36	0.008	0.04	<0.1	0.14	0.2	0.3	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1095277	Soil	15	0.05	1524	0.004	2	0.76	0.002	0.06	<0.1	0.13	1.9	0.2	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095278	Soil	6	0.02	118	0.001	2	0.38	0.009	0.05	<0.1	0.02	<0.1	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095279	Soil	9	0.03	124	0.002	2	0.44	0.020	0.03	<0.1	0.02	<0.1	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095281	Soil	9	0.07	266	0.007	2	0.87	0.023	0.03	<0.1	0.05	0.6	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095282	Soil	15	0.01	1858	0.005	5	0.42	0.004	0.11	<0.1	0.33	3.6	0.3	0.13	<1	5.8	0.2	N.A.	N.A.	N.A.	N.A.
1095283	Soil	4	0.08	237	0.009	2	0.69	0.032	0.02	<0.1	0.18	0.8	<0.1	<0.05	<1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1095284	Soil	16	0.13	193	0.005	2	0.84	0.016	0.06	<0.1	0.08	1.0	0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095285	Soil	5	0.08	134	0.007	1	0.58	0.026	0.02	<0.1	0.05	0.4	<0.1	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1095255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095258	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095259	Soil	0.5	36.0	12.8	373	2.45	16.0	2.3	0.2	17	0.4	1.8	0.2	36	0.05	0.088	4	17	0.06	615	0.002
1095260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095271	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095272	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095273	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095274	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095275	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095276	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095277	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095278	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095279	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095281	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095282	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095283	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095284	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1095255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095258	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095259	Soil	<20	0.46	0.010	0.05	0.1	0.05	0.6	0.4	0.09	2	1.5	<0.2
1095260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095271	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095272	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095273	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095274	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095275	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095276	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095277	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095278	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095279	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095281	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095282	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095283	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095284	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1095286	Soil	33.2	126.0	26.8	461	2.1	224.6	25.1	517	4.91	50.3	2.6	1.4	69	3.7	12.6	0.2	157	0.62	0.302	19
1095287	Soil	30.4	130.2	26.5	459	2.4	213.8	21.9	385	4.64	85.3	5.5	1.5	59	3.7	12.8	0.2	131	0.62	0.308	16
1095288	Soil	21.4	53.8	26.7	245	0.6	84.4	8.6	116	2.34	24.2	2.0	<0.1	24	1.2	5.6	0.2	66	0.22	0.252	10
1095289	Soil	21.8	105.8	28.3	457	1.5	164.5	10.6	231	3.09	28.2	1.5	0.7	65	3.4	7.7	0.2	98	0.79	0.305	11
1095290	Soil	31.5	86.3	25.3	348	0.9	128.8	14.4	314	3.51	30.9	0.8	3.6	112	2.7	12.7	0.2	95	3.35	0.185	7
1095291	Soil	38.1	80.0	26.5	451	1.1	138.7	12.6	278	3.49	32.0	0.9	2.2	63	2.6	15.2	0.2	100	1.22	0.168	7
1095292	Soil	36.1	73.6	23.4	452	0.8	125.2	12.9	321	3.13	24.9	2.8	2.6	83	3.4	16.0	0.2	116	1.89	0.140	5
1095293	Soil	33.3	61.9	22.3	352	0.8	112.2	10.0	229	2.86	20.7	2.8	1.6	69	2.9	8.2	0.2	90	1.42	0.135	4
1095294	Soil	31.1	78.8	23.8	320	1.1	120.5	12.4	311	3.35	20.3	2.6	2.9	100	2.7	7.6	0.2	83	2.15	0.147	5
1095295	Soil	55.7	59.5	18.9	441	0.5	139.4	11.1	333	2.75	23.4	2.1	2.9	143	4.7	7.8	0.1	103	5.47	0.123	3
1095296	Soil	36.4	124.7	58.5	468	1.8	160.7	16.7	335	3.74	29.4	6.4	4.4	79	2.0	17.4	0.4	111	0.74	0.285	11
1095297	Soil	41.5	85.5	31.7	481	1.0	145.7	11.3	229	3.93	27.9	7.2	1.8	32	3.2	16.5	0.3	95	0.30	0.086	7
1095298	Soil	12.3	84.0	20.9	230	1.7	92.3	11.3	282	3.19	15.3	3.0	1.9	76	1.0	5.5	0.3	46	0.67	0.097	5
1095299	Soil	66.4	60.8	14.9	604	0.4	173.7	11.4	335	2.68	24.0	1.3	3.0	129	6.1	9.1	0.1	128	5.98	0.072	3
1095300	Soil	62.0	55.9	12.5	418	0.2	157.7	9.7	303	2.52	20.2	1.3	3.1	173	4.8	7.3	<0.1	108	8.46	0.091	3
1094751	Soil	15.9	20.9	30.0	57	1.3	15.5	1.3	31	1.55	22.7	2.7	0.6	45	0.6	4.1	0.3	73	0.14	0.085	12
1094752	Soil	28.6	58.3	18.8	324	0.6	84.4	9.5	444	3.64	53.7	3.6	0.5	115	3.1	13.4	0.1	202	2.21	0.167	9
1094753	Soil	58.8	85.7	21.8	661	1.0	169.9	10.1	224	2.51	53.5	1.8	1.9	102	6.7	17.0	0.2	236	2.20	0.205	14
1094754	Soil	11.4	108.2	36.9	243	1.8	103.8	10.5	157	2.68	56.2	3.0	0.7	141	2.0	8.2	0.3	119	0.76	0.504	20
1094755	Soil	22.6	89.6	33.5	402	0.9	155.2	19.8	364	4.57	39.6	5.4	2.4	62	1.7	7.6	0.4	41	0.49	0.369	25
1094756	Soil	23.5	93.5	34.1	437	0.8	189.8	28.7	604	5.94	52.6	6.0	2.0	46	1.8	7.7	0.4	30	0.37	0.313	26
1094758	Soil	19.8	98.7	38.3	602	0.6	226.0	61.2	1890	7.48	36.0	4.7	1.7	24	2.3	5.4	0.5	27	0.06	0.225	24
1092381	Soil	2.8	25.0	12.1	44	1.0	11.6	4.0	207	1.50	9.3	5.4	0.3	17	<0.1	3.6	0.2	36	0.04	0.057	3
1092382	Soil	3.3	25.2	18.8	11	1.7	3.2	0.5	15	2.13	105.5	4.3	1.3	66	0.2	10.8	0.2	53	<0.01	0.351	1
1092383	Soil	3.1	29.8	18.3	9	1.9	2.7	0.4	11	1.90	78.7	3.4	1.4	46	<0.1	9.0	0.2	46	<0.01	0.223	1
1092384	Soil	7.8	62.9	55.3	80	2.8	16.1	4.4	68	4.17	43.8	2.5	2.8	72	0.2	10.2	0.5	75	0.02	0.152	2
1092385	Soil	8.0	54.0	47.3	83	2.4	15.8	4.4	63	3.83	36.0	2.5	2.5	79	<0.1	9.8	0.4	74	0.01	0.118	2
1092386	Soil	6.9	38.7	37.5	60	2.4	10.5	2.7	40	3.16	51.5	2.5	1.9	83	<0.1	11.2	0.4	68	0.01	0.117	2
1092387	Soil	6.6	36.0	14.4	53	1.1	16.4	1.3	51	1.45	11.3	0.6	0.3	63	0.3	3.8	0.2	98	0.15	0.092	1
1092388	Soil	15.4	69.2	38.6	79	5.2	22.8	3.2	176	5.80	51.5	12.7	0.9	56	0.2	12.5	0.4	158	0.03	0.225	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1095286	Soil	45	0.12	179	0.003	4	0.46	0.003	0.10	<0.1	0.47	4.7	0.6	0.06	1	6.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095287	Soil	34	0.08	178	0.003	3	0.35	0.002	0.10	<0.1	0.45	4.3	0.6	0.05	1	7.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095288	Soil	20	0.04	236	0.002	3	0.37	0.006	0.08	0.1	0.04	0.8	0.2	0.06	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1095289	Soil	20	0.07	352	0.003	3	0.37	0.003	0.09	<0.1	0.28	2.3	0.4	0.07	1	3.7	0.2	N.A.	N.A.	N.A.	N.A.
1095290	Soil	19	1.46	801	0.002	4	0.28	0.004	0.07	<0.1	0.28	5.0	0.4	0.06	<1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1095291	Soil	20	0.32	980	0.002	3	0.39	0.003	0.05	<0.1	0.36	4.6	0.4	0.05	<1	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095292	Soil	22	0.81	812	0.001	3	0.34	0.004	0.05	<0.1	0.23	4.2	0.4	<0.05	<1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1095293	Soil	17	0.53	514	0.001	3	0.28	0.003	0.04	<0.1	0.24	3.8	0.3	<0.05	<1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095294	Soil	16	0.99	1189	0.002	2	0.27	0.003	0.05	<0.1	0.22	4.3	0.3	<0.05	<1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1095295	Soil	15	2.18	304	0.002	3	0.19	0.005	0.04	<0.1	0.23	3.5	0.6	<0.05	<1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095296	Soil	16	0.09	1101	0.002	5	0.39	0.002	0.12	<0.1	0.30	4.7	0.4	<0.05	1	4.7	0.3	N.A.	N.A.	N.A.	N.A.
1095297	Soil	18	0.08	1307	0.002	<1	0.34	0.002	0.04	<0.1	0.29	4.1	0.4	<0.05	<1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095298	Soil	15	0.08	1335	0.002	2	0.38	0.011	0.04	<0.1	0.21	4.6	0.1	0.05	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095299	Soil	13	2.76	215	0.002	3	0.18	0.006	0.03	<0.1	0.27	3.5	0.8	<0.05	<1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095300	Soil	14	3.87	187	0.002	4	0.16	0.007	0.03	<0.1	0.20	3.2	0.8	0.05	<1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094751	Soil	16	0.06	555	0.003	3	0.36	0.003	0.13	<0.1	0.29	1.1	0.9	0.23	2	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094752	Soil	17	1.15	515	0.003	3	0.46	0.010	0.05	<0.1	0.35	1.6	0.3	<0.05	1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094753	Soil	21	0.96	461	0.003	5	0.34	0.004	0.09	0.2	0.64	2.8	0.9	0.07	1	5.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094754	Soil	30	0.07	746	0.004	4	0.54	0.006	0.10	0.1	0.55	1.5	0.3	0.09	2	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094755	Soil	12	0.07	977	0.004	4	0.48	0.004	0.14	<0.1	0.28	3.2	0.2	0.06	1	5.5	0.3	N.A.	N.A.	N.A.	N.A.
1094756	Soil	10	0.06	1051	0.003	3	0.42	0.003	0.11	<0.1	0.22	3.5	0.2	<0.05	1	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094758	Soil	9	0.06	701	0.004	2	0.71	0.004	0.07	<0.1	0.14	3.9	0.3	0.06	1	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092381	Soil	10	0.07	170	0.006	2	0.52	0.013	0.07	<0.1	0.07	1.4	0.3	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092382	Soil	27	0.01	433	0.002	2	0.12	0.007	0.13	<0.1	0.38	31.2	0.4	0.30	3	7.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092383	Soil	27	0.01	426	0.001	2	0.13	0.009	0.12	<0.1	0.43	16.4	0.4	0.30	3	8.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092384	Soil	28	0.03	450	0.001	3	0.38	0.010	0.19	<0.1	1.34	10.6	0.7	0.39	3	8.4	<0.2	N.A.	N.A.	N.A.	N.A.
1092385	Soil	23	0.02	575	<0.001	5	0.35	0.006	0.18	<0.1	1.50	7.2	0.7	0.35	3	8.1	<0.2	N.A.	N.A.	N.A.	N.A.
1092386	Soil	26	0.02	389	<0.001	6	0.29	0.005	0.20	<0.1	2.17	5.4	0.8	0.42	3	8.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092387	Soil	18	0.04	496	<0.001	3	0.28	0.003	0.08	<0.1	0.26	1.6	0.4	0.11	1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092388	Soil	31	0.12	561	0.007	2	0.86	0.010	0.10	0.1	0.32	6.3	0.7	0.17	4	10.2	0.3	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1095286	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095287	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095288	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095289	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095290	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095291	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095292	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095293	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095294	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095295	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095296	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095297	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095298	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095299	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095300	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094751	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094752	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094753	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094754	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094755	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094756	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094758	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092381	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092382	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092383	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092384	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092385	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092386	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092387	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092388	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1095286	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095287	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095288	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095289	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095290	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095291	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095292	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095293	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095294	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095295	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095296	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095297	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095298	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095299	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095300	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094751	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094752	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094753	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094754	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094755	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094756	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094758	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092381	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092382	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092383	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092384	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092385	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092386	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092387	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092388	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1092389	Soil	12.4	70.6	21.1	108	4.0	29.1	4.8	160	4.17	91.2	16.4	1.5	143	0.5	12.4	0.4	144	0.07	0.287	3
1092391	Soil	41.2	286.8	33.4	243	12.5	106.6	9.9	416	4.51	248.3	29.9	1.6	384	4.0	29.7	0.4	300	0.17	0.478	5
1092392	Soil	27.2	124.7	23.5	234	8.4	84.5	6.8	400	3.65	105.8	35.9	0.9	208	3.8	16.6	0.3	164	0.12	0.249	5
1092393	Soil	14.6	256.2	23.7	199	3.9	147.3	21.8	671	7.63	286.3	53.0	2.4	146	1.7	21.0	0.4	96	0.04	0.323	5
1092394	Soil	6.3	108.8	65.4	176	1.5	53.8	21.7	645	5.54	51.9	3.4	3.4	100	0.8	9.5	0.5	138	0.05	0.115	5
1092395	Soil	45.4	22.1	64.8	10	3.4	4.4	0.2	6	1.44	25.4	0.7	2.9	81	<0.1	9.4	0.6	98	<0.01	0.040	51
1092396	Soil	22.8	54.8	50.8	40	0.5	10.9	1.7	31	2.50	43.8	1.8	4.6	80	0.2	3.7	0.4	28	<0.01	0.044	16
1092397	Soil	11.0	20.4	12.9	44	0.5	9.7	2.9	83	1.36	15.0	2.8	0.4	23	0.1	4.8	0.2	87	0.01	0.050	16
1092398	Soil	1.1	14.8	6.3	54	<0.1	15.1	5.5	259	1.05	10.5	1.9	0.2	14	0.5	0.8	<0.1	11	0.03	0.040	2
1092399	Soil	2.5	54.1	30.1	265	0.2	67.2	28.5	649	4.40	19.7	0.6	2.1	17	1.1	1.5	0.4	23	0.03	0.065	5
1092400	Soil	2.5	34.0	6.0	88	<0.1	18.6	11.7	136	2.16	9.0	0.5	0.5	6	<0.1	0.8	0.2	32	<0.01	0.036	6
1274031	Soil	2.8	14.7	11.1	21	1.6	4.0	0.7	20	0.75	36.3	7.2	0.1	19	0.2	4.0	0.1	33	0.03	0.036	4
1274032	Soil	1.7	18.6	11.2	10	4.6	3.3	0.5	10	0.51	5.7	4.9	<0.1	8	<0.1	1.6	0.1	21	0.02	0.038	1
1274033	Soil	2.7	14.5	5.7	12	5.4	3.4	0.7	22	0.65	6.4	5.9	<0.1	13	<0.1	2.3	0.1	23	0.06	0.044	2
1274034	Soil	6.0	11.3	16.4	16	1.6	4.0	0.7	16	0.84	18.6	2.5	<0.1	40	<0.1	4.8	0.2	69	0.02	0.059	4
1274035	Soil	3.3	19.3	8.5	15	2.5	3.5	0.6	19	0.59	8.1	4.9	<0.1	17	0.2	2.6	0.1	33	0.02	0.046	2
1274036	Soil	4.7	11.9	12.1	15	1.8	2.4	0.4	11	0.69	17.2	4.4	<0.1	44	<0.1	4.4	0.2	63	0.01	0.055	4
1274037	Soil	9.5	50.8	24.1	34	9.4	8.6	1.7	76	1.44	30.5	8.1	0.1	72	0.2	9.0	0.3	99	0.04	0.148	4
1274038	Soil	2.5	4.1	2.7	15	0.3	3.8	1.0	17	0.40	3.8	<0.5	<0.1	6	<0.1	0.7	<0.1	26	<0.01	0.029	6
1274039	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1274040	Soil	28.6	40.8	12.8	303	3.2	38.7	3.7	156	6.77	14.1	10.4	0.3	35	3.6	8.8	0.2	158	0.09	0.233	4
1274041	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1274042	Soil	1.0	7.1	1.5	6	1.8	3.0	0.5	15	0.34	1.9	<0.5	<0.1	12	<0.1	0.5	<0.1	10	0.10	0.047	2
1274043	Soil	1.0	2.3	1.9	5	0.9	2.2	0.4	10	0.20	0.6	<0.5	<0.1	7	<0.1	0.2	<0.1	7	0.03	0.020	1
1274044	Soil	1.0	2.3	1.8	4	1.9	2.0	0.2	7	0.18	0.8	0.9	<0.1	10	<0.1	0.5	<0.1	7	0.03	0.030	<1
1274045	Soil	8.2	9.0	11.9	22	1.6	5.1	0.6	11	0.70	14.3	3.8	<0.1	35	<0.1	3.5	0.1	58	0.03	0.073	3
1274046	Soil	4.4	9.9	6.0	36	0.6	14.5	0.9	27	0.71	8.1	2.1	<0.1	19	0.3	2.3	<0.1	40	0.15	0.050	2
1274047	Soil	5.9	30.1	17.7	148	1.3	41.0	15.9	312	2.01	19.5	5.9	1.0	43	0.8	3.6	0.2	98	0.16	0.092	8
1274048	Soil	5.9	15.8	12.5	66	0.6	14.6	2.7	72	1.29	14.8	0.8	<0.1	21	0.1	3.2	0.2	87	0.02	0.074	6
1274049	Soil	7.5	15.3	11.7	41	0.8	9.4	1.5	25	0.94	15.7	9.2	0.1	22	0.1	3.9	0.1	71	0.02	0.077	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1092389	Soil	30	0.07	754	0.002	2	0.74	0.007	0.15	<0.1	0.46	4.3	0.5	0.25	3	10.8	0.3	N.A.	N.A.	N.A.	N.A.
1092391	Soil	75	0.04	449	0.003	7	0.96	0.005	0.21	0.1	2.95	6.7	1.4	0.34	4	32.7	0.4	N.A.	N.A.	N.A.	N.A.
1092392	Soil	45	0.08	1294	0.004	4	0.92	0.012	0.15	0.1	1.84	4.0	1.0	0.21	3	14.2	0.3	N.A.	N.A.	N.A.	N.A.
1092393	Soil	31	0.06	900	0.003	2	1.47	0.004	0.09	<0.1	0.68	9.9	0.6	0.13	2	7.4	0.3	N.A.	N.A.	N.A.	N.A.
1092394	Soil	14	0.05	995	0.001	2	0.55	0.003	0.13	<0.1	0.19	6.3	0.3	0.15	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1092395	Soil	17	0.01	483	0.002	5	0.27	0.003	0.15	0.2	1.13	1.1	2.9	0.42	5	9.5	0.2	N.A.	N.A.	N.A.	N.A.
1092396	Soil	10	0.01	214	<0.001	3	0.27	0.003	0.23	0.1	0.82	3.6	2.3	0.65	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1092397	Soil	11	0.02	352	0.007	2	0.45	0.010	0.06	0.1	0.20	0.7	0.8	0.08	3	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1092398	Soil	3	0.02	240	0.006	<1	0.51	0.023	0.03	<0.1	0.05	1.1	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092399	Soil	9	0.08	287	0.001	1	0.45	0.005	0.05	<0.1	0.05	4.8	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1092400	Soil	6	0.02	104	0.002	<1	0.28	0.002	0.04	<0.1	<0.01	1.4	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274031	Soil	11	0.04	879	0.006	1	0.35	0.009	0.03	<0.1	0.08	0.4	0.2	<0.05	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274032	Soil	7	0.02	224	0.003	2	0.44	0.020	0.02	<0.1	0.15	<0.1	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274033	Soil	8	0.02	172	0.009	2	0.48	0.023	0.03	<0.1	0.34	0.2	0.3	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274034	Soil	15	0.02	690	0.005	3	0.42	0.013	0.04	<0.1	0.13	0.1	0.4	0.06	4	7.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274035	Soil	9	0.02	394	0.004	2	0.55	0.022	0.03	<0.1	0.22	<0.1	0.3	<0.05	3	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274036	Soil	13	0.02	674	0.004	3	0.39	0.008	0.04	<0.1	0.12	0.2	0.2	<0.05	3	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274037	Soil	30	0.05	1305	0.008	3	0.73	0.013	0.07	0.1	0.69	0.8	0.9	<0.05	4	14.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274038	Soil	6	0.01	96	0.003	2	0.21	0.013	0.03	<0.1	0.02	<0.1	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274039	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	23.8	35.4	31.1	147
1274040	Soil	27	0.07	1378	0.005	4	1.36	0.014	0.07	0.1	1.12	0.9	1.0	0.09	3	9.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274041	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	40.7	37.9	16.3	72
1274042	Soil	5	0.03	102	0.015	<1	0.44	0.030	0.02	<0.1	0.06	0.1	0.3	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274043	Soil	4	0.01	51	0.005	<1	0.12	0.025	0.02	<0.1	0.02	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274044	Soil	5	0.01	434	0.005	1	0.14	0.025	0.02	<0.1	0.08	<0.1	0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274045	Soil	12	0.02	835	0.003	4	0.36	0.016	0.06	<0.1	0.19	0.2	0.8	0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274046	Soil	11	0.04	1259	0.003	2	0.32	0.026	0.04	<0.1	0.20	0.3	0.3	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274047	Soil	21	0.14	2376	0.002	2	1.05	0.008	0.08	<0.1	0.53	3.6	0.7	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274048	Soil	20	0.04	459	0.002	3	0.52	0.012	0.08	<0.1	0.07	0.2	0.3	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274049	Soil	13	0.03	450	0.005	2	0.43	0.014	0.06	<0.1	0.80	0.5	0.8	0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1092389	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092391	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092392	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092393	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092394	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092395	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092396	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092397	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092398	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092399	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092400	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274031	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274032	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274033	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274034	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274035	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274036	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274037	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274038	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274039	Soil		1.3	21.7	2.7	77	4.41	56.0	8.3	0.3	55	0.7	7.0	0.3	256	0.05	0.261	6	38	0.04	768	0.004
1274040	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274041	Soil		1.2	13.3	2.3	118	4.15	39.2	5.8	0.4	37	2.5	11.2	0.2	171	0.09	0.164	10	23	0.01	869	0.001
1274042	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274043	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274044	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274045	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274046	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274047	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274048	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274049	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1092389	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092391	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092392	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092393	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092394	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092395	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092396	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092397	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092398	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092399	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1092400	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274031	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274032	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274033	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274034	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274035	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274036	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274037	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274038	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274039	Soil	<20	0.65	0.008	0.12	0.1	0.25	0.4	1.1	0.16	4	5.8	<0.2
1274040	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274041	Soil	<20	0.31	0.009	0.06	0.1	0.21	0.3	1.0	0.12	2	6.9	<0.2
1274042	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274043	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274044	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274045	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274046	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274047	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274048	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274049	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274050	Soil	6.6	14.8	9.2	43	0.2	8.0	1.3	21	1.04	24.0	1.6	0.1	14	<0.1	2.7	0.1	48	0.01	0.055	6
1274081	Soil	3.5	7.3	6.2	15	0.4	6.0	0.6	14	0.38	3.9	<0.5	<0.1	12	0.8	0.9	<0.1	23	0.02	0.052	2
1274082	Soil	12.5	8.2	6.2	31	0.2	5.1	1.0	17	0.69	8.6	<0.5	<0.1	11	<0.1	2.7	<0.1	55	0.01	0.032	8
1274083	Soil	4.3	14.4	13.3	11	1.4	2.9	0.5	9	0.43	3.0	0.7	<0.1	17	<0.1	1.7	<0.1	23	0.02	0.065	2
1274084	Soil	1.2	2.6	4.7	10	0.1	3.8	0.3	8	0.21	2.4	<0.5	<0.1	10	0.1	0.3	<0.1	21	0.02	0.056	1
1274085	Soil	1.9	4.5	5.6	15	0.2	3.8	0.8	15	0.36	2.1	<0.5	<0.1	9	<0.1	0.7	<0.1	18	0.02	0.030	3
1274086	Soil	2.9	12.3	3.9	43	0.2	7.5	2.1	32	0.81	7.7	0.7	<0.1	6	0.1	1.2	<0.1	30	0.02	0.023	8
1274087	Soil	3.9	14.4	4.6	61	0.2	9.3	2.6	47	1.25	9.1	1.7	<0.1	6	<0.1	1.6	<0.1	45	0.02	0.032	7
1274088	Soil	3.8	11.0	7.2	39	0.4	8.7	2.1	36	0.96	7.8	1.3	0.1	11	0.1	2.1	0.1	42	0.02	0.038	10
1274089	Soil	8.1	14.9	13.9	57	0.8	11.6	3.0	56	1.65	17.9	<0.5	0.2	16	<0.1	4.2	0.3	98	0.02	0.043	13
1274090	Soil	4.2	10.0	10.0	38	0.6	8.5	2.0	54	1.29	10.6	1.2	<0.1	13	<0.1	1.7	0.2	55	0.02	0.047	11
1274091	Soil	5.4	10.8	7.6	46	0.6	8.2	2.0	40	1.01	9.6	<0.5	<0.1	12	<0.1	2.4	0.2	61	0.01	0.037	9
1274092	Soil	7.9	24.5	14.3	78	0.8	19.7	4.7	131	1.92	19.3	3.3	1.6	40	0.4	5.2	0.2	79	0.06	0.085	10
1274093	Soil	15.6	29.6	17.4	136	0.7	30.2	6.4	106	2.82	29.1	3.3	1.2	35	0.4	7.3	0.3	161	0.02	0.072	12
1274094	Soil	28.3	31.2	19.2	325	0.6	67.9	6.8	116	2.68	38.6	2.1	2.1	23	0.6	12.5	0.2	299	0.03	0.089	18
1274095	Soil	7.8	27.7	14.4	112	0.5	48.2	8.8	102	2.28	29.1	0.8	0.3	15	0.1	3.8	0.2	76	0.02	0.052	21
1274096	Soil	4.4	14.2	4.9	56	0.5	16.8	3.6	52	1.20	17.1	<0.5	0.1	6	<0.1	2.5	0.1	47	<0.01	0.029	14
1274097	Soil	6.7	27.1	17.8	125	0.3	25.1	6.1	135	2.43	20.7	1.5	0.7	17	0.3	3.0	0.3	78	0.03	0.055	11
1274098	Soil	4.5	28.6	16.6	109	0.3	22.2	5.6	89	1.96	15.5	1.7	0.2	12	0.2	2.6	0.2	45	0.01	0.065	7
1274099	Soil	5.2	37.6	17.0	143	0.3	29.2	7.4	125	2.59	19.2	2.5	0.8	16	0.3	3.1	0.2	46	0.03	0.078	8
1274100	Soil	4.2	20.8	11.2	88	0.5	16.2	4.8	76	1.61	13.0	1.3	0.1	10	0.2	2.4	0.2	40	<0.01	0.042	6
1274101	Soil	4.7	16.8	9.4	60	0.3	13.0	2.8	43	1.06	9.2	<0.5	<0.1	9	0.2	2.5	0.1	41	0.01	0.040	5
1274102	Soil	5.9	21.2	15.2	66	0.9	13.8	3.6	69	1.77	15.2	0.9	0.2	19	0.2	3.5	0.2	62	0.03	0.050	9
1274103	Soil	9.9	23.1	19.7	88	0.9	18.1	4.0	136	2.09	24.0	2.7	0.3	19	0.3	3.4	0.3	112	0.03	0.074	13
1274104	Soil	4.6	16.3	7.5	37	0.3	7.7	1.6	25	0.70	7.5	1.3	0.1	12	0.2	1.7	0.1	43	0.01	0.034	9
1274105	Soil	8.0	24.8	19.2	111	0.3	22.0	6.2	85	2.51	24.0	<0.5	1.2	20	0.2	3.4	0.3	57	0.01	0.063	12
1274106	Soil	4.7	16.9	14.3	81	0.6	15.7	4.1	70	1.70	13.5	1.4	0.2	13	0.3	2.8	0.2	58	0.02	0.065	7
1274107	Soil	7.4	26.3	19.1	116	0.4	22.0	4.3	84	2.26	22.6	0.5	0.2	16	0.3	4.4	0.3	84	0.02	0.130	10
1274108	Soil	9.2	37.8	26.5	109	1.8	25.3	4.2	88	2.81	33.2	4.7	0.4	24	0.5	5.1	0.3	93	0.05	0.195	8
1274109	Soil	3.2	19.8	8.5	47	0.6	9.6	2.3	26	0.86	8.6	0.8	<0.1	8	0.3	2.1	0.1	19	0.02	0.051	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1274050	Soil	9	0.01	629	0.002	3	0.32	0.010	0.04	<0.1	0.06	0.2	0.3	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274081	Soil	5	0.02	171	0.002	<1	0.22	0.019	0.03	<0.1	0.08	0.1	0.2	<0.05	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274082	Soil	6	0.01	169	0.003	3	0.22	0.010	0.04	0.1	0.03	<0.1	0.2	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274083	Soil	5	0.01	585	0.001	2	0.26	0.019	0.03	<0.1	0.11	0.2	0.5	<0.05	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274084	Soil	5	0.02	124	0.002	2	0.22	0.023	0.03	<0.1	0.03	<0.1	0.4	<0.05	<1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274085	Soil	5	0.01	125	0.003	2	0.16	0.022	0.03	<0.1	0.02	<0.1	0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274086	Soil	7	0.01	95	0.004	2	0.20	0.011	0.03	<0.1	0.02	0.2	0.1	<0.05	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274087	Soil	6	0.01	109	0.004	2	0.23	0.012	0.03	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274088	Soil	10	0.03	427	0.004	2	0.35	0.008	0.04	<0.1	0.04	0.3	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274089	Soil	11	0.04	235	0.006	2	0.52	0.004	0.04	0.1	0.02	0.5	0.3	<0.05	4	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274090	Soil	12	0.05	167	0.005	1	0.50	0.007	0.05	<0.1	0.04	0.2	0.2	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274091	Soil	9	0.03	629	0.006	1	0.34	0.011	0.04	<0.1	0.03	0.2	0.1	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274092	Soil	19	0.15	1038	0.009	2	0.70	0.004	0.08	<0.1	0.09	1.7	0.4	0.07	3	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274093	Soil	19	0.12	905	0.006	1	0.68	0.003	0.08	<0.1	0.08	2.0	0.5	0.06	3	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274094	Soil	24	0.07	415	0.013	1	0.60	0.003	0.08	0.1	0.11	1.6	0.6	<0.05	3	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274095	Soil	15	0.05	201	0.006	1	0.55	0.004	0.07	0.1	0.02	0.8	0.3	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274096	Soil	8	0.03	130	0.006	1	0.41	0.012	0.04	<0.1	0.02	0.3	0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274097	Soil	14	0.08	191	0.009	2	0.75	0.006	0.08	<0.1	0.02	1.2	0.2	0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274098	Soil	10	0.03	111	0.003	2	0.39	0.006	0.05	<0.1	0.02	0.4	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274099	Soil	13	0.08	166	0.003	2	0.54	0.003	0.06	<0.1	0.03	1.1	0.2	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274100	Soil	8	0.02	120	0.003	2	0.32	0.004	0.04	<0.1	0.03	0.5	0.1	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274101	Soil	7	0.02	111	0.002	1	0.25	0.009	0.04	<0.1	0.03	0.2	0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274102	Soil	12	0.04	247	0.007	2	0.40	0.003	0.06	0.1	0.05	0.5	0.2	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274103	Soil	18	0.08	284	0.010	2	0.75	0.003	0.07	0.1	0.06	0.6	0.3	<0.05	5	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274104	Soil	7	0.01	211	0.004	1	0.35	0.008	0.04	<0.1	0.04	0.2	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274105	Soil	8	0.02	189	0.004	<1	0.35	0.002	0.04	<0.1	0.01	1.3	0.1	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274106	Soil	11	0.04	162	0.004	1	0.46	0.007	0.04	<0.1	0.04	0.3	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274107	Soil	14	0.03	232	0.004	<1	0.71	0.004	0.05	<0.1	0.03	0.3	0.3	<0.05	4	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274108	Soil	20	0.06	742	0.004	4	1.07	0.008	0.12	0.1	0.61	1.0	0.4	<0.05	4	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274109	Soil	5	0.01	159	0.002	<1	0.26	0.013	0.03	<0.1	0.06	0.2	<0.1	<0.05	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1274050	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274081	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274085	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274087	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274050	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274081	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274085	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274087	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274110	Soil	4.6	28.2	12.9	77	0.3	14.2	3.8	48	1.65	18.4	1.2	0.3	12	0.4	3.3	0.2	32	0.03	0.083	7
1274111	Soil	7.6	49.1	18.0	156	0.4	29.4	7.7	125	2.75	32.9	3.3	2.2	25	0.9	6.0	0.3	46	0.12	0.129	13
1274112	Soil	8.1	54.8	19.1	161	0.4	33.0	6.6	78	2.74	34.5	2.7	1.8	21	0.7	6.8	0.4	54	0.10	0.128	10
1274113	Soil	7.5	48.4	19.1	166	0.6	31.8	6.7	118	2.68	31.0	3.0	1.6	25	0.8	5.6	0.3	61	0.11	0.140	11
1274114	Soil	20.3	68.5	17.7	382	1.1	107.6	32.0	1403	8.57	90.7	3.3	2.2	51	2.8	5.1	0.3	57	0.56	0.146	9
1274115	Soil	29.0	61.3	17.1	602	0.8	129.2	14.0	317	3.36	32.6	3.3	2.1	98	4.8	8.5	0.1	119	2.24	0.224	9
1274116	Soil	13.8	30.5	19.5	115	1.0	28.2	3.9	99	2.13	22.6	4.7	0.7	54	1.0	7.0	0.2	74	0.29	0.146	8
1274117	Soil	4.4	14.5	6.8	60	0.3	13.1	2.5	152	1.02	8.8	1.3	0.2	30	1.0	2.7	0.1	38	0.16	0.140	5
1274118	Soil	10.9	37.2	24.9	173	0.3	48.2	7.1	200	2.74	28.4	2.6	0.3	18	1.6	7.2	0.2	73	0.11	0.193	7
1274119	Soil	19.2	26.2	19.0	173	0.3	55.2	7.5	97	2.15	30.8	1.0	0.4	10	0.3	10.5	0.2	103	0.03	0.080	6
1274120	Soil	4.4	25.0	9.7	128	0.9	32.8	7.2	206	1.48	10.9	2.7	0.3	23	0.9	2.9	0.1	39	0.20	0.064	4
1274121	Soil	1.9	17.6	5.2	49	0.2	18.3	2.4	83	0.56	5.1	<0.5	0.2	44	0.8	2.0	<0.1	17	0.83	0.060	2
1274122	Soil	1.5	13.7	3.3	51	0.2	17.1	1.8	59	0.44	3.6	0.8	<0.1	31	0.4	1.5	<0.1	13	0.42	0.040	1
1274123	Soil	15.5	38.8	13.3	236	0.4	139.2	14.4	279	2.19	41.5	3.0	3.2	163	5.2	10.1	0.1	77	2.42	0.189	15
1274124	Soil	12.5	39.4	15.9	301	1.0	78.6	9.8	160	2.23	21.0	2.5	2.2	114	2.1	7.9	0.2	93	0.81	0.121	7
1274125	Soil	6.2	46.5	14.1	158	0.4	156.3	21.7	387	2.78	72.8	3.6	3.0	171	0.9	5.8	0.1	78	1.20	0.166	23
1274126	Soil	4.8	60.4	16.3	285	1.6	83.3	11.2	233	2.36	14.2	2.0	3.0	67	1.4	5.1	0.1	64	0.67	0.097	7
1274127	Soil	9.8	24.1	8.9	366	0.3	49.9	4.3	170	1.31	12.7	0.8	0.5	37	5.0	6.8	<0.1	84	0.92	0.043	3
1274128	Soil	5.7	24.5	12.3	244	0.7	43.5	7.1	340	2.30	12.9	1.4	1.3	55	2.5	5.4	<0.1	61	1.06	0.097	6
1274129	Soil	19.3	14.9	8.4	154	0.2	43.2	4.2	107	1.10	9.5	<0.5	0.4	31	0.8	3.2	<0.1	63	0.70	0.050	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1274110	Soil	7	0.03	168	0.003	<1	0.39	0.007	0.04	<0.1	0.04	0.4	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274111	Soil	11	0.07	1112	0.003	1	0.46	0.002	0.05	<0.1	0.12	1.8	0.2	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274112	Soil	12	0.05	361	0.002	2	0.43	0.003	0.07	2.9	0.10	1.6	0.2	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274113	Soil	13	0.07	941	0.002	2	0.62	0.002	0.09	<0.1	0.20	1.6	0.2	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274114	Soil	15	0.11	1348	0.002	5	1.04	0.008	0.11	<0.1	0.35	3.4	0.3	0.06	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274115	Soil	20	0.96	1378	0.003	3	0.51	0.004	0.05	<0.1	0.26	2.8	0.4	0.07	<1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274116	Soil	15	0.06	652	0.002	2	0.62	0.005	0.06	<0.1	0.25	1.7	0.3	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274117	Soil	11	0.04	476	0.002	1	0.57	0.014	0.04	0.2	0.12	0.4	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274118	Soil	19	0.03	382	0.004	2	0.47	0.007	0.05	<0.1	0.07	0.7	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274119	Soil	18	0.02	142	0.002	2	0.33	0.002	0.04	<0.1	0.02	1.0	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274120	Soil	11	0.05	775	0.003	2	0.74	0.022	0.06	<0.1	0.14	1.3	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274121	Soil	7	0.03	358	0.005	2	0.34	0.027	0.03	<0.1	0.08	0.5	<0.1	<0.05	<1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274122	Soil	4	0.03	283	0.007	2	0.24	0.034	0.03	<0.1	0.06	0.4	<0.1	<0.05	<1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274123	Soil	39	1.07	732	0.006	6	0.40	0.004	0.08	<0.1	0.14	3.5	0.2	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274124	Soil	23	0.16	749	0.004	4	0.45	0.008	0.07	<0.1	0.22	3.9	0.2	<0.05	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274125	Soil	124	0.84	617	0.006	7	0.85	0.010	0.06	<0.1	0.11	5.7	0.1	0.06	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274126	Soil	33	0.13	433	0.002	3	0.43	0.002	0.06	<0.1	0.24	5.4	<0.1	<0.05	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274127	Soil	9	0.12	294	0.006	3	0.34	0.022	0.03	<0.1	0.15	1.4	0.2	<0.05	<1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274128	Soil	18	0.13	488	0.005	4	0.45	0.010	0.05	<0.1	0.13	2.5	0.1	0.06	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274129	Soil	12	0.09	259	0.003	2	0.32	0.015	0.03	<0.1	0.09	1.3	0.3	<0.05	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1274110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11000996.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1090861	Soil	5.0	15.4	10.4	57	0.6	10.4	1.7	28	0.93	10.9	1.6	0.1	17	0.2	2.1	0.2	44	0.01	0.072	4
REP 1090861	QC	5.2	16.6	11.2	60	0.7	11.3	1.8	28	1.01	11.9	1.2	<0.1	19	0.3	2.2	0.1	49	0.02	0.078	4
1094733	Soil	4.1	33.7	10.6	93	0.7	24.6	6.4	180	2.44	16.1	4.3	3.7	21	0.5	2.6	0.2	65	0.13	0.100	12
REP 1094733	QC	4.2	34.7	10.6	97	0.7	23.8	6.5	189	2.49	16.2	6.5	4.0	24	0.4	2.8	0.2	67	0.13	0.102	14
1094777	Soil	1.6	16.7	10.0	96	0.4	20.1	4.5	147	1.79	5.9	<0.5	0.5	33	0.5	0.5	0.2	29	0.54	0.159	7
REP 1094777	QC	1.6	16.4	9.4	96	0.4	20.6	4.5	143	1.62	6.4	<0.5	0.5	31	0.5	0.5	0.2	30	0.53	0.157	7
1094785	Soil	3.0	36.2	16.3	78	0.8	17.4	3.8	87	1.74	10.1	2.3	0.1	13	1.1	1.3	0.2	49	0.03	0.067	5
REP 1094785	QC	3.2	36.3	15.7	78	0.7	17.0	3.6	85	1.78	10.1	1.2	0.1	14	0.9	1.2	0.2	49	0.02	0.065	5
1095161	Soil	1.6	4.3	7.4	12	<0.1	3.7	1.2	16	0.34	1.8	1.1	0.1	4	<0.1	0.3	<0.1	17	0.01	0.048	2
REP 1095161	QC	1.7	4.2	7.4	13	<0.1	3.8	1.2	16	0.35	2.2	<0.5	0.2	4	<0.1	0.3	<0.1	16	0.02	0.051	2
1095172	Soil	5.4	22.6	10.4	107	0.6	28.1	3.1	43	0.89	8.1	1.0	0.4	46	0.6	2.7	0.1	44	1.10	0.094	4
REP 1095172	QC	5.4	23.4	10.6	112	0.5	27.7	2.9	41	0.91	8.1	2.5	0.3	45	0.6	2.9	<0.1	44	1.12	0.099	4
1095193	Soil	28.3	70.7	20.8	1085	1.2	187.8	20.5	429	3.89	35.5	3.8	2.0	51	7.7	11.4	0.2	136	0.41	0.204	9
REP 1095193	QC	29.0	70.2	20.6	1123	1.2	189.0	20.6	423	3.81	34.3	6.3	2.1	52	8.1	10.9	0.2	139	0.42	0.216	10
1095194	Soil	24.2	64.6	20.6	538	1.0	113.0	13.6	328	3.34	42.6	2.0	2.0	89	3.5	11.0	0.2	114	1.27	0.194	10
REP 1095194	QC	24.4	63.3	20.7	527	1.0	110.5	13.5	330	3.26	40.2	1.6	2.0	90	3.1	10.4	0.2	113	1.23	0.186	10
1095220	Soil	42.2	69.6	17.5	725	0.9	159.6	13.1	496	3.21	26.5	3.6	1.5	143	4.8	9.1	0.2	130	4.63	0.194	8
REP 1095220	QC	44.1	70.4	17.7	779	0.9	165.5	14.1	515	3.37	27.4	3.0	1.5	147	4.8	9.4	0.2	138	4.98	0.196	8
1095245	Soil	4.5	17.6	10.4	69	0.1	16.0	3.5	96	2.02	11.8	3.4	1.1	7	0.2	1.6	0.2	54	0.02	0.034	8
REP 1095245	QC	4.3	16.6	10.7	65	0.2	16.3	3.6	98	1.98	11.4	2.7	1.1	8	0.2	1.6	0.2	56	0.02	0.033	8
1095258	Soil	7.7	14.6	21.1	27	1.6	6.0	1.2	31	1.48	15.9	4.8	0.1	40	<0.1	7.0	0.2	71	0.02	0.065	8
REP 1095258	QC	7.6	14.4	20.6	25	1.6	6.2	1.2	31	1.44	14.9	3.0	0.1	39	<0.1	6.8	0.2	68	0.02	0.065	7
1095281	Soil	1.9	22.6	5.6	71	0.2	27.0	4.0	87	0.96	7.4	2.7	0.1	21	0.7	1.2	<0.1	19	0.47	0.108	5
REP 1095281	QC	2.0	23.3	5.3	72	0.2	28.4	3.9	86	0.94	7.3	1.0	0.1	21	0.7	1.1	<0.1	19	0.45	0.107	6
1095294	Soil	31.1	78.8	23.8	320	1.1	120.5	12.4	311	3.35	20.3	2.6	2.9	100	2.7	7.6	0.2	83	2.15	0.147	5
REP 1095294	QC	31.0	79.2	24.2	326	1.1	121.5	12.5	313	3.34	20.4	3.0	3.0	102	2.4	7.9	0.2	88	2.18	0.151	5
1092391	Soil	41.2	286.8	33.4	243	12.5	106.6	9.9	416	4.51	248.3	29.9	1.6	384	4.0	29.7	0.4	300	0.17	0.478	5
REP 1092391	QC	40.4	282.4	31.9	244	12.3	107.7	10.3	415	4.50	246.5	24.4	1.7	367	3.9	27.4	0.4	277	0.18	0.488	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11000996.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1090861	Soil	7	0.02	427	0.003	2	0.28	0.012	0.04	<0.1	0.08	0.4	0.2	0.06	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1090861	QC	8	0.02	457	0.003	2	0.29	0.013	0.05	<0.1	0.11	0.4	0.2	0.05	1	2.1	<0.2				
1094733	Soil	20	0.29	234	0.042	2	0.99	0.005	0.06	0.2	0.15	2.9	0.3	<0.05	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094733	QC	22	0.29	240	0.049	2	1.03	0.006	0.07	0.2	0.15	2.9	0.3	0.07	4	2.0	<0.2				
1094777	Soil	17	0.08	489	0.004	2	0.76	0.005	0.04	<0.1	0.06	1.5	0.2	0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094777	QC	16	0.07	491	0.004	3	0.75	0.004	0.03	<0.1	0.06	1.8	0.1	<0.05	2	1.3	<0.2				
1094785	Soil	15	0.04	221	0.004	2	0.68	0.007	0.05	0.1	0.04	0.7	0.1	0.08	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094785	QC	14	0.04	217	0.003	2	0.70	0.007	0.05	<0.1	0.05	0.7	0.1	0.08	3	1.7	<0.2				
1095161	Soil	4	0.01	48	0.002	<1	0.26	0.010	0.03	<0.1	0.02	0.5	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1095161	QC	5	0.01	48	0.003	1	0.25	0.010	0.03	<0.1	<0.01	0.7	<0.1	0.05	1	0.6	<0.2				
1095172	Soil	15	0.07	523	0.005	3	0.48	0.008	0.03	<0.1	0.08	1.2	0.2	0.14	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1095172	QC	14	0.07	518	0.005	2	0.48	0.008	0.03	<0.1	0.08	1.4	0.1	0.16	2	0.9	<0.2				
1095193	Soil	22	0.07	1018	0.004	2	0.70	0.003	0.06	0.1	0.42	3.9	0.7	<0.05	1	15.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1095193	QC	22	0.08	1101	0.004	2	0.73	0.003	0.07	0.1	0.44	4.0	0.7	<0.05	1	17.0	<0.2				
1095194	Soil	20	0.49	1318	0.004	3	0.54	0.004	0.07	<0.1	0.40	3.6	0.5	0.08	1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1095194	QC	19	0.48	1327	0.004	3	0.53	0.004	0.07	<0.1	0.37	3.5	0.5	0.08	1	4.0	<0.2				
1095220	Soil	17	1.95	1204	0.002	5	0.37	0.005	0.06	<0.1	0.36	2.8	0.6	0.17	<1	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1095220	QC	18	1.98	1261	0.002	5	0.39	0.005	0.06	<0.1	0.36	2.9	0.6	0.18	<1	4.7	<0.2				
1095245	Soil	13	0.10	137	0.003	1	0.74	0.006	0.05	0.1	0.04	0.9	0.2	0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1095245	QC	13	0.10	146	0.003	2	0.74	0.006	0.06	0.1	0.08	0.9	0.2	<0.05	3	0.8	<0.2				
1095258	Soil	13	0.02	630	0.006	2	0.31	0.008	0.07	0.2	0.10	0.3	0.4	0.10	4	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1095258	QC	13	0.02	605	0.006	1	0.30	0.009	0.07	0.1	0.09	0.4	0.4	0.09	3	5.4	<0.2				
1095281	Soil	9	0.07	266	0.007	2	0.87	0.023	0.03	<0.1	0.05	0.6	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1095281	QC	8	0.07	259	0.007	1	0.87	0.022	0.03	<0.1	0.05	0.6	<0.1	<0.05	2	0.8	<0.2				
1095294	Soil	16	0.99	1189	0.002	2	0.27	0.003	0.05	<0.1	0.22	4.3	0.3	<0.05	<1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1095294	QC	17	1.02	1274	0.002	3	0.29	0.003	0.05	<0.1	0.24	4.3	0.3	<0.05	<1	2.9	<0.2				
1092391	Soil	75	0.04	449	0.003	7	0.96	0.005	0.21	0.1	2.95	6.7	1.4	0.34	4	32.7	0.4	N.A.	N.A.	N.A.	N.A.
REP 1092391	QC	72	0.04	216	0.002	5	0.87	0.005	0.20	<0.1	2.97	6.8	1.2	0.35	4	33.0	0.4				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11000996.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1090861	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090861	QC																					
1094733	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094733	QC																					
1094777	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094777	QC																					
1094785	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094785	QC																					
1095161	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095161	QC																					
1095172	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095172	QC																					
1095193	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095193	QC																					
1095194	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095194	QC																					
1095220	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095220	QC																					
1095245	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095245	QC																					
1095258	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095258	QC																					
1095281	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095281	QC																					
1095294	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095294	QC																					
1092391	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092391	QC																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11000996.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1090861	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1090861	QC													
1094733	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094733	QC													
1094777	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094777	QC													
1094785	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094785	QC													
1095161	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095161	QC													
1095172	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095172	QC													
1095193	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095193	QC													
1095194	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095194	QC													
1095220	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095220	QC													
1095245	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095245	QC													
1095258	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095258	QC													
1095281	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095281	QC													
1095294	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095294	QC													
1092391	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1092391	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11000996.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1274036	Soil	4.7	11.9	12.1	15	1.8	2.4	0.4	11	0.69	17.2	4.4	<0.1	44	<0.1	4.4	0.2	63	0.01	0.055	4
REP 1274036	QC	4.9	12.1	12.1	15	1.8	2.8	0.4	11	0.71	17.8	2.8	<0.1	46	<0.1	4.6	0.2	67	0.02	0.057	4
1274094	Soil	28.3	31.2	19.2	325	0.6	67.9	6.8	116	2.68	38.6	2.1	2.1	23	0.6	12.5	0.2	299	0.03	0.089	18
REP 1274094	QC	28.7	31.2	18.8	312	0.6	66.0	7.0	114	2.73	37.8	1.5	2.1	23	0.6	12.1	0.2	305	0.03	0.082	18
1274099	Soil	5.2	37.6	17.0	143	0.3	29.2	7.4	125	2.59	19.2	2.5	0.8	16	0.3	3.1	0.2	46	0.03	0.078	8
REP 1274099	QC	5.2	36.9	16.3	145	0.4	28.9	7.0	119	2.51	18.4	3.1	0.6	16	0.4	3.1	0.2	44	0.04	0.077	7
1274116	Soil	13.8	30.5	19.5	115	1.0	28.2	3.9	99	2.13	22.6	4.7	0.7	54	1.0	7.0	0.2	74	0.29	0.146	8
REP 1274116	QC	13.6	30.5	20.0	115	1.1	27.6	3.8	99	2.14	22.3	4.2	0.8	55	1.0	6.9	0.2	75	0.29	0.150	8
Reference Materials																					
STD DS8	Standard	11.7	103.8	124.8	307	1.7	37.1	7.4	599	2.47	23.6	117.5	6.1	56	2.5	4.8	6.3	40	0.65	0.076	14
STD DS8	Standard	12.7	109.0	124.0	317	1.9	38.3	7.6	593	2.44	24.3	105.4	6.8	65	2.3	5.2	6.4	41	0.66	0.082	15
STD DS8	Standard	13.5	109.7	122.8	314	1.8	37.7	7.6	634	2.49	24.7	111.3	6.9	69	2.3	5.7	6.3	43	0.72	0.077	16
STD DS8	Standard	14.8	116.5	125.7	325	1.9	40.8	8.1	678	2.65	26.7	112.5	7.6	80	2.5	6.6	7.4	45	0.78	0.081	19
STD DS8	Standard	14.0	112.6	127.2	325	1.8	39.0	7.3	635	2.59	25.9	112.6	6.9	64	2.1	4.9	6.2	43	0.70	0.078	16
STD DS8	Standard	12.9	105.1	120.3	296	1.7	37.4	7.5	586	2.34	24.1	106.5	7.4	64	2.4	5.6	6.8	42	0.69	0.075	16
STD DS8	Standard	12.9	102.3	110.6	293	1.7	35.5	7.1	578	2.34	23.8	109.2	6.7	62	2.2	4.9	6.4	39	0.65	0.074	15
STD DS8	Standard	14.5	97.5	134.7	306	1.9	39.2	6.8	634	2.54	22.0	117.2	6.4	66	2.0	5.0	5.8	39	0.73	0.071	16
STD DS8	Standard	11.8	104.3	118.8	297	1.8	35.0	6.9	559	2.25	22.0	106.8	5.7	52	2.2	4.6	5.8	39	0.63	0.072	12
STD DS8	Standard	12.3	108.3	124.0	306	1.8	37.5	7.7	589	2.41	24.9	116.6	6.2	63	2.2	5.5	6.4	41	0.63	0.079	13
STD DS8	Standard																				
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11000996.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1274036	Soil	13	0.02	674	0.004	3	0.39	0.008	0.04	<0.1	0.12	0.2	0.2	<0.05	3	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274036	QC	14	0.02	680	0.003	3	0.39	0.008	0.04	<0.1	0.12	0.1	0.2	<0.05	3	6.7	<0.2				
1274094	Soil	24	0.07	415	0.013	1	0.60	0.003	0.08	0.1	0.11	1.6	0.6	<0.05	3	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274094	QC	23	0.07	403	0.012	2	0.61	0.003	0.08	0.2	0.08	1.7	0.6	<0.05	3	3.6	<0.2				
1274099	Soil	13	0.08	166	0.003	2	0.54	0.003	0.06	<0.1	0.03	1.1	0.2	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274099	QC	12	0.08	158	0.004	2	0.53	0.003	0.06	<0.1	0.03	1.1	0.2	<0.05	2	1.7	<0.2				
1274116	Soil	15	0.06	652	0.002	2	0.62	0.005	0.06	<0.1	0.25	1.7	0.3	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274116	QC	16	0.06	656	0.003	2	0.62	0.006	0.06	0.3	0.26	1.8	0.3	<0.05	2	1.6	<0.2				
Reference Materials																					
STD DS8	Standard	109	0.58	265	0.106	2	0.87	0.081	0.40	3.0	0.18	2.1	5.5	0.15	4	5.9	4.4				
STD DS8	Standard	114	0.61	276	0.113	3	0.91	0.087	0.40	2.8	0.21	2.1	5.5	0.17	5	5.0	4.8				
STD DS8	Standard	122	0.61	274	0.126	2	0.90	0.085	0.42	3.1	0.18	2.2	5.3	0.14	5	6.0	4.6				
STD DS8	Standard	128	0.69	296	0.143	3	1.00	0.095	0.43	3.3	0.20	2.2	5.3	0.18	5	5.6	5.3				
STD DS8	Standard	123	0.61	288	0.122	4	0.93	0.087	0.42	3.1	0.23	2.2	5.5	0.13	5	5.5	4.8				
STD DS8	Standard	116	0.59	269	0.114	3	0.88	0.085	0.40	2.9	0.19	2.0	5.1	0.16	4	5.0	4.3				
STD DS8	Standard	109	0.58	253	0.105	2	0.86	0.080	0.38	2.8	0.18	1.9	4.9	0.14	4	4.5	4.5				
STD DS8	Standard	123	0.61	248	0.125	3	0.92	0.081	0.42	3.2	0.23	1.7	5.7	0.19	5	5.2	5.2				
STD DS8	Standard	110	0.57	244	0.099	3	0.84	0.074	0.38	2.8	0.20	2.1	5.1	0.10	4	4.9	4.3				
STD DS8	Standard	115	0.58	254	0.106	3	0.87	0.081	0.40	3.1	0.21	2.2	5.3	0.16	5	5.6	5.2				
STD DS8	Standard																	14.2	119.9	125.1	325
STD DS8	Standard																	11.8	106.7	124.9	309
STD OREAS45CA	Standard																	0.9	570.7	22.2	69
STD OREAS45CA	Standard																	0.7	436.8	18.4	55
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11000996.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1274036	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274036	QC																				
1274094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274094	QC																				
1274099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274099	QC																				
1274116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274116	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.7	41.1	8.3	652	2.53	27.0	136.8	7.2	76	2.4	5.4	7.4	47	0.73	0.081	17	128	0.61	304	0.123
STD DS8	Standard	1.7	35.0	7.0	598	2.39	23.6	223.8	6.4	75	2.1	5.4	6.0	38	0.63	0.078	15	107	0.60	297	0.099
STD OREAS45CA	Standard	0.3	271.0	97.9	970	17.25	3.5	43.2	7.3	16	<0.1	<0.1	0.2	218	0.43	0.039	17	793	0.16	172	0.144
STD OREAS45CA	Standard	0.2	207.6	73.7	819	13.75	2.6	40.1	6.6	14	<0.1	<0.1	0.2	171	0.36	0.034	14	573	0.12	142	0.089
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11000996.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1274036	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274036	QC												
1274094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274094	QC												
1274099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274099	QC												
1274116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274116	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.94	0.096	0.43	2.3	0.19	2.4	5.5	0.17	5	4.4	5.4
STD DS8	Standard	<20	0.90	0.109	0.42	2.3	0.15	2.1	5.5	0.15	4	5.0	5.5
STD OREAS45CA	Standard	<20	3.94	0.013	0.08	<0.1	0.03	39.8	<0.1	0.05	19	0.9	<0.2
STD OREAS45CA	Standard	<20	3.15	0.011	0.06	<0.1	0.03	32.1	<0.1	<0.05	16	0.5	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11000996.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11000996.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11000996.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	0.04	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11000996.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 03, 2011
Report Date: October 31, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11000997.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: # 9
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve to 230 mesh			WHI
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	317	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	3	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274130	Soil	33.1	23.5	8.5	147	<0.1	72.5	3.9	38	1.18	13.1	2.5	0.4	24	1.2	3.1	0.2	39	0.46	0.027	5
1274132	Soil	2.1	21.6	19.0	135	0.1	36.9	12.5	348	4.31	14.0	2.5	0.7	12	0.1	1.5	0.3	29	0.03	0.066	5
1274133	Soil	1.5	11.9	16.8	67	<0.1	16.8	6.1	109	1.59	8.2	2.8	0.1	8	<0.1	0.6	0.2	18	0.03	0.061	3
1274134	Soil	1.7	15.7	9.8	62	<0.1	15.6	7.0	97	1.54	8.4	1.9	<0.1	5	<0.1	0.6	0.2	21	0.02	0.061	3
1274135	Soil	1.9	16.1	11.0	68	<0.1	15.6	6.0	106	1.50	10.7	2.6	0.1	6	0.1	0.8	0.2	24	0.04	0.074	5
1274136	Soil	2.1	22.8	16.3	87	<0.1	17.8	9.6	222	2.36	13.6	1.1	0.2	7	<0.1	1.0	0.3	28	0.03	0.060	5
1274137	Soil	1.9	16.4	10.4	56	<0.1	13.4	4.8	143	1.86	8.5	2.6	<0.1	8	0.1	0.8	0.2	24	0.04	0.048	6
1274138	Soil	1.2	11.6	7.0	43	<0.1	9.8	4.3	140	1.22	6.1	1.2	<0.1	6	<0.1	0.5	0.1	16	0.04	0.048	3
1274139	Soil	0.8	7.4	2.9	20	<0.1	5.5	2.0	37	0.62	2.7	1.2	<0.1	6	<0.1	0.3	<0.1	10	0.04	0.042	2
1274140	Soil	1.8	18.3	13.4	74	<0.1	22.0	9.3	201	2.40	10.7	1.7	<0.1	9	0.1	0.8	0.2	25	0.05	0.055	6
1274141	Soil	1.8	25.0	15.9	136	<0.1	28.8	14.4	513	3.03	12.2	3.3	0.5	13	0.2	0.9	0.2	25	0.10	0.088	7
1274142	Soil	0.7	9.0	4.4	32	<0.1	6.5	2.6	78	0.83	3.2	0.7	<0.1	6	<0.1	0.3	0.1	11	0.04	0.046	3
1274143	Soil	1.6	19.5	12.9	79	<0.1	21.3	10.9	333	2.28	11.1	1.4	0.2	10	0.1	0.8	0.2	21	0.06	0.078	5
1274144	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1274145	Soil	1.8	13.9	9.9	69	<0.1	18.3	9.1	203	1.81	11.8	0.9	0.1	6	<0.1	0.8	0.2	19	0.02	0.055	3
1274146	Soil	0.3	2.1	2.4	8	<0.1	2.5	0.8	16	0.21	0.9	0.7	<0.1	4	<0.1	<0.1	<0.1	4	0.02	0.024	<1
1274147	Soil	1.7	4.1	5.7	14	1.0	4.5	1.2	16	0.42	2.8	0.8	<0.1	6	<0.1	0.4	<0.1	9	0.02	0.042	2
1274148	Soil	14.6	21.8	27.7	63	0.8	16.8	4.4	83	2.02	19.9	3.1	0.3	48	0.3	3.6	0.3	40	0.03	0.055	2
1274149	Soil	11.3	22.1	25.5	75	1.1	18.6	5.9	170	1.83	17.8	3.5	0.2	49	0.4	3.5	0.2	39	0.03	0.069	2
1274150	Soil	11.0	30.4	24.1	140	0.5	38.8	12.0	279	2.60	21.4	1.5	0.5	40	0.5	3.3	0.2	44	0.06	0.076	4
1274151	Soil	9.7	28.0	21.7	117	0.5	29.1	10.0	284	2.56	20.1	2.3	0.4	36	0.5	3.0	0.2	38	0.08	0.074	4
1274152	Soil	22.3	35.2	20.5	280	0.6	81.4	9.7	277	2.45	24.6	1.8	0.8	62	3.0	6.1	0.2	94	0.51	0.081	5
1274153	Soil	18.0	35.2	21.5	149	1.5	48.6	4.2	110	1.74	13.8	4.9	0.6	47	0.9	4.4	0.2	77	0.13	0.083	4
1274154	Soil	9.9	12.4	12.1	56	0.9	15.5	2.0	34	0.83	6.7	1.1	0.2	23	0.4	2.0	0.1	34	0.05	0.039	2
1274155	Soil	29.8	38.1	16.2	599	0.5	102.8	9.4	182	2.24	33.2	5.1	1.9	59	3.8	18.4	0.1	87	0.66	0.160	11
1274156	Soil	22.1	30.5	6.9	4127	0.5	293.7	4.9	265	1.18	12.8	2.2	0.5	220	30.4	5.6	<0.1	54	13.07	0.062	4
1274157	Soil	23.8	34.1	7.3	435	0.4	99.4	4.9	149	1.21	16.4	1.6	0.5	81	3.1	7.1	<0.1	71	3.32	0.068	7
1274158	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1274159	Soil	34.1	19.9	9.3	196	0.2	73.2	5.2	97	1.38	12.9	1.7	1.0	43	1.4	3.8	0.1	38	0.88	0.054	6
1274160	Soil	3.0	16.1	14.5	68	0.2	17.9	7.7	211	2.23	13.9	1.4	0.2	9	<0.1	1.2	0.3	35	0.05	0.056	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1274130	Soil	8	0.06	276	0.005	3	0.33	0.004	0.03	0.1	0.08	1.2	0.4	<0.05	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274132	Soil	25	0.28	60	0.004	2	1.33	0.004	0.04	0.1	0.06	1.8	0.2	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274133	Soil	10	0.03	60	0.002	1	0.30	0.006	0.04	<0.1	0.04	0.4	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274134	Soil	9	0.02	43	0.001	1	0.31	0.006	0.03	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274135	Soil	13	0.03	53	0.004	2	0.36	0.003	0.03	0.1	0.04	0.5	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274136	Soil	12	0.08	47	0.002	<1	0.58	0.002	0.03	<0.1	0.03	0.4	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274137	Soil	13	0.12	49	0.006	1	0.65	0.009	0.03	0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274138	Soil	8	0.05	35	0.005	1	0.43	0.011	0.02	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274139	Soil	5	0.02	47	0.003	2	0.44	0.019	0.02	<0.1	0.03	<0.1	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274140	Soil	14	0.12	54	0.005	1	0.59	0.007	0.04	<0.1	0.02	0.5	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274141	Soil	13	0.13	64	0.006	1	0.63	0.004	0.03	<0.1	0.03	2.0	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274142	Soil	5	0.04	37	0.005	<1	0.50	0.020	0.03	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274143	Soil	10	0.08	55	0.003	1	0.48	0.006	0.03	<0.1	0.02	0.8	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274144	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	0.7	9.2	9.5	30
1274145	Soil	8	0.04	36	0.002	<1	0.39	0.008	0.03	<0.1	0.01	0.8	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274146	Soil	3	<0.01	10	0.002	<1	0.09	0.017	0.02	<0.1	0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274147	Soil	5	0.01	44	0.003	1	0.21	0.016	0.03	<0.1	0.06	0.2	0.2	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274148	Soil	9	0.01	391	<0.001	3	0.31	0.008	0.17	<0.1	0.21	1.2	1.3	0.41	1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274149	Soil	8	0.02	332	0.001	2	0.34	0.008	0.11	<0.1	0.18	0.9	0.9	0.22	1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274150	Soil	13	0.04	222	0.002	2	0.39	0.004	0.08	<0.1	0.06	2.2	0.6	0.11	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274151	Soil	11	0.04	139	0.001	2	0.37	0.004	0.05	<0.1	0.07	1.6	0.4	0.11	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274152	Soil	10	0.17	204	0.001	2	0.38	0.004	0.06	<0.1	0.14	1.9	0.5	0.10	1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274153	Soil	10	0.03	308	0.002	3	0.57	0.009	0.06	<0.1	0.37	1.4	0.8	0.09	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274154	Soil	6	0.02	122	0.003	2	0.19	0.014	0.04	<0.1	0.12	0.6	0.4	<0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274155	Soil	15	0.08	577	0.004	3	0.41	0.004	0.06	0.1	0.33	4.0	0.4	0.07	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274156	Soil	13	0.71	223	0.004	3	0.34	0.008	0.03	0.1	0.31	3.1	1.1	0.22	<1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274157	Soil	10	1.15	267	0.003	5	0.30	0.018	0.04	0.1	0.27	1.4	0.5	0.10	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274158	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	31.9	38.9	13.1	590
1274159	Soil	10	0.09	297	0.004	2	0.45	0.009	0.04	0.2	0.16	1.8	0.4	0.15	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274160	Soil	11	0.08	66	0.008	<1	0.66	0.006	0.04	0.1	0.02	0.8	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1274130	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274132	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274133	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274134	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274135	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274136	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274137	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274138	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274139	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274140	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274141	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274142	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274143	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274144	Soil		0.1	10.1	4.1	171	0.72	3.3	4.0	<0.1	9	<0.1	0.2	<0.1	9	0.04	0.032	2	13	0.03	93	0.003
1274145	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274146	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274147	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274148	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274149	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274150	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274151	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274152	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274153	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274154	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274155	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274156	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274157	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274158	Soil		0.5	81.4	5.3	185	1.30	28.6	1.6	0.4	73	4.6	12.2	0.1	134	1.56	0.077	9	19	0.19	278	0.004
1274159	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274160	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274141	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274142	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274143	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274144	Soil	<20	0.23	0.029	0.03	<0.1	0.04	0.4	<0.1	0.06	<1	<0.5	<0.2
1274145	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274146	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274147	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274148	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274149	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274150	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274151	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274152	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274153	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274154	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274155	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274156	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274157	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274158	Soil	<20	0.38	0.011	0.05	0.1	0.40	1.6	0.6	0.12	1	1.9	<0.2
1274159	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274160	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274161	Soil	2.8	25.5	20.6	385	0.2	58.0	28.2	550	4.21	34.3	1.2	0.7	24	0.6	2.5	0.3	18	0.11	0.072	4
1274162	Soil	1.8	9.5	8.2	41	0.1	12.4	5.7	53	0.96	7.4	<0.5	<0.1	4	<0.1	0.7	0.1	14	0.02	0.041	2
1274163	Soil	4.3	24.7	22.5	154	0.3	38.8	13.8	189	3.02	25.1	1.2	0.6	28	0.3	2.7	0.3	28	0.03	0.057	5
1274164	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1274165	Soil	3.4	21.3	5.2	103	0.2	23.9	2.5	74	0.85	9.1	1.9	0.3	54	0.6	3.3	<0.1	18	0.77	0.064	3
1274166	Soil	16.7	21.2	13.1	220	0.2	48.1	5.1	142	1.85	44.2	1.5	0.4	33	2.3	18.0	0.1	49	0.53	0.146	5
1274167	Soil	6.8	10.8	5.0	98	0.3	18.5	4.4	186	0.93	39.2	2.6	<0.1	15	1.8	6.9	0.1	30	0.15	0.100	4
1274168	Soil	11.6	12.5	6.1	102	<0.1	23.3	5.9	235	1.16	75.9	2.5	0.1	5	1.1	14.2	<0.1	54	0.03	0.067	2
1274169	Soil	17.6	26.3	12.4	211	0.1	43.4	6.9	249	1.97	109.6	2.7	0.1	16	1.6	26.7	0.2	77	0.10	0.091	5
1274170	Soil	35.1	29.5	12.4	166	0.1	68.2	8.4	310	3.25	308.8	7.1	0.1	11	1.6	38.3	0.1	105	0.13	0.078	3
1274171	Soil	5.6	9.8	3.8	57	<0.1	13.6	2.4	80	0.89	105.7	0.9	<0.1	8	0.7	17.3	<0.1	28	0.08	0.050	2
1274172	Soil	5.3	33.5	7.7	54	0.2	31.6	12.8	344	3.81	1178	53.9	0.3	13	0.3	168.6	<0.1	112	0.19	0.072	4
1274173	Soil	1.4	82.7	17.9	172	1.1	69.6	37.8	944	14.17	>10000	1548	0.2	77	0.9	480.5	<0.1	40	0.76	0.139	6
1274174	Soil	4.2	27.8	9.3	118	0.2	38.4	6.0	105	1.68	94.2	12.0	0.2	8	0.3	15.3	<0.1	42	0.12	0.073	3
1274175	Soil	15.0	96.9	12.2	574	0.7	115.8	11.1	158	3.49	55.7	5.4	1.5	21	4.0	22.3	0.2	69	0.22	0.084	5
1274176	Soil	11.1	78.5	15.0	569	1.2	111.7	13.1	182	2.85	59.2	5.0	1.1	45	3.5	25.2	0.1	62	0.32	0.147	4
1274177	Soil	5.1	82.6	34.7	109	0.9	51.4	13.0	197	5.91	40.2	3.9	0.5	9	0.2	30.8	0.4	24	0.03	0.115	5
1274178	Soil	12.3	20.7	19.9	183	<0.1	36.8	4.8	52	1.75	25.6	11.1	<0.1	21	0.3	11.7	0.1	111	0.02	0.090	5
1274179	Soil	8.4	24.0	13.6	189	<0.1	37.8	5.9	78	2.00	17.6	1.0	<0.1	13	0.2	6.7	0.1	77	0.01	0.098	4
1274180	Soil	6.0	59.9	40.7	272	2.3	90.7	18.6	530	5.81	18.2	<0.5	1.5	29	0.4	7.7	0.2	38	0.57	0.066	9
1274181	Soil	5.0	47.8	17.7	155	0.9	59.1	9.6	209	3.04	11.9	1.4	0.1	19	0.5	5.5	0.2	28	0.28	0.093	3
1274182	Soil	4.2	69.0	36.7	141	0.3	81.4	20.2	224	6.02	13.1	0.6	0.2	10	0.4	6.1	0.3	32	0.07	0.100	6
1274183	Soil	11.4	135.1	40.2	266	1.3	164.8	53.7	1072	12.42	15.6	3.9	2.4	66	<0.1	10.3	0.3	39	0.46	0.152	6
1274184	Soil	15.8	46.7	40.4	127	0.8	85.6	17.6	356	5.12	12.4	2.0	0.5	22	<0.1	5.6	0.2	29	0.35	0.072	5
1274185	Soil	7.9	43.8	38.0	77	0.9	64.5	8.5	152	2.32	21.9	2.3	0.2	53	0.3	7.1	0.2	23	0.12	0.125	2
1274186	Soil	8.1	70.5	34.1	69	0.5	104.4	13.8	205	3.25	23.2	3.3	2.2	42	<0.1	9.0	0.3	25	0.41	0.095	4
1274187	Soil	7.4	14.1	85.5	34	0.3	14.1	2.2	29	1.28	12.8	2.5	0.1	17	<0.1	6.2	0.2	39	0.02	0.076	3
1274188	Soil	0.8	2.6	10.6	4	0.2	1.8	0.8	73	0.41	1.2	0.9	<0.1	5	<0.1	0.5	<0.1	6	0.03	0.028	2
1274189	Soil	5.6	6.2	87.7	12	0.6	4.0	0.7	17	0.65	9.3	3.5	<0.1	24	<0.1	8.8	0.1	23	0.03	0.039	3
1274190	Soil	10.7	8.7	91.8	18	0.9	7.2	0.9	23	0.74	17.2	3.3	<0.1	18	<0.1	11.0	0.2	43	0.03	0.047	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1274161	Soil	8	0.06	149	0.002	<1	0.47	0.007	0.04	<0.1	0.06	3.1	0.2	<0.05	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274162	Soil	5	0.02	34	0.001	<1	0.22	0.013	0.02	<0.1	0.02	0.4	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274163	Soil	12	0.08	100	0.002	<1	0.55	0.004	0.05	<0.1	0.03	2.0	0.3	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274164	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	27.6	43.8	23.8	321
1274165	Soil	7	0.13	337	0.008	3	0.58	0.032	0.03	<0.1	0.12	0.9	0.1	0.08	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274166	Soil	12	0.11	347	0.006	2	0.58	0.012	0.05	<0.1	0.03	1.0	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274167	Soil	8	0.04	166	0.003	2	0.39	0.013	0.03	<0.1	0.03	0.4	0.2	0.11	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274168	Soil	10	0.03	124	0.002	<1	0.36	0.011	0.03	<0.1	0.01	0.3	0.2	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274169	Soil	14	0.03	180	0.002	2	0.44	0.006	0.05	<0.1	<0.01	0.2	0.2	0.11	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274170	Soil	16	0.03	233	0.001	2	0.37	0.008	0.04	<0.1	0.06	1.2	0.4	0.09	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274171	Soil	5	0.02	98	0.002	2	0.38	0.019	0.03	<0.1	0.02	0.2	<0.1	0.09	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274172	Soil	17	0.05	417	0.002	2	0.69	0.011	0.06	<0.1	0.05	4.6	0.1	0.06	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274173	Soil	55	0.12	408	0.003	3	0.65	0.003	0.10	0.3	0.37	29.0	0.1	0.17	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274174	Soil	14	0.04	130	0.002	1	0.41	0.012	0.03	<0.1	0.11	0.9	0.1	<0.05	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274175	Soil	20	0.04	381	<0.001	1	0.29	0.001	0.03	<0.1	0.33	5.3	0.2	<0.05	<1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274176	Soil	17	0.03	303	0.001	1	0.30	0.002	0.05	<0.1	0.40	3.8	0.2	<0.05	<1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274177	Soil	21	0.03	1598	0.001	3	0.45	0.005	0.05	<0.1	0.11	4.0	0.2	0.08	1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274178	Soil	10	0.02	154	0.002	2	0.38	0.003	0.03	<0.1	0.02	0.2	<0.1	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274179	Soil	13	0.02	132	<0.001	1	0.43	0.006	0.03	<0.1	0.03	<0.1	0.1	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274180	Soil	24	0.14	578	0.001	6	0.28	0.003	0.04	<0.1	0.25	7.4	0.2	0.10	<1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274181	Soil	20	0.05	344	0.001	3	0.34	0.015	0.04	<0.1	0.16	1.0	0.1	0.08	1	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274182	Soil	18	0.04	171	0.002	1	0.39	0.004	0.05	<0.1	0.05	1.1	0.2	0.07	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274183	Soil	10	0.09	633	0.002	3	0.32	0.002	0.06	<0.1	0.23	10.7	0.3	<0.05	<1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274184	Soil	14	0.07	377	0.001	2	0.39	0.005	0.06	<0.1	0.17	3.9	0.1	0.07	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274185	Soil	9	0.02	461	<0.001	3	0.42	0.008	0.05	<0.1	0.13	0.9	0.1	0.07	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274186	Soil	8	0.04	385	<0.001	2	0.26	0.002	0.07	<0.1	0.19	5.0	0.2	<0.05	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274187	Soil	11	0.01	147	0.001	1	0.24	0.006	0.07	<0.1	0.05	<0.1	0.4	0.19	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274188	Soil	3	0.01	18	0.007	<1	0.54	0.022	0.01	<0.1	0.07	0.1	<0.1	0.06	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274189	Soil	7	0.01	79	0.002	<1	0.26	0.015	0.04	<0.1	0.04	<0.1	0.2	0.10	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274190	Soil	13	0.02	131	0.003	1	0.26	0.008	0.05	<0.1	0.07	<0.1	0.3	0.11	3	3.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1274161	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274162	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274163	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274164	Soil	1.2	85.7	5.3	300	1.11	28.4	4.3	0.1	50	4.2	5.1	0.2	127	0.34	0.085	6	16	0.06	248	0.003
1274165	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274174	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274175	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274176	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274178	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274180	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274161	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274162	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274163	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274164	Soil	<20	0.71	0.024	0.04	<0.1	0.30	1.0	1.4	0.09	2	2.4	<0.2
1274165	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274174	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274175	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274176	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274178	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274180	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274191	Soil		15.5	10.0	274.3	6	3.0	2.9	0.2	9	0.45	14.2	2.9	0.3	17	<0.1	42.2	0.3	23	0.01	0.012	2
1274192	Soil		6.8	26.0	58.3	67	0.7	19.9	2.4	62	1.57	86.2	4.2	<0.1	218	0.4	12.4	0.3	70	0.08	0.190	6
1274193	Soil		4.1	74.6	35.9	219	2.0	60.0	19.0	1217	3.43	11.5	6.3	0.6	30	2.4	3.7	0.3	44	0.08	0.083	4
1274194	Soil		10.1	158.6	41.0	2713	1.5	337.7	61.8	1067	8.48	22.1	5.1	2.9	154	31.8	8.9	0.4	116	0.75	0.220	8
1274195	Soil		17.8	155.8	50.0	6085	1.8	586.6	109.3	2288	14.74	26.2	4.4	4.2	229	67.5	11.5	0.2	250	1.21	0.343	13
1274196	Soil		15.0	118.7	35.8	4289	1.3	440.1	65.7	923	9.75	18.0	4.7	2.2	128	39.3	7.5	0.2	187	0.83	0.223	8
1274197	Soil		50.0	129.4	52.1	3679	1.8	484.9	78.6	935	9.45	26.8	<0.5	2.2	167	39.0	9.7	0.1	280	1.42	0.269	8
1274198	Soil		46.6	144.9	53.5	4854	1.6	453.0	77.7	1198	10.86	26.5	1.5	2.4	183	41.3	11.8	0.1	372	0.95	0.338	7
1274199	Soil		49.1	65.5	23.5	1612	0.8	193.1	23.7	414	4.83	22.0	<0.5	0.6	86	13.7	10.2	0.1	276	0.62	0.208	5
1274200	Soil		43.3	45.6	27.5	822	0.3	145.8	19.3	387	4.21	37.5	2.2	0.3	44	4.8	14.2	0.1	240	0.22	0.162	4
1274201	Soil		79.0	64.7	21.0	488	0.7	183.9	7.9	128	2.04	71.0	2.5	1.2	101	4.5	20.7	0.2	165	4.17	0.104	6
1274202	Soil		70.4	52.4	14.5	394	0.4	151.4	7.8	174	1.89	54.5	0.7	2.2	99	3.1	20.9	0.1	136	4.93	0.106	6
1274203	Soil		4.2	159.0	27.3	62	1.8	96.9	38.1	1029	13.44	24.8	5.5	4.7	40	0.3	7.3	1.2	18	0.34	0.139	26
1274204	Soil		7.6	71.5	32.7	27	1.0	67.4	17.0	272	5.52	34.8	3.1	6.3	11	0.2	10.0	0.4	13	0.14	0.050	16
1274205	Soil		13.5	112.1	19.9	542	1.6	121.6	7.9	194	2.39	43.2	3.1	0.6	128	7.2	21.9	0.3	135	0.59	0.262	10
1274206	Soil		5.3	4.8	4.1	31	0.7	7.6	0.8	13	0.44	4.0	<0.5	<0.1	5	0.1	2.3	0.1	21	0.02	0.059	2
1274207	Soil		28.3	26.4	14.3	145	0.5	46.6	4.4	86	2.01	26.9	<0.5	0.3	30	1.5	10.8	0.2	59	0.19	0.135	4
1274208	Soil		83.5	27.9	13.9	332	<0.1	107.4	7.6	125	2.69	27.8	<0.5	0.2	9	1.5	15.4	0.2	96	0.12	0.057	3
1274209	Soil		32.0	28.3	10.9	201	0.1	65.8	8.5	214	2.88	18.8	<0.5	0.3	9	0.8	12.7	0.1	74	0.11	0.075	4
1274210	Soil		33.5	26.2	14.0	119	0.2	84.1	3.9	223	1.87	20.4	<0.5	1.3	188	0.9	12.7	<0.1	81	13.99	0.028	5
1274211	Soil		61.5	44.8	17.7	72	0.1	133.6	8.6	361	3.87	20.2	1.7	0.5	16	0.6	13.3	0.1	51	0.33	0.072	5
1274212	Soil		34.6	52.4	11.7	394	0.1	64.5	12.9	237	4.60	394.7	9.5	0.4	11	1.8	35.5	0.2	162	0.11	0.088	5
1274213	Soil		13.7	87.2	35.8	371	0.4	60.7	27.4	647	7.06	1584	105.1	0.7	30	1.3	66.5	<0.1	86	0.60	0.066	5
1274214	Soil		35.7	59.4	14.5	522	0.5	97.9	18.4	336	4.57	300.4	12.8	1.3	55	4.6	44.3	0.1	203	2.17	0.074	5
1274215	Soil		12.5	33.0	7.0	218	0.3	49.8	11.4	219	2.41	88.3	7.1	0.6	29	1.3	33.8	0.1	102	0.50	0.066	4
1274216	Soil		16.8	49.0	12.4	351	0.6	65.7	8.4	187	2.77	46.3	<0.5	0.7	37	2.6	18.5	0.3	83	0.49	0.117	5
1274217	Soil		13.6	54.2	47.4	159	1.5	119.9	18.1	355	3.62	19.6	5.3	0.9	69	1.8	13.1	0.3	98	0.47	0.105	4
1274218	Soil		3.7	52.0	210.4	791	1.3	215.7	23.8	1953	6.64	104.1	14.7	1.4	106	2.8	30.5	0.3	57	0.57	0.136	6
1274219	Soil		3.2	7.7	11.0	27	0.5	7.4	1.6	18	0.62	13.8	1.7	<0.1	6	<0.1	2.8	<0.1	22	0.02	0.031	4
1274220	Soil		4.3	94.1	174.3	561	2.0	82.4	15.4	847	4.40	157.7	21.3	1.0	44	1.7	63.1	0.3	36	0.09	0.096	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1274191	Soil	6	<0.01	237	<0.001	1	0.14	0.003	0.06	<0.1	0.21	0.2	0.3	0.13	1	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274192	Soil	35	0.01	160	0.002	2	0.47	0.005	0.06	<0.1	0.08	0.3	0.6	0.19	6	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274193	Soil	17	0.08	122	0.007	2	0.56	0.017	0.05	<0.1	0.16	4.3	0.3	0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274194	Soil	71	0.18	416	0.002	<1	0.53	0.005	0.04	<0.1	0.93	14.6	0.4	0.08	2	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274195	Soil	289	0.30	1008	0.003	3	0.82	0.010	0.06	<0.1	0.56	27.6	0.9	0.16	2	9.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274196	Soil	200	0.10	683	0.002	2	0.71	0.012	0.04	<0.1	0.91	18.9	0.5	0.10	3	7.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274197	Soil	187	0.26	831	0.008	5	0.67	0.009	0.06	<0.1	1.08	18.5	1.0	0.10	3	8.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274198	Soil	224	0.16	892	0.003	6	0.75	0.005	0.07	<0.1	1.05	21.8	0.8	0.08	3	7.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274199	Soil	97	0.08	557	0.003	3	0.68	0.012	0.05	0.2	0.48	7.5	0.7	0.09	3	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274200	Soil	49	0.06	535	0.002	1	0.40	0.006	0.06	<0.1	0.11	2.5	0.5	0.06	2	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274201	Soil	19	2.00	320	0.001	5	0.29	0.006	0.06	0.2	0.51	3.0	1.1	0.09	<1	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274202	Soil	15	2.27	247	0.001	4	0.25	0.005	0.05	0.1	0.33	3.3	0.9	0.08	<1	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274203	Soil	12	0.09	1377	0.002	4	0.40	0.003	0.11	<0.1	0.18	9.9	0.2	<0.05	<1	3.6	0.3	N.A.	N.A.	N.A.	N.A.
1274204	Soil	7	0.06	418	<0.001	2	0.26	0.002	0.07	<0.1	0.23	5.7	0.2	<0.05	<1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274205	Soil	17	0.05	282	0.003	4	0.46	0.006	0.06	<0.1	0.32	1.8	0.4	<0.05	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274206	Soil	3	0.01	29	<0.001	1	0.25	0.015	0.02	<0.1	<0.01	0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274207	Soil	14	0.04	192	0.001	3	0.31	0.005	0.04	<0.1	0.05	0.6	0.4	<0.05	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274208	Soil	13	0.03	99	0.002	<1	0.33	0.006	0.03	<0.1	<0.01	0.6	0.5	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274209	Soil	24	0.10	277	0.002	1	0.73	0.006	0.05	<0.1	<0.01	1.7	0.4	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274210	Soil	11	6.74	113	<0.001	11	0.13	0.015	0.03	<0.1	0.11	2.2	0.7	0.05	<1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274211	Soil	21	0.03	344	0.002	1	0.32	0.003	0.03	0.1	0.25	2.9	0.8	<0.05	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274212	Soil	32	0.06	277	0.002	2	0.77	0.003	0.05	<0.1	0.06	5.5	0.5	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274213	Soil	35	0.11	620	0.001	2	0.64	0.013	0.07	0.1	0.29	27.0	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274214	Soil	25	1.10	356	0.001	3	0.37	0.008	0.05	<0.1	0.48	11.5	0.5	<0.05	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274215	Soil	19	0.09	268	0.003	2	0.52	0.021	0.04	<0.1	0.19	6.5	0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274216	Soil	17	0.11	397	0.003	3	0.57	0.009	0.05	<0.1	0.16	4.6	0.3	<0.05	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274217	Soil	57	0.06	493	0.002	3	0.27	0.003	0.06	0.1	0.53	5.5	0.6	<0.05	<1	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274218	Soil	21	0.07	307	0.003	3	0.49	0.003	0.05	<0.1	0.39	6.5	0.2	<0.05	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274219	Soil	5	0.01	55	0.003	2	0.18	0.009	0.02	<0.1	<0.01	0.1	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274220	Soil	14	0.03	330	0.002	2	0.56	0.005	0.05	<0.1	0.43	4.1	0.2	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1274191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274218	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274218	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274221	Soil		8.8	15.4	17.3	65	0.2	18.2	3.2	36	1.15	25.3	0.5	0.1	9	<0.1	6.1	0.1	54	0.01	0.029	5
1274222	Soil		1.5	2.3	3.7	7	0.4	2.2	0.6	12	0.25	1.8	<0.5	<0.1	5	<0.1	0.7	<0.1	10	0.02	0.023	1
1274223	Soil		2.6	8.2	5.6	11	1.2	5.0	0.9	16	0.47	4.0	<0.5	0.2	4	<0.1	1.3	<0.1	18	0.02	0.017	2
1274224	Soil		8.5	12.4	104.0	30	0.2	8.5	1.4	21	0.78	13.4	<0.5	<0.1	19	<0.1	10.4	0.2	39	0.01	0.049	8
1274225	Soil		5.3	8.6	164.8	13	0.7	5.6	0.5	10	0.37	15.6	1.1	0.2	27	<0.1	13.0	0.1	28	0.03	0.041	3
1274226	Soil		6.4	26.6	699.5	7	1.2	2.5	0.2	5	0.46	66.1	7.6	0.3	68	0.3	28.4	0.1	45	0.03	0.071	4
1274227	Soil		5.4	16.1	113.8	47	1.3	12.8	2.3	51	1.81	94.0	1.3	0.3	45	0.2	13.2	0.2	64	0.04	0.077	11
1274228	Soil		2.4	11.4	54.8	27	0.5	5.5	0.9	17	0.64	25.1	2.7	<0.1	205	0.1	13.2	0.4	42	0.10	0.172	10
1274229	Soil		4.8	57.5	146.7	186	1.7	53.1	13.6	863	3.91	174.5	6.1	0.2	170	1.5	24.5	0.3	69	0.12	0.277	8
1274230	Soil		7.5	73.9	68.7	210	1.8	55.5	13.5	642	2.79	24.5	7.4	0.5	35	1.8	14.0	0.3	48	0.05	0.088	5
1274231	Soil		6.6	26.3	54.5	30	0.9	9.4	1.5	56	1.30	29.6	2.8	0.1	134	<0.1	16.2	0.5	38	0.05	0.103	6
1274232	Soil		3.8	31.9	15.1	72	0.1	28.5	5.7	79	1.52	10.9	0.5	<0.1	17	0.3	3.3	0.2	40	0.03	0.055	3
1274233	Soil		44.3	41.5	11.2	282	0.8	188.1	15.8	182	2.96	20.2	3.2	1.8	93	1.6	7.6	0.1	256	0.74	0.242	12
1274234	Soil		66.4	53.4	22.4	698	0.9	206.3	12.2	266	3.30	36.8	2.5	1.4	90	4.6	19.3	0.2	430	0.70	0.178	10
1274235	Soil		12.9	24.7	19.5	175	<0.1	42.6	5.7	64	1.59	18.1	<0.5	0.2	20	0.3	8.2	0.1	120	0.03	0.051	6
1274236	Soil		22.5	60.4	31.4	386	0.6	134.1	16.0	414	3.79	34.4	1.4	0.9	130	3.3	16.1	0.2	152	0.78	0.207	9
1274237	Soil		14.3	56.0	16.2	171	0.9	84.8	12.9	225	3.65	21.7	3.5	3.7	56	1.0	6.6	0.3	39	0.59	0.173	16
1274238	Soil		14.0	53.4	14.1	258	0.5	116.3	18.7	228	3.92	29.3	3.5	3.2	53	1.5	16.7	0.2	71	0.50	0.124	15
1274239	Soil		16.2	51.4	15.4	1343	0.7	176.3	7.7	168	2.12	18.1	4.2	0.6	75	3.2	18.5	0.3	57	1.03	0.169	6
1274240	Soil		12.9	113.7	18.4	162	0.5	59.3	12.9	115	3.49	28.8	8.4	0.1	10	0.3	7.3	0.3	47	0.11	0.194	4
1274241	Soil		8.5	60.8	19.6	195	0.2	39.7	7.9	58	2.18	16.0	4.1	0.1	13	0.4	4.9	0.3	42	0.05	0.091	7
1274242	Soil		4.3	56.6	11.5	160	0.8	29.0	6.7	355	2.40	12.8	3.4	0.7	25	1.6	3.3	0.2	30	0.77	0.177	12
1274243	Soil		7.1	65.5	67.2	279	1.0	44.9	8.3	801	3.01	21.4	4.0	0.8	57	3.0	10.0	0.2	36	2.87	0.274	5
1274244	Soil		6.7	48.8	27.4	196	0.8	41.0	11.0	374	3.53	27.4	3.8	1.0	41	1.3	5.9	0.2	31	1.43	0.144	7
1274245	Soil		9.3	56.0	28.7	267	0.9	45.7	11.3	459	3.48	30.9	2.7	1.1	39	2.2	8.2	0.2	39	0.82	0.170	7
1274246	Soil		15.7	98.0	29.9	519	1.7	70.3	14.0	239	3.35	31.7	4.2	2.4	45	3.7	9.1	0.2	50	0.88	0.300	11
1274247	Soil		9.1	18.2	16.2	38	2.0	10.0	2.9	91	1.83	16.5	3.3	0.6	34	0.1	5.0	0.3	61	0.05	0.071	5
1274248	Soil		17.7	20.8	31.7	13	5.9	4.0	0.8	34	2.30	28.9	6.0	0.9	81	<0.1	15.2	0.4	65	0.02	0.094	4
1274249	Soil		5.9	35.1	17.5	60	2.6	17.4	4.3	114	3.62	38.1	4.4	1.1	172	0.1	12.8	0.2	94	0.09	0.250	11
1274250	Soil		3.9	31.8	16.8	112	1.1	31.8	9.9	335	2.88	23.6	2.9	3.3	32	0.4	4.3	0.3	57	0.20	0.145	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1274221	Soil	8	0.01	82	0.004	2	0.15	0.007	0.03	<0.1	<0.01	0.4	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274222	Soil	3	0.01	24	0.006	<1	0.15	0.016	0.02	<0.1	<0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274223	Soil	6	0.01	32	0.016	1	0.27	0.017	0.02	<0.1	0.03	0.3	<0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274224	Soil	10	0.01	83	0.002	1	0.34	0.004	0.04	0.1	<0.01	0.2	0.3	<0.05	4	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274225	Soil	10	0.01	66	0.002	<1	0.26	0.006	0.03	<0.1	0.03	0.2	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274226	Soil	13	<0.01	110	<0.001	<1	0.28	0.002	0.04	<0.1	0.17	0.5	0.3	<0.05	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274227	Soil	16	0.03	131	0.015	1	0.44	0.004	0.06	0.2	0.04	0.6	0.3	0.06	6	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274228	Soil	22	0.01	131	0.003	1	0.62	0.009	0.03	<0.1	<0.01	0.1	0.2	<0.05	5	1.2	0.2	N.A.	N.A.	N.A.	N.A.
1274229	Soil	46	0.09	205	0.006	<1	0.75	0.010	0.06	<0.1	0.06	3.4	0.6	0.07	6	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274230	Soil	26	0.07	161	0.006	3	0.55	0.009	0.07	0.1	0.08	3.6	0.4	0.06	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274231	Soil	13	0.02	392	0.002	1	0.40	0.009	0.12	<0.1	0.02	0.2	0.6	0.12	2	6.3	0.3	N.A.	N.A.	N.A.	N.A.
1274232	Soil	17	0.02	55	0.002	<1	0.25	0.011	0.03	<0.1	<0.01	0.5	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274233	Soil	47	0.05	387	0.004	3	0.51	0.007	0.06	0.1	0.10	4.9	0.7	<0.05	1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274234	Soil	46	0.06	607	0.004	3	0.64	0.009	0.06	0.2	0.32	4.5	0.9	<0.05	2	8.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274235	Soil	18	0.02	158	0.003	2	0.25	0.006	0.03	<0.1	<0.01	0.5	0.1	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274236	Soil	55	0.11	760	0.004	2	0.64	0.007	0.07	0.1	0.11	4.4	0.3	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274237	Soil	13	0.04	703	0.002	4	0.42	0.003	0.09	<0.1	0.33	5.7	0.1	<0.05	<1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274238	Soil	43	0.10	486	0.003	2	0.47	0.005	0.07	<0.1	0.12	6.0	0.2	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274239	Soil	23	0.12	441	0.004	4	0.64	0.013	0.03	<0.1	0.24	2.2	0.3	0.09	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274240	Soil	12	0.06	134	0.002	4	0.39	0.005	0.05	<0.1	0.06	0.5	0.2	0.06	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274241	Soil	9	0.02	110	0.002	2	0.29	0.003	0.03	0.1	0.03	0.4	0.1	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274242	Soil	9	0.12	1012	0.004	3	0.55	0.011	0.03	<0.1	0.14	2.2	0.1	0.07	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274243	Soil	11	0.39	670	0.004	4	0.37	0.007	0.03	<0.1	0.40	2.6	0.3	0.07	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274244	Soil	11	0.12	492	0.004	4	0.46	0.006	0.03	<0.1	0.18	3.0	0.2	0.06	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274245	Soil	14	0.07	536	0.004	2	0.55	0.006	0.03	<0.1	0.22	2.9	0.3	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274246	Soil	10	0.05	2318	0.003	3	0.37	0.003	0.06	<0.1	0.44	4.5	0.1	<0.05	<1	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274247	Soil	15	0.10	384	0.008	2	0.59	0.010	0.09	0.1	0.07	1.2	0.5	0.17	4	5.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274248	Soil	21	0.03	346	0.002	2	0.27	0.024	0.22	0.1	0.39	3.4	0.8	0.51	4	21.3	0.3	N.A.	N.A.	N.A.	N.A.
1274249	Soil	27	0.21	613	0.012	2	0.84	0.011	0.18	0.2	0.17	3.0	0.9	0.37	5	6.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274250	Soil	28	0.47	257	0.026	2	1.29	0.006	0.08	0.3	0.15	2.6	0.3	0.05	4	2.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1274221	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274222	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274223	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274224	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274225	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274226	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274227	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274228	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274229	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274230	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274231	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274232	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274233	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274234	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274235	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274236	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274237	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274238	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274239	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274240	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274241	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274242	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274243	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274244	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274245	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274246	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274247	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274248	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274249	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274250	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274222	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274224	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274226	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274227	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274231	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274232	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274233	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274234	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274235	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274236	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274237	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274238	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274239	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274240	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274241	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274242	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274243	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274244	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274245	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274247	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274249	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274250	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274251	Soil	2.0	13.3	6.8	16	0.4	4.4	1.4	58	0.71	5.6	2.7	0.2	8	<0.1	1.7	<0.1	23	0.06	0.057	3
1274252	Soil	4.3	20.1	13.3	53	1.3	14.9	3.9	103	2.26	15.9	3.1	1.7	12	0.2	5.2	0.2	59	0.07	0.050	8
1274253	Soil	4.1	15.2	12.7	41	0.4	9.8	2.6	63	1.49	14.1	3.2	0.5	6	0.1	3.6	0.2	68	0.02	0.038	7
1274254	Soil	3.5	18.2	12.3	33	1.3	8.8	2.2	68	1.47	11.4	2.4	0.2	16	0.2	4.6	0.1	42	0.04	0.061	5
1274255	Soil	4.3	15.6	15.5	40	0.6	8.7	2.5	103	1.73	14.7	1.1	0.2	15	0.1	5.4	0.2	64	0.02	0.042	6
1274256	Soil	3.5	10.2	4.9	19	1.0	4.4	1.4	66	0.79	5.4	0.8	<0.1	7	<0.1	2.1	<0.1	30	0.02	0.042	5
1274257	Soil	5.7	13.0	10.5	32	1.3	6.7	1.6	34	1.23	12.2	2.0	<0.1	10	<0.1	4.2	0.1	54	0.01	0.039	7
1274258	Soil	8.3	13.6	9.9	41	0.2	8.7	2.2	39	1.28	10.1	4.0	0.2	9	0.1	3.7	0.1	64	<0.01	0.033	11
1274259	Soil	2.3	4.7	4.3	14	0.1	3.3	0.8	18	0.40	2.9	<0.5	<0.1	5	<0.1	0.7	<0.1	21	<0.01	0.022	5
1274260	Soil	5.3	10.9	7.6	48	0.4	7.5	1.8	23	0.98	8.9	0.9	<0.1	5	<0.1	1.7	0.1	53	<0.01	0.036	5
1274261	Soil	4.6	41.5	13.6	332	0.2	45.0	12.6	127	3.80	27.0	1.8	1.1	7	0.8	2.7	0.2	20	0.01	0.049	2
1274262	Soil	7.7	15.3	12.4	61	0.2	11.9	4.0	62	1.50	23.1	0.9	<0.1	12	<0.1	3.6	0.2	51	<0.01	0.054	5
1274263	Soil	1.8	4.6	3.0	10	0.2	2.4	0.5	10	0.27	2.3	<0.5	<0.1	4	<0.1	0.6	<0.1	13	<0.01	0.026	4
1274264	Soil	10.6	15.5	14.1	62	0.4	12.0	2.8	42	1.32	16.1	<0.5	<0.1	15	0.2	3.3	0.2	61	0.02	0.054	6
1274265	Soil	10.1	25.1	19.0	77	1.1	19.5	4.7	109	1.89	19.8	1.4	0.1	22	0.3	4.1	0.2	62	0.06	0.106	5
1274266	Soil	7.9	17.8	13.6	63	0.4	12.6	3.7	56	1.61	16.9	1.2	<0.1	13	0.1	3.5	0.2	63	0.01	0.050	8
1274267	Soil	5.4	11.6	9.1	45	0.1	9.1	2.8	43	1.19	15.1	<0.5	<0.1	11	0.1	2.8	0.2	49	<0.01	0.028	8
1274268	Soil	4.7	26.3	14.4	69	0.3	13.1	2.5	38	1.46	16.3	1.0	<0.1	20	0.2	1.9	0.2	35	0.02	0.066	4
1274269	Soil	4.7	14.8	20.0	44	0.3	8.4	1.8	40	1.02	13.2	1.2	0.2	27	0.5	1.6	0.2	33	0.03	0.067	6
1274270	Soil	3.7	22.5	19.8	85	0.3	17.4	3.5	57	1.54	31.9	1.7	0.2	20	0.8	2.4	0.2	28	0.02	0.048	6
1274271	Soil	3.4	22.5	15.5	94	0.2	15.6	4.0	52	1.40	13.0	1.4	<0.1	13	0.2	2.0	0.2	31	0.01	0.044	7
1274272	Soil	3.2	25.4	14.2	112	0.6	21.4	5.7	108	1.75	8.8	2.1	<0.1	6	0.2	1.8	0.2	27	0.01	0.038	6
1274273	Soil	2.2	15.3	6.0	46	0.8	9.5	2.6	40	0.99	5.8	0.9	<0.1	3	<0.1	1.1	0.1	26	0.01	0.034	5
1274274	Soil	1.3	18.3	6.2	31	0.4	7.6	2.0	36	0.71	4.5	<0.5	<0.1	15	0.5	0.8	0.1	16	0.08	0.084	2
1274275	Soil	0.7	7.3	4.0	19	0.1	3.8	1.0	20	0.39	3.3	<0.5	<0.1	5	0.3	0.3	0.2	10	0.02	0.040	1
1274276	Soil	1.8	18.9	8.0	52	0.2	10.5	2.0	48	1.07	9.9	1.0	<0.1	17	0.5	0.9	0.2	25	0.12	0.047	4
1274277	Soil	2.2	36.8	12.7	72	1.0	16.0	2.5	58	1.54	8.8	1.3	<0.1	35	0.5	1.2	0.3	26	0.22	0.069	6
1274278	Soil	2.5	36.2	11.1	64	0.8	11.5	1.8	37	1.09	13.4	<0.5	<0.1	25	0.4	1.4	0.2	24	0.15	0.041	6
1274279	Soil	7.1	117.0	43.9	324	2.9	60.1	7.2	167	3.60	71.7	9.7	1.2	53	0.8	4.6	0.3	44	0.30	0.151	11
1274280	Soil	11.6	14.1	6.4	186	0.3	16.8	2.4	41	1.04	12.6	0.8	<0.1	5	0.4	2.4	0.1	115	0.01	0.037	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1274251	Soil	5	0.03	65	0.013	2	0.43	0.011	0.03	0.1	0.06	0.4	<0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274252	Soil	19	0.14	127	0.023	2	0.91	0.004	0.03	0.2	0.13	1.2	0.2	<0.05	4	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274253	Soil	12	0.02	83	0.022	1	0.26	0.002	0.02	0.2	0.07	0.5	0.1	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274254	Soil	12	0.09	218	0.011	1	0.63	0.010	0.05	0.1	0.22	0.5	0.2	0.08	4	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274255	Soil	12	0.04	167	0.017	<1	0.43	0.004	0.04	0.1	0.10	0.4	0.2	<0.05	4	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274256	Soil	5	0.01	92	0.006	1	0.34	0.012	0.02	<0.1	0.06	0.2	<0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274257	Soil	9	0.02	137	0.005	<1	0.31	0.004	0.03	0.1	0.06	0.2	0.2	<0.05	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274258	Soil	9	0.01	132	0.009	<1	0.20	0.005	0.02	0.1	0.03	0.2	0.1	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274259	Soil	4	<0.01	57	0.003	<1	0.25	0.008	0.02	<0.1	0.01	0.1	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274260	Soil	6	<0.01	108	0.003	<1	0.27	0.005	0.02	<0.1	0.02	0.2	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274261	Soil	6	0.03	238	0.001	<1	0.34	0.001	0.03	<0.1	0.08	5.0	0.2	<0.05	<1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274262	Soil	6	0.01	352	0.002	<1	0.29	0.003	0.02	0.2	0.03	0.3	0.2	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274263	Soil	3	<0.01	88	0.002	1	0.16	0.008	0.02	<0.1	0.01	<0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274264	Soil	8	0.01	369	0.002	<1	0.28	0.003	0.04	0.2	0.03	0.3	0.3	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274265	Soil	16	0.06	1180	0.003	2	0.71	0.006	0.05	0.2	0.18	0.8	0.5	<0.05	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274266	Soil	9	0.02	216	0.002	1	0.33	0.002	0.03	0.1	0.04	0.2	0.2	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274267	Soil	5	<0.01	299	0.005	1	0.18	0.001	0.02	<0.1	0.01	0.3	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274268	Soil	6	0.01	287	0.002	1	0.26	0.007	0.04	<0.1	0.02	0.2	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274269	Soil	7	0.02	332	0.004	<1	0.49	0.006	0.04	0.1	0.05	0.4	0.3	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274270	Soil	7	0.02	220	0.004	<1	0.36	0.004	0.04	<0.1	0.03	0.7	0.2	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274271	Soil	7	0.01	93	0.003	1	0.25	0.004	0.03	<0.1	0.01	0.2	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274272	Soil	6	0.01	59	0.003	1	0.19	0.005	0.03	<0.1	0.02	0.3	<0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274273	Soil	6	<0.01	37	0.003	2	0.21	0.007	0.02	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274274	Soil	6	0.02	71	0.004	2	0.24	0.009	0.02	<0.1	0.01	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274275	Soil	4	<0.01	33	0.003	<1	0.17	0.011	0.02	<0.1	0.01	0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274276	Soil	7	0.04	122	0.004	2	0.30	0.010	0.03	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274277	Soil	11	0.09	169	0.007	3	0.65	0.013	0.03	<0.1	0.06	0.5	0.1	0.06	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274278	Soil	6	0.06	187	0.004	<1	0.45	0.010	0.03	<0.1	0.07	0.4	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274279	Soil	20	0.14	412	0.005	4	1.07	0.007	0.09	0.1	0.63	3.6	0.7	<0.05	3	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274280	Soil	8	0.02	64	0.004	<1	0.26	0.008	0.03	0.1	0.03	0.2	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1274251	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274252	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274253	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274254	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274255	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274256	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274257	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274258	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274259	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274260	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274261	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274262	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274263	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274264	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274265	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274266	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274267	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274268	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274269	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274270	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274271	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274272	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274273	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274274	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274275	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274276	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274277	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274278	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274279	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274280	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274254	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274258	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274259	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274271	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274272	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274273	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274274	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274275	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274276	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274277	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274278	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274279	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274280	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274281	Soil	35.1	67.5	17.6	1154	1.5	177.6	9.6	279	4.41	48.7	4.2	1.9	37	3.3	8.6	0.3	81	0.56	0.122	15
1274282	Soil	5.6	12.4	5.1	41	0.3	7.8	1.5	25	0.76	11.9	4.4	<0.1	4	0.2	1.6	0.1	42	0.01	0.024	10
1274283	Soil	7.1	17.6	18.2	78	0.3	15.1	2.4	42	2.17	33.2	<0.5	0.4	16	0.1	3.4	0.4	76	0.01	0.059	10
1274284	Soil	12.0	41.8	24.8	115	0.7	27.2	4.2	77	2.98	37.6	1.7	0.3	24	0.3	6.5	0.4	87	0.04	0.148	10
1274285	Soil	3.7	8.8	3.9	33	0.3	5.1	1.1	17	0.60	10.8	1.2	0.1	7	<0.1	1.8	0.1	55	<0.01	0.023	16
1274286	Soil	9.3	38.7	24.1	139	0.4	26.5	4.9	50	1.88	25.1	<0.5	0.6	18	0.3	4.5	0.3	58	0.01	0.051	12
1274287	Soil	8.7	56.4	23.4	179	0.5	38.0	6.9	63	2.87	39.5	2.1	0.7	22	0.6	4.4	0.4	101	0.04	0.175	10
1274288	Soil	5.8	41.0	14.8	165	0.5	34.3	13.0	282	2.07	25.9	3.7	1.5	35	1.2	4.1	0.3	60	0.23	0.147	10
1274289	Soil	5.2	29.2	17.6	134	0.7	25.4	5.1	101	2.19	19.8	2.1	1.2	26	1.1	2.7	0.3	67	0.09	0.109	12
1274290	Soil	11.3	63.7	18.2	295	0.9	52.3	7.9	82	3.03	37.0	3.6	1.0	26	1.2	5.9	0.3	71	0.12	0.146	10
1274291	Soil	28.0	32.2	27.6	642	0.4	96.3	15.3	318	3.41	35.0	2.4	1.3	89	2.2	9.8	0.2	130	0.40	0.170	7
1274292	Soil	3.8	29.9	22.8	128	0.3	26.3	5.8	88	2.75	23.7	1.0	0.9	17	0.3	2.0	0.2	32	0.11	0.078	4
1274293	Soil	6.4	59.7	8.3	555	0.5	104.3	6.0	596	1.17	9.2	1.7	0.5	80	6.8	5.0	<0.1	40	1.39	0.085	3
1274294	Soil	8.0	37.8	19.4	552	0.5	92.5	10.5	210	2.42	22.5	1.4	2.3	133	3.2	5.7	0.1	66	1.57	0.179	6
1274295	Soil	3.7	39.3	20.5	440	0.6	89.4	8.1	344	2.48	20.9	1.8	1.8	65	3.2	3.3	0.2	44	0.82	0.107	7
1274296	Soil	4.7	44.7	11.5	323	0.5	60.7	6.2	202	1.46	13.9	1.7	0.8	78	6.4	5.0	0.1	41	0.66	0.096	4
1274297	Soil	4.7	49.2	22.4	437	0.7	76.4	7.8	216	2.59	15.9	2.5	1.8	95	6.8	3.7	0.2	54	0.75	0.121	7
1274298	Soil	3.7	33.6	12.9	204	0.7	38.7	4.9	180	1.82	14.2	2.9	0.6	86	1.9	2.5	0.1	32	0.84	0.092	4
1274299	Soil	4.2	22.2	17.3	192	0.4	34.4	6.8	231	2.09	15.3	1.8	1.5	63	0.6	2.4	0.1	39	0.56	0.125	7
1274300	Soil	2.8	33.2	13.1	133	0.1	31.6	7.4	90	2.46	19.8	<0.5	1.4	40	0.9	1.5	0.2	27	0.32	0.045	4
1274301	Soil	3.6	26.4	9.2	112	0.3	30.8	5.3	85	1.54	14.1	0.8	0.7	58	0.5	1.6	0.1	26	0.74	0.058	3
1274302	Soil	6.6	40.7	21.4	233	0.1	45.1	9.6	147	3.21	40.0	1.6	2.8	29	0.7	3.6	0.3	42	0.29	0.087	8
1274303	Soil	2.6	26.5	11.1	83	0.2	28.3	6.0	124	1.65	12.4	0.8	1.1	60	0.3	1.5	0.1	27	0.79	0.062	4
1274304	Soil	2.1	10.5	5.7	64	<0.1	12.0	3.3	44	1.12	10.4	<0.5	0.2	5	0.2	1.1	<0.1	21	0.03	0.028	3
1274305	Soil	12.8	82.9	29.9	385	0.9	100.1	11.8	201	3.96	191.9	6.3	2.9	107	1.4	11.8	0.3	67	0.53	0.183	12
1274306	Soil	0.9	24.5	8.0	44	0.3	20.1	6.4	116	0.67	5.2	0.8	0.3	57	0.6	1.0	0.1	12	0.75	0.071	3
1274307	Soil	3.9	25.6	18.9	87	0.3	19.2	8.3	186	1.60	13.0	1.4	1.1	20	1.4	1.5	0.2	36	0.09	0.047	4
1274308	Soil	6.9	63.7	32.4	115	0.9	24.0	5.7	134	3.24	38.0	7.6	1.0	96	0.4	4.7	0.4	76	0.04	0.115	15
1274309	Soil	5.4	86.9	17.1	142	0.4	26.9	5.9	146	3.73	21.1	2.4	0.2	38	0.5	3.1	0.3	86	0.04	0.124	7
1274310	Soil	4.5	157.0	21.7	403	0.7	77.4	19.4	544	3.73	30.8	4.1	2.0	123	2.9	3.7	0.4	115	0.10	0.156	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1274281	Soil	15	0.08	455	0.003	2	0.52	0.004	0.05	0.1	0.54	3.7	0.7	<0.05	1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274282	Soil	6	<0.01	71	0.004	<1	0.23	0.004	0.02	0.1	0.01	0.2	<0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274283	Soil	11	0.03	197	0.007	<1	0.54	0.003	0.05	0.1	0.03	0.8	0.2	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274284	Soil	15	0.05	194	0.006	1	0.62	0.003	0.05	0.1	0.03	0.9	0.3	<0.05	4	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274285	Soil	6	<0.01	129	0.007	1	0.20	0.005	0.02	0.1	0.01	0.2	<0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274286	Soil	7	0.02	134	0.008	<1	0.32	0.002	0.04	0.1	0.03	0.7	0.2	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274287	Soil	13	0.03	267	0.004	<1	0.44	0.002	0.06	0.1	0.06	1.4	0.3	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274288	Soil	11	0.05	2307	0.004	3	0.47	0.004	0.06	<0.1	0.08	1.6	0.2	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274289	Soil	20	0.13	691	0.008	3	0.86	0.004	0.08	0.2	0.10	1.8	0.3	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274290	Soil	13	0.05	2040	0.003	2	0.58	0.002	0.06	<0.1	0.11	1.9	0.3	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274291	Soil	24	0.08	528	0.003	1	0.65	0.004	0.04	0.2	0.22	2.7	0.3	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274292	Soil	17	0.16	518	0.003	<1	0.96	0.014	0.04	<0.1	0.11	1.6	0.3	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274293	Soil	11	0.21	334	0.005	3	0.44	0.021	0.04	<0.1	0.34	1.7	0.4	<0.05	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274294	Soil	17	0.43	803	0.004	4	0.65	0.007	0.07	<0.1	0.24	3.1	0.3	0.07	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274295	Soil	16	0.17	914	0.003	3	0.73	0.008	0.06	<0.1	0.26	3.2	0.2	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274296	Soil	12	0.11	483	0.005	2	0.62	0.015	0.04	<0.1	0.22	2.1	0.3	0.06	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274297	Soil	20	0.23	1026	0.004	2	0.98	0.007	0.07	<0.1	0.37	3.6	0.3	0.05	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274298	Soil	12	0.17	475	0.005	2	0.73	0.017	0.07	<0.1	0.26	1.8	0.2	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274299	Soil	15	0.20	878	0.005	2	0.86	0.009	0.05	<0.1	0.14	2.1	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274300	Soil	14	0.14	409	0.002	<1	0.79	0.008	0.06	<0.1	0.07	2.6	0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274301	Soil	10	0.13	344	0.003	<1	0.58	0.014	0.04	<0.1	0.11	2.1	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274302	Soil	16	0.17	294	0.002	1	0.64	0.003	0.05	<0.1	0.08	3.5	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274303	Soil	13	0.12	495	0.003	<1	0.75	0.012	0.06	<0.1	0.10	2.8	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274304	Soil	7	0.04	47	0.003	1	0.35	0.008	0.03	<0.1	<0.01	0.6	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274305	Soil	18	0.11	813	0.002	2	0.69	0.003	0.09	<0.1	0.35	6.4	0.3	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274306	Soil	8	0.14	211	0.003	1	0.46	0.020	0.04	<0.1	0.11	1.0	<0.1	0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274307	Soil	11	0.06	283	0.002	1	0.66	0.009	0.07	<0.1	0.14	2.1	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274308	Soil	30	0.09	214	0.010	<1	0.63	0.003	0.07	0.2	0.09	2.3	0.4	0.08	8	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274309	Soil	30	0.08	68	0.007	<1	0.82	0.002	0.04	0.2	0.11	1.3	0.2	<0.05	4	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274310	Soil	33	0.11	115	0.008	<1	0.95	0.004	0.04	<0.1	0.08	8.3	0.2	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1274281	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274282	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274283	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274284	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274285	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274286	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274287	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274288	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274289	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274290	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274291	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274292	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274293	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274294	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274295	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274296	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274297	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274298	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274299	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274300	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274301	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274302	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274303	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274304	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274305	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274306	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274307	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274308	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274309	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274310	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274281	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274282	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274283	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274284	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274286	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274287	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274288	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274289	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274290	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274291	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274292	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274293	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274294	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274295	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274296	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274297	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274298	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274299	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274300	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274301	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274302	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274303	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274304	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274305	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274306	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274307	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274308	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274309	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274310	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274311	Soil	9.3	58.8	19.1	188	0.2	49.4	12.2	305	2.86	22.0	1.6	0.2	20	1.0	4.6	0.6	71	0.05	0.130	10
1274312	Soil	5.3	56.2	20.6	175	0.4	45.6	20.9	1108	3.79	14.1	3.3	0.5	22	1.0	2.7	0.4	64	0.16	0.108	8
1274313	Soil	7.6	89.9	27.6	417	0.4	590.3	88.8	1402	9.16	16.6	<0.5	1.3	106	3.4	4.6	0.1	186	1.61	0.158	12
1274314	Soil	6.0	126.0	17.0	276	0.4	734.2	127.4	1348	8.88	12.0	1.2	3.4	168	0.8	3.2	0.1	162	2.37	0.344	14
1274315	Soil	9.6	140.4	15.6	191	0.4	564.0	112.9	1836	10.16	12.6	<0.5	3.2	249	0.5	3.3	<0.1	191	3.92	0.394	10
1274316	Soil	23.4	129.6	21.8	704	0.6	477.6	100.6	2015	12.18	18.6	<0.5	3.3	160	6.0	4.5	<0.1	246	2.52	0.336	7
1274317	Soil	46.7	120.1	19.7	745	0.8	423.1	74.0	1543	10.64	27.0	2.1	3.0	163	4.0	6.8	0.1	331	3.33	0.283	8
1274318	Soil	39.9	72.1	13.9	506	0.5	232.3	33.3	775	6.37	25.3	0.7	1.1	77	3.0	6.2	0.1	207	0.85	0.172	6
1274319	Soil	48.9	33.0	13.7	355	0.1	97.7	9.2	169	2.65	31.3	<0.5	0.2	15	1.6	8.4	0.1	149	0.15	0.096	4
1274320	Soil	32.3	32.5	10.7	286	0.4	84.4	6.9	293	2.25	15.9	<0.5	0.1	17	1.2	5.1	0.1	115	0.28	0.077	4
1274321	Soil	67.0	46.1	13.1	383	0.2	123.0	7.7	421	3.15	23.4	<0.5	0.1	15	3.0	8.2	0.1	257	0.23	0.136	4
1274322	Soil	61.6	44.5	10.1	512	0.4	84.8	3.3	102	1.40	29.8	0.6	0.1	26	5.9	10.5	0.1	244	0.47	0.095	3
1274323	Soil	115.7	112.7	18.3	1231	1.4	229.3	6.5	228	2.65	63.3	2.9	0.8	80	18.4	25.0	0.2	374	2.33	0.129	5
1274324	Soil	82.0	114.9	29.5	1718	0.6	239.9	17.9	464	5.02	29.1	3.4	2.3	128	12.9	16.2	0.2	223	3.63	0.171	12
1274325	Soil	79.0	67.1	21.4	618	0.4	201.4	10.5	422	3.97	24.9	<0.5	0.9	47	3.5	8.1	0.1	143	1.29	0.111	5
1274326	Soil	81.3	62.4	16.9	250	0.3	182.9	11.9	412	4.01	27.1	1.5	2.0	102	1.7	5.1	0.2	108	4.04	0.114	5
1274327	Soil	7.4	38.3	12.5	83	<0.1	48.1	11.5	198	2.95	30.6	1.6	0.2	3	<0.1	4.2	0.2	33	0.04	0.079	13
1274328	Soil	10.7	56.3	30.2	82	0.6	65.0	7.9	95	2.50	23.5	2.4	<0.1	36	0.2	3.5	0.3	56	0.05	0.182	9
1274329	Soil	16.0	68.7	62.7	134	1.2	57.9	6.3	57	3.17	21.0	1.1	0.2	151	0.5	5.2	0.5	126	0.17	0.315	17
1274330	Soil	8.5	26.2	30.5	92	0.4	29.8	4.2	94	1.56	10.0	0.6	<0.1	36	0.1	2.0	0.3	58	0.02	0.109	10
1274331	Soil	11.8	16.3	6.9	60	0.5	20.4	2.9	63	0.98	7.4	<0.5	<0.1	6	0.2	1.6	0.1	58	0.01	0.035	8
1274332	Soil	17.6	47.5	26.8	396	0.6	113.8	7.5	265	5.59	28.7	<0.5	0.4	28	4.5	5.5	0.1	99	0.07	0.181	10
1274333	Soil	3.3	12.1	18.8	25	0.8	7.2	1.1	11	0.78	7.9	2.6	0.1	12	<0.1	1.6	0.2	26	0.02	0.093	5
1274334	Soil	5.8	27.2	12.6	121	0.2	22.4	3.1	37	1.22	9.8	3.6	0.2	11	0.2	2.7	0.1	25	0.02	0.102	5
1274335	Soil	11.1	46.4	13.9	189	0.8	26.8	4.0	45	1.50	12.2	0.9	0.3	13	0.6	3.9	0.1	31	0.07	0.127	7
1274336	Soil	8.4	20.7	15.9	79	0.3	18.7	3.2	37	1.25	13.6	<0.5	<0.1	13	0.1	2.5	0.3	58	0.01	0.065	9
1274337	Soil	10.9	42.2	17.5	148	0.3	31.9	5.0	50	1.77	23.1	1.1	<0.1	10	0.2	4.5	0.2	47	0.02	0.072	6
1274338	Soil	13.8	113.4	16.8	224	0.2	67.5	12.6	92	3.59	29.4	4.8	0.4	11	0.3	6.3	0.2	60	0.03	0.094	9
1274339	Soil	9.1	51.1	11.4	131	1.0	29.3	4.1	70	1.32	14.3	2.0	<0.1	10	0.6	4.6	0.2	31	0.13	0.073	4
1274340	Soil	12.9	40.3	9.6	128	2.5	21.7	3.4	34	1.16	13.5	0.6	<0.1	11	0.5	3.9	0.1	30	0.12	0.094	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1274311	Soil	26	0.05	78	0.005	3	0.52	0.004	0.06	0.2	0.06	0.9	0.2	0.08	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274312	Soil	22	0.12	156	0.008	1	0.66	0.007	0.05	0.1	0.08	3.0	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274313	Soil	279	0.35	316	0.004	3	0.52	0.014	0.02	<0.1	0.24	19.3	0.3	0.08	1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274314	Soil	264	0.56	450	0.003	1	0.58	0.009	0.04	<0.1	0.16	21.1	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274315	Soil	245	0.97	792	0.003	<1	0.50	0.007	0.04	<0.1	0.11	20.9	0.3	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274316	Soil	256	1.04	537	0.002	2	0.60	0.006	0.04	<0.1	0.24	23.2	0.6	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274317	Soil	195	1.46	483	0.002	2	0.56	0.005	0.04	<0.1	0.26	18.5	0.7	<0.05	2	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274318	Soil	122	0.14	328	0.003	1	0.62	0.009	0.03	<0.1	0.20	10.7	0.4	0.06	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274319	Soil	17	0.04	132	0.002	<1	0.39	0.007	0.02	<0.1	0.10	1.0	0.4	<0.05	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274320	Soil	14	0.06	115	0.003	<1	0.61	0.019	0.02	<0.1	0.09	1.1	0.3	<0.05	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274321	Soil	20	0.03	207	0.002	<1	0.53	0.009	0.02	<0.1	0.02	0.6	0.5	<0.05	2	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274322	Soil	14	0.04	196	0.002	<1	0.44	0.009	0.04	0.1	0.12	0.7	0.7	<0.05	1	7.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274323	Soil	22	0.55	202	0.004	4	0.43	0.009	0.05	0.2	0.53	2.7	1.0	<0.05	1	9.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274324	Soil	30	1.56	346	0.003	5	0.40	0.006	0.04	0.1	0.41	4.9	1.0	0.09	1	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274325	Soil	19	0.37	250	0.002	2	0.39	0.006	0.03	<0.1	0.19	3.4	0.6	0.07	<1	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274326	Soil	16	1.80	299	0.002	3	0.24	0.007	0.03	<0.1	0.29	4.2	1.0	0.06	<1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1274327	Soil	6	0.02	290	0.004	<1	0.29	0.004	0.05	<0.1	0.02	0.8	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274328	Soil	13	0.03	228	<0.001	2	0.53	0.005	0.07	<0.1	0.02	0.1	0.2	0.11	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274329	Soil	15	0.02	395	0.002	<1	0.53	0.003	0.09	<0.1	0.04	0.2	0.2	0.12	3	5.3	0.2	N.A.	N.A.	N.A.	N.A.
1274330	Soil	9	0.02	130	0.002	1	0.48	0.006	0.05	<0.1	0.02	0.1	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274331	Soil	6	0.01	57	0.003	<1	0.32	0.010	0.03	<0.1	0.02	0.1	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274332	Soil	24	0.03	168	0.003	<1	0.41	0.006	0.05	0.1	0.06	1.2	0.5	<0.05	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274333	Soil	7	0.02	123	0.001	<1	0.42	0.002	0.02	<0.1	0.12	0.2	0.2	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274334	Soil	7	0.02	99	0.002	<1	0.34	0.010	0.04	<0.1	0.05	0.3	0.2	0.06	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1274335	Soil	6	0.02	2426	0.002	<1	0.54	0.008	0.05	<0.1	0.19	0.5	0.2	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1274336	Soil	9	0.02	157	0.002	<1	0.48	0.003	0.04	<0.1	0.03	0.2	0.3	<0.05	5	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1274337	Soil	9	0.02	93	0.002	<1	0.25	0.003	0.04	<0.1	0.04	0.4	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274338	Soil	13	0.02	218	0.002	<1	0.31	0.003	0.05	<0.1	0.04	1.2	0.2	<0.05	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274339	Soil	9	0.02	221	0.002	1	0.22	0.011	0.04	<0.1	0.09	0.4	0.1	0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274340	Soil	8	0.03	152	0.001	<1	0.35	0.008	0.05	<0.1	0.21	0.5	0.3	0.08	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1274311	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274320	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274323	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274326	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274327	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274328	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274329	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274330	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274331	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274332	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274333	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274334	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274335	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274336	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274338	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274340	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274311	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274320	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274323	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274326	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274327	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274328	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274329	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274330	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274331	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274332	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274333	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274334	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274335	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274336	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274338	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274340	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274341	Soil	15.1	76.7	13.9	183	4.0	26.4	3.6	81	1.78	19.3	4.3	0.3	12	1.1	5.3	0.2	39	0.28	0.232	5
1274342	Soil	15.6	87.5	13.7	289	1.7	49.6	7.0	167	2.81	28.5	1.8	0.8	24	1.9	6.8	0.2	54	0.48	0.257	9
1274343	Soil	12.8	72.5	17.4	201	1.2	41.0	6.0	124	2.66	27.5	4.0	0.9	22	1.5	6.2	0.2	55	0.36	0.212	9
1274344	Soil	16.0	86.1	26.4	236	0.4	52.9	9.7	203	3.92	41.8	4.7	1.2	30	0.8	8.8	0.2	75	0.30	0.256	13
1274345	Soil	15.7	142.1	26.4	250	1.7	76.8	11.0	271	5.32	67.0	9.1	0.6	24	1.5	11.6	0.2	58	0.58	0.283	13
1274346	Soil	19.3	54.0	19.4	204	0.3	44.9	5.4	64	2.61	28.5	<0.5	<0.1	15	0.7	5.3	0.2	88	0.06	0.104	8
1274347	Soil	14.1	43.6	23.0	159	0.3	33.7	5.2	87	2.64	30.2	4.0	<0.1	24	0.3	5.4	0.3	81	0.03	0.142	8
1274349	Soil	11.8	29.6	24.3	277	1.1	37.4	60.5	1992	4.35	28.7	8.4	0.7	27	1.5	4.3	0.3	72	0.09	0.088	7
1274350	Soil	11.2	21.4	20.0	81	1.7	11.5	7.6	252	2.25	26.1	12.8	0.4	26	0.1	4.4	0.2	57	0.01	0.056	9
1276111	Soil	102.4	199.2	19.1	1622	3.6	235.3	6.2	219	2.29	50.9	5.9	1.3	156	58.4	22.0	0.2	867	5.90	0.286	20
1276112	Soil	9.1	17.3	8.3	307	0.5	34.1	3.2	101	0.91	12.2	2.8	<0.1	24	3.7	2.2	0.1	106	0.31	0.084	6
1276113	Soil	19.3	27.0	17.3	243	0.7	43.6	5.5	135	2.67	29.7	7.8	0.4	26	0.9	5.9	0.2	145	0.04	0.061	10
1276114	Soil	12.7	10.0	10.1	80	0.5	15.8	2.0	29	0.90	10.9	3.3	<0.1	12	<0.1	2.2	0.1	78	0.01	0.055	6
1276115	Soil	6.1	4.3	5.6	28	0.1	4.4	0.8	14	0.40	5.6	3.3	<0.1	10	<0.1	1.2	<0.1	44	<0.01	0.026	10
1276116	Soil	18.7	27.7	11.9	1721	0.9	130.8	5.0	200	2.08	19.5	7.6	0.5	61	13.0	4.8	0.1	175	0.67	0.138	8
1276117	Soil	26.0	75.6	51.5	187	0.9	73.6	8.3	67	2.80	21.0	5.4	0.1	81	0.3	7.2	0.4	160	0.07	0.170	12
1276118	Soil	17.6	82.4	30.5	188	1.5	85.7	7.1	143	2.38	17.2	4.1	0.1	73	0.9	6.4	0.3	128	0.35	0.322	15
1276119	Soil	13.0	129.0	17.5	319	1.3	177.2	8.4	70	2.53	19.6	5.9	0.2	49	0.5	6.0	0.3	82	0.23	0.289	16
1276120	Soil	19.3	286.5	28.2	488	4.0	254.2	18.5	395	4.63	36.1	6.0	1.6	102	1.9	8.8	0.5	189	0.72	0.861	18
1276121	Soil	19.6	304.7	30.1	507	4.0	272.9	20.2	415	4.88	38.7	8.8	1.7	101	1.7	8.9	0.5	202	0.78	0.904	18
1276122	Soil	5.2	28.7	6.1	60	0.8	41.2	5.5	203	1.40	18.6	3.0	<0.1	12	0.4	6.5	<0.1	31	0.11	0.124	6
1276123	Soil	13.4	43.5	10.1	168	0.2	36.0	5.6	160	1.70	13.7	6.1	<0.1	12	0.4	3.9	0.2	50	0.06	0.129	6
1276124	Soil	24.3	83.8	20.7	279	0.3	59.8	10.3	291	3.68	23.3	4.0	0.1	16	0.6	6.8	0.2	78	0.11	0.207	8
1276125	Soil	11.1	172.2	36.9	292	2.6	65.4	27.7	980	5.75	24.9	12.2	1.8	30	2.2	7.2	0.3	39	0.40	0.350	17
1276126	Soil	13.5	105.5	55.4	364	2.1	137.9	13.4	169	3.92	49.1	5.0	0.2	153	1.5	7.9	0.3	75	0.22	0.322	16
1276127	Soil	22.8	106.5	53.4	496	2.0	243.7	26.0	1517	5.90	52.1	4.5	<0.1	153	1.6	8.4	0.3	165	0.33	0.477	21
1276128	Soil	23.7	77.9	118.6	380	1.6	107.0	12.7	344	4.57	49.6	6.0	0.4	140	0.7	14.4	0.5	95	0.09	0.288	22
1276129	Soil	36.9	71.0	47.1	189	1.6	50.7	15.5	693	3.05	38.2	1.5	0.1	330	1.0	9.2	0.3	202	0.32	0.508	19
1276130	Soil	29.5	100.2	50.9	200	2.5	78.4	5.9	102	3.20	67.8	7.0	0.1	186	1.5	15.2	0.3	149	0.39	0.504	19
1276141	Soil	19.6	4.1	9.6	6	0.4	2.3	0.2	11	0.54	8.0	3.5	0.4	4	<0.1	12.5	0.2	60	<0.01	0.021	29

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1274341	Soil	7	0.02	330	0.002	2	0.41	0.007	0.07	0.2	0.60	0.8	0.2	0.06	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1274342	Soil	12	0.04	647	0.003	3	0.56	0.004	0.10	<0.1	0.40	2.4	0.2	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274343	Soil	13	0.05	635	0.003	2	0.59	0.005	0.10	<0.1	0.32	2.4	0.3	0.07	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274344	Soil	17	0.08	547	0.004	2	0.62	0.002	0.08	0.1	0.10	2.1	0.3	0.08	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1274345	Soil	15	0.07	923	0.002	1	0.52	0.003	0.06	<0.1	0.33	2.7	0.3	0.08	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1274346	Soil	10	0.02	241	0.002	2	0.31	0.004	0.05	<0.1	0.07	0.4	0.3	0.12	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1274347	Soil	11	0.02	271	0.001	2	0.51	0.002	0.05	<0.1	0.04	0.3	0.3	<0.05	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1274349	Soil	12	0.06	787	0.003	3	0.58	0.005	0.06	<0.1	0.17	1.1	0.6	<0.05	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1274350	Soil	11	0.04	343	0.003	2	0.46	0.003	0.06	0.2	0.39	0.5	1.2	0.06	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276111	Soil	78	3.24	717	0.004	7	0.46	0.010	0.10	0.6	4.27	3.0	2.0	0.07	1	10.8	0.3	N.A.	N.A.	N.A.	N.A.
1276112	Soil	10	0.05	395	0.005	1	0.56	0.014	0.03	0.1	0.13	0.3	0.6	0.06	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276113	Soil	22	0.19	298	0.007	3	0.84	0.003	0.07	0.2	0.32	0.8	0.6	<0.05	4	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276114	Soil	7	0.02	138	0.002	2	0.40	0.006	0.03	0.1	0.03	0.2	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276115	Soil	5	<0.01	107	0.003	1	0.18	0.003	0.02	0.8	0.01	0.1	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276116	Soil	20	0.10	784	0.004	3	0.74	0.008	0.05	0.1	0.57	1.4	1.0	0.07	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276117	Soil	16	0.02	196	0.002	2	0.41	0.004	0.08	0.1	0.07	0.2	0.2	0.09	2	6.6	0.3	N.A.	N.A.	N.A.	N.A.
1276118	Soil	21	0.02	204	0.002	3	0.43	0.003	0.09	<0.1	0.15	0.3	0.3	0.08	2	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276119	Soil	20	0.03	169	0.003	4	0.41	0.003	0.08	0.1	0.23	0.6	0.2	0.06	2	7.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276120	Soil	30	0.05	213	0.007	3	0.58	0.007	0.14	0.2	0.70	3.2	0.3	0.15	2	13.6	0.3	N.A.	N.A.	N.A.	N.A.
1276121	Soil	32	0.05	225	0.007	5	0.62	0.008	0.16	0.2	0.80	4.0	0.3	0.18	2	14.3	0.3	N.A.	N.A.	N.A.	N.A.
1276122	Soil	10	0.02	76	<0.001	<1	0.46	0.016	0.03	<0.1	0.08	0.3	<0.1	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276123	Soil	11	0.02	95	<0.001	1	0.38	0.009	0.05	<0.1	0.02	0.2	0.1	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276124	Soil	16	0.04	120	0.002	2	0.38	0.003	0.06	<0.1	0.05	0.3	0.2	<0.05	2	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276125	Soil	12	0.08	341	0.005	3	0.58	0.005	0.11	<0.1	0.13	3.2	0.4	<0.05	2	8.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276126	Soil	22	0.02	506	0.001	2	0.38	0.003	0.09	0.1	0.14	0.5	0.2	0.13	1	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276127	Soil	31	0.03	406	0.003	1	0.47	0.004	0.10	0.1	0.09	0.4	0.4	0.19	1	8.9	0.3	N.A.	N.A.	N.A.	N.A.
1276128	Soil	15	0.02	591	0.002	2	0.45	0.003	0.11	0.2	0.09	0.5	0.3	0.17	2	6.1	0.3	N.A.	N.A.	N.A.	N.A.
1276129	Soil	23	0.05	1580	0.003	2	0.74	0.005	0.10	0.2	0.05	0.3	0.4	0.12	3	5.9	0.4	N.A.	N.A.	N.A.	N.A.
1276130	Soil	21	0.05	917	0.002	2	0.55	0.003	0.13	0.3	0.15	0.2	0.3	0.12	2	7.7	0.3	N.A.	N.A.	N.A.	N.A.
1276141	Soil	4	<0.01	84	0.003	1	0.20	<0.001	0.04	<0.1	0.03	0.2	0.2	<0.05	1	4.7	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1274341	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274342	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274343	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274344	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274345	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274346	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274347	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274349	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274350	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276141	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274341	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274342	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274343	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274344	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274345	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274346	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274347	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274349	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1274350	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276141	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276142	Soil		19.4	122.8	25.4	53	1.3	14.8	2.1	50	2.32	36.6	1.7	3.8	61	0.3	5.6	0.3	264	0.02	0.216	15
1276143	Soil		16.6	38.2	25.3	57	1.3	13.8	1.8	40	1.70	26.3	6.1	0.3	32	0.1	5.4	0.3	125	0.03	0.117	20
1276144	Soil		12.4	16.1	37.8	65	0.8	15.7	2.8	53	1.67	27.8	3.0	<0.1	35	0.1	3.6	0.3	105	0.02	0.090	8
1276145	Soil		10.2	13.1	15.4	63	0.4	14.4	1.9	27	1.24	12.8	1.7	<0.1	17	<0.1	2.4	0.2	77	0.02	0.071	8
1276146	Soil		18.5	21.9	18.5	130	0.4	29.7	3.3	67	1.93	24.9	<0.5	<0.1	25	0.2	4.5	0.3	126	0.02	0.094	12
1276147	Soil		43.4	26.5	13.4	230	0.4	67.0	4.6	50	1.87	31.6	2.5	<0.1	13	0.1	7.9	0.2	177	<0.01	0.060	10
1276148	Soil		6.2	5.8	14.6	22	0.4	6.3	0.6	10	0.59	5.7	2.0	0.1	12	<0.1	1.3	0.1	30	0.01	0.046	9
1276149	Soil		32.7	39.3	18.8	398	0.3	66.7	5.3	86	3.48	60.9	5.2	0.2	32	1.9	6.4	0.2	270	0.05	0.373	7
1276150	Soil		4.3	6.9	6.5	32	0.7	8.7	1.1	13	0.57	6.4	1.7	<0.1	12	<0.1	1.0	<0.1	35	0.02	0.060	4
1276151	Soil		3.2	9.9	5.3	16	2.0	3.7	0.7	15	0.84	11.3	2.1	<0.1	10	<0.1	2.3	<0.1	42	<0.01	0.030	3
1276152	Soil		9.6	7.6	9.8	25	0.3	7.5	1.2	21	0.97	15.3	2.6	0.2	21	<0.1	3.9	0.1	112	0.01	0.042	4
1276153	Soil		7.0	24.1	21.0	23	9.6	7.2	1.5	51	1.59	13.3	11.3	<0.1	29	<0.1	2.8	0.3	59	0.02	0.097	4
1276154	Soil		8.1	13.7	15.3	46	0.9	9.9	2.3	43	1.44	14.6	2.3	0.2	21	0.1	3.0	0.3	97	0.01	0.040	11
1276155	Soil		3.6	6.5	4.6	24	0.4	6.9	1.4	25	0.59	4.6	<0.5	<0.1	7	<0.1	0.9	<0.1	37	0.01	0.028	6
1276156	Soil		8.6	8.8	17.3	34	0.8	7.1	1.3	27	0.88	12.9	<0.5	<0.1	17	<0.1	2.4	0.2	84	<0.01	0.037	10
1276157	Soil		4.9	6.0	4.8	27	0.4	4.7	1.2	22	0.54	6.7	<0.5	<0.1	10	<0.1	1.4	<0.1	62	<0.01	0.020	9
1276158	Soil		10.0	12.3	9.7	41	1.8	7.9	1.5	32	1.06	15.6	<0.5	0.6	14	0.1	3.8	0.1	101	<0.01	0.036	5
1276159	Soil		13.2	22.6	16.4	63	1.3	7.7	1.3	35	8.39	55.2	2.1	0.4	40	<0.1	6.3	0.1	237	0.01	0.300	3
1276160	Soil		12.8	18.2	16.3	32	1.0	7.1	0.6	16	3.29	26.9	<0.5	0.2	40	<0.1	5.7	0.1	125	<0.01	0.142	1
1276161	Soil		12.3	23.7	14.0	77	1.5	11.1	1.9	43	7.53	60.2	1.8	0.5	39	0.2	6.8	0.1	287	0.03	0.325	4
1276162	Soil		11.6	35.0	17.2	231	0.7	29.5	4.3	57	5.22	49.6	<0.5	0.7	17	0.8	3.2	0.2	144	0.03	0.175	4
1276163	Soil		6.6	13.6	4.7	39	1.2	4.3	0.4	10	12.43	175.4	<0.5	<0.1	6	0.1	10.4	<0.1	749	0.02	0.859	<1
1276164	Soil		8.3	21.5	9.9	33	0.8	7.1	0.9	17	10.07	65.1	0.7	0.1	25	0.2	3.8	<0.1	180	0.02	0.256	2
1276165	Soil		6.7	58.3	7.6	194	1.9	7.4	0.9	18	27.94	87.2	3.7	0.9	9	0.1	7.1	<0.1	625	0.01	0.747	2
1276166	Soil		11.2	36.3	20.1	87	1.3	12.9	2.1	29	4.58	81.4	6.6	0.5	25	0.3	8.3	0.2	112	0.02	0.229	3
1276167	Soil		9.0	13.6	15.4	52	0.4	12.5	2.7	41	1.80	34.9	2.1	0.2	23	0.2	3.1	0.1	51	0.01	0.075	5
1276168	Soil		72.1	7.4	9.1	28	1.6	13.5	1.1	55	2.80	58.8	2.6	<0.1	10	0.4	10.1	<0.1	55	0.04	0.119	4
1276169	Soil		4.0	3.6	3.6	10	1.1	4.8	0.5	13	0.32	3.3	<0.5	<0.1	6	<0.1	0.6	<0.1	19	0.02	0.027	8
1276170	Soil		2.0	1.7	1.5	6	0.2	1.3	0.3	<1	0.13	1.4	1.2	<0.1	3	<0.1	0.5	<0.1	12	<0.01	0.013	5
1276171	Soil		19.3	10.2	7.7	45	0.3	9.0	1.5	24	0.75	15.3	<0.5	<0.1	11	0.1	2.9	<0.1	72	0.02	0.038	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276142	Soil	28	0.10	552	0.012	4	2.94	0.002	0.09	0.2	0.60	2.5	0.7	0.11	3	7.2	0.2	N.A.	N.A.	N.A.	N.A.
1276143	Soil	18	0.07	590	0.004	2	0.78	0.002	0.07	<0.1	0.47	0.7	0.9	<0.05	3	7.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276144	Soil	16	0.04	569	0.005	1	0.69	0.008	0.09	0.1	0.10	0.3	0.7	0.06	4	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276145	Soil	9	0.03	257	0.004	<1	0.61	0.007	0.05	<0.1	0.05	0.1	0.3	<0.05	4	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276146	Soil	15	0.05	245	0.006	1	0.78	0.004	0.07	0.1	0.08	0.2	0.7	<0.05	5	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276147	Soil	11	0.02	156	0.002	<1	0.36	0.003	0.04	0.1	0.04	0.1	0.6	<0.05	2	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276148	Soil	5	0.01	183	0.003	1	0.27	0.011	0.06	<0.1	0.01	0.1	0.4	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276149	Soil	43	0.06	216	0.003	<1	1.60	0.003	0.04	0.1	0.28	0.3	0.5	<0.05	3	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276150	Soil	5	0.01	86	0.002	1	0.20	0.013	0.02	<0.1	0.02	<0.1	0.6	<0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276151	Soil	5	0.01	122	0.007	<1	0.36	0.016	0.02	<0.1	0.02	<0.1	0.1	<0.05	3	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276152	Soil	11	<0.01	675	0.002	<1	0.15	0.003	0.04	0.1	0.04	0.5	0.2	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276153	Soil	15	0.06	297	0.003	2	0.72	0.013	0.06	0.1	0.54	0.2	0.4	0.06	5	8.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276154	Soil	14	0.03	190	0.009	2	0.59	0.006	0.04	0.1	0.03	0.3	0.2	<0.05	6	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276155	Soil	11	0.01	98	0.003	2	0.16	0.012	0.02	<0.1	<0.01	0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276156	Soil	10	0.02	241	0.006	3	0.49	0.006	0.05	0.1	0.01	0.2	0.3	<0.05	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276157	Soil	8	<0.01	232	0.003	3	0.17	0.002	0.02	<0.1	0.01	0.3	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276158	Soil	13	0.02	335	0.006	2	0.46	0.007	0.04	<0.1	0.07	0.7	0.2	<0.05	3	2.3	0.2	N.A.	N.A.	N.A.	N.A.
1276159	Soil	27	0.03	569	0.003	3	0.34	0.005	0.08	<0.1	0.21	1.1	0.6	0.16	2	6.0	0.2	N.A.	N.A.	N.A.	N.A.
1276160	Soil	18	0.01	561	0.001	3	0.21	0.004	0.08	<0.1	0.19	0.6	0.7	0.14	1	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276161	Soil	30	0.03	1039	0.004	2	0.36	0.004	0.07	<0.1	0.18	1.4	0.4	0.11	2	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276162	Soil	21	0.03	379	0.001	3	0.51	0.004	0.05	<0.1	0.26	2.3	1.1	0.07	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276163	Soil	100	0.01	58	0.005	2	0.31	0.009	0.02	<0.1	0.22	0.7	0.4	0.24	1	7.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276164	Soil	19	0.03	322	0.002	3	0.27	0.005	0.04	<0.1	0.19	0.9	0.9	0.22	2	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276165	Soil	46	0.02	80	0.006	2	1.28	0.003	0.01	<0.1	0.40	4.5	0.9	0.14	1	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276166	Soil	18	0.02	551	0.002	2	0.59	0.004	0.05	<0.1	1.32	2.3	1.5	0.07	1	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276167	Soil	10	0.02	254	0.002	2	0.33	0.006	0.05	<0.1	0.21	0.3	0.6	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276168	Soil	9	0.02	122	0.002	3	0.31	0.017	0.04	<0.1	1.03	0.1	0.8	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276169	Soil	9	0.01	65	0.004	2	0.17	0.017	0.02	<0.1	0.02	0.2	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276170	Soil	4	0.01	33	0.003	2	0.14	0.007	0.02	<0.1	0.02	<0.1	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276171	Soil	9	0.02	134	0.002	2	0.29	0.004	0.04	0.1	0.04	0.1	0.8	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276142	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276143	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276144	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276145	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276146	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276147	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276148	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276149	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276150	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276151	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276152	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276153	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276154	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276155	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276156	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276157	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276158	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276159	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276160	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276161	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276162	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276163	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276164	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276165	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276142	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276143	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276144	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276145	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276146	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276147	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276148	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276149	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276150	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276151	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276152	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276153	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276154	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276155	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276156	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276157	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276158	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276159	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276160	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276161	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276162	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276163	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276164	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276165	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276166	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276167	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276168	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276169	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276170	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276172	Soil	10.6	10.3	3.8	45	0.2	9.0	1.4	21	0.63	8.0	<0.5	<0.1	6	<0.1	3.1	<0.1	70	<0.01	0.022	11
1276173	Soil	136.4	41.2	170.3	144	16.2	32.5	3.0	38	3.74	92.9	47.9	0.2	122	0.9	41.0	0.9	440	0.07	0.335	10
1276174	Soil	17.5	45.6	21.6	586	2.8	131.3	1.8	91	1.21	28.5	8.4	0.1	43	13.8	10.8	<0.1	198	0.26	0.127	4
1276175	Soil	4.9	28.6	5.9	853	0.6	114.4	1.8	92	0.75	10.0	<0.5	0.1	36	25.8	3.2	<0.1	107	0.53	0.106	4
1276176	Soil	50.9	45.3	14.0	609	0.3	102.7	4.8	40	2.00	41.5	<0.5	0.7	16	1.3	17.1	<0.1	370	0.02	0.093	15
1276177	Soil	58.6	31.8	11.0	559	0.1	87.9	3.9	36	2.21	33.0	<0.5	0.4	11	0.9	7.9	<0.1	247	0.02	0.059	17
1276178	Soil	21.3	28.3	10.1	300	0.4	59.8	3.4	75	1.43	22.0	3.0	0.4	34	1.7	5.2	<0.1	132	0.28	0.084	9
1276179	Soil	43.1	37.1	9.9	315	0.2	87.1	4.9	33	1.64	31.7	<0.5	1.1	32	1.1	7.4	<0.1	133	0.10	0.100	18
1276180	Soil	42.5	49.3	12.0	453	0.3	87.6	4.2	35	1.84	39.7	2.9	0.7	47	1.8	11.4	<0.1	172	0.10	0.137	17
1276181	Soil	75.7	99.2	15.6	2040	0.4	136.5	4.3	61	3.86	119.0	<0.5	0.3	35	3.8	24.3	<0.1	832	0.12	0.175	14
1276182	Soil	46.4	41.2	18.2	459	0.5	84.4	5.4	89	3.08	69.1	<0.5	0.4	38	1.6	10.2	0.1	300	0.05	0.145	15
1276183	Soil	27.1	33.9	13.8	276	1.0	54.1	3.4	43	1.77	36.2	<0.5	0.4	33	1.8	9.5	<0.1	176	0.05	0.085	14
1276184	Soil	33.6	50.5	15.0	373	1.0	74.2	4.0	46	2.06	40.2	1.0	0.5	47	1.9	10.3	<0.1	235	0.08	0.134	12
1276185	Soil	21.5	17.9	11.6	140	0.3	28.9	2.2	26	1.05	16.1	0.6	0.3	14	0.2	4.0	<0.1	104	<0.01	0.051	15
1276186	Soil	10.8	9.4	10.9	62	0.3	13.6	1.2	16	0.65	13.9	<0.5	<0.1	25	<0.1	1.9	<0.1	76	<0.01	0.033	14
1276187	Soil	6.8	10.2	5.2	51	0.8	9.4	1.7	19	0.70	11.5	<0.5	0.2	7	0.2	2.0	<0.1	55	<0.01	0.022	17
1276188	Soil	14.2	25.9	20.3	129	1.2	24.2	3.1	32	1.73	48.5	<0.5	0.3	38	0.4	6.1	0.2	111	0.01	0.080	21
1276189	Soil	20.4	18.2	9.7	132	1.3	22.4	2.1	27	1.23	23.5	<0.5	0.2	11	0.2	7.1	<0.1	110	<0.01	0.034	16
1276190	Soil	26.6	38.8	19.4	240	0.5	36.5	5.1	49	3.36	90.9	1.7	1.7	66	0.7	10.2	0.3	181	0.01	0.114	15
1276191	Soil	23.2	39.7	18.7	209	0.5	36.2	5.7	55	2.65	75.5	2.1	0.6	47	0.5	9.4	0.3	149	0.01	0.097	14
1276192	Soil	18.3	37.1	14.9	182	0.5	32.6	3.8	46	2.19	52.6	2.1	0.2	52	0.7	7.3	0.2	128	0.02	0.125	9
1276193	Soil	8.5	17.8	15.3	122	<0.1	22.9	6.7	69	2.09	17.8	1.2	0.4	11	0.2	3.2	0.2	72	<0.01	0.057	9
1276194	Soil	8.6	38.7	19.8	156	1.8	28.3	4.5	59	1.92	24.1	2.2	0.8	35	0.7	4.6	0.2	77	0.18	0.102	7
1276195	Soil	8.8	33.4	18.2	158	0.4	24.9	3.5	41	1.69	17.4	1.0	<0.1	20	0.6	4.2	0.2	78	0.03	0.115	8
1276196	Soil	12.6	23.8	19.1	124	0.3	20.8	3.4	46	1.37	24.3	1.4	0.1	11	0.2	10.0	0.1	44	0.07	0.048	3
1276197	Soil	13.5	61.3	24.7	313	1.3	48.8	9.6	269	2.51	33.1	4.4	1.1	34	3.0	10.3	0.3	76	0.41	0.137	6
1276198	Soil	15.6	95.9	86.0	475	3.4	95.2	7.5	467	3.47	46.4	12.5	1.1	90	2.9	19.1	0.2	139	1.54	0.160	7
1276199	Soil	19.6	57.0	29.6	224	1.6	53.8	5.0	81	2.43	36.8	6.6	0.5	57	1.0	7.2	0.2	161	0.08	0.198	7
1276200	Soil	14.4	37.3	23.7	174	0.8	35.4	4.0	59	1.88	23.8	5.7	0.2	46	0.7	5.2	0.2	110	0.14	0.127	9
1276201	Soil	2.1	20.4	8.9	48	0.5	9.7	2.6	43	1.00	7.0	1.4	0.1	6	0.1	0.9	0.2	31	<0.01	0.043	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276172	Soil	9	0.01	97	0.004	3	0.18	0.008	0.03	<0.1	<0.01	0.2	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276173	Soil	45	0.05	414	0.002	6	1.11	0.008	0.29	0.9	8.74	0.4	7.4	0.35	7	35.5	0.7	N.A.	N.A.	N.A.	N.A.
1276174	Soil	22	0.05	746	0.003	4	0.77	0.022	0.09	0.2	1.28	0.3	2.2	<0.05	3	4.9	0.2	N.A.	N.A.	N.A.	N.A.
1276175	Soil	14	0.05	511	0.005	3	0.72	0.022	0.04	<0.1	0.30	0.3	0.5	0.06	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276176	Soil	24	0.04	815	0.003	5	0.52	0.005	0.07	0.2	0.14	0.6	0.5	<0.05	2	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276177	Soil	23	0.07	250	0.004	4	0.74	0.004	0.08	0.2	0.07	0.5	1.1	<0.05	4	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276178	Soil	17	0.07	1704	0.004	4	0.72	0.012	0.07	0.2	0.20	1.0	0.8	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276179	Soil	15	0.05	985	0.002	3	0.42	0.002	0.07	0.2	0.10	1.2	0.8	<0.05	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276180	Soil	19	0.04	2309	0.002	5	0.43	0.003	0.07	0.2	0.17	1.2	0.6	<0.05	2	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276181	Soil	46	0.08	590	0.002	5	0.69	0.006	0.09	0.3	1.10	0.9	1.1	<0.05	4	3.3	0.2	N.A.	N.A.	N.A.	N.A.
1276182	Soil	36	0.08	709	0.003	5	0.77	0.004	0.11	0.2	0.12	1.0	1.0	<0.05	4	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276183	Soil	19	0.03	2135	0.003	4	0.38	0.003	0.07	0.1	0.30	0.8	0.5	<0.05	2	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276184	Soil	26	0.05	2231	0.003	4	0.57	0.004	0.09	0.2	0.38	1.4	0.6	<0.05	2	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276185	Soil	13	0.02	232	0.003	3	0.24	0.008	0.05	0.1	0.05	0.1	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276186	Soil	12	0.02	144	0.004	2	0.35	0.007	0.04	<0.1	0.03	0.2	0.3	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276187	Soil	7	0.02	117	0.006	3	0.23	0.004	0.05	<0.1	<0.01	0.2	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276188	Soil	15	0.03	232	0.008	2	0.52	0.002	0.07	<0.1	0.02	0.7	0.3	<0.05	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276189	Soil	9	0.01	149	0.007	3	0.21	0.004	0.04	<0.1	0.03	0.4	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276190	Soil	19	0.02	332	0.004	2	0.48	0.002	0.07	0.1	0.05	1.7	0.4	<0.05	4	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276191	Soil	15	0.02	293	0.002	1	0.48	0.002	0.05	0.1	0.05	0.9	0.3	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276192	Soil	17	0.02	882	0.002	2	0.49	0.005	0.05	<0.1	0.12	0.4	0.3	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276193	Soil	10	0.02	118	0.002	2	0.33	0.003	0.03	<0.1	0.03	0.8	0.1	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276194	Soil	13	0.06	1096	0.003	2	0.58	0.009	0.05	<0.1	0.30	1.7	0.3	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276195	Soil	13	0.02	404	0.003	1	0.44	0.003	0.04	<0.1	0.05	0.2	0.2	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276196	Soil	6	0.02	139	<0.001	2	0.19	0.003	0.02	<0.1	0.06	0.5	0.2	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276197	Soil	14	0.04	1225	0.002	2	0.47	0.004	0.05	<0.1	0.39	2.6	0.3	<0.05	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276198	Soil	26	0.17	2128	0.002	4	0.94	0.007	0.08	0.1	0.98	3.3	0.5	0.08	3	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276199	Soil	26	0.07	944	0.002	2	0.80	0.006	0.11	0.1	0.68	1.3	0.7	0.07	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276200	Soil	16	0.05	668	0.002	<1	0.43	0.003	0.07	0.1	0.24	0.6	0.5	0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276201	Soil	9	0.02	88	0.009	1	0.59	0.008	0.04	<0.1	0.02	0.4	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276174	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276175	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276176	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276178	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276180	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276172	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276173	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276174	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276175	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276176	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276177	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276178	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276179	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276180	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276202	Soil	3.7	27.8	15.0	107	1.9	18.9	4.9	87	2.27	13.8	2.2	0.1	7	0.2	1.6	0.3	55	0.02	0.061	7
1276203	Soil	2.4	15.3	7.2	55	0.4	9.0	2.9	46	1.00	6.9	1.0	<0.1	5	<0.1	0.9	0.2	34	<0.01	0.040	7
1276204	Soil	4.3	24.5	19.0	90	1.8	15.9	4.3	85	3.70	26.0	1.4	0.9	8	0.2	2.3	0.4	66	0.02	0.076	8
1276205	Soil	4.4	31.2	10.1	133	0.5	20.7	5.8	95	2.24	17.5	<0.5	0.2	4	0.2	2.1	0.2	60	<0.01	0.053	7
1276206	Soil	3.7	15.8	5.4	59	1.2	9.5	2.6	42	0.94	10.2	1.7	<0.1	5	0.5	1.5	<0.1	32	<0.01	0.038	10
1276207	Soil	6.6	22.8	14.8	82	0.4	14.8	3.2	53	1.51	14.8	1.2	0.1	10	0.5	2.5	0.2	51	0.01	0.062	9
1276208	Soil	10.9	58.9	20.3	398	0.7	70.5	12.3	337	3.66	32.4	4.6	2.3	26	2.7	6.9	0.3	42	0.17	0.112	12
1276209	Soil	10.2	66.3	42.0	522	0.8	79.0	14.0	369	3.64	67.9	6.9	2.1	37	4.4	12.8	0.4	49	0.41	0.147	11
1276210	Soil	1.5	17.7	4.4	61	0.7	14.1	1.6	81	0.53	3.5	1.7	0.2	80	0.9	1.0	<0.1	10	1.41	0.065	2
1276211	Soil	3.9	10.5	3.5	34	0.2	5.7	1.1	15	0.52	9.8	1.3	<0.1	4	<0.1	1.6	<0.1	29	0.02	0.038	9
1276212	Soil	6.6	29.0	4.9	403	0.6	106.1	54.8	5014	2.27	17.1	1.8	0.2	123	5.6	3.4	<0.1	19	2.59	0.116	2
1276213	Soil	8.8	31.0	17.4	112	0.2	20.6	3.8	39	1.87	29.4	2.3	<0.1	10	0.3	4.9	0.3	57	<0.01	0.070	8
1276214	Soil	0.2	1.3	1.0	4	0.2	1.2	0.3	7	0.11	<0.5	<0.5	<0.1	5	<0.1	<0.1	<0.1	4	0.03	0.020	<1
1276215	Soil	0.3	1.5	0.8	4	0.7	1.1	0.3	7	0.12	<0.5	<0.5	<0.1	5	<0.1	<0.1	<0.1	4	0.02	0.022	<1
1276216	Soil	5.9	13.1	4.7	30	1.3	6.1	1.4	18	0.54	7.4	0.7	0.3	12	0.1	1.6	<0.1	31	0.01	0.024	12
1276217	Soil	9.6	17.1	8.5	49	1.8	8.9	1.5	21	0.75	12.1	1.5	0.1	12	0.1	3.5	0.1	43	0.02	0.040	5
1276218	Soil	3.0	17.4	7.5	32	0.8	7.1	1.4	19	0.62	7.6	1.1	<0.1	9	0.3	1.2	0.1	25	0.01	0.040	5
1276219	Soil	5.6	32.6	13.6	113	0.9	21.5	3.7	42	1.62	20.5	2.2	<0.1	16	0.6	3.0	0.2	54	0.04	0.067	8
1276220	Soil	4.7	37.6	16.2	172	1.0	34.1	7.0	119	2.04	23.2	5.5	0.6	31	1.0	3.7	0.3	55	0.22	0.118	9
1276251	Soil	4.8	38.4	12.7	89	2.0	23.2	3.0	58	1.39	17.3	6.8	0.6	48	0.4	2.5	0.2	107	0.33	0.147	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276202	Soil	10	0.03	90	0.005	<1	0.75	0.004	0.04	0.1	0.04	0.5	0.1	<0.05	5	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276203	Soil	7	0.02	77	0.003	<1	0.69	0.008	0.03	<0.1	0.02	0.2	0.1	<0.05	4	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276204	Soil	14	0.06	81	0.013	<1	0.89	0.004	0.04	0.1	0.06	1.1	0.2	<0.05	6	1.0	0.2	N.A.	N.A.	N.A.	N.A.
1276205	Soil	9	0.02	90	0.004	<1	0.66	0.003	0.04	0.1	0.02	0.4	0.1	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276206	Soil	6	0.01	101	0.002	1	0.28	0.005	0.03	<0.1	0.03	0.2	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276207	Soil	9	0.02	216	0.003	1	0.47	0.003	0.05	<0.1	0.03	0.3	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276208	Soil	13	0.06	1789	0.004	2	0.43	0.003	0.07	<0.1	0.20	3.0	0.4	<0.05	1	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276209	Soil	13	0.11	738	0.003	3	0.64	0.004	0.09	0.1	0.33	3.5	0.4	<0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276210	Soil	6	0.17	514	0.006	3	0.34	0.023	0.02	<0.1	0.10	0.5	<0.1	0.08	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276211	Soil	5	<0.01	89	0.003	1	0.21	0.005	0.03	<0.1	0.02	<0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276212	Soil	6	0.30	1037	0.006	13	0.46	0.015	0.04	<0.1	0.21	0.4	0.3	0.24	1	8.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276213	Soil	8	0.02	102	0.003	1	0.37	0.003	0.04	<0.1	0.04	0.2	0.2	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276214	Soil	2	<0.01	21	0.004	<1	0.10	0.021	0.02	<0.1	0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276215	Soil	2	<0.01	22	0.003	<1	0.09	0.020	0.02	<0.1	0.02	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276216	Soil	7	<0.01	173	0.005	1	0.29	0.005	0.04	<0.1	0.04	0.5	0.1	<0.05	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276217	Soil	5	<0.01	136	0.005	2	0.26	0.011	0.03	<0.1	0.07	0.4	0.1	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276218	Soil	5	0.01	100	0.003	<1	0.31	0.010	0.02	<0.1	0.04	<0.1	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276219	Soil	8	0.02	495	0.003	1	0.46	0.008	0.08	<0.1	0.07	0.2	0.2	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276220	Soil	10	0.07	2333	0.003	2	0.70	0.009	0.08	<0.1	0.27	1.5	0.3	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276251	Soil	19	0.07	2001	0.002	2	1.17	0.011	0.06	0.1	0.68	2.0	0.3	0.06	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276218	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11000997.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276218	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1274138	Soil	1.2	11.6	7.0	43	<0.1	9.8	4.3	140	1.22	6.1	1.2	<0.1	6	<0.1	0.5	0.1	16	0.04	0.048	3
REP 1274138	QC	1.3	11.3	6.6	43	<0.1	9.0	4.4	127	1.18	6.0	1.7	<0.1	6	<0.1	0.5	0.2	15	0.04	0.050	3
1274155	Soil	29.8	38.1	16.2	599	0.5	102.8	9.4	182	2.24	33.2	5.1	1.9	59	3.8	18.4	0.1	87	0.66	0.160	11
REP 1274155	QC	30.1	38.6	16.0	612	0.5	104.4	9.2	183	2.27	34.2	5.2	1.8	57	3.6	18.3	0.1	85	0.66	0.155	11
1274175	Soil	15.0	96.9	12.2	574	0.7	115.8	11.1	158	3.49	55.7	5.4	1.5	21	4.0	22.3	0.2	69	0.22	0.084	5
REP 1274175	QC	14.1	96.3	12.2	567	0.6	116.0	11.1	156	3.35	54.6	4.6	1.4	21	4.4	22.0	0.2	70	0.23	0.084	4
1274191	Soil	15.5	10.0	274.3	6	3.0	2.9	0.2	9	0.45	14.2	2.9	0.3	17	<0.1	42.2	0.3	23	0.01	0.012	2
REP 1274191	QC	15.2	10.9	280.8	12	3.1	3.3	0.1	5	0.48	13.9	2.4	0.4	16	<0.1	42.2	0.3	24	0.01	0.012	2
1274206	Soil	5.3	4.8	4.1	31	0.7	7.6	0.8	13	0.44	4.0	<0.5	<0.1	5	0.1	2.3	0.1	21	0.02	0.059	2
REP 1274206	QC	4.9	5.5	4.2	32	0.6	7.3	0.9	12	0.46	4.2	<0.5	<0.1	3	0.1	2.2	0.1	21	0.02	0.063	2
1274228	Soil	2.4	11.4	54.8	27	0.5	5.5	0.9	17	0.64	25.1	2.7	<0.1	205	0.1	13.2	0.4	42	0.10	0.172	10
REP 1274228	QC	2.7	11.2	54.0	27	0.5	5.2	0.8	17	0.65	26.0	1.1	<0.1	214	<0.1	13.3	0.4	43	0.10	0.180	9
1274252	Soil	4.3	20.1	13.3	53	1.3	14.9	3.9	103	2.26	15.9	3.1	1.7	12	0.2	5.2	0.2	59	0.07	0.050	8
REP 1274252	QC	4.1	20.9	13.8	55	1.2	15.4	3.8	102	2.32	16.5	2.5	1.8	12	0.3	5.4	0.2	61	0.06	0.053	8
1274277	Soil	2.2	36.8	12.7	72	1.0	16.0	2.5	58	1.54	8.8	1.3	<0.1	35	0.5	1.2	0.3	26	0.22	0.069	6
REP 1274277	QC	2.1	34.6	12.4	67	0.9	15.3	2.5	55	1.47	8.2	1.8	0.1	33	0.5	1.2	0.2	24	0.21	0.065	5
1274302	Soil	6.6	40.7	21.4	233	0.1	45.1	9.6	147	3.21	40.0	1.6	2.8	29	0.7	3.6	0.3	42	0.29	0.087	8
REP 1274302	QC	6.5	41.0	21.5	228	0.2	43.7	10.0	148	3.28	38.6	0.7	2.8	29	0.7	3.5	0.3	41	0.29	0.082	8
1274327	Soil	7.4	38.3	12.5	83	<0.1	48.1	11.5	198	2.95	30.6	1.6	0.2	3	<0.1	4.2	0.2	33	0.04	0.079	13
REP 1274327	QC	7.3	40.1	13.0	81	<0.1	50.4	11.5	198	3.04	30.9	<0.5	0.1	5	<0.1	4.2	0.2	33	0.02	0.078	13
1274341	Soil	15.1	76.7	13.9	183	4.0	26.4	3.6	81	1.78	19.3	4.3	0.3	12	1.1	5.3	0.2	39	0.28	0.232	5
REP 1274341	QC	15.9	80.4	14.2	189	4.4	29.5	3.8	85	1.98	19.0	6.0	0.2	13	1.2	5.6	0.2	38	0.31	0.247	5
1276112	Soil	9.1	17.3	8.3	307	0.5	34.1	3.2	101	0.91	12.2	2.8	<0.1	24	3.7	2.2	0.1	106	0.31	0.084	6
REP 1276112	QC	8.2	15.6	7.4	293	0.4	30.4	2.8	96	0.83	11.2	3.8	<0.1	23	3.0	2.1	0.1	97	0.26	0.079	6
1276151	Soil	3.2	9.9	5.3	16	2.0	3.7	0.7	15	0.84	11.3	2.1	<0.1	10	<0.1	2.3	<0.1	42	<0.01	0.030	3
REP 1276151	QC	3.5	10.0	5.5	17	1.9	3.3	0.8	15	0.83	11.3	<0.5	<0.1	10	<0.1	2.1	0.1	44	<0.01	0.029	3
1276154	Soil	8.1	13.7	15.3	46	0.9	9.9	2.3	43	1.44	14.6	2.3	0.2	21	0.1	3.0	0.3	97	0.01	0.040	11
REP 1276154	QC	8.2	13.5	14.7	46	0.9	9.9	2.4	42	1.46	13.8	1.9	0.1	21	<0.1	3.0	0.2	99	0.01	0.040	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11000997.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1274138	Soil	8	0.05	35	0.005	1	0.43	0.011	0.02	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274138	QC	8	0.05	35	0.007	1	0.41	0.010	0.02	0.1	0.03	0.4	<0.1	<0.05	2	<0.5	<0.2				
1274155	Soil	15	0.08	577	0.004	3	0.41	0.004	0.06	0.1	0.33	4.0	0.4	0.07	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274155	QC	15	0.08	575	0.004	3	0.39	0.004	0.06	0.1	0.28	4.1	0.4	<0.05	1	2.3	<0.2				
1274175	Soil	20	0.04	381	<0.001	1	0.29	0.001	0.03	<0.1	0.33	5.3	0.2	<0.05	<1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274175	QC	20	0.04	375	0.002	<1	0.28	0.001	0.03	<0.1	0.36	5.4	0.2	<0.05	<1	4.1	<0.2				
1274191	Soil	6	<0.01	237	<0.001	1	0.14	0.003	0.06	<0.1	0.21	0.2	0.3	0.13	1	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274191	QC	5	<0.01	236	<0.001	2	0.15	0.003	0.07	<0.1	0.24	0.2	0.4	0.14	1	5.1	<0.2				
1274206	Soil	3	0.01	29	<0.001	1	0.25	0.015	0.02	<0.1	<0.01	0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274206	QC	3	0.01	29	<0.001	2	0.26	0.016	0.02	<0.1	0.02	0.2	0.1	<0.05	1	<0.5	<0.2				
1274228	Soil	22	0.01	131	0.003	1	0.62	0.009	0.03	<0.1	<0.01	0.1	0.2	<0.05	5	1.2	0.2	N.A.	N.A.	N.A.	N.A.
REP 1274228	QC	23	0.01	133	0.002	1	0.63	0.009	0.03	<0.1	0.01	0.3	0.2	<0.05	5	<0.5	<0.2				
1274252	Soil	19	0.14	127	0.023	2	0.91	0.004	0.03	0.2	0.13	1.2	0.2	<0.05	4	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274252	QC	19	0.15	132	0.024	<1	0.92	0.004	0.04	0.2	0.15	1.2	0.2	<0.05	4	3.0	<0.2				
1274277	Soil	11	0.09	169	0.007	3	0.65	0.013	0.03	<0.1	0.06	0.5	0.1	0.06	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274277	QC	10	0.09	159	0.007	<1	0.63	0.013	0.03	<0.1	0.07	0.4	0.1	<0.05	3	1.0	<0.2				
1274302	Soil	16	0.17	294	0.002	1	0.64	0.003	0.05	<0.1	0.08	3.5	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274302	QC	17	0.17	302	0.003	<1	0.66	0.003	0.05	<0.1	0.10	3.4	0.1	<0.05	2	1.5	<0.2				
1274327	Soil	6	0.02	290	0.004	<1	0.29	0.004	0.05	<0.1	0.02	0.8	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274327	QC	7	0.03	294	0.003	1	0.31	0.004	0.05	<0.1	0.03	0.5	0.1	<0.05	2	<0.5	<0.2				
1274341	Soil	7	0.02	330	0.002	2	0.41	0.007	0.07	0.2	0.60	0.8	0.2	0.06	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1274341	QC	7	0.02	340	0.002	<1	0.41	0.007	0.06	<0.1	0.59	0.9	0.2	0.09	2	2.4	<0.2				
1276112	Soil	10	0.05	395	0.005	1	0.56	0.014	0.03	0.1	0.13	0.3	0.6	0.06	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276112	QC	9	0.05	360	0.004	<1	0.49	0.014	0.03	<0.1	0.14	0.3	0.6	<0.05	2	2.5	<0.2				
1276151	Soil	5	0.01	122	0.007	<1	0.36	0.016	0.02	<0.1	0.02	<0.1	0.1	<0.05	3	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276151	QC	4	<0.01	118	0.006	<1	0.35	0.015	0.02	<0.1	0.03	<0.1	0.1	<0.05	4	3.4	<0.2				
1276154	Soil	14	0.03	190	0.009	2	0.59	0.006	0.04	0.1	0.03	0.3	0.2	<0.05	6	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276154	QC	14	0.04	187	0.010	2	0.59	0.006	0.04	0.2	0.02	0.3	0.2	<0.05	6	0.8	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11000997.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1274138	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274138	QC																					
1274155	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274155	QC																					
1274175	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274175	QC																					
1274191	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274191	QC																					
1274206	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274206	QC																					
1274228	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274228	QC																					
1274252	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274252	QC																					
1274277	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274277	QC																					
1274302	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274302	QC																					
1274327	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274327	QC																					
1274341	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274341	QC																					
1276112	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276112	QC																					
1276151	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276151	QC																					
1276154	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276154	QC																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11000997.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1274138	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274138	QC													
1274155	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274155	QC													
1274175	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274175	QC													
1274191	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274191	QC													
1274206	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274206	QC													
1274228	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274228	QC													
1274252	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274252	QC													
1274277	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274277	QC													
1274302	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274302	QC													
1274327	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274327	QC													
1274341	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1274341	QC													
1276112	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276112	QC													
1276151	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276151	QC													
1276154	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276154	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11000997.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1276171	Soil	19.3	10.2	7.7	45	0.3	9.0	1.5	24	0.75	15.3	<0.5	<0.1	11	0.1	2.9	<0.1	72	0.02	0.038	11
REP 1276171	QC	19.2	10.2	7.8	46	0.3	8.7	1.3	24	0.73	15.0	0.9	0.2	10	<0.1	2.9	<0.1	71	0.01	0.036	11
1276197	Soil	13.5	61.3	24.7	313	1.3	48.8	9.6	269	2.51	33.1	4.4	1.1	34	3.0	10.3	0.3	76	0.41	0.137	6
REP 1276197	QC	13.8	64.6	25.3	321	1.4	50.3	10.0	280	2.54	33.3	4.0	1.0	35	3.1	10.3	0.2	76	0.41	0.139	6
1276251	Soil	4.8	38.4	12.7	89	2.0	23.2	3.0	58	1.39	17.3	6.8	0.6	48	0.4	2.5	0.2	107	0.33	0.147	5
REP 1276251	QC	4.7	38.1	12.3	88	1.9	22.9	2.9	56	1.40	17.0	6.5	0.6	46	0.6	2.3	0.2	106	0.33	0.151	5
Reference Materials																					
STD DS8	Standard	12.7	106.6	123.7	311	1.7	37.6	7.4	596	2.43	24.1	109.7	6.2	61	2.6	5.1	6.6	43	0.69	0.079	15
STD DS8	Standard	13.3	104.0	121.0	302	1.9	36.9	7.3	593	2.66	23.6	130.3	6.4	60	2.2	5.6	5.7	40	0.68	0.078	15
STD DS8	Standard	12.7	94.1	111.8	298	1.8	38.0	6.7	606	2.40	21.8	111.7	5.8	56	2.0	4.7	5.6	39	0.67	0.076	13
STD DS8	Standard	11.8	111.4	131.8	313	1.9	40.2	7.7	624	2.51	26.0	109.8	6.4	61	2.4	5.0	6.8	42	0.68	0.085	13
STD DS8	Standard	14.0	110.8	126.7	316	1.8	40.7	7.6	612	2.66	25.4	109.2	6.6	62	2.3	4.9	5.9	42	0.68	0.077	15
STD DS8	Standard	12.9	110.8	131.7	320	2.0	39.0	7.9	631	2.59	26.9	132.1	6.7	66	2.4	5.6	6.8	43	0.67	0.087	14
STD DS8	Standard	12.1	100.6	120.0	300	1.6	35.7	7.0	558	2.61	23.4	107.3	6.0	62	2.3	4.5	5.7	39	0.66	0.072	14
STD DS8	Standard	13.5	104.2	120.5	312	1.8	37.4	7.6	623	2.69	25.6	108.4	7.1	69	2.3	5.2	5.6	43	0.68	0.075	16
STD DS8	Standard	13.3	102.1	120.7	305	1.6	36.5	6.8	590	2.40	24.7	104.8	6.6	63	2.0	5.6	5.4	39	0.71	0.079	16
STD DS8	Standard	11.8	112.5	118.3	314	1.7	38.0	7.6	638	2.53	25.9	116.8	6.3	64	2.4	5.3	6.7	44	0.68	0.089	13
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11000997.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1276171	Soil	9	0.02	134	0.002	2	0.29	0.004	0.04	0.1	0.04	0.1	0.8	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276171	QC	9	0.02	140	0.002	2	0.28	0.004	0.04	<0.1	0.07	0.1	0.8	<0.05	2	0.7	<0.2				
1276197	Soil	14	0.04	1225	0.002	2	0.47	0.004	0.05	<0.1	0.39	2.6	0.3	<0.05	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276197	QC	15	0.05	1362	0.003	2	0.51	0.004	0.05	<0.1	0.33	2.7	0.3	<0.05	2	3.7	<0.2				
1276251	Soil	19	0.07	2001	0.002	2	1.17	0.011	0.06	0.1	0.68	2.0	0.3	0.06	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276251	QC	19	0.07	2019	0.002	2	1.16	0.011	0.07	<0.1	0.67	2.1	0.3	0.08	3	2.9	<0.2				
Reference Materials																					
STD DS8	Standard	117	0.63	271	0.113	2	0.92	0.084	0.41	2.8	0.22	2.0	5.4	0.11	5	4.6	4.8				
STD DS8	Standard	109	0.60	265	0.110	3	0.92	0.088	0.40	2.9	0.22	1.9	5.3	0.17	5	4.8	4.5				
STD DS8	Standard	122	0.61	267	0.112	3	0.92	0.082	0.39	3.0	0.19	1.8	5.4	0.18	5	4.9	4.8				
STD DS8	Standard	117	0.64	274	0.109	4	0.90	0.079	0.41	3.0	0.22	2.1	5.8	0.14	5	5.8	4.7				
STD DS8	Standard	117	0.59	265	0.113	2	0.87	0.088	0.41	2.8	0.21	2.2	5.4	0.16	5	5.3	4.8				
STD DS8	Standard	117	0.65	286	0.117	3	0.95	0.085	0.44	3.3	0.21	2.1	5.7	0.12	5	5.4	5.3				
STD DS8	Standard	106	0.53	274	0.108	2	0.85	0.078	0.38	2.8	0.17	1.8	5.2	0.08	5	6.3	4.7				
STD DS8	Standard	116	0.55	280	0.119	3	0.86	0.084	0.38	2.9	0.19	2.0	5.4	0.14	5	5.2	5.0				
STD DS8	Standard	111	0.57	283	0.115	3	0.89	0.082	0.39	2.9	0.16	2.0	5.0	0.09	5	5.2	4.9				
STD DS8	Standard	120	0.63	269	0.113	2	0.91	0.091	0.43	2.9	0.20	2.3	5.3	0.14	5	5.0	4.6				
STD DS8	Standard																	13.4	112.1	127.5	309
STD OREAS45CA	Standard																	0.8	516.8	19.7	63
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11000997.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1276171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276171	QC																				
1276197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276197	QC																				
1276251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276251	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	2.0	37.3	7.2	600	2.41	25.1	107.3	6.8	74	2.5	5.0	7.0	42	0.71	0.076	16	118	0.61	307	0.120
STD OREAS45CA	Standard	0.3	247.0	89.6	919	17.06	4.2	46.9	6.7	16	<0.1	<0.1	0.2	198	0.42	0.034	16	674	0.16	161	0.133
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11000997.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1276171	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276171	QC												
1276197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276197	QC												
1276251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276251	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.94	0.092	0.43	1.8	0.22	2.3	5.6	0.16	5	5.5	5.0
STD OREAS45CA	Standard	<20	3.74	0.013	0.08	<0.1	0.03	39.5	<0.1	<0.05	19	0.8	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11000997.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11000997.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11000997.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11000997.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 03, 2011
Report Date: October 06, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11000998.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #9
P.O. Number
Number of Samples: 322

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve to 230 mesh			WHI
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	316	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	4	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276252	Soil	9.2	49.5	15.0	201	0.6	40.7	7.6	136	2.49	22.4	2.4	2.7	50	1.4	6.1	0.3	67	0.22	0.112	9
1276253	Soil	9.9	41.9	25.6	435	1.0	68.4	9.5	279	2.76	23.9	3.3	1.4	47	2.4	6.7	0.2	71	0.32	0.161	9
1276254	Soil	6.3	21.3	12.6	81	1.4	18.3	2.6	34	1.20	10.8	3.5	0.1	18	0.6	2.0	0.1	60	0.02	0.080	3
1276255	Soil	15.5	59.9	17.4	369	1.4	77.4	10.4	404	3.11	35.2	6.9	1.0	61	3.1	5.4	0.2	134	0.26	0.166	8
1276256	Soil	13.2	47.3	15.8	291	0.6	56.6	8.4	270	2.58	25.7	2.7	1.7	63	2.7	6.9	0.2	110	0.23	0.118	12
1276257	Soil	17.3	66.3	18.3	358	1.9	75.3	8.3	402	2.84	29.7	5.0	1.2	94	2.5	6.8	0.3	172	0.55	0.132	9
1276258	Soil	11.7	44.2	13.4	166	1.6	40.8	4.2	66	1.76	20.2	4.5	0.2	33	1.4	3.8	0.2	120	0.08	0.092	6
1276259	Soil	19.1	42.4	21.2	188	0.4	42.0	5.9	71	2.38	32.5	1.4	0.1	29	1.6	6.5	0.3	123	0.03	0.078	12
1276260	Soil	18.7	44.6	19.9	220	0.5	42.8	8.6	238	2.79	33.2	1.9	1.0	37	1.8	6.3	0.3	148	0.06	0.107	11
1276261	Soil	12.3	29.8	16.4	141	1.0	28.8	4.3	54	1.88	21.2	1.9	<0.1	25	0.8	3.6	0.2	101	0.05	0.076	9
1276262	Soil	23.8	45.4	12.4	601	0.4	104.5	25.0	636	4.99	40.6	3.9	1.9	29	1.5	8.8	0.1	150	0.06	0.167	10
1276263	Soil	26.5	66.0	19.3	558	1.9	112.1	30.6	822	7.28	46.2	2.6	1.7	21	1.5	7.5	0.2	197	0.06	0.244	9
1276264	Soil	23.7	48.3	12.0	721	1.0	135.6	38.0	784	5.95	48.4	4.1	1.5	22	5.1	7.8	0.2	127	0.08	0.219	6
1276265	Soil	25.4	49.0	16.6	856	0.4	144.7	51.4	1357	7.67	54.9	3.4	2.0	21	2.2	9.6	0.2	142	0.05	0.332	6
1276266	Soil	20.1	33.8	15.6	321	0.7	64.3	7.8	154	2.40	25.5	0.9	0.3	20	1.5	6.6	0.2	92	0.08	0.168	8
1276267	Soil	10.8	49.2	18.7	258	0.6	53.1	7.3	140	2.70	31.7	2.7	0.6	40	1.3	6.1	0.3	87	0.22	0.130	10
1276268	Soil	21.9	34.6	17.4	506	0.8	90.7	12.1	322	3.22	34.1	2.0	1.1	66	1.9	8.1	0.2	125	0.59	0.181	9
1276269	Soil	31.4	57.3	27.2	552	0.6	136.8	16.2	311	3.49	38.5	2.7	1.1	50	2.0	16.3	0.2	95	0.27	0.147	9
1276270	Soil	15.1	61.9	15.9	1338	0.9	222.2	23.1	348	3.19	29.9	6.2	2.0	132	6.8	11.9	0.2	75	7.74	0.129	6
1276271	Soil	8.7	29.6	10.0	842	0.6	95.2	7.3	263	1.55	16.9	1.9	1.2	208	6.1	6.6	0.1	47	17.34	0.080	4
1276272	Soil	21.1	77.5	18.4	1017	1.1	157.7	11.2	186	3.10	40.7	3.9	3.0	73	7.1	26.1	0.2	97	2.22	0.147	11
1276273	Soil	27.8	64.9	21.1	613	1.2	132.9	9.9	271	2.88	32.0	2.1	2.9	113	3.7	16.8	0.2	96	2.77	0.123	9
1276274	Soil	17.6	50.1	18.6	365	0.8	88.9	11.1	188	2.66	26.5	2.2	2.2	55	2.5	9.6	0.2	89	0.53	0.121	14
1276275	Soil	24.6	46.9	20.4	448	0.4	83.7	11.1	200	2.81	28.0	1.5	2.7	49	3.3	7.9	0.2	103	0.40	0.105	12
1276276	Soil	21.9	44.2	14.0	1340	0.7	143.0	9.5	166	2.12	20.9	1.9	2.4	53	8.6	6.7	0.2	90	0.66	0.101	10
1276277	Soil	67.8	77.6	17.2	1130	1.3	218.6	9.3	265	2.36	48.4	2.0	1.8	91	18.8	12.8	0.2	192	0.41	0.155	10
1276278	Soil	42.2	30.6	33.7	250	0.9	55.0	5.7	193	2.21	36.1	4.9	0.4	36	1.2	10.9	0.3	130	0.07	0.088	6
1276279	Soil	31.2	21.0	48.0	95	1.4	25.1	2.8	38	1.43	19.4	3.8	0.4	39	0.5	8.5	0.3	79	0.03	0.058	6
1276280	Soil	22.8	14.5	45.0	71	1.0	16.5	2.0	23	1.17	12.0	0.5	0.3	35	0.5	6.4	0.3	65	0.01	0.049	4
1276281	Soil	26.4	11.3	28.1	836	1.2	93.2	3.6	188	1.63	20.8	7.9	<0.1	52	1.4	7.5	0.3	64	0.24	0.126	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276252	Soil	13	0.09	1405	0.005	<1	0.39	0.002	0.05	<0.1	0.20	2.5	0.2	0.06	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276253	Soil	18	0.09	919	0.002	<1	0.56	0.002	0.06	<0.1	0.33	2.3	0.2	0.06	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276254	Soil	11	0.03	481	0.001	2	0.58	0.010	0.05	<0.1	0.27	0.3	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276255	Soil	26	0.10	1501	0.002	<1	1.10	0.006	0.07	0.1	0.54	2.2	0.3	0.06	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276256	Soil	17	0.10	2018	0.005	<1	0.57	0.003	0.06	<0.1	0.24	2.3	0.3	0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276257	Soil	28	0.12	1778	0.003	<1	1.13	0.007	0.09	0.1	0.52	2.8	0.4	0.08	3	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276258	Soil	18	0.06	987	0.002	<1	0.76	0.012	0.07	<0.1	0.45	0.7	0.3	0.07	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276259	Soil	15	0.03	496	0.002	<1	0.46	0.002	0.05	0.2	0.09	0.2	0.4	0.06	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276260	Soil	20	0.09	820	0.003	1	0.61	0.003	0.06	0.2	0.17	1.6	0.4	0.07	3	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276261	Soil	13	0.03	597	<0.001	1	0.50	0.004	0.05	<0.1	0.15	0.1	0.3	0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276262	Soil	21	0.09	235	0.004	<1	1.23	0.001	0.05	<0.1	0.24	2.4	0.7	<0.05	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276263	Soil	28	0.06	300	0.007	<1	1.94	0.005	0.05	0.1	0.31	2.2	0.9	0.05	3	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276264	Soil	16	0.05	724	0.005	2	1.67	0.006	0.04	<0.1	0.41	2.3	1.0	0.07	1	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276265	Soil	20	0.06	300	0.007	2	2.15	0.004	0.05	0.1	0.19	2.2	1.1	0.06	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276266	Soil	14	0.04	547	0.004	<1	0.56	0.006	0.06	<0.1	0.07	0.9	0.7	0.06	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276267	Soil	16	0.08	1859	0.004	<1	0.67	0.006	0.09	<0.1	0.18	1.4	0.3	0.09	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276268	Soil	18	0.08	1232	0.004	1	0.62	0.008	0.05	<0.1	0.33	2.0	0.5	0.07	1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276269	Soil	23	0.07	649	0.003	<1	0.52	0.003	0.04	<0.1	0.21	3.1	0.5	0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276270	Soil	24	0.43	697	0.005	4	1.01	0.004	0.04	<0.1	0.40	4.0	0.5	0.08	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276271	Soil	14	0.53	431	0.005	3	0.37	0.003	0.04	<0.1	0.30	2.3	0.4	0.08	<1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276272	Soil	20	0.26	509	0.004	1	0.55	0.003	0.06	<0.1	0.51	5.8	0.4	0.07	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276273	Soil	17	1.07	610	0.004	3	0.36	0.004	0.07	0.1	0.34	4.2	0.5	0.07	<1	18.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276274	Soil	29	0.19	978	0.007	2	0.64	0.006	0.08	<0.1	0.25	3.6	0.4	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276275	Soil	22	0.24	609	0.007	1	0.76	0.004	0.07	0.1	0.30	3.4	0.4	<0.05	3	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276276	Soil	17	0.22	553	0.008	2	0.69	0.010	0.06	0.1	0.30	3.0	0.4	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276277	Soil	19	0.05	422	0.002	2	0.53	0.002	0.06	0.2	0.80	3.0	1.2	<0.05	1	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276278	Soil	14	0.07	315	0.002	<1	0.46	0.004	0.06	0.1	0.31	0.9	1.0	<0.05	2	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276279	Soil	9	0.03	232	0.002	<1	0.30	0.002	0.06	0.1	0.29	0.6	0.9	0.10	1	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276280	Soil	6	0.01	249	0.002	1	0.23	0.006	0.10	0.1	0.17	0.3	0.8	0.19	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276281	Soil	25	0.06	1281	0.002	<1	0.77	0.012	0.08	<0.1	0.68	0.3	1.5	0.13	3	5.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276254	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276258	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276259	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276271	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276272	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276273	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276274	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276275	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276276	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276277	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276278	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276279	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276280	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276281	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276254	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276258	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276259	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276271	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276272	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276273	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276274	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276275	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276276	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276277	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276278	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276279	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276280	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276281	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276282	Soil	14.3	11.3	7.2	43	0.8	11.4	2.0	26	0.84	10.2	1.4	<0.1	11	<0.1	3.6	0.1	70	<0.01	0.038	16
1276283	Soil	4.3	3.8	17.0	3	0.4	1.7	0.1	4	0.18	2.0	2.0	0.8	3	<0.1	3.9	0.3	25	<0.01	0.012	36
1276284	Soil	17.5	17.0	26.2	30	2.1	9.2	1.2	21	2.74	30.3	10.5	0.7	39	<0.1	10.4	0.5	102	0.01	0.248	18
1276285	Soil	2.7	8.2	4.7	12	0.9	2.9	0.6	16	0.39	2.6	1.0	<0.1	11	<0.1	0.7	<0.1	28	0.01	0.029	16
1276286	Soil	8.2	6.3	12.9	19	0.4	3.5	0.6	9	0.87	12.6	<0.5	0.1	15	<0.1	3.4	0.2	70	<0.01	0.029	9
1276287	Soil	14.3	21.2	12.1	79	1.0	13.1	0.7	11	1.06	13.6	1.8	<0.1	69	0.2	5.3	0.2	173	0.02	0.096	8
1276288	Soil	29.2	15.6	22.1	56	0.9	9.8	1.8	30	1.98	35.6	1.3	0.1	39	0.2	7.4	0.4	92	0.02	0.112	9
1276289	Soil	6.5	7.0	8.0	9	0.4	2.8	0.3	6	0.34	5.2	1.8	0.3	10	<0.1	1.0	0.2	19	<0.01	0.028	13
1276290	Soil	25.8	14.3	25.8	26	0.7	6.3	0.7	18	0.92	20.5	2.6	0.3	30	0.2	3.9	0.3	67	0.02	0.041	15
1276291	Soil	23.3	15.8	59.4	64	2.0	8.9	1.4	35	3.35	127.6	4.3	0.2	101	0.1	13.3	0.4	99	0.02	0.506	23
1276292	Soil	12.8	18.0	22.2	68	0.4	14.0	4.1	62	1.91	26.6	1.7	<0.1	29	0.2	3.5	0.3	90	0.01	0.066	12
1276293	Soil	5.7	16.4	6.0	43	0.3	8.1	2.4	35	0.84	7.9	1.2	<0.1	8	0.1	1.3	0.2	50	0.01	0.028	17
1276294	Soil	6.1	10.0	9.4	48	0.4	8.8	3.1	42	1.01	9.7	<0.5	0.1	12	<0.1	1.9	0.2	58	<0.01	0.030	11
1276295	Soil	11.5	25.1	22.3	127	0.7	27.7	7.7	97	3.32	23.9	2.7	0.8	29	0.2	4.6	0.4	73	0.01	0.077	10
1276296	Soil	27.9	30.9	22.6	208	1.6	37.8	4.5	164	2.29	28.2	1.9	<0.1	31	0.7	7.3	0.4	194	0.02	0.165	8
1276297	Soil	20.1	21.1	15.6	168	0.2	28.5	4.7	66	1.70	24.7	1.2	0.3	20	0.3	5.4	0.2	110	0.01	0.055	11
1276298	Soil	19.8	27.0	12.1	190	0.6	36.1	3.8	52	1.44	19.7	1.3	0.2	19	0.9	4.8	0.2	126	0.03	0.052	10
1276299	Soil	13.7	43.8	12.8	214	0.6	58.8	6.7	139	2.30	20.6	4.2	1.1	34	1.4	5.5	0.2	71	0.27	0.082	12
1276300	Soil	8.4	42.2	12.9	230	1.0	56.7	6.0	221	1.99	18.3	4.9	1.4	67	3.9	4.0	0.2	79	0.56	0.099	8
1276301	Soil	2.9	19.0	12.0	67	<0.1	16.0	7.7	114	1.73	13.9	1.3	0.3	8	0.1	1.5	0.3	39	0.02	0.033	9
1276302	Soil	2.4	23.0	12.3	57	<0.1	18.9	11.7	123	1.92	16.3	3.6	0.2	8	<0.1	1.1	0.3	33	<0.01	0.035	6
1276303	Soil	1.3	11.5	4.3	53	0.1	7.8	4.3	115	0.95	5.8	<0.5	<0.1	7	0.2	0.6	0.2	16	0.01	0.070	3
1276304	Soil	3.2	25.5	20.9	125	<0.1	34.4	17.1	164	2.85	16.0	0.6	0.6	9	0.1	1.3	0.3	23	<0.01	0.046	3
1276305	Soil	0.3	3.9	1.7	13	<0.1	2.3	1.5	54	0.33	1.2	<0.5	<0.1	6	<0.1	0.1	<0.1	5	0.02	0.028	<1
1276306	Soil	1.0	15.8	8.2	38	0.2	12.7	5.6	117	0.91	6.3	1.2	0.2	16	0.3	0.6	0.2	14	0.02	0.083	2
1276307	Soil	2.1	27.7	19.0	99	0.1	35.7	15.8	174	2.31	21.6	1.0	0.6	24	0.2	1.7	0.4	18	0.08	0.053	4
1276308	Soil	2.7	19.7	19.6	84	<0.1	23.7	12.5	387	1.65	17.6	2.4	0.5	30	1.6	1.6	0.3	18	0.10	0.062	4
1276309	Soil	2.1	10.7	9.7	40	0.4	7.8	4.7	47	0.75	7.7	<0.5	0.2	10	0.7	0.7	0.1	19	0.02	0.058	4
1276310	Soil	4.8	11.2	8.6	64	0.2	14.8	3.3	51	0.91	8.9	<0.5	0.1	12	0.4	2.3	0.1	34	0.04	0.064	5
1276311	Soil	5.0	17.4	7.2	35	0.1	12.9	1.6	17	0.53	3.8	0.8	<0.1	11	0.6	1.2	0.1	41	0.03	0.054	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276282	Soil	6	0.01	1936	0.005	2	0.22	0.005	0.04	0.2	0.08	0.1	0.4	0.07	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276283	Soil	3	<0.01	161	0.002	<1	0.19	<0.001	0.04	<0.1	0.07	0.1	0.5	<0.05	<1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276284	Soil	17	0.02	235	0.002	1	0.50	0.003	0.11	0.2	0.42	0.7	2.0	0.35	3	7.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276285	Soil	5	<0.01	346	0.006	<1	0.34	0.009	0.02	<0.1	0.04	0.2	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276286	Soil	7	0.01	726	0.005	<1	0.30	0.002	0.03	<0.1	0.07	0.3	0.2	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276287	Soil	16	0.01	1233	0.002	1	0.58	0.006	0.06	0.1	0.11	0.2	0.5	0.11	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276288	Soil	9	0.02	544	0.002	<1	0.31	0.004	0.11	0.2	0.05	0.2	0.9	0.26	2	3.6	0.2	N.A.	N.A.	N.A.	N.A.
1276289	Soil	5	<0.01	315	0.002	<1	0.25	0.006	0.03	<0.1	0.16	0.3	0.3	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276290	Soil	7	0.01	381	0.002	2	0.25	0.002	0.07	0.1	0.22	0.4	0.9	0.12	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276291	Soil	17	0.02	531	0.007	3	0.51	0.006	0.16	0.1	0.15	0.5	1.4	0.36	4	7.7	0.6	N.A.	N.A.	N.A.	N.A.
1276292	Soil	10	0.02	293	0.004	<1	0.45	0.003	0.05	<0.1	0.03	0.3	0.5	0.09	4	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276293	Soil	7	<0.01	85	0.004	1	0.27	0.002	0.02	0.1	0.02	0.3	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276294	Soil	4	0.01	258	0.003	<1	0.24	0.004	0.03	<0.1	0.02	0.4	0.2	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276295	Soil	12	0.07	352	0.003	1	0.56	0.002	0.06	<0.1	0.06	1.9	0.4	0.08	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276296	Soil	16	0.03	283	0.004	2	0.45	0.004	0.07	0.1	0.19	0.4	0.7	0.10	4	7.2	0.2	N.A.	N.A.	N.A.	N.A.
1276297	Soil	7	0.02	611	0.002	1	0.25	0.002	0.04	0.1	0.02	0.6	0.4	0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276298	Soil	9	0.02	670	0.003	2	0.37	0.005	0.04	0.1	0.07	0.6	0.5	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276299	Soil	11	0.05	1763	0.004	1	0.40	0.004	0.05	<0.1	0.17	2.1	0.3	0.08	1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276300	Soil	12	0.13	2112	0.004	3	0.60	0.005	0.06	<0.1	0.33	2.5	0.4	0.09	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276301	Soil	9	0.03	46	0.010	<1	0.47	0.004	0.03	0.1	0.01	1.1	0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276302	Soil	7	0.02	43	0.004	<1	0.43	0.003	0.02	<0.1	0.01	1.0	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276303	Soil	5	0.02	60	0.003	<1	0.33	0.012	0.03	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276304	Soil	7	0.04	51	0.001	<1	0.49	0.003	0.03	<0.1	0.01	2.8	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276305	Soil	2	0.01	24	0.003	<1	0.23	0.018	0.02	<0.1	<0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276306	Soil	5	0.03	177	0.002	<1	0.53	0.009	0.03	<0.1	0.03	1.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276307	Soil	7	0.08	148	<0.001	<1	0.40	0.003	0.05	<0.1	0.02	1.9	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276308	Soil	6	0.05	240	0.002	<1	0.38	0.006	0.07	<0.1	0.03	2.0	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276309	Soil	5	0.02	144	0.003	<1	0.43	0.010	0.05	<0.1	0.03	0.6	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276310	Soil	7	0.03	160	0.002	<1	0.45	0.008	0.04	<0.1	0.02	0.4	<0.1	0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276311	Soil	12	0.01	151	0.003	1	0.38	0.007	0.03	<0.1	<0.01	0.2	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276282	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276283	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276284	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276285	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276286	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276287	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276288	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276289	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276290	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276291	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276292	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276293	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276294	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276295	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276296	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276297	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276298	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276299	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276300	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276301	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276302	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276303	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276304	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276305	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276306	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276307	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276308	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276309	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276310	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276311	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276282	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276283	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276284	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276285	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276286	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276287	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276288	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276289	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276290	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276291	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276292	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276293	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276294	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276295	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276296	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276297	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276298	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276299	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276300	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276301	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276302	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276303	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276304	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276305	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276306	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276307	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276308	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276309	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276310	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276311	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276312	Soil	0.3	1.7	1.3	7	0.2	1.4	0.4	6	0.12	0.6	<0.5	<0.1	8	0.1	0.2	<0.1	6	0.04	0.016	<1
1276313	Soil	1.6	11.3	5.4	40	0.6	14.2	2.2	43	0.52	4.0	0.7	0.3	43	0.9	1.0	<0.1	18	0.43	0.046	2
1276314	Soil	1.0	19.2	6.8	51	0.6	15.2	3.5	163	0.60	4.3	<0.5	0.3	74	1.8	1.7	<0.1	22	1.06	0.082	3
1276315	Soil	1.8	22.1	7.2	175	0.4	19.8	3.2	154	0.72	6.3	1.5	0.4	102	2.9	2.8	0.1	19	1.84	0.115	3
1276316	Soil	3.8	32.8	18.3	97	0.5	36.1	6.8	130	1.41	14.6	2.0	0.5	72	1.6	3.4	0.2	45	0.84	0.085	4
1276317	Soil	5.9	25.3	13.3	208	0.9	36.1	6.2	146	1.39	15.0	1.6	0.9	76	1.8	4.3	0.1	57	1.33	0.060	6
1276318	Soil	2.4	15.5	7.4	157	0.2	12.6	3.1	276	0.50	4.0	1.8	0.3	99	3.8	1.5	<0.1	18	2.04	0.077	3
1276319	Soil	4.0	10.1	7.0	60	0.3	13.7	2.5	45	0.62	6.8	2.0	0.5	41	0.3	2.3	<0.1	28	0.41	0.043	3
1276320	Soil	3.4	35.2	10.6	215	0.5	64.8	18.8	6291	1.50	8.7	1.9	0.8	98	2.7	2.3	0.1	29	1.63	0.079	4
1276321	Soil	1.8	35.4	7.7	158	0.3	38.3	4.6	399	1.11	4.7	1.4	0.4	125	1.5	1.6	0.1	19	4.40	0.094	3
1276322	Soil	2.2	24.9	8.4	189	0.3	32.8	4.8	313	1.25	7.1	1.5	0.7	139	1.5	1.9	0.1	29	5.39	0.091	4
1276323	Soil	2.7	49.3	17.7	274	0.5	77.3	9.4	117	2.02	14.2	2.0	1.2	96	2.4	2.9	0.2	40	1.84	0.095	6
1276324	Soil	3.5	41.5	15.5	289	0.5	67.2	9.9	142	2.49	16.1	2.3	1.4	82	1.0	2.5	0.2	41	1.24	0.108	5
1276325	Soil	3.0	33.2	14.8	300	0.4	69.0	10.7	810	2.35	15.4	2.5	1.2	78	1.6	2.2	0.2	40	1.23	0.098	4
1276326	Soil	1.4	50.6	3.3	98	0.2	70.8	5.1	793	0.44	1.7	3.0	0.1	191	3.4	2.6	<0.1	9	4.21	0.071	2
1276327	Soil	3.7	24.1	6.8	168	0.2	39.1	14.1	928	4.35	27.8	1.6	0.4	92	2.4	3.0	<0.1	34	1.59	0.076	3
1276328	Soil	3.3	25.4	2.4	205	0.2	63.4	30.6	2110	0.81	4.6	1.5	<0.1	123	2.8	2.3	<0.1	11	2.62	0.072	2
1276329	Soil	4.9	37.4	10.9	352	0.4	87.4	15.4	3160	1.30	9.0	3.2	0.5	128	4.4	3.2	0.1	37	2.32	0.104	4
1276330	Soil	4.4	31.6	16.0	500	0.3	69.3	12.0	630	2.16	16.7	4.4	1.5	71	2.9	4.1	0.2	57	1.13	0.105	5
1276351	Soil	17.0	52.2	16.0	282	0.9	77.6	14.9	521	3.70	49.0	4.4	0.8	46	6.2	6.5	0.2	125	0.53	0.165	9
1276352	Soil	20.8	122.4	28.8	512	1.8	158.5	16.6	642	6.99	70.1	12.5	3.0	40	2.7	16.3	0.3	97	1.49	0.430	9
1276353	Soil	8.7	29.8	11.3	253	1.3	60.3	5.5	176	1.97	15.5	4.8	0.8	36	1.5	3.5	0.2	59	0.42	0.122	6
1276354	Soil	10.3	29.7	18.4	134	3.0	40.1	3.7	42	1.92	19.9	3.2	0.2	16	0.3	4.1	0.2	94	0.02	0.069	8
1276355	Soil	16.1	41.1	17.3	1458	1.2	119.8	7.0	190	2.32	17.7	4.7	0.7	61	8.9	4.9	0.2	107	2.40	0.130	5
1276356	Soil	12.6	13.1	9.3	64	0.3	12.1	1.8	22	0.90	14.0	2.5	0.1	14	0.1	3.8	0.1	67	0.03	0.034	12
1276357	Soil	4.7	18.9	8.5	65	0.2	15.1	2.4	26	0.70	9.5	1.7	<0.1	8	<0.1	1.5	0.1	37	0.03	0.086	7
1276358	Soil	13.2	78.2	26.1	214	0.3	68.1	12.4	93	3.01	29.4	3.5	0.2	13	0.4	6.5	0.2	61	0.02	0.110	9
1276359	Soil	10.9	100.6	19.8	239	1.0	80.9	13.0	110	3.13	35.8	3.2	0.2	11	0.7	7.7	0.2	51	0.06	0.141	8
1276360	Soil	22.6	54.3	22.0	138	0.4	47.8	8.6	77	2.84	41.9	1.9	0.3	7	0.3	10.3	0.2	41	0.01	0.080	6
1276361	Soil	23.8	72.9	18.9	315	1.1	112.9	11.7	258	2.97	20.9	2.1	2.9	111	2.0	8.2	0.2	77	2.84	0.140	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276312	Soil		2	0.01	31	0.003	<1	0.11	0.022	0.02	<0.1	0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276313	Soil		5	0.07	361	0.002	1	0.53	0.023	0.05	<0.1	0.08	1.0	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276314	Soil		10	0.16	298	0.007	2	0.53	0.020	0.04	<0.1	0.11	1.3	0.1	0.14	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276315	Soil		6	0.29	360	0.004	4	0.47	0.013	0.03	0.1	0.12	0.8	<0.1	0.17	<1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276316	Soil		11	0.14	462	0.003	3	0.88	0.012	0.06	<0.1	0.14	1.7	0.2	0.11	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276317	Soil		13	0.21	426	0.004	3	0.52	0.006	0.06	0.2	0.17	2.0	0.2	0.11	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276318	Soil		7	0.18	327	0.008	6	0.34	0.012	0.03	0.4	0.10	1.0	<0.1	0.19	<1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276319	Soil		7	0.09	131	0.004	1	0.33	0.017	0.03	<0.1	0.03	0.8	0.1	<0.05	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276320	Soil		11	0.32	495	0.003	7	0.74	0.013	0.09	<0.1	0.17	2.9	0.3	0.14	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276321	Soil		9	0.44	180	0.003	14	0.54	0.012	0.07	<0.1	0.15	2.1	0.2	0.22	1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276322	Soil		9	0.39	223	0.003	9	0.55	0.011	0.07	<0.1	0.16	1.9	0.2	0.15	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276323	Soil		14	0.38	335	0.003	6	0.81	0.010	0.08	<0.1	0.18	3.5	0.3	0.12	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276324	Soil		15	0.35	748	0.002	6	0.88	0.008	0.09	<0.1	0.20	2.9	0.3	0.06	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276325	Soil		14	0.32	530	0.002	7	0.84	0.009	0.09	<0.1	0.17	2.5	0.3	0.07	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276326	Soil		6	0.46	600	0.004	13	0.35	0.011	0.02	<0.1	0.10	0.9	<0.1	0.24	1	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276327	Soil		8	0.18	437	0.005	5	0.67	0.019	0.04	<0.1	0.09	1.2	0.2	0.06	2	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276328	Soil		3	0.14	460	0.006	7	0.41	0.018	0.02	<0.1	0.06	0.6	<0.1	0.16	<1	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276329	Soil		11	0.20	688	0.005	7	0.65	0.013	0.05	<0.1	0.14	1.9	0.2	0.16	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276330	Soil		15	0.20	421	0.004	5	0.72	0.010	0.09	<0.1	0.20	2.8	0.2	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276351	Soil		14	0.12	1194	0.004	2	0.73	0.005	0.07	<0.1	0.32	1.6	1.0	0.06	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276352	Soil		20	0.25	592	0.003	3	0.50	0.003	0.11	<0.1	0.40	6.4	0.4	0.07	1	4.3	0.2	N.A.	N.A.	N.A.	N.A.
1276353	Soil		15	0.08	1373	0.003	2	0.64	0.011	0.05	<0.1	0.33	2.0	0.3	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276354	Soil		13	0.03	590	0.004	2	0.54	0.004	0.04	0.2	0.13	0.5	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276355	Soil		22	0.06	722	0.003	2	0.74	0.006	0.05	<0.1	0.41	2.6	0.5	0.10	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276356	Soil		6	<0.01	242	0.003	<1	0.18	0.002	0.04	0.1	0.03	0.4	0.3	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276357	Soil		8	0.02	80	0.001	<1	0.38	0.003	0.05	<0.1	0.03	0.3	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276358	Soil		13	0.03	113	0.003	1	0.42	0.002	0.05	<0.1	0.02	0.7	0.2	<0.05	3	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276359	Soil		13	0.02	135	0.003	1	0.32	0.003	0.05	<0.1	0.03	0.6	0.2	<0.05	2	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276360	Soil		7	0.01	75	0.001	<1	0.31	0.001	0.03	<0.1	0.03	1.0	0.3	<0.05	<1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276361	Soil		15	1.37	2314	0.002	3	0.28	0.003	0.06	<0.1	0.29	4.3	0.2	<0.05	<1	3.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276320	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276323	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276326	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276327	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276328	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276329	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276330	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276351	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276352	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276353	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276354	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276355	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276356	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276357	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276358	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276359	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276360	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276361	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276320	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276323	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276326	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276327	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276328	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276329	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276330	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276351	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276352	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276353	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276354	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276355	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276356	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276357	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276358	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276359	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276360	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276361	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276362	Soil	30.2	75.2	21.0	358	1.1	126.6	12.0	310	3.10	22.4	2.8	3.1	111	3.0	8.5	0.2	99	3.18	0.166	5
1276363	Soil	15.5	77.0	21.5	302	1.1	100.3	12.2	310	3.08	25.6	4.2	3.5	132	2.2	9.7	0.2	71	3.75	0.136	6
1276364	Soil	8.9	26.7	15.9	108	0.3	38.1	5.5	46	1.46	18.2	1.3	<0.1	9	<0.1	4.6	0.2	51	0.04	0.049	8
1276365	Soil	11.1	22.6	8.9	117	0.4	31.1	3.4	57	1.83	8.9	2.2	0.5	11	0.3	2.8	0.1	44	0.08	0.113	5
1276366	Soil	12.7	36.3	9.9	125	0.4	53.6	6.1	158	1.89	10.1	2.6	0.3	15	0.7	3.3	0.1	50	0.23	0.099	4
1276367	Soil	2.0	12.0	3.6	38	0.4	21.9	2.3	66	0.70	2.3	1.8	<0.1	12	0.2	1.2	<0.1	21	0.18	0.065	2
1276368	Soil	21.6	42.3	16.5	56	0.7	109.4	12.3	240	3.62	24.5	1.6	0.2	14	0.1	8.0	0.1	193	0.09	0.127	3
1276369	Soil	21.1	44.0	24.5	140	0.7	118.0	12.4	546	5.33	20.4	2.4	0.5	32	0.5	7.9	0.2	129	0.31	0.191	6
1276370	Soil	81.5	56.2	14.9	414	0.2	179.8	10.8	364	3.03	21.8	1.8	3.1	116	3.3	7.0	0.1	116	5.53	0.104	4
1276371	Soil	7.1	31.0	63.3	241	0.4	39.2	6.0	89	2.25	26.8	3.2	0.1	119	0.6	15.4	0.2	89	0.04	0.152	5
1276372	Soil	8.0	80.6	67.5	322	1.2	83.3	15.4	503	3.88	48.1	5.6	0.7	233	2.5	26.6	0.2	142	0.33	0.299	9
1276373	Soil	13.5	63.4	42.0	245	1.4	84.6	7.8	108	2.64	38.6	4.7	0.4	95	1.0	24.3	0.3	189	0.13	0.186	10
1276374	Soil	18.4	70.0	75.1	165	2.4	55.2	6.4	94	3.22	63.3	6.6	1.2	257	1.3	33.3	0.4	235	0.51	0.678	17
1276375	Soil	7.9	50.6	15.7	199	<0.1	74.2	12.6	113	3.88	58.2	2.0	0.3	6	0.3	10.1	0.3	45	0.03	0.094	11
1276376	Soil	0.5	4.6	2.4	8	<0.1	3.4	1.1	49	0.30	6.8	1.0	<0.1	6	0.1	0.8	<0.1	6	0.04	0.025	1
1276377	Soil	1.5	82.2	80.3	317	1.0	129.2	41.3	875	7.56	3805	374.5	0.6	40	1.1	369.4	<0.1	38	0.87	0.115	8
1276378	Soil	4.8	45.0	11.3	154	0.3	49.8	6.7	58	1.65	29.6	3.2	0.2	5	0.3	21.5	0.1	29	0.04	0.063	4
1276379	Soil	5.8	40.3	29.9	208	<0.1	56.3	8.6	100	2.35	64.9	3.5	0.1	11	0.2	29.0	0.2	56	0.02	0.088	6
1276380	Soil	49.7	28.9	8.8	371	0.2	56.8	5.6	33	1.60	22.8	0.6	0.5	5	0.6	36.7	0.1	182	0.04	0.036	6
1276381	Soil	8.1	35.4	30.3	151	0.3	45.1	6.6	70	2.46	28.5	1.0	0.2	43	0.2	10.7	0.4	65	0.02	0.078	13
1276382	Soil	4.3	40.9	11.0	121	0.2	42.0	10.1	170	3.25	14.7	1.2	0.5	33	1.1	7.4	0.2	28	0.04	0.095	15
1276383	Soil	5.6	42.7	11.6	169	0.7	52.8	8.2	129	2.62	10.0	1.2	0.6	40	0.6	5.0	0.2	32	0.21	0.175	7
1276384	Soil	79.7	54.5	8.7	141	0.2	173.9	9.8	199	1.85	17.6	1.5	1.5	120	1.0	10.5	0.1	47	5.68	0.071	7
1276385	Soil	52.6	44.3	11.6	156	0.3	131.2	8.4	199	2.08	15.9	1.6	1.3	39	1.8	9.4	0.1	71	1.59	0.056	7
1276386	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1276387	Soil	70.8	102.8	10.3	1101	2.7	235.3	5.4	121	1.53	46.5	3.0	1.3	104	16.9	27.1	0.1	485	1.96	0.215	10
1276388	Soil	26.9	39.1	8.5	757	0.8	138.8	6.4	120	1.56	21.6	1.7	0.9	39	19.4	7.4	<0.1	168	1.89	0.064	6
1276389	Soil	69.4	56.4	24.6	218	0.3	166.3	11.2	515	4.36	37.5	1.0	3.0	159	1.5	12.6	0.1	74	5.92	0.107	4
1276390	Soil	63.8	52.6	25.0	1145	0.7	150.7	12.2	585	3.28	36.3	1.6	3.4	118	12.8	16.5	0.1	202	4.29	0.085	4
1276391	Soil	18.4	76.7	25.9	590	1.7	118.6	13.5	465	3.50	19.4	0.6	4.0	110	5.4	10.5	0.2	112	3.64	0.109	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276362	Soil	14	1.41	1587	0.002	3	0.27	0.003	0.06	<0.1	0.28	4.4	0.3	<0.05	<1	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276363	Soil	16	1.71	1988	0.002	4	0.25	0.003	0.06	<0.1	0.27	4.4	0.2	<0.05	<1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276364	Soil	8	0.03	121	0.003	<1	0.43	0.005	0.03	0.1	0.01	0.3	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276365	Soil	10	0.02	207	0.002	<1	0.38	0.004	0.03	<0.1	0.04	1.0	0.2	<0.05	<1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276366	Soil	14	0.04	194	0.003	<1	0.44	0.011	0.03	<0.1	0.04	1.2	0.2	<0.05	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276367	Soil	7	0.03	93	0.003	<1	0.51	0.020	0.02	<0.1	0.04	0.5	<0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276368	Soil	21	0.03	158	0.002	<1	0.32	0.006	0.03	<0.1	0.04	1.0	0.2	<0.05	1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276369	Soil	27	0.08	349	0.005	<1	0.49	0.003	0.05	0.1	0.12	2.8	0.3	<0.05	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276370	Soil	14	1.96	204	0.004	2	0.21	0.005	0.04	<0.1	0.30	3.9	0.9	<0.05	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276371	Soil	13	0.02	202	0.002	1	0.39	0.005	0.05	<0.1	0.04	0.4	0.2	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276372	Soil	22	0.13	412	0.006	2	0.62	0.003	0.07	0.2	0.16	1.6	0.2	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276373	Soil	16	0.03	225	0.003	1	0.45	0.005	0.06	0.1	0.13	0.7	0.3	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276374	Soil	23	0.07	497	0.010	4	0.64	0.005	0.13	0.2	0.26	2.4	0.7	0.15	3	6.6	0.4	N.A.	N.A.	N.A.	N.A.
1276375	Soil	12	0.02	104	0.003	<1	0.45	0.004	0.05	<0.1	0.02	0.9	0.1	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276376	Soil	2	0.01	26	0.006	<1	0.36	0.019	0.02	<0.1	0.02	0.5	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276377	Soil	35	0.33	349	0.002	3	0.84	0.007	0.11	0.2	0.11	23.8	0.1	0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276378	Soil	12	0.02	98	0.002	<1	0.35	0.008	0.03	<0.1	0.05	0.4	0.1	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276379	Soil	17	0.03	190	0.001	<1	0.62	0.004	0.04	<0.1	0.01	0.4	0.2	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276380	Soil	10	0.03	112	0.002	2	0.39	0.002	0.04	<0.1	0.07	0.4	0.6	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276381	Soil	15	0.03	192	0.006	4	0.44	0.003	0.05	0.1	0.03	0.4	0.2	0.06	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276382	Soil	14	0.04	201	0.004	2	0.54	0.007	0.06	0.1	0.03	1.1	<0.1	0.06	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276383	Soil	13	0.06	1665	0.003	1	0.49	0.011	0.06	<0.1	0.06	1.1	0.2	0.13	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276384	Soil	16	1.50	177	0.002	3	0.28	0.008	0.04	0.3	0.37	2.7	1.0	0.09	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276385	Soil	21	0.73	246	0.003	4	0.51	0.004	0.05	0.2	0.32	3.0	1.0	0.07	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276386	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	97.2	120.4	12.7	558
1276387	Soil	52	0.52	350	0.006	6	0.56	0.009	0.12	0.3	0.97	2.6	1.6	0.15	2	20.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276388	Soil	18	0.94	314	0.003	2	0.45	0.015	0.04	<0.1	0.32	2.0	0.4	0.06	1	6.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276389	Soil	19	2.91	402	0.004	5	0.25	0.012	0.04	<0.1	0.24	4.7	0.8	0.16	<1	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276390	Soil	16	2.10	376	0.004	3	0.22	0.008	0.04	<0.1	0.42	5.3	0.7	0.09	<1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276391	Soil	23	1.91	402	0.002	4	0.24	0.006	0.06	<0.1	0.32	5.7	0.3	0.10	<1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276362	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276363	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276364	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276365	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276366	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276367	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276368	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276369	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276370	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276371	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276372	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276373	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276374	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276375	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276376	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276377	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276378	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276379	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276380	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276381	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276382	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276383	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276384	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276385	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276386	Soil	1.8	244.4	6.4	267	1.46	38.2	2.6	0.5	160	10.5	28.4	0.2	304	5.94	0.117	9	31	1.23	230	0.004
1276387	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276388	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276389	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276390	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276391	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276362	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276363	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276364	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276365	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276366	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276367	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276368	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276369	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276370	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276371	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276372	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276373	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276374	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276375	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276376	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276377	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276378	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276379	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276380	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276381	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276382	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276383	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276384	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276385	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276386	Soil	<20	0.38	0.007	0.10	0.3	0.85	2.2	2.2	0.12	<1	12.6	0.2
1276387	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276388	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276389	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276390	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276391	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276392	Soil	16.6	103.0	44.7	178	3.1	115.9	23.6	494	5.28	63.9	4.5	6.0	188	0.5	12.6	0.3	32	2.20	0.174	13
1276393	Soil	12.7	92.8	28.5	192	1.1	107.2	28.4	659	5.91	16.7	4.1	5.0	23	0.2	5.4	0.4	19	0.30	0.074	15
1276394	Soil	77.5	58.2	21.2	983	0.4	171.3	12.0	358	3.03	46.6	0.8	5.1	96	6.3	18.7	0.1	183	4.15	0.068	6
1276395	Soil	41.3	50.8	26.8	301	0.7	127.0	11.9	444	3.66	52.0	1.1	5.0	115	2.6	23.6	0.1	200	4.96	0.078	7
1276396	Soil	12.5	97.1	22.9	161	1.1	118.3	14.6	385	2.93	27.1	1.1	5.5	121	1.5	9.4	0.1	69	4.65	0.128	5
1276397	Soil	9.4	98.3	20.6	122	1.2	133.7	19.4	276	3.56	26.2	1.7	3.9	83	0.7	7.1	0.2	75	2.41	0.134	7
1276398	Soil	4.0	19.6	9.9	55	0.2	23.2	4.1	114	1.07	7.0	1.0	0.1	15	0.1	1.6	<0.1	23	0.08	0.071	4
1276399	Soil	24.0	69.7	49.9	244	0.6	90.5	7.9	68	2.62	33.6	0.7	<0.1	102	0.7	10.8	0.3	167	0.04	0.219	13
1276400	Soil	21.0	80.9	32.2	194	0.9	85.2	10.2	260	2.80	27.2	4.7	0.4	122	1.1	6.2	0.2	112	0.18	0.262	13
1276401	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1276402	Soil	2.1	15.0	6.5	56	<0.1	13.4	6.1	94	1.41	8.4	<0.5	0.2	7	0.1	0.6	0.1	17	0.02	0.042	4
1276403	Soil	2.5	19.9	6.3	78	<0.1	12.9	6.7	83	1.51	7.8	1.0	0.4	7	<0.1	0.7	0.2	33	<0.01	0.033	7
1276404	Soil	1.4	23.2	9.7	63	<0.1	16.8	9.2	268	1.43	6.1	<0.5	0.2	10	0.1	0.5	0.1	15	0.06	0.071	3
1276405	Soil	0.3	4.0	3.4	8	<0.1	2.6	1.2	43	0.35	1.4	<0.5	<0.1	7	<0.1	<0.1	<0.1	4	0.04	0.032	1
1276406	Soil	3.0	33.5	33.7	171	0.2	55.0	31.9	531	3.27	37.6	<0.5	0.5	32	0.3	1.7	0.3	14	0.08	0.100	4
1276407	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1276408	Soil	2.3	11.2	8.1	52	0.3	15.8	5.2	42	0.96	7.5	<0.5	<0.1	10	0.1	1.0	<0.1	12	0.03	0.057	1
1276409	Soil	3.2	9.4	9.4	36	0.6	14.0	2.3	27	0.64	7.2	<0.5	0.1	21	0.2	1.5	<0.1	17	0.08	0.056	1
1276410	Soil	1.7	6.1	3.3	28	0.1	9.5	1.2	21	0.35	3.0	<0.5	<0.1	13	0.5	0.8	<0.1	14	0.10	0.042	1
1276411	Soil	12.0	46.7	14.7	176	0.2	65.2	8.1	90	2.65	21.2	1.9	0.3	9	0.4	7.5	0.3	47	0.13	0.107	13
1276412	Soil	31.0	43.9	13.4	457	0.3	88.4	13.7	369	2.98	98.1	4.2	1.4	55	2.1	23.9	0.1	124	0.41	0.155	10
1276413	Soil	57.3	59.0	16.6	387	0.3	149.6	13.3	285	2.94	47.0	3.5	1.2	99	3.1	42.3	<0.1	82	4.23	0.120	4
1276414	Soil	11.8	102.5	11.5	424	0.7	121.8	35.1	473	5.48	130.9	8.9	1.5	33	4.2	39.7	<0.1	92	0.78	0.075	5
1276415	Soil	64.5	29.8	13.6	308	<0.1	106.2	8.3	168	2.70	30.1	<0.5	0.4	9	1.6	12.9	0.1	105	0.10	0.046	4
1276416	Soil	41.2	30.7	13.6	489	0.4	85.6	8.8	200	2.45	41.6	2.2	1.4	31	3.2	21.2	0.2	143	0.43	0.076	6
1276417	Soil	43.3	21.7	9.1	93	<0.1	57.3	4.3	42	1.21	24.0	<0.5	0.3	8	0.4	14.7	0.1	42	0.09	0.035	8
1276418	Soil	108.1	84.6	10.8	266	0.3	215.2	10.1	151	2.21	31.8	1.2	3.3	242	1.8	6.0	0.2	36	6.99	0.069	12
1276419	Soil	38.8	53.4	27.6	435	1.4	126.8	10.8	363	3.36	28.7	2.8	1.4	68	2.7	9.9	0.3	92	0.51	0.136	7
1276420	Soil	5.4	26.0	11.3	88	0.2	29.1	5.7	69	1.95	13.9	2.2	0.3	14	0.3	3.1	0.2	47	0.05	0.035	8
1276421	Soil	5.7	46.5	10.0	246	0.3	71.3	15.3	164	4.02	21.5	2.9	0.7	13	0.2	6.9	0.3	58	0.03	0.084	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276392	Soil	19	0.77	3983	0.002	6	0.58	0.004	0.08	<0.1	0.44	7.0	0.3	0.10	1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276393	Soil	10	0.10	864	0.004	4	0.41	0.008	0.09	<0.1	0.16	5.8	0.3	0.08	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276394	Soil	15	2.15	447	0.002	2	0.21	0.006	0.05	<0.1	0.50	4.4	0.8	0.09	<1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276395	Soil	13	2.49	351	0.003	3	0.20	0.007	0.05	<0.1	0.21	4.3	0.5	0.10	<1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276396	Soil	21	2.09	272	0.002	5	0.24	0.004	0.07	<0.1	0.19	5.0	0.2	0.12	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276397	Soil	25	1.14	272	0.003	4	0.30	0.004	0.08	<0.1	0.24	7.2	0.2	0.10	<1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276398	Soil	8	0.03	107	0.003	1	0.33	0.019	0.03	<0.1	0.03	0.3	<0.1	0.11	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276399	Soil	22	0.03	236	0.002	<1	0.66	0.003	0.06	<0.1	0.04	0.1	0.3	0.15	3	5.2	0.2	N.A.	N.A.	N.A.	N.A.
1276400	Soil	27	0.05	256	0.004	2	0.53	0.009	0.09	0.1	0.06	0.7	0.6	0.13	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276401	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.2	20.8	7.4	58
1276402	Soil	11	0.04	43	0.004	<1	0.27	0.008	0.03	<0.1	0.02	0.8	<0.1	0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276403	Soil	12	0.03	46	0.003	<1	0.30	0.004	0.04	<0.1	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276404	Soil	15	0.08	65	0.009	1	0.54	0.017	0.05	<0.1	0.02	1.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276405	Soil	4	0.02	24	0.007	<1	0.42	0.031	0.03	<0.1	0.01	0.2	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276406	Soil	18	0.06	142	0.001	<1	0.46	0.006	0.07	<0.1	0.06	2.6	0.3	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276407	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	6.5	33.4	21.5	198
1276408	Soil	11	0.02	52	0.002	<1	0.23	0.020	0.03	<0.1	0.03	0.3	0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276409	Soil	11	0.02	105	0.004	1	0.24	0.024	0.04	<0.1	0.07	0.7	0.1	<0.05	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276410	Soil	7	0.02	99	0.006	<1	0.37	0.024	0.02	<0.1	0.04	0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276411	Soil	17	0.07	221	0.002	2	0.40	0.005	0.07	<0.1	0.03	0.4	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276412	Soil	32	0.10	490	0.006	3	0.57	0.006	0.07	<0.1	0.14	6.1	0.3	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276413	Soil	19	2.03	253	0.002	4	0.29	0.007	0.05	<0.1	0.29	6.1	0.4	0.08	<1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276414	Soil	29	0.15	463	0.002	5	0.41	0.008	0.07	<0.1	0.28	17.9	0.1	0.17	<1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276415	Soil	16	0.04	221	0.003	2	0.34	0.004	0.03	<0.1	0.09	2.1	0.3	0.05	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276416	Soil	19	0.08	345	0.004	2	0.41	0.005	0.03	0.1	0.33	5.5	0.3	<0.05	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276417	Soil	9	0.03	78	0.004	2	0.33	0.005	0.02	0.2	0.04	0.6	0.3	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276418	Soil	13	1.16	171	0.002	3	0.13	0.004	0.04	0.3	0.33	3.5	1.5	<0.05	<1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276419	Soil	27	0.09	1410	0.005	3	0.59	0.006	0.06	0.1	0.33	4.6	0.5	<0.05	1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276420	Soil	12	0.03	469	0.004	2	0.34	0.005	0.04	0.1	0.02	1.0	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276421	Soil	15	0.03	95	0.005	4	0.34	0.004	0.04	0.1	0.03	1.9	<0.1	<0.05	2	1.8	0.3	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276392	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276393	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276394	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276395	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276396	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276397	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276398	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276399	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276400	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276401	Soil	<0.1	19.4	6.2	98	1.39	10.0	<0.5	0.2	10	0.3	0.8	0.2	33	0.08	0.056	4	19	0.05	71	0.002
1276402	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276403	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276404	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276405	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276406	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276407	Soil	0.2	57.8	19.0	319	3.34	30.3	0.7	0.3	24	0.5	3.1	0.3	31	0.15	0.093	3	25	0.07	195	0.001
1276408	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276409	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276410	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276411	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276412	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276413	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276414	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276415	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276416	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276417	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276418	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276419	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276420	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276421	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276392	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276393	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276394	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276395	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276396	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276397	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276398	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276399	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276400	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276401	Soil	<20	0.32	0.007	0.05	<0.1	0.05	0.9	<0.1	0.08	2	1.0	<0.2
1276402	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276403	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276404	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276405	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276406	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276407	Soil	<20	0.45	0.011	0.06	<0.1	0.05	0.9	0.3	0.08	2	1.4	<0.2
1276408	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276409	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276410	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276411	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276412	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276413	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276414	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276415	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276416	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276417	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276418	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276419	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276420	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276421	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276422	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1276423	Soil	3.7	81.2	27.9	196	1.4	108.1	22.2	356	4.07	13.2	4.0	0.7	122	0.5	5.9	0.2	25	0.25	0.211	5
1276424	Soil	0.2	1.6	0.9	5	0.2	1.7	0.4	8	0.13	<0.5	<0.5	<0.1	4	<0.1	0.8	<0.1	3	0.02	0.014	<1
1276425	Soil	5.1	14.2	12.3	92	1.4	22.9	4.4	71	0.76	23.9	0.9	<0.1	17	0.5	70.2	<0.1	61	0.27	0.051	2
1276426	Soil	21.7	43.3	22.0	337	0.4	96.5	12.9	162	3.26	35.9	1.0	0.3	16	0.5	10.7	0.2	129	0.04	0.127	5
1276427	Soil	9.7	153.3	24.8	1070	0.8	263.0	46.8	433	8.68	53.7	1.4	1.2	66	3.7	14.7	0.1	114	0.56	0.231	7
1276428	Soil	41.4	127.8	34.1	2008	1.5	513.0	55.5	694	8.91	137.6	2.5	2.5	155	14.2	27.2	0.2	292	1.01	0.334	7
1276429	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1276430	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1276471	Soil	10.6	118.0	15.7	261	0.7	83.4	18.4	267	3.25	44.3	3.9	0.1	13	0.7	14.6	0.1	64	0.13	0.305	11
1276472	Soil	9.9	47.0	7.9	174	0.2	43.1	7.1	85	1.90	47.3	1.7	<0.1	7	0.3	4.5	0.1	91	0.02	0.088	7
1276473	Soil	11.1	25.5	8.0	182	0.2	42.3	6.9	87	2.14	75.5	0.7	<0.1	8	0.4	3.7	0.1	143	0.02	0.092	8
1276474	Soil	19.9	49.2	13.9	351	0.3	75.7	11.7	442	5.45	78.7	2.4	0.2	16	1.2	7.1	0.2	204	0.04	0.193	12
1276475	Soil	11.5	25.8	26.0	26	4.4	5.1	0.9	53	1.47	34.8	7.1	0.3	70	0.1	11.6	0.2	121	0.04	0.105	3
1276476	Soil	13.4	26.8	25.2	22	4.7	3.3	0.6	21	1.62	38.4	5.0	0.5	62	0.1	12.8	0.2	120	0.02	0.085	2
1276477	Soil	3.7	12.3	8.9	32	0.7	6.6	1.9	37	0.93	9.3	1.6	<0.1	12	<0.1	1.6	0.2	41	0.02	0.055	6
1276478	Soil	6.3	15.6	15.3	48	0.5	9.8	2.9	56	1.33	13.7	1.9	<0.1	25	<0.1	2.6	0.3	57	0.02	0.078	5
1276479	Soil	7.7	34.5	21.5	229	0.5	39.1	12.7	212	3.33	26.3	1.8	1.2	27	0.5	4.5	0.3	41	0.01	0.061	4
1276480	Soil	3.0	23.9	14.7	100	0.1	24.3	8.7	140	1.86	11.7	1.1	0.2	14	<0.1	1.1	0.2	22	0.02	0.074	4
1276481	Soil	2.3	32.7	13.7	80	0.1	23.9	12.2	341	2.26	11.3	0.8	0.4	6	0.3	0.8	0.3	16	0.03	0.089	2
1276482	Soil	0.8	6.9	3.9	16	0.1	3.5	1.6	36	0.59	2.5	0.6	<0.1	4	<0.1	0.2	<0.1	9	0.03	0.034	2
1276483	Soil	1.3	10.6	7.0	30	<0.1	6.4	2.1	45	1.24	5.3	0.9	<0.1	5	<0.1	0.5	0.1	15	0.02	0.039	2
1276484	Soil	1.8	14.3	7.8	36	<0.1	6.8	2.9	43	1.24	6.6	<0.5	<0.1	5	<0.1	0.6	0.2	29	0.01	0.059	3
1276485	Soil	2.1	26.0	21.0	207	<0.1	50.3	7.1	117	2.71	10.9	0.5	1.2	14	0.4	0.5	0.3	19	0.09	0.041	2
1276486	Soil	1.9	5.2	4.2	19	0.1	4.1	1.3	24	0.52	4.9	3.6	<0.1	5	<0.1	0.6	<0.1	23	<0.01	0.029	8
1276487	Soil	5.0	16.7	16.7	56	0.2	11.6	3.5	81	2.51	16.7	1.5	0.1	9	<0.1	2.2	0.3	48	0.02	0.058	7
1276488	Soil	6.3	16.5	13.5	59	0.3	11.5	3.3	65	1.57	15.9	1.6	<0.1	13	<0.1	2.9	0.2	61	<0.01	0.043	9
1276489	Soil	0.7	3.3	3.3	5	0.6	1.3	0.3	8	0.25	2.3	1.1	<0.1	5	<0.1	0.3	<0.1	8	0.02	0.035	1
1276490	Soil	5.9	11.3	12.6	41	0.4	7.2	1.8	35	1.16	14.3	1.2	<0.1	9	<0.1	2.6	0.2	65	0.01	0.033	12
1276491	Soil	37.8	59.8	16.1	178	0.8	29.0	5.3	139	2.88	47.6	15.8	0.3	51	0.4	14.2	0.2	209	0.08	0.117	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276422	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	11.3	79.7	45.1	364
1276423	Soil	23	0.04	318	0.003	2	0.40	0.007	0.06	<0.1	0.10	3.2	0.1	0.14	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276424	Soil	2	<0.01	12	0.006	<1	0.09	0.020	0.02	<0.1	<0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276425	Soil	11	0.03	117	0.004	<1	0.33	0.020	0.02	<0.1	0.17	0.3	0.2	<0.05	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276426	Soil	35	0.04	81	0.004	<1	0.51	0.003	0.03	0.1	0.04	1.5	0.2	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276427	Soil	68	0.05	439	0.005	1	0.70	0.013	0.03	0.2	0.13	14.2	0.5	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276428	Soil	106	0.09	373	0.004	2	0.54	0.005	0.06	0.1	0.54	14.4	1.0	<0.05	2	5.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276429	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1276430	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1276471	Soil	20	0.05	838	0.003	1	0.77	0.011	0.04	0.1	0.09	0.6	0.3	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276472	Soil	16	0.03	101	0.003	1	0.47	0.010	0.04	0.1	0.03	0.5	0.2	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276473	Soil	31	0.07	146	0.004	<1	0.80	0.009	0.03	0.1	0.04	0.3	0.3	<0.05	5	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276474	Soil	47	0.11	499	0.006	1	1.22	0.005	0.06	0.1	0.06	0.7	0.6	0.07	5	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276475	Soil	32	0.03	1975	0.006	4	0.40	0.007	0.11	0.1	0.30	1.5	0.8	0.23	3	16.8	0.3	N.A.	N.A.	N.A.	N.A.
1276476	Soil	30	0.02	806	0.003	2	0.27	0.005	0.10	0.1	0.32	1.4	0.8	0.20	3	20.4	0.3	N.A.	N.A.	N.A.	N.A.
1276477	Soil	9	0.04	353	0.006	<1	0.45	0.011	0.04	0.1	0.05	0.2	0.2	0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276478	Soil	10	0.03	464	0.004	1	0.58	0.012	0.05	0.1	0.05	0.2	0.5	0.05	4	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276479	Soil	6	0.02	604	0.001	1	0.30	0.004	0.06	<0.1	0.20	5.1	0.8	0.09	<1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276480	Soil	7	0.05	1701	0.005	<1	0.52	0.013	0.04	<0.1	0.04	1.2	0.3	0.10	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276481	Soil	9	0.09	83	0.004	2	0.73	0.012	0.06	<0.1	0.04	1.8	0.2	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276482	Soil	3	0.02	35	0.007	<1	0.52	0.019	0.02	<0.1	0.02	0.4	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276483	Soil	6	0.04	39	0.005	<1	0.56	0.015	0.03	<0.1	0.02	0.4	<0.1	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276484	Soil	7	0.02	53	0.002	<1	0.52	0.005	0.03	<0.1	0.02	0.3	<0.1	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276485	Soil	17	0.36	170	0.001	<1	1.07	0.005	0.04	<0.1	0.07	2.7	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276486	Soil	4	0.01	65	0.002	<1	0.33	0.006	0.03	<0.1	<0.01	0.1	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276487	Soil	12	0.04	132	0.004	<1	0.56	0.004	0.03	0.1	0.03	0.5	0.2	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276488	Soil	8	0.02	189	0.004	<1	0.42	0.003	0.04	0.1	0.03	0.4	0.4	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276489	Soil	2	0.01	51	0.004	<1	0.28	0.020	0.02	<0.1	0.06	0.1	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276490	Soil	8	0.03	129	0.009	1	0.44	0.005	0.04	0.1	0.04	0.4	0.2	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276491	Soil	23	0.17	319	0.014	2	0.77	0.004	0.10	0.2	0.50	1.2	1.4	0.15	3	9.6	0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276422	Soil		2.1	88.4	10.6	108	2.61	16.1	2.1	1.2	504	1.7	5.6	0.4	101	0.74	0.506	13	34	0.05	1131	0.006
1276423	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276424	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276425	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276426	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276427	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276428	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276429	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1276430	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1276471	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276472	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276473	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276474	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276475	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276476	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276477	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276478	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276479	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276480	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276481	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276482	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276483	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276484	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276485	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276486	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276487	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276488	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276489	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276490	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276491	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276422	Soil		<20	0.82	0.007	0.19	<0.1	0.12	1.3	0.3	0.10	2	4.3	0.3
1276423	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276424	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276425	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276426	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276427	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276428	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276429	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1276430	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1276471	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276472	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276473	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276474	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276475	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276476	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276477	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276478	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276479	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276480	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276481	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276482	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276483	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276484	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276485	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276486	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276487	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276488	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276489	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276490	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276491	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276492	Soil		4.7	103.0	26.8	175	0.5	30.3	6.6	116	3.14	30.4	1.8	0.3	88	0.5	3.1	0.4	36	0.03	0.130	8
1276493	Soil		4.7	78.9	28.4	238	0.5	35.1	9.4	172	3.05	20.8	3.1	0.4	59	0.5	2.9	0.4	34	0.02	0.096	9
1276494	Soil		4.0	63.7	42.2	140	0.5	21.3	4.9	79	1.84	14.5	3.4	3.4	91	0.5	4.5	0.5	17	0.01	0.044	7
1276495	Soil		9.1	47.5	35.7	186	0.5	23.1	6.4	143	2.61	35.6	5.9	1.6	74	0.2	5.0	0.6	45	0.03	0.073	6
1276496	Soil		3.5	40.8	25.7	204	0.2	29.2	7.9	102	2.22	16.8	1.0	0.7	38	0.2	2.3	0.5	28	0.01	0.056	9
1276497	Soil		2.5	25.7	7.5	68	0.1	12.1	3.4	45	1.16	18.1	0.8	<0.1	7	0.3	1.2	0.2	27	0.02	0.052	7
1276498	Soil		3.0	28.0	12.1	115	0.2	17.2	5.2	96	1.96	16.6	2.1	0.1	13	0.2	1.7	0.2	32	0.02	0.051	6
1276499	Soil		5.1	40.1	19.1	131	0.4	23.4	7.2	158	3.39	23.3	2.4	0.2	21	0.2	3.1	0.3	44	0.03	0.069	8
1276500	Soil		1.1	7.6	2.8	16	0.3	2.9	0.9	23	0.39	2.3	<0.5	<0.1	5	<0.1	0.4	<0.1	15	0.02	0.028	4
1277001	Soil		10.4	23.3	19.7	27	1.0	6.5	1.5	63	1.01	21.8	4.3	0.6	32	0.2	3.1	0.2	50	0.03	0.047	19
1277002	Soil		5.1	17.3	15.1	41	1.3	15.1	1.0	55	0.57	10.1	3.9	0.3	32	0.4	1.8	0.2	39	0.15	0.050	14
1277003	Soil		10.4	14.4	19.7	59	1.1	21.0	0.8	22	0.91	17.2	4.7	0.3	35	0.1	3.5	0.2	46	0.14	0.046	19
1277004	Soil		5.4	4.2	9.7	17	0.6	3.1	0.6	13	0.37	7.8	0.7	0.2	12	<0.1	1.2	0.2	37	0.02	0.033	16
1277005	Soil		2.8	3.8	6.5	9	0.5	1.8	0.4	9	0.21	3.0	<0.5	0.1	8	<0.1	0.6	0.1	28	<0.01	0.022	28
1277006	Soil		8.7	5.3	12.7	20	0.2	3.1	0.8	15	0.44	12.9	0.7	0.3	13	<0.1	2.1	0.2	47	<0.01	0.023	24
1277007	Soil		3.7	5.7	4.4	11	0.8	2.2	0.5	12	0.31	4.3	1.3	<0.1	6	0.1	1.0	<0.1	21	0.01	0.016	13
1277008	Soil		7.9	8.2	23.2	28	0.9	5.5	1.2	26	0.76	16.2	0.5	0.1	21	<0.1	2.0	0.3	62	0.01	0.030	17
1277009	Soil		20.8	21.3	31.0	61	1.1	13.6	2.4	46	1.99	33.3	4.2	0.2	49	0.2	7.5	0.6	86	0.03	0.072	17
1277010	Soil		7.0	24.9	28.6	148	2.9	21.8	3.1	84	2.06	51.1	9.5	0.8	54	0.7	4.4	2.1	86	0.24	0.112	12
1277011	Soil		3.3	11.7	9.3	45	1.4	11.4	1.2	75	0.84	14.0	2.0	<0.1	16	0.2	1.7	0.4	24	0.08	0.098	4
1277012	Soil		10.2	19.9	22.2	73	0.3	14.7	3.6	125	3.03	21.4	2.3	0.2	21	0.2	3.2	0.5	87	0.07	0.073	17
1277013	Soil		16.2	24.2	20.2	160	0.6	31.3	4.9	136	3.07	25.2	1.7	0.7	33	0.3	5.2	0.3	73	0.15	0.058	14
1277014	Soil		32.1	11.6	8.3	483	0.3	39.1	8.2	1037	6.18	53.9	1.9	<0.1	32	2.4	3.5	0.1	29	0.32	0.209	3
1277015	Soil		0.4	1.0	1.1	4	0.6	1.0	0.3	6	0.14	<0.5	<0.5	<0.1	5	<0.1	0.1	<0.1	5	0.02	0.024	1
1277016	Soil		23.2	24.9	16.8	172	1.1	22.6	5.5	130	3.66	37.9	2.3	0.5	38	0.7	5.6	0.3	59	0.08	0.093	16
1277017	Soil		2.4	4.5	6.4	8	1.5	1.7	0.4	12	0.46	3.5	1.3	<0.1	31	<0.1	1.5	<0.1	27	0.02	0.058	3
1277018	Soil		3.6	6.2	8.6	9	1.6	1.5	0.4	9	0.45	5.1	1.1	<0.1	47	<0.1	2.0	<0.1	31	0.02	0.052	4
1277019	Soil		3.0	10.7	7.6	25	1.6	6.1	1.4	28	0.65	8.1	1.8	<0.1	10	<0.1	2.0	<0.1	44	0.02	0.030	9
1277020	Soil		1.6	6.5	6.0	11	2.3	2.6	0.5	11	0.44	7.6	0.8	<0.1	12	<0.1	1.8	<0.1	19	0.02	0.030	4
1277021	Soil		3.4	13.2	8.8	25	1.8	5.9	1.1	27	0.78	13.2	0.8	<0.1	13	0.1	3.4	<0.1	46	0.02	0.040	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276492	Soil	11	0.04	261	0.005	3	0.72	0.007	0.09	<0.1	0.07	1.5	0.4	0.11	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276493	Soil	11	0.05	351	0.006	2	0.65	0.007	0.08	0.1	0.07	1.4	0.3	0.07	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276494	Soil	5	0.02	1009	0.002	2	0.33	0.004	0.08	<0.1	0.23	2.4	0.2	0.07	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276495	Soil	13	0.06	427	0.007	4	0.50	0.006	0.11	<0.1	0.11	2.3	0.3	0.10	2	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276496	Soil	8	0.02	152	0.003	2	0.43	0.002	0.08	<0.1	0.03	1.1	0.2	0.06	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276497	Soil	6	0.02	70	0.003	<1	0.53	0.014	0.03	<0.1	0.03	0.2	0.1	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276498	Soil	8	0.04	92	0.003	<1	0.52	0.006	0.04	<0.1	0.03	0.3	0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276499	Soil	14	0.07	144	0.006	2	0.78	0.003	0.06	<0.1	0.04	0.6	0.2	0.06	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276500	Soil	3	0.01	57	0.003	<1	0.29	0.018	0.02	<0.1	0.02	0.1	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277001	Soil	8	0.03	1554	0.003	2	0.37	0.003	0.07	<0.1	0.26	0.5	0.7	0.10	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277002	Soil	7	0.04	1202	0.002	3	0.40	0.008	0.07	<0.1	0.18	0.4	0.7	0.09	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277003	Soil	6	0.03	1069	0.003	2	0.32	0.006	0.08	<0.1	0.22	0.3	0.7	0.12	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277004	Soil	6	0.02	136	0.004	2	0.30	0.006	0.05	<0.1	0.04	0.3	0.4	0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277005	Soil	6	0.01	121	0.004	2	0.21	0.003	0.04	<0.1	0.03	0.2	0.3	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277006	Soil	5	0.01	179	0.004	1	0.24	0.002	0.04	0.1	0.02	0.2	0.3	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277007	Soil	4	0.01	65	0.007	1	0.22	0.015	0.03	<0.1	0.03	0.2	0.2	<0.05	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277008	Soil	9	0.03	149	0.008	2	0.44	0.004	0.06	0.1	0.03	0.2	0.5	0.06	5	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277009	Soil	12	0.03	487	0.006	3	0.43	0.005	0.12	0.2	0.14	0.5	1.0	0.19	3	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277010	Soil	19	0.13	3088	0.004	6	1.17	0.011	0.18	0.1	0.73	1.3	0.7	0.09	4	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277011	Soil	6	0.04	580	0.003	3	0.75	0.021	0.07	<0.1	0.15	0.3	0.3	0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277012	Soil	23	0.13	248	0.019	1	0.96	0.004	0.08	<0.1	0.04	0.5	0.4	0.06	6	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277013	Soil	21	0.25	833	0.013	3	1.07	0.006	0.08	0.2	0.08	1.3	0.6	0.05	4	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277014	Soil	7	0.04	328	0.003	3	0.47	0.012	0.05	<0.1	0.08	0.5	1.0	0.10	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277015	Soil	2	0.01	31	0.003	<1	0.14	0.022	0.02	<0.1	0.03	<0.1	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277016	Soil	13	0.09	1555	0.004	3	0.42	0.003	0.10	<0.1	0.13	0.9	0.4	0.12	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277017	Soil	6	<0.01	481	0.002	<1	0.23	0.015	0.03	<0.1	0.05	0.1	0.3	0.07	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277018	Soil	8	<0.01	363	0.003	<1	0.27	0.011	0.04	<0.1	0.05	0.1	0.3	0.08	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277019	Soil	7	0.01	189	0.006	<1	0.28	0.015	0.02	<0.1	0.04	0.1	<0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277020	Soil	4	<0.01	172	0.003	1	0.17	0.015	0.02	<0.1	0.04	0.1	<0.1	<0.05	<1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277021	Soil	8	0.02	271	0.009	1	0.29	0.008	0.03	<0.1	0.05	0.4	0.1	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276492	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276493	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276494	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276495	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276496	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276497	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276498	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276499	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276500	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277001	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277002	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277003	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277004	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277005	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277006	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277007	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277008	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277009	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277010	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277011	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277012	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277013	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277014	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277015	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277016	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277017	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277018	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277019	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277020	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277021	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276492	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276493	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276494	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276495	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276496	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276497	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276498	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276499	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276500	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277017	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277019	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277021	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277022	Soil		6.6	14.1	7.7	36	0.8	8.3	2.2	43	1.18	11.3	2.3	0.5	17	<0.1	3.3	<0.1	75	<0.01	0.030	21
1277023	Soil		6.9	10.7	9.0	23	0.3	5.5	1.1	20	0.80	11.8	0.9	0.1	20	<0.1	4.3	<0.1	71	<0.01	0.032	13
1277024	Soil		5.1	23.8	10.0	40	1.9	10.6	2.7	117	1.43	11.9	8.5	0.5	52	0.1	4.6	0.1	62	0.06	0.061	10
1277025	Soil		7.2	57.3	33.8	92	0.6	20.3	5.3	147	2.15	41.4	5.9	0.9	101	0.3	5.1	0.3	58	0.05	0.105	12
1277026	Soil		5.4	80.9	23.7	139	0.4	30.4	7.1	150	2.42	25.1	4.8	0.5	62	0.3	3.4	0.3	65	0.05	0.127	11
1277027	Soil		4.2	55.4	19.2	114	0.3	23.4	7.4	301	2.03	16.1	3.0	0.9	42	0.4	2.5	0.2	51	0.07	0.093	11
1277028	Soil		7.2	42.5	16.3	116	0.1	31.5	7.5	126	2.74	13.9	1.5	0.2	21	0.8	3.2	0.2	57	0.03	0.077	7
1277029	Soil		5.0	51.7	11.8	358	0.3	72.8	12.6	219	3.51	23.5	1.1	0.1	20	0.6	6.8	<0.1	41	0.05	0.172	6
1277030	Soil		8.3	77.7	15.2	296	0.2	96.5	12.4	150	3.49	15.5	0.6	<0.1	11	0.6	5.6	0.3	73	0.03	0.132	4
1277031	Soil		12.8	49.7	20.2	477	0.1	82.0	10.4	138	2.84	39.6	1.1	<0.1	12	0.7	11.5	0.2	86	0.01	0.126	4
1277032	Soil		24.3	36.6	17.6	503	<0.1	85.9	12.6	496	3.03	33.7	<0.5	<0.1	11	0.6	14.1	0.2	125	0.02	0.127	4
1277033	Soil		15.2	27.4	15.4	261	0.2	56.4	7.5	83	2.12	25.7	1.3	<0.1	25	0.9	8.7	0.2	85	0.22	0.090	4
1277034	Soil		3.7	17.5	5.9	97	0.3	20.5	5.0	61	1.27	99.4	0.8	<0.1	15	1.1	8.9	<0.1	32	0.14	0.076	2
1277035	Soil		10.9	62.1	29.8	352	0.6	79.8	14.6	221	3.39	162.3	4.8	0.2	18	1.7	31.6	0.2	72	0.12	0.105	4
1277036	Soil		3.1	107.6	33.5	285	0.9	105.0	47.0	974	6.61	1826	80.0	0.3	53	2.3	104.2	<0.1	47	1.57	0.113	6
1277037	Soil		5.8	84.8	19.1	307	0.8	79.3	19.1	312	3.60	314.6	14.4	0.8	44	1.9	41.1	<0.1	67	1.02	0.095	5
1277038	Soil		15.8	74.8	20.5	584	1.1	110.6	13.0	264	3.03	71.6	7.6	1.2	62	4.1	22.9	0.2	87	1.15	0.137	4
1277039	Soil		5.1	15.9	11.8	141	0.7	23.2	4.6	197	1.00	19.5	1.7	0.1	27	1.5	7.3	<0.1	29	0.37	0.109	3
1277040	Soil		43.6	54.3	15.9	1134	0.8	303.4	26.5	2803	3.47	25.9	1.5	0.7	81	13.8	12.2	<0.1	107	1.64	0.130	4
1277041	Soil		15.3	59.1	16.5	2064	0.8	178.5	27.0	2800	6.94	57.2	3.6	4.3	102	13.2	8.8	0.2	67	1.82	0.160	12
1277042	Soil		6.4	60.4	22.7	378	1.0	78.3	11.3	512	3.18	35.9	5.3	1.9	137	3.6	6.8	0.2	52	5.43	0.144	8
1277043	Soil		3.6	30.8	19.3	155	1.0	20.6	4.3	261	1.66	15.1	0.8	0.4	49	1.9	3.6	0.2	43	0.70	0.193	7
1277044	Soil		12.9	52.4	43.6	540	0.8	90.7	10.7	227	3.17	46.0	7.1	2.7	84	3.3	20.5	0.3	65	0.66	0.181	12
1277045	Soil		12.0	47.5	25.2	921	1.1	112.6	10.5	270	2.80	30.0	3.3	2.1	87	6.1	7.7	0.2	56	1.70	0.163	10
1277046	Soil		12.2	69.1	39.6	515	1.5	91.6	12.6	231	3.04	38.4	4.0	2.0	87	5.0	18.5	0.2	65	0.73	0.185	12
1277047	Soil		10.4	61.5	55.4	560	1.8	93.5	10.7	327	3.09	78.1	10.9	0.8	105	4.5	53.4	0.2	58	0.98	0.228	7
1277048	Soil		7.5	28.2	15.9	178	1.0	34.8	3.6	85	1.41	17.9	2.2	<0.1	48	0.7	4.3	0.1	45	0.61	0.096	5
1277049	Soil		8.6	24.3	13.5	119	0.6	29.7	2.9	35	1.08	15.2	1.2	<0.1	15	0.8	4.6	0.1	46	0.06	0.076	5
1277050	Soil		25.3	46.3	26.0	453	0.6	93.8	9.8	236	2.75	34.6	3.6	1.1	76	2.4	14.0	0.2	91	0.43	0.174	10
1277051	Soil		36.1	45.0	20.9	367	1.4	94.7	7.0	115	1.89	28.2	2.6	0.1	61	3.9	10.6	0.2	103	0.15	0.128	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277022	Soil	11	0.01	234	0.015	2	0.27	0.003	0.03	0.1	0.03	0.4	0.1	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277023	Soil	8	<0.01	287	0.006	1	0.20	0.002	0.03	0.1	0.02	0.3	0.2	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277024	Soil	18	0.13	422	0.015	1	0.67	0.005	0.05	0.1	0.06	0.8	0.2	<0.05	3	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277025	Soil	19	0.05	211	0.005	1	0.53	0.007	0.07	<0.1	0.04	2.1	0.6	0.13	6	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277026	Soil	24	0.08	153	0.007	1	0.64	0.006	0.07	<0.1	0.06	2.5	0.3	0.05	4	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277027	Soil	16	0.11	117	0.016	1	0.73	0.010	0.06	0.1	0.03	2.4	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277028	Soil	13	0.03	192	0.005	3	0.41	0.004	0.09	<0.1	0.06	1.0	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277029	Soil	16	0.04	880	0.003	4	0.51	0.004	0.07	<0.1	0.04	1.3	0.2	0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277030	Soil	21	0.02	432	0.002	2	0.36	0.003	0.03	<0.1	0.02	0.6	0.1	<0.05	1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277031	Soil	22	0.02	162	0.001	1	0.40	0.003	0.03	<0.1	0.02	0.3	0.2	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277032	Soil	20	0.02	136	0.002	1	0.42	0.002	0.03	<0.1	0.02	0.4	0.3	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277033	Soil	17	0.02	510	0.001	<1	0.49	0.005	0.02	0.1	0.03	0.4	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277034	Soil	10	0.03	268	0.002	1	0.46	0.010	0.02	<0.1	0.04	0.5	0.1	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277035	Soil	23	0.04	309	0.002	<1	0.54	0.005	0.04	0.1	0.12	1.7	0.2	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277036	Soil	32	0.17	465	0.002	3	0.51	0.008	0.07	<0.1	0.23	24.3	0.1	0.13	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277037	Soil	31	0.13	426	0.002	3	0.63	0.011	0.05	<0.1	0.30	13.2	0.1	0.10	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277038	Soil	20	0.32	257	0.003	3	0.30	0.004	0.04	<0.1	0.37	5.7	0.2	0.10	<1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277039	Soil	7	0.07	130	0.004	1	0.75	0.014	0.02	<0.1	0.08	0.8	0.1	0.06	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277040	Soil	28	0.65	313	0.004	2	0.41	0.014	0.02	<0.1	0.48	4.4	0.3	<0.05	<1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277041	Soil	27	0.57	944	0.068	4	1.26	0.012	0.04	0.3	0.33	3.9	0.4	0.13	4	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277042	Soil	19	0.50	1227	0.021	4	0.75	0.008	0.06	0.2	0.27	3.5	0.3	0.12	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277043	Soil	12	0.08	891	0.006	2	0.87	0.011	0.02	<0.1	0.18	1.1	0.2	0.09	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277044	Soil	19	0.18	378	0.009	2	0.71	0.004	0.06	0.2	0.23	3.2	0.3	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277045	Soil	22	0.24	624	0.014	4	0.90	0.008	0.06	0.2	0.34	2.9	0.7	0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277046	Soil	21	0.20	1115	0.012	3	0.79	0.007	0.09	0.2	0.37	3.9	0.3	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277047	Soil	17	0.16	727	0.005	5	0.49	0.007	0.07	0.2	0.32	3.1	0.2	0.10	1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277048	Soil	11	0.09	552	0.004	2	0.55	0.014	0.04	0.2	0.13	0.5	0.2	0.14	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277049	Soil	9	0.03	712	0.002	1	0.48	0.010	0.03	2.6	0.06	0.4	0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277050	Soil	21	0.13	693	0.007	2	0.59	0.004	0.05	0.1	0.15	2.0	0.4	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277051	Soil	14	0.05	726	0.002	2	0.43	0.009	0.06	0.4	0.13	0.6	1.3	0.07	1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277022	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277023	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277025	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277026	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277027	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277028	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277029	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277030	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277031	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277032	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277033	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277034	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277035	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277036	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277037	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277038	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277039	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277040	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277041	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277042	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277043	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277044	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277045	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277046	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277047	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277048	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277049	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277050	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277051	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277022	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277023	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277024	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277025	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277026	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277027	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277028	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277029	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277030	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277031	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277032	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277033	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277034	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277035	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277036	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277037	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277038	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277039	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277040	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277041	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277042	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277043	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277044	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277045	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277046	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277047	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277048	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277049	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277050	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277051	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277052	Soil		19.9	21.9	16.9	146	0.4	30.5	2.8	30	1.05	13.2	2.2	<0.1	19	0.9	5.5	0.1	82	0.02	0.068	4
1277053	Soil		23.2	29.0	32.3	268	0.5	69.7	7.9	150	3.06	47.9	1.0	1.3	45	0.7	12.2	0.3	101	0.09	0.152	10
1277054	Soil		29.1	24.9	16.4	240	0.3	61.6	4.4	93	1.65	22.8	2.5	<0.1	20	0.9	8.1	0.1	109	0.04	0.061	7
1277055	Soil		12.1	12.4	16.6	102	0.6	28.3	2.7	54	1.14	14.9	0.9	<0.1	21	0.7	3.6	0.2	67	0.03	0.050	9
1277056	Soil		5.5	12.1	10.3	59	1.1	14.1	4.2	134	0.67	9.3	1.1	<0.1	14	0.8	2.1	<0.1	32	0.02	0.101	3
1277057	Soil		6.7	16.2	13.0	109	0.3	38.5	6.1	83	1.75	18.8	1.7	0.2	12	0.3	3.7	0.1	50	0.03	0.068	6
1277058	Soil		5.8	16.2	18.0	86	0.3	20.4	3.6	43	1.10	16.7	1.3	0.2	12	0.6	3.3	0.2	38	0.02	0.061	8
1277059	Soil		3.9	8.5	10.6	62	0.3	13.1	2.8	47	0.82	8.9	1.7	0.1	9	0.4	1.9	0.1	32	0.02	0.042	5
1277060	Soil		8.7	25.1	21.0	134	0.7	33.7	4.5	73	1.52	20.1	2.2	0.6	38	1.2	3.4	0.2	50	0.14	0.073	9
1277061	Soil		5.0	47.4	28.2	125	1.1	53.0	10.2	308	1.76	14.7	6.6	0.8	74	1.0	2.9	0.2	45	0.88	0.088	6
1277062	Soil		7.7	22.8	23.9	156	0.3	31.3	4.3	115	2.34	31.3	1.0	0.1	21	1.1	2.2	0.3	48	0.16	0.120	7
1277063	Soil		6.2	18.1	21.0	165	0.4	30.0	3.7	103	1.55	17.1	2.8	0.2	26	0.6	1.5	0.2	64	0.36	0.066	8
1277064	Soil		0.6	11.5	3.1	75	0.1	18.8	1.4	35	0.27	2.6	<0.5	0.1	14	0.7	0.6	<0.1	6	0.16	0.049	2
1277065	Soil		1.8	10.5	11.6	50	0.2	14.3	2.5	67	2.57	12.6	2.2	1.4	7	0.2	0.7	0.2	45	0.03	0.035	4
1277066	Soil		3.1	14.6	16.8	44	0.2	8.4	1.4	28	3.84	22.0	<0.5	0.5	6	<0.1	1.5	0.2	24	0.03	0.067	3
1277067	Soil		5.2	21.0	21.8	190	0.2	40.9	11.7	185	3.60	26.7	0.6	2.9	26	0.5	2.6	0.3	38	0.28	0.052	9
1277068	Soil		4.4	33.9	14.6	202	0.7	39.0	4.3	74	1.58	15.0	0.7	0.9	54	2.2	3.1	0.1	27	0.89	0.077	5
1277069	Soil		3.3	17.9	13.6	98	0.2	20.1	4.9	108	1.44	13.1	<0.5	0.4	13	0.7	1.8	0.1	24	0.11	0.063	7
1277070	Soil		6.6	25.1	19.9	156	0.2	30.9	5.1	83	3.13	22.8	1.0	1.3	13	0.5	2.9	0.2	51	0.07	0.091	11
1277071	Soil		4.9	33.3	21.5	207	0.4	52.2	11.0	238	2.76	18.2	1.6	2.2	53	0.7	2.6	0.2	36	0.66	0.100	7
1277072	Soil		4.3	40.4	21.1	204	0.3	51.9	14.2	165	2.84	14.1	1.6	3.6	32	1.0	2.4	0.2	40	0.27	0.106	11
1277073	Soil		3.6	52.1	33.0	132	0.6	35.4	7.8	239	2.67	15.0	<0.5	2.6	63	0.2	1.9	0.3	46	0.41	0.074	12
1277074	Soil		3.4	49.6	14.8	128	0.9	35.4	5.1	165	1.88	11.0	4.0	1.5	71	0.6	2.2	0.2	53	0.58	0.069	7
1277075	Soil		5.8	53.2	17.1	139	0.7	31.6	6.0	178	2.56	18.5	0.5	1.6	54	0.9	2.9	0.3	68	0.48	0.100	12
1277076	Soil		5.6	38.6	19.4	106	0.1	32.9	4.0	97	2.00	10.3	<0.5	1.1	35	1.5	0.6	0.3	43	0.22	0.057	6
1277077	Soil		3.8	154.2	21.1	179	0.5	39.9	9.8	243	2.98	11.6	8.6	1.4	26	0.8	1.0	0.3	52	0.16	0.064	8
1277078	Soil		2.4	42.9	12.4	52	0.8	23.3	6.1	218	1.42	5.1	3.7	0.8	42	0.6	0.6	0.2	35	0.48	0.133	6
1277079	Soil		3.3	20.7	18.4	80	0.1	20.3	4.3	111	2.85	14.6	0.5	1.7	9	0.3	1.4	0.2	58	0.02	0.036	8
1277080	Soil		3.2	41.6	17.8	141	0.4	42.2	6.6	178	3.26	15.3	4.1	2.1	40	0.6	1.4	0.2	36	0.37	0.094	6
1277081	Soil		2.3	24.2	20.3	102	0.1	24.4	4.8	142	3.72	13.4	2.2	1.1	11	0.2	0.7	0.2	41	0.05	0.104	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277052	Soil	8	0.01	135	0.002	2	0.31	0.006	0.03	0.1	0.02	0.3	0.3	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277053	Soil	22	0.09	392	0.008	1	0.55	0.003	0.06	0.2	0.03	1.9	0.4	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277054	Soil	10	0.02	222	0.003	2	0.41	0.003	0.04	0.3	0.04	0.5	0.4	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277055	Soil	10	0.05	226	0.005	1	0.47	0.005	0.04	0.4	0.02	0.4	0.3	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277056	Soil	6	0.02	213	0.003	<1	0.51	0.013	0.04	<0.1	0.07	0.4	0.3	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277057	Soil	15	0.04	117	0.006	<1	0.42	0.005	0.02	0.1	0.02	0.9	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277058	Soil	7	0.02	228	0.004	1	0.53	0.005	0.04	0.1	0.02	0.9	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277059	Soil	5	0.03	74	0.008	<1	0.31	0.007	0.03	0.1	0.01	0.5	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277060	Soil	15	0.06	421	0.004	1	0.65	0.008	0.06	0.1	0.07	1.5	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277061	Soil	18	0.15	868	0.003	4	0.97	0.013	0.07	0.1	0.33	3.7	0.3	0.10	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277062	Soil	13	0.09	351	0.003	<1	0.93	0.008	0.04	0.2	0.04	0.4	0.2	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277063	Soil	10	0.08	578	0.005	<1	0.69	0.005	0.02	0.1	0.08	0.7	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277064	Soil	2	0.03	61	0.009	1	0.47	0.028	0.03	<0.1	0.04	1.1	<0.1	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277065	Soil	18	0.17	142	0.002	<1	1.35	0.004	0.02	<0.1	0.02	1.3	0.2	<0.05	5	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277066	Soil	14	0.05	77	0.003	1	0.56	0.010	0.03	<0.1	0.03	0.7	<0.1	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277067	Soil	23	0.34	308	0.004	2	1.06	0.004	0.06	0.1	0.03	1.9	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277068	Soil	12	0.13	483	0.006	3	0.49	0.019	0.03	<0.1	0.22	1.8	0.2	0.05	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277069	Soil	10	0.09	308	0.005	1	0.49	0.013	0.03	<0.1	0.07	0.7	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277070	Soil	15	0.13	407	0.003	1	0.90	0.004	0.03	0.1	0.02	1.2	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277071	Soil	19	0.27	319	0.003	2	0.94	0.006	0.06	<0.1	0.15	2.5	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277072	Soil	23	0.34	1113	0.003	1	1.06	0.003	0.06	<0.1	0.19	2.7	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277073	Soil	26	0.28	1322	0.004	5	1.06	0.005	0.09	0.2	0.22	3.8	0.2	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277074	Soil	17	0.20	982	0.005	5	1.08	0.018	0.11	0.1	0.28	2.8	0.2	0.13	3	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277075	Soil	20	0.18	1272	0.005	6	0.95	0.005	0.11	0.2	0.32	2.8	0.2	0.08	3	2.8	0.3	N.A.	N.A.	N.A.	N.A.
1277076	Soil	39	0.15	479	0.004	3	0.84	0.007	0.09	<0.1	0.03	1.8	0.1	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277077	Soil	35	0.27	704	0.008	4	1.30	0.008	0.11	0.1	0.10	3.8	0.2	<0.05	5	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277078	Soil	18	0.10	952	0.005	5	0.97	0.012	0.07	<0.1	0.18	2.4	0.2	0.07	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277079	Soil	18	0.13	185	0.005	3	1.13	0.005	0.05	0.1	0.04	1.6	0.2	<0.05	4	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277080	Soil	19	0.26	403	0.002	2	0.84	0.004	0.07	<0.1	0.14	2.8	0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277081	Soil	24	0.24	120	0.002	2	1.12	0.005	0.06	<0.1	0.03	1.9	0.1	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277052	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277053	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277054	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277055	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277056	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277057	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277058	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277059	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277060	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277061	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277062	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277063	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277064	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277065	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277066	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277067	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277068	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277069	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277070	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277071	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277072	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277073	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277074	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277075	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277076	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277077	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277078	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277079	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277080	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277081	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277052	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277053	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277054	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277055	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277056	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277058	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277062	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277063	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277071	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277075	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277081	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277082	Soil	3.5	37.1	15.7	151	0.6	59.5	7.0	333	2.66	8.6	6.3	0.9	75	0.4	0.6	0.2	28	1.12	0.105	6
1277083	Soil	2.4	16.3	12.6	47	0.1	16.4	2.3	45	1.15	6.1	0.5	0.4	27	0.2	0.6	0.1	38	0.30	0.036	5
1277084	Soil	2.7	27.0	14.7	79	0.6	30.8	5.6	218	1.67	8.8	2.2	1.0	66	0.4	0.7	0.2	34	0.60	0.092	5
1277085	Soil	4.2	62.4	18.0	118	1.0	56.1	9.8	457	1.87	10.8	8.6	0.6	110	0.5	1.2	0.2	30	1.36	0.116	5
1277086	Soil	2.5	48.4	31.0	99	1.1	41.9	6.2	224	2.10	21.6	30.4	1.3	86	0.5	0.9	0.2	35	1.22	0.105	5
1277087	Soil	1.9	14.6	27.0	60	0.6	15.5	3.1	77	1.80	15.3	6.2	1.5	49	0.2	0.9	0.2	25	0.20	0.053	4
1277088	Soil	2.1	16.6	15.4	55	0.2	11.0	2.2	84	1.27	18.8	<0.5	0.2	31	0.4	0.8	0.2	47	0.12	0.055	7
1277089	Soil	2.8	14.4	22.5	493	0.3	87.9	22.7	1435	2.87	76.1	15.7	0.9	21	4.2	1.1	0.1	38	0.43	0.082	5
1277090	Soil	0.5	6.1	2.6	14	0.1	2.4	0.7	10	0.40	6.1	<0.5	<0.1	5	0.3	0.3	<0.1	13	0.02	0.025	2
1277091	Soil	3.4	17.3	11.0	63	0.1	14.6	3.4	51	1.55	11.8	<0.5	2.1	13	<0.1	1.2	0.2	67	0.07	0.020	11
1277092	Soil	3.2	15.8	11.6	76	0.1	19.9	4.6	74	2.37	11.9	<0.5	1.6	15	0.4	1.1	0.2	55	0.11	0.040	7
1277093	Soil	2.2	27.6	13.1	105	1.9	39.5	5.0	136	2.39	12.4	<0.5	0.6	72	1.4	1.2	0.2	48	2.02	0.140	13
1277094	Soil	0.6	9.7	4.0	29	0.3	8.9	1.3	46	0.57	1.8	1.1	<0.1	40	0.5	0.2	<0.1	12	1.31	0.068	5
1277095	Soil	4.7	24.3	17.1	89	0.4	21.0	3.7	63	1.86	12.6	2.2	0.4	12	0.3	1.4	0.2	68	0.03	0.051	11
1277096	Soil	1.9	15.4	14.5	94	0.6	17.3	5.3	89	2.75	9.4	<0.5	1.6	10	0.2	0.6	0.2	56	0.04	0.029	9
1277097	Soil	3.1	25.7	15.1	82	0.4	18.2	3.7	103	1.89	12.7	<0.5	0.6	16	0.2	1.0	0.3	62	0.13	0.035	9
1277098	Soil	3.5	92.2	11.9	149	1.5	52.4	10.2	511	2.07	7.8	3.3	0.7	39	1.3	1.2	0.2	46	1.14	0.170	7
1277099	Soil	4.9	63.8	15.7	177	0.2	32.5	5.6	138	3.82	13.9	<0.5	1.1	10	0.8	2.1	0.2	72	0.04	0.074	6
1277100	Soil	3.7	17.0	15.4	84	0.2	23.5	4.9	77	2.36	9.9	<0.5	1.5	14	0.8	1.0	0.2	65	0.24	0.032	7
1277101	Soil	4.7	38.7	15.5	130	0.4	30.4	6.3	157	2.58	15.1	2.1	1.3	25	1.2	1.7	0.2	54	0.26	0.077	8
1277102	Soil	5.3	32.7	15.8	139	0.2	31.4	7.6	186	2.66	18.7	4.7	2.6	21	0.6	2.8	0.3	56	0.12	0.082	8
1277103	Soil	4.6	52.2	15.8	136	0.6	39.5	8.4	221	2.74	17.2	4.4	3.4	34	0.6	2.7	0.2	48	0.36	0.084	10
1277104	Soil	1.9	35.9	8.8	72	0.7	20.0	3.0	57	1.23	4.6	<0.5	0.7	28	0.9	0.8	0.1	30	0.58	0.044	8
1277105	Soil	1.6	7.8	5.0	33	0.2	6.8	1.6	31	0.73	4.6	<0.5	0.5	11	0.1	0.8	<0.1	21	0.13	0.020	3
1277106	Soil	3.7	34.2	17.7	146	<0.1	29.3	6.4	94	1.86	15.1	2.3	1.3	33	0.2	1.2	0.2	50	0.04	0.051	7
1277107	Soil	2.0	128.3	15.7	118	2.9	63.2	5.6	216	1.71	8.4	19.7	2.3	68	1.1	1.8	0.2	39	1.34	0.098	6
1277108	Soil	1.0	68.1	10.9	98	1.1	41.2	5.2	188	1.50	8.5	4.3	1.7	67	0.9	1.6	0.1	33	1.50	0.083	6
1277109	Soil	5.2	20.5	15.1	86	0.1	16.8	3.4	63	1.57	16.3	<0.5	1.1	14	0.2	2.6	0.2	71	0.04	0.062	7
1277110	Soil	3.3	52.7	13.6	174	0.5	48.5	10.0	188	2.83	12.2	4.4	2.7	28	0.9	1.7	0.2	45	0.26	0.081	9
1277111	Soil	1.8	30.0	11.1	43	0.4	10.8	2.5	93	1.56	10.7	7.2	1.4	35	1.0	1.0	0.1	32	0.61	0.045	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277082	Soil	34	0.32	455	0.004	5	1.36	0.013	0.10	<0.1	0.29	3.3	0.2	0.07	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277083	Soil	16	0.05	138	0.003	1	0.56	0.008	0.04	<0.1	0.02	0.9	0.1	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277084	Soil	22	0.16	445	0.004	4	0.94	0.011	0.07	0.2	0.14	2.4	0.2	<0.05	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277085	Soil	33	0.20	689	0.005	8	1.21	0.014	0.08	0.1	0.32	2.8	0.2	0.06	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277086	Soil	31	0.27	591	0.003	6	1.35	0.011	0.12	<0.1	0.91	4.0	0.2	0.16	3	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277087	Soil	18	0.13	579	0.003	4	0.83	0.007	0.10	<0.1	0.28	2.3	0.1	0.13	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277088	Soil	12	0.06	288	0.008	2	0.99	0.015	0.05	0.2	0.06	0.6	0.1	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277089	Soil	18	0.11	227	0.006	3	2.08	0.014	0.03	<0.1	0.44	1.9	0.1	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277090	Soil	3	0.01	35	0.006	1	0.33	0.021	0.02	<0.1	0.01	0.4	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277091	Soil	12	0.04	201	0.004	2	0.58	0.003	0.05	<0.1	0.02	1.4	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277092	Soil	18	0.16	423	0.002	2	1.01	0.004	0.06	<0.1	0.03	1.7	0.2	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277093	Soil	28	0.14	623	0.003	3	0.95	0.009	0.06	<0.1	0.24	1.9	0.1	0.08	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277094	Soil	7	0.05	216	0.006	2	0.38	0.035	0.03	<0.1	0.04	0.6	<0.1	0.09	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277095	Soil	14	0.04	207	0.004	3	0.61	0.004	0.06	0.2	0.07	1.0	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277096	Soil	19	0.13	178	0.003	1	1.23	0.004	0.05	<0.1	0.03	1.9	0.2	<0.05	5	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277097	Soil	16	0.10	314	0.010	2	0.81	0.006	0.05	0.2	0.03	1.6	0.2	<0.05	4	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277098	Soil	17	0.23	546	0.006	3	1.27	0.011	0.06	<0.1	0.40	3.7	0.3	0.11	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277099	Soil	21	0.06	181	0.004	3	0.71	0.004	0.06	0.1	0.02	2.3	0.2	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277100	Soil	14	0.04	263	0.003	2	0.74	0.008	0.03	<0.1	0.02	1.5	0.1	<0.05	3	0.6	0.3	N.A.	N.A.	N.A.	N.A.
1277101	Soil	18	0.14	680	0.002	3	0.89	0.005	0.08	<0.1	0.11	1.8	0.2	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277102	Soil	18	0.17	442	0.004	<1	0.81	0.005	0.06	0.1	0.09	1.7	0.2	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277103	Soil	23	0.23	957	0.004	3	0.88	0.005	0.07	0.1	0.29	2.8	0.1	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277104	Soil	13	0.04	427	0.007	<1	0.55	0.011	0.05	0.1	0.08	0.9	<0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277105	Soil	8	0.04	89	0.005	<1	0.25	0.013	0.03	<0.1	0.04	0.5	<0.1	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277106	Soil	12	0.03	171	0.003	3	0.47	0.005	0.04	0.1	0.03	1.3	0.1	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277107	Soil	23	0.19	508	0.003	7	1.08	0.013	0.09	<0.1	0.81	4.3	0.3	0.08	3	5.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277108	Soil	21	0.20	412	0.003	<1	0.87	0.012	0.06	<0.1	0.43	2.6	<0.1	<0.05	2	6.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277109	Soil	15	0.03	115	0.004	4	0.39	0.005	0.06	0.2	0.05	1.2	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277110	Soil	24	0.23	637	0.003	3	1.04	0.005	0.06	0.1	0.26	3.4	0.1	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277111	Soil	16	0.03	466	0.004	2	0.54	0.012	0.05	<0.1	0.14	1.9	<0.1	<0.05	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277085	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277087	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277085	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277087	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277112	Soil	2.2	18.8	11.6	59	0.3	16.8	3.3	88	1.62	11.4	3.4	1.1	24	0.2	1.2	0.1	24	0.35	0.042	3
1277113	Soil	2.7	24.5	9.8	76	0.5	19.5	6.4	201	1.80	9.5	4.6	1.0	28	0.8	0.8	0.1	19	0.48	0.087	4
1277114	Soil	7.4	33.9	11.1	113	0.4	27.4	6.1	95	2.31	13.6	2.7	1.0	17	0.5	2.5	0.1	65	0.07	0.070	7
1277115	Soil	17.9	36.3	13.6	56	1.0	31.5	2.7	55	1.65	15.8	2.8	0.4	24	1.1	5.0	0.2	84	0.18	0.124	6
1277116	Soil	13.8	15.3	14.2	108	1.5	23.5	4.1	176	1.13	7.5	6.4	1.1	25	1.0	3.8	0.2	75	0.14	0.090	7
1277117	Soil	13.6	36.3	14.7	148	1.0	34.2	5.5	304	1.74	12.2	5.9	0.8	26	2.2	4.1	0.2	62	0.25	0.098	6
1277118	Soil	15.8	48.2	16.9	329	1.1	65.5	7.3	306	1.78	13.2	5.1	1.5	51	3.9	6.2	0.2	68	0.40	0.117	8
1277119	Soil	17.0	111.2	12.8	1072	2.0	256.8	20.0	467	2.23	12.2	7.5	1.2	38	18.3	5.6	0.2	80	0.48	0.120	8
1277120	Soil	8.9	75.0	7.5	1641	0.8	325.3	6.4	599	1.58	9.3	5.8	0.8	50	21.8	2.6	0.2	41	0.83	0.072	5
1277121	Soil	5.3	40.5	14.8	866	1.0	86.3	6.5	265	1.81	14.7	7.6	1.3	70	4.0	2.6	0.2	44	1.11	0.084	6
1277122	Soil	7.5	60.7	16.1	594	1.1	80.1	6.8	140	2.15	26.4	9.3	1.5	62	5.2	4.1	0.3	66	0.76	0.101	7
1277123	Soil	12.4	39.9	14.3	658	0.8	82.9	6.2	351	2.25	26.9	6.1	1.1	71	5.1	3.7	0.2	76	0.85	0.137	7
1277124	Soil	6.4	25.4	9.9	105	0.4	34.0	3.9	167	1.13	7.9	4.4	0.7	48	1.2	1.7	0.1	32	0.64	0.084	5
1277125	Soil	7.1	30.2	14.2	176	0.6	39.7	7.3	285	2.10	15.4	3.6	2.0	36	1.7	2.5	0.2	51	0.25	0.103	7
1277126	Soil	9.1	30.3	11.6	663	0.9	101.0	10.0	392	2.88	20.1	3.2	2.2	50	2.8	1.8	0.2	44	0.42	0.099	8
1277127	Soil	5.0	57.3	25.2	261	1.1	68.8	11.8	294	3.02	14.3	5.4	2.5	118	1.8	2.5	0.2	34	1.11	0.126	9
1277128	Soil	13.1	30.0	29.3	204	0.3	61.9	13.8	92	2.46	26.5	4.1	4.1	23	0.7	2.5	0.3	28	0.27	0.039	10
1277129	Soil	12.0	28.7	15.2	165	0.4	33.8	6.2	150	1.88	20.9	2.8	1.0	28	1.0	3.1	0.2	63	0.14	0.103	9
1277130	Soil	9.1	26.7	14.5	168	0.4	33.7	6.7	172	1.77	18.9	3.4	0.9	21	0.9	2.9	0.2	53	0.09	0.079	8
1277131	Soil	13.5	31.8	14.9	230	0.3	42.6	9.9	220	2.21	18.3	2.7	2.3	40	1.3	3.6	0.2	74	0.21	0.130	14
1277132	Soil	12.0	42.3	16.2	248	0.7	51.4	11.4	266	2.47	19.2	4.6	2.4	49	2.6	3.1	0.2	67	0.37	0.118	11
1277133	Soil	10.5	38.6	14.4	206	0.7	42.6	7.8	150	1.98	16.1	2.4	2.3	33	1.8	2.9	0.2	61	0.19	0.102	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277112	Soil	14	0.06	252	0.001	1	0.54	0.012	0.04	<0.1	0.13	1.6	<0.1	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277113	Soil	14	0.09	348	0.002	2	0.69	0.013	0.04	0.1	0.15	1.7	<0.1	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277114	Soil	20	0.16	311	0.003	2	0.95	0.008	0.06	0.1	0.10	1.6	0.2	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277115	Soil	15	0.06	671	0.004	2	0.96	0.011	0.06	0.2	0.44	1.2	0.4	<0.05	3	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277116	Soil	17	0.10	535	0.002	2	0.75	0.008	0.07	0.1	0.42	1.2	0.5	<0.05	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277117	Soil	12	0.10	599	0.002	2	0.74	0.010	0.05	0.1	0.37	1.3	0.4	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277118	Soil	14	0.12	969	0.001	3	0.63	0.004	0.08	0.2	0.55	1.7	0.9	0.06	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277119	Soil	19	0.14	1344	0.002	3	1.22	0.013	0.07	0.1	0.70	2.7	1.5	0.05	2	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277120	Soil	11	0.11	722	0.002	3	0.86	0.013	0.05	0.1	0.38	1.3	0.5	0.08	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277121	Soil	16	0.19	1268	0.001	3	0.76	0.005	0.05	0.1	0.55	2.0	0.2	0.09	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277122	Soil	19	0.14	1287	0.002	4	0.77	0.005	0.05	0.1	0.88	2.7	0.3	0.08	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277123	Soil	17	0.15	1678	0.003	4	0.77	0.008	0.06	0.1	0.69	2.1	0.5	0.13	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277124	Soil	10	0.13	1042	0.005	2	0.56	0.013	0.03	0.1	0.31	1.0	0.2	0.08	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277125	Soil	17	0.17	1349	0.002	1	0.82	0.005	0.05	0.1	0.40	1.8	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277126	Soil	15	0.17	1074	0.004	2	0.76	0.009	0.05	0.1	0.53	2.5	0.4	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277127	Soil	14	0.20	1622	0.004	3	1.04	0.010	0.08	<0.1	0.20	2.3	0.2	0.12	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277128	Soil	7	0.08	750	0.003	2	0.51	0.003	0.08	<0.1	0.14	1.8	0.1	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277129	Soil	13	0.09	718	0.001	1	0.59	0.005	0.05	0.1	0.15	1.1	0.3	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277130	Soil	11	0.07	539	0.002	1	0.53	0.007	0.05	0.1	0.19	0.9	0.3	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277131	Soil	16	0.12	1608	0.002	2	0.72	0.003	0.07	0.1	0.25	1.7	0.3	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277132	Soil	18	0.16	1895	0.002	2	0.94	0.005	0.06	0.1	0.37	2.5	0.3	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277133	Soil	17	0.13	1282	0.002	2	0.76	0.003	0.06	0.2	0.27	2.0	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11000998.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1276301	Soil	2.9	19.0	12.0	67	<0.1	16.0	7.7	114	1.73	13.9	1.3	0.3	8	0.1	1.5	0.3	39	0.02	0.033	9
REP 1276301	QC	2.8	18.6	12.1	67	<0.1	15.6	7.6	115	1.72	13.9	4.9	0.3	8	0.2	1.5	0.3	39	0.01	0.032	8
1276312	Soil	0.3	1.7	1.3	7	0.2	1.4	0.4	6	0.12	0.6	<0.5	<0.1	8	0.1	0.2	<0.1	6	0.04	0.016	<1
REP 1276312	QC	0.4	1.7	1.3	7	0.2	1.5	0.4	5	0.12	0.7	0.8	<0.1	7	0.1	0.2	<0.1	6	0.05	0.016	<1
1276325	Soil	3.0	33.2	14.8	300	0.4	69.0	10.7	810	2.35	15.4	2.5	1.2	78	1.6	2.2	0.2	40	1.23	0.098	4
REP 1276325	QC	2.6	29.3	13.1	274	0.4	61.7	9.9	736	2.15	13.6	1.8	1.1	70	1.4	2.0	0.2	37	1.15	0.087	4
1276373	Soil	13.5	63.4	42.0	245	1.4	84.6	7.8	108	2.64	38.6	4.7	0.4	95	1.0	24.3	0.3	189	0.13	0.186	10
REP 1276373	QC	12.4	66.3	41.3	246	1.3	86.0	7.8	107	2.69	39.8	4.0	0.3	96	1.2	24.6	0.2	182	0.12	0.186	11
1276389	Soil	69.4	56.4	24.6	218	0.3	166.3	11.2	515	4.36	37.5	1.0	3.0	159	1.5	12.6	0.1	74	5.92	0.107	4
REP 1276389	QC	67.1	55.0	24.2	216	0.3	162.4	11.0	510	4.20	38.0	1.0	2.9	154	1.3	12.6	<0.1	73	5.83	0.105	4
1276403	Soil	2.5	19.9	6.3	78	<0.1	12.9	6.7	83	1.51	7.8	1.0	0.4	7	<0.1	0.7	0.2	33	<0.01	0.033	7
REP 1276403	QC	2.6	19.2	6.4	76	<0.1	13.4	6.5	86	1.49	8.1	1.1	0.4	11	<0.1	0.6	0.2	35	0.01	0.033	8
1276473	Soil	11.1	25.5	8.0	182	0.2	42.3	6.9	87	2.14	75.5	0.7	<0.1	8	0.4	3.7	0.1	143	0.02	0.092	8
REP 1276473	QC	11.5	26.5	8.0	183	0.3	43.4	6.8	87	2.14	77.7	0.7	<0.1	8	0.4	3.7	0.1	144	0.03	0.091	8
1276477	Soil	3.7	12.3	8.9	32	0.7	6.6	1.9	37	0.93	9.3	1.6	<0.1	12	<0.1	1.6	0.2	41	0.02	0.055	6
REP 1276477	QC	3.7	12.4	9.0	32	0.7	7.0	2.0	38	0.95	9.4	1.3	<0.1	12	<0.1	1.7	0.2	42	0.02	0.053	6
1276499	Soil	5.1	40.1	19.1	131	0.4	23.4	7.2	158	3.39	23.3	2.4	0.2	21	0.2	3.1	0.3	44	0.03	0.069	8
REP 1276499	QC	5.3	38.1	19.3	128	0.4	22.2	7.0	156	3.35	23.1	2.6	0.2	20	0.2	3.2	0.3	43	0.03	0.065	8
1277012	Soil	10.2	19.9	22.2	73	0.3	14.7	3.6	125	3.03	21.4	2.3	0.2	21	0.2	3.2	0.5	87	0.07	0.073	17
REP 1277012	QC	10.4	19.2	21.8	71	0.3	14.7	3.5	121	2.94	20.8	1.6	0.2	22	0.1	3.1	0.4	85	0.06	0.071	17
1277042	Soil	6.4	60.4	22.7	378	1.0	78.3	11.3	512	3.18	35.9	5.3	1.9	137	3.6	6.8	0.2	52	5.43	0.144	8
REP 1277042	QC	6.5	59.7	22.5	372	1.0	76.8	11.4	525	3.09	35.1	5.6	1.9	139	3.5	6.8	0.2	51	5.42	0.142	8
1277064	Soil	0.6	11.5	3.1	75	0.1	18.8	1.4	35	0.27	2.6	<0.5	0.1	14	0.7	0.6	<0.1	6	0.16	0.049	2
REP 1277064	QC	0.6	11.6	3.1	73	0.1	19.3	1.4	36	0.29	2.9	0.8	0.1	14	0.7	0.6	<0.1	6	0.15	0.052	2
1277072	Soil	4.3	40.4	21.1	204	0.3	51.9	14.2	165	2.84	14.1	1.6	3.6	32	1.0	2.4	0.2	40	0.27	0.106	11
REP 1277072	QC	4.1	39.8	20.6	205	0.3	52.9	14.1	163	2.86	14.0	1.6	3.7	33	1.2	2.4	0.2	44	0.29	0.105	12
1277088	Soil	2.1	16.6	15.4	55	0.2	11.0	2.2	84	1.27	18.8	<0.5	0.2	31	0.4	0.8	0.2	47	0.12	0.055	7
REP 1277088	QC	2.2	16.5	15.4	56	0.2	10.7	2.4	84	1.24	18.0	<0.5	0.2	29	0.2	0.7	0.2	47	0.11	0.057	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000998.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1276301	Soil	9	0.03	46	0.010	<1	0.47	0.004	0.03	0.1	0.01	1.1	0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276301	QC	8	0.03	50	0.010	<1	0.43	0.003	0.03	0.1	0.02	1.1	<0.1	<0.05	3	<0.5	<0.2				
1276312	Soil	2	0.01	31	0.003	<1	0.11	0.022	0.02	<0.1	0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276312	QC	1	0.01	31	0.003	<1	0.11	0.021	0.02	<0.1	<0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2				
1276325	Soil	14	0.32	530	0.002	7	0.84	0.009	0.09	<0.1	0.17	2.5	0.3	0.07	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276325	QC	13	0.29	485	0.002	6	0.77	0.008	0.08	<0.1	0.17	2.3	0.3	<0.05	2	1.4	<0.2				
1276373	Soil	16	0.03	225	0.003	1	0.45	0.005	0.06	0.1	0.13	0.7	0.3	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276373	QC	16	0.03	231	0.004	1	0.46	0.005	0.06	0.1	0.12	0.8	0.3	<0.05	2	2.7	<0.2				
1276389	Soil	19	2.91	402	0.004	5	0.25	0.012	0.04	<0.1	0.24	4.7	0.8	0.16	<1	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276389	QC	18	2.85	381	0.004	3	0.24	0.011	0.04	<0.1	0.22	4.6	0.8	0.16	<1	4.1	<0.2				
1276403	Soil	12	0.03	46	0.003	<1	0.30	0.004	0.04	<0.1	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276403	QC	12	0.03	49	0.003	<1	0.33	0.004	0.04	<0.1	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2				
1276473	Soil	31	0.07	146	0.004	<1	0.80	0.009	0.03	0.1	0.04	0.3	0.3	<0.05	5	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276473	QC	32	0.08	148	0.005	<1	0.81	0.009	0.03	0.1	0.03	0.3	0.3	<0.05	5	2.1	<0.2				
1276477	Soil	9	0.04	353	0.006	<1	0.45	0.011	0.04	0.1	0.05	0.2	0.2	0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276477	QC	9	0.04	365	0.006	<1	0.46	0.012	0.04	0.1	0.06	0.2	0.2	<0.05	3	1.3	<0.2				
1276499	Soil	14	0.07	144	0.006	2	0.78	0.003	0.06	<0.1	0.04	0.6	0.2	0.06	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276499	QC	14	0.07	143	0.006	2	0.77	0.003	0.06	<0.1	0.05	0.6	0.2	0.05	3	2.0	<0.2				
1277012	Soil	23	0.13	248	0.019	1	0.96	0.004	0.08	<0.1	0.04	0.5	0.4	0.06	6	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277012	QC	23	0.13	252	0.019	2	0.97	0.004	0.08	0.1	0.06	0.5	0.4	<0.05	6	1.4	<0.2				
1277042	Soil	19	0.50	1227	0.021	4	0.75	0.008	0.06	0.2	0.27	3.5	0.3	0.12	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277042	QC	19	0.50	1254	0.020	3	0.74	0.008	0.06	0.3	0.29	3.2	0.3	0.08	2	0.8	<0.2				
1277064	Soil	2	0.03	61	0.009	1	0.47	0.028	0.03	<0.1	0.04	1.1	<0.1	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277064	QC	2	0.03	65	0.009	<1	0.47	0.028	0.03	<0.1	0.04	1.1	<0.1	<0.05	<1	0.7	<0.2				
1277072	Soil	23	0.34	1113	0.003	1	1.06	0.003	0.06	<0.1	0.19	2.7	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277072	QC	23	0.33	1154	0.003	2	1.11	0.004	0.06	<0.1	0.19	3.0	0.2	<0.05	3	1.8	<0.2				
1277088	Soil	12	0.06	288	0.008	2	0.99	0.015	0.05	0.2	0.06	0.6	0.1	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277088	QC	12	0.06	293	0.007	1	0.96	0.014	0.05	0.1	0.08	0.7	0.1	<0.05	4	0.8	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000998.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																					
1276301	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276301	QC																				
1276312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276312	QC																				
1276325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276325	QC																				
1276373	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276373	QC																				
1276389	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276389	QC																				
1276403	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276403	QC																				
1276473	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276473	QC																				
1276477	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276477	QC																				
1276499	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276499	QC																				
1277012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277012	QC																				
1277042	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277042	QC																				
1277064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277064	QC																				
1277072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277072	QC																				
1277088	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277088	QC																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000998.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1276301	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276301	QC													
1276312	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276312	QC													
1276325	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276325	QC													
1276373	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276373	QC													
1276389	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276389	QC													
1276403	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276403	QC													
1276473	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276473	QC													
1276477	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276477	QC													
1276499	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276499	QC													
1277012	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277012	QC													
1277042	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277042	QC													
1277064	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277064	QC													
1277072	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277072	QC													
1277088	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277088	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000998.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1277116	Soil	13.8	15.3	14.2	108	1.5	23.5	4.1	176	1.13	7.5	6.4	1.1	25	1.0	3.8	0.2	75	0.14	0.090	7
REP 1277116	QC	13.8	15.8	13.6	110	1.5	23.1	4.4	175	1.11	7.3	4.6	1.1	24	1.0	3.6	0.2	73	0.13	0.085	7
1277122	Soil	7.5	60.7	16.1	594	1.1	80.1	6.8	140	2.15	26.4	9.3	1.5	62	5.2	4.1	0.3	66	0.76	0.101	7
REP 1277122	QC	7.8	61.9	16.0	601	1.1	80.0	6.8	144	2.13	27.3	8.9	1.5	64	5.3	4.3	0.2	62	0.77	0.101	7
Reference Materials																					
STD DS8	Standard	13.9	112.8	125.6	311	1.8	37.9	7.9	613	2.42	25.6	106.1	7.1	70	2.2	5.4	6.8	41	0.70	0.079	16
STD DS8	Standard	13.6	108.8	121.7	305	1.7	37.3	7.5	605	2.47	24.5	103.7	7.3	69	2.3	5.2	6.2	41	0.68	0.077	17
STD DS8	Standard	13.2	108.4	125.3	310	1.8	37.6	7.7	582	2.40	24.3	112.5	7.1	65	2.2	5.9	7.1	41	0.67	0.077	15
STD DS8	Standard	12.9	108.0	127.4	315	1.8	37.2	7.3	602	2.79	24.3	103.7	7.3	61	2.2	4.7	6.3	42	0.74	0.076	16
STD DS8	Standard	13.2	111.7	125.8	313	1.7	38.3	7.4	615	2.47	25.7	119.6	6.7	66	2.3	5.4	6.7	43	0.68	0.082	15
STD DS8	Standard	12.1	107.1	118.5	312	1.8	38.2	7.3	619	2.42	23.8	111.3	5.8	58	2.2	4.9	6.0	41	0.68	0.081	13
STD DS8	Standard	12.3	98.4	116.7	290	1.7	35.6	7.0	551	2.26	23.5	100.0	6.8	63	2.2	5.2	6.7	38	0.62	0.071	13
STD DS8	Standard	13.6	108.4	120.3	311	1.7	37.2	7.4	620	2.44	25.1	134.8	6.6	69	2.5	5.2	6.6	42	0.68	0.082	16
STD DS8	Standard	13.0	104.7	121.0	302	1.8	38.0	7.2	610	2.41	24.3	109.7	6.4	60	2.4	5.0	6.1	42	0.69	0.078	14
STD DS8	Standard	12.3	108.3	124.0	306	1.8	37.5	7.7	589	2.41	24.9	116.6	6.2	63	2.2	5.5	6.4	41	0.63	0.079	13
STD DS8	Standard	12.7	93.5	112.6	284	1.6	33.8	6.8	561	2.26	23.2	101.4	5.9	56	2.2	5.1	6.2	39	0.65	0.074	14
STD DS8	Standard	12.8	108.2	123.2	303	1.7	37.9	7.5	619	2.49	25.2	120.4	6.7	70	2.4	5.8	6.8	43	0.72	0.080	16
STD DS8	Standard	12.5	109.2	128.5	304	1.8	37.4	7.5	597	2.35	23.9	113.7	6.6	58	2.2	5.1	6.8	40	0.65	0.082	14
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000998.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1277116	Soil	17	0.10	535	0.002	2	0.75	0.008	0.07	0.1	0.42	1.2	0.5	<0.05	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277116	QC	16	0.10	531	0.002	4	0.75	0.008	0.07	0.1	0.42	1.2	0.5	<0.05	3	2.8	<0.2				
1277122	Soil	19	0.14	1287	0.002	4	0.77	0.005	0.05	0.1	0.88	2.7	0.3	0.08	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277122	QC	18	0.14	1164	0.002	3	0.72	0.005	0.05	0.1	0.89	2.5	0.3	0.09	2	2.8	<0.2				
Reference Materials																					
STD DS8	Standard	119	0.59	282	0.126	2	0.92	0.094	0.41	3.0	0.19	2.3	5.2	0.17	5	4.9	4.6				
STD DS8	Standard	116	0.60	271	0.124	2	0.91	0.085	0.39	2.9	0.20	2.0	5.2	0.15	5	4.5	4.7				
STD DS8	Standard	117	0.64	256	0.116	<1	0.88	0.082	0.39	2.9	0.22	2.0	5.3	0.15	4	6.1	5.2				
STD DS8	Standard	117	0.57	273	0.122	3	0.91	0.083	0.42	2.9	0.20	2.2	5.6	0.16	5	5.8	4.7				
STD DS8	Standard	115	0.61	272	0.117	2	0.89	0.084	0.42	2.9	0.19	2.2	5.5	0.19	5	4.6	5.0				
STD DS8	Standard	118	0.62	265	0.101	3	0.91	0.082	0.42	2.9	0.18	2.3	5.4	0.18	5	5.4	5.5				
STD DS8	Standard	105	0.55	254	0.097	3	0.84	0.096	0.41	2.8	0.18	2.0	5.1	0.14	4	4.8	4.7				
STD DS8	Standard	119	0.62	276	0.121	2	0.92	0.087	0.40	2.9	0.19	2.2	5.2	0.17	5	5.6	5.0				
STD DS8	Standard	117	0.59	270	0.107	2	0.90	0.090	0.42	3.1	0.21	2.6	5.5	0.08	5	6.3	4.7				
STD DS8	Standard	115	0.58	254	0.106	3	0.87	0.081	0.40	3.1	0.21	2.2	5.3	0.16	5	5.6	5.2				
STD DS8	Standard	106	0.57	270	0.097	3	0.88	0.084	0.39	2.7	0.18	1.6	4.8	0.16	4	4.3	4.7				
STD DS8	Standard	119	0.60	283	0.116	3	0.93	0.087	0.40	3.2	0.22	2.4	5.4	0.07	5	6.7	4.6				
STD DS8	Standard	118	0.60	268	0.105	2	0.86	0.075	0.40	3.0	0.20	1.8	5.6	0.13	4	5.0	4.9				
STD DS8	Standard																	13.8	114.4	130.1	309
STD OREAS45CA	Standard																	1.0	536.7	20.0	62
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000998.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1277116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277116	QC																				
1277122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277122	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.9	38.8	8.0	635	2.50	23.9	99.5	7.4	73	2.4	5.4	7.0	45	0.72	0.076	16	122	0.60	297	0.123
STD OREAS45CA	Standard	0.3	252.6	88.8	895	16.54	4.1	45.8	6.9	16	0.1	0.1	0.2	203	0.42	0.036	16	732	0.16	165	0.149
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000998.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1277116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277116	QC												
1277122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277122	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.94	0.096	0.42	3.3	0.18	2.4	5.5	0.15	5	5.2	4.8
STD OREAS45CA	Standard	<20	3.78	0.013	0.07	<0.1	0.03	36.8	<0.1	<0.05	18	0.8	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000998.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000998.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000998.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11000998.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 03, 2011
Report Date: October 10, 2011
Page: 1 of 10

CERTIFICATE OF ANALYSIS WHI11000999.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #9
P.O. Number
Number of Samples: 264

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	264	Sieve to 230 mesh			WHI
RJSV	264	Saving all or part of Soil Reject			WHI
1DX2	263	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	1	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277134	Soil	4.0	60.4	18.9	203	2.9	86.1	14.7	255	3.78	23.1	5.5	2.0	37	0.3	1.4	0.5	38	0.04	0.122	7
1277135	Soil	2.6	42.8	24.8	153	1.7	54.9	8.8	174	3.39	24.7	6.0	2.0	59	0.5	1.3	0.4	28	0.21	0.117	6
1277136	Soil	3.3	27.2	12.6	110	0.3	27.1	7.1	366	2.92	18.1	3.7	0.1	13	0.3	1.4	0.3	51	0.05	0.108	7
1277137	Soil	2.5	33.5	13.0	73	0.5	23.6	4.4	119	2.09	11.0	3.9	0.8	14	0.2	0.9	0.2	40	0.08	0.072	7
1277138	Soil	4.3	22.9	10.1	91	0.2	27.2	5.1	73	2.18	25.4	4.6	0.5	9	0.1	1.6	0.2	69	0.04	0.056	9
1277139	Soil	3.2	21.7	17.6	81	0.2	19.2	4.0	76	2.29	21.6	2.2	1.0	9	0.1	1.7	0.3	55	0.02	0.038	7
1277140	Soil	3.5	47.4	34.4	163	1.5	55.4	27.1	581	3.67	21.5	4.6	2.8	21	0.6	1.2	0.3	31	0.09	0.099	5
1277141	Soil	3.5	60.3	16.6	194	0.9	57.3	13.6	426	3.70	17.6	4.4	1.7	32	0.4	1.7	0.3	35	0.05	0.086	7
1277142	Soil	3.1	61.7	20.1	211	0.9	77.2	19.1	614	4.93	14.7	7.1	1.2	41	0.5	1.8	0.3	45	0.13	0.122	7
1277143	Soil	2.3	52.1	20.1	222	2.4	79.5	13.5	231	3.61	15.7	3.7	2.9	85	1.1	1.5	0.3	42	1.48	0.261	13
1277144	Soil	3.6	69.0	43.3	223	1.5	91.2	38.8	256	5.21	41.9	2.3	3.5	63	0.5	1.3	0.4	36	0.37	0.110	3
1277145	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1277146	Soil	1.1	39.9	13.7	120	1.0	54.0	7.0	160	2.08	18.9	3.9	0.9	86	0.4	0.9	0.2	25	1.74	0.100	6
1277147	Soil	0.8	15.8	5.1	57	0.2	12.8	1.6	34	1.66	204.5	15.8	0.6	21	0.2	7.0	<0.1	8	0.25	0.033	2
1277148	Soil	1.3	37.8	15.0	150	0.7	50.6	8.0	148	2.26	104.8	19.3	1.2	59	0.9	4.9	0.2	28	0.92	0.116	7
1277149	Soil	1.6	36.8	12.9	147	1.3	45.2	7.4	197	1.88	24.1	8.6	1.0	73	1.0	1.5	0.2	27	1.73	0.141	9
1277150	Soil	2.4	53.3	20.3	219	2.0	76.8	13.8	212	3.13	50.7	10.4	2.2	65	1.2	2.4	0.3	32	0.91	0.175	9
1277601	Soil	74.8	68.8	12.7	463	0.3	188.5	10.7	313	2.73	23.2	<0.5	2.9	153	3.5	8.5	<0.1	112	8.52	0.071	3
1277602	Soil	85.6	80.3	14.9	601	0.5	222.0	12.6	294	2.96	28.6	1.1	3.0	113	5.3	13.1	0.1	139	6.87	0.065	3
1277603	Soil	84.0	94.0	18.0	843	0.9	205.6	8.9	218	2.69	41.0	4.0	1.0	77	5.7	22.3	0.2	219	3.82	0.079	3
1277604	Soil	71.7	79.0	14.9	391	0.5	203.1	18.7	422	3.59	22.3	1.2	1.1	115	3.8	4.1	0.1	118	4.19	0.158	4
1277605	Soil	90.6	141.8	15.7	1069	2.1	278.0	8.5	199	2.21	47.2	3.1	0.8	257	12.9	21.9	0.2	323	3.75	0.332	6
1277606	Soil	16.0	41.2	14.6	244	<0.1	43.6	8.8	132	2.61	18.8	2.4	0.1	11	0.5	5.0	0.3	70	0.05	0.081	7
1277607	Soil	21.7	54.2	16.8	258	<0.1	63.9	11.6	164	2.91	23.6	1.5	0.1	13	0.4	6.1	0.3	96	0.03	0.067	6
1277608	Soil	10.2	27.2	98.2	150	1.3	24.7	4.4	200	2.20	42.7	3.7	0.3	95	0.2	14.9	0.3	53	0.03	0.069	4
1277609	Soil	8.5	12.9	31.9	66	1.4	14.1	2.1	25	0.79	11.4	1.4	<0.1	18	0.1	4.1	0.2	43	0.01	0.062	2
1277610	Soil	13.1	22.7	34.5	93	0.5	24.0	3.4	130	1.35	21.1	2.8	<0.1	33	0.4	5.7	0.2	61	0.05	0.090	4
1277611	Soil	48.2	65.9	36.4	915	1.4	178.2	12.2	239	3.32	37.4	3.5	0.6	126	10.8	15.7	0.2	184	1.03	0.193	4
1277612	Soil	20.6	65.0	65.1	500	0.3	68.3	8.6	284	3.08	31.8	1.1	<0.1	108	1.4	8.3	0.2	116	0.05	0.129	5
1277613	Soil	7.1	44.1	36.7	134	0.4	24.3	3.0	62	1.36	18.7	1.3	<0.1	109	0.7	5.0	0.1	66	0.07	0.135	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277134	Soil	26	0.11	384	0.003	3	0.96	0.005	0.11	<0.1	0.61	4.0	0.3	0.13	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277135	Soil	20	0.08	821	0.001	4	0.83	0.006	0.13	<0.1	0.23	2.9	0.2	0.21	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277136	Soil	27	0.18	177	0.006	2	1.06	0.005	0.07	0.1	0.09	0.5	0.2	0.13	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277137	Soil	19	0.18	275	0.011	5	1.15	0.011	0.09	0.2	0.15	1.1	0.2	0.06	4	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277138	Soil	20	0.05	120	0.008	2	0.61	0.004	0.04	0.3	0.03	1.1	0.1	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277139	Soil	15	0.06	139	0.010	2	0.57	0.003	0.05	0.2	0.04	1.4	0.2	0.06	4	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277140	Soil	31	0.19	791	0.003	4	1.26	0.007	0.12	0.1	0.13	5.3	0.2	0.12	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277141	Soil	24	0.18	276	0.004	2	0.92	0.004	0.08	0.1	0.09	3.8	0.2	0.11	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277142	Soil	25	0.15	342	0.005	2	1.05	0.004	0.06	0.1	0.15	3.7	0.1	0.10	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277143	Soil	30	0.16	830	0.003	4	0.83	0.010	0.11	<0.1	0.25	4.2	0.2	0.11	2	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277144	Soil	29	0.30	249	0.001	2	1.41	0.005	0.11	<0.1	0.13	5.3	0.2	0.22	3	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277145	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.3	64.0	24.1	258
1277146	Soil	23	0.13	664	0.002	8	0.67	0.006	0.09	<0.1	0.39	2.8	0.1	0.20	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277147	Soil	8	0.02	131	<0.001	2	0.22	0.002	0.03	0.1	0.78	0.8	<0.1	0.08	<1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277148	Soil	25	0.09	480	0.002	7	0.70	0.006	0.10	0.1	0.98	2.5	0.1	0.10	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277149	Soil	23	0.13	462	0.002	7	0.62	0.008	0.08	<0.1	0.36	2.4	0.1	0.13	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277150	Soil	29	0.14	503	0.003	5	0.75	0.006	0.11	<0.1	0.44	3.8	0.2	0.19	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277601	Soil	15	3.94	192	0.002	3	0.17	0.007	0.03	<0.1	0.24	3.7	0.9	0.09	<1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277602	Soil	17	3.81	179	0.003	4	0.21	0.006	0.04	0.1	0.31	4.3	0.9	0.11	<1	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277603	Soil	21	1.71	707	0.001	3	0.28	0.003	0.04	0.1	0.44	3.1	0.7	0.10	<1	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277604	Soil	53	1.87	212	0.003	3	0.41	0.005	0.04	0.2	0.22	5.9	0.9	0.13	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277605	Soil	38	1.12	210	0.004	4	0.44	0.007	0.06	0.3	0.81	3.3	1.5	0.10	1	8.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277606	Soil	14	0.04	72	0.003	1	0.53	0.004	0.04	0.1	0.02	0.4	0.2	0.09	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277607	Soil	14	0.02	56	0.004	<1	0.40	0.005	0.03	<0.1	0.03	0.6	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277608	Soil	11	0.03	154	0.005	1	0.37	0.006	0.07	<0.1	0.08	0.8	0.5	0.19	3	3.0	0.2	N.A.	N.A.	N.A.	N.A.
1277609	Soil	8	0.01	64	0.002	<1	0.25	0.008	0.03	<0.1	0.06	0.2	0.3	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277610	Soil	13	0.03	126	0.002	<1	0.45	0.008	0.04	0.1	0.10	0.2	0.7	0.11	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277611	Soil	46	0.14	348	0.003	2	0.43	0.007	0.05	0.1	0.71	4.3	0.7	0.10	1	6.1	0.2	N.A.	N.A.	N.A.	N.A.
1277612	Soil	17	0.03	338	0.003	1	0.45	0.009	0.04	0.1	0.04	0.5	0.2	0.10	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277613	Soil	10	0.02	251	0.002	1	0.56	0.016	0.04	0.1	0.06	0.2	0.2	0.09	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277134	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277135	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277136	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277137	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277138	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277139	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277140	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277141	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277142	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277143	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277144	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277145	Soil		2.0	98.6	18.4	293	3.24	17.4	2.5	1.8	93	1.4	1.3	0.3	41	1.59	0.235	9	32	0.18	917	0.002
1277146	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277147	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277148	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277149	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277150	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277601	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277602	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277603	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277604	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277605	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277606	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277607	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277608	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277609	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277610	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277611	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277612	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277613	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277141	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277142	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277143	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277144	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277145	Soil	<20	0.96	0.010	0.13	<0.1	0.29	3.9	0.3	0.12	3	4.6	<0.2
1277146	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277147	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277148	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277149	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277150	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277601	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277602	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277603	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277604	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277605	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277606	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277607	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277608	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277609	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277610	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277611	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277612	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277613	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277614	Soil	64.0	297.7	99.5	3293	2.9	374.5	42.1	1027	10.63	225.8	5.1	1.6	592	15.6	36.8	0.3	505	0.59	0.727	6
1277615	Soil	12.4	28.1	96.1	78	1.4	8.6	2.2	63	1.43	27.5	4.3	<0.1	159	0.3	6.2	0.2	198	0.08	0.163	5
1277616	Soil	11.3	48.3	67.7	269	0.3	68.0	8.3	112	2.33	51.5	3.6	0.1	69	0.3	25.3	0.3	139	0.02	0.080	7
1277617	Soil	2.4	27.4	10.5	68	0.9	22.7	5.0	159	1.59	7.9	4.7	0.7	69	0.7	1.2	0.2	44	1.90	0.059	6
1277618	Soil	0.4	14.5	3.1	39	0.2	10.6	2.2	128	0.44	1.4	0.7	<0.1	67	0.7	0.4	<0.1	11	1.91	0.060	4
1277619	Soil	2.0	18.3	9.3	102	0.8	29.1	4.2	139	1.83	8.7	1.6	0.3	83	1.5	1.0	0.1	44	2.20	0.111	10
1277620	Soil	1.8	25.6	5.8	71	0.6	18.6	3.9	134	1.04	5.4	2.1	0.5	47	1.0	0.8	0.3	26	1.04	0.064	5
1277621	Soil	1.8	27.9	6.2	69	1.0	19.2	2.5	94	0.94	5.3	2.2	0.2	42	0.7	0.9	0.2	24	0.86	0.063	4
1277622	Soil	2.0	36.0	6.8	54	0.8	28.9	6.7	607	1.48	6.4	3.5	0.3	66	1.2	1.2	0.3	27	1.39	0.108	6
1277623	Soil	5.9	43.4	15.7	153	0.2	37.3	6.6	184	2.73	19.2	4.3	2.2	22	0.7	2.4	0.2	57	0.17	0.093	9
1277624	Soil	3.7	17.1	11.1	68	0.3	13.5	3.1	88	1.84	11.9	1.5	0.4	11	0.5	1.3	0.2	49	0.06	0.038	7
1277625	Soil	1.3	38.5	5.1	51	1.0	25.1	3.3	149	0.90	3.9	1.5	0.2	79	1.3	0.8	0.2	17	2.04	0.086	4
1277626	Soil	3.1	40.7	8.0	106	0.9	39.9	5.3	358	1.63	8.4	3.1	0.9	64	1.6	1.8	0.2	35	1.05	0.094	7
1277627	Soil	3.0	47.1	12.8	173	0.8	48.9	7.5	244	2.30	11.4	3.7	1.5	58	1.2	2.0	0.2	47	1.00	0.119	8
1277628	Soil	3.0	51.8	14.4	176	0.9	49.6	8.5	286	2.39	11.7	5.4	1.7	58	1.4	1.9	0.2	47	1.01	0.119	7
1277629	Soil	2.5	50.1	15.4	196	1.0	50.9	10.1	277	2.48	12.2	7.0	1.9	55	1.4	1.8	0.2	52	0.88	0.119	8
1277630	Soil	3.1	55.7	13.1	213	0.9	54.1	8.1	434	2.56	13.2	5.3	1.9	70	1.4	2.2	0.2	52	1.27	0.116	8
1277631	Soil	3.1	53.3	16.1	250	1.6	68.9	10.0	416	4.24	21.0	5.6	2.2	67	1.9	1.6	0.2	53	1.28	0.116	7
1277632	Soil	0.6	9.2	1.7	38	0.2	6.9	1.7	150	0.43	2.3	1.1	0.1	35	0.5	0.6	<0.1	13	0.68	0.053	2
1277633	Soil	4.8	25.6	12.8	119	0.5	25.5	8.1	218	2.12	13.3	3.2	2.5	48	0.8	1.9	0.2	56	0.60	0.103	10
1277634	Soil	3.2	30.0	6.5	83	0.8	22.2	4.5	501	1.26	6.6	1.7	0.6	78	2.7	1.4	0.1	37	1.43	0.100	5
1277635	Soil	10.1	23.2	14.2	135	0.5	27.2	4.5	92	2.33	22.6	2.7	1.0	20	0.4	3.4	0.2	103	0.05	0.051	8
1277636	Soil	4.9	32.7	6.3	120	1.0	30.9	6.8	450	1.56	6.2	1.7	0.3	57	3.0	1.4	0.2	37	0.98	0.169	3
1277637	Soil	6.7	39.8	15.9	174	0.6	35.0	6.5	185	2.79	18.7	3.7	1.4	31	2.4	2.6	0.3	79	0.24	0.067	12
1277638	Soil	8.1	41.2	18.6	221	0.2	39.9	6.4	156	3.65	28.3	4.4	2.2	22	0.8	3.5	0.3	98	0.05	0.124	10
1277639	Soil	1.0	7.4	4.3	21	0.1	5.0	1.1	31	0.56	3.0	0.6	<0.1	8	0.1	0.4	<0.1	23	0.07	0.058	6
1277640	Soil	2.0	15.3	8.5	54	0.2	11.8	2.8	90	1.48	8.0	3.8	<0.1	10	0.1	0.9	0.2	34	0.05	0.069	5
1277641	Soil	1.2	10.2	6.6	33	0.1	7.5	1.8	44	1.09	6.3	0.7	<0.1	7	0.1	0.6	0.1	25	0.03	0.072	3
1277642	Soil	1.7	16.6	7.9	52	0.2	12.8	3.3	102	1.72	8.0	0.9	<0.1	10	0.2	0.9	0.2	30	0.05	0.060	7
1277643	Soil	1.9	28.2	12.0	92	0.5	27.0	5.7	153	2.10	10.3	2.0	0.3	29	0.3	0.7	0.2	27	0.10	0.078	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277614	Soil	33	0.03	888	0.007	2	0.89	0.003	0.07	0.2	0.40	7.7	0.6	0.07	1	5.3	0.2	N.A.	N.A.	N.A.	N.A.
1277615	Soil	13	0.08	164	0.004	1	0.69	0.015	0.04	0.2	0.08	0.2	0.2	0.09	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277616	Soil	13	0.02	137	0.004	1	0.31	0.001	0.03	0.1	0.04	0.6	0.1	0.06	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277617	Soil	15	0.12	830	0.003	2	0.90	0.010	0.04	<0.1	0.16	1.7	0.2	0.10	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277618	Soil	6	0.05	251	0.006	3	0.38	0.026	0.02	<0.1	0.04	0.4	<0.1	0.10	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277619	Soil	23	0.17	612	0.005	4	0.86	0.009	0.05	0.1	0.11	1.3	0.1	0.09	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277620	Soil	12	0.08	478	0.003	4	0.60	0.016	0.03	<0.1	0.12	1.3	<0.1	0.08	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277621	Soil	10	0.06	526	0.005	2	0.66	0.022	0.04	<0.1	0.15	0.9	0.1	0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277622	Soil	10	0.10	727	0.008	5	0.83	0.019	0.04	<0.1	0.20	1.3	0.1	0.13	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277623	Soil	18	0.16	557	0.002	3	0.90	0.005	0.05	0.1	0.08	2.1	0.3	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277624	Soil	12	0.08	173	0.006	2	0.60	0.005	0.05	0.1	0.04	0.9	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277625	Soil	9	0.10	575	0.006	2	0.66	0.014	0.03	<0.1	0.20	1.0	<0.1	0.12	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277626	Soil	12	0.13	1058	0.005	3	0.83	0.013	0.05	0.1	0.23	1.9	0.2	0.09	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277627	Soil	20	0.24	956	0.003	4	0.99	0.007	0.09	0.2	0.41	2.9	0.2	0.10	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277628	Soil	21	0.24	840	0.002	3	0.98	0.006	0.09	0.2	0.42	3.1	0.2	0.07	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277629	Soil	21	0.26	927	0.002	5	1.10	0.006	0.10	0.2	0.45	3.3	0.2	0.05	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277630	Soil	20	0.27	817	0.002	5	1.07	0.007	0.11	0.1	0.41	3.0	0.2	0.10	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277631	Soil	22	0.27	583	0.002	5	1.17	0.007	0.11	<0.1	0.50	3.8	0.2	0.11	3	7.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277632	Soil	4	0.05	470	0.008	2	0.40	0.031	0.04	<0.1	0.08	0.4	<0.1	0.06	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277633	Soil	19	0.24	856	0.004	2	0.92	0.005	0.07	0.2	0.17	2.2	0.1	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277634	Soil	13	0.13	1087	0.006	4	0.92	0.014	0.05	<0.1	0.16	1.3	<0.1	0.10	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277635	Soil	14	0.08	312	0.004	2	0.85	0.005	0.04	0.2	0.06	1.4	0.3	<0.05	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277636	Soil	11	0.10	788	0.008	5	0.94	0.018	0.06	<0.1	0.26	2.0	0.3	0.16	3	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277637	Soil	20	0.13	1750	0.003	2	1.24	0.005	0.07	0.2	0.25	2.1	0.3	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277638	Soil	26	0.15	413	0.003	3	1.21	0.004	0.09	0.2	0.09	2.1	0.3	<0.05	4	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277639	Soil	7	0.04	195	0.005	<1	0.58	0.014	0.03	<0.1	0.03	0.2	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277640	Soil	14	0.04	263	0.003	1	0.68	0.008	0.04	0.1	0.04	0.4	0.1	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277641	Soil	10	0.03	75	0.004	1	0.66	0.012	0.03	<0.1	0.05	0.2	<0.1	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277642	Soil	15	0.12	118	0.011	1	0.90	0.013	0.05	0.2	0.04	0.5	0.1	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277643	Soil	17	0.13	408	0.005	3	0.98	0.013	0.06	<0.1	0.09	1.3	0.1	0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277614	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277615	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277616	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277617	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277618	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277619	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277620	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277621	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277622	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277623	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277624	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277625	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277626	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277627	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277628	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277629	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277630	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277631	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277632	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277633	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277634	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277635	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277636	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277637	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277638	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277639	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277640	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277641	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277642	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277643	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277614	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277615	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277616	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277617	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277618	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277619	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277620	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277621	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277622	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277623	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277624	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277625	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277626	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277627	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277628	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277629	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277630	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277631	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277632	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277633	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277634	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277635	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277636	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277637	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277638	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277639	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277640	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277641	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277642	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277643	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277644	Soil	2.5	21.0	9.7	70	0.4	18.4	4.7	82	1.86	9.7	0.9	0.1	12	0.1	0.8	0.2	38	0.06	0.092	5
1277645	Soil	2.4	32.1	17.0	115	0.7	27.5	6.8	382	3.13	14.5	3.4	0.5	19	0.4	1.3	0.2	36	0.07	0.104	7
1277646	Soil	2.1	37.8	18.2	125	1.0	40.3	10.0	127	3.20	14.2	2.6	0.6	22	0.2	0.8	0.2	29	0.04	0.112	4
1277647	Soil	3.0	43.3	28.6	154	1.1	46.8	15.3	502	3.43	16.9	1.8	1.7	32	0.3	1.1	0.3	28	0.06	0.136	4
1277648	Soil	3.4	31.1	31.8	103	1.1	22.5	7.7	317	2.42	19.1	1.4	0.4	22	0.2	1.2	0.2	25	0.05	0.098	3
1277649	Soil	2.8	44.0	12.8	117	0.2	41.3	5.5	42	2.63	14.0	0.9	1.6	43	0.1	0.8	0.2	21	0.04	0.053	2
1277650	Soil	3.6	51.9	16.7	147	0.5	36.1	6.8	108	3.52	15.0	6.3	0.4	25	0.2	1.7	0.3	53	0.02	0.107	6
1277651	Soil	2.3	69.2	28.2	232	2.3	91.5	20.2	565	4.20	27.8	4.4	2.7	89	1.0	1.6	0.3	33	0.54	0.202	8
1277652	Soil	2.9	37.9	17.2	175	3.6	62.9	6.2	104	2.89	22.2	2.7	1.5	91	1.4	1.5	0.2	48	1.51	0.253	14
1277653	Soil	3.8	58.8	21.4	204	4.0	65.7	7.4	148	3.01	20.4	6.0	1.6	132	1.4	1.6	0.3	43	1.55	0.196	12
1277654	Soil	1.5	28.3	12.6	129	1.7	37.9	4.7	104	1.94	8.6	1.9	0.5	64	0.8	1.0	0.2	29	1.74	0.145	7
1277655	Soil	2.4	42.9	19.6	164	1.8	50.5	8.3	220	3.05	32.7	9.7	1.0	75	0.8	1.3	0.2	32	1.37	0.129	8
1277656	Soil	3.2	44.8	22.4	100	1.2	26.4	5.2	153	2.83	534.0	355.6	1.3	104	0.4	3.7	0.3	32	0.05	0.123	5
1277657	Soil	2.7	48.3	39.5	131	1.7	35.6	10.5	299	3.64	645.3	106.0	2.9	95	0.8	4.2	0.3	27	0.09	0.121	6
1277658	Soil	1.7	22.5	17.6	68	0.9	18.2	4.6	171	2.14	84.3	18.3	0.5	34	0.2	0.9	0.2	19	0.04	0.107	2
1277659	Soil	4.7	40.0	11.1	180	1.4	35.0	5.8	161	2.01	15.6	5.3	1.1	58	2.0	3.1	0.2	48	0.81	0.094	6
1277660	Soil	2.3	45.1	7.0	98	1.0	42.2	7.7	288	2.16	10.2	6.1	0.2	143	13.7	2.8	0.2	46	2.53	0.153	5
1277661	Soil	4.8	23.9	9.9	185	1.0	29.6	9.4	1690	1.87	9.1	3.5	0.6	95	6.9	1.9	0.2	59	1.60	0.167	6
1277662	Soil	7.7	29.8	14.3	189	0.4	33.8	6.4	185	2.44	22.7	5.5	1.1	42	1.2	3.4	0.2	80	0.33	0.083	9
1277663	Soil	6.5	43.6	12.4	222	0.8	41.6	6.8	198	2.26	18.5	5.4	1.6	62	1.3	3.5	0.2	78	0.64	0.109	9
1277664	Soil	1.7	21.0	2.5	76	0.4	19.6	3.2	193	0.75	5.0	2.3	0.1	45	2.0	1.4	0.1	25	0.74	0.079	3
1277665	Soil	9.0	62.6	15.7	747	1.5	120.2	13.6	888	2.58	33.4	9.2	1.5	82	6.3	5.6	0.2	76	0.74	0.154	9
1277666	Soil	12.8	33.7	14.7	317	0.7	63.0	6.0	271	1.94	35.6	9.8	0.7	56	1.8	5.4	0.2	99	0.45	0.153	9
1277667	Soil	48.1	41.6	15.3	4447	1.1	1002	16.2	3676	2.75	96.7	7.8	1.3	55	10.3	5.6	0.2	96	0.28	0.124	9
1277668	Soil	16.3	60.1	20.4	665	1.4	144.0	29.2	3195	5.32	86.2	11.5	1.5	44	5.6	10.5	0.2	156	0.26	0.563	8
1277669	Soil	11.7	28.4	12.5	291	1.2	43.5	3.8	218	1.78	39.4	5.5	0.6	39	1.1	4.4	0.2	97	0.12	0.155	7
1277670	Soil	1.5	27.1	7.9	103	1.1	24.8	5.9	52	0.59	3.8	4.5	0.4	58	2.3	1.3	0.2	43	0.95	0.083	5
1278001	Soil	0.8	20.7	9.0	79	0.6	21.3	3.5	68	1.51	140.1	19.9	0.9	38	0.4	3.7	<0.1	14	0.48	0.073	4
1278002	Soil	1.7	38.1	14.5	139	1.3	44.0	8.2	137	2.76	111.3	13.5	1.6	60	0.5	3.2	0.2	27	0.69	0.108	7
1278003	Soil	1.7	50.9	15.7	168	1.6	54.8	8.2	110	2.78	48.0	9.1	1.4	81	0.7	2.2	0.2	33	0.96	0.153	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277644	Soil	16	0.06	337	0.003	2	0.81	0.008	0.05	0.1	0.04	0.5	0.1	0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277645	Soil	22	0.15	185	0.006	2	0.88	0.004	0.08	0.1	0.09	1.5	0.1	0.07	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277646	Soil	28	0.09	225	0.003	2	1.12	0.007	0.05	<0.1	0.07	1.9	0.1	0.06	4	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277647	Soil	25	0.18	324	0.003	2	1.24	0.008	0.10	<0.1	0.07	4.4	0.1	<0.05	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277648	Soil	17	0.06	348	0.003	3	0.74	0.011	0.10	<0.1	0.13	1.5	0.1	0.10	3	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277649	Soil	20	0.10	321	<0.001	1	0.83	0.004	0.05	<0.1	0.17	4.6	<0.1	<0.05	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277650	Soil	18	0.05	183	0.004	3	0.66	0.004	0.08	0.1	0.10	1.9	0.2	0.09	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277651	Soil	18	0.11	499	0.004	3	0.63	0.012	0.09	0.1	0.78	7.7	0.2	0.06	2	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277652	Soil	29	0.07	666	0.003	7	0.72	0.010	0.13	<0.1	0.32	3.1	0.3	0.19	2	7.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277653	Soil	33	0.14	672	0.003	6	0.95	0.010	0.13	<0.1	0.52	3.5	0.3	0.15	2	5.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277654	Soil	20	0.10	387	0.003	4	0.71	0.011	0.06	<0.1	0.22	1.4	<0.1	0.11	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277655	Soil	25	0.14	544	0.002	6	0.87	0.007	0.13	<0.1	0.29	3.2	0.2	0.14	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277656	Soil	24	0.07	260	0.003	2	0.81	0.004	0.14	0.3	0.37	1.8	0.3	0.22	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277657	Soil	27	0.11	365	0.002	2	0.96	0.003	0.12	0.3	0.27	5.2	0.2	0.15	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277658	Soil	21	0.08	218	0.002	2	0.74	0.008	0.09	<0.1	0.14	1.1	0.1	0.15	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277659	Soil	15	0.13	2420	0.002	2	0.81	0.010	0.06	0.1	0.31	2.1	0.2	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277660	Soil	13	0.10	2310	0.005	4	0.85	0.007	0.03	<0.1	0.38	1.1	0.1	0.29	2	12.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277661	Soil	19	0.15	1164	0.004	3	1.12	0.009	0.04	0.2	0.56	1.5	0.2	0.19	3	9.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277662	Soil	20	0.17	907	0.003	2	0.87	0.005	0.07	0.2	0.18	1.6	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277663	Soil	22	0.18	2187	0.003	3	1.00	0.006	0.10	0.2	0.40	2.4	0.3	0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277664	Soil	5	0.06	641	0.004	2	0.48	0.027	0.03	<0.1	0.23	0.6	0.1	0.08	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277665	Soil	23	0.12	2058	0.002	3	0.80	0.004	0.06	<0.1	1.45	3.0	0.4	0.07	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277666	Soil	21	0.08	1040	0.002	3	0.74	0.005	0.09	0.1	0.51	1.2	0.6	0.06	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277667	Soil	25	0.10	1506	0.004	4	0.86	0.002	0.11	0.2	0.38	2.5	0.8	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277668	Soil	28	0.06	1847	0.008	4	1.02	0.001	0.07	0.2	0.58	4.0	0.7	<0.05	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277669	Soil	17	0.05	1184	0.003	3	0.62	0.001	0.06	0.1	0.35	0.9	0.4	0.07	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277670	Soil	12	0.08	1003	0.003	3	0.90	0.022	0.05	<0.1	0.45	1.5	0.3	0.17	3	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278001	Soil	14	0.06	254	0.001	4	0.39	0.003	0.06	<0.1	0.68	1.9	<0.1	0.07	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278002	Soil	21	0.10	399	0.001	3	0.67	0.004	0.09	<0.1	0.68	3.2	0.1	0.08	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278003	Soil	25	0.14	497	0.002	5	0.96	0.007	0.09	<0.1	0.53	3.4	0.2	0.08	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277644	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277645	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277646	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277647	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277648	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277649	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277650	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277651	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277652	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277653	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277654	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277655	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277656	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277657	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277658	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277659	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277660	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277661	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277662	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277663	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277664	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277665	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277666	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277667	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277668	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277669	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277670	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278001	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278002	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278003	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277644	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277645	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277646	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277647	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277648	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277649	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277650	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277651	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277652	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277653	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277654	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277655	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277656	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277657	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277658	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277659	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277660	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277661	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277662	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277663	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277664	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277665	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277666	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277667	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277668	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277669	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277670	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278004	Soil		3.7	47.5	21.4	146	0.4	38.9	11.3	405	4.01	29.7	5.4	1.7	45	0.6	2.1	0.3	69	0.54	0.133	7
1278005	Soil		2.0	30.4	13.7	119	0.6	32.9	8.8	258	2.62	25.8	5.5	0.8	59	0.3	1.5	0.2	34	1.01	0.133	8
1278006	Soil		2.2	30.0	15.4	88	0.4	20.9	7.1	266	3.29	17.8	3.1	0.2	15	0.1	1.4	0.3	37	0.06	0.132	6
1278007	Soil		3.3	61.2	20.6	163	0.4	36.7	10.4	470	3.64	26.8	7.1	1.3	76	0.2	1.6	0.3	60	0.16	0.166	9
1278008	Soil		2.4	51.2	18.5	109	0.2	31.6	14.0	478	3.75	13.6	3.2	1.8	45	0.1	1.2	0.3	47	0.07	0.127	6
1278009	Soil		2.5	119.1	24.5	316	1.4	95.9	29.9	1027	4.50	15.8	9.7	4.2	166	0.4	1.5	0.3	36	0.24	0.099	6
1278010	Soil		2.5	48.9	23.3	140	0.5	30.8	12.7	631	3.44	13.3	2.4	1.5	194	0.2	1.1	0.3	45	0.39	0.095	6
1278011	Soil		2.5	41.8	22.6	104	0.2	28.7	7.3	216	3.37	16.5	5.0	2.1	32	0.2	1.3	0.3	39	0.03	0.084	6
1278012	Soil		2.3	44.8	17.9	130	0.2	38.0	10.3	369	3.57	16.0	4.5	3.1	54	0.5	1.3	0.3	28	0.18	0.112	8
1278013	Soil		2.8	78.4	22.3	192	1.1	76.0	20.7	921	4.00	14.8	8.3	2.0	68	0.3	1.1	0.3	24	0.12	0.087	3
1278014	Soil		3.8	74.7	30.4	113	1.0	32.2	6.2	243	4.43	14.1	24.1	1.6	80	0.1	0.9	0.5	34	0.04	0.119	3
1278015	Soil		3.1	46.9	21.5	126	0.4	40.9	8.3	360	3.69	13.4	4.5	1.9	171	0.2	0.8	0.3	39	0.37	0.094	4
1278016	Soil		1.7	20.2	23.3	80	<0.1	26.2	9.2	382	3.21	14.3	1.6	1.6	40	0.1	0.5	0.3	29	0.08	0.083	3
1278017	Soil		2.5	23.8	22.2	105	0.2	33.8	9.7	404	3.58	14.0	1.0	2.4	55	0.2	0.9	0.3	38	0.12	0.089	4
1278018	Soil		3.0	27.6	22.7	127	0.1	37.7	12.0	492	4.34	16.3	1.4	2.6	33	0.2	1.3	0.3	42	0.08	0.124	5
1279501	Soil		103.8	124.6	18.4	1034	0.6	238.3	9.7	374	3.20	38.6	3.8	1.3	113	9.0	17.9	0.2	216	4.83	0.087	5
1279502	Soil		86.8	72.1	22.7	1430	0.7	224.7	15.6	563	5.21	48.8	1.6	0.4	40	10.6	17.5	0.2	571	0.48	0.203	11
1279503	Soil		145.3	114.4	33.2	1709	0.3	329.2	33.8	609	7.70	77.4	1.0	0.7	37	7.0	19.3	0.2	796	0.47	0.185	17
1279504	Soil		129.5	100.4	25.2	1497	0.2	286.8	24.0	642	7.62	53.5	1.2	0.7	13	3.4	21.5	0.3	687	0.04	0.193	10
1279505	Soil		28.9	108.6	67.1	423	2.2	334.7	60.3	1232	12.80	41.4	3.0	1.5	118	2.5	15.4	0.2	238	1.25	0.319	12
1279506	Soil		35.6	94.4	22.2	618	0.5	275.8	37.1	824	10.81	172.6	3.4	1.5	89	2.2	26.2	0.2	262	0.95	0.377	15
1279507	Soil		69.0	116.0	27.5	1189	0.6	236.7	32.9	542	5.33	94.2	0.5	0.7	61	8.4	17.6	0.2	351	0.52	0.325	20
1279508	Soil		29.5	147.5	29.4	170	1.1	502.8	93.9	1926	11.08	37.2	0.6	2.4	381	0.5	5.0	0.1	281	4.20	0.172	6
1279509	Soil		19.3	176.1	30.0	5051	0.9	1010	188.2	2405	10.96	25.9	1.2	3.4	174	11.5	7.4	0.1	225	2.02	0.221	15
1279510	Soil		72.4	65.6	44.2	175	0.8	18.7	6.2	164	2.96	39.5	2.9	0.1	221	1.0	14.2	0.4	259	0.07	0.212	9
1279511	Soil		11.5	99.4	25.7	1200	0.5	96.4	45.2	1508	6.47	18.6	3.0	1.5	32	11.5	6.9	0.5	105	0.08	0.136	8
1279512	Soil		10.2	134.5	23.1	1117	1.1	106.2	27.9	872	5.28	21.4	5.7	1.5	34	8.1	5.2	0.5	73	0.23	0.134	8
1279513	Soil		38.1	57.6	20.8	1018	1.1	126.4	7.3	198	2.03	25.4	1.7	0.5	128	14.3	11.0	0.2	200	2.82	0.147	3
1279514	Soil		80.6	80.7	36.4	1021	0.6	155.3	13.7	290	3.18	36.2	2.3	0.3	101	9.1	17.5	0.3	373	0.11	0.162	4
1279515	Soil		27.6	63.5	28.3	516	0.3	72.2	11.6	444	3.06	22.3	2.0	0.2	42	1.5	8.2	0.3	137	0.02	0.157	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1278004	Soil	28	0.29	537	0.003	3	1.25	0.005	0.12	0.1	0.22	2.5	0.2	0.10	4	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278005	Soil	24	0.16	534	0.005	5	0.98	0.008	0.09	0.2	0.22	2.2	0.1	0.13	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278006	Soil	22	0.10	973	0.004	2	0.96	0.009	0.06	0.2	0.09	0.5	0.1	0.10	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278007	Soil	36	0.27	877	0.005	5	1.71	0.007	0.18	0.2	0.12	3.0	0.3	0.09	5	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278008	Soil	36	0.23	318	0.007	6	1.21	0.004	0.10	<0.1	0.11	2.3	0.1	0.06	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278009	Soil	38	0.57	965	0.002	3	1.80	0.006	0.11	<0.1	0.19	5.8	0.2	0.07	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278010	Soil	31	0.30	384	0.004	4	1.37	0.008	0.09	<0.1	0.05	2.2	0.2	<0.05	5	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278011	Soil	24	0.29	288	0.003	3	1.15	0.007	0.08	<0.1	0.07	2.5	0.1	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278012	Soil	21	0.36	1221	0.005	2	1.00	0.006	0.07	0.2	0.09	3.3	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278013	Soil	24	0.20	1779	0.002	4	1.16	0.015	0.09	<0.1	0.24	5.1	0.2	0.14	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278014	Soil	36	0.15	1066	0.002	4	1.38	0.012	0.09	<0.1	0.29	3.5	0.2	0.12	4	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278015	Soil	29	0.49	956	0.003	3	1.50	0.011	0.10	<0.1	0.13	4.2	0.2	0.13	5	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278016	Soil	23	0.39	220	0.003	1	1.20	0.010	0.09	<0.1	0.04	2.6	<0.1	0.06	5	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278017	Soil	28	0.49	338	0.002	1	1.47	0.009	0.12	<0.1	0.05	2.7	0.1	0.12	5	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278018	Soil	29	0.49	205	0.002	<1	1.42	0.005	0.08	<0.1	0.05	3.0	0.1	0.05	4	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279501	Soil	21	1.92	153	0.002	2	0.24	0.004	0.04	0.1	0.43	3.4	1.5	<0.05	<1	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279502	Soil	63	0.14	350	0.004	2	0.91	0.007	0.05	0.1	0.22	3.0	0.9	<0.05	3	9.2	<0.2	N.A.	N.A.	N.A.	N.A.
1279503	Soil	67	0.12	373	0.004	<1	0.84	0.004	0.05	0.2	0.13	4.1	0.9	<0.05	3	11.7	0.3	N.A.	N.A.	N.A.	N.A.
1279504	Soil	92	0.06	231	0.006	<1	0.94	0.006	0.03	0.2	0.10	3.4	0.8	<0.05	3	9.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279505	Soil	133	0.30	567	0.003	2	0.58	0.007	0.04	0.2	0.56	16.7	0.8	0.09	2	5.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279506	Soil	158	0.16	444	0.003	<1	0.91	0.004	0.03	0.1	0.13	15.3	0.5	<0.05	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279507	Soil	75	0.13	249	0.003	<1	0.93	0.008	0.04	0.2	0.35	4.9	1.0	<0.05	3	7.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279508	Soil	220	2.05	566	0.003	<1	0.59	0.009	0.03	<0.1	0.25	24.7	1.3	<0.05	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279509	Soil	245	0.25	672	0.002	1	0.66	0.010	0.04	<0.1	0.28	35.4	0.5	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279510	Soil	24	0.12	219	0.004	<1	0.97	0.003	0.06	0.1	0.29	0.4	1.1	0.08	4	12.7	0.3	N.A.	N.A.	N.A.	N.A.
1279511	Soil	39	0.23	232	0.006	1	1.43	0.003	0.05	0.1	0.07	6.4	0.3	<0.05	4	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279512	Soil	34	0.17	249	0.004	<1	1.31	0.003	0.05	<0.1	0.12	5.6	0.2	<0.05	4	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279513	Soil	20	1.12	593	0.003	3	0.45	0.015	0.03	<0.1	0.43	1.8	0.4	0.08	<1	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1279514	Soil	31	0.04	616	0.002	<1	0.53	0.003	0.07	0.1	0.20	1.1	1.1	0.07	2	8.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279515	Soil	23	0.06	117	0.002	<1	0.55	0.005	0.04	<0.1	0.06	0.6	0.4	<0.05	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1278004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278017	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279501	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279502	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279503	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279504	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279505	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279506	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279507	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279508	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279509	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279510	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279511	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279512	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279513	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279514	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279515	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278017	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279501	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279502	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279503	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279504	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279505	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279506	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279507	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279508	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279509	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279510	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279511	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279512	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279513	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279514	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279515	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279516	Soil	20.7	24.3	14.6	247	0.3	40.0	3.7	87	1.39	11.2	<0.5	<0.1	28	1.1	4.8	0.2	118	0.02	0.076	3
1279517	Soil	41.4	89.1	27.3	808	0.5	113.8	16.0	393	3.48	28.2	2.2	0.4	71	5.7	10.6	0.3	214	0.10	0.134	5
1279518	Soil	26.1	46.0	15.9	358	0.5	56.0	7.0	195	1.83	15.3	1.6	<0.1	39	2.3	6.3	0.2	139	0.04	0.095	3
1279519	Soil	21.5	78.0	22.7	513	0.5	82.4	12.8	253	3.92	20.6	2.6	0.1	29	1.9	6.1	0.4	109	0.02	0.153	4
1279520	Soil	13.6	148.1	38.2	459	0.8	114.0	16.6	373	4.47	68.2	4.2	3.5	97	4.4	20.3	0.3	132	0.23	0.201	12
1279521	Soil	45.1	142.7	47.2	1344	1.0	258.4	41.5	882	8.64	80.4	5.8	1.5	146	13.1	54.8	0.2	206	0.83	0.345	10
1279522	Soil	11.8	49.3	25.7	1178	0.7	258.7	10.1	193	8.03	21.9	5.0	0.8	104	7.8	87.6	0.2	61	0.60	0.190	8
1279523	Soil	60.6	85.0	31.2	1294	1.2	229.4	16.8	394	3.62	45.7	1.6	0.9	154	11.0	19.4	0.2	233	2.90	0.183	5
1279524	Soil	8.1	53.6	34.3	246	0.9	55.3	11.7	229	2.91	57.2	4.2	0.4	54	1.0	31.1	0.2	57	0.20	0.179	12
1279525	Soil	6.4	38.3	15.9	197	0.2	52.1	14.6	406	2.76	106.8	1.2	0.2	31	0.7	25.9	0.2	44	0.12	0.160	5
1279526	Soil	3.2	61.2	14.5	239	0.1	61.0	22.2	528	5.05	144.2	2.6	0.8	26	0.9	36.9	<0.1	45	0.18	0.107	7
1279527	Soil	5.3	47.3	18.7	157	0.1	60.1	22.7	655	8.94	112.5	<0.5	1.1	18	0.5	25.5	0.1	85	0.05	0.171	9
1279528	Soil	15.4	72.4	46.0	292	0.6	95.4	12.7	175	3.69	74.1	3.6	0.5	77	0.8	45.4	0.3	94	0.07	0.202	8
1279529	Soil	7.7	20.8	20.9	102	0.2	27.2	4.8	63	1.52	24.2	<0.5	<0.1	19	0.1	15.7	0.2	49	<0.01	0.077	7
1279530	Soil	10.5	47.7	43.9	213	0.4	55.5	8.4	128	2.94	52.5	4.0	0.2	64	0.6	29.1	0.3	73	0.08	0.203	11
1279531	Soil	6.4	54.9	19.2	244	1.3	70.6	6.9	217	1.99	28.9	4.2	0.2	74	1.2	20.0	0.2	44	0.50	0.129	7
1279532	Soil	10.3	121.3	265.4	774	2.7	111.8	19.0	633	5.44	425.1	38.4	2.1	98	3.9	264.8	0.3	75	0.36	0.215	16
1279533	Soil	8.8	34.5	79.4	269	0.3	50.3	9.0	182	2.60	104.0	3.5	0.3	31	0.6	58.9	0.3	59	0.05	0.119	9
1279534	Soil	7.8	20.5	18.0	139	0.1	30.4	4.5	66	1.56	18.9	<0.5	0.2	29	0.6	9.8	0.2	58	0.05	0.079	12
1279535	Soil	4.4	15.6	13.5	87	0.3	17.3	2.7	60	0.92	10.2	1.3	0.1	45	0.7	6.7	0.1	34	0.34	0.074	6
1279536	Soil	10.4	46.5	12.0	200	0.4	57.8	5.9	108	1.84	16.1	1.2	0.1	29	1.6	11.1	0.1	41	0.24	0.101	8
1279537	Soil	8.1	24.4	7.8	145	0.7	28.6	3.3	119	1.19	10.6	<0.5	0.1	34	1.2	5.5	0.1	48	0.38	0.089	6
1279538	Soil	29.0	34.5	16.0	380	0.2	78.9	9.0	169	2.39	26.6	0.8	0.3	44	1.2	11.5	0.2	128	0.33	0.085	11
1279539	Soil	49.1	41.9	9.9	324	0.6	109.0	7.3	210	1.68	18.4	1.8	0.8	59	2.8	12.7	0.2	67	1.79	0.102	9
1279540	Soil	23.9	52.0	13.5	353	0.9	91.5	7.2	206	1.71	22.5	1.9	0.9	72	4.3	9.5	0.2	89	1.45	0.110	7
1279541	Soil	16.8	29.2	18.0	163	0.3	78.8	8.1	164	2.57	32.8	1.5	0.3	19	1.4	7.4	0.2	92	0.05	0.100	7
1279542	Soil	15.5	33.3	16.9	85	0.2	41.3	4.4	49	1.69	18.6	<0.5	0.3	14	1.4	3.6	0.2	53	0.02	0.146	8
1279543	Soil	14.7	60.6	31.5	343	1.1	69.4	8.1	145	3.93	110.4	2.5	3.3	27	1.3	7.8	0.4	79	0.09	0.143	10
1279544	Soil	20.0	11.4	20.9	111	1.2	25.3	2.1	27	0.85	10.1	<0.5	0.1	24	0.3	5.1	0.1	55	0.02	0.028	6
1279545	Soil	13.4	23.8	18.0	184	0.8	47.7	3.9	52	1.49	19.5	1.5	0.2	39	2.3	5.5	0.2	53	0.06	0.095	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1279516	Soil	15	0.02	109	0.001	<1	0.31	0.010	0.03	<0.1	0.08	0.2	0.3	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279517	Soil	27	0.07	273	0.002	<1	0.59	0.003	0.05	<0.1	0.15	1.7	0.6	<0.05	2	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279518	Soil	16	0.03	146	0.003	<1	0.46	0.012	0.04	<0.1	0.19	0.3	0.4	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279519	Soil	25	0.03	85	0.002	<1	0.42	0.003	0.03	<0.1	0.04	0.6	0.3	<0.05	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279520	Soil	44	0.27	501	0.015	2	1.08	0.005	0.09	0.1	0.22	6.8	0.4	<0.05	5	3.4	0.2	N.A.	N.A.	N.A.	N.A.
1279521	Soil	106	0.22	572	0.005	2	0.86	0.005	0.06	<0.1	0.49	11.0	0.7	0.06	3	8.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279522	Soil	20	0.18	481	0.010	2	0.94	0.009	0.05	0.1	0.21	2.8	0.5	0.08	3	5.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279523	Soil	48	0.99	411	0.002	2	0.46	0.005	0.04	0.1	0.69	5.3	0.8	0.08	1	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279524	Soil	21	0.16	203	0.004	2	0.69	0.004	0.06	<0.1	0.10	1.2	0.2	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1279525	Soil	18	0.05	345	0.002	<1	0.73	0.009	0.06	<0.1	0.04	1.1	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1279526	Soil	35	0.10	631	0.001	1	1.19	0.007	0.06	<0.1	0.12	12.4	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279527	Soil	45	0.09	337	0.003	<1	1.15	0.002	0.06	<0.1	0.02	5.2	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279528	Soil	22	0.04	272	0.003	<1	0.57	0.004	0.06	<0.1	0.03	1.2	0.3	<0.05	2	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1279529	Soil	12	0.02	119	<0.001	<1	0.45	0.008	0.05	<0.1	0.02	0.1	0.1	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1279530	Soil	20	0.06	195	0.002	<1	0.55	0.002	0.06	<0.1	0.05	0.2	0.2	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279531	Soil	14	0.14	665	0.002	1	0.63	0.017	0.05	<0.1	0.30	0.8	0.2	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1279532	Soil	30	0.11	931	0.002	1	0.59	0.002	0.09	<0.1	0.65	9.9	0.3	<0.05	1	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1279533	Soil	16	0.03	226	0.002	<1	0.43	0.004	0.07	<0.1	0.03	0.7	0.2	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1279534	Soil	14	0.05	317	0.002	<1	0.57	0.002	0.05	0.1	0.01	0.3	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279535	Soil	12	0.08	326	0.004	<1	0.50	0.017	0.04	<0.1	0.02	0.3	0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1279536	Soil	16	0.08	371	0.002	<1	0.47	0.010	0.04	<0.1	0.08	0.4	0.2	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279537	Soil	14	0.09	541	0.002	1	0.56	0.016	0.05	<0.1	0.07	0.3	0.2	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279538	Soil	25	0.19	371	0.004	<1	0.99	0.004	0.06	0.2	0.07	0.8	0.4	<0.05	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1279539	Soil	16	0.62	378	0.005	1	0.48	0.011	0.06	0.2	0.21	2.3	0.6	<0.05	1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279540	Soil	16	0.16	362	0.005	3	0.62	0.010	0.03	0.2	0.39	1.8	0.3	0.05	1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279541	Soil	39	0.04	231	0.005	2	0.66	0.005	0.03	0.2	0.04	0.6	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279542	Soil	24	0.02	186	0.006	2	0.61	0.003	0.02	0.1	0.03	0.4	0.3	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1279543	Soil	22	0.16	285	0.006	1	1.04	0.004	0.06	0.3	0.10	2.1	0.3	<0.05	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279544	Soil	6	<0.01	83	0.004	2	0.14	0.005	0.03	0.1	0.04	0.3	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279545	Soil	13	0.04	281	0.003	2	0.54	0.009	0.05	<0.1	0.12	0.6	0.3	0.06	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1279516	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279517	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279518	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279519	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279520	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279521	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279522	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279523	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279524	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279525	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279526	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279527	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279528	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279529	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279530	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279531	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279532	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279533	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279534	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279535	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279536	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279537	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279538	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279539	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279540	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279541	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279542	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279543	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279544	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279545	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279516	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279517	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279518	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279519	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279520	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279521	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279522	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279523	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279524	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279525	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279526	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279527	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279528	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279529	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279530	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279531	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279532	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279533	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279534	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279535	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279536	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279537	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279538	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279539	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279540	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279541	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279542	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279543	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279544	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279545	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279546	Soil	59.6	70.5	23.3	1874	1.2	354.4	13.2	284	4.38	36.5	4.2	1.5	95	4.5	14.4	0.2	111	0.89	0.162	7
1279547	Soil	32.4	44.5	26.8	701	1.1	149.6	7.5	239	2.36	38.3	2.9	0.6	121	7.0	12.1	0.2	83	0.99	0.151	5
1279548	Soil	18.0	32.6	24.0	861	0.5	144.6	9.6	448	2.17	33.9	<0.5	1.6	93	4.6	7.0	0.3	72	0.62	0.150	8
1279549	Soil	3.0	27.2	15.3	833	0.5	150.0	5.8	272	1.12	13.0	2.0	0.6	66	4.7	3.0	0.1	34	1.10	0.106	5
1279550	Soil	3.6	16.7	10.7	95	0.1	21.0	3.9	92	2.01	15.5	<0.5	0.5	18	0.4	1.5	0.2	22	0.16	0.056	3
1279551	Soil	2.3	50.6	17.3	180	<0.1	49.8	26.0	516	4.07	21.6	0.8	0.6	6	0.3	2.0	0.5	17	0.01	0.075	3
1279552	Soil	3.8	42.9	29.2	219	0.1	44.5	12.5	172	3.75	18.1	1.2	1.2	15	0.3	1.6	0.4	21	0.02	0.063	3
1279553	Soil	10.1	67.0	40.3	251	0.4	50.2	10.7	181	4.39	29.6	2.0	1.7	69	0.7	3.2	0.5	80	0.02	0.112	3
1279554	Soil	8.2	9.6	9.6	36	0.4	6.3	0.8	12	0.53	7.6	<0.5	0.1	2	0.1	2.3	0.2	56	<0.01	0.038	23
1279555	Soil	29.5	15.3	15.3	121	0.4	12.4	1.6	31	1.36	29.9	0.6	0.2	9	0.1	11.1	0.2	117	<0.01	0.059	23
1279556	Soil	7.4	11.4	15.3	32	0.2	6.3	1.7	49	1.12	10.8	1.7	<0.1	15	<0.1	2.5	0.3	47	0.03	0.059	13
1279557	Soil	45.6	116.0	28.3	1524	0.7	288.6	26.4	3168	16.68	52.6	3.7	2.5	52	12.8	13.3	0.3	190	0.09	0.173	12
1279558	Soil	15.5	10.4	14.7	27	0.7	4.1	0.9	22	0.66	6.5	2.0	0.3	8	0.2	2.3	0.2	42	0.02	0.036	26
1279559	Soil	19.0	35.7	24.1	83	0.5	23.6	3.5	88	2.04	32.5	<0.5	<0.1	22	0.3	7.5	0.2	102	0.02	0.064	18
1279560	Soil	7.2	141.3	37.7	146	0.9	30.5	6.9	192	5.30	105.3	16.8	1.2	77	0.4	11.7	0.5	50	0.02	0.171	7
1279561	Soil	3.3	53.7	14.5	71	1.0	12.4	3.1	61	2.06	30.5	0.6	0.2	10	0.3	3.6	0.3	29	0.02	0.079	3
1279562	Soil	16.0	61.3	54.6	645	0.8	87.0	36.8	1633	12.11	82.8	5.6	2.5	24	1.9	6.2	0.4	129	0.02	0.140	6
1279563	Soil	15.4	23.8	15.8	96	0.4	22.6	3.4	43	1.67	22.8	2.1	0.2	27	0.6	5.6	0.2	93	0.03	0.080	10
1279564	Soil	12.7	27.3	28.2	78	3.2	17.4	2.7	149	1.70	15.8	6.0	<0.1	54	0.6	3.5	0.3	177	0.08	0.231	7
1279565	Soil	5.4	6.2	5.3	29	0.1	5.1	1.3	24	0.59	6.1	<0.5	<0.1	11	<0.1	1.4	<0.1	45	0.01	0.040	13
1279566	Soil	6.8	6.3	5.4	27	0.1	7.1	1.1	17	0.45	5.1	2.6	<0.1	13	<0.1	1.3	0.2	45	0.01	0.022	16
1279567	Soil	1.5	2.3	2.8	6	0.2	2.2	0.3	6	0.15	1.5	<0.5	<0.1	8	<0.1	0.2	0.1	18	0.01	0.026	9
1279568	Soil	11.6	13.3	8.3	61	0.3	14.3	2.5	28	0.97	13.5	0.9	0.2	16	<0.1	3.1	0.2	79	0.01	0.025	13
1279569	Soil	16.7	17.1	12.6	80	0.2	22.4	2.9	34	1.04	18.7	<0.5	0.3	10	0.1	2.9	0.2	93	0.01	0.033	13
1279570	Soil	22.5	33.2	21.2	157	0.3	39.3	5.1	80	2.19	32.2	0.6	<0.1	24	0.3	6.3	0.3	135	0.02	0.074	10
1279572	Soil	10.9	43.3	15.6	149	0.9	24.7	3.5	58	1.66	26.2	1.7	<0.1	8	1.0	5.0	0.2	32	0.09	0.131	6
1279573	Soil	11.2	45.5	18.7	94	1.0	13.8	3.5	155	1.48	22.2	2.0	0.3	8	0.9	4.2	0.2	28	0.11	0.156	6
1279574	Soil	10.9	64.9	18.6	143	1.5	26.0	4.8	121	1.71	20.2	4.4	<0.1	12	1.0	4.1	0.2	34	0.21	0.193	8
1279575	Soil	15.0	252.4	28.0	188	0.3	119.2	17.1	200	5.50	32.0	5.9	0.2	13	0.3	6.0	0.4	48	0.03	0.170	7
1279576	Soil	4.0	92.0	22.1	114	0.9	52.2	8.3	87	2.08	16.9	12.0	0.5	7	0.2	2.4	0.3	15	0.02	0.057	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1279546	Soil	21	0.09	585	0.004	4	0.61	0.004	0.06	0.1	0.40	3.0	0.6	0.08	2	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1279547	Soil	17	0.13	589	0.003	3	0.51	0.005	0.06	0.1	0.25	1.5	0.5	0.08	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1279548	Soil	17	0.11	436	0.004	3	0.58	0.004	0.07	<0.1	0.26	2.4	0.3	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1279549	Soil	10	0.10	308	0.005	4	0.52	0.014	0.05	<0.1	0.25	1.3	0.3	0.07	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279550	Soil	8	0.06	199	0.003	2	0.57	0.012	0.03	<0.1	0.05	1.0	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1279551	Soil	6	0.05	213	<0.001	1	0.41	0.001	0.04	<0.1	0.05	3.5	0.2	<0.05	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279552	Soil	9	0.13	134	<0.001	<1	0.73	0.003	0.03	<0.1	0.05	3.2	0.3	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279553	Soil	16	0.05	233	<0.001	1	0.67	0.003	0.07	<0.1	0.06	6.6	0.6	0.09	2	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1279554	Soil	6	<0.01	54	0.003	2	0.24	0.008	0.03	<0.1	0.04	0.2	0.3	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279555	Soil	7	<0.01	119	0.003	3	0.34	0.004	0.05	<0.1	0.02	0.2	0.4	0.05	2	7.0	0.3	N.A.	N.A.	N.A.	N.A.
1279556	Soil	7	0.06	133	0.007	<1	0.58	0.008	0.04	0.1	0.07	0.2	0.4	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1279557	Soil	26	0.09	479	0.005	<1	1.99	0.005	0.04	0.1	0.34	6.8	1.0	<0.05	3	9.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279558	Soil	6	0.01	103	0.003	<1	0.33	0.005	0.04	<0.1	0.03	0.2	0.3	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279559	Soil	10	0.02	137	0.004	<1	0.39	0.006	0.04	0.2	0.03	0.2	0.2	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279560	Soil	13	0.04	221	0.004	<1	0.76	0.005	0.09	<0.1	0.04	5.1	0.4	0.13	2	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279561	Soil	6	0.01	59	0.002	2	0.35	0.007	0.05	<0.1	0.04	0.6	0.1	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279562	Soil	16	0.04	465	0.003	<1	1.15	0.003	0.05	<0.1	0.12	2.6	0.4	<0.05	3	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279563	Soil	11	0.03	296	0.003	<1	0.36	0.006	0.06	0.1	0.04	0.3	0.5	0.10	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279564	Soil	26	0.05	1233	0.001	2	1.25	0.009	0.08	0.1	0.81	0.2	0.9	0.14	4	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279565	Soil	4	0.01	147	0.002	2	0.28	0.007	0.03	<0.1	0.02	<0.1	0.2	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279566	Soil	4	0.01	125	0.004	<1	0.24	0.004	0.02	<0.1	0.01	0.1	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279567	Soil	3	<0.01	81	0.002	<1	0.21	0.008	0.02	<0.1	0.02	<0.1	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279568	Soil	5	<0.01	534	0.004	<1	0.23	0.003	0.03	0.2	0.01	0.2	0.1	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279569	Soil	8	0.02	79	0.005	1	0.52	0.004	0.03	0.1	<0.01	0.4	0.2	<0.05	5	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279570	Soil	13	0.02	193	0.002	<1	0.44	0.004	0.05	<0.1	0.03	0.2	0.5	<0.05	4	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279572	Soil	6	0.02	284	<0.001	1	0.35	0.006	0.04	<0.1	0.12	0.1	0.2	<0.05	1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279573	Soil	4	0.01	366	0.002	1	0.43	0.005	0.03	<0.1	0.18	0.6	0.2	<0.05	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1279574	Soil	6	0.02	474	0.001	2	0.31	0.004	0.05	<0.1	0.21	0.2	0.2	<0.05	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279575	Soil	10	0.02	104	0.002	2	0.26	0.003	0.07	<0.1	0.03	0.9	0.2	0.06	2	6.8	0.3	N.A.	N.A.	N.A.	N.A.
1279576	Soil	6	<0.01	69	<0.001	2	0.20	0.001	0.06	<0.1	0.19	1.2	0.1	<0.05	<1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1279546	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279547	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279548	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279549	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279550	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279551	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279552	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279553	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279554	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279555	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279556	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279557	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279558	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279559	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279560	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279561	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279562	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279563	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279564	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279565	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279566	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279567	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279568	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279569	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279570	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279572	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279573	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279574	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279575	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279576	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279546	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279547	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279548	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279549	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279550	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279551	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279552	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279553	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279554	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279555	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279556	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279557	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279558	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279559	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279560	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279561	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279562	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279563	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279564	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279565	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279566	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279567	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279568	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279569	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279570	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279572	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279573	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279574	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279575	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279576	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279577	Soil	22.4	314.2	27.8	650	1.2	387.4	70.9	1235	13.90	55.1	7.8	3.2	72	1.3	3.3	0.3	57	0.50	0.481	35
1279578	Soil	29.8	233.6	59.7	391	2.3	286.4	15.9	836	18.29	43.7	2.2	3.8	26	14.6	10.4	0.2	129	0.34	0.558	18
1279579	Soil	2.7	18.6	6.9	41	0.4	17.3	2.0	45	0.87	4.0	1.0	<0.1	13	0.7	0.7	0.1	18	0.10	0.118	5
1279580	Soil	39.0	140.0	24.9	894	2.8	240.6	34.0	485	7.11	35.9	1.8	2.8	134	17.8	7.1	0.3	153	0.55	0.390	39
1279581	Soil	13.4	48.8	25.3	101	0.8	36.8	4.1	48	1.54	9.6	1.7	<0.1	59	0.3	4.1	0.2	117	0.04	0.159	12
1279582	Soil	18.6	73.1	30.1	353	0.6	130.4	19.0	347	4.21	27.4	3.2	0.5	33	1.0	5.5	0.4	54	0.28	0.230	11
1279583	Soil	23.0	38.4	33.7	167	0.3	81.9	14.8	159	3.24	34.4	0.7	1.0	10	0.3	6.2	0.3	26	0.07	0.067	6
1279584	Soil	5.1	52.0	22.3	192	0.2	91.3	32.3	667	6.24	25.5	2.4	1.9	21	0.5	3.7	0.3	39	0.15	0.057	17
1279585	Soil	4.4	127.9	35.4	352	3.9	92.9	19.4	562	6.09	88.2	5.1	4.5	102	1.0	19.5	0.4	28	0.39	0.351	13
1279586	Soil	11.9	75.2	26.0	200	0.9	105.1	12.4	347	3.31	19.0	1.1	3.4	100	1.3	7.7	0.2	89	4.14	0.084	5
1279587	Soil	22.0	73.5	24.6	510	1.8	109.9	11.1	212	2.71	13.9	0.9	2.3	85	3.7	9.4	0.2	116	2.37	0.113	3
1279588	Soil	111.3	59.5	21.9	583	0.5	205.5	11.9	260	3.35	28.4	<0.5	3.2	66	3.8	13.8	0.2	212	2.47	0.072	3
1279589	Soil	104.2	61.5	17.0	339	0.3	206.3	11.1	291	3.23	23.2	1.3	3.8	68	2.1	7.5	0.1	114	3.36	0.069	3
1279590	Soil	85.3	61.1	10.7	405	0.3	177.8	8.8	233	2.43	22.5	0.9	1.4	46	2.9	6.3	0.1	84	3.19	0.060	7
1279591	Soil	89.7	76.7	11.8	712	0.6	173.8	6.5	195	1.68	33.2	0.8	2.0	74	7.5	13.4	0.1	187	5.06	0.061	9
1279592	Soil	60.6	64.6	9.2	525	0.6	128.8	5.4	172	1.30	28.5	1.1	0.5	57	6.2	13.1	0.1	155	2.62	0.065	8
1279593	Soil	75.3	82.0	10.2	520	0.7	171.4	7.0	168	1.51	32.8	<0.5	2.6	249	5.5	17.3	0.1	194	12.89	0.080	7
1279594	Soil	114.2	105.2	15.3	699	1.4	259.0	6.7	258	1.87	42.7	2.5	1.4	149	8.0	21.9	0.2	395	5.29	0.095	9
1279595	Soil	250.2	110.7	50.1	1263	1.5	702.6	16.8	2040	8.89	49.9	1.5	2.8	130	9.7	23.5	0.2	545	1.16	0.228	4
1279596	Soil	166.3	102.3	53.7	807	1.7	372.9	20.6	230	4.45	67.0	1.3	2.6	166	4.9	22.1	0.2	393	0.87	0.193	8
1279597	Soil	120.3	109.1	31.9	1214	1.1	292.5	17.4	414	3.94	46.5	<0.5	2.0	278	9.3	18.0	0.1	533	9.35	0.193	5
1279598	Soil	100.1	108.9	32.3	1157	1.5	270.6	17.4	537	4.62	43.2	<0.5	1.2	210	9.8	16.2	0.1	465	7.46	0.166	4
1279599	Soil	84.6	135.9	39.4	1335	2.1	357.4	24.6	600	5.37	58.5	1.8	2.4	426	13.2	17.8	0.2	609	3.65	0.617	13
1279600	Soil	109.5	72.4	21.1	864	1.2	292.1	10.0	219	3.07	37.2	0.5	0.5	65	5.6	9.9	0.1	296	0.68	0.150	5
1279601	Soil	2.9	49.9	19.2	206	1.4	62.9	9.5	165	2.82	24.2	4.0	2.1	93	0.9	1.3	0.2	27	1.20	0.106	5
1279602	Soil	2.6	40.9	20.5	169	1.1	56.9	10.3	249	2.86	24.2	7.5	1.9	88	0.8	1.1	0.2	24	0.88	0.116	5
1279603	Soil	2.7	49.4	27.1	190	1.1	56.2	10.1	214	3.12	62.9	8.9	2.1	82	0.9	1.8	0.2	21	0.40	0.091	3
1279604	Soil	2.9	57.8	43.9	155	1.3	40.5	6.3	188	2.86	122.8	15.2	2.1	101	0.8	2.7	0.2	20	0.19	0.073	3
1279605	Soil	3.3	39.0	32.6	152	1.9	38.1	7.9	139	3.35	74.4	3.0	3.1	170	1.1	2.2	0.3	15	0.24	0.091	2
1279606	Soil	7.8	81.2	18.1	360	3.2	117.6	13.8	143	3.21	23.3	5.7	2.5	168	1.9	2.5	0.3	42	2.26	0.159	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1279577	Soil	41	0.07	265	0.005	4	0.57	0.005	0.10	0.1	0.28	13.9	0.4	<0.05	1	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1279578	Soil	45	0.06	974	0.006	1	0.43	<0.001	0.05	<0.1	0.46	8.9	0.6	<0.05	<1	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1279579	Soil	6	0.03	116	0.001	<1	0.37	0.015	0.04	<0.1	0.06	0.2	0.1	0.09	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279580	Soil	37	0.06	377	0.006	4	0.58	0.003	0.10	0.2	0.39	6.5	0.8	0.08	1	8.3	<0.2	N.A.	N.A.	N.A.	N.A.
1279581	Soil	11	0.02	172	0.002	1	0.42	0.012	0.07	0.2	0.05	0.2	0.2	0.08	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1279582	Soil	12	0.04	503	0.002	5	0.45	0.002	0.12	<0.1	0.14	1.4	0.3	0.07	1	4.7	0.2	N.A.	N.A.	N.A.	N.A.
1279583	Soil	7	0.03	351	0.001	3	0.35	0.002	0.12	<0.1	0.04	2.2	0.4	<0.05	1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1279584	Soil	18	0.23	586	0.009	1	1.10	0.003	0.05	0.2	0.02	4.2	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279585	Soil	12	0.05	4284	0.005	3	1.53	0.002	0.09	<0.1	0.52	6.5	0.3	0.06	1	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1279586	Soil	20	2.03	492	0.001	4	0.23	0.004	0.07	<0.1	0.12	5.7	0.1	<0.05	<1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1279587	Soil	21	1.13	443	0.001	4	0.28	0.004	0.06	<0.1	0.22	5.0	0.2	<0.05	<1	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279588	Soil	15	1.17	347	0.002	3	0.29	0.005	0.05	<0.1	0.29	4.8	0.6	<0.05	<1	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279589	Soil	13	1.34	185	0.003	3	0.28	0.005	0.04	<0.1	0.31	4.5	0.8	<0.05	<1	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279590	Soil	17	1.59	171	0.003	4	0.36	0.007	0.05	0.1	0.12	3.5	0.7	<0.05	<1	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279591	Soil	16	2.65	161	0.004	4	0.37	0.011	0.06	0.2	0.18	3.1	0.8	<0.05	<1	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279592	Soil	14	1.02	160	0.005	4	0.45	0.017	0.04	0.1	0.17	2.0	0.7	0.07	<1	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279593	Soil	16	3.63	135	0.003	4	0.19	0.006	0.05	0.1	0.45	2.7	1.2	<0.05	<1	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1279594	Soil	23	1.27	248	0.003	5	0.31	0.004	0.08	0.4	0.31	3.2	1.2	<0.05	<1	12.3	0.2	N.A.	N.A.	N.A.	N.A.
1279595	Soil	40	0.13	311	0.003	2	0.42	0.003	0.07	0.2	0.62	7.4	4.1	<0.05	1	9.3	0.3	N.A.	N.A.	N.A.	N.A.
1279596	Soil	40	0.09	633	0.002	3	0.48	0.003	0.08	0.1	0.57	7.3	2.1	0.11	2	7.5	0.3	N.A.	N.A.	N.A.	N.A.
1279597	Soil	49	1.88	401	0.003	5	0.41	0.006	0.07	0.1	0.45	5.8	1.0	<0.05	1	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279598	Soil	63	2.61	395	0.002	4	0.40	0.007	0.06	0.1	0.60	6.3	0.7	<0.05	1	6.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279599	Soil	100	1.04	722	0.007	8	0.81	0.005	0.13	0.1	0.67	8.1	1.1	<0.05	2	10.5	0.2	N.A.	N.A.	N.A.	N.A.
1279600	Soil	39	0.08	372	0.003	<1	0.55	0.009	0.05	0.2	0.38	3.9	1.0	<0.05	2	7.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279601	Soil	18	0.12	814	<0.001	5	0.73	0.006	0.11	<0.1	0.25	3.5	0.2	0.15	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279602	Soil	18	0.13	773	<0.001	3	0.63	0.005	0.12	<0.1	0.27	3.8	0.2	0.16	1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279603	Soil	16	0.16	597	<0.001	4	0.60	0.005	0.14	<0.1	0.26	4.0	0.2	0.23	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279604	Soil	17	0.22	324	<0.001	3	0.54	0.008	0.17	<0.1	0.28	3.4	0.3	0.30	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279605	Soil	13	0.05	314	<0.001	4	0.38	0.007	0.25	<0.1	0.42	3.2	0.5	0.48	<1	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279606	Soil	24	0.09	707	<0.001	5	0.88	0.005	0.14	<0.1	0.20	3.7	0.3	0.20	2	7.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1279577	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279578	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279579	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279580	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279581	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279582	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279583	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279584	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279585	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279586	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279587	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279588	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279589	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279590	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279591	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279592	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279593	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279594	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279595	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279596	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279597	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279598	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279599	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279600	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279601	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279602	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279603	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279604	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279605	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279606	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279577	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279578	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279579	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279580	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279581	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279582	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279583	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279584	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279585	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279586	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279587	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279588	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279589	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279590	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279591	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279592	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279593	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279594	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279595	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279596	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279597	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279598	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279599	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279600	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279601	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279602	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279603	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279604	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279605	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279606	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279607	Soil	2.2	40.6	15.5	88	1.6	32.4	3.9	64	2.19	11.7	3.8	0.9	101	0.5	0.6	0.2	25	1.82	0.096	5
1279608	Soil	2.2	26.0	11.8	98	1.3	29.0	3.3	97	1.57	8.2	6.1	0.5	78	0.7	1.0	0.2	22	1.87	0.107	4
1279609	Soil	3.9	45.7	15.1	153	1.9	49.4	5.3	92	2.36	12.4	8.4	1.1	92	1.0	1.4	0.2	31	2.01	0.118	6
1279610	Soil	2.9	39.9	14.6	130	1.6	43.8	5.6	100	2.24	11.6	6.9	0.7	93	0.9	1.1	0.2	30	1.60	0.131	6
1279611	Soil	1.6	38.4	11.2	136	1.1	46.4	5.9	111	2.18	9.6	7.4	0.7	58	0.9	0.8	0.2	33	1.65	0.129	8
1279612	Soil	2.2	132.5	35.4	268	2.5	118.8	28.4	221	5.99	17.0	24.8	1.9	37	0.8	2.3	0.2	35	0.54	0.117	5
1279613	Soil	3.2	86.1	37.8	361	2.7	142.4	53.6	612	6.32	27.1	6.3	2.5	26	0.9	1.6	0.3	29	0.22	0.102	4
1279614	Soil	3.4	69.9	21.5	204	1.9	81.8	15.5	240	4.40	16.0	2.9	1.4	40	0.6	1.1	0.2	46	0.27	0.096	5
1279615	Soil	2.4	23.0	10.9	92	0.6	20.0	4.9	134	2.35	11.8	<0.5	<0.1	11	0.5	1.1	0.2	47	0.04	0.089	6
1279616	Soil	2.7	23.1	7.0	75	0.3	16.8	3.9	136	1.77	10.4	<0.5	<0.1	11	0.3	1.0	0.2	42	0.01	0.085	6
1279617	Soil	3.7	45.3	18.6	79	1.7	22.0	3.9	84	2.71	21.9	10.3	1.5	31	<0.1	2.4	0.2	46	0.02	0.060	6
1279618	Soil	2.4	23.3	11.5	85	0.3	15.2	4.0	186	2.00	11.3	1.9	<0.1	11	0.3	1.1	0.2	50	0.02	0.090	7
1279619	Soil	2.7	21.8	10.0	67	0.2	15.1	3.6	123	2.03	10.3	2.8	<0.1	9	0.3	1.0	0.2	47	0.02	0.077	7
1279620	Soil	2.5	31.7	10.8	86	0.4	22.5	4.0	61	2.16	12.7	1.5	0.1	13	0.1	1.1	0.1	37	0.02	0.068	6
1279621	Soil	2.2	33.0	8.5	72	0.9	20.1	3.4	71	2.30	12.5	2.0	<0.1	10	0.4	1.3	0.1	32	0.03	0.082	4
1279622	Soil	2.9	74.4	15.9	114	1.0	44.0	7.0	151	3.13	10.4	4.5	0.4	17	0.6	1.0	0.2	40	0.03	0.091	6
1279623	Soil	2.9	86.2	14.9	65	2.7	33.1	4.6	270	2.12	9.2	11.7	1.0	22	0.2	0.9	0.2	23	0.14	0.085	4
1279624	Soil	0.8	45.7	6.9	45	1.7	21.1	3.6	184	1.02	3.3	2.1	0.2	54	0.9	0.5	<0.1	10	1.75	0.145	4
1279625	Soil	1.9	23.8	11.4	65	0.8	23.3	3.0	66	1.55	7.1	1.9	0.5	22	0.7	0.4	0.2	17	0.18	0.063	3
1279626	Soil	6.1	31.8	13.1	83	0.9	22.2	2.8	67	2.39	15.4	6.5	0.7	12	0.5	1.4	0.2	28	0.19	0.063	2
1279627	Soil	3.3	18.8	7.0	59	0.7	13.4	2.5	33	1.38	13.7	<0.5	<0.1	7	<0.1	0.7	0.1	45	<0.01	0.047	7
1279628	Soil	2.4	16.4	5.4	32	0.3	7.2	1.5	22	0.84	7.4	<0.5	<0.1	6	0.2	0.5	<0.1	32	0.02	0.042	6
1279629	Soil	3.4	17.3	14.9	101	0.2	18.2	5.9	149	2.94	11.7	<0.5	1.0	8	<0.1	0.8	0.2	49	<0.01	0.042	7
1279630	Soil	4.5	29.9	15.1	98	0.3	25.1	6.0	127	2.57	16.8	3.9	1.2	12	0.2	1.4	0.2	39	0.02	0.059	7
1279631	Soil	4.9	20.8	16.1	78	0.2	19.9	4.0	80	2.30	17.6	1.9	0.9	13	0.2	1.0	0.2	49	0.01	0.063	6
1279632	Soil	17.7	30.6	17.7	83	0.4	22.5	4.0	59	2.06	17.0	<0.5	0.8	27	0.3	3.7	0.2	78	0.03	0.066	5
1279633	Soil	11.5	27.1	14.6	81	0.3	20.1	3.7	64	2.11	17.8	3.0	0.3	24	0.3	2.5	0.2	71	0.09	0.082	5
1279634	Soil	17.3	39.0	13.8	274	0.7	42.6	4.7	84	2.43	22.3	3.2	1.2	25	2.5	4.0	0.2	162	0.10	0.078	6
1279635	Soil	55.9	46.9	8.1	2067	1.5	390.2	16.2	934	3.47	16.9	3.4	0.6	33	28.1	1.9	0.1	94	0.45	0.108	4
1279636	Soil	7.0	29.8	8.8	462	0.7	63.1	7.6	198	2.16	9.4	4.8	0.6	32	1.4	1.1	0.1	35	0.50	0.071	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1279607	Soil	16	0.14	697	<0.001	7	0.58	0.008	0.19	<0.1	0.18	2.4	0.3	0.35	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279608	Soil	13	0.09	645	<0.001	7	0.53	0.007	0.13	<0.1	0.12	1.2	0.2	0.29	1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279609	Soil	19	0.17	537	0.001	4	0.64	0.007	0.14	<0.1	0.22	2.7	0.2	0.22	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1279610	Soil	19	0.19	593	<0.001	6	0.66	0.006	0.17	<0.1	0.22	2.0	0.2	0.24	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279611	Soil	23	0.14	598	0.001	6	0.84	0.004	0.08	<0.1	0.13	2.2	0.1	0.10	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1279612	Soil	26	0.22	360	0.002	3	1.12	0.004	0.08	<0.1	0.17	5.5	0.2	<0.05	3	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279613	Soil	20	0.14	292	0.002	2	0.91	0.003	0.08	<0.1	0.25	10.2	0.2	<0.05	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279614	Soil	22	0.12	405	0.002	2	0.84	0.005	0.09	<0.1	0.29	5.8	0.2	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279615	Soil	18	0.08	242	0.003	2	0.80	0.003	0.07	0.1	0.04	0.5	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1279616	Soil	14	0.03	177	0.001	2	0.50	0.003	0.06	0.1	0.02	0.2	0.1	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279617	Soil	17	0.10	212	0.006	3	0.66	0.005	0.11	0.2	0.12	1.6	0.3	0.14	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279618	Soil	14	0.04	153	0.003	2	0.64	0.005	0.07	<0.1	0.03	0.3	0.2	<0.05	4	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279619	Soil	17	0.07	161	0.003	2	0.77	0.004	0.07	0.1	0.02	0.4	0.1	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279620	Soil	12	0.04	151	0.003	2	0.46	0.003	0.05	0.1	0.02	0.6	0.1	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279621	Soil	13	0.02	122	0.001	3	0.53	0.007	0.04	<0.1	<0.01	0.3	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279622	Soil	18	0.07	248	0.003	2	1.06	0.005	0.06	<0.1	0.09	1.3	0.2	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1279623	Soil	15	0.07	420	0.002	2	0.83	0.010	0.07	<0.1	0.41	2.9	0.2	0.07	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279624	Soil	10	0.06	310	0.002	4	0.79	0.012	0.03	<0.1	0.43	1.4	0.1	0.19	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279625	Soil	13	0.08	138	0.003	2	0.56	0.003	0.04	<0.1	0.02	1.2	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279626	Soil	16	0.03	218	0.001	4	0.48	0.004	0.06	<0.1	0.11	1.6	<0.1	<0.05	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279627	Soil	11	0.01	86	0.002	2	0.35	0.003	0.04	<0.1	0.02	0.4	<0.1	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279628	Soil	9	0.01	105	0.002	1	0.28	0.006	0.04	<0.1	<0.01	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279629	Soil	12	0.05	75	0.003	<1	0.59	0.002	0.04	<0.1	<0.01	2.5	0.2	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1279630	Soil	14	0.09	137	0.001	2	0.71	0.002	0.05	<0.1	0.01	1.6	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279631	Soil	15	0.06	117	0.002	3	0.74	0.003	0.06	<0.1	<0.01	1.3	0.1	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279632	Soil	16	0.05	241	0.001	2	0.54	0.004	0.09	0.2	0.08	1.5	1.0	0.06	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279633	Soil	15	0.06	267	0.001	3	0.59	0.004	0.08	0.2	0.07	0.9	0.5	0.07	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1279634	Soil	19	0.09	417	0.001	2	0.64	0.003	0.07	0.2	0.20	2.0	0.5	0.06	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279635	Soil	19	0.08	1357	0.002	3	0.92	0.011	0.10	<0.1	0.49	2.8	4.1	0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279636	Soil	14	0.06	494	0.001	2	0.62	0.012	0.07	<0.1	0.09	1.6	0.7	0.06	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1279607	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279608	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279609	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279610	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279611	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279612	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279613	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279614	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279615	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279616	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279617	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279618	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279619	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279620	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279621	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279622	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279623	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279624	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279625	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279626	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279627	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279628	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279629	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279630	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279631	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279632	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279633	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279634	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279635	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279636	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279607	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279608	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279609	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279610	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279611	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279612	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279613	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279614	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279615	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279616	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279617	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279618	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279619	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279620	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279621	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279622	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279623	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279624	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279625	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279626	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279627	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279628	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279629	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279630	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279631	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279632	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279633	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279634	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279635	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279636	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279637	Soil	7.4	61.4	14.4	197	1.4	53.3	5.1	168	1.98	14.1	4.4	1.2	54	1.5	2.8	0.1	73	0.75	0.090	7
1279638	Soil	7.8	45.1	16.7	214	1.3	44.4	7.5	512	2.08	13.9	2.6	0.9	49	2.0	2.1	0.2	69	0.72	0.095	6
1279639	Soil	6.6	42.6	27.3	181	0.5	49.1	10.2	179	3.94	26.6	2.0	3.0	12	0.2	2.0	0.5	43	0.02	0.181	14
1279640	Soil	6.0	48.2	17.5	194	1.0	50.4	9.4	357	2.05	13.0	3.5	0.8	55	2.2	1.9	0.3	28	0.40	0.121	11
1277681	Soil	13.7	40.6	13.3	196	0.3	45.6	8.2	181	2.27	23.5	2.2	1.5	33	1.2	3.8	0.2	64	0.16	0.114	12
1277682	Soil	12.6	34.2	14.8	180	0.2	40.9	7.6	192	2.47	24.2	2.7	1.9	32	0.7	3.8	0.3	66	0.19	0.117	12
1277683	Soil	8.4	26.1	13.1	129	0.4	29.7	5.7	129	1.97	19.2	2.4	0.7	18	1.0	2.8	0.2	51	0.07	0.071	9
1277684	Soil	1.4	7.2	4.3	16	0.4	4.8	0.8	15	0.40	2.9	0.7	<0.1	5	0.2	0.4	<0.1	13	0.02	0.032	3
1277685	Soil	2.8	19.8	28.2	75	1.2	18.0	3.8	165	1.72	50.5	7.2	1.3	57	0.4	1.5	0.3	21	0.13	0.080	5
1277686	Soil	14.7	38.8	58.2	528	0.5	139.7	54.4	2151	4.89	211.1	32.6	3.4	44	1.1	6.0	0.3	41	0.04	0.154	12
1277687	Soil	6.6	92.9	54.1	240	1.9	77.6	17.3	518	4.23	129.9	12.8	3.3	132	0.5	7.2	0.4	27	0.08	0.096	9
1277688	Soil	4.3	38.6	24.3	146	0.6	36.0	10.3	383	3.10	46.6	7.5	2.0	47	0.4	2.7	0.3	37	0.07	0.092	9
1277689	Soil	2.8	24.7	18.0	78	1.0	18.2	4.5	187	2.03	25.6	6.0	1.4	29	0.2	1.5	0.2	31	0.06	0.093	5
1277690	Soil	0.6	13.5	2.6	16	0.3	4.2	1.4	38	0.65	2.3	1.5	<0.1	8	<0.1	0.2	0.1	10	0.03	0.046	1
1277671	Soil	8.9	34.1	13.4	194	0.7	37.4	7.3	207	2.19	19.0	3.8	2.1	43	1.1	2.9	0.3	80	0.25	0.087	9
1277672	Soil	6.2	22.2	13.4	125	<0.1	24.2	5.5	119	2.14	19.5	2.8	1.7	25	0.9	2.6	0.2	59	0.13	0.081	8
1277673	Soil	7.3	15.8	8.1	68	0.8	18.1	6.1	299	1.54	10.7	1.9	0.2	45	0.7	1.9	0.1	52	0.44	0.137	4
1277674	Soil	7.9	30.7	11.4	153	0.4	36.8	4.7	125	1.71	15.7	1.5	0.7	27	1.9	2.3	0.2	66	0.23	0.064	11
1277675	Soil	3.4	8.1	10.1	38	0.3	7.9	1.8	52	1.10	11.0	0.7	0.3	8	0.3	1.1	0.2	56	0.03	0.032	11
1277676	Soil	6.2	25.0	15.0	125	0.3	27.9	5.3	129	3.08	29.1	1.0	1.2	14	0.5	2.3	0.2	62	0.02	0.068	7
1277677	Soil	5.8	27.2	12.2	121	0.2	26.9	5.8	123	2.30	19.5	2.0	1.6	16	0.5	2.2	0.2	49	0.06	0.072	9
1277678	Soil	9.7	37.8	13.3	197	0.2	44.6	7.1	176	2.40	23.1	1.6	2.6	37	1.1	3.4	0.2	59	0.20	0.110	12
1277679	Soil	6.6	34.8	14.8	182	0.3	38.1	7.9	171	2.67	23.5	2.5	1.9	27	0.9	2.7	0.2	48	0.12	0.102	9
1277680	Soil	6.2	29.7	15.2	77	1.1	22.0	2.4	40	1.45	15.3	1.6	0.2	29	0.9	2.2	0.2	62	0.16	0.112	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1279637	Soil	20	0.14	1545	0.002	7	1.27	0.010	0.15	0.1	0.47	4.2	0.5	0.11	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1279638	Soil	20	0.12	1291	0.001	4	1.06	0.008	0.12	<0.1	0.36	2.6	0.4	0.08	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279639	Soil	10	0.07	382	0.003	5	0.90	0.002	0.07	<0.1	0.03	2.1	0.3	0.07	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279640	Soil	8	0.06	683	0.002	4	0.51	0.008	0.07	<0.1	0.18	2.3	0.3	0.10	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277681	Soil	14	0.15	920	0.003	4	0.61	0.003	0.05	0.1	0.20	2.0	0.2	0.07	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277682	Soil	16	0.20	599	0.004	5	0.72	0.003	0.05	0.1	0.11	2.0	0.2	0.08	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277683	Soil	14	0.14	277	0.004	5	0.65	0.005	0.04	0.1	0.09	1.0	0.2	0.06	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277684	Soil	5	0.02	183	0.003	2	0.26	0.015	0.02	<0.1	0.04	0.1	<0.1	<0.05	1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277685	Soil	16	0.06	311	0.002	8	0.42	0.006	0.13	<0.1	0.35	1.9	0.2	0.20	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277686	Soil	35	0.97	160	0.005	4	1.75	0.005	0.06	0.1	0.26	3.8	0.2	0.13	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277687	Soil	23	0.16	310	0.001	4	0.52	0.007	0.21	<0.1	0.45	4.9	0.4	0.48	2	7.1	0.3	N.A.	N.A.	N.A.	N.A.
1277688	Soil	26	0.27	335	0.004	6	0.90	0.006	0.11	0.1	0.15	2.6	0.2	0.22	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277689	Soil	22	0.11	384	0.003	4	0.70	0.006	0.10	0.1	0.18	2.0	0.1	0.15	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277690	Soil	5	0.03	82	0.008	4	0.40	0.022	0.02	<0.1	0.05	0.2	<0.1	0.08	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277671	Soil	19	0.18	1101	0.003	5	0.87	0.005	0.06	0.1	0.36	2.6	0.3	0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277672	Soil	16	0.18	566	0.002	3	0.71	0.003	0.05	<0.1	0.09	1.9	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277673	Soil	11	0.12	814	0.004	6	0.67	0.017	0.03	0.1	0.23	0.6	0.2	0.13	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277674	Soil	12	0.09	1171	0.004	2	0.71	0.009	0.06	0.1	0.16	1.5	0.3	0.06	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277675	Soil	9	0.06	145	0.007	4	0.50	0.003	0.03	0.1	0.03	0.4	0.2	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277676	Soil	15	0.11	232	0.003	2	0.74	0.004	0.05	<0.1	0.06	1.7	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277677	Soil	14	0.14	421	0.003	3	0.73	0.004	0.03	<0.1	0.08	2.0	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277678	Soil	14	0.16	1324	0.004	2	0.59	0.003	0.05	<0.1	0.20	2.7	0.1	0.07	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277679	Soil	15	0.18	874	0.004	3	0.65	0.003	0.04	0.1	0.10	2.6	0.1	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277680	Soil	15	0.12	679	0.001	3	0.72	0.007	0.06	0.1	0.29	0.4	0.3	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1279637	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279638	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279639	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279640	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277681	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277682	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277683	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277684	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277685	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277686	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277687	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277688	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277689	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277690	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277671	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277672	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277673	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277674	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277675	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277676	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277677	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277678	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277679	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277680	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

CERTIFICATE OF ANALYSIS WHI11000999.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279637	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279638	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279639	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279640	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277681	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277682	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277683	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277684	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277685	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277686	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277687	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277688	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277689	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277690	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277671	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277672	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277673	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277674	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277675	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277676	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277677	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277678	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277679	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277680	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

QUALITY CONTROL REPORT WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1277145	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1277145	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1277613	Soil	7.1	44.1	36.7	134	0.4	24.3	3.0	62	1.36	18.7	1.3	<0.1	109	0.7	5.0	0.1	66	0.07	0.135	3
REP 1277613	QC	7.3	44.9	37.3	130	0.4	24.4	3.1	62	1.32	19.1	1.2	<0.1	109	0.7	4.9	0.1	66	0.07	0.134	3
1277632	Soil	0.6	9.2	1.7	38	0.2	6.9	1.7	150	0.43	2.3	1.1	0.1	35	0.5	0.6	<0.1	13	0.68	0.053	2
REP 1277632	QC	0.7	9.2	1.8	42	0.2	7.8	1.9	155	0.45	2.5	0.7	0.2	38	0.4	0.6	<0.1	14	0.75	0.057	2
1277646	Soil	2.1	37.8	18.2	125	1.0	40.3	10.0	127	3.20	14.2	2.6	0.6	22	0.2	0.8	0.2	29	0.04	0.112	4
REP 1277646	QC	1.9	37.3	18.1	124	0.9	40.9	10.2	123	3.19	13.9	1.3	0.6	22	0.1	0.9	0.2	29	0.04	0.109	4
1277668	Soil	16.3	60.1	20.4	665	1.4	144.0	29.2	3195	5.32	86.2	11.5	1.5	44	5.6	10.5	0.2	156	0.26	0.563	8
REP 1277668	QC	15.7	57.8	19.4	667	1.5	146.8	29.1	3071	5.20	83.9	11.5	1.4	44	5.9	10.0	0.3	155	0.27	0.553	8
1279501	Soil	103.8	124.6	18.4	1034	0.6	238.3	9.7	374	3.20	38.6	3.8	1.3	113	9.0	17.9	0.2	216	4.83	0.087	5
REP 1279501	QC	107.5	131.7	18.6	1057	0.7	253.8	10.6	403	3.31	40.8	4.3	1.3	115	9.2	18.8	0.2	233	4.97	0.090	5
1279502	Soil	86.8	72.1	22.7	1430	0.7	224.7	15.6	563	5.21	48.8	1.6	0.4	40	10.6	17.5	0.2	571	0.48	0.203	11
REP 1279502	QC	83.4	69.6	21.8	1376	0.7	216.7	15.2	541	5.03	48.2	1.3	0.5	38	9.9	17.4	0.2	562	0.40	0.194	11
1279512	Soil	10.2	134.5	23.1	1117	1.1	106.2	27.9	872	5.28	21.4	5.7	1.5	34	8.1	5.2	0.5	73	0.23	0.134	8
REP 1279512	QC	10.1	135.2	22.6	1135	1.1	104.9	27.6	908	5.18	21.4	6.5	1.5	34	7.9	5.1	0.5	74	0.23	0.134	8
1279538	Soil	29.0	34.5	16.0	380	0.2	78.9	9.0	169	2.39	26.6	0.8	0.3	44	1.2	11.5	0.2	128	0.33	0.085	11
REP 1279538	QC	28.4	33.9	16.0	376	0.2	76.6	9.2	168	2.38	26.0	1.5	0.4	45	1.4	11.1	0.2	132	0.33	0.090	11
1279548	Soil	18.0	32.6	24.0	861	0.5	144.6	9.6	448	2.17	33.9	<0.5	1.6	93	4.6	7.0	0.3	72	0.62	0.150	8
REP 1279548	QC	17.9	31.3	23.6	854	0.5	139.1	9.1	417	2.10	33.7	0.7	1.5	91	4.6	6.7	0.2	71	0.58	0.146	8
1279579	Soil	2.7	18.6	6.9	41	0.4	17.3	2.0	45	0.87	4.0	1.0	<0.1	13	0.7	0.7	0.1	18	0.10	0.118	5
REP 1279579	QC	2.5	18.2	7.0	41	0.4	17.4	2.0	47	0.86	4.0	1.2	<0.1	13	1.0	0.7	0.1	17	0.09	0.121	4
1279597	Soil	120.3	109.1	31.9	1214	1.1	292.5	17.4	414	3.94	46.5	<0.5	2.0	278	9.3	18.0	0.1	533	9.35	0.193	5
REP 1279597	QC	119.4	110.3	32.2	1224	1.1	295.2	17.6	415	3.96	47.9	0.7	2.1	277	9.4	17.6	0.2	532	9.20	0.186	5
1279619	Soil	2.7	21.8	10.0	67	0.2	15.1	3.6	123	2.03	10.3	2.8	<0.1	9	0.3	1.0	0.2	47	0.02	0.077	7
REP 1279619	QC	2.6	23.1	9.7	69	0.2	14.4	3.8	118	2.00	10.4	6.4	<0.1	9	0.3	1.0	0.2	46	0.02	0.074	7
1279634	Soil	17.3	39.0	13.8	274	0.7	42.6	4.7	84	2.43	22.3	3.2	1.2	25	2.5	4.0	0.2	162	0.10	0.078	6
REP 1279634	QC	16.8	38.8	13.6	272	0.7	44.0	4.8	81	2.42	21.9	1.3	1.1	26	2.7	3.9	0.2	177	0.10	0.076	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

QUALITY CONTROL REPORT WHI11000999.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1277145	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.3	64.0	24.1	258
REP 1277145	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.				
1277613	Soil	10	0.02	251	0.002	1	0.56	0.016	0.04	0.1	0.06	0.2	0.2	0.09	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277613	QC	10	0.02	249	0.002	1	0.55	0.015	0.03	<0.1	0.05	0.2	0.2	0.09	2	1.3	<0.2				
1277632	Soil	4	0.05	470	0.008	2	0.40	0.031	0.04	<0.1	0.08	0.4	<0.1	0.06	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277632	QC	4	0.06	504	0.008	3	0.43	0.034	0.04	<0.1	0.08	0.5	<0.1	0.09	1	1.7	<0.2				
1277646	Soil	28	0.09	225	0.003	2	1.12	0.007	0.05	<0.1	0.07	1.9	0.1	0.06	4	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277646	QC	27	0.09	221	0.003	1	1.11	0.007	0.05	<0.1	0.09	1.9	0.1	0.07	4	2.3	<0.2				
1277668	Soil	28	0.06	1847	0.008	4	1.02	0.001	0.07	0.2	0.58	4.0	0.7	<0.05	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277668	QC	29	0.06	1797	0.008	4	1.00	<0.001	0.07	0.2	0.60	4.1	0.7	0.08	2	3.5	<0.2				
1279501	Soil	21	1.92	153	0.002	2	0.24	0.004	0.04	0.1	0.43	3.4	1.5	<0.05	<1	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1279501	QC	22	1.99	161	0.002	2	0.25	0.005	0.04	0.1	0.43	3.3	1.5	0.05	<1	5.5	<0.2				
1279502	Soil	63	0.14	350	0.004	2	0.91	0.007	0.05	0.1	0.22	3.0	0.9	<0.05	3	9.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1279502	QC	59	0.11	351	0.004	1	0.90	0.007	0.06	0.2	0.22	3.5	0.9	<0.05	3	9.4	<0.2				
1279512	Soil	34	0.17	249	0.004	<1	1.31	0.003	0.05	<0.1	0.12	5.6	0.2	<0.05	4	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1279512	QC	34	0.17	246	0.004	<1	1.31	0.004	0.05	<0.1	0.11	5.5	0.2	<0.05	4	3.3	<0.2				
1279538	Soil	25	0.19	371	0.004	<1	0.99	0.004	0.06	0.2	0.07	0.8	0.4	<0.05	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1279538	QC	25	0.20	367	0.004	<1	0.99	0.004	0.06	0.1	0.06	0.9	0.4	<0.05	3	4.0	<0.2				
1279548	Soil	17	0.11	436	0.004	3	0.58	0.004	0.07	<0.1	0.26	2.4	0.3	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1279548	QC	17	0.11	437	0.004	2	0.58	0.004	0.07	0.1	0.25	2.1	0.3	<0.05	2	2.7	<0.2				
1279579	Soil	6	0.03	116	0.001	<1	0.37	0.015	0.04	<0.1	0.06	0.2	0.1	0.09	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1279579	QC	7	0.03	114	0.001	<1	0.37	0.015	0.04	<0.1	0.07	0.1	0.1	0.09	1	0.8	<0.2				
1279597	Soil	49	1.88	401	0.003	5	0.41	0.006	0.07	0.1	0.45	5.8	1.0	<0.05	1	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1279597	QC	48	1.86	382	0.004	5	0.39	0.006	0.07	<0.1	0.42	5.8	0.9	<0.05	1	6.4	0.2				
1279619	Soil	17	0.07	161	0.003	2	0.77	0.004	0.07	0.1	0.02	0.4	0.1	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1279619	QC	16	0.07	149	0.002	2	0.73	0.003	0.06	0.1	0.03	0.2	0.1	<0.05	4	0.8	<0.2				
1279634	Soil	19	0.09	417	0.001	2	0.64	0.003	0.07	0.2	0.20	2.0	0.5	0.06	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1279634	QC	20	0.10	429	0.001	3	0.71	0.004	0.08	0.1	0.17	2.0	0.6	0.06	2	2.0	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

QUALITY CONTROL REPORT WHI11000999.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																					
1277145	Soil	2.0	98.6	18.4	293	3.24	17.4	2.5	1.8	93	1.4	1.3	0.3	41	1.59	0.235	9	32	0.18	917	0.002
REP 1277145	QC																				
1277613	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277613	QC																				
1277632	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277632	QC																				
1277646	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277646	QC																				
1277668	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277668	QC																				
1279501	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279501	QC																				
1279502	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279502	QC																				
1279512	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279512	QC																				
1279538	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279538	QC																				
1279548	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279548	QC																				
1279579	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279579	QC																				
1279597	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279597	QC																				
1279619	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279619	QC																				
1279634	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279634	QC																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

QUALITY CONTROL REPORT WHI11000999.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1277145	Soil		<20	0.96	0.010	0.13	<0.1	0.29	3.9	0.3	0.12	3	4.6	<0.2
REP 1277145	QC													
1277613	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277613	QC													
1277632	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277632	QC													
1277646	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277646	QC													
1277668	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277668	QC													
1279501	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279501	QC													
1279502	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279502	QC													
1279512	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279512	QC													
1279538	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279538	QC													
1279548	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279548	QC													
1279579	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279579	QC													
1279597	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279597	QC													
1279619	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279619	QC													
1279634	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1279634	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

QUALITY CONTROL REPORT WHI11000999.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1277672	Soil	6.2	22.2	13.4	125	<0.1	24.2	5.5	119	2.14	19.5	2.8	1.7	25	0.9	2.6	0.2	59	0.13	0.081	8
REP 1277672	QC	6.5	22.7	13.4	127	0.1	23.6	5.3	119	2.13	19.3	2.8	1.7	27	0.8	2.6	0.2	60	0.13	0.079	9
Reference Materials																					
STD DS8	Standard	11.6	107.6	123.6	305	1.8	37.0	7.3	596	2.44	26.1	110.7	6.5	59	2.3	5.6	7.1	39	0.65	0.087	12
STD DS8	Standard	12.4	103.7	120.2	292	1.7	35.0	7.1	573	2.30	23.8	110.7	7.1	66	2.1	5.4	7.0	40	0.64	0.073	15
STD DS8	Standard	13.0	112.0	134.4	323	1.8	37.2	7.3	625	2.49	26.0	130.7	7.4	73	2.3	6.6	7.8	42	0.70	0.083	15
STD DS8	Standard	13.5	109.2	122.3	311	1.8	35.8	7.6	642	2.45	26.2	95.6	7.0	76	2.3	6.1	7.2	40	0.68	0.080	17
STD DS8	Standard	13.8	119.0	134.2	334	1.9	37.6	7.9	656	2.64	27.6	116.8	7.3	68	2.4	5.8	6.9	46	0.75	0.087	16
STD DS8	Standard	14.1	111.9	135.8	331	2.0	39.4	7.9	640	2.56	26.7	128.5	7.2	70	2.4	5.9	7.1	44	0.75	0.085	16
STD DS8	Standard	13.0	117.4	132.5	328	1.9	39.7	8.0	641	2.60	25.7	127.6	7.7	69	2.4	5.7	6.8	44	0.75	0.083	16
STD DS8	Standard	13.2	106.7	121.4	296	1.6	35.4	7.3	574	2.33	23.9	113.5	6.9	68	2.2	5.8	7.0	43	0.67	0.076	15
STD DS8	Standard	14.1	111.5	131.9	330	2.0	40.0	8.2	635	2.54	26.1	128.2	6.9	68	2.4	5.7	6.5	45	0.74	0.084	16
STD DS8	Standard	13.0	106.6	116.2	295	1.7	37.7	7.3	585	2.36	24.5	91.1	6.2	58	2.4	4.5	6.0	36	0.66	0.076	14
STD DS8	Standard	13.0	114.6	124.9	318	1.7	41.1	7.3	593	2.42	21.1	112.1	5.9	63	1.9	4.5	5.7	39	0.69	0.065	14
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	0.6	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

QUALITY CONTROL REPORT WHI11000999.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1277672	Soil	16	0.18	566	0.002	3	0.71	0.003	0.05	<0.1	0.09	1.9	0.2	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277672	QC	17	0.18	588	0.002	5	0.74	0.003	0.05	<0.1	0.09	1.9	0.2	<0.05	2	1.6	<0.2				
Reference Materials																					
STD DS8	Standard	112	0.59	250	0.099	4	0.87	0.082	0.41	2.8	0.20	2.1	5.7	0.18	5	5.1	4.6				
STD DS8	Standard	109	0.55	248	0.119	3	0.82	0.077	0.37	2.7	0.18	2.1	4.9	0.18	4	4.9	4.7				
STD DS8	Standard	113	0.64	286	0.126	2	0.93	0.087	0.41	3.1	0.22	2.0	5.6	0.14	5	5.6	5.5				
STD DS8	Standard	120	0.60	279	0.124	3	0.92	0.088	0.40	3.0	0.18	2.1	5.2	0.15	5	5.5	4.8				
STD DS8	Standard	128	0.67	304	0.129	3	0.99	0.091	0.44	3.3	0.22	2.2	5.9	0.21	5	6.1	5.6				
STD DS8	Standard	120	0.66	293	0.120	3	0.95	0.091	0.44	3.1	0.20	2.2	6.1	0.16	5	5.7	5.1				
STD DS8	Standard	123	0.65	297	0.124	2	0.94	0.088	0.43	3.1	0.21	2.3	5.7	0.15	5	5.0	4.9				
STD DS8	Standard	111	0.66	260	0.119	2	0.89	0.076	0.40	3.0	0.18	2.1	5.0	0.17	5	4.5	4.8				
STD DS8	Standard	120	0.66	287	0.126	2	0.95	0.089	0.44	3.2	0.22	2.1	6.0	0.14	5	5.0	5.6				
STD DS8	Standard	111	0.57	264	0.101	3	0.85	0.083	0.39	2.7	0.18	2.2	5.1	0.14	4	5.1	4.4				
STD DS8	Standard	119	0.60	252	0.120	2	0.92	0.092	0.40	2.7	0.19	1.7	5.3	0.19	4	4.7	4.6				
STD DS8	Standard																	13.4	111.3	123.9	307
STD OREAS45CA	Standard																	0.9	492.3	20.7	61
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

QUALITY CONTROL REPORT WHI11000999.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1277672	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277672	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	2.0	36.7	7.7	597	2.44	24.8	106.2	5.9	65	2.4	4.9	6.1	41	0.69	0.081	15	117	0.61	299	0.113
STD OREAS45CA	Standard	0.3	239.5	87.2	925	16.38	4.3	45.1	6.3	15	<0.1	0.1	0.2	200	0.41	0.040	15	702	0.16	159	0.137
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

QUALITY CONTROL REPORT WHI11000999.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1277672	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277672	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.91	0.091	0.41	2.7	0.17	2.1	5.7	0.15	5	4.6	4.8
STD OREAS45CA	Standard	<20	3.72	0.014	0.07	<0.1	0.03	36.8	<0.1	<0.05	19	1.3	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

QUALITY CONTROL REPORT WHI11000999.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

QUALITY CONTROL REPORT WHI11000999.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

QUALITY CONTROL REPORT WHI11000999.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 10, 2011

QUALITY CONTROL REPORT WHI11000999.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 12, 2011
Report Date: October 06, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001135.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #13
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve to 230 mesh			WHI
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	318	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	2	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094801	Soil		13.4	34.4	13.8	190	1.1	41.1	3.7	72	1.79	13.9	1.6	0.9	22	1.1	3.7	0.2	73	0.08	0.068	6
1094802	Soil		5.5	39.7	12.9	328	0.4	49.3	8.0	251	2.34	13.2	4.2	2.0	35	3.6	2.5	0.2	52	0.27	0.093	9
1094803	Soil		12.2	47.3	10.9	2809	0.8	372.9	10.2	668	2.50	32.7	5.8	1.5	84	52.8	3.0	0.2	54	1.24	0.104	8
1094804	Soil		5.3	49.1	12.5	2545	0.7	358.0	24.3	2694	2.20	20.1	3.6	1.4	105	10.7	2.3	0.2	46	2.00	0.089	7
1094805	Soil		3.3	10.7	12.4	88	<0.1	15.6	3.4	74	1.16	7.1	1.3	1.5	29	0.6	1.3	0.2	44	0.20	0.059	13
1094806	Soil		4.6	57.7	14.5	386	1.5	95.4	5.2	226	1.37	7.9	5.3	0.6	65	11.1	2.1	0.2	65	0.77	0.098	10
1094807	Soil		8.4	13.3	12.3	117	0.2	20.0	3.4	117	1.44	11.8	1.5	1.2	26	0.9	2.0	0.2	62	0.16	0.055	11
1094808	Soil		4.4	34.3	13.7	205	0.7	41.0	5.5	64	1.61	11.3	5.0	1.2	51	3.1	2.2	0.2	62	0.55	0.085	10
1094809	Soil		6.1	39.6	14.9	163	0.3	37.2	11.0	332	2.82	20.3	5.5	2.8	28	0.8	3.1	0.2	60	0.14	0.102	12
1094810	Soil		6.9	25.4	14.2	151	0.3	27.0	5.6	170	3.31	19.8	3.6	2.3	16	0.5	3.2	0.2	95	0.04	0.097	11
1094811	Soil		6.3	43.5	16.1	194	0.6	44.4	8.0	191	2.77	20.4	5.0	2.9	30	0.9	3.5	0.3	77	0.14	0.094	13
1094812	Soil		8.5	16.7	13.6	97	0.1	17.5	2.5	41	1.29	11.2	2.7	0.1	17	0.4	2.1	0.2	68	0.02	0.077	9
1094813	Soil		5.3	20.6	10.7	155	0.3	21.8	5.8	210	1.55	13.1	3.7	1.3	34	1.2	2.4	0.2	64	0.20	0.080	8
1094814	Soil		7.8	21.5	13.7	189	0.2	26.4	2.8	61	1.55	25.6	4.0	0.6	27	0.7	4.3	0.2	76	0.05	0.071	6
1094815	Soil		10.3	73.9	18.9	461	0.9	83.4	13.5	386	2.98	29.6	6.7	3.0	69	5.5	5.7	0.3	82	0.45	0.153	11
1094816	Soil		17.0	36.5	14.9	358	1.1	56.0	14.8	891	3.03	36.6	6.3	1.4	68	2.4	4.6	0.2	75	0.56	0.143	8
1094817	Soil		10.2	26.8	10.9	435	0.6	48.4	10.5	460	2.53	24.9	4.4	1.3	66	1.5	4.4	0.2	83	0.61	0.156	6
1094818	Soil		2.4	48.4	24.5	142	1.5	46.4	12.6	237	3.41	22.7	3.1	1.6	25	0.3	1.3	0.3	24	0.10	0.089	3
1094819	Soil		1.5	23.6	9.9	106	0.4	25.3	5.8	230	1.79	62.8	5.1	0.9	41	0.6	4.4	0.2	22	0.16	0.085	6
1094820	Soil		1.0	36.5	11.5	160	0.7	54.0	10.7	237	2.13	24.5	4.1	1.4	74	0.5	1.8	0.2	26	0.47	0.106	8
1094821	Soil		3.2	48.4	25.3	122	0.9	30.0	10.0	442	5.53	20.3	7.6	0.9	20	0.2	1.6	0.3	45	0.04	0.108	6
1094822	Soil		2.7	39.9	12.8	85	1.6	18.8	4.9	270	3.71	9.9	3.9	0.2	15	0.2	1.2	0.3	48	0.03	0.121	5
1094823	Soil		3.0	57.0	29.5	133	1.0	46.8	35.7	1610	3.69	12.7	5.9	0.7	22	0.3	1.4	0.3	35	0.06	0.103	5
1094824	Soil		3.9	80.7	42.6	198	3.0	52.7	19.8	284	5.79	35.4	3.4	4.9	56	0.5	1.6	0.4	33	0.10	0.109	3
1094825	Soil		3.7	89.2	32.4	286	2.9	106.5	29.6	578	5.78	25.8	2.3	3.6	45	0.8	1.7	0.3	32	0.18	0.127	4
1094826	Soil		3.4	76.4	35.0	252	2.3	88.8	24.7	421	5.38	26.5	2.1	4.3	53	0.6	1.5	0.4	32	0.26	0.126	5
1094827	Soil		3.1	59.7	29.6	172	2.0	59.8	13.4	213	3.80	21.7	3.3	2.4	43	0.3	1.3	0.3	24	0.38	0.099	3
1094828	Soil		2.9	47.3	20.1	107	0.3	30.7	11.6	616	4.02	13.0	4.8	0.6	23	0.2	1.4	0.2	37	0.04	0.089	6
1094829	Soil		2.3	61.5	17.5	103	0.4	33.5	11.8	464	2.97	9.9	3.1	0.8	44	<0.1	1.2	0.3	28	0.04	0.136	6
1094830	Soil		3.0	42.4	19.2	112	1.1	36.1	21.3	947	3.38	14.1	3.4	0.9	30	0.3	1.5	0.3	46	0.08	0.120	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094801	Soil		15	0.09	427	0.001	1	0.67	0.004	0.06	0.1	0.12	1.5	0.4	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094802	Soil		19	0.21	932	0.002	3	0.94	0.005	0.09	<0.1	0.24	2.6	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094803	Soil		17	0.22	792	0.002	3	1.07	0.006	0.09	0.2	0.42	2.7	0.6	0.05	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094804	Soil		16	0.30	639	0.003	8	0.93	0.008	0.10	<0.1	0.31	2.8	0.3	0.10	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094805	Soil		12	0.17	249	0.007	1	0.55	0.004	0.08	0.2	0.04	1.0	0.3	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094806	Soil		17	0.07	720	0.007	2	0.73	0.006	0.06	0.1	0.39	2.0	0.5	0.08	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094807	Soil		12	0.06	363	0.007	<1	0.49	0.005	0.06	0.1	0.05	0.9	0.3	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094808	Soil		16	0.13	822	0.003	3	0.82	0.009	0.06	0.1	0.34	2.2	0.4	0.06	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094809	Soil		19	0.23	819	0.008	1	0.89	0.003	0.05	0.2	0.13	2.2	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094810	Soil		21	0.18	364	0.003	2	1.12	0.003	0.07	0.1	0.06	1.6	0.3	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094811	Soil		23	0.26	600	0.005	1	1.12	0.004	0.08	0.2	0.21	2.5	0.3	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094812	Soil		9	0.03	246	0.002	2	0.39	0.004	0.07	0.1	0.03	0.2	0.4	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094813	Soil		14	0.09	422	0.002	2	0.59	0.004	0.07	<0.1	0.21	1.6	0.3	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094814	Soil		14	0.03	289	0.002	3	0.36	0.003	0.06	0.1	0.12	0.9	0.4	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094815	Soil		19	0.19	1815	0.003	4	0.76	0.005	0.11	0.1	0.74	3.8	0.6	<0.05	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094816	Soil		18	0.16	1758	0.002	3	0.74	0.005	0.07	0.1	0.98	2.5	0.4	0.09	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094817	Soil		19	0.18	2502	0.004	5	0.70	0.008	0.09	0.1	0.46	2.0	0.3	0.08	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094818	Soil		23	0.14	580	<0.001	3	1.00	0.007	0.11	<0.1	0.16	4.7	0.1	0.11	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094819	Soil		16	0.07	304	0.003	2	0.59	0.005	0.06	<0.1	0.51	1.9	<0.1	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094820	Soil		20	0.13	636	0.001	3	0.91	0.005	0.08	<0.1	0.49	2.7	0.1	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094821	Soil		33	0.26	119	0.012	1	1.16	0.003	0.05	0.1	0.10	2.0	0.2	<0.05	4	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094822	Soil		27	0.08	151	0.006	2	0.91	0.004	0.06	<0.1	0.15	0.6	<0.1	0.09	6	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094823	Soil		27	0.27	213	0.007	1	1.16	0.004	0.06	0.1	0.11	1.6	0.2	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094824	Soil		33	0.15	779	<0.001	4	1.36	0.008	0.13	<0.1	0.20	7.3	0.2	0.16	3	6.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094825	Soil		28	0.20	594	<0.001	3	1.15	0.006	0.10	<0.1	0.16	7.5	0.2	0.09	3	6.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094826	Soil		28	0.18	595	<0.001	3	1.07	0.006	0.11	<0.1	0.19	6.7	0.1	0.10	2	5.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094827	Soil		26	0.14	596	<0.001	2	1.03	0.005	0.10	<0.1	0.22	5.8	0.1	0.09	2	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094828	Soil		27	0.27	120	0.008	2	1.05	0.004	0.05	0.1	0.07	1.4	0.1	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094829	Soil		30	0.21	343	0.005	2	1.16	0.008	0.07	<0.1	0.06	1.2	0.2	0.07	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094830	Soil		30	0.35	176	0.012	3	1.29	0.006	0.09	0.1	0.09	1.5	0.1	<0.05	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094801	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094802	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094803	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094804	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094805	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094806	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094807	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094808	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094809	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094810	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094811	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094812	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094813	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094814	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094815	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094816	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094817	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094818	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094819	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094820	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094821	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094822	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094823	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094824	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094825	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094826	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094827	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094828	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094829	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094830	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094801	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094802	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094803	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094804	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094805	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094806	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094807	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094808	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094809	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094810	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094811	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094812	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094813	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094814	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094815	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094816	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094817	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094818	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094819	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094820	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094821	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094822	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094823	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094824	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094825	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094826	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094827	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094828	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094829	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094830	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094831	Soil		3.2	54.3	19.1	109	0.4	38.7	17.1	874	3.69	11.3	4.3	2.2	18	0.1	1.5	0.3	35	0.03	0.069	8
1094832	Soil		3.6	49.3	18.5	103	0.2	31.3	11.1	788	3.71	11.5	3.2	0.8	24	0.1	1.5	0.3	44	0.03	0.083	8
1094833	Soil		3.4	55.1	23.2	122	1.2	56.0	21.4	1402	2.98	12.1	4.1	0.8	58	0.2	1.1	0.3	29	0.15	0.117	7
1094834	Soil		3.6	57.6	25.3	140	0.8	57.1	27.3	1718	3.86	14.1	3.8	2.3	59	0.3	1.2	0.3	36	0.06	0.118	7
1094835	Soil		2.4	41.0	17.9	100	0.9	35.5	15.7	955	2.76	8.5	3.5	1.3	35	0.1	0.9	0.3	31	0.08	0.101	6
1094836	Soil		2.4	39.2	16.5	103	0.8	38.9	14.8	1071	2.90	9.6	1.3	1.2	40	0.2	1.0	0.3	33	0.05	0.100	6
1094837	Soil		2.8	45.7	20.4	132	0.6	45.8	17.8	738	3.52	13.2	2.7	1.3	40	0.2	1.4	0.3	39	0.05	0.104	6
1094838	Soil		3.5	51.1	17.1	88	0.5	28.0	6.7	186	2.98	11.8	2.9	1.3	30	0.1	1.2	0.3	36	0.03	0.075	6
1094839	Soil		7.0	66.1	19.7	105	1.0	32.5	8.2	239	3.17	9.5	8.9	1.5	38	0.1	1.0	0.4	35	0.03	0.049	5
1094840	Soil		2.2	37.4	24.9	78	0.2	26.1	8.1	277	4.05	13.1	1.1	2.5	69	0.1	0.9	0.3	29	0.02	0.133	4
1094841	Soil		1.7	27.6	12.9	51	0.8	16.1	5.3	215	2.15	6.9	3.3	0.3	23	<0.1	0.6	0.2	23	0.03	0.091	3
1094842	Soil		1.5	13.6	15.5	40	<0.1	12.1	3.2	92	2.24	9.0	2.1	1.4	18	<0.1	0.5	0.2	37	0.01	0.061	4
1094843	Soil		1.2	14.3	9.2	35	0.3	11.9	5.9	769	2.35	5.3	1.1	1.0	17	<0.1	0.3	0.2	21	0.02	0.083	3
1094844	Soil		3.4	35.6	15.7	126	0.4	36.0	7.8	235	3.23	48.4	3.5	0.9	15	0.4	1.9	0.2	49	0.06	0.091	11
1094845	Soil		2.5	32.5	19.3	121	0.7	29.0	7.7	198	2.86	43.0	2.4	1.6	32	0.3	1.5	0.3	42	0.08	0.075	7
1094846	Soil		2.5	51.2	16.7	202	1.0	66.1	13.8	344	3.80	26.2	4.4	1.3	41	0.5	1.4	0.2	35	0.10	0.119	7
1094847	Soil		4.3	42.9	17.8	113	1.3	36.0	9.5	339	3.08	18.0	2.7	0.9	22	0.2	1.4	0.3	40	0.05	0.098	7
1094848	Soil		3.4	28.6	18.7	74	1.0	22.4	6.6	240	2.14	11.6	3.1	1.0	21	0.2	1.2	0.3	36	0.04	0.075	5
1094849	Soil		2.9	93.7	23.1	160	0.9	46.5	10.0	382	3.05	18.8	7.2	1.6	33	0.6	1.5	0.2	29	0.09	0.069	6
1094850	Soil		10.4	23.5	21.3	39	3.2	9.9	1.4	47	2.08	34.0	5.3	0.6	30	0.1	3.0	0.2	33	0.02	0.071	3
1094851	Soil		4.9	38.4	22.7	77	2.1	20.3	3.7	100	2.29	23.0	3.5	0.3	22	0.3	1.7	0.3	46	0.10	0.085	6
1094852	Soil		10.8	50.0	15.9	86	0.1	60.0	17.3	325	4.19	16.3	1.6	0.5	6	0.2	2.4	0.3	46	0.06	0.076	14
1094853	Soil		3.7	22.0	6.2	49	<0.1	22.7	8.1	151	2.23	4.8	<0.5	0.4	11	<0.1	1.2	0.2	25	0.06	0.085	7
1094854	Soil		13.0	35.1	12.0	125	0.1	43.2	10.6	648	3.45	11.8	<0.5	0.3	11	0.2	3.0	0.3	56	0.08	0.114	13
1094855	Soil		109.7	53.0	17.0	328	0.2	163.7	9.8	178	3.43	26.2	<0.5	0.7	16	1.2	10.3	0.2	167	0.28	0.081	4
1094856	Soil		83.3	77.4	13.7	289	0.2	176.9	11.5	259	3.06	22.4	<0.5	1.3	59	2.5	5.1	0.1	59	1.21	0.097	5
1094857	Soil		103.3	81.4	22.0	498	0.3	226.9	13.4	361	4.03	32.9	1.7	0.7	40	2.7	11.1	0.1	215	0.72	0.115	7
1094858	Soil		108.2	101.7	17.5	568	0.5	261.3	11.8	386	3.44	32.0	<0.5	1.2	87	3.7	9.7	0.2	170	3.48	0.111	4
1094859	Soil		126.8	149.6	27.6	1576	1.9	322.5	10.9	292	3.34	89.7	<0.5	2.9	289	15.5	39.4	0.1	510	11.81	0.114	5
1094860	Soil		84.4	58.1	29.5	773	0.6	173.8	10.2	390	2.82	68.7	<0.5	2.6	158	7.2	18.2	0.1	279	5.27	0.145	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094831	Soil	28	0.24	309	0.007	2	1.18	0.004	0.05	0.2	0.07	2.1	0.1	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094832	Soil	29	0.16	272	0.008	2	0.98	0.004	0.05	0.2	0.05	1.3	0.1	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094833	Soil	28	0.21	967	0.006	3	1.35	0.012	0.06	<0.1	0.22	1.8	0.1	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094834	Soil	34	0.28	1146	0.005	3	1.45	0.006	0.07	<0.1	0.14	2.6	0.1	<0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094835	Soil	27	0.23	1597	0.006	4	1.24	0.007	0.07	0.1	0.13	2.0	0.1	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094836	Soil	24	0.22	847	0.006	3	1.20	0.007	0.07	<0.1	0.10	1.8	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094837	Soil	27	0.26	1134	0.007	<1	1.23	0.008	0.06	0.1	0.09	2.2	0.1	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094838	Soil	39	0.28	312	0.006	2	1.31	0.006	0.06	0.1	0.08	1.8	0.1	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094839	Soil	53	0.37	848	0.005	2	1.43	0.007	0.05	<0.1	0.22	2.6	0.2	<0.05	4	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094840	Soil	28	0.32	213	0.004	<1	1.32	0.012	0.06	<0.1	0.06	2.7	0.2	0.06	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094841	Soil	18	0.14	426	0.005	1	0.94	0.013	0.05	<0.1	0.10	0.7	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094842	Soil	17	0.18	93	0.003	<1	0.99	0.006	0.05	<0.1	0.01	1.4	0.1	<0.05	5	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094843	Soil	16	0.17	126	0.003	<1	0.96	0.011	0.04	<0.1	0.09	1.5	0.1	<0.05	3	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094844	Soil	24	0.24	176	0.011	2	1.21	0.004	0.07	0.3	0.08	1.4	0.1	0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094845	Soil	22	0.14	553	0.003	3	0.93	0.005	0.12	0.1	0.16	2.3	0.2	0.15	3	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094846	Soil	20	0.15	272	0.005	2	0.93	0.008	0.08	0.1	0.14	2.1	0.2	0.07	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094847	Soil	21	0.17	190	0.008	<1	0.90	0.010	0.09	0.1	0.06	1.8	0.2	0.05	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094848	Soil	17	0.10	275	0.003	3	0.73	0.006	0.11	<0.1	0.16	1.7	0.3	0.12	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094849	Soil	17	0.12	283	0.005	3	1.02	0.009	0.08	<0.1	0.23	2.3	0.2	0.07	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094850	Soil	24	0.04	180	0.001	<1	0.46	0.002	0.07	<0.1	0.79	1.2	0.3	0.08	2	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094851	Soil	22	0.06	392	0.003	<1	0.64	0.003	0.09	0.1	0.43	0.6	0.2	0.09	3	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094852	Soil	11	0.05	120	0.007	<1	0.41	0.003	0.07	0.1	0.03	1.1	0.1	<0.05	2	1.2	0.3	N.A.	N.A.	N.A.	N.A.
1094853	Soil	7	0.04	593	0.003	<1	0.47	0.010	0.06	<0.1	0.03	0.3	0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094854	Soil	12	0.05	277	0.004	<1	0.51	0.003	0.08	0.1	0.04	0.5	0.1	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094855	Soil	14	0.05	157	0.002	<1	0.33	0.002	0.04	<0.1	0.15	2.8	0.7	<0.05	1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094856	Soil	17	0.28	183	0.002	<1	0.30	0.002	0.04	<0.1	0.36	3.7	0.8	<0.05	<1	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094857	Soil	25	0.09	392	0.003	<1	0.53	0.004	0.03	0.1	0.21	3.4	0.9	0.07	1	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094858	Soil	21	1.05	182	0.003	2	0.36	0.004	0.05	0.1	0.24	4.1	1.3	0.07	<1	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094859	Soil	32	2.66	231	0.003	4	0.24	0.005	0.07	0.1	1.95	3.8	1.9	0.11	<1	14.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094860	Soil	22	2.43	431	0.002	4	0.26	0.006	0.06	<0.1	0.87	4.6	0.7	0.08	<1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094831	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094832	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094833	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094834	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094835	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094836	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094837	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094838	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094839	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094840	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094841	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094842	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094843	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094844	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094845	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094846	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094847	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094848	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094849	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094850	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094851	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094852	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094853	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094854	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094855	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094856	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094857	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094858	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094859	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094860	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094831	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094832	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094833	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094834	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094835	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094836	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094837	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094838	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094839	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094840	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094841	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094842	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094843	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094844	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094845	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094846	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094847	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094848	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094849	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094850	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094851	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094852	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094853	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094854	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094855	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094856	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094857	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094858	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094859	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094860	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094861	Soil		114.2	51.9	32.2	671	0.4	207.6	11.9	402	3.48	64.3	<0.5	2.3	136	4.3	13.1	0.1	184	4.31	0.112	3
1094862	Soil		79.0	60.3	66.4	722	0.9	190.9	12.0	719	4.48	105.4	1.1	2.9	156	3.5	25.4	0.1	69	6.50	0.110	4
1094863	Soil		71.6	77.6	89.4	606	1.0	207.5	11.8	428	2.94	97.9	<0.5	1.7	121	4.0	24.0	0.1	135	5.38	0.112	4
1094864	Soil		206.1	69.1	14.8	691	0.9	392.5	8.1	119	2.56	87.6	1.0	0.4	23	5.5	23.8	0.2	276	0.30	0.077	3
1094865	Soil		8.1	27.4	93.7	398	0.8	89.2	10.4	328	2.34	113.0	4.9	0.8	50	1.6	17.8	0.2	56	0.13	0.093	7
1094866	Soil		8.1	16.7	83.1	34	1.6	24.4	2.4	43	1.03	38.9	4.0	0.9	49	0.2	12.2	0.3	28	0.14	0.027	1
1094867	Soil		30.6	120.4	27.1	186	0.6	490.3	97.5	1799	12.89	57.0	1.8	1.6	99	0.3	7.4	0.1	200	1.75	0.163	3
1094868	Soil		10.3	56.3	163.0	344	1.2	238.0	37.0	915	3.66	99.2	3.5	1.4	101	2.0	22.4	0.2	81	1.14	0.124	5
1094869	Soil		5.2	80.6	15.4	248	0.3	490.3	77.9	1297	7.52	12.1	0.8	1.0	105	1.5	3.3	<0.1	152	2.16	0.172	10
1094870	Soil		7.4	38.7	21.0	123	0.3	32.2	9.3	255	2.63	19.9	2.9	0.2	18	0.5	4.0	0.3	63	0.03	0.096	5
1094871	Soil		7.1	39.4	31.5	82	0.7	20.9	4.3	109	1.41	19.9	2.8	0.2	44	0.8	6.0	0.2	66	0.09	0.072	3
1094872	Soil		32.4	13.4	145.0	14	1.0	9.4	1.5	34	1.13	9.0	1.2	1.8	15	0.1	17.3	0.4	40	0.07	0.011	2
1094873	Soil		7.2	96.3	33.4	507	0.6	398.6	85.3	2189	11.84	63.8	<0.5	1.5	358	2.2	10.6	<0.1	176	7.12	0.254	3
1094874	Soil		56.5	110.0	61.9	1502	0.9	312.5	49.9	1072	7.27	74.9	2.7	1.6	202	8.3	22.0	0.2	106	0.81	0.204	3
1094875	Soil		44.3	68.2	65.4	649	1.3	147.9	19.6	342	4.03	77.1	12.5	0.8	204	5.6	26.8	0.3	92	0.45	0.164	4
1094876	Soil		29.2	54.6	47.0	516	0.8	108.2	15.2	350	3.35	49.1	7.9	0.6	128	5.7	15.9	0.2	79	0.32	0.153	3
1094877	Soil		15.8	43.6	57.8	178	0.8	48.2	9.3	316	2.61	29.8	6.6	0.2	121	0.9	15.4	0.3	71	0.11	0.163	6
1094878	Soil		5.3	54.2	11.3	196	0.4	70.2	7.4	132	2.48	17.2	0.8	0.3	7	0.6	6.4	0.2	37	0.02	0.104	2
1094879	Soil		39.1	34.7	14.6	413	<0.1	69.5	6.9	74	2.01	44.5	<0.5	0.2	7	1.1	12.0	0.2	167	0.02	0.101	3
1094880	Soil		6.2	60.8	11.3	89	0.1	40.6	12.9	179	3.88	28.4	1.4	0.2	8	<0.1	9.9	0.3	36	<0.01	0.065	4
1094881	Soil		21.9	38.7	46.8	457	0.3	69.0	10.5	459	3.21	82.1	3.5	0.2	11	1.1	51.8	0.2	141	0.05	0.114	4
1094882	Soil		13.4	36.0	16.3	273	0.2	60.1	8.6	211	2.70	41.8	3.3	0.3	15	1.0	36.7	0.2	68	0.03	0.117	7
1094883	Soil		2.9	74.9	14.1	155	0.6	59.5	17.5	348	4.74	674.6	116.2	0.5	32	1.0	964.6	<0.1	81	0.51	0.102	3
1094884	Soil		3.5	87.0	7.3	147	0.3	58.8	26.1	792	5.71	63.9	2.9	0.7	22	1.1	53.3	<0.1	69	0.61	0.119	6
1094885	Soil		11.3	33.2	20.7	261	0.1	54.4	11.1	440	3.35	38.3	1.2	0.4	21	2.2	15.6	0.3	118	0.29	0.111	8
1094886	Soil		7.7	38.1	16.0	335	0.8	66.2	11.0	432	2.51	40.9	6.0	0.8	43	2.2	19.2	0.2	74	0.82	0.129	4
1094887	Soil		46.4	52.4	19.9	490	0.4	124.2	13.9	339	3.69	29.0	1.2	1.9	39	3.0	18.8	0.2	154	0.64	0.106	4
1094888	Soil		7.8	17.6	9.6	77	0.7	23.8	2.2	57	0.92	7.9	0.8	0.3	41	1.3	5.3	0.1	52	0.84	0.173	3
1094889	Soil		54.6	48.1	18.1	388	0.4	131.4	9.4	196	2.65	28.5	3.8	1.1	37	3.4	19.8	0.1	101	0.88	0.107	5
1094890	Soil		23.8	35.4	13.6	457	0.5	136.0	6.7	205	1.79	23.9	3.3	1.2	107	4.3	10.7	0.1	51	7.79	0.091	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094861	Soil		18	1.80	231	0.002	3	0.22	0.005	0.05	<0.1	0.57	4.9	0.6	0.07	<1	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094862	Soil		21	3.11	227	0.003	3	0.26	0.007	0.04	<0.1	0.48	7.8	0.9	0.24	<1	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094863	Soil		32	2.39	269	0.002	3	0.26	0.004	0.05	0.1	0.51	4.6	1.2	0.06	<1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094864	Soil		20	0.04	1109	0.001	<1	0.42	<0.001	0.04	0.4	0.51	2.0	1.7	<0.05	<1	7.4	0.3	N.A.	N.A.	N.A.	N.A.
1094865	Soil		40	0.12	132	0.006	3	0.63	0.003	0.03	<0.1	0.11	2.3	0.2	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094866	Soil		8	0.02	288	<0.001	2	0.10	0.003	0.11	<0.1	0.26	1.3	0.6	0.22	<1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094867	Soil		234	0.67	305	0.005	3	0.45	0.010	0.03	<0.1	0.24	20.5	0.8	<0.05	2	4.8	0.4	N.A.	N.A.	N.A.	N.A.
1094868	Soil		94	0.26	518	0.002	3	0.26	0.003	0.06	<0.1	0.39	8.1	0.6	0.12	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094869	Soil		256	0.18	223	0.004	2	0.47	0.010	0.03	<0.1	0.13	16.9	0.2	0.07	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094870	Soil		15	0.04	107	0.004	2	0.43	0.005	0.05	0.1	0.05	0.8	0.3	0.07	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094871	Soil		15	0.06	369	0.003	2	0.46	0.006	0.04	0.1	0.12	1.6	0.3	0.08	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094872	Soil		10	0.03	447	0.001	3	0.10	0.004	0.11	0.1	0.44	1.5	0.9	0.23	1	9.8	0.2	N.A.	N.A.	N.A.	N.A.
1094873	Soil		241	1.93	685	0.005	2	0.50	0.009	0.04	<0.1	0.20	24.1	0.2	0.17	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094874	Soil		55	0.27	714	0.002	2	0.52	0.003	0.04	<0.1	0.41	14.4	0.7	0.11	1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094875	Soil		39	0.07	898	0.002	3	0.46	0.003	0.08	<0.1	0.45	5.7	0.7	0.14	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094876	Soil		36	0.07	1055	0.006	3	0.45	0.004	0.05	0.1	0.33	3.6	0.5	0.10	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094877	Soil		25	0.04	803	0.004	3	0.47	0.004	0.06	0.1	0.17	1.1	0.3	0.08	3	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094878	Soil		19	0.03	157	0.002	1	0.29	0.003	0.04	0.1	0.05	0.9	0.1	<0.05	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094879	Soil		12	0.02	146	0.003	2	0.38	0.003	0.05	<0.1	0.02	0.6	0.4	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094880	Soil		9	0.03	138	0.003	2	0.30	0.004	0.06	<0.1	0.07	1.0	0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094881	Soil		14	0.04	232	0.002	2	0.42	0.004	0.05	<0.1	0.05	1.2	0.3	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094882	Soil		20	0.12	105	0.004	1	0.62	0.004	0.04	<0.1	0.03	0.9	0.2	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094883	Soil		48	0.12	277	0.001	<1	0.66	0.011	0.03	<0.1	0.13	8.1	0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094884	Soil		46	0.09	812	0.001	2	0.91	0.003	0.06	<0.1	0.16	26.5	0.2	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094885	Soil		28	0.17	238	0.011	2	0.72	0.004	0.08	<0.1	0.05	1.7	0.2	<0.05	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094886	Soil		23	0.14	322	0.002	2	0.70	0.004	0.03	<0.1	0.24	4.6	0.2	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094887	Soil		21	0.13	341	0.002	2	0.56	0.002	0.04	<0.1	0.19	5.2	0.3	<0.05	1	6.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094888	Soil		8	0.10	325	0.004	2	0.62	0.013	0.03	<0.1	0.15	1.4	0.2	0.13	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094889	Soil		15	0.13	226	0.003	2	0.40	0.004	0.04	0.1	0.23	4.5	0.4	<0.05	1	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094890	Soil		15	1.18	236	0.005	3	0.44	0.005	0.04	0.1	0.27	3.4	0.9	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094861	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094862	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094863	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094864	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094865	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094866	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094867	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094868	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094869	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094870	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094871	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094872	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094873	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094874	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094875	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094876	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094877	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094878	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094879	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094880	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094881	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094882	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094883	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094884	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094885	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094886	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094887	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094888	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094889	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094890	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094861	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094862	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094863	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094864	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094865	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094866	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094867	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094868	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094869	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094870	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094871	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094872	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094873	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094874	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094875	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094876	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094877	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094878	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094879	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094880	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094881	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094882	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094883	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094884	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094885	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094886	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094887	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094888	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094889	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094890	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094891	Soil		14.6	68.0	20.4	495	0.9	145.4	10.6	209	1.65	29.1	4.8	2.5	119	5.9	11.1	0.2	64	5.06	0.123	8
1094892	Soil		4.0	14.3	10.9	93	0.4	22.0	4.1	67	0.95	14.2	0.6	0.2	19	0.6	1.9	<0.1	21	0.08	0.051	2
1094893	Soil		3.0	12.0	10.6	374	0.4	81.1	3.3	74	0.85	18.0	0.6	0.2	31	1.9	1.8	0.1	18	0.27	0.049	2
1094894	Soil		12.1	30.7	37.9	153	1.4	46.4	8.2	155	2.60	31.5	3.6	0.5	95	0.7	6.3	0.3	56	0.07	0.088	2
1094895	Soil		2.3	9.3	5.8	48	0.4	13.0	3.4	51	0.75	6.6	<0.5	<0.1	10	0.3	1.2	0.1	16	0.02	0.044	2
1094896	Soil		6.0	16.3	11.3	105	<0.1	25.3	9.3	191	1.96	16.9	<0.5	0.3	11	0.4	2.5	0.2	46	0.02	0.055	5
1094897	Soil		2.6	59.3	15.7	137	1.5	43.9	6.3	134	2.50	25.3	13.3	1.4	82	0.6	2.6	0.2	36	1.33	0.075	5
1094898	Soil		2.0	32.0	12.1	93	0.8	27.6	5.7	155	1.72	30.5	10.0	1.1	58	0.4	2.8	0.2	30	1.33	0.062	5
1094899	Soil		4.9	35.8	16.1	122	1.1	27.6	9.6	298	2.34	38.0	14.4	2.0	30	0.6	4.1	0.3	52	0.26	0.084	7
1094900	Soil		11.4	22.4	17.1	158	0.2	37.9	8.4	204	2.18	22.5	1.9	0.3	17	0.6	4.4	0.3	61	0.04	0.081	6
1094901	Soil		2.3	19.3	20.1	41	0.1	35.2	11.3	147	2.67	12.9	0.6	0.7	6	0.2	1.0	0.4	26	0.01	0.042	3
1094902	Soil		8.6	17.7	9.9	113	<0.1	24.7	6.6	102	1.51	15.0	<0.5	0.1	8	0.5	3.0	0.3	59	0.02	0.055	6
1094903	Soil		7.9	15.8	11.5	116	0.1	25.1	7.8	218	1.76	12.8	<0.5	0.4	8	2.6	2.4	0.3	56	0.02	0.064	5
1094904	Soil		17.6	18.9	17.0	183	0.4	40.7	4.5	85	1.56	17.9	<0.5	0.9	17	3.2	5.9	0.2	90	0.04	0.063	10
1094905	Soil		5.5	28.0	13.7	117	0.2	30.9	5.9	88	1.17	12.0	<0.5	0.3	34	0.5	2.5	0.2	33	0.29	0.069	4
1094906	Soil		13.8	30.7	18.8	198	0.8	49.6	8.0	96	2.00	24.1	1.4	0.4	30	1.0	5.4	0.2	65	0.08	0.084	7
1094907	Soil		11.2	27.7	24.8	279	0.4	54.4	10.4	325	2.86	26.8	2.3	1.7	110	2.0	9.6	0.2	63	0.71	0.127	7
1094908	Soil		2.8	32.7	24.0	79	1.0	15.8	2.9	46	2.19	21.4	0.9	1.5	32	0.2	0.8	0.3	42	0.01	0.058	4
1094909	Soil		2.8	72.7	32.0	115	0.5	26.0	3.9	169	3.57	29.1	1.8	2.1	133	0.4	0.8	0.4	36	0.02	0.106	3
1094910	Soil		2.2	96.9	33.0	120	2.1	29.8	4.2	109	3.46	42.8	2.5	2.2	105	0.5	1.8	0.3	47	0.06	0.127	5
1094911	Soil		3.4	21.5	21.8	46	1.1	8.3	1.6	52	2.21	29.5	6.9	0.3	43	0.2	2.2	0.3	54	0.05	0.095	4
1094912	Soil		7.2	36.5	26.4	68	1.2	11.6	2.3	55	3.02	51.3	16.1	0.6	135	0.2	3.4	0.4	83	0.06	0.102	7
1094913	Soil		4.3	27.7	18.1	62	1.2	12.8	2.8	55	2.78	32.7	15.2	1.4	48	0.1	3.0	0.3	67	0.03	0.059	7
1094914	Soil		4.5	26.0	14.8	67	0.9	14.2	3.3	71	1.96	23.7	6.5	0.6	38	0.4	2.3	0.3	66	0.04	0.053	11
1094915	Soil		7.7	19.5	14.5	66	0.5	15.2	3.5	50	1.40	34.3	2.3	0.3	13	0.1	3.8	0.3	79	0.02	0.048	12
1094916	Soil		27.0	27.9	24.0	54	4.0	12.5	2.6	41	1.91	42.9	3.6	0.5	105	0.6	12.0	0.3	155	0.07	0.263	11
1094917	Soil		22.2	62.6	20.5	163	3.7	22.5	2.6	32	1.62	63.9	3.0	0.4	69	0.4	26.5	0.3	245	0.03	0.151	6
1094918	Soil		20.9	3.5	16.0	5	0.3	2.3	0.1	3	0.92	6.6	<0.5	0.6	12	<0.1	4.0	0.1	31	<0.01	0.011	1
1094919	Soil		3.8	16.1	21.0	183	0.6	23.5	7.9	108	3.00	132.4	12.0	2.8	12	0.2	11.9	0.5	26	0.02	0.063	21
1094920	Soil		3.0	27.3	65.1	163	0.4	27.2	8.4	46	4.58	400.9	33.3	10.6	64	0.3	21.0	0.5	14	<0.01	0.088	35

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094891	Soil	22	0.96	588	0.013	3	0.61	0.007	0.06	0.2	0.32	4.3	0.7	0.06	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094892	Soil	8	0.03	167	0.002	<1	0.34	0.016	0.03	<0.1	0.08	0.8	0.2	<0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094893	Soil	7	0.04	85	0.002	1	0.28	0.017	0.03	<0.1	0.07	1.3	0.5	<0.05	<1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094894	Soil	11	0.03	322	0.004	2	0.34	0.005	0.05	<0.1	0.16	2.3	0.7	<0.05	1	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094895	Soil	5	0.01	84	0.002	<1	0.25	0.018	0.02	<0.1	0.05	0.4	0.1	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094896	Soil	11	0.03	101	0.003	<1	0.48	0.010	0.05	0.1	0.03	1.0	0.2	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094897	Soil	26	0.26	550	0.001	4	1.02	0.006	0.07	<0.1	0.88	3.3	0.1	0.07	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094898	Soil	17	0.14	841	0.001	3	0.80	0.007	0.05	<0.1	0.88	2.2	0.1	0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094899	Soil	22	0.15	783	0.001	2	0.94	0.005	0.06	0.1	1.46	2.8	0.3	<0.05	3	2.7	0.3	N.A.	N.A.	N.A.	N.A.
1094900	Soil	14	0.07	134	0.004	1	0.46	0.010	0.05	0.1	0.05	0.9	0.3	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094901	Soil	8	0.04	42	0.001	1	0.34	0.004	0.04	<0.1	<0.01	2.1	0.1	0.15	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094902	Soil	8	0.03	64	0.003	2	0.42	0.006	0.04	<0.1	<0.01	0.2	0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094903	Soil	10	0.04	176	0.003	<1	0.71	0.007	0.05	<0.1	<0.01	1.0	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094904	Soil	11	0.05	282	0.006	1	0.61	0.006	0.05	0.2	<0.01	0.8	0.3	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094905	Soil	8	0.07	528	0.002	2	0.64	0.015	0.06	<0.1	0.07	1.1	0.2	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094906	Soil	13	0.08	364	0.003	2	0.54	0.008	0.06	0.1	0.08	1.2	0.3	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094907	Soil	16	0.08	470	0.006	3	0.43	0.009	0.06	0.1	0.13	2.4	0.3	<0.05	1	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094908	Soil	16	0.04	236	0.001	2	0.96	0.004	0.06	<0.1	0.03	1.6	0.1	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094909	Soil	23	0.10	437	<0.001	3	1.38	0.004	0.10	<0.1	0.10	2.4	0.1	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094910	Soil	23	0.11	625	0.002	6	1.24	0.008	0.14	<0.1	0.17	5.1	0.1	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094911	Soil	13	0.02	543	0.004	5	0.45	0.004	0.17	0.1	0.16	0.6	0.1	0.37	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094912	Soil	18	0.04	684	0.011	3	0.38	0.004	0.13	0.2	0.14	1.5	0.2	0.18	3	3.2	0.2	N.A.	N.A.	N.A.	N.A.
1094913	Soil	14	0.06	353	0.015	2	0.48	0.003	0.09	0.2	0.23	1.3	0.1	0.06	4	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094914	Soil	13	0.07	475	0.013	2	0.46	0.003	0.07	0.2	0.11	1.0	0.1	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1094915	Soil	12	0.03	124	0.005	2	0.41	0.003	0.05	0.2	0.31	0.5	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1094916	Soil	30	0.05	269	0.004	2	0.53	0.004	0.11	0.4	0.33	0.7	0.8	0.10	5	10.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094917	Soil	16	0.02	178	0.004	2	0.67	0.008	0.06	0.4	0.46	0.6	0.9	<0.05	3	9.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094918	Soil	3	<0.01	154	<0.001	2	0.17	0.005	0.13	<0.1	0.17	0.3	0.9	0.21	<1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094919	Soil	5	0.02	69	0.001	2	0.52	0.008	0.05	<0.1	4.21	0.9	0.2	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094920	Soil	6	0.01	183	<0.001	3	0.45	0.012	0.11	<0.1	6.95	2.3	0.3	0.41	1	3.6	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094891	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094892	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094893	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094894	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094895	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094896	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094897	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094898	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094899	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094900	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094901	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094902	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094903	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094904	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094905	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094906	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094907	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094908	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094909	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094910	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094911	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094912	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094913	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094914	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094915	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094916	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094917	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094918	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094919	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094920	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094891	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094892	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094893	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094894	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094895	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094896	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094897	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094898	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094899	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094900	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094901	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094902	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094903	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094904	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094905	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094906	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094907	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094908	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094909	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094910	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094911	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094912	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094913	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094914	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094915	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094916	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094917	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094918	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094919	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094920	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094921	Soil		3.4	40.1	20.2	159	0.1	46.3	17.8	345	2.95	69.0	2.3	1.1	20	0.6	2.1	0.2	27	0.02	0.052	4
1094922	Soil		3.4	47.5	24.8	174	0.1	41.2	18.2	327	3.26	53.3	1.2	1.0	17	0.3	1.6	0.4	23	0.02	0.065	4
1094923	Soil		4.5	24.6	29.9	82	0.3	21.4	7.1	107	1.71	90.4	21.3	0.7	50	0.3	3.6	0.3	36	0.02	0.044	3
1094924	Soil		7.7	26.0	124.1	43	1.6	8.9	2.1	28	1.02	50.2	117.1	0.7	88	0.2	12.5	0.3	88	0.02	0.070	4
1094925	Soil		15.9	41.8	240.6	17	3.3	4.2	0.6	33	1.20	67.3	106.7	1.1	119	0.1	20.8	0.3	187	0.03	0.119	7
1094926	Soil		2.6	13.9	25.7	18	0.9	3.3	0.6	13	0.61	28.7	44.4	0.6	67	<0.1	6.2	0.3	35	0.02	0.050	3
1094927	Soil		3.8	19.5	35.0	14	1.1	2.7	0.4	17	0.85	47.9	51.6	0.7	87	<0.1	12.0	0.3	72	0.03	0.081	3
1094928	Soil		5.5	12.2	19.0	10	0.7	2.7	0.6	27	0.68	56.1	33.1	0.5	98	<0.1	9.9	0.2	68	0.03	0.080	3
1094929	Soil		5.0	29.9	15.3	35	0.4	10.4	1.8	59	1.40	248.3	15.8	0.7	34	<0.1	7.2	0.3	67	0.04	0.085	4
1094930	Soil		6.1	22.1	18.9	34	0.4	8.7	1.5	39	1.34	73.4	7.7	0.8	42	<0.1	4.5	0.3	65	0.03	0.084	4
1094931	Soil		5.4	15.1	14.3	30	0.4	10.3	1.4	50	1.36	98.1	6.6	1.3	33	<0.1	4.8	0.3	79	0.03	0.071	5
1094932	Soil		5.4	105.4	16.3	351	0.9	73.6	26.2	686	4.19	79.2	4.1	2.7	37	1.0	4.7	0.3	77	0.03	0.098	3
1094933	Soil		6.2	51.6	20.7	80	0.6	21.3	4.8	134	2.22	143.8	6.4	1.7	33	0.2	6.7	0.3	65	0.03	0.082	3
1094934	Soil		6.7	33.6	22.7	46	0.7	11.4	1.4	53	1.80	205.1	7.2	0.9	44	0.1	7.7	0.3	66	0.02	0.080	3
1094935	Soil		7.7	66.1	12.7	179	0.8	36.0	10.8	450	2.78	82.7	6.8	0.8	17	0.4	4.1	0.3	54	0.02	0.114	3
1094936	Soil		4.6	17.5	5.5	59	0.1	13.4	3.4	114	1.07	27.4	3.4	0.1	13	0.3	1.7	0.1	35	0.05	0.073	2
1094937	Soil		11.0	41.9	42.1	132	0.7	29.2	10.8	520	3.14	95.9	21.6	0.8	50	0.5	5.7	0.5	55	0.02	0.109	2
1094938	Soil		149.2	250.9	23.0	1137	4.9	256.3	14.7	316	3.03	218.3	111.1	0.9	66	20.4	72.1	0.3	980	0.46	0.173	12
1094939	Soil		89.7	92.8	16.3	217	3.8	47.4	1.5	16	2.13	92.6	51.5	0.1	62	2.4	32.6	0.2	477	0.03	0.154	8
1094940	Soil		181.4	283.4	28.8	7099	4.4	665.7	15.9	350	2.93	445.7	50.4	1.6	270	39.8	92.1	0.3	1740	7.62	0.205	16
1094941	Soil		26.9	230.6	26.6	762	2.5	153.0	24.5	493	6.04	123.1	21.1	7.5	73	6.7	10.9	0.3	112	1.12	0.139	14
1094942	Soil		36.4	190.2	33.0	621	3.0	162.3	27.3	395	6.22	128.0	17.1	5.5	108	3.7	10.2	0.3	124	1.16	0.148	12
1094943	Soil		53.6	136.3	15.4	908	1.8	198.5	12.6	257	2.58	85.4	16.2	0.9	101	10.0	12.7	0.2	319	2.29	0.131	11
1094944	Soil		11.5	64.5	11.1	198	0.6	41.8	11.0	131	2.94	88.1	2.0	0.4	17	0.7	5.0	0.1	55	0.10	0.143	4
1094945	Soil		13.3	100.1	20.3	252	0.8	65.1	22.6	567	5.06	272.9	20.6	1.7	27	1.8	7.7	0.3	75	0.22	0.186	12
1094946	Soil		94.7	171.3	17.9	2494	2.3	339.3	10.7	243	2.03	105.1	2.4	1.2	185	22.9	34.2	0.2	871	5.62	0.115	15
1094947	Soil		98.8	159.6	16.9	1048	1.9	347.1	14.9	314	2.63	99.6	1.9	2.0	195	15.1	24.8	0.2	525	2.78	0.140	18
1094948	Soil		82.4	111.0	13.3	2255	2.3	271.2	7.1	116	1.73	81.6	5.0	1.2	135	15.4	27.1	0.2	970	3.20	0.142	20
1094949	Soil		67.2	81.1	13.4	1518	1.4	187.8	4.5	56	1.35	67.5	3.1	0.4	52	12.1	26.1	0.2	1129	0.64	0.108	16
1094950	Soil		24.7	44.1	7.2	361	0.5	87.8	5.2	334	1.05	26.3	<0.5	0.3	58	8.9	8.5	<0.1	209	1.33	0.093	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094921	Soil	8	0.06	108	<0.001	12	0.54	0.004	0.05	<0.1	0.18	3.6	0.2	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094922	Soil	5	0.06	146	<0.001	<1	0.51	0.005	0.07	<0.1	0.20	3.3	0.3	0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094923	Soil	9	0.02	460	<0.001	1	0.33	0.003	0.06	<0.1	0.64	2.2	0.4	<0.05	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094924	Soil	14	0.02	1061	0.001	3	0.36	0.003	0.08	0.1	2.72	1.7	0.8	<0.05	2	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094925	Soil	23	0.02	1921	0.002	4	0.48	0.005	0.13	0.3	5.94	1.8	1.5	0.27	3	12.3	0.3	N.A.	N.A.	N.A.	N.A.
1094926	Soil	11	0.01	832	<0.001	4	0.26	0.002	0.09	<0.1	2.64	1.4	0.6	0.07	2	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094927	Soil	18	0.01	1296	0.001	4	0.33	0.004	0.12	<0.1	5.45	1.1	0.9	0.13	2	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094928	Soil	16	0.01	994	0.002	2	0.29	0.005	0.08	<0.1	2.15	1.3	0.5	0.07	2	6.9	<0.2	N.A.	N.A.	N.A.	N.A.
1094929	Soil	15	0.04	516	0.003	2	0.53	0.006	0.08	<0.1	0.73	2.7	0.4	0.06	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094930	Soil	18	0.05	555	0.003	2	0.50	0.004	0.09	<0.1	0.34	2.7	0.5	0.10	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094931	Soil	14	0.04	388	0.003	2	0.51	0.002	0.07	<0.1	0.23	1.6	0.3	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094932	Soil	18	0.06	753	<0.001	2	0.57	0.002	0.08	<0.1	0.23	7.0	0.5	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1094933	Soil	18	0.03	700	0.001	2	0.51	0.002	0.10	<0.1	0.17	4.4	0.5	0.10	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1094934	Soil	18	0.02	509	<0.001	3	0.45	0.002	0.10	<0.1	0.26	3.5	0.6	0.18	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094935	Soil	18	0.04	213	0.002	2	0.51	0.004	0.07	<0.1	0.26	3.4	0.3	0.08	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094936	Soil	7	0.02	132	0.002	2	0.16	0.011	0.06	<0.1	0.19	0.5	0.1	0.09	<1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1094937	Soil	12	0.02	380	0.001	4	0.40	0.002	0.12	<0.1	1.12	1.6	0.7	0.23	2	2.9	0.2	N.A.	N.A.	N.A.	N.A.
1094938	Soil	56	0.10	531	0.004	7	0.94	0.005	0.14	1.5	6.23	2.7	6.7	0.27	4	16.3	0.6	N.A.	N.A.	N.A.	N.A.
1094939	Soil	30	0.02	263	0.001	4	0.56	0.003	0.11	0.8	3.33	0.3	4.9	0.33	3	10.6	0.4	N.A.	N.A.	N.A.	N.A.
1094940	Soil	75	0.88	730	0.011	11	0.68	0.002	0.17	1.2	5.48	4.2	11.8	0.14	4	18.6	0.4	N.A.	N.A.	N.A.	N.A.
1094941	Soil	15	0.28	399	0.004	5	0.39	0.002	0.13	0.1	1.92	8.5	1.0	0.08	1	6.8	<0.2	N.A.	N.A.	N.A.	N.A.
1094942	Soil	16	0.46	872	0.003	7	0.48	0.002	0.16	0.2	0.75	8.5	1.1	0.11	1	8.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094943	Soil	26	0.29	576	0.003	7	0.45	0.002	0.09	0.5	1.45	2.5	1.3	0.12	2	6.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094944	Soil	8	0.04	159	0.003	3	0.45	0.009	0.10	0.2	0.17	0.6	0.4	0.09	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1094945	Soil	12	0.07	278	0.004	4	0.50	0.003	0.12	0.2	0.74	2.6	0.5	0.07	1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1094946	Soil	44	1.79	323	0.006	6	0.52	0.006	0.11	0.5	0.63	2.9	5.5	0.08	3	8.6	<0.2	N.A.	N.A.	N.A.	N.A.
1094947	Soil	43	0.66	339	0.004	7	0.58	0.003	0.10	0.6	0.55	5.6	5.9	0.06	2	5.5	0.3	N.A.	N.A.	N.A.	N.A.
1094948	Soil	54	1.27	285	0.006	7	0.63	0.006	0.14	0.5	1.02	4.2	5.7	0.09	3	7.5	0.3	N.A.	N.A.	N.A.	N.A.
1094949	Soil	60	0.13	348	0.006	5	0.91	0.010	0.11	0.4	0.58	1.4	3.9	0.07	3	6.4	0.2	N.A.	N.A.	N.A.	N.A.
1094950	Soil	24	0.36	262	0.006	3	0.54	0.010	0.06	0.2	0.33	1.4	1.6	0.12	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094921	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094922	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094923	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094924	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094925	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094926	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094927	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094928	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094929	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094930	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094931	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094932	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094933	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094934	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094935	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094936	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094937	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094938	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094939	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094940	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094941	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094942	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094943	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094944	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094945	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094946	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094947	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094948	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094949	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094950	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094921	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094922	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094923	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094924	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094925	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094926	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094927	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094928	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094929	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094930	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094931	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094932	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094933	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094934	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094935	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094936	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094937	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094938	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094939	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094940	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094941	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094942	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094943	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094944	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094945	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094946	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094947	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094948	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094949	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094950	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276131	Soil		16.8	50.7	62.7	150	0.6	43.3	5.0	56	2.69	33.5	2.4	0.1	145	0.4	5.3	0.4	91	0.06	0.351	19
1276132	Soil		23.6	165.4	194.4	274	2.1	89.3	23.8	387	4.61	60.0	14.0	3.7	327	1.7	10.2	0.9	90	0.49	0.914	38
1276133	Soil		3.3	47.1	31.6	182	1.2	57.2	10.3	262	3.33	39.6	19.6	2.0	104	0.9	2.0	0.2	37	0.73	0.129	5
1276134	Soil		3.4	65.6	32.9	239	1.2	83.5	14.1	335	3.70	44.0	20.9	2.6	114	1.3	2.0	0.3	40	0.48	0.155	7
1276135	Soil		2.1	43.3	23.0	67	1.0	16.9	3.9	132	3.09	23.1	8.9	1.7	55	0.1	1.2	0.3	29	0.02	0.066	2
1276136	Soil		2.8	58.7	15.3	162	1.5	63.4	8.1	146	2.76	16.2	5.5	1.8	103	0.8	1.6	0.2	34	1.70	0.112	6
1276137	Soil		7.9	34.3	19.0	91	1.5	20.7	2.9	42	4.50	26.1	1.9	2.1	11	0.1	3.7	0.3	40	0.01	0.072	5
1276138	Soil		1.8	15.2	7.0	53	0.4	14.3	3.9	82	1.42	9.0	<0.5	0.3	51	0.6	0.8	0.1	24	0.31	0.052	4
1276139	Soil		4.7	45.1	22.5	943	0.7	176.5	15.4	638	2.33	23.3	1.3	1.6	197	3.6	7.2	0.2	56	1.64	0.207	7
1276140	Soil		5.2	51.6	24.0	971	0.7	184.1	21.1	621	2.57	23.9	2.4	1.6	151	4.3	7.0	0.2	52	1.33	0.172	6
1276331	Soil		4.3	38.2	15.1	487	0.4	79.5	11.5	306	2.09	16.9	3.6	1.9	85	3.9	4.4	0.2	55	1.18	0.135	6
1276332	Soil		5.6	34.5	15.2	579	0.3	91.7	11.7	210	2.61	18.7	1.2	2.3	108	2.7	5.5	0.2	56	1.35	0.154	7
1276333	Soil		3.2	24.4	12.0	544	0.2	68.0	11.0	352	2.47	15.0	0.6	1.2	66	2.2	3.8	0.2	42	0.97	0.084	4
1276334	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1276335	Soil		4.4	40.9	2.8	931	0.3	175.7	38.2	2204	0.96	1.0	<0.5	0.2	143	8.4	4.6	<0.1	13	2.84	0.117	2
1276336	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1276337	Soil		5.5	45.5	13.0	147	0.7	34.2	7.4	228	2.51	17.2	4.9	1.6	44	0.7	2.7	0.2	53	0.39	0.101	6
1276338	Soil		5.8	55.1	14.2	161	0.6	37.3	7.1	238	2.88	19.3	6.7	1.8	47	1.0	3.0	0.3	57	0.33	0.126	8
1276339	Soil		4.8	51.4	12.4	117	0.8	34.0	6.6	396	2.38	14.0	6.5	1.7	58	0.9	2.4	0.2	59	0.58	0.101	8
1276340	Soil		5.7	43.9	11.3	124	1.0	34.9	6.7	447	2.53	16.0	5.4	1.3	48	0.7	2.6	0.2	63	0.53	0.115	6
1276341	Soil		2.5	53.2	15.3	161	0.9	47.5	7.2	345	3.41	16.6	8.7	1.2	63	0.9	1.3	0.2	42	0.94	0.109	5
1276342	Soil		1.3	34.4	6.5	47	3.1	18.6	1.9	39	1.12	4.8	6.4	0.5	26	0.4	0.4	0.1	29	0.22	0.145	4
1276343	Soil		1.8	26.6	7.9	75	0.9	19.8	4.8	229	1.38	6.6	4.1	0.8	46	1.0	0.7	<0.1	32	0.32	0.075	4
1276344	Soil		3.8	28.5	17.4	112	0.2	21.5	4.9	142	3.17	21.5	1.9	1.2	12	0.4	2.0	0.4	61	0.07	0.093	6
1276345	Soil		1.3	9.1	4.3	27	0.9	7.1	1.3	26	0.64	4.5	1.0	0.2	7	0.2	0.5	0.2	21	0.03	0.032	3
1276346	Soil		3.6	21.7	11.2	58	1.2	10.7	2.5	84	2.41	14.5	1.4	0.3	13	0.3	1.4	0.4	39	0.08	0.070	3
1276347	Soil		3.8	22.4	12.4	99	0.2	17.1	3.3	79	1.75	18.8	1.7	0.5	27	0.4	1.7	0.3	49	0.25	0.049	6
1276348	Soil		3.0	50.1	12.6	638	1.8	46.0	12.3	2484	2.61	17.5	2.1	0.5	77	7.8	1.7	0.3	33	1.91	0.114	4
1276349	Soil		2.1	13.0	10.7	57	0.2	13.6	4.1	322	1.23	13.0	2.0	0.5	44	1.2	0.8	0.2	35	0.71	0.046	6
1276350	Soil		1.6	25.2	7.0	67	0.4	20.3	4.7	304	1.13	5.2	1.8	0.5	81	0.5	1.2	0.2	26	2.16	0.093	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276131	Soil		18	0.03	311	0.002	<1	0.55	0.003	0.08	0.1	0.07	0.2	0.3	0.19	4	4.1	0.2	N.A.	N.A.	N.A.	N.A.
1276132	Soil		27	0.04	511	0.010	4	0.70	0.006	0.29	0.1	0.63	3.1	0.6	0.50	3	15.0	0.4	N.A.	N.A.	N.A.	N.A.
1276133	Soil		26	0.14	844	<0.001	5	0.89	0.006	0.12	<0.1	0.49	3.5	0.2	0.17	2	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276134	Soil		29	0.12	1149	0.001	5	0.85	0.004	0.15	<0.1	0.69	4.9	0.2	0.16	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276135	Soil		25	0.09	216	<0.001	2	0.89	0.005	0.09	<0.1	0.15	1.8	0.2	0.13	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276136	Soil		21	0.10	731	<0.001	6	0.81	0.007	0.11	<0.1	0.21	3.6	0.2	0.25	2	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276137	Soil		18	0.13	139	0.002	1	0.76	0.003	0.05	<0.1	0.05	1.2	0.3	<0.05	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1276138	Soil		8	0.08	187	0.003	1	0.58	0.017	0.03	<0.1	0.04	0.6	0.1	0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276139	Soil		17	0.27	877	0.004	4	0.63	0.006	0.07	0.1	0.22	2.5	0.4	0.12	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276140	Soil		20	0.30	839	0.004	5	0.74	0.005	0.08	<0.1	0.23	2.8	0.3	0.12	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276331	Soil		15	0.25	845	0.003	5	0.72	0.008	0.08	<0.1	0.19	2.5	0.3	0.10	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276332	Soil		15	0.33	1067	0.003	4	0.76	0.006	0.07	0.2	0.14	2.2	0.3	0.09	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276333	Soil		14	0.26	406	0.002	4	0.79	0.012	0.04	<0.1	0.15	1.8	0.3	0.11	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276334	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.3	26.6	4.5	500
1276335	Soil		6	0.12	561	0.007	10	0.58	0.017	0.02	<0.1	0.08	0.5	0.2	0.29	1	9.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276336	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	5.5	23.8	2.7	474
1276337	Soil		19	0.20	1990	0.002	3	0.88	0.009	0.08	0.1	0.27	1.9	0.2	0.07	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276338	Soil		21	0.23	2109	0.003	2	0.93	0.006	0.09	0.1	0.30	2.3	0.2	0.07	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276339	Soil		21	0.22	2455	0.002	4	1.09	0.007	0.09	0.1	0.47	2.8	0.2	0.08	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276340	Soil		21	0.20	1489	0.003	5	1.06	0.011	0.09	0.1	0.44	2.2	0.2	0.08	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276341	Soil		21	0.26	737	0.002	5	1.26	0.009	0.08	<0.1	0.54	2.9	0.2	0.12	3	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276342	Soil		15	0.09	953	0.002	2	0.90	0.012	0.06	<0.1	0.52	2.5	0.2	0.11	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276343	Soil		16	0.17	633	0.002	3	0.75	0.006	0.06	<0.1	0.35	1.9	0.1	0.07	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276344	Soil		16	0.10	163	0.003	3	0.81	0.004	0.05	0.1	0.04	1.7	0.2	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276345	Soil		5	0.02	144	0.011	3	0.49	0.018	0.03	<0.1	0.05	0.7	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276346	Soil		11	0.04	200	0.004	3	0.51	0.009	0.05	0.1	0.05	0.8	<0.1	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276347	Soil		10	0.07	341	0.002	2	0.51	0.007	0.05	0.1	0.03	1.0	0.1	<0.05	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1276348	Soil		19	0.30	368	0.006	4	0.91	0.008	0.05	0.1	0.25	1.8	0.1	0.08	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276349	Soil		12	0.21	315	0.009	2	0.71	0.010	0.03	0.1	0.06	1.3	<0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276350	Soil		11	0.13	563	0.005	4	0.78	0.015	0.04	0.1	0.15	1.2	<0.1	0.07	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276331	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276332	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276333	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276334	Soil	0.2	75.9	7.5	651	0.95	3.3	2.6	0.2	158	2.2	2.7	<0.1	14	3.02	0.097	1	7	0.27	355	0.004
1276335	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276336	Soil	0.1	84.3	14.7	3131	0.97	1.6	2.7	0.1	138	3.6	3.0	<0.1	8	2.15	0.100	2	5	0.11	466	0.006
1276337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276338	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276340	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276341	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276342	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276343	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276344	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276345	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276346	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276347	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276348	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276349	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276350	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276131	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276132	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276133	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276134	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276135	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276136	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276137	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276138	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276139	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276140	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276331	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276332	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276333	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276334	Soil	<20	0.31	0.013	0.02	<0.1	0.10	0.6	<0.1	0.54	<1	2.5	<0.2
1276335	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276336	Soil	<20	0.57	0.016	0.02	<0.1	0.10	0.5	0.1	0.32	<1	3.7	<0.2
1276337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276338	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276340	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276341	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276342	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276343	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276344	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276345	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276346	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276347	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276348	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276349	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276350	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277691	Soil		2.2	57.2	17.5	99	0.8	27.8	9.1	341	3.07	11.9	4.8	1.0	30	0.2	1.0	0.3	29	0.03	0.113	3
1277692	Soil		7.3	77.9	26.0	93	1.2	25.0	4.8	84	2.77	19.3	4.3	2.3	193	0.1	0.8	0.4	38	0.08	0.074	2
1277693	Soil		2.9	37.7	22.2	83	0.3	23.5	5.8	205	3.28	12.7	1.8	3.4	76	0.1	0.5	0.3	22	0.03	0.070	2
1277694	Soil		1.7	43.9	29.1	116	0.2	37.2	21.0	848	4.53	17.2	1.6	3.9	86	0.2	0.6	0.4	25	0.04	0.129	4
1277695	Soil		2.0	28.8	20.6	98	0.1	45.3	21.3	5549	7.31	17.8	1.9	3.1	31	0.2	0.7	0.4	34	0.04	0.130	5
1277696	Soil		1.8	18.3	16.0	54	<0.1	12.5	4.0	145	2.16	13.7	0.7	0.8	15	0.1	0.8	0.3	36	0.01	0.074	3
1277697	Soil		1.9	19.6	7.0	50	0.5	10.8	2.4	51	1.13	6.3	1.0	0.3	12	0.2	0.7	0.1	26	0.02	0.103	3
1277698	Soil		1.4	35.8	26.6	123	1.1	48.0	9.6	52	3.31	18.5	1.4	2.5	64	0.3	0.7	0.3	25	0.10	0.062	2
1277699	Soil		2.5	53.2	24.7	156	1.2	46.7	12.1	297	4.10	20.7	3.6	2.0	27	0.4	1.3	0.4	33	0.02	0.101	3
1277700	Soil		1.2	18.0	8.0	35	0.5	10.6	2.0	94	1.13	5.7	2.3	0.3	11	0.2	0.6	0.1	19	0.02	0.050	3
1277701	Soil		2.1	17.1	9.1	81	0.8	18.1	3.5	68	1.51	7.6	2.2	0.2	15	0.2	0.8	0.2	33	0.03	0.082	5
1277702	Soil		2.2	19.5	8.9	73	0.3	19.9	3.6	47	1.33	7.8	2.1	0.2	10	0.2	0.8	0.2	36	0.01	0.052	6
1277703	Soil		11.6	48.6	14.5	96	0.8	34.9	4.3	65	3.53	34.7	2.7	0.4	9	0.1	1.9	0.3	106	0.01	0.081	5
1277704	Soil		2.4	19.3	10.0	59	0.4	11.7	2.1	25	1.36	10.7	1.0	0.6	6	0.2	0.6	0.2	39	<0.01	0.063	3
1277705	Soil		4.1	8.1	9.4	29	0.7	4.9	1.0	16	0.70	6.7	1.4	1.8	8	<0.1	0.6	0.2	30	0.01	0.050	14
1277706	Soil		47.5	33.1	17.2	23	5.9	4.5	0.9	130	2.42	55.4	1.6	1.2	72	0.6	34.0	0.3	607	0.04	0.149	9
1277707	Soil		28.2	14.1	10.7	83	1.4	14.5	1.6	23	1.05	13.7	1.8	0.2	20	0.2	8.8	0.2	254	0.02	0.050	12
1277708	Soil		33.4	26.4	15.2	98	0.5	21.5	2.2	28	1.48	18.2	2.4	0.5	27	0.6	7.1	0.2	207	0.15	0.080	10
1277709	Soil		25.3	25.4	13.7	112	0.6	27.0	3.8	149	1.71	16.4	2.5	1.0	44	1.0	6.2	0.2	161	0.32	0.077	9
1277710	Soil		18.3	38.9	12.7	156	0.9	44.4	5.3	117	2.02	17.0	3.8	1.3	67	1.0	5.5	0.2	152	1.25	0.108	7
1277711	Soil		28.6	54.6	25.1	1590	0.6	279.8	29.9	1657	3.91	33.1	3.4	1.4	41	14.7	6.0	0.2	110	0.41	0.111	9
1277712	Soil		3.1	11.8	6.7	55	0.5	13.5	2.8	60	0.96	5.3	1.8	0.2	24	0.2	0.8	0.1	31	0.38	0.039	7
1277713	Soil		0.8	10.0	2.6	26	1.2	8.2	1.6	24	0.49	2.0	<0.5	<0.1	9	0.1	0.3	<0.1	10	0.15	0.028	3
1277714	Soil		0.2	1.6	0.7	6	0.6	1.1	0.5	7	0.15	<0.5	<0.5	<0.1	5	<0.1	<0.1	<0.1	5	0.02	0.013	<1
1277715	Soil		4.7	19.4	15.4	78	0.1	18.4	4.4	99	1.90	13.4	<0.5	0.8	12	0.2	1.4	0.2	57	0.03	0.044	13
1277716	Soil		2.1	34.2	12.0	87	1.2	26.8	4.1	94	1.58	6.1	1.8	1.0	56	1.0	0.8	0.2	38	0.37	0.094	11
1277717	Soil		3.4	21.3	6.1	57	1.8	10.7	1.3	20	1.00	6.5	1.8	0.2	10	0.2	0.9	<0.1	27	0.09	0.053	5
1277718	Soil		4.6	13.1	24.0	67	0.5	13.6	3.0	64	1.24	12.0	1.5	0.2	14	0.2	1.2	0.3	59	0.02	0.058	13
1277719	Soil		5.6	36.1	28.3	81	0.6	24.6	6.2	149	1.87	14.1	2.6	0.6	31	0.3	1.4	0.3	51	0.17	0.180	13
1277720	Soil		3.9	9.5	11.9	40	0.2	9.1	1.9	36	1.14	9.0	1.3	0.4	8	0.1	1.0	0.2	52	0.02	0.059	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277691	Soil	26	0.24	283	0.005	4	1.10	0.011	0.07	<0.1	0.06	3.0	0.1	0.06	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277692	Soil	23	0.13	1053	0.001	4	0.70	0.023	0.10	<0.1	0.19	3.6	0.1	0.23	2	6.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277693	Soil	23	0.33	659	0.002	2	1.16	0.013	0.08	<0.1	0.07	3.6	0.1	0.13	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277694	Soil	28	0.48	226	0.003	2	1.56	0.013	0.09	<0.1	0.05	5.6	0.2	0.11	5	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277695	Soil	29	0.38	267	0.003	2	1.73	0.006	0.07	<0.1	0.08	4.3	0.1	0.05	5	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277696	Soil	11	0.06	78	0.005	2	0.62	0.007	0.04	<0.1	0.02	1.2	0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277697	Soil	10	0.03	214	0.003	2	0.56	0.008	0.04	<0.1	0.05	0.7	<0.1	0.08	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277698	Soil	28	0.09	781	0.001	3	1.04	0.005	0.09	<0.1	0.11	4.6	0.1	0.06	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277699	Soil	27	0.09	325	0.002	3	1.14	0.005	0.11	<0.1	0.06	3.3	0.1	0.07	4	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277700	Soil	8	0.03	104	0.008	3	0.56	0.016	0.05	<0.1	0.06	0.7	<0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277701	Soil	12	0.04	180	0.006	3	0.43	0.005	0.06	<0.1	0.06	0.5	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277702	Soil	10	0.02	97	0.004	3	0.36	0.006	0.04	0.1	0.01	0.4	<0.1	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277703	Soil	21	0.02	119	0.004	3	0.50	0.004	0.05	0.1	0.06	1.0	0.1	<0.05	3	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277704	Soil	10	0.02	113	0.003	3	0.52	0.006	0.04	<0.1	0.02	1.1	<0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277705	Soil	6	0.02	94	0.001	3	0.51	0.003	0.05	0.1	0.08	0.7	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277706	Soil	33	0.04	437	0.006	3	0.76	0.010	0.16	1.8	0.17	1.1	12.3	0.32	5	16.1	0.3	N.A.	N.A.	N.A.	N.A.
1277707	Soil	14	0.03	131	0.006	2	0.42	0.005	0.05	0.4	0.03	0.5	1.7	<0.05	3	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277708	Soil	18	0.05	341	0.003	3	0.55	0.005	0.08	0.3	0.12	1.1	1.4	0.06	3	4.9	0.2	N.A.	N.A.	N.A.	N.A.
1277709	Soil	19	0.09	1688	0.003	3	0.55	0.005	0.08	0.3	0.09	1.6	1.3	0.10	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277710	Soil	23	0.12	595	0.002	5	0.81	0.006	0.08	0.2	0.19	2.7	0.7	0.05	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277711	Soil	14	0.12	797	0.002	3	0.54	0.003	0.06	0.2	0.31	4.4	1.2	0.06	1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277712	Soil	7	0.06	770	0.004	3	0.48	0.015	0.06	0.2	0.05	0.7	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277713	Soil	4	0.04	446	0.005	2	0.32	0.025	0.03	<0.1	0.10	0.6	<0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277714	Soil	1	<0.01	19	0.007	<1	0.11	0.024	0.02	<0.1	<0.01	0.3	<0.1	<0.05	<1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277715	Soil	9	0.05	434	0.003	2	0.66	0.004	0.06	<0.1	0.01	1.0	0.2	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277716	Soil	15	0.16	2463	0.004	2	1.05	0.005	0.08	0.2	0.09	1.8	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277717	Soil	7	0.02	548	0.003	3	0.30	0.012	0.05	<0.1	0.08	0.5	<0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277718	Soil	11	0.05	141	0.005	2	0.58	0.004	0.08	0.1	0.03	0.4	0.2	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277719	Soil	13	0.07	429	0.003	2	0.77	0.005	0.10	0.1	0.09	0.6	0.2	0.07	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277720	Soil	9	0.04	146	0.006	4	0.60	0.006	0.07	0.1	<0.01	0.4	0.2	<0.05	4	0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277691	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277692	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277693	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277694	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277695	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277696	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277697	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277698	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277699	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277700	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277701	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277702	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277703	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277704	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277705	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277706	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277707	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277708	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277709	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277710	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277711	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277712	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277713	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277714	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277715	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277716	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277717	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277718	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277719	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277720	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277691	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277692	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277693	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277694	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277695	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277696	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277697	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277698	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277699	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277700	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277701	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277702	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277703	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277704	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277705	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277706	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277707	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277708	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277709	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277710	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277711	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277712	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277713	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277714	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277715	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277716	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277717	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277718	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277719	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277720	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277721	Soil		1.7	17.5	3.2	23	<0.1	5.6	1.5	37	1.00	3.6	0.7	1.4	3	<0.1	0.6	0.2	34	0.01	0.021	10
1277722	Soil		1.8	6.8	4.1	14	<0.1	3.7	0.9	16	0.36	3.3	1.3	<0.1	4	<0.1	0.3	<0.1	24	0.02	0.036	7
1277723	Soil		7.1	64.8	14.4	84	0.4	23.9	8.4	90	2.24	24.8	1.8	1.2	8	0.3	2.2	0.2	62	0.02	0.038	14
1277724	Soil		63.1	19.3	26.6	98	1.0	15.1	1.4	18	1.80	26.2	0.9	0.8	25	1.1	3.6	0.2	290	0.03	0.050	24
1277725	Soil		152.7	127.1	21.8	2730	2.2	296.5	6.4	119	2.23	93.1	5.3	2.7	125	36.0	40.7	0.2	2534	1.94	0.097	30
1277726	Soil		9.3	44.3	11.7	302	0.7	54.0	4.8	155	1.38	14.7	3.0	0.8	111	8.8	4.5	0.2	244	1.73	0.097	11
1277727	Soil		5.1	44.4	5.9	124	0.8	36.6	4.3	343	1.20	8.5	4.9	0.4	67	1.8	2.2	0.1	44	1.47	0.084	5
1277728	Soil		9.3	61.1	14.6	260	0.9	55.6	8.9	343	2.37	18.1	6.4	1.7	48	1.6	3.2	0.2	83	0.75	0.121	11
1277729	Soil		4.1	38.9	9.8	1623	0.8	143.8	12.2	455	1.43	11.8	4.6	0.8	92	10.3	1.8	0.2	88	4.27	0.129	6
1277730	Soil		13.7	49.4	15.0	380	0.9	64.3	10.0	443	2.34	20.7	4.6	1.4	45	2.6	3.2	0.2	73	0.61	0.140	11
1277731	Soil		16.9	50.6	13.4	273	0.7	71.8	9.3	450	2.39	21.2	3.7	1.9	44	2.4	3.0	0.2	69	0.67	0.117	12
1277732	Soil		8.8	54.6	13.8	232	1.3	67.2	10.7	385	2.64	17.5	4.7	1.4	51	2.6	2.0	0.2	71	0.81	0.120	9
1277733	Soil		9.7	48.4	16.7	233	1.7	57.6	22.3	1360	2.77	17.9	5.4	1.5	40	2.4	2.2	0.2	81	0.41	0.122	9
1277734	Soil		6.0	28.6	9.0	95	0.8	30.2	3.7	98	1.44	13.2	2.8	0.3	30	1.9	1.4	0.1	37	0.46	0.119	6
1277735	Soil		4.1	19.0	10.1	83	0.6	28.7	1.9	20	0.76	7.8	1.7	1.0	21	1.9	1.0	0.1	33	0.18	0.048	7
1277736	Soil		2.5	21.0	13.3	24	0.1	7.8	0.9	11	1.66	142.3	9.6	1.0	43	<0.1	5.2	0.2	38	0.02	0.048	5
1277737	Soil		1.1	17.2	8.1	21	0.2	6.8	0.9	10	1.20	64.4	1.0	1.0	26	<0.1	2.4	0.1	18	0.01	0.039	3
1277738	Soil		3.6	37.0	10.0	76	1.4	18.0	4.0	89	3.23	29.8	4.6	0.7	29	0.2	2.1	0.2	49	0.04	0.072	8
1277739	Soil		2.8	27.6	12.0	66	0.7	18.3	4.5	55	2.02	14.1	3.3	0.2	20	0.2	0.8	0.2	32	0.03	0.198	4
1277740	Soil		2.5	52.2	18.9	157	1.5	53.3	12.2	179	3.58	15.7	3.2	2.4	39	0.3	0.8	0.2	29	0.02	0.149	3
1277741	Soil		3.7	81.5	22.7	175	2.2	57.9	15.2	164	3.38	16.0	4.6	1.2	57	0.3	0.9	0.2	26	0.04	0.151	3
1277742	Soil		2.7	71.4	31.9	218	4.5	83.7	26.5	809	4.27	19.8	2.3	3.8	73	0.4	0.9	0.3	25	0.11	0.089	3
1277743	Soil		2.2	69.1	25.9	171	2.9	68.2	22.4	566	3.53	17.0	2.6	2.7	88	0.4	0.8	0.3	22	0.16	0.093	4
1277744	Soil		2.5	68.5	29.2	174	2.5	69.0	24.7	708	3.82	16.5	2.9	2.7	80	0.4	0.8	0.3	27	0.10	0.104	3
1277745	Soil		2.3	62.0	28.5	158	2.1	59.1	27.1	899	3.63	14.8	2.6	2.3	57	0.4	0.8	0.3	27	0.06	0.117	3
1277746	Soil		1.5	24.1	9.3	43	0.4	12.1	3.2	94	1.10	5.3	1.8	0.3	16	0.2	0.6	0.1	20	0.06	0.078	3
1277747	Soil		2.4	67.5	19.3	117	0.6	38.8	12.5	665	3.46	11.2	4.5	1.4	106	0.2	1.1	0.3	31	0.07	0.152	5
1277748	Soil		2.5	63.6	18.4	122	0.8	40.5	10.5	578	3.69	12.0	5.0	1.1	60	0.3	1.3	0.3	39	0.12	0.158	7
1277749	Soil		2.7	69.8	26.0	145	0.5	50.7	24.0	1184	3.31	13.3	3.8	2.3	56	0.2	1.2	0.3	32	0.06	0.094	7
1277750	Soil		4.5	82.3	26.4	149	2.2	66.4	14.1	487	3.61	17.3	9.3	2.0	72	0.2	1.4	0.3	35	0.30	0.151	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277721	Soil	6	0.03	80	0.007	2	0.50	0.010	0.06	<0.1	<0.01	0.7	0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277722	Soil	6	0.02	106	0.003	<1	0.39	0.010	0.03	<0.1	0.01	0.2	0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277723	Soil	8	0.04	127	0.006	2	0.50	0.005	0.07	0.1	<0.01	1.1	0.2	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277724	Soil	13	0.04	367	0.002	4	0.36	0.012	0.27	0.2	0.05	0.7	2.7	0.52	2	10.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277725	Soil	121	0.83	858	0.013	11	1.59	0.005	0.22	0.5	0.61	4.1	4.4	<0.05	7	11.1	0.2	N.A.	N.A.	N.A.	N.A.
1277726	Soil	22	0.17	1063	0.003	6	0.76	0.006	0.09	0.1	0.22	1.5	0.7	0.09	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277727	Soil	10	0.13	1180	0.003	6	0.88	0.017	0.09	<0.1	0.25	1.1	0.2	0.09	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277728	Soil	20	0.18	1555	0.002	5	1.13	0.009	0.15	0.1	0.37	2.7	0.4	<0.05	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277729	Soil	15	0.21	798	0.002	7	0.67	0.005	0.09	<0.1	0.39	1.4	1.1	0.14	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277730	Soil	16	0.13	1753	0.002	4	0.86	0.004	0.09	0.1	0.26	2.3	0.6	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277731	Soil	16	0.12	1557	0.002	5	0.83	0.005	0.10	0.1	0.28	2.5	0.6	0.06	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277732	Soil	18	0.16	2236	0.002	3	1.34	0.010	0.11	0.1	0.41	2.9	0.5	0.08	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277733	Soil	21	0.16	2584	0.002	5	1.23	0.006	0.14	<0.1	0.45	3.0	0.5	0.06	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277734	Soil	11	0.09	769	0.003	3	0.56	0.012	0.05	<0.1	0.18	0.7	0.2	0.07	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277735	Soil	11	0.05	290	0.002	2	0.43	0.007	0.05	<0.1	0.17	0.9	0.2	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277736	Soil	29	0.01	331	0.002	3	0.38	0.002	0.05	0.1	0.59	1.8	<0.1	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277737	Soil	13	0.01	252	0.001	4	0.39	0.002	0.06	<0.1	0.29	1.3	<0.1	<0.05	2	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277738	Soil	30	0.09	145	0.009	2	0.89	0.003	0.06	0.2	0.27	1.0	0.1	0.08	4	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277739	Soil	24	0.04	185	0.005	4	0.80	0.006	0.07	<0.1	0.11	0.6	0.1	0.14	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277740	Soil	34	0.16	260	0.002	3	1.37	0.004	0.09	<0.1	0.18	2.4	0.2	0.09	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277741	Soil	26	0.06	389	0.002	3	1.10	0.005	0.11	<0.1	0.16	2.2	0.2	0.12	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277742	Soil	30	0.35	433	0.001	4	1.34	0.008	0.11	<0.1	0.17	5.8	0.2	<0.05	3	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277743	Soil	30	0.31	584	0.001	4	1.27	0.007	0.11	<0.1	0.15	5.1	0.2	<0.05	3	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277744	Soil	34	0.34	560	0.001	4	1.39	0.007	0.12	<0.1	0.15	5.0	0.2	0.06	3	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277745	Soil	31	0.27	533	0.001	5	1.40	0.006	0.13	<0.1	0.14	3.9	0.2	0.05	4	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277746	Soil	12	0.05	200	0.007	1	0.49	0.017	0.05	<0.1	0.05	0.7	<0.1	0.06	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277747	Soil	33	0.22	1322	0.003	4	1.32	0.007	0.09	<0.1	0.23	1.5	0.2	0.15	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277748	Soil	38	0.21	1051	0.008	3	1.36	0.009	0.09	0.1	0.12	2.0	0.2	0.13	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277749	Soil	33	0.34	1165	0.004	4	1.29	0.007	0.07	<0.1	0.14	2.3	0.1	0.06	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277750	Soil	36	0.30	3672	0.005	6	1.51	0.009	0.09	<0.1	0.36	4.1	0.2	0.12	4	2.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277721	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277722	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277723	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277724	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277725	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277726	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277727	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277728	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277729	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277730	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277731	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277732	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277733	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277734	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277735	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277736	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277737	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277738	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277739	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277740	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277741	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277742	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277743	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277744	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277745	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277746	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277747	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277748	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277749	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277750	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277721	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277722	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277723	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277724	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277725	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277726	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277727	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277728	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277729	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277730	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277731	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277732	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277733	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277734	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277735	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277736	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277737	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277738	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277739	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277740	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277741	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277742	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277743	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277744	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277745	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277746	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277747	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277748	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277749	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277750	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277751	Soil	2.2	50.5	14.1	90	2.3	47.3	8.8	677	2.06	6.7	6.1	1.1	165	0.2	0.8	0.2	16	1.26	0.172	10
1277752	Soil	2.8	60.6	17.8	105	1.5	41.2	13.1	731	2.76	7.5	6.9	0.8	51	0.3	0.8	0.3	30	0.33	0.177	8
1277753	Soil	2.5	54.6	18.5	124	1.7	45.2	16.3	628	2.96	8.9	7.9	1.0	49	0.2	0.8	0.3	36	0.24	0.146	5
1277754	Soil	2.2	57.9	15.1	96	1.1	33.1	6.6	170	2.51	7.4	7.0	0.6	45	0.2	0.6	0.2	29	0.18	0.130	4
1277755	Soil	1.0	23.2	7.3	33	0.3	9.1	2.5	70	1.05	2.7	3.4	0.1	14	0.2	0.4	0.4	17	0.05	0.058	2
1277756	Soil	1.6	20.2	12.5	41	0.5	15.1	3.0	120	2.09	8.7	2.4	0.5	30	0.3	0.7	0.4	21	0.09	0.079	4
1277757	Soil	1.2	24.0	9.5	69	0.6	23.9	4.7	106	1.81	12.1	3.1	1.1	42	0.3	0.6	0.3	24	0.37	0.075	4
1277758	Soil	3.1	42.2	20.5	103	1.0	27.2	7.9	334	3.58	17.1	3.2	0.3	16	0.3	1.5	0.4	51	0.05	0.130	6
1277759	Soil	3.0	157.9	24.7	194	1.2	67.3	40.7	1437	4.84	15.5	7.0	1.8	89	0.2	1.8	0.3	37	0.08	0.130	4
1277760	Soil	1.9	123.4	14.3	50	1.5	17.2	7.1	242	2.00	7.8	9.3	0.3	22	0.2	0.8	0.3	20	0.06	0.131	4
1277761	Soil	3.9	141.3	47.9	195	1.7	69.8	65.7	2585	5.52	24.0	11.2	3.4	47	0.4	1.4	0.5	33	0.09	0.201	6
1277762	Soil	4.4	136.2	40.7	162	1.6	50.5	51.9	1997	5.68	18.5	11.6	2.9	19	0.2	1.5	0.4	40	0.04	0.212	8
1277763	Soil	4.4	141.7	45.4	174	1.9	64.9	50.6	2428	6.63	18.8	11.2	2.9	28	0.3	1.7	0.4	35	0.04	0.209	8
1277764	Soil	4.6	101.3	43.8	169	1.2	66.7	48.7	2432	5.03	21.8	12.5	3.3	56	0.4	2.0	0.4	31	0.20	0.146	9
1277765	Soil	2.7	63.4	23.1	130	0.6	58.1	17.0	875	3.06	12.4	7.6	2.1	88	<0.1	1.3	0.3	25	0.11	0.072	8
1277766	Soil	2.3	69.8	15.3	94	1.3	38.7	13.0	1071	2.10	7.1	7.3	1.3	82	<0.1	0.7	0.2	24	0.47	0.129	8
1277767	Soil	2.4	43.1	15.4	120	0.7	44.7	14.1	529	2.68	8.0	4.4	1.7	42	0.2	0.6	0.3	26	0.12	0.128	7
1277768	Soil	1.6	39.2	11.8	69	1.7	26.0	8.4	280	1.44	4.0	5.6	0.8	88	0.2	0.4	0.1	20	0.44	0.114	5
1277769	Soil	2.6	69.2	26.5	106	0.4	28.8	16.3	894	3.60	11.9	11.9	1.3	27	0.3	0.8	0.3	38	0.04	0.115	5
1277770	Soil	1.7	44.2	14.1	67	0.5	22.6	6.0	216	1.98	6.4	4.6	0.5	19	0.1	0.5	0.1	22	0.05	0.077	4
1277771	Soil	1.4	38.4	14.2	119	1.2	47.0	8.4	227	2.44	25.6	3.9	1.4	69	0.6	1.0	0.1	31	0.97	0.131	7
1277772	Soil	3.4	40.0	20.1	130	0.2	44.0	12.5	327	3.96	25.5	1.9	2.2	32	0.3	1.3	0.3	55	0.08	0.124	8
1277773	Soil	1.6	45.1	15.1	169	1.5	62.8	10.4	201	2.86	26.8	4.1	1.0	76	0.6	1.0	0.1	29	1.24	0.135	10
1277774	Soil	2.4	41.0	15.8	180	1.6	62.7	8.5	159	2.36	15.1	3.0	1.6	72	0.7	1.0	0.2	35	1.09	0.140	11
1277775	Soil	1.9	49.6	13.1	149	1.8	54.3	6.2	102	2.06	11.6	4.9	0.8	78	0.7	1.0	0.1	28	1.81	0.134	8
1277776	Soil	2.4	38.2	12.8	127	1.8	44.9	5.7	88	2.13	12.3	1.9	0.9	93	0.9	1.2	0.1	28	2.37	0.133	9
1277777	Soil	1.7	17.2	8.8	124	1.0	32.6	6.0	378	1.95	9.3	<0.5	0.4	89	1.2	0.8	<0.1	34	3.07	0.209	20
1277778	Soil	1.2	33.6	11.3	141	1.5	48.9	6.8	156	1.89	11.8	2.1	0.6	85	0.8	0.8	0.1	26	2.48	0.140	10
1277779	Soil	4.5	100.9	51.0	132	2.4	45.8	10.7	134	4.19	47.3	7.9	2.6	126	0.4	3.5	0.4	54	0.09	0.109	6
1277780	Soil	2.3	45.8	24.1	90	1.2	24.5	4.9	97	3.11	22.6	1.2	3.5	58	0.1	1.1	0.2	31	0.10	0.057	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277751	Soil	20	0.16	6192	0.004	7	0.98	0.008	0.06	<0.1	0.41	3.6	0.1	0.19	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277752	Soil	30	0.19	3577	0.006	4	1.45	0.007	0.07	<0.1	0.30	2.9	0.1	0.13	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277753	Soil	36	0.33	3427	0.006	5	1.67	0.007	0.09	0.1	0.26	2.6	0.2	0.10	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277754	Soil	38	0.23	2074	0.004	5	1.25	0.009	0.08	<0.1	0.18	2.0	0.1	0.16	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277755	Soil	16	0.09	190	0.011	2	0.60	0.020	0.03	<0.1	0.04	0.6	<0.1	<0.05	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277756	Soil	16	0.22	386	0.005	2	0.97	0.015	0.05	0.1	0.07	1.3	0.1	0.07	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277757	Soil	18	0.11	656	0.002	3	1.02	0.018	0.06	<0.1	0.14	2.4	0.1	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277758	Soil	31	0.18	199	0.010	3	1.25	0.004	0.08	0.2	0.16	1.0	0.1	0.08	5	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277759	Soil	37	0.41	390	0.004	2	1.86	0.009	0.06	<0.1	0.14	3.2	0.2	0.10	4	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277760	Soil	18	0.11	164	0.007	2	1.07	0.016	0.05	<0.1	0.16	1.2	0.1	0.10	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277761	Soil	35	0.39	376	0.005	4	1.74	0.007	0.11	<0.1	0.19	5.4	0.2	0.09	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277762	Soil	42	0.45	512	0.010	6	1.84	0.005	0.11	0.1	0.16	5.4	0.2	0.08	5	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277763	Soil	41	0.36	1403	0.006	4	1.61	0.005	0.09	<0.1	0.24	6.8	0.3	0.13	4	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277764	Soil	38	0.49	3550	0.006	5	1.70	0.005	0.09	<0.1	0.15	5.0	0.2	<0.05	4	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277765	Soil	30	0.43	2859	0.004	2	1.37	0.008	0.05	<0.1	0.10	3.2	<0.1	0.06	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277766	Soil	27	0.30	1033	0.006	3	1.40	0.011	0.05	<0.1	0.20	3.8	0.1	0.07	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277767	Soil	33	0.35	1010	0.005	3	1.32	0.006	0.07	<0.1	0.11	3.3	0.1	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277768	Soil	21	0.23	1028	0.005	3	0.99	0.015	0.06	<0.1	0.20	2.6	0.2	0.08	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277769	Soil	34	0.25	345	0.004	1	1.25	0.005	0.06	<0.1	0.06	1.9	0.1	<0.05	5	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277770	Soil	23	0.18	331	0.004	2	0.91	0.012	0.04	<0.1	0.06	1.3	<0.1	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277771	Soil	26	0.20	686	0.002	6	1.21	0.007	0.09	<0.1	0.20	3.4	0.2	0.07	3	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277772	Soil	38	0.33	750	0.006	3	1.78	0.006	0.11	0.2	0.05	3.2	0.2	<0.05	5	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277773	Soil	24	0.15	685	0.002	6	1.11	0.007	0.07	<0.1	0.21	2.4	0.1	0.11	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277774	Soil	23	0.09	573	0.003	4	1.00	0.011	0.06	<0.1	0.21	2.3	0.1	0.06	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277775	Soil	23	0.12	481	0.002	9	0.76	0.005	0.07	0.1	0.27	1.8	0.1	0.14	2	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277776	Soil	21	0.14	603	0.002	8	0.65	0.006	0.08	<0.1	0.29	1.6	0.2	0.16	2	6.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277777	Soil	24	0.14	562	0.005	7	0.64	0.005	0.05	0.1	0.19	0.9	0.1	0.18	1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277778	Soil	20	0.13	563	0.002	7	0.63	0.005	0.07	<0.1	0.23	1.3	0.1	0.15	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277779	Soil	32	0.14	368	0.003	3	1.17	0.007	0.11	0.1	0.31	4.8	0.2	0.09	4	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277780	Soil	22	0.14	599	0.005	3	0.70	0.008	0.17	0.1	0.14	3.4	0.2	0.31	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277751	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277752	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277753	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277754	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277755	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277756	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277757	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277758	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277759	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277760	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277761	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277762	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277763	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277764	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277765	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277766	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277767	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277768	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277769	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277770	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277771	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277772	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277773	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277774	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277775	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277776	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277777	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277778	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277779	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277780	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277751	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277752	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277753	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277754	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277755	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277756	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277757	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277758	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277759	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277760	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277761	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277762	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277763	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277764	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277765	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277766	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277767	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277768	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277769	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277770	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277771	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277772	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277773	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277774	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277775	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277776	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277777	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277778	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277779	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277780	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277781	Soil		3.5	46.0	18.5	139	1.1	48.4	9.1	317	3.40	53.9	6.5	1.0	69	0.3	2.4	0.2	52	0.07	0.143	9
1277782	Soil		3.1	40.5	16.0	130	0.8	40.1	8.6	242	3.00	34.3	4.6	1.2	52	0.5	1.9	0.1	46	0.21	0.100	9
1277783	Soil		2.4	26.6	12.5	102	0.9	29.3	5.6	142	2.41	16.1	8.3	0.6	38	0.3	1.1	<0.1	35	0.23	0.092	6
1277784	Soil		1.6	24.3	9.2	74	1.5	18.3	2.7	38	1.02	4.6	3.3	0.9	59	0.8	0.6	<0.1	13	1.39	0.133	3
1277785	Soil		2.2	25.7	10.4	86	0.4	22.2	4.4	93	1.92	11.1	1.6	0.1	20	0.5	0.9	<0.1	29	0.13	0.099	5
1277786	Soil		2.5	26.5	9.0	70	0.4	18.8	4.2	47	1.69	11.0	2.3	0.2	10	0.4	1.0	<0.1	46	0.02	0.083	8
1277787	Soil		1.9	35.5	13.1	89	1.0	32.7	5.5	158	2.12	15.5	7.4	1.2	52	0.3	0.9	<0.1	31	0.66	0.109	6
1277788	Soil		2.9	38.3	19.8	86	0.6	20.1	4.4	85	2.73	26.7	1.8	0.2	18	<0.1	1.1	0.3	33	0.03	0.145	4
1277789	Soil		9.1	43.4	14.3	33	3.9	9.3	2.0	47	1.58	14.0	3.9	0.9	31	0.1	6.6	<0.1	30	0.12	0.146	3
1277790	Soil		3.7	22.2	13.1	27	3.3	6.8	1.0	13	0.86	7.4	3.2	0.2	29	<0.1	2.6	<0.1	25	0.10	0.162	2
1277791	Soil		3.8	12.1	9.5	33	0.8	6.8	1.5	17	0.84	6.4	3.1	0.3	14	0.2	0.8	0.5	28	0.02	0.105	3
1277792	Soil		12.5	14.2	12.8	59	0.6	13.9	2.7	30	1.13	10.4	1.1	0.1	14	0.2	2.5	0.2	74	0.01	0.061	6
1277793	Soil		10.8	26.5	17.1	112	0.9	26.0	5.4	71	2.64	21.0	2.3	0.6	19	0.5	3.0	0.3	101	0.02	0.093	9
1277794	Soil		4.5	104.3	9.5	159	0.2	34.7	11.6	95	2.03	14.7	9.1	0.8	15	0.5	5.7	0.2	32	0.22	0.099	8
1277795	Soil		26.9	71.0	22.0	598	0.9	160.8	9.9	121	2.74	27.2	5.4	1.0	89	5.1	8.0	0.2	114	1.12	0.184	8
1277796	Soil		7.0	25.3	7.2	2287	0.3	229.4	3.5	99	0.99	5.6	2.4	0.3	118	32.3	2.3	0.2	42	4.95	0.138	4
1277797	Soil		68.5	81.8	22.4	929	1.0	252.3	24.9	412	4.12	37.8	4.0	1.4	146	6.9	14.8	0.2	325	0.90	0.267	8
1277798	Soil		60.4	64.3	16.6	623	0.5	174.2	16.6	338	3.16	28.7	2.7	0.7	65	4.7	12.3	0.2	237	0.53	0.170	7
1277799	Soil		74.9	76.1	16.2	659	0.6	228.6	19.4	327	3.83	30.7	3.6	1.4	81	4.5	12.0	0.2	231	0.70	0.170	6
1277800	Soil		59.8	85.1	20.4	850	1.0	265.0	27.6	477	5.00	41.8	2.4	1.3	122	4.1	11.6	0.2	326	1.01	0.223	6
1277801	Soil		110.7	142.0	20.5	1119	0.8	535.5	76.2	1182	7.73	39.0	2.3	3.1	94	5.1	10.6	0.2	239	0.92	0.204	6
1277802	Soil		30.4	103.0	41.1	1278	1.4	436.5	68.1	725	7.08	24.6	1.4	1.4	149	9.7	14.2	<0.1	173	1.35	0.217	8
1277803	Soil		28.6	244.5	84.8	1948	2.1	898.1	166.3	1339	11.21	38.1	2.9	4.7	292	33.0	26.1	0.1	228	1.06	0.345	12
1277804	Soil		3.5	63.9	13.5	133	0.2	23.5	4.6	79	1.39	11.3	1.2	0.2	42	0.6	2.3	0.2	36	0.04	0.088	3
1277805	Soil		6.4	67.5	70.1	53	1.3	14.8	2.5	105	2.18	91.2	3.4	0.4	318	0.6	9.6	0.3	74	0.11	0.244	5
1277806	Soil		3.8	29.4	80.9	41	0.7	11.1	2.4	82	1.63	89.8	4.0	0.1	168	0.4	7.2	0.2	53	0.07	0.132	6
1277807	Soil		5.6	20.0	63.1	23	1.4	5.3	0.9	27	1.38	55.7	9.5	0.3	82	0.2	18.5	0.3	44	0.02	0.071	5
1277808	Soil		3.5	4.9	75.2	5	1.2	1.4	0.3	7	0.23	8.5	5.6	<0.1	39	<0.1	3.6	0.1	13	0.02	0.049	2
1277809	Soil		2.4	3.7	75.5	5	1.3	1.3	0.3	5	0.13	3.8	1.9	0.1	10	<0.1	10.0	0.1	16	0.01	0.028	2
1277810	Soil		0.4	2.2	2.4	5	0.1	1.1	0.5	39	0.21	<0.5	<0.5	<0.1	6	<0.1	0.2	<0.1	7	0.03	0.029	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277781	Soil	29	0.19	264	0.007	3	1.28	0.005	0.12	0.1	0.18	1.7	0.2	0.08	4	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277782	Soil	23	0.17	390	0.005	3	0.96	0.004	0.08	0.2	0.13	2.0	0.2	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277783	Soil	22	0.12	270	0.003	3	0.75	0.003	0.07	0.2	0.12	1.2	0.1	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277784	Soil	11	0.07	506	0.005	4	0.43	0.006	0.04	0.1	0.28	1.5	<0.1	0.21	1	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277785	Soil	18	0.08	191	0.004	2	0.62	0.008	0.07	0.1	0.07	0.4	<0.1	0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277786	Soil	15	0.03	141	0.005	2	0.60	0.003	0.05	0.1	0.04	0.5	0.1	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277787	Soil	21	0.15	709	0.003	3	1.04	0.006	0.08	<0.1	0.26	2.5	0.1	0.06	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277788	Soil	20	0.05	119	0.004	2	0.72	0.005	0.06	<0.1	0.07	0.4	0.1	0.06	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277789	Soil	24	0.01	326	0.002	<1	0.31	0.004	0.05	<0.1	0.26	2.1	0.2	0.06	2	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277790	Soil	12	0.02	256	0.001	<1	0.38	0.009	0.05	<0.1	0.18	0.5	0.2	0.06	1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277791	Soil	9	0.02	78	0.002	2	0.35	0.009	0.04	<0.1	0.07	0.5	0.2	0.24	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277792	Soil	11	0.02	81	0.003	3	0.31	0.009	0.05	0.1	0.03	<0.1	0.5	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277793	Soil	18	0.05	162	0.005	3	0.51	0.005	0.07	0.2	0.04	1.0	0.4	0.09	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277794	Soil	10	0.04	622	0.003	2	0.41	0.006	0.05	<0.1	0.02	1.7	0.1	0.07	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277795	Soil	33	0.25	831	0.004	5	0.51	0.006	0.05	<0.1	0.45	3.6	0.4	0.30	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277796	Soil	26	0.19	326	0.007	3	0.55	0.020	0.03	<0.1	0.19	1.4	0.4	0.08	1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277797	Soil	81	0.11	367	0.005	4	0.59	0.004	0.07	0.2	0.30	6.9	0.9	<0.05	2	7.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277798	Soil	62	0.07	503	0.004	2	0.62	0.006	0.05	0.2	0.17	4.1	0.8	<0.05	2	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277799	Soil	66	0.09	502	0.004	3	0.59	0.005	0.05	0.2	0.22	6.8	0.8	0.14	2	5.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277800	Soil	120	0.11	610	0.004	2	0.73	0.009	0.05	0.2	0.29	9.4	0.8	0.15	2	6.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277801	Soil	161	0.20	655	0.003	4	0.63	0.003	0.05	0.1	0.32	17.6	1.5	<0.05	3	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277802	Soil	199	0.13	572	0.003	3	0.59	0.014	0.03	<0.1	0.43	16.4	0.4	0.18	2	7.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277803	Soil	350	0.06	709	0.003	2	0.70	0.006	0.04	<0.1	0.65	34.6	0.4	<0.05	2	12.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277804	Soil	2	0.03	57	0.005	<1	0.55	0.020	0.03	<0.1	0.04	0.9	0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277805	Soil	40	0.08	312	0.009	1	0.73	0.020	0.07	<0.1	0.07	3.0	0.4	0.09	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277806	Soil	26	0.08	316	0.010	1	0.66	0.016	0.05	0.1	0.05	0.7	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277807	Soil	16	0.02	287	0.002	1	0.27	0.003	0.07	<0.1	0.11	0.4	0.3	0.07	3	6.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277808	Soil	7	<0.01	74	0.003	<1	0.24	0.017	0.03	<0.1	0.09	0.1	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277809	Soil	6	<0.01	50	0.003	1	0.19	0.009	0.03	<0.1	0.07	0.2	0.2	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277810	Soil	4	0.01	18	0.007	<1	0.38	0.034	0.02	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277781	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277782	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277783	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277784	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277785	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277786	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277787	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277788	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277789	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277790	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277791	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277792	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277793	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277794	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277795	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277796	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277797	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277798	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277799	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277800	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277801	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277802	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277803	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277804	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277805	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277806	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277807	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277808	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277809	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277810	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277781	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277782	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277783	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277784	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277785	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277786	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277787	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277788	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277789	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277790	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277791	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277792	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277793	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277794	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277795	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277796	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277797	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277798	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277799	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277800	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277801	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277802	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277803	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277804	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277805	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277806	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277807	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277808	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277809	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277810	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277811	Soil	36.9	14.3	82.7	61	0.2	16.1	2.3	38	0.97	11.7	0.6	0.1	40	<0.1	10.3	0.3	95	0.01	0.049	6
1277812	Soil	2.9	7.9	8.9	21	0.3	5.8	1.3	18	0.54	5.5	<0.5	<0.1	14	<0.1	1.7	<0.1	24	0.02	0.030	2
1277813	Soil	8.4	33.9	33.2	113	1.3	29.9	6.4	81	2.08	20.2	1.8	0.2	43	0.2	5.6	0.2	50	0.01	0.103	3
1277814	Soil	9.6	22.6	14.7	164	0.3	37.3	7.6	725	1.92	35.5	2.5	0.1	14	0.4	6.6	0.1	56	0.01	0.094	3
1277815	Soil	21.3	52.6	57.7	152	1.3	102.6	20.9	464	3.24	23.6	3.2	0.5	64	1.6	15.2	0.2	104	0.31	0.127	4
1277816	Soil	0.6	7.2	3.0	16	<0.1	5.4	1.7	101	0.54	3.1	<0.5	<0.1	6	<0.1	1.2	<0.1	9	0.03	0.029	1
1277817	Soil	5.7	122.3	49.6	579	2.8	108.3	21.5	278	5.00	55.7	5.2	1.0	94	1.1	19.7	0.3	41	0.25	0.168	7
1277818	Soil	34.4	81.3	43.0	516	0.7	127.0	12.4	226	3.81	56.4	3.9	1.2	39	1.0	28.7	0.2	116	0.18	0.197	7
1277819	Soil	54.1	78.2	37.6	381	0.8	143.7	12.9	394	3.64	75.6	2.3	0.9	32	2.9	28.4	0.2	102	0.33	0.109	7
1277820	Soil	32.6	38.4	11.7	455	0.4	76.8	6.5	152	2.29	31.9	0.6	0.6	29	3.6	13.1	0.1	128	0.52	0.094	5
1277821	Soil	8.7	118.0	26.2	342	1.1	131.6	15.1	212	4.18	21.0	2.1	3.1	13	3.2	9.6	0.2	47	0.19	0.028	7
1277822	Soil	20.1	38.5	7.9	202	0.3	53.8	9.1	207	2.94	256.1	1.1	0.2	13	0.9	13.0	0.1	93	0.16	0.093	4
1277823	Soil	26.9	33.4	6.7	196	<0.1	54.5	6.7	73	2.12	47.6	<0.5	0.2	8	0.5	11.9	0.1	66	0.06	0.104	5
1277824	Soil	35.2	39.9	19.2	514	0.4	94.5	10.4	314	3.59	61.5	1.8	0.5	14	3.9	18.0	0.1	163	0.12	0.106	7
1277825	Soil	121.7	85.2	16.9	426	0.1	228.4	11.9	139	2.51	63.2	2.4	0.7	36	4.3	24.1	0.1	66	0.49	0.105	4
1277826	Soil	89.9	76.5	16.1	292	0.2	191.7	16.7	354	3.52	175.1	2.4	1.4	92	0.8	20.0	<0.1	68	4.30	0.077	5
1277827	Soil	56.3	46.1	9.7	233	0.2	130.6	11.3	458	2.62	81.2	3.7	0.5	33	1.3	13.0	0.2	49	0.92	0.090	3
1277828	Soil	28.5	35.7	9.3	311	0.4	77.7	4.9	115	1.91	34.7	1.3	0.5	39	5.0	15.5	0.1	56	0.91	0.122	4
1277829	Soil	18.6	34.3	26.3	435	0.6	73.6	9.9	739	5.26	27.8	0.9	0.6	143	3.9	17.0	0.2	183	3.50	0.079	12
1277830	Soil	29.2	20.0	14.2	208	<0.1	49.8	4.7	67	2.25	20.2	<0.5	0.1	4	0.5	10.2	0.1	128	0.02	0.089	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277811	Soil	14	0.01	119	0.005	<1	0.35	0.004	0.04	0.1	0.05	0.3	0.5	<0.05	3	8.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277812	Soil	6	0.01	34	0.008	<1	0.30	0.022	0.02	0.3	0.03	<0.1	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277813	Soil	14	0.01	82	0.003	<1	0.35	0.007	0.03	<0.1	0.03	0.4	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277814	Soil	17	0.02	99	0.004	<1	0.41	0.011	0.04	<0.1	0.03	0.3	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277815	Soil	47	0.05	531	0.003	2	0.28	0.004	0.08	0.2	0.40	3.4	0.7	0.10	1	6.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277816	Soil	2	0.02	33	0.009	<1	0.47	0.039	0.03	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277817	Soil	18	0.04	1155	0.002	3	0.42	0.004	0.07	<0.1	0.32	4.0	0.2	<0.05	1	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277818	Soil	23	0.03	204	0.003	3	0.33	0.002	0.06	<0.1	0.08	4.1	0.3	<0.05	1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277819	Soil	19	0.07	389	0.003	1	0.28	0.003	0.04	0.1	0.41	5.4	0.5	0.07	<1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277820	Soil	15	0.13	279	0.004	1	0.58	0.010	0.04	<0.1	0.22	3.6	0.4	<0.05	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277821	Soil	31	0.07	190	0.001	2	0.23	0.002	0.05	<0.1	0.39	10.9	0.2	<0.05	<1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277822	Soil	20	0.10	171	0.005	<1	0.68	0.009	0.05	<0.1	0.05	1.4	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277823	Soil	18	0.04	144	0.003	<1	0.55	0.003	0.04	0.1	0.03	0.8	0.3	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277824	Soil	22	0.07	189	0.003	<1	0.60	0.005	0.04	<0.1	0.26	2.7	0.4	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277825	Soil	15	0.06	175	0.002	<1	0.33	0.001	0.03	0.2	0.44	3.8	0.6	<0.05	<1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277826	Soil	32	1.79	291	0.002	2	0.47	0.006	0.05	0.1	0.22	8.6	0.9	0.16	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277827	Soil	18	0.14	190	0.003	2	0.48	0.009	0.05	0.1	0.14	3.1	0.5	<0.05	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277828	Soil	12	0.14	236	0.005	2	0.56	0.015	0.03	0.1	0.13	2.4	0.3	<0.05	1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277829	Soil	21	1.65	1052	0.006	3	0.47	0.010	0.04	<0.1	0.24	2.6	0.4	<0.05	1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277830	Soil	8	0.02	61	0.002	2	0.28	0.006	0.03	<0.1	0.03	0.2	0.3	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277811	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277812	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277813	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277814	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277815	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277816	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277817	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277818	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277819	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277820	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277821	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277822	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277823	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277824	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277825	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277826	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277827	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277828	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277829	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277830	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001135.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277811	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277812	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277813	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277814	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277815	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277816	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277817	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277818	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277819	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277820	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277821	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277822	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277823	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277824	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277825	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277826	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277827	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277828	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277829	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277830	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001135.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1094825	Soil	3.7	89.2	32.4	286	2.9	106.5	29.6	578	5.78	25.8	2.3	3.6	45	0.8	1.7	0.3	32	0.18	0.127	4
REP 1094825	QC	3.7	86.6	32.8	286	2.8	104.7	29.0	581	5.71	24.6	3.4	3.7	44	0.9	1.6	0.3	32	0.17	0.121	4
1094837	Soil	2.8	45.7	20.4	132	0.6	45.8	17.8	738	3.52	13.2	2.7	1.3	40	0.2	1.4	0.3	39	0.05	0.104	6
REP 1094837	QC	3.0	43.8	19.6	130	0.6	46.7	16.8	697	3.36	13.5	2.4	1.2	41	0.1	1.4	0.3	40	0.05	0.108	8
1094855	Soil	109.7	53.0	17.0	328	0.2	163.7	9.8	178	3.43	26.2	<0.5	0.7	16	1.2	10.3	0.2	167	0.28	0.081	4
REP 1094855	QC	106.1	50.1	16.3	324	0.2	164.7	9.6	171	3.32	25.7	<0.5	0.7	16	1.2	10.0	0.2	160	0.27	0.080	4
1094878	Soil	5.3	54.2	11.3	196	0.4	70.2	7.4	132	2.48	17.2	0.8	0.3	7	0.6	6.4	0.2	37	0.02	0.104	2
REP 1094878	QC	4.9	55.4	11.4	200	0.5	72.8	7.3	134	2.49	16.5	1.2	0.3	8	0.4	6.9	0.2	38	0.02	0.106	2
1094898	Soil	2.0	32.0	12.1	93	0.8	27.6	5.7	155	1.72	30.5	10.0	1.1	58	0.4	2.8	0.2	30	1.33	0.062	5
REP 1094898	QC	2.3	34.0	12.8	100	0.8	29.4	6.2	163	1.84	33.2	11.6	1.1	62	0.4	2.9	0.2	31	1.44	0.069	5
1094902	Soil	8.6	17.7	9.9	113	<0.1	24.7	6.6	102	1.51	15.0	<0.5	0.1	8	0.5	3.0	0.3	59	0.02	0.055	6
REP 1094902	QC	8.5	17.7	10.0	113	<0.1	24.6	6.5	101	1.50	15.1	0.9	0.2	8	0.5	3.1	0.3	57	0.02	0.054	5
1094925	Soil	15.9	41.8	240.6	17	3.3	4.2	0.6	33	1.20	67.3	106.7	1.1	119	0.1	20.8	0.3	187	0.03	0.119	7
REP 1094925	QC	16.0	41.6	241.0	17	3.3	4.0	0.6	33	1.19	67.0	99.0	0.8	111	0.1	20.6	0.3	180	0.03	0.112	7
1094947	Soil	98.8	159.6	16.9	1048	1.9	347.1	14.9	314	2.63	99.6	1.9	2.0	195	15.1	24.8	0.2	525	2.78	0.140	18
REP 1094947	QC	100.0	159.1	16.5	1045	1.9	348.3	14.4	306	2.63	99.8	2.5	1.9	197	14.1	24.4	0.2	532	2.80	0.131	19
1276136	Soil	2.8	58.7	15.3	162	1.5	63.4	8.1	146	2.76	16.2	5.5	1.8	103	0.8	1.6	0.2	34	1.70	0.112	6
REP 1276136	QC	2.7	56.8	15.2	165	1.5	62.3	8.0	132	2.66	16.5	4.4	1.8	93	0.9	1.5	0.2	33	1.58	0.106	6
1276350	Soil	1.6	25.2	7.0	67	0.4	20.3	4.7	304	1.13	5.2	1.8	0.5	81	0.5	1.2	0.2	26	2.16	0.093	5
REP 1276350	QC	1.4	24.7	7.4	64	0.4	19.6	4.6	311	1.13	5.8	1.3	0.5	81	0.6	1.3	0.2	25	2.20	0.090	5
1277707	Soil	28.2	14.1	10.7	83	1.4	14.5	1.6	23	1.05	13.7	1.8	0.2	20	0.2	8.8	0.2	254	0.02	0.050	12
REP 1277707	QC	28.3	14.1	11.1	84	1.3	14.3	1.5	24	1.07	14.1	<0.5	0.3	21	0.4	9.0	0.2	267	0.02	0.049	13
1277736	Soil	2.5	21.0	13.3	24	0.1	7.8	0.9	11	1.66	142.3	9.6	1.0	43	<0.1	5.2	0.2	38	0.02	0.048	5
REP 1277736	QC	2.4	20.0	13.1	24	0.1	7.0	0.9	10	1.60	136.3	10.8	1.0	42	<0.1	5.1	0.2	39	0.02	0.048	4
1277751	Soil	2.2	50.5	14.1	90	2.3	47.3	8.8	677	2.06	6.7	6.1	1.1	165	0.2	0.8	0.2	16	1.26	0.172	10
REP 1277751	QC	2.1	49.0	15.6	95	2.3	47.9	9.4	695	2.14	6.9	7.0	1.3	157	0.2	0.8	0.2	18	1.18	0.172	9
1277772	Soil	3.4	40.0	20.1	130	0.2	44.0	12.5	327	3.96	25.5	1.9	2.2	32	0.3	1.3	0.3	55	0.08	0.124	8
REP 1277772	QC	2.9	37.8	19.4	122	0.2	40.2	12.5	309	3.74	24.4	2.7	2.1	30	0.2	1.2	0.2	51	0.08	0.116	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001135.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1094825	Soil	28	0.20	594	<0.001	3	1.15	0.006	0.10	<0.1	0.16	7.5	0.2	0.09	3	6.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094825	QC	28	0.19	597	<0.001	4	1.13	0.006	0.10	<0.1	0.18	7.3	0.2	0.10	3	6.5	<0.2				
1094837	Soil	27	0.26	1134	0.007	<1	1.23	0.008	0.06	0.1	0.09	2.2	0.1	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094837	QC	27	0.27	1300	0.010	2	1.30	0.008	0.07	0.1	0.08	2.3	0.2	0.05	4	1.6	<0.2				
1094855	Soil	14	0.05	157	0.002	<1	0.33	0.002	0.04	<0.1	0.15	2.8	0.7	<0.05	1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094855	QC	14	0.05	162	0.003	<1	0.30	0.002	0.04	<0.1	0.11	2.7	0.7	<0.05	<1	4.1	<0.2				
1094878	Soil	19	0.03	157	0.002	1	0.29	0.003	0.04	0.1	0.05	0.9	0.1	<0.05	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094878	QC	19	0.02	159	0.003	1	0.29	0.003	0.04	0.1	0.05	0.9	0.1	<0.05	1	1.5	<0.2				
1094898	Soil	17	0.14	841	0.001	3	0.80	0.007	0.05	<0.1	0.88	2.2	0.1	0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094898	QC	19	0.14	892	0.002	3	0.84	0.007	0.05	0.1	0.97	2.2	0.1	<0.05	2	2.3	0.2				
1094902	Soil	8	0.03	64	0.003	2	0.42	0.006	0.04	<0.1	<0.01	0.2	0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1094902	QC	7	0.03	61	0.004	1	0.40	0.006	0.04	<0.1	<0.01	0.3	0.1	<0.05	2	0.5	<0.2				
1094925	Soil	23	0.02	1921	0.002	4	0.48	0.005	0.13	0.3	5.94	1.8	1.5	0.27	3	12.3	0.3	N.A.	N.A.	N.A.	N.A.
REP 1094925	QC	23	0.02	1776	0.002	4	0.45	0.004	0.12	0.2	6.09	1.5	1.5	0.28	3	12.6	0.2				
1094947	Soil	43	0.66	339	0.004	7	0.58	0.003	0.10	0.6	0.55	5.6	5.9	0.06	2	5.5	0.3	N.A.	N.A.	N.A.	N.A.
REP 1094947	QC	43	0.67	337	0.005	7	0.61	0.004	0.11	0.6	0.58	5.5	6.3	0.07	2	5.5	0.3				
1276136	Soil	21	0.10	731	<0.001	6	0.81	0.007	0.11	<0.1	0.21	3.6	0.2	0.25	2	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276136	QC	21	0.10	692	<0.001	7	0.82	0.007	0.10	<0.1	0.21	3.5	0.2	0.24	2	4.0	<0.2				
1276350	Soil	11	0.13	563	0.005	4	0.78	0.015	0.04	0.1	0.15	1.2	<0.1	0.07	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276350	QC	10	0.14	563	0.004	3	0.76	0.012	0.04	0.1	0.13	1.1	<0.1	0.07	2	2.6	<0.2				
1277707	Soil	14	0.03	131	0.006	2	0.42	0.005	0.05	0.4	0.03	0.5	1.7	<0.05	3	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277707	QC	14	0.04	137	0.006	3	0.44	0.006	0.06	0.5	0.03	0.6	1.7	<0.05	4	3.3	<0.2				
1277736	Soil	29	0.01	331	0.002	3	0.38	0.002	0.05	0.1	0.59	1.8	<0.1	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277736	QC	28	0.01	327	0.002	3	0.37	0.002	0.05	0.1	0.58	1.8	<0.1	<0.05	2	1.6	0.2				
1277751	Soil	20	0.16	6192	0.004	7	0.98	0.008	0.06	<0.1	0.41	3.6	0.1	0.19	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277751	QC	20	0.18	5642	0.003	7	0.99	0.008	0.06	<0.1	0.38	3.8	0.1	0.17	2	1.5	<0.2				
1277772	Soil	38	0.33	750	0.006	3	1.78	0.006	0.11	0.2	0.05	3.2	0.2	<0.05	5	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277772	QC	36	0.31	703	0.004	3	1.66	0.005	0.10	0.2	0.06	2.9	0.2	<0.05	5	1.3	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001135.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1094825	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094825	QC																					
1094837	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094837	QC																					
1094855	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094855	QC																					
1094878	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094878	QC																					
1094898	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094898	QC																					
1094902	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094902	QC																					
1094925	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094925	QC																					
1094947	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094947	QC																					
1276136	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276136	QC																					
1276350	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276350	QC																					
1277707	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277707	QC																					
1277736	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277736	QC																					
1277751	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277751	QC																					
1277772	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277772	QC																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001135.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1094825	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094825	QC													
1094837	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094837	QC													
1094855	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094855	QC													
1094878	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094878	QC													
1094898	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094898	QC													
1094902	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094902	QC													
1094925	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094925	QC													
1094947	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1094947	QC													
1276136	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276136	QC													
1276350	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276350	QC													
1277707	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277707	QC													
1277736	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277736	QC													
1277751	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277751	QC													
1277772	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277772	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001135.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1277789	Soil	9.1	43.4	14.3	33	3.9	9.3	2.0	47	1.58	14.0	3.9	0.9	31	0.1	6.6	<0.1	30	0.12	0.146	3
REP 1277789	QC	8.9	41.8	14.0	34	3.9	8.8	1.9	45	1.47	13.3	4.9	0.9	30	0.1	6.4	<0.1	29	0.11	0.142	3
1277802	Soil	30.4	103.0	41.1	1278	1.4	436.5	68.1	725	7.08	24.6	1.4	1.4	149	9.7	14.2	<0.1	173	1.35	0.217	8
REP 1277802	QC	31.1	104.4	41.0	1278	1.4	438.9	69.4	731	7.21	24.6	1.7	1.5	151	9.7	14.5	<0.1	177	1.40	0.220	8
1277810	Soil	0.4	2.2	2.4	5	0.1	1.1	0.5	39	0.21	<0.5	<0.5	<0.1	6	<0.1	0.2	<0.1	7	0.03	0.029	<1
REP 1277810	QC	0.5	2.3	2.4	6	0.1	1.6	0.6	41	0.23	<0.5	<0.5	<0.1	6	<0.1	0.2	<0.1	8	0.03	0.028	1
1277827	Soil	56.3	46.1	9.7	233	0.2	130.6	11.3	458	2.62	81.2	3.7	0.5	33	1.3	13.0	0.2	49	0.92	0.090	3
REP 1277827	QC	55.3	44.8	9.3	229	0.2	130.2	11.4	451	2.61	80.8	1.8	0.5	32	1.4	13.2	0.1	48	0.91	0.093	3
Reference Materials																					
STD DS8	Standard	12.6	101.3	118.4	298	1.7	35.4	7.1	583	2.35	23.6	107.0	6.4	67	2.0	5.0	6.5	39	0.65	0.079	16
STD DS8	Standard	15.0	117.7	133.2	322	1.9	41.4	8.2	635	2.57	26.2	113.8	7.6	68	2.3	5.7	5.8	50	0.74	0.090	17
STD DS8	Standard	13.9	109.5	117.2	293	1.7	38.8	7.7	587	2.36	21.7	108.1	6.7	60	2.0	5.0	4.9	47	0.65	0.075	16
STD DS8	Standard	14.2	110.0	127.9	311	1.8	37.8	7.6	617	2.49	24.3	113.4	7.0	70	2.4	5.2	6.4	42	0.71	0.076	17
STD DS8	Standard	12.8	107.5	125.9	314	1.7	38.5	7.3	612	2.49	25.2	112.8	6.5	69	2.4	5.5	6.5	41	0.68	0.077	15
STD DS8	Standard	13.1	112.9	130.8	304	1.8	38.6	7.6	590	2.44	24.9	109.5	7.0	68	2.1	5.6	6.8	44	0.71	0.080	16
STD DS8	Standard	13.1	109.8	124.3	314	1.8	37.6	7.4	610	2.49	25.6	110.5	7.1	69	2.5	5.5	6.4	41	0.69	0.081	15
STD DS8	Standard	13.2	114.2	123.5	315	1.9	40.9	7.9	622	2.49	27.3	108.4	7.2	60	2.5	5.3	6.5	46	0.72	0.083	15
STD DS8	Standard	14.4	119.3	120.3	306	1.8	40.4	8.0	653	2.68	27.3	114.2	6.8	64	2.5	5.8	6.8	45	0.72	0.084	16
STD DS8	Standard	13.3	118.1	133.2	316	1.9	40.1	8.1	630	2.57	26.8	115.4	6.9	69	2.4	5.9	7.4	44	0.70	0.081	14
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001135.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1277789	Soil	24	0.01	326	0.002	<1	0.31	0.004	0.05	<0.1	0.26	2.1	0.2	0.06	2	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277789	QC	24	0.01	322	0.001	1	0.32	0.004	0.05	<0.1	0.25	2.0	0.2	0.06	1	6.5	<0.2				
1277802	Soil	199	0.13	572	0.003	3	0.59	0.014	0.03	<0.1	0.43	16.4	0.4	0.18	2	7.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277802	QC	200	0.14	576	0.004	3	0.59	0.013	0.03	<0.1	0.45	17.0	0.4	0.05	2	7.2	<0.2				
1277810	Soil	4	0.01	18	0.007	<1	0.38	0.034	0.02	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277810	QC	4	0.02	20	0.008	<1	0.39	0.033	0.02	<0.1	0.02	0.1	<0.1	<0.05	2	<0.5	<0.2				
1277827	Soil	18	0.14	190	0.003	2	0.48	0.009	0.05	0.1	0.14	3.1	0.5	<0.05	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277827	QC	18	0.14	194	0.003	1	0.48	0.010	0.04	0.1	0.16	3.0	0.5	<0.05	1	1.9	<0.2				
Reference Materials																					
STD DS8	Standard	108	0.59	271	0.118	3	0.91	0.088	0.39	2.9	0.20	2.0	5.2	0.15	5	4.8	4.8				
STD DS8	Standard	125	0.63	288	0.128	2	0.97	0.122	0.45	3.1	0.21	2.7	5.5	0.16	5	5.0	4.7				
STD DS8	Standard	116	0.58	245	0.120	2	0.87	0.079	0.39	2.8	0.21	2.1	5.1	0.16	4	4.6	4.5				
STD DS8	Standard	121	0.59	289	0.122	2	0.97	0.112	0.42	2.9	0.19	3.1	5.4	0.11	5	6.4	5.6				
STD DS8	Standard	121	0.58	279	0.112	2	0.96	0.114	0.43	3.0	0.21	3.1	5.4	0.13	5	6.3	4.8				
STD DS8	Standard	118	0.63	281	0.120	3	0.95	0.100	0.40	3.1	0.19	2.3	5.4	0.15	5	4.6	4.6				
STD DS8	Standard	119	0.62	275	0.115	3	0.95	0.111	0.45	3.2	0.19	2.9	5.2	0.14	5	6.1	5.1				
STD DS8	Standard	121	0.65	277	0.108	3	0.96	0.095	0.43	2.9	0.19	1.9	5.6	0.16	5	5.4	5.6				
STD DS8	Standard	121	0.63	310	0.120	3	0.96	0.094	0.43	3.1	0.19	2.0	5.6	0.19	5	6.1	4.7				
STD DS8	Standard	124	0.62	287	0.120	3	0.92	0.090	0.41	3.1	0.20	2.4	5.8	0.16	5	5.2	5.3				
STD DS8	Standard																	14.2	119.9	125.1	325
STD OREAS45CA	Standard																	0.9	570.7	22.2	69
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001135.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1277789	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277789	QC																				
1277802	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277802	QC																				
1277810	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277810	QC																				
1277827	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277827	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.7	41.1	8.3	652	2.53	27.0	136.8	7.2	76	2.4	5.4	7.4	47	0.73	0.081	17	128	0.61	304	0.123
STD OREAS45CA	Standard	0.3	271.0	97.9	970	17.25	3.5	43.2	7.3	16	<0.1	<0.1	0.2	218	0.43	0.039	17	793	0.16	172	0.144
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001135.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1277789	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277789	QC												
1277802	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277802	QC												
1277810	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277810	QC												
1277827	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277827	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.94	0.096	0.43	2.3	0.19	2.4	5.5	0.17	5	4.4	5.4
STD OREAS45CA	Standard	<20	3.94	0.013	0.08	<0.1	0.03	39.8	<0.1	0.05	19	0.9	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001135.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001135.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001135.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001135.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 12, 2011
Report Date: October 07, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001136.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #13
P.O. Number
Number of Samples: 320

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	318	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277831	Soil	23.7	67.3	133.9	358	0.4	83.0	14.8	294	3.92	112.7	1.7	0.4	24	0.7	48.9	0.6	82	0.03	0.153	12
1277832	Soil	15.2	44.9	17.4	269	0.3	64.4	8.2	165	2.35	38.9	1.8	<0.1	19	0.6	11.1	0.2	80	0.03	0.113	7
1277833	Soil	18.6	22.7	10.3	139	0.1	40.1	4.4	75	1.35	22.3	0.5	<0.1	10	0.5	6.4	0.1	51	0.02	0.076	4
1277834	Soil	29.8	15.8	11.2	146	0.2	47.9	5.0	57	1.32	25.4	<0.5	<0.1	6	0.1	4.0	0.1	76	0.01	0.045	3
1277835	Soil	26.1	11.8	4.9	110	0.2	38.6	2.6	34	0.80	12.4	<0.5	<0.1	4	0.2	4.0	<0.1	45	0.02	0.040	1
1277836	Soil	65.1	90.9	48.0	391	1.4	108.9	7.5	154	1.76	48.9	1.0	2.5	55	10.1	13.5	0.2	194	0.23	0.057	6
1277837	Soil	2.1	16.6	5.0	41	<0.1	9.4	5.2	90	1.06	6.2	<0.5	<0.1	5	<0.1	0.6	0.1	23	0.02	0.036	4
1277838	Soil	4.2	31.0	28.3	96	0.2	26.3	11.8	132	2.04	15.1	0.9	0.3	8	0.4	1.2	0.3	32	0.02	0.064	3
1277839	Soil	1.2	16.0	7.7	52	<0.1	10.4	6.0	99	1.27	6.7	<0.5	<0.1	6	<0.1	0.6	0.1	17	0.02	0.038	3
1277840	Soil	1.5	16.6	7.9	37	<0.1	8.6	4.5	64	1.02	4.5	<0.5	<0.1	6	<0.1	0.4	0.2	21	0.01	0.042	5
1277841	Soil	1.6	30.1	6.2	79	0.1	12.5	7.2	136	1.55	6.7	12.8	<0.1	7	0.2	0.6	0.2	26	0.02	0.062	4
1277842	Soil	0.9	21.8	5.8	63	<0.1	10.9	6.7	95	1.22	5.5	<0.5	<0.1	5	<0.1	0.4	0.2	19	0.01	0.049	3
1277843	Soil	2.0	30.1	11.6	102	<0.1	23.4	13.3	158	2.06	12.3	<0.5	<0.1	15	0.2	0.9	0.2	25	0.02	0.063	4
1277844	Soil	2.0	13.7	7.4	50	0.1	11.8	4.8	204	0.98	6.2	1.2	<0.1	12	0.3	1.0	0.1	17	0.11	0.069	3
1277845	Soil	1.0	9.3	4.5	29	0.1	6.9	3.1	71	0.74	4.0	<0.5	<0.1	13	0.1	0.4	<0.1	11	0.10	0.050	2
1277846	Soil	1.6	27.4	18.0	102	0.2	29.7	16.7	199	2.27	13.5	<0.5	0.5	17	0.1	0.8	0.3	16	0.12	0.067	4
1277847	Soil	1.7	21.6	16.3	105	<0.1	26.2	13.7	152	1.84	10.5	<0.5	0.8	20	0.1	0.9	0.2	19	0.18	0.048	4
1277848	Soil	1.7	20.4	16.3	128	<0.1	19.8	19.3	445	1.62	7.6	<0.5	0.8	21	1.0	0.7	0.2	19	0.26	0.042	4
1277849	Soil	0.5	15.0	5.8	35	<0.1	10.3	4.1	41	0.76	3.2	<0.5	0.2	52	<0.1	0.3	<0.1	10	0.84	0.063	3
1277850	Soil	1.0	16.8	6.6	53	0.1	11.3	2.2	32	0.57	2.1	<0.5	0.2	49	0.3	0.7	<0.1	11	1.12	0.057	3
1277851	Soil	24.9	50.2	49.9	427	1.4	64.0	9.1	239	3.11	85.4	2.9	2.8	68	2.3	22.4	0.2	113	0.45	0.130	9
1277852	Soil	16.0	44.9	28.5	176	1.2	35.1	6.0	315	2.31	44.6	3.0	1.4	56	2.1	12.2	0.2	108	0.50	0.122	7
1277853	Soil	10.5	54.2	17.5	258	0.9	52.8	9.8	294	2.60	30.6	3.4	2.2	81	2.8	4.9	0.2	106	0.44	0.128	10
1277854	Soil	9.8	66.0	19.5	320	1.5	69.5	10.9	526	2.81	35.0	4.8	2.2	71	6.3	4.3	0.2	115	0.45	0.115	9
1277855	Soil	19.9	60.0	29.3	200	1.5	52.5	5.8	78	2.80	39.1	6.0	2.1	76	3.2	8.1	0.3	140	0.23	0.130	11
1277856	Soil	24.9	44.5	16.9	245	1.2	46.6	7.4	262	2.42	51.1	5.3	1.1	40	2.8	7.4	0.2	160	0.21	0.115	12
1277857	Soil	67.9	110.2	22.2	2342	1.5	284.8	40.6	335	9.89	336.6	3.0	3.9	124	62.4	13.3	0.3	208	0.43	0.381	12
1277858	Soil	9.8	33.0	15.7	162	0.6	37.2	5.8	137	1.79	26.8	2.6	1.9	68	1.8	3.3	0.2	90	0.66	0.060	10
1277859	Soil	7.4	38.5	12.7	193	0.8	44.9	10.1	726	2.46	22.7	3.3	1.3	110	5.0	3.0	0.2	78	1.36	0.109	8
1277860	Soil	8.4	32.9	23.6	91	2.0	24.1	3.0	177	1.26	22.6	4.0	1.3	63	1.5	4.5	0.2	110	0.43	0.086	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277831	Soil	14	0.04	142	0.004	<1	0.44	0.003	0.07	0.1	0.05	0.4	0.4	0.09	2	4.0	0.2
1277832	Soil	16	0.03	279	<0.001	1	0.49	0.004	0.05	<0.1	0.04	<0.1	0.2	0.06	2	2.5	<0.2
1277833	Soil	8	0.02	71	0.001	<1	0.28	0.009	0.03	<0.1	0.01	<0.1	0.2	<0.05	1	0.8	<0.2
1277834	Soil	7	0.01	38	0.002	<1	0.24	0.006	0.02	<0.1	0.02	0.1	0.2	<0.05	2	1.9	<0.2
1277835	Soil	5	0.01	25	0.002	<1	0.19	0.011	0.02	0.1	0.01	<0.1	0.2	<0.05	<1	0.8	<0.2
1277836	Soil	14	0.13	251	0.004	<1	0.42	0.002	0.06	0.2	0.39	4.0	1.6	<0.05	1	6.7	0.2
1277837	Soil	5	0.02	30	0.004	<1	0.40	0.012	0.02	<0.1	<0.01	0.2	<0.1	<0.05	2	<0.5	<0.2
1277838	Soil	8	0.03	51	0.002	<1	0.37	0.004	0.04	<0.1	0.04	1.1	0.3	<0.05	2	0.5	<0.2
1277839	Soil	5	0.03	29	0.004	<1	0.46	0.013	0.02	<0.1	0.01	0.3	<0.1	<0.05	2	0.6	<0.2
1277840	Soil	6	0.02	38	0.004	<1	0.47	0.008	0.03	<0.1	0.01	0.2	<0.1	<0.05	2	<0.5	<0.2
1277841	Soil	8	0.04	63	0.002	<1	0.62	0.006	0.04	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2
1277842	Soil	6	0.03	48	0.002	<1	0.48	0.008	0.03	<0.1	<0.01	0.2	<0.1	<0.05	2	<0.5	<0.2
1277843	Soil	8	0.04	70	0.001	<1	0.46	0.003	0.04	<0.1	0.01	0.3	<0.1	<0.05	2	<0.5	<0.2
1277844	Soil	6	0.04	103	0.001	<1	0.36	0.015	0.04	<0.1	0.03	0.1	<0.1	<0.05	2	0.8	<0.2
1277845	Soil	4	0.03	90	0.003	<1	0.34	0.016	0.03	<0.1	0.02	0.1	<0.1	<0.05	2	<0.5	<0.2
1277846	Soil	13	0.09	101	<0.001	<1	0.37	0.003	0.07	<0.1	0.03	2.3	<0.1	<0.05	1	0.6	<0.2
1277847	Soil	9	0.10	117	0.002	<1	0.42	0.006	0.07	<0.1	0.03	2.8	0.1	<0.05	1	0.7	<0.2
1277848	Soil	11	0.09	111	0.003	<1	0.47	0.008	0.09	<0.1	0.01	2.1	<0.1	0.07	2	<0.5	<0.2
1277849	Soil	5	0.08	196	0.003	<1	0.60	0.017	0.03	<0.1	0.03	0.8	<0.1	0.09	2	1.3	<0.2
1277850	Soil	5	0.21	127	0.006	2	0.47	0.030	0.04	<0.1	0.07	0.5	<0.1	0.09	<1	1.1	<0.2
1277851	Soil	21	0.19	2454	0.003	2	1.02	0.005	0.08	0.1	1.05	2.9	0.8	0.06	3	4.6	<0.2
1277852	Soil	19	0.13	2111	0.003	2	1.07	0.010	0.06	0.2	0.69	2.4	0.6	0.11	3	3.1	<0.2
1277853	Soil	24	0.21	1852	0.004	3	1.01	0.005	0.08	0.1	0.63	3.0	0.4	<0.05	3	2.4	<0.2
1277854	Soil	23	0.17	1859	0.003	3	1.13	0.008	0.08	0.1	0.75	3.5	0.5	<0.05	3	3.1	<0.2
1277855	Soil	26	0.14	1932	0.003	2	1.16	0.005	0.08	0.2	0.99	3.4	1.0	<0.05	3	4.1	<0.2
1277856	Soil	21	0.12	1116	0.004	5	0.91	0.012	0.10	0.2	0.95	1.9	0.9	<0.05	3	2.4	<0.2
1277857	Soil	37	0.16	2751	0.005	6	1.42	0.004	0.12	0.2	1.02	5.2	3.2	0.08	3	13.1	<0.2
1277858	Soil	18	0.10	876	0.005	2	0.63	0.009	0.07	0.2	0.45	2.0	0.3	0.05	2	1.5	<0.2
1277859	Soil	16	0.24	1465	0.003	1	0.80	0.009	0.06	0.1	0.53	2.4	0.3	0.20	2	3.1	<0.2
1277860	Soil	18	0.11	766	0.004	2	0.65	0.010	0.06	0.2	0.81	1.9	0.6	0.09	2	3.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277861	Soil		10.9	52.0	20.8	242	1.1	58.2	6.7	204	1.91	29.3	4.2	2.6	70	3.5	4.8	0.2	116	0.51	0.125	12
1277862	Soil		11.0	78.2	21.2	386	1.6	99.0	10.1	163	2.12	42.8	4.3	2.0	92	6.2	7.0	0.2	101	0.51	0.169	11
1277863	Soil		9.3	46.1	34.7	58	0.9	14.6	2.5	84	2.17	64.1	3.2	0.9	164	0.2	7.2	0.3	92	0.17	0.271	12
1277864	Soil		5.8	113.3	33.5	61	0.8	18.8	1.5	27	3.40	55.5	5.7	0.8	106	0.5	5.1	0.5	104	0.05	0.239	9
1277865	Soil		46.2	128.5	91.6	51	2.6	11.1	1.1	48	2.00	45.6	2.7	0.6	212	0.6	19.7	0.3	217	0.09	0.235	5
1277866	Soil		4.2	21.2	12.4	62	0.3	10.0	2.1	51	0.99	9.9	<0.5	<0.1	18	0.3	2.1	<0.1	26	0.02	0.067	2
1277867	Soil		10.5	56.0	597.2	139	2.3	19.6	5.3	190	2.61	106.8	6.3	1.5	548	1.5	38.0	0.7	109	0.16	0.299	17
1277868	Soil		10.4	66.3	23.6	189	0.2	35.1	7.0	163	3.21	30.9	2.1	0.3	29	0.8	5.1	0.4	76	0.05	0.070	8
1277869	Soil		8.2	67.1	30.2	177	0.3	31.0	6.2	171	2.49	25.8	3.8	<0.1	40	1.4	4.7	0.3	59	0.05	0.083	6
1277870	Soil		2.7	15.9	8.0	84	0.2	10.0	1.9	45	0.92	6.8	2.3	<0.1	12	0.1	1.9	0.1	23	0.03	0.043	2
1277881	Soil		5.1	16.1	28.4	87	0.7	21.0	3.1	38	1.01	20.0	7.6	<0.1	17	0.2	11.6	0.2	37	0.03	0.060	5
1277882	Soil		12.6	40.5	37.2	222	0.3	58.0	7.9	113	2.85	41.3	2.7	0.2	41	0.5	15.7	0.3	79	0.07	0.146	13
1277883	Soil		13.0	57.1	30.8	307	0.5	69.2	9.0	193	2.86	40.7	2.6	0.5	44	1.2	11.4	0.3	75	0.17	0.168	13
1277884	Soil		17.1	58.3	33.9	386	0.7	77.1	9.7	215	3.41	51.6	3.4	0.3	39	1.1	11.1	0.4	85	0.14	0.185	15
1277885	Soil		7.1	35.0	16.2	176	0.8	44.6	4.9	115	1.60	19.2	1.8	0.1	64	1.2	6.6	0.2	44	0.56	0.118	7
1277886	Soil		8.4	68.7	68.2	478	1.8	83.5	10.1	186	2.84	86.7	16.9	1.5	111	2.9	61.1	0.3	59	0.67	0.215	12
1277887	Soil		4.1	16.1	10.8	99	1.5	19.7	2.0	52	0.86	9.6	0.9	<0.1	22	0.7	5.1	0.1	32	0.16	0.062	3
1277888	Soil		1.8	228.0	29.7	478	1.8	112.7	16.7	463	10.36	36.2	3.1	3.6	365	0.4	1.2	0.3	54	0.31	0.436	9
1277889	Soil		2.9	44.8	21.8	73	1.3	13.7	2.6	67	2.37	33.8	2.3	1.3	45	0.1	1.6	0.3	62	0.03	0.066	5
1277890	Soil		4.2	36.9	21.9	117	2.7	34.5	5.7	103	3.02	23.1	4.7	0.6	30	0.2	1.4	0.3	61	0.02	0.100	4
1277891	Soil		6.5	63.0	19.4	55	2.9	12.2	2.0	31	2.60	33.9	5.4	1.4	54	0.1	1.5	0.3	49	0.01	0.085	4
1277892	Soil		12.5	44.4	14.6	102	3.3	17.6	2.6	23	2.64	27.6	4.2	0.8	16	<0.1	1.9	0.2	35	<0.01	0.040	2
1277893	Soil		6.2	35.6	10.5	63	1.4	15.0	2.4	31	1.76	17.5	4.3	0.2	23	0.1	1.0	0.2	37	0.03	0.068	4
1277894	Soil		5.4	80.0	20.9	245	2.4	117.9	15.2	223	4.59	25.3	5.4	1.8	37	0.6	2.8	0.2	33	0.02	0.091	5
1277895	Soil		4.9	53.6	19.0	145	2.4	63.7	8.7	146	3.02	27.2	4.8	0.8	53	0.4	2.2	0.2	33	0.08	0.089	5
1277896	Soil		4.0	46.9	16.7	146	1.8	59.0	8.0	130	2.70	26.0	4.3	0.6	57	0.4	2.0	0.2	33	0.06	0.096	5
1277897	Soil		4.3	49.2	21.6	137	1.5	46.9	9.3	176	3.09	27.1	3.8	1.3	52	0.3	1.7	0.3	33	0.06	0.078	4
1277898	Soil		4.5	52.1	21.6	139	1.7	45.6	10.1	183	3.23	28.0	3.8	1.4	45	0.2	2.0	0.3	34	0.03	0.077	4
1277899	Soil		4.2	35.0	21.6	152	0.8	39.9	8.5	258	3.30	90.8	13.5	1.1	45	0.9	4.7	0.4	44	0.13	0.111	7
1277900	Soil		6.0	30.9	15.5	92	0.5	21.0	3.9	54	1.85	61.9	4.8	0.2	16	0.2	3.6	0.3	74	0.01	0.080	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277861	Soil	22	0.15	1754	0.003	4	0.81	0.004	0.09	0.1	0.67	3.1	0.5	0.06	2	1.8	<0.2
1277862	Soil	25	0.11	1020	0.002	4	0.67	0.004	0.08	<0.1	2.01	3.1	0.5	0.16	2	6.2	<0.2
1277863	Soil	32	0.13	215	0.013	<1	0.84	0.015	0.08	0.1	0.09	6.3	0.7	0.12	7	4.2	<0.2
1277864	Soil	42	0.04	202	0.002	<1	0.72	0.003	0.05	<0.1	0.31	5.7	0.2	0.11	3	3.8	<0.2
1277865	Soil	28	0.04	386	0.004	<1	0.52	0.005	0.12	<0.1	0.24	3.4	1.5	0.19	3	12.8	0.3
1277866	Soil	6	0.01	44	0.003	<1	0.30	0.019	0.03	<0.1	0.04	<0.1	0.1	<0.05	2	1.2	<0.2
1277867	Soil	39	0.04	449	0.006	2	0.75	0.005	0.12	<0.1	0.30	2.9	1.2	0.27	7	5.2	<0.2
1277868	Soil	23	0.11	68	0.015	2	0.69	0.003	0.04	0.2	<0.01	1.3	0.2	<0.05	4	2.2	<0.2
1277869	Soil	19	0.09	83	0.005	2	0.62	0.007	0.04	0.1	0.01	0.5	0.1	0.06	3	1.3	<0.2
1277870	Soil	6	0.02	37	0.002	1	0.21	0.012	0.02	<0.1	<0.01	0.1	<0.1	<0.05	2	<0.5	<0.2
1277881	Soil	7	0.02	243	0.001	2	0.34	0.009	0.03	<0.1	0.01	0.1	0.1	<0.05	2	1.0	<0.2
1277882	Soil	15	0.05	255	0.005	2	0.57	0.003	0.06	0.1	<0.01	0.5	0.2	<0.05	3	2.2	<0.2
1277883	Soil	19	0.12	332	0.007	3	0.79	0.004	0.06	0.2	0.07	1.2	0.3	0.06	3	1.9	<0.2
1277884	Soil	20	0.11	369	0.006	2	0.73	0.003	0.07	0.2	0.49	0.8	0.3	<0.05	3	2.5	<0.2
1277885	Soil	12	0.11	1071	0.004	2	0.57	0.016	0.05	<0.1	0.10	0.5	0.2	0.07	2	1.4	<0.2
1277886	Soil	17	0.11	622	0.005	2	0.54	0.006	0.06	<0.1	0.36	4.3	0.2	<0.05	1	2.4	<0.2
1277887	Soil	5	0.04	448	0.003	2	0.42	0.018	0.03	<0.1	0.09	0.3	0.2	<0.05	1	0.9	<0.2
1277888	Soil	28	0.10	582	0.003	4	2.93	0.004	0.08	0.1	0.30	12.2	0.1	0.10	2	5.2	<0.2
1277889	Soil	20	0.03	510	0.003	4	0.78	0.004	0.08	<0.1	0.11	1.7	0.1	0.05	3	3.0	0.3
1277890	Soil	23	0.03	1124	0.002	6	0.81	0.004	0.09	<0.1	0.23	1.1	0.1	0.13	3	4.2	0.2
1277891	Soil	44	0.02	664	0.001	4	0.64	0.005	0.16	<0.1	0.41	4.0	0.2	0.30	3	13.0	<0.2
1277892	Soil	29	0.01	563	<0.001	6	0.49	0.003	0.08	<0.1	0.58	2.6	0.1	<0.05	2	11.3	<0.2
1277893	Soil	25	0.03	402	0.003	4	0.63	0.011	0.06	<0.1	0.16	0.7	0.1	<0.05	2	5.4	<0.2
1277894	Soil	25	0.06	343	0.002	2	0.73	0.003	0.06	<0.1	0.25	4.6	0.1	0.06	2	4.6	<0.2
1277895	Soil	24	0.06	777	0.002	3	0.77	0.006	0.07	<0.1	0.48	2.7	0.2	0.07	2	4.5	<0.2
1277896	Soil	21	0.05	477	0.002	3	0.77	0.008	0.07	<0.1	0.29	2.0	0.2	0.06	3	3.1	<0.2
1277897	Soil	22	0.07	594	0.002	3	0.77	0.006	0.08	<0.1	0.16	3.1	0.2	<0.05	3	4.1	<0.2
1277898	Soil	23	0.08	456	0.002	3	0.79	0.007	0.08	<0.1	0.11	3.4	0.1	<0.05	3	4.1	<0.2
1277899	Soil	17	0.07	490	0.004	2	0.86	0.007	0.07	0.2	2.65	1.9	0.4	0.13	3	2.5	<0.2
1277900	Soil	14	0.02	200	0.003	2	0.56	0.003	0.05	0.2	0.68	0.6	0.2	<0.05	3	1.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277902	Soil	2.2	55.4	10.2	215	0.7	73.3	8.6	67	2.51	17.3	1.6	0.5	6	0.3	1.5	0.1	34	0.03	0.051	5
1277903	Soil	2.8	37.5	14.5	180	0.6	60.9	8.7	72	2.05	39.5	12.1	0.3	40	0.6	3.2	0.2	29	0.01	0.078	8
1277904	Soil	0.9	23.5	5.5	110	1.7	40.2	4.0	50	0.90	6.9	6.2	0.1	24	0.9	0.7	<0.1	12	0.28	0.062	4
1277905	Soil	5.2	36.9	14.9	77	2.7	21.6	3.1	70	1.72	36.3	7.2	0.4	45	0.3	2.1	0.2	28	0.26	0.062	4
1277906	Soil	5.1	30.1	20.2	106	1.4	24.2	4.5	103	2.59	98.7	19.6	0.5	28	0.3	4.9	0.6	53	0.03	0.078	9
1277907	Soil	4.8	126.8	47.9	195	1.4	45.3	12.4	383	5.63	93.0	9.7	1.7	39	0.5	5.2	0.6	52	0.04	0.139	9
1277908	Soil	7.8	39.0	38.8	127	2.2	24.2	4.8	85	2.23	264.0	34.6	4.0	39	0.5	54.8	1.5	33	0.04	0.056	21
1277909	Soil	2.2	55.3	12.7	140	4.0	67.9	9.8	164	2.61	14.3	9.8	1.7	51	1.0	1.7	0.2	18	1.08	0.097	8
1277910	Soil	2.8	36.9	12.6	201	2.6	71.9	10.5	116	2.69	19.1	11.7	1.3	66	0.7	2.3	0.2	17	1.10	0.070	4
1277911	Soil	3.3	55.3	16.5	275	3.7	143.8	19.2	164	4.17	22.7	4.6	3.4	73	1.5	2.1	0.2	19	0.93	0.180	8
1277912	Soil	10.7	36.5	26.6	246	2.1	53.5	6.2	66	2.52	106.9	32.5	1.8	82	0.7	7.9	0.7	87	0.11	0.099	12
1277913	Soil	1.1	34.6	4.6	72	1.2	35.9	3.9	55	1.18	5.5	4.9	0.2	20	0.3	0.6	<0.1	15	0.34	0.045	4
1277914	Soil	1.7	33.6	9.0	111	1.3	36.4	5.5	50	1.56	12.2	5.4	0.5	30	0.5	0.9	0.2	15	0.23	0.069	4
1277915	Soil	7.6	56.6	20.2	90	1.7	29.5	5.4	156	2.19	65.2	21.2	2.2	53	1.0	6.3	0.4	72	0.50	0.090	9
1277916	Soil	5.4	37.9	14.6	97	1.5	24.6	3.3	82	1.73	41.7	12.0	2.2	46	0.6	4.2	0.4	39	0.59	0.074	7
1277917	Soil	17.8	50.0	17.7	164	2.2	46.5	3.9	38	2.76	41.2	16.3	2.4	90	0.6	3.6	0.3	38	0.21	0.071	5
1277918	Soil	7.6	66.4	28.2	133	5.6	50.4	4.6	112	2.43	63.7	54.0	1.5	82	0.6	8.6	0.6	40	0.54	0.091	7
1277919	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1277920	Soil	2.8	19.6	18.5	47	2.5	11.8	1.9	47	0.95	42.4	55.3	0.5	36	0.3	7.3	0.5	26	0.23	0.058	7
1277921	Soil	4.7	33.8	21.2	94	2.1	24.1	4.5	107	1.60	77.4	21.7	1.0	39	0.5	4.6	0.5	57	0.17	0.098	7
1277922	Soil	0.9	13.9	16.3	23	1.3	11.2	4.2	85	0.40	19.7	20.9	<0.1	10	0.2	1.4	0.2	9	0.09	0.085	2
1277923	Soil	5.3	22.0	29.6	70	1.0	12.7	1.9	27	1.59	233.4	55.2	0.7	19	0.3	15.8	1.3	28	0.11	0.079	13
1277924	Soil	20.1	81.6	102.6	166	4.1	24.1	4.8	104	5.22	866.4	230.5	3.4	101	1.2	42.1	5.5	87	0.05	0.202	24
1277925	Soil	11.7	38.8	111.1	116	1.2	22.3	4.3	121	3.01	295.0	60.6	1.9	68	0.7	16.9	1.6	77	0.05	0.099	19
1277926	Soil	10.9	25.2	54.4	117	1.4	22.6	3.5	83	2.29	201.1	20.3	0.5	42	0.6	11.9	1.3	80	0.06	0.092	14
1277927	Soil	6.0	14.5	15.8	68	0.2	13.0	2.3	31	1.02	97.9	10.7	0.3	16	0.2	5.1	0.9	57	0.02	0.041	14
1277928	Soil	13.2	38.9	39.8	161	1.1	30.1	4.7	70	3.06	346.6	22.5	3.1	46	0.4	13.9	2.9	93	0.03	0.064	25
1277929	Soil	6.1	18.2	35.4	68	0.9	11.9	3.0	78	2.77	213.7	27.7	0.9	31	0.1	11.6	3.5	60	0.02	0.076	15
1277930	Soil	3.6	35.5	41.9	91	1.8	17.3	4.3	96	2.53	286.1	42.6	2.2	42	0.3	29.7	8.8	28	0.03	0.102	18
1277871	Soil	10.5	42.1	23.2	218	0.2	50.6	8.7	133	2.75	32.7	1.4	<0.1	44	1.0	7.2	0.3	75	0.03	0.121	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277902	Soil	14	0.01	98	0.002	2	0.29	0.002	0.03	<0.1	0.82	1.8	0.2	<0.05	1	1.1	<0.2
1277903	Soil	13	0.02	212	0.002	3	0.57	0.009	0.05	<0.1	1.60	0.5	0.2	<0.05	2	1.9	<0.2
1277904	Soil	7	0.02	451	0.003	3	0.55	0.021	0.04	<0.1	0.72	0.6	0.1	<0.05	1	1.0	<0.2
1277905	Soil	21	0.03	783	0.001	5	0.58	0.006	0.07	<0.1	0.95	1.6	0.1	0.05	2	5.0	<0.2
1277906	Soil	16	0.08	177	0.004	3	0.73	0.007	0.06	0.3	1.25	1.0	0.4	<0.05	3	2.9	<0.2
1277907	Soil	21	0.07	252	0.003	4	0.79	0.006	0.09	0.2	0.81	3.1	0.2	<0.05	3	3.4	<0.2
1277908	Soil	13	0.08	366	0.002	3	0.44	0.003	0.08	0.4	20.24	2.3	0.6	0.05	1	9.4	<0.2
1277909	Soil	19	0.08	493	0.001	3	0.76	0.005	0.05	<0.1	2.32	6.0	0.2	<0.05	2	2.8	<0.2
1277910	Soil	16	0.10	297	0.001	4	0.67	0.008	0.04	<0.1	2.72	3.7	0.1	0.09	2	3.4	<0.2
1277911	Soil	19	0.08	519	0.001	3	0.88	0.004	0.06	<0.1	1.28	6.8	0.1	0.09	1	2.9	<0.2
1277912	Soil	20	0.05	355	0.004	6	0.68	0.006	0.07	0.4	2.53	2.0	0.6	<0.05	3	2.7	<0.2
1277913	Soil	7	0.02	304	0.003	2	0.39	0.016	0.02	<0.1	0.38	1.4	<0.1	<0.05	1	1.4	<0.2
1277914	Soil	9	0.02	289	0.002	2	0.39	0.012	0.03	<0.1	0.55	2.3	<0.1	0.08	1	1.9	<0.2
1277915	Soil	16	0.10	719	0.001	3	0.74	0.005	0.05	0.2	2.63	2.7	0.4	0.06	2	4.0	<0.2
1277916	Soil	16	0.09	561	0.001	4	0.59	0.004	0.05	0.1	1.32	2.7	0.2	0.06	1	3.6	<0.2
1277917	Soil	25	0.04	541	<0.001	4	0.37	0.004	0.10	<0.1	0.45	2.4	0.2	0.21	2	5.0	<0.2
1277918	Soil	24	0.08	656	0.001	5	0.67	0.004	0.08	0.2	6.92	3.6	0.4	0.06	2	6.0	<0.2
1277919	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1277920	Soil	9	0.05	603	0.002	2	0.48	0.015	0.05	0.2	7.89	1.0	0.3	<0.05	2	3.7	<0.2
1277921	Soil	14	0.07	701	0.002	1	0.67	0.009	0.07	0.3	1.66	1.8	0.4	0.06	2	2.5	<0.2
1277922	Soil	14	0.02	196	0.001	2	0.27	0.019	0.03	<0.1	1.23	0.2	0.2	<0.05	<1	0.6	<0.2
1277923	Soil	6	0.03	117	0.005	4	0.37	0.013	0.07	0.5	4.34	0.6	0.7	<0.05	2	3.0	<0.2
1277924	Soil	21	0.12	395	0.004	4	0.85	0.012	0.18	2.1	20.47	1.7	3.6	0.40	3	11.3	0.3
1277925	Soil	17	0.14	289	0.006	3	0.90	0.005	0.08	0.4	3.22	1.4	0.9	0.08	4	4.3	0.2
1277926	Soil	14	0.09	219	0.005	3	0.61	0.007	0.07	0.4	1.80	0.7	0.6	<0.05	3	3.2	<0.2
1277927	Soil	7	0.02	123	0.004	2	0.30	0.009	0.04	0.4	0.84	0.4	0.3	<0.05	3	1.2	<0.2
1277928	Soil	14	0.11	215	0.003	2	0.68	0.004	0.06	0.7	3.38	1.2	0.5	<0.05	3	3.9	<0.2
1277929	Soil	13	0.07	137	0.004	2	0.60	0.004	0.05	0.5	4.36	0.7	0.4	<0.05	4	1.8	<0.2
1277930	Soil	10	0.06	191	0.005	3	0.64	0.016	0.08	4.5	4.02	0.7	0.5	0.13	2	4.9	<0.2
1277871	Soil	16	0.03	150	0.002	2	0.47	0.004	0.05	<0.1	0.03	0.2	0.2	<0.05	3	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277872	Soil		6.0	26.0	14.3	117	0.3	26.3	4.9	154	1.57	18.1	1.9	<0.1	52	0.6	4.3	0.1	45	0.08	0.136	5
1277873	Soil		6.7	53.1	19.4	303	0.9	70.4	7.9	135	2.40	25.0	2.6	0.3	53	1.9	8.7	0.2	47	0.36	0.127	6
1277874	Soil		3.1	33.0	9.7	207	0.3	32.3	4.0	143	1.23	22.5	2.3	0.2	43	3.2	4.8	<0.1	26	0.31	0.118	4
1277875	Soil		42.3	79.3	29.7	943	0.8	205.1	19.2	345	3.69	40.8	4.3	1.1	249	9.9	17.5	0.2	190	4.66	0.243	5
1277876	Soil		1.3	12.0	4.3	56	0.1	15.2	1.5	35	0.45	8.2	0.7	0.1	47	1.9	3.9	<0.1	11	0.87	0.058	3
1277877	Soil		15.2	29.7	17.6	188	0.2	44.8	6.3	122	2.24	60.1	2.6	0.2	25	0.8	23.3	0.2	77	0.10	0.090	9
1277878	Soil		4.9	58.3	16.8	169	0.8	60.3	13.5	247	3.25	119.8	3.4	0.6	47	0.9	17.6	0.2	41	0.56	0.108	5
1277879	Soil		6.6	17.8	15.1	94	0.4	23.2	3.1	55	1.26	18.1	1.6	<0.1	32	0.2	6.8	0.1	43	0.04	0.084	6
1277880	Soil		9.7	63.3	28.4	152	1.3	69.7	10.9	223	3.28	41.3	3.9	0.7	89	0.6	19.7	0.3	74	0.46	0.280	9
1278021	Soil		5.4	88.2	27.1	122	2.3	45.1	5.0	64	4.46	48.8	6.6	3.2	163	0.2	1.6	0.4	31	0.03	0.175	5
1278022	Soil		1.6	16.0	6.5	30	1.4	9.6	1.7	40	0.99	5.3	2.9	<0.1	7	0.1	0.7	0.1	25	0.02	0.045	4
1278023	Soil		4.5	25.2	44.6	106	1.0	20.7	3.1	50	1.98	16.9	1.3	0.5	47	0.1	0.7	0.5	34	0.02	0.109	20
1278024	Soil		8.1	21.6	26.4	66	0.9	17.9	4.6	26	1.75	22.5	1.2	0.2	34	0.3	2.2	0.4	96	<0.01	0.088	5
1278025	Soil		54.7	37.7	25.7	78	1.6	18.7	2.8	28	2.53	33.9	4.2	1.2	449	1.2	10.2	0.2	158	0.06	0.139	10
1278026	Soil		7.4	19.3	23.4	78	1.1	17.5	4.6	50	1.74	17.1	1.4	<0.1	26	0.3	4.4	0.3	53	0.01	0.075	5
1278027	Soil		20.4	22.1	15.9	90	0.7	21.9	3.6	56	1.84	18.4	2.7	0.3	32	0.4	4.1	0.2	110	0.02	0.066	11
1278028	Soil		158.0	121.7	28.8	919	0.8	446.3	18.1	624	3.89	74.9	2.3	2.7	190	7.0	13.2	0.2	149	4.87	0.161	18
1278029	Soil		10.0	49.6	61.4	125	1.3	36.5	4.6	52	1.96	12.4	3.7	<0.1	92	0.2	1.5	0.5	33	0.15	0.153	17
1278030	Soil		6.2	22.6	17.7	99	0.7	32.3	5.5	83	2.05	10.4	0.7	0.5	15	<0.1	1.3	0.2	40	0.03	0.047	12
1278031	Soil		3.4	35.3	24.9	132	0.2	28.1	9.1	100	4.15	6.0	2.6	5.8	12	<0.1	0.9	0.4	7	0.01	0.042	19
1278032	Soil		3.0	17.7	5.9	55	0.2	14.4	3.4	53	1.48	5.5	<0.5	0.2	4	<0.1	0.8	0.2	52	0.02	0.030	13
1278033	Soil		4.7	21.5	22.7	93	9.8	26.0	5.0	136	3.45	15.0	2.1	0.7	14	0.1	1.6	0.3	66	0.03	0.089	12
1278034	Soil		4.5	21.0	16.6	102	0.7	27.8	5.7	135	3.34	14.7	1.7	3.2	8	0.1	1.5	0.3	65	0.01	0.041	14
1278035	Soil		1.9	13.5	8.3	41	0.4	10.5	2.2	37	1.15	5.0	<0.5	<0.1	6	<0.1	0.6	0.1	28	0.02	0.034	6
1278036	Soil		3.3	34.5	13.5	93	1.2	22.8	4.6	102	2.21	8.0	0.6	0.2	10	0.4	1.0	0.2	48	0.02	0.069	13
1278037	Soil		4.0	22.4	13.5	103	<0.1	29.6	6.7	115	2.72	12.0	0.7	1.4	10	0.2	1.4	0.2	46	0.02	0.038	13
1278038	Soil		2.7	16.8	8.1	55	0.1	21.1	6.0	269	2.13	5.4	<0.5	1.5	6	0.2	0.8	0.2	32	0.05	0.034	11
1278039	Soil		10.5	61.4	25.0	214	0.5	77.0	13.7	179	3.91	23.9	3.8	3.6	21	0.2	2.0	0.3	34	0.16	0.117	27
1278040	Soil		6.8	43.9	18.1	124	1.0	45.4	9.4	610	2.16	12.8	1.9	1.1	34	0.4	1.7	0.2	35	0.48	0.096	15
1278041	Soil		12.7	80.4	38.9	175	2.1	61.0	11.8	329	2.93	27.6	5.5	1.3	63	0.6	2.8	0.3	58	0.54	0.175	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277872	Soil	12	0.03	242	0.001	2	0.58	0.013	0.05	<0.1	0.02	0.1	0.1	0.07	2	1.3	<0.2
1277873	Soil	22	0.08	243	0.004	2	0.54	0.012	0.05	<0.1	0.11	1.8	0.2	<0.05	2	2.4	<0.2
1277874	Soil	9	0.08	247	0.007	2	0.68	0.022	0.03	<0.1	0.03	0.8	<0.1	<0.05	2	1.2	<0.2
1277875	Soil	48	1.78	564	0.004	4	0.41	0.007	0.05	0.2	0.46	5.2	0.7	0.13	1	5.9	<0.2
1277876	Soil	3	0.09	96	0.009	1	0.53	0.025	0.02	<0.1	0.02	0.4	<0.1	0.10	1	1.2	<0.2
1277877	Soil	18	0.09	176	0.004	<1	0.67	0.003	0.05	0.2	<0.01	0.7	0.3	<0.05	3	1.3	<0.2
1277878	Soil	19	0.15	473	0.002	1	0.80	0.016	0.05	<0.1	0.07	3.6	0.2	<0.05	2	1.9	<0.2
1277879	Soil	10	0.04	83	0.003	1	0.29	0.010	0.04	0.1	<0.01	0.2	0.1	<0.05	2	1.1	<0.2
1277880	Soil	22	0.09	315	0.004	3	0.62	0.004	0.08	<0.1	0.11	2.1	0.2	<0.05	2	3.1	<0.2
1278021	Soil	23	0.02	341	0.002	2	0.87	0.009	0.25	<0.1	0.10	4.4	0.4	0.60	2	7.3	<0.2
1278022	Soil	11	0.03	97	0.005	1	0.63	0.014	0.04	<0.1	0.03	0.2	<0.1	<0.05	3	1.0	<0.2
1278023	Soil	11	0.05	274	<0.001	2	1.14	0.005	0.08	<0.1	<0.01	0.2	0.2	<0.05	4	1.7	<0.2
1278024	Soil	15	0.01	94	0.002	<1	0.38	0.004	0.05	<0.1	0.03	0.5	0.3	<0.05	2	1.6	<0.2
1278025	Soil	24	0.02	674	0.001	3	0.47	0.005	0.13	0.5	0.18	3.1	3.1	0.34	2	11.0	0.2
1278026	Soil	11	0.03	179	<0.001	<1	0.53	0.005	0.04	<0.1	0.02	0.2	0.3	<0.05	3	1.3	<0.2
1278027	Soil	14	0.07	209	0.003	2	0.51	0.003	0.06	0.2	0.07	0.5	1.0	0.08	2	2.7	<0.2
1278028	Soil	25	2.30	409	0.004	10	0.43	0.005	0.12	0.6	0.42	4.8	5.1	0.08	1	4.8	0.2
1278029	Soil	13	0.07	691	<0.001	3	0.60	0.005	0.13	<0.1	0.06	0.1	0.4	0.24	2	2.9	0.2
1278030	Soil	18	0.04	259	0.003	5	0.45	0.006	0.09	<0.1	0.03	0.5	0.2	0.15	3	1.2	<0.2
1278031	Soil	6	0.02	184	<0.001	5	0.41	0.001	0.12	<0.1	0.04	2.4	0.2	0.12	<1	3.7	<0.2
1278032	Soil	11	0.05	194	0.005	2	0.70	0.006	0.06	0.1	0.02	0.3	0.2	<0.05	5	<0.5	<0.2
1278033	Soil	28	0.13	440	0.008	4	1.13	0.004	0.11	0.2	0.09	0.8	0.3	0.05	5	1.4	<0.2
1278034	Soil	19	0.12	312	0.004	3	1.21	0.003	0.10	0.2	0.04	1.5	0.3	<0.05	5	1.2	<0.2
1278035	Soil	7	0.04	122	0.004	2	0.57	0.012	0.05	<0.1	0.02	0.2	0.1	<0.05	3	<0.5	<0.2
1278036	Soil	16	0.09	754	0.002	3	1.07	0.005	0.10	0.1	0.05	0.2	0.2	<0.05	4	1.1	<0.2
1278037	Soil	14	0.10	440	0.007	3	0.81	0.004	0.12	0.1	0.02	1.2	0.2	<0.05	4	0.9	<0.2
1278038	Soil	13	0.06	270	0.004	3	0.71	0.006	0.10	0.1	0.02	1.0	0.2	<0.05	3	<0.5	<0.2
1278039	Soil	13	0.09	675	0.001	5	0.76	0.002	0.14	<0.1	0.20	3.0	0.2	<0.05	2	2.3	0.2
1278040	Soil	14	0.15	1119	0.003	6	0.68	0.010	0.14	<0.1	0.20	1.7	0.2	0.16	2	1.9	<0.2
1278041	Soil	16	0.12	1146	0.001	7	0.77	0.004	0.18	<0.1	0.64	2.3	0.5	0.13	2	2.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278042	Soil		20.8	44.8	16.9	421	0.7	70.0	7.2	207	2.56	24.1	3.3	1.8	43	2.2	4.6	0.2	279	0.62	0.123	17
1278043	Soil		11.5	30.7	18.4	169	0.2	37.8	4.9	83	2.07	16.3	2.8	0.7	15	0.4	2.4	0.2	87	0.06	0.057	14
1278044	Soil		12.0	47.9	21.0	255	0.5	57.3	9.5	276	2.92	19.3	5.4	2.5	38	1.0	3.1	0.2	97	0.38	0.135	15
1278045	Soil		10.0	64.4	24.4	297	0.9	75.1	11.0	353	3.38	20.7	5.6	4.2	59	2.3	3.3	0.2	115	0.58	0.150	14
1278046	Soil		11.3	51.6	19.7	251	0.7	55.7	7.3	175	2.75	18.8	5.4	4.1	43	1.3	3.5	0.2	96	0.45	0.171	19
1278047	Soil		9.9	34.1	22.2	146	1.0	40.9	4.5	117	1.90	12.5	3.0	0.4	35	0.7	2.0	0.2	95	0.38	0.104	8
1278048	Soil		3.1	16.9	106.7	49	0.9	12.1	1.1	39	1.25	3.6	4.2	1.1	78	0.3	0.9	0.4	31	0.29	0.069	16
1278049	Soil		21.9	22.7	25.1	195	0.4	47.2	4.9	88	2.41	21.1	0.8	1.6	18	0.5	3.0	0.2	193	0.15	0.061	13
1278050	Soil		13.4	14.2	12.2	86	0.1	21.2	2.4	44	1.11	13.2	0.6	0.2	9	0.3	2.1	0.2	166	0.02	0.042	16
1278051	Soil		3.9	81.7	25.2	139	1.6	41.1	10.1	225	4.18	30.3	2.9	1.1	17	0.2	1.4	0.3	37	0.05	0.195	5
1278052	Soil		5.2	35.6	15.0	95	0.7	24.1	4.7	174	2.78	18.8	3.1	<0.1	19	0.2	1.7	0.2	38	0.03	0.146	5
1278053	Soil		112.9	45.0	68.6	96	2.6	16.1	1.9	54	2.78	40.6	1.3	1.2	101	0.5	22.5	0.4	304	0.07	0.220	11
1278054	Soil		141.7	120.9	31.1	2655	1.5	294.6	6.1	261	2.74	65.6	1.2	0.9	437	13.8	24.7	0.1	476	13.98	0.106	3
1278055	Soil		117.7	160.7	39.2	2972	1.3	310.9	21.5	434	4.91	58.4	1.6	1.0	222	17.4	20.2	0.1	457	4.80	0.170	6
1278056	Soil		91.7	64.1	22.0	685	0.3	217.3	10.7	286	2.49	21.4	0.6	1.8	151	4.4	6.3	0.1	88	8.51	0.107	3
1278057	Soil		31.9	183.0	13.6	978	0.4	816.3	116.3	1070	8.52	371.0	1.7	7.0	293	1.8	14.3	<0.1	258	4.36	0.521	46
1278058	Soil		131.9	95.4	10.3	992	1.1	300.3	5.8	109	1.81	46.8	<0.5	2.0	327	9.0	24.3	0.1	310	9.73	0.077	2
1278059	Soil		56.5	113.9	38.4	1632	2.6	341.2	35.4	694	6.96	65.9	2.0	1.5	149	23.4	27.2	0.1	238	2.59	0.205	5
1278060	Soil		164.6	71.3	51.3	321	2.7	47.1	1.4	16	1.98	43.9	1.5	0.3	63	1.6	23.0	0.2	306	0.06	0.068	1
1278061	Soil		174.2	78.8	108.7	374	2.7	71.1	3.1	37	2.87	50.2	2.1	0.3	322	1.3	27.2	0.3	338	0.14	0.277	3
1278062	Soil		60.3	59.8	52.0	535	0.7	79.0	10.7	342	3.80	29.2	2.0	0.2	99	2.4	12.7	0.3	203	0.04	0.152	4
1278063	Soil		37.8	66.8	54.4	1127	1.1	220.1	23.7	668	5.28	53.8	2.0	0.7	171	10.8	16.2	0.3	148	2.53	0.154	5
1278064	Soil		29.3	62.1	70.8	649	1.3	161.5	20.3	506	4.68	21.4	3.9	0.9	75	5.4	10.0	0.2	140	0.57	0.125	5
1278065	Soil		28.4	16.0	33.0	37	0.9	10.7	0.7	25	0.86	14.5	3.1	0.3	30	1.3	7.5	0.2	32	0.04	0.022	1
1278066	Soil		13.0	161.2	72.0	598	1.5	104.2	17.4	444	4.58	44.1	4.8	0.7	639	7.0	10.5	0.5	77	0.35	0.406	5
1278067	Soil		12.3	190.8	108.4	557	3.4	115.0	13.1	488	4.66	60.6	6.8	0.7	1436	11.0	13.6	0.5	130	0.82	0.746	6
1278068	Soil		19.1	75.9	119.0	87	3.7	14.6	1.0	20	1.52	13.7	9.3	1.0	758	0.5	6.4	0.6	107	0.60	0.518	5
1278069	Soil		39.3	100.5	1033	157	9.1	24.4	2.7	61	3.11	47.6	6.1	0.5	1173	2.9	17.7	0.5	763	0.32	0.624	9
1278070	Soil		9.7	71.4	188.2	37	6.6	8.6	0.8	16	1.37	14.9	14.3	0.4	1632	0.5	12.5	0.9	159	0.10	0.422	10
1278071	Soil		4.8	142.2	44.9	726	1.2	179.6	20.0	524	3.15	53.2	2.4	2.7	137	0.5	8.4	0.3	33	2.85	0.080	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278042	Soil	27	0.20	992	0.004	6	0.96	0.006	0.15	0.2	0.18	1.8	0.9	0.08	3	2.3	<0.2
1278043	Soil	14	0.06	533	0.001	2	0.67	0.003	0.09	0.1	0.07	0.6	0.3	<0.05	3	1.3	<0.2
1278044	Soil	21	0.17	1027	0.003	5	0.99	0.005	0.14	0.1	0.22	2.0	0.4	0.06	3	1.8	<0.2
1278045	Soil	25	0.25	1435	0.002	6	1.24	0.007	0.21	0.1	0.39	3.2	0.5	0.09	3	2.2	<0.2
1278046	Soil	17	0.18	1363	0.004	5	0.82	0.005	0.14	0.1	0.30	2.3	0.4	0.11	2	2.0	<0.2
1278047	Soil	18	0.13	1050	0.002	4	0.97	0.016	0.14	0.1	0.24	0.6	0.4	0.10	3	1.3	<0.2
1278048	Soil	10	0.04	694	0.002	5	0.32	0.003	0.17	<0.1	0.10	0.5	0.2	0.30	1	1.8	<0.2
1278049	Soil	19	0.08	461	0.002	2	0.95	0.003	0.09	0.2	0.05	1.1	0.7	0.06	4	1.2	<0.2
1278050	Soil	14	0.05	183	0.003	2	0.63	0.003	0.07	0.2	0.04	0.2	0.5	<0.05	4	0.7	<0.2
1278051	Soil	18	0.08	167	0.002	1	0.80	0.005	0.10	<0.1	0.11	1.4	0.2	0.13	3	3.1	<0.2
1278052	Soil	16	0.06	165	<0.001	2	0.60	0.007	0.09	0.1	0.13	<0.1	0.2	0.16	2	2.5	<0.2
1278053	Soil	25	0.03	400	0.003	3	0.54	0.013	0.18	1.0	0.26	0.8	4.4	0.48	4	30.8	0.4
1278054	Soil	20	1.55	192	0.002	3	0.24	0.006	0.05	0.1	0.73	2.5	1.2	0.14	<1	10.1	<0.2
1278055	Soil	25	0.90	426	0.001	3	0.47	0.005	0.06	<0.1	1.39	3.6	1.0	0.22	2	8.1	<0.2
1278056	Soil	14	3.37	190	<0.001	4	0.25	0.005	0.05	<0.1	0.32	3.6	0.8	0.16	<1	3.2	<0.2
1278057	Soil	234	2.23	554	<0.001	3	1.77	0.004	0.07	<0.1	0.18	15.8	0.6	0.19	7	2.5	<0.2
1278058	Soil	10	1.72	152	0.001	3	0.19	0.004	0.05	0.3	0.59	2.1	1.4	0.19	<1	7.6	<0.2
1278059	Soil	91	1.13	384	0.001	2	0.48	0.005	0.06	0.1	0.84	9.6	0.8	0.18	1	7.3	<0.2
1278060	Soil	11	0.01	222	<0.001	<1	0.27	0.003	0.10	0.1	0.77	1.4	2.0	0.30	1	19.9	0.5
1278061	Soil	20	0.02	329	0.001	<1	0.49	0.003	0.10	0.2	0.68	1.3	2.4	0.25	2	20.2	0.5
1278062	Soil	16	0.03	157	0.002	<1	0.47	0.007	0.06	<0.1	0.05	1.3	0.8	0.07	2	6.8	<0.2
1278063	Soil	50	1.00	415	0.002	<1	0.41	0.007	0.10	<0.1	0.30	3.1	0.8	0.28	2	8.1	<0.2
1278064	Soil	72	0.09	443	0.002	1	0.42	0.004	0.06	0.1	0.63	6.1	0.6	0.15	1	5.2	<0.2
1278065	Soil	3	<0.01	700	<0.001	<1	0.17	0.001	0.09	0.2	0.59	0.6	1.4	0.24	<1	6.0	<0.2
1278066	Soil	22	0.05	682	0.001	2	0.62	0.004	0.06	<0.1	0.21	3.6	0.3	0.14	2	4.6	<0.2
1278067	Soil	36	0.08	1328	0.003	4	0.88	0.012	0.08	<0.1	0.57	4.3	0.4	0.19	3	8.0	<0.2
1278068	Soil	26	0.08	574	0.002	4	0.69	0.005	0.10	<0.1	0.35	1.6	0.4	0.24	3	7.2	0.3
1278069	Soil	48	0.08	974	0.005	4	0.92	0.004	0.15	0.3	1.73	0.8	0.8	0.34	5	7.5	0.5
1278070	Soil	50	0.03	2298	0.006	9	0.68	0.003	0.11	<0.1	1.50	0.7	0.8	0.24	3	7.6	0.5
1278071	Soil	22	1.47	269	<0.001	3	0.15	0.003	0.04	<0.1	0.24	7.2	0.2	<0.05	<1	3.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278072	Soil	1.7	81.1	36.0	227	0.7	75.4	19.9	306	7.77	10.5	5.9	1.0	11	<0.1	3.5	0.7	25	0.09	0.101	4
1278073	Soil	94.0	77.5	97.2	220	4.1	37.6	4.6	116	3.11	66.5	3.8	0.2	173	1.0	116.0	0.5	925	0.03	0.149	6
1278074	Soil	9.6	37.0	48.2	155	0.4	39.2	5.3	61	2.06	49.7	2.1	<0.1	139	0.6	18.9	0.5	87	0.03	0.190	9
1278075	Soil	3.6	47.6	331.5	543	1.0	58.9	15.3	328	4.55	1805	210.3	0.5	31	2.5	604.9	0.1	43	0.09	0.112	5
1278076	Soil	15.8	63.7	37.4	228	0.5	83.8	14.6	227	4.25	71.9	1.4	0.3	67	1.1	25.7	0.4	90	0.02	0.163	9
1278077	Soil	4.8	127.4	91.3	358	0.7	89.1	25.4	725	6.43	1721	12.3	0.9	97	3.8	61.2	0.2	67	0.18	0.145	11
1278078	Soil	7.2	51.4	46.7	216	0.8	41.7	6.3	183	2.17	118.0	7.8	0.2	86	2.5	45.4	0.2	61	0.11	0.194	8
1278079	Soil	5.4	22.6	40.6	106	0.4	23.6	4.6	171	1.56	44.6	2.2	0.2	65	0.9	21.0	0.2	47	0.20	0.142	8
1278080	Soil	12.9	67.6	32.5	221	1.0	92.9	15.9	368	3.83	49.1	15.2	0.8	76	1.6	80.7	0.3	78	0.32	0.176	16
1278081	Soil	15.0	99.9	31.3	177	0.8	126.6	13.1	114	3.47	74.6	6.1	1.3	50	0.5	46.5	0.4	51	0.58	0.223	15
1278082	Soil	0.3	6.3	1.1	33	<0.1	5.1	0.5	27	0.18	0.6	<0.5	<0.1	23	0.6	0.4	<0.1	6	0.36	0.024	1
1278083	Soil	37.1	31.5	14.3	478	0.2	99.0	10.3	254	2.73	17.7	1.8	2.3	81	3.8	20.5	0.1	142	3.49	0.050	7
1278084	Soil	13.4	11.0	9.8	128	0.1	33.2	2.3	52	0.74	6.8	0.7	0.2	16	1.1	4.3	<0.1	27	0.22	0.037	3
1278085	Soil	76.6	85.8	12.3	342	0.2	164.7	10.8	227	2.09	19.4	2.1	2.8	163	2.8	11.5	0.2	42	6.72	0.091	7
1278086	Soil	49.5	46.3	22.3	294	0.3	137.9	9.7	528	2.05	15.7	1.6	1.1	46	2.8	14.4	0.2	68	2.23	0.080	9
1278087	Soil	22.8	34.4	8.9	292	0.3	66.1	5.0	417	0.92	12.2	0.6	0.3	68	12.9	8.8	0.1	128	1.99	0.070	9
1278088	Soil	11.5	183.6	38.6	201	1.1	488.2	111.9	1361	13.27	16.9	1.3	11.9	130	1.6	5.1	<0.1	204	3.42	0.419	23
1278089	Soil	17.6	173.9	49.8	136	1.1	486.5	111.6	1347	10.91	49.7	3.7	8.9	141	1.2	9.3	0.1	207	1.80	0.418	22
1278090	Soil	32.8	142.3	43.1	183	1.1	415.4	76.1	817	8.90	27.7	1.8	4.2	101	1.1	7.0	0.1	232	1.05	0.379	20
1278091	Soil	49.6	126.7	20.9	1109	1.2	358.2	48.9	1233	8.28	31.2	2.7	1.3	130	13.9	6.9	0.1	290	0.68	0.353	10
1278092	Soil	27.0	95.8	57.9	522	0.4	307.9	52.9	519	6.70	45.0	0.8	0.8	108	1.9	6.9	0.1	142	0.42	0.298	8
1278093	Soil	82.8	82.3	39.2	1006	0.2	327.6	31.2	467	4.99	20.6	0.6	0.4	45	12.3	8.7	0.2	221	0.23	0.170	5
1278094	Soil	74.7	56.4	26.5	592	0.2	172.0	19.7	472	3.74	24.2	2.6	0.4	37	3.8	8.4	0.2	223	0.15	0.169	6
1278095	Soil	31.5	75.4	16.5	723	0.3	222.6	32.0	670	7.14	13.4	0.5	0.3	32	3.3	4.9	0.1	177	0.11	0.194	5
1278096	Soil	25.9	77.6	25.9	469	<0.1	121.3	17.7	167	3.87	29.8	2.2	0.2	28	1.0	7.5	0.3	127	0.07	0.127	5
1278097	Soil	12.8	23.1	9.8	151	0.1	34.3	4.7	89	1.45	13.2	<0.5	<0.1	19	0.2	3.2	0.1	71	0.02	0.078	2
1278098	Soil	4.8	12.6	69.0	47	0.4	9.9	1.3	14	0.57	9.4	1.3	0.1	90	0.1	4.4	0.3	41	0.02	0.055	3
1278099	Soil	15.6	20.8	31.8	122	0.3	32.1	4.7	75	1.65	16.1	0.7	<0.1	35	0.2	7.6	0.2	79	<0.01	0.065	5
1278100	Soil	11.6	27.3	67.1	128	0.6	28.2	4.1	60	1.92	46.1	2.9	0.3	102	0.4	12.8	0.2	82	0.03	0.105	5
1278101	Soil	20.1	43.9	15.5	284	0.9	59.6	6.5	205	2.07	19.8	3.5	1.5	55	1.4	4.8	0.2	177	0.76	0.101	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278072	Soil	11	0.07	164	0.001	2	0.35	0.002	0.04	<0.1	0.16	6.1	0.2	0.07	<1	0.8	0.2
1278073	Soil	23	0.02	387	0.003	3	0.51	0.004	0.10	0.3	0.21	0.5	0.8	0.23	3	4.4	0.6
1278074	Soil	14	0.02	362	0.002	3	0.51	0.007	0.07	<0.1	0.03	0.2	0.2	0.10	3	1.6	<0.2
1278075	Soil	19	0.04	388	0.002	1	0.85	0.007	0.05	0.1	0.15	8.3	0.2	0.07	2	1.3	<0.2
1278076	Soil	22	0.03	295	0.003	2	0.37	0.002	0.07	<0.1	0.03	0.7	0.5	0.07	2	2.6	<0.2
1278077	Soil	29	0.09	2245	0.001	2	0.98	0.006	0.10	<0.1	0.12	13.2	0.3	0.07	2	1.6	<0.2
1278078	Soil	16	0.04	429	0.002	2	0.61	0.010	0.06	0.1	0.06	0.5	0.3	0.09	2	1.8	<0.2
1278079	Soil	15	0.07	320	0.002	2	0.50	0.007	0.07	0.1	0.03	0.3	0.2	0.06	2	0.9	<0.2
1278080	Soil	21	0.16	478	0.005	2	0.66	0.004	0.07	0.1	0.28	2.3	0.3	<0.05	2	2.2	<0.2
1278081	Soil	13	0.07	396	0.001	5	0.41	0.003	0.12	<0.1	0.17	2.5	0.3	0.05	1	2.3	<0.2
1278082	Soil	1	0.06	70	0.008	<1	0.41	0.047	0.02	<0.1	0.04	0.5	<0.1	0.05	<1	<0.5	<0.2
1278083	Soil	13	1.84	161	0.002	3	0.20	0.005	0.04	<0.1	0.21	3.6	0.6	<0.05	<1	1.4	<0.2
1278084	Soil	8	0.03	140	0.005	1	0.40	0.021	0.02	<0.1	0.12	0.5	0.3	0.06	1	0.7	<0.2
1278085	Soil	16	2.40	227	0.004	4	0.31	0.006	0.04	0.2	0.28	3.9	1.0	0.05	<1	1.8	<0.2
1278086	Soil	17	1.02	285	0.006	5	0.59	0.015	0.11	0.2	0.08	2.2	1.2	0.07	1	2.8	<0.2
1278087	Soil	14	0.19	228	0.005	3	0.52	0.019	0.03	0.1	0.13	1.0	0.4	0.13	1	3.2	<0.2
1278088	Soil	346	0.22	415	0.005	3	0.58	0.006	0.06	0.1	0.39	36.0	0.2	0.18	2	1.8	<0.2
1278089	Soil	249	0.25	405	0.002	2	0.71	0.005	0.07	<0.1	0.25	28.2	0.4	0.07	3	1.8	<0.2
1278090	Soil	178	0.17	392	0.003	2	0.82	0.005	0.05	0.1	0.33	20.6	0.5	0.07	3	2.5	<0.2
1278091	Soil	174	0.16	847	0.005	2	0.76	0.004	0.05	0.1	0.38	16.2	0.7	<0.05	3	4.3	<0.2
1278092	Soil	118	0.07	424	0.004	<1	0.54	0.005	0.04	0.1	0.08	5.7	0.4	0.07	3	2.8	<0.2
1278093	Soil	69	0.06	304	0.002	1	0.47	0.002	0.04	0.1	0.17	3.9	0.8	<0.05	2	8.2	<0.2
1278094	Soil	52	0.07	217	0.003	1	0.61	0.002	0.05	0.2	0.14	2.4	1.0	<0.05	2	4.9	<0.2
1278095	Soil	148	0.07	164	0.003	<1	0.57	0.008	0.03	<0.1	0.09	5.9	0.5	<0.05	2	4.9	<0.2
1278096	Soil	49	0.03	105	0.002	<1	0.39	0.003	0.04	<0.1	0.03	1.1	0.3	<0.05	3	2.8	<0.2
1278097	Soil	15	0.02	46	0.003	<1	0.41	0.013	0.02	<0.1	0.03	0.3	<0.1	<0.05	3	1.1	<0.2
1278098	Soil	9	<0.01	70	0.002	<1	0.21	0.004	0.03	<0.1	0.04	0.2	0.3	<0.05	2	1.1	<0.2
1278099	Soil	20	0.02	89	0.003	<1	0.24	0.005	0.04	0.1	0.02	0.3	0.4	0.05	2	1.8	<0.2
1278100	Soil	17	0.05	129	0.003	1	0.50	0.009	0.04	<0.1	0.06	0.4	0.5	0.06	3	2.6	<0.2
1278101	Soil	26	0.16	1026	0.002	4	0.88	0.010	0.14	0.1	0.27	2.2	0.5	<0.05	3	1.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278102	Soil	14.8	46.5	24.9	236	0.5	57.4	7.7	123	3.03	22.4	4.7	1.3	22	0.5	3.9	0.4	66	0.04	0.122	9
1278103	Soil	8.2	20.1	20.4	146	0.1	31.7	6.0	133	2.34	15.5	0.9	0.8	12	0.2	1.9	0.4	67	0.02	0.064	10
1278104	Soil	30.9	74.9	24.7	208	5.0	64.8	13.6	103	2.71	17.2	1.3	0.2	20	1.9	6.7	0.4	109	0.02	0.196	12
1278105	Soil	11.1	26.9	16.1	207	0.3	29.3	4.0	44	1.71	16.8	1.7	0.3	10	0.3	2.8	0.2	71	<0.01	0.047	10
1278106	Soil	1.8	11.7	7.5	29	0.1	7.7	1.6	21	0.90	63.0	1.6	<0.1	7	0.1	2.0	0.2	20	0.01	0.052	4
1278107	Soil	0.5	6.1	2.7	10	<0.1	2.5	0.7	16	0.41	6.1	<0.5	<0.1	5	<0.1	0.3	0.1	9	0.03	0.043	2
1278108	Soil	1.6	26.6	17.0	114	0.6	39.0	11.0	262	2.65	13.9	2.2	1.2	30	0.3	0.7	0.2	28	0.35	0.114	6
1278109	Soil	2.2	34.2	12.0	163	0.9	53.7	10.2	365	3.32	13.2	3.3	0.6	64	1.4	1.3	0.2	45	1.45	0.175	16
1278110	Soil	2.3	38.5	13.9	154	0.9	49.2	8.3	251	2.64	18.8	3.5	1.2	59	1.2	1.7	0.2	45	1.35	0.150	17
1278111	Soil	1.5	20.4	9.1	95	0.9	28.4	4.7	256	2.07	7.8	2.2	0.6	59	0.7	0.9	0.2	40	1.73	0.183	25
1278112	Soil	2.6	28.4	12.2	104	0.2	27.0	6.6	160	2.64	10.6	1.9	0.4	11	0.4	1.4	0.2	44	0.07	0.084	11
1278113	Soil	1.3	18.4	7.9	63	0.6	20.6	5.0	148	1.45	5.8	2.3	0.3	14	0.2	0.5	0.1	19	0.14	0.093	5
1278114	Soil	3.1	37.8	18.2	126	0.4	43.1	8.5	263	2.84	35.0	3.5	1.6	18	0.3	1.5	0.3	48	0.04	0.093	11
1278115	Soil	3.2	30.8	12.5	96	0.3	28.2	6.8	174	2.31	15.3	3.2	0.7	16	0.3	1.5	0.2	45	0.08	0.067	11
1278116	Soil	3.0	21.0	9.0	56	0.1	12.9	3.2	102	1.52	11.3	1.7	0.1	7	0.1	1.2	0.4	49	0.02	0.057	8
1278117	Soil	3.6	40.2	11.5	116	0.4	33.3	7.6	216	2.59	16.9	4.6	2.1	22	0.4	1.6	0.2	44	0.14	0.078	15
1278118	Soil	3.1	52.4	15.3	101	0.6	27.2	7.2	217	2.79	19.0	2.9	0.3	20	0.3	1.4	0.2	36	0.04	0.080	7
1278119	Soil	2.6	30.8	14.4	71	0.2	17.2	4.1	195	2.68	17.6	1.5	0.2	11	0.1	1.1	0.3	37	0.02	0.100	6
1278120	Soil	2.9	24.6	11.9	63	0.3	16.7	4.0	127	2.17	13.3	3.0	0.3	14	0.2	1.2	0.3	44	0.05	0.086	10
1278121	Soil	6.2	21.3	28.9	131	0.2	32.0	5.7	56	2.72	22.8	1.7	0.4	10	0.2	2.2	0.2	21	<0.01	0.040	3
1278122	Soil	5.2	155.9	38.1	183	2.2	73.9	25.6	400	4.39	45.0	7.9	4.0	190	0.6	2.5	0.3	39	0.10	0.152	6
1278123	Soil	5.2	117.1	35.7	186	4.3	67.2	30.6	771	5.28	42.0	4.8	3.2	125	0.4	1.8	0.3	28	0.04	0.200	4
1278124	Soil	4.1	105.8	46.1	160	4.4	55.9	36.3	959	4.47	32.5	5.4	2.8	88	0.3	1.4	0.3	26	0.05	0.201	4
1278125	Soil	4.7	96.9	29.3	134	4.4	44.9	17.7	426	3.63	18.6	4.5	2.5	80	0.2	1.4	0.3	26	0.03	0.134	4
1278126	Soil	2.7	107.8	25.6	175	1.1	62.4	27.4	502	3.32	13.9	5.1	3.0	103	0.2	1.3	0.3	25	0.08	0.076	6
1278127	Soil	2.7	140.0	31.7	227	1.7	105.6	45.6	1807	4.74	14.8	8.7	3.2	62	0.4	1.4	0.4	29	0.12	0.120	9
1278128	Soil	3.5	112.3	35.5	188	1.5	71.1	41.6	1696	4.32	14.9	9.5	2.6	48	0.3	1.4	0.4	29	0.09	0.129	7
1278129	Soil	3.3	87.6	25.9	168	1.2	63.5	25.7	958	3.83	12.3	7.8	2.1	49	0.2	1.3	0.3	25	0.10	0.112	6
1278130	Soil	5.0	135.0	47.5	176	1.1	63.7	54.6	3301	4.70	22.8	12.8	2.2	36	0.3	1.7	0.4	34	0.07	0.145	8
1278131	Soil	3.9	91.6	21.3	192	1.3	86.4	16.4	390	4.20	15.1	9.0	3.7	65	0.2	1.5	0.3	21	0.24	0.083	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278102	Soil	14	0.07	379	0.002	3	0.57	0.002	0.05	0.1	0.07	1.6	0.3	0.07	2	2.0	<0.2
1278103	Soil	9	0.04	90	0.009	2	0.57	0.003	0.03	0.2	0.01	1.1	0.2	<0.05	4	0.8	<0.2
1278104	Soil	14	0.04	307	0.004	2	0.76	0.003	0.05	0.3	0.16	0.6	0.3	0.08	3	1.7	<0.2
1278105	Soil	7	0.02	87	0.003	2	0.32	0.001	0.03	0.1	0.02	0.7	0.2	<0.05	3	1.1	<0.2
1278106	Soil	11	0.02	67	0.003	2	0.31	0.002	0.02	0.1	0.62	0.3	<0.1	0.07	2	0.6	<0.2
1278107	Soil	4	0.02	33	0.005	<1	0.49	0.016	0.02	<0.1	0.05	0.2	<0.1	<0.05	1	<0.5	<0.2
1278108	Soil	21	0.17	384	0.002	2	1.00	0.006	0.05	<0.1	0.06	2.5	0.1	0.07	3	1.0	<0.2
1278109	Soil	31	0.20	453	0.004	4	0.90	0.007	0.04	0.2	0.17	1.4	<0.1	0.14	2	2.0	<0.2
1278110	Soil	29	0.24	394	0.006	3	0.95	0.008	0.05	0.2	0.30	2.2	0.1	0.08	3	1.2	<0.2
1278111	Soil	29	0.14	364	0.004	2	0.81	0.006	0.03	0.2	0.16	1.7	<0.1	0.15	2	1.4	<0.2
1278112	Soil	21	0.18	114	0.005	<1	1.01	0.004	0.03	0.4	0.06	0.7	0.1	<0.05	3	1.1	<0.2
1278113	Soil	14	0.09	258	0.003	2	0.87	0.012	0.03	0.1	0.09	0.7	<0.1	0.07	2	0.9	<0.2
1278114	Soil	25	0.25	223	0.005	2	1.25	0.005	0.07	0.2	0.11	2.1	0.2	<0.05	4	1.5	<0.2
1278115	Soil	18	0.21	142	0.009	1	0.93	0.004	0.05	0.2	0.10	1.0	0.2	<0.05	3	1.4	<0.2
1278116	Soil	11	0.04	80	0.006	1	0.67	0.007	0.04	0.2	0.05	0.3	0.2	0.06	4	0.7	<0.2
1278117	Soil	21	0.30	137	0.017	2	0.93	0.004	0.05	0.3	0.38	1.7	0.2	<0.05	3	1.4	<0.2
1278118	Soil	19	0.13	111	0.006	1	0.88	0.007	0.06	0.1	0.10	0.5	0.1	0.08	3	1.7	<0.2
1278119	Soil	17	0.09	79	0.005	1	0.84	0.008	0.04	0.1	0.04	0.4	0.1	0.08	4	1.4	<0.2
1278120	Soil	19	0.15	100	0.007	1	0.93	0.004	0.05	0.2	0.06	0.5	0.2	<0.05	4	1.0	<0.2
1278121	Soil	6	0.02	94	<0.001	<1	0.30	0.002	0.03	<0.1	0.09	1.6	0.2	<0.05	<1	1.4	<0.2
1278122	Soil	38	0.11	568	0.001	3	0.93	0.007	0.14	<0.1	0.18	5.9	0.2	0.13	3	6.1	0.2
1278123	Soil	44	0.14	423	0.001	3	1.30	0.010	0.10	<0.1	0.27	6.0	0.3	0.18	3	6.2	<0.2
1278124	Soil	37	0.21	338	0.002	4	1.29	0.009	0.11	<0.1	0.25	5.6	0.3	0.14	3	4.3	<0.2
1278125	Soil	40	0.21	354	0.001	4	1.30	0.006	0.10	<0.1	0.33	4.7	0.3	0.10	3	4.4	<0.2
1278126	Soil	30	0.40	925	0.003	2	1.31	0.009	0.07	<0.1	0.17	3.5	0.2	0.09	3	1.9	<0.2
1278127	Soil	34	0.41	1478	0.003	4	1.72	0.005	0.08	<0.1	0.23	5.1	0.2	0.08	3	2.2	<0.2
1278128	Soil	36	0.37	1309	0.003	3	1.65	0.006	0.07	<0.1	0.21	4.3	0.2	0.06	4	1.9	<0.2
1278129	Soil	32	0.36	1595	0.002	3	1.35	0.007	0.08	<0.1	0.18	3.3	0.2	0.07	3	1.6	<0.2
1278130	Soil	34	0.41	1306	0.005	4	1.57	0.009	0.08	<0.1	0.16	4.3	0.2	0.10	4	2.2	<0.2
1278131	Soil	30	0.38	4249	0.002	3	1.23	0.005	0.06	<0.1	0.33	6.4	<0.1	<0.05	2	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278132	Soil		3.8	48.8	23.3	111	0.8	45.8	10.9	489	2.77	9.1	3.1	0.6	26	0.3	1.0	0.3	18	0.08	0.122	4
1278133	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1278134	Soil		3.5	79.3	29.0	138	1.5	44.6	25.9	925	3.87	16.5	6.6	1.8	61	0.3	1.2	0.3	35	0.05	0.121	6
1278135	Soil		3.1	39.9	20.1	105	0.6	31.2	12.6	595	3.51	15.9	3.8	1.8	34	0.2	1.0	0.4	45	0.05	0.087	7
1278136	Soil		5.1	110.6	29.6	115	0.3	31.1	17.2	546	4.38	17.5	55.5	1.5	28	0.2	2.1	0.5	56	0.03	0.116	5
1278137	Soil		4.8	34.7	11.5	42	0.2	13.8	2.5	66	1.39	6.6	7.9	0.1	15	<0.1	1.1	0.2	26	0.03	0.050	2
1278138	Soil		3.3	46.4	23.3	72	1.3	19.6	3.0	64	3.08	16.4	11.3	1.9	48	0.3	1.4	1.1	23	0.68	0.072	3
1278139	Soil		3.9	60.4	27.4	69	1.8	27.8	2.9	45	2.96	17.3	5.3	1.7	41	0.2	1.6	0.4	30	0.49	0.063	3
1278140	Soil		3.5	53.0	22.8	73	1.2	26.2	3.0	50	2.34	12.7	6.0	1.2	53	0.3	1.3	0.4	22	1.07	0.083	3
1278141	Soil		2.9	37.3	12.7	152	1.6	45.8	5.5	95	1.92	12.3	5.0	0.8	92	1.1	1.2	0.3	25	2.44	0.199	10
1278142	Soil		2.9	46.0	23.0	143	1.6	45.7	6.6	110	2.70	16.6	4.9	1.5	91	0.5	1.4	0.3	22	0.61	0.086	5
1278143	Soil		2.2	49.8	36.5	193	1.4	68.2	18.8	317	4.27	22.4	3.8	2.9	85	0.5	1.5	0.5	22	0.13	0.083	3
1278144	Soil		1.9	25.3	31.0	65	1.9	17.1	3.7	96	2.32	45.4	6.7	1.8	23	0.2	7.3	0.3	25	0.07	0.049	4
1278145	Soil		2.8	41.4	16.8	148	1.1	46.8	8.2	124	2.60	49.5	5.6	1.4	39	0.4	2.2	0.3	35	0.05	0.085	8
1278146	Soil		2.8	71.7	16.5	233	3.4	99.5	15.8	469	3.52	28.5	8.5	1.5	51	1.0	1.6	0.2	24	0.67	0.144	7
1278147	Soil		1.5	25.8	6.9	74	0.7	25.2	4.2	163	1.30	11.3	2.4	0.3	47	0.6	0.7	0.2	14	1.03	0.103	4
1278148	Soil		2.6	44.9	15.6	107	1.1	40.8	6.6	208	2.33	15.4	5.5	1.0	43	0.4	1.2	0.2	28	0.58	0.092	6
1278149	Soil		2.1	19.4	5.3	38	0.8	9.8	1.9	42	1.07	6.6	2.7	<0.1	8	<0.1	1.0	0.1	23	0.04	0.079	3
1278150	Soil		4.2	75.9	23.4	106	1.3	32.3	5.0	78	4.07	38.2	5.6	0.3	27	0.2	1.9	0.3	37	0.09	0.142	4
1278151	Soil		18.2	31.1	50.9	429	0.6	71.3	6.0	204	2.52	38.4	4.5	0.3	148	1.3	11.5	0.2	99	0.12	0.205	7
1278152	Soil		28.6	31.0	29.9	569	0.5	86.3	4.8	81	2.21	22.9	2.6	0.4	48	11.1	8.6	0.2	138	0.33	0.091	3
1278153	Soil		12.8	39.7	47.2	189	0.3	40.6	5.4	69	2.16	32.1	1.5	<0.1	210	0.4	11.7	0.3	94	0.07	0.175	6
1278154	Soil		12.2	32.5	37.4	113	0.4	27.0	3.3	66	1.64	24.9	1.7	0.2	320	0.2	8.6	0.3	96	0.03	0.196	6
1278155	Soil		4.3	32.7	31.9	50	0.2	12.1	2.0	62	1.37	15.1	2.0	<0.1	475	0.2	4.7	0.4	45	0.05	0.234	6
1278156	Soil		6.1	43.5	41.6	147	0.3	38.0	5.5	77	2.47	25.9	2.1	<0.1	456	0.4	7.4	0.4	57	0.11	0.326	6
1278157	Soil		9.0	34.0	31.0	161	0.3	40.1	6.2	102	2.32	56.2	2.8	0.1	26	0.2	31.9	0.2	55	0.02	0.125	5
1278158	Soil		6.5	15.9	32.8	62	1.1	14.6	2.3	35	1.50	20.4	2.7	<0.1	36	0.2	11.9	0.3	45	0.03	0.136	5
1278159	Soil		9.1	23.8	48.9	113	1.0	23.0	4.0	102	2.16	28.5	4.7	0.3	64	0.3	16.0	0.2	55	0.02	0.150	5
1278160	Soil		6.8	31.8	24.0	122	<0.1	35.1	7.4	148	2.27	42.5	1.2	0.2	19	0.2	17.2	0.3	52	0.01	0.101	10
1278161	Soil		8.5	89.3	42.2	107	1.3	81.1	15.2	160	5.59	27.2	3.1	2.5	22	0.3	30.2	0.4	21	0.02	0.094	19

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278132	Soil	32	0.11	1009	0.003	3	0.74	0.006	0.04	<0.1	0.11	1.4	<0.1	<0.05	2	1.1	<0.2
1278133	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1278134	Soil	35	0.26	640	0.004	2	1.47	0.008	0.06	0.1	0.22	2.3	0.1	0.08	4	1.7	<0.2
1278135	Soil	31	0.26	624	0.005	2	1.29	0.006	0.08	0.1	0.11	2.2	0.1	0.05	4	1.1	<0.2
1278136	Soil	39	0.30	628	0.004	2	1.37	0.006	0.06	0.1	0.09	2.7	0.2	0.07	5	1.7	<0.2
1278137	Soil	16	0.14	170	0.003	<1	0.61	0.013	0.03	<0.1	0.03	0.3	0.2	<0.05	3	1.1	<0.2
1278138	Soil	21	0.06	593	0.001	10	0.44	0.015	0.23	<0.1	0.21	2.2	0.3	0.65	2	3.7	<0.2
1278139	Soil	25	0.04	197	<0.001	7	0.49	0.018	0.26	<0.1	0.30	2.4	0.3	0.77	2	5.3	<0.2
1278140	Soil	18	0.08	593	<0.001	7	0.54	0.012	0.18	<0.1	0.21	1.9	0.2	0.50	2	3.2	<0.2
1278141	Soil	19	0.13	501	0.002	7	0.71	0.010	0.09	0.1	0.17	1.1	0.1	0.25	1	2.6	<0.2
1278142	Soil	21	0.14	462	<0.001	3	0.68	0.005	0.08	<0.1	0.38	3.9	0.1	0.08	2	5.2	<0.2
1278143	Soil	31	0.14	1016	<0.001	3	0.96	0.005	0.09	<0.1	0.11	5.0	<0.1	0.08	3	7.4	<0.2
1278144	Soil	15	0.07	537	0.001	3	0.49	0.004	0.11	<0.1	0.27	1.8	0.2	0.14	2	4.0	<0.2
1278145	Soil	19	0.09	375	0.002	2	0.82	0.004	0.07	<0.1	0.16	1.7	0.2	0.10	3	1.7	<0.2
1278146	Soil	18	0.09	376	0.002	2	0.84	0.006	0.06	<0.1	0.39	3.8	0.2	0.14	2	3.1	<0.2
1278147	Soil	10	0.06	225	0.004	2	0.57	0.015	0.04	<0.1	0.18	0.8	<0.1	0.12	2	1.1	<0.2
1278148	Soil	20	0.13	342	0.004	3	0.71	0.006	0.09	0.1	0.20	2.1	0.1	0.09	2	2.0	<0.2
1278149	Soil	9	0.01	78	0.003	2	0.51	0.011	0.04	<0.1	0.08	0.2	<0.1	0.07	2	1.4	<0.2
1278150	Soil	29	0.08	187	0.002	2	0.78	0.006	0.07	<0.1	0.15	0.6	0.1	0.14	3	3.6	<0.2
1278151	Soil	25	0.10	244	0.004	1	0.68	0.006	0.05	<0.1	0.10	0.7	0.8	0.07	3	2.4	<0.2
1278152	Soil	37	0.03	267	0.002	1	0.37	0.004	0.03	<0.1	0.21	2.9	0.4	<0.05	1	2.4	<0.2
1278153	Soil	15	0.04	223	0.002	2	0.41	0.003	0.05	<0.1	0.03	0.2	0.3	0.05	2	2.3	<0.2
1278154	Soil	11	0.02	220	0.003	1	0.35	0.009	0.06	<0.1	0.03	0.3	0.2	0.08	2	2.1	<0.2
1278155	Soil	13	0.04	190	0.001	<1	0.74	0.012	0.04	<0.1	0.04	0.1	0.2	0.07	3	1.7	<0.2
1278156	Soil	14	0.04	386	<0.001	2	0.72	0.003	0.06	<0.1	0.03	0.2	0.3	0.10	2	3.2	<0.2
1278157	Soil	11	0.02	128	0.001	<1	0.41	0.003	0.04	<0.1	0.03	0.2	0.2	<0.05	2	1.8	<0.2
1278158	Soil	11	0.04	118	<0.001	<1	0.47	0.002	0.04	<0.1	0.11	0.1	0.2	<0.05	2	1.1	<0.2
1278159	Soil	13	0.05	147	0.002	1	0.40	0.003	0.04	<0.1	0.11	0.4	0.2	0.05	2	1.5	<0.2
1278160	Soil	11	0.03	133	0.004	2	0.43	0.003	0.05	0.1	0.02	0.3	0.2	<0.05	2	1.2	<0.2
1278161	Soil	13	0.04	298	<0.001	1	0.36	0.002	0.05	<0.1	0.26	4.3	0.3	<0.05	<1	2.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278162	Soil		7.3	56.2	56.9	421	0.7	81.4	11.1	250	3.87	52.4	5.0	0.6	62	1.6	34.0	0.2	85	0.27	0.227	9
1278163	Soil		7.6	9.9	10.0	52	0.1	11.7	2.1	42	0.90	12.1	1.1	0.5	14	0.3	2.3	0.2	45	0.07	0.034	9
1278164	Soil		16.8	15.3	20.8	86	0.3	24.3	1.2	31	0.64	19.2	4.2	0.6	34	1.4	9.5	0.2	63	0.55	0.036	7
1278165	Soil		60.2	63.6	22.1	1426	1.7	222.5	15.9	860	2.95	210.5	3.9	1.5	93	6.6	21.1	0.2	89	0.56	0.187	7
1278166	Soil		24.7	57.7	18.1	721	1.2	124.7	8.9	389	2.22	159.7	6.7	1.7	72	3.8	9.0	0.2	91	0.56	0.141	10
1278167	Soil		17.8	120.1	21.8	1835	1.5	254.2	124.6	637	6.27	180.2	17.8	2.7	68	23.9	16.3	0.5	78	0.51	0.102	11
1278168	Soil		32.7	68.8	16.3	962	1.5	294.6	18.6	5211	2.92	46.4	12.5	1.1	117	20.4	11.4	0.3	162	0.88	0.286	9
1278169	Soil		5.6	23.4	17.2	137	0.2	29.7	6.2	157	1.64	28.8	1.1	0.1	16	0.4	13.5	0.2	41	0.03	0.070	7
1278170	Soil		5.2	19.0	17.5	107	0.3	27.2	5.0	218	1.57	37.9	1.5	0.2	22	0.3	12.8	0.2	40	0.13	0.098	6
1278171	Soil		10.4	32.5	23.3	206	0.5	45.3	6.1	262	1.86	40.0	1.5	0.3	65	1.9	16.5	0.2	61	0.20	0.114	8
1278172	Soil		16.6	47.4	25.3	323	0.4	75.6	10.6	284	2.95	44.0	2.3	0.8	63	2.4	21.1	0.3	94	0.30	0.232	10
1278173	Soil		27.3	48.0	12.8	423	0.2	88.7	9.1	85	2.54	33.8	0.9	0.4	10	1.0	16.2	0.2	113	0.09	0.078	7
1278174	Soil		18.0	60.5	16.7	498	0.2	96.5	10.4	220	3.12	34.5	1.8	0.7	26	2.9	18.5	0.3	105	0.13	0.177	7
1278175	Soil		22.7	22.2	7.1	166	0.2	51.4	4.6	107	1.30	10.0	1.5	0.7	28	1.9	6.4	0.3	58	0.49	0.061	4
1278176	Soil		53.9	29.7	10.4	158	<0.1	98.7	9.4	156	1.77	16.0	0.9	2.4	18	1.2	14.2	0.2	55	0.34	0.041	5
1278177	Soil		75.6	67.8	12.6	834	0.7	187.0	7.7	102	2.31	27.9	1.5	0.2	39	4.0	15.8	0.2	198	0.09	0.078	6
1278178	Soil		65.7	50.7	18.9	370	1.1	108.4	4.1	39	1.89	28.4	0.7	<0.1	43	2.6	12.6	0.2	185	0.03	0.099	5
1278179	Soil		126.9	151.6	21.8	1022	0.4	317.7	18.1	199	4.11	50.8	2.3	2.5	59	12.2	30.4	0.3	117	0.21	0.051	6
1278180	Soil		111.6	116.0	12.7	1076	1.3	397.9	13.4	204	2.73	35.7	2.0	1.8	113	11.3	11.7	0.2	158	2.82	0.121	8
1279662	Soil		33.1	54.2	34.5	485	0.6	94.9	9.2	97	3.65	90.1	3.5	3.1	90	1.0	13.5	0.5	155	0.15	0.283	14
1279663	Soil		25.1	28.4	24.3	253	0.8	51.6	5.3	79	1.94	52.7	3.2	0.2	57	0.6	7.1	0.3	121	0.02	0.079	13
1279664	Soil		15.3	21.2	27.0	176	4.0	35.4	3.6	89	2.21	58.4	5.8	0.5	55	0.4	6.0	0.7	113	0.03	0.108	12
1279665	Soil		15.4	35.4	242.2	109	3.6	18.1	1.7	30	2.38	31.9	2.0	0.3	257	1.0	6.3	0.7	103	0.10	0.212	25
1279666	Soil		14.0	51.0	20.8	562	0.3	111.5	17.1	227	5.31	263.2	1.5	0.6	9	0.7	9.7	0.4	81	0.01	0.110	30
1279667	Soil		16.7	31.5	24.9	255	0.2	48.9	6.9	79	2.73	120.8	4.3	1.7	43	0.6	10.7	0.4	188	0.03	0.049	14
1279668	Soil		12.0	62.8	79.5	408	0.5	73.6	10.1	111	3.93	145.0	5.4	1.5	103	0.4	11.6	0.5	125	0.07	0.196	12
1279669	Soil		7.2	28.7	20.8	133	0.6	36.9	5.2	100	1.96	45.4	3.4	0.6	15	0.3	4.0	0.2	60	0.03	0.058	10
1279670	Soil		4.3	34.6	11.6	217	0.8	53.5	8.2	1058	1.64	10.5	3.7	1.3	76	3.4	1.9	0.2	60	0.74	0.103	8
1279641	Soil		9.9	66.7	17.4	323	1.2	93.5	12.1	102	4.35	63.5	1.5	0.8	11	0.2	6.3	0.6	45	0.01	0.065	16
1279642	Soil		6.3	36.1	16.8	197	0.7	37.8	8.1	211	2.37	13.8	3.9	2.5	48	1.4	2.2	0.3	68	0.31	0.128	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278162	Soil	23	0.05	337	0.002	2	0.52	0.003	0.06	<0.1	0.09	1.3	0.2	<0.05	2	3.5	<0.2
1278163	Soil	9	0.04	184	0.003	1	0.42	0.005	0.04	<0.1	0.06	0.4	0.2	<0.05	3	0.6	<0.2
1278164	Soil	10	0.03	305	0.003	2	0.21	0.006	0.05	0.2	0.27	0.5	0.6	0.06	1	1.5	<0.2
1278165	Soil	17	0.07	999	0.001	4	0.59	0.005	0.07	0.1	0.97	2.7	0.8	0.07	1	4.1	<0.2
1278166	Soil	20	0.13	1622	0.002	4	0.58	0.006	0.07	0.2	1.00	2.8	0.5	0.09	2	2.8	<0.2
1278167	Soil	19	0.15	794	0.002	5	1.06	0.008	0.07	0.3	2.67	4.7	1.1	0.21	2	7.5	<0.2
1278168	Soil	26	0.21	1630	0.003	5	1.02	0.007	0.09	0.1	1.15	2.6	0.4	0.10	3	7.6	<0.2
1278169	Soil	8	0.02	163	0.001	1	0.32	0.007	0.04	<0.1	0.07	0.2	0.1	<0.05	2	1.1	<0.2
1278170	Soil	11	0.05	667	0.002	1	0.49	0.011	0.04	<0.1	0.04	0.4	0.1	<0.05	2	1.0	<0.2
1278171	Soil	13	0.05	576	0.002	2	0.43	0.009	0.05	<0.1	0.06	0.5	0.2	0.06	2	2.2	<0.2
1278172	Soil	19	0.08	431	0.003	3	0.38	0.005	0.06	<0.1	0.06	1.1	0.3	<0.05	1	4.6	<0.2
1278173	Soil	14	0.04	123	0.002	1	0.28	0.004	0.04	<0.1	0.04	0.6	0.3	<0.05	1	3.6	<0.2
1278174	Soil	21	0.02	151	0.001	2	0.30	0.003	0.04	<0.1	0.03	1.6	0.3	<0.05	<1	5.0	<0.2
1278175	Soil	9	0.06	276	0.005	2	0.31	0.013	0.03	0.1	0.05	1.2	0.2	<0.05	1	1.7	<0.2
1278176	Soil	17	0.08	269	0.003	3	0.44	0.003	0.03	0.2	0.02	1.7	0.4	<0.05	1	1.5	<0.2
1278177	Soil	15	0.03	137	0.003	<1	0.54	0.005	0.03	0.2	0.13	0.6	1.1	<0.05	2	7.4	<0.2
1278178	Soil	12	0.01	107	0.002	<1	0.44	0.006	0.04	0.1	0.03	0.3	0.9	<0.05	2	4.0	<0.2
1278179	Soil	10	0.03	386	<0.001	1	0.35	0.002	0.05	0.2	0.23	3.4	2.3	0.07	<1	8.5	<0.2
1278180	Soil	12	0.18	197	<0.001	2	0.28	0.003	0.05	0.2	0.36	3.3	1.3	<0.05	<1	5.2	<0.2
1279662	Soil	14	0.07	440	0.005	2	0.64	0.002	0.11	0.3	0.13	2.1	0.8	0.15	3	5.2	<0.2
1279663	Soil	10	0.02	343	0.003	<1	0.38	0.002	0.06	0.2	0.29	0.4	0.6	0.08	2	2.0	<0.2
1279664	Soil	13	0.06	359	0.004	<1	0.72	0.002	0.07	0.3	1.12	0.6	0.6	0.10	4	2.5	<0.2
1279665	Soil	16	0.02	368	0.002	2	0.46	0.005	0.23	0.1	0.16	0.3	0.8	0.53	3	11.9	0.4
1279666	Soil	15	0.03	163	0.004	2	0.51	0.005	0.05	0.2	0.08	1.3	0.2	<0.05	2	1.4	<0.2
1279667	Soil	12	0.04	602	0.004	2	0.54	0.002	0.07	0.3	0.31	1.1	0.5	0.07	3	2.2	<0.2
1279668	Soil	13	0.02	527	0.005	2	0.65	0.003	0.07	0.3	0.24	1.5	0.4	0.08	3	3.3	<0.2
1279669	Soil	9	0.03	651	0.004	1	0.66	0.006	0.04	0.2	0.21	0.8	0.2	<0.05	2	1.4	<0.2
1279670	Soil	13	0.12	1933	0.001	2	0.94	0.009	0.07	0.1	0.28	1.7	0.3	0.07	2	1.6	<0.2
1279641	Soil	10	0.03	216	0.002	1	0.37	0.002	0.04	0.1	0.16	1.3	0.3	<0.05	2	3.8	<0.2
1279642	Soil	20	0.18	1031	0.002	2	1.03	0.004	0.10	0.1	0.31	2.3	0.3	<0.05	3	1.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279643	Soil	9.8	47.9	19.2	192	0.9	52.9	8.7	254	2.53	20.3	4.5	2.1	51	1.0	3.4	0.3	78	0.27	0.159	11
1279644	Soil	6.4	37.2	14.9	125	1.0	32.6	4.3	116	1.61	12.0	3.7	0.8	45	0.5	2.2	0.2	67	0.14	0.157	8
1279645	Soil	5.9	130.3	41.7	201	2.2	95.5	21.0	442	2.47	14.1	8.6	1.9	69	1.2	2.4	0.3	112	0.19	0.356	10
1279646	Soil	7.0	46.3	23.2	127	1.3	42.4	4.2	124	1.75	11.1	6.2	0.7	40	0.7	2.0	0.2	70	0.22	0.179	8
1279647	Soil	27.1	53.3	20.0	210	1.7	79.6	8.5	267	2.56	25.5	4.8	1.1	66	1.5	6.3	0.2	112	0.23	0.172	13
1279648	Soil	6.2	45.5	15.4	219	1.2	110.2	3.5	98	1.48	8.8	5.5	1.2	41	2.2	2.4	0.2	51	0.38	0.115	9
1279649	Soil	9.5	66.1	17.5	230	1.5	55.2	7.1	169	2.54	17.4	5.1	2.1	40	1.9	3.4	0.2	78	0.25	0.110	11
1279650	Soil	8.8	79.1	21.3	659	1.9	76.9	4.4	99	2.28	21.0	6.6	2.5	44	14.7	5.8	0.3	210	0.26	0.103	11
1279651	Soil	16.0	41.6	14.3	440	0.5	49.2	9.5	299	2.22	16.6	3.4	1.8	42	9.8	3.1	0.2	97	0.39	0.091	10
1279652	Soil	9.8	60.3	17.7	307	1.1	55.5	7.6	249	2.40	16.8	4.4	1.6	81	3.7	3.0	0.2	65	0.72	0.159	9
1279653	Soil	12.8	32.4	11.1	166	0.8	37.0	7.1	367	1.79	11.1	2.3	1.2	50	1.7	2.4	0.2	55	0.58	0.142	7
1279654	Soil	2.7	27.7	8.2	76	1.5	21.3	2.6	169	1.27	7.0	2.7	0.5	24	1.3	1.0	0.1	41	0.23	0.096	5
1279655	Soil	5.6	38.9	11.3	144	1.0	35.1	6.9	343	1.91	10.9	3.9	1.3	44	2.1	1.8	0.2	61	0.59	0.119	9
1279656	Soil	5.5	25.9	10.2	74	0.3	16.9	5.1	183	1.17	7.1	1.5	0.6	21	1.0	1.0	0.1	47	0.19	0.081	7
1279657	Soil	10.6	22.4	8.6	118	1.2	20.9	5.1	200	1.48	9.5	2.0	0.4	21	1.4	1.7	0.1	80	0.20	0.082	5
1279658	Soil	10.4	30.1	12.0	191	0.4	37.5	9.9	377	2.21	14.3	2.4	1.7	28	1.4	2.4	0.2	60	0.23	0.081	9
1279659	Soil	9.1	32.5	11.7	136	0.9	26.8	7.2	287	1.95	11.5	4.6	0.9	27	1.2	1.9	0.2	56	0.26	0.116	7
1279660	Soil	10.0	27.9	10.2	158	0.5	33.8	6.3	257	1.77	13.1	2.9	0.8	31	1.4	2.7	0.1	51	0.35	0.079	6
1279671	Soil	10.7	42.3	11.9	379	0.8	99.4	11.0	99	4.29	48.2	0.7	2.3	3	0.8	4.4	0.3	49	<0.01	0.043	30
1279672	Soil	15.5	36.1	16.0	437	0.3	97.1	10.4	138	5.06	39.9	2.2	1.8	4	0.4	5.4	0.3	54	0.01	0.052	25
1279673	Soil	25.3	31.3	13.3	448	0.3	106.7	9.1	131	4.18	49.9	2.0	1.8	5	0.4	7.3	0.2	66	0.01	0.056	21
1279674	Soil	42.2	21.5	12.6	680	<0.1	163.0	8.5	164	3.94	40.0	1.0	1.7	2	0.9	7.3	0.2	227	0.02	0.029	11
1279675	Soil	38.9	22.5	10.5	308	0.3	74.0	5.7	48	2.34	35.6	0.9	1.1	7	1.3	8.1	0.2	224	0.01	0.032	19
1279676	Soil	104.4	60.3	13.0	1897	1.1	477.4	25.0	482	4.60	74.0	1.6	2.3	31	23.9	13.0	0.2	193	0.31	0.141	32
1279677	Soil	32.6	19.3	7.6	260	<0.1	63.9	4.5	28	1.29	30.8	0.9	0.4	9	0.3	4.7	0.1	123	0.03	0.029	17
1279678	Soil	77.3	48.8	10.4	652	0.2	187.3	7.6	40	2.95	46.3	<0.5	1.0	10	0.8	16.6	0.2	193	0.06	0.058	17
1279679	Soil	19.9	171.8	11.5	1282	1.3	206.2	12.0	217	4.00	82.4	3.3	2.5	136	24.5	14.4	0.1	268	0.24	0.143	11
1279680	Soil	1.1	2.0	12.3	5	2.1	<0.1	<0.1	2	0.10	3.7	18.8	0.7	17	<0.1	3.6	0.1	17	<0.01	0.022	9
1279681	Soil	3.7	5.4	34.3	16	1.6	3.8	0.3	4	0.55	18.4	9.9	1.6	25	0.3	8.7	0.2	50	<0.01	0.025	8
1279682	Soil	13.6	4.5	15.7	7	3.9	2.8	0.2	2	0.36	37.3	29.6	0.3	22	<0.1	25.3	0.2	174	<0.01	0.027	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279643	Soil	19	0.15	689	0.002	2	0.89	0.004	0.12	0.1	0.42	2.1	0.3	0.05	2	2.0	<0.2
1279644	Soil	14	0.09	368	0.002	2	0.72	0.008	0.09	0.1	0.28	1.0	0.3	0.06	2	1.2	<0.2
1279645	Soil	31	0.13	969	0.002	3	1.59	0.006	0.13	0.1	1.19	2.8	0.5	0.09	3	2.5	<0.2
1279646	Soil	15	0.08	722	0.002	2	0.74	0.007	0.09	<0.1	0.50	1.2	0.3	0.06	2	1.7	<0.2
1279647	Soil	15	0.08	663	0.002	2	0.59	0.003	0.08	0.1	0.41	1.4	0.6	0.07	2	2.7	<0.2
1279648	Soil	15	0.11	1154	0.002	3	0.97	0.007	0.09	<0.1	0.39	1.9	0.3	0.08	3	1.9	<0.2
1279649	Soil	19	0.16	1185	0.001	3	1.02	0.004	0.13	0.1	0.56	4.0	0.4	0.05	3	1.7	<0.2
1279650	Soil	28	0.18	924	0.001	3	1.18	0.004	0.11	0.2	0.91	3.2	0.9	0.08	3	2.9	<0.2
1279651	Soil	19	0.18	692	0.002	1	0.87	0.004	0.07	0.1	0.22	2.3	0.3	<0.05	3	1.5	<0.2
1279652	Soil	18	0.18	1037	0.001	3	0.93	0.007	0.11	<0.1	0.32	2.3	0.3	0.10	2	2.8	<0.2
1279653	Soil	14	0.16	852	0.001	2	0.75	0.005	0.06	<0.1	0.25	1.9	0.2	0.07	2	1.4	<0.2
1279654	Soil	11	0.08	759	0.002	1	0.77	0.014	0.05	<0.1	0.31	1.2	0.2	0.07	2	1.1	<0.2
1279655	Soil	17	0.18	1246	0.002	2	0.95	0.006	0.06	0.1	0.34	2.4	0.2	0.06	2	1.2	<0.2
1279656	Soil	13	0.10	673	0.002	2	0.63	0.008	0.05	0.1	0.11	1.0	0.1	<0.05	2	0.7	<0.2
1279657	Soil	13	0.09	698	0.002	<1	0.60	0.010	0.05	<0.1	0.20	0.9	0.2	<0.05	2	0.8	<0.2
1279658	Soil	18	0.19	817	0.002	2	0.82	0.006	0.07	<0.1	0.18	1.9	0.2	<0.05	2	1.0	<0.2
1279659	Soil	14	0.14	868	0.002	<1	0.80	0.006	0.06	<0.1	0.30	1.5	0.2	0.06	2	1.1	<0.2
1279660	Soil	12	0.11	776	0.003	1	0.65	0.018	0.06	<0.1	0.20	1.8	0.2	<0.05	2	0.7	<0.2
1279671	Soil	12	0.03	149	0.002	4	0.43	0.001	0.07	<0.1	0.07	2.0	0.3	<0.05	2	2.9	<0.2
1279672	Soil	15	0.05	132	0.005	4	0.56	0.002	0.07	0.1	0.05	1.7	0.3	<0.05	2	2.2	<0.2
1279673	Soil	14	0.04	135	0.004	4	0.57	0.001	0.07	0.1	0.12	1.4	0.5	<0.05	2	4.2	<0.2
1279674	Soil	19	0.11	173	0.002	2	1.24	0.001	0.05	0.2	0.02	1.5	1.3	<0.05	4	4.3	<0.2
1279675	Soil	13	0.03	124	0.006	3	0.46	0.001	0.07	0.3	0.05	0.8	1.4	<0.05	3	4.3	<0.2
1279676	Soil	43	0.08	606	0.007	12	1.91	0.006	0.06	0.8	0.62	8.4	2.2	<0.05	3	10.3	0.2
1279677	Soil	11	0.04	129	0.005	4	0.50	0.002	0.06	0.2	0.05	0.7	0.9	<0.05	3	2.9	<0.2
1279678	Soil	21	0.07	181	0.003	4	0.73	0.002	0.10	0.5	0.12	1.2	1.8	<0.05	3	4.0	<0.2
1279679	Soil	37	0.05	381	0.004	6	1.30	0.007	0.08	0.2	1.96	5.0	1.1	<0.05	3	7.7	<0.2
1279680	Soil	5	<0.01	407	0.002	4	0.18	0.002	0.05	0.2	6.85	0.5	0.5	<0.05	1	1.2	<0.2
1279681	Soil	11	0.01	596	0.003	5	0.21	0.001	0.13	0.3	6.11	0.8	1.1	0.13	1	9.9	<0.2
1279682	Soil	11	0.01	124	0.002	3	0.29	<0.001	0.06	0.8	7.10	0.4	1.6	<0.05	2	6.6	0.4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279683	Soil		16.9	37.2	18.7	195	1.4	42.7	4.9	80	2.16	159.6	21.5	2.2	33	0.9	21.0	0.7	108	0.03	0.062	18
1279684	Soil		30.7	34.7	19.0	206	1.8	43.7	3.6	45	1.74	100.1	22.0	0.6	52	1.0	27.5	0.3	157	0.02	0.101	12
1279685	Soil		13.7	42.6	39.9	211	1.5	34.4	5.6	121	3.09	134.4	22.6	2.1	91	5.0	15.6	0.4	103	0.16	0.177	18
1279686	Soil		7.1	26.9	18.2	127	0.7	24.2	3.9	58	2.06	158.0	17.6	1.5	24	0.6	8.6	1.2	51	0.02	0.049	17
1279687	Soil		4.0	33.4	17.1	70	0.9	17.6	2.7	32	1.04	65.8	5.0	0.4	21	0.5	4.3	0.5	35	0.07	0.051	9
1279688	Soil		18.9	23.2	24.2	60	2.0	17.3	2.0	23	1.06	69.8	46.7	1.0	35	0.3	16.7	0.3	107	0.03	0.065	14
1279689	Soil		7.5	103.4	9.9	101	0.7	27.6	5.3	67	1.13	42.9	9.2	1.2	14	1.2	5.6	0.3	66	0.02	0.063	13
1279690	Soil		2.8	80.8	10.7	113	0.4	41.2	7.7	96	1.46	136.3	2.6	1.2	20	4.2	2.9	0.6	31	0.11	0.049	15
1279691	Soil		1.4	69.6	3.3	26	0.8	7.6	1.9	15	0.60	27.1	<0.5	0.3	6	1.0	1.0	0.2	19	0.02	0.037	11
1279692	Soil		3.9	48.7	16.2	153	0.5	38.8	9.0	86	5.46	539.1	2.1	5.8	21	0.4	5.2	2.0	48	<0.01	0.068	29
1279693	Soil		5.7	45.3	38.5	93	1.3	13.7	3.5	87	20.81	2145	31.5	7.6	15	0.5	13.5	2.5	51	0.02	0.294	8
1279694	Soil		14.2	30.1	27.7	126	0.6	29.2	3.9	39	1.92	128.3	12.8	2.3	31	0.3	10.4	1.1	95	0.01	0.043	17
1279695	Soil		29.4	66.1	38.3	201	1.7	48.5	5.4	83	1.84	100.4	20.6	1.7	49	0.7	17.8	1.0	262	0.04	0.084	17
1279696	Soil		5.8	41.5	15.1	88	1.4	19.1	5.7	137	1.67	124.0	12.9	1.8	24	0.9	5.6	1.2	43	0.02	0.046	13
1279697	Soil		13.0	88.1	24.0	222	0.8	49.2	5.1	60	8.48	201.1	9.5	4.0	16	1.0	14.5	1.5	99	0.01	0.099	17
1279698	Soil		12.7	63.2	22.4	168	0.9	31.4	4.2	44	7.46	120.8	5.6	3.2	17	0.6	13.3	0.8	94	0.03	0.086	16
1279699	Soil		15.7	32.9	22.6	110	2.9	24.7	5.7	175	1.62	85.6	36.4	1.1	45	1.1	10.8	0.7	128	0.07	0.091	11
1279700	Soil		11.2	61.2	26.1	152	1.5	34.8	5.1	106	2.00	106.4	22.3	1.4	40	1.1	8.4	0.9	92	0.06	0.087	13
1279701	Soil		13.6	25.7	5.2	499	0.7	67.4	3.6	66	0.94	25.2	2.5	0.2	14	2.7	6.7	0.1	327	0.11	0.059	8
1279702	Soil		24.2	61.6	13.0	1365	2.4	131.6	5.9	223	2.29	67.1	5.3	0.4	72	12.5	19.6	0.2	308	1.17	0.112	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

CERTIFICATE OF ANALYSIS WHI11001136.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279683	Soil	14	0.08	387	0.002	3	0.58	0.002	0.07	0.5	7.54	1.6	0.9	<0.05	2	5.4	0.2
1279684	Soil	14	0.04	392	0.004	3	0.58	0.005	0.09	0.6	5.45	0.9	1.7	0.05	2	10.5	<0.2
1279685	Soil	15	0.05	687	0.002	5	0.53	0.004	0.12	0.3	6.45	3.1	0.9	0.12	2	7.4	0.3
1279686	Soil	10	0.07	159	0.003	3	0.58	0.008	0.07	0.5	1.75	1.2	0.3	<0.05	2	2.2	<0.2
1279687	Soil	8	0.04	175	0.002	3	0.62	0.015	0.06	0.2	0.75	0.8	0.2	<0.05	2	1.1	<0.2
1279688	Soil	21	0.02	314	0.007	4	0.42	0.005	0.09	0.7	22.09	1.4	1.4	<0.05	3	7.5	0.3
1279689	Soil	13	0.03	229	0.003	2	0.98	0.005	0.05	0.3	1.98	2.0	0.3	<0.05	2	2.7	<0.2
1279690	Soil	9	0.03	449	0.002	<1	0.66	0.011	0.05	0.1	0.49	1.5	0.2	<0.05	2	0.9	<0.2
1279691	Soil	4	0.01	71	0.004	1	0.48	0.016	0.03	<0.1	0.20	0.8	<0.1	<0.05	2	0.6	<0.2
1279692	Soil	17	0.21	127	0.002	2	0.99	0.003	0.07	0.2	0.34	2.6	0.3	<0.05	3	2.1	0.2
1279693	Soil	16	0.04	166	0.010	1	0.87	0.003	0.05	0.4	3.92	1.8	0.3	0.11	3	8.2	0.2
1279694	Soil	10	0.03	174	0.003	2	0.43	0.003	0.06	0.5	0.77	1.4	0.6	<0.05	2	2.3	0.2
1279695	Soil	18	0.03	313	0.005	6	0.71	0.004	0.11	0.7	1.27	2.0	1.7	<0.05	3	6.8	0.3
1279696	Soil	11	0.07	490	0.002	2	0.62	0.013	0.07	0.5	1.05	1.5	0.3	<0.05	2	1.6	<0.2
1279697	Soil	15	0.02	189	0.003	5	0.52	0.003	0.08	1.4	1.68	2.0	0.5	<0.05	2	6.3	0.4
1279698	Soil	15	0.02	249	0.005	4	0.44	0.003	0.07	0.7	1.58	2.1	0.5	<0.05	2	3.7	0.3
1279699	Soil	17	0.05	504	0.003	6	0.67	0.009	0.12	0.5	2.68	2.0	1.5	<0.05	2	3.5	0.6
1279700	Soil	16	0.07	516	0.002	3	0.73	0.007	0.09	0.4	2.29	2.2	0.8	<0.05	2	2.9	0.2
1279701	Soil	32	0.12	216	0.008	3	0.76	0.019	0.06	0.2	0.45	0.9	0.9	<0.05	2	3.6	0.2
1279702	Soil	51	0.67	247	0.006	3	0.94	0.007	0.10	0.2	0.73	1.2	1.2	0.06	3	7.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

QUALITY CONTROL REPORT WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1277837	Soil	2.1	16.6	5.0	41	<0.1	9.4	5.2	90	1.06	6.2	<0.5	<0.1	5	<0.1	0.6	0.1	23	0.02	0.036	4
REP 1277837	QC	2.2	17.4	5.4	42	<0.1	9.4	5.1	88	1.04	6.3	<0.5	<0.1	6	<0.1	0.6	0.2	22	0.02	0.035	4
1277844	Soil	2.0	13.7	7.4	50	0.1	11.8	4.8	204	0.98	6.2	1.2	<0.1	12	0.3	1.0	0.1	17	0.11	0.069	3
REP 1277844	QC	1.7	13.4	6.9	47	<0.1	12.0	4.9	204	1.00	5.3	<0.5	<0.1	12	0.2	0.7	0.1	17	0.11	0.074	3
1277868	Soil	10.4	66.3	23.6	189	0.2	35.1	7.0	163	3.21	30.9	2.1	0.3	29	0.8	5.1	0.4	76	0.05	0.070	8
REP 1277868	QC	10.8	67.8	24.4	192	0.2	32.4	7.1	160	3.23	31.0	4.0	0.3	35	0.9	4.9	0.3	76	0.05	0.076	9
1277906	Soil	5.1	30.1	20.2	106	1.4	24.2	4.5	103	2.59	98.7	19.6	0.5	28	0.3	4.9	0.6	53	0.03	0.078	9
REP 1277906	QC	5.2	30.8	20.0	104	1.3	23.4	4.5	102	2.55	98.9	19.3	0.5	28	0.3	4.9	0.6	53	0.03	0.078	9
1277915	Soil	7.6	56.6	20.2	90	1.7	29.5	5.4	156	2.19	65.2	21.2	2.2	53	1.0	6.3	0.4	72	0.50	0.090	9
REP 1277915	QC	7.2	54.1	19.4	88	1.7	28.5	5.2	156	2.17	65.6	17.6	2.1	52	1.0	6.0	0.4	70	0.50	0.093	9
1277877	Soil	15.2	29.7	17.6	188	0.2	44.8	6.3	122	2.24	60.1	2.6	0.2	25	0.8	23.3	0.2	77	0.10	0.090	9
REP 1277877	QC	15.6	29.4	18.1	184	0.3	43.5	6.1	122	2.18	63.3	5.3	0.3	25	0.8	23.5	0.2	77	0.10	0.092	9
1278045	Soil	10.0	64.4	24.4	297	0.9	75.1	11.0	353	3.38	20.7	5.6	4.2	59	2.3	3.3	0.2	115	0.58	0.150	14
REP 1278045	QC	9.8	64.3	24.2	292	0.9	74.1	11.0	358	3.43	20.9	5.3	4.4	59	2.1	3.4	0.2	120	0.56	0.159	14
1278058	Soil	131.9	95.4	10.3	992	1.1	300.3	5.8	109	1.81	46.8	<0.5	2.0	327	9.0	24.3	0.1	310	9.73	0.077	2
REP 1278058	QC	136.7	96.9	10.4	1017	1.1	303.9	5.8	104	1.80	47.0	<0.5	1.9	329	9.0	24.5	0.1	343	9.88	0.078	2
1278080	Soil	12.9	67.6	32.5	221	1.0	92.9	15.9	368	3.83	49.1	15.2	0.8	76	1.6	80.7	0.3	78	0.32	0.176	16
REP 1278080	QC	12.9	68.4	32.3	224	1.1	96.1	16.1	375	3.88	49.8	16.7	0.8	76	1.5	81.2	0.3	81	0.31	0.184	16
1278085	Soil	76.6	85.8	12.3	342	0.2	164.7	10.8	227	2.09	19.4	2.1	2.8	163	2.8	11.5	0.2	42	6.72	0.091	7
REP 1278085	QC	76.7	87.6	12.4	356	0.2	167.2	10.9	232	2.07	19.9	2.5	3.1	163	2.7	11.8	0.2	42	6.85	0.092	8
1278111	Soil	1.5	20.4	9.1	95	0.9	28.4	4.7	256	2.07	7.8	2.2	0.6	59	0.7	0.9	0.2	40	1.73	0.183	25
REP 1278111	QC	1.5	20.1	9.4	97	0.9	28.9	4.5	258	2.09	8.1	1.9	0.6	59	0.7	0.9	0.2	39	1.72	0.187	25
1278133	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1278133	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1278138	Soil	3.3	46.4	23.3	72	1.3	19.6	3.0	64	3.08	16.4	11.3	1.9	48	0.3	1.4	1.1	23	0.68	0.072	3
REP 1278138	QC	3.2	46.2	22.6	70	1.3	19.9	2.9	62	3.02	16.0	12.5	2.0	47	0.3	1.3	0.8	21	0.66	0.071	2
1278162	Soil	7.3	56.2	56.9	421	0.7	81.4	11.1	250	3.87	52.4	5.0	0.6	62	1.6	34.0	0.2	85	0.27	0.227	9
REP 1278162	QC	7.5	56.8	57.6	432	0.7	82.3	11.0	255	3.96	53.7	4.7	0.5	63	1.7	35.2	0.2	85	0.27	0.232	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

QUALITY CONTROL REPORT WHI11001136.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1277837	Soil	5	0.02	30	0.004	<1	0.40	0.012	0.02	<0.1	<0.01	0.2	<0.1	<0.05	2	<0.5	<0.2
REP 1277837	QC	5	0.02	31	0.004	<1	0.40	0.012	0.02	<0.1	<0.01	0.2	<0.1	<0.05	2	<0.5	<0.2
1277844	Soil	6	0.04	103	0.001	<1	0.36	0.015	0.04	<0.1	0.03	0.1	<0.1	<0.05	2	0.8	<0.2
REP 1277844	QC	6	0.04	75	0.001	<1	0.37	0.017	0.04	<0.1	0.01	<0.1	<0.1	<0.05	2	<0.5	<0.2
1277868	Soil	23	0.11	68	0.015	2	0.69	0.003	0.04	0.2	<0.01	1.3	0.2	<0.05	4	2.2	<0.2
REP 1277868	QC	23	0.12	72	0.016	2	0.71	0.003	0.04	0.2	<0.01	1.2	0.2	0.07	4	2.0	<0.2
1277906	Soil	16	0.08	177	0.004	3	0.73	0.007	0.06	0.3	1.25	1.0	0.4	<0.05	3	2.9	<0.2
REP 1277906	QC	16	0.08	184	0.005	3	0.73	0.007	0.07	0.3	1.19	0.9	0.3	<0.05	3	2.4	<0.2
1277915	Soil	16	0.10	719	0.001	3	0.74	0.005	0.05	0.2	2.63	2.7	0.4	0.06	2	4.0	<0.2
REP 1277915	QC	15	0.11	722	0.001	2	0.74	0.005	0.06	0.3	2.66	2.6	0.5	0.09	2	4.0	<0.2
1277877	Soil	18	0.09	176	0.004	<1	0.67	0.003	0.05	0.2	<0.01	0.7	0.3	<0.05	3	1.3	<0.2
REP 1277877	QC	19	0.09	178	0.004	<1	0.66	0.003	0.04	0.2	0.02	0.8	0.3	<0.05	3	1.4	<0.2
1278045	Soil	25	0.25	1435	0.002	6	1.24	0.007	0.21	0.1	0.39	3.2	0.5	0.09	3	2.2	<0.2
REP 1278045	QC	26	0.26	1454	0.002	7	1.32	0.007	0.22	<0.1	0.42	3.2	0.5	0.09	3	2.1	<0.2
1278058	Soil	10	1.72	152	0.001	3	0.19	0.004	0.05	0.3	0.59	2.1	1.4	0.19	<1	7.6	<0.2
REP 1278058	QC	15	1.73	174	0.001	3	0.21	0.004	0.06	0.3	0.58	2.1	1.4	0.20	<1	7.8	<0.2
1278080	Soil	21	0.16	478	0.005	2	0.66	0.004	0.07	0.1	0.28	2.3	0.3	<0.05	2	2.2	<0.2
REP 1278080	QC	24	0.16	493	0.005	2	0.66	0.004	0.08	0.1	0.25	2.5	0.3	0.05	2	2.1	<0.2
1278085	Soil	16	2.40	227	0.004	4	0.31	0.006	0.04	0.2	0.28	3.9	1.0	0.05	<1	1.8	<0.2
REP 1278085	QC	16	2.48	234	0.005	5	0.33	0.006	0.05	0.3	0.33	3.9	1.1	0.08	<1	1.9	<0.2
1278111	Soil	29	0.14	364	0.004	2	0.81	0.006	0.03	0.2	0.16	1.7	<0.1	0.15	2	1.4	<0.2
REP 1278111	QC	29	0.15	358	0.004	2	0.84	0.007	0.03	0.1	0.19	1.7	<0.1	0.16	2	1.5	<0.2
1278133	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1278133	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1278138	Soil	21	0.06	593	0.001	10	0.44	0.015	0.23	<0.1	0.21	2.2	0.3	0.65	2	3.7	<0.2
REP 1278138	QC	21	0.06	611	<0.001	9	0.42	0.014	0.23	<0.1	0.24	2.1	0.3	0.62	2	3.7	<0.2
1278162	Soil	23	0.05	337	0.002	2	0.52	0.003	0.06	<0.1	0.09	1.3	0.2	<0.05	2	3.5	<0.2
REP 1278162	QC	23	0.05	349	0.003	2	0.53	0.003	0.06	<0.1	0.10	1.1	0.2	<0.05	2	3.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

QUALITY CONTROL REPORT WHI11001136.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1278175	Soil	22.7	22.2	7.1	166	0.2	51.4	4.6	107	1.30	10.0	1.5	0.7	28	1.9	6.4	0.3	58	0.49	0.061	4
REP 1278175	QC	23.4	23.0	7.7	173	0.2	52.7	5.0	109	1.34	10.3	1.7	0.7	29	2.0	6.8	0.2	60	0.53	0.064	4
1279658	Soil	10.4	30.1	12.0	191	0.4	37.5	9.9	377	2.21	14.3	2.4	1.7	28	1.4	2.4	0.2	60	0.23	0.081	9
REP 1279658	QC	10.8	32.1	12.6	197	0.4	38.6	10.3	386	2.32	14.9	2.6	1.8	29	1.5	2.4	0.2	59	0.24	0.083	9
1279682	Soil	13.6	4.5	15.7	7	3.9	2.8	0.2	2	0.36	37.3	29.6	0.3	22	<0.1	25.3	0.2	174	<0.01	0.027	10
REP 1279682	QC	13.6	4.4	16.6	7	3.9	2.8	0.2	2	0.36	38.3	33.8	0.3	21	0.1	26.3	0.1	164	<0.01	0.028	10
1279691	Soil	1.4	69.6	3.3	26	0.8	7.6	1.9	15	0.60	27.1	<0.5	0.3	6	1.0	1.0	0.2	19	0.02	0.037	11
REP 1279691	QC	1.7	68.8	3.4	28	0.8	8.1	1.8	15	0.62	27.6	1.9	0.4	6	0.9	0.9	0.1	20	0.02	0.039	12
Reference Materials																					
STD DS8	Standard	14.3	102.8	121.3	310	1.7	39.6	7.1	628	2.50	22.8	106.7	7.5	71	2.1	4.9	5.9	40	0.76	0.077	16
STD DS8	Standard	14.6	121.7	133.2	325	1.8	42.3	8.4	624	2.54	25.1	115.1	7.1	68	2.2	5.6	6.7	48	0.71	0.078	16
STD DS8	Standard	12.9	114.9	126.3	319	1.9	40.2	7.8	618	2.54	25.3	115.2	7.2	65	2.5	5.2	6.6	45	0.71	0.079	15
STD DS8	Standard	14.4	127.0	137.2	340	1.9	41.5	8.4	670	2.75	27.7	116.8	8.2	76	2.4	5.9	7.7	46	0.75	0.083	16
STD DS8	Standard	11.9	91.0	107.7	289	1.6	37.2	6.4	582	2.32	20.4	102.1	5.2	59	1.9	4.3	5.2	36	0.64	0.065	12
STD DS8	Standard	13.4	98.8	127.0	305	1.8	31.7	7.0	576	2.63	25.1	111.1	6.5	63	2.2	5.0	6.1	40	0.67	0.074	16
STD DS8	Standard	14.1	121.0	131.8	319	1.8	39.7	8.0	633	2.47	25.7	116.0	7.6	57	2.4	6.0	7.2	44	0.71	0.079	17
STD DS8	Standard	13.2	114.9	130.4	316	1.8	37.8	7.3	622	2.50	25.8	116.1	6.8	70	2.5	5.9	6.8	43	0.70	0.083	16
STD DS8	Standard	12.9	117.0	131.3	316	1.7	39.9	7.8	612	2.50	24.2	111.5	6.5	65	2.3	5.6	6.4	43	0.68	0.078	15
STD DS8	Standard	12.3	114.0	128.6	313	1.8	37.5	7.4	603	2.42	25.0	114.3	6.2	61	2.4	5.6	6.3	41	0.68	0.080	14
STD DS8	Standard	12.8	106.8	125.1	303	1.8	36.4	7.4	609	2.40	26.3	115.1	7.4	67	2.2	5.7	7.2	39	0.69	0.078	16
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

QUALITY CONTROL REPORT WHI11001136.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1278175	Soil	9	0.06	276	0.005	2	0.31	0.013	0.03	0.1	0.05	1.2	0.2	<0.05	1	1.7	<0.2
REP 1278175	QC	9	0.06	291	0.005	2	0.33	0.014	0.03	<0.1	0.05	1.3	0.3	0.06	1	1.4	<0.2
1279658	Soil	18	0.19	817	0.002	2	0.82	0.006	0.07	<0.1	0.18	1.9	0.2	<0.05	2	1.0	<0.2
REP 1279658	QC	17	0.19	819	0.002	<1	0.83	0.006	0.06	0.1	0.16	1.8	0.2	<0.05	3	1.0	<0.2
1279682	Soil	11	0.01	124	0.002	3	0.29	<0.001	0.06	0.8	7.10	0.4	1.6	<0.05	2	6.6	0.4
REP 1279682	QC	11	0.01	127	0.001	4	0.27	<0.001	0.06	0.9	7.39	0.4	1.6	<0.05	2	5.6	0.4
1279691	Soil	4	0.01	71	0.004	1	0.48	0.016	0.03	<0.1	0.20	0.8	<0.1	<0.05	2	0.6	<0.2
REP 1279691	QC	4	0.01	73	0.003	1	0.50	0.018	0.03	<0.1	0.23	0.8	<0.1	<0.05	1	0.6	0.2
Reference Materials																	
STD DS8	Standard	122	0.62	290	0.127	2	0.94	0.090	0.41	3.0	0.20	1.6	5.4	0.22	5	5.3	5.1
STD DS8	Standard	128	0.67	268	0.132	2	0.97	0.080	0.41	3.0	0.21	2.0	5.4	0.18	5	6.0	4.9
STD DS8	Standard	118	0.61	270	0.125	4	0.89	0.084	0.41	2.9	0.14	2.2	5.6	0.16	5	5.3	4.9
STD DS8	Standard	128	0.65	297	0.131	2	0.99	0.086	0.43	3.1	0.18	2.5	5.8	0.20	5	5.7	5.2
STD DS8	Standard	118	0.59	227	0.091	2	0.83	0.083	0.38	2.7	0.20	1.4	5.3	0.14	4	5.0	4.8
STD DS8	Standard	111	0.58	285	0.112	3	0.92	0.102	0.40	3.1	0.18	3.2	5.5	0.08	5	4.6	4.6
STD DS8	Standard	117	0.63	283	0.120	3	0.95	0.100	0.42	3.1	0.20	2.3	5.5	0.19	5	4.8	4.8
STD DS8	Standard	120	0.62	287	0.115	2	0.93	0.104	0.42	3.1	0.19	2.3	5.5	0.17	5	5.1	5.1
STD DS8	Standard	119	0.60	275	0.112	3	0.93	0.106	0.41	3.0	0.19	2.3	5.6	0.17	5	5.1	5.3
STD DS8	Standard	119	0.60	265	0.106	2	0.85	0.086	0.41	2.8	0.19	2.2	5.5	0.16	5	4.9	4.8
STD DS8	Standard	111	0.60	274	0.110	2	0.89	0.087	0.41	3.1	0.20	2.3	5.4	0.15	5	5.3	5.0
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

QUALITY CONTROL REPORT WHI11001136.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 07, 2011

QUALITY CONTROL REPORT WHI11001136.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 12, 2011
Report Date: September 15, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11001137.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #13
P.O. Number
Number of Samples: 38

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	38	Sieve to 230 mesh			WHI
RJSV	38	Saving all or part of Soil Reject			WHI
1DX2	38	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 15, 2011

CERTIFICATE OF ANALYSIS WHI11001137.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279703	Soil		19.3	40.4	16.0	282	0.7	61.4	7.9	144	2.67	41.3	4.7	0.9	20	1.4	5.3	0.3	77	0.10	0.070	11
1279704	Soil		76.3	251.7	18.3	4183	2.7	337.8	14.4	625	2.21	124.2	7.9	0.5	160	78.7	31.0	0.2	1018	2.33	0.192	13
1279705	Soil		81.4	151.8	14.4	2389	2.3	268.4	10.0	263	1.95	101.7	6.0	0.5	98	38.8	25.3	0.2	888	0.80	0.173	15
1279706	Soil		85.5	142.8	22.6	1745	3.5	244.1	19.5	556	2.16	113.1	6.9	0.2	164	34.3	28.1	0.3	1201	0.26	0.203	18
1279707	Soil		132.9	268.7	23.1	4704	5.5	501.8	15.1	408	2.96	282.2	5.8	1.4	173	52.9	61.2	0.3	1947	0.87	0.321	26
1279708	Soil		53.6	57.4	13.8	307	0.9	65.1	3.1	74	1.78	76.8	5.5	0.1	66	0.9	15.7	0.2	650	0.05	0.118	15
1279709	Soil		116.0	198.9	17.9	307	4.4	86.3	2.4	43	1.88	269.9	90.4	1.1	169	2.3	65.8	0.2	1541	0.05	0.227	18
1279710	Soil		27.4	31.0	12.4	84	1.9	18.8	1.4	22	0.81	37.8	21.1	<0.1	93	0.5	14.4	0.2	446	0.04	0.120	13
1279711	Soil		59.7	39.5	17.2	92	2.4	20.6	1.5	34	1.36	81.0	11.9	0.2	96	0.5	22.5	0.3	1045	0.03	0.161	15
1279712	Soil		58.7	31.4	19.1	77	1.9	17.6	1.6	32	1.39	77.2	10.7	0.2	77	0.4	17.5	0.3	588	0.03	0.133	16
1279713	Soil		40.2	53.1	40.4	135	1.8	31.4	3.2	53	2.86	195.8	32.3	3.9	50	0.3	26.2	0.4	281	0.02	0.101	9
1279714	Soil		13.9	11.9	40.3	11	1.6	2.6	0.3	10	0.88	54.1	26.9	3.0	24	<0.1	12.1	0.3	41	<0.01	0.033	4
1279715	Soil		43.4	27.2	40.0	33	7.6	5.0	0.6	20	1.91	114.3	19.7	1.2	83	0.2	38.6	0.6	167	0.03	0.134	25
1279716	Soil		11.0	65.7	45.9	240	0.4	45.9	17.3	929	6.00	113.0	3.8	1.8	50	0.9	4.5	0.4	91	0.01	0.138	6
1279717	Soil		3.2	23.4	26.9	94	1.4	15.0	4.7	416	2.81	143.2	14.2	1.7	11	0.3	9.3	1.4	33	0.01	0.063	17
1279718	Soil		3.2	33.7	41.9	163	1.4	24.1	7.7	159	4.14	308.6	56.5	4.1	14	0.3	28.5	2.0	27	0.01	0.068	20
1279719	Soil		2.4	26.4	43.2	112	1.2	15.6	4.2	104	2.96	252.6	45.4	5.0	13	0.3	33.5	1.8	23	0.02	0.066	33
1279720	Soil		1.4	29.6	28.4	100	0.4	18.5	4.5	130	2.70	92.1	5.2	5.9	19	0.7	10.0	0.5	18	0.03	0.058	37
1279721	Soil		2.6	33.0	57.5	130	1.4	19.5	6.2	112	3.91	305.2	41.7	5.5	13	0.3	38.2	2.6	22	<0.01	0.062	30
1279722	Soil		4.8	44.9	76.0	167	2.0	22.6	5.7	60	3.77	604.1	58.2	4.3	18	0.2	184.0	2.8	24	0.01	0.070	32
1279723	Soil		7.8	137.0	173.3	288	2.9	60.2	12.4	160	13.70	4482	190.9	17.9	65	0.6	99.1	17.9	81	0.02	0.307	33
1279724	Soil		6.0	84.2	53.0	152	1.2	21.1	5.0	165	8.13	481.6	47.1	8.9	21	0.4	26.0	2.0	59	0.02	0.184	30
1279725	Soil		3.8	53.8	27.6	121	0.9	17.8	4.0	151	5.38	254.5	12.8	4.0	19	0.4	15.3	1.1	46	0.02	0.154	29
1279726	Soil		7.2	93.4	39.2	155	9.2	26.9	4.3	125	3.82	123.3	66.8	3.4	259	1.2	13.4	0.4	142	0.52	0.956	18
1279727	Soil		2.7	23.5	22.9	160	1.3	25.0	5.9	79	2.79	117.0	6.0	1.2	43	0.3	7.8	0.3	31	0.01	0.111	6
1279728	Soil		4.6	34.1	44.7	243	0.3	50.2	11.2	255	3.92	51.1	2.0	2.1	45	0.7	3.9	0.4	17	0.08	0.057	5
1279729	Soil		2.2	28.5	24.4	222	0.2	45.5	10.4	272	3.20	41.2	2.4	1.7	27	0.9	3.2	0.3	16	0.08	0.044	4
1279730	Soil		2.8	15.4	23.7	131	0.2	25.8	5.4	189	1.93	28.5	2.4	1.5	37	0.6	4.5	0.3	15	0.07	0.029	5
1279751	Soil		13.6	55.6	23.8	151	1.5	23.9	4.2	117	3.63	191.3	14.4	1.9	30	0.9	8.9	0.4	61	0.04	0.077	13
1279752	Soil		9.3	39.3	19.7	159	1.0	28.5	5.4	107	2.42	80.6	13.3	2.4	25	0.8	6.2	0.3	61	0.04	0.069	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 15, 2011

CERTIFICATE OF ANALYSIS WHI11001137.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279703	Soil	13	0.07	548	0.003	3	0.45	0.004	0.08	0.1	0.63	1.7	0.5	0.12	1	3.2	<0.2
1279704	Soil	57	0.28	793	0.006	12	0.84	0.005	0.13	0.5	1.47	2.7	5.1	0.21	3	14.5	<0.2
1279705	Soil	58	0.18	740	0.007	9	0.93	0.004	0.13	0.5	1.25	2.9	4.8	0.08	3	9.9	0.2
1279706	Soil	60	0.10	778	0.008	11	0.99	0.002	0.17	0.5	1.48	2.0	9.6	0.13	3	15.5	0.3
1279707	Soil	90	0.22	996	0.028	13	1.67	0.002	0.18	0.7	3.47	5.8	8.4	0.06	4	16.6	0.5
1279708	Soil	39	0.08	258	0.008	4	0.83	0.008	0.09	0.4	0.85	0.6	3.4	0.06	3	7.3	<0.2
1279709	Soil	78	0.09	945	0.014	8	1.13	0.003	0.16	0.7	34.40	3.9	5.9	0.07	4	15.0	0.4
1279710	Soil	35	0.03	881	0.003	5	0.53	0.008	0.08	0.3	13.28	0.3	2.2	0.07	3	6.1	0.2
1279711	Soil	63	0.05	1588	0.004	6	0.71	0.004	0.14	0.4	9.89	0.3	4.5	0.12	6	11.2	0.3
1279712	Soil	41	0.06	1101	0.005	5	0.68	0.005	0.12	0.5	6.95	0.6	2.7	0.11	5	12.4	0.3
1279713	Soil	23	0.07	472	0.007	4	0.48	0.004	0.21	0.3	13.42	3.8	1.9	0.42	3	13.9	0.3
1279714	Soil	7	0.01	522	0.002	4	0.22	0.002	0.12	0.1	5.29	1.2	0.7	0.17	1	6.9	0.2
1279715	Soil	18	0.01	1952	0.003	6	0.53	0.002	0.07	0.6	4.84	0.9	1.9	0.11	4	9.3	0.4
1279716	Soil	15	0.04	161	0.003	2	0.75	0.005	0.11	<0.1	0.34	6.1	1.1	0.20	2	3.6	<0.2
1279717	Soil	10	0.05	95	0.002	2	0.67	0.005	0.06	0.3	0.88	1.2	0.2	<0.05	3	1.7	<0.2
1279718	Soil	11	0.10	83	<0.001	1	0.74	0.001	0.07	0.4	2.11	2.7	0.4	0.08	2	4.0	<0.2
1279719	Soil	9	0.12	87	<0.001	2	0.63	0.001	0.08	0.4	1.88	1.8	0.3	0.07	2	3.7	<0.2
1279720	Soil	9	0.22	87	<0.001	1	0.83	0.002	0.07	<0.1	0.83	2.3	0.1	0.05	2	1.1	<0.2
1279721	Soil	9	0.08	85	<0.001	2	0.70	0.002	0.09	0.3	1.05	2.6	0.4	0.10	2	3.7	<0.2
1279722	Soil	9	0.06	105	0.001	2	0.44	0.002	0.09	0.7	4.36	1.5	0.7	0.12	2	9.5	<0.2
1279723	Soil	32	0.34	320	0.006	3	1.37	0.007	0.13	8.7	8.04	9.1	1.3	0.35	5	22.0	3.0
1279724	Soil	26	0.41	145	0.009	3	1.36	0.005	0.12	0.4	5.48	5.3	1.2	0.23	5	8.2	0.2
1279725	Soil	23	0.44	373	0.008	2	1.49	0.003	0.11	0.3	2.61	2.9	0.5	0.15	4	4.1	0.3
1279726	Soil	42	0.04	692	0.007	11	0.96	0.005	0.19	0.4	8.49	5.3	0.8	0.25	3	15.7	0.4
1279727	Soil	8	0.01	430	<0.001	3	0.35	0.002	0.09	<0.1	0.58	1.8	0.3	0.12	1	2.3	<0.2
1279728	Soil	6	0.03	377	<0.001	3	0.24	0.002	0.09	<0.1	0.33	3.6	0.7	0.10	<1	1.1	<0.2
1279729	Soil	6	0.03	363	<0.001	3	0.24	0.002	0.07	<0.1	0.22	3.6	0.3	0.06	<1	1.3	<0.2
1279730	Soil	5	0.02	407	<0.001	4	0.18	0.002	0.09	<0.1	19.04	1.9	0.4	0.17	<1	1.8	<0.2
1279751	Soil	13	0.08	254	0.002	2	0.58	0.006	0.06	0.2	0.89	1.9	0.6	0.07	2	4.1	<0.2
1279752	Soil	16	0.09	372	0.001	3	0.68	0.003	0.07	0.2	1.42	1.8	0.5	<0.05	2	3.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 15, 2011

CERTIFICATE OF ANALYSIS WHI11001137.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279753	Soil	12.4	35.0	17.6	228	0.7	34.9	5.6	154	3.23	130.2	9.8	2.4	28	0.4	9.2	0.3	62	0.12	0.081	14
1279754	Soil	14.7	32.4	19.5	267	0.6	39.3	17.4	715	3.46	114.2	13.1	2.7	27	0.4	11.3	0.3	72	0.09	0.086	16
1279755	Soil	10.6	28.4	18.0	148	1.6	22.9	4.8	134	1.78	63.8	15.4	1.0	24	0.4	5.3	0.3	59	0.08	0.075	11
1279756	Soil	18.5	41.0	95.2	116	3.1	14.8	3.2	56	3.35	679.3	232.6	1.5	74	0.7	43.4	3.5	82	0.04	0.140	20
1279757	Soil	15.1	31.0	62.8	125	2.3	22.7	2.5	43	2.44	499.4	317.9	1.4	66	2.0	34.2	2.2	77	0.18	0.131	18
1279758	Soil	8.0	48.6	21.1	130	2.0	29.5	4.4	101	2.43	100.0	20.5	1.4	48	0.8	12.5	0.4	40	0.21	0.094	8
1279759	Soil	7.6	39.7	32.0	107	2.3	20.9	4.0	105	2.41	189.6	49.2	1.4	45	0.6	17.9	0.8	41	0.23	0.090	10
1279760	Soil	6.1	53.4	26.3	126	1.7	28.9	4.5	72	2.48	130.4	28.4	1.9	40	0.6	18.0	0.5	29	0.16	0.067	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 15, 2011

CERTIFICATE OF ANALYSIS WHI11001137.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279753	Soil	13	0.10	403	0.001	2	0.58	0.003	0.05	0.2	0.99	1.8	0.5	0.07	2	3.1	<0.2
1279754	Soil	17	0.10	303	0.002	4	0.66	0.003	0.07	0.2	0.81	1.7	0.5	<0.05	2	4.6	<0.2
1279755	Soil	12	0.05	364	0.001	3	0.63	0.005	0.07	0.2	1.55	1.3	0.8	0.08	2	2.5	<0.2
1279756	Soil	13	0.05	288	0.003	4	0.59	0.009	0.13	1.5	29.02	1.0	3.5	0.25	3	11.8	0.4
1279757	Soil	12	0.05	255	0.002	4	0.35	0.005	0.11	1.2	37.24	1.0	2.5	0.17	2	14.7	0.3
1279758	Soil	17	0.05	553	0.001	4	0.46	0.003	0.08	0.1	9.01	2.2	0.3	0.08	1	6.8	0.3
1279759	Soil	14	0.05	573	0.001	3	0.45	0.003	0.08	0.4	11.03	1.8	0.7	0.09	2	6.3	<0.2
1279760	Soil	14	0.05	435	<0.001	3	0.43	0.003	0.08	0.1	7.65	2.6	0.3	0.09	1	6.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 15, 2011

QUALITY CONTROL REPORT WHI11001137.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1279720	Soil	1.4	29.6	28.4	100	0.4	18.5	4.5	130	2.70	92.1	5.2	5.9	19	0.7	10.0	0.5	18	0.03	0.058	37
REP 1279720	QC	1.5	28.7	28.3	99	0.3	19.4	4.6	128	2.67	90.2	3.7	5.7	19	0.6	8.8	0.5	18	0.03	0.059	35
1279721	Soil	2.6	33.0	57.5	130	1.4	19.5	6.2	112	3.91	305.2	41.7	5.5	13	0.3	38.2	2.6	22	<0.01	0.062	30
REP 1279721	QC	2.8	33.9	59.4	129	1.4	20.9	6.4	111	3.97	309.7	43.0	5.6	14	0.3	33.3	2.6	23	<0.01	0.063	32
Reference Materials																					
STD DS8	Standard	12.6	108.5	125.2	321	1.9	37.5	7.5	618	2.51	25.4	114.3	6.0	58	2.1	4.7	6.3	41	0.71	0.085	14
STD DS8	Standard	13.6	113.6	123.2	324	1.8	38.9	7.9	644	2.54	26.0	110.3	6.9	69	2.5	5.2	6.6	44	0.73	0.082	17
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 15, 2011

QUALITY CONTROL REPORT WHI11001137.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1279720	Soil	9	0.22	87	<0.001	1	0.83	0.002	0.07	<0.1	0.83	2.3	0.1	0.05	2	1.1	<0.2
REP 1279720	QC	10	0.23	86	<0.001	<1	0.83	0.002	0.07	<0.1	0.79	2.2	0.1	0.09	2	1.2	<0.2
1279721	Soil	9	0.08	85	<0.001	2	0.70	0.002	0.09	0.3	1.05	2.6	0.4	0.10	2	3.7	<0.2
REP 1279721	QC	10	0.08	90	<0.001	1	0.71	0.002	0.09	0.3	1.05	2.5	0.4	0.06	2	4.5	<0.2
Reference Materials																	
STD DS8	Standard	116	0.64	274	0.107	2	0.90	0.084	0.42	2.8	0.21	2.2	5.3	0.12	5	5.6	5.0
STD DS8	Standard	119	0.63	279	0.125	3	0.98	0.086	0.41	2.8	0.18	2.2	5.6	0.20	5	5.3	5.4
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 19, 2011
Report Date: September 25, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11001137P.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #13
P.O. Number
Number of Samples: 38

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	38	Sieve to 230 mesh			WHI
1DX2	27	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Resplit from rejects and prep at SS230 because of the wrong prep for the original job.

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

CERTIFICATE OF ANALYSIS WHI11001137P.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279703	Soil		20.7	39.7	15.4	288	0.7	62.9	7.9	124	2.69	39.8	4.7	0.6	20	1.5	5.4	0.2	82	0.11	0.074	10
1279704	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279705	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279706	Soil		90.0	145.8	25.4	1730	3.5	237.9	20.4	573	2.18	114.8	8.7	0.4	155	33.4	30.5	0.2	1231	0.27	0.199	19
1279707	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279708	Soil		55.5	58.9	14.8	308	1.0	63.8	3.1	76	1.80	79.4	4.9	0.2	63	0.9	14.3	0.2	607	0.04	0.120	12
1279709	Soil		113.2	191.3	20.2	281	5.0	79.3	2.0	34	1.71	260.5	106.6	0.9	222	2.3	63.9	0.2	1419	0.05	0.226	15
1279710	Soil		27.6	29.0	12.1	83	1.9	19.0	1.4	18	0.72	37.2	18.1	<0.1	74	0.3	13.5	0.2	327	0.04	0.108	9
1279711	Soil		59.8	39.2	18.7	92	2.7	24.3	1.7	32	1.25	81.1	14.4	0.2	80	0.3	22.5	0.2	1020	0.04	0.171	15
1279712	Soil		57.0	33.0	18.9	77	1.9	18.8	1.7	34	1.33	77.1	17.4	0.2	63	0.5	18.1	0.3	500	0.04	0.135	14
1279713	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279714	Soil		13.8	10.5	43.0	10	1.7	2.9	0.3	10	0.82	54.7	22.9	2.2	21	<0.1	11.2	0.3	38	<0.01	0.029	4
1279715	Soil		47.7	29.8	42.8	35	7.4	6.1	0.7	20	2.07	126.6	13.3	1.1	70	0.1	39.6	0.5	174	0.03	0.122	25
1279716	Soil		10.3	60.0	43.1	211	0.4	41.5	14.3	780	5.22	94.2	3.6	1.2	40	0.8	4.1	0.4	79	0.01	0.119	5
1279717	Soil		3.9	23.4	28.5	94	1.4	16.3	4.4	328	2.93	152.7	16.1	2.0	11	0.2	11.9	1.4	35	0.01	0.063	19
1279718	Soil		3.5	28.4	45.7	133	1.5	21.1	6.0	124	3.60	305.1	80.7	3.2	14	0.3	34.5	2.0	27	0.01	0.060	21
1279719	Soil		2.1	23.0	42.0	94	1.2	13.0	3.7	80	2.71	237.1	46.6	4.1	11	0.3	35.3	1.6	22	0.02	0.060	30
1279720	Soil		1.7	27.7	31.9	87	0.4	18.3	4.6	128	2.73	94.9	6.3	4.8	20	0.6	10.6	0.5	21	0.03	0.056	37
1279721	Soil		2.9	30.3	60.4	109	1.5	18.4	5.2	87	3.68	305.5	48.5	4.4	13	0.2	46.3	2.4	23	<0.01	0.060	29
1279722	Soil		5.8	44.0	88.4	153	2.4	23.3	5.3	54	3.85	622.9	93.6	3.6	20	0.2	233.9	2.7	25	0.02	0.069	32
1279723	Soil		7.9	129.4	187.0	263	3.2	56.7	11.7	143	12.17	4291	219.2	12.9	63	0.7	110.2	15.8	78	0.02	0.294	31
1279724	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279725	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279726	Soil		8.3	95.8	44.8	163	9.7	29.0	4.5	134	4.17	132.5	71.1	2.7	292	1.5	14.1	0.4	140	0.49	1.013	18
1279727	Soil		2.8	21.9	24.6	139	1.4	23.6	5.4	68	2.68	111.7	6.1	0.9	41	0.2	7.8	0.3	29	0.01	0.107	6
1279728	Soil		4.8	32.7	48.7	226	0.3	50.3	10.6	251	3.70	50.0	2.9	1.6	43	0.6	3.9	0.4	18	0.09	0.051	4
1279729	Soil		2.5	26.8	25.0	208	0.2	41.7	9.4	243	2.99	38.6	2.4	1.0	24	0.9	3.3	0.3	15	0.08	0.040	3
1279730	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279751	Soil		13.0	50.9	24.5	142	1.4	24.0	3.9	113	3.49	187.1	15.6	1.5	28	0.8	9.6	0.4	56	0.05	0.071	11
1279752	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

CERTIFICATE OF ANALYSIS WHI11001137P.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279703	Soil	17	0.08	606	0.003	3	0.49	0.004	0.09	0.2	0.71	1.7	0.5	0.11	2	2.8	<0.2
1279704	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279705	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279706	Soil	67	0.10	778	0.008	10	0.93	0.002	0.16	0.7	1.70	2.9	9.8	0.14	3	16.1	0.6
1279707	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279708	Soil	40	0.07	230	0.005	4	0.80	0.008	0.08	0.4	1.00	0.6	3.3	0.08	3	7.0	0.2
1279709	Soil	82	0.08	1267	0.007	6	1.04	0.003	0.14	0.8	49.15	3.9	6.4	0.11	4	15.7	0.4
1279710	Soil	31	0.02	612	0.002	2	0.41	0.005	0.06	0.3	14.48	0.1	1.9	0.06	3	6.1	<0.2
1279711	Soil	70	0.04	1269	0.006	5	0.68	0.004	0.13	0.6	10.95	0.5	4.5	0.08	6	12.3	0.3
1279712	Soil	44	0.06	887	0.007	3	0.67	0.005	0.10	0.6	6.93	0.7	2.8	0.11	5	12.8	0.3
1279713	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279714	Soil	8	0.01	520	0.002	4	0.19	0.002	0.12	0.1	5.70	1.2	0.7	0.20	1	7.5	0.2
1279715	Soil	19	0.02	1935	0.003	4	0.48	0.003	0.06	0.7	5.15	0.8	1.9	0.11	4	11.1	0.6
1279716	Soil	13	0.04	152	0.003	1	0.67	0.005	0.10	<0.1	0.42	5.4	1.0	0.16	2	2.6	<0.2
1279717	Soil	14	0.05	104	0.003	<1	0.67	0.004	0.08	0.3	0.98	1.5	0.3	<0.05	3	2.2	<0.2
1279718	Soil	15	0.07	92	<0.001	2	0.66	0.002	0.09	0.7	2.30	2.2	0.5	0.09	2	3.3	<0.2
1279719	Soil	9	0.10	87	<0.001	<1	0.56	0.001	0.08	0.4	1.40	1.8	0.3	0.06	2	2.3	<0.2
1279720	Soil	13	0.19	100	<0.001	3	0.81	0.002	0.09	<0.1	1.01	2.1	0.1	0.08	2	1.7	<0.2
1279721	Soil	12	0.07	96	<0.001	1	0.68	0.002	0.09	0.4	0.98	2.5	0.4	0.08	2	4.1	<0.2
1279722	Soil	14	0.06	128	0.002	2	0.46	0.003	0.11	1.0	4.07	1.4	0.8	0.12	2	12.1	0.2
1279723	Soil	35	0.33	365	0.007	2	1.26	0.009	0.15	10.4	4.55	9.4	1.3	0.34	5	22.0	2.6
1279724	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279725	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279726	Soil	45	0.04	1498	0.007	10	0.95	0.006	0.19	0.4	7.18	5.6	0.9	0.31	4	16.8	0.4
1279727	Soil	11	0.01	458	<0.001	3	0.32	0.002	0.10	<0.1	0.78	1.8	0.3	0.16	1	2.4	<0.2
1279728	Soil	9	0.03	423	<0.001	3	0.24	0.003	0.09	<0.1	0.31	3.8	0.8	0.12	<1	0.8	<0.2
1279729	Soil	6	0.03	366	<0.001	2	0.21	0.002	0.06	<0.1	0.36	3.6	0.3	0.06	<1	1.2	<0.2
1279730	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279751	Soil	17	0.07	260	0.003	2	0.55	0.006	0.07	0.3	1.35	1.9	0.6	0.06	2	3.8	<0.2
1279752	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

CERTIFICATE OF ANALYSIS WHI11001137P.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279753	Soil	12.3	33.3	19.2	231	0.9	36.3	6.1	168	3.40	142.2	11.1	1.9	28	0.4	9.2	0.3	58	0.13	0.080	13
1279754	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279755	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279756	Soil	20.8	43.1	113.7	126	3.4	16.3	3.2	48	3.67	733.8	272.2	1.8	79	0.8	52.9	3.5	86	0.04	0.143	21
1279757	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279758	Soil	9.0	44.3	23.0	124	2.3	27.6	4.0	97	2.29	97.3	23.5	1.1	49	0.7	13.1	0.4	40	0.22	0.104	7
1279759	Soil	7.8	39.2	33.1	100	2.6	23.4	4.1	120	2.22	180.4	77.5	1.5	52	0.6	21.7	1.0	43	0.24	0.092	12
1279760	Soil	6.9	53.3	29.5	128	2.1	28.9	4.9	89	2.37	130.8	27.8	2.0	50	0.7	24.2	0.7	35	0.17	0.070	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

CERTIFICATE OF ANALYSIS WHI11001137P.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279753	Soil	16	0.10	506	0.001	3	0.59	0.004	0.06	0.3	1.15	2.0	0.5	0.09	2	3.3	<0.2
1279754	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279755	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279756	Soil	16	0.06	325	0.004	4	0.59	0.009	0.15	2.0	31.41	1.1	3.9	0.29	3	13.6	0.2
1279757	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279758	Soil	18	0.06	615	0.001	4	0.43	0.003	0.08	0.2	11.19	2.1	0.3	0.11	1	8.0	<0.2
1279759	Soil	18	0.08	713	0.002	3	0.53	0.005	0.09	0.4	11.83	1.7	0.7	0.08	2	7.3	0.3
1279760	Soil	18	0.06	548	0.001	4	0.48	0.004	0.09	0.2	9.80	2.5	0.4	0.07	1	7.2	0.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

QUALITY CONTROL REPORT WHI11001137P.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1279719	Soil	2.1	23.0	42.0	94	1.2	13.0	3.7	80	2.71	237.1	46.6	4.1	11	0.3	35.3	1.6	22	0.02	0.060	30
REP 1279719	QC	2.0	21.8	42.0	93	1.2	13.0	3.5	79	2.63	229.1	43.0	3.9	11	0.2	33.7	1.6	22	0.02	0.058	30
1279754	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1279754	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
Reference Materials																					
STD DS8	Standard	14.0	119.2	129.4	327	1.8	40.8	8.4	644	2.57	25.4	108.5	6.9	72	2.6	5.6	7.1	47	0.72	0.084	16
STD DS8	Standard	12.5	109.3	113.9	307	1.7	37.5	7.7	592	2.37	24.6	101.6	5.4	56	2.1	4.8	5.3	41	0.68	0.073	14
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

QUALITY CONTROL REPORT WHI11001137P.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1279719	Soil	9	0.10	87	<0.001	<1	0.56	0.001	0.08	0.4	1.40	1.8	0.3	0.06	2	2.3	<0.2
REP 1279719	QC	9	0.10	86	<0.001	1	0.56	0.001	0.08	0.4	1.56	1.7	0.3	0.06	2	2.8	<0.2
1279754	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1279754	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
Reference Materials																	
STD DS8	Standard	125	0.63	284	0.133	2	0.97	0.099	0.42	3.3	0.23	3.3	5.5	0.20	4	5.6	5.4
STD DS8	Standard	118	0.60	266	0.106	3	0.88	0.095	0.41	2.9	0.24	2.5	5.3	0.14	5	5.4	5.2
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 18, 2011
Report Date: October 06, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001180.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #14
P.O. Number
Number of Samples: 321

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	321	Sieve soil to 230 mesh			WHI
RJSV	321	Saving all or part of Soil Reject			WHI
1DX2	320	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	1	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1091682	Soil		24.1	31.7	5.4	71	0.5	3.6	1.1	38	32.19	1228	2.3	1.0	6	0.5	49.5	0.2	2427	0.02	1.421	2
1091683	Soil		23.4	25.0	18.7	33	1.1	7.9	0.7	52	1.71	41.3	2.1	1.1	27	0.1	8.1	0.3	106	0.03	0.050	14
1091684	Soil		6.2	65.9	20.0	76	0.1	41.5	32.2	312	4.85	22.2	2.2	3.4	12	0.6	2.8	1.2	42	0.09	0.098	21
1091685	Soil		14.2	51.2	29.6	247	0.3	55.8	8.3	140	3.21	27.9	2.1	0.4	32	0.4	4.1	0.3	119	0.03	0.185	11
1091686	Soil		50.2	57.8	14.2	698	0.9	125.2	10.9	240	2.57	22.2	3.0	4.6	93	7.4	13.0	0.2	152	3.18	0.087	11
1091687	Soil		3.7	45.2	24.5	178	0.6	41.3	12.8	193	3.84	21.8	<0.5	2.5	76	0.2	1.5	0.3	54	0.14	0.116	4
1091688	Soil		3.4	57.4	56.5	178	0.4	44.1	13.6	232	7.90	24.5	2.3	6.1	65	<0.1	1.7	0.3	36	0.03	0.102	3
1091689	Soil		1.6	36.0	24.3	70	0.3	21.8	5.3	180	3.60	15.4	3.7	1.4	17	0.1	0.7	0.3	49	0.02	0.084	4
1091690	Soil		1.3	24.2	22.2	47	0.2	14.3	6.7	275	2.41	9.9	1.0	0.7	20	0.2	0.6	0.4	41	0.04	0.108	5
1091640	Soil		5.2	214.6	9.9	85	1.8	6.7	1.2	23	33.80	14.5	3.8	1.1	33	0.3	5.3	0.3	130	0.03	0.126	<1
1091642	Soil		19.8	60.1	19.0	143	1.9	28.4	3.0	84	7.13	25.0	2.8	1.3	57	0.5	10.8	0.2	250	0.04	0.247	1
1091650	Soil		6.1	9.5	18.4	2	1.4	2.4	<0.1	<1	0.53	<0.5	<0.5	1.7	46	<0.1	5.6	0.3	72	<0.01	0.038	<1
1093461	Soil		25.8	30.5	17.9	287	0.8	60.7	6.5	217	2.63	17.8	1.9	0.8	27	1.2	5.5	0.3	126	0.15	0.141	7
1095280	Soil		5.4	25.8	24.2	316	0.6	97.2	4.4	79	1.41	12.2	3.8	0.4	74	2.8	3.9	0.2	43	0.58	0.315	11
1095495	Soil		6.0	153.9	15.1	1124	0.3	543.7	138.6	2585	15.86	161.6	1.5	2.3	133	4.9	4.3	<0.1	204	1.90	0.199	5
1095496	Soil		13.1	153.0	21.2	253	0.4	497.3	90.0	2023	15.71	22.4	2.2	3.2	132	0.7	2.9	<0.1	318	2.25	0.314	6
1094951	Soil		1.3	23.8	17.3	66	0.5	12.7	4.0	63	2.21	13.3	1.8	1.1	13	0.2	0.6	0.2	54	0.02	0.065	4
1276431	Soil		130.7	129.7	22.0	1429	1.4	268.7	9.2	218	2.43	188.9	13.3	3.5	171	14.7	43.5	0.2	492	5.29	0.110	13
1276432	Soil		106.5	133.7	15.8	1954	2.6	311.8	6.0	152	1.40	72.7	4.6	2.4	211	18.2	32.3	0.2	914	7.83	0.103	15
1276433	Soil		56.0	65.4	14.0	351	0.5	175.9	9.7	337	2.36	40.0	1.6	2.0	244	4.0	7.2	<0.1	135	8.28	0.087	10
1276434	Soil		97.4	68.9	10.8	450	0.2	213.0	11.0	202	2.07	83.9	2.6	2.9	231	4.2	8.6	<0.1	78	8.95	0.085	8
1276435	Soil		65.7	81.7	13.4	757	0.7	216.0	9.6	267	1.90	89.5	3.2	2.2	177	5.1	16.8	<0.1	320	7.16	0.107	16
1276436	Soil		68.8	93.4	15.3	1112	0.9	201.9	9.6	157	1.93	69.9	1.3	1.0	82	9.5	16.4	0.1	375	2.68	0.104	17
1276437	Soil		89.6	68.3	9.3	179	0.2	167.3	9.8	174	1.94	22.0	0.8	3.2	124	1.5	2.8	0.1	42	4.54	0.085	8
1276438	Soil		74.4	68.1	8.7	154	0.2	169.4	7.9	181	1.51	20.4	<0.5	2.4	291	1.7	2.7	<0.1	39	9.57	0.064	6
1276439	Soil		119.7	65.3	12.1	672	0.2	248.4	19.9	381	2.22	29.8	<0.5	3.1	234	5.2	4.2	0.2	59	6.38	0.120	6
1276440	Soil		12.5	74.1	29.6	331	1.9	92.5	15.1	535	4.12	54.9	4.1	4.1	124	2.1	4.9	0.4	87	0.96	0.220	17
1276441	Soil		3.6	44.6	13.0	69	1.0	38.7	9.7	254	2.71	93.4	4.6	1.1	73	<0.1	2.0	0.2	16	0.98	0.126	8
1276442	Soil		4.8	108.3	38.1	146	2.5	74.1	20.4	451	5.45	216.1	10.8	3.2	214	0.5	4.5	0.4	28	0.83	0.268	10
1276443	Soil		8.3	60.9	16.3	84	0.3	48.3	14.6	321	3.62	29.2	3.7	0.4	15	0.4	2.1	0.3	52	0.06	0.173	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1091682	Soil		103	0.02	219	0.015	2	0.56	0.004	0.02	<0.1	0.13	1.5	<0.1	0.36	2	11.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091683	Soil		16	0.02	379	0.003	1	0.32	0.009	0.09	<0.1	0.29	1.5	1.2	0.17	2	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091684	Soil		24	0.08	440	0.006	12	0.81	0.003	0.23	<0.1	0.06	4.5	0.6	<0.05	2	1.2	0.3	N.A.	N.A.	N.A.	N.A.
1091685	Soil		26	0.06	238	0.003	2	0.80	0.003	0.10	0.2	0.07	0.7	0.6	0.09	4	2.1	0.2	N.A.	N.A.	N.A.	N.A.
1091686	Soil		20	1.66	504	0.003	6	0.29	0.005	0.10	<0.1	0.31	4.8	0.5	<0.05	<1	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091687	Soil		33	0.11	1712	<0.001	<1	0.94	0.005	0.08	<0.1	0.72	7.0	0.1	0.06	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091688	Soil		57	0.35	303	0.001	<1	1.63	0.007	0.11	<0.1	0.16	7.4	0.3	0.15	5	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1091689	Soil		36	0.22	366	<0.001	<1	1.49	0.006	0.08	<0.1	0.07	2.9	0.1	<0.05	5	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1091690	Soil		29	0.12	287	0.003	1	1.16	0.011	0.07	<0.1	0.04	1.5	0.2	<0.05	4	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1091640	Soil		35	0.03	205	0.007	2	0.50	0.005	0.04	<0.1	0.34	1.7	0.3	0.92	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1091642	Soil		40	0.09	347	0.002	2	0.50	0.004	0.10	<0.1	0.43	4.0	0.7	0.41	2	7.2	<0.2	N.A.	N.A.	N.A.	N.A.
1091650	Soil		18	0.01	445	<0.001	2	0.20	0.003	0.11	<0.1	0.47	3.7	0.5	0.13	<1	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
1093461	Soil		28	0.08	440	0.003	2	0.77	0.008	0.07	<0.1	0.26	2.3	0.5	0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1095280	Soil		21	0.11	438	0.006	3	0.73	0.022	0.06	<0.1	0.17	1.2	0.2	0.08	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1095495	Soil		391	1.15	412	0.002	6	1.38	0.004	0.03	<0.1	0.11	35.3	0.2	<0.05	5	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1095496	Soil		371	0.77	571	0.004	2	0.71	0.007	0.06	<0.1	0.14	30.9	0.9	<0.05	3	2.5	0.2	N.A.	N.A.	N.A.	N.A.
1094951	Soil		15	0.04	215	0.001	<1	0.80	0.007	0.08	<0.1	0.03	1.7	<0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1276431	Soil		36	1.85	328	0.003	8	0.40	0.006	0.12	0.3	10.51	4.4	2.2	<0.05	1	7.8	0.2	N.A.	N.A.	N.A.	N.A.
1276432	Soil		53	1.55	338	0.010	10	0.65	0.014	0.17	0.3	1.53	3.7	3.8	<0.05	2	6.8	0.2	N.A.	N.A.	N.A.	N.A.
1276433	Soil		25	3.56	347	0.004	11	0.36	0.009	0.11	0.2	0.35	3.4	3.2	0.07	<1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1276434	Soil		23	2.95	317	0.002	6	0.35	0.006	0.08	0.1	0.73	3.6	3.2	<0.05	<1	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276435	Soil		35	3.45	299	0.005	15	0.50	0.009	0.15	0.2	0.38	4.0	3.7	0.05	1	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276436	Soil		35	1.13	362	0.006	10	0.66	0.017	0.14	0.2	0.37	3.4	2.2	0.06	2	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1276437	Soil		19	1.68	243	0.003	6	0.26	0.006	0.07	0.1	0.29	4.4	1.4	<0.05	<1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1276438	Soil		20	1.39	216	0.003	5	0.19	0.006	0.06	0.1	0.34	3.4	1.5	<0.05	<1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276439	Soil		22	1.87	245	0.003	7	0.26	0.005	0.08	0.2	0.48	5.4	1.7	<0.05	<1	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276440	Soil		23	0.21	3777	0.004	8	0.74	0.011	0.20	<0.1	0.65	6.0	0.4	0.10	1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1276441	Soil		12	0.18	1161	0.005	6	0.60	0.022	0.09	<0.1	0.25	3.1	0.2	0.13	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1276442	Soil		11	0.14	1078	0.002	8	0.59	0.006	0.13	<0.1	0.58	6.4	0.4	0.18	1	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276443	Soil		10	0.05	333	0.003	5	0.46	0.004	0.08	<0.1	0.07	0.4	0.1	0.09	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1091682	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091683	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091684	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091685	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091686	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091687	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091688	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091689	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091690	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091640	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091642	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091650	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093461	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095280	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095495	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095496	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094951	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276431	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276432	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276433	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276434	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276435	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276436	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276437	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276438	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276439	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276440	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276441	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276442	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276443	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1091682	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091683	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091684	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091685	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091686	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091687	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091688	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091689	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091690	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091640	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091642	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1091650	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1093461	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095280	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095495	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095496	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1094951	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276431	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276432	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276433	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276434	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276435	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276436	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276437	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276438	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276439	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276440	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276441	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276442	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276443	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1276444	Soil		6.3	123.0	19.6	282	2.1	141.5	5.6	283	2.00	44.2	7.0	2.2	142	1.6	5.8	0.2	85	1.01	0.328	19
1276445	Soil		7.0	133.7	22.0	272	2.1	153.1	7.2	143	1.96	56.6	10.3	2.0	149	1.6	6.8	0.2	84	1.18	0.254	17
1276446	Soil		41.5	108.1	116.6	186	5.4	53.9	5.1	98	3.77	91.4	5.2	1.8	377	3.0	16.1	0.5	406	0.79	0.803	25
1276447	Soil		14.2	40.1	50.6	80	1.4	24.4	3.0	70	1.54	20.0	4.1	<0.1	142	1.0	4.2	0.3	134	0.20	0.252	14
1276448	Soil		1.9	79.4	46.0	52	0.9	116.6	44.5	2243	11.67	18.4	9.4	3.8	11	0.2	2.4	0.2	22	0.13	0.072	23
1276449	Soil		3.2	84.3	20.4	69	0.3	74.5	23.6	855	4.93	33.7	7.6	1.1	11	0.1	1.9	0.4	21	0.06	0.084	35
1276450	Soil		3.4	101.9	19.7	90	0.4	72.6	29.4	1016	6.94	53.4	7.2	1.5	12	0.2	2.5	0.5	31	0.12	0.081	30
1277931	Soil		3.3	15.9	19.1	51	2.1	8.8	2.4	46	1.23	109.3	72.3	0.4	17	0.1	10.0	10.0	36	0.02	0.044	13
1277932	Soil		4.9	33.1	14.6	72	0.4	20.2	5.0	57	2.83	225.5	6.5	0.7	25	0.4	8.4	2.3	51	0.02	0.075	21
1277933	Soil		2.0	21.8	7.4	30	0.7	9.6	2.1	30	1.35	48.4	3.9	0.2	9	0.2	2.8	0.9	25	0.03	0.080	8
1277934	Soil		5.8	48.3	28.2	63	1.5	12.8	3.0	42	1.88	193.6	8.2	0.3	15	0.4	10.0	5.9	60	0.03	0.071	24
1277935	Soil		1.8	55.0	5.1	14	0.7	3.4	0.8	16	0.76	28.5	3.7	0.1	7	0.3	1.6	0.4	18	0.02	0.061	5
1277936	Soil		5.2	31.7	14.8	53	0.6	9.6	2.4	43	1.73	83.2	3.9	0.3	15	0.4	3.8	1.1	60	0.02	0.087	18
1277937	Soil		7.5	65.3	29.8	86	1.3	14.6	5.5	97	6.04	614.7	34.3	4.0	25	0.3	8.9	11.1	43	<0.01	0.131	30
1277938	Soil		6.1	56.7	34.2	76	1.5	11.8	4.8	146	5.50	533.7	18.4	9.8	44	0.3	11.8	11.6	47	0.06	0.113	25
1277939	Soil		3.4	38.3	24.2	48	0.6	8.8	1.9	40	3.36	216.3	22.1	7.5	35	0.3	8.4	1.9	24	<0.01	0.067	24
1277940	Soil		5.9	27.1	54.3	82	0.7	16.8	3.6	44	3.05	336.8	41.8	4.7	38	0.3	10.8	1.5	38	0.01	0.072	24
1277941	Soil		18.8	24.5	58.8	94	1.1	16.3	3.5	82	2.52	93.4	26.3	0.6	89	0.3	13.4	0.4	111	0.02	0.113	9
1277942	Soil		11.6	23.0	53.2	99	1.0	17.8	4.7	103	2.73	100.2	18.9	2.2	66	0.3	15.2	0.4	62	0.01	0.063	13
1277943	Soil		4.2	33.4	42.1	131	0.7	30.2	8.1	161	4.06	109.6	6.5	3.9	56	0.2	9.6	0.5	35	<0.01	0.077	20
1277944	Soil		10.3	24.4	37.0	132	0.4	17.3	3.9	110	3.21	52.0	10.0	1.1	81	0.4	10.7	0.3	76	0.01	0.067	8
1277945	Soil		15.0	20.9	46.5	64	1.2	9.7	1.4	27	1.75	45.7	12.9	0.6	125	0.2	9.8	0.3	115	0.11	0.125	8
1277946	Soil		107.1	53.3	649.5	20	3.1	20.3	0.7	23	2.22	240.3	1.2	1.9	115	<0.1	41.3	0.7	441	0.12	0.136	9
1277947	Soil		36.3	37.7	388.4	52	9.4	38.5	1.2	21	1.22	73.8	14.2	0.7	95	0.5	21.9	0.4	285	0.05	0.139	13
1277948	Soil		123.8	58.5	1635	96	8.0	27.9	2.3	47	3.18	318.5	97.9	1.3	348	0.4	67.8	0.9	558	0.14	0.243	12
1277949	Soil		65.1	495.8	30.3	330	11.4	109.3	1.8	19	3.83	390.1	206.5	3.2	208	1.4	106.6	0.3	1014	0.08	0.501	19
1277950	Soil		46.7	94.4	33.4	164	4.0	38.8	2.0	30	2.19	159.1	126.5	0.3	182	1.2	25.4	0.3	819	0.09	0.323	13
1277951	Soil		54.2	238.8	25.3	1045	5.9	241.7	23.4	562	3.78	276.7	112.5	3.0	138	10.2	59.4	0.3	631	0.19	0.236	16
1277952	Soil		95.1	245.6	23.9	1166	11.1	260.1	17.5	249	4.50	616.6	264.8	2.1	254	14.5	146.2	0.2	1045	0.09	0.307	13
1277953	Soil		57.8	51.7	31.2	354	4.8	56.4	4.9	56	2.39	64.2	20.5	0.4	80	0.9	23.4	0.3	475	0.04	0.156	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1276444	Soil	22	0.30	474	0.003	10	0.54	0.005	0.18	0.1	1.20	3.6	0.6	0.13	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276445	Soil	17	0.49	587	0.003	7	0.53	0.006	0.14	0.1	1.28	3.4	0.5	0.15	1	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1276446	Soil	30	0.09	763	0.008	6	0.77	0.007	0.24	0.6	0.51	1.9	1.3	0.39	3	11.0	0.5	N.A.	N.A.	N.A.	N.A.
1276447	Soil	16	0.04	324	0.001	4	0.54	0.010	0.09	0.3	0.14	<0.1	0.4	0.21	2	2.7	0.3	N.A.	N.A.	N.A.	N.A.
1276448	Soil	11	0.10	586	0.002	5	0.44	0.005	0.08	<0.1	0.26	6.9	0.2	<0.05	<1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276449	Soil	8	0.06	166	0.004	5	0.39	0.012	0.08	<0.1	0.12	2.8	0.1	<0.05	1	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1276450	Soil	14	0.12	338	0.005	4	0.67	0.003	0.09	0.1	0.09	3.4	0.1	<0.05	2	1.0	0.3	N.A.	N.A.	N.A.	N.A.
1277931	Soil	7	0.02	94	0.006	3	0.47	0.014	0.04	3.1	1.93	0.2	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277932	Soil	11	0.03	123	0.006	<1	0.55	0.009	0.04	0.4	0.49	0.6	0.2	0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277933	Soil	7	0.03	80	0.004	2	0.53	0.016	0.03	0.4	0.30	0.2	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277934	Soil	12	0.02	130	0.007	3	0.59	0.007	0.04	4.0	1.10	0.2	0.1	<0.05	3	1.5	0.2	N.A.	N.A.	N.A.	N.A.
1277935	Soil	5	0.02	40	0.003	<1	0.42	0.020	0.02	0.2	0.29	0.2	0.1	<0.05	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277936	Soil	11	0.03	117	0.007	2	0.68	0.006	0.04	0.5	0.41	0.3	0.2	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277937	Soil	16	0.07	161	0.002	1	0.68	0.002	0.07	3.6	0.37	1.2	0.2	0.07	3	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277938	Soil	18	0.19	225	0.001	2	0.76	0.004	0.14	0.9	0.89	2.1	0.3	0.21	3	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277939	Soil	11	0.18	147	<0.001	2	0.61	0.003	0.09	0.2	0.72	1.8	0.2	0.15	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277940	Soil	11	0.08	195	<0.001	3	0.62	0.003	0.09	0.3	0.78	1.5	0.3	0.14	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277941	Soil	14	0.04	564	0.003	5	0.48	0.007	0.11	0.3	2.40	0.9	1.1	0.21	2	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277942	Soil	9	0.02	511	0.002	2	0.33	0.002	0.08	0.2	2.08	1.7	0.8	0.07	1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277943	Soil	14	0.02	309	<0.001	1	0.51	0.002	0.06	0.1	0.21	2.5	0.3	0.08	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277944	Soil	11	0.02	456	0.001	4	0.35	0.004	0.11	0.1	0.34	1.9	0.7	0.19	1	3.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277945	Soil	13	0.02	814	0.004	6	0.34	0.005	0.20	0.2	0.65	0.9	1.4	0.42	2	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277946	Soil	27	0.02	466	0.002	4	0.49	0.004	0.25	0.9	3.29	2.9	2.1	0.54	4	22.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277947	Soil	39	0.02	1131	0.003	4	0.53	0.003	0.08	0.9	2.28	0.6	0.8	0.16	3	6.1	0.3	N.A.	N.A.	N.A.	N.A.
1277948	Soil	44	0.02	725	0.003	4	0.69	0.003	0.21	2.0	15.77	0.9	3.1	0.59	4	19.5	0.4	N.A.	N.A.	N.A.	N.A.
1277949	Soil	94	0.05	657	0.004	4	2.00	0.002	0.11	0.9	>50	6.7	5.6	0.14	4	17.4	0.6	N.A.	N.A.	N.A.	N.A.
1277950	Soil	82	0.07	672	0.002	5	1.48	0.002	0.11	0.6	6.79	0.6	2.8	0.16	6	8.8	0.3	N.A.	N.A.	N.A.	N.A.
1277951	Soil	47	0.26	704	0.009	5	2.13	0.004	0.12	0.5	42.27	4.1	3.9	0.10	3	9.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277952	Soil	56	0.11	556	0.007	6	3.46	0.005	0.09	0.9	>50	4.8	2.8	0.14	4	15.5	0.5	N.A.	N.A.	N.A.	N.A.
1277953	Soil	33	0.03	546	0.004	3	0.81	0.004	0.12	0.4	1.61	0.3	1.5	0.15	4	5.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1276444	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276445	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276446	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276447	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276448	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276449	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276450	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277931	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277932	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277933	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277934	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277935	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277936	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277937	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277938	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277939	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277940	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277941	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277942	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277943	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277944	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277945	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277946	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277947	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277948	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277949	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277950	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277951	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277952	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277953	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1276444	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276445	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276446	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276447	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276448	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276449	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1276450	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277931	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277932	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277933	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277934	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277935	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277936	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277937	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277938	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277939	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277940	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277941	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277942	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277943	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277944	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277945	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277946	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277947	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277948	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277949	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277950	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277951	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277952	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277953	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277954	Soil	22.0	22.0	21.1	199	0.6	40.2	4.0	48	1.46	34.2	5.2	0.2	27	0.3	9.4	0.2	235	0.01	0.054	13
1277955	Soil	12.7	15.4	22.2	112	0.3	22.1	2.5	37	1.08	33.7	4.3	0.1	22	0.3	5.4	0.2	117	0.02	0.055	10
1277956	Soil	4.2	15.2	6.7	38	0.6	8.1	1.2	18	0.59	9.9	4.1	0.2	9	0.6	1.8	<0.1	43	0.01	0.097	5
1277957	Soil	11.2	32.7	24.3	146	0.6	30.4	10.1	270	2.02	58.4	7.0	0.5	24	1.7	5.6	0.3	88	0.01	0.122	14
1277958	Soil	12.3	20.0	20.5	132	0.4	25.3	3.9	72	1.17	39.6	3.9	0.3	19	1.2	4.8	0.3	89	0.02	0.105	10
1277959	Soil	10.9	34.7	13.4	477	1.4	58.7	5.0	292	1.89	40.6	7.5	0.6	37	2.7	4.6	0.4	84	0.35	0.129	9
1277960	Soil	1.1	10.8	2.8	46	1.2	7.0	0.6	11	0.33	5.4	2.9	0.1	13	1.5	0.7	0.1	15	0.12	0.044	1
1277961	Soil	11.1	27.2	15.8	131	0.4	26.6	3.6	58	1.55	40.5	5.1	0.2	19	1.0	4.3	0.3	79	0.02	0.071	10
1277962	Soil	21.5	33.8	12.9	217	0.9	45.6	3.4	56	1.56	51.1	6.5	0.5	20	1.7	9.2	0.3	289	0.03	0.095	13
1277963	Soil	9.4	31.1	13.8	164	1.7	33.8	3.1	52	1.26	34.2	11.2	0.4	26	1.6	4.4	0.3	90	0.05	0.098	8
1277964	Soil	90.7	101.3	13.7	864	1.6	268.2	11.9	356	2.58	72.7	5.2	1.2	66	8.6	17.8	0.3	330	1.25	0.146	15
1277965	Soil	166.5	138.0	17.4	1304	2.4	406.9	12.4	193	2.95	125.3	5.6	2.0	109	17.5	34.9	0.2	596	2.76	0.138	14
1277966	Soil	47.5	52.7	13.1	408	0.5	125.7	8.7	202	2.36	60.8	2.7	1.1	61	4.3	9.4	0.2	169	1.20	0.081	10
1277967	Soil	50.6	70.0	13.6	482	0.7	182.9	11.8	251	3.01	69.7	7.8	2.6	35	1.7	9.5	0.2	162	0.36	0.079	16
1277968	Soil	18.1	19.6	7.8	183	0.1	42.1	3.2	44	1.06	26.7	1.0	0.3	22	0.9	4.2	0.1	154	0.24	0.056	9
1277969	Soil	110.8	126.0	19.0	1506	1.4	261.4	10.1	260	2.33	118.7	7.5	0.6	100	16.2	30.2	0.2	478	1.07	0.176	20
1277970	Soil	44.6	105.5	12.4	797	0.8	140.3	4.5	92	1.40	76.0	8.0	0.5	118	14.7	15.3	0.2	357	1.61	0.159	10
1277971	Soil	32.9	53.9	41.8	331	1.2	77.5	7.4	118	2.64	80.6	9.9	0.6	57	2.1	12.9	0.4	235	0.19	0.205	16
1277972	Soil	44.8	51.0	8.6	466	0.3	154.7	7.8	220	1.61	44.1	3.0	0.9	48	6.3	9.1	0.1	214	0.78	0.090	13
1277973	Soil	67.7	52.2	10.4	532	0.4	202.0	9.2	153	2.08	74.8	6.4	1.1	38	5.8	11.8	0.2	160	0.33	0.087	12
1277974	Soil	52.8	68.3	16.3	713	1.7	115.2	5.6	117	2.26	83.2	6.3	0.4	33	13.3	29.1	0.2	634	0.12	0.132	18
1277975	Soil	11.0	56.6	23.6	542	0.8	82.9	9.5	232	2.66	83.2	11.1	0.7	37	4.1	8.7	0.3	191	0.12	0.128	12
1277976	Soil	6.7	14.0	23.7	101	0.5	15.9	3.4	84	1.70	46.2	10.0	0.7	36	0.5	7.5	0.3	29	0.02	0.031	5
1277977	Soil	6.5	12.7	25.9	101	0.4	16.9	3.2	88	1.87	44.3	10.2	0.7	52	0.5	7.3	0.3	32	0.01	0.041	6
1277978	Soil	5.3	11.5	20.5	84	0.4	14.2	3.5	246	1.71	38.6	6.7	0.7	39	0.4	6.1	0.2	30	<0.01	0.045	7
1277979	Soil	37.0	19.3	6.8	213	0.1	64.3	4.6	106	1.34	34.0	1.9	1.0	13	0.9	5.7	0.1	122	0.17	0.029	15
1277980	Soil	15.6	54.8	54.5	299	3.0	128.7	22.6	4481	13.50	61.2	10.2	3.3	33	6.7	8.3	0.2	130	0.50	0.234	27
1277981	Soil	11.9	53.5	24.8	231	0.5	40.4	6.5	140	2.65	38.8	3.4	0.3	17	0.5	7.1	0.3	63	0.11	0.158	12
1277982	Soil	23.2	35.2	29.4	202	0.4	55.5	5.6	74	2.98	45.7	3.2	0.6	49	0.3	6.9	0.3	79	0.02	0.074	10
1277983	Soil	8.9	50.8	28.3	89	1.1	22.1	3.4	78	1.29	18.0	2.7	0.2	113	0.4	3.5	0.3	73	0.11	0.191	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277954	Soil	13	0.02	426	0.005	2	0.36	0.003	0.06	0.2	0.86	0.2	0.6	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277955	Soil	9	0.02	180	0.003	1	0.38	0.007	0.05	0.2	0.36	0.2	0.4	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277956	Soil	6	0.02	120	0.003	<1	0.45	0.016	0.03	<0.1	0.38	0.4	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277957	Soil	13	0.04	383	0.004	<1	0.65	0.004	0.06	0.1	0.47	0.4	0.4	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1277958	Soil	10	0.03	521	0.004	3	0.53	0.003	0.05	0.2	0.30	0.5	0.4	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277959	Soil	13	0.08	829	0.004	3	0.85	0.008	0.05	0.2	0.99	1.4	0.6	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277960	Soil	3	0.01	250	0.004	1	0.26	0.021	0.02	<0.1	0.49	0.5	<0.1	<0.05	<1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277961	Soil	11	0.04	167	0.005	1	0.44	0.004	0.05	0.2	0.33	0.6	0.3	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277962	Soil	23	0.08	225	0.006	2	0.72	0.004	0.06	0.2	0.90	0.6	0.9	<0.05	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277963	Soil	15	0.08	355	0.005	3	0.70	0.011	0.07	0.2	2.02	0.8	0.6	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277964	Soil	46	0.21	429	0.003	6	0.62	0.003	0.09	0.4	1.97	5.6	2.0	0.09	2	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277965	Soil	48	1.03	378	0.003	7	0.57	0.004	0.12	0.7	3.57	6.1	3.2	0.10	2	9.9	0.3	N.A.	N.A.	N.A.	N.A.
1277966	Soil	23	0.23	547	0.004	3	0.61	0.004	0.08	0.3	0.61	2.7	1.4	0.06	2	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277967	Soil	38	0.23	721	0.007	4	1.44	0.005	0.06	0.3	1.37	5.7	2.4	<0.05	3	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277968	Soil	14	0.05	423	0.004	2	0.63	0.009	0.05	0.2	0.10	0.8	0.8	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277969	Soil	42	0.24	572	0.004	4	0.86	0.005	0.07	0.6	2.85	2.8	3.2	<0.05	3	10.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277970	Soil	20	0.09	528	0.006	4	0.60	0.014	0.06	0.3	5.08	1.6	1.6	0.09	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277971	Soil	21	0.11	400	0.007	4	0.63	0.005	0.12	0.3	2.79	1.1	1.3	0.12	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277972	Soil	24	0.14	675	0.004	5	0.79	0.011	0.07	0.4	0.38	3.1	2.3	<0.05	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1277973	Soil	24	0.07	513	0.004	4	0.61	0.005	0.06	0.5	0.49	3.6	2.8	<0.05	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277974	Soil	34	0.07	498	0.006	4	0.71	0.004	0.09	0.3	0.65	0.8	2.4	<0.05	4	8.9	0.2	N.A.	N.A.	N.A.	N.A.
1277975	Soil	23	0.24	266	0.008	2	1.32	0.006	0.07	0.2	2.23	1.3	1.0	<0.05	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277976	Soil	5	0.01	380	<0.001	6	0.21	0.002	0.08	<0.1	13.10	1.7	0.7	0.10	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277977	Soil	5	0.01	614	<0.001	4	0.22	0.002	0.09	<0.1	11.57	1.5	0.7	0.12	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277978	Soil	5	0.01	670	<0.001	5	0.26	0.002	0.08	<0.1	6.77	1.5	0.5	0.09	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277979	Soil	14	0.09	311	0.005	1	0.64	0.003	0.05	0.3	0.14	1.3	0.8	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277980	Soil	22	0.14	785	0.006	3	1.36	0.002	0.05	0.2	2.51	7.0	0.5	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1277981	Soil	11	0.05	134	0.006	2	0.57	0.003	0.06	0.1	0.16	0.7	0.4	<0.05	4	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277982	Soil	10	0.03	262	0.005	2	0.31	0.003	0.21	0.2	0.13	1.0	0.4	0.36	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1277983	Soil	14	0.03	345	0.007	2	0.64	0.006	0.09	0.1	0.41	0.4	0.3	0.10	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277954	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277955	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277956	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277957	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277958	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277959	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277960	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277961	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277962	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277963	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277964	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277965	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277966	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277967	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277968	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277969	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277970	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277971	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277972	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277973	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277974	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277975	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277976	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277977	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277978	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277979	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277980	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277981	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277982	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277983	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277954	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277955	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277956	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277957	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277958	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277959	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277960	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277961	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277962	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277963	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277964	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277965	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277966	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277967	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277968	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277969	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277970	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277971	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277972	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277973	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277974	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277975	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277976	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277977	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277978	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277979	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277980	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277981	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277982	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277983	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277984	Soil		7.5	21.7	5.7	81	<0.1	25.5	6.1	61	2.09	18.7	0.6	2.0	5	0.1	3.0	0.2	59	<0.01	0.027	17
1277985	Soil		6.5	12.2	9.4	69	0.4	14.7	2.3	34	0.96	13.5	1.5	1.5	8	<0.1	2.1	0.1	56	0.01	0.026	20
1277986	Soil		11.7	140.7	27.3	450	3.9	158.5	23.9	746	6.81	59.0	6.1	4.2	26	2.9	9.3	0.4	48	0.13	0.083	16
1277987	Soil		14.3	63.3	15.0	429	1.6	114.2	18.1	218	4.00	19.9	4.9	2.8	33	1.3	4.2	0.2	37	0.41	0.141	13
1277988	Soil		9.3	44.9	15.3	228	0.9	60.1	12.8	387	3.32	25.2	3.3	2.9	25	0.6	3.7	0.2	34	0.36	0.087	11
1277989	Soil		12.0	59.7	12.2	1247	1.4	150.2	12.6	449	2.93	34.8	3.9	2.5	42	17.4	5.4	0.2	41	0.64	0.095	12
1277990	Soil		64.8	86.3	14.8	1481	1.8	256.6	9.5	202	3.18	62.1	4.7	2.1	52	12.7	17.7	0.2	220	0.70	0.127	15
1277991	Soil		22.1	50.1	19.5	896	1.0	146.4	7.4	103	2.31	50.1	8.9	1.7	47	5.6	11.6	0.2	91	0.45	0.068	13
1277992	Soil		9.9	36.1	9.7	178	0.7	43.2	6.2	335	1.25	18.8	2.0	1.5	62	9.9	3.9	0.1	50	1.32	0.071	8
1277993	Soil		48.2	54.9	11.5	1080	2.4	186.9	10.0	275	2.61	48.9	4.6	1.9	50	25.6	13.0	0.1	107	0.74	0.108	16
1277994	Soil		48.7	89.1	14.5	1235	2.7	137.8	4.9	84	1.70	69.2	5.4	1.0	114	23.5	19.5	0.2	701	0.93	0.304	20
1277995	Soil		22.4	46.9	16.3	324	1.1	76.5	7.5	128	2.51	55.4	2.7	0.6	27	4.5	8.7	0.2	161	0.34	0.114	12
1277996	Soil		16.1	25.6	10.9	150	0.5	37.6	4.0	55	1.46	27.3	1.4	0.2	13	1.2	4.3	0.2	82	0.07	0.083	13
1277997	Soil		30.0	26.4	26.7	114	2.3	24.6	3.7	93	2.14	63.1	8.6	0.8	34	1.1	10.7	0.2	113	0.04	0.124	12
1277998	Soil		59.0	52.0	192.8	137	5.5	27.4	2.3	98	3.48	429.7	28.6	3.0	216	8.7	25.6	0.4	252	0.16	0.962	22
1277999	Soil		11.9	43.1	28.0	3165	2.0	533.0	7.3	287	1.80	45.2	12.6	0.7	77	115.1	23.9	0.2	189	0.84	0.156	7
1278000	Soil		26.8	42.6	26.5	958	1.2	131.5	8.9	283	2.48	74.8	10.3	1.9	57	8.7	19.1	0.3	176	0.27	0.153	13
1278181	Soil		12.7	16.9	22.6	139	0.2	42.9	5.1	91	2.22	31.8	0.8	0.5	21	0.4	4.8	0.2	82	0.06	0.095	15
1278182	Soil		18.3	17.9	15.4	136	0.2	42.3	4.6	76	1.65	25.0	1.1	0.1	16	0.6	6.3	0.2	106	0.02	0.060	9
1278183	Soil		30.1	33.2	27.9	732	1.2	119.3	5.5	103	2.12	28.5	2.3	0.6	82	4.6	9.2	0.2	125	0.38	0.076	9
1278184	Soil		12.8	46.3	25.5	286	0.6	72.6	8.4	168	2.33	30.6	3.2	1.1	56	3.0	6.8	0.2	77	0.77	0.122	11
1278185	Soil		38.3	55.4	25.8	358	0.5	107.4	10.0	216	3.03	42.3	4.0	1.5	55	2.4	20.2	0.2	98	0.26	0.139	14
1278186	Soil		17.3	18.8	11.6	196	0.5	38.4	4.8	39	1.46	21.2	1.0	0.2	8	0.4	11.9	0.1	77	0.01	0.070	6
1278187	Soil		8.8	18.2	14.2	122	0.2	31.9	5.0	40	1.47	19.2	0.8	0.2	11	0.2	9.2	0.2	61	0.01	0.042	11
1278188	Soil		10.8	26.0	25.7	203	0.4	47.8	6.8	128	2.80	43.9	3.6	0.4	31	0.5	15.4	0.2	77	0.09	0.168	10
1278189	Soil		2.9	44.4	11.3	168	1.0	41.5	6.4	102	3.10	22.5	5.4	1.3	72	2.5	2.5	0.2	53	1.68	0.123	7
1278190	Soil		2.4	72.1	18.8	301	0.9	84.7	13.5	257	1.71	6.9	5.5	3.2	80	8.2	3.0	0.3	56	1.44	0.097	10
1278191	Soil		6.2	23.7	15.7	138	0.3	31.1	7.0	194	2.47	20.7	2.4	1.5	19	0.7	2.2	0.2	77	0.10	0.075	11
1278192	Soil		3.9	16.9	14.7	92	0.4	20.1	5.9	110	2.99	18.7	1.3	1.6	12	0.3	1.4	0.2	60	0.04	0.054	6
1278193	Soil		4.1	14.1	14.2	61	0.3	13.9	4.2	84	2.14	18.7	0.8	0.6	10	0.2	1.1	0.3	68	0.03	0.049	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1277984	Soil	8	0.03	123	0.008	2	0.49	0.004	0.05	0.1	0.01	1.2	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277985	Soil	7	0.02	159	0.006	2	0.36	0.002	0.05	0.1	0.02	0.7	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277986	Soil	18	0.05	2714	0.002	3	0.68	0.003	0.10	<0.1	0.94	8.5	0.4	0.10	<1	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277987	Soil	12	0.06	1277	0.003	5	0.47	0.006	0.08	<0.1	0.37	3.9	0.3	<0.05	1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277988	Soil	10	0.07	1264	0.003	3	0.49	0.005	0.06	<0.1	0.45	3.1	0.2	<0.05	1	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1277989	Soil	12	0.07	351	0.003	5	0.49	0.005	0.07	0.1	0.74	4.0	0.9	<0.05	1	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277990	Soil	23	0.07	761	0.003	5	0.57	0.003	0.07	0.4	1.45	4.3	1.4	<0.05	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277991	Soil	15	0.10	871	0.003	4	0.70	0.007	0.08	0.3	0.98	2.9	0.8	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277992	Soil	11	0.22	1828	0.003	4	0.61	0.009	0.05	0.1	0.32	2.6	0.6	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1277993	Soil	25	0.16	1044	0.003	5	0.83	0.004	0.08	0.3	0.63	6.0	1.6	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277994	Soil	39	0.15	884	0.005	9	0.85	0.007	0.16	0.3	0.90	2.5	2.6	<0.05	3	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1277995	Soil	14	0.07	783	0.003	4	0.39	0.004	0.07	0.2	0.32	1.1	0.5	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277996	Soil	12	0.04	341	0.003	3	0.56	0.003	0.06	0.1	0.15	0.3	0.4	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1277997	Soil	18	0.09	387	0.004	4	0.75	0.003	0.09	0.4	0.94	0.9	1.2	0.07	3	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1277998	Soil	66	0.04	2155	0.004	3	1.01	0.004	0.11	1.2	5.75	6.3	4.3	0.21	7	11.6	0.5	N.A.	N.A.	N.A.	N.A.
1277999	Soil	23	0.11	1513	0.004	5	0.96	0.006	0.09	0.2	2.09	2.0	1.0	0.12	2	6.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278000	Soil	23	0.11	1830	0.003	5	0.83	0.004	0.11	0.3	1.00	2.4	1.0	0.09	2	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278181	Soil	17	0.08	137	0.007	2	0.61	0.003	0.05	0.2	0.04	0.7	0.3	<0.05	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278182	Soil	15	0.05	146	0.004	1	0.59	0.005	0.04	0.1	0.04	0.4	0.3	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278183	Soil	21	0.10	398	0.004	1	0.75	0.006	0.06	0.2	0.17	1.2	0.8	<0.05	3	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278184	Soil	19	0.19	901	0.009	2	0.95	0.010	0.07	0.2	0.17	1.5	0.4	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278185	Soil	19	0.14	524	0.010	2	0.71	0.004	0.07	0.2	0.14	2.1	0.5	<0.05	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278186	Soil	9	0.02	105	0.002	1	0.39	0.005	0.05	<0.1	0.03	0.3	0.1	<0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278187	Soil	9	0.02	109	0.005	1	0.40	0.003	0.04	0.1	0.01	0.3	0.1	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278188	Soil	19	0.09	134	0.007	1	0.81	0.004	0.06	0.1	0.06	0.7	0.2	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278189	Soil	23	0.19	1930	0.003	4	1.26	0.008	0.06	<0.1	0.59	2.5	0.2	0.14	3	9.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278190	Soil	25	0.26	1751	0.002	7	1.06	0.006	0.09	<0.1	0.47	3.6	0.3	0.19	3	36.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278191	Soil	20	0.19	517	0.005	1	1.21	0.003	0.05	0.2	0.09	1.5	0.3	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278192	Soil	17	0.13	219	0.002	2	1.22	0.004	0.05	0.1	0.04	1.7	0.2	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278193	Soil	15	0.09	247	0.004	<1	1.02	0.004	0.04	0.1	0.05	1.0	0.2	<0.05	5	1.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1277984	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277985	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277986	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277987	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277988	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277989	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277990	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277991	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277992	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277993	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277994	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277995	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277996	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277997	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277998	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277999	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278000	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278181	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278182	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278183	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278184	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278185	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278186	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278187	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278188	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278189	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278190	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278191	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278192	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278193	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277984	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277985	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277986	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277987	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277988	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277989	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277990	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277991	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277992	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277993	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277994	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277995	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277996	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277997	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277998	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277999	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278000	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278181	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278182	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278183	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278184	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278185	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278186	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278187	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278188	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278189	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278190	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278191	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278192	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278193	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278194	Soil	6.3	25.5	16.3	109	0.3	21.6	5.1	196	2.36	21.7	1.6	0.8	12	0.4	1.9	0.3	75	0.02	0.087	9
1278195	Soil	4.9	33.8	10.2	125	1.1	32.6	4.7	116	1.69	12.4	3.4	0.9	90	0.7	1.9	0.1	58	0.92	0.071	6
1278196	Soil	11.0	46.6	20.6	249	0.5	55.9	11.3	274	3.38	33.0	5.5	2.2	49	1.5	5.0	0.3	79	0.39	0.109	10
1278197	Soil	10.7	49.6	16.5	252	0.7	62.6	8.7	176	2.99	29.5	5.4	2.7	44	1.4	4.4	0.2	79	0.33	0.119	12
1278198	Soil	7.7	31.1	15.5	165	0.4	35.7	6.6	161	2.50	21.5	6.7	1.3	37	1.2	2.4	0.2	83	0.42	0.084	10
1278199	Soil	2.7	32.2	13.9	113	0.9	31.7	8.8	479	2.47	12.5	2.6	0.9	62	1.0	1.3	0.2	56	1.45	0.077	9
1278200	Soil	6.6	25.5	12.9	150	0.5	31.7	5.9	135	2.11	19.5	2.2	1.2	53	0.8	2.9	0.2	68	0.83	0.068	7
1278201	Soil	6.3	41.4	15.0	198	0.9	47.1	11.1	237	2.80	19.7	6.3	2.3	51	1.3	2.8	0.3	50	0.64	0.074	10
1278202	Soil	7.0	28.5	11.2	166	0.8	37.3	7.1	252	2.11	17.5	5.3	1.7	52	0.9	2.9	0.2	62	0.57	0.062	9
1278203	Soil	5.1	16.9	12.7	89	0.3	18.6	4.2	105	1.97	18.7	3.8	1.2	17	0.4	2.2	0.2	68	0.13	0.035	11
1278204	Soil	3.3	15.8	17.0	111	1.0	25.8	5.0	338	4.02	20.6	5.6	2.6	10	0.3	1.6	0.2	39	0.04	0.103	9
1278205	Soil	4.0	28.9	11.8	130	1.4	29.2	5.9	101	2.64	20.5	1.6	2.0	9	0.2	1.4	0.2	38	0.02	0.054	10
1278206	Soil	6.5	39.2	14.7	146	1.1	41.7	7.8	242	2.18	18.9	5.6	1.4	167	1.3	2.9	0.3	67	1.30	0.089	7
1278207	Soil	5.8	46.9	12.9	206	0.9	40.5	8.3	237	2.11	19.3	7.7	1.6	89	2.8	3.4	0.2	64	0.72	0.125	8
1278208	Soil	7.7	46.8	16.0	233	0.4	46.7	9.4	239	2.66	26.7	7.7	2.6	44	1.3	5.1	0.2	75	0.16	0.109	10
1278209	Soil	9.4	47.2	18.0	225	0.5	43.7	8.0	210	2.71	25.6	5.4	1.9	56	1.2	4.8	0.2	101	0.28	0.098	10
1278210	Soil	8.2	69.6	16.7	262	0.8	47.1	9.8	361	2.61	19.0	8.3	2.4	75	1.8	5.0	0.3	86	0.33	0.134	12
1278211	Soil	9.7	65.3	18.6	232	1.2	45.3	8.9	209	2.71	28.0	5.2	2.5	53	1.4	6.4	0.3	103	0.14	0.101	11
1278212	Soil	11.8	73.7	20.4	253	1.6	55.0	7.3	159	2.58	34.8	10.4	2.1	106	2.4	6.7	0.3	98	0.43	0.135	9
1278213	Soil	10.5	83.7	21.8	142	1.4	26.6	3.9	132	2.37	29.9	3.1	1.1	40	2.2	3.9	0.3	120	0.07	0.132	10
1278214	Soil	9.2	70.7	17.4	787	1.5	129.7	11.8	550	2.82	48.1	9.4	1.7	94	9.7	8.0	0.3	87	0.57	0.172	8
1278215	Soil	88.9	101.5	24.0	1147	2.0	329.8	50.3	2566	5.59	204.5	10.4	2.1	67	10.6	33.3	0.3	106	0.53	0.144	8
1278216	Soil	68.2	81.9	22.3	1046	1.7	272.4	29.0	1468	3.46	278.0	13.3	1.9	71	10.1	27.6	0.2	90	0.83	0.127	7
1278217	Soil	185.4	84.9	18.3	979	1.5	202.6	53.4	1628	11.42	4468	10.7	1.7	64	28.3	111.8	0.2	86	0.57	0.213	6
1278218	Soil	30.9	54.1	30.8	445	2.3	86.0	12.7	528	2.49	89.2	6.8	3.4	73	3.7	18.5	0.2	110	0.38	0.135	12
1278219	Soil	50.9	112.1	31.9	424	1.5	128.2	9.2	266	2.74	66.4	6.9	2.6	77	5.7	17.2	0.2	125	0.45	0.152	11
1278220	Soil	5.7	8.5	9.2	28	1.2	7.0	0.9	18	0.35	8.7	<0.5	<0.1	9	0.2	1.8	<0.1	30	0.02	0.023	4
1278221	Soil	23.8	37.5	21.6	86	1.5	53.3	2.4	37	0.89	20.7	3.0	0.6	29	2.9	5.7	0.2	61	0.27	0.041	8
1278222	Soil	13.8	39.8	36.0	68	2.9	18.2	1.9	29	1.07	31.7	2.0	0.2	26	0.7	5.0	0.4	106	0.06	0.078	13
1278223	Soil	22.2	20.8	32.0	57	5.1	13.0	1.7	31	2.04	52.8	1.3	0.6	103	0.3	6.0	0.4	113	0.02	0.116	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1278194	Soil		15	0.08	326	0.004	2	0.75	0.003	0.05	0.1	0.04	1.0	0.2	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278195	Soil		16	0.13	2549	0.004	2	1.15	0.015	0.06	0.1	0.25	1.8	0.2	0.08	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278196	Soil		21	0.17	2244	0.004	2	0.94	0.004	0.06	0.1	0.15	2.1	0.3	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278197	Soil		21	0.17	3313	0.002	3	0.90	0.004	0.07	0.2	0.32	2.6	0.3	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278198	Soil		19	0.13	2653	0.002	1	1.03	0.004	0.06	0.2	0.10	1.5	0.2	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278199	Soil		24	0.25	4045	0.010	2	1.22	0.005	0.04	0.2	0.21	2.1	<0.1	<0.05	4	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278200	Soil		17	0.14	1233	0.002	2	0.90	0.008	0.05	0.2	0.14	1.3	0.2	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278201	Soil		23	0.25	1655	0.003	3	0.89	0.004	0.06	<0.1	0.22	3.2	0.2	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278202	Soil		20	0.18	2197	0.004	2	0.89	0.005	0.06	0.1	0.22	2.1	0.2	0.06	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278203	Soil		16	0.10	386	0.007	1	0.77	0.003	0.05	0.1	0.04	0.9	0.2	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278204	Soil		35	0.05	214	0.003	<1	1.22	0.002	0.03	0.5	0.13	1.4	0.1	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278205	Soil		16	0.08	1155	0.004	3	0.77	0.006	0.04	0.1	0.10	1.8	0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278206	Soil		24	0.21	2311	0.003	4	0.94	0.008	0.06	0.2	0.47	2.3	0.2	0.11	2	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278207	Soil		22	0.20	2144	0.003	3	0.93	0.005	0.07	0.1	0.63	2.3	0.2	0.08	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278208	Soil		24	0.19	1672	0.003	3	0.84	0.003	0.07	0.1	0.25	1.9	0.3	0.05	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278209	Soil		21	0.14	1301	0.003	2	0.89	0.004	0.09	0.2	0.20	1.8	0.4	<0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278210	Soil		24	0.19	1728	0.004	3	0.83	0.005	0.08	0.1	0.31	3.0	0.3	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278211	Soil		26	0.18	2377	0.003	3	1.08	0.003	0.07	0.1	0.53	3.1	0.3	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278212	Soil		28	0.16	2110	0.004	4	0.83	0.006	0.08	0.2	1.09	3.8	0.5	0.08	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278213	Soil		26	0.07	626	0.005	3	0.87	0.004	0.08	0.2	0.30	1.8	0.5	<0.05	4	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278214	Soil		25	0.15	1670	0.002	6	0.71	0.005	0.08	<0.1	1.93	3.6	0.5	0.09	2	6.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278215	Soil		24	0.13	1616	0.003	5	0.88	0.005	0.08	0.2	1.53	3.6	1.5	0.05	3	9.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278216	Soil		22	0.11	1366	0.003	5	0.78	0.008	0.07	0.2	1.39	3.3	1.3	<0.05	2	6.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278217	Soil		18	0.09	1301	0.003	4	0.68	0.007	0.05	0.2	1.15	2.7	1.4	<0.05	2	13.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278218	Soil		23	0.14	1942	0.004	4	0.66	0.004	0.09	0.3	0.99	3.1	0.9	0.06	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278219	Soil		22	0.13	1859	0.005	5	0.76	0.005	0.10	0.2	1.13	2.9	1.0	0.06	2	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278220	Soil		6	0.01	91	0.005	1	0.19	0.016	0.03	<0.1	0.05	0.3	0.2	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278221	Soil		20	0.02	574	0.008	4	0.48	0.006	0.04	0.1	0.24	1.3	0.4	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278222	Soil		27	0.03	362	0.004	3	0.92	0.007	0.07	0.2	0.28	0.3	0.7	<0.05	5	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278223	Soil		19	0.02	552	0.011	3	0.56	0.005	0.17	0.3	0.13	0.8	1.5	0.35	4	3.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1278194	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278195	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278196	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278197	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278198	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278199	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278200	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278201	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278202	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278203	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278204	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278205	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278206	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278207	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278208	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278209	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278210	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278211	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278212	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278213	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278214	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278215	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278216	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278217	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278218	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278219	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278220	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278221	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278222	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278223	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278194	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278195	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278196	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278197	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278198	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278199	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278200	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278201	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278202	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278203	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278204	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278205	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278206	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278207	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278208	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278209	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278210	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278211	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278212	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278213	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278214	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278215	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278216	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278217	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278218	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278219	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278220	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278221	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278222	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278223	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278224	Soil		16.5	25.2	14.3	169	0.7	37.5	3.8	66	1.94	33.4	2.7	2.0	20	0.4	5.9	0.2	127	0.05	0.077	15
1278225	Soil		18.0	16.1	19.6	103	2.9	19.2	2.2	43	2.19	57.3	1.8	2.3	51	0.7	8.6	0.3	170	0.02	0.135	13
1278226	Soil		18.0	60.8	11.9	487	1.1	103.1	5.2	127	1.86	42.9	5.8	1.3	42	5.8	8.4	0.2	127	0.37	0.100	11
1278227	Soil		19.0	64.5	16.4	412	1.0	75.5	9.6	204	2.54	56.5	7.6	2.9	41	4.2	9.9	0.2	162	0.23	0.144	19
1278228	Soil		19.9	37.0	10.3	>10000	1.1	2043	13.9	3424	1.52	94.3	2.7	0.3	69	39.9	29.7	0.1	273	3.75	0.224	4
1278229	Soil		40.4	66.7	17.6	1296	1.4	193.6	16.5	1294	2.61	43.0	5.3	1.8	42	13.3	10.9	0.2	157	0.62	0.113	13
1278230	Soil		12.2	41.4	18.4	255	0.3	44.2	4.1	74	1.46	21.7	2.4	1.0	49	1.1	5.8	0.2	70	0.11	0.070	12
1278231	Soil		14.2	41.5	18.3	301	0.3	66.5	10.7	172	3.15	69.3	0.8	0.5	21	0.7	5.8	0.3	61	0.12	0.081	23
1278232	Soil		21.6	63.5	34.9	232	1.4	73.6	10.0	234	3.21	48.7	6.8	1.4	75	1.1	9.4	0.3	60	0.24	0.202	17
1278233	Soil		13.2	47.0	12.3	162	1.5	32.5	3.1	36	1.36	18.6	0.9	0.2	10	0.2	4.4	0.2	85	0.02	0.043	13
1278234	Soil		10.0	12.2	4.7	67	0.1	22.0	1.7	28	0.51	7.3	2.1	0.2	25	0.9	1.1	0.1	33	0.47	0.035	6
1278235	Soil		28.3	41.3	13.9	349	0.6	80.8	6.6	103	1.98	48.0	5.0	1.9	37	1.6	8.6	0.3	128	0.59	0.060	12
1278236	Soil		5.2	19.2	18.1	30	3.7	6.1	0.7	14	0.55	5.6	1.8	<0.1	50	0.3	2.3	0.2	100	0.04	0.054	7
1278237	Soil		5.0	28.7	15.4	205	0.5	44.2	6.0	121	3.16	19.5	2.3	0.8	9	0.3	2.1	0.3	66	0.02	0.053	9
1278238	Soil		2.8	17.5	7.1	53	1.6	11.8	2.2	36	1.00	6.3	1.0	0.2	6	0.2	1.0	0.2	48	0.01	0.030	9
1278239	Soil		4.4	25.3	14.4	86	0.7	17.2	3.1	107	1.74	12.6	2.4	0.2	18	0.7	1.3	0.3	68	0.09	0.096	9
1278240	Soil		0.1	3.5	1.6	19	<0.1	1.6	0.7	47	0.16	<0.5	0.6	<0.1	25	0.2	<0.1	<0.1	5	0.68	0.029	1
1278241	Soil		5.0	24.9	14.7	138	0.3	24.8	5.8	222	2.69	16.2	3.0	1.9	14	0.9	2.1	0.3	77	0.06	0.047	11
1278242	Soil		5.5	50.3	20.5	184	0.4	40.8	7.7	164	2.64	19.3	6.5	2.3	28	0.7	3.9	0.3	64	0.15	0.053	9
1278243	Soil		5.7	54.7	18.2	202	0.6	52.1	9.6	249	3.02	21.4	6.5	2.1	36	0.7	3.0	0.3	56	0.17	0.101	9
1278244	Soil		4.2	17.1	10.5	77	0.4	16.1	3.1	105	1.74	12.2	1.2	0.5	9	0.2	1.5	0.2	55	0.03	0.065	8
1278245	Soil		3.4	13.3	9.1	61	0.1	11.5	2.5	54	1.29	8.7	0.8	0.4	7	0.2	1.3	0.2	63	0.02	0.036	10
1278246	Soil		2.0	17.4	5.7	53	0.5	10.1	2.2	43	1.03	3.9	0.9	0.1	5	0.2	0.8	0.1	31	0.02	0.046	7
1278247	Soil		3.7	20.3	12.0	119	0.5	20.1	4.4	86	1.85	11.5	0.8	0.7	23	0.6	2.1	0.2	42	0.02	0.063	9
1278248	Soil		5.8	32.5	18.0	198	0.6	29.9	7.0	285	3.13	18.3	3.9	1.5	17	1.9	2.2	0.3	75	0.07	0.061	11
1278249	Soil		3.4	29.5	15.0	153	0.5	28.9	8.6	245	2.58	8.9	3.0	1.5	19	1.5	1.8	0.3	27	0.14	0.065	14
1278250	Soil		5.9	62.4	15.5	182	0.9	61.6	11.9	354	4.14	14.5	7.0	2.5	35	0.7	2.4	0.3	32	0.26	0.053	10
1278251	Soil		4.7	44.0	14.4	142	0.5	26.6	7.4	202	2.27	13.5	3.2	1.2	56	1.5	1.7	0.3	61	0.51	0.056	8
1278252	Soil		3.3	9.9	9.4	50	0.2	8.9	2.1	66	0.98	9.3	1.5	0.1	8	0.2	1.0	0.2	59	0.03	0.033	11
1278253	Soil		4.7	20.9	14.0	132	<0.1	25.4	4.4	93	2.36	15.2	1.6	1.3	14	0.7	2.1	0.2	74	0.06	0.039	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1278224	Soil	17	0.06	323	0.004	2	0.90	0.004	0.07	0.2	0.15	1.4	0.6	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278225	Soil	21	0.06	387	0.005	3	0.88	0.004	0.11	0.3	0.26	1.4	1.9	0.06	4	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278226	Soil	18	0.08	783	0.003	4	0.74	0.010	0.09	0.1	0.56	2.6	0.6	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278227	Soil	23	0.09	908	0.002	4	0.77	0.003	0.10	0.1	0.63	2.9	0.6	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278228	Soil	19	0.13	271	0.005	8	0.66	0.007	0.07	0.1	0.45	0.7	0.8	0.79	2	42.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278229	Soil	18	0.06	2045	0.003	5	0.52	0.004	0.07	0.2	1.00	3.6	1.0	<0.05	1	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278230	Soil	13	0.04	1060	0.003	3	0.42	0.004	0.11	0.1	0.09	1.3	0.4	0.08	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278231	Soil	12	0.06	445	0.005	3	0.64	0.006	0.08	0.1	0.07	1.3	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278232	Soil	12	0.05	525	0.004	6	0.54	0.003	0.17	<0.1	0.74	2.2	0.5	0.16	1	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278233	Soil	8	0.03	88	0.008	2	0.36	0.005	0.06	0.1	0.02	0.5	0.3	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278234	Soil	7	0.09	297	0.003	2	0.51	0.017	0.04	0.1	0.09	0.4	0.4	0.09	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278235	Soil	14	0.10	604	0.002	3	0.53	0.004	0.07	0.2	0.53	1.7	0.5	0.08	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278236	Soil	9	0.01	277	0.003	2	0.35	0.008	0.06	0.2	0.06	<0.1	0.6	0.11	4	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278237	Soil	14	0.05	127	0.008	2	0.56	0.003	0.04	0.2	0.07	1.0	0.2	<0.05	4	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278238	Soil	9	0.02	170	0.007	1	0.44	0.009	0.03	0.1	0.06	0.3	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278239	Soil	19	0.08	763	0.003	2	0.92	0.005	0.05	0.1	0.14	0.3	0.2	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278240	Soil	2	0.02	189	0.005	<1	0.25	0.036	0.02	<0.1	0.03	0.1	<0.1	0.07	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278241	Soil	22	0.18	790	0.004	2	1.10	0.003	0.07	0.1	0.08	1.4	0.2	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278242	Soil	25	0.20	2843	0.001	2	1.01	0.003	0.06	0.1	0.20	2.0	0.3	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278243	Soil	25	0.23	1520	0.001	2	0.95	0.003	0.07	0.1	0.16	2.0	0.2	0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278244	Soil	14	0.10	229	0.004	2	0.69	0.007	0.05	0.1	0.03	0.6	0.2	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278245	Soil	10	0.04	207	0.008	1	0.57	0.008	0.04	0.1	0.02	0.5	0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278246	Soil	8	0.03	172	0.006	2	0.36	0.014	0.04	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278247	Soil	14	0.09	372	0.004	1	0.61	0.009	0.06	<0.1	0.03	0.8	0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278248	Soil	24	0.18	2022	0.004	2	1.17	0.005	0.07	0.1	0.07	1.6	0.2	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278249	Soil	17	0.11	1297	0.002	2	0.71	0.003	0.07	<0.1	0.05	1.7	0.1	<0.05	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278250	Soil	23	0.19	2957	0.001	2	0.91	0.003	0.06	<0.1	0.29	5.0	0.2	0.07	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278251	Soil	21	0.13	1630	0.003	2	0.93	0.006	0.07	0.1	0.09	1.8	0.2	0.06	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278252	Soil	10	0.05	180	0.005	1	0.57	0.004	0.03	0.1	0.02	0.2	0.2	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278253	Soil	22	0.17	582	0.001	2	1.06	0.004	0.05	0.1	0.04	1.2	0.2	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1278224	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278225	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278226	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278227	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278228	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278229	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278230	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278231	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278232	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278233	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278234	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278235	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278236	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278237	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278238	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278239	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278240	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278241	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278242	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278243	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278244	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278245	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278246	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278247	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278248	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278249	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278250	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278251	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278252	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278253	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278224	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278225	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278226	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278227	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278228	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278229	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278230	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278231	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278232	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278233	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278234	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278235	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278236	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278237	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278238	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278239	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278240	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278241	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278242	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278243	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278244	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278245	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278246	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278247	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278248	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278249	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278250	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278254	Soil		3.0	21.1	13.2	254	0.7	33.4	8.7	185	2.86	13.5	2.6	1.5	37	1.2	1.4	0.2	80	0.51	0.062	20
1278255	Soil		3.6	26.2	14.3	119	0.6	24.6	8.2	171	2.43	9.9	1.4	1.4	52	0.7	1.0	0.2	66	0.84	0.060	8
1278256	Soil		3.1	59.6	22.3	139	0.2	50.5	11.4	241	3.93	21.2	6.3	2.9	32	0.3	1.8	0.4	46	0.05	0.034	7
1278257	Soil		4.4	27.3	11.0	80	0.4	15.2	2.8	48	1.26	12.7	1.5	0.4	15	0.5	1.4	0.3	56	0.09	0.028	10
1278258	Soil		5.4	172.5	24.7	271	1.7	87.8	12.9	303	2.96	15.3	11.9	1.8	116	0.5	2.3	0.3	70	0.60	0.103	9
1278259	Soil		6.1	100.8	15.2	201	1.6	75.7	11.6	276	2.64	16.6	7.7	1.9	129	1.4	2.6	0.3	81	0.80	0.109	12
1278260	Soil		8.9	17.9	15.9	128	0.2	24.2	4.6	139	2.08	24.5	1.5	1.8	22	0.6	3.0	0.3	98	0.06	0.029	13
1278261	Soil		8.5	38.8	22.2	238	0.3	43.3	7.5	276	2.90	27.8	4.7	1.1	27	1.4	4.6	0.3	108	0.10	0.150	9
1278262	Soil		15.8	38.7	27.8	262	0.6	54.2	7.8	149	3.39	35.9	6.5	2.8	40	0.7	5.5	0.4	144	0.05	0.083	11
1278263	Soil		24.4	11.7	24.9	21	1.8	11.9	0.4	13	0.58	15.4	<0.5	0.9	9	0.1	8.7	0.2	82	0.02	0.027	16
1278264	Soil		2.0	13.6	18.1	30	0.5	5.8	1.4	43	0.70	10.8	2.7	0.3	22	<0.1	1.3	0.2	17	0.06	0.045	4
1278265	Soil		77.0	65.4	35.2	678	0.5	238.9	8.7	292	2.29	87.8	3.5	2.2	100	3.8	10.7	0.1	99	3.60	0.073	13
1278266	Soil		20.9	97.5	84.8	471	2.5	168.6	23.7	259	6.26	157.3	7.1	1.4	27	2.8	23.5	0.3	50	0.08	0.236	5
1278267	Soil		97.0	113.5	18.6	1462	1.6	230.2	8.9	263	2.36	76.6	3.6	1.2	75	15.5	24.2	0.2	823	1.73	0.109	24
1278268	Soil		71.9	77.4	12.2	805	0.4	243.6	11.2	1111	2.57	36.8	0.8	1.4	228	5.7	4.4	0.1	165	5.96	0.091	11
1278269	Soil		49.5	40.0	17.6	420	0.3	92.7	8.2	195	2.72	56.7	3.9	0.6	15	2.7	10.8	0.2	384	0.10	0.119	17
1278270	Soil		19.8	41.2	11.2	2274	0.7	326.6	4.8	84	1.75	25.0	7.6	0.7	74	5.9	4.8	0.2	118	2.27	0.119	8
1278271	Soil		37.0	44.6	12.5	453	1.4	114.6	7.6	128	2.41	56.2	7.5	0.8	39	2.6	9.3	0.1	288	0.49	0.154	14
1278272	Soil		23.2	38.1	12.5	1297	1.0	112.4	6.8	165	1.92	34.8	4.7	0.6	45	9.0	5.5	0.2	209	0.52	0.116	12
1278273	Soil		140.1	209.9	22.4	3289	2.2	410.9	13.6	234	2.39	122.9	2.1	1.1	176	24.4	49.2	0.2	1108	5.19	0.171	22
1278274	Soil		62.1	99.0	14.7	850	1.0	203.9	10.3	446	1.98	51.4	1.2	1.0	174	7.3	23.3	0.1	341	6.09	0.125	12
1278275	Soil		36.2	33.5	7.6	354	0.4	99.5	5.4	217	1.35	32.0	0.7	0.6	31	4.3	6.0	<0.1	167	0.75	0.070	10
1278276	Soil		28.8	32.1	12.7	248	0.3	73.4	5.5	71	1.57	33.6	<0.5	0.3	32	1.5	5.0	0.1	153	0.44	0.087	10
1278277	Soil		59.7	56.5	11.6	280	0.3	150.6	9.2	232	2.06	30.7	0.9	1.5	55	3.0	3.8	0.1	78	2.05	0.118	15
1278278	Soil		13.9	14.1	6.0	89	0.1	29.9	1.9	36	0.66	9.9	<0.5	0.3	22	0.7	1.5	<0.1	84	0.37	0.059	6
1278279	Soil		69.6	68.1	11.4	347	0.3	163.6	8.8	141	1.87	26.8	<0.5	2.0	30	2.6	3.6	0.1	57	0.32	0.132	17
1278280	Soil		5.6	5.5	3.1	25	0.3	10.2	0.7	11	0.26	2.3	<0.5	<0.1	12	0.3	0.4	<0.1	25	0.15	0.040	3
1278281	Soil		21.0	15.6	8.0	139	<0.1	44.2	3.2	44	1.09	12.1	<0.5	0.2	11	1.1	1.7	0.1	62	0.08	0.095	12
1278282	Soil		34.0	16.5	7.2	132	<0.1	52.9	3.6	85	1.03	14.4	0.7	0.3	8	0.6	2.8	0.1	99	0.07	0.055	9
1278283	Soil		38.3	27.0	13.5	185	0.1	70.4	7.2	58	1.96	64.0	<0.5	0.7	5	0.2	4.5	0.1	113	0.02	0.070	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1278254	Soil		35	0.15	1039	0.005	2	1.44	0.007	0.04	0.2	0.11	3.8	0.2	<0.05	3	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278255	Soil		26	0.15	1548	0.004	2	1.26	0.006	0.06	0.1	0.07	2.0	0.2	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278256	Soil		42	0.50	710	0.001	2	1.76	0.006	0.06	<0.1	0.13	2.8	0.1	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278257	Soil		12	0.03	334	0.004	1	0.47	0.003	0.04	0.1	0.02	0.6	0.2	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278258	Soil		39	0.31	4665	0.003	5	1.60	0.013	0.10	0.1	0.49	5.5	0.4	0.13	4	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278259	Soil		31	0.31	1253	0.005	4	1.32	0.008	0.09	0.1	0.60	3.9	0.3	0.08	4	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278260	Soil		17	0.12	291	0.012	2	0.61	0.004	0.07	0.2	0.03	1.1	0.3	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278261	Soil		24	0.12	922	0.002	2	0.84	0.003	0.07	0.2	0.16	1.4	0.4	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278262	Soil		28	0.13	528	0.004	2	1.36	0.004	0.08	0.2	0.25	2.1	0.6	<0.05	4	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278263	Soil		9	0.01	275	0.001	3	0.19	0.003	0.07	0.3	0.62	0.4	0.7	0.13	1	5.8	0.2	N.A.	N.A.	N.A.	N.A.
1278264	Soil		6	0.03	124	0.004	2	0.59	0.016	0.07	<0.1	0.17	0.3	0.2	0.09	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278265	Soil		17	1.92	193	0.001	4	0.29	0.005	0.06	0.4	1.46	3.6	1.5	0.09	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278266	Soil		15	0.06	184	0.002	2	0.80	0.003	0.08	0.2	4.34	2.6	1.2	0.14	1	6.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278267	Soil		54	0.84	733	0.005	6	0.78	0.004	0.14	0.4	0.57	4.3	4.0	0.09	3	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278268	Soil		20	2.97	310	0.002	4	0.33	0.007	0.07	0.3	0.50	3.1	1.9	<0.05	<1	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278269	Soil		32	0.14	421	0.007	3	0.81	0.003	0.11	0.3	0.64	0.8	1.1	0.09	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278270	Soil		19	0.17	447	0.005	7	0.56	0.007	0.06	0.2	0.76	1.7	2.0	0.14	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278271	Soil		32	0.10	456	0.006	4	0.98	0.007	0.06	0.2	1.93	2.0	1.0	0.05	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278272	Soil		26	0.14	921	0.004	4	0.88	0.007	0.06	0.2	0.99	1.3	2.0	0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278273	Soil		59	1.17	415	0.008	9	0.59	0.006	0.15	0.6	0.66	3.8	5.7	0.06	2	11.0	0.2	N.A.	N.A.	N.A.	N.A.
1278274	Soil		26	3.26	301	0.004	6	0.38	0.008	0.08	0.3	0.45	2.4	2.7	0.10	1	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278275	Soil		20	0.14	526	0.005	3	0.63	0.011	0.05	0.3	1.82	2.1	1.5	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278276	Soil		22	0.09	656	0.004	3	0.52	0.005	0.06	0.2	0.28	0.8	1.0	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278277	Soil		15	1.00	351	0.004	4	0.31	0.004	0.06	0.2	0.38	3.1	0.9	<0.05	<1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278278	Soil		11	0.07	251	0.003	4	0.37	0.011	0.04	0.1	0.07	0.7	0.5	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278279	Soil		13	0.06	497	0.004	2	0.35	0.004	0.06	0.3	0.29	3.2	1.1	<0.05	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278280	Soil		5	0.03	108	0.003	1	0.25	0.015	0.03	<0.1	0.04	0.4	0.6	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278281	Soil		14	0.10	184	0.003	3	0.46	0.004	0.05	0.1	0.06	0.4	0.6	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278282	Soil		13	0.07	295	0.003	2	0.52	0.005	0.04	0.1	0.04	0.9	1.0	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278283	Soil		20	0.04	103	0.001	4	0.62	0.003	0.05	0.2	0.03	0.9	0.6	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1278254	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278255	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278256	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278257	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278258	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278259	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278260	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278261	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278262	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278263	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278264	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278265	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278266	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278267	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278268	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278269	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278270	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278271	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278272	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278273	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278274	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278275	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278276	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278277	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278278	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278279	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278280	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278281	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278282	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278283	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278254	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278255	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278256	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278257	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278258	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278259	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278260	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278261	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278262	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278263	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278264	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278265	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278266	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278267	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278268	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278269	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278270	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278271	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278272	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278273	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278274	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278275	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278276	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278277	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278278	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278279	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278280	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278281	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278282	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278283	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278284	Soil		9.5	19.3	12.8	73	0.2	23.9	5.6	535	1.83	9.8	1.3	0.2	11	0.2	1.8	0.2	44	0.03	0.118	4
1278285	Soil		5.2	41.6	24.2	52	0.5	22.8	4.5	85	2.28	13.6	<0.5	0.1	28	<0.1	2.5	0.3	53	0.01	0.063	6
1278286	Soil		7.4	104.0	35.8	46	1.6	39.5	5.9	104	3.87	27.8	2.7	0.3	53	0.1	4.4	0.3	77	0.03	0.149	4
1278287	Soil		7.0	209.9	54.3	105	2.1	93.5	19.5	439	6.84	40.0	5.5	1.4	106	0.3	4.8	0.4	63	0.03	0.223	4
1278288	Soil		4.7	60.4	19.6	98	0.2	39.1	11.2	185	2.54	22.8	3.1	0.4	8	0.2	2.7	0.4	37	0.02	0.069	3
1278289	Soil		6.7	115.1	32.7	455	1.3	83.1	24.5	507	5.00	64.0	6.3	1.7	26	1.2	6.3	0.4	48	0.22	0.110	3
1278290	Soil		52.9	90.8	20.6	887	1.5	214.3	6.2	206	1.96	52.0	2.2	2.3	256	13.1	15.6	0.1	341	10.65	0.137	9
1278291	Soil		5.4	214.0	44.0	169	2.0	179.2	87.4	3003	12.23	54.9	18.8	3.2	33	0.6	5.9	0.7	31	0.45	0.092	17
1278292	Soil		6.6	67.9	23.3	98	0.4	66.3	22.5	779	5.80	27.3	3.6	1.8	4	0.1	5.7	0.4	24	0.03	0.082	24
1278293	Soil		12.2	57.0	18.9	312	0.8	68.5	8.3	277	2.68	41.2	1.2	0.4	47	3.4	7.3	0.2	202	0.23	0.274	10
1278294	Soil		5.1	16.9	8.0	70	0.1	17.4	4.2	297	1.26	7.7	0.6	0.2	8	0.1	1.2	0.1	33	0.03	0.085	4
1278295	Soil		14.7	86.2	38.7	276	1.3	67.6	6.7	215	3.39	44.4	2.1	0.2	31	1.4	6.7	0.3	84	0.06	0.198	5
1278296	Soil		21.9	55.8	42.6	94	1.6	34.9	2.6	59	1.41	26.1	9.5	<0.1	55	0.9	8.7	0.2	153	0.17	0.216	14
1278297	Soil		18.1	75.3	111.3	197	2.5	56.1	7.3	542	3.55	27.1	3.0	0.6	178	0.5	5.2	0.7	140	0.12	0.471	25
1278298	Soil		12.2	40.4	24.5	145	0.3	45.0	15.2	648	3.77	19.4	1.6	0.8	5	0.2	2.3	0.3	24	0.03	0.073	10
1278299	Soil		3.0	61.8	30.8	160	1.4	68.1	25.7	846	5.23	15.0	7.7	1.5	52	0.4	1.9	0.5	28	0.29	0.145	12
1278300	Soil		5.5	42.3	31.0	183	1.6	43.5	7.9	100	2.66	13.7	3.4	0.9	131	0.2	2.1	0.3	42	0.16	0.227	8
1278501	Soil		28.0	24.9	18.3	468	0.4	60.3	6.9	202	2.16	58.3	2.3	1.9	30	3.1	12.0	0.2	167	0.13	0.107	13
1278502	Soil		31.1	39.3	14.0	746	0.9	128.2	9.1	445	1.89	46.5	4.3	0.8	51	15.3	16.3	0.2	159	0.53	0.143	10
1278503	Soil		22.7	30.2	10.0	1424	0.4	216.1	4.3	113	1.35	36.7	2.3	0.7	53	16.3	13.9	0.1	118	1.08	0.079	8
1278504	Soil		17.9	108.4	16.8	791	1.2	144.3	5.3	218	1.19	21.4	3.0	0.7	54	28.8	9.2	0.2	129	0.89	0.097	14
1278505	Soil		22.1	39.0	18.0	358	0.6	54.1	4.2	65	1.55	41.6	6.5	1.9	40	3.1	10.2	0.2	139	0.20	0.109	14
1278506	Soil		19.1	54.6	14.6	5150	0.9	682.2	6.9	291	4.60	731.4	4.1	0.4	97	58.1	93.4	0.2	294	2.09	0.905	4
1278507	Soil		25.3	28.5	23.4	1252	0.6	142.6	4.5	243	1.13	64.4	3.4	0.3	65	9.9	16.9	0.1	97	0.81	0.149	5
1278508	Soil		28.2	36.3	22.3	908	0.7	138.6	7.0	188	1.77	60.1	5.8	0.8	54	7.1	18.9	0.2	124	0.68	0.166	9
1278509	Soil		17.4	55.2	14.2	809	1.6	203.9	3.8	213	1.00	25.3	5.9	0.8	56	5.5	14.4	0.1	67	1.05	0.119	7
1278510	Soil		93.2	71.4	21.2	731	1.1	130.5	8.3	295	4.22	129.9	0.7	2.6	63	3.4	21.3	0.2	86	0.31	0.125	6
1278511	Soil		52.0	46.8	16.5	886	1.1	159.4	16.0	591	2.77	109.2	7.9	2.0	44	7.1	16.6	0.2	69	0.56	0.108	6
1278512	Soil		46.4	56.3	19.9	867	1.3	135.9	9.9	235	3.45	965.8	10.0	2.4	53	5.7	17.6	0.2	86	0.45	0.115	8
1278513	Soil		22.0	50.3	40.2	354	1.7	48.2	4.4	118	2.03	439.8	31.0	4.9	81	2.8	22.5	0.4	74	0.35	0.138	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1278284	Soil		15	0.03	188	0.004	1	0.49	0.008	0.05	0.1	0.04	0.5	0.2	0.10	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278285	Soil		10	0.01	112	0.004	1	0.26	0.003	0.06	0.1	0.02	0.6	0.1	0.06	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278286	Soil		14	0.01	174	0.006	2	0.37	0.004	0.09	<0.1	0.04	2.0	0.3	0.14	3	4.2	0.2	N.A.	N.A.	N.A.	N.A.
1278287	Soil		20	0.06	157	0.005	3	1.03	0.007	0.08	<0.1	0.08	7.2	0.4	0.10	3	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278288	Soil		11	0.02	62	0.003	1	0.42	0.005	0.07	<0.1	0.03	1.7	0.2	0.06	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278289	Soil		14	0.07	599	0.002	2	0.57	0.002	0.07	<0.1	0.21	4.7	0.3	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278290	Soil		25	5.39	448	0.002	8	0.31	0.009	0.09	<0.1	1.33	3.7	0.9	0.12	<1	6.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278291	Soil		18	0.21	1747	0.006	4	0.69	0.003	0.14	<0.1	0.19	10.6	0.6	0.17	2	3.3	0.5	N.A.	N.A.	N.A.	N.A.
1278292	Soil		8	0.05	170	0.003	2	0.43	0.003	0.09	<0.1	0.11	4.3	0.2	<0.05	1	2.0	0.2	N.A.	N.A.	N.A.	N.A.
1278293	Soil		19	0.10	308	0.007	2	0.71	0.003	0.08	0.2	0.24	0.9	0.5	0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278294	Soil		7	0.03	209	0.004	2	0.41	0.014	0.06	<0.1	0.02	0.3	0.1	0.06	2	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278295	Soil		18	0.03	255	0.004	2	0.42	0.006	0.11	0.1	0.28	0.8	0.4	0.18	2	4.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278296	Soil		18	0.03	463	0.003	3	0.38	0.009	0.09	0.2	0.51	0.2	0.4	0.21	1	3.7	0.2	N.A.	N.A.	N.A.	N.A.
1278297	Soil		21	0.03	696	0.009	4	0.52	0.005	0.19	0.1	0.15	1.2	0.8	0.34	2	9.5	0.4	N.A.	N.A.	N.A.	N.A.
1278298	Soil		8	0.05	522	0.002	3	0.47	0.002	0.13	<0.1	0.05	2.5	0.2	<0.05	1	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278299	Soil		14	0.17	1939	0.007	3	1.25	0.005	0.15	0.1	0.13	5.0	0.2	0.16	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278300	Soil		14	0.14	3519	0.009	2	1.03	0.008	0.16	0.1	0.11	2.1	0.2	0.14	3	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278501	Soil		16	0.07	421	0.004	2	0.59	0.003	0.08	0.3	0.14	1.5	0.7	0.06	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278502	Soil		18	0.06	1229	0.003	2	0.64	0.006	0.07	0.2	0.53	1.7	0.8	0.10	2	4.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278503	Soil		12	0.04	582	0.007	3	0.41	0.012	0.06	0.2	0.31	1.3	0.5	0.08	1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278504	Soil		19	0.04	2054	0.005	6	0.77	0.007	0.07	0.2	0.85	2.1	0.7	0.07	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278505	Soil		15	0.05	900	0.003	5	0.41	0.005	0.09	0.2	0.52	1.9	0.9	0.12	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278506	Soil		17	0.16	749	0.006	5	0.48	0.003	0.04	0.2	1.13	0.9	2.7	0.24	1	24.5	0.3	N.A.	N.A.	N.A.	N.A.
1278507	Soil		18	0.07	269	0.003	2	0.38	0.009	0.06	0.2	0.35	1.0	1.3	0.10	2	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278508	Soil		16	0.07	438	0.003	4	0.39	0.003	0.07	0.3	0.43	1.7	0.9	0.07	1	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278509	Soil		17	0.11	408	0.005	2	0.47	0.007	0.05	0.2	1.10	1.8	1.0	0.07	1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278510	Soil		15	0.07	969	0.001	3	0.48	0.003	0.08	0.1	1.04	3.9	0.8	0.09	1	6.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278511	Soil		16	0.10	1010	<0.001	3	0.59	0.003	0.05	0.1	1.21	2.9	0.5	<0.05	2	5.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278512	Soil		15	0.10	980	0.001	3	0.55	0.003	0.06	0.2	1.21	3.0	0.5	0.06	2	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278513	Soil		15	0.04	694	<0.001	4	0.38	0.002	0.08	0.3	1.47	2.0	0.6	0.08	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1278284	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278285	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278286	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278287	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278288	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278289	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278290	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278291	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278292	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278293	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278294	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278295	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278296	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278297	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278298	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278299	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278300	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278501	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278502	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278503	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278504	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278505	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278506	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278507	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278508	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278509	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278510	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278511	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278512	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278513	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278284	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278285	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278286	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278287	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278288	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278289	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278290	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278291	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278292	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278293	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278294	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278295	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278296	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278297	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278298	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278299	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278300	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278501	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278502	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278503	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278504	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278505	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278506	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278507	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278508	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278509	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278510	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278511	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278512	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278513	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278514	Soil	29.6	58.4	24.7	1980	2.3	208.2	6.0	278	2.32	225.8	12.5	1.9	78	10.7	22.3	0.3	99	0.55	0.158	8
1278515	Soil	23.8	65.2	21.9	2766	2.4	294.3	7.3	353	1.86	212.5	15.6	1.9	83	9.9	17.5	0.3	80	0.70	0.159	7
1278516	Soil	30.3	63.9	23.5	2671	2.4	301.4	9.5	623	2.27	289.0	10.4	2.0	94	6.2	22.7	0.3	108	0.78	0.208	7
1278517	Soil	29.8	66.7	19.6	1942	2.7	245.6	7.6	264	2.30	341.5	3.7	1.6	103	8.4	22.1	0.3	86	0.74	0.217	6
1278518	Soil	29.0	59.2	19.1	2106	2.5	281.4	5.2	244	2.04	299.3	6.3	1.5	103	8.1	22.0	0.2	88	0.88	0.214	6
1278519	Soil	10.5	51.0	13.6	162	0.5	34.9	4.4	95	1.80	32.8	7.1	1.1	61	1.4	6.7	0.2	103	0.14	0.121	7
1278520	Soil	10.2	51.0	13.5	179	0.6	39.0	4.2	88	1.75	30.9	7.2	1.0	61	2.2	6.3	0.2	86	0.17	0.124	7
1278521	Soil	13.1	63.6	16.5	255	0.9	54.1	5.4	112	2.06	38.0	6.6	1.7	80	3.4	8.5	0.2	115	0.22	0.138	7
1278522	Soil	13.0	60.4	17.1	228	0.8	46.8	6.6	133	2.26	38.9	6.5	1.6	77	2.1	8.0	0.2	103	0.17	0.135	10
1278523	Soil	8.9	66.2	16.5	338	1.5	71.6	8.5	155	2.12	39.7	10.6	2.0	83	2.9	5.9	0.2	84	0.63	0.154	11
1278524	Soil	7.4	41.6	20.6	132	1.7	24.5	4.2	80	2.54	25.4	5.0	1.0	25	1.0	3.3	0.3	98	0.05	0.078	8
1278525	Soil	9.1	47.6	21.6	157	0.6	31.7	4.5	84	2.55	24.8	7.7	1.4	35	0.5	3.8	0.3	100	0.03	0.080	6
1278526	Soil	10.1	97.0	21.1	240	0.6	53.5	9.1	182	3.01	30.5	7.0	2.5	56	1.7	5.2	0.5	93	0.11	0.103	10
1278527	Soil	12.2	79.5	19.4	226	0.7	54.1	7.3	120	2.87	32.2	10.1	2.4	73	0.9	6.1	0.3	85	0.12	0.113	9
1278528	Soil	2.9	18.2	6.8	67	0.3	14.0	2.1	41	1.02	9.6	2.8	0.3	14	0.2	1.5	0.2	38	0.03	0.053	4
1278529	Soil	12.5	34.8	24.1	171	0.7	37.1	5.9	130	3.06	34.1	5.4	1.4	52	0.6	5.3	0.3	118	0.02	0.103	8
1278530	Soil	11.4	55.1	22.9	238	0.7	51.0	7.0	132	3.67	35.5	8.9	2.4	54	0.7	6.0	0.3	115	0.04	0.101	8
1278531	Soil	8.6	68.1	17.4	216	0.2	48.0	7.9	181	2.89	25.6	7.0	2.0	47	0.8	4.6	0.2	81	0.11	0.096	8
1278532	Soil	8.4	63.0	16.8	218	0.4	48.9	9.4	198	2.92	26.5	7.3	2.5	49	0.9	4.7	0.2	75	0.14	0.100	8
1278533	Soil	6.9	39.2	15.9	165	0.5	35.3	6.5	135	2.58	26.5	3.5	1.4	32	0.5	3.4	0.3	81	0.10	0.068	7
1278534	Soil	5.6	25.8	12.4	107	0.2	24.4	4.2	59	1.83	17.6	1.3	1.9	13	0.4	2.7	0.2	64	0.02	0.033	12
1278535	Soil	3.2	14.7	7.2	65	0.4	16.4	3.2	46	1.29	10.1	0.6	0.8	12	0.1	1.6	0.1	40	0.01	0.041	10
1278536	Soil	5.1	18.1	12.6	104	0.3	21.0	3.9	110	2.28	18.0	1.6	2.4	15	0.3	2.6	0.2	66	0.02	0.044	11
1278537	Soil	5.1	17.3	13.6	82	0.2	17.7	3.1	67	2.00	17.3	2.3	1.7	15	0.3	2.6	0.2	75	0.02	0.046	12
1278538	Soil	13.2	34.8	20.9	149	0.4	35.6	5.2	90	2.58	29.9	4.7	1.9	52	0.4	5.1	0.2	114	0.03	0.067	11
1278539	Soil	8.3	66.0	16.5	242	0.4	57.5	9.4	198	3.15	28.0	5.2	2.9	54	1.1	5.3	0.4	69	0.23	0.114	10
1278540	Soil	9.7	46.4	18.7	269	0.4	53.4	10.4	242	3.17	28.9	4.6	2.5	67	1.1	5.7	0.3	164	0.40	0.108	11
1278541	Soil	6.9	87.8	14.3	311	1.3	74.4	11.2	242	3.05	20.9	9.4	3.0	86	2.2	5.0	0.2	83	0.70	0.113	9
1278542	Soil	7.2	49.5	13.8	326	0.7	66.8	13.2	281	3.06	13.8	3.8	2.3	74	3.4	2.5	0.2	51	0.98	0.102	7
1278543	Soil	5.2	66.0	14.8	215	0.8	68.1	11.1	176	3.28	16.4	5.7	2.7	44	1.2	2.9	0.2	43	0.37	0.073	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1278514	Soil	18	0.08	1201	0.002	5	0.57	0.004	0.09	0.2	2.63	2.5	1.0	0.06	2	4.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278515	Soil	17	0.07	1043	0.002	6	0.66	0.005	0.08	0.1	2.66	2.6	1.1	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278516	Soil	19	0.08	1115	0.002	6	0.64	0.004	0.09	0.2	2.50	2.8	1.2	0.05	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278517	Soil	16	0.09	983	0.002	6	0.66	0.006	0.08	0.1	1.92	2.9	1.2	<0.05	2	4.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278518	Soil	16	0.08	904	0.002	7	0.66	0.005	0.08	0.2	1.79	2.5	1.1	0.06	2	12.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278519	Soil	21	0.05	1341	0.003	3	0.50	0.002	0.08	0.1	0.82	2.4	0.5	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278520	Soil	18	0.05	1182	0.002	3	0.46	0.002	0.07	0.1	0.74	2.2	0.4	<0.05	1	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278521	Soil	24	0.06	1873	0.004	5	0.46	0.003	0.09	0.1	0.95	3.0	0.6	<0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278522	Soil	22	0.08	1885	0.004	5	0.56	0.003	0.09	0.2	0.81	2.8	0.5	0.06	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278523	Soil	25	0.13	2036	0.002	5	0.67	0.004	0.09	0.1	2.39	3.8	0.5	0.05	2	3.5	0.2	N.A.	N.A.	N.A.	N.A.
1278524	Soil	27	0.09	524	0.005	2	0.86	0.005	0.08	0.1	0.16	1.5	0.4	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278525	Soil	33	0.14	456	0.003	3	0.97	0.006	0.08	0.1	0.22	2.0	0.4	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278526	Soil	39	0.23	1308	0.004	2	1.07	0.004	0.06	0.2	0.37	3.2	0.4	0.19	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278527	Soil	30	0.16	1274	0.004	2	0.72	0.003	0.07	0.1	0.40	3.3	0.4	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278528	Soil	13	0.07	150	0.004	<1	0.41	0.011	0.04	<0.1	0.06	0.4	0.1	<0.05	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278529	Soil	29	0.13	384	0.004	1	0.85	0.005	0.07	0.2	0.09	1.7	0.4	<0.05	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278530	Soil	43	0.22	531	0.002	2	1.25	0.004	0.07	0.1	0.20	2.7	0.5	<0.05	4	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278531	Soil	36	0.24	1299	0.003	2	0.97	0.003	0.06	<0.1	0.17	2.5	0.3	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278532	Soil	35	0.26	1341	0.003	<1	0.95	0.003	0.05	0.1	0.24	2.6	0.3	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278533	Soil	26	0.16	723	0.003	<1	0.89	0.004	0.06	0.1	0.11	1.8	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278534	Soil	13	0.06	567	0.003	<1	0.64	0.002	0.04	<0.1	0.06	1.2	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278535	Soil	10	0.05	998	0.003	<1	0.47	0.007	0.04	<0.1	0.04	0.7	0.1	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278536	Soil	23	0.13	413	0.005	1	0.88	0.003	0.05	0.1	0.05	1.3	0.2	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278537	Soil	19	0.10	237	0.007	<1	0.88	0.003	0.05	0.1	0.04	1.3	0.2	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278538	Soil	21	0.09	514	0.007	<1	0.77	0.003	0.06	0.2	0.21	1.7	0.4	<0.05	3	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278539	Soil	32	0.27	1583	0.003	<1	0.92	0.002	0.05	0.1	0.26	2.7	0.3	<0.05	3	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278540	Soil	31	0.24	1558	0.005	2	1.15	0.004	0.08	0.2	0.22	2.4	0.4	0.09	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278541	Soil	38	0.30	2033	0.003	5	1.25	0.006	0.11	<0.1	0.58	4.4	0.3	0.14	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278542	Soil	25	0.30	598	0.002	4	0.99	0.005	0.08	<0.1	0.45	3.1	0.2	0.34	2	7.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278543	Soil	19	0.19	2804	0.002	2	0.80	0.006	0.05	<0.1	0.26	4.0	0.2	0.08	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1278514	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278515	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278516	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278517	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278518	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278519	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278520	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278521	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278522	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278523	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278524	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278525	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278526	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278527	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278528	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278529	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278530	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278531	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278532	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278533	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278534	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278535	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278536	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278537	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278538	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278539	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278540	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278541	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278542	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278543	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278514	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278515	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278516	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278517	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278518	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278519	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278520	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278521	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278522	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278523	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278524	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278525	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278526	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278527	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278528	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278529	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278530	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278531	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278532	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278533	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278534	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278535	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278536	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278537	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278538	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278539	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278540	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278541	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278542	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278543	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278544	Soil		4.8	40.4	13.7	166	0.3	43.1	7.1	135	2.65	16.0	1.9	1.5	22	0.5	2.7	0.2	48	0.04	0.087	7
1278545	Soil		4.2	19.9	10.9	88	0.3	17.9	3.6	94	1.77	12.8	0.8	0.2	12	0.3	1.7	0.2	48	0.03	0.040	9
1278546	Soil		4.1	48.7	8.1	286	0.9	55.7	6.2	459	1.94	9.4	4.2	0.5	125	3.4	2.4	0.2	43	2.00	0.165	6
1278547	Soil		4.8	30.6	13.6	170	1.0	34.5	8.6	275	2.54	16.8	4.9	2.3	74	1.1	2.5	0.2	63	0.64	0.103	11
1278548	Soil		3.4	58.6	9.6	197	1.2	43.0	5.6	131	1.85	10.7	11.2	0.9	126	2.3	2.7	0.1	58	1.22	0.121	7
1278549	Soil		20.8	70.1	16.0	481	1.9	96.7	19.5	948	4.23	22.7	8.2	1.5	79	3.8	6.6	0.2	102	0.77	0.208	8
1278550	Soil		17.5	66.0	17.4	466	1.4	97.0	18.9	1041	4.11	26.9	8.2	1.2	77	3.4	5.3	0.2	100	0.67	0.210	8
1278551	Soil		3.6	24.7	12.0	67	0.3	17.2	3.5	97	1.44	26.8	3.2	0.3	23	0.3	1.9	0.2	41	0.08	0.070	6
1278552	Soil		3.4	19.6	12.2	50	0.3	13.2	2.8	50	1.36	31.5	48.8	0.3	17	0.1	2.3	0.2	35	0.04	0.071	6
1278553	Soil		3.4	31.3	20.9	93	1.2	30.5	5.5	89	2.49	45.9	6.1	0.9	62	0.4	2.1	0.2	41	0.14	0.082	6
1278554	Soil		1.4	20.7	9.2	110	1.5	32.4	5.3	143	1.94	12.1	4.6	0.7	76	1.1	0.9	0.1	39	1.52	0.106	9
1278555	Soil		2.7	55.5	13.4	96	1.0	39.0	7.7	177	2.10	14.0	7.9	0.7	65	0.5	1.8	0.2	45	1.39	0.085	7
1278556	Soil		0.6	32.6	9.0	166	1.1	58.0	6.3	197	1.48	9.7	3.7	0.6	112	1.5	1.2	0.1	53	3.58	0.171	14
1278557	Soil		5.3	35.6	14.3	262	1.8	80.6	9.6	293	2.22	19.3	3.7	0.8	100	1.7	2.3	0.2	66	2.46	0.321	20
1278558	Soil		5.8	63.7	18.3	223	2.5	67.1	7.4	107	2.41	16.3	4.6	1.6	141	1.5	2.1	0.2	49	1.60	0.183	9
1278559	Soil		3.3	33.1	17.7	132	2.0	39.0	4.6	93	1.71	13.7	6.0	1.3	98	0.8	1.3	0.2	37	1.89	0.117	8
1278560	Soil		3.0	41.1	17.9	141	1.9	43.3	5.5	104	1.92	15.3	6.9	0.9	99	0.9	1.5	0.2	42	1.52	0.135	9
1278561	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1278562	Soil		0.8	22.4	10.4	111	1.0	22.5	4.2	177	1.38	10.1	6.6	0.6	85	0.7	1.1	0.2	27	1.81	0.110	6
1278563	Soil		2.1	34.2	14.2	133	0.9	31.7	6.6	269	1.69	30.7	20.8	0.9	77	1.1	3.8	0.3	39	1.71	0.100	8
1278564	Soil		12.2	23.7	18.1	99	0.8	23.7	2.1	31	0.87	24.5	13.7	0.8	31	0.6	7.6	0.2	73	0.23	0.042	7
1278565	Soil		12.4	53.1	26.7	157	2.3	44.2	6.4	179	1.18	38.9	44.8	1.0	107	1.5	11.8	0.3	111	1.36	0.124	10
1278566	Soil		0.9	8.4	5.6	17	0.7	5.2	0.5	13	0.24	3.5	6.8	0.1	19	0.2	1.3	<0.1	19	0.18	0.024	1
1278567	Soil		17.2	67.3	28.7	164	1.1	46.9	5.1	96	2.76	135.4	29.1	2.1	85	1.9	18.8	0.3	177	0.71	0.131	11
1278568	Soil		11.0	44.0	22.1	127	1.4	35.9	3.0	68	1.02	27.1	26.8	0.8	83	1.4	11.3	0.2	78	0.61	0.085	8
1278569	Soil		4.0	28.9	10.1	76	0.3	21.1	4.8	111	1.69	16.9	10.7	1.2	25	0.3	4.8	0.2	35	0.14	0.066	5
1278570	Soil		2.9	97.9	13.2	171	0.3	43.9	7.9	92	2.92	12.3	16.8	2.0	32	0.4	3.0	0.2	35	0.27	0.039	5
1278571	Soil		3.1	117.6	18.2	147	1.0	41.8	7.0	116	1.89	24.3	27.5	1.6	79	0.6	5.7	0.3	60	0.76	0.080	7
1278572	Soil		3.0	117.6	19.3	164	1.1	46.8	7.5	153	2.15	26.4	27.1	1.3	116	1.0	5.3	0.3	57	1.06	0.089	5
1278573	Soil		2.3	79.3	15.5	178	0.9	44.8	8.4	102	2.58	18.5	20.8	1.8	121	0.7	3.3	0.3	48	0.68	0.056	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1278544	Soil	16	0.13	2471	0.003	1	0.70	0.008	0.05	<0.1	0.04	1.6	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278545	Soil	13	0.07	1149	0.008	1	0.45	0.008	0.05	<0.1	0.04	0.6	0.1	<0.05	3	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278546	Soil	18	0.17	1341	0.005	5	1.00	0.012	0.05	<0.1	0.79	1.3	0.2	0.26	2	5.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278547	Soil	25	0.28	2146	0.005	2	1.15	0.005	0.06	0.1	0.49	3.2	0.2	0.20	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278548	Soil	24	0.20	1663	0.004	4	1.00	0.008	0.08	<0.1	0.88	2.2	0.2	0.21	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278549	Soil	30	0.18	2460	0.003	4	1.34	0.008	0.10	<0.1	1.16	4.0	0.4	0.37	3	5.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278550	Soil	33	0.18	2446	0.004	4	1.29	0.011	0.10	0.2	0.90	3.9	0.3	0.08	3	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278551	Soil	13	0.04	216	0.004	<1	0.68	0.016	0.05	0.1	0.32	0.8	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278552	Soil	12	0.04	136	0.005	<1	0.65	0.014	0.04	0.2	0.52	0.4	0.2	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278553	Soil	22	0.08	484	0.005	1	0.88	0.009	0.07	0.1	0.34	1.9	0.2	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278554	Soil	21	0.15	523	0.003	2	0.77	0.018	0.04	<0.1	0.48	2.1	<0.1	0.20	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278555	Soil	23	0.07	517	0.006	3	0.66	0.005	0.05	0.1	0.35	2.7	0.2	0.16	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278556	Soil	32	0.15	919	0.004	5	0.74	0.008	0.06	<0.1	0.48	1.8	0.2	0.38	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278557	Soil	33	0.29	895	0.005	9	1.00	0.014	0.08	0.1	0.57	1.7	0.4	0.16	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278558	Soil	23	0.23	727	0.002	5	0.94	0.012	0.13	<0.1	0.41	3.3	0.3	0.23	2	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278559	Soil	22	0.27	560	0.002	4	0.77	0.009	0.10	<0.1	0.42	2.1	0.2	0.23	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278560	Soil	20	0.21	630	0.002	5	0.78	0.010	0.09	<0.1	0.43	2.2	0.2	0.24	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278561	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	3.2	39.0	15.9	142
1278562	Soil	15	0.11	407	0.002	5	0.64	0.012	0.06	<0.1	0.35	1.5	<0.1	0.11	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1278563	Soil	16	0.17	464	0.003	4	0.72	0.011	0.05	0.1	1.78	1.9	0.2	0.11	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278564	Soil	13	0.02	183	0.003	2	0.28	0.009	0.04	0.4	0.77	0.9	0.3	0.07	1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278565	Soil	18	0.07	675	0.006	5	0.64	0.009	0.07	0.4	2.75	1.9	1.5	0.16	2	5.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278566	Soil	4	0.02	136	0.004	2	0.16	0.023	0.03	<0.1	0.92	0.6	0.2	0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278567	Soil	20	0.13	765	0.002	3	0.76	0.006	0.06	0.4	3.49	2.6	0.8	0.09	2	5.5	0.2	N.A.	N.A.	N.A.	N.A.
1278568	Soil	16	0.07	593	0.002	4	0.46	0.012	0.06	0.3	2.17	1.6	0.9	0.10	1	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278569	Soil	21	0.21	549	0.002	2	0.76	0.009	0.04	0.1	0.49	1.3	0.1	0.06	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278570	Soil	43	0.56	554	<0.001	2	1.41	0.004	0.05	<0.1	0.33	2.3	<0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278571	Soil	29	0.32	872	0.001	2	1.05	0.007	0.06	0.1	1.82	2.7	0.4	0.06	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278572	Soil	33	0.37	794	0.002	4	1.16	0.007	0.06	0.1	1.60	3.1	0.3	0.08	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278573	Soil	48	0.50	692	<0.001	3	1.35	0.005	0.05	<0.1	1.24	3.3	0.3	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1278544	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278545	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278546	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278547	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278548	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278549	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278550	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278551	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278552	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278553	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278554	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278555	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278556	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278557	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278558	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278559	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278560	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278561	Soil	1.8	37.8	4.7	120	1.81	13.6	5.8	1.0	88	0.6	0.8	0.2	46	1.33	0.096	8	25	0.22	613	0.002
1278562	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278563	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278564	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278565	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278566	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278567	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278568	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278569	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278570	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278571	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278572	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278573	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278544	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278545	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278546	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278547	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278548	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278549	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278550	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278551	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278552	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278553	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278554	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278555	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278556	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278557	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278558	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278559	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278560	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278561	Soil	<20	0.91	0.014	0.08	<0.1	0.44	2.4	0.2	0.14	2	2.7	<0.2
1278562	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278563	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278564	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278565	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278566	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278567	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278568	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278569	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278570	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278571	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278572	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278573	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278574	Soil	1.9	80.5	15.3	150	0.6	40.8	7.6	103	2.39	13.8	19.6	1.4	91	0.6	2.9	0.3	41	0.64	0.054	4
1278575	Soil	3.0	110.4	19.5	172	0.9	47.7	8.2	100	2.92	18.2	24.4	1.6	121	0.4	3.9	0.4	47	0.64	0.057	5
1278576	Soil	3.2	95.2	15.8	176	0.5	43.8	9.1	125	2.75	15.4	20.5	1.5	48	0.6	3.0	0.3	44	0.42	0.056	4
1278577	Soil	3.3	89.5	13.9	168	0.6	43.8	9.1	143	2.83	18.1	17.1	1.5	56	0.4	3.1	0.3	45	0.42	0.060	5
1278578	Soil	10.4	73.1	19.1	442	1.7	89.6	9.4	263	2.73	43.7	9.7	1.8	98	4.9	6.9	0.3	84	0.57	0.168	10
1278579	Soil	3.8	38.9	14.7	221	1.0	36.4	6.2	289	1.78	18.6	5.9	0.9	81	2.2	2.9	0.2	67	1.36	0.113	7
1278580	Soil	3.1	51.3	9.8	123	0.4	33.2	4.5	127	1.62	11.9	7.9	1.1	208	0.9	1.8	0.2	38	0.63	0.075	4
1278581	Soil	2.8	62.9	10.2	167	0.9	46.5	6.0	196	1.72	10.5	10.8	1.4	324	1.3	2.3	0.2	38	1.07	0.076	4
1278582	Soil	4.6	57.2	10.6	226	1.0	52.3	12.2	1518	2.23	13.3	9.2	1.4	297	3.0	3.0	0.2	52	0.90	0.094	5
1278583	Soil	3.6	48.4	12.1	182	1.3	42.3	5.8	482	1.73	13.2	9.5	1.2	241	1.6	2.6	0.2	54	0.79	0.114	5
1278584	Soil	8.9	82.5	15.6	368	1.1	61.0	11.7	218	2.78	21.3	9.3	1.8	91	4.2	5.5	0.3	73	0.51	0.110	7
1278585	Soil	9.0	68.7	19.2	504	1.2	98.8	11.9	215	2.82	41.9	8.5	2.3	88	4.4	5.5	0.2	73	0.51	0.157	10
1278586	Soil	5.5	144.0	16.1	245	1.0	46.8	9.5	195	2.59	22.5	16.4	2.0	123	0.8	3.9	0.3	53	0.49	0.074	7
1278587	Soil	3.9	79.0	16.3	183	0.8	40.9	9.9	258	2.55	23.5	11.6	2.1	145	0.5	3.6	0.3	50	0.63	0.071	6
1278588	Soil	3.9	61.2	16.3	139	1.0	34.7	11.8	528	2.20	23.9	11.1	1.8	112	0.4	3.8	0.3	42	0.64	0.077	6
1278589	Soil	2.8	46.6	15.7	147	0.9	37.6	8.7	271	2.40	21.3	11.0	2.0	63	0.4	2.6	0.3	41	0.82	0.063	6
1278590	Soil	2.4	51.3	12.7	134	1.4	41.0	5.8	162	2.13	16.7	12.3	1.6	75	0.4	2.7	0.2	34	1.00	0.079	6
1278591	Soil	2.5	39.7	12.6	152	0.8	43.2	10.2	424	2.59	10.7	9.2	3.0	48	0.2	1.7	0.3	31	0.55	0.072	9
1278592	Soil	2.4	53.5	14.4	168	0.9	49.4	10.3	257	2.39	11.4	11.4	2.2	49	0.4	1.9	0.3	29	0.68	0.068	9
1278593	Soil	1.1	75.6	15.9	147	0.8	42.5	9.6	266	2.08	8.8	10.3	2.9	67	0.3	1.4	0.3	25	1.11	0.063	13
1278594	Soil	2.3	70.9	15.6	171	0.8	43.3	8.4	196	2.18	16.9	10.0	1.9	63	0.6	2.6	0.3	30	1.04	0.067	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1278574	Soil	44	0.48	831	0.001	2	1.28	0.007	0.05	<0.1	0.71	2.5	0.2	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278575	Soil	56	0.58	1146	<0.001	4	1.48	0.006	0.05	<0.1	0.95	3.1	0.2	0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278576	Soil	48	0.52	838	0.001	3	1.42	0.007	0.05	<0.1	0.63	2.8	0.2	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278577	Soil	47	0.50	1223	<0.001	3	1.42	0.006	0.05	<0.1	0.63	2.7	0.2	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1278578	Soil	25	0.15	1833	0.001	6	0.70	0.004	0.09	<0.1	1.99	3.8	0.5	0.09	2	4.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278579	Soil	20	0.17	950	0.002	4	0.87	0.007	0.07	0.1	0.97	2.0	0.3	0.10	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278580	Soil	22	0.23	1016	0.002	3	0.89	0.007	0.06	<0.1	0.34	1.9	0.2	0.07	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1278581	Soil	20	0.30	1311	0.001	4	0.90	0.007	0.07	<0.1	0.50	2.5	0.2	0.08	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278582	Soil	20	0.27	1857	0.003	6	1.04	0.010	0.09	<0.1	0.56	2.7	0.3	0.11	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1278583	Soil	22	0.26	1586	0.002	3	1.02	0.008	0.07	<0.1	0.76	2.6	0.2	0.08	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1278584	Soil	24	0.22	1396	0.001	3	1.20	0.005	0.07	<0.1	0.85	3.5	0.3	0.07	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278585	Soil	24	0.19	1663	0.001	4	0.79	0.004	0.09	<0.1	1.50	3.6	0.4	0.08	2	4.8	<0.2	N.A.	N.A.	N.A.	N.A.
1278586	Soil	30	0.37	1208	0.001	3	1.15	0.005	0.07	<0.1	0.74	3.7	0.3	<0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278587	Soil	29	0.38	1078	0.002	2	1.18	0.006	0.07	<0.1	0.72	3.0	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278588	Soil	25	0.33	1171	0.001	3	1.11	0.009	0.05	<0.1	0.88	2.7	0.2	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1278589	Soil	28	0.37	1233	0.001	3	1.13	0.006	0.07	<0.1	0.81	2.9	0.2	<0.05	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1278590	Soil	23	0.33	1267	0.001	4	1.08	0.007	0.07	<0.1	0.73	2.8	0.2	0.07	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278591	Soil	30	0.48	1052	0.001	4	1.19	0.006	0.06	<0.1	0.30	3.8	0.1	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1278592	Soil	27	0.43	1426	0.001	3	1.18	0.006	0.07	<0.1	0.34	3.5	0.1	0.07	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278593	Soil	26	0.45	1167	0.002	3	1.15	0.006	0.07	<0.1	0.32	3.2	0.1	0.05	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1278594	Soil	24	0.39	652	0.001	4	1.03	0.006	0.06	<0.1	0.63	2.2	0.2	0.06	2	1.4	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
Unit		ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
MDL		0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1278574	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278575	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278576	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278577	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278578	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278579	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278580	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278581	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278582	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278583	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278584	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278585	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278586	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278587	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278588	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278589	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278590	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278591	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278592	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278593	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278594	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001180.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278574	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278575	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278576	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278577	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278578	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278579	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278580	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278581	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278582	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278583	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278584	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278585	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278586	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278587	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278588	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278589	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278590	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278591	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278592	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278593	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1278594	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1276440	Soil	12.5	74.1	29.6	331	1.9	92.5	15.1	535	4.12	54.9	4.1	4.1	124	2.1	4.9	0.4	87	0.96	0.220	17
REP 1276440	QC	12.0	76.4	32.6	334	2.1	91.9	14.6	523	4.12	55.6	3.0	3.6	125	1.9	4.9	0.4	83	0.90	0.226	16
1277933	Soil	2.0	21.8	7.4	30	0.7	9.6	2.1	30	1.35	48.4	3.9	0.2	9	0.2	2.8	0.9	25	0.03	0.080	8
REP 1277933	QC	2.1	21.9	7.6	33	0.7	9.8	2.3	29	1.39	49.5	3.7	0.2	9	0.1	2.9	0.9	25	0.03	0.082	8
1277948	Soil	123.8	58.5	1635	96	8.0	27.9	2.3	47	3.18	318.5	97.9	1.3	348	0.4	67.8	0.9	558	0.14	0.243	12
REP 1277948	QC	121.0	57.0	1609	101	7.8	27.4	2.4	47	3.11	318.7	104.3	1.2	336	0.5	68.4	0.9	538	0.14	0.237	12
1277961	Soil	11.1	27.2	15.8	131	0.4	26.6	3.6	58	1.55	40.5	5.1	0.2	19	1.0	4.3	0.3	79	0.02	0.071	10
REP 1277961	QC	10.7	27.5	15.7	133	0.4	25.4	3.8	59	1.43	40.5	4.8	0.3	19	0.9	4.1	0.3	79	0.02	0.070	10
1277979	Soil	37.0	19.3	6.8	213	0.1	64.3	4.6	106	1.34	34.0	1.9	1.0	13	0.9	5.7	0.1	122	0.17	0.029	15
REP 1277979	QC	38.9	19.5	7.0	214	<0.1	67.2	4.4	107	1.45	36.1	1.1	1.1	13	1.1	6.0	0.1	124	0.17	0.030	15
1277995	Soil	22.4	46.9	16.3	324	1.1	76.5	7.5	128	2.51	55.4	2.7	0.6	27	4.5	8.7	0.2	161	0.34	0.114	12
REP 1277995	QC	22.9	48.2	16.6	332	1.1	79.3	8.0	138	2.59	58.1	2.4	0.6	30	4.8	9.2	0.3	173	0.35	0.113	13
1278201	Soil	6.3	41.4	15.0	198	0.9	47.1	11.1	237	2.80	19.7	6.3	2.3	51	1.3	2.8	0.3	50	0.64	0.074	10
REP 1278201	QC	6.2	40.8	15.1	201	1.0	45.8	10.9	233	2.77	19.9	7.4	2.5	51	1.3	2.8	0.3	50	0.64	0.077	10
1278227	Soil	19.0	64.5	16.4	412	1.0	75.5	9.6	204	2.54	56.5	7.6	2.9	41	4.2	9.9	0.2	162	0.23	0.144	19
REP 1278227	QC	18.5	61.7	15.5	393	1.0	73.0	9.2	191	2.44	55.2	6.6	2.7	39	4.2	9.3	0.2	159	0.22	0.135	18
1278233	Soil	13.2	47.0	12.3	162	1.5	32.5	3.1	36	1.36	18.6	0.9	0.2	10	0.2	4.4	0.2	85	0.02	0.043	13
REP 1278233	QC	13.4	47.0	12.1	163	1.5	32.4	3.1	36	1.35	18.2	1.5	0.3	11	0.2	4.2	0.2	81	0.02	0.045	13
1278246	Soil	2.0	17.4	5.7	53	0.5	10.1	2.2	43	1.03	3.9	0.9	0.1	5	0.2	0.8	0.1	31	0.02	0.046	7
REP 1278246	QC	1.9	16.8	5.3	50	0.5	9.7	2.1	40	0.97	3.6	<0.5	<0.1	5	0.2	0.7	0.1	30	0.02	0.043	7
1278262	Soil	15.8	38.7	27.8	262	0.6	54.2	7.8	149	3.39	35.9	6.5	2.8	40	0.7	5.5	0.4	144	0.05	0.083	11
REP 1278262	QC	15.6	37.7	27.5	253	0.6	52.0	7.6	148	3.30	35.1	6.0	2.9	39	0.6	5.3	0.3	133	0.05	0.082	10
1278278	Soil	13.9	14.1	6.0	89	0.1	29.9	1.9	36	0.66	9.9	<0.5	0.3	22	0.7	1.5	<0.1	84	0.37	0.059	6
REP 1278278	QC	13.9	13.6	6.2	91	0.1	29.3	1.9	37	0.65	9.9	<0.5	0.4	23	0.8	1.4	<0.1	85	0.36	0.056	7
1278293	Soil	12.2	57.0	18.9	312	0.8	68.5	8.3	277	2.68	41.2	1.2	0.4	47	3.4	7.3	0.2	202	0.23	0.274	10
REP 1278293	QC	11.8	58.7	19.4	319	0.8	69.6	8.3	270	2.71	41.7	0.8	0.3	45	3.3	7.1	0.2	200	0.24	0.279	11
1278542	Soil	7.2	49.5	13.8	326	0.7	66.8	13.2	281	3.06	13.8	3.8	2.3	74	3.4	2.5	0.2	51	0.98	0.102	7
REP 1278542	QC	7.0	47.6	13.4	319	0.7	64.1	12.7	273	2.93	13.4	4.0	2.1	71	3.3	2.5	0.2	47	0.94	0.098	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001180.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1276440	Soil	23	0.21	3777	0.004	8	0.74	0.011	0.20	<0.1	0.65	6.0	0.4	0.10	1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1276440	QC	21	0.19	3469	0.003	7	0.69	0.017	0.18	0.3	0.65	5.8	0.3	0.09	1	3.3	<0.2				
1277933	Soil	7	0.03	80	0.004	2	0.53	0.016	0.03	0.4	0.30	0.2	0.1	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277933	QC	7	0.03	84	0.005	1	0.55	0.017	0.04	0.5	0.34	0.3	0.1	<0.05	2	0.8	<0.2				
1277948	Soil	44	0.02	725	0.003	4	0.69	0.003	0.21	2.0	15.77	0.9	3.1	0.59	4	19.5	0.4	N.A.	N.A.	N.A.	N.A.
REP 1277948	QC	42	0.02	1376	0.003	4	0.67	0.003	0.21	2.0	15.33	1.0	3.2	0.59	4	19.0	0.3				
1277961	Soil	11	0.04	167	0.005	1	0.44	0.004	0.05	0.2	0.33	0.6	0.3	<0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277961	QC	11	0.04	169	0.004	2	0.46	0.004	0.05	0.2	0.21	0.5	0.3	<0.05	2	1.3	<0.2				
1277979	Soil	14	0.09	311	0.005	1	0.64	0.003	0.05	0.3	0.14	1.3	0.8	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277979	QC	15	0.09	317	0.004	2	0.65	0.003	0.05	0.3	0.13	1.1	0.8	<0.05	3	1.5	<0.2				
1277995	Soil	14	0.07	783	0.003	4	0.39	0.004	0.07	0.2	0.32	1.1	0.5	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1277995	QC	16	0.07	814	0.004	4	0.44	0.004	0.08	0.2	0.30	1.1	0.5	<0.05	2	3.8	<0.2				
1278201	Soil	23	0.25	1655	0.003	3	0.89	0.004	0.06	<0.1	0.22	3.2	0.2	<0.05	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1278201	QC	22	0.25	1617	0.003	2	0.91	0.004	0.06	0.1	0.23	3.3	0.2	<0.05	2	2.6	<0.2				
1278227	Soil	23	0.09	908	0.002	4	0.77	0.003	0.10	0.1	0.63	2.9	0.6	<0.05	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1278227	QC	22	0.09	857	0.002	5	0.76	0.003	0.10	0.1	0.61	2.8	0.5	<0.05	2	2.8	<0.2				
1278233	Soil	8	0.03	88	0.008	2	0.36	0.005	0.06	0.1	0.02	0.5	0.3	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1278233	QC	8	0.02	89	0.007	2	0.35	0.004	0.06	0.1	0.02	0.4	0.3	<0.05	3	1.5	<0.2				
1278246	Soil	8	0.03	172	0.006	2	0.36	0.014	0.04	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1278246	QC	7	0.03	160	0.006	1	0.35	0.014	0.04	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2				
1278262	Soil	28	0.13	528	0.004	2	1.36	0.004	0.08	0.2	0.25	2.1	0.6	<0.05	4	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1278262	QC	26	0.12	514	0.003	<1	1.32	0.006	0.07	0.2	0.24	2.1	0.5	0.06	4	2.9	<0.2				
1278278	Soil	11	0.07	251	0.003	4	0.37	0.011	0.04	0.1	0.07	0.7	0.5	<0.05	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1278278	QC	12	0.07	263	0.005	2	0.38	0.011	0.05	0.2	0.07	0.9	0.5	<0.05	2	1.6	<0.2				
1278293	Soil	19	0.10	308	0.007	2	0.71	0.003	0.08	0.2	0.24	0.9	0.5	0.05	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1278293	QC	19	0.11	316	0.005	2	0.74	0.003	0.08	0.1	0.21	0.9	0.5	0.05	3	2.1	<0.2				
1278542	Soil	25	0.30	598	0.002	4	0.99	0.005	0.08	<0.1	0.45	3.1	0.2	0.34	2	7.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1278542	QC	23	0.29	532	0.002	4	0.92	0.010	0.06	<0.1	0.42	2.9	0.2	0.31	2	7.6	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001180.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1276440	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276440	QC																					
1277933	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277933	QC																					
1277948	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277948	QC																					
1277961	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277961	QC																					
1277979	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277979	QC																					
1277995	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277995	QC																					
1278201	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278201	QC																					
1278227	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278227	QC																					
1278233	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278233	QC																					
1278246	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278246	QC																					
1278262	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278262	QC																					
1278278	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278278	QC																					
1278293	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278293	QC																					
1278542	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278542	QC																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001180.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1276440	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1276440	QC													
1277933	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277933	QC													
1277948	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277948	QC													
1277961	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277961	QC													
1277979	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277979	QC													
1277995	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1277995	QC													
1278201	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278201	QC													
1278227	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278227	QC													
1278233	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278233	QC													
1278246	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278246	QC													
1278262	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278262	QC													
1278278	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278278	QC													
1278293	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278293	QC													
1278542	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278542	QC													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001180.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1278556	Soil	0.6	32.6	9.0	166	1.1	58.0	6.3	197	1.48	9.7	3.7	0.6	112	1.5	1.2	0.1	53	3.58	0.171	14
REP 1278556	QC	0.6	32.8	8.4	164	1.1	56.7	6.2	193	1.45	9.4	4.5	0.4	110	1.5	1.2	<0.1	52	3.60	0.173	14
1278565	Soil	12.4	53.1	26.7	157	2.3	44.2	6.4	179	1.18	38.9	44.8	1.0	107	1.5	11.8	0.3	111	1.36	0.124	10
REP 1278565	QC	12.5	50.0	25.8	150	2.2	43.7	5.7	177	1.18	38.9	41.3	0.9	104	1.6	11.7	0.3	104	1.34	0.115	11
1278582	Soil	4.6	57.2	10.6	226	1.0	52.3	12.2	1518	2.23	13.3	9.2	1.4	297	3.0	3.0	0.2	52	0.90	0.094	5
REP 1278582	QC	4.6	56.1	10.8	221	1.0	51.6	12.2	1475	2.18	13.3	13.0	1.4	292	3.2	3.0	0.2	51	0.86	0.089	5
Reference Materials																					
STD DS8	Standard	13.7	107.3	121.1	308	1.7	37.7	7.2	609	2.45	21.5	114.2	7.2	73	2.3	5.8	6.5	42	0.71	0.074	17
STD DS8	Standard	13.0	108.5	128.0	313	1.7	36.8	7.5	606	2.47	25.8	140.4	6.5	69	2.2	5.6	6.5	42	0.69	0.078	15
STD DS8	Standard	13.5	107.1	126.3	306	1.9	37.5	7.4	600	2.41	24.5	117.8	7.0	73	2.3	5.9	7.1	41	0.69	0.081	15
STD DS8	Standard	13.7	111.6	129.5	316	1.7	38.0	7.5	604	2.43	26.8	109.4	7.5	71	2.4	5.8	6.9	43	0.75	0.075	16
STD DS8	Standard	13.4	111.1	121.9	300	1.7	38.0	7.5	602	2.44	24.9	109.9	7.1	67	2.0	5.5	6.8	43	0.69	0.074	15
STD DS8	Standard	14.0	119.2	129.4	327	1.8	40.8	8.4	644	2.57	25.4	108.5	6.9	72	2.6	5.6	7.1	47	0.72	0.084	16
STD DS8	Standard	13.4	104.0	122.4	303	1.8	38.4	7.7	608	2.43	25.5	115.6	7.1	61	2.4	5.4	6.4	42	0.68	0.081	14
STD DS8	Standard	11.5	106.3	118.0	294	1.7	37.4	7.1	574	2.34	22.9	105.0	6.2	53	2.2	4.6	5.8	40	0.61	0.073	12
STD DS8	Standard	13.9	109.6	118.4	302	1.8	39.0	7.5	619	2.42	23.8	98.4	6.2	69	2.2	4.9	5.8	44	0.68	0.072	15
STD DS8	Standard	14.4	119.7	132.1	341	1.9	41.1	8.0	665	2.66	25.7	116.2	6.8	72	2.4	5.9	6.7	46	0.74	0.092	17
STD DS8	Standard	13.8	118.7	131.3	309	1.8	41.1	8.1	609	2.46	24.4	113.6	7.1	63	2.3	5.3	5.4	46	0.67	0.087	14
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	4	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001180.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
1278556	Soil	32	0.15	919	0.004	5	0.74	0.008	0.06	<0.1	0.48	1.8	0.2	0.38	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1278556	QC	31	0.15	897	0.003	6	0.73	0.007	0.05	<0.1	0.48	1.7	0.2	0.32	2	2.4	<0.2				
1278565	Soil	18	0.07	675	0.006	5	0.64	0.009	0.07	0.4	2.75	1.9	1.5	0.16	2	5.8	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1278565	QC	18	0.07	678	0.006	6	0.63	0.009	0.07	0.5	3.09	1.9	1.3	0.14	2	4.0	<0.2				
1278582	Soil	20	0.27	1857	0.003	6	1.04	0.010	0.09	<0.1	0.56	2.7	0.3	0.11	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1278582	QC	20	0.27	1795	0.003	7	1.01	0.010	0.09	<0.1	0.52	2.6	0.3	0.08	3	2.2	<0.2				
Reference Materials																					
STD DS8	Standard	121	0.60	281	0.127	2	0.93	0.104	0.41	3.0	0.20	2.8	5.5	0.14	5	4.0	4.8				
STD DS8	Standard	117	0.60	286	0.118	3	0.95	0.113	0.43	3.2	0.21	3.4	5.6	0.14	5	5.6	4.5				
STD DS8	Standard	113	0.62	288	0.112	3	0.97	0.106	0.44	3.1	0.22	2.2	5.5	0.16	5	5.0	5.2				
STD DS8	Standard	118	0.66	285	0.120	3	0.93	0.094	0.41	3.1	0.21	2.0	5.6	0.16	5	5.1	4.6				
STD DS8	Standard	118	0.59	267	0.121	3	0.90	0.095	0.40	3.1	0.19	2.4	5.3	0.12	5	4.5	4.6				
STD DS8	Standard	125	0.63	284	0.133	2	0.97	0.099	0.42	3.3	0.23	3.3	5.5	0.20	4	5.6	5.4				
STD DS8	Standard	117	0.62	273	0.105	3	0.91	0.086	0.42	3.1	0.21	1.8	5.7	0.14	5	5.5	5.2				
STD DS8	Standard	111	0.52	244	0.094	2	0.84	0.088	0.39	2.8	0.19	1.9	5.3	0.14	4	4.8	4.7				
STD DS8	Standard	123	0.58	277	0.118	3	0.93	0.102	0.44	2.9	0.17	3.4	5.2	0.16	5	5.8	4.9				
STD DS8	Standard	131	0.65	309	0.127	2	1.00	0.108	0.45	3.3	0.20	2.2	5.6	0.19	5	5.6	5.2				
STD DS8	Standard	122	0.62	257	0.112	1	0.93	0.102	0.44	2.7	0.18	2.4	5.3	0.20	5	4.9	4.7				
STD DS8	Standard																	13.8	114.4	130.1	309
STD OREAS45CA	Standard																	1.0	536.7	20.0	62
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001180.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
1278556	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278556	QC																				
1278565	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278565	QC																				
1278582	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278582	QC																				
Reference Materials																					
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.9	38.8	8.0	635	2.50	23.9	99.5	7.4	73	2.4	5.4	7.0	45	0.72	0.076	16	122	0.60	297	0.123
STD OREAS45CA	Standard	0.3	252.6	88.8	895	16.54	4.1	45.8	6.9	16	0.1	0.1	0.2	203	0.42	0.036	16	732	0.16	165	0.149
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001180.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
1278556	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278556	QC												
1278565	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278565	QC												
1278582	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1278582	QC												
Reference Materials													
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.94	0.096	0.42	3.3	0.18	2.4	5.5	0.15	5	5.2	4.8
STD OREAS45CA	Standard	<20	3.78	0.013	0.07	<0.1	0.03	36.8	<0.1	<0.05	18	0.8	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001180.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001180.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001180.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001180.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 18, 2011
Report Date: September 26, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001181.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #14
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve soil to 230 mesh			WHI
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	320	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278595	Soil	4.2	46.9	13.0	172	0.5	44.8	11.6	352	2.10	13.6	11.5	1.8	49	0.4	3.1	0.3	30	0.46	0.068	9
1278596	Soil	2.2	29.5	13.1	120	1.1	28.1	4.8	117	1.58	27.2	18.3	0.8	83	0.5	3.0	0.3	37	1.56	0.091	6
1278597	Soil	2.5	34.5	13.7	150	1.2	36.1	5.0	121	1.71	39.4	18.9	1.1	74	0.9	4.6	0.3	51	1.55	0.088	7
1278598	Soil	2.7	37.9	12.7	130	1.0	34.9	4.7	139	1.45	33.8	18.4	0.8	71	0.9	4.6	0.3	45	1.82	0.098	6
1278599	Soil	2.4	45.0	13.5	145	1.3	46.4	5.1	215	1.46	32.8	21.8	0.5	84	1.1	5.5	0.3	45	2.43	0.119	9
1278600	Soil	2.6	32.4	11.0	88	0.8	29.2	3.1	159	0.91	17.0	14.5	0.4	79	1.3	3.6	0.2	32	2.36	0.077	6
1278601	Soil	2.0	6.6	5.5	32	<0.1	5.4	1.1	13	0.44	7.8	2.2	0.3	7	<0.1	1.5	0.1	30	0.03	0.023	8
1278602	Soil	2.0	29.2	13.3	155	1.2	43.6	7.7	155	2.69	19.0	7.1	1.3	73	0.7	1.8	0.2	32	1.21	0.118	8
1278603	Soil	1.3	23.3	8.0	50	2.3	20.6	3.6	39	1.17	8.1	6.1	0.6	57	0.1	0.7	0.2	18	0.53	0.083	3
1278604	Soil	1.6	43.2	16.6	55	4.2	26.9	6.3	135	1.69	11.9	14.9	1.0	44	0.2	1.1	0.3	25	0.87	0.094	4
1278605	Soil	5.7	35.2	13.8	89	0.9	24.0	4.6	109	1.80	41.1	12.8	1.8	34	0.6	4.2	0.3	42	0.39	0.068	7
1278606	Soil	7.6	25.5	8.2	54	0.9	14.9	3.3	133	1.14	30.9	15.8	0.4	21	0.3	3.9	0.2	44	0.18	0.064	3
1278607	Soil	7.4	24.3	15.5	87	1.1	19.4	5.4	229	1.93	49.1	12.0	2.0	31	0.4	5.7	0.3	51	0.24	0.062	8
1278608	Soil	4.7	44.4	14.2	133	1.4	37.2	7.3	210	1.96	41.1	13.3	1.3	46	0.8	4.0	0.3	42	0.53	0.079	6
1278609	Soil	1.8	40.0	12.8	131	1.6	47.6	6.4	131	2.17	19.1	9.3	1.1	69	0.7	2.3	0.2	24	1.02	0.077	5
1278610	Soil	5.9	20.0	14.3	91	0.3	23.6	3.1	63	1.76	36.2	6.5	1.9	33	0.5	5.0	0.2	49	0.42	0.033	11
1278611	Soil	5.1	15.2	9.0	68	0.2	16.9	2.4	35	1.02	23.9	3.8	0.5	23	0.4	3.0	0.2	51	0.36	0.023	10
1278612	Soil	9.6	16.6	13.2	120	0.4	26.8	4.5	91	1.93	36.4	3.8	1.5	24	0.2	5.4	0.2	56	0.29	0.041	9
1278613	Soil	6.0	31.5	17.0	120	0.4	30.9	4.3	71	2.44	39.5	5.5	1.2	22	0.4	5.0	0.3	55	0.14	0.057	9
1278614	Soil	3.8	31.9	12.2	81	0.5	14.7	2.4	39	2.11	21.9	2.7	0.7	19	0.2	2.4	0.2	46	0.06	0.056	4
1278615	Soil	18.6	36.9	22.4	224	0.2	40.0	4.6	104	2.08	42.2	2.5	0.6	24	0.5	7.1	0.3	131	0.09	0.060	9
1278616	Soil	4.8	23.0	14.0	68	0.4	14.2	3.2	136	1.57	20.2	4.3	0.6	11	0.1	2.3	0.2	48	0.02	0.068	5
1278617	Soil	3.7	72.7	16.7	187	1.7	51.8	9.2	209	2.24	19.2	10.3	2.1	48	0.5	2.5	0.3	34	0.59	0.072	6
1278618	Soil	4.7	61.8	14.7	192	0.9	47.3	8.7	200	2.49	23.1	8.0	2.0	56	0.6	3.3	0.2	33	0.71	0.077	6
1278619	Soil	1.7	43.5	10.6	170	0.9	36.9	5.3	134	1.99	21.7	9.4	1.0	59	0.5	2.4	0.2	27	1.17	0.075	5
1278620	Soil	2.1	52.6	11.1	164	1.1	42.5	5.4	137	2.09	22.1	11.0	0.8	64	0.6	2.3	0.2	32	1.33	0.075	5
1278621	Soil	8.5	60.2	16.5	351	1.3	64.3	7.5	113	2.00	30.1	8.5	1.6	79	3.5	5.3	0.2	70	0.38	0.131	8
1278622	Soil	3.4	27.2	7.9	97	1.2	20.9	3.6	118	0.97	10.5	8.2	0.5	37	2.3	1.7	0.1	49	0.16	0.060	3
1278623	Soil	6.7	65.0	12.4	235	1.5	44.8	7.8	387	1.84	16.9	7.1	1.0	34	4.1	3.0	0.2	76	0.17	0.081	8
1278624	Soil	6.9	124.4	18.7	304	2.0	61.6	8.1	194	2.33	18.1	9.5	1.8	54	6.4	2.9	0.3	96	0.22	0.102	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278595	Soil	21	0.34	509	0.002	2	0.93	0.006	0.05	<0.1	0.51	1.8	0.1	0.07	2	1.3	<0.2
1278596	Soil	17	0.17	595	0.001	4	0.77	0.007	0.05	<0.1	1.45	1.6	0.2	0.13	2	3.0	<0.2
1278597	Soil	18	0.16	591	0.001	3	0.72	0.005	0.06	0.1	1.68	2.1	0.2	0.10	2	2.0	<0.2
1278598	Soil	15	0.12	723	0.002	3	0.65	0.006	0.04	0.2	1.89	1.6	0.3	0.13	2	2.7	<0.2
1278599	Soil	19	0.09	829	0.001	5	0.67	0.007	0.04	0.1	2.46	1.3	0.3	0.15	2	2.5	<0.2
1278600	Soil	12	0.07	559	0.003	4	0.52	0.009	0.04	0.1	1.45	0.8	0.3	0.16	1	2.6	<0.2
1278601	Soil	6	0.02	80	0.004	2	0.39	0.006	0.02	0.1	0.19	0.3	0.1	<0.05	3	<0.5	<0.2
1278602	Soil	21	0.15	567	0.001	4	0.77	0.006	0.05	<0.1	0.70	2.8	0.1	0.09	2	1.8	<0.2
1278603	Soil	12	0.14	732	<0.001	2	0.74	0.009	0.04	<0.1	0.69	2.1	0.2	0.09	2	1.4	<0.2
1278604	Soil	14	0.16	618	0.001	3	0.93	0.008	0.05	<0.1	1.32	3.6	0.2	0.12	2	2.9	<0.2
1278605	Soil	15	0.15	711	<0.001	2	0.71	0.004	0.05	0.2	1.34	1.9	0.2	<0.05	2	2.0	<0.2
1278606	Soil	10	0.06	444	0.001	4	0.49	0.016	0.05	0.1	0.68	1.1	0.3	<0.05	2	1.4	<0.2
1278607	Soil	17	0.18	635	<0.001	2	0.72	0.003	0.05	0.2	1.75	1.5	0.2	<0.05	2	2.3	<0.2
1278608	Soil	18	0.17	817	<0.001	2	0.81	0.005	0.07	0.2	1.08	2.6	0.3	0.07	2	2.2	<0.2
1278609	Soil	19	0.19	472	<0.001	4	0.86	0.006	0.06	<0.1	1.04	3.5	0.2	0.09	2	3.0	<0.2
1278610	Soil	11	0.09	309	0.005	2	0.51	0.003	0.05	0.2	0.59	1.2	0.2	<0.05	2	1.8	<0.2
1278611	Soil	8	0.03	304	0.008	1	0.35	0.006	0.03	0.2	0.19	0.5	0.1	<0.05	3	0.9	<0.2
1278612	Soil	10	0.07	287	0.002	<1	0.43	0.003	0.04	0.1	0.18	0.9	0.2	<0.05	2	1.5	<0.2
1278613	Soil	15	0.11	464	0.003	1	0.63	0.003	0.05	0.1	0.29	1.4	0.2	<0.05	3	1.8	<0.2
1278614	Soil	13	0.03	148	0.002	2	0.38	0.008	0.05	<0.1	0.10	1.0	0.1	<0.05	3	2.1	<0.2
1278615	Soil	15	0.05	241	0.002	3	0.43	0.003	0.07	0.2	0.12	1.0	0.5	<0.05	3	2.5	<0.2
1278616	Soil	14	0.04	137	0.002	2	0.54	0.005	0.04	0.1	0.19	0.7	0.2	<0.05	3	1.2	<0.2
1278617	Soil	21	0.25	624	0.001	2	0.98	0.008	0.06	<0.1	0.58	2.4	0.2	0.06	2	1.7	<0.2
1278618	Soil	20	0.27	1419	0.002	3	0.85	0.007	0.06	<0.1	0.37	1.9	0.2	0.08	2	1.9	<0.2
1278619	Soil	20	0.23	614	0.001	5	0.92	0.007	0.06	<0.1	1.00	2.0	0.2	0.12	2	2.6	<0.2
1278620	Soil	22	0.27	547	<0.001	4	0.90	0.004	0.07	<0.1	0.94	2.0	0.1	0.10	2	2.5	<0.2
1278621	Soil	20	0.13	1184	<0.001	3	0.67	0.003	0.06	<0.1	1.31	2.9	0.4	0.13	2	5.7	<0.2
1278622	Soil	11	0.05	1182	0.002	2	0.51	0.016	0.05	<0.1	0.74	1.3	0.3	<0.05	1	1.3	<0.2
1278623	Soil	19	0.11	951	0.003	2	0.84	0.006	0.08	0.1	0.36	1.8	0.5	<0.05	3	1.4	<0.2
1278624	Soil	27	0.18	1419	0.003	3	1.34	0.004	0.09	0.2	0.74	3.3	0.6	<0.05	4	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278625	Soil	2.4	46.9	11.8	105	1.3	29.7	3.8	114	1.32	9.5	6.4	0.9	75	1.4	1.4	0.2	49	0.39	0.088	6
1278626	Soil	2.1	71.1	9.6	197	1.0	44.2	10.2	364	1.80	7.9	7.7	0.8	99	1.4	1.2	0.2	32	1.18	0.090	6
1278627	Soil	1.8	50.3	10.9	127	0.9	43.4	8.3	219	2.38	8.9	5.9	1.2	76	1.0	1.0	0.2	33	1.26	0.062	6
1278628	Soil	4.5	35.2	24.7	192	0.3	32.4	9.0	329	5.04	26.6	4.8	0.8	26	1.5	2.3	0.2	51	0.23	0.096	5
1278629	Soil	4.5	31.2	13.1	114	0.4	21.2	4.3	106	2.45	13.9	2.1	0.6	23	0.3	1.8	0.3	47	0.04	0.047	6
1278630	Soil	4.8	34.0	14.6	119	0.5	23.4	4.5	117	3.26	19.2	8.3	1.6	9	0.4	2.0	0.3	67	0.02	0.106	6
1278631	Soil	2.6	65.4	12.4	121	1.0	33.8	5.6	223	2.16	9.8	11.6	0.8	106	0.8	1.2	0.3	29	1.21	0.083	4
1278632	Soil	8.6	42.4	15.6	108	0.5	22.4	3.6	83	1.86	17.5	4.9	0.9	21	0.2	2.4	0.3	56	0.04	0.047	7
1278633	Soil	9.3	19.3	16.2	116	0.3	24.0	4.1	97	2.38	23.8	2.4	1.3	15	0.3	3.7	0.2	77	0.02	0.036	7
1278634	Soil	10.6	33.5	20.9	176	0.5	35.2	7.6	214	2.64	36.2	5.3	0.6	40	0.5	5.3	0.3	74	0.06	0.098	7
1278635	Soil	8.1	24.1	18.4	153	0.4	27.7	5.5	146	2.21	26.0	4.4	1.5	38	0.5	4.1	0.3	75	0.10	0.078	8
1278636	Soil	8.2	71.0	29.9	276	2.9	56.8	9.3	337	3.29	27.9	6.1	1.5	80	2.2	5.0	0.3	140	0.37	0.136	10
1278637	Soil	7.8	35.3	18.1	208	0.6	38.9	6.8	208	2.42	24.1	4.3	1.1	49	1.4	4.5	0.2	72	0.21	0.114	8
1278638	Soil	8.2	14.0	17.9	95	0.3	19.1	3.0	64	1.81	22.1	1.2	0.8	21	0.4	3.2	0.3	73	0.05	0.038	8
1278639	Soil	9.5	31.6	16.3	200	0.7	37.5	7.3	142	2.39	26.1	3.2	1.9	61	0.9	4.3	0.2	60	0.50	0.095	7
1278640	Soil	11.1	31.6	19.7	229	1.4	37.8	6.0	104	1.96	28.4	4.3	1.3	76	1.5	8.9	0.3	78	0.42	0.153	6
1278681	Soil	47.0	72.1	14.9	162	0.3	152.1	8.1	319	3.19	33.7	1.4	1.2	211	1.6	4.9	0.1	57	6.23	0.090	11
1278682	Soil	24.5	22.4	5.7	99	0.2	43.7	3.3	176	1.03	9.6	<0.5	0.4	26	1.9	1.6	0.2	20	0.61	0.091	4
1278683	Soil	10.7	72.7	9.4	363	1.0	103.6	9.9	722	2.36	19.9	3.9	1.2	17	5.3	4.4	0.2	32	0.41	0.104	11
1278684	Soil	4.6	51.5	13.5	185	0.4	66.1	8.0	56	2.24	16.7	1.6	1.3	2	<0.1	4.2	0.2	26	0.02	0.060	10
1278685	Soil	9.0	44.8	12.9	296	0.5	100.3	13.3	149	3.59	74.4	1.4	1.1	8	1.1	6.5	0.2	67	0.07	0.173	13
1278686	Soil	21.1	26.4	16.9	345	0.2	58.5	9.8	349	3.10	43.0	2.0	0.7	12	1.0	7.0	0.2	117	0.07	0.117	13
1278687	Soil	33.4	41.8	19.0	655	0.6	103.1	8.8	162	3.61	66.6	2.4	0.5	5	1.3	11.2	0.2	167	0.03	0.130	8
1278688	Soil	24.0	56.5	19.2	460	0.6	89.6	10.2	378	3.31	41.0	2.0	0.7	18	2.5	8.1	0.2	115	0.15	0.153	10
1278689	Soil	16.1	27.3	10.2	344	0.4	57.1	5.9	78	2.02	30.4	2.2	0.6	14	1.2	4.4	0.2	74	0.09	0.127	12
1278690	Soil	5.9	83.5	32.3	64	2.7	35.9	5.5	119	3.59	117.5	3.4	0.3	40	0.3	4.2	0.3	77	0.03	0.167	5
1278691	Soil	5.2	41.8	31.1	49	2.1	24.3	4.5	162	2.64	106.9	5.1	0.6	43	0.2	5.2	0.2	41	0.06	0.165	4
1278692	Soil	3.8	22.3	42.8	22	1.7	10.1	1.8	54	1.27	32.2	2.7	0.2	26	0.1	2.6	0.2	38	0.02	0.055	3
1278693	Soil	2.2	11.5	24.4	13	1.1	4.7	0.8	33	0.80	18.5	1.1	0.1	17	<0.1	1.2	0.2	30	0.01	0.080	2
1278694	Soil	3.3	19.8	26.3	16	0.7	7.8	1.2	56	0.78	14.9	1.8	0.1	29	<0.1	1.8	0.2	30	0.02	0.068	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278625	Soil	17	0.13	1161	0.002	3	0.84	0.008	0.06	<0.1	0.42	1.9	0.4	<0.05	2	1.8	<0.2
1278626	Soil	17	0.20	1356	0.002	2	0.90	0.007	0.04	<0.1	0.30	2.4	0.1	0.11	2	2.0	<0.2
1278627	Soil	23	0.25	939	0.002	2	0.90	0.006	0.04	<0.1	0.18	2.7	<0.1	0.09	2	1.9	<0.2
1278628	Soil	21	0.07	1909	0.005	2	0.81	0.004	0.04	<0.1	0.06	1.3	0.1	0.07	3	2.2	<0.2
1278629	Soil	16	0.13	275	0.003	<1	0.78	0.007	0.05	<0.1	0.02	1.0	0.2	<0.05	3	1.2	<0.2
1278630	Soil	17	0.11	232	0.003	1	0.73	0.004	0.04	<0.1	0.03	1.2	0.2	<0.05	4	1.2	<0.2
1278631	Soil	21	0.25	1103	0.002	3	0.99	0.006	0.03	<0.1	0.30	2.0	0.1	0.14	2	2.1	<0.2
1278632	Soil	12	0.07	223	0.004	2	0.61	0.003	0.04	0.2	0.07	1.0	0.2	0.06	3	1.4	<0.2
1278633	Soil	11	0.09	206	0.004	2	0.65	0.003	0.03	0.2	0.03	1.0	0.2	<0.05	3	1.7	<0.2
1278634	Soil	14	0.08	558	0.002	2	0.50	0.003	0.05	0.2	0.13	1.0	0.3	0.07	2	2.6	<0.2
1278635	Soil	13	0.12	1029	0.003	<1	0.66	0.003	0.04	0.2	0.10	1.2	0.3	0.06	2	2.0	<0.2
1278636	Soil	28	0.11	1904	0.002	2	1.44	0.005	0.09	0.2	1.34	3.1	0.5	0.06	4	2.5	<0.2
1278637	Soil	16	0.15	1330	0.002	1	0.78	0.004	0.05	0.2	0.25	1.5	0.3	0.05	2	2.1	<0.2
1278638	Soil	8	0.04	174	0.006	<1	0.43	0.003	0.04	0.2	0.03	0.6	0.2	<0.05	3	1.2	<0.2
1278639	Soil	18	0.15	893	0.003	2	0.67	0.004	0.04	0.1	0.33	2.0	0.2	0.06	2	2.0	<0.2
1278640	Soil	17	0.08	1457	0.001	2	0.49	0.003	0.05	0.2	0.47	1.4	0.5	0.06	2	2.6	<0.2
1278681	Soil	15	3.21	346	0.002	4	0.23	0.008	0.03	0.1	0.43	3.3	1.1	<0.05	<1	2.7	<0.2
1278682	Soil	4	0.07	180	0.004	1	0.46	0.015	0.02	<0.1	0.09	1.1	0.6	0.05	1	0.9	<0.2
1278683	Soil	12	0.09	519	0.002	2	0.54	0.006	0.03	<0.1	0.38	2.1	0.2	0.06	1	1.5	<0.2
1278684	Soil	10	0.01	57	0.001	1	0.24	<0.001	0.03	<0.1	0.05	1.3	0.1	<0.05	<1	2.0	<0.2
1278685	Soil	25	0.04	356	0.002	1	0.37	0.001	0.04	<0.1	0.13	1.8	0.2	<0.05	1	2.1	<0.2
1278686	Soil	22	0.19	203	0.007	<1	0.85	0.003	0.04	0.2	0.12	1.6	0.3	<0.05	3	1.7	<0.2
1278687	Soil	23	0.04	166	0.002	3	0.46	0.002	0.03	<0.1	0.13	1.0	0.4	<0.05	1	2.7	<0.2
1278688	Soil	16	0.05	590	0.002	2	0.47	0.003	0.04	<0.1	0.26	2.1	0.5	<0.05	1	2.6	<0.2
1278689	Soil	20	0.05	514	0.002	2	0.62	0.002	0.04	<0.1	0.14	1.3	0.3	<0.05	2	1.2	<0.2
1278690	Soil	22	0.04	307	0.005	1	0.57	0.003	0.07	0.2	0.12	1.4	0.2	0.11	3	2.8	<0.2
1278691	Soil	14	0.08	194	0.006	<1	0.62	0.006	0.06	0.1	0.06	1.6	0.2	0.11	2	4.0	<0.2
1278692	Soil	11	0.04	160	0.003	<1	0.36	0.003	0.06	<0.1	0.07	0.7	0.3	0.09	2	5.4	<0.2
1278693	Soil	9	0.02	128	0.002	<1	0.42	0.005	0.03	<0.1	0.05	0.5	0.2	<0.05	2	1.5	<0.2
1278694	Soil	8	0.02	264	0.002	<1	0.31	0.005	0.04	<0.1	0.18	0.3	0.2	<0.05	2	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278695	Soil	5.1	28.9	24.4	64	0.4	15.3	3.1	90	1.85	36.2	1.2	0.1	27	0.1	2.5	0.3	66	0.02	0.107	5
1278696	Soil	13.7	18.9	74.5	42	1.5	9.5	2.0	52	2.01	258.5	2.3	0.1	25	<0.1	4.4	1.8	61	0.02	0.125	4
1278697	Soil	2.9	22.6	26.6	97	0.1	21.9	8.6	219	2.83	64.3	1.2	0.6	16	0.1	2.1	0.4	23	0.01	0.087	3
1278698	Soil	2.0	16.9	17.7	68	0.2	14.9	4.7	79	2.09	46.8	<0.5	0.2	10	0.2	1.5	0.3	20	0.02	0.078	2
1278699	Soil	1.5	13.3	14.1	56	<0.1	11.4	3.5	62	1.56	36.4	0.7	0.4	7	0.3	1.0	0.2	13	0.01	0.063	2
1278700	Soil	1.6	13.2	27.2	61	0.1	12.2	4.1	117	1.49	203.4	<0.5	0.2	12	0.3	1.9	0.6	14	0.01	0.070	2
1278701	Soil	1.3	9.9	7.7	53	<0.1	8.5	2.7	54	0.87	22.6	<0.5	0.1	11	0.3	0.8	0.2	14	0.10	0.058	2
1278702	Soil	1.5	25.2	16.1	108	0.3	53.8	10.6	412	3.20	190.7	1.0	0.8	28	0.2	2.6	0.4	12	0.31	0.070	2
1278703	Soil	2.5	23.3	27.0	104	0.2	23.1	9.8	266	3.18	160.2	1.1	0.5	10	0.3	3.8	0.5	26	0.01	0.074	3
1278704	Soil	0.9	7.8	6.6	17	0.2	5.3	1.6	29	0.59	21.9	0.8	<0.1	5	0.2	0.7	<0.1	7	0.01	0.050	1
1278705	Soil	3.3	22.8	10.4	57	0.3	16.0	4.5	152	1.81	55.5	1.2	0.2	7	0.2	1.8	0.2	31	0.01	0.056	3
1278706	Soil	5.2	55.9	29.6	47	1.6	28.9	5.7	193	3.28	65.6	3.7	0.4	28	0.1	5.5	0.3	53	0.02	0.118	5
1278707	Soil	1.2	15.6	5.1	9	1.3	4.6	1.0	24	0.51	4.9	<0.5	<0.1	5	<0.1	0.5	<0.1	16	0.02	0.032	1
1278708	Soil	3.6	36.2	38.3	25	1.6	26.9	4.2	91	2.69	38.5	2.3	0.3	31	0.2	3.4	0.2	47	0.03	0.097	3
1278709	Soil	3.2	51.4	12.4	70	0.9	54.3	10.8	1243	5.54	16.2	2.8	1.2	11	0.3	2.0	0.2	75	0.31	0.067	7
1278710	Soil	1.0	16.5	10.7	47	0.4	8.8	2.7	33	2.64	10.9	0.9	0.9	11	<0.1	0.5	0.2	32	0.01	0.041	2
1278711	Soil	1.1	17.0	13.0	48	0.1	7.8	2.9	35	2.06	10.9	1.6	0.5	11	<0.1	0.5	0.2	37	0.01	0.059	2
1278712	Soil	1.2	15.0	12.0	46	0.3	7.5	2.8	39	2.09	13.8	1.2	0.5	9	<0.1	0.6	0.2	36	<0.01	0.057	2
1278713	Soil	1.4	14.1	10.4	49	0.3	8.6	2.9	47	1.77	9.9	0.5	1.1	12	<0.1	0.6	0.2	37	0.01	0.030	3
1278714	Soil	2.0	16.7	15.9	58	0.2	10.1	3.7	66	2.55	14.9	1.8	0.8	17	<0.1	0.8	0.2	46	0.01	0.074	3
1278715	Soil	2.0	19.3	17.9	61	0.3	12.4	4.5	100	3.10	18.9	2.0	1.0	17	0.1	0.8	0.3	60	0.02	0.115	3
1278716	Soil	1.3	15.4	10.2	40	0.4	9.7	3.1	51	1.43	8.5	2.1	0.5	13	<0.1	0.5	0.2	27	0.02	0.059	3
1278717	Soil	2.5	33.8	22.3	85	0.6	24.6	6.3	115	3.47	19.8	3.4	1.5	24	0.3	1.1	0.3	51	0.03	0.104	5
1278718	Soil	1.6	18.4	12.9	52	0.4	13.1	3.7	68	1.90	13.6	2.5	0.4	14	0.1	0.7	0.2	35	0.02	0.067	3
1278719	Soil	2.5	36.7	18.9	70	0.6	20.3	7.0	204	2.10	12.7	4.3	1.0	23	0.4	0.9	0.2	44	0.05	0.095	8
1278720	Soil	1.8	26.6	15.3	121	0.8	34.1	12.4	334	2.16	10.1	3.3	1.4	65	0.7	0.6	0.2	38	0.17	0.075	4
1278721	Soil	1.8	21.8	15.9	68	0.7	21.5	6.4	79	2.10	11.2	5.1	0.8	44	0.1	0.5	0.3	38	0.13	0.089	3
1278722	Soil	2.0	24.8	15.8	104	0.6	30.5	12.3	532	2.22	11.3	3.8	1.1	73	0.2	0.6	0.2	38	0.32	0.071	4
1278723	Soil	3.7	31.5	18.4	146	0.5	36.3	17.5	453	2.88	15.1	3.6	2.1	41	0.5	1.3	0.3	48	0.15	0.076	7
1278724	Soil	3.4	30.3	18.2	144	0.2	34.3	20.1	461	3.13	16.2	3.7	2.3	32	0.6	1.2	0.3	45	0.13	0.071	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278695	Soil	12	0.03	129	0.004	<1	0.58	0.005	0.04	0.1	0.03	0.3	0.2	<0.05	4	1.6	<0.2
1278696	Soil	12	0.02	198	0.001	<1	0.45	0.004	0.09	<0.1	0.21	0.5	0.8	0.13	3	5.7	<0.2
1278697	Soil	11	0.06	102	0.002	<1	0.54	0.002	0.06	<0.1	0.04	1.0	0.3	<0.05	2	0.8	<0.2
1278698	Soil	8	0.02	78	0.001	2	0.39	0.002	0.06	<0.1	0.03	0.4	0.1	<0.05	2	<0.5	<0.2
1278699	Soil	6	0.02	75	0.001	<1	0.50	0.004	0.04	<0.1	0.02	0.7	0.1	<0.05	1	<0.5	<0.2
1278700	Soil	5	0.02	127	0.001	1	0.36	0.004	0.04	<0.1	0.05	0.4	0.2	<0.05	2	<0.5	<0.2
1278701	Soil	4	0.02	115	0.002	<1	0.30	0.009	0.04	<0.1	0.02	0.3	<0.1	<0.05	1	<0.5	<0.2
1278702	Soil	7	0.09	244	<0.001	2	0.54	0.005	0.05	<0.1	0.26	3.0	0.1	<0.05	1	0.9	<0.2
1278703	Soil	10	0.03	122	0.002	2	0.55	0.003	0.05	<0.1	0.05	1.4	0.1	<0.05	2	0.6	<0.2
1278704	Soil	3	0.01	58	0.003	<1	0.25	0.012	0.02	<0.1	0.06	0.4	0.1	<0.05	1	<0.5	<0.2
1278705	Soil	8	0.01	77	0.003	1	0.35	0.006	0.03	<0.1	0.03	0.4	<0.1	<0.05	2	0.9	<0.2
1278706	Soil	15	0.07	162	0.006	<1	0.85	0.005	0.06	0.1	0.07	1.2	0.3	0.10	3	3.0	<0.2
1278707	Soil	5	<0.01	37	0.004	<1	0.26	0.012	0.02	<0.1	0.03	0.2	<0.1	<0.05	1	<0.5	<0.2
1278708	Soil	11	0.01	175	0.004	1	0.40	0.010	0.06	<0.1	0.03	1.2	0.2	0.17	2	2.4	<0.2
1278709	Soil	24	0.15	313	0.003	1	0.80	0.002	0.04	<0.1	0.08	4.1	0.1	<0.05	2	1.5	<0.2
1278710	Soil	14	0.06	127	<0.001	<1	0.74	0.006	0.04	<0.1	0.04	1.1	<0.1	<0.05	3	0.5	<0.2
1278711	Soil	8	0.03	120	<0.001	1	0.60	0.003	0.03	<0.1	0.01	0.9	<0.1	<0.05	3	0.9	<0.2
1278712	Soil	9	0.03	68	<0.001	2	0.50	0.004	0.03	<0.1	0.02	0.7	<0.1	<0.05	3	0.8	<0.2
1278713	Soil	9	0.04	107	0.001	<1	0.70	0.004	0.02	<0.1	0.02	1.1	<0.1	<0.05	3	<0.5	<0.2
1278714	Soil	12	0.06	151	0.001	<1	0.66	0.003	0.04	<0.1	0.02	1.2	<0.1	<0.05	4	0.8	<0.2
1278715	Soil	17	0.06	227	0.001	1	0.84	0.006	0.06	<0.1	0.04	1.7	0.1	<0.05	4	<0.5	<0.2
1278716	Soil	10	0.06	208	0.002	<1	0.63	0.014	0.05	<0.1	0.06	1.1	<0.1	<0.05	2	0.6	<0.2
1278717	Soil	22	0.15	612	0.001	1	1.31	0.006	0.08	<0.1	0.12	3.0	0.2	0.05	4	1.6	<0.2
1278718	Soil	12	0.07	347	0.002	1	0.72	0.011	0.05	<0.1	0.06	1.3	<0.1	<0.05	3	<0.5	<0.2
1278719	Soil	18	0.09	482	0.002	1	1.08	0.006	0.08	<0.1	0.10	1.8	0.2	<0.05	4	1.3	<0.2
1278720	Soil	22	0.21	1263	0.001	1	1.30	0.008	0.09	<0.1	0.18	3.1	0.1	0.09	4	1.7	<0.2
1278721	Soil	16	0.16	1064	0.001	1	1.15	0.014	0.08	<0.1	0.15	2.7	0.2	0.10	3	1.0	<0.2
1278722	Soil	20	0.22	1298	0.001	1	1.12	0.010	0.08	<0.1	0.13	2.8	0.1	0.10	3	1.2	<0.2
1278723	Soil	24	0.24	1177	0.002	2	1.19	0.006	0.09	<0.1	0.15	3.5	0.2	0.09	3	1.6	<0.2
1278724	Soil	21	0.21	712	0.002	1	1.11	0.005	0.09	<0.1	0.07	3.1	0.1	0.06	3	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278725	Soil	5.3	35.8	15.1	150	0.4	38.0	8.8	128	2.52	15.7	2.3	2.0	41	0.8	1.9	0.2	49	0.29	0.080	7
1278726	Soil	6.9	28.5	11.6	145	0.3	34.0	6.7	99	1.92	13.1	3.2	1.3	31	0.6	2.1	0.2	51	0.25	0.076	7
1278727	Soil	8.8	35.8	21.2	188	0.6	46.6	9.9	119	2.69	19.2	2.9	1.8	23	0.5	3.4	0.2	57	0.07	0.079	8
1278728	Soil	1.4	13.3	13.0	147	0.2	20.6	12.2	259	2.45	16.3	1.0	1.1	9	0.3	0.6	0.2	39	0.04	0.055	3
1278729	Soil	0.6	5.5	4.0	37	0.1	6.0	2.8	63	0.71	3.0	0.8	<0.1	5	0.2	0.2	<0.1	13	0.03	0.030	2
1278730	Soil	2.7	22.3	16.1	112	<0.1	24.8	7.9	104	2.87	19.1	1.8	1.6	16	0.2	1.1	0.3	48	0.02	0.048	6
1279731	Soil	5.8	12.3	30.2	72	0.6	12.5	2.2	47	1.35	34.4	5.9	1.2	46	0.5	7.3	0.3	23	0.07	0.026	7
1279732	Soil	6.2	15.6	32.3	94	0.4	16.5	3.1	62	2.11	40.6	6.9	0.7	57	0.4	7.1	0.4	28	0.04	0.042	7
1279733	Soil	14.3	39.0	22.8	173	0.8	45.5	4.9	76	1.79	23.9	3.4	0.3	14	0.3	3.6	0.3	82	0.04	0.077	15
1279734	Soil	7.3	23.2	17.4	120	2.3	24.9	4.4	118	1.94	18.2	5.7	0.4	17	0.5	2.2	0.3	86	0.08	0.135	16
1279735	Soil	22.5	90.6	23.1	332	1.6	68.5	8.3	119	2.79	32.9	2.9	0.6	10	0.7	6.1	0.3	115	0.02	0.125	13
1279736	Soil	15.4	42.2	26.3	271	0.6	56.4	7.3	504	3.89	31.7	3.0	0.6	21	0.8	5.0	0.3	105	0.14	0.307	14
1279737	Soil	12.4	34.8	21.6	162	0.8	35.9	4.7	98	2.15	32.0	5.5	0.4	30	0.5	4.7	0.4	81	0.07	0.120	12
1279738	Soil	6.8	18.3	10.2	89	0.3	19.8	3.4	62	1.39	21.8	1.1	0.3	14	0.7	2.7	0.2	50	0.02	0.046	15
1279739	Soil	7.9	24.3	12.3	121	0.2	30.8	5.5	72	1.83	37.9	2.7	1.7	15	0.2	5.1	0.3	58	0.01	0.030	15
1279740	Soil	11.1	33.1	24.4	194	1.6	42.8	6.5	113	3.27	65.4	8.6	0.7	32	0.3	7.8	0.4	84	0.06	0.165	13
1279741	Soil	6.4	40.8	46.9	131	3.3	27.1	5.4	85	4.12	25.6	7.9	1.4	48	0.3	5.3	0.3	39	0.03	0.158	8
1279742	Soil	11.9	115.7	29.8	372	6.2	119.5	18.3	346	5.29	23.2	9.5	6.0	42	1.9	4.4	0.4	38	0.38	0.186	21
1279743	Soil	94.5	40.7	11.4	297	<0.1	215.7	10.1	145	2.41	38.2	1.7	1.1	7	1.6	8.3	0.2	86	0.05	0.057	15
1279744	Soil	48.0	46.5	7.4	954	0.9	185.3	5.8	360	1.57	42.2	4.0	0.5	48	15.7	11.0	0.1	145	1.05	0.096	7
1279745	Soil	60.1	38.9	16.7	704	0.2	150.6	7.6	62	2.94	100.1	3.5	0.7	11	0.8	60.5	0.2	337	<0.01	0.063	16
1279746	Soil	147.0	55.7	14.6	488	2.3	150.2	2.5	21	1.97	93.4	3.6	0.3	18	1.5	42.0	0.2	918	0.01	0.110	13
1279747	Soil	73.8	39.4	8.9	315	3.1	71.8	2.8	26	1.72	42.1	1.2	0.2	13	0.4	23.4	0.2	358	<0.01	0.056	12
1279748	Soil	116.4	58.2	20.1	387	4.1	67.8	2.3	26	2.30	59.2	2.0	0.2	52	1.4	30.2	0.4	1015	0.01	0.124	18
1279749	Soil	310.7	78.9	18.8	1304	2.6	253.4	6.7	30	4.87	232.1	2.2	1.9	86	1.5	85.4	0.4	1270	0.02	0.124	29
1279750	Soil	3.5	18.5	13.1	73	0.4	18.2	3.2	109	2.31	7.6	1.1	1.3	4	0.2	0.7	0.2	20	<0.01	0.039	6
1279761	Soil	8.2	42.8	30.1	115	2.1	25.7	4.5	84	2.29	188.8	66.0	1.5	52	0.6	24.0	0.6	48	0.23	0.103	12
1279762	Soil	2.5	45.8	13.3	166	1.4	48.6	7.4	361	2.46	42.9	14.1	1.2	61	1.2	3.5	0.2	44	1.09	0.092	7
1279763	Soil	1.7	36.8	16.6	96	0.8	29.7	4.6	61	1.60	21.5	12.5	1.9	74	1.3	2.3	0.3	53	1.19	0.055	7
1279764	Soil	2.1	33.3	14.3	130	0.9	33.4	5.4	99	2.00	30.3	10.1	1.7	52	0.9	3.3	0.2	42	0.72	0.078	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278725	Soil	19	0.20	1183	0.002	1	0.89	0.005	0.09	<0.1	0.11	3.4	0.2	0.09	3	1.2	<0.2
1278726	Soil	14	0.14	1453	0.002	1	0.71	0.007	0.08	<0.1	0.10	2.0	0.2	0.08	2	0.9	<0.2
1278727	Soil	17	0.15	1317	0.002	2	0.91	0.003	0.08	<0.1	0.11	2.4	0.3	0.09	2	1.3	<0.2
1278728	Soil	20	0.22	357	0.002	1	1.45	0.010	0.10	<0.1	0.01	1.7	0.1	<0.05	5	<0.5	<0.2
1278729	Soil	6	0.06	126	0.005	2	0.33	0.015	0.04	<0.1	0.01	0.2	<0.1	<0.05	1	<0.5	<0.2
1278730	Soil	18	0.14	286	0.002	2	0.98	0.004	0.08	<0.1	0.02	2.1	0.1	0.07	4	0.7	<0.2
1279731	Soil	5	0.02	506	<0.001	4	0.18	0.007	0.12	0.4	20.95	1.2	0.8	0.24	<1	2.0	<0.2
1279732	Soil	6	0.01	565	<0.001	5	0.24	0.006	0.13	0.2	9.47	1.3	0.7	0.21	<1	2.4	<0.2
1279733	Soil	18	0.05	190	0.006	1	0.58	0.003	0.08	0.1	0.12	0.5	0.5	0.08	3	1.4	<0.2
1279734	Soil	22	0.22	255	0.011	1	1.16	0.004	0.09	0.1	0.18	0.6	0.4	0.06	5	0.8	<0.2
1279735	Soil	12	0.05	322	0.005	2	0.68	0.002	0.10	<0.1	0.07	1.1	0.4	0.09	3	2.0	<0.2
1279736	Soil	16	0.08	344	0.008	2	0.85	0.003	0.09	0.2	0.13	1.1	0.5	0.08	4	1.7	<0.2
1279737	Soil	14	0.08	266	0.007	2	0.64	0.005	0.09	0.2	0.44	0.7	0.6	0.14	3	1.8	<0.2
1279738	Soil	9	0.04	436	0.008	1	0.53	0.004	0.06	0.1	0.04	0.5	0.3	<0.05	3	0.8	<0.2
1279739	Soil	8	0.03	420	0.008	<1	0.46	0.002	0.05	0.2	0.05	0.9	0.4	<0.05	3	1.3	<0.2
1279740	Soil	16	0.07	480	0.004	2	1.08	0.003	0.08	0.2	0.57	1.0	0.5	0.07	3	2.4	<0.2
1279741	Soil	7	0.02	149	0.004	1	0.63	0.011	0.33	0.1	0.36	1.3	0.5	0.76	2	6.0	<0.2
1279742	Soil	14	0.06	2238	0.001	4	0.82	0.002	0.09	<0.1	0.91	9.0	0.4	0.06	<1	3.7	<0.2
1279743	Soil	18	0.04	204	0.001	3	0.54	0.002	0.05	0.6	0.39	1.7	1.6	<0.05	2	2.1	<0.2
1279744	Soil	24	0.12	564	0.003	3	0.56	0.012	0.05	0.3	0.87	2.4	2.0	0.12	1	2.4	<0.2
1279745	Soil	17	0.04	95	0.003	1	0.44	0.002	0.07	0.5	0.13	0.9	1.5	<0.05	3	5.6	<0.2
1279746	Soil	48	0.06	222	0.003	5	0.63	0.008	0.13	0.7	1.17	0.5	3.7	<0.05	4	18.6	0.3
1279747	Soil	16	0.03	101	0.005	2	0.46	0.006	0.06	0.5	0.07	0.3	1.7	<0.05	3	14.5	<0.2
1279748	Soil	38	0.05	250	0.002	4	0.73	0.005	0.15	0.7	0.18	0.3	4.9	0.13	5	12.9	0.3
1279749	Soil	32	0.04	192	0.006	2	0.68	0.006	0.12	2.1	0.13	2.0	6.9	0.08	4	28.3	0.4
1279750	Soil	10	0.10	1013	0.001	<1	0.68	0.003	0.03	<0.1	0.02	1.4	0.1	<0.05	2	0.6	<0.2
1279761	Soil	16	0.07	769	0.001	3	0.53	0.005	0.08	0.4	13.74	1.9	0.8	0.11	2	8.2	0.2
1279762	Soil	20	0.15	586	<0.001	3	0.87	0.006	0.07	<0.1	1.65	3.3	0.3	0.11	2	3.1	<0.2
1279763	Soil	16	0.08	633	0.001	1	0.73	0.004	0.05	<0.1	1.29	2.8	0.2	0.14	2	2.8	<0.2
1279764	Soil	17	0.14	629	<0.001	3	0.71	0.011	0.07	<0.1	1.14	3.0	0.2	0.09	2	2.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279765	Soil	3.7	43.4	18.9	107	1.1	33.0	8.0	176	2.70	21.7	3.3	1.2	44	0.2	2.0	0.2	32	0.05	0.073	4
1279766	Soil	3.6	47.2	22.2	134	1.7	45.5	10.7	217	3.23	21.6	3.6	1.2	57	0.3	1.9	0.3	31	0.17	0.082	4
1279767	Soil	3.7	54.9	22.2	215	2.3	75.4	14.7	245	4.07	21.1	4.5	1.9	61	0.7	2.0	0.2	32	0.33	0.113	5
1279768	Soil	3.0	44.7	19.8	194	3.0	69.7	10.9	181	3.68	16.0	6.1	2.0	61	0.6	1.6	0.2	30	0.69	0.106	8
1279769	Soil	1.9	30.7	11.9	120	1.9	43.4	6.5	148	2.72	10.6	4.7	1.0	62	0.4	1.1	0.1	27	1.12	0.105	7
1279770	Soil	1.3	24.6	11.2	147	1.4	40.4	5.4	186	1.92	16.7	7.5	0.7	67	1.0	1.7	0.2	40	1.50	0.144	12
1279771	Soil	1.4	17.3	6.2	124	0.8	28.7	3.6	102	1.15	8.0	4.1	0.4	53	0.6	1.1	<0.1	25	1.07	0.101	5
1279772	Soil	1.5	29.9	11.1	116	1.5	39.4	5.5	171	1.75	13.2	6.6	0.8	66	0.3	1.4	0.2	38	1.15	0.155	10
1279773	Soil	2.5	22.7	15.3	108	1.1	29.6	5.3	169	1.85	24.9	12.3	0.7	59	0.6	2.5	0.2	38	0.99	0.128	7
1279774	Soil	1.6	19.9	9.8	95	0.7	25.0	4.3	147	1.44	16.6	10.7	0.7	40	0.5	1.3	0.1	27	0.53	0.108	5
1279775	Soil	2.7	46.1	17.5	108	1.7	35.6	5.1	162	2.21	54.3	45.1	0.8	69	0.5	2.1	0.2	53	1.00	0.158	6
1279776	Soil	2.5	41.1	11.9	59	1.0	20.8	4.5	167	1.58	18.4	10.1	0.4	46	0.6	1.4	0.2	36	0.91	0.124	5
1279777	Soil	1.5	44.3	11.5	59	0.9	30.5	4.5	122	1.69	14.3	6.9	0.9	41	0.1	1.1	0.2	46	0.71	0.093	9
1279778	Soil	1.4	54.1	9.5	47	0.9	27.9	4.3	231	1.15	8.0	8.5	0.4	60	0.6	1.2	0.1	30	1.31	0.118	6
1279779	Soil	9.9	22.0	18.9	143	0.4	30.1	5.1	87	1.52	37.3	10.0	1.0	26	0.6	5.6	0.2	78	0.16	0.051	11
1279780	Soil	2.5	25.5	11.7	66	0.8	12.7	2.3	73	1.10	20.7	13.6	0.7	52	0.9	2.1	0.2	42	0.86	0.064	7
1279781	Soil	1.9	49.7	13.1	96	1.2	30.6	3.5	125	1.36	27.9	20.5	0.6	79	0.8	2.5	0.2	37	1.47	0.091	8
1279782	Soil	2.0	68.8	17.7	123	1.5	41.5	5.6	255	1.56	25.9	27.9	0.6	108	1.5	3.4	0.3	40	2.09	0.095	8
1279783	Soil	2.1	74.9	18.8	139	1.5	43.9	6.3	209	1.65	25.4	29.3	1.0	87	0.9	3.4	0.4	40	1.47	0.092	7
1279784	Soil	2.2	79.8	16.8	151	1.3	51.7	6.7	226	1.86	26.6	26.3	1.3	67	1.9	4.5	0.2	45	1.34	0.087	7
1279785	Soil	4.4	65.1	16.6	137	1.7	39.1	5.2	188	1.71	41.3	37.6	1.1	68	1.5	7.8	0.3	61	1.45	0.102	7
1279786	Soil	6.5	80.9	14.7	166	2.7	52.5	6.0	190	1.53	44.1	38.2	1.1	66	2.9	10.3	0.3	68	1.25	0.105	7
1279787	Soil	2.2	58.7	12.9	111	1.6	45.3	5.2	204	0.99	14.2	24.6	0.8	61	1.5	5.2	0.2	35	1.09	0.094	7
1279788	Soil	20.0	43.4	45.2	195	2.3	43.9	6.9	137	2.37	145.2	45.5	1.8	87	0.8	22.8	0.7	147	0.36	0.140	11
1279789	Soil	8.2	110.5	26.0	210	2.9	84.2	9.9	195	2.30	66.1	49.5	2.1	119	3.9	11.9	0.3	90	1.76	0.126	9
1279790	Soil	9.6	80.4	26.3	164	2.2	58.5	9.5	199	2.23	73.2	48.7	2.0	86	2.3	12.4	0.3	92	1.02	0.110	9
1279791	Soil	4.5	44.7	19.7	116	2.0	31.7	5.3	138	1.80	73.3	36.5	1.2	63	1.5	9.4	0.3	92	0.62	0.122	6
1279792	Soil	6.9	70.9	26.9	207	2.4	49.3	11.1	202	2.28	72.8	44.3	2.1	130	1.2	12.1	0.4	98	0.86	0.114	8
1279793	Soil	6.6	59.3	22.1	189	2.0	51.6	8.7	226	2.26	54.8	30.8	2.2	110	1.6	9.0	0.3	73	0.79	0.107	8
1279794	Soil	10.6	57.2	25.3	231	1.9	58.6	10.6	377	2.19	72.5	35.3	1.8	137	1.9	14.8	0.3	87	0.99	0.123	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279765	Soil	21	0.07	470	0.001	1	0.76	0.008	0.08	<0.1	0.18	2.8	0.2	0.09	3	3.6	<0.2
1279766	Soil	23	0.09	594	<0.001	1	0.90	0.009	0.09	<0.1	0.21	3.4	0.2	0.10	3	3.7	<0.2
1279767	Soil	27	0.11	598	<0.001	2	0.90	0.008	0.09	<0.1	0.47	5.2	0.2	0.09	2	4.3	<0.2
1279768	Soil	31	0.12	637	<0.001	2	0.92	0.007	0.08	<0.1	0.62	5.7	0.2	0.10	2	3.2	<0.2
1279769	Soil	24	0.10	673	0.002	3	0.88	0.015	0.06	<0.1	0.37	3.4	0.1	0.14	2	2.5	<0.2
1279770	Soil	26	0.11	601	0.001	3	0.81	0.008	0.06	<0.1	0.58	2.2	0.1	0.13	2	1.6	<0.2
1279771	Soil	13	0.08	376	0.003	3	0.61	0.022	0.05	<0.1	0.31	1.1	<0.1	0.13	1	1.2	<0.2
1279772	Soil	23	0.09	784	0.001	3	1.00	0.011	0.05	<0.1	0.49	2.3	0.2	0.15	2	2.3	<0.2
1279773	Soil	20	0.09	651	0.002	2	0.82	0.010	0.05	0.1	1.04	2.0	0.2	0.14	2	1.8	<0.2
1279774	Soil	15	0.07	455	0.001	2	0.64	0.013	0.06	<0.1	0.46	1.7	0.1	0.11	2	1.3	<0.2
1279775	Soil	27	0.10	1076	<0.001	2	1.22	0.009	0.09	<0.1	1.41	2.9	0.3	0.17	3	2.5	<0.2
1279776	Soil	18	0.10	711	0.003	3	0.91	0.012	0.06	0.1	0.55	1.5	0.1	0.17	3	2.3	<0.2
1279777	Soil	20	0.17	604	0.004	<1	1.11	0.009	0.05	0.2	0.49	1.9	0.2	0.12	4	1.3	<0.2
1279778	Soil	17	0.13	775	0.003	3	0.88	0.014	0.05	<0.1	0.50	1.3	0.2	0.19	2	1.9	<0.2
1279779	Soil	13	0.02	290	0.003	2	0.31	0.003	0.05	0.3	1.38	1.1	0.3	0.08	2	2.3	<0.2
1279780	Soil	14	0.07	717	0.005	2	0.58	0.007	0.06	0.2	1.14	1.3	0.2	0.12	3	1.5	<0.2
1279781	Soil	16	0.11	509	0.003	3	0.69	0.012	0.05	0.1	1.73	1.6	0.3	0.15	2	2.2	<0.2
1279782	Soil	21	0.17	673	0.002	4	0.79	0.011	0.06	0.1	1.82	2.1	0.4	0.16	2	2.9	<0.2
1279783	Soil	22	0.20	691	0.004	7	0.95	0.008	0.07	0.1	1.75	2.4	0.3	0.10	2	3.4	<0.2
1279784	Soil	21	0.18	712	0.002	4	0.99	0.009	0.06	<0.1	2.16	2.9	0.4	0.08	3	3.2	0.2
1279785	Soil	19	0.16	551	0.003	3	0.73	0.006	0.04	0.2	4.23	2.2	0.4	0.09	2	3.7	<0.2
1279786	Soil	19	0.08	903	0.002	3	0.65	0.007	0.05	0.2	6.56	3.2	0.6	0.09	2	4.9	<0.2
1279787	Soil	17	0.10	653	0.002	2	0.80	0.012	0.05	0.1	1.95	2.2	0.3	0.09	2	3.1	<0.2
1279788	Soil	18	0.05	395	0.003	5	0.47	0.003	0.09	0.8	12.83	1.6	1.5	0.13	3	7.7	0.3
1279789	Soil	23	0.10	1093	0.002	4	0.90	0.005	0.06	0.4	4.74	4.4	0.8	0.11	2	7.0	<0.2
1279790	Soil	21	0.09	813	0.003	4	0.79	0.004	0.05	0.4	4.43	3.4	0.7	0.09	2	5.7	0.2
1279791	Soil	19	0.08	933	0.002	4	0.73	0.006	0.05	0.2	5.17	2.3	0.7	0.08	2	4.8	<0.2
1279792	Soil	25	0.19	641	0.002	2	0.93	0.008	0.06	0.3	4.78	3.8	0.7	0.06	2	3.1	0.3
1279793	Soil	26	0.22	866	0.001	4	0.84	0.004	0.06	0.2	4.17	3.3	0.5	0.06	2	2.9	<0.2
1279794	Soil	20	0.13	692	0.002	4	0.65	0.005	0.07	0.4	4.00	2.6	0.8	0.12	2	7.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279795	Soil	11.6	57.0	23.5	250	1.7	57.1	11.3	290	2.60	71.0	20.9	1.9	76	1.8	10.6	0.3	86	0.52	0.149	10
1279796	Soil	19.1	52.7	15.6	361	0.8	100.9	33.8	3382	3.65	33.6	8.1	1.5	58	7.6	5.7	0.2	117	0.24	0.145	6
1279797	Soil	10.5	78.0	13.6	1379	1.6	368.4	20.0	922	3.34	44.6	8.9	1.3	78	11.7	5.1	0.2	101	0.60	0.164	6
1279798	Soil	6.0	66.2	11.2	465	1.2	117.8	8.2	226	2.22	17.3	11.1	1.4	56	6.0	3.5	0.2	73	0.57	0.124	8
1279799	Soil	11.0	54.8	15.6	529	1.7	216.6	6.9	194	2.34	29.3	4.5	0.6	70	8.0	5.7	0.2	102	0.96	0.195	5
1279800	Soil	12.6	32.4	17.5	187	1.0	32.1	5.0	151	2.56	35.0	5.2	0.8	48	0.7	5.6	0.3	123	0.09	0.196	6
1279801	Soil	84.4	36.7	15.9	396	2.1	94.9	4.2	39	2.22	100.3	5.7	0.4	83	0.5	22.8	0.2	434	0.02	0.079	14
1279802	Soil	69.3	36.3	14.3	408	1.2	95.2	3.9	42	2.11	141.4	4.8	1.3	145	0.6	23.6	0.2	302	0.03	0.122	14
1279803	Soil	20.9	12.1	7.9	107	0.6	27.1	1.1	10	0.49	32.3	21.5	<0.1	17	0.2	11.3	<0.1	155	<0.01	0.035	9
1279804	Soil	37.6	6.9	25.4	20	8.3	3.6	0.3	8	1.49	473.7	85.6	0.3	29	0.2	84.5	0.2	347	<0.01	0.081	9
1279805	Soil	17.0	24.3	39.6	48	4.2	9.5	0.9	13	0.63	55.5	93.1	0.2	88	0.1	42.9	0.4	230	0.02	0.068	13
1279806	Soil	23.8	13.3	37.0	81	1.6	18.1	1.6	21	0.96	62.0	54.0	0.3	60	0.1	28.1	0.4	148	0.02	0.064	10
1279807	Soil	16.8	16.9	34.4	102	0.8	23.2	2.7	30	1.02	42.3	14.7	0.4	22	0.3	11.1	0.2	129	<0.01	0.035	15
1279808	Soil	27.1	53.5	37.4	247	2.2	63.7	5.7	189	2.38	73.6	13.0	1.6	55	2.6	19.5	0.2	171	0.16	0.215	13
1279809	Soil	22.3	40.3	28.7	181	2.1	44.3	4.7	129	1.75	61.7	13.5	0.4	45	2.1	15.6	0.2	121	0.06	0.158	8
1279810	Soil	37.2	59.5	48.1	336	1.4	72.0	7.5	170	2.63	118.3	23.1	1.8	84	3.3	30.4	0.3	166	0.24	0.176	15
1279811	Soil	31.9	45.7	96.5	180	2.0	45.3	4.1	79	1.79	102.6	36.8	1.1	85	2.0	32.3	0.3	145	0.18	0.144	14
1279812	Soil	28.6	34.5	42.3	183	1.5	42.6	3.9	83	1.76	96.8	27.2	1.6	62	1.0	29.1	0.2	145	0.08	0.127	14
1279813	Soil	29.5	41.8	40.8	260	1.3	66.8	5.7	145	2.06	115.6	25.1	0.9	65	2.0	35.0	0.3	156	0.13	0.126	15
1279814	Soil	46.5	68.5	21.2	793	1.6	155.6	16.6	688	3.16	115.7	21.9	2.3	52	9.0	25.5	0.3	121	0.35	0.119	11
1279815	Soil	23.9	55.5	39.1	292	1.7	59.8	8.2	236	2.63	152.1	22.6	2.1	87	5.4	18.2	0.4	98	0.33	0.133	13
1279816	Soil	13.6	43.6	19.1	233	1.2	55.3	19.2	563	2.11	69.9	15.2	1.7	48	3.2	9.9	0.3	120	0.26	0.105	7
1279817	Soil	10.9	45.2	20.6	133	1.7	28.1	6.5	99	1.94	71.2	17.5	2.0	40	1.6	9.9	0.3	121	0.06	0.113	8
1279818	Soil	7.3	49.9	15.9	216	0.9	49.2	10.0	116	2.48	51.3	5.6	2.4	37	2.4	7.8	0.3	60	0.19	0.083	7
1279819	Soil	10.0	44.1	17.9	241	1.7	51.6	15.0	310	1.93	64.1	11.6	1.7	43	1.9	8.1	0.4	82	0.23	0.111	7
1279820	Soil	5.0	42.8	9.7	205	1.2	41.4	15.0	449	1.65	62.3	7.9	1.0	25	1.0	5.0	0.2	43	0.12	0.069	5
1279821	Soil	12.2	95.6	19.8	580	1.5	134.7	57.1	2569	4.64	306.0	9.4	2.1	41	5.1	11.2	0.3	90	0.17	0.131	8
1279822	Soil	15.1	70.8	18.6	629	0.9	97.6	67.4	3704	7.42	650.9	12.1	2.2	35	5.2	13.9	0.3	78	0.15	0.115	7
1279823	Soil	8.4	63.6	17.0	389	1.2	93.5	15.4	1112	2.50	129.8	13.2	1.9	56	6.0	8.3	0.3	83	0.42	0.104	8
1279824	Soil	6.2	65.3	15.8	615	0.9	118.1	20.0	999	2.81	101.7	9.2	2.3	54	8.2	6.6	0.3	54	0.43	0.083	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279795	Soil	22	0.11	1695	0.003	3	0.74	0.004	0.07	0.2	3.17	3.1	0.7	0.10	2	5.1	<0.2
1279796	Soil	17	0.11	2498	0.003	4	0.73	0.002	0.09	0.2	0.90	2.4	0.5	0.09	2	5.5	<0.2
1279797	Soil	18	0.11	2275	0.002	3	0.85	0.003	0.08	0.1	1.24	2.9	0.6	0.10	2	5.1	<0.2
1279798	Soil	19	0.17	2040	0.004	5	1.03	0.007	0.10	0.1	0.88	2.9	0.5	0.08	3	3.7	<0.2
1279799	Soil	22	0.06	1944	0.003	3	0.53	0.004	0.08	0.1	0.68	1.9	0.6	0.11	2	4.2	<0.2
1279800	Soil	20	0.04	939	0.005	3	0.54	0.003	0.07	0.2	0.26	1.3	0.5	0.08	3	3.4	<0.2
1279801	Soil	17	0.02	174	0.004	2	0.43	0.003	0.06	0.7	0.77	0.7	1.7	0.06	3	8.2	<0.2
1279802	Soil	20	0.03	221	0.003	<1	0.64	0.002	0.07	0.6	1.24	1.1	1.4	<0.05	2	7.7	<0.2
1279803	Soil	10	0.01	119	0.005	2	0.26	0.008	0.04	0.4	1.31	0.2	0.6	<0.05	2	2.2	<0.2
1279804	Soil	17	0.01	219	0.003	2	0.26	0.010	0.08	2.4	35.31	2.4	5.1	0.19	4	36.5	1.1
1279805	Soil	13	0.01	244	0.003	2	0.30	0.007	0.07	1.2	>50	0.1	3.3	0.10	2	6.4	0.5
1279806	Soil	9	0.01	185	0.004	2	0.30	0.005	0.07	0.9	4.30	0.3	1.4	0.07	3	4.4	<0.2
1279807	Soil	10	0.02	205	0.006	1	0.36	0.002	0.05	0.4	0.71	0.3	0.9	<0.05	3	3.5	<0.2
1279808	Soil	23	0.05	904	0.004	4	0.46	0.003	0.12	0.5	2.18	2.1	2.0	0.18	2	7.8	<0.2
1279809	Soil	16	0.04	677	0.002	4	0.53	0.007	0.09	0.4	2.58	0.8	1.4	0.11	2	5.0	<0.2
1279810	Soil	19	0.07	728	0.004	3	0.51	0.003	0.13	0.7	3.15	2.1	2.0	0.16	2	10.4	0.4
1279811	Soil	16	0.05	623	0.003	2	0.50	0.003	0.10	0.8	5.33	1.3	2.3	0.12	2	11.7	0.3
1279812	Soil	14	0.04	473	0.002	2	0.42	0.002	0.08	0.6	2.68	1.4	2.0	0.09	2	5.9	0.2
1279813	Soil	16	0.06	561	0.002	3	0.44	0.002	0.10	0.6	2.69	1.1	1.9	0.10	2	6.2	<0.2
1279814	Soil	16	0.04	325	0.002	2	0.56	0.003	0.06	0.5	4.41	2.7	1.2	<0.05	1	7.0	<0.2
1279815	Soil	14	0.06	622	0.007	3	0.52	0.003	0.08	0.4	4.37	2.3	1.0	0.12	2	7.3	<0.2
1279816	Soil	21	0.11	1157	0.001	2	0.84	0.005	0.08	0.2	1.88	2.4	0.6	<0.05	3	3.7	<0.2
1279817	Soil	20	0.09	573	0.001	3	0.90	0.003	0.06	0.3	2.64	2.5	1.0	0.05	2	4.8	<0.2
1279818	Soil	22	0.16	1782	0.001	3	0.82	0.003	0.07	0.1	1.51	3.2	0.3	<0.05	2	4.6	<0.2
1279819	Soil	24	0.14	822	0.001	3	1.07	0.006	0.09	0.2	1.90	2.9	0.7	0.05	3	2.6	<0.2
1279820	Soil	17	0.11	653	0.002	3	0.85	0.013	0.07	<0.1	0.85	2.3	0.3	<0.05	2	1.9	<0.2
1279821	Soil	26	0.17	988	0.002	4	1.36	0.006	0.09	0.2	1.75	3.8	0.7	<0.05	3	5.0	<0.2
1279822	Soil	24	0.17	758	0.002	3	0.95	0.005	0.08	0.2	1.15	3.4	0.5	<0.05	3	4.0	<0.2
1279823	Soil	22	0.20	988	0.001	4	1.00	0.005	0.09	0.2	1.45	3.4	0.5	0.08	3	3.0	<0.2
1279824	Soil	23	0.24	1324	0.001	4	1.06	0.006	0.08	0.2	1.35	3.6	0.3	0.08	3	4.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279825	Soil	10.9	63.8	18.3	1683	1.3	208.8	23.8	544	4.95	207.4	7.6	2.6	66	6.3	12.3	0.4	72	0.60	0.088	9
1279826	Soil	7.9	57.5	13.4	1128	1.1	188.4	30.5	807	2.48	70.1	12.7	1.6	57	7.6	8.2	0.3	57	0.61	0.088	8
1279827	Soil	13.4	59.4	21.9	1313	1.4	185.1	28.8	1011	3.57	130.0	17.3	2.5	64	10.1	13.0	0.5	77	0.39	0.103	12
1279828	Soil	13.1	91.7	20.6	1478	1.8	308.0	55.3	2539	3.60	328.0	27.6	2.4	65	16.2	10.1	0.5	70	0.58	0.120	9
1279829	Soil	9.6	45.6	36.1	421	1.9	78.6	14.1	1089	2.79	238.8	87.6	2.3	55	4.2	16.9	1.1	56	0.39	0.111	11
1279830	Soil	6.1	45.1	13.8	259	1.0	64.7	9.8	364	2.05	61.6	21.1	1.2	43	3.1	7.8	0.3	37	0.38	0.079	6
1279831	Soil	8.9	49.2	42.4	96	2.7	20.3	5.1	257	2.80	321.4	82.4	2.4	39	1.7	18.1	2.4	50	0.24	0.124	13
1279832	Soil	6.2	37.3	27.4	114	2.9	27.9	4.6	135	1.93	132.4	95.7	1.7	47	0.7	14.8	0.9	38	0.15	0.095	12
1279833	Soil	13.1	30.6	15.0	113	0.5	24.2	2.9	59	1.96	34.7	5.5	1.4	47	0.3	6.8	0.2	113	0.07	0.137	6
1279834	Soil	15.7	76.4	15.4	224	1.2	42.2	6.7	146	2.54	44.1	7.2	2.2	85	2.4	10.2	0.2	147	0.21	0.208	7
1279835	Soil	11.7	87.5	18.5	528	1.3	96.8	9.3	233	3.05	39.4	6.8	2.4	90	5.2	8.1	0.3	126	0.57	0.150	7
1279836	Soil	8.7	58.2	16.4	357	1.3	74.1	10.1	257	2.55	38.8	8.3	1.5	82	4.2	5.3	0.2	80	0.66	0.146	9
1279837	Soil	10.7	31.7	15.6	135	0.6	27.2	3.0	66	1.49	26.9	4.5	0.5	51	0.9	5.3	0.2	100	0.11	0.100	6
1279838	Soil	10.7	42.0	13.8	173	1.1	36.6	4.7	85	1.88	29.0	12.3	1.2	58	1.8	6.6	0.2	97	0.11	0.129	6
1279839	Soil	8.6	33.0	13.3	169	1.1	31.9	8.1	616	1.76	20.8	4.0	1.2	63	2.0	3.5	0.2	76	0.58	0.115	6
1279840	Soil	7.5	38.5	10.2	258	0.8	41.0	8.2	489	2.51	20.4	9.5	1.5	113	1.3	3.8	0.2	83	0.67	0.132	6
1279841	Soil	4.7	51.8	9.0	273	0.7	54.5	6.2	199	2.17	17.2	6.7	2.0	115	2.2	3.5	0.2	65	0.59	0.123	8
1279842	Soil	4.4	63.9	12.5	252	0.9	59.1	7.7	223	2.24	18.4	6.2	2.3	91	1.8	3.3	0.2	78	0.73	0.102	8
1279843	Soil	5.9	54.5	12.3	284	0.7	55.3	8.5	266	2.57	21.9	5.9	1.9	61	1.5	3.6	0.2	77	0.43	0.105	7
1279844	Soil	5.4	78.9	13.8	306	2.3	80.6	7.4	226	2.67	21.5	9.4	1.6	83	3.2	3.0	0.2	103	0.92	0.101	6
1279845	Soil	6.1	29.1	15.2	153	0.6	27.9	4.1	106	2.26	18.3	1.0	1.6	21	1.2	2.6	0.2	78	0.02	0.062	8
1279846	Soil	6.3	34.3	16.4	167	0.2	27.8	4.3	129	3.94	22.9	<0.5	1.7	20	0.4	3.1	0.3	90	0.03	0.068	7
1279847	Soil	8.1	26.6	23.6	146	0.9	27.2	4.4	139	3.40	26.2	<0.5	1.7	30	0.7	3.7	0.4	125	0.02	0.097	10
1279848	Soil	4.2	17.5	15.2	111	0.5	14.4	3.7	111	2.47	13.2	1.5	1.6	13	0.6	1.6	0.3	73	0.02	0.087	9
1279849	Soil	4.9	16.0	16.0	106	0.3	17.6	3.4	86	1.80	15.9	1.1	2.0	17	0.4	2.2	0.3	79	0.02	0.044	12
1279850	Soil	4.8	25.8	13.9	135	0.2	22.3	4.7	137	3.37	19.5	<0.5	2.3	12	0.3	2.3	0.3	75	0.01	0.059	8
1279851	Soil	4.3	48.0	22.5	161	0.2	48.4	10.0	245	3.89	24.5	4.0	2.8	27	0.4	2.8	0.3	61	0.07	0.081	10
1279852	Soil	5.9	30.9	17.9	142	0.1	35.7	6.0	133	3.52	22.7	3.8	2.6	15	0.4	2.7	0.3	86	0.04	0.037	9
1279853	Soil	6.0	23.8	14.5	137	0.4	28.5	5.4	149	2.99	22.4	1.5	1.4	15	0.7	2.8	0.3	76	0.03	0.069	9
1279854	Soil	5.4	60.5	11.9	207	1.0	57.5	9.9	227	2.61	17.7	7.2	2.5	41	0.6	2.8	0.2	75	0.70	0.068	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279825	Soil	22	0.21	979	0.002	4	0.93	0.005	0.08	0.2	1.83	3.8	0.5	0.09	2	5.0	<0.2
1279826	Soil	16	0.16	697	0.002	3	0.89	0.009	0.06	0.3	1.53	2.8	0.5	0.10	2	2.2	<0.2
1279827	Soil	18	0.15	914	0.002	3	0.84	0.004	0.08	0.3	2.56	3.5	0.7	0.09	2	5.4	<0.2
1279828	Soil	19	0.17	625	0.002	3	1.17	0.006	0.08	0.2	3.10	4.0	0.9	0.09	3	4.9	<0.2
1279829	Soil	18	0.11	742	0.002	3	0.61	0.004	0.08	0.5	9.77	2.7	1.1	0.13	2	5.6	<0.2
1279830	Soil	15	0.09	1113	0.002	3	0.51	0.010	0.05	0.1	2.24	2.1	0.3	0.11	2	3.8	<0.2
1279831	Soil	14	0.05	322	0.002	3	0.63	0.004	0.07	0.6	8.38	1.7	0.8	0.07	3	5.7	0.2
1279832	Soil	17	0.05	384	0.002	3	0.64	0.003	0.06	0.4	11.25	2.0	0.7	0.07	2	6.0	<0.2
1279833	Soil	19	0.04	1019	0.003	2	0.48	0.003	0.06	0.2	0.38	1.4	0.3	0.09	2	2.9	0.2
1279834	Soil	26	0.05	1390	0.003	4	0.58	0.003	0.09	0.2	1.35	3.8	0.5	0.10	1	3.8	0.2
1279835	Soil	26	0.16	1899	0.003	5	0.89	0.004	0.13	0.1	1.16	3.4	0.7	0.06	2	3.0	0.2
1279836	Soil	23	0.14	2180	0.002	5	0.72	0.005	0.09	0.1	2.21	3.2	0.4	0.11	2	5.5	<0.2
1279837	Soil	17	0.04	1185	0.002	3	0.48	0.003	0.07	0.1	0.37	1.1	0.4	0.08	2	2.3	<0.2
1279838	Soil	19	0.05	1082	0.003	3	0.49	0.003	0.07	0.1	0.65	2.3	0.5	0.07	2	3.2	<0.2
1279839	Soil	18	0.12	1684	0.002	4	0.79	0.006	0.07	0.1	0.57	1.9	0.3	0.07	2	2.5	<0.2
1279840	Soil	23	0.19	1904	0.003	4	0.96	0.005	0.09	0.1	1.05	2.5	0.2	<0.05	3	1.2	<0.2
1279841	Soil	22	0.20	2274	0.004	4	0.83	0.007	0.08	0.1	0.85	2.8	0.2	<0.05	2	2.6	<0.2
1279842	Soil	27	0.25	2175	0.003	5	1.15	0.006	0.09	0.1	0.80	3.2	0.2	<0.05	3	2.1	<0.2
1279843	Soil	25	0.22	1970	0.005	4	0.90	0.004	0.09	0.1	0.77	2.5	0.2	<0.05	3	1.7	<0.2
1279844	Soil	29	0.16	3600	0.002	6	1.69	0.017	0.15	<0.1	1.34	4.0	0.4	<0.05	4	2.7	<0.2
1279845	Soil	19	0.09	383	0.012	3	0.81	0.007	0.08	0.1	0.08	1.6	0.3	<0.05	4	1.2	<0.2
1279846	Soil	24	0.12	300	0.005	2	0.94	0.005	0.08	0.1	0.07	1.7	0.2	<0.05	5	1.4	<0.2
1279847	Soil	22	0.09	305	0.011	2	0.94	0.004	0.08	0.1	0.10	1.8	0.3	<0.05	6	1.6	<0.2
1279848	Soil	17	0.07	294	0.008	3	0.81	0.005	0.08	<0.1	0.02	1.3	0.2	<0.05	5	1.2	<0.2
1279849	Soil	14	0.08	241	0.010	<1	0.74	0.004	0.06	0.1	<0.01	1.3	0.2	<0.05	4	0.9	<0.2
1279850	Soil	24	0.15	239	0.006	3	1.15	0.005	0.06	0.1	0.02	1.9	0.2	<0.05	5	1.1	<0.2
1279851	Soil	30	0.27	2511	0.002	4	1.48	0.004	0.08	<0.1	0.13	2.6	0.2	<0.05	4	2.3	0.2
1279852	Soil	26	0.20	880	0.002	3	1.29	0.003	0.08	0.1	0.05	2.1	0.2	<0.05	4	1.6	<0.2
1279853	Soil	21	0.17	666	0.003	3	0.92	0.004	0.08	0.1	0.05	1.4	0.2	<0.05	3	2.4	<0.2
1279854	Soil	30	0.28	2959	0.002	5	1.30	0.006	0.10	<0.1	0.36	3.9	0.2	<0.05	3	1.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279855	Soil		6.1	58.9	14.3	220	0.7	50.5	8.4	213	2.69	20.9	6.0	1.6	49	1.1	3.3	0.3	57	0.39	0.098	9
1279856	Soil		7.7	81.0	19.5	331	1.1	71.6	9.9	243	3.57	27.4	6.7	3.0	75	2.0	4.5	0.3	65	0.65	0.134	9
1279857	Soil		6.8	54.9	14.7	217	0.6	51.5	11.1	257	2.87	21.1	5.4	2.2	55	1.0	3.4	0.3	59	0.38	0.106	10
1279858	Soil		5.6	53.9	13.2	149	0.9	42.1	11.1	540	2.93	15.5	5.3	1.1	57	3.2	2.5	0.3	54	0.66	0.162	8
1279859	Soil		3.5	30.6	9.7	88	0.6	25.4	4.4	154	1.54	10.3	2.8	0.7	44	0.9	1.4	0.2	42	0.72	0.076	5
1279860	Soil		5.9	62.5	18.1	241	0.6	60.5	9.8	238	3.18	24.6	5.6	4.0	63	1.0	3.9	0.3	63	0.30	0.097	12
1279861	Soil		5.1	54.2	15.1	219	0.8	50.8	9.8	378	2.85	17.0	5.5	2.1	48	1.3	2.5	0.3	66	0.32	0.097	13
1279862	Soil		8.1	102.6	18.2	484	1.8	94.9	18.5	285	3.50	25.5	9.9	2.6	64	1.1	4.2	0.3	14	0.57	0.073	12
1279863	Soil		2.4	67.3	23.2	141	0.4	26.8	16.6	653	3.80	9.2	9.4	1.6	27	1.5	1.4	0.4	22	0.18	0.174	3
1279864	Soil		4.2	30.5	14.6	143	1.1	28.6	9.6	181	3.28	11.9	2.6	2.3	50	0.7	1.6	0.3	39	0.77	0.058	6
1279865	Soil		2.9	39.9	13.5	122	0.6	26.5	5.3	73	2.06	8.7	2.1	0.8	43	1.5	1.2	0.2	30	0.40	0.046	6
1279866	Soil		0.7	72.2	5.4	55	1.0	56.7	5.2	627	1.48	1.9	5.4	0.2	197	5.7	1.1	0.1	17	4.05	0.210	11
1279867	Soil		3.2	101.4	13.1	228	1.3	60.0	7.6	285	2.27	12.6	7.3	1.1	82	2.2	2.0	0.3	54	1.26	0.124	10
1279868	Soil		7.4	63.7	25.5	235	0.5	51.1	9.7	252	3.83	26.3	6.3	2.5	29	0.5	3.5	0.4	83	0.09	0.156	8
1279869	Soil		5.4	34.2	19.2	163	0.8	39.2	12.7	224	4.29	17.3	3.5	2.9	19	0.7	2.1	0.2	59	0.07	0.057	9
1279870	Soil		8.9	49.9	13.1	251	0.6	57.2	7.8	144	2.52	22.4	3.1	2.7	43	1.5	4.0	0.2	60	0.32	0.113	10
1279871	Soil		8.1	51.6	15.6	219	1.0	51.8	8.2	130	2.62	22.1	4.5	2.2	70	1.2	3.5	0.2	74	0.61	0.097	9
1279872	Soil		8.7	128.5	15.4	245	0.9	63.5	9.4	179	2.75	23.4	8.8	1.7	69	1.1	3.3	0.2	60	0.67	0.082	7
1279873	Soil		3.8	68.4	13.4	139	1.0	39.7	6.5	271	1.78	13.0	8.5	0.9	124	2.1	2.2	0.2	64	1.12	0.116	6
1279874	Soil		8.6	59.2	13.0	226	1.2	55.3	11.4	374	2.36	18.0	7.0	1.5	80	1.9	3.1	0.2	76	0.59	0.098	7
1279875	Soil		11.6	48.9	21.8	215	0.9	40.2	8.1	208	2.47	28.2	5.7	2.4	101	1.8	4.4	0.3	103	0.47	0.102	9
1279876	Soil		9.3	50.8	19.0	185	1.0	35.1	7.6	149	2.23	23.0	6.0	1.9	67	1.0	3.9	0.3	78	0.32	0.089	7
1279877	Soil		9.4	60.6	14.6	290	0.5	59.3	10.3	215	2.81	25.9	4.6	3.1	51	1.7	4.8	0.3	72	0.28	0.108	11
1279878	Soil		9.5	39.7	20.2	261	0.2	52.1	11.2	251	3.16	30.5	6.2	2.7	40	1.1	4.0	0.3	102	0.15	0.075	10
1279879	Soil		11.0	35.1	18.6	194	0.4	39.4	7.0	149	2.85	30.1	4.4	2.7	30	0.7	4.5	0.2	100	0.04	0.068	9
1279880	Soil		9.2	66.9	19.7	363	1.5	78.9	12.9	559	2.97	26.9	9.2	2.1	109	4.2	4.2	0.3	87	0.93	0.129	9
1279881	Soil		2.6	56.0	20.7	110	0.8	33.6	8.6	173	4.30	14.0	4.2	2.2	62	0.1	1.0	0.3	39	0.02	0.085	3
1279882	Soil		2.5	31.2	26.3	111	1.1	38.5	14.6	312	2.84	36.9	2.5	2.6	57	0.4	1.6	0.3	29	0.04	0.083	6
1279883	Soil		3.1	41.2	13.0	50	0.8	11.9	2.2	58	2.17	17.9	9.7	1.1	83	0.1	1.7	0.2	33	0.08	0.122	7
1279884	Soil		3.3	29.0	11.2	59	0.5	17.5	2.7	54	2.36	38.3	6.8	0.5	45	<0.1	2.3	0.2	44	0.03	0.051	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279855	Soil	21	0.23	2546	0.002	2	0.93	0.004	0.06	0.1	0.34	2.4	0.2	0.07	3	1.2	<0.2
1279856	Soil	26	0.35	2545	0.002	3	1.17	0.005	0.10	0.1	0.57	3.8	0.3	0.07	3	1.9	<0.2
1279857	Soil	23	0.27	3007	0.002	3	1.01	0.003	0.06	0.1	0.28	2.6	0.2	0.06	3	1.6	<0.2
1279858	Soil	22	0.21	2581	0.003	2	1.17	0.007	0.05	0.1	0.45	2.3	0.2	0.12	3	2.2	<0.2
1279859	Soil	13	0.08	1920	0.002	1	0.83	0.007	0.04	0.1	0.13	1.1	0.1	<0.05	3	1.0	<0.2
1279860	Soil	24	0.27	2985	0.002	3	1.05	0.003	0.07	0.1	0.33	3.3	0.2	<0.05	2	2.1	<0.2
1279861	Soil	26	0.25	2965	0.003	2	1.28	0.004	0.08	0.1	0.34	3.3	0.2	<0.05	3	1.6	<0.2
1279862	Soil	9	0.09	2366	<0.001	3	0.43	0.003	0.05	<0.1	0.34	4.8	0.2	0.09	<1	1.6	<0.2
1279863	Soil	29	0.30	4246	0.002	2	1.47	0.006	0.05	<0.1	0.14	1.9	<0.1	0.06	3	1.1	<0.2
1279864	Soil	21	0.20	1989	0.003	2	0.93	0.004	0.06	<0.1	0.10	2.5	0.1	0.06	3	1.5	<0.2
1279865	Soil	16	0.15	838	0.006	1	0.74	0.004	0.06	0.1	0.07	1.3	<0.1	<0.05	3	1.1	<0.2
1279866	Soil	21	0.19	849	0.005	6	0.64	0.007	0.02	<0.1	0.34	2.0	<0.1	0.26	<1	4.0	<0.2
1279867	Soil	27	0.29	1322	0.004	5	0.95	0.005	0.07	<0.1	0.86	3.4	0.3	0.11	2	2.1	<0.2
1279868	Soil	28	0.25	415	0.003	2	1.28	0.004	0.06	<0.1	0.06	2.1	0.3	<0.05	4	1.5	<0.2
1279869	Soil	25	0.24	1230	0.002	<1	1.44	0.002	0.04	0.2	0.08	2.0	0.2	<0.05	4	2.1	<0.2
1279870	Soil	18	0.21	1764	0.002	2	0.75	0.003	0.06	<0.1	0.34	2.8	0.2	<0.05	2	1.3	<0.2
1279871	Soil	20	0.18	1703	0.002	1	0.96	0.003	0.06	0.1	0.47	3.1	0.2	<0.05	3	3.4	<0.2
1279872	Soil	24	0.23	1018	0.001	<1	0.96	0.004	0.05	0.1	0.49	3.4	0.2	<0.05	3	2.8	<0.2
1279873	Soil	19	0.18	1246	0.003	3	0.99	0.009	0.05	<0.1	0.48	2.3	0.2	0.11	3	2.7	<0.2
1279874	Soil	19	0.18	1020	0.003	2	1.02	0.009	0.06	0.1	0.51	3.0	0.3	0.05	3	3.0	<0.2
1279875	Soil	23	0.17	1159	0.002	2	0.88	0.003	0.06	0.2	0.51	2.7	0.3	<0.05	3	2.3	<0.2
1279876	Soil	17	0.15	893	0.002	2	0.80	0.007	0.05	0.1	0.49	2.5	0.3	<0.05	2	2.1	<0.2
1279877	Soil	18	0.17	1944	0.005	2	0.84	0.002	0.06	0.1	0.35	3.2	0.3	<0.05	2	2.1	<0.2
1279878	Soil	23	0.20	1086	0.002	2	1.22	0.003	0.06	0.1	0.17	2.4	0.3	<0.05	3	1.8	<0.2
1279879	Soil	17	0.11	558	0.002	<1	0.95	0.002	0.05	0.2	0.15	1.9	0.3	<0.05	3	1.9	<0.2
1279880	Soil	26	0.24	1530	0.003	4	1.06	0.004	0.08	0.1	0.79	3.9	0.3	0.09	3	3.1	<0.2
1279881	Soil	31	0.22	180	0.002	2	1.23	0.005	0.05	<0.1	0.09	2.3	0.2	<0.05	4	1.8	<0.2
1279882	Soil	18	0.12	245	0.003	2	0.84	0.004	0.09	<0.1	0.15	3.1	0.2	<0.05	2	1.5	<0.2
1279883	Soil	19	0.06	290	0.003	2	0.69	0.005	0.13	0.1	0.16	2.0	0.2	0.18	2	3.0	<0.2
1279884	Soil	17	0.05	167	0.006	<1	0.55	0.002	0.05	0.2	0.14	0.9	0.1	0.05	3	3.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279885	Soil	3.4	40.8	14.8	278	2.0	92.6	15.4	491	2.71	45.8	9.1	0.7	90	2.0	3.5	0.2	56	1.62	0.198	15
1279886	Soil	2.5	58.2	21.1	210	1.7	66.8	18.8	380	3.55	35.2	9.8	2.0	81	0.9	3.4	0.2	36	0.53	0.159	11
1279887	Soil	2.9	94.2	37.1	193	1.0	94.0	68.2	1820	3.56	25.9	21.9	2.1	31	0.2	2.3	0.3	38	0.12	0.082	4
1279888	Soil	2.8	51.7	10.9	214	1.8	77.2	9.6	106	2.83	13.4	4.1	0.6	90	0.8	1.1	0.2	22	1.68	0.102	5
1279889	Soil	7.7	117.8	25.1	172	3.3	44.8	11.8	184	5.63	35.2	2.7	3.7	63	0.4	2.1	0.3	39	0.08	0.127	3
1279890	Soil	2.6	58.9	22.2	187	1.4	67.6	12.6	165	3.75	89.5	3.9	2.8	106	0.4	2.1	0.3	21	0.10	0.083	4
1279891	Soil	2.7	50.8	13.6	163	2.1	63.9	11.3	186	2.75	25.2	3.4	1.3	40	0.5	1.3	0.2	28	0.20	0.107	6
1279892	Soil	2.9	76.3	17.9	197	2.4	74.3	10.3	169	3.62	105.1	119.1	2.3	82	0.4	3.8	0.2	31	0.18	0.102	6
1279893	Soil	2.6	24.4	7.5	66	0.9	18.7	3.0	38	1.39	19.6	13.7	0.4	11	0.2	1.3	0.1	35	0.07	0.066	4
1279894	Soil	1.4	30.0	10.7	74	2.3	30.2	4.4	102	1.22	14.5	26.8	0.9	58	0.6	0.8	0.2	20	1.06	0.088	5
1279895	Soil	7.4	51.4	10.8	135	1.7	44.0	4.5	52	2.37	15.2	3.5	1.7	61	0.4	1.3	0.2	19	0.14	0.060	8
1279896	Soil	7.5	38.6	16.6	73	2.5	20.8	2.3	27	2.47	32.8	6.0	0.3	27	0.1	1.5	0.2	48	0.03	0.096	3
1279897	Soil	5.5	20.8	32.6	23	1.9	7.9	1.1	60	1.82	30.1	6.4	0.8	27	<0.1	2.5	0.3	25	0.12	0.050	2
1279898	Soil	5.9	27.9	10.3	80	0.3	16.7	2.7	31	1.70	19.8	2.1	0.6	11	<0.1	1.8	0.1	58	0.01	0.043	7
1279899	Soil	4.8	9.6	6.1	41	<0.1	8.0	1.2	15	1.55	31.9	1.9	<0.1	3	<0.1	4.4	0.2	70	<0.01	0.042	6
1279900	Soil	91.1	22.0	60.6	211	2.0	25.5	1.6	24	9.59	221.4	3.7	0.4	255	0.2	24.4	0.2	378	0.02	0.225	4
1279901	Soil	3.7	18.8	14.7	81	<0.1	15.4	2.9	107	2.29	16.7	1.6	1.5	9	0.1	1.7	0.3	70	<0.01	0.071	8
1279902	Soil	6.0	16.3	16.6	87	0.4	18.1	3.6	126	2.70	21.4	4.0	1.7	16	0.2	2.3	0.3	83	0.03	0.050	9
1279903	Soil	5.2	16.9	14.9	86	0.2	16.8	3.0	68	2.41	19.2	1.6	1.9	12	0.2	2.4	0.2	80	0.01	0.057	9
1279904	Soil	3.6	16.6	9.4	62	0.3	12.0	2.0	41	0.97	11.3	2.6	1.2	11	0.3	1.5	0.2	46	0.03	0.032	9
1279905	Soil	7.9	28.2	18.8	124	0.3	25.0	4.6	109	2.58	24.5	4.3	1.4	31	0.5	3.4	0.3	91	0.03	0.068	10
1279906	Soil	6.8	48.5	15.9	222	0.9	45.6	9.1	485	2.83	20.3	5.1	1.9	103	2.3	3.7	0.3	76	0.65	0.126	8
1279907	Soil	5.3	39.2	11.9	161	1.2	34.6	4.8	159	1.91	15.1	6.8	0.9	76	1.3	2.7	0.2	56	0.39	0.092	5
1279908	Soil	6.4	26.8	16.3	135	0.3	26.7	4.4	114	2.58	22.7	2.2	1.0	24	0.6	2.9	0.3	98	0.05	0.073	10
1279909	Soil	6.8	56.9	16.6	201	2.0	53.6	14.5	739	2.55	19.2	9.2	1.3	88	1.3	3.0	0.2	63	0.46	0.107	6
1279910	Soil	3.3	35.2	15.9	165	1.7	26.4	6.0	263	2.06	11.4	9.3	1.3	54	1.8	2.2	0.2	65	0.47	0.163	9
1279911	Soil	5.0	38.6	16.0	168	0.3	35.6	5.8	166	2.90	23.4	4.7	1.6	25	0.7	2.7	0.2	73	0.07	0.099	7
1279912	Soil	7.2	13.5	17.2	76	0.1	16.4	3.1	102	2.30	22.9	1.8	2.2	15	0.2	2.5	0.3	102	0.02	0.030	11
1279913	Soil	6.3	19.0	19.2	88	0.2	18.3	3.1	70	2.51	23.5	<0.5	1.4	19	0.2	3.0	0.2	88	0.02	0.054	9
1279914	Soil	5.8	25.6	15.7	123	<0.1	23.7	4.3	121	4.21	25.2	0.6	1.8	12	0.2	2.9	0.3	106	0.01	0.080	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279885	Soil	30	0.07	572	0.001	5	0.74	0.004	0.07	0.1	0.71	2.5	0.2	0.10	2	4.0	0.2
1279886	Soil	28	0.08	555	0.002	5	0.65	0.005	0.11	<0.1	0.22	5.4	0.1	0.11	2	2.8	<0.2
1279887	Soil	24	0.14	616	0.002	<1	0.80	0.004	0.07	0.3	0.09	6.1	0.2	0.06	2	3.1	<0.2
1279888	Soil	23	0.09	806	<0.001	4	0.62	0.006	0.07	<0.1	0.51	2.9	0.1	0.15	1	4.4	<0.2
1279889	Soil	39	0.06	897	0.001	3	0.81	0.008	0.14	<0.1	0.14	7.3	0.2	0.21	3	9.1	<0.2
1279890	Soil	14	0.04	737	<0.001	1	0.64	0.007	0.11	<0.1	0.25	3.7	0.1	0.18	1	3.2	<0.2
1279891	Soil	19	0.09	574	0.001	2	0.81	0.004	0.07	<0.1	0.24	2.9	0.1	0.11	2	3.0	<0.2
1279892	Soil	21	0.08	1006	0.002	3	1.10	0.006	0.11	<0.1	1.24	3.8	0.2	0.23	2	6.0	<0.2
1279893	Soil	13	0.02	202	0.002	3	0.35	0.003	0.05	0.1	0.15	1.1	<0.1	0.07	2	1.8	<0.2
1279894	Soil	15	0.05	1443	<0.001	2	0.74	0.007	0.07	<0.1	0.64	2.4	0.1	0.10	2	1.6	<0.2
1279895	Soil	14	0.05	592	0.001	1	0.31	0.003	0.06	<0.1	0.21	3.0	<0.1	0.11	<1	4.5	<0.2
1279896	Soil	21	0.02	1078	0.001	3	0.54	0.004	0.05	<0.1	0.22	1.2	0.1	0.13	2	6.6	<0.2
1279897	Soil	10	0.01	475	<0.001	2	0.29	0.005	0.13	<0.1	0.78	1.7	0.4	0.39	2	7.8	<0.2
1279898	Soil	12	0.01	217	0.002	2	0.32	0.002	0.04	<0.1	0.05	0.7	0.2	<0.05	2	1.6	<0.2
1279899	Soil	7	0.01	65	0.003	2	0.35	0.003	0.04	<0.1	0.05	0.1	0.4	<0.05	3	0.9	<0.2
1279900	Soil	33	0.01	257	0.003	3	0.43	0.008	0.33	0.4	0.89	0.4	2.1	0.60	3	12.0	0.3
1279901	Soil	14	0.09	159	0.003	2	0.81	0.002	0.04	<0.1	0.01	1.1	0.2	<0.05	5	1.0	<0.2
1279902	Soil	20	0.14	200	0.005	2	1.09	0.003	0.05	0.2	0.07	1.3	0.2	<0.05	5	1.4	<0.2
1279903	Soil	14	0.06	203	0.006	2	0.72	0.002	0.04	0.1	0.03	1.1	0.2	<0.05	4	1.0	<0.2
1279904	Soil	9	0.05	306	0.003	<1	0.55	0.002	0.04	0.1	0.11	0.7	0.1	<0.05	3	1.3	<0.2
1279905	Soil	21	0.11	462	0.005	2	0.98	0.003	0.06	0.2	0.12	1.6	0.3	0.06	4	2.2	<0.2
1279906	Soil	26	0.24	2477	0.002	3	1.12	0.005	0.07	0.1	0.38	2.7	0.2	0.13	3	3.1	<0.2
1279907	Soil	20	0.16	1966	0.003	2	0.92	0.014	0.06	<0.1	0.49	1.7	0.2	0.09	3	1.9	<0.2
1279908	Soil	20	0.10	1070	0.004	3	1.11	0.004	0.06	0.1	0.15	1.6	0.3	0.05	4	1.0	<0.2
1279909	Soil	26	0.19	2534	0.002	4	1.31	0.012	0.09	<0.1	0.89	2.8	0.3	0.10	3	1.9	<0.2
1279910	Soil	26	0.20	1967	0.003	3	1.49	0.009	0.06	<0.1	1.41	2.5	0.3	0.13	4	4.5	<0.2
1279911	Soil	24	0.19	684	0.003	5	1.16	0.005	0.06	0.1	0.20	1.8	0.2	<0.05	3	<0.5	<0.2
1279912	Soil	15	0.09	184	0.010	1	0.83	0.003	0.04	0.1	0.07	1.1	0.2	<0.05	5	1.2	<0.2
1279913	Soil	16	0.07	186	0.009	<1	0.77	0.004	0.05	0.2	0.07	1.1	0.3	0.05	4	1.6	<0.2
1279914	Soil	25	0.11	215	0.004	1	1.09	0.003	0.05	0.1	0.03	1.7	0.2	<0.05	6	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279915	Soil	2.4	8.8	6.0	41	0.3	7.3	1.7	63	0.99	5.7	<0.5	0.4	14	0.1	0.9	0.1	40	0.02	0.030	5
1279916	Soil	3.1	17.6	10.2	93	0.3	13.6	3.1	102	2.01	10.9	0.6	1.1	13	0.5	1.4	0.2	55	0.02	0.044	7
1279917	Soil	5.7	27.5	19.3	179	0.8	26.5	4.8	156	3.94	23.1	<0.5	1.2	20	1.4	2.7	0.3	92	0.03	0.117	8
1279918	Soil	6.1	29.3	16.8	222	0.8	36.4	5.6	178	3.46	26.5	1.5	1.9	23	0.6	3.2	0.2	98	0.02	0.125	6
1279919	Soil	5.4	37.9	11.7	217	0.5	41.5	6.6	180	2.18	24.2	4.2	1.8	34	1.2	3.1	0.2	72	0.10	0.086	7
1279920	Soil	7.7	41.4	13.9	305	0.8	60.0	7.2	250	3.04	28.1	7.8	2.3	42	0.7	3.4	0.2	97	0.14	0.115	6
1279921	Soil	7.3	80.7	16.0	384	0.9	79.1	8.4	238	3.19	41.6	10.7	2.4	68	3.4	5.4	0.2	82	0.36	0.128	8
1279922	Soil	6.2	79.1	12.8	312	1.1	76.6	8.6	332	2.40	27.2	7.9	1.6	71	3.3	3.8	0.2	77	1.00	0.108	7
1279923	Soil	3.6	45.4	6.5	177	1.0	43.9	5.2	361	1.22	11.2	4.6	0.5	63	3.2	2.3	0.1	43	0.93	0.072	4
1279924	Soil	6.1	76.3	12.8	263	1.1	69.1	7.4	690	2.64	30.5	9.4	1.6	86	5.6	5.2	0.2	97	1.21	0.112	6
1279925	Soil	14.2	62.6	19.2	208	0.9	41.4	5.1	104	2.48	30.4	6.3	2.0	93	1.1	6.6	0.2	118	0.36	0.120	8
1279926	Soil	13.9	60.3	17.9	171	0.7	37.2	4.6	87	2.28	31.6	7.3	1.3	85	0.9	6.9	0.2	106	0.23	0.120	8
1279927	Soil	14.5	58.2	17.5	152	0.8	34.8	4.0	81	2.23	30.4	6.2	1.2	84	0.8	6.8	0.2	111	0.15	0.117	8
1279928	Soil	5.8	38.4	27.3	185	4.4	43.0	6.2	300	2.53	22.7	12.0	1.0	91	1.3	3.4	0.2	61	0.97	0.115	8
1279929	Soil	3.6	40.8	15.3	174	1.1	37.7	7.5	195	2.33	39.8	14.5	1.5	64	0.9	4.0	0.2	55	0.93	0.100	7
1279930	Soil	2.3	52.9	6.5	131	1.1	35.5	5.7	791	1.63	16.0	7.7	0.5	65	1.4	2.6	0.1	29	1.21	0.077	4
1279961	Soil	5.8	34.5	15.6	167	0.1	40.3	7.1	199	3.56	23.7	4.0	1.4	21	0.5	2.7	0.2	77	0.08	0.140	8
1279962	Soil	13.6	23.9	21.1	109	1.8	20.8	2.7	66	1.81	14.6	<0.5	0.3	198	0.4	3.5	0.3	91	0.06	0.210	9
1279963	Soil	6.6	26.5	12.5	104	0.4	19.6	3.1	74	2.11	15.4	1.8	0.8	15	0.4	2.3	0.2	86	0.02	0.074	7
1279964	Soil	6.7	47.6	17.1	190	0.6	40.6	6.1	165	3.42	23.0	8.4	2.1	20	0.6	3.4	0.2	85	0.04	0.085	8
1279965	Soil	4.3	25.5	8.3	67	0.2	13.4	3.1	50	1.25	10.9	1.2	0.3	12	0.4	1.2	0.2	61	0.03	0.074	7
1279966	Soil	5.0	46.1	14.1	119	0.5	24.9	4.5	144	2.57	16.7	2.9	0.5	20	0.8	1.9	0.2	77	0.07	0.092	8
1279967	Soil	4.0	18.3	14.4	77	0.2	14.1	3.1	78	1.74	13.7	1.2	0.3	12	0.7	1.3	0.2	63	0.03	0.063	10
1279968	Soil	6.6	23.9	17.5	247	0.2	34.7	8.6	274	4.20	22.1	1.3	2.5	14	2.6	2.7	0.3	126	0.03	0.054	10
1279969	Soil	5.5	40.8	14.1	184	0.2	43.4	4.9	112	3.37	11.9	0.9	1.8	9	0.6	1.4	0.3	37	0.01	0.063	12
1279970	Soil	3.6	42.9	13.4	189	0.9	42.9	10.5	452	2.42	15.7	2.4	1.0	51	3.3	1.6	0.2	49	0.75	0.082	7
1279971	Soil	3.0	24.5	10.7	101	0.5	17.3	4.4	57	1.86	7.5	1.8	0.7	50	1.8	0.9	0.2	27	0.83	0.043	3
1279972	Soil	2.7	86.2	12.0	144	0.7	27.4	7.6	288	2.34	10.7	3.7	0.7	90	2.1	1.2	0.2	32	1.15	0.079	4
1279973	Soil	2.5	98.9	11.2	211	1.0	48.5	9.4	267	2.24	10.2	5.4	0.7	73	2.3	1.3	0.2	27	1.14	0.091	5
1279974	Soil	3.3	58.1	14.1	165	1.4	47.2	8.8	244	2.59	15.0	7.1	1.0	67	1.7	1.9	0.3	28	1.32	0.068	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279915	Soil	7	0.03	857	0.007	2	0.49	0.011	0.04	<0.1	0.05	0.6	<0.1	<0.05	3	<0.5	<0.2
1279916	Soil	15	0.10	340	0.006	2	0.87	0.006	0.06	0.2	0.07	1.2	0.1	<0.05	4	1.0	<0.2
1279917	Soil	24	0.13	269	0.007	1	1.01	0.004	0.08	0.1	0.06	1.3	0.2	<0.05	5	1.1	<0.2
1279918	Soil	23	0.15	366	0.004	2	1.16	0.004	0.08	0.1	0.13	2.1	0.3	<0.05	4	1.7	<0.2
1279919	Soil	20	0.15	1914	0.003	2	0.89	0.005	0.07	0.1	0.26	2.1	0.2	0.06	3	1.5	<0.2
1279920	Soil	29	0.21	1863	0.002	4	1.28	0.004	0.09	<0.1	0.66	2.5	0.3	0.05	3	1.2	<0.2
1279921	Soil	26	0.22	1426	0.005	3	0.91	0.004	0.09	<0.1	1.05	3.1	0.3	0.13	2	2.9	<0.2
1279922	Soil	23	0.18	2496	0.002	6	1.07	0.008	0.09	<0.1	1.02	3.1	0.3	0.08	2	2.1	<0.2
1279923	Soil	13	0.08	1424	0.006	2	0.72	0.021	0.06	<0.1	0.67	1.7	0.2	0.09	2	1.6	<0.2
1279924	Soil	25	0.14	2795	0.002	5	1.00	0.007	0.07	0.1	1.10	3.1	0.3	0.12	2	3.6	<0.2
1279925	Soil	25	0.11	2330	0.003	3	0.66	0.004	0.08	0.2	0.76	3.1	0.4	0.09	2	3.1	<0.2
1279926	Soil	21	0.09	1587	0.003	3	0.52	0.003	0.07	0.1	0.67	2.6	0.4	0.10	2	3.7	<0.2
1279927	Soil	22	0.08	1642	0.003	2	0.54	0.003	0.08	0.2	0.71	2.5	0.4	0.12	2	3.5	<0.2
1279928	Soil	19	0.10	1625	0.002	4	0.79	0.011	0.11	0.1	1.73	2.0	0.3	0.17	2	3.4	<0.2
1279929	Soil	21	0.17	686	0.002	4	0.92	0.007	0.08	<0.1	1.21	3.2	0.2	0.07	2	2.8	<0.2
1279930	Soil	14	0.11	1029	0.003	4	0.79	0.022	0.06	<0.1	0.66	1.8	0.1	0.11	2	2.5	<0.2
1279961	Soil	26	0.22	553	0.009	3	1.26	0.004	0.07	0.1	0.10	1.5	0.2	<0.05	3	2.3	<0.2
1279962	Soil	18	0.05	768	0.007	3	0.78	0.009	0.09	0.2	0.04	0.5	0.7	0.12	4	4.9	<0.2
1279963	Soil	15	0.07	547	0.002	1	0.91	0.005	0.06	<0.1	0.07	1.1	0.2	<0.05	4	1.3	<0.2
1279964	Soil	28	0.24	1030	0.002	3	1.19	0.003	0.07	0.1	0.18	2.1	0.2	<0.05	3	1.5	<0.2
1279965	Soil	12	0.04	405	0.006	3	0.65	0.006	0.05	<0.1	0.02	0.4	0.1	<0.05	4	0.6	<0.2
1279966	Soil	23	0.13	937	0.004	3	1.13	0.004	0.07	0.1	0.07	1.1	0.2	<0.05	4	1.4	<0.2
1279967	Soil	14	0.06	446	0.007	1	0.78	0.004	0.05	0.1	0.04	0.5	0.2	<0.05	4	0.7	<0.2
1279968	Soil	29	0.16	3662	0.005	2	1.67	0.004	0.05	0.2	0.02	2.6	0.3	<0.05	5	1.0	<0.2
1279969	Soil	16	0.10	2173	0.002	2	0.94	0.004	0.06	<0.1	0.02	2.7	0.1	<0.05	3	<0.5	<0.2
1279970	Soil	17	0.13	8159	0.007	2	1.14	0.011	0.04	0.1	0.13	2.0	0.1	<0.05	3	1.7	<0.2
1279971	Soil	14	0.10	1214	0.004	1	0.58	0.004	0.05	<0.1	0.07	1.1	<0.1	<0.05	2	1.4	<0.2
1279972	Soil	22	0.26	1225	0.004	2	0.91	0.005	0.04	0.1	0.18	1.8	<0.1	0.07	3	3.1	<0.2
1279973	Soil	18	0.23	2183	0.003	2	0.93	0.004	0.04	<0.1	0.27	1.8	0.1	0.09	2	2.6	<0.2
1279974	Soil	19	0.23	1662	0.002	2	0.80	0.004	0.04	0.1	0.33	2.2	0.2	0.08	2	2.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279975	Soil	3.0	87.5	11.8	203	1.8	63.5	5.3	124	2.45	12.5	9.1	1.1	103	1.6	1.7	0.2	27	1.23	0.108	7
1279976	Soil	3.0	24.4	12.6	132	0.4	23.4	6.1	208	2.42	12.5	3.2	1.1	42	1.3	1.4	0.2	46	0.71	0.086	4
1279977	Soil	3.7	29.7	12.2	147	0.5	32.3	7.8	164	2.32	13.1	2.8	1.6	44	1.5	1.7	0.2	43	0.89	0.046	10
1279978	Soil	3.8	40.9	11.9	165	0.9	44.3	7.5	304	2.10	13.3	4.5	0.8	85	1.8	2.0	0.2	39	1.71	0.085	8
1279979	Soil	2.7	55.2	10.9	103	1.4	51.4	6.7	253	1.64	10.1	6.0	0.6	115	1.5	2.1	0.2	32	2.09	0.069	6
1279980	Soil	5.2	39.0	12.3	165	1.1	40.9	10.0	214	2.73	16.0	4.9	1.1	100	1.7	2.4	0.2	30	1.29	0.095	6
1279981	Soil	6.0	23.2	13.6	151	0.3	28.3	5.6	229	3.33	20.1	0.8	1.9	13	0.4	2.3	0.2	61	0.06	0.101	7
1279982	Soil	4.8	23.8	16.7	163	1.0	19.1	6.7	194	3.42	18.9	<0.5	1.9	30	1.0	1.5	0.3	51	0.05	0.082	6
1279983	Soil	4.3	17.7	10.9	94	0.5	15.8	3.4	123	2.21	11.5	2.5	0.9	11	0.5	1.6	0.2	68	0.04	0.050	9
1279984	Soil	3.7	33.4	11.5	92	0.9	25.7	7.2	301	1.59	10.3	3.5	0.3	23	1.1	1.4	0.2	64	0.09	0.108	8
1279985	Soil	4.1	26.5	11.9	117	0.5	22.0	4.8	172	2.38	14.4	2.3	0.9	14	0.9	1.7	0.2	67	0.05	0.067	9
1279986	Soil	4.4	51.0	16.6	173	1.2	46.2	12.8	487	2.70	14.1	5.7	1.3	64	1.4	1.6	0.2	75	0.41	0.143	10
1279987	Soil	5.8	39.9	13.4	169	0.7	35.6	7.1	280	2.53	16.6	2.9	0.8	42	1.0	1.9	0.2	75	0.37	0.110	8
1279988	Soil	6.1	34.5	15.3	209	0.2	40.4	8.2	242	3.66	21.0	6.9	2.0	28	0.8	2.4	0.2	79	0.15	0.096	8
1279989	Soil	5.6	22.7	15.4	137	0.9	25.3	4.5	116	3.81	23.5	2.2	1.8	11	0.3	2.1	0.3	88	0.02	0.083	8
1279990	Soil	4.7	17.3	10.0	68	0.5	14.4	2.3	43	1.30	13.3	1.8	0.2	16	0.2	2.0	0.2	56	0.01	0.051	7
1279991	Soil	1.7	19.0	15.8	74	<0.1	18.6	6.8	163	3.55	14.4	1.9	0.9	16	<0.1	0.7	0.3	46	0.01	0.067	4
1279992	Soil	2.0	37.6	23.8	117	0.3	28.8	17.9	447	3.44	19.7	2.2	2.2	30	0.3	1.0	0.3	35	0.04	0.081	3
1279993	Soil	1.9	33.9	22.4	94	0.2	21.7	7.4	154	3.65	18.7	3.9	2.2	26	<0.1	1.0	0.3	35	0.02	0.082	3
1279994	Soil	1.9	27.0	17.7	75	0.1	16.1	5.4	159	3.44	15.6	2.6	1.0	17	<0.1	0.8	0.3	47	0.02	0.088	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

CERTIFICATE OF ANALYSIS WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279975	Soil	23	0.21	2497	0.002	4	0.76	0.005	0.04	<0.1	0.94	2.7	0.2	0.08	2	2.4	<0.2
1279976	Soil	16	0.08	2148	0.004	1	0.54	0.004	0.03	<0.1	0.09	1.3	<0.1	<0.05	2	1.4	<0.2
1279977	Soil	19	0.17	2351	0.003	1	0.82	0.005	0.04	0.1	0.14	2.1	0.1	<0.05	2	1.4	<0.2
1279978	Soil	19	0.17	2045	0.004	3	0.81	0.006	0.04	<0.1	0.27	1.9	0.2	0.08	2	2.2	<0.2
1279979	Soil	15	0.13	2632	0.002	3	0.73	0.005	0.04	<0.1	0.38	1.7	0.1	0.09	2	2.7	<0.2
1279980	Soil	17	0.21	1670	0.002	3	0.73	0.005	0.04	<0.1	0.30	2.1	0.2	0.11	2	5.3	<0.2
1279981	Soil	21	0.21	302	0.003	1	1.15	0.003	0.05	0.1	0.05	1.4	0.2	<0.05	3	1.0	<0.2
1279982	Soil	19	0.10	685	0.002	1	1.15	0.004	0.09	<0.1	0.05	1.1	0.2	0.05	4	0.9	<0.2
1279983	Soil	15	0.11	413	0.008	3	0.83	0.004	0.05	0.1	0.04	1.1	0.2	<0.05	4	<0.5	<0.2
1279984	Soil	17	0.08	2577	0.005	3	0.97	0.007	0.05	0.2	0.12	0.5	0.1	<0.05	3	0.7	<0.2
1279985	Soil	21	0.16	1060	0.006	2	1.13	0.004	0.05	0.2	0.08	1.5	0.2	<0.05	4	0.9	<0.2
1279986	Soil	28	0.26	3983	0.004	3	1.56	0.005	0.06	0.2	0.33	3.0	0.2	0.07	4	0.7	<0.2
1279987	Soil	22	0.18	2312	0.003	2	1.09	0.005	0.05	<0.1	0.16	1.5	0.2	<0.05	3	<0.5	<0.2
1279988	Soil	27	0.24	2547	0.004	3	1.40	0.004	0.07	0.1	0.15	2.3	0.3	<0.05	4	1.3	<0.2
1279989	Soil	25	0.18	996	0.004	3	1.26	0.003	0.06	0.1	0.04	1.9	0.2	<0.05	4	1.7	<0.2
1279990	Soil	9	0.04	2827	0.007	3	0.49	0.004	0.05	0.1	0.08	0.5	0.2	0.06	3	0.9	<0.2
1279991	Soil	22	0.14	145	0.003	1	1.11	0.004	0.06	<0.1	0.03	1.9	0.1	<0.05	5	0.8	<0.2
1279992	Soil	24	0.19	508	0.001	3	1.09	0.007	0.08	<0.1	0.08	4.1	0.2	<0.05	3	1.5	<0.2
1279993	Soil	24	0.17	364	0.001	2	1.11	0.006	0.08	<0.1	0.08	2.7	0.2	0.10	3	1.1	<0.2
1279994	Soil	21	0.13	235	0.003	<1	1.06	0.006	0.06	<0.1	0.05	1.6	0.2	<0.05	5	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

QUALITY CONTROL REPORT WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1278602	Soil	2.0	29.2	13.3	155	1.2	43.6	7.7	155	2.69	19.0	7.1	1.3	73	0.7	1.8	0.2	32	1.21	0.118	8
REP 1278602	QC	2.1	29.2	13.0	155	1.2	44.0	7.4	150	2.67	18.8	7.4	1.3	73	0.8	1.8	0.2	33	1.19	0.121	8
1278613	Soil	6.0	31.5	17.0	120	0.4	30.9	4.3	71	2.44	39.5	5.5	1.2	22	0.4	5.0	0.3	55	0.14	0.057	9
REP 1278613	QC	6.0	31.4	16.8	118	0.4	30.2	4.2	71	2.45	39.1	5.8	1.2	22	0.4	5.0	0.3	55	0.13	0.057	9
1278634	Soil	10.6	33.5	20.9	176	0.5	35.2	7.6	214	2.64	36.2	5.3	0.6	40	0.5	5.3	0.3	74	0.06	0.098	7
REP 1278634	QC	10.7	33.9	21.4	180	0.5	35.1	7.7	217	2.69	37.2	4.6	0.6	41	0.5	5.4	0.3	76	0.06	0.098	7
1278701	Soil	1.3	9.9	7.7	53	<0.1	8.5	2.7	54	0.87	22.6	<0.5	0.1	11	0.3	0.8	0.2	14	0.10	0.058	2
REP 1278701	QC	1.2	9.7	7.7	53	<0.1	8.3	2.6	55	0.87	22.9	<0.5	<0.1	11	0.3	0.8	0.2	14	0.11	0.058	2
1278712	Soil	1.2	15.0	12.0	46	0.3	7.5	2.8	39	2.09	13.8	1.2	0.5	9	<0.1	0.6	0.2	36	<0.01	0.057	2
REP 1278712	QC	1.2	14.6	12.4	46	0.3	7.8	2.8	39	2.11	14.0	<0.5	0.5	9	<0.1	0.6	0.2	38	<0.01	0.057	2
1278720	Soil	1.8	26.6	15.3	121	0.8	34.1	12.4	334	2.16	10.1	3.3	1.4	65	0.7	0.6	0.2	38	0.17	0.075	4
REP 1278720	QC	1.8	27.4	15.1	130	0.8	35.2	12.5	351	2.26	10.0	4.2	1.4	62	0.7	0.7	0.2	40	0.18	0.076	4
1279762	Soil	2.5	45.8	13.3	166	1.4	48.6	7.4	361	2.46	42.9	14.1	1.2	61	1.2	3.5	0.2	44	1.09	0.092	7
REP 1279762	QC	2.5	46.1	13.8	175	1.5	49.9	7.5	362	2.46	44.0	14.2	1.3	63	1.1	3.5	0.2	47	1.13	0.096	7
1279765	Soil	3.7	43.4	18.9	107	1.1	33.0	8.0	176	2.70	21.7	3.3	1.2	44	0.2	2.0	0.2	32	0.05	0.073	4
REP 1279765	QC	3.7	42.6	19.2	105	1.1	32.5	7.9	180	2.79	21.7	4.1	1.0	44	0.2	1.9	0.2	33	0.05	0.075	4
1279798	Soil	6.0	66.2	11.2	465	1.2	117.8	8.2	226	2.22	17.3	11.1	1.4	56	6.0	3.5	0.2	73	0.57	0.124	8
REP 1279798	QC	6.3	67.1	11.6	465	1.2	118.9	8.2	227	2.23	17.5	10.3	1.3	56	6.5	3.4	0.2	75	0.58	0.127	8
1279804	Soil	37.6	6.9	25.4	20	8.3	3.6	0.3	8	1.49	473.7	85.6	0.3	29	0.2	84.5	0.2	347	<0.01	0.081	9
REP 1279804	QC	38.5	6.8	26.3	20	8.4	3.5	0.3	8	1.47	491.6	78.4	0.3	29	<0.1	85.4	0.2	366	<0.01	0.082	9
1279819	Soil	10.0	44.1	17.9	241	1.7	51.6	15.0	310	1.93	64.1	11.6	1.7	43	1.9	8.1	0.4	82	0.23	0.111	7
REP 1279819	QC	9.8	44.5	16.8	232	1.6	49.6	15.2	298	1.84	59.1	14.2	1.6	42	1.7	8.0	0.3	83	0.22	0.106	7
1279845	Soil	6.1	29.1	15.2	153	0.6	27.9	4.1	106	2.26	18.3	1.0	1.6	21	1.2	2.6	0.2	78	0.02	0.062	8
REP 1279845	QC	6.2	28.6	15.1	155	0.6	28.1	4.2	105	2.21	18.4	<0.5	1.6	22	1.3	2.8	0.2	77	0.02	0.065	9
1279883	Soil	3.1	41.2	13.0	50	0.8	11.9	2.2	58	2.17	17.9	9.7	1.1	83	0.1	1.7	0.2	33	0.08	0.122	7
REP 1279883	QC	3.1	39.0	12.0	46	0.8	11.0	2.1	54	2.03	16.9	9.1	1.1	76	0.1	1.6	0.2	30	0.06	0.116	7
1279904	Soil	3.6	16.6	9.4	62	0.3	12.0	2.0	41	0.97	11.3	2.6	1.2	11	0.3	1.5	0.2	46	0.03	0.032	9
REP 1279904	QC	3.8	16.9	9.4	64	0.3	12.3	2.0	42	0.98	11.5	1.8	1.1	11	0.3	1.4	0.2	45	0.02	0.030	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

QUALITY CONTROL REPORT WHI11001181.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1278602	Soil	21	0.15	567	0.001	4	0.77	0.006	0.05	<0.1	0.70	2.8	0.1	0.09	2	1.8	<0.2
REP 1278602	QC	21	0.15	560	0.001	4	0.78	0.005	0.05	<0.1	0.68	2.9	0.1	0.09	2	1.9	<0.2
1278613	Soil	15	0.11	464	0.003	1	0.63	0.003	0.05	0.1	0.29	1.4	0.2	<0.05	3	1.8	<0.2
REP 1278613	QC	15	0.11	463	0.003	1	0.63	0.003	0.05	0.1	0.31	1.3	0.2	<0.05	3	1.7	<0.2
1278634	Soil	14	0.08	558	0.002	2	0.50	0.003	0.05	0.2	0.13	1.0	0.3	0.07	2	2.6	<0.2
REP 1278634	QC	15	0.08	570	0.002	1	0.51	0.003	0.05	0.2	0.12	1.0	0.4	0.06	2	2.5	<0.2
1278701	Soil	4	0.02	115	0.002	<1	0.30	0.009	0.04	<0.1	0.02	0.3	<0.1	<0.05	1	<0.5	<0.2
REP 1278701	QC	5	0.03	110	0.002	1	0.31	0.009	0.04	<0.1	0.03	0.1	<0.1	<0.05	1	<0.5	<0.2
1278712	Soil	9	0.03	68	<0.001	2	0.50	0.004	0.03	<0.1	0.02	0.7	<0.1	<0.05	3	0.8	<0.2
REP 1278712	QC	9	0.03	68	<0.001	<1	0.51	0.004	0.03	<0.1	0.02	0.9	<0.1	<0.05	3	0.6	<0.2
1278720	Soil	22	0.21	1263	0.001	1	1.30	0.008	0.09	<0.1	0.18	3.1	0.1	0.09	4	1.7	<0.2
REP 1278720	QC	22	0.21	1264	0.001	1	1.25	0.008	0.09	<0.1	0.16	3.0	0.1	0.09	4	1.8	<0.2
1279762	Soil	20	0.15	586	<0.001	3	0.87	0.006	0.07	<0.1	1.65	3.3	0.3	0.11	2	3.1	<0.2
REP 1279762	QC	20	0.16	607	<0.001	4	0.95	0.007	0.08	0.1	1.68	3.3	0.3	0.13	2	3.1	<0.2
1279765	Soil	21	0.07	470	0.001	1	0.76	0.008	0.08	<0.1	0.18	2.8	0.2	0.09	3	3.6	<0.2
REP 1279765	QC	22	0.08	491	0.002	2	0.81	0.009	0.09	<0.1	0.16	2.8	0.2	0.07	3	3.7	<0.2
1279798	Soil	19	0.17	2040	0.004	5	1.03	0.007	0.10	0.1	0.88	2.9	0.5	0.08	3	3.7	<0.2
REP 1279798	QC	18	0.18	2049	0.006	4	1.03	0.007	0.11	0.1	0.96	3.0	0.4	0.09	3	3.3	<0.2
1279804	Soil	17	0.01	219	0.003	2	0.26	0.010	0.08	2.4	35.31	2.4	5.1	0.19	4	36.5	1.1
REP 1279804	QC	17	0.01	215	0.003	1	0.28	0.010	0.08	2.5	35.62	2.2	5.2	0.20	4	36.8	0.8
1279819	Soil	24	0.14	822	0.001	3	1.07	0.006	0.09	0.2	1.90	2.9	0.7	0.05	3	2.6	<0.2
REP 1279819	QC	23	0.14	815	0.002	5	1.09	0.006	0.09	0.2	1.71	2.5	0.7	<0.05	3	2.9	<0.2
1279845	Soil	19	0.09	383	0.012	3	0.81	0.007	0.08	0.1	0.08	1.6	0.3	<0.05	4	1.2	<0.2
REP 1279845	QC	17	0.09	406	0.006	3	0.78	0.007	0.08	<0.1	0.07	1.6	0.3	<0.05	4	1.8	<0.2
1279883	Soil	19	0.06	290	0.003	2	0.69	0.005	0.13	0.1	0.16	2.0	0.2	0.18	2	3.0	<0.2
REP 1279883	QC	18	0.06	281	0.003	4	0.66	0.005	0.13	<0.1	0.18	1.6	0.2	0.18	2	3.4	<0.2
1279904	Soil	9	0.05	306	0.003	<1	0.55	0.002	0.04	0.1	0.11	0.7	0.1	<0.05	3	1.3	<0.2
REP 1279904	QC	9	0.05	299	0.003	1	0.55	0.002	0.04	0.1	0.10	0.8	0.1	<0.05	3	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

QUALITY CONTROL REPORT WHI11001181.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1279916	Soil	3.1	17.6	10.2	93	0.3	13.6	3.1	102	2.01	10.9	0.6	1.1	13	0.5	1.4	0.2	55	0.02	0.044	7
REP 1279916	QC	3.3	17.1	9.5	94	0.4	13.3	2.9	100	1.98	10.8	<0.5	1.1	13	0.5	1.4	0.2	53	0.02	0.043	7
1279966	Soil	5.0	46.1	14.1	119	0.5	24.9	4.5	144	2.57	16.7	2.9	0.5	20	0.8	1.9	0.2	77	0.07	0.092	8
REP 1279966	QC	5.5	49.3	15.0	132	0.5	25.9	5.0	151	2.76	17.9	2.1	0.6	21	0.7	1.9	0.2	81	0.07	0.098	9
1279973	Soil	2.5	98.9	11.2	211	1.0	48.5	9.4	267	2.24	10.2	5.4	0.7	73	2.3	1.3	0.2	27	1.14	0.091	5
REP 1279973	QC	2.5	95.9	10.6	204	1.0	47.8	9.3	270	2.22	10.3	4.0	0.7	75	2.1	1.3	0.2	27	1.12	0.092	5
1279992	Soil	2.0	37.6	23.8	117	0.3	28.8	17.9	447	3.44	19.7	2.2	2.2	30	0.3	1.0	0.3	35	0.04	0.081	3
REP 1279992	QC	2.1	40.6	24.6	123	0.3	31.7	19.6	494	3.65	21.3	2.9	2.3	32	0.2	1.1	0.3	38	0.04	0.088	3
Reference Materials																					
STD DS8	Standard	13.5	121.4	138.0	339	1.8	41.7	8.6	644	2.48	27.9	113.1	7.5	63	2.6	5.7	6.6	45	0.73	0.087	17
STD DS8	Standard	14.1	107.3	120.5	319	1.8	38.0	7.4	619	2.55	25.1	114.0	7.1	67	2.3	5.7	6.6	43	0.71	0.082	16
STD DS8	Standard	11.3	103.7	117.1	290	1.7	35.4	7.0	558	2.31	23.6	101.9	6.0	53	2.1	4.7	5.7	37	0.61	0.072	12
STD DS8	Standard	13.0	110.3	126.5	307	1.8	36.5	7.4	582	2.39	24.9	108.7	6.5	62	2.1	5.2	6.0	42	0.66	0.076	14
STD DS8	Standard	13.0	114.6	122.4	319	1.8	39.5	7.7	619	2.45	25.6	109.3	6.7	66	2.4	5.5	6.3	45	0.70	0.081	15
STD DS8	Standard	11.0	98.6	118.4	290	1.8	36.1	7.1	586	2.39	24.9	105.4	5.6	54	2.1	5.1	6.2	38	0.62	0.074	11
STD DS8	Standard	12.7	104.9	123.0	313	1.8	38.3	7.3	630	2.44	26.3	115.3	6.9	64	2.2	5.3	6.0	43	0.69	0.077	15
STD DS8	Standard	11.2	103.1	123.6	309	1.8	36.2	6.9	572	2.29	24.0	110.5	5.6	54	2.2	5.1	5.9	38	0.60	0.079	11
STD DS8	Standard	12.5	102.9	118.2	305	1.8	36.8	7.1	583	2.41	22.5	126.2	6.0	62	2.1	5.0	5.7	38	0.65	0.074	14
STD DS8	Standard	13.4	105.7	125.3	297	1.8	37.0	7.2	574	2.35	23.1	118.1	6.3	63	2.2	5.2	5.7	42	0.64	0.075	16
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

QUALITY CONTROL REPORT WHI11001181.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1279916	Soil	15	0.10	340	0.006	2	0.87	0.006	0.06	0.2	0.07	1.2	0.1	<0.05	4	1.0	<0.2
REP 1279916	QC	15	0.10	329	0.005	<1	0.87	0.006	0.06	0.2	0.03	1.0	0.1	<0.05	4	<0.5	<0.2
1279966	Soil	23	0.13	937	0.004	3	1.13	0.004	0.07	0.1	0.07	1.1	0.2	<0.05	4	1.4	<0.2
REP 1279966	QC	23	0.14	993	0.004	2	1.20	0.005	0.07	0.1	0.08	1.2	0.2	<0.05	4	1.2	<0.2
1279973	Soil	18	0.23	2183	0.003	2	0.93	0.004	0.04	<0.1	0.27	1.8	0.1	0.09	2	2.6	<0.2
REP 1279973	QC	18	0.23	2138	0.003	2	0.93	0.005	0.04	<0.1	0.25	1.8	0.1	0.07	2	2.4	<0.2
1279992	Soil	24	0.19	508	0.001	3	1.09	0.007	0.08	<0.1	0.08	4.1	0.2	<0.05	3	1.5	<0.2
REP 1279992	QC	26	0.20	522	0.002	3	1.16	0.008	0.09	<0.1	0.08	4.4	0.2	0.06	4	0.8	<0.2
Reference Materials																	
STD DS8	Standard	124	0.64	278	0.122	2	0.99	0.113	0.41	4.0	0.23	2.1	5.3	0.20	5	4.6	4.8
STD DS8	Standard	124	0.62	284	0.123	3	0.96	0.098	0.42	3.1	0.22	3.3	5.3	0.12	5	6.8	5.3
STD DS8	Standard	109	0.52	245	0.089	3	0.83	0.085	0.39	2.5	0.19	1.8	5.2	0.15	4	4.4	4.8
STD DS8	Standard	111	0.57	273	0.101	<1	0.93	0.103	0.42	3.0	0.30	1.6	5.4	0.14	5	6.0	4.6
STD DS8	Standard	117	0.63	281	0.117	3	0.96	0.115	0.43	3.0	0.18	2.6	5.4	0.18	5	5.0	4.9
STD DS8	Standard	111	0.58	246	0.088	2	0.82	0.077	0.39	2.8	0.19	1.7	5.2	0.14	4	5.3	4.7
STD DS8	Standard	115	0.59	282	0.120	3	0.92	0.096	0.41	3.0	0.18	2.2	5.5	0.17	5	4.5	4.9
STD DS8	Standard	108	0.57	252	0.095	2	0.83	0.077	0.39	2.9	0.21	1.6	5.3	0.18	4	5.0	4.6
STD DS8	Standard	110	0.59	260	0.105	2	0.88	0.103	0.42	2.8	0.20	1.9	5.2	0.16	5	5.0	4.8
STD DS8	Standard	113	0.58	260	0.114	2	0.87	0.083	0.41	2.9	0.20	2.0	5.5	0.19	4	5.1	4.7
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

QUALITY CONTROL REPORT WHI11001181.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 26, 2011

QUALITY CONTROL REPORT WHI11001181.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 18, 2011
Report Date: October 06, 2011
Page: 1 of 9

CERTIFICATE OF ANALYSIS WHI11001182.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #14
P.O. Number
Number of Samples: 216

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	216	Sieve soil to 230 mesh			WHI
RJSV	216	Saving all or part of Soil Reject			WHI
1DX2	214	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	2	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279995	Soil	1.4	6.1	1.5	9	<0.1	3.6	1.1	63	0.65	7.0	1.5	0.3	6	0.1	0.3	0.1	20	0.09	0.018	2
1279996	Soil	1.1	28.3	16.5	95	0.5	21.2	7.8	95	2.66	14.4	1.5	1.1	20	0.1	0.7	0.3	45	0.03	0.074	3
1279997	Soil	1.3	38.7	33.9	57	0.5	9.8	4.5	139	3.50	24.4	4.2	2.4	26	<0.1	0.6	0.4	38	0.01	0.092	3
1279998	Soil	2.5	25.6	24.5	77	0.2	17.9	6.1	199	3.80	17.2	3.1	0.5	11	0.1	1.3	0.4	48	0.03	0.111	4
1279999	Soil	1.6	36.3	25.2	115	0.3	28.5	10.0	247	3.74	17.7	3.0	2.1	11	0.2	0.6	0.4	53	0.02	0.075	3
1280000	Soil	1.8	28.5	22.1	90	0.8	18.0	7.8	170	3.92	14.1	2.3	2.2	12	0.2	0.7	0.4	62	0.02	0.072	4
1280001	Soil	3.4	20.4	14.1	113	1.1	15.2	3.9	106	2.52	10.3	1.1	0.8	20	1.2	1.2	0.3	39	0.02	0.041	5
1280002	Soil	4.0	57.8	13.3	141	0.5	47.4	9.9	231	2.71	13.5	6.6	1.6	64	0.4	2.4	0.3	45	0.79	0.051	5
1280003	Soil	0.9	61.8	8.4	43	0.2	11.7	2.1	78	1.98	1.9	1.5	0.1	38	0.3	0.3	0.1	29	0.27	0.061	2
1280004	Soil	4.2	37.8	9.1	42	0.6	5.6	1.3	24	2.61	9.1	1.0	0.7	4	0.1	1.3	0.3	51	0.01	0.039	2
1280005	Soil	3.0	49.1	14.9	195	0.6	33.2	8.6	209	2.18	10.1	7.3	1.2	52	1.5	1.5	0.3	38	0.62	0.064	7
1280006	Soil	3.1	43.9	18.9	154	0.1	46.1	11.8	326	3.80	11.9	4.1	1.8	22	0.7	1.5	0.3	18	0.11	0.079	7
1280007	Soil	4.5	37.0	15.2	119	0.8	30.8	4.2	88	2.70	11.4	3.8	1.9	21	0.6	1.6	0.3	37	0.06	0.047	11
1280008	Soil	4.6	35.4	11.3	117	0.6	29.4	6.2	209	2.07	14.6	4.6	0.8	47	0.7	2.2	0.2	54	0.36	0.082	7
1280009	Soil	5.2	20.4	14.6	88	0.3	20.2	4.0	141	2.23	18.2	1.5	0.4	17	0.5	2.2	0.3	67	0.02	0.069	8
1280010	Soil	5.7	24.0	16.0	121	0.4	22.2	3.9	102	2.41	16.6	<0.5	0.2	18	1.5	2.6	0.3	88	0.02	0.092	9
1280011	Soil	5.2	26.8	17.3	102	2.5	21.6	3.7	93	1.86	9.5	2.9	0.6	68	0.8	2.2	0.2	83	0.03	0.139	8
1280012	Soil	4.3	19.6	14.1	150	0.2	24.0	6.8	193	2.56	9.1	0.8	0.3	8	1.1	1.7	0.2	64	0.02	0.075	10
1280013	Soil	5.5	21.3	13.8	117	<0.1	23.0	4.8	155	2.84	15.9	0.9	1.8	10	0.3	2.3	0.2	83	0.02	0.065	9
1280014	Soil	6.0	27.1	15.7	111	0.5	22.5	4.9	183	3.05	17.6	1.1	2.1	13	0.4	2.4	0.3	91	0.03	0.095	10
1280015	Soil	5.0	18.0	14.8	101	0.4	19.9	4.9	184	2.92	17.5	1.3	2.3	13	0.4	2.1	0.3	93	0.04	0.079	11
1280016	Soil	2.5	46.1	15.9	192	1.7	53.8	6.0	142	2.29	15.1	6.2	0.9	60	1.1	1.5	0.2	42	0.89	0.163	10
1280017	Soil	2.5	42.4	15.6	279	1.5	72.8	7.5	167	2.58	16.2	6.6	1.4	78	1.7	2.2	0.2	55	0.96	0.209	13
1280018	Soil	2.4	42.5	16.1	199	1.7	55.1	8.0	149	3.07	12.1	4.4	1.5	55	0.9	1.2	0.2	38	0.83	0.156	12
1280019	Soil	3.4	57.9	17.3	252	1.9	65.5	8.6	170	3.44	15.4	5.0	1.9	71	1.5	1.8	0.3	49	1.07	0.213	18
1280020	Soil	3.1	49.6	18.9	189	2.5	57.3	9.6	169	3.54	14.0	3.3	2.1	62	1.1	1.2	0.3	34	0.75	0.137	8
1280021	Soil	3.9	61.0	26.3	193	2.9	65.8	14.1	292	4.61	21.2	3.1	2.1	51	0.7	1.4	0.3	42	0.32	0.141	7
1280022	Soil	3.6	51.7	24.9	124	1.8	37.6	9.3	260	3.73	21.3	2.8	1.5	43	0.5	1.8	0.3	40	0.04	0.122	6
1280023	Soil	2.3	33.8	11.8	82	0.8	24.8	5.2	124	2.10	10.6	3.6	0.7	25	0.2	1.0	0.2	29	0.05	0.101	5
1280024	Soil	3.2	47.9	15.7	201	0.9	60.4	10.7	164	3.17	25.3	3.4	2.5	40	0.7	1.7	0.2	31	0.17	0.087	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1279995	Soil	10	<0.01	80	0.005	1	0.24	0.020	0.03	<0.1	0.01	0.5	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1279996	Soil	23	0.06	488	<0.001	1	0.88	0.008	0.04	<0.1	0.09	2.7	<0.1	0.06	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1279997	Soil	23	0.11	179	0.001	1	1.08	0.006	0.07	<0.1	0.13	2.5	0.2	0.08	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279998	Soil	30	0.11	96	0.005	1	1.00	0.005	0.04	0.1	0.07	0.9	0.1	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1279999	Soil	33	0.23	271	0.001	2	1.60	0.004	0.09	<0.1	0.07	3.3	0.1	<0.05	5	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280000	Soil	27	0.07	249	0.002	1	1.14	0.003	0.06	<0.1	0.06	2.4	0.1	<0.05	5	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280001	Soil	12	0.07	2554	0.005	2	0.67	0.005	0.05	0.1	0.04	1.1	<0.1	0.07	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280002	Soil	26	0.36	2218	0.002	2	1.18	0.005	0.04	<0.1	0.28	2.8	0.1	0.08	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280003	Soil	27	0.06	630	0.006	1	0.60	0.011	0.02	<0.1	0.04	0.7	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280004	Soil	20	0.02	352	0.002	2	0.53	0.004	0.04	<0.1	0.03	0.8	<0.1	<0.05	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280005	Soil	17	0.12	2181	0.003	2	0.85	0.005	0.05	<0.1	0.21	3.7	0.1	0.06	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280006	Soil	24	0.27	2632	0.002	2	0.82	0.002	0.03	<0.1	0.06	2.4	<0.1	0.07	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280007	Soil	16	0.12	3133	0.002	2	0.80	0.002	0.05	<0.1	0.12	2.1	0.1	0.06	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280008	Soil	20	0.19	2051	0.004	1	0.88	0.009	0.05	0.1	0.14	1.4	0.2	0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280009	Soil	16	0.11	642	0.005	1	0.67	0.003	0.05	0.1	0.04	0.7	0.2	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1280010	Soil	17	0.08	623	0.005	2	0.76	0.004	0.05	0.1	0.05	0.5	0.2	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280011	Soil	20	0.06	587	0.005	2	0.68	0.011	0.06	<0.1	0.12	0.9	0.2	0.06	2	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280012	Soil	22	0.10	385	0.005	2	0.93	0.005	0.05	0.1	0.03	0.7	0.1	<0.05	4	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280013	Soil	22	0.16	236	0.006	3	0.95	0.003	0.05	0.1	0.03	1.6	0.2	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1280014	Soil	26	0.15	426	0.005	3	1.21	0.003	0.07	0.1	0.05	1.8	0.3	<0.05	5	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1280015	Soil	22	0.15	404	0.011	1	1.04	0.004	0.06	0.2	0.03	1.7	0.2	<0.05	5	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280016	Soil	25	0.10	662	0.002	4	0.92	0.006	0.07	<0.1	0.22	2.9	0.1	0.11	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280017	Soil	33	0.11	846	0.004	5	1.03	0.007	0.09	<0.1	0.24	3.5	0.2	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280018	Soil	34	0.14	731	0.003	7	1.07	0.012	0.08	<0.1	0.24	4.1	0.1	<0.05	2	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280019	Soil	44	0.21	1693	0.005	7	1.06	0.009	0.11	0.1	0.35	5.2	0.2	0.08	3	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280020	Soil	33	0.13	883	0.003	6	1.09	0.012	0.12	<0.1	0.32	5.1	0.2	0.10	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280021	Soil	42	0.15	671	0.002	4	1.30	0.008	0.11	<0.1	0.30	6.2	0.2	0.05	3	4.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280022	Soil	35	0.15	466	0.004	4	1.22	0.007	0.10	<0.1	0.16	3.1	0.2	0.11	3	3.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280023	Soil	21	0.07	310	0.004	4	0.72	0.010	0.08	<0.1	0.10	1.6	0.1	0.07	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280024	Soil	22	0.13	523	0.004	2	0.80	0.006	0.08	<0.1	0.13	3.0	0.1	0.12	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1279995	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279996	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279997	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279998	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279999	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280000	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280017	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280019	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280021	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280022	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280023	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279995	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279996	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279997	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279998	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279999	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280000	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280001	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280002	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280003	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280004	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280005	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280006	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280007	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280008	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280009	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280010	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280011	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280012	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280013	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280014	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280015	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280016	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280017	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280018	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280019	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280020	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280021	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280022	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280023	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280024	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280025	Soil		4.2	35.9	17.9	96	0.6	25.4	6.4	223	2.59	29.7	3.8	0.5	26	0.3	2.2	0.3	44	0.06	0.104	8
1280026	Soil		3.4	43.1	14.9	129	0.8	39.2	6.2	131	2.47	16.8	4.1	0.5	21	0.4	1.3	0.2	35	0.05	0.090	6
1280027	Soil		5.0	78.1	25.5	154	2.3	43.6	6.6	121	4.07	22.9	6.5	1.6	29	0.2	2.2	0.3	41	0.03	0.088	6
1280028	Soil		6.0	73.5	24.7	116	1.4	32.1	4.5	82	4.22	27.1	6.6	1.0	12	<0.1	2.1	0.3	49	<0.01	0.083	4
1280029	Soil		3.4	33.2	15.9	61	1.0	13.0	2.6	58	2.44	24.6	2.5	0.5	20	0.1	1.2	0.3	56	0.01	0.072	4
1280030	Soil		2.7	39.7	29.9	82	1.8	17.9	3.9	180	3.17	32.9	2.8	1.1	35	0.1	1.1	0.3	43	0.01	0.084	3
1280031	Soil		2.5	55.2	30.0	75	1.3	22.1	5.2	203	2.86	43.7	3.0	1.6	43	0.2	1.4	0.4	35	0.03	0.092	4
1280032	Soil		6.4	25.3	18.2	67	0.6	14.7	3.5	128	1.98	30.5	4.4	0.2	21	0.2	3.0	0.3	55	0.09	0.096	7
1280033	Soil		15.4	16.9	16.7	36	2.4	12.1	0.8	73	0.96	13.8	1.6	0.7	38	0.3	8.4	0.3	57	0.26	0.067	2
1280034	Soil		16.4	8.7	18.0	37	0.6	10.1	1.2	35	1.16	14.3	<0.5	0.3	18	0.2	6.3	0.2	66	0.03	0.037	1
1280035	Soil		11.2	12.1	16.3	57	1.0	11.5	1.2	37	0.95	21.8	2.0	0.3	23	0.2	4.8	0.2	53	0.01	0.095	3
1280036	Soil		3.8	74.0	31.1	41	2.0	69.6	21.4	1406	5.88	67.3	3.5	0.8	48	0.2	3.0	0.4	69	1.15	0.195	4
1280037	Soil		6.1	65.5	44.6	25	1.5	32.8	7.0	125	3.51	25.8	1.6	0.9	59	<0.1	4.8	0.5	49	0.02	0.086	2
1280038	Soil		5.1	70.3	35.8	53	1.2	81.0	19.2	936	6.15	209.4	<0.5	1.2	37	0.2	3.9	0.4	80	0.22	0.125	5
1280039	Soil		7.8	54.9	45.6	37	2.4	16.9	3.7	127	2.84	174.5	2.0	0.3	66	0.1	4.3	0.4	64	0.03	0.158	4
1280040	Soil		1.7	14.3	7.5	27	0.4	9.6	2.6	104	0.95	13.9	0.9	0.1	8	0.1	0.7	0.1	21	0.02	0.086	2
1280041	Soil		4.9	21.7	22.1	64	0.2	16.3	4.0	147	1.89	37.1	<0.5	0.2	15	0.4	1.6	0.3	38	0.03	0.092	6
1280042	Soil		2.1	21.9	27.2	115	0.1	23.8	11.3	331	3.05	18.1	<0.5	0.3	17	0.3	1.0	0.3	30	0.05	0.123	4
1280043	Soil		1.7	18.1	18.2	63	<0.1	12.2	4.4	150	2.55	12.2	1.3	0.8	10	0.2	0.7	0.2	30	0.02	0.064	3
1280044	Soil		1.7	20.8	16.5	100	<0.1	23.1	11.7	280	2.62	15.6	3.2	0.8	11	0.2	0.8	0.3	33	0.02	0.060	4
1280045	Soil		1.8	44.3	41.0	174	0.1	55.9	51.0	1138	4.90	32.7	0.7	3.1	25	0.2	1.2	0.4	38	0.06	0.074	3
1280046	Soil		2.1	24.0	15.5	107	<0.1	28.5	12.9	270	3.10	16.2	0.9	1.4	35	0.2	1.0	0.2	33	0.03	0.071	7
1280047	Soil		2.6	21.2	17.6	80	0.2	19.8	6.8	157	3.59	17.7	<0.5	0.6	15	0.2	1.1	0.3	51	0.03	0.078	8
1280048	Soil		1.9	28.1	19.1	112	0.2	32.9	11.0	201	3.34	20.2	<0.5	3.0	19	0.2	1.1	0.3	34	0.03	0.048	6
1280049	Soil		3.1	78.2	39.8	308	0.3	65.2	36.8	490	7.40	36.4	<0.5	4.4	97	0.4	1.4	0.4	38	0.02	0.139	4
1280050	Soil		1.4	20.1	19.6	74	<0.1	16.5	6.0	128	3.54	14.7	<0.5	1.5	15	<0.1	0.7	0.4	46	<0.01	0.074	4
1280051	Soil		8.0	143.8	16.3	74	0.3	417.4	77.6	694	6.66	27.1	<0.5	13.2	257	0.3	3.2	<0.1	187	2.99	0.772	76
1280052	Soil		17.0	113.1	22.1	377	0.7	461.8	84.0	1851	6.59	129.9	2.0	10.4	169	3.7	8.3	0.2	248	1.97	0.589	66
1280053	Soil		20.2	104.6	35.8	431	0.8	460.1	71.3	844	7.62	119.3	2.0	8.2	106	4.2	10.3	0.1	218	2.06	0.474	67
1280054	Soil		15.7	85.3	28.9	345	0.5	356.5	51.8	605	7.35	96.5	4.0	5.5	84	3.0	11.3	<0.1	178	1.06	0.455	61

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1280025	Soil	24	0.12	321	0.005	3	0.67	0.004	0.08	0.1	0.10	0.9	0.2	0.09	3	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280026	Soil	20	0.13	453	0.007	2	0.83	0.011	0.06	<0.1	0.09	1.9	0.1	0.06	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280027	Soil	29	0.13	378	0.006	3	0.90	0.004	0.07	<0.1	0.36	3.0	0.2	0.05	3	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280028	Soil	31	0.05	479	0.003	4	0.70	0.004	0.06	<0.1	0.23	2.5	0.2	<0.05	3	5.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280029	Soil	20	0.02	705	0.003	3	0.63	0.004	0.06	<0.1	0.13	0.8	0.1	<0.05	3	1.9	0.2	N.A.	N.A.	N.A.	N.A.
1280030	Soil	20	0.06	1146	0.002	5	0.78	0.007	0.09	<0.1	0.10	1.8	0.1	0.07	3	3.1	0.2	N.A.	N.A.	N.A.	N.A.
1280031	Soil	19	0.15	993	0.003	5	1.09	0.010	0.10	<0.1	0.20	3.1	0.2	0.08	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280032	Soil	15	0.08	505	0.006	2	0.61	0.007	0.07	0.1	0.20	0.6	0.3	0.06	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280033	Soil	9	0.01	765	<0.001	3	0.19	0.003	0.08	0.2	3.48	0.8	0.8	0.14	<1	5.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280034	Soil	8	0.01	306	<0.001	2	0.16	0.004	0.08	0.1	0.09	0.4	0.9	0.15	<1	2.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280035	Soil	9	0.01	105	0.002	2	0.19	0.006	0.05	<0.1	0.24	0.2	0.4	<0.05	<1	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280036	Soil	23	0.10	903	0.002	4	0.68	0.004	0.09	<0.1	0.18	5.3	0.2	0.07	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280037	Soil	15	0.01	155	<0.001	1	0.30	0.002	0.09	<0.1	0.05	4.2	0.3	<0.05	1	4.1	0.2	N.A.	N.A.	N.A.	N.A.
1280038	Soil	40	0.07	327	0.002	2	0.70	0.004	0.10	0.1	0.11	6.0	0.2	<0.05	2	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280039	Soil	24	0.02	232	0.006	2	0.59	0.008	0.11	<0.1	0.09	1.9	0.5	0.18	2	2.9	0.2	N.A.	N.A.	N.A.	N.A.
1280040	Soil	10	0.02	63	0.003	2	0.31	0.012	0.04	<0.1	0.04	0.4	<0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280041	Soil	15	0.04	132	0.003	2	0.49	0.006	0.05	0.1	0.04	0.6	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1280042	Soil	23	0.10	168	0.003	2	0.72	0.004	0.09	<0.1	0.05	0.8	0.2	0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1280043	Soil	20	0.13	127	0.004	2	0.88	0.012	0.06	<0.1	0.04	1.2	0.1	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280044	Soil	16	0.09	163	0.003	2	0.82	0.004	0.08	<0.1	0.03	1.7	0.2	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280045	Soil	32	0.50	273	0.001	1	1.62	0.003	0.08	<0.1	0.04	5.2	0.3	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280046	Soil	23	0.25	75	0.006	1	1.01	0.004	0.05	0.1	0.04	1.5	0.2	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280047	Soil	25	0.19	127	0.005	2	1.07	0.003	0.05	0.2	0.07	1.1	0.1	<0.05	4	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280048	Soil	27	0.34	137	0.005	1	1.27	0.004	0.07	<0.1	0.05	2.4	0.2	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280049	Soil	35	0.34	619	0.008	2	1.52	0.014	0.09	<0.1	0.07	9.9	0.7	0.10	5	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280050	Soil	24	0.11	127	0.002	2	0.97	0.005	0.05	<0.1	0.05	1.9	0.1	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280051	Soil	257	0.51	1402	0.005	15	1.35	0.005	0.22	0.1	0.18	23.0	0.5	<0.05	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280052	Soil	198	0.36	2002	0.005	16	1.35	0.007	0.16	0.2	0.58	16.1	0.6	<0.05	4	4.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280053	Soil	120	0.37	2403	0.006	13	0.93	0.007	0.12	0.2	0.89	13.2	0.6	<0.05	3	5.1	<0.2	N.A.	N.A.	N.A.	N.A.
1280054	Soil	107	0.14	4136	0.006	11	0.99	0.008	0.12	0.3	0.51	11.5	0.5	<0.05	2	3.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1280025	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280026	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280027	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280028	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280029	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280030	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280031	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280032	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280033	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280034	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280035	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280036	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280037	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280038	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280039	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280040	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280041	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280042	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280043	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280044	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280045	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280046	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280047	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280048	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280049	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280050	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280051	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280052	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280053	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280054	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280025	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280026	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280027	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280028	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280029	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280030	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280031	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280032	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280033	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280034	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280035	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280036	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280037	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280038	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280039	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280040	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280041	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280042	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280043	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280044	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280045	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280046	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280047	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280048	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280049	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280050	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280051	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280052	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280053	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280054	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280055	Soil		15.0	104.5	26.9	295	0.5	429.8	64.4	774	8.79	109.5	3.6	8.1	85	3.4	6.3	<0.1	155	1.20	0.495	66
1280056	Soil		14.8	114.0	23.8	420	0.6	523.9	67.3	866	8.00	242.2	3.1	10.4	174	6.3	9.1	<0.1	177	2.36	0.627	78
1280057	Soil		10.8	82.5	17.0	252	0.5	364.4	46.4	488	6.13	158.4	1.5	8.5	106	2.4	5.7	0.1	128	1.27	0.517	71
1280058	Soil		8.0	50.6	14.2	248	0.8	213.8	31.4	518	3.97	83.7	1.8	3.1	85	2.1	4.4	0.1	84	1.03	0.342	40
1280059	Soil		15.7	29.8	10.3	163	0.3	49.4	6.1	58	1.97	48.6	2.9	0.3	12	0.2	3.7	0.2	84	0.03	0.082	11
1280060	Soil		6.2	10.6	5.5	65	0.7	17.3	2.2	34	0.82	12.5	1.9	0.2	8	0.2	1.3	0.1	57	0.02	0.093	7
1280061	Soil		18.2	22.1	10.1	255	0.3	55.2	5.8	65	2.29	40.6	7.6	1.2	12	0.7	4.5	0.2	120	0.02	0.080	13
1280062	Soil		13.1	12.4	6.1	88	0.3	24.4	2.6	26	1.01	22.4	1.9	0.3	6	0.2	2.4	0.1	72	0.01	0.070	11
1280063	Soil		14.3	13.0	6.0	117	0.3	26.8	2.3	47	0.88	17.8	3.2	0.2	10	0.9	1.9	0.1	50	0.07	0.107	8
1280064	Soil		7.8	26.9	57.3	161	0.8	38.9	1.8	48	0.90	21.9	11.6	1.6	49	4.3	4.7	0.3	39	0.19	0.051	8
1280065	Soil		2.0	5.9	4.0	32	0.7	7.0	1.3	26	0.40	3.6	1.6	<0.1	6	<0.1	0.6	<0.1	17	0.02	0.041	2
1280066	Soil		1.6	15.9	5.4	61	0.3	10.1	2.1	62	0.66	7.1	2.3	<0.1	7	0.1	0.9	<0.1	15	0.02	0.052	2
1280067	Soil		3.5	10.9	10.7	59	0.5	8.1	1.5	27	0.84	7.5	3.3	0.3	5	0.2	1.9	0.2	22	<0.01	0.034	2
1280068	Soil		1.7	19.0	7.5	72	0.6	11.4	7.9	367	0.92	6.4	1.6	0.1	13	0.3	0.8	0.1	13	0.05	0.051	2
1280069	Soil		12.9	28.4	21.7	167	0.9	31.4	5.6	84	2.39	28.3	3.3	0.3	12	0.5	5.3	0.3	67	0.01	0.060	5
1280070	Soil		12.4	64.9	24.8	96	1.8	25.4	2.9	51	2.03	60.9	6.5	1.1	49	0.4	8.8	0.2	83	0.06	0.153	4
1280071	Soil		5.5	54.7	20.6	197	1.3	54.9	11.9	213	3.47	57.2	6.8	1.4	66	0.9	3.5	0.3	43	0.09	0.106	5
1280072	Soil		6.8	49.4	17.5	191	0.9	49.9	7.6	154	2.61	55.8	12.3	1.6	50	2.5	3.4	0.3	46	0.05	0.104	5
1280073	Soil		3.6	34.3	12.0	336	0.9	68.7	9.1	223	3.03	40.0	5.0	1.2	62	4.3	2.1	0.2	29	0.43	0.077	4
1280074	Soil		1.7	42.9	12.1	248	1.1	66.1	7.6	163	2.24	36.0	13.8	0.9	94	1.7	2.4	0.2	32	1.45	0.154	11
1280075	Soil		1.9	27.8	8.8	120	1.3	36.1	5.0	150	1.31	16.2	2.5	0.6	66	0.6	1.3	0.1	25	0.75	0.091	4
1280076	Soil		2.7	13.9	9.5	74	1.0	16.9	2.7	34	1.39	24.1	6.3	0.1	16	0.1	2.1	0.1	34	0.03	0.059	3
1280077	Soil		8.3	14.8	13.7	82	0.2	18.5	2.2	33	1.24	27.1	0.8	0.2	13	0.1	2.9	0.2	69	0.02	0.048	7
1280078	Soil		1.0	27.6	7.6	134	0.9	31.0	3.6	166	1.36	37.7	14.2	0.3	82	1.8	4.1	0.1	25	2.08	0.166	8
1280079	Soil		1.7	38.8	14.8	135	1.4	45.4	6.8	120	2.50	68.3	18.4	1.0	69	0.7	5.1	0.2	38	1.16	0.125	6
1280080	Soil		0.8	24.8	5.9	57	0.9	26.6	3.2	65	1.00	14.4	12.6	0.3	81	0.5	1.5	0.1	14	1.71	0.124	5
1280081	Soil		3.5	47.0	23.8	104	1.4	35.6	5.4	90	2.92	116.3	48.3	1.4	119	0.2	3.5	0.2	39	0.06	0.121	7
1280082	Soil		2.3	31.5	13.8	112	0.6	33.1	6.0	92	2.59	47.3	8.9	0.7	38	0.2	3.1	0.2	36	0.03	0.097	4
1280083	Soil		2.4	59.0	15.8	158	1.5	57.2	10.6	226	3.25	48.4	9.6	2.8	81	0.4	3.0	0.2	35	0.38	0.089	7
1280084	Soil		0.3	13.7	1.8	10	0.7	6.8	0.7	18	0.38	1.4	0.9	<0.1	55	<0.1	0.2	<0.1	6	0.33	0.040	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1280055	Soil		125	0.14	4307	0.008	14	1.02	0.006	0.15	0.1	0.76	14.4	0.5	0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280056	Soil		169	0.51	1934	0.007	19	0.99	0.007	0.19	0.2	1.67	17.0	0.5	0.07	3	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280057	Soil		136	0.24	2353	0.007	11	1.10	0.009	0.12	0.2	3.19	13.0	0.4	<0.05	3	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280058	Soil		72	0.23	1243	0.006	12	0.83	0.013	0.11	0.2	1.43	7.1	0.3	0.10	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280059	Soil		12	0.03	253	0.003	2	0.40	0.005	0.06	0.1	0.30	0.4	0.3	0.05	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280060	Soil		14	0.04	271	0.003	2	0.47	0.011	0.04	<0.1	0.19	0.3	0.2	<0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1280061	Soil		23	0.07	516	0.003	4	0.71	0.005	0.05	0.1	0.68	1.4	0.4	0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280062	Soil		13	0.04	130	0.003	3	0.58	0.007	0.05	0.1	0.34	0.5	0.4	<0.05	3	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280063	Soil		11	0.03	473	0.003	2	0.55	0.010	0.04	0.1	0.67	0.6	0.5	0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280064	Soil		17	0.03	536	0.002	8	0.27	0.004	0.09	<0.1	1.28	1.5	0.6	0.09	2	4.7	0.3	N.A.	N.A.	N.A.	N.A.
1280065	Soil		10	0.01	42	0.003	2	0.19	0.012	0.04	<0.1	0.12	0.5	<0.1	<0.05	1	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280066	Soil		7	0.03	33	0.005	<1	0.38	0.020	0.03	<0.1	0.06	0.5	0.1	0.07	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1280067	Soil		8	0.01	89	<0.001	3	0.30	0.003	0.05	<0.1	0.08	0.8	0.2	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280068	Soil		8	0.03	75	0.009	1	0.62	0.021	0.03	<0.1	0.08	0.8	0.1	<0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280069	Soil		9	0.02	118	0.004	4	0.41	0.007	0.06	0.1	0.17	0.9	0.3	<0.05	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280070	Soil		16	0.03	1448	0.002	3	0.63	0.003	0.08	<0.1	1.84	2.4	1.0	0.07	2	7.0	<0.2	N.A.	N.A.	N.A.	N.A.
1280071	Soil		22	0.09	1607	0.001	4	0.87	0.006	0.09	<0.1	0.51	3.8	0.3	<0.05	2	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280072	Soil		23	0.09	1152	0.002	4	1.09	0.004	0.08	<0.1	0.65	3.0	0.3	0.05	3	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280073	Soil		15	0.12	622	<0.001	1	0.81	0.007	0.06	<0.1	0.90	3.0	0.2	<0.05	2	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1280074	Soil		28	0.14	682	0.003	12	0.90	0.011	0.08	<0.1	1.75	2.7	0.1	0.08	2	6.2	<0.2	N.A.	N.A.	N.A.	N.A.
1280075	Soil		14	0.09	1249	0.003	5	0.76	0.018	0.06	0.1	0.55	1.6	0.1	0.08	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280076	Soil		11	0.02	135	0.002	2	0.37	0.010	0.05	0.1	0.27	0.5	0.1	<0.05	2	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280077	Soil		11	0.02	141	0.002	3	0.32	0.006	0.05	<0.1	0.08	0.5	0.2	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280078	Soil		20	0.07	624	0.003	7	0.72	0.017	0.05	<0.1	1.70	1.1	<0.1	0.07	2	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280079	Soil		28	0.07	659	0.002	5	0.77	0.006	0.09	0.1	1.53	3.5	0.1	0.07	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280080	Soil		13	0.08	411	0.004	6	0.84	0.020	0.04	<0.1	1.41	0.9	0.1	0.08	2	5.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280081	Soil		23	0.10	460	0.002	4	1.21	0.008	0.11	<0.1	14.71	2.2	0.5	<0.05	4	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280082	Soil		19	0.07	240	0.002	2	0.79	0.006	0.08	<0.1	0.63	1.4	0.2	<0.05	3	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1280083	Soil		28	0.20	1269	0.001	4	1.14	0.006	0.12	<0.1	3.58	4.3	0.2	<0.05	3	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280084	Soil		4	0.04	204	0.006	2	0.35	0.037	0.03	<0.1	0.14	0.6	<0.1	<0.05	1	1.3	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1280055	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280056	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280057	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280058	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280059	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280060	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280061	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280062	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280063	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280064	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280065	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280066	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280067	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280068	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280069	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280070	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280071	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280072	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280073	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280074	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280075	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280076	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280077	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280078	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280079	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280080	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280081	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280082	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280083	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280084	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280055	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280056	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280057	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280058	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280059	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280060	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280061	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280062	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280063	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280064	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280065	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280066	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280067	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280068	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280069	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280070	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280071	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280072	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280073	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280074	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280075	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280076	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280077	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280078	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280079	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280080	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280081	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280082	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280083	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280084	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280085	Soil		0.6	5.0	2.3	11	0.4	3.2	0.7	16	0.31	2.0	<0.5	<0.1	6	<0.1	0.2	<0.1	10	0.02	0.023	1
1280086	Soil		1.3	30.1	13.9	47	0.6	11.3	1.5	29	1.39	7.2	1.8	1.1	66	0.1	0.4	0.2	22	0.08	0.044	2
1280087	Soil		3.5	54.1	15.7	159	1.2	47.8	7.7	166	2.86	10.9	3.7	1.1	93	0.6	0.8	0.2	30	0.28	0.106	4
1280088	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280089	Soil		2.1	76.3	16.9	146	0.4	38.8	11.0	186	2.90	9.6	9.0	1.8	63	0.2	0.9	0.2	31	0.04	0.061	3
1280090	Soil		1.3	32.7	7.8	69	1.2	41.2	4.2	232	1.25	3.5	3.5	0.8	382	0.1	0.4	0.2	17	1.55	0.100	3
1280091	Soil		2.4	30.5	17.0	91	0.5	26.6	6.2	176	2.87	11.4	2.7	1.5	190	0.1	1.1	0.3	33	0.09	0.084	5
1280092	Soil		4.8	47.9	24.2	141	0.4	36.5	9.2	320	3.16	225.8	0.9	0.5	16	0.2	3.0	0.5	51	0.03	0.135	7
1280093	Soil		4.2	24.9	11.8	48	2.0	17.1	3.5	172	1.26	150.9	<0.5	0.4	13	<0.1	2.1	0.2	41	0.10	0.092	4
1280094	Soil		6.3	31.9	30.9	40	1.9	14.8	3.0	93	2.54	266.2	0.8	0.5	37	0.1	3.7	0.2	50	0.04	0.108	3
1280095	Soil		12.0	21.0	38.7	27	1.4	11.0	1.9	39	1.64	37.3	1.3	0.5	29	<0.1	2.7	0.6	49	0.03	0.078	2
1280096	Soil		0.9	13.8	11.9	31	<0.1	11.4	5.9	131	0.83	8.5	<0.5	0.3	14	<0.1	0.4	0.2	11	0.11	0.052	3
1280097	Soil		1.6	20.4	16.0	81	0.1	19.3	11.1	276	2.65	20.8	<0.5	1.0	10	0.1	1.0	0.3	32	0.02	0.071	5
1280098	Soil		1.9	24.2	23.3	116	0.1	27.2	20.5	970	2.75	16.2	<0.5	0.9	10	0.2	1.0	0.3	33	0.03	0.086	6
1280099	Soil		2.9	38.5	35.0	157	0.1	63.6	33.7	904	3.81	28.7	2.3	2.5	26	<0.1	1.1	0.3	27	0.04	0.062	4
1280100	Soil		2.1	33.3	23.5	120	0.2	36.3	28.7	1249	3.99	16.0	3.3	1.9	11	0.2	0.9	0.3	38	0.03	0.109	5
1280101	Soil		0.6	7.1	4.3	20	<0.1	4.0	2.1	158	0.80	2.1	<0.5	0.1	7	<0.1	0.2	<0.1	12	0.04	0.056	1
1280102	Soil		1.8	24.5	14.1	72	0.2	27.8	17.9	426	1.96	10.7	1.2	0.3	10	0.2	0.6	0.2	27	0.08	0.085	3
1280103	Soil		1.9	28.1	30.6	104	0.2	34.7	15.2	462	3.37	22.4	<0.5	1.9	17	0.2	0.7	0.3	36	0.03	0.071	4
1280104	Soil		2.8	33.4	35.0	73	0.2	17.7	6.0	154	3.80	19.1	1.3	2.0	19	<0.1	0.8	0.3	26	0.03	0.082	4
1280105	Soil		2.0	24.8	16.4	93	<0.1	24.3	10.5	273	3.52	18.3	1.9	2.2	9	0.2	1.1	0.3	36	0.03	0.060	5
1280106	Soil		1.7	25.0	13.0	100	<0.1	30.6	16.3	326	2.54	15.1	0.8	1.6	9	0.2	1.0	0.2	27	0.03	0.042	7
1280107	Soil		2.1	41.3	26.5	119	0.2	29.9	9.5	334	4.05	23.0	0.8	2.9	32	0.1	1.2	0.3	32	0.01	0.082	2
1280108	Soil		6.6	32.7	18.1	107	0.4	27.5	7.4	199	2.35	21.4	1.6	1.4	76	0.5	2.4	0.3	22	0.19	0.046	3
1280109	Soil		2.1	37.5	27.7	94	0.6	26.5	8.3	257	2.80	18.5	3.1	1.9	19	0.1	0.6	0.3	33	0.04	0.088	2
1280110	Soil		1.7	34.1	26.5	111	0.2	23.8	9.3	241	4.12	17.4	3.3	2.4	14	0.1	0.8	0.3	43	0.02	0.079	4
1280111	Soil		0.9	23.7	26.3	72	0.3	17.1	14.2	343	2.52	9.6	2.2	0.8	8	<0.1	0.4	0.3	24	0.02	0.072	2
1280112	Soil		1.7	44.1	31.8	71	0.6	16.9	5.8	137	3.03	36.4	1.7	2.5	17	<0.1	1.0	0.4	45	0.02	0.070	3
1280113	Soil		1.5	44.2	44.0	95	0.8	18.6	8.1	155	3.63	32.0	3.0	2.9	16	<0.1	1.3	0.3	43	0.02	0.097	3
1280114	Soil		1.3	28.8	27.4	68	0.7	14.1	4.9	184	3.02	18.5	4.1	1.7	19	0.1	0.7	0.3	42	0.02	0.109	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1280085	Soil		4	0.01	391	0.004	3	0.17	0.022	0.03	<0.1	0.09	0.3	<0.1	<0.05	<1	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280086	Soil		16	0.08	681	0.002	4	0.70	0.010	0.08	<0.1	0.15	1.1	0.1	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280087	Soil		30	0.17	1829	0.002	3	1.04	0.011	0.08	<0.1	0.42	2.4	0.1	<0.05	3	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280088	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	1.7	15.8	6.8	36
1280089	Soil		55	0.34	2167	0.002	3	1.47	0.007	0.06	<0.1	0.27	2.7	<0.1	<0.05	4	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280090	Soil		23	0.28	1703	0.002	3	1.00	0.013	0.04	<0.1	0.25	1.6	<0.1	0.08	2	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1280091	Soil		30	0.17	578	0.002	2	1.00	0.007	0.06	<0.1	0.13	1.5	0.1	<0.05	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280092	Soil		19	0.03	128	0.002	2	0.47	0.003	0.09	0.1	0.07	1.1	0.3	<0.05	2	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280093	Soil		14	0.03	144	0.005	4	0.37	0.006	0.08	<0.1	0.11	1.7	0.2	0.06	2	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280094	Soil		14	0.02	181	0.004	1	0.43	0.014	0.12	<0.1	0.07	1.4	0.4	0.08	2	5.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280095	Soil		9	0.04	326	<0.001	4	0.55	0.006	0.09	<0.1	0.20	1.1	0.7	<0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
1280096	Soil		7	0.06	178	0.001	<1	0.46	0.017	0.09	<0.1	0.02	1.0	0.2	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280097	Soil		17	0.12	82	0.005	<1	0.85	0.003	0.10	<0.1	0.01	1.6	0.2	<0.05	4	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1280098	Soil		18	0.20	182	0.004	2	1.02	0.005	0.09	<0.1	0.03	1.7	0.3	<0.05	4	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280099	Soil		19	0.18	204	0.005	1	1.03	0.006	0.13	<0.1	0.05	5.7	0.5	<0.05	3	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1280100	Soil		31	0.23	178	0.005	3	1.33	0.005	0.15	<0.1	0.05	3.3	0.3	<0.05	4	2.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280101	Soil		8	0.03	119	0.004	<1	0.38	0.025	0.04	<0.1	0.05	0.5	<0.1	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280102	Soil		20	0.13	141	0.006	2	0.76	0.019	0.08	<0.1	0.05	1.5	0.2	<0.05	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280103	Soil		25	0.18	190	0.002	2	1.27	0.004	0.12	<0.1	0.05	3.0	0.4	<0.05	4	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280104	Soil		29	0.19	132	0.002	2	1.18	0.009	0.10	<0.1	0.08	2.1	0.3	0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280105	Soil		24	0.21	95	0.003	1	1.13	0.003	0.04	0.1	0.03	2.0	0.2	<0.05	4	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1280106	Soil		20	0.25	94	0.005	1	0.94	0.003	0.04	<0.1	0.03	1.8	0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280107	Soil		28	0.28	368	0.003	2	1.31	0.006	0.07	<0.1	0.03	4.5	0.3	0.06	5	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280108	Soil		10	0.03	1278	<0.001	2	0.41	0.004	0.06	<0.1	0.44	3.1	0.3	0.08	1	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280109	Soil		28	0.18	432	0.001	1	1.18	0.006	0.07	<0.1	0.08	4.6	0.1	<0.05	3	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280110	Soil		28	0.21	219	0.002	<1	1.41	0.003	0.06	<0.1	0.06	3.2	0.1	<0.05	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280111	Soil		20	0.13	139	0.002	1	1.06	0.012	0.05	<0.1	0.06	1.9	<0.1	<0.05	3	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280112	Soil		27	0.17	300	0.003	<1	1.16	0.008	0.07	<0.1	0.07	4.4	0.2	<0.05	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280113	Soil		24	0.14	184	0.002	<1	1.01	0.006	0.07	<0.1	0.08	4.9	0.2	<0.05	4	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280114	Soil		23	0.09	235	0.001	<1	1.02	0.004	0.08	<0.1	0.14	2.4	0.1	0.07	4	1.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1280085	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280086	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280087	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280088	Soil		0.2	10.1	1.4	23	0.63	2.8	2.3	0.1	105	0.3	0.3	0.1	18	0.35	0.050	3	10	0.04	699	0.002
1280089	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280090	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280091	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280092	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280093	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280094	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280095	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280096	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280097	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280098	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280099	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280100	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280101	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280102	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280103	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280104	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280105	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280106	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280107	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280108	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280109	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280110	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280111	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280112	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280113	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280114	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280085	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280086	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280087	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280088	Soil	<20	0.34	0.012	0.05	<0.1	0.07	0.6	<0.1	0.12	2	0.6	<0.2
1280089	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280090	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280091	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280092	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280093	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280094	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280095	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280096	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280097	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280098	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280099	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280100	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280101	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280102	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280103	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280104	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280105	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280106	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280107	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280108	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280109	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280110	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280111	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280112	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280113	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280114	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280115	Soil	1.5	37.4	31.6	79	0.6	16.7	6.1	233	4.03	28.6	3.6	2.9	27	0.2	0.8	0.3	42	0.03	0.127	4
1280116	Soil	0.7	17.3	12.3	31	0.4	7.2	2.6	42	1.50	7.1	1.2	0.7	9	<0.1	0.3	0.1	20	0.02	0.067	2
1280117	Soil	0.8	39.0	26.2	115	0.3	27.7	13.4	184	3.41	14.8	2.0	3.1	22	<0.1	0.5	0.4	34	<0.01	0.065	2
1280118	Soil	0.8	29.7	21.8	106	0.2	24.4	11.9	226	2.89	15.0	1.1	1.9	16	0.2	0.5	0.3	36	0.05	0.080	2
1280119	Soil	4.6	67.0	22.8	144	0.2	44.9	11.9	357	2.67	564.3	1.6	0.6	8	0.4	3.2	0.8	30	0.03	0.070	3
1280120	Soil	3.7	62.9	28.0	54	0.6	36.2	12.3	382	3.81	76.1	2.2	0.4	10	0.1	2.7	0.5	53	<0.01	0.113	4
1280121	Soil	3.7	78.1	21.8	40	0.9	50.8	17.7	500	4.25	49.0	3.5	0.7	13	0.1	3.1	0.4	48	0.02	0.091	3
1280122	Soil	5.1	114.6	49.3	42	2.3	36.3	6.4	189	5.31	698.2	6.0	1.2	106	0.2	8.6	0.5	53	0.01	0.160	3
1280123	Soil	9.7	37.6	62.2	22	2.2	11.1	1.5	27	1.34	94.3	5.6	0.6	59	0.2	3.2	0.3	31	0.05	0.049	2
1280124	Soil	3.4	21.2	20.7	39	0.7	13.8	4.2	81	1.32	24.7	1.1	0.2	12	<0.1	1.3	0.3	24	0.01	0.059	3
1280125	Soil	4.9	17.7	28.7	17	2.0	8.8	1.7	39	0.78	30.9	2.3	0.3	16	0.1	0.9	0.2	19	0.02	0.045	2
1280126	Soil	9.7	72.4	39.2	230	0.9	42.3	9.9	237	4.50	1439	5.3	1.1	47	0.8	8.3	0.4	39	0.20	0.075	3
1280127	Soil	8.8	166.5	62.1	973	1.8	167.7	42.2	875	7.49	72.0	4.4	1.5	79	2.2	7.6	0.6	51	0.76	0.103	3
1280128	Soil	6.6	159.6	46.5	401	1.4	112.9	48.1	1486	5.81	83.3	5.3	1.3	47	1.5	5.2	0.5	46	0.29	0.119	4
1280129	Soil	7.8	76.3	53.3	283	1.6	64.1	23.9	952	4.31	43.5	3.3	0.4	21	1.1	3.4	0.4	51	0.12	0.190	3
1280130	Soil	9.8	40.0	18.2	161	0.5	41.0	8.9	413	2.76	29.9	1.6	0.2	9	0.3	2.4	0.3	58	0.03	0.110	3
1280251	Soil	32.1	21.6	12.1	603	1.2	98.9	5.6	123	2.28	66.6	55.9	0.5	30	3.1	10.8	0.2	53	0.32	0.166	7
1280252	Soil	36.4	54.6	18.8	530	0.7	101.5	10.0	243	2.89	67.2	9.3	0.9	29	1.6	8.7	0.2	144	0.09	0.145	12
1280253	Soil	61.3	130.5	16.0	443	0.9	171.3	13.3	370	2.90	40.9	3.2	1.9	21	10.0	4.6	0.1	91	0.36	0.109	20
1280254	Soil	20.8	87.3	15.7	497	1.3	69.6	8.7	186	2.90	27.4	3.2	2.4	11	3.5	8.6	0.2	62	0.16	0.049	20
1280255	Soil	5.6	113.5	21.4	565	1.7	114.8	12.7	218	3.12	18.4	1.4	8.2	24	2.4	3.9	0.4	24	0.34	0.126	28
1280256	Soil	6.2	177.9	32.0	218	2.3	156.4	39.0	380	15.86	160.6	8.1	5.8	9	0.9	3.3	0.5	10	0.02	0.091	36
1280257	Soil	5.5	145.1	30.0	331	3.6	105.7	18.1	161	4.78	26.7	4.9	4.5	77	0.9	3.5	0.5	20	0.28	0.151	24
1280258	Soil	7.4	149.8	18.0	171	0.4	690.2	113.7	1491	9.27	1382	8.6	22.6	469	1.1	12.1	<0.1	154	5.11	0.634	74
1280259	Soil	19.5	151.0	31.6	288	0.7	698.5	120.7	1268	9.36	968.2	6.7	20.2	513	1.6	12.4	0.1	159	5.95	0.547	53
1280260	Soil	2.4	141.0	14.4	112	0.2	770.2	113.3	786	7.22	2705	11.9	16.9	429	0.3	20.7	<0.1	92	4.56	0.589	71
1280261	Soil	1.3	143.6	18.6	101	0.2	677.3	119.2	1224	6.37	2120	6.0	16.7	530	0.3	17.0	0.2	116	5.93	0.671	68
1280262	Soil	1.2	129.1	11.3	123	0.2	501.3	100.1	927	5.68	121.2	2.6	29.8	471	0.3	3.9	0.1	102	5.14	0.960	79
1280263	Soil	11.5	146.3	25.1	256	0.4	696.5	100.1	1229	7.21	175.2	3.8	28.1	299	1.2	7.2	0.2	204	4.34	0.788	84
1280264	Soil	34.9	54.1	12.7	423	0.8	199.1	18.8	312	2.88	67.6	2.5	0.7	37	2.9	14.4	0.2	314	0.49	0.207	21

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1280115	Soil		30	0.14	293	0.001	<1	1.27	0.005	0.09	<0.1	0.12	4.2	0.2	0.08	4	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280116	Soil		13	0.04	120	0.002	1	0.72	0.012	0.03	<0.1	0.05	1.1	<0.1	<0.05	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280117	Soil		20	0.11	165	<0.001	<1	0.98	0.004	0.07	<0.1	0.11	3.6	<0.1	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280118	Soil		17	0.09	292	<0.001	<1	0.73	0.003	0.08	<0.1	0.09	3.1	<0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280119	Soil		10	0.03	142	0.001	1	0.43	0.002	0.05	<0.1	0.08	4.1	0.2	<0.05	1	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1280120	Soil		15	0.03	156	0.003	<1	0.53	0.002	0.06	<0.1	0.09	2.1	0.3	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280121	Soil		14	0.04	172	0.003	<1	0.49	0.002	0.06	<0.1	0.09	4.4	0.3	<0.05	2	2.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280122	Soil		26	0.02	235	0.001	8	0.67	0.003	0.09	<0.1	0.10	7.6	0.4	0.13	2	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280123	Soil		9	0.02	240	<0.001	1	0.32	0.003	0.09	<0.1	0.33	1.7	0.6	0.12	1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280124	Soil		7	0.01	101	0.002	1	0.42	0.007	0.05	<0.1	0.03	0.6	0.2	0.05	2	1.1	<0.2	N.A.	N.A.	N.A.	N.A.
1280125	Soil		5	<0.01	135	0.002	2	0.37	0.009	0.04	<0.1	0.17	0.9	0.2	0.06	1	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1280126	Soil		11	0.06	362	0.003	2	0.24	0.003	0.11	<0.1	0.10	3.3	0.4	0.20	<1	6.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280127	Soil		12	0.07	896	0.001	2	0.38	0.002	0.07	<0.1	0.17	5.6	0.2	<0.05	1	4.5	0.2	N.A.	N.A.	N.A.	N.A.
1280128	Soil		14	0.07	1178	0.002	2	0.44	0.003	0.09	<0.1	0.17	6.5	0.5	0.08	1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280129	Soil		25	0.05	582	0.005	1	0.44	0.004	0.09	<0.1	0.12	4.1	0.4	0.10	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280130	Soil		24	0.03	118	0.003	2	0.35	0.009	0.06	<0.1	0.04	1.2	0.3	0.07	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280251	Soil		11	0.06	418	0.004	2	0.55	0.009	0.05	0.5	6.02	0.9	1.7	0.12	2	3.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280252	Soil		20	0.09	245	0.004	3	0.72	0.003	0.08	0.1	0.75	1.5	1.0	0.06	2	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280253	Soil		33	0.08	468	0.003	3	0.76	0.002	0.06	0.2	1.44	7.8	2.0	<0.05	1	5.2	<0.2	N.A.	N.A.	N.A.	N.A.
1280254	Soil		6	0.03	1051	0.002	2	0.22	0.001	0.05	<0.1	1.19	3.9	0.3	<0.05	<1	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1280255	Soil		8	0.05	461	0.002	3	0.19	0.001	0.07	<0.1	1.01	4.9	0.1	<0.05	<1	8.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280256	Soil		6	0.07	1317	0.002	3	0.65	0.002	0.06	<0.1	1.03	14.4	0.3	<0.05	<1	5.5	0.2	N.A.	N.A.	N.A.	N.A.
1280257	Soil		9	0.06	3684	0.002	2	0.61	0.003	0.14	<0.1	2.44	5.4	0.2	<0.05	<1	5.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280258	Soil		187	1.78	2722	0.010	16	0.84	0.006	0.19	0.1	0.48	31.1	0.4	0.05	2	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280259	Soil		145	2.08	1363	0.008	13	0.77	0.009	0.16	0.2	1.46	23.5	0.9	0.10	2	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1280260	Soil		167	1.36	2519	0.007	17	0.88	0.006	0.20	0.2	0.38	23.1	0.3	<0.05	2	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280261	Soil		196	1.68	2008	0.002	20	0.83	0.006	0.19	0.5	0.15	22.5	0.3	0.22	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280262	Soil		211	1.37	1616	0.003	19	1.04	0.006	0.24	<0.1	0.32	26.5	0.2	0.18	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280263	Soil		178	1.19	1284	0.004	21	0.90	0.006	0.23	0.2	0.76	23.7	0.5	0.18	3	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280264	Soil		41	0.06	652	0.003	4	0.59	0.013	0.06	0.2	0.25	1.8	0.8	0.15	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1280115	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280116	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280117	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280118	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280119	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280120	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280121	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280122	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280123	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280124	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280125	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280126	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280127	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280128	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280129	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280130	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280251	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280252	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280253	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280254	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280255	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280256	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280257	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280258	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280259	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280260	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280261	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280262	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280263	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280264	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280115	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280116	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280117	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280118	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280119	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280120	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280121	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280122	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280123	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280124	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280125	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280126	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280127	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280128	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280129	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280130	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280251	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280252	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280253	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280254	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280255	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280256	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280257	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280258	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280259	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280260	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280261	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280262	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280263	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280264	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280265	Soil		34.9	62.5	12.1	543	0.8	133.2	9.4	406	2.33	66.6	2.3	0.9	181	6.4	18.1	0.1	276	6.53	0.134	14
1280266	Soil		135.8	202.8	19.3	2460	2.8	433.1	7.0	143	1.71	108.8	4.6	0.5	208	21.8	43.1	0.2	789	6.30	0.133	19
1280267	Soil		110.5	153.8	17.6	1548	1.6	296.6	8.7	174	2.02	93.5	3.5	2.1	305	12.4	40.6	0.2	469	9.97	0.124	15
1280268	Soil		98.7	132.1	17.0	1709	1.7	288.5	9.1	214	2.26	92.2	3.8	1.4	142	10.7	32.7	0.2	470	4.73	0.130	18
1280269	Soil		99.0	107.1	9.4	546	0.7	263.4	8.9	166	1.84	39.7	3.4	2.6	118	6.1	10.0	0.2	168	4.11	0.112	19
1280270	Soil		61.3	38.9	8.0	419	<0.1	139.9	6.0	137	1.48	28.1	1.9	1.0	15	2.9	7.5	0.1	243	0.24	0.077	12
1280301	Soil		3.1	32.7	23.7	119	0.1	37.4	18.5	3134	3.39	18.2	1.9	0.4	15	0.4	1.6	0.3	27	0.15	0.096	10
1280302	Soil		5.5	46.4	28.1	105	0.2	56.8	23.4	1643	4.54	801.9	3.3	1.1	6	0.2	3.3	0.4	28	0.02	0.077	12
1280303	Soil		5.4	46.2	11.3	127	<0.1	49.4	14.8	692	4.37	121.2	2.0	0.5	5	0.1	2.7	0.3	34	0.03	0.070	12
1280304	Soil		6.0	81.7	33.3	140	0.7	105.6	34.6	978	7.20	132.4	4.7	1.5	24	0.5	4.6	0.4	33	0.09	0.118	12
1280305	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280306	Soil		9.3	89.0	32.9	222	1.6	96.2	21.5	550	5.08	83.6	7.7	2.1	50	0.8	4.5	0.4	40	0.30	0.163	16
1280307	Soil		20.9	143.7	52.6	115	5.4	75.8	2.8	31	3.63	33.5	1.1	1.5	227	0.8	8.9	0.5	128	0.56	0.396	43
1280308	Soil		21.1	168.6	32.4	882	6.4	340.3	13.6	401	3.96	42.9	6.5	1.0	254	7.9	12.5	0.4	243	1.25	0.613	21
1280309	Soil		26.7	81.4	58.6	120	4.3	32.5	1.8	43	2.27	26.9	3.5	0.1	309	1.7	12.8	0.6	165	0.14	0.380	29
1280310	Soil		17.1	68.8	14.5	314	0.9	125.9	11.8	189	2.79	18.4	3.1	3.2	49	1.3	4.8	0.3	87	0.92	0.407	19
1280311	Soil		26.8	33.2	22.4	146	0.5	49.9	8.0	125	2.53	19.8	1.0	0.1	28	0.3	3.7	0.3	115	0.04	0.108	12
1280312	Soil		5.9	40.3	10.1	123	0.3	49.7	13.2	461	3.51	11.2	1.3	0.7	11	0.4	1.7	0.3	39	0.17	0.126	5
1280313	Soil		35.4	35.6	13.7	337	0.3	72.4	6.5	102	1.98	26.0	1.2	0.4	25	2.4	8.4	0.2	97	0.30	0.116	7
1280314	Soil		96.7	116.3	14.7	883	1.2	208.0	13.8	305	3.02	70.2	6.2	1.2	58	9.0	25.4	0.2	328	0.70	0.153	21
1280315	Soil		2.2	13.0	5.8	26	0.1	6.8	1.7	29	0.86	10.2	1.1	0.2	5	<0.1	0.8	0.2	17	0.03	0.088	3
1280316	Soil		2.4	6.8	5.0	16	0.1	3.6	0.7	12	0.40	3.3	<0.5	0.1	6	<0.1	0.4	0.1	20	0.01	0.089	3
1280317	Soil		2.3	24.3	39.4	77	0.1	40.2	12.5	218	3.07	19.8	1.4	0.9	14	<0.1	1.3	0.3	20	0.02	0.063	4
1280318	Soil		1.5	18.2	21.4	61	<0.1	18.7	8.9	182	1.50	17.2	0.6	0.6	26	<0.1	0.8	0.3	13	0.04	0.051	3
1280319	Soil		1.7	19.9	12.3	71	<0.1	15.7	7.2	321	2.65	10.2	1.2	0.3	10	0.1	1.0	0.2	28	0.05	0.101	4
1280320	Soil		2.5	19.8	17.1	75	0.1	16.4	7.1	572	4.18	13.4	0.6	0.7	7	0.1	1.0	0.3	40	0.03	0.103	3
1280321	Soil		6.3	28.8	38.1	14	5.1	12.7	1.5	23	1.78	28.8	7.0	0.3	27	<0.1	3.5	0.2	28	0.02	0.096	2
1280322	Soil		7.4	38.9	33.5	39	0.9	20.0	3.7	116	2.56	66.5	4.1	0.3	36	0.1	3.9	0.3	61	0.02	0.108	6
1280323	Soil		4.2	14.0	15.1	33	0.2	10.2	2.8	60	1.12	24.2	1.2	0.3	8	<0.1	1.4	0.3	23	0.01	0.064	3
1280324	Soil		1.3	14.2	12.5	55	<0.1	14.8	6.4	90	1.26	10.5	0.7	0.4	11	0.2	0.6	0.2	13	0.05	0.080	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1280265	Soil	22	3.65	575	0.003	7	0.32	0.009	0.07	0.2	0.18	2.2	1.8	0.18	<1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280266	Soil	44	0.95	501	0.004	8	0.46	0.005	0.14	0.5	1.27	1.9	4.4	0.24	2	9.6	0.2	N.A.	N.A.	N.A.	N.A.
1280267	Soil	25	1.68	375	0.004	7	0.32	0.005	0.10	0.4	0.59	2.9	3.9	0.23	<1	6.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280268	Soil	28	1.67	398	0.003	5	0.42	0.005	0.09	0.4	0.35	3.2	3.0	0.20	1	5.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280269	Soil	18	1.63	340	0.003	5	0.33	0.004	0.08	0.4	0.47	5.2	2.5	0.19	<1	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280270	Soil	18	0.12	456	0.003	3	0.71	0.005	0.05	0.3	0.04	1.1	1.4	0.15	2	2.1	<0.2	N.A.	N.A.	N.A.	N.A.
1280301	Soil	10	0.06	392	0.003	4	0.57	0.006	0.10	0.1	0.04	0.8	0.2	0.15	2	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280302	Soil	9	0.05	178	0.004	3	0.60	0.004	0.09	<0.1	0.05	2.8	0.3	0.08	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280303	Soil	8	0.03	194	0.004	2	0.55	0.005	0.07	0.1	0.04	1.1	0.1	0.09	3	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280304	Soil	12	0.06	896	0.003	3	0.57	0.005	0.10	<0.1	0.13	4.6	0.3	0.13	2	2.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280305	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	2.7	105.6	34.1	237
1280306	Soil	15	0.08	1593	0.003	3	0.46	0.004	0.11	<0.1	0.37	4.7	0.3	0.25	1	2.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280307	Soil	24	0.04	124	0.001	2	0.40	0.007	0.33	0.4	2.82	2.9	1.4	1.07	1	11.6	0.4	N.A.	N.A.	N.A.	N.A.
1280308	Soil	27	0.23	1479	0.004	4	0.93	0.010	0.16	0.3	1.72	2.7	0.8	0.35	2	5.6	0.3	N.A.	N.A.	N.A.	N.A.
1280309	Soil	28	0.02	682	<0.001	2	0.51	0.008	0.14	0.3	0.41	<0.1	0.8	0.44	2	5.5	0.4	N.A.	N.A.	N.A.	N.A.
1280310	Soil	11	0.04	588	0.002	8	0.43	0.002	0.17	<0.1	0.63	3.6	0.2	0.11	1	3.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280311	Soil	8	0.02	224	0.002	2	0.27	0.003	0.07	0.2	0.05	0.2	0.3	0.13	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1280312	Soil	9	0.05	329	0.004	4	0.31	0.006	0.09	<0.1	0.08	4.0	0.1	0.14	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280313	Soil	10	0.06	370	0.001	2	0.27	0.006	0.05	0.1	0.19	1.0	0.4	0.12	1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1280314	Soil	22	0.13	516	0.002	3	0.51	0.004	0.07	0.3	1.33	3.8	1.5	0.09	2	5.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280315	Soil	9	0.04	56	0.003	1	0.63	0.011	0.03	<0.1	0.03	0.2	0.1	<0.05	2	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280316	Soil	5	0.01	170	0.002	1	0.51	0.010	0.03	<0.1	0.02	0.1	0.4	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280317	Soil	12	0.06	113	0.001	<1	0.51	0.003	0.06	<0.1	0.04	2.0	0.3	<0.05	1	0.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280318	Soil	7	0.06	303	<0.001	<1	0.44	0.004	0.06	<0.1	0.02	1.1	0.2	0.07	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280319	Soil	20	0.14	88	0.004	<1	1.02	0.009	0.04	<0.1	0.02	0.5	0.1	0.06	4	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280320	Soil	27	0.13	80	0.003	<1	0.87	0.004	0.05	<0.1	0.03	1.0	0.1	<0.05	5	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280321	Soil	15	<0.01	148	<0.001	1	0.30	0.005	0.05	<0.1	0.17	1.0	0.2	0.12	1	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280322	Soil	15	0.05	140	0.005	<1	0.47	0.005	0.05	0.2	0.03	1.1	0.2	0.08	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280323	Soil	7	0.03	79	0.002	1	0.46	0.006	0.04	<0.1	0.02	0.4	0.2	<0.05	2	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280324	Soil	6	0.04	134	<0.001	<1	0.46	0.005	0.05	<0.1	<0.01	0.9	0.1	<0.05	1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1280265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280301	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280302	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280303	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280304	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280305	Soil	1.5	125.2	44.3	1542	7.90	206.4	6.7	4.4	45	0.5	2.0	0.5	37	0.21	0.156	18	20	0.12	2014	0.003
1280306	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280307	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280308	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280309	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280310	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280311	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280320	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280323	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280265	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280266	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280267	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280268	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280269	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280270	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280301	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280302	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280303	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280304	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280305	Soil	<20	0.81	0.004	0.13	<0.1	0.12	8.0	0.3	0.12	2	2.3	<0.2
1280306	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280307	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280308	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280309	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280310	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280311	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280312	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280313	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280314	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280315	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280316	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280317	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280318	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280319	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280320	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280321	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280322	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280323	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280324	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280325	Soil		1.2	25.9	21.3	92	<0.1	29.8	15.2	389	2.37	15.0	0.9	1.1	10	0.1	0.8	0.3	20	0.02	0.074	3
1280326	Soil		1.9	29.0	59.9	150	0.1	31.5	27.4	947	3.74	14.7	0.9	0.9	8	0.3	1.1	0.3	35	0.05	0.082	6
1280327	Soil		2.4	28.5	35.6	110	0.1	20.0	12.5	668	3.77	18.3	0.8	1.1	9	0.2	1.1	0.4	38	0.02	0.132	3
1280328	Soil		0.9	10.4	5.7	30	0.1	4.3	3.9	420	1.61	3.1	<0.5	0.2	6	0.2	0.3	<0.1	16	0.03	0.136	3
1280329	Soil		0.8	7.7	4.6	19	<0.1	3.6	1.9	185	1.22	3.0	<0.5	0.1	5	0.1	0.3	<0.1	14	0.02	0.085	2
1280330	Soil		0.8	14.1	8.0	30	<0.1	7.5	4.6	310	1.38	6.8	0.6	0.2	5	<0.1	0.4	0.1	14	0.03	0.077	2
1280331	Soil		2.2	24.2	22.6	75	0.2	16.6	8.9	440	3.30	18.3	<0.5	0.6	7	0.2	1.1	0.3	38	0.03	0.119	3
1280332	Soil		1.8	16.6	14.3	61	0.1	13.3	5.8	328	3.06	11.0	<0.5	0.3	8	0.2	0.8	0.2	30	0.03	0.111	3
1280333	Soil		1.7	16.2	12.8	79	<0.1	14.6	11.5	682	2.76	14.4	<0.5	0.4	10	0.2	0.9	0.2	28	0.05	0.129	3
1280334	Soil		0.6	6.2	5.1	25	<0.1	4.8	2.5	90	0.99	3.7	<0.5	0.2	6	0.1	0.3	<0.1	9	0.02	0.059	1
1280335	Soil		2.7	33.3	25.0	104	0.3	21.9	13.4	430	3.87	24.9	0.5	0.9	19	0.1	1.3	0.4	53	0.03	0.128	6
1280336	Soil		2.0	24.7	17.9	57	0.3	10.2	3.6	81	2.75	17.5	1.2	0.3	14	<0.1	0.9	0.3	57	0.03	0.149	4
1280337	Soil		1.6	18.6	11.7	45	0.1	7.8	2.9	64	1.76	12.8	<0.5	0.5	10	<0.1	0.6	0.2	50	0.02	0.091	4
1280338	Soil		1.9	19.5	15.7	59	0.1	9.8	3.9	126	2.63	14.5	<0.5	0.4	14	0.1	0.8	0.3	55	0.02	0.132	4
1280339	Soil		0.6	6.4	5.9	19	<0.1	3.5	1.0	36	0.77	3.7	<0.5	<0.1	6	<0.1	0.3	0.1	18	0.01	0.081	2
1280340	Soil		1.8	28.7	25.7	85	0.2	20.8	8.5	351	3.67	17.0	1.0	1.5	15	0.2	0.7	0.3	47	0.03	0.115	3
1280341	Soil		1.8	34.0	25.0	105	0.3	25.1	11.1	279	4.03	21.2	<0.5	2.0	15	0.1	0.8	0.4	48	0.02	0.126	4
1280342	Soil		1.6	20.2	15.1	52	0.2	11.8	3.9	103	2.68	12.9	<0.5	0.6	10	<0.1	0.8	0.2	35	0.03	0.066	4
1280343	Soil		1.0	42.0	29.3	97	0.7	26.9	9.7	476	4.24	20.5	<0.5	1.6	14	0.3	0.5	0.3	49	0.03	0.113	4
1280344	Soil		0.5	24.2	10.1	42	0.1	7.3	4.2	250	1.53	6.2	<0.5	0.5	7	0.2	0.3	0.2	23	0.03	0.119	3
1280345	Soil		0.9	20.5	12.3	59	0.4	11.4	4.5	61	1.98	9.2	<0.5	0.3	10	<0.1	0.4	0.2	32	0.02	0.084	2
1280346	Soil		3.5	74.4	26.3	44	2.1	60.4	29.8	1223	5.46	25.7	4.3	1.0	18	0.3	3.3	0.4	72	0.32	0.104	5
1280347	Soil		4.0	82.0	19.9	28	0.9	51.8	20.6	650	3.71	53.7	1.8	0.9	16	<0.1	3.1	0.4	50	0.16	0.079	4
1280348	Soil		2.3	27.8	18.6	15	2.1	12.7	3.6	80	1.71	30.3	<0.5	0.2	10	<0.1	1.8	0.2	27	0.01	0.045	2
1280349	Soil		2.9	52.5	51.3	37	4.0	20.9	3.8	73	2.34	98.5	<0.5	0.4	33	0.1	2.7	1.2	33	0.04	0.124	2
1280350	Soil		15.7	59.9	58.5	15	1.4	24.2	3.1	57	1.85	44.8	1.3	0.6	109	0.1	3.2	0.4	46	0.04	0.076	3
1280401	Soil		4.9	54.4	25.2	107	1.2	31.9	7.5	308	2.82	147.8	2.4	0.4	19	0.2	2.3	0.4	43	0.14	0.121	5
1280402	Soil		6.2	121.5	32.7	418	0.6	74.3	23.9	503	4.25	48.7	2.0	1.0	43	0.8	4.3	0.5	40	0.28	0.101	4
1280403	Soil		7.8	35.9	14.2	123	0.6	30.9	10.6	388	1.03	10.9	<0.5	0.5	97	2.1	1.8	0.2	16	1.96	0.112	2
1280404	Soil		8.6	54.3	18.0	220	0.2	39.8	8.7	140	2.54	30.4	<0.5	0.7	10	0.4	3.4	0.3	57	0.03	0.066	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1280325	Soil	16	0.24	97	<0.001	<1	0.94	0.005	0.07	<0.1	0.01	1.6	0.2	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280326	Soil	28	0.35	81	0.005	1	1.28	0.003	0.05	0.1	0.05	1.6	0.2	0.07	4	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280327	Soil	28	0.21	107	0.003	2	1.38	0.003	0.07	<0.1	0.04	1.9	0.3	0.09	5	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280328	Soil	12	0.03	46	0.004	<1	0.91	0.013	0.03	<0.1	0.05	0.3	<0.1	0.11	3	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280329	Soil	10	0.03	31	0.005	<1	0.68	0.014	0.03	<0.1	0.02	0.3	<0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1280330	Soil	11	0.08	36	0.005	<1	0.74	0.015	0.04	<0.1	0.03	0.3	<0.1	<0.05	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280331	Soil	25	0.13	100	0.005	<1	1.08	0.003	0.07	<0.1	0.06	1.2	0.2	<0.05	5	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1280332	Soil	23	0.10	82	0.005	1	0.88	0.007	0.05	<0.1	0.06	0.7	0.1	0.10	4	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280333	Soil	18	0.09	79	0.005	<1	0.88	0.008	0.06	<0.1	0.03	0.5	<0.1	0.09	3	1.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280334	Soil	7	0.03	48	0.004	<1	0.48	0.017	0.03	<0.1	0.03	0.3	<0.1	0.07	1	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280335	Soil	26	0.20	157	0.005	<1	1.18	0.006	0.07	<0.1	0.04	1.7	0.1	0.09	5	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1280336	Soil	18	0.03	114	0.004	<1	0.81	0.005	0.05	<0.1	0.05	0.5	0.1	0.10	5	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1280337	Soil	12	0.03	117	0.002	<1	0.76	0.004	0.05	<0.1	0.02	0.8	<0.1	<0.05	4	1.0	<0.2	N.A.	N.A.	N.A.	N.A.
1280338	Soil	16	0.05	112	0.004	<1	0.84	0.005	0.05	0.1	0.04	0.6	0.1	0.07	5	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280339	Soil	6	0.02	45	0.003	<1	0.38	0.012	0.03	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280340	Soil	31	0.16	143	0.003	1	1.29	0.006	0.05	<0.1	0.06	2.3	0.1	<0.05	5	1.4	<0.2	N.A.	N.A.	N.A.	N.A.
1280341	Soil	29	0.21	159	0.003	<1	1.44	0.004	0.07	<0.1	0.10	3.2	0.1	0.07	5	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
1280342	Soil	17	0.13	83	0.005	<1	0.96	0.011	0.05	<0.1	0.04	1.1	<0.1	<0.05	4	0.6	<0.2	N.A.	N.A.	N.A.	N.A.
1280343	Soil	26	0.13	328	0.002	1	1.50	0.007	0.08	<0.1	0.06	3.8	<0.1	<0.05	6	1.3	0.2	N.A.	N.A.	N.A.	N.A.
1280344	Soil	11	0.04	135	0.004	<1	0.87	0.013	0.03	<0.1	0.04	1.0	<0.1	<0.05	3	1.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280345	Soil	13	0.05	99	0.002	<1	0.71	0.009	0.05	<0.1	0.07	1.0	<0.1	<0.05	3	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280346	Soil	20	0.09	431	0.004	<1	0.71	0.003	0.08	<0.1	0.16	7.8	0.5	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1280347	Soil	19	0.04	1047	0.001	2	0.54	0.002	0.08	<0.1	0.11	6.0	0.2	<0.05	2	2.3	<0.2	N.A.	N.A.	N.A.	N.A.
1280348	Soil	7	0.01	81	0.002	<1	0.36	0.007	0.06	<0.1	0.06	1.2	0.2	<0.05	2	1.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280349	Soil	8	0.01	166	0.001	5	0.45	0.003	0.06	<0.1	0.09	1.0	0.2	0.10	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280350	Soil	12	<0.01	398	<0.001	2	0.35	0.003	0.10	<0.1	0.28	3.6	1.0	0.15	1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280401	Soil	15	0.07	236	0.003	2	0.85	0.011	0.06	<0.1	0.11	2.0	0.3	0.06	3	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1280402	Soil	15	0.06	657	0.002	2	0.44	0.004	0.09	<0.1	0.11	4.1	0.3	0.07	1	3.1	<0.2	N.A.	N.A.	N.A.	N.A.
1280403	Soil	9	0.18	947	0.004	6	0.20	0.010	0.05	<0.1	0.12	1.9	0.3	0.17	<1	4.1	<0.2	N.A.	N.A.	N.A.	N.A.
1280404	Soil	12	0.03	74	0.001	3	0.52	0.004	0.05	<0.1	0.03	1.5	0.2	<0.05	2	1.8	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1280325	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280326	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280327	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280328	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280329	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280330	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280331	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280332	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280333	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280334	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280335	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280336	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280337	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280338	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280339	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280340	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280341	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280342	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280343	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280344	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280345	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280346	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280347	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280348	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280349	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280350	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280401	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280402	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280403	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280404	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280325	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280326	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280327	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280328	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280329	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280330	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280331	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280332	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280333	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280334	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280335	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280336	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280337	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280338	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280339	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280340	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280341	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280342	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280343	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280344	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280345	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280346	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280347	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280348	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280349	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280350	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280401	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280402	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280403	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280404	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280405	Soil	15.8	40.4	16.6	195	0.1	41.1	7.4	125	2.40	34.0	1.4	0.7	10	0.2	3.9	0.3	84	0.02	0.050	7
1280406	Soil	63.3	40.5	16.0	252	<0.1	80.7	6.2	76	2.53	34.7	<0.5	1.1	9	0.5	5.8	0.2	111	0.02	0.065	8
1280407	Soil	2.3	4.0	1.8	11	0.9	3.9	0.5	9	0.21	0.9	<0.5	<0.1	5	0.2	0.2	<0.1	12	0.04	0.039	2
1280408	Soil	5.2	9.2	3.7	43	0.5	8.7	1.6	33	0.57	6.6	<0.5	<0.1	4	<0.1	0.8	<0.1	21	0.02	0.031	2
1280409	Soil	19.0	30.2	10.8	125	0.8	34.9	6.0	209	1.58	16.2	3.0	0.7	21	0.5	2.4	0.3	55	0.24	0.075	5
1280410	Soil	9.0	27.3	5.3	113	0.8	29.5	3.1	58	0.86	6.7	2.5	0.4	19	0.7	1.8	<0.1	38	0.20	0.054	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1280405	Soil	11	0.03	132	0.002	3	0.43	0.003	0.06	0.1	0.03	1.5	0.3	<0.05	3	1.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280406	Soil	14	0.05	317	0.004	5	0.71	0.003	0.06	0.2	0.04	1.8	0.6	<0.05	3	2.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280407	Soil	4	0.01	95	0.003	<1	0.16	0.015	0.03	<0.1	0.04	0.4	<0.1	<0.05	<1	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
1280408	Soil	4	0.01	60	0.003	<1	0.17	0.013	0.03	<0.1	0.02	0.4	<0.1	<0.05	1	0.8	<0.2	N.A.	N.A.	N.A.	N.A.
1280409	Soil	13	0.06	596	0.003	3	0.57	0.008	0.08	0.1	0.15	1.9	0.3	<0.05	2	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
1280410	Soil	8	0.06	592	0.005	4	0.47	0.021	0.05	<0.1	0.20	1.2	0.3	<0.05	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
	Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
	MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1280405	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280406	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280407	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280408	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280409	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280410	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001182.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280405	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280406	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280407	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280408	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280409	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1280410	Soil	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001182.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1280012	Soil	4.3	19.6	14.1	150	0.2	24.0	6.8	193	2.56	9.1	0.8	0.3	8	1.1	1.7	0.2	64	0.02	0.075	10
REP 1280012	QC	4.4	19.0	14.4	148	0.2	24.7	7.0	189	2.56	9.0	<0.5	0.4	9	1.0	1.6	0.3	64	0.02	0.074	10
1280024	Soil	3.2	47.9	15.7	201	0.9	60.4	10.7	164	3.17	25.3	3.4	2.5	40	0.7	1.7	0.2	31	0.17	0.087	7
REP 1280024	QC	2.9	47.5	15.4	203	0.9	58.1	10.5	158	3.04	24.9	4.5	2.5	39	0.6	1.8	0.2	32	0.17	0.083	7
1280039	Soil	7.8	54.9	45.6	37	2.4	16.9	3.7	127	2.84	174.5	2.0	0.3	66	0.1	4.3	0.4	64	0.03	0.158	4
REP 1280039	QC	7.9	56.6	47.1	40	2.4	16.6	3.7	130	2.92	184.5	2.1	0.4	70	0.1	4.3	0.4	67	0.03	0.167	4
1280049	Soil	3.1	78.2	39.8	308	0.3	65.2	36.8	490	7.40	36.4	<0.5	4.4	97	0.4	1.4	0.4	38	0.02	0.139	4
REP 1280049	QC	2.7	76.8	37.6	316	0.3	62.2	35.2	476	6.96	36.6	<0.5	4.4	102	0.4	1.5	0.4	39	0.02	0.143	4
1280071	Soil	5.5	54.7	20.6	197	1.3	54.9	11.9	213	3.47	57.2	6.8	1.4	66	0.9	3.5	0.3	43	0.09	0.106	5
REP 1280071	QC	5.4	53.2	21.7	198	1.2	53.6	11.8	208	3.33	55.3	5.9	1.4	64	0.8	3.6	0.3	42	0.08	0.104	5
1280095	Soil	12.0	21.0	38.7	27	1.4	11.0	1.9	39	1.64	37.3	1.3	0.5	29	<0.1	2.7	0.6	49	0.03	0.078	2
REP 1280095	QC	12.4	22.4	39.2	29	1.5	11.2	2.0	41	1.70	37.3	<0.5	0.5	30	0.1	2.6	0.6	51	0.03	0.076	2
1280118	Soil	0.8	29.7	21.8	106	0.2	24.4	11.9	226	2.89	15.0	1.1	1.9	16	0.2	0.5	0.3	36	0.05	0.080	2
REP 1280118	QC	1.1	31.0	23.6	110	0.3	24.7	12.0	239	2.97	15.8	0.9	1.9	18	0.2	0.5	0.3	38	0.05	0.081	3
1280128	Soil	6.6	159.6	46.5	401	1.4	112.9	48.1	1486	5.81	83.3	5.3	1.3	47	1.5	5.2	0.5	46	0.29	0.119	4
REP 1280128	QC	6.5	156.0	45.0	403	1.4	110.6	47.7	1466	5.75	82.2	6.4	0.9	47	1.7	5.0	0.5	46	0.28	0.117	4
1280262	Soil	1.2	129.1	11.3	123	0.2	501.3	100.1	927	5.68	121.2	2.6	29.8	471	0.3	3.9	0.1	102	5.14	0.960	79
REP 1280262	QC	1.1	127.8	11.1	122	0.2	493.7	95.4	923	5.53	117.4	2.4	29.7	463	0.3	3.8	0.1	101	5.29	0.966	78
1280311	Soil	26.8	33.2	22.4	146	0.5	49.9	8.0	125	2.53	19.8	1.0	0.1	28	0.3	3.7	0.3	115	0.04	0.108	12
REP 1280311	QC	26.9	33.0	22.7	148	0.5	49.7	7.7	127	2.48	19.8	0.9	0.2	28	0.3	3.8	0.3	111	0.04	0.111	12
1280329	Soil	0.8	7.7	4.6	19	<0.1	3.6	1.9	185	1.22	3.0	<0.5	0.1	5	0.1	0.3	<0.1	14	0.02	0.085	2
REP 1280329	QC	0.7	7.8	4.4	20	<0.1	3.8	1.9	182	1.21	3.0	<0.5	0.2	5	<0.1	0.4	<0.1	14	0.02	0.088	2
1280350	Soil	15.7	59.9	58.5	15	1.4	24.2	3.1	57	1.85	44.8	1.3	0.6	109	0.1	3.2	0.4	46	0.04	0.076	3
REP 1280350	QC	16.0	61.9	57.0	15	1.3	23.7	3.1	59	1.91	45.6	2.0	0.7	108	<0.1	3.6	0.4	47	0.04	0.077	3
Reference Materials																					
STD DS8	Standard	13.7	107.3	121.1	308	1.7	37.7	7.2	609	2.45	21.5	114.2	7.2	73	2.3	5.8	6.5	42	0.71	0.074	17
STD DS8	Standard	13.2	111.7	129.7	335	1.9	37.7	7.9	637	2.57	25.9	127.2	6.8	68	2.4	5.7	7.2	43	0.68	0.087	15
STD DS8	Standard	13.7	113.7	125.9	311	1.8	39.5	8.1	628	2.54	24.6	111.1	6.9	69	2.5	6.0	7.2	44	0.71	0.076	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001182.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1280012	Soil	22	0.10	385	0.005	2	0.93	0.005	0.05	0.1	0.03	0.7	0.1	<0.05	4	0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1280012	QC	23	0.10	399	0.005	2	0.92	0.005	0.05	0.1	0.02	0.8	0.2	<0.05	4	0.9	<0.2				
1280024	Soil	22	0.13	523	0.004	2	0.80	0.006	0.08	<0.1	0.13	3.0	0.1	0.12	2	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1280024	QC	22	0.12	534	0.004	2	0.77	0.006	0.07	<0.1	0.12	3.1	0.1	0.11	2	1.7	<0.2				
1280039	Soil	24	0.02	232	0.006	2	0.59	0.008	0.11	<0.1	0.09	1.9	0.5	0.18	2	2.9	0.2	N.A.	N.A.	N.A.	N.A.
REP 1280039	QC	25	0.02	246	0.003	2	0.63	0.008	0.11	<0.1	0.08	1.9	0.5	0.17	2	3.8	<0.2				
1280049	Soil	35	0.34	619	0.008	2	1.52	0.014	0.09	<0.1	0.07	9.9	0.7	0.10	5	1.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1280049	QC	35	0.35	628	0.002	2	1.56	0.014	0.10	<0.1	0.08	9.9	0.7	0.15	4	1.3	<0.2				
1280071	Soil	22	0.09	1607	0.001	4	0.87	0.006	0.09	<0.1	0.51	3.8	0.3	<0.05	2	5.6	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1280071	QC	21	0.09	1572	0.002	4	0.90	0.006	0.10	<0.1	0.54	3.8	0.3	0.07	3	5.2	<0.2				
1280095	Soil	9	0.04	326	<0.001	4	0.55	0.006	0.09	<0.1	0.20	1.1	0.7	<0.05	2	3.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1280095	QC	9	0.04	334	0.002	2	0.57	0.006	0.10	<0.1	0.22	1.2	0.7	0.05	2	3.4	<0.2				
1280118	Soil	17	0.09	292	<0.001	<1	0.73	0.003	0.08	<0.1	0.09	3.1	<0.1	<0.05	2	0.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1280118	QC	19	0.09	310	0.002	<1	0.78	0.003	0.08	<0.1	0.09	3.3	<0.1	<0.05	3	1.2	<0.2				
1280128	Soil	14	0.07	1178	0.002	2	0.44	0.003	0.09	<0.1	0.17	6.5	0.5	0.08	1	3.9	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1280128	QC	14	0.07	1206	0.001	2	0.46	0.005	0.09	<0.1	0.17	6.5	0.5	0.07	1	2.9	<0.2				
1280262	Soil	211	1.37	1616	0.003	19	1.04	0.006	0.24	<0.1	0.32	26.5	0.2	0.18	3	<0.5	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1280262	QC	206	1.32	1561	0.003	22	1.02	0.006	0.25	<0.1	0.31	26.7	0.2	0.16	3	<0.5	<0.2				
1280311	Soil	8	0.02	224	0.002	2	0.27	0.003	0.07	0.2	0.05	0.2	0.3	0.13	2	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1280311	QC	8	0.02	218	0.002	2	0.28	0.003	0.08	0.2	0.04	0.3	0.3	0.09	2	1.9	<0.2				
1280329	Soil	10	0.03	31	0.005	<1	0.68	0.014	0.03	<0.1	0.02	0.3	<0.1	<0.05	3	1.2	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1280329	QC	9	0.03	31	0.005	<1	0.70	0.012	0.03	<0.1	0.03	0.3	<0.1	0.07	3	0.7	<0.2				
1280350	Soil	12	<0.01	398	<0.001	2	0.35	0.003	0.10	<0.1	0.28	3.6	1.0	0.15	1	3.7	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1280350	QC	13	<0.01	399	<0.001	4	0.37	0.003	0.10	<0.1	0.28	3.9	0.9	0.15	1	5.2	<0.2				
Reference Materials																					
STD DS8	Standard	121	0.60	281	0.127	2	0.93	0.104	0.41	3.0	0.20	2.8	5.5	0.14	5	4.0	4.8				
STD DS8	Standard	120	0.61	283	0.115	3	0.93	0.096	0.42	3.3	0.22	2.4	5.6	0.15	5	5.9	5.1				
STD DS8	Standard	123	0.59	291	0.133	3	0.92	0.088	0.42	2.9	0.21	2.3	5.3	0.17	5	5.1	4.9				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001182.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1280012	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280012	QC																					
1280024	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280024	QC																					
1280039	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280039	QC																					
1280049	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280049	QC																					
1280071	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280071	QC																					
1280095	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280095	QC																					
1280118	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280118	QC																					
1280128	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280128	QC																					
1280262	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280262	QC																					
1280311	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280311	QC																					
1280329	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280329	QC																					
1280350	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280350	QC																					
Reference Materials																						
STD DS8	Standard																					
STD DS8	Standard																					
STD DS8	Standard																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001182.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1280012	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280012	QC													
1280024	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280024	QC													
1280039	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280039	QC													
1280049	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280049	QC													
1280071	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280071	QC													
1280095	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280095	QC													
1280118	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280118	QC													
1280128	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280128	QC													
1280262	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280262	QC													
1280311	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280311	QC													
1280329	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280329	QC													
1280350	Soil		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1280350	QC													
Reference Materials														
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard													

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001182.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	12.1	102.2	124.9	293	1.7	38.3	7.5	579	2.44	23.8	112.6	5.8	55	2.2	5.5	6.4	40	0.62	0.077	12
STD DS8	Standard	12.6	110.2	127.3	308	1.8	38.4	7.5	619	2.46	24.7	112.9	6.3	71	2.4	5.9	6.5	42	0.68	0.081	14
STD DS8	Standard	13.4	113.3	129.0	316	1.9	38.5	7.5	630	2.49	24.6	115.7	7.7	77	2.4	5.9	6.7	44	0.76	0.078	19
STD DS8	Standard	12.3	99.9	113.4	283	1.6	34.1	6.8	567	2.27	23.4	100.3	6.2	64	2.3	5.0	6.0	37	0.64	0.071	14
STD DS8	Standard																				
STD OREAS45CA	Standard																				
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																					
BLK	Blank	<0.1	<0.1	<0.1	4	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001182.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1
STD DS8	Standard	114	0.58	241	0.102	3	0.84	0.089	0.40	3.1	0.18	1.8	5.2	0.27	4	4.9	4.8				
STD DS8	Standard	117	0.64	278	0.111	2	0.95	0.107	0.43	3.2	0.18	3.4	5.5	0.15	5	7.0	5.2				
STD DS8	Standard	116	0.62	301	0.128	2	1.05	0.115	0.45	3.0	0.20	3.5	5.5	0.06	5	4.7	5.1				
STD DS8	Standard	106	0.56	269	0.101	3	0.87	0.092	0.41	2.7	0.18	2.4	4.9	0.15	4	5.2	4.6				
STD DS8	Standard																	14.2	119.9	125.1	325
STD OREAS45CA	Standard																	0.9	570.7	22.2	69
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001182.2

		1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01	1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard																				
STD DS8	Standard	1.7	41.1	8.3	652	2.53	27.0	136.8	7.2	76	2.4	5.4	7.4	47	0.73	0.081	17	128	0.61	304	0.123
STD OREAS45CA	Standard	0.3	271.0	97.9	970	17.25	3.5	43.2	7.3	16	<0.1	<0.1	0.2	218	0.43	0.039	17	793	0.16	172	0.144
STD DS8 Expected		1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected		0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank																				
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001182.2

		1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Sc ppm 0.1	1DX Tl ppm 0.1	1DX S % 0.05	1DX Ga ppm 1	1DX Se ppm 0.5	1DX Te ppm 0.2
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard												
STD DS8	Standard	<20	0.94	0.096	0.43	2.3	0.19	2.4	5.5	0.17	5	4.4	5.4
STD OREAS45CA	Standard	<20	3.94	0.013	0.08	<0.1	0.03	39.8	<0.1	0.05	19	0.9	<0.2
STD DS8 Expected		2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected			3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank												
BLK	Blank	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 24, 2011
Report Date: January 12, 2012
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001217.3

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #15
P.O. Number
Number of Samples: 316

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	316	Sieve soil to 230 mesh			WHI
RJSV	316	Saving all or part of Soil Reject			WHI
1DX2	311	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Version 3: Revised sample ID's for 1279951 to 1279960

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094952	Soil	2.4	21.6	17.9	125	<0.1	33.3	15.2	246	3.13	15.6	2.3	1.4	12	0.1	1.0	0.3	30	0.02	0.047	4
1094953	Soil	2.6	18.8	23.8	67	<0.1	16.3	6.7	127	1.63	12.6	1.9	0.4	17	0.1	0.8	0.3	27	0.03	0.049	5
1094954	Soil	5.1	24.5	30.8	70	0.6	27.5	7.6	114	2.27	20.5	3.3	1.0	33	0.2	1.7	0.3	26	<0.01	0.046	3
1094955	Soil	3.7	36.5	20.2	153	1.1	35.1	11.4	202	2.92	22.4	3.5	1.7	36	0.7	1.9	0.3	46	0.08	0.138	7
1094956	Soil	3.5	26.7	18.3	87	0.2	19.4	7.2	163	2.21	25.5	1.1	0.3	16	0.3	1.3	0.3	37	0.02	0.060	6
1094957	Soil	2.1	12.0	8.1	43	0.1	9.1	3.2	41	0.99	9.2	1.2	0.2	8	<0.1	0.5	0.1	24	<0.01	0.036	4
1094958	Soil	2.3	21.5	12.0	72	<0.1	14.6	5.7	72	1.73	15.0	<0.5	0.3	10	0.2	1.0	0.2	33	0.01	0.051	5
1094959	Soil	18.7	61.5	28.9	220	3.9	49.0	4.6	63	3.97	41.1	2.0	0.4	54	1.5	9.9	0.3	124	0.04	0.328	5
1094960	Soil	1.6	22.5	5.3	38	0.4	9.0	2.5	42	0.80	4.0	0.9	<0.1	11	0.5	0.8	0.1	18	0.12	0.076	2
1094961	Soil	3.4	41.0	13.4	73	1.0	19.9	6.6	72	1.66	14.8	1.8	0.2	6	0.3	1.7	0.4	44	0.02	0.074	5
1094962	Soil	1.2	25.0	9.1	91	0.3	15.2	6.3	589	2.11	14.2	1.3	0.3	19	0.6	0.7	0.1	22	0.42	0.093	3
1094963	Soil	7.8	58.5	33.5	243	0.7	43.9	14.4	823	3.15	259.9	2.7	0.4	27	1.0	3.8	0.4	53	0.30	0.134	5
1094964	Soil	1.9	11.6	9.1	47	0.5	9.7	1.8	82	0.64	133.1	1.6	<0.1	16	0.2	1.1	0.1	15	0.32	0.041	1
1094965	Soil	49.2	52.1	16.6	321	0.6	104.8	6.9	141	2.12	367.0	2.8	1.0	51	2.0	6.2	0.2	53	0.74	0.083	7
1094966	Soil	86.7	82.7	13.7	458	0.4	195.8	8.7	173	2.06	163.2	11.3	2.2	143	4.4	9.5	0.2	95	4.72	0.110	11
1094967	Soil	63.4	69.2	15.2	385	0.4	176.0	9.3	238	2.25	116.8	6.0	2.7	108	3.6	6.8	0.2	95	5.02	0.091	11
1094968	Soil	89.6	99.0	17.0	669	1.2	175.5	7.4	169	2.33	147.3	4.0	1.3	95	8.4	20.5	0.2	220	2.59	0.137	10
1094969	Soil	85.0	73.5	10.6	529	0.6	180.4	6.9	134	1.85	81.2	2.5	1.9	148	6.3	15.9	0.2	175	5.06	0.140	11
1094970	Soil	56.8	34.4	9.9	116	<0.1	112.0	8.3	64	1.99	16.3	1.3	1.7	20	0.6	1.9	0.1	55	0.46	0.046	8
1094991	Soil	138.8	59.5	21.6	437	0.9	228.4	8.5	73	3.08	59.4	1.5	0.1	19	0.5	13.2	0.3	208	0.02	0.118	13
1094992	Soil	175.4	103.4	18.8	991	1.0	262.6	12.5	217	3.01	92.6	2.0	0.4	15	8.4	43.9	0.2	681	0.13	0.151	20
1094993	Soil	38.2	30.6	13.3	303	0.2	78.2	6.8	73	2.29	34.3	1.2	0.2	9	0.6	9.3	0.2	242	0.02	0.086	11
1094994	Soil	34.8	31.4	8.8	313	0.5	166.6	3.5	309	1.53	19.5	0.9	0.2	56	2.5	5.3	0.2	107	0.68	0.087	7
1094995	Soil	40.8	76.6	16.1	6462	1.3	531.3	13.5	288	3.34	45.9	4.2	0.9	98	15.6	13.5	0.2	181	1.08	0.218	16
1094996	Soil	49.6	101.2	20.0	1010	1.5	240.7	15.1	321	3.57	65.0	5.1	1.2	73	14.3	18.0	0.2	247	1.11	0.226	18
1094997	Soil	41.1	77.3	21.0	770	1.0	196.9	21.3	533	4.00	63.3	4.0	2.7	47	4.6	15.4	0.2	226	0.38	0.306	24
1094998	Soil	32.1	47.6	20.5	507	0.6	126.7	11.5	157	2.99	47.1	2.2	0.3	31	3.3	10.3	0.2	203	0.34	0.115	13
1094999	Soil	58.3	92.1	17.8	3041	1.1	363.0	12.8	360	2.98	57.3	2.9	1.1	136	21.2	17.9	0.2	252	3.55	0.213	15
1095000	Soil	15.3	54.7	14.7	339	0.4	98.5	18.2	373	3.13	34.3	2.6	3.6	33	2.5	6.9	0.2	90	0.36	0.145	17
1278401	Soil	13.7	38.0	24.5	261	1.7	64.4	16.2	549	4.67	21.5	4.7	1.5	53	0.4	2.3	0.3	22	0.44	0.102	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094952	Soil	16	0.19	91	0.002	4	0.75	0.003	0.06	<0.1	0.02	2.2	0.1	<0.05	3	<0.5	<0.2
1094953	Soil	8	0.07	178	0.002	3	0.52	0.004	0.05	<0.1	0.02	1.1	0.2	0.06	2	<0.5	<0.2
1094954	Soil	7	0.04	215	0.002	4	0.32	0.003	0.08	<0.1	0.10	1.9	0.5	0.14	1	1.9	<0.2
1094955	Soil	14	0.14	246	0.003	3	0.70	0.004	0.06	<0.1	0.07	2.6	0.2	0.07	2	3.0	<0.2
1094956	Soil	10	0.05	236	0.004	3	0.55	0.003	0.05	0.1	0.04	1.1	0.2	0.06	2	0.9	<0.2
1094957	Soil	5	0.02	120	0.003	2	0.45	0.007	0.03	<0.1	0.01	0.6	0.1	<0.05	2	<0.5	<0.2
1094958	Soil	7	0.03	133	0.003	3	0.49	0.004	0.04	<0.1	0.01	1.0	0.1	<0.05	3	<0.5	<0.2
1094959	Soil	15	0.03	1446	0.004	4	1.06	0.007	0.04	<0.1	0.87	0.9	0.8	0.13	3	9.6	<0.2
1094960	Soil	5	0.02	533	0.002	3	0.24	0.016	0.03	<0.1	0.03	0.5	<0.1	<0.05	1	<0.5	<0.2
1094961	Soil	13	0.01	243	0.003	3	0.44	0.003	0.05	<0.1	0.04	1.0	0.1	<0.05	3	0.6	<0.2
1094962	Soil	9	0.06	220	0.008	2	0.59	0.025	0.03	<0.1	0.06	1.6	<0.1	0.06	2	0.8	<0.2
1094963	Soil	14	0.06	481	0.004	3	0.58	0.009	0.07	<0.1	0.22	2.3	0.3	0.11	2	2.2	<0.2
1094964	Soil	4	0.04	519	0.003	3	0.25	0.025	0.03	<0.1	0.14	0.6	<0.1	0.06	<1	0.6	<0.2
1094965	Soil	12	0.09	1484	0.002	3	0.43	0.007	0.05	0.2	0.46	3.4	0.5	0.08	1	2.1	<0.2
1094966	Soil	16	1.95	462	0.002	5	0.22	0.006	0.05	0.2	0.66	4.1	1.5	<0.05	<1	3.1	<0.2
1094967	Soil	15	2.48	543	0.003	5	0.22	0.005	0.05	0.2	0.53	4.2	1.2	<0.05	<1	2.9	<0.2
1094968	Soil	19	1.01	856	0.003	5	0.40	0.006	0.05	0.2	1.56	3.8	0.8	0.07	1	7.1	<0.2
1094969	Soil	18	2.36	564	0.003	7	0.26	0.006	0.06	0.2	0.72	3.1	1.4	0.06	<1	3.5	<0.2
1094970	Soil	11	0.07	529	0.003	2	0.43	0.003	0.04	0.2	0.09	2.5	0.6	<0.05	1	1.6	<0.2
1094991	Soil	20	0.03	193	0.004	3	0.40	0.004	0.05	0.3	0.07	0.4	1.8	<0.05	3	8.4	<0.2
1094992	Soil	33	0.04	257	0.003	2	0.46	0.002	0.07	0.3	0.29	1.0	2.1	<0.05	2	16.6	0.3
1094993	Soil	20	0.04	143	0.004	1	0.62	0.004	0.04	0.1	0.03	0.4	0.6	<0.05	3	3.0	<0.2
1094994	Soil	14	0.02	291	0.005	2	0.42	0.015	0.05	0.2	0.18	0.8	1.3	0.11	2	3.5	<0.2
1094995	Soil	32	0.27	508	0.008	4	0.88	0.008	0.06	0.2	0.62	3.3	2.3	0.09	2	6.8	<0.2
1094996	Soil	35	0.29	713	0.007	4	0.73	0.007	0.07	0.2	0.71	4.2	0.9	0.06	2	6.2	0.2
1094997	Soil	46	0.23	371	0.013	3	0.98	0.003	0.07	0.3	0.22	4.0	0.8	<0.05	2	5.9	<0.2
1094998	Soil	31	0.12	918	0.006	2	0.88	0.007	0.05	0.2	0.18	1.3	0.7	<0.05	4	3.6	<0.2
1094999	Soil	33	1.31	518	0.007	4	0.51	0.006	0.07	0.2	0.55	3.2	1.4	0.06	1	6.7	<0.2
1095000	Soil	34	0.36	1827	0.021	2	0.83	0.005	0.05	0.2	0.12	3.5	0.3	<0.05	2	1.9	<0.2
1278401	Soil	10	0.10	5575	0.005	3	0.70	0.007	0.09	<0.1	0.47	4.7	0.3	0.07	1	3.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278402	Soil		5.1	62.6	29.4	195	1.9	62.2	22.1	717	5.69	10.9	5.3	2.6	19	0.6	1.6	0.3	25	0.06	0.132	10
1278403	Soil		3.4	95.0	30.7	261	2.9	91.5	22.9	528	5.95	16.6	4.2	3.3	34	0.6	1.9	0.4	25	0.15	0.134	10
1278404	Soil		6.9	115.6	33.7	381	3.5	119.1	18.6	328	4.84	58.9	7.7	2.7	125	1.2	3.6	0.4	29	0.57	0.275	12
1278405	Soil		7.8	62.2	27.5	201	1.5	58.5	10.0	171	2.85	26.4	2.7	0.3	63	0.5	2.1	0.3	29	0.18	0.281	10
1278406	Soil		18.4	174.2	43.0	337	1.7	118.3	8.9	144	3.96	45.9	3.0	0.6	166	1.2	6.3	0.4	117	0.11	0.368	24
1278407	Soil		20.9	42.6	38.0	119	3.1	31.3	3.1	61	1.81	16.8	2.7	0.8	262	0.9	10.4	0.3	108	0.08	0.211	16
1278408	Soil		6.4	145.2	51.1	1037	1.2	105.0	11.6	221	3.51	54.2	7.0	0.5	20	6.4	5.6	0.3	54	0.21	0.165	9
1278409	Soil		6.9	28.9	23.2	141	0.5	34.3	3.8	57	1.95	27.6	0.7	0.1	37	0.3	2.8	0.3	72	0.03	0.124	9
1278410	Soil		7.3	23.2	18.2	87	<0.1	21.0	5.7	76	1.92	46.4	1.4	0.1	11	<0.1	2.2	0.3	59	<0.01	0.068	8
1278411	Soil		7.9	36.4	20.3	134	0.3	39.4	8.1	116	2.71	48.1	0.8	0.2	18	0.2	3.0	0.4	66	0.02	0.135	11
1278412	Soil		7.1	65.7	33.2	227	1.5	83.9	16.2	343	3.39	45.4	4.4	1.8	38	1.0	2.6	0.4	59	0.32	0.131	11
1278413	Soil		3.7	44.9	14.5	160	1.0	41.6	10.0	458	2.18	41.2	5.0	2.2	37	0.8	1.7	0.3	47	0.39	0.137	13
1278414	Soil		8.5	111.5	29.0	492	1.4	115.2	20.6	659	5.10	53.8	3.1	5.0	51	2.9	5.7	0.4	57	0.56	0.181	17
1278415	Soil		9.0	30.8	23.0	104	0.3	25.1	6.6	210	2.30	20.2	1.7	1.1	25	0.4	5.2	0.3	51	0.40	0.110	6
1278416	Soil		4.5	30.5	14.5	124	0.6	23.0	6.1	308	2.64	13.6	2.0	1.5	27	0.8	3.5	0.3	43	0.58	0.125	7
1278417	Soil		2.3	6.9	6.5	33	0.2	7.1	1.6	39	0.68	6.1	<0.5	<0.1	7	<0.1	4.8	0.1	37	0.02	0.081	6
1278418	Soil		31.5	53.8	25.3	427	0.2	95.1	11.4	209	3.90	83.3	2.3	0.5	9	0.7	16.7	0.3	200	<0.01	0.115	9
1278419	Soil		21.5	43.8	20.1	339	0.1	77.3	9.5	109	2.96	49.1	1.8	0.5	11	0.5	8.0	0.2	105	0.03	0.111	10
1278420	Soil		47.8	77.1	20.5	465	0.7	161.8	15.0	335	3.41	56.2	3.4	2.8	42	3.3	8.5	0.2	117	0.60	0.169	14
1278421	Soil		2.2	21.6	10.7	86	0.1	21.9	8.2	81	1.80	17.2	<0.5	0.5	15	0.1	0.7	0.2	31	0.02	0.051	3
1278422	Soil		7.0	29.8	30.0	49	0.7	15.9	4.7	206	1.60	46.3	1.3	0.3	76	0.3	2.5	0.2	55	0.02	0.093	4
1278423	Soil		2.7	28.2	20.3	117	0.2	38.8	20.5	466	2.71	28.1	<0.5	0.7	34	0.4	1.2	0.3	29	0.05	0.081	4
1278424	Soil		3.4	24.6	16.2	78	0.2	20.3	6.8	78	1.75	42.9	1.1	0.3	20	<0.1	1.5	0.3	44	0.02	0.043	6
1278425	Soil		11.3	47.0	50.2	66	1.8	23.3	3.0	57	1.66	78.6	5.2	1.1	130	0.1	6.1	0.3	80	0.04	0.102	5
1278426	Soil		4.1	32.6	15.4	52	0.5	23.6	5.9	75	1.91	55.0	1.4	0.2	19	0.1	2.4	0.3	47	0.02	0.093	3
1278427	Soil		5.1	42.0	19.4	125	0.4	29.7	7.0	211	2.59	38.1	3.3	0.2	18	0.5	2.5	0.4	62	0.04	0.109	7
1278428	Soil		5.8	48.4	15.4	96	0.4	21.1	5.6	87	1.67	23.3	1.0	0.2	11	0.4	2.0	0.3	65	0.05	0.084	6
1278429	Soil		5.1	67.0	25.9	176	0.5	42.9	17.1	678	3.37	50.4	3.5	0.4	27	1.0	3.0	0.4	66	0.09	0.099	7
1278430	Soil		3.7	35.0	12.4	88	0.3	18.8	6.6	324	1.85	34.2	2.1	0.1	16	0.6	1.5	0.3	47	0.08	0.069	4
1278431	Soil		4.0	25.1	13.1	61	0.2	15.6	3.7	77	1.29	52.0	1.4	0.1	19	0.1	1.5	0.3	50	0.09	0.059	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278402	Soil	11	0.07	8680	0.004	4	1.19	0.004	0.10	<0.1	0.21	6.5	0.3	0.07	2	3.9	<0.2
1278403	Soil	11	0.06	9301	0.003	4	0.97	0.003	0.12	<0.1	0.29	7.9	0.3	0.06	1	5.8	<0.2
1278404	Soil	12	0.09	4255	0.003	5	0.77	0.004	0.17	<0.1	0.57	7.0	0.2	0.13	1	5.8	<0.2
1278405	Soil	10	0.05	2974	0.002	4	0.63	0.005	0.11	<0.1	0.24	0.9	0.2	0.17	1	3.7	<0.2
1278406	Soil	22	0.09	562	0.004	5	0.65	0.005	0.18	0.2	0.16	1.6	0.6	0.36	2	6.0	0.3
1278407	Soil	14	0.03	623	0.003	3	0.47	0.011	0.15	0.3	0.17	0.6	1.5	0.29	1	4.7	0.2
1278408	Soil	12	0.04	186	0.002	3	0.37	0.005	0.07	<0.1	1.82	2.7	0.2	<0.05	1	4.4	<0.2
1278409	Soil	13	0.05	140	0.004	2	0.57	0.005	0.06	0.1	0.05	0.1	0.3	<0.05	3	1.9	<0.2
1278410	Soil	7	0.03	90	0.002	3	0.37	0.002	0.05	<0.1	0.03	0.3	0.3	<0.05	2	1.7	<0.2
1278411	Soil	12	0.04	216	0.002	4	0.67	0.004	0.09	0.1	0.07	0.4	0.3	<0.05	3	2.0	<0.2
1278412	Soil	15	0.10	697	0.005	4	1.39	0.009	0.15	<0.1	0.78	4.1	0.3	0.06	3	3.5	<0.2
1278413	Soil	12	0.09	1544	0.002	5	0.87	0.005	0.12	<0.1	0.39	3.6	0.2	<0.05	2	1.9	<0.2
1278414	Soil	15	0.15	3349	0.004	8	0.68	0.002	0.18	<0.1	0.50	5.7	0.3	<0.05	2	3.5	<0.2
1278415	Soil	9	0.07	398	0.003	3	0.48	0.003	0.07	<0.1	0.07	1.8	0.2	<0.05	2	1.8	<0.2
1278416	Soil	10	0.12	503	0.002	3	0.80	0.007	0.08	<0.1	0.19	2.4	0.1	0.06	2	1.8	<0.2
1278417	Soil	6	0.02	63	0.002	3	0.33	0.008	0.05	<0.1	0.05	0.2	0.1	<0.05	2	0.7	<0.2
1278418	Soil	16	0.04	97	0.002	2	0.49	0.002	0.05	0.1	0.05	1.1	0.2	<0.05	2	3.1	<0.2
1278419	Soil	12	0.03	101	0.002	3	0.39	0.001	0.06	<0.1	0.04	0.8	0.2	<0.05	2	2.4	<0.2
1278420	Soil	17	0.12	866	0.004	7	0.47	0.002	0.10	0.1	0.64	4.7	0.6	0.05	1	3.5	<0.2
1278421	Soil	7	0.04	193	<0.001	2	0.40	0.005	0.05	<0.1	0.05	1.4	0.1	<0.05	2	0.8	<0.2
1278422	Soil	10	0.02	972	0.001	1	0.48	0.005	0.09	<0.1	0.05	1.0	0.5	0.13	2	2.2	<0.2
1278423	Soil	9	0.04	391	0.002	2	0.34	0.003	0.09	<0.1	0.05	2.9	0.3	0.11	1	1.4	<0.2
1278424	Soil	8	0.02	161	0.003	2	0.34	0.003	0.05	0.1	0.03	1.2	0.2	<0.05	2	1.4	<0.2
1278425	Soil	13	0.03	1194	0.008	3	0.48	0.004	0.10	<0.1	0.31	2.8	0.8	0.14	2	6.1	<0.2
1278426	Soil	10	0.02	324	0.003	3	0.54	0.006	0.05	<0.1	0.06	0.7	0.2	<0.05	2	1.7	<0.2
1278427	Soil	17	0.04	274	0.003	4	0.46	0.004	0.08	0.1	0.09	0.8	0.2	0.07	2	1.8	<0.2
1278428	Soil	17	0.03	166	0.003	3	0.53	0.004	0.06	<0.1	0.07	0.9	0.1	<0.05	3	1.5	<0.2
1278429	Soil	19	0.11	394	0.008	1	0.91	0.008	0.07	<0.1	0.06	2.9	0.3	<0.05	3	2.0	<0.2
1278430	Soil	9	0.06	163	0.006	2	0.52	0.019	0.05	<0.1	0.06	0.8	0.1	<0.05	3	1.4	<0.2
1278431	Soil	9	0.05	207	0.003	3	0.40	0.012	0.06	<0.1	0.04	0.6	0.2	<0.05	2	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278432	Soil		4.5	17.5	22.3	42	0.4	11.5	1.4	23	0.56	92.7	1.6	<0.1	31	0.8	1.7	0.4	44	0.05	0.057	2
1278433	Soil		92.6	73.6	9.2	724	0.5	201.8	5.9	113	2.40	62.6	1.5	2.1	103	5.2	9.4	0.1	168	3.76	0.099	15
1278434	Soil		30.6	37.2	19.4	180	0.2	70.2	8.9	198	2.10	39.8	1.6	0.9	20	1.1	4.2	0.3	94	0.11	0.067	6
1278435	Soil		92.1	76.3	23.9	673	0.5	237.1	11.0	154	3.17	59.5	2.2	0.9	24	3.1	20.5	0.3	294	0.18	0.105	12
1278436	Soil		69.9	68.9	8.8	774	0.7	179.0	5.7	135	1.68	34.8	2.5	1.6	224	4.7	15.2	0.1	180	9.29	0.083	10
1278437	Soil		62.2	59.6	9.6	461	0.3	161.8	8.0	213	2.27	21.9	1.6	1.4	90	1.8	2.9	0.1	70	3.04	0.102	11
1278438	Soil		40.4	42.8	9.4	141	0.3	117.1	8.6	203	2.22	17.1	1.7	1.5	86	1.1	2.4	0.1	55	2.14	0.093	9
1278439	Soil		48.3	54.8	8.9	195	0.4	131.3	6.7	103	1.60	30.3	2.0	0.8	59	3.6	3.8	0.2	85	1.17	0.056	11
1278440	Soil		9.0	22.5	5.2	76	0.1	43.1	2.9	137	0.73	7.7	0.6	0.2	91	1.4	1.3	<0.1	37	2.24	0.070	5
1278441	Soil		42.7	45.7	13.2	336	0.5	113.6	8.4	374	1.62	35.1	1.7	1.4	90	4.3	4.5	0.2	85	1.71	0.106	10
1278442	Soil		49.7	69.3	22.5	559	1.5	129.7	5.6	110	1.77	83.0	1.8	1.1	109	8.8	9.8	0.3	151	1.11	0.134	8
1278443	Soil		41.0	84.8	25.4	551	1.4	135.5	5.1	99	1.72	122.8	2.5	0.6	122	8.5	9.5	0.3	154	1.30	0.128	5
1278444	Soil		60.1	80.9	24.7	681	1.4	169.2	8.7	197	1.80	91.0	2.2	1.5	178	9.7	12.7	0.3	207	4.85	0.147	7
1278445	Soil		30.3	26.3	16.1	260	0.2	75.0	6.7	101	2.81	27.0	1.3	2.3	10	0.8	3.8	0.2	120	0.04	0.036	9
1278446	Soil		19.6	17.0	13.3	147	0.2	37.1	3.7	63	1.69	20.5	1.5	1.9	13	0.8	3.3	0.2	116	0.13	0.035	11
1278447	Soil		29.0	30.1	19.8	337	0.5	69.1	7.4	114	3.31	28.1	1.6	3.2	8	0.8	7.1	0.2	128	0.02	0.050	11
1278448	Soil		26.9	52.5	13.8	370	0.7	90.2	9.0	185	2.55	24.2	2.4	2.8	43	2.5	5.3	0.2	109	0.60	0.123	12
1278449	Soil		29.7	31.6	15.5	265	0.3	62.7	6.9	134	2.34	25.2	0.8	2.4	20	2.4	4.0	0.2	120	0.18	0.061	12
1278450	Soil		40.4	25.0	13.5	248	<0.1	66.2	5.7	78	2.00	29.2	0.7	1.7	7	0.6	6.1	0.2	120	0.02	0.037	11
1278451	Soil		31.1	49.8	13.4	345	0.5	99.7	9.2	242	2.09	22.8	2.2	3.6	50	5.1	6.1	0.2	94	0.72	0.131	12
1278452	Soil		13.7	36.7	12.8	251	0.7	58.7	8.8	198	2.11	18.8	2.1	3.2	50	1.6	3.4	0.2	79	0.70	0.102	10
1278453	Soil		13.8	27.4	13.3	188	0.6	29.8	5.5	266	2.01	17.7	1.6	2.0	57	1.5	3.5	0.2	76	0.74	0.109	10
1278454	Soil		17.7	57.3	14.2	338	0.7	83.7	9.6	396	2.32	25.3	2.7	2.0	67	3.8	5.5	0.2	88	1.32	0.109	8
1278455	Soil		9.7	55.8	12.9	291	0.7	77.6	8.8	227	2.22	18.5	2.5	3.3	64	2.8	4.5	0.2	61	1.44	0.139	12
1278456	Soil		12.5	40.1	16.9	199	0.3	51.4	13.2	222	2.49	29.1	3.7	2.0	22	1.3	3.9	0.3	86	0.14	0.088	14
1278457	Soil		7.0	24.4	12.2	100	<0.1	26.4	6.7	238	3.40	23.2	1.2	1.4	7	0.3	2.2	0.3	62	0.02	0.037	11
1278458	Soil		22.3	44.8	16.9	232	0.7	62.1	9.8	251	2.88	56.2	3.6	1.8	37	1.4	3.6	0.3	42	0.30	0.085	15
1278459	Soil		71.8	74.8	32.5	726	2.2	166.8	11.4	95	3.60	100.5	0.7	0.7	143	1.8	16.4	0.4	182	0.10	0.158	16
1278460	Soil		6.6	19.7	9.3	104	0.5	26.9	7.0	359	1.44	19.8	1.0	1.4	31	1.3	1.8	0.2	53	0.52	0.082	6
1278461	Soil		7.1	72.9	12.4	191	1.7	102.1	18.4	417	2.65	46.0	2.4	1.7	77	4.8	3.4	0.2	63	1.38	0.122	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278432	Soil	5	0.03	123	0.003	3	0.26	0.020	0.04	<0.1	0.27	0.4	0.3	<0.05	1	0.9	<0.2
1278433	Soil	19	1.81	319	0.002	6	0.33	0.005	0.06	0.2	0.77	3.7	1.4	<0.05	<1	6.5	<0.2
1278434	Soil	13	0.05	642	0.001	4	0.59	0.003	0.06	0.1	0.08	2.0	0.7	0.08	2	2.0	<0.2
1278435	Soil	22	0.08	297	0.002	3	0.55	0.003	0.09	0.3	0.25	1.8	0.9	0.07	2	9.0	0.2
1278436	Soil	14	3.11	306	0.003	7	0.25	0.008	0.07	0.1	0.46	2.3	1.5	<0.05	<1	4.9	0.2
1278437	Soil	18	1.20	504	0.004	6	0.41	0.006	0.07	0.2	0.28	3.4	1.1	<0.05	1	2.7	<0.2
1278438	Soil	12	0.59	775	0.003	5	0.33	0.007	0.05	0.2	0.35	3.1	0.6	<0.05	<1	1.9	<0.2
1278439	Soil	20	0.16	390	0.003	3	0.50	0.008	0.05	0.2	0.45	3.4	1.5	<0.05	2	2.5	<0.2
1278440	Soil	10	0.19	378	0.005	4	0.46	0.021	0.04	<0.1	0.13	0.9	0.6	0.09	1	3.3	<0.2
1278441	Soil	23	0.16	370	0.003	6	0.36	0.004	0.08	0.2	0.46	4.3	1.4	0.07	1	3.0	<0.2
1278442	Soil	18	0.10	587	0.003	7	0.32	0.003	0.09	0.2	1.23	3.6	0.9	0.05	1	5.6	<0.2
1278443	Soil	16	0.12	570	0.002	5	0.32	0.004	0.08	0.1	1.10	1.8	0.7	<0.05	1	6.4	0.2
1278444	Soil	21	2.02	369	0.002	7	0.26	0.005	0.07	0.2	1.18	3.4	1.1	0.07	<1	5.9	<0.2
1278445	Soil	18	0.11	370	0.002	2	0.94	0.002	0.05	0.1	0.06	1.8	0.4	<0.05	3	2.0	<0.2
1278446	Soil	12	0.09	410	0.005	2	0.64	0.002	0.04	0.2	0.06	1.1	0.4	<0.05	3	1.4	<0.2
1278447	Soil	19	0.09	194	0.003	3	0.90	0.004	0.05	0.1	0.06	1.7	0.4	<0.05	3	2.6	<0.2
1278448	Soil	23	0.20	1126	0.004	3	0.89	0.003	0.07	0.2	0.45	4.3	0.3	<0.05	2	1.9	<0.2
1278449	Soil	17	0.13	678	0.003	2	0.82	0.002	0.06	0.1	0.11	1.9	0.4	<0.05	3	1.5	<0.2
1278450	Soil	10	0.03	133	0.004	2	0.41	0.002	0.04	0.1	0.07	1.2	0.4	<0.05	2	1.5	<0.2
1278451	Soil	16	0.19	737	0.004	5	0.52	0.004	0.08	0.1	0.35	3.5	0.4	<0.05	2	1.9	<0.2
1278452	Soil	17	0.19	581	0.004	3	0.74	0.005	0.06	0.1	0.28	3.4	0.2	<0.05	2	1.3	<0.2
1278453	Soil	15	0.19	717	0.004	3	0.68	0.005	0.07	0.1	0.33	2.7	0.2	0.06	2	2.3	<0.2
1278454	Soil	15	0.45	1146	0.003	5	0.70	0.011	0.09	0.1	0.37	3.3	0.4	0.06	2	2.6	<0.2
1278455	Soil	12	0.57	725	0.005	4	0.46	0.004	0.07	<0.1	0.28	3.9	0.2	0.05	1	2.0	<0.2
1278456	Soil	12	0.08	370	0.004	2	0.64	0.003	0.05	0.1	0.09	1.7	0.2	<0.05	3	2.0	<0.2
1278457	Soil	13	0.04	175	0.006	2	0.71	0.004	0.04	0.2	0.03	1.1	0.1	<0.05	3	1.0	<0.2
1278458	Soil	9	0.08	583	0.002	3	0.51	0.004	0.07	<0.1	0.42	2.3	0.2	<0.05	1	1.6	<0.2
1278459	Soil	19	0.02	491	0.003	2	0.49	0.004	0.09	0.2	0.17	1.4	1.2	0.13	3	4.6	0.2
1278460	Soil	10	0.10	479	0.003	2	0.51	0.012	0.04	<0.1	0.28	1.6	0.1	0.05	2	1.1	<0.2
1278461	Soil	21	0.14	1017	0.002	2	0.75	0.006	0.04	0.1	0.61	5.3	0.2	0.14	2	3.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278462	Soil		24.2	45.6	15.8	635	0.8	90.9	6.6	163	2.51	50.4	2.8	2.6	65	5.3	5.7	0.2	90	0.82	0.194	13
1278463	Soil		13.9	35.9	11.9	212	0.8	45.3	6.0	170	2.16	21.4	1.4	1.1	36	2.6	2.7	0.2	69	0.41	0.116	6
1278464	Soil		15.9	38.9	12.8	261	0.5	55.1	8.0	155	2.24	23.4	2.5	3.0	50	1.6	3.6	0.2	76	0.50	0.114	10
1278465	Soil		7.4	53.4	19.3	183	0.9	46.3	5.8	96	1.93	15.3	2.7	1.0	44	1.7	1.9	0.2	50	0.22	0.124	11
1278466	Soil		6.4	12.9	14.2	85	0.1	18.1	4.6	120	2.23	19.8	0.7	1.5	9	0.3	1.7	0.2	63	0.02	0.068	9
1278467	Soil		13.6	40.0	14.0	214	0.3	52.6	7.8	125	2.56	25.9	2.1	2.5	17	0.8	3.6	0.2	79	0.06	0.079	11
1278468	Soil		83.1	62.8	28.5	423	0.4	184.0	10.7	609	5.03	24.6	<0.5	2.4	200	1.5	6.8	0.1	88	9.27	0.115	4
1278469	Soil		90.6	81.3	30.1	748	0.5	202.7	10.6	480	3.62	31.8	0.9	2.2	193	7.2	12.0	0.1	197	9.46	0.129	4
1278470	Soil		84.3	135.4	34.2	1440	1.4	270.9	18.7	697	5.38	43.3	1.6	1.7	194	13.1	15.2	0.2	451	4.13	0.294	6
1278471	Soil		90.0	120.8	29.2	1728	1.3	249.6	23.1	824	4.75	41.9	0.8	2.9	319	16.3	14.1	0.2	464	8.85	0.385	9
1278472	Soil		85.0	100.9	36.9	590	0.6	246.7	14.8	384	4.74	33.0	0.8	1.8	92	5.5	6.6	0.2	152	3.79	0.118	8
1278473	Soil		63.0	66.0	12.8	500	0.3	160.4	8.5	217	2.28	25.5	1.4	1.0	38	5.3	7.5	0.1	116	0.84	0.112	7
1278474	Soil		65.3	73.4	14.4	500	0.4	170.7	9.1	214	2.61	27.9	1.5	1.4	35	4.8	8.7	0.2	134	0.72	0.110	9
1278475	Soil		81.4	70.4	15.4	561	0.4	174.6	10.3	230	2.77	30.4	0.9	1.7	29	5.1	8.5	0.2	127	0.59	0.092	9
1278476	Soil		76.2	70.9	16.3	413	0.5	178.8	11.3	266	3.27	22.6	1.3	1.8	38	3.3	6.6	0.2	105	0.64	0.128	7
1278477	Soil		67.0	55.5	15.6	347	0.4	134.0	9.5	207	2.97	19.9	1.3	1.4	31	2.1	6.4	0.2	108	0.49	0.116	5
1278478	Soil		52.6	79.8	35.7	257	0.6	133.2	21.0	661	5.78	41.0	4.6	2.0	20	1.1	16.2	0.4	76	0.29	0.104	9
1278479	Soil		13.3	93.8	29.2	231	1.1	105.5	14.7	329	4.01	21.8	2.4	2.0	54	1.3	8.2	0.3	74	0.81	0.166	8
1278480	Soil		4.7	16.6	12.1	57	0.2	22.2	3.0	106	0.93	4.1	2.0	<0.1	8	0.2	1.2	0.2	25	0.01	0.091	3
1278481	Soil		50.8	116.4	45.8	138	2.9	46.0	5.3	228	2.33	31.0	4.8	0.3	72	2.1	10.4	0.4	299	0.09	0.311	12
1278482	Soil		18.1	178.3	18.5	219	0.2	73.3	10.3	135	3.23	28.7	3.2	0.2	6	0.9	6.5	0.3	61	<0.01	0.077	7
1278483	Soil		53.4	128.4	27.0	643	1.4	173.9	11.0	124	4.37	49.3	2.5	0.2	4	2.3	15.1	0.3	115	0.02	0.114	5
1278484	Soil		2.4	92.4	26.0	239	0.7	80.0	9.5	115	2.62	15.9	4.2	2.0	12	3.4	3.6	0.2	15	0.18	0.088	7
1278485	Soil		8.3	90.5	16.7	178	0.7	67.5	9.9	143	2.80	17.8	6.4	0.4	25	0.7	3.7	0.3	39	0.11	0.129	11
1278486	Soil		22.7	136.5	26.3	475	0.4	72.1	13.4	124	3.62	38.3	2.2	0.2	7	0.6	14.0	0.3	66	0.02	0.119	6
1278487	Soil		3.3	17.2	3.8	41	0.3	9.0	2.5	56	0.64	4.6	<0.5	<0.1	4	0.1	1.7	<0.1	17	0.01	0.051	2
1278488	Soil		7.7	189.1	24.2	183	1.0	122.7	12.7	168	3.88	30.1	4.9	1.4	39	0.8	5.4	0.3	34	0.29	0.195	10
1278489	Soil		81.4	138.7	41.9	681	6.9	165.5	10.5	145	6.03	89.6	1.9	1.4	183	3.6	21.3	0.4	209	0.10	0.331	22
1278490	Soil		78.8	172.6	76.2	373	5.3	100.6	6.4	100	2.96	47.3	2.9	0.3	123	2.5	21.3	0.4	333	0.21	0.328	19
1278491	Soil		9.1	75.0	85.6	319	0.6	111.7	12.5	267	2.83	35.9	1.1	0.1	111	0.3	5.1	0.7	62	0.05	0.285	18

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278462	Soil	15	0.09	878	0.003	4	0.47	0.004	0.07	<0.1	0.62	3.0	0.5	0.07	1	3.1	<0.2
1278463	Soil	15	0.16	971	0.003	2	0.80	0.007	0.06	0.1	0.19	1.9	0.2	<0.05	3	1.1	<0.2
1278464	Soil	18	0.19	1127	0.003	3	0.77	0.005	0.07	0.1	0.34	3.1	0.2	<0.05	2	1.9	<0.2
1278465	Soil	13	0.10	1064	0.002	2	0.83	0.009	0.09	<0.1	0.31	1.8	0.2	0.05	2	1.4	<0.2
1278466	Soil	11	0.08	131	0.006	<1	0.57	0.002	0.04	0.1	0.02	1.1	0.1	<0.05	3	0.8	<0.2
1278467	Soil	16	0.14	418	0.003	2	0.78	0.003	0.04	0.1	0.14	2.4	0.3	<0.05	2	1.4	<0.2
1278468	Soil	20	4.82	274	0.002	4	0.14	0.009	0.03	<0.1	0.30	4.1	0.9	<0.05	<1	2.6	<0.2
1278469	Soil	21	4.47	367	0.002	4	0.18	0.009	0.03	<0.1	0.38	4.5	0.8	0.05	<1	5.2	<0.2
1278470	Soil	57	1.63	352	0.004	4	0.52	0.009	0.05	0.1	0.51	6.1	0.5	0.06	1	11.6	<0.2
1278471	Soil	45	3.45	396	0.005	3	0.39	0.009	0.04	0.1	0.59	6.3	0.5	<0.05	1	8.5	<0.2
1278472	Soil	25	1.53	223	0.002	3	0.36	0.007	0.03	0.1	0.42	4.9	0.8	0.06	<1	4.6	<0.2
1278473	Soil	16	0.14	168	0.004	2	0.37	0.005	0.03	0.1	0.16	2.8	0.5	0.08	1	4.0	<0.2
1278474	Soil	19	0.14	221	0.004	2	0.44	0.005	0.03	0.1	0.21	3.4	0.5	<0.05	1	4.5	<0.2
1278475	Soil	18	0.13	198	0.002	1	0.37	0.003	0.04	0.2	0.20	3.9	0.5	<0.05	<1	4.9	<0.2
1278476	Soil	20	0.16	224	0.004	2	0.42	0.004	0.04	0.1	0.26	4.3	0.5	<0.05	1	4.3	<0.2
1278477	Soil	17	0.11	897	0.003	1	0.47	0.005	0.03	0.1	0.17	3.6	0.4	0.05	1	3.8	<0.2
1278478	Soil	15	0.10	439	0.003	2	0.39	0.002	0.05	<0.1	0.18	5.8	0.3	<0.05	1	3.1	<0.2
1278479	Soil	19	0.23	988	0.003	2	0.36	0.004	0.05	<0.1	0.17	4.8	0.1	<0.05	<1	3.4	<0.2
1278480	Soil	5	0.01	77	0.002	1	0.31	0.016	0.03	<0.1	0.03	0.2	<0.1	<0.05	1	1.6	<0.2
1278481	Soil	18	0.03	187	0.004	2	0.65	0.011	0.06	0.3	0.13	0.5	0.4	<0.05	2	3.6	0.4
1278482	Soil	12	0.02	55	0.004	2	0.21	0.002	0.04	<0.1	0.02	0.6	0.1	<0.05	2	3.2	0.2
1278483	Soil	11	0.02	58	0.003	1	0.17	0.004	0.04	0.1	0.07	1.4	0.7	<0.05	<1	6.1	<0.2
1278484	Soil	9	0.02	69	<0.001	2	0.11	0.001	0.03	<0.1	0.13	3.5	<0.1	<0.05	<1	3.0	<0.2
1278485	Soil	11	0.02	297	0.002	2	0.27	0.003	0.05	<0.1	0.10	1.6	0.1	<0.05	<1	2.3	<0.2
1278486	Soil	9	0.02	108	0.003	19	0.28	0.003	0.06	<0.1	0.06	0.6	0.2	<0.05	1	5.5	0.2
1278487	Soil	3	0.01	30	0.003	<1	0.16	0.019	0.03	<0.1	0.03	0.1	<0.1	<0.05	<1	0.5	<0.2
1278488	Soil	19	0.02	236	0.002	2	0.27	0.001	0.07	<0.1	0.21	3.4	0.2	<0.05	<1	5.3	<0.2
1278489	Soil	26	0.05	378	0.006	3	0.45	0.004	0.23	0.4	0.69	2.7	2.4	0.32	2	13.1	0.3
1278490	Soil	21	0.04	242	0.003	<1	0.48	0.010	0.11	0.6	0.27	0.7	0.6	0.06	2	9.4	0.5
1278491	Soil	15	0.04	373	0.001	2	0.49	0.005	0.10	<0.1	0.05	0.3	0.2	<0.05	2	4.7	0.4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278492	Soil	6.3	49.3	18.0	120	0.2	56.3	17.8	439	4.19	32.6	3.0	0.7	22	0.4	5.2	0.5	37	0.07	0.144	11
1278493	Soil	8.8	118.3	29.3	363	2.8	145.5	23.1	347	4.75	41.8	4.2	6.1	156	1.1	8.2	0.5	37	1.57	0.174	12
1278494	Soil	58.8	47.2	17.8	427	0.6	136.1	12.0	412	3.00	28.1	<0.5	3.2	125	3.8	15.8	0.2	212	5.07	0.083	3
1278495	Soil	76.1	64.8	21.2	432	0.7	164.0	14.8	520	3.25	34.5	<0.5	3.9	124	3.2	16.7	0.2	218	4.18	0.074	3
1278496	Soil	87.9	54.0	18.9	393	0.3	180.7	11.3	535	3.57	22.2	<0.5	2.5	71	2.9	9.0	0.2	176	1.96	0.096	5
1278497	Soil	103.5	66.0	15.9	340	0.3	216.8	12.1	351	3.16	22.0	2.2	3.0	66	2.5	6.1	0.1	94	2.60	0.074	3
1278498	Soil	90.8	62.1	12.8	246	0.2	182.2	9.9	312	2.45	20.6	<0.5	3.4	72	2.7	2.9	0.1	50	3.52	0.066	4
1278499	Soil	70.1	51.7	8.8	181	0.2	141.6	7.3	262	2.17	14.7	<0.5	3.0	176	1.7	2.6	<0.1	52	9.71	0.064	5
1278500	Soil	91.6	67.7	10.8	308	0.4	203.0	8.1	250	1.51	22.8	1.0	2.9	90	3.2	6.1	0.1	91	5.40	0.045	7
1278731	Soil	2.9	15.3	13.8	63	0.1	13.2	4.4	108	2.06	14.8	<0.5	0.8	14	0.1	1.2	0.3	46	0.04	0.050	8
1278732	Soil	2.0	22.1	13.8	60	0.1	17.3	6.9	120	1.10	7.3	<0.5	0.8	22	0.4	0.5	0.3	24	0.13	0.056	4
1278733	Soil	2.9	22.0	11.2	83	0.2	20.5	7.7	172	1.76	11.5	3.6	0.9	20	0.4	1.0	0.2	38	0.26	0.049	5
1278734	Soil	3.4	17.4	13.1	101	2.4	13.1	2.8	30	1.09	7.0	<0.5	0.1	15	0.4	1.5	0.2	56	0.01	0.059	3
1278735	Soil	3.5	11.6	10.3	37	0.9	6.7	2.6	34	0.95	6.7	<0.5	0.3	9	<0.1	0.6	0.2	40	<0.01	0.046	4
1278736	Soil	3.4	22.1	14.3	100	0.5	24.0	7.6	116	2.84	15.9	2.3	1.6	14	0.2	1.1	0.3	51	0.01	0.042	5
1278737	Soil	2.2	16.2	11.6	66	0.5	15.4	4.9	78	2.49	13.5	<0.5	0.9	11	0.1	0.9	0.2	38	0.01	0.042	3
1278738	Soil	27.4	13.0	55.6	10	1.4	3.3	0.5	11	2.46	15.1	1.3	0.4	100	<0.1	4.5	0.3	79	0.01	0.083	2
1278739	Soil	15.9	22.4	28.1	49	0.9	13.0	2.5	67	1.26	16.6	<0.5	0.6	41	0.2	3.2	0.3	56	0.06	0.051	3
1278740	Soil	3.1	15.3	12.9	62	0.3	12.4	4.3	59	1.77	15.1	<0.5	0.8	13	<0.1	1.0	0.2	49	<0.01	0.053	4
1278741	Soil	2.3	15.1	11.5	68	0.1	14.0	4.5	69	2.24	11.6	0.7	0.7	12	<0.1	0.9	0.3	48	<0.01	0.052	4
1278742	Soil	8.5	88.2	21.2	337	0.4	95.3	20.3	273	4.47	15.2	0.6	1.3	27	0.2	3.0	0.5	74	0.03	0.128	3
1278743	Soil	14.6	33.8	22.7	86	0.8	25.2	3.8	66	1.68	13.6	2.6	1.2	52	0.5	2.5	0.4	71	0.11	0.074	5
1278744	Soil	30.1	25.0	24.6	85	0.9	19.4	2.6	34	1.84	18.1	1.5	0.6	53	0.4	4.7	0.2	98	0.08	0.072	4
1278745	Soil	16.2	30.8	17.6	161	1.1	34.7	5.0	126	1.93	21.9	<0.5	1.1	38	1.4	3.1	0.3	127	0.24	0.093	5
1278746	Soil	21.7	38.4	17.5	407	0.9	66.7	10.8	549	1.82	17.1	2.9	1.2	48	4.0	4.2	0.3	94	0.54	0.083	4
1278747	Soil	12.0	39.3	15.6	1248	0.5	123.7	7.9	230	2.35	20.3	2.5	1.4	63	10.3	3.2	0.2	76	0.96	0.089	5
1278748	Soil	20.5	32.0	6.6	162	0.3	88.3	4.6	97	1.44	11.8	0.7	1.0	66	1.5	1.9	<0.1	41	2.37	0.052	6
1278749	Soil	4.8	28.2	10.6	372	0.3	157.1	6.8	167	1.84	13.6	1.8	0.7	103	3.0	1.6	0.2	36	2.18	0.071	4
1278750	Soil	20.3	43.7	12.1	231	0.6	78.0	8.1	226	1.97	17.7	2.9	1.0	62	2.2	3.8	0.2	76	1.63	0.062	5
1278751	Soil	22.7	35.6	12.0	211	0.5	64.5	8.2	191	2.07	17.0	3.2	1.5	36	0.8	2.6	0.2	56	0.36	0.072	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278492	Soil	18	0.12	1475	0.005	1	0.74	0.003	0.06	<0.1	0.06	1.1	0.1	<0.05	2	3.0	<0.2
1278493	Soil	14	0.67	4343	0.001	3	0.53	0.002	0.07	<0.1	0.31	6.7	0.2	<0.05	<1	4.7	0.3
1278494	Soil	12	2.39	322	0.003	2	0.14	0.007	0.03	<0.1	0.23	4.1	0.4	<0.05	<1	3.3	<0.2
1278495	Soil	14	1.95	453	0.003	3	0.22	0.008	0.04	<0.1	0.25	4.5	0.5	<0.05	<1	3.3	<0.2
1278496	Soil	17	0.96	371	0.005	2	0.31	0.006	0.05	<0.1	0.19	5.1	0.6	<0.05	<1	4.4	<0.2
1278497	Soil	13	1.10	144	0.004	2	0.31	0.006	0.04	<0.1	0.32	4.4	0.9	<0.05	<1	5.0	<0.2
1278498	Soil	13	1.66	112	0.003	3	0.27	0.004	0.04	<0.1	0.20	4.3	0.8	<0.05	<1	3.9	<0.2
1278499	Soil	12	2.82	109	0.002	4	0.19	0.006	0.03	<0.1	0.25	3.1	0.9	0.09	<1	3.0	<0.2
1278500	Soil	13	2.40	109	0.002	4	0.17	0.005	0.04	0.2	0.25	3.8	1.0	0.08	<1	4.6	<0.2
1278731	Soil	12	0.09	184	0.007	<1	0.56	0.004	0.05	0.1	<0.01	1.3	0.1	<0.05	3	1.1	0.2
1278732	Soil	10	0.07	619	0.001	<1	0.66	0.009	0.06	<0.1	0.03	1.6	0.1	<0.05	2	0.6	<0.2
1278733	Soil	13	0.15	398	0.003	<1	0.65	0.005	0.05	0.1	0.05	1.7	0.1	<0.05	2	1.4	<0.2
1278734	Soil	7	0.01	145	0.003	<1	0.30	0.011	0.04	<0.1	0.04	0.3	0.1	<0.05	2	3.9	<0.2
1278735	Soil	8	0.02	124	0.002	<1	0.52	0.006	0.04	<0.1	0.04	0.6	0.1	<0.05	3	0.8	<0.2
1278736	Soil	18	0.12	177	0.002	1	0.99	0.004	0.04	<0.1	0.06	2.0	0.1	<0.05	3	1.7	<0.2
1278737	Soil	14	0.07	94	0.002	<1	0.68	0.007	0.04	<0.1	0.04	1.4	<0.1	<0.05	3	1.4	<0.2
1278738	Soil	10	<0.01	331	0.001	1	0.27	0.013	0.28	<0.1	0.14	0.8	1.0	0.62	2	5.2	<0.2
1278739	Soil	9	0.04	757	0.002	3	0.36	0.004	0.07	<0.1	0.17	1.1	0.6	<0.05	2	2.8	<0.2
1278740	Soil	8	0.03	100	0.001	<1	0.46	0.004	0.04	<0.1	0.02	1.3	0.1	<0.05	3	0.7	<0.2
1278741	Soil	11	0.05	91	0.002	1	0.58	0.006	0.04	<0.1	0.03	1.2	0.1	<0.05	3	<0.5	<0.2
1278742	Soil	28	0.06	164	0.003	1	0.84	0.005	0.07	<0.1	0.06	5.6	0.3	<0.05	3	3.1	0.2
1278743	Soil	16	0.08	466	<0.001	<1	0.60	0.006	0.07	<0.1	0.33	2.6	0.4	<0.05	2	2.5	<0.2
1278744	Soil	13	0.05	301	0.001	1	0.48	0.007	0.06	0.1	0.25	1.5	0.6	<0.05	2	3.8	<0.2
1278745	Soil	17	0.11	939	<0.001	<1	0.81	0.006	0.06	0.1	0.31	2.7	0.5	<0.05	3	3.3	0.2
1278746	Soil	17	0.10	1077	0.001	3	0.67	0.008	0.05	<0.1	0.40	2.9	0.4	<0.05	2	3.0	<0.2
1278747	Soil	15	0.15	887	0.001	2	0.71	0.004	0.05	<0.1	0.33	2.8	0.5	0.07	2	4.5	<0.2
1278748	Soil	13	1.08	264	0.003	2	0.41	0.014	0.03	<0.1	0.17	2.4	0.6	0.05	<1	1.4	<0.2
1278749	Soil	12	0.17	649	0.002	3	0.57	0.005	0.02	0.1	0.14	1.4	0.2	0.13	1	1.9	<0.2
1278750	Soil	17	0.18	1008	0.002	3	0.73	0.006	0.04	<0.1	0.26	2.2	0.2	<0.05	2	2.1	<0.2
1278751	Soil	17	0.12	836	0.002	2	0.79	0.007	0.05	0.1	0.16	2.1	0.2	<0.05	2	1.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278752	Soil		14.0	31.6	12.0	159	0.3	45.6	7.2	138	2.12	16.8	2.5	2.1	36	0.7	2.3	0.2	48	0.44	0.077	6
1278753	Soil		43.9	59.0	12.4	263	0.5	148.5	9.9	206	2.29	23.2	<0.5	2.4	51	2.8	3.7	0.2	85	1.42	0.066	10
1278754	Soil		18.5	40.6	8.5	186	0.3	90.6	5.0	121	1.37	11.7	0.6	0.8	57	2.0	2.2	0.1	49	1.21	0.078	7
1278755	Soil		24.5	42.8	9.9	726	0.6	115.6	13.9	356	2.05	19.7	2.2	1.1	71	6.0	4.0	0.1	86	1.11	0.124	7
1278756	Soil		23.4	46.3	11.2	1162	0.8	112.9	10.7	333	2.30	24.1	2.1	1.8	86	4.0	4.9	0.2	84	2.20	0.117	8
1278757	Soil		19.4	39.4	11.6	216	0.4	77.1	9.7	416	1.99	28.9	0.8	1.4	53	3.0	3.7	0.1	49	1.14	0.092	7
1278758	Soil		23.3	43.7	13.9	290	0.7	79.7	8.3	215	2.29	22.9	1.0	1.5	53	2.3	4.9	0.2	95	0.72	0.095	7
1278759	Soil		31.1	47.6	17.9	320	0.5	92.1	9.1	180	2.88	28.6	1.7	2.9	43	1.9	5.4	0.2	92	0.37	0.102	11
1278760	Soil		24.3	21.7	12.2	200	<0.1	48.6	4.9	97	2.02	22.4	1.0	1.2	13	0.8	5.0	0.2	116	0.08	0.058	9
1278761	Soil		15.7	18.1	12.9	197	<0.1	28.9	4.5	103	1.99	18.0	1.1	1.6	10	1.1	4.1	0.2	101	0.05	0.045	11
1278762	Soil		16.1	45.1	15.4	288	0.8	59.0	10.4	268	2.70	26.7	4.0	2.0	41	2.6	4.5	0.3	81	0.23	0.102	10
1278763	Soil		22.9	61.1	14.6	925	0.8	136.6	9.3	171	2.42	51.3	3.2	2.4	101	7.5	7.3	0.2	98	2.07	0.163	13
1278764	Soil		13.1	43.6	13.9	286	0.7	63.0	8.9	284	2.45	23.3	3.5	2.2	52	2.1	4.1	0.2	76	0.62	0.099	7
1278765	Soil		11.3	33.4	14.1	215	0.7	41.6	7.0	220	2.23	26.7	3.5	1.9	49	1.7	3.5	0.2	76	0.52	0.102	8
1278766	Soil		18.4	40.8	17.2	258	0.7	50.7	10.3	300	2.73	33.9	4.7	2.6	50	1.9	4.4	0.3	94	0.37	0.108	9
1278767	Soil		14.6	40.9	15.7	211	0.7	41.6	8.2	156	2.28	19.8	2.1	2.6	38	1.0	3.8	0.2	77	0.23	0.106	10
1278768	Soil		13.6	61.3	24.7	217	0.7	50.0	12.5	300	2.61	34.2	4.1	2.2	45	1.4	5.1	0.3	90	0.21	0.156	12
1278769	Soil		10.3	127.9	43.1	252	2.6	53.3	12.3	196	5.95	28.9	2.8	1.4	44	0.5	7.5	0.4	68	0.03	0.133	2
1278770	Soil		6.4	112.8	38.0	316	1.4	82.1	25.7	742	5.39	20.6	3.8	2.6	45	1.0	5.8	0.4	51	0.04	0.097	3
1278771	Soil		10.4	66.6	30.5	146	0.9	54.9	4.3	80	1.89	19.8	3.4	<0.1	43	0.5	6.4	0.3	58	0.07	0.177	8
1278772	Soil		14.6	52.0	19.5	163	0.3	72.2	7.1	122	2.09	22.5	1.0	<0.1	41	0.2	7.1	0.2	97	0.04	0.169	7
1278773	Soil		11.0	42.8	26.4	118	1.1	57.7	4.9	77	2.46	32.7	1.4	0.1	49	0.4	9.7	0.3	83	0.11	0.328	12
1278774	Soil		8.6	23.7	7.9	109	0.2	35.1	5.4	275	1.57	24.2	0.9	<0.1	15	0.6	4.8	0.1	55	0.06	0.150	6
1278775	Soil		10.9	122.8	22.7	227	0.3	77.3	12.1	327	4.66	37.2	2.1	0.3	21	0.7	7.0	0.3	78	0.13	0.290	12
1278776	Soil		8.8	101.6	14.7	201	0.2	48.8	11.0	142	3.76	23.1	5.1	0.2	13	0.5	6.4	0.2	39	0.07	0.246	7
1278777	Soil		10.6	58.8	22.8	195	0.6	68.3	12.4	414	3.13	28.7	2.1	0.4	33	1.1	9.4	0.3	59	0.09	0.234	14
1278778	Soil		10.2	54.0	28.7	318	0.4	49.5	19.8	837	5.19	24.1	0.9	0.8	14	1.3	11.3	0.5	47	0.02	0.128	7
1278779	Soil		10.2	174.8	30.0	206	1.6	160.4	18.1	352	4.75	46.4	6.1	2.7	99	2.9	22.4	0.3	64	0.64	0.329	23
1278780	Soil		18.2	66.6	21.3	296	1.2	125.2	14.6	652	3.48	36.2	1.9	0.3	45	1.6	7.5	0.3	66	0.25	0.262	11
1278811	Soil		9.1	30.2	27.3	141	0.4	46.7	8.7	181	2.84	28.8	1.9	0.2	40	0.2	6.4	0.3	89	0.05	0.064	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278752	Soil	15	0.16	582	0.003	2	0.71	0.005	0.04	<0.1	0.15	2.3	0.1	<0.05	2	1.3	<0.2
1278753	Soil	26	0.54	571	0.002	3	0.70	0.005	0.06	0.2	0.26	5.1	1.0	<0.05	2	1.5	<0.2
1278754	Soil	17	0.14	318	0.004	3	0.60	0.012	0.04	0.1	0.21	2.0	0.6	0.07	1	2.1	<0.2
1278755	Soil	14	0.09	628	0.003	3	0.58	0.006	0.05	<0.1	0.33	2.5	0.7	0.05	1	1.7	<0.2
1278756	Soil	15	0.86	710	0.003	5	0.49	0.006	0.06	<0.1	0.49	3.1	0.7	0.06	1	2.3	<0.2
1278757	Soil	17	0.18	837	0.003	3	0.69	0.010	0.04	0.1	0.62	2.8	0.3	<0.05	2	2.0	<0.2
1278758	Soil	20	0.18	1190	0.002	3	0.90	0.008	0.07	<0.1	0.36	2.8	0.4	<0.05	2	2.0	<0.2
1278759	Soil	20	0.16	804	0.003	2	0.73	0.003	0.05	0.1	0.31	3.0	0.3	<0.05	2	2.5	<0.2
1278760	Soil	13	0.08	304	0.002	2	0.66	0.002	0.04	0.1	0.05	1.2	0.3	<0.05	2	1.5	<0.2
1278761	Soil	13	0.11	252	0.004	1	0.75	0.003	0.05	0.1	0.04	1.2	0.2	<0.05	3	1.1	<0.2
1278762	Soil	19	0.15	1513	0.002	3	0.88	0.005	0.07	0.1	0.35	2.8	0.3	<0.05	2	1.7	<0.2
1278763	Soil	16	0.82	967	0.004	5	0.48	0.004	0.07	0.1	1.01	3.2	0.6	0.07	1	2.3	<0.2
1278764	Soil	17	0.21	1274	0.002	3	0.89	0.008	0.07	0.1	0.38	3.2	0.3	<0.05	2	2.0	<0.2
1278765	Soil	17	0.16	1010	0.002	3	0.93	0.009	0.06	0.1	0.45	2.5	0.3	0.05	3	1.8	<0.2
1278766	Soil	19	0.14	1208	0.002	3	0.88	0.004	0.06	0.1	0.57	2.8	0.3	<0.05	2	2.3	<0.2
1278767	Soil	19	0.17	851	0.003	3	0.81	0.004	0.07	0.1	0.43	2.8	0.3	<0.05	2	1.4	<0.2
1278768	Soil	16	0.14	618	0.004	3	0.70	0.004	0.06	0.1	0.26	2.1	0.3	<0.05	2	2.2	<0.2
1278769	Soil	23	0.15	343	0.002	2	1.04	0.007	0.10	<0.1	0.14	7.2	0.4	0.13	4	6.4	<0.2
1278770	Soil	16	0.14	417	0.003	2	0.91	0.006	0.09	<0.1	0.10	5.8	0.4	0.08	3	3.3	<0.2
1278771	Soil	12	0.01	159	0.001	1	0.34	0.003	0.05	<0.1	0.05	0.2	0.2	0.10	1	3.2	0.2
1278772	Soil	13	0.02	143	0.002	1	0.42	0.005	0.05	<0.1	0.02	0.2	0.2	0.07	2	3.0	<0.2
1278773	Soil	19	0.02	262	0.003	2	0.47	0.005	0.10	<0.1	0.05	0.2	0.3	0.21	2	3.5	<0.2
1278774	Soil	18	0.03	103	0.002	1	0.46	0.013	0.04	<0.1	0.02	0.2	0.2	0.07	2	1.8	<0.2
1278775	Soil	25	0.04	157	0.005	2	0.55	0.003	0.05	<0.1	0.04	0.8	0.3	0.07	3	3.6	<0.2
1278776	Soil	12	0.04	99	0.003	1	0.44	0.004	0.05	<0.1	0.04	0.4	0.1	0.06	2	3.1	<0.2
1278777	Soil	34	0.09	149	0.005	1	0.60	0.005	0.06	<0.1	0.05	0.9	0.3	0.09	2	3.5	<0.2
1278778	Soil	14	0.06	99	0.006	1	0.52	0.006	0.06	0.1	0.03	3.0	0.5	0.05	2	3.1	<0.2
1278779	Soil	51	0.16	239	0.004	2	0.47	0.003	0.08	<0.1	0.34	7.2	0.3	0.07	1	5.7	<0.2
1278780	Soil	16	0.03	541	0.003	2	0.43	0.005	0.08	<0.1	0.15	0.9	0.5	0.14	1	4.0	<0.2
1278811	Soil	35	0.06	123	0.008	1	0.66	0.005	0.04	0.1	0.02	0.9	0.2	<0.05	4	1.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278812	Soil		6.1	203.8	17.0	434	3.7	229.2	23.5	1289	7.25	46.3	13.6	1.3	164	4.0	10.9	0.4	164	0.34	0.308	3
1278813	Soil		7.3	174.2	21.3	332	4.7	190.8	19.6	951	7.25	59.9	17.7	1.5	164	3.0	15.4	0.4	144	0.25	0.285	4
1278814	Soil		6.6	127.4	24.9	107	2.7	101.1	25.6	931	5.98	53.3	10.0	1.6	108	0.8	8.1	0.4	97	0.11	0.172	3
1278815	Soil		6.8	153.4	27.2	267	4.2	151.0	16.7	607	5.83	48.3	16.3	1.4	157	2.3	12.3	0.4	123	0.22	0.249	4
1278816	Soil		10.9	70.3	33.7	58	7.6	25.2	4.1	197	2.67	45.6	15.0	0.7	211	0.4	11.6	0.4	120	0.09	0.225	7
1278817	Soil		2.5	48.7	9.2	78	1.5	59.5	7.3	840	4.91	13.6	4.7	0.6	40	1.2	3.1	0.2	62	0.19	0.116	4
1278818	Soil		5.5	71.0	20.6	81	3.5	38.3	6.7	384	3.24	26.5	7.7	0.8	107	0.7	6.3	0.3	78	0.13	0.150	6
1278819	Soil		9.2	108.0	41.0	95	7.7	56.9	9.3	437	3.76	54.8	14.6	1.0	244	1.0	13.5	0.4	127	0.13	0.256	6
1278820	Soil		7.2	148.7	27.0	199	4.7	155.3	21.9	705	5.68	57.1	16.5	1.1	204	2.4	11.4	0.4	101	0.24	0.266	4
1278821	Soil		11.8	37.9	22.2	23	5.6	10.9	1.2	40	2.42	63.7	11.2	0.6	117	0.2	13.5	0.3	97	0.02	0.183	4
1278822	Soil		8.1	39.6	12.0	43	2.1	15.6	2.5	78	2.27	32.0	4.5	0.2	64	0.2	6.4	0.2	95	0.03	0.147	5
1278823	Soil		3.4	52.2	9.7	75	1.8	44.0	6.9	245	2.69	42.8	7.2	0.3	82	0.7	7.4	0.2	50	0.10	0.150	3
1278824	Soil		52.5	139.2	24.3	358	4.9	55.6	8.1	311	7.00	56.6	10.8	2.2	96	1.9	21.3	0.3	336	0.08	0.286	6
1278825	Soil		12.4	30.2	11.9	84	1.1	15.6	1.9	39	1.32	15.0	2.8	0.2	21	0.3	5.4	0.2	218	0.03	0.094	13
1278826	Soil		14.2	93.2	24.8	60	5.1	26.6	3.8	129	3.40	58.8	11.2	0.5	145	0.4	11.4	0.4	146	0.07	0.236	4
1278827	Soil		81.6	262.7	22.1	1559	7.7	178.4	10.3	342	3.10	90.6	3.4	1.2	208	48.0	62.4	0.3	1765	0.79	0.499	35
1278828	Soil		17.7	43.7	10.6	159	1.5	27.4	2.4	40	1.54	21.8	2.7	0.3	26	1.0	10.2	0.2	220	0.05	0.131	15
1278829	Soil		34.3	231.0	14.9	2540	4.9	268.1	11.1	314	2.74	65.8	5.8	0.4	101	42.1	21.0	0.3	552	0.64	0.374	21
1278830	Soil		43.6	199.3	18.9	1346	5.0	158.8	8.5	255	3.02	61.6	5.9	1.2	115	24.5	30.0	0.3	614	0.60	0.345	31
1278861	Soil		26.4	28.3	53.0	81	1.2	25.4	4.7	81	2.21	38.5	1.9	0.6	44	0.3	12.1	0.3	57	0.04	0.032	2
1278862	Soil		20.8	24.4	38.3	77	0.7	20.6	5.1	113	1.86	28.6	2.2	0.2	31	0.3	8.7	0.2	51	0.02	0.041	3
1278863	Soil		10.3	19.2	21.9	71	0.4	19.6	5.9	114	1.53	17.0	1.6	0.3	15	0.2	4.5	0.2	29	0.05	0.052	3
1278864	Soil		25.6	54.5	18.4	446	0.5	88.5	9.6	216	3.37	33.5	8.1	0.6	37	2.5	34.8	0.3	88	0.38	0.154	13
1278865	Soil		9.1	33.0	12.5	175	0.4	42.0	5.2	112	2.25	22.3	2.3	0.4	22	0.7	9.5	0.2	50	0.11	0.123	11
1278866	Soil		17.2	29.6	8.0	213	0.1	44.3	9.2	221	2.56	100.5	2.5	0.3	7	0.6	39.4	0.1	80	0.03	0.102	7
1278867	Soil		44.6	60.4	15.5	685	<0.1	78.6	21.6	559	5.70	213.1	6.7	0.3	9	1.9	457.2	0.2	258	0.04	0.145	6
1278868	Soil		15.4	28.1	9.1	158	<0.1	33.2	14.1	430	2.42	66.8	1.6	0.2	6	1.0	25.7	0.1	74	0.03	0.103	5
1278869	Soil		37.0	36.7	22.6	567	0.4	94.5	9.4	163	3.14	53.7	1.6	1.0	22	4.8	27.6	0.2	263	1.16	0.056	6
1278870	Soil		12.5	18.7	10.3	246	0.3	35.4	4.6	56	1.81	23.8	1.0	0.1	4	0.4	11.2	0.1	127	0.01	0.090	3
1278871	Soil		59.8	67.9	19.5	651	1.9	166.3	10.5	363	5.61	31.7	3.3	1.1	60	5.7	14.1	0.2	116	0.59	0.122	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278812	Soil	42	0.11	841	0.002	4	1.27	0.006	0.08	<0.1	0.43	9.2	0.6	0.21	2	6.5	<0.2
1278813	Soil	37	0.11	808	0.003	4	1.10	0.007	0.11	0.1	0.53	8.4	0.7	0.23	3	7.4	<0.2
1278814	Soil	26	0.09	604	0.002	3	0.81	0.009	0.12	<0.1	0.16	7.5	0.4	0.20	2	5.2	<0.2
1278815	Soil	34	0.12	765	0.003	3	0.99	0.007	0.10	0.1	0.34	7.4	0.6	0.20	3	6.8	<0.2
1278816	Soil	29	0.11	1085	0.004	3	0.71	0.015	0.12	<0.1	0.43	3.0	1.0	0.23	3	16.9	0.3
1278817	Soil	21	0.12	265	0.009	2	0.76	0.024	0.05	<0.1	0.10	6.7	0.3	0.09	2	2.8	<0.2
1278818	Soil	22	0.15	539	0.011	3	0.78	0.022	0.08	<0.1	0.20	3.6	0.5	0.14	3	6.4	<0.2
1278819	Soil	30	0.07	1229	0.003	2	0.70	0.008	0.10	<0.1	0.48	4.4	0.9	0.21	3	11.9	0.3
1278820	Soil	32	0.09	890	0.002	3	0.87	0.005	0.12	<0.1	0.58	7.1	0.6	0.21	3	6.3	0.2
1278821	Soil	24	0.03	293	0.001	4	0.32	0.006	0.20	<0.1	0.82	2.4	0.9	0.45	3	22.3	0.3
1278822	Soil	23	0.06	498	0.003	2	0.59	0.014	0.08	0.1	0.19	0.5	0.5	0.21	3	9.5	<0.2
1278823	Soil	16	0.05	563	0.004	2	0.50	0.016	0.07	<0.1	0.15	2.3	0.3	0.18	2	4.2	<0.2
1278824	Soil	46	0.10	132	0.002	3	3.72	0.006	0.10	0.2	0.61	4.8	1.5	0.64	3	16.2	0.2
1278825	Soil	28	0.04	342	0.003	2	0.75	0.011	0.05	0.2	0.07	0.2	0.8	<0.05	4	3.5	<0.2
1278826	Soil	30	0.07	675	0.002	4	0.75	0.009	0.19	<0.1	0.90	2.5	0.9	0.43	3	17.4	0.3
1278827	Soil	180	0.14	1613	0.005	12	1.00	0.005	0.19	0.7	1.86	3.5	4.9	0.20	6	36.0	0.7
1278828	Soil	30	0.03	272	0.003	2	0.61	0.012	0.05	0.2	0.14	0.3	0.9	<0.05	3	6.6	<0.2
1278829	Soil	86	0.16	895	0.002	5	1.06	0.007	0.11	0.2	1.08	1.1	3.8	0.14	4	9.2	0.3
1278830	Soil	116	0.11	1621	0.005	8	0.73	0.004	0.13	0.3	1.66	2.8	1.8	0.07	3	26.1	0.3
1278861	Soil	5	0.02	389	<0.001	2	0.18	0.003	0.08	<0.1	0.25	1.7	0.9	0.14	<1	5.2	<0.2
1278862	Soil	7	0.02	270	0.001	1	0.27	0.006	0.05	<0.1	0.14	1.0	0.6	0.05	1	3.4	<0.2
1278863	Soil	6	0.03	129	<0.001	1	0.34	0.008	0.04	<0.1	0.09	1.2	0.3	<0.05	1	1.2	<0.2
1278864	Soil	18	0.08	647	0.002	3	0.43	0.006	0.07	<0.1	0.16	2.2	0.4	0.09	1	2.4	<0.2
1278865	Soil	11	0.03	327	0.002	2	0.33	0.011	0.06	<0.1	0.09	0.6	0.2	<0.05	1	1.7	<0.2
1278866	Soil	14	0.03	196	0.002	2	0.44	0.007	0.05	<0.1	0.01	1.0	0.2	<0.05	2	1.4	<0.2
1278867	Soil	38	0.04	328	0.002	1	0.57	0.003	0.05	0.1	0.08	2.9	0.3	<0.05	2	2.4	<0.2
1278868	Soil	18	0.05	185	0.002	1	0.61	0.007	0.06	<0.1	0.01	1.0	0.3	<0.05	3	0.8	<0.2
1278869	Soil	17	0.54	340	0.002	2	0.28	0.003	0.05	<0.1	0.30	5.6	0.6	0.12	<1	2.2	<0.2
1278870	Soil	11	0.02	70	0.003	1	0.43	0.008	0.04	<0.1	0.02	0.3	0.3	<0.05	2	1.7	<0.2
1278871	Soil	29	0.09	564	0.004	2	0.47	0.004	0.05	0.1	0.50	5.9	0.7	0.08	1	4.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278872	Soil	23.5	16.6	5.3	166	0.1	45.7	3.8	92	1.28	11.8	0.8	0.1	24	2.0	5.6	<0.1	80	0.37	0.058	3
1278873	Soil	17.9	14.4	5.5	134	0.5	32.5	3.3	46	1.10	11.7	<0.5	0.1	11	0.8	5.9	<0.1	65	0.07	0.082	3
1278874	Soil	17.2	66.2	19.3	346	1.1	95.5	9.2	194	2.58	43.9	4.3	0.5	53	2.5	23.8	0.2	86	0.93	0.112	6
1278875	Soil	4.4	12.3	10.6	65	0.8	14.3	1.8	26	0.72	7.1	1.6	<0.1	11	0.4	3.0	<0.1	33	0.06	0.094	2
1278876	Soil	8.4	40.0	45.1	187	0.8	45.5	7.6	206	2.26	20.2	4.1	0.5	52	0.6	7.6	0.2	59	0.19	0.160	8
1278877	Soil	8.8	56.8	37.8	223	0.9	71.2	15.9	480	2.83	23.2	4.8	0.6	70	0.8	8.5	0.2	67	0.24	0.150	11
1278878	Soil	6.8	123.1	34.0	112	0.5	124.4	15.0	146	4.01	27.5	3.0	2.7	80	0.3	8.7	0.3	61	0.35	0.264	14
1278879	Soil	14.8	82.3	43.7	381	0.9	112.0	17.5	315	5.04	30.0	2.5	1.2	61	1.7	11.9	0.3	64	0.29	0.159	11
1278880	Soil	12.4	73.7	73.6	230	1.5	75.9	16.0	304	3.60	30.5	4.3	0.9	266	0.8	13.5	0.4	88	0.21	0.304	9
1278881	Soil	19.4	109.6	62.1	478	1.2	136.7	16.0	246	4.95	34.1	6.8	2.8	194	1.2	14.0	0.4	157	0.58	0.449	12
1278882	Soil	24.9	25.0	911.2	126	1.7	20.4	2.6	40	2.25	57.4	1.5	0.3	498	0.6	76.6	0.5	347	0.07	0.209	12
1278883	Soil	12.5	35.4	119.6	164	0.3	44.5	7.1	188	3.35	44.7	2.3	0.4	51	0.3	13.2	0.2	84	0.08	0.106	7
1278884	Soil	6.8	25.8	154.8	107	0.5	26.8	4.7	107	2.11	53.7	4.0	0.3	41	0.2	15.4	0.3	68	0.04	0.095	8
1278885	Soil	5.0	13.0	20.3	51	1.1	14.8	2.5	32	0.80	15.0	<0.5	<0.1	9	<0.1	5.8	0.1	37	0.01	0.025	5
1278886	Soil	3.9	10.0	12.2	32	0.1	11.8	2.2	21	0.53	9.2	<0.5	<0.1	10	<0.1	3.2	0.1	29	0.01	0.026	6
1278887	Soil	11.4	42.7	18.7	199	0.7	65.8	11.2	516	2.61	22.4	3.3	1.4	42	3.3	1.8	0.2	42	0.78	0.074	4
1278888	Soil	8.5	40.1	15.3	189	0.4	45.7	9.7	171	2.53	22.1	1.5	2.4	33	1.0	2.8	0.3	58	0.20	0.066	8
1278889	Soil	2.3	18.5	9.3	81	0.2	20.0	4.4	106	1.57	11.4	1.5	1.1	31	0.7	0.9	0.2	31	0.76	0.037	3
1278890	Soil	3.1	30.5	13.8	110	0.4	32.2	8.4	129	2.28	12.6	2.2	2.3	44	1.1	1.2	0.2	43	0.75	0.052	6
1278891	Soil	5.6	38.0	14.3	134	0.5	37.3	7.0	142	2.23	15.7	3.7	2.7	46	1.4	2.2	0.3	55	0.42	0.087	8
1278892	Soil	3.9	28.0	16.3	97	0.6	23.5	5.4	112	1.72	14.6	2.3	1.9	38	1.4	1.8	0.3	59	0.43	0.066	5
1278893	Soil	8.0	22.2	15.4	91	0.4	21.3	5.8	197	2.15	17.0	1.4	1.6	33	0.6	1.6	0.2	51	0.26	0.064	5
1278894	Soil	7.2	30.3	19.8	107	0.5	27.5	3.9	75	2.30	19.4	1.4	2.1	35	0.7	1.9	0.3	60	0.23	0.073	6
1278895	Soil	9.5	49.1	16.3	316	0.6	55.7	10.8	213	2.37	18.5	0.9	2.6	46	2.1	2.5	0.3	56	0.32	0.087	7
1278896	Soil	18.6	48.1	18.5	341	0.7	74.8	7.3	189	2.05	22.3	1.2	1.6	67	3.9	4.9	0.3	114	0.47	0.120	7
1278897	Soil	13.9	27.9	13.8	239	0.6	46.6	9.7	526	1.88	16.7	1.7	0.9	30	2.9	2.3	0.2	64	0.33	0.068	4
1278898	Soil	7.4	35.8	10.2	1320	0.6	160.5	7.6	626	1.25	12.0	2.6	0.9	95	11.1	2.8	0.2	85	1.63	0.105	6
1278899	Soil	7.0	32.2	9.2	1049	0.4	196.4	8.0	232	1.65	11.6	4.8	1.2	193	3.9	1.8	0.2	45	7.61	0.080	4
1278900	Soil	22.5	37.8	8.7	368	0.4	73.4	5.9	145	1.47	20.7	2.5	1.8	108	3.6	5.5	0.1	78	3.21	0.120	8
1278921	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278872	Soil	8	0.07	206	0.003	1	0.39	0.022	0.03	<0.1	0.07	1.0	0.4	0.09	1	1.0	<0.2
1278873	Soil	9	0.03	288	0.002	1	0.34	0.013	0.04	<0.1	0.10	0.6	0.3	<0.05	2	0.9	<0.2
1278874	Soil	16	0.28	441	0.003	3	0.42	0.008	0.05	<0.1	0.32	3.0	0.4	0.13	1	3.0	<0.2
1278875	Soil	9	0.03	266	0.001	2	0.34	0.018	0.04	<0.1	0.12	0.6	0.2	0.07	1	0.7	<0.2
1278876	Soil	16	0.07	499	0.003	3	0.61	0.009	0.06	<0.1	0.15	1.1	0.2	0.06	2	2.0	<0.2
1278877	Soil	20	0.10	1157	0.003	5	0.57	0.006	0.10	<0.1	0.17	1.9	0.3	0.05	2	2.4	<0.2
1278878	Soil	24	0.04	610	0.002	5	0.44	0.001	0.09	<0.1	0.05	3.5	0.2	<0.05	1	3.5	<0.2
1278879	Soil	19	0.07	770	0.002	3	0.46	0.002	0.05	<0.1	0.17	3.2	0.2	<0.05	1	5.3	<0.2
1278880	Soil	16	0.04	1004	0.002	3	0.53	0.006	0.08	<0.1	0.26	2.9	0.4	<0.05	2	2.6	0.2
1278881	Soil	28	0.04	1758	0.003	10	0.68	0.002	0.16	<0.1	0.25	4.3	0.3	<0.05	2	3.0	0.3
1278882	Soil	23	0.02	716	0.009	3	0.44	0.008	0.06	0.2	0.06	0.3	0.7	0.08	3	3.3	<0.2
1278883	Soil	20	0.05	180	0.004	2	0.66	0.002	0.04	0.1	0.07	1.4	0.3	<0.05	3	1.5	<0.2
1278884	Soil	17	0.08	152	0.007	3	0.43	0.004	0.05	0.2	0.04	0.8	0.3	<0.05	3	1.8	<0.2
1278885	Soil	6	0.01	79	0.005	1	0.18	0.012	0.03	<0.1	0.02	0.2	0.1	<0.05	2	0.8	<0.2
1278886	Soil	7	0.01	56	0.004	<1	0.19	0.006	0.02	<0.1	<0.01	0.2	<0.1	<0.05	2	1.3	<0.2
1278887	Soil	19	0.15	733	<0.001	2	0.92	0.007	0.06	<0.1	0.34	3.3	0.3	0.07	3	3.6	<0.2
1278888	Soil	19	0.17	880	0.002	1	0.86	0.003	0.06	<0.1	0.18	2.8	0.1	<0.05	3	1.0	<0.2
1278889	Soil	12	0.15	316	0.002	1	0.76	0.011	0.05	<0.1	0.05	1.7	<0.1	<0.05	2	0.9	<0.2
1278890	Soil	18	0.24	547	0.002	2	0.94	0.006	0.07	0.1	0.15	3.0	0.1	<0.05	3	2.1	<0.2
1278891	Soil	18	0.19	995	0.002	1	0.96	0.005	0.06	<0.1	0.28	3.1	0.2	<0.05	3	2.4	<0.2
1278892	Soil	16	0.14	653	0.001	1	0.87	0.008	0.06	<0.1	0.27	3.0	0.2	<0.05	3	2.3	<0.2
1278893	Soil	15	0.15	508	0.001	2	0.80	0.008	0.06	<0.1	0.24	2.3	0.2	<0.05	3	1.8	<0.2
1278894	Soil	18	0.15	670	0.001	2	0.97	0.006	0.08	<0.1	0.29	2.9	0.3	<0.05	3	3.2	<0.2
1278895	Soil	19	0.17	1013	0.001	2	0.90	0.005	0.07	<0.1	0.27	3.6	0.3	<0.05	3	3.9	<0.2
1278896	Soil	18	0.14	1054	0.001	3	0.81	0.009	0.07	<0.1	0.43	2.8	0.4	<0.05	2	4.3	<0.2
1278897	Soil	13	0.10	536	0.003	2	0.80	0.015	0.06	<0.1	0.24	2.0	0.3	<0.05	2	3.9	<0.2
1278898	Soil	15	0.21	875	0.002	5	0.67	0.009	0.07	0.1	0.51	2.3	0.9	0.08	2	2.3	<0.2
1278899	Soil	14	0.21	194	0.001	4	0.51	0.004	0.04	<0.1	0.28	1.9	5.2	0.26	1	1.2	<0.2
1278900	Soil	13	1.45	568	0.002	5	0.23	0.005	0.05	<0.1	0.27	2.5	0.3	0.06	<1	1.5	<0.2
1278921	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278922	Soil		68.0	382.3	27.9	2910	13.8	329.8	17.6	528	4.43	78.5	4.7	3.3	223	68.9	39.2	0.4	1097	1.14	0.704	29
1278923	Soil		17.6	144.8	36.5	622	9.3	153.2	5.1	164	5.55	44.9	6.2	5.6	171	4.9	9.2	0.6	128	1.64	0.171	10
1278924	Soil		19.3	108.7	15.1	699	3.5	119.2	5.9	126	2.19	30.5	1.7	0.3	56	9.9	10.1	0.2	273	0.26	0.212	19
1278925	Soil		38.7	225.6	29.3	882	0.8	112.4	8.5	148	5.14	28.1	8.7	0.4	20	1.0	8.2	0.3	244	0.05	0.176	32
1278926	Soil		5.6	303.4	46.0	652	1.2	183.2	42.8	963	14.08	22.3	18.7	8.6	62	3.6	3.5	0.7	43	0.20	0.125	38
1278927	Soil		70.6	120.3	12.0	1108	1.5	224.4	7.2	202	1.93	56.3	2.3	5.3	105	16.4	31.9	0.2	522	4.84	0.079	28
1278928	Soil		48.1	137.5	16.3	1909	2.1	274.3	27.7	938	3.98	27.5	4.7	5.2	124	11.9	14.2	0.3	184	3.00	0.085	20
1278929	Soil		18.9	146.7	18.9	1293	3.2	214.7	8.6	207	3.33	78.2	3.9	1.8	53	5.5	15.2	0.3	85	1.90	0.134	28
1278930	Soil		5.2	43.9	8.7	83	0.2	32.1	6.5	115	2.08	13.9	0.7	<0.1	8	0.3	2.7	0.2	31	0.04	0.052	3
1279931	Soil		4.3	60.5	16.6	213	1.1	48.4	8.3	160	2.49	29.5	10.4	2.2	63	1.4	3.8	0.3	64	0.66	0.089	8
1279932	Soil		4.7	61.3	13.4	217	0.7	47.8	8.2	272	2.80	27.1	6.9	2.5	59	1.4	3.8	0.2	53	0.40	0.093	7
1279933	Soil		5.5	56.6	14.4	239	0.6	54.6	8.1	155	2.58	29.6	7.9	2.6	57	1.6	5.0	0.2	75	0.33	0.109	8
1279934	Soil		5.5	63.3	17.3	186	1.6	40.1	4.3	45	1.09	20.7	10.8	1.1	74	2.1	3.7	0.3	72	0.47	0.116	7
1279935	Soil		6.4	34.4	9.4	114	0.5	21.0	3.8	85	1.24	15.9	6.9	0.9	50	0.5	2.7	0.2	54	0.48	0.066	8
1279936	Soil		13.0	46.3	18.1	210	1.1	32.6	10.6	397	2.84	34.2	7.9	1.7	76	1.5	5.0	0.3	104	0.38	0.116	8
1279937	Soil		7.3	71.4	15.4	340	1.3	75.2	14.9	3012	2.56	27.0	11.0	1.8	65	5.9	4.1	0.2	86	0.31	0.122	8
1279938	Soil		8.1	81.7	13.8	362	1.0	67.9	8.2	296	3.05	32.6	7.2	2.5	67	5.0	4.7	0.2	103	0.33	0.125	8
1279939	Soil		3.8	38.7	8.1	209	0.9	48.5	3.6	202	1.45	15.0	5.3	1.0	177	1.3	2.0	0.1	57	0.65	0.063	3
1279940	Soil		3.6	58.5	11.3	331	1.3	74.8	6.8	195	2.03	18.6	7.9	1.7	271	2.5	2.9	0.2	78	0.87	0.092	5
1279941	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279942	Soil		5.5	72.9	34.2	300	0.5	79.3	14.1	195	3.98	33.4	14.8	3.4	23	1.0	3.6	0.5	74	0.03	0.081	5
1279943	Soil		3.8	18.7	11.1	86	0.7	14.8	2.9	60	1.76	12.3	1.9	1.2	13	0.5	1.8	0.2	59	0.01	0.068	8
1279944	Soil		5.9	30.5	15.8	236	0.5	37.5	6.0	136	3.33	31.0	4.6	2.0	19	0.7	3.7	0.2	81	0.02	0.064	7
1279945	Soil		3.4	18.4	10.2	85	0.4	12.6	2.5	59	1.35	10.2	2.4	1.2	11	0.7	1.5	0.2	53	0.02	0.043	7
1279946	Soil		4.3	21.3	13.1	128	0.3	19.9	3.6	87	2.40	19.7	2.3	1.5	13	0.4	2.3	0.2	65	0.01	0.069	6
1279947	Soil		4.7	21.3	12.8	133	0.8	21.9	3.9	125	3.18	22.3	1.5	1.8	13	0.3	2.6	0.3	73	0.02	0.068	6
1279948	Soil		4.2	25.3	12.6	118	0.4	26.1	4.7	136	2.39	19.2	7.8	1.6	15	0.4	2.2	0.2	55	0.03	0.055	7
1279949	Soil		3.5	40.7	10.6	139	0.3	16.3	4.0	221	2.52	9.7	2.0	1.4	10	0.7	1.7	0.2	67	0.03	0.039	6
1279950	Soil		5.0	52.4	10.0	250	0.5	50.1	6.3	129	2.09	17.6	6.9	1.4	44	1.4	4.3	0.2	70	0.19	0.088	6
1279951	Soil		4.7	19.6	10.3	92	0.3	15.4	3.1	63	1.88	15.0	1.3	1.2	11	0.3	2.3	0.2	70	0.01	0.035	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278922	Soil	196	0.13	763	0.010	9	0.82	0.008	0.16	0.6	0.43	5.2	4.2	0.31	5	52.3	0.5
1278923	Soil	70	0.78	103	0.006	6	0.34	0.009	0.43	0.2	0.67	4.5	1.6	1.26	2	13.1	0.3
1278924	Soil	67	0.07	433	0.005	4	0.48	0.009	0.09	0.3	0.25	0.9	1.0	0.15	3	12.5	<0.2
1278925	Soil	30	0.04	181	0.003	3	0.42	0.003	0.08	0.2	0.12	1.6	0.4	0.07	3	4.6	<0.2
1278926	Soil	18	0.14	687	0.005	7	0.44	0.003	0.12	<0.1	0.36	13.8	0.5	0.13	1	5.6	0.2
1278927	Soil	27	2.85	743	0.003	8	0.35	0.007	0.07	0.2	1.35	4.0	1.6	<0.05	1	6.5	<0.2
1278928	Soil	38	1.67	1932	0.003	7	0.35	0.005	0.09	0.2	0.55	6.9	0.5	0.08	1	8.2	<0.2
1278929	Soil	36	0.98	414	0.004	6	0.30	0.004	0.09	<0.1	1.18	3.3	0.3	<0.05	<1	10.4	<0.2
1278930	Soil	7	0.04	114	0.003	2	0.27	0.015	0.05	0.1	0.03	0.5	0.1	<0.05	1	1.0	<0.2
1279931	Soil	27	0.23	2047	0.002	4	1.11	0.005	0.09	<0.1	1.06	3.6	0.2	<0.05	3	1.7	<0.2
1279932	Soil	29	0.28	2844	0.002	3	1.07	0.004	0.08	<0.1	0.69	2.9	0.2	0.05	3	1.9	<0.2
1279933	Soil	29	0.25	2480	0.002	5	1.05	0.004	0.08	<0.1	0.70	2.7	0.2	<0.05	3	1.5	<0.2
1279934	Soil	19	0.09	1573	0.002	3	0.74	0.005	0.06	0.2	0.98	2.7	0.4	0.09	2	3.1	<0.2
1279935	Soil	12	0.05	932	0.004	6	0.48	0.009	0.05	0.1	0.34	1.6	0.2	0.06	2	0.9	<0.2
1279936	Soil	21	0.11	1630	0.002	3	0.79	0.003	0.06	0.1	0.77	2.7	0.3	<0.05	2	2.1	<0.2
1279937	Soil	26	0.18	2098	0.002	3	1.17	0.005	0.07	<0.1	1.41	3.6	0.3	<0.05	3	2.3	<0.2
1279938	Soil	29	0.21	2039	0.002	5	1.05	0.003	0.08	0.1	0.99	3.5	0.3	0.05	3	3.1	<0.2
1279939	Soil	16	0.16	1165	0.002	2	0.79	0.012	0.05	<0.1	0.60	1.6	0.2	0.06	2	1.2	<0.2
1279940	Soil	22	0.19	2129	0.002	4	1.06	0.008	0.08	0.1	0.79	2.9	0.3	0.10	2	2.8	<0.2
1279941	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1279942	Soil	34	0.35	410	0.002	5	1.60	0.003	0.08	<0.1	0.19	2.3	0.3	<0.05	3	1.6	<0.2
1279943	Soil	12	0.04	302	0.005	3	0.76	0.005	0.05	0.1	0.08	1.2	0.2	<0.05	3	0.7	<0.2
1279944	Soil	24	0.17	287	0.005	2	1.14	0.003	0.06	0.1	0.07	1.9	0.2	<0.05	3	1.3	<0.2
1279945	Soil	10	0.04	231	0.004	2	0.57	0.006	0.05	0.1	0.03	0.9	0.1	<0.05	3	<0.5	<0.2
1279946	Soil	13	0.07	205	0.003	<1	0.80	0.005	0.04	<0.1	0.04	1.2	0.2	<0.05	3	1.4	<0.2
1279947	Soil	21	0.12	221	0.003	1	1.10	0.003	0.05	0.1	0.09	1.4	0.2	<0.05	4	0.5	<0.2
1279948	Soil	21	0.15	220	0.004	2	0.92	0.003	0.04	<0.1	0.11	1.1	0.2	<0.05	3	1.3	<0.2
1279949	Soil	17	0.08	337	0.005	2	0.98	0.005	0.04	<0.1	0.03	1.4	0.1	<0.05	5	0.6	<0.2
1279950	Soil	18	0.10	2038	0.003	3	0.79	0.005	0.06	0.1	0.39	2.0	0.2	<0.05	2	1.3	<0.2
1279951	Soil	10	0.03	198	0.007	2	0.58	0.005	0.04	<0.1	0.05	1.0	0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279952	Soil	4.9	40.0	11.6	175	0.3	29.6	4.5	112	2.27	17.3	2.7	1.7	16	0.4	2.9	0.2	64	0.02	0.033	7
1279953	Soil	2.2	38.7	10.1	160	1.0	36.9	4.4	152	1.44	11.9	9.3	1.4	102	1.4	1.7	0.2	46	0.49	0.081	5
1279954	Soil	4.6	15.3	12.5	80	1.2	18.1	3.0	85	1.98	16.1	3.0	0.9	18	0.4	3.6	0.2	60	0.04	0.059	7
1279955	Soil	16.2	49.8	23.6	153	2.1	36.9	5.5	157	5.22	30.9	3.4	2.6	29	0.4	7.8	0.4	106	0.03	0.157	7
1279956	Soil	4.2	17.3	11.9	61	0.6	12.2	2.6	46	1.54	14.2	1.8	0.3	11	0.2	1.6	0.3	69	0.02	0.040	9
1279957	Soil	4.5	37.5	14.5	134	0.6	23.6	4.7	108	2.55	17.4	6.2	1.0	14	0.3	1.6	0.3	68	0.04	0.078	10
1279958	Soil	2.9	17.3	13.1	68	2.0	13.0	2.1	39	1.68	13.8	3.8	0.7	15	0.2	1.3	0.3	50	0.02	0.037	6
1279959	Soil	3.6	17.9	8.8	65	0.6	13.8	2.6	35	1.30	9.7	0.7	0.2	7	0.3	1.2	0.2	64	0.01	0.037	9
1279960	Soil	3.4	39.6	10.6	120	0.4	27.2	4.5	76	2.03	10.1	3.5	0.3	10	0.5	1.0	0.2	45	0.02	0.066	3
1280131	Soil	5.3	60.5	37.7	129	1.8	26.5	11.7	306	2.34	13.3	8.0	1.1	65	1.6	7.1	0.3	81	0.03	0.054	3
1280132	Soil	138.7	67.9	13.1	932	1.8	334.5	6.2	85	2.07	67.7	4.5	2.6	113	10.2	24.8	0.2	408	3.43	0.123	10
1280133	Soil	18.0	37.6	5.9	104	0.2	66.7	2.9	116	0.84	10.6	3.3	0.4	62	1.1	1.7	<0.1	27	1.85	0.055	4
1280134	Soil	21.7	30.8	9.0	165	<0.1	51.4	5.7	98	1.41	16.2	4.5	1.3	18	0.6	2.8	0.2	47	0.30	0.037	6
1280135	Soil	8.4	14.2	3.8	61	0.1	19.4	2.4	51	0.62	6.4	2.4	0.3	25	0.2	1.1	<0.1	20	0.56	0.040	3
1280136	Soil	37.0	65.7	14.2	194	0.5	128.2	8.8	137	3.76	31.3	2.2	2.4	178	1.4	3.3	0.1	70	0.67	0.183	13
1280137	Soil	29.3	79.4	18.7	394	0.8	95.4	11.1	230	2.52	33.0	5.9	1.2	64	2.3	5.7	0.3	84	0.77	0.107	7
1280138	Soil	19.5	72.5	21.3	346	0.5	72.7	13.3	309	2.90	33.2	6.4	1.1	43	1.6	4.4	0.3	58	0.54	0.083	5
1280139	Soil	1.9	29.7	20.1	119	0.4	28.2	11.1	264	2.70	16.2	4.1	2.0	21	0.1	0.7	0.3	37	0.04	0.078	4
1280140	Soil	1.9	29.2	23.2	116	2.0	17.6	6.3	142	3.44	17.9	4.0	1.7	17	0.1	1.0	0.3	42	0.03	0.081	3
1280141	Soil	1.5	15.1	12.7	59	0.3	11.6	4.1	165	1.84	10.7	1.2	0.4	8	0.2	0.6	0.2	30	0.02	0.073	3
1280142	Soil	0.8	7.6	6.0	29	0.2	5.8	2.1	48	1.04	4.6	<0.5	0.1	5	<0.1	0.4	0.1	16	0.01	0.033	2
1280143	Soil	1.6	22.2	19.1	92	0.3	21.7	8.8	180	2.45	13.6	2.5	1.2	22	0.3	0.8	0.2	40	0.01	0.074	5
1280144	Soil	1.7	18.4	14.5	78	0.6	13.7	5.3	104	2.44	13.6	3.1	0.8	14	0.1	0.8	0.2	47	0.03	0.081	4
1280145	Soil	1.2	14.5	12.0	47	0.6	11.3	3.5	61	1.40	6.1	3.5	0.6	17	0.2	0.6	0.2	25	0.03	0.078	2
1280146	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280147	Soil	2.5	23.7	18.1	88	0.5	20.1	5.8	158	2.58	15.7	2.7	1.2	34	0.2	1.1	0.3	40	0.04	0.084	5
1280148	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280149	Soil	2.3	13.7	13.2	57	0.5	11.9	3.8	149	1.73	8.0	3.9	0.6	35	0.2	0.8	0.2	21	0.03	0.072	3
1280150	Soil	4.6	15.8	21.1	93	0.6	20.6	9.2	435	2.22	11.8	2.9	1.1	47	0.3	1.4	0.2	26	0.06	0.072	4
1280151	Soil	3.7	18.3	15.6	107	0.4	22.9	15.4	538	2.19	13.3	<0.5	1.7	33	0.4	1.7	0.2	35	0.08	0.070	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279952	Soil	16	0.11	461	0.003	2	0.79	0.003	0.06	<0.1	0.08	1.5	0.2	<0.05	3	0.7	<0.2
1279953	Soil	15	0.11	2095	0.002	3	0.73	0.010	0.07	<0.1	0.51	2.3	0.2	0.06	2	1.7	<0.2
1279954	Soil	12	0.08	3004	0.008	3	0.73	0.003	0.07	0.2	0.07	1.1	0.5	0.07	3	1.3	<0.2
1279955	Soil	32	0.14	790	0.002	3	1.36	0.003	0.10	0.2	0.15	2.3	1.3	0.09	4	4.2	<0.2
1279956	Soil	9	0.03	712	0.009	1	0.60	0.002	0.04	0.2	0.03	0.5	0.2	<0.05	5	0.5	<0.2
1279957	Soil	22	0.18	291	0.007	2	1.22	0.004	0.06	0.2	0.04	1.3	0.2	<0.05	5	1.1	<0.2
1279958	Soil	10	0.03	226	0.004	2	0.50	0.004	0.05	<0.1	0.03	0.9	0.1	<0.05	3	1.2	<0.2
1279959	Soil	10	0.03	150	0.004	1	0.56	0.003	0.04	0.2	<0.01	0.4	0.1	<0.05	3	0.7	<0.2
1279960	Soil	15	0.04	201	0.002	2	0.64	0.006	0.05	<0.1	0.03	1.0	<0.1	<0.05	3	1.4	<0.2
1280131	Soil	10	0.01	277	0.001	2	0.33	0.001	0.09	<0.1	0.60	3.9	0.9	0.14	<1	6.4	<0.2
1280132	Soil	24	1.41	700	0.005	7	0.36	0.004	0.12	0.2	1.07	3.3	2.4	<0.05	1	6.3	<0.2
1280133	Soil	8	0.45	539	0.006	6	0.31	0.018	0.03	<0.1	0.18	1.4	0.5	0.07	<1	1.2	<0.2
1280134	Soil	11	0.05	298	0.003	2	0.32	0.003	0.05	<0.1	0.08	1.7	0.3	<0.05	1	1.3	<0.2
1280135	Soil	5	0.06	392	0.005	1	0.26	0.020	0.04	<0.1	0.01	0.7	0.1	0.05	<1	0.9	<0.2
1280136	Soil	27	0.09	444	0.003	5	0.73	0.002	0.08	0.2	0.46	5.5	1.0	<0.05	1	2.4	<0.2
1280137	Soil	15	0.08	670	0.002	4	0.45	0.004	0.07	<0.1	0.24	3.0	0.5	0.07	1	2.5	<0.2
1280138	Soil	13	0.07	436	0.001	3	0.38	0.004	0.08	<0.1	0.16	3.0	0.3	0.08	1	2.3	<0.2
1280139	Soil	18	0.10	535	0.006	2	0.88	0.004	0.10	<0.1	0.05	3.5	0.1	0.06	3	1.8	<0.2
1280140	Soil	21	0.09	429	<0.001	<1	1.01	0.003	0.07	<0.1	0.16	3.2	<0.1	<0.05	3	1.3	<0.2
1280141	Soil	11	0.04	102	0.002	1	0.78	0.009	0.04	<0.1	0.04	0.8	<0.1	<0.05	3	<0.5	<0.2
1280142	Soil	7	0.04	45	0.003	1	0.42	0.016	0.03	<0.1	0.04	0.5	<0.1	<0.05	1	0.8	<0.2
1280143	Soil	19	0.12	249	0.002	<1	1.11	0.006	0.06	<0.1	0.07	2.0	<0.1	<0.05	4	1.0	<0.2
1280144	Soil	13	0.06	308	0.001	<1	0.83	0.006	0.04	<0.1	0.06	1.4	<0.1	<0.05	4	0.6	<0.2
1280145	Soil	11	0.06	481	0.004	2	0.69	0.012	0.04	<0.1	0.12	1.6	<0.1	0.06	2	<0.5	<0.2
1280146	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280147	Soil	17	0.13	684	0.002	2	0.91	0.006	0.07	<0.1	0.10	2.1	0.1	<0.05	3	2.3	<0.2
1280148	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280149	Soil	10	0.05	1816	<0.001	<1	0.62	0.011	0.05	<0.1	0.12	1.3	0.2	0.05	2	1.4	<0.2
1280150	Soil	14	0.08	2336	0.002	3	0.71	0.006	0.08	<0.1	0.14	2.4	0.2	0.06	2	0.6	<0.2
1280151	Soil	15	0.14	1458	0.003	2	0.76	0.005	0.07	0.1	0.17	2.5	0.2	<0.05	2	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280152	Soil	5.8	30.8	15.5	195	0.4	38.1	13.4	378	2.62	16.4	1.0	2.1	40	0.7	2.4	0.2	45	0.15	0.096	7
1280153	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280154	Soil	1.2	10.8	6.3	51	0.5	14.6	3.2	62	0.80	4.4	1.1	0.4	33	0.2	0.6	<0.1	18	0.23	0.056	3
1280155	Soil	2.9	12.4	11.9	81	0.4	13.5	3.9	108	2.06	11.3	0.6	0.7	11	0.6	0.9	0.2	44	0.03	0.068	5
1280156	Soil	4.0	16.1	14.2	103	0.3	20.3	5.6	138	2.59	15.6	<0.5	2.3	13	0.4	1.5	0.2	50	0.03	0.058	8
1280157	Soil	0.6	4.6	4.4	22	0.3	4.8	1.5	41	0.59	2.8	<0.5	<0.1	5	0.1	0.2	<0.1	12	0.02	0.024	2
1280158	Soil	1.2	10.2	7.7	35	0.3	6.5	2.1	51	0.93	5.1	<0.5	0.2	7	0.2	0.4	0.1	17	0.02	0.057	3
1280159	Soil	2.6	15.8	13.1	78	<0.1	15.8	4.8	101	2.61	14.7	<0.5	2.1	12	0.2	1.1	0.2	44	0.03	0.045	6
1280160	Soil	1.9	23.0	20.6	92	0.3	17.9	6.0	202	4.20	20.9	0.8	1.7	12	<0.1	1.0	0.3	52	0.02	0.123	4
1280161	Soil	2.1	11.9	9.5	59	0.3	12.6	4.0	84	1.36	11.6	1.4	0.1	9	0.3	0.9	0.2	30	0.03	0.057	6
1280162	Soil	2.5	13.5	13.6	71	1.5	15.7	4.7	102	1.71	14.1	3.3	0.3	14	0.4	1.3	0.2	35	0.03	0.076	6
1280163	Soil	2.6	12.0	13.8	57	0.9	11.2	2.6	51	1.25	9.5	2.0	0.2	19	0.2	0.9	0.2	23	0.03	0.091	4
1280164	Soil	10.9	36.4	14.9	73	1.1	19.7	5.2	201	2.01	24.1	4.2	1.9	29	0.3	5.8	0.2	76	0.12	0.117	14
1280165	Soil	39.6	38.5	28.3	82	1.2	15.1	2.6	114	3.03	65.3	4.2	3.1	39	0.1	16.9	0.3	164	0.05	0.165	23
1280166	Soil	18.7	27.5	17.7	52	1.5	9.7	2.0	122	1.58	31.7	3.8	0.3	24	0.2	9.0	0.2	94	0.04	0.093	13
1280167	Soil	22.8	29.6	25.1	81	1.1	16.2	2.9	152	2.46	40.5	4.4	1.1	25	0.2	11.0	0.3	115	0.05	0.107	25

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

CERTIFICATE OF ANALYSIS WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280152	Soil	15	0.17	976	0.002	<1	0.75	0.003	0.06	0.1	0.14	2.8	0.2	<0.05	2	1.6	<0.2
1280153	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280154	Soil	9	0.09	757	0.004	2	0.58	0.020	0.05	<0.1	0.11	1.3	0.1	<0.05	2	<0.5	<0.2
1280155	Soil	15	0.12	267	0.003	1	0.85	0.008	0.06	0.1	0.03	1.1	0.1	<0.05	4	<0.5	<0.2
1280156	Soil	18	0.17	266	0.004	1	0.99	0.004	0.06	<0.1	0.04	1.9	0.2	<0.05	4	0.5	<0.2
1280157	Soil	5	0.04	74	0.003	<1	0.31	0.016	0.03	<0.1	0.04	0.3	<0.1	<0.05	2	<0.5	<0.2
1280158	Soil	6	0.03	154	0.002	<1	0.49	0.011	0.04	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2
1280159	Soil	15	0.12	196	0.003	<1	0.87	0.004	0.07	<0.1	0.02	1.6	0.1	<0.05	4	0.6	<0.2
1280160	Soil	26	0.16	128	0.003	1	1.19	0.005	0.05	<0.1	0.06	2.3	0.1	<0.05	5	1.2	<0.2
1280161	Soil	9	0.07	140	0.003	1	0.50	0.006	0.04	<0.1	0.03	0.4	0.1	<0.05	2	<0.5	<0.2
1280162	Soil	12	0.11	183	0.004	2	0.63	0.007	0.05	0.1	0.09	0.5	0.2	<0.05	2	<0.5	<0.2
1280163	Soil	7	0.05	477	0.003	2	0.39	0.010	0.05	<0.1	0.10	0.3	0.3	<0.05	2	1.0	<0.2
1280164	Soil	20	0.22	262	0.018	2	0.77	0.009	0.08	0.2	0.19	2.0	0.7	0.09	4	4.7	<0.2
1280165	Soil	24	0.14	463	0.016	2	0.71	0.006	0.13	0.2	0.07	3.5	1.7	0.16	4	11.6	0.4
1280166	Soil	15	0.07	340	0.008	1	0.69	0.013	0.08	0.2	0.23	0.8	0.7	0.11	4	8.0	0.3
1280167	Soil	19	0.11	362	0.011	2	0.64	0.007	0.10	0.2	0.11	1.3	0.9	0.11	4	9.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1094952	Soil	2.4	21.6	17.9	125	<0.1	33.3	15.2	246	3.13	15.6	2.3	1.4	12	0.1	1.0	0.3	30	0.02	0.047	4
REP 1094952	QC	2.1	21.4	18.3	122	0.1	32.7	14.4	234	2.99	15.3	2.3	1.4	11	<0.1	0.9	0.3	29	0.02	0.043	4
1094992	Soil	175.4	103.4	18.8	991	1.0	262.6	12.5	217	3.01	92.6	2.0	0.4	15	8.4	43.9	0.2	681	0.13	0.151	20
REP 1094992	QC	172.3	103.9	18.3	995	1.0	257.6	12.2	219	2.96	90.1	2.3	0.4	15	8.8	43.8	0.2	668	0.12	0.144	20
1278423	Soil	2.7	28.2	20.3	117	0.2	38.8	20.5	466	2.71	28.1	<0.5	0.7	34	0.4	1.2	0.3	29	0.05	0.081	4
REP 1278423	QC	2.7	27.2	18.0	120	0.2	41.8	21.1	446	2.72	28.1	<0.5	0.7	34	0.4	1.1	0.3	29	0.05	0.081	4
1278429	Soil	5.1	67.0	25.9	176	0.5	42.9	17.1	678	3.37	50.4	3.5	0.4	27	1.0	3.0	0.4	66	0.09	0.099	7
REP 1278429	QC	5.1	67.9	25.4	186	0.6	42.7	17.1	689	3.42	50.1	3.8	0.4	28	0.8	3.0	0.4	64	0.09	0.098	8
1278455	Soil	9.7	55.8	12.9	291	0.7	77.6	8.8	227	2.22	18.5	2.5	3.3	64	2.8	4.5	0.2	61	1.44	0.139	12
REP 1278455	QC	9.7	55.7	13.4	280	0.6	77.0	8.9	227	2.19	18.1	2.7	3.5	65	2.7	4.4	0.2	61	1.45	0.145	12
1278464	Soil	15.9	38.9	12.8	261	0.5	55.1	8.0	155	2.24	23.4	2.5	3.0	50	1.6	3.6	0.2	76	0.50	0.114	10
REP 1278464	QC	15.4	38.5	12.4	247	0.5	52.2	7.8	152	2.25	23.1	3.5	2.9	49	1.6	3.6	0.2	78	0.48	0.113	10
1278495	Soil	76.1	64.8	21.2	432	0.7	164.0	14.8	520	3.25	34.5	<0.5	3.9	124	3.2	16.7	0.2	218	4.18	0.074	3
REP 1278495	QC	71.8	64.1	19.2	411	0.8	156.2	14.0	493	3.14	34.1	1.2	3.6	124	3.0	15.6	0.2	201	4.22	0.078	3
1278737	Soil	2.2	16.2	11.6	66	0.5	15.4	4.9	78	2.49	13.5	<0.5	0.9	11	0.1	0.9	0.2	38	0.01	0.042	3
REP 1278737	QC	2.0	16.2	11.2	65	0.5	16.1	5.1	80	2.46	13.0	<0.5	0.9	11	0.1	0.9	0.2	38	0.01	0.042	3
1278754	Soil	18.5	40.6	8.5	186	0.3	90.6	5.0	121	1.37	11.7	0.6	0.8	57	2.0	2.2	0.1	49	1.21	0.078	7
REP 1278754	QC	18.0	39.2	8.2	188	0.3	89.2	5.1	123	1.39	11.4	0.7	0.8	58	2.2	2.2	0.1	49	1.26	0.075	7
1278768	Soil	13.6	61.3	24.7	217	0.7	50.0	12.5	300	2.61	34.2	4.1	2.2	45	1.4	5.1	0.3	90	0.21	0.156	12
REP 1278768	QC	13.3	58.7	24.4	214	0.7	47.4	12.0	292	2.49	34.4	3.1	2.0	45	1.2	4.9	0.2	91	0.20	0.157	12
1278814	Soil	6.6	127.4	24.9	107	2.7	101.1	25.6	931	5.98	53.3	10.0	1.6	108	0.8	8.1	0.4	97	0.11	0.172	3
REP 1278814	QC	6.4	129.6	25.3	108	2.7	101.1	26.0	921	5.99	53.7	9.9	1.7	110	0.8	7.9	0.4	96	0.12	0.171	3
1278862	Soil	20.8	24.4	38.3	77	0.7	20.6	5.1	113	1.86	28.6	2.2	0.2	31	0.3	8.7	0.2	51	0.02	0.041	3
REP 1278862	QC	20.2	24.5	39.2	78	0.7	20.2	4.9	111	1.88	28.6	2.1	0.2	31	0.3	8.6	0.2	51	0.02	0.041	3
1278880	Soil	12.4	73.7	73.6	230	1.5	75.9	16.0	304	3.60	30.5	4.3	0.9	266	0.8	13.5	0.4	88	0.21	0.304	9
REP 1278880	QC	12.1	70.8	72.9	231	1.5	76.4	15.8	293	3.61	29.1	5.3	0.9	253	0.8	13.4	0.4	88	0.21	0.302	9
1279935	Soil	6.4	34.4	9.4	114	0.5	21.0	3.8	85	1.24	15.9	6.9	0.9	50	0.5	2.7	0.2	54	0.48	0.066	8
REP 1279935	QC	6.2	33.6	8.9	110	0.5	20.6	3.7	85	1.23	14.8	6.6	0.9	49	0.6	2.5	0.2	52	0.49	0.063	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11001217.3

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1094952	Soil	16	0.19	91	0.002	4	0.75	0.003	0.06	<0.1	0.02	2.2	0.1	<0.05	3	<0.5	<0.2
REP 1094952	QC	15	0.19	89	0.002	3	0.72	0.002	0.06	<0.1	0.02	2.2	0.1	<0.05	3	<0.5	<0.2
1094992	Soil	33	0.04	257	0.003	2	0.46	0.002	0.07	0.3	0.29	1.0	2.1	<0.05	2	16.6	0.3
REP 1094992	QC	32	0.04	257	0.005	2	0.47	0.002	0.07	0.3	0.28	1.1	2.1	<0.05	2	16.5	0.4
1278423	Soil	9	0.04	391	0.002	2	0.34	0.003	0.09	<0.1	0.05	2.9	0.3	0.11	1	1.4	<0.2
REP 1278423	QC	9	0.05	389	<0.001	1	0.35	0.003	0.09	<0.1	0.03	3.0	0.2	0.05	1	1.5	<0.2
1278429	Soil	19	0.11	394	0.008	1	0.91	0.008	0.07	<0.1	0.06	2.9	0.3	<0.05	3	2.0	<0.2
REP 1278429	QC	19	0.11	393	0.005	1	0.91	0.008	0.06	<0.1	0.07	3.0	0.3	<0.05	3	2.4	<0.2
1278455	Soil	12	0.57	725	0.005	4	0.46	0.004	0.07	<0.1	0.28	3.9	0.2	0.05	1	2.0	<0.2
REP 1278455	QC	12	0.59	739	0.003	4	0.47	0.005	0.07	<0.1	0.28	3.9	0.2	<0.05	1	2.1	<0.2
1278464	Soil	18	0.19	1127	0.003	3	0.77	0.005	0.07	0.1	0.34	3.1	0.2	<0.05	2	1.9	<0.2
REP 1278464	QC	18	0.18	1115	0.003	2	0.76	0.006	0.07	0.1	0.29	3.0	0.2	<0.05	2	1.5	<0.2
1278495	Soil	14	1.95	453	0.003	3	0.22	0.008	0.04	<0.1	0.25	4.5	0.5	<0.05	<1	3.3	<0.2
REP 1278495	QC	13	1.94	433	0.004	2	0.21	0.008	0.04	<0.1	0.20	4.4	0.5	<0.05	<1	2.9	<0.2
1278737	Soil	14	0.07	94	0.002	<1	0.68	0.007	0.04	<0.1	0.04	1.4	<0.1	<0.05	3	1.4	<0.2
REP 1278737	QC	14	0.08	97	0.002	1	0.70	0.008	0.04	<0.1	0.04	1.5	<0.1	<0.05	3	<0.5	<0.2
1278754	Soil	17	0.14	318	0.004	3	0.60	0.012	0.04	0.1	0.21	2.0	0.6	0.07	1	2.1	<0.2
REP 1278754	QC	17	0.14	312	0.004	3	0.59	0.011	0.04	<0.1	0.22	2.1	0.6	0.06	1	1.6	<0.2
1278768	Soil	16	0.14	618	0.004	3	0.70	0.004	0.06	0.1	0.26	2.1	0.3	<0.05	2	2.2	<0.2
REP 1278768	QC	17	0.14	613	0.004	2	0.73	0.004	0.06	0.2	0.24	2.1	0.3	0.06	2	2.1	<0.2
1278814	Soil	26	0.09	604	0.002	3	0.81	0.009	0.12	<0.1	0.16	7.5	0.4	0.20	2	5.2	<0.2
REP 1278814	QC	25	0.09	597	0.001	3	0.77	0.009	0.12	<0.1	0.15	7.6	0.4	0.21	2	5.4	<0.2
1278862	Soil	7	0.02	270	0.001	1	0.27	0.006	0.05	<0.1	0.14	1.0	0.6	0.05	1	3.4	<0.2
REP 1278862	QC	6	0.02	273	0.001	1	0.26	0.006	0.05	<0.1	0.14	0.9	0.6	<0.05	1	3.4	<0.2
1278880	Soil	16	0.04	1004	0.002	3	0.53	0.006	0.08	<0.1	0.26	2.9	0.4	<0.05	2	2.6	0.2
REP 1278880	QC	17	0.04	994	0.003	3	0.52	0.006	0.10	<0.1	0.24	2.6	0.4	<0.05	2	2.9	<0.2
1279935	Soil	12	0.05	932	0.004	6	0.48	0.009	0.05	0.1	0.34	1.6	0.2	0.06	2	0.9	<0.2
REP 1279935	QC	12	0.05	895	0.003	4	0.46	0.009	0.05	0.1	0.29	1.4	0.2	0.10	2	1.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11001217.3

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1280134	Soil	21.7	30.8	9.0	165	<0.1	51.4	5.7	98	1.41	16.2	4.5	1.3	18	0.6	2.8	0.2	47	0.30	0.037	6
REP 1280134	QC	24.1	32.7	9.9	176	<0.1	54.7	6.0	107	1.50	17.5	2.7	1.4	20	0.6	3.0	0.2	52	0.32	0.039	7
1280142	Soil	0.8	7.6	6.0	29	0.2	5.8	2.1	48	1.04	4.6	<0.5	0.1	5	<0.1	0.4	0.1	16	0.01	0.033	2
REP 1280142	QC	0.7	7.1	6.1	28	0.2	5.3	2.1	45	1.00	4.5	1.5	0.1	5	<0.1	0.4	<0.1	15	0.01	0.034	2
1280159	Soil	2.6	15.8	13.1	78	<0.1	15.8	4.8	101	2.61	14.7	<0.5	2.1	12	0.2	1.1	0.2	44	0.03	0.045	6
REP 1280159	QC	2.4	14.5	12.2	76	<0.1	15.6	4.6	92	2.45	14.5	<0.5	1.9	11	0.3	1.0	0.2	40	0.02	0.041	6
Reference Materials																					
STD DS8	Standard	12.8	110.5	125.0	307	1.8	36.9	7.6	604	2.44	24.4	107.0	6.6	68	2.3	5.7	6.7	41	0.70	0.077	16
STD DS8	Standard	14.4	107.6	128.6	319	1.9	38.5	7.5	623	2.49	23.8	111.0	7.1	71	2.3	5.7	6.3	42	0.71	0.076	18
STD DS8	Standard	13.2	107.9	121.6	315	1.8	39.2	7.4	607	2.40	24.6	117.2	7.0	70	2.3	5.6	6.8	41	0.68	0.072	16
STD DS8	Standard	14.1	110.8	124.2	305	1.8	38.8	7.7	613	2.38	24.4	129.3	6.7	68	2.0	5.3	7.3	47	0.69	0.075	16
STD DS8	Standard	13.6	117.6	129.5	324	1.9	40.7	8.0	642	2.56	27.3	114.3	7.3	73	2.5	5.7	7.7	33	0.72	0.082	16
STD DS8	Standard	13.2	118.2	124.9	313	1.7	39.8	7.7	600	2.44	25.2	105.6	6.9	62	2.4	5.4	6.7	42	0.68	0.085	14
STD DS8	Standard	13.3	115.2	129.3	303	1.8	39.9	7.9	605	2.44	24.9	131.7	6.9	66	2.5	5.5	7.0	42	0.68	0.084	14
STD DS8	Standard	13.1	104.6	121.5	331	1.7	36.5	7.2	611	2.44	24.9	117.4	6.7	72	2.6	5.9	6.4	39	0.70	0.080	17
STD DS8	Standard	13.4	112.4	126.9	312	1.7	38.2	7.4	594	2.38	23.7	121.9	6.9	66	2.3	5.6	6.6	50	0.67	0.077	16
STD DS8	Standard	12.4	112.1	128.5	320	1.9	37.9	7.8	616	2.54	25.3	119.9	6.8	64	2.5	5.9	6.8	41	0.65	0.082	13
STD DS8	Standard	13.8	117.8	129.2	307	1.8	38.9	7.8	642	2.50	25.3	120.7	6.3	60	2.4	5.5	6.3	45	0.69	0.078	15
STD DS8	Standard	11.4	94.5	117.0	301	1.7	33.6	6.6	561	2.25	22.1	109.3	5.9	62	1.9	5.1	5.7	38	0.62	0.073	13
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11001217.3

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1280134	Soil	11	0.05	298	0.003	2	0.32	0.003	0.05	<0.1	0.08	1.7	0.3	<0.05	1	1.3	<0.2
REP 1280134	QC	12	0.06	333	0.003	2	0.36	0.004	0.06	0.1	0.06	1.9	0.3	<0.05	1	1.2	<0.2
1280142	Soil	7	0.04	45	0.003	1	0.42	0.016	0.03	<0.1	0.04	0.5	<0.1	<0.05	1	0.8	<0.2
REP 1280142	QC	6	0.04	41	0.003	<1	0.38	0.014	0.02	<0.1	0.03	0.4	<0.1	<0.05	1	<0.5	<0.2
1280159	Soil	15	0.12	196	0.003	<1	0.87	0.004	0.07	<0.1	0.02	1.6	0.1	<0.05	4	0.6	<0.2
REP 1280159	QC	14	0.11	180	0.002	<1	0.77	0.004	0.06	<0.1	0.03	1.6	<0.1	<0.05	4	<0.5	<0.2
Reference Materials																	
STD DS8	Standard	114	0.60	275	0.113	3	0.94	0.093	0.42	3.1	0.17	2.4	5.4	0.16	5	5.5	5.3
STD DS8	Standard	120	0.59	292	0.121	3	0.91	0.099	0.40	3.0	0.21	2.2	5.6	0.18	5	5.4	5.3
STD DS8	Standard	114	0.58	276	0.118	2	0.88	0.106	0.41	3.0	0.20	2.2	5.3	0.14	5	5.2	4.6
STD DS8	Standard	119	0.60	274	0.119	2	0.91	0.095	0.41	3.0	0.19	2.2	5.4	0.10	5	5.1	5.1
STD DS8	Standard	116	0.66	288	0.117	2	1.02	0.110	0.45	3.0	0.22	2.8	5.7	0.14	5	5.6	5.2
STD DS8	Standard	120	0.59	269	0.113	2	0.92	0.088	0.39	3.1	0.21	2.3	5.3	0.16	5	5.5	4.7
STD DS8	Standard	117	0.62	279	0.111	4	0.92	0.098	0.44	3.0	0.21	2.6	5.6	0.18	5	5.0	5.1
STD DS8	Standard	108	0.60	298	0.115	3	0.96	0.098	0.45	2.9	0.20	3.2	5.9	0.17	5	4.8	4.7
STD DS8	Standard	120	0.59	271	0.114	2	0.89	0.103	0.42	2.9	0.21	2.4	5.3	0.17	5	5.0	4.8
STD DS8	Standard	120	0.61	265	0.111	3	0.89	0.089	0.40	3.1	0.21	2.1	5.4	0.15	5	5.3	4.9
STD DS8	Standard	124	0.62	278	0.112	3	0.92	0.091	0.43	3.1	0.20	2.2	5.6	0.15	5	5.7	5.0
STD DS8	Standard	106	0.54	255	0.099	2	0.83	0.084	0.38	2.5	0.21	2.3	5.0	0.11	4	4.2	4.8
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11001217.3

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 12, 2012

QUALITY CONTROL REPORT WHI11001217.3

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 24, 2011
Report Date: November 07, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001218.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #15
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve soil to 230 mesh			WHI
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	311	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280168	Soil	18.7	30.6	22.7	78	0.8	18.4	3.7	173	2.25	31.2	5.8	0.8	28	0.2	8.4	0.3	109	0.05	0.095	20
1280169	Soil	11.9	34.5	26.9	75	1.3	17.8	3.3	130	2.38	37.0	4.8	0.6	45	0.2	7.5	0.3	111	0.05	0.209	17
1280170	Soil	10.6	17.8	18.8	79	0.3	21.1	3.4	77	1.81	23.6	0.7	0.1	19	0.2	3.8	0.4	122	0.07	0.088	14
1280171	Soil	12.1	16.3	13.8	80	0.4	23.0	5.8	161	1.41	19.8	1.2	0.2	22	0.3	3.8	0.2	89	0.10	0.103	11
1280172	Soil	4.2	147.0	20.4	277	0.1	454.3	142.4	902	12.27	11.1	<0.5	8.9	182	0.7	1.7	0.1	55	5.27	0.341	31
1280173	Soil	166.7	94.6	11.6	1530	1.5	532.8	8.4	179	1.96	72.8	<0.5	1.6	110	15.6	33.8	0.2	635	1.29	0.159	23
1280174	Soil	70.7	169.6	13.7	2761	3.8	325.8	7.0	170	1.74	54.2	5.5	2.8	216	34.3	36.3	0.3	597	7.95	0.210	22
1280175	Soil	74.1	102.8	15.7	1773	2.5	236.1	6.4	194	1.93	53.2	1.8	1.2	120	26.4	28.6	0.2	674	4.69	0.261	22
1280176	Soil	11.3	12.7	3.9	181	0.4	27.1	2.0	95	0.68	9.2	<0.5	0.1	17	3.1	4.1	<0.1	97	0.23	0.135	6
1280177	Soil	51.2	52.7	17.6	723	0.4	133.1	8.5	208	2.41	41.0	3.3	0.5	34	5.8	17.2	0.2	295	0.41	0.316	19
1280178	Soil	29.7	45.0	18.6	437	0.7	106.9	13.4	436	2.78	39.2	<0.5	0.4	33	2.6	11.5	0.2	158	0.22	0.307	15
1280179	Soil	27.2	52.0	10.9	971	1.0	144.0	5.4	195	1.62	28.2	<0.5	0.4	43	9.9	10.9	0.1	185	0.49	0.169	15
1280180	Soil	19.9	41.2	15.3	383	0.5	99.7	10.6	96	3.09	28.9	<0.5	0.3	18	0.3	7.9	0.2	104	0.04	0.187	12
1280181	Soil	2.7	4.5	4.5	31	0.5	7.8	1.2	15	0.36	3.3	<0.5	<0.1	7	0.2	0.8	<0.1	22	0.03	0.065	2
1280182	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280183	Soil	36.7	50.0	10.1	440	1.2	105.9	8.0	393	1.79	43.2	<0.5	0.4	34	7.5	13.2	0.1	213	0.27	0.188	17
1280184	Soil	17.9	13.4	14.7	111	0.4	32.1	3.0	33	0.89	16.6	<0.5	0.1	16	0.1	4.7	0.1	104	0.02	0.077	12
1280185	Soil	10.9	41.6	17.2	578	0.7	156.6	8.9	283	2.02	26.0	<0.5	0.6	43	4.6	6.3	0.1	104	0.52	0.278	14
1280186	Soil	9.3	18.2	10.3	113	0.3	30.4	2.8	59	1.30	12.9	<0.5	0.1	9	<0.1	3.1	0.1	73	0.03	0.118	7
1280187	Soil	5.2	18.5	9.5	75	0.3	20.7	3.5	94	1.02	9.8	<0.5	0.1	11	0.4	2.4	<0.1	41	0.12	0.110	5
1280188	Soil	23.7	163.2	32.3	317	3.0	162.8	19.6	343	4.13	55.9	<0.5	2.0	48	1.8	17.5	0.3	59	1.90	0.146	3
1280189	Soil	5.4	11.2	7.8	57	0.3	14.7	2.3	32	0.76	7.7	<0.5	<0.1	5	0.1	2.5	<0.1	40	0.02	0.056	4
1280190	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280191	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280192	Soil	1.6	18.0	8.8	64	0.2	12.2	5.1	135	1.42	7.4	<0.5	0.2	9	0.3	0.7	0.1	23	0.04	0.092	4
1280193	Soil	0.8	11.3	6.5	50	0.2	13.4	5.7	242	1.13	7.9	<0.5	0.2	10	<0.1	0.6	0.1	15	0.03	0.093	3
1280194	Soil	1.5	22.5	10.7	75	0.1	16.9	8.8	240	2.00	8.8	<0.5	0.2	8	0.2	0.7	0.2	17	0.03	0.102	3
1280195	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280196	Soil	1.6	32.9	23.3	113	<0.1	29.3	18.4	659	3.25	15.6	<0.5	1.0	16	0.1	1.0	0.4	26	0.08	0.081	7
1280197	Soil	0.8	13.1	6.1	33	<0.1	7.6	3.0	99	0.96	4.6	<0.5	0.1	9	<0.1	0.4	0.1	16	0.06	0.065	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280168	Soil	18	0.12	433	0.013	2	0.71	0.007	0.10	0.2	0.18	1.4	0.8	0.13	4	6.6	<0.2
1280169	Soil	24	0.11	811	0.012	2	0.73	0.006	0.10	0.2	0.24	1.4	0.8	0.13	4	6.6	<0.2
1280170	Soil	18	0.06	695	0.010	<1	0.93	0.005	0.07	0.3	0.06	0.6	0.5	0.08	6	2.3	<0.2
1280171	Soil	16	0.04	633	0.005	2	0.56	0.010	0.06	0.1	0.09	0.3	0.4	0.08	3	3.2	<0.2
1280172	Soil	49	0.09	4107	0.011	11	0.71	0.004	0.13	<0.1	0.33	13.6	0.3	<0.05	1	0.9	<0.2
1280173	Soil	36	0.19	690	0.007	6	0.57	0.014	0.10	0.3	0.54	2.9	2.9	<0.05	2	12.9	<0.2
1280174	Soil	54	4.06	562	0.005	11	0.37	0.010	0.11	0.2	1.20	3.6	1.3	0.13	<1	25.1	0.2
1280175	Soil	59	2.21	734	0.006	8	0.64	0.008	0.14	0.2	0.80	3.0	1.7	<0.05	2	15.3	0.3
1280176	Soil	9	0.04	171	0.004	2	0.43	0.023	0.05	<0.1	0.08	0.3	0.3	<0.05	2	3.7	<0.2
1280177	Soil	43	0.09	419	0.005	4	0.63	0.007	0.10	0.2	0.08	1.2	1.0	<0.05	2	12.2	<0.2
1280178	Soil	31	0.07	502	0.006	4	0.62	0.009	0.08	0.2	0.05	0.9	0.6	0.05	2	4.0	<0.2
1280179	Soil	23	0.08	327	0.008	2	0.66	0.023	0.06	0.2	0.29	2.4	0.8	<0.05	2	4.3	<0.2
1280180	Soil	20	0.04	767	0.006	1	0.70	0.008	0.06	0.1	0.06	0.6	0.4	<0.05	3	3.5	<0.2
1280181	Soil	5	0.01	62	0.003	<1	0.23	0.018	0.03	<0.1	0.02	0.3	<0.1	<0.05	<1	<0.5	<0.2
1280182	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280183	Soil	20	0.04	655	0.009	2	0.52	0.017	0.06	0.2	0.72	1.9	0.9	<0.05	1	3.8	<0.2
1280184	Soil	12	0.02	95	0.006	2	0.29	0.010	0.05	0.1	0.02	0.2	0.4	<0.05	2	1.6	<0.2
1280185	Soil	33	0.13	330	0.007	2	0.89	0.011	0.10	<0.1	0.16	2.4	0.4	<0.05	3	2.5	<0.2
1280186	Soil	15	0.04	119	0.005	2	0.64	0.008	0.07	<0.1	0.03	0.3	0.2	<0.05	3	1.5	<0.2
1280187	Soil	11	0.03	152	0.003	1	0.44	0.017	0.05	<0.1	0.04	0.3	0.1	<0.05	2	0.6	<0.2
1280188	Soil	20	0.84	277	0.002	2	0.40	0.003	0.07	<0.1	0.37	5.0	0.3	0.35	1	8.8	<0.2
1280189	Soil	6	0.02	58	0.003	1	0.27	0.015	0.04	<0.1	0.02	0.1	0.1	<0.05	2	0.6	<0.2
1280190	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280191	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280192	Soil	10	0.04	71	0.003	<1	0.53	0.013	0.05	<0.1	0.04	0.3	<0.1	<0.05	2	<0.5	<0.2
1280193	Soil	6	0.03	47	0.005	1	0.35	0.015	0.05	<0.1	0.02	0.7	<0.1	<0.05	1	<0.5	<0.2
1280194	Soil	14	0.05	56	0.003	1	0.46	0.010	0.06	<0.1	0.02	1.6	<0.1	0.05	1	<0.5	<0.2
1280195	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280196	Soil	14	0.15	83	0.002	3	0.74	0.004	0.06	<0.1	0.03	3.8	0.1	<0.05	2	2.2	<0.2
1280197	Soil	7	0.06	49	0.005	<1	0.62	0.021	0.03	<0.1	0.02	0.6	<0.1	<0.05	2	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280198	Soil	1.6	22.7	12.1	82	<0.1	22.3	9.8	299	2.44	12.2	<0.5	0.5	19	0.1	1.0	0.2	28	0.16	0.078	9
1280199	Soil	0.6	9.3	3.8	18	<0.1	5.6	1.8	41	0.69	3.4	<0.5	<0.1	8	<0.1	0.3	<0.1	9	0.06	0.050	3
1280200	Soil	0.6	7.9	4.2	26	<0.1	6.7	3.0	113	0.81	3.7	<0.5	<0.1	9	<0.1	0.3	<0.1	12	0.07	0.044	3
1280201	Soil	1.1	13.5	5.5	44	<0.1	8.5	4.7	82	1.15	5.6	<0.5	0.2	8	<0.1	0.5	0.1	17	0.03	0.041	3
1280202	Soil	1.3	16.0	9.1	64	<0.1	14.6	7.1	105	1.39	9.9	<0.5	0.2	10	<0.1	0.8	0.2	20	0.02	0.043	3
1280203	Soil	1.2	23.1	17.3	75	<0.1	20.8	12.2	280	1.78	12.8	<0.5	0.3	11	<0.1	0.7	0.2	13	0.05	0.069	3
1280204	Soil	3.0	32.7	21.9	190	0.1	47.9	26.0	795	3.89	28.3	0.8	0.6	16	0.4	2.6	0.4	25	0.06	0.109	3
1280205	Soil	16.7	9.3	9.2	35	0.6	7.4	2.0	30	1.05	12.5	1.1	0.4	7	<0.1	3.7	0.3	47	0.02	0.035	2
1280206	Soil	7.4	13.8	13.8	36	0.5	10.7	3.0	49	0.94	8.6	1.5	0.3	16	0.1	2.4	0.3	24	0.16	0.036	2
1280207	Soil	1.2	5.9	4.2	25	0.2	6.0	1.7	44	0.41	2.6	<0.5	<0.1	11	0.2	0.7	<0.1	10	0.08	0.036	1
1280208	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280209	Soil	28.6	43.4	13.3	432	0.5	88.5	8.1	219	2.10	24.4	2.3	1.8	109	3.0	21.5	0.2	70	2.77	0.128	8
1280210	Soil	4.5	6.2	2.7	31	0.3	7.9	1.2	14	0.35	4.2	<0.5	<0.1	5	<0.1	1.8	<0.1	22	0.02	0.035	3
1280211	Soil	13.6	22.5	15.8	190	0.3	41.3	5.5	167	1.29	20.0	1.8	0.6	52	1.9	7.9	0.1	51	0.66	0.086	6
1280212	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280213	Soil	45.9	47.3	17.4	1111	0.4	132.3	14.7	432	2.87	195.5	21.0	2.6	106	9.1	34.2	0.2	198	3.12	0.102	6
1280214	Soil	4.6	150.7	23.2	197	2.2	79.5	24.7	1100	3.13	26.1	2.4	0.8	62	1.7	4.0	0.3	65	0.09	0.187	5
1280215	Soil	4.0	32.2	88.0	48	1.0	9.2	1.5	37	1.45	61.0	2.3	0.1	145	0.2	7.1	0.2	51	0.07	0.179	6
1280216	Soil	4.6	42.3	95.1	39	1.6	9.4	2.4	112	2.13	92.9	6.6	0.5	190	<0.1	8.1	0.2	59	0.11	0.257	6
1280217	Soil	8.3	33.2	57.7	74	1.4	19.2	4.0	122	2.46	36.6	3.3	0.4	116	0.2	5.3	0.3	72	0.06	0.150	10
1280218	Soil	5.8	25.8	52.6	56	0.9	14.1	3.0	84	2.61	54.6	4.2	0.5	119	0.2	4.9	0.2	67	0.07	0.247	8
1280219	Soil	4.9	24.8	36.8	64	0.9	17.2	4.2	160	2.05	21.1	5.7	0.7	84	0.3	3.9	0.2	50	0.14	0.145	11
1280220	Soil	6.1	14.8	19.6	51	0.3	15.7	2.9	73	1.05	9.5	2.4	0.1	21	0.2	2.2	0.1	39	0.03	0.057	6
1280271	Soil	79.8	42.7	11.3	253	0.1	137.7	7.0	43	1.89	49.4	1.9	0.3	9	0.8	8.1	0.2	156	0.04	0.077	12
1280272	Soil	103.6	36.8	9.1	247	<0.1	165.3	7.0	39	1.97	78.4	1.3	0.4	4	0.3	9.0	0.2	87	0.02	0.036	12
1280273	Soil	11.3	107.8	50.7	91	1.3	116.2	16.5	252	5.51	38.0	<0.5	5.2	67	0.9	11.7	0.3	23	3.40	0.041	6
1280274	Soil	13.1	119.4	35.7	524	1.5	101.9	11.3	274	3.49	60.3	3.8	2.3	80	3.6	7.6	0.3	72	0.69	0.202	13
1280275	Soil	25.6	125.6	55.5	407	4.6	106.9	7.0	122	3.56	49.5	8.0	3.7	259	3.8	11.1	0.5	309	1.94	0.949	34
1280276	Soil	1.0	22.5	33.7	47	0.1	18.2	9.8	170	2.37	79.7	0.8	2.0	14	<0.1	3.6	0.5	4	0.08	0.038	10
1280277	Soil	0.5	12.9	25.3	24	<0.1	8.9	7.1	169	1.26	12.7	0.5	0.7	11	<0.1	1.1	0.3	6	0.03	0.037	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280198	Soil	14	0.14	89	0.005	<1	0.66	0.005	0.05	<0.1	0.02	2.0	<0.1	<0.05	2	<0.5	<0.2
1280199	Soil	4	0.03	46	0.006	<1	0.59	0.025	0.03	<0.1	0.03	0.6	<0.1	<0.05	2	<0.5	<0.2
1280200	Soil	5	0.05	50	0.006	<1	0.41	0.022	0.03	<0.1	0.02	0.5	<0.1	<0.05	2	<0.5	<0.2
1280201	Soil	5	0.03	41	0.003	<1	0.41	0.019	0.04	<0.1	0.02	0.9	<0.1	<0.05	2	<0.5	<0.2
1280202	Soil	6	0.03	36	0.004	<1	0.28	0.010	0.04	<0.1	0.01	0.7	<0.1	<0.05	2	<0.5	<0.2
1280203	Soil	8	0.05	54	0.003	<1	0.51	0.015	0.04	<0.1	0.03	1.5	0.1	<0.05	1	<0.5	<0.2
1280204	Soil	19	0.09	70	0.003	1	0.79	0.008	0.05	<0.1	0.04	2.9	0.3	<0.05	2	<0.5	<0.2
1280205	Soil	7	0.01	77	0.004	4	0.33	0.005	0.05	<0.1	0.07	0.9	0.4	<0.05	2	<0.5	<0.2
1280206	Soil	5	0.06	113	<0.001	2	0.34	0.006	0.04	<0.1	0.15	0.9	0.4	<0.05	1	<0.5	<0.2
1280207	Soil	3	0.03	72	0.005	<1	0.23	0.025	0.03	<0.1	0.02	0.5	<0.1	<0.05	1	<0.5	<0.2
1280208	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280209	Soil	12	1.32	571	0.004	4	0.29	0.006	0.06	<0.1	0.18	3.6	0.4	<0.05	<1	<0.5	<0.2
1280210	Soil	4	0.01	102	0.003	2	0.16	0.016	0.03	<0.1	0.03	0.3	<0.1	<0.05	1	<0.5	<0.2
1280211	Soil	13	0.10	431	0.005	2	0.45	0.014	0.05	<0.1	0.19	2.3	0.2	<0.05	2	<0.5	<0.2
1280212	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280213	Soil	19	1.50	457	0.006	3	0.38	0.005	0.05	0.1	0.60	7.3	0.6	<0.05	1	<0.5	<0.2
1280214	Soil	23	0.10	156	0.008	2	1.58	0.010	0.06	<0.1	0.09	4.5	0.4	<0.05	3	<0.5	<0.2
1280215	Soil	13	0.03	508	0.007	1	0.49	0.010	0.06	0.1	0.05	0.5	0.2	<0.05	3	<0.5	0.2
1280216	Soil	29	0.07	596	0.012	<1	0.71	0.016	0.06	<0.1	0.09	2.7	0.3	0.08	3	4.1	<0.2
1280217	Soil	21	0.09	303	0.014	2	0.69	0.008	0.08	0.2	0.07	1.0	0.4	0.09	4	<0.5	<0.2
1280218	Soil	26	0.11	340	0.008	1	0.71	0.008	0.08	0.1	0.06	0.6	0.3	0.10	4	1.3	<0.2
1280219	Soil	19	0.18	439	0.014	1	0.73	0.010	0.09	0.1	0.07	2.0	0.3	0.11	4	1.8	<0.2
1280220	Soil	8	0.02	142	0.010	2	0.31	0.016	0.05	0.1	0.04	0.6	0.1	<0.05	2	<0.5	0.2
1280271	Soil	16	0.04	234	0.006	3	0.37	0.002	0.06	0.3	0.03	0.9	1.4	<0.05	1	0.8	<0.2
1280272	Soil	13	0.03	85	0.003	3	0.28	0.002	0.05	0.3	0.17	0.8	1.3	<0.05	1	<0.5	<0.2
1280273	Soil	11	1.49	252	0.001	4	0.19	0.003	0.08	<0.1	0.39	7.2	0.2	0.73	<1	5.2	<0.2
1280274	Soil	17	0.16	433	0.003	6	0.45	0.003	0.16	<0.1	0.63	4.1	0.6	0.14	1	1.3	<0.2
1280275	Soil	63	0.08	647	0.016	20	0.84	0.006	0.42	0.4	0.99	5.3	1.1	0.39	3	5.4	0.4
1280276	Soil	4	0.03	247	<0.001	2	0.21	0.002	0.09	<0.1	0.06	2.6	<0.1	<0.05	<1	<0.5	<0.2
1280277	Soil	3	0.01	97	0.002	3	0.23	0.013	0.08	<0.1	0.03	1.3	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280278	Soil	0.9	11.7	78.3	27	0.1	11.2	6.1	103	1.80	12.7	0.6	1.5	16	<0.1	1.3	0.5	4	0.02	0.029	10
1280279	Soil	2.5	20.8	20.4	82	0.1	33.9	8.6	114	1.59	19.7	0.8	0.9	15	0.1	1.4	0.3	11	0.09	0.028	6
1280280	Soil	7.2	25.6	39.9	72	0.5	27.1	7.4	99	2.06	29.0	1.4	0.6	36	0.2	2.9	0.5	39	0.04	0.086	3
1280281	Soil	5.1	92.7	34.6	48	1.0	41.1	10.9	373	4.18	118.5	3.0	0.4	46	0.2	4.0	0.4	69	0.02	0.148	5
1280282	Soil	4.9	70.5	18.7	54	0.8	42.0	9.8	250	3.12	44.9	<0.5	0.3	15	0.1	3.3	0.3	61	0.04	0.160	4
1280283	Soil	4.1	75.0	20.6	62	1.1	45.5	18.3	498	3.13	33.9	5.8	0.5	19	<0.1	3.7	0.4	44	0.05	0.106	6
1280284	Soil	3.0	38.1	12.9	36	0.4	15.3	3.8	59	1.45	17.6	1.3	0.2	15	0.3	1.3	0.2	33	0.06	0.183	7
1280285	Soil	6.9	77.4	36.9	319	0.6	82.1	18.1	254	4.67	58.1	3.4	0.7	26	0.4	5.3	0.5	62	0.02	0.101	5
1280286	Soil	4.8	96.5	31.9	196	1.2	70.8	18.5	791	4.58	43.5	4.1	1.2	51	0.9	3.8	0.4	37	0.15	0.098	5
1280287	Soil	5.2	41.4	23.0	130	0.4	38.2	8.2	148	2.60	29.7	1.1	0.5	31	0.3	2.8	0.4	38	0.08	0.079	5
1280288	Soil	7.8	43.3	24.2	139	0.4	36.8	9.3	244	2.88	29.9	2.1	0.4	23	0.3	3.1	0.4	50	0.05	0.111	8
1280289	Soil	6.1	130.7	42.9	299	1.8	80.8	34.6	805	4.60	45.9	3.9	1.5	34	0.8	4.8	0.5	44	0.21	0.111	7
1280290	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280291	Soil	8.1	41.4	11.3	167	0.2	34.6	9.4	162	2.31	27.3	1.6	0.3	9	0.2	2.7	0.4	43	0.05	0.055	3
1280292	Soil	41.6	39.6	11.7	235	0.4	72.3	5.7	135	1.74	25.6	4.0	0.5	28	1.2	7.2	0.2	76	0.21	0.057	7
1280293	Soil	48.7	52.4	14.8	260	1.1	97.8	5.4	186	1.91	21.0	6.9	0.9	55	3.0	7.3	0.2	93	0.47	0.079	7
1280294	Soil	25.5	22.5	11.9	143	0.6	46.1	2.2	27	1.10	10.6	2.0	0.3	30	1.5	4.1	0.1	79	0.24	0.042	5
1280295	Soil	41.6	37.1	17.8	256	0.1	76.6	6.4	94	2.03	27.6	1.4	1.2	33	1.2	6.0	0.2	114	0.25	0.036	7
1280296	Soil	24.0	23.2	9.8	143	<0.1	39.8	4.0	55	1.25	15.0	0.9	0.5	23	0.8	3.8	0.1	68	0.23	0.038	5
1280297	Soil	54.3	64.8	17.2	469	0.7	135.0	11.5	262	2.53	38.0	2.6	1.4	112	5.2	8.5	0.2	106	2.48	0.119	8
1280298	Soil	62.8	66.0	16.7	406	0.6	144.4	10.8	232	2.61	42.7	2.4	1.8	101	3.4	7.6	0.2	96	2.26	0.106	8
1280299	Soil	45.6	36.1	8.1	320	0.1	114.8	5.3	163	1.40	20.7	<0.5	2.6	229	2.9	4.7	<0.1	64	8.72	0.117	6
1280300	Soil	44.0	36.3	9.7	292	0.4	95.2	7.0	155	1.91	23.1	1.6	1.2	63	2.6	4.9	0.2	83	0.98	0.115	8
1280351	Soil	32.7	33.6	9.1	275	0.4	77.9	4.9	114	1.58	18.7	1.1	0.6	42	2.1	4.1	0.1	62	0.72	0.064	6
1280352	Soil	1.1	12.4	10.3	36	1.0	6.7	1.4	35	1.44	7.2	1.0	0.2	12	0.2	0.4	0.2	25	0.03	0.052	2
1280353	Soil	1.8	46.7	27.0	90	1.0	18.5	5.1	227	3.47	21.8	3.5	1.6	27	0.1	0.6	0.3	45	0.05	0.092	3
1280354	Soil	3.0	91.9	33.2	163	2.8	26.1	9.1	209	5.84	37.6	12.6	2.8	32	0.2	1.3	0.4	70	0.02	0.142	5
1280355	Soil	2.6	20.7	14.4	68	0.2	15.1	4.1	134	3.20	14.3	2.4	1.1	11	<0.1	1.0	0.3	50	0.03	0.056	7
1280356	Soil	1.6	20.6	15.1	37	0.2	7.0	1.8	43	1.64	9.8	1.3	0.6	14	<0.1	0.4	0.2	41	0.02	0.072	4
1280357	Soil	1.7	18.7	13.6	42	0.2	9.6	3.9	148	1.79	7.8	4.4	0.4	12	0.2	0.6	0.2	29	0.02	0.062	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280278	Soil	3	0.02	139	<0.001	3	0.23	0.003	0.11	<0.1	0.07	1.9	<0.1	0.07	<1	<0.5	<0.2
1280279	Soil	5	0.01	518	<0.001	<1	0.30	0.003	0.07	0.4	0.07	3.4	0.2	<0.05	<1	<0.5	<0.2
1280280	Soil	10	0.02	1036	<0.001	3	0.37	0.005	0.12	<0.1	0.09	2.5	0.7	0.12	1	<0.5	<0.2
1280281	Soil	20	0.04	152	0.003	1	0.65	0.004	0.09	<0.1	0.02	2.6	0.2	<0.05	2	<0.5	<0.2
1280282	Soil	17	0.03	117	0.007	3	0.45	0.004	0.09	<0.1	0.07	3.4	0.2	<0.05	2	<0.5	<0.2
1280283	Soil	15	0.05	186	0.003	1	0.67	0.002	0.07	<0.1	0.09	3.3	0.3	<0.05	2	<0.5	<0.2
1280284	Soil	12	0.02	170	0.006	1	0.71	0.008	0.05	0.1	0.05	0.8	0.1	0.08	2	<0.5	<0.2
1280285	Soil	21	0.02	74	0.002	2	0.53	0.003	0.07	<0.1	0.07	2.9	0.2	<0.05	3	<0.5	0.3
1280286	Soil	15	0.05	186	0.003	1	0.42	0.008	0.08	<0.1	0.13	3.5	0.2	<0.05	2	<0.5	<0.2
1280287	Soil	12	0.03	127	0.004	1	0.42	0.009	0.08	<0.1	0.03	1.8	0.2	<0.05	2	<0.5	<0.2
1280288	Soil	15	0.03	136	0.005	3	0.49	0.003	0.09	0.1	0.05	1.7	0.2	<0.05	2	<0.5	<0.2
1280289	Soil	14	0.10	415	0.002	2	0.58	0.003	0.10	<0.1	0.13	6.4	0.4	<0.05	2	1.9	0.2
1280290	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280291	Soil	8	0.03	100	0.001	2	0.33	0.007	0.05	<0.1	0.02	1.1	0.2	<0.05	2	1.0	<0.2
1280292	Soil	10	0.06	484	0.002	1	0.31	0.008	0.05	0.1	0.07	1.6	0.4	<0.05	1	1.5	<0.2
1280293	Soil	11	0.07	1005	0.003	3	0.39	0.010	0.07	0.2	0.30	2.4	0.6	0.08	1	2.5	<0.2
1280294	Soil	9	0.06	651	0.002	1	0.40	0.017	0.04	0.1	0.15	1.1	0.3	<0.05	2	0.9	<0.2
1280295	Soil	12	0.05	376	0.002	2	0.31	0.003	0.06	<0.1	0.08	1.5	0.3	<0.05	1	1.4	<0.2
1280296	Soil	8	0.06	178	0.002	2	0.24	0.009	0.05	0.1	0.03	0.8	0.2	<0.05	1	0.9	<0.2
1280297	Soil	17	0.92	381	0.002	3	0.30	0.005	0.08	0.1	0.29	3.3	0.8	0.05	<1	3.4	<0.2
1280298	Soil	17	0.93	377	0.002	4	0.28	0.005	0.08	0.1	0.32	3.5	0.9	0.05	<1	4.0	<0.2
1280299	Soil	10	2.50	222	0.002	5	0.17	0.006	0.07	<0.1	0.21	2.3	0.7	<0.05	<1	1.6	<0.2
1280300	Soil	13	0.10	252	0.003	3	0.30	0.006	0.05	0.1	0.35	2.5	0.6	<0.05	<1	2.1	<0.2
1280351	Soil	10	0.10	258	0.004	2	0.47	0.018	0.04	0.1	0.26	1.9	0.4	<0.05	1	2.5	<0.2
1280352	Soil	10	0.04	177	0.002	<1	0.65	0.014	0.06	<0.1	0.04	0.6	<0.1	<0.05	3	0.5	<0.2
1280353	Soil	27	0.20	481	0.001	<1	1.31	0.007	0.10	<0.1	0.07	4.2	0.1	<0.05	5	1.3	<0.2
1280354	Soil	39	0.19	289	0.003	<1	1.58	0.006	0.09	0.1	0.24	6.5	0.1	0.10	5	2.5	0.3
1280355	Soil	19	0.16	105	0.004	<1	0.96	0.006	0.04	<0.1	0.03	1.5	0.1	<0.05	4	0.9	<0.2
1280356	Soil	14	0.03	171	<0.001	<1	0.74	0.005	0.06	<0.1	0.04	0.8	<0.1	<0.05	4	0.6	<0.2
1280357	Soil	13	0.09	259	0.002	1	0.79	0.017	0.05	<0.1	0.07	0.8	<0.1	<0.05	3	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280358	Soil		0.7	6.4	5.9	14	0.3	3.3	0.9	22	0.66	2.9	0.9	<0.1	8	<0.1	0.3	<0.1	13	0.01	0.044	1
1280359	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280360	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280361	Soil		4.5	26.6	16.1	114	0.2	25.3	8.4	197	2.56	16.1	4.0	1.2	37	0.2	2.1	0.2	36	0.04	0.068	6
1280362	Soil		4.0	35.3	16.1	93	0.2	22.9	5.4	98	2.04	13.1	1.8	1.0	37	0.3	1.4	0.2	32	0.06	0.062	5
1280363	Soil		2.5	26.9	18.5	107	0.2	26.2	10.2	286	2.88	16.8	1.5	1.2	45	0.4	1.3	0.2	30	0.09	0.072	3
1280364	Soil		5.4	27.9	9.2	405	0.3	76.8	20.2	322	2.74	13.9	0.8	1.5	25	2.8	3.4	0.1	40	0.11	0.050	3
1280365	Soil		3.5	3.7	14.0	22	<0.1	3.7	1.0	15	0.89	17.9	<0.5	1.0	52	<0.1	1.8	0.2	10	0.07	0.011	1
1280366	Soil		0.7	10.8	5.2	37	0.1	9.0	4.2	145	0.89	6.1	<0.5	0.1	7	0.3	0.3	<0.1	10	0.03	0.064	2
1280367	Soil		2.8	24.5	21.1	107	0.2	26.9	10.5	231	3.29	24.5	<0.5	1.6	17	0.2	1.1	0.3	41	0.03	0.049	4
1280368	Soil		2.0	43.3	30.8	161	0.1	51.6	29.8	682	4.03	26.4	1.9	2.9	38	0.3	1.6	0.3	38	0.13	0.077	5
1280369	Soil		1.6	15.6	12.6	68	<0.1	21.3	9.1	149	1.65	11.7	<0.5	0.6	13	<0.1	0.7	0.2	15	0.09	0.040	2
1280370	Soil		1.4	15.3	10.3	71	<0.1	12.0	5.2	45	0.99	11.7	<0.5	0.5	14	0.1	0.7	0.2	14	0.03	0.029	3
1280371	Soil		1.4	24.7	8.2	53	<0.1	23.8	10.5	105	2.06	11.3	0.5	0.6	11	<0.1	0.5	0.2	15	<0.01	0.033	3
1280372	Soil		6.0	17.6	38.1	32	0.5	14.4	3.4	30	1.31	34.2	1.4	0.3	86	<0.1	1.9	0.2	27	0.04	0.091	2
1280373	Soil		8.0	32.5	58.1	15	1.5	9.5	1.7	21	1.08	36.0	4.3	0.4	68	<0.1	4.0	0.2	31	0.01	0.063	3
1280374	Soil		15.8	28.1	62.2	34	0.9	17.1	1.8	14	2.31	75.9	4.3	1.1	146	0.1	7.9	0.2	33	0.01	0.068	3
1280375	Soil		3.9	50.3	23.0	36	0.7	23.5	6.3	82	2.52	101.7	0.9	0.2	33	0.2	2.8	0.4	45	0.01	0.120	3
1280376	Soil		4.6	48.3	22.6	140	0.5	27.9	6.6	110	2.49	84.9	2.6	0.2	13	0.2	2.8	0.4	45	<0.01	0.082	4
1280377	Soil		3.6	18.8	17.5	94	0.2	18.2	5.6	168	3.45	28.0	1.3	2.4	15	0.3	1.6	0.3	53	0.03	0.070	8
1280378	Soil		2.8	16.4	13.6	80	<0.1	18.4	6.4	112	2.07	17.2	0.7	1.4	15	0.3	1.2	0.3	34	0.02	0.035	6
1280379	Soil		3.9	21.7	21.7	78	0.7	20.1	7.5	192	2.09	17.4	1.0	1.2	30	0.3	1.6	0.3	35	0.03	0.062	6
1280380	Soil		8.2	25.0	14.3	164	0.8	33.7	8.4	198	2.39	18.3	3.1	1.6	37	1.5	2.4	0.2	59	0.21	0.120	10
1280381	Soil		12.4	45.1	15.6	237	0.3	55.8	12.3	272	2.63	29.1	2.5	3.1	36	1.4	4.4	0.2	68	0.19	0.131	14
1280382	Soil		12.1	36.5	15.0	214	0.3	48.3	7.4	150	2.63	28.4	4.1	3.1	30	0.9	4.3	0.2	72	0.14	0.123	14
1280383	Soil		13.7	46.5	16.1	254	0.4	53.8	8.1	211	2.48	28.3	3.1	1.4	42	2.1	4.6	0.2	79	0.21	0.139	13
1280384	Soil		18.6	65.7	25.5	398	0.8	77.4	16.4	393	3.38	35.8	4.5	2.7	52	3.1	6.7	0.3	119	0.25	0.154	18
1280385	Soil		9.0	26.0	11.0	146	0.7	28.7	6.6	159	1.54	13.7	2.6	1.2	29	1.2	2.2	0.2	67	0.16	0.111	10
1280386	Soil		17.4	28.6	11.7	131	0.4	31.9	3.9	70	1.37	16.3	2.7	0.3	16	1.2	3.0	0.2	68	0.04	0.099	8
1280387	Soil		10.8	29.8	18.2	196	0.3	40.8	6.6	129	2.86	27.7	3.7	2.4	26	0.8	3.9	0.3	90	0.05	0.089	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280358	Soil		5	0.02	152	0.002	<1	0.23	0.021	0.03	<0.1	0.02	0.3	<0.1	<0.05	1	<0.5	<0.2
1280359	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280360	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280361	Soil		15	0.17	1191	0.002	1	0.69	0.004	0.07	<0.1	0.07	1.9	0.2	0.07	2	1.4	<0.2
1280362	Soil		16	0.16	1140	0.002	1	0.70	0.008	0.07	<0.1	0.06	3.0	0.2	0.07	2	0.9	<0.2
1280363	Soil		18	0.18	1574	0.001	<1	0.84	0.006	0.08	<0.1	0.11	2.4	0.2	0.12	3	1.3	<0.2
1280364	Soil		9	0.06	4290	0.002	<1	2.05	0.011	0.05	<0.1	0.11	3.7	0.7	<0.05	2	1.8	<0.2
1280365	Soil		4	0.03	1054	<0.001	<1	0.17	0.005	0.07	<0.1	0.03	0.6	0.3	0.08	<1	1.6	<0.2
1280366	Soil		4	0.02	305	0.002	<1	0.43	0.016	0.03	<0.1	0.03	0.5	<0.1	<0.05	1	<0.5	<0.2
1280367	Soil		24	0.33	265	0.002	<1	1.36	0.007	0.10	<0.1	0.02	2.1	0.2	<0.05	4	0.6	<0.2
1280368	Soil		27	0.50	581	0.001	<1	1.40	0.006	0.14	<0.1	0.06	5.0	0.2	0.07	4	0.5	<0.2
1280369	Soil		14	0.14	233	0.002	<1	0.51	0.007	0.11	<0.1	0.01	1.0	0.1	<0.05	2	<0.5	<0.2
1280370	Soil		5	0.02	247	<0.001	<1	0.30	0.003	0.06	<0.1	<0.01	1.2	0.1	<0.05	<1	<0.5	<0.2
1280371	Soil		6	0.03	135	<0.001	<1	0.29	0.003	0.05	<0.1	0.03	1.8	<0.1	<0.05	<1	<0.5	<0.2
1280372	Soil		7	0.01	520	<0.001	1	0.29	0.004	0.08	<0.1	0.07	1.5	0.4	0.12	1	2.0	<0.2
1280373	Soil		7	<0.01	805	<0.001	<1	0.27	0.004	0.11	<0.1	0.31	2.0	0.5	0.13	1	4.2	<0.2
1280374	Soil		10	<0.01	287	<0.001	1	0.20	0.006	0.14	<0.1	0.30	3.6	1.4	0.32	1	5.7	<0.2
1280375	Soil		16	0.01	148	0.001	<1	0.37	0.003	0.06	<0.1	0.05	1.2	0.1	<0.05	2	1.3	<0.2
1280376	Soil		11	0.02	136	0.003	2	0.42	0.002	0.05	<0.1	0.06	0.9	0.2	<0.05	2	0.9	<0.2
1280377	Soil		22	0.20	142	0.008	2	1.03	0.005	0.06	0.2	0.04	2.2	0.2	<0.05	4	1.2	<0.2
1280378	Soil		10	0.07	307	0.003	1	0.58	0.003	0.06	<0.1	0.01	1.9	0.1	<0.05	2	0.5	<0.2
1280379	Soil		12	0.08	407	0.006	3	0.59	0.005	0.09	<0.1	0.06	2.4	0.3	0.08	2	1.3	<0.2
1280380	Soil		17	0.17	1576	0.003	3	0.97	0.006	0.06	0.1	0.31	2.7	0.2	<0.05	3	1.5	<0.2
1280381	Soil		15	0.14	1292	0.004	3	0.67	0.002	0.07	0.1	0.24	3.2	0.2	<0.05	2	1.8	<0.2
1280382	Soil		17	0.14	387	0.004	3	0.80	0.002	0.06	0.2	0.18	2.4	0.3	<0.05	2	1.6	<0.2
1280383	Soil		17	0.14	1315	0.004	2	0.75	0.005	0.08	0.2	0.31	2.5	0.3	<0.05	2	1.9	<0.2
1280384	Soil		27	0.19	1333	0.008	4	1.17	0.005	0.11	0.2	0.40	4.1	0.4	<0.05	3	2.4	<0.2
1280385	Soil		16	0.11	868	0.003	2	0.87	0.007	0.07	0.2	0.33	1.8	0.3	<0.05	2	1.1	<0.2
1280386	Soil		13	0.05	544	0.005	3	0.58	0.009	0.08	0.1	0.14	1.3	0.4	<0.05	2	1.1	<0.2
1280387	Soil		19	0.13	401	0.003	2	1.05	0.003	0.07	0.2	0.10	2.3	0.3	<0.05	3	1.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280388	Soil		10.9	20.9	12.4	125	0.5	27.1	3.7	60	1.70	18.4	1.6	1.5	17	0.8	2.9	0.2	83	0.04	0.043	11
1280389	Soil		14.6	39.2	17.2	258	0.3	53.5	8.3	200	2.76	28.4	3.5	3.0	37	1.2	5.3	0.2	90	0.17	0.125	14
1280390	Soil		7.9	31.0	10.5	146	0.3	31.7	4.4	107	1.66	16.3	1.6	0.6	24	1.4	2.8	0.1	62	0.10	0.092	7
1280391	Soil		6.7	25.2	15.1	63	0.5	14.0	2.8	54	1.58	16.4	1.9	0.3	32	0.3	4.0	0.3	63	0.02	0.063	10
1280392	Soil		2.9	11.0	7.0	34	0.2	6.2	1.4	42	0.75	8.5	0.6	<0.1	11	0.2	1.1	0.1	27	0.02	0.051	5
1280393	Soil		5.0	46.4	113.9	128	0.4	26.3	9.8	231	3.05	264.6	8.9	1.3	54	0.3	6.8	0.4	34	0.02	0.080	6
1280394	Soil		7.3	43.3	22.8	164	<0.1	33.1	7.4	118	2.82	61.8	1.8	0.3	13	0.3	4.5	0.4	47	0.01	0.078	9
1280395	Soil		5.4	22.7	10.5	82	0.1	17.0	4.2	80	1.49	32.6	3.3	0.2	7	0.4	2.8	0.2	38	0.02	0.059	7
1280396	Soil		18.6	34.2	20.7	251	0.3	57.2	8.9	282	3.47	54.3	2.8	0.3	20	1.4	7.1	0.3	152	0.06	0.101	14
1280397	Soil		127.0	197.7	28.3	2014	5.1	284.3	15.9	420	2.72	113.7	5.3	2.3	82	46.0	57.4	0.2	1053	0.68	0.221	41
1280398	Soil		74.9	49.1	17.6	657	0.7	174.2	9.5	219	3.60	59.6	2.0	0.2	12	2.7	23.9	0.2	458	0.04	0.120	18
1280399	Soil		81.7	31.6	13.1	192	0.1	136.9	6.5	89	2.05	22.9	1.7	0.9	8	0.2	6.2	0.2	144	0.02	0.066	14
1280400	Soil		197.1	95.8	21.0	1050	0.6	298.7	5.0	62	2.81	128.0	<0.5	0.6	12	1.2	111.3	0.3	1111	0.02	0.087	23
1280411	Soil		15.9	35.7	7.3	250	0.3	81.3	4.3	187	0.96	10.5	<0.5	0.5	117	5.3	3.6	0.1	50	3.06	0.071	4
1280412	Soil		66.8	73.5	16.9	497	0.6	163.9	11.4	257	2.61	39.2	3.6	3.0	108	4.1	9.1	0.2	136	2.43	0.122	11
1280413	Soil		23.3	67.7	14.1	377	1.0	108.9	9.3	451	1.68	21.2	3.0	1.0	94	5.4	5.3	0.2	82	1.67	0.089	8
1280414	Soil		18.1	35.2	13.9	179	0.7	43.2	8.8	377	1.76	17.5	2.7	1.6	47	1.2	3.0	0.2	65	0.68	0.099	9
1280415	Soil		2.7	20.3	16.0	101	0.1	26.2	8.7	116	2.35	23.4	1.8	0.7	20	0.1	1.0	0.2	31	0.04	0.042	6
1280416	Soil		2.8	28.9	27.5	112	0.1	34.6	10.8	200	3.50	20.0	1.7	1.3	29	0.1	1.0	0.3	27	0.05	0.041	4
1280417	Soil		1.7	11.8	10.4	32	0.4	8.6	2.3	36	0.87	11.6	<0.5	0.2	13	0.3	0.5	0.2	20	0.02	0.061	3
1280418	Soil		3.1	33.8	22.7	90	0.3	25.6	8.0	223	2.67	56.7	3.8	0.7	21	0.4	1.8	0.3	41	0.07	0.099	8
1280419	Soil		2.8	35.4	13.6	75	0.3	22.5	6.1	124	1.83	42.6	4.1	0.4	21	0.3	1.9	0.2	31	0.04	0.066	5
1280420	Soil		7.1	36.9	18.5	77	1.4	21.6	3.9	96	1.90	37.3	4.2	0.5	41	0.1	4.7	0.2	59	0.02	0.118	4
1280421	Soil		5.6	24.8	27.4	54	0.4	16.4	4.1	65	1.74	93.3	2.4	0.3	23	0.2	3.0	0.3	48	0.02	0.095	4
1280422	Soil		2.4	27.8	11.2	33	<0.1	12.2	4.2	222	1.18	12.5	3.1	0.1	9	0.2	1.1	0.2	20	0.04	0.049	3
1280423	Soil		4.2	29.3	14.8	110	0.2	22.4	5.9	170	1.94	68.3	2.6	0.1	11	0.2	2.1	0.3	34	0.02	0.063	3
1280424	Soil		7.7	37.9	24.0	114	0.4	31.3	8.4	205	2.70	81.6	2.7	1.0	34	0.3	3.1	0.4	53	0.05	0.088	6
1280425	Soil		132.6	131.9	18.9	1379	2.4	252.7	5.9	241	2.11	114.3	4.5	2.2	96	29.4	50.1	0.2	349	1.66	0.168	20
1280426	Soil		74.2	76.8	10.3	288	0.5	203.4	7.9	143	2.54	37.6	1.8	2.8	180	4.5	9.0	0.1	112	6.02	0.084	10
1280427	Soil		53.2	47.1	8.3	436	0.7	104.1	4.3	126	1.33	52.6	2.3	0.4	57	4.7	14.4	0.2	140	0.66	0.111	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280388	Soil	13	0.07	423	0.005	2	0.72	0.006	0.05	0.2	0.08	1.4	0.3	<0.05	3	1.2	<0.2
1280389	Soil	19	0.15	689	0.006	3	0.82	0.004	0.08	0.2	0.14	2.7	0.3	<0.05	2	3.0	<0.2
1280390	Soil	13	0.09	1006	0.003	2	0.72	0.012	0.07	0.1	0.18	1.5	0.2	<0.05	2	1.2	<0.2
1280391	Soil	14	0.02	295	0.019	2	0.34	0.010	0.06	0.3	0.04	0.6	0.2	<0.05	3	2.6	<0.2
1280392	Soil	6	0.02	81	0.007	<1	0.41	0.018	0.04	<0.1	0.02	0.2	<0.1	<0.05	2	0.8	<0.2
1280393	Soil	14	0.06	193	0.005	1	0.81	0.004	0.07	<0.1	0.04	2.0	0.3	<0.05	3	2.3	<0.2
1280394	Soil	10	0.02	95	0.006	2	0.44	0.005	0.06	0.1	0.03	0.6	0.2	<0.05	3	2.3	<0.2
1280395	Soil	10	0.03	78	0.005	1	0.44	0.008	0.05	0.1	0.04	0.4	0.2	<0.05	3	1.2	<0.2
1280396	Soil	45	0.20	187	0.010	2	1.02	0.004	0.08	0.1	0.06	0.7	0.6	<0.05	4	3.0	<0.2
1280397	Soil	78	0.19	791	0.019	9	1.19	0.004	0.18	0.5	1.54	6.3	3.5	<0.05	2	15.6	0.2
1280398	Soil	80	0.14	233	0.014	2	1.04	0.005	0.08	0.1	0.10	0.7	1.6	<0.05	4	11.0	<0.2
1280399	Soil	30	0.10	107	0.010	2	0.74	0.006	0.05	0.3	0.03	0.6	1.5	<0.05	3	3.7	<0.2
1280400	Soil	69	0.11	221	0.011	4	1.10	0.003	0.12	0.4	0.05	1.0	4.0	<0.05	5	26.2	0.6
1280411	Soil	7	0.22	513	0.003	7	0.24	0.005	0.03	0.2	0.18	1.2	0.3	0.09	<1	5.5	<0.2
1280412	Soil	15	1.15	409	0.003	5	0.35	0.004	0.08	0.2	0.36	3.7	0.8	<0.05	<1	5.5	0.3
1280413	Soil	13	0.16	1287	0.004	4	0.56	0.014	0.05	0.1	0.50	3.2	0.4	<0.05	1	3.8	<0.2
1280414	Soil	14	0.16	1112	0.004	3	0.76	0.007	0.07	0.1	0.27	3.0	0.4	<0.05	2	1.8	<0.2
1280415	Soil	8	0.04	298	0.002	2	0.41	0.004	0.07	<0.1	0.03	2.0	0.2	<0.05	2	0.9	<0.2
1280416	Soil	8	0.03	541	0.001	3	0.29	0.004	0.08	<0.1	0.15	4.1	0.3	0.08	<1	0.9	<0.2
1280417	Soil	6	0.03	294	0.005	2	0.64	0.024	0.07	<0.1	0.07	0.6	0.2	<0.05	2	<0.5	<0.2
1280418	Soil	18	0.12	218	0.007	3	0.73	0.006	0.06	0.1	0.07	1.7	0.2	<0.05	3	0.9	<0.2
1280419	Soil	10	0.07	285	0.005	2	0.52	0.009	0.05	<0.1	0.05	1.3	0.2	<0.05	2	1.1	<0.2
1280420	Soil	9	0.02	2422	0.005	2	0.59	0.011	0.05	<0.1	0.48	1.3	0.2	0.07	2	3.6	<0.2
1280421	Soil	11	0.02	274	0.005	8	0.49	0.004	0.07	0.1	0.04	0.9	0.3	<0.05	2	2.0	<0.2
1280422	Soil	6	0.02	90	0.004	2	0.43	0.018	0.04	<0.1	0.05	0.7	0.1	<0.05	2	0.8	<0.2
1280423	Soil	8	0.02	95	0.003	2	0.33	0.011	0.05	<0.1	0.04	1.1	0.2	<0.05	2	1.1	<0.2
1280424	Soil	15	0.11	404	0.002	3	0.65	0.003	0.07	<0.1	0.05	2.8	0.3	<0.05	2	1.6	<0.2
1280425	Soil	29	0.45	1113	0.003	4	0.43	0.004	0.08	0.3	4.46	4.5	1.1	<0.05	<1	5.1	<0.2
1280426	Soil	13	3.19	272	0.002	6	0.15	0.008	0.05	0.2	0.49	4.1	2.0	<0.05	<1	2.7	<0.2
1280427	Soil	14	0.11	676	0.004	3	0.49	0.016	0.04	0.2	0.83	1.5	0.7	0.07	1	2.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280428	Soil	37.3	58.0	6.1	568	0.4	135.6	3.6	132	1.19	22.7	1.9	0.3	108	3.4	9.5	0.1	107	2.68	0.103	6
1280429	Soil	13.0	11.5	5.8	73	<0.1	18.4	2.2	39	0.92	16.1	0.7	0.6	5	0.1	1.9	0.1	53	0.04	0.022	10
1280430	Soil	87.9	29.4	5.7	192	<0.1	121.5	6.6	24	1.70	23.4	<0.5	1.0	3	0.2	2.7	0.2	68	0.05	0.028	7
1280431	Soil	22.5	24.2	6.4	102	0.3	59.6	5.8	829	1.23	11.3	<0.5	0.3	68	1.0	1.7	0.1	49	1.58	0.099	5
1280432	Soil	19.2	29.6	6.2	153	0.3	73.6	4.7	325	1.22	17.4	1.3	0.6	94	2.0	2.3	0.1	52	2.17	0.080	6
1280433	Soil	8.3	10.2	5.7	62	0.3	19.1	2.2	35	0.95	8.2	<0.5	0.3	19	0.2	1.1	<0.1	28	0.24	0.039	3
1280434	Soil	4.2	92.5	20.1	106	0.6	51.5	14.7	362	4.03	34.4	3.3	1.3	57	0.5	4.4	0.4	36	0.02	0.082	4
1280435	Soil	3.8	60.0	23.9	155	0.4	34.8	13.6	411	3.22	12.5	2.0	1.3	18	0.3	2.5	0.4	17	0.01	0.056	4
1280436	Soil	6.1	62.8	26.0	193	0.4	36.3	13.6	403	3.19	13.3	2.4	1.2	12	0.5	3.2	0.4	25	0.01	0.053	4
1280437	Soil	16.1	47.5	24.7	227	0.2	42.8	8.0	221	2.64	18.9	1.0	0.2	14	0.6	5.6	0.4	82	0.02	0.087	7
1280438	Soil	19.4	95.8	10.7	541	0.9	163.4	23.3	304	4.06	26.5	2.5	2.5	88	5.7	7.9	0.2	173	3.24	0.253	26
1280439	Soil	11.1	71.9	8.4	351	0.5	123.8	24.2	444	4.11	19.2	2.4	1.4	38	2.5	4.0	0.1	85	0.88	0.181	26
1280440	Soil	19.8	102.0	10.6	496	0.5	186.6	37.5	666	5.52	22.3	2.6	2.3	66	7.2	6.4	<0.1	147	2.31	0.264	33
1280441	Soil	56.8	124.2	12.7	818	1.0	319.0	42.9	431	5.18	39.7	2.7	2.8	84	9.8	10.9	<0.1	328	1.30	0.233	35
1280442	Soil	91.8	70.0	10.9	780	0.3	194.9	14.1	221	2.94	57.9	1.2	1.2	26	4.0	16.9	0.1	781	0.32	0.142	23
1280443	Soil	122.2	139.6	21.1	1514	1.2	213.0	7.1	174	2.95	100.3	2.3	0.5	31	13.5	34.4	0.2	573	0.45	0.112	23
1280444	Soil	186.8	247.1	24.7	3152	2.4	466.2	11.1	168	1.97	181.9	2.0	2.5	307	33.1	61.3	0.2	741	8.72	0.105	15
1280445	Soil	100.2	86.6	22.9	347	0.6	224.3	24.6	610	5.46	100.5	3.3	5.5	81	1.9	19.3	0.2	168	2.10	0.080	12
1280446	Soil	37.3	161.4	26.6	953	1.6	273.1	39.6	572	7.54	93.1	3.9	0.8	126	4.9	10.4	0.2	188	0.55	0.414	20
1280447	Soil	11.5	67.5	17.6	245	1.3	94.3	5.6	50	2.15	33.2	3.7	0.3	49	1.1	6.4	0.2	28	0.11	0.144	11
1280448	Soil	18.0	23.9	19.8	138	0.9	44.3	3.7	90	1.50	18.2	1.3	<0.1	40	0.3	4.2	0.2	68	0.03	0.110	9
1280449	Soil	5.5	11.7	16.1	43	0.4	14.5	1.7	226	0.73	7.4	1.1	<0.1	20	0.2	1.9	<0.1	26	0.05	0.130	5
1280450	Soil	21.8	45.8	71.6	166	1.3	56.8	4.4	42	2.03	34.7	0.9	<0.1	63	0.3	12.4	0.3	156	0.03	0.161	11
1280451	Soil	80.7	35.9	11.4	351	0.2	149.4	5.9	60	2.14	27.5	1.0	0.2	6	0.5	8.5	0.1	308	0.01	0.057	14
1280452	Soil	69.4	22.1	5.9	320	0.3	135.3	4.3	30	1.36	15.4	<0.5	<0.1	3	0.3	6.0	<0.1	204	<0.01	0.029	11
1280453	Soil	105.0	22.1	7.7	339	0.2	168.9	4.9	18	1.54	24.1	1.3	0.3	2	0.4	11.0	<0.1	347	<0.01	0.033	20
1280454	Soil	75.5	29.6	7.9	372	0.3	146.6	3.9	37	1.21	21.0	0.8	0.1	17	2.6	6.3	<0.1	135	0.08	0.040	15
1280455	Soil	21.1	56.6	5.4	161	0.2	183.2	25.1	322	3.06	35.8	<0.5	0.5	23	0.5	6.9	<0.1	82	0.44	0.104	9
1280456	Soil	205.7	129.7	37.7	932	3.4	170.0	3.2	76	3.29	230.6	2.7	0.6	114	6.6	67.9	0.2	809	0.03	0.098	15
1280457	Soil	9.2	23.6	8.6	96	<0.1	75.1	17.5	410	2.93	7.9	<0.5	0.7	30	1.0	1.3	<0.1	128	0.83	0.149	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280428	Soil	11	0.23	639	0.003	7	0.40	0.011	0.04	0.1	0.33	1.0	0.6	0.11	<1	4.0	<0.2
1280429	Soil	6	0.03	66	0.004	1	0.40	0.003	0.03	<0.1	0.04	0.6	0.3	<0.05	3	0.8	<0.2
1280430	Soil	10	0.04	170	0.002	3	0.44	0.001	0.05	0.2	0.04	1.2	1.0	<0.05	2	0.8	<0.2
1280431	Soil	7	0.19	1337	0.005	3	0.61	0.019	0.04	0.1	0.19	1.1	0.3	0.07	2	1.0	<0.2
1280432	Soil	12	0.20	550	0.004	5	0.48	0.013	0.04	0.2	0.28	1.7	0.6	0.08	1	1.3	<0.2
1280433	Soil	6	0.06	315	0.002	<1	0.42	0.021	0.03	<0.1	0.05	0.5	0.1	<0.05	1	0.5	<0.2
1280434	Soil	9	0.04	157	0.002	2	0.39	0.004	0.10	<0.1	0.06	4.6	0.4	0.12	1	2.4	<0.2
1280435	Soil	5	0.03	90	0.002	2	0.27	0.003	0.08	<0.1	0.05	2.9	0.2	<0.05	<1	1.4	<0.2
1280436	Soil	6	0.04	99	0.003	2	0.32	0.004	0.08	<0.1	0.02	2.8	0.2	<0.05	<1	1.7	<0.2
1280437	Soil	12	0.04	220	0.003	2	0.46	0.004	0.07	0.1	0.05	0.6	0.3	0.06	2	2.4	<0.2
1280438	Soil	45	1.28	897	0.003	4	0.68	0.008	0.06	0.1	0.18	7.5	0.3	0.17	2	3.0	<0.2
1280439	Soil	30	0.12	950	0.003	3	0.72	0.012	0.04	0.1	0.13	6.4	0.2	0.13	2	2.4	<0.2
1280440	Soil	45	0.70	1158	0.003	6	0.55	0.006	0.07	0.1	0.17	9.4	0.3	0.16	1	2.3	<0.2
1280441	Soil	69	0.27	708	0.003	4	0.66	0.004	0.08	0.2	0.40	10.3	0.9	0.12	1	5.3	<0.2
1280442	Soil	64	0.13	748	0.003	2	1.07	0.006	0.09	0.3	0.21	3.0	1.7	<0.05	3	7.3	<0.2
1280443	Soil	36	0.09	312	0.003	2	0.74	0.007	0.06	0.3	0.61	1.6	1.9	<0.05	2	10.5	0.3
1280444	Soil	45	1.36	230	0.004	5	0.31	0.005	0.10	0.4	2.43	3.2	4.7	0.18	<1	12.3	0.3
1280445	Soil	25	0.96	460	0.003	3	0.18	0.007	0.05	<0.1	0.74	6.2	0.8	0.15	<1	5.2	<0.2
1280446	Soil	69	0.08	417	0.004	3	0.57	0.007	0.06	<0.1	1.49	4.3	0.3	0.06	2	9.5	<0.2
1280447	Soil	13	0.02	185	0.001	1	0.30	0.003	0.03	<0.1	0.38	0.7	0.3	<0.05	<1	3.4	<0.2
1280448	Soil	24	0.02	156	0.002	<1	0.38	0.004	0.05	0.1	0.05	<0.1	0.4	<0.05	2	2.6	<0.2
1280449	Soil	14	0.02	106	0.002	<1	0.39	0.013	0.04	<0.1	0.05	0.2	<0.1	<0.05	2	1.1	<0.2
1280450	Soil	23	0.02	181	<0.001	<1	0.53	0.005	0.05	<0.1	0.06	0.1	0.4	<0.05	2	3.5	0.2
1280451	Soil	29	0.06	135	0.003	1	0.57	0.003	0.05	0.2	0.04	0.4	1.2	<0.05	3	4.1	<0.2
1280452	Soil	11	0.02	83	0.003	<1	0.26	0.002	0.02	0.2	<0.01	0.2	0.6	<0.05	1	2.7	<0.2
1280453	Soil	13	0.01	84	0.002	<1	0.24	0.001	0.03	0.2	<0.01	0.3	0.8	<0.05	<1	5.8	<0.2
1280454	Soil	16	0.02	619	0.003	1	0.28	0.005	0.04	0.3	0.07	0.4	1.2	<0.05	1	3.7	<0.2
1280455	Soil	52	0.04	210	0.002	<1	0.57	0.013	0.03	<0.1	0.03	3.3	0.2	<0.05	2	3.2	<0.2
1280456	Soil	39	0.03	286	0.004	<1	0.49	0.006	0.11	0.2	0.60	1.4	5.8	<0.05	2	21.5	0.4
1280457	Soil	178	1.07	235	0.081	2	1.02	0.007	0.03	0.3	<0.01	1.7	0.3	<0.05	6	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280458	Soil	33.3	25.9	8.9	343	0.2	88.8	8.8	1023	5.81	39.2	2.3	2.2	74	2.1	7.5	<0.1	347	0.95	0.138	18
1280459	Soil	32.2	24.0	9.2	205	<0.1	77.2	6.8	79	1.76	22.6	<0.5	0.3	20	1.0	7.2	<0.1	177	0.33	0.034	11
1280460	Soil	2.1	13.1	13.2	17	0.4	4.6	1.3	61	0.60	5.7	2.7	0.1	26	<0.1	2.4	0.1	17	0.05	0.060	3
1280461	Soil	7.1	107.8	18.5	100	0.4	32.1	6.2	310	2.91	27.5	3.9	0.3	47	0.5	4.4	0.2	65	0.06	0.159	7
1280462	Soil	2.4	23.9	5.3	51	<0.1	13.8	3.8	88	0.89	5.2	0.7	<0.1	9	0.2	1.0	<0.1	15	0.04	0.044	3
1280463	Soil	29.9	93.5	45.6	384	1.5	116.0	30.0	531	3.34	33.1	4.1	0.5	69	3.0	10.2	0.2	123	0.19	0.181	5
1280464	Soil	60.3	62.3	15.7	500	0.2	137.2	12.8	357	3.22	31.5	1.7	0.3	45	3.0	9.2	0.1	215	0.21	0.133	5
1280465	Soil	42.5	26.3	11.1	148	<0.1	57.9	4.6	120	1.67	14.2	1.6	0.2	10	0.8	3.5	<0.1	51	0.09	0.065	3
1280466	Soil	74.5	44.6	18.2	572	<0.1	122.8	10.4	192	3.12	32.9	<0.5	0.2	11	1.7	7.9	0.1	147	0.09	0.068	4
1280467	Soil	55.6	26.0	10.5	342	<0.1	88.0	8.2	116	2.23	31.2	<0.5	<0.1	5	0.6	7.3	<0.1	152	0.02	0.058	2
1280468	Soil	81.8	118.1	31.5	710	0.9	277.8	27.8	690	5.64	44.9	2.9	2.9	80	7.4	11.3	0.1	299	0.61	0.222	19
1280469	Soil	75.6	75.2	31.8	408	0.7	227.6	20.4	816	6.17	85.7	2.1	1.2	57	3.1	16.8	0.1	141	0.66	0.172	9
1280470	Soil	34.8	48.9	14.1	400	0.1	118.9	18.9	403	3.00	23.9	0.7	0.5	27	1.5	5.3	<0.1	125	0.18	0.144	11
1280471	Soil	61.8	125.1	32.2	1889	1.2	417.9	56.9	574	6.49	41.0	2.0	4.2	187	8.7	12.4	0.1	412	2.10	0.287	13
1280472	Soil	93.0	82.2	26.9	660	0.5	226.3	20.3	680	5.06	28.8	1.5	1.4	53	4.4	9.0	0.1	143	1.06	0.123	8
1280473	Soil	70.3	181.6	33.2	473	1.4	338.8	81.9	860	8.71	38.9	6.8	4.2	68	1.6	9.1	<0.1	141	1.37	0.272	16
1280474	Soil	26.5	23.5	8.9	170	0.2	55.6	5.8	260	2.09	9.8	1.3	0.2	9	1.6	2.7	<0.1	54	0.06	0.132	4
1280475	Soil	10.9	8.0	4.7	32	0.1	11.0	1.4	18	0.52	6.0	0.6	<0.1	5	<0.1	1.2	0.1	40	0.01	0.029	7
1280476	Soil	19.2	23.4	7.8	68	0.4	39.9	4.8	59	1.35	19.8	0.6	<0.1	6	<0.1	6.3	0.1	106	<0.01	0.045	4
1280477	Soil	7.9	14.2	7.2	38	0.8	12.9	1.7	25	0.85	7.7	1.1	<0.1	8	0.1	1.6	0.1	36	0.01	0.068	6
1280478	Soil	12.5	25.2	9.1	92	0.2	28.3	4.3	50	1.52	13.5	1.1	0.1	11	0.1	3.2	0.2	70	0.01	0.043	12
1280479	Soil	5.9	7.3	4.1	26	0.2	6.2	1.1	14	0.49	7.4	0.7	0.2	9	<0.1	1.4	<0.1	36	<0.01	0.022	12
1280480	Soil	6.8	113.1	43.4	351	1.1	186.0	31.1	646	5.90	46.7	4.9	2.0	43	1.1	6.1	0.3	54	0.08	0.135	7
1280481	Soil	3.9	64.8	17.0	48	0.6	17.4	3.4	102	2.11	14.9	1.7	0.2	26	0.3	2.5	0.2	52	0.05	0.088	6
1280482	Soil	5.9	35.8	21.9	46	1.5	12.9	2.4	51	2.30	38.0	4.3	0.1	23	0.1	2.8	0.3	77	0.03	0.084	7
1280483	Soil	4.3	20.9	37.8	49	0.7	12.3	2.7	95	2.03	43.8	1.3	0.3	69	0.1	3.4	0.2	52	0.05	0.188	7
1280484	Soil	8.1	49.4	80.8	56	2.6	18.1	4.4	241	2.77	53.3	6.2	0.7	145	0.3	6.8	0.4	68	0.10	0.269	10
1280485	Soil	4.2	26.3	27.7	67	0.6	18.4	4.3	220	2.32	35.2	2.2	0.5	57	0.4	3.8	0.2	52	0.13	0.186	10
1280486	Soil	1.4	15.6	14.5	17	1.2	5.3	1.4	74	0.70	9.0	1.1	<0.1	22	0.2	0.9	<0.1	17	0.04	0.067	3
1280487	Soil	3.7	40.5	41.0	57	1.1	18.2	5.7	307	1.92	22.6	3.4	0.4	41	0.3	2.8	0.2	42	0.10	0.147	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280458	Soil	45	0.23	576	0.004	1	0.78	0.008	0.04	0.1	0.06	5.2	0.3	<0.05	2	2.4	<0.2
1280459	Soil	34	0.10	358	0.012	<1	0.46	0.006	0.03	0.1	0.03	1.2	0.4	<0.05	2	1.8	<0.2
1280460	Soil	8	0.04	65	0.008	<1	0.46	0.018	0.04	<0.1	0.03	0.6	<0.1	<0.05	2	1.4	<0.2
1280461	Soil	27	0.09	102	0.005	<1	0.82	0.005	0.04	<0.1	0.02	2.1	0.2	<0.05	3	2.6	<0.2
1280462	Soil	6	0.02	37	0.005	<1	0.38	0.019	0.03	<0.1	<0.01	0.6	<0.1	<0.05	2	<0.5	<0.2
1280463	Soil	55	0.05	320	0.003	<1	0.50	0.006	0.07	<0.1	0.33	4.5	0.6	0.06	2	5.5	0.2
1280464	Soil	55	0.05	280	0.003	<1	0.53	0.006	0.03	0.1	0.14	1.9	0.7	<0.05	2	4.3	<0.2
1280465	Soil	15	0.02	171	0.002	<1	0.42	0.008	0.02	<0.1	0.04	0.8	0.4	<0.05	1	1.3	<0.2
1280466	Soil	29	0.03	182	0.002	<1	0.28	0.002	0.02	<0.1	0.07	1.2	0.5	<0.05	1	2.9	<0.2
1280467	Soil	23	0.02	76	0.001	<1	0.28	0.004	0.03	<0.1	0.03	0.6	0.5	<0.05	1	1.4	<0.2
1280468	Soil	69	0.10	502	0.003	2	0.51	0.003	0.05	<0.1	0.47	8.5	0.9	<0.05	1	3.6	<0.2
1280469	Soil	44	0.15	276	0.002	3	0.46	0.004	0.04	<0.1	0.47	5.7	0.9	<0.05	1	2.4	<0.2
1280470	Soil	43	0.09	195	0.003	<1	0.73	0.005	0.03	<0.1	0.06	2.1	0.5	<0.05	2	1.6	<0.2
1280471	Soil	101	0.82	414	0.005	2	0.65	0.005	0.06	<0.1	0.51	12.4	1.8	<0.05	2	6.2	<0.2
1280472	Soil	29	0.43	343	0.003	2	0.54	0.005	0.04	<0.1	0.20	4.8	1.0	0.07	1	2.9	<0.2
1280473	Soil	135	0.64	397	0.002	3	0.82	0.004	0.07	<0.1	0.25	11.9	0.9	0.09	3	3.3	<0.2
1280474	Soil	17	0.06	128	0.004	<1	0.38	0.013	0.03	<0.1	0.03	0.5	0.3	0.09	2	1.6	<0.2
1280475	Soil	6	0.02	53	0.005	1	0.28	0.008	0.03	0.1	0.01	0.2	0.2	<0.05	3	<0.5	<0.2
1280476	Soil	9	0.01	74	0.004	<1	0.20	0.006	0.03	<0.1	<0.01	0.3	0.2	<0.05	2	1.7	<0.2
1280477	Soil	7	0.02	160	0.004	1	0.36	0.013	0.03	<0.1	0.04	0.2	0.2	<0.05	2	1.2	<0.2
1280478	Soil	9	0.02	151	0.005	8	0.24	0.005	0.04	0.1	0.01	0.3	0.2	<0.05	2	1.4	<0.2
1280479	Soil	4	<0.01	276	0.005	1	0.16	0.003	0.03	<0.1	0.01	0.2	0.2	<0.05	2	0.7	<0.2
1280480	Soil	23	0.15	148	0.021	1	1.35	0.004	0.05	0.1	0.07	6.8	0.3	0.07	2	2.9	<0.2
1280481	Soil	18	0.09	139	0.011	<1	0.83	0.013	0.05	0.1	0.04	1.2	0.2	0.11	4	2.7	<0.2
1280482	Soil	20	0.04	128	0.007	1	0.42	0.004	0.05	0.1	0.08	0.5	0.2	0.13	5	2.5	<0.2
1280483	Soil	18	0.08	205	0.007	1	0.59	0.009	0.06	0.2	0.04	0.4	0.3	0.16	4	3.1	<0.2
1280484	Soil	29	0.20	493	0.012	1	0.85	0.008	0.11	0.1	0.14	4.9	0.6	0.22	4	5.1	<0.2
1280485	Soil	23	0.21	209	0.012	1	0.74	0.006	0.06	0.2	0.05	0.8	0.2	0.12	3	2.1	<0.2
1280486	Soil	7	0.05	88	0.010	<1	0.59	0.023	0.04	<0.1	0.05	0.4	<0.1	0.09	2	1.1	<0.2
1280487	Soil	20	0.20	242	0.014	2	1.03	0.013	0.07	0.1	0.10	1.3	0.2	0.13	3	2.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280488	Soil		3.5	22.1	27.1	49	0.3	12.3	3.1	139	2.46	20.1	1.7	0.1	28	0.2	2.6	0.2	50	0.03	0.086	7
1280489	Soil		3.8	30.4	21.7	62	0.3	23.5	6.6	180	2.94	16.5	3.1	0.2	19	0.3	2.4	0.2	57	0.03	0.069	7
1280490	Soil		31.5	35.0	15.9	256	0.2	72.6	8.1	143	2.92	25.4	1.7	0.2	12	0.5	7.2	0.2	112	0.03	0.072	8
1280491	Soil		7.3	33.8	12.5	114	0.1	32.1	11.2	159	2.53	15.6	1.2	0.2	10	0.3	2.7	0.2	52	<0.01	0.069	5
1280492	Soil		5.9	21.5	9.8	81	0.1	20.4	5.9	81	1.64	9.9	1.1	<0.1	6	0.2	1.7	0.2	50	<0.01	0.050	5
1280493	Soil		3.8	16.1	9.8	67	0.2	18.5	6.9	307	1.24	5.6	<0.5	0.2	18	0.5	1.2	0.1	26	0.15	0.130	3
1280494	Soil		9.7	22.8	16.9	105	0.3	31.3	7.5	129	2.69	15.9	1.0	0.3	10	0.4	2.4	0.2	52	0.02	0.077	6
1280495	Soil		8.9	24.6	45.2	120	0.4	29.1	7.7	159	2.58	15.7	2.0	0.3	9	0.5	2.5	0.3	50	0.02	0.075	7
1280496	Soil		7.9	22.8	16.1	106	0.3	27.2	7.1	123	2.35	13.7	<0.5	0.6	8	0.6	2.2	0.2	49	0.01	0.064	7
1280497	Soil		5.0	30.5	14.8	83	0.3	17.2	4.1	61	1.64	19.8	<0.5	0.2	10	0.1	2.9	0.2	42	<0.01	0.038	6
1280498	Soil		9.8	16.9	12.9	86	0.3	21.4	4.8	65	1.54	11.7	<0.5	0.2	7	0.5	2.2	0.2	55	<0.01	0.037	7
1280499	Soil		3.6	38.3	10.8	107	0.3	32.0	10.1	150	2.59	36.5	2.6	0.2	6	0.4	3.1	0.3	46	<0.01	0.054	4
1280500	Soil		31.5	12.4	13.9	12	2.3	5.2	0.3	10	1.09	28.8	2.3	0.3	32	0.2	10.2	0.2	293	0.03	0.057	2
1280501	Soil		69.3	79.7	19.0	459	0.7	207.9	17.2	642	4.04	28.3	1.6	3.8	322	6.1	16.1	<0.1	315	9.60	0.140	17
1280502	Soil		66.1	92.6	17.2	683	1.2	188.2	13.2	360	2.67	31.6	1.5	1.8	146	8.7	15.7	0.1	259	4.97	0.133	16
1280503	Soil		8.8	149.1	13.7	96	0.4	267.7	81.1	1013	6.56	8.9	1.5	9.3	137	0.7	2.7	0.1	131	1.49	0.408	50
1280504	Soil		37.4	54.8	12.1	916	0.9	118.7	4.6	176	1.37	38.8	1.3	0.7	59	8.0	16.3	0.2	214	0.84	0.113	7
1280505	Soil		30.7	32.1	11.3	295	0.1	85.5	7.7	219	1.54	11.7	1.3	0.8	47	4.3	3.8	0.1	72	0.74	0.056	6
1280506	Soil		111.7	153.7	24.7	1457	2.4	252.7	9.2	133	1.94	72.5	2.7	1.3	204	21.8	66.1	0.2	308	5.84	0.138	13
1280507	Soil		23.2	42.1	42.5	256	0.5	57.5	5.5	70	2.97	27.3	0.9	0.7	20	0.6	9.6	0.4	109	0.03	0.085	6
1280508	Soil		5.9	11.0	6.2	50	0.2	12.2	1.5	29	0.63	5.4	1.7	0.1	6	0.3	1.4	<0.1	39	0.03	0.037	4
1280509	Soil		9.0	14.3	7.3	61	0.2	18.2	2.7	44	0.99	9.6	<0.5	0.4	8	<0.1	1.9	0.2	80	0.02	0.027	8
1280510	Soil		2.9	24.3	13.4	76	0.3	25.8	7.6	178	1.60	8.9	1.9	0.2	26	0.3	1.2	0.1	24	0.29	0.088	3
1280511	Soil		3.0	32.2	20.0	114	0.5	37.1	11.4	208	3.08	13.5	2.5	1.1	42	0.3	1.1	0.3	41	0.39	0.117	5
1280512	Soil		1.9	26.3	9.8	57	0.3	25.1	5.2	197	1.27	4.2	0.9	0.4	46	0.5	0.6	0.1	22	0.84	0.091	4
1280513	Soil		3.0	40.0	9.7	48	0.4	29.9	6.9	242	0.99	5.0	1.4	0.3	66	0.6	0.8	0.2	18	1.40	0.124	4
1280514	Soil		0.8	10.4	3.8	15	0.1	5.3	1.7	74	0.32	0.8	<0.5	0.2	28	0.5	0.2	<0.1	9	0.51	0.057	3
1280515	Soil		11.7	15.9	35.6	21	0.6	21.0	2.7	100	1.36	7.2	3.0	0.5	19	0.2	2.1	0.2	25	0.30	0.035	2
1280516	Soil		5.2	13.7	9.5	46	0.1	12.0	3.1	48	1.06	7.7	1.4	0.5	7	0.5	1.3	0.2	54	0.03	0.025	8
1280517	Soil		4.3	21.4	13.7	67	0.2	23.5	6.2	112	1.85	9.4	1.6	0.5	18	0.2	1.4	0.2	32	0.19	0.056	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280488	Soil	17	0.07	123	0.008	<1	0.59	0.003	0.04	<0.1	0.04	0.4	0.1	0.08	4	1.8	<0.2
1280489	Soil	21	0.16	115	0.010	1	0.91	0.006	0.04	0.1	0.03	0.7	0.2	0.05	4	1.0	<0.2
1280490	Soil	23	0.07	117	0.008	1	0.65	0.004	0.05	0.1	0.04	0.5	0.4	0.05	3	2.3	<0.2
1280491	Soil	12	0.02	65	0.005	<1	0.38	0.003	0.04	<0.1	0.01	0.9	0.1	<0.05	2	1.1	<0.2
1280492	Soil	10	0.02	73	0.004	<1	0.42	0.006	0.03	0.1	<0.01	0.4	<0.1	<0.05	3	0.6	<0.2
1280493	Soil	10	0.07	240	0.004	<1	0.54	0.013	0.04	<0.1	0.03	0.6	0.1	0.08	2	0.6	<0.2
1280494	Soil	16	0.08	123	0.006	1	0.58	0.006	0.05	0.1	0.03	1.1	0.2	<0.05	3	0.9	<0.2
1280495	Soil	14	0.07	95	0.005	<1	0.50	0.003	0.04	<0.1	0.02	1.6	0.2	<0.05	3	1.0	<0.2
1280496	Soil	11	0.04	84	0.009	<1	0.40	0.004	0.04	<0.1	0.01	2.0	0.1	<0.05	2	1.0	<0.2
1280497	Soil	7	0.01	69	0.004	1	0.26	0.003	0.03	<0.1	0.02	0.8	0.1	<0.05	2	0.8	<0.2
1280498	Soil	7	0.02	67	0.006	<1	0.32	0.002	0.02	<0.1	0.01	0.9	0.1	<0.05	2	0.8	<0.2
1280499	Soil	9	0.02	68	0.003	<1	0.33	0.005	0.03	<0.1	0.01	1.5	0.1	<0.05	2	0.8	<0.2
1280500	Soil	11	0.01	257	0.002	2	0.27	0.002	0.10	0.2	0.43	0.5	1.5	0.11	1	4.9	<0.2
1280501	Soil	33	3.40	513	0.002	2	0.18	0.009	0.04	0.3	0.24	5.1	0.6	0.09	<1	5.7	<0.2
1280502	Soil	26	2.17	300	0.003	2	0.29	0.011	0.04	0.2	0.34	3.9	0.6	0.09	<1	6.5	<0.2
1280503	Soil	182	0.36	306	0.006	2	0.80	0.018	0.05	<0.1	0.08	26.3	0.2	0.07	2	1.0	<0.2
1280504	Soil	24	0.08	337	0.005	2	0.59	0.011	0.04	0.2	0.77	1.9	2.0	0.10	2	3.3	<0.2
1280505	Soil	18	0.10	329	0.004	1	0.47	0.005	0.03	0.1	0.10	2.0	0.4	0.09	1	2.7	<0.2
1280506	Soil	34	1.42	315	0.003	3	0.39	0.010	0.05	0.2	1.11	3.8	1.4	0.08	<1	7.6	<0.2
1280507	Soil	26	0.02	130	0.003	<1	0.52	0.004	0.04	0.1	0.04	1.6	0.5	0.06	2	2.6	<0.2
1280508	Soil	8	0.03	83	0.005	<1	0.40	0.013	0.03	<0.1	0.02	0.3	0.1	<0.05	2	0.6	<0.2
1280509	Soil	10	0.03	71	0.008	<1	0.63	0.009	0.02	0.1	0.01	0.7	0.2	<0.05	4	0.6	<0.2
1280510	Soil	13	0.11	158	0.004	1	0.56	0.013	0.04	<0.1	0.09	1.7	0.1	<0.05	2	1.3	<0.2
1280511	Soil	22	0.14	335	0.003	<1	0.83	0.005	0.04	<0.1	0.22	5.6	0.2	<0.05	2	1.7	<0.2
1280512	Soil	11	0.14	197	0.006	1	0.64	0.013	0.03	<0.1	0.11	1.8	0.1	0.05	2	1.3	<0.2
1280513	Soil	11	0.18	211	0.006	2	0.59	0.015	0.03	<0.1	0.16	1.6	0.1	0.10	1	1.7	<0.2
1280514	Soil	5	0.05	108	0.008	<1	0.47	0.027	0.02	<0.1	0.04	0.9	<0.1	0.05	1	0.5	<0.2
1280515	Soil	10	0.04	531	<0.001	5	0.31	0.006	0.04	<0.1	0.29	1.7	0.3	<0.05	1	0.9	<0.2
1280516	Soil	7	0.01	93	0.004	1	0.32	0.004	0.02	<0.1	0.02	1.2	<0.1	<0.05	2	<0.5	<0.2
1280517	Soil	13	0.08	334	0.003	<1	0.62	0.009	0.03	<0.1	0.05	2.4	0.1	<0.05	2	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280518	Soil		9.0	26.9	27.5	94	0.3	28.7	9.8	349	2.31	15.2	2.1	0.7	25	0.5	2.1	0.3	56	0.23	0.061	6
1280519	Soil		2.6	9.0	7.3	20	0.3	5.1	1.0	20	0.48	4.1	<0.5	<0.1	6	0.1	0.7	0.1	22	0.02	0.022	8
1280520	Soil		6.4	20.9	13.1	68	0.4	19.4	3.4	69	1.56	11.6	1.7	<0.1	9	0.2	2.1	0.2	50	0.08	0.035	8
1280521	Soil		2.0	40.0	9.8	25	1.4	9.4	1.3	24	0.58	4.8	1.8	0.1	13	0.4	0.7	0.1	19	0.15	0.051	6
1280522	Soil		18.1	68.2	19.3	189	0.3	60.6	10.1	295	2.09	28.1	1.7	0.7	24	2.5	4.2	0.2	72	0.18	0.062	8
1280523	Soil		31.2	112.1	16.4	510	1.0	96.0	5.1	90	2.10	55.0	2.3	1.4	58	6.6	9.6	0.2	189	0.45	0.111	7
1280524	Soil		26.6	52.2	28.3	271	1.0	51.0	7.0	205	2.10	35.4	4.3	0.7	35	3.2	6.5	0.3	150	0.30	0.102	5
1280525	Soil		28.0	23.1	33.9	197	0.4	41.6	4.3	76	1.81	12.4	3.7	0.7	17	2.3	6.1	0.2	44	0.15	0.056	4
1280526	Soil		10.6	23.2	12.1	119	<0.1	25.1	4.4	88	1.77	18.8	0.9	0.9	11	0.8	3.3	0.3	47	0.05	0.035	8
1280527	Soil		0.4	11.1	2.3	70	0.2	29.7	0.8	23	0.29	0.7	1.2	0.1	26	2.1	0.9	<0.1	6	0.38	0.029	1
1280528	Soil		10.3	20.2	13.3	119	0.6	28.2	8.6	343	1.53	13.9	3.4	0.8	29	1.4	3.1	0.2	41	0.27	0.072	4
1280529	Soil		22.5	33.6	29.4	234	0.5	48.9	20.8	1021	3.20	30.2	3.7	2.1	45	1.8	6.2	0.3	85	0.35	0.113	8
1280530	Soil		13.4	33.3	20.8	197	0.4	44.3	15.5	441	2.66	20.6	3.0	1.9	34	2.2	4.3	0.3	69	0.22	0.103	8
1280531	Soil		9.9	35.1	19.6	168	0.7	44.3	6.5	142	2.19	15.9	2.7	1.7	38	2.0	3.3	0.3	61	0.34	0.098	7
1280532	Soil		6.3	17.8	17.5	48	0.2	12.5	2.4	71	1.25	8.2	1.1	<0.1	21	0.3	1.4	0.2	56	0.02	0.113	8
1280533	Soil		2.1	5.1	3.1	16	<0.1	4.2	0.8	17	0.34	2.5	1.0	<0.1	6	<0.1	0.5	<0.1	16	0.02	0.040	2
1280534	Soil		11.2	17.6	11.5	94	0.1	25.4	3.9	57	1.39	12.2	1.9	<0.1	15	0.2	2.6	0.2	66	0.04	0.091	8
1280535	Soil		22.7	32.5	14.9	199	0.6	60.8	7.3	166	2.06	19.2	2.3	0.4	27	1.1	4.7	0.2	96	0.14	0.110	8
1280536	Soil		8.8	16.6	7.2	95	1.0	26.7	7.4	400	1.17	7.6	2.7	0.2	20	0.5	1.9	0.1	46	0.13	0.094	5
1280537	Soil		16.9	22.2	11.8	130	0.5	38.6	4.4	77	1.62	14.0	2.2	0.2	18	0.7	3.2	0.1	73	0.16	0.098	6
1280538	Soil		21.6	40.3	20.1	257	0.7	74.6	11.8	296	2.82	23.5	3.7	1.5	58	1.1	5.6	0.2	96	0.58	0.164	9
1280539	Soil		30.2	21.3	15.0	203	0.3	54.8	5.5	113	2.11	17.4	0.7	0.2	12	0.3	5.0	0.2	113	0.03	0.063	10
1280540	Soil		18.0	27.0	16.8	205	0.5	50.1	9.1	214	2.25	14.6	2.2	1.4	25	0.7	3.7	0.2	73	0.20	0.095	9
1280541	Soil		10.4	23.4	12.8	135	0.1	36.6	10.4	278	1.83	14.1	<0.5	0.8	18	0.4	2.8	0.2	49	0.18	0.054	6
1280542	Soil		5.4	28.9	15.5	91	0.7	38.5	6.1	192	1.62	8.3	1.7	1.0	41	0.8	1.5	0.2	49	0.66	0.090	6
1280543	Soil		25.0	36.6	15.5	272	0.6	68.3	12.5	394	2.24	18.5	2.1	2.3	47	1.1	5.5	0.2	77	0.48	0.126	11
1280544	Soil		4.4	29.2	10.9	73	0.5	32.4	18.3	764	1.42	7.0	2.3	0.8	31	0.5	1.5	0.2	44	0.53	0.085	5
1280545	Soil		5.0	28.5	10.7	51	0.3	19.0	5.0	160	1.18	5.4	<0.5	0.1	13	0.6	1.2	0.1	48	0.07	0.069	7
1280546	Soil		6.2	16.2	7.2	62	0.3	14.0	3.5	53	1.01	7.1	<0.5	0.1	6	0.2	1.4	0.1	42	0.01	0.034	6
1280547	Soil		18.3	51.5	46.6	227	1.1	53.3	7.1	120	2.48	19.8	5.3	0.3	25	1.0	5.1	0.3	63	0.11	0.084	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280518	Soil	14	0.14	596	0.003	2	0.61	0.005	0.06	<0.1	0.04	2.3	0.2	<0.05	2	0.7	<0.2
1280519	Soil	4	0.01	96	0.003	1	0.22	0.006	0.03	<0.1	0.02	0.3	0.1	<0.05	2	<0.5	<0.2
1280520	Soil	8	0.05	122	0.007	1	0.32	0.004	0.03	0.1	0.02	0.5	0.1	<0.05	3	0.6	<0.2
1280521	Soil	6	0.05	239	0.003	<1	0.43	0.018	0.04	<0.1	0.10	0.3	0.1	<0.05	2	<0.5	<0.2
1280522	Soil	14	0.04	547	0.004	1	0.53	0.005	0.06	<0.1	0.09	2.2	0.2	<0.05	2	2.0	<0.2
1280523	Soil	16	0.13	810	0.003	1	0.58	0.005	0.06	0.1	0.67	3.1	0.9	<0.05	2	3.5	<0.2
1280524	Soil	15	0.10	792	0.002	2	0.66	0.009	0.07	0.1	0.55	2.1	0.6	<0.05	2	2.7	<0.2
1280525	Soil	9	0.04	525	0.001	4	0.41	0.006	0.06	<0.1	0.20	1.0	0.3	<0.05	1	3.1	<0.2
1280526	Soil	10	0.04	203	0.004	2	0.34	0.002	0.06	0.1	0.02	1.5	0.1	<0.05	2	1.1	<0.2
1280527	Soil	2	0.04	255	0.008	<1	0.20	0.036	0.03	<0.1	0.14	0.7	<0.1	<0.05	<1	1.5	<0.2
1280528	Soil	11	0.13	677	0.003	2	0.57	0.014	0.05	<0.1	0.22	1.5	0.2	<0.05	2	1.7	<0.2
1280529	Soil	20	0.24	1399	0.003	2	0.99	0.006	0.09	0.2	0.31	2.6	0.3	<0.05	3	3.1	<0.2
1280530	Soil	20	0.21	1301	0.003	2	1.09	0.007	0.09	<0.1	0.26	2.7	0.3	<0.05	3	2.3	<0.2
1280531	Soil	20	0.26	1015	0.002	2	1.07	0.008	0.09	<0.1	0.28	2.5	0.3	<0.05	3	2.5	<0.2
1280532	Soil	11	0.04	201	0.002	<1	0.72	0.005	0.06	<0.1	0.02	0.2	0.3	<0.05	4	0.6	<0.2
1280533	Soil	3	0.01	27	0.003	<1	0.18	0.019	0.03	<0.1	<0.01	0.1	<0.1	<0.05	1	<0.5	<0.2
1280534	Soil	11	0.03	131	0.003	2	0.40	0.006	0.06	0.1	0.01	0.3	0.2	<0.05	3	0.9	<0.2
1280535	Soil	21	0.06	511	0.002	3	0.50	0.006	0.07	0.1	0.12	1.3	0.3	<0.05	2	1.6	<0.2
1280536	Soil	11	0.05	464	0.003	1	0.59	0.018	0.04	<0.1	0.10	0.9	0.2	<0.05	2	0.7	<0.2
1280537	Soil	13	0.05	356	0.003	2	0.48	0.008	0.04	0.1	0.09	0.4	0.2	<0.05	2	1.1	<0.2
1280538	Soil	24	0.12	838	0.003	4	0.72	0.006	0.06	0.2	0.19	3.0	0.3	<0.05	2	1.9	<0.2
1280539	Soil	15	0.05	153	0.005	2	0.50	0.003	0.05	0.1	0.04	0.5	0.3	<0.05	3	1.3	<0.2
1280540	Soil	20	0.13	353	0.003	1	0.86	0.008	0.05	0.1	0.18	2.9	0.3	<0.05	3	1.3	<0.2
1280541	Soil	13	0.07	201	0.002	<1	0.48	0.007	0.05	<0.1	0.03	2.5	0.2	<0.05	2	1.1	<0.2
1280542	Soil	20	0.12	431	0.002	1	0.80	0.011	0.04	<0.1	0.27	3.5	0.3	0.07	2	1.5	<0.2
1280543	Soil	16	0.13	285	0.005	3	0.55	0.005	0.06	0.1	0.15	3.4	0.3	<0.05	2	2.2	<0.2
1280544	Soil	14	0.14	680	0.003	2	0.79	0.015	0.04	<0.1	0.13	3.2	0.2	0.07	2	1.0	<0.2
1280545	Soil	13	0.03	238	0.003	2	0.73	0.011	0.04	<0.1	0.05	0.5	0.2	<0.05	3	0.7	<0.2
1280546	Soil	6	0.02	66	0.004	2	0.32	0.007	0.03	<0.1	0.01	0.5	0.1	<0.05	2	0.6	<0.2
1280547	Soil	14	0.06	388	0.002	1	0.68	0.005	0.07	0.1	0.40	2.1	0.5	0.05	2	2.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280548	Soil		5.2	29.9	9.4	111	0.1	19.3	6.6	125	2.18	11.2	<0.5	0.2	6	0.2	2.5	0.2	72	0.01	0.043	7
1280549	Soil		4.5	16.2	5.3	56	0.6	14.1	3.9	72	1.14	4.9	<0.5	0.1	5	0.2	1.4	0.1	45	0.02	0.026	4
1280550	Soil		10.0	28.7	18.6	129	0.2	35.1	8.1	136	2.59	18.3	<0.5	0.3	11	0.3	3.3	0.2	65	0.02	0.063	7
1280561	Soil		9.0	48.6	13.8	326	0.6	65.5	6.1	132	1.76	16.2	2.8	2.2	64	4.7	4.8	0.2	102	1.07	0.103	9
1280562	Soil		22.3	47.6	14.6	422	0.5	79.0	10.8	226	2.45	26.2	1.0	2.5	40	2.8	5.5	0.2	109	0.27	0.102	13
1280563	Soil		18.5	42.8	14.3	384	0.8	72.8	9.1	318	2.26	23.5	1.3	2.1	69	3.1	5.1	0.2	123	1.09	0.105	9
1280564	Soil		19.0	42.9	12.7	365	0.8	70.5	6.9	180	1.96	19.7	1.0	2.7	71	3.3	4.6	0.2	140	1.16	0.110	10
1280565	Soil		25.8	50.0	13.3	525	0.8	110.4	8.2	230	2.20	28.4	1.8	3.0	69	5.1	7.0	0.2	183	1.16	0.105	12
1280566	Soil		13.0	35.8	8.6	200	0.3	76.4	4.7	194	1.13	12.1	0.9	0.7	76	2.6	3.2	0.1	75	1.87	0.075	8
1280567	Soil		28.6	46.7	11.1	227	0.4	100.7	5.6	168	1.47	16.1	2.1	1.0	72	2.6	3.8	0.1	94	1.68	0.085	11
1280568	Soil		37.8	45.1	18.1	557	0.5	106.2	9.9	271	3.02	32.5	1.3	2.7	45	2.5	8.0	0.2	303	1.38	0.048	15
1280569	Soil		25.7	34.3	9.9	278	0.3	79.2	6.3	263	1.56	15.3	<0.5	1.6	53	2.7	4.7	0.1	158	2.83	0.056	18
1280570	Soil		23.8	28.2	8.8	392	0.3	32.2	1.8	39	0.53	21.3	<0.5	0.9	25	5.2	14.2	0.1	523	0.38	0.029	12
1280581	Soil		5.5	77.2	11.0	155	0.2	22.4	7.7	123	2.67	12.8	2.4	0.3	10	0.7	3.2	0.2	35	0.03	0.150	9
1280582	Soil		8.4	43.0	19.1	107	0.2	31.1	10.7	312	3.56	18.2	4.6	0.5	11	0.2	2.5	0.2	21	0.03	0.122	11
1280583	Soil		4.3	69.7	14.1	113	0.2	23.2	7.9	99	3.11	14.3	4.5	0.3	14	0.2	2.3	0.3	36	0.03	0.203	10
1280584	Soil		3.6	88.6	8.0	218	0.2	34.8	6.5	132	2.16	45.8	5.4	0.2	8	0.7	8.4	0.2	29	0.03	0.118	6
1280585	Soil		3.5	117.4	21.6	204	0.7	57.0	12.8	312	4.25	102.1	12.3	0.8	29	0.7	15.0	0.3	41	0.04	0.099	13
1280586	Soil		2.6	65.7	16.9	86	0.2	24.8	13.7	238	3.29	14.8	13.9	0.4	10	0.1	2.2	0.3	31	0.03	0.137	12
1280587	Soil		5.5	50.3	19.2	135	0.2	29.0	6.0	129	2.77	12.9	3.5	0.4	46	0.5	3.0	0.3	48	0.07	0.180	12
1280588	Soil		11.4	113.6	32.6	716	0.6	91.3	21.0	488	6.42	31.8	9.0	1.3	37	2.6	6.6	0.3	43	0.04	0.161	16
1280589	Soil		1.6	14.7	5.5	58	0.2	10.3	2.4	163	0.87	3.1	0.7	0.2	17	0.3	0.8	<0.1	17	0.04	0.136	4
1280590	Soil		12.0	85.0	39.7	473	0.6	98.5	34.2	1670	7.56	34.9	4.3	1.3	62	2.6	4.7	0.4	38	0.08	0.216	12
1280591	Soil		5.1	21.6	17.1	91	0.3	19.1	3.7	371	1.44	14.5	<0.5	0.1	19	0.2	2.6	0.2	35	0.03	0.083	6
1280592	Soil		5.5	40.0	12.2	113	0.4	31.9	7.8	182	3.10	19.2	1.1	0.2	11	0.2	2.2	0.3	31	0.01	0.073	4
1280593	Soil		6.4	37.1	15.2	180	0.2	34.0	7.8	249	2.91	18.8	1.2	0.3	15	0.2	3.3	0.3	79	0.02	0.086	11
1280594	Soil		6.4	33.7	12.4	136	0.9	26.3	3.5	90	1.83	18.9	4.1	0.4	25	0.6	2.8	0.2	104	0.03	0.103	6
1280595	Soil		32.1	130.0	24.3	499	0.4	74.5	8.6	131	2.86	46.2	4.6	0.3	17	1.2	11.3	0.3	132	0.07	0.097	24
1280596	Soil		27.1	160.1	29.5	832	1.4	134.4	19.2	505	4.98	50.1	9.3	3.7	86	9.7	17.1	0.4	258	0.35	0.251	24
1280597	Soil		22.0	43.3	22.0	284	0.2	58.1	5.3	98	3.37	38.2	0.7	0.3	12	0.5	9.7	0.4	300	0.02	0.185	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280548	Soil	11	0.03	60	0.005	1	0.42	0.006	0.03	0.1	0.02	0.8	0.1	<0.05	5	1.1	<0.2
1280549	Soil	8	0.02	60	0.004	<1	0.38	0.013	0.03	0.1	0.02	0.6	<0.1	<0.05	3	0.8	<0.2
1280550	Soil	12	0.04	91	0.004	<1	0.43	0.003	0.05	<0.1	0.02	1.7	0.2	<0.05	3	1.6	<0.2
1280561	Soil	19	0.23	1040	0.002	4	0.94	0.006	0.08	0.1	0.40	3.2	0.4	0.09	2	2.5	<0.2
1280562	Soil	19	0.18	837	0.003	3	0.87	0.004	0.08	0.1	0.35	3.0	0.4	<0.05	2	2.1	<0.2
1280563	Soil	22	0.24	889	0.003	6	0.94	0.009	0.13	0.1	0.38	3.2	0.4	<0.05	2	2.3	<0.2
1280564	Soil	24	0.23	831	0.003	5	0.89	0.005	0.11	0.1	0.48	3.8	0.5	0.05	2	2.2	<0.2
1280565	Soil	25	0.25	515	0.004	6	0.84	0.008	0.12	0.2	0.34	4.0	1.1	<0.05	2	1.9	<0.2
1280566	Soil	14	0.20	372	0.005	5	0.62	0.015	0.07	0.1	0.32	1.9	0.7	0.08	2	2.3	<0.2
1280567	Soil	17	0.31	416	0.006	4	0.59	0.010	0.07	0.2	0.29	3.0	1.0	0.06	2	2.3	<0.2
1280568	Soil	36	0.68	797	0.002	5	1.45	0.006	0.11	0.1	0.23	4.2	1.3	<0.05	3	3.4	<0.2
1280569	Soil	24	1.34	472	0.003	6	0.75	0.010	0.09	0.1	0.31	3.8	1.2	<0.05	2	1.5	<0.2
1280570	Soil	30	0.11	274	0.006	4	0.59	0.012	0.11	0.1	0.23	1.1	1.5	<0.05	2	1.7	<0.2
1280581	Soil	7	0.04	121	0.003	2	0.57	0.011	0.09	<0.1	0.06	0.7	0.2	0.08	2	1.9	<0.2
1280582	Soil	6	0.06	90	0.004	3	0.66	0.008	0.09	<0.1	0.09	1.1	0.2	0.05	2	1.7	<0.2
1280583	Soil	10	0.05	145	0.005	4	0.67	0.010	0.13	<0.1	0.05	0.8	0.2	0.06	2	1.2	<0.2
1280584	Soil	7	0.02	72	0.004	2	0.34	0.014	0.07	<0.1	0.04	0.5	<0.1	0.09	2	1.2	<0.2
1280585	Soil	18	0.13	114	0.009	3	0.77	0.006	0.08	0.1	0.12	4.1	0.2	0.08	3	2.6	<0.2
1280586	Soil	9	0.09	128	0.004	3	0.75	0.013	0.10	<0.1	0.03	1.1	0.2	0.05	2	1.6	<0.2
1280587	Soil	11	0.05	309	0.004	2	0.68	0.005	0.08	<0.1	0.03	0.7	0.1	0.10	2	1.7	<0.2
1280588	Soil	10	0.09	524	0.005	2	1.07	0.006	0.11	<0.1	0.12	2.5	0.3	<0.05	2	3.0	<0.2
1280589	Soil	4	0.02	166	0.004	2	0.50	0.022	0.05	<0.1	0.05	0.3	<0.1	0.07	2	0.6	<0.2
1280590	Soil	10	0.09	900	0.005	4	1.21	0.007	0.14	<0.1	0.11	4.1	0.3	0.14	2	3.5	<0.2
1280591	Soil	8	0.03	318	0.002	2	0.26	0.013	0.07	<0.1	0.05	0.2	0.1	0.08	1	0.9	<0.2
1280592	Soil	7	0.04	494	0.005	3	0.51	0.016	0.08	<0.1	0.05	0.8	0.2	0.08	3	0.8	<0.2
1280593	Soil	12	0.03	254	0.003	3	0.49	0.005	0.08	<0.1	0.03	1.1	0.2	<0.05	2	1.4	<0.2
1280594	Soil	17	0.06	384	0.003	2	0.78	0.013	0.06	<0.1	0.16	1.3	0.3	<0.05	3	1.7	<0.2
1280595	Soil	18	0.03	429	0.005	3	0.43	0.005	0.09	<0.1	0.03	0.7	0.4	<0.05	3	5.1	0.2
1280596	Soil	32	0.06	3162	0.006	5	0.53	0.002	0.11	0.2	0.61	4.4	0.8	<0.05	2	7.5	0.3
1280597	Soil	30	0.04	470	0.006	2	0.61	0.004	0.06	0.1	0.04	0.3	0.5	<0.05	4	4.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280598	Soil	15.2	56.2	18.6	341	0.6	69.3	10.6	372	3.74	33.6	3.2	0.8	27	1.1	9.4	0.3	198	0.10	0.248	19
1280599	Soil	21.1	42.1	19.5	228	0.4	45.4	4.3	128	3.67	34.0	2.1	0.4	13	0.5	8.9	0.3	255	0.04	0.194	19
1280600	Soil	11.3	13.6	6.2	105	0.5	14.7	2.1	80	2.39	8.6	<0.5	0.2	5	0.3	3.0	0.2	121	0.02	0.074	7
1280601	Soil	8.0	89.1	23.3	201	0.9	54.9	17.9	421	4.44	16.9	6.3	0.5	17	0.6	3.4	0.3	58	0.06	0.092	7
1280602	Soil	4.6	31.9	12.0	111	0.4	25.5	6.8	371	2.84	11.2	1.9	0.3	19	0.5	2.4	0.3	70	0.11	0.115	9
1280603	Soil	6.8	104.1	40.3	219	0.5	90.9	48.6	3085	11.07	16.8	5.0	4.3	14	0.8	3.0	0.7	42	0.02	0.107	16
1280604	Soil	22.0	37.4	27.0	179	1.6	36.6	3.0	53	2.13	26.7	0.7	0.2	49	0.3	11.1	0.3	354	0.03	0.113	17
1280605	Soil	4.1	40.4	14.2	141	0.4	27.4	5.5	124	2.62	18.6	1.8	1.4	7	0.4	2.4	0.3	40	0.01	0.087	13
1280606	Soil	19.3	161.1	18.5	1308	7.1	233.0	10.1	283	3.11	43.5	5.0	1.0	90	11.9	13.5	0.3	320	0.67	0.363	24
1280607	Soil	18.2	146.1	17.9	1070	5.6	219.3	8.6	173	3.21	42.4	2.8	1.0	50	6.3	15.0	0.3	213	0.41	0.280	26
1280608	Soil	22.9	113.1	17.3	694	2.7	133.3	8.8	152	3.33	40.6	3.0	1.2	80	3.4	13.3	0.3	333	0.38	0.532	21
1280609	Soil	35.3	106.4	13.6	617	1.8	107.2	7.1	267	2.60	41.5	3.2	1.3	38	5.9	18.2	0.2	665	0.17	0.312	26
1280610	Soil	11.4	39.3	17.3	311	0.6	50.3	9.5	529	5.74	14.3	2.8	1.5	15	1.1	4.7	0.3	158	0.04	0.132	26
1280611	Soil	74.8	233.0	16.2	539	15.3	139.6	3.8	114	2.94	67.8	4.9	0.8	84	3.4	20.6	0.3	2125	0.17	0.312	43
1280612	Soil	159.6	283.3	29.6	604	20.8	140.2	2.7	63	3.84	116.4	3.8	7.0	128	3.5	57.5	0.4	5670	0.15	0.348	52
1280613	Soil	19.3	52.2	13.2	633	3.0	124.9	5.1	82	1.69	13.7	0.9	0.2	43	4.2	8.4	0.2	885	0.28	0.189	24
1280614	Soil	34.9	65.3	25.9	411	1.4	93.7	12.0	188	5.90	43.4	3.7	1.2	36	0.9	12.8	0.4	453	0.06	0.526	18
1280615	Soil	18.5	61.8	14.6	191	2.7	41.7	6.1	157	2.57	28.6	4.2	0.1	45	1.4	8.7	0.2	257	0.07	0.306	9
1280616	Soil	26.7	50.8	19.4	223	1.7	50.4	8.2	193	2.53	37.2	3.4	0.3	59	1.0	13.9	0.3	564	0.09	0.293	13
1280617	Soil	21.5	65.1	15.3	159	2.8	35.8	2.5	61	1.70	27.6	4.1	0.4	61	2.2	10.7	0.2	878	0.08	0.220	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280598	Soil	29	0.07	378	0.005	3	0.76	0.005	0.06	0.1	0.10	1.0	0.4	<0.05	3	3.7	<0.2
1280599	Soil	24	0.04	607	0.005	3	0.53	0.003	0.07	0.2	0.08	0.4	0.4	<0.05	3	3.4	<0.2
1280600	Soil	9	0.04	442	0.004	2	0.51	0.009	0.04	<0.1	0.04	0.5	0.5	<0.05	3	1.0	<0.2
1280601	Soil	12	0.10	465	0.005	2	0.68	0.014	0.07	<0.1	0.16	2.6	0.4	<0.05	2	2.2	<0.2
1280602	Soil	15	0.14	1897	0.007	2	1.09	0.017	0.06	<0.1	0.06	1.2	0.2	<0.05	3	1.7	<0.2
1280603	Soil	11	0.07	1963	0.003	3	0.87	0.003	0.10	0.1	0.15	10.8	0.3	<0.05	1	1.9	0.2
1280604	Soil	29	0.02	1616	0.005	3	0.32	0.007	0.08	0.3	0.08	0.4	0.6	0.11	3	7.1	0.2
1280605	Soil	10	0.04	239	0.002	4	0.60	0.003	0.08	<0.1	0.08	1.8	0.1	<0.05	2	1.4	<0.2
1280606	Soil	94	0.29	2340	0.006	6	0.87	0.006	0.12	0.2	0.83	2.6	0.8	<0.05	3	12.8	0.3
1280607	Soil	85	0.09	2229	0.004	4	0.61	0.004	0.09	0.3	0.69	2.3	0.5	<0.05	2	10.9	0.3
1280608	Soil	82	0.10	2669	0.006	4	0.99	0.005	0.10	0.3	0.44	2.1	0.7	0.06	3	11.5	0.3
1280609	Soil	66	0.11	3209	0.007	5	1.00	0.004	0.10	0.3	0.33	1.4	1.1	<0.05	4	7.4	0.2
1280610	Soil	31	0.07	2470	0.004	3	0.84	0.002	0.07	0.1	0.10	2.0	0.4	<0.05	2	2.9	<0.2
1280611	Soil	436	0.49	948	0.070	11	1.76	0.004	0.18	0.4	1.17	4.2	1.2	0.20	11	28.0	0.5
1280612	Soil	469	0.73	426	0.136	33	1.83	0.006	0.34	1.2	2.21	12.7	2.5	0.34	15	59.3	0.6
1280613	Soil	102	0.13	1438	0.017	7	0.71	0.009	0.12	0.2	0.19	1.2	1.0	0.07	5	11.6	<0.2
1280614	Soil	50	0.06	1554	0.008	4	1.05	0.003	0.09	0.2	0.21	1.2	0.6	0.09	4	9.6	0.3
1280615	Soil	33	0.04	1278	0.003	3	0.93	0.010	0.07	0.1	0.35	0.3	0.6	0.17	2	6.7	<0.2
1280616	Soil	64	0.05	1883	0.011	3	0.76	0.006	0.08	0.2	0.13	0.5	1.0	0.10	5	10.2	<0.2
1280617	Soil	78	0.10	1281	0.007	3	1.05	0.013	0.09	0.2	0.35	0.7	1.2	0.10	5	8.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

QUALITY CONTROL REPORT WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1280180	Soil	19.9	41.2	15.3	383	0.5	99.7	10.6	96	3.09	28.9	<0.5	0.3	18	0.3	7.9	0.2	104	0.04	0.187	12
REP 1280180	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280196	Soil	1.6	32.9	23.3	113	<0.1	29.3	18.4	659	3.25	15.6	<0.5	1.0	16	0.1	1.0	0.4	26	0.08	0.081	7
REP 1280196	QC	1.4	34.4	24.1	119	<0.1	31.0	19.2	688	3.42	17.7	<0.5	1.0	17	0.1	1.1	0.4	27	0.09	0.079	7
1280217	Soil	8.3	33.2	57.7	74	1.4	19.2	4.0	122	2.46	36.6	3.3	0.4	116	0.2	5.3	0.3	72	0.06	0.150	10
REP 1280217	QC	7.6	32.9	60.3	73	1.3	19.7	3.9	120	2.38	36.6	1.1	0.4	120	0.1	5.3	0.3	71	0.06	0.153	11
1280281	Soil	5.1	92.7	34.6	48	1.0	41.1	10.9	373	4.18	118.5	3.0	0.4	46	0.2	4.0	0.4	69	0.02	0.148	5
REP 1280281	QC	5.0	94.1	35.2	48	1.0	40.7	11.0	376	4.17	120.2	2.8	0.4	46	0.3	4.0	0.5	69	0.02	0.148	5
1280293	Soil	48.7	52.4	14.8	260	1.1	97.8	5.4	186	1.91	21.0	6.9	0.9	55	3.0	7.3	0.2	93	0.47	0.079	7
REP 1280293	QC	49.1	51.3	15.2	254	1.1	93.3	5.4	187	1.87	21.3	6.0	0.7	53	3.0	7.1	0.2	93	0.47	0.078	8
1280361	Soil	4.5	26.6	16.1	114	0.2	25.3	8.4	197	2.56	16.1	4.0	1.2	37	0.2	2.1	0.2	36	0.04	0.068	6
REP 1280361	QC	4.5	26.6	17.1	111	0.2	23.6	8.1	193	2.57	16.0	2.5	1.2	38	0.3	2.0	0.2	37	0.05	0.072	7
1280388	Soil	10.9	20.9	12.4	125	0.5	27.1	3.7	60	1.70	18.4	1.6	1.5	17	0.8	2.9	0.2	83	0.04	0.043	11
REP 1280388	QC	11.0	20.6	11.9	126	0.5	27.9	3.9	63	1.71	18.7	1.3	1.4	17	0.7	3.1	0.2	82	0.04	0.045	11
1280396	Soil	18.6	34.2	20.7	251	0.3	57.2	8.9	282	3.47	54.3	2.8	0.3	20	1.4	7.1	0.3	152	0.06	0.101	14
REP 1280396	QC	17.5	33.0	20.1	242	0.3	55.9	8.6	274	3.42	53.3	3.0	0.3	19	1.5	7.1	0.3	152	0.05	0.102	14
1280427	Soil	53.2	47.1	8.3	436	0.7	104.1	4.3	126	1.33	52.6	2.3	0.4	57	4.7	14.4	0.2	140	0.66	0.111	8
REP 1280427	QC	53.0	47.3	8.2	421	0.7	105.9	4.2	129	1.33	52.1	2.2	0.5	59	4.9	14.4	0.2	140	0.67	0.107	8
1280449	Soil	5.5	11.7	16.1	43	0.4	14.5	1.7	226	0.73	7.4	1.1	<0.1	20	0.2	1.9	<0.1	26	0.05	0.130	5
REP 1280449	QC	5.2	11.0	15.5	41	0.4	13.8	1.7	223	0.70	7.7	0.8	0.1	19	0.1	1.8	<0.1	27	0.05	0.124	5
1280465	Soil	42.5	26.3	11.1	148	<0.1	57.9	4.6	120	1.67	14.2	1.6	0.2	10	0.8	3.5	<0.1	51	0.09	0.065	3
REP 1280465	QC	40.8	25.8	11.1	141	<0.1	56.3	4.5	117	1.61	13.4	0.6	0.2	10	0.8	3.3	<0.1	50	0.08	0.062	3
1280479	Soil	5.9	7.3	4.1	26	0.2	6.2	1.1	14	0.49	7.4	0.7	0.2	9	<0.1	1.4	<0.1	36	<0.01	0.022	12
REP 1280479	QC	5.9	6.8	4.3	25	0.2	6.4	1.1	13	0.49	7.1	<0.5	0.2	9	<0.1	1.5	<0.1	36	<0.01	0.024	13
1280494	Soil	9.7	22.8	16.9	105	0.3	31.3	7.5	129	2.69	15.9	1.0	0.3	10	0.4	2.4	0.2	52	0.02	0.077	6
REP 1280494	QC	9.5	22.9	17.0	108	0.3	31.3	7.2	128	2.65	15.7	1.2	0.2	9	0.3	2.2	0.2	50	0.02	0.076	6
1280517	Soil	4.3	21.4	13.7	67	0.2	23.5	6.2	112	1.85	9.4	1.6	0.5	18	0.2	1.4	0.2	32	0.19	0.056	5
REP 1280517	QC	4.3	21.1	14.4	67	0.2	22.2	6.0	107	1.81	9.5	1.8	0.5	18	0.2	1.4	0.2	32	0.19	0.052	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

QUALITY CONTROL REPORT WHI11001218.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1280180	Soil	20	0.04	767	0.006	1	0.70	0.008	0.06	0.1	0.06	0.6	0.4	<0.05	3	3.5	<0.2
REP 1280180	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280196	Soil	14	0.15	83	0.002	3	0.74	0.004	0.06	<0.1	0.03	3.8	0.1	<0.05	2	2.2	<0.2
REP 1280196	QC	15	0.15	87	0.003	<1	0.76	0.003	0.06	<0.1	0.04	4.0	0.1	<0.05	2	<0.5	<0.2
1280217	Soil	21	0.09	303	0.014	2	0.69	0.008	0.08	0.2	0.07	1.0	0.4	0.09	4	<0.5	<0.2
REP 1280217	QC	21	0.08	301	0.013	2	0.68	0.008	0.08	0.2	0.07	1.4	0.3	0.08	4	<0.5	<0.2
1280281	Soil	20	0.04	152	0.003	1	0.65	0.004	0.09	<0.1	0.02	2.6	0.2	<0.05	2	<0.5	<0.2
REP 1280281	QC	21	0.04	161	0.004	2	0.67	0.005	0.09	<0.1	0.03	2.8	0.2	0.05	3	<0.5	<0.2
1280293	Soil	11	0.07	1005	0.003	3	0.39	0.010	0.07	0.2	0.30	2.4	0.6	0.08	1	2.5	<0.2
REP 1280293	QC	12	0.07	1032	0.003	2	0.39	0.010	0.07	0.1	0.27	2.4	0.6	0.06	1	2.5	<0.2
1280361	Soil	15	0.17	1191	0.002	1	0.69	0.004	0.07	<0.1	0.07	1.9	0.2	0.07	2	1.4	<0.2
REP 1280361	QC	16	0.18	1300	0.003	1	0.69	0.005	0.07	0.1	0.07	2.0	0.3	0.08	2	1.2	<0.2
1280388	Soil	13	0.07	423	0.005	2	0.72	0.006	0.05	0.2	0.08	1.4	0.3	<0.05	3	1.2	<0.2
REP 1280388	QC	13	0.07	422	0.004	1	0.71	0.006	0.05	0.1	0.10	1.6	0.2	<0.05	3	1.2	<0.2
1280396	Soil	45	0.20	187	0.010	2	1.02	0.004	0.08	0.1	0.06	0.7	0.6	<0.05	4	3.0	<0.2
REP 1280396	QC	45	0.19	192	0.011	2	1.00	0.004	0.08	0.1	0.06	0.8	0.5	<0.05	4	2.9	<0.2
1280427	Soil	14	0.11	676	0.004	3	0.49	0.016	0.04	0.2	0.83	1.5	0.7	0.07	1	2.5	<0.2
REP 1280427	QC	13	0.11	674	0.004	3	0.49	0.015	0.04	0.2	0.83	1.5	0.7	0.06	1	2.6	<0.2
1280449	Soil	14	0.02	106	0.002	<1	0.39	0.013	0.04	<0.1	0.05	0.2	<0.1	<0.05	2	1.1	<0.2
REP 1280449	QC	13	0.02	103	0.002	<1	0.39	0.013	0.04	<0.1	0.04	0.2	<0.1	<0.05	2	1.0	<0.2
1280465	Soil	15	0.02	171	0.002	<1	0.42	0.008	0.02	<0.1	0.04	0.8	0.4	<0.05	1	1.3	<0.2
REP 1280465	QC	15	0.02	157	0.001	<1	0.40	0.006	0.02	<0.1	0.04	0.8	0.4	<0.05	1	1.1	<0.2
1280479	Soil	4	<0.01	276	0.005	1	0.16	0.003	0.03	<0.1	0.01	0.2	0.2	<0.05	2	0.7	<0.2
REP 1280479	QC	5	<0.01	273	0.006	2	0.17	0.003	0.03	<0.1	0.01	0.2	0.2	0.06	1	<0.5	<0.2
1280494	Soil	16	0.08	123	0.006	1	0.58	0.006	0.05	0.1	0.03	1.1	0.2	<0.05	3	0.9	<0.2
REP 1280494	QC	15	0.08	121	0.006	<1	0.56	0.005	0.04	<0.1	0.02	1.3	0.2	<0.05	2	1.0	<0.2
1280517	Soil	13	0.08	334	0.003	<1	0.62	0.009	0.03	<0.1	0.05	2.4	0.1	<0.05	2	0.7	<0.2
REP 1280517	QC	12	0.08	326	0.004	1	0.59	0.009	0.03	<0.1	0.05	2.4	0.1	<0.05	2	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

QUALITY CONTROL REPORT WHI11001218.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1280531	Soil	9.9	35.1	19.6	168	0.7	44.3	6.5	142	2.19	15.9	2.7	1.7	38	2.0	3.3	0.3	61	0.34	0.098	7
REP 1280531	QC	9.9	35.6	19.5	174	0.6	45.5	6.8	143	2.23	16.1	1.9	1.7	38	2.1	3.3	0.3	61	0.34	0.099	7
1280562	Soil	22.3	47.6	14.6	422	0.5	79.0	10.8	226	2.45	26.2	1.0	2.5	40	2.8	5.5	0.2	109	0.27	0.102	13
REP 1280562	QC	21.7	46.1	14.0	411	0.6	75.5	10.4	218	2.42	24.5	1.6	2.6	39	2.8	5.3	0.2	108	0.27	0.098	13
1280586	Soil	2.6	65.7	16.9	86	0.2	24.8	13.7	238	3.29	14.8	13.9	0.4	10	0.1	2.2	0.3	31	0.03	0.137	12
REP 1280586	QC	2.9	62.9	16.6	83	0.2	23.2	13.3	230	3.18	13.7	13.0	0.3	11	0.2	2.1	0.3	31	0.03	0.126	11
1280605	Soil	4.1	40.4	14.2	141	0.4	27.4	5.5	124	2.62	18.6	1.8	1.4	7	0.4	2.4	0.3	40	0.01	0.087	13
REP 1280605	QC	4.1	40.9	14.9	140	0.4	28.1	5.6	123	2.65	18.8	1.5	1.6	8	0.3	2.3	0.3	41	0.01	0.086	13
Reference Materials																					
STD DS8	Standard	13.3	110.5	128.5	320	1.8	38.5	7.8	617	2.48	24.8	110.2	6.9	77	2.4	5.9	6.6	42	0.72	0.079	16
STD DS8	Standard	13.3	107.6	127.9	307	1.7	38.1	7.7	609	2.45	25.4	107.3	7.0	78	2.6	5.9	6.7	42	0.73	0.079	16
STD DS8	Standard	13.8	108.7	130.2	306	1.8	39.0	7.6	617	2.45	25.2	119.2	7.3	70	2.5	5.8	6.8	48	0.69	0.075	17
STD DS8	Standard	13.8	102.0	125.3	315	1.7	36.1	7.3	642	2.55	25.0	110.2	7.1	76	2.5	5.7	6.9	43	0.74	0.077	17
STD DS8	Standard	13.1	105.0	125.2	311	1.7	37.1	7.0	611	2.50	24.2	107.3	6.8	73	2.2	5.6	6.7	41	0.74	0.080	16
STD DS8	Standard	13.0	109.9	127.4	319	1.8	39.1	7.7	620	2.51	24.3	110.3	6.3	65	2.2	5.8	6.5	43	0.68	0.079	14
STD DS8	Standard	12.2	103.4	119.7	300	1.8	36.5	6.9	581	2.34	23.7	107.8	5.7	66	2.2	5.5	6.7	41	0.65	0.074	14
STD DS8	Standard	13.4	114.4	129.4	325	1.8	40.6	7.4	629	2.54	25.9	114.5	6.5	75	2.4	6.2	7.2	41	0.68	0.086	15
STD DS8	Standard	12.6	107.4	122.8	302	1.6	37.8	7.8	585	2.39	24.8	101.3	6.5	68	2.3	5.4	6.8	41	0.66	0.085	14
STD DS8	Standard	11.5	109.0	118.0	298	1.7	36.3	7.3	566	2.29	24.1	110.0	6.0	66	2.3	5.5	6.5	39	0.63	0.074	14
STD DS8	Standard	13.1	107.6	117.4	288	1.7	36.8	7.2	588	2.31	22.4	99.5	6.6	58	2.1	4.7	5.4	37	0.67	0.070	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

QUALITY CONTROL REPORT WHI11001218.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1280531	Soil	20	0.26	1015	0.002	2	1.07	0.008	0.09	<0.1	0.28	2.5	0.3	<0.05	3	2.5	<0.2
REP 1280531	QC	20	0.26	1018	0.002	2	1.08	0.008	0.08	<0.1	0.28	2.6	0.3	<0.05	3	2.5	<0.2
1280562	Soil	19	0.18	837	0.003	3	0.87	0.004	0.08	0.1	0.35	3.0	0.4	<0.05	2	2.1	<0.2
REP 1280562	QC	19	0.18	826	0.003	3	0.80	0.004	0.08	0.2	0.35	3.1	0.4	<0.05	2	1.9	<0.2
1280586	Soil	9	0.09	128	0.004	3	0.75	0.013	0.10	<0.1	0.03	1.1	0.2	0.05	2	1.6	<0.2
REP 1280586	QC	10	0.09	121	0.005	3	0.72	0.013	0.10	<0.1	0.03	1.0	0.2	0.06	2	1.7	<0.2
1280605	Soil	10	0.04	239	0.002	4	0.60	0.003	0.08	<0.1	0.08	1.8	0.1	<0.05	2	1.4	<0.2
REP 1280605	QC	10	0.04	243	0.002	3	0.61	0.003	0.08	<0.1	0.07	1.9	0.2	<0.05	2	1.4	<0.2
Reference Materials																	
STD DS8	Standard	119	0.61	298	0.126	3	0.98	0.111	0.45	3.2	0.18	2.3	5.4	0.13	5	3.2	5.1
STD DS8	Standard	117	0.61	300	0.122	3	1.02	0.110	0.46	3.1	0.21	3.2	5.3	0.13	5	4.4	5.2
STD DS8	Standard	120	0.59	294	0.115	2	0.90	0.103	0.42	3.3	0.19	2.7	5.6	0.08	5	5.6	5.0
STD DS8	Standard	118	0.62	296	0.122	3	1.03	0.096	0.43	3.0	0.20	3.0	5.5	0.14	5	5.2	5.1
STD DS8	Standard	117	0.60	281	0.122	3	0.98	0.101	0.42	3.0	0.20	2.8	5.4	0.14	5	5.7	5.3
STD DS8	Standard	122	0.62	270	0.109	2	0.89	0.084	0.41	2.9	0.21	2.1	5.6	0.14	5	5.0	4.7
STD DS8	Standard	112	0.59	263	0.104	3	0.87	0.099	0.40	3.0	0.21	2.2	5.4	0.14	4	4.9	4.9
STD DS8	Standard	117	0.66	300	0.111	5	1.00	0.103	0.45	2.8	0.23	2.8	5.4	0.18	5	6.4	5.0
STD DS8	Standard	111	0.58	271	0.113	2	0.93	0.098	0.45	3.0	0.20	3.0	5.3	0.06	5	5.3	4.5
STD DS8	Standard	110	0.58	273	0.115	2	0.93	0.112	0.40	2.9	0.18	2.8	5.2	0.17	4	4.9	5.1
STD DS8	Standard	115	0.60	259	0.109	2	0.87	0.087	0.37	2.8	0.19	2.3	5.2	0.18	5	4.8	4.8
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

QUALITY CONTROL REPORT WHI11001218.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

QUALITY CONTROL REPORT WHI11001218.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 24, 2011
Report Date: October 24, 2011
Page: 1 of 8

CERTIFICATE OF ANALYSIS WHI11001219.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #15
P.O. Number
Number of Samples: 193

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	193	Sieve soil to 230 mesh			WHI
RJSV	193	Saving all or part of Soil Reject			WHI
1DX2	191	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280618	Soil	64.8	220.4	17.4	390	6.8	86.0	4.6	146	2.39	57.9	6.5	0.8	192	9.5	35.9	0.3	1074	0.32	0.379	26
1280619	Soil	88.8	74.4	16.7	217	3.2	33.2	1.6	33	2.30	25.0	5.8	0.6	102	7.3	22.7	0.3	581	0.13	0.267	15
1280620	Soil	7.3	58.9	25.0	104	1.2	22.9	6.8	228	3.16	35.2	3.5	1.3	63	0.5	6.8	0.4	58	0.03	0.098	6
1280621	Soil	5.6	81.5	25.4	188	0.9	28.0	8.8	222	4.04	43.6	6.6	2.6	37	1.1	5.6	0.4	44	0.01	0.099	6
1280622	Soil	3.5	60.6	43.3	191	0.6	29.8	9.6	185	4.18	20.6	5.5	2.8	84	0.6	3.3	0.5	32	<0.01	0.087	3
1280623	Soil	2.5	72.1	27.5	252	0.7	44.3	15.0	388	3.53	14.9	2.9	0.7	20	0.7	2.4	0.4	24	0.02	0.069	2
1280624	Soil	2.8	61.8	32.8	218	1.2	40.5	22.9	1092	3.20	15.3	2.5	0.9	13	1.2	2.9	0.4	27	0.02	0.079	4
1280625	Soil	2.2	44.1	26.7	189	0.5	29.5	13.4	700	2.67	28.9	1.8	0.5	17	0.4	3.6	0.4	25	0.01	0.063	3
1280626	Soil	3.1	43.7	22.5	175	0.4	26.5	8.4	191	2.48	34.1	1.3	0.3	28	0.3	3.8	0.3	30	<0.01	0.077	2
1280627	Soil	2.8	62.7	24.0	217	0.6	37.0	14.5	517	2.77	21.7	2.2	1.3	17	0.7	3.1	0.3	24	0.02	0.087	5
1280628	Soil	3.5	48.4	28.8	190	0.9	34.4	12.8	329	2.67	27.7	2.4	1.0	12	0.6	4.3	0.3	32	<0.01	0.066	3
1280629	Soil	5.4	24.8	23.5	15	1.4	6.4	0.6	19	1.72	22.5	6.8	0.8	46	<0.1	8.5	0.3	89	<0.01	0.045	3
1280630	Soil	1.9	16.3	7.3	14	0.9	3.4	1.0	37	0.79	35.7	8.3	0.1	9	<0.1	4.1	0.1	18	0.02	0.029	2
1281001	Soil	6.0	11.6	8.0	53	0.3	13.9	1.9	124	0.70	7.2	<0.5	<0.1	18	0.7	1.8	0.1	31	0.05	0.131	4
1281002	Soil	14.5	83.9	38.2	337	1.0	96.4	14.1	464	3.21	37.2	4.4	1.3	124	1.7	9.1	0.4	67	0.90	0.533	21
1281003	Soil	3.2	16.9	11.7	40	0.2	14.4	3.1	109	0.79	7.8	2.7	0.1	14	0.3	1.8	0.1	19	0.20	0.121	4
1281004	Soil	10.7	252.8	1372	1202	2.2	168.2	32.9	1380	7.65	362.2	28.1	0.8	49	4.1	309.3	0.4	80	0.62	0.468	18
1281005	Soil	3.1	13.2	9.5	41	0.2	12.5	1.8	59	0.70	7.3	0.7	0.1	15	0.3	1.7	0.1	19	0.16	0.091	6
1281006	Soil	7.0	51.0	17.5	141	0.3	57.5	10.4	377	2.55	21.4	1.6	0.4	24	0.9	4.1	0.3	37	0.27	0.170	10
1281007	Soil	0.9	4.2	1.8	20	0.1	4.6	0.4	15	0.22	1.3	<0.5	<0.1	12	0.3	0.3	<0.1	6	0.16	0.044	2
1281008	Soil	13.5	30.4	15.3	379	0.3	51.3	4.2	94	1.23	15.9	1.4	0.3	28	2.7	3.7	0.2	61	0.36	0.074	3
1281009	Soil	6.3	23.8	7.0	489	0.4	51.2	3.4	134	0.77	7.8	1.5	0.2	24	3.6	2.0	<0.1	29	0.46	0.081	3
1281010	Soil	0.7	3.9	2.2	12	0.7	4.4	0.5	8	0.19	1.3	1.3	0.2	10	<0.1	0.4	<0.1	9	0.07	0.030	<1
1281011	Soil	6.3	20.9	9.4	68	0.5	24.6	4.4	42	1.20	19.4	0.9	<0.1	7	0.1	3.8	0.1	41	0.02	0.053	3
1281012	Soil	8.6	28.4	16.7	116	0.6	32.4	5.8	75	1.93	20.6	2.0	<0.1	13	0.2	4.5	0.3	57	0.02	0.066	6
1281013	Soil	9.5	43.6	15.6	147	0.8	46.3	7.1	211	2.25	21.1	2.5	0.6	57	0.4	5.5	0.2	57	0.42	0.089	6
1281014	Soil	11.0	50.5	17.1	199	1.4	74.8	12.6	206	3.26	28.5	6.0	0.9	51	1.2	7.9	0.3	60	0.27	0.087	8
1281015	Soil	10.0	60.3	38.3	344	1.4	103.1	16.5	877	3.39	33.0	4.0	0.8	82	2.6	13.0	0.3	77	0.50	0.185	7
1281016	Soil	2.5	57.4	12.2	209	1.8	50.6	9.9	952	1.69	5.7	3.9	0.4	62	2.2	2.4	0.2	22	0.39	0.153	7
1281017	Soil	22.7	53.1	27.3	352	1.0	104.6	10.2	281	2.46	38.5	4.1	1.0	61	3.1	15.2	0.2	77	0.70	0.110	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280618	Soil	118	0.09	1259	0.012	4	0.86	0.005	0.11	0.4	0.73	2.0	2.0	0.22	5	36.3	0.6
1280619	Soil	45	0.02	198	0.009	4	0.61	0.004	0.14	0.7	0.59	1.1	4.2	0.52	4	42.9	0.6
1280620	Soil	13	0.05	549	0.002	2	0.48	0.003	0.09	<0.1	0.08	3.1	0.4	0.13	2	4.4	<0.2
1280621	Soil	13	0.06	440	0.004	3	0.52	0.003	0.08	<0.1	0.07	4.7	0.3	0.10	2	4.2	<0.2
1280622	Soil	10	0.02	405	0.002	3	0.33	0.003	0.15	<0.1	0.05	4.5	0.4	0.28	1	2.4	<0.2
1280623	Soil	8	0.03	255	0.003	3	0.49	0.006	0.09	<0.1	0.03	3.4	0.2	<0.05	2	2.1	<0.2
1280624	Soil	8	0.05	173	0.004	3	0.49	0.005	0.07	<0.1	0.10	3.0	0.2	<0.05	1	1.9	<0.2
1280625	Soil	7	0.03	126	0.004	3	0.44	0.005	0.06	<0.1	0.05	1.7	0.2	<0.05	2	2.6	<0.2
1280626	Soil	6	0.02	100	0.004	2	0.39	0.006	0.07	<0.1	0.04	1.2	0.2	0.05	2	1.4	<0.2
1280627	Soil	8	0.05	95	0.004	2	0.59	0.005	0.07	<0.1	0.08	2.6	0.2	<0.05	2	1.7	<0.2
1280628	Soil	7	0.02	161	0.003	2	0.36	0.002	0.05	<0.1	0.05	2.2	0.2	<0.05	2	2.7	<0.2
1280629	Soil	14	<0.01	503	0.001	2	0.25	0.001	0.03	<0.1	0.16	1.1	0.2	<0.05	4	7.5	<0.2
1280630	Soil	7	0.03	87	0.008	2	0.42	0.010	0.03	<0.1	0.06	0.5	0.1	<0.05	2	3.2	<0.2
1281001	Soil	8	0.02	144	0.002	1	0.36	0.013	0.04	<0.1	0.04	0.2	0.1	0.05	2	1.7	<0.2
1281002	Soil	18	0.07	846	0.006	5	0.50	0.004	0.16	<0.1	0.25	1.8	0.2	0.08	1	5.8	0.2
1281003	Soil	7	0.04	107	0.003	<1	0.47	0.015	0.03	<0.1	0.03	0.3	<0.1	<0.05	2	1.2	<0.2
1281004	Soil	72	0.08	194	0.006	2	0.59	0.007	0.08	0.1	0.23	3.7	0.1	<0.05	3	3.5	<0.2
1281005	Soil	7	0.04	64	0.004	<1	0.63	0.012	0.03	<0.1	0.03	0.2	<0.1	<0.05	2	<0.5	<0.2
1281006	Soil	22	0.05	105	0.007	1	0.45	0.005	0.04	<0.1	0.03	1.2	0.1	<0.05	2	2.1	<0.2
1281007	Soil	1	0.02	42	0.010	<1	0.45	0.026	0.02	<0.1	0.02	0.6	<0.1	<0.05	2	0.7	<0.2
1281008	Soil	9	0.05	158	0.003	<1	0.40	0.012	0.03	<0.1	0.08	1.0	0.3	<0.05	2	1.9	<0.2
1281009	Soil	5	0.03	127	0.010	1	0.62	0.022	0.03	<0.1	0.08	0.8	0.1	<0.05	1	0.8	<0.2
1281010	Soil	3	0.01	192	0.003	<1	0.12	0.017	0.02	<0.1	0.06	0.4	<0.1	<0.05	<1	<0.5	<0.2
1281011	Soil	7	0.02	120	0.003	1	0.36	0.005	0.03	<0.1	0.03	0.4	0.1	<0.05	2	<0.5	<0.2
1281012	Soil	10	0.02	160	0.003	1	0.32	0.005	0.04	<0.1	0.05	0.5	0.2	<0.05	2	1.9	<0.2
1281013	Soil	14	0.08	1621	0.003	3	0.62	0.008	0.05	<0.1	0.20	2.1	0.2	<0.05	2	2.5	<0.2
1281014	Soil	27	0.09	1084	0.003	1	0.61	0.007	0.06	0.1	0.25	4.9	0.3	<0.05	2	1.9	<0.2
1281015	Soil	34	0.10	1106	0.004	2	0.66	0.005	0.04	<0.1	0.23	3.5	0.2	<0.05	2	2.9	<0.2
1281016	Soil	10	0.06	1161	0.006	3	0.79	0.014	0.04	<0.1	0.33	1.7	0.1	<0.05	2	2.6	<0.2
1281017	Soil	20	0.07	369	0.002	3	0.30	0.004	0.04	<0.1	0.52	4.3	0.3	<0.05	<1	3.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281018	Soil	22.3	52.5	33.8	329	0.9	121.0	15.6	495	3.00	43.9	2.4	1.2	64	2.6	16.7	0.2	93	0.74	0.098	4
1281019	Soil	19.7	32.9	21.2	243	0.1	68.1	7.6	123	2.26	33.3	1.0	0.9	35	1.4	11.5	0.2	88	0.25	0.111	5
1281020	Soil	15.3	60.8	26.4	302	0.9	104.5	6.8	115	2.28	34.7	3.0	0.6	74	3.3	12.9	0.2	68	1.12	0.133	5
1281021	Soil	44.0	41.4	11.9	117	0.1	99.6	5.8	139	1.25	12.2	0.8	0.6	69	1.3	2.7	<0.1	20	1.68	0.047	5
1281022	Soil	92.7	75.0	9.8	186	0.2	203.1	11.5	178	1.87	27.8	0.7	1.5	65	2.0	6.7	0.1	34	0.92	0.041	9
1281023	Soil	32.7	26.9	8.1	41	<0.1	80.9	5.9	144	1.53	12.5	<0.5	0.6	24	0.4	2.4	<0.1	26	0.46	0.033	9
1281024	Soil	70.3	68.6	19.3	232	0.3	184.0	7.9	160	1.85	16.6	<0.5	1.2	128	4.5	6.7	0.2	43	4.57	0.052	8
1281025	Soil	5.2	10.2	1.6	58	<0.1	21.0	1.5	57	0.32	2.8	<0.5	0.2	23	0.7	1.0	<0.1	11	0.49	0.031	2
1281026	Soil	18.2	85.6	30.1	893	1.5	238.5	26.8	467	3.67	52.4	4.4	1.7	103	4.7	14.6	0.2	100	0.91	0.175	7
1281027	Soil	13.1	58.1	27.5	397	1.1	94.9	11.7	279	2.50	33.6	4.0	0.8	82	3.6	17.3	0.2	64	0.57	0.129	5
1281028	Soil	30.5	89.4	45.9	909	1.5	217.0	30.0	731	4.74	83.5	3.1	2.2	143	9.7	32.2	0.2	161	1.01	0.253	8
1281029	Soil	21.7	159.5	35.7	375	0.7	115.9	17.3	314	4.09	75.4	6.3	0.4	97	1.2	25.7	0.3	66	0.32	0.189	3
1281030	Soil	11.0	58.1	29.8	311	0.7	97.2	20.4	474	4.22	30.6	3.4	1.0	49	0.8	8.6	0.3	49	0.25	0.095	4
1281051	Soil	7.6	95.8	21.7	187	0.4	42.1	14.1	198	4.25	25.4	6.3	0.4	13	0.8	3.7	0.3	29	0.09	0.218	7
1281052	Soil	14.8	168.2	16.3	261	0.7	58.1	11.0	386	3.68	39.1	7.7	0.1	35	1.6	7.1	0.3	75	0.52	0.256	8
1281053	Soil	4.8	164.5	19.4	151	0.2	75.4	18.1	282	5.32	43.0	13.4	0.3	11	0.2	6.5	0.5	52	0.02	0.102	7
1281054	Soil	3.7	166.4	27.3	123	0.7	61.9	20.1	473	4.80	25.2	12.8	1.5	20	0.4	4.1	0.4	35	0.09	0.113	8
1281055	Soil	5.3	99.0	19.4	235	1.2	68.5	16.7	576	4.28	22.9	14.6	1.3	51	1.6	3.4	0.2	30	1.63	0.176	15
1281056	Soil	5.4	48.7	10.3	133	0.7	58.8	12.2	1031	8.03	17.7	9.6	0.9	130	0.4	3.4	0.1	41	8.48	0.181	7
1281057	Soil	2.7	102.1	8.9	105	0.2	37.4	6.3	125	2.46	16.2	8.2	<0.1	7	0.1	2.5	0.2	30	0.05	0.075	3
1281058	Soil	3.6	128.1	14.5	151	0.2	41.9	13.2	514	4.17	14.8	13.2	0.4	13	0.2	2.8	0.4	42	0.08	0.111	9
1281059	Soil	4.9	190.1	24.8	255	0.2	79.2	25.2	515	5.76	24.5	44.8	0.8	13	0.3	5.1	0.5	46	0.05	0.110	10
1281060	Soil	7.6	207.9	20.8	565	0.4	122.9	24.3	718	5.36	29.2	21.3	0.4	30	1.4	5.4	0.4	46	0.27	0.209	11
1281061	Soil	4.9	63.0	16.5	121	0.3	29.9	7.3	243	2.77	15.0	11.7	0.2	13	0.3	2.6	0.3	34	0.04	0.111	9
1281062	Soil	4.0	53.0	14.1	106	0.2	28.9	5.7	100	2.17	15.0	2.4	<0.1	10	0.3	2.6	0.3	39	0.02	0.086	5
1281063	Soil	3.7	123.3	13.4	188	0.2	57.7	10.3	542	4.12	20.5	5.2	0.4	8	0.5	5.5	0.4	42	<0.01	0.090	12
1281064	Soil	3.7	169.4	13.9	292	<0.1	83.1	18.6	320	4.66	28.3	7.2	0.3	11	0.2	6.3	0.5	45	0.01	0.086	9
1281065	Soil	0.9	22.3	3.1	76	0.1	20.9	4.7	521	1.57	2.2	1.1	0.3	85	0.5	0.7	<0.1	15	3.73	0.066	5
1281066	Soil	5.2	84.1	19.1	172	0.3	29.2	12.7	219	4.64	15.2	3.9	0.5	12	0.6	3.1	0.3	55	0.20	0.133	14
1281067	Soil	3.7	45.6	16.9	110	<0.1	22.4	10.7	393	3.00	11.2	3.9	0.5	12	0.3	1.5	0.2	27	0.14	0.164	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281018	Soil	24	0.12	368	0.002	3	0.27	0.003	0.03	<0.1	0.41	4.1	0.3	<0.05	<1	3.8	<0.2
1281019	Soil	16	0.05	393	0.003	4	0.60	0.006	0.02	<0.1	0.18	3.1	0.2	<0.05	2	2.8	<0.2
1281020	Soil	17	0.06	424	0.003	3	0.33	0.003	0.03	<0.1	0.54	3.3	0.2	0.07	<1	4.5	<0.2
1281021	Soil	8	0.18	121	0.004	3	0.30	0.015	0.02	0.1	0.14	1.7	0.5	0.05	<1	1.5	<0.2
1281022	Soil	12	0.04	150	0.003	1	0.36	0.005	0.02	0.2	0.21	3.4	1.0	<0.05	<1	2.5	<0.2
1281023	Soil	6	0.05	102	0.004	2	0.31	0.013	0.02	0.1	0.11	1.3	0.4	<0.05	<1	1.7	<0.2
1281024	Soil	14	1.63	126	0.002	4	0.17	0.006	0.03	0.3	0.39	3.2	1.1	<0.05	<1	2.7	<0.2
1281025	Soil	2	0.03	73	0.006	1	0.20	0.023	0.02	<0.1	0.05	0.4	0.1	<0.05	<1	0.8	<0.2
1281026	Soil	45	0.11	551	0.003	2	0.73	0.006	0.03	<0.1	0.32	6.9	0.6	0.06	2	4.5	<0.2
1281027	Soil	20	0.07	620	0.004	2	0.65	0.009	0.04	<0.1	0.27	3.3	0.3	<0.05	2	2.5	<0.2
1281028	Soil	77	0.09	794	0.004	3	0.51	0.004	0.04	0.1	0.52	9.3	0.5	<0.05	1	4.3	<0.2
1281029	Soil	17	0.04	322	0.003	1	0.25	0.005	0.03	<0.1	0.11	2.4	0.2	<0.05	<1	5.1	<0.2
1281030	Soil	18	0.06	504	0.003	2	0.33	0.004	0.04	<0.1	0.14	4.2	0.2	<0.05	1	1.4	<0.2
1281051	Soil	7	0.05	228	0.003	2	0.34	0.003	0.08	<0.1	0.12	0.9	0.2	0.07	1	2.7	<0.2
1281052	Soil	12	0.07	250	0.003	3	0.33	0.005	0.07	<0.1	0.17	0.8	0.3	0.14	2	3.1	<0.2
1281053	Soil	13	0.04	83	0.006	<1	0.42	0.002	0.06	0.1	0.06	1.9	0.1	0.05	3	2.0	0.3
1281054	Soil	14	0.12	106	0.012	2	0.61	0.006	0.06	0.1	0.09	3.7	0.2	<0.05	2	2.9	<0.2
1281055	Soil	10	0.32	763	0.003	3	0.68	0.003	0.10	<0.1	0.28	3.2	0.2	0.08	1	2.6	<0.2
1281056	Soil	11	3.06	363	0.003	3	0.47	0.005	0.05	<0.1	0.13	1.5	0.1	0.06	1	1.8	<0.2
1281057	Soil	7	0.02	41	0.006	1	0.42	0.013	0.04	<0.1	0.07	0.8	<0.1	<0.05	2	1.1	<0.2
1281058	Soil	14	0.14	130	0.010	1	0.83	0.010	0.05	0.1	0.06	2.1	0.1	0.06	3	1.6	<0.2
1281059	Soil	14	0.11	84	0.010	<1	0.64	0.004	0.04	0.2	0.06	2.7	0.1	<0.05	3	2.5	0.3
1281060	Soil	13	0.07	150	0.004	2	0.62	0.006	0.05	<0.1	0.11	1.5	0.2	0.06	2	1.9	0.2
1281061	Soil	11	0.08	69	0.007	1	0.67	0.005	0.04	0.2	0.06	0.4	0.1	<0.05	3	1.4	0.2
1281062	Soil	7	0.02	65	0.003	<1	0.29	0.004	0.04	0.1	0.04	0.3	<0.1	<0.05	2	1.1	<0.2
1281063	Soil	9	0.02	71	0.005	1	0.31	0.003	0.04	0.1	0.04	1.0	<0.1	<0.05	2	1.8	<0.2
1281064	Soil	9	0.03	59	0.007	<1	0.40	0.003	0.05	0.1	0.03	1.4	<0.1	<0.05	3	1.9	0.3
1281065	Soil	3	1.44	440	0.005	2	0.29	0.018	0.04	<0.1	0.05	0.5	<0.1	<0.05	<1	<0.5	<0.2
1281066	Soil	12	0.12	170	0.005	1	0.59	0.002	0.08	<0.1	0.09	1.2	0.3	0.08	4	2.0	<0.2
1281067	Soil	11	0.12	196	0.004	<1	0.66	0.003	0.06	0.1	0.05	0.9	0.1	<0.05	2	0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281068	Soil	4.8	110.8	25.0	237	0.9	65.9	20.5	767	5.51	27.8	23.2	1.3	28	1.2	3.5	0.3	37	0.39	0.211	18
1281069	Soil	4.3	80.4	19.0	133	<0.1	30.6	12.7	260	4.40	21.4	9.1	0.4	9	0.3	3.1	0.3	47	0.04	0.140	10
1281070	Soil	3.6	118.0	29.3	170	0.2	49.3	25.2	597	5.75	35.0	10.6	2.4	27	0.6	3.7	0.4	42	0.31	0.196	16
1281071	Soil	13.2	196.3	38.6	236	1.0	87.9	50.1	1306	10.04	68.5	19.6	4.3	48	1.3	4.9	0.5	14	1.17	0.169	21
1281072	Soil	2.7	40.4	11.0	98	0.2	19.2	8.7	1471	2.76	11.2	2.7	0.1	12	1.4	1.4	0.2	25	0.09	0.207	6
1281073	Soil	2.6	54.4	11.3	57	0.1	17.8	10.2	1666	2.56	11.7	<0.5	0.2	7	0.6	1.7	0.2	27	0.03	0.124	6
1281074	Soil	5.6	88.0	16.2	125	<0.1	34.8	17.3	1298	4.41	22.9	3.7	0.3	9	0.2	3.7	0.2	21	0.01	0.199	9
1281075	Soil	7.6	61.3	22.7	112	0.1	30.0	17.5	514	5.08	17.0	3.1	0.5	15	0.5	2.4	0.3	45	0.04	0.143	12
1281076	Soil	6.4	58.9	21.4	103	0.2	25.7	16.3	653	4.62	15.2	2.9	0.5	10	0.3	1.8	0.3	40	0.09	0.203	11
1281077	Soil	10.6	57.5	26.4	104	0.3	44.4	18.6	702	4.00	19.3	2.5	2.8	16	0.2	2.0	0.3	27	0.28	0.137	22
1281078	Soil	12.1	153.7	31.7	265	2.1	66.2	19.9	642	7.05	32.9	10.0	4.8	71	2.0	4.4	0.3	35	0.27	0.278	20
1281079	Soil	6.1	77.9	32.5	133	0.2	51.5	27.9	727	5.03	12.4	1.5	4.2	16	0.3	1.4	0.3	39	0.26	0.166	19
1281080	Soil	7.1	59.3	20.3	138	0.1	37.3	14.4	444	4.37	17.2	2.5	0.8	19	0.2	2.6	0.4	62	0.15	0.147	13
1281081	Soil	4.4	32.3	11.1	70	0.1	19.1	7.4	259	2.54	9.2	<0.5	0.5	11	0.1	1.4	0.3	36	0.03	0.133	11
1281082	Soil	7.4	58.3	14.5	113	0.1	24.3	10.1	171	2.90	11.9	1.5	0.4	9	0.1	1.7	0.3	63	0.01	0.086	13
1281083	Soil	7.7	50.9	13.0	102	<0.1	22.5	9.1	245	3.35	13.4	0.5	0.6	8	0.2	1.9	0.3	70	0.02	0.132	12
1281084	Soil	11.3	109.2	24.8	166	1.0	45.5	18.0	707	5.72	23.0	4.7	3.0	15	1.9	2.6	0.3	46	0.26	0.187	18
1281085	Soil	6.5	38.2	10.1	68	0.2	18.0	6.0	138	1.70	7.2	2.0	1.4	16	0.4	1.2	0.2	32	0.10	0.060	16
1281086	Soil	7.2	102.0	24.3	138	0.5	37.7	22.6	930	4.65	15.5	4.0	3.3	19	0.4	2.5	0.4	50	0.11	0.140	19
1281087	Soil	5.4	50.4	17.1	107	0.2	26.9	14.7	656	3.64	12.4	1.9	1.1	17	0.3	1.8	0.3	51	0.11	0.194	18
1281088	Soil	2.9	19.9	7.3	43	<0.1	10.7	3.5	68	1.28	7.2	<0.5	0.2	9	<0.1	1.0	0.2	45	0.04	0.054	10
1281089	Soil	5.2	69.6	14.7	109	0.4	38.2	16.8	454	3.26	10.8	3.2	4.7	35	0.4	1.6	0.2	35	0.49	0.172	25
1281090	Soil	1.7	24.1	8.8	32	0.8	9.6	8.1	505	1.26	3.1	3.3	1.5	19	0.7	0.5	0.1	21	0.19	0.069	12
1281091	Soil	1.4	34.2	7.9	26	0.9	11.1	5.7	259	1.47	3.4	3.7	1.0	18	0.8	0.4	0.2	21	0.21	0.095	13
1281092	Soil	4.1	40.1	14.5	90	1.7	21.9	10.4	617	2.49	7.0	6.7	1.3	29	0.9	1.3	0.2	43	0.44	0.178	17
1281093	Soil	7.1	83.3	16.8	216	1.3	61.0	27.4	1294	6.35	17.2	7.2	2.7	67	1.5	2.3	0.2	29	0.74	0.227	27
1281094	Soil	7.4	112.2	27.6	139	1.6	51.7	23.4	830	4.51	12.1	11.3	4.0	47	0.7	2.3	0.4	42	0.43	0.155	25
1281095	Soil	4.7	36.5	16.3	72	0.5	17.7	7.8	312	2.34	9.4	4.7	2.3	20	0.2	1.6	0.3	43	0.18	0.115	15
1281096	Soil	4.6	81.7	17.6	67	2.5	24.5	5.8	289	1.92	8.5	10.9	0.7	28	0.3	1.6	0.2	49	0.26	0.107	13
1281097	Soil	0.2	1.9	1.5	3	<0.1	0.7	0.3	10	0.16	<0.5	<0.5	<0.1	4	<0.1	<0.1	<0.1	5	0.02	0.021	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281068	Soil	14	0.28	459	0.004	2	0.95	0.004	0.07	<0.1	0.16	3.7	0.2	<0.05	3	1.5	<0.2
1281069	Soil	14	0.18	128	0.004	<1	0.86	0.003	0.05	<0.1	0.05	0.7	0.2	<0.05	4	0.9	<0.2
1281070	Soil	18	0.56	459	0.006	<1	1.38	0.003	0.07	<0.1	0.06	4.2	0.1	<0.05	4	1.6	<0.2
1281071	Soil	6	0.45	591	0.003	3	0.33	0.002	0.09	<0.1	0.15	9.8	0.4	0.14	<1	2.8	<0.2
1281072	Soil	8	0.04	280	0.002	1	0.55	0.006	0.05	<0.1	0.04	0.4	<0.1	0.08	2	0.9	<0.2
1281073	Soil	6	0.02	181	0.003	1	0.43	0.007	0.05	<0.1	0.05	0.5	<0.1	<0.05	2	<0.5	<0.2
1281074	Soil	6	0.03	181	0.003	<1	0.51	0.003	0.04	<0.1	0.09	1.2	0.1	<0.05	1	1.0	<0.2
1281075	Soil	19	0.14	315	0.005	<1	0.89	0.003	0.07	<0.1	0.04	1.3	0.1	<0.05	4	1.2	<0.2
1281076	Soil	22	0.22	180	0.004	1	1.04	0.002	0.06	<0.1	0.07	0.8	0.1	0.08	4	1.8	<0.2
1281077	Soil	22	0.40	245	0.002	<1	1.02	0.002	0.07	<0.1	0.15	3.9	0.2	<0.05	3	1.5	<0.2
1281078	Soil	18	0.26	383	0.007	<1	0.95	0.011	0.12	<0.1	0.20	6.8	0.4	0.15	2	2.6	<0.2
1281079	Soil	36	0.55	302	0.004	3	1.57	0.004	0.11	<0.1	0.07	5.2	0.1	<0.05	4	0.5	<0.2
1281080	Soil	22	0.27	172	0.006	3	1.06	0.004	0.09	<0.1	0.03	1.5	0.2	0.06	5	1.2	<0.2
1281081	Soil	14	0.15	68	0.006	2	0.80	0.010	0.07	<0.1	0.02	0.5	0.1	0.06	3	0.9	<0.2
1281082	Soil	10	0.09	65	0.007	2	0.84	0.006	0.07	<0.1	0.02	0.9	0.2	<0.05	5	1.2	<0.2
1281083	Soil	15	0.13	66	0.005	2	0.85	0.003	0.07	0.1	0.02	1.0	0.2	<0.05	6	1.9	<0.2
1281084	Soil	18	0.61	160	0.004	2	1.27	0.005	0.07	<0.1	0.19	3.7	0.3	<0.05	3	2.9	<0.2
1281085	Soil	13	0.19	256	0.005	2	0.73	0.005	0.10	<0.1	0.07	1.8	0.3	<0.05	3	0.6	<0.2
1281086	Soil	21	0.44	219	0.004	4	1.28	0.004	0.10	<0.1	0.05	3.1	0.2	0.05	3	2.0	<0.2
1281087	Soil	20	0.28	185	0.007	2	1.10	0.004	0.11	<0.1	0.07	1.9	0.2	<0.05	4	1.2	<0.2
1281088	Soil	10	0.07	77	0.005	1	0.53	0.012	0.06	<0.1	0.02	0.4	0.1	<0.05	4	<0.5	<0.2
1281089	Soil	19	0.47	184	0.007	3	1.00	0.006	0.14	<0.1	0.10	3.9	0.1	<0.05	3	1.1	<0.2
1281090	Soil	10	0.17	313	0.004	2	0.63	0.017	0.06	<0.1	0.19	2.8	0.2	<0.05	2	1.4	<0.2
1281091	Soil	10	0.13	247	0.004	<1	0.71	0.017	0.06	<0.1	0.26	2.4	0.1	0.07	2	1.4	<0.2
1281092	Soil	19	0.38	196	0.006	2	0.97	0.007	0.08	<0.1	0.36	3.2	0.2	0.05	3	1.6	<0.2
1281093	Soil	13	0.42	315	0.004	3	1.08	0.012	0.09	<0.1	0.47	9.3	0.2	0.22	2	3.4	<0.2
1281094	Soil	28	0.46	538	0.005	4	1.64	0.007	0.10	<0.1	0.59	8.5	0.2	0.07	4	2.4	<0.2
1281095	Soil	15	0.25	172	0.004	3	0.78	0.008	0.09	<0.1	0.37	2.2	0.2	<0.05	3	1.8	<0.2
1281096	Soil	21	0.25	261	0.002	3	0.94	0.008	0.09	<0.1	0.48	1.9	0.3	0.08	3	2.0	<0.2
1281097	Soil	1	0.01	13	0.005	<1	0.09	0.032	0.02	<0.1	0.01	0.3	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281098	Soil	8.9	41.3	15.1	85	0.6	21.4	6.8	102	1.95	10.2	4.3	0.6	17	0.2	1.9	0.2	36	0.07	0.062	11
1281099	Soil	1.8	16.3	8.7	25	0.5	5.7	2.8	134	0.99	3.6	2.0	0.9	10	0.1	0.6	0.2	29	0.04	0.058	11
1281100	Soil	4.9	28.1	13.0	82	0.5	21.2	7.2	164	1.97	6.2	2.4	2.8	21	0.1	1.4	0.2	55	0.15	0.102	19
1281151	Soil	11.4	26.1	14.8	121	0.2	36.4	8.6	250	2.65	16.5	<0.5	0.3	13	0.2	3.1	0.3	65	0.02	0.071	7
1281152	Soil	6.1	21.9	14.9	91	0.1	27.1	9.1	201	2.54	14.1	<0.5	0.4	10	0.1	2.2	0.3	55	0.03	0.066	7
1281153	Soil	4.1	50.3	18.4	127	0.6	35.3	17.1	533	2.64	12.5	1.5	0.2	11	0.7	2.2	0.3	35	0.04	0.079	4
1281154	Soil	3.6	48.2	11.2	152	0.3	47.6	14.0	246	2.81	7.5	1.1	0.2	8	0.2	2.7	0.3	30	0.01	0.063	3
1281155	Soil	6.7	41.8	11.1	147	0.5	29.3	9.6	109	1.79	9.7	1.7	0.2	8	0.4	3.5	0.4	38	0.02	0.047	6
1281156	Soil	1.4	12.6	3.7	33	0.7	7.8	2.1	40	0.73	3.0	0.5	0.2	6	0.3	0.7	0.1	15	0.02	0.056	3
1281157	Soil	6.3	18.2	11.2	81	0.5	19.1	4.6	88	1.50	7.9	<0.5	0.4	8	0.2	1.7	0.2	50	0.02	0.043	8
1281158	Soil	5.2	29.5	10.1	71	0.7	22.5	5.6	93	1.69	18.8	0.8	0.1	11	0.3	2.3	0.3	45	0.02	0.057	4
1281159	Soil	1.8	19.3	5.8	64	0.6	14.2	4.4	90	1.22	8.7	<0.5	0.1	8	0.7	1.3	0.2	22	0.03	0.042	2
1281160	Soil	5.9	23.5	13.4	61	0.7	17.3	3.5	73	1.38	14.6	<0.5	<0.1	11	0.2	2.6	0.2	44	0.02	0.068	5
1281161	Soil	11.7	89.4	41.4	172	1.8	54.8	8.1	331	2.69	54.7	6.3	0.8	67	3.8	5.3	0.4	99	0.21	0.133	7
1281162	Soil	3.7	12.6	8.5	54	<0.1	12.2	3.0	57	1.20	11.2	<0.5	0.3	8	<0.1	2.2	0.1	38	0.01	0.022	7
1281163	Soil	3.4	15.3	12.1	78	0.3	15.0	3.8	102	2.47	13.6	<0.5	1.0	11	0.2	1.7	0.3	50	0.02	0.047	4
1281164	Soil	4.1	14.3	10.0	70	0.1	13.6	3.7	78	1.90	13.2	0.6	0.6	10	0.2	2.1	0.2	55	0.03	0.038	6
1281165	Soil	1.9	8.9	5.6	40	<0.1	7.0	1.8	56	1.18	6.1	0.5	<0.1	8	0.2	1.1	0.1	28	0.03	0.053	3
1281166	Soil	3.0	13.2	9.3	70	0.1	12.6	3.7	95	2.48	13.9	<0.5	0.3	6	0.2	2.1	0.2	51	0.02	0.059	6
1281167	Soil	3.2	24.5	8.2	53	0.2	11.1	4.6	108	1.69	7.1	13.5	0.2	4	0.4	1.0	0.2	35	0.02	0.131	7
1281168	Soil	3.6	14.9	5.6	17	0.3	6.3	4.8	3530	0.80	2.2	1.3	<0.1	81	0.2	0.5	0.1	18	1.79	0.139	4
1281169	Soil	3.3	17.8	4.5	35	0.9	4.9	1.1	10	0.86	7.4	<0.5	<0.1	5	0.6	1.0	<0.1	21	0.02	0.042	3
1281170	Soil	27.2	134.4	21.6	401	1.9	83.0	18.0	288	4.84	43.9	5.7	2.8	105	4.3	9.7	0.2	26	3.10	0.101	9
1281171	Soil	10.7	81.5	12.1	195	1.5	48.4	10.9	222	2.76	17.6	3.0	1.4	44	2.5	4.4	0.2	19	1.56	0.076	8
1281172	Soil	6.1	98.8	10.2	149	1.5	46.2	6.9	95	2.15	9.9	4.5	1.2	56	1.8	3.5	0.2	21	2.18	0.086	9
1281173	Soil	3.0	36.8	4.6	114	0.6	21.1	4.3	133	1.05	5.5	0.5	0.4	71	2.7	1.8	0.1	10	3.13	0.081	4
1281174	Soil	3.2	28.4	7.4	85	0.5	19.0	6.5	198	1.95	6.2	4.4	2.0	23	0.4	1.0	0.2	43	0.42	0.115	15
1281175	Soil	4.4	54.0	11.2	121	0.5	33.1	12.0	447	2.86	10.0	4.3	2.3	31	0.7	1.7	0.2	44	0.49	0.152	18
1281176	Soil	3.3	28.2	8.6	82	0.3	18.6	9.4	265	1.92	5.9	4.1	1.8	18	0.2	1.1	0.2	39	0.22	0.082	16
1281177	Soil	7.5	31.7	28.3	140	0.3	22.2	4.7	161	2.02	36.8	2.7	0.5	23	0.3	6.5	0.4	105	0.02	0.082	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281098	Soil	12	0.13	134	0.004	2	0.49	0.007	0.08	<0.1	0.19	1.3	0.2	<0.05	2	1.3	<0.2
1281099	Soil	10	0.13	130	0.004	2	0.57	0.010	0.08	<0.1	0.17	1.2	0.2	<0.05	2	0.8	<0.2
1281100	Soil	23	0.41	257	0.005	3	0.94	0.004	0.13	<0.1	0.18	2.0	0.2	<0.05	4	0.8	<0.2
1281151	Soil	16	0.06	81	0.009	2	0.58	0.005	0.05	<0.1	0.02	0.6	0.2	<0.05	3	1.2	<0.2
1281152	Soil	17	0.05	63	0.009	5	0.55	0.005	0.05	0.1	0.03	0.8	0.2	<0.05	3	0.7	<0.2
1281153	Soil	10	0.04	101	0.005	<1	0.51	0.006	0.05	<0.1	0.04	1.8	0.3	<0.05	2	1.4	<0.2
1281154	Soil	7	0.01	53	0.002	<1	0.30	0.006	0.03	<0.1	<0.01	1.4	0.1	<0.05	2	0.6	<0.2
1281155	Soil	10	0.02	96	0.003	2	0.31	0.004	0.04	<0.1	0.02	0.9	0.2	<0.05	2	1.4	<0.2
1281156	Soil	6	0.01	58	0.005	1	0.37	0.026	0.03	<0.1	0.02	0.3	<0.1	<0.05	2	0.6	<0.2
1281157	Soil	9	0.03	76	0.007	<1	0.42	0.005	0.04	<0.1	<0.01	1.3	0.2	<0.05	3	0.7	<0.2
1281158	Soil	10	0.02	85	0.007	1	0.39	0.011	0.04	0.3	0.01	0.6	0.2	<0.05	2	1.0	<0.2
1281159	Soil	5	0.02	112	0.004	<1	0.47	0.018	0.03	<0.1	0.02	0.8	<0.1	<0.05	2	0.9	<0.2
1281160	Soil	12	0.02	144	0.005	1	0.32	0.010	0.04	<0.1	0.06	0.4	0.1	<0.05	2	1.4	<0.2
1281161	Soil	25	0.06	1820	0.003	2	1.25	0.010	0.13	<0.1	0.34	3.6	0.5	0.06	4	3.7	<0.2
1281162	Soil	5	0.01	80	0.006	<1	0.27	0.008	0.03	<0.1	<0.01	0.7	<0.1	<0.05	2	0.6	<0.2
1281163	Soil	15	0.06	137	0.003	2	0.95	0.013	0.05	<0.1	0.03	1.3	0.2	<0.05	5	0.6	<0.2
1281164	Soil	12	0.07	86	0.007	<1	0.61	0.010	0.04	0.1	0.01	1.1	0.2	<0.05	4	0.7	<0.2
1281165	Soil	9	0.04	58	0.006	2	0.37	0.018	0.04	<0.1	0.03	0.4	0.1	<0.05	3	<0.5	<0.2
1281166	Soil	12	0.04	62	0.008	<1	0.56	0.006	0.04	<0.1	0.02	0.8	0.1	<0.05	5	<0.5	<0.2
1281167	Soil	9	0.07	71	0.004	2	0.56	0.007	0.05	<0.1	0.05	0.4	0.1	<0.05	4	1.2	<0.2
1281168	Soil	8	0.32	181	0.007	2	0.65	0.015	0.02	0.2	0.10	0.5	0.1	0.17	2	1.0	<0.2
1281169	Soil	4	0.01	39	0.005	<1	0.18	0.016	0.03	<0.1	0.03	0.4	<0.1	<0.05	1	1.2	<0.2
1281170	Soil	8	0.19	113	0.001	2	0.45	0.004	0.07	<0.1	0.54	5.6	0.5	0.09	<1	4.3	<0.2
1281171	Soil	10	0.14	137	0.002	3	0.52	0.010	0.06	<0.1	0.45	3.9	0.2	0.09	1	2.3	<0.2
1281172	Soil	11	0.31	158	0.001	5	0.63	0.004	0.07	<0.1	0.53	4.9	0.2	0.09	1	2.4	<0.2
1281173	Soil	6	0.19	129	0.003	9	0.36	0.012	0.04	<0.1	0.18	1.4	0.1	0.14	<1	2.4	<0.2
1281174	Soil	20	0.44	409	0.004	2	1.17	0.004	0.11	<0.1	0.10	2.1	0.2	<0.05	4	0.8	<0.2
1281175	Soil	24	0.54	292	0.005	3	1.26	0.005	0.14	<0.1	0.15	3.9	0.2	<0.05	3	0.9	<0.2
1281176	Soil	21	0.37	190	0.005	4	1.00	0.004	0.11	<0.1	0.07	2.0	0.1	<0.05	4	<0.5	<0.2
1281177	Soil	16	0.07	2351	0.006	2	0.48	0.007	0.05	0.2	0.03	0.9	0.2	0.06	3	1.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281178	Soil	3.0	25.4	8.7	58	0.3	14.8	8.4	401	1.59	5.7	3.7	1.3	14	0.2	0.9	0.1	33	0.15	0.120	12
1281179	Soil	3.8	51.1	12.7	118	0.4	31.7	14.5	356	2.80	9.2	4.1	3.7	34	0.6	1.4	0.2	45	0.49	0.147	23
1281180	Soil	3.3	27.7	11.0	51	0.2	13.8	8.7	502	1.67	7.1	2.0	1.4	20	0.4	0.8	0.2	34	0.28	0.075	13
1281181	Soil	0.8	68.4	12.3	34	0.6	24.2	4.8	95	1.31	2.3	3.0	1.6	29	1.3	0.6	0.2	18	0.41	0.131	20
1281182	Soil	0.5	21.1	5.4	18	0.4	7.1	1.3	38	0.55	1.3	2.7	0.8	28	0.3	0.2	<0.1	18	0.58	0.080	10
1281183	Soil	2.9	33.9	12.2	61	0.9	18.6	15.4	1827	1.77	5.7	4.9	0.9	19	0.5	0.7	0.2	36	0.30	0.144	14
1281184	Soil	2.5	27.5	9.8	60	0.2	15.8	7.1	152	1.54	5.6	2.4	1.3	24	0.2	0.9	0.2	35	0.37	0.081	15
1281185	Soil	1.3	23.7	5.3	30	0.4	12.2	5.1	489	0.89	3.1	3.3	0.5	97	0.6	0.7	<0.1	17	2.15	0.090	9
1281186	Soil	5.5	86.9	21.3	127	1.5	43.9	17.6	570	3.77	12.4	8.5	2.7	51	1.0	2.1	0.2	32	0.98	0.154	24
1281187	Soil	4.0	56.3	10.8	78	0.9	27.3	10.9	396	2.52	8.6	6.5	1.8	46	0.4	1.1	0.2	32	0.95	0.110	18
1281188	Soil	4.0	23.5	10.3	56	0.3	13.2	4.2	83	1.71	6.1	3.8	1.0	21	0.4	1.0	0.1	20	0.35	0.096	9
1281189	Soil	6.8	64.0	12.0	124	1.1	34.8	13.1	400	3.01	12.0	6.6	3.2	39	0.8	1.5	0.2	33	0.87	0.121	17
1281190	Soil	3.7	42.7	9.0	69	0.6	23.3	8.9	516	1.77	6.2	3.7	1.2	65	0.9	1.0	0.1	22	1.79	0.116	11
1281191	Soil	2.7	39.4	9.3	93	0.3	22.1	10.4	357	1.95	10.0	7.8	2.2	24	0.4	2.1	0.2	30	0.24	0.114	11
1281192	Soil	2.6	23.8	10.9	61	0.6	13.0	11.9	695	2.28	9.6	6.8	1.7	15	0.3	1.5	0.2	48	0.13	0.087	9
1281193	Soil	3.0	26.0	9.3	67	0.5	12.8	11.0	494	2.36	9.4	6.4	2.0	13	0.2	1.5	0.2	42	0.09	0.089	11
1281194	Soil	1.7	12.5	4.7	27	0.7	5.3	1.8	76	0.79	4.1	1.9	0.3	6	0.1	0.6	<0.1	20	0.05	0.058	5
1281195	Soil	1.1	15.3	3.7	26	0.8	7.8	2.2	65	0.68	3.1	4.2	0.7	14	<0.1	0.7	0.1	21	0.17	0.067	5
1281196	Soil	0.9	17.5	5.8	26	0.8	6.3	1.4	28	0.79	4.8	2.7	0.9	13	0.2	0.5	0.1	28	0.10	0.066	7
1281197	Soil	0.9	22.0	5.4	35	1.4	11.1	2.5	54	1.24	3.0	9.9	1.0	13	0.4	0.6	0.1	23	0.11	0.093	5
1281198	Soil	2.7	27.7	10.7	70	1.0	15.1	5.0	172	2.10	10.4	5.0	1.7	20	0.5	1.0	0.2	44	0.25	0.100	12
1281199	Soil	2.1	15.4	7.9	57	0.9	10.3	14.0	743	1.86	8.3	3.1	1.3	22	0.5	1.3	0.1	41	0.22	0.085	7
1281200	Soil	2.5	27.9	10.7	58	0.4	11.4	9.1	708	2.22	10.3	5.6	1.9	31	0.4	1.8	0.2	41	0.33	0.088	11
1281251	Soil	2.2	29.1	9.5	109	0.4	19.1	6.9	332	1.82	9.4	3.8	1.7	40	0.6	1.4	0.2	41	0.50	0.082	9
1281252	Soil	2.6	30.9	8.8	80	0.4	20.3	6.5	277	1.91	8.8	6.8	1.1	64	0.7	1.5	0.3	28	1.39	0.111	12
1281253	Soil	2.8	40.2	9.9	111	0.7	23.3	7.7	347	2.17	10.8	6.1	1.3	72	0.7	2.0	0.2	36	1.34	0.121	11
1281254	Soil	3.9	25.1	15.5	61	2.2	10.8	1.9	71	1.55	14.9	7.5	1.1	30	0.9	2.2	0.3	84	0.34	0.131	10
1281255	Soil	12.5	54.6	14.7	226	1.2	42.1	23.9	1321	2.34	20.9	5.3	1.4	57	2.5	5.8	0.2	111	0.52	0.132	13
1281256	Soil	17.8	104.3	21.4	495	2.0	84.7	13.4	317	3.54	39.5	9.0	2.4	69	4.0	12.8	0.3	186	0.21	0.261	18
1281257	Soil	14.4	40.2	15.9	173	0.9	33.5	4.5	142	3.26	31.4	3.8	1.6	23	0.6	7.0	0.3	191	0.06	0.358	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281178	Soil	18	0.24	277	0.003	2	0.83	0.009	0.08	<0.1	0.05	1.8	0.1	<0.05	3	0.5	<0.2
1281179	Soil	24	0.58	300	0.006	4	1.26	0.005	0.13	<0.1	0.13	3.9	0.1	<0.05	4	1.2	<0.2
1281180	Soil	16	0.22	210	0.004	1	0.76	0.009	0.09	<0.1	0.06	1.8	0.2	<0.05	3	0.8	<0.2
1281181	Soil	16	0.18	259	0.005	2	0.91	0.005	0.06	<0.1	0.25	3.1	0.1	0.10	2	3.0	<0.2
1281182	Soil	12	0.20	165	0.004	2	0.59	0.011	0.07	<0.1	0.10	1.4	0.2	<0.05	2	0.7	<0.2
1281183	Soil	21	0.29	275	0.006	2	1.04	0.008	0.07	<0.1	0.24	2.4	0.2	0.06	3	1.1	<0.2
1281184	Soil	22	0.32	153	0.004	3	0.85	0.004	0.11	<0.1	0.05	1.7	0.1	<0.05	4	0.8	<0.2
1281185	Soil	10	0.25	149	0.005	3	0.55	0.011	0.04	<0.1	0.15	1.6	<0.1	0.13	1	1.1	<0.2
1281186	Soil	19	0.59	212	0.003	3	1.09	0.005	0.09	<0.1	0.35	6.2	0.2	0.05	3	1.6	0.2
1281187	Soil	16	0.43	300	0.004	3	1.08	0.007	0.08	<0.1	0.29	4.1	0.2	0.05	3	1.6	<0.2
1281188	Soil	9	0.15	214	0.004	2	0.48	0.007	0.06	<0.1	0.13	1.7	0.1	0.06	2	<0.5	<0.2
1281189	Soil	18	0.58	184	0.003	3	1.05	0.006	0.08	<0.1	0.30	5.1	0.2	<0.05	3	1.9	<0.2
1281190	Soil	13	0.33	240	0.003	3	0.68	0.009	0.06	<0.1	0.20	2.8	0.2	0.11	2	0.9	<0.2
1281191	Soil	10	0.12	1355	0.003	3	0.56	0.003	0.10	<0.1	0.10	2.2	0.1	<0.05	2	0.9	<0.2
1281192	Soil	16	0.19	559	0.002	4	0.98	0.006	0.15	<0.1	0.20	2.3	0.2	<0.05	3	1.1	<0.2
1281193	Soil	13	0.16	448	0.003	4	0.90	0.005	0.13	<0.1	0.16	2.1	0.1	<0.05	3	0.5	<0.2
1281194	Soil	6	0.06	182	0.004	2	0.39	0.011	0.06	<0.1	0.07	0.7	0.1	<0.05	2	<0.5	<0.2
1281195	Soil	9	0.07	442	0.002	4	0.50	0.009	0.09	<0.1	0.16	1.4	0.1	<0.05	2	0.6	<0.2
1281196	Soil	9	0.08	341	0.002	2	0.63	0.005	0.10	<0.1	0.22	1.4	0.2	<0.05	2	<0.5	<0.2
1281197	Soil	11	0.09	456	0.002	3	0.64	0.009	0.09	<0.1	0.25	2.0	0.2	<0.05	2	1.1	<0.2
1281198	Soil	14	0.19	453	0.003	2	0.85	0.005	0.09	<0.1	0.27	2.8	0.2	<0.05	3	1.3	<0.2
1281199	Soil	10	0.11	532	0.003	3	0.65	0.009	0.09	<0.1	0.21	1.8	0.1	<0.05	2	0.8	<0.2
1281200	Soil	10	0.12	649	0.002	2	0.74	0.004	0.08	<0.1	0.23	2.7	0.1	<0.05	2	1.4	<0.2
1281251	Soil	11	0.13	1019	0.002	3	0.72	0.004	0.09	<0.1	0.20	2.5	0.1	<0.05	2	0.5	<0.2
1281252	Soil	10	0.18	759	0.001	5	0.61	0.006	0.07	<0.1	0.23	2.7	0.1	0.17	2	1.0	<0.2
1281253	Soil	12	0.23	622	0.002	4	0.62	0.006	0.09	<0.1	0.26	2.7	0.2	0.13	2	1.4	<0.2
1281254	Soil	17	0.08	457	0.002	2	0.56	0.004	0.07	<0.1	0.44	1.4	0.3	0.07	3	1.6	<0.2
1281255	Soil	18	0.12	1481	0.002	3	0.58	0.005	0.07	<0.1	0.30	2.2	0.3	0.08	2	3.1	<0.2
1281256	Soil	27	0.08	1728	0.003	4	0.59	0.003	0.10	0.1	0.33	3.3	0.6	0.08	2	5.2	<0.2
1281257	Soil	28	0.05	664	0.004	2	0.82	0.003	0.06	0.1	0.12	1.1	0.5	<0.05	3	3.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281258	Soil	7.0	18.8	15.3	107	2.7	16.9	3.1	157	2.96	18.3	1.9	1.0	13	0.6	3.6	0.3	107	0.03	0.110	15
1281259	Soil	10.7	20.2	15.4	127	0.8	26.2	2.7	56	1.98	23.8	1.5	1.1	20	0.2	4.9	0.4	180	0.04	0.141	17
1281260	Soil	13.6	38.7	15.3	173	2.0	37.7	3.6	67	2.98	32.7	3.2	1.4	27	1.0	7.0	0.3	222	0.08	0.423	15
1281301	Soil	4.5	28.8	15.5	59	0.5	12.2	8.2	338	2.18	10.5	3.5	2.7	17	0.3	1.3	0.3	53	0.15	0.095	17
1281302	Soil	7.3	17.3	3.4	60	<0.1	12.3	2.3	27	0.75	7.8	1.9	0.4	5	0.1	2.1	<0.1	77	0.02	0.024	16
1281303	Soil	14.4	35.5	13.4	176	0.3	33.4	4.5	58	1.81	20.4	1.2	0.3	9	0.4	6.0	0.3	158	0.01	0.093	16
1281304	Soil	11.9	44.3	16.6	242	0.8	40.0	6.7	214	2.27	26.0	3.1	0.6	42	1.1	7.1	0.3	139	0.14	0.186	14
1281305	Soil	15.8	71.6	14.5	414	1.2	67.6	8.7	134	2.46	25.9	3.1	3.4	55	4.0	9.8	0.3	155	0.26	0.159	19
1281306	Soil	10.3	36.6	18.3	153	0.3	26.9	5.3	114	2.65	23.4	0.5	0.3	14	0.3	3.9	0.4	85	0.01	0.096	13
1281307	Soil	13.7	45.6	21.2	203	0.5	38.4	6.2	135	2.90	41.4	1.7	0.4	19	0.4	5.9	0.4	143	0.02	0.138	11
1281308	Soil	25.3	38.7	18.3	213	0.5	37.9	3.7	126	2.01	27.0	<0.5	0.5	23	0.5	7.0	0.3	173	0.02	0.101	20
1281309	Soil	22.1	78.8	15.1	293	0.6	64.0	7.9	446	3.34	29.1	6.1	0.8	29	2.9	7.7	0.3	132	0.18	0.154	19
1281310	Soil	8.7	29.5	8.9	123	0.7	25.2	2.3	32	1.08	11.5	1.5	1.2	16	0.6	2.7	0.1	90	0.05	0.077	17
1281311	Soil	24.2	136.8	20.3	506	1.7	74.6	13.0	287	3.16	50.5	6.0	3.2	82	8.1	17.9	0.3	320	0.37	0.252	24
1281312	Soil	21.8	34.9	15.1	209	0.6	44.8	4.4	51	1.74	27.2	1.0	0.5	20	0.3	6.3	0.2	139	0.01	0.063	20
1281313	Soil	13.5	24.1	14.4	124	0.3	24.7	3.3	44	1.30	18.9	<0.5	0.6	15	0.2	3.9	0.2	90	0.01	0.037	19
1281314	Soil	13.1	29.5	7.5	128	0.3	28.9	4.4	47	1.58	21.0	<0.5	0.3	7	0.2	4.1	0.2	78	<0.01	0.030	14
1281315	Soil	11.3	121.7	8.3	298	0.1	51.2	8.6	75	2.51	30.3	11.8	<0.1	8	0.2	5.4	0.2	66	0.02	0.085	7
1281316	Soil	3.6	24.4	11.6	61	0.1	13.1	3.2	55	1.23	15.6	1.1	0.2	10	<0.1	1.8	0.3	41	0.02	0.035	16
1281317	Soil	3.0	43.9	10.9	101	0.1	19.8	8.1	130	2.20	11.2	5.4	0.3	8	0.3	1.7	0.2	26	0.04	0.126	5
1281318	Soil	9.0	32.5	6.2	106	<0.1	23.4	5.2	75	1.68	16.8	1.6	0.2	6	0.2	3.3	0.2	84	<0.01	0.039	14
1281319	Soil	9.3	68.8	20.5	123	1.2	38.2	6.7	86	2.60	50.3	8.7	1.0	53	1.1	10.1	0.3	87	0.04	0.117	11
1281320	Soil	4.9	20.7	14.7	62	0.1	19.2	3.8	83	1.56	18.8	1.0	0.6	11	0.1	2.8	0.3	61	0.02	0.041	13
1281321	Soil	7.6	23.4	10.0	91	0.2	22.5	3.4	55	1.20	13.3	<0.5	0.2	13	0.2	3.1	0.2	68	0.07	0.043	12
1281322	Soil	8.3	22.7	5.1	75	<0.1	18.7	3.4	52	1.13	12.7	0.8	0.1	6	0.2	2.5	<0.1	72	0.01	0.043	14
1281323	Soil	8.8	62.7	47.8	145	0.8	43.0	8.8	510	3.76	32.2	5.0	0.7	165	0.7	4.3	0.5	62	0.22	0.317	15
1281324	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281325	Soil	13.1	63.1	20.2	243	0.6	47.2	13.7	496	3.48	16.8	6.8	1.0	39	2.0	4.5	0.3	92	0.12	0.176	15
1281326	Soil	28.7	105.3	14.8	493	1.2	101.3	9.4	305	2.52	21.3	3.8	1.9	74	4.4	10.2	0.2	178	0.62	0.167	19
1281327	Soil	4.1	40.4	14.0	182	2.3	28.7	5.9	236	2.08	13.6	12.8	1.5	47	0.9	2.5	0.2	106	0.54	0.093	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281258	Soil	18	0.06	373	0.010	2	0.73	0.004	0.06	0.1	0.06	1.0	0.3	<0.05	4	2.2	<0.2
1281259	Soil	20	0.06	220	0.007	2	0.65	0.002	0.07	0.1	0.03	0.9	0.4	<0.05	5	2.2	<0.2
1281260	Soil	30	0.06	620	0.004	2	0.97	0.002	0.07	0.1	0.19	1.4	0.5	0.05	3	3.9	<0.2
1281301	Soil	17	0.28	447	0.001	2	1.01	0.003	0.10	<0.1	0.21	1.8	0.2	<0.05	3	0.9	<0.2
1281302	Soil	10	0.03	125	0.003	2	0.29	0.005	0.05	<0.1	0.01	0.4	0.2	<0.05	2	1.0	<0.2
1281303	Soil	17	0.05	228	0.002	2	0.51	0.003	0.08	0.1	0.05	0.3	0.4	<0.05	4	2.6	<0.2
1281304	Soil	21	0.06	1329	0.003	2	0.56	0.005	0.07	0.1	0.11	1.1	0.3	0.06	3	3.1	<0.2
1281305	Soil	23	0.10	1658	0.004	3	0.46	0.003	0.09	0.1	0.16	2.7	0.4	0.07	2	4.0	<0.2
1281306	Soil	13	0.05	262	0.004	2	0.54	0.004	0.08	0.1	0.04	0.4	0.3	0.06	3	1.9	<0.2
1281307	Soil	18	0.05	235	0.003	3	0.56	0.006	0.07	0.1	0.08	0.4	0.4	0.06	3	2.6	<0.2
1281308	Soil	20	0.04	297	0.003	2	0.49	0.005	0.09	0.1	0.05	0.8	0.6	0.07	3	3.0	<0.2
1281309	Soil	16	0.07	572	0.002	2	0.54	0.006	0.07	<0.1	0.21	1.6	0.4	<0.05	2	2.7	<0.2
1281310	Soil	14	0.05	446	0.001	<1	0.58	0.005	0.07	<0.1	0.15	1.3	0.3	<0.05	2	0.8	<0.2
1281311	Soil	38	0.07	2093	0.003	5	0.59	0.002	0.11	0.1	0.67	3.6	0.6	0.06	2	9.2	0.2
1281312	Soil	17	0.04	259	0.002	3	0.51	0.003	0.08	0.1	0.04	0.6	0.4	<0.05	3	2.1	<0.2
1281313	Soil	10	0.03	137	0.004	<1	0.31	0.004	0.06	0.1	0.03	0.6	0.3	<0.05	3	1.5	<0.2
1281314	Soil	8	0.02	90	0.004	<1	0.23	0.006	0.04	0.1	0.02	0.5	0.2	<0.05	2	1.2	<0.2
1281315	Soil	10	0.02	81	0.002	2	0.29	0.010	0.06	<0.1	0.07	0.3	0.1	<0.05	2	2.7	<0.2
1281316	Soil	9	0.03	83	0.008	<1	0.38	0.004	0.06	0.1	0.01	0.3	0.2	<0.05	3	0.5	<0.2
1281317	Soil	7	0.04	125	0.002	2	0.42	0.009	0.07	<0.1	0.06	0.5	0.1	<0.05	2	0.7	<0.2
1281318	Soil	9	0.03	185	0.003	2	0.32	0.005	0.06	<0.1	0.02	0.3	0.1	<0.05	2	1.0	<0.2
1281319	Soil	13	0.02	1087	0.002	2	0.33	0.004	0.07	<0.1	0.23	2.0	0.3	0.11	1	4.1	<0.2
1281320	Soil	17	0.05	151	0.011	<1	0.45	0.004	0.06	0.1	0.03	0.8	0.2	<0.05	5	0.8	<0.2
1281321	Soil	13	0.03	168	0.004	2	0.34	0.007	0.07	<0.1	0.02	0.5	0.2	<0.05	2	0.9	<0.2
1281322	Soil	17	0.02	162	0.004	2	0.27	0.005	0.06	<0.1	0.02	0.2	0.1	<0.05	2	0.9	<0.2
1281323	Soil	18	0.06	920	0.003	3	0.73	0.007	0.16	<0.1	0.17	1.7	0.2	0.21	2	3.5	0.3
1281324	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281325	Soil	21	0.15	664	0.003	3	0.84	0.005	0.14	<0.1	0.14	1.8	0.4	0.12	3	2.2	<0.2
1281326	Soil	21	0.18	958	0.003	4	0.58	0.004	0.14	<0.1	0.64	2.8	0.5	0.11	2	4.2	<0.2
1281327	Soil	24	0.20	1158	0.002	3	1.07	0.012	0.13	<0.1	0.56	3.6	0.4	0.07	3	2.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281328	Soil	1.4	8.4	4.2	28	0.6	7.8	0.8	24	0.35	1.6	2.7	0.2	15	0.3	0.6	<0.1	17	0.13	0.032	2
1281329	Soil	3.4	36.3	9.5	132	1.3	28.1	5.1	164	1.55	8.6	8.3	0.8	46	1.5	2.0	0.2	43	0.35	0.134	7
1281330	Soil	2.9	24.5	9.3	76	0.2	17.7	3.9	135	1.26	6.5	2.7	0.5	24	0.4	1.5	0.1	31	0.13	0.094	5
1281331	Soil	4.4	39.9	13.2	152	0.4	27.0	10.3	585	3.16	18.5	9.6	0.7	30	1.1	3.4	0.3	52	0.25	0.211	13
1281332	Soil	4.7	39.2	16.7	98	0.2	22.9	7.2	244	1.80	13.3	5.9	0.8	12	0.4	2.9	0.2	43	0.04	0.094	11
1281333	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281334	Soil	5.4	53.9	14.5	159	0.5	32.6	8.7	238	2.86	15.3	5.0	2.1	26	0.6	2.9	0.3	54	0.17	0.153	12
1281335	Soil	5.4	73.5	17.0	134	0.3	30.0	9.0	176	3.91	18.6	4.8	2.1	16	0.4	3.1	0.3	57	0.10	0.242	10
1281336	Soil	1.4	22.0	4.9	36	0.4	8.0	2.1	41	0.87	4.1	2.4	0.1	10	0.3	0.8	<0.1	21	0.06	0.128	4
1281337	Soil	2.6	65.0	8.7	76	0.8	18.8	4.2	142	1.59	5.3	1.3	0.3	19	3.6	1.4	0.2	36	0.07	0.248	10
1281338	Soil	3.4	68.7	13.1	73	0.5	21.6	8.1	402	2.96	10.3	4.4	0.4	13	0.4	1.8	0.3	46	0.08	0.133	10
1281339	Soil	6.9	132.0	22.2	160	0.7	33.3	14.8	151	4.33	18.1	4.2	0.3	22	1.8	3.2	0.3	47	0.11	0.232	16
1281340	Soil	5.4	129.9	27.1	199	0.7	29.4	15.1	337	5.17	17.8	6.4	0.7	23	1.9	3.3	0.3	74	0.22	0.236	19

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001219.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281328	Soil	9	0.06	463	0.004	1	0.25	0.024	0.04	<0.1	0.08	0.7	<0.1	<0.05	<1	0.5	<0.2
1281329	Soil	15	0.20	616	0.008	4	0.64	0.013	0.11	0.1	0.21	2.2	0.2	<0.05	2	0.7	<0.2
1281330	Soil	12	0.10	360	0.006	2	0.43	0.012	0.07	<0.1	0.04	1.0	0.1	0.06	2	1.2	<0.2
1281331	Soil	19	0.11	824	0.006	2	0.74	0.004	0.07	0.1	0.09	1.9	0.2	<0.05	3	1.7	<0.2
1281332	Soil	16	0.05	482	0.008	2	0.44	0.004	0.08	<0.1	0.03	1.6	0.2	<0.05	2	1.2	<0.2
1281333	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281334	Soil	16	0.17	433	0.009	2	0.72	0.004	0.12	<0.1	0.04	2.4	0.1	<0.05	3	1.2	<0.2
1281335	Soil	18	0.13	315	0.008	1	0.84	0.005	0.09	0.1	0.04	2.3	0.2	<0.05	3	1.3	<0.2
1281336	Soil	7	0.06	291	0.003	<1	0.51	0.020	0.04	<0.1	0.03	0.3	<0.1	<0.05	2	0.5	<0.2
1281337	Soil	16	0.05	622	0.005	<1	0.87	0.010	0.09	<0.1	0.03	0.5	<0.1	0.12	3	<0.5	<0.2
1281338	Soil	20	0.14	266	0.007	1	0.77	0.009	0.07	<0.1	0.04	0.5	0.1	0.07	3	1.1	<0.2
1281339	Soil	15	0.08	661	0.003	1	0.80	0.004	0.11	<0.1	0.08	0.8	0.2	0.09	3	2.1	<0.2
1281340	Soil	27	0.81	983	0.008	2	1.58	0.008	0.18	0.1	0.06	1.4	0.2	0.07	5	2.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

QUALITY CONTROL REPORT WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1281002	Soil	14.5	83.9	38.2	337	1.0	96.4	14.1	464	3.21	37.2	4.4	1.3	124	1.7	9.1	0.4	67	0.90	0.533	21
REP 1281002	QC	14.2	80.9	37.0	327	0.9	91.9	14.2	443	3.14	36.2	4.8	1.7	120	1.6	9.6	0.4	64	0.91	0.533	22
1281008	Soil	13.5	30.4	15.3	379	0.3	51.3	4.2	94	1.23	15.9	1.4	0.3	28	2.7	3.7	0.2	61	0.36	0.074	3
REP 1281008	QC	13.2	30.8	15.5	378	0.3	53.0	4.0	94	1.22	16.0	0.7	0.3	27	2.8	3.8	0.2	59	0.36	0.070	3
1281059	Soil	4.9	190.1	24.8	255	0.2	79.2	25.2	515	5.76	24.5	44.8	0.8	13	0.3	5.1	0.5	46	0.05	0.110	10
REP 1281059	QC	4.5	187.8	25.3	251	0.2	76.7	25.6	495	5.71	24.2	27.9	0.8	13	0.3	5.1	0.5	46	0.04	0.104	10
1281078	Soil	12.1	153.7	31.7	265	2.1	66.2	19.9	642	7.05	32.9	10.0	4.8	71	2.0	4.4	0.3	35	0.27	0.278	20
REP 1281078	QC	12.2	159.9	31.5	273	2.2	68.0	20.8	669	7.37	34.3	10.0	4.8	71	1.9	4.7	0.3	36	0.29	0.290	20
1281092	Soil	4.1	40.1	14.5	90	1.7	21.9	10.4	617	2.49	7.0	6.7	1.3	29	0.9	1.3	0.2	43	0.44	0.178	17
REP 1281092	QC	4.3	39.7	15.2	88	1.6	22.0	10.3	606	2.47	7.4	7.0	1.4	29	1.0	1.3	0.2	44	0.45	0.180	17
1281165	Soil	1.9	8.9	5.6	40	<0.1	7.0	1.8	56	1.18	6.1	0.5	<0.1	8	0.2	1.1	0.1	28	0.03	0.053	3
REP 1281165	QC	1.6	8.5	4.9	36	<0.1	6.2	1.8	52	1.07	5.8	<0.5	<0.1	7	0.2	1.0	0.1	25	0.03	0.051	3
1281172	Soil	6.1	98.8	10.2	149	1.5	46.2	6.9	95	2.15	9.9	4.5	1.2	56	1.8	3.5	0.2	21	2.18	0.086	9
REP 1281172	QC	5.5	94.1	9.9	147	1.5	44.9	6.9	90	2.13	9.5	5.1	1.2	52	1.8	3.5	0.2	22	2.05	0.084	9
1281186	Soil	5.5	86.9	21.3	127	1.5	43.9	17.6	570	3.77	12.4	8.5	2.7	51	1.0	2.1	0.2	32	0.98	0.154	24
REP 1281186	QC	5.4	88.0	21.4	124	1.5	45.6	18.1	584	3.86	12.9	12.4	2.8	52	1.1	2.1	0.2	36	1.00	0.163	25
1281301	Soil	4.5	28.8	15.5	59	0.5	12.2	8.2	338	2.18	10.5	3.5	2.7	17	0.3	1.3	0.3	53	0.15	0.095	17
REP 1281301	QC	4.5	28.8	15.7	59	0.5	12.7	8.3	338	2.21	10.4	4.5	2.8	17	0.3	1.4	0.3	59	0.15	0.095	18
Reference Materials																					
STD DS8	Standard	11.2	106.9	120.5	316	1.9	36.0	7.2	588	2.38	24.9	112.1	6.1	62	2.3	5.4	6.7	39	0.64	0.079	12
STD DS8	Standard	12.5	110.3	121.4	311	1.7	37.8	7.6	601	2.45	24.6	115.1	6.5	65	2.4	5.4	6.6	43	0.66	0.079	13
STD DS8	Standard	12.6	103.0	115.7	294	1.7	36.0	7.0	578	2.34	23.8	114.0	6.1	63	2.2	5.4	6.2	40	0.66	0.074	14
STD DS8	Standard	12.9	107.3	125.2	303	1.7	36.1	7.3	587	2.36	24.8	112.0	7.0	66	2.3	5.7	6.7	41	0.67	0.081	16
STD DS8	Standard	12.9	105.6	120.0	298	1.7	36.1	7.1	591	2.33	23.2	100.8	7.0	76	2.2	6.2	7.6	41	0.68	0.075	16
STD DS8	Standard	13.3	113.4	117.9	308	1.7	38.9	8.1	607	2.43	24.8	109.5	6.9	72	2.6	5.7	6.8	43	0.75	0.081	16
STD DS8	Standard	13.4	114.4	119.4	302	1.6	37.6	7.7	613	2.45	25.1	101.4	6.8	68	2.3	5.5	6.4	43	0.68	0.075	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

QUALITY CONTROL REPORT WHI11001219.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1281002	Soil	18	0.07	846	0.006	5	0.50	0.004	0.16	<0.1	0.25	1.8	0.2	0.08	1	5.8	0.2
REP 1281002	QC	17	0.07	852	0.007	7	0.48	0.004	0.15	<0.1	0.23	2.7	0.2	0.06	1	7.1	0.3
1281008	Soil	9	0.05	158	0.003	<1	0.40	0.012	0.03	<0.1	0.08	1.0	0.3	<0.05	2	1.9	<0.2
REP 1281008	QC	8	0.04	156	0.003	<1	0.39	0.012	0.02	<0.1	0.09	0.9	0.4	<0.05	2	1.5	<0.2
1281059	Soil	14	0.11	84	0.010	<1	0.64	0.004	0.04	0.2	0.06	2.7	0.1	<0.05	3	2.5	0.3
REP 1281059	QC	14	0.11	85	0.012	<1	0.63	0.004	0.04	0.2	0.05	2.7	0.1	<0.05	3	2.2	0.3
1281078	Soil	18	0.26	383	0.007	<1	0.95	0.011	0.12	<0.1	0.20	6.8	0.4	0.15	2	2.6	<0.2
REP 1281078	QC	19	0.27	378	0.008	1	0.98	0.011	0.12	<0.1	0.20	7.1	0.5	0.17	2	3.3	<0.2
1281092	Soil	19	0.38	196	0.006	2	0.97	0.007	0.08	<0.1	0.36	3.2	0.2	0.05	3	1.6	<0.2
REP 1281092	QC	19	0.37	199	0.007	3	0.97	0.008	0.09	<0.1	0.36	3.2	0.2	<0.05	3	1.9	<0.2
1281165	Soil	9	0.04	58	0.006	2	0.37	0.018	0.04	<0.1	0.03	0.4	0.1	<0.05	3	<0.5	<0.2
REP 1281165	QC	7	0.03	53	0.005	1	0.33	0.017	0.04	<0.1	0.02	0.2	0.1	<0.05	3	<0.5	<0.2
1281172	Soil	11	0.31	158	0.001	5	0.63	0.004	0.07	<0.1	0.53	4.9	0.2	0.09	1	2.4	<0.2
REP 1281172	QC	11	0.32	153	0.002	6	0.65	0.004	0.07	<0.1	0.56	4.8	0.3	0.09	1	2.0	<0.2
1281186	Soil	19	0.59	212	0.003	3	1.09	0.005	0.09	<0.1	0.35	6.2	0.2	0.05	3	1.6	0.2
REP 1281186	QC	20	0.62	230	0.004	4	1.18	0.005	0.11	<0.1	0.39	6.5	0.2	<0.05	3	2.2	0.2
1281301	Soil	17	0.28	447	0.001	2	1.01	0.003	0.10	<0.1	0.21	1.8	0.2	<0.05	3	0.9	<0.2
REP 1281301	QC	18	0.29	461	0.002	3	1.06	0.003	0.12	<0.1	0.22	2.1	0.2	<0.05	3	1.0	<0.2
Reference Materials																	
STD DS8	Standard	114	0.60	261	0.105	2	0.88	0.085	0.42	3.0	0.19	2.2	5.3	0.15	4	5.4	4.7
STD DS8	Standard	118	0.62	265	0.112	3	0.92	0.094	0.41	3.1	0.19	2.7	5.5	0.14	4	5.3	4.7
STD DS8	Standard	110	0.58	259	0.113	2	0.87	0.082	0.39	2.8	0.19	2.3	5.1	0.16	4	5.0	4.7
STD DS8	Standard	109	0.59	275	0.107	2	0.91	0.098	0.41	2.8	0.20	2.2	5.2	0.15	4	4.9	4.7
STD DS8	Standard	113	0.59	289	0.128	3	0.97	0.126	0.44	2.9	0.21	3.5	5.1	0.15	5	5.4	4.4
STD DS8	Standard	122	0.62	289	0.137	2	0.98	0.114	0.43	2.9	0.19	2.6	5.1	0.16	5	5.0	4.9
STD DS8	Standard	118	0.60	266	0.116	3	0.98	0.110	0.42	2.7	0.18	2.7	5.3	0.11	5	4.8	4.9
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

QUALITY CONTROL REPORT WHI11001219.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

QUALITY CONTROL REPORT WHI11001219.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 24, 2011
Report Date: October 24, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001220.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #16
P.O. Number
Number of Samples: 321

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve soil to 230 mesh			WHI
1DX2	320	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
RJSV	320	Saving all or part of Soil Reject			VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094971	Soil	48.7	23.1	8.7	133	<0.1	66.5	6.1	54	1.41	15.3	1.9	0.8	13	0.5	1.8	0.2	58	0.16	0.031	7
1094972	Soil	36.6	22.3	5.6	132	0.2	69.8	6.0	289	1.16	32.8	1.9	0.5	34	0.9	2.5	0.1	53	0.78	0.046	4
1094973	Soil	3.9	16.4	7.7	92	0.4	9.2	1.8	79	0.91	8.4	1.7	0.2	15	0.3	1.7	0.2	40	0.06	0.057	5
1094974	Soil	25.0	20.7	22.7	55	0.9	9.8	1.8	81	2.06	37.1	7.4	0.2	46	0.2	8.6	0.3	127	0.02	0.095	16
1094975	Soil	18.3	24.0	20.0	87	0.4	17.6	3.2	84	1.75	23.4	2.2	0.1	17	0.2	5.2	0.4	122	0.02	0.069	18
1094976	Soil	23.5	25.6	16.5	86	0.3	17.4	3.5	161	2.58	51.3	6.6	0.3	26	0.2	5.7	0.3	136	0.04	0.100	16
1094977	Soil	35.1	15.6	17.4	38	0.4	9.4	1.5	33	2.29	85.4	0.8	0.2	58	<0.1	4.9	0.3	240	0.01	0.121	10
1094978	Soil	11.5	37.2	22.0	112	0.3	21.7	4.7	85	2.04	30.3	4.3	0.1	20	0.2	4.7	0.3	102	0.01	0.075	9
1094979	Soil	29.4	40.7	22.6	30	2.1	7.7	1.1	39	1.60	35.2	5.2	0.9	60	0.1	12.1	0.3	130	0.03	0.088	14
1094980	Soil	10.8	21.5	15.0	74	0.3	19.0	3.2	87	1.65	17.6	3.4	0.1	21	0.4	3.2	0.3	79	0.02	0.071	11
1094981	Soil	15.7	94.9	79.6	122	0.7	540.0	64.3	893	7.28	167.7	10.0	4.2	122	0.6	12.6	0.2	95	0.99	0.198	19
1094982	Soil	14.4	106.2	81.2	112	0.7	610.2	79.4	923	7.23	146.0	10.8	5.6	121	0.3	15.6	0.2	91	0.91	0.225	21
1094983	Soil	5.3	123.9	34.0	92	0.4	671.4	88.5	1524	10.39	74.6	1.9	4.9	78	0.4	7.9	0.1	90	1.02	0.246	26
1094984	Soil	2.5	148.8	12.9	73	0.3	705.7	113.8	1426	10.88	17.3	2.3	9.8	175	0.2	2.8	0.1	128	1.88	0.362	39
1094985	Soil	2.1	97.1	12.9	69	0.2	579.4	68.8	952	8.29	7.6	<0.5	4.9	112	0.2	1.7	<0.1	94	1.30	0.327	23
1094986	Soil	18.9	69.3	11.8	144	0.2	434.7	39.8	688	7.26	8.7	1.4	4.9	57	0.7	1.3	0.1	174	0.73	0.322	25
1094987	Soil	17.6	90.6	10.1	164	0.2	501.4	56.2	708	6.06	12.4	0.7	4.5	62	1.3	3.4	0.1	103	0.71	0.375	23
1094988	Soil	53.2	41.3	7.3	263	0.9	168.3	10.2	78	2.40	21.9	1.7	0.2	16	0.4	7.0	0.1	170	0.05	0.101	11
1094989	Soil	138.3	109.5	15.6	1078	3.2	452.8	13.9	203	2.91	52.1	9.1	1.3	87	13.4	22.5	0.2	409	0.46	0.197	22
1094990	Soil	85.5	62.9	15.9	710	0.4	261.6	19.1	145	3.94	55.0	1.8	0.2	21	0.9	15.0	0.2	346	0.02	0.131	12
1277551	Soil	9.3	117.3	20.8	317	1.9	125.2	18.4	604	5.29	121.9	100.7	1.7	95	2.1	12.4	0.3	69	0.39	0.147	2
1277552	Soil	41.1	275.0	21.9	1486	11.0	256.2	7.3	210	3.00	51.0	1.6	1.5	192	27.4	22.4	0.3	600	0.97	0.430	24
1277561	Soil	88.1	107.3	11.4	1033	1.3	242.3	9.2	221	2.13	41.2	3.5	3.8	141	10.9	19.4	0.2	341	3.43	0.093	24
1277563	Soil	31.2	36.7	18.5	38	1.7	8.6	1.0	40	1.30	21.4	5.2	0.3	72	0.2	11.7	0.3	127	0.02	0.089	11
1277564	Soil	7.0	73.9	35.0	294	0.8	40.5	8.7	70	5.02	48.2	4.0	2.1	262	0.5	5.2	0.4	323	0.04	0.158	4
1277565	Soil	7.4	35.1	38.8	92	2.6	15.8	3.4	90	2.47	26.1	9.6	1.4	50	0.3	12.9	0.3	77	0.02	0.081	3
1277566	Soil	38.5	24.9	25.1	204	3.0	23.3	2.8	78	2.43	46.8	4.0	0.5	26	0.5	35.4	0.4	134	0.01	0.099	4
1277567	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1277568	Soil	109.2	59.1	8.3	2776	0.8	234.7	74.2	580	38.46	463.2	6.5	0.8	13	3.1	26.2	<0.1	82	<0.01	0.113	2
1277569	Soil	74.7	62.2	15.7	1666	1.0	195.3	61.9	666	18.82	242.4	10.3	1.2	20	24.5	15.5	0.2	131	0.05	0.198	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094971	Soil	9	0.05	249	0.003	2	0.46	0.003	0.04	0.2	0.04	1.0	0.5	0.12	2	1.2	<0.2
1094972	Soil	6	0.07	223	0.004	2	0.39	0.016	0.02	0.1	0.43	1.1	0.3	0.14	<1	1.1	<0.2
1094973	Soil	9	0.04	109	0.014	<1	0.67	0.013	0.04	0.1	0.07	0.3	0.1	0.12	3	2.5	0.2
1094974	Soil	16	0.04	314	0.005	2	0.55	0.003	0.10	0.1	0.46	0.1	1.3	0.28	4	7.2	0.3
1094975	Soil	16	0.03	169	0.009	<1	0.58	0.007	0.05	0.2	0.07	0.2	0.4	0.13	4	5.4	<0.2
1094976	Soil	21	0.10	206	0.006	1	0.54	0.005	0.07	0.1	0.09	0.4	0.7	0.14	4	4.4	0.2
1094977	Soil	14	0.02	306	0.003	<1	0.34	0.004	0.11	<0.1	0.05	0.2	1.1	0.29	3	3.6	0.2
1094978	Soil	12	0.02	134	0.007	1	0.43	0.002	0.05	<0.1	0.04	0.4	0.4	0.08	3	2.5	0.2
1094979	Soil	22	0.05	696	0.005	2	0.31	0.005	0.10	0.2	0.59	2.0	1.3	0.25	4	12.0	0.3
1094980	Soil	14	0.03	343	0.005	<1	0.50	0.008	0.05	0.1	0.03	0.1	0.4	0.06	4	2.3	<0.2
1094981	Soil	98	0.22	2072	0.003	5	0.58	0.008	0.09	0.3	0.32	12.1	0.5	0.21	2	4.5	<0.2
1094982	Soil	107	0.23	2195	0.005	4	0.61	0.011	0.10	0.3	0.37	12.5	0.5	0.24	2	3.5	0.3
1094983	Soil	154	0.24	1537	0.006	5	0.65	0.014	0.06	0.1	0.18	18.0	0.3	0.12	2	2.4	<0.2
1094984	Soil	219	0.59	3999	0.007	5	0.83	0.007	0.08	0.1	0.06	21.3	0.1	0.17	2	1.5	0.2
1094985	Soil	185	0.27	4969	0.005	5	1.07	0.008	0.06	<0.1	0.05	16.2	0.1	0.13	2	1.5	<0.2
1094986	Soil	170	0.18	3342	0.003	2	1.03	0.008	0.06	0.1	0.06	11.4	0.3	0.08	3	1.8	<0.2
1094987	Soil	128	0.18	2833	0.005	4	0.90	0.004	0.08	0.1	0.05	8.6	0.4	<0.05	2	3.6	<0.2
1094988	Soil	24	0.03	421	0.003	<1	0.50	0.011	0.04	0.1	0.03	0.5	0.7	<0.05	2	4.6	<0.2
1094989	Soil	38	0.04	1318	0.003	4	0.59	0.003	0.06	0.5	0.64	3.8	2.8	<0.05	<1	12.6	0.6
1094990	Soil	29	0.04	143	0.003	<1	0.44	0.003	0.05	0.2	0.04	0.4	1.3	0.05	3	8.9	0.2
1277551	Soil	16	0.09	851	0.001	4	0.46	0.004	0.10	<0.1	0.79	5.4	0.4	0.15	1	6.7	<0.2
1277552	Soil	118	0.13	1008	0.005	10	0.62	0.004	0.14	0.3	1.75	3.6	1.1	0.32	3	36.7	0.5
1277561	Soil	23	1.68	878	0.003	4	0.22	0.005	0.06	0.3	1.02	3.9	1.2	0.10	<1	6.6	<0.2
1277563	Soil	16	0.03	603	0.002	1	0.37	0.003	0.10	0.2	0.25	0.8	1.6	0.26	2	9.7	<0.2
1277564	Soil	24	0.03	659	0.002	2	0.81	0.002	0.10	<0.1	0.14	4.7	3.2	0.22	3	4.2	<0.2
1277565	Soil	17	0.03	713	0.003	<1	0.44	0.004	0.12	<0.1	0.57	3.4	1.0	0.25	2	5.7	<0.2
1277566	Soil	12	0.03	247	0.002	<1	0.44	0.004	0.07	0.2	0.08	1.4	0.8	0.14	2	8.5	0.2
1277567	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1277568	Soil	6	<0.01	330	0.001	<1	0.26	0.001	0.02	0.1	1.38	2.6	1.8	0.52	<1	7.9	<0.2
1277569	Soil	13	0.02	388	0.002	1	0.43	0.002	0.04	<0.1	2.43	2.9	2.2	<0.05	1	9.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1277576	Soil	8.9	64.2	16.2	331	0.6	118.3	20.1	3819	19.05	94.0	10.4	1.5	21	1.8	11.8	0.2	68	0.89	0.184	18
1278641	Soil	9.6	14.3	11.2	92	0.5	17.7	2.2	22	0.95	12.6	<0.5	0.9	26	0.2	3.2	0.2	67	0.02	0.023	7
1278642	Soil	9.2	29.9	13.9	194	0.4	32.1	4.0	86	2.39	31.5	2.9	1.0	26	1.2	4.9	0.2	96	0.05	0.081	6
1278643	Soil	10.4	51.9	17.1	323	1.2	65.5	8.7	268	2.51	51.2	7.6	1.5	73	3.7	5.4	0.3	79	0.45	0.143	10
1278644	Soil	16.3	89.1	22.8	309	1.5	71.4	7.1	140	2.89	37.6	7.3	2.4	139	3.3	8.5	0.3	125	0.39	0.153	9
1278645	Soil	2.7	29.9	16.0	131	0.1	30.2	9.5	146	1.95	13.0	<0.5	0.7	37	0.4	0.9	0.3	20	0.04	0.043	3
1278646	Soil	3.8	25.3	13.7	32	0.4	23.2	5.0	126	1.42	13.8	1.0	<0.1	18	<0.1	1.3	0.2	38	0.02	0.082	3
1278647	Soil	4.9	85.9	23.1	70	1.5	41.6	8.6	263	3.70	20.9	8.2	0.9	55	0.2	3.6	0.3	59	0.04	0.121	7
1278648	Soil	2.2	27.6	30.9	14	1.2	11.7	2.0	62	1.13	8.1	5.0	0.8	48	0.1	2.1	0.2	14	0.04	0.029	2
1278649	Soil	4.5	58.9	37.7	40	1.5	32.3	9.1	553	2.73	13.9	5.7	0.8	57	0.2	3.3	0.3	45	0.04	0.103	4
1278650	Soil	7.8	130.2	46.8	638	2.4	114.3	38.4	915	5.73	40.6	12.3	2.2	36	2.7	7.4	0.5	56	0.24	0.134	3
1278651	Soil	5.0	121.9	40.9	408	1.6	99.0	39.1	982	5.30	41.3	4.3	2.6	33	4.5	7.4	0.5	44	0.22	0.107	3
1278652	Soil	39.8	67.9	24.4	568	1.1	115.7	16.0	421	2.97	41.9	1.1	3.2	42	6.1	15.0	0.2	118	0.56	0.101	6
1278653	Soil	41.3	36.1	15.1	764	0.3	97.0	6.9	202	2.06	28.4	<0.5	3.7	102	8.1	20.5	<0.1	181	4.65	0.068	6
1278654	Soil	5.5	77.9	28.6	285	1.6	74.4	16.7	153	4.83	62.2	3.0	0.5	35	0.7	5.2	0.3	27	0.22	0.197	9
1278655	Soil	30.6	233.7	51.3	568	3.5	332.4	83.1	453	8.16	191.4	7.6	6.8	338	5.4	25.4	0.4	625	0.59	0.998	66
1278656	Soil	18.7	150.3	29.2	438	3.3	173.9	9.5	247	3.09	56.9	6.4	2.5	257	5.3	9.4	0.3	126	2.18	0.322	13
1278657	Soil	2.8	26.3	5.8	44	0.6	18.8	1.8	80	0.65	7.3	<0.5	0.2	35	0.8	1.4	<0.1	55	0.25	0.205	4
1278658	Soil	87.7	125.4	41.2	1380	5.0	292.1	31.6	555	6.19	138.3	4.9	0.9	137	13.4	24.0	0.4	244	0.30	0.301	16
1278659	Soil	44.3	129.3	70.6	630	3.4	128.6	16.9	357	4.26	81.4	4.7	1.2	287	6.5	14.0	0.4	361	0.84	0.898	24
1278660	Soil	53.0	117.0	116.5	287	7.0	83.5	7.5	337	5.31	79.7	5.6	3.8	303	2.2	13.4	0.7	341	0.57	0.775	25
1278661	Soil	35.3	92.8	65.0	252	4.3	44.3	5.5	138	2.64	32.1	2.8	0.8	127	1.1	8.0	0.5	183	0.14	0.263	14
1278662	Soil	9.7	71.5	20.6	169	1.0	64.2	7.7	238	2.46	26.9	5.0	0.8	48	0.9	3.6	0.2	53	0.17	0.182	13
1278663	Soil	10.0	128.4	37.8	418	3.2	117.9	20.9	369	6.11	26.3	7.6	2.0	43	1.4	3.9	0.4	104	0.20	0.269	14
1278664	Soil	8.8	79.1	19.5	219	2.1	119.0	18.0	531	5.37	16.0	3.2	1.9	38	0.7	3.1	0.3	95	0.50	0.135	15
1278665	Soil	15.5	192.9	41.8	519	4.2	184.4	24.1	440	7.22	24.3	7.8	4.7	61	1.8	4.5	0.4	55	0.88	0.155	14
1278666	Soil	11.1	74.1	29.0	228	1.4	108.6	18.8	765	6.55	20.5	2.6	6.5	46	0.9	3.3	0.3	25	0.35	0.103	21
1278667	Soil	78.6	122.0	38.8	1300	8.3	258.2	14.8	204	4.62	117.4	5.6	5.2	177	8.3	24.2	0.4	228	0.41	0.207	18
1278668	Soil	14.8	98.7	29.9	442	1.8	115.3	12.1	372	3.19	40.6	3.4	1.8	98	4.0	5.8	0.3	83	0.68	0.313	16
1278669	Soil	11.7	96.2	42.5	412	0.2	66.9	9.7	90	3.30	25.3	1.6	0.2	23	0.4	3.9	0.3	59	0.03	0.120	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1277576	Soil	22	0.40	758	0.011	<1	0.82	0.004	0.03	0.2	0.21	4.2	0.1	0.09	2	4.9	<0.2
1278641	Soil	9	0.01	698	0.002	1	0.24	0.002	0.05	0.2	0.41	0.7	0.3	0.06	2	2.3	<0.2
1278642	Soil	15	0.04	999	0.002	<1	0.55	0.007	0.06	0.1	0.15	1.2	0.3	0.07	2	2.2	<0.2
1278643	Soil	24	0.10	1870	0.002	3	0.57	0.003	0.07	0.1	3.05	2.5	0.3	0.10	2	5.8	0.3
1278644	Soil	27	0.13	1620	0.005	3	0.63	0.005	0.11	0.1	1.06	4.0	0.7	0.15	2	5.4	0.2
1278645	Soil	6	0.02	606	<0.001	<1	0.37	0.004	0.05	<0.1	0.10	2.3	0.2	0.06	1	1.8	<0.2
1278646	Soil	9	0.03	85	0.004	<1	0.51	0.010	0.04	<0.1	0.05	0.5	0.1	0.07	2	1.1	<0.2
1278647	Soil	22	0.16	125	0.006	1	1.05	0.003	0.05	0.2	0.14	2.4	0.3	0.12	2	3.0	<0.2
1278648	Soil	4	<0.01	167	<0.001	5	0.11	0.005	0.11	<0.1	0.09	1.1	0.2	0.26	<1	1.7	<0.2
1278649	Soil	12	0.07	217	0.005	2	0.48	0.009	0.10	<0.1	0.06	3.0	0.4	0.23	2	2.7	<0.2
1278650	Soil	17	0.09	663	0.001	3	0.78	0.002	0.05	<0.1	0.19	6.5	0.4	<0.05	3	4.5	<0.2
1278651	Soil	14	0.08	918	<0.001	3	0.60	0.002	0.06	<0.1	0.08	6.4	0.5	<0.05	2	3.3	<0.2
1278652	Soil	10	0.19	488	0.003	3	0.34	0.005	0.08	0.1	1.18	5.0	0.6	0.06	<1	7.0	<0.2
1278653	Soil	10	2.12	356	0.003	9	0.20	0.007	0.06	<0.1	0.49	3.3	0.4	<0.05	<1	2.0	<0.2
1278654	Soil	9	0.07	1400	0.002	3	0.47	0.001	0.07	<0.1	0.35	2.1	0.2	0.10	<1	3.1	<0.2
1278655	Soil	72	0.05	920	0.005	7	0.71	0.003	0.17	0.1	0.84	18.5	1.1	0.19	2	27.4	0.4
1278656	Soil	14	0.69	608	0.003	8	0.36	0.005	0.17	0.2	1.65	3.1	0.9	0.36	<1	6.5	0.2
1278657	Soil	6	0.05	205	0.004	1	0.46	0.017	0.03	0.1	0.31	0.6	0.2	0.12	2	2.3	<0.2
1278658	Soil	20	0.03	568	0.003	6	0.47	0.002	0.11	0.5	2.17	2.4	2.4	0.13	1	6.8	0.3
1278659	Soil	30	0.05	2170	0.008	6	0.85	0.003	0.11	0.4	1.29	2.1	0.5	0.24	2	4.5	0.3
1278660	Soil	39	0.09	334	0.012	8	0.56	0.007	0.36	0.5	0.43	3.1	1.7	0.65	3	13.6	0.6
1278661	Soil	17	0.03	491	0.003	2	0.41	0.009	0.14	0.3	0.17	0.7	0.8	0.32	2	9.0	0.4
1278662	Soil	9	0.03	1241	0.002	4	0.48	0.004	0.08	0.1	0.39	1.2	0.3	0.09	1	3.5	0.2
1278663	Soil	16	0.04	4977	0.003	2	0.81	0.003	0.08	<0.1	0.71	3.9	0.3	<0.05	1	5.2	<0.2
1278664	Soil	20	0.19	3546	0.002	3	0.57	0.003	0.07	<0.1	0.40	4.7	0.2	<0.05	1	3.4	<0.2
1278665	Soil	22	0.33	3896	0.002	5	0.50	0.002	0.12	<0.1	0.70	8.3	0.3	0.06	<1	8.0	<0.2
1278666	Soil	9	0.09	>10000	0.002	4	0.58	0.001	0.09	<0.1	0.60	7.9	0.3	<0.05	<1	1.6	<0.2
1278667	Soil	20	0.03	342	0.003	3	0.46	0.002	0.17	0.6	1.29	4.7	3.3	0.27	1	6.6	<0.2
1278668	Soil	18	0.07	703	0.003	7	0.52	0.002	0.18	0.1	0.45	3.2	0.7	0.06	2	3.1	<0.2
1278669	Soil	11	0.03	193	0.002	2	0.36	0.001	0.08	0.1	0.07	0.6	0.3	<0.05	2	2.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278670	Soil	7.6	33.6	26.4	287	0.1	31.5	7.7	886	4.89	31.7	<0.5	1.2	14	0.6	7.2	0.2	57	0.27	0.271	9
1278671	Soil	5.5	41.0	21.7	244	0.2	30.7	6.2	661	2.20	25.2	2.3	0.2	12	0.9	2.6	0.2	32	0.08	0.163	6
1278672	Soil	3.0	19.4	11.0	74	<0.1	19.9	7.9	124	2.45	14.3	1.1	0.4	4	<0.1	1.7	0.3	20	<0.01	0.044	6
1278673	Soil	2.8	11.1	9.7	63	<0.1	20.7	8.5	153	3.74	14.3	<0.5	1.2	3	<0.1	2.2	0.3	23	<0.01	0.040	4
1278674	Soil	18.5	37.7	19.7	178	0.2	55.9	6.5	106	2.36	54.1	4.4	0.5	21	0.3	5.9	0.3	68	0.04	0.171	10
1278675	Soil	71.8	63.5	9.4	376	0.6	197.3	10.5	197	2.02	112.6	5.0	1.0	34	2.6	16.2	0.2	82	0.36	0.144	9
1278676	Soil	4.0	63.3	31.2	109	1.5	59.8	21.2	840	6.32	654.6	20.6	3.2	19	0.3	10.0	0.4	22	0.03	0.128	17
1278677	Soil	9.4	73.0	20.2	241	1.3	78.3	18.9	666	4.49	145.9	15.8	1.5	24	0.6	7.3	0.3	38	0.07	0.130	13
1278678	Soil	32.9	32.3	8.5	175	0.5	57.6	2.7	14	1.15	31.9	0.7	1.7	154	1.9	8.3	0.1	127	0.19	0.107	34
1278679	Soil	90.2	112.5	37.9	3544	1.0	321.1	32.0	444	7.78	81.5	3.8	1.2	43	10.4	24.8	0.2	460	0.28	0.204	24
1278680	Soil	58.7	57.1	16.1	213	0.2	123.1	9.7	171	2.75	34.0	1.6	0.7	8	0.6	7.2	0.2	87	0.15	0.074	12
1278781	Soil	22.3	141.8	36.0	526	1.3	257.3	51.7	1044	6.02	61.5	4.8	2.3	100	5.3	18.8	0.3	138	0.52	0.395	49
1278782	Soil	7.0	176.4	43.2	501	1.1	263.7	69.4	2679	11.42	49.4	7.4	6.9	21	1.8	6.0	0.8	16	0.14	0.103	31
1278783	Soil	12.7	83.6	44.9	176	1.7	98.9	31.1	1083	6.42	29.7	8.9	3.1	35	0.3	4.3	0.5	15	0.36	0.098	13
1278784	Soil	10.0	146.4	51.0	531	1.9	159.0	13.4	207	3.44	18.3	5.5	2.0	235	1.2	5.7	0.5	66	1.62	0.878	29
1278785	Soil	35.7	192.3	100.4	518	3.3	198.3	15.3	390	4.69	60.3	6.0	4.3	239	3.4	16.3	0.6	207	1.59	0.999	25
1278786	Soil	17.1	181.7	143.6	709	2.9	265.5	23.6	748	6.67	58.1	9.5	6.2	360	2.4	11.3	0.7	77	1.92	1.407	37
1278787	Soil	74.8	298.4	191.1	685	8.0	298.6	22.2	673	6.13	124.8	4.9	2.7	350	6.8	32.1	0.8	452	1.62	1.124	25
1278788	Soil	18.8	86.5	26.7	63	4.4	56.7	0.9	29	0.89	30.8	1.8	0.4	69	1.5	8.4	0.3	99	0.39	0.187	13
1278789	Soil	95.3	172.3	21.3	1290	2.2	342.0	25.5	433	4.36	78.3	2.1	3.2	176	23.2	27.4	0.2	402	6.43	0.256	19
1278790	Soil	71.8	68.2	11.2	209	0.3	176.1	8.6	243	2.42	31.3	2.8	2.6	317	2.5	6.3	0.1	50	10.29	0.101	7
1278791	Soil	75.5	64.7	11.9	213	0.3	172.6	8.8	232	2.14	30.0	2.7	2.8	237	2.6	5.8	0.1	51	7.81	0.105	8
1278792	Soil	89.6	83.1	13.0	427	0.5	216.0	10.2	245	2.24	43.7	1.3	2.6	167	4.9	11.0	0.2	114	5.17	0.120	11
1278793	Soil	97.3	82.0	14.5	466	0.4	235.6	9.5	239	2.23	32.2	1.9	2.9	116	3.8	8.1	0.2	92	5.34	0.112	10
1278794	Soil	89.3	65.5	12.8	388	0.3	206.0	8.9	228	2.18	26.5	2.4	2.8	117	2.4	5.5	0.1	67	6.79	0.126	9
1278795	Soil	111.2	80.5	19.6	693	0.5	245.6	16.4	326	2.96	65.2	<0.5	3.8	142	6.6	18.7	0.2	225	4.49	0.157	9
1278796	Soil	83.3	60.1	15.3	293	0.2	247.1	12.6	593	3.87	38.9	3.3	2.4	202	1.2	7.4	0.1	83	7.60	0.093	7
1278797	Soil	20.7	32.5	27.6	82	0.8	24.2	3.0	71	2.00	24.5	3.8	0.3	49	0.4	5.3	0.3	72	0.41	0.086	12
1278798	Soil	34.0	56.4	25.4	206	0.4	46.8	4.2	80	2.52	34.1	4.5	0.2	32	0.4	9.1	0.3	162	0.14	0.105	14
1278799	Soil	2.2	26.2	13.6	93	<0.1	19.5	11.5	180	2.22	13.8	3.2	0.4	10	0.2	1.0	0.3	24	0.06	0.061	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278670	Soil	12	0.08	365	0.004	5	0.66	0.003	0.03	<0.1	0.06	1.8	0.2	<0.05	2	1.4	<0.2
1278671	Soil	9	0.04	176	0.003	2	0.49	0.008	0.05	<0.1	0.11	0.4	0.1	<0.05	2	1.1	<0.2
1278672	Soil	6	0.03	56	0.005	5	0.35	0.006	0.05	<0.1	0.03	0.8	<0.1	<0.05	2	1.6	<0.2
1278673	Soil	7	0.04	72	0.001	4	0.36	<0.001	0.07	<0.1	0.03	2.0	<0.1	<0.05	2	0.7	<0.2
1278674	Soil	15	0.08	223	0.003	4	0.51	0.004	0.08	0.1	0.44	0.5	0.4	0.06	2	2.0	<0.2
1278675	Soil	15	0.07	418	0.003	4	0.51	0.008	0.06	0.5	1.31	2.5	2.1	<0.05	1	3.0	<0.2
1278676	Soil	10	0.06	701	0.002	3	0.67	0.003	0.09	0.1	1.13	7.3	0.5	0.07	1	2.2	<0.2
1278677	Soil	12	0.07	797	0.003	5	0.71	0.004	0.08	<0.1	0.99	2.8	0.4	0.06	2	3.8	<0.2
1278678	Soil	12	0.03	601	0.002	6	0.53	<0.001	0.07	0.2	0.27	1.4	1.4	<0.05	<1	6.2	<0.2
1278679	Soil	50	0.03	815	0.004	3	0.68	0.002	0.05	0.3	2.19	3.4	0.8	<0.05	3	40.9	<0.2
1278680	Soil	18	0.09	345	0.002	4	0.66	0.002	0.06	0.2	0.18	1.5	1.3	<0.05	2	3.7	<0.2
1278781	Soil	84	0.51	444	0.006	8	1.15	0.003	0.15	0.2	0.18	7.1	0.6	0.13	3	7.8	<0.2
1278782	Soil	5	0.08	876	0.004	5	0.37	0.001	0.09	<0.1	0.26	8.3	0.3	<0.05	<1	2.9	0.2
1278783	Soil	6	0.09	878	0.002	4	0.34	0.002	0.10	<0.1	0.20	5.0	0.3	0.06	<1	2.6	<0.2
1278784	Soil	24	0.05	1059	0.006	11	0.77	0.003	0.24	<0.1	0.53	2.5	0.3	0.11	2	12.0	0.3
1278785	Soil	29	0.08	718	0.009	10	0.70	0.004	0.32	0.3	0.71	4.1	0.5	0.42	2	15.8	0.5
1278786	Soil	26	0.08	589	0.011	10	0.75	0.005	0.31	0.1	0.77	4.8	0.6	0.39	2	11.5	0.5
1278787	Soil	40	0.04	185	0.008	8	0.94	0.006	0.36	0.7	0.81	3.4	1.1	1.02	2	14.6	0.9
1278788	Soil	23	0.02	170	0.002	3	0.18	0.002	0.09	0.3	1.81	1.0	0.8	0.14	<1	4.0	<0.2
1278789	Soil	44	2.84	217	0.003	5	0.27	0.006	0.08	0.3	0.96	6.8	1.2	0.09	<1	8.5	<0.2
1278790	Soil	10	3.98	179	0.002	3	0.13	0.005	0.04	0.2	0.33	3.2	1.5	<0.05	<1	2.8	<0.2
1278791	Soil	11	3.35	184	0.002	5	0.16	0.005	0.04	0.2	0.36	3.2	1.5	0.06	<1	3.0	<0.2
1278792	Soil	14	2.46	240	0.003	5	0.29	0.005	0.06	0.3	0.30	3.5	2.0	0.07	<1	4.0	<0.2
1278793	Soil	13	2.77	151	0.003	6	0.24	0.005	0.06	0.3	0.24	4.0	1.8	0.05	<1	5.4	<0.2
1278794	Soil	12	3.11	152	0.002	4	0.17	0.005	0.05	0.2	0.26	3.5	1.1	<0.05	<1	3.7	<0.2
1278795	Soil	21	2.22	327	0.002	5	0.28	0.005	0.07	0.2	0.77	4.2	0.9	0.14	<1	7.3	<0.2
1278796	Soil	15	4.15	171	0.002	4	0.14	0.006	0.03	0.2	0.23	4.0	0.8	<0.05	<1	1.9	<0.2
1278797	Soil	10	0.18	352	0.002	3	0.31	0.003	0.08	<0.1	0.14	0.5	0.6	0.17	1	3.7	<0.2
1278798	Soil	18	0.11	245	0.003	2	0.65	0.003	0.07	0.1	0.19	0.4	0.8	0.16	3	3.7	<0.2
1278799	Soil	10	0.08	49	0.002	1	0.51	0.003	0.04	<0.1	0.03	1.5	0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278800	Soil	1.6	34.0	18.3	126	<0.1	34.8	25.0	466	3.00	17.2	1.2	0.5	11	0.1	1.3	0.3	22	0.05	0.049	4
1278801	Soil	8.3	53.8	15.1	143	1.1	63.7	7.7	180	2.14	14.6	3.8	0.8	64	2.0	5.5	0.2	54	0.63	0.156	7
1278802	Soil	6.6	54.1	23.2	147	1.1	67.9	13.5	290	4.01	25.3	4.5	2.5	60	0.6	5.8	0.3	26	0.47	0.113	7
1278803	Soil	9.0	73.2	22.4	149	1.2	93.9	13.1	270	3.57	23.9	4.5	1.3	42	1.0	8.3	0.2	50	0.39	0.134	9
1278804	Soil	18.5	83.0	47.6	187	1.0	101.9	17.3	171	3.97	89.5	5.8	1.3	60	0.9	15.7	0.4	138	0.08	0.178	12
1278805	Soil	9.1	48.4	18.0	124	0.8	56.5	11.0	218	3.27	24.7	4.1	0.6	36	0.3	7.0	0.3	35	0.34	0.118	9
1278806	Soil	6.8	17.4	4.7	66	<0.1	22.8	4.4	37	1.25	11.6	1.6	0.2	7	0.1	4.6	<0.1	43	0.02	0.031	10
1278807	Soil	55.0	70.2	19.7	1620	1.3	219.4	13.5	265	2.95	44.3	3.1	0.7	120	9.3	20.0	0.2	287	1.01	0.212	7
1278808	Soil	27.1	85.0	33.6	747	0.9	299.9	52.4	520	6.96	32.5	2.0	2.6	115	3.7	15.3	0.1	205	1.13	0.262	28
1278809	Soil	5.1	60.0	12.7	1618	0.1	682.5	114.2	3651	32.82	205.7	0.8	1.9	112	1.4	6.7	<0.1	88	1.11	0.136	6
1278810	Soil	5.1	35.4	27.5	134	0.4	42.7	7.7	158	2.70	37.5	3.3	0.8	48	0.3	7.8	0.2	59	0.08	0.107	8
1278831	Soil	43.9	151.5	14.3	956	3.3	121.4	4.5	130	2.29	75.9	5.7	1.5	60	14.3	34.0	0.2	579	0.34	0.297	34
1278832	Soil	18.6	83.0	31.4	335	1.4	58.1	7.1	221	5.06	63.1	4.2	0.5	26	1.3	10.2	0.4	181	0.07	0.358	16
1278833	Soil	18.4	37.8	18.6	75	2.1	17.5	2.2	32	1.78	22.7	4.7	0.2	61	0.4	6.6	0.2	85	0.02	0.118	14
1278834	Soil	4.8	81.3	18.5	226	0.4	40.0	17.4	629	3.32	24.3	5.9	0.7	25	1.2	1.7	0.4	32	0.07	0.089	8
1278835	Soil	5.1	239.1	42.0	327	0.6	99.3	28.0	766	7.46	31.5	27.8	3.0	19	0.8	4.3	0.7	57	0.02	0.091	14
1278836	Soil	3.8	213.4	33.0	165	0.2	40.8	24.5	643	6.20	9.7	16.6	1.9	23	0.6	2.0	0.4	39	0.11	0.162	14
1278837	Soil	2.0	40.7	15.7	75	0.5	12.2	6.1	209	2.15	4.3	4.6	0.5	14	0.6	1.1	0.1	32	0.06	0.104	11
1278838	Soil	12.4	102.7	20.8	77	2.7	22.6	2.1	129	1.31	14.2	7.9	0.4	162	1.3	6.2	0.2	163	0.28	0.236	18
1278839	Soil	17.2	132.0	21.0	537	1.7	119.3	23.6	505	4.64	17.7	10.1	3.0	53	5.6	7.6	0.3	95	0.71	0.096	14
1278840	Soil	13.6	78.9	27.9	162	0.6	55.4	14.5	1479	4.92	18.8	4.5	1.7	18	0.6	3.0	0.4	42	0.03	0.103	12
1278841	Soil	11.5	51.0	25.5	109	0.6	29.0	5.5	163	2.47	15.8	5.1	0.4	35	0.2	3.8	0.3	90	0.02	0.108	10
1278842	Soil	3.4	12.6	6.3	56	0.2	12.9	2.6	54	0.81	5.8	2.0	0.5	21	0.6	0.8	<0.1	25	0.11	0.031	2
1278843	Soil	8.5	26.0	13.1	132	0.3	31.3	7.9	215	1.88	14.4	4.6	1.1	35	0.7	1.8	0.2	50	0.30	0.049	4
1278844	Soil	8.9	39.2	15.0	156	0.4	38.1	7.1	98	2.31	17.0	4.1	1.9	58	1.0	2.7	0.2	49	0.30	0.067	5
1278845	Soil	2.1	10.1	7.0	38	<0.1	9.8	2.5	43	1.04	7.1	3.0	0.4	16	0.2	0.6	0.1	25	0.10	0.028	2
1278846	Soil	5.2	52.6	14.0	132	0.8	41.2	8.4	150	2.02	17.7	5.0	1.8	79	0.5	2.3	0.2	58	0.68	0.069	6
1278847	Soil	4.4	19.5	14.6	83	0.1	21.1	6.2	119	2.18	18.2	3.8	1.2	15	0.1	1.4	0.2	51	0.05	0.031	5
1278848	Soil	6.2	21.9	15.5	108	0.1	24.2	6.6	118	3.25	21.5	3.1	1.5	15	0.2	2.1	0.3	61	0.02	0.037	5
1278849	Soil	2.8	28.6	12.9	67	0.3	20.6	4.1	67	1.80	10.7	1.5	0.7	21	0.3	0.7	0.2	37	0.06	0.054	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278800	Soil	11	0.08	101	0.002	1	0.43	0.002	0.04	<0.1	0.03	2.9	0.2	<0.05	1	0.6	<0.2
1278801	Soil	12	0.05	886	0.004	2	0.46	0.007	0.04	<0.1	0.15	1.9	0.1	0.06	1	2.0	<0.2
1278802	Soil	11	0.06	2233	0.003	3	0.46	0.007	0.04	<0.1	0.11	3.3	0.1	0.07	<1	1.8	<0.2
1278803	Soil	15	0.06	703	0.002	3	0.37	0.005	0.05	<0.1	0.23	3.8	0.2	<0.05	<1	2.7	<0.2
1278804	Soil	15	0.03	420	0.002	2	0.46	0.002	0.06	<0.1	0.10	2.6	0.2	0.08	2	2.4	0.3
1278805	Soil	11	0.05	429	0.003	2	0.34	0.011	0.06	<0.1	0.11	1.8	0.2	<0.05	1	2.4	<0.2
1278806	Soil	7	0.01	109	0.003	2	0.17	0.004	0.03	<0.1	0.01	0.3	<0.1	<0.05	2	1.0	<0.2
1278807	Soil	47	0.11	299	0.004	2	0.54	0.006	0.06	0.1	0.34	3.5	0.8	0.08	2	7.0	<0.2
1278808	Soil	112	0.22	297	0.004	5	0.77	0.011	0.05	<0.1	0.24	10.8	0.7	0.08	2	3.4	<0.2
1278809	Soil	163	0.45	352	0.002	4	0.73	0.002	0.04	<0.1	0.02	14.5	1.6	<0.05	2	1.1	<0.2
1278810	Soil	24	0.10	110	0.010	2	0.50	0.003	0.04	0.2	0.04	1.7	0.2	<0.05	3	1.7	<0.2
1278831	Soil	63	0.06	1249	0.004	4	0.59	0.002	0.09	0.3	3.66	2.1	1.4	0.09	3	10.7	<0.2
1278832	Soil	31	0.06	292	0.005	4	0.61	0.003	0.08	0.1	0.27	0.8	0.5	0.09	3	6.7	<0.2
1278833	Soil	12	0.02	425	0.003	3	0.29	0.007	0.08	<0.1	0.38	0.5	0.5	0.16	2	3.3	<0.2
1278834	Soil	12	0.09	157	0.012	3	0.68	0.016	0.10	<0.1	0.07	3.1	0.2	0.08	3	1.8	<0.2
1278835	Soil	22	0.11	175	0.013	3	0.79	0.002	0.13	<0.1	0.13	6.9	0.3	0.05	4	4.1	0.5
1278836	Soil	19	0.33	307	0.006	5	1.10	0.003	0.24	<0.1	0.08	5.9	0.2	0.05	4	2.4	<0.2
1278837	Soil	15	0.25	203	0.005	3	0.88	0.012	0.10	<0.1	0.06	0.7	0.1	0.07	4	1.0	<0.2
1278838	Soil	25	0.05	1085	0.002	6	0.56	0.006	0.15	<0.1	0.48	0.7	0.5	0.20	2	5.5	0.2
1278839	Soil	17	0.45	814	0.004	2	0.51	0.003	0.11	<0.1	0.33	5.7	0.3	0.24	2	3.0	<0.2
1278840	Soil	11	0.05	282	0.003	2	0.72	0.005	0.08	<0.1	0.38	2.6	0.3	0.24	2	3.2	<0.2
1278841	Soil	14	0.03	214	0.003	<1	0.41	0.004	0.07	<0.1	0.08	0.3	0.2	0.23	2	2.7	<0.2
1278842	Soil	9	0.06	489	0.002	<1	0.36	0.017	0.04	<0.1	0.09	0.8	<0.1	0.12	1	<0.5	<0.2
1278843	Soil	16	0.14	646	0.002	<1	0.61	0.010	0.05	<0.1	0.10	1.6	<0.1	0.13	2	0.8	<0.2
1278844	Soil	17	0.16	2772	0.001	<1	0.77	0.005	0.05	<0.1	0.18	2.5	0.2	0.17	2	1.9	<0.2
1278845	Soil	11	0.08	415	0.002	<1	0.43	0.016	0.03	<0.1	0.02	0.7	<0.1	0.11	2	<0.5	<0.2
1278846	Soil	19	0.20	960	0.002	1	0.86	0.009	0.06	0.1	0.30	3.4	0.2	0.16	2	1.6	<0.2
1278847	Soil	16	0.18	212	0.002	<1	0.79	0.004	0.05	<0.1	<0.01	1.3	0.1	0.11	3	0.7	<0.2
1278848	Soil	18	0.11	316	0.002	<1	0.88	0.004	0.04	<0.1	0.01	1.5	0.2	0.09	4	0.5	<0.2
1278849	Soil	17	0.11	399	0.004	<1	0.94	0.008	0.05	<0.1	0.04	1.3	<0.1	0.11	3	0.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278850	Soil	11.3	41.6	18.0	196	<0.1	52.3	11.1	183	2.87	19.4	7.0	2.4	21	0.5	2.7	0.2	52	0.05	0.049	8
1278851	Soil	0.5	7.3	3.3	17	<0.1	4.7	1.9	59	0.47	2.0	2.9	<0.1	8	<0.1	0.3	<0.1	9	0.04	0.050	2
1278852	Soil	3.0	27.8	14.2	89	<0.1	20.1	9.3	179	2.66	14.2	2.1	0.2	10	0.1	1.4	0.3	34	0.04	0.095	7
1278853	Soil	2.6	22.8	11.1	74	<0.1	17.0	8.1	262	2.25	11.4	4.1	0.3	10	0.2	1.2	0.2	33	0.05	0.076	8
1278854	Soil	1.9	20.6	12.2	64	<0.1	13.8	5.7	138	1.73	8.6	4.1	0.2	10	0.2	1.0	0.2	30	0.05	0.078	6
1278855	Soil	2.5	22.7	12.2	88	<0.1	16.1	7.3	121	1.97	13.2	3.7	0.3	8	0.1	1.3	0.3	39	0.02	0.038	8
1278856	Soil	2.1	23.9	17.3	93	<0.1	22.0	9.1	194	2.65	14.9	3.5	0.5	15	0.3	1.4	0.3	33	0.09	0.076	8
1278857	Soil	1.7	23.1	10.1	51	0.2	11.3	4.4	105	1.32	7.8	5.1	<0.1	10	0.1	0.7	0.2	24	0.04	0.128	5
1278858	Soil	2.8	24.5	9.7	90	<0.1	16.3	8.2	128	1.98	11.3	2.4	0.3	6	0.1	1.0	0.2	36	0.02	0.046	6
1278859	Soil	1.1	17.0	11.5	51	<0.1	10.6	6.9	241	1.15	5.9	1.6	<0.1	10	<0.1	0.4	0.1	15	0.03	0.046	2
1278860	Soil	1.4	34.8	19.5	120	<0.1	27.8	15.6	308	2.65	11.8	0.8	0.6	19	0.2	0.8	0.3	18	0.08	0.067	3
1278901	Soil	23.1	54.3	15.8	331	0.7	78.6	8.5	154	2.51	26.7	10.2	2.4	58	2.5	5.4	0.2	97	0.61	0.090	10
1278902	Soil	4.8	74.8	20.8	45	5.0	18.9	2.0	60	4.18	120.3	15.9	2.2	132	0.2	16.0	0.3	67	0.03	0.226	8
1278903	Soil	5.2	97.2	29.4	178	1.5	47.0	12.5	229	3.90	20.7	4.5	2.0	33	0.5	4.1	0.3	47	0.07	0.099	4
1278904	Soil	6.1	117.7	32.3	219	1.5	52.7	23.7	838	4.79	25.3	5.4	2.0	32	0.7	5.6	0.3	55	0.03	0.107	6
1278905	Soil	6.0	75.4	32.9	158	0.8	36.0	18.2	680	3.79	20.2	3.6	1.6	27	0.3	4.5	0.4	54	0.04	0.120	6
1278906	Soil	4.2	80.8	25.2	169	0.2	41.0	22.4	1025	4.70	17.3	3.8	0.9	12	0.2	3.5	0.4	39	0.02	0.111	3
1278907	Soil	3.4	41.1	27.9	56	0.2	6.5	2.4	66	4.88	20.0	4.1	0.9	29	0.1	3.3	0.4	38	0.01	0.110	2
1278908	Soil	47.2	52.0	35.6	152	2.6	26.4	2.8	77	9.55	93.7	3.1	2.3	176	0.2	18.9	0.4	100	0.04	0.473	13
1278909	Soil	27.1	301.5	22.0	1417	3.5	422.9	60.6	2608	6.16	42.5	3.4	4.0	70	15.6	13.3	0.2	271	0.18	0.367	16
1278910	Soil	45.2	218.8	14.7	2123	3.4	412.4	25.0	1038	3.00	37.9	11.0	1.0	143	28.1	21.0	0.2	200	0.34	0.286	9
1278911	Soil	31.2	306.8	5.6	2134	1.6	451.4	37.0	1014	1.62	20.2	3.7	0.3	138	24.7	11.6	0.1	149	0.37	0.195	6
1278912	Soil	167.0	268.0	30.0	313	14.5	72.5	1.8	57	5.21	152.9	*	4.3	492	5.6	69.6	0.4	469	0.20	0.822	33
1278913	Soil	62.5	142.5	19.3	313	8.2	63.5	2.3	89	2.52	58.3	4.5	0.5	100	2.8	30.1	0.3	946	0.04	0.227	29
1278914	Soil	186.1	178.9	23.5	6949	7.1	631.0	19.5	1053	3.61	89.7	7.1	1.4	141	67.3	55.7	0.4	1649	0.45	0.189	21
1278915	Soil	80.6	100.1	27.8	576	5.3	68.8	6.2	253	2.77	38.2	1.8	0.7	92	9.4	45.8	0.4	639	0.11	0.265	23
1278916	Soil	94.9	132.6	27.8	683	7.5	98.5	9.7	331	4.17	80.2	4.1	1.1	165	12.4	64.7	0.4	580	0.29	0.641	23
1278917	Soil	53.8	107.5	14.0	138	4.4	35.8	1.3	50	2.29	40.6	1.6	1.2	168	1.6	26.9	0.2	242	0.20	0.541	17
1278918	Soil	79.8	250.4	23.8	1033	7.2	194.9	7.1	215	3.67	92.4	5.2	1.5	151	18.8	57.2	0.3	656	0.55	0.494	28
1278919	Soil	100.8	519.1	28.6	2556	21.6	407.8	18.6	451	6.50	134.5	4.1	3.9	412	50.1	49.6	0.4	702	2.99	1.293	29

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278850	Soil	20	0.25	311	0.002	<1	0.99	0.003	0.05	<0.1	0.12	2.6	0.2	0.08	3	1.0	<0.2
1278851	Soil	5	0.03	42	0.004	<1	0.35	0.016	0.04	<0.1	<0.01	0.2	<0.1	0.07	1	0.8	<0.2
1278852	Soil	16	0.06	66	0.006	<1	0.49	0.003	0.03	0.1	0.02	0.4	<0.1	0.07	2	1.0	<0.2
1278853	Soil	16	0.12	91	0.008	<1	0.68	0.007	0.05	0.1	<0.01	0.4	<0.1	0.08	2	0.8	<0.2
1278854	Soil	14	0.12	59	0.005	<1	0.63	0.006	0.03	0.1	0.01	0.4	<0.1	0.07	2	0.7	<0.2
1278855	Soil	13	0.05	55	0.009	<1	0.46	0.002	0.03	0.2	<0.01	0.9	0.1	0.05	3	0.7	<0.2
1278856	Soil	17	0.16	54	0.010	<1	0.64	0.003	0.03	0.1	<0.01	1.4	<0.1	0.06	2	1.0	<0.2
1278857	Soil	12	0.05	102	0.003	1	0.68	0.009	0.04	<0.1	<0.01	0.4	<0.1	0.12	2	1.3	<0.2
1278858	Soil	12	0.03	37	0.004	<1	0.35	0.002	0.03	0.1	<0.01	1.4	<0.1	0.07	2	<0.5	<0.2
1278859	Soil	7	0.03	61	0.005	<1	0.41	0.015	0.03	<0.1	0.01	0.6	<0.1	<0.05	2	<0.5	<0.2
1278860	Soil	9	0.05	76	0.001	<1	0.24	0.006	0.04	<0.1	0.02	3.4	<0.1	0.06	<1	<0.5	<0.2
1278901	Soil	24	0.18	1200	0.003	3	0.85	0.004	0.08	0.2	0.34	3.0	0.3	0.15	2	1.9	<0.2
1278902	Soil	28	0.10	325	0.004	3	0.54	0.006	0.10	<0.1	0.26	5.3	0.9	0.36	3	8.6	<0.2
1278903	Soil	17	0.20	379	0.007	<1	0.93	0.019	0.07	<0.1	0.05	5.1	0.3	0.11	3	2.2	<0.2
1278904	Soil	19	0.18	362	0.006	1	0.92	0.014	0.08	<0.1	0.07	6.0	0.4	0.18	3	3.4	<0.2
1278905	Soil	17	0.17	192	0.007	2	0.93	0.009	0.08	0.1	0.03	3.3	0.4	0.17	3	3.6	<0.2
1278906	Soil	14	0.05	845	0.004	1	0.61	0.006	0.06	<0.1	0.03	3.0	0.2	0.13	2	2.5	<0.2
1278907	Soil	19	0.01	219	0.002	2	0.36	0.004	0.09	<0.1	0.05	1.6	0.2	0.21	2	2.5	<0.2
1278908	Soil	45	0.06	98	0.003	2	0.58	0.017	0.36	0.5	0.24	2.4	7.3	1.21	2	23.6	0.3
1278909	Soil	63	0.29	970	0.010	4	4.81	0.006	0.16	0.3	0.35	12.0	4.3	0.30	3	12.5	<0.2
1278910	Soil	39	0.25	764	0.005	3	2.05	0.006	0.08	0.3	0.19	3.4	3.1	0.18	2	9.1	<0.2
1278911	Soil	30	0.34	812	0.003	3	3.02	0.005	0.04	0.2	0.16	1.3	2.0	0.13	2	6.2	<0.2
1278912	Soil	179	0.06	94	0.007	3	1.07	0.013	0.33	1.2	2.31	7.2	4.3	1.11	7	76.6	0.6
1278913	Soil	148	0.07	639	0.005	2	0.80	0.008	0.13	0.5	0.38	1.2	3.2	0.37	6	32.4	0.4
1278914	Soil	119	0.13	1080	0.008	7	1.38	0.004	0.13	0.9	1.21	4.6	14.0	0.43	6	30.6	0.5
1278915	Soil	94	0.08	743	0.004	4	0.82	0.004	0.14	0.6	0.42	1.1	6.2	0.35	6	42.4	0.7
1278916	Soil	120	0.12	910	0.007	5	1.10	0.007	0.18	0.7	0.55	1.8	6.9	0.45	6	53.5	1.0
1278917	Soil	48	0.05	551	0.005	4	1.07	0.011	0.12	0.5	0.41	1.9	2.4	0.39	3	26.4	0.4
1278918	Soil	119	0.07	1080	0.005	4	0.76	0.005	0.15	0.7	1.39	3.6	4.0	0.41	5	42.3	0.5
1278919	Soil	296	1.04	562	0.008	3	0.90	0.011	0.16	1.1	2.01	7.5	2.5	0.59	7	51.7	0.8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278920	Soil	65.3	387.6	24.3	3262	13.4	352.8	14.1	471	4.52	77.1	4.7	1.4	201	64.3	34.9	0.3	1334	1.31	0.594	28
1278931	Soil	7.4	155.8	25.3	357	0.3	93.1	23.8	782	6.32	55.5	9.7	1.0	6	0.8	7.5	0.4	52	0.06	0.074	5
1278932	Soil	8.9	406.4	32.7	463	0.8	195.0	30.6	273	13.17	70.1	12.1	1.3	9	1.4	10.7	0.5	100	0.02	0.156	7
1278933	Soil	5.3	155.6	34.7	246	0.6	98.6	20.0	503	7.24	106.2	10.9	0.9	23	1.5	9.9	0.4	59	0.02	0.106	8
1278934	Soil	9.0	85.4	33.6	211	0.4	74.3	44.5	2387	6.20	19.5	3.9	1.7	22	0.4	3.8	0.4	36	0.02	0.120	9
1278935	Soil	12.8	100.7	47.0	352	1.0	135.6	39.4	1146	9.16	26.5	9.0	3.1	21	0.9	3.6	0.4	15	0.16	0.063	10
1278936	Soil	10.0	54.4	15.9	201	0.4	59.8	13.2	223	3.22	17.8	2.3	0.8	5	0.3	3.3	0.2	38	0.01	0.054	5
1278937	Soil	4.1	30.4	12.1	88	<0.1	21.1	6.1	196	2.07	10.3	3.6	0.2	12	0.2	2.0	0.3	51	0.02	0.062	10
1278938	Soil	4.4	164.3	35.0	379	2.0	157.4	41.5	757	10.67	20.7	17.5	1.8	17	0.5	3.3	0.5	21	0.18	0.050	8
1278939	Soil	3.6	69.7	15.0	143	1.0	53.6	14.7	378	3.15	11.8	6.4	1.2	12	0.2	1.9	0.2	17	0.12	0.057	5
1278940	Soil	9.5	93.5	21.8	292	0.8	72.0	16.0	342	4.04	20.3	6.7	1.0	22	0.5	4.4	0.2	47	0.03	0.092	9
1278941	Soil	24.4	216.2	49.8	436	4.1	94.7	40.0	889	8.58	72.4	44.6	4.9	72	5.3	17.8	0.4	44	0.42	0.173	8
1278942	Soil	25.6	184.8	30.8	820	1.8	126.3	23.4	751	5.19	53.7	22.5	2.5	75	5.8	10.7	0.3	90	0.56	0.213	14
1278943	Soil	9.8	159.8	17.1	155	1.0	55.7	12.9	323	3.83	42.4	15.4	0.5	30	1.2	8.3	0.3	80	0.11	0.249	11
1278944	Soil	11.1	57.0	24.7	145	0.5	33.8	6.0	148	3.49	32.8	6.4	0.2	24	0.3	5.7	0.4	148	0.03	0.166	11
1278945	Soil	14.4	58.0	23.9	154	0.4	35.0	6.1	97	2.68	28.9	18.4	0.3	20	0.4	6.2	0.4	157	0.01	0.076	14
1278946	Soil	3.5	19.0	5.4	35	<0.1	10.5	2.4	33	0.91	10.3	1.8	0.1	5	<0.1	1.7	0.2	49	0.01	0.024	12
1278947	Soil	8.5	85.3	16.1	177	2.1	50.3	7.8	273	2.79	33.9	13.7	0.9	77	0.9	8.0	0.3	73	0.72	0.138	9
1278948	Soil	19.5	112.0	25.3	372	1.4	76.9	18.5	683	5.48	61.6	10.7	1.9	55	3.1	12.3	0.4	151	0.17	0.355	17
1278949	Soil	9.5	14.9	3.3	72	4.1	15.7	2.1	28	0.77	8.1	3.0	0.1	4	0.2	2.4	<0.1	81	0.01	0.034	15
1278950	Soil	26.8	160.3	32.5	696	2.6	127.4	15.6	468	5.88	63.8	11.9	2.3	85	8.9	16.8	0.4	220	0.36	0.326	21
1280221	Soil	5.6	14.0	9.5	49	0.2	14.2	2.3	82	1.05	9.5	1.8	0.1	17	0.2	1.7	0.1	34	0.06	0.065	5
1280222	Soil	14.5	18.9	10.3	101	0.3	35.5	4.3	56	1.36	12.6	1.3	<0.1	10	0.3	2.9	0.2	61	0.03	0.067	5
1280223	Soil	15.6	25.9	13.4	124	0.1	43.9	6.6	142	2.14	14.6	1.4	<0.1	11	0.2	3.1	0.2	70	0.02	0.089	9
1280224	Soil	10.1	19.0	9.6	84	<0.1	23.4	4.8	82	1.49	10.6	0.9	<0.1	8	0.1	1.8	0.2	46	0.02	0.064	5
1280225	Soil	7.6	18.2	8.7	80	<0.1	22.6	6.1	85	1.64	10.9	1.2	<0.1	7	0.1	1.7	0.2	39	<0.01	0.048	6
1280226	Soil	4.6	374.2	16.0	567	3.3	366.3	49.1	2157	11.91	90.7	11.1	1.9	171	20.5	20.3	0.2	171	0.38	0.276	3
1280227	Soil	11.7	253.2	31.9	148	5.4	102.4	26.9	1066	7.88	112.5	20.1	2.0	173	2.1	16.5	0.4	109	0.07	0.287	4
1280228	Soil	5.6	163.0	44.9	332	1.9	70.3	23.1	466	6.95	23.2	7.8	5.1	39	1.5	5.6	0.4	67	0.07	0.107	2
1280229	Soil	3.1	41.6	17.7	84	0.5	20.4	6.7	232	2.28	12.2	3.1	0.2	14	0.2	2.6	0.2	28	0.02	0.079	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278920	Soil	216	0.24	1339	0.007	9	0.87	0.006	0.15	0.5	0.68	4.0	3.3	0.34	6	37.9	0.5
1278931	Soil	15	0.05	258	0.004	3	0.47	0.002	0.09	<0.1	0.07	4.2	0.2	<0.05	2	3.2	0.3
1278932	Soil	30	0.06	91	0.008	2	0.77	0.004	0.06	0.1	0.11	8.9	0.2	0.06	4	7.7	0.3
1278933	Soil	18	0.06	94	0.010	<1	0.68	0.006	0.05	0.1	0.06	4.8	0.2	0.05	3	3.9	0.4
1278934	Soil	10	0.08	348	0.006	2	0.76	0.004	0.08	<0.1	0.13	3.8	0.3	0.09	2	2.6	<0.2
1278935	Soil	5	0.09	1754	0.002	1	0.53	0.002	0.07	<0.1	0.34	7.7	0.3	<0.05	<1	1.8	<0.2
1278936	Soil	8	0.04	701	0.002	3	0.45	0.002	0.08	<0.1	0.07	2.3	0.2	0.07	2	1.0	<0.2
1278937	Soil	11	0.05	162	0.009	<1	0.81	0.006	0.04	0.2	0.04	0.5	0.2	0.06	4	1.7	<0.2
1278938	Soil	8	0.13	1421	0.003	<1	0.64	0.002	0.07	<0.1	0.32	11.0	0.5	<0.05	1	2.2	0.3
1278939	Soil	6	0.08	394	0.007	<1	0.45	0.011	0.05	<0.1	0.22	3.7	0.1	<0.05	1	1.4	<0.2
1278940	Soil	10	0.05	207	0.005	2	0.57	0.004	0.07	<0.1	0.08	2.7	0.2	0.05	2	3.1	0.2
1278941	Soil	10	0.95	843	0.002	1	1.49	0.002	0.10	<0.1	0.90	8.6	0.6	0.14	2	6.9	<0.2
1278942	Soil	16	0.27	860	0.003	4	0.71	0.003	0.09	<0.1	0.61	5.1	0.5	0.13	1	4.7	<0.2
1278943	Soil	15	0.24	658	0.004	1	0.67	0.003	0.07	<0.1	0.11	1.9	0.3	0.10	2	2.4	<0.2
1278944	Soil	19	0.05	224	0.005	2	0.58	0.002	0.07	0.2	0.08	0.6	0.3	0.13	4	3.2	<0.2
1278945	Soil	13	0.03	292	0.004	2	0.37	0.001	0.06	0.2	0.03	0.5	0.3	0.10	4	3.7	0.3
1278946	Soil	6	0.02	55	0.008	1	0.23	0.004	0.03	<0.1	<0.01	0.2	0.1	0.07	3	0.6	<0.2
1278947	Soil	16	0.22	997	0.004	4	0.86	0.005	0.08	<0.1	0.48	2.8	0.3	0.17	2	4.4	<0.2
1278948	Soil	21	0.07	1754	0.004	3	0.69	0.002	0.09	0.1	0.17	3.1	0.4	0.12	2	5.7	<0.2
1278949	Soil	12	0.01	132	0.004	2	0.23	0.004	0.04	0.1	0.04	0.3	0.2	0.07	2	1.2	<0.2
1278950	Soil	30	0.06	2338	0.004	4	0.54	0.004	0.08	0.1	0.73	4.1	0.5	0.12	1	7.8	<0.2
1280221	Soil	10	0.05	90	0.009	2	0.57	0.014	0.04	0.1	0.05	0.4	0.1	0.08	2	0.9	<0.2
1280222	Soil	22	0.03	142	0.004	<1	0.42	0.008	0.03	<0.1	0.05	0.2	0.2	0.12	3	1.0	<0.2
1280223	Soil	31	0.03	97	0.004	<1	0.40	0.006	0.05	0.1	0.02	0.2	0.2	0.08	3	0.9	<0.2
1280224	Soil	13	0.02	62	0.002	<1	0.36	0.007	0.03	<0.1	0.02	0.2	0.1	0.06	2	1.1	<0.2
1280225	Soil	8	0.02	51	0.004	<1	0.36	0.006	0.03	0.1	<0.01	0.3	0.1	<0.05	2	0.8	<0.2
1280226	Soil	55	0.65	2137	0.002	2	2.57	0.004	0.06	<0.1	0.37	13.2	0.9	0.16	6	7.4	<0.2
1280227	Soil	30	0.33	948	0.003	2	1.38	0.004	0.14	<0.1	0.29	10.5	0.8	0.26	6	8.4	0.3
1280228	Soil	23	0.22	567	0.001	1	1.39	0.003	0.07	<0.1	0.20	7.2	0.5	0.09	4	4.4	<0.2
1280229	Soil	11	0.04	93	0.004	1	0.61	0.011	0.05	<0.1	0.06	0.8	0.2	0.10	2	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280230	Soil	3.1	32.9	18.7	73	0.3	16.2	5.7	215	1.98	10.2	2.7	0.7	14	0.1	2.2	0.3	30	0.02	0.069	4
1280231	Soil	5.1	35.6	20.2	88	0.8	18.4	4.7	93	2.06	21.1	2.3	0.3	27	0.2	3.4	0.3	63	0.02	0.084	6
1280232	Soil	4.1	67.3	48.7	196	1.4	39.5	24.4	1067	4.49	19.9	4.9	1.4	34	0.6	5.0	0.4	51	0.03	0.119	5
1280233	Soil	5.5	82.3	63.1	284	1.6	53.2	45.3	1922	4.56	26.6	7.3	3.3	31	0.8	4.9	0.4	56	0.02	0.127	8
1280234	Soil	56.5	95.0	57.2	309	2.6	43.2	8.6	195	6.65	84.4	2.1	7.6	305	1.8	16.9	0.5	117	0.05	0.339	18
1280235	Soil	118.2	181.6	31.8	302	6.1	90.4	2.0	32	3.22	37.4	2.0	4.4	535	21.6	71.0	0.4	561	0.29	0.340	27
1280236	Soil	78.6	164.0	31.0	271	4.9	58.0	2.6	59	3.60	48.6	2.6	3.1	406	10.4	48.8	0.4	461	0.32	0.433	25
1280237	Soil	15.4	107.0	58.1	460	1.8	67.6	30.3	773	4.74	29.8	3.0	4.6	103	3.3	10.0	0.4	108	0.09	0.132	12
1280238	Soil	9.5	25.6	14.7	63	0.7	13.8	3.1	143	1.17	7.3	2.0	0.2	39	0.6	3.9	0.1	52	0.04	0.094	5
1280239	Soil	28.1	175.7	25.1	924	4.7	122.2	8.4	655	3.17	59.7	4.0	1.2	92	22.9	23.0	0.3	397	0.47	0.414	15
1280240	Soil	0.5	4.4	2.5	9	0.7	2.0	0.5	11	0.24	0.6	1.0	<0.1	5	0.3	0.2	<0.1	3	0.02	0.045	<1
1280241	Soil	2.0	7.1	5.6	21	0.7	5.8	1.1	39	0.42	1.8	1.3	<0.1	8	0.3	0.6	<0.1	13	0.03	0.059	1
1280242	Soil	1.8	5.7	3.2	13	0.4	2.8	0.5	10	0.27	1.4	1.4	<0.1	11	0.2	0.7	<0.1	19	0.03	0.071	1
1280243	Soil	14.3	95.7	16.2	358	2.0	97.4	12.3	213	2.15	24.8	3.5	0.8	57	3.8	7.1	0.2	131	0.26	0.248	6
1280244	Soil	6.5	17.8	13.0	76	0.5	12.1	2.0	39	1.19	12.2	1.7	<0.1	13	0.2	2.5	0.2	75	0.02	0.083	8
1280245	Soil	9.7	86.2	20.8	432	2.4	72.6	8.1	310	3.18	24.1	12.1	1.3	36	4.4	4.5	0.3	134	0.34	0.168	7
1280246	Soil	2.3	25.4	5.1	134	1.3	20.0	3.2	124	1.16	4.9	3.8	0.4	37	1.2	1.3	<0.1	41	0.47	0.080	3
1280247	Soil	0.7	9.7	3.5	34	0.5	5.1	1.9	78	0.52	1.4	3.0	0.2	29	0.3	0.5	0.1	11	0.35	0.041	2
1280248	Soil	4.0	36.8	9.0	138	1.5	25.0	4.4	114	1.58	9.9	5.7	0.7	43	1.1	2.0	0.2	42	0.42	0.125	5
1280249	Soil	1.3	12.4	3.8	53	0.6	8.9	1.5	33	0.59	2.6	4.1	0.3	45	0.7	0.7	<0.1	16	0.53	0.085	2
1280250	Soil	5.3	35.7	9.4	126	1.6	28.9	4.6	305	1.60	10.2	6.7	0.6	59	2.5	2.3	0.2	41	0.69	0.129	4
1280551	Soil	5.1	18.0	7.2	49	0.6	14.4	3.1	48	1.08	9.1	0.9	0.2	5	0.1	1.7	0.2	43	<0.01	0.021	9
1280552	Soil	5.5	22.3	14.0	58	1.1	18.0	4.7	90	1.66	14.8	<0.5	0.4	13	<0.1	2.0	0.3	54	0.02	0.037	6
1280553	Soil	5.1	36.9	15.6	105	0.3	29.7	8.0	172	2.97	25.4	1.1	1.3	13	0.3	3.6	0.3	43	<0.01	0.047	4
1280554	Soil	9.3	44.7	21.4	94	1.4	36.6	6.5	214	1.92	25.5	8.5	1.1	77	1.3	4.2	0.4	51	0.69	0.072	4
1280555	Soil	6.0	40.4	25.7	127	1.2	42.9	8.0	309	2.17	24.5	7.6	1.2	69	1.6	3.0	0.4	41	0.61	0.086	4
1280556	Soil	3.9	13.7	16.4	72	0.1	16.8	5.3	135	2.83	17.5	1.5	0.6	9	<0.1	2.4	0.2	55	0.02	0.074	6
1280557	Soil	1.7	9.9	8.6	52	<0.1	11.1	4.7	126	1.82	12.3	<0.5	0.8	5	<0.1	1.2	0.2	34	0.01	0.033	5
1280558	Soil	0.9	6.4	3.9	18	<0.1	3.4	1.5	48	0.48	2.3	2.4	0.3	5	<0.1	0.3	<0.1	10	0.02	0.023	2
1280559	Soil	8.6	33.4	14.9	171	0.6	36.4	5.6	90	2.00	23.0	2.7	2.5	46	0.7	2.5	0.2	75	0.45	0.081	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280230	Soil	11	0.02	94	0.003	2	0.58	0.011	0.06	<0.1	0.06	0.7	0.2	0.07	2	1.5	<0.2
1280231	Soil	12	0.02	191	0.003	2	0.47	0.004	0.09	<0.1	0.07	0.8	0.3	0.11	3	2.1	<0.2
1280232	Soil	26	0.45	202	0.007	3	1.59	0.007	0.08	<0.1	0.20	2.1	0.4	0.11	5	3.3	<0.2
1280233	Soil	22	0.27	228	0.006	2	1.27	0.004	0.09	<0.1	0.11	3.6	0.4	0.06	4	3.6	<0.2
1280234	Soil	26	0.10	288	0.002	4	0.77	0.004	0.24	0.1	0.80	9.6	1.6	0.45	4	23.0	0.2
1280235	Soil	56	0.03	188	0.004	8	0.65	0.007	0.25	1.0	1.67	4.4	6.3	0.61	5	81.5	0.7
1280236	Soil	56	0.05	209	0.004	10	0.79	0.007	0.24	0.7	1.43	4.6	3.9	0.62	4	54.9	0.6
1280237	Soil	25	0.26	1109	0.003	4	1.06	0.004	0.14	0.1	0.20	5.8	1.0	0.20	3	10.4	<0.2
1280238	Soil	14	0.03	380	0.003	2	0.47	0.016	0.05	0.1	0.10	0.3	0.6	0.13	2	4.6	<0.2
1280239	Soil	87	0.07	856	0.006	4	0.90	0.007	0.11	0.3	0.64	2.8	1.4	0.13	3	16.6	0.6
1280240	Soil	2	<0.01	72	0.003	<1	0.16	0.024	0.02	<0.1	0.03	0.1	<0.1	<0.05	<1	<0.5	<0.2
1280241	Soil	8	0.02	85	0.003	1	0.23	0.021	0.03	<0.1	0.05	0.2	0.1	0.06	<1	1.1	<0.2
1280242	Soil	4	0.01	183	0.002	<1	0.17	0.021	0.03	<0.1	0.06	0.2	0.1	0.08	<1	1.5	<0.2
1280243	Soil	31	0.05	962	0.002	5	1.74	0.006	0.07	0.1	0.73	1.5	0.8	0.21	2	9.1	<0.2
1280244	Soil	11	0.02	102	0.001	2	0.32	0.007	0.06	<0.1	0.05	0.1	0.3	<0.05	3	1.7	<0.2
1280245	Soil	27	0.21	1476	0.002	3	1.31	0.004	0.12	<0.1	1.46	3.3	0.8	0.10	4	4.4	<0.2
1280246	Soil	12	0.11	599	0.004	4	0.63	0.016	0.07	<0.1	0.21	1.3	0.2	0.11	2	1.5	<0.2
1280247	Soil	3	0.08	358	0.008	2	0.33	0.021	0.03	<0.1	0.11	0.3	<0.1	0.14	2	0.6	<0.2
1280248	Soil	13	0.21	768	0.004	3	0.86	0.007	0.06	<0.1	0.58	1.8	0.2	0.14	2	1.3	<0.2
1280249	Soil	5	0.10	628	0.005	2	0.42	0.016	0.03	<0.1	0.18	0.5	<0.1	0.14	1	0.6	<0.2
1280250	Soil	15	0.18	992	0.004	2	0.87	0.010	0.07	<0.1	0.35	1.6	0.2	0.14	3	2.2	<0.2
1280551	Soil	7	<0.01	42	0.008	<1	0.39	0.004	0.02	0.2	<0.01	0.5	<0.1	<0.05	3	0.6	<0.2
1280552	Soil	9	0.02	109	0.003	1	0.42	0.002	0.04	<0.1	0.03	1.1	0.1	0.06	2	<0.5	<0.2
1280553	Soil	11	0.04	119	0.004	1	0.45	0.001	0.04	<0.1	0.04	2.7	0.1	0.06	2	0.8	<0.2
1280554	Soil	14	0.11	1437	0.002	3	0.65	0.003	0.06	<0.1	0.68	3.4	0.3	0.10	2	3.1	<0.2
1280555	Soil	12	0.17	1819	0.001	2	0.77	0.007	0.07	<0.1	0.75	3.7	0.4	0.12	2	3.4	<0.2
1280556	Soil	15	0.13	112	0.007	<1	0.79	0.003	0.04	0.1	<0.01	0.9	0.1	<0.05	4	0.7	<0.2
1280557	Soil	11	0.13	78	0.004	1	0.75	0.004	0.03	<0.1	<0.01	0.8	0.1	<0.05	4	<0.5	<0.2
1280558	Soil	5	0.03	72	0.004	1	0.38	0.016	0.03	<0.1	<0.01	0.4	<0.1	<0.05	2	<0.5	<0.2
1280559	Soil	19	0.21	862	0.002	6	0.84	0.004	0.07	0.1	0.40	2.4	0.3	<0.05	2	1.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280560	Soil	10.7	34.8	10.9	229	0.6	46.1	7.3	271	1.82	15.0	4.9	1.6	50	1.7	2.8	0.2	76	0.66	0.088	7
1280571	Soil	22.8	41.3	7.7	342	0.7	79.8	4.8	162	1.42	20.8	0.7	1.2	71	4.4	7.2	0.1	157	2.45	0.056	12
1280572	Soil	16.9	51.7	11.0	263	0.7	58.1	7.1	219	1.96	17.5	1.9	1.5	84	2.8	3.9	0.2	85	1.32	0.069	8
1280573	Soil	8.0	16.0	4.9	86	0.3	21.7	6.4	277	0.94	6.9	3.8	0.5	79	1.6	1.5	<0.1	33	1.22	0.067	4
1280574	Soil	28.5	55.6	12.8	364	0.8	85.4	7.3	124	2.27	27.5	3.1	1.9	63	3.3	6.2	0.3	97	0.51	0.116	10
1280575	Soil	8.8	83.8	9.2	205	0.1	40.6	15.0	732	3.03	29.3	<0.5	0.3	14	1.0	5.5	0.2	32	0.07	0.163	7
1280576	Soil	6.7	56.9	13.0	154	0.2	24.3	8.4	184	2.64	17.5	4.2	0.1	17	0.4	5.2	0.2	25	0.04	0.136	7
1280577	Soil	7.8	152.3	12.0	145	0.1	42.6	12.8	269	3.76	32.5	10.7	0.1	8	0.4	6.5	0.3	45	0.03	0.112	8
1280578	Soil	4.7	46.1	7.9	72	0.1	19.2	6.1	204	1.83	14.7	2.1	0.1	9	0.3	2.6	0.1	18	0.07	0.154	5
1280579	Soil	7.9	149.3	23.1	221	0.8	51.3	24.3	660	4.95	57.5	21.2	1.6	30	1.6	7.4	0.3	29	0.28	0.202	15
1280580	Soil	2.5	46.9	10.5	85	0.2	19.6	8.4	394	2.26	12.3	5.1	0.7	25	0.3	2.0	0.2	22	0.37	0.170	16
1280631	Soil	4.2	14.4	11.8	17	1.1	4.3	0.8	18	0.73	19.4	<0.5	0.3	21	<0.1	4.5	0.1	38	0.01	0.030	2
1280632	Soil	3.9	19.8	23.8	19	3.4	6.5	0.9	26	0.92	22.2	6.8	<0.1	13	0.1	4.3	0.2	42	0.03	0.044	2
1280633	Soil	4.7	58.0	10.9	19	5.3	5.0	0.9	19	0.96	15.8	7.5	<0.1	12	0.1	4.0	0.2	49	0.01	0.032	2
1280634	Soil	8.6	24.5	14.4	22	2.9	5.1	1.0	28	1.52	21.8	5.6	0.2	25	<0.1	4.7	0.3	80	0.02	0.054	5
1280635	Soil	5.8	9.0	5.9	25	0.5	5.8	1.3	24	0.82	8.9	<0.5	<0.1	19	<0.1	2.3	0.1	63	<0.01	0.031	6
1280636	Soil	7.0	69.8	21.1	148	0.4	28.1	13.1	302	3.53	18.5	6.1	0.8	23	0.6	3.8	0.3	75	0.09	0.134	18
1280637	Soil	8.0	34.9	18.4	109	0.5	19.9	7.7	232	3.63	16.1	4.8	0.5	24	0.7	3.1	0.3	99	0.06	0.166	14
1280638	Soil	2.4	23.6	7.3	37	0.2	11.7	4.4	312	1.17	4.4	4.4	0.2	10	0.3	1.1	0.1	31	0.06	0.107	8
1280639	Soil	4.6	41.9	13.2	95	0.1	20.8	9.1	407	2.82	11.9	2.9	0.4	19	0.3	1.6	0.2	71	0.17	0.126	13
1280640	Soil	3.8	36.7	10.4	77	0.2	15.0	7.4	252	2.11	9.1	3.4	0.3	15	0.1	1.3	0.2	61	0.13	0.080	13
1280641	Soil	5.8	55.9	16.3	127	0.3	32.5	13.2	576	3.46	16.8	6.8	0.8	28	0.5	2.2	0.2	61	0.26	0.180	20
1280642	Soil	2.8	34.2	10.6	66	<0.1	15.9	6.1	167	2.62	9.3	3.1	0.5	8	0.2	1.3	0.2	53	0.03	0.089	12
1280643	Soil	8.2	110.8	31.3	157	0.2	47.8	34.4	1754	6.02	25.9	10.8	3.4	26	0.8	4.3	0.3	83	0.33	0.324	24
1280644	Soil	4.4	37.0	16.8	83	<0.1	18.7	13.9	902	2.59	10.3	4.6	0.9	17	0.4	1.5	0.2	60	0.18	0.135	16
1280645	Soil	2.4	29.7	9.7	30	0.2	8.8	15.4	3624	1.93	5.3	4.2	0.4	20	0.4	0.7	0.1	37	0.25	0.153	14
1280646	Soil	2.6	43.7	11.1	91	0.1	19.9	11.2	425	2.84	7.8	3.0	0.7	6	0.2	1.1	0.1	33	0.06	0.116	14
1280647	Soil	6.5	113.0	19.2	153	0.3	44.7	26.6	1373	4.78	33.0	5.9	1.7	34	0.4	4.4	0.3	42	0.44	0.255	24
1280648	Soil	4.9	44.1	11.3	144	0.3	24.6	9.9	584	3.03	12.6	1.8	0.4	27	3.2	1.9	0.2	47	0.24	0.293	14
1280649	Soil	5.1	40.8	10.9	95	0.2	20.5	11.9	400	3.13	14.2	2.8	0.3	13	0.4	1.9	0.2	36	0.11	0.199	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280560	Soil	15	0.18	864	0.002	3	0.84	0.011	0.07	0.1	0.29	2.4	0.3	0.09	2	0.6	<0.2
1280571	Soil	18	0.84	376	0.004	3	0.51	0.010	0.05	0.1	0.26	2.4	0.9	0.13	1	3.1	0.2
1280572	Soil	21	0.21	1036	0.004	2	0.86	0.006	0.06	0.2	0.30	2.8	0.2	0.14	2	2.0	<0.2
1280573	Soil	8	0.10	661	0.004	<1	0.53	0.014	0.03	<0.1	0.15	1.0	0.1	0.14	1	0.8	<0.2
1280574	Soil	16	0.17	1379	0.004	3	0.68	0.006	0.07	0.2	0.45	3.0	0.3	0.12	2	2.2	<0.2
1280575	Soil	11	0.05	495	0.002	3	0.50	0.005	0.09	<0.1	0.02	0.5	0.2	0.15	2	2.3	<0.2
1280576	Soil	11	0.04	169	0.002	1	0.46	0.008	0.10	<0.1	0.05	0.2	0.2	0.15	2	2.5	<0.2
1280577	Soil	10	0.04	103	0.003	2	0.40	0.004	0.08	<0.1	0.04	0.5	0.2	0.08	2	2.0	<0.2
1280578	Soil	9	0.04	210	0.001	<1	0.37	0.009	0.06	<0.1	0.04	0.3	0.1	0.11	1	2.5	<0.2
1280579	Soil	9	0.13	479	0.003	2	0.55	0.003	0.09	<0.1	0.22	3.8	0.2	0.06	1	2.8	<0.2
1280580	Soil	8	0.11	357	0.004	1	0.68	0.011	0.05	<0.1	0.07	1.2	0.1	0.12	2	1.0	<0.2
1280631	Soil	10	0.02	259	0.004	1	0.19	0.003	0.02	<0.1	0.06	0.7	0.1	<0.05	2	4.9	<0.2
1280632	Soil	14	0.03	219	0.007	<1	0.54	0.014	0.03	<0.1	0.14	0.4	0.2	0.07	4	5.9	<0.2
1280633	Soil	12	0.03	177	0.005	2	0.41	0.014	0.03	<0.1	0.21	0.3	0.3	<0.05	3	10.0	<0.2
1280634	Soil	16	0.05	325	0.005	2	0.84	0.011	0.03	<0.1	0.17	0.5	0.4	<0.05	4	6.2	<0.2
1280635	Soil	8	<0.01	316	0.004	<1	0.22	0.005	0.02	0.1	0.01	0.3	0.1	<0.05	2	2.0	<0.2
1280636	Soil	30	0.61	139	0.013	2	1.57	0.006	0.11	0.1	0.09	1.2	0.3	0.07	5	4.1	<0.2
1280637	Soil	30	0.41	163	0.010	2	1.39	0.004	0.10	0.2	0.04	0.6	0.3	0.06	6	1.5	<0.2
1280638	Soil	17	0.34	91	0.004	2	0.74	0.015	0.05	<0.1	0.03	0.4	<0.1	0.05	3	0.9	<0.2
1280639	Soil	30	0.57	218	0.005	3	1.28	0.005	0.11	<0.1	0.03	0.7	0.2	<0.05	5	0.8	<0.2
1280640	Soil	21	0.45	184	0.005	3	1.04	0.008	0.09	<0.1	0.02	0.6	0.1	<0.05	5	1.2	<0.2
1280641	Soil	27	0.46	463	0.006	2	1.21	0.005	0.10	0.1	0.10	1.5	0.2	0.06	4	0.9	<0.2
1280642	Soil	24	0.44	113	0.005	3	0.99	0.005	0.08	<0.1	0.04	0.5	0.1	<0.05	5	0.9	<0.2
1280643	Soil	34	0.74	354	0.007	3	1.58	0.003	0.17	<0.1	0.11	3.8	0.2	<0.05	5	2.4	<0.2
1280644	Soil	29	0.34	433	0.004	2	1.07	0.004	0.11	<0.1	0.03	1.5	0.2	<0.05	6	0.7	<0.2
1280645	Soil	14	0.09	555	0.006	1	0.74	0.018	0.04	<0.1	0.08	0.9	<0.1	<0.05	4	0.9	<0.2
1280646	Soil	13	0.14	156	0.003	1	0.85	0.009	0.07	<0.1	0.04	1.8	0.1	<0.05	3	0.9	<0.2
1280647	Soil	24	0.27	767	0.005	3	1.10	0.006	0.14	<0.1	0.08	3.8	0.2	<0.05	3	0.8	<0.2
1280648	Soil	30	0.26	275	0.004	2	0.96	0.009	0.12	<0.1	0.06	0.8	0.1	0.09	4	1.4	<0.2
1280649	Soil	15	0.14	133	0.003	2	0.81	0.010	0.10	<0.1	0.05	0.6	0.2	0.07	3	0.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280650	Soil	7.7	75.1	18.6	161	0.3	37.7	23.7	689	5.33	28.9	3.8	1.3	28	0.6	3.2	0.2	39	0.32	0.234	28
1280651	Soil	5.7	49.0	14.8	118	0.1	25.2	13.3	449	4.24	14.3	3.3	0.4	9	1.1	2.0	0.2	51	0.03	0.233	10
1280652	Soil	2.0	24.1	9.9	65	<0.1	11.1	5.6	257	2.59	5.6	<0.5	0.3	8	0.6	1.2	0.2	41	0.03	0.143	8
1280653	Soil	3.5	71.5	23.5	112	<0.1	28.5	33.2	1659	4.65	14.4	2.8	0.9	13	0.2	2.0	0.3	41	0.11	0.162	16
1280654	Soil	4.9	48.0	16.3	117	0.1	32.6	15.7	773	3.97	17.1	5.4	0.9	24	0.3	1.9	0.2	52	0.24	0.186	17
1280655	Soil	3.2	68.3	17.4	102	0.1	27.0	16.4	1099	3.48	16.7	6.4	1.0	19	0.4	1.9	0.2	44	0.23	0.171	19
1280656	Soil	4.0	43.1	14.9	92	<0.1	19.2	11.5	565	3.10	12.4	2.2	0.5	14	0.1	1.8	0.2	51	0.10	0.167	10
1280657	Soil	3.4	44.3	12.9	86	0.1	19.4	10.3	386	3.31	13.5	3.5	0.5	11	0.2	1.7	0.2	49	0.06	0.199	10
1280658	Soil	1.9	32.8	8.3	73	0.2	16.1	6.7	332	1.63	6.4	2.8	0.4	18	0.5	0.9	0.1	29	0.26	0.145	13
1280659	Soil	1.8	17.0	4.9	43	<0.1	8.1	3.0	296	0.93	3.6	<0.5	0.3	36	0.4	0.6	0.1	25	0.72	0.143	6
1280660	Soil	5.7	52.5	13.7	106	<0.1	20.0	12.1	539	3.42	11.0	3.3	0.6	10	0.6	1.2	0.2	43	0.06	0.180	11
1280661	Soil	3.2	26.8	11.1	63	0.1	14.0	5.8	110	2.29	9.9	0.5	0.3	9	0.1	1.3	0.2	49	0.04	0.107	9
1280662	Soil	4.5	37.8	15.5	103	0.3	20.3	9.4	510	3.53	13.1	2.0	0.7	11	1.2	1.7	0.2	55	0.04	0.142	11
1280663	Soil	4.5	51.8	10.6	111	0.4	27.2	8.7	373	2.83	15.8	3.6	0.7	30	0.7	1.9	0.2	32	0.69	0.204	19
1280664	Soil	7.0	53.5	14.6	123	0.2	27.7	11.3	363	3.30	15.1	0.9	0.5	12	1.3	2.0	0.2	57	0.12	0.191	9
1280665	Soil	3.7	27.1	7.6	62	0.1	14.6	6.6	311	1.91	7.0	<0.5	0.3	9	0.6	0.8	<0.1	28	0.06	0.145	6
1280666	Soil	5.3	35.2	9.3	91	0.2	19.2	7.4	300	2.35	9.8	1.9	0.3	13	0.8	1.2	0.1	30	0.23	0.189	5
1280667	Soil	5.2	53.3	11.3	112	0.3	24.4	9.8	173	2.69	11.7	2.4	0.1	5	0.8	1.7	0.2	62	0.01	0.155	7
1280668	Soil	6.3	60.6	18.9	121	0.5	32.6	18.8	742	4.51	14.4	4.2	1.8	18	0.6	1.7	0.2	36	0.21	0.283	19
1280669	Soil	6.9	49.3	17.5	211	0.3	24.6	19.9	1862	3.98	18.4	0.7	0.4	26	3.2	2.3	0.2	55	0.20	0.368	12
1280670	Soil	4.2	50.7	13.5	130	0.2	23.5	13.0	997	2.78	15.4	2.8	0.2	19	0.9	2.3	0.1	26	0.13	0.200	7
1280671	Soil	7.0	67.4	17.2	139	0.3	36.1	15.1	400	3.59	18.3	5.0	0.1	13	1.1	3.0	0.3	48	0.03	0.227	10
1280672	Soil	10.5	60.7	18.3	143	0.5	31.9	19.0	877	6.62	25.7	7.0	1.5	8	0.6	2.5	0.2	51	0.11	0.269	18
1280673	Soil	8.5	74.1	17.5	160	0.6	42.7	26.6	1574	6.00	23.6	6.1	1.9	38	0.9	1.9	0.2	41	0.27	0.284	24
1280674	Soil	6.2	87.6	20.8	166	1.3	48.6	23.2	776	5.53	22.8	13.3	2.4	39	0.9	2.7	0.2	24	1.08	0.217	29
1280675	Soil	20.3	220.2	45.4	361	1.8	128.9	62.6	1709	8.35	46.2	21.5	3.6	41	2.7	8.5	0.6	43	0.57	0.251	26
1280676	Soil	18.4	136.5	31.7	268	1.1	96.3	48.0	1422	9.01	36.5	8.8	2.6	128	1.3	6.5	0.3	35	0.43	0.278	31
1280677	Soil	9.0	176.4	23.7	232	0.6	76.2	34.5	1379	9.36	30.8	6.3	5.4	22	0.9	2.1	0.4	12	1.05	0.127	25
1280678	Soil	8.4	183.2	32.1	241	0.5	90.0	48.9	1706	10.58	42.7	9.5	4.5	36	0.8	7.6	0.4	24	0.34	0.196	26
1280679	Soil	10.7	106.5	27.1	228	0.9	74.3	41.6	2600	10.81	36.4	9.8	2.8	161	1.5	7.6	0.2	20	0.13	0.267	30

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280650	Soil	17	0.39	219	0.003	2	1.23	0.003	0.16	<0.1	0.10	3.1	0.2	0.06	3	1.5	<0.2
1280651	Soil	19	0.16	157	0.005	<1	1.01	0.006	0.06	<0.1	0.03	0.5	0.1	0.05	4	1.5	<0.2
1280652	Soil	18	0.09	98	0.005	2	0.65	0.008	0.06	<0.1	0.04	0.3	<0.1	0.07	4	0.7	<0.2
1280653	Soil	24	0.39	103	0.009	<1	1.36	0.005	0.07	<0.1	0.05	1.5	0.1	0.06	4	1.3	<0.2
1280654	Soil	28	0.45	209	0.006	2	1.27	0.005	0.09	<0.1	0.03	2.0	0.1	0.07	4	1.4	<0.2
1280655	Soil	20	0.41	227	0.004	1	1.27	0.006	0.10	<0.1	0.05	1.5	0.1	0.05	4	1.8	<0.2
1280656	Soil	20	0.26	120	0.004	<1	0.89	0.004	0.06	<0.1	0.04	0.4	<0.1	0.07	4	1.3	<0.2
1280657	Soil	23	0.22	111	0.004	2	1.01	0.005	0.06	0.1	0.04	0.5	0.1	0.08	4	1.6	<0.2
1280658	Soil	17	0.28	176	0.006	3	1.06	0.013	0.05	<0.1	0.07	0.8	<0.1	0.06	3	1.2	<0.2
1280659	Soil	10	0.09	211	0.007	2	0.68	0.014	0.05	0.1	<0.01	0.4	<0.1	0.11	3	0.9	<0.2
1280660	Soil	19	0.18	134	0.004	1	0.85	0.007	0.08	<0.1	0.03	0.9	0.1	0.08	4	1.6	<0.2
1280661	Soil	15	0.14	82	0.005	<1	0.76	0.006	0.05	0.1	0.03	0.4	0.1	0.06	4	0.8	<0.2
1280662	Soil	21	0.17	99	0.008	3	0.98	0.005	0.07	0.1	0.03	0.6	0.1	0.08	5	1.3	<0.2
1280663	Soil	17	0.28	262	0.004	1	1.08	0.008	0.08	<0.1	0.14	1.5	0.2	0.09	3	1.0	<0.2
1280664	Soil	20	0.18	206	0.004	4	0.81	0.004	0.09	<0.1	0.04	0.4	0.2	0.06	4	1.0	<0.2
1280665	Soil	10	0.08	114	0.002	2	0.54	0.008	0.06	<0.1	0.01	0.2	0.1	<0.05	2	0.8	<0.2
1280666	Soil	12	0.07	133	0.002	<1	0.50	0.006	0.06	<0.1	0.04	0.2	0.1	0.10	2	0.8	<0.2
1280667	Soil	13	0.06	167	0.002	2	0.73	0.003	0.07	<0.1	0.03	0.4	0.2	<0.05	4	1.1	<0.2
1280668	Soil	20	0.41	146	0.005	3	1.19	0.005	0.09	<0.1	0.09	1.5	0.2	0.07	3	2.6	<0.2
1280669	Soil	19	0.14	399	0.007	2	0.95	0.005	0.13	<0.1	0.06	0.8	0.2	0.12	3	1.1	<0.2
1280670	Soil	10	0.08	190	0.002	<1	0.61	0.007	0.08	<0.1	0.05	0.3	0.1	0.10	2	0.7	<0.2
1280671	Soil	15	0.05	202	0.002	3	0.65	0.003	0.07	<0.1	0.07	0.3	0.2	0.09	3	1.8	0.2
1280672	Soil	17	0.33	121	0.003	2	1.12	0.002	0.05	<0.1	0.22	3.0	0.2	<0.05	3	2.0	<0.2
1280673	Soil	16	0.41	389	0.003	4	1.50	0.009	0.10	<0.1	0.24	4.4	0.3	0.18	3	2.1	<0.2
1280674	Soil	12	0.32	298	0.002	5	0.85	0.006	0.09	<0.1	0.44	7.9	0.2	0.08	2	3.3	<0.2
1280675	Soil	16	0.32	251	0.003	3	1.09	0.003	0.12	<0.1	0.78	8.4	0.5	<0.05	3	4.3	0.5
1280676	Soil	12	0.23	610	0.002	2	1.09	0.006	0.16	<0.1	0.58	6.6	0.5	0.25	2	3.5	0.3
1280677	Soil	5	0.31	319	0.003	3	0.45	0.003	0.12	<0.1	0.48	10.8	0.3	0.08	1	1.9	<0.2
1280678	Soil	12	0.23	387	0.001	2	1.08	0.003	0.09	<0.1	0.41	9.5	0.4	0.05	2	2.3	<0.2
1280679	Soil	8	0.06	399	0.002	2	0.61	0.008	0.17	<0.1	0.57	9.5	0.6	0.38	1	2.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280680	Soil	13.9	86.8	20.0	195	0.9	65.4	25.8	1275	6.44	33.6	4.2	3.9	39	1.1	2.4	0.2	30	1.48	0.156	29
1280681	Soil	10.7	98.0	19.7	261	0.9	86.7	53.2	2518	8.05	28.4	3.1	3.9	56	2.1	2.6	0.2	37	1.04	0.228	29
1280682	Soil	10.7	121.4	25.2	191	0.7	60.9	33.4	1161	5.76	28.0	7.1	4.3	126	1.0	3.3	0.3	21	0.59	0.195	24
1280683	Soil	7.7	186.9	30.9	202	1.1	82.3	39.3	1576	7.10	20.0	17.3	4.1	26	2.7	3.9	0.4	23	0.47	0.164	20
1280684	Soil	6.4	82.3	15.3	141	0.8	45.1	18.2	857	3.90	20.8	9.8	1.9	48	0.7	2.5	0.2	32	0.89	0.180	24
1280685	Soil	14.5	80.5	29.7	196	0.6	59.3	16.7	803	4.99	23.7	6.3	2.4	39	0.8	3.0	0.4	29	0.03	0.103	19
1280686	Soil	4.9	295.6	23.0	453	1.8	127.6	24.4	252	8.11	34.1	17.5	2.4	9	1.0	4.1	0.7	85	0.01	0.091	7
1280687	Soil	3.7	145.9	17.4	154	0.2	44.6	9.3	143	3.16	14.2	22.8	0.2	9	0.1	2.5	0.4	47	0.03	0.067	8
1280688	Soil	6.1	176.2	28.1	202	0.3	50.6	20.7	603	5.31	19.4	17.4	0.7	41	0.7	3.0	0.4	52	0.20	0.243	13
1280689	Soil	5.0	57.5	13.5	140	0.3	17.6	5.6	177	1.96	8.5	5.1	<0.1	20	0.7	2.1	0.3	51	0.06	0.193	9
1280690	Soil	5.4	94.1	19.5	165	0.4	27.7	10.9	442	3.51	12.6	11.0	0.3	28	0.8	3.8	0.2	55	0.12	0.211	8
1280691	Soil	2.4	151.3	28.7	147	0.2	36.7	34.0	1063	6.18	9.1	12.0	2.4	23	0.4	4.0	0.5	32	0.22	0.153	12
1280692	Soil	3.4	183.1	35.9	234	0.4	79.6	24.6	628	6.02	35.4	16.8	1.2	20	0.5	10.0	0.6	51	0.03	0.103	10
1280693	Soil	9.6	83.0	39.0	145	0.8	56.4	23.3	1387	4.81	24.6	9.4	1.4	82	0.5	3.8	0.5	41	0.24	0.217	17
1280694	Soil	8.3	122.2	37.2	266	0.3	105.8	36.2	2473	8.36	15.1	4.8	2.6	18	1.0	2.8	0.4	54	0.03	0.110	19
1280695	Soil	7.2	157.4	40.1	266	1.9	63.9	22.8	465	7.40	17.3	22.0	1.1	146	0.6	4.6	0.4	50	0.03	0.266	19
1280696	Soil	8.6	158.4	27.7	186	0.8	38.0	17.6	500	7.73	16.6	30.0	3.6	75	0.5	2.7	0.2	46	0.16	0.488	15
1280697	Soil	8.5	148.6	31.7	230	1.2	56.6	27.8	841	5.92	18.2	17.3	2.6	50	1.1	3.2	0.2	36	0.38	0.137	14
1280698	Soil	6.4	180.4	42.3	250	0.9	86.4	40.8	1531	8.13	19.3	17.0	2.9	42	1.0	3.9	0.5	30	0.21	0.179	18
1280699	Soil	6.5	173.0	54.8	245	0.6	88.7	46.5	1712	10.66	23.0	9.6	3.9	26	0.3	3.2	0.5	23	0.06	0.105	14
1280700	Soil	6.2	210.6	45.5	223	0.9	76.3	48.5	2234	13.24	16.6	8.0	3.9	10	0.3	2.7	0.4	15	0.04	0.106	10
1280701	Soil	15.6	104.5	36.2	176	1.0	86.2	22.9	1241	5.38	24.5	4.0	3.0	44	0.8	3.5	0.4	23	0.23	0.096	15
1280702	Soil	2.8	272.7	29.4	663	1.1	175.7	43.4	963	8.08	37.8	12.8	3.5	31	15.4	4.6	0.5	32	0.08	0.100	28
1280703	Soil	4.0	155.2	33.9	216	1.0	62.6	22.7	951	6.06	24.3	21.3	1.5	27	0.5	3.9	0.5	47	0.04	0.120	15
1280704	Soil	3.8	333.9	44.6	283	0.9	105.0	42.5	1226	9.79	40.7	29.1	3.3	21	1.4	7.3	0.5	67	0.04	0.163	24
1280705	Soil	8.2	134.9	26.1	182	0.8	41.2	18.6	539	5.18	19.0	18.6	3.8	39	1.1	4.5	0.2	58	0.62	0.197	32
1280706	Soil	1.4	57.0	26.1	88	0.2	24.7	20.4	1302	2.91	5.0	8.3	4.2	26	0.2	0.9	0.2	34	0.62	0.142	30
1280707	Soil	6.5	198.2	46.5	163	1.2	57.5	36.4	1131	5.19	22.6	24.4	4.7	52	1.1	4.3	0.4	72	0.92	0.216	36
1280708	Soil	8.9	73.1	15.1	197	0.8	66.6	21.3	449	5.78	28.8	4.3	2.4	43	1.1	2.7	0.1	88	1.23	0.158	28
1280709	Soil	12.1	154.0	35.5	247	0.8	63.4	39.7	1271	6.20	30.9	23.2	2.7	32	1.3	4.3	0.3	73	0.60	0.178	29

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280680	Soil	13	0.59	304	0.001	3	1.02	0.002	0.11	<0.1	0.43	7.3	0.3	0.05	3	1.9	<0.2
1280681	Soil	13	0.71	404	0.003	4	1.47	0.012	0.13	<0.1	0.43	8.9	0.4	0.33	3	3.1	<0.2
1280682	Soil	10	0.34	295	0.002	3	0.80	0.017	0.13	<0.1	0.63	6.4	0.3	0.23	2	1.5	<0.2
1280683	Soil	13	0.47	337	0.002	3	0.95	0.004	0.12	<0.1	0.45	8.1	0.4	0.06	3	2.7	<0.2
1280684	Soil	15	0.32	366	0.003	4	1.12	0.009	0.11	<0.1	0.44	5.0	0.2	0.08	3	1.9	<0.2
1280685	Soil	8	0.07	583	0.004	4	0.86	0.004	0.16	<0.1	0.43	4.0	0.3	0.14	2	4.2	0.3
1280686	Soil	23	0.04	97	0.007	4	0.83	0.002	0.10	<0.1	0.14	5.8	0.1	<0.05	5	3.0	0.4
1280687	Soil	12	0.05	73	0.009	<1	0.67	0.010	0.06	<0.1	0.05	0.9	0.1	<0.05	4	1.9	0.2
1280688	Soil	23	0.43	415	0.005	5	1.32	0.005	0.19	<0.1	0.15	1.4	0.2	0.08	4	3.2	0.2
1280689	Soil	12	0.05	178	0.001	4	0.73	0.005	0.14	<0.1	0.07	0.2	0.1	0.15	3	1.4	<0.2
1280690	Soil	20	0.20	323	0.003	6	0.85	0.006	0.21	<0.1	0.15	0.7	0.2	0.21	3	3.1	0.2
1280691	Soil	14	0.31	449	0.008	6	0.81	0.006	0.22	<0.1	0.07	9.9	0.2	<0.05	3	1.6	<0.2
1280692	Soil	19	0.10	112	0.015	3	0.84	0.007	0.11	<0.1	0.05	4.0	0.2	<0.05	4	3.1	0.3
1280693	Soil	8	0.08	1042	0.003	3	0.70	0.005	0.18	<0.1	0.23	4.2	0.2	0.27	2	3.1	<0.2
1280694	Soil	9	0.10	1899	0.004	3	1.04	0.004	0.14	<0.1	0.07	7.6	0.2	<0.05	2	2.3	<0.2
1280695	Soil	15	0.07	433	0.004	3	0.81	0.006	0.29	<0.1	0.16	2.7	0.4	0.51	3	5.4	<0.2
1280696	Soil	18	0.29	319	0.007	5	1.60	0.003	0.22	<0.1	0.14	3.8	0.4	0.07	4	4.4	<0.2
1280697	Soil	10	0.32	925	0.006	4	1.09	0.012	0.15	<0.1	0.32	5.8	0.4	<0.05	3	3.0	<0.2
1280698	Soil	9	0.14	1221	0.003	4	0.87	0.003	0.15	<0.1	0.22	8.1	0.4	<0.05	2	2.3	0.3
1280699	Soil	8	0.12	529	0.003	3	0.97	0.004	0.19	<0.1	0.17	8.2	0.3	0.20	2	1.7	0.2
1280700	Soil	6	0.07	314	0.004	3	0.73	0.008	0.10	<0.1	0.58	8.6	0.3	0.07	2	2.9	0.3
1280701	Soil	5	0.08	2299	0.003	4	0.54	0.007	0.13	<0.1	0.51	4.9	0.3	0.06	1	5.1	0.2
1280702	Soil	13	0.08	2238	0.002	2	1.17	0.002	0.08	<0.1	0.11	14.1	0.1	<0.05	2	3.6	0.2
1280703	Soil	26	0.14	411	0.010	3	1.24	0.011	0.10	<0.1	0.12	5.0	0.3	0.09	4	3.1	<0.2
1280704	Soil	36	0.26	211	0.011	2	1.87	0.007	0.10	<0.1	0.13	8.0	0.3	<0.05	5	4.4	0.2
1280705	Soil	28	1.13	1228	0.004	3	1.90	0.003	0.19	<0.1	0.24	5.4	0.3	0.12	5	3.1	<0.2
1280706	Soil	29	1.20	330	0.006	7	1.93	0.005	0.25	<0.1	0.08	5.3	0.2	0.11	6	0.9	<0.2
1280707	Soil	56	1.60	271	0.011	5	2.18	0.006	0.28	<0.1	0.22	9.0	0.2	0.07	7	2.5	<0.2
1280708	Soil	45	1.00	291	0.004	6	1.69	0.006	0.24	<0.1	0.39	8.4	0.3	0.05	5	1.5	<0.2
1280709	Soil	37	1.13	315	0.006	4	1.88	0.004	0.18	<0.1	0.24	4.9	0.2	<0.05	5	2.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280710	Soil	5.8	117.0	26.8	174	1.3	50.0	22.7	465	5.54	159.9	25.6	2.6	47	1.2	7.2	0.2	48	1.17	0.203	34
1280711	Soil	3.5	86.8	17.8	128	0.6	40.0	25.4	1003	4.86	21.8	11.2	2.6	30	0.4	3.3	0.2	41	0.96	0.227	33
1280712	Soil	14.5	121.4	23.4	231	1.6	80.6	32.1	1020	8.58	77.9	13.2	4.1	33	1.7	9.5	0.3	74	0.74	0.209	31
1280713	Soil	2.8	51.2	9.5	70	0.7	27.2	8.7	312	2.63	20.0	8.7	1.0	48	0.3	1.9	0.2	38	1.84	0.167	25
1280714	Soil	7.9	108.4	25.7	190	0.8	62.3	27.5	985	6.15	27.0	12.3	2.3	35	1.1	2.6	0.2	88	0.87	0.199	33
1280715	Soil	8.0	76.4	19.2	146	0.8	54.5	18.9	684	4.96	22.2	6.7	1.8	36	0.8	2.2	0.1	62	1.03	0.154	27
1280716	Soil	5.7	73.6	23.2	115	0.6	41.4	23.1	2227	5.30	19.1	7.0	2.4	59	0.8	2.2	0.2	80	1.52	0.251	38
1280717	Soil	6.3	130.5	47.8	128	0.3	43.8	43.6	2243	3.81	17.3	8.3	3.2	35	0.6	3.6	0.3	85	0.72	0.156	32
1280718	Soil	11.6	132.7	31.6	263	2.1	50.1	25.6	1101	5.08	22.6	14.5	2.9	54	3.3	5.6	0.3	98	0.81	0.201	34
1280719	Soil	7.7	124.7	28.3	199	1.8	57.0	34.2	2098	6.06	22.7	17.7	3.6	42	1.6	3.4	0.2	88	0.66	0.232	36
1280720	Soil	3.3	60.3	13.2	100	0.7	26.2	12.1	638	2.52	8.8	8.8	1.2	50	0.6	1.7	0.2	50	1.17	0.170	22
1280721	Soil	7.2	182.7	27.7	254	0.4	47.4	15.5	886	5.57	21.4	41.6	0.8	21	0.4	3.7	0.4	95	0.06	0.152	18
1280722	Soil	2.8	58.9	13.9	90	0.2	21.5	4.5	140	1.68	9.2	7.0	0.2	20	0.3	1.3	0.2	35	0.09	0.085	10
1280723	Soil	5.6	131.3	19.2	286	0.6	64.1	16.7	456	4.30	19.3	14.1	4.1	50	2.3	3.3	0.3	64	0.48	0.197	25
1280724	Soil	5.4	68.6	18.5	133	0.5	29.7	14.3	737	3.36	16.5	8.7	0.9	23	0.9	2.7	0.2	63	0.14	0.217	17
1280725	Soil	5.1	153.4	21.6	171	1.3	43.2	18.6	710	3.19	9.6	23.6	1.4	62	1.0	2.2	0.2	57	1.25	0.169	14
1280726	Soil	2.1	40.2	7.9	137	0.4	22.9	5.3	302	1.54	6.4	3.2	0.4	81	1.2	1.3	0.2	28	2.02	0.113	11
1280727	Soil	3.5	133.1	16.5	178	0.6	37.9	10.7	462	2.76	16.7	12.1	1.0	76	1.3	2.9	0.2	50	1.62	0.197	16
1280728	Soil	1.0	5.9	2.1	12	<0.1	3.8	1.7	70	0.40	1.1	<0.5	<0.1	5	<0.1	0.2	<0.1	6	0.03	0.027	1
1280729	Soil	22.7	94.4	33.1	207	0.4	87.6	44.5	2140	7.20	24.7	9.8	3.8	49	0.8	3.1	0.3	45	0.14	0.143	23
1280730	Soil	5.8	155.4	36.3	181	0.5	46.3	27.7	1065	6.60	26.3	9.2	2.3	50	0.7	3.0	0.4	59	0.10	0.147	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

CERTIFICATE OF ANALYSIS WHI11001220.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280710	Soil	24	0.71	542	0.003	4	1.29	0.004	0.17	<0.1	0.35	9.5	0.2	0.06	4	2.8	<0.2
1280711	Soil	23	0.71	2175	0.003	4	1.47	0.004	0.18	<0.1	0.24	9.8	0.1	0.08	5	1.9	<0.2
1280712	Soil	37	0.69	877	0.003	3	1.50	0.005	0.18	<0.1	0.64	11.2	0.4	0.10	5	4.2	<0.2
1280713	Soil	22	0.34	834	0.004	5	1.03	0.008	0.10	<0.1	0.25	4.1	0.1	0.15	3	1.9	<0.2
1280714	Soil	43	0.96	452	0.004	6	1.71	0.006	0.25	<0.1	0.26	8.2	0.2	0.07	5	2.0	<0.2
1280715	Soil	29	0.51	398	0.004	5	1.18	0.010	0.18	<0.1	0.33	8.2	0.2	0.07	4	2.1	<0.2
1280716	Soil	44	0.74	451	0.005	4	1.78	0.007	0.13	<0.1	0.17	4.9	0.2	0.12	5	2.2	<0.2
1280717	Soil	31	0.89	453	0.006	5	1.68	0.004	0.25	<0.1	0.14	5.8	0.2	<0.05	6	1.4	<0.2
1280718	Soil	39	0.82	482	0.005	6	1.92	0.007	0.25	<0.1	0.34	5.7	0.4	0.05	6	4.0	<0.2
1280719	Soil	39	0.91	375	0.009	7	2.04	0.009	0.27	<0.1	0.30	9.3	0.2	<0.05	6	2.7	<0.2
1280720	Soil	23	0.50	303	0.006	4	1.32	0.017	0.12	<0.1	0.17	3.0	0.1	0.08	5	1.2	<0.2
1280721	Soil	37	0.23	173	0.008	3	1.15	0.005	0.14	0.1	0.14	1.5	0.2	0.07	7	1.8	0.3
1280722	Soil	16	0.10	112	0.004	1	0.66	0.016	0.06	<0.1	0.06	0.4	0.1	<0.05	3	1.0	<0.2
1280723	Soil	30	0.55	393	0.016	3	1.23	0.007	0.16	0.1	0.17	5.0	0.2	<0.05	4	2.3	<0.2
1280724	Soil	24	0.40	256	0.009	3	1.45	0.011	0.12	0.1	0.11	1.0	0.2	<0.05	5	2.2	<0.2
1280725	Soil	19	0.43	498	0.005	3	1.19	0.008	0.19	<0.1	0.20	2.9	0.3	0.06	4	2.6	<0.2
1280726	Soil	10	0.33	251	0.005	3	0.81	0.026	0.06	<0.1	0.17	0.9	0.1	0.09	2	1.4	<0.2
1280727	Soil	21	0.47	392	0.005	3	1.24	0.007	0.13	<0.1	0.20	1.9	0.2	0.07	3	2.1	<0.2
1280728	Soil	3	0.03	63	0.003	<1	0.15	0.022	0.03	<0.1	0.03	0.1	<0.1	<0.05	<1	<0.5	<0.2
1280729	Soil	27	0.33	1015	0.003	2	1.63	0.010	0.21	<0.1	0.12	4.2	0.3	0.12	5	2.0	<0.2
1280730	Soil	30	0.35	559	0.006	2	1.69	0.010	0.19	<0.1	0.08	3.2	0.3	0.17	5	1.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

QUALITY CONTROL REPORT WHI11001220.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1094972	Soil	36.6	22.3	5.6	132	0.2	69.8	6.0	289	1.16	32.8	1.9	0.5	34	0.9	2.5	0.1	53	0.78	0.046	4
REP 1094972	QC	36.3	22.1	6.1	136	0.2	69.2	5.7	275	1.12	32.8	3.0	0.5	34	0.9	2.6	0.1	51	0.76	0.044	4
1277561	Soil	88.1	107.3	11.4	1033	1.3	242.3	9.2	221	2.13	41.2	3.5	3.8	141	10.9	19.4	0.2	341	3.43	0.093	24
REP 1277561	QC	87.8	110.6	12.0	1054	1.3	243.8	8.8	231	2.22	42.3	2.5	3.9	141	11.5	20.1	0.2	363	3.57	0.092	25
1278663	Soil	10.0	128.4	37.8	418	3.2	117.9	20.9	369	6.11	26.3	7.6	2.0	43	1.4	3.9	0.4	104	0.20	0.269	14
REP 1278663	QC	10.6	128.1	37.4	426	3.3	121.7	20.4	364	6.19	27.9	8.9	2.1	43	1.4	4.0	0.4	102	0.20	0.270	14
1278668	Soil	14.8	98.7	29.9	442	1.8	115.3	12.1	372	3.19	40.6	3.4	1.8	98	4.0	5.8	0.3	83	0.68	0.313	16
REP 1278668	QC	16.7	103.6	31.3	455	1.8	123.0	12.8	373	3.30	42.0	5.7	2.0	104	4.2	6.3	0.3	91	0.68	0.323	17
1278785	Soil	35.7	192.3	100.4	518	3.3	198.3	15.3	390	4.69	60.3	6.0	4.3	239	3.4	16.3	0.6	207	1.59	0.999	25
REP 1278785	QC	35.2	191.7	100.9	500	3.3	195.7	15.2	388	4.66	58.8	6.2	4.2	228	3.5	15.9	0.6	198	1.48	0.949	25
1278834	Soil	4.8	81.3	18.5	226	0.4	40.0	17.4	629	3.32	24.3	5.9	0.7	25	1.2	1.7	0.4	32	0.07	0.089	8
REP 1278834	QC	4.7	79.1	18.7	224	0.4	39.5	17.5	623	3.36	24.2	6.4	0.7	25	1.1	1.7	0.4	34	0.06	0.091	8
1278855	Soil	2.5	22.7	12.2	88	<0.1	16.1	7.3	121	1.97	13.2	3.7	0.3	8	0.1	1.3	0.3	39	0.02	0.038	8
REP 1278855	QC	2.4	22.9	12.2	92	<0.1	16.4	7.7	122	2.02	13.4	3.3	0.2	8	<0.1	1.4	0.3	41	0.02	0.038	8
1278909	Soil	27.1	301.5	22.0	1417	3.5	422.9	60.6	2608	6.16	42.5	3.4	4.0	70	15.6	13.3	0.2	271	0.18	0.367	16
REP 1278909	QC	28.1	302.1	21.3	1400	3.3	404.1	57.7	2594	6.03	42.0	2.9	3.8	71	15.5	12.7	0.2	273	0.18	0.388	16
1278916	Soil	94.9	132.6	27.8	683	7.5	98.5	9.7	331	4.17	80.2	4.1	1.1	165	12.4	64.7	0.4	580	0.29	0.641	23
REP 1278916	QC	92.8	135.8	28.1	679	7.5	101.7	9.2	334	4.35	80.4	5.4	1.2	164	12.8	64.9	0.4	566	0.28	0.631	22
1278949	Soil	9.5	14.9	3.3	72	4.1	15.7	2.1	28	0.77	8.1	3.0	0.1	4	0.2	2.4	<0.1	81	0.01	0.034	15
REP 1278949	QC	8.9	15.1	3.3	75	4.1	15.9	2.1	27	0.76	7.9	0.7	0.1	4	0.2	2.2	0.1	80	0.01	0.032	15
1280244	Soil	6.5	17.8	13.0	76	0.5	12.1	2.0	39	1.19	12.2	1.7	<0.1	13	0.2	2.5	0.2	75	0.02	0.083	8
REP 1280244	QC	6.9	17.1	12.6	73	0.5	11.8	2.0	39	1.21	12.2	3.1	<0.1	14	0.2	2.5	0.2	74	0.02	0.079	8
1280574	Soil	28.5	55.6	12.8	364	0.8	85.4	7.3	124	2.27	27.5	3.1	1.9	63	3.3	6.2	0.3	97	0.51	0.116	10
REP 1280574	QC	26.6	54.4	12.4	359	0.8	86.1	7.1	128	2.18	27.1	2.2	1.8	60	2.9	6.1	0.2	92	0.52	0.110	10
1280577	Soil	7.8	152.3	12.0	145	0.1	42.6	12.8	269	3.76	32.5	10.7	0.1	8	0.4	6.5	0.3	45	0.03	0.112	8
REP 1280577	QC	6.9	146.5	11.6	142	<0.1	41.4	12.3	252	3.54	31.4	9.4	0.2	8	0.4	6.0	0.3	44	0.03	0.112	7
1280653	Soil	3.5	71.5	23.5	112	<0.1	28.5	33.2	1659	4.65	14.4	2.8	0.9	13	0.2	2.0	0.3	41	0.11	0.162	16
REP 1280653	QC	3.5	70.9	22.8	114	<0.1	29.2	32.3	1590	4.37	13.9	2.6	1.0	13	0.3	2.1	0.3	40	0.11	0.160	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

QUALITY CONTROL REPORT WHI11001220.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1094972	Soil		6	0.07	223	0.004	2	0.39	0.016	0.02	0.1	0.43	1.1	0.3	0.14	<1	1.1	<0.2
REP 1094972	QC		6	0.07	222	0.004	3	0.40	0.016	0.02	0.1	0.42	1.0	0.3	0.13	<1	0.8	<0.2
1277561	Soil		23	1.68	878	0.003	4	0.22	0.005	0.06	0.3	1.02	3.9	1.2	0.10	<1	6.6	<0.2
REP 1277561	QC		25	1.82	886	0.002	4	0.23	0.005	0.06	0.2	1.03	4.0	1.4	0.12	<1	6.4	0.2
1278663	Soil		16	0.04	4977	0.003	2	0.81	0.003	0.08	<0.1	0.71	3.9	0.3	<0.05	1	5.2	<0.2
REP 1278663	QC		17	0.05	5037	0.003	4	0.81	0.003	0.08	<0.1	0.77	4.0	0.2	<0.05	2	7.8	<0.2
1278668	Soil		18	0.07	703	0.003	7	0.52	0.002	0.18	0.1	0.45	3.2	0.7	0.06	2	3.1	<0.2
REP 1278668	QC		20	0.07	743	0.003	8	0.56	0.002	0.18	0.2	0.49	3.3	0.8	0.10	2	3.5	<0.2
1278785	Soil		29	0.08	718	0.009	10	0.70	0.004	0.32	0.3	0.71	4.1	0.5	0.42	2	15.8	0.5
REP 1278785	QC		28	0.07	655	0.008	10	0.69	0.004	0.28	0.3	0.74	4.0	0.5	0.39	2	16.9	0.5
1278834	Soil		12	0.09	157	0.012	3	0.68	0.016	0.10	<0.1	0.07	3.1	0.2	0.08	3	1.8	<0.2
REP 1278834	QC		12	0.10	159	0.012	4	0.70	0.017	0.10	<0.1	0.06	3.1	0.2	0.09	3	1.8	<0.2
1278855	Soil		13	0.05	55	0.009	<1	0.46	0.002	0.03	0.2	<0.01	0.9	0.1	0.05	3	0.7	<0.2
REP 1278855	QC		12	0.05	54	0.010	<1	0.47	0.002	0.03	0.2	<0.01	0.9	0.1	0.07	3	<0.5	<0.2
1278909	Soil		63	0.29	970	0.010	4	4.81	0.006	0.16	0.3	0.35	12.0	4.3	0.30	3	12.5	<0.2
REP 1278909	QC		64	0.30	1004	0.010	5	4.91	0.007	0.15	0.3	0.32	12.0	4.3	0.31	3	13.2	0.3
1278916	Soil		120	0.12	910	0.007	5	1.10	0.007	0.18	0.7	0.55	1.8	6.9	0.45	6	53.5	1.0
REP 1278916	QC		121	0.11	965	0.006	3	1.08	0.007	0.17	0.8	0.57	2.2	6.8	0.47	6	54.3	0.8
1278949	Soil		12	0.01	132	0.004	2	0.23	0.004	0.04	0.1	0.04	0.3	0.2	0.07	2	1.2	<0.2
REP 1278949	QC		12	0.01	134	0.005	2	0.22	0.004	0.04	0.1	0.01	0.2	0.2	0.05	2	1.2	<0.2
1280244	Soil		11	0.02	102	0.001	2	0.32	0.007	0.06	<0.1	0.05	0.1	0.3	<0.05	3	1.7	<0.2
REP 1280244	QC		12	0.02	100	0.001	3	0.32	0.007	0.05	<0.1	0.04	0.2	0.3	0.05	3	1.8	<0.2
1280574	Soil		16	0.17	1379	0.004	3	0.68	0.006	0.07	0.2	0.45	3.0	0.3	0.12	2	2.2	<0.2
REP 1280574	QC		17	0.16	1306	0.003	4	0.66	0.006	0.07	0.2	0.47	2.8	0.3	0.09	2	2.5	<0.2
1280577	Soil		10	0.04	103	0.003	2	0.40	0.004	0.08	<0.1	0.04	0.5	0.2	0.08	2	2.0	<0.2
REP 1280577	QC		10	0.04	94	0.003	2	0.37	0.004	0.07	<0.1	0.04	0.5	0.1	0.08	2	2.8	<0.2
1280653	Soil		24	0.39	103	0.009	<1	1.36	0.005	0.07	<0.1	0.05	1.5	0.1	0.06	4	1.3	<0.2
REP 1280653	QC		22	0.38	99	0.008	3	1.36	0.004	0.07	0.1	0.05	1.3	0.1	0.07	4	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

QUALITY CONTROL REPORT WHI11001220.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1280680	Soil	13.9	86.8	20.0	195	0.9	65.4	25.8	1275	6.44	33.6	4.2	3.9	39	1.1	2.4	0.2	30	1.48	0.156	29
REP 1280680	QC	14.1	90.5	21.3	208	0.9	68.0	26.8	1268	6.48	34.5	4.3	4.0	43	1.1	2.2	0.2	31	1.56	0.166	30
1280700	Soil	6.2	210.6	45.5	223	0.9	76.3	48.5	2234	13.24	16.6	8.0	3.9	10	0.3	2.7	0.4	15	0.04	0.106	10
REP 1280700	QC	6.4	212.2	47.9	231	0.9	75.8	48.0	2349	13.40	16.9	7.8	3.9	10	0.3	2.9	0.4	16	0.04	0.107	10
1280710	Soil	5.8	117.0	26.8	174	1.3	50.0	22.7	465	5.54	159.9	25.6	2.6	47	1.2	7.2	0.2	48	1.17	0.203	34
REP 1280710	QC	5.8	117.3	26.9	177	1.3	51.1	23.2	465	5.66	163.5	27.0	2.7	48	1.3	7.3	0.2	50	1.19	0.209	34
1280715	Soil	8.0	76.4	19.2	146	0.8	54.5	18.9	684	4.96	22.2	6.7	1.8	36	0.8	2.2	0.1	62	1.03	0.154	27
REP 1280715	QC	8.2	77.9	18.8	145	0.9	56.9	20.0	725	5.38	24.4	6.5	2.0	36	0.8	2.5	0.1	67	1.03	0.159	29
Reference Materials																					
STD DS8	Standard	11.6	109.1	125.2	301	1.7	37.7	7.0	584	2.34	23.7	132.2	6.1	66	2.3	5.7	6.0	41	0.64	0.075	13
STD DS8	Standard	12.1	106.2	122.1	311	1.7	38.0	7.4	574	2.40	23.3	129.0	6.3	64	2.3	5.4	5.7	41	0.65	0.080	14
STD DS8	Standard	12.5	106.0	122.9	301	1.9	36.8	7.4	570	2.45	24.7	125.6	6.3	62	2.4	5.3	6.3	40	0.62	0.080	14
STD DS8	Standard	13.3	107.6	129.7	310	1.8	38.2	7.8	610	2.49	26.9	122.6	6.8	65	2.4	5.6	7.3	42	0.71	0.083	15
STD DS8	Standard	13.8	110.5	126.6	325	1.9	37.4	7.8	637	2.48	25.3	106.6	7.1	66	2.4	5.6	6.7	44	0.72	0.076	16
STD DS8	Standard	13.0	116.0	125.3	310	1.7	39.7	7.8	609	2.38	25.3	112.5	6.3	65	2.2	5.2	7.3	44	0.68	0.076	14
STD DS8	Standard	13.2	115.3	123.7	307	1.8	38.9	7.7	574	2.48	24.5	110.4	7.0	72	2.1	5.5	7.2	43	0.66	0.084	15
STD DS8	Standard	13.5	117.3	130.4	332	1.9	40.9	7.9	643	2.59	27.4	121.8	6.6	72	2.3	5.6	7.1	47	0.69	0.086	14
STD DS8	Standard	13.4	114.4	119.4	302	1.6	37.6	7.7	613	2.45	25.1	101.4	6.8	68	2.3	5.5	6.4	43	0.68	0.075	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 24, 2011

QUALITY CONTROL REPORT WHI11001220.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1280680	Soil	13	0.59	304	0.001	3	1.02	0.002	0.11	<0.1	0.43	7.3	0.3	0.05	3	1.9	<0.2
REP 1280680	QC	14	0.62	323	0.003	3	1.17	0.003	0.12	<0.1	0.45	7.8	0.3	<0.05	3	1.9	<0.2
1280700	Soil	6	0.07	314	0.004	3	0.73	0.008	0.10	<0.1	0.58	8.6	0.3	0.07	2	2.9	0.3
REP 1280700	QC	6	0.07	313	0.005	3	0.71	0.008	0.11	<0.1	0.64	8.9	0.2	0.06	2	2.9	0.4
1280710	Soil	24	0.71	542	0.003	4	1.29	0.004	0.17	<0.1	0.35	9.5	0.2	0.06	4	2.8	<0.2
REP 1280710	QC	25	0.72	556	0.003	6	1.37	0.005	0.18	<0.1	0.37	10.0	0.1	0.05	4	3.0	<0.2
1280715	Soil	29	0.51	398	0.004	5	1.18	0.010	0.18	<0.1	0.33	8.2	0.2	0.07	4	2.1	<0.2
REP 1280715	QC	31	0.54	430	0.004	6	1.21	0.010	0.18	<0.1	0.35	8.6	0.2	0.06	4	1.7	<0.2
Reference Materials																	
STD DS8	Standard	110	0.58	262	0.103	2	0.87	0.093	0.43	2.9	0.21	2.0	5.5	0.10	4	5.3	4.8
STD DS8	Standard	117	0.64	259	0.107	<1	0.93	0.093	0.42	2.8	0.16	2.1	5.3	0.18	5	5.5	4.6
STD DS8	Standard	107	0.59	258	0.097	2	0.86	0.082	0.41	2.7	0.20	1.9	5.6	0.21	4	5.0	4.9
STD DS8	Standard	117	0.61	280	0.112	3	0.91	0.091	0.42	3.1	0.19	2.4	5.6	0.18	5	5.7	5.4
STD DS8	Standard	118	0.61	284	0.114	3	0.92	0.096	0.45	3.0	0.18	2.5	5.5	0.13	5	6.0	4.7
STD DS8	Standard	117	0.62	269	0.117	2	0.90	0.087	0.41	3.2	0.21	2.0	5.4	0.17	4	5.3	4.8
STD DS8	Standard	113	0.66	271	0.119	3	0.95	0.108	0.39	2.9	0.17	2.1	5.5	0.21	5	4.2	4.9
STD DS8	Standard	119	0.65	266	0.116	3	0.90	0.089	0.43	2.9	0.19	2.1	5.6	0.27	5	5.3	5.0
STD DS8	Standard	118	0.60	266	0.116	3	0.98	0.110	0.42	2.7	0.18	2.7	5.3	0.11	5	4.8	4.9
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 24, 2011
Report Date: November 02, 2011
Page: 1 of 7

CERTIFICATE OF ANALYSIS WHI11001221.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #16
P.O. Number
Number of Samples: 170

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	170	Sieve soil to 230 mesh			WHI
RJSV	170	Saving all or part of Soil Reject			WHI
1DX2	169	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

CERTIFICATE OF ANALYSIS WHI11001221.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280731	Soil		7.9	93.2	38.5	159	0.6	49.3	30.8	2208	6.13	27.5	4.4	3.4	29	0.4	2.4	0.4	50	0.07	0.125	17
1280732	Soil		4.5	160.4	27.4	744	0.8	147.5	48.9	2804	6.81	209.8	15.1	3.5	26	3.3	4.7	0.4	60	0.03	0.092	16
1280733	Soil		3.7	38.1	10.4	506	0.4	100.9	22.8	2591	2.81	17.2	5.4	0.8	140	2.7	2.3	0.1	46	6.64	0.100	10
1280734	Soil		2.4	37.9	11.1	83	0.2	15.2	8.9	598	2.19	7.2	5.4	0.4	14	0.7	1.3	0.2	43	0.30	0.160	11
1280735	Soil		6.2	81.2	18.6	162	0.8	23.2	13.8	785	3.01	16.5	15.1	0.8	39	0.7	2.8	0.3	83	0.56	0.219	18
1280736	Soil		3.4	77.6	21.6	92	0.4	19.4	15.4	509	2.74	13.2	5.1	0.3	19	0.7	3.1	0.4	73	0.21	0.164	12
1280737	Soil		18.0	42.5	31.4	313	0.3	62.9	9.3	240	3.44	35.1	3.6	2.6	27	1.2	4.8	0.4	93	0.02	0.100	14
1280738	Soil		7.9	27.4	16.2	145	0.7	24.7	9.0	323	1.86	17.4	4.4	1.5	38	1.4	2.3	0.2	73	0.29	0.074	8
1280739	Soil		16.1	48.5	19.1	271	0.6	60.0	8.5	264	2.42	26.0	4.9	2.3	28	2.9	4.9	0.8	130	0.13	0.085	12
1280740	Soil		14.3	31.1	24.0	192	0.2	43.8	6.5	123	2.92	31.9	8.9	1.3	26	0.7	4.9	0.5	119	0.03	0.073	12
1280741	Soil		15.8	38.0	23.4	179	0.6	42.3	5.9	101	2.53	30.7	4.9	1.6	28	0.7	4.7	0.4	103	0.05	0.074	15
1280742	Soil		18.9	46.5	14.5	294	0.5	65.8	9.0	163	2.30	23.7	4.7	3.7	35	3.1	5.2	0.5	90	0.24	0.105	15
1280743	Soil		13.7	21.4	13.5	125	0.3	31.1	3.6	76	1.62	24.0	2.4	0.3	14	0.9	3.7	0.3	108	0.06	0.081	14
1280744	Soil		19.4	49.9	15.6	286	1.1	64.0	5.0	161	2.09	29.6	5.2	0.6	28	3.1	5.5	0.3	139	0.14	0.105	12
1280745	Soil		10.9	20.1	17.0	125	0.8	27.0	4.1	101	2.64	21.8	5.4	1.3	21	0.6	2.9	0.3	112	0.06	0.069	12
1280746	Soil		14.8	22.1	16.1	171	0.2	37.5	4.8	96	2.29	29.3	2.0	2.1	13	0.5	4.0	0.3	155	0.02	0.094	14
1280747	Soil		25.4	30.6	19.4	294	1.3	59.0	5.2	110	2.73	38.4	3.1	0.6	18	0.8	6.4	0.3	169	0.02	0.130	12
1280748	Soil		16.4	22.1	14.1	240	1.1	42.0	4.5	106	2.65	26.0	3.2	1.8	13	1.0	4.0	0.3	178	0.04	0.100	13
1280749	Soil		56.2	14.1	8.9	286	1.4	100.6	2.6	35	1.31	14.9	0.8	1.2	5	0.5	10.1	0.3	405	0.01	0.028	36
1280750	Soil		27.0	13.8	4.7	204	0.6	49.5	1.5	19	0.84	10.1	2.0	0.3	4	0.9	9.5	0.1	259	0.02	0.030	23
1280751	Soil		19.6	53.0	13.2	314	0.5	65.8	5.4	135	1.80	28.7	4.6	1.4	36	5.1	5.7	0.2	134	0.28	0.112	17
1280752	Soil		14.7	26.2	7.8	213	0.5	42.9	5.5	363	1.26	16.1	3.3	0.7	32	2.1	3.4	0.2	91	0.36	0.074	10
1280753	Soil		10.3	34.3	7.4	363	0.3	60.8	8.1	460	1.01	10.3	3.3	1.1	70	2.5	2.8	0.2	58	2.15	0.093	7
1280754	Soil		12.4	61.1	11.3	1188	0.8	212.6	6.8	118	1.79	19.3	3.8	2.3	61	17.1	4.4	0.2	114	1.04	0.089	11
1280755	Soil		16.2	79.4	10.9	1889	0.8	204.5	4.2	134	1.55	23.5	5.2	1.1	46	10.4	4.7	0.1	134	0.63	0.051	11
1280756	Soil		17.7	41.2	11.1	262	0.8	44.8	4.3	209	1.84	30.5	5.9	2.3	64	1.7	5.9	0.2	96	0.64	0.106	10
1280757	Soil		13.8	62.7	14.8	333	1.2	70.3	9.0	234	2.49	23.9	4.9	3.0	48	3.3	4.1	0.6	103	0.28	0.121	13
1280758	Soil		15.0	64.2	20.3	266	1.1	55.6	7.3	220	2.79	26.6	5.2	1.1	33	3.5	3.8	0.3	114	0.09	0.125	12
1280759	Soil		12.9	48.7	17.1	251	0.7	52.3	7.9	207	2.65	28.6	5.5	1.2	35	2.0	3.9	0.3	99	0.14	0.104	11
1280760	Soil		13.8	44.8	17.3	243	0.4	50.8	7.6	184	2.74	31.5	4.9	2.3	39	1.4	4.6	0.3	95	0.15	0.130	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

CERTIFICATE OF ANALYSIS WHI11001221.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280731	Soil		23	0.32	728	0.010	4	1.59	0.013	0.17	0.1	0.13	4.5	0.2	0.13	5	1.7	0.3
1280732	Soil		27	0.20	233	0.007	2	1.40	0.004	0.09	0.1	0.10	6.3	0.2	<0.05	5	1.1	<0.2
1280733	Soil		15	0.58	569	0.007	4	0.93	0.007	0.08	0.1	0.17	1.5	0.2	<0.05	2	0.9	<0.2
1280734	Soil		18	0.32	212	0.003	3	0.87	0.007	0.08	<0.1	0.12	0.5	0.1	0.13	5	<0.5	<0.2
1280735	Soil		23	0.44	429	0.003	2	1.29	0.006	0.07	<0.1	0.28	1.5	0.2	0.05	6	1.4	<0.2
1280736	Soil		24	0.35	260	0.004	4	1.07	0.006	0.12	0.1	0.20	0.8	0.1	0.11	6	<0.5	<0.2
1280737	Soil		14	0.05	467	0.003	3	0.51	0.003	0.10	0.1	0.10	2.0	0.4	<0.05	2	1.2	<0.2
1280738	Soil		16	0.12	772	0.002	2	0.83	0.009	0.06	<0.1	0.45	2.2	0.3	<0.05	2	1.8	<0.2
1280739	Soil		22	0.13	714	0.004	4	0.90	0.005	0.07	0.2	0.39	2.9	0.6	0.12	3	2.0	<0.2
1280740	Soil		21	0.12	210	0.006	3	0.92	0.004	0.06	0.2	0.05	1.5	0.4	<0.05	4	2.1	<0.2
1280741	Soil		18	0.12	282	0.005	2	0.72	0.004	0.07	0.2	0.18	1.6	0.4	<0.05	3	2.7	<0.2
1280742	Soil		19	0.15	1001	0.003	2	0.84	0.003	0.06	0.1	0.37	3.2	0.3	<0.05	2	2.4	<0.2
1280743	Soil		12	0.05	250	0.003	2	0.52	0.004	0.05	0.2	0.09	0.5	0.5	<0.05	3	1.3	<0.2
1280744	Soil		20	0.10	991	0.003	3	0.96	0.008	0.07	0.2	0.49	1.2	0.7	<0.05	3	2.4	<0.2
1280745	Soil		20	0.14	251	0.009	2	0.97	0.005	0.06	0.2	0.12	1.3	0.4	<0.05	4	1.6	<0.2
1280746	Soil		16	0.09	237	0.003	2	0.81	0.003	0.06	0.2	0.02	1.4	0.5	<0.05	4	1.6	<0.2
1280747	Soil		20	0.10	175	0.005	2	0.81	0.004	0.06	0.2	0.07	0.7	0.6	<0.05	5	2.6	<0.2
1280748	Soil		22	0.11	229	0.004	2	1.15	0.004	0.05	0.2	0.13	1.3	0.6	<0.05	4	1.9	<0.2
1280749	Soil		18	0.04	81	0.015	2	0.42	0.004	0.05	0.4	<0.01	0.7	1.3	<0.05	4	2.4	<0.2
1280750	Soil		12	0.02	64	0.005	2	0.24	0.010	0.04	0.2	<0.01	0.1	0.5	<0.05	3	4.9	<0.2
1280751	Soil		17	0.13	1110	0.002	3	0.67	0.005	0.08	0.1	0.39	1.8	0.5	<0.05	2	1.5	<0.2
1280752	Soil		13	0.11	564	0.003	3	0.63	0.016	0.07	0.1	0.24	1.2	0.3	<0.05	2	0.9	<0.2
1280753	Soil		9	0.08	765	0.003	6	0.47	0.018	0.05	<0.1	0.26	1.5	0.2	0.24	1	1.0	<0.2
1280754	Soil		22	0.17	673	0.003	3	0.88	0.007	0.06	0.2	0.38	2.9	0.6	0.17	3	1.9	<0.2
1280755	Soil		20	0.13	621	0.003	3	0.91	0.017	0.07	0.1	0.40	2.5	0.8	0.13	2	1.2	<0.2
1280756	Soil		18	0.14	775	0.003	4	0.74	0.008	0.09	0.2	0.50	2.0	0.7	0.14	2	2.2	<0.2
1280757	Soil		19	0.15	2019	0.002	3	1.04	0.008	0.09	0.2	0.48	3.3	0.5	0.07	3	1.9	<0.2
1280758	Soil		24	0.14	972	0.002	2	1.18	0.005	0.10	0.2	0.47	1.7	0.4	<0.05	3	1.9	<0.2
1280759	Soil		20	0.14	1109	0.002	2	0.95	0.006	0.09	0.2	0.32	2.0	0.3	<0.05	3	1.7	<0.2
1280760	Soil		19	0.14	866	0.003	2	0.85	0.003	0.09	0.2	0.23	2.1	0.4	<0.05	3	2.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

CERTIFICATE OF ANALYSIS WHI11001221.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280761	Soil		11.8	36.2	17.1	200	0.2	43.8	6.3	123	2.65	28.9	3.5	3.1	30	0.8	4.0	0.3	89	0.07	0.086	13
1280762	Soil		13.3	48.0	18.4	212	1.2	47.1	7.0	134	2.71	28.4	5.2	2.0	43	1.3	3.9	0.3	100	0.16	0.136	12
1280763	Soil		13.9	61.5	17.3	277	0.6	63.3	11.0	293	3.50	30.0	5.5	3.8	38	1.8	5.1	0.2	96	0.17	0.159	14
1280764	Soil		10.9	36.0	16.5	187	0.4	41.4	6.0	104	2.41	24.1	1.6	2.6	25	1.4	4.0	0.2	95	0.05	0.079	14
1280765	Soil		16.0	62.0	16.2	289	0.6	61.9	8.4	225	2.34	74.4	6.2	1.8	48	1.8	5.9	0.2	96	0.22	0.175	19
1280766	Soil		14.6	56.2	15.8	283	0.4	57.8	8.3	225	2.43	32.1	3.6	3.2	50	2.1	5.5	0.2	98	0.25	0.158	20
1280767	Soil		12.8	47.4	16.2	253	0.3	51.3	9.2	232	2.34	27.4	5.2	2.9	44	1.9	4.7	0.2	80	0.20	0.148	15
1280768	Soil		13.6	65.3	16.3	300	0.6	67.9	8.4	200	2.60	29.3	4.3	3.8	57	2.6	5.3	0.2	88	0.29	0.157	18
1280769	Soil		17.0	48.3	17.9	260	0.3	47.0	9.6	240	2.68	27.1	2.9	2.4	38	2.0	3.8	0.3	86	0.25	0.109	13
1280770	Soil		11.6	45.8	14.0	219	0.5	50.8	7.3	148	2.52	25.3	2.9	2.5	37	1.2	3.1	0.2	65	0.33	0.104	13
1281201	Soil		8.1	32.4	14.6	156	0.3	40.3	8.2	136	2.13	13.2	2.9	3.1	47	0.8	2.0	0.2	54	0.52	0.086	9
1281202	Soil		6.2	23.7	11.0	97	0.3	23.8	4.8	109	1.52	14.1	2.1	2.0	44	0.8	1.9	0.2	62	0.50	0.089	7
1281203	Soil		4.0	33.5	19.7	99	0.8	30.0	4.1	150	1.26	7.0	2.5	1.4	40	1.3	1.8	0.2	45	0.55	0.063	4
1281204	Soil		1.6	31.5	21.6	89	0.7	27.2	3.8	40	1.01	3.5	3.1	2.0	40	1.4	1.1	0.2	48	0.66	0.050	4
1281205	Soil		15.1	65.3	16.0	310	0.7	67.4	10.7	276	2.78	24.8	4.6	2.2	45	3.3	5.0	0.5	102	0.28	0.116	16
1281206	Soil		25.8	34.8	10.4	243	0.5	55.5	8.0	841	2.80	24.6	5.6	1.0	45	2.4	3.5	0.2	118	0.72	0.107	7
1281207	Soil		18.9	33.0	11.3	223	0.4	43.7	6.7	114	1.98	16.6	2.6	2.2	41	1.5	3.1	0.2	97	0.54	0.097	9
1281208	Soil		23.3	38.8	12.0	232	0.5	46.1	8.0	216	2.23	19.2	2.7	2.9	44	1.5	3.8	0.2	103	0.53	0.104	11
1281209	Soil		26.1	44.5	10.8	334	0.4	100.1	8.4	316	2.00	18.3	3.8	1.8	63	2.8	3.4	0.2	71	0.82	0.104	7
1281210	Soil		19.1	37.9	11.8	258	0.3	56.6	9.4	176	2.31	18.1	2.4	2.5	37	1.7	3.5	0.2	82	0.32	0.091	10
1281261	Soil		6.7	12.9	8.5	67	0.3	13.2	1.7	32	0.76	8.7	1.2	0.4	8	0.2	2.4	0.2	103	0.01	0.025	19
1281262	Soil		14.6	27.2	13.4	164	0.6	37.9	3.6	72	2.12	23.5	3.1	0.7	16	0.3	5.7	0.3	210	0.03	0.176	15
1281263	Soil		14.5	26.1	8.9	159	1.6	35.8	3.1	46	1.66	17.3	1.2	1.7	10	0.3	5.1	0.2	178	0.03	0.113	16
1281264	Soil		20.8	54.6	15.1	315	3.2	65.1	6.0	116	2.87	33.2	3.0	1.5	30	1.1	10.3	0.3	277	0.10	0.265	18
1281265	Soil		20.9	97.5	17.6	575	1.6	101.3	13.6	331	3.58	37.1	4.8	2.8	62	4.8	11.9	0.3	321	0.25	0.341	21
1281266	Soil		8.4	44.0	10.7	217	1.1	32.9	3.6	72	1.99	18.5	3.3	0.4	21	1.1	6.1	0.2	123	0.05	0.126	10
1281267	Soil		6.6	24.1	7.3	77	0.4	16.6	2.9	41	1.15	7.6	1.2	0.1	14	0.2	2.0	0.1	68	0.03	0.073	7
1281268	Soil		1.2	5.3	3.1	17	0.2	3.2	0.8	14	0.33	1.7	<0.5	0.2	6	<0.1	0.5	<0.1	25	0.01	0.028	13
1281269	Soil		1.9	12.2	5.0	27	0.8	5.3	1.4	20	0.65	3.2	<0.5	0.1	7	0.2	0.6	0.1	27	0.01	0.075	7
1281270	Soil		16.7	61.6	11.9	562	0.5	90.7	9.0	218	2.50	15.0	6.7	0.6	51	3.5	5.4	0.2	126	0.55	0.119	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

CERTIFICATE OF ANALYSIS WHI11001221.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280761	Soil		18	0.13	451	0.004	2	0.84	0.003	0.06	0.1	0.10	2.2	0.3	<0.05	3	1.8	<0.2
1280762	Soil		21	0.16	1424	0.003	3	1.12	0.009	0.09	0.2	0.52	2.6	0.4	0.06	3	2.2	<0.2
1280763	Soil		20	0.14	921	0.002	3	0.98	0.005	0.08	0.2	0.38	3.2	0.4	<0.05	3	2.1	<0.2
1280764	Soil		17	0.11	403	0.003	2	0.99	0.005	0.07	0.1	0.16	1.8	0.3	<0.05	3	1.6	<0.2
1280765	Soil		16	0.12	1088	0.003	4	0.65	0.005	0.09	0.2	0.39	2.0	0.3	0.05	2	2.1	<0.2
1280766	Soil		17	0.14	1485	0.004	4	0.65	0.004	0.09	0.2	0.33	2.6	0.3	<0.05	2	2.2	<0.2
1280767	Soil		16	0.14	1055	0.003	2	0.64	0.004	0.07	0.1	0.28	2.3	0.3	<0.05	2	1.7	<0.2
1280768	Soil		18	0.14	1559	0.004	3	0.68	0.004	0.09	0.2	0.47	3.3	0.3	0.07	2	1.9	<0.2
1280769	Soil		20	0.17	1021	0.003	2	0.91	0.004	0.08	0.2	0.28	2.5	0.3	<0.05	3	1.9	<0.2
1280770	Soil		17	0.17	1020	0.003	2	0.81	0.006	0.07	<0.1	0.22	2.7	0.2	<0.05	2	1.7	<0.2
1281201	Soil		18	0.23	707	0.002	2	0.86	0.005	0.06	<0.1	0.15	2.8	0.2	0.06	3	0.9	<0.2
1281202	Soil		12	0.14	744	0.001	2	0.58	0.011	0.05	0.1	0.26	2.3	0.2	0.12	2	1.1	<0.2
1281203	Soil		12	0.14	596	<0.001	3	0.59	0.006	0.06	<0.1	0.40	2.4	0.4	0.13	2	3.2	<0.2
1281204	Soil		14	0.18	718	0.001	2	0.66	0.007	0.06	<0.1	0.42	2.4	0.4	0.22	2	2.9	<0.2
1281205	Soil		23	0.19	1745	0.003	4	1.04	0.004	0.10	0.1	0.42	3.2	0.4	<0.05	3	1.8	<0.2
1281206	Soil		16	0.16	1119	0.002	4	0.90	0.009	0.06	0.1	0.29	2.1	0.4	0.09	2	2.0	<0.2
1281207	Soil		18	0.19	1096	0.002	4	0.82	0.006	0.07	<0.1	0.30	2.7	0.3	<0.05	2	1.2	<0.2
1281208	Soil		20	0.21	1056	0.002	3	0.81	0.004	0.08	0.1	0.32	3.1	0.4	<0.05	2	1.7	<0.2
1281209	Soil		18	0.16	790	0.002	3	0.78	0.008	0.07	0.1	0.28	3.0	0.9	<0.05	2	1.9	<0.2
1281210	Soil		18	0.18	1117	0.003	2	0.78	0.005	0.07	0.1	0.28	2.9	0.3	<0.05	2	1.5	<0.2
1281261	Soil		13	0.03	142	0.007	2	0.43	0.003	0.05	0.1	0.02	0.5	0.3	<0.05	4	1.1	<0.2
1281262	Soil		25	0.04	361	0.004	3	0.57	0.004	0.07	0.1	0.06	0.7	0.4	<0.05	4	2.7	<0.2
1281263	Soil		20	0.04	224	0.004	2	0.52	0.004	0.06	0.2	0.05	1.0	0.3	<0.05	3	2.9	<0.2
1281264	Soil		34	0.06	1366	0.004	3	0.72	0.003	0.07	0.1	0.20	1.7	0.5	<0.05	3	5.4	<0.2
1281265	Soil		42	0.09	2298	0.004	5	0.73	0.002	0.11	0.1	0.25	3.4	0.6	0.05	2	5.0	<0.2
1281266	Soil		17	0.04	1419	0.004	2	0.42	0.010	0.06	0.1	0.10	1.0	0.3	<0.05	2	2.6	<0.2
1281267	Soil		15	0.04	238	0.002	3	0.44	0.011	0.07	<0.1	0.03	0.4	0.2	<0.05	3	1.3	<0.2
1281268	Soil		6	0.02	90	0.004	2	0.33	0.005	0.04	<0.1	<0.01	0.3	0.1	<0.05	3	<0.5	<0.2
1281269	Soil		8	0.02	208	0.003	3	0.44	0.007	0.05	<0.1	0.02	0.2	0.1	<0.05	3	<0.5	<0.2
1281270	Soil		26	0.20	1130	0.004	4	0.64	0.005	0.12	<0.1	0.25	2.0	0.5	0.09	2	3.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

CERTIFICATE OF ANALYSIS WHI11001221.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281271	Soil		1.6	5.3	2.3	18	<0.1	3.8	0.7	13	0.33	1.3	<0.5	<0.1	5	0.1	0.5	<0.1	22	0.02	0.055	5
1281272	Soil		9.7	31.0	8.1	133	0.3	31.8	4.2	109	1.50	7.0	1.1	0.3	23	1.5	3.2	0.2	65	0.17	0.208	11
1281273	Soil		2.4	50.4	7.0	75	0.8	34.0	5.0	82	1.09	1.8	10.6	0.7	66	2.5	1.2	0.1	34	0.90	0.141	7
1281274	Soil		7.0	37.6	10.0	119	<0.1	24.3	5.0	114	1.92	8.4	1.1	0.2	10	0.2	2.4	0.2	61	0.02	0.101	9
1281275	Soil		5.2	55.0	10.2	139	0.2	26.6	6.8	85	2.61	8.7	1.9	0.6	11	0.3	2.2	0.4	48	0.02	0.068	11
1281276	Soil		7.1	40.6	9.3	103	0.1	19.7	5.5	87	2.19	10.4	<0.5	0.2	12	0.2	2.4	0.2	64	0.01	0.092	13
1281277	Soil		5.7	85.9	12.4	147	0.8	33.9	8.5	94	3.63	28.1	3.3	0.3	8	0.7	4.1	0.3	91	0.01	0.099	14
1281278	Soil		3.9	41.7	7.8	108	0.2	14.7	6.1	175	2.14	7.8	1.1	0.3	8	0.4	2.8	0.2	49	0.01	0.125	12
1281279	Soil		4.1	86.1	25.4	141	0.2	25.2	21.0	623	4.83	12.6	7.3	1.7	33	0.3	2.7	0.3	39	0.04	0.153	14
1281280	Soil		3.6	73.7	15.3	108	0.3	20.3	7.3	131	3.06	10.2	8.8	0.5	15	0.4	1.9	0.3	39	0.08	0.203	7
1281281	Soil		4.9	73.9	8.3	109	0.2	33.2	7.8	91	2.77	17.3	8.4	0.3	6	0.2	3.2	0.3	75	0.02	0.053	13
1281282	Soil		4.6	62.0	7.9	337	0.4	69.5	10.8	218	2.77	12.0	4.4	0.3	11	0.9	2.6	0.3	66	0.07	0.096	8
1281283	Soil		2.4	57.9	7.8	129	<0.1	23.0	6.3	99	2.67	4.2	4.1	0.3	5	0.3	1.1	0.2	28	0.02	0.088	4
1281284	Soil		12.1	61.0	22.0	186	0.6	39.7	9.2	715	3.32	15.2	4.5	0.4	38	0.7	3.7	0.3	75	0.09	0.248	12
1281285	Soil		1.2	14.4	4.8	33	0.3	7.9	1.8	31	0.91	3.6	1.1	<0.1	7	0.1	0.6	0.1	16	0.03	0.061	2
1281286	Soil		1.1	6.1	2.6	29	0.2	4.6	1.9	744	0.38	1.1	<0.5	<0.1	14	0.3	0.3	<0.1	10	0.08	0.150	1
1281287	Soil		3.5	41.1	11.9	124	0.6	33.6	12.7	597	3.15	8.5	1.5	0.5	13	0.3	1.2	0.2	30	0.03	0.053	8
1281288	Soil		3.0	40.6	14.6	101	0.2	17.3	8.3	470	3.49	6.8	3.1	1.5	13	1.6	1.3	0.2	62	0.13	0.104	19
1281289	Soil		5.7	61.9	18.0	108	0.3	22.8	13.8	464	3.43	14.5	4.3	0.6	9	0.9	2.5	0.3	106	0.06	0.171	16
1281290	Soil		4.0	50.6	15.3	72	0.2	13.3	8.9	783	2.68	8.6	2.2	0.4	10	0.6	1.7	0.3	59	0.09	0.271	12
1281291	Soil		4.2	63.4	19.3	129	0.6	28.2	13.7	1124	3.86	11.9	6.6	1.0	22	0.8	2.0	0.2	81	0.48	0.214	26
1281292	Soil		15.6	217.4	51.8	317	1.5	62.6	35.6	1475	9.52	54.6	22.8	4.0	70	2.6	7.1	0.5	38	0.35	0.438	28
1281293	Soil		1.1	17.3	4.6	38	<0.1	4.9	2.3	160	0.77	2.9	2.3	<0.1	26	0.2	0.7	0.1	22	0.60	0.109	6
1281294	Soil		9.1	115.4	32.8	162	0.5	39.6	24.5	555	6.44	47.5	18.3	2.7	25	1.2	5.0	0.2	67	0.38	0.139	20
1281295	Soil		3.2	61.8	17.9	111	0.8	32.6	16.3	1600	2.88	10.9	26.4	1.5	61	1.2	1.4	0.2	40	1.62	0.241	31
1281296	Soil		1.2	47.2	9.9	52	0.4	16.5	8.2	747	1.63	6.2	10.1	0.4	72	0.5	1.1	0.1	22	2.55	0.144	19
1281297	Soil		6.5	66.7	13.9	166	0.9	47.9	16.1	636	4.47	24.6	6.4	1.8	40	1.5	2.9	0.2	76	1.14	0.161	27
1281298	Soil		7.1	54.6	12.6	137	0.8	51.6	14.4	679	4.78	25.4	6.7	2.3	30	0.8	2.1	0.1	77	0.73	0.173	30
1281299	Soil		4.2	43.7	10.1	105	0.4	27.7	10.0	475	3.13	15.7	4.8	1.3	19	0.5	1.7	0.2	56	0.31	0.179	18
1281300	Soil		7.4	112.2	27.2	164	1.1	57.1	20.1	2336	5.75	26.7	12.3	5.5	36	2.1	3.8	0.2	59	0.33	0.231	40

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

CERTIFICATE OF ANALYSIS WHI11001221.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281271	Soil		5	0.02	149	0.002	2	0.23	0.014	0.04	<0.1	0.01	0.2	<0.1	<0.05	1	<0.5	<0.2
1281272	Soil		14	0.06	1004	0.004	3	0.83	0.011	0.06	<0.1	0.06	0.6	0.2	0.14	2	2.2	<0.2
1281273	Soil		10	0.29	1212	0.006	4	0.87	0.013	0.09	<0.1	0.43	1.3	0.2	0.22	2	5.7	<0.2
1281274	Soil		11	0.04	185	0.005	4	0.39	0.009	0.09	<0.1	0.01	0.3	0.1	<0.05	2	1.3	<0.2
1281275	Soil		7	0.03	176	0.004	2	0.40	0.005	0.10	<0.1	0.02	0.4	0.2	0.07	2	1.4	<0.2
1281276	Soil		11	0.05	260	0.004	3	0.54	0.003	0.11	<0.1	0.02	0.3	0.2	<0.05	3	1.0	<0.2
1281277	Soil		17	0.05	287	0.004	3	0.53	0.003	0.12	0.1	0.07	0.8	0.2	0.05	4	1.7	<0.2
1281278	Soil		10	0.05	180	0.004	2	0.57	0.005	0.13	<0.1	0.02	0.4	0.2	0.05	3	0.9	<0.2
1281279	Soil		16	0.32	456	0.007	3	1.25	0.009	0.22	<0.1	0.06	2.7	0.3	0.17	4	1.8	<0.2
1281280	Soil		11	0.09	101	0.004	2	0.64	0.010	0.10	<0.1	0.06	0.6	0.2	0.07	3	1.6	<0.2
1281281	Soil		13	0.04	95	0.007	2	0.42	0.007	0.07	0.1	0.04	0.8	0.2	<0.05	4	1.3	<0.2
1281282	Soil		12	0.05	332	0.007	3	0.70	0.013	0.07	<0.1	0.18	1.1	0.2	<0.05	3	1.3	<0.2
1281283	Soil		8	0.06	70	0.004	3	0.61	0.013	0.08	<0.1	0.02	0.5	0.1	<0.05	3	0.8	<0.2
1281284	Soil		17	0.09	532	0.004	4	0.70	0.007	0.15	<0.1	0.08	0.5	0.3	0.20	3	2.4	<0.2
1281285	Soil		4	0.02	56	0.003	<1	0.25	0.020	0.04	<0.1	0.03	<0.1	<0.1	0.06	1	<0.5	<0.2
1281286	Soil		3	0.02	190	0.002	<1	0.26	0.024	0.03	<0.1	0.02	0.1	<0.1	0.06	1	<0.5	<0.2
1281287	Soil		11	0.14	439	0.013	2	0.87	0.011	0.07	0.1	0.05	1.3	0.1	0.06	3	0.9	<0.2
1281288	Soil		26	0.67	183	0.006	3	1.50	0.004	0.18	<0.1	0.05	1.8	0.2	0.05	6	0.8	<0.2
1281289	Soil		31	0.52	201	0.005	3	1.40	0.004	0.18	<0.1	0.11	1.2	0.2	0.08	7	1.2	<0.2
1281290	Soil		23	0.25	206	0.004	4	1.05	0.009	0.11	0.1	0.11	0.5	0.1	0.20	4	1.0	<0.2
1281291	Soil		28	0.73	315	0.004	5	1.47	0.005	0.12	<0.1	0.20	2.2	0.2	0.09	5	2.2	<0.2
1281292	Soil		15	0.34	428	0.004	2	1.21	0.003	0.14	<0.1	0.43	6.6	0.5	0.09	3	7.5	0.3
1281293	Soil		7	0.11	104	0.002	2	0.47	0.016	0.06	<0.1	0.01	0.2	<0.1	0.08	3	0.6	<0.2
1281294	Soil		29	0.94	268	0.006	2	1.70	0.004	0.08	0.1	0.23	3.4	0.3	<0.05	5	3.4	<0.2
1281295	Soil		27	0.76	226	0.004	4	1.21	0.004	0.07	<0.1	0.33	4.7	0.1	0.12	3	1.1	<0.2
1281296	Soil		13	0.40	258	0.004	6	0.69	0.007	0.06	<0.1	0.19	1.7	<0.1	0.18	2	1.5	<0.2
1281297	Soil		33	0.59	356	0.005	5	1.26	0.007	0.12	<0.1	0.33	6.5	0.2	0.07	4	1.7	<0.2
1281298	Soil		37	0.65	334	0.005	5	1.47	0.007	0.11	<0.1	0.29	7.1	0.2	0.05	4	1.5	<0.2
1281299	Soil		26	0.42	270	0.005	2	1.28	0.008	0.08	<0.1	0.11	2.6	0.1	0.06	4	1.3	<0.2
1281300	Soil		28	0.95	457	0.009	3	1.83	0.004	0.12	<0.1	0.19	5.1	0.3	<0.05	4	2.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

CERTIFICATE OF ANALYSIS WHI11001221.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281341	Soil		4.0	121.2	26.3	192	1.4	26.6	22.1	834	5.35	12.5	4.5	1.6	14	15.5	2.4	0.3	77	0.06	0.293	19
1281342	Soil		5.1	61.6	18.9	129	0.5	17.9	7.9	164	4.56	12.4	3.8	0.6	13	0.7	2.7	0.4	80	0.02	0.162	18
1281343	Soil		5.8	68.1	51.8	251	0.2	125.3	62.8	3699	8.20	6.1	13.2	4.9	12	0.3	2.2	0.3	20	0.32	0.045	23
1281344	Soil		10.0	86.3	25.8	186	0.8	64.9	11.2	336	4.08	23.3	3.7	4.7	55	0.7	4.0	0.4	35	0.17	0.060	18
1281345	Soil		15.9	94.2	13.0	115	2.8	41.3	2.2	65	1.39	21.0	2.0	2.7	112	1.6	9.5	0.2	143	0.15	0.059	19
1281346	Soil		4.6	68.1	8.6	95	0.4	19.1	5.2	81	1.96	11.9	9.8	0.2	7	0.2	2.0	0.2	68	0.03	0.084	10
1281347	Soil		11.7	137.1	33.8	183	0.6	33.9	13.8	395	5.82	21.8	13.7	1.2	57	1.5	6.2	0.4	78	0.10	0.215	15
1281348	Soil		8.3	79.7	21.0	121	0.5	55.2	15.6	694	5.09	11.1	12.2	2.5	39	0.3	1.8	0.3	35	0.53	0.125	22
1281349	Soil		4.6	214.8	37.5	232	0.5	63.6	20.1	461	6.72	57.5	19.9	1.9	17	0.3	5.5	0.6	50	0.02	0.114	10
1281350	Soil		9.2	445.5	59.6	318	4.4	88.7	22.6	454	7.81	28.2	63.5	1.7	41	1.1	3.8	0.4	34	0.21	0.205	8
1281351	Soil		5.7	64.3	17.8	153	0.3	27.5	13.7	533	3.89	15.0	5.7	1.1	19	0.9	2.6	0.3	77	0.11	0.185	17
1281352	Soil		4.5	54.1	14.2	133	0.2	23.1	12.0	386	2.89	11.1	8.3	2.0	13	0.9	2.5	0.2	47	0.10	0.146	18
1281353	Soil		5.0	48.7	16.2	130	0.2	16.7	10.4	631	3.31	12.7	4.3	0.3	30	0.7	2.3	0.3	77	0.53	0.150	13
1281354	Soil		1.7	16.4	4.7	31	0.1	6.0	3.1	187	0.91	3.8	0.8	<0.1	6	0.1	0.7	<0.1	26	0.02	0.092	4
1281355	Soil		2.7	29.9	12.6	64	0.1	11.9	7.6	737	2.55	9.6	1.3	0.2	10	0.2	1.3	0.2	56	0.05	0.170	8
1281356	Soil		9.1	116.9	20.8	220	0.9	47.8	16.8	438	4.00	15.5	15.5	4.7	43	1.7	3.6	0.2	83	0.39	0.172	35
1281357	Soil		2.7	50.2	9.3	118	0.7	28.4	10.5	402	2.77	7.8	10.5	2.3	38	0.6	1.2	0.1	59	0.69	0.148	24
1281358	Soil		3.2	67.6	16.1	141	0.3	34.0	13.7	444	2.95	8.7	10.3	3.6	43	0.8	1.4	0.2	79	0.46	0.148	25
1281359	Soil		11.9	92.6	24.2	163	2.4	40.5	4.9	353	2.66	23.8	8.2	1.5	180	4.7	6.0	0.2	196	0.91	0.369	15
1281360	Soil		3.0	82.9	16.6	173	1.3	34.7	5.7	188	1.83	9.4	11.9	1.5	118	1.4	2.1	0.2	80	1.66	0.226	15
1281361	Soil		0.5	27.9	2.7	42	0.4	9.1	1.6	145	0.44	1.4	2.2	0.3	56	1.0	0.6	<0.1	12	1.16	0.111	4
1281362	Soil		3.5	23.8	5.2	71	<0.1	11.2	2.5	47	0.84	6.0	1.3	0.2	5	0.2	1.3	0.1	49	0.03	0.057	9
1281363	Soil		3.8	71.7	12.0	211	1.3	37.2	10.7	454	2.30	10.6	10.5	2.1	44	1.9	1.6	0.2	69	0.30	0.189	22
1281364	Soil		1.0	16.2	5.6	29	0.9	9.5	4.0	187	0.61	1.6	5.9	0.1	19	0.2	0.2	<0.1	19	0.18	0.083	5
1281365	Soil		8.3	81.8	18.7	180	0.9	63.0	11.9	372	2.95	13.2	10.8	2.4	97	1.2	2.5	0.3	58	0.56	0.116	17
1281366	Soil		2.6	55.1	11.8	157	0.6	31.5	9.5	1404	2.14	8.5	6.0	2.1	57	0.9	1.5	0.2	47	1.05	0.123	14
1281367	Soil		4.5	41.2	17.4	211	1.1	33.5	5.9	323	2.18	11.3	7.2	1.2	65	2.2	1.7	0.3	65	0.37	0.203	14
1281368	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281369	Soil		6.0	56.7	19.6	127	0.9	33.7	7.0	381	2.27	13.7	7.1	1.3	98	1.5	2.8	0.3	59	1.07	0.174	13
1281370	Soil		4.8	75.2	15.5	203	0.8	43.7	11.4	603	2.65	13.6	10.2	1.8	71	2.1	2.5	0.2	44	1.35	0.174	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

CERTIFICATE OF ANALYSIS WHI11001221.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281341	Soil		40	0.34	954	0.008	2	1.91	0.004	0.10	<0.1	0.13	1.5	0.2	0.10	7	2.5	<0.2
1281342	Soil		25	0.16	293	0.007	2	1.16	0.003	0.11	<0.1	0.07	0.7	0.2	0.06	7	1.7	<0.2
1281343	Soil		13	0.37	997	0.003	4	1.34	0.003	0.14	<0.1	0.08	7.1	0.2	<0.05	3	0.9	<0.2
1281344	Soil		17	0.25	1474	0.002	4	0.94	0.003	0.19	<0.1	0.51	4.6	0.2	0.16	3	2.7	0.2
1281345	Soil		16	0.05	578	0.002	2	0.37	0.002	0.12	<0.1	0.72	2.6	0.4	0.14	2	5.9	<0.2
1281346	Soil		14	0.05	222	0.005	4	0.48	0.005	0.10	0.1	0.08	0.7	0.1	0.08	4	1.1	<0.2
1281347	Soil		34	0.44	618	0.006	5	1.51	0.004	0.23	<0.1	0.19	1.5	0.4	0.20	6	5.5	0.2
1281348	Soil		24	0.44	2488	0.006	5	1.21	0.004	0.14	<0.1	0.44	4.2	0.2	0.12	3	1.4	<0.2
1281349	Soil		21	0.12	181	0.009	2	0.84	0.005	0.11	<0.1	0.11	4.7	0.3	0.07	4	3.3	0.3
1281350	Soil		17	0.23	884	0.004	4	1.06	0.002	0.18	<0.1	1.46	5.2	0.4	0.06	2	12.9	0.3
1281351	Soil		30	0.52	275	0.008	4	1.27	0.005	0.13	<0.1	0.06	1.6	0.2	0.06	6	1.3	<0.2
1281352	Soil		21	0.36	237	0.003	3	1.10	0.005	0.12	<0.1	0.11	2.4	0.2	0.05	4	1.1	<0.2
1281353	Soil		21	0.24	237	0.007	2	0.85	0.007	0.11	<0.1	0.03	0.5	0.2	0.05	6	1.1	<0.2
1281354	Soil		9	0.06	52	0.003	1	0.41	0.018	0.04	<0.1	0.03	0.1	<0.1	<0.05	2	0.6	<0.2
1281355	Soil		22	0.13	143	0.006	2	0.70	0.009	0.07	<0.1	0.05	0.5	<0.1	0.06	4	0.5	<0.2
1281356	Soil		33	1.17	401	0.005	4	1.95	0.004	0.21	<0.1	0.28	5.0	0.3	<0.05	6	2.3	<0.2
1281357	Soil		31	0.75	296	0.007	5	1.51	0.008	0.16	<0.1	0.21	4.7	0.1	0.06	5	1.4	<0.2
1281358	Soil		33	1.10	334	0.006	6	1.90	0.005	0.22	<0.1	0.21	4.6	0.2	0.07	6	1.2	<0.2
1281359	Soil		40	0.24	584	0.004	5	0.75	0.010	0.24	<0.1	0.60	2.5	0.4	0.49	3	7.4	<0.2
1281360	Soil		26	0.56	508	0.006	7	1.12	0.007	0.17	<0.1	0.53	2.5	0.2	0.16	3	3.2	<0.2
1281361	Soil		8	0.10	543	0.008	2	0.44	0.023	0.04	<0.1	0.13	0.7	<0.1	0.13	1	0.7	<0.2
1281362	Soil		10	0.05	85	0.004	3	0.39	0.009	0.09	<0.1	0.04	0.3	0.1	<0.05	3	0.6	<0.2
1281363	Soil		25	0.43	589	0.004	6	1.66	0.006	0.13	<0.1	0.38	3.4	0.2	0.11	4	1.8	<0.2
1281364	Soil		9	0.14	263	0.006	2	0.53	0.023	0.06	<0.1	0.20	0.7	0.1	0.07	2	<0.5	<0.2
1281365	Soil		28	0.59	671	0.008	6	1.35	0.008	0.19	<0.1	0.35	3.5	0.2	0.12	4	2.2	<0.2
1281366	Soil		20	0.42	818	0.005	3	1.23	0.009	0.09	<0.1	0.23	2.8	0.1	0.08	3	1.7	<0.2
1281367	Soil		21	0.28	620	0.004	4	1.05	0.007	0.08	0.1	0.47	1.7	0.2	0.08	3	2.1	<0.2
1281368	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281369	Soil		20	0.34	694	0.005	4	0.91	0.007	0.10	0.2	0.24	1.6	0.2	0.10	3	2.3	<0.2
1281370	Soil		21	0.52	446	0.008	6	1.00	0.009	0.10	0.2	0.21	2.4	0.2	0.08	3	1.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

CERTIFICATE OF ANALYSIS WHI11001221.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281451	Soil	13.5	88.8	31.9	173	1.5	41.9	6.5	315	2.78	20.8	6.3	0.5	105	1.3	5.0	0.4	80	0.21	0.201	13
1281452	Soil	24.4	150.4	27.0	370	1.0	78.6	14.0	500	4.31	28.8	9.9	1.2	52	3.6	11.4	0.4	94	0.16	0.124	15
1281453	Soil	19.8	219.5	13.6	781	5.3	219.1	4.9	166	2.31	34.3	6.3	5.4	107	6.4	12.2	0.3	248	1.01	0.300	23
1281454	Soil	17.2	151.1	43.3	235	2.0	72.9	17.9	654	5.30	38.1	13.2	1.4	89	1.0	6.6	0.5	55	0.08	0.128	13
1281455	Soil	12.9	159.8	33.8	236	1.6	67.6	17.6	567	5.30	35.4	12.9	1.6	73	1.4	5.9	0.5	53	0.09	0.145	11
1281456	Soil	3.4	182.8	12.3	183	0.5	41.1	12.9	322	4.46	20.7	12.7	0.7	12	0.7	2.3	0.3	21	0.06	0.153	6
1281457	Soil	4.6	196.1	15.8	218	0.7	47.7	15.0	538	4.52	18.4	19.4	0.6	18	0.6	2.6	0.3	28	0.09	0.141	6
1281458	Soil	14.5	163.2	28.6	255	0.6	62.8	20.3	402	5.62	17.4	12.3	2.6	43	1.4	3.4	0.3	32	0.35	0.184	16
1281459	Soil	3.8	84.7	18.1	125	0.3	23.4	10.7	707	4.43	7.7	7.0	2.6	23	0.5	1.9	0.2	75	0.32	0.284	21
1281460	Soil	15.5	125.9	29.6	224	0.8	31.3	15.6	486	4.39	24.5	17.4	1.9	33	0.8	8.3	0.3	106	0.10	0.223	23
1281461	Soil	8.0	92.4	28.7	148	1.7	38.6	10.6	384	3.13	13.8	23.8	2.6	79	1.8	4.0	0.2	44	1.37	0.205	31
1281462	Soil	5.1	164.1	47.7	201	1.4	44.5	13.1	300	3.63	8.0	28.1	3.0	64	1.0	2.7	0.3	31	0.97	0.184	19
1281463	Soil	27.4	144.4	23.1	113	3.4	32.4	2.7	93	1.90	27.9	5.0	1.0	194	2.8	12.9	0.3	106	0.24	0.095	19
1281464	Soil	16.0	116.0	47.3	196	2.5	62.3	11.9	796	4.15	28.4	7.9	1.4	214	2.0	6.8	0.5	83	0.38	0.279	19
1281465	Soil	11.5	90.4	17.5	155	0.8	58.2	15.0	396	3.40	10.7	10.5	1.3	34	1.2	2.5	0.4	20	0.22	0.125	9
1281466	Soil	3.0	59.5	14.5	122	0.5	41.3	14.1	404	2.92	7.6	4.2	0.9	17	0.3	1.4	0.2	19	0.12	0.055	5
1281467	Soil	116.6	112.2	12.1	1682	0.6	295.1	9.7	174	2.23	54.2	2.1	6.7	72	16.9	26.6	0.2	391	2.07	0.096	35
1281468	Soil	80.9	176.6	12.5	1646	1.7	211.9	6.4	71	2.30	73.6	3.4	3.0	49	21.2	39.2	0.2	403	0.65	0.120	34
1281469	Soil	13.0	35.2	10.2	188	0.2	40.6	6.0	149	2.35	15.6	1.8	0.2	12	0.7	4.1	0.3	77	0.04	0.122	11
1281470	Soil	7.6	79.4	18.4	213	0.1	60.0	13.5	147	3.91	14.2	3.0	0.3	18	0.4	2.6	0.3	29	0.17	0.086	6
1281471	Soil	7.3	41.6	17.4	116	0.2	38.7	9.9	195	2.45	9.5	3.6	0.3	10	0.3	2.0	0.2	24	0.06	0.062	4
1281472	Soil	20.1	77.6	59.8	151	0.5	79.2	23.4	1298	5.43	20.9	5.7	1.3	13	0.7	3.4	0.4	25	0.03	0.069	8
1281473	Soil	4.1	114.8	25.4	166	1.0	75.2	25.6	629	7.48	26.3	11.1	1.6	7	0.5	3.1	0.5	26	0.03	0.056	4
1281474	Soil	3.1	42.5	13.1	93	0.2	22.2	6.5	210	4.65	8.5	4.5	0.5	6	0.2	1.9	0.3	29	0.01	0.055	4
1281475	Soil	5.1	59.6	12.8	107	0.4	32.8	9.5	310	3.70	11.5	8.6	0.3	6	0.3	2.4	0.3	32	0.02	0.066	4
1281476	Soil	2.9	21.0	7.5	43	0.2	11.4	3.3	54	1.49	6.9	1.8	0.2	6	<0.1	1.3	0.2	31	0.02	0.074	4
1281477	Soil	33.3	111.9	23.0	565	5.4	136.0	8.0	274	2.75	41.8	4.7	0.5	60	3.8	14.7	0.3	254	0.33	0.247	21
1281478	Soil	7.5	55.6	40.8	151	0.7	28.8	13.2	584	2.75	14.5	3.6	2.8	47	0.5	4.2	0.4	64	0.05	0.102	9
1281479	Soil	14.7	103.4	31.4	64	2.0	17.6	0.9	28	1.30	9.9	6.7	2.5	68	1.8	8.4	0.3	116	0.02	0.159	6
1281480	Soil	3.8	40.3	33.5	137	0.4	18.4	11.7	475	2.56	9.3	3.1	0.9	45	0.3	2.0	0.3	27	0.02	0.067	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

CERTIFICATE OF ANALYSIS WHI11001221.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281451	Soil	16	0.06	947	0.003	3	0.60	0.010	0.10	<0.1	0.53	1.2	0.2	0.15	2	4.5	0.2
1281452	Soil	11	0.07	1830	0.003	3	0.53	0.005	0.09	<0.1	0.71	2.9	0.4	0.08	1	4.7	0.2
1281453	Soil	82	0.10	2225	0.003	6	0.38	0.003	0.09	0.2	1.92	3.6	0.2	<0.05	1	9.4	0.2
1281454	Soil	11	0.05	1087	0.002	3	0.52	0.003	0.13	<0.1	0.49	4.2	0.5	0.15	2	4.5	<0.2
1281455	Soil	13	0.09	1112	0.002	3	0.69	0.003	0.13	<0.1	0.35	4.2	0.4	0.18	2	4.0	0.3
1281456	Soil	7	0.08	208	0.002	3	0.52	0.007	0.11	<0.1	0.12	3.0	0.1	<0.05	2	2.3	0.2
1281457	Soil	8	0.11	178	0.006	2	0.59	0.014	0.10	<0.1	0.15	2.8	0.2	<0.05	3	2.7	<0.2
1281458	Soil	16	0.15	578	0.003	4	0.57	0.005	0.17	<0.1	0.31	3.8	0.4	<0.05	2	3.8	<0.2
1281459	Soil	30	0.59	841	0.006	3	1.53	0.004	0.11	0.1	0.11	2.9	0.2	0.13	6	1.1	<0.2
1281460	Soil	30	0.59	544	0.004	4	1.41	0.005	0.20	<0.1	0.43	1.8	0.5	0.15	6	5.8	<0.2
1281461	Soil	27	0.71	575	0.006	9	1.02	0.007	0.21	0.1	0.52	4.3	0.3	0.20	3	3.9	<0.2
1281462	Soil	15	0.38	915	0.003	6	0.73	0.004	0.13	<0.1	0.57	4.9	0.2	0.10	2	3.7	<0.2
1281463	Soil	13	0.04	592	0.002	3	0.36	0.005	0.17	<0.1	0.67	1.8	0.7	0.30	1	8.3	0.2
1281464	Soil	18	0.05	593	0.004	5	0.66	0.005	0.24	<0.1	0.74	3.2	0.4	0.36	2	5.6	0.3
1281465	Soil	8	0.08	1530	0.002	3	0.53	0.003	0.09	<0.1	0.27	3.4	0.2	0.06	1	1.6	<0.2
1281466	Soil	7	0.06	1208	0.004	4	0.56	0.012	0.09	<0.1	0.08	2.6	0.2	<0.05	2	1.4	<0.2
1281467	Soil	16	0.98	535	0.003	6	0.25	0.004	0.08	0.3	1.94	4.2	1.6	<0.05	1	9.0	<0.2
1281468	Soil	27	0.08	988	0.003	6	0.36	0.002	0.08	0.3	2.85	3.6	1.0	<0.05	2	15.6	0.3
1281469	Soil	18	0.06	276	0.003	3	0.66	0.003	0.07	0.1	0.12	0.5	0.3	<0.05	3	2.1	<0.2
1281470	Soil	11	0.06	565	0.003	3	0.51	0.006	0.08	<0.1	0.13	2.5	0.2	<0.05	2	2.6	<0.2
1281471	Soil	7	0.05	772	0.006	2	0.56	0.013	0.06	<0.1	0.11	1.8	0.2	<0.05	2	1.6	<0.2
1281472	Soil	7	0.04	1761	0.002	3	0.52	0.002	0.10	<0.1	0.22	4.3	0.3	<0.05	1	3.0	<0.2
1281473	Soil	13	0.13	1580	0.003	3	0.76	0.005	0.07	<0.1	0.22	9.0	0.3	<0.05	3	2.0	<0.2
1281474	Soil	10	0.03	265	0.002	2	0.43	0.003	0.06	<0.1	0.07	2.1	0.1	<0.05	1	1.3	<0.2
1281475	Soil	13	0.04	785	0.003	3	0.60	0.006	0.07	<0.1	0.15	2.2	0.1	<0.05	2	1.2	<0.2
1281476	Soil	8	0.03	443	0.004	2	0.72	0.011	0.04	<0.1	0.05	0.6	0.1	<0.05	3	0.9	<0.2
1281477	Soil	65	0.11	804	0.004	3	0.76	0.005	0.11	0.2	1.00	1.1	1.0	0.09	3	10.5	0.2
1281478	Soil	18	0.16	623	0.007	3	0.78	0.007	0.13	0.1	0.08	3.0	0.8	0.11	3	4.8	<0.2
1281479	Soil	27	0.01	1518	0.002	5	0.35	0.002	0.11	0.3	1.58	2.9	1.5	0.15	2	14.8	1.3
1281480	Soil	8	0.04	435	0.004	4	0.50	0.010	0.13	<0.1	0.05	2.8	0.4	0.15	2	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

CERTIFICATE OF ANALYSIS WHI11001221.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281481	Soil	30.3	113.5	21.4	173	1.6	27.3	1.8	29	1.76	23.3	3.4	2.0	125	0.4	10.4	0.3	83	0.03	0.203	4
1281482	Soil	3.7	52.6	43.1	154	0.6	22.3	11.1	412	3.43	14.4	3.5	2.4	66	0.7	2.6	0.5	28	0.01	0.079	3
1281483	Soil	3.2	48.6	37.7	127	0.4	23.7	30.2	1720	2.77	10.8	1.9	1.4	14	0.2	1.9	0.4	28	0.03	0.081	5
1281484	Soil	4.0	65.4	41.1	278	0.5	53.3	30.0	1390	3.67	12.1	2.7	1.9	9	0.3	2.9	0.4	26	0.02	0.074	4
1281485	Soil	2.7	20.2	17.3	110	0.4	18.7	5.8	105	3.56	22.0	0.5	1.6	24	0.3	1.3	0.2	57	0.03	0.094	6
1281486	Soil	1.5	7.4	7.4	22	0.3	10.2	1.4	41	0.80	4.4	1.3	0.2	8	<0.1	0.2	0.1	23	0.03	0.038	2
1281487	Soil	1.1	16.5	7.5	21	0.5	7.0	1.1	21	0.58	2.8	0.5	0.4	9	0.1	0.2	0.1	24	0.03	0.033	4
1281488	Soil	1.2	12.1	7.3	25	0.5	6.6	1.7	30	0.71	6.2	0.6	0.2	9	<0.1	0.4	0.1	23	0.03	0.036	4
1281489	Soil	1.6	17.5	12.5	55	0.5	14.1	3.8	59	1.85	12.7	<0.5	0.7	16	0.1	0.6	0.2	37	0.02	0.056	3
1281490	Soil	1.9	30.3	18.0	105	0.4	26.8	7.9	185	3.02	17.1	2.9	1.5	25	0.1	0.7	0.2	45	0.03	0.064	4
1281491	Soil	1.2	17.2	10.1	35	0.6	10.6	2.8	67	1.04	5.8	2.1	0.6	11	0.1	0.4	0.1	24	0.02	0.036	2
1281492	Soil	1.3	26.1	22.0	118	0.4	35.7	15.2	437	2.90	12.6	4.9	1.6	30	0.1	0.4	0.3	43	0.09	0.064	3
1281493	Soil	1.9	30.6	22.0	103	0.6	27.5	64.3	1887	3.22	16.2	3.5	1.8	25	0.2	0.6	0.3	43	0.04	0.074	5
1281494	Soil	2.9	26.5	14.5	95	0.5	25.4	5.8	116	2.08	12.5	2.8	1.0	21	0.4	0.8	0.2	39	0.06	0.060	3
1281495	Soil	2.8	35.4	17.7	99	0.4	26.8	7.5	120	2.68	17.2	2.0	1.4	22	0.3	1.1	0.2	46	0.05	0.072	5
1281496	Soil	2.0	28.0	16.6	100	0.2	28.7	7.4	133	2.54	16.0	2.5	1.6	29	0.2	0.8	0.2	40	0.07	0.059	5
1281497	Soil	1.7	31.2	18.0	132	0.2	29.8	9.5	147	3.15	15.9	1.9	2.1	31	<0.1	0.6	0.2	38	0.07	0.051	4
1281498	Soil	4.9	23.1	11.8	127	0.3	29.0	8.3	171	2.31	15.1	1.0	1.8	39	0.5	1.8	0.2	38	0.15	0.062	6
1281499	Soil	4.4	17.1	13.7	57	0.4	16.7	4.4	133	1.65	13.3	2.6	0.8	61	0.7	1.6	0.2	33	0.23	0.052	3
1281500	Soil	7.3	28.5	14.4	125	0.3	29.0	5.9	71	2.20	17.9	2.3	1.6	70	1.0	2.4	0.2	47	0.15	0.058	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

CERTIFICATE OF ANALYSIS WHI11001221.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281481	Soil	11	0.01	541	0.001	3	0.58	0.003	0.11	0.3	0.59	3.6	3.4	0.21	2	7.7	<0.2
1281482	Soil	9	0.04	463	0.002	5	0.44	0.004	0.21	<0.1	0.10	3.8	0.6	0.31	2	2.2	<0.2
1281483	Soil	10	0.10	274	0.006	3	0.78	0.011	0.11	<0.1	0.08	2.6	0.4	<0.05	3	1.1	<0.2
1281484	Soil	10	0.06	381	0.004	2	0.67	0.004	0.12	<0.1	0.07	3.5	0.3	<0.05	2	0.8	<0.2
1281485	Soil	22	0.13	338	0.005	2	1.18	0.008	0.08	<0.1	0.04	2.2	0.1	<0.05	4	<0.5	0.3
1281486	Soil	16	0.03	151	0.003	<1	0.39	0.019	0.05	<0.1	0.03	0.6	<0.1	<0.05	2	<0.5	<0.2
1281487	Soil	11	0.02	202	0.002	2	0.54	0.012	0.05	<0.1	0.02	0.6	<0.1	<0.05	3	<0.5	<0.2
1281488	Soil	9	0.03	135	0.003	<1	0.41	0.015	0.04	<0.1	0.02	0.6	<0.1	<0.05	2	<0.5	<0.2
1281489	Soil	16	0.08	225	0.002	2	0.69	0.013	0.07	<0.1	0.05	1.6	<0.1	<0.05	3	0.8	<0.2
1281490	Soil	25	0.17	433	0.003	2	1.11	0.008	0.09	<0.1	0.06	3.1	0.1	<0.05	3	1.5	<0.2
1281491	Soil	13	0.06	269	0.002	2	0.82	0.024	0.06	<0.1	0.08	1.5	0.1	<0.05	3	0.9	<0.2
1281492	Soil	32	0.22	684	<0.001	2	1.29	0.009	0.09	<0.1	0.09	3.1	0.1	<0.05	4	1.7	<0.2
1281493	Soil	24	0.21	609	0.001	2	1.28	0.008	0.09	<0.1	0.11	3.6	0.1	<0.05	4	1.5	<0.2
1281494	Soil	19	0.14	467	0.001	2	0.96	0.016	0.07	<0.1	0.12	2.5	0.1	<0.05	3	0.6	<0.2
1281495	Soil	22	0.15	634	0.003	2	1.08	0.010	0.08	<0.1	0.09	2.8	0.2	<0.05	3	1.6	<0.2
1281496	Soil	26	0.19	560	0.001	<1	1.04	0.007	0.08	<0.1	0.09	2.8	0.1	<0.05	3	1.4	<0.2
1281497	Soil	24	0.22	417	0.004	2	1.09	0.005	0.08	<0.1	0.09	3.5	<0.1	<0.05	3	1.0	<0.2
1281498	Soil	15	0.16	1432	0.002	<1	0.72	0.004	0.06	<0.1	0.07	2.0	0.1	<0.05	2	0.6	<0.2
1281499	Soil	12	0.09	1646	<0.001	2	0.65	0.010	0.07	<0.1	0.14	1.8	0.2	<0.05	2	1.3	<0.2
1281500	Soil	16	0.11	2080	<0.001	2	0.68	0.005	0.09	<0.1	0.16	2.3	0.2	<0.05	2	1.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

QUALITY CONTROL REPORT WHI11001221.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1280739	Soil	16.1	48.5	19.1	271	0.6	60.0	8.5	264	2.42	26.0	4.9	2.3	28	2.9	4.9	0.8	130	0.13	0.085	12
REP 1280739	QC	16.5	50.2	19.3	276	0.6	60.7	8.7	273	2.51	26.7	7.4	2.3	29	3.4	5.8	1.0	149	0.15	0.087	14
1281204	Soil	1.6	31.5	21.6	89	0.7	27.2	3.8	40	1.01	3.5	3.1	2.0	40	1.4	1.1	0.2	48	0.66	0.050	4
REP 1281204	QC	1.5	30.8	21.3	89	0.7	26.4	3.7	38	0.96	3.1	4.1	2.0	41	1.3	1.2	0.2	50	0.65	0.050	4
1281208	Soil	23.3	38.8	12.0	232	0.5	46.1	8.0	216	2.23	19.2	2.7	2.9	44	1.5	3.8	0.2	103	0.53	0.104	11
REP 1281208	QC	23.1	38.9	11.6	231	0.5	45.6	8.2	221	2.21	19.1	2.6	2.8	44	1.4	3.7	0.2	107	0.54	0.105	11
1281290	Soil	4.0	50.6	15.3	72	0.2	13.3	8.9	783	2.68	8.6	2.2	0.4	10	0.6	1.7	0.3	59	0.09	0.271	12
REP 1281290	QC	3.9	51.0	15.0	74	0.2	13.5	8.9	715	2.59	7.8	2.3	0.6	11	0.6	1.6	0.3	57	0.10	0.261	11
1281295	Soil	3.2	61.8	17.9	111	0.8	32.6	16.3	1600	2.88	10.9	26.4	1.5	61	1.2	1.4	0.2	40	1.62	0.241	31
REP 1281295	QC	3.3	60.7	18.1	114	0.8	33.1	16.9	1665	2.89	11.0	25.7	1.4	59	1.2	1.6	0.2	42	1.61	0.236	32
1281349	Soil	4.6	214.8	37.5	232	0.5	63.6	20.1	461	6.72	57.5	19.9	1.9	17	0.3	5.5	0.6	50	0.02	0.114	10
REP 1281349	QC	4.5	218.3	37.6	231	0.5	64.2	20.7	461	6.77	57.5	20.1	2.1	18	0.5	5.4	0.5	50	0.02	0.115	10
1281456	Soil	3.4	182.8	12.3	183	0.5	41.1	12.9	322	4.46	20.7	12.7	0.7	12	0.7	2.3	0.3	21	0.06	0.153	6
REP 1281456	QC	3.4	186.3	12.3	184	0.4	41.6	13.3	322	4.50	20.7	13.4	0.7	12	0.8	2.2	0.3	22	0.06	0.151	6
1281477	Soil	33.3	111.9	23.0	565	5.4	136.0	8.0	274	2.75	41.8	4.7	0.5	60	3.8	14.7	0.3	254	0.33	0.247	21
REP 1281477	QC	33.8	111.2	22.3	558	5.6	134.3	8.2	270	2.78	40.5	4.7	0.6	59	4.2	15.2	0.3	236	0.32	0.231	21
1281485	Soil	2.7	20.2	17.3	110	0.4	18.7	5.8	105	3.56	22.0	0.5	1.6	24	0.3	1.3	0.2	57	0.03	0.094	6
REP 1281485	QC	2.7	20.9	17.5	109	0.4	21.6	5.9	111	3.61	22.9	1.3	1.5	25	0.2	1.5	0.2	57	0.03	0.093	6
Reference Materials																					
STD DS8	Standard	13.1	114.8	131.4	326	1.9	37.6	7.3	619	2.50	25.8	123.1	7.1	67	2.5	5.6	7.3	41	0.68	0.080	15
STD DS8	Standard	13.6	110.3	130.4	313	1.8	38.2	7.6	620	2.47	25.6	104.4	7.3	69	2.6	5.7	6.9	42	0.69	0.081	16
STD DS8	Standard	13.3	112.7	118.8	318	1.7	37.7	7.6	624	2.49	25.6	123.4	6.5	73	2.4	5.4	6.5	43	0.72	0.078	16
STD DS8	Standard	11.4	94.5	117.0	301	1.7	33.6	6.6	561	2.25	22.1	109.3	5.9	62	1.9	5.1	5.7	38	0.62	0.073	13
STD DS8	Standard	14.0	114.0	127.3	309	1.8	40.6	7.8	642	2.51	24.2	125.7	6.8	67	2.3	5.4	6.3	45	0.71	0.075	16
STD DS8	Standard	13.7	116.4	127.2	304	1.7	38.0	7.2	603	2.41	23.1	103.3	6.5	66	2.2	5.5	6.1	44	0.68	0.080	17
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

QUALITY CONTROL REPORT WHI11001221.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1280739	Soil		22	0.13	714	0.004	4	0.90	0.005	0.07	0.2	0.39	2.9	0.6	0.12	3	2.0	<0.2
REP 1280739	QC		22	0.14	785	0.007	7	0.98	0.006	0.09	0.3	0.37	3.4	0.7	<0.05	4	2.3	<0.2
1281204	Soil		14	0.18	718	0.001	2	0.66	0.007	0.06	<0.1	0.42	2.4	0.4	0.22	2	2.9	<0.2
REP 1281204	QC		13	0.17	728	0.001	3	0.70	0.007	0.06	<0.1	0.41	2.6	0.4	0.21	2	2.7	<0.2
1281208	Soil		20	0.21	1056	0.002	3	0.81	0.004	0.08	0.1	0.32	3.1	0.4	<0.05	2	1.7	<0.2
REP 1281208	QC		20	0.22	1090	0.002	3	0.81	0.004	0.08	0.1	0.35	3.1	0.3	<0.05	2	1.6	<0.2
1281290	Soil		23	0.25	206	0.004	4	1.05	0.009	0.11	0.1	0.11	0.5	0.1	0.20	4	1.0	<0.2
REP 1281290	QC		23	0.23	203	0.005	3	1.00	0.009	0.11	<0.1	0.10	0.8	0.2	0.18	4	1.0	<0.2
1281295	Soil		27	0.76	226	0.004	4	1.21	0.004	0.07	<0.1	0.33	4.7	0.1	0.12	3	1.1	<0.2
REP 1281295	QC		28	0.77	231	0.004	5	1.26	0.005	0.08	<0.1	0.34	4.8	0.1	0.11	4	1.2	<0.2
1281349	Soil		21	0.12	181	0.009	2	0.84	0.005	0.11	<0.1	0.11	4.7	0.3	0.07	4	3.3	0.3
REP 1281349	QC		21	0.12	187	0.010	3	0.84	0.005	0.12	0.1	0.12	4.8	0.3	0.08	4	4.1	0.3
1281456	Soil		7	0.08	208	0.002	3	0.52	0.007	0.11	<0.1	0.12	3.0	0.1	<0.05	2	2.3	0.2
REP 1281456	QC		7	0.07	222	0.002	3	0.51	0.007	0.12	<0.1	0.12	2.9	0.1	<0.05	2	2.2	<0.2
1281477	Soil		65	0.11	804	0.004	3	0.76	0.005	0.11	0.2	1.00	1.1	1.0	0.09	3	10.5	0.2
REP 1281477	QC		63	0.10	828	0.004	3	0.70	0.004	0.10	0.2	0.98	1.2	0.9	0.09	3	11.8	0.3
1281485	Soil		22	0.13	338	0.005	2	1.18	0.008	0.08	<0.1	0.04	2.2	0.1	<0.05	4	<0.5	0.3
REP 1281485	QC		23	0.14	350	0.008	3	1.22	0.008	0.09	<0.1	0.03	2.3	0.1	<0.05	4	0.9	0.3
Reference Materials																		
STD DS8	Standard		114	0.62	290	0.106	3	0.91	0.093	0.40	3.1	0.23	1.9	5.7	0.14	5	5.4	4.8
STD DS8	Standard		120	0.62	274	0.117	2	0.93	0.092	0.42	3.0	0.22	2.2	5.5	0.17	5	5.4	5.3
STD DS8	Standard		119	0.62	292	0.123	2	1.01	0.091	0.46	2.9	0.20	3.2	5.5	0.14	5	5.1	5.3
STD DS8	Standard		106	0.54	255	0.099	2	0.83	0.084	0.38	2.5	0.21	2.3	5.0	0.11	4	4.2	4.8
STD DS8	Standard		123	0.63	287	0.119	2	0.96	0.100	0.43	3.0	0.17	2.6	5.6	0.16	5	4.9	4.9
STD DS8	Standard		116	0.59	261	0.126	3	0.89	0.086	0.39	2.9	0.18	2.4	5.4	0.21	5	5.2	5.0
STD DS8 Expected			115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank		<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank		<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

QUALITY CONTROL REPORT WHI11001221.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	0.5	<0.1	<1	<0.1	<0.1	<0.1	<1	0.03	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 02, 2011

QUALITY CONTROL REPORT WHI11001221.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 24, 2011
Report Date: October 17, 2011
Page: 1 of 10

CERTIFICATE OF ANALYSIS WHI11001222.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #17
P.O. Number
Number of Samples: 250

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	250	Sieve soil to 230 mesh			WHI
RJSV	250	Saving all or part of Soil Reject			WHI
1DX2	247	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280801	Soil	12.7	40.0	21.6	63	1.8	19.6	2.6	78	2.62	32.4	3.1	1.2	68	0.1	8.0	0.4	95	0.04	0.111	5
1280802	Soil	7.5	34.4	19.2	35	1.8	8.3	1.7	41	2.92	29.7	6.2	0.3	59	<0.1	7.7	0.3	87	0.02	0.119	7
1280803	Soil	5.5	29.9	10.4	47	0.8	10.9	2.4	71	3.31	15.5	4.5	1.6	26	0.1	3.2	0.2	102	0.03	0.082	9
1280804	Soil	6.0	23.1	12.1	47	0.6	9.5	2.3	70	4.15	13.4	2.0	0.4	22	0.1	2.9	0.5	131	0.02	0.095	7
1280805	Soil	6.3	42.2	17.5	65	1.5	16.2	4.4	186	3.71	23.3	6.0	2.2	36	0.2	4.7	0.3	140	0.06	0.155	9
1280806	Soil	7.4	24.8	13.3	77	0.8	14.3	2.7	88	3.06	16.2	7.1	0.8	21	0.2	4.1	0.2	138	0.05	0.112	9
1280807	Soil	12.7	9.9	6.9	23	1.0	3.9	0.9	34	1.94	8.2	2.4	<0.1	12	<0.1	3.6	0.1	81	0.02	0.052	5
1280808	Soil	18.5	21.3	21.4	16	2.9	4.3	0.8	57	1.34	13.0	12.3	0.3	21	<0.1	11.1	0.3	109	0.02	0.034	19
1280809	Soil	19.4	22.2	10.9	43	1.3	9.3	2.1	81	2.08	12.5	6.3	0.6	15	0.1	6.2	0.2	173	0.02	0.041	11
1280810	Soil	9.9	9.3	10.3	18	2.0	3.5	1.0	33	0.85	7.5	11.5	<0.1	6	<0.1	2.6	0.2	52	0.02	0.038	10
1280811	Soil	8.5	102.7	11.4	100	1.6	53.6	5.9	164	3.27	24.5	9.6	0.4	127	0.4	7.4	0.2	96	0.08	0.160	6
1280812	Soil	8.7	124.8	13.4	125	2.8	101.2	8.2	281	4.23	19.0	7.3	0.5	111	0.6	8.3	0.3	115	0.03	0.120	4
1280813	Soil	10.1	209.4	17.2	354	5.0	295.6	27.6	1089	7.17	31.2	9.2	0.8	112	2.9	11.2	0.2	241	0.14	0.169	7
1280814	Soil	13.9	278.6	25.5	127	6.3	106.5	7.8	211	4.88	75.7	16.4	2.2	360	0.8	19.4	0.3	171	0.09	0.252	6
1280815	Soil	7.4	142.8	30.0	192	4.4	121.4	12.2	578	4.42	41.5	11.0	0.7	228	1.0	13.2	0.3	246	0.16	0.270	11
1280816	Soil	6.8	172.6	34.5	179	5.3	100.6	9.9	297	3.70	45.7	17.4	0.9	241	1.0	14.9	0.3	246	0.24	0.331	11
1280817	Soil	5.1	120.3	17.3	212	4.6	287.3	27.2	1037	7.44	785.4	76.1	1.5	126	0.7	80.6	0.2	78	0.19	0.142	2
1280818	Soil	1.8	28.3	10.7	37	1.1	25.2	3.7	261	1.65	54.9	37.1	0.3	19	0.2	3.8	0.2	26	0.10	0.074	3
1280819	Soil	7.3	69.1	31.7	168	1.7	27.9	5.8	99	3.57	41.0	13.9	2.2	58	0.4	5.5	0.3	48	0.02	0.141	3
1280820	Soil	3.4	44.9	20.9	95	0.8	22.7	14.3	625	2.24	14.1	4.8	0.6	22	0.2	2.6	0.2	30	0.03	0.078	3
1280821	Soil	4.1	44.4	23.9	108	0.5	25.4	14.1	604	2.64	14.5	5.0	1.0	20	0.2	2.7	0.3	38	0.03	0.077	5
1280822	Soil	5.5	57.2	38.2	161	0.5	34.7	16.8	1034	3.85	19.3	5.0	0.9	20	0.2	3.8	0.4	46	0.02	0.110	4
1280823	Soil	4.5	37.6	19.9	159	0.2	29.1	9.5	264	2.39	11.7	2.3	0.4	12	0.2	2.2	0.3	41	<0.01	0.054	4
1280824	Soil	35.8	123.0	20.4	103	3.1	29.6	3.1	91	2.98	3.4	3.7	0.6	108	1.3	8.1	0.3	265	0.08	0.411	14
1280825	Soil	48.3	137.5	21.2	406	8.7	128.3	4.0	60	2.65	5.5	3.9	0.5	133	7.7	24.8	0.3	631	0.17	0.219	35
1280826	Soil	69.1	434.4	17.0	887	35.1	247.3	5.5	212	3.98	59.9	3.0	1.1	524	25.0	24.2	0.2	601	0.77	0.726	28
1280827	Soil	24.9	147.1	18.3	1617	8.0	241.6	7.2	413	3.20	33.4	3.5	1.6	702	37.0	14.0	0.1	278	9.08	0.376	12
1280828	Soil	9.8	65.2	7.0	127	3.5	28.5	1.7	47	0.91	8.6	1.8	0.1	64	3.3	4.6	0.1	156	0.19	0.158	9
1280829	Soil	16.9	106.2	30.6	240	3.0	54.9	12.0	465	2.83	22.2	4.0	1.1	175	3.6	8.8	0.3	166	0.25	0.219	8
1280830	Soil	38.7	232.5	25.5	567	8.6	136.7	9.2	360	2.97	37.3	4.1	1.2	367	12.4	22.2	0.3	501	0.67	0.479	21

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280801	Soil	23	0.07	637	0.004	3	0.52	0.010	0.08	0.1	0.46	3.5	0.7	0.15	3	5.9	0.2
1280802	Soil	23	0.06	520	0.006	3	0.60	0.013	0.08	0.2	0.31	0.9	0.7	0.22	5	4.7	<0.2
1280803	Soil	20	0.14	269	0.021	1	0.62	0.004	0.09	0.2	0.09	1.7	0.5	0.10	4	4.5	<0.2
1280804	Soil	17	0.10	216	0.016	1	0.72	0.009	0.09	0.2	0.08	0.9	0.5	0.16	5	3.9	<0.2
1280805	Soil	29	0.23	353	0.027	3	0.96	0.011	0.11	0.2	0.22	3.0	0.6	0.14	5	5.2	<0.2
1280806	Soil	21	0.14	343	0.016	2	0.69	0.006	0.07	0.2	0.14	1.3	0.4	0.10	3	3.9	<0.2
1280807	Soil	8	0.03	326	0.006	1	0.44	0.013	0.07	0.1	0.11	0.2	0.5	0.11	3	2.4	<0.2
1280808	Soil	14	0.03	382	0.006	2	0.40	0.002	0.08	0.2	1.61	0.4	1.0	0.16	2	6.2	<0.2
1280809	Soil	15	0.07	207	0.013	2	0.50	0.004	0.04	0.2	0.44	0.8	0.5	<0.05	3	5.6	<0.2
1280810	Soil	7	0.03	233	0.006	2	0.50	0.009	0.03	0.2	1.30	0.1	0.5	<0.05	3	3.2	<0.2
1280811	Soil	21	0.12	536	0.005	3	0.87	0.005	0.09	0.1	0.24	1.5	0.4	0.13	3	5.7	0.3
1280812	Soil	19	0.05	694	0.003	3	0.61	0.006	0.11	<0.1	0.16	3.8	0.5	0.16	2	8.5	0.2
1280813	Soil	41	0.17	1012	0.008	3	1.27	0.006	0.08	0.1	0.37	12.5	0.6	0.11	3	7.4	0.2
1280814	Soil	34	0.17	858	0.007	3	0.97	0.006	0.12	0.1	0.54	5.2	2.3	0.18	3	15.6	0.5
1280815	Soil	38	0.11	1261	0.010	5	0.79	0.004	0.11	0.2	0.34	3.3	0.7	0.06	3	10.5	0.3
1280816	Soil	37	0.16	1118	0.008	5	0.84	0.004	0.10	0.2	0.59	2.4	0.7	0.08	3	13.1	0.4
1280817	Soil	26	0.05	899	0.001	3	0.43	0.003	0.06	<0.1	1.17	6.6	1.1	0.12	1	14.2	<0.2
1280818	Soil	8	0.06	487	0.005	2	0.63	0.022	0.05	<0.1	0.18	1.3	0.2	0.07	2	1.7	<0.2
1280819	Soil	10	0.03	743	<0.001	2	0.48	0.004	0.12	<0.1	0.19	3.3	0.4	0.23	1	5.9	<0.2
1280820	Soil	8	0.07	210	0.005	3	0.56	0.012	0.09	0.1	0.07	1.8	0.3	0.08	2	1.9	<0.2
1280821	Soil	12	0.12	188	0.005	3	0.71	0.010	0.09	<0.1	0.06	1.9	0.3	0.05	3	1.7	<0.2
1280822	Soil	13	0.06	261	0.003	2	0.60	0.004	0.10	<0.1	0.05	1.4	0.3	0.07	2	2.4	<0.2
1280823	Soil	9	0.03	407	0.002	2	0.46	0.003	0.09	<0.1	0.03	1.5	0.2	<0.05	2	1.5	<0.2
1280824	Soil	35	0.05	847	0.003	11	0.58	0.003	0.18	0.3	0.56	0.8	1.7	0.36	3	51.8	0.7
1280825	Soil	93	0.04	1401	0.004	7	0.65	0.003	0.13	0.4	0.62	2.0	2.6	0.27	4	98.5	0.3
1280826	Soil	203	0.16	195	0.004	7	1.24	0.006	0.17	0.6	1.95	4.1	2.5	0.65	8	66.5	0.5
1280827	Soil	70	4.80	1182	0.004	12	0.35	0.015	0.07	0.1	1.08	3.5	0.7	<0.05	1	20.1	<0.2
1280828	Soil	32	0.06	656	0.002	3	0.46	0.019	0.06	<0.1	0.34	0.2	0.9	0.14	2	8.1	<0.2
1280829	Soil	28	0.05	1571	0.002	7	0.55	0.004	0.13	0.1	0.50	2.9	1.2	0.17	2	10.3	<0.2
1280830	Soil	94	0.08	1991	0.004	13	0.88	0.005	0.18	0.2	1.08	3.5	2.1	0.24	4	29.9	0.4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280831	Soil	12.5	59.8	24.3	318	1.3	51.9	7.6	131	3.12	23.2	3.2	0.4	55	0.8	6.7	0.3	128	0.05	0.149	8
1280832	Soil	3.0	16.5	6.4	48	1.4	10.4	1.8	67	0.66	4.0	1.7	0.1	15	1.1	1.4	<0.1	26	0.05	0.087	2
1280833	Soil	20.6	44.2	22.4	290	1.1	55.8	4.3	66	2.03	23.0	1.7	0.6	46	0.5	9.3	0.3	181	0.01	0.071	11
1280834	Soil	14.5	41.6	14.3	198	0.7	36.8	3.9	58	1.78	18.0	1.5	0.2	35	0.5	6.1	0.2	139	0.03	0.109	12
1280835	Soil	29.0	58.5	23.5	293	2.0	50.8	4.2	45	2.05	17.4	2.3	0.7	49	1.0	9.9	0.3	191	0.02	0.079	14
1280836	Soil	19.7	78.7	42.8	484	0.9	59.7	11.4	95	5.65	89.6	3.2	0.2	126	0.4	20.1	0.5	234	0.02	0.178	7
1280837	Soil	14.2	50.0	24.3	116	1.7	27.5	2.7	30	1.88	33.1	4.3	0.6	89	0.4	6.5	0.3	128	0.03	0.187	15
1280838	Soil	52.7	198.4	18.0	269	3.6	93.8	2.5	38	2.15	85.1	<0.5	0.6	224	4.4	21.0	0.2	646	0.14	0.124	37
1280839	Soil	10.5	117.5	19.9	559	0.7	202.3	41.0	1457	12.45	159.1	7.0	2.1	7	2.3	16.2	0.3	128	0.03	0.074	12
1280840	Soil	6.5	470.2	37.3	334	2.3	100.6	26.4	859	8.55	40.3	233.0	4.1	105	1.0	6.2	0.5	94	1.74	0.866	19
1280841	Soil	4.5	123.0	15.1	302	0.7	43.1	13.1	1541	6.55	30.4	16.3	2.1	249	1.3	3.3	0.2	51	7.86	0.142	8
1280842	Soil	6.5	258.0	24.6	433	1.5	76.5	33.2	612	7.73	36.2	29.2	5.0	50	3.3	5.4	0.3	52	1.36	0.140	11
1280843	Soil	7.3	417.6	24.5	485	2.0	108.3	27.7	1014	7.81	40.6	44.6	1.8	73	1.1	7.3	0.4	50	1.99	0.178	12
1280844	Soil	5.1	168.1	15.5	412	1.0	62.9	13.4	876	6.43	19.1	21.7	1.4	47	1.7	3.4	0.2	46	2.16	0.223	9
1280845	Soil	7.5	77.3	23.4	304	0.6	44.0	10.1	740	3.83	18.1	3.4	0.3	39	3.9	2.8	0.3	59	0.29	0.217	11
1280846	Soil	6.7	117.2	27.6	258	0.7	66.2	34.5	975	6.33	13.0	33.2	2.3	27	1.0	2.5	0.3	40	0.51	0.137	11
1280847	Soil	6.4	79.3	20.0	207	0.2	50.9	19.2	456	4.53	16.0	4.6	0.8	25	0.9	2.4	0.3	41	0.22	0.088	7
1280848	Soil	71.8	134.2	12.5	1136	1.1	177.1	9.1	234	2.43	49.5	1.6	3.7	97	15.4	27.0	0.2	390	3.50	0.082	22
1280849	Soil	32.4	109.1	15.8	456	1.2	95.9	12.7	270	3.48	20.2	5.5	2.8	56	3.6	7.6	0.3	106	0.35	0.072	11
1280850	Soil	5.0	85.9	28.0	158	1.0	44.7	11.8	298	2.90	16.9	9.9	0.6	41	0.5	3.5	0.3	39	0.04	0.059	5
1280851	Soil	2.8	138.6	20.9	203	0.5	48.3	12.7	336	3.68	16.3	10.7	0.3	13	0.3	2.7	0.3	38	0.03	0.075	4
1280852	Soil	4.5	223.5	18.1	406	0.7	80.7	20.8	774	5.56	22.6	23.5	0.4	11	0.5	3.2	0.4	64	0.05	0.135	5
1280853	Soil	4.0	44.4	10.4	108	0.3	29.0	8.1	426	2.68	8.4	2.9	0.1	13	0.8	1.7	0.2	28	0.05	0.136	3
1280854	Soil	2.1	29.5	4.7	58	0.1	14.6	4.6	98	1.86	5.7	1.3	<0.1	5	0.1	1.1	0.2	25	0.02	0.065	2
1280855	Soil	2.7	83.6	11.8	91	0.3	24.6	5.6	131	2.40	16.0	5.1	0.1	8	0.1	3.0	0.3	49	0.01	0.045	5
1280856	Soil	7.8	131.9	16.1	225	0.6	39.5	7.4	130	4.15	255.4	4.7	0.6	15	0.5	12.0	0.4	105	0.01	0.076	7
1280857	Soil	12.8	50.9	23.5	157	0.9	27.2	7.4	183	2.74	40.5	<0.5	0.2	46	0.4	4.5	0.3	111	0.02	0.097	8
1280858	Soil	2.6	63.1	15.4	182	0.3	51.6	19.9	731	6.34	32.2	4.6	1.0	8	0.9	3.0	0.3	35	0.05	0.069	5
1280859	Soil	3.4	60.8	11.4	157	0.2	46.3	12.2	108	4.12	18.4	0.9	0.1	7	1.2	2.3	0.3	47	0.02	0.102	4
1280860	Soil	8.6	52.9	13.3	127	0.3	44.0	10.6	153	3.62	17.4	3.4	0.2	11	0.2	2.9	0.2	24	0.02	0.096	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280831	Soil	18	0.05	505	0.003	4	0.49	0.007	0.10	0.1	0.16	1.4	0.6	0.09	2	5.6	<0.2
1280832	Soil	7	0.02	227	0.001	3	0.18	0.017	0.04	<0.1	0.14	0.2	0.2	<0.05	<1	1.7	<0.2
1280833	Soil	21	0.02	242	0.002	4	0.35	0.002	0.07	0.2	0.10	0.8	0.7	0.07	2	7.1	<0.2
1280834	Soil	20	0.03	580	0.003	4	0.40	0.004	0.07	<0.1	0.11	0.7	0.5	0.05	2	4.6	<0.2
1280835	Soil	27	0.02	651	0.002	5	0.41	0.003	0.10	0.2	0.13	0.8	1.1	0.18	2	10.4	0.3
1280836	Soil	39	0.02	289	0.004	6	0.54	0.004	0.11	<0.1	0.07	1.6	0.3	0.13	4	4.9	<0.2
1280837	Soil	21	0.02	346	0.002	3	0.48	0.003	0.08	<0.1	0.23	1.4	0.4	0.11	3	4.0	<0.2
1280838	Soil	76	0.03	768	0.003	5	0.62	0.003	0.12	0.1	0.27	1.5	0.8	0.18	2	22.6	0.4
1280839	Soil	10	0.14	2724	0.002	3	1.38	0.001	0.08	<0.1	1.34	16.1	0.4	<0.05	4	2.4	<0.2
1280840	Soil	43	0.12	731	0.008	12	1.21	0.003	0.26	0.1	0.35	11.1	0.2	<0.05	4	4.7	0.3
1280841	Soil	16	3.25	530	0.004	8	0.92	0.008	0.18	<0.1	0.11	4.5	0.2	<0.05	2	1.9	<0.2
1280842	Soil	13	0.48	286	0.003	6	0.88	0.003	0.22	<0.1	0.27	10.7	0.5	<0.05	2	4.9	<0.2
1280843	Soil	19	0.76	1296	0.003	5	0.92	0.003	0.17	<0.1	0.40	6.1	0.2	0.06	2	4.3	<0.2
1280844	Soil	14	0.65	652	0.003	5	0.90	0.002	0.19	<0.1	0.29	4.2	0.2	0.08	2	2.9	<0.2
1280845	Soil	16	0.10	1092	0.004	2	0.97	0.006	0.10	<0.1	0.11	0.6	0.2	0.15	3	2.2	<0.2
1280846	Soil	23	0.34	1689	0.008	5	1.27	0.004	0.18	<0.1	0.17	5.5	0.2	0.12	3	2.0	<0.2
1280847	Soil	15	0.16	703	0.006	3	0.77	0.004	0.14	<0.1	0.13	2.7	0.2	0.06	3	1.2	<0.2
1280848	Soil	13	1.96	486	0.002	6	0.41	0.004	0.10	<0.1	2.57	4.3	1.0	<0.05	1	8.1	<0.2
1280849	Soil	9	0.16	584	0.002	3	0.57	0.003	0.13	<0.1	0.73	5.2	0.4	<0.05	1	3.2	<0.2
1280850	Soil	12	0.03	312	0.002	2	0.43	0.002	0.10	<0.1	0.32	3.5	0.2	0.11	2	1.4	<0.2
1280851	Soil	12	0.07	79	0.012	2	0.72	0.013	0.07	<0.1	0.11	2.2	0.2	0.05	3	1.8	<0.2
1280852	Soil	21	0.08	175	0.005	5	0.75	0.003	0.16	0.1	0.17	4.6	0.2	0.08	3	2.1	0.3
1280853	Soil	8	0.04	293	0.003	3	0.59	0.013	0.08	<0.1	0.12	0.6	0.2	0.06	2	1.0	<0.2
1280854	Soil	8	0.03	75	0.004	1	0.42	0.011	0.06	<0.1	0.06	0.4	0.1	<0.05	2	<0.5	<0.2
1280855	Soil	13	0.02	82	0.006	2	0.38	0.005	0.05	<0.1	0.04	0.8	<0.1	<0.05	3	1.4	<0.2
1280856	Soil	23	0.04	184	0.007	4	0.62	0.002	0.08	<0.1	0.07	2.8	0.4	<0.05	5	2.8	0.2
1280857	Soil	16	0.04	321	0.004	2	0.54	0.003	0.09	0.1	0.06	0.4	0.3	0.06	3	1.6	<0.2
1280858	Soil	14	0.07	1515	0.003	3	0.73	0.003	0.10	<0.1	0.13	4.1	0.2	<0.05	3	1.1	<0.2
1280859	Soil	12	0.03	233	0.003	3	0.53	0.005	0.09	<0.1	0.03	0.8	0.1	<0.05	2	1.2	<0.2
1280860	Soil	6	0.03	151	0.002	2	0.38	0.011	0.05	<0.1	0.07	1.0	0.1	<0.05	2	0.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280771	Soil		10.0	32.4	13.1	207	0.6	37.5	7.5	136	2.04	18.8	2.5	2.2	49	1.5	2.7	0.2	83	0.54	0.113	10
1280772	Soil		8.5	48.3	14.9	218	0.8	53.4	8.6	201	2.25	18.7	5.1	2.3	55	2.9	3.0	0.2	79	0.65	0.108	10
1280773	Soil		6.0	29.4	15.1	166	0.8	27.2	6.6	315	2.11	17.3	3.6	2.0	43	1.8	2.1	0.2	88	0.37	0.103	9
1280774	Soil		4.8	14.1	8.4	91	0.1	16.1	2.4	50	0.90	14.3	0.5	0.5	13	0.5	1.5	0.1	85	0.03	0.033	11
1280775	Soil		4.3	129.3	27.5	121	1.3	36.4	24.7	1544	2.98	12.5	32.7	1.3	72	0.9	2.1	0.3	59	1.36	0.226	24
1280776	Soil		3.6	71.9	19.5	124	1.1	34.3	19.5	931	4.48	18.0	18.1	2.8	42	0.4	1.6	0.2	66	0.82	0.179	23
1280777	Soil		1.7	57.5	8.9	78	0.6	22.0	8.7	284	2.23	6.1	12.6	1.3	56	0.3	0.9	0.1	45	1.27	0.143	19
1280778	Soil		1.3	55.7	7.7	56	0.5	17.4	6.3	273	1.77	5.1	8.5	0.8	49	0.2	0.7	0.1	38	1.15	0.126	13
1280779	Soil		2.8	68.1	13.4	139	0.9	28.4	13.7	436	2.62	8.6	16.9	1.7	53	0.7	1.4	0.2	64	1.13	0.145	20
1280780	Soil		3.0	70.8	11.2	76	0.4	20.4	11.1	802	2.12	9.2	12.7	1.1	53	0.6	1.4	0.1	44	1.10	0.122	15
1280781	Soil		2.7	63.6	10.5	57	0.5	18.2	11.1	1529	1.67	5.3	11.5	0.8	57	0.6	1.1	0.1	38	1.29	0.126	15
1280782	Soil		2.6	33.2	13.4	91	0.5	18.1	10.8	728	2.32	9.2	6.1	2.2	48	0.5	1.0	0.2	43	0.98	0.132	17
1280783	Soil		3.2	35.9	12.6	67	0.4	15.4	11.5	785	2.21	8.2	5.4	1.4	46	0.3	0.9	0.3	36	0.91	0.110	13
1280784	Soil		4.1	36.8	14.7	64	0.4	15.4	14.6	756	2.33	12.1	4.7	2.0	49	0.4	1.0	0.2	34	0.86	0.111	14
1280785	Soil		4.8	46.7	15.4	85	0.4	21.8	10.3	351	2.68	11.1	8.1	2.7	34	0.5	1.4	0.3	29	0.59	0.129	17
1280786	Soil		3.9	20.4	17.5	72	0.2	13.4	4.9	256	1.82	16.1	10.1	0.7	9	0.2	1.7	0.3	51	0.04	0.077	11
1280787	Soil		2.4	19.7	7.0	42	<0.1	9.5	4.0	101	1.64	8.5	<0.5	0.6	5	<0.1	1.0	0.2	44	0.02	0.039	10
1280788	Soil		9.4	14.5	10.8	30	0.6	8.8	2.5	148	1.54	20.3	1.4	0.1	33	0.1	3.9	0.2	96	0.03	0.077	5
1280789	Soil		7.2	19.6	14.6	45	0.7	10.3	2.7	121	2.08	25.0	3.0	0.1	28	0.2	4.2	0.3	97	0.03	0.098	6
1280790	Soil		3.7	23.4	9.5	64	0.6	17.9	4.4	140	2.35	17.5	5.0	0.5	17	0.2	3.3	0.2	73	0.06	0.058	11
1280791	Soil		4.6	33.4	10.8	41	3.3	13.2	3.2	122	2.01	23.7	10.0	0.3	32	0.2	4.2	0.2	66	0.06	0.117	7
1280792	Soil		4.9	11.6	10.4	8	1.8	2.2	0.4	18	1.06	19.6	5.0	0.4	16	<0.1	6.2	0.2	39	0.01	0.035	2
1280793	Soil		3.0	16.4	6.4	18	0.7	4.9	1.4	68	0.95	11.5	2.4	<0.1	20	<0.1	1.7	0.2	34	0.05	0.077	3
1280794	Soil		11.7	26.9	19.6	25	1.9	6.7	1.1	34	1.85	14.5	6.0	0.2	47	0.1	2.9	0.3	89	0.04	0.119	5
1280795	Soil		6.6	32.4	43.2	122	1.0	30.0	9.2	393	3.20	26.5	5.9	1.2	57	0.4	3.7	0.3	109	0.14	0.140	13
1280796	Soil		12.2	30.6	22.7	52	1.7	8.4	1.4	41	1.68	18.5	3.1	0.2	52	0.1	3.8	0.2	84	0.03	0.093	4
1280797	Soil		18.4	37.9	41.4	40	3.4	6.8	0.9	29	1.43	18.3	1.3	0.7	61	0.3	7.0	0.2	81	0.02	0.067	2
1280798	Soil		17.2	49.3	29.3	32	2.9	8.0	1.0	31	1.33	16.0	2.5	0.3	52	0.3	5.3	0.2	84	0.03	0.110	3
1280799	Soil		1.7	36.0	6.9	35	0.8	15.2	4.5	455	2.05	7.2	3.3	0.6	13	0.3	1.5	0.1	41	0.04	0.078	3
1280800	Soil		5.9	51.6	19.9	67	0.8	20.8	3.8	161	3.93	23.7	3.6	0.6	41	0.2	4.2	0.3	103	0.03	0.119	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280771	Soil	20	0.17	1497	0.003	3	0.85	0.005	0.08	0.1	0.40	2.7	0.2	<0.05	3	1.6	<0.2
1280772	Soil	18	0.16	1924	0.002	3	0.80	0.004	0.08	0.1	0.38	3.1	0.3	0.05	2	1.6	<0.2
1280773	Soil	21	0.15	1536	0.002	2	1.09	0.006	0.07	0.1	0.57	2.8	0.3	<0.05	3	1.5	<0.2
1280774	Soil	14	0.02	562	0.003	2	0.48	0.003	0.05	0.1	0.15	0.7	0.2	<0.05	3	0.7	<0.2
1280775	Soil	34	0.71	211	0.005	3	1.58	0.005	0.08	<0.1	0.29	3.4	0.1	0.11	5	1.8	<0.2
1280776	Soil	37	1.00	201	0.006	6	1.67	0.006	0.17	<0.1	0.24	7.0	0.1	<0.05	5	0.7	<0.2
1280777	Soil	27	0.66	176	0.006	6	1.26	0.011	0.12	<0.1	0.19	4.0	0.1	0.09	4	0.9	<0.2
1280778	Soil	20	0.56	179	0.007	3	1.18	0.016	0.08	<0.1	0.14	2.7	<0.1	0.10	4	1.3	<0.2
1280779	Soil	33	1.08	207	0.006	6	1.58	0.006	0.18	<0.1	0.20	5.9	0.1	0.06	5	1.3	<0.2
1280780	Soil	20	0.56	219	0.007	4	1.20	0.018	0.11	<0.1	0.14	2.9	0.1	0.07	4	0.9	<0.2
1280781	Soil	19	0.53	255	0.008	5	1.08	0.015	0.09	<0.1	0.14	2.6	<0.1	0.08	3	1.0	<0.2
1280782	Soil	21	0.41	246	0.003	4	1.14	0.005	0.12	<0.1	0.25	5.0	0.2	<0.05	3	0.7	<0.2
1280783	Soil	16	0.43	231	0.003	3	1.02	0.008	0.07	<0.1	0.24	2.5	0.2	0.09	3	1.0	<0.2
1280784	Soil	14	0.38	248	0.003	4	0.95	0.006	0.08	0.1	0.20	2.8	0.1	0.07	3	1.0	<0.2
1280785	Soil	15	0.43	218	0.002	3	0.94	0.005	0.08	<0.1	0.33	3.8	0.2	0.06	3	1.4	<0.2
1280786	Soil	11	0.10	108	0.004	2	0.55	0.005	0.06	0.1	0.03	0.7	0.2	<0.05	4	0.9	<0.2
1280787	Soil	12	0.09	69	0.004	1	0.71	0.009	0.05	0.1	0.02	0.8	<0.1	<0.05	4	<0.5	<0.2
1280788	Soil	15	0.09	181	0.007	1	0.50	0.005	0.06	0.1	0.04	0.5	0.6	0.10	3	3.0	<0.2
1280789	Soil	17	0.05	258	0.004	2	0.53	0.003	0.07	<0.1	0.09	0.2	0.4	0.13	4	3.9	<0.2
1280790	Soil	23	0.30	168	0.015	1	1.15	0.004	0.05	0.2	0.07	1.0	0.2	<0.05	4	2.2	<0.2
1280791	Soil	17	0.19	347	0.012	2	1.02	0.011	0.07	0.1	0.34	1.0	0.3	0.10	3	4.7	<0.2
1280792	Soil	9	0.02	573	0.001	3	0.37	0.005	0.10	<0.1	0.07	0.4	0.3	0.17	2	3.3	<0.2
1280793	Soil	9	0.08	180	0.006	2	0.64	0.017	0.06	<0.1	0.05	0.6	0.2	<0.05	2	1.6	<0.2
1280794	Soil	20	0.10	299	0.003	2	0.78	0.008	0.06	0.1	0.26	0.5	0.7	0.08	3	3.8	<0.2
1280795	Soil	35	0.55	267	0.026	2	1.82	0.007	0.09	0.2	0.18	2.2	0.4	0.06	6	7.8	<0.2
1280796	Soil	18	0.10	271	0.005	3	0.77	0.014	0.07	0.1	0.24	0.9	0.8	0.12	4	5.7	<0.2
1280797	Soil	18	0.03	518	0.004	3	0.27	0.006	0.11	0.1	1.28	2.3	1.2	0.27	3	15.3	0.2
1280798	Soil	20	0.06	433	0.003	3	0.43	0.006	0.08	0.1	0.86	1.2	1.0	0.19	2	9.8	<0.2
1280799	Soil	16	0.07	64	0.011	1	0.63	0.022	0.04	<0.1	0.06	2.5	0.2	<0.05	2	1.1	<0.2
1280800	Soil	34	0.18	209	0.013	2	0.92	0.011	0.08	0.1	0.11	2.6	0.6	0.13	5	3.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281041	Soil	35.5	95.9	27.3	460	1.5	69.7	3.9	63	2.42	27.8	4.5	0.6	62	5.0	20.0	0.2	295	0.10	0.166	19
1281042	Soil	38.2	80.9	14.3	622	2.1	121.7	8.5	124	2.79	22.0	5.1	0.7	26	4.8	12.0	0.2	215	0.23	0.108	22
1281043	Soil	19.6	76.8	30.0	526	0.6	90.6	10.4	186	3.95	32.6	4.2	0.7	25	2.1	7.8	0.4	213	0.09	0.162	17
1281044	Soil	14.7	58.9	14.9	372	1.0	74.1	7.8	139	3.04	27.5	1.5	0.3	26	2.0	5.5	0.3	107	0.08	0.160	11
1281045	Soil	40.8	146.8	19.3	1494	3.5	226.5	13.1	540	3.59	41.7	5.8	1.9	92	14.0	15.1	0.3	219	0.53	0.207	22
1281046	Soil	13.1	44.4	13.6	310	0.2	61.7	10.0	155	3.39	20.6	1.9	1.1	15	0.7	3.1	0.3	116	0.04	0.101	7
1281047	Soil	10.4	63.0	18.1	508	0.6	73.3	15.9	447	3.57	19.4	6.1	1.1	37	1.9	3.8	0.3	82	0.12	0.186	11
1281048	Soil	2.5	24.3	5.2	67	0.5	26.5	3.2	355	0.85	2.5	7.0	0.2	89	0.4	1.2	0.1	31	0.98	0.125	4
1281049	Soil	6.9	29.9	7.4	125	0.3	25.3	4.3	74	1.68	11.3	2.1	0.1	9	0.2	2.7	0.3	66	0.02	0.045	8
1281050	Soil	2.7	14.4	3.3	42	0.1	8.7	2.0	49	0.78	3.7	0.9	<0.1	6	<0.1	0.9	0.1	31	0.02	0.033	5
1281101	Soil	10.0	62.8	22.8	211	0.7	57.0	8.7	254	4.66	34.3	7.1	0.5	19	0.4	7.6	0.4	103	0.02	0.171	9
1281102	Soil	8.9	60.2	15.2	219	0.3	47.1	7.6	178	3.34	18.9	6.1	1.2	15	0.4	4.1	0.3	75	0.03	0.158	13
1281103	Soil	6.2	31.5	6.7	123	0.2	25.2	5.3	115	1.77	8.2	5.0	0.4	12	0.3	2.1	0.2	56	0.05	0.074	7
1281104	Soil	2.5	19.3	6.5	49	<0.1	11.4	3.3	53	1.13	4.3	2.0	0.1	8	0.1	0.9	0.1	29	<0.01	0.043	6
1281105	Soil	4.9	45.6	8.6	104	0.1	22.8	6.4	89	2.16	9.4	4.5	0.2	9	0.1	1.9	0.2	54	<0.01	0.042	11
1281106	Soil	11.1	68.5	10.4	189	0.1	31.0	14.8	90	3.30	23.2	5.0	0.3	6	0.4	3.4	0.2	43	0.01	0.123	3
1281107	Soil	4.0	91.8	6.3	102	<0.1	22.3	5.8	61	1.94	19.9	4.7	<0.1	5	0.2	3.9	0.2	52	0.01	0.051	5
1281108	Soil	4.0	32.9	13.8	83	0.2	19.0	4.8	83	1.82	9.3	2.4	0.3	14	0.1	1.8	0.3	44	0.01	0.048	11
1281109	Soil	5.1	54.4	16.3	124	0.1	30.1	8.6	106	2.87	11.6	2.7	0.4	19	0.2	2.1	0.3	41	<0.01	0.067	7
1281110	Soil	6.8	52.3	27.5	133	0.4	30.7	6.2	73	2.21	17.4	2.4	0.2	17	0.2	3.7	0.3	62	0.02	0.072	7
1281111	Soil	3.2	40.4	10.2	77	0.2	15.3	3.4	49	1.52	12.7	1.0	0.1	7	0.1	2.3	0.2	53	0.01	0.039	7
1281112	Soil	2.7	15.7	5.8	42	0.3	8.4	2.3	42	0.91	6.5	0.9	0.2	7	<0.1	1.2	0.2	41	0.01	0.027	11
1281113	Soil	5.5	36.8	13.2	117	0.2	31.6	7.7	193	3.32	13.3	3.1	0.6	8	0.2	2.1	0.3	44	0.02	0.051	8
1281114	Soil	2.4	14.8	8.0	39	0.3	8.7	2.1	44	0.99	6.7	1.7	0.1	8	0.2	1.0	0.2	33	0.02	0.048	8
1281115	Soil	2.9	33.4	5.3	76	0.3	19.7	5.3	76	1.90	7.7	1.4	0.1	5	0.2	1.7	0.1	43	<0.01	0.055	7
1281116	Soil	0.3	1.9	1.0	5	0.4	1.0	0.4	11	0.15	<0.5	<0.5	<0.1	5	<0.1	<0.1	<0.1	5	0.02	0.021	<1
1281117	Soil	2.4	58.1	7.0	100	0.5	26.3	6.2	112	2.06	12.8	4.2	0.2	6	0.2	1.6	0.2	33	0.02	0.039	4
1281118	Soil	2.4	26.4	5.0	51	0.1	10.4	2.7	37	1.08	7.9	1.6	0.1	5	<0.1	1.0	0.1	39	0.02	0.041	7
1281119	Soil	1.1	12.5	3.2	27	1.6	5.4	1.3	23	0.50	2.4	1.1	<0.1	4	0.1	0.4	<0.1	18	0.02	0.036	4
1281120	Soil	4.2	69.0	11.0	148	0.7	32.4	7.7	90	2.57	14.3	5.5	0.2	12	0.3	2.5	0.2	49	0.04	0.099	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281041	Soil	41	0.04	845	0.002	5	0.44	0.005	0.10	0.2	0.48	1.5	1.4	0.14	2	11.8	0.3
1281042	Soil	23	0.07	726	0.002	4	0.42	0.004	0.08	0.1	0.72	1.8	0.6	<0.05	1	4.5	<0.2
1281043	Soil	27	0.06	845	0.002	4	0.59	0.003	0.11	0.1	0.21	1.8	0.4	<0.05	2	3.7	<0.2
1281044	Soil	18	0.03	1212	0.002	3	0.46	0.005	0.08	<0.1	0.18	1.1	0.2	<0.05	2	3.5	<0.2
1281045	Soil	37	0.12	1567	0.002	5	0.55	0.004	0.10	0.2	1.49	4.3	0.9	0.07	1	8.5	0.2
1281046	Soil	15	0.05	1776	0.002	8	0.60	0.004	0.09	<0.1	0.08	2.5	0.2	0.07	2	1.6	<0.2
1281047	Soil	18	0.05	1620	0.003	5	0.63	0.002	0.11	<0.1	0.19	3.3	0.3	0.06	2	2.2	<0.2
1281048	Soil	9	0.16	572	0.005	5	0.77	0.024	0.04	<0.1	0.36	0.7	0.2	0.13	2	3.2	<0.2
1281049	Soil	9	0.02	107	0.003	2	0.27	0.008	0.05	<0.1	0.05	0.4	0.2	<0.05	2	1.5	<0.2
1281050	Soil	4	0.02	65	0.003	2	0.20	0.013	0.03	<0.1	0.03	0.1	0.1	<0.05	2	<0.5	<0.2
1281101	Soil	21	0.06	401	0.003	5	0.72	0.005	0.09	0.1	0.09	1.4	0.3	0.07	3	3.1	<0.2
1281102	Soil	15	0.05	353	0.003	5	0.50	0.003	0.09	<0.1	0.07	1.8	0.2	<0.05	2	2.0	<0.2
1281103	Soil	11	0.05	392	0.003	5	0.40	0.012	0.08	<0.1	0.07	1.1	0.2	<0.05	2	1.1	<0.2
1281104	Soil	6	0.03	168	0.003	2	0.31	0.011	0.05	<0.1	0.04	0.3	0.1	<0.05	2	0.6	<0.2
1281105	Soil	8	0.03	116	0.005	3	0.36	0.006	0.08	0.1	0.03	0.5	0.1	<0.05	3	1.1	<0.2
1281106	Soil	8	0.05	130	0.003	4	0.53	0.010	0.09	<0.1	0.08	0.6	0.2	<0.05	3	1.5	<0.2
1281107	Soil	8	0.02	68	0.004	2	0.22	0.014	0.06	<0.1	0.04	0.3	<0.1	<0.05	2	1.6	<0.2
1281108	Soil	8	0.04	155	0.006	2	0.35	0.003	0.07	0.1	0.05	0.6	0.2	<0.05	3	0.9	<0.2
1281109	Soil	9	0.03	262	0.004	3	0.36	0.006	0.09	0.1	0.03	1.2	0.1	0.09	3	1.2	<0.2
1281110	Soil	12	0.03	145	0.004	5	0.36	0.006	0.07	0.1	0.04	0.5	0.1	<0.05	3	2.0	<0.2
1281111	Soil	8	0.02	91	0.004	1	0.34	0.004	0.04	0.1	0.02	0.6	0.1	0.07	4	0.9	<0.2
1281112	Soil	8	0.02	78	0.008	1	0.32	0.005	0.04	0.1	0.01	0.4	<0.1	<0.05	3	<0.5	<0.2
1281113	Soil	12	0.06	173	0.006	2	0.62	0.004	0.07	0.1	0.04	1.5	0.1	<0.05	3	1.2	<0.2
1281114	Soil	9	0.03	83	0.005	2	0.40	0.007	0.04	0.1	0.03	0.2	0.1	<0.05	3	0.6	<0.2
1281115	Soil	10	0.02	103	0.003	3	0.37	0.004	0.06	0.1	0.02	0.2	<0.1	<0.05	3	0.6	<0.2
1281116	Soil	3	<0.01	17	0.005	<1	0.08	0.016	0.02	<0.1	<0.01	0.4	<0.1	<0.05	<1	<0.5	<0.2
1281117	Soil	8	0.03	64	0.010	2	0.34	0.013	0.04	0.1	0.05	1.0	<0.1	<0.05	2	0.8	<0.2
1281118	Soil	8	0.02	61	0.007	1	0.45	0.011	0.04	0.1	0.02	0.3	<0.1	<0.05	3	1.1	<0.2
1281119	Soil	6	0.02	64	0.005	1	0.26	0.012	0.04	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2
1281120	Soil	12	0.04	511	0.005	2	0.59	0.007	0.07	0.1	0.06	0.8	<0.1	<0.05	3	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281121	Soil	3.6	35.7	7.4	94	1.1	23.5	6.0	78	1.91	9.8	1.3	0.3	8	0.1	1.8	0.1	53	0.02	0.054	6
1281122	Soil	2.2	27.1	4.2	54	0.3	9.8	2.4	32	0.88	7.4	5.2	0.1	4	0.1	1.1	<0.1	34	0.01	0.031	7
1281123	Soil	4.5	46.5	7.8	120	0.2	21.4	5.2	71	1.89	11.3	3.8	0.4	5	0.1	1.9	0.2	55	<0.01	0.044	10
1281124	Soil	8.0	26.3	5.8	99	0.1	20.8	3.4	43	1.11	10.1	1.7	0.8	5	0.1	2.9	<0.1	77	0.01	0.037	12
1281125	Soil	4.6	21.4	4.6	70	0.2	13.5	2.3	26	0.76	5.1	1.1	0.1	5	<0.1	1.6	<0.1	45	0.01	0.039	9
1281126	Soil	2.4	13.4	7.8	33	0.5	6.7	1.5	33	0.82	5.3	2.2	0.2	10	0.1	0.8	0.1	34	0.03	0.062	9
1281127	Soil	22.5	65.9	10.6	267	1.3	43.9	4.4	101	2.07	17.1	7.4	1.1	29	2.7	8.0	0.1	161	0.13	0.140	16
1281128	Soil	24.1	96.9	15.4	407	1.1	70.2	10.0	289	2.94	24.4	4.7	2.2	67	3.6	9.5	0.2	191	0.52	0.152	20
1281129	Soil	4.1	40.5	10.3	134	0.4	22.3	5.9	192	2.45	7.8	4.0	1.5	15	0.6	1.8	0.1	63	0.07	0.075	9
1281130	Soil	2.6	40.9	10.3	75	1.1	18.6	6.5	308	1.50	5.3	15.8	1.2	41	1.3	1.0	0.1	43	0.40	0.107	13
1281211	Soil	8.5	101.6	15.6	183	0.7	66.9	21.4	350	6.17	16.8	6.2	4.3	31	0.5	1.8	0.3	35	0.76	0.229	23
1281212	Soil	4.5	51.8	14.9	117	0.5	37.0	14.3	274	3.57	10.5	3.8	4.7	31	0.4	1.1	0.3	32	0.56	0.146	23
1281213	Soil	2.2	34.6	14.3	65	0.1	24.9	14.2	346	2.79	5.9	2.8	1.9	14	0.1	0.7	0.2	39	0.15	0.094	14
1281214	Soil	3.5	76.3	42.9	139	0.4	40.8	37.1	1540	6.39	10.0	1.9	3.7	15	0.2	1.5	0.5	51	0.21	0.117	20
1281215	Soil	0.3	5.2	1.8	7	<0.1	1.6	0.8	26	0.34	1.2	<0.5	<0.1	5	<0.1	0.2	<0.1	9	0.02	0.049	2
1281216	Soil	8.0	51.9	23.9	161	0.2	43.3	63.8	3872	5.53	29.2	3.6	1.7	20	0.4	2.6	0.2	36	0.15	0.211	16
1281217	Soil	5.7	53.1	25.9	95	0.2	21.8	11.7	1468	4.31	21.6	2.0	0.5	11	0.4	2.5	0.4	79	0.04	0.232	13
1281218	Soil	7.7	53.5	23.3	146	0.1	28.7	14.3	892	4.28	23.9	3.2	1.0	11	0.5	3.1	0.3	72	0.04	0.183	12
1281219	Soil	5.8	34.6	13.7	80	<0.1	18.2	7.6	145	1.75	9.0	4.3	1.7	13	0.3	1.8	0.2	44	0.03	0.070	17
1281220	Soil	4.0	26.1	12.0	78	0.1	15.5	10.0	375	2.15	9.5	2.0	1.4	14	0.2	1.4	0.2	50	0.09	0.085	13
1281371	Soil	0.5	10.1	2.6	31	0.1	5.1	1.4	118	0.37	2.0	0.9	0.1	77	0.3	0.3	<0.1	9	2.10	0.052	2
1281372	Soil	4.6	121.5	59.5	273	1.0	61.5	48.6	1759	5.63	30.3	8.6	2.3	26	1.3	4.9	0.4	57	0.08	0.116	6
1281373	Soil	4.5	128.0	78.7	386	1.0	86.3	65.9	2225	6.76	32.0	7.3	4.9	18	2.3	4.8	0.6	38	0.08	0.100	6
1281374	Soil	3.1	43.1	40.4	128	0.3	24.3	17.5	931	4.59	15.2	1.6	1.1	10	0.4	2.2	0.4	36	0.02	0.140	3
1281375	Soil	1.6	22.5	19.1	76	0.7	13.4	11.2	567	1.82	8.4	3.3	0.5	7	0.1	1.7	0.2	15	0.02	0.089	1
1281376	Soil	3.6	52.4	33.3	186	0.5	28.9	17.9	851	4.45	22.9	2.9	1.1	13	0.5	3.8	0.5	37	0.03	0.137	3
1281377	Soil	0.8	9.4	9.5	20	0.3	3.4	7.6	429	0.60	2.0	<0.5	<0.1	7	0.2	0.4	<0.1	9	0.03	0.051	1
1281378	Soil	15.6	79.8	30.5	285	2.8	64.1	11.9	752	3.35	55.6	5.2	0.8	86	2.7	18.0	0.4	196	0.54	0.413	9
1281379	Soil	19.8	14.5	7.0	103	0.9	11.7	1.2	25	0.96	11.3	<0.5	<0.1	13	1.6	8.4	<0.1	98	0.05	0.096	2
1281380	Soil	34.8	66.4	45.1	328	4.6	41.7	13.0	828	4.58	64.1	2.9	1.6	119	6.4	22.2	0.4	275	0.21	0.361	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281121	Soil	8	0.03	101	0.004	2	0.38	0.008	0.06	<0.1	0.02	0.9	0.1	<0.05	3	1.3	<0.2
1281122	Soil	7	0.02	102	0.005	1	0.29	0.008	0.04	0.1	0.02	0.3	<0.1	<0.05	3	0.7	<0.2
1281123	Soil	8	0.03	89	0.005	2	0.39	0.004	0.06	0.2	<0.01	1.0	0.1	<0.05	3	0.9	<0.2
1281124	Soil	10	0.03	98	0.003	4	0.39	0.004	0.07	0.1	0.02	0.8	0.1	<0.05	4	1.7	<0.2
1281125	Soil	9	0.03	75	0.006	2	0.33	0.009	0.07	<0.1	0.02	0.3	0.1	<0.05	3	1.1	<0.2
1281126	Soil	10	0.05	242	0.007	2	0.62	0.008	0.05	0.1	0.05	0.2	0.2	<0.05	3	1.1	<0.2
1281127	Soil	18	0.08	582	0.005	4	0.64	0.004	0.08	0.1	0.48	1.8	0.5	<0.05	2	3.1	<0.2
1281128	Soil	20	0.17	1469	0.004	5	0.69	0.004	0.12	0.1	0.51	3.4	0.5	<0.05	2	3.9	<0.2
1281129	Soil	18	0.22	284	0.008	3	0.91	0.010	0.09	0.1	0.08	1.9	0.1	<0.05	4	1.2	<0.2
1281130	Soil	17	0.36	876	0.007	4	0.91	0.013	0.13	<0.1	0.41	3.0	0.2	<0.05	3	1.1	<0.2
1281211	Soil	34	0.67	160	0.004	3	1.37	0.003	0.11	<0.1	0.24	10.7	0.2	<0.05	3	1.6	<0.2
1281212	Soil	26	0.71	165	0.004	4	1.39	0.005	0.15	<0.1	0.21	6.5	0.2	<0.05	4	1.0	<0.2
1281213	Soil	33	0.44	155	0.004	4	1.46	0.007	0.11	<0.1	0.06	3.0	0.1	<0.05	5	0.7	<0.2
1281214	Soil	33	0.58	309	0.003	3	2.23	0.004	0.15	<0.1	0.11	4.4	0.2	<0.05	6	0.8	<0.2
1281215	Soil	4	0.01	24	0.004	<1	0.21	0.020	0.02	<0.1	0.01	0.3	<0.1	<0.05	<1	<0.5	<0.2
1281216	Soil	21	0.21	262	0.006	2	1.27	0.005	0.09	0.1	0.05	2.7	0.2	<0.05	4	1.1	<0.2
1281217	Soil	24	0.11	126	0.009	3	0.93	0.006	0.08	0.1	0.05	1.2	0.2	<0.05	5	2.0	<0.2
1281218	Soil	21	0.15	131	0.007	2	1.04	0.004	0.08	0.1	0.06	2.0	0.2	<0.05	5	1.6	<0.2
1281219	Soil	15	0.07	127	0.007	2	0.59	0.004	0.08	0.1	0.02	1.3	0.2	<0.05	4	0.8	<0.2
1281220	Soil	20	0.15	147	0.005	1	0.93	0.005	0.08	0.1	0.04	1.6	0.2	<0.05	5	0.5	<0.2
1281371	Soil	5	0.07	229	0.009	4	0.43	0.025	0.02	<0.1	0.06	0.5	<0.1	0.07	<1	0.8	<0.2
1281372	Soil	23	0.22	439	0.004	3	1.42	0.008	0.12	<0.1	0.12	4.8	0.5	<0.05	4	3.2	<0.2
1281373	Soil	22	0.31	386	0.003	3	1.26	0.003	0.11	<0.1	0.16	6.4	0.5	<0.05	3	2.7	<0.2
1281374	Soil	21	0.09	142	0.006	2	1.02	0.014	0.08	0.1	0.08	1.6	0.2	<0.05	4	1.6	<0.2
1281375	Soil	6	0.03	60	0.004	2	0.39	0.014	0.04	<0.1	0.07	0.6	0.1	0.10	2	0.8	<0.2
1281376	Soil	19	0.12	170	0.004	2	0.86	0.006	0.07	<0.1	0.11	1.7	0.2	0.09	3	2.0	<0.2
1281377	Soil	4	0.02	52	0.005	1	0.39	0.020	0.02	<0.1	0.05	0.4	<0.1	0.09	2	<0.5	<0.2
1281378	Soil	37	0.04	528	0.005	5	0.60	0.007	0.10	0.2	0.30	3.1	1.0	0.16	3	8.4	0.3
1281379	Soil	9	0.03	119	0.002	1	0.19	0.017	0.02	<0.1	0.18	0.3	0.8	0.13	<1	3.4	<0.2
1281380	Soil	41	0.06	858	0.004	3	0.59	0.004	0.13	0.2	0.43	3.7	1.9	0.28	3	11.5	0.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281381	Soil	25.4	30.4	41.3	160	3.7	21.0	3.7	81	1.95	26.5	1.9	0.1	61	1.4	9.4	0.3	155	0.06	0.172	5
1281382	Soil	2.0	23.3	8.8	50	0.2	7.0	3.8	178	1.95	3.6	3.4	0.3	10	0.2	0.9	0.2	34	0.05	0.098	8
1281383	Soil	3.0	78.2	14.0	105	0.9	25.7	9.1	401	2.07	10.1	13.2	2.4	85	1.1	1.8	0.2	51	1.17	0.121	20
1281384	Soil	16.5	190.4	30.4	397	2.4	58.2	18.0	264	4.29	37.4	65.5	1.8	125	1.9	6.0	0.3	135	0.97	0.498	18
1281385	Soil	4.6	64.1	14.4	168	2.9	23.4	6.2	90	1.96	6.7	20.6	2.2	25	1.1	1.8	0.2	107	0.21	0.138	17
1281386	Soil	1.6	127.3	13.4	91	0.5	34.8	8.1	512	2.03	6.6	10.7	2.8	102	0.9	1.1	0.2	47	1.14	0.116	21
1281387	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281388	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281389	Soil	2.7	53.9	14.9	100	0.3	21.7	10.5	406	2.16	7.5	3.2	2.1	21	0.4	1.4	0.2	67	0.18	0.127	19
1281390	Soil	1.3	38.4	11.3	27	0.4	11.3	3.3	152	1.14	5.2	3.1	1.9	22	0.7	0.6	0.3	36	0.27	0.115	16
1281391	Soil	0.6	10.6	3.4	11	0.4	4.2	2.3	175	0.35	1.3	0.9	<0.1	15	0.2	0.3	<0.1	10	0.23	0.079	4
1281392	Soil	1.2	18.6	4.2	30	0.2	7.4	3.3	142	0.66	3.4	1.0	0.5	17	0.4	0.8	0.1	21	0.20	0.069	7
1281393	Soil	1.0	46.2	11.8	36	0.8	13.2	8.2	370	1.31	5.3	5.6	1.1	28	0.6	0.9	0.3	30	0.33	0.153	16
1281394	Soil	2.0	12.9	13.4	37	0.4	7.1	12.6	744	1.33	6.3	2.2	0.9	13	0.2	0.6	0.2	41	0.11	0.082	13
1281395	Soil	2.6	49.9	11.2	99	0.6	25.8	11.8	540	2.14	11.4	5.3	2.4	46	0.7	1.5	0.2	37	0.81	0.133	17
1281396	Soil	1.0	11.8	9.8	21	0.8	5.0	2.2	99	0.84	9.7	3.6	0.6	12	0.2	0.5	0.2	26	0.13	0.074	5
1281397	Soil	5.7	16.6	19.0	61	0.5	11.7	17.9	869	1.99	12.4	3.5	2.1	20	0.3	1.2	0.3	51	0.25	0.109	14
1281398	Soil	9.4	169.1	62.7	325	1.0	222.4	25.0	570	6.27	201.2	<0.5	2.1	122	6.6	19.4	0.3	1211	0.55	0.070	6
1281399	Soil	7.9	28.8	10.7	35	1.0	6.9	1.1	39	1.48	13.1	2.1	1.1	57	0.1	4.0	0.2	75	0.04	0.101	4
1281400	Soil	9.3	15.8	14.2	30	1.5	7.3	1.3	72	1.57	11.3	2.7	0.2	40	0.1	3.8	0.3	88	0.03	0.103	5
1281401	Soil	23.0	23.2	22.4	57	1.9	16.1	1.9	47	1.76	18.7	1.4	0.6	45	0.2	5.8	0.3	90	0.03	0.057	4
1281402	Soil	27.8	25.4	28.1	68	1.9	16.5	2.5	78	2.27	28.6	2.8	0.7	67	0.3	7.0	0.4	114	0.03	0.103	4
1281403	Soil	29.4	29.4	28.0	44	2.5	15.9	2.9	111	2.96	27.7	1.1	2.0	82	0.2	8.9	0.4	131	0.03	0.122	4
1281404	Soil	8.5	32.4	24.2	21	3.1	6.5	2.1	76	2.16	20.8	2.2	1.8	67	0.1	4.5	0.4	65	0.03	0.074	5
1281405	Soil	20.0	20.5	19.0	50	1.7	13.7	1.6	42	1.55	16.9	1.8	0.6	40	0.2	5.0	0.3	78	0.03	0.052	4
1281406	Soil	8.2	34.3	25.5	21	3.2	7.1	2.2	77	2.11	20.9	3.9	2.0	73	0.1	5.3	0.4	70	0.04	0.080	6
1281407	Soil	6.4	18.0	19.9	30	2.0	6.6	1.5	65	1.45	15.5	2.2	0.5	83	<0.1	3.6	0.3	51	0.03	0.095	3
1281408	Soil	55.8	46.7	21.9	6	5.3	7.8	0.3	6	2.20	22.1	1.0	1.3	117	0.2	15.0	0.3	209	0.02	0.104	<1
1281409	Soil	36.0	60.6	36.1	4	6.2	9.3	0.3	9	1.91	40.5	<0.5	2.1	66	<0.1	16.4	0.5	103	0.02	0.113	1
1281410	Soil	5.4	12.8	15.5	11	3.7	2.6	0.5	21	1.87	38.9	4.1	0.4	121	<0.1	7.5	0.3	75	0.02	0.115	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281381	Soil	19	0.03	544	0.002	2	0.43	0.010	0.08	0.1	0.26	0.6	1.3	0.19	2	6.9	<0.2
1281382	Soil	13	0.19	164	0.006	3	0.76	0.012	0.10	<0.1	0.07	0.8	0.1	0.14	3	1.0	<0.2
1281383	Soil	22	0.74	531	0.004	3	1.17	0.008	0.09	<0.1	0.32	3.9	0.2	0.09	4	2.5	<0.2
1281384	Soil	29	0.73	402	0.006	7	1.43	0.007	0.15	<0.1	0.44	3.6	0.3	0.21	4	7.0	<0.2
1281385	Soil	38	1.01	150	0.006	4	1.47	0.006	0.15	0.1	0.74	2.4	0.4	0.12	5	2.6	<0.2
1281386	Soil	27	1.01	295	0.005	4	1.45	0.006	0.10	<0.1	0.26	5.4	0.1	0.12	4	1.8	<0.2
1281387	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281388	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281389	Soil	34	0.93	276	0.005	2	1.52	0.006	0.10	<0.1	0.08	1.9	0.1	0.07	6	0.7	<0.2
1281390	Soil	19	0.18	368	0.003	3	1.00	0.006	0.08	<0.1	0.21	2.7	<0.1	0.10	3	1.1	<0.2
1281391	Soil	7	0.04	119	0.002	1	0.25	0.021	0.04	<0.1	0.07	0.6	<0.1	0.07	<1	<0.5	<0.2
1281392	Soil	11	0.11	245	0.004	2	0.39	0.016	0.05	<0.1	0.07	1.3	<0.1	0.09	2	0.8	<0.2
1281393	Soil	21	0.23	296	0.006	2	1.06	0.006	0.06	<0.1	0.41	3.6	0.2	0.14	3	1.9	<0.2
1281394	Soil	14	0.28	138	0.005	3	0.74	0.008	0.09	<0.1	0.08	1.3	0.1	<0.05	4	0.7	<0.2
1281395	Soil	19	0.45	337	0.003	4	1.12	0.008	0.10	0.1	0.24	3.7	0.1	0.07	3	1.4	<0.2
1281396	Soil	7	0.08	159	0.004	1	0.44	0.020	0.07	0.1	0.10	1.4	<0.1	0.05	2	0.7	<0.2
1281397	Soil	16	0.33	298	0.003	2	1.01	0.007	0.12	0.1	0.19	2.1	0.2	<0.05	4	0.9	<0.2
1281398	Soil	12	0.17	1301	0.002	2	0.77	0.004	0.08	<0.1	0.42	5.3	<0.1	0.07	2	4.4	<0.2
1281399	Soil	17	0.07	388	0.003	1	0.36	0.004	0.08	<0.1	0.10	2.3	0.4	0.18	2	4.2	<0.2
1281400	Soil	14	0.07	458	0.004	2	0.64	0.013	0.10	<0.1	0.06	0.7	0.7	0.21	3	3.4	<0.2
1281401	Soil	14	0.05	512	0.003	2	0.31	0.006	0.11	<0.1	0.23	1.4	0.8	0.25	2	8.0	<0.2
1281402	Soil	17	0.06	435	0.003	2	0.47	0.010	0.12	0.1	0.16	1.7	1.3	0.34	3	9.7	<0.2
1281403	Soil	21	0.10	465	0.004	2	0.48	0.011	0.16	0.2	0.29	2.5	1.4	0.53	3	14.4	<0.2
1281404	Soil	23	0.09	479	0.006	3	0.45	0.010	0.21	<0.1	0.30	2.6	0.5	0.45	5	7.1	0.3
1281405	Soil	11	0.04	456	0.002	2	0.28	0.005	0.10	<0.1	0.19	1.3	0.7	0.25	2	6.4	<0.2
1281406	Soil	24	0.10	544	0.009	3	0.48	0.011	0.21	<0.1	0.30	2.9	0.6	0.48	5	6.1	<0.2
1281407	Soil	15	0.05	440	0.014	2	0.39	0.012	0.11	<0.1	0.10	1.5	0.4	0.28	4	6.5	<0.2
1281408	Soil	16	<0.01	262	0.002	3	0.14	0.013	0.26	0.1	0.65	2.2	3.3	0.87	2	32.9	0.3
1281409	Soil	17	0.01	497	0.002	3	0.18	0.012	0.20	0.2	0.81	3.3	2.6	0.54	3	24.0	0.3
1281410	Soil	18	0.02	698	0.002	2	0.38	0.008	0.17	<0.1	0.19	1.3	0.7	0.45	5	7.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281411	Soil	22.4	23.4	14.4	18	2.4	4.3	1.1	49	1.67	40.4	6.9	0.7	71	<0.1	10.8	0.2	113	0.05	0.154	8
1281412	Soil	15.3	21.3	18.2	19	3.0	4.9	1.3	52	1.79	42.4	7.6	1.2	72	<0.1	10.2	0.2	100	0.04	0.136	5
1281413	Soil	8.5	18.1	9.5	25	1.2	6.3	1.6	72	1.31	22.4	3.4	0.5	52	<0.1	5.2	0.2	77	0.05	0.093	7
1281414	Soil	15.6	18.0	25.9	26	1.6	4.8	0.7	25	1.08	14.6	7.3	0.4	25	<0.1	6.8	0.2	63	0.02	0.081	8
1281415	Soil	23.9	38.3	23.8	50	2.4	10.1	0.5	18	1.20	17.9	8.3	0.8	45	0.1	10.4	0.2	93	0.05	0.163	11
1281416	Soil	17.6	31.0	20.3	34	1.9	7.0	0.5	19	1.00	15.5	7.5	0.9	36	<0.1	8.8	0.2	74	0.04	0.108	9
1281417	Soil	6.7	16.4	13.4	50	0.7	11.0	3.0	98	1.95	15.1	5.8	0.4	14	0.1	3.1	0.2	66	0.02	0.045	7
1281418	Soil	3.9	17.9	9.2	64	0.1	15.5	5.6	92	1.61	11.5	2.1	<0.1	7	<0.1	1.8	0.2	36	<0.01	0.038	3
1281419	Soil	3.9	66.0	15.6	83	2.0	40.6	7.3	438	3.17	38.1	63.5	0.6	65	0.5	5.1	0.3	46	1.20	0.125	2
1281420	Soil	4.1	68.7	16.6	92	2.2	46.7	8.7	437	3.30	30.7	22.8	0.6	69	0.7	5.3	0.3	55	1.32	0.122	1
1281421	Soil	6.3	92.8	17.6	172	2.9	81.7	13.1	522	4.13	54.8	37.0	0.8	78	1.0	7.9	0.3	66	0.80	0.115	1
1281422	Soil	6.9	101.0	15.8	243	2.6	136.0	17.2	826	5.42	49.3	16.1	0.6	74	1.6	10.0	0.3	83	0.90	0.115	1
1281423	Soil	7.4	110.6	16.0	689	2.5	305.2	31.4	2238	10.35	66.6	21.3	1.4	73	7.1	15.1	0.3	116	0.62	0.168	2
1281424	Soil	6.0	104.8	15.1	821	2.4	379.8	37.2	2468	12.02	71.5	25.2	2.0	50	9.9	16.1	0.3	129	0.55	0.101	3
1281425	Soil	6.1	110.4	16.8	565	2.3	295.2	28.6	2149	11.03	102.1	28.3	1.6	53	6.7	16.7	0.3	131	0.58	0.100	2
1281426	Soil	7.1	125.0	17.6	677	2.8	300.0	27.1	3579	13.70	251.4	24.7	1.8	63	10.5	23.8	0.3	124	0.53	0.133	2
1281427	Soil	5.1	132.1	14.3	219	1.8	97.5	13.0	592	3.96	96.5	17.0	1.1	59	2.4	10.3	0.3	101	0.11	0.102	6
1281428	Soil	4.5	85.8	38.9	113	3.3	43.2	6.1	275	2.94	168.0	33.5	1.0	129	1.0	16.1	0.3	93	0.04	0.096	5
1281429	Soil	5.9	40.7	15.0	55	4.5	17.6	2.4	69	2.15	79.6	31.5	0.1	134	0.3	9.1	0.3	84	0.03	0.108	4
1281430	Soil	13.6	86.1	25.2	73	6.4	29.4	3.8	170	2.95	115.3	47.5	1.1	166	0.6	13.7	0.4	107	0.04	0.188	3
1281431	Soil	8.9	54.4	16.3	65	3.9	20.4	3.1	124	2.72	78.7	15.8	0.7	152	0.2	8.6	0.4	78	0.03	0.166	1
1281432	Soil	9.1	49.8	16.7	50	3.7	15.0	2.1	93	2.29	92.2	31.2	0.7	129	0.2	8.4	0.4	74	0.02	0.130	2
1281433	Soil	14.5	62.9	21.8	179	3.4	43.4	4.5	107	4.38	48.6	9.2	0.4	162	0.7	9.9	0.4	192	0.03	0.253	1
1281434	Soil	8.1	101.9	22.8	94	4.5	33.3	3.7	116	3.64	39.8	7.8	0.8	122	0.4	13.4	0.4	125	0.03	0.203	2
1281435	Soil	6.5	278.6	24.5	338	5.7	142.1	17.4	921	8.76	44.2	8.6	1.2	117	3.0	15.0	0.4	256	0.04	0.273	1
1281436	Soil	9.4	177.1	27.8	163	6.5	60.3	6.5	286	5.51	51.6	7.3	1.0	177	1.1	18.1	0.4	179	0.07	0.365	2
1281437	Soil	3.9	70.2	27.2	130	1.9	38.6	7.4	213	3.10	23.1	14.2	1.5	72	0.5	4.7	0.4	36	0.57	0.114	2
1281438	Soil	3.3	72.7	52.9	257	1.0	67.1	30.4	820	4.60	14.1	4.1	4.3	38	0.6	4.8	0.5	23	0.14	0.069	3
1281439	Soil	5.0	87.6	50.0	211	1.5	56.8	24.6	903	4.78	27.5	5.4	3.2	58	1.1	6.7	0.4	32	0.10	0.094	4
1281440	Soil	5.3	91.0	38.0	223	1.3	48.4	16.0	406	4.21	30.6	7.9	4.0	81	1.1	6.5	0.4	32	0.07	0.089	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281411	Soil	21	0.04	999	0.006	1	0.44	0.006	0.11	0.2	0.19	2.0	1.0	0.25	4	11.7	<0.2
1281412	Soil	24	0.05	950	0.004	2	0.33	0.003	0.12	0.2	0.34	2.8	1.1	0.24	4	10.0	<0.2
1281413	Soil	15	0.07	835	0.012	3	0.48	0.012	0.07	0.1	0.07	1.5	0.4	0.20	4	4.3	<0.2
1281414	Soil	12	0.04	777	0.004	1	0.39	0.004	0.05	0.2	0.16	0.8	0.8	0.08	3	7.2	<0.2
1281415	Soil	19	0.02	918	0.003	2	0.42	0.002	0.07	0.2	0.63	1.3	1.5	0.15	3	10.7	<0.2
1281416	Soil	14	0.02	901	0.003	2	0.31	0.002	0.06	0.2	0.46	1.2	1.2	0.12	2	9.8	<0.2
1281417	Soil	16	0.11	379	0.011	<1	0.81	0.002	0.03	0.2	0.17	0.7	0.3	<0.05	4	2.4	<0.2
1281418	Soil	5	0.01	145	0.004	<1	0.27	0.005	0.02	0.1	0.02	0.6	<0.1	<0.05	2	1.0	<0.2
1281419	Soil	15	0.18	1479	0.002	4	0.36	0.005	0.05	<0.1	0.67	2.6	0.1	0.16	<1	5.5	<0.2
1281420	Soil	15	0.19	1251	0.002	3	0.32	0.005	0.05	<0.1	0.77	2.8	0.1	0.16	<1	5.4	<0.2
1281421	Soil	18	0.13	1207	0.001	3	0.43	0.004	0.07	<0.1	0.82	4.2	0.2	0.12	1	5.7	<0.2
1281422	Soil	23	0.17	1026	0.001	3	0.54	0.004	0.06	<0.1	1.56	4.2	0.3	0.11	1	6.6	<0.2
1281423	Soil	38	0.14	771	0.002	3	0.59	0.003	0.07	<0.1	0.94	6.5	0.5	0.09	1	7.2	<0.2
1281424	Soil	45	0.18	628	0.004	3	1.17	0.007	0.04	<0.1	1.01	7.2	0.5	0.05	2	5.6	<0.2
1281425	Soil	45	0.19	670	0.003	2	1.01	0.004	0.05	<0.1	0.74	6.7	0.5	0.10	2	6.2	<0.2
1281426	Soil	46	0.20	523	0.003	3	0.84	0.003	0.06	<0.1	0.69	7.6	0.5	0.09	2	5.4	<0.2
1281427	Soil	26	0.20	1223	0.008	1	0.93	0.004	0.05	0.2	0.22	2.9	0.5	0.08	3	4.6	<0.2
1281428	Soil	21	0.10	416	0.007	1	0.58	0.003	0.08	0.1	0.29	2.1	1.0	0.19	3	12.4	<0.2
1281429	Soil	17	0.05	509	0.004	1	0.45	0.003	0.05	0.1	0.93	0.4	0.8	0.16	3	8.7	<0.2
1281430	Soil	32	0.04	593	0.002	1	0.39	0.003	0.12	0.1	0.62	3.6	1.3	0.34	2	16.1	0.4
1281431	Soil	15	0.02	640	0.002	<1	0.31	0.003	0.13	<0.1	0.34	2.7	0.8	0.30	2	9.1	0.2
1281432	Soil	15	0.02	717	0.001	1	0.30	0.002	0.12	<0.1	0.38	2.2	0.8	0.31	2	10.4	0.3
1281433	Soil	25	0.02	727	0.002	1	0.30	0.004	0.14	<0.1	0.36	2.4	1.1	0.36	2	7.3	0.4
1281434	Soil	28	0.03	449	0.002	2	0.44	0.004	0.13	<0.1	0.62	3.0	1.0	0.34	2	11.7	0.3
1281435	Soil	43	0.04	315	0.003	<1	1.19	0.003	0.08	<0.1	0.58	10.4	0.9	0.21	2	12.5	0.4
1281436	Soil	42	0.03	682	0.002	2	0.62	0.007	0.15	<0.1	0.86	5.6	1.5	0.46	3	20.2	0.3
1281437	Soil	11	0.08	1130	0.001	1	0.38	0.003	0.08	<0.1	0.52	2.8	0.2	0.15	1	3.7	<0.2
1281438	Soil	8	0.10	396	0.001	<1	0.41	0.002	0.06	<0.1	0.21	4.9	0.3	<0.05	2	1.7	<0.2
1281439	Soil	11	0.05	1166	0.002	2	0.31	0.003	0.10	<0.1	0.27	4.9	0.4	0.15	1	4.5	<0.2
1281440	Soil	6	0.03	1270	<0.001	2	0.26	0.003	0.11	<0.1	0.18	4.6	0.3	0.15	<1	5.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281441	Soil	54.7	355.5	17.4	515	19.0	134.0	3.0	92	3.02	39.4	2.0	1.7	227	9.1	23.5	0.3	290	0.86	0.408	17
1281442	Soil	10.4	84.8	37.7	170	2.4	35.3	8.7	120	3.06	22.1	4.6	1.3	53	1.1	6.8	0.4	66	0.03	0.157	5
1281443	Soil	28.9	166.9	29.5	1184	6.2	176.5	11.4	342	3.68	39.7	4.8	2.3	127	13.0	17.7	0.3	193	1.18	0.242	12
1281444	Soil	11.0	76.1	20.2	196	1.8	66.4	13.8	269	4.47	14.4	5.7	0.8	26	1.9	6.6	0.3	75	0.09	0.149	6
1281445	Soil	9.0	88.3	16.2	195	0.8	71.3	14.3	195	4.08	13.4	7.4	0.6	30	0.3	2.7	0.3	23	0.33	0.061	4
1281446	Soil	5.3	93.3	23.5	180	1.2	68.2	14.2	203	3.99	18.2	10.3	1.0	22	0.3	2.5	0.3	12	0.29	0.036	4
1281447	Soil	4.5	100.1	22.6	187	1.0	83.2	20.6	448	4.34	12.7	10.1	1.2	20	0.4	2.5	0.4	21	0.32	0.066	5
1281448	Soil	19.1	81.5	47.1	159	0.5	58.0	13.6	652	3.41	18.6	2.3	0.8	10	0.6	4.1	0.3	39	0.02	0.046	5
1281449	Soil	3.6	30.8	14.5	80	0.4	14.1	2.8	47	1.33	21.7	5.2	0.2	11	<0.1	2.6	0.2	37	0.01	0.045	2
1281450	Soil	4.9	161.0	17.7	181	0.6	60.5	12.9	145	4.09	14.9	10.0	0.2	6	0.4	3.8	0.4	64	0.04	0.109	5
1281501	Soil	6.7	399.4	26.5	251	0.3	82.6	14.5	115	6.65	174.9	45.3	0.6	43	0.3	12.3	0.5	117	0.02	0.137	3
1281502	Soil	1.9	96.0	7.0	76	<0.1	16.2	9.0	77	4.02	4.8	8.1	0.9	3	<0.1	1.0	0.3	34	0.01	0.071	4
1281503	Soil	2.9	73.6	15.5	122	0.1	26.1	9.9	150	3.41	11.1	7.5	0.6	9	0.4	1.9	0.4	40	0.07	0.097	9
1281504	Soil	7.9	435.2	22.3	280	<0.1	86.1	22.8	136	5.71	41.2	63.7	1.1	4	0.3	7.2	0.6	91	0.01	0.061	8
1281505	Soil	3.2	177.5	33.0	118	0.8	55.3	13.5	198	4.36	31.8	16.6	0.4	12	0.2	5.1	0.4	33	0.03	0.089	4
1281506	Soil	4.7	143.9	32.1	130	0.8	51.1	11.7	199	4.29	31.1	13.2	2.0	27	0.2	4.4	0.4	55	0.09	0.121	9
1281507	Soil	13.7	55.8	14.1	144	0.1	25.7	5.0	70	1.92	21.2	2.9	0.2	16	0.3	6.5	0.2	124	0.03	0.083	15
1281508	Soil	2.0	145.8	10.4	330	<0.1	75.8	19.7	763	5.74	19.6	3.6	1.5	8	2.0	2.1	0.5	28	0.08	0.060	7
1281509	Soil	5.4	76.4	16.9	237	0.4	66.2	18.7	555	4.00	13.6	6.5	0.8	7	0.7	2.4	0.3	28	0.06	0.067	5
1281510	Soil	6.1	100.1	9.3	409	1.5	40.6	9.8	105	3.64	84.9	5.8	0.4	5	0.7	20.9	0.3	99	0.01	0.075	9
1281511	Soil	5.0	174.4	44.9	1015	2.2	77.6	25.5	722	7.45	109.3	16.8	1.1	23	3.5	29.3	0.6	78	0.02	0.156	6
1281512	Soil	6.3	50.5	7.2	238	0.1	32.1	6.7	106	2.75	31.0	2.3	0.7	6	0.4	5.7	0.3	66	0.01	0.043	8
1281513	Soil	1.7	35.9	8.4	103	0.3	22.6	7.7	223	2.23	13.5	3.0	0.1	10	0.5	1.9	0.2	17	0.05	0.062	4
1281514	Soil	3.7	58.6	19.4	148	0.2	38.8	15.6	552	4.26	12.5	2.7	2.0	7	0.2	2.4	0.3	46	0.01	0.056	8
1281515	Soil	6.1	63.1	22.6	75	0.4	43.6	12.0	404	4.10	10.5	5.6	0.5	7	0.2	2.2	0.3	18	0.03	0.068	8
1281516	Soil	6.9	57.4	16.9	140	0.2	42.0	17.9	1384	3.64	8.1	1.6	0.7	4	0.2	1.2	0.3	15	0.01	0.063	4
1281517	Soil	3.5	14.8	12.1	49	0.1	11.1	2.9	106	1.69	9.5	1.2	0.4	11	<0.1	1.5	0.3	54	0.03	0.042	14
1281518	Soil	5.8	46.3	16.4	159	<0.1	39.5	10.3	504	3.84	10.0	1.6	0.8	7	0.2	1.7	0.3	33	0.02	0.070	8
1281519	Soil	7.9	45.2	31.2	139	0.3	34.4	6.1	178	3.62	38.4	9.4	1.1	34	0.3	4.8	0.4	89	0.02	0.068	8
1281520	Soil	3.6	151.3	6.5	331	0.1	21.1	3.8	47	2.14	24.8	18.7	<0.1	5	1.2	3.2	0.2	49	0.02	0.064	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281441	Soil	139	0.08	894	0.002	2	0.49	0.006	0.09	0.5	4.76	4.8	1.7	0.48	5	45.5	0.5
1281442	Soil	19	0.02	427	0.002	2	0.37	0.003	0.09	<0.1	0.54	2.3	0.6	0.15	2	7.8	0.3
1281443	Soil	44	0.38	839	0.002	3	0.33	0.003	0.08	0.2	1.14	4.6	0.8	0.16	2	17.5	0.3
1281444	Soil	23	0.03	413	0.002	2	0.31	0.002	0.05	<0.1	0.24	3.0	0.3	<0.05	1	4.3	<0.2
1281445	Soil	6	0.07	1134	0.001	4	0.26	0.001	0.06	<0.1	0.55	5.4	0.2	<0.05	<1	1.9	<0.2
1281446	Soil	7	0.09	1264	<0.001	3	0.30	0.001	0.06	<0.1	0.73	8.1	0.1	<0.05	<1	2.5	<0.2
1281447	Soil	11	0.14	1515	0.002	5	0.58	0.002	0.11	<0.1	0.25	9.2	0.2	0.07	1	1.4	<0.2
1281448	Soil	8	0.02	385	<0.001	4	0.54	0.002	0.10	<0.1	1.29	4.3	0.3	0.07	1	3.3	<0.2
1281449	Soil	10	0.01	275	0.003	3	0.18	0.001	0.05	<0.1	0.07	1.2	<0.1	0.05	2	2.2	<0.2
1281450	Soil	16	0.04	101	0.004	5	0.41	0.004	0.08	0.1	0.21	2.4	0.2	0.10	3	1.8	0.2
1281501	Soil	31	0.03	93	0.003	4	0.44	0.002	0.07	<0.1	0.14	3.8	0.2	0.07	4	3.7	0.4
1281502	Soil	9	0.09	115	0.003	5	0.48	0.001	0.15	<0.1	0.04	3.7	<0.1	<0.05	3	<0.5	<0.2
1281503	Soil	16	0.20	92	0.008	3	0.85	0.003	0.07	0.1	0.07	1.5	0.2	0.05	3	1.2	<0.2
1281504	Soil	18	0.05	78	0.005	3	0.42	0.002	0.06	0.1	0.07	3.1	0.2	<0.05	5	3.1	0.4
1281505	Soil	12	0.07	54	0.009	2	0.52	0.013	0.05	<0.1	0.11	3.8	0.2	0.06	2	2.7	<0.2
1281506	Soil	20	0.22	101	0.028	4	0.85	0.017	0.09	0.1	0.07	5.3	0.3	0.07	3	2.6	<0.2
1281507	Soil	15	0.04	175	0.003	3	0.50	0.003	0.06	<0.1	0.10	0.5	0.3	<0.05	3	1.7	<0.2
1281508	Soil	10	0.10	1995	0.002	2	0.79	0.002	0.08	<0.1	0.05	5.7	<0.1	<0.05	2	0.9	<0.2
1281509	Soil	11	0.07	1159	0.002	3	0.57	0.003	0.11	<0.1	0.19	5.2	0.3	<0.05	2	1.3	<0.2
1281510	Soil	17	0.04	189	0.008	2	0.51	0.004	0.07	0.2	0.16	2.4	0.3	<0.05	4	1.6	0.2
1281511	Soil	24	0.09	148	0.008	3	0.88	0.010	0.08	<0.1	0.87	8.2	0.5	0.09	4	3.8	0.3
1281512	Soil	10	0.03	301	0.008	2	0.38	0.002	0.05	0.1	0.03	1.7	0.2	<0.05	3	1.1	<0.2
1281513	Soil	5	0.04	503	0.004	2	0.49	0.018	0.05	<0.1	0.08	1.0	0.1	<0.05	2	0.6	<0.2
1281514	Soil	11	0.07	814	0.006	2	0.77	0.003	0.08	<0.1	0.04	4.5	0.2	<0.05	3	0.7	<0.2
1281515	Soil	10	0.05	973	0.004	3	0.48	0.011	0.07	<0.1	0.11	3.1	0.2	<0.05	1	0.6	<0.2
1281516	Soil	5	0.05	1058	0.004	2	0.69	0.009	0.08	<0.1	0.06	2.9	0.1	0.06	2	<0.5	<0.2
1281517	Soil	14	0.11	182	0.010	1	0.83	0.004	0.06	0.1	0.02	0.8	0.2	<0.05	5	0.5	<0.2
1281518	Soil	9	0.06	234	0.004	2	0.73	0.006	0.07	<0.1	0.05	2.0	0.2	<0.05	3	0.7	<0.2
1281519	Soil	21	0.10	223	0.014	4	1.06	0.006	0.09	0.1	0.09	2.0	0.3	0.06	5	1.8	<0.2
1281520	Soil	10	0.02	68	0.004	2	0.31	0.016	0.03	<0.1	0.03	0.6	<0.1	<0.05	2	1.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281521	Soil	5.7	52.2	12.2	153	0.2	21.1	5.0	69	1.72	11.8	2.4	0.1	11	0.2	2.6	0.2	67	<0.01	0.055	10
1281522	Soil	9.5	77.0	14.2	174	0.2	29.8	5.6	92	2.37	25.1	2.8	0.6	10	0.2	5.5	0.3	136	0.01	0.050	10
1281523	Soil	6.3	46.4	17.2	134	2.5	25.8	6.9	283	3.00	21.4	6.9	2.6	33	0.6	4.2	0.2	82	0.11	0.166	11
1281524	Soil	7.7	57.5	14.5	105	0.2	21.8	4.7	75	1.92	18.0	2.8	0.2	11	0.2	3.6	0.3	116	0.02	0.062	11
1281525	Soil	8.3	38.3	25.0	106	0.3	21.3	4.0	77	1.70	15.9	3.7	1.1	25	0.1	3.8	0.3	99	0.01	0.048	10
1281526	Soil	6.8	38.6	23.5	88	1.0	22.2	4.9	169	2.52	21.0	7.7	0.8	39	0.2	3.8	0.3	73	0.03	0.151	9
1281527	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281528	Soil	1.4	12.2	7.3	21	0.5	5.0	1.4	88	0.68	4.0	3.9	0.1	11	<0.1	0.7	0.1	23	0.04	0.058	4
1281529	Soil	6.7	46.3	13.4	119	0.9	25.3	4.3	110	1.62	15.6	6.3	0.6	36	0.5	4.0	0.2	60	0.03	0.074	7
1281530	Soil	11.0	68.8	17.2	158	1.1	33.9	6.6	215	2.30	27.6	7.4	1.5	74	1.1	7.8	0.2	103	0.12	0.131	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001222.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281521	Soil	11	0.03	107	0.003	2	0.40	0.002	0.08	<0.1	0.02	0.4	0.2	<0.05	3	1.3	<0.2
1281522	Soil	12	0.04	90	0.004	3	0.49	0.003	0.07	0.1	0.03	1.4	0.2	<0.05	4	2.3	<0.2
1281523	Soil	28	0.21	200	0.013	2	1.33	0.006	0.07	0.2	0.21	2.4	0.3	0.06	3	3.1	<0.2
1281524	Soil	15	0.04	144	0.003	2	0.55	0.004	0.06	0.1	0.04	0.6	0.3	<0.05	5	1.5	<0.2
1281525	Soil	12	0.03	156	0.005	2	0.41	0.003	0.07	<0.1	0.02	1.2	0.3	0.05	3	2.3	<0.2
1281526	Soil	18	0.08	259	0.004	2	0.75	0.008	0.09	0.2	0.16	1.3	0.3	0.13	3	2.7	<0.2
1281527	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281528	Soil	7	0.05	221	0.004	1	0.34	0.015	0.04	<0.1	0.15	0.5	0.1	<0.05	1	0.6	<0.2
1281529	Soil	12	0.05	729	0.003	3	0.37	0.008	0.07	0.1	0.20	1.6	0.3	0.06	1	1.8	<0.2
1281530	Soil	19	0.09	1604	0.003	3	0.57	0.004	0.08	0.1	0.55	2.5	0.4	0.09	2	3.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

QUALITY CONTROL REPORT WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1280809	Soil	19.4	22.2	10.9	43	1.3	9.3	2.1	81	2.08	12.5	6.3	0.6	15	0.1	6.2	0.2	173	0.02	0.041	11
REP 1280809	QC	20.2	22.0	11.3	44	1.4	8.7	2.3	86	2.17	13.0	7.0	0.6	17	0.1	6.7	0.2	175	0.03	0.043	13
1280832	Soil	3.0	16.5	6.4	48	1.4	10.4	1.8	67	0.66	4.0	1.7	0.1	15	1.1	1.4	<0.1	26	0.05	0.087	2
REP 1280832	QC	2.9	16.1	6.4	47	1.4	10.1	1.9	65	0.62	3.8	1.1	<0.1	15	1.1	1.3	<0.1	25	0.05	0.081	2
1280847	Soil	6.4	79.3	20.0	207	0.2	50.9	19.2	456	4.53	16.0	4.6	0.8	25	0.9	2.4	0.3	41	0.22	0.088	7
REP 1280847	QC	6.2	80.6	19.8	207	0.2	49.1	19.1	448	4.51	15.8	4.1	0.8	25	1.1	2.2	0.3	40	0.21	0.086	7
1280778	Soil	1.3	55.7	7.7	56	0.5	17.4	6.3	273	1.77	5.1	8.5	0.8	49	0.2	0.7	0.1	38	1.15	0.126	13
REP 1280778	QC	1.4	54.6	7.8	55	0.5	17.2	6.4	274	1.78	5.0	10.3	0.9	50	0.2	0.8	0.1	40	1.14	0.123	13
1280791	Soil	4.6	33.4	10.8	41	3.3	13.2	3.2	122	2.01	23.7	10.0	0.3	32	0.2	4.2	0.2	66	0.06	0.117	7
REP 1280791	QC	4.9	37.5	12.2	46	3.7	14.6	3.9	135	2.27	26.3	10.5	0.3	35	0.2	4.6	0.2	70	0.07	0.127	7
1281105	Soil	4.9	45.6	8.6	104	0.1	22.8	6.4	89	2.16	9.4	4.5	0.2	9	0.1	1.9	0.2	54	<0.01	0.042	11
REP 1281105	QC	4.9	45.7	8.6	103	0.1	21.8	6.4	85	2.16	9.6	2.7	0.2	9	0.1	1.9	0.2	55	<0.01	0.043	11
1281116	Soil	0.3	1.9	1.0	5	0.4	1.0	0.4	11	0.15	<0.5	<0.5	<0.1	5	<0.1	<0.1	<0.1	5	0.02	0.021	<1
REP 1281116	QC	0.2	1.9	1.1	6	0.4	1.0	0.4	11	0.15	<0.5	0.5	<0.1	5	<0.1	<0.1	<0.1	6	0.02	0.023	<1
1281217	Soil	5.7	53.1	25.9	95	0.2	21.8	11.7	1468	4.31	21.6	2.0	0.5	11	0.4	2.5	0.4	79	0.04	0.232	13
REP 1281217	QC	5.1	51.2	26.0	92	0.2	21.5	11.6	1340	4.16	21.7	3.3	0.5	12	0.4	2.5	0.3	75	0.05	0.236	14
1281387	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1281387	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281406	Soil	8.2	34.3	25.5	21	3.2	7.1	2.2	77	2.11	20.9	3.9	2.0	73	0.1	5.3	0.4	70	0.04	0.080	6
REP 1281406	QC	8.1	33.3	24.2	22	3.2	6.5	2.1	79	2.14	21.8	4.8	2.1	72	0.1	4.9	0.4	70	0.03	0.082	5
1281417	Soil	6.7	16.4	13.4	50	0.7	11.0	3.0	98	1.95	15.1	5.8	0.4	14	0.1	3.1	0.2	66	0.02	0.045	7
REP 1281417	QC	6.8	15.2	12.7	47	0.7	10.6	2.8	95	1.95	14.7	4.5	0.4	13	0.1	3.0	0.2	68	0.02	0.043	7
1281432	Soil	9.1	49.8	16.7	50	3.7	15.0	2.1	93	2.29	92.2	31.2	0.7	129	0.2	8.4	0.4	74	0.02	0.130	2
REP 1281432	QC	9.4	52.1	17.0	52	3.8	15.6	2.2	97	2.45	94.0	35.5	0.7	132	0.3	8.9	0.4	74	0.02	0.134	2
1281519	Soil	7.9	45.2	31.2	139	0.3	34.4	6.1	178	3.62	38.4	9.4	1.1	34	0.3	4.8	0.4	89	0.02	0.068	8
REP 1281519	QC	8.3	47.1	31.1	149	0.2	36.4	6.3	186	3.66	39.9	9.3	1.2	34	0.2	5.0	0.4	91	0.02	0.065	9
Reference Materials																					
STD DS8	Standard	11.9	107.0	117.0	289	1.7	35.6	6.8	542	2.18	23.2	106.8	6.1	60	2.2	5.2	5.8	38	0.60	0.080	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

QUALITY CONTROL REPORT WHI11001222.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1280809	Soil	15	0.07	207	0.013	2	0.50	0.004	0.04	0.2	0.44	0.8	0.5	<0.05	3	5.6	<0.2
REP 1280809	QC	15	0.08	215	0.018	4	0.53	0.004	0.05	0.3	0.51	0.9	0.6	<0.05	3	5.6	<0.2
1280832	Soil	7	0.02	227	0.001	3	0.18	0.017	0.04	<0.1	0.14	0.2	0.2	<0.05	<1	1.7	<0.2
REP 1280832	QC	7	0.02	225	0.001	3	0.18	0.017	0.04	<0.1	0.13	0.2	0.2	<0.05	<1	1.8	<0.2
1280847	Soil	15	0.16	703	0.006	3	0.77	0.004	0.14	<0.1	0.13	2.7	0.2	0.06	3	1.2	<0.2
REP 1280847	QC	14	0.15	716	0.006	4	0.75	0.003	0.13	<0.1	0.13	2.6	0.2	<0.05	2	1.2	<0.2
1280778	Soil	20	0.56	179	0.007	3	1.18	0.016	0.08	<0.1	0.14	2.7	<0.1	0.10	4	1.3	<0.2
REP 1280778	QC	21	0.56	183	0.007	5	1.17	0.016	0.10	<0.1	0.17	2.8	<0.1	0.08	4	0.8	<0.2
1280791	Soil	17	0.19	347	0.012	2	1.02	0.011	0.07	0.1	0.34	1.0	0.3	0.10	3	4.7	<0.2
REP 1280791	QC	18	0.22	382	0.014	2	1.12	0.013	0.08	0.2	0.38	1.2	0.4	0.12	4	5.1	<0.2
1281105	Soil	8	0.03	116	0.005	3	0.36	0.006	0.08	0.1	0.03	0.5	0.1	<0.05	3	1.1	<0.2
REP 1281105	QC	8	0.04	117	0.005	3	0.37	0.006	0.08	0.1	0.03	0.5	0.1	<0.05	3	1.3	<0.2
1281116	Soil	3	<0.01	17	0.005	<1	0.08	0.016	0.02	<0.1	<0.01	0.4	<0.1	<0.05	<1	<0.5	<0.2
REP 1281116	QC	3	<0.01	17	0.005	<1	0.09	0.019	0.02	<0.1	<0.01	0.1	<0.1	<0.05	<1	<0.5	<0.2
1281217	Soil	24	0.11	126	0.009	3	0.93	0.006	0.08	0.1	0.05	1.2	0.2	<0.05	5	2.0	<0.2
REP 1281217	QC	24	0.12	129	0.014	4	0.96	0.007	0.08	0.2	0.04	1.3	0.2	<0.05	5	1.5	0.2
1281387	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1281387	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281406	Soil	24	0.10	544	0.009	3	0.48	0.011	0.21	<0.1	0.30	2.9	0.6	0.48	5	6.1	<0.2
REP 1281406	QC	24	0.09	526	0.012	4	0.48	0.011	0.20	<0.1	0.32	2.7	0.5	0.48	5	7.5	<0.2
1281417	Soil	16	0.11	379	0.011	<1	0.81	0.002	0.03	0.2	0.17	0.7	0.3	<0.05	4	2.4	<0.2
REP 1281417	QC	16	0.10	370	0.010	<1	0.78	0.002	0.03	0.2	0.16	0.7	0.3	<0.05	4	2.3	<0.2
1281432	Soil	15	0.02	717	0.001	1	0.30	0.002	0.12	<0.1	0.38	2.2	0.8	0.31	2	10.4	0.3
REP 1281432	QC	15	0.03	727	0.001	1	0.32	0.002	0.13	<0.1	0.37	2.3	0.9	0.32	2	10.3	0.3
1281519	Soil	21	0.10	223	0.014	4	1.06	0.006	0.09	0.1	0.09	2.0	0.3	0.06	5	1.8	<0.2
REP 1281519	QC	22	0.11	225	0.013	4	1.08	0.005	0.10	0.1	0.10	2.1	0.3	<0.05	5	1.9	<0.2
Reference Materials																	
STD DS8	Standard	107	0.55	237	0.113	2	0.81	0.084	0.37	2.8	0.18	2.3	4.9	0.15	4	4.4	4.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

QUALITY CONTROL REPORT WHI11001222.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	13.4	106.8	127.6	303	1.8	38.0	7.6	631	2.57	26.5	110.8	6.5	67	2.6	5.8	6.7	44	0.71	0.081	15
STD DS8	Standard	12.6	98.9	119.5	299	1.8	35.2	7.2	579	2.26	26.2	111.8	6.8	70	2.5	5.7	7.0	41	0.69	0.081	16
STD DS8	Standard	10.3	110.7	127.0	311	1.8	36.6	6.9	568	2.34	24.8	114.2	6.0	54	2.4	5.7	7.0	38	0.60	0.073	9
STD DS8	Standard	12.5	103.6	118.0	297	1.7	37.6	7.6	603	2.45	23.6	106.6	6.5	64	2.2	5.1	5.4	41	0.67	0.072	14
STD DS8	Standard	13.2	109.9	109.9	307	1.7	37.0	7.7	599	2.43	24.4	103.7	6.0	63	2.2	5.0	5.8	43	0.69	0.077	15
STD DS8	Standard	13.2	104.8	123.3	299	1.8	36.5	7.5	603	2.40	22.9	114.8	6.1	68	2.1	5.6	6.0	42	0.69	0.078	16
STD DS8	Standard	13.5	108.2	124.9	306	1.8	37.0	7.6	591	2.43	24.8	116.6	6.9	70	2.5	5.7	7.1	41	0.69	0.080	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

QUALITY CONTROL REPORT WHI11001222.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
STD DS8	Standard	120	0.60	283	0.119	3	0.91	0.099	0.44	3.2	0.21	3.4	5.7	0.11	5	5.3	5.2
STD DS8	Standard	110	0.56	293	0.118	3	0.88	0.102	0.42	3.0	0.20	2.8	5.1	0.16	5	5.9	4.6
STD DS8	Standard	108	0.56	251	0.094	2	0.76	0.068	0.38	3.0	0.21	1.6	5.4	0.14	4	4.9	4.8
STD DS8	Standard	116	0.60	247	0.111	4	0.88	0.085	0.38	2.8	0.20	2.1	5.2	0.14	4	5.2	4.6
STD DS8	Standard	117	0.60	278	0.111	2	0.92	0.093	0.41	2.9	0.20	2.5	5.2	0.15	5	4.6	5.4
STD DS8	Standard	117	0.61	275	0.112	2	0.90	0.085	0.41	2.8	0.21	2.0	5.5	0.15	5	5.2	5.1
STD DS8	Standard	117	0.58	279	0.116	3	0.89	0.098	0.45	3.2	0.20	2.2	5.5	0.17	5	5.6	4.8
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 14, 2011
Report Date: November 04, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001376.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #20
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve soil to 230 mesh			WHI
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	317	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Version 2: Revised sample ID's for 1280971 to 1280980

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094401	Soil	3.8	24.9	17.7	130	0.1	24.4	7.5	82	2.20	13.3	2.6	0.3	12	0.3	1.2	0.4	32	0.07	0.052	6
1094402	Soil	1.9	11.3	58.1	74	<0.1	8.8	2.1	31	1.89	9.8	1.9	0.9	7	0.2	4.0	0.3	15	0.07	0.019	3
1094403	Soil	2.2	7.6	14.2	30	<0.1	5.9	1.2	22	0.93	7.8	1.6	0.7	16	<0.1	0.6	0.3	22	0.02	0.025	2
1094404	Soil	20.8	17.6	24.2	81	0.4	16.4	2.5	70	1.64	23.1	2.1	<0.1	21	0.3	4.1	0.3	106	0.06	0.097	7
1094405	Soil	37.4	25.2	41.4	65	0.7	15.2	2.9	54	2.13	20.5	1.6	0.2	35	0.3	13.4	0.2	183	0.06	0.083	7
1094406	Soil	55.8	23.7	34.4	50	1.2	10.9	2.0	79	1.79	22.1	4.9	0.2	88	0.4	12.1	0.3	201	0.06	0.118	13
1094407	Soil	13.7	26.4	8.1	47	0.6	14.1	1.8	24	0.77	6.8	1.2	0.1	7	0.5	2.4	0.2	88	0.04	0.029	12
1094408	Soil	177.5	99.7	101.6	180	4.0	55.8	2.9	64	4.40	152.9	3.6	6.0	249	1.2	50.6	0.4	1597	0.08	0.392	10
1094409	Soil	75.9	38.4	198.0	455	0.7	84.6	2.6	60	2.26	36.2	1.7	0.1	49	0.9	21.3	0.2	636	0.02	0.128	17
1094410	Soil	100.5	48.9	15.9	517	1.1	120.9	2.7	26	1.87	33.1	1.1	<0.1	12	3.5	27.5	0.2	769	0.03	0.102	19
1094411	Soil	104.2	34.5	22.5	437	0.4	133.6	3.3	32	1.86	28.1	1.2	0.2	21	1.8	17.0	0.3	819	0.03	0.076	30
1094412	Soil	7.4	25.9	12.4	137	0.1	32.2	7.7	191	2.16	13.8	1.8	0.3	10	0.9	1.7	0.2	35	0.03	0.082	10
1094413	Soil	2.9	38.0	9.1	103	<0.1	45.0	14.5	113	3.50	35.5	1.2	1.3	6	0.2	2.4	0.3	35	0.05	0.064	7
1094414	Soil	4.4	34.7	10.3	72	<0.1	28.0	9.5	141	3.37	10.6	0.8	2.4	7	0.2	1.4	0.4	37	0.04	0.034	12
1094415	Soil	5.0	19.2	6.1	81	<0.1	22.3	6.7	143	2.15	14.9	1.5	1.3	4	<0.1	1.4	0.2	54	0.02	0.026	17
1094416	Soil	7.6	51.4	15.3	262	0.7	75.4	21.1	697	6.12	60.3	0.6	2.3	6	0.2	1.8	0.4	59	0.03	0.071	24
1094417	Soil	10.0	66.0	21.1	306	0.6	49.8	14.4	445	3.37	37.3	4.4	0.5	23	0.7	2.4	0.3	36	0.26	0.138	18
1094418	Soil	2.1	17.6	5.1	57	1.3	12.0	1.8	31	0.66	4.7	3.1	<0.1	12	0.6	0.5	<0.1	22	0.12	0.095	6
1094419	Soil	3.8	16.2	9.5	47	0.7	12.6	2.0	23	0.83	5.6	1.2	0.2	15	0.1	0.8	0.1	29	0.04	0.074	9
1094420	Soil	11.5	34.5	20.9	164	0.4	43.4	6.4	102	2.34	19.5	2.1	0.5	20	0.3	3.2	0.2	62	0.03	0.061	11
1094421	Soil	11.1	21.3	9.3	106	0.1	27.3	5.3	67	1.79	20.6	0.7	1.6	7	0.1	2.1	0.2	85	0.02	0.035	15
1094422	Soil	9.4	25.4	12.8	112	0.1	31.3	7.0	87	2.05	15.0	1.1	0.4	10	0.2	2.1	0.3	58	0.05	0.042	13
1094423	Soil	21.8	87.2	17.7	1125	1.8	180.8	8.9	193	3.15	19.3	6.8	2.3	61	5.5	4.1	0.3	136	0.58	0.140	13
1094424	Soil	22.9	40.4	22.1	236	0.5	49.7	6.7	222	2.71	24.7	4.5	1.3	30	1.0	5.8	0.3	228	0.07	0.120	13
1094425	Soil	13.0	45.0	16.5	206	1.0	42.4	6.3	189	2.42	16.9	5.0	1.7	30	1.1	3.4	0.2	133	0.21	0.153	14
1094426	Soil	6.6	20.8	10.3	93	0.9	25.3	3.0	44	1.20	6.9	2.7	0.2	16	0.5	1.7	0.1	52	0.07	0.093	5
1094427	Soil	6.8	21.7	13.4	72	0.2	19.4	2.9	46	1.31	6.5	1.2	0.3	13	0.3	1.2	0.2	57	0.03	0.097	12
1094428	Soil	10.3	17.0	31.1	84	0.3	20.5	2.9	30	1.07	11.1	1.1	<0.1	21	<0.1	2.1	0.2	58	0.01	0.038	12
1094429	Soil	14.4	27.3	37.9	122	0.7	30.4	4.2	89	2.43	22.1	1.5	0.2	26	0.4	3.1	0.3	123	0.06	0.226	10
1094430	Soil	8.4	46.1	10.3	248	1.7	46.6	4.5	195	1.90	12.3	4.5	0.9	27	2.0	2.5	0.2	77	0.25	0.094	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094401	Soil	11	0.06	124	0.003	1	0.52	0.005	0.04	<0.1	0.04	1.0	0.2	0.10	2	0.6	<0.2
1094402	Soil	6	0.04	113	<0.001	1	0.25	0.003	0.04	<0.1	0.05	1.0	0.1	<0.05	<1	0.7	<0.2
1094403	Soil	5	0.03	123	<0.001	2	0.31	0.002	0.04	<0.1	0.03	0.8	0.1	<0.05	<1	0.5	<0.2
1094404	Soil	14	0.04	173	0.002	1	0.54	0.008	0.05	0.2	0.06	0.2	0.7	<0.05	3	2.6	<0.2
1094405	Soil	16	0.05	328	0.003	2	0.38	0.005	0.11	0.5	0.08	0.5	2.7	0.26	4	9.3	<0.2
1094406	Soil	19	0.09	376	0.005	2	0.55	0.005	0.11	0.6	0.18	0.6	5.7	0.17	4	6.6	0.3
1094407	Soil	20	0.01	116	0.004	2	0.28	0.008	0.03	0.2	0.05	0.2	0.6	<0.05	2	2.2	<0.2
1094408	Soil	88	0.07	290	0.109	6	1.69	0.007	0.22	1.6	0.41	5.8	14.3	0.41	7	22.5	0.6
1094409	Soil	37	0.06	203	0.002	4	0.63	0.005	0.09	0.2	0.03	0.4	3.2	<0.05	4	7.7	<0.2
1094410	Soil	46	0.04	150	0.002	3	0.54	0.005	0.08	0.3	0.09	0.2	2.3	<0.05	5	9.2	0.2
1094411	Soil	48	0.06	127	0.003	4	0.64	0.005	0.09	0.5	0.05	0.5	3.1	<0.05	5	5.6	<0.2
1094412	Soil	10	0.07	480	0.003	3	0.62	0.008	0.06	<0.1	0.03	0.6	0.3	<0.05	2	0.8	<0.2
1094413	Soil	13	0.05	241	0.002	4	0.56	0.007	0.07	<0.1	0.03	2.1	0.2	<0.05	2	0.8	<0.2
1094414	Soil	11	0.06	497	0.005	2	0.67	0.003	0.10	0.1	0.02	1.9	0.2	<0.05	3	0.6	<0.2
1094415	Soil	9	0.04	113	0.005	2	0.50	0.002	0.06	0.1	0.01	1.0	0.2	<0.05	4	<0.5	<0.2
1094416	Soil	13	0.06	103	0.001	3	0.64	0.003	0.08	<0.1	0.04	3.1	0.2	<0.05	3	0.9	<0.2
1094417	Soil	13	0.08	354	0.003	4	0.46	0.007	0.11	<0.1	0.13	1.4	0.2	0.05	2	1.8	<0.2
1094418	Soil	9	0.05	357	<0.001	2	0.45	0.018	0.05	<0.1	0.17	0.2	0.2	<0.05	2	0.5	<0.2
1094419	Soil	9	0.04	444	0.002	2	0.49	0.009	0.06	<0.1	0.05	0.2	0.2	<0.05	2	0.6	<0.2
1094420	Soil	19	0.09	286	0.004	2	0.58	0.005	0.08	0.1	0.03	1.0	0.3	<0.05	3	1.7	<0.2
1094421	Soil	14	0.05	190	0.002	2	0.73	0.004	0.05	0.2	0.03	1.1	0.4	<0.05	5	0.6	<0.2
1094422	Soil	7	0.05	278	0.003	2	0.56	0.006	0.07	0.1	0.03	0.7	0.3	<0.05	3	0.8	<0.2
1094423	Soil	28	0.17	1522	0.002	5	1.10	0.006	0.14	<0.1	0.74	4.6	0.9	0.15	3	2.4	<0.2
1094424	Soil	26	0.12	1027	0.003	5	1.05	0.004	0.14	0.2	0.12	2.0	0.9	0.07	3	2.2	<0.2
1094425	Soil	25	0.20	1061	0.003	4	1.14	0.006	0.13	0.2	0.48	2.7	0.5	<0.05	3	1.7	<0.2
1094426	Soil	14	0.06	601	0.002	3	0.61	0.016	0.10	<0.1	0.21	0.6	0.3	<0.05	2	0.9	<0.2
1094427	Soil	13	0.05	433	0.002	2	0.77	0.005	0.08	0.1	0.05	0.4	0.2	<0.05	3	0.8	<0.2
1094428	Soil	8	0.02	133	0.003	2	0.36	0.003	0.07	0.1	0.02	0.2	0.3	<0.05	3	1.3	<0.2
1094429	Soil	19	0.08	164	0.003	2	0.77	0.005	0.07	0.2	0.03	0.3	0.3	<0.05	5	1.9	<0.2
1094430	Soil	19	0.13	914	0.002	4	1.18	0.016	0.13	0.1	0.59	2.1	0.4	0.06	3	1.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094431	Soil	19.5	33.8	12.4	260	0.6	45.2	4.1	125	1.70	22.7	2.7	0.4	33	2.2	4.8	0.2	141	0.52	0.200	8
1094432	Soil	23.1	67.8	16.8	310	0.3	56.2	8.9	70	2.61	28.3	2.7	0.4	28	1.8	5.7	0.2	118	0.38	0.141	9
1094433	Soil	49.2	82.3	16.3	584	1.3	123.1	6.2	162	1.74	42.1	4.1	0.9	57	5.8	13.5	0.2	226	0.81	0.132	15
1094434	Soil	31.8	49.0	9.1	292	0.3	88.8	5.8	274	1.47	36.8	2.2	0.8	42	3.9	7.8	0.1	172	1.01	0.083	14
1094435	Soil	20.5	30.5	6.3	122	0.2	58.7	4.6	306	1.18	12.2	0.6	0.2	195	1.9	3.3	<0.1	210	5.82	0.069	11
1094436	Soil	38.0	64.3	10.1	247	0.6	213.4	8.5	295	1.58	24.8	1.3	0.8	112	3.6	6.5	0.1	147	5.00	0.103	14
1094437	Soil	33.3	70.3	7.4	181	0.4	159.5	6.2	161	1.33	18.5	3.3	0.6	82	3.6	4.2	0.3	85	2.41	0.086	14
1094438	Soil	45.8	52.4	7.2	209	0.2	129.3	6.0	132	1.40	24.1	2.9	1.0	108	2.0	3.8	0.1	69	3.27	0.086	10
1094439	Soil	49.7	59.3	8.1	222	0.2	148.2	7.8	110	1.70	22.7	2.3	1.2	67	2.2	3.6	0.1	56	2.26	0.092	12
1094440	Soil	31.1	66.8	6.1	301	0.4	139.4	5.8	123	1.01	15.1	1.9	0.9	46	3.4	3.3	0.1	76	0.87	0.094	16
1094441	Soil	13.6	12.2	6.3	75	<0.1	16.6	1.6	18	0.60	7.8	<0.5	0.4	7	0.3	1.5	<0.1	72	0.07	0.059	9
1094442	Soil	59.7	57.7	10.4	556	0.5	155.3	7.2	150	1.76	47.3	1.9	1.2	92	5.6	7.3	0.1	153	2.58	0.119	9
1094443	Soil	13.1	16.5	12.3	109	<0.1	22.1	2.6	73	1.34	12.2	0.8	0.3	12	0.4	2.3	0.2	117	0.03	0.084	8
1094444	Soil	37.4	31.4	10.2	560	0.3	66.5	4.1	27	1.24	23.2	1.3	0.8	8	3.0	15.9	0.1	132	0.07	0.030	7
1094445	Soil	10.2	25.1	11.2	70	0.6	18.7	2.2	47	0.97	6.1	2.2	0.3	25	1.2	1.9	0.1	41	0.06	0.064	3
1094446	Soil	15.2	36.4	27.3	413	1.2	60.3	5.6	133	2.59	16.5	6.5	0.8	50	1.5	3.7	0.3	92	0.10	0.087	5
1094447	Soil	10.8	20.1	5.5	290	0.9	35.2	2.1	34	0.79	9.5	1.4	<0.1	39	4.5	3.3	0.1	110	0.65	0.053	5
1094448	Soil	11.2	21.4	12.6	88	0.1	22.8	3.7	53	1.28	11.6	0.7	0.3	10	0.1	2.2	0.2	80	0.01	0.037	7
1094449	Soil	11.1	14.2	12.8	81	0.2	17.8	2.3	28	0.99	11.4	0.6	<0.1	14	0.1	2.7	0.1	79	0.01	0.036	6
1094450	Soil	5.5	67.7	30.7	248	0.7	56.9	23.9	792	3.84	13.5	2.0	0.4	8	0.6	2.5	0.3	40	0.04	0.115	4
1094451	Soil	4.2	67.9	58.2	257	1.7	61.6	30.6	1396	4.03	13.4	3.6	1.0	10	0.8	2.6	0.4	38	0.06	0.097	6
1094452	Soil	7.1	13.9	16.9	60	0.3	12.5	2.8	58	1.45	13.4	0.6	0.1	14	0.1	1.8	0.3	72	0.02	0.038	9
1094453	Soil	9.9	19.5	21.7	72	0.6	16.6	3.2	64	1.63	13.0	1.6	0.2	19	0.3	2.5	0.4	66	0.02	0.068	4
1094454	Soil	5.9	36.1	19.5	68	0.7	17.7	3.8	111	1.56	10.8	1.8	<0.1	20	0.5	1.9	0.3	58	0.06	0.067	6
1094455	Soil	4.9	45.8	13.1	57	1.1	20.0	4.5	226	1.69	6.4	1.7	<0.1	30	0.8	1.1	0.2	63	0.38	0.102	6
1094456	Soil	5.0	9.8	12.2	31	0.4	7.0	1.5	48	0.67	6.3	<0.5	<0.1	13	0.2	1.2	0.1	39	0.01	0.038	3
1094457	Soil	9.8	37.1	63.1	52	2.2	13.4	2.6	152	1.49	14.3	3.3	0.2	44	0.6	2.9	0.4	80	0.03	0.105	6
1094458	Soil	8.0	13.3	35.9	56	1.3	11.8	2.5	63	1.71	15.6	1.6	1.2	22	0.2	2.6	0.3	82	0.02	0.032	8
1094459	Soil	6.1	15.7	18.5	87	0.6	15.6	3.4	75	2.55	23.5	1.0	0.9	12	0.4	2.2	0.2	81	0.01	0.070	6
1094460	Soil	12.6	24.6	37.5	93	1.7	25.8	3.5	47	1.67	25.8	2.8	0.9	21	0.2	3.7	0.2	72	0.01	0.043	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094431	Soil	17	0.11	906	0.002	4	0.65	0.010	0.08	<0.1	0.38	1.1	0.6	0.20	2	1.5	<0.2
1094432	Soil	12	0.06	1028	0.003	3	0.46	0.007	0.07	0.1	0.14	1.0	0.4	0.12	2	2.3	<0.2
1094433	Soil	21	0.08	479	0.004	4	0.57	0.009	0.06	0.2	0.94	3.0	1.4	0.19	2	3.7	<0.2
1094434	Soil	20	0.15	453	0.004	4	0.57	0.007	0.06	0.2	0.39	2.2	1.3	0.23	2	2.2	<0.2
1094435	Soil	19	2.67	400	0.004	4	0.47	0.013	0.04	0.1	0.20	1.4	1.3	0.22	2	1.8	<0.2
1094436	Soil	23	2.39	272	0.004	8	0.40	0.008	0.10	0.2	0.23	2.8	4.0	0.24	1	3.4	<0.2
1094437	Soil	20	0.58	390	0.003	6	0.44	0.009	0.06	0.2	0.37	2.0	1.5	0.31	<1	2.6	<0.2
1094438	Soil	16	1.24	350	0.003	6	0.33	0.006	0.07	0.2	0.22	2.6	1.5	0.22	<1	2.1	<0.2
1094439	Soil	13	0.77	323	0.003	4	0.37	0.006	0.05	0.1	0.20	2.8	1.1	0.26	<1	2.2	<0.2
1094440	Soil	22	0.14	391	0.003	5	0.39	0.003	0.07	0.2	0.27	3.6	1.4	0.23	<1	1.6	<0.2
1094441	Soil	11	0.05	120	0.002	3	0.55	0.004	0.04	0.1	0.04	0.5	0.3	0.13	3	0.5	<0.2
1094442	Soil	20	0.95	403	0.002	6	0.34	0.005	0.06	0.2	0.67	2.8	1.3	0.27	1	2.8	<0.2
1094443	Soil	16	0.06	225	0.002	2	0.78	0.004	0.05	0.1	0.04	0.5	0.4	0.16	4	0.7	<0.2
1094444	Soil	7	0.02	187	0.001	2	0.27	0.002	0.05	<0.1	0.27	0.9	0.3	0.06	1	2.7	<0.2
1094445	Soil	9	0.02	256	0.002	2	0.26	0.010	0.06	<0.1	0.09	1.2	0.3	0.14	1	0.9	<0.2
1094446	Soil	18	0.06	416	<0.001	6	0.60	0.004	0.12	<0.1	0.30	2.3	1.0	0.21	2	3.0	<0.2
1094447	Soil	11	0.03	347	0.003	2	0.37	0.015	0.04	<0.1	0.15	0.4	0.6	0.18	2	1.3	<0.2
1094448	Soil	9	0.02	103	0.002	2	0.31	0.002	0.04	<0.1	0.03	0.8	0.3	0.10	2	1.1	<0.2
1094449	Soil	7	0.01	114	0.002	2	0.26	0.003	0.03	0.1	0.02	0.3	0.4	0.07	2	1.2	<0.2
1094450	Soil	13	0.06	165	0.001	3	0.53	0.004	0.08	<0.1	0.06	2.6	0.3	0.12	2	1.2	<0.2
1094451	Soil	13	0.07	285	0.001	1	0.62	0.003	0.08	<0.1	0.10	5.1	0.4	0.06	2	1.4	<0.2
1094452	Soil	10	0.03	159	0.004	2	0.53	0.003	0.05	0.1	0.03	0.3	0.3	0.06	3	1.1	<0.2
1094453	Soil	11	0.03	205	0.002	2	0.51	0.003	0.05	<0.1	0.03	0.7	0.4	0.09	2	2.3	<0.2
1094454	Soil	13	0.05	281	0.003	1	0.62	0.004	0.05	<0.1	0.03	0.3	0.3	0.08	3	1.2	<0.2
1094455	Soil	18	0.05	578	<0.001	1	0.95	0.007	0.05	0.1	0.05	0.3	0.3	0.12	4	0.7	<0.2
1094456	Soil	6	0.01	121	0.002	<1	0.31	0.009	0.03	<0.1	0.01	0.2	0.2	<0.05	2	0.9	<0.2
1094457	Soil	20	0.04	352	0.001	2	0.87	0.007	0.08	0.1	0.08	0.9	0.6	0.11	4	3.5	<0.2
1094458	Soil	13	0.05	212	0.006	<1	0.61	0.003	0.05	0.1	0.05	1.0	0.4	<0.05	4	2.6	<0.2
1094459	Soil	14	0.05	161	0.003	<1	0.75	0.003	0.04	0.1	0.03	1.1	0.3	0.07	4	1.4	<0.2
1094460	Soil	10	0.02	161	0.001	1	0.34	0.002	0.05	<0.1	0.05	1.3	0.4	0.09	2	2.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094461	Soil	8.5	11.6	13.6	11	0.2	6.1	0.3	8	0.44	3.7	2.2	0.5	11	0.2	1.9	0.2	23	0.02	0.008	3
1094462	Soil	22.6	65.6	17.2	309	1.4	109.8	6.6	123	4.06	20.1	2.5	1.2	34	3.0	7.2	0.2	214	0.07	0.213	4
1094463	Soil	10.5	15.7	23.9	83	0.8	17.7	2.9	47	1.74	19.2	<0.5	0.4	37	0.2	3.3	0.3	114	0.03	0.102	4
1094464	Soil	3.3	25.8	16.3	66	1.2	17.0	3.0	101	1.54	8.5	2.2	0.4	41	0.5	1.3	0.2	49	0.13	0.114	5
1094465	Soil	4.5	9.3	14.6	47	0.3	9.6	2.6	142	1.77	14.3	<0.5	1.1	13	0.2	1.3	0.2	73	0.03	0.058	9
1094466	Soil	5.0	11.2	11.3	52	1.1	12.1	2.4	50	1.61	11.8	<0.5	0.8	12	0.1	1.4	0.1	52	0.02	0.059	6
1094467	Soil	7.5	14.7	32.7	74	2.7	16.9	2.9	57	1.98	16.9	0.6	0.8	26	0.4	2.7	0.2	87	0.03	0.087	7
1094468	Soil	12.4	33.9	28.6	116	1.8	35.6	6.6	231	2.37	14.4	5.5	0.4	51	0.8	2.7	0.2	68	0.52	0.118	4
1094469	Soil	15.9	31.4	18.2	176	0.6	45.9	4.0	62	1.59	17.4	2.3	0.7	44	0.8	3.3	0.1	72	0.21	0.076	9
1094470	Soil	23.1	38.0	21.8	197	1.0	52.6	7.7	147	2.15	20.2	2.9	1.3	34	1.0	4.1	0.2	121	0.08	0.077	8
1094471	Soil	18.5	26.8	17.5	183	0.7	34.0	8.0	257	2.09	15.7	3.4	0.9	24	0.7	4.4	0.2	82	0.11	0.080	9
1094472	Soil	3.9	21.6	9.0	82	0.7	18.6	3.3	74	0.90	5.6	0.8	<0.1	15	2.1	1.0	0.1	31	0.05	0.072	4
1094473	Soil	8.2	23.5	16.3	310	0.1	37.4	6.1	143	2.18	16.7	1.1	0.4	35	4.2	2.4	0.4	88	0.12	0.064	5
1094474	Soil	5.0	27.9	11.5	146	0.2	32.6	7.8	232	2.13	15.2	3.6	0.9	48	0.9	1.9	0.2	39	0.67	0.064	4
1094475	Soil	5.5	34.8	15.1	179	0.2	37.1	11.1	215	2.64	18.1	3.8	1.7	31	0.9	2.0	0.2	39	0.17	0.078	6
1094476	Soil	3.6	24.1	10.3	100	0.9	33.8	8.3	895	1.86	8.8	4.7	0.7	87	1.9	1.7	0.2	29	1.56	0.087	4
1094477	Soil	5.7	32.6	14.5	173	0.1	34.1	7.5	163	2.71	18.8	2.2	1.9	31	0.7	2.3	0.2	40	0.10	0.079	6
1094478	Soil	4.9	23.9	12.9	121	0.1	24.7	5.2	102	2.64	20.2	3.0	1.2	15	0.4	1.8	0.2	46	0.03	0.060	5
1094479	Soil	5.2	30.7	13.7	151	0.2	34.8	7.0	147	2.37	18.3	4.8	1.2	31	0.8	1.8	0.2	40	0.10	0.067	5
1094480	Soil	5.2	30.2	12.8	147	0.2	28.7	5.0	112	2.36	18.1	2.0	1.1	25	0.6	1.9	0.2	43	0.03	0.073	5
1094481	Soil	4.3	21.1	11.7	73	0.4	20.5	3.7	58	1.73	13.6	3.0	0.7	39	0.5	1.1	0.2	33	0.22	0.068	3
1094482	Soil	3.5	12.0	12.1	52	0.2	15.7	2.6	45	1.16	7.4	1.3	0.6	29	0.2	0.8	0.1	25	0.06	0.029	2
1094483	Soil	2.1	20.8	9.6	85	0.3	18.5	5.2	106	1.82	13.4	1.1	1.2	71	0.3	1.0	0.2	32	0.56	0.041	4
1094484	Soil	2.1	16.5	11.3	85	0.1	20.3	5.9	92	2.08	12.7	2.9	1.1	36	0.3	0.8	0.2	33	0.25	0.031	3
1094485	Soil	2.2	13.6	11.6	61	0.2	15.9	4.7	114	1.53	11.1	2.4	0.9	46	0.1	1.0	0.2	33	0.40	0.038	4
1094486	Soil	0.9	12.9	4.8	23	0.6	9.8	1.9	69	0.86	3.6	2.2	0.3	53	0.2	0.4	0.1	14	0.50	0.056	3
1094487	Soil	0.7	23.8	9.6	35	0.8	14.5	1.7	30	1.41	4.7	3.8	1.0	69	0.2	0.3	0.2	25	0.72	0.072	4
1094488	Soil	2.1	21.4	11.2	53	0.8	19.4	7.3	215	1.86	8.2	6.5	0.8	66	0.2	0.5	0.4	32	0.60	0.077	4
1094489	Soil	3.2	18.8	9.0	96	0.4	22.9	10.7	348	2.07	10.4	1.7	1.1	59	0.5	1.1	0.1	30	0.40	0.067	4
1094490	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094461	Soil	4	<0.01	513	<0.001	4	0.26	0.003	0.05	<0.1	0.16	0.8	0.5	<0.05	<1	1.3	<0.2
1094462	Soil	16	0.03	1726	0.003	2	1.07	0.002	0.05	0.1	0.11	2.8	0.5	0.11	2	6.3	<0.2
1094463	Soil	13	0.03	807	0.002	2	0.49	0.003	0.07	0.1	0.03	0.8	0.6	<0.05	3	2.8	<0.2
1094464	Soil	15	0.09	1632	0.001	2	0.80	0.007	0.05	<0.1	0.40	1.1	0.3	0.12	2	1.9	<0.2
1094465	Soil	12	0.07	169	0.005	<1	0.74	0.004	0.04	0.1	0.02	0.9	0.2	<0.05	4	0.8	<0.2
1094466	Soil	10	0.04	147	0.003	<1	0.67	0.006	0.03	<0.1	0.04	0.8	0.2	<0.05	3	0.8	<0.2
1094467	Soil	12	0.05	175	0.004	<1	0.59	0.004	0.04	0.1	0.06	1.1	0.3	<0.05	3	1.4	<0.2
1094468	Soil	12	0.05	957	<0.001	3	0.68	0.008	0.06	<0.1	0.47	1.6	1.0	0.16	2	4.9	<0.2
1094469	Soil	16	0.06	799	0.001	3	0.44	0.004	0.06	<0.1	0.13	1.5	0.4	0.07	2	1.9	<0.2
1094470	Soil	22	0.09	1050	0.001	6	0.80	0.004	0.08	<0.1	0.25	2.6	0.6	<0.05	2	2.9	<0.2
1094471	Soil	16	0.15	530	0.002	2	0.68	0.004	0.06	0.2	0.20	1.4	0.4	<0.05	2	1.7	<0.2
1094472	Soil	8	0.03	462	0.002	2	0.47	0.015	0.05	<0.1	0.07	0.3	0.2	<0.05	2	0.7	<0.2
1094473	Soil	17	0.08	499	0.002	2	0.66	0.006	0.06	<0.1	0.03	1.0	0.2	<0.05	2	0.7	<0.2
1094474	Soil	15	0.18	726	0.001	2	0.66	0.007	0.05	<0.1	0.08	1.6	<0.1	<0.05	2	1.4	<0.2
1094475	Soil	17	0.19	1073	0.001	2	0.71	0.005	0.06	<0.1	0.10	2.4	0.1	<0.05	2	0.8	<0.2
1094476	Soil	17	0.21	1089	0.002	3	0.85	0.013	0.05	<0.1	0.15	1.7	0.1	0.13	2	2.9	<0.2
1094477	Soil	16	0.20	1264	0.001	2	0.70	0.003	0.05	<0.1	0.04	2.2	0.2	0.05	2	1.3	<0.2
1094478	Soil	15	0.14	466	<0.001	1	0.83	0.005	0.05	<0.1	0.03	1.5	0.1	<0.05	3	0.6	<0.2
1094479	Soil	17	0.17	1331	<0.001	1	0.74	0.006	0.08	0.1	0.06	1.8	0.1	0.05	2	0.6	<0.2
1094480	Soil	15	0.14	996	0.001	2	0.75	0.006	0.06	<0.1	0.03	1.5	0.1	0.06	2	0.7	<0.2
1094481	Soil	14	0.14	1046	<0.001	1	0.69	0.008	0.07	<0.1	0.10	1.2	<0.1	0.07	2	0.9	<0.2
1094482	Soil	16	0.06	635	<0.001	2	0.52	0.014	0.05	<0.1	0.05	0.8	0.1	0.05	2	<0.5	<0.2
1094483	Soil	13	0.21	630	0.003	2	0.72	0.008	0.04	0.1	0.03	1.7	<0.1	<0.05	2	0.9	<0.2
1094484	Soil	17	0.22	287	<0.001	1	0.82	0.005	0.05	<0.1	0.03	1.5	<0.1	<0.05	2	0.7	<0.2
1094485	Soil	11	0.19	379	0.002	2	0.72	0.008	0.04	<0.1	0.05	1.2	<0.1	<0.05	2	0.6	<0.2
1094486	Soil	7	0.11	465	0.003	2	0.52	0.026	0.03	<0.1	0.11	1.1	<0.1	0.07	1	0.9	<0.2
1094487	Soil	13	0.20	820	0.001	1	0.90	0.006	0.05	<0.1	0.26	2.1	0.1	0.08	2	1.1	<0.2
1094488	Soil	14	0.20	506	0.002	1	0.98	0.013	0.06	0.1	0.17	2.6	0.1	0.10	2	0.9	<0.2
1094489	Soil	13	0.20	995	0.001	1	0.72	0.013	0.04	<0.1	0.10	1.8	<0.1	0.06	2	1.2	<0.2
1094490	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094491	Soil		6.4	87.1	37.2	98	2.0	51.3	15.0	465	2.77	20.1	3.7	1.4	73	0.6	3.7	0.4	63	0.19	0.097	5
1094492	Soil		8.8	67.4	29.7	233	1.8	56.5	16.9	415	2.33	18.5	3.6	1.4	46	0.8	3.8	0.4	94	0.30	0.076	6
1094493	Soil		9.8	93.3	44.0	279	1.9	58.0	13.8	345	2.80	40.3	2.6	1.8	96	1.8	4.7	0.4	103	0.20	0.125	5
1094494	Soil		150.1	140.7	10.3	4575	4.5	472.2	4.4	66	1.56	103.6	1.5	0.8	128	39.6	46.7	0.2	1882	1.79	0.166	16
1094495	Soil		210.0	220.7	20.0	>10000	6.6	929.3	18.0	313	2.16	158.9	1.4	2.4	259	64.6	74.4	0.2	3181	4.73	0.293	17
1094496	Soil		239.3	301.8	24.4	>10000	8.8	1012	23.4	436	2.88	215.2	1.9	3.3	192	97.2	106.9	0.3	4471	1.65	0.390	22
1094497	Soil		70.7	71.4	14.0	440	0.7	192.9	7.6	206	4.82	40.3	0.8	2.0	226	3.2	10.4	0.1	177	8.49	0.084	9
1094498	Soil		52.8	85.6	12.1	931	0.9	216.1	6.4	210	2.01	41.7	<0.5	0.3	133	9.1	11.2	0.1	244	4.55	0.117	9
1094499	Soil		79.6	121.7	15.6	1306	1.4	262.4	9.9	294	2.36	64.2	0.9	0.6	214	10.2	20.3	0.1	232	7.20	0.107	9
1094500	Soil		18.5	720.9	52.4	1064	1.4	239.4	19.6	292	3.61	93.4	7.3	5.0	50	9.4	8.5	0.5	81	0.35	0.222	8
1280971	Soil		4.3	29.8	13.6	126	0.5	26.0	8.2	485	1.90	13.5	3.9	1.8	46	0.6	2.0	0.2	54	0.65	0.096	11
1280972	Soil		2.9	31.2	11.7	117	0.3	20.7	6.1	261	1.65	10.4	3.6	1.5	39	0.9	1.5	0.2	49	0.53	0.095	10
1280973	Soil		3.2	33.9	13.6	146	0.6	26.4	7.9	376	2.11	12.6	4.8	2.5	48	0.8	1.5	0.2	59	0.56	0.112	12
1280974	Soil		2.8	29.1	7.4	159	1.7	25.5	3.5	120	1.24	8.5	7.3	0.6	31	1.4	1.6	0.1	37	0.31	0.068	5
1280975	Soil		22.1	65.3	31.2	371	1.2	39.9	4.1	98	3.91	54.4	8.3	1.3	39	0.6	13.9	0.3	172	0.05	0.144	6
1280976	Soil		7.3	33.7	16.2	95	0.6	26.0	10.6	455	2.28	18.9	3.4	1.5	29	1.1	1.9	0.2	61	0.21	0.089	6
1280977	Soil		3.6	38.1	12.2	102	1.0	28.0	4.5	153	1.68	13.5	1.8	0.9	33	1.3	1.4	0.2	51	0.26	0.092	5
1280978	Soil		12.2	36.8	13.9	147	1.1	33.8	13.3	2310	2.73	18.9	3.0	1.1	39	2.0	2.0	0.2	64	0.30	0.111	5
1280979	Soil		15.6	33.4	10.8	186	0.7	41.0	7.9	373	1.73	14.8	2.1	1.0	51	2.4	2.3	0.4	62	0.75	0.099	6
1280980	Soil		37.1	43.0	12.1	404	1.0	103.3	8.0	220	1.73	22.8	2.8	1.9	71	4.3	6.6	0.3	115	1.25	0.129	8
1280981	Soil		14.5	36.4	12.5	204	0.5	58.2	6.7	183	1.88	17.1	2.8	1.0	68	1.8	2.4	0.3	66	1.21	0.078	7
1280982	Soil		11.8	41.9	9.8	280	0.5	75.0	6.6	211	1.66	14.5	1.8	0.9	65	1.9	2.8	0.2	63	1.09	0.089	6
1280983	Soil		1.8	116.4	16.0	156	3.5	248.1	7.7	173	1.66	21.0	5.1	1.3	96	3.1	5.1	0.3	92	0.89	0.336	16
1280984	Soil		4.2	70.1	11.4	47	1.4	27.9	2.1	34	0.84	8.0	1.1	0.1	26	1.8	1.2	0.2	46	0.13	0.097	11
1280985	Soil		9.6	23.6	20.0	111	0.6	34.5	5.7	141	2.43	29.9	2.1	0.6	30	0.8	4.6	0.2	117	0.08	0.106	9
1280986	Soil		7.2	28.5	11.8	73	1.7	36.3	4.4	62	1.91	21.0	2.5	0.2	35	0.4	3.0	<0.1	63	0.06	0.116	6
1280987	Soil		12.0	27.2	21.0	155	3.0	42.7	5.9	147	3.54	46.4	4.7	3.3	45	0.6	4.1	0.2	111	0.13	0.340	11
1280988	Soil		4.7	13.0	12.7	59	0.7	15.2	2.1	49	1.33	16.7	<0.5	0.1	18	0.3	1.3	0.2	59	0.04	0.116	8
1280989	Soil		10.8	46.6	19.4	169	0.7	54.4	9.3	300	2.61	66.5	4.7	1.6	28	0.4	5.1	0.2	39	0.33	0.086	12
1280990	Soil		5.9	24.8	15.4	116	0.9	26.7	5.2	117	2.83	21.5	4.2	2.1	23	0.5	2.2	0.2	79	0.10	0.099	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094491	Soil	17	0.06	669	<0.001	1	0.42	0.004	0.09	<0.1	0.13	6.5	0.4	0.16	1	3.4	<0.2
1094492	Soil	15	0.11	566	<0.001	3	0.40	0.003	0.09	<0.1	0.17	5.8	0.4	0.09	1	2.8	<0.2
1094493	Soil	20	0.05	921	<0.001	2	0.40	0.005	0.10	<0.1	0.15	4.7	0.6	0.21	1	4.5	<0.2
1094494	Soil	81	0.17	695	0.004	9	0.82	0.007	0.16	0.4	1.11	3.3	6.7	0.09	3	16.4	0.2
1094495	Soil	130	0.40	1072	0.012	20	1.12	0.004	0.27	0.6	1.48	5.8	11.5	0.13	5	28.0	0.3
1094496	Soil	168	0.36	1305	0.034	23	1.42	0.006	0.33	0.8	1.57	8.9	15.5	0.11	7	39.3	0.6
1094497	Soil	17	2.77	293	0.003	5	0.24	0.008	0.06	0.1	0.99	2.7	2.7	<0.05	<1	7.1	<0.2
1094498	Soil	25	1.19	378	0.002	6	0.26	0.007	0.07	0.2	0.98	1.7	2.2	0.11	<1	6.7	<0.2
1094499	Soil	19	2.09	389	0.001	4	0.25	0.006	0.06	0.2	0.68	2.0	2.7	0.07	<1	7.1	<0.2
1094500	Soil	30	0.07	240	0.002	2	1.84	0.003	0.08	<0.1	0.98	11.1	0.6	0.08	2	3.7	0.3
1280971	Soil	18	0.32	822	0.008	4	0.87	0.014	0.09	0.2	0.19	2.1	0.1	<0.05	2	1.1	<0.2
1280972	Soil	17	0.32	666	0.005	2	0.83	0.013	0.09	0.2	0.15	1.5	0.1	<0.05	3	0.9	<0.2
1280973	Soil	18	0.37	856	0.003	2	1.02	0.008	0.08	0.2	0.28	2.3	0.1	<0.05	3	1.3	<0.2
1280974	Soil	11	0.13	988	0.003	1	0.58	0.016	0.05	<0.1	0.57	1.3	0.2	<0.05	2	0.9	<0.2
1280975	Soil	27	0.07	880	0.005	2	0.47	0.004	0.09	0.3	0.28	1.8	0.6	0.10	3	6.0	<0.2
1280976	Soil	17	0.13	694	0.001	1	0.77	0.006	0.05	0.1	0.24	2.2	0.2	<0.05	2	1.1	<0.2
1280977	Soil	14	0.12	748	0.001	1	0.80	0.008	0.05	<0.1	0.30	1.8	0.1	0.05	2	1.7	<0.2
1280978	Soil	17	0.12	860	0.001	<1	0.85	0.008	0.05	0.1	0.25	2.2	0.3	0.05	2	2.1	<0.2
1280979	Soil	18	0.18	1179	0.003	2	0.81	0.008	0.06	0.2	0.22	2.1	0.2	0.07	2	1.2	<0.2
1280980	Soil	26	0.13	627	0.003	4	0.56	0.006	0.07	0.2	0.45	3.5	0.6	0.06	1	2.7	<0.2
1280981	Soil	18	0.19	1035	0.003	2	0.81	0.006	0.05	0.2	0.24	2.3	0.3	<0.05	2	1.2	<0.2
1280982	Soil	14	0.14	838	0.003	3	0.78	0.010	0.05	0.2	0.24	2.0	0.3	<0.05	2	1.4	<0.2
1280983	Soil	26	0.12	968	0.006	2	1.21	0.007	0.06	0.2	2.41	2.5	0.5	0.08	2	6.4	<0.2
1280984	Soil	17	0.03	556	0.005	2	0.47	0.007	0.04	0.2	0.22	0.5	0.2	<0.05	2	0.6	0.2
1280985	Soil	23	0.11	467	0.005	2	0.81	0.004	0.05	0.2	0.31	1.2	0.2	<0.05	3	1.9	<0.2
1280986	Soil	19	0.05	554	0.005	2	0.74	0.013	0.07	0.1	0.62	1.3	0.2	<0.05	2	1.7	0.2
1280987	Soil	28	0.11	273	0.005	2	1.12	0.005	0.08	0.2	0.29	2.2	0.3	<0.05	3	2.1	<0.2
1280988	Soil	12	0.04	229	0.009	1	0.61	0.006	0.05	0.1	0.06	0.4	0.2	<0.05	3	0.8	<0.2
1280989	Soil	15	0.06	930	0.006	5	0.55	0.006	0.11	<0.1	0.54	3.0	0.2	<0.05	2	1.0	<0.2
1280990	Soil	24	0.18	682	0.005	2	1.25	0.004	0.08	0.2	0.27	1.9	0.2	<0.05	4	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281031	Soil	3.2	17.7	6.5	45	0.3	12.2	4.0	99	1.62	6.3	<0.5	0.2	6	0.1	1.4	0.1	55	0.02	0.034	5
1281032	Soil	5.5	14.5	7.0	59	0.4	12.5	3.0	50	1.25	7.5	<0.5	0.2	7	0.1	2.0	0.1	71	0.01	0.030	11
1281033	Soil	8.6	34.3	15.8	86	0.8	18.7	3.2	51	1.60	14.0	<0.5	<0.1	17	0.4	3.0	0.2	75	0.02	0.068	8
1281034	Soil	7.4	34.0	17.0	156	0.4	40.9	6.8	117	2.09	20.9	2.4	1.1	44	0.5	4.9	0.2	49	0.22	0.122	8
1281035	Soil	11.1	30.8	19.0	203	2.2	86.4	9.5	289	2.04	19.6	2.9	0.8	49	0.9	4.1	0.2	57	0.40	0.082	5
1281036	Soil	2.2	33.1	13.1	169	0.9	180.7	3.2	39	0.96	10.7	3.3	0.4	61	3.0	2.7	0.1	21	0.90	0.074	4
1281037	Soil	4.9	17.3	17.2	119	0.1	24.3	6.0	125	3.50	17.8	0.5	1.2	18	0.3	2.4	0.2	60	0.20	0.057	6
1281038	Soil	10.0	32.1	15.6	207	0.7	23.4	2.5	45	1.56	19.3	0.5	0.1	10	1.3	4.0	0.1	88	0.07	0.081	4
1281039	Soil	84.0	112.3	17.3	4587	1.0	404.9	8.5	196	2.63	56.4	2.6	3.5	86	57.3	33.0	0.2	420	3.23	0.121	29
1281040	Soil	12.0	62.0	25.7	605	1.9	89.8	6.7	266	3.63	25.6	8.2	0.8	37	3.7	7.1	0.2	147	0.13	0.185	7
1281671	Soil	5.7	65.7	15.6	177	1.1	32.3	5.1	150	2.57	23.5	10.0	3.0	52	1.6	4.0	0.2	78	0.73	0.124	12
1281672	Soil	2.7	45.1	7.4	161	0.8	33.2	8.5	375	1.52	9.3	6.0	0.8	48	1.3	2.3	<0.1	44	0.88	0.113	7
1281673	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281674	Soil	3.1	45.0	8.7	161	0.8	23.4	5.3	324	1.62	10.8	4.3	2.0	63	0.8	2.4	0.2	52	1.00	0.128	10
1281675	Soil	3.7	56.4	13.6	240	1.1	39.9	6.9	218	2.18	15.0	7.7	2.1	78	1.5	2.5	0.2	65	1.35	0.148	12
1281676	Soil	4.6	64.0	17.7	170	0.7	35.4	11.8	361	3.54	30.6	7.6	4.5	59	1.3	2.7	0.3	57	0.79	0.170	19
1281677	Soil	3.1	38.7	14.5	142	0.3	24.4	10.6	337	2.95	20.4	3.4	4.6	50	0.7	2.0	0.2	48	0.62	0.179	18
1281678	Soil	2.8	48.7	15.1	170	0.9	29.3	8.1	369	2.36	13.1	6.9	3.1	61	0.8	1.8	0.2	69	0.71	0.164	16
1281679	Soil	9.2	42.2	18.1	207	2.0	30.2	4.9	196	3.23	37.6	9.4	1.7	27	0.5	6.0	0.2	115	0.10	0.153	8
1281680	Soil	3.8	30.5	16.1	131	0.3	28.4	8.4	170	2.80	17.9	1.3	1.6	30	0.4	1.5	0.2	36	0.07	0.069	4
1281681	Soil	3.7	18.4	16.5	106	0.5	24.5	16.2	458	2.81	12.5	3.1	1.7	54	0.5	1.0	0.2	38	0.40	0.081	3
1281682	Soil	1.7	18.6	12.4	71	0.5	18.1	5.3	94	2.03	9.3	2.1	1.0	21	0.3	0.6	0.1	30	0.08	0.056	3
1281683	Soil	1.8	14.3	10.7	45	<0.1	8.1	2.4	49	1.22	9.9	0.8	0.3	11	0.1	0.5	0.1	31	0.02	0.052	4
1281684	Soil	2.2	15.3	11.1	82	<0.1	15.7	4.9	72	2.69	14.7	1.1	1.0	10	0.1	0.9	0.1	37	0.01	0.036	4
1281685	Soil	2.7	28.7	14.9	109	0.1	25.3	7.7	143	2.72	17.6	<0.5	1.8	25	0.3	1.2	0.3	32	0.04	0.054	5
1281686	Soil	1.6	26.0	10.5	84	0.3	23.5	4.0	74	1.45	7.8	1.1	0.7	48	0.1	0.5	0.2	22	0.22	0.033	2
1281687	Soil	1.6	18.6	15.8	58	0.7	20.1	3.2	26	1.43	9.4	2.0	1.1	77	0.3	0.5	0.3	30	0.25	0.066	3
1281688	Soil	1.9	19.2	9.2	48	0.4	19.7	12.0	471	1.73	8.6	0.8	0.6	91	0.4	0.7	0.2	22	0.79	0.062	2
1281689	Soil	1.9	20.7	13.8	77	0.4	22.9	8.3	175	2.14	10.7	3.2	1.3	59	0.4	0.6	0.2	30	0.34	0.055	3
1281690	Soil	2.4	18.8	14.9	86	0.3	19.5	6.2	67	2.99	13.9	1.6	1.8	27	0.2	0.9	0.2	34	0.10	0.053	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281031	Soil	7	0.02	62	0.007	<1	0.50	0.009	0.02	0.1	0.03	0.7	0.1	<0.05	3	0.8	<0.2
1281032	Soil	9	0.01	82	0.008	<1	0.34	0.005	0.03	0.2	0.02	0.5	<0.1	<0.05	3	0.6	<0.2
1281033	Soil	11	0.01	188	0.010	1	0.61	0.004	0.03	0.1	0.02	0.3	<0.1	<0.05	3	1.0	<0.2
1281034	Soil	14	0.11	1038	0.005	2	0.61	0.005	0.06	0.1	0.11	1.6	0.3	<0.05	2	1.1	<0.2
1281035	Soil	18	0.13	1247	0.002	2	1.07	0.015	0.11	<0.1	0.47	2.5	0.5	<0.05	3	2.5	0.2
1281036	Soil	9	0.15	999	0.003	3	0.59	0.019	0.05	<0.1	0.34	1.6	0.2	0.11	1	3.9	<0.2
1281037	Soil	20	0.12	139	0.003	<1	1.05	0.004	0.05	0.1	0.02	1.8	0.1	<0.05	5	1.0	<0.2
1281038	Soil	12	0.05	126	0.002	2	0.38	0.009	0.05	0.1	0.11	0.6	0.3	0.07	2	2.9	<0.2
1281039	Soil	22	1.63	325	0.003	5	0.23	0.005	0.08	0.3	2.99	4.3	2.8	0.14	<1	19.1	<0.2
1281040	Soil	37	0.08	486	0.005	5	0.94	0.009	0.14	0.1	0.61	2.9	0.5	0.09	4	3.4	<0.2
1281671	Soil	24	0.29	954	0.004	4	1.13	0.005	0.13	0.1	0.60	3.5	0.3	0.09	3	3.4	<0.2
1281672	Soil	13	0.19	669	0.007	3	0.78	0.020	0.08	0.1	0.38	1.6	0.2	0.09	2	2.7	<0.2
1281673	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281674	Soil	17	0.33	1010	0.010	6	0.90	0.011	0.12	0.2	0.43	2.4	0.3	0.08	2	2.1	<0.2
1281675	Soil	23	0.40	1026	0.005	5	1.11	0.006	0.14	0.2	0.61	3.1	0.3	0.08	3	2.2	<0.2
1281676	Soil	20	0.55	1161	0.006	4	1.11	0.006	0.15	0.5	0.46	4.0	0.2	0.06	3	3.3	<0.2
1281677	Soil	17	0.54	1012	0.005	4	1.03	0.005	0.14	0.4	0.25	3.0	0.1	0.06	3	1.6	<0.2
1281678	Soil	24	0.45	892	0.006	4	1.26	0.005	0.18	0.2	0.45	3.4	0.3	0.05	4	1.5	<0.2
1281679	Soil	22	0.11	742	0.005	2	0.76	0.004	0.06	0.2	0.67	1.9	0.5	0.08	3	3.1	<0.2
1281680	Soil	20	0.18	966	0.004	2	0.90	0.003	0.06	<0.1	0.09	2.4	0.1	0.08	3	1.8	<0.2
1281681	Soil	20	0.26	784	0.001	1	1.07	0.009	0.06	<0.1	0.12	2.6	0.1	0.09	3	1.4	<0.2
1281682	Soil	15	0.15	651	0.001	2	1.01	0.012	0.06	<0.1	0.13	2.2	0.1	0.10	3	1.1	<0.2
1281683	Soil	9	0.03	155	0.002	1	0.56	0.006	0.04	<0.1	0.03	0.6	<0.1	0.06	4	0.7	<0.2
1281684	Soil	12	0.08	257	0.002	<1	0.91	0.004	0.04	<0.1	0.04	1.5	<0.1	0.06	3	0.8	<0.2
1281685	Soil	17	0.16	1082	0.001	3	0.81	0.003	0.04	<0.1	0.06	2.3	<0.1	<0.05	2	1.8	<0.2
1281686	Soil	11	0.10	389	0.005	2	0.69	0.016	0.05	<0.1	0.10	2.0	0.1	<0.05	2	0.7	<0.2
1281687	Soil	14	0.13	1284	<0.001	2	0.92	0.008	0.05	<0.1	0.19	2.1	0.1	0.08	2	1.5	<0.2
1281688	Soil	11	0.14	553	0.002	3	0.67	0.016	0.03	<0.1	0.11	1.4	<0.1	0.09	2	1.4	<0.2
1281689	Soil	16	0.16	722	<0.001	2	0.92	0.006	0.05	<0.1	0.12	2.1	<0.1	<0.05	3	1.5	<0.2
1281690	Soil	18	0.17	1018	<0.001	2	0.84	0.003	0.04	<0.1	0.09	1.9	<0.1	<0.05	3	1.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281691	Soil	2.2	14.8	12.8	47	0.4	15.6	4.3	80	2.46	12.8	2.9	0.7	43	0.4	0.5	0.2	30	0.28	0.071	2
1281692	Soil	1.0	12.6	8.9	26	1.1	10.3	2.0	23	0.80	4.9	1.8	0.3	37	0.4	0.6	0.1	14	0.24	0.057	2
1281693	Soil	1.9	15.4	10.2	61	0.8	17.2	2.7	42	1.18	7.2	1.9	0.7	46	0.9	0.7	0.2	21	0.29	0.051	2
1281694	Soil	5.5	20.4	14.2	72	0.4	15.9	4.2	76	2.06	16.2	1.6	1.1	39	0.3	2.0	0.2	41	0.20	0.062	3
1281695	Soil	3.4	19.0	13.7	57	1.2	20.6	3.1	32	2.55	13.9	3.0	1.0	61	0.4	1.3	0.2	32	0.37	0.068	3
1281696	Soil	2.7	13.1	9.1	48	0.2	8.7	3.3	72	1.30	13.6	0.7	0.7	17	0.2	1.0	0.2	29	0.06	0.035	6
1281697	Soil	2.3	23.2	15.7	54	0.7	22.1	3.5	43	1.48	13.5	4.8	0.9	36	0.5	0.7	0.2	28	0.17	0.081	4
1281698	Soil	4.1	28.5	14.8	148	0.7	45.7	16.7	358	2.80	14.4	3.0	1.7	70	0.7	1.0	0.2	40	0.50	0.071	5
1281699	Soil	3.6	28.7	13.5	131	0.4	40.3	10.0	329	2.22	16.4	1.9	1.4	79	0.9	1.4	0.2	31	0.48	0.071	4
1281700	Soil	71.0	14.8	57.2	46	1.1	10.5	1.8	31	1.50	20.3	1.5	0.2	8	0.2	12.7	0.3	210	0.01	0.039	9
1281721	Soil	1.8	32.6	12.7	186	1.1	22.7	7.0	267	1.64	7.8	10.9	1.4	83	1.4	1.5	0.2	47	2.05	0.081	7
1281722	Soil	1.2	54.1	12.2	116	0.8	19.9	5.3	255	1.22	4.9	9.9	0.8	101	0.9	1.0	0.1	23	2.79	0.097	8
1281723	Soil	2.8	61.9	11.4	228	1.0	30.6	7.5	250	2.11	13.3	7.2	1.3	116	1.4	2.3	0.2	54	2.81	0.124	9
1281724	Soil	3.0	26.5	6.3	160	0.7	19.8	4.2	158	1.26	10.9	6.7	0.5	82	0.9	2.4	0.1	38	1.95	0.085	4
1281725	Soil	1.4	41.7	7.8	140	0.7	27.6	5.3	271	1.24	9.8	4.1	0.4	113	1.1	2.1	0.1	34	2.90	0.082	5
1281726	Soil	25.4	38.8	11.9	247	0.3	64.3	9.1	234	2.18	18.6	2.6	2.1	42	1.7	2.9	0.2	86	0.50	0.087	8
1281727	Soil	14.9	25.0	11.3	155	0.4	32.4	7.1	258	2.14	16.0	1.8	1.5	40	1.6	2.0	0.2	73	0.47	0.097	6
1281728	Soil	11.5	29.8	12.3	204	0.5	41.5	6.3	159	2.06	14.6	1.7	2.0	44	1.9	2.2	0.2	69	0.53	0.092	7
1281729	Soil	12.7	23.2	9.6	185	0.7	30.1	5.7	222	1.64	12.1	2.0	1.0	42	1.7	1.9	0.2	56	0.58	0.082	4
1281730	Soil	14.9	36.1	9.7	223	0.3	46.9	6.7	107	2.08	15.6	2.1	2.5	33	1.5	2.8	0.3	71	0.31	0.080	10
1281731	Soil	6.9	36.2	14.6	180	0.6	38.5	6.9	186	1.75	12.6	3.8	1.9	48	2.7	2.8	0.2	95	0.67	0.097	7
1281732	Soil	8.1	21.2	6.7	119	0.4	27.4	3.3	69	1.21	10.5	1.2	0.6	22	0.9	1.9	0.1	45	0.17	0.057	4
1281733	Soil	12.1	32.5	14.0	170	0.6	36.7	8.2	220	2.29	18.9	2.2	1.7	38	1.8	2.5	0.2	72	0.37	0.095	7
1281734	Soil	14.3	28.7	12.8	137	0.7	30.3	8.0	279	2.11	16.0	2.8	0.9	30	1.7	1.9	0.2	72	0.27	0.102	6
1281735	Soil	15.0	45.0	10.1	261	0.7	68.2	9.7	404	1.77	13.6	2.7	1.0	49	3.2	2.5	0.2	87	0.65	0.088	7
1281736	Soil	17.7	44.8	10.5	266	1.1	64.8	17.7	1204	2.19	15.6	3.3	1.0	57	3.4	3.6	0.2	89	0.73	0.115	8
1281737	Soil	6.8	55.1	8.6	181	1.1	71.8	4.1	140	1.51	11.2	4.1	0.7	49	3.5	2.5	0.2	60	0.66	0.137	5
1281738	Soil	12.4	44.1	14.2	360	0.8	60.7	9.5	441	2.14	20.8	3.0	1.8	69	4.0	3.7	0.2	108	1.09	0.111	8
1281739	Soil	6.9	37.8	14.4	425	0.5	51.1	9.3	166	2.70	17.0	2.7	2.3	39	1.2	1.8	0.2	51	0.40	0.077	5
1281740	Soil	4.3	27.6	12.6	166	0.4	27.8	9.0	199	2.74	14.0	1.4	1.9	30	0.4	1.3	0.2	39	0.27	0.071	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281691	Soil	13	0.10	463	0.001	1	0.67	0.007	0.04	<0.1	0.15	1.4	0.1	0.07	2	1.5	<0.2
1281692	Soil	9	0.04	399	0.001	1	0.42	0.012	0.02	<0.1	0.24	1.0	0.1	0.08	1	1.6	<0.2
1281693	Soil	12	0.09	499	0.001	2	0.55	0.011	0.04	<0.1	0.19	1.3	0.1	<0.05	2	1.6	<0.2
1281694	Soil	14	0.12	439	0.001	3	0.59	0.004	0.05	<0.1	0.10	1.4	0.1	<0.05	2	1.6	<0.2
1281695	Soil	13	0.10	674	<0.001	2	0.67	0.007	0.04	<0.1	0.24	1.8	0.2	0.06	2	2.8	<0.2
1281696	Soil	8	0.06	203	0.003	1	0.43	0.004	0.04	0.2	0.02	0.8	0.1	<0.05	2	0.8	<0.2
1281697	Soil	14	0.09	1157	0.002	3	0.80	0.010	0.05	<0.1	0.17	2.4	0.1	0.09	2	1.8	<0.2
1281698	Soil	20	0.19	1088	0.001	2	1.10	0.008	0.05	<0.1	0.19	3.2	0.2	<0.05	3	1.5	<0.2
1281699	Soil	14	0.17	1355	0.001	3	0.71	0.005	0.05	<0.1	0.15	2.4	0.2	0.06	2	1.7	<0.2
1281700	Soil	14	0.01	256	0.005	2	0.31	0.003	0.10	0.8	0.18	0.3	2.3	0.19	3	10.2	0.4
1281721	Soil	14	0.14	840	0.003	4	0.57	0.008	0.05	<0.1	0.55	2.2	0.2	0.07	2	1.4	<0.2
1281722	Soil	11	0.22	586	0.006	7	0.59	0.014	0.06	<0.1	0.42	1.7	0.1	0.12	1	2.0	<0.2
1281723	Soil	14	0.57	1678	0.004	6	0.68	0.006	0.08	<0.1	0.55	2.3	0.2	0.11	2	2.2	<0.2
1281724	Soil	9	0.30	652	0.006	5	0.45	0.012	0.04	0.2	0.30	1.1	<0.1	0.11	1	2.0	<0.2
1281725	Soil	11	0.19	762	0.005	5	0.59	0.009	0.04	<0.1	0.38	1.2	0.1	0.13	2	2.3	<0.2
1281726	Soil	17	0.14	976	0.002	2	0.75	0.004	0.06	0.1	0.22	2.5	0.3	<0.05	2	1.5	<0.2
1281727	Soil	16	0.15	1143	0.002	2	0.84	0.006	0.04	0.1	0.19	2.0	0.2	<0.05	3	1.4	<0.2
1281728	Soil	16	0.16	1098	0.003	2	0.79	0.004	0.04	0.1	0.31	2.4	0.2	<0.05	2	2.2	<0.2
1281729	Soil	13	0.14	930	0.003	2	0.78	0.012	0.04	0.1	0.29	1.8	0.2	<0.05	2	1.2	<0.2
1281730	Soil	17	0.18	1084	0.002	2	0.73	0.002	0.04	<0.1	0.21	2.7	0.2	<0.05	2	1.8	<0.2
1281731	Soil	19	0.16	1497	0.002	3	0.95	0.007	0.05	0.1	0.40	2.8	0.3	0.05	3	2.6	<0.2
1281732	Soil	10	0.08	587	0.003	2	0.48	0.013	0.05	<0.1	0.16	1.2	0.2	<0.05	2	1.2	<0.2
1281733	Soil	17	0.17	1130	0.002	2	0.86	0.005	0.06	0.1	0.26	2.2	0.2	<0.05	3	1.7	<0.2
1281734	Soil	15	0.13	1036	0.002	3	0.80	0.008	0.06	0.1	0.24	1.7	0.2	<0.05	2	1.6	<0.2
1281735	Soil	16	0.14	1675	0.002	2	0.93	0.010	0.06	0.1	0.30	2.2	0.3	<0.05	2	1.8	<0.2
1281736	Soil	15	0.16	1626	0.003	3	0.93	0.010	0.07	<0.1	0.37	2.5	0.3	<0.05	2	2.5	<0.2
1281737	Soil	14	0.13	1572	0.003	3	0.95	0.011	0.05	<0.1	0.35	1.7	0.2	0.10	2	2.5	<0.2
1281738	Soil	19	0.17	1159	0.002	3	0.85	0.007	0.07	0.1	0.39	3.0	0.3	0.06	2	2.4	<0.2
1281739	Soil	22	0.22	1129	0.001	3	1.00	0.005	0.07	<0.1	0.27	3.5	0.3	<0.05	3	1.8	<0.2
1281740	Soil	18	0.19	1110	0.001	2	0.99	0.005	0.05	<0.1	0.19	2.9	0.2	<0.05	3	1.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281741	Soil	4.9	48.0	14.7	219	0.5	47.5	11.0	232	3.24	18.8	1.3	2.4	35	1.1	1.9	0.3	37	0.20	0.071	4
1281742	Soil	7.6	29.5	12.5	174	0.5	32.8	12.9	1159	3.01	17.8	2.4	1.4	32	1.2	1.7	0.2	39	0.47	0.068	3
1281743	Soil	3.8	28.9	10.7	136	0.4	27.2	6.4	170	2.00	12.1	2.3	1.3	23	0.6	1.2	0.2	30	0.44	0.068	4
1281744	Soil	2.5	25.1	14.4	103	0.4	23.8	7.0	154	2.23	14.0	2.1	1.8	30	0.2	1.2	0.2	34	0.48	0.065	4
1281745	Soil	2.7	30.2	14.0	120	0.3	30.6	8.5	129	2.36	14.6	1.9	2.0	32	0.3	1.1	0.2	34	0.53	0.056	3
1281746	Soil	5.7	32.7	17.5	166	0.6	42.6	10.2	477	2.14	14.6	2.9	1.3	38	1.4	1.4	0.2	36	0.93	0.064	3
1281747	Soil	3.1	28.1	15.6	123	0.4	28.2	13.3	263	2.92	14.8	1.0	2.0	28	0.5	1.1	0.2	36	0.12	0.067	4
1281748	Soil	3.1	19.2	11.4	71	0.2	13.8	3.6	54	1.98	13.9	1.5	0.9	13	0.2	1.1	0.2	39	0.02	0.056	4
1281749	Soil	3.3	29.9	13.9	118	0.2	25.1	8.3	144	2.54	18.3	1.7	1.7	21	0.3	1.4	0.2	31	0.03	0.055	3
1281750	Soil	6.3	36.1	19.3	103	0.7	33.0	8.2	162	2.29	14.8	2.3	1.5	36	1.3	1.7	0.2	44	0.25	0.069	3
1281751	Soil	11.5	32.6	19.9	224	0.3	40.3	5.0	61	2.38	22.7	0.6	1.2	20	0.5	2.7	0.2	69	0.06	0.145	8
1281752	Soil	10.3	51.5	12.2	235	0.2	41.0	9.9	99	2.98	28.1	3.0	1.4	8	0.2	2.2	0.2	65	0.04	0.102	8
1281753	Soil	9.6	126.6	15.4	145	0.2	54.0	26.6	137	4.39	44.8	4.6	4.2	5	0.3	2.6	0.2	38	0.05	0.077	10
1281754	Soil	28.0	168.0	50.3	91	6.2	79.1	11.1	138	3.06	46.6	6.0	2.8	38	0.1	9.9	0.3	92	0.86	0.251	9
1281755	Soil	11.8	68.5	30.3	136	1.5	47.0	10.7	120	2.44	36.9	2.8	2.2	44	0.6	4.5	0.2	44	0.67	0.162	11
1281756	Soil	59.7	57.8	9.8	504	0.6	131.1	6.6	142	1.62	39.7	1.6	1.3	134	5.1	8.2	0.1	140	4.43	0.096	7
1281757	Soil	14.4	31.0	16.8	145	0.9	29.9	7.8	234	2.57	23.2	2.7	2.3	27	0.8	2.5	0.2	71	0.23	0.112	8
1281758	Soil	10.5	27.2	14.2	123	0.6	29.9	6.7	158	2.19	17.2	3.2	2.0	25	0.7	1.8	0.2	57	0.21	0.087	7
1281759	Soil	11.5	34.3	14.5	183	0.3	42.0	9.8	241	2.24	17.5	2.2	2.1	28	0.7	2.9	0.2	54	0.22	0.098	10
1281760	Soil	10.4	34.6	15.2	151	0.5	36.9	9.2	325	2.30	17.1	1.9	2.1	34	0.9	2.5	0.2	58	0.30	0.100	8
1281761	Soil	11.0	43.8	16.8	156	0.5	44.6	9.1	152	2.38	20.9	3.6	2.8	32	1.1	2.7	0.2	54	0.36	0.093	12
1281762	Soil	9.9	25.5	17.5	138	0.1	34.0	6.8	162	3.48	27.4	1.7	1.4	14	0.2	2.7	0.2	76	0.04	0.091	6
1281763	Soil	4.3	17.8	15.8	99	0.5	20.5	4.9	97	3.00	19.7	1.2	1.4	13	0.1	1.8	0.2	54	0.02	0.051	5
1281764	Soil	6.8	25.9	13.4	128	0.2	32.5	7.4	135	2.67	20.9	2.8	1.8	17	0.3	2.0	0.2	51	0.14	0.062	7
1281765	Soil	3.0	11.4	8.2	67	0.1	12.0	3.0	70	1.80	12.9	0.9	1.0	9	0.1	1.0	0.2	47	0.03	0.031	7
1281766	Soil	5.6	15.4	9.3	72	0.1	17.0	4.1	82	1.40	13.7	1.0	0.5	10	0.3	1.3	0.2	53	0.06	0.034	10
1281767	Soil	20.6	120.5	18.7	370	1.7	108.7	15.3	203	3.82	36.9	3.8	3.9	21	1.5	7.1	0.3	41	0.27	0.063	11
1281768	Soil	11.1	27.2	11.1	126	0.4	30.8	5.8	202	1.88	16.5	1.8	1.0	29	1.4	2.0	0.2	62	0.49	0.069	6
1281769	Soil	16.6	31.5	11.7	140	0.3	47.0	6.7	108	2.08	17.9	1.8	1.0	25	0.8	2.1	0.2	57	0.49	0.054	7
1281770	Soil	21.1	44.3	12.5	232	0.6	55.2	7.4	183	1.83	21.5	2.9	1.3	44	1.5	4.9	0.2	108	0.55	0.107	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281741	Soil	18	0.17	1481	0.001	2	0.82	0.005	0.07	<0.1	0.20	4.4	0.2	0.06	2	2.7	<0.2
1281742	Soil	17	0.16	890	0.001	2	0.87	0.007	0.05	<0.1	0.21	2.9	0.2	0.08	2	2.2	<0.2
1281743	Soil	13	0.15	568	0.001	1	0.78	0.007	0.05	<0.1	0.14	2.6	0.1	0.06	2	1.5	<0.2
1281744	Soil	17	0.20	1381	0.001	<1	0.87	0.005	0.05	<0.1	0.16	3.0	0.1	0.07	2	1.3	<0.2
1281745	Soil	19	0.22	1386	<0.001	<1	0.90	0.004	0.05	<0.1	0.14	3.2	0.1	0.06	3	1.3	<0.2
1281746	Soil	16	0.16	844	<0.001	2	0.75	0.007	0.05	<0.1	0.29	2.6	0.2	0.13	2	3.2	<0.2
1281747	Soil	19	0.20	1741	0.001	1	0.95	0.003	0.05	<0.1	0.12	3.0	0.1	<0.05	3	2.0	<0.2
1281748	Soil	11	0.07	375	0.002	<1	0.81	0.006	0.04	<0.1	0.04	1.3	0.1	<0.05	3	1.1	<0.2
1281749	Soil	15	0.15	1000	0.001	<1	0.77	0.004	0.04	<0.1	0.07	2.7	0.1	<0.05	2	1.5	<0.2
1281750	Soil	15	0.12	1112	<0.001	<1	0.80	0.004	0.05	<0.1	0.36	3.1	0.3	0.05	2	3.9	<0.2
1281751	Soil	12	0.04	311	0.003	2	0.50	0.003	0.06	<0.1	0.04	1.4	0.3	<0.05	2	1.6	<0.2
1281752	Soil	10	0.03	470	0.003	1	0.50	0.002	0.04	0.1	0.04	1.6	0.2	<0.05	3	2.5	<0.2
1281753	Soil	10	0.05	793	0.002	2	0.76	0.005	0.06	<0.1	0.09	3.6	0.3	<0.05	1	4.9	<0.2
1281754	Soil	11	0.12	679	0.002	6	0.39	0.003	0.11	<0.1	1.29	4.8	0.4	<0.05	<1	4.9	<0.2
1281755	Soil	9	0.11	1102	0.002	4	0.50	0.004	0.10	<0.1	0.36	3.6	0.7	0.08	1	2.7	<0.2
1281756	Soil	14	1.53	387	0.002	4	0.22	0.005	0.06	0.2	0.70	3.0	1.0	0.07	<1	3.7	<0.2
1281757	Soil	18	0.14	1078	0.002	2	0.87	0.004	0.07	<0.1	0.33	2.8	0.3	<0.05	2	1.8	<0.2
1281758	Soil	15	0.13	1016	0.002	<1	0.76	0.004	0.06	<0.1	0.26	2.6	0.3	<0.05	2	1.6	<0.2
1281759	Soil	13	0.09	1058	0.002	2	0.54	0.003	0.07	<0.1	0.20	2.4	0.2	<0.05	2	1.2	<0.2
1281760	Soil	15	0.13	1576	0.002	1	0.66	0.004	0.07	<0.1	0.23	2.9	0.2	<0.05	2	1.1	<0.2
1281761	Soil	13	0.12	1168	0.002	2	0.64	0.003	0.07	<0.1	0.32	3.5	0.2	<0.05	2	1.8	<0.2
1281762	Soil	19	0.10	305	0.002	<1	0.74	0.003	0.06	0.1	0.04	1.7	0.2	<0.05	3	1.8	<0.2
1281763	Soil	15	0.12	137	0.002	<1	0.81	0.003	0.04	<0.1	0.05	1.5	0.1	<0.05	3	0.9	<0.2
1281764	Soil	15	0.13	681	0.002	<1	0.91	0.003	0.04	<0.1	0.07	2.1	0.2	<0.05	2	1.1	<0.2
1281765	Soil	11	0.09	162	0.004	<1	0.68	0.004	0.04	0.1	0.02	0.9	0.1	<0.05	4	0.5	<0.2
1281766	Soil	8	0.06	462	0.004	<1	0.48	0.003	0.03	0.1	0.02	0.7	0.1	<0.05	3	0.8	<0.2
1281767	Soil	10	0.09	894	0.001	2	0.43	0.002	0.06	<0.1	0.98	6.0	0.2	<0.05	1	2.9	<0.2
1281768	Soil	14	0.17	1173	0.002	<1	0.65	0.004	0.04	<0.1	0.24	2.0	0.2	<0.05	2	1.4	<0.2
1281769	Soil	14	0.13	727	0.004	<1	0.70	0.003	0.04	0.1	0.11	2.1	0.3	<0.05	2	1.1	<0.2
1281770	Soil	16	0.12	1108	0.002	2	0.70	0.004	0.06	0.1	0.29	2.6	0.4	<0.05	2	1.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281781	Soil	5.3	32.0	12.1	125	1.0	32.0	8.0	214	2.10	12.7	3.2	1.2	34	1.6	1.5	0.2	47	0.32	0.098	5
1281782	Soil	4.6	19.8	10.8	80	0.5	17.3	10.3	359	1.79	12.6	2.7	0.8	21	0.5	1.2	0.1	41	0.12	0.076	3
1281783	Soil	15.6	37.5	19.2	186	1.0	40.4	16.0	602	6.98	46.8	5.4	1.5	27	0.9	3.3	0.2	73	0.18	0.097	5
1281784	Soil	2.4	11.9	7.9	44	0.3	11.4	2.6	60	1.34	10.1	<0.5	0.4	9	0.2	0.9	0.1	33	0.03	0.040	4
1281785	Soil	3.8	17.7	10.9	61	0.7	13.0	3.7	85	1.68	13.1	1.8	1.2	9	0.2	1.1	0.2	51	0.01	0.050	8
1281786	Soil	14.3	25.9	18.2	85	0.7	18.8	4.4	92	2.23	30.3	2.8	1.4	16	0.3	2.3	0.2	63	0.03	0.062	8
1281787	Soil	12.1	76.0	28.9	75	1.9	37.2	7.2	238	2.19	25.8	6.6	0.8	22	0.8	2.0	0.4	87	0.06	0.106	5
1281788	Soil	2.1	23.0	7.7	28	1.1	8.0	1.9	53	0.71	6.0	4.3	0.2	9	0.2	0.5	0.1	27	0.03	0.036	2
1281789	Soil	2.0	37.6	10.1	28	1.6	17.6	1.7	33	0.68	4.0	3.3	0.2	13	0.5	0.5	0.1	23	0.06	0.086	2
1281790	Soil	3.8	13.7	10.8	54	0.2	10.6	2.5	39	1.19	12.8	1.2	0.9	10	0.1	1.2	0.2	39	0.02	0.044	5
1281771	Soil	8.8	28.4	8.8	123	0.3	38.3	5.9	165	1.59	11.1	2.2	0.8	55	0.8	1.8	0.2	46	1.42	0.067	4
1281772	Soil	38.9	48.8	8.8	165	0.3	108.5	7.2	206	1.61	15.7	1.8	1.4	63	2.7	2.2	0.2	59	1.38	0.060	9
1281773	Soil	16.6	44.9	10.8	226	0.4	97.4	7.8	174	1.84	15.1	3.1	1.7	48	2.0	1.9	0.2	54	0.94	0.046	8
1281774	Soil	14.0	43.7	7.0	105	0.2	110.2	5.5	149	1.24	8.9	1.4	1.0	80	2.3	1.3	0.1	48	2.39	0.045	9
1281775	Soil	19.2	52.8	9.1	370	0.5	114.8	8.1	281	1.52	17.8	1.8	1.1	80	4.7	4.9	0.1	136	1.99	0.048	10
1281776	Soil	10.2	30.2	9.9	427	0.4	72.7	6.9	171	1.67	12.1	2.7	1.0	84	2.8	2.8	0.1	65	1.42	0.090	6
1281777	Soil	15.0	28.7	14.6	290	0.8	52.2	7.3	176	2.25	17.7	2.3	1.1	29	2.3	1.9	0.2	66	0.19	0.106	5
1281778	Soil	1.8	53.6	13.9	27	0.5	8.5	1.3	21	0.67	4.4	1.6	0.4	11	1.1	0.5	0.2	22	0.06	0.038	6
1281779	Soil	3.0	30.5	11.1	60	1.2	23.0	3.0	39	1.44	11.0	4.0	0.6	20	0.7	1.0	0.2	52	0.11	0.094	4
1281780	Soil	4.3	91.6	16.7	245	1.3	108.0	8.3	108	1.86	16.1	4.4	1.5	47	7.1	2.7	0.2	84	0.53	0.121	7
1281791	Soil	5.9	61.3	15.0	164	0.7	43.8	18.9	1220	2.50	17.2	1.9	2.1	15	0.7	2.0	0.2	50	0.06	0.059	7
1281792	Soil	4.6	77.0	13.7	170	1.3	63.4	13.5	434	2.21	14.5	4.1	1.6	45	1.2	2.0	0.2	42	0.51	0.102	7
1281793	Soil	10.5	37.6	11.9	188	0.6	43.5	8.4	292	2.40	15.6	2.4	2.2	47	2.1	2.6	0.2	49	0.48	0.093	6
1281794	Soil	14.5	26.4	15.9	135	1.2	30.0	7.9	264	2.16	14.2	3.0	0.9	32	2.8	2.1	0.2	68	0.27	0.105	5
1281795	Soil	0.9	15.8	7.7	48	0.4	15.1	5.3	154	1.00	4.1	1.0	0.4	52	1.5	0.5	0.1	18	0.82	0.069	3
1281796	Soil	3.0	13.7	10.0	75	<0.1	14.6	4.8	98	2.18	22.2	<0.5	1.1	8	0.2	1.2	0.2	47	0.02	0.024	5
1281797	Soil	3.2	10.7	8.9	65	<0.1	12.3	4.1	72	1.79	15.5	<0.5	1.6	7	0.1	1.4	0.2	56	0.01	0.025	7
1281798	Soil	2.9	14.1	11.7	56	<0.1	12.9	5.1	109	2.07	14.6	0.8	2.0	8	0.2	1.2	0.2	53	0.03	0.021	8
1281799	Soil	1.1	16.1	5.4	50	0.3	20.3	7.5	220	1.13	5.1	1.1	0.5	77	0.2	0.6	0.1	17	0.86	0.056	4
1281800	Soil	1.8	22.4	9.3	69	0.3	24.2	6.4	162	1.72	9.7	<0.5	1.0	100	0.6	0.8	0.2	29	1.02	0.046	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281781	Soil	15	0.13	1754	0.002	<1	0.90	0.010	0.05	<0.1	0.21	3.2	0.2	0.07	2	3.8	<0.2
1281782	Soil	11	0.09	1059	0.001	<1	0.67	0.010	0.04	<0.1	0.15	1.6	0.2	<0.05	2	1.8	<0.2
1281783	Soil	19	0.09	886	0.001	1	1.26	0.005	0.06	0.1	0.35	3.2	0.5	0.08	2	5.7	<0.2
1281784	Soil	10	0.07	412	0.004	<1	0.58	0.009	0.03	<0.1	0.05	0.9	0.1	<0.05	2	0.8	<0.2
1281785	Soil	10	0.05	203	0.003	<1	0.77	0.003	0.03	<0.1	0.04	1.3	0.1	<0.05	3	0.7	<0.2
1281786	Soil	13	0.10	251	0.004	<1	0.78	0.003	0.04	0.1	0.10	1.6	0.2	<0.05	3	1.9	<0.2
1281787	Soil	21	0.06	421	0.003	4	0.91	0.009	0.07	0.1	0.18	1.6	0.4	<0.05	4	1.7	<0.2
1281788	Soil	6	0.04	142	0.003	2	0.49	0.014	0.04	<0.1	0.11	0.7	0.1	<0.05	2	0.5	<0.2
1281789	Soil	8	0.03	277	0.002	2	0.53	0.015	0.04	<0.1	0.15	0.6	0.2	<0.05	2	1.0	<0.2
1281790	Soil	5	0.03	98	0.003	1	0.36	0.005	0.03	<0.1	0.03	0.7	0.1	<0.05	2	0.5	<0.2
1281771	Soil	14	0.17	860	0.002	3	0.66	0.007	0.04	<0.1	0.14	1.6	0.2	0.08	2	1.5	<0.2
1281772	Soil	16	0.26	572	0.002	2	0.54	0.005	0.04	0.2	0.20	3.0	0.5	<0.05	1	1.9	<0.2
1281773	Soil	17	0.18	646	0.002	2	0.74	0.006	0.04	0.1	0.16	3.1	0.4	<0.05	2	2.0	<0.2
1281774	Soil	14	0.70	372	0.003	4	0.47	0.012	0.04	0.1	0.17	2.2	1.0	0.06	1	1.8	<0.2
1281775	Soil	20	0.45	660	0.003	2	0.60	0.007	0.05	0.2	0.19	2.1	1.0	0.06	2	2.1	<0.2
1281776	Soil	16	0.20	924	0.003	4	0.64	0.009	0.06	<0.1	0.18	1.8	0.3	<0.05	2	2.1	<0.2
1281777	Soil	14	0.14	1162	0.002	2	0.81	0.008	0.05	<0.1	0.24	2.3	0.3	<0.05	2	2.4	<0.2
1281778	Soil	11	0.02	294	0.003	2	0.56	0.009	0.03	<0.1	0.04	0.8	<0.1	<0.05	3	0.9	<0.2
1281779	Soil	12	0.06	694	0.001	2	0.87	0.015	0.06	<0.1	0.35	2.0	0.3	<0.05	2	1.9	<0.2
1281780	Soil	20	0.15	1602	0.002	3	1.09	0.009	0.07	<0.1	0.45	3.6	0.9	0.10	3	30.9	<0.2
1281791	Soil	16	0.15	433	0.002	2	0.90	0.003	0.04	<0.1	0.15	3.1	0.2	<0.05	2	1.8	<0.2
1281792	Soil	14	0.18	1188	0.002	2	0.92	0.009	0.06	0.1	0.25	3.9	0.3	<0.05	2	3.2	<0.2
1281793	Soil	16	0.19	1629	0.002	3	0.68	0.005	0.06	<0.1	0.29	3.0	0.2	<0.05	2	2.8	<0.2
1281794	Soil	16	0.15	761	0.002	3	0.97	0.009	0.06	<0.1	0.32	1.9	0.3	<0.05	3	5.2	<0.2
1281795	Soil	8	0.15	523	0.005	2	0.63	0.019	0.03	<0.1	0.09	1.1	<0.1	0.06	2	1.5	<0.2
1281796	Soil	10	0.07	146	0.002	<1	0.69	0.004	0.03	<0.1	0.02	1.2	<0.1	<0.05	3	0.7	<0.2
1281797	Soil	8	0.04	140	0.003	<1	0.62	0.003	0.03	<0.1	0.01	1.2	0.1	<0.05	3	<0.5	<0.2
1281798	Soil	11	0.09	231	0.003	<1	0.85	0.003	0.03	<0.1	0.02	1.3	0.1	<0.05	3	0.7	<0.2
1281799	Soil	9	0.12	484	0.003	2	1.00	0.022	0.04	<0.1	0.09	1.4	0.1	<0.05	2	1.4	<0.2
1281800	Soil	13	0.21	1044	0.002	2	0.79	0.009	0.05	<0.1	0.10	1.9	0.1	0.07	2	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281801	Soil		4.0	21.4	10.8	87	0.4	17.9	8.0	371	1.48	13.1	1.9	1.0	43	1.1	1.3	0.2	39	0.59	0.063	4
1281802	Soil		2.0	24.2	9.9	67	1.1	16.6	5.4	127	1.05	8.0	2.8	0.6	34	0.8	1.1	0.2	34	0.46	0.077	3
1281803	Soil		1.1	18.1	6.5	21	0.6	7.9	1.4	22	0.56	4.2	2.3	0.4	9	0.2	0.4	<0.1	12	0.07	0.040	2
1281804	Soil		3.9	21.9	7.9	128	0.3	20.3	5.7	77	1.74	16.7	<0.5	0.8	4	0.2	1.8	0.2	59	0.02	0.027	7
1281805	Soil		2.5	56.1	16.3	83	1.4	41.2	5.8	95	1.56	10.6	5.2	1.1	50	0.5	1.3	0.2	34	1.09	0.051	4
1281806	Soil		4.7	31.7	6.8	55	0.6	14.5	2.6	70	0.88	14.1	1.3	0.7	13	0.4	1.4	0.1	31	0.12	0.036	4
1281807	Soil		4.6	24.2	7.9	83	0.6	18.5	3.3	59	1.31	9.4	0.7	0.4	8	0.4	1.3	0.1	41	0.02	0.043	4
1281808	Soil		3.8	7.1	10.1	41	0.2	7.5	1.9	37	0.91	10.0	<0.5	0.5	9	0.2	1.0	0.2	41	0.02	0.036	8
1281809	Soil		5.0	15.9	11.8	88	0.2	17.0	4.2	77	1.88	18.5	0.8	0.7	8	0.2	2.0	0.2	57	<0.01	0.041	7
1281810	Soil		3.1	12.0	8.0	50	0.1	8.7	2.5	37	0.95	9.0	2.4	0.7	7	0.1	0.9	0.1	39	0.02	0.027	7
1281811	Soil		3.9	13.1	10.5	71	0.2	14.9	4.3	96	2.02	14.5	0.8	1.5	8	0.3	1.5	0.2	47	0.02	0.027	7
1281812	Soil		1.9	10.8	6.0	55	0.3	13.6	3.2	40	1.22	9.0	<0.5	0.3	5	0.2	0.7	0.1	30	0.02	0.029	3
1281813	Soil		6.4	27.5	15.0	164	0.2	31.9	7.0	130	2.79	21.9	1.9	2.5	17	0.5	2.7	0.3	54	0.07	0.074	8
1281814	Soil		12.0	46.6	14.0	292	0.8	58.2	8.3	196	2.52	21.9	3.4	2.6	64	2.1	3.9	0.2	74	0.82	0.123	9
1281815	Soil		13.2	35.3	13.6	289	0.5	54.8	7.1	155	2.21	18.9	2.5	2.0	53	3.3	3.6	0.2	63	0.67	0.093	7
1281816	Soil		4.8	29.6	14.3	190	0.5	37.9	9.3	437	1.92	10.2	2.6	1.4	50	2.7	1.4	0.2	34	0.87	0.084	4
1281817	Soil		4.4	35.4	15.9	153	0.6	36.5	6.1	129	1.68	11.3	2.9	1.0	50	1.3	1.9	0.2	37	0.93	0.075	5
1281818	Soil		4.2	21.8	8.7	67	0.5	24.2	5.9	303	1.03	6.0	2.5	0.3	56	1.2	1.5	0.1	23	0.98	0.080	3
1281819	Soil		20.2	42.8	13.2	484	0.3	70.2	19.0	670	2.27	29.1	3.4	2.2	46	3.6	5.5	0.2	93	0.27	0.155	14
1281820	Soil		5.0	25.0	8.8	139	0.5	34.4	11.2	942	1.70	9.2	2.1	0.8	45	3.2	1.5	0.1	35	0.45	0.110	6
1281821	Soil		4.0	24.7	8.9	121	0.5	23.1	4.4	83	1.49	10.9	2.5	1.0	31	1.5	1.7	0.1	45	0.21	0.079	6
1281822	Soil		1.8	16.6	28.9	36	0.6	5.6	1.4	21	1.72	15.5	2.1	1.1	15	<0.1	0.6	0.3	12	0.02	0.040	2
1281823	Soil		5.4	12.7	13.1	32	1.5	9.8	1.6	42	1.08	11.5	1.3	0.1	18	<0.1	1.2	0.2	17	0.04	0.182	3
1281824	Soil		3.0	34.1	20.3	143	0.1	41.5	22.6	554	4.42	16.9	1.0	1.8	11	0.3	1.4	0.3	33	0.04	0.081	6
1281825	Soil		2.7	14.9	15.6	60	<0.1	12.5	3.2	52	1.76	9.7	2.5	0.4	11	0.1	1.0	0.3	29	0.01	0.063	4
1281826	Soil		37.9	17.0	24.1	64	2.5	15.7	3.0	57	2.13	37.3	3.0	0.2	40	0.2	11.9	0.4	174	0.03	0.151	10
1281827	Soil		58.5	22.4	50.8	42	1.4	12.1	1.7	27	1.23	22.7	1.1	0.2	99	0.2	9.8	0.4	139	0.05	0.141	13
1281828	Soil		13.3	15.9	16.3	31	0.9	10.1	1.2	25	1.05	14.0	0.9	0.1	37	0.2	2.9	0.2	346	0.03	0.132	6
1281829	Soil		100.8	33.4	28.8	125	0.7	32.2	2.7	54	2.50	34.3	1.1	0.1	43	0.5	17.6	0.3	383	0.03	0.109	9
1281830	Soil		94.1	41.5	17.8	397	1.2	99.5	3.3	53	1.71	42.5	0.6	0.2	21	1.0	25.9	0.2	793	0.02	0.046	28

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281801	Soil	10	0.12	612	0.001	2	0.59	0.007	0.04	<0.1	0.16	1.9	0.1	<0.05	2	1.2	<0.2
1281802	Soil	9	0.07	630	0.002	2	0.60	0.012	0.05	<0.1	0.18	1.6	0.1	<0.05	2	1.4	<0.2
1281803	Soil	6	0.02	185	0.002	2	0.25	0.014	0.03	<0.1	0.15	0.7	0.1	<0.05	<1	1.1	<0.2
1281804	Soil	8	0.02	73	0.003	2	0.42	0.003	0.02	0.1	0.02	1.1	0.1	<0.05	3	0.6	<0.2
1281805	Soil	12	0.19	948	0.003	3	0.75	0.011	0.06	<0.1	0.26	2.7	0.3	0.05	2	1.8	<0.2
1281806	Soil	7	0.04	287	0.002	1	0.29	0.008	0.04	<0.1	0.12	1.0	0.2	<0.05	1	0.8	<0.2
1281807	Soil	7	0.04	152	0.003	1	0.53	0.010	0.03	<0.1	0.06	0.8	0.1	<0.05	2	0.8	<0.2
1281808	Soil	6	0.03	99	0.004	1	0.34	0.003	0.03	0.1	0.02	0.5	0.2	<0.05	3	0.5	<0.2
1281809	Soil	8	0.05	167	0.003	<1	0.47	0.002	0.02	0.1	0.03	0.8	0.1	<0.05	3	0.8	<0.2
1281810	Soil	5	0.02	99	0.003	<1	0.33	0.003	0.03	0.1	0.01	0.5	0.1	<0.05	2	<0.5	<0.2
1281811	Soil	10	0.10	174	0.004	<1	0.65	0.002	0.03	<0.1	0.02	1.1	0.1	<0.05	3	0.6	<0.2
1281812	Soil	5	0.02	98	0.004	1	0.29	0.009	0.03	<0.1	0.01	0.7	<0.1	<0.05	2	<0.5	<0.2
1281813	Soil	14	0.16	452	0.003	2	0.84	0.003	0.04	0.1	0.07	2.1	0.2	<0.05	3	<0.5	<0.2
1281814	Soil	18	0.28	1280	0.004	6	0.78	0.006	0.10	0.2	0.36	3.5	0.4	<0.05	2	3.7	<0.2
1281815	Soil	21	0.20	768	0.004	3	0.70	0.007	0.07	0.1	0.26	2.7	0.2	<0.05	2	1.7	<0.2
1281816	Soil	17	0.23	650	0.001	3	0.77	0.007	0.06	<0.1	0.22	2.7	0.1	0.09	2	4.3	<0.2
1281817	Soil	17	0.23	552	0.002	3	0.73	0.009	0.08	0.1	0.20	2.6	0.2	0.07	2	1.9	<0.2
1281818	Soil	14	0.21	524	0.006	4	0.46	0.022	0.03	0.1	0.14	1.0	0.1	0.10	1	0.8	<0.2
1281819	Soil	17	0.09	1331	0.003	3	0.62	0.003	0.06	0.2	0.71	2.6	0.4	<0.05	2	2.1	<0.2
1281820	Soil	14	0.13	849	0.003	3	0.86	0.013	0.06	0.1	0.23	1.8	0.1	0.07	2	1.5	<0.2
1281821	Soil	12	0.11	909	0.003	2	0.72	0.010	0.05	0.1	0.32	1.6	0.2	<0.05	2	1.6	<0.2
1281822	Soil	6	0.01	203	<0.001	2	0.24	0.007	0.09	<0.1	0.07	1.1	0.1	0.18	<1	1.5	<0.2
1281823	Soil	14	0.02	222	0.003	2	0.32	0.016	0.05	<0.1	0.20	0.5	0.3	0.10	1	1.4	<0.2
1281824	Soil	25	0.22	110	0.004	1	1.22	0.003	0.04	0.1	0.03	3.0	0.2	<0.05	3	1.3	<0.2
1281825	Soil	14	0.06	111	0.003	1	0.70	0.006	0.04	<0.1	0.07	0.7	0.2	<0.05	2	<0.5	<0.2
1281826	Soil	23	0.06	207	0.003	2	0.51	0.004	0.06	0.3	0.66	0.4	1.6	0.11	4	6.1	<0.2
1281827	Soil	22	0.02	338	0.003	2	0.47	0.007	0.09	0.7	0.11	0.3	8.7	0.20	4	4.0	0.3
1281828	Soil	31	0.03	137	0.004	2	0.64	0.016	0.05	0.2	0.08	0.4	2.5	0.07	4	1.4	<0.2
1281829	Soil	26	0.03	321	0.004	2	0.53	0.005	0.07	0.3	0.08	0.3	2.7	0.12	5	7.0	0.3
1281830	Soil	36	0.04	182	0.006	3	0.50	0.003	0.08	0.3	0.09	0.5	2.2	<0.05	4	7.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281831	Soil	46.4	30.0	27.1	383	0.2	103.6	6.8	105	2.68	28.9	<0.5	0.5	18	0.7	4.4	0.3	202	0.02	0.062	14
1281832	Soil	15.9	34.2	41.3	501	0.3	108.0	8.0	84	3.10	17.0	<0.5	0.2	40	0.8	2.6	0.4	103	0.09	0.171	10
1281833	Soil	3.6	16.1	6.8	66	0.1	18.4	3.7	105	1.41	7.4	<0.5	0.1	6	0.2	0.9	0.2	32	0.03	0.049	6
1281834	Soil	5.4	40.4	6.8	148	0.4	35.9	8.3	58	2.27	13.1	<0.5	0.6	4	0.1	2.5	0.2	45	<0.01	0.054	33
1281835	Soil	4.9	23.6	24.5	100	0.8	23.6	5.3	79	2.32	23.6	0.5	0.5	34	0.2	1.8	0.3	57	0.02	0.056	10
1281836	Soil	4.3	30.4	17.8	86	0.8	38.9	8.9	93	3.70	65.9	1.4	2.6	31	0.2	1.8	0.3	36	0.02	0.080	12
1281837	Soil	4.5	19.3	12.7	62	0.6	17.5	3.6	59	1.45	9.3	1.1	0.2	12	0.2	1.1	0.2	40	0.03	0.071	10
1281838	Soil	5.7	32.7	13.4	129	0.8	37.2	7.7	127	2.39	12.8	2.2	1.0	24	0.5	1.6	0.2	36	0.15	0.090	8
1281839	Soil	3.7	47.1	20.3	162	1.2	40.5	9.2	85	3.23	15.3	1.6	0.4	20	0.4	2.0	0.2	27	0.03	0.099	6
1281840	Soil	3.8	42.1	18.3	168	1.0	54.7	11.8	267	3.25	14.1	6.3	2.4	46	0.4	1.4	0.3	32	0.68	0.064	8
1281841	Soil	5.2	40.6	19.3	171	0.6	50.0	10.3	224	2.84	13.6	5.6	2.0	52	0.8	1.8	0.2	43	0.94	0.081	9
1281842	Soil	24.7	75.6	25.1	1539	1.1	205.4	17.6	829	3.74	31.6	4.8	2.4	43	19.3	5.2	0.3	66	0.44	0.123	21
1281843	Soil	12.0	31.5	19.0	169	1.9	38.0	5.0	119	2.14	17.1	4.8	1.1	30	0.8	2.4	0.2	95	0.19	0.112	8
1281844	Soil	9.1	36.3	21.4	176	1.1	38.3	5.7	137	2.35	15.7	3.2	0.7	34	0.5	2.2	0.2	80	0.08	0.132	8
1281845	Soil	2.7	10.1	5.3	35	0.5	9.3	1.6	25	0.65	4.4	<0.5	0.1	10	0.2	0.6	<0.1	25	0.06	0.047	5
1281846	Soil	6.5	16.8	12.2	79	0.1	18.6	3.0	53	1.29	10.0	<0.5	0.3	12	0.2	1.3	0.2	61	0.03	0.054	12
1281847	Soil	16.4	39.8	21.4	265	0.6	61.9	7.5	114	2.63	21.5	1.6	1.1	53	1.2	4.4	0.3	103	0.21	0.127	14
1281848	Soil	7.9	18.2	14.4	106	0.3	22.5	3.9	111	1.76	14.0	1.3	0.2	25	0.4	1.9	0.2	80	0.14	0.064	9
1281849	Soil	9.1	28.7	13.4	156	1.1	34.4	3.9	90	1.65	11.7	2.6	0.4	23	1.0	2.3	0.2	94	0.17	0.092	8
1281850	Soil	10.5	31.0	10.7	155	0.3	40.9	7.0	64	2.23	10.1	<0.5	0.7	6	0.2	1.9	0.2	69	0.01	0.047	18
1281851	Soil	92.6	22.8	84.4	37	2.5	11.3	1.4	26	1.54	25.1	4.0	0.4	15	0.2	12.6	0.3	389	0.01	0.082	14
1281852	Soil	37.5	21.1	20.4	100	0.3	20.1	2.9	57	2.05	25.5	1.4	0.2	35	0.5	8.7	0.3	253	0.03	0.073	13
1281853	Soil	59.2	28.8	52.0	181	1.2	37.4	2.5	54	2.12	30.6	2.0	0.3	53	1.4	14.4	0.3	352	0.12	0.190	21
1281854	Soil	67.3	17.9	17.3	112	1.8	23.0	2.2	51	2.06	37.5	2.3	1.1	31	0.6	14.3	0.3	345	0.02	0.044	17
1281855	Soil	72.0	44.7	10.1	198	0.7	45.1	1.1	25	1.21	30.8	1.0	0.3	21	0.9	16.7	0.1	493	0.03	0.058	22
1281856	Soil	107.4	18.3	26.4	182	0.6	41.0	1.8	38	2.02	38.1	1.3	0.6	22	0.6	19.1	0.3	484	0.02	0.047	18
1281857	Soil	78.2	44.9	14.3	236	1.4	49.4	1.1	38	1.20	37.5	2.8	0.2	18	0.6	15.9	0.2	538	0.01	0.081	28
1281858	Soil	59.2	65.3	116.8	1415	0.4	95.5	8.7	3346	7.90	211.7	72.0	2.1	17	2.8	10.0	0.2	165	0.10	0.078	18
1281859	Soil	4.6	65.5	23.8	238	0.2	69.8	24.3	508	5.65	31.2	6.3	5.1	7	0.2	4.0	1.8	31	0.01	0.088	23
1281860	Soil	129.0	143.7	29.2	1253	3.1	291.7	9.4	174	3.52	107.5	7.3	0.9	193	12.0	52.9	0.4	1209	0.06	0.152	28

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281831	Soil	20	0.09	165	0.006	2	0.89	0.003	0.06	0.2	0.03	0.9	1.0	<0.05	5	3.2	<0.2
1281832	Soil	22	0.05	230	0.008	3	0.63	0.005	0.07	<0.1	0.02	0.4	0.4	0.06	4	2.6	<0.2
1281833	Soil	12	0.04	223	0.006	2	0.47	0.012	0.05	<0.1	0.02	0.4	0.2	<0.05	3	<0.5	<0.2
1281834	Soil	13	0.03	90	0.002	3	0.33	0.003	0.05	<0.1	0.02	0.8	0.2	<0.05	2	1.0	<0.2
1281835	Soil	15	0.06	241	0.006	2	0.71	0.004	0.08	0.1	0.02	0.9	0.2	0.06	4	1.0	<0.2
1281836	Soil	16	0.05	1204	0.005	3	0.82	0.008	0.08	0.1	0.06	2.4	0.2	0.07	3	1.6	<0.2
1281837	Soil	14	0.04	401	0.005	2	0.62	0.004	0.07	0.1	0.04	0.4	0.2	<0.05	3	<0.5	<0.2
1281838	Soil	17	0.10	1429	0.002	4	0.72	0.006	0.10	<0.1	0.10	1.6	0.2	<0.05	2	0.6	<0.2
1281839	Soil	17	0.03	966	0.003	2	0.61	0.010	0.09	<0.1	0.05	0.9	0.2	0.10	2	1.2	<0.2
1281840	Soil	24	0.16	1437	0.002	4	0.74	0.006	0.08	<0.1	0.24	5.0	0.1	<0.05	2	1.3	<0.2
1281841	Soil	25	0.13	1185	0.004	7	0.74	0.008	0.11	<0.1	0.14	4.1	0.2	0.08	2	1.3	<0.2
1281842	Soil	21	0.10	728	0.003	4	0.48	0.004	0.09	0.1	0.45	3.7	0.8	0.06	1	3.6	<0.2
1281843	Soil	26	0.15	892	0.003	4	1.09	0.011	0.13	0.2	0.45	2.1	0.5	<0.05	4	1.3	<0.2
1281844	Soil	21	0.10	956	0.004	5	1.04	0.011	0.14	0.2	0.19	1.6	0.4	0.08	3	1.1	<0.2
1281845	Soil	5	0.03	390	0.004	2	0.38	0.016	0.04	<0.1	0.06	0.3	0.1	<0.05	2	<0.5	<0.2
1281846	Soil	9	0.04	258	0.003	2	0.57	0.006	0.05	<0.1	0.03	0.4	0.2	<0.05	3	<0.5	<0.2
1281847	Soil	21	0.11	453	0.004	3	0.72	0.005	0.09	0.2	0.13	1.8	0.4	<0.05	3	1.8	<0.2
1281848	Soil	15	0.11	298	0.006	2	0.77	0.007	0.06	0.1	0.05	0.6	0.2	<0.05	4	0.7	<0.2
1281849	Soil	18	0.09	904	0.003	2	1.04	0.012	0.10	<0.1	0.25	1.2	0.4	<0.05	3	1.1	<0.2
1281850	Soil	13	0.05	342	0.003	2	0.83	0.004	0.08	<0.1	0.02	0.9	0.2	<0.05	4	1.1	<0.2
1281851	Soil	27	0.02	303	0.003	2	0.39	0.003	0.12	0.8	0.30	0.7	2.6	0.21	4	23.5	0.4
1281852	Soil	17	0.04	377	0.005	2	0.65	0.004	0.07	0.3	0.06	0.5	1.4	0.05	4	3.9	<0.2
1281853	Soil	30	0.03	434	0.004	3	0.54	0.005	0.12	0.5	0.22	0.4	3.5	0.16	4	9.4	<0.2
1281854	Soil	19	0.03	486	0.016	2	0.43	0.003	0.13	0.6	0.25	1.0	4.0	0.23	4	9.0	<0.2
1281855	Soil	22	0.03	318	0.006	4	0.45	0.006	0.09	0.4	0.08	0.7	2.7	0.09	2	5.2	<0.2
1281856	Soil	21	0.04	381	0.011	3	0.45	0.003	0.10	0.4	0.05	0.8	2.5	0.07	4	5.9	0.4
1281857	Soil	24	0.05	280	0.002	6	0.50	0.003	0.12	0.3	0.25	0.7	3.2	<0.05	3	6.3	0.2
1281858	Soil	20	0.08	333	0.003	3	0.96	0.003	0.09	<0.1	1.36	5.3	1.0	<0.05	3	3.8	<0.2
1281859	Soil	14	0.04	266	0.002	3	0.66	0.002	0.12	<0.1	0.12	5.9	0.4	<0.05	2	1.5	0.2
1281860	Soil	82	0.12	316	0.005	4	1.10	0.003	0.16	0.6	1.64	2.8	10.0	0.07	5	26.4	0.4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281861	Soil	68.9	92.3	23.6	836	0.9	221.6	10.1	323	2.21	48.2	2.2	1.0	70	8.2	16.5	0.2	362	1.08	0.138	15
1281862	Soil	24.2	139.7	197.4	436	0.9	100.4	11.2	219	5.46	76.1	3.5	1.5	182	1.7	8.6	1.3	201	2.17	1.364	39
1281863	Soil	4.6	35.6	8.6	76	<0.1	28.8	8.4	253	2.86	132.5	1.2	0.3	5	0.2	2.3	0.3	41	0.03	0.077	18
1281864	Soil	3.0	37.0	15.1	94	0.3	25.0	6.4	88	2.33	24.3	1.5	0.4	16	0.2	1.5	0.2	30	0.03	0.095	10
1281865	Soil	7.7	20.5	11.7	116	0.3	22.1	3.8	47	1.17	20.1	1.6	0.1	8	0.2	2.2	0.2	69	0.02	0.057	14
1281866	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281867	Soil	6.3	35.5	13.4	240	1.8	34.9	3.4	51	1.48	11.5	3.7	<0.1	29	1.4	1.4	0.2	53	0.25	0.209	7
1281868	Soil	3.3	38.7	18.5	133	1.3	36.2	4.5	352	1.44	7.4	3.1	0.4	87	1.5	1.3	0.2	40	1.01	0.226	11
1281869	Soil	9.6	28.0	20.7	138	0.4	31.6	4.7	93	2.24	14.7	2.5	0.4	25	0.3	2.6	0.3	77	0.06	0.152	15
1281870	Soil	10.5	35.1	60.9	147	0.4	35.3	4.7	42	1.57	12.8	1.3	<0.1	42	0.2	1.6	0.4	69	0.02	0.119	15
1281871	Soil	10.9	14.6	14.1	82	0.7	20.2	2.4	32	0.95	9.7	2.6	0.1	14	0.1	2.1	0.2	78	0.02	0.060	9
1281872	Soil	25.2	32.3	22.7	205	0.6	46.6	5.3	108	3.41	27.7	2.6	1.6	28	0.4	4.7	0.3	251	0.04	0.097	16
1281873	Soil	92.5	41.8	21.9	666	0.2	126.2	4.3	63	1.92	45.0	0.6	0.2	10	0.8	21.3	0.3	1262	0.03	0.089	18
1281874	Soil	45.5	35.7	45.5	319	0.5	67.0	3.7	42	1.40	21.8	1.3	<0.1	34	0.9	7.7	0.3	396	0.06	0.113	12
1281875	Soil	89.5	48.8	17.2	784	0.2	144.1	5.5	63	1.98	40.3	1.8	0.4	21	3.0	19.0	0.2	1311	0.23	0.119	21
1281876	Soil	60.0	68.9	13.4	656	0.7	159.9	8.6	218	2.11	30.5	2.0	0.7	50	6.8	9.8	0.2	301	0.67	0.156	21
1281877	Soil	9.0	25.3	12.7	114	2.0	26.1	3.2	44	1.56	6.1	6.3	1.0	27	0.5	1.4	0.2	44	0.10	0.159	9
1281878	Soil	7.9	38.5	7.0	89	<0.1	45.4	11.2	172	2.93	12.7	<0.5	0.6	3	<0.1	1.8	0.3	44	0.02	0.053	12
1281879	Soil	11.4	67.4	18.6	203	0.2	108.4	18.7	795	4.85	16.1	1.0	2.0	6	0.4	2.2	0.4	51	0.03	0.076	22
1281880	Soil	1.5	30.4	6.3	126	1.1	38.8	1.7	112	0.68	6.9	3.3	0.3	41	1.3	1.0	0.1	24	0.55	0.239	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

CERTIFICATE OF ANALYSIS WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281861	Soil	32	0.15	502	0.004	4	0.66	0.006	0.09	0.4	1.42	4.0	2.5	0.08	2	8.1	<0.2
1281862	Soil	55	0.11	990	0.016	25	1.20	0.005	0.42	0.1	0.41	3.3	1.2	0.11	4	6.6	0.4
1281863	Soil	10	0.04	147	0.004	2	0.56	0.003	0.10	0.1	0.05	0.5	0.2	<0.05	3	0.5	<0.2
1281864	Soil	10	0.04	239	0.004	1	0.71	0.011	0.06	<0.1	0.06	0.5	0.1	<0.05	3	0.8	<0.2
1281865	Soil	8	0.04	145	0.003	2	0.55	0.007	0.07	<0.1	0.05	0.2	0.3	<0.05	3	0.7	<0.2
1281866	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281867	Soil	17	0.09	643	0.002	6	0.84	0.013	0.12	<0.1	0.56	0.5	0.4	0.05	2	1.0	<0.2
1281868	Soil	13	0.18	1610	0.005	3	0.90	0.017	0.07	<0.1	0.43	1.0	0.2	0.13	2	1.9	<0.2
1281869	Soil	16	0.10	250	0.004	2	0.85	0.003	0.09	<0.1	0.07	0.5	0.3	<0.05	3	1.9	<0.2
1281870	Soil	14	0.05	277	0.005	3	0.56	0.004	0.12	<0.1	0.05	0.3	0.3	0.10	3	1.7	<0.2
1281871	Soil	10	0.03	99	0.003	1	0.36	0.011	0.05	<0.1	0.03	0.2	0.3	<0.05	3	1.1	<0.2
1281872	Soil	31	0.17	257	0.006	2	1.42	0.004	0.10	0.2	0.06	1.9	0.7	<0.05	5	2.1	<0.2
1281873	Soil	68	0.11	202	0.004	3	1.03	0.005	0.12	0.2	0.05	0.4	2.1	<0.05	6	4.3	0.2
1281874	Soil	27	0.05	191	0.004	2	0.49	0.010	0.10	0.1	0.05	0.3	0.9	0.06	3	2.6	0.2
1281875	Soil	76	0.14	305	0.005	5	1.11	0.005	0.14	0.3	0.09	1.2	2.1	<0.05	5	4.7	0.2
1281876	Soil	29	0.13	568	0.003	3	0.76	0.005	0.09	0.3	0.34	2.0	1.6	<0.05	2	3.8	<0.2
1281877	Soil	20	0.06	2503	0.004	4	0.79	0.003	0.06	0.1	0.99	1.6	0.3	0.09	2	1.3	<0.2
1281878	Soil	5	0.03	73	0.003	4	0.37	0.005	0.06	<0.1	0.07	1.1	0.1	<0.05	2	0.9	<0.2
1281879	Soil	11	0.05	167	0.002	3	0.69	0.004	0.06	<0.1	0.03	3.0	0.2	<0.05	2	1.1	<0.2
1281880	Soil	8	0.09	352	0.005	2	0.77	0.021	0.03	<0.1	0.56	0.4	0.2	0.12	2	1.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

QUALITY CONTROL REPORT WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1094403	Soil	2.2	7.6	14.2	30	<0.1	5.9	1.2	22	0.93	7.8	1.6	0.7	16	<0.1	0.6	0.3	22	0.02	0.025	2
REP 1094403	QC	2.1	7.6	13.9	29	<0.1	5.6	1.2	21	0.89	7.6	1.2	0.7	15	<0.1	0.6	0.2	21	0.02	0.023	2
1094436	Soil	38.0	64.3	10.1	247	0.6	213.4	8.5	295	1.58	24.8	1.3	0.8	112	3.6	6.5	0.1	147	5.00	0.103	14
REP 1094436	QC	38.7	65.1	10.4	250	0.6	214.6	9.0	308	1.60	26.1	1.6	0.8	115	3.7	6.8	0.1	156	4.97	0.107	14
1094437	Soil	33.3	70.3	7.4	181	0.4	159.5	6.2	161	1.33	18.5	3.3	0.6	82	3.6	4.2	0.3	85	2.41	0.086	14
REP 1094437	QC	33.4	71.6	7.4	191	0.4	158.7	6.1	163	1.30	18.4	3.7	0.5	83	3.6	4.2	0.2	87	2.44	0.084	14
1094467	Soil	7.5	14.7	32.7	74	2.7	16.9	2.9	57	1.98	16.9	0.6	0.8	26	0.4	2.7	0.2	87	0.03	0.087	7
REP 1094467	QC	7.5	14.6	32.6	77	2.6	16.9	2.9	54	1.91	16.5	<0.5	0.8	26	0.4	2.7	0.2	83	0.03	0.080	7
1094486	Soil	0.9	12.9	4.8	23	0.6	9.8	1.9	69	0.86	3.6	2.2	0.3	53	0.2	0.4	0.1	14	0.50	0.056	3
REP 1094486	QC	0.8	12.5	4.5	22	0.5	8.0	1.6	65	0.81	3.1	2.4	0.2	49	0.2	0.3	0.1	15	0.48	0.054	3
1094495	Soil	210.0	220.7	20.0	>10000	6.6	929.3	18.0	313	2.16	158.9	1.4	2.4	259	64.6	74.4	0.2	3181	4.73	0.293	17
REP 1094495	QC	212.8	225.0	20.7	>10000	6.8	944.7	18.6	317	2.18	160.8	1.0	2.4	259	65.2	76.8	0.2	3132	4.67	0.296	17
1281034	Soil	7.4	34.0	17.0	156	0.4	40.9	6.8	117	2.09	20.9	2.4	1.1	44	0.5	4.9	0.2	49	0.22	0.122	8
REP 1281034	QC	7.8	36.2	16.8	160	0.4	43.4	6.9	119	2.10	20.4	2.2	0.9	43	0.6	4.5	0.1	51	0.23	0.121	8
1281677	Soil	3.1	38.7	14.5	142	0.3	24.4	10.6	337	2.95	20.4	3.4	4.6	50	0.7	2.0	0.2	48	0.62	0.179	18
REP 1281677	QC	3.3	37.9	14.5	141	0.3	24.9	10.7	351	2.89	21.1	3.9	4.6	49	0.7	1.9	0.2	47	0.62	0.176	18
1281726	Soil	25.4	38.8	11.9	247	0.3	64.3	9.1	234	2.18	18.6	2.6	2.1	42	1.7	2.9	0.2	86	0.50	0.087	8
REP 1281726	QC	26.1	37.9	11.8	254	0.4	64.7	9.3	233	2.15	18.9	2.1	2.1	42	1.8	3.0	0.2	84	0.50	0.086	8
1281730	Soil	14.9	36.1	9.7	223	0.3	46.9	6.7	107	2.08	15.6	2.1	2.5	33	1.5	2.8	0.3	71	0.31	0.080	10
REP 1281730	QC	13.9	35.7	9.2	211	0.3	45.6	6.3	109	2.04	14.6	2.6	2.5	33	1.5	2.7	0.2	68	0.30	0.078	7
1281749	Soil	3.3	29.9	13.9	118	0.2	25.1	8.3	144	2.54	18.3	1.7	1.7	21	0.3	1.4	0.2	31	0.03	0.055	3
REP 1281749	QC	3.1	29.0	13.6	117	0.2	24.8	8.6	142	2.55	17.7	1.2	1.7	20	0.3	1.4	0.2	30	0.02	0.054	3
1281763	Soil	4.3	17.8	15.8	99	0.5	20.5	4.9	97	3.00	19.7	1.2	1.4	13	0.1	1.8	0.2	54	0.02	0.051	5
REP 1281763	QC	4.3	17.7	15.8	101	0.4	21.0	5.1	97	3.00	20.0	1.3	1.4	13	0.1	1.8	0.2	54	0.02	0.051	5
1281774	Soil	14.0	43.7	7.0	105	0.2	110.2	5.5	149	1.24	8.9	1.4	1.0	80	2.3	1.3	0.1	48	2.39	0.045	9
REP 1281774	QC	13.5	43.2	6.4	101	0.2	106.5	5.4	144	1.18	8.4	<0.5	0.9	79	2.2	1.4	0.1	43	2.34	0.043	8
1281811	Soil	3.9	13.1	10.5	71	0.2	14.9	4.3	96	2.02	14.5	0.8	1.5	8	0.3	1.5	0.2	47	0.02	0.027	7
REP 1281811	QC	3.9	12.4	10.7	71	0.2	15.3	4.4	97	2.09	14.9	1.5	1.4	7	0.3	1.5	0.2	48	0.02	0.028	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

QUALITY CONTROL REPORT WHI11001376.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1094403	Soil	5	0.03	123	<0.001	2	0.31	0.002	0.04	<0.1	0.03	0.8	0.1	<0.05	<1	0.5	<0.2
REP 1094403	QC	5	0.03	121	<0.001	1	0.30	0.002	0.04	<0.1	0.03	0.8	0.1	<0.05	1	<0.5	<0.2
1094436	Soil	23	2.39	272	0.004	8	0.40	0.008	0.10	0.2	0.23	2.8	4.0	0.24	1	3.4	<0.2
REP 1094436	QC	23	2.41	281	0.005	9	0.43	0.008	0.11	0.2	0.25	2.9	4.2	0.26	1	3.8	<0.2
1094437	Soil	20	0.58	390	0.003	6	0.44	0.009	0.06	0.2	0.37	2.0	1.5	0.31	<1	2.6	<0.2
REP 1094437	QC	19	0.55	388	0.004	5	0.41	0.009	0.06	0.2	0.39	2.0	1.6	0.29	<1	2.6	<0.2
1094467	Soil	12	0.05	175	0.004	<1	0.59	0.004	0.04	0.1	0.06	1.1	0.3	<0.05	3	1.4	<0.2
REP 1094467	QC	12	0.04	172	0.004	1	0.58	0.004	0.05	0.1	0.08	1.2	0.3	<0.05	3	1.4	<0.2
1094486	Soil	7	0.11	465	0.003	2	0.52	0.026	0.03	<0.1	0.11	1.1	<0.1	0.07	1	0.9	<0.2
REP 1094486	QC	6	0.11	435	0.003	1	0.50	0.026	0.03	<0.1	0.11	1.0	<0.1	0.07	1	0.6	<0.2
1094495	Soil	130	0.40	1072	0.012	20	1.12	0.004	0.27	0.6	1.48	5.8	11.5	0.13	5	28.0	0.3
REP 1094495	QC	129	0.40	1086	0.011	18	1.11	0.005	0.26	0.7	1.61	6.1	12.0	0.12	5	28.9	0.3
1281034	Soil	14	0.11	1038	0.005	2	0.61	0.005	0.06	0.1	0.11	1.6	0.3	<0.05	2	1.1	<0.2
REP 1281034	QC	14	0.11	1003	0.005	1	0.61	0.005	0.06	<0.1	0.09	1.7	0.3	<0.05	2	1.4	<0.2
1281677	Soil	17	0.54	1012	0.005	4	1.03	0.005	0.14	0.4	0.25	3.0	0.1	0.06	3	1.6	<0.2
REP 1281677	QC	18	0.53	1047	0.005	4	0.99	0.005	0.14	0.4	0.27	3.0	0.1	<0.05	3	2.0	<0.2
1281726	Soil	17	0.14	976	0.002	2	0.75	0.004	0.06	0.1	0.22	2.5	0.3	<0.05	2	1.5	<0.2
REP 1281726	QC	17	0.14	1006	0.002	2	0.74	0.004	0.06	0.2	0.23	2.6	0.3	<0.05	2	1.4	<0.2
1281730	Soil	17	0.18	1084	0.002	2	0.73	0.002	0.04	<0.1	0.21	2.7	0.2	<0.05	2	1.8	<0.2
REP 1281730	QC	16	0.17	1053	0.002	2	0.71	0.003	0.04	0.1	0.17	2.5	0.2	<0.05	2	1.7	<0.2
1281749	Soil	15	0.15	1000	0.001	<1	0.77	0.004	0.04	<0.1	0.07	2.7	0.1	<0.05	2	1.5	<0.2
REP 1281749	QC	15	0.16	992	0.001	<1	0.79	0.004	0.04	<0.1	0.09	2.6	<0.1	0.05	2	1.8	<0.2
1281763	Soil	15	0.12	137	0.002	<1	0.81	0.003	0.04	<0.1	0.05	1.5	0.1	<0.05	3	0.9	<0.2
REP 1281763	QC	15	0.12	141	0.002	<1	0.83	0.004	0.04	<0.1	0.05	1.5	0.1	<0.05	3	1.7	<0.2
1281774	Soil	14	0.70	372	0.003	4	0.47	0.012	0.04	0.1	0.17	2.2	1.0	0.06	1	1.8	<0.2
REP 1281774	QC	12	0.66	368	0.003	3	0.45	0.011	0.04	0.1	0.15	2.0	0.8	0.06	1	1.5	<0.2
1281811	Soil	10	0.10	174	0.004	<1	0.65	0.002	0.03	<0.1	0.02	1.1	0.1	<0.05	3	0.6	<0.2
REP 1281811	QC	10	0.10	172	0.003	<1	0.61	0.003	0.03	<0.1	0.02	1.0	0.1	<0.05	3	0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

QUALITY CONTROL REPORT WHI11001376.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1281818	Soil	4.2	21.8	8.7	67	0.5	24.2	5.9	303	1.03	6.0	2.5	0.3	56	1.2	1.5	0.1	23	0.98	0.080	3
REP 1281818	QC	4.2	22.9	9.4	69	0.5	25.5	6.1	318	1.01	6.5	2.3	0.5	56	1.3	1.5	0.1	23	0.96	0.085	3
1281837	Soil	4.5	19.3	12.7	62	0.6	17.5	3.6	59	1.45	9.3	1.1	0.2	12	0.2	1.1	0.2	40	0.03	0.071	10
REP 1281837	QC	4.1	20.3	12.6	67	0.6	18.5	3.7	63	1.51	9.7	0.5	0.3	13	0.2	1.3	0.2	44	0.03	0.092	12
1281849	Soil	9.1	28.7	13.4	156	1.1	34.4	3.9	90	1.65	11.7	2.6	0.4	23	1.0	2.3	0.2	94	0.17	0.092	8
REP 1281849	QC	9.7	27.9	13.5	158	1.1	34.8	3.9	90	1.64	11.6	3.0	0.4	25	1.0	2.5	0.2	104	0.17	0.097	9
1281865	Soil	7.7	20.5	11.7	116	0.3	22.1	3.8	47	1.17	20.1	1.6	0.1	8	0.2	2.2	0.2	69	0.02	0.057	14
REP 1281865	QC	7.8	20.2	11.6	117	0.3	21.8	4.0	49	1.19	20.0	0.7	0.2	8	0.3	2.2	0.2	66	0.01	0.056	14
Reference Materials																					
STD DS8	Standard	13.0	103.2	118.9	293	1.7	35.0	7.0	577	2.31	22.7	203.9	6.5	60	2.1	5.2	5.8	41	0.66	0.072	15
STD DS8	Standard	12.3	99.2	114.0	287	1.6	34.8	7.1	575	2.26	22.3	109.9	6.4	59	2.0	5.0	5.8	40	0.65	0.072	14
STD DS8	Standard	12.1	108.1	115.4	305	1.7	37.7	7.2	584	2.39	23.6	110.1	5.9	58	2.1	5.0	5.9	41	0.64	0.077	13
STD DS8	Standard	12.6	113.4	121.2	305	1.8	38.6	7.9	605	2.44	25.3	103.9	6.6	64	2.5	5.5	6.9	42	0.70	0.075	14
STD DS8	Standard	12.8	108.9	124.0	307	1.8	38.2	7.5	600	2.45	24.2	112.8	6.8	64	2.6	5.6	6.9	43	0.69	0.075	14
STD DS8	Standard	13.7	116.0	134.2	336	1.9	41.1	8.1	649	2.63	26.6	115.4	6.6	73	2.5	5.7	6.4	43	0.72	0.080	16
STD DS8	Standard	12.9	102.7	117.6	288	1.7	36.6	7.0	585	2.33	23.1	100.5	5.8	68	2.1	5.3	5.7	39	0.65	0.074	15
STD DS8	Standard	11.9	101.3	118.6	310	1.8	36.2	7.4	601	2.40	25.3	111.4	6.3	65	2.4	5.5	6.7	43	0.64	0.077	13
STD DS8	Standard	13.2	104.6	121.1	308	1.8	36.7	7.1	593	2.39	24.4	102.4	6.8	68	2.2	5.7	6.6	41	0.69	0.080	15
STD DS8	Standard	13.0	106.8	127.6	308	1.8	37.9	7.5	611	2.45	24.6	106.6	6.4	66	2.3	5.8	6.8	42	0.68	0.081	14
STD DS8	Standard	13.3	110.9	123.6	312	1.8	37.8	7.8	608	2.47	24.7	122.0	7.2	75	2.5	5.3	6.4	43	0.73	0.079	17
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

QUALITY CONTROL REPORT WHI11001376.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1281818	Soil	14	0.21	524	0.006	4	0.46	0.022	0.03	0.1	0.14	1.0	0.1	0.10	1	0.8	<0.2
REP 1281818	QC	15	0.21	573	0.008	4	0.47	0.022	0.04	0.1	0.16	1.1	<0.1	0.08	1	0.9	<0.2
1281837	Soil	14	0.04	401	0.005	2	0.62	0.004	0.07	0.1	0.04	0.4	0.2	<0.05	3	<0.5	<0.2
REP 1281837	QC	15	0.05	422	0.005	3	0.67	0.005	0.08	0.1	0.05	0.6	0.2	0.06	3	<0.5	<0.2
1281849	Soil	18	0.09	904	0.003	2	1.04	0.012	0.10	<0.1	0.25	1.2	0.4	<0.05	3	1.1	<0.2
REP 1281849	QC	19	0.09	933	0.004	2	1.08	0.013	0.13	0.1	0.26	1.6	0.5	<0.05	3	0.8	<0.2
1281865	Soil	8	0.04	145	0.003	2	0.55	0.007	0.07	<0.1	0.05	0.2	0.3	<0.05	3	0.7	<0.2
REP 1281865	QC	8	0.03	144	0.006	2	0.53	0.007	0.06	<0.1	0.03	0.3	0.3	<0.05	3	0.7	<0.2
Reference Materials																	
STD DS8	Standard	111	0.55	262	0.107	3	0.85	0.074	0.38	2.9	0.19	1.9	5.2	0.23	4	5.0	4.6
STD DS8	Standard	112	0.57	250	0.105	2	0.84	0.076	0.38	2.7	0.19	2.1	5.0	0.20	4	4.8	4.6
STD DS8	Standard	113	0.58	264	0.100	2	0.86	0.093	0.40	2.8	0.20	2.2	5.4	0.14	4	5.2	4.7
STD DS8	Standard	118	0.61	276	0.115	3	0.89	0.092	0.40	2.7	0.19	2.2	5.3	0.14	5	5.3	5.1
STD DS8	Standard	117	0.62	275	0.108	3	0.91	0.096	0.42	2.9	0.19	2.2	5.4	0.15	5	5.0	5.1
STD DS8	Standard	122	0.62	282	0.117	2	1.00	0.125	0.45	3.1	0.23	2.9	5.8	0.15	5	5.3	5.0
STD DS8	Standard	112	0.63	257	0.107	2	0.88	0.084	0.37	2.6	0.19	1.9	5.0	0.16	4	4.8	4.7
STD DS8	Standard	116	0.58	278	0.113	2	0.85	0.093	0.41	3.0	0.20	2.4	5.3	0.16	5	5.7	4.5
STD DS8	Standard	116	0.60	278	0.114	2	0.91	0.092	0.41	2.9	0.19	2.1	5.3	0.15	4	5.6	4.5
STD DS8	Standard	117	0.64	275	0.115	3	0.92	0.100	0.42	3.1	0.23	2.3	5.4	0.15	5	5.4	4.8
STD DS8	Standard	116	0.62	286	0.125	2	1.00	0.110	0.45	2.8	0.21	3.0	5.4	0.10	5	4.7	4.8
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

QUALITY CONTROL REPORT WHI11001376.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 04, 2011

QUALITY CONTROL REPORT WHI11001376.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 27, 2011
Report Date: October 27, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001377.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #20
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	319	Sieve soil to 230 mesh			WHI
RJSV	319	Saving all or part of Soil Reject			WHI
1DX2	306	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281881	Soil		34.6	86.6	15.2	813	0.9	161.2	8.5	182	2.00	41.8	1.1	1.7	114	6.0	9.4	0.2	241	3.22	0.167	17
1281882	Soil		11.5	25.4	10.4	1183	1.4	83.4	3.3	100	1.12	13.7	1.5	0.2	34	2.8	2.4	0.2	56	0.55	0.075	8
1281883	Soil		14.1	31.6	9.9	2892	0.5	189.7	4.8	174	1.55	17.1	1.3	0.6	47	3.2	3.5	0.2	90	1.29	0.120	8
1281884	Soil		12.8	35.5	11.2	1393	0.7	110.5	4.8	120	1.77	15.9	1.7	0.5	51	2.7	2.9	0.2	73	0.78	0.111	9
1281885	Soil		29.3	25.8	9.5	1015	0.5	101.1	2.9	60	0.94	23.1	<0.5	0.2	39	4.0	8.1	0.1	243	0.85	0.098	8
1281886	Soil		5.6	3.9	2.1	31	<0.1	6.3	0.3	3	0.15	3.5	0.6	<0.1	2	0.1	1.3	<0.1	63	0.01	0.028	2
1281887	Soil		49.3	34.6	9.4	405	0.3	86.4	3.6	50	1.23	35.8	<0.5	0.4	25	1.8	12.4	0.1	267	0.41	0.066	11
1281888	Soil		69.8	42.1	12.2	226	0.1	122.1	7.5	94	2.02	37.7	1.1	1.0	10	1.2	5.5	0.2	96	0.12	0.069	10
1281889	Soil		104.7	76.9	16.7	357	0.4	225.0	14.8	320	3.11	61.4	1.6	2.4	82	2.6	6.5	0.1	77	3.96	0.100	10
1281890	Soil		42.2	115.3	19.1	149	0.3	134.5	26.1	350	4.44	64.9	<0.5	3.5	174	1.3	3.6	<0.1	54	3.42	0.253	26
1281891	Soil		67.8	82.7	11.2	212	0.4	203.9	10.2	276	2.11	30.4	0.9	1.2	111	2.3	3.5	0.1	62	3.43	0.108	11
1281892	Soil		48.0	56.2	7.3	169	0.2	139.3	7.4	139	1.74	23.4	1.9	1.1	73	2.7	2.2	<0.1	47	2.08	0.101	10
1281893	Soil		80.2	72.0	14.0	404	0.3	185.8	10.6	256	2.48	57.5	<0.5	1.2	127	3.2	4.9	0.1	87	4.20	0.112	9
1281894	Soil		115.7	99.4	15.6	959	1.0	249.3	10.9	229	2.33	65.9	1.0	2.4	170	7.2	19.5	0.2	298	5.21	0.116	12
1281895	Soil		125.3	156.3	18.5	1931	2.8	316.7	5.1	97	1.57	87.0	1.5	1.4	268	17.0	40.3	0.2	547	7.24	0.118	12
1281896	Soil		130.1	138.1	17.2	1662	2.2	296.1	7.0	182	1.65	91.6	1.4	2.1	257	15.5	37.3	0.2	651	7.54	0.125	11
1281897	Soil		98.7	128.0	18.8	1379	2.6	233.6	7.6	245	1.64	67.4	1.8	1.2	146	18.8	26.0	0.2	492	4.85	0.095	13
1281898	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281899	Soil		10.3	32.6	27.6	157	1.4	40.6	7.7	190	3.29	20.8	1.7	1.9	17	0.3	4.1	0.4	108	0.03	0.034	11
1281900	Soil		3.8	6.5	61.0	28	2.7	7.3	0.9	27	0.56	4.5	1.1	0.7	82	<0.1	1.4	0.2	42	0.05	0.088	3
1282501	Soil		12.0	13.0	33.2	46	0.6	8.6	1.6	23	0.86	21.3	6.7	1.2	33	0.2	3.3	0.2	20	0.03	0.026	1
1282502	Soil		11.1	31.6	38.0	95	1.0	18.3	4.9	109	1.96	36.5	8.0	1.1	44	0.3	3.4	0.3	36	0.01	0.052	3
1282503	Soil		5.9	54.1	18.6	234	0.3	44.5	13.3	221	3.57	41.9	4.1	0.9	41	0.4	3.3	0.4	39	0.02	0.068	4
1282504	Soil		5.4	26.0	8.2	100	0.2	23.0	7.2	96	1.62	22.8	3.4	0.3	11	0.2	1.9	0.2	44	0.02	0.041	8
1282505	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1282506	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1282507	Soil		8.5	29.8	51.4	126	1.2	18.4	4.4	107	2.35	132.5	8.3	1.3	71	0.1	9.4	0.4	46	0.02	0.070	4
1282508	Soil		8.6	26.5	36.6	89	0.9	21.8	4.8	129	2.99	67.5	20.2	0.5	125	0.2	7.5	0.4	87	0.05	0.114	9
1282509	Soil		6.5	15.3	42.3	47	1.1	8.6	1.9	39	1.43	48.2	22.1	0.5	82	<0.1	6.9	0.2	46	0.02	0.066	4
1282510	Soil		7.3	16.3	49.7	49	2.0	8.6	1.9	41	1.57	54.4	73.6	0.9	174	0.2	15.1	0.3	74	0.03	0.095	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281881	Soil	22	1.42	613	0.005	11	0.44	0.005	0.12	0.2	0.70	3.7	1.5	<0.05	1	4.1	<0.2
1281882	Soil	9	0.08	471	0.004	4	0.60	0.015	0.06	0.1	0.20	0.8	0.9	<0.05	2	1.2	<0.2
1281883	Soil	11	0.30	297	0.004	7	0.73	0.013	0.05	<0.1	0.21	1.4	2.9	0.08	2	2.1	<0.2
1281884	Soil	16	0.17	412	0.004	3	0.80	0.010	0.06	0.1	0.23	1.6	2.0	0.07	2	1.8	<0.2
1281885	Soil	20	0.10	231	0.004	3	0.50	0.010	0.05	0.2	0.09	0.8	2.9	0.09	2	2.6	<0.2
1281886	Soil	5	0.01	17	0.002	2	0.12	0.006	0.02	<0.1	<0.01	0.4	0.3	<0.05	<1	<0.5	<0.2
1281887	Soil	20	0.10	236	0.004	3	0.57	0.014	0.05	0.2	0.15	1.0	1.8	<0.05	2	2.2	<0.2
1281888	Soil	12	0.05	723	0.006	5	0.36	0.003	0.08	0.3	0.14	2.0	1.7	0.06	1	1.5	<0.2
1281889	Soil	14	1.55	249	0.004	6	0.22	0.007	0.07	0.3	0.70	4.5	2.2	0.08	<1	5.2	<0.2
1281890	Soil	12	1.06	554	0.007	12	0.50	0.008	0.15	0.2	0.75	4.9	1.7	0.22	1	1.8	<0.2
1281891	Soil	19	1.32	295	0.004	10	0.38	0.005	0.12	0.3	0.13	3.8	3.1	0.08	<1	2.5	<0.2
1281892	Soil	15	0.81	247	0.002	7	0.32	0.003	0.06	0.2	0.19	3.7	1.6	0.05	<1	1.4	<0.2
1281893	Soil	15	1.69	347	0.003	6	0.29	0.007	0.07	0.2	0.38	3.4	1.7	0.09	<1	3.2	<0.2
1281894	Soil	24	2.06	430	0.004	9	0.33	0.006	0.09	0.3	0.59	3.9	3.0	<0.05	1	4.8	<0.2
1281895	Soil	31	1.28	581	0.004	8	0.32	0.005	0.10	0.4	1.03	2.7	3.9	<0.05	1	7.2	0.2
1281896	Soil	36	1.85	473	0.005	10	0.38	0.007	0.12	0.4	0.98	3.1	4.9	0.06	1	8.3	0.3
1281897	Soil	30	2.16	389	0.004	7	0.38	0.008	0.09	0.3	0.78	3.1	2.4	<0.05	1	7.9	0.2
1281898	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281899	Soil	21	0.11	142	0.011	3	0.98	0.003	0.06	0.2	0.03	2.7	0.4	<0.05	5	2.6	<0.2
1281900	Soil	11	0.02	231	0.004	2	0.31	0.002	0.05	<0.1	0.05	0.8	0.2	<0.05	2	0.8	<0.2
1282501	Soil	7	<0.01	220	<0.001	4	0.20	0.002	0.07	<0.1	1.75	1.6	0.4	0.08	<1	1.4	<0.2
1282502	Soil	11	0.01	211	0.002	3	0.34	0.003	0.08	<0.1	8.00	1.9	0.4	0.08	2	2.2	<0.2
1282503	Soil	13	0.02	139	0.002	3	0.31	0.003	0.06	0.1	0.32	2.5	0.2	0.05	2	0.9	<0.2
1282504	Soil	12	0.02	71	0.003	2	0.26	0.003	0.04	0.1	0.21	1.0	0.2	<0.05	2	0.6	<0.2
1282505	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1282506	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1282507	Soil	11	0.03	367	0.002	3	0.42	0.003	0.14	<0.1	0.17	4.8	0.5	0.11	2	4.7	<0.2
1282508	Soil	19	0.11	702	0.008	2	0.76	0.005	0.14	0.2	0.26	1.4	0.4	0.17	4	4.8	<0.2
1282509	Soil	10	0.03	636	0.003	2	0.27	0.005	0.12	<0.1	0.29	1.5	0.3	0.23	2	4.8	<0.2
1282510	Soil	14	0.04	1141	0.006	3	0.33	0.006	0.15	<0.1	0.68	1.9	0.6	0.33	3	5.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282511	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1282512	Soil		13.0	22.0	38.6	74	1.2	14.6	3.6	79	1.76	29.0	19.6	0.4	69	<0.1	6.0	0.3	63	0.03	0.089	6
1282513	Soil		7.1	27.6	21.2	85	0.7	19.2	4.7	100	1.68	20.3	5.4	0.2	38	0.2	3.4	0.2	46	0.03	0.093	5
1282514	Soil		3.5	11.4	11.8	36	0.2	7.3	1.7	37	0.76	11.0	2.4	<0.1	14	<0.1	1.1	0.2	33	0.03	0.047	5
1282515	Soil		13.4	20.5	29.7	55	0.6	11.4	2.6	44	1.53	75.1	23.6	0.2	64	0.1	10.4	0.3	94	0.03	0.076	6
1282516	Soil		15.4	20.1	50.5	43	1.7	9.0	2.1	38	2.11	60.8	20.1	0.6	109	<0.1	11.1	0.5	85	0.03	0.108	4
1282517	Soil		14.3	20.3	60.0	11	1.7	3.3	0.4	16	1.21	70.0	57.6	0.5	98	0.1	11.5	0.4	67	0.02	0.100	3
1282518	Soil		9.8	15.6	55.4	18	1.3	4.0	1.3	73	1.22	51.7	40.5	0.3	76	0.1	7.1	0.3	53	0.03	0.090	4
1282519	Soil		12.1	18.7	77.0	24	1.5	5.3	1.0	29	1.40	57.1	32.6	0.9	130	0.3	11.1	0.4	90	0.03	0.116	7
1282520	Soil		2.8	8.3	14.0	37	0.2	7.9	2.5	37	0.83	15.6	11.9	0.3	19	<0.1	2.1	0.1	30	0.01	0.044	4
1282521	Soil		3.4	9.7	11.0	43	<0.1	9.5	3.1	42	1.09	35.1	4.0	0.2	19	<0.1	1.9	0.1	34	0.01	0.040	4
1282522	Soil		5.6	24.9	22.4	114	0.2	24.0	7.5	110	3.75	51.9	2.6	0.9	23	<0.1	3.6	0.3	56	0.01	0.062	6
1282523	Soil		4.5	19.5	17.5	91	0.2	21.4	6.1	114	2.06	36.4	5.2	0.6	25	0.1	2.8	0.2	40	0.04	0.061	6
1282524	Soil		4.6	15.5	17.1	68	0.6	15.4	4.2	72	1.62	31.7	12.1	0.3	29	0.2	3.4	0.2	39	0.02	0.043	5
1282525	Soil		4.8	18.3	15.4	94	0.3	20.5	5.6	82	2.09	35.1	6.1	0.3	21	<0.1	3.0	0.2	47	0.03	0.049	9
1282526	Soil		2.0	6.0	4.9	25	0.5	5.1	1.5	22	0.53	8.1	<0.5	<0.1	10	<0.1	0.9	<0.1	28	0.01	0.029	7
1282527	Soil		4.4	9.8	9.5	51	0.6	9.9	2.6	35	0.93	17.1	1.0	0.2	15	<0.1	2.1	0.1	49	0.01	0.048	7
1282528	Soil		9.3	54.7	18.3	95	3.5	25.2	3.8	65	2.78	36.5	1.6	1.1	61	0.1	2.3	0.2	34	0.02	0.068	4
1282529	Soil		2.9	40.4	13.2	185	0.8	66.1	9.5	138	2.50	10.4	4.7	1.0	49	2.3	1.0	0.2	25	0.75	0.059	4
1282530	Soil		0.9	5.9	3.6	71	0.1	15.7	2.7	31	0.73	6.1	1.7	0.1	13	0.5	0.5	<0.1	13	0.04	0.043	2
1282531	Soil		3.6	23.0	14.4	192	0.8	47.0	6.8	128	2.10	27.4	6.9	1.1	52	2.1	2.9	0.2	52	0.23	0.071	9
1282532	Soil		2.2	18.6	11.4	226	0.6	35.4	6.6	214	1.55	8.4	1.3	0.3	52	9.1	1.4	0.2	33	2.00	0.107	9
1282533	Soil		3.5	46.5	23.9	178	0.9	72.9	10.7	111	2.97	18.0	2.6	1.8	101	0.4	1.5	0.2	32	0.13	0.082	7
1282534	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1282535	Soil		0.3	6.3	3.6	16	0.1	3.7	1.0	26	0.47	2.0	<0.5	<0.1	14	0.1	0.2	<0.1	10	0.14	0.057	3
1282536	Soil		3.9	18.3	38.4	66	0.2	32.9	5.7	73	1.56	26.0	4.8	0.6	14	0.7	2.8	<0.1	36	0.14	0.041	3
1282537	Soil		3.4	68.5	26.8	107	2.1	35.7	4.6	64	2.18	14.0	3.3	0.3	19	0.7	2.0	0.2	39	0.06	0.152	3
1282538	Soil		4.7	43.1	38.1	73	3.3	37.0	3.6	40	1.54	8.8	3.1	0.4	14	0.5	1.2	0.2	34	0.11	0.102	3
1282539	Soil		2.5	27.3	10.8	75	0.3	25.9	4.4	48	1.64	12.4	1.7	0.7	19	0.3	1.3	0.1	34	0.11	0.072	5
1282540	Soil		1.5	15.8	7.9	35	0.1	15.0	1.9	23	0.80	3.6	<0.5	0.1	18	0.2	0.6	<0.1	20	0.04	0.061	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282511	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1282512	Soil	13	0.04	730	0.008	3	0.32	0.005	0.12	0.2	0.48	1.3	0.5	0.29	2	4.9	<0.2
1282513	Soil	13	0.07	507	0.007	4	0.44	0.010	0.08	0.2	0.18	1.1	0.3	0.19	2	2.4	<0.2
1282514	Soil	8	0.03	163	0.006	2	0.35	0.015	0.04	0.1	0.11	0.4	0.1	0.07	2	<0.5	<0.2
1282515	Soil	12	0.02	841	0.007	2	0.38	0.006	0.08	0.2	0.52	0.6	0.7	0.18	3	4.3	<0.2
1282516	Soil	18	0.01	833	0.003	3	0.30	0.004	0.20	0.2	1.62	1.0	0.9	0.39	4	8.1	<0.2
1282517	Soil	16	0.02	1250	0.002	4	0.46	0.006	0.14	0.1	4.01	1.6	1.0	0.25	2	8.5	<0.2
1282518	Soil	14	0.04	984	0.003	4	0.56	0.009	0.13	0.1	2.02	1.4	0.7	0.21	3	4.7	<0.2
1282519	Soil	18	0.04	1579	0.006	6	0.52	0.006	0.15	0.4	3.83	1.7	1.7	0.22	3	9.3	<0.2
1282520	Soil	5	0.02	174	0.002	2	0.32	0.014	0.05	<0.1	0.44	0.7	0.2	<0.05	2	0.8	<0.2
1282521	Soil	5	0.01	193	0.002	2	0.32	0.013	0.04	<0.1	0.26	0.5	0.2	<0.05	2	1.0	<0.2
1282522	Soil	12	0.03	164	0.003	2	0.57	0.003	0.05	0.2	0.09	2.1	0.2	<0.05	5	1.6	<0.2
1282523	Soil	11	0.09	294	0.003	<1	0.56	0.006	0.06	<0.1	0.39	1.5	0.2	<0.05	2	1.4	<0.2
1282524	Soil	9	0.06	287	0.006	1	0.45	0.014	0.06	0.1	0.80	0.8	0.4	<0.05	2	2.8	<0.2
1282525	Soil	12	0.07	145	0.005	<1	0.53	0.005	0.06	0.1	0.20	0.8	0.2	<0.05	3	1.0	<0.2
1282526	Soil	5	0.02	94	0.003	1	0.22	0.014	0.04	<0.1	0.07	0.4	<0.1	<0.05	2	<0.5	<0.2
1282527	Soil	7	0.02	175	0.002	2	0.32	0.009	0.05	<0.1	0.14	0.5	0.2	<0.05	2	0.7	<0.2
1282528	Soil	32	0.04	935	0.001	3	0.54	0.005	0.11	<0.1	0.51	3.0	0.1	0.11	2	11.4	<0.2
1282529	Soil	21	0.06	532	0.001	2	0.56	0.006	0.06	<0.1	0.15	2.7	<0.1	<0.05	2	2.2	<0.2
1282530	Soil	5	0.02	106	0.007	<1	0.26	0.017	0.03	<0.1	0.05	0.6	<0.1	<0.05	1	<0.5	<0.2
1282531	Soil	17	0.04	334	0.005	3	0.69	0.005	0.06	0.1	0.26	1.9	0.2	<0.05	3	1.8	<0.2
1282532	Soil	13	0.03	753	0.005	5	0.55	0.008	0.05	<0.1	0.07	1.6	0.1	0.10	2	2.2	<0.2
1282533	Soil	20	0.04	772	<0.001	2	1.03	0.007	0.09	<0.1	0.12	3.7	0.3	0.06	3	3.3	<0.2
1282534	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1282535	Soil	4	0.03	78	0.010	<1	0.51	0.031	0.03	<0.1	<0.01	0.4	<0.1	<0.05	2	<0.5	<0.2
1282536	Soil	21	0.03	218	0.002	6	0.42	0.012	0.05	<0.1	0.11	1.3	0.2	<0.05	2	<0.5	<0.2
1282537	Soil	23	0.03	363	0.004	4	0.53	0.009	0.08	<0.1	0.25	2.1	0.1	<0.05	2	1.4	<0.2
1282538	Soil	34	0.02	303	0.004	4	0.45	0.014	0.05	<0.1	0.15	2.1	<0.1	0.08	2	1.4	<0.2
1282539	Soil	13	0.02	277	0.003	2	0.55	0.008	0.06	<0.1	0.05	1.6	0.1	0.05	3	0.5	<0.2
1282540	Soil	10	0.02	100	0.006	2	0.29	0.018	0.04	<0.1	0.01	0.8	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282601	Soil	3.1	25.9	14.7	88	0.3	26.4	6.4	169	3.24	15.1	2.1	2.7	16	0.2	1.4	0.2	52	0.08	0.058	9
1282602	Soil	10.2	55.9	38.9	183	2.6	69.8	13.0	250	5.30	20.7	3.3	3.9	90	0.4	2.1	0.4	31	0.04	0.117	6
1282603	Soil	1.2	36.5	18.7	107	1.1	45.3	8.8	190	2.25	11.9	3.4	1.2	69	0.6	1.0	0.3	30	1.74	0.105	9
1282604	Soil	1.0	37.3	11.9	159	1.1	51.2	9.0	236	2.13	9.1	3.2	1.3	65	0.9	0.9	0.2	35	1.26	0.134	11
1282605	Soil	1.7	31.9	21.3	76	1.4	28.1	4.8	254	2.47	12.7	3.8	1.1	96	0.6	1.1	0.2	31	1.76	0.149	10
1282606	Soil	2.0	22.0	12.9	61	0.2	15.0	3.2	67	1.80	66.2	3.7	0.4	23	0.1	2.0	0.2	32	0.24	0.097	4
1282607	Soil	2.3	51.7	18.2	103	0.6	31.1	7.0	191	3.72	29.3	5.6	2.0	39	0.2	1.6	0.3	43	0.01	0.075	5
1282608	Soil	2.9	24.1	16.7	84	0.2	21.0	4.7	153	3.29	20.0	1.8	1.2	16	0.3	1.7	0.3	64	0.03	0.082	6
1282609	Soil	3.8	30.7	25.4	91	0.3	24.1	5.7	164	3.58	17.5	3.0	1.7	29	0.2	1.7	0.3	73	0.02	0.056	9
1282610	Soil	3.1	27.7	26.5	80	0.4	24.4	5.5	122	3.11	15.8	3.9	1.4	24	<0.1	1.6	0.3	56	0.02	0.112	5
1282641	Soil	0.6	15.7	11.1	44	0.3	8.6	2.5	155	0.82	2.5	2.0	0.8	46	1.0	0.4	0.2	26	0.91	0.037	6
1282642	Soil	0.9	21.2	13.6	190	0.7	28.1	9.6	530	2.27	7.7	1.2	0.7	60	2.0	0.7	0.2	51	1.56	0.086	14
1282643	Soil	1.6	22.3	8.4	185	2.8	39.3	5.3	303	1.55	7.4	2.1	0.4	78	1.8	0.9	0.2	29	1.26	0.145	13
1282644	Soil	15.0	38.2	16.5	262	3.6	82.7	7.7	337	3.78	20.2	7.3	0.4	59	3.0	3.6	0.2	56	1.37	0.151	24
1282645	Soil	1.0	7.5	54.7	25	<0.1	4.5	0.5	13	0.86	70.1	19.2	0.2	6	0.1	5.2	0.1	22	0.01	0.019	4
1282646	Soil	2.7	36.8	18.2	95	0.1	28.8	7.5	158	3.89	23.6	3.0	2.8	13	0.3	1.4	0.3	56	0.05	0.052	8
1282647	Soil	2.2	35.8	27.4	90	0.3	31.3	8.9	217	3.65	35.1	6.7	3.3	12	0.3	1.5	0.3	48	0.03	0.050	8
1282648	Soil	1.8	27.7	17.2	103	0.8	33.7	9.6	160	2.92	28.6	2.6	1.6	32	0.3	1.0	0.2	41	0.43	0.047	6
1282649	Soil	1.5	54.0	18.7	141	1.1	58.0	14.1	107	2.53	15.7	2.1	3.0	31	0.4	0.5	0.2	26	0.28	0.071	5
1282650	Soil	1.5	19.2	17.8	53	0.1	8.1	1.4	39	1.12	50.9	4.8	0.5	8	0.7	1.4	0.1	30	0.02	0.039	2
1283001	Soil	6.8	14.1	21.5	55	1.4	14.1	2.0	38	0.81	11.2	1.3	0.2	15	0.2	1.5	0.1	57	0.03	0.048	5
1283002	Soil	7.5	27.3	22.2	79	0.6	19.1	3.1	52	1.44	21.5	1.1	0.1	10	0.3	2.1	0.2	78	0.03	0.050	10
1283003	Soil	6.2	22.2	11.2	80	0.4	17.4	3.4	51	1.40	12.5	1.1	0.1	9	0.2	2.1	0.2	84	0.02	0.042	9
1283004	Soil	2.9	17.1	7.5	32	0.3	7.7	1.6	25	0.64	5.5	0.5	0.1	6	<0.1	0.8	0.2	45	0.02	0.036	10
1283005	Soil	7.6	29.6	22.1	152	0.8	30.3	5.6	162	3.74	20.8	2.6	0.5	16	0.3	3.1	0.3	82	0.03	0.095	8
1283006	Soil	8.9	17.8	13.8	82	0.6	19.4	3.2	57	1.43	11.7	1.0	0.2	11	0.3	2.2	0.2	99	0.02	0.045	8
1283007	Soil	9.9	21.4	20.6	73	0.4	18.8	3.0	58	1.43	12.3	1.2	<0.1	15	0.2	1.9	0.2	75	0.02	0.091	7
1283008	Soil	5.3	15.2	12.2	74	<0.1	16.2	2.9	43	1.26	13.1	0.9	0.1	15	0.2	1.5	0.2	63	0.03	0.072	5
1283009	Soil	3.9	15.9	8.2	49	0.4	12.3	2.0	35	0.75	5.4	0.5	0.1	12	0.9	1.0	0.1	47	0.04	0.055	4
1283010	Soil	8.2	18.4	22.2	68	0.7	21.2	4.2	234	1.33	9.9	3.9	0.4	37	0.6	2.1	0.2	66	0.12	0.106	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282601	Soil	31	0.32	160	0.009	3	1.31	0.005	0.07	0.2	0.04	2.0	0.1	<0.05	4	1.1	<0.2
1282602	Soil	29	0.16	543	0.003	2	1.36	0.010	0.10	<0.1	0.22	5.3	0.2	0.22	3	5.9	0.2
1282603	Soil	23	0.23	551	0.002	4	0.92	0.005	0.07	<0.1	0.12	1.9	0.1	0.09	2	3.2	<0.2
1282604	Soil	25	0.23	504	0.004	4	1.01	0.009	0.07	<0.1	0.17	2.1	0.1	0.08	3	2.2	<0.2
1282605	Soil	23	0.11	817	0.002	3	0.77	0.007	0.09	<0.1	0.19	2.0	0.1	0.16	2	2.5	0.3
1282606	Soil	20	0.05	282	0.003	2	0.73	0.008	0.06	0.1	0.10	0.9	0.1	0.07	3	1.6	<0.2
1282607	Soil	31	0.31	222	0.002	2	1.47	0.007	0.08	<0.1	0.18	2.8	0.2	<0.05	4	2.1	<0.2
1282608	Soil	25	0.18	236	0.005	1	1.26	0.004	0.07	0.1	0.08	1.4	0.2	<0.05	5	1.2	<0.2
1282609	Soil	27	0.16	209	0.007	1	0.99	0.004	0.08	0.1	0.05	1.9	0.2	<0.05	6	0.7	<0.2
1282610	Soil	31	0.15	287	0.004	4	1.13	0.007	0.12	0.1	0.08	2.2	0.2	0.07	5	1.1	<0.2
1282641	Soil	14	0.09	361	0.004	<1	0.64	0.008	0.05	<0.1	0.01	0.9	<0.1	<0.05	3	<0.5	<0.2
1282642	Soil	30	0.31	576	0.009	2	1.43	0.011	0.06	0.1	0.05	2.0	0.1	0.06	4	1.7	<0.2
1282643	Soil	16	0.07	348	0.005	3	0.92	0.024	0.04	<0.1	0.18	1.2	<0.1	0.07	2	2.1	<0.2
1282644	Soil	20	0.15	217	0.003	3	0.80	0.016	0.03	<0.1	0.24	2.3	0.1	<0.05	2	4.9	<0.2
1282645	Soil	9	<0.01	29	0.004	1	0.14	0.004	<0.01	0.2	0.06	0.4	<0.1	<0.05	1	0.7	<0.2
1282646	Soil	36	0.30	133	0.005	2	2.09	0.005	0.05	0.2	0.10	2.2	0.1	<0.05	5	1.3	<0.2
1282647	Soil	35	0.37	149	0.004	2	1.74	0.004	0.06	0.2	0.12	2.3	0.1	<0.05	5	0.9	<0.2
1282648	Soil	23	0.17	461	0.002	2	1.12	0.013	0.06	<0.1	0.10	2.0	0.1	<0.05	3	1.1	<0.2
1282649	Soil	26	0.24	241	0.002	3	1.14	0.004	0.08	<0.1	0.20	3.1	<0.1	<0.05	3	1.1	<0.2
1282650	Soil	10	0.01	93	0.004	4	0.24	0.009	0.03	<0.1	0.07	1.0	<0.1	0.09	2	0.9	<0.2
1283001	Soil	9	0.03	177	0.003	1	0.57	0.011	0.04	<0.1	0.04	0.4	0.2	<0.05	2	0.9	<0.2
1283002	Soil	14	0.02	134	0.005	2	0.63	0.008	0.05	<0.1	0.03	0.3	0.2	<0.05	3	1.7	<0.2
1283003	Soil	12	0.02	111	0.006	<1	0.50	0.005	0.04	0.1	0.04	0.4	0.2	<0.05	3	1.6	<0.2
1283004	Soil	9	0.02	89	0.005	1	0.54	0.008	0.03	<0.1	0.02	0.2	0.1	<0.05	3	0.6	<0.2
1283005	Soil	22	0.11	264	0.004	2	1.05	0.003	0.06	0.1	0.13	1.0	0.3	<0.05	4	1.9	<0.2
1283006	Soil	11	0.04	207	0.004	1	0.65	0.004	0.05	0.1	0.02	0.5	0.3	<0.05	3	0.9	<0.2
1283007	Soil	14	0.03	282	0.002	2	0.57	0.007	0.07	<0.1	0.05	0.2	0.6	<0.05	3	0.8	<0.2
1283008	Soil	10	0.03	349	0.002	2	0.48	0.007	0.05	<0.1	0.02	0.3	0.3	<0.05	3	0.9	<0.2
1283009	Soil	10	0.02	399	0.003	1	0.38	0.010	0.04	<0.1	0.02	0.4	0.2	<0.05	2	0.6	<0.2
1283010	Soil	12	0.04	818	0.003	4	0.55	0.006	0.08	<0.1	0.07	1.6	0.8	0.10	2	2.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283011	Soil	4.6	16.1	9.3	46	0.3	10.7	2.2	31	0.84	8.1	1.1	0.1	11	0.3	1.1	0.2	46	0.02	0.057	8
1283012	Soil	4.2	13.8	11.7	43	0.8	12.4	2.2	37	1.05	8.9	1.8	<0.1	10	0.2	1.1	0.2	52	0.02	0.048	8
1283013	Soil	4.6	12.9	12.2	54	0.3	11.4	2.7	53	1.27	15.2	0.7	0.2	16	0.1	1.4	0.2	59	0.02	0.053	7
1283014	Soil	7.5	25.5	23.2	95	0.8	24.3	5.4	123	2.88	25.4	3.3	1.8	37	0.2	2.9	0.3	77	0.03	0.105	6
1283015	Soil	5.0	16.7	37.9	38	1.5	9.4	1.9	56	1.54	25.0	1.7	0.1	28	0.2	1.6	0.2	58	0.04	0.183	5
1283016	Soil	5.4	11.4	10.9	42	2.2	9.2	2.0	34	0.84	8.5	0.6	0.2	11	0.1	1.1	0.1	46	0.02	0.043	11
1283017	Soil	4.3	13.0	7.8	44	0.2	9.1	2.0	34	0.80	9.6	<0.5	0.2	8	<0.1	1.2	0.1	51	0.02	0.029	8
1283018	Soil	5.1	15.4	7.0	62	0.4	17.2	3.3	44	1.17	9.8	<0.5	0.2	7	0.3	1.3	0.1	44	0.02	0.040	4
1283019	Soil	2.1	14.8	8.3	49	0.4	11.1	2.5	38	0.80	5.1	0.7	0.1	13	0.5	0.7	0.1	31	0.06	0.080	4
1283020	Soil	1.5	21.3	5.5	60	1.2	20.3	3.1	136	0.75	3.6	2.0	0.3	49	0.7	0.5	0.1	23	0.74	0.089	4
1283021	Soil	1.7	34.8	10.0	86	0.8	29.8	5.7	175	1.59	7.7	3.9	0.8	45	0.8	0.8	0.2	40	0.59	0.080	5
1283022	Soil	2.2	49.3	36.2	64	1.2	31.7	7.2	165	1.65	7.9	3.1	0.7	69	1.5	1.3	0.3	57	0.69	0.095	4
1283023	Soil	1.2	37.1	12.0	36	0.6	26.1	4.6	70	0.96	3.5	1.2	0.5	35	2.6	0.4	0.1	23	0.40	0.062	4
1283024	Soil	4.5	27.5	31.0	66	1.0	22.7	4.5	109	1.47	11.5	2.9	0.4	63	1.6	1.5	0.2	44	0.43	0.101	4
1283025	Soil	4.5	32.2	38.5	45	0.8	24.8	4.0	62	1.15	8.1	3.1	0.7	56	0.7	0.8	0.3	44	0.22	0.087	3
1283026	Soil	1.9	25.4	11.6	37	0.4	28.9	4.4	91	1.22	5.5	1.8	0.7	90	0.4	0.6	0.1	19	1.53	0.062	3
1283027	Soil	2.4	15.8	16.8	75	0.3	18.7	3.4	134	1.04	6.1	1.9	0.7	99	0.6	0.9	0.1	26	1.13	0.046	2
1283028	Soil	2.8	18.8	14.4	80	0.4	25.2	7.4	267	1.38	8.9	1.2	0.8	93	0.4	1.1	0.1	31	1.18	0.056	2
1283029	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283030	Soil	4.5	16.8	14.5	53	0.5	17.0	11.3	817	1.38	8.2	<0.5	0.5	75	0.6	1.2	0.2	25	0.87	0.057	2
1283031	Soil	1.6	29.9	16.7	72	0.7	48.8	14.7	423	2.10	11.4	1.1	0.9	125	0.7	1.2	0.2	24	1.41	0.072	4
1283032	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283033	Soil	0.7	7.9	3.2	29	0.3	8.2	4.3	129	0.52	2.1	1.8	0.1	29	0.3	0.3	<0.1	9	0.36	0.032	1
1283034	Soil	1.9	9.8	6.9	34	0.5	10.2	2.1	53	0.94	6.0	1.1	0.4	36	0.3	0.6	<0.1	19	0.17	0.045	2
1283035	Soil	2.8	16.3	12.1	102	0.2	20.8	6.9	112	2.04	15.3	1.3	1.6	38	0.3	0.9	0.2	34	0.13	0.055	4
1283036	Soil	2.2	7.1	7.2	33	0.2	6.9	1.7	37	0.95	9.8	1.1	0.8	10	0.2	0.8	0.1	35	0.02	0.027	7
1283037	Soil	3.1	10.3	11.0	59	0.5	11.6	3.4	94	1.97	16.0	1.4	1.4	9	0.1	1.3	0.2	53	0.02	0.042	8
1283038	Soil	8.2	22.8	18.3	103	0.4	24.6	5.0	119	2.41	17.1	0.9	1.1	22	0.5	2.3	0.2	73	0.02	0.051	6
1283039	Soil	5.9	28.5	15.9	96	0.3	21.5	5.1	95	2.04	16.4	0.5	0.4	13	0.3	2.0	0.2	57	0.01	0.060	5
1283040	Soil	4.1	39.0	17.6	133	0.4	17.9	4.0	74	1.91	9.5	1.8	0.1	31	1.1	1.6	0.3	57	0.02	0.075	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283011	Soil	8	0.02	178	0.004	1	0.45	0.006	0.04	<0.1	0.02	0.3	0.2	<0.05	3	0.7	<0.2
1283012	Soil	15	0.03	123	0.005	<1	0.55	0.008	0.04	<0.1	0.04	0.2	0.1	<0.05	3	0.6	<0.2
1283013	Soil	9	0.03	151	0.004	1	0.46	0.003	0.04	<0.1	0.02	0.4	0.2	<0.05	3	0.7	<0.2
1283014	Soil	23	0.10	253	0.002	1	1.17	0.003	0.07	0.1	0.06	3.3	0.3	0.07	4	2.6	<0.2
1283015	Soil	19	0.05	237	0.005	1	0.67	0.009	0.05	<0.1	0.09	0.6	0.2	0.06	4	2.6	<0.2
1283016	Soil	10	0.02	248	0.004	2	0.44	0.004	0.04	0.1	0.03	0.5	0.2	<0.05	4	0.7	<0.2
1283017	Soil	7	0.03	148	0.005	<1	0.55	0.010	0.03	0.1	0.02	0.6	0.2	<0.05	3	0.6	<0.2
1283018	Soil	13	0.02	128	0.003	1	0.41	0.008	0.03	<0.1	0.02	0.5	<0.1	<0.05	2	<0.5	<0.2
1283019	Soil	9	0.03	395	0.003	1	0.53	0.011	0.05	<0.1	0.02	0.5	0.1	<0.05	2	<0.5	<0.2
1283020	Soil	12	0.13	1028	0.004	2	0.79	0.025	0.04	<0.1	0.12	1.4	0.1	0.06	2	1.0	<0.2
1283021	Soil	19	0.17	1140	0.002	2	1.11	0.011	0.06	<0.1	0.11	2.6	0.2	0.05	3	1.3	<0.2
1283022	Soil	18	0.08	1071	0.004	4	1.01	0.010	0.07	<0.1	0.17	3.9	0.3	0.10	3	1.6	<0.2
1283023	Soil	11	0.08	532	0.002	<1	0.75	0.012	0.04	<0.1	0.07	2.1	0.1	0.05	2	1.2	<0.2
1283024	Soil	20	0.07	420	0.002	2	0.60	0.008	0.08	<0.1	0.08	1.1	0.2	0.09	2	2.3	<0.2
1283025	Soil	22	0.08	514	<0.001	3	0.63	0.005	0.08	<0.1	0.21	1.9	0.4	<0.05	2	1.2	<0.2
1283026	Soil	19	0.20	863	0.002	3	0.80	0.014	0.06	<0.1	0.12	1.9	0.2	0.11	2	2.6	<0.2
1283027	Soil	13	0.17	841	0.002	5	0.61	0.008	0.08	<0.1	0.11	1.5	0.3	0.18	2	1.9	<0.2
1283028	Soil	16	0.18	1170	0.001	4	0.67	0.006	0.08	<0.1	0.15	2.1	0.3	0.16	2	1.7	<0.2
1283029	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283030	Soil	7	0.12	851	0.004	3	0.49	0.008	0.06	<0.1	0.12	1.2	0.2	<0.05	1	<0.5	<0.2
1283031	Soil	13	0.17	1381	0.003	2	0.83	0.006	0.06	<0.1	0.21	2.7	0.2	0.08	2	1.6	<0.2
1283032	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283033	Soil	4	0.05	164	0.005	1	0.37	0.024	0.03	<0.1	0.05	0.5	<0.1	<0.05	<1	<0.5	<0.2
1283034	Soil	10	0.06	373	0.004	2	0.42	0.015	0.04	<0.1	0.09	1.0	<0.1	<0.05	2	1.0	<0.2
1283035	Soil	14	0.16	533	0.002	<1	0.63	0.004	0.05	0.1	0.04	1.6	<0.1	<0.05	2	<0.5	<0.2
1283036	Soil	6	0.03	181	0.004	<1	0.43	0.003	0.03	0.1	0.01	0.5	<0.1	<0.05	3	<0.5	<0.2
1283037	Soil	10	0.06	152	0.006	1	0.74	0.003	0.03	0.2	0.02	1.0	0.1	<0.05	4	0.6	<0.2
1283038	Soil	16	0.10	227	0.004	1	0.97	0.007	0.06	<0.1	0.04	1.6	0.3	<0.05	3	1.3	<0.2
1283039	Soil	10	0.03	151	0.002	<1	0.45	0.002	0.05	<0.1	0.04	1.2	0.2	<0.05	2	0.9	<0.2
1283040	Soil	11	0.02	125	0.004	2	0.47	0.006	0.04	<0.1	0.03	0.8	0.1	<0.05	2	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283041	Soil	3.8	31.8	26.3	150	0.2	22.0	4.4	76	1.72	13.9	0.7	0.2	34	0.6	2.0	0.3	53	0.02	0.081	7
1283042	Soil	3.9	50.5	20.7	213	1.3	29.3	9.6	448	2.42	12.8	0.7	0.3	15	5.2	1.5	0.3	64	0.03	0.080	7
1283043	Soil	1.1	10.6	7.0	36	0.2	7.7	1.4	37	0.60	3.1	0.8	<0.1	7	1.4	0.4	<0.1	16	0.03	0.054	2
1283044	Soil	1.2	41.2	7.6	80	1.4	29.7	4.9	250	0.85	2.9	2.1	0.2	38	1.4	0.6	0.1	18	0.94	0.082	3
1283045	Soil	0.9	90.8	9.0	98	1.6	47.4	5.1	194	1.08	6.1	1.3	0.1	41	3.5	0.4	0.1	36	1.12	0.106	5
1283046	Soil	1.3	7.4	4.4	22	0.3	5.9	1.5	31	0.66	4.9	0.6	<0.1	5	<0.1	0.5	<0.1	20	0.02	0.027	3
1283047	Soil	4.5	21.3	10.4	70	0.3	13.6	3.2	63	1.40	12.8	<0.5	0.7	10	0.7	1.2	0.2	61	0.03	0.058	7
1283048	Soil	0.4	16.9	4.7	25	0.8	11.6	3.4	99	0.50	1.4	0.8	0.1	28	0.6	0.3	<0.1	8	0.72	0.045	2
1283049	Soil	1.5	42.8	11.9	64	0.6	18.9	4.0	88	1.57	6.7	1.1	1.4	19	0.8	0.6	0.2	34	0.17	0.036	6
1283050	Soil	1.8	36.4	9.8	59	0.2	19.0	6.5	124	1.53	7.9	0.8	0.7	15	0.8	1.0	0.2	22	0.13	0.050	4
1283051	Soil	35.0	35.7	12.0	185	0.5	76.6	5.9	83	1.99	16.6	<0.5	0.9	18	0.5	4.1	0.2	104	0.15	0.081	13
1283052	Soil	11.8	23.6	17.5	149	0.6	35.6	4.6	70	2.70	17.1	<0.5	0.7	12	0.4	3.4	0.3	85	0.02	0.082	11
1283053	Soil	6.2	19.4	9.7	91	0.3	22.9	4.6	59	1.73	9.3	1.9	0.9	11	0.1	1.8	0.2	53	0.01	0.034	15
1283054	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283055	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283056	Soil	9.7	62.7	15.8	300	1.0	64.7	7.5	199	2.28	19.8	3.9	2.0	61	2.6	3.6	0.2	58	0.77	0.152	12
1283057	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283058	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283059	Soil	6.1	39.1	12.6	105	0.3	27.1	8.5	111	1.85	22.2	<0.5	1.0	14	0.4	1.7	0.1	39	0.28	0.058	8
1283060	Soil	10.7	32.7	23.6	39	0.2	24.8	5.7	67	2.05	79.6	1.9	1.3	10	0.4	3.0	0.3	61	0.15	0.065	12
1283061	Soil	45.3	67.1	11.9	251	0.2	130.5	15.4	279	2.91	43.3	1.1	2.6	154	2.1	4.4	0.1	55	5.34	0.148	15
1283062	Soil	38.6	52.4	12.3	210	0.2	107.8	13.7	247	2.97	49.5	2.0	2.4	114	1.5	3.7	0.2	51	4.25	0.146	13
1283063	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283064	Soil	12.0	13.3	7.6	77	0.2	18.1	2.2	35	0.92	9.9	1.9	0.2	11	0.2	1.4	0.1	45	0.03	0.041	7
1283065	Soil	49.9	58.2	18.2	634	0.6	97.2	8.6	298	2.63	51.8	4.0	3.2	89	7.4	12.6	0.2	133	1.63	0.093	12
1283066	Soil	15.7	46.6	12.4	632	1.0	88.5	6.7	144	2.07	21.9	6.2	2.0	61	3.6	4.8	0.2	88	0.82	0.126	11
1283067	Soil	13.8	26.3	14.2	151	0.2	34.3	4.1	60	1.58	17.8	2.7	1.0	20	0.4	3.8	0.2	80	0.04	0.051	8
1283068	Soil	11.6	23.6	13.1	132	0.2	26.6	3.7	67	1.56	16.2	3.2	1.1	28	0.6	3.2	0.2	86	0.14	0.061	7
1283069	Soil	7.5	28.0	8.3	148	1.7	34.7	4.1	132	1.17	8.5	3.5	0.6	38	1.5	2.2	0.2	62	0.33	0.075	4
1283070	Soil	9.0	27.3	8.2	135	1.1	31.5	3.3	87	1.12	11.2	2.4	0.6	51	1.3	2.3	0.1	58	0.75	0.069	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283041	Soil	14	0.04	165	0.003	<1	0.69	0.003	0.05	<0.1	0.02	0.8	0.2	<0.05	3	0.6	<0.2
1283042	Soil	19	0.08	519	0.005	1	0.96	0.005	0.08	<0.1	0.03	1.0	0.2	<0.05	4	<0.5	<0.2
1283043	Soil	5	0.01	105	0.003	<1	0.25	0.013	0.03	<0.1	0.01	0.3	<0.1	<0.05	1	<0.5	<0.2
1283044	Soil	9	0.10	423	0.006	<1	0.64	0.019	0.04	<0.1	0.09	1.4	0.1	0.05	2	1.3	<0.2
1283045	Soil	14	0.09	329	0.005	<1	0.89	0.017	0.03	0.1	0.11	2.0	0.1	0.05	2	1.3	<0.2
1283046	Soil	4	0.02	44	0.005	<1	0.32	0.013	0.02	<0.1	0.01	0.4	<0.1	<0.05	2	0.5	<0.2
1283047	Soil	10	0.04	123	0.004	3	0.65	0.006	0.05	<0.1	0.04	1.4	0.2	<0.05	3	<0.5	<0.2
1283048	Soil	4	0.07	151	0.007	<1	0.52	0.024	0.02	<0.1	0.07	1.1	<0.1	<0.05	1	0.9	<0.2
1283049	Soil	14	0.12	397	0.003	1	0.87	0.008	0.06	0.2	0.05	2.6	0.1	<0.05	3	0.5	<0.2
1283050	Soil	10	0.06	324	0.006	3	0.51	0.008	0.05	<0.1	0.06	2.3	0.2	<0.05	2	2.3	<0.2
1283051	Soil	14	0.07	512	0.006	2	0.66	0.004	0.07	0.2	0.09	1.6	1.0	<0.05	2	0.7	<0.2
1283052	Soil	13	0.04	331	0.010	1	0.71	0.004	0.06	0.1	0.05	1.0	0.2	<0.05	3	2.1	<0.2
1283053	Soil	8	0.03	143	0.006	<1	0.42	0.002	0.05	0.1	0.02	0.6	0.2	<0.05	3	<0.5	<0.2
1283054	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283055	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283056	Soil	26	0.14	1365	0.004	5	0.70	0.006	0.13	0.1	0.44	2.6	0.4	0.05	2	1.9	<0.2
1283057	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283058	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283059	Soil	7	0.08	1104	0.005	4	0.48	0.005	0.08	<0.1	0.09	1.6	0.2	<0.05	2	1.6	<0.2
1283060	Soil	7	0.03	268	0.004	4	0.38	0.003	0.12	<0.1	0.02	1.0	0.2	<0.05	1	1.0	<0.2
1283061	Soil	13	2.16	314	0.003	5	0.28	0.006	0.08	0.1	0.43	4.2	1.1	<0.05	<1	2.2	<0.2
1283062	Soil	11	1.72	334	0.003	6	0.32	0.006	0.08	<0.1	0.35	3.9	0.7	<0.05	<1	1.5	<0.2
1283063	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283064	Soil	6	0.03	247	0.003	2	0.35	0.005	0.04	<0.1	0.05	0.4	0.3	<0.05	2	<0.5	<0.2
1283065	Soil	13	0.81	855	0.004	3	0.45	0.006	0.06	0.1	1.13	4.1	0.4	<0.05	1	2.7	<0.2
1283066	Soil	16	0.18	878	0.005	8	0.68	0.005	0.10	0.1	0.48	3.5	0.6	<0.05	2	2.3	0.3
1283067	Soil	10	0.03	719	0.002	5	0.35	0.003	0.05	0.3	0.08	1.4	0.3	<0.05	2	1.6	<0.2
1283068	Soil	12	0.06	906	0.003	3	0.51	0.005	0.05	0.1	0.10	1.6	0.3	0.06	2	1.4	<0.2
1283069	Soil	12	0.07	1260	0.004	3	0.75	0.015	0.09	<0.1	0.25	2.2	0.3	0.06	2	1.4	<0.2
1283070	Soil	11	0.11	926	0.003	5	0.56	0.018	0.07	<0.1	0.19	1.8	0.3	0.06	2	1.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283071	Soil	20.0	34.4	8.7	206	0.8	58.8	6.0	339	1.59	13.2	2.2	0.9	57	2.2	2.9	0.1	68	0.82	0.106	6
1283072	Soil	28.0	36.7	10.0	250	0.5	81.1	6.4	173	1.83	19.6	2.5	1.3	56	1.7	4.1	0.2	78	1.15	0.115	9
1283073	Soil	69.2	17.1	6.2	169	<0.1	87.3	4.6	27	1.48	14.1	2.4	0.6	7	0.2	2.9	0.1	102	0.12	0.028	6
1283074	Soil	23.9	18.2	7.9	99	<0.1	30.7	3.7	41	1.28	16.3	1.5	0.5	10	0.2	2.1	0.2	79	0.06	0.030	8
1283075	Soil	53.2	22.3	9.7	193	<0.1	92.6	4.4	46	1.72	21.8	1.1	0.7	13	0.3	3.4	0.2	132	0.11	0.040	10
1283076	Soil	28.0	25.6	7.6	268	0.4	65.8	4.0	139	1.05	14.6	0.6	0.2	27	2.5	4.2	0.1	136	0.52	0.052	6
1283077	Soil	15.7	45.8	14.8	336	0.6	65.6	7.5	147	2.58	28.2	2.3	2.6	58	1.4	5.6	0.2	197	0.55	0.113	15
1283078	Soil	10.8	49.6	11.5	296	0.9	63.7	6.6	180	2.21	21.2	2.7	1.3	77	2.6	3.7	0.2	77	1.46	0.116	10
1283079	Soil	17.0	52.3	15.2	279	0.9	62.4	10.3	343	2.54	24.1	2.1	1.9	48	2.8	4.0	0.2	80	0.64	0.130	14
1283080	Soil	10.4	44.7	18.7	189	0.5	42.8	12.3	418	2.55	23.7	3.6	1.8	54	1.6	3.1	0.3	86	0.29	0.112	9
1283081	Soil	8.7	29.6	14.8	139	0.4	30.4	5.6	158	1.85	16.4	3.2	1.2	44	0.6	2.3	0.2	65	0.35	0.075	7
1283082	Soil	3.1	19.7	12.5	94	0.9	18.8	3.8	184	1.08	7.1	2.8	0.7	57	0.6	1.4	0.1	38	0.79	0.066	3
1283083	Soil	4.8	10.3	6.7	44	0.1	9.2	1.6	25	0.70	7.2	1.0	0.6	10	0.2	0.9	0.1	48	0.01	0.039	7
1283084	Soil	5.6	24.8	15.7	155	0.6	22.2	4.3	113	1.85	14.7	0.6	1.0	15	0.5	2.2	0.2	63	0.04	0.052	6
1283085	Soil	7.6	12.4	9.5	85	0.5	15.8	3.1	95	1.47	16.4	<0.5	0.7	9	0.2	1.7	0.2	65	0.01	0.029	7
1283086	Soil	3.1	17.8	14.9	28	0.9	8.9	1.0	16	0.50	6.2	<0.5	0.3	19	0.5	0.6	0.1	37	0.04	0.070	4
1283087	Soil	9.6	26.9	12.9	97	0.6	24.7	3.1	44	1.51	19.4	2.0	0.5	17	0.9	2.2	0.2	78	0.03	0.106	6
1283088	Soil	6.1	36.8	21.8	58	1.1	13.4	2.0	36	1.37	7.7	5.1	0.5	30	0.2	1.3	0.2	62	0.02	0.106	3
1283089	Soil	5.4	20.8	17.5	93	0.7	18.1	4.9	167	3.09	18.1	4.2	3.0	16	0.2	2.3	0.3	83	0.03	0.066	10
1283090	Soil	3.6	9.8	12.7	48	0.3	10.7	2.8	71	1.75	12.4	<0.5	1.3	11	0.1	1.3	0.2	57	0.02	0.064	8
1283091	Soil	4.2	11.7	11.1	53	0.8	10.7	2.5	44	1.50	12.2	1.0	1.3	10	<0.1	1.4	0.2	50	0.01	0.058	7
1283092	Soil	3.3	9.8	7.3	41	0.4	8.0	2.1	34	0.86	8.4	0.5	0.4	8	<0.1	0.9	0.1	40	0.02	0.046	8
1283093	Soil	4.4	14.6	14.9	67	0.7	13.9	3.8	92	1.93	13.3	1.1	1.6	13	0.2	1.5	0.2	64	0.03	0.061	10
1283094	Soil	6.1	28.6	14.5	117	0.4	26.4	6.3	123	3.61	20.1	3.4	2.0	11	0.2	2.3	0.2	70	0.02	0.050	7
1283095	Soil	2.2	15.9	8.7	29	0.4	7.0	1.9	41	0.81	6.0	<0.5	0.4	10	0.1	0.6	0.1	37	0.03	0.039	7
1283096	Soil	3.1	10.6	10.0	49	0.4	10.1	2.5	56	1.25	11.2	0.6	0.5	10	0.2	1.1	0.1	41	0.02	0.043	7
1283097	Soil	5.5	11.1	13.8	65	0.8	12.4	3.7	79	1.73	16.2	0.7	0.8	11	0.1	1.9	0.2	66	0.02	0.059	8
1283098	Soil	12.4	14.9	17.1	73	0.4	14.4	3.8	71	1.86	17.7	1.0	1.6	12	0.2	3.0	0.2	83	0.02	0.055	8
1283099	Soil	10.0	22.5	16.4	130	0.2	24.5	6.1	118	2.60	20.3	1.9	1.4	11	0.4	2.8	0.2	68	0.02	0.058	7
1283100	Soil	2.4	31.9	18.3	87	0.9	27.9	6.6	187	1.93	11.9	4.0	0.8	91	1.2	1.4	0.2	39	1.35	0.073	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283071	Soil	14	0.12	871	0.003	3	0.70	0.009	0.05	0.1	0.41	2.5	0.3	0.05	2	1.8	<0.2
1283072	Soil	14	0.15	571	0.004	4	0.55	0.007	0.06	0.1	0.63	2.7	0.4	<0.05	1	2.1	<0.2
1283073	Soil	10	0.04	183	0.003	3	0.42	0.002	0.05	0.2	0.02	0.8	0.7	<0.05	2	0.9	<0.2
1283074	Soil	10	0.03	148	0.004	2	0.42	0.003	0.04	0.1	0.02	0.7	0.4	<0.05	3	0.7	<0.2
1283075	Soil	17	0.08	237	0.003	2	0.78	0.003	0.05	0.2	0.02	1.0	0.9	<0.05	4	1.5	<0.2
1283076	Soil	18	0.11	454	0.004	3	0.60	0.010	0.06	0.2	0.08	0.9	1.7	<0.05	2	2.1	<0.2
1283077	Soil	29	0.16	826	0.003	3	0.89	0.004	0.08	0.2	0.21	3.1	0.5	<0.05	2	3.5	<0.2
1283078	Soil	16	0.16	1756	0.003	7	0.91	0.008	0.13	0.1	0.46	2.9	0.4	0.12	2	2.2	<0.2
1283079	Soil	16	0.12	1717	0.003	7	0.76	0.004	0.15	0.1	0.48	3.5	0.4	0.12	2	3.8	<0.2
1283080	Soil	19	0.17	1043	0.002	4	0.89	0.004	0.10	<0.1	0.24	2.9	0.3	<0.05	3	2.4	<0.2
1283081	Soil	14	0.16	642	0.002	3	0.67	0.007	0.06	0.1	0.13	1.7	0.2	<0.05	2	1.3	<0.2
1283082	Soil	10	0.12	694	0.002	3	0.59	0.015	0.05	<0.1	0.19	1.6	0.2	0.07	2	3.3	<0.2
1283083	Soil	8	0.03	140	0.003	2	0.51	0.007	0.04	<0.1	0.01	0.7	0.1	<0.05	3	0.7	<0.2
1283084	Soil	15	0.06	200	0.005	4	0.65	0.007	0.06	0.1	0.08	1.5	0.3	<0.05	3	1.2	<0.2
1283085	Soil	7	0.03	100	0.005	<1	0.50	0.004	0.03	<0.1	0.01	0.9	0.2	<0.05	3	1.5	<0.2
1283086	Soil	8	0.03	296	0.002	2	0.54	0.008	0.04	<0.1	0.05	1.1	0.3	<0.05	3	1.0	<0.2
1283087	Soil	12	0.04	453	0.002	3	0.67	0.004	0.06	<0.1	0.11	1.0	0.2	<0.05	3	1.3	<0.2
1283088	Soil	14	0.04	365	0.002	3	0.88	0.011	0.08	<0.1	0.17	1.5	0.4	<0.05	4	2.4	<0.2
1283089	Soil	22	0.20	244	0.010	2	1.44	0.005	0.07	0.2	0.07	2.0	0.2	<0.05	5	1.5	<0.2
1283090	Soil	11	0.07	149	0.006	2	0.81	0.005	0.04	0.1	0.03	1.2	0.2	<0.05	4	1.1	<0.2
1283091	Soil	9	0.04	127	0.004	2	0.64	0.006	0.04	0.1	0.03	1.0	0.1	<0.05	3	0.9	<0.2
1283092	Soil	6	0.03	168	0.003	<1	0.55	0.004	0.03	0.1	0.01	0.6	0.2	<0.05	4	0.8	<0.2
1283093	Soil	12	0.08	235	0.006	1	1.06	0.007	0.05	0.2	0.03	1.5	0.2	<0.05	4	1.4	<0.2
1283094	Soil	18	0.12	292	0.003	2	1.21	0.003	0.04	0.1	0.05	2.4	0.2	<0.05	4	1.6	<0.2
1283095	Soil	9	0.05	296	0.004	1	0.65	0.006	0.04	0.1	0.02	0.7	0.2	<0.05	3	<0.5	<0.2
1283096	Soil	8	0.07	207	0.003	1	0.59	0.003	0.04	<0.1	0.02	0.8	0.2	<0.05	3	0.6	<0.2
1283097	Soil	9	0.05	207	0.006	<1	0.69	0.003	0.05	0.1	0.02	1.0	0.2	<0.05	3	1.4	<0.2
1283098	Soil	11	0.06	336	0.004	1	0.82	0.004	0.04	<0.1	0.03	1.4	0.2	<0.05	4	1.3	<0.2
1283099	Soil	14	0.13	363	0.002	1	0.78	0.004	0.06	0.1	0.06	1.7	0.2	<0.05	3	2.1	<0.2
1283100	Soil	12	0.19	1462	0.002	4	0.85	0.011	0.06	<0.1	0.24	3.0	0.2	0.10	2	3.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283101	Soil	13.9	24.9	9.6	263	0.6	42.2	11.3	251	2.18	16.0	5.8	1.5	33	2.4	2.6	0.2	50	0.25	0.122	7
1283102	Soil	9.2	44.5	21.6	159	0.9	45.1	9.0	325	2.20	13.9	7.3	1.6	65	3.3	2.3	0.3	53	0.87	0.083	5
1283103	Soil	9.8	30.2	24.4	194	0.8	39.3	12.5	623	2.26	16.3	5.7	1.4	63	2.5	2.2	0.2	55	0.88	0.105	5
1283104	Soil	2.1	10.9	9.0	26	0.4	7.6	2.4	28	1.12	4.0	2.0	1.1	13	0.2	0.5	0.1	28	0.06	0.024	4
1283105	Soil	3.1	11.9	9.4	63	0.1	15.7	4.1	74	2.12	16.3	3.7	1.4	12	0.2	1.3	0.2	42	0.04	0.021	6
1283106	Soil	2.3	12.0	14.8	49	<0.1	12.9	3.5	66	1.32	10.2	2.5	1.1	12	0.2	0.8	0.1	24	0.06	0.027	3
1283107	Soil	3.3	16.9	12.3	87	<0.1	19.1	4.8	81	2.41	22.8	2.9	1.4	15	0.1	1.9	0.2	40	0.03	0.042	6
1283108	Soil	1.8	9.3	10.5	39	0.2	9.3	2.3	46	1.03	7.3	2.1	0.4	11	0.1	0.6	<0.1	22	0.04	0.038	2
1283109	Soil	2.6	37.4	12.2	83	0.3	25.5	3.6	48	1.43	7.1	7.2	1.3	23	0.1	0.8	0.1	38	0.07	0.035	6
1283110	Soil	1.5	45.2	22.6	103	0.6	66.8	11.1	291	2.10	12.6	4.3	1.6	211	0.2	0.9	0.2	37	1.05	0.076	6
1283111	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283112	Soil	1.9	23.8	13.0	72	0.5	24.2	7.3	105	2.03	8.9	4.9	1.2	94	0.4	1.2	0.2	40	0.48	0.073	4
1283113	Soil	2.7	9.4	7.0	42	0.1	9.9	2.5	45	1.22	11.2	1.5	0.7	10	0.1	0.9	0.1	38	0.04	0.029	6
1283114	Soil	1.4	9.8	11.8	20	0.5	6.6	1.4	37	0.57	3.5	2.8	0.1	13	0.1	0.3	<0.1	18	0.06	0.051	2
1283115	Soil	1.5	31.8	9.3	61	2.0	21.2	5.9	80	1.10	6.0	4.0	0.7	42	0.2	0.6	0.1	25	0.35	0.062	4
1283116	Soil	1.4	19.0	33.2	44	0.7	23.5	2.9	23	1.57	8.5	7.1	0.7	61	0.3	0.7	<0.1	33	0.53	0.073	3
1283117	Soil	4.4	19.5	13.0	75	0.8	22.1	5.7	132	1.92	10.1	2.2	1.5	58	0.5	1.0	0.2	51	0.46	0.085	5
1283118	Soil	3.5	26.1	14.9	91	1.0	32.5	7.8	173	1.84	10.7	3.8	0.9	69	0.5	1.1	0.2	42	0.71	0.103	4
1283119	Soil	2.8	28.0	10.8	59	0.9	23.2	4.4	80	1.83	10.1	2.6	1.1	36	0.4	0.8	0.2	37	0.28	0.082	5
1283120	Soil	2.8	12.9	8.6	45	0.7	10.6	2.3	32	0.94	7.0	1.4	<0.1	9	0.2	1.0	0.1	33	0.03	0.070	4
1283121	Soil	6.1	30.7	18.0	119	1.2	33.0	5.2	85	2.25	14.6	4.3	0.9	36	0.5	2.0	0.2	55	0.13	0.136	9
1283122	Soil	12.8	30.5	19.0	160	0.7	36.1	5.7	124	2.70	21.6	6.3	0.5	25	0.5	3.5	0.3	95	0.07	0.092	12
1283123	Soil	316.1	176.5	24.2	400	1.9	90.8	2.2	53	3.86	103.9	5.5	2.0	96	4.4	58.6	0.3	522	0.09	0.162	13
1283124	Soil	23.4	30.3	15.3	159	0.5	31.1	4.0	101	1.89	17.5	4.0	0.5	25	1.1	5.0	0.2	148	0.07	0.087	14
1283125	Soil	48.8	21.7	23.3	254	0.7	54.9	2.3	42	1.16	21.3	3.1	0.2	14	0.7	10.2	0.1	310	0.02	0.059	18
1283126	Soil	13.5	10.6	17.9	98	0.6	16.0	1.1	28	0.71	11.2	1.4	0.5	9	0.3	2.8	0.1	205	0.02	0.064	17
1283127	Soil	59.2	75.2	79.3	836	1.8	139.2	11.5	537	4.04	47.4	2.8	0.9	53	5.6	18.1	0.4	331	0.09	0.149	26
1283128	Soil	53.8	164.8	16.7	3162	4.6	298.6	5.2	150	2.22	51.1	6.7	1.4	123	31.3	26.4	0.2	805	1.20	0.248	16
1283129	Soil	59.4	234.4	22.3	3767	4.9	348.0	6.1	149	2.29	59.5	4.2	1.3	195	42.8	27.5	0.3	1102	2.38	0.229	17
1283130	Soil	65.4	232.3	40.0	3686	4.5	365.0	7.3	185	2.56	61.7	4.6	1.3	202	32.5	28.1	0.3	798	2.47	0.230	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283101	Soil	14	0.19	1363	0.005	2	0.85	0.007	0.06	0.1	0.22	1.9	0.3	0.07	2	3.4	<0.2
1283102	Soil	16	0.19	1102	0.001	2	0.96	0.008	0.06	<0.1	0.31	3.1	0.3	0.12	2	6.3	<0.2
1283103	Soil	26	0.26	939	0.002	3	1.04	0.007	0.08	<0.1	0.31	2.9	0.2	0.09	3	6.0	<0.2
1283104	Soil	9	0.04	305	0.002	1	0.97	0.015	0.05	<0.1	0.07	1.4	0.2	<0.05	3	0.6	<0.2
1283105	Soil	12	0.13	266	0.002	<1	0.82	0.005	0.04	<0.1	0.02	1.2	0.1	<0.05	3	0.9	<0.2
1283106	Soil	13	0.09	186	0.002	3	0.47	0.009	0.05	<0.1	0.03	1.2	<0.1	<0.05	2	0.6	<0.2
1283107	Soil	12	0.12	203	0.002	<1	0.67	0.005	0.05	0.1	0.02	1.3	0.1	<0.05	3	1.4	<0.2
1283108	Soil	8	0.07	279	0.002	1	0.52	0.015	0.05	<0.1	0.04	0.6	0.2	<0.05	2	<0.5	<0.2
1283109	Soil	11	0.08	852	0.005	1	1.17	0.020	0.06	0.1	0.06	2.8	0.3	<0.05	3	1.6	<0.2
1283110	Soil	21	0.28	1059	0.004	5	1.25	0.016	0.06	0.1	0.21	3.9	0.2	0.09	3	2.8	<0.2
1283111	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283112	Soil	16	0.13	1300	0.003	<1	0.88	0.010	0.05	<0.1	0.11	2.1	0.2	0.11	2	3.2	<0.2
1283113	Soil	7	0.04	327	0.003	<1	0.60	0.012	0.03	<0.1	0.03	0.9	<0.1	<0.05	3	0.5	<0.2
1283114	Soil	7	0.03	153	0.002	<1	0.34	0.015	0.04	<0.1	0.02	0.4	<0.1	<0.05	2	0.6	<0.2
1283115	Soil	9	0.09	622	0.002	2	0.86	0.017	0.04	0.1	0.17	1.6	0.1	0.05	2	1.5	<0.2
1283116	Soil	14	0.10	458	0.003	1	0.68	0.019	0.04	<0.1	0.20	2.2	0.1	0.08	2	1.3	<0.2
1283117	Soil	16	0.16	618	0.002	<1	0.91	0.008	0.06	0.1	0.24	1.9	0.2	<0.05	3	2.8	<0.2
1283118	Soil	21	0.16	625	0.002	2	0.94	0.009	0.05	0.1	0.27	2.4	0.2	0.10	3	3.8	<0.2
1283119	Soil	13	0.11	687	0.002	2	0.94	0.010	0.04	<0.1	0.24	2.4	0.2	0.06	3	2.6	<0.2
1283120	Soil	7	0.02	136	0.004	1	0.38	0.011	0.04	0.1	0.07	0.5	0.1	<0.05	2	1.3	<0.2
1283121	Soil	25	0.22	519	0.003	2	1.11	0.007	0.07	0.2	0.31	1.8	0.3	0.05	3	1.6	<0.2
1283122	Soil	22	0.24	459	0.009	2	1.14	0.006	0.08	0.3	0.10	1.6	0.4	<0.05	4	1.7	<0.2
1283123	Soil	37	0.02	381	0.004	4	0.69	0.006	0.21	1.4	0.40	1.8	8.5	0.50	2	15.5	0.6
1283124	Soil	18	0.14	399	0.005	2	0.81	0.007	0.06	0.2	0.16	0.9	0.8	<0.05	3	2.7	<0.2
1283125	Soil	14	0.03	143	0.003	4	0.32	0.005	0.06	0.3	0.06	0.3	1.1	<0.05	2	4.3	<0.2
1283126	Soil	15	0.04	125	0.005	5	0.55	0.008	0.05	0.1	0.03	0.3	0.9	<0.05	4	2.1	<0.2
1283127	Soil	25	0.04	1160	0.007	5	0.43	0.004	0.10	0.3	0.19	2.3	2.2	<0.05	2	12.8	0.4
1283128	Soil	89	0.23	723	0.006	10	0.91	0.013	0.14	0.3	1.35	3.8	3.8	0.13	3	18.4	0.2
1283129	Soil	97	0.76	803	0.006	12	0.79	0.007	0.16	0.3	1.76	4.5	4.4	0.15	3	14.5	0.3
1283130	Soil	67	0.93	728	0.007	7	0.77	0.009	0.16	0.3	1.67	4.0	4.0	0.15	3	17.4	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283131	Soil	8.1	60.8	44.8	227	0.6	52.6	11.6	306	4.40	38.7	5.1	1.4	118	1.2	4.4	0.4	61	0.12	0.177	21
1283132	Soil	11.2	38.6	17.9	146	0.5	34.1	7.5	142	2.55	27.2	2.3	0.9	14	0.4	2.8	0.3	116	0.03	0.081	19
1283133	Soil	11.1	31.6	14.8	135	0.2	30.5	5.7	86	1.95	19.9	1.5	0.5	10	0.3	2.8	0.2	136	0.05	0.074	16
1283134	Soil	61.0	137.6	22.4	998	0.4	91.4	9.7	100	3.62	46.7	6.5	0.2	14	1.0	8.1	0.3	118	0.07	0.169	10
1283135	Soil	16.3	27.9	22.5	81	1.7	22.1	2.1	21	1.54	18.2	3.6	0.2	67	0.4	5.1	0.3	81	0.02	0.105	9
1283136	Soil	2.7	44.0	6.6	63	0.2	25.4	3.3	40	1.52	7.1	3.4	0.4	6	0.4	1.3	0.1	267	0.02	0.092	7
1283137	Soil	7.8	38.1	11.1	129	0.3	26.0	4.1	106	1.76	14.6	3.7	0.2	15	0.6	2.2	0.3	66	0.03	0.192	9
1283138	Soil	9.6	41.8	12.1	383	1.0	43.4	4.1	168	1.80	12.8	4.3	1.4	52	4.3	2.4	0.2	73	0.72	0.170	10
1283139	Soil	9.5	49.2	26.1	230	1.2	63.3	10.1	256	3.08	16.9	4.2	0.6	62	1.0	2.8	0.4	68	0.39	0.198	13
1283140	Soil	5.8	21.0	19.7	90	0.2	24.2	3.4	103	1.28	7.6	2.0	0.1	36	0.2	1.3	0.3	35	0.12	0.128	7
1283151	Soil	1.3	29.0	8.9	42	0.4	26.7	6.0	168	1.78	8.0	2.5	0.7	153	0.4	0.8	0.2	24	1.46	0.071	3
1283152	Soil	2.2	27.8	11.8	68	0.7	35.8	5.0	157	1.93	7.6	3.8	0.8	204	0.5	1.4	0.2	23	1.48	0.087	3
1283153	Soil	1.3	20.2	8.1	54	0.8	25.8	6.1	224	1.86	7.2	2.4	0.6	190	0.6	1.2	0.2	30	1.35	0.073	2
1283154	Soil	1.4	14.5	6.8	42	0.6	18.3	2.8	110	1.36	5.5	1.4	0.3	121	0.5	0.7	0.1	21	0.94	0.062	2
1283155	Soil	3.1	31.2	14.6	71	0.6	25.4	4.4	113	2.21	12.3	2.2	1.2	111	0.6	0.9	0.2	41	0.84	0.073	4
1283156	Soil	0.5	18.1	6.8	28	0.5	16.6	1.7	18	0.73	4.7	2.3	0.2	51	0.3	0.5	0.1	16	0.40	0.051	3
1283157	Soil	2.8	26.1	9.3	101	0.2	21.8	15.1	472	1.93	11.1	1.7	1.2	46	0.6	0.7	0.2	42	0.33	0.037	6
1283158	Soil	2.5	10.6	6.7	65	<0.1	11.9	3.2	87	1.38	10.6	<0.5	0.8	13	0.3	0.7	0.1	31	0.05	0.020	4
1283159	Soil	2.7	23.0	9.6	101	0.7	28.3	6.8	151	1.96	11.0	1.5	0.8	64	0.2	0.9	0.1	35	0.48	0.087	6
1283160	Soil	4.5	29.6	13.0	146	0.2	30.7	10.8	268	2.43	22.4	2.0	1.8	26	0.7	2.0	0.2	47	0.12	0.056	7
1283161	Soil	1.3	38.7	14.3	39	1.0	25.7	3.2	29	2.02	10.9	3.8	1.1	43	0.7	0.7	0.2	27	0.28	0.090	6
1283162	Soil	0.8	11.6	4.1	19	0.2	6.2	1.2	17	0.49	1.8	0.8	0.1	11	0.3	0.2	<0.1	18	0.05	0.022	3
1283163	Soil	0.7	24.3	4.2	36	0.6	22.4	2.1	16	0.73	2.6	2.8	0.1	34	1.0	0.4	<0.1	12	0.21	0.052	3
1283164	Soil	3.8	21.2	11.2	61	1.2	16.5	2.2	33	1.73	23.4	7.6	0.2	17	0.2	1.4	0.2	37	0.02	0.099	4
1283165	Soil	2.3	29.5	8.0	85	2.1	26.3	3.3	88	1.48	15.2	6.4	0.4	45	0.3	1.1	0.1	21	0.70	0.072	3
1283166	Soil	5.5	44.5	19.2	150	1.1	41.1	6.0	76	2.60	35.3	4.2	0.4	32	0.2	2.4	0.3	51	0.11	0.087	4
1283167	Soil	1.8	56.8	11.0	109	1.8	44.5	3.9	230	1.59	13.0	7.5	0.3	44	0.4	0.9	0.2	25	0.94	0.118	3
1283168	Soil	4.2	18.6	7.0	76	0.7	17.9	2.4	28	1.31	22.5	1.4	0.3	8	<0.1	1.7	0.2	53	0.01	0.037	3
1283169	Soil	3.0	31.5	16.3	117	0.5	30.4	4.1	75	2.10	21.3	5.7	0.6	22	0.3	1.1	0.3	28	0.06	0.086	3
1283170	Soil	6.5	76.7	24.7	270	2.4	89.7	11.5	213	3.11	43.4	7.5	1.3	61	1.2	2.5	0.2	34	0.49	0.116	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283131	Soil	15	0.07	734	0.005	3	0.75	0.005	0.16	<0.1	0.20	2.4	0.6	0.17	3	3.8	<0.2
1283132	Soil	14	0.07	412	0.004	2	0.91	0.006	0.08	0.1	0.06	1.2	0.4	<0.05	4	2.1	<0.2
1283133	Soil	13	0.05	244	0.003	1	0.70	0.005	0.07	0.1	0.04	0.8	0.5	<0.05	4	1.8	<0.2
1283134	Soil	15	0.04	213	0.003	2	0.41	0.004	0.09	0.2	0.17	0.4	0.4	<0.05	3	5.0	<0.2
1283135	Soil	13	0.02	374	0.002	1	0.32	0.007	0.11	0.2	0.11	0.2	1.1	0.18	2	4.6	<0.2
1283136	Soil	5	0.03	224	0.003	1	0.55	0.013	0.05	<0.1	0.08	0.6	0.1	<0.05	2	1.0	<0.2
1283137	Soil	13	0.06	248	0.002	2	0.85	0.005	0.07	<0.1	0.07	0.2	0.3	0.07	3	1.2	<0.2
1283138	Soil	25	0.21	1367	0.002	3	0.86	0.007	0.10	<0.1	0.35	2.4	0.3	0.08	2	1.4	<0.2
1283139	Soil	18	0.19	2027	0.003	3	0.92	0.006	0.13	0.1	0.21	1.2	0.3	0.07	2	1.6	<0.2
1283140	Soil	11	0.05	474	0.002	2	0.38	0.010	0.09	<0.1	0.02	0.3	0.1	0.08	1	1.0	<0.2
1283151	Soil	12	0.25	732	0.002	1	0.74	0.014	0.03	<0.1	0.15	1.8	0.1	0.15	2	2.1	<0.2
1283152	Soil	14	0.20	673	0.002	3	0.76	0.014	0.08	0.1	0.23	2.1	0.4	0.17	2	2.7	<0.2
1283153	Soil	9	0.17	546	0.002	2	0.58	0.017	0.05	<0.1	0.21	1.6	0.2	0.12	2	2.4	<0.2
1283154	Soil	8	0.11	395	0.003	1	0.60	0.024	0.04	<0.1	0.14	1.1	0.1	0.10	2	1.6	<0.2
1283155	Soil	18	0.22	533	0.001	1	0.90	0.008	0.08	<0.1	0.21	2.4	0.1	0.07	3	1.6	<0.2
1283156	Soil	7	0.08	328	0.003	<1	0.58	0.023	0.03	<0.1	0.14	0.9	0.1	0.07	2	1.6	<0.2
1283157	Soil	17	0.23	317	0.003	1	0.82	0.011	0.07	<0.1	0.03	1.7	0.1	<0.05	3	1.0	<0.2
1283158	Soil	10	0.13	207	0.001	<1	0.58	0.008	0.06	<0.1	0.02	1.0	<0.1	<0.05	2	<0.5	<0.2
1283159	Soil	14	0.25	874	0.003	1	0.81	0.012	0.05	0.1	0.18	1.8	0.1	0.05	2	1.3	<0.2
1283160	Soil	14	0.17	794	0.003	<1	0.73	0.004	0.05	0.1	0.08	2.0	0.1	<0.05	2	1.5	<0.2
1283161	Soil	15	0.12	843	0.001	<1	1.00	0.007	0.05	<0.1	0.44	3.7	0.2	0.11	2	1.8	<0.2
1283162	Soil	6	0.04	243	0.003	<1	0.51	0.024	0.04	<0.1	0.03	0.4	<0.1	<0.05	2	<0.5	<0.2
1283163	Soil	6	0.04	534	0.002	<1	0.45	0.026	0.03	<0.1	0.15	1.1	0.1	0.09	1	1.0	<0.2
1283164	Soil	16	0.05	251	0.002	1	0.68	0.006	0.05	<0.1	0.12	0.4	0.1	<0.05	2	1.2	<0.2
1283165	Soil	14	0.06	780	0.002	2	0.67	0.022	0.06	<0.1	0.43	1.7	<0.1	0.05	2	1.8	<0.2
1283166	Soil	17	0.03	510	0.002	2	0.57	0.006	0.08	<0.1	0.12	1.3	0.1	0.05	2	2.7	<0.2
1283167	Soil	12	0.06	555	0.002	1	0.73	0.014	0.05	<0.1	0.47	1.6	0.1	0.09	2	2.0	<0.2
1283168	Soil	10	0.02	194	<0.001	2	0.32	0.004	0.04	<0.1	0.04	0.7	0.2	<0.05	3	0.9	<0.2
1283169	Soil	15	0.04	508	<0.001	<1	0.60	0.005	0.08	<0.1	0.23	1.8	<0.1	<0.05	2	1.5	<0.2
1283170	Soil	23	0.11	1178	<0.001	1	0.76	0.007	0.09	<0.1	0.56	4.1	0.1	0.08	2	4.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283171	Soil	3.8	33.4	54.2	61	6.6	21.7	3.1	258	2.40	187.0	814.3	0.5	89	0.2	7.1	0.7	37	0.44	0.138	4
1283172	Soil	2.7	14.7	26.7	34	3.4	12.5	1.1	85	1.40	59.2	153.6	<0.1	59	0.3	4.0	0.3	23	0.33	0.106	2
1283173	Soil	8.8	28.7	21.1	70	1.7	15.7	2.3	43	2.48	55.1	13.8	0.5	40	<0.1	5.4	0.3	58	0.02	0.116	2
1283174	Soil	5.2	58.0	19.6	169	2.6	48.8	7.5	177	2.95	62.4	16.3	0.8	45	0.6	2.8	0.3	33	0.26	0.115	4
1283175	Soil	5.0	66.4	27.4	194	2.8	59.0	8.7	273	3.30	79.8	34.4	1.0	68	0.7	3.5	0.3	37	0.51	0.159	4
1283176	Soil	5.3	38.0	16.6	96	2.2	25.4	2.2	39	2.40	49.2	8.3	0.6	69	0.5	3.2	0.2	23	0.04	0.085	2
1283177	Soil	9.8	68.6	14.3	144	2.5	48.6	4.1	74	2.69	57.8	10.6	0.5	57	0.5	3.6	0.2	29	0.18	0.083	3
1283178	Soil	4.8	13.5	18.0	40	0.7	12.6	1.2	25	1.14	22.2	2.9	<0.1	37	0.1	1.8	0.3	49	0.04	0.065	6
1283179	Soil	7.3	34.9	17.0	64	1.6	16.9	2.9	70	2.38	32.9	3.5	0.3	56	0.4	5.3	0.3	120	0.04	0.080	9
1283180	Soil	6.8	70.0	16.5	124	2.0	49.8	7.5	234	2.92	54.2	14.6	0.7	49	0.4	3.0	0.2	43	0.31	0.099	4
1283181	Soil	24.0	38.3	35.0	99	3.1	20.8	2.1	46	3.71	79.2	5.9	0.1	35	0.2	11.9	0.4	227	0.03	0.196	5
1283182	Soil	7.1	17.8	14.0	22	4.4	8.2	1.0	21	1.03	22.2	4.2	<0.1	54	<0.1	5.0	0.2	71	0.02	0.069	2
1283183	Soil	18.6	37.9	27.4	75	7.7	22.6	1.6	56	3.25	121.1	30.1	0.7	594	0.2	24.6	0.4	247	0.16	0.500	4
1283184	Soil	9.3	82.8	23.8	115	5.7	58.5	4.8	77	2.32	42.5	62.8	0.4	99	1.2	6.5	0.4	92	0.22	0.161	4
1283185	Soil	11.3	32.4	17.6	78	2.1	20.8	3.7	150	2.21	26.5	15.6	0.4	91	0.6	3.7	0.3	82	0.21	0.113	2
1283186	Soil	7.9	41.5	13.5	90	2.7	28.7	1.5	21	2.17	27.8	7.5	0.6	56	0.1	2.7	0.2	28	<0.01	0.056	3
1283187	Soil	5.7	19.2	19.4	59	2.6	16.4	1.4	22	1.78	36.2	11.6	0.5	45	<0.1	5.9	0.3	29	<0.01	0.050	2
1283188	Soil	5.8	53.3	18.6	118	1.3	33.5	3.4	49	3.23	49.2	13.5	0.8	40	0.1	4.0	0.3	40	<0.01	0.080	2
1283189	Soil	16.2	71.1	33.6	214	4.2	41.4	7.5	237	5.96	105.9	84.0	1.6	54	0.7	11.9	0.3	84	0.10	0.382	3
1283190	Soil	2.5	48.3	14.2	104	1.0	38.6	5.7	139	2.22	35.2	5.0	0.6	29	0.2	1.9	0.2	23	0.02	0.072	3
1283201	Soil	6.0	32.1	14.8	128	0.2	35.4	9.3	312	2.94	11.0	2.6	0.3	10	0.3	1.7	0.4	24	0.02	0.088	8
1283202	Soil	40.6	44.0	12.6	205	0.1	94.4	7.2	101	2.45	21.1	1.8	0.4	11	0.5	5.7	0.2	82	0.02	0.109	13
1283203	Soil	52.6	30.9	7.0	217	<0.1	90.5	6.0	117	1.69	17.2	0.8	0.4	17	1.7	3.4	0.1	75	0.16	0.130	10
1283204	Soil	12.4	132.0	23.9	443	2.1	121.1	14.7	200	4.34	22.8	2.7	4.5	24	1.5	3.8	0.4	37	0.19	0.090	18
1283205	Soil	1.9	17.6	4.9	40	<0.1	15.2	4.1	201	1.40	5.7	0.8	0.1	5	<0.1	0.5	0.2	13	0.03	0.049	5
1283206	Soil	7.2	52.5	15.0	186	<0.1	68.7	13.5	464	3.70	19.6	1.1	0.4	9	0.3	2.2	0.4	46	0.02	0.092	21
1283207	Soil	5.6	14.5	17.1	37	0.5	7.7	1.4	104	0.83	4.4	<0.5	0.2	16	0.1	0.7	0.2	43	0.01	0.071	7
1283208	Soil	9.7	105.1	32.4	312	0.3	79.9	8.7	445	2.26	23.7	2.9	0.6	57	1.8	3.4	0.2	71	0.15	0.195	11
1283209	Soil	9.9	106.5	20.6	317	0.2	53.2	11.2	156	3.94	27.6	5.2	0.6	15	0.6	3.4	0.2	63	0.14	0.336	9
1283210	Soil	9.6	89.1	26.4	59	0.8	68.2	18.6	190	4.28	33.4	7.0	2.7	28	0.2	10.9	0.3	55	0.32	0.439	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283171	Soil	15	0.06	1594	0.001	2	0.89	0.020	0.12	0.1	3.23	2.4	0.3	0.20	3	7.9	0.2
1283172	Soil	7	0.04	947	0.002	1	0.51	0.025	0.08	<0.1	1.96	0.5	0.3	0.15	2	4.4	<0.2
1283173	Soil	11	0.02	382	<0.001	<1	0.46	0.007	0.07	<0.1	0.35	1.0	0.3	0.13	2	3.2	<0.2
1283174	Soil	19	0.07	1034	<0.001	1	0.66	0.007	0.08	<0.1	0.53	2.9	0.1	0.09	2	4.5	<0.2
1283175	Soil	19	0.13	882	0.001	2	0.78	0.009	0.09	<0.1	0.81	3.8	0.2	0.14	2	6.2	<0.2
1283176	Soil	17	0.01	512	<0.001	2	0.38	0.005	0.09	<0.1	0.47	2.4	<0.1	0.12	2	6.5	<0.2
1283177	Soil	22	0.02	1018	<0.001	2	0.50	0.005	0.08	<0.1	1.05	2.6	0.1	0.08	2	5.6	<0.2
1283178	Soil	12	0.03	346	0.002	<1	0.48	0.005	0.05	<0.1	0.18	0.1	0.3	<0.05	3	1.2	<0.2
1283179	Soil	23	0.14	344	0.011	<1	0.98	0.006	0.06	0.2	0.41	0.8	0.4	0.09	5	4.7	<0.2
1283180	Soil	23	0.06	1332	<0.001	3	0.70	0.006	0.06	<0.1	0.99	2.9	0.2	0.08	2	4.7	<0.2
1283181	Soil	18	0.03	946	0.002	1	0.49	0.008	0.09	0.2	0.56	0.5	0.8	0.16	4	6.5	<0.2
1283182	Soil	12	0.02	219	0.002	<1	0.40	0.016	0.06	<0.1	0.12	0.2	0.6	0.09	3	3.3	<0.2
1283183	Soil	72	0.02	217	0.003	2	1.03	0.007	0.17	0.2	0.61	2.5	2.5	0.50	4	14.4	0.3
1283184	Soil	23	0.05	1509	0.001	3	1.10	0.011	0.11	<0.1	3.01	2.9	1.0	0.16	3	6.3	<0.2
1283185	Soil	17	0.05	1008	0.001	2	0.49	0.005	0.10	<0.1	1.43	1.7	0.5	0.17	2	3.6	<0.2
1283186	Soil	22	0.01	836	<0.001	3	0.37	0.003	0.06	<0.1	0.63	2.4	0.1	<0.05	1	5.9	<0.2
1283187	Soil	15	0.01	630	<0.001	2	0.34	0.003	0.08	<0.1	0.77	1.2	0.2	0.10	1	4.7	<0.2
1283188	Soil	21	0.01	297	<0.001	1	0.51	0.003	0.07	<0.1	0.24	2.5	0.1	0.07	2	5.1	<0.2
1283189	Soil	27	0.03	784	0.002	2	0.65	0.005	0.10	0.1	0.64	2.6	0.6	0.16	2	7.3	<0.2
1283190	Soil	12	0.05	287	<0.001	<1	0.57	0.006	0.06	<0.1	1.20	2.0	0.1	0.06	2	2.2	<0.2
1283201	Soil	7	0.05	249	0.002	2	0.52	0.007	0.09	<0.1	0.04	0.6	0.2	0.08	2	0.8	<0.2
1283202	Soil	14	0.06	357	0.002	2	0.66	0.005	0.07	0.1	0.07	0.6	0.9	0.06	1	2.6	<0.2
1283203	Soil	14	0.07	620	0.002	2	0.57	0.006	0.07	0.2	0.04	0.9	1.4	0.06	2	1.9	<0.2
1283204	Soil	11	0.06	1259	0.002	2	0.30	0.002	0.07	<0.1	0.46	5.6	0.2	<0.05	<1	2.6	<0.2
1283205	Soil	4	0.03	90	0.004	2	0.53	0.019	0.06	<0.1	<0.01	0.6	<0.1	0.05	2	<0.5	<0.2
1283206	Soil	21	0.04	164	0.003	2	0.46	0.004	0.11	<0.1	0.02	0.6	0.1	0.05	2	0.9	0.2
1283207	Soil	9	0.02	85	0.004	1	0.50	0.012	0.07	<0.1	0.01	0.1	0.2	0.08	2	0.9	<0.2
1283208	Soil	15	0.06	461	0.002	2	0.59	0.005	0.10	<0.1	0.11	0.9	0.3	0.08	1	2.2	<0.2
1283209	Soil	11	0.05	562	0.003	3	0.83	0.006	0.09	<0.1	0.09	1.2	0.3	0.10	2	2.4	<0.2
1283210	Soil	13	0.07	1149	0.004	4	1.21	0.006	0.10	<0.1	0.17	2.4	0.5	0.09	1	5.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283211	Soil		15.8	9.4	3.4	57	<0.1	23.6	1.5	17	0.53	9.8	<0.5	<0.1	4	0.2	1.4	<0.1	68	0.03	0.047	3
1283212	Soil		68.5	91.5	13.8	1289	1.7	186.0	6.0	149	1.68	58.8	1.4	1.0	93	16.3	19.0	0.2	668	1.73	0.136	13
1283213	Soil		40.9	49.1	11.4	520	1.2	109.2	6.4	180	1.40	38.4	0.9	0.5	76	8.0	9.3	0.1	182	1.29	0.100	9
1283214	Soil		49.8	61.0	16.1	619	1.4	109.5	6.7	150	2.16	56.9	3.0	0.9	47	4.8	12.4	0.2	331	0.48	0.069	11
1283215	Soil		46.2	71.6	8.2	919	0.7	138.5	3.6	81	1.20	33.1	1.7	0.5	66	8.9	10.9	0.1	359	1.28	0.107	12
1283216	Soil		104.1	156.0	14.0	1497	2.4	270.6	5.5	164	1.61	57.1	1.8	0.9	267	16.6	30.9	0.1	885	7.25	0.121	18
1283217	Soil		66.1	77.5	9.1	441	0.6	182.7	7.3	193	1.67	41.5	1.6	1.3	117	4.2	10.0	0.1	172	5.05	0.097	13
1283218	Soil		74.1	92.7	11.2	676	0.7	207.7	7.4	237	1.69	46.9	1.3	1.7	175	5.7	15.0	0.1	272	6.01	0.113	12
1283219	Soil		120.2	158.1	16.3	2151	2.0	339.8	7.4	249	1.79	69.8	<0.5	1.2	119	15.3	32.4	0.2	686	3.11	0.115	19
1283220	Soil		71.6	98.2	12.5	1107	1.2	237.4	9.7	330	1.84	49.9	0.5	1.9	178	8.5	18.9	0.1	363	5.91	0.087	12
1283221	Soil		61.3	96.8	10.0	966	1.2	184.1	8.3	200	1.48	44.5	1.7	0.9	65	12.3	14.6	0.2	337	1.27	0.072	15
1283222	Soil		112.7	94.4	10.0	432	0.6	261.0	9.8	177	2.16	50.9	0.7	1.7	286	3.6	7.7	0.1	122	7.56	0.094	10
1283223	Soil		44.9	74.3	32.1	323	1.3	88.3	6.4	115	2.41	82.5	1.4	1.0	99	2.9	13.1	0.3	157	0.29	0.076	7
1283224	Soil		8.6	64.4	27.3	213	0.7	54.2	22.2	1021	3.36	16.5	3.1	0.4	12	0.8	3.2	0.4	92	0.09	0.099	7
1283225	Soil		3.6	34.0	7.5	90	0.2	22.1	5.9	180	1.47	13.8	<0.5	0.1	10	0.2	1.3	0.2	39	0.06	0.071	3
1283226	Soil		8.0	59.9	17.7	169	1.3	45.5	12.7	386	3.24	15.9	2.1	0.2	9	0.3	2.6	0.3	82	0.03	0.082	5
1283227	Soil		7.3	17.4	10.0	54	0.3	15.1	2.2	48	1.04	8.9	<0.5	0.1	14	0.3	1.6	0.2	60	0.03	0.051	5
1283228	Soil		1.3	5.8	3.3	10	0.2	2.8	0.5	14	0.34	1.5	<0.5	<0.1	6	<0.1	0.3	<0.1	12	0.03	0.024	1
1283229	Soil		16.2	21.5	19.8	122	0.1	31.2	3.5	83	1.82	20.0	0.5	0.1	11	0.1	3.0	0.3	109	0.02	0.049	10
1283230	Soil		11.3	13.6	8.3	95	0.4	22.4	2.2	98	1.06	9.7	1.3	0.2	12	0.2	2.0	0.1	68	0.05	0.074	4
1283231	Soil		15.4	20.9	13.4	130	0.4	33.5	4.1	183	1.80	14.4	0.6	0.1	11	0.3	3.0	0.2	102	0.02	0.072	10
1283232	Soil		11.9	19.1	32.5	59	1.4	15.4	2.1	48	1.23	27.8	1.8	0.1	19	0.1	3.6	0.3	81	0.03	0.053	7
1283233	Soil		13.2	24.0	22.0	118	0.2	28.4	4.7	102	1.96	18.8	<0.5	0.2	23	0.2	3.3	0.2	99	0.01	0.064	7
1283234	Soil		10.7	26.4	19.4	111	0.6	24.3	4.0	76	1.83	12.1	0.6	0.2	18	0.8	2.6	0.3	98	0.03	0.064	11
1283235	Soil		15.0	25.4	52.8	118	1.1	26.7	4.0	110	2.49	19.5	0.6	0.2	76	0.4	3.4	0.3	109	0.03	0.105	9
1283236	Soil		1.0	6.6	2.5	5	2.6	1.9	0.4	23	0.32	<0.5	1.0	<0.1	9	0.4	0.2	<0.1	11	0.03	0.039	2
1283237	Soil		19.2	63.7	86.2	16	1.4	6.3	0.3	7	1.18	15.9	1.0	0.2	157	0.2	4.2	0.3	52	0.02	0.063	2
1283238	Soil		0.9	8.4	8.9	6	0.5	2.0	0.5	11	0.27	1.4	<0.5	<0.1	23	0.2	0.2	<0.1	9	0.04	0.051	1
1283239	Soil		7.8	29.9	39.0	45	1.1	13.5	2.0	48	1.36	10.3	0.7	0.1	73	0.5	2.1	0.3	78	0.08	0.138	5
1283240	Soil		27.9	124.8	97.8	38	4.6	23.0	0.5	11	3.33	132.3	<0.5	2.8	211	0.8	7.1	0.4	216	0.07	0.283	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283211	Soil	6	0.02	54	0.002	<1	0.25	0.015	0.03	<0.1	0.04	0.2	0.4	<0.05	1	<0.5	<0.2
1283212	Soil	43	0.62	379	0.003	7	0.44	0.007	0.14	0.2	1.00	3.0	2.1	0.09	2	6.4	<0.2
1283213	Soil	21	0.34	380	0.003	4	0.63	0.010	0.07	0.2	0.81	2.3	1.3	0.13	1	4.8	<0.2
1283214	Soil	27	0.08	367	<0.001	4	0.44	0.005	0.12	0.2	0.69	3.6	1.3	0.09	1	3.9	<0.2
1283215	Soil	24	0.26	391	0.003	2	0.55	0.017	0.07	0.2	0.47	1.8	1.4	0.08	1	3.2	<0.2
1283216	Soil	52	1.80	338	0.005	8	0.54	0.010	0.14	0.3	1.02	3.0	4.5	<0.05	2	6.7	<0.2
1283217	Soil	22	2.49	282	0.003	8	0.37	0.008	0.12	0.2	0.38	3.1	2.3	<0.05	<1	2.8	<0.2
1283218	Soil	22	2.62	269	0.003	6	0.30	0.008	0.08	0.3	0.39	3.1	2.6	<0.05	<1	3.5	<0.2
1283219	Soil	44	1.28	396	0.005	8	0.65	0.011	0.14	0.3	0.67	3.6	4.5	0.09	2	7.6	0.2
1283220	Soil	28	2.61	329	0.004	8	0.38	0.010	0.10	0.3	0.76	3.7	3.6	0.06	1	5.8	<0.2
1283221	Soil	35	0.15	434	0.002	4	0.50	0.003	0.08	0.3	0.45	3.5	2.1	0.12	2	5.6	<0.2
1283222	Soil	20	2.07	447	0.002	6	0.22	0.007	0.08	0.3	0.41	3.4	3.6	<0.05	<1	4.1	<0.2
1283223	Soil	16	0.04	443	0.001	3	0.31	0.005	0.16	0.1	0.78	4.3	1.0	0.32	1	4.5	<0.2
1283224	Soil	19	0.09	203	0.002	2	0.52	0.009	0.10	<0.1	0.06	2.6	0.4	0.07	2	1.4	<0.2
1283225	Soil	8	0.03	112	0.002	1	0.53	0.019	0.04	<0.1	0.02	0.5	0.2	0.08	2	0.7	<0.2
1283226	Soil	18	0.04	144	0.002	2	0.53	0.005	0.10	<0.1	0.10	1.9	0.3	0.07	2	1.5	<0.2
1283227	Soil	9	0.02	93	0.004	<1	0.33	0.012	0.04	<0.1	0.04	0.3	0.1	0.06	2	0.9	<0.2
1283228	Soil	3	0.01	29	0.005	<1	0.47	0.029	0.03	<0.1	0.02	0.4	<0.1	<0.05	2	<0.5	<0.2
1283229	Soil	15	0.04	108	0.005	<1	0.64	0.004	0.05	0.1	0.02	0.3	0.3	<0.05	4	2.0	<0.2
1283230	Soil	9	0.03	116	0.006	1	0.36	0.012	0.05	<0.1	0.04	0.3	0.3	<0.05	2	1.3	<0.2
1283231	Soil	14	0.04	115	0.004	1	0.59	0.007	0.07	0.1	0.02	0.2	0.2	<0.05	4	1.5	<0.2
1283232	Soil	12	0.02	174	0.003	2	0.44	0.009	0.05	0.1	0.08	0.1	0.9	<0.05	3	3.4	0.2
1283233	Soil	14	0.04	280	0.004	1	0.57	0.003	0.06	0.1	0.03	0.5	0.4	<0.05	3	2.1	<0.2
1283234	Soil	15	0.04	477	0.005	2	0.57	0.005	0.08	0.2	0.04	0.5	0.3	<0.05	4	2.0	<0.2
1283235	Soil	19	0.08	704	0.007	<1	0.83	0.004	0.08	0.2	0.07	0.4	0.7	0.07	4	3.0	<0.2
1283236	Soil	3	0.01	77	0.006	<1	0.70	0.032	0.03	<0.1	0.04	0.4	0.1	<0.05	2	1.1	<0.2
1283237	Soil	10	<0.01	722	0.001	7	0.35	0.005	0.14	0.2	3.02	0.9	1.6	0.28	1	3.2	<0.2
1283238	Soil	3	0.01	55	0.004	<1	0.22	0.026	0.03	<0.1	0.04	0.1	<0.1	<0.05	<1	<0.5	<0.2
1283239	Soil	18	0.03	499	0.004	<1	0.55	0.010	0.07	<0.1	0.19	0.3	0.2	0.11	3	2.1	<0.2
1283240	Soil	69	0.01	276	0.003	5	0.47	0.010	0.30	0.1	2.57	10.4	1.0	0.74	6	29.3	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283241	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1283242	Soil	4.3	8.9	61.0	7	2.2	4.2	0.2	3	0.26	14.3	<0.5	0.2	12	0.1	2.0	0.1	28	<0.01	0.009	<1
1283243	Soil	6.3	17.9	88.7	16	3.4	7.2	0.4	6	0.58	38.2	1.0	0.2	20	<0.1	2.9	0.2	43	0.01	0.013	<1
1283244	Soil	14.6	177.3	43.9	229	2.6	51.4	8.1	164	3.20	28.5	3.2	0.8	56	1.7	3.9	0.4	94	0.26	0.103	3
1283245	Soil	13.8	47.0	39.2	150	2.6	33.6	4.1	96	1.35	20.6	3.1	0.3	40	1.7	4.6	0.3	80	0.64	0.064	2
1283246	Soil	19.1	35.4	40.3	107	2.8	25.0	1.6	23	1.13	22.2	3.2	0.2	28	1.0	4.2	0.2	98	0.20	0.066	2
1283247	Soil	51.5	87.8	47.4	510	2.6	98.3	6.4	140	1.91	50.7	3.1	0.7	53	4.6	13.3	0.3	268	0.38	0.091	6
1283248	Soil	187.8	152.6	19.7	1928	2.1	402.9	16.1	222	3.14	353.2	0.8	3.3	192	10.0	31.7	0.2	563	7.39	0.110	15
1283249	Soil	93.2	116.6	20.5	674	0.4	225.4	11.9	345	3.32	87.0	<0.5	2.3	228	3.7	7.3	0.2	60	9.15	0.096	10
1283250	Soil	57.5	58.7	11.3	587	0.9	135.1	6.8	172	1.87	35.1	1.2	0.8	37	6.7	6.3	0.2	189	0.67	0.070	9
1283401	Soil	1.1	57.7	13.3	51	1.2	51.6	8.2	233	1.59	7.5	4.0	0.6	75	0.9	0.8	0.2	17	1.53	0.099	4
1283402	Soil	2.1	18.6	24.4	42	0.4	13.4	3.0	48	1.48	11.5	1.4	0.9	86	0.4	1.1	0.2	38	0.57	0.081	4
1283403	Soil	0.9	30.3	27.2	17	1.4	24.7	3.9	35	1.17	4.5	4.6	0.5	72	0.4	1.1	0.4	19	1.09	0.115	3
1283404	Soil	2.4	22.0	14.0	91	0.1	38.9	10.7	213	2.95	12.7	1.5	1.8	24	0.4	0.7	0.2	33	0.46	0.045	2
1283405	Soil	4.8	22.6	12.5	60	0.2	21.3	6.2	137	1.28	11.0	1.4	0.9	39	0.5	1.0	0.2	28	0.31	0.045	4
1283406	Soil	3.8	20.6	13.1	36	0.4	18.4	2.2	20	0.94	8.5	1.2	0.6	34	0.6	0.7	0.2	23	0.24	0.041	2
1283407	Soil	2.7	18.9	12.4	28	0.7	14.7	2.1	21	1.24	9.1	2.4	0.8	23	0.7	0.6	0.2	22	0.13	0.051	3
1283408	Soil	2.5	24.1	13.1	82	0.6	29.2	10.0	153	1.73	11.0	2.3	1.2	60	0.5	0.8	0.2	32	0.40	0.049	4
1283409	Soil	3.0	10.1	8.0	51	<0.1	9.4	2.1	31	1.10	11.1	1.0	1.0	19	0.3	1.1	0.1	30	0.09	0.023	5
1283410	Soil	1.3	12.7	6.7	37	0.4	13.2	2.4	27	1.07	6.1	2.5	0.5	54	0.3	0.6	0.1	19	0.56	0.046	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001377.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283241	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1283242	Soil	7	<0.01	70	<0.001	<1	0.09	0.001	0.02	<0.1	0.18	0.3	0.4	<0.05	<1	4.7	<0.2
1283243	Soil	9	<0.01	114	<0.001	<1	0.12	0.002	0.04	<0.1	0.19	0.5	0.4	<0.05	1	9.3	<0.2
1283244	Soil	29	0.05	195	<0.001	2	0.59	0.005	0.09	<0.1	0.20	7.7	0.6	0.06	3	6.3	<0.2
1283245	Soil	14	0.06	188	<0.001	3	0.24	0.005	0.05	<0.1	0.18	2.1	0.6	0.13	1	6.7	<0.2
1283246	Soil	20	0.04	143	0.001	3	0.21	0.006	0.06	<0.1	0.17	1.7	0.5	0.14	2	5.9	<0.2
1283247	Soil	28	0.08	310	0.002	4	0.40	0.005	0.09	0.2	0.26	2.6	1.4	0.07	2	8.8	<0.2
1283248	Soil	34	1.84	298	0.002	6	0.54	0.005	0.11	0.4	0.75	3.6	5.8	0.11	2	9.2	<0.2
1283249	Soil	15	3.45	641	0.002	7	0.34	0.010	0.10	0.2	0.80	3.1	2.8	0.15	<1	5.1	<0.2
1283250	Soil	19	0.08	314	0.004	3	0.54	0.012	0.05	0.2	0.50	2.5	1.5	0.12	1	4.1	<0.2
1283401	Soil	13	0.23	573	0.002	2	0.89	0.008	0.04	<0.1	0.25	2.9	0.2	0.18	2	2.6	<0.2
1283402	Soil	15	0.11	291	0.003	1	0.64	0.005	0.06	<0.1	0.05	1.7	0.1	0.08	3	0.8	<0.2
1283403	Soil	8	0.10	742	0.002	1	0.72	0.009	0.04	<0.1	0.35	1.8	0.3	0.20	2	2.9	<0.2
1283404	Soil	27	0.52	421	0.001	2	1.33	0.005	0.08	<0.1	0.05	2.4	0.1	<0.05	4	1.2	<0.2
1283405	Soil	10	0.08	701	0.001	2	0.51	0.006	0.08	<0.1	0.09	1.7	0.2	<0.05	1	1.0	<0.2
1283406	Soil	6	0.07	809	<0.001	2	0.43	0.006	0.09	<0.1	0.08	1.0	0.2	<0.05	1	0.6	<0.2
1283407	Soil	8	0.05	641	<0.001	2	0.56	0.005	0.07	<0.1	0.14	1.4	0.2	<0.05	2	1.1	<0.2
1283408	Soil	14	0.13	997	0.001	1	0.75	0.011	0.07	<0.1	0.20	2.5	0.1	<0.05	2	1.7	<0.2
1283409	Soil	7	0.07	145	0.003	<1	0.37	0.005	0.06	<0.1	0.01	0.9	0.1	<0.05	2	0.6	<0.2
1283410	Soil	8	0.13	526	0.004	2	0.49	0.018	0.04	<0.1	0.10	1.3	<0.1	0.05	2	1.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

QUALITY CONTROL REPORT WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1281887	Soil	49.3	34.6	9.4	405	0.3	86.4	3.6	50	1.23	35.8	<0.5	0.4	25	1.8	12.4	0.1	267	0.41	0.066	11
REP 1281887	QC	46.7	33.0	8.7	389	0.3	79.8	3.3	46	1.08	34.7	<0.5	0.4	23	1.8	12.0	0.1	262	0.39	0.061	11
1281899	Soil	10.3	32.6	27.6	157	1.4	40.6	7.7	190	3.29	20.8	1.7	1.9	17	0.3	4.1	0.4	108	0.03	0.034	11
REP 1281899	QC	10.3	31.6	27.0	153	1.4	38.5	7.8	188	3.17	20.0	1.3	2.0	17	0.3	4.0	0.3	105	0.03	0.036	11
1282519	Soil	12.1	18.7	77.0	24	1.5	5.3	1.0	29	1.40	57.1	32.6	0.9	130	0.3	11.1	0.4	90	0.03	0.116	7
REP 1282519	QC	12.7	18.4	75.7	22	1.6	5.4	1.0	29	1.39	56.5	39.6	0.8	123	<0.1	11.0	0.4	88	0.03	0.112	6
1282642	Soil	0.9	21.2	13.6	190	0.7	28.1	9.6	530	2.27	7.7	1.2	0.7	60	2.0	0.7	0.2	51	1.56	0.086	14
REP 1282642	QC	0.9	21.0	13.8	192	0.7	29.5	9.7	540	2.37	7.8	<0.5	0.8	61	1.7	0.7	0.3	50	1.60	0.088	14
1282650	Soil	1.5	19.2	17.8	53	0.1	8.1	1.4	39	1.12	50.9	4.8	0.5	8	0.7	1.4	0.1	30	0.02	0.039	2
REP 1282650	QC	1.4	18.8	17.7	51	0.2	8.4	1.5	38	1.12	51.5	4.5	0.5	9	0.9	1.6	0.1	32	0.03	0.038	3
1283017	Soil	4.3	13.0	7.8	44	0.2	9.1	2.0	34	0.80	9.6	<0.5	0.2	8	<0.1	1.2	0.1	51	0.02	0.029	8
REP 1283017	QC	4.0	12.5	7.6	42	0.2	9.1	2.0	33	0.78	9.6	0.8	0.2	8	0.1	1.1	0.1	49	0.01	0.028	8
1283039	Soil	5.9	28.5	15.9	96	0.3	21.5	5.1	95	2.04	16.4	0.5	0.4	13	0.3	2.0	0.2	57	0.01	0.060	5
REP 1283039	QC	6.0	29.0	15.8	98	0.4	22.3	5.1	98	2.10	16.0	2.4	0.3	13	0.3	2.0	0.3	57	0.01	0.062	5
1283047	Soil	4.5	21.3	10.4	70	0.3	13.6	3.2	63	1.40	12.8	<0.5	0.7	10	0.7	1.2	0.2	61	0.03	0.058	7
REP 1283047	QC	4.4	21.1	10.8	71	0.3	14.3	3.3	63	1.42	12.4	<0.5	0.6	11	0.4	1.3	0.2	63	0.02	0.059	5
1283081	Soil	8.7	29.6	14.8	139	0.4	30.4	5.6	158	1.85	16.4	3.2	1.2	44	0.6	2.3	0.2	65	0.35	0.075	7
REP 1283081	QC	8.6	28.5	14.4	138	0.4	30.0	5.9	166	1.82	15.6	2.8	1.8	43	0.6	2.4	0.2	66	0.35	0.075	7
1283107	Soil	3.3	16.9	12.3	87	<0.1	19.1	4.8	81	2.41	22.8	2.9	1.4	15	0.1	1.9	0.2	40	0.03	0.042	6
REP 1283107	QC	3.3	16.7	12.5	84	<0.1	18.6	4.6	85	2.40	22.6	4.7	1.3	14	0.2	1.7	0.2	40	0.04	0.041	5
1283122	Soil	12.8	30.5	19.0	160	0.7	36.1	5.7	124	2.70	21.6	6.3	0.5	25	0.5	3.5	0.3	95	0.07	0.092	12
REP 1283122	QC	12.1	28.1	17.1	156	0.7	36.6	5.4	118	2.58	17.4	4.7	0.3	24	0.4	3.2	0.3	88	0.06	0.090	12
1283161	Soil	1.3	38.7	14.3	39	1.0	25.7	3.2	29	2.02	10.9	3.8	1.1	43	0.7	0.7	0.2	27	0.28	0.090	6
REP 1283161	QC	1.3	38.8	14.2	37	1.0	25.9	3.1	29	1.97	11.2	4.8	1.1	41	0.6	0.7	0.2	30	0.29	0.087	6
1283178	Soil	4.8	13.5	18.0	40	0.7	12.6	1.2	25	1.14	22.2	2.9	<0.1	37	0.1	1.8	0.3	49	0.04	0.065	6
REP 1283178	QC	4.6	13.1	18.0	39	0.7	12.7	1.2	25	1.16	22.3	6.6	0.1	38	0.1	1.7	0.3	52	0.04	0.066	6
1283187	Soil	5.7	19.2	19.4	59	2.6	16.4	1.4	22	1.78	36.2	11.6	0.5	45	<0.1	5.9	0.3	29	<0.01	0.050	2
REP 1283187	QC	5.4	19.3	19.3	62	2.6	16.1	1.3	22	1.74	34.7	9.8	0.5	44	<0.1	5.7	0.3	29	0.01	0.051	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

QUALITY CONTROL REPORT WHI11001377.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1281887	Soil	20	0.10	236	0.004	3	0.57	0.014	0.05	0.2	0.15	1.0	1.8	<0.05	2	2.2	<0.2
REP 1281887	QC	19	0.10	232	0.004	2	0.55	0.011	0.05	0.2	0.13	1.1	1.6	<0.05	2	1.9	<0.2
1281899	Soil	21	0.11	142	0.011	3	0.98	0.003	0.06	0.2	0.03	2.7	0.4	<0.05	5	2.6	<0.2
REP 1281899	QC	20	0.11	143	0.010	2	0.98	0.003	0.06	0.1	0.04	2.6	0.3	<0.05	5	2.9	<0.2
1282519	Soil	18	0.04	1579	0.006	6	0.52	0.006	0.15	0.4	3.83	1.7	1.7	0.22	3	9.3	<0.2
REP 1282519	QC	18	0.04	1500	0.005	5	0.48	0.006	0.15	0.4	3.71	1.8	1.5	0.22	3	9.4	<0.2
1282642	Soil	30	0.31	576	0.009	2	1.43	0.011	0.06	0.1	0.05	2.0	0.1	0.06	4	1.7	<0.2
REP 1282642	QC	30	0.31	588	0.008	2	1.48	0.012	0.06	0.2	0.04	2.1	0.1	0.05	4	1.7	<0.2
1282650	Soil	10	0.01	93	0.004	4	0.24	0.009	0.03	<0.1	0.07	1.0	<0.1	0.09	2	0.9	<0.2
REP 1282650	QC	10	0.01	96	0.004	4	0.23	0.009	0.04	<0.1	0.04	1.1	<0.1	0.08	2	0.6	<0.2
1283017	Soil	7	0.03	148	0.005	<1	0.55	0.010	0.03	0.1	0.02	0.6	0.2	<0.05	3	0.6	<0.2
REP 1283017	QC	7	0.02	145	0.005	1	0.53	0.010	0.03	<0.1	0.01	0.5	0.1	<0.05	3	<0.5	<0.2
1283039	Soil	10	0.03	151	0.002	<1	0.45	0.002	0.05	<0.1	0.04	1.2	0.2	<0.05	2	0.9	<0.2
REP 1283039	QC	10	0.03	145	0.003	1	0.45	0.002	0.05	<0.1	0.05	1.3	0.1	<0.05	2	1.3	<0.2
1283047	Soil	10	0.04	123	0.004	3	0.65	0.006	0.05	<0.1	0.04	1.4	0.2	<0.05	3	<0.5	<0.2
REP 1283047	QC	11	0.04	126	0.004	3	0.68	0.006	0.05	<0.1	0.03	1.4	0.1	<0.05	4	0.7	<0.2
1283081	Soil	14	0.16	642	0.002	3	0.67	0.007	0.06	0.1	0.13	1.7	0.2	<0.05	2	1.3	<0.2
REP 1283081	QC	14	0.16	648	0.005	3	0.67	0.006	0.06	<0.1	0.13	1.8	0.2	<0.05	2	1.9	<0.2
1283107	Soil	12	0.12	203	0.002	<1	0.67	0.005	0.05	0.1	0.02	1.3	0.1	<0.05	3	1.4	<0.2
REP 1283107	QC	14	0.12	201	0.002	1	0.69	0.005	0.05	0.1	0.01	1.4	0.1	<0.05	3	0.8	<0.2
1283122	Soil	22	0.24	459	0.009	2	1.14	0.006	0.08	0.3	0.10	1.6	0.4	<0.05	4	1.7	<0.2
REP 1283122	QC	25	0.23	430	0.009	6	1.05	0.006	0.08	0.2	0.09	1.5	0.4	<0.05	4	1.5	<0.2
1283161	Soil	15	0.12	843	0.001	<1	1.00	0.007	0.05	<0.1	0.44	3.7	0.2	0.11	2	1.8	<0.2
REP 1283161	QC	14	0.12	851	0.002	1	1.01	0.008	0.05	0.1	0.43	3.8	0.2	0.11	2	2.0	<0.2
1283178	Soil	12	0.03	346	0.002	<1	0.48	0.005	0.05	<0.1	0.18	0.1	0.3	<0.05	3	1.2	<0.2
REP 1283178	QC	13	0.03	352	0.002	<1	0.51	0.006	0.06	<0.1	0.19	0.1	0.3	0.05	3	1.3	<0.2
1283187	Soil	15	0.01	630	<0.001	2	0.34	0.003	0.08	<0.1	0.77	1.2	0.2	0.10	1	4.7	<0.2
REP 1283187	QC	15	0.01	594	<0.001	1	0.33	0.003	0.09	<0.1	0.71	1.2	0.2	0.11	1	4.6	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

QUALITY CONTROL REPORT WHI11001377.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1283217	Soil	66.1	77.5	9.1	441	0.6	182.7	7.3	193	1.67	41.5	1.6	1.3	117	4.2	10.0	0.1	172	5.05	0.097	13
REP 1283217	QC	67.5	78.2	9.2	464	0.6	187.5	7.5	197	1.68	42.5	<0.5	1.3	122	4.6	9.9	0.2	170	5.07	0.098	13
1283237	Soil	19.2	63.7	86.2	16	1.4	6.3	0.3	7	1.18	15.9	1.0	0.2	157	0.2	4.2	0.3	52	0.02	0.063	2
REP 1283237	QC	20.1	63.6	86.6	17	1.4	6.0	0.3	7	1.21	15.7	1.1	0.3	160	0.2	4.3	0.2	52	0.03	0.063	2
1283402	Soil	2.1	18.6	24.4	42	0.4	13.4	3.0	48	1.48	11.5	1.4	0.9	86	0.4	1.1	0.2	38	0.57	0.081	4
REP 1283402	QC	2.1	19.1	23.8	44	0.4	13.4	3.0	49	1.45	11.5	1.1	0.8	85	0.4	1.0	0.2	41	0.58	0.081	4
Reference Materials																					
STD DS8	Standard	15.0	117.7	132.0	327	1.9	40.3	8.0	644	2.53	26.5	113.2	7.2	68	2.5	5.8	7.5	44	0.72	0.084	16
STD DS8	Standard	12.8	104.7	127.1	307	1.9	37.9	7.3	609	2.44	25.5	110.4	6.3	69	2.2	5.7	6.6	41	0.68	0.079	14
STD DS8	Standard	14.1	106.6	126.5	324	1.9	38.3	7.4	643	2.52	25.5	105.4	6.9	74	2.2	5.6	6.6	43	0.74	0.082	16
STD DS8	Standard	13.4	111.3	128.6	331	1.9	37.8	7.4	628	2.54	25.0	123.9	6.8	72	2.1	6.4	7.0	44	0.73	0.083	15
STD DS8	Standard	13.5	113.8	127.0	321	1.8	40.8	7.7	634	2.55	25.5	132.9	6.9	68	2.4	5.5	6.6	44	0.71	0.082	16
STD DS8	Standard	12.4	107.1	115.0	304	1.7	35.7	7.0	585	2.34	23.2	103.5	6.3	66	2.2	5.4	6.3	40	0.68	0.076	14
STD DS8	Standard	13.7	107.0	123.5	310	1.7	37.9	7.4	622	2.41	23.2	112.5	6.4	71	2.2	5.3	6.4	43	0.70	0.080	16
STD DS8	Standard	12.7	103.4	118.2	289	1.7	36.1	6.7	571	2.29	22.9	123.5	5.8	70	2.1	5.1	6.1	41	0.68	0.074	15
STD DS8	Standard	13.4	114.4	129.4	325	1.8	40.6	7.4	629	2.54	25.9	114.5	6.5	75	2.4	6.2	7.2	41	0.68	0.086	15
STD DS8	Standard	14.0	111.4	130.8	320	1.9	39.1	7.3	649	2.56	25.6	115.5	7.0	76	2.3	6.3	7.3	43	0.77	0.085	17
STD DS8	Standard	13.3	109.0	123.3	312	1.8	39.0	7.3	603	2.49	23.4	110.5	6.6	64	2.1	5.2	6.0	40	0.68	0.076	16
STD DS8	Standard	13.9	112.6	127.2	304	1.7	40.3	7.5	618	2.44	23.0	117.2	6.9	70	2.5	5.9	6.3	43	0.70	0.076	16
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

QUALITY CONTROL REPORT WHI11001377.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1283217	Soil	22	2.49	282	0.003	8	0.37	0.008	0.12	0.2	0.38	3.1	2.3	<0.05	<1	2.8	<0.2
REP 1283217	QC	21	2.50	283	0.003	8	0.36	0.008	0.10	0.2	0.36	3.2	2.2	<0.05	<1	2.4	<0.2
1283237	Soil	10	<0.01	722	0.001	7	0.35	0.005	0.14	0.2	3.02	0.9	1.6	0.28	1	3.2	<0.2
REP 1283237	QC	10	<0.01	684	0.001	5	0.35	0.005	0.14	0.2	3.03	0.9	1.5	0.29	1	2.5	<0.2
1283402	Soil	15	0.11	291	0.003	1	0.64	0.005	0.06	<0.1	0.05	1.7	0.1	0.08	3	0.8	<0.2
REP 1283402	QC	16	0.12	297	0.004	1	0.67	0.005	0.06	<0.1	0.03	1.8	0.1	0.06	3	0.7	<0.2
Reference Materials																	
STD DS8	Standard	119	0.65	302	0.122	2	1.02	0.104	0.45	3.0	0.20	2.2	5.7	0.17	5	5.2	5.2
STD DS8	Standard	115	0.60	277	0.113	2	0.91	0.085	0.41	3.1	0.20	2.4	5.3	0.13	4	6.4	4.7
STD DS8	Standard	125	0.62	290	0.118	2	0.97	0.105	0.44	3.0	0.18	2.9	5.7	0.15	5	4.7	5.4
STD DS8	Standard	122	0.62	295	0.127	3	0.95	0.097	0.45	3.4	0.22	2.3	5.6	0.14	5	5.5	5.1
STD DS8	Standard	121	0.62	293	0.116	3	0.97	0.106	0.44	2.9	0.21	2.6	5.6	0.14	5	5.2	4.8
STD DS8	Standard	113	0.57	280	0.110	3	0.89	0.105	0.42	3.1	0.17	2.8	5.1	0.15	5	4.3	4.9
STD DS8	Standard	117	0.64	271	0.117	2	0.93	0.099	0.39	2.7	0.20	2.5	5.3	0.15	4	4.4	4.5
STD DS8	Standard	111	0.60	256	0.110	1	0.92	0.112	0.44	2.5	0.16	2.8	5.1	0.16	4	4.7	4.7
STD DS8	Standard	117	0.66	300	0.111	5	1.00	0.103	0.45	2.8	0.23	2.8	5.4	0.18	5	6.4	5.0
STD DS8	Standard	121	0.61	303	0.122	3	1.01	0.111	0.45	3.1	0.24	3.1	5.7	0.10	5	5.6	5.0
STD DS8	Standard	118	0.60	267	0.119	2	0.94	0.096	0.40	2.8	0.19	2.5	5.3	0.14	5	5.0	4.8
STD DS8	Standard	118	0.60	275	0.123	3	0.96	0.100	0.41	3.2	0.20	2.3	5.5	0.17	4	4.7	4.8
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

QUALITY CONTROL REPORT WHI11001377.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

QUALITY CONTROL REPORT WHI11001377.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 14, 2011
Report Date: October 17, 2011
Page: 1 of 6

CERTIFICATE OF ANALYSIS WHI11001378.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID:
P.O. Number
Number of Samples: 130

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	130	Sieve soil to 230 mesh			WHI
RJSV	130	Saving all or part of Soil Reject			WHI
1DX2	130	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001378.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283411	Soil		0.8	14.5	5.0	34	0.9	12.3	1.8	38	0.79	4.0	5.9	0.4	30	0.2	0.4	0.1	15	0.30	0.040	2
1283412	Soil		2.6	11.7	4.3	21	1.0	12.3	4.7	157	1.67	5.7	3.5	0.2	36	0.3	0.6	0.1	20	0.32	0.099	2
1283413	Soil		3.1	25.3	7.7	42	0.7	18.9	4.0	69	1.11	10.9	2.3	1.2	48	1.4	1.0	0.2	27	0.33	0.043	6
1283414	Soil		4.1	20.6	9.0	66	0.2	13.9	2.9	38	1.21	13.6	0.6	0.8	14	0.4	1.2	0.2	35	0.06	0.036	7
1283415	Soil		25.7	16.2	3.9	104	<0.1	35.8	2.3	17	0.77	10.3	0.5	0.1	5	0.3	1.7	0.1	86	0.05	0.048	6
1283416	Soil		24.4	19.2	9.4	98	0.2	32.5	2.6	31	0.98	13.7	3.9	0.3	18	0.3	2.7	0.2	137	0.23	0.051	7
1283417	Soil		55.2	70.3	10.2	553	0.5	165.5	7.4	229	1.86	30.2	1.2	0.7	54	4.7	5.9	0.2	119	1.47	0.098	11
1283418	Soil		15.5	42.7	22.5	177	0.6	37.5	5.2	51	1.85	21.3	3.2	0.3	22	1.0	3.4	0.2	88	0.08	0.132	13
1283419	Soil		9.0	15.0	6.7	82	0.2	20.5	3.9	46	1.25	7.8	2.4	0.5	5	0.4	1.9	0.2	87	0.01	0.029	9
1283420	Soil		9.3	17.9	8.4	77	0.1	20.8	3.9	61	1.67	10.4	1.6	0.3	6	0.2	1.9	0.2	90	0.02	0.038	10
1283421	Soil		2.0	26.8	6.4	72	1.1	21.3	4.0	132	1.01	4.3	1.9	0.4	54	0.3	1.0	0.1	18	0.56	0.071	6
1283422	Soil		9.3	33.1	11.9	156	1.0	38.3	6.8	112	2.15	13.0	1.6	0.7	19	0.4	2.5	0.2	46	0.10	0.094	11
1283423	Soil		9.9	38.8	10.9	201	1.0	40.7	6.7	85	2.19	14.9	1.9	0.9	13	0.6	3.0	0.2	46	0.04	0.082	12
1283424	Soil		13.3	39.7	13.3	220	1.8	44.1	6.0	152	1.99	15.5	2.3	0.4	24	1.2	3.3	0.2	80	0.14	0.122	9
1283425	Soil		2.0	17.5	2.5	34	1.4	8.4	0.9	25	0.45	2.9	2.2	0.1	26	0.6	0.7	<0.1	26	0.59	0.094	3
1283426	Soil		6.6	38.1	9.4	224	0.5	43.7	8.3	79	2.42	11.9	2.6	1.2	6	0.6	1.7	0.2	45	0.03	0.063	8
1283427	Soil		3.8	9.5	11.3	38	0.4	7.8	1.4	32	0.72	4.4	1.7	0.2	14	0.3	0.7	0.2	44	0.02	0.033	18
1283428	Soil		8.6	13.4	15.6	91	0.7	21.0	3.2	88	1.84	13.4	2.1	1.1	15	0.2	1.6	0.2	70	0.02	0.075	13
1283429	Soil		8.6	56.1	20.9	85	3.7	20.7	3.4	74	3.11	34.1	8.4	0.8	44	0.2	2.2	0.3	45	0.01	0.083	5
1283430	Soil		13.7	63.1	15.1	87	6.5	22.5	2.6	29	2.87	28.5	7.2	0.6	53	0.2	2.2	0.2	40	0.01	0.095	4
1283431	Soil		5.8	34.4	11.6	96	1.0	23.8	3.5	48	1.76	15.8	2.9	0.1	18	0.2	1.6	0.2	53	0.02	0.093	6
1283432	Soil		4.4	137.3	20.6	191	1.6	63.6	11.1	297	5.58	21.2	8.8	1.7	52	0.4	1.8	0.3	43	0.02	0.128	4
1283433	Soil		2.9	104.7	12.9	191	1.7	67.9	8.6	106	4.23	12.9	4.1	1.2	21	0.6	1.3	0.2	32	0.03	0.141	3
1283434	Soil		3.7	93.3	15.1	277	2.1	82.6	15.0	304	4.49	14.1	0.9	1.7	41	0.8	1.3	0.2	38	0.03	0.145	6
1283435	Soil		2.1	77.9	11.5	289	1.2	91.8	12.2	166	3.02	17.2	5.6	1.3	41	1.4	1.1	0.2	23	0.15	0.121	6
1283436	Soil		3.4	85.4	11.4	271	1.6	97.5	11.8	119	3.48	11.7	3.9	1.2	44	0.6	1.1	0.2	25	0.09	0.109	4
1283437	Soil		2.9	37.8	13.9	137	0.6	49.2	7.4	78	2.40	57.3	22.7	0.9	26	0.2	4.4	0.2	36	0.04	0.051	4
1283438	Soil		3.1	50.2	14.5	119	1.6	41.1	6.0	80	2.67	27.5	9.5	1.2	45	0.2	2.5	0.2	29	0.02	0.069	5
1283439	Soil		2.2	35.0	11.3	135	1.5	46.4	6.7	119	2.69	17.3	6.6	0.5	88	0.8	1.6	0.2	25	1.68	0.099	5
1283440	Soil		2.3	39.3	13.4	195	1.6	65.6	10.4	128	3.07	16.9	5.1	1.9	56	0.8	1.7	0.2	30	0.70	0.090	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001378.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283411	Soil	7	0.07	316	0.002	1	0.58	0.019	0.04	<0.1	0.19	1.3	<0.1	<0.05	2	1.0	<0.2
1283412	Soil	7	0.05	455	0.003	2	0.46	0.019	0.02	<0.1	0.16	0.9	0.1	0.10	1	1.5	<0.2
1283413	Soil	13	0.04	371	0.006	1	0.40	0.006	0.04	<0.1	0.07	1.4	<0.1	0.06	2	1.2	<0.2
1283414	Soil	8	0.02	224	0.002	1	0.37	0.003	0.03	<0.1	0.03	0.9	<0.1	<0.05	2	1.0	<0.2
1283415	Soil	8	0.04	142	0.002	<1	0.43	0.011	0.04	<0.1	0.03	0.4	0.9	<0.05	2	1.1	<0.2
1283416	Soil	14	0.06	255	0.003	2	0.53	0.006	0.05	0.1	0.04	0.6	0.8	<0.05	3	1.0	<0.2
1283417	Soil	21	0.22	259	0.003	6	0.41	0.005	0.06	0.1	0.46	2.8	1.7	0.07	<1	3.9	<0.2
1283418	Soil	11	0.04	551	0.003	2	0.50	0.003	0.08	<0.1	0.06	0.4	0.3	0.05	2	1.5	<0.2
1283419	Soil	7	0.03	148	0.003	2	0.44	0.008	0.04	0.1	0.02	0.5	0.2	<0.05	2	0.6	<0.2
1283420	Soil	10	0.04	230	0.005	2	0.60	0.006	0.05	<0.1	0.03	0.5	0.2	<0.05	3	<0.5	<0.2
1283421	Soil	6	0.10	2221	0.006	<1	0.43	0.020	0.05	<0.1	0.11	0.9	<0.1	0.06	1	1.4	<0.2
1283422	Soil	14	0.07	1131	0.002	3	0.48	0.005	0.08	<0.1	0.09	1.2	0.2	<0.05	2	1.7	<0.2
1283423	Soil	10	0.05	964	0.003	2	0.44	0.005	0.07	<0.1	0.14	1.8	0.2	<0.05	1	1.2	<0.2
1283424	Soil	16	0.07	957	0.002	3	0.65	0.006	0.10	<0.1	0.30	1.5	0.4	0.06	2	1.7	<0.2
1283425	Soil	5	0.11	376	0.003	<1	0.31	0.021	0.03	<0.1	0.24	0.7	0.1	0.08	<1	0.9	<0.2
1283426	Soil	9	0.04	140	0.006	1	0.47	0.008	0.07	<0.1	0.03	1.3	0.2	<0.05	3	1.1	<0.2
1283427	Soil	8	0.03	147	0.007	<1	0.45	0.004	0.05	0.1	0.03	0.2	0.2	<0.05	4	0.5	<0.2
1283428	Soil	11	0.10	154	0.006	<1	0.72	0.005	0.06	0.3	0.02	0.8	0.2	<0.05	4	1.2	<0.2
1283429	Soil	32	0.05	786	0.001	3	0.69	0.004	0.11	<0.1	0.42	2.2	0.2	0.13	3	9.4	0.2
1283430	Soil	39	0.02	676	0.001	4	0.53	0.005	0.11	<0.1	0.60	2.1	0.2	0.19	2	11.0	<0.2
1283431	Soil	18	0.02	322	0.002	4	0.44	0.004	0.07	<0.1	0.09	0.4	<0.1	<0.05	3	2.8	<0.2
1283432	Soil	41	0.11	330	0.002	1	1.31	0.005	0.08	<0.1	0.17	3.8	0.2	0.11	3	4.9	<0.2
1283433	Soil	27	0.07	192	0.002	2	1.74	0.005	0.05	<0.1	0.17	2.6	<0.1	0.09	3	3.6	<0.2
1283434	Soil	25	0.10	203	0.002	2	1.47	0.005	0.05	<0.1	0.14	3.7	0.2	<0.05	3	4.1	<0.2
1283435	Soil	16	0.08	283	0.002	1	2.03	0.010	0.05	<0.1	0.38	2.7	0.1	<0.05	2	2.5	<0.2
1283436	Soil	21	0.08	429	0.002	2	1.22	0.009	0.05	<0.1	0.23	2.7	0.1	<0.05	2	3.5	<0.2
1283437	Soil	17	0.02	198	<0.001	1	0.47	0.003	0.05	<0.1	0.33	1.3	0.1	<0.05	2	2.2	<0.2
1283438	Soil	19	0.04	265	0.001	2	0.70	0.003	0.06	<0.1	0.27	2.0	0.2	<0.05	2	2.8	<0.2
1283439	Soil	20	0.08	727	0.001	4	0.63	0.005	0.06	<0.1	0.39	2.0	<0.1	0.09	2	2.3	<0.2
1283440	Soil	24	0.10	495	0.001	2	0.82	0.005	0.07	<0.1	0.43	4.2	0.1	0.05	2	3.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001378.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283551	Soil	3.2	16.4	72.6	23	3.2	5.1	0.8	24	0.63	27.1	2.0	0.6	167	0.1	1.5	0.2	42	0.04	0.137	2
1283552	Soil	3.4	15.0	54.0	61	2.0	14.0	3.7	117	1.22	15.3	3.2	1.8	103	0.3	2.0	0.2	36	0.08	0.090	7
1283553	Soil	6.4	21.5	63.9	52	3.8	12.2	2.2	78	1.51	44.3	2.1	0.2	90	0.2	2.9	0.3	72	0.03	0.124	8
1283554	Soil	3.4	16.1	27.7	46	1.5	10.6	2.4	84	1.30	26.9	3.7	0.6	62	0.1	2.3	0.2	45	0.05	0.084	8
1283555	Soil	4.0	10.7	41.9	23	2.6	5.6	1.2	41	0.87	20.0	6.4	0.4	59	<0.1	2.3	0.2	34	0.03	0.056	4
1283556	Soil	2.5	14.6	18.1	19	1.8	5.0	1.6	86	0.72	9.4	4.7	0.2	28	<0.1	1.1	0.1	24	0.06	0.050	4
1283557	Soil	6.1	27.9	25.0	74	2.6	21.1	4.6	222	1.98	26.4	8.1	1.0	37	0.3	2.3	0.2	54	0.08	0.095	10
1283558	Soil	8.5	12.8	15.2	42	0.9	14.9	2.1	53	0.93	11.2	3.1	<0.1	25	0.2	1.6	0.2	50	0.04	0.065	6
1283559	Soil	7.7	21.3	17.7	74	1.1	19.0	3.5	137	1.56	19.6	3.4	0.4	22	0.2	1.9	0.2	54	0.05	0.065	9
1283560	Soil	11.9	21.8	33.6	54	1.2	13.9	2.2	60	1.53	14.4	1.5	0.3	21	0.3	3.1	0.3	100	0.02	0.061	6
1283561	Soil	9.8	14.3	44.5	81	0.6	18.1	2.3	50	1.40	16.0	1.5	0.3	46	0.2	2.7	0.2	87	0.02	0.055	7
1283562	Soil	7.4	18.0	27.4	76	0.7	19.2	4.3	107	1.72	29.6	1.6	0.2	52	0.3	2.8	0.2	57	0.06	0.060	10
1283563	Soil	15.5	16.6	22.5	144	0.4	34.1	3.5	76	1.74	18.3	<0.5	0.4	26	0.4	3.6	0.3	111	0.02	0.045	12
1283564	Soil	14.3	27.8	17.4	158	0.8	35.8	5.0	137	1.96	17.8	<0.5	0.2	29	1.5	3.2	0.3	93	0.03	0.076	10
1283565	Soil	4.3	15.4	17.6	55	0.6	10.8	2.1	94	1.08	9.8	1.4	0.2	32	0.8	1.4	0.2	49	0.02	0.078	8
1283566	Soil	2.5	9.1	14.7	17	1.2	4.8	1.2	56	0.67	7.2	1.5	<0.1	17	0.2	0.9	<0.1	26	0.04	0.036	3
1283567	Soil	3.1	16.3	11.1	40	2.0	8.1	1.8	51	1.13	8.0	1.4	<0.1	18	0.2	0.9	0.1	39	0.02	0.056	4
1283568	Soil	4.8	26.2	16.0	95	0.7	17.3	3.7	121	1.86	23.0	0.5	0.6	41	0.6	1.4	0.2	75	0.04	0.131	6
1283569	Soil	6.6	26.3	67.6	106	1.1	20.3	4.2	99	2.60	37.6	0.7	1.6	168	0.3	2.4	0.3	104	0.06	0.239	9
1283570	Soil	4.9	14.5	20.7	64	2.9	12.5	2.9	53	1.27	14.6	<0.5	0.2	26	0.2	1.3	0.2	55	0.02	0.058	7
1283571	Soil	6.4	36.9	28.4	97	1.9	18.7	4.0	74	1.83	17.1	1.8	0.4	30	0.3	1.9	0.4	72	0.02	0.080	10
1283572	Soil	5.4	37.7	14.4	95	0.3	22.3	3.8	57	1.70	14.5	1.5	0.8	21	0.3	1.9	0.2	56	0.02	0.065	6
1283573	Soil	3.7	25.4	10.4	38	1.0	7.5	0.9	15	14.30	9.0	3.4	1.2	19	0.1	1.4	0.2	114	0.01	0.186	3
1283574	Soil	10.0	45.0	16.6	135	0.5	35.2	4.9	78	1.82	19.1	2.9	0.7	43	1.0	2.6	0.2	70	0.19	0.066	6
1283575	Soil	8.7	33.7	16.7	115	0.2	27.2	4.9	91	2.08	21.3	1.7	0.7	25	0.5	2.6	0.2	74	0.03	0.059	7
1283576	Soil	9.5	22.5	26.0	57	0.6	16.3	2.7	28	1.96	28.5	2.4	1.4	67	0.9	2.6	0.3	41	0.05	0.063	3
1283577	Soil	6.6	29.5	19.2	62	0.3	19.8	4.0	61	1.40	13.8	3.3	0.7	30	0.6	1.5	0.2	40	0.10	0.039	3
1283578	Soil	3.3	16.9	13.5	77	0.3	16.1	4.5	113	2.33	18.8	<0.5	1.3	17	0.4	1.4	0.3	57	0.08	0.042	6
1283579	Soil	2.4	11.2	11.4	38	0.1	8.4	2.5	39	0.99	10.8	1.3	0.3	13	0.1	0.8	0.2	39	0.01	0.059	5
1283580	Soil	3.5	12.3	8.8	53	0.1	9.4	2.8	42	1.19	14.9	<0.5	0.9	10	<0.1	1.2	0.2	49	<0.01	0.026	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001378.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283551	Soil	18	0.03	2293	0.003	<1	0.34	0.002	0.06	<0.1	0.06	0.9	1.3	0.10	2	4.1	<0.2
1283552	Soil	15	0.14	867	0.011	<1	0.61	0.003	0.07	0.2	0.06	1.2	0.4	0.09	3	5.1	<0.2
1283553	Soil	20	0.06	933	0.008	<1	0.55	0.004	0.08	0.2	0.10	0.8	0.5	0.12	4	4.4	<0.2
1283554	Soil	13	0.09	969	0.010	<1	0.53	0.003	0.05	0.2	0.07	0.7	0.3	0.06	3	2.9	<0.2
1283555	Soil	12	0.05	572	0.005	<1	0.32	0.003	0.05	<0.1	0.15	0.5	0.4	0.05	3	3.9	<0.2
1283556	Soil	9	0.05	201	0.011	1	0.48	0.014	0.04	<0.1	0.07	0.5	0.3	<0.05	2	1.9	<0.2
1283557	Soil	20	0.21	238	0.013	2	0.91	0.005	0.06	0.3	0.16	1.1	0.4	0.07	4	3.1	<0.2
1283558	Soil	15	0.02	183	0.007	3	0.27	0.011	0.05	0.1	0.10	0.3	0.2	0.06	3	1.1	<0.2
1283559	Soil	16	0.15	159	0.009	1	0.75	0.007	0.05	0.2	0.04	0.8	0.3	<0.05	4	1.7	<0.2
1283560	Soil	14	0.07	301	0.005	2	0.70	0.004	0.07	0.1	0.12	0.6	1.3	0.13	3	3.1	<0.2
1283561	Soil	14	0.07	285	0.006	2	0.49	0.003	0.06	0.1	0.10	0.5	0.4	0.06	3	2.6	<0.2
1283562	Soil	16	0.16	246	0.012	2	0.81	0.009	0.05	0.2	0.07	0.7	0.2	<0.05	3	1.3	<0.2
1283563	Soil	15	0.06	199	0.017	3	0.50	0.002	0.06	0.1	0.03	1.0	0.4	<0.05	4	1.8	<0.2
1283564	Soil	19	0.07	319	0.008	2	0.75	0.003	0.08	0.1	0.06	0.4	0.3	<0.05	3	2.0	<0.2
1283565	Soil	13	0.03	378	0.007	2	0.54	0.009	0.05	<0.1	0.04	0.2	0.2	0.05	3	0.8	<0.2
1283566	Soil	6	0.04	191	0.009	2	0.52	0.026	0.03	0.1	0.14	0.3	0.3	<0.05	2	1.5	<0.2
1283567	Soil	8	0.03	455	0.004	<1	0.75	0.014	0.03	<0.1	0.03	0.2	0.1	<0.05	3	0.8	<0.2
1283568	Soil	15	0.07	405	0.004	2	1.07	0.010	0.08	0.1	0.04	1.3	0.3	<0.05	4	0.7	<0.2
1283569	Soil	24	0.09	682	0.007	1	1.10	0.006	0.08	<0.1	0.03	3.5	0.4	<0.05	5	2.0	<0.2
1283570	Soil	9	0.03	228	0.006	<1	0.42	0.006	0.04	<0.1	0.03	0.5	0.2	<0.05	3	1.0	<0.2
1283571	Soil	13	0.04	193	0.005	2	0.64	0.003	0.06	0.1	0.05	0.9	0.5	<0.05	4	1.1	<0.2
1283572	Soil	12	0.06	429	0.003	3	0.59	0.006	0.06	<0.1	0.05	1.7	0.2	<0.05	2	1.1	<0.2
1283573	Soil	12	0.03	604	0.003	2	0.54	0.004	0.05	<0.1	0.15	1.5	0.7	0.16	2	3.4	<0.2
1283574	Soil	14	0.06	1312	0.002	3	0.52	0.003	0.07	<0.1	0.13	2.0	0.3	0.05	2	1.5	<0.2
1283575	Soil	13	0.08	463	0.002	1	0.71	0.003	0.05	<0.1	0.07	1.6	0.3	<0.05	3	1.6	<0.2
1283576	Soil	7	0.01	482	<0.001	4	0.27	0.006	0.17	<0.1	0.20	2.3	1.1	0.42	1	3.0	<0.2
1283577	Soil	9	0.05	1786	0.001	3	0.46	0.003	0.07	<0.1	0.19	2.1	0.5	0.06	1	1.8	<0.2
1283578	Soil	15	0.12	306	0.003	2	0.91	0.005	0.05	<0.1	0.05	1.7	0.2	<0.05	4	1.1	<0.2
1283579	Soil	7	0.03	121	0.002	1	0.53	0.006	0.03	<0.1	<0.01	0.4	0.1	<0.05	3	<0.5	<0.2
1283580	Soil	7	0.03	169	0.002	2	0.50	0.004	0.03	<0.1	<0.01	0.9	0.1	<0.05	3	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001378.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283581	Soil		2.7	19.8	7.4	47	0.2	10.7	2.4	33	1.17	9.3	0.5	0.3	11	0.2	0.8	0.2	45	0.02	0.046	5
1283582	Soil		0.7	22.5	5.8	21	0.7	13.0	2.7	25	0.63	2.7	<0.5	0.2	12	0.4	0.2	<0.1	17	0.06	0.049	2
1283583	Soil		2.6	72.0	13.2	149	0.8	55.4	17.9	395	2.13	12.2	2.4	1.1	42	0.7	1.0	0.2	44	0.73	0.089	5
1283584	Soil		1.5	42.4	11.5	136	1.1	38.2	10.0	296	1.72	11.9	3.0	0.9	44	1.3	0.8	0.2	39	1.04	0.081	4
1283585	Soil		1.7	50.6	13.4	96	0.8	38.2	5.6	152	1.61	9.3	2.2	0.7	43	1.0	1.0	0.2	34	1.08	0.083	3
1283586	Soil		1.9	46.9	14.5	83	0.8	37.5	6.6	132	1.94	11.2	2.4	1.2	42	0.2	0.9	0.2	42	0.95	0.073	5
1283587	Soil		2.8	47.4	18.1	105	1.5	39.2	7.5	164	2.11	13.2	4.9	1.1	106	0.9	1.2	0.2	46	0.84	0.112	5
1283588	Soil		3.5	50.0	18.4	140	1.1	40.3	8.1	242	2.01	12.5	5.4	1.0	79	1.4	1.2	0.2	42	0.67	0.104	4
1283589	Soil		2.3	49.8	18.4	102	0.9	39.7	6.5	130	1.58	10.1	3.0	1.1	66	1.0	1.0	0.2	40	0.75	0.083	4
1283590	Soil		52.0	135.7	24.1	979	1.8	175.1	7.2	162	2.75	59.8	3.5	1.2	75	9.9	16.1	0.2	325	0.82	0.166	17
1283591	Soil		30.0	70.4	24.4	383	0.8	74.2	5.4	85	2.17	42.9	2.1	1.0	86	3.4	7.6	0.2	178	0.20	0.166	11
1283592	Soil		15.2	31.6	8.5	213	0.6	33.1	2.5	88	0.88	18.2	<0.5	0.3	47	2.3	4.1	0.1	173	0.62	0.098	7
1283593	Soil		40.9	120.8	27.3	1228	1.3	207.7	13.3	288	3.38	54.2	3.5	0.9	70	8.7	11.7	0.3	467	0.55	0.242	16
1283594	Soil		14.3	32.7	17.1	168	0.4	40.1	5.5	100	2.18	22.2	2.4	0.2	25	0.6	2.7	0.2	80	0.10	0.229	9
1283595	Soil		14.0	33.9	19.3	188	0.3	43.0	7.2	208	3.08	24.0	1.7	0.4	25	0.5	3.0	0.3	95	0.08	0.180	11
1283596	Soil		40.0	178.2	61.6	701	2.7	228.8	19.3	318	3.48	59.8	5.0	1.2	155	3.1	9.9	0.4	136	0.60	0.467	18
1283597	Soil		35.0	69.5	17.0	552	0.9	114.5	10.9	319	2.93	27.6	2.8	2.6	82	6.1	9.0	0.2	135	1.88	0.153	11
1283598	Soil		34.5	59.0	20.8	306	0.8	98.5	15.4	607	3.69	29.5	2.9	1.5	39	2.0	5.1	0.3	107	0.25	0.358	18
1283599	Soil		48.6	39.4	8.6	224	0.3	120.5	7.2	140	1.83	15.6	1.8	0.3	34	1.8	2.6	0.1	67	0.44	0.168	11
1283600	Soil		59.3	58.6	18.3	608	0.3	173.0	11.7	261	3.02	47.8	2.2	0.6	33	4.3	9.5	0.2	174	0.17	0.210	17
1283601	Soil		168.5	275.2	45.1	2771	3.5	442.1	22.7	360	3.95	84.7	5.3	1.7	230	46.6	33.5	0.4	1345	5.86	0.316	33
1283602	Soil		7.2	34.8	22.2	156	0.3	49.2	15.7	266	3.87	13.1	3.0	2.6	34	0.6	2.4	0.5	73	0.14	0.088	20
1283603	Soil		7.4	111.2	41.3	274	3.3	66.4	11.6	174	4.29	13.0	5.4	4.5	128	1.0	2.7	0.5	28	0.37	0.176	17
1283604	Soil		3.1	32.3	13.5	89	1.1	24.0	4.7	71	1.51	6.6	1.0	0.2	42	0.3	1.4	0.1	28	0.20	0.114	6
1283605	Soil		9.8	55.8	13.5	221	1.6	54.1	7.7	143	2.50	12.6	4.1	0.6	31	1.5	3.0	0.2	48	0.20	0.109	14
1283606	Soil		81.3	41.5	12.3	414	0.3	134.0	7.1	74	2.13	27.3	2.1	0.6	10	2.2	7.3	0.2	71	0.06	0.089	14
1283607	Soil		5.8	16.1	25.9	67	0.2	12.1	2.3	53	2.50	13.4	1.9	1.6	17	0.4	2.4	0.4	32	0.01	0.060	15
1283608	Soil		9.8	29.2	17.4	160	0.3	33.8	6.9	225	3.02	21.3	3.4	0.4	18	0.7	2.3	0.3	88	0.09	0.163	12
1283609	Soil		9.7	59.4	21.0	281	0.5	59.5	12.4	345	3.33	30.7	4.6	2.2	20	1.1	3.5	0.3	116	0.15	0.143	20
1283610	Soil		10.6	59.7	24.7	213	1.2	44.0	6.5	124	3.67	36.5	5.6	1.1	47	1.6	4.6	0.2	73	0.20	0.253	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001378.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283581	Soil	9	0.03	221	0.002	3	0.59	0.009	0.04	<0.1	0.02	0.7	0.1	<0.05	3	<0.5	<0.2
1283582	Soil	7	0.04	336	0.002	2	0.49	0.020	0.04	<0.1	0.07	0.9	0.1	<0.05	2	<0.5	<0.2
1283583	Soil	19	0.23	861	0.002	2	1.05	0.007	0.07	<0.1	0.23	3.6	0.2	0.09	3	1.7	<0.2
1283584	Soil	13	0.15	651	0.002	2	0.92	0.012	0.05	<0.1	0.28	2.4	0.2	0.11	2	1.6	<0.2
1283585	Soil	14	0.20	683	0.001	2	0.85	0.008	0.05	<0.1	0.27	2.2	0.1	0.14	2	2.3	<0.2
1283586	Soil	17	0.22	964	0.001	2	1.04	0.009	0.06	<0.1	0.24	2.9	0.1	0.09	3	1.7	<0.2
1283587	Soil	17	0.18	1223	0.001	3	1.04	0.009	0.08	<0.1	0.34	2.8	0.2	0.12	3	3.1	<0.2
1283588	Soil	17	0.15	1164	0.002	2	0.91	0.007	0.07	<0.1	0.40	2.6	0.2	0.12	3	3.5	<0.2
1283589	Soil	16	0.18	1063	0.002	3	0.85	0.006	0.06	<0.1	0.36	2.7	0.2	0.11	2	2.5	<0.2
1283590	Soil	31	0.15	771	0.005	7	0.68	0.004	0.12	0.2	0.80	4.4	1.6	0.12	2	4.7	<0.2
1283591	Soil	19	0.05	586	0.003	5	0.51	0.007	0.10	0.1	0.30	1.7	1.0	0.14	1	2.5	<0.2
1283592	Soil	14	0.08	330	0.003	4	0.56	0.021	0.04	0.1	0.30	0.9	0.9	0.07	2	1.8	<0.2
1283593	Soil	46	0.16	950	0.005	6	0.77	0.004	0.13	0.2	0.71	2.4	1.1	<0.05	2	4.8	<0.2
1283594	Soil	13	0.07	343	0.003	3	0.67	0.005	0.08	<0.1	0.08	0.3	0.4	<0.05	2	1.9	<0.2
1283595	Soil	20	0.13	181	0.006	2	1.07	0.004	0.09	0.1	0.05	0.5	0.4	<0.05	4	2.2	<0.2
1283596	Soil	25	0.05	854	0.004	3	0.73	0.003	0.11	0.3	0.54	2.3	0.5	0.10	1	6.5	0.3
1283597	Soil	15	0.90	975	0.005	5	0.44	0.005	0.11	0.1	0.38	3.9	0.5	0.05	1	3.8	<0.2
1283598	Soil	18	0.08	795	0.006	7	0.75	0.002	0.11	0.1	0.14	2.3	0.7	<0.05	2	2.8	<0.2
1283599	Soil	19	0.10	701	0.003	4	0.65	0.009	0.08	0.2	0.17	1.1	1.0	<0.05	2	2.4	<0.2
1283600	Soil	23	0.07	593	0.003	4	0.83	0.004	0.09	0.3	0.23	1.3	1.6	<0.05	2	4.4	<0.2
1283601	Soil	90	1.01	721	0.009	12	0.97	0.007	0.23	0.5	2.50	4.5	3.9	0.12	3	12.8	0.3
1283602	Soil	23	0.18	787	0.010	5	0.87	0.005	0.22	<0.1	0.08	2.8	0.2	0.08	3	1.2	<0.2
1283603	Soil	10	0.07	1349	0.003	3	0.70	0.004	0.15	<0.1	0.55	4.1	0.3	0.18	<1	5.1	0.2
1283604	Soil	8	0.06	1013	0.002	4	0.50	0.017	0.07	<0.1	0.13	0.5	0.2	0.10	1	1.6	<0.2
1283605	Soil	10	0.05	1699	0.003	4	0.50	0.009	0.08	<0.1	0.31	1.8	0.2	<0.05	1	1.8	<0.2
1283606	Soil	12	0.04	475	0.004	3	0.48	0.003	0.08	0.3	0.18	0.9	0.7	<0.05	1	2.4	<0.2
1283607	Soil	9	0.03	255	0.003	4	0.37	0.003	0.34	<0.1	0.03	0.7	0.5	0.54	2	2.1	<0.2
1283608	Soil	22	0.25	257	0.005	3	1.13	0.005	0.10	0.2	0.05	0.6	0.4	<0.05	4	1.7	<0.2
1283609	Soil	23	0.31	369	0.008	3	1.29	0.004	0.11	0.4	0.20	2.2	0.4	<0.05	4	2.2	<0.2
1283610	Soil	20	0.12	368	0.006	4	1.03	0.003	0.15	0.2	0.32	1.1	0.5	0.19	2	3.4	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001378.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283611	Soil		7.9	41.6	20.5	190	0.3	35.2	8.8	226	3.13	29.9	3.1	2.4	18	0.6	2.6	0.3	75	0.06	0.171	15
1283612	Soil		9.3	52.6	21.5	243	0.3	49.7	9.8	247	3.51	41.8	5.3	0.6	19	0.5	3.0	0.3	72	0.09	0.144	15
1283613	Soil		5.8	25.4	14.6	96	0.4	23.3	4.6	113	1.96	16.6	2.9	0.3	15	0.4	1.6	0.2	52	0.06	0.130	11
1283614	Soil		61.7	75.9	48.0	576	1.2	257.3	23.6	1028	4.88	36.0	1.9	8.7	64	2.0	5.2	0.2	92	0.70	0.282	35
1283615	Soil		33.2	29.3	17.4	284	0.3	66.6	5.3	89	1.88	28.4	1.8	0.2	10	0.3	8.0	0.2	272	0.03	0.067	17
1283616	Soil		96.9	207.0	17.1	2651	7.3	371.7	8.8	243	2.68	89.6	6.6	2.1	232	32.6	39.3	0.3	927	4.77	0.233	18
1283617	Soil		183.5	195.4	31.0	2312	6.7	326.4	5.3	94	3.30	87.3	2.9	4.9	225	49.6	37.4	0.4	2019	0.64	0.255	33
1283618	Soil		70.5	53.1	14.8	533	3.3	132.3	3.8	86	1.39	37.4	3.9	0.2	43	7.5	17.5	0.2	896	0.20	0.087	20
1283619	Soil		65.4	71.9	12.3	1424	2.2	215.8	5.6	213	1.49	37.9	3.3	0.4	90	21.0	17.2	0.2	862	0.60	0.147	17
1283620	Soil		45.2	31.4	18.9	581	2.3	86.2	9.3	385	2.56	29.9	8.5	1.1	46	2.5	6.8	0.2	190	0.56	0.124	9
1283621	Soil		28.2	33.9	19.4	330	1.2	65.0	10.5	444	2.33	24.3	6.4	1.0	47	3.5	6.4	0.2	138	0.30	0.134	9
1283622	Soil		19.0	25.6	16.7	296	0.7	60.1	9.0	325	2.97	25.3	3.9	1.2	42	2.3	4.9	0.2	107	0.37	0.150	7
1283623	Soil		16.0	50.6	22.8	379	0.8	71.4	11.5	262	3.04	27.9	4.5	3.1	60	4.1	5.8	0.2	116	0.33	0.142	12
1283624	Soil		8.7	15.6	13.0	86	0.9	20.3	3.1	54	1.32	12.3	3.0	0.3	24	0.6	2.1	0.1	68	0.06	0.065	7
1283625	Soil		6.8	18.4	16.1	116	0.5	27.7	7.0	285	2.37	18.8	4.1	0.5	28	0.7	2.7	0.2	82	0.14	0.117	10
1283626	Soil		20.0	29.1	23.2	89	2.1	22.6	3.7	64	2.32	27.1	5.2	0.4	51	0.8	4.7	0.2	147	0.04	0.145	7
1283627	Soil		11.7	15.6	16.3	66	0.9	15.2	3.0	47	1.51	12.4	1.3	0.5	20	0.3	2.5	0.2	102	0.03	0.061	3
1283628	Soil		32.2	29.3	21.0	83	2.2	14.4	1.7	23	1.73	20.2	1.7	0.2	93	0.3	7.1	0.3	339	0.03	0.115	5
1283629	Soil		3.8	8.3	10.5	44	0.2	8.3	2.2	29	1.27	9.2	<0.5	0.5	17	0.2	0.9	0.2	27	0.02	0.039	1
1283630	Soil		2.5	22.5	19.2	121	<0.1	26.6	7.2	97	2.65	11.5	<0.5	0.9	9	0.1	0.7	0.3	34	<0.01	0.036	3
1283631	Soil		1.2	11.3	6.8	40	<0.1	12.8	6.8	66	1.02	8.6	<0.5	0.2	5	<0.1	0.5	0.2	15	0.01	0.061	2
1283632	Soil		16.5	38.1	31.8	53	6.9	16.3	1.7	38	4.37	27.5	3.4	0.9	101	1.1	7.1	0.4	60	0.15	0.671	8
1283633	Soil		8.0	27.4	13.5	74	7.6	16.6	3.1	65	2.88	39.6	4.7	0.9	54	0.5	6.7	0.2	136	0.13	0.366	7
1283634	Soil		2.9	20.0	10.5	77	0.4	18.8	4.0	134	1.73	13.5	1.6	0.2	17	0.2	0.9	0.2	35	0.06	0.082	6
1283635	Soil		1.9	8.3	4.7	18	<0.1	4.2	1.0	20	0.60	4.6	0.5	<0.1	5	<0.1	0.5	0.2	25	0.02	0.045	5
1283636	Soil		2.1	11.5	11.7	50	0.4	15.6	2.3	77	1.16	9.3	2.1	<0.1	17	0.4	0.6	0.2	21	0.11	0.085	3
1283637	Soil		1.4	8.7	6.0	34	0.2	9.9	2.1	64	0.91	5.3	0.6	<0.1	6	0.1	0.6	0.1	25	0.03	0.049	5
1283638	Soil		2.1	12.5	7.3	46	0.2	10.6	2.6	65	1.79	15.2	0.6	0.8	8	0.1	0.9	0.2	45	0.03	0.033	8
1283639	Soil		3.9	33.5	18.2	83	0.5	35.1	7.7	371	3.96	19.9	2.9	2.3	27	0.4	1.4	0.3	44	0.19	0.082	5
1283640	Soil		2.0	39.8	9.8	75	2.2	22.1	5.2	243	1.74	10.3	5.2	1.2	38	1.2	0.9	0.2	36	0.20	0.093	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001378.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283611	Soil	16	0.06	263	0.006	3	0.88	0.003	0.11	0.1	0.09	1.8	0.3	<0.05	3	2.0	<0.2
1283612	Soil	17	0.17	353	0.005	3	0.95	0.003	0.13	0.1	0.10	1.1	0.3	0.07	3	1.8	<0.2
1283613	Soil	14	0.13	294	0.003	5	0.92	0.009	0.10	0.1	0.13	0.5	0.3	0.05	3	1.9	<0.2
1283614	Soil	14	0.10	1085	0.029	9	0.58	0.003	0.11	0.3	0.94	8.1	0.7	<0.05	1	3.4	<0.2
1283615	Soil	17	0.05	141	0.004	3	0.57	0.004	0.07	0.2	0.08	0.3	1.4	<0.05	4	2.2	<0.2
1283616	Soil	82	2.48	518	0.007	8	0.75	0.006	0.12	0.5	1.42	5.9	4.6	0.10	3	11.3	0.2
1283617	Soil	113	0.18	354	0.020	18	1.02	0.006	0.34	0.8	0.96	6.0	15.3	0.58	6	24.3	0.7
1283618	Soil	52	0.10	503	0.007	9	0.65	0.013	0.11	0.4	0.34	1.0	3.8	0.07	4	8.2	0.3
1283619	Soil	55	0.12	552	0.006	6	0.80	0.010	0.11	0.4	0.45	1.6	4.0	0.10	3	7.9	<0.2
1283620	Soil	28	0.20	577	0.003	3	1.10	0.007	0.09	0.2	0.59	2.1	1.0	<0.05	3	3.4	<0.2
1283621	Soil	22	0.20	670	0.003	3	1.07	0.005	0.09	0.2	0.36	1.9	0.6	<0.05	3	3.5	<0.2
1283622	Soil	20	0.19	348	0.003	3	0.78	0.005	0.07	0.1	0.30	2.0	0.5	<0.05	3	3.8	<0.2
1283623	Soil	24	0.26	581	0.009	4	0.92	0.006	0.09	0.2	0.47	3.1	0.7	<0.05	3	3.3	<0.2
1283624	Soil	14	0.12	240	0.003	13	0.60	0.006	0.06	0.2	0.18	0.5	0.5	<0.05	2	1.6	<0.2
1283625	Soil	18	0.20	204	0.007	2	0.77	0.005	0.07	0.2	0.08	0.9	0.3	<0.05	3	2.2	<0.2
1283626	Soil	19	0.09	215	0.003	2	0.67	0.005	0.07	0.3	0.41	0.8	1.3	0.09	3	5.0	<0.2
1283627	Soil	10	0.03	112	0.001	1	0.46	0.004	0.06	0.1	0.10	0.9	0.6	<0.05	2	2.5	<0.2
1283628	Soil	24	0.02	287	0.002	3	0.39	0.009	0.13	0.3	0.10	0.4	2.9	0.23	3	14.8	<0.2
1283629	Soil	5	0.02	83	<0.001	2	0.29	0.005	0.05	<0.1	0.06	0.6	0.3	0.20	1	0.7	<0.2
1283630	Soil	10	0.11	66	<0.001	<1	0.63	0.002	0.04	<0.1	0.01	2.3	0.1	0.07	2	<0.5	<0.2
1283631	Soil	6	0.03	36	0.004	1	0.25	0.008	0.04	<0.1	0.02	1.1	<0.1	<0.05	1	0.8	<0.2
1283632	Soil	42	0.02	216	0.002	2	0.47	0.023	0.28	0.1	0.41	1.5	0.6	0.85	3	10.6	0.2
1283633	Soil	20	0.08	172	0.004	<1	0.49	0.004	0.05	0.3	0.23	0.9	0.3	0.12	3	7.4	<0.2
1283634	Soil	14	0.09	244	0.003	1	0.68	0.005	0.05	0.1	0.06	0.5	0.2	0.07	3	1.0	<0.2
1283635	Soil	6	0.02	44	0.004	<1	0.46	0.011	0.03	0.1	0.04	<0.1	0.1	<0.05	2	<0.5	<0.2
1283636	Soil	16	0.04	160	0.004	1	0.33	0.008	0.05	<0.1	0.19	0.2	0.1	<0.05	2	0.6	<0.2
1283637	Soil	7	0.05	57	0.005	<1	0.39	0.007	0.03	0.1	0.04	<0.1	<0.1	<0.05	2	<0.5	<0.2
1283638	Soil	14	0.10	119	0.007	<1	0.70	0.003	0.04	0.2	0.04	0.7	0.1	<0.05	4	0.9	<0.2
1283639	Soil	20	0.31	368	0.001	<1	1.12	0.006	0.06	<0.1	0.22	2.6	0.2	0.10	3	1.4	<0.2
1283640	Soil	14	0.11	1401	0.002	<1	0.89	0.005	0.04	<0.1	0.69	1.9	0.2	0.10	3	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001378.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283641	Soil	3.8	41.0	15.4	179	0.4	31.1	11.5	532	3.54	24.1	3.1	2.9	20	0.8	2.3	0.2	47	0.14	0.154	6
1283642	Soil	2.4	15.6	14.1	76	0.2	19.6	16.6	868	2.49	10.3	1.3	1.6	16	0.2	0.7	0.2	34	0.10	0.061	5
1283643	Soil	1.4	21.7	11.7	44	0.3	17.4	10.8	831	1.89	6.4	2.2	1.4	14	0.2	0.6	0.2	23	0.10	0.069	5
1283644	Soil	2.2	10.5	5.2	40	<0.1	8.4	2.1	64	1.06	8.9	<0.5	0.9	5	<0.1	0.6	0.1	33	0.01	0.019	6
1283645	Soil	1.0	23.9	8.8	57	0.4	26.9	4.6	214	1.58	4.5	1.6	0.8	52	0.5	0.5	0.1	20	0.42	0.069	3
1283646	Soil	2.5	34.4	16.3	106	0.4	43.8	18.0	1159	3.06	11.0	2.3	2.5	43	0.5	1.0	0.2	34	0.33	0.084	5
1283647	Soil	2.2	41.7	12.0	137	0.2	40.5	10.5	325	3.30	10.1	2.3	2.9	21	0.5	1.0	0.2	32	0.19	0.098	7
1283648	Soil	3.6	43.5	17.5	185	0.7	52.7	12.4	595	3.25	13.6	4.5	2.7	58	0.7	1.3	0.3	41	0.42	0.095	7
1283649	Soil	2.6	44.8	19.1	176	0.6	55.4	14.3	737	3.33	14.3	2.5	2.8	53	0.8	1.1	0.3	31	0.32	0.097	6
1283650	Soil	2.1	47.7	13.8	153	0.9	49.7	9.2	366	2.69	11.3	5.7	2.1	94	0.4	0.7	0.2	28	0.57	0.069	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

CERTIFICATE OF ANALYSIS WHI11001378.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283641	Soil	19	0.25	222	0.002	<1	0.88	0.004	0.04	0.3	0.13	2.2	0.2	<0.05	3	1.5	<0.2
1283642	Soil	18	0.27	198	0.001	<1	0.92	0.006	0.06	0.1	0.08	1.3	0.2	<0.05	3	0.7	<0.2
1283643	Soil	13	0.17	157	0.002	<1	0.77	0.012	0.05	<0.1	0.18	1.9	0.1	<0.05	3	1.0	<0.2
1283644	Soil	8	0.07	102	0.005	<1	0.48	0.006	0.04	<0.1	0.06	0.7	0.1	<0.05	4	<0.5	<0.2
1283645	Soil	14	0.24	319	0.002	1	0.74	0.014	0.06	<0.1	0.15	1.6	<0.1	0.10	2	0.7	<0.2
1283646	Soil	24	0.46	324	0.001	1	1.27	0.006	0.07	<0.1	0.21	3.1	0.1	0.08	4	1.1	<0.2
1283647	Soil	28	0.52	365	0.002	<1	1.34	0.004	0.06	<0.1	0.14	2.5	0.1	<0.05	4	1.0	<0.2
1283648	Soil	26	0.51	585	0.001	1	1.43	0.007	0.08	<0.1	0.27	3.3	0.2	0.09	4	1.5	<0.2
1283649	Soil	26	0.51	655	0.001	2	1.31	0.006	0.07	<0.1	0.26	3.2	0.1	0.08	4	1.5	<0.2
1283650	Soil	26	0.45	900	0.001	2	1.26	0.006	0.07	<0.1	0.28	3.3	0.1	0.14	3	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

QUALITY CONTROL REPORT WHI11001378.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1283414	Soil	4.1	20.6	9.0	66	0.2	13.9	2.9	38	1.21	13.6	0.6	0.8	14	0.4	1.2	0.2	35	0.06	0.036	7
REP 1283414	QC	3.9	21.2	8.8	65	0.2	13.8	2.9	38	1.24	13.4	3.2	0.8	14	0.4	1.3	0.2	34	0.06	0.037	7
1283431	Soil	5.8	34.4	11.6	96	1.0	23.8	3.5	48	1.76	15.8	2.9	0.1	18	0.2	1.6	0.2	53	0.02	0.093	6
REP 1283431	QC	5.5	33.2	11.6	92	1.0	22.7	3.5	46	1.78	15.3	1.2	0.1	17	0.2	1.7	0.2	50	0.02	0.099	6
1283571	Soil	6.4	36.9	28.4	97	1.9	18.7	4.0	74	1.83	17.1	1.8	0.4	30	0.3	1.9	0.4	72	0.02	0.080	10
REP 1283571	QC	6.3	34.6	26.9	95	1.8	18.3	3.7	74	1.75	16.1	2.2	0.3	30	0.4	1.8	0.3	70	0.02	0.076	10
1283591	Soil	30.0	70.4	24.4	383	0.8	74.2	5.4	85	2.17	42.9	2.1	1.0	86	3.4	7.6	0.2	178	0.20	0.166	11
REP 1283591	QC	29.0	64.1	23.0	361	0.7	71.2	5.1	81	2.03	40.2	0.9	0.6	82	3.4	7.7	0.2	175	0.19	0.157	12
1283609	Soil	9.7	59.4	21.0	281	0.5	59.5	12.4	345	3.33	30.7	4.6	2.2	20	1.1	3.5	0.3	116	0.15	0.143	20
REP 1283609	QC	9.8	58.0	19.7	280	0.5	54.9	12.1	345	3.27	30.6	5.7	2.1	20	1.1	3.5	0.3	118	0.15	0.131	20
1283614	Soil	61.7	75.9	48.0	576	1.2	257.3	23.6	1028	4.88	36.0	1.9	8.7	64	2.0	5.2	0.2	92	0.70	0.282	35
REP 1283614	QC	57.0	70.1	40.7	516	1.1	237.8	21.2	956	4.31	32.2	3.6	7.9	57	1.9	5.0	0.2	84	0.59	0.258	31
Reference Materials																					
STD DS8	Standard	12.5	106.8	120.1	301	1.7	37.1	7.6	578	2.37	22.9	114.4	6.3	65	2.0	5.1	6.6	40	0.65	0.077	14
STD DS8	Standard	12.7	107.4	121.5	311	1.8	37.8	7.2	587	2.43	23.5	112.1	6.2	64	2.3	5.2	6.3	39	0.67	0.078	15
STD DS8	Standard	13.9	113.8	125.3	317	1.9	38.5	7.8	646	2.54	25.9	132.0	7.0	73	2.4	6.0	7.0	44	0.72	0.079	16
STD DS8	Standard	13.5	111.3	124.5	303	1.8	38.4	7.6	598	2.44	24.9	108.8	6.5	70	2.3	5.3	6.5	43	0.68	0.079	15
STD DS8	Standard	13.8	117.8	129.2	307	1.8	38.9	7.8	642	2.50	25.3	120.7	6.3	60	2.4	5.5	6.3	45	0.69	0.078	15
STD DS8	Standard	13.7	113.1	120.6	314	1.7	39.2	7.8	608	2.38	23.9	106.6	7.2	69	2.2	5.5	6.5	48	0.72	0.075	17
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 17, 2011

QUALITY CONTROL REPORT WHI11001378.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1283414	Soil	8	0.02	224	0.002	1	0.37	0.003	0.03	<0.1	0.03	0.9	<0.1	<0.05	2	1.0	<0.2
REP 1283414	QC	8	0.02	219	0.002	1	0.36	0.003	0.03	0.1	0.04	0.9	<0.1	<0.05	2	0.8	<0.2
1283431	Soil	18	0.02	322	0.002	4	0.44	0.004	0.07	<0.1	0.09	0.4	<0.1	<0.05	3	2.8	<0.2
REP 1283431	QC	18	0.02	313	0.003	5	0.43	0.004	0.07	0.1	0.09	0.7	<0.1	<0.05	2	3.2	<0.2
1283571	Soil	13	0.04	193	0.005	2	0.64	0.003	0.06	0.1	0.05	0.9	0.5	<0.05	4	1.1	<0.2
REP 1283571	QC	13	0.05	199	0.010	2	0.65	0.003	0.06	0.2	0.07	0.7	0.5	<0.05	3	1.9	<0.2
1283591	Soil	19	0.05	586	0.003	5	0.51	0.007	0.10	0.1	0.30	1.7	1.0	0.14	1	2.5	<0.2
REP 1283591	QC	18	0.05	573	0.004	5	0.51	0.008	0.10	0.1	0.29	1.7	1.0	0.15	1	2.4	<0.2
1283609	Soil	23	0.31	369	0.008	3	1.29	0.004	0.11	0.4	0.20	2.2	0.4	<0.05	4	2.2	<0.2
REP 1283609	QC	23	0.30	364	0.009	3	1.27	0.004	0.12	0.4	0.22	2.3	0.4	<0.05	4	1.7	<0.2
1283614	Soil	14	0.10	1085	0.029	9	0.58	0.003	0.11	0.3	0.94	8.1	0.7	<0.05	1	3.4	<0.2
REP 1283614	QC	13	0.09	969	0.026	7	0.52	0.002	0.10	0.3	0.84	7.2	0.6	<0.05	1	4.0	<0.2
Reference Materials																	
STD DS8	Standard	111	0.59	261	0.103	2	0.91	0.107	0.42	2.7	0.19	2.5	5.3	0.14	5	5.6	4.5
STD DS8	Standard	111	0.58	268	0.107	3	0.88	0.108	0.42	2.7	0.18	1.6	5.4	0.18	5	5.2	5.2
STD DS8	Standard	118	0.64	291	0.120	3	1.01	0.114	0.45	3.0	0.22	2.9	5.5	0.17	5	5.1	4.5
STD DS8	Standard	117	0.60	270	0.116	3	0.94	0.101	0.41	2.8	0.21	2.2	5.5	0.14	5	5.3	5.6
STD DS8	Standard	124	0.62	278	0.112	3	0.92	0.091	0.43	3.1	0.20	2.2	5.6	0.15	5	5.7	5.0
STD DS8	Standard	121	0.60	282	0.127	3	0.92	0.105	0.42	3.1	0.18	3.2	5.5	0.14	5	6.0	4.9
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 05, 2011
Report Date: October 31, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001404.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #21
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve soil to 230 mesh			WHI
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	320	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278961	Soil	3.7	19.9	9.5	78	0.5	20.0	2.4	30	1.61	19.3	3.4	0.4	19	0.2	1.5	0.2	29	0.04	0.076	3
1278962	Soil	4.1	24.2	10.3	91	0.4	22.6	3.4	74	1.81	22.9	3.4	0.5	23	0.3	1.7	0.2	33	0.05	0.114	3
1278963	Soil	2.2	20.1	9.5	148	1.0	38.1	3.7	80	1.91	12.2	4.6	0.6	24	0.2	1.8	0.2	33	0.17	0.079	3
1278964	Soil	3.0	17.0	6.8	59	0.4	16.1	2.3	40	1.32	11.2	2.4	0.4	15	0.1	0.8	0.1	22	0.07	0.063	2
1278965	Soil	4.3	23.0	8.5	104	0.5	24.9	3.0	50	1.76	15.0	2.4	0.3	19	0.2	1.2	0.2	26	0.07	0.084	3
1278966	Soil	3.1	23.7	10.2	68	0.3	17.8	3.5	58	1.79	16.1	2.5	0.1	10	0.1	1.2	0.2	34	0.03	0.060	4
1278967	Soil	4.9	24.9	14.4	112	0.2	30.7	5.3	85	2.67	22.3	2.6	0.5	17	0.2	1.9	0.2	40	0.11	0.084	3
1278968	Soil	3.0	23.3	9.9	119	1.4	31.4	3.9	153	1.80	9.2	3.1	0.5	43	0.3	1.3	0.2	42	0.81	0.143	5
1278969	Soil	2.2	36.5	11.0	175	1.2	52.8	5.9	138	2.13	11.4	6.4	0.6	52	0.7	1.3	0.2	28	1.05	0.110	7
1278970	Soil	3.2	31.4	11.4	92	0.8	27.5	5.1	110	1.99	12.5	3.8	0.7	21	0.2	0.9	0.2	24	0.07	0.066	3
1278971	Soil	4.3	42.3	15.5	119	1.3	38.1	7.3	159	2.70	18.0	4.5	0.9	26	0.2	1.2	0.2	23	0.05	0.069	3
1278972	Soil	3.2	35.1	12.9	100	0.8	29.7	6.0	111	2.40	20.5	4.4	0.9	18	0.2	1.2	0.2	26	0.04	0.062	4
1278973	Soil	2.3	23.0	11.3	56	1.1	17.3	3.3	72	1.56	18.4	8.2	0.3	17	0.1	0.9	0.2	24	0.04	0.096	4
1278974	Soil	2.2	45.1	15.4	69	3.6	25.6	4.9	137	1.91	34.6	25.1	0.7	51	0.2	1.8	0.2	27	0.36	0.104	4
1278975	Soil	0.3	7.1	2.0	7	0.4	2.4	1.1	75	0.34	2.2	2.0	<0.1	9	<0.1	0.1	<0.1	9	0.10	0.043	2
1278976	Soil	0.6	10.9	3.4	28	0.5	5.7	1.4	91	0.53	7.5	4.8	0.1	26	0.2	0.4	<0.1	14	0.41	0.065	3
1278977	Soil	3.8	39.6	18.8	152	2.3	50.4	7.5	134	2.44	42.7	19.5	1.6	65	0.7	2.0	0.3	22	0.31	0.094	8
1278978	Soil	2.6	37.0	12.4	105	2.6	44.9	6.7	235	3.07	9.3	4.9	0.6	54	0.5	0.7	0.2	24	1.33	0.098	10
1278979	Soil	4.1	62.4	19.1	132	1.9	41.6	6.3	119	3.31	17.5	14.1	0.7	24	0.1	1.5	0.3	33	0.02	0.093	2
1278980	Soil	7.3	49.1	13.7	94	1.6	27.9	2.7	42	2.36	23.1	4.4	0.7	26	0.1	1.4	0.2	23	0.03	0.052	3
1278981	Soil	1.6	27.1	11.7	45	0.7	11.1	1.7	36	1.47	12.6	4.6	0.4	9	<0.1	1.0	0.2	22	0.01	0.033	2
1278982	Soil	1.0	23.0	10.0	40	0.9	9.5	4.7	299	1.13	12.2	1.7	0.3	10	<0.1	0.4	0.1	15	0.05	0.049	2
1278983	Soil	1.9	153.7	31.5	570	1.9	158.2	25.1	576	10.89	116.5	5.4	1.8	39	0.3	1.1	0.3	44	0.04	0.140	3
1278984	Soil	7.9	7.0	6.4	36	0.3	6.8	1.2	19	0.55	6.3	<0.5	0.1	5	<0.1	3.2	0.1	46	0.01	0.026	4
1278985	Soil	1.1	2.2	1.9	8	0.6	2.4	0.3	7	0.16	1.0	<0.5	<0.1	4	<0.1	0.7	<0.1	13	0.02	0.022	<1
1278986	Soil	8.0	6.9	2.8	28	0.2	5.4	0.9	14	0.53	4.3	0.6	<0.1	4	<0.1	1.4	<0.1	50	<0.01	0.025	3
1278987	Soil	29.1	8.2	3.7	40	0.2	7.5	0.9	15	1.29	20.5	0.7	<0.1	3	<0.1	6.9	0.1	120	0.01	0.040	1
1278988	Soil	28.0	14.7	7.2	137	0.1	18.4	1.9	24	1.81	22.5	0.8	0.2	7	0.2	4.9	0.2	101	0.01	0.047	1
1278989	Soil	47.2	8.7	42.8	42	1.0	9.7	1.2	58	4.61	124.1	2.1	0.4	23	0.3	15.4	0.6	207	0.13	0.138	1
1278990	Soil	64.2	10.0	15.5	46	0.2	15.2	1.6	15	1.84	40.4	1.0	0.2	10	<0.1	7.3	0.3	109	0.02	0.055	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278961	Soil	12	0.02	349	<0.001	1	0.44	0.004	0.04	<0.1	0.06	0.9	<0.1	0.10	2	1.3	<0.2
1278962	Soil	12	0.02	320	0.002	2	0.57	0.004	0.04	<0.1	0.05	1.2	<0.1	0.08	2	1.5	<0.2
1278963	Soil	16	0.05	602	<0.001	1	0.61	0.006	0.03	<0.1	0.21	1.4	0.1	0.06	2	1.6	<0.2
1278964	Soil	10	0.02	412	0.001	2	0.50	0.007	0.03	<0.1	0.07	0.8	<0.1	<0.05	2	1.4	<0.2
1278965	Soil	14	0.03	300	0.001	1	0.51	0.006	0.03	<0.1	0.07	0.6	<0.1	<0.05	2	2.1	<0.2
1278966	Soil	10	0.02	198	0.002	1	0.55	0.006	0.03	<0.1	0.04	0.3	<0.1	<0.05	3	1.3	<0.2
1278967	Soil	16	0.05	208	0.001	<1	0.69	0.004	0.03	<0.1	0.08	1.2	0.1	<0.05	3	1.7	<0.2
1278968	Soil	18	0.07	1334	0.001	1	0.88	0.007	0.04	<0.1	0.11	1.3	0.2	0.17	2	1.3	<0.2
1278969	Soil	20	0.07	733	<0.001	2	0.65	0.005	0.05	<0.1	0.21	2.1	<0.1	0.15	2	2.5	<0.2
1278970	Soil	16	0.08	400	0.001	1	0.68	0.005	0.05	<0.1	0.11	2.2	<0.1	0.06	2	2.6	<0.2
1278971	Soil	17	0.07	696	<0.001	2	0.65	0.004	0.05	<0.1	0.18	3.2	0.1	0.06	2	3.5	<0.2
1278972	Soil	17	0.08	341	0.001	1	0.60	0.004	0.04	<0.1	0.09	2.1	<0.1	<0.05	2	2.5	<0.2
1278973	Soil	15	0.07	243	0.002	2	0.85	0.008	0.04	<0.1	0.13	0.8	0.1	<0.05	3	1.4	<0.2
1278974	Soil	18	0.08	1169	<0.001	1	0.98	0.009	0.09	<0.1	0.77	2.1	0.2	0.12	3	2.9	<0.2
1278975	Soil	3	0.02	148	0.007	1	0.43	0.023	0.02	<0.1	0.05	0.2	<0.1	<0.05	2	<0.5	<0.2
1278976	Soil	4	0.03	275	0.004	2	0.51	0.023	0.03	<0.1	0.08	0.3	<0.1	0.12	2	0.6	<0.2
1278977	Soil	15	0.07	663	0.001	2	0.61	0.010	0.08	<0.1	0.33	2.9	0.1	0.15	2	3.0	<0.2
1278978	Soil	22	0.16	563	<0.001	3	0.80	0.004	0.03	<0.1	0.33	3.0	<0.1	0.21	2	2.6	<0.2
1278979	Soil	22	0.04	530	0.002	5	0.59	0.007	0.08	<0.1	0.18	3.2	0.2	0.18	2	5.1	<0.2
1278980	Soil	14	0.03	554	<0.001	2	0.40	0.006	0.04	<0.1	0.23	2.4	<0.1	<0.05	1	6.2	<0.2
1278981	Soil	11	0.03	320	<0.001	2	0.47	0.005	0.04	<0.1	0.10	1.3	<0.1	<0.05	2	2.4	<0.2
1278982	Soil	6	0.07	237	0.007	1	0.44	0.017	0.04	<0.1	0.04	1.3	<0.1	<0.05	2	0.7	<0.2
1278983	Soil	21	0.18	911	<0.001	<1	1.55	0.002	0.05	<0.1	0.19	9.1	<0.1	<0.05	2	3.2	<0.2
1278984	Soil	5	0.01	98	0.001	1	0.21	0.004	0.03	0.2	<0.01	0.2	0.2	<0.05	2	0.6	<0.2
1278985	Soil	3	<0.01	87	0.001	<1	0.14	0.009	0.02	<0.1	0.01	0.2	0.1	<0.05	<1	<0.5	<0.2
1278986	Soil	7	<0.01	96	0.002	<1	0.17	0.006	0.02	0.1	<0.01	0.1	0.1	<0.05	1	<0.5	<0.2
1278987	Soil	5	<0.01	70	0.001	<1	0.18	0.009	0.02	0.2	0.02	0.1	0.3	<0.05	2	1.6	<0.2
1278988	Soil	7	0.01	167	0.001	<1	0.26	0.005	0.02	0.4	0.03	0.5	0.9	<0.05	2	2.0	<0.2
1278989	Soil	11	0.03	1562	<0.001	1	0.36	0.003	0.07	0.9	0.15	1.1	2.1	0.17	1	6.4	<0.2
1278990	Soil	7	0.01	1663	<0.001	1	0.27	0.004	0.04	0.6	0.05	0.4	1.7	0.11	1	3.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278991	Soil	20.1	8.8	19.3	128	0.6	12.5	1.8	97	0.96	14.2	<0.5	0.2	16	1.0	7.2	0.3	94	0.14	0.070	2
1278992	Soil	125.4	117.9	7.5	1244	2.1	60.6	8.0	34	18.61	452.9	2.9	1.2	56	12.2	249.6	<0.1	474	0.08	2.206	32
1278993	Soil	10.9	68.4	10.6	138	0.6	18.4	2.5	47	3.88	46.6	2.1	0.1	19	1.0	7.5	<0.1	99	0.04	0.488	4
1278994	Soil	16.1	32.4	21.1	190	2.5	53.7	5.9	228	2.92	31.9	8.6	0.3	96	1.4	9.3	0.3	173	0.24	0.350	5
1278995	Soil	8.0	25.0	16.9	156	1.5	33.8	4.5	165	1.99	16.0	6.8	0.1	91	1.2	4.2	0.2	141	0.14	0.188	5
1278996	Soil	5.8	53.9	7.5	79	0.5	13.3	1.2	19	3.03	10.9	1.7	0.4	54	0.5	2.6	0.1	72	0.02	0.089	5
1278997	Soil	2.2	6.4	5.7	15	4.0	2.7	0.5	56	0.43	2.7	1.4	<0.1	13	0.3	0.9	0.2	23	0.02	0.052	2
1278998	Soil	16.7	14.8	23.2	51	1.2	9.9	1.3	37	2.07	31.5	3.0	0.1	38	0.1	7.7	0.3	155	0.01	0.081	4
1278999	Soil	8.2	55.6	10.3	222	2.9	39.2	3.9	220	4.71	34.0	6.5	0.1	21	0.7	9.9	0.2	175	0.01	0.099	2
1279000	Soil	20.2	36.5	9.4	80	0.5	57.1	5.0	123	3.13	37.6	2.8	0.4	43	0.2	4.7	0.2	163	0.01	0.095	5
1282541	Soil	1.3	20.3	7.4	39	0.8	12.8	2.8	118	1.08	5.0	2.6	0.2	31	<0.1	0.6	0.1	15	0.29	0.078	2
1282542	Soil	1.4	10.7	5.4	28	1.7	8.5	1.7	22	0.74	4.4	2.1	0.2	15	<0.1	0.5	0.1	18	0.02	0.062	3
1282543	Soil	5.2	16.5	7.1	63	0.1	18.6	3.1	33	1.03	23.0	1.5	1.1	11	<0.1	2.2	0.1	57	0.02	0.024	9
1282544	Soil	7.3	35.0	12.2	144	0.2	36.8	6.0	77	2.05	37.6	3.0	<0.1	25	0.3	4.0	0.3	65	0.04	0.113	8
1282545	Soil	3.9	28.3	8.3	101	0.3	25.9	3.9	85	1.38	16.4	1.9	<0.1	33	1.1	1.7	0.2	38	0.23	0.135	5
1282546	Soil	4.8	21.7	11.8	102	0.2	24.1	3.7	53	1.59	46.5	3.7	0.5	23	0.1	4.0	0.2	55	0.05	0.067	7
1282547	Soil	1.8	26.1	8.4	67	0.4	17.7	2.8	90	1.04	33.0	13.3	0.4	68	0.5	3.6	0.3	17	1.69	0.079	5
1282548	Soil	2.4	21.5	17.5	103	<0.1	20.4	4.4	118	1.80	37.3	18.9	2.0	36	0.8	2.4	0.3	46	0.17	0.051	8
1282549	Soil	3.1	29.2	17.4	189	0.7	37.1	9.2	365	3.01	42.3	10.8	2.3	63	2.1	2.8	0.3	60	1.09	0.127	13
1282550	Soil	1.5	26.7	8.6	88	0.6	18.4	4.1	316	1.64	16.2	10.0	0.3	86	0.6	1.8	0.1	31	2.59	0.127	5
1282551	Soil	1.9	37.9	11.7	143	1.3	30.3	4.6	184	2.10	22.4	18.2	0.5	85	1.0	2.1	0.2	34	2.08	0.149	10
1282552	Soil	1.4	51.0	13.8	135	1.2	35.0	6.5	184	2.02	25.0	17.3	0.7	82	0.7	2.2	0.2	38	1.92	0.109	8
1282553	Soil	1.4	34.9	12.9	116	0.9	22.5	5.2	199	1.65	28.4	12.5	0.8	83	0.9	1.8	0.2	43	2.31	0.101	7
1282554	Soil	1.6	44.0	13.5	115	0.8	27.2	5.2	180	1.77	25.7	11.5	0.7	71	0.9	2.5	0.3	43	1.80	0.105	7
1282555	Soil	1.8	35.7	11.3	97	0.8	22.6	3.5	134	1.43	23.8	16.4	0.4	84	0.7	2.4	0.3	34	2.33	0.100	6
1282556	Soil	5.8	14.0	22.8	64	0.4	15.2	3.0	117	2.34	16.6	1.7	0.9	20	0.2	1.4	0.3	88	0.05	0.089	16
1282557	Soil	8.2	36.5	32.0	110	0.3	43.1	10.9	244	3.60	27.0	4.3	0.6	9	0.2	2.8	0.4	60	0.03	0.062	14
1282558	Soil	12.0	64.4	17.1	609	0.9	73.5	26.2	2523	2.94	20.1	4.7	2.5	51	8.2	3.5	0.3	93	0.51	0.143	18
1282559	Soil	8.9	64.1	19.6	225	1.9	50.2	8.6	383	2.90	21.2	5.7	1.5	54	1.6	3.7	0.3	98	0.48	0.130	11
1282560	Soil	6.2	43.5	13.7	141	0.8	30.2	5.7	135	2.06	15.2	1.2	0.4	46	1.1	1.9	0.2	55	0.87	0.115	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278991	Soil	7	0.01	1041	<0.001	1	0.29	0.003	0.06	0.5	0.05	0.6	0.8	0.12	1	1.7	<0.2
1278992	Soil	125	0.03	1254	0.008	<1	2.14	0.003	0.02	0.3	0.86	3.2	1.3	0.07	3	27.6	<0.2
1278993	Soil	14	0.02	882	0.002	<1	1.38	0.008	0.02	<0.1	0.31	0.2	0.4	0.06	2	3.1	<0.2
1278994	Soil	24	0.04	1283	0.001	2	0.79	0.005	0.06	<0.1	2.01	1.0	1.6	0.12	2	4.0	<0.2
1278995	Soil	22	0.03	1634	0.001	<1	0.57	0.003	0.06	<0.1	0.41	0.5	0.9	0.08	2	2.6	<0.2
1278996	Soil	18	0.03	459	0.001	<1	0.51	0.002	0.04	<0.1	0.09	1.2	0.3	0.05	1	3.5	<0.2
1278997	Soil	4	0.01	289	0.003	2	0.29	0.014	0.02	<0.1	0.09	0.1	0.2	<0.05	2	<0.5	<0.2
1278998	Soil	9	0.02	688	0.002	1	0.37	0.005	0.04	0.2	0.34	0.4	0.5	0.09	3	2.8	0.2
1278999	Soil	24	0.03	1322	0.003	1	0.36	0.008	0.02	0.1	0.49	1.6	0.3	0.11	2	3.2	<0.2
1279000	Soil	11	0.04	768	0.004	2	0.62	0.003	0.05	0.2	0.13	1.1	1.3	0.16	2	4.7	<0.2
1282541	Soil	10	0.04	491	0.003	1	0.60	0.018	0.03	<0.1	0.11	0.7	<0.1	0.07	2	0.9	<0.2
1282542	Soil	8	0.02	506	0.003	2	0.34	0.010	0.03	<0.1	0.06	0.3	<0.1	<0.05	2	0.6	<0.2
1282543	Soil	9	0.02	120	0.003	1	0.34	0.005	0.03	0.1	0.08	0.8	0.1	<0.05	3	1.1	<0.2
1282544	Soil	16	0.02	279	0.002	2	0.45	0.004	0.05	0.1	0.32	0.3	0.2	0.06	2	2.0	<0.2
1282545	Soil	14	0.03	248	0.002	2	0.56	0.009	0.05	<0.1	0.08	0.3	0.1	0.07	2	0.8	<0.2
1282546	Soil	10	0.02	166	0.002	3	0.38	0.006	0.04	0.1	0.52	0.9	0.2	0.05	2	1.5	<0.2
1282547	Soil	9	0.04	492	0.004	3	0.51	0.022	0.04	0.1	1.28	0.8	0.2	0.16	1	1.9	<0.2
1282548	Soil	18	0.09	493	<0.001	3	0.90	0.005	0.04	<0.1	1.24	2.4	0.2	<0.05	3	1.1	<0.2
1282549	Soil	29	0.27	585	0.007	2	0.98	0.006	0.06	0.2	0.89	2.9	0.2	0.06	3	1.5	<0.2
1282550	Soil	17	0.06	551	0.005	4	0.67	0.014	0.03	<0.1	0.54	1.1	<0.1	0.16	2	2.0	<0.2
1282551	Soil	20	0.09	641	0.003	4	0.76	0.012	0.05	0.1	0.87	1.8	0.1	0.14	2	2.0	<0.2
1282552	Soil	23	0.16	618	0.003	3	0.84	0.009	0.06	<0.1	1.11	2.5	0.2	0.13	2	2.2	<0.2
1282553	Soil	19	0.13	666	0.003	4	0.72	0.008	0.05	0.1	1.04	1.8	0.1	0.13	2	1.7	<0.2
1282554	Soil	20	0.14	606	0.003	3	0.72	0.007	0.05	<0.1	1.06	1.8	0.1	0.13	2	2.0	<0.2
1282555	Soil	16	0.12	705	0.004	4	0.67	0.011	0.05	<0.1	1.10	1.2	0.1	0.14	2	2.0	<0.2
1282556	Soil	19	0.23	226	0.011	1	0.98	0.004	0.06	0.4	0.05	1.0	0.2	<0.05	5	1.0	<0.2
1282557	Soil	14	0.11	154	0.007	2	0.58	0.006	0.07	0.5	0.10	1.2	0.2	<0.05	4	1.3	<0.2
1282558	Soil	24	0.27	1393	0.005	4	1.20	0.008	0.12	0.2	0.40	3.9	0.4	0.06	3	2.7	<0.2
1282559	Soil	21	0.24	1439	0.003	5	1.29	0.010	0.20	0.1	0.74	3.6	0.4	0.08	3	1.8	<0.2
1282560	Soil	14	0.18	1318	0.003	4	0.75	0.013	0.12	<0.1	0.12	1.2	0.2	0.07	3	1.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282561	Soil	10.4	33.7	17.9	165	0.3	35.2	8.7	62	2.60	13.9	0.7	0.3	12	1.0	2.0	0.3	92	0.02	0.069	14
1282562	Soil	9.7	28.6	26.5	140	1.0	29.9	5.5	129	3.07	24.4	2.5	2.4	37	0.5	2.5	0.3	132	0.06	0.183	16
1282563	Soil	8.5	48.3	35.0	199	0.4	42.7	18.5	3794	5.90	55.6	1.3	0.9	29	2.9	3.7	0.2	113	0.51	0.183	13
1282564	Soil	2.9	27.0	40.6	424	0.7	33.2	19.4	5569	6.28	29.0	1.9	0.7	60	8.3	2.9	0.2	57	3.41	0.215	20
1282565	Soil	20.0	40.6	50.4	218	0.6	41.8	5.5	108	2.22	31.8	1.4	0.5	41	0.4	8.7	0.4	153	0.04	0.092	13
1282566	Soil	39.7	31.5	31.3	242	2.0	63.5	3.6	61	3.18	42.9	1.5	1.3	283	1.1	10.5	0.4	143	0.05	0.172	22
1282567	Soil	34.3	28.8	19.8	262	0.9	64.4	4.4	86	2.67	39.5	2.2	0.5	61	0.8	10.2	0.3	397	0.05	0.140	18
1282568	Soil	3.3	23.6	15.5	75	0.7	21.6	2.9	134	0.87	7.6	2.0	1.0	36	8.3	1.5	0.2	58	0.28	0.073	11
1282569	Soil	21.8	33.2	25.1	235	0.1	42.0	5.9	135	3.12	47.7	1.4	0.9	23	0.8	7.3	0.3	215	0.04	0.104	13
1282570	Soil	11.1	114.4	29.4	229	0.6	56.6	10.8	98	5.65	35.3	3.4	1.5	24	0.5	5.8	0.5	118	0.03	0.117	13
1282571	Soil	5.5	11.7	13.9	62	0.2	13.0	1.7	26	0.68	7.6	0.9	0.6	15	<0.1	1.6	0.1	55	0.05	0.027	12
1282572	Soil	5.0	26.6	15.2	64	0.8	15.9	1.8	30	0.85	7.7	4.0	0.3	34	1.1	1.4	0.2	43	0.23	0.084	10
1282573	Soil	18.7	44.1	14.8	319	1.1	66.6	4.6	319	1.31	18.4	5.4	0.8	46	8.6	4.4	0.2	160	0.65	0.097	11
1282574	Soil	41.5	69.9	71.4	2362	1.0	237.4	36.5	1846	3.07	49.4	9.1	2.0	63	18.0	5.9	0.3	111	0.66	0.175	12
1282575	Soil	12.2	53.1	20.8	2893	1.4	274.7	10.2	568	1.79	19.3	7.7	1.4	61	14.3	3.5	0.2	104	0.62	0.129	11
1282576	Soil	10.3	23.5	15.2	1838	0.4	163.7	3.5	80	1.56	18.9	8.7	1.0	48	9.8	2.6	0.2	60	0.66	0.083	7
1282577	Soil	11.1	37.4	9.4	1174	1.1	132.7	4.1	89	1.14	13.1	5.7	1.0	64	6.5	4.0	0.1	98	1.22	0.060	5
1282578	Soil	4.5	4.9	3.0	129	0.3	13.8	2.3	152	0.53	5.5	1.6	<0.1	14	1.7	0.5	<0.1	13	0.23	0.029	1
1282579	Soil	11.9	13.0	10.2	195	0.5	23.7	6.6	384	1.23	9.6	2.9	0.4	30	2.1	1.3	0.1	48	0.32	0.071	3
1282580	Soil	70.5	42.4	18.5	885	1.0	144.0	19.3	624	3.32	39.6	3.6	2.6	87	9.7	11.9	0.2	207	0.18	0.114	8
1282581	Soil	37.1	60.3	16.7	2972	1.6	394.2	11.9	646	2.56	21.0	7.7	1.1	55	48.6	6.6	0.2	69	0.42	0.113	4
1282582	Soil	10.6	140.8	18.6	1416	1.4	269.6	12.1	1427	2.89	28.4	10.7	1.6	90	25.0	4.5	0.2	59	1.10	0.096	6
1282583	Soil	21.2	54.3	23.7	3100	1.3	639.4	18.4	1491	2.18	22.0	5.4	0.9	103	23.2	5.2	0.2	56	1.44	0.120	5
1282584	Soil	3.0	34.0	17.2	148	0.8	39.8	6.0	135	2.39	41.1	15.2	1.2	37	0.6	1.9	0.2	32	0.20	0.064	4
1282585	Soil	1.8	33.7	20.3	103	0.3	28.5	4.4	66	2.27	52.4	17.7	1.2	23	0.4	1.6	0.2	26	0.16	0.059	3
1282586	Soil	1.4	45.2	19.2	132	0.6	44.4	7.8	168	2.62	49.7	19.4	2.1	50	0.5	1.6	0.2	24	0.58	0.068	4
1282587	Soil	1.6	45.7	27.3	122	0.3	39.0	8.3	156	3.27	76.4	30.2	2.2	34	0.2	2.0	0.2	29	0.09	0.060	4
1282588	Soil	1.5	41.0	21.1	113	0.3	36.4	7.3	137	3.02	45.0	20.1	1.9	29	0.2	1.6	0.2	27	0.11	0.051	4
1282589	Soil	1.0	22.9	10.9	56	0.7	17.3	2.7	54	1.14	15.2	7.5	0.3	36	0.4	0.7	0.1	22	0.70	0.086	3
1282590	Soil	3.0	23.4	12.2	100	0.6	40.7	5.4	67	2.39	12.8	1.1	0.1	8	0.7	1.1	0.2	40	0.04	0.063	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282561	Soil	13	0.06	177	0.006	<1	0.70	0.004	0.09	<0.1	0.03	0.5	0.2	<0.05	3	0.7	<0.2
1282562	Soil	17	0.12	461	0.008	2	0.97	0.004	0.11	0.2	0.06	1.7	0.4	0.05	4	1.5	<0.2
1282563	Soil	22	0.19	1073	0.006	2	1.38	0.010	0.05	<0.1	0.09	2.3	0.3	0.08	4	1.3	<0.2
1282564	Soil	14	1.46	753	0.006	4	0.84	0.013	0.04	<0.1	0.15	2.4	0.3	0.10	2	1.2	<0.2
1282565	Soil	13	0.05	277	0.003	1	0.58	0.003	0.11	<0.1	0.03	0.8	0.5	0.11	3	4.2	<0.2
1282566	Soil	17	0.04	550	0.004	2	0.58	0.005	0.20	0.2	0.05	1.0	1.3	0.44	3	4.5	0.2
1282567	Soil	32	0.10	267	0.007	1	0.83	0.004	0.10	0.3	0.05	0.8	1.2	0.06	4	4.0	<0.2
1282568	Soil	12	0.07	579	0.008	2	0.70	0.006	0.06	0.1	0.15	1.3	0.3	0.07	3	1.3	<0.2
1282569	Soil	16	0.07	202	0.006	2	0.61	0.004	0.07	0.2	0.03	1.5	0.6	<0.05	3	2.3	<0.2
1282570	Soil	15	0.05	239	0.008	2	0.63	0.004	0.07	0.2	0.09	3.1	0.3	<0.05	4	4.1	<0.2
1282571	Soil	8	0.04	105	0.006	2	0.32	0.004	0.04	0.1	0.02	0.5	0.2	<0.05	3	<0.5	<0.2
1282572	Soil	11	0.04	444	0.004	1	0.48	0.009	0.06	0.1	0.17	0.6	0.2	0.12	2	1.2	<0.2
1282573	Soil	17	0.11	952	0.002	3	0.77	0.007	0.06	0.2	0.39	1.5	0.8	0.11	2	1.9	<0.2
1282574	Soil	15	0.09	612	0.003	5	0.72	0.005	0.09	0.1	0.86	3.0	0.8	0.08	2	4.2	<0.2
1282575	Soil	18	0.12	736	0.002	5	0.85	0.008	0.08	0.1	0.81	2.8	0.6	0.10	2	2.8	<0.2
1282576	Soil	15	0.14	183	0.003	3	0.50	0.005	0.05	0.1	0.17	1.2	1.1	0.08	2	1.8	<0.2
1282577	Soil	11	0.09	368	0.003	5	0.60	0.014	0.05	0.2	0.29	1.1	1.4	0.12	2	2.6	<0.2
1282578	Soil	2	0.02	88	0.006	2	0.17	0.029	0.02	<0.1	0.05	0.2	<0.1	0.06	<1	0.8	<0.2
1282579	Soil	10	0.09	429	0.002	2	0.55	0.013	0.05	<0.1	0.14	0.7	0.2	0.07	2	1.3	<0.2
1282580	Soil	24	0.15	849	0.004	3	0.65	0.004	0.11	0.4	0.35	2.4	2.3	0.17	2	6.5	<0.2
1282581	Soil	23	0.15	616	<0.001	3	1.09	0.007	0.09	0.1	1.30	2.1	1.5	<0.05	3	3.1	<0.2
1282582	Soil	28	0.20	2307	<0.001	6	1.32	0.007	0.12	0.1	0.93	3.5	0.4	0.12	3	3.2	<0.2
1282583	Soil	21	0.17	651	0.001	6	0.85	0.009	0.08	0.2	1.19	2.0	1.0	0.18	2	5.0	<0.2
1282584	Soil	24	0.20	940	<0.001	4	1.01	0.007	0.07	<0.1	0.44	2.0	0.1	0.05	3	1.4	<0.2
1282585	Soil	21	0.18	537	<0.001	3	0.86	0.004	0.06	<0.1	0.11	1.6	<0.1	<0.05	3	0.9	<0.2
1282586	Soil	26	0.27	1313	<0.001	3	1.10	0.005	0.09	<0.1	0.20	2.9	<0.1	<0.05	3	1.0	<0.2
1282587	Soil	29	0.33	792	0.001	4	1.23	0.005	0.07	<0.1	0.11	2.6	<0.1	<0.05	4	0.8	<0.2
1282588	Soil	27	0.34	718	0.001	3	1.22	0.006	0.06	<0.1	0.09	2.3	<0.1	<0.05	3	0.8	<0.2
1282589	Soil	13	0.07	743	0.001	2	0.78	0.016	0.05	<0.1	0.10	0.6	<0.1	0.07	2	0.6	<0.2
1282590	Soil	11	0.03	111	0.002	1	0.51	0.004	0.03	<0.1	0.02	0.5	<0.1	<0.05	3	0.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282591	Soil	4.2	31.9	29.9	126	0.3	25.3	8.7	391	5.30	47.6	2.5	2.3	15	0.4	2.3	0.5	76	0.10	0.214	17
1282592	Soil	2.6	22.6	15.4	72	0.4	15.1	3.6	73	2.01	22.1	0.8	0.2	24	0.3	1.3	0.3	49	0.02	0.075	10
1282593	Soil	4.9	18.4	19.6	66	0.3	15.7	4.2	120	2.52	22.1	3.2	0.4	22	0.1	2.4	0.2	36	0.05	0.050	8
1282594	Soil	0.8	3.8	3.0	10	<0.1	2.5	0.7	19	0.43	1.6	<0.5	<0.1	5	<0.1	0.2	<0.1	7	0.03	0.036	2
1282595	Soil	2.0	11.0	16.2	51	<0.1	11.9	3.6	68	1.76	8.0	0.7	0.1	7	<0.1	0.5	0.2	23	0.02	0.066	5
1282596	Soil	2.4	19.4	18.5	90	<0.1	20.0	8.0	142	2.58	13.2	<0.5	0.2	8	<0.1	0.9	0.3	29	0.02	0.122	6
1282597	Soil	1.8	17.0	11.8	72	<0.1	16.4	6.2	138	2.11	9.2	0.9	0.2	8	0.1	0.7	0.2	19	0.03	0.110	4
1282598	Soil	1.8	15.5	11.3	81	<0.1	14.9	7.7	210	1.77	8.0	0.6	0.2	19	0.2	0.8	0.2	23	0.30	0.140	4
1282599	Soil	0.6	5.7	3.9	22	<0.1	4.6	2.8	251	0.67	2.5	<0.5	<0.1	4	<0.1	0.2	<0.1	9	0.02	0.057	2
1282600	Soil	1.1	15.8	11.4	67	0.2	18.1	8.4	580	1.34	6.6	1.0	0.3	36	0.2	0.5	0.1	15	0.89	0.131	2
1282611	Soil	3.5	21.6	15.8	61	0.6	12.7	2.5	49	2.13	12.1	1.5	0.2	8	0.4	1.0	0.3	47	0.04	0.134	6
1282612	Soil	2.9	32.6	17.9	72	0.9	18.1	3.6	116	3.57	14.7	1.8	0.5	11	0.6	1.0	0.3	45	0.04	0.172	6
1282613	Soil	3.2	48.3	12.2	57	0.5	12.7	3.1	120	2.52	9.3	2.5	0.2	9	0.3	1.0	0.3	47	0.04	0.124	6
1282614	Soil	1.2	29.1	7.6	25	0.6	9.4	1.6	46	0.79	3.3	2.0	<0.1	8	0.1	0.4	0.1	13	0.07	0.116	4
1282615	Soil	3.1	87.2	30.9	124	1.4	44.3	33.6	1581	4.10	20.5	10.7	1.3	26	0.1	1.4	0.4	26	0.04	0.147	7
1282616	Soil	5.5	111.3	29.8	164	1.3	61.8	35.4	1486	4.21	26.7	17.2	1.6	20	0.2	1.6	0.4	32	0.07	0.134	7
1282617	Soil	2.1	72.9	17.8	107	0.9	35.4	14.3	541	2.10	11.4	11.5	0.4	42	0.1	0.7	0.2	18	0.27	0.083	5
1282618	Soil	2.7	61.5	17.0	146	1.3	56.7	15.1	675	3.27	9.6	9.3	2.0	70	0.2	1.0	0.3	24	0.59	0.111	8
1282619	Soil	1.8	33.1	9.0	59	0.6	14.4	4.5	179	1.73	10.7	2.6	0.3	25	0.1	0.6	0.4	28	0.09	0.096	5
1282620	Soil	1.6	41.4	10.2	58	1.4	23.7	4.4	157	1.77	6.3	3.8	0.6	51	<0.1	0.5	0.3	30	0.26	0.123	5
1282621	Soil	1.3	37.1	9.6	66	2.0	22.6	4.3	84	1.71	5.1	2.5	0.8	34	0.1	0.5	0.2	26	0.13	0.090	5
1282622	Soil	0.1	26.3	3.6	4	0.3	1.9	0.3	10	0.18	<0.5	<0.5	<0.1	5	<0.1	<0.1	0.1	6	0.02	0.026	1
1282623	Soil	0.7	108.0	12.1	15	0.4	4.9	0.8	36	0.44	1.8	2.6	0.1	8	<0.1	0.2	0.1	12	0.02	0.039	2
1282624	Soil	0.4	7.3	2.7	5	0.5	2.0	0.4	11	0.26	0.7	0.8	<0.1	5	<0.1	0.1	<0.1	10	0.02	0.021	1
1282625	Soil	2.8	25.7	9.5	46	0.3	15.9	28.7	1592	2.80	6.5	1.0	0.2	6	0.1	0.6	0.1	26	0.03	0.053	3
1282626	Soil	1.7	14.6	6.5	31	0.1	7.6	3.4	215	1.22	6.7	1.3	0.3	7	<0.1	0.5	0.1	26	0.02	0.038	5
1282627	Soil	2.5	36.9	15.7	101	0.5	29.0	22.5	1513	3.05	12.0	4.4	1.8	14	0.2	0.7	0.3	37	0.04	0.085	6
1282628	Soil	1.9	16.5	11.6	63	0.3	18.8	5.5	179	2.52	7.5	<0.5	1.3	8	0.2	0.6	0.2	36	0.03	0.061	4
1282629	Soil	3.0	118.0	26.9	269	1.3	138.4	42.4	2250	4.15	16.7	9.1	1.9	113	1.3	1.0	0.3	26	0.62	0.123	5
1282630	Soil	2.8	70.4	22.6	150	1.1	55.2	27.9	968	3.93	16.7	6.9	2.4	56	0.2	1.1	0.3	29	0.16	0.105	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282591	Soil	25	0.28	156	0.008	1	1.39	0.006	0.08	0.4	0.05	1.8	0.2	<0.05	7	1.2	<0.2
1282592	Soil	13	0.07	134	0.005	2	0.75	0.007	0.05	0.2	0.05	0.5	0.1	<0.05	5	0.8	<0.2
1282593	Soil	16	0.18	116	0.013	2	0.77	0.004	0.04	<0.1	0.03	1.1	0.2	<0.05	3	1.6	<0.2
1282594	Soil	3	0.02	20	0.004	1	0.55	0.023	0.02	<0.1	0.02	0.1	<0.1	<0.05	2	<0.5	<0.2
1282595	Soil	8	0.03	50	0.002	1	0.53	0.003	0.04	<0.1	0.02	0.4	0.1	<0.05	3	<0.5	<0.2
1282596	Soil	11	0.02	61	0.003	1	0.52	0.003	0.06	<0.1	<0.01	0.3	0.1	<0.05	3	<0.5	<0.2
1282597	Soil	11	0.05	60	0.003	<1	0.60	0.009	0.05	<0.1	0.03	0.4	<0.1	<0.05	2	<0.5	<0.2
1282598	Soil	10	0.06	78	0.002	1	0.46	0.008	0.07	<0.1	<0.01	0.9	<0.1	0.11	2	<0.5	<0.2
1282599	Soil	4	0.02	53	0.003	<1	0.47	0.022	0.03	<0.1	0.02	0.1	<0.1	<0.05	2	<0.5	<0.2
1282600	Soil	9	0.12	193	0.003	2	0.67	0.018	0.05	<0.1	0.06	1.1	0.2	0.16	2	<0.5	<0.2
1282611	Soil	18	0.04	164	0.003	1	0.78	0.004	0.06	0.1	0.08	0.2	0.1	0.09	4	0.9	<0.2
1282612	Soil	27	0.07	185	0.004	1	1.31	0.004	0.06	0.1	0.13	0.6	0.1	0.08	5	1.2	<0.2
1282613	Soil	23	0.05	168	0.003	1	0.90	0.004	0.06	<0.1	0.12	0.4	0.2	0.09	5	0.9	<0.2
1282614	Soil	13	0.05	126	0.004	2	0.75	0.015	0.03	<0.1	0.11	0.4	<0.1	0.13	1	0.7	<0.2
1282615	Soil	22	0.30	768	0.005	2	1.35	0.014	0.07	<0.1	0.18	3.1	0.2	0.09	3	1.8	<0.2
1282616	Soil	26	0.34	744	0.005	2	1.81	0.013	0.07	0.1	0.16	3.2	0.2	0.06	4	2.2	<0.2
1282617	Soil	18	0.23	579	0.006	2	1.17	0.025	0.05	<0.1	0.13	1.6	0.1	0.07	3	1.2	<0.2
1282618	Soil	29	0.40	1208	0.002	2	1.20	0.007	0.06	<0.1	0.24	5.0	0.1	0.12	3	1.5	<0.2
1282619	Soil	19	0.14	281	0.005	3	1.02	0.015	0.06	<0.1	0.06	0.9	0.1	0.07	4	0.9	<0.2
1282620	Soil	23	0.25	477	0.004	2	1.23	0.012	0.06	<0.1	0.10	1.7	0.2	0.06	4	1.0	<0.2
1282621	Soil	24	0.23	325	0.003	2	0.96	0.008	0.06	<0.1	0.20	1.7	0.1	<0.05	3	<0.5	<0.2
1282622	Soil	3	<0.01	60	0.003	1	0.14	0.023	0.02	<0.1	0.03	0.2	<0.1	<0.05	<1	<0.5	<0.2
1282623	Soil	8	0.02	234	0.005	1	0.31	0.015	0.02	<0.1	0.02	0.4	<0.1	<0.05	<1	<0.5	<0.2
1282624	Soil	4	0.01	129	0.004	1	0.18	0.020	0.02	<0.1	0.04	0.2	<0.1	<0.05	<1	<0.5	<0.2
1282625	Soil	14	0.06	77	0.007	2	0.55	0.012	0.03	<0.1	0.06	0.5	0.1	<0.05	3	0.8	<0.2
1282626	Soil	10	0.04	128	0.004	1	0.50	0.013	0.04	<0.1	0.03	0.7	<0.1	<0.05	3	<0.5	<0.2
1282627	Soil	32	0.27	328	0.002	2	1.37	0.006	0.07	<0.1	0.09	2.1	0.1	<0.05	4	1.0	<0.2
1282628	Soil	21	0.23	133	0.002	2	1.02	0.007	0.05	<0.1	0.04	1.3	0.1	<0.05	4	<0.5	<0.2
1282629	Soil	31	0.44	2137	0.002	3	1.65	0.009	0.06	<0.1	0.22	4.7	0.2	0.10	3	1.8	<0.2
1282630	Soil	33	0.40	1994	0.003	3	1.40	0.006	0.07	<0.1	0.12	3.9	0.1	<0.05	3	1.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282631	Soil		1.3	321.7	10.8	320	1.6	184.4	13.6	1381	2.05	5.9	5.7	0.8	80	1.3	0.7	0.2	19	0.42	0.130	12
1282632	Soil		1.9	157.9	17.3	276	1.3	89.5	15.3	755	3.20	14.0	7.7	1.8	93	0.5	0.9	0.3	32	0.46	0.111	10
1282633	Soil		2.5	73.6	16.5	261	0.7	99.6	19.0	2921	3.37	11.6	1.4	2.2	129	2.4	1.3	0.3	45	0.86	0.113	7
1282634	Soil		3.2	67.0	21.7	253	0.7	89.7	29.1	4609	4.18	14.6	4.0	3.3	59	1.4	1.3	0.3	50	0.36	0.112	8
1282635	Soil		4.8	41.2	16.9	162	0.2	41.5	10.5	320	3.27	19.4	4.3	3.3	21	0.6	2.3	0.3	56	0.14	0.092	11
1282636	Soil		0.8	21.3	7.6	14	0.2	8.1	1.3	29	0.54	2.5	<0.5	0.1	25	0.1	0.2	0.1	17	0.19	0.040	3
1282637	Soil		4.9	32.6	16.4	136	0.3	34.5	16.5	603	3.20	13.2	3.4	2.9	28	0.4	2.1	0.3	63	0.17	0.109	11
1282638	Soil		5.8	50.3	14.9	189	0.8	44.3	10.1	328	2.72	15.6	2.5	4.0	63	1.3	3.0	0.3	82	0.36	0.118	15
1282639	Soil		3.7	30.0	21.0	94	0.6	25.1	7.2	206	4.03	20.4	1.4	1.7	15	0.2	1.9	0.4	83	0.05	0.049	13
1282640	Soil		1.4	30.8	12.1	35	0.6	9.6	2.6	60	1.41	5.9	4.5	0.5	13	0.2	0.4	0.2	47	0.03	0.054	10
1282651	Soil		1.2	68.1	9.7	57	1.1	21.1	3.5	79	1.39	8.6	6.3	0.9	60	0.2	0.6	0.2	22	0.26	0.080	6
1282652	Soil		1.7	20.4	5.2	45	0.6	11.9	1.9	33	1.01	6.2	0.7	1.1	32	0.1	0.5	<0.1	26	0.11	0.033	4
1282653	Soil		2.5	29.2	15.3	98	1.0	23.8	7.5	233	2.08	16.0	4.2	1.8	69	0.2	0.8	0.2	45	0.28	0.060	4
1282654	Soil		2.9	18.3	11.5	82	0.5	20.6	4.3	121	1.61	12.0	1.0	1.7	50	0.2	0.8	0.2	54	0.27	0.069	5
1282655	Soil		0.3	11.4	2.8	14	0.4	5.9	0.8	20	0.35	1.2	1.4	0.2	13	<0.1	0.2	<0.1	9	0.08	0.040	2
1282656	Soil		2.4	19.5	13.2	111	0.6	36.3	10.1	282	3.67	13.5	2.6	2.8	12	0.1	0.9	0.2	55	0.05	0.040	7
1282657	Soil		5.2	39.8	22.2	117	1.1	29.7	9.8	297	3.91	17.3	4.7	1.6	12	0.2	1.3	0.3	46	0.03	0.076	4
1282658	Soil		3.7	49.8	23.5	96	1.2	19.2	5.2	375	3.37	33.1	2.7	0.6	42	0.3	1.6	0.3	46	0.03	0.118	7
1282659	Soil		2.7	24.0	12.2	45	0.5	9.5	1.7	36	1.49	16.7	0.6	0.1	19	0.2	1.1	0.2	42	0.02	0.086	5
1282660	Soil		3.6	42.3	21.8	72	1.3	15.5	3.2	115	3.64	28.7	2.5	0.4	38	0.1	1.5	0.3	43	0.02	0.129	6
1282661	Soil		2.3	21.6	24.6	40	2.0	8.3	1.7	34	1.99	16.5	1.6	0.9	41	<0.1	0.8	0.3	60	<0.01	0.059	5
1282662	Soil		2.6	38.6	20.8	57	1.0	8.8	1.9	51	1.66	21.8	1.4	0.5	23	0.2	0.9	0.3	56	0.02	0.101	4
1282663	Soil		2.6	33.2	31.0	60	1.0	15.1	4.5	248	2.69	22.8	<0.5	1.2	25	0.5	0.9	0.3	51	0.02	0.096	4
1282664	Soil		3.3	61.0	24.2	92	1.6	17.7	4.1	110	2.81	31.7	2.4	<0.1	30	0.7	1.3	0.3	45	0.03	0.193	4
1282665	Soil		2.2	32.9	18.0	71	1.0	10.8	2.0	42	1.66	22.3	2.1	0.1	20	0.5	1.2	0.2	28	0.02	0.138	2
1282666	Soil		1.5	25.7	5.8	29	0.4	6.6	1.3	30	0.80	9.0	1.1	<0.1	11	0.3	0.7	0.1	16	0.03	0.080	3
1282667	Soil		4.8	28.7	24.2	115	0.2	22.6	7.3	146	2.60	33.7	7.2	0.7	22	0.1	2.9	0.3	34	0.02	0.063	6
1282668	Soil		6.5	27.9	30.3	129	0.3	24.9	8.8	178	2.73	46.2	18.6	0.7	37	0.1	4.9	0.4	44	0.02	0.070	6
1282669	Soil		9.4	29.0	41.2	111	0.8	21.8	7.8	146	2.31	40.4	10.7	0.9	52	0.3	7.2	0.3	43	0.01	0.068	4
1282670	Soil		4.9	29.7	22.7	127	0.2	26.7	9.2	179	2.55	32.6	5.3	0.7	28	0.3	3.1	0.3	29	0.01	0.054	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282631	Soil	22	0.20	1127	0.005	3	1.68	0.018	0.04	<0.1	0.50	6.5	0.1	0.10	3	3.6	<0.2
1282632	Soil	31	0.43	1055	0.002	3	1.72	0.009	0.06	<0.1	0.33	5.9	0.2	<0.05	3	1.3	<0.2
1282633	Soil	31	0.50	673	0.001	3	1.68	0.010	0.08	<0.1	0.28	4.9	0.2	0.09	4	1.9	<0.2
1282634	Soil	39	0.55	659	0.002	2	1.99	0.008	0.11	<0.1	0.35	6.2	0.2	0.06	5	2.0	<0.2
1282635	Soil	26	0.39	515	0.004	2	1.17	0.005	0.06	0.1	0.14	2.7	0.1	<0.05	3	1.2	<0.2
1282636	Soil	6	0.04	116	0.004	<1	0.41	0.020	0.03	<0.1	0.03	0.1	<0.1	<0.05	2	<0.5	<0.2
1282637	Soil	27	0.39	927	0.003	3	1.37	0.005	0.08	0.1	0.17	2.4	0.2	<0.05	4	1.3	<0.2
1282638	Soil	27	0.33	1727	0.003	4	1.20	0.006	0.11	0.2	0.42	3.0	0.3	<0.05	3	2.6	<0.2
1282639	Soil	36	0.34	167	0.016	3	1.91	0.006	0.07	0.2	0.06	2.1	0.2	<0.05	7	1.2	<0.2
1282640	Soil	20	0.10	282	0.004	1	1.16	0.005	0.06	0.1	0.02	0.8	0.1	<0.05	5	0.6	<0.2
1282651	Soil	14	0.14	564	0.003	2	0.93	0.014	0.05	<0.1	0.21	2.8	0.1	0.06	2	1.4	<0.2
1282652	Soil	15	0.13	523	<0.001	2	0.64	0.007	0.05	<0.1	0.15	1.2	<0.1	<0.05	3	0.5	<0.2
1282653	Soil	25	0.27	759	<0.001	3	1.11	0.006	0.10	<0.1	0.48	1.9	0.2	<0.05	3	0.6	<0.2
1282654	Soil	20	0.23	400	0.002	3	0.85	0.008	0.07	<0.1	0.27	1.7	0.2	<0.05	3	0.7	<0.2
1282655	Soil	7	0.03	190	0.003	1	0.20	0.025	0.03	<0.1	0.10	0.6	<0.1	<0.05	<1	<0.5	<0.2
1282656	Soil	35	0.47	209	0.004	2	1.62	0.004	0.07	<0.1	0.09	1.9	0.2	<0.05	5	0.6	<0.2
1282657	Soil	28	0.15	224	0.003	2	1.18	0.005	0.05	<0.1	0.17	2.5	0.2	<0.05	4	1.8	<0.2
1282658	Soil	21	0.12	292	0.004	3	1.02	0.007	0.10	<0.1	0.14	1.2	0.1	0.06	3	2.4	<0.2
1282659	Soil	11	0.03	176	0.003	3	0.62	0.014	0.05	<0.1	0.05	0.3	<0.1	<0.05	3	0.9	<0.2
1282660	Soil	22	0.05	473	0.005	2	0.94	0.008	0.08	<0.1	0.14	0.6	0.1	0.10	3	2.4	<0.2
1282661	Soil	18	0.02	506	0.002	4	0.54	0.005	0.13	<0.1	0.10	0.7	0.1	0.15	4	2.1	<0.2
1282662	Soil	14	0.02	373	0.001	4	0.70	0.007	0.08	<0.1	0.09	1.0	0.1	<0.05	3	1.0	<0.2
1282663	Soil	20	0.03	255	0.002	2	1.08	0.007	0.09	<0.1	0.08	1.6	0.2	0.05	4	1.4	<0.2
1282664	Soil	20	0.02	269	0.002	2	0.87	0.007	0.08	<0.1	0.21	0.3	0.2	0.12	3	1.8	<0.2
1282665	Soil	12	0.02	136	0.003	3	0.37	0.010	0.05	<0.1	0.13	0.5	<0.1	0.06	2	1.9	<0.2
1282666	Soil	6	0.01	88	0.005	2	0.49	0.019	0.04	<0.1	0.17	0.3	<0.1	0.05	2	0.8	<0.2
1282667	Soil	13	0.09	119	0.003	2	0.66	0.005	0.06	<0.1	0.21	2.0	0.3	<0.05	2	1.4	<0.2
1282668	Soil	13	0.06	217	0.004	1	0.56	0.004	0.07	0.1	0.66	2.0	0.5	0.05	2	2.5	<0.2
1282669	Soil	12	0.03	741	0.002	2	0.36	0.002	0.08	<0.1	2.78	2.7	0.5	0.09	2	4.4	<0.2
1282670	Soil	9	0.03	281	0.003	1	0.41	0.004	0.05	<0.1	0.50	2.5	0.3	<0.05	1	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282671	Soil	5.3	28.9	23.9	143	0.2	30.6	9.8	141	2.35	35.6	5.7	1.2	34	1.0	3.4	0.3	26	0.02	0.042	4
1282672	Soil	7.9	25.9	28.0	114	0.5	22.9	6.6	144	2.04	38.2	10.9	0.3	36	0.4	5.2	0.3	47	0.03	0.076	6
1282673	Soil	4.4	74.3	21.3	161	0.4	27.6	5.5	90	1.88	88.0	5.2	0.5	90	0.5	4.3	0.3	58	0.03	0.081	4
1282674	Soil	4.3	39.3	22.7	129	0.4	9.1	2.0	29	1.70	97.6	6.2	1.0	183	0.2	4.5	0.3	72	0.02	0.079	4
1282675	Soil	19.0	19.6	60.5	33	1.4	9.5	1.8	33	1.30	29.5	15.5	0.8	78	0.2	10.2	0.3	73	0.04	0.093	5
1282676	Soil	23.1	29.6	82.0	79	1.8	19.7	4.1	127	2.34	79.9	27.7	0.4	139	0.2	15.8	0.4	107	0.04	0.169	7
1282677	Soil	32.1	34.1	82.6	66	1.8	16.0	3.6	95	2.53	73.4	37.0	0.9	217	0.3	17.7	0.4	131	0.07	0.192	7
1282678	Soil	32.8	34.5	75.9	67	1.7	15.8	3.5	85	2.57	90.5	43.4	1.1	234	0.2	17.5	0.3	141	0.08	0.201	7
1282679	Soil	4.4	19.0	13.2	48	0.2	11.0	2.7	140	1.30	21.4	3.2	0.1	25	0.1	2.3	0.2	38	0.03	0.077	5
1282680	Soil	15.5	18.4	40.3	37	1.0	8.1	2.3	91	1.40	32.0	8.5	0.4	58	<0.1	5.2	0.2	56	0.07	0.098	4
1282681	Soil	12.8	24.0	49.5	76	1.4	15.3	3.4	70	2.42	68.7	12.5	0.4	117	0.2	8.4	0.3	84	0.03	0.148	6
1282682	Soil	8.1	41.0	31.1	145	0.7	25.5	5.8	183	2.06	33.7	3.8	0.8	69	0.3	4.7	0.4	61	0.05	0.088	5
1282683	Soil	6.1	40.1	22.1	185	0.2	33.0	5.8	105	2.10	25.1	2.2	0.4	59	0.3	2.6	0.4	68	0.06	0.126	4
1282684	Soil	6.9	101.2	29.0	722	1.0	117.4	27.7	774	6.98	104.7	5.0	1.9	317	0.9	5.6	0.5	90	0.08	0.215	5
1282685	Soil	6.2	80.8	27.0	381	2.2	93.0	33.7	1816	5.76	124.6	4.7	2.0	131	0.7	6.0	0.6	58	0.37	0.142	7
1282686	Soil	7.4	62.0	28.2	246	1.0	61.0	21.2	798	3.98	62.3	3.6	0.5	52	0.8	4.2	0.5	52	0.06	0.177	4
1282687	Soil	14.4	17.3	47.0	52	0.8	8.9	1.5	58	1.09	25.9	4.5	1.7	87	<0.1	6.0	0.4	35	0.02	0.048	3
1282688	Soil	14.3	18.0	58.6	64	1.0	7.8	1.9	62	1.30	35.7	3.8	2.4	135	0.1	6.3	0.4	29	0.02	0.047	3
1282689	Soil	9.4	20.9	63.3	85	0.7	14.3	3.2	74	3.35	42.3	3.8	6.3	49	0.1	9.3	0.6	72	<0.01	0.069	4
1282690	Soil	134.4	23.9	69.0	44	4.7	8.4	0.6	26	3.13	117.6	25.0	11.7	151	0.4	47.2	0.4	265	0.03	0.214	12
1282691	Soil	123.0	41.9	41.6	137	3.8	23.1	2.1	65	1.82	69.6	7.3	2.3	55	0.6	42.1	0.3	247	0.03	0.112	11
1282692	Soil	161.3	257.1	30.8	1151	6.7	234.0	6.4	235	3.31	147.3	6.3	2.3	331	21.9	82.9	0.3	1051	0.74	0.330	22
1282693	Soil	166.6	331.9	42.5	7922	8.1	661.6	24.5	487	2.52	205.5	4.0	4.0	179	58.8	109.7	0.3	2192	2.84	0.210	26
1282694	Soil	114.8	151.8	20.8	900	1.7	319.7	10.9	247	2.49	159.6	4.1	1.2	82	12.6	35.2	0.2	634	1.68	0.134	21
1282695	Soil	8.9	41.7	36.8	229	1.7	46.4	8.1	105	3.55	208.9	30.0	1.2	130	0.4	16.4	0.4	49	0.03	0.199	11
1282696	Soil	207.0	47.4	23.5	299	3.4	62.8	3.8	138	2.62	171.4	4.8	0.2	84	2.3	34.2	0.4	226	0.27	0.223	12
1282697	Soil	168.2	224.2	21.8	2788	3.5	417.0	11.3	278	2.15	234.8	4.2	1.1	195	26.3	59.4	0.3	850	4.55	0.194	21
1282698	Soil	97.0	35.7	33.4	368	3.7	50.3	2.8	41	2.50	88.4	4.8	0.1	78	1.2	46.9	0.3	948	0.06	0.102	21
1282699	Soil	22.3	12.8	9.3	57	2.2	16.0	1.9	34	1.05	61.3	10.0	0.1	13	0.2	7.9	0.1	88	0.02	0.046	7
1282700	Soil	20.0	19.6	15.3	98	0.8	27.6	3.6	49	1.37	126.0	0.8	0.2	14	0.3	6.2	0.2	76	0.04	0.069	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282671	Soil	7	0.03	278	<0.001	<1	0.28	0.002	0.06	<0.1	0.90	2.9	0.3	<0.05	<1	2.0	<0.2
1282672	Soil	11	0.06	470	0.005	3	0.50	0.007	0.07	0.1	0.71	1.1	0.4	0.08	2	2.7	<0.2
1282673	Soil	13	0.03	1444	0.002	4	0.48	0.009	0.06	<0.1	0.29	3.9	0.5	0.09	2	2.8	<0.2
1282674	Soil	13	<0.01	931	<0.001	3	0.35	0.003	0.09	<0.1	0.32	3.3	0.8	0.17	1	3.6	<0.2
1282675	Soil	14	0.05	1380	0.004	2	0.48	0.005	0.10	0.2	1.99	1.3	1.0	0.17	2	7.3	<0.2
1282676	Soil	21	0.06	1273	0.006	3	0.61	0.008	0.16	0.2	5.98	1.3	0.8	0.29	3	9.5	0.4
1282677	Soil	28	0.11	1211	0.008	4	0.72	0.010	0.20	0.2	5.23	2.9	1.6	0.41	4	13.2	0.4
1282678	Soil	30	0.10	964	0.007	4	0.70	0.012	0.21	0.3	2.73	3.1	1.6	0.39	4	11.1	0.3
1282679	Soil	10	0.05	253	0.008	2	0.60	0.016	0.05	<0.1	0.21	0.4	0.2	0.05	3	1.4	<0.2
1282680	Soil	10	0.04	773	0.009	2	0.41	0.018	0.09	<0.1	0.80	1.3	0.3	0.17	2	5.3	<0.2
1282681	Soil	16	0.05	878	0.005	3	0.48	0.005	0.14	0.1	0.47	2.0	0.5	0.28	3	6.9	0.3
1282682	Soil	12	0.10	205	0.007	2	0.59	0.015	0.09	<0.1	0.11	2.8	0.5	0.07	2	2.4	<0.2
1282683	Soil	16	0.02	268	0.004	3	0.49	0.004	0.07	0.1	0.13	1.7	0.1	0.10	2	1.4	<0.2
1282684	Soil	28	0.08	901	0.003	2	1.27	0.003	0.08	<0.1	0.16	10.3	0.4	0.08	2	2.4	0.2
1282685	Soil	23	0.16	1170	0.009	2	1.02	0.004	0.08	0.1	0.23	9.7	0.4	0.05	3	2.2	<0.2
1282686	Soil	17	0.05	475	0.004	3	0.63	0.005	0.09	<0.1	0.28	2.8	0.4	0.14	2	1.7	<0.2
1282687	Soil	8	0.05	268	0.002	3	0.32	0.004	0.12	<0.1	0.23	2.1	0.5	0.13	1	3.3	<0.2
1282688	Soil	7	0.02	435	0.004	3	0.29	0.006	0.12	<0.1	0.22	2.6	0.6	0.17	1	3.8	<0.2
1282689	Soil	8	0.01	313	0.003	4	0.18	0.003	0.27	0.2	1.07	2.0	0.6	0.54	2	7.6	0.2
1282690	Soil	31	0.03	312	0.005	4	0.38	0.004	0.31	0.8	18.32	6.5	4.1	0.73	4	24.4	0.8
1282691	Soil	28	0.05	405	0.006	5	0.42	0.005	0.14	0.7	2.03	4.2	3.6	0.23	4	15.3	0.7
1282692	Soil	80	0.12	1027	0.008	11	1.05	0.007	0.22	1.0	0.52	4.7	8.6	0.20	4	40.5	0.3
1282693	Soil	103	1.20	739	0.047	20	1.10	0.007	0.25	0.8	1.24	6.9	13.2	0.07	5	18.0	0.3
1282694	Soil	40	0.71	1810	0.006	8	0.66	0.005	0.12	0.7	1.59	5.3	4.8	0.05	2	5.0	<0.2
1282695	Soil	11	0.03	512	0.002	4	0.36	0.002	0.12	<0.1	8.61	2.1	0.9	0.12	1	8.0	<0.2
1282696	Soil	16	0.06	712	0.004	5	0.43	0.004	0.19	1.1	2.16	0.5	7.1	0.37	1	14.0	0.4
1282697	Soil	49	1.06	526	0.005	12	0.59	0.005	0.20	0.9	2.62	3.2	9.2	0.10	3	8.4	0.4
1282698	Soil	43	0.04	468	0.009	3	0.42	0.007	0.13	0.7	0.52	0.3	5.3	0.14	6	11.8	0.3
1282699	Soil	7	0.02	130	0.004	2	0.26	0.012	0.06	0.2	1.15	0.2	1.4	0.06	2	2.6	<0.2
1282700	Soil	8	0.03	161	0.002	3	0.39	0.009	0.06	0.1	0.27	0.3	0.6	<0.05	2	2.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282701	Soil	13.8	6.1	95.8	11	0.7	1.6	0.3	7	2.24	31.0	3.6	2.9	60	<0.1	4.5	0.9	32	0.01	0.061	4
1282702	Soil	13.9	16.9	23.4	104	0.3	14.5	3.4	44	1.65	38.8	10.4	0.5	17	<0.1	9.3	0.2	47	<0.01	0.022	9
1282703	Soil	6.7	24.7	21.3	66	1.4	10.9	3.5	43	1.41	56.3	27.2	0.8	90	0.2	6.3	0.4	33	0.02	0.074	2
1282704	Soil	11.6	62.3	33.4	101	0.9	11.6	3.3	127	3.61	71.6	6.2	1.8	145	0.2	6.4	0.4	55	0.03	0.140	4
1282705	Soil	0.4	2.4	1.2	8	0.2	1.6	0.6	20	0.21	1.7	1.6	<0.1	6	<0.1	0.2	<0.1	6	0.02	0.025	<1
1282706	Soil	7.5	58.8	20.2	304	1.2	48.1	15.4	399	3.72	235.3	2.5	0.2	17	0.5	12.1	0.3	45	0.02	0.101	4
1282707	Soil	8.6	53.8	17.7	174	0.5	42.4	13.4	418	4.66	31.1	2.9	0.3	18	0.4	3.3	0.4	65	0.03	0.142	5
1282708	Soil	8.3	47.3	13.0	161	0.9	35.1	12.5	302	3.24	29.4	2.3	0.1	16	0.3	3.0	0.4	69	0.04	0.106	5
1282709	Soil	7.2	51.6	18.9	247	1.1	57.0	18.1	1415	4.78	173.9	5.2	0.2	17	1.3	3.9	0.3	53	0.16	0.177	2
1282710	Soil	8.3	36.2	49.9	99	1.8	12.9	3.3	103	1.89	132.0	29.7	1.3	172	0.7	9.7	0.3	50	0.03	0.072	3
1282711	Soil	21.8	48.8	57.0	117	2.7	27.1	6.8	252	2.23	64.9	285.9	1.3	117	0.5	14.3	0.4	91	0.06	0.124	8
1282712	Soil	6.6	15.6	27.7	34	0.7	7.9	1.8	118	1.03	26.1	20.7	<0.1	53	<0.1	4.5	0.2	57	0.05	0.073	3
1282713	Soil	23.3	31.0	60.0	85	2.2	18.4	4.1	94	2.22	72.1	48.2	0.4	154	0.3	14.8	0.4	108	0.05	0.134	6
1282714	Soil	3.6	4.0	8.1	9	1.0	5.9	0.5	17	0.27	5.1	8.6	<0.1	18	<0.1	2.0	<0.1	21	0.02	0.033	2
1282715	Soil	40.9	44.6	34.7	37	3.6	9.2	1.0	22	1.92	92.3	18.9	0.9	234	0.6	30.5	0.3	249	0.06	0.232	9
1282716	Soil	7.9	29.4	57.6	53	1.8	13.5	2.6	48	1.32	11.0	3.2	0.1	74	0.4	2.0	0.3	76	0.05	0.109	10
1282717	Soil	5.3	16.5	37.8	44	1.2	10.8	2.8	58	1.54	20.8	1.5	0.3	49	0.1	2.3	0.2	71	0.02	0.071	4
1282718	Soil	4.1	14.0	17.4	29	0.9	7.6	1.6	27	0.76	5.4	2.3	0.2	23	0.1	1.1	0.2	47	0.01	0.027	15
1282719	Soil	5.7	141.5	40.7	68	0.8	80.5	43.4	685	6.30	108.8	6.7	1.7	17	0.2	5.2	0.6	83	0.06	0.111	3
1282720	Soil	5.4	21.6	21.6	33	0.4	16.0	3.9	104	1.24	10.5	2.1	<0.1	12	0.3	1.3	0.2	43	0.03	0.049	3
1282721	Soil	140.5	84.3	21.9	899	1.8	212.6	6.3	113	1.97	39.6	3.1	0.9	107	8.6	21.4	0.2	810	0.61	0.162	18
1282722	Soil	27.1	41.4	22.3	387	1.1	79.4	4.7	126	1.93	17.6	5.5	0.8	47	3.4	5.7	0.2	198	0.50	0.055	5
1282723	Soil	66.4	87.4	17.1	1039	1.5	183.3	6.8	154	1.78	34.6	4.0	1.3	187	9.9	15.8	0.2	384	3.98	0.138	11
1282724	Soil	63.3	73.4	21.0	815	1.3	151.7	7.8	183	2.22	30.5	5.2	1.7	110	11.3	12.9	0.2	286	1.01	0.149	12
1282725	Soil	29.1	61.6	41.3	251	2.3	55.2	30.5	1272	2.06	30.8	4.1	0.7	43	4.3	4.2	0.3	144	0.10	0.097	5
1282726	Soil	25.5	58.6	36.2	196	1.9	44.8	10.3	358	2.65	36.9	4.9	0.5	58	1.8	4.7	0.3	122	0.52	0.071	3
1282727	Soil	42.1	64.5	35.0	504	0.7	99.1	38.4	1267	2.41	32.1	7.6	1.9	246	5.1	9.5	0.2	282	0.78	0.304	12
1282728	Soil	9.7	21.6	14.1	52	0.5	17.6	1.5	33	0.66	6.3	<0.5	0.2	30	1.4	1.4	0.1	68	0.25	0.039	7
1282729	Soil	10.5	18.9	13.2	130	1.5	27.6	2.1	55	0.78	7.3	0.7	0.2	24	0.9	1.3	0.1	61	0.12	0.058	2
1282730	Soil	24.4	10.9	14.5	48	0.1	19.8	1.9	33	0.87	10.1	2.5	0.5	16	0.1	1.1	0.1	78	0.03	0.033	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282701	Soil	6	0.01	215	0.002	3	0.22	0.004	0.31	0.2	0.47	0.4	1.0	0.69	2	2.4	<0.2
1282702	Soil	5	0.01	61	0.002	4	0.20	0.002	0.06	<0.1	2.78	0.3	0.4	0.05	2	1.9	0.3
1282703	Soil	6	<0.01	126	0.001	3	0.31	0.004	0.09	<0.1	>50	0.7	0.7	0.14	2	11.2	<0.2
1282704	Soil	15	0.05	366	0.003	3	0.49	0.007	0.19	<0.1	5.47	2.7	0.7	0.47	3	5.1	<0.2
1282705	Soil	2	<0.01	19	0.003	1	0.11	0.021	0.02	<0.1	0.39	<0.1	<0.1	<0.05	<1	<0.5	<0.2
1282706	Soil	10	0.03	231	0.004	2	0.44	0.007	0.07	<0.1	0.44	1.5	0.3	0.05	2	1.5	<0.2
1282707	Soil	18	0.05	151	0.003	1	0.61	0.003	0.08	<0.1	0.40	1.9	0.3	0.07	4	1.9	<0.2
1282708	Soil	16	0.04	123	0.004	1	0.44	0.003	0.08	<0.1	0.38	1.0	0.2	0.09	3	1.3	<0.2
1282709	Soil	17	0.05	153	0.002	3	0.37	0.005	0.07	<0.1	0.34	2.6	0.3	0.10	2	2.3	<0.2
1282710	Soil	15	<0.01	432	<0.001	2	0.32	0.002	0.09	<0.1	0.83	4.2	0.5	0.14	1	4.0	<0.2
1282711	Soil	17	0.07	970	0.004	3	0.65	0.003	0.10	0.2	5.33	3.0	0.7	0.16	3	12.4	<0.2
1282712	Soil	11	0.05	441	0.008	2	0.61	0.017	0.07	<0.1	0.25	0.4	0.3	0.13	3	2.8	<0.2
1282713	Soil	21	0.03	1259	0.004	3	0.49	0.004	0.15	0.2	1.40	1.3	1.0	0.26	3	10.4	<0.2
1282714	Soil	11	0.01	206	0.004	1	0.13	0.014	0.03	<0.1	0.49	0.2	0.2	<0.05	1	1.2	<0.2
1282715	Soil	38	0.01	1143	0.003	6	0.47	0.003	0.17	0.4	6.61	2.7	1.9	0.35	4	11.1	0.2
1282716	Soil	17	0.02	1059	0.007	<1	0.69	0.007	0.03	0.1	0.14	0.4	0.2	<0.05	4	1.9	<0.2
1282717	Soil	9	0.02	362	0.003	<1	0.37	0.002	0.04	<0.1	0.18	1.0	0.2	<0.05	3	1.5	<0.2
1282718	Soil	11	0.01	155	0.007	<1	0.39	0.002	0.02	0.2	0.09	0.2	0.1	<0.05	3	<0.5	<0.2
1282719	Soil	28	0.10	200	<0.001	1	1.19	0.002	0.06	<0.1	0.20	6.5	0.5	<0.05	3	3.8	<0.2
1282720	Soil	16	0.02	161	0.004	2	0.33	0.012	0.03	<0.1	0.09	0.5	0.2	<0.05	2	0.7	<0.2
1282721	Soil	40	0.12	754	0.003	5	0.69	0.004	0.12	0.3	0.39	2.9	2.8	0.06	2	6.8	<0.2
1282722	Soil	23	0.07	466	0.001	3	0.47	0.007	0.07	0.1	0.27	2.5	0.8	0.06	2	2.6	<0.2
1282723	Soil	31	1.33	546	0.002	7	0.40	0.006	0.09	0.2	0.42	3.4	1.8	0.08	2	4.9	<0.2
1282724	Soil	26	0.12	495	0.002	6	0.44	0.003	0.11	0.2	0.44	3.5	1.3	0.06	1	5.5	<0.2
1282725	Soil	30	0.03	513	0.002	2	0.65	0.004	0.08	0.1	0.52	2.7	0.9	0.12	3	4.5	<0.2
1282726	Soil	27	0.08	351	0.002	4	0.50	0.007	0.07	<0.1	0.30	1.7	0.8	0.10	3	4.1	<0.2
1282727	Soil	39	0.07	482	0.005	7	0.81	0.005	0.14	0.1	0.26	2.5	1.1	<0.05	3	3.2	<0.2
1282728	Soil	16	0.06	360	0.002	<1	0.44	0.008	0.05	<0.1	0.06	0.4	0.3	<0.05	2	0.6	<0.2
1282729	Soil	12	0.06	303	0.002	3	0.56	0.022	0.07	<0.1	0.24	1.0	0.3	<0.05	2	0.6	<0.2
1282730	Soil	11	0.04	131	0.003	3	0.54	0.003	0.05	0.1	0.06	0.5	0.5	<0.05	2	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282731	Soil	33.5	20.7	24.5	164	0.3	41.6	3.9	61	1.73	21.0	2.5	0.9	33	0.3	5.4	0.2	130	0.02	0.074	8
1282732	Soil	37.6	16.4	17.5	145	0.2	49.2	4.7	44	1.55	20.6	1.2	1.1	18	0.2	3.3	0.2	107	0.02	0.051	8
1282733	Soil	25.5	19.6	13.9	87	0.6	30.9	2.4	31	0.82	8.8	0.9	0.3	24	1.0	2.4	<0.1	76	0.26	0.067	5
1282734	Soil	28.9	12.2	12.3	90	0.5	27.9	2.4	27	1.02	12.2	1.7	0.4	11	0.2	2.4	0.1	107	0.01	0.035	8
1282735	Soil	14.9	17.5	18.3	168	0.1	27.2	4.0	69	1.34	10.8	1.8	0.5	29	0.8	2.0	0.1	58	0.06	0.080	5
1282736	Soil	21.4	25.2	16.2	206	0.8	30.2	9.9	400	1.18	11.5	2.8	0.5	32	1.9	1.5	0.2	82	0.35	0.076	6
1282737	Soil	28.0	24.4	11.6	177	0.3	42.9	6.1	149	1.73	17.0	0.7	1.8	34	1.5	2.8	0.2	71	0.31	0.090	8
1282738	Soil	23.6	29.4	13.3	151	0.9	44.4	9.5	402	1.83	16.3	3.1	0.9	34	1.7	3.0	0.2	77	0.24	0.093	6
1282739	Soil	38.6	20.8	13.0	180	0.1	60.5	6.0	102	1.60	18.0	1.2	1.3	16	0.7	3.3	0.1	100	0.07	0.066	8
1282740	Soil	53.3	53.0	15.7	338	0.4	111.1	8.8	163	2.18	29.3	1.7	3.9	52	2.6	5.5	0.2	110	0.73	0.130	11
1282741	Soil	26.2	47.1	13.7	512	1.2	83.8	5.9	252	1.36	23.7	2.5	1.2	77	6.1	7.0	0.2	310	1.15	0.129	10
1282742	Soil	9.8	24.0	13.4	157	0.3	36.4	6.3	248	1.65	16.6	1.4	1.8	51	2.6	2.1	0.2	96	0.82	0.084	7
1282743	Soil	6.2	44.7	21.5	215	0.6	47.1	7.4	194	1.64	15.6	4.9	2.6	57	2.5	2.0	0.2	75	0.64	0.092	9
1282744	Soil	7.9	48.3	19.3	302	0.7	60.0	7.7	194	1.75	16.1	2.8	2.4	61	2.9	2.6	0.2	80	0.80	0.094	9
1282745	Soil	7.3	41.4	13.2	132	1.1	47.7	6.1	204	1.26	8.5	5.2	1.1	36	2.0	1.3	0.2	54	0.44	0.062	7
1282746	Soil	15.5	39.4	20.0	291	1.0	65.7	6.8	158	2.04	15.1	3.1	1.6	33	1.1	2.2	0.3	82	0.16	0.108	11
1282747	Soil	6.8	24.1	18.7	91	0.4	28.3	2.9	44	0.94	6.8	1.5	0.9	28	1.2	1.3	0.1	68	0.31	0.037	5
1282748	Soil	10.3	20.6	18.8	125	0.3	28.9	4.6	111	2.00	15.9	1.4	1.9	27	0.5	2.0	0.2	71	0.07	0.101	12
1282749	Soil	4.6	6.6	6.7	32	0.2	9.3	1.5	24	0.47	3.3	<0.5	0.5	9	0.1	0.6	<0.1	34	0.01	0.026	13
1282750	Soil	21.3	33.2	19.5	173	0.3	50.1	8.2	145	2.56	20.1	2.7	1.8	21	0.7	3.0	0.3	72	0.09	0.107	8
1282751	Soil	9.8	33.1	14.3	169	0.5	35.5	6.1	141	1.76	12.6	3.5	2.4	53	1.2	2.3	0.2	57	0.61	0.127	12
1282752	Soil	12.2	46.5	17.3	213	1.4	51.6	7.6	224	2.22	15.7	3.4	0.9	46	2.0	2.6	0.2	92	0.55	0.118	9
1282753	Soil	8.8	23.7	15.0	180	<0.1	37.8	6.5	125	2.25	20.2	1.2	1.6	20	0.9	2.4	0.2	79	0.10	0.068	11
1282754	Soil	4.9	26.0	12.8	125	0.4	42.9	5.0	425	0.78	6.8	1.8	0.5	96	3.2	1.6	0.1	49	2.17	0.085	5
1282755	Soil	4.7	15.1	14.6	114	0.6	20.2	5.0	148	1.61	10.6	2.4	2.3	47	0.9	1.4	0.2	68	0.88	0.077	9
1282756	Soil	5.5	27.0	16.8	97	0.4	26.9	5.8	132	1.51	11.7	2.0	1.5	30	0.9	1.4	0.2	52	0.42	0.078	9
1282757	Soil	13.0	19.8	15.0	125	<0.1	29.8	4.6	74	1.52	22.6	1.4	1.5	18	0.3	2.9	0.3	85	0.11	0.034	14
1282758	Soil	5.5	40.8	14.2	661	0.7	107.5	31.1	3110	3.32	66.7	4.8	2.3	56	5.4	2.4	0.2	73	1.40	0.116	10
1282759	Soil	9.8	32.3	12.5	101	0.3	35.7	4.3	121	1.15	10.7	1.7	0.7	71	2.5	2.3	0.2	52	1.46	0.038	5
1282760	Soil	16.3	26.1	10.0	256	0.3	45.0	5.0	92	1.45	22.4	0.8	1.1	19	3.1	4.1	0.2	178	0.19	0.040	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282731	Soil	11	0.03	193	0.002	1	0.46	0.003	0.05	<0.1	0.05	1.2	0.3	<0.05	2	1.4	<0.2
1282732	Soil	9	0.03	530	0.002	2	0.39	0.003	0.06	<0.1	0.04	0.8	0.4	<0.05	2	1.5	<0.2
1282733	Soil	17	0.06	279	0.002	2	0.46	0.012	0.06	<0.1	0.09	0.7	0.5	<0.05	2	0.5	<0.2
1282734	Soil	12	0.02	109	0.003	2	0.38	0.004	0.04	<0.1	0.04	0.5	0.3	<0.05	3	0.7	<0.2
1282735	Soil	15	0.05	576	0.002	3	0.49	0.004	0.06	<0.1	0.08	0.9	0.3	<0.05	2	1.1	<0.2
1282736	Soil	17	0.10	616	0.003	2	0.62	0.007	0.06	0.1	0.15	1.4	0.4	<0.05	2	0.9	<0.2
1282737	Soil	13	0.11	729	0.003	3	0.47	0.003	0.06	0.1	0.09	1.7	0.3	<0.05	2	1.2	<0.2
1282738	Soil	18	0.09	946	0.002	3	0.63	0.009	0.05	<0.1	0.28	2.1	0.4	<0.05	2	1.7	<0.2
1282739	Soil	14	0.05	1139	0.002	3	0.59	0.003	0.05	0.1	0.05	1.4	0.4	<0.05	2	0.8	<0.2
1282740	Soil	14	0.25	883	0.003	5	0.37	0.003	0.07	0.1	0.46	4.3	0.7	<0.05	1	2.0	<0.2
1282741	Soil	29	0.12	804	0.004	5	0.67	0.009	0.07	0.2	0.54	2.9	1.4	<0.05	2	2.5	<0.2
1282742	Soil	17	0.09	466	0.003	4	0.52	0.007	0.06	<0.1	0.15	1.8	0.3	<0.05	2	1.5	<0.2
1282743	Soil	18	0.13	928	0.002	3	0.76	0.004	0.07	0.1	0.24	3.5	0.3	<0.05	2	2.2	<0.2
1282744	Soil	19	0.20	896	0.002	4	0.76	0.006	0.07	0.1	0.30	3.5	0.4	<0.05	2	1.7	<0.2
1282745	Soil	15	0.12	1109	0.003	3	0.76	0.019	0.09	0.1	0.21	2.5	0.3	<0.05	2	1.2	<0.2
1282746	Soil	26	0.14	694	0.003	4	0.94	0.008	0.11	0.2	0.30	2.4	0.7	<0.05	3	1.3	<0.2
1282747	Soil	19	0.10	622	0.002	4	0.62	0.015	0.08	<0.1	0.11	1.5	0.2	<0.05	2	<0.5	<0.2
1282748	Soil	18	0.17	344	0.004	3	0.77	0.003	0.07	0.1	0.04	1.5	0.3	<0.05	3	0.9	<0.2
1282749	Soil	8	0.02	143	0.004	3	0.27	0.004	0.03	<0.1	0.01	0.4	0.1	<0.05	3	<0.5	<0.2
1282750	Soil	20	0.07	480	0.002	4	0.69	0.004	0.08	<0.1	0.08	1.8	0.4	<0.05	2	1.4	<0.2
1282751	Soil	15	0.16	919	0.004	4	0.73	0.006	0.09	<0.1	0.14	2.4	0.2	<0.05	2	1.5	<0.2
1282752	Soil	23	0.17	1508	0.003	3	1.22	0.012	0.12	0.1	0.31	2.2	0.4	<0.05	3	1.7	<0.2
1282753	Soil	20	0.16	366	0.003	3	0.95	0.008	0.07	0.1	0.03	1.7	0.3	<0.05	3	0.8	<0.2
1282754	Soil	18	0.21	948	0.007	4	0.51	0.016	0.04	0.1	0.17	1.2	0.4	0.08	1	2.2	<0.2
1282755	Soil	21	0.25	476	0.005	4	0.78	0.008	0.08	0.1	0.18	2.2	0.2	<0.05	3	1.3	<0.2
1282756	Soil	18	0.16	532	0.003	3	0.61	0.005	0.08	0.1	0.09	1.7	0.2	<0.05	2	0.9	<0.2
1282757	Soil	10	0.06	186	0.008	2	0.29	0.003	0.06	0.1	0.02	1.0	0.3	<0.05	2	1.0	<0.2
1282758	Soil	17	0.28	544	0.005	6	0.79	0.006	0.11	0.1	0.39	3.1	0.7	0.07	2	1.6	<0.2
1282759	Soil	14	0.14	511	0.004	3	0.51	0.008	0.04	0.1	0.08	1.6	0.2	<0.05	2	1.8	<0.2
1282760	Soil	21	0.09	286	0.003	3	0.65	0.010	0.06	0.1	0.12	1.3	0.4	<0.05	3	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282761	Soil	12.6	21.8	12.6	190	0.3	32.4	7.2	138	1.79	16.7	1.6	2.3	55	0.9	2.5	0.2	58	0.83	0.077	10
1282762	Soil	16.5	27.8	12.5	189	0.1	41.9	5.4	133	1.43	17.7	1.4	0.5	24	2.1	3.2	0.2	125	0.25	0.060	13
1282763	Soil	5.5	27.7	8.1	144	0.6	35.6	3.5	106	1.08	8.0	2.9	0.5	30	1.4	1.2	0.1	31	0.32	0.033	1
1282764	Soil	14.5	36.1	15.2	225	0.3	51.2	6.8	139	3.07	25.4	5.4	1.8	22	2.2	4.1	0.2	70	0.06	0.046	6
1282765	Soil	16.5	27.4	17.8	316	2.9	47.2	5.8	98	2.69	30.5	5.0	1.3	26	4.7	3.3	0.2	154	0.07	0.062	6
1282766	Soil	26.5	19.2	13.1	217	0.4	49.9	3.9	78	1.54	22.7	1.5	0.8	14	1.5	3.9	0.2	134	0.04	0.051	9
1282767	Soil	9.6	17.8	11.3	427	0.3	32.7	7.1	216	1.94	19.7	<0.5	1.5	19	8.0	2.1	0.2	130	0.12	0.035	7
1282768	Soil	72.2	25.1	21.9	239	1.6	48.5	3.2	54	2.19	38.8	0.5	1.1	84	2.4	13.7	0.3	209	0.03	0.082	14
1282769	Soil	1.7	7.3	4.2	30	0.5	7.1	1.9	26	0.59	6.9	<0.5	<0.1	3	<0.1	0.8	<0.1	18	0.01	0.014	3
1282770	Soil	4.0	20.7	10.0	84	0.2	22.2	5.3	75	1.66	15.0	<0.5	<0.1	6	<0.1	1.6	0.2	32	<0.01	0.039	5
1282771	Soil	2.4	17.4	16.1	95	<0.1	24.4	7.5	132	2.67	23.3	<0.5	0.9	14	0.2	1.2	0.3	26	0.02	0.036	2
1282772	Soil	0.9	5.4	5.1	17	0.2	3.6	1.4	24	0.57	2.9	<0.5	0.2	6	<0.1	0.4	0.1	12	0.01	0.023	2
1282773	Soil	4.0	25.7	19.2	64	<0.1	15.2	4.3	73	3.11	14.6	1.7	1.3	13	0.1	1.4	0.3	46	0.02	0.067	5
1282774	Soil	3.1	15.0	13.4	57	0.3	13.9	3.7	129	3.60	12.9	2.4	0.3	8	0.4	1.1	0.3	36	0.03	0.123	4
1282775	Soil	8.6	25.5	17.7	114	0.2	33.8	9.5	238	2.24	13.3	2.7	0.6	32	0.3	1.8	0.2	41	0.24	0.102	5
1282776	Soil	2.6	27.3	19.5	133	0.1	44.1	19.8	522	3.17	20.0	2.0	1.2	11	0.2	1.7	0.2	22	0.06	0.071	3
1282777	Soil	1.2	8.7	7.1	34	0.1	10.8	4.1	69	0.98	6.5	0.9	0.2	4	<0.1	0.5	0.1	16	0.01	0.042	4
1282778	Soil	4.5	28.2	23.5	130	0.2	42.7	27.3	761	3.42	14.9	1.3	1.6	14	0.2	1.5	0.2	34	0.04	0.081	4
1282779	Soil	4.3	24.0	23.6	119	<0.1	38.2	13.8	415	3.41	13.7	1.1	1.3	12	0.2	1.6	0.2	37	0.06	0.083	6
1282780	Soil	2.8	15.8	12.8	72	0.1	23.2	6.4	141	2.31	9.7	3.7	0.4	9	0.1	1.1	0.2	31	0.05	0.072	5
1282781	Soil	3.0	14.6	11.5	64	0.2	17.6	5.0	151	2.42	9.0	1.3	0.5	7	0.1	1.1	0.2	37	0.03	0.061	6
1282782	Soil	3.8	11.5	13.9	52	<0.1	16.2	4.3	155	2.02	11.7	1.7	0.4	8	<0.1	1.2	0.3	53	0.03	0.044	9
1282783	Soil	3.9	14.2	16.1	55	0.1	14.6	3.8	98	3.50	14.6	1.2	0.2	8	<0.1	1.4	0.3	55	0.02	0.072	5
1282784	Soil	2.6	14.1	14.4	53	0.2	15.0	4.7	154	3.85	11.4	1.0	0.2	7	<0.1	1.0	0.2	39	0.03	0.090	5
1282785	Soil	3.1	16.6	17.3	68	<0.1	14.8	6.1	246	3.90	15.8	0.7	0.4	8	<0.1	1.2	0.3	55	0.03	0.078	6
1282786	Soil	3.1	18.3	13.5	76	<0.1	19.8	7.3	190	2.89	13.3	3.2	0.4	8	<0.1	1.1	0.3	47	0.03	0.070	6
1282787	Soil	1.3	12.0	9.9	45	0.2	11.6	5.6	248	2.07	7.5	1.1	0.2	6	0.1	0.6	0.1	18	0.03	0.061	3
1282788	Soil	2.4	20.8	17.4	84	0.2	20.0	9.0	449	4.78	15.1	0.7	0.5	11	<0.1	1.2	0.3	40	0.02	0.131	4
1282789	Soil	0.5	4.8	3.9	14	<0.1	3.8	1.4	37	0.56	1.9	<0.5	<0.1	5	<0.1	0.2	<0.1	8	0.02	0.044	2
1282790	Soil	1.8	11.4	6.8	31	0.1	11.7	2.9	42	0.84	4.3	0.9	<0.1	7	0.2	0.5	0.1	17	0.02	0.045	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282761	Soil	15	0.18	455	0.003	3	0.65	0.007	0.07	<0.1	0.12	2.2	0.2	<0.05	2	1.5	<0.2
1282762	Soil	19	0.08	544	0.004	2	0.48	0.004	0.07	0.2	0.04	1.0	0.5	<0.05	3	1.5	<0.2
1282763	Soil	21	0.12	636	0.002	3	0.69	0.026	0.07	<0.1	0.15	1.5	0.3	<0.05	2	1.4	<0.2
1282764	Soil	37	0.33	540	0.001	2	1.16	0.005	0.05	<0.1	0.06	1.9	0.4	<0.05	3	1.7	<0.2
1282765	Soil	31	0.25	399	0.002	2	1.12	0.007	0.08	<0.1	0.17	1.7	0.7	<0.05	4	2.1	<0.2
1282766	Soil	15	0.05	255	0.003	2	0.41	0.004	0.05	0.2	0.02	1.0	0.7	<0.05	3	2.1	<0.2
1282767	Soil	23	0.23	895	0.002	2	1.12	0.006	0.04	0.1	0.02	1.9	0.4	<0.05	3	1.4	<0.2
1282768	Soil	17	0.04	294	0.009	2	0.64	0.005	0.06	0.6	0.03	1.1	3.3	<0.05	3	4.6	<0.2
1282769	Soil	4	<0.01	37	0.001	1	0.19	0.010	0.03	<0.1	<0.01	0.3	<0.1	<0.05	2	<0.5	<0.2
1282770	Soil	7	0.01	77	0.011	1	0.29	0.005	0.03	<0.1	0.02	0.5	0.1	<0.05	2	<0.5	<0.2
1282771	Soil	14	0.15	75	0.002	2	0.79	0.008	0.06	<0.1	0.01	1.2	0.2	<0.05	3	<0.5	<0.2
1282772	Soil	4	0.02	57	0.002	<1	0.35	0.018	0.03	<0.1	0.01	0.5	<0.1	<0.05	2	<0.5	<0.2
1282773	Soil	19	0.06	111	0.001	1	0.99	0.006	0.05	<0.1	0.03	1.2	0.2	<0.05	6	<0.5	<0.2
1282774	Soil	20	0.12	103	0.004	2	0.87	0.009	0.05	<0.1	0.05	0.8	0.1	<0.05	5	<0.5	<0.2
1282775	Soil	17	0.20	315	0.002	2	0.75	0.007	0.06	<0.1	0.09	1.6	0.2	<0.05	2	0.8	<0.2
1282776	Soil	18	0.19	110	0.001	1	0.68	0.003	0.06	<0.1	0.05	2.4	0.2	<0.05	2	<0.5	<0.2
1282777	Soil	8	0.03	40	0.001	1	0.38	0.007	0.03	0.1	0.02	0.4	0.1	<0.05	3	<0.5	<0.2
1282778	Soil	31	0.32	89	0.002	1	1.16	0.005	0.06	<0.1	0.06	1.9	0.2	<0.05	4	0.7	<0.2
1282779	Soil	25	0.37	88	0.005	2	1.18	0.005	0.06	0.1	0.05	1.7	0.2	<0.05	4	0.7	<0.2
1282780	Soil	22	0.21	68	0.003	1	0.80	0.006	0.05	<0.1	0.04	1.0	0.1	<0.05	3	0.5	<0.2
1282781	Soil	18	0.17	71	0.004	1	0.92	0.006	0.04	<0.1	0.05	0.7	0.2	<0.05	3	0.6	<0.2
1282782	Soil	18	0.11	67	0.012	<1	0.70	0.006	0.05	0.1	0.01	0.8	0.2	<0.05	5	<0.5	<0.2
1282783	Soil	19	0.08	69	0.004	<1	0.79	0.005	0.04	0.1	0.05	0.7	0.2	<0.05	6	0.7	<0.2
1282784	Soil	24	0.14	57	0.006	<1	0.92	0.006	0.04	<0.1	0.04	0.7	0.1	<0.05	4	0.6	<0.2
1282785	Soil	21	0.08	76	0.005	<1	0.82	0.004	0.05	0.1	0.03	0.8	0.2	<0.05	6	0.5	<0.2
1282786	Soil	18	0.09	105	0.003	<1	1.00	0.005	0.05	<0.1	0.02	1.0	0.1	<0.05	5	<0.5	<0.2
1282787	Soil	12	0.10	38	0.005	<1	0.61	0.015	0.03	<0.1	0.03	0.5	0.1	<0.05	2	<0.5	<0.2
1282788	Soil	24	0.08	76	0.003	<1	1.04	0.005	0.05	<0.1	0.10	1.0	0.2	<0.05	5	0.5	<0.2
1282789	Soil	4	0.02	37	0.002	<1	0.33	0.024	0.03	<0.1	0.02	<0.1	<0.1	<0.05	1	<0.5	<0.2
1282790	Soil	13	0.02	99	0.001	<1	0.37	0.010	0.03	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282791	Soil	1.6	20.5	17.3	104	0.2	34.8	13.1	230	3.18	13.8	0.6	1.1	12	0.2	1.0	0.2	21	0.08	0.045	2
1282792	Soil	0.9	11.2	7.2	50	0.3	13.0	5.1	131	1.70	5.6	0.6	0.5	4	0.1	0.4	0.1	16	0.02	0.039	1
1282793	Soil	2.5	18.7	12.9	80	<0.1	21.1	8.3	176	4.54	16.3	<0.5	1.7	4	<0.1	1.1	0.2	38	0.01	0.058	3
1282794	Soil	3.4	16.5	17.1	76	<0.1	22.9	6.8	206	3.02	20.0	0.6	0.3	10	0.1	1.7	0.3	39	0.04	0.066	8
1282795	Soil	1.8	17.9	14.5	83	<0.1	25.2	9.5	275	3.89	22.0	0.9	0.5	6	<0.1	1.4	0.2	29	0.02	0.069	3
1282796	Soil	2.1	12.8	7.4	46	0.1	14.5	5.5	227	1.39	7.1	0.5	0.2	6	<0.1	0.8	0.1	22	0.02	0.086	3
1282797	Soil	1.8	15.9	13.1	69	0.1	21.1	7.4	172	2.61	13.5	0.9	0.3	8	<0.1	1.0	0.2	28	0.03	0.057	5
1282798	Soil	1.5	9.3	8.2	42	<0.1	9.9	3.7	111	1.76	9.2	1.7	0.2	6	<0.1	0.8	0.1	32	0.02	0.043	6
1282799	Soil	2.1	16.0	16.6	74	0.7	21.0	9.9	344	2.68	12.9	1.7	0.3	7	0.2	1.1	0.2	30	0.03	0.066	6
1282800	Soil	2.2	15.7	14.3	74	0.1	18.3	7.8	259	4.17	14.8	3.2	0.7	7	<0.1	1.3	0.2	42	0.03	0.072	5
1282801	Soil	2.5	6.9	17.5	16	0.1	14.8	1.6	58	0.81	2.8	1.2	<0.1	4	<0.1	0.3	<0.1	13	0.02	0.055	2
1282802	Soil	2.1	17.2	12.6	75	<0.1	17.8	8.4	904	2.93	14.8	0.8	0.2	7	0.1	1.2	0.2	39	0.02	0.063	6
1282803	Soil	1.6	9.4	7.5	37	<0.1	11.3	3.4	96	1.44	7.4	1.1	<0.1	4	<0.1	0.6	0.1	24	0.03	0.057	3
1282804	Soil	0.9	6.8	6.1	25	<0.1	7.3	2.8	67	0.88	4.6	0.6	<0.1	4	<0.1	0.5	0.1	18	0.02	0.041	3
1282805	Soil	2.6	11.9	15.3	46	<0.1	19.0	4.4	85	1.74	14.5	1.2	0.2	8	<0.1	1.0	0.2	27	0.02	0.052	4
1282806	Soil	2.0	11.8	12.9	64	<0.1	16.8	7.7	330	2.51	14.2	1.2	1.0	9	<0.1	1.1	0.3	32	0.04	0.072	6
1282807	Soil	2.6	17.0	17.5	91	<0.1	29.5	10.2	209	3.97	18.8	1.2	1.3	7	0.1	1.6	0.3	37	0.02	0.078	4
1282808	Soil	2.3	11.8	14.4	62	0.1	13.7	4.5	142	3.52	13.2	0.9	0.8	10	0.1	1.0	0.2	42	0.04	0.079	4
1282809	Soil	1.7	10.2	9.4	56	0.2	13.9	4.8	149	2.28	9.9	0.9	0.9	7	<0.1	0.7	0.2	33	0.04	0.050	3
1282810	Soil	4.2	25.6	21.8	131	0.1	37.7	15.0	342	4.16	22.0	1.3	2.1	12	0.2	2.0	0.3	44	0.02	0.071	6
1283141	Soil	6.4	26.4	8.2	103	<0.1	32.7	7.4	270	2.59	16.3	1.9	0.4	8	0.2	1.5	0.3	51	0.04	0.067	13
1283142	Soil	6.1	78.8	15.9	222	<0.1	75.5	14.8	372	7.39	62.3	1.9	1.7	6	0.2	2.9	0.5	28	0.03	0.111	15
1283143	Soil	1.7	25.7	8.2	48	<0.1	15.1	4.2	128	1.63	4.2	0.9	0.2	6	0.2	0.6	0.2	14	0.06	0.051	8
1283144	Soil	4.1	21.2	8.3	98	0.2	27.8	7.5	192	2.86	74.3	2.0	0.3	7	0.1	3.2	0.2	31	0.05	0.058	11
1283145	Soil	6.8	37.6	13.6	139	0.2	37.8	8.6	146	2.92	68.6	6.0	0.3	12	0.2	4.4	0.3	39	0.02	0.073	15
1283146	Soil	49.1	30.8	10.8	311	0.3	88.9	6.9	73	2.11	90.7	30.8	0.1	4	0.3	15.8	0.2	139	0.02	0.072	13
1283147	Soil	9.4	5.5	17.8	19	1.2	5.6	0.7	58	0.89	13.2	11.4	0.2	10	<0.1	3.3	0.2	38	0.02	0.051	4
1283148	Soil	36.5	14.0	20.3	55	2.4	13.8	1.4	39	1.08	21.9	4.7	0.1	19	0.1	5.6	0.2	134	0.03	0.083	7
1283149	Soil	12.8	22.6	46.3	58	2.7	14.7	2.0	39	2.07	24.2	5.9	1.1	30	0.5	4.3	0.3	43	0.02	0.074	2
1283150	Soil	16.0	18.8	41.3	70	0.8	14.1	2.4	39	1.48	39.2	11.1	1.0	32	0.2	5.3	0.3	28	0.02	0.035	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282791	Soil	21	0.27	60	0.001	<1	0.89	0.005	0.07	<0.1	0.04	1.9	<0.1	<0.05	3	<0.5	<0.2
1282792	Soil	13	0.10	48	0.002	<1	0.69	0.015	0.04	<0.1	0.05	1.0	<0.1	<0.05	3	<0.5	<0.2
1282793	Soil	26	0.12	64	0.002	<1	1.14	0.005	0.04	<0.1	0.02	2.0	0.1	<0.05	6	<0.5	<0.2
1282794	Soil	24	0.12	74	0.006	<1	0.66	0.004	0.06	0.1	0.03	0.7	0.2	<0.05	4	0.7	<0.2
1282795	Soil	18	0.12	58	0.002	<1	0.84	0.007	0.04	<0.1	0.03	1.3	0.1	<0.05	3	<0.5	<0.2
1282796	Soil	16	0.03	88	0.002	<1	0.57	0.012	0.04	<0.1	0.03	0.3	0.1	<0.05	3	<0.5	<0.2
1282797	Soil	17	0.15	67	0.004	<1	0.75	0.008	0.05	0.1	0.04	0.9	0.1	<0.05	3	<0.5	<0.2
1282798	Soil	10	0.05	66	0.005	<1	0.57	0.008	0.04	0.1	0.02	0.4	0.1	<0.05	4	<0.5	<0.2
1282799	Soil	21	0.15	74	0.004	<1	0.78	0.006	0.05	0.1	0.04	0.7	0.1	<0.05	3	<0.5	<0.2
1282800	Soil	21	0.10	82	0.005	<1	0.98	0.006	0.05	0.1	0.02	1.4	0.2	<0.05	5	0.5	<0.2
1282801	Soil	24	0.02	40	0.003	<1	0.37	0.017	0.03	<0.1	0.03	0.1	<0.1	<0.05	2	<0.5	<0.2
1282802	Soil	19	0.06	128	0.004	<1	0.68	0.008	0.06	<0.1	0.03	0.8	0.1	<0.05	4	<0.5	<0.2
1282803	Soil	13	0.03	38	0.002	<1	0.51	0.012	0.04	<0.1	0.04	0.2	<0.1	<0.05	3	<0.5	<0.2
1282804	Soil	8	0.02	43	0.003	<1	0.42	0.013	0.03	<0.1	0.02	0.2	<0.1	<0.05	3	<0.5	<0.2
1282805	Soil	20	0.03	60	0.003	<1	0.53	0.008	0.05	<0.1	0.02	0.6	0.1	<0.05	3	<0.5	<0.2
1282806	Soil	14	0.08	145	0.004	<1	0.63	0.003	0.06	<0.1	0.02	1.1	0.2	<0.05	3	<0.5	<0.2
1282807	Soil	26	0.16	81	0.002	<1	1.06	0.004	0.05	<0.1	0.03	2.2	0.2	<0.05	4	<0.5	<0.2
1282808	Soil	23	0.08	130	0.002	<1	1.01	0.007	0.06	<0.1	0.04	1.1	0.1	<0.05	5	<0.5	<0.2
1282809	Soil	16	0.09	134	0.002	<1	0.91	0.012	0.06	<0.1	<0.01	0.9	<0.1	<0.05	4	<0.5	<0.2
1282810	Soil	29	0.23	147	0.002	2	1.14	0.004	0.07	0.1	<0.01	2.1	0.3	<0.05	4	0.8	<0.2
1283141	Soil	17	0.04	174	0.004	3	0.48	0.007	0.08	0.1	<0.01	0.5	0.2	<0.05	3	0.5	<0.2
1283142	Soil	17	0.06	108	0.002	4	0.58	0.004	0.10	<0.1	<0.01	3.1	0.3	<0.05	2	0.9	<0.2
1283143	Soil	5	0.04	70	0.005	3	0.36	0.019	0.04	<0.1	<0.01	0.3	<0.1	<0.05	2	0.5	<0.2
1283144	Soil	10	0.05	91	0.004	2	0.60	0.009	0.05	<0.1	0.14	0.5	0.2	<0.05	3	0.8	<0.2
1283145	Soil	11	0.05	251	0.004	2	0.65	0.005	0.06	0.1	1.23	0.4	0.3	<0.05	3	2.0	<0.2
1283146	Soil	14	0.03	93	0.001	4	0.37	0.005	0.06	0.2	5.20	0.3	0.8	<0.05	2	2.9	<0.2
1283147	Soil	8	0.02	115	0.005	3	0.24	0.016	0.09	0.1	1.81	0.2	0.6	0.12	2	2.1	<0.2
1283148	Soil	16	0.02	156	0.002	4	0.44	0.012	0.08	0.2	0.60	0.1	1.2	0.06	4	3.5	<0.2
1283149	Soil	11	0.01	255	<0.001	3	0.36	0.004	0.12	<0.1	0.43	1.1	0.3	0.14	2	3.1	<0.2
1283150	Soil	10	0.01	209	0.001	3	0.27	0.003	0.10	<0.1	3.19	1.3	0.4	0.11	1	3.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283251	Soil	3.0	29.6	26.2	139	0.1	38.9	20.3	457	3.98	17.0	1.3	1.9	12	0.1	1.3	0.3	35	0.02	0.066	5
1283252	Soil	2.6	17.4	12.8	74	0.1	15.0	5.8	117	2.63	11.7	0.5	0.9	6	0.1	1.0	0.2	45	0.02	0.076	5
1283253	Soil	2.0	29.5	33.6	115	0.1	35.4	9.8	183	4.32	12.8	<0.5	1.5	19	<0.1	0.6	0.3	21	0.01	0.061	2
1283254	Soil	1.5	13.9	7.9	62	<0.1	12.2	5.0	66	1.47	6.1	<0.5	0.1	5	<0.1	0.6	0.2	25	0.01	0.051	3
1283255	Soil	2.6	19.7	15.5	100	<0.1	20.5	7.8	142	4.13	15.1	<0.5	1.4	9	0.1	1.2	0.3	43	0.03	0.067	4
1283256	Soil	0.5	4.1	3.2	12	<0.1	4.2	1.3	58	0.40	1.1	<0.5	<0.1	4	<0.1	0.2	<0.1	7	0.02	0.054	1
1283257	Soil	4.1	18.3	15.7	68	0.1	18.5	5.7	140	1.98	11.8	<0.5	0.2	8	0.2	1.3	0.2	45	0.03	0.069	7
1283258	Soil	3.5	23.8	16.8	129	0.2	35.7	15.4	331	3.64	14.1	0.6	1.5	6	0.1	1.5	0.2	35	0.02	0.057	4
1283259	Soil	3.4	25.4	25.8	91	0.1	21.6	8.5	267	5.60	19.3	0.5	0.6	9	0.1	1.3	0.3	55	0.05	0.144	4
1283260	Soil	1.5	13.8	13.5	52	<0.1	12.7	5.0	150	1.79	5.3	<0.5	0.2	20	0.3	0.5	0.1	24	0.08	0.064	5
1283441	Soil	2.2	34.5	12.8	116	1.1	40.7	5.0	127	2.22	12.1	5.7	0.6	69	0.7	1.2	0.2	30	1.63	0.108	7
1283442	Soil	2.3	34.7	14.1	130	1.0	43.3	6.2	139	2.39	13.8	6.3	0.8	57	0.6	1.3	0.2	35	1.07	0.104	8
1283443	Soil	1.5	17.9	9.4	107	0.6	23.2	3.3	94	1.20	7.2	2.7	0.4	50	0.7	1.0	0.1	27	1.13	0.130	9
1283444	Soil	0.7	13.0	6.1	65	0.3	12.6	1.8	77	0.82	4.9	1.1	0.1	41	0.6	0.6	0.3	25	1.06	0.105	8
1283445	Soil	0.6	12.1	3.3	68	0.3	10.0	1.6	127	0.55	2.6	1.0	0.1	35	0.7	0.5	<0.1	16	0.93	0.102	9
1283446	Soil	0.2	4.8	2.0	20	<0.1	3.5	0.9	65	0.26	0.8	<0.5	<0.1	28	0.2	0.1	<0.1	8	0.79	0.042	3
1283447	Soil	1.6	25.1	11.0	129	0.9	32.8	3.7	125	1.45	15.7	5.9	0.6	66	1.0	1.5	0.2	30	1.40	0.106	9
1283448	Soil	0.9	15.8	7.7	68	0.5	16.6	2.8	79	1.02	15.7	16.7	0.3	40	0.5	1.1	0.1	17	1.01	0.058	5
1283449	Soil	1.2	17.7	9.5	96	0.8	23.4	3.6	181	1.32	14.7	8.9	0.4	73	0.8	1.2	0.2	29	1.84	0.105	6
1283450	Soil	1.5	25.0	10.1	164	0.9	38.6	4.9	166	1.59	11.3	4.4	0.7	81	1.1	1.2	0.2	32	1.47	0.174	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

CERTIFICATE OF ANALYSIS WHI11001404.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283251	Soil	24	0.27	92	0.002	1	1.19	0.003	0.06	<0.1	0.05	2.7	0.2	<0.05	4	0.5	<0.2
1283252	Soil	12	0.06	101	0.004	<1	0.65	0.006	0.05	<0.1	0.01	1.5	0.1	<0.05	4	<0.5	<0.2
1283253	Soil	25	0.34	65	<0.001	1	1.21	0.003	0.05	<0.1	0.02	4.1	0.2	<0.05	3	1.3	<0.2
1283254	Soil	10	0.02	44	0.002	1	0.48	0.009	0.03	<0.1	<0.01	0.4	<0.1	<0.05	3	<0.5	<0.2
1283255	Soil	17	0.11	73	0.002	<1	0.97	0.003	0.05	<0.1	<0.01	2.0	0.1	<0.05	5	<0.5	<0.2
1283256	Soil	6	0.02	27	0.002	<1	0.28	0.020	0.02	<0.1	<0.01	<0.1	<0.1	<0.05	1	<0.5	<0.2
1283257	Soil	17	0.08	73	0.004	1	0.56	0.006	0.05	0.1	<0.01	0.4	0.1	<0.05	4	<0.5	<0.2
1283258	Soil	23	0.30	61	0.003	1	1.11	0.006	0.04	<0.1	<0.01	2.3	0.1	<0.05	4	<0.5	<0.2
1283259	Soil	28	0.15	73	0.005	<1	1.01	0.005	0.05	0.1	<0.01	1.4	0.2	<0.05	6	<0.5	<0.2
1283260	Soil	15	0.07	103	0.005	1	0.94	0.013	0.04	<0.1	<0.01	0.7	0.1	<0.05	4	<0.5	<0.2
1283441	Soil	25	0.08	529	0.001	3	0.70	0.005	0.06	<0.1	0.26	1.9	<0.1	0.14	2	2.3	<0.2
1283442	Soil	25	0.09	509	0.002	3	0.77	0.004	0.05	<0.1	0.31	2.2	0.1	0.08	2	2.3	<0.2
1283443	Soil	17	0.11	231	0.005	3	0.73	0.021	0.05	<0.1	0.11	1.0	<0.1	0.10	2	1.1	<0.2
1283444	Soil	11	0.04	252	0.005	2	0.77	0.024	0.04	<0.1	0.13	0.6	<0.1	0.10	2	0.7	<0.2
1283445	Soil	12	0.06	120	0.007	2	0.48	0.031	0.03	<0.1	0.07	0.4	<0.1	0.08	<1	<0.5	<0.2
1283446	Soil	5	0.03	76	0.006	1	0.40	0.031	0.02	<0.1	<0.01	0.2	<0.1	0.06	<1	<0.5	<0.2
1283447	Soil	19	0.12	324	0.002	4	0.67	0.013	0.05	<0.1	0.61	1.5	0.1	0.09	2	1.2	<0.2
1283448	Soil	10	0.04	278	0.003	2	0.52	0.023	0.04	<0.1	0.44	0.9	<0.1	0.07	1	0.6	<0.2
1283449	Soil	16	0.08	610	0.002	4	0.76	0.011	0.04	<0.1	0.52	0.9	0.1	0.13	2	1.2	<0.2
1283450	Soil	20	0.09	539	0.001	4	0.69	0.011	0.06	<0.1	0.42	1.6	0.1	0.10	2	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1278967	Soil	4.9	24.9	14.4	112	0.2	30.7	5.3	85	2.67	22.3	2.6	0.5	17	0.2	1.9	0.2	40	0.11	0.084	3
REP 1278967	QC	5.0	25.9	14.5	118	0.2	31.5	5.3	87	2.74	22.8	2.1	0.5	17	0.2	2.0	0.2	42	0.11	0.087	3
1278984	Soil	7.9	7.0	6.4	36	0.3	6.8	1.2	19	0.55	6.3	<0.5	0.1	5	<0.1	3.2	0.1	46	0.01	0.026	4
REP 1278984	QC	7.7	6.6	6.5	36	0.3	7.1	1.2	20	0.52	5.9	0.5	0.1	5	<0.1	3.1	0.1	45	<0.01	0.026	4
1282554	Soil	1.6	44.0	13.5	115	0.8	27.2	5.2	180	1.77	25.7	11.5	0.7	71	0.9	2.5	0.3	43	1.80	0.105	7
REP 1282554	QC	1.8	45.4	14.7	119	0.8	26.7	5.2	180	1.79	25.2	13.1	0.6	74	0.9	2.6	0.3	43	1.79	0.102	7
1282569	Soil	21.8	33.2	25.1	235	0.1	42.0	5.9	135	3.12	47.7	1.4	0.9	23	0.8	7.3	0.3	215	0.04	0.104	13
REP 1282569	QC	20.5	33.6	24.9	231	0.2	41.5	5.7	131	3.04	46.3	1.1	0.9	21	0.7	7.4	0.3	213	0.04	0.098	14
1282577	Soil	11.1	37.4	9.4	1174	1.1	132.7	4.1	89	1.14	13.1	5.7	1.0	64	6.5	4.0	0.1	98	1.22	0.060	5
REP 1282577	QC	11.0	36.8	9.2	1195	1.0	132.9	4.2	91	1.18	13.4	5.9	0.6	65	6.5	4.0	0.1	107	1.24	0.060	5
1282595	Soil	2.0	11.0	16.2	51	<0.1	11.9	3.6	68	1.76	8.0	0.7	0.1	7	<0.1	0.5	0.2	23	0.02	0.066	5
REP 1282595	QC	2.0	11.2	16.3	51	<0.1	11.9	3.5	68	1.76	8.2	1.1	0.1	7	<0.1	0.6	0.2	23	0.02	0.069	5
1282625	Soil	2.8	25.7	9.5	46	0.3	15.9	28.7	1592	2.80	6.5	1.0	0.2	6	0.1	0.6	0.1	26	0.03	0.053	3
REP 1282625	QC	3.2	25.9	9.6	47	0.3	16.3	29.0	1570	2.84	6.3	<0.5	0.2	7	0.1	0.6	0.2	25	0.03	0.055	3
1282661	Soil	2.3	21.6	24.6	40	2.0	8.3	1.7	34	1.99	16.5	1.6	0.9	41	<0.1	0.8	0.3	60	<0.01	0.059	5
REP 1282661	QC	2.2	21.4	24.1	39	2.1	8.1	1.7	33	1.94	16.6	2.0	0.7	41	<0.1	0.8	0.2	58	<0.01	0.062	5
1282682	Soil	8.1	41.0	31.1	145	0.7	25.5	5.8	183	2.06	33.7	3.8	0.8	69	0.3	4.7	0.4	61	0.05	0.088	5
REP 1282682	QC	8.2	42.9	31.8	145	0.8	26.6	5.9	185	2.10	34.3	2.0	0.8	68	0.2	4.6	0.4	60	0.05	0.090	4
1282688	Soil	14.3	18.0	58.6	64	1.0	7.8	1.9	62	1.30	35.7	3.8	2.4	135	0.1	6.3	0.4	29	0.02	0.047	3
REP 1282688	QC	13.6	17.7	58.3	63	0.9	7.8	1.8	59	1.25	34.6	5.1	2.4	131	<0.1	6.3	0.4	28	0.02	0.046	3
1282718	Soil	4.1	14.0	17.4	29	0.9	7.6	1.6	27	0.76	5.4	2.3	0.2	23	0.1	1.1	0.2	47	0.01	0.027	15
REP 1282718	QC	4.4	12.8	14.9	30	0.9	7.1	1.4	29	0.71	5.4	2.6	0.2	22	0.2	1.2	0.2	48	0.01	0.024	14
1282732	Soil	37.6	16.4	17.5	145	0.2	49.2	4.7	44	1.55	20.6	1.2	1.1	18	0.2	3.3	0.2	107	0.02	0.051	8
REP 1282732	QC	39.5	18.1	16.5	179	0.2	48.5	4.0	43	1.44	19.8	0.5	1.1	19	0.2	3.4	0.2	119	0.02	0.051	8
1282741	Soil	26.2	47.1	13.7	512	1.2	83.8	5.9	252	1.36	23.7	2.5	1.2	77	6.1	7.0	0.2	310	1.15	0.129	10
REP 1282741	QC	25.4	45.9	13.6	505	1.2	79.8	5.6	246	1.30	22.8	1.9	1.2	73	6.3	7.3	0.2	292	1.11	0.128	10
1282758	Soil	5.5	40.8	14.2	661	0.7	107.5	31.1	3110	3.32	66.7	4.8	2.3	56	5.4	2.4	0.2	73	1.40	0.116	10
REP 1282758	QC	5.7	40.1	13.4	658	0.7	105.2	30.3	3009	3.24	67.1	3.4	2.2	54	5.4	2.5	0.2	72	1.36	0.114	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11001404.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1278967	Soil	16	0.05	208	0.001	<1	0.69	0.004	0.03	<0.1	0.08	1.2	0.1	<0.05	3	1.7	<0.2
REP 1278967	QC	17	0.05	213	0.001	1	0.71	0.004	0.04	<0.1	0.07	1.2	0.1	<0.05	3	1.9	<0.2
1278984	Soil	5	0.01	98	0.001	1	0.21	0.004	0.03	0.2	<0.01	0.2	0.2	<0.05	2	0.6	<0.2
REP 1278984	QC	5	0.01	95	0.001	1	0.20	0.003	0.02	0.2	<0.01	0.2	0.2	<0.05	2	0.7	<0.2
1282554	Soil	20	0.14	606	0.003	3	0.72	0.007	0.05	<0.1	1.06	1.8	0.1	0.13	2	2.0	<0.2
REP 1282554	QC	20	0.14	642	0.003	3	0.77	0.008	0.05	0.1	1.10	1.8	0.1	0.12	2	1.8	<0.2
1282569	Soil	16	0.07	202	0.006	2	0.61	0.004	0.07	0.2	0.03	1.5	0.6	<0.05	3	2.3	<0.2
REP 1282569	QC	17	0.07	210	0.006	2	0.63	0.004	0.07	0.2	0.03	1.4	0.6	<0.05	3	1.7	<0.2
1282577	Soil	11	0.09	368	0.003	5	0.60	0.014	0.05	0.2	0.29	1.1	1.4	0.12	2	2.6	<0.2
REP 1282577	QC	12	0.09	368	0.003	5	0.63	0.015	0.06	0.1	0.28	1.1	1.5	0.14	2	2.6	<0.2
1282595	Soil	8	0.03	50	0.002	1	0.53	0.003	0.04	<0.1	0.02	0.4	0.1	<0.05	3	<0.5	<0.2
REP 1282595	QC	8	0.03	51	0.002	<1	0.55	0.003	0.05	<0.1	0.02	0.5	0.1	<0.05	3	<0.5	<0.2
1282625	Soil	14	0.06	77	0.007	2	0.55	0.012	0.03	<0.1	0.06	0.5	0.1	<0.05	3	0.8	<0.2
REP 1282625	QC	14	0.06	79	0.007	2	0.57	0.013	0.03	0.1	0.04	0.6	0.1	<0.05	3	1.3	<0.2
1282661	Soil	18	0.02	506	0.002	4	0.54	0.005	0.13	<0.1	0.10	0.7	0.1	0.15	4	2.1	<0.2
REP 1282661	QC	17	0.02	510	0.002	4	0.56	0.005	0.13	<0.1	0.08	0.8	0.1	0.16	3	2.3	<0.2
1282682	Soil	12	0.10	205	0.007	2	0.59	0.015	0.09	<0.1	0.11	2.8	0.5	0.07	2	2.4	<0.2
REP 1282682	QC	13	0.10	204	0.007	2	0.60	0.014	0.09	<0.1	0.11	2.9	0.4	0.08	2	2.7	<0.2
1282688	Soil	7	0.02	435	0.004	3	0.29	0.006	0.12	<0.1	0.22	2.6	0.6	0.17	1	3.8	<0.2
REP 1282688	QC	6	0.02	426	0.002	3	0.30	0.006	0.12	<0.1	0.22	2.5	0.6	0.17	1	4.1	<0.2
1282718	Soil	11	0.01	155	0.007	<1	0.39	0.002	0.02	0.2	0.09	0.2	0.1	<0.05	3	<0.5	<0.2
REP 1282718	QC	12	<0.01	144	0.007	1	0.35	0.002	0.02	0.2	0.07	0.2	<0.1	<0.05	3	<0.5	<0.2
1282732	Soil	9	0.03	530	0.002	2	0.39	0.003	0.06	<0.1	0.04	0.8	0.4	<0.05	2	1.5	<0.2
REP 1282732	QC	10	0.02	521	0.002	2	0.35	0.002	0.06	<0.1	0.03	1.1	0.4	<0.05	3	0.9	<0.2
1282741	Soil	29	0.12	804	0.004	5	0.67	0.009	0.07	0.2	0.54	2.9	1.4	<0.05	2	2.5	<0.2
REP 1282741	QC	28	0.11	806	0.003	5	0.62	0.008	0.07	0.2	0.53	2.8	1.3	<0.05	2	3.5	<0.2
1282758	Soil	17	0.28	544	0.005	6	0.79	0.006	0.11	0.1	0.39	3.1	0.7	0.07	2	1.6	<0.2
REP 1282758	QC	17	0.27	523	0.004	6	0.77	0.006	0.11	<0.1	0.37	2.8	0.7	0.06	2	1.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11001404.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1282783	Soil	3.9	14.2	16.1	55	0.1	14.6	3.8	98	3.50	14.6	1.2	0.2	8	<0.1	1.4	0.3	55	0.02	0.072	5
REP 1282783	QC	3.6	13.9	16.8	54	0.1	13.4	3.6	97	3.55	14.2	2.1	0.2	8	<0.1	1.4	0.3	53	0.03	0.076	5
1282803	Soil	1.6	9.4	7.5	37	<0.1	11.3	3.4	96	1.44	7.4	1.1	<0.1	4	<0.1	0.6	0.1	24	0.03	0.057	3
REP 1282803	QC	1.3	8.2	6.8	32	<0.1	9.4	3.0	85	1.23	6.2	0.6	<0.1	4	<0.1	0.6	0.1	21	0.03	0.049	2
1283147	Soil	9.4	5.5	17.8	19	1.2	5.6	0.7	58	0.89	13.2	11.4	0.2	10	<0.1	3.3	0.2	38	0.02	0.051	4
REP 1283147	QC	8.7	4.9	16.2	18	1.1	5.0	0.7	56	0.81	12.4	13.8	<0.1	10	<0.1	3.1	0.2	34	0.02	0.050	4
1283444	Soil	0.7	13.0	6.1	65	0.3	12.6	1.8	77	0.82	4.9	1.1	0.1	41	0.6	0.6	0.3	25	1.06	0.105	8
REP 1283444	QC	0.7	11.7	5.7	62	0.3	11.2	1.7	70	0.76	4.3	2.0	0.2	38	0.5	0.6	0.1	23	0.96	0.095	8
Reference Materials																					
STD DS8	Standard	11.4	98.0	113.0	286	1.6	36.1	7.0	568	2.25	21.6	98.7	5.7	56	2.0	4.8	5.9	41	0.62	0.070	13
STD DS8	Standard	13.0	102.8	122.1	300	1.7	37.6	7.0	599	2.34	22.8	107.9	6.2	65	2.1	4.8	6.2	40	0.67	0.078	15
STD DS8	Standard	13.6	115.3	122.9	313	1.7	39.4	7.9	652	2.57	25.3	111.2	6.9	69	2.2	5.8	6.5	48	0.74	0.079	18
STD DS8	Standard	13.1	116.5	125.7	303	1.7	37.6	7.7	614	2.51	25.4	110.6	7.3	74	2.3	6.1	7.3	44	0.66	0.075	15
STD DS8	Standard	12.8	101.3	120.7	297	1.7	36.6	7.0	570	2.34	22.5	120.2	6.2	63	2.1	5.3	6.0	39	0.65	0.072	15
STD DS8	Standard	15.2	118.5	125.5	329	1.8	41.5	7.7	635	2.40	26.2	102.3	6.8	70	2.4	5.5	6.6	41	0.70	0.078	15
STD DS8	Standard	12.9	93.8	104.1	282	1.6	35.3	7.2	572	2.25	24.7	107.3	5.5	62	2.3	5.0	6.1	42	0.64	0.080	15
STD DS8	Standard	13.4	112.5	128.4	319	1.8	39.1	8.1	625	2.56	25.9	118.9	6.8	70	2.3	6.0	7.1	43	0.70	0.082	15
STD DS8	Standard	11.8	102.4	118.4	294	1.6	36.2	7.0	632	2.32	22.8	102.7	6.0	59	2.1	5.0	6.5	37	0.59	0.073	13
STD DS8	Standard	13.7	109.1	123.4	310	1.8	38.5	7.5	603	2.48	24.3	114.1	6.6	65	2.2	5.4	5.7	45	0.71	0.078	16
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11001404.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1282783	Soil	19	0.08	69	0.004	<1	0.79	0.005	0.04	0.1	0.05	0.7	0.2	<0.05	6	0.7	<0.2
REP 1282783	QC	19	0.09	67	0.006	2	0.84	0.006	0.04	0.1	0.06	0.7	0.2	<0.05	5	0.8	<0.2
1282803	Soil	13	0.03	38	0.002	<1	0.51	0.012	0.04	<0.1	0.04	0.2	<0.1	<0.05	3	<0.5	<0.2
REP 1282803	QC	12	0.03	37	0.003	<1	0.49	0.014	0.04	<0.1	0.03	0.3	<0.1	<0.05	3	<0.5	<0.2
1283147	Soil	8	0.02	115	0.005	3	0.24	0.016	0.09	0.1	1.81	0.2	0.6	0.12	2	2.1	<0.2
REP 1283147	QC	7	0.02	109	0.004	3	0.23	0.016	0.08	<0.1	1.77	0.1	0.5	0.08	2	1.8	<0.2
1283444	Soil	11	0.04	252	0.005	2	0.77	0.024	0.04	<0.1	0.13	0.6	<0.1	0.10	2	0.7	<0.2
REP 1283444	QC	12	0.04	227	0.004	2	0.70	0.020	0.03	<0.1	0.11	0.5	<0.1	0.07	2	0.5	<0.2
Reference Materials																	
STD DS8	Standard	111	0.59	221	0.097	2	0.87	0.085	0.40	2.7	0.18	1.8	4.9	0.16	4	4.9	4.6
STD DS8	Standard	114	0.59	265	0.111	2	0.90	0.096	0.39	2.6	0.18	2.2	5.3	0.17	4	4.9	5.0
STD DS8	Standard	130	0.63	277	0.135	3	0.96	0.097	0.42	3.0	0.19	2.5	5.4	0.17	5	5.3	5.0
STD DS8	Standard	121	0.59	262	0.123	2	0.90	0.095	0.40	2.7	0.21	2.5	5.5	0.17	4	5.3	4.6
STD DS8	Standard	116	0.58	258	0.105	2	0.86	0.084	0.43	2.9	0.20	1.8	5.4	0.14	4	5.0	4.8
STD DS8	Standard	113	0.59	286	0.116	2	0.93	0.086	0.41	3.3	0.21	2.1	5.5	0.17	5	5.4	4.6
STD DS8	Standard	109	0.58	275	0.110	2	0.87	0.087	0.40	2.8	0.20	1.9	5.0	0.16	4	4.8	4.5
STD DS8	Standard	121	0.62	291	0.118	3	0.93	0.098	0.43	3.1	0.24	2.3	5.4	0.16	5	5.9	4.9
STD DS8	Standard	109	0.57	240	0.092	5	0.83	0.098	0.39	2.8	0.19	2.5	5.3	0.13	4	4.8	4.5
STD DS8	Standard	117	0.60	272	0.116	3	0.95	0.104	0.43	2.8	0.18	2.0	5.3	0.11	5	5.0	4.8
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11001404.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 31, 2011

QUALITY CONTROL REPORT WHI11001404.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 05, 2011
Report Date: October 26, 2011
Page: 1 of 10

CERTIFICATE OF ANALYSIS WHI11001405.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #21
P.O. Number
Number of Samples: 270

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	270	Sieve soil to 230 mesh			WHI
RJSV	270	Saving all or part of Soil Reject			WHI
1DX2	261	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283651	Soil		28.0	39.3	10.6	88	0.5	65.3	9.9	150	3.10	33.3	10.0	1.3	45	0.3	5.3	0.2	184	0.02	0.059	6
1283652	Soil		3.2	14.5	7.6	87	1.9	14.1	1.5	39	1.24	9.4	3.5	<0.1	40	0.2	0.8	0.2	30	0.02	0.111	3
1283653	Soil		5.7	60.1	19.3	73	1.5	19.1	3.8	210	2.61	25.4	13.0	0.4	37	<0.1	1.5	0.3	36	0.03	0.141	4
1283654	Soil		12.0	187.5	29.3	191	3.0	64.1	13.7	534	6.50	63.5	25.8	1.7	52	0.2	2.9	0.5	57	0.04	0.169	5
1283655	Soil		1.6	35.1	21.3	90	1.1	20.7	4.5	77	2.16	29.0	2.5	0.5	40	<0.1	1.2	0.3	38	0.01	0.085	2
1283656	Soil		2.4	37.2	24.8	87	0.9	18.9	4.2	103	2.60	52.5	5.2	1.1	29	<0.1	2.1	0.4	36	<0.01	0.057	2
1283657	Soil		2.2	48.8	23.7	103	1.3	25.0	5.2	88	2.91	35.5	3.4	0.7	36	<0.1	1.2	0.3	42	0.02	0.093	3
1283658	Soil		3.6	74.9	31.5	161	1.9	42.9	12.1	376	4.48	54.3	31.4	1.4	47	0.2	2.0	0.3	41	0.06	0.101	5
1283659	Soil		5.0	55.3	49.7	117	3.3	30.1	6.5	128	6.03	58.9	5.0	2.4	109	<0.1	2.1	0.5	47	0.06	0.143	4
1283660	Soil		14.9	104.3	16.9	206	3.7	76.3	4.7	66	3.47	39.5	<0.5	2.4	119	0.8	2.5	0.2	33	0.26	0.089	3
1283661	Soil		5.8	206.6	33.0	252	3.7	109.6	21.6	238	6.44	93.5	12.7	4.0	218	1.6	2.9	0.3	40	0.14	0.155	5
1283662	Soil		2.9	21.5	7.6	68	0.8	20.3	3.5	33	1.54	24.4	3.8	0.3	9	<0.1	1.3	0.1	31	0.01	0.049	2
1283663	Soil		2.7	27.0	15.5	68	0.6	19.9	3.7	56	1.85	33.6	15.8	1.4	31	0.2	2.2	0.3	22	0.02	0.036	3
1283664	Soil		4.5	66.5	18.0	150	2.0	42.9	10.2	202	3.22	53.2	22.0	1.5	39	0.4	3.7	0.2	35	0.05	0.090	3
1283665	Soil		5.0	64.0	19.0	145	1.6	47.2	7.6	131	3.21	137.7	32.1	1.4	55	0.3	5.9	0.2	38	0.02	0.088	3
1283666	Soil		3.6	72.2	19.4	179	1.5	71.2	13.1	195	3.66	89.4	27.8	1.9	75	0.7	5.3	0.2	25	0.09	0.094	4
1283667	Soil		3.4	40.4	13.3	112	2.1	34.1	5.8	65	2.53	41.9	20.8	0.8	24	<0.1	2.8	0.2	45	0.02	0.094	3
1283668	Soil		4.9	45.5	10.6	109	1.3	46.3	4.7	36	1.82	30.2	17.7	0.7	53	0.3	2.3	0.2	23	0.13	0.065	3
1283669	Soil		10.7	74.6	10.7	185	2.5	70.2	5.3	63	2.32	33.6	8.7	1.1	84	1.0	2.6	0.2	25	0.21	0.068	4
1283670	Soil		8.6	15.5	69.8	52	1.8	12.3	2.3	52	1.46	26.8	2.3	0.6	86	0.1	3.0	0.3	122	0.03	0.069	10
1283671	Soil		7.0	22.0	53.6	56	1.4	13.7	2.8	83	1.72	39.6	2.4	0.4	78	0.2	3.1	0.2	98	0.04	0.076	9
1283672	Soil		8.5	34.3	52.1	57	1.9	14.9	2.9	172	1.34	33.8	5.0	0.5	80	0.2	3.3	0.3	84	0.07	0.103	7
1283673	Soil		6.5	17.4	26.3	38	1.9	8.8	1.1	33	1.23	21.8	2.3	0.4	33	0.1	1.9	0.3	67	0.02	0.062	6
1283674	Soil		3.6	24.7	21.5	33	0.6	7.3	1.7	98	1.23	34.7	5.0	0.8	42	0.2	1.9	0.3	44	0.03	0.061	4
1283675	Soil		2.6	14.5	19.9	34	0.6	7.6	1.7	87	1.00	12.7	<0.5	0.1	41	0.2	1.2	0.2	38	0.05	0.065	4
1283676	Soil		2.9	13.4	36.0	29	0.8	6.3	1.6	41	1.12	17.2	2.2	0.3	58	0.1	1.5	0.1	35	0.03	0.072	4
1283677	Soil		3.9	20.3	35.7	53	0.9	12.8	4.0	338	1.56	18.8	1.0	0.2	54	0.3	1.4	0.2	39	0.03	0.111	4
1283678	Soil		4.9	17.5	30.5	56	0.9	10.7	2.6	51	1.26	12.5	1.0	0.2	52	0.5	1.6	0.2	56	0.04	0.068	7
1283679	Soil		4.3	19.9	24.7	60	1.6	13.1	3.1	60	1.28	13.2	0.6	0.2	35	0.2	1.6	0.2	47	0.02	0.058	6
1283680	Soil		3.6	19.7	17.1	61	1.2	12.0	2.4	39	0.99	7.9	<0.5	0.2	20	0.9	1.1	0.2	46	0.02	0.072	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283651	Soil	11	0.02	656	0.005	2	0.66	0.005	0.07	0.3	0.19	1.8	1.7	0.20	2	5.8	<0.2
1283652	Soil	16	0.01	299	0.002	2	0.30	0.009	0.07	<0.1	0.06	<0.1	0.2	0.15	2	4.2	<0.2
1283653	Soil	17	0.05	778	0.004	3	0.65	0.006	0.10	0.1	0.19	1.3	0.2	0.20	2	3.1	<0.2
1283654	Soil	24	0.03	531	0.002	3	1.57	0.003	0.11	0.2	1.17	4.6	0.3	0.20	3	3.9	0.4
1283655	Soil	10	0.02	404	0.002	4	0.40	0.004	0.11	<0.1	0.07	1.4	0.1	0.09	2	2.0	<0.2
1283656	Soil	12	0.03	582	<0.001	3	0.50	0.003	0.10	<0.1	0.13	1.6	0.1	0.07	2	2.3	0.3
1283657	Soil	11	0.02	380	0.002	3	0.45	0.003	0.10	<0.1	0.18	1.5	<0.1	0.10	2	2.2	<0.2
1283658	Soil	16	0.11	709	0.005	2	0.80	0.007	0.10	10.9	0.18	3.5	0.1	<0.05	3	3.6	0.2
1283659	Soil	15	0.04	443	0.001	5	0.42	0.007	0.16	<0.1	0.34	3.7	0.1	0.29	2	8.5	0.4
1283660	Soil	34	0.03	696	<0.001	5	0.43	0.006	0.09	<0.1	0.57	5.9	0.1	0.11	1	16.0	<0.2
1283661	Soil	34	0.05	748	0.001	2	0.77	0.006	0.15	<0.1	0.40	13.9	0.2	0.27	2	6.1	0.2
1283662	Soil	11	0.02	212	0.002	2	0.44	0.010	0.04	<0.1	0.04	1.2	0.1	<0.05	2	1.1	<0.2
1283663	Soil	12	0.02	268	<0.001	4	0.45	0.003	0.08	<0.1	0.59	1.5	0.1	0.07	1	1.8	<0.2
1283664	Soil	19	0.05	586	0.001	2	0.65	0.004	0.08	<0.1	0.30	3.5	0.2	0.09	2	3.0	<0.2
1283665	Soil	20	0.03	532	<0.001	2	0.68	0.004	0.08	<0.1	0.26	2.8	0.2	0.11	2	2.9	<0.2
1283666	Soil	18	0.04	578	<0.001	2	0.63	0.005	0.09	<0.1	0.29	4.0	0.2	0.13	1	2.9	<0.2
1283667	Soil	22	0.04	361	0.002	3	0.63	0.006	0.09	<0.1	0.15	2.6	0.2	0.07	3	2.5	<0.2
1283668	Soil	16	0.04	520	0.001	3	0.53	0.011	0.06	<0.1	0.30	2.0	0.1	0.07	1	2.6	<0.2
1283669	Soil	22	0.03	1309	<0.001	5	0.45	0.003	0.07	<0.1	0.57	3.5	<0.1	0.06	1	5.6	<0.2
1283670	Soil	20	0.06	482	0.015	2	0.53	0.004	0.04	0.2	0.10	1.1	0.4	<0.05	4	3.1	<0.2
1283671	Soil	23	0.09	398	0.012	<1	0.65	0.003	0.05	0.2	0.13	0.8	0.6	<0.05	4	3.7	<0.2
1283672	Soil	21	0.09	424	0.014	1	0.66	0.011	0.07	0.1	0.14	1.3	0.6	0.08	4	3.1	<0.2
1283673	Soil	13	0.02	219	0.005	2	0.35	0.003	0.09	0.1	0.07	1.0	0.4	0.07	3	1.4	<0.2
1283674	Soil	18	0.05	260	0.003	<1	0.37	0.003	0.07	<0.1	0.07	3.0	0.4	0.08	2	2.0	<0.2
1283675	Soil	9	0.04	288	0.006	<1	0.40	0.013	0.06	<0.1	0.05	0.2	0.2	0.08	3	1.6	<0.2
1283676	Soil	10	0.03	362	0.007	<1	0.31	0.010	0.06	0.1	0.04	0.9	0.2	0.07	2	2.7	<0.2
1283677	Soil	13	0.05	393	0.003	1	0.44	0.007	0.07	<0.1	0.04	0.5	0.2	0.09	2	2.3	<0.2
1283678	Soil	12	0.02	494	0.011	1	0.47	0.006	0.06	0.1	0.03	0.6	0.2	<0.05	3	1.4	<0.2
1283679	Soil	9	0.01	347	0.005	<1	0.31	0.004	0.05	<0.1	0.03	0.7	0.1	<0.05	2	1.3	<0.2
1283680	Soil	8	0.02	376	0.008	<1	0.54	0.006	0.03	<0.1	0.03	0.4	0.1	<0.05	2	0.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283681	Soil	6.0	28.2	57.3	56	1.9	11.6	1.3	21	0.95	6.6	0.9	0.3	64	2.4	2.0	0.3	63	0.03	0.085	5
1283682	Soil	1.7	14.2	20.2	29	1.2	9.3	1.0	11	0.55	3.7	2.0	<0.1	29	0.5	0.6	0.1	27	0.08	0.043	2
1283683	Soil	2.3	14.3	34.3	16	1.7	4.1	0.6	11	0.46	8.6	1.8	<0.1	54	0.4	1.0	0.1	28	0.03	0.049	3
1283684	Soil	1.2	5.9	13.4	13	1.8	3.3	0.7	10	0.35	3.6	1.7	<0.1	21	0.1	0.4	<0.1	18	0.03	0.041	2
1283685	Soil	4.8	11.1	31.9	26	1.5	6.8	1.3	29	0.68	12.8	3.4	0.5	36	0.2	1.7	0.1	33	0.04	0.039	5
1283686	Soil	4.6	10.6	24.6	21	0.6	6.0	1.3	27	0.68	8.4	3.5	0.3	27	0.2	1.3	0.1	31	0.06	0.038	3
1283687	Soil	3.2	14.5	11.9	89	<0.1	14.7	5.8	134	2.30	19.5	1.7	1.0	14	0.2	1.5	0.3	46	0.03	0.036	5
1283688	Soil	1.5	13.9	10.7	73	0.2	21.5	7.2	161	2.45	12.2	0.5	1.1	17	0.3	0.6	0.3	42	0.08	0.055	4
1283689	Soil	2.1	41.1	11.7	106	0.8	50.1	16.3	447	2.21	9.9	3.7	1.5	140	0.6	1.0	0.3	38	0.96	0.096	8
1283690	Soil	5.2	19.5	31.5	54	1.4	14.6	4.3	246	1.17	14.9	5.4	0.8	108	0.3	2.2	0.3	39	0.53	0.067	5
1283691	Soil	6.4	27.9	30.6	68	1.6	19.7	5.0	267	1.58	17.7	5.9	0.8	101	0.3	2.3	0.3	61	0.53	0.080	5
1283692	Soil	2.7	31.6	20.9	144	1.3	45.1	8.5	239	2.27	14.1	4.0	1.1	75	1.1	1.5	0.3	47	0.71	0.116	4
1283693	Soil	2.4	27.4	17.6	151	1.3	36.4	7.9	202	1.75	9.8	6.9	1.5	90	0.8	1.4	0.3	44	0.59	0.093	4
1283694	Soil	3.2	15.5	10.0	47	0.9	12.5	1.6	31	1.14	6.7	3.1	0.6	19	0.3	0.7	0.2	36	0.04	0.041	3
1283695	Soil	3.2	18.3	11.1	81	1.2	18.2	4.5	70	2.25	17.0	1.1	1.0	9	0.3	1.3	0.2	51	0.01	0.054	5
1283696	Soil	3.1	13.5	14.4	78	1.4	16.2	4.5	129	2.68	21.7	1.3	1.7	13	0.2	1.7	0.3	57	0.02	0.092	7
1283697	Soil	2.6	7.1	10.2	32	1.0	5.1	1.2	24	1.08	5.1	2.1	0.2	13	0.2	1.5	0.2	49	<0.01	0.039	10
1283698	Soil	3.7	17.7	17.0	114	0.4	18.0	4.7	136	3.68	26.1	1.1	2.0	18	0.6	2.2	0.3	69	0.02	0.119	8
1283699	Soil	5.2	10.7	11.5	37	1.9	7.0	2.9	61	2.22	13.0	1.9	1.0	17	0.4	2.9	0.2	57	0.04	0.067	9
1283700	Soil	3.1	12.4	12.3	51	1.0	9.6	2.7	46	1.88	12.5	3.5	1.7	13	0.1	1.3	0.2	59	0.02	0.048	9
1283701	Soil	2.7	17.2	14.7	83	0.5	15.7	3.7	85	2.90	25.2	1.0	0.6	20	0.3	1.4	0.3	57	0.02	0.125	7
1283702	Soil	2.7	38.0	18.8	110	0.8	37.0	5.9	138	1.93	13.4	4.9	1.4	82	0.8	1.2	0.3	44	0.70	0.075	5
1283703	Soil	3.0	36.1	14.5	113	0.7	36.7	6.5	211	1.89	12.8	5.7	1.2	65	0.8	1.9	0.2	45	0.87	0.087	5
1283704	Soil	3.8	34.5	18.8	104	0.9	28.2	8.3	226	1.88	13.8	2.4	1.1	61	1.1	1.4	0.2	47	0.87	0.088	4
1283705	Soil	4.5	38.4	19.2	80	0.6	25.4	4.4	110	1.61	14.6	1.7	1.0	52	0.6	1.7	0.2	47	0.49	0.059	4
1283706	Soil	3.4	35.4	18.9	112	0.9	30.6	5.5	169	1.71	12.3	2.2	1.2	71	0.8	1.5	0.2	43	0.89	0.077	4
1283707	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283708	Soil	3.5	33.9	14.4	140	0.9	36.5	8.7	267	2.35	14.1	4.3	1.8	75	0.8	1.4	0.2	49	0.59	0.080	6
1283709	Soil	2.4	27.9	11.6	121	0.8	31.1	7.7	526	2.64	12.7	5.6	1.4	91	1.2	1.4	0.2	42	0.74	0.087	5
1283710	Soil	2.3	34.6	28.5	149	0.1	35.8	17.9	440	3.96	15.9	1.2	1.5	23	0.1	1.3	0.3	29	0.02	0.089	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283681	Soil	12	0.02	1215	0.002	2	0.51	0.009	0.07	<0.1	0.05	0.9	0.4	0.06	2	2.6	<0.2
1283682	Soil	6	0.02	490	0.003	<1	0.56	0.018	0.04	<0.1	0.09	0.6	0.2	<0.05	2	1.2	<0.2
1283683	Soil	9	0.02	396	0.004	<1	0.25	0.008	0.03	<0.1	0.05	0.4	0.2	<0.05	2	2.5	<0.2
1283684	Soil	5	0.02	248	0.003	<1	0.28	0.016	0.03	<0.1	0.08	0.3	0.2	<0.05	2	0.6	<0.2
1283685	Soil	10	0.05	328	0.005	2	0.28	0.003	0.04	<0.1	0.58	0.7	0.6	<0.05	2	1.4	<0.2
1283686	Soil	8	0.04	449	0.002	<1	0.35	0.010	0.05	<0.1	0.47	0.8	0.5	<0.05	2	1.1	<0.2
1283687	Soil	12	0.09	197	0.002	3	0.67	0.004	0.06	<0.1	0.04	1.3	0.1	<0.05	3	<0.5	<0.2
1283688	Soil	23	0.32	485	0.004	2	1.20	0.005	0.07	<0.1	0.03	1.6	0.1	<0.05	5	<0.5	<0.2
1283689	Soil	18	0.29	1672	0.003	7	1.48	0.015	0.09	<0.1	0.14	3.9	0.4	0.10	3	1.1	<0.2
1283690	Soil	12	0.13	766	0.005	6	0.52	0.006	0.07	<0.1	0.84	1.5	0.5	0.12	2	2.1	<0.2
1283691	Soil	15	0.14	917	0.004	5	0.72	0.008	0.08	<0.1	0.63	2.3	0.7	0.10	3	2.7	<0.2
1283692	Soil	14	0.15	1446	0.001	3	0.80	0.004	0.08	<0.1	0.36	3.2	0.2	0.08	2	2.8	<0.2
1283693	Soil	15	0.18	1678	0.002	6	0.90	0.007	0.10	<0.1	0.37	3.2	0.3	0.09	3	2.1	<0.2
1283694	Soil	11	0.05	472	0.004	3	0.82	0.017	0.07	0.1	0.08	1.3	0.2	<0.05	3	<0.5	<0.2
1283695	Soil	11	0.08	252	0.003	2	0.85	0.005	0.04	<0.1	0.06	1.4	0.1	<0.05	3	0.8	<0.2
1283696	Soil	15	0.13	199	0.007	2	0.94	0.005	0.06	0.1	0.04	1.4	0.2	<0.05	4	1.3	<0.2
1283697	Soil	10	0.02	277	0.007	3	0.40	0.005	0.06	0.1	<0.01	0.2	0.1	<0.05	3	<0.5	<0.2
1283698	Soil	21	0.15	326	0.005	2	1.27	0.005	0.06	0.1	0.03	1.8	0.2	<0.05	5	1.5	<0.2
1283699	Soil	12	0.10	373	0.007	2	0.85	0.009	0.05	0.2	0.05	0.8	0.3	<0.05	4	1.9	<0.2
1283700	Soil	12	0.05	388	0.004	1	0.94	0.006	0.04	0.2	0.04	1.1	0.2	<0.05	4	0.6	<0.2
1283701	Soil	15	0.10	307	0.004	2	0.88	0.005	0.06	0.1	0.03	1.0	0.1	<0.05	4	1.4	<0.2
1283702	Soil	15	0.22	1123	0.002	8	0.92	0.008	0.09	<0.1	0.34	2.8	0.3	<0.05	3	1.8	<0.2
1283703	Soil	14	0.23	1066	0.003	5	0.99	0.011	0.09	<0.1	0.24	2.6	0.2	0.06	3	2.6	<0.2
1283704	Soil	14	0.21	919	0.001	3	0.91	0.009	0.07	<0.1	0.36	2.4	0.3	0.08	3	2.9	<0.2
1283705	Soil	11	0.14	861	0.001	4	0.61	0.007	0.08	<0.1	0.38	2.0	0.4	0.08	2	2.5	<0.2
1283706	Soil	14	0.21	933	0.001	5	0.88	0.008	0.08	<0.1	0.42	2.4	0.4	0.08	3	2.6	<0.2
1283707	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283708	Soil	18	0.25	1068	0.001	4	1.11	0.009	0.09	<0.1	0.30	3.2	0.2	0.06	3	2.2	<0.2
1283709	Soil	15	0.18	980	0.003	6	1.09	0.016	0.08	<0.1	0.26	3.1	0.2	0.13	3	1.8	<0.2
1283710	Soil	23	0.30	100	0.004	2	1.18	0.004	0.10	<0.1	0.04	2.7	0.2	<0.05	4	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283711	Soil	2.9	26.4	28.8	134	0.1	25.4	11.1	377	4.06	16.5	<0.5	0.7	13	<0.1	1.7	0.3	36	0.02	0.096	5
1283712	Soil	3.5	29.4	40.8	121	0.2	20.3	9.3	336	3.26	14.1	0.6	0.5	33	0.1	1.1	0.3	28	0.03	0.100	4
1283713	Soil	2.3	32.7	25.2	76	0.2	18.7	9.2	225	3.03	12.5	<0.5	1.1	21	<0.1	0.9	0.2	24	0.02	0.091	3
1283714	Soil	1.8	28.8	24.6	119	0.1	32.3	28.4	714	3.22	18.2	1.2	1.0	20	<0.1	1.4	0.3	27	0.03	0.083	6
1283715	Soil	3.0	32.0	34.4	119	0.2	28.5	28.7	1190	4.03	26.8	2.9	0.7	12	0.1	1.5	0.4	41	0.03	0.173	5
1283716	Soil	2.1	18.6	12.3	80	<0.1	17.4	8.5	289	2.57	12.0	2.2	0.3	10	0.1	1.0	0.2	34	0.04	0.084	6
1283717	Soil	2.6	18.1	14.3	55	<0.1	13.3	5.7	277	2.82	10.3	1.7	0.2	10	0.1	1.1	0.2	41	0.04	0.087	6
1283718	Soil	1.7	25.7	19.1	78	<0.1	18.2	11.8	572	2.74	12.7	1.0	0.3	11	0.3	0.9	0.2	28	0.03	0.101	4
1283719	Soil	2.1	24.5	14.9	64	<0.1	16.3	7.7	238	3.57	10.8	1.2	1.0	12	0.1	0.9	0.3	41	0.01	0.074	5
1283720	Soil	1.2	48.4	19.0	188	<0.1	67.8	55.2	797	3.59	15.3	<0.5	2.9	20	0.2	0.9	0.3	24	0.03	0.049	4
1283721	Soil	1.5	37.1	22.3	159	<0.1	48.8	23.3	359	3.63	15.7	0.6	1.5	26	0.1	0.8	0.3	27	0.02	0.056	4
1283722	Soil	2.0	34.6	22.4	128	0.1	35.7	20.0	597	3.16	16.6	0.9	1.7	21	0.2	0.9	0.3	28	0.02	0.084	5
1283723	Soil	0.7	12.9	6.0	26	0.1	6.2	3.5	210	1.42	3.8	0.7	0.1	6	0.1	0.3	0.1	17	0.02	0.079	2
1283724	Soil	0.8	13.5	12.1	58	<0.1	12.3	6.2	138	1.46	7.3	0.8	0.2	8	<0.1	0.4	0.2	18	0.02	0.050	2
1283725	Soil	2.1	32.6	20.5	125	<0.1	22.0	13.0	461	4.93	15.6	1.0	0.5	7	0.1	1.0	0.3	39	0.03	0.188	4
1283726	Soil	2.1	30.9	28.5	154	<0.1	27.5	15.5	308	4.24	21.1	2.8	0.6	8	0.2	1.1	0.4	28	0.01	0.112	4
1283727	Soil	1.7	18.6	12.2	77	0.1	11.6	6.5	136	2.30	10.5	2.0	0.2	6	0.2	0.8	0.3	42	0.03	0.134	3
1283728	Soil	1.2	19.0	14.0	65	<0.1	17.0	7.5	139	2.24	8.4	<0.5	0.2	6	0.2	0.6	0.2	28	0.02	0.076	2
1283729	Soil	2.0	32.3	25.9	140	<0.1	39.6	17.8	332	3.72	19.2	1.4	0.8	12	0.1	1.1	0.3	28	0.02	0.076	2
1283730	Soil	1.1	17.4	13.1	76	<0.1	21.2	9.9	178	2.03	10.2	1.9	0.5	6	0.1	0.5	0.2	18	0.01	0.040	2
1283731	Soil	1.6	28.0	19.1	131	0.1	42.5	18.7	353	3.23	14.4	<0.5	1.3	13	0.3	1.0	0.3	28	0.07	0.072	3
1283732	Soil	0.7	13.2	12.0	38	0.2	14.8	6.1	113	1.16	7.6	1.4	0.3	9	<0.1	0.4	0.2	16	0.03	0.048	1
1283733	Soil	1.7	25.8	21.2	103	<0.1	30.8	17.3	524	3.38	14.4	1.6	0.7	9	0.1	1.0	0.3	32	0.02	0.088	3
1283734	Soil	1.1	24.2	17.1	95	<0.1	31.4	15.1	392	3.20	12.6	1.8	0.9	6	<0.1	1.0	0.3	26	0.02	0.067	2
1283735	Soil	1.2	23.4	17.8	95	<0.1	25.1	15.7	380	3.08	11.4	<0.5	0.8	5	0.1	0.8	0.3	29	0.01	0.047	2
1283736	Soil	1.6	29.1	15.7	111	<0.1	34.9	15.5	239	3.53	15.3	1.0	1.0	4	<0.1	0.9	0.3	35	<0.01	0.050	3
1283737	Soil	0.5	6.3	3.0	16	0.2	6.2	2.6	133	0.49	2.6	<0.5	0.1	7	<0.1	0.2	<0.1	15	0.03	0.094	1
1283738	Soil	1.4	19.0	10.8	83	<0.1	34.8	12.4	269	2.99	21.9	<0.5	0.5	5	<0.1	3.0	0.2	26	<0.01	0.059	2
1283739	Soil	1.8	21.9	18.3	91	0.1	34.3	12.2	225	3.52	18.2	1.8	1.0	6	<0.1	2.4	0.3	28	<0.01	0.058	2
1283740	Soil	1.7	17.3	10.8	67	<0.1	22.4	9.7	144	2.06	14.8	<0.5	0.4	7	<0.1	1.4	0.2	31	<0.01	0.047	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283711	Soil	20	0.11	57	0.005	3	0.84	0.003	0.07	<0.1	0.05	1.5	0.2	<0.05	4	<0.5	<0.2
1283712	Soil	19	0.19	78	0.005	2	1.04	0.010	0.09	<0.1	0.05	1.7	0.2	0.08	4	<0.5	<0.2
1283713	Soil	17	0.16	71	0.003	2	0.94	0.009	0.08	<0.1	0.06	2.7	0.3	<0.05	3	<0.5	<0.2
1283714	Soil	20	0.28	77	0.005	2	1.08	0.009	0.08	<0.1	0.03	2.3	0.3	<0.05	4	<0.5	<0.2
1283715	Soil	27	0.24	84	0.006	3	1.22	0.009	0.09	<0.1	0.05	2.1	0.4	<0.05	5	0.8	<0.2
1283716	Soil	17	0.15	59	0.007	2	0.81	0.009	0.05	0.1	0.02	0.6	0.1	<0.05	3	<0.5	<0.2
1283717	Soil	23	0.15	68	0.008	2	0.87	0.012	0.06	<0.1	0.05	0.4	0.1	0.07	4	<0.5	<0.2
1283718	Soil	20	0.17	89	0.005	3	1.07	0.013	0.07	<0.1	0.03	0.8	0.2	<0.05	4	<0.5	<0.2
1283719	Soil	22	0.13	91	0.005	2	1.08	0.003	0.10	<0.1	0.04	1.7	0.2	<0.05	6	<0.5	<0.2
1283720	Soil	25	0.52	213	0.002	2	1.42	0.003	0.10	<0.1	0.04	3.9	0.4	<0.05	4	<0.5	<0.2
1283721	Soil	23	0.28	79	0.002	2	1.18	0.005	0.08	<0.1	0.02	3.2	0.3	<0.05	4	0.5	<0.2
1283722	Soil	23	0.33	96	0.003	2	1.29	0.005	0.10	<0.1	0.01	2.6	0.2	<0.05	4	<0.5	<0.2
1283723	Soil	11	0.03	36	0.004	2	0.59	0.011	0.03	<0.1	0.04	0.2	<0.1	0.07	2	0.6	<0.2
1283724	Soil	7	0.05	37	0.005	2	0.61	0.011	0.04	<0.1	0.02	0.5	<0.1	<0.05	2	<0.5	<0.2
1283725	Soil	29	0.13	106	0.008	3	1.20	0.003	0.04	<0.1	0.05	0.6	0.2	<0.05	5	0.9	<0.2
1283726	Soil	21	0.14	57	0.004	1	0.96	0.003	0.05	<0.1	0.02	1.2	0.2	<0.05	3	0.7	<0.2
1283727	Soil	12	0.05	60	0.007	3	0.55	0.007	0.04	<0.1	0.01	0.6	0.1	<0.05	3	1.4	<0.2
1283728	Soil	14	0.14	70	0.004	<1	0.74	0.008	0.04	<0.1	0.01	0.5	0.1	<0.05	3	<0.5	<0.2
1283729	Soil	17	0.15	98	0.002	<1	0.80	0.003	0.05	<0.1	0.04	2.5	0.2	<0.05	3	<0.5	<0.2
1283730	Soil	8	0.05	53	0.002	<1	0.51	0.009	0.04	<0.1	0.03	1.4	0.1	<0.05	2	0.5	<0.2
1283731	Soil	18	0.21	110	0.002	1	0.90	0.003	0.06	<0.1	0.04	2.9	0.1	<0.05	2	0.8	<0.2
1283732	Soil	6	0.04	86	0.002	<1	0.47	0.013	0.04	<0.1	0.04	0.7	0.1	<0.05	2	0.7	<0.2
1283733	Soil	19	0.16	49	0.003	1	0.84	0.004	0.04	<0.1	0.03	1.3	0.1	<0.05	3	<0.5	<0.2
1283734	Soil	16	0.23	57	0.003	1	0.89	0.005	0.04	<0.1	0.01	1.9	0.1	<0.05	3	<0.5	<0.2
1283735	Soil	15	0.16	67	0.003	2	0.78	0.005	0.05	<0.1	0.01	1.8	0.1	<0.05	3	<0.5	<0.2
1283736	Soil	13	0.08	59	0.002	2	0.61	0.003	0.04	<0.1	<0.01	2.6	0.1	<0.05	3	<0.5	<0.2
1283737	Soil	5	0.01	72	0.005	1	0.21	0.013	0.04	<0.1	0.01	0.4	<0.1	<0.05	<1	<0.5	<0.2
1283738	Soil	10	0.02	34	0.001	2	0.29	0.004	0.03	<0.1	0.02	2.1	<0.1	<0.05	2	<0.5	<0.2
1283739	Soil	13	0.05	46	0.002	<1	0.49	0.003	0.04	<0.1	0.02	2.3	0.1	<0.05	2	<0.5	<0.2
1283740	Soil	8	0.02	74	0.003	2	0.35	0.004	0.03	<0.1	<0.01	1.2	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283741	Soil	2.1	22.7	25.9	89	<0.1	30.2	14.1	367	4.25	26.8	1.9	1.5	11	<0.1	3.9	0.3	27	0.01	0.082	3
1283742	Soil	1.2	11.8	7.6	42	0.1	14.6	5.8	104	1.39	9.0	<0.5	0.1	4	<0.1	1.4	0.1	28	0.02	0.068	2
1283743	Soil	2.2	17.3	13.3	55	<0.1	16.0	6.3	203	2.64	14.3	1.1	0.3	9	<0.1	1.5	0.2	39	0.03	0.079	6
1283744	Soil	1.9	27.8	19.8	104	<0.1	38.9	18.7	456	3.41	26.7	1.6	1.8	10	0.1	2.7	0.3	31	0.02	0.058	4
1283745	Soil	2.1	22.6	18.9	74	0.3	21.6	12.4	498	4.14	14.5	0.6	0.4	11	0.1	1.6	0.3	45	0.04	0.121	6
1283746	Soil	1.2	14.6	11.0	59	0.1	17.2	8.0	188	2.41	14.5	0.6	0.2	5	<0.1	1.3	0.2	33	0.02	0.060	3
1283747	Soil	1.6	24.8	18.5	117	0.1	44.0	22.2	620	3.83	24.8	1.9	1.2	7	0.2	2.0	0.3	35	0.03	0.075	6
1283748	Soil	1.5	12.5	8.9	44	<0.1	9.1	4.3	70	1.46	8.7	<0.5	0.3	7	<0.1	0.7	0.2	47	0.01	0.064	3
1283749	Soil	0.9	15.6	10.7	34	0.2	8.2	2.3	34	0.84	6.8	1.2	0.4	7	<0.1	0.4	0.2	50	0.01	0.056	4
1283750	Soil	2.9	20.3	18.5	60	0.2	14.2	5.6	313	3.43	15.2	4.5	0.2	13	0.2	1.3	0.4	62	0.06	0.082	9
1283751	Soil	4.5	13.1	7.9	60	<0.1	13.2	4.0	71	1.97	16.8	1.3	1.5	6	<0.1	1.7	0.2	73	0.02	0.018	7
1283752	Soil	3.2	19.0	10.8	73	0.3	25.5	5.2	118	2.61	10.8	4.4	1.9	5	0.2	1.2	0.2	62	0.01	0.019	7
1283753	Soil	0.4	6.2	1.6	7	0.2	1.4	0.6	14	0.28	1.1	1.1	<0.1	7	<0.1	0.1	<0.1	24	0.03	0.022	1
1283754	Soil	1.5	32.9	1.6	18	0.2	16.5	0.7	11	0.29	<0.5	3.4	0.3	150	0.3	0.7	<0.1	17	1.13	0.031	2
1283755	Soil	3.4	13.5	6.1	57	0.4	9.3	1.8	28	0.90	8.7	<0.5	0.2	6	0.5	0.9	0.1	52	0.01	0.040	6
1283756	Soil	2.5	8.6	8.6	52	0.3	9.4	2.3	53	1.29	10.2	<0.5	0.2	7	0.3	1.1	0.2	54	0.02	0.046	9
1283757	Soil	1.5	8.9	3.2	22	0.4	4.9	1.4	22	0.62	5.0	<0.5	0.2	4	0.2	0.5	<0.1	29	<0.01	0.020	8
1283758	Soil	2.4	10.7	6.3	43	0.2	8.8	2.4	43	1.10	11.7	1.9	0.3	6	0.1	1.2	0.1	46	0.02	0.035	9
1283759	Soil	0.6	2.6	3.8	14	0.2	1.6	0.5	18	0.29	1.8	1.0	0.4	5	<0.1	0.2	0.3	19	0.02	0.013	10
1283760	Soil	1.8	8.0	7.3	39	0.2	6.6	2.1	60	0.96	9.8	1.6	0.4	7	0.2	0.9	0.3	44	0.02	0.031	12
1283761	Soil	1.7	7.4	4.3	37	0.2	6.5	1.7	32	0.76	7.2	0.5	0.2	5	0.1	0.7	0.2	32	0.01	0.031	6
1283762	Soil	0.4	3.2	2.0	10	0.2	1.3	0.4	13	0.27	1.0	1.7	0.1	3	<0.1	0.2	0.1	13	0.01	0.017	7
1283763	Soil	2.6	11.1	6.2	52	0.4	10.0	2.7	56	1.39	11.0	4.1	0.2	6	0.2	1.2	0.2	50	0.01	0.030	7
1283764	Soil	2.8	6.8	11.9	54	0.4	9.1	2.5	99	2.08	15.5	0.5	1.3	6	0.4	1.3	0.3	70	0.03	0.059	10
1283765	Soil	2.1	7.7	7.7	42	0.3	7.4	2.2	57	1.11	10.8	<0.5	0.3	6	0.1	1.0	0.2	47	0.02	0.036	9
1283766	Soil	1.7	6.7	6.3	44	0.3	7.3	2.0	60	1.14	6.6	1.0	0.5	5	0.5	0.8	0.2	51	0.02	0.025	8
1283767	Soil	1.6	5.9	7.1	42	0.4	6.5	1.8	56	1.11	7.3	0.7	1.0	5	0.3	0.9	0.2	50	0.01	0.023	10
1283768	Soil	1.5	8.1	3.8	31	0.4	5.8	1.5	34	0.83	5.5	<0.5	<0.1	5	0.3	0.7	0.1	32	0.02	0.023	5
1283769	Soil	1.8	7.1	5.4	32	0.2	5.4	1.6	34	0.74	8.3	1.6	0.2	6	<0.1	0.7	0.2	33	0.02	0.026	9
1283770	Soil	2.3	9.1	5.9	43	0.4	7.5	2.1	40	1.05	8.3	0.8	0.3	6	<0.1	0.9	0.2	45	0.01	0.029	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283741	Soil	16	0.04	88	0.003	<1	0.42	0.003	0.04	<0.1	0.04	2.5	0.2	<0.05	2	<0.5	<0.2
1283742	Soil	7	0.02	36	0.006	2	0.38	0.010	0.03	<0.1	<0.01	0.5	0.1	<0.05	3	<0.5	<0.2
1283743	Soil	16	0.08	60	0.008	<1	0.63	0.007	0.04	<0.1	0.02	0.6	0.1	<0.05	3	0.6	<0.2
1283744	Soil	19	0.17	75	0.003	<1	0.81	0.003	0.05	<0.1	0.05	2.6	0.2	<0.05	2	<0.5	<0.2
1283745	Soil	26	0.14	115	0.009	1	1.03	0.006	0.06	0.1	0.05	1.2	0.2	<0.05	4	0.7	<0.2
1283746	Soil	13	0.06	50	0.004	<1	0.55	0.007	0.03	<0.1	0.01	0.6	0.1	<0.05	3	<0.5	<0.2
1283747	Soil	18	0.14	89	0.006	1	0.73	0.005	0.04	<0.1	0.05	2.3	0.1	<0.05	2	<0.5	<0.2
1283748	Soil	8	0.02	100	0.002	<1	0.43	0.006	0.03	<0.1	0.01	0.3	<0.1	<0.05	3	<0.5	<0.2
1283749	Soil	8	0.02	171	0.002	2	0.51	0.005	0.03	<0.1	<0.01	0.6	<0.1	<0.05	3	<0.5	<0.2
1283750	Soil	26	0.14	82	0.013	<1	0.94	0.007	0.05	0.2	0.03	0.7	0.1	<0.05	4	0.8	<0.2
1283751	Soil	9	0.05	127	0.003	<1	0.69	0.003	0.03	0.1	<0.01	1.2	0.1	<0.05	3	0.6	<0.2
1283752	Soil	20	0.17	338	0.002	<1	1.05	0.003	0.03	<0.1	0.02	1.4	0.1	<0.05	4	0.8	<0.2
1283753	Soil	3	0.01	31	0.005	<1	0.17	0.020	0.02	<0.1	0.01	0.1	<0.1	<0.05	<1	<0.5	<0.2
1283754	Soil	4	0.11	296	0.008	<1	0.29	0.013	0.01	<0.1	0.06	0.9	<0.1	0.11	<1	2.0	<0.2
1283755	Soil	6	0.02	148	0.007	1	0.42	0.004	0.03	0.1	<0.01	0.3	0.1	<0.05	3	<0.5	<0.2
1283756	Soil	8	0.04	109	0.007	<1	0.48	0.003	0.03	0.2	0.01	0.3	0.1	<0.05	4	<0.5	<0.2
1283757	Soil	4	0.01	99	0.009	<1	0.34	0.009	0.02	0.1	0.03	0.2	<0.1	<0.05	3	0.6	<0.2
1283758	Soil	5	0.02	98	0.007	<1	0.33	0.004	0.02	0.2	<0.01	0.3	0.1	<0.05	4	0.7	<0.2
1283759	Soil	4	0.02	83	0.007	2	0.35	0.006	0.02	0.1	0.02	0.2	0.1	<0.05	3	<0.5	<0.2
1283760	Soil	7	0.03	117	0.013	2	0.46	0.004	0.03	0.3	0.01	0.3	0.2	<0.05	4	0.8	<0.2
1283761	Soil	4	0.02	104	0.004	2	0.35	0.007	0.02	0.2	0.01	0.2	0.1	<0.05	3	<0.5	<0.2
1283762	Soil	3	0.01	66	0.006	1	0.24	0.012	0.02	0.1	0.03	<0.1	<0.1	<0.05	2	<0.5	<0.2
1283763	Soil	6	0.03	141	0.007	1	0.46	0.006	0.02	0.2	0.02	0.4	0.1	<0.05	3	0.5	<0.2
1283764	Soil	11	0.08	162	0.012	2	0.70	0.004	0.03	0.2	0.02	0.8	0.1	<0.05	5	<0.5	<0.2
1283765	Soil	7	0.04	77	0.007	2	0.39	0.006	0.03	0.2	0.01	0.4	0.1	<0.05	4	<0.5	<0.2
1283766	Soil	7	0.04	212	0.010	<1	0.59	0.006	0.02	0.2	0.02	0.4	0.1	<0.05	4	<0.5	<0.2
1283767	Soil	7	0.04	120	0.010	<1	0.52	0.004	0.02	0.2	0.01	0.6	0.1	<0.05	4	<0.5	<0.2
1283768	Soil	4	0.02	101	0.007	1	0.34	0.011	0.02	0.1	0.02	0.2	<0.1	<0.05	3	<0.5	<0.2
1283769	Soil	5	0.03	85	0.006	2	0.41	0.005	0.03	0.2	0.02	0.2	0.1	<0.05	4	0.6	<0.2
1283770	Soil	6	0.03	109	0.006	3	0.50	0.004	0.03	0.2	0.01	0.4	0.2	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283771	Soil	3.4	8.8	6.8	59	0.2	8.9	2.1	268	1.51	11.3	1.4	0.2	8	0.2	1.4	0.2	56	0.01	0.077	5
1283772	Soil	2.7	10.9	8.1	57	0.5	10.5	2.7	62	1.48	12.3	0.6	0.3	6	0.2	1.3	0.2	58	0.01	0.054	8
1283773	Soil	2.5	11.2	9.6	59	0.4	10.7	3.0	79	1.81	15.4	0.5	0.4	6	0.2	1.3	0.2	56	0.02	0.118	6
1283774	Soil	3.0	12.4	12.9	68	0.9	11.9	3.0	119	2.53	21.8	0.7	0.2	8	0.2	1.5	0.3	87	0.03	0.134	7
1283775	Soil	2.0	9.3	6.6	43	0.3	6.5	1.6	37	1.11	9.3	0.8	0.3	7	<0.1	0.9	0.1	46	0.02	0.034	7
1283776	Soil	2.2	14.4	3.4	53	0.1	8.1	2.0	38	1.01	9.0	<0.5	<0.1	5	0.3	0.9	<0.1	40	0.03	0.035	6
1283777	Soil	0.5	14.4	2.5	22	0.2	8.5	1.0	44	0.39	<0.5	<0.5	0.3	52	0.7	0.6	0.1	4	0.53	0.045	2
1283778	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283779	Soil	3.9	20.6	14.5	106	1.2	19.6	6.1	213	4.00	24.5	8.2	2.8	11	0.2	2.4	0.2	67	0.04	0.107	8
1283780	Soil	5.3	15.0	36.6	17	0.8	5.6	0.9	23	1.29	9.8	3.3	0.2	24	<0.1	2.0	0.3	41	0.01	0.053	3
1283781	Soil	3.0	24.7	14.6	23	0.3	6.9	1.8	58	1.06	11.4	1.8	0.3	24	<0.1	1.6	0.1	30	0.07	0.073	3
1283782	Soil	29.6	166.0	60.1	33	9.3	11.0	2.1	70	8.33	78.3	6.1	1.9	244	0.2	9.0	0.3	432	0.03	0.447	6
1283783	Soil	3.7	14.3	36.5	35	0.4	8.4	1.1	38	1.67	16.6	<0.5	1.4	59	<0.1	1.8	0.2	27	0.02	0.044	3
1283784	Soil	1.8	41.3	19.5	117	0.2	45.4	27.5	809	2.91	19.5	1.7	1.9	34	0.2	1.2	0.4	20	0.22	0.095	6
1283785	Soil	1.4	34.2	19.0	137	0.1	37.6	23.9	694	2.74	18.5	1.1	1.0	21	0.2	1.1	0.4	16	0.26	0.091	6
1283786	Soil	1.8	27.8	20.6	162	<0.1	32.0	19.5	486	2.64	17.2	<0.5	0.6	22	0.3	1.1	0.3	17	0.16	0.096	5
1283787	Soil	2.9	27.9	28.2	329	<0.1	44.4	19.8	347	2.92	15.3	<0.5	0.7	22	0.4	1.1	0.3	13	0.12	0.069	4
1283788	Soil	1.7	25.4	28.0	149	<0.1	35.4	17.4	412	2.59	13.2	<0.5	0.7	16	0.1	0.7	0.3	11	0.07	0.068	4
1283789	Soil	1.6	30.5	25.6	146	<0.1	40.1	20.2	561	2.84	14.0	<0.5	0.7	13	0.1	0.8	0.4	13	0.08	0.066	3
1283790	Soil	0.8	9.4	5.7	36	<0.1	5.3	3.5	125	0.95	4.0	0.9	0.2	6	<0.1	0.3	0.1	10	0.04	0.072	2
1283791	Soil	1.1	16.1	13.3	75	<0.1	12.5	7.7	362	2.42	8.8	<0.5	0.3	6	<0.1	0.6	0.2	18	0.02	0.107	2
1283792	Soil	1.6	33.8	26.1	178	0.1	40.2	35.6	1074	3.00	17.0	1.3	0.9	12	0.1	0.9	0.3	23	0.04	0.078	4
1283793	Soil	1.1	27.5	22.1	127	<0.1	27.0	21.0	586	2.17	12.1	1.1	0.8	9	<0.1	0.7	0.3	14	0.05	0.051	3
1283794	Soil	1.4	23.1	15.5	125	<0.1	19.4	11.1	250	2.83	13.1	<0.5	0.2	8	<0.1	0.8	0.3	18	0.03	0.125	3
1283795	Soil	2.3	27.1	23.4	119	0.1	30.6	15.2	528	4.66	19.0	1.6	1.0	17	0.2	1.3	0.3	41	0.05	0.118	9
1283796	Soil	2.4	27.2	23.5	120	<0.1	37.0	29.2	934	3.77	17.0	0.9	1.5	19	0.2	1.1	0.4	43	0.04	0.098	8
1283797	Soil	1.8	30.3	24.6	105	0.1	29.9	16.5	395	2.79	13.5	<0.5	1.2	17	0.2	0.8	0.3	26	0.03	0.065	5
1283798	Soil	1.4	26.2	16.6	103	0.1	27.5	17.1	441	2.64	12.6	2.1	1.0	15	0.1	0.7	0.2	27	0.05	0.082	4
1283799	Soil	1.8	34.2	20.7	166	0.1	54.0	44.6	821	3.96	17.9	<0.5	1.6	21	0.2	0.9	0.3	34	0.03	0.093	6
1283800	Soil	1.8	29.6	23.7	134	0.1	38.0	21.6	447	3.23	14.5	1.7	1.5	19	0.2	0.7	0.3	29	0.02	0.066	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283771	Soil	10	0.04	120	0.004	1	0.57	0.004	0.05	0.2	0.07	0.4	0.1	<0.05	4	0.8	<0.2
1283772	Soil	8	0.05	128	0.007	2	0.55	0.003	0.03	0.2	0.04	0.5	0.1	<0.05	4	0.7	<0.2
1283773	Soil	8	0.05	149	0.005	2	0.66	0.004	0.04	0.2	<0.01	0.5	0.2	<0.05	5	0.8	<0.2
1283774	Soil	14	0.08	162	0.006	1	0.82	0.005	0.04	0.2	0.04	0.6	0.2	<0.05	5	1.1	<0.2
1283775	Soil	7	0.03	119	0.005	1	0.55	0.008	0.04	0.2	0.03	0.5	0.1	<0.05	4	<0.5	<0.2
1283776	Soil	5	0.02	128	0.004	2	0.30	0.007	0.03	0.1	0.04	0.3	<0.1	<0.05	3	<0.5	<0.2
1283777	Soil	4	0.06	856	0.009	2	0.28	0.019	0.02	<0.1	0.19	0.9	<0.1	0.14	<1	3.4	<0.2
1283778	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283779	Soil	25	0.25	194	0.012	3	1.83	0.009	0.06	0.3	0.14	1.8	0.2	0.06	5	1.2	<0.2
1283780	Soil	12	0.02	133	0.002	<1	0.29	0.007	0.10	<0.1	0.04	1.1	0.2	0.18	2	2.9	<0.2
1283781	Soil	9	0.07	70	0.011	1	0.40	0.019	0.05	<0.1	0.05	0.8	<0.1	<0.05	2	1.9	<0.2
1283782	Soil	91	0.07	319	0.008	2	0.59	0.015	0.37	<0.1	0.39	11.4	1.5	0.73	8	17.3	<0.2
1283783	Soil	7	0.01	262	<0.001	2	0.24	0.007	0.12	<0.1	0.05	3.9	0.7	0.20	1	2.0	<0.2
1283784	Soil	13	0.08	113	0.002	1	0.53	0.006	0.07	<0.1	0.07	5.4	0.2	<0.05	2	0.8	<0.2
1283785	Soil	10	0.06	139	0.002	2	0.48	0.005	0.07	<0.1	0.08	5.2	0.2	<0.05	2	<0.5	<0.2
1283786	Soil	9	0.05	104	0.001	3	0.44	0.004	0.08	<0.1	0.07	2.9	0.2	0.06	2	<0.5	<0.2
1283787	Soil	9	0.06	100	<0.001	1	0.42	0.003	0.06	<0.1	0.06	3.6	0.1	<0.05	1	<0.5	<0.2
1283788	Soil	9	0.05	90	<0.001	<1	0.48	0.003	0.06	<0.1	0.04	3.6	0.2	<0.05	1	<0.5	<0.2
1283789	Soil	9	0.06	94	0.001	<1	0.46	0.002	0.06	<0.1	0.05	3.8	0.2	<0.05	1	<0.5	<0.2
1283790	Soil	7	0.04	34	0.004	<1	0.57	0.017	0.03	<0.1	0.03	0.4	<0.1	<0.05	2	<0.5	<0.2
1283791	Soil	12	0.07	35	0.002	1	0.59	0.010	0.06	<0.1	0.03	0.5	0.1	<0.05	3	<0.5	<0.2
1283792	Soil	20	0.34	138	0.003	2	1.13	0.009	0.09	<0.1	0.04	2.9	0.3	<0.05	3	<0.5	<0.2
1283793	Soil	8	0.08	65	0.003	<1	0.63	0.011	0.06	<0.1	0.02	2.3	0.2	<0.05	2	<0.5	<0.2
1283794	Soil	12	0.03	54	0.002	1	0.53	0.005	0.06	<0.1	0.04	0.6	0.1	0.06	2	0.5	<0.2
1283795	Soil	34	0.27	129	0.010	4	1.48	0.005	0.10	<0.1	0.04	1.9	0.2	0.06	4	1.1	<0.2
1283796	Soil	29	0.28	163	0.007	3	1.37	0.008	0.10	<0.1	0.02	2.9	0.3	<0.05	5	0.6	<0.2
1283797	Soil	20	0.24	232	0.003	2	1.27	0.014	0.10	<0.1	0.02	3.5	0.3	<0.05	4	0.7	<0.2
1283798	Soil	21	0.24	147	0.003	2	1.19	0.014	0.08	<0.1	0.03	2.6	0.3	0.06	4	0.7	<0.2
1283799	Soil	27	0.27	118	0.004	2	1.33	0.010	0.08	<0.1	0.03	3.4	0.3	0.09	4	1.0	<0.2
1283800	Soil	22	0.23	190	0.004	2	1.22	0.011	0.10	<0.1	0.03	3.6	0.3	<0.05	4	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283801	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283802	Soil	0.9	29.3	6.5	51	1.8	17.8	2.9	137	0.88	4.5	10.0	0.4	56	0.2	0.6	0.1	21	1.11	0.110	4
1283803	Soil	1.2	33.8	11.4	78	1.7	24.0	5.2	207	1.66	10.3	10.0	0.8	80	0.3	0.9	0.2	36	1.35	0.134	6
1283804	Soil	0.7	9.9	2.5	11	0.3	2.8	2.1	245	0.30	<0.5	1.3	0.3	91	0.3	0.4	<0.1	2	2.23	0.072	2
1283805	Soil	1.6	24.8	10.0	76	1.3	17.0	3.6	151	1.17	13.1	12.9	0.5	66	0.5	1.1	0.2	38	1.20	0.113	5
1283806	Soil	8.0	10.5	7.4	77	0.2	18.0	2.0	20	0.78	22.5	4.8	1.2	17	<0.1	4.5	0.1	102	0.02	0.029	16
1283807	Soil	3.3	10.5	6.9	45	0.3	8.2	1.2	17	0.57	12.1	6.2	0.4	21	0.9	2.5	<0.1	36	0.15	0.035	5
1283808	Soil	3.3	38.6	18.0	102	1.1	28.4	4.8	182	1.60	31.4	23.2	1.2	78	0.7	4.4	0.2	77	1.50	0.105	9
1283809	Soil	1.0	17.0	4.9	35	0.5	11.0	1.7	79	0.60	9.3	7.8	0.2	49	0.2	1.8	<0.1	20	0.99	0.070	3
1283810	Soil	1.4	32.8	9.7	88	0.7	19.8	3.7	225	1.13	15.7	13.5	0.4	87	1.4	3.6	0.2	33	1.67	0.091	5
1283811	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283812	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283813	Soil	2.5	78.7	12.2	120	1.0	37.7	5.3	112	2.01	21.0	18.2	1.0	66	0.3	3.5	0.2	53	0.97	0.085	7
1283814	Soil	1.9	61.2	8.7	159	0.6	22.8	3.8	132	1.38	13.8	12.1	0.6	74	1.2	2.2	0.2	35	1.14	0.076	4
1283815	Soil	2.5	34.0	9.1	126	0.4	22.1	5.6	111	1.73	16.1	10.3	1.0	45	1.0	2.3	0.2	43	0.57	0.063	5
1283816	Soil	2.2	93.8	9.0	163	0.9	39.3	3.9	104	1.51	13.0	12.0	0.5	81	0.5	2.5	0.2	36	1.18	0.082	5
1283817	Soil	21.9	52.3	19.1	238	1.1	57.4	16.2	372	2.60	73.9	15.8	2.9	84	2.1	7.8	0.2	115	0.60	0.146	19
1283818	Soil	11.5	34.3	14.7	240	0.6	37.5	3.6	102	2.45	37.3	6.1	0.3	48	1.2	7.0	0.3	194	0.12	0.223	6
1283819	Soil	15.7	40.2	17.2	327	1.6	46.5	3.6	91	3.68	53.3	7.1	1.3	76	0.9	10.4	0.3	254	0.19	0.356	7
1283820	Soil	1.8	30.5	9.2	63	0.8	20.9	3.3	60	0.94	16.8	20.6	0.7	57	0.3	3.8	0.1	47	0.66	0.065	6
1283821	Soil	4.1	38.4	13.2	65	1.5	22.7	5.6	134	1.37	31.0	24.8	0.8	35	0.8	5.3	0.2	71	0.27	0.085	6
1283822	Soil	0.5	35.7	2.0	28	0.2	15.1	2.2	65	0.41	7.6	2.3	0.1	61	0.8	2.8	<0.1	15	1.13	0.056	2
1283823	Soil	6.5	70.4	23.5	148	2.0	43.1	4.8	116	1.60	42.6	39.8	1.4	100	2.0	9.0	0.3	102	1.30	0.110	13
1283824	Soil	4.0	23.3	10.2	45	0.6	14.7	1.5	35	0.61	15.3	8.7	0.4	55	0.8	3.1	0.2	62	0.71	0.043	14
1283825	Soil	10.9	18.7	19.6	112	0.3	23.5	3.0	54	1.61	40.2	7.2	1.0	19	0.3	5.0	0.4	156	0.03	0.050	17
1283826	Soil	16.8	22.3	26.8	121	0.2	28.8	3.4	42	1.37	56.6	10.2	0.7	32	0.1	10.7	0.3	139	0.03	0.045	17
1283827	Soil	1.2	6.9	3.5	25	0.5	4.3	1.0	22	0.35	5.4	2.9	0.2	32	0.3	0.9	<0.1	23	0.54	0.043	2
1283828	Soil	10.8	17.7	19.0	124	0.2	27.9	3.2	31	1.14	64.6	15.7	1.5	28	0.2	5.7	0.4	107	0.03	0.042	17
1283829	Soil	1.4	39.5	15.8	132	0.9	26.5	4.6	97	1.40	25.5	16.9	1.3	76	1.6	2.0	0.3	62	1.47	0.088	11
1283830	Soil	1.8	36.6	11.6	148	0.8	29.1	4.9	196	1.68	23.6	12.2	1.0	91	1.0	2.0	0.2	52	1.63	0.109	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283801	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283802	Soil	13	0.08	498	0.004	3	0.88	0.029	0.05	<0.1	0.36	1.5	0.2	0.12	2	2.4	<0.2
1283803	Soil	23	0.21	739	0.004	8	1.28	0.013	0.10	0.1	0.71	2.6	0.2	0.13	3	2.7	<0.2
1283804	Soil	4	0.06	292	0.012	4	0.48	0.023	0.02	<0.1	0.13	0.5	<0.1	0.22	1	2.4	<0.2
1283805	Soil	18	0.13	619	0.004	5	0.99	0.016	0.09	<0.1	0.65	1.8	0.2	0.15	3	2.3	<0.2
1283806	Soil	12	0.03	368	0.003	5	0.48	0.007	0.08	0.3	0.33	0.9	0.4	<0.05	3	1.3	<0.2
1283807	Soil	6	0.02	180	0.007	3	0.30	0.024	0.04	0.1	0.50	0.8	0.2	<0.05	1	0.7	<0.2
1283808	Soil	21	0.14	1015	0.004	4	0.90	0.009	0.08	0.2	2.62	2.1	0.7	0.13	3	3.0	<0.2
1283809	Soil	6	0.06	486	0.007	2	0.39	0.026	0.04	<0.1	0.74	0.7	0.1	<0.05	1	1.2	<0.2
1283810	Soil	13	0.14	901	0.006	4	0.73	0.016	0.06	0.1	1.49	1.5	0.2	<0.05	2	2.2	<0.2
1283811	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283812	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283813	Soil	28	0.27	1034	0.002	4	1.25	0.010	0.09	<0.1	1.57	2.5	0.3	0.10	3	2.8	<0.2
1283814	Soil	19	0.18	773	0.005	6	0.92	0.026	0.08	<0.1	0.79	1.9	0.2	0.12	2	1.2	<0.2
1283815	Soil	26	0.23	619	0.003	4	0.93	0.013	0.09	0.1	0.77	1.7	0.2	0.09	3	0.6	<0.2
1283816	Soil	18	0.17	890	0.004	5	0.99	0.029	0.07	<0.1	1.04	2.0	0.2	0.11	2	1.8	<0.2
1283817	Soil	28	0.09	2355	0.002	8	0.73	0.005	0.12	<0.1	3.06	3.9	0.6	0.10	2	3.9	<0.2
1283818	Soil	28	0.06	1764	0.007	8	0.76	0.009	0.15	0.2	0.37	1.2	0.6	0.10	3	2.9	<0.2
1283819	Soil	34	0.07	3540	0.008	11	0.91	0.008	0.18	0.2	0.22	2.3	1.1	0.14	4	4.2	0.2
1283820	Soil	15	0.11	611	0.005	3	0.68	0.033	0.06	0.1	1.58	1.3	0.4	0.06	2	1.7	<0.2
1283821	Soil	22	0.13	937	0.003	4	0.75	0.016	0.06	0.2	2.79	2.0	0.6	0.08	2	1.9	<0.2
1283822	Soil	3	0.04	475	0.013	2	0.32	0.045	0.02	<0.1	0.36	0.6	<0.1	0.08	1	1.6	<0.2
1283823	Soil	24	0.12	1316	0.009	8	0.94	0.012	0.14	0.3	3.87	3.7	1.0	0.16	3	3.3	0.2
1283824	Soil	12	0.06	553	0.014	5	0.55	0.014	0.09	0.1	0.79	1.0	0.5	<0.05	3	1.3	<0.2
1283825	Soil	19	0.05	363	0.005	5	0.72	0.006	0.09	0.2	0.50	1.2	0.5	0.05	5	1.7	0.2
1283826	Soil	16	0.04	263	0.007	4	0.62	0.007	0.09	0.3	1.15	0.9	0.6	<0.05	4	2.6	<0.2
1283827	Soil	6	0.03	293	0.007	2	0.29	0.027	0.04	<0.1	0.46	0.9	<0.1	0.09	<1	0.5	<0.2
1283828	Soil	11	0.02	337	0.004	5	0.46	0.012	0.08	0.3	2.01	1.2	0.4	0.06	3	1.6	<0.2
1283829	Soil	23	0.16	697	0.005	5	0.99	0.009	0.12	0.1	1.45	2.4	0.4	0.11	3	2.1	<0.2
1283830	Soil	24	0.16	760	0.005	6	1.03	0.014	0.11	<0.1	0.96	2.5	0.2	0.10	2	1.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283831	Soil	16.6	10.1	11.2	93	0.8	26.6	2.1	32	1.16	15.5	1.8	0.4	10	0.5	3.9	0.4	110	0.01	0.027	11
1283832	Soil	48.7	35.7	29.5	1101	1.2	190.6	5.3	216	2.78	34.6	4.0	1.6	232	12.1	13.2	0.3	238	0.71	0.403	11
1283833	Soil	56.5	28.5	13.7	355	0.9	77.9	2.2	42	1.61	25.9	3.8	0.3	19	0.9	15.2	0.3	638	0.03	0.054	22
1283834	Soil	14.7	14.4	14.3	99	0.6	16.7	1.8	29	0.91	14.1	1.5	0.7	12	0.4	5.0	0.3	179	0.02	0.024	12
1283835	Soil	18.2	21.4	17.7	95	1.3	18.2	2.6	47	1.59	31.0	2.0	0.4	27	0.8	8.0	0.3	130	0.03	0.077	6
1283836	Soil	4.5	16.7	8.5	119	0.6	17.3	3.6	87	0.91	9.1	4.9	1.1	27	1.3	1.9	0.2	66	0.26	0.052	5
1283837	Soil	1.2	47.0	11.0	122	0.8	45.1	8.1	146	1.45	10.0	5.7	0.9	92	1.2	1.4	0.3	41	1.48	0.070	4
1283838	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283839	Soil	5.5	30.5	12.9	113	1.0	31.1	4.1	90	2.59	17.1	5.0	1.9	31	0.4	2.1	0.3	66	0.36	0.044	5
1283840	Soil	2.1	42.0	9.0	37	0.4	19.1	1.4	18	0.99	5.4	5.1	1.0	28	1.9	1.6	0.3	33	0.37	0.049	4
1283841	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283842	Soil	4.4	11.8	11.9	78	1.1	12.8	2.1	23	0.94	9.2	3.4	1.0	29	0.5	1.3	0.2	119	0.25	0.051	7
1283843	Soil	1.2	10.3	4.1	61	0.3	10.7	2.2	30	0.60	3.6	1.7	0.5	33	0.4	0.6	0.1	32	0.53	0.033	2
1283844	Soil	4.4	30.4	11.4	225	0.6	42.5	5.7	80	1.66	13.3	4.2	1.8	75	1.3	2.1	0.2	78	1.19	0.074	7
1283845	Soil	1.0	11.7	5.0	80	0.5	12.9	2.6	126	0.64	4.2	2.2	0.7	67	1.0	1.1	0.2	34	1.27	0.055	4
1283846	Soil	3.2	47.5	12.2	251	0.7	74.6	7.2	102	1.69	12.5	5.9	1.6	88	1.6	2.3	0.2	69	1.60	0.092	6
1283847	Soil	7.0	32.8	15.3	184	1.4	31.6	6.2	158	3.66	22.1	1.5	2.0	26	0.5	2.7	0.3	75	0.02	0.052	7
1283848	Soil	2.5	12.2	7.5	59	0.2	12.1	4.1	135	1.29	7.0	2.0	1.1	24	0.1	0.9	0.2	40	0.04	0.029	4
1283849	Soil	1.4	15.2	8.7	76	1.1	11.0	4.8	160	1.50	6.2	1.9	0.8	22	0.3	0.7	0.2	24	0.05	0.033	2
1283850	Soil	3.7	17.0	9.0	87	0.3	15.4	3.9	78	1.94	13.0	1.2	1.8	10	0.2	1.6	0.2	57	0.01	0.028	7
1283851	Soil	1.7	34.9	29.6	189	0.1	54.5	43.0	896	3.48	18.1	1.4	2.2	17	0.2	0.9	0.3	25	0.03	0.061	4
1283852	Soil	1.4	25.2	18.1	104	<0.1	31.9	24.5	709	2.69	13.0	1.6	1.1	16	0.1	0.7	0.2	24	0.03	0.066	4
1283853	Soil	1.0	21.0	12.4	58	0.1	15.9	9.1	288	1.77	8.1	1.4	0.7	16	<0.1	0.5	0.2	16	0.04	0.050	2
1283854	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283855	Soil	1.1	15.8	15.4	69	<0.1	17.2	10.5	669	2.59	9.3	0.8	0.2	10	0.2	0.6	0.2	19	0.04	0.134	2
1283856	Soil	1.6	35.4	33.6	177	<0.1	68.0	31.6	1336	5.52	18.0	1.5	0.8	7	<0.1	1.5	0.3	30	0.02	0.096	3
1283857	Soil	1.8	35.4	39.5	152	0.1	41.7	48.8	2073	4.44	24.4	1.0	2.0	15	0.2	1.1	0.3	32	0.09	0.121	4
1283858	Soil	1.1	17.5	17.3	78	0.1	21.0	16.4	765	2.42	12.0	1.2	0.2	8	0.1	0.9	0.1	20	0.03	0.095	3
1283859	Soil	0.7	9.6	8.7	33	<0.1	6.9	5.1	278	1.62	6.2	<0.5	<0.1	7	<0.1	0.3	<0.1	10	0.05	0.073	2
1283860	Soil	1.7	20.3	47.0	111	0.1	33.8	35.5	1238	3.39	35.8	1.5	0.4	8	<0.1	2.5	0.3	25	0.02	0.080	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283831	Soil	7	0.02	113	0.004	1	0.37	0.003	0.03	0.2	0.02	0.5	0.5	0.06	3	1.4	<0.2
1283832	Soil	80	0.08	814	0.003	2	1.40	0.003	0.03	0.3	0.10	1.9	1.5	<0.05	4	7.0	<0.2
1283833	Soil	18	0.04	260	0.009	2	0.56	0.005	0.05	0.4	0.03	0.6	1.6	<0.05	4	11.4	<0.2
1283834	Soil	11	0.02	114	0.005	2	0.43	0.003	0.04	0.2	0.06	0.6	0.7	<0.05	4	1.8	<0.2
1283835	Soil	12	0.03	127	0.006	2	0.37	0.005	0.04	0.2	0.05	0.5	0.5	<0.05	3	3.4	<0.2
1283836	Soil	10	0.11	412	0.002	1	0.50	0.015	0.05	<0.1	0.49	1.1	0.4	<0.05	2	1.8	<0.2
1283837	Soil	13	0.18	313	0.002	4	0.69	0.006	0.05	<0.1	0.95	1.8	0.2	0.15	2	2.7	<0.2
1283838	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283839	Soil	13	0.09	203	0.007	4	0.51	0.014	0.07	0.2	0.48	1.4	0.3	0.08	2	2.1	<0.2
1283840	Soil	8	0.03	339	0.007	2	0.36	0.012	0.03	<0.1	0.54	1.5	0.2	0.15	1	3.8	<0.2
1283841	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283842	Soil	17	0.13	233	0.002	3	0.60	0.004	0.07	<0.1	0.83	1.1	0.9	0.08	2	1.6	<0.2
1283843	Soil	6	0.08	265	0.003	2	0.41	0.022	0.03	<0.1	0.16	0.8	0.2	0.06	1	1.0	<0.2
1283844	Soil	16	0.23	419	0.002	3	0.82	0.006	0.06	0.1	0.50	2.3	0.3	0.09	2	2.1	<0.2
1283845	Soil	7	0.10	279	0.006	4	0.43	0.021	0.05	<0.1	0.20	1.0	0.2	0.12	1	1.1	<0.2
1283846	Soil	17	0.24	509	0.003	7	0.83	0.008	0.08	<0.1	0.58	2.3	0.3	0.20	2	5.2	<0.2
1283847	Soil	21	0.16	268	0.002	<1	1.05	0.004	0.07	<0.1	0.06	1.5	0.2	<0.05	4	2.1	<0.2
1283848	Soil	11	0.13	937	0.003	1	0.86	0.016	0.07	<0.1	0.05	1.1	0.1	<0.05	3	0.5	<0.2
1283849	Soil	8	0.10	816	0.005	1	0.87	0.015	0.05	<0.1	0.03	0.9	<0.1	<0.05	3	<0.5	<0.2
1283850	Soil	11	0.09	293	0.004	<1	0.88	0.006	0.04	<0.1	0.04	1.1	0.1	<0.05	4	0.9	<0.2
1283851	Soil	20	0.28	237	0.004	<1	1.08	0.009	0.08	<0.1	0.03	5.0	0.4	<0.05	4	1.1	<0.2
1283852	Soil	16	0.16	124	0.003	<1	0.80	0.006	0.07	<0.1	0.03	3.3	0.3	<0.05	3	0.5	<0.2
1283853	Soil	12	0.15	114	0.003	<1	0.75	0.014	0.08	<0.1	0.02	2.2	0.2	<0.05	2	<0.5	<0.2
1283854	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283855	Soil	17	0.13	111	0.004	1	0.89	0.012	0.06	<0.1	0.08	0.5	0.1	0.10	3	<0.5	<0.2
1283856	Soil	19	0.10	121	0.007	<1	0.60	0.004	0.06	<0.1	0.02	3.2	0.2	<0.05	2	0.7	<0.2
1283857	Soil	26	0.40	153	0.002	<1	1.41	0.004	0.09	<0.1	0.08	3.4	0.4	<0.05	4	0.7	<0.2
1283858	Soil	13	0.15	67	0.004	1	0.81	0.010	0.06	<0.1	0.05	0.7	0.2	<0.05	3	<0.5	<0.2
1283859	Soil	9	0.05	51	0.005	<1	0.77	0.019	0.04	<0.1	0.03	0.4	<0.1	<0.05	2	<0.5	<0.2
1283860	Soil	12	0.06	124	0.002	1	0.50	0.006	0.07	<0.1	0.03	1.4	0.3	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283861	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283862	Soil	0.8	13.3	8.9	50	<0.1	10.9	6.9	371	1.25	9.2	0.7	<0.1	6	<0.1	0.9	<0.1	14	0.03	0.056	2
1283863	Soil	1.4	16.5	15.4	93	<0.1	30.3	14.1	322	2.36	30.7	1.6	<0.1	8	<0.1	4.5	0.1	25	0.02	0.055	4
1283864	Soil	1.0	14.5	19.4	66	0.2	19.5	10.5	371	2.23	19.0	1.9	<0.1	9	0.2	1.7	<0.1	22	0.03	0.118	2
1283865	Soil	0.3	3.1	2.8	10	0.2	2.9	1.5	113	0.45	2.1	1.1	<0.1	10	<0.1	0.3	<0.1	5	0.07	0.079	<1
1283866	Soil	1.3	12.3	10.6	46	0.2	15.5	5.7	92	1.63	17.5	1.2	<0.1	5	<0.1	3.9	<0.1	17	0.01	0.072	2
1283867	Soil	0.3	3.9	3.1	12	0.1	2.8	2.1	246	0.46	1.7	<0.5	<0.1	8	0.1	0.3	<0.1	8	0.05	0.071	1
1283868	Soil	0.2	2.2	2.2	7	<0.1	1.8	0.8	68	0.28	0.6	0.7	<0.1	6	<0.1	0.1	<0.1	6	0.04	0.052	<1
1283869	Soil	0.1	1.1	1.4	2	<0.1	0.8	0.3	13	0.15	<0.5	<0.5	0.2	6	<0.1	<0.1	<0.1	4	0.03	0.037	<1
1283870	Soil	2.1	11.3	9.2	32	0.2	5.5	1.7	19	1.20	10.5	1.1	0.3	8	<0.1	1.2	0.1	27	0.03	0.071	1
1283871	Soil	2.0	10.9	3.5	31	0.2	6.3	2.2	28	0.84	7.7	<0.5	0.2	5	0.1	0.8	<0.1	30	0.01	0.034	3
1283872	Soil	1.2	7.8	3.8	23	0.3	5.6	2.1	27	0.85	7.3	<0.5	0.2	4	<0.1	0.7	<0.1	22	0.01	0.041	2
1283873	Soil	2.7	12.3	7.9	56	0.1	11.5	3.7	48	1.12	9.9	0.7	0.2	7	<0.1	1.0	0.2	36	0.01	0.048	3
1283874	Soil	3.5	17.9	9.3	61	0.3	12.6	3.2	38	1.17	8.2	<0.5	0.3	11	0.4	1.2	0.2	32	0.02	0.098	3
1283875	Soil	2.5	10.8	8.1	56	0.3	11.0	2.5	38	1.05	6.6	<0.5	0.4	9	0.2	0.9	0.1	27	0.02	0.069	3
1283876	Soil	1.7	7.2	4.2	32	0.6	6.0	1.7	27	0.59	2.9	<0.5	0.3	5	0.2	0.5	<0.1	20	0.01	0.031	2
1283877	Soil	0.9	7.0	5.4	43	0.2	6.5	2.0	35	0.73	3.0	<0.5	0.2	10	0.6	0.3	0.1	19	0.02	0.057	2
1283878	Soil	2.5	10.0	7.7	68	0.2	12.6	3.4	45	1.04	5.6	<0.5	0.5	13	0.7	0.8	0.1	27	0.02	0.037	3
1283879	Soil	5.1	13.8	12.4	80	1.2	16.7	3.3	64	1.48	9.6	<0.5	0.4	24	0.5	1.5	0.2	46	0.04	0.143	4
1283880	Soil	2.1	5.7	6.4	36	<0.1	5.8	1.6	37	1.05	8.6	<0.5	0.5	6	<0.1	0.6	0.1	26	0.01	0.024	1
1284001	Soil	1.9	11.0	12.0	55	0.2	14.5	5.6	406	1.02	6.4	2.6	0.1	19	0.4	0.9	0.2	24	0.14	0.144	4
1284002	Soil	1.2	17.8	16.6	80	<0.1	23.9	13.0	463	2.32	78.0	<0.5	0.4	16	<0.1	1.4	0.2	21	0.04	0.076	3
1284003	Soil	2.3	16.2	9.7	80	<0.1	15.7	6.7	118	1.85	11.7	<0.5	0.1	5	<0.1	1.0	0.2	41	0.01	0.067	5
1284004	Soil	1.0	8.7	4.1	24	<0.1	5.6	2.6	82	0.88	3.8	1.4	<0.1	6	<0.1	0.4	<0.1	19	0.03	0.049	3
1284005	Soil	0.6	10.7	5.7	23	0.1	7.0	6.1	273	0.87	3.7	1.8	0.2	6	<0.1	0.3	<0.1	12	0.04	0.065	2
1284006	Soil	2.0	42.9	37.9	141	0.2	44.8	39.5	1081	4.58	20.0	1.7	1.7	14	<0.1	1.4	0.3	30	0.02	0.104	4
1284007	Soil	0.7	15.5	9.0	39	0.1	12.2	14.1	497	1.22	4.9	1.1	0.2	7	<0.1	0.6	0.1	14	0.05	0.066	2
1284008	Soil	1.7	37.9	24.1	128	0.1	41.5	38.4	1034	3.46	16.5	1.0	1.4	9	0.1	1.7	0.3	30	0.02	0.092	4
1284009	Soil	1.4	32.7	22.4	124	<0.1	46.3	22.9	601	2.87	14.2	2.6	1.0	14	0.1	2.0	0.3	25	0.02	0.049	3
1284010	Soil	3.0	28.2	37.0	130	0.1	44.8	33.3	1128	3.71	22.4	1.3	0.9	13	0.2	2.6	0.3	40	0.05	0.076	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283861	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283862	Soil	6	0.03	107	0.004	<1	0.48	0.018	0.05	<0.1	0.03	0.3	0.1	<0.05	2	0.5	<0.2
1283863	Soil	8	0.03	72	0.004	<1	0.31	0.004	0.06	<0.1	0.05	0.7	0.1	<0.05	2	0.6	<0.2
1283864	Soil	11	0.07	133	0.003	2	0.76	0.011	0.07	<0.1	0.04	0.6	0.2	0.06	3	0.6	<0.2
1283865	Soil	2	0.02	65	0.002	<1	0.24	0.022	0.03	<0.1	0.03	0.1	<0.1	<0.05	1	<0.5	<0.2
1283866	Soil	4	0.02	46	<0.001	<1	0.34	0.010	0.04	<0.1	0.07	0.3	0.1	<0.05	2	<0.5	<0.2
1283867	Soil	4	0.02	46	0.005	1	0.49	0.025	0.03	<0.1	0.04	0.4	<0.1	0.06	2	<0.5	<0.2
1283868	Soil	3	0.01	27	0.004	1	0.23	0.023	0.02	<0.1	0.01	0.3	<0.1	<0.05	<1	<0.5	<0.2
1283869	Soil	2	0.01	25	0.004	<1	0.22	0.025	0.02	<0.1	0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2
1283870	Soil	6	0.02	131	0.003	2	0.41	0.009	0.05	<0.1	0.03	0.7	0.2	<0.05	2	0.9	<0.2
1283871	Soil	5	0.01	95	0.003	2	0.34	0.008	0.04	<0.1	0.01	0.5	<0.1	<0.05	2	<0.5	<0.2
1283872	Soil	5	0.01	67	0.003	2	0.38	0.012	0.03	<0.1	0.02	0.5	<0.1	<0.05	2	<0.5	<0.2
1283873	Soil	5	0.02	155	0.003	2	0.36	0.008	0.04	<0.1	0.02	0.6	<0.1	<0.05	2	<0.5	<0.2
1283874	Soil	6	0.02	169	0.006	1	0.57	0.012	0.04	<0.1	0.02	0.7	0.1	<0.05	3	0.8	<0.2
1283875	Soil	6	0.03	98	0.004	1	0.43	0.013	0.04	<0.1	0.02	0.7	<0.1	<0.05	2	<0.5	<0.2
1283876	Soil	4	0.02	102	0.005	2	0.39	0.014	0.04	<0.1	0.03	0.6	<0.1	<0.05	2	<0.5	<0.2
1283877	Soil	5	0.02	210	0.012	<1	0.44	0.014	0.05	<0.1	0.01	0.4	<0.1	<0.05	2	<0.5	<0.2
1283878	Soil	6	0.02	280	0.003	2	0.40	0.012	0.06	<0.1	0.01	1.0	<0.1	<0.05	2	<0.5	<0.2
1283879	Soil	10	0.03	641	0.003	3	0.55	0.008	0.06	<0.1	0.04	0.9	0.2	0.07	2	1.3	<0.2
1283880	Soil	5	0.02	202	0.002	1	0.48	0.009	0.05	<0.1	<0.01	0.8	0.1	<0.05	2	<0.5	<0.2
1284001	Soil	23	0.05	139	0.005	3	0.53	0.013	0.09	<0.1	0.03	0.6	0.1	0.12	2	0.7	<0.2
1284002	Soil	11	0.08	84	0.005	2	0.57	0.010	0.07	<0.1	0.05	1.5	0.1	0.07	2	<0.5	<0.2
1284003	Soil	9	0.02	39	0.007	2	0.45	0.007	0.04	<0.1	0.01	0.4	0.1	<0.05	4	<0.5	<0.2
1284004	Soil	6	0.03	37	0.005	<1	0.59	0.018	0.03	<0.1	0.02	0.4	0.1	<0.05	3	<0.5	<0.2
1284005	Soil	7	0.05	32	0.011	<1	0.71	0.022	0.04	<0.1	0.04	0.8	<0.1	0.09	2	<0.5	<0.2
1284006	Soil	22	0.18	81	0.002	2	1.16	0.006	0.09	<0.1	0.05	3.3	0.4	0.06	3	0.6	<0.2
1284007	Soil	8	0.08	39	0.007	<1	0.62	0.021	0.04	<0.1	0.04	0.7	0.1	<0.05	2	<0.5	<0.2
1284008	Soil	20	0.18	70	0.003	2	0.84	0.004	0.07	<0.1	0.06	3.1	0.2	<0.05	3	0.5	<0.2
1284009	Soil	14	0.09	81	0.002	1	0.48	0.003	0.07	<0.1	0.03	2.9	0.2	<0.05	2	0.6	<0.2
1284010	Soil	26	0.31	85	0.012	1	1.16	0.003	0.06	0.1	0.03	2.1	0.3	<0.05	4	0.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1284011	Soil	2.2	29.1	47.5	123	0.2	38.5	28.1	1056	3.75	28.5	1.1	0.5	12	0.1	3.6	0.3	35	0.03	0.146	4
1284012	Soil	2.1	23.6	39.2	111	0.2	29.2	17.2	541	3.29	54.4	1.4	0.3	11	0.2	3.0	0.2	40	0.06	0.106	7
1284013	Soil	0.9	14.6	11.1	64	<0.1	17.4	7.9	339	1.96	166.7	0.8	0.2	11	0.1	2.2	0.2	22	0.03	0.077	3
1284014	Soil	0.5	4.3	3.0	19	<0.1	4.5	2.1	197	0.51	12.8	0.5	<0.1	5	<0.1	0.3	<0.1	9	0.03	0.065	1
1284015	Soil	1.2	15.1	7.7	67	<0.1	17.2	7.6	283	1.53	34.0	0.6	<0.1	7	<0.1	1.3	0.2	21	0.02	0.067	4
1284016	Soil	1.7	21.2	13.3	85	<0.1	23.5	9.1	289	2.90	15.8	<0.5	0.2	8	0.1	2.9	0.2	31	0.03	0.079	7
1284017	Soil	2.0	25.6	20.8	128	<0.1	35.9	22.3	662	3.30	17.6	0.8	0.4	9	0.2	3.4	0.2	33	0.03	0.070	6
1284018	Soil	1.6	22.8	17.1	96	<0.1	34.1	14.2	265	3.00	21.0	<0.5	0.5	8	<0.1	8.4	0.2	32	0.03	0.061	6
1284019	Soil	0.3	3.5	1.5	8	<0.1	1.8	1.0	82	0.36	1.0	1.8	<0.1	6	<0.1	0.2	<0.1	9	0.04	0.045	1
1284020	Soil	0.6	7.3	4.1	14	<0.1	4.3	2.6	86	0.67	2.6	0.6	<0.1	5	<0.1	0.4	<0.1	12	0.03	0.050	3
1284021	Soil	0.5	13.8	9.0	31	0.1	9.5	6.4	429	1.25	3.5	1.9	0.2	6	0.2	0.5	0.1	17	0.02	0.076	2
1284022	Soil	0.2	4.6	1.6	4	<0.1	1.0	1.2	51	0.26	0.5	<0.5	<0.1	7	<0.1	<0.1	<0.1	5	0.06	0.039	2
1284023	Soil	1.1	17.6	16.4	43	0.1	11.2	10.0	685	1.83	6.6	3.7	0.1	7	0.3	0.7	0.2	17	0.03	0.106	3
1284024	Soil	0.6	15.2	12.3	25	0.2	9.3	11.8	364	0.81	3.0	2.0	<0.1	19	0.2	0.4	<0.1	6	0.14	0.082	2
1284025	Soil	0.8	10.2	8.9	29	<0.1	5.2	3.7	291	1.43	4.5	1.9	<0.1	5	0.1	0.6	0.1	17	0.03	0.056	2
1284026	Soil	0.6	12.6	7.9	30	<0.1	13.5	7.4	542	0.87	4.9	2.1	0.1	17	0.4	1.3	0.4	10	0.12	0.105	2
1284027	Soil	3.5	26.0	19.5	107	<0.1	32.0	17.1	1263	2.12	19.2	7.2	0.5	52	0.5	2.6	0.2	29	0.46	0.159	4
1284028	Soil	0.6	24.2	7.8	35	0.2	19.0	7.9	831	0.75	12.2	4.3	0.1	24	0.7	0.8	<0.1	7	0.20	0.126	4
1284029	Soil	1.0	12.1	10.1	59	<0.1	13.1	8.1	295	1.47	10.4	2.2	0.1	6	0.3	1.3	0.2	19	0.03	0.048	2
1284030	Soil	0.3	3.5	2.1	17	<0.1	2.6	1.5	67	0.41	2.2	<0.5	0.1	6	0.3	0.4	<0.1	6	0.03	0.044	<1
1284201	Soil	1.9	17.8	15.3	51	0.2	10.4	3.8	152	2.20	13.1	1.7	0.2	9	<0.1	0.9	0.3	36	0.02	0.077	4
1284202	Soil	1.4	27.6	22.9	92	0.3	19.2	10.8	240	2.82	19.9	2.2	1.3	21	<0.1	0.8	0.3	28	0.05	0.075	4
1284203	Soil	1.4	28.7	20.6	52	0.6	7.9	2.7	54	2.78	19.2	3.9	0.9	21	0.1	0.7	0.3	44	0.02	0.113	4
1284204	Soil	1.0	21.7	15.4	49	0.3	8.1	4.5	180	1.71	10.5	<0.5	0.9	11	0.3	0.5	0.3	37	0.01	0.086	3
1284205	Soil	0.5	10.1	6.1	23	0.5	4.7	1.8	101	0.76	3.9	0.6	0.2	7	<0.1	0.2	0.1	12	0.02	0.065	2
1284206	Soil	1.4	22.7	20.7	66	0.6	11.8	5.3	156	3.07	15.9	1.0	0.5	17	0.2	0.7	0.3	39	0.02	0.092	4
1284207	Soil	0.6	10.9	4.8	16	0.2	3.1	1.0	39	0.82	3.8	0.6	<0.1	5	<0.1	0.3	<0.1	16	0.01	0.030	2
1284208	Soil	0.9	11.1	10.2	37	0.1	5.1	2.4	65	1.17	4.6	1.6	0.3	8	0.1	0.5	0.2	30	0.01	0.058	3
1284209	Soil	0.5	13.7	11.0	49	0.6	8.9	8.0	407	1.26	5.8	1.1	0.2	9	<0.1	0.2	0.1	19	0.02	0.048	2
1284210	Soil	1.0	19.6	13.3	63	0.7	11.0	7.1	336	2.01	12.2	0.7	0.4	15	0.2	0.4	0.2	25	0.03	0.075	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

CERTIFICATE OF ANALYSIS WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284011	Soil	23	0.15	72	0.004	1	0.96	0.008	0.07	<0.1	0.06	2.0	0.3	0.08	3	1.0	<0.2
1284012	Soil	25	0.22	95	0.009	1	1.14	0.005	0.05	0.1	0.09	1.2	0.3	0.09	4	1.0	<0.2
1284013	Soil	11	0.04	54	0.004	1	0.56	0.009	0.05	<0.1	0.04	0.5	<0.1	0.06	2	<0.5	<0.2
1284014	Soil	3	0.02	27	0.004	<1	0.22	0.018	0.03	<0.1	0.02	0.2	<0.1	<0.05	1	<0.5	<0.2
1284015	Soil	7	0.02	51	0.004	1	0.45	0.010	0.06	<0.1	0.02	0.4	<0.1	<0.05	2	<0.5	<0.2
1284016	Soil	18	0.07	55	0.006	1	0.67	0.003	0.05	0.1	0.04	0.6	0.2	0.06	3	<0.5	<0.2
1284017	Soil	19	0.17	77	0.006	2	0.79	0.003	0.05	<0.1	0.04	1.2	0.2	<0.05	3	0.7	<0.2
1284018	Soil	18	0.13	58	0.007	<1	0.71	0.004	0.04	<0.1	0.05	1.2	0.2	<0.05	2	0.6	<0.2
1284019	Soil	2	0.02	16	0.006	<1	0.38	0.024	0.03	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2
1284020	Soil	5	0.04	41	0.006	<1	0.66	0.025	0.02	<0.1	0.03	0.4	<0.1	0.06	3	<0.5	<0.2
1284021	Soil	10	0.07	87	0.006	<1	0.72	0.017	0.05	<0.1	0.03	0.5	<0.1	<0.05	3	<0.5	<0.2
1284022	Soil	2	0.02	21	0.012	<1	0.62	0.040	0.02	<0.1	0.01	0.9	<0.1	<0.05	2	<0.5	<0.2
1284023	Soil	12	0.10	100	0.007	3	0.84	0.014	0.05	<0.1	0.05	0.2	<0.1	0.24	4	<0.5	<0.2
1284024	Soil	5	0.06	156	0.005	1	0.54	0.023	0.03	<0.1	0.05	0.2	<0.1	0.14	2	<0.5	<0.2
1284025	Soil	9	0.05	47	0.008	1	0.50	0.019	0.03	<0.1	0.04	0.2	<0.1	<0.05	3	<0.5	<0.2
1284026	Soil	3	0.05	171	0.005	2	0.39	0.024	0.04	<0.1	0.04	0.2	0.2	0.09	2	<0.5	<0.2
1284027	Soil	11	0.10	345	0.006	3	0.59	0.011	0.09	<0.1	0.05	1.1	0.2	0.14	2	0.6	<0.2
1284028	Soil	5	0.05	632	0.006	2	0.73	0.019	0.04	<0.1	0.05	0.3	<0.1	0.14	2	<0.5	<0.2
1284029	Soil	8	0.08	94	0.006	3	0.48	0.012	0.03	0.1	0.02	0.5	<0.1	<0.05	2	<0.5	<0.2
1284030	Soil	2	0.01	62	0.009	2	0.41	0.020	0.02	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2
1284201	Soil	14	0.08	71	0.004	1	0.59	0.004	0.04	0.1	0.03	0.6	<0.1	0.05	3	0.6	<0.2
1284202	Soil	14	0.13	120	0.005	<1	0.68	0.005	0.04	<0.1	0.04	2.5	<0.1	0.08	2	0.8	<0.2
1284203	Soil	16	0.04	202	0.004	3	0.73	0.007	0.06	<0.1	0.06	1.1	0.1	0.07	3	1.1	<0.2
1284204	Soil	17	0.04	280	0.003	<1	0.86	0.008	0.06	<0.1	0.02	1.1	0.1	<0.05	3	0.6	<0.2
1284205	Soil	7	0.03	88	0.003	1	0.48	0.014	0.03	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2
1284206	Soil	18	0.08	180	0.002	1	0.94	0.006	0.05	<0.1	0.04	0.7	<0.1	<0.05	4	0.7	<0.2
1284207	Soil	5	0.02	67	0.005	<1	0.41	0.014	0.02	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2
1284208	Soil	7	0.03	110	0.003	<1	0.53	0.008	0.04	<0.1	0.01	0.5	<0.1	<0.05	3	<0.5	<0.2
1284209	Soil	8	0.05	191	0.004	1	0.70	0.012	0.05	<0.1	0.04	0.6	<0.1	<0.05	3	<0.5	<0.2
1284210	Soil	11	0.06	346	0.003	1	0.84	0.013	0.05	<0.1	0.05	1.1	<0.1	<0.05	3	0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1283655	Soil	1.6	35.1	21.3	90	1.1	20.7	4.5	77	2.16	29.0	2.5	0.5	40	<0.1	1.2	0.3	38	0.01	0.085	2
REP 1283655	QC	1.7	33.7	21.5	86	1.1	21.3	4.5	74	2.14	28.2	4.2	0.5	39	<0.1	1.2	0.3	37	0.01	0.084	2
1283672	Soil	8.5	34.3	52.1	57	1.9	14.9	2.9	172	1.34	33.8	5.0	0.5	80	0.2	3.3	0.3	84	0.07	0.103	7
REP 1283672	QC	9.0	34.4	52.9	58	1.9	15.0	2.9	172	1.37	34.3	4.6	0.6	84	0.2	3.4	0.3	85	0.07	0.105	7
1283692	Soil	2.7	31.6	20.9	144	1.3	45.1	8.5	239	2.27	14.1	4.0	1.1	75	1.1	1.5	0.3	47	0.71	0.116	4
REP 1283692	QC	2.6	30.2	20.7	138	1.3	45.0	8.1	231	2.19	13.9	4.6	1.1	78	1.1	1.4	0.3	48	0.68	0.118	4
1283699	Soil	5.2	10.7	11.5	37	1.9	7.0	2.9	61	2.22	13.0	1.9	1.0	17	0.4	2.9	0.2	57	0.04	0.067	9
REP 1283699	QC	5.0	10.7	11.1	40	1.9	8.0	3.0	65	2.23	13.8	1.4	1.0	17	0.5	2.8	0.2	58	0.04	0.066	9
1283751	Soil	4.5	13.1	7.9	60	<0.1	13.2	4.0	71	1.97	16.8	1.3	1.5	6	<0.1	1.7	0.2	73	0.02	0.018	7
REP 1283751	QC	4.4	12.7	8.7	59	<0.1	12.8	3.8	70	2.02	16.2	<0.5	1.4	6	0.2	1.6	0.2	74	0.03	0.018	7
1283752	Soil	3.2	19.0	10.8	73	0.3	25.5	5.2	118	2.61	10.8	4.4	1.9	5	0.2	1.2	0.2	62	0.01	0.019	7
REP 1283752	QC	3.5	19.5	10.8	74	0.3	25.3	5.3	115	2.60	10.6	3.4	1.8	5	0.2	1.2	0.2	58	0.01	0.018	7
1283759	Soil	0.6	2.6	3.8	14	0.2	1.6	0.5	18	0.29	1.8	1.0	0.4	5	<0.1	0.2	0.3	19	0.02	0.013	10
REP 1283759	QC	0.5	3.0	3.4	13	0.2	1.5	0.5	15	0.30	1.7	1.7	0.4	4	<0.1	0.2	0.1	18	0.02	0.012	10
1283763	Soil	2.6	11.1	6.2	52	0.4	10.0	2.7	56	1.39	11.0	4.1	0.2	6	0.2	1.2	0.2	50	0.01	0.030	7
REP 1283763	QC	2.4	11.1	6.3	56	0.4	10.2	2.9	57	1.41	11.4	0.8	0.2	6	0.2	1.2	0.2	55	0.01	0.031	7
1283805	Soil	1.6	24.8	10.0	76	1.3	17.0	3.6	151	1.17	13.1	12.9	0.5	66	0.5	1.1	0.2	38	1.20	0.113	5
REP 1283805	QC	1.4	23.6	9.7	71	1.2	16.3	3.5	156	1.12	13.0	13.8	0.6	61	0.6	1.1	0.1	38	1.16	0.105	5
1283809	Soil	1.0	17.0	4.9	35	0.5	11.0	1.7	79	0.60	9.3	7.8	0.2	49	0.2	1.8	<0.1	20	0.99	0.070	3
REP 1283809	QC	1.0	16.5	4.9	38	0.5	9.7	1.8	78	0.60	9.5	8.6	0.2	49	0.3	1.8	<0.1	23	0.99	0.070	3
1283829	Soil	1.4	39.5	15.8	132	0.9	26.5	4.6	97	1.40	25.5	16.9	1.3	76	1.6	2.0	0.3	62	1.47	0.088	11
REP 1283829	QC	1.4	42.7	16.3	139	1.0	27.7	4.6	95	1.36	24.9	15.5	1.6	78	1.7	2.0	0.2	64	1.54	0.092	12
1283836	Soil	4.5	16.7	8.5	119	0.6	17.3	3.6	87	0.91	9.1	4.9	1.1	27	1.3	1.9	0.2	66	0.26	0.052	5
REP 1283836	QC	4.5	17.2	8.4	122	0.7	17.7	3.7	90	0.93	8.6	3.9	1.0	27	1.2	1.9	0.2	71	0.26	0.053	4
1283853	Soil	1.0	21.0	12.4	58	0.1	15.9	9.1	288	1.77	8.1	1.4	0.7	16	<0.1	0.5	0.2	16	0.04	0.050	2
REP 1283853	QC	1.0	21.6	12.4	60	0.1	17.2	9.5	294	1.80	7.9	1.4	0.8	16	<0.1	0.5	0.2	16	0.04	0.052	2
1284004	Soil	1.0	8.7	4.1	24	<0.1	5.6	2.6	82	0.88	3.8	1.4	<0.1	6	<0.1	0.4	<0.1	19	0.03	0.049	3
REP 1284004	QC	1.0	8.5	4.3	25	<0.1	5.6	2.5	87	0.86	3.9	<0.5	<0.1	6	<0.1	0.5	<0.1	20	0.03	0.060	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11001405.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1283655	Soil	10	0.02	404	0.002	4	0.40	0.004	0.11	<0.1	0.07	1.4	0.1	0.09	2	2.0	<0.2
REP 1283655	QC	9	0.02	404	0.002	3	0.41	0.004	0.11	<0.1	0.08	1.3	0.1	0.10	2	1.8	<0.2
1283672	Soil	21	0.09	424	0.014	1	0.66	0.011	0.07	0.1	0.14	1.3	0.6	0.08	4	3.1	<0.2
REP 1283672	QC	21	0.09	447	0.014	1	0.68	0.011	0.07	0.1	0.14	1.3	0.7	0.08	3	3.5	<0.2
1283692	Soil	14	0.15	1446	0.001	3	0.80	0.004	0.08	<0.1	0.36	3.2	0.2	0.08	2	2.8	<0.2
REP 1283692	QC	14	0.15	1517	0.002	4	0.83	0.005	0.09	<0.1	0.36	3.3	0.2	0.08	2	2.3	<0.2
1283699	Soil	12	0.10	373	0.007	2	0.85	0.009	0.05	0.2	0.05	0.8	0.3	<0.05	4	1.9	<0.2
REP 1283699	QC	12	0.10	385	0.008	2	0.88	0.011	0.06	0.2	0.04	1.0	0.3	<0.05	4	1.9	<0.2
1283751	Soil	9	0.05	127	0.003	<1	0.69	0.003	0.03	0.1	<0.01	1.2	0.1	<0.05	3	0.6	<0.2
REP 1283751	QC	10	0.05	137	0.003	<1	0.72	0.004	0.03	<0.1	0.02	1.1	0.1	<0.05	3	<0.5	<0.2
1283752	Soil	20	0.17	338	0.002	<1	1.05	0.003	0.03	<0.1	0.02	1.4	0.1	<0.05	4	0.8	<0.2
REP 1283752	QC	19	0.17	333	0.003	<1	1.06	0.003	0.03	<0.1	0.01	1.4	0.1	<0.05	4	0.6	<0.2
1283759	Soil	4	0.02	83	0.007	2	0.35	0.006	0.02	0.1	0.02	0.2	0.1	<0.05	3	<0.5	<0.2
REP 1283759	QC	4	0.02	83	0.006	<1	0.32	0.005	0.02	0.1	0.02	0.2	0.1	<0.05	3	<0.5	<0.2
1283763	Soil	6	0.03	141	0.007	1	0.46	0.006	0.02	0.2	0.02	0.4	0.1	<0.05	3	0.5	<0.2
REP 1283763	QC	7	0.04	146	0.007	2	0.48	0.008	0.03	0.2	0.01	0.4	0.1	<0.05	4	0.6	<0.2
1283805	Soil	18	0.13	619	0.004	5	0.99	0.016	0.09	<0.1	0.65	1.8	0.2	0.15	3	2.3	<0.2
REP 1283805	QC	17	0.13	604	0.004	5	0.96	0.018	0.09	<0.1	0.71	1.7	0.2	0.14	3	1.6	<0.2
1283809	Soil	6	0.06	486	0.007	2	0.39	0.026	0.04	<0.1	0.74	0.7	0.1	<0.05	1	1.2	<0.2
REP 1283809	QC	7	0.06	499	0.009	4	0.43	0.028	0.04	<0.1	0.73	0.8	0.2	0.09	1	1.5	<0.2
1283829	Soil	23	0.16	697	0.005	5	0.99	0.009	0.12	0.1	1.45	2.4	0.4	0.11	3	2.1	<0.2
REP 1283829	QC	23	0.17	718	0.008	9	1.01	0.010	0.13	0.2	1.39	2.8	0.4	0.14	3	1.3	<0.2
1283836	Soil	10	0.11	412	0.002	1	0.50	0.015	0.05	<0.1	0.49	1.1	0.4	<0.05	2	1.8	<0.2
REP 1283836	QC	11	0.11	419	0.003	2	0.51	0.016	0.05	<0.1	0.47	1.1	0.4	0.07	2	2.0	<0.2
1283853	Soil	12	0.15	114	0.003	<1	0.75	0.014	0.08	<0.1	0.02	2.2	0.2	<0.05	2	<0.5	<0.2
REP 1283853	QC	13	0.15	115	0.003	2	0.78	0.015	0.08	<0.1	0.02	2.0	0.2	<0.05	3	<0.5	<0.2
1284004	Soil	6	0.03	37	0.005	<1	0.59	0.018	0.03	<0.1	0.02	0.4	0.1	<0.05	3	<0.5	<0.2
REP 1284004	QC	7	0.03	41	0.009	2	0.64	0.019	0.04	0.1	0.02	0.4	<0.1	<0.05	3	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11001405.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1284021	Soil	0.5	13.8	9.0	31	0.1	9.5	6.4	429	1.25	3.5	1.9	0.2	6	0.2	0.5	0.1	17	0.02	0.076	2
REP 1284021	QC	0.5	13.3	8.4	30	0.1	9.2	6.0	417	1.15	3.5	<0.5	0.2	6	0.2	0.5	0.1	17	0.02	0.072	2
1284201	Soil	1.9	17.8	15.3	51	0.2	10.4	3.8	152	2.20	13.1	1.7	0.2	9	<0.1	0.9	0.3	36	0.02	0.077	4
REP 1284201	QC	2.0	18.3	16.7	52	0.3	10.9	4.0	149	2.26	13.9	0.7	0.5	9	0.1	0.9	0.4	38	0.02	0.078	5
Reference Materials																					
STD DS8	Standard	13.0	106.6	122.5	311	1.8	37.0	7.0	616	2.47	23.7	123.0	6.1	63	2.1	5.4	6.5	42	0.71	0.075	15
STD DS8	Standard	12.5	102.3	120.8	308	1.8	36.3	7.0	581	2.31	24.2	119.9	7.0	72	2.2	5.7	6.7	39	0.70	0.077	16
STD DS8	Standard	12.6	106.3	129.6	324	1.8	37.6	7.5	628	2.51	25.8	143.3	6.8	75	2.2	5.9	7.0	41	0.72	0.081	16
STD DS8	Standard	13.3	115.2	127.9	314	1.8	40.2	7.8	630	2.46	25.6	115.2	6.6	66	2.5	5.6	6.8	49	0.67	0.076	14
STD DS8	Standard	13.0	108.4	121.7	292	1.6	37.2	7.5	572	2.29	23.3	112.9	7.2	66	2.3	5.6	6.4	43	0.64	0.072	15
STD DS8	Standard	11.4	108.6	113.4	287	1.6	35.2	6.8	538	2.15	22.9	98.9	6.2	59	2.4	5.5	6.8	39	0.61	0.069	12
STD DS8	Standard	13.3	109.0	129.0	314	1.9	37.8	7.7	616	2.51	26.1	117.4	6.7	69	2.5	5.7	6.6	45	0.72	0.079	15
STD DS8	Standard	13.9	108.4	125.8	320	1.9	39.3	8.0	642	2.48	25.4	128.6	7.7	84	2.3	5.6	6.9	46	0.82	0.082	21
STD DS8	Standard	14.0	115.7	123.4	303	1.7	38.8	7.7	624	2.40	24.9	109.4	7.1	67	2.4	5.4	6.3	41	0.68	0.079	16
STD DS8	Standard	12.4	108.9	129.1	315	1.8	39.3	7.4	618	2.51	25.7	120.0	6.7	73	2.4	6.2	7.0	41	0.71	0.083	15
STD DS8	Standard	13.3	107.6	124.9	304	1.7	35.3	7.3	610	2.42	24.2	103.4	7.0	75	2.3	5.4	6.5	41	0.71	0.075	16
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 26, 2011

QUALITY CONTROL REPORT WHI11001405.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1284021	Soil	10	0.07	87	0.006	<1	0.72	0.017	0.05	<0.1	0.03	0.5	<0.1	<0.05	3	<0.5	<0.2
REP 1284021	QC	9	0.07	87	0.005	1	0.72	0.019	0.04	<0.1	0.03	0.3	<0.1	<0.05	3	<0.5	<0.2
1284201	Soil	14	0.08	71	0.004	1	0.59	0.004	0.04	0.1	0.03	0.6	<0.1	0.05	3	0.6	<0.2
REP 1284201	QC	15	0.08	77	0.004	<1	0.60	0.004	0.04	0.1	0.03	0.5	0.1	<0.05	3	0.6	<0.2
Reference Materials																	
STD DS8	Standard	118	0.69	273	0.109	3	0.89	0.086	0.42	3.1	0.19	2.0	5.4	0.13	5	5.2	5.3
STD DS8	Standard	111	0.60	279	0.116	3	0.90	0.111	0.43	2.8	0.19	2.6	5.2	0.15	5	4.8	4.7
STD DS8	Standard	113	0.64	291	0.114	2	0.95	0.106	0.45	2.9	0.20	2.4	5.6	0.17	5	5.2	4.9
STD DS8	Standard	117	0.61	267	0.116	2	0.94	0.099	0.42	3.0	0.20	2.3	5.6	0.09	5	5.1	4.9
STD DS8	Standard	115	0.57	258	0.124	3	0.87	0.085	0.38	2.8	0.17	2.2	5.1	0.16	4	4.4	4.8
STD DS8	Standard	109	0.56	236	0.105	2	0.82	0.083	0.38	2.6	0.19	2.0	4.9	0.14	4	4.1	4.4
STD DS8	Standard	123	0.62	286	0.125	2	0.92	0.097	0.45	2.9	0.21	2.8	5.6	0.16	5	5.0	5.3
STD DS8	Standard	123	0.65	299	0.142	3	1.09	0.116	0.49	3.0	0.22	3.4	5.3	0.16	5	5.6	5.1
STD DS8	Standard	112	0.58	265	0.117	3	0.86	0.081	0.39	2.9	0.19	1.9	5.3	0.24	5	4.8	4.8
STD DS8	Standard	118	0.63	296	0.113	3	1.00	0.116	0.45	3.0	0.19	2.8	5.6	0.08	5	4.6	4.8
STD DS8	Standard	113	0.56	278	0.118	3	0.96	0.104	0.42	2.8	0.18	3.0	5.3	<0.05	5	4.8	4.8
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 05, 2011
Report Date: November 07, 2011
Page: 1 of 10

CERTIFICATE OF ANALYSIS WHI11001406.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #22
P.O. Number
Number of Samples: 250

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
RJSV	249	Saving all or part of Soil Reject			WHI
1DX2	236	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280991	Soil		6.8	36.7	17.6	162	0.3	40.4	9.7	216	2.88	31.1	3.3	2.1	30	0.5	2.9	0.2	60	0.13	0.104	9
1280992	Soil		8.5	42.7	14.8	168	0.4	39.4	9.6	242	2.30	25.0	3.3	1.5	43	1.2	3.1	0.2	51	0.25	0.167	11
1280993	Soil		4.5	17.8	7.7	56	0.5	14.6	3.0	267	1.86	20.6	2.4	0.4	43	1.1	1.1	0.1	39	0.56	0.087	4
1280994	Soil		5.3	26.5	13.2	126	0.8	28.9	7.6	203	1.81	13.6	3.2	1.8	29	1.1	1.4	0.2	50	0.20	0.106	8
1280995	Soil		5.5	38.5	10.1	121	0.7	33.4	5.5	216	1.82	11.3	4.4	1.2	42	1.7	1.7	0.2	43	0.76	0.091	7
1280996	Soil		10.7	73.5	23.7	103	1.6	35.5	5.2	109	1.98	25.0	4.4	0.9	32	1.0	3.7	0.2	49	0.45	0.119	7
1280997	Soil		8.8	29.7	18.4	81	0.7	21.5	4.2	96	1.71	14.1	3.0	0.9	27	0.6	2.0	0.2	42	0.21	0.115	6
1280998	Soil		6.5	16.7	10.1	86	0.2	17.0	4.7	159	1.53	13.3	1.3	1.4	28	0.5	1.3	0.2	35	0.39	0.076	6
1280999	Soil		8.8	33.6	15.4	165	0.6	34.0	7.8	156	2.44	18.7	2.8	2.4	28	1.4	2.0	0.2	53	0.25	0.100	10
1281000	Soil		10.0	41.5	16.4	236	0.3	45.2	11.4	268	2.61	23.2	3.2	2.5	23	1.8	3.0	0.2	52	0.25	0.099	17
1282811	Soil		0.5	4.6	3.0	12	0.2	3.0	0.9	26	0.40	1.7	<0.5	<0.1	5	<0.1	0.2	<0.1	9	0.02	0.036	1
1282812	Soil		0.2	2.7	2.3	7	0.2	1.9	0.6	19	0.19	0.6	<0.5	<0.1	14	<0.1	<0.1	<0.1	4	0.13	0.025	<1
1282813	Soil		2.6	26.0	17.2	107	0.5	25.6	7.6	168	2.50	14.3	2.1	1.8	21	0.3	1.0	0.2	35	0.06	0.090	4
1282814	Soil		5.8	15.3	10.7	70	1.8	13.9	2.1	78	1.83	20.9	2.1	0.4	14	<0.1	2.7	0.2	88	0.03	0.081	7
1282815	Soil		6.5	14.5	12.2	60	0.3	12.2	1.8	26	0.73	10.3	<0.5	0.1	13	0.2	1.9	0.2	60	0.02	0.025	10
1282816	Soil		10.9	41.8	15.4	210	2.1	37.2	3.8	324	1.64	16.4	7.3	0.7	136	2.5	4.7	0.2	153	0.59	0.262	9
1282817	Soil		14.2	68.8	14.5	280	2.2	51.0	6.5	1164	2.12	23.0	8.7	1.3	183	4.9	7.4	0.2	194	0.44	0.304	10
1282818	Soil		22.6	61.2	12.6	300	1.4	66.5	7.8	326	2.30	24.8	5.3	1.2	114	3.2	8.3	0.2	185	0.33	0.199	12
1282819	Soil		13.2	53.0	14.0	218	2.8	42.6	5.7	242	1.81	19.9	6.7	0.3	113	2.3	6.2	0.2	180	0.27	0.192	8
1282820	Soil		13.9	49.5	16.2	202	1.9	38.6	4.2	261	1.87	25.5	4.9	0.3	106	2.0	7.4	0.2	210	0.15	0.149	10
1282821	Soil		13.7	72.0	13.7	209	2.6	43.1	5.1	173	1.86	21.0	5.9	0.8	148	3.3	7.3	0.2	186	0.31	0.222	12
1282822	Soil		12.2	60.7	13.8	215	1.7	42.9	7.2	300	2.02	22.0	5.5	0.6	148	2.5	7.2	0.2	191	0.41	0.256	10
1282823	Soil		17.2	66.9	17.8	209	1.7	41.8	4.1	122	2.47	24.3	4.1	0.9	145	1.7	8.0	0.2	207	0.19	0.258	11
1282824	Soil		14.7	63.7	14.8	173	2.4	32.3	3.1	89	1.92	21.4	3.8	0.4	171	1.7	7.6	0.2	211	0.26	0.304	10
1282825	Soil		14.3	67.5	14.4	148	2.7	26.8	2.6	72	1.85	19.4	4.1	0.6	148	1.4	8.1	0.2	210	0.15	0.229	10
1282826	Soil		12.0	37.3	15.8	129	1.2	20.7	2.5	74	1.76	18.7	2.9	0.2	108	0.7	5.7	0.2	180	0.07	0.185	9
1282827	Soil		10.2	26.2	18.0	107	1.1	19.5	2.7	85	1.60	18.3	2.8	0.1	77	0.5	4.1	0.3	170	0.04	0.114	7
1282828	Soil		9.9	45.1	13.8	127	1.6	24.5	3.6	155	2.19	22.2	4.6	0.7	131	0.9	6.3	0.2	200	0.22	0.263	10
1282829	Soil		10.3	30.0	18.0	107	0.9	20.0	2.9	95	2.06	19.7	2.2	0.3	102	0.5	4.6	0.3	182	0.10	0.177	10
1282830	Soil		8.4	30.4	14.7	143	4.2	23.2	2.8	80	2.04	17.4	1.9	1.6	132	0.8	4.2	0.2	191	0.19	0.314	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280991	Soil	16	0.14	501	0.003	2	0.87	0.004	0.05	0.1	0.13	2.1	0.2	<0.05	2	2.1	<0.2
1280992	Soil	13	0.12	1437	0.003	2	0.55	0.003	0.06	<0.1	0.15	2.0	0.2	<0.05	2	2.0	<0.2
1280993	Soil	7	0.07	1043	0.004	2	0.51	0.013	0.03	0.1	0.25	1.0	0.1	0.05	2	1.4	<0.2
1280994	Soil	17	0.15	1482	0.002	2	0.98	0.007	0.06	0.1	0.48	2.9	0.3	<0.05	2	1.4	<0.2
1280995	Soil	13	0.17	1006	0.003	3	0.78	0.010	0.06	<0.1	0.29	2.5	0.2	<0.05	2	1.8	<0.2
1280996	Soil	10	0.09	755	0.002	3	0.52	0.006	0.06	<0.1	0.40	2.1	0.3	<0.05	1	2.7	<0.2
1280997	Soil	9	0.06	428	0.002	1	0.43	0.006	0.05	<0.1	0.09	1.3	0.2	<0.05	2	1.4	<0.2
1280998	Soil	12	0.20	464	0.003	2	0.59	0.005	0.04	<0.1	0.07	1.3	0.1	<0.05	2	1.0	<0.2
1280999	Soil	16	0.18	811	0.002	2	0.84	0.004	0.06	0.1	0.36	2.5	0.2	<0.05	2	2.1	<0.2
1281000	Soil	15	0.21	497	0.003	2	0.69	0.004	0.09	<0.1	0.07	2.3	0.2	<0.05	2	1.9	<0.2
1282811	Soil	5	0.01	37	0.004	<1	0.21	0.020	0.03	<0.1	0.01	0.2	<0.1	<0.05	1	<0.5	<0.2
1282812	Soil	2	0.03	40	0.004	<1	0.18	0.025	0.02	<0.1	0.02	0.2	<0.1	<0.05	<1	<0.5	<0.2
1282813	Soil	23	0.18	606	0.001	1	0.96	0.005	0.06	<0.1	0.20	3.1	0.1	<0.05	3	1.5	<0.2
1282814	Soil	12	0.03	188	0.009	1	0.44	0.006	0.04	0.1	0.14	0.7	0.2	<0.05	4	1.5	<0.2
1282815	Soil	10	0.02	135	0.005	2	0.29	0.003	0.04	<0.1	0.05	0.3	0.2	<0.05	3	1.3	<0.2
1282816	Soil	26	0.15	659	0.004	4	0.76	0.007	0.08	0.1	1.25	1.9	0.4	0.07	2	4.7	<0.2
1282817	Soil	29	0.11	1047	0.005	6	0.76	0.004	0.10	0.1	1.43	2.7	0.5	<0.05	2	6.1	0.2
1282818	Soil	21	0.05	712	0.003	4	0.44	0.003	0.08	0.1	0.53	2.0	0.5	<0.05	2	5.7	0.2
1282819	Soil	26	0.09	721	0.004	4	0.66	0.009	0.09	0.1	1.63	1.1	0.6	<0.05	3	6.3	0.2
1282820	Soil	27	0.05	630	0.003	3	0.49	0.005	0.07	0.2	1.11	0.9	0.5	<0.05	2	5.7	<0.2
1282821	Soil	26	0.11	853	0.005	5	0.64	0.004	0.09	0.1	1.40	2.0	0.6	<0.05	2	5.4	0.3
1282822	Soil	26	0.10	771	0.006	5	0.56	0.005	0.09	0.1	0.80	1.8	0.6	<0.05	2	8.0	0.2
1282823	Soil	27	0.05	635	0.004	4	0.57	0.004	0.09	0.1	0.90	2.2	0.7	0.07	2	10.4	0.2
1282824	Soil	29	0.06	712	0.004	5	0.59	0.005	0.09	0.1	1.37	1.0	0.8	0.07	2	9.0	0.3
1282825	Soil	29	0.05	614	0.003	4	0.52	0.003	0.09	0.1	1.28	1.5	0.7	0.10	2	9.8	<0.2
1282826	Soil	22	0.03	427	0.003	3	0.53	0.003	0.08	0.1	0.35	0.4	0.7	0.07	3	6.8	<0.2
1282827	Soil	25	0.04	304	0.003	2	0.57	0.005	0.07	0.1	0.38	0.3	0.5	<0.05	4	4.8	<0.2
1282828	Soil	27	0.11	410	0.005	3	0.83	0.004	0.08	0.1	0.77	1.4	0.5	<0.05	3	6.8	<0.2
1282829	Soil	27	0.08	466	0.007	3	0.79	0.004	0.09	0.1	0.20	0.6	0.7	<0.05	4	5.3	<0.2
1282830	Soil	29	0.07	449	0.006	4	0.78	0.003	0.09	0.1	0.39	1.8	0.6	<0.05	3	6.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282831	Soil		11.8	26.1	16.3	132	2.2	21.9	2.8	71	1.59	15.9	0.9	0.1	71	0.7	4.1	0.3	155	0.03	0.121	8
1282832	Soil		7.0	14.8	13.0	61	1.6	12.3	1.9	41	0.97	11.8	1.6	<0.1	35	0.3	2.2	0.2	114	0.03	0.094	7
1282833	Soil		8.9	40.1	12.5	75	1.4	17.9	1.8	52	1.39	12.5	4.3	<0.1	107	0.4	6.6	0.2	269	0.12	0.210	7
1282834	Soil		8.5	27.3	15.5	130	2.3	22.4	2.2	67	1.87	18.6	4.4	0.5	139	0.5	4.8	0.2	168	0.19	0.297	8
1282835	Soil		9.1	22.8	17.1	121	1.6	19.6	2.8	71	1.97	20.2	1.8	0.1	69	0.4	4.0	0.3	127	0.03	0.164	8
1282836	Soil		9.7	22.8	15.3	132	2.0	21.5	2.7	56	1.69	16.6	2.2	0.2	79	0.6	4.1	0.3	139	0.07	0.150	9
1282837	Soil		5.6	19.9	13.2	93	0.4	17.6	2.9	106	1.76	11.9	1.1	0.8	31	0.4	2.8	0.2	100	0.04	0.081	8
1282838	Soil		15.7	43.0	17.8	262	1.2	44.1	3.7	57	1.93	18.7	1.6	0.3	134	1.3	8.7	0.3	167	0.04	0.170	9
1282839	Soil		7.1	23.4	17.1	105	1.8	16.3	2.7	59	1.52	13.4	1.7	0.3	46	1.0	3.6	0.2	99	0.02	0.057	9
1282840	Soil		4.4	15.1	11.5	64	1.2	10.6	2.3	60	1.12	10.7	1.9	0.2	17	0.5	1.6	0.2	65	0.03	0.047	8
1282841	Soil		2.8	10.4	10.4	57	0.9	9.1	1.7	41	0.84	9.2	1.2	0.4	11	0.2	1.7	0.2	46	0.02	0.030	9
1282842	Soil		3.9	16.9	13.6	119	0.7	16.9	3.4	108	2.23	15.0	1.2	0.8	16	0.5	2.5	0.2	80	0.03	0.067	10
1282843	Soil		5.3	31.0	13.6	173	0.7	29.3	4.9	177	2.34	27.8	9.9	0.5	32	0.8	5.8	0.2	82	0.06	0.144	7
1282844	Soil		5.8	43.0	13.8	254	0.8	39.6	6.3	181	2.38	37.4	10.7	0.9	50	1.1	6.2	0.2	92	0.21	0.132	9
1282845	Soil		6.5	46.0	13.7	240	2.1	40.7	6.2	185	2.23	32.3	16.3	1.0	48	1.4	6.9	0.2	89	0.27	0.106	7
1282846	Soil		4.8	29.7	10.4	168	0.3	26.7	4.4	97	1.83	13.7	2.6	0.6	24	1.1	3.3	0.2	50	0.06	0.075	5
1282847	Soil		3.7	37.4	10.1	200	0.6	28.9	6.5	215	1.94	11.6	6.1	1.0	44	2.4	3.2	0.2	51	0.37	0.101	6
1282848	Soil		6.4	32.6	13.6	126	1.3	22.3	4.6	195	1.57	21.3	4.5	0.3	21	2.5	2.9	0.3	75	0.05	0.108	4
1282849	Soil		10.6	20.7	18.3	116	0.4	23.4	3.0	46	1.39	28.2	1.6	0.1	22	0.5	4.4	0.2	97	0.02	0.048	9
1282850	Soil		12.5	16.2	10.6	109	0.6	23.2	2.5	32	1.23	23.9	1.4	0.6	17	0.4	4.5	0.1	97	0.01	0.046	6
1282851	Soil		12.6	27.7	22.1	200	0.7	31.3	2.9	57	2.16	33.6	2.4	0.2	45	0.7	6.1	0.3	125	0.02	0.089	6
1282852	Soil		13.6	76.6	15.9	389	1.7	68.5	11.6	402	3.27	48.2	10.9	1.3	82	7.0	10.4	0.2	138	0.42	0.314	6
1282853	Soil		9.2	16.6	17.6	97	0.8	21.1	2.8	57	1.65	36.0	8.0	0.8	26	0.2	4.6	0.2	118	0.03	0.083	6
1282854	Soil		8.7	16.2	20.7	96	0.5	20.7	2.5	32	1.14	21.3	2.9	0.6	27	0.1	3.8	0.3	78	0.02	0.048	8
1282855	Soil		9.4	20.7	14.0	123	0.4	22.9	2.3	38	1.45	27.3	2.4	0.2	22	0.4	5.2	0.2	104	0.02	0.065	6
1282856	Soil		6.1	12.3	7.5	43	0.4	9.2	1.1	16	0.66	6.1	0.8	<0.1	15	0.2	1.7	0.1	73	0.02	0.033	5
1282857	Soil		12.5	29.5	17.2	105	0.6	21.7	2.6	40	1.67	20.5	0.7	0.1	33	0.2	4.5	0.2	147	0.03	0.054	9
1282858	Soil		11.3	30.8	11.1	74	2.0	16.1	2.0	28	1.21	14.0	0.7	0.1	18	0.5	3.6	0.2	134	0.02	0.039	8
1282859	Soil		16.1	47.9	19.1	264	1.6	44.0	2.6	63	3.04	56.1	7.0	1.1	33	0.8	10.3	0.2	175	0.12	0.253	5
1282860	Soil		4.8	19.8	9.6	106	0.3	12.7	1.7	224	0.85	6.0	<0.5	<0.1	26	2.3	1.7	0.1	50	0.10	0.060	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282831	Soil	20	0.02	325	0.003	2	0.47	0.004	0.06	0.1	0.20	0.3	0.6	<0.05	3	4.6	<0.2
1282832	Soil	16	0.03	190	0.004	2	0.55	0.006	0.05	0.1	0.22	0.2	0.5	<0.05	4	2.7	<0.2
1282833	Soil	31	0.03	390	0.002	3	0.56	0.003	0.07	<0.1	1.63	0.2	1.0	<0.05	3	6.2	<0.2
1282834	Soil	27	0.06	407	0.004	2	0.78	0.003	0.07	0.2	0.68	0.7	0.7	<0.05	4	5.7	0.2
1282835	Soil	18	0.04	270	0.006	<1	0.67	0.004	0.05	0.2	0.22	0.4	0.6	<0.05	4	3.8	<0.2
1282836	Soil	18	0.04	324	0.006	2	0.62	0.004	0.06	0.2	0.29	0.5	0.4	<0.05	3	3.7	<0.2
1282837	Soil	18	0.08	189	0.004	3	0.70	0.007	0.06	<0.1	0.08	1.1	0.3	<0.05	3	1.1	<0.2
1282838	Soil	31	0.02	588	0.003	5	0.54	0.003	0.09	0.1	0.19	0.8	0.6	0.08	3	6.6	<0.2
1282839	Soil	11	0.03	196	0.006	2	0.49	0.006	0.05	0.2	0.06	0.8	0.2	<0.05	3	1.7	<0.2
1282840	Soil	10	0.04	185	0.010	3	0.53	0.007	0.05	<0.1	0.06	0.3	0.2	<0.05	3	0.8	<0.2
1282841	Soil	8	0.02	105	0.010	2	0.36	0.007	0.04	0.1	0.11	0.7	0.2	<0.05	3	0.7	<0.2
1282842	Soil	15	0.08	175	0.012	2	0.67	0.004	0.07	0.1	0.05	1.2	0.2	<0.05	4	0.7	<0.2
1282843	Soil	28	0.12	809	0.003	3	0.96	0.005	0.08	0.1	0.13	1.3	0.3	<0.05	3	1.6	<0.2
1282844	Soil	29	0.16	1019	0.003	5	0.99	0.005	0.12	0.1	0.44	2.3	0.3	<0.05	3	2.5	<0.2
1282845	Soil	27	0.16	1145	0.003	5	0.95	0.008	0.15	0.1	0.93	2.5	0.4	0.05	3	2.4	<0.2
1282846	Soil	17	0.05	400	0.002	5	0.44	0.003	0.08	0.1	0.11	1.6	0.2	<0.05	2	1.2	<0.2
1282847	Soil	13	0.11	1290	0.003	4	0.57	0.005	0.10	<0.1	0.20	2.3	0.2	<0.05	2	1.1	<0.2
1282848	Soil	21	0.04	490	0.003	5	0.72	0.013	0.11	<0.1	0.44	0.8	0.8	<0.05	3	1.3	<0.2
1282849	Soil	10	0.02	179	0.004	2	0.37	0.005	0.05	0.1	0.06	0.4	0.4	<0.05	3	1.3	<0.2
1282850	Soil	8	0.02	203	0.004	1	0.34	0.007	0.04	0.1	0.09	0.7	0.4	<0.05	2	1.4	<0.2
1282851	Soil	15	0.02	348	0.004	2	0.37	0.003	0.07	0.1	0.12	0.9	0.6	0.07	3	2.6	<0.2
1282852	Soil	35	0.06	1725	0.003	5	0.56	0.003	0.09	0.1	1.01	3.6	0.6	0.07	2	4.1	<0.2
1282853	Soil	14	0.03	520	0.005	2	0.43	0.006	0.05	0.1	0.26	1.0	0.4	<0.05	3	1.7	<0.2
1282854	Soil	12	0.02	190	0.003	2	0.39	0.005	0.06	0.1	0.32	0.9	0.4	<0.05	3	1.5	<0.2
1282855	Soil	15	0.02	414	0.002	3	0.39	0.005	0.05	0.1	0.18	0.7	0.3	<0.05	3	1.5	<0.2
1282856	Soil	15	0.01	303	0.003	2	0.32	0.006	0.04	0.1	0.05	0.2	0.2	<0.05	2	1.0	<0.2
1282857	Soil	27	0.03	530	0.008	2	0.47	0.006	0.06	0.2	0.07	0.5	0.5	<0.05	3	2.1	<0.2
1282858	Soil	17	0.01	743	0.006	3	0.47	0.007	0.04	0.1	0.09	0.5	0.3	<0.05	3	1.6	<0.2
1282859	Soil	23	0.03	418	0.003	3	0.50	0.006	0.06	0.2	1.99	1.9	0.6	0.06	2	3.7	<0.2
1282860	Soil	12	0.02	904	0.005	2	0.38	0.007	0.04	<0.1	0.04	0.3	0.2	<0.05	2	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282861	Soil	8.1	27.9	19.2	105	0.8	18.4	2.7	54	2.67	32.4	0.7	<0.1	27	0.3	6.1	0.2	85	0.01	0.080	5
1282862	Soil	3.2	8.1	8.3	35	<0.1	6.4	1.3	39	0.80	8.2	1.3	<0.1	9	0.1	1.1	0.2	62	0.02	0.023	9
1282863	Soil	8.0	25.2	12.0	79	0.2	15.7	2.7	49	1.48	14.7	1.6	<0.1	15	0.2	2.6	0.2	88	0.02	0.060	9
1282864	Soil	3.8	13.5	9.7	67	0.4	12.0	2.4	55	1.18	13.4	1.6	0.3	11	0.1	1.8	0.2	52	0.01	0.038	8
1282865	Soil	2.9	21.6	12.2	75	0.6	12.3	2.9	170	1.35	9.1	2.0	0.3	25	0.9	1.2	0.2	53	0.06	0.104	7
1282866	Soil	5.4	15.5	12.3	80	0.3	15.1	2.4	73	1.07	13.9	1.5	0.1	22	0.3	2.3	0.2	56	0.08	0.050	7
1282867	Soil	6.9	30.7	14.5	145	0.6	21.9	4.4	169	2.04	20.1	5.0	0.3	39	2.2	3.1	0.2	84	0.11	0.119	8
1282868	Soil	5.6	16.8	13.6	77	0.2	14.3	3.3	108	1.82	18.3	0.8	0.3	14	0.1	2.8	0.2	56	0.01	0.038	5
1282869	Soil	9.8	45.0	20.6	248	0.8	37.0	5.7	131	3.11	34.2	2.8	0.4	31	0.6	6.9	0.3	118	0.02	0.124	6
1282870	Soil	5.9	39.6	13.0	134	0.5	22.7	3.3	61	2.13	18.1	3.2	0.2	17	0.8	3.5	0.2	69	0.05	0.108	6
1284031	Soil	0.3	2.3	2.7	5	<0.1	1.4	1.8	158	0.49	2.0	0.6	<0.1	7	<0.1	0.2	<0.1	9	0.04	0.037	1
1284032	Soil	<0.1	3.3	0.8	6	<0.1	1.1	0.8	18	0.27	1.1	<0.5	0.2	20	<0.1	<0.1	<0.1	9	0.22	0.058	2
1284033	Soil	3.3	17.5	13.3	74	<0.1	14.6	4.5	55	1.65	18.8	<0.5	0.5	9	<0.1	1.7	0.3	48	0.01	0.050	5
1284034	Soil	4.1	23.7	16.5	104	0.2	26.3	5.7	71	3.29	19.3	<0.5	1.4	9	0.2	1.8	0.2	42	0.01	0.070	4
1284035	Soil	2.5	9.8	10.7	54	<0.1	12.6	3.4	56	1.13	9.8	0.9	0.1	7	0.1	0.9	0.2	35	0.02	0.039	7
1284036	Soil	2.1	6.7	4.8	31	<0.1	8.7	2.2	40	0.81	5.4	<0.5	0.2	6	0.1	0.6	0.1	21	0.02	0.030	3
1284037	Soil	2.9	17.9	15.6	131	0.2	22.0	7.3	115	2.96	21.1	0.7	1.2	9	0.6	1.8	0.2	41	0.03	0.073	4
1284038	Soil	1.6	18.8	12.2	43	0.5	11.2	2.8	50	1.06	6.1	0.5	1.2	8	0.3	0.5	0.1	20	0.03	0.036	7
1284039	Soil	0.4	3.1	2.4	9	0.3	1.9	0.9	23	0.32	1.7	<0.5	0.2	4	<0.1	0.2	<0.1	8	0.01	0.022	1
1284040	Soil	3.4	89.2	30.9	135	0.2	39.7	10.8	303	4.25	13.9	8.6	2.1	50	0.2	0.9	0.4	35	0.04	0.072	4
1284041	Soil	2.7	61.7	28.7	104	0.5	35.3	35.2	1105	4.01	13.9	4.5	2.4	33	0.1	1.1	0.3	36	0.03	0.096	4
1284042	Soil	0.5	11.2	5.6	11	0.3	3.9	1.1	56	0.67	2.4	0.7	0.2	7	<0.1	0.1	<0.1	8	0.02	0.032	<1
1284043	Soil	1.1	21.2	8.5	30	1.1	10.9	2.2	42	0.84	11.0	<0.5	0.5	18	<0.1	0.5	0.1	14	0.07	0.064	2
1284044	Soil	0.6	12.2	4.5	17	0.3	4.8	1.1	17	0.52	6.2	<0.5	0.1	6	0.1	0.3	<0.1	11	0.02	0.032	<1
1284045	Soil	2.2	68.8	18.3	173	0.9	64.5	17.5	435	3.02	114.9	1.7	2.2	58	0.6	3.9	0.2	21	0.24	0.075	4
1284046	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284047	Soil	1.4	13.2	11.7	26	<0.1	6.8	1.9	39	1.02	11.0	0.5	0.9	6	<0.1	0.5	0.2	26	0.03	0.033	3
1284048	Soil	0.7	3.9	3.3	11	0.3	3.3	1.0	20	0.45	2.6	<0.5	0.2	4	<0.1	0.2	<0.1	13	0.02	0.022	2
1284049	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284050	Soil	2.5	18.5	21.2	76	0.3	28.1	12.9	790	2.71	10.7	3.3	1.7	18	<0.1	0.7	0.2	39	0.12	0.078	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282861	Soil	12	0.02	571	0.004	2	0.41	0.006	0.06	0.1	0.05	0.5	0.4	0.08	3	2.8	<0.2
1282862	Soil	9	0.03	158	0.007	1	0.50	0.005	0.03	<0.1	0.03	0.4	0.2	<0.05	3	0.5	<0.2
1282863	Soil	16	0.02	300	0.004	2	0.60	0.006	0.05	0.1	0.06	0.3	0.3	<0.05	3	1.0	<0.2
1282864	Soil	8	0.02	121	0.005	2	0.40	0.004	0.05	<0.1	0.04	0.6	0.2	<0.05	3	<0.5	<0.2
1282865	Soil	16	0.07	437	0.003	2	0.72	0.006	0.06	0.1	0.12	0.6	0.3	<0.05	3	0.8	<0.2
1282866	Soil	10	0.03	372	0.006	3	0.33	0.005	0.06	<0.1	0.06	0.4	0.2	<0.05	2	1.1	<0.2
1282867	Soil	18	0.12	552	0.006	2	0.65	0.004	0.07	0.1	0.31	1.2	0.3	0.06	3	2.2	<0.2
1282868	Soil	10	0.02	129	0.004	2	0.41	0.006	0.05	0.1	0.06	0.7	0.2	<0.05	3	1.2	<0.2
1282869	Soil	14	0.03	274	0.003	2	0.46	0.003	0.07	0.1	0.09	1.2	0.3	<0.05	3	2.7	<0.2
1282870	Soil	14	0.03	509	0.003	2	0.53	0.006	0.06	0.1	0.07	0.7	0.2	<0.05	2	1.8	<0.2
1284031	Soil	2	0.02	30	0.005	<1	0.29	0.023	0.02	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2
1284032	Soil	2	0.05	48	0.035	1	0.35	0.044	0.02	<0.1	<0.01	0.5	<0.1	0.10	2	0.6	<0.2
1284033	Soil	8	0.02	121	0.002	2	0.45	0.004	0.03	<0.1	0.02	0.9	<0.1	<0.05	3	0.9	<0.2
1284034	Soil	20	0.12	124	0.002	2	1.00	0.006	0.04	<0.1	0.04	1.7	0.1	<0.05	4	1.0	<0.2
1284035	Soil	10	0.04	82	0.006	1	0.42	0.005	0.03	<0.1	0.01	0.3	0.1	<0.05	3	<0.5	<0.2
1284036	Soil	8	0.02	101	0.005	1	0.42	0.014	0.03	<0.1	0.02	0.4	<0.1	<0.05	2	<0.5	<0.2
1284037	Soil	14	0.12	269	0.002	2	0.87	0.006	0.06	<0.1	0.02	1.6	<0.1	<0.05	3	0.9	<0.2
1284038	Soil	9	0.05	298	0.002	1	1.02	0.016	0.04	<0.1	0.06	1.4	0.2	<0.05	3	<0.5	<0.2
1284039	Soil	2	<0.01	51	0.006	1	0.26	0.018	0.02	<0.1	0.02	0.3	<0.1	<0.05	1	<0.5	<0.2
1284040	Soil	47	0.50	340	0.002	2	1.59	0.007	0.06	<0.1	0.06	3.0	0.1	<0.05	5	1.1	<0.2
1284041	Soil	40	0.44	222	0.004	3	1.53	0.006	0.06	<0.1	0.06	3.0	0.2	<0.05	4	1.4	<0.2
1284042	Soil	6	0.05	72	0.005	1	0.29	0.019	0.03	<0.1	0.06	0.6	<0.1	<0.05	1	<0.5	<0.2
1284043	Soil	15	0.04	276	0.003	2	0.39	0.010	0.03	<0.1	0.11	1.2	<0.1	<0.05	1	0.9	<0.2
1284044	Soil	5	0.01	72	0.003	2	0.19	0.012	0.02	<0.1	0.04	0.5	<0.1	<0.05	<1	0.6	<0.2
1284045	Soil	21	0.17	604	<0.001	3	0.74	0.004	0.08	<0.1	0.74	3.5	0.1	0.08	2	3.2	<0.2
1284046	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284047	Soil	9	0.02	53	0.002	2	0.45	0.004	0.03	<0.1	0.03	0.7	<0.1	<0.05	4	<0.5	<0.2
1284048	Soil	3	0.01	27	0.005	<1	0.25	0.015	0.02	<0.1	0.03	0.5	<0.1	<0.05	1	<0.5	<0.2
1284049	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284050	Soil	26	0.38	200	0.005	2	1.20	0.007	0.06	0.1	0.13	2.3	0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1284051	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284052	Soil	4.0	14.3	15.1	54	0.1	14.4	5.2	157	1.92	10.4	<0.5	1.2	9	<0.1	1.2	0.3	51	0.02	0.057	5
1284053	Soil	4.0	42.1	16.1	130	0.4	36.5	9.5	297	3.06	13.1	1.9	2.8	30	0.5	2.1	0.2	41	0.15	0.117	6
1284054	Soil	3.8	20.2	14.3	71	0.6	22.0	5.1	177	2.52	9.4	2.6	1.9	18	0.2	1.6	0.2	44	0.11	0.094	5
1284055	Soil	3.6	23.0	11.4	90	0.2	26.3	5.4	131	2.20	9.1	1.7	1.9	23	0.3	1.4	0.2	45	0.14	0.089	4
1284056	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284057	Soil	46.9	18.8	88.7	457	0.3	120.3	4.3	1089	2.51	132.7	1.1	0.6	15	1.8	6.8	<0.1	172	0.09	0.054	9
1284058	Soil	15.3	49.0	56.2	1245	1.0	176.3	6.1	580	2.19	25.7	5.5	1.9	93	11.7	4.7	0.2	63	1.04	0.128	12
1284059	Soil	14.9	37.6	37.9	339	0.9	62.0	6.2	146	1.89	20.9	3.7	2.3	97	1.7	3.7	0.3	94	0.45	0.218	13
1284060	Soil	6.5	47.1	14.0	282	1.3	63.3	10.9	129	2.30	7.3	2.4	3.5	46	2.0	2.3	0.2	23	0.60	0.091	16
1284061	Soil	28.4	21.6	18.9	282	0.5	56.8	3.9	147	1.51	25.0	0.6	1.3	43	1.6	7.6	0.2	295	0.14	0.070	12
1284062	Soil	61.3	72.3	43.1	788	0.7	129.1	12.2	329	5.45	58.3	2.6	5.0	50	2.7	14.3	0.5	274	0.13	0.234	36
1284063	Soil	41.8	63.6	9.5	875	2.5	139.0	4.1	246	1.30	49.4	0.9	1.1	25	12.3	21.3	0.1	165	0.16	0.069	9
1284064	Soil	44.4	17.0	18.4	245	0.4	84.9	2.3	39	1.22	22.3	<0.5	0.2	23	0.6	9.9	0.2	297	0.02	0.046	13
1284065	Soil	31.2	75.8	15.3	1204	0.9	147.0	6.9	198	2.04	30.9	0.7	1.1	41	16.9	11.0	0.2	323	0.31	0.107	15
1284066	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284067	Soil	15.4	29.7	15.3	390	0.6	73.7	6.4	702	1.44	12.0	1.6	1.5	33	7.8	2.4	0.1	56	0.31	0.083	7
1284068	Soil	10.0	15.7	9.6	126	0.2	18.8	4.2	131	1.78	14.4	<0.5	1.8	18	0.7	1.8	0.2	46	0.15	0.048	8
1284069	Soil	4.8	34.7	10.9	168	0.3	36.9	6.9	169	2.55	23.2	3.0	1.6	27	1.4	2.6	0.2	40	0.15	0.074	6
1284070	Soil	5.1	45.4	13.3	208	0.5	42.3	8.5	283	2.99	27.1	2.8	3.0	42	1.5	3.0	0.2	42	0.25	0.115	7
1284241	Soil	17.0	43.1	10.4	1943	0.7	208.1	17.9	711	2.51	20.5	2.4	1.4	73	11.2	5.7	0.2	84	0.67	0.093	6
1284242	Soil	5.3	43.6	12.7	191	0.4	37.3	8.2	275	2.86	25.4	3.0	2.8	34	1.4	2.7	0.2	42	0.16	0.108	8
1284243	Soil	4.8	36.3	12.2	153	0.4	31.2	6.5	192	2.63	22.7	5.0	2.3	30	0.9	2.6	0.2	42	0.13	0.089	7
1284244	Soil	4.5	34.3	10.8	145	0.4	27.8	5.9	174	2.34	21.0	3.4	1.5	27	0.9	2.3	0.2	39	0.11	0.087	6
1284245	Soil	4.6	34.7	11.5	158	0.3	29.9	6.2	157	2.45	21.3	3.0	2.2	31	1.0	2.5	0.2	41	0.13	0.092	7
1284246	Soil	5.2	44.5	12.4	205	0.5	42.0	8.6	268	2.89	26.9	4.4	3.0	37	1.4	3.0	0.2	44	0.17	0.112	8
1284247	Soil	5.5	24.1	14.4	100	0.6	23.1	6.3	224	2.49	13.5	6.5	2.5	38	0.5	1.9	0.3	57	0.22	0.081	10
1284248	Soil	3.4	24.6	16.9	98	0.9	22.1	6.1	239	2.34	16.2	7.1	2.6	33	0.6	1.5	0.3	70	0.18	0.080	11
1284249	Soil	3.7	19.5	8.7	94	0.3	20.7	5.0	143	1.95	6.1	4.8	2.2	30	0.3	0.9	0.2	40	0.16	0.071	8
1284250	Soil	2.0	27.0	12.5	82	1.2	21.2	3.8	100	1.94	7.3	6.6	2.1	34	0.6	1.1	0.3	40	0.19	0.100	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284051	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284052	Soil	16	0.18	93	0.002	1	0.76	0.004	0.05	<0.1	0.05	1.3	0.2	<0.05	4	0.9	<0.2
1284053	Soil	23	0.37	765	0.002	1	1.02	0.004	0.05	<0.1	0.17	2.5	0.1	<0.05	3	1.1	<0.2
1284054	Soil	21	0.30	297	0.002	2	0.98	0.005	0.05	<0.1	0.21	1.6	0.2	<0.05	3	1.0	<0.2
1284055	Soil	20	0.33	400	0.002	2	0.94	0.004	0.04	<0.1	0.36	1.8	0.1	<0.05	3	1.0	<0.2
1284056	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284057	Soil	14	0.05	140	0.003	1	0.60	0.005	0.04	0.1	0.13	0.8	0.6	<0.05	2	2.5	<0.2
1284058	Soil	13	0.12	664	0.004	4	0.51	0.006	0.08	0.2	0.29	3.4	0.5	0.09	1	2.1	<0.2
1284059	Soil	14	0.06	1028	0.004	4	0.58	0.005	0.10	<0.1	0.17	1.7	0.4	0.05	2	2.6	<0.2
1284060	Soil	8	0.11	505	0.003	3	0.35	0.007	0.07	<0.1	0.20	2.9	0.1	<0.05	<1	2.1	<0.2
1284061	Soil	22	0.11	563	0.003	2	0.54	0.005	0.09	0.2	0.07	1.3	1.5	<0.05	2	3.0	<0.2
1284062	Soil	32	0.29	610	0.005	5	1.47	0.006	0.21	0.3	0.11	2.8	1.6	<0.05	5	7.3	<0.2
1284063	Soil	16	0.05	370	0.002	2	0.57	0.002	0.05	0.2	1.19	2.6	0.7	<0.05	1	5.7	<0.2
1284064	Soil	16	0.03	126	0.004	3	0.33	0.003	0.06	0.2	0.05	0.5	1.5	<0.05	4	4.1	<0.2
1284065	Soil	27	0.16	627	0.005	3	0.83	0.006	0.09	0.3	0.30	2.4	1.7	<0.05	3	2.9	<0.2
1284066	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284067	Soil	12	0.12	746	0.003	2	0.57	0.012	0.05	<0.1	0.27	2.1	0.3	<0.05	2	2.6	<0.2
1284068	Soil	11	0.12	381	0.003	1	0.49	0.003	0.05	0.1	0.08	1.1	0.1	<0.05	2	0.9	<0.2
1284069	Soil	13	0.15	1387	0.002	2	0.65	0.005	0.05	0.2	0.15	2.5	0.2	<0.05	2	1.8	<0.2
1284070	Soil	15	0.20	1202	0.004	2	0.64	0.006	0.06	0.2	0.19	3.9	0.2	<0.05	2	1.7	<0.2
1284241	Soil	14	0.12	832	0.003	4	0.62	0.014	0.06	0.2	0.61	2.3	0.6	0.08	2	5.4	<0.2
1284242	Soil	15	0.20	1506	0.004	2	0.69	0.004	0.06	0.1	0.16	3.5	0.2	<0.05	2	1.8	<0.2
1284243	Soil	15	0.19	1582	0.003	2	0.73	0.004	0.06	0.2	0.16	2.9	0.2	<0.05	2	2.3	<0.2
1284244	Soil	14	0.16	1229	0.003	2	0.66	0.008	0.06	0.1	0.12	2.3	0.2	<0.05	2	2.1	<0.2
1284245	Soil	15	0.18	1470	0.003	2	0.71	0.004	0.06	0.1	0.16	2.8	0.1	<0.05	2	2.1	<0.2
1284246	Soil	14	0.20	1803	0.004	2	0.71	0.004	0.06	0.2	0.20	3.5	0.2	<0.05	2	2.3	<0.2
1284247	Soil	22	0.25	1279	0.003	2	1.01	0.006	0.07	0.1	0.27	2.3	0.2	0.05	3	1.6	<0.2
1284248	Soil	24	0.25	1282	0.002	3	1.18	0.006	0.09	0.1	0.45	2.9	0.3	0.05	3	1.5	<0.2
1284249	Soil	22	0.34	1371	0.004	2	0.95	0.004	0.06	<0.1	0.14	1.8	0.2	0.06	3	0.8	<0.2
1284250	Soil	24	0.27	1983	0.004	3	0.96	0.004	0.07	0.1	0.61	2.8	0.3	0.07	3	1.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283271	Soil	3.8	14.1	15.4	67	0.2	12.8	3.7	86	2.09	15.9	1.8	0.3	14	0.2	1.5	0.2	73	0.02	0.056	7
1283272	Soil	4.7	17.4	30.6	84	0.5	18.8	4.8	93	2.63	23.0	1.3	0.9	22	0.2	1.9	0.3	99	0.03	0.067	8
1283273	Soil	3.0	18.6	15.6	105	0.6	13.7	3.2	50	2.54	23.8	<0.5	0.6	15	0.2	1.2	0.2	63	0.01	0.079	4
1283274	Soil	3.5	21.8	18.3	104	0.5	16.8	4.6	80	2.98	20.0	1.1	0.9	13	0.4	1.7	0.3	64	0.01	0.079	5
1283275	Soil	2.9	19.3	22.1	119	1.0	18.4	5.4	87	3.63	20.6	1.5	1.4	21	0.3	1.5	0.2	69	0.03	0.147	4
1283276	Soil	4.1	15.0	22.5	93	0.9	16.8	4.8	90	2.45	12.7	1.1	1.2	24	0.4	1.1	0.2	64	0.03	0.072	5
1283277	Soil	1.5	7.8	28.7	18	0.6	5.4	1.0	17	0.37	3.7	0.9	<0.1	49	0.3	0.6	<0.1	27	0.05	0.055	2
1283278	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283279	Soil	2.1	12.3	7.3	40	<0.1	8.6	2.2	51	1.11	7.5	1.1	0.3	7	<0.1	0.7	0.1	40	0.02	0.032	9
1283280	Soil	4.7	44.7	25.3	126	0.3	40.9	11.8	367	4.20	31.3	8.7	2.0	37	0.3	1.9	0.4	40	0.02	0.058	3
1283281	Soil	0.4	4.2	1.9	11	0.7	3.9	0.7	15	0.28	0.6	0.8	<0.1	5	0.1	0.1	<0.1	6	0.03	0.029	1
1283282	Soil	2.1	41.7	12.1	118	1.4	36.2	6.5	405	2.37	12.4	7.4	1.3	44	0.3	1.4	0.2	39	0.38	0.129	8
1283283	Soil	1.8	31.3	12.1	110	0.2	32.3	7.6	210	2.75	12.3	3.4	2.8	30	0.3	1.2	0.2	29	0.18	0.091	7
1283284	Soil	1.0	5.2	2.4	18	0.2	4.8	1.1	22	0.44	3.6	<0.5	0.2	6	<0.1	0.3	<0.1	15	0.04	0.018	3
1283285	Soil	1.5	19.4	12.1	86	1.5	23.6	5.1	456	1.81	8.0	2.5	0.7	83	1.2	0.6	0.2	54	1.46	0.142	13
1283286	Soil	0.6	9.1	4.1	33	0.2	8.2	2.3	103	0.78	3.3	1.7	0.3	49	0.2	0.3	<0.1	17	0.99	0.053	3
1283287	Soil	1.5	23.2	11.6	111	0.7	28.9	6.5	230	2.08	9.6	5.5	1.1	65	0.7	1.1	0.1	34	1.45	0.094	7
1283288	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283289	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283290	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286041	Soil	4.2	37.6	9.3	94	0.5	21.6	3.7	89	1.66	12.2	4.3	1.6	15	0.4	2.2	0.2	71	0.05	0.052	10
1286042	Soil	2.0	19.7	9.5	46	0.8	11.1	4.9	433	1.62	6.0	4.9	0.8	18	0.4	0.8	0.2	37	0.16	0.089	5
1286043	Soil	3.2	10.2	14.0	39	1.2	8.4	2.0	37	0.99	6.8	2.4	0.2	21	0.2	1.0	0.2	48	0.02	0.034	8
1286044	Soil	3.7	11.5	26.1	48	0.5	10.0	2.3	43	1.12	10.8	1.6	0.9	36	0.1	1.4	0.2	65	0.02	0.053	7
1286045	Soil	2.4	45.8	7.4	117	0.6	28.5	5.2	872	1.58	7.6	5.9	1.3	53	0.8	1.4	0.2	32	0.81	0.072	6
1286046	Soil	4.5	42.5	12.3	199	0.7	54.6	10.6	264	2.45	10.1	5.2	4.2	50	0.9	2.4	0.3	39	0.45	0.102	17
1286047	Soil	0.8	18.3	7.4	57	0.4	21.1	2.6	77	1.09	2.5	4.5	1.4	42	0.4	0.6	0.2	20	0.39	0.052	8
1286048	Soil	3.1	28.0	11.4	100	0.5	25.7	8.3	575	1.78	6.7	9.3	1.7	90	0.5	1.2	0.2	45	1.03	0.067	10
1286049	Soil	6.1	53.5	19.2	188	0.4	45.1	8.5	304	3.05	19.1	6.1	3.8	30	0.9	3.5	0.3	68	0.15	0.104	11
1286050	Soil	4.5	43.3	17.1	165	0.7	51.5	16.7	1337	3.52	17.1	3.9	3.0	38	1.3	1.5	0.3	47	0.25	0.100	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283271	Soil	11	0.05	164	0.006	1	0.55	0.005	0.04	0.3	0.03	0.9	0.2	<0.05	4	0.9	<0.2
1283272	Soil	14	0.06	293	0.007	1	0.66	0.005	0.04	0.1	0.04	1.7	0.2	<0.05	4	0.9	<0.2
1283273	Soil	8	0.04	113	0.005	<1	0.44	0.007	0.03	0.1	0.02	2.2	0.1	<0.05	3	1.0	<0.2
1283274	Soil	13	0.06	177	0.003	<1	0.76	0.004	0.04	<0.1	0.03	2.1	0.2	<0.05	3	1.1	<0.2
1283275	Soil	15	0.08	232	0.004	1	0.93	0.006	0.05	<0.1	0.03	3.1	0.2	<0.05	4	1.3	<0.2
1283276	Soil	12	0.07	473	0.004	1	0.72	0.007	0.06	<0.1	0.03	1.8	0.2	<0.05	3	1.0	<0.2
1283277	Soil	5	0.02	228	0.003	2	0.20	0.014	0.03	<0.1	0.04	0.4	<0.1	<0.05	1	0.8	<0.2
1283278	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283279	Soil	11	0.03	105	0.004	1	0.46	0.004	0.04	<0.1	0.02	0.4	0.1	<0.05	4	0.7	<0.2
1283280	Soil	26	0.29	2540	0.002	3	1.38	0.006	0.07	<0.1	0.07	3.1	0.2	0.08	4	2.1	<0.2
1283281	Soil	5	0.02	326	0.005	<1	0.24	0.021	0.02	<0.1	0.03	0.3	<0.1	<0.05	<1	<0.5	<0.2
1283282	Soil	24	0.25	1268	0.005	4	1.50	0.011	0.07	<0.1	0.29	4.4	0.3	0.08	4	2.0	<0.2
1283283	Soil	21	0.37	818	0.004	2	1.02	0.004	0.05	<0.1	0.11	2.7	<0.1	<0.05	3	1.1	<0.2
1283284	Soil	5	0.02	118	0.003	<1	0.20	0.017	0.03	<0.1	0.02	0.5	<0.1	<0.05	1	0.5	<0.2
1283285	Soil	30	0.08	771	0.006	3	1.08	0.008	0.04	<0.1	0.17	2.8	0.2	0.06	2	1.8	<0.2
1283286	Soil	8	0.07	309	0.008	2	0.51	0.028	0.03	<0.1	0.04	0.8	<0.1	0.06	2	0.8	<0.2
1283287	Soil	23	0.23	662	0.003	4	0.96	0.008	0.06	<0.1	0.31	2.7	0.1	0.07	3	1.5	<0.2
1283288	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283289	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283290	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286041	Soil	19	0.14	987	0.004	4	1.08	0.011	0.08	0.1	0.16	2.1	0.2	<0.05	3	0.7	<0.2
1286042	Soil	18	0.14	632	0.005	4	0.65	0.014	0.06	0.1	0.22	1.5	0.2	0.05	2	1.1	<0.2
1286043	Soil	8	0.03	222	0.009	<1	0.49	0.007	0.04	<0.1	0.03	0.6	0.2	<0.05	3	0.8	<0.2
1286044	Soil	9	0.02	290	0.005	1	0.44	0.003	0.03	<0.1	0.01	1.1	0.2	<0.05	3	1.2	<0.2
1286045	Soil	15	0.23	2248	0.004	3	0.75	0.016	0.06	0.1	0.15	1.7	0.1	<0.05	2	0.9	<0.2
1286046	Soil	25	0.41	2724	0.006	2	0.97	0.005	0.07	<0.1	0.20	2.6	0.1	<0.05	2	1.0	<0.2
1286047	Soil	15	0.19	1783	0.005	2	0.58	0.017	0.05	<0.1	0.21	1.9	0.1	<0.05	2	1.2	<0.2
1286048	Soil	21	0.30	2150	0.006	4	0.93	0.009	0.06	0.2	0.21	2.4	0.2	0.07	2	0.7	<0.2
1286049	Soil	26	0.36	822	0.003	2	1.09	0.004	0.06	0.2	0.13	2.4	0.2	<0.05	3	1.3	<0.2
1286050	Soil	31	0.50	819	0.002	2	1.49	0.007	0.07	<0.1	0.35	3.7	0.2	<0.05	4	1.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286051	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286052	Soil	3.5	47.3	12.3	132	0.7	35.1	8.8	1164	2.23	13.6	4.3	0.7	87	1.2	1.6	0.2	59	2.06	0.076	13
1286053	Soil	6.6	56.8	19.4	194	0.2	47.0	15.8	507	3.02	20.5	7.2	3.9	34	0.9	3.4	0.3	62	0.19	0.117	11
1286054	Soil	3.3	33.7	12.6	126	0.4	28.8	13.5	479	1.93	7.1	4.2	2.6	29	0.5	1.5	0.2	44	0.15	0.061	13
1286055	Soil	1.6	29.8	5.7	69	0.4	24.5	5.4	322	1.12	5.8	6.6	0.9	87	0.7	1.2	0.1	25	1.13	0.047	4
1286056	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286057	Soil	2.2	18.1	7.8	73	0.4	17.9	4.8	153	1.65	8.7	2.6	1.6	14	0.3	1.4	0.1	35	0.08	0.058	6
1286058	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286059	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286060	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1286501	Soil	2.7	31.9	11.9	70	0.3	25.4	6.2	283	1.81	9.4	2.0	0.8	52	0.7	0.8	0.2	37	0.67	0.062	3
1286502	Soil	2.1	31.4	9.5	85	0.6	35.1	8.0	348	1.73	8.3	4.5	0.7	48	0.6	1.0	0.1	25	0.57	0.053	3
1286503	Soil	4.0	30.7	15.1	124	0.5	29.0	8.9	191	2.31	12.5	2.7	1.7	38	0.6	1.4	0.2	40	0.24	0.076	4
1286504	Soil	3.8	18.3	59.9	85	1.1	14.8	3.9	69	2.35	17.1	1.2	1.4	225	0.2	1.4	0.2	69	0.03	0.167	4
1286505	Soil	3.6	12.9	14.2	67	0.3	13.0	3.9	75	1.81	18.8	0.9	0.6	12	<0.1	1.6	0.2	62	0.01	0.069	6
1286506	Soil	8.6	24.5	21.8	144	0.5	26.7	3.4	66	1.33	11.6	1.9	0.5	40	0.4	2.1	0.2	56	0.08	0.068	3
1286507	Soil	14.0	42.2	17.6	541	0.7	68.1	11.4	241	1.87	13.7	3.7	1.8	52	2.6	2.9	0.2	82	0.21	0.078	7
1286508	Soil	26.6	58.6	13.4	1478	0.8	212.1	10.9	346	1.68	19.6	4.6	1.2	141	10.6	7.3	0.2	238	1.66	0.132	7
1286509	Soil	11.1	24.6	11.6	327	1.3	51.4	8.1	354	1.95	11.4	2.9	0.7	41	2.5	1.8	0.2	66	0.33	0.090	4
1286510	Soil	11.0	41.5	13.1	1643	0.8	162.6	20.9	640	2.32	13.1	2.2	1.5	90	4.3	2.4	0.2	68	1.22	0.087	4
1286511	Soil	3.3	50.9	6.2	1574	0.3	230.4	17.2	762	0.89	2.2	2.3	0.2	215	7.9	1.5	<0.1	36	4.26	0.068	2
1286512	Soil	6.0	53.6	8.2	477	0.5	195.7	35.5	1136	1.63	7.7	3.6	0.7	145	2.1	1.3	0.2	31	2.38	0.055	3
1286513	Soil	18.1	39.3	13.8	316	0.4	67.4	9.0	324	1.92	18.8	2.3	1.9	70	3.2	4.2	0.2	88	1.02	0.093	7
1286514	Soil	10.8	38.8	8.9	350	0.4	66.0	6.9	492	1.57	10.6	2.1	0.5	111	4.5	4.5	0.1	73	2.00	0.064	5
1286515	Soil	4.1	24.0	7.0	2880	0.3	165.1	33.7	910	1.36	10.0	1.5	0.7	251	5.5	1.6	<0.1	41	7.41	0.054	3
1286516	Soil	20.9	34.2	11.3	720	0.3	99.1	8.6	180	1.72	14.4	1.6	2.1	107	2.0	2.9	0.1	72	2.25	0.106	9
1286517	Soil	10.1	34.7	12.8	1704	0.4	132.7	11.5	407	2.24	18.2	2.2	1.4	141	1.5	2.1	0.2	55	1.91	0.068	5
1286518	Soil	13.8	36.3	11.0	1615	0.3	153.7	9.6	434	1.63	11.4	2.3	1.0	113	3.2	1.9	0.1	42	2.38	0.072	4
1286519	Soil	10.7	32.6	12.2	2106	0.3	103.7	11.3	454	1.79	11.7	2.4	1.3	84	9.3	3.4	0.1	58	1.46	0.077	5
1286520	Soil	3.3	42.9	9.6	2871	0.4	139.7	7.7	443	1.30	7.8	2.8	0.8	85	13.7	2.1	0.1	46	2.10	0.074	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286051	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286052	Soil	26	0.34	3448	0.009	5	1.06	0.010	0.06	0.2	0.26	2.3	0.1	0.09	3	1.9	<0.2
1286053	Soil	24	0.37	1081	0.003	2	1.03	0.004	0.06	0.2	0.20	3.1	0.2	<0.05	3	1.3	<0.2
1286054	Soil	25	0.25	1161	0.005	4	0.91	0.004	0.06	0.1	0.10	1.8	0.2	<0.05	3	<0.5	<0.2
1286055	Soil	13	0.16	1381	0.006	2	0.55	0.021	0.04	<0.1	0.12	1.3	<0.1	<0.05	1	0.8	<0.2
1286056	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286057	Soil	14	0.20	222	0.006	<1	0.76	0.010	0.03	0.2	0.07	1.1	<0.1	<0.05	2	<0.5	<0.2
1286058	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286059	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286060	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1286501	Soil	13	0.14	874	0.002	<1	0.68	0.011	0.06	<0.1	0.09	2.0	<0.1	<0.05	2	1.5	<0.2
1286502	Soil	10	0.08	1045	0.002	1	0.61	0.019	0.04	<0.1	0.12	2.5	0.1	0.06	1	2.1	<0.2
1286503	Soil	14	0.12	1245	0.001	2	0.67	0.007	0.07	<0.1	0.11	2.9	0.2	<0.05	2	0.9	<0.2
1286504	Soil	15	0.04	1114	0.003	<1	0.78	0.004	0.04	<0.1	0.03	1.9	0.1	<0.05	3	1.3	<0.2
1286505	Soil	8	0.03	129	0.005	<1	0.46	0.002	0.03	0.1	0.02	1.0	0.1	<0.05	4	0.6	<0.2
1286506	Soil	10	0.02	476	0.002	1	0.31	0.009	0.05	<0.1	0.11	1.6	0.2	<0.05	1	1.5	<0.2
1286507	Soil	18	0.12	456	0.003	2	0.62	0.003	0.05	0.1	0.15	2.9	0.4	<0.05	2	1.0	<0.2
1286508	Soil	17	0.11	286	0.003	5	0.38	0.005	0.06	0.1	0.29	2.7	1.0	0.16	1	2.7	<0.2
1286509	Soil	10	0.07	904	0.002	2	0.64	0.015	0.05	<0.1	0.35	2.8	0.7	<0.05	2	2.1	<0.2
1286510	Soil	17	0.20	1086	0.002	3	0.77	0.007	0.06	<0.1	0.19	3.7	0.6	0.06	2	3.0	<0.2
1286511	Soil	8	0.16	576	0.003	11	0.33	0.008	0.03	<0.1	0.15	1.0	1.1	0.37	<1	4.1	<0.2
1286512	Soil	11	0.20	1116	0.001	5	0.65	0.010	0.06	<0.1	0.18	2.3	0.8	0.15	1	2.7	<0.2
1286513	Soil	16	0.17	920	0.002	2	0.53	0.004	0.06	<0.1	0.30	3.3	0.3	0.05	1	1.7	<0.2
1286514	Soil	10	0.16	782	0.003	4	0.48	0.007	0.04	<0.1	0.19	1.7	0.2	0.14	1	2.1	<0.2
1286515	Soil	9	0.18	467	0.002	8	0.46	0.011	0.04	<0.1	0.13	1.6	1.6	0.23	1	1.5	<0.2
1286516	Soil	15	0.88	642	0.002	4	0.48	0.006	0.06	<0.1	0.25	2.9	0.6	0.05	1	0.9	<0.2
1286517	Soil	13	0.30	704	0.002	5	0.59	0.006	0.06	<0.1	0.20	2.8	0.6	0.12	1	1.1	<0.2
1286518	Soil	11	0.28	560	0.002	5	0.51	0.006	0.04	<0.1	0.17	2.2	0.6	0.11	1	1.3	<0.2
1286519	Soil	15	0.21	634	0.003	3	0.63	0.006	0.06	<0.1	0.16	2.5	0.6	0.08	2	1.4	<0.2
1286520	Soil	12	0.23	571	0.002	5	0.59	0.006	0.05	<0.1	0.16	2.0	0.4	0.11	2	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286521	Soil		7.2	37.2	3.5	1854	0.2	137.5	23.7	3508	1.13	3.8	2.6	0.1	120	3.9	2.0	<0.1	14	3.69	0.066	2
1286522	Soil		4.0	27.4	9.6	1917	0.3	116.4	8.0	455	1.56	9.7	2.9	0.8	83	3.0	1.8	0.2	35	2.18	0.076	4
1286523	Soil		10.1	36.3	15.3	343	0.5	64.2	13.3	1102	1.92	17.6	2.1	1.6	68	3.6	3.1	0.2	60	1.11	0.087	7
1286524	Soil		29.7	60.3	16.5	482	0.6	82.5	8.7	230	1.96	26.8	2.0	3.2	82	4.4	6.8	0.2	173	1.55	0.147	12
1286525	Soil		3.0	21.2	7.6	69	0.4	20.6	5.4	171	1.06	7.1	0.7	0.8	83	1.1	1.2	0.1	41	1.58	0.060	4
1286526	Soil		1.3	16.8	4.7	74	0.2	17.0	2.6	194	0.63	3.6	1.3	0.5	77	0.9	0.8	<0.1	19	1.71	0.056	3
1286527	Soil		1.4	22.9	3.9	75	0.3	28.7	2.7	134	0.63	2.5	0.7	0.4	58	1.9	1.1	<0.1	23	0.90	0.047	3
1286528	Soil		3.7	32.7	9.2	105	0.5	45.9	4.8	476	1.30	5.4	1.0	0.8	61	3.8	1.7	0.2	49	0.82	0.079	6
1286529	Soil		0.5	3.6	1.2	12	0.1	5.0	0.7	22	0.25	0.8	<0.5	<0.1	23	0.3	0.2	<0.1	7	0.23	0.017	<1
1286530	Soil		4.4	35.5	11.4	170	0.7	59.7	4.1	93	1.51	8.2	3.1	2.1	44	4.3	1.0	0.2	40	0.40	0.063	6
1286531	Soil		8.5	34.2	18.2	160	0.1	32.6	5.7	129	2.67	16.1	<0.5	3.2	13	0.5	2.4	0.3	58	0.02	0.046	11
1286532	Soil		3.9	8.4	6.9	36	0.1	9.0	2.2	54	1.14	7.2	0.6	0.7	6	0.1	0.9	0.1	38	0.01	0.026	4
1286533	Soil		9.1	32.0	17.3	153	0.2	35.6	8.5	234	2.58	19.8	1.7	2.3	30	0.7	2.5	0.3	67	0.18	0.072	9
1286534	Soil		7.3	43.8	17.7	167	0.3	42.6	10.9	219	2.53	17.0	2.6	3.1	42	0.7	2.3	0.2	55	0.23	0.089	8
1286535	Soil		6.7	28.7	16.6	117	0.6	28.3	12.9	422	2.29	11.0	1.5	1.8	36	1.0	1.5	0.2	46	0.23	0.079	5
1286536	Soil		12.2	31.4	15.4	461	0.7	46.9	7.9	168	2.19	22.3	0.6	2.3	15	2.3	5.8	0.2	320	0.06	0.029	9
1286537	Soil		9.1	28.2	11.1	153	0.3	37.6	7.5	212	1.78	13.6	2.0	0.8	23	1.1	2.6	0.2	67	0.16	0.059	7
1286538	Soil		3.4	27.0	11.3	162	0.5	58.1	4.5	110	1.07	2.3	0.5	1.3	91	8.0	1.9	0.2	28	0.99	0.054	4
1286539	Soil		8.6	39.2	14.4	97	0.7	26.0	33.8	1614	2.66	12.5	2.8	1.3	55	2.2	1.4	0.3	70	0.59	0.078	5
1286540	Soil		8.2	27.0	14.2	126	0.5	31.4	4.8	83	1.75	13.3	1.3	2.1	44	0.6	1.7	0.2	60	0.32	0.090	8
1286011	Soil		3.7	6.8	9.0	42	0.2	7.1	2.2	64	1.41	14.9	<0.5	1.8	8	<0.1	1.6	0.2	62	0.02	0.040	7
1286012	Soil		3.1	9.7	14.1	59	0.4	11.3	2.9	175	2.37	20.0	1.2	1.4	11	0.3	1.6	0.3	75	0.03	0.089	8
1286013	Soil		2.4	9.9	8.2	47	1.0	9.9	2.7	61	1.55	13.0	1.5	0.9	6	0.2	1.4	0.2	54	0.01	0.054	7
1286014	Soil		2.5	9.5	9.8	50	0.5	10.5	2.4	79	1.37	13.3	2.1	0.6	7	0.1	1.3	0.2	53	0.02	0.058	8
1286015	Soil		2.6	10.6	10.1	50	0.2	8.6	2.5	79	1.54	13.0	<0.5	0.3	8	0.2	1.5	0.2	57	0.02	0.066	7
1286016	Soil		2.7	11.4	10.9	63	0.3	10.9	3.0	82	1.60	17.7	1.1	0.8	7	0.2	1.5	0.2	63	0.01	0.053	7
1286017	Soil		2.1	6.7	9.8	45	0.2	6.2	1.7	58	1.42	11.9	1.5	0.3	8	<0.1	1.0	0.2	55	0.02	0.047	9
1286018	Soil		4.8	17.4	20.0	95	1.1	17.1	4.9	208	4.13	35.1	0.9	2.1	9	0.3	2.5	0.4	118	0.02	0.295	5
1286019	Soil		1.7	8.2	6.1	40	0.2	6.4	1.7	43	0.96	7.1	0.9	0.5	7	0.3	0.8	0.1	41	0.02	0.032	7
1286020	Soil		2.9	9.4	9.7	51	0.2	9.5	2.6	86	1.71	16.2	0.9	0.8	6	0.2	1.3	0.2	57	0.01	0.062	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286521	Soil	4	0.12	852	0.005	5	0.38	0.014	0.02	<0.1	0.10	0.6	<0.1	0.15	1	2.5	<0.2
1286522	Soil	11	0.27	613	0.003	5	0.59	0.008	0.05	<0.1	0.15	1.6	0.2	0.15	1	1.6	<0.2
1286523	Soil	12	0.15	615	0.003	4	0.49	0.005	0.07	<0.1	0.25	2.6	0.2	0.11	1	1.9	<0.2
1286524	Soil	15	0.63	975	0.003	5	0.36	0.004	0.08	0.1	0.34	2.9	0.6	0.08	1	2.8	<0.2
1286525	Soil	8	0.15	419	0.005	2	0.53	0.013	0.03	<0.1	0.13	1.2	0.1	0.13	1	1.3	<0.2
1286526	Soil	6	0.12	350	0.005	6	0.39	0.020	0.03	<0.1	0.09	0.9	<0.1	0.15	1	1.1	<0.2
1286527	Soil	6	0.09	437	0.007	4	0.40	0.025	0.03	<0.1	0.15	1.1	0.1	0.09	1	1.0	<0.2
1286528	Soil	12	0.11	825	0.004	2	0.71	0.010	0.04	<0.1	0.25	2.0	0.3	0.13	2	2.7	<0.2
1286529	Soil	2	0.02	177	0.010	<1	0.15	0.030	0.02	<0.1	0.03	0.5	<0.1	<0.05	<1	0.7	<0.2
1286530	Soil	14	0.20	873	0.003	1	0.71	0.008	0.07	<0.1	0.22	2.5	0.2	0.05	2	1.5	<0.2
1286531	Soil	13	0.10	277	0.003	1	0.82	0.004	0.07	<0.1	0.07	2.2	0.2	<0.05	2	0.9	<0.2
1286532	Soil	6	0.03	112	0.004	1	0.46	0.013	0.03	<0.1	0.03	0.7	<0.1	<0.05	2	<0.5	<0.2
1286533	Soil	18	0.16	792	0.005	2	0.71	0.004	0.06	<0.1	0.06	2.1	0.2	<0.05	2	1.7	<0.2
1286534	Soil	16	0.16	1188	0.003	2	0.68	0.004	0.06	<0.1	0.14	3.6	0.2	<0.05	2	1.9	<0.2
1286535	Soil	14	0.13	1102	0.002	2	0.71	0.009	0.06	<0.1	0.15	2.8	0.2	<0.05	2	1.1	<0.2
1286536	Soil	32	0.14	946	0.002	1	0.94	0.005	0.05	0.1	0.10	1.9	0.3	<0.05	3	1.6	<0.2
1286537	Soil	11	0.08	547	0.004	1	0.56	0.008	0.05	<0.1	0.10	1.4	0.2	<0.05	2	1.4	<0.2
1286538	Soil	10	0.13	1154	0.005	2	0.46	0.009	0.04	<0.1	0.22	2.4	0.3	0.24	1	5.8	<0.2
1286539	Soil	14	0.17	791	0.004	3	0.74	0.011	0.07	<0.1	0.28	2.7	0.3	0.14	2	2.0	<0.2
1286540	Soil	16	0.19	816	0.003	3	0.68	0.007	0.07	<0.1	0.20	2.1	0.3	<0.05	2	0.7	<0.2
1286011	Soil	8	0.05	91	0.009	<1	0.44	0.004	0.04	0.2	0.01	0.7	0.1	<0.05	3	0.7	<0.2
1286012	Soil	15	0.12	160	0.008	1	0.91	0.007	0.04	0.2	0.02	1.0	0.1	<0.05	5	1.0	<0.2
1286013	Soil	10	0.03	135	0.011	<1	0.44	0.005	0.02	0.2	0.03	0.8	0.1	<0.05	4	0.7	<0.2
1286014	Soil	8	0.05	157	0.007	1	0.48	0.004	0.03	0.2	<0.01	0.7	0.2	<0.05	4	0.6	<0.2
1286015	Soil	8	0.04	113	0.009	<1	0.44	0.006	0.03	0.2	0.01	0.5	0.1	<0.05	3	0.7	<0.2
1286016	Soil	8	0.05	110	0.009	<1	0.47	0.006	0.03	0.2	0.03	0.8	0.1	<0.05	3	1.2	<0.2
1286017	Soil	8	0.07	102	0.010	<1	0.53	0.006	0.03	0.2	0.01	0.5	0.1	<0.05	4	<0.5	<0.2
1286018	Soil	21	0.11	165	0.007	<1	1.09	0.005	0.05	0.2	0.06	1.6	0.2	<0.05	6	1.5	<0.2
1286019	Soil	6	0.03	170	0.011	<1	0.36	0.005	0.03	0.2	0.02	0.5	0.1	<0.05	3	<0.5	<0.2
1286020	Soil	8	0.04	90	0.011	<1	0.45	0.006	0.03	0.2	0.01	0.7	0.1	<0.05	4	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286601	Soil		1.3	26.0	19.2	54	0.5	31.8	3.8	117	2.41	8.7	1.7	1.2	42	<0.1	0.5	0.3	24	0.12	0.106	4
1286602	Soil		1.8	27.5	27.9	91	0.1	29.9	21.3	885	3.69	13.8	1.8	2.3	29	<0.1	0.7	0.4	35	0.06	0.106	4
1286603	Soil		2.4	34.3	26.3	136	<0.1	50.2	67.6	1633	3.81	13.8	5.8	3.4	30	0.2	1.0	0.4	33	0.09	0.101	5
1286604	Soil		1.8	45.6	17.7	133	0.4	58.8	16.5	723	3.17	10.1	2.4	2.9	51	0.5	0.9	0.3	32	0.34	0.098	6
1286605	Soil		2.0	31.9	25.6	121	0.2	39.9	29.4	2262	3.98	11.1	1.4	2.5	18	<0.1	0.9	0.3	31	0.09	0.096	4
1286606	Soil		1.8	16.1	9.5	32	0.4	10.3	3.9	152	1.10	4.8	1.9	0.6	10	<0.1	0.4	0.1	23	0.04	0.071	3
1286607	Soil		2.2	30.4	24.1	79	0.2	28.1	7.6	353	3.37	10.4	3.2	2.4	13	<0.1	0.8	0.3	30	0.03	0.097	4
1286608	Soil		1.6	27.2	19.4	113	0.5	46.8	53.4	>10000	2.72	6.6	2.5	1.4	31	0.8	0.5	0.3	27	0.17	0.136	5
1286609	Soil		1.6	35.8	19.0	155	0.3	66.5	23.9	4123	2.92	8.9	1.1	1.8	32	0.8	0.6	0.3	29	0.22	0.111	6
1286610	Soil		1.4	52.1	11.6	106	1.3	29.2	7.1	172	2.14	6.0	3.5	1.0	24	0.1	0.7	0.2	25	0.10	0.068	3
1286001	Soil		2.3	34.2	11.2	123	0.8	30.5	9.3	438	1.97	10.6	3.0	1.0	39	1.3	1.2	0.2	38	0.50	0.100	8
1286002	Soil		3.6	31.3	11.2	153	0.4	26.5	5.0	131	2.44	20.4	1.2	0.5	13	0.5	1.7	0.2	45	0.06	0.084	6
1286003	Soil		4.9	34.9	18.0	158	0.3	40.0	15.5	373	3.91	41.7	3.8	3.4	23	0.6	3.6	0.2	63	0.12	0.125	7
1286004	Soil		4.4	20.9	16.2	155	0.4	24.6	6.8	215	3.43	27.6	2.1	2.3	11	0.5	2.5	0.2	65	0.03	0.062	6
1286005	Soil		4.2	12.5	14.0	86	0.2	12.2	3.6	128	3.11	25.4	<0.5	1.4	10	0.5	2.1	0.2	74	0.03	0.077	7
1286006	Soil		3.5	11.2	11.3	64	0.2	10.9	2.8	127	2.07	23.6	0.9	0.8	9	0.9	1.8	0.2	71	0.02	0.069	7
1286007	Soil		2.2	7.7	9.1	47	0.1	7.6	2.2	100	1.44	15.1	0.8	0.5	7	0.4	1.1	0.2	48	0.02	0.065	7
1286008	Soil		3.0	10.4	11.0	66	0.1	10.2	2.7	96	2.47	16.6	<0.5	0.1	8	<0.1	1.3	0.2	66	0.04	0.064	7
1286009	Soil		2.4	8.5	9.2	44	0.2	7.4	2.3	95	1.45	17.9	<0.5	0.6	6	0.2	1.1	0.2	67	0.02	0.044	8
1286010	Soil		2.0	6.7	8.9	45	0.5	7.1	1.7	56	1.39	10.6	0.8	1.2	5	0.4	1.2	0.2	66	0.02	0.027	9
1286021	Soil		1.9	6.0	7.4	26	0.2	4.2	1.2	40	1.21	8.6	<0.5	0.6	8	0.2	0.7	0.2	48	0.03	0.033	8
1286022	Soil		2.7	13.0	10.1	73	0.2	12.9	3.4	91	2.00	18.3	<0.5	0.9	6	0.4	1.4	0.3	65	0.02	0.076	7
1286023	Soil		3.4	17.6	10.0	83	0.5	14.2	3.3	99	2.56	21.3	<0.5	1.2	7	0.5	1.5	0.2	72	0.02	0.061	7
1286024	Soil		2.3	12.4	7.5	66	0.4	9.8	2.3	58	1.58	13.4	1.6	0.3	5	0.6	1.2	0.2	62	0.01	0.046	7
1286025	Soil		2.3	9.7	7.2	72	0.7	10.3	2.2	63	1.43	9.6	<0.5	0.5	6	0.7	1.0	0.2	53	0.02	0.037	6
1286026	Soil		2.3	8.2	9.6	51	0.2	7.5	1.9	95	1.47	11.8	<0.5	0.9	12	0.7	1.0	0.2	55	0.05	0.043	10
1286027	Soil		5.0	28.3	16.7	145	0.7	26.9	6.4	148	3.76	30.6	3.0	2.9	13	0.5	3.1	0.3	61	0.03	0.122	7
1286028	Soil		4.4	18.1	12.7	93	0.3	15.3	3.4	100	2.98	27.0	1.8	2.2	12	0.1	2.4	0.2	53	0.02	0.067	8
1286029	Soil		3.7	26.8	11.3	105	0.5	16.2	3.0	73	2.39	20.8	3.4	1.5	12	0.3	2.0	0.2	49	0.03	0.066	6
1286030	Soil		2.5	10.3	8.6	53	0.4	9.6	2.6	89	1.69	9.9	0.6	1.4	7	0.3	1.0	0.2	53	0.04	0.050	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286601	Soil	19	0.24	223	0.003	1	1.10	0.013	0.07	<0.1	0.11	2.6	0.1	0.11	4	<0.5	<0.2
1286602	Soil	28	0.47	139	0.003	2	1.38	0.008	0.07	<0.1	0.04	2.6	0.1	0.08	5	0.6	<0.2
1286603	Soil	29	0.55	131	0.005	1	1.59	0.006	0.07	<0.1	0.09	3.7	0.2	<0.05	4	0.8	<0.2
1286604	Soil	30	0.57	293	0.002	1	1.59	0.009	0.08	<0.1	0.17	5.1	0.1	0.05	4	1.0	<0.2
1286605	Soil	31	0.66	110	0.003	1	1.54	0.005	0.06	<0.1	0.02	2.6	0.1	<0.05	4	0.6	<0.2
1286606	Soil	12	0.11	73	0.003	<1	0.66	0.013	0.05	<0.1	0.12	1.4	0.1	<0.05	2	<0.5	<0.2
1286607	Soil	27	0.42	80	0.003	<1	1.24	0.004	0.06	<0.1	0.13	2.2	0.2	0.05	4	1.0	<0.2
1286608	Soil	22	0.30	269	0.003	2	1.38	0.011	0.07	<0.1	0.18	4.0	0.3	0.07	5	0.5	<0.2
1286609	Soil	23	0.40	248	0.003	2	1.39	0.008	0.07	<0.1	0.09	4.0	0.2	<0.05	4	<0.5	<0.2
1286610	Soil	32	0.27	135	0.003	2	0.99	0.012	0.05	<0.1	0.22	2.0	0.1	<0.05	3	1.0	<0.2
1286001	Soil	17	0.15	749	0.006	3	0.90	0.010	0.05	0.2	0.20	2.2	0.2	<0.05	3	1.5	<0.2
1286002	Soil	13	0.10	266	0.006	2	0.75	0.007	0.05	0.3	0.07	1.3	0.2	<0.05	4	1.3	<0.2
1286003	Soil	21	0.21	771	0.004	3	1.22	0.005	0.06	0.4	0.06	2.4	0.3	<0.05	3	2.1	<0.2
1286004	Soil	20	0.18	267	0.006	2	1.30	0.006	0.06	0.2	0.05	2.2	0.2	<0.05	4	1.6	<0.2
1286005	Soil	15	0.11	201	0.006	1	0.84	0.004	0.04	0.2	0.02	1.0	0.1	<0.05	4	1.0	<0.2
1286006	Soil	9	0.07	247	0.010	1	0.56	0.004	0.04	0.2	0.01	0.8	0.1	<0.05	4	0.9	<0.2
1286007	Soil	8	0.05	118	0.008	1	0.50	0.005	0.03	0.2	0.01	0.6	0.1	<0.05	3	1.0	<0.2
1286008	Soil	15	0.11	107	0.006	2	0.78	0.006	0.04	0.2	0.02	0.4	0.1	<0.05	4	0.7	<0.2
1286009	Soil	7	0.04	100	0.012	1	0.47	0.003	0.03	0.2	<0.01	0.6	0.1	<0.05	4	<0.5	<0.2
1286010	Soil	8	0.04	129	0.009	<1	0.59	0.004	0.03	0.2	0.02	0.8	0.1	<0.05	3	0.6	<0.2
1286021	Soil	9	0.06	169	0.007	1	0.76	0.007	0.03	0.2	0.02	0.8	0.1	<0.05	4	0.8	<0.2
1286022	Soil	9	0.05	129	0.007	<1	0.61	0.005	0.03	0.2	<0.01	1.0	0.2	<0.05	4	0.8	<0.2
1286023	Soil	15	0.08	218	0.008	<1	1.08	0.007	0.03	0.2	0.02	1.3	0.2	<0.05	4	0.8	<0.2
1286024	Soil	8	0.03	149	0.012	2	0.55	0.005	0.03	0.2	0.02	0.8	0.2	<0.05	4	0.6	<0.2
1286025	Soil	9	0.05	307	0.005	<1	0.77	0.007	0.03	0.1	0.01	1.0	0.1	<0.05	3	<0.5	<0.2
1286026	Soil	11	0.06	221	0.010	1	0.51	0.004	0.05	0.2	<0.01	0.7	<0.1	<0.05	4	0.5	<0.2
1286027	Soil	20	0.16	267	0.004	2	1.28	0.005	0.05	0.2	0.11	2.3	0.2	<0.05	4	2.8	<0.2
1286028	Soil	15	0.13	290	0.005	1	0.76	0.004	0.05	0.3	0.05	1.3	0.2	<0.05	3	2.5	<0.2
1286029	Soil	14	0.12	246	0.004	2	0.90	0.005	0.04	0.2	0.07	1.6	0.2	<0.05	3	1.9	<0.2
1286030	Soil	13	0.13	299	0.006	1	0.88	0.007	0.06	0.3	0.02	1.1	0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286031	Soil	2.9	21.9	10.0	87	0.3	18.3	4.3	115	1.93	15.0	3.0	1.3	17	0.3	1.5	0.2	49	0.09	0.059	10
1286032	Soil	2.9	13.7	8.6	42	0.3	6.8	1.6	54	1.44	10.8	1.4	0.5	13	0.4	0.9	0.1	36	0.05	0.084	6
1286033	Soil	3.9	30.6	12.6	119	0.3	24.1	5.7	117	2.91	27.3	1.9	2.9	17	0.6	2.5	0.2	51	0.05	0.090	9
1286034	Soil	5.0	34.8	12.1	155	0.3	28.8	5.7	158	2.65	22.2	3.1	2.4	19	0.4	2.6	0.2	48	0.06	0.079	8
1286035	Soil	5.1	32.6	14.1	139	0.3	28.0	5.1	127	2.75	25.4	2.4	2.2	24	0.5	2.2	0.2	51	0.08	0.086	8
1286036	Soil	4.6	35.0	11.5	153	0.2	28.7	5.8	179	2.65	22.6	3.3	2.0	27	0.6	2.5	0.2	41	0.10	0.082	7
1286037	Soil	4.0	31.4	11.7	131	0.4	26.9	6.5	193	2.51	20.0	3.1	1.9	34	0.9	2.2	0.3	41	0.14	0.099	8
1286038	Soil	5.3	49.1	14.4	186	0.3	39.6	8.9	214	3.24	27.6	6.2	3.5	30	1.0	3.1	0.2	49	0.09	0.069	8
1286039	Soil	4.8	37.5	12.9	172	0.3	35.5	8.1	243	2.77	25.6	3.8	2.7	32	1.1	2.8	0.2	42	0.15	0.102	7
1286040	Soil	5.1	41.9	13.0	194	0.4	39.4	9.1	282	2.91	26.4	2.5	3.1	35	1.0	2.8	0.2	42	0.20	0.103	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

CERTIFICATE OF ANALYSIS WHI11001406.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286031	Soil	15	0.18	711	0.006	2	0.90	0.007	0.06	0.2	0.06	1.5	0.1	<0.05	3	0.9	<0.2
1286032	Soil	10	0.07	456	0.004	2	0.67	0.005	0.05	0.2	0.07	0.6	0.1	<0.05	3	1.0	<0.2
1286033	Soil	18	0.17	632	0.004	2	1.07	0.004	0.06	0.2	0.06	2.0	0.2	<0.05	3	2.6	<0.2
1286034	Soil	15	0.16	1028	0.003	2	0.81	0.004	0.05	0.2	0.08	2.4	0.2	<0.05	2	1.7	<0.2
1286035	Soil	17	0.17	1415	0.004	2	0.89	0.007	0.07	0.3	0.06	2.1	0.2	<0.05	3	1.9	<0.2
1286036	Soil	15	0.17	1563	0.003	2	0.75	0.006	0.06	0.1	0.10	2.4	0.2	<0.05	2	2.2	<0.2
1286037	Soil	15	0.19	1981	0.003	2	0.78	0.004	0.06	0.1	0.16	2.3	0.2	<0.05	2	2.2	<0.2
1286038	Soil	18	0.21	1763	0.005	2	0.85	0.004	0.07	0.2	0.20	4.0	0.2	<0.05	2	2.8	<0.2
1286039	Soil	15	0.19	1521	0.004	2	0.74	0.004	0.07	0.2	0.14	2.8	0.2	<0.05	2	1.6	<0.2
1286040	Soil	15	0.19	1544	0.005	1	0.72	0.004	0.07	0.1	0.16	3.4	0.2	<0.05	2	2.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

QUALITY CONTROL REPORT WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1280999	Soil	8.8	33.6	15.4	165	0.6	34.0	7.8	156	2.44	18.7	2.8	2.4	28	1.4	2.0	0.2	53	0.25	0.100	10
REP 1280999	QC	8.4	32.6	15.2	159	0.6	32.7	7.8	148	2.32	18.3	3.8	2.3	28	1.3	2.0	0.2	52	0.25	0.099	9
1282826	Soil	12.0	37.3	15.8	129	1.2	20.7	2.5	74	1.76	18.7	2.9	0.2	108	0.7	5.7	0.2	180	0.07	0.185	9
REP 1282826	QC	12.1	38.0	16.4	131	1.3	21.1	2.5	79	1.82	20.2	9.8	0.1	112	0.8	6.0	0.2	181	0.08	0.184	9
1282841	Soil	2.8	10.4	10.4	57	0.9	9.1	1.7	41	0.84	9.2	1.2	0.4	11	0.2	1.7	0.2	46	0.02	0.030	9
REP 1282841	QC	2.9	10.8	10.5	56	0.9	9.4	1.7	41	0.86	9.2	0.5	0.5	11	0.2	1.6	0.2	47	0.02	0.031	9
1282855	Soil	9.4	20.7	14.0	123	0.4	22.9	2.3	38	1.45	27.3	2.4	0.2	22	0.4	5.2	0.2	104	0.02	0.065	6
REP 1282855	QC	10.0	21.3	15.0	130	0.4	24.9	2.3	40	1.50	28.4	2.4	0.3	22	0.5	5.7	0.2	108	0.02	0.072	6
1284042	Soil	0.5	11.2	5.6	11	0.3	3.9	1.1	56	0.67	2.4	0.7	0.2	7	<0.1	0.1	<0.1	8	0.02	0.032	<1
REP 1284042	QC	0.6	11.2	5.7	12	0.3	3.8	1.2	55	0.66	2.3	0.6	0.2	7	<0.1	0.1	<0.1	9	0.02	0.031	<1
1284068	Soil	10.0	15.7	9.6	126	0.2	18.8	4.2	131	1.78	14.4	<0.5	1.8	18	0.7	1.8	0.2	46	0.15	0.048	8
REP 1284068	QC	10.0	16.1	9.6	125	0.2	19.3	4.3	132	1.79	14.5	<0.5	1.9	18	0.7	1.9	0.2	46	0.14	0.047	8
1284242	Soil	5.3	43.6	12.7	191	0.4	37.3	8.2	275	2.86	25.4	3.0	2.8	34	1.4	2.7	0.2	42	0.16	0.108	8
REP 1284242	QC	5.3	43.3	13.4	193	0.4	38.0	8.3	278	2.91	25.4	3.6	3.0	35	1.3	2.9	0.2	43	0.17	0.110	8
1283283	Soil	1.8	31.3	12.1	110	0.2	32.3	7.6	210	2.75	12.3	3.4	2.8	30	0.3	1.2	0.2	29	0.18	0.091	7
REP 1283283	QC	1.9	32.4	12.9	112	0.2	33.8	7.9	216	2.84	12.8	3.6	2.9	32	0.4	1.3	0.2	31	0.19	0.095	7
1286053	Soil	6.6	56.8	19.4	194	0.2	47.0	15.8	507	3.02	20.5	7.2	3.9	34	0.9	3.4	0.3	62	0.19	0.117	11
REP 1286053	QC	5.9	55.4	19.2	189	0.2	46.5	14.9	477	2.94	19.2	6.5	3.9	34	1.2	3.2	0.4	57	0.18	0.107	10
1286510	Soil	11.0	41.5	13.1	1643	0.8	162.6	20.9	640	2.32	13.1	2.2	1.5	90	4.3	2.4	0.2	68	1.22	0.087	4
REP 1286510	QC	11.1	42.5	13.7	1715	0.8	162.8	21.9	722	2.49	13.3	3.1	1.6	91	4.4	2.6	0.2	71	1.18	0.083	4
1286534	Soil	7.3	43.8	17.7	167	0.3	42.6	10.9	219	2.53	17.0	2.6	3.1	42	0.7	2.3	0.2	55	0.23	0.089	8
REP 1286534	QC	6.8	43.5	16.8	163	0.3	41.4	10.2	216	2.47	16.2	2.3	2.9	38	0.7	2.2	0.2	53	0.22	0.083	7
1286019	Soil	1.7	8.2	6.1	40	0.2	6.4	1.7	43	0.96	7.1	0.9	0.5	7	0.3	0.8	0.1	41	0.02	0.032	7
REP 1286019	QC	1.6	7.7	5.9	40	0.2	7.3	1.6	43	0.96	7.1	<0.5	0.5	6	0.3	0.8	0.2	40	0.02	0.033	7
1286023	Soil	3.4	17.6	10.0	83	0.5	14.2	3.3	99	2.56	21.3	<0.5	1.2	7	0.5	1.5	0.2	72	0.02	0.061	7
REP 1286023	QC	3.1	17.7	10.4	84	0.5	13.3	3.4	100	2.50	21.2	<0.5	1.2	7	0.4	1.7	0.2	71	0.02	0.059	7
Reference Materials																					
STD DS8	Standard	12.5	107.1	122.1	300	1.6	36.7	7.4	613	2.44	23.6	107.7	6.8	74	2.5	5.7	6.3	41	0.73	0.077	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

QUALITY CONTROL REPORT WHI11001406.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1280999	Soil	16	0.18	811	0.002	2	0.84	0.004	0.06	0.1	0.36	2.5	0.2	<0.05	2	2.1	<0.2
REP 1280999	QC	15	0.18	799	0.003	2	0.82	0.004	0.06	0.1	0.33	2.5	0.2	<0.05	2	1.8	<0.2
1282826	Soil	22	0.03	427	0.003	3	0.53	0.003	0.08	0.1	0.35	0.4	0.7	0.07	3	6.8	<0.2
REP 1282826	QC	23	0.03	435	0.003	3	0.54	0.004	0.08	<0.1	0.39	0.4	0.7	0.05	3	6.7	<0.2
1282841	Soil	8	0.02	105	0.010	2	0.36	0.007	0.04	0.1	0.11	0.7	0.2	<0.05	3	0.7	<0.2
REP 1282841	QC	8	0.03	103	0.010	2	0.37	0.006	0.04	0.1	0.06	0.7	0.2	<0.05	3	<0.5	<0.2
1282855	Soil	15	0.02	414	0.002	3	0.39	0.005	0.05	0.1	0.18	0.7	0.3	<0.05	3	1.5	<0.2
REP 1282855	QC	17	0.02	444	0.005	3	0.42	0.005	0.06	<0.1	0.18	0.9	0.4	<0.05	3	2.1	<0.2
1284042	Soil	6	0.05	72	0.005	1	0.29	0.019	0.03	<0.1	0.06	0.6	<0.1	<0.05	1	<0.5	<0.2
REP 1284042	QC	6	0.05	70	0.004	<1	0.29	0.019	0.03	<0.1	0.05	0.5	<0.1	<0.05	1	<0.5	<0.2
1284068	Soil	11	0.12	381	0.003	1	0.49	0.003	0.05	0.1	0.08	1.1	0.1	<0.05	2	0.9	<0.2
REP 1284068	QC	10	0.12	382	0.002	2	0.49	0.003	0.05	0.1	0.08	1.2	0.1	<0.05	2	1.2	<0.2
1284242	Soil	15	0.20	1506	0.004	2	0.69	0.004	0.06	0.1	0.16	3.5	0.2	<0.05	2	1.8	<0.2
REP 1284242	QC	16	0.20	1585	0.008	2	0.71	0.004	0.07	0.1	0.16	3.5	0.2	<0.05	2	1.9	<0.2
1283283	Soil	21	0.37	818	0.004	2	1.02	0.004	0.05	<0.1	0.11	2.7	<0.1	<0.05	3	1.1	<0.2
REP 1283283	QC	22	0.38	876	0.005	2	1.08	0.004	0.06	<0.1	0.10	2.7	0.1	<0.05	3	1.3	<0.2
1286053	Soil	24	0.37	1081	0.003	2	1.03	0.004	0.06	0.2	0.20	3.1	0.2	<0.05	3	1.3	<0.2
REP 1286053	QC	23	0.37	1061	0.003	2	0.97	0.003	0.05	0.2	0.22	2.9	0.2	<0.05	3	1.3	<0.2
1286510	Soil	17	0.20	1086	0.002	3	0.77	0.007	0.06	<0.1	0.19	3.7	0.6	0.06	2	3.0	<0.2
REP 1286510	QC	17	0.20	1484	0.002	3	0.78	0.008	0.08	<0.1	0.24	4.2	0.7	0.05	2	2.6	<0.2
1286534	Soil	16	0.16	1188	0.003	2	0.68	0.004	0.06	<0.1	0.14	3.6	0.2	<0.05	2	1.9	<0.2
REP 1286534	QC	16	0.15	1145	0.002	1	0.65	0.004	0.06	<0.1	0.15	3.3	0.2	<0.05	2	2.2	<0.2
1286019	Soil	6	0.03	170	0.011	<1	0.36	0.005	0.03	0.2	0.02	0.5	0.1	<0.05	3	<0.5	<0.2
REP 1286019	QC	6	0.03	174	0.007	1	0.36	0.005	0.03	0.2	0.01	0.5	0.1	<0.05	3	0.6	<0.2
1286023	Soil	15	0.08	218	0.008	<1	1.08	0.007	0.03	0.2	0.02	1.3	0.2	<0.05	4	0.8	<0.2
REP 1286023	QC	15	0.08	216	0.005	1	1.06	0.007	0.04	0.2	0.02	1.4	0.2	<0.05	4	1.2	<0.2
Reference Materials																	
STD DS8	Standard	116	0.58	285	0.117	2	0.96	0.099	0.45	3.0	0.17	3.2	5.2	0.16	5	4.6	5.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

QUALITY CONTROL REPORT WHI11001406.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	12.3	101.9	114.0	285	1.7	34.5	7.1	565	2.27	23.3	102.8	6.1	66	2.3	5.3	5.8	39	0.65	0.071	14
STD DS8	Standard	12.9	108.9	121.7	310	1.8	36.3	7.4	607	2.45	25.5	190.8	6.7	69	2.3	5.8	6.6	43	0.71	0.078	15
STD DS8	Standard	13.0	111.7	127.2	305	1.7	38.4	7.8	592	2.30	22.8	110.6	7.1	69	2.1	5.9	7.0	42	0.65	0.072	14
STD DS8	Standard	14.8	118.3	137.9	304	2.0	41.3	7.8	624	2.38	24.0	103.1	7.5	74	2.5	6.0	7.6	46	0.68	0.075	15
STD DS8	Standard	14.2	113.3	124.4	313	1.8	38.5	7.7	599	2.44	25.3	121.6	6.4	66	2.8	5.8	6.5	43	0.68	0.084	15
STD DS8	Standard	11.2	106.0	112.6	300	1.8	35.1	7.0	575	2.35	24.6	103.0	5.6	58	2.2	4.8	6.1	38	0.64	0.077	12
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 07, 2011

QUALITY CONTROL REPORT WHI11001406.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
STD DS8	Standard	107	0.56	271	0.111	3	0.90	0.102	0.41	2.7	0.18	3.0	5.1	0.12	4	4.7	4.4
STD DS8	Standard	114	0.61	288	0.119	2	0.95	0.101	0.44	3.0	0.20	3.1	5.3	0.17	5	4.6	5.1
STD DS8	Standard	119	0.64	255	0.113	2	0.87	0.095	0.41	2.8	0.19	2.4	5.1	0.17	4	5.0	4.6
STD DS8	Standard	130	0.67	264	0.119	3	0.93	0.102	0.43	3.0	0.22	2.6	5.6	0.12	4	5.3	5.2
STD DS8	Standard	118	0.61	279	0.115	2	0.93	0.091	0.41	2.9	0.20	2.4	5.2	0.15	5	4.9	5.1
STD DS8	Standard	108	0.57	257	0.101	2	0.84	0.096	0.41	2.6	0.19	2.2	5.2	0.11	4	5.3	4.9
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 06, 2011
Report Date: January 19, 2012
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001408.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #23
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve soil to 230 mesh			WHI
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	320	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Version 2: Sample ID Revision - Sample 1286080 revised to 1286680

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282871	Soil	12.4	21.8	9.7	21	3.0	7.0	0.6	13	0.95	37.1	35.9	<0.1	23	<0.1	7.3	0.2	35	0.02	0.072	3
1282872	Soil	5.2	28.1	9.1	17	1.7	6.8	0.8	14	1.01	19.8	29.9	<0.1	14	<0.1	3.1	0.1	26	0.02	0.062	3
1282873	Soil	7.0	12.0	8.1	39	1.5	10.6	1.4	27	0.91	11.6	3.6	<0.1	8	<0.1	2.3	0.2	61	0.02	0.034	7
1282874	Soil	4.8	11.6	9.0	32	1.8	7.8	1.1	27	1.86	18.9	4.9	0.1	13	<0.1	2.7	0.1	36	0.02	0.111	3
1282875	Soil	7.9	14.1	18.3	54	0.5	12.3	1.7	32	1.41	20.2	3.3	0.1	15	<0.1	2.9	0.3	84	0.02	0.038	10
1282876	Soil	3.7	10.5	6.4	30	1.3	6.6	1.0	18	0.68	6.8	1.9	<0.1	7	<0.1	1.2	0.1	39	0.02	0.030	7
1282877	Soil	7.8	17.4	17.5	64	0.8	14.3	2.5	66	2.66	22.1	2.9	1.0	20	0.2	3.2	0.3	94	0.05	0.075	12
1282878	Soil	21.1	84.8	20.0	305	2.4	59.9	6.3	203	3.89	39.4	7.8	1.2	79	4.8	9.2	0.3	143	0.18	0.207	9
1282879	Soil	17.9	30.0	23.6	141	1.8	29.2	2.6	55	2.74	34.8	2.4	0.1	70	0.3	6.3	0.3	171	0.02	0.146	6
1282880	Soil	5.9	10.7	14.2	55	0.3	10.9	1.7	36	0.99	10.4	0.5	0.4	15	<0.1	1.9	0.2	78	0.02	0.030	12
1282881	Soil	8.5	21.7	15.5	80	0.5	19.6	2.7	53	1.94	18.5	0.8	<0.1	26	0.2	3.0	0.3	98	0.02	0.084	8
1282882	Soil	7.9	24.5	15.3	109	0.6	21.2	1.8	32	1.30	13.6	1.0	<0.1	46	2.8	3.1	0.2	83	0.11	0.099	6
1282883	Soil	13.4	37.1	23.0	185	1.9	29.1	4.5	1143	2.99	37.3	4.2	0.1	68	3.5	9.5	0.2	116	0.38	0.245	4
1282884	Soil	3.2	16.8	5.7	41	1.5	9.5	1.0	21	0.75	5.0	2.1	<0.1	11	1.2	1.2	<0.1	46	0.03	0.084	4
1282885	Soil	7.3	34.3	12.1	131	0.5	21.6	3.3	54	1.64	9.2	1.4	0.2	19	2.8	3.0	0.2	90	0.03	0.074	8
1282886	Soil	5.3	16.4	11.8	90	0.7	17.0	2.3	43	1.35	10.8	1.3	0.3	20	0.5	2.9	0.2	82	0.03	0.043	9
1282887	Soil	6.3	28.3	10.6	108	0.5	21.2	2.9	49	1.40	10.6	4.1	0.1	11	0.2	3.1	0.2	96	0.01	0.039	8
1282888	Soil	5.6	29.5	10.2	109	0.3	21.0	3.1	49	1.45	11.8	3.5	0.3	9	0.1	3.2	0.2	92	<0.01	0.027	9
1282889	Soil	4.6	17.4	15.0	77	0.4	15.5	2.6	96	1.98	15.7	2.3	0.2	18	0.2	2.2	0.2	90	0.04	0.086	10
1282890	Soil	4.7	23.0	15.1	93	0.4	17.6	3.2	79	1.87	12.9	3.8	0.2	22	0.5	2.1	0.2	85	0.07	0.056	11
1282891	Soil	19.3	26.1	27.9	84	1.5	17.8	1.9	31	3.12	44.3	3.6	<0.1	28	0.2	17.3	0.3	195	0.01	0.102	4
1282892	Soil	7.7	23.9	20.0	122	0.5	22.5	3.2	93	1.93	20.3	1.5	0.3	20	0.3	3.9	0.3	107	0.02	0.062	10
1282893	Soil	11.3	24.4	15.2	213	0.9	29.5	3.4	107	2.99	53.6	2.7	0.4	11	0.6	6.0	0.2	155	0.02	0.141	5
1282894	Soil	7.0	81.9	17.0	216	0.6	54.8	12.8	443	3.58	16.9	12.3	1.8	37	1.2	4.2	0.2	62	0.16	0.137	9
1282895	Soil	8.1	30.5	11.6	169	0.3	26.9	7.3	218	2.40	13.6	3.8	0.8	28	0.6	2.6	0.2	69	0.12	0.111	8
1282896	Soil	8.3	25.6	20.0	135	2.7	19.7	3.5	142	4.15	44.9	6.8	0.4	22	0.4	5.3	0.3	93	0.05	0.349	8
1282897	Soil	7.1	56.3	16.3	174	0.4	41.7	7.9	391	2.83	18.7	7.4	0.8	31	0.8	4.0	0.2	77	0.10	0.129	10
1282898	Soil	11.8	29.6	16.9	90	1.7	13.1	1.5	26	1.76	29.9	2.0	0.1	25	0.3	5.2	0.2	127	0.01	0.061	5
1282899	Soil	26.2	55.1	42.3	143	4.9	27.4	2.5	64	6.19	85.3	7.6	0.6	108	0.4	17.7	0.4	240	0.14	0.548	6
1282900	Soil	16.6	27.7	21.1	98	1.7	15.7	1.9	31	2.08	37.8	1.4	0.4	25	0.2	6.0	0.3	166	0.01	0.071	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282871	Soil	10	0.01	284	0.002	2	0.48	0.017	0.04	<0.1	1.30	0.2	0.8	0.11	2	4.0	<0.2
1282872	Soil	8	0.02	204	0.003	2	0.50	0.017	0.03	<0.1	0.64	0.5	0.4	0.05	2	3.5	<0.2
1282873	Soil	9	0.01	175	0.003	2	0.23	0.009	0.03	0.1	0.14	0.2	0.3	<0.05	2	1.1	<0.2
1282874	Soil	9	0.02	454	0.003	1	0.30	0.015	0.04	<0.1	0.45	0.2	0.4	0.07	2	2.4	<0.2
1282875	Soil	12	0.03	285	0.005	1	0.43	0.005	0.05	0.1	0.05	0.3	0.3	<0.05	4	1.5	<0.2
1282876	Soil	7	0.02	258	0.004	<1	0.42	0.017	0.03	0.1	0.06	0.1	0.2	<0.05	3	0.7	<0.2
1282877	Soil	21	0.10	522	0.011	<1	1.08	0.005	0.06	0.2	0.15	1.1	0.4	<0.05	6	2.1	<0.2
1282878	Soil	27	0.05	1704	<0.001	4	0.61	0.004	0.07	0.1	1.43	3.2	0.6	0.05	2	10.8	<0.2
1282879	Soil	22	0.02	671	0.002	1	0.42	0.006	0.10	0.2	0.10	0.4	1.0	0.16	3	3.7	<0.2
1282880	Soil	11	0.03	212	0.008	<1	0.48	0.004	0.04	0.1	0.06	0.5	0.3	<0.05	5	1.1	<0.2
1282881	Soil	18	0.04	792	0.003	<1	0.80	0.008	0.05	0.1	0.09	0.2	0.4	<0.05	4	2.1	<0.2
1282882	Soil	16	0.03	676	0.001	2	0.41	0.004	0.08	<0.1	0.06	0.2	0.4	0.05	2	2.1	<0.2
1282883	Soil	20	0.09	763	0.001	4	0.46	0.009	0.12	0.1	0.27	0.4	0.9	0.17	2	4.2	<0.2
1282884	Soil	10	0.02	351	0.003	1	0.43	0.017	0.04	<0.1	0.12	0.3	0.2	<0.05	2	1.0	<0.2
1282885	Soil	16	0.02	319	0.003	2	0.44	0.005	0.06	<0.1	0.04	0.3	0.2	<0.05	3	2.4	<0.2
1282886	Soil	11	0.03	177	0.006	1	0.33	0.005	0.06	<0.1	0.03	0.6	0.3	<0.05	3	1.7	<0.2
1282887	Soil	9	0.02	126	0.002	2	0.28	0.002	0.05	<0.1	0.03	0.4	0.2	<0.05	3	2.1	<0.2
1282888	Soil	8	0.02	95	0.004	<1	0.30	0.003	0.04	<0.1	0.03	0.6	0.2	<0.05	3	1.7	<0.2
1282889	Soil	16	0.09	133	0.007	<1	0.73	0.005	0.06	0.1	0.03	0.5	0.2	<0.05	4	1.3	<0.2
1282890	Soil	16	0.07	652	0.006	<1	0.73	0.004	0.07	0.1	0.07	0.5	0.2	<0.05	4	1.3	<0.2
1282891	Soil	24	0.04	1113	0.002	1	0.40	0.005	0.07	0.2	0.26	0.2	0.6	0.10	3	6.9	0.2
1282892	Soil	15	0.04	189	0.004	<1	0.55	0.004	0.06	0.1	0.09	0.3	0.3	<0.05	5	2.2	<0.2
1282893	Soil	16	0.03	262	0.002	<1	0.67	0.006	0.04	0.1	0.15	0.9	0.5	<0.05	4	2.2	<0.2
1282894	Soil	15	0.09	963	0.002	3	0.58	0.002	0.10	<0.1	0.21	3.4	0.3	<0.05	2	2.7	<0.2
1282895	Soil	17	0.11	353	0.003	2	0.70	0.004	0.08	<0.1	0.13	1.8	0.2	<0.05	2	1.7	<0.2
1282896	Soil	23	0.08	717	0.006	<1	0.73	0.004	0.06	0.2	0.46	0.8	0.4	0.07	4	2.9	<0.2
1282897	Soil	17	0.13	376	0.002	<1	0.85	0.004	0.08	<0.1	0.19	1.4	0.3	<0.05	2	2.1	<0.2
1282898	Soil	10	0.01	792	0.002	<1	0.37	0.007	0.04	0.2	0.11	0.3	0.3	0.07	3	2.4	<0.2
1282899	Soil	37	0.06	580	0.003	1	0.70	0.009	0.15	0.2	0.96	1.2	2.0	0.27	4	9.3	0.2
1282900	Soil	11	0.02	316	0.002	<1	0.42	0.005	0.05	0.2	0.09	0.6	0.6	<0.05	4	2.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283291	Soil	2.2	83.1	9.9	117	0.9	35.8	5.4	202	1.78	7.1	8.5	0.8	206	0.5	1.2	0.2	29	1.48	0.081	5
1283292	Soil	3.6	33.4	8.8	98	0.9	22.2	6.1	323	1.90	8.4	6.0	1.0	79	0.6	1.4	0.2	40	0.67	0.089	4
1283293	Soil	4.3	31.6	12.8	99	0.8	23.2	7.4	378	2.48	11.5	5.8	1.6	35	0.5	1.3	0.2	45	0.20	0.080	5
1283294	Soil	4.1	43.9	16.6	128	0.9	31.9	7.9	460	2.74	13.6	8.8	1.8	62	0.7	1.4	0.3	48	0.41	0.089	6
1283295	Soil	1.7	43.6	11.7	138	1.0	38.9	6.8	301	2.01	8.0	9.7	1.1	134	1.2	1.1	0.2	36	1.59	0.090	5
1283296	Soil	2.8	28.2	8.8	89	0.6	23.9	4.6	160	1.54	7.6	5.8	0.8	77	0.7	1.5	0.2	33	1.44	0.081	3
1283297	Soil	2.3	34.1	9.2	92	0.8	25.9	6.0	416	1.87	8.2	5.1	1.2	44	0.8	1.1	0.2	31	0.62	0.074	4
1283298	Soil	3.6	38.4	13.0	114	0.5	32.3	9.3	392	2.56	11.8	10.1	1.8	35	0.6	1.4	0.3	44	0.34	0.084	6
1283299	Soil	0.6	34.3	4.0	53	0.3	18.2	1.9	119	0.60	1.6	6.0	0.5	162	1.0	0.7	0.1	14	2.21	0.056	2
1283300	Soil	4.9	58.2	15.2	207	0.8	47.8	10.7	401	2.97	17.4	8.8	2.0	91	2.0	2.6	0.2	59	1.07	0.102	7
1283881	Soil	6.1	17.3	11.8	92	0.4	20.0	3.8	58	1.52	12.7	1.3	0.4	15	0.4	1.7	0.2	46	0.02	0.068	3
1283882	Soil	3.6	16.5	7.5	68	0.1	13.3	2.7	34	1.28	11.8	1.8	0.7	9	0.1	1.3	0.1	38	0.01	0.035	4
1283883	Soil	1.2	15.2	7.2	39	0.3	14.1	2.8	49	1.17	5.9	2.4	0.3	15	0.2	0.4	0.1	18	0.08	0.036	3
1283884	Soil	2.2	20.6	13.2	80	0.3	21.0	8.8	208	1.74	14.1	3.0	0.5	10	0.4	1.1	0.2	23	0.05	0.062	6
1283885	Soil	1.2	5.8	4.3	32	<0.1	6.4	1.9	39	0.73	6.7	1.8	0.3	4	0.2	0.7	0.1	22	0.01	0.019	3
1283886	Soil	2.0	28.9	11.5	137	0.6	30.8	11.3	175	2.47	13.5	3.8	1.9	103	0.6	1.0	0.2	28	0.67	0.059	4
1283887	Soil	1.2	18.2	6.1	37	0.4	13.7	2.1	35	0.79	5.0	0.6	0.6	126	0.9	0.6	0.1	17	0.95	0.042	3
1283888	Soil	2.3	15.7	7.7	86	0.4	16.9	7.2	169	1.89	11.4	2.3	1.3	84	0.4	1.2	0.1	28	0.68	0.059	4
1283889	Soil	0.4	10.6	6.1	23	0.8	11.7	3.6	41	0.82	4.6	4.8	0.3	71	0.3	0.5	<0.1	15	0.54	0.083	3
1283890	Soil	5.8	36.2	24.8	165	0.6	26.6	6.1	162	4.74	36.4	3.7	1.4	39	0.5	2.9	0.3	67	0.18	0.225	4
1283891	Soil	2.1	14.6	11.8	70	0.4	15.3	5.1	110	1.68	9.6	4.7	0.7	28	0.3	0.8	0.2	19	0.15	0.057	3
1283892	Soil	1.4	32.6	7.7	95	1.6	41.7	7.0	135	1.47	7.5	6.0	0.6	82	1.0	0.9	0.1	26	0.66	0.061	4
1283893	Soil	1.1	28.1	11.3	62	0.5	31.9	8.8	305	1.99	9.1	3.0	0.9	114	0.8	0.8	0.2	21	1.33	0.061	3
1283894	Soil	3.0	49.3	16.4	136	0.7	57.5	13.6	1116	2.34	11.1	3.6	1.3	54	1.0	1.2	0.2	34	0.50	0.075	4
1283895	Soil	4.1	83.0	21.0	72	1.1	41.1	3.2	30	2.08	10.5	4.8	1.1	59	0.6	1.3	0.2	48	0.39	0.078	3
1283896	Soil	4.0	58.3	18.5	109	0.8	35.1	9.3	237	2.40	17.0	4.2	1.4	64	0.6	1.3	0.2	37	0.42	0.082	4
1283897	Soil	2.6	32.6	15.1	200	0.6	72.6	27.5	1549	2.73	11.6	5.0	1.4	61	1.5	0.9	0.2	32	0.65	0.077	4
1283898	Soil	4.3	115.4	15.0	102	0.4	27.4	4.6	78	6.95	21.6	5.9	1.4	33	0.8	1.3	0.2	49	0.10	0.136	3
1283899	Soil	4.4	101.2	13.5	110	0.9	37.9	4.3	59	10.08	10.6	6.1	1.2	41	1.2	1.4	0.2	31	0.23	0.080	3
1283900	Soil	2.6	34.0	15.9	80	0.7	25.1	8.7	262	2.08	13.5	3.8	1.2	49	0.4	1.0	0.2	51	0.40	0.078	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283291	Soil	18	0.30	458	0.002	3	0.96	0.009	0.08	<0.1	0.32	2.1	0.2	0.17	2	3.2	<0.2
1283292	Soil	18	0.22	835	0.002	1	0.91	0.010	0.06	<0.1	0.19	1.8	0.2	0.07	3	1.1	<0.2
1283293	Soil	21	0.26	816	<0.001	<1	0.99	0.006	0.06	<0.1	0.25	2.2	0.2	<0.05	3	1.2	<0.2
1283294	Soil	23	0.29	973	<0.001	<1	1.23	0.007	0.08	<0.1	0.37	2.5	0.2	<0.05	3	1.7	<0.2
1283295	Soil	22	0.25	680	0.001	1	0.92	0.009	0.06	<0.1	0.34	2.5	0.1	0.11	2	2.2	<0.2
1283296	Soil	17	0.16	1503	0.001	2	0.77	0.009	0.06	<0.1	0.22	1.5	0.1	0.12	2	1.3	<0.2
1283297	Soil	18	0.18	1558	0.002	3	0.82	0.011	0.05	0.1	0.18	2.0	<0.1	0.06	3	1.5	<0.2
1283298	Soil	25	0.28	1224	0.002	3	1.12	0.006	0.07	<0.1	0.19	2.6	0.1	<0.05	3	1.7	<0.2
1283299	Soil	10	0.10	592	0.002	4	0.37	0.007	0.04	<0.1	0.16	0.9	<0.1	0.15	<1	1.4	<0.2
1283300	Soil	25	0.32	1442	0.002	5	1.06	0.006	0.09	0.2	0.40	3.3	0.2	0.08	3	3.1	<0.2
1283881	Soil	10	0.03	353	0.001	2	0.50	0.007	0.05	<0.1	0.06	0.8	0.2	<0.05	2	1.1	<0.2
1283882	Soil	6	0.03	154	0.001	<1	0.62	0.007	0.04	<0.1	0.03	0.9	0.1	<0.05	3	0.8	<0.2
1283883	Soil	9	0.05	220	0.002	2	0.61	0.018	0.05	<0.1	0.06	1.1	0.1	<0.05	2	0.7	<0.2
1283884	Soil	10	0.08	286	0.003	1	0.73	0.013	0.04	<0.1	0.05	1.2	0.2	<0.05	2	0.7	<0.2
1283885	Soil	3	0.02	68	0.005	<1	0.32	0.012	0.02	<0.1	<0.01	0.4	<0.1	<0.05	2	<0.5	<0.2
1283886	Soil	15	0.22	1134	0.001	2	0.65	0.005	0.07	<0.1	0.16	4.1	0.1	0.06	2	1.5	<0.2
1283887	Soil	11	0.20	643	0.004	3	0.45	0.010	0.04	<0.1	0.06	1.0	<0.1	0.07	2	0.9	<0.2
1283888	Soil	13	0.26	895	0.003	2	0.70	0.006	0.04	<0.1	0.09	2.0	0.1	0.07	2	1.4	<0.2
1283889	Soil	7	0.12	963	0.004	1	0.56	0.019	0.03	<0.1	0.13	1.4	0.1	0.10	2	1.3	<0.2
1283890	Soil	23	0.14	721	0.002	1	0.96	0.005	0.08	0.1	0.07	2.2	0.4	0.05	4	3.1	<0.2
1283891	Soil	7	0.08	1193	<0.001	<1	0.45	0.009	0.05	<0.1	0.12	1.6	0.1	<0.05	1	1.3	<0.2
1283892	Soil	9	0.11	2619	0.002	2	0.81	0.017	0.05	<0.1	0.37	2.4	0.2	0.09	2	2.3	<0.2
1283893	Soil	10	0.14	903	0.001	2	0.63	0.005	0.04	<0.1	0.13	2.5	0.1	0.14	2	4.3	<0.2
1283894	Soil	13	0.13	1266	<0.001	2	0.69	0.005	0.06	<0.1	0.25	3.7	0.3	0.07	2	5.1	<0.2
1283895	Soil	14	0.09	1158	<0.001	2	0.83	0.006	0.05	<0.1	0.29	2.9	0.6	0.12	2	6.5	<0.2
1283896	Soil	12	0.13	950	<0.001	1	0.83	0.005	0.05	<0.1	0.22	2.5	0.5	0.06	2	3.5	<0.2
1283897	Soil	12	0.11	1419	<0.001	2	0.84	0.006	0.05	<0.1	0.17	3.5	0.3	0.09	2	3.0	<0.2
1283898	Soil	12	0.07	883	<0.001	1	0.74	0.003	0.06	<0.1	0.23	2.6	1.2	0.08	2	3.1	<0.2
1283899	Soil	9	0.06	725	<0.001	3	0.69	0.005	0.05	<0.1	0.16	2.6	0.5	0.16	2	4.4	<0.2
1283900	Soil	14	0.12	1135	<0.001	1	0.83	0.005	0.04	<0.1	0.15	2.5	0.1	0.05	2	2.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283901	Soil	7.3	30.1	10.6	109	1.4	22.0	5.3	199	2.00	11.1	7.2	1.7	52	1.4	2.6	0.2	67	0.27	0.125	9
1283902	Soil	10.5	21.0	11.7	116	0.8	20.1	11.9	1229	2.00	14.6	6.5	1.7	38	0.8	3.1	0.2	73	0.16	0.089	8
1283903	Soil	3.7	17.4	3.9	62	0.9	16.0	3.6	574	0.81	5.1	5.5	0.3	18	0.8	1.4	<0.1	32	0.11	0.045	3
1283904	Soil	90.5	40.0	9.8	185	1.0	49.2	41.2	4700	4.92	92.3	9.0	1.9	46	3.1	9.6	0.2	91	0.36	0.263	9
1283905	Soil	37.7	29.2	13.3	130	1.0	25.0	13.5	1572	2.80	45.6	7.2	2.2	43	1.5	5.0	0.2	82	0.31	0.144	10
1283906	Soil	62.6	39.1	15.3	203	1.1	43.2	23.0	1656	2.99	39.7	7.3	2.1	46	2.8	8.1	0.3	85	0.38	0.148	10
1283907	Soil	24.6	29.3	15.9	132	1.2	27.0	6.8	268	2.37	21.1	6.1	1.7	36	2.3	4.2	0.3	89	0.23	0.123	10
1283908	Soil	49.5	31.6	13.7	171	1.1	28.0	35.7	5213	3.10	26.6	6.9	1.8	39	1.8	5.5	0.2	85	0.34	0.137	11
1283909	Soil	20.1	35.9	12.4	178	1.1	38.4	19.1	1987	2.16	12.8	7.0	1.8	48	2.6	3.4	0.2	63	0.52	0.115	10
1283910	Soil	1.1	12.3	1.8	25	0.4	7.8	1.2	46	0.36	1.6	3.3	0.1	16	0.3	0.6	<0.1	10	0.26	0.027	2
1283911	Soil	13.2	33.2	14.0	158	0.6	26.9	9.8	1045	2.34	18.3	5.1	2.5	40	1.7	3.2	0.2	84	0.36	0.129	12
1283912	Soil	8.2	21.2	8.7	68	0.3	11.4	8.3	768	1.58	10.1	4.1	0.9	19	1.1	2.0	0.2	65	0.17	0.083	8
1283913	Soil	10.4	39.8	12.7	135	0.8	29.0	6.9	361	2.47	15.0	6.8	2.0	44	0.7	2.5	0.2	94	0.53	0.124	11
1283914	Soil	9.3	15.7	6.2	61	0.5	13.5	2.8	143	1.55	16.7	3.3	0.9	25	0.8	1.3	0.1	55	0.26	0.119	7
1283915	Soil	3.5	22.7	5.2	46	0.5	12.1	4.1	324	0.91	7.0	3.2	0.7	17	1.2	0.9	<0.1	39	0.19	0.075	5
1283916	Soil	7.2	46.7	11.2	200	0.9	45.3	16.7	956	2.34	16.0	5.9	1.5	56	5.9	2.6	0.2	86	0.75	0.168	9
1283917	Soil	9.1	52.4	11.5	218	0.9	51.2	11.2	791	2.62	22.6	4.8	2.0	70	4.2	3.0	0.2	86	1.01	0.181	11
1283918	Soil	6.6	76.0	13.7	275	1.3	64.9	7.6	478	2.68	16.0	5.6	2.7	63	5.9	4.1	0.3	99	0.72	0.167	15
1283919	Soil	15.0	65.9	12.1	249	1.1	54.6	8.7	582	3.62	28.4	5.4	2.4	69	3.6	4.3	0.2	98	0.77	0.190	13
1283920	Soil	9.3	47.9	11.9	191	0.6	44.1	10.0	735	2.34	20.4	3.6	2.3	59	1.6	3.0	0.2	104	0.70	0.154	13
1284071	Soil	6.8	19.3	13.6	61	0.9	12.2	2.3	76	2.00	26.1	4.1	0.2	39	0.2	4.2	0.3	80	0.02	0.097	4
1284072	Soil	6.7	50.8	14.9	102	0.7	27.0	4.7	85	2.56	20.1	3.8	0.3	24	0.5	3.2	0.3	88	0.04	0.095	8
1284073	Soil	4.4	37.6	8.1	70	0.6	20.9	4.2	65	1.78	9.7	0.7	0.1	17	0.7	1.7	0.2	55	0.03	0.065	4
1284074	Soil	4.7	20.3	7.1	43	0.7	11.6	2.3	32	0.95	7.0	1.1	0.2	10	0.2	1.4	0.2	48	0.01	0.045	3
1284075	Soil	14.0	94.7	29.8	87	2.2	21.4	3.3	93	2.55	24.4	16.9	0.7	121	0.7	4.3	0.4	112	0.04	0.183	6
1284076	Soil	9.1	31.2	17.1	63	0.5	17.0	3.0	44	1.60	12.2	1.1	0.2	58	0.2	2.3	0.3	73	0.01	0.066	3
1284077	Soil	4.5	24.5	9.1	45	1.4	11.5	1.5	35	0.79	6.6	5.2	0.1	49	0.6	1.8	0.2	49	0.16	0.062	2
1284078	Soil	5.7	63.6	23.6	74	2.2	22.4	2.1	52	1.61	18.0	13.4	1.4	83	0.9	3.9	0.4	131	0.17	0.116	7
1284079	Soil	10.2	49.8	15.0	119	1.4	26.7	15.2	603	1.86	15.3	6.0	1.7	67	1.4	4.8	0.2	91	0.22	0.114	9
1284080	Soil	7.9	58.1	13.6	157	1.1	40.6	7.9	286	2.21	15.8	5.0	2.0	66	1.9	4.1	0.3	76	0.31	0.115	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283901	Soil	17	0.16	2222	0.002	3	0.81	0.006	0.09	0.2	0.62	2.2	0.3	0.05	3	3.0	<0.2
1283902	Soil	18	0.16	1955	0.002	2	0.87	0.007	0.08	0.1	0.30	1.6	0.3	<0.05	3	1.7	<0.2
1283903	Soil	9	0.05	774	0.003	2	0.49	0.019	0.06	<0.1	0.22	1.2	0.2	<0.05	2	1.5	<0.2
1283904	Soil	21	0.16	2014	0.002	3	1.20	0.006	0.11	0.2	0.57	3.1	0.6	0.06	3	10.1	0.2
1283905	Soil	19	0.18	1734	0.002	2	1.03	0.004	0.09	0.2	0.59	2.2	0.5	<0.05	3	7.0	<0.2
1283906	Soil	18	0.20	2035	0.002	3	1.09	0.006	0.10	0.1	0.54	2.9	0.4	<0.05	3	11.4	<0.2
1283907	Soil	20	0.19	1836	0.002	3	1.08	0.005	0.08	0.1	0.59	2.4	0.3	0.06	3	7.0	<0.2
1283908	Soil	21	0.21	1834	0.002	2	1.24	0.006	0.11	0.1	0.57	2.9	0.3	<0.05	3	6.4	<0.2
1283909	Soil	20	0.21	1873	0.002	3	1.10	0.008	0.10	0.1	0.45	2.8	0.3	0.06	3	3.1	<0.2
1283910	Soil	3	0.04	355	0.006	<1	0.22	0.025	0.03	<0.1	0.09	0.4	<0.1	<0.05	<1	0.8	<0.2
1283911	Soil	23	0.24	1602	0.003	3	0.99	0.005	0.13	0.2	0.32	1.9	0.3	<0.05	3	1.9	<0.2
1283912	Soil	15	0.11	736	0.002	2	0.75	0.009	0.08	0.1	0.17	1.2	0.2	<0.05	3	1.5	<0.2
1283913	Soil	23	0.24	1828	0.004	3	1.12	0.008	0.10	0.2	0.40	3.2	0.2	0.13	3	1.6	<0.2
1283914	Soil	13	0.13	766	0.007	3	0.55	0.018	0.07	0.2	0.27	1.5	0.2	0.07	2	1.4	<0.2
1283915	Soil	12	0.09	536	0.005	<1	0.48	0.016	0.05	<0.1	0.21	1.4	0.1	0.05	2	1.3	<0.2
1283916	Soil	20	0.22	2132	0.005	3	1.00	0.010	0.09	0.2	0.43	2.9	0.2	0.13	3	2.2	<0.2
1283917	Soil	22	0.27	2240	0.004	4	1.09	0.008	0.12	0.2	0.49	3.0	0.2	0.15	3	2.5	<0.2
1283918	Soil	26	0.28	2298	0.005	4	1.21	0.008	0.14	0.2	0.68	4.1	0.2	0.13	4	5.8	<0.2
1283919	Soil	25	0.28	2273	0.004	2	1.25	0.006	0.13	0.2	0.59	3.8	0.2	0.13	3	6.4	<0.2
1283920	Soil	22	0.27	2110	0.004	3	1.15	0.009	0.13	0.2	0.48	3.2	0.2	0.10	3	2.8	<0.2
1284071	Soil	14	0.04	380	0.002	2	0.48	0.006	0.09	<0.1	0.09	0.8	0.4	0.16	3	2.2	<0.2
1284072	Soil	21	0.03	635	0.003	2	0.74	0.005	0.06	0.1	0.21	1.2	0.2	0.05	3	2.0	<0.2
1284073	Soil	16	0.02	236	0.002	2	0.36	0.013	0.05	<0.1	0.03	0.6	<0.1	0.05	2	1.6	<0.2
1284074	Soil	11	0.02	189	0.002	3	0.39	0.006	0.05	<0.1	0.03	0.5	0.1	<0.05	2	0.6	<0.2
1284075	Soil	31	0.07	842	0.002	3	1.07	0.004	0.11	<0.1	0.77	3.7	0.7	0.09	3	4.9	<0.2
1284076	Soil	18	0.02	381	0.002	3	0.51	0.006	0.11	<0.1	0.04	1.2	0.4	0.10	2	1.7	<0.2
1284077	Soil	11	0.04	980	0.002	4	0.33	0.014	0.07	<0.1	0.51	1.1	0.4	0.05	1	1.7	<0.2
1284078	Soil	26	0.12	2577	0.002	3	0.91	0.004	0.11	0.1	2.25	3.9	0.6	<0.05	3	4.8	<0.2
1284079	Soil	18	0.16	1610	0.002	4	0.74	0.008	0.10	0.1	0.67	2.7	0.4	<0.05	2	3.7	<0.2
1284080	Soil	19	0.18	2101	0.002	4	0.85	0.008	0.12	0.1	0.51	3.3	0.3	<0.05	3	2.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1284081	Soil		7.3	45.9	12.1	145	1.2	34.6	7.3	279	1.98	14.9	6.7	1.2	63	1.7	3.8	0.2	77	0.37	0.101	7
1284082	Soil		5.9	45.9	12.5	140	0.7	30.7	6.7	143	2.11	14.6	5.3	2.4	62	1.1	3.6	0.2	67	0.31	0.103	10
1284083	Soil		6.4	51.3	11.9	172	0.9	37.0	7.6	228	2.23	16.6	5.0	2.9	66	1.7	4.1	0.2	70	0.33	0.132	11
1284084	Soil		7.1	39.5	14.6	125	1.0	29.7	6.6	259	2.44	16.3	5.5	2.2	54	1.1	3.4	0.3	74	0.30	0.102	9
1284085	Soil		6.9	35.5	12.8	133	0.8	27.8	7.1	269	2.13	14.6	5.1	1.9	54	1.1	3.2	0.3	72	0.36	0.090	8
1284086	Soil		7.3	43.0	12.9	198	0.8	36.7	8.8	649	2.25	16.0	5.0	2.8	63	1.7	4.0	0.3	94	0.68	0.108	12
1284087	Soil		6.1	31.3	15.5	117	0.9	22.5	5.6	198	2.04	15.3	6.4	2.2	51	1.0	3.3	0.3	88	0.39	0.097	8
1284088	Soil		8.2	31.7	13.8	121	0.9	23.2	7.0	305	2.25	15.8	5.6	2.0	51	1.2	3.9	0.3	85	0.35	0.098	8
1284089	Soil		6.7	37.4	14.2	130	0.9	29.8	4.9	204	1.74	13.3	6.1	1.6	65	1.7	3.0	0.2	75	0.58	0.106	8
1284090	Soil		5.2	38.8	12.4	131	0.8	39.9	5.1	281	1.19	7.9	4.8	1.1	71	4.9	2.8	0.2	54	0.84	0.087	6
1284091	Soil		4.0	24.5	8.5	77	0.7	19.0	6.8	538	1.26	10.3	3.2	0.6	55	1.1	2.0	0.2	52	0.58	0.084	5
1284092	Soil		6.7	53.4	13.7	191	1.0	39.8	7.8	255	2.30	16.7	5.6	2.2	64	1.7	3.8	0.2	74	0.40	0.109	10
1284093	Soil		2.3	39.7	13.1	120	0.9	31.6	3.7	108	1.51	9.1	4.8	1.8	65	1.5	2.1	0.2	59	0.65	0.086	7
1284094	Soil		3.0	24.8	8.3	66	0.7	16.9	2.0	98	1.35	9.1	4.0	1.2	43	1.1	1.4	0.2	45	0.35	0.087	6
1284095	Soil		1.8	22.5	8.6	53	0.8	15.1	1.4	42	1.34	12.1	3.7	1.0	47	0.8	1.5	0.2	46	0.39	0.098	6
1284096	Soil		11.0	50.0	16.4	204	1.2	42.7	6.6	309	2.37	18.4	5.9	2.3	70	2.8	4.6	0.3	83	0.59	0.116	9
1284097	Soil		11.5	43.8	13.8	207	1.0	39.9	10.1	770	2.02	14.4	5.0	1.8	77	3.9	4.1	0.2	78	0.79	0.112	8
1284098	Soil		6.5	47.1	15.2	163	0.9	33.1	4.7	119	1.23	10.7	4.4	2.0	61	3.1	4.5	0.2	80	0.45	0.097	10
1284099	Soil		18.1	45.6	15.9	267	1.2	44.7	24.5	2561	3.26	23.5	6.8	1.9	63	4.6	5.0	0.3	84	0.45	0.137	9
1284100	Soil		11.5	68.1	13.8	597	1.1	86.7	7.6	340	2.26	18.0	5.8	2.3	66	3.9	4.3	0.2	75	0.84	0.119	10
1284211	Soil		0.4	6.3	4.4	19	1.0	3.3	1.1	35	0.63	2.7	<0.5	0.3	9	<0.1	0.1	<0.1	15	0.03	0.031	1
1284212	Soil		1.4	30.6	24.6	105	0.5	14.9	8.3	286	3.04	21.0	2.0	0.9	32	0.1	0.7	0.2	35	0.04	0.084	3
1284213	Soil		0.9	17.1	16.7	104	0.7	14.0	6.0	85	1.84	11.5	1.9	1.4	19	0.1	0.4	0.3	39	0.01	0.030	2
1284214	Soil		1.2	9.9	9.5	36	0.9	5.6	1.8	36	0.99	5.0	0.6	0.3	17	0.2	0.5	0.1	25	0.02	0.073	3
1284215	Soil		0.6	6.6	2.9	11	0.8	2.0	0.6	11	0.39	1.3	<0.5	<0.1	10	0.1	0.2	<0.1	9	0.02	0.058	2
1284216	Soil		3.8	7.5	12.0	33	0.4	7.2	1.2	21	1.14	9.7	<0.5	0.5	30	0.4	1.3	0.1	36	0.04	0.070	2
1284217	Soil		2.6	18.7	11.2	92	0.1	22.9	6.5	91	2.19	14.9	1.8	1.1	22	0.3	1.7	0.2	27	0.03	0.037	3
1284218	Soil		1.7	12.3	8.5	55	0.5	24.9	7.5	73	1.28	6.4	1.8	0.6	33	0.2	0.9	0.1	24	0.26	0.041	2
1284219	Soil		4.3	25.7	11.3	100	0.5	47.4	12.6	451	1.99	7.6	2.0	1.1	45	0.9	1.8	0.2	27	0.52	0.058	2
1284220	Soil		1.7	29.1	17.5	71	0.4	24.9	23.7	2473	3.22	10.1	<0.5	1.5	33	0.1	0.5	0.2	27	0.21	0.117	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284081	Soil	18	0.14	2113	0.002	4	0.83	0.011	0.11	<0.1	0.52	3.0	0.3	0.05	3	3.1	<0.2
1284082	Soil	19	0.20	2448	0.002	3	0.82	0.004	0.10	0.1	0.44	3.1	0.2	<0.05	2	2.3	<0.2
1284083	Soil	18	0.19	2413	0.003	4	0.72	0.005	0.11	0.1	0.46	3.2	0.2	<0.05	2	1.9	<0.2
1284084	Soil	20	0.18	2369	0.002	3	0.93	0.007	0.09	0.1	0.45	3.2	0.2	<0.05	3	4.1	<0.2
1284085	Soil	21	0.18	2473	0.002	2	0.86	0.007	0.09	0.1	0.43	2.7	0.2	<0.05	3	2.0	<0.2
1284086	Soil	20	0.24	1489	0.004	3	0.97	0.009	0.13	0.1	0.40	3.4	0.2	<0.05	3	2.8	<0.2
1284087	Soil	20	0.18	1948	0.001	3	0.89	0.007	0.09	0.1	0.51	2.8	0.3	<0.05	3	5.2	<0.2
1284088	Soil	21	0.19	2167	0.002	3	0.93	0.007	0.09	0.1	0.51	2.8	0.2	<0.05	3	5.0	<0.2
1284089	Soil	22	0.19	1773	0.002	3	0.85	0.007	0.10	0.2	0.50	2.7	0.3	0.05	3	3.4	<0.2
1284090	Soil	15	0.11	1879	0.001	3	0.55	0.006	0.07	0.1	0.49	2.1	0.3	0.08	2	4.6	<0.2
1284091	Soil	12	0.11	1532	0.002	3	0.57	0.016	0.07	<0.1	0.38	1.8	0.2	0.06	2	2.0	<0.2
1284092	Soil	23	0.21	3123	0.002	3	1.01	0.006	0.10	0.1	0.44	3.6	0.3	<0.05	3	2.7	<0.2
1284093	Soil	19	0.19	2256	0.001	3	0.88	0.007	0.08	<0.1	0.46	2.9	0.3	0.05	3	2.0	<0.2
1284094	Soil	15	0.12	1732	0.002	2	0.70	0.010	0.06	<0.1	0.43	2.0	0.2	0.06	2	1.7	<0.2
1284095	Soil	16	0.12	1526	0.002	2	0.66	0.009	0.07	0.1	0.41	1.9	0.2	0.07	2	2.4	<0.2
1284096	Soil	23	0.23	2564	0.002	4	0.98	0.006	0.10	0.1	0.56	3.6	0.3	0.06	3	3.4	<0.2
1284097	Soil	20	0.21	2507	0.002	3	0.93	0.007	0.10	0.1	0.52	3.0	0.3	<0.05	3	2.5	<0.2
1284098	Soil	22	0.21	2273	0.002	4	0.93	0.006	0.10	0.2	0.50	3.0	0.3	0.05	3	2.9	<0.2
1284099	Soil	19	0.19	1933	0.001	2	0.84	0.005	0.09	0.2	0.60	3.4	0.3	<0.05	3	5.0	<0.2
1284100	Soil	21	0.23	1977	0.002	4	0.95	0.006	0.12	0.1	0.49	3.8	0.3	0.06	3	4.4	<0.2
1284211	Soil	5	0.03	153	0.003	1	0.46	0.022	0.04	<0.1	0.02	0.5	<0.1	<0.05	2	<0.5	<0.2
1284212	Soil	18	0.10	373	0.003	1	0.98	0.013	0.08	<0.1	0.04	2.0	<0.1	<0.05	4	1.3	<0.2
1284213	Soil	17	0.13	593	<0.001	1	1.19	0.005	0.09	<0.1	0.04	1.9	<0.1	<0.05	4	<0.5	<0.2
1284214	Soil	7	0.03	350	0.002	2	0.56	0.014	0.05	<0.1	0.03	0.6	<0.1	<0.05	3	<0.5	<0.2
1284215	Soil	3	0.01	216	0.004	1	0.47	0.021	0.03	<0.1	0.04	0.3	<0.1	<0.05	2	<0.5	<0.2
1284216	Soil	11	0.05	495	0.002	2	0.50	0.013	0.07	<0.1	0.02	0.6	0.2	<0.05	2	0.8	<0.2
1284217	Soil	13	0.14	1538	0.001	1	0.67	0.004	0.05	<0.1	0.04	2.0	0.1	<0.05	2	2.5	<0.2
1284218	Soil	9	0.08	592	0.002	2	0.67	0.015	0.05	<0.1	0.04	1.5	0.2	<0.05	2	2.4	<0.2
1284219	Soil	13	0.16	554	0.001	3	0.80	0.013	0.05	<0.1	0.20	3.2	0.2	0.05	2	6.5	<0.2
1284220	Soil	26	0.32	186	0.003	<1	1.42	0.009	0.05	<0.1	0.11	3.3	0.1	<0.05	4	1.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1284221	Soil	1.4	26.1	16.8	71	0.6	34.5	14.0	714	2.37	7.1	1.3	1.3	73	0.2	0.4	0.2	26	0.59	0.105	5
1284222	Soil	1.8	23.1	18.1	63	0.9	21.8	5.9	236	2.39	8.1	2.3	1.0	32	<0.1	0.4	0.2	27	0.14	0.123	3
1284223	Soil	1.6	18.1	11.1	47	0.9	16.9	3.4	106	1.49	5.1	1.4	0.6	16	0.1	0.4	0.2	21	0.09	0.126	2
1284224	Soil	1.2	18.0	10.7	36	0.3	13.4	4.7	213	1.84	5.9	1.1	0.6	72	<0.1	0.4	0.1	22	0.57	0.081	2
1284225	Soil	1.9	17.3	14.8	48	0.4	14.0	4.0	112	2.40	10.4	1.5	0.8	11	<0.1	0.6	0.2	30	0.04	0.090	3
1284226	Soil	2.1	27.9	21.7	160	0.2	45.7	24.5	1563	4.04	14.2	1.2	2.4	56	0.2	0.7	0.4	37	0.20	0.100	4
1284227	Soil	1.6	24.0	15.4	53	0.6	15.5	57.6	1457	2.31	8.9	1.1	1.1	11	<0.1	0.5	0.2	27	0.05	0.085	3
1284228	Soil	2.3	20.1	13.0	55	<0.1	14.4	4.4	210	2.21	10.0	<0.5	1.1	13	0.2	0.7	0.2	38	0.07	0.045	5
1284229	Soil	2.5	35.8	28.6	91	<0.1	23.2	8.0	300	5.19	18.6	1.9	2.2	22	0.1	0.9	0.4	37	0.02	0.120	3
1284230	Soil	2.0	29.0	25.4	76	0.3	18.1	4.8	170	4.41	14.1	0.7	1.9	16	0.2	0.7	0.3	30	0.02	0.103	2
1284231	Soil	2.4	12.7	12.5	62	0.1	12.6	5.1	214	2.52	9.6	0.8	2.3	10	0.1	0.9	0.2	50	0.04	0.049	9
1284232	Soil	5.3	9.5	19.5	38	0.2	8.8	2.8	53	2.13	10.8	1.2	1.2	43	<0.1	0.8	0.3	39	0.03	0.047	4
1284233	Soil	2.8	15.5	10.6	33	0.3	6.2	1.8	41	1.54	8.8	2.9	1.4	6	<0.1	1.1	0.3	61	0.02	0.019	13
1284234	Soil	8.1	24.6	9.8	48	0.7	7.7	1.5	27	1.81	15.3	1.9	0.2	23	0.3	1.9	0.2	41	0.12	0.064	6
1284235	Soil	10.4	42.2	19.7	94	0.7	32.9	5.2	115	4.31	11.5	5.1	2.9	2	0.2	1.4	0.4	32	0.01	0.046	18
1284236	Soil	4.8	41.4	15.6	136	0.6	40.6	8.0	157	3.22	11.5	3.5	2.3	14	0.3	1.4	0.3	57	0.08	0.070	14
1284237	Soil	10.5	115.3	38.0	234	0.3	72.5	30.6	2153	5.52	27.9	10.5	2.3	38	0.9	2.6	0.5	77	0.23	0.205	16
1284238	Soil	7.4	77.9	16.4	129	0.4	38.2	13.1	831	5.20	20.7	3.3	1.7	17	0.3	1.5	0.4	85	0.10	0.061	10
1284239	Soil	2.5	39.5	12.4	137	0.5	39.6	9.9	200	2.03	7.4	6.6	2.5	146	0.5	1.4	0.2	23	1.46	0.073	10
1284240	Soil	2.7	32.3	11.2	95	1.3	25.9	4.2	143	1.56	8.3	5.7	0.9	44	0.7	1.3	0.2	67	0.50	0.070	7
1284301	Soil	14.1	22.9	9.4	118	0.5	19.6	8.6	336	2.35	15.5	2.9	1.1	40	1.5	3.2	0.2	68	0.36	0.087	7
1284302	Soil	12.0	44.7	17.0	260	0.3	34.9	4.6	100	2.35	33.1	3.1	0.3	26	0.6	7.0	0.3	121	0.04	0.111	7
1284303	Soil	7.1	33.1	16.9	159	1.8	32.8	3.3	80	1.82	24.9	7.3	1.7	49	2.2	3.5	0.3	97	0.20	0.094	8
1284304	Soil	11.9	55.1	14.1	391	0.8	54.6	6.7	127	2.80	32.6	5.6	2.2	54	3.0	7.8	0.2	110	0.30	0.142	8
1284305	Soil	11.4	57.0	14.1	408	1.9	56.0	6.2	201	2.63	34.6	7.2	0.5	38	3.3	7.6	0.3	122	0.24	0.169	6
1284306	Soil	6.3	28.2	11.7	176	0.3	24.8	4.4	103	1.62	18.4	3.9	0.6	22	1.0	3.8	0.2	76	0.08	0.074	7
1284307	Soil	6.9	104.0	14.7	404	1.9	74.4	11.2	312	2.66	21.6	10.1	2.9	60	3.9	4.0	0.3	89	0.80	0.148	15
1284308	Soil	13.3	78.7	19.3	495	2.9	70.3	11.1	358	4.12	47.6	10.3	1.6	43	5.6	10.5	0.3	132	0.20	0.273	7
1284309	Soil	7.5	81.8	13.8	471	4.1	89.5	11.8	356	2.34	23.4	12.7	1.6	64	7.3	5.7	0.2	95	0.61	0.146	7
1284310	Soil	6.2	72.0	14.2	281	1.9	58.5	10.4	593	2.70	22.8	10.6	1.8	67	5.0	3.9	0.2	84	0.84	0.146	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284221	Soil	23	0.28	231	0.002	2	1.39	0.012	0.05	<0.1	0.13	4.8	0.2	<0.05	4	1.7	<0.2
1284222	Soil	24	0.28	485	0.002	<1	1.17	0.008	0.06	<0.1	0.08	2.6	0.1	<0.05	4	0.9	<0.2
1284223	Soil	19	0.13	196	0.002	<1	0.89	0.015	0.06	<0.1	0.13	2.6	0.1	<0.05	3	0.9	<0.2
1284224	Soil	14	0.21	276	0.004	<1	0.83	0.017	0.03	<0.1	0.06	1.7	<0.1	<0.05	3	1.5	<0.2
1284225	Soil	17	0.20	111	0.002	<1	0.90	0.008	0.04	<0.1	0.05	1.2	<0.1	<0.05	4	1.0	<0.2
1284226	Soil	31	0.48	194	0.002	<1	1.60	0.006	0.07	<0.1	0.06	4.2	0.1	<0.05	5	1.2	<0.2
1284227	Soil	18	0.16	128	0.002	<1	0.99	0.012	0.05	<0.1	0.12	2.3	0.1	<0.05	4	1.1	<0.2
1284228	Soil	15	0.15	113	0.003	<1	0.78	0.008	0.05	<0.1	<0.01	1.3	<0.1	<0.05	4	0.8	<0.2
1284229	Soil	26	0.25	1092	0.003	<1	1.13	0.004	0.05	<0.1	0.03	2.5	0.1	<0.05	5	1.4	<0.2
1284230	Soil	21	0.23	170	0.002	<1	1.11	0.008	0.05	<0.1	0.03	2.1	0.1	<0.05	4	1.5	<0.2
1284231	Soil	20	0.21	101	0.008	<1	1.26	0.005	0.05	0.1	0.02	1.8	0.1	<0.05	5	0.6	<0.2
1284232	Soil	13	0.11	230	0.002	<1	1.02	0.007	0.04	<0.1	0.01	1.4	0.1	<0.05	5	1.1	<0.2
1284233	Soil	14	0.05	83	0.014	<1	0.67	0.002	0.03	0.1	0.02	0.8	0.2	<0.05	5	0.6	<0.2
1284234	Soil	10	0.03	753	0.003	<1	0.38	0.006	0.04	0.1	0.03	0.5	0.1	<0.05	3	2.1	<0.2
1284235	Soil	24	0.18	560	0.002	3	1.18	0.003	0.05	<0.1	0.09	3.0	0.1	<0.05	4	1.9	<0.2
1284236	Soil	28	0.18	850	0.002	3	1.33	0.005	0.05	<0.1	0.06	2.4	0.2	<0.05	4	1.4	<0.2
1284237	Soil	33	0.24	1241	0.004	3	1.27	0.005	0.05	0.1	0.13	4.0	0.1	<0.05	4	3.0	0.2
1284238	Soil	33	0.19	566	0.003	2	1.20	0.004	0.04	0.1	0.03	3.0	<0.1	<0.05	6	1.0	<0.2
1284239	Soil	16	0.26	520	0.004	4	0.62	0.004	0.04	<0.1	0.11	3.1	<0.1	0.07	2	2.5	<0.2
1284240	Soil	19	0.13	1774	0.002	3	1.29	0.017	0.09	0.1	0.39	2.4	0.2	<0.05	4	1.6	<0.2
1284301	Soil	11	0.09	1113	0.004	1	0.58	0.007	0.05	<0.1	0.18	1.4	0.1	<0.05	2	3.4	<0.2
1284302	Soil	15	0.03	372	0.003	2	0.50	0.003	0.07	0.2	0.11	1.0	0.3	<0.05	3	3.3	<0.2
1284303	Soil	18	0.10	2268	0.002	1	0.66	0.003	0.06	0.1	0.87	2.0	0.3	<0.05	3	3.0	<0.2
1284304	Soil	22	0.11	1877	0.004	2	0.59	0.003	0.07	0.2	0.52	2.4	0.4	<0.05	2	4.4	<0.2
1284305	Soil	17	0.06	1750	0.003	<1	0.59	0.004	0.07	0.2	0.64	1.7	0.4	<0.05	2	3.6	<0.2
1284306	Soil	13	0.04	742	0.003	2	0.47	0.003	0.06	<0.1	0.19	1.2	0.3	<0.05	2	2.4	<0.2
1284307	Soil	22	0.27	1642	0.004	5	1.00	0.005	0.13	0.2	1.03	4.2	0.3	<0.05	3	3.1	<0.2
1284308	Soil	22	0.06	2358	0.004	3	0.80	0.004	0.07	0.2	1.01	3.2	0.5	<0.05	2	4.5	<0.2
1284309	Soil	21	0.10	3326	0.002	2	0.80	0.003	0.07	0.2	1.46	4.1	0.4	<0.05	2	4.6	<0.2
1284310	Soil	20	0.22	1665	0.002	3	0.82	0.005	0.09	0.2	1.05	3.6	0.3	<0.05	2	4.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1284311	Soil	7.2	52.6	14.1	270	1.4	48.7	5.2	159	2.03	26.7	13.5	1.4	56	3.6	4.6	0.2	88	0.43	0.139	7
1284312	Soil	5.0	38.6	11.4	186	1.0	25.4	6.5	215	1.74	18.9	9.7	0.5	20	2.9	3.6	0.2	68	0.09	0.095	7
1284313	Soil	4.2	83.6	12.2	405	4.2	82.3	9.6	135	1.94	14.7	11.6	1.8	54	11.3	4.1	0.2	66	0.50	0.123	9
1284314	Soil	2.9	21.6	5.3	91	1.1	18.3	7.3	924	1.14	10.8	5.0	0.4	32	2.8	2.0	0.1	40	0.39	0.107	4
1284315	Soil	5.7	48.0	10.8	295	1.7	45.3	7.8	388	1.93	18.2	8.3	1.2	75	3.6	4.6	0.2	70	1.07	0.138	6
1284316	Soil	1.6	21.4	4.4	87	0.7	20.2	2.4	140	0.84	6.9	3.6	0.2	36	2.6	1.6	0.1	28	0.48	0.067	3
1284317	Soil	7.7	35.6	8.1	152	1.5	37.1	9.5	1488	2.70	21.9	8.4	0.8	74	2.6	4.2	0.2	67	1.13	0.123	5
1284318	Soil	3.5	41.3	10.0	161	1.3	34.2	4.0	233	1.42	14.1	5.0	1.3	65	2.6	3.2	0.2	58	0.81	0.113	6
1284319	Soil	9.6	75.3	12.9	262	1.8	34.3	4.2	84	2.07	28.9	2.4	1.6	57	2.5	10.3	0.2	92	0.30	0.169	6
1284320	Soil	3.7	15.8	7.7	87	0.7	14.6	3.5	166	1.48	13.9	3.2	0.3	22	0.5	2.3	0.1	56	0.19	0.126	4
1286061	Soil	8.4	47.1	11.0	200	0.8	59.5	8.4	197	2.67	13.2	3.0	2.8	57	1.4	2.4	0.2	38	0.76	0.086	14
1286062	Soil	6.1	21.9	16.3	141	0.3	25.9	7.9	110	2.39	13.4	2.0	5.1	29	0.5	1.8	0.2	57	0.26	0.085	19
1286063	Soil	1.9	10.1	5.9	36	0.5	6.0	1.6	34	0.71	4.5	1.3	0.5	11	0.2	0.5	0.1	37	0.03	0.028	11
1286064	Soil	5.2	16.5	10.7	91	<0.1	21.9	7.0	99	2.52	14.7	1.0	2.2	10	0.4	1.4	0.2	83	0.05	0.039	12
1286065	Soil	4.5	13.5	12.7	102	0.1	17.7	5.3	114	2.24	19.1	<0.5	2.0	10	0.4	1.8	0.2	59	0.03	0.045	10
1286066	Soil	2.2	4.1	6.7	74	<0.1	7.8	2.6	51	1.15	5.8	0.7	0.8	5	0.4	0.9	0.2	48	0.02	0.026	7
1286067	Soil	12.8	42.3	17.1	232	0.5	52.8	10.0	235	2.56	24.1	4.0	2.9	54	1.6	3.2	0.2	74	0.44	0.097	10
1286068	Soil	10.4	27.6	29.5	75	1.0	14.8	3.7	140	2.47	25.2	4.1	0.2	80	0.1	4.9	0.4	85	0.03	0.101	8
1286069	Soil	4.3	18.8	16.4	86	0.8	13.1	2.8	79	1.96	23.7	4.4	0.2	33	0.2	3.2	0.3	52	0.04	0.053	6
1286070	Soil	6.2	17.8	14.6	42	1.3	7.4	1.3	34	1.17	24.4	3.0	0.2	42	0.1	6.3	0.3	77	0.01	0.046	5
1286071	Soil	5.4	27.9	11.0	47	1.8	10.5	1.6	35	1.33	18.4	1.1	0.2	39	0.3	2.7	0.3	80	0.02	0.055	6
1286072	Soil	3.1	15.6	9.9	39	0.8	9.1	2.1	51	1.30	15.1	2.9	0.2	11	0.1	1.8	0.2	52	0.03	0.049	10
1286073	Soil	1.9	9.4	3.4	17	1.1	4.3	0.9	18	0.51	7.3	0.8	<0.1	7	0.2	1.5	<0.1	26	0.02	0.023	3
1286074	Soil	2.1	7.2	3.4	12	1.3	2.8	0.7	15	0.46	8.7	1.5	0.3	7	<0.1	1.6	<0.1	23	0.02	0.020	2
1286075	Soil	6.0	12.7	8.9	39	1.8	7.5	1.5	36	1.02	27.6	2.5	0.1	21	0.2	5.4	0.2	60	0.02	0.061	5
1286076	Soil	13.1	28.3	18.6	144	3.5	25.3	4.5	131	2.83	60.6	8.6	1.7	74	0.8	8.9	0.3	127	0.10	0.227	9
1286077	Soil	4.9	15.1	13.4	73	1.9	14.4	2.5	61	1.59	16.3	1.2	0.4	32	0.5	2.5	0.2	96	0.02	0.091	9
1286078	Soil	12.1	76.9	15.5	369	1.7	61.3	11.9	626	2.81	24.0	7.9	1.9	128	5.6	7.2	0.3	135	0.60	0.221	14
1286079	Soil	34.5	63.7	19.8	1517	2.4	252.9	8.0	1097	5.99	184.3	23.9	0.9	190	20.6	34.5	0.3	490	1.04	1.130	6
1286680	Soil	4.4	55.1	17.3	173	0.4	40.2	9.1	299	3.40	21.6	4.3	6.7	30	0.6	2.7	0.4	52	0.27	0.101	23

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284311	Soil	16	0.11	1904	0.003	2	0.58	0.003	0.07	0.2	0.90	2.5	0.3	<0.05	2	4.4	<0.2
1284312	Soil	12	0.04	1470	0.007	1	0.57	0.007	0.04	0.1	0.31	1.5	0.2	0.05	3	2.1	<0.2
1284313	Soil	20	0.15	1721	0.005	2	0.87	0.006	0.07	0.2	1.43	4.5	0.5	0.11	2	5.4	<0.2
1284314	Soil	8	0.07	707	0.006	3	0.36	0.019	0.04	<0.1	0.50	1.3	0.2	0.08	1	2.6	<0.2
1284315	Soil	15	0.16	1385	0.003	4	0.59	0.007	0.07	0.1	0.91	2.5	0.2	0.10	2	4.3	<0.2
1284316	Soil	7	0.07	777	0.005	2	0.31	0.022	0.03	<0.1	0.49	1.0	0.1	0.09	1	3.4	<0.2
1284317	Soil	14	0.15	1335	0.007	5	0.57	0.008	0.05	0.1	0.81	2.2	0.2	0.14	2	8.2	<0.2
1284318	Soil	14	0.18	1451	0.003	3	0.61	0.006	0.07	0.1	0.76	2.6	0.3	0.09	2	4.0	<0.2
1284319	Soil	17	0.09	967	0.002	4	0.51	0.003	0.08	0.1	1.12	3.3	0.4	0.15	2	12.0	<0.2
1284320	Soil	10	0.06	440	0.004	2	0.49	0.018	0.05	<0.1	0.14	0.8	0.2	<0.05	2	1.2	<0.2
1286061	Soil	12	0.16	670	0.003	4	0.51	0.008	0.08	<0.1	0.23	3.3	0.2	0.06	1	1.6	<0.2
1286062	Soil	17	0.28	638	0.003	3	0.95	0.004	0.11	<0.1	0.12	2.6	0.2	<0.05	3	1.3	<0.2
1286063	Soil	7	0.05	225	0.004	1	0.45	0.007	0.04	<0.1	0.02	0.5	0.1	<0.05	3	<0.5	<0.2
1286064	Soil	19	0.24	467	0.004	2	1.28	0.005	0.06	<0.1	0.01	2.2	0.2	<0.05	5	<0.5	<0.2
1286065	Soil	13	0.13	261	0.006	<1	0.71	0.004	0.04	0.1	<0.01	1.4	0.1	<0.05	3	0.7	<0.2
1286066	Soil	8	0.05	197	0.005	<1	0.56	0.013	0.04	0.1	0.01	0.8	<0.1	<0.05	3	<0.5	<0.2
1286067	Soil	19	0.21	1459	0.003	3	0.79	0.006	0.09	0.1	0.24	3.5	0.3	<0.05	2	2.0	<0.2
1286068	Soil	22	0.11	418	0.006	2	0.79	0.008	0.09	0.1	0.28	0.4	0.4	0.11	4	6.3	<0.2
1286069	Soil	15	0.09	425	0.006	2	0.67	0.005	0.07	0.1	0.05	0.7	0.2	<0.05	4	1.7	<0.2
1286070	Soil	10	0.01	431	0.004	1	0.34	0.005	0.06	0.1	0.05	0.5	0.3	0.07	3	3.6	<0.2
1286071	Soil	16	0.03	224	0.004	1	0.53	0.006	0.06	<0.1	0.07	0.5	0.3	0.06	3	1.6	<0.2
1286072	Soil	12	0.10	162	0.008	<1	0.82	0.009	0.03	0.1	0.05	0.3	0.2	<0.05	4	1.0	<0.2
1286073	Soil	4	0.01	79	0.009	<1	0.35	0.021	0.03	<0.1	0.06	0.2	0.2	<0.05	2	1.0	<0.2
1286074	Soil	4	0.02	81	0.012	<1	0.31	0.022	0.03	<0.1	0.05	0.4	0.2	<0.05	2	0.7	<0.2
1286075	Soil	10	0.03	186	0.008	<1	0.45	0.016	0.05	0.1	0.11	0.4	0.5	<0.05	3	4.4	<0.2
1286076	Soil	26	0.18	606	0.011	2	0.93	0.007	0.12	0.2	0.32	2.1	0.8	0.11	5	10.2	0.2
1286077	Soil	16	0.05	309	0.012	2	0.54	0.005	0.07	0.1	0.08	0.9	0.3	<0.05	4	1.3	<0.2
1286078	Soil	27	0.20	2022	0.005	6	1.05	0.006	0.14	0.1	0.98	3.6	0.4	0.08	3	6.4	<0.2
1286079	Soil	28	0.20	2027	0.009	7	1.17	0.009	0.14	0.2	2.94	2.7	0.9	0.16	3	47.5	0.4
1286680	Soil	25	0.36	1112	0.007	2	1.35	0.008	0.12	0.3	0.21	3.8	0.2	<0.05	4	1.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286081	Soil	4.5	18.1	12.2	95	1.2	21.7	3.2	77	2.08	15.8	3.5	1.7	14	0.2	1.7	0.2	65	0.02	0.044	10
1286082	Soil	2.4	32.4	10.6	41	5.2	8.8	1.7	33	1.12	11.9	1.1	0.2	9	0.9	1.2	0.2	55	0.02	0.065	10
1286083	Soil	3.7	14.3	12.3	79	1.8	14.7	3.4	143	2.25	15.6	2.2	2.2	11	0.3	1.5	0.2	59	0.03	0.038	8
1286084	Soil	4.0	16.0	12.2	82	0.3	17.3	3.6	94	1.99	15.6	1.3	0.9	11	0.2	1.6	0.2	57	0.02	0.047	7
1286085	Soil	3.6	15.8	13.1	73	0.6	13.2	3.0	86	1.60	13.1	0.8	1.0	13	0.7	1.4	0.3	59	0.03	0.051	11
1286086	Soil	3.2	27.6	12.3	83	0.9	20.2	3.7	85	1.76	12.6	2.1	0.9	19	0.4	1.3	0.2	52	0.06	0.062	6
1286087	Soil	3.3	17.6	11.0	110	0.2	18.8	3.4	85	1.70	18.4	2.9	0.9	35	0.8	2.3	0.2	62	0.46	0.040	6
1286088	Soil	5.9	52.3	17.1	213	0.4	42.9	9.9	359	3.09	31.9	5.5	1.7	39	0.6	3.4	0.3	70	0.16	0.099	7
1286089	Soil	5.2	23.7	18.9	148	0.8	24.1	6.3	207	4.03	22.8	3.4	2.2	12	0.6	2.5	0.3	79	0.03	0.097	8
1286090	Soil	2.7	22.9	7.4	56	0.5	9.8	1.7	34	1.07	8.9	3.8	1.1	7	0.2	1.2	0.2	37	<0.01	0.031	5
1286091	Soil	4.2	14.5	9.6	77	0.3	14.4	2.7	68	1.73	15.9	1.8	0.7	9	0.2	1.9	0.2	61	0.01	0.044	7
1286092	Soil	5.9	28.2	16.5	160	0.5	32.8	6.1	175	2.74	21.0	4.8	1.7	18	0.4	2.8	0.2	57	0.02	0.062	6
1286093	Soil	3.2	13.3	8.9	70	0.4	11.1	2.1	45	1.38	7.9	1.9	1.7	12	0.5	1.6	0.2	49	0.01	0.025	8
1286094	Soil	6.1	22.1	14.6	136	0.5	21.4	4.1	119	2.73	21.7	2.2	0.9	17	0.7	2.5	0.2	79	0.02	0.066	6
1286095	Soil	9.6	57.5	16.5	149	1.0	33.6	4.1	65	1.94	27.2	11.4	1.8	91	0.9	4.8	0.2	79	0.21	0.105	8
1286096	Soil	4.4	17.0	10.3	57	0.5	10.2	2.1	55	1.35	10.9	2.8	0.2	10	0.2	1.7	0.2	66	0.03	0.039	13
1286097	Soil	12.4	28.8	19.9	110	2.6	16.7	1.7	39	2.74	43.5	3.8	0.7	37	0.4	7.1	0.2	123	0.02	0.157	5
1286098	Soil	18.7	38.7	28.7	145	2.0	23.8	2.5	54	3.55	59.6	5.0	1.7	40	0.4	9.6	0.3	199	0.03	0.166	7
1286099	Soil	8.5	22.8	17.3	75	1.0	14.3	1.5	25	1.89	30.9	3.0	0.4	15	0.1	4.4	0.3	95	<0.01	0.066	5
1286100	Soil	5.5	15.2	11.3	66	0.8	10.0	1.7	28	1.19	12.2	1.8	0.5	13	0.2	2.2	0.2	80	0.01	0.038	9
1286101	Soil	3.7	11.3	9.7	43	0.4	8.3	1.8	69	1.26	11.7	1.4	0.1	11	0.1	1.4	0.2	60	0.03	0.049	10
1286102	Soil	12.3	26.2	17.8	144	0.4	21.8	2.6	48	2.32	29.7	3.1	0.2	26	0.4	4.5	0.2	152	0.03	0.106	7
1286103	Soil	7.9	17.3	11.2	77	0.5	13.3	1.8	30	1.52	15.6	1.9	0.1	15	0.1	2.8	0.2	104	0.01	0.057	8
1286104	Soil	5.2	16.4	10.6	74	0.1	12.1	2.2	49	1.19	11.3	2.6	0.1	9	0.2	1.8	0.2	61	0.01	0.040	10
1286105	Soil	7.9	18.0	16.5	107	0.4	18.8	2.7	54	1.69	23.2	2.4	0.8	24	0.6	3.7	0.2	94	0.11	0.042	8
1286106	Soil	9.5	38.4	14.7	200	1.1	30.1	4.8	203	2.18	20.5	3.4	0.3	31	3.8	3.2	0.2	95	0.22	0.095	7
1286107	Soil	4.9	42.4	5.9	174	1.2	43.6	2.2	197	1.24	7.0	6.9	0.3	55	2.3	2.3	0.1	61	0.71	0.110	5
1286108	Soil	11.7	34.1	20.1	232	1.4	35.4	4.1	139	3.15	37.1	4.2	1.2	25	0.5	5.9	0.3	149	0.03	0.112	8
1286109	Soil	12.4	26.9	9.7	131	1.3	17.8	2.1	46	1.82	21.4	1.2	<0.1	9	0.4	3.9	0.2	147	0.01	0.056	6
1286110	Soil	13.5	27.9	12.4	168	1.2	22.7	1.9	62	1.74	25.6	1.8	0.8	15	0.7	4.7	0.2	145	0.01	0.061	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286081	Soil	18	0.09	272	0.005	2	0.96	0.005	0.06	<0.1	0.13	1.4	0.2	<0.05	4	1.2	<0.2
1286082	Soil	16	0.02	186	0.007	1	0.64	0.010	0.04	<0.1	0.08	0.3	<0.1	<0.05	2	0.8	<0.2
1286083	Soil	19	0.14	206	0.006	<1	0.98	0.005	0.05	0.1	0.08	1.5	0.2	<0.05	4	0.7	<0.2
1286084	Soil	14	0.08	173	0.006	1	0.62	0.004	0.05	<0.1	0.06	1.1	0.1	<0.05	4	1.2	<0.2
1286085	Soil	14	0.06	189	0.006	1	0.58	0.004	0.06	0.1	0.03	1.0	0.1	<0.05	4	1.0	<0.2
1286086	Soil	19	0.12	773	0.002	2	1.03	0.009	0.06	<0.1	0.21	1.4	0.2	<0.05	3	1.0	<0.2
1286087	Soil	15	0.07	673	0.003	2	0.67	0.009	0.05	0.1	0.28	1.5	0.2	<0.05	3	1.1	<0.2
1286088	Soil	27	0.24	1063	0.003	3	1.00	0.004	0.08	0.1	0.25	2.2	0.2	<0.05	3	1.9	<0.2
1286089	Soil	25	0.17	250	0.009	3	1.07	0.003	0.07	0.1	0.07	1.6	0.2	<0.05	5	1.1	<0.2
1286090	Soil	9	0.03	266	0.002	2	0.58	0.006	0.04	<0.1	0.08	0.9	0.1	<0.05	3	0.6	<0.2
1286091	Soil	10	0.04	203	0.005	2	0.48	0.003	0.04	0.1	0.01	0.7	0.2	<0.05	4	0.9	<0.2
1286092	Soil	18	0.14	292	0.003	2	0.83	0.005	0.06	<0.1	0.05	1.4	0.2	<0.05	3	1.3	<0.2
1286093	Soil	9	0.03	254	0.005	2	0.55	0.004	0.05	<0.1	0.01	0.8	0.1	<0.05	3	<0.5	<0.2
1286094	Soil	18	0.09	292	0.005	2	0.78	0.006	0.05	0.1	0.07	1.0	0.2	<0.05	4	1.2	<0.2
1286095	Soil	20	0.12	1829	0.002	3	0.68	0.003	0.06	0.1	0.71	2.3	0.4	0.05	2	2.5	<0.2
1286096	Soil	11	0.04	353	0.008	2	0.54	0.002	0.04	0.1	0.02	0.4	0.2	<0.05	4	1.0	<0.2
1286097	Soil	15	0.03	872	0.004	2	0.49	0.009	0.07	0.2	0.28	0.9	0.8	0.10	3	4.2	<0.2
1286098	Soil	20	0.03	1004	0.005	4	0.62	0.005	0.08	0.3	0.20	1.4	0.9	0.11	4	4.8	0.3
1286099	Soil	11	0.02	206	0.004	2	0.47	0.004	0.05	0.2	0.04	0.7	0.3	<0.05	3	3.3	<0.2
1286100	Soil	9	0.02	248	0.004	2	0.44	0.003	0.04	0.2	0.04	0.6	0.3	<0.05	4	1.0	<0.2
1286101	Soil	12	0.07	136	0.011	2	0.56	0.008	0.04	0.1	0.04	0.4	0.2	<0.05	4	0.8	<0.2
1286102	Soil	17	0.03	835	0.003	3	0.44	0.003	0.06	0.2	0.11	0.5	0.5	0.06	4	2.4	<0.2
1286103	Soil	12	0.02	595	0.004	2	0.38	0.004	0.04	0.1	0.05	0.3	0.3	<0.05	3	1.6	<0.2
1286104	Soil	10	0.03	165	0.005	2	0.41	0.003	0.05	0.2	0.03	0.3	0.2	<0.05	4	0.8	<0.2
1286105	Soil	12	0.04	363	0.008	2	0.38	0.004	0.05	0.2	0.02	0.8	0.3	<0.05	3	1.7	<0.2
1286106	Soil	19	0.10	1281	0.004	2	0.86	0.005	0.06	0.1	0.23	0.9	0.5	0.05	3	1.9	<0.2
1286107	Soil	13	0.14	1606	0.007	4	0.73	0.018	0.05	<0.1	0.61	0.9	0.3	0.13	2	3.7	<0.2
1286108	Soil	19	0.08	437	0.006	2	0.79	0.004	0.08	0.2	0.13	1.4	0.5	<0.05	4	3.3	<0.2
1286109	Soil	10	0.02	182	0.003	2	0.38	0.005	0.04	0.1	0.05	0.2	0.3	<0.05	3	2.0	<0.2
1286110	Soil	11	0.03	333	0.001	1	0.63	0.003	0.05	0.1	0.10	0.9	0.4	<0.05	3	2.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286111	Soil	22.8	35.0	30.8	117	1.9	19.3	1.8	31	2.70	52.4	1.2	0.1	36	0.3	9.1	0.4	186	0.01	0.107	5
1286112	Soil	12.2	29.0	13.8	159	1.3	24.6	2.2	29	1.66	25.0	2.2	0.4	25	0.5	5.3	0.2	122	0.02	0.076	4
1286113	Soil	12.9	27.3	20.4	135	1.8	20.4	2.8	91	3.23	40.9	3.8	1.3	27	0.3	6.4	0.3	119	0.04	0.165	8
1286114	Soil	7.4	16.8	14.3	115	1.3	16.6	2.2	43	1.72	19.9	1.6	0.2	13	0.2	3.3	0.2	94	0.02	0.071	7
1286115	Soil	8.6	17.9	19.6	98	0.4	13.8	1.7	32	1.39	21.4	2.0	0.4	10	0.4	3.1	0.2	119	0.02	0.041	8
1286116	Soil	7.3	26.3	10.3	150	0.9	24.1	2.1	47	1.47	18.9	2.4	<0.1	22	1.3	3.4	0.2	79	0.16	0.076	6
1286117	Soil	11.5	41.9	15.6	299	2.8	51.3	5.9	165	2.95	34.4	7.7	0.6	29	1.8	6.9	0.2	136	0.13	0.161	6
1286118	Soil	5.5	21.7	8.6	93	1.4	19.1	1.6	31	1.08	14.1	3.7	0.1	12	2.1	2.7	0.1	65	0.05	0.055	9
1286119	Soil	11.2	30.6	27.1	118	1.3	19.5	1.9	32	2.39	32.9	4.3	0.7	30	0.6	5.0	0.2	130	0.03	0.132	6
1286120	Soil	9.9	31.9	17.7	151	1.5	21.2	2.2	51	2.78	34.7	4.6	0.4	19	0.4	5.6	0.2	122	0.04	0.183	7
1286121	Soil	7.6	21.0	14.8	112	0.8	15.3	2.1	43	1.95	21.6	3.0	0.3	12	0.4	3.6	0.2	88	0.02	0.086	9
1286122	Soil	9.2	21.2	14.7	144	0.8	21.0	2.4	39	1.85	26.6	1.8	0.3	14	0.3	4.6	0.2	113	0.02	0.082	5
1286123	Soil	8.6	24.7	12.5	110	0.9	17.0	2.1	56	2.00	23.9	2.9	0.6	16	0.4	4.3	0.2	127	0.04	0.085	7
1286124	Soil	5.2	13.7	10.8	59	0.5	8.8	1.3	23	1.09	13.8	4.9	0.4	8	<0.1	2.3	0.2	72	<0.01	0.033	11
1286125	Soil	2.8	9.4	11.8	78	2.8	10.5	1.9	64	1.92	12.2	4.1	1.3	14	0.5	1.6	0.3	68	0.12	0.071	9
1286126	Soil	6.1	15.5	9.3	79	0.5	10.7	1.4	28	1.07	12.6	2.1	0.2	7	0.2	2.6	0.2	72	0.02	0.035	7
1286127	Soil	7.0	16.9	11.9	102	0.8	12.7	2.1	69	1.71	21.5	2.8	0.3	10	0.4	3.6	0.3	99	0.02	0.087	7
1286128	Soil	7.4	51.5	12.7	295	2.1	53.5	5.5	154	2.08	23.5	5.5	1.4	68	3.6	5.9	0.3	77	0.97	0.102	5
1286129	Soil	6.7	47.5	6.0	199	0.8	51.0	2.4	33	0.67	10.5	7.9	0.8	86	9.7	4.4	0.4	40	2.00	0.053	3
1286130	Soil	7.0	44.7	11.4	243	2.4	48.0	8.5	475	1.39	9.1	8.2	0.9	64	7.0	3.5	0.3	43	0.94	0.092	5
1286401	Soil	4.7	11.6	10.6	56	0.6	10.0	2.1	62	1.50	12.7	3.2	0.6	12	0.1	1.7	0.3	79	0.04	0.048	12
1286402	Soil	9.7	20.2	12.7	111	0.8	20.9	2.2	35	1.57	19.4	3.1	0.3	23	0.2	3.9	0.2	128	0.02	0.102	6
1286403	Soil	11.1	31.0	12.7	123	3.5	25.5	3.5	87	2.31	28.3	4.4	0.9	35	0.6	5.4	0.3	148	0.09	0.189	6
1286404	Soil	15.6	69.1	17.3	399	2.6	74.0	12.4	324	3.35	43.4	9.7	0.7	64	3.8	9.8	0.3	178	0.24	0.227	6
1286405	Soil	7.8	58.2	14.4	345	1.8	59.1	6.6	124	2.50	27.5	11.4	1.1	54	2.3	6.8	0.3	81	0.33	0.107	5
1286406	Soil	5.0	47.6	9.5	171	0.6	34.1	6.8	204	2.01	9.5	6.2	2.6	58	1.0	2.4	0.2	58	0.69	0.132	11
1286407	Soil	6.3	44.6	10.5	213	1.7	47.1	4.6	178	1.65	18.9	9.6	1.9	68	2.6	4.3	0.2	80	0.59	0.099	7
1286408	Soil	2.5	56.1	10.8	164	1.0	39.8	4.7	157	1.50	9.7	8.3	1.5	72	2.8	3.3	0.3	63	0.89	0.087	6
1286409	Soil	2.1	30.5	11.3	97	0.9	21.1	10.1	315	1.57	8.8	12.0	1.1	80	1.1	1.6	0.2	50	0.94	0.091	5
1286410	Soil	2.4	47.5	12.1	132	1.2	30.7	5.7	167	2.17	13.4	7.6	1.5	56	1.9	2.3	0.3	67	0.67	0.076	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286111	Soil	13	0.01	673	0.001	2	0.39	0.005	0.06	0.2	0.08	0.3	0.6	0.13	3	4.5	<0.2
1286112	Soil	10	0.02	897	0.002	2	0.36	0.008	0.05	0.2	0.16	0.7	0.4	0.08	3	3.2	<0.2
1286113	Soil	16	0.06	1589	0.008	2	0.54	0.004	0.08	0.2	0.20	1.2	0.7	0.10	4	4.1	<0.2
1286114	Soil	11	0.02	268	0.005	2	0.41	0.005	0.05	0.1	0.07	0.5	0.3	<0.05	3	2.0	<0.2
1286115	Soil	10	0.02	273	0.008	2	0.36	0.006	0.05	0.1	0.07	0.7	0.4	<0.05	3	1.6	<0.2
1286116	Soil	10	0.02	985	0.003	2	0.35	0.008	0.04	0.1	0.17	0.3	0.3	<0.05	2	1.9	<0.2
1286117	Soil	19	0.04	1657	0.003	2	0.65	0.006	0.06	0.2	0.83	1.6	0.5	0.05	3	3.0	<0.2
1286118	Soil	10	0.02	893	0.005	2	0.39	0.007	0.04	0.1	0.25	0.3	0.3	<0.05	3	1.4	<0.2
1286119	Soil	15	0.03	358	0.004	3	0.44	0.007	0.06	0.2	0.19	1.1	0.4	<0.05	3	3.6	<0.2
1286120	Soil	16	0.03	461	0.007	2	0.44	0.006	0.06	0.2	0.27	0.9	0.4	0.06	3	2.9	<0.2
1286121	Soil	12	0.02	391	0.006	2	0.48	0.005	0.05	0.2	0.13	0.6	0.4	<0.05	3	2.1	<0.2
1286122	Soil	11	0.02	195	0.003	2	0.41	0.005	0.05	0.2	0.15	0.7	0.3	<0.05	3	2.5	<0.2
1286123	Soil	12	0.03	398	0.005	2	0.42	0.005	0.05	0.2	0.13	0.8	0.3	<0.05	4	2.0	<0.2
1286124	Soil	10	0.02	153	0.006	1	0.34	0.003	0.05	0.1	0.11	0.4	0.2	<0.05	4	1.3	<0.2
1286125	Soil	15	0.08	262	0.012	2	0.76	0.008	0.03	0.2	0.16	0.9	0.2	<0.05	5	0.7	<0.2
1286126	Soil	8	0.01	167	0.003	2	0.22	0.006	0.03	0.1	0.05	0.2	0.2	<0.05	2	1.0	<0.2
1286127	Soil	12	0.04	381	0.003	2	0.49	0.004	0.04	0.1	0.14	0.3	0.4	<0.05	3	1.5	<0.2
1286128	Soil	14	0.13	1217	0.003	3	0.43	0.006	0.05	0.2	1.20	2.5	0.5	0.16	1	6.2	<0.2
1286129	Soil	11	0.20	681	0.005	7	0.32	0.009	0.03	<0.1	0.54	1.5	0.4	0.77	<1	52.6	<0.2
1286130	Soil	14	0.11	818	0.003	2	0.49	0.005	0.05	0.1	1.12	2.4	0.6	0.16	2	5.7	<0.2
1286401	Soil	16	0.10	140	0.009	2	0.60	0.003	0.04	0.1	0.09	0.7	0.3	<0.05	4	1.4	<0.2
1286402	Soil	18	0.02	294	0.002	2	0.38	0.003	0.05	0.1	0.19	0.6	0.5	<0.05	3	2.0	<0.2
1286403	Soil	24	0.04	474	0.002	3	0.57	0.003	0.06	0.1	0.53	1.5	0.5	<0.05	2	2.4	<0.2
1286404	Soil	28	0.06	1952	0.002	3	0.54	0.005	0.07	0.2	1.12	2.3	0.9	<0.05	2	3.3	<0.2
1286405	Soil	14	0.06	977	0.001	2	0.52	0.006	0.06	<0.1	1.00	2.4	0.4	<0.05	2	3.2	<0.2
1286406	Soil	18	0.26	1393	0.006	5	0.80	0.006	0.13	0.1	0.35	2.7	0.2	0.10	3	2.0	<0.2
1286407	Soil	19	0.15	1727	0.002	4	0.51	0.005	0.08	0.1	1.11	2.9	0.3	0.14	2	2.8	<0.2
1286408	Soil	16	0.21	1348	0.003	5	0.62	0.005	0.08	<0.1	0.63	2.9	0.2	0.20	2	5.3	<0.2
1286409	Soil	14	0.24	967	0.002	4	0.58	0.004	0.08	<0.1	0.56	2.2	0.2	0.18	2	2.5	<0.2
1286410	Soil	16	0.19	1094	0.002	3	0.75	0.005	0.08	0.1	0.47	3.0	0.3	0.19	2	3.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286421	Soil	6.0	30.4	12.2	116	1.1	26.1	9.7	682	1.82	17.3	6.5	1.2	39	1.5	2.9	0.2	69	0.27	0.081	7
1286422	Soil	7.3	29.4	14.0	175	0.8	27.4	14.7	869	2.08	19.3	9.3	1.6	43	1.1	3.4	0.2	77	0.27	0.088	7
1286423	Soil	5.2	36.1	12.7	141	1.4	26.4	15.0	425	1.60	12.3	8.2	1.0	32	1.2	2.7	0.2	76	0.20	0.088	7
1286424	Soil	4.0	17.8	10.1	133	1.1	19.6	9.1	476	1.40	11.7	9.0	0.9	37	0.9	1.9	0.2	54	0.42	0.060	5
1286425	Soil	6.7	24.4	9.2	130	1.0	20.8	11.1	418	2.19	16.1	5.4	0.9	33	1.1	2.9	0.2	56	0.37	0.075	5
1286426	Soil	5.6	50.9	9.6	252	1.5	42.2	14.3	826	2.23	14.0	9.6	1.4	45	2.1	3.1	0.2	62	0.59	0.089	7
1286427	Soil	4.1	27.7	9.9	99	1.1	18.4	2.6	85	1.40	13.8	5.6	0.8	33	1.2	2.5	0.2	58	0.31	0.078	6
1286428	Soil	6.6	23.2	8.4	112	0.7	19.3	4.6	198	1.51	15.3	3.6	1.0	30	0.9	2.9	0.2	70	0.26	0.086	6
1286429	Soil	2.2	25.2	9.8	55	1.5	13.9	1.5	52	1.20	10.6	6.0	0.8	25	1.3	1.2	0.3	52	0.24	0.078	6
1286430	Soil	5.8	31.6	12.7	105	1.7	20.2	2.8	61	1.85	16.5	6.7	1.6	30	1.5	2.8	0.3	81	0.23	0.085	7
1286551	Soil	4.7	40.5	15.3	196	0.4	41.2	13.2	492	3.16	15.0	4.5	2.4	46	1.2	1.7	0.3	53	0.34	0.099	6
1286552	Soil	4.2	22.6	18.3	83	0.1	20.3	4.8	162	3.74	19.2	2.5	0.3	10	0.2	1.8	0.3	72	0.02	0.104	6
1286553	Soil	2.6	41.6	7.3	59	0.8	18.2	5.7	315	1.05	7.3	3.6	0.4	15	4.0	1.1	0.2	35	0.26	0.063	14
1286554	Soil	4.8	32.7	9.0	130	0.6	26.5	5.9	176	1.68	11.9	3.3	1.3	35	1.6	1.9	0.2	57	0.39	0.085	7
1286555	Soil	4.0	48.4	15.0	160	2.0	38.7	13.5	3679	2.99	14.6	10.8	1.8	32	2.4	1.7	0.3	59	0.32	0.131	8
1286556	Soil	1.7	44.3	9.9	95	0.6	35.5	3.2	145	1.66	9.0	4.6	0.9	52	1.6	1.3	0.2	48	0.73	0.085	7
1286557	Soil	3.5	34.7	13.5	122	1.0	30.3	7.5	454	2.35	10.2	6.2	1.9	25	1.2	1.3	0.2	51	0.23	0.099	7
1286558	Soil	3.8	33.5	15.6	145	0.6	32.4	12.9	1204	2.62	13.3	4.8	2.1	34	1.6	1.6	0.2	47	0.36	0.094	8
1286559	Soil	5.6	53.7	12.9	227	0.9	44.1	10.9	453	2.57	15.4	5.4	3.7	41	1.9	3.8	0.3	91	0.39	0.139	17
1286560	Soil	5.2	41.0	13.7	187	0.8	37.9	14.7	488	2.67	14.4	5.0	3.5	30	1.5	2.9	0.2	72	0.25	0.119	14
1286561	Soil	5.2	42.1	13.5	238	0.7	40.4	9.4	408	2.98	17.5	4.5	3.1	40	1.2	2.7	0.3	53	0.54	0.111	9
1286562	Soil	4.4	33.2	12.6	142	0.8	29.1	7.5	352	2.22	12.3	3.3	2.1	33	1.6	1.6	0.2	46	0.35	0.094	7
1286563	Soil	12.3	13.0	9.3	76	0.3	11.9	2.6	72	1.22	8.9	0.7	0.3	19	0.4	1.3	0.2	45	0.09	0.067	6
1286564	Soil	10.9	30.4	22.5	112	0.7	19.4	2.5	62	2.26	32.0	3.0	1.2	32	0.4	5.2	0.4	109	0.04	0.124	6
1286565	Soil	8.3	22.8	21.5	102	0.6	18.6	3.2	105	2.66	36.9	1.6	1.5	25	0.3	4.7	0.3	127	0.02	0.148	7
1286566	Soil	8.6	17.9	15.3	63	0.7	11.0	1.7	35	1.56	22.4	1.2	0.3	16	0.2	3.5	0.2	89	0.02	0.062	5
1286567	Soil	5.7	47.0	12.5	170	2.0	45.7	7.3	213	2.41	16.1	3.7	1.0	45	1.9	3.4	0.2	56	0.23	0.114	7
1286568	Soil	5.4	24.3	11.0	51	0.7	11.0	1.3	25	0.87	10.0	0.6	0.4	25	0.4	2.6	0.2	31	0.15	0.045	4
1286569	Soil	0.1	3.5	1.1	4	0.6	1.0	0.3	9	0.25	<0.5	<0.5	<0.1	6	<0.1	0.1	<0.1	2	0.04	0.026	<1
1286570	Soil	0.5	11.8	3.6	12	0.6	4.3	0.6	14	0.50	1.5	0.5	<0.1	7	0.3	0.3	<0.1	7	0.05	0.057	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286421	Soil	13	0.09	1223	0.001	3	0.64	0.006	0.06	<0.1	0.70	2.2	0.4	0.07	2	2.0	<0.2
1286422	Soil	14	0.11	1559	0.001	3	0.61	0.004	0.07	<0.1	0.71	2.0	0.3	0.06	2	1.8	<0.2
1286423	Soil	16	0.10	1331	0.001	3	0.76	0.006	0.06	0.1	0.95	2.5	0.4	<0.05	2	2.0	<0.2
1286424	Soil	11	0.08	866	0.002	2	0.57	0.010	0.05	<0.1	0.65	1.3	0.3	0.09	2	1.3	<0.2
1286425	Soil	11	0.08	936	0.002	2	0.58	0.009	0.05	<0.1	0.58	1.6	0.3	0.10	2	2.1	<0.2
1286426	Soil	17	0.12	1078	0.001	2	0.82	0.008	0.06	0.1	0.61	3.1	0.3	0.13	2	2.4	<0.2
1286427	Soil	13	0.09	1260	0.002	3	0.52	0.009	0.06	0.1	0.44	1.5	0.2	0.11	2	1.8	<0.2
1286428	Soil	14	0.10	893	0.003	3	0.55	0.009	0.06	0.1	0.35	1.4	0.2	0.09	2	1.7	<0.2
1286429	Soil	13	0.10	657	0.002	2	0.68	0.005	0.07	0.1	0.72	1.3	0.4	0.13	3	1.9	<0.2
1286430	Soil	17	0.11	1088	0.001	2	0.78	0.004	0.06	0.1	0.83	2.0	0.3	0.09	3	2.5	<0.2
1286551	Soil	27	0.34	1088	0.001	2	1.18	0.004	0.08	<0.1	0.35	3.4	0.2	0.09	3	1.6	<0.2
1286552	Soil	24	0.14	155	0.004	2	0.93	0.004	0.06	0.2	0.07	0.8	0.2	<0.05	5	1.2	<0.2
1286553	Soil	12	0.03	1169	0.004	<1	0.65	0.007	0.03	<0.1	0.34	1.2	0.2	<0.05	3	0.7	<0.2
1286554	Soil	17	0.16	1023	0.004	2	0.67	0.006	0.05	0.1	0.21	1.7	0.3	0.11	3	1.4	<0.2
1286555	Soil	28	0.26	1523	0.002	2	1.35	0.008	0.07	0.1	0.77	4.1	0.4	0.10	4	2.3	<0.2
1286556	Soil	20	0.19	1495	0.004	2	0.97	0.008	0.05	0.1	0.25	2.1	0.2	0.22	3	2.5	<0.2
1286557	Soil	23	0.27	1237	0.001	2	1.21	0.007	0.07	<0.1	0.48	3.1	0.3	0.12	3	1.9	<0.2
1286558	Soil	21	0.27	1194	0.002	2	1.04	0.008	0.05	0.1	0.31	2.7	0.2	0.10	3	1.7	<0.2
1286559	Soil	23	0.25	926	0.005	3	1.01	0.007	0.11	0.2	0.37	2.7	0.3	0.08	3	2.1	<0.2
1286560	Soil	23	0.27	778	0.006	3	1.00	0.006	0.09	0.3	0.31	2.6	0.3	0.05	3	1.6	<0.2
1286561	Soil	18	0.25	817	0.003	2	0.87	0.005	0.07	0.2	0.26	2.4	0.2	<0.05	3	1.5	<0.2
1286562	Soil	19	0.20	1301	0.002	2	0.91	0.005	0.06	0.1	0.35	2.5	0.1	<0.05	3	2.2	<0.2
1286563	Soil	18	0.08	617	0.001	2	0.63	0.004	0.05	0.1	0.38	0.4	0.2	<0.05	3	0.6	<0.2
1286564	Soil	12	0.03	193	0.003	1	0.40	0.003	0.05	0.2	0.13	1.2	0.4	<0.05	4	2.9	<0.2
1286565	Soil	12	0.04	185	0.004	<1	0.58	0.002	0.04	0.2	0.12	1.1	0.4	<0.05	4	2.2	<0.2
1286566	Soil	8	0.02	237	0.002	<1	0.37	0.003	0.04	0.2	0.07	0.4	0.3	<0.05	4	1.8	<0.2
1286567	Soil	14	0.14	1787	0.004	<1	0.67	0.008	0.05	0.2	0.69	2.3	0.4	<0.05	2	2.3	<0.2
1286568	Soil	12	0.01	492	0.002	2	0.24	0.005	0.04	0.1	0.19	0.7	0.1	<0.05	1	3.0	<0.2
1286569	Soil	2	<0.01	69	0.002	<1	0.12	0.017	0.01	<0.1	0.09	0.2	<0.1	<0.05	<1	<0.5	<0.2
1286570	Soil	6	0.02	225	0.003	<1	0.25	0.012	0.02	<0.1	0.47	0.5	0.1	<0.05	<1	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286571	Soil	7.8	25.2	12.2	104	0.6	15.2	3.3	118	1.70	16.2	1.5	1.4	20	0.4	2.6	0.2	65	0.07	0.072	7
1286572	Soil	15.5	19.3	16.9	136	0.5	17.4	6.7	273	2.08	18.3	1.7	2.3	37	0.9	3.5	0.3	97	0.16	0.149	11
1286573	Soil	1.9	6.4	8.1	26	<0.1	4.3	0.9	20	0.43	4.8	<0.5	0.1	10	<0.1	0.6	0.1	33	0.02	0.025	8
1286574	Soil	13.3	22.7	13.6	195	0.3	32.4	3.5	109	1.60	20.0	0.5	0.5	29	0.4	5.0	0.2	99	0.07	0.059	9
1286575	Soil	7.0	23.2	8.5	123	0.2	22.3	3.8	58	1.46	12.1	<0.5	0.3	11	0.4	2.6	0.2	76	<0.01	0.032	8
1286576	Soil	14.4	43.8	21.9	267	0.7	43.4	5.8	145	3.09	31.2	1.2	0.2	28	0.6	6.2	0.4	135	0.03	0.166	6
1286577	Soil	11.6	34.8	23.6	283	0.7	41.0	4.0	230	3.28	42.1	5.7	0.2	12	0.8	6.3	0.3	95	0.04	0.193	5
1286578	Soil	4.6	29.2	8.3	73	1.2	14.4	1.7	29	1.35	11.9	2.9	0.1	11	0.8	2.1	0.1	42	0.03	0.125	5
1286579	Soil	6.2	14.4	14.3	82	0.3	14.3	2.3	57	1.27	14.3	2.2	0.4	13	0.2	2.4	0.3	77	0.02	0.044	9
1286580	Soil	11.1	20.2	14.5	122	0.6	20.7	2.9	54	1.61	23.3	1.0	0.5	15	0.3	4.0	0.3	99	0.02	0.047	7
1286581	Soil	17.4	31.5	23.9	212	0.7	37.6	4.0	80	2.94	48.8	2.2	0.2	31	0.5	7.5	0.4	155	0.02	0.126	6
1286582	Soil	9.6	24.9	22.2	151	0.6	26.0	3.7	126	3.40	43.5	1.5	0.7	25	0.3	5.1	0.3	142	0.05	0.171	8
1286583	Soil	9.5	77.4	36.2	170	1.3	39.8	5.2	195	2.87	23.3	<0.5	0.1	331	1.4	5.3	0.4	103	0.33	0.316	14
1286584	Soil	4.9	19.0	12.0	52	0.7	9.3	1.4	53	1.50	14.2	0.8	<0.1	11	2.3	2.3	0.1	40	0.04	0.139	3
1286585	Soil	4.0	19.2	14.4	81	0.1	14.5	4.4	298	2.53	19.0	1.8	1.6	13	0.2	1.9	0.2	66	0.02	0.052	8
1286586	Soil	4.6	17.3	16.0	74	0.3	14.5	3.9	311	2.60	24.1	<0.5	1.7	19	0.2	2.1	0.2	69	0.03	0.075	8
1286587	Soil	3.9	13.1	15.7	51	0.2	10.4	3.3	248	1.98	17.4	<0.5	2.0	14	<0.1	1.4	0.2	62	0.02	0.065	10
1286588	Soil	2.6	7.6	13.6	37	0.2	7.0	1.6	76	1.09	10.0	<0.5	0.3	13	<0.1	1.0	0.2	46	0.02	0.049	9
1286589	Soil	4.5	23.2	13.9	88	0.9	17.6	4.4	281	2.28	16.7	2.6	1.2	20	0.3	2.1	0.2	72	0.03	0.066	8
1286590	Soil	4.9	35.0	16.5	105	0.8	17.7	2.8	178	1.49	10.6	0.7	<0.1	32	0.6	2.1	0.2	58	0.04	0.164	6
1286591	Soil	7.1	52.0	11.6	199	2.0	35.3	4.4	448	2.12	13.8	8.7	1.1	53	1.8	3.5	0.2	85	0.47	0.143	7
1286592	Soil	8.7	61.2	14.8	207	2.1	41.4	6.8	396	2.10	16.5	10.6	1.1	76	1.7	4.0	0.3	72	0.74	0.129	7
1286593	Soil	3.7	33.2	8.6	141	1.8	31.9	5.5	308	1.61	14.0	7.2	0.6	63	1.9	2.6	0.1	48	0.78	0.091	3
1286594	Soil	5.6	39.0	11.5	125	0.7	28.0	6.4	291	1.74	19.0	2.1	0.9	46	2.4	2.4	0.2	63	0.47	0.061	5
1286595	Soil	15.5	49.6	18.4	319	1.0	51.2	4.9	101	3.98	61.3	7.2	1.4	29	0.6	10.0	0.3	168	0.07	0.208	5
1286596	Soil	14.6	26.2	16.5	158	0.5	29.7	3.2	50	2.16	43.8	3.7	1.5	36	0.6	7.0	0.2	145	0.02	0.066	6
1286597	Soil	15.7	29.7	13.1	184	1.4	32.2	3.3	75	2.72	38.6	5.6	0.7	18	0.5	7.4	0.2	172	0.03	0.119	6
1286598	Soil	14.4	29.5	12.2	145	0.5	22.8	2.8	51	1.76	23.3	1.5	0.4	12	0.1	4.3	0.2	163	<0.01	0.051	9
1286599	Soil	15.2	30.3	17.9	210	1.4	37.1	4.4	138	3.25	44.7	5.2	0.7	25	0.6	7.9	0.3	178	0.08	0.220	10
1286600	Soil	4.9	32.8	12.3	91	1.3	20.0	2.3	51	1.13	10.8	6.3	1.4	57	1.8	2.6	0.2	78	0.54	0.048	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286571	Soil	15	0.07	386	0.002	1	0.43	0.003	0.06	0.2	0.27	1.1	0.3	<0.05	3	1.9	<0.2
1286572	Soil	16	0.13	336	0.004	2	0.68	0.003	0.10	0.3	0.17	1.3	0.3	<0.05	3	2.5	<0.2
1286573	Soil	6	0.02	128	0.002	<1	0.41	0.002	0.03	<0.1	0.03	0.2	0.1	<0.05	3	<0.5	<0.2
1286574	Soil	11	0.03	293	0.004	<1	0.44	0.003	0.05	0.1	0.05	0.8	0.3	<0.05	3	2.0	<0.2
1286575	Soil	7	0.02	117	0.002	<1	0.37	0.002	0.04	0.1	0.05	0.6	0.1	<0.05	3	1.0	<0.2
1286576	Soil	14	0.03	168	0.003	1	0.48	0.002	0.05	0.1	0.08	0.5	0.3	<0.05	3	3.2	<0.2
1286577	Soil	19	0.02	182	0.002	<1	0.31	0.003	0.04	0.1	0.37	0.5	0.3	<0.05	2	2.6	<0.2
1286578	Soil	9	0.03	578	0.002	<1	0.49	0.006	0.04	<0.1	0.23	0.4	0.2	<0.05	2	1.0	<0.2
1286579	Soil	9	0.02	189	0.005	<1	0.38	0.003	0.04	0.1	0.05	0.5	0.2	<0.05	3	0.9	<0.2
1286580	Soil	9	0.02	153	0.003	<1	0.50	0.002	0.04	0.2	0.05	0.7	0.3	<0.05	3	1.8	<0.2
1286581	Soil	15	0.02	260	0.003	<1	0.42	0.002	0.06	0.1	0.18	0.6	0.5	<0.05	3	3.4	<0.2
1286582	Soil	16	0.07	251	0.007	<1	0.67	0.003	0.05	0.2	0.12	1.1	0.4	<0.05	4	2.4	<0.2
1286583	Soil	15	0.03	860	0.003	<1	0.74	0.005	0.13	<0.1	0.07	0.3	0.2	0.07	2	5.5	<0.2
1286584	Soil	6	0.02	622	0.002	<1	0.36	0.009	0.04	0.1	0.16	0.2	0.2	<0.05	2	1.4	<0.2
1286585	Soil	14	0.08	238	0.002	1	0.90	0.002	0.05	0.1	0.02	1.4	0.2	<0.05	4	0.8	0.2
1286586	Soil	15	0.09	257	0.003	<1	1.04	0.003	0.05	<0.1	0.03	1.2	0.2	<0.05	4	1.3	<0.2
1286587	Soil	12	0.07	184	0.004	<1	0.87	0.002	0.04	0.1	0.02	1.0	0.2	<0.05	4	0.6	<0.2
1286588	Soil	8	0.05	143	0.004	<1	0.62	0.003	0.03	0.1	0.01	0.7	0.2	<0.05	4	<0.5	<0.2
1286589	Soil	17	0.10	274	0.003	<1	1.07	0.004	0.05	0.1	0.06	1.2	0.2	<0.05	4	1.0	<0.2
1286590	Soil	13	0.03	377	0.002	<1	0.71	0.005	0.05	<0.1	0.17	0.2	0.2	<0.05	3	1.5	<0.2
1286591	Soil	17	0.17	1617	0.002	2	0.99	0.005	0.06	<0.1	0.89	2.7	0.3	<0.05	3	5.0	<0.2
1286592	Soil	15	0.20	1487	0.002	1	0.80	0.005	0.07	<0.1	0.92	2.8	0.3	<0.05	2	4.2	<0.2
1286593	Soil	10	0.15	1044	0.002	2	0.55	0.009	0.03	<0.1	0.58	1.5	0.2	<0.05	2	4.5	<0.2
1286594	Soil	11	0.11	978	0.001	1	0.39	0.003	0.04	0.1	0.30	1.4	0.2	<0.05	2	2.6	<0.2
1286595	Soil	19	0.04	987	0.002	<1	0.67	0.002	0.05	0.2	0.76	1.7	0.4	<0.05	2	4.3	0.2
1286596	Soil	11	0.03	755	0.001	<1	0.51	0.002	0.05	0.1	0.22	1.2	0.4	<0.05	2	3.7	<0.2
1286597	Soil	14	0.03	501	0.003	2	0.56	0.005	0.06	0.2	0.25	1.3	0.5	<0.05	3	3.5	<0.2
1286598	Soil	13	0.02	296	0.005	2	0.47	0.003	0.06	0.2	0.07	0.7	0.3	<0.05	3	1.3	<0.2
1286599	Soil	19	0.05	345	0.007	2	0.74	0.004	0.07	0.2	0.29	1.4	0.5	<0.05	4	2.1	<0.2
1286600	Soil	12	0.06	4011	0.007	2	0.45	0.004	0.05	0.1	0.31	1.7	0.3	0.16	2	3.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286611	Soil	3.7	137.8	22.8	106	1.7	33.7	4.7	109	4.16	12.6	9.9	2.0	22	0.2	1.3	0.4	54	0.07	0.100	5
1286612	Soil	3.6	22.6	6.9	62	0.1	13.5	3.3	77	1.44	10.6	0.9	0.5	6	<0.1	1.4	0.2	61	0.02	0.035	9
1286613	Soil	2.9	72.6	13.9	179	1.2	60.8	23.3	2664	2.59	8.3	6.4	1.7	43	1.0	1.0	0.3	50	0.36	0.103	9
1286614	Soil	1.9	24.9	5.2	45	0.5	13.3	2.1	44	0.90	5.6	1.3	0.6	16	0.2	0.7	0.1	35	0.07	0.042	7
1286615	Soil	3.2	82.4	18.5	325	1.2	122.1	25.2	1192	4.46	24.5	7.9	2.6	87	1.9	1.6	0.3	54	0.43	0.152	10
1286616	Soil	0.7	16.0	7.7	66	0.4	26.6	6.5	153	0.96	6.1	2.4	0.4	59	0.2	0.4	<0.1	20	1.15	0.067	4
1286617	Soil	2.2	30.0	10.6	228	1.0	81.0	20.5	802	3.30	14.3	6.2	1.6	107	1.3	0.9	0.2	40	1.55	0.134	6
1286618	Soil	2.6	68.8	13.5	247	1.1	60.5	8.4	330	1.92	11.0	8.0	1.7	94	3.3	2.7	0.2	79	1.65	0.129	9
1286619	Soil	4.9	92.6	14.0	293	1.4	79.9	9.7	751	2.80	20.8	8.4	1.4	126	3.9	3.8	0.2	97	2.05	0.126	10
1286620	Soil	2.7	33.3	13.8	219	1.0	33.1	8.3	358	2.14	14.9	4.8	3.1	84	1.4	1.8	0.2	98	1.24	0.115	12
1286621	Soil	7.3	67.4	15.0	309	1.6	52.8	10.1	451	2.50	19.7	4.0	3.3	92	4.1	4.0	0.2	141	0.89	0.154	14
1286622	Soil	5.7	54.8	12.0	231	1.3	44.7	6.3	200	2.14	14.8	5.2	1.8	74	2.0	3.3	0.2	103	0.85	0.112	10
1286623	Soil	3.1	48.9	9.7	239	1.2	40.7	6.0	182	1.96	13.3	2.9	1.1	107	1.6	3.0	0.2	86	2.25	0.125	8
1286624	Soil	5.3	51.6	12.9	230	1.1	44.6	9.3	667	2.53	18.4	3.6	2.3	86	2.4	2.8	0.2	107	1.49	0.117	11
1286625	Soil	5.5	33.7	12.0	157	0.9	23.1	4.7	216	2.23	16.0	1.8	2.8	80	1.0	2.5	0.2	120	0.72	0.127	13
1286626	Soil	4.3	41.4	12.3	162	1.0	33.2	6.8	727	2.19	12.8	4.2	2.8	82	1.9	2.2	0.2	94	0.90	0.127	12
1286627	Soil	5.7	38.9	11.5	254	1.0	39.0	6.9	261	2.12	16.1	4.6	2.7	87	1.4	3.4	0.2	98	0.98	0.146	13
1286628	Soil	3.2	55.6	15.9	220	0.7	54.9	14.7	622	3.21	20.7	5.2	1.9	87	2.9	2.2	0.2	45	1.15	0.137	6
1286629	Soil	6.9	30.3	17.6	102	0.8	18.0	3.0	81	2.42	24.7	3.5	0.5	70	0.3	3.4	0.3	113	0.04	0.116	5
1286630	Soil	11.9	36.0	17.4	66	5.2	12.2	2.0	41	1.52	13.4	2.6	0.1	145	1.3	4.9	0.3	158	0.11	0.183	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001408.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286611	Soil	54	0.35	221	0.005	2	1.66	0.005	0.07	0.2	0.33	3.2	0.2	0.13	4	2.5	<0.2
1286612	Soil	11	0.03	286	0.005	1	0.40	0.008	0.04	0.2	0.03	0.7	<0.1	0.08	4	<0.5	<0.2
1286613	Soil	34	0.34	1713	0.004	2	1.25	0.008	0.07	<0.1	0.23	4.1	0.2	0.15	4	2.1	<0.2
1286614	Soil	11	0.07	624	0.005	2	0.59	0.017	0.04	<0.1	0.04	1.1	<0.1	0.08	3	0.7	<0.2
1286615	Soil	34	0.23	1777	0.003	5	1.14	0.006	0.13	<0.1	0.33	5.9	0.2	0.17	3	2.4	<0.2
1286616	Soil	8	0.05	456	0.005	4	0.58	0.029	0.09	<0.1	0.09	1.7	<0.1	0.23	1	<0.5	<0.2
1286617	Soil	18	0.16	902	0.001	6	0.89	0.013	0.12	<0.1	0.20	4.0	0.1	0.19	1	2.7	<0.2
1286618	Soil	22	0.23	782	0.003	7	1.14	0.011	0.12	0.1	2.06	3.3	0.2	0.18	3	5.1	<0.2
1286619	Soil	25	0.25	1291	0.004	98	1.27	0.011	0.15	0.2	1.03	3.7	0.3	0.24	3	7.2	<0.2
1286620	Soil	23	0.29	729	0.004	5	1.29	0.013	0.13	0.3	0.47	3.3	0.2	0.12	3	2.1	<0.2
1286621	Soil	27	0.24	954	0.006	7	1.03	0.007	0.14	0.2	0.70	3.9	0.4	0.11	3	5.0	<0.2
1286622	Soil	23	0.18	892	0.003	5	0.95	0.010	0.10	0.2	0.59	3.3	0.3	0.12	3	2.8	<0.2
1286623	Soil	19	0.18	677	0.003	7	0.84	0.009	0.10	0.2	0.74	2.8	0.2	0.19	2	4.0	<0.2
1286624	Soil	24	0.21	820	0.004	5	1.00	0.010	0.12	0.2	0.84	3.6	0.2	0.16	3	5.7	<0.2
1286625	Soil	21	0.28	596	0.004	5	1.09	0.007	0.12	0.2	0.52	3.0	0.2	0.09	3	2.8	<0.2
1286626	Soil	22	0.25	794	0.003	5	0.98	0.009	0.11	0.1	0.61	3.5	0.3	0.12	3	4.7	<0.2
1286627	Soil	20	0.22	641	0.006	4	0.90	0.011	0.10	0.2	0.45	3.1	0.2	0.11	3	2.6	<0.2
1286628	Soil	24	0.32	1074	0.002	4	0.98	0.007	0.10	<0.1	0.51	4.0	0.2	0.21	2	3.3	<0.2
1286629	Soil	19	0.05	825	0.004	4	0.63	0.003	0.09	0.1	0.09	1.7	0.3	0.16	3	3.1	<0.2
1286630	Soil	30	0.03	657	0.012	3	0.60	0.005	0.09	0.2	1.64	0.6	2.0	0.15	5	11.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1282872	Soil	5.2	28.1	9.1	17	1.7	6.8	0.8	14	1.01	19.8	29.9	<0.1	14	<0.1	3.1	0.1	26	0.02	0.062	3
REP 1282872	QC	5.2	27.8	9.0	17	1.7	6.4	0.8	14	0.97	19.6	29.1	<0.1	14	0.1	3.0	0.1	26	0.02	0.061	3
1282889	Soil	4.6	17.4	15.0	77	0.4	15.5	2.6	96	1.98	15.7	2.3	0.2	18	0.2	2.2	0.2	90	0.04	0.086	10
REP 1282889	QC	4.7	17.6	15.4	76	0.4	15.9	2.6	95	1.98	16.0	1.2	0.2	17	0.2	2.2	0.2	89	0.04	0.086	10
1283300	Soil	4.9	58.2	15.2	207	0.8	47.8	10.7	401	2.97	17.4	8.8	2.0	91	2.0	2.6	0.2	59	1.07	0.102	7
REP 1283300	QC	4.5	56.5	15.0	205	0.8	47.4	10.2	389	2.80	16.7	10.6	2.1	94	1.9	2.8	0.2	59	1.06	0.101	7
1283912	Soil	8.2	21.2	8.7	68	0.3	11.4	8.3	768	1.58	10.1	4.1	0.9	19	1.1	2.0	0.2	65	0.17	0.083	8
REP 1283912	QC	8.9	22.1	9.1	67	0.3	12.0	8.6	800	1.66	10.6	5.3	1.3	21	1.2	2.2	0.2	70	0.18	0.094	9
1283920	Soil	9.3	47.9	11.9	191	0.6	44.1	10.0	735	2.34	20.4	3.6	2.3	59	1.6	3.0	0.2	104	0.70	0.154	13
REP 1283920	QC	9.6	48.7	11.7	194	0.6	45.1	10.0	707	2.28	19.9	5.1	2.4	60	1.4	2.8	0.2	97	0.66	0.154	12
1284072	Soil	6.7	50.8	14.9	102	0.7	27.0	4.7	85	2.56	20.1	3.8	0.3	24	0.5	3.2	0.3	88	0.04	0.095	8
REP 1284072	QC	6.4	51.9	15.1	104	0.7	26.1	4.5	86	2.52	20.7	1.7	0.3	24	0.6	3.3	0.3	92	0.04	0.096	8
1284089	Soil	6.7	37.4	14.2	130	0.9	29.8	4.9	204	1.74	13.3	6.1	1.6	65	1.7	3.0	0.2	75	0.58	0.106	8
REP 1284089	QC	6.4	36.6	14.5	129	0.9	29.4	4.8	202	1.73	13.2	5.5	1.5	62	1.6	3.1	0.3	77	0.57	0.105	8
1284217	Soil	2.6	18.7	11.2	92	0.1	22.9	6.5	91	2.19	14.9	1.8	1.1	22	0.3	1.7	0.2	27	0.03	0.037	3
REP 1284217	QC	2.6	19.6	11.4	100	0.1	25.3	7.0	98	2.36	15.8	1.3	1.2	23	0.3	1.8	0.2	32	0.04	0.039	3
1284309	Soil	7.5	81.8	13.8	471	4.1	89.5	11.8	356	2.34	23.4	12.7	1.6	64	7.3	5.7	0.2	95	0.61	0.146	7
REP 1284309	QC	7.1	76.8	12.4	439	3.6	85.4	11.1	309	2.17	21.2	11.0	1.5	59	6.4	5.4	0.2	92	0.53	0.137	7
1284319	Soil	9.6	75.3	12.9	262	1.8	34.3	4.2	84	2.07	28.9	2.4	1.6	57	2.5	10.3	0.2	92	0.30	0.169	6
REP 1284319	QC	9.3	73.5	12.9	258	1.7	33.1	4.4	88	2.09	28.8	2.8	1.6	58	2.4	10.3	0.2	93	0.30	0.173	6
1286077	Soil	4.9	15.1	13.4	73	1.9	14.4	2.5	61	1.59	16.3	1.2	0.4	32	0.5	2.5	0.2	96	0.02	0.091	9
REP 1286077	QC	4.6	13.8	13.0	69	1.9	13.3	2.4	60	1.53	15.2	1.3	0.4	31	0.4	2.3	0.2	93	0.02	0.090	8
1286100	Soil	5.5	15.2	11.3	66	0.8	10.0	1.7	28	1.19	12.2	1.8	0.5	13	0.2	2.2	0.2	80	0.01	0.038	9
REP 1286100	QC	5.7	15.2	11.4	67	0.8	10.1	1.7	28	1.22	12.3	1.0	0.6	14	0.3	2.2	0.2	83	0.01	0.038	9
1286101	Soil	3.7	11.3	9.7	43	0.4	8.3	1.8	69	1.26	11.7	1.4	0.1	11	0.1	1.4	0.2	60	0.03	0.049	10
REP 1286101	QC	3.7	11.3	9.7	42	0.4	8.3	1.8	66	1.25	11.7	1.8	0.1	10	0.1	1.4	0.2	57	0.03	0.048	9
1286129	Soil	6.7	47.5	6.0	199	0.8	51.0	2.4	33	0.67	10.5	7.9	0.8	86	9.7	4.4	0.4	40	2.00	0.053	3
REP 1286129	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001408.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1282872	Soil	8	0.02	204	0.003	2	0.50	0.017	0.03	<0.1	0.64	0.5	0.4	0.05	2	3.5	<0.2
REP 1282872	QC	8	0.02	200	0.003	2	0.48	0.016	0.03	<0.1	0.70	0.6	0.4	0.05	2	3.5	<0.2
1282889	Soil	16	0.09	133	0.007	<1	0.73	0.005	0.06	0.1	0.03	0.5	0.2	<0.05	4	1.3	<0.2
REP 1282889	QC	15	0.09	131	0.006	<1	0.73	0.006	0.05	0.1	0.03	0.4	0.3	<0.05	5	1.3	<0.2
1283300	Soil	25	0.32	1442	0.002	5	1.06	0.006	0.09	0.2	0.40	3.3	0.2	0.08	3	3.1	<0.2
REP 1283300	QC	22	0.32	1485	0.003	6	1.05	0.007	0.09	0.2	0.50	3.2	0.2	0.06	3	3.1	<0.2
1283912	Soil	15	0.11	736	0.002	2	0.75	0.009	0.08	0.1	0.17	1.2	0.2	<0.05	3	1.5	<0.2
REP 1283912	QC	16	0.12	808	0.004	2	0.84	0.009	0.09	0.2	0.18	1.5	0.2	<0.05	3	1.3	<0.2
1283920	Soil	22	0.27	2110	0.004	3	1.15	0.009	0.13	0.2	0.48	3.2	0.2	0.10	3	2.8	<0.2
REP 1283920	QC	21	0.27	2103	0.005	4	1.20	0.009	0.13	0.1	0.49	3.1	0.2	0.09	4	3.8	<0.2
1284072	Soil	21	0.03	635	0.003	2	0.74	0.005	0.06	0.1	0.21	1.2	0.2	0.05	3	2.0	<0.2
REP 1284072	QC	20	0.04	653	0.006	2	0.78	0.005	0.07	0.1	0.16	1.4	0.2	0.06	3	1.9	<0.2
1284089	Soil	22	0.19	1773	0.002	3	0.85	0.007	0.10	0.2	0.50	2.7	0.3	0.05	3	3.4	<0.2
REP 1284089	QC	22	0.19	1762	0.002	3	0.84	0.007	0.10	0.1	0.52	2.8	0.3	<0.05	3	3.2	<0.2
1284217	Soil	13	0.14	1538	0.001	1	0.67	0.004	0.05	<0.1	0.04	2.0	0.1	<0.05	2	2.5	<0.2
REP 1284217	QC	14	0.15	1583	0.001	<1	0.73	0.005	0.05	<0.1	0.03	2.0	0.1	<0.05	2	2.5	<0.2
1284309	Soil	21	0.10	3326	0.002	2	0.80	0.003	0.07	0.2	1.46	4.1	0.4	<0.05	2	4.6	<0.2
REP 1284309	QC	20	0.10	2986	0.002	3	0.73	0.003	0.07	0.1	1.23	3.8	0.4	<0.05	2	3.9	<0.2
1284319	Soil	17	0.09	967	0.002	4	0.51	0.003	0.08	0.1	1.12	3.3	0.4	0.15	2	12.0	<0.2
REP 1284319	QC	17	0.09	930	0.002	3	0.51	0.003	0.08	0.1	1.15	3.3	0.4	0.15	2	12.0	<0.2
1286077	Soil	16	0.05	309	0.012	2	0.54	0.005	0.07	0.1	0.08	0.9	0.3	<0.05	4	1.3	<0.2
REP 1286077	QC	16	0.05	294	0.007	2	0.54	0.005	0.07	0.1	0.07	0.8	0.3	0.05	4	1.4	<0.2
1286100	Soil	9	0.02	248	0.004	2	0.44	0.003	0.04	0.2	0.04	0.6	0.3	<0.05	4	1.0	<0.2
REP 1286100	QC	10	0.02	260	0.005	2	0.45	0.004	0.04	0.1	0.03	0.5	0.3	<0.05	4	1.0	<0.2
1286101	Soil	12	0.07	136	0.011	2	0.56	0.008	0.04	0.1	0.04	0.4	0.2	<0.05	4	0.8	<0.2
REP 1286101	QC	11	0.07	127	0.010	1	0.56	0.007	0.04	0.1	0.04	0.4	0.2	<0.05	4	0.9	<0.2
1286129	Soil	11	0.20	681	0.005	7	0.32	0.009	0.03	<0.1	0.54	1.5	0.4	0.77	<1	52.6	<0.2
REP 1286129	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001408.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1286553	Soil	2.6	41.6	7.3	59	0.8	18.2	5.7	315	1.05	7.3	3.6	0.4	15	4.0	1.1	0.2	35	0.26	0.063	14
REP 1286553	QC	2.7	43.4	7.4	60	0.9	18.7	5.7	324	1.10	7.6	3.8	0.4	16	4.1	1.2	0.2	39	0.26	0.067	15
1286575	Soil	7.0	23.2	8.5	123	0.2	22.3	3.8	58	1.46	12.1	<0.5	0.3	11	0.4	2.6	0.2	76	<0.01	0.032	8
REP 1286575	QC	7.1	23.2	9.1	122	0.2	22.6	3.8	59	1.42	11.8	<0.5	0.3	11	0.3	2.7	0.2	74	<0.01	0.033	8
1286588	Soil	2.6	7.6	13.6	37	0.2	7.0	1.6	76	1.09	10.0	<0.5	0.3	13	<0.1	1.0	0.2	46	0.02	0.049	9
REP 1286588	QC	2.6	8.1	13.7	39	0.2	6.9	1.7	78	1.11	10.2	<0.5	0.4	13	<0.1	1.1	0.2	47	0.02	0.050	9
1286622	Soil	5.7	54.8	12.0	231	1.3	44.7	6.3	200	2.14	14.8	5.2	1.8	74	2.0	3.3	0.2	103	0.85	0.112	10
REP 1286622	QC	5.4	54.6	11.4	236	1.3	45.7	6.1	192	2.11	15.3	3.5	1.9	74	2.0	3.1	0.2	97	0.86	0.112	9
Reference Materials																					
STD DS8	Standard	13.5	105.9	127.2	304	1.8	37.7	7.7	610	2.45	26.9	110.1	7.1	71	2.4	5.9	6.9	43	0.71	0.081	15
STD DS8	Standard	12.7	101.0	119.9	301	1.8	34.2	7.0	585	2.34	25.6	112.3	7.0	66	2.2	5.5	6.6	42	0.67	0.076	15
STD DS8	Standard	12.5	98.8	121.6	298	1.8	36.9	6.6	588	2.38	23.1	133.7	6.3	61	2.2	5.2	6.1	37	0.66	0.074	15
STD DS8	Standard	12.9	102.9	124.7	302	1.8	35.9	7.0	587	2.42	22.7	114.6	6.7	61	2.1	5.1	6.2	40	0.66	0.076	15
STD DS8	Standard	11.7	97.2	119.8	280	1.7	34.3	6.6	548	2.24	23.1	92.7	6.2	60	2.2	5.2	6.2	38	0.63	0.074	13
STD DS8	Standard	13.1	108.7	120.7	298	1.7	38.0	7.7	587	2.37	22.9	106.1	7.0	60	2.1	5.3	6.2	42	0.66	0.074	15
STD DS8	Standard	11.6	104.8	115.7	293	1.6	35.5	7.2	533	2.25	23.4	98.3	5.7	55	2.3	4.8	6.0	36	0.60	0.072	13
STD DS8	Standard	12.5	107.0	117.2	298	1.7	35.9	7.4	569	2.32	24.1	100.1	6.5	62	2.3	5.2	6.6	46	0.65	0.074	15
STD DS8	Standard	14.4	118.0	114.5	325	1.8	41.8	8.0	669	2.67	26.9	116.6	6.5	72	2.2	5.6	6.5	55	0.76	0.082	17
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001408.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1286553	Soil	12	0.03	1169	0.004	<1	0.65	0.007	0.03	<0.1	0.34	1.2	0.2	<0.05	3	0.7	<0.2
REP 1286553	QC	13	0.04	1206	0.005	1	0.71	0.008	0.04	0.1	0.34	1.2	0.2	<0.05	3	0.7	<0.2
1286575	Soil	7	0.02	117	0.002	<1	0.37	0.002	0.04	0.1	0.05	0.6	0.1	<0.05	3	1.0	<0.2
REP 1286575	QC	7	0.02	111	0.003	<1	0.34	0.002	0.03	0.1	0.02	0.6	0.1	<0.05	3	1.1	<0.2
1286588	Soil	8	0.05	143	0.004	<1	0.62	0.003	0.03	0.1	0.01	0.7	0.2	<0.05	4	<0.5	<0.2
REP 1286588	QC	8	0.05	139	0.004	<1	0.61	0.003	0.03	0.1	<0.01	0.6	0.2	<0.05	4	<0.5	<0.2
1286622	Soil	23	0.18	892	0.003	5	0.95	0.010	0.10	0.2	0.59	3.3	0.3	0.12	3	2.8	<0.2
REP 1286622	QC	21	0.19	857	0.003	5	0.95	0.011	0.10	0.1	0.62	3.3	0.3	0.11	3	3.1	<0.2
Reference Materials																	
STD DS8	Standard	116	0.60	292	0.121	3	0.98	0.127	0.48	2.8	0.19	3.4	5.6	0.14	5	4.7	5.4
STD DS8	Standard	111	0.57	265	0.121	2	0.93	0.111	0.42	2.9	0.19	2.9	5.3	0.15	5	4.9	4.7
STD DS8	Standard	109	0.59	273	0.102	3	0.86	0.084	0.41	2.9	0.21	2.0	5.5	0.15	4	5.1	4.8
STD DS8	Standard	117	0.60	274	0.109	3	0.90	0.082	0.40	3.0	0.17	2.0	5.4	0.15	5	5.0	4.9
STD DS8	Standard	105	0.56	245	0.100	2	0.85	0.079	0.40	2.5	0.19	2.0	5.1	0.16	4	5.0	4.9
STD DS8	Standard	118	0.58	254	0.109	3	0.87	0.079	0.38	2.7	0.20	2.4	5.3	0.20	5	4.9	4.9
STD DS8	Standard	104	0.56	240	0.092	2	0.82	0.085	0.38	2.7	0.19	2.5	5.2	<0.05	4	4.8	4.4
STD DS8	Standard	109	0.58	268	0.104	2	0.88	0.104	0.39	2.7	0.16	3.1	5.1	0.07	5	4.8	4.6
STD DS8	Standard	130	0.63	319	0.127	3	1.00	0.104	0.48	3.2	0.19	3.0	5.4	0.21	5	5.2	5.1
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 06, 2011
Report Date: October 27, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001409.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #23
P.O. Number
Number of Samples: 20

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	20	Sieve soil to 230 mesh			WHI
RJSV	20	Saving all or part of Soil Reject			WHI
1DX2	20	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001409.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286641	Soil	6.6	46.3	13.1	190	2.7	34.4	3.7	121	1.63	17.2	4.9	0.8	113	3.2	4.4	0.2	147	0.35	0.166	7
1286642	Soil	6.8	48.3	13.9	194	2.0	35.8	5.6	208	1.84	19.1	3.2	1.2	96	3.5	4.4	0.3	160	0.36	0.154	9
1286643	Soil	4.8	45.5	12.8	135	1.6	27.3	2.5	55	1.99	18.7	2.9	1.5	81	2.4	4.0	0.3	146	0.28	0.134	9
1286644	Soil	7.7	51.7	13.5	169	1.9	32.2	5.3	199	2.17	22.1	8.0	1.4	98	2.7	4.4	0.3	141	0.37	0.154	7
1286645	Soil	4.6	52.3	10.1	100	2.1	23.0	2.8	120	1.71	15.1	2.8	1.0	97	2.8	3.7	0.2	140	0.33	0.165	7
1286646	Soil	5.8	29.4	13.8	58	1.7	12.8	1.9	85	1.38	20.4	2.3	1.1	88	1.1	2.8	0.3	185	0.22	0.152	9
1286647	Soil	3.3	52.4	12.1	103	2.3	25.0	2.8	93	1.37	11.2	4.2	1.5	96	2.6	3.4	0.2	139	0.42	0.143	10
1286648	Soil	6.1	42.9	12.6	118	1.8	24.6	3.7	160	1.66	12.4	4.0	1.2	82	1.6	3.3	0.2	120	0.44	0.135	9
1286649	Soil	4.7	32.0	9.0	94	1.4	17.5	3.3	145	1.61	11.9	1.2	0.9	44	0.9	2.7	0.2	105	0.23	0.103	7
1286650	Soil	7.2	83.1	11.8	280	2.1	55.4	5.4	489	1.83	11.7	5.7	1.3	101	6.3	5.0	0.2	127	0.39	0.140	9
1286661	Soil	7.5	87.2	14.4	355	1.5	76.5	8.0	484	2.26	19.5	6.1	2.0	113	5.0	4.8	0.2	139	0.75	0.141	10
1286662	Soil	6.9	82.2	14.1	386	1.7	70.8	7.6	455	2.06	17.1	4.8	1.6	121	6.5	5.1	0.2	133	1.11	0.148	9
1286663	Soil	4.6	77.8	12.5	311	1.2	52.5	7.5	305	1.32	12.5	4.1	1.4	103	5.1	4.3	0.2	112	0.93	0.120	9
1286664	Soil	5.6	84.4	13.1	309	1.6	72.2	9.7	848	1.78	13.2	6.1	1.3	98	5.5	5.0	0.2	123	0.87	0.122	9
1286665	Soil	7.8	57.3	13.0	294	1.3	54.8	10.4	902	2.27	18.3	5.2	1.6	93	3.2	3.9	0.2	117	0.72	0.139	9
1286666	Soil	5.9	74.2	13.0	433	1.5	74.4	7.9	671	1.88	12.4	3.8	1.7	100	6.1	4.5	0.2	123	0.70	0.138	10
1286667	Soil	5.9	47.6	8.4	269	1.2	42.6	4.5	379	1.57	13.1	3.8	1.0	66	2.9	3.8	0.1	92	0.49	0.109	6
1286668	Soil	7.8	48.5	10.9	203	1.4	38.5	11.7	675	2.28	12.4	3.0	0.9	63	3.3	3.1	0.2	103	0.46	0.114	7
1286669	Soil	7.1	47.7	9.2	270	1.1	50.1	12.7	878	1.82	12.5	2.2	0.7	62	4.3	3.2	0.2	67	0.58	0.100	7
1286670	Soil	8.7	76.7	15.3	400	1.7	81.1	12.7	1356	2.38	18.1	7.0	1.4	103	5.3	4.8	0.2	143	0.91	0.134	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

CERTIFICATE OF ANALYSIS WHI11001409.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286641	Soil	23	0.09	1605	0.004	5	0.73	0.008	0.11	0.2	1.36	2.0	0.5	0.06	3	5.2	<0.2
1286642	Soil	24	0.13	1309	0.004	8	0.87	0.005	0.11	0.1	1.12	2.3	0.4	0.06	3	5.5	<0.2
1286643	Soil	23	0.11	1415	0.003	5	0.86	0.006	0.09	0.1	1.16	2.4	0.4	<0.05	3	6.3	<0.2
1286644	Soil	24	0.11	1727	0.003	5	0.83	0.007	0.09	0.1	1.05	2.6	0.4	0.06	3	6.9	<0.2
1286645	Soil	23	0.08	2117	0.003	6	0.70	0.006	0.07	0.1	1.10	2.4	0.4	0.06	2	8.4	<0.2
1286646	Soil	28	0.08	1087	0.003	5	0.71	0.003	0.10	0.1	0.86	1.2	0.6	<0.05	3	3.1	<0.2
1286647	Soil	28	0.11	2165	0.005	4	0.76	0.004	0.09	0.2	1.41	2.5	0.5	<0.05	3	6.0	<0.2
1286648	Soil	24	0.12	1525	0.005	6	0.85	0.005	0.10	0.1	1.03	2.2	0.4	0.07	3	3.9	<0.2
1286649	Soil	18	0.09	814	0.005	2	0.71	0.010	0.07	0.1	0.76	1.6	0.3	<0.05	2	2.6	<0.2
1286650	Soil	25	0.12	1851	0.003	7	0.89	0.004	0.12	0.1	1.57	3.6	0.4	<0.05	3	5.2	<0.2
1286661	Soil	23	0.19	1602	0.003	7	0.86	0.004	0.14	0.1	1.06	4.0	0.4	0.07	3	6.1	<0.2
1286662	Soil	26	0.20	1378	0.003	7	0.82	0.005	0.13	<0.1	1.00	3.5	0.4	0.12	2	6.8	<0.2
1286663	Soil	22	0.18	1313	0.003	7	0.81	0.006	0.12	0.1	0.96	3.3	0.3	0.14	2	7.2	<0.2
1286664	Soil	24	0.17	1288	0.003	4	0.83	0.007	0.11	0.1	0.96	3.1	0.3	0.07	2	8.1	<0.2
1286665	Soil	23	0.16	1762	0.005	6	0.87	0.006	0.12	<0.1	0.84	3.0	0.3	0.06	2	4.6	<0.2
1286666	Soil	24	0.17	1583	0.003	6	0.87	0.005	0.13	0.1	1.09	3.2	0.4	0.09	3	6.7	<0.2
1286667	Soil	14	0.09	926	0.003	5	0.58	0.015	0.08	<0.1	0.83	2.0	0.3	0.09	2	4.9	<0.2
1286668	Soil	17	0.11	861	0.004	5	0.67	0.010	0.09	0.1	0.70	2.4	0.3	<0.05	2	5.5	<0.2
1286669	Soil	16	0.12	1233	0.005	3	0.61	0.013	0.08	0.1	0.56	2.1	0.2	0.08	2	4.6	<0.2
1286670	Soil	27	0.18	1533	0.003	8	0.95	0.007	0.14	0.1	1.28	3.6	0.4	0.10	3	8.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

QUALITY CONTROL REPORT WHI11001409.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1286644	Soil	7.7	51.7	13.5	169	1.9	32.2	5.3	199	2.17	22.1	8.0	1.4	98	2.7	4.4	0.3	141	0.37	0.154	7
REP 1286644	QC	8.5	52.3	13.7	171	1.9	33.0	5.2	198	2.23	23.2	3.8	1.4	106	3.0	4.2	0.2	148	0.37	0.162	8
1286670	Soil	8.7	76.7	15.3	400	1.7	81.1	12.7	1356	2.38	18.1	7.0	1.4	103	5.3	4.8	0.2	143	0.91	0.134	9
REP 1286670	QC	8.5	76.6	13.2	408	1.7	78.9	11.9	1253	2.25	17.0	5.2	1.5	100	4.8	4.8	0.2	140	0.87	0.137	10
Reference Materials																					
STD DS8	Standard	13.1	110.6	118.8	313	1.8	38.7	7.6	592	2.42	24.5	105.4	7.0	68	2.3	5.6	6.6	48	0.71	0.074	16
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 27, 2011

QUALITY CONTROL REPORT WHI11001409.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1286644	Soil	24	0.11	1727	0.003	5	0.83	0.007	0.09	0.1	1.05	2.6	0.4	0.06	3	6.9	<0.2
REP 1286644	QC	25	0.12	1925	0.003	5	0.89	0.007	0.10	0.1	1.02	2.7	0.4	0.06	3	7.1	<0.2
1286670	Soil	27	0.18	1533	0.003	8	0.95	0.007	0.14	0.1	1.28	3.6	0.4	0.10	3	8.1	<0.2
REP 1286670	QC	26	0.17	1462	0.003	7	0.92	0.005	0.13	0.1	1.16	3.4	0.4	0.12	3	9.6	<0.2
Reference Materials																	
STD DS8	Standard	120	0.57	273	0.129	2	0.92	0.079	0.41	2.7	0.17	2.2	5.0	0.10	5	5.1	4.7
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 07, 2011
Report Date: November 03, 2011
Page: 1 of 7

CERTIFICATE OF ANALYSIS WHI11001410.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #24
P.O. Number
Number of Samples: 160

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	160	Sieve soil to 230 mesh			WHI
RJSV	160	Saving all or part of Soil Reject			WHI
1DX2	160	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001410.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1284111	Soil		45.2	50.2	11.7	848	0.9	127.0	12.8	850	3.09	24.4	3.0	2.5	66	3.8	4.9	0.3	63	1.31	0.148
1284112	Soil		31.7	57.0	12.6	1211	1.5	125.1	10.5	1652	6.44	77.8	3.5	2.8	87	8.8	8.5	0.2	106	0.93	0.520
1284113	Soil		41.7	69.7	14.6	1161	1.4	160.7	13.4	1038	5.55	87.7	3.5	3.2	82	12.0	8.8	0.3	106	0.88	0.411
1284114	Soil		1.9	27.6	21.1	85	<0.1	30.4	14.2	167	2.25	23.8	<0.5	0.7	31	<0.1	0.8	0.4	22	0.04	0.066
1284115	Soil		1.3	15.3	15.3	81	<0.1	14.2	8.1	140	1.63	22.7	1.0	0.6	16	<0.1	0.8	0.4	17	0.07	0.055
1284116	Soil		1.2	22.9	16.6	92	<0.1	23.2	14.5	400	1.93	18.0	1.7	0.7	24	0.2	0.7	0.3	15	0.05	0.063
1284117	Soil		2.4	47.7	21.1	237	0.2	57.9	51.1	1716	4.58	17.3	0.6	1.8	15	0.3	1.3	0.3	32	0.05	0.106
1284118	Soil		2.9	23.9	22.0	93	<0.1	23.1	10.3	367	4.75	17.4	0.9	0.9	19	<0.1	1.5	0.4	41	0.03	0.074
1284119	Soil		1.5	21.0	30.8	80	<0.1	24.9	18.2	1126	2.68	12.8	0.5	0.4	9	0.1	1.0	0.2	20	0.05	0.099
1284120	Soil		1.9	26.4	33.3	111	0.2	33.0	37.6	2051	3.88	16.5	0.9	0.9	10	0.2	1.4	0.3	31	0.04	0.110
1284121	Soil		2.1	22.5	16.0	84	0.1	20.4	10.7	667	3.93	15.2	<0.5	0.3	8	<0.1	1.4	0.3	37	0.03	0.133
1284122	Soil		1.9	29.1	23.1	125	<0.1	36.5	19.0	570	4.02	18.4	0.7	0.8	11	0.1	1.3	0.3	32	0.05	0.104
1284123	Soil		1.5	26.4	16.9	123	<0.1	38.1	18.2	432	3.19	25.8	0.5	0.8	9	0.2	2.1	0.3	26	0.01	0.074
1284124	Soil		14.3	51.0	21.2	691	1.1	109.9	19.4	551	3.75	24.5	<0.5	2.0	67	6.8	8.5	0.2	91	0.24	0.095
1284125	Soil		13.9	18.9	22.1	86	2.4	25.5	3.4	60	2.44	26.8	1.0	1.0	51	0.5	7.3	0.2	77	0.07	0.123
1284126	Soil		2.2	15.5	9.1	40	1.6	7.8	1.5	59	1.33	5.3	2.3	0.1	40	0.1	1.2	0.1	24	0.02	0.140
1284127	Soil		1.6	33.0	20.7	65	0.5	12.0	3.4	160	2.52	16.7	2.9	0.7	12	<0.1	0.8	0.2	33	0.03	0.098
1284128	Soil		1.6	22.6	20.9	57	0.3	11.6	3.4	183	2.35	16.7	1.7	0.7	12	<0.1	0.7	0.3	35	0.02	0.099
1284129	Soil		1.3	29.9	22.8	77	0.5	19.2	5.5	138	1.96	13.0	0.9	1.2	45	0.3	0.6	0.3	25	0.04	0.077
1284130	Soil		2.8	31.8	29.4	71	1.4	17.8	4.8	115	2.03	12.5	3.0	0.9	61	0.2	1.0	0.3	32	0.07	0.116
1284131	Soil		4.1	31.4	31.9	87	1.3	19.1	5.1	147	2.43	15.8	3.7	0.8	65	0.2	1.5	0.3	42	0.05	0.166
1284132	Soil		9.7	13.6	22.1	49	1.3	9.2	1.8	69	1.92	13.2	<0.5	0.5	30	0.3	5.3	0.2	66	0.04	0.131
1284133	Soil		7.5	9.0	22.3	30	1.1	5.7	1.0	23	1.81	12.0	<0.5	0.5	29	0.2	4.0	0.3	44	0.05	0.104
1284134	Soil		14.5	35.3	31.3	90	5.2	22.3	2.2	103	2.92	17.2	1.9	1.3	128	0.7	7.2	0.4	105	0.61	0.484
1284135	Soil		7.9	19.4	26.2	105	1.8	13.2	3.0	54	2.92	19.0	0.7	1.2	91	0.3	4.1	0.3	50	0.11	0.352
1284136	Soil		34.1	26.3	31.0	89	5.7	22.0	2.6	35	3.24	34.6	1.3	2.3	148	0.4	14.1	0.3	160	0.13	0.798
1284137	Soil		11.2	61.9	16.9	844	2.3	121.8	15.4	200	3.81	19.0	<0.5	1.7	175	1.0	6.8	0.2	191	0.18	0.592
1284138	Soil		0.3	3.3	1.6	5	0.1	1.3	0.6	16	0.32	<0.5	<0.5	<0.1	8	<0.1	0.2	<0.1	7	0.04	0.037
1284139	Soil		5.3	21.4	13.7	110	1.6	19.7	3.8	79	2.65	14.8	3.6	0.6	61	0.4	3.5	0.2	64	0.18	0.295
1284140	Soil		1.9	10.5	9.8	45	0.4	8.0	1.6	34	1.11	7.1	<0.5	0.1	21	0.1	0.9	0.2	32	0.03	0.161

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001410.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284111	Soil	10	19	0.30	1010	0.003	7	1.05	0.008	0.13	0.2	0.36	2.7	0.2	0.12	3	4.7	<0.2
1284112	Soil	10	22	0.24	1340	0.005	6	0.97	0.007	0.14	0.3	0.70	3.4	0.4	0.07	2	10.1	<0.2
1284113	Soil	13	25	0.29	1406	0.004	7	1.15	0.007	0.16	0.3	0.69	3.6	0.4	0.09	3	10.3	0.2
1284114	Soil	4	8	0.04	125	<0.001	<1	0.47	0.004	0.07	0.1	0.02	1.7	0.2	<0.05	2	<0.5	<0.2
1284115	Soil	3	7	0.06	306	<0.001	<1	0.51	0.005	0.06	<0.1	0.02	0.9	0.2	<0.05	2	<0.5	<0.2
1284116	Soil	4	7	0.08	319	0.005	<1	0.54	0.005	0.07	<0.1	0.02	1.6	0.2	<0.05	2	<0.5	<0.2
1284117	Soil	4	22	0.31	211	0.005	<1	1.25	0.008	0.09	<0.1	0.03	3.7	0.5	<0.05	4	<0.5	<0.2
1284118	Soil	6	24	0.15	112	0.006	<1	1.13	0.004	0.09	<0.1	0.03	1.7	0.2	<0.05	5	0.9	<0.2
1284119	Soil	3	14	0.10	167	0.003	2	0.71	0.014	0.07	<0.1	0.05	1.4	0.3	<0.05	2	<0.5	<0.2
1284120	Soil	5	16	0.17	153	0.007	1	0.93	0.016	0.08	0.1	0.05	2.5	0.4	<0.05	3	<0.5	<0.2
1284121	Soil	4	22	0.12	103	0.005	1	0.98	0.008	0.06	<0.1	0.07	0.8	0.1	0.06	5	<0.5	<0.2
1284122	Soil	5	20	0.20	125	0.004	<1	1.04	0.005	0.06	<0.1	0.03	1.8	0.2	<0.05	3	<0.5	<0.2
1284123	Soil	3	14	0.06	202	0.001	<1	0.58	0.005	0.06	<0.1	0.04	2.1	0.2	<0.05	2	<0.5	<0.2
1284124	Soil	5	11	0.03	1205	0.002	1	0.93	0.012	0.11	<0.1	0.22	5.7	0.6	0.13	1	3.8	<0.2
1284125	Soil	5	13	0.04	785	0.001	2	0.55	0.010	0.13	<0.1	0.15	1.6	0.7	0.20	2	4.4	<0.2
1284126	Soil	3	11	0.02	905	0.001	3	0.46	0.015	0.10	<0.1	0.11	0.3	0.2	0.18	2	3.0	<0.2
1284127	Soil	3	17	0.11	200	0.003	<1	1.02	0.013	0.06	<0.1	0.04	1.6	0.1	<0.05	3	<0.5	<0.2
1284128	Soil	3	19	0.07	188	0.003	2	0.97	0.009	0.07	<0.1	0.05	1.0	<0.1	<0.05	3	0.9	<0.2
1284129	Soil	3	17	0.10	1113	<0.001	3	0.81	0.008	0.11	0.2	0.07	2.2	0.1	0.11	2	1.7	<0.2
1284130	Soil	5	21	0.10	1214	0.001	2	0.88	0.013	0.14	<0.1	0.15	2.0	0.1	0.17	3	2.2	<0.2
1284131	Soil	4	23	0.08	1288	0.004	3	0.96	0.009	0.15	<0.1	0.12	1.7	0.2	0.20	3	2.4	0.3
1284132	Soil	2	11	0.02	729	0.001	3	0.48	0.015	0.18	<0.1	0.06	1.1	0.6	0.32	2	6.2	<0.2
1284133	Soil	2	9	0.01	479	<0.001	3	0.35	0.015	0.21	0.5	0.05	0.9	0.6	0.38	2	3.5	<0.2
1284134	Soil	9	28	0.03	322	0.002	7	0.82	0.020	0.26	<0.1	0.28	2.8	0.4	0.40	3	18.5	<0.2
1284135	Soil	6	18	0.03	630	0.002	3	0.56	0.013	0.16	<0.1	0.30	2.2	0.6	0.28	2	5.9	<0.2
1284136	Soil	10	39	0.03	821	0.005	5	0.69	0.011	0.20	<0.1	0.60	4.9	0.6	0.28	3	21.7	<0.2
1284137	Soil	11	37	0.03	1197	0.007	5	2.09	0.011	0.13	<0.1	0.23	3.2	0.2	0.14	2	7.4	0.2
1284138	Soil	<1	3	0.02	63	0.004	<1	0.22	0.030	0.03	<0.1	0.03	0.2	<0.1	<0.05	1	<0.5	<0.2
1284139	Soil	9	23	0.08	1418	0.004	2	0.67	0.007	0.09	0.2	0.15	0.6	0.3	0.12	3	3.1	<0.2
1284140	Soil	4	11	0.03	509	0.002	2	0.61	0.015	0.06	<0.1	0.04	0.3	0.2	0.08	2	0.5	0.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001410.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1284141	Soil		1.2	7.3	6.7	24	0.2	4.7	1.3	147	1.00	5.3	0.9	0.2	9	<0.1	0.5	0.1	21	0.03	0.075
1284142	Soil		2.3	23.3	19.3	64	0.2	10.7	2.9	77	3.51	17.2	<0.5	0.3	15	<0.1	1.3	0.3	46	0.03	0.112
1284143	Soil		2.4	18.7	17.0	50	0.6	9.7	2.8	188	2.66	16.3	3.4	0.3	29	<0.1	1.1	0.2	39	0.04	0.171
1284144	Soil		2.3	25.7	14.8	109	1.2	12.2	3.8	130	6.65	8.6	0.8	0.2	13	0.1	0.9	0.2	34	0.04	0.149
1284145	Soil		2.6	31.5	20.0	79	0.9	19.0	8.5	378	3.11	17.6	1.4	0.4	17	0.3	1.3	0.2	45	0.04	0.163
1284146	Soil		1.8	13.7	8.1	37	0.3	9.8	3.2	125	1.44	7.7	0.9	0.2	10	0.1	0.7	0.2	27	0.04	0.084
1284147	Soil		1.6	14.2	8.7	40	0.2	8.9	2.6	81	1.59	8.9	1.9	0.2	10	<0.1	0.8	0.2	31	0.03	0.064
1284148	Soil		0.7	8.5	3.7	13	<0.1	2.8	1.1	40	0.74	2.7	<0.5	<0.1	6	<0.1	0.3	0.1	19	0.03	0.050
1284149	Soil		3.1	19.1	11.4	60	<0.1	13.8	4.0	184	2.65	12.6	1.2	0.2	11	<0.1	1.3	0.3	63	0.03	0.070
1284150	Soil		2.4	23.6	17.0	63	0.2	13.7	4.8	283	3.76	17.2	1.9	0.4	14	0.1	0.9	0.3	48	0.03	0.112
1284151	Soil		0.7	7.6	3.4	13	0.1	2.2	1.0	29	0.66	2.9	1.8	<0.1	6	<0.1	0.2	<0.1	14	0.03	0.046
1284152	Soil		1.8	15.7	9.6	52	0.3	10.8	3.1	254	2.64	9.7	2.3	0.3	13	0.1	1.0	0.3	45	0.05	0.128
1284153	Soil		1.2	8.0	4.9	24	<0.1	4.0	1.6	122	1.24	4.6	<0.5	<0.1	8	<0.1	0.5	0.1	21	0.03	0.050
1284154	Soil		2.3	13.8	9.6	41	0.2	8.5	2.9	164	1.98	9.8	2.7	0.2	11	<0.1	0.8	0.2	41	0.03	0.075
1284155	Soil		2.4	15.6	14.0	45	0.2	9.1	4.0	182	2.43	11.6	1.6	0.3	13	<0.1	0.7	0.3	45	0.02	0.129
1284156	Soil		1.7	10.7	7.4	31	<0.1	7.2	2.1	71	1.51	5.7	1.3	0.2	8	<0.1	0.4	0.2	33	0.03	0.069
1284157	Soil		1.6	15.0	7.6	38	<0.1	8.8	2.6	73	1.77	5.9	2.0	0.3	8	<0.1	0.5	0.2	42	0.03	0.089
1284158	Soil		0.4	4.8	1.8	6	<0.1	1.3	0.9	19	0.45	0.8	0.8	<0.1	7	<0.1	<0.1	<0.1	13	0.05	0.032
1284159	Soil		2.0	12.5	7.5	39	0.2	7.9	2.6	68	1.19	6.6	1.4	0.1	8	<0.1	0.6	0.2	45	0.02	0.060
1284160	Soil		1.7	28.0	16.8	54	0.1	13.2	4.9	220	2.93	9.4	1.3	0.3	11	0.2	0.7	0.3	59	0.03	0.127
1286151	Soil		1.7	24.6	26.5	117	0.1	32.8	14.7	497	4.96	51.9	0.8	0.8	10	0.3	1.9	0.4	43	0.02	0.132
1286152	Soil		2.0	18.1	12.2	96	<0.1	18.5	8.5	209	3.20	16.0	<0.5	0.3	7	0.1	1.3	0.3	45	0.02	0.082
1286153	Soil		2.3	19.9	16.3	112	0.2	18.2	8.2	388	4.73	16.4	<0.5	0.6	11	0.5	1.1	0.3	64	0.04	0.104
1286154	Soil		2.2	16.5	17.7	122	0.2	18.7	9.0	396	5.26	18.2	<0.5	1.1	8	0.6	1.1	0.3	64	0.03	0.144
1286155	Soil		1.9	13.8	16.1	62	0.3	10.0	4.5	222	2.67	12.5	2.0	0.3	8	0.5	0.8	0.2	57	0.04	0.139
1286156	Soil		6.3	16.0	17.9	68	0.9	12.3	3.2	69	1.80	16.5	1.5	0.2	36	0.2	2.8	0.2	85	0.02	0.076
1286157	Soil		10.1	15.8	15.7	91	0.9	14.6	3.2	57	2.34	22.7	1.8	0.3	32	0.3	3.6	0.2	86	0.02	0.086
1286158	Soil		1.1	28.2	23.0	111	0.2	36.7	19.9	283	2.75	21.1	1.2	1.9	18	0.2	0.6	0.4	41	0.03	0.042
1286159	Soil		1.7	40.2	30.0	112	0.6	27.4	9.3	286	3.55	21.6	4.9	2.3	50	0.2	0.7	0.3	40	0.07	0.076
1286160	Soil		1.5	18.9	13.6	32	2.7	9.5	1.8	24	1.02	5.9	1.1	0.3	44	0.3	0.6	0.1	24	0.04	0.099

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001410.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284141	Soil	3	8	0.03	148	0.003	1	0.38	0.018	0.05	<0.1	0.04	0.2	<0.1	<0.05	2	<0.5	<0.2
1284142	Soil	6	19	0.06	194	0.004	<1	0.96	0.005	0.06	0.2	0.04	0.6	0.1	<0.05	4	1.3	<0.2
1284143	Soil	6	19	0.08	318	0.008	2	0.92	0.013	0.08	0.1	0.07	0.6	0.2	0.06	3	1.9	<0.2
1284144	Soil	3	14	0.07	384	0.004	2	0.94	0.012	0.06	<0.1	0.15	0.8	0.1	0.06	3	2.1	<0.2
1284145	Soil	6	22	0.16	314	0.004	3	1.12	0.008	0.09	<0.1	0.09	1.0	0.1	0.07	3	1.6	<0.2
1284146	Soil	5	14	0.11	110	0.005	2	0.84	0.016	0.05	0.1	0.04	0.5	<0.1	<0.05	3	<0.5	<0.2
1284147	Soil	5	15	0.10	89	0.006	3	0.75	0.016	0.05	0.1	0.05	0.3	<0.1	0.06	3	1.1	<0.2
1284148	Soil	3	5	0.03	61	0.007	<1	0.61	0.024	0.03	<0.1	0.04	0.3	<0.1	0.07	3	<0.5	<0.2
1284149	Soil	14	24	0.10	156	0.010	1	0.93	0.005	0.07	<0.1	0.02	0.5	0.2	0.06	5	1.6	<0.2
1284150	Soil	5	28	0.10	181	0.004	<1	1.08	0.004	0.06	<0.1	0.06	0.7	0.1	0.06	4	1.3	<0.2
1284151	Soil	2	6	0.02	51	0.004	1	0.60	0.021	0.03	<0.1	0.05	0.2	<0.1	<0.05	2	<0.5	<0.2
1284152	Soil	5	17	0.06	182	0.005	2	0.86	0.008	0.07	<0.1	0.08	0.5	0.1	0.09	4	<0.5	0.2
1284153	Soil	3	8	0.03	70	0.004	<1	0.61	0.020	0.04	<0.1	0.04	0.2	<0.1	<0.05	3	<0.5	<0.2
1284154	Soil	7	14	0.06	112	0.010	<1	0.71	0.013	0.05	<0.1	0.03	0.3	0.1	<0.05	4	0.8	<0.2
1284155	Soil	5	18	0.06	144	0.004	<1	0.78	0.011	0.07	<0.1	0.03	0.4	0.1	0.06	3	0.6	<0.2
1284156	Soil	5	14	0.07	76	0.004	<1	0.80	0.014	0.05	0.1	0.03	0.4	<0.1	<0.05	3	1.1	<0.2
1284157	Soil	5	15	0.07	110	0.003	<1	0.92	0.011	0.06	<0.1	0.02	0.5	0.1	<0.05	4	0.9	<0.2
1284158	Soil	2	2	0.03	24	0.014	<1	0.54	0.029	0.02	<0.1	0.03	0.3	<0.1	<0.05	2	1.0	<0.2
1284159	Soil	7	11	0.04	134	0.004	<1	0.64	0.010	0.06	<0.1	0.02	0.4	0.1	<0.05	4	<0.5	<0.2
1284160	Soil	9	24	0.07	185	0.005	<1	1.05	0.007	0.07	<0.1	0.03	0.5	0.2	0.05	6	1.2	<0.2
1286151	Soil	3	23	0.15	89	0.004	<1	1.03	0.004	0.09	<0.1	0.03	1.5	0.2	<0.05	4	0.5	<0.2
1286152	Soil	3	19	0.10	114	0.004	<1	0.87	0.007	0.08	<0.1	0.03	1.1	0.1	<0.05	5	1.0	<0.2
1286153	Soil	7	26	0.20	168	0.005	1	1.43	0.005	0.10	0.1	0.04	1.3	0.2	<0.05	6	0.9	<0.2
1286154	Soil	5	30	0.20	166	0.006	<1	1.50	0.005	0.08	<0.1	0.05	1.6	0.1	<0.05	7	0.6	<0.2
1286155	Soil	4	16	0.07	128	0.006	1	0.74	0.010	0.07	<0.1	0.03	0.4	0.1	<0.05	4	1.2	<0.2
1286156	Soil	7	13	0.04	292	0.004	<1	0.70	0.010	0.08	<0.1	0.03	0.5	0.3	0.06	4	2.2	<0.2
1286157	Soil	6	14	0.05	214	0.005	<1	0.52	0.012	0.07	<0.1	0.04	0.6	0.2	<0.05	3	2.8	<0.2
1286158	Soil	3	25	0.26	505	<0.001	<1	1.40	0.005	0.08	<0.1	0.06	2.6	<0.1	<0.05	4	1.2	<0.2
1286159	Soil	4	25	0.19	301	0.001	<1	1.39	0.005	0.08	<0.1	0.07	2.7	<0.1	<0.05	4	1.9	0.2
1286160	Soil	3	10	0.03	742	0.002	2	0.65	0.013	0.07	<0.1	0.11	1.1	0.1	<0.05	2	1.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001410.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1286171	Soil		1.7	22.2	12.1	92	1.0	23.5	7.3	144	1.58	8.5	4.9	0.7	38	0.6	0.5	0.2	33	0.11	0.074
1286172	Soil		3.8	22.3	15.5	108	0.4	27.0	8.7	373	2.28	12.9	2.1	1.2	25	0.4	1.0	0.2	53	0.06	0.086
1286173	Soil		4.4	25.2	13.5	107	0.5	26.1	5.3	125	1.96	14.2	4.6	0.7	37	0.4	1.4	0.2	47	0.21	0.078
1286174	Soil		10.0	43.2	17.8	980	0.7	129.1	33.0	1054	2.58	27.1	2.9	1.4	63	9.0	2.7	0.2	58	0.52	0.124
1286175	Soil		3.8	21.4	11.1	99	1.0	23.3	5.6	127	1.79	14.1	1.2	0.7	31	0.5	1.4	0.2	42	0.18	0.107
1286176	Soil		3.5	23.5	10.8	112	0.3	27.7	7.4	198	1.76	14.4	1.2	0.4	20	0.6	1.3	0.2	35	0.11	0.089
1286177	Soil		1.5	45.2	12.6	550	0.9	196.9	11.9	407	2.14	10.1	5.5	1.6	51	0.4	0.6	0.2	36	0.39	0.107
1286178	Soil		3.4	31.6	16.2	238	0.4	61.0	8.5	272	2.92	14.4	4.6	2.0	37	0.5	0.9	0.2	43	0.14	0.074
1286179	Soil		4.6	18.6	19.2	55	0.6	13.6	2.8	131	1.67	11.8	<0.5	0.4	37	0.3	0.5	0.2	51	0.03	0.168
1286180	Soil		1.4	7.8	8.8	34	0.4	7.4	1.8	56	0.82	4.7	1.9	0.2	17	0.1	0.4	0.1	23	0.02	0.077
1286411	Soil		3.7	56.5	12.5	123	0.7	36.5	6.9	237	2.48	11.4	14.7	1.7	76	1.0	1.9	0.3	47	0.72	0.091
1286412	Soil		1.6	38.4	7.9	117	1.2	29.7	3.8	141	1.57	7.7	11.5	0.7	88	1.3	1.6	0.1	45	1.14	0.083
1286413	Soil		4.3	28.7	13.1	106	0.5	17.4	5.1	158	2.28	19.1	6.6	1.7	42	1.5	2.5	0.3	76	0.26	0.100
1286414	Soil		15.4	55.7	17.1	199	0.7	42.0	6.3	155	2.21	50.2	3.8	2.2	57	1.9	9.0	0.2	74	0.25	0.097
1286415	Soil		3.8	55.1	14.0	84	1.5	21.6	2.4	47	1.98	21.1	10.4	1.1	44	2.7	3.2	0.3	96	0.26	0.116
1286416	Soil		2.6	37.3	11.8	145	2.1	33.2	4.7	202	1.98	14.8	10.4	0.5	47	2.4	2.1	0.2	70	0.46	0.125
1286417	Soil		8.4	55.6	11.5	210	1.0	36.1	6.8	152	2.03	24.6	7.0	2.2	53	2.0	5.2	0.2	77	0.29	0.118
1286418	Soil		9.3	36.5	14.3	137	1.2	25.5	4.0	141	2.99	40.5	9.6	0.8	37	1.7	4.5	0.2	90	0.16	0.136
1286419	Soil		7.2	36.1	14.5	166	1.2	30.8	7.4	496	1.97	24.1	9.5	1.3	47	2.0	3.3	0.2	70	0.24	0.098
1286420	Soil		5.4	21.1	9.7	75	1.1	18.8	2.2	94	1.75	20.1	7.8	0.4	34	1.0	2.3	0.2	48	0.22	0.089
1286431	Soil		1.2	36.8	11.5	76	2.0	16.5	1.7	39	0.86	7.2	8.3	1.4	26	1.6	1.5	0.2	51	0.20	0.069
1286432	Soil		2.6	31.6	14.4	65	2.5	12.5	1.5	38	1.21	11.4	8.8	1.5	23	1.7	2.0	0.3	64	0.18	0.065
1286433	Soil		3.5	25.7	17.2	92	3.4	17.0	2.4	103	1.59	18.4	10.0	1.5	31	1.1	2.0	0.3	83	0.19	0.087
1286434	Soil		5.8	40.5	17.3	107	0.9	23.7	3.8	84	2.12	21.7	7.1	3.4	36	1.3	3.2	0.3	68	0.18	0.085
1286435	Soil		12.1	57.0	18.2	183	0.9	43.3	5.5	92	2.40	32.5	6.6	2.7	57	1.5	5.9	0.3	90	0.16	0.111
1286436	Soil		5.3	56.0	16.8	194	0.5	45.2	10.7	349	3.39	26.8	4.7	7.7	31	0.8	3.7	0.4	51	0.29	0.103
1286437	Soil		8.7	40.5	16.3	149	0.8	32.6	6.6	181	2.38	24.2	5.2	2.3	40	1.0	3.5	0.3	79	0.20	0.086
1286438	Soil		5.4	41.6	13.2	145	0.6	32.0	6.9	220	2.21	16.8	4.5	2.6	33	0.8	2.4	0.2	58	0.19	0.086
1286439	Soil		3.8	53.2	12.8	183	1.2	44.4	7.9	1099	2.13	15.9	5.8	1.8	45	2.9	2.8	0.3	61	0.44	0.099
1286440	Soil		7.3	52.5	15.5	219	0.9	46.5	8.8	331	2.37	24.8	5.2	1.9	61	2.8	4.0	0.3	70	0.50	0.127

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001410.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286171	Soil	4	15	0.14	1320	0.002	<1	1.04	0.012	0.07	<0.1	0.12	2.0	0.2	<0.05	3	2.2	<0.2
1286172	Soil	6	21	0.19	730	0.002	<1	1.11	0.005	0.10	<0.1	0.07	2.1	0.2	<0.05	4	1.1	<0.2
1286173	Soil	7	16	0.15	661	0.003	<1	0.93	0.011	0.08	<0.1	0.12	1.5	0.2	<0.05	3	1.3	<0.2
1286174	Soil	7	16	0.18	1098	0.002	2	0.95	0.006	0.10	<0.1	0.28	3.0	0.3	<0.05	2	2.8	<0.2
1286175	Soil	7	15	0.15	434	0.002	<1	0.85	0.011	0.08	<0.1	0.12	1.2	0.2	<0.05	2	0.7	<0.2
1286176	Soil	6	12	0.11	402	0.003	<1	0.76	0.015	0.07	<0.1	0.07	1.1	0.1	<0.05	2	0.8	<0.2
1286177	Soil	6	19	0.22	467	0.002	3	2.83	0.009	0.09	0.1	0.20	3.5	0.1	0.08	3	3.5	<0.2
1286178	Soil	5	22	0.23	959	<0.001	<1	1.10	0.005	0.09	<0.1	0.18	3.0	0.1	<0.05	3	1.8	<0.2
1286179	Soil	4	15	0.05	674	0.002	<1	1.07	0.010	0.09	<0.1	0.07	1.0	0.2	<0.05	4	1.4	<0.2
1286180	Soil	2	9	0.03	429	0.002	1	0.44	0.015	0.06	<0.1	0.05	0.5	0.1	<0.05	2	<0.5	<0.2
1286411	Soil	6	13	0.19	580	0.002	4	0.73	0.003	0.12	<0.1	0.47	3.5	0.2	<0.05	2	2.9	<0.2
1286412	Soil	5	13	0.24	773	0.003	3	0.69	0.009	0.10	<0.1	0.50	2.1	0.3	0.06	2	2.3	<0.2
1286413	Soil	7	18	0.12	1105	0.003	4	0.79	0.003	0.05	0.2	0.54	2.4	0.2	<0.05	3	4.5	<0.2
1286414	Soil	7	12	0.05	1482	0.002	3	0.34	0.002	0.05	0.1	0.98	2.6	0.3	<0.05	1	4.2	<0.2
1286415	Soil	7	18	0.10	1386	0.002	2	0.67	0.003	0.04	0.1	1.46	2.9	0.4	0.07	2	9.0	<0.2
1286416	Soil	6	17	0.11	1173	0.003	2	0.65	0.005	0.04	0.1	1.75	2.1	0.3	<0.05	2	4.7	<0.2
1286417	Soil	8	15	0.08	1950	0.003	3	0.45	0.002	0.07	<0.1	0.76	2.8	0.3	<0.05	2	3.0	<0.2
1286418	Soil	6	15	0.07	1383	0.003	2	0.59	0.005	0.05	0.1	0.87	1.9	0.3	<0.05	2	2.3	<0.2
1286419	Soil	8	15	0.09	1811	0.002	3	0.59	0.003	0.06	0.1	0.97	2.2	0.3	<0.05	2	2.9	<0.2
1286420	Soil	5	10	0.05	1117	0.002	3	0.47	0.009	0.04	0.1	0.67	1.6	0.2	<0.05	2	2.4	<0.2
1286431	Soil	8	19	0.09	996	0.002	3	0.72	0.005	0.06	0.1	1.15	2.3	0.3	<0.05	3	2.5	<0.2
1286432	Soil	9	18	0.10	783	0.003	2	0.71	0.005	0.05	0.1	1.09	1.9	0.3	<0.05	3	3.2	<0.2
1286433	Soil	7	17	0.08	805	0.002	3	0.80	0.003	0.08	0.1	1.90	2.0	0.5	<0.05	3	3.6	<0.2
1286434	Soil	12	20	0.16	1391	0.002	2	0.96	0.004	0.07	0.2	0.79	2.8	0.3	<0.05	3	2.2	<0.2
1286435	Soil	10	22	0.13	2011	0.003	3	0.74	0.003	0.08	0.2	0.75	3.3	0.4	<0.05	2	2.7	<0.2
1286436	Soil	24	22	0.38	1147	0.008	3	1.21	0.006	0.10	0.4	0.35	4.1	0.2	<0.05	4	1.6	<0.2
1286437	Soil	11	21	0.16	1578	0.003	3	0.92	0.004	0.08	0.2	0.65	2.5	0.3	<0.05	3	2.8	<0.2
1286438	Soil	13	19	0.19	1541	0.003	2	0.95	0.007	0.08	0.2	0.41	2.6	0.2	<0.05	3	2.2	<0.2
1286439	Soil	10	18	0.14	1656	0.004	3	0.91	0.008	0.06	0.2	0.57	3.2	0.2	<0.05	3	3.2	<0.2
1286440	Soil	9	19	0.16	2052	0.003	4	0.77	0.005	0.10	0.2	0.62	2.9	0.3	<0.05	3	3.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001410.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1286541	Soil		4.4	18.6	8.2	67	0.2	16.1	2.0	57	1.06	7.6	2.0	1.7	29	0.7	0.9	0.1	51	0.26	0.041
1286542	Soil		9.5	28.4	17.1	244	0.5	55.3	10.9	295	2.18	17.9	3.1	1.9	32	0.8	2.9	0.2	86	0.18	0.108
1286543	Soil		7.4	23.2	19.9	84	1.7	15.9	2.7	68	1.96	28.6	6.7	0.2	36	0.3	4.9	0.3	104	0.03	0.110
1286544	Soil		5.8	12.3	13.9	53	1.1	10.4	2.3	58	1.54	17.7	4.0	2.0	20	0.2	3.0	0.3	91	0.02	0.059
1286545	Soil		2.1	11.2	8.7	24	0.2	4.5	1.2	35	0.57	5.5	3.0	0.2	12	0.2	0.7	0.2	39	0.04	0.036
1286546	Soil		7.6	36.3	15.8	138	0.6	25.7	4.3	121	2.40	25.0	8.2	0.6	44	1.1	4.4	0.3	111	0.07	0.130
1286547	Soil		8.0	42.6	16.7	172	0.7	32.9	7.0	311	2.63	28.9	7.9	2.2	63	1.6	5.4	0.4	101	0.16	0.146
1286548	Soil		8.5	53.2	17.0	168	0.6	32.9	27.7	1416	3.00	27.7	8.9	2.8	55	1.5	5.4	0.3	105	0.14	0.155
1286549	Soil		4.8	26.0	11.2	69	1.7	15.2	4.8	250	1.74	13.0	7.3	0.9	33	0.9	2.4	0.2	67	0.11	0.119
1286550	Soil		7.2	23.3	13.4	94	0.8	17.8	5.0	238	2.01	17.2	6.3	1.3	43	0.9	2.9	0.3	85	0.21	0.116
1286681	Soil		5.7	56.5	17.2	180	0.7	46.3	13.7	717	2.93	21.2	5.6	3.5	44	1.2	2.8	0.3	65	0.49	0.095
1286682	Soil		5.0	46.9	18.0	148	0.4	33.8	10.5	252	2.83	19.0	5.5	5.1	26	0.7	2.6	0.3	58	0.21	0.085
1286683	Soil		3.8	30.3	13.7	102	0.5	24.9	9.5	323	2.27	13.5	4.3	2.5	27	0.4	1.6	0.2	47	0.27	0.081
1286684	Soil		1.1	17.2	15.8	64	0.7	29.2	3.9	93	1.29	6.8	3.9	0.4	19	0.3	0.4	0.1	15	0.14	0.067
1286685	Soil		2.4	30.2	19.6	145	0.9	63.6	16.9	878	2.17	13.6	3.9	1.1	73	0.9	0.8	0.3	32	0.52	0.119
1286686	Soil		1.7	23.3	18.3	28	1.4	11.6	1.7	47	1.20	7.6	5.1	0.7	95	0.4	0.7	0.2	23	0.19	0.185
1286687	Soil		0.7	8.0	7.1	22	1.6	8.5	2.4	40	0.63	3.0	4.8	0.2	22	0.1	0.2	<0.1	11	0.04	0.086
1286688	Soil		6.9	29.0	18.0	185	0.7	48.1	14.5	815	3.50	23.2	5.0	1.5	64	1.6	1.7	0.2	34	0.30	0.374
1286689	Soil		3.1	29.4	15.4	141	0.6	40.6	6.1	129	2.07	12.4	2.9	1.0	74	1.5	1.2	0.2	29	0.30	0.180
1286690	Soil		13.5	24.0	16.9	101	0.8	21.8	48.4	1292	3.74	23.3	2.8	1.3	48	0.6	1.6	0.2	35	0.07	0.625
1286691	Soil		3.8	27.6	17.2	73	1.5	16.8	4.7	101	2.23	15.9	3.3	0.5	29	0.3	1.4	0.2	38	0.04	0.147
1286692	Soil		4.3	22.9	16.7	94	1.1	36.1	4.5	102	2.11	16.7	2.5	0.3	51	0.5	2.1	0.2	38	0.37	0.175
1286693	Soil		2.6	10.8	10.3	53	0.2	9.3	2.8	51	1.31	11.6	<0.5	0.1	8	<0.1	1.0	0.2	34	0.02	0.043
1286694	Soil		4.0	30.3	17.9	81	0.8	16.4	4.6	70	2.77	18.2	0.9	0.7	19	0.2	1.8	0.2	42	0.02	0.077
1286695	Soil		0.8	5.5	3.8	17	0.3	3.8	1.3	25	0.48	3.7	<0.5	<0.1	6	0.1	0.4	<0.1	10	0.02	0.020
1286696	Soil		2.4	12.7	9.3	44	0.2	8.5	2.5	56	1.27	10.2	0.6	0.3	9	0.2	1.1	0.2	40	0.03	0.027
1286697	Soil		3.5	17.2	14.4	87	<0.1	15.8	4.4	74	2.30	21.2	0.8	0.7	9	0.2	1.8	0.3	43	0.01	0.049
1286698	Soil		0.9	5.6	4.7	20	<0.1	4.1	1.3	22	0.61	4.9	0.9	0.3	5	<0.1	0.4	<0.1	15	0.02	0.024
1286699	Soil		3.3	18.2	13.9	93	0.2	17.4	5.5	94	2.26	21.3	0.6	0.7	15	0.3	1.7	0.2	39	0.04	0.054
1286700	Soil		1.0	8.6	8.4	40	0.1	6.7	2.4	69	1.41	7.1	0.6	0.7	7	0.1	0.4	0.1	22	0.02	0.029

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001410.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286541	Soil	8	12	0.11	398	0.002	2	0.49	0.004	0.06	0.1	0.06	1.7	0.2	<0.05	2	1.1	<0.2
1286542	Soil	11	22	0.18	913	0.005	3	0.78	0.005	0.09	0.1	0.19	2.1	0.4	<0.05	3	1.8	<0.2
1286543	Soil	8	15	0.05	430	0.004	1	0.63	0.006	0.06	0.2	0.17	0.9	0.3	<0.05	4	2.5	<0.2
1286544	Soil	10	12	0.06	331	0.006	2	0.73	0.003	0.05	0.2	0.12	1.3	0.3	<0.05	4	1.5	<0.2
1286545	Soil	14	10	0.03	324	0.005	2	0.57	0.006	0.05	0.1	0.04	0.5	0.2	<0.05	4	0.5	<0.2
1286546	Soil	10	21	0.12	2083	0.004	4	0.92	0.004	0.09	0.3	0.29	1.2	0.4	<0.05	4	2.4	<0.2
1286547	Soil	11	20	0.14	1807	0.003	3	0.82	0.003	0.09	0.2	0.31	2.4	0.4	<0.05	3	2.3	<0.2
1286548	Soil	14	23	0.16	2072	0.004	3	1.01	0.003	0.09	0.2	0.23	2.5	0.4	<0.05	3	2.6	<0.2
1286549	Soil	8	17	0.11	1958	0.003	4	0.83	0.010	0.08	0.2	0.69	1.7	0.3	<0.05	3	1.9	<0.2
1286550	Soil	11	20	0.14	2254	0.004	3	0.86	0.005	0.09	0.2	0.27	1.8	0.3	0.05	3	2.1	<0.2
1286681	Soil	16	24	0.26	1445	0.003	3	1.28	0.006	0.12	0.2	0.38	3.8	0.2	<0.05	4	2.0	<0.2
1286682	Soil	20	24	0.29	781	0.004	3	1.28	0.006	0.11	0.3	0.25	3.2	0.2	<0.05	4	1.5	<0.2
1286683	Soil	12	18	0.23	787	0.003	2	1.13	0.010	0.11	0.2	0.22	2.5	0.2	<0.05	4	1.3	<0.2
1286684	Soil	2	13	0.06	344	0.002	3	0.56	0.016	0.05	<0.1	0.13	1.7	<0.1	<0.05	2	1.3	<0.2
1286685	Soil	5	17	0.13	1496	0.002	3	0.94	0.008	0.07	<0.1	0.20	3.2	0.1	<0.05	3	4.2	<0.2
1286686	Soil	4	12	0.07	2530	0.002	3	0.54	0.009	0.06	<0.1	0.26	2.2	0.2	<0.05	2	2.4	<0.2
1286687	Soil	1	8	0.03	574	0.002	2	0.37	0.018	0.04	<0.1	0.14	1.1	0.1	<0.05	1	1.4	<0.2
1286688	Soil	5	17	0.17	1594	0.004	3	0.91	0.007	0.09	<0.1	0.16	3.1	0.2	<0.05	3	2.5	<0.2
1286689	Soil	4	14	0.16	1053	0.002	3	0.73	0.009	0.07	<0.1	0.10	2.3	0.1	0.12	2	3.2	<0.2
1286690	Soil	4	17	0.10	883	0.003	2	1.00	0.008	0.06	<0.1	0.08	2.6	0.2	0.07	3	2.1	<0.2
1286691	Soil	5	14	0.08	456	0.003	1	0.78	0.008	0.05	0.3	0.13	1.0	0.2	0.07	3	1.9	<0.2
1286692	Soil	5	13	0.09	668	0.002	2	0.67	0.010	0.06	<0.1	0.11	1.0	0.2	0.09	3	3.6	<0.2
1286693	Soil	6	7	0.03	125	0.004	1	0.47	0.007	0.03	<0.1	0.01	0.4	<0.1	<0.05	3	<0.5	<0.2
1286694	Soil	6	13	0.08	304	0.004	2	0.64	0.007	0.06	0.1	0.04	1.6	0.2	0.06	3	1.7	<0.2
1286695	Soil	2	3	0.01	66	0.005	1	0.23	0.025	0.03	<0.1	0.03	0.3	<0.1	<0.05	1	<0.5	<0.2
1286696	Soil	9	8	0.03	210	0.006	<1	0.50	0.003	0.04	0.1	0.01	0.6	0.1	<0.05	4	<0.5	<0.2
1286697	Soil	7	9	0.05	116	0.003	1	0.53	0.004	0.04	<0.1	0.02	1.3	0.1	<0.05	4	<0.5	<0.2
1286698	Soil	3	4	0.02	98	0.005	<1	0.34	0.020	0.03	<0.1	0.02	0.4	<0.1	<0.05	2	<0.5	<0.2
1286699	Soil	6	9	0.06	435	0.003	2	0.59	0.007	0.05	<0.1	0.02	1.3	0.1	<0.05	3	0.5	<0.2
1286700	Soil	2	8	0.06	153	0.003	1	0.61	0.016	0.06	<0.1	0.03	0.9	<0.1	<0.05	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001410.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1287501	Soil		2.7	24.2	12.4	76	0.1	14.3	5.4	221	3.93	13.6	0.5	0.2	12	0.1	1.1	0.3	44	0.05	0.112
1287502	Soil		1.8	17.7	10.7	67	<0.1	12.3	9.1	448	3.25	8.9	<0.5	0.2	8	0.1	0.8	0.2	35	0.03	0.085
1287503	Soil		2.2	21.3	15.1	99	0.1	18.2	12.9	494	3.53	15.9	0.8	1.1	9	0.2	1.0	0.3	37	0.02	0.064
1287504	Soil		2.0	28.1	25.6	102	0.3	36.1	16.0	415	3.80	17.5	1.0	1.1	12	0.1	0.9	0.3	31	0.02	0.076
1287505	Soil		1.3	17.8	11.2	55	0.5	15.7	6.2	181	2.20	8.1	0.9	0.6	7	0.1	0.5	0.2	22	0.02	0.048
1287506	Soil		2.3	27.4	26.0	94	0.3	27.5	7.4	239	4.14	15.0	1.9	2.3	17	0.1	0.8	0.3	29	0.02	0.068
1287507	Soil		2.2	25.8	22.8	103	0.3	29.3	10.4	283	3.56	13.8	<0.5	1.3	15	0.1	0.7	0.3	27	0.03	0.083
1287508	Soil		2.4	26.9	25.7	101	0.2	29.6	12.1	335	3.80	15.1	1.0	1.5	15	0.1	0.8	0.3	29	0.02	0.082
1287509	Soil		2.0	25.9	21.6	93	0.3	30.2	8.5	234	3.40	12.8	0.8	1.4	13	0.2	0.8	0.3	25	0.03	0.092
1287510	Soil		2.0	35.2	13.9	57	0.2	13.1	9.2	813	1.86	10.5	1.2	0.3	11	0.3	0.8	0.2	28	0.04	0.115
1287511	Soil		0.4	4.9	4.3	11	0.3	2.7	0.8	24	0.41	1.7	<0.5	<0.1	4	<0.1	0.2	<0.1	8	0.02	0.042
1287512	Soil		1.7	25.2	15.6	40	0.2	8.2	3.2	151	1.99	7.8	0.9	0.2	6	<0.1	0.6	0.2	39	0.03	0.094
1287513	Soil		1.2	14.0	9.3	57	0.2	16.3	6.5	123	1.65	8.0	0.7	0.3	5	<0.1	0.5	0.1	18	0.03	0.053
1287514	Soil		2.3	21.8	16.4	93	0.2	26.0	10.1	226	2.97	14.4	0.9	0.4	9	<0.1	0.9	0.2	35	0.02	0.077
1287515	Soil		3.1	25.4	18.7	110	<0.1	32.4	12.8	352	3.77	16.7	0.6	0.8	10	0.2	1.1	0.3	37	0.03	0.083
1287516	Soil		0.2	2.3	1.6	5	<0.1	1.2	0.4	14	0.17	<0.5	0.6	<0.1	6	<0.1	<0.1	<0.1	4	0.03	0.023
1287517	Soil		2.2	22.2	23.7	94	0.2	27.8	8.6	248	4.77	16.4	1.0	1.4	14	<0.1	0.8	0.3	38	0.01	0.096
1287518	Soil		2.2	20.5	15.3	75	0.1	12.7	6.3	233	3.58	11.9	<0.5	0.8	7	0.1	0.7	0.3	39	0.01	0.077
1287519	Soil		1.8	21.3	14.3	83	0.1	21.3	9.4	312	3.21	15.0	1.5	0.5	8	0.2	0.9	0.2	35	0.02	0.074
1287520	Soil		2.3	22.1	18.0	104	0.4	19.1	13.8	638	3.48	16.6	1.2	0.2	12	1.2	1.1	0.3	44	0.05	0.100
1287521	Soil		0.3	4.0	2.0	8	0.1	2.1	0.7	19	0.34	1.2	<0.5	<0.1	4	<0.1	0.1	<0.1	7	0.02	0.032
1287522	Soil		2.0	14.7	10.5	37	0.1	7.3	2.7	76	1.56	9.0	0.9	0.3	7	<0.1	0.6	0.2	38	0.03	0.074
1287523	Soil		2.0	19.0	16.4	70	<0.1	18.4	7.1	342	4.75	15.8	0.7	0.8	7	0.1	0.9	0.2	39	0.02	0.110
1287524	Soil		1.5	16.1	9.6	41	<0.1	7.8	4.1	169	1.81	10.4	<0.5	0.2	9	<0.1	0.7	0.2	35	0.03	0.082
1287525	Soil		2.3	17.6	14.6	74	<0.1	12.1	5.4	488	3.86	14.6	<0.5	0.4	7	<0.1	1.0	0.3	53	0.01	0.100
1287526	Soil		1.6	14.7	9.8	61	<0.1	6.6	3.3	186	2.36	9.6	0.7	0.1	5	<0.1	0.7	0.2	40	0.01	0.054
1287527	Soil		1.8	19.1	18.1	94	0.1	28.5	13.3	1238	5.14	14.7	<0.5	1.7	10	0.2	0.7	0.3	32	0.03	0.116
1287528	Soil		2.6	19.6	20.6	85	0.1	17.1	17.6	744	3.98	12.3	0.8	0.6	10	0.2	0.9	0.3	40	0.03	0.110
1287529	Soil		2.4	17.7	18.1	74	0.2	19.2	8.2	393	4.22	13.8	0.5	0.3	8	0.2	1.1	0.3	45	0.03	0.101
1287530	Soil		1.9	13.9	16.4	48	<0.1	7.5	3.0	292	5.88	10.4	1.0	0.3	7	<0.1	0.7	0.3	50	0.02	0.130

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001410.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287501	Soil	5	24	0.10	129	0.005	1	1.06	0.007	0.04	<0.1	0.05	0.5	0.1	0.05	5	<0.5	<0.2
1287502	Soil	4	21	0.14	93	0.007	1	1.04	0.012	0.04	<0.1	0.04	0.6	<0.1	<0.05	5	<0.5	<0.2
1287503	Soil	3	20	0.15	147	0.004	2	1.03	0.008	0.05	<0.1	0.04	1.8	0.1	<0.05	5	<0.5	<0.2
1287504	Soil	3	27	0.41	128	0.004	1	1.34	0.006	0.07	<0.1	0.04	1.7	0.1	<0.05	4	0.5	<0.2
1287505	Soil	3	15	0.17	213	0.004	<1	0.96	0.014	0.04	<0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
1287506	Soil	3	29	0.36	101	0.001	<1	1.52	0.004	0.07	<0.1	0.05	2.0	0.2	<0.05	5	<0.5	<0.2
1287507	Soil	2	24	0.35	112	0.002	2	1.19	0.005	0.07	<0.1	0.06	1.7	0.2	<0.05	4	<0.5	<0.2
1287508	Soil	3	27	0.37	125	0.002	1	1.33	0.004	0.07	<0.1	0.04	1.9	0.1	<0.05	5	<0.5	<0.2
1287509	Soil	2	27	0.34	109	0.003	1	1.21	0.006	0.07	<0.1	0.06	1.7	0.1	<0.05	4	<0.5	<0.2
1287510	Soil	5	11	0.08	161	0.005	1	0.92	0.013	0.04	<0.1	0.03	0.4	0.1	<0.05	4	<0.5	<0.2
1287511	Soil	<1	5	0.02	18	0.003	<1	0.23	0.021	0.02	<0.1	0.03	0.2	<0.1	<0.05	1	<0.5	<0.2
1287512	Soil	3	14	0.04	43	0.003	1	0.67	0.011	0.04	<0.1	0.04	0.4	<0.1	<0.05	4	<0.5	<0.2
1287513	Soil	2	10	0.11	44	0.003	1	0.56	0.011	0.03	<0.1	0.04	0.9	<0.1	<0.05	2	<0.5	<0.2
1287514	Soil	5	19	0.19	70	0.004	<1	0.91	0.006	0.05	<0.1	0.04	1.0	0.2	<0.05	4	<0.5	<0.2
1287515	Soil	4	27	0.36	62	0.006	<1	1.13	0.005	0.05	<0.1	0.03	1.6	0.1	<0.05	4	0.5	<0.2
1287516	Soil	<1	2	0.01	18	0.004	<1	0.16	0.027	0.02	<0.1	0.02	<0.1	<0.1	<0.05	<1	<0.5	<0.2
1287517	Soil	3	26	0.34	72	0.002	1	1.41	0.003	0.04	<0.1	0.02	1.9	0.1	<0.05	5	<0.5	<0.2
1287518	Soil	4	15	0.11	106	0.003	<1	0.98	0.007	0.04	<0.1	0.01	1.2	<0.1	<0.05	5	<0.5	<0.2
1287519	Soil	5	17	0.15	75	0.004	1	0.83	0.006	0.05	<0.1	0.03	1.1	0.1	<0.05	4	<0.5	<0.2
1287520	Soil	5	21	0.11	192	0.005	2	0.79	0.006	0.08	<0.1	0.04	0.7	0.1	<0.05	5	<0.5	<0.2
1287521	Soil	<1	3	0.01	22	0.004	<1	0.19	0.023	0.02	<0.1	0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2
1287522	Soil	6	12	0.05	93	0.004	1	0.69	0.007	0.04	0.1	0.02	0.3	0.1	<0.05	4	<0.5	<0.2
1287523	Soil	5	27	0.25	80	0.006	<1	1.27	0.005	0.04	<0.1	0.03	0.9	0.1	<0.05	5	0.6	<0.2
1287524	Soil	5	11	0.05	154	0.004	<1	0.91	0.012	0.04	<0.1	0.02	0.4	0.1	<0.05	4	<0.5	<0.2
1287525	Soil	5	21	0.12	100	0.006	1	1.08	0.003	0.05	<0.1	0.02	0.8	0.2	<0.05	6	0.7	<0.2
1287526	Soil	3	12	0.06	60	0.005	1	0.64	0.008	0.05	<0.1	0.01	0.5	0.1	<0.05	5	<0.5	<0.2
1287527	Soil	4	35	0.30	98	0.004	<1	1.64	0.005	0.04	<0.1	0.04	1.5	0.1	<0.05	5	0.7	<0.2
1287528	Soil	5	25	0.14	164	0.005	<1	1.21	0.005	0.06	<0.1	0.02	0.7	0.1	<0.05	6	0.8	<0.2
1287529	Soil	5	25	0.16	79	0.008	1	0.92	0.004	0.06	<0.1	0.04	0.8	0.1	<0.05	5	0.6	<0.2
1287530	Soil	4	26	0.07	78	0.006	1	1.10	0.007	0.04	<0.1	0.04	0.5	<0.1	<0.05	8	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001410.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1287531	Soil		2.6	25.7	27.8	150	<0.1	45.7	29.0	984	4.32	19.6	0.9	0.9	9	0.2	1.3	0.3	31	0.02	0.091
1287532	Soil		1.1	13.5	9.0	34	<0.1	6.5	4.2	271	1.76	6.4	0.7	0.2	7	0.1	0.5	0.1	25	0.03	0.095
1287533	Soil		2.2	23.1	24.2	118	0.2	18.1	31.7	2305	3.84	18.7	<0.5	0.9	11	0.5	0.8	0.3	41	0.04	0.135
1287534	Soil		0.7	6.5	5.8	28	0.1	5.6	2.5	84	1.09	5.2	<0.5	0.2	5	<0.1	0.3	<0.1	15	0.03	0.042
1287535	Soil		1.7	25.0	17.6	132	0.3	44.1	20.8	509	5.27	29.3	<0.5	1.7	6	0.1	1.1	0.3	36	0.01	0.072
1287536	Soil		1.9	20.5	17.5	116	<0.1	28.5	15.6	432	4.40	21.0	1.3	2.1	7	0.1	0.8	0.3	40	0.02	0.073
1287537	Soil		1.7	12.4	12.0	52	<0.1	7.1	5.2	199	1.97	10.3	<0.5	0.2	6	0.1	0.5	0.2	24	0.02	0.051
1287538	Soil		1.8	56.6	13.9	142	0.5	36.2	42.0	1679	1.73	7.5	<0.5	0.2	31	7.3	0.8	0.2	22	0.17	0.178
1287539	Soil		3.3	19.4	16.4	80	0.3	14.0	4.6	135	4.51	18.5	0.6	2.4	8	0.2	1.6	0.3	58	0.02	0.058
1287540	Soil		3.1	30.6	23.0	164	0.1	23.7	10.5	362	4.26	21.4	1.1	1.5	19	0.4	1.3	0.3	42	0.04	0.109

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

CERTIFICATE OF ANALYSIS WHI11001410.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287531	Soil	3	21	0.20	70	0.003	1	0.90	0.004	0.05	<0.1	0.03	1.6	0.2	<0.05	3	<0.5	<0.2
1287532	Soil	3	12	0.04	68	0.005	<1	0.59	0.015	0.04	<0.1	0.02	0.2	<0.1	<0.05	3	<0.5	<0.2
1287533	Soil	5	23	0.10	267	0.004	1	1.01	0.007	0.07	<0.1	0.03	1.0	0.1	<0.05	4	0.8	<0.2
1287534	Soil	2	6	0.04	61	0.006	1	0.54	0.021	0.04	<0.1	0.02	0.4	<0.1	<0.05	2	<0.5	<0.2
1287535	Soil	2	24	0.14	1103	0.002	<1	0.98	0.002	0.05	<0.1	0.03	3.2	0.1	<0.05	3	<0.5	<0.2
1287536	Soil	3	30	0.30	200	0.002	2	1.35	0.003	0.07	<0.1	0.02	2.3	0.1	<0.05	5	<0.5	<0.2
1287537	Soil	3	11	0.05	90	0.005	1	0.51	0.010	0.05	<0.1	0.02	0.5	<0.1	<0.05	3	<0.5	<0.2
1287538	Soil	6	19	0.05	384	0.005	2	0.65	0.008	0.07	<0.1	0.02	0.5	<0.1	<0.05	2	0.7	<0.2
1287539	Soil	7	22	0.11	95	0.013	<1	1.03	0.003	0.05	0.1	0.03	1.5	0.2	<0.05	6	0.7	<0.2
1287540	Soil	3	24	0.22	203	0.003	1	1.24	0.005	0.08	<0.1	0.02	1.7	0.2	<0.05	5	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

QUALITY CONTROL REPORT WHI11001410.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1284121	Soil		2.1	22.5	16.0	84	0.1	20.4	10.7	667	3.93	15.2	<0.5	0.3	8	<0.1	1.4	0.3	37	0.03	0.133
REP 1284121	QC		2.4	23.2	16.5	85	0.2	20.5	10.4	683	3.86	14.7	<0.5	0.3	9	<0.1	1.2	0.3	39	0.03	0.137
1284138	Soil		0.3	3.3	1.6	5	0.1	1.3	0.6	16	0.32	<0.5	<0.5	<0.1	8	<0.1	0.2	<0.1	7	0.04	0.037
REP 1284138	QC		0.4	3.5	1.5	6	0.1	1.6	0.8	17	0.33	<0.5	<0.5	<0.1	10	<0.1	0.1	<0.1	8	0.05	0.039
1284152	Soil		1.8	15.7	9.6	52	0.3	10.8	3.1	254	2.64	9.7	2.3	0.3	13	0.1	1.0	0.3	45	0.05	0.128
REP 1284152	QC		1.9	17.1	10.5	51	0.2	10.7	3.2	269	2.68	9.9	<0.5	0.3	14	0.2	1.0	0.2	45	0.05	0.126
1286157	Soil		10.1	15.8	15.7	91	0.9	14.6	3.2	57	2.34	22.7	1.8	0.3	32	0.3	3.6	0.2	86	0.02	0.086
REP 1286157	QC		9.6	15.3	16.4	90	0.9	14.3	3.4	56	2.36	23.0	1.6	0.3	32	0.3	3.5	0.2	87	0.02	0.085
1286414	Soil		15.4	55.7	17.1	199	0.7	42.0	6.3	155	2.21	50.2	3.8	2.2	57	1.9	9.0	0.2	74	0.25	0.097
REP 1286414	QC		15.2	55.0	16.8	201	0.7	42.7	6.2	159	2.25	51.2	3.6	2.1	57	2.1	8.8	0.2	74	0.25	0.096
1286542	Soil		9.5	28.4	17.1	244	0.5	55.3	10.9	295	2.18	17.9	3.1	1.9	32	0.8	2.9	0.2	86	0.18	0.108
REP 1286542	QC		8.8	28.5	16.9	239	0.5	54.3	10.8	296	2.15	17.2	4.2	1.9	30	0.7	2.9	0.2	83	0.17	0.102
1286694	Soil		4.0	30.3	17.9	81	0.8	16.4	4.6	70	2.77	18.2	0.9	0.7	19	0.2	1.8	0.2	42	0.02	0.077
REP 1286694	QC		3.8	30.8	17.1	82	0.8	16.6	4.7	71	2.75	19.3	0.8	0.7	19	0.2	1.8	0.2	43	0.03	0.079
1287519	Soil		1.8	21.3	14.3	83	0.1	21.3	9.4	312	3.21	15.0	1.5	0.5	8	0.2	0.9	0.2	35	0.02	0.074
REP 1287519	QC		1.9	22.3	15.3	87	0.1	21.4	9.3	323	3.19	15.4	0.9	0.5	8	0.1	0.8	0.3	35	0.02	0.076
1287530	Soil		1.9	13.9	16.4	48	<0.1	7.5	3.0	292	5.88	10.4	1.0	0.3	7	<0.1	0.7	0.3	50	0.02	0.130
REP 1287530	QC		2.0	14.2	16.2	49	<0.1	7.6	3.1	292	5.92	10.8	0.5	0.3	7	<0.1	0.7	0.3	51	0.02	0.130
Reference Materials																					
STD DS8	Standard		13.2	108.9	117.6	304	1.8	37.0	7.4	590	2.37	24.9	116.4	6.8	63	2.4	5.1	6.5	41	0.67	0.077
STD DS8	Standard		12.1	110.3	116.7	313	1.8	36.8	7.5	607	2.40	25.7	109.4	6.4	67	2.5	5.3	6.5	40	0.69	0.078
STD DS8	Standard		14.5	105.2	126.8	292	1.7	38.1	7.3	620	2.42	22.9	116.0	7.0	75	2.1	5.3	6.6	42	0.73	0.073
STD DS8	Standard		14.0	108.5	134.1	321	1.9	38.4	7.5	662	2.56	27.4	115.5	7.0	79	2.3	6.0	6.7	43	0.76	0.080
STD DS8	Standard		12.3	103.1	115.3	283	1.6	35.7	7.1	558	2.22	21.8	100.9	6.4	65	2.1	5.3	6.4	40	0.62	0.072
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

QUALITY CONTROL REPORT WHI11001410.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1284121	Soil	4	22	0.12	103	0.005	1	0.98	0.008	0.06	<0.1	0.07	0.8	0.1	0.06	5	<0.5	<0.2
REP 1284121	QC	4	22	0.13	109	0.006	2	1.00	0.008	0.07	<0.1	0.04	0.8	0.1	0.06	5	0.5	<0.2
1284138	Soil	<1	3	0.02	63	0.004	<1	0.22	0.030	0.03	<0.1	0.03	0.2	<0.1	<0.05	1	<0.5	<0.2
REP 1284138	QC	<1	3	0.02	69	0.004	<1	0.25	0.036	0.03	<0.1	0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2
1284152	Soil	5	17	0.06	182	0.005	2	0.86	0.008	0.07	<0.1	0.08	0.5	0.1	0.09	4	<0.5	0.2
REP 1284152	QC	5	19	0.06	183	0.005	1	0.86	0.010	0.08	0.1	0.10	0.5	0.1	0.10	4	1.3	<0.2
1286157	Soil	6	14	0.05	214	0.005	<1	0.52	0.012	0.07	<0.1	0.04	0.6	0.2	<0.05	3	2.8	<0.2
REP 1286157	QC	6	13	0.05	206	0.005	<1	0.51	0.012	0.07	<0.1	0.03	0.7	0.1	<0.05	3	1.6	<0.2
1286414	Soil	7	12	0.05	1482	0.002	3	0.34	0.002	0.05	0.1	0.98	2.6	0.3	<0.05	1	4.2	<0.2
REP 1286414	QC	7	12	0.05	1495	0.002	4	0.35	0.002	0.05	0.1	0.94	2.6	0.3	<0.05	1	3.7	<0.2
1286542	Soil	11	22	0.18	913	0.005	3	0.78	0.005	0.09	0.1	0.19	2.1	0.4	<0.05	3	1.8	<0.2
REP 1286542	QC	11	21	0.17	873	0.004	3	0.77	0.005	0.09	0.1	0.17	2.2	0.4	<0.05	3	1.6	<0.2
1286694	Soil	6	13	0.08	304	0.004	2	0.64	0.007	0.06	0.1	0.04	1.6	0.2	0.06	3	1.7	<0.2
REP 1286694	QC	6	13	0.08	319	0.003	2	0.66	0.007	0.06	<0.1	0.05	1.7	0.2	0.05	3	2.0	<0.2
1287519	Soil	5	17	0.15	75	0.004	1	0.83	0.006	0.05	<0.1	0.03	1.1	0.1	<0.05	4	<0.5	<0.2
REP 1287519	QC	5	18	0.16	79	0.005	<1	0.83	0.006	0.05	<0.1	0.03	1.1	0.1	<0.05	4	<0.5	<0.2
1287530	Soil	4	26	0.07	78	0.006	1	1.10	0.007	0.04	<0.1	0.04	0.5	<0.1	<0.05	8	<0.5	<0.2
REP 1287530	QC	4	26	0.07	79	0.007	<1	1.14	0.007	0.04	<0.1	0.03	0.6	<0.1	<0.05	7	0.6	<0.2
Reference Materials																		
STD DS8	Standard	16	110	0.59	280	0.108	2	0.90	0.101	0.42	2.9	0.19	3.0	5.2	<0.05	5	4.7	4.4
STD DS8	Standard	14	110	0.60	279	0.115	3	0.89	0.099	0.43	2.7	0.23	2.4	5.5	0.14	5	5.0	5.3
STD DS8	Standard	17	116	0.60	282	0.122	2	0.96	0.107	0.42	3.0	0.20	2.8	5.5	0.16	4	5.3	4.9
STD DS8	Standard	17	122	0.64	297	0.125	2	1.02	0.114	0.45	3.3	0.21	2.7	5.5	0.13	5	5.3	5.8
STD DS8	Standard	14	114	0.57	247	0.108	2	0.85	0.096	0.39	2.7	0.17	2.4	4.8	0.11	4	5.2	4.3
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

QUALITY CONTROL REPORT WHI11001410.1

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 03, 2011

QUALITY CONTROL REPORT WHI11001410.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 09, 2011
Report Date: November 08, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001423.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #25
P.O. Number
Number of Samples: 304

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	304	Sieve soil to 230 mesh			WHI
RJSV	304	Saving all or part of Soil Reject			WHI
1DX2	300	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287581	Soil		4.1	5.7	4.8	39	0.3	9.0	1.1	28	0.39	12.4	2.0	<0.1	6	0.5	5.5	<0.1	14	0.03	0.046	<1
1287582	Soil		22.6	24.0	15.9	189	<0.1	49.4	5.5	91	1.78	64.0	1.6	0.2	12	1.1	31.9	0.1	72	0.05	0.086	5
1287583	Soil		4.6	7.5	3.7	44	0.1	11.9	1.4	54	0.47	18.7	1.2	<0.1	10	1.1	4.7	<0.1	16	0.08	0.053	1
1287584	Soil		34.3	26.1	12.1	212	<0.1	60.9	7.9	237	2.29	186.3	2.3	0.2	10	1.6	41.0	<0.1	102	0.10	0.096	3
1287585	Soil		7.9	43.0	7.8	109	<0.1	47.3	13.9	373	4.00	620.6	13.0	0.5	19	0.6	68.8	<0.1	150	0.23	0.098	3
1287586	Soil		0.9	41.9	5.5	52	0.1	26.2	12.7	332	2.64	253.0	15.5	0.2	44	0.3	28.7	<0.1	15	0.55	0.057	3
1287587	Soil		5.0	90.8	16.3	240	1.3	115.2	13.2	419	3.20	63.3	6.1	4.0	57	1.3	34.8	0.2	53	0.62	0.178	5
1287588	Soil		9.7	24.7	9.4	178	0.2	41.2	4.7	85	1.34	23.1	1.6	0.2	14	0.4	10.8	<0.1	63	0.17	0.074	3
1287589	Soil		8.0	61.3	14.9	271	0.6	90.4	9.4	154	2.16	39.8	2.1	0.7	35	1.6	13.3	0.2	49	0.30	0.114	4
1287590	Soil		8.8	90.3	49.8	388	1.8	114.6	11.5	220	2.81	56.0	4.4	0.7	30	1.5	37.3	0.2	61	0.27	0.122	4
1287591	Soil		2.3	6.1	3.5	37	<0.1	8.7	1.2	18	0.46	4.9	0.5	<0.1	6	0.1	1.8	<0.1	20	0.02	0.053	1
1287592	Soil		3.6	23.2	13.3	119	0.4	28.0	4.2	108	1.17	9.6	1.8	0.1	33	0.5	4.6	<0.1	33	0.09	0.102	2
1287593	Soil		12.6	89.2	48.4	358	1.7	125.2	15.4	436	4.19	31.3	1.4	1.7	78	3.6	11.6	0.2	48	2.15	0.106	4
1287594	Soil		4.3	127.0	46.7	143	1.5	131.8	18.8	340	4.23	21.6	3.3	2.6	19	0.6	9.1	0.2	23	0.18	0.052	4
1287595	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287596	Soil		10.9	98.6	32.5	238	2.0	116.3	26.6	503	7.20	13.4	8.5	0.8	19	<0.1	6.4	0.4	23	0.22	0.074	7
1287597	Soil		13.5	129.3	79.3	309	1.8	111.8	14.6	296	3.53	90.3	50.7	1.1	800	2.3	63.4	0.4	80	0.99	0.593	7
1287598	Soil		18.9	54.6	118.3	225	1.7	55.3	5.8	95	2.37	33.0	3.6	0.1	310	0.9	9.4	0.7	149	0.04	0.309	6
1287599	Soil		9.5	94.0	50.6	318	1.3	160.6	23.6	428	4.78	32.7	6.5	0.8	34	0.3	10.4	0.3	23	0.23	0.074	3
1287600	Soil		9.4	38.5	47.9	61	1.2	29.0	3.0	39	1.44	19.0	3.2	0.3	262	0.5	6.2	0.2	61	0.28	0.257	2
1287701	Soil		3.5	22.3	13.0	145	0.2	27.0	7.2	133	2.19	19.7	1.3	1.4	26	0.7	1.9	0.2	30	0.14	0.088	6
1287702	Soil		3.2	22.2	14.1	82	0.1	22.8	5.2	91	1.80	17.9	1.7	0.9	9	0.3	1.8	0.2	34	0.03	0.054	5
1287703	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287704	Soil		3.3	26.2	16.6	135	0.2	30.1	10.0	214	2.51	24.7	1.4	1.2	12	0.3	2.1	0.2	28	0.05	0.068	5
1287705	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287706	Soil		7.1	9.3	5.8	75	0.2	17.0	1.8	43	0.65	11.7	<0.5	0.1	11	1.2	6.4	<0.1	26	0.11	0.074	3
1287707	Soil		7.9	12.9	6.4	70	0.1	20.4	3.3	76	0.70	11.4	<0.5	0.2	23	0.7	6.9	<0.1	26	0.47	0.088	3
1287708	Soil		23.6	27.9	6.9	136	0.2	57.2	4.0	87	1.01	20.6	2.1	0.4	47	1.5	17.9	<0.1	38	1.28	0.056	3
1287709	Soil		21.0	37.7	15.3	292	0.3	69.4	8.2	190	2.16	61.5	4.5	0.7	32	1.6	40.7	<0.1	73	0.60	0.068	5
1287710	Soil		54.8	35.8	16.5	345	0.2	126.3	6.7	117	1.99	27.3	2.3	0.8	53	2.6	14.8	0.1	52	1.27	0.100	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287581	Soil		5	0.01	83	0.002	<1	0.14	0.014	0.02	<0.1	0.02	0.3	<0.1	<0.05	<1	<0.5	<0.2
1287582	Soil		14	0.05	191	0.003	2	0.38	0.006	0.04	0.1	0.02	0.5	0.3	<0.05	1	1.3	<0.2
1287583	Soil		6	0.02	115	0.003	<1	0.25	0.019	0.02	<0.1	0.03	0.2	<0.1	<0.05	1	0.8	<0.2
1287584	Soil		17	0.04	212	0.004	1	0.36	0.005	0.06	<0.1	0.02	1.7	0.3	<0.05	1	1.4	<0.2
1287585	Soil		28	0.08	485	0.003	2	0.62	0.007	0.05	<0.1	0.02	6.3	0.1	<0.05	1	0.9	<0.2
1287586	Soil		14	0.10	294	0.002	3	0.47	0.024	0.05	<0.1	0.06	9.4	<0.1	<0.05	<1	0.7	<0.2
1287587	Soil		25	0.10	130	0.001	2	0.19	0.001	0.05	<0.1	0.39	6.5	0.2	<0.05	<1	4.0	<0.2
1287588	Soil		14	0.04	113	0.003	1	0.36	0.013	0.02	<0.1	0.06	0.8	0.2	<0.05	1	1.6	<0.2
1287589	Soil		18	0.04	291	0.002	2	0.24	0.004	0.03	<0.1	0.14	3.3	0.1	<0.05	<1	3.4	<0.2
1287590	Soil		23	0.06	735	0.002	2	0.37	0.003	0.04	<0.1	0.43	5.1	0.2	<0.05	<1	5.5	<0.2
1287591	Soil		3	0.01	51	0.002	<1	0.23	0.016	0.02	<0.1	0.02	0.2	<0.1	<0.05	1	0.8	<0.2
1287592	Soil		9	0.03	196	0.004	1	0.30	0.015	0.03	<0.1	0.04	0.4	<0.1	<0.05	1	1.0	<0.2
1287593	Soil		22	0.94	540	0.001	4	0.22	0.003	0.05	<0.1	0.31	6.0	0.2	<0.05	<1	4.8	<0.2
1287594	Soil		17	0.06	308	0.001	1	0.18	0.001	0.03	<0.1	0.27	8.5	0.1	<0.05	<1	3.4	<0.2
1287595	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287596	Soil		16	0.09	438	0.004	3	0.44	0.005	0.07	<0.1	0.18	7.7	0.2	<0.05	1	2.3	<0.2
1287597	Soil		23	0.04	1577	0.003	5	0.48	0.004	0.10	<0.1	0.39	4.5	0.2	0.09	1	4.7	0.4
1287598	Soil		20	0.01	535	0.003	3	0.44	0.005	0.09	0.1	0.06	0.5	0.4	0.19	3	2.6	0.3
1287599	Soil		8	0.05	708	0.002	2	0.29	0.008	0.04	<0.1	0.24	5.2	0.2	<0.05	<1	1.4	<0.2
1287600	Soil		16	0.01	578	0.003	2	0.29	0.007	0.07	<0.1	0.07	0.7	0.4	0.22	1	2.9	<0.2
1287701	Soil		13	0.13	1036	0.002	1	0.53	0.005	0.04	<0.1	0.05	1.9	<0.1	<0.05	2	0.8	<0.2
1287702	Soil		14	0.08	402	0.002	1	0.62	0.008	0.07	<0.1	0.05	1.7	0.2	<0.05	2	0.9	<0.2
1287703	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287704	Soil		14	0.12	371	0.002	2	0.48	0.005	0.05	<0.1	0.06	2.0	0.1	<0.05	2	0.8	<0.2
1287705	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287706	Soil		8	0.04	255	0.002	<1	0.33	0.017	0.03	<0.1	0.05	0.4	0.1	<0.05	1	0.5	<0.2
1287707	Soil		7	0.06	207	0.006	2	0.53	0.022	0.02	<0.1	0.05	0.6	0.1	<0.05	2	<0.5	<0.2
1287708	Soil		11	0.17	207	0.003	2	0.42	0.015	0.02	<0.1	0.14	1.7	0.3	<0.05	1	1.7	<0.2
1287709	Soil		18	0.13	242	0.004	1	0.55	0.010	0.04	0.1	0.10	3.0	0.3	<0.05	1	1.6	<0.2
1287710	Soil		14	0.30	215	0.004	3	0.41	0.007	0.03	0.2	0.19	3.0	0.5	<0.05	1	2.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287711	Soil	59.9	45.4	20.9	251	0.2	135.9	9.3	211	2.73	46.2	1.3	0.6	28	2.0	24.4	0.1	80	0.81	0.068	4
1287712	Soil	26.1	22.2	14.2	216	<0.1	52.5	6.9	106	1.82	57.0	<0.5	0.2	6	1.0	35.6	0.1	129	0.06	0.052	2
1287713	Soil	15.8	15.6	9.1	129	<0.1	39.2	4.3	65	1.21	39.1	1.5	0.1	5	0.6	18.4	<0.1	83	0.03	0.041	2
1287714	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287715	Soil	13.3	13.7	5.7	108	<0.1	27.8	3.6	139	0.94	41.1	1.8	0.1	12	1.2	20.7	<0.1	45	0.14	0.087	1
1287716	Soil	11.9	13.7	9.6	204	<0.1	31.6	5.0	202	2.10	51.5	3.0	0.1	12	1.4	80.3	<0.1	85	0.15	0.102	2
1287717	Soil	1.4	17.5	4.4	45	<0.1	12.7	4.9	120	1.36	243.2	4.3	0.1	9	0.4	50.0	0.2	18	0.07	0.108	2
1287718	Soil	3.9	39.3	7.6	123	0.1	40.6	12.6	201	3.16	338.0	11.0	0.2	5	0.5	105.6	0.2	63	0.03	0.121	3
1287719	Soil	6.5	18.2	9.0	189	0.6	23.5	3.5	141	0.83	30.7	0.9	0.1	18	3.2	15.5	0.1	39	0.24	0.094	2
1287720	Soil	6.5	71.0	19.6	521	1.7	97.8	9.7	335	2.76	26.5	3.9	0.5	53	6.9	16.9	0.2	89	0.55	0.154	3
1287721	Soil	6.8	59.4	17.9	421	2.2	89.8	11.0	417	4.35	63.7	4.1	1.2	112	7.2	27.8	0.2	113	2.51	0.132	6
1287722	Soil	17.7	112.3	17.9	762	1.7	158.4	16.8	279	3.91	86.3	5.5	1.7	47	6.2	25.0	0.2	90	0.40	0.145	7
1287723	Soil	43.8	60.3	25.1	398	0.7	160.6	16.2	441	4.62	69.6	23.7	2.8	189	2.2	41.7	0.2	212	5.95	0.078	7
1287724	Soil	4.7	97.7	22.1	159	1.9	127.8	13.8	338	3.77	49.5	1.9	3.0	127	1.3	23.0	0.2	87	3.83	0.119	4
1287725	Soil	9.1	41.6	19.7	325	0.6	74.9	8.0	240	3.64	52.7	2.2	0.5	18	1.6	21.8	0.2	102	0.40	0.079	3
1287726	Soil	19.4	18.3	12.9	95	0.3	28.7	3.1	51	1.40	20.0	1.1	0.1	4	0.2	8.3	0.1	41	0.02	0.098	2
1287727	Soil	140.5	42.2	18.6	457	<0.1	129.1	8.5	65	2.28	48.7	<0.5	0.2	5	0.2	23.2	0.2	194	0.02	0.051	3
1287728	Soil	111.1	41.2	25.7	329	<0.1	177.8	13.9	112	2.92	32.4	0.5	0.4	5	0.5	10.4	0.1	123	0.02	0.057	3
1287729	Soil	7.2	11.3	15.3	68	<0.1	16.2	1.9	28	0.73	12.5	0.9	0.1	21	0.7	4.8	0.1	33	0.05	0.117	2
1287730	Soil	1.9	7.8	9.8	26	<0.1	6.2	1.1	197	0.46	3.7	<0.5	<0.1	33	0.2	2.0	<0.1	12	0.05	0.071	1
1287781	Soil	28.2	49.3	22.8	618	0.5	100.2	13.3	223	2.38	50.9	1.7	0.5	5	3.1	31.3	0.2	201	0.04	0.058	4
1287782	Soil	40.3	57.6	26.6	605	0.2	109.6	12.4	342	3.63	48.4	1.3	0.6	27	1.9	22.7	0.2	182	0.23	0.116	8
1287783	Soil	8.7	26.4	13.9	161	0.3	40.8	5.8	145	1.89	18.7	0.8	0.1	21	0.5	7.0	0.1	61	0.04	0.143	5
1287784	Soil	7.1	20.0	13.9	113	0.2	29.6	4.0	54	1.52	17.3	<0.5	0.2	13	0.2	6.1	0.1	47	0.02	0.104	3
1287785	Soil	6.5	24.4	15.0	132	0.1	37.4	5.3	93	1.79	14.2	0.7	0.1	13	0.3	5.3	0.2	56	0.02	0.120	4
1287786	Soil	6.7	33.3	14.4	137	0.3	42.1	7.3	85	2.04	15.0	<0.5	0.1	10	0.2	6.5	0.2	46	0.02	0.116	4
1287787	Soil	11.5	104.0	37.0	354	1.0	123.1	15.2	367	4.13	51.5	3.4	0.8	40	3.4	35.2	0.2	62	0.35	0.120	5
1287788	Soil	6.2	43.0	24.9	251	0.5	50.7	6.4	81	2.28	16.4	1.8	0.2	47	0.6	6.1	0.2	45	0.09	0.171	4
1287789	Soil	15.2	58.0	28.8	340	0.3	69.2	10.0	141	2.72	44.0	2.3	0.2	10	1.7	22.1	0.2	114	0.03	0.067	3
1287790	Soil	18.5	69.2	44.3	286	0.8	105.4	14.7	245	3.73	43.7	1.7	0.5	54	1.5	11.9	0.2	95	0.28	0.155	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287711	Soil	16	0.27	210	0.003	2	0.37	0.007	0.03	0.1	0.11	3.1	0.6	<0.05	1	2.6	<0.2
1287712	Soil	14	0.04	135	0.003	2	0.39	0.008	0.03	<0.1	0.03	1.2	0.3	<0.05	2	1.1	<0.2
1287713	Soil	12	0.03	101	0.005	2	0.30	0.012	0.03	<0.1	0.03	0.6	0.2	<0.05	1	0.8	<0.2
1287714	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287715	Soil	9	0.03	146	0.002	1	0.34	0.018	0.04	<0.1	0.02	0.3	0.1	<0.05	2	<0.5	<0.2
1287716	Soil	13	0.04	184	0.003	1	0.39	0.011	0.04	<0.1	0.02	1.0	0.1	0.07	1	0.9	<0.2
1287717	Soil	10	0.03	185	0.004	3	0.46	0.015	0.03	<0.1	0.02	1.4	<0.1	0.06	2	<0.5	<0.2
1287718	Soil	21	0.04	226	0.004	3	0.69	0.008	0.04	<0.1	0.03	3.4	0.2	<0.05	2	1.0	<0.2
1287719	Soil	9	0.04	118	0.003	2	0.42	0.026	0.03	<0.1	0.12	0.6	0.1	<0.05	1	1.4	<0.2
1287720	Soil	23	0.07	189	0.007	3	0.37	0.013	0.04	<0.1	0.38	4.9	0.2	<0.05	<1	4.1	<0.2
1287721	Soil	26	1.16	625	0.004	3	0.29	0.007	0.05	<0.1	0.40	7.0	0.2	<0.05	<1	4.4	<0.2
1287722	Soil	26	0.07	340	0.002	1	0.32	0.004	0.05	<0.1	0.42	7.7	0.3	<0.05	<1	3.7	<0.2
1287723	Soil	17	3.06	802	0.004	4	0.21	0.013	0.04	<0.1	0.39	6.3	0.6	<0.05	<1	3.5	<0.2
1287724	Soil	27	1.87	494	0.002	5	0.21	0.006	0.05	<0.1	0.31	7.0	0.2	0.05	<1	3.5	<0.2
1287725	Soil	18	0.09	246	0.004	3	0.29	0.008	0.03	<0.1	0.11	2.5	0.2	<0.05	<1	2.7	<0.2
1287726	Soil	8	0.02	70	0.003	1	0.34	0.011	0.02	<0.1	0.03	0.4	0.2	<0.05	2	1.0	<0.2
1287727	Soil	10	0.02	67	0.001	1	0.33	0.003	0.03	0.2	0.02	0.7	0.5	<0.05	1	2.5	<0.2
1287728	Soil	8	0.02	87	0.001	2	0.31	0.002	0.02	0.1	0.01	1.3	0.5	<0.05	<1	3.6	<0.2
1287729	Soil	8	0.02	125	0.003	1	0.22	0.022	0.03	<0.1	0.02	0.3	0.1	<0.05	1	0.7	<0.2
1287730	Soil	5	0.02	140	0.003	1	0.28	0.024	0.02	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2
1287781	Soil	16	0.02	144	0.002	1	0.33	0.002	0.05	<0.1	0.24	3.3	0.6	<0.05	<1	2.7	<0.2
1287782	Soil	27	0.08	1050	0.002	2	0.48	0.003	0.04	<0.1	0.10	3.4	0.5	<0.05	1	3.0	<0.2
1287783	Soil	14	0.03	215	0.003	2	0.48	0.008	0.05	<0.1	0.02	0.4	0.1	<0.05	2	1.8	<0.2
1287784	Soil	9	0.02	102	0.004	1	0.39	0.012	0.03	<0.1	0.02	0.5	<0.1	<0.05	2	1.5	<0.2
1287785	Soil	15	0.02	143	0.007	1	0.40	0.006	0.04	<0.1	0.02	0.5	<0.1	<0.05	2	1.6	<0.2
1287786	Soil	15	0.02	108	0.003	1	0.45	0.009	0.04	<0.1	0.02	0.3	<0.1	<0.05	2	1.5	<0.2
1287787	Soil	30	0.08	551	0.003	4	0.33	0.005	0.05	<0.1	0.28	5.4	0.2	<0.05	<1	2.7	<0.2
1287788	Soil	17	0.02	429	0.004	2	0.35	0.009	0.04	<0.1	0.04	1.0	0.2	<0.05	1	2.1	<0.2
1287789	Soil	15	0.03	268	0.002	2	0.35	0.005	0.04	<0.1	0.06	2.0	0.2	<0.05	1	2.3	<0.2
1287790	Soil	21	0.06	400	0.002	2	0.33	0.004	0.05	<0.1	0.11	3.4	0.2	<0.05	<1	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282921	Soil		1.7	36.0	26.6	63	1.2	16.1	3.2	58	2.79	18.8	4.6	1.1	16	0.2	0.9	0.3	51	0.02	0.191	4
1282922	Soil		1.3	21.7	16.3	50	0.3	12.1	2.3	71	1.61	9.6	<0.5	0.3	12	0.2	0.6	0.2	32	0.03	0.185	3
1282923	Soil		2.1	24.0	17.5	74	0.4	15.9	3.8	153	1.77	10.3	1.8	0.2	22	0.6	0.8	0.2	33	0.06	0.239	3
1282924	Soil		3.7	26.4	20.2	47	1.6	14.4	1.9	35	1.45	9.9	0.7	<0.1	54	0.5	1.2	0.2	24	0.03	0.177	4
1282925	Soil		1.0	14.1	6.2	33	0.6	7.9	1.6	24	0.99	3.4	1.4	0.1	9	0.4	0.2	0.1	15	0.02	0.107	1
1282926	Soil		1.3	13.9	14.4	60	0.6	10.5	2.9	73	1.53	8.2	0.9	0.5	14	0.2	0.4	0.2	36	0.03	0.065	3
1282927	Soil		0.8	15.4	11.4	93	0.3	10.7	3.7	69	1.91	7.4	<0.5	0.4	11	0.6	0.3	0.2	36	0.02	0.080	3
1282928	Soil		0.9	25.7	11.7	41	1.0	10.5	2.0	30	1.39	4.4	0.7	0.8	10	0.8	0.4	0.2	38	0.02	0.139	5
1282929	Soil		1.5	20.2	18.7	150	0.3	21.2	7.1	153	3.02	24.4	<0.5	1.6	12	0.7	0.5	0.3	50	0.03	0.070	3
1282930	Soil		4.9	29.5	22.5	146	0.4	33.0	7.7	125	3.49	23.9	2.0	2.1	17	0.4	2.4	0.3	55	0.02	0.079	6
1284161	Soil		1.6	11.7	7.1	36	0.1	7.0	2.6	207	1.18	5.0	<0.5	0.2	6	<0.1	0.6	0.1	32	0.03	0.079	5
1284162	Soil		0.2	3.4	1.7	3	<0.1	0.7	0.4	10	0.24	<0.5	<0.5	<0.1	6	<0.1	<0.1	<0.1	5	0.03	0.028	<1
1284163	Soil		0.2	2.4	1.4	4	<0.1	0.7	0.4	17	0.23	<0.5	<0.5	<0.1	5	<0.1	<0.1	0.1	5	0.03	0.035	<1
1284164	Soil		1.7	21.7	11.0	54	0.2	10.1	4.0	149	2.32	9.1	2.4	0.3	10	0.1	0.7	0.2	35	0.02	0.100	5
1284165	Soil		0.6	5.5	4.1	16	0.1	3.2	1.4	182	0.68	3.0	<0.5	<0.1	6	<0.1	0.3	<0.1	13	0.02	0.078	2
1284166	Soil		1.3	17.2	6.5	31	0.2	6.4	2.1	65	1.10	5.8	1.3	0.2	8	0.1	0.6	0.1	24	0.02	0.069	4
1284167	Soil		3.9	22.1	16.4	69	0.6	11.6	3.3	75	2.29	14.2	2.1	0.3	40	0.2	1.1	0.2	37	0.02	0.182	4
1284168	Soil		2.8	21.0	13.1	59	0.4	10.3	2.6	57	1.85	11.5	1.6	<0.1	24	0.1	1.1	0.3	45	0.02	0.142	5
1284169	Soil		2.4	15.5	13.8	44	0.6	8.8	2.4	53	1.65	9.4	1.8	0.2	19	0.1	1.1	0.2	35	0.02	0.111	4
1284170	Soil		2.7	13.9	10.5	44	0.1	7.9	2.2	34	1.58	11.0	<0.5	0.1	13	<0.1	1.1	0.2	38	0.02	0.067	4
1284171	Soil		3.2	7.4	9.6	18	0.2	3.3	0.8	17	0.73	5.8	1.0	0.4	8	<0.1	2.2	0.2	16	0.01	0.021	2
1284172	Soil		4.8	17.7	15.9	64	0.6	11.4	2.7	50	2.50	14.7	1.3	0.2	22	<0.1	2.3	0.2	43	0.02	0.083	4
1284173	Soil		3.2	12.3	7.0	52	0.2	8.2	2.6	37	1.57	13.3	3.7	0.6	6	<0.1	1.4	0.1	38	0.01	0.030	5
1284174	Soil		3.0	13.5	9.5	42	0.6	8.5	2.5	35	1.52	9.6	1.4	0.4	9	<0.1	0.9	0.2	35	0.01	0.039	5
1284175	Soil		3.7	25.8	20.9	102	0.4	22.7	7.2	113	3.93	19.8	0.9	0.5	14	0.1	1.3	0.3	65	0.02	0.106	4
1284176	Soil		0.4	4.1	2.1	8	0.2	1.9	0.6	9	0.32	1.4	<0.5	<0.1	5	<0.1	0.1	<0.1	7	0.02	0.037	1
1284177	Soil		1.8	26.2	20.3	74	0.9	13.4	3.8	75	3.02	20.5	1.3	0.8	12	0.1	0.8	0.3	51	0.02	0.100	3
1284178	Soil		1.5	20.2	17.4	55	0.3	9.1	2.7	47	1.89	12.6	1.3	0.6	12	<0.1	0.7	0.3	46	0.01	0.057	4
1284179	Soil		6.3	29.4	20.3	97	2.3	14.5	3.3	102	2.40	13.4	3.3	0.1	54	0.2	1.7	0.2	36	0.05	0.251	4
1284180	Soil		0.5	6.2	4.2	11	0.3	2.2	0.7	12	0.45	1.8	0.7	<0.1	6	<0.1	0.2	<0.1	12	0.01	0.039	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282921	Soil	28	0.05	341	0.003	1	1.12	0.007	0.07	<0.1	0.06	1.5	<0.1	<0.05	4	0.9	<0.2
1282922	Soil	18	0.03	322	0.004	2	0.65	0.011	0.05	<0.1	0.05	0.6	<0.1	<0.05	2	<0.5	<0.2
1282923	Soil	21	0.04	449	0.003	2	0.68	0.009	0.07	<0.1	0.03	0.6	<0.1	<0.05	2	0.5	<0.2
1282924	Soil	18	0.01	912	0.001	2	0.49	0.010	0.05	<0.1	0.04	0.3	0.1	0.09	2	2.0	<0.2
1282925	Soil	10	0.02	203	0.003	2	0.41	0.020	0.03	<0.1	0.03	0.5	<0.1	<0.05	1	<0.5	<0.2
1282926	Soil	11	0.04	275	0.002	1	0.68	0.010	0.07	<0.1	0.04	0.8	<0.1	<0.05	3	<0.5	<0.2
1282927	Soil	12	0.05	240	0.003	2	0.89	0.013	0.06	<0.1	0.03	0.8	<0.1	<0.05	4	<0.5	<0.2
1282928	Soil	14	0.03	425	0.002	1	0.97	0.008	0.05	<0.1	0.03	1.1	<0.1	<0.05	3	<0.5	<0.2
1282929	Soil	23	0.17	427	0.002	<1	1.38	0.007	0.09	<0.1	0.02	2.2	<0.1	<0.05	5	<0.5	<0.2
1282930	Soil	21	0.18	441	0.003	2	1.06	0.004	0.07	<0.1	0.05	2.2	0.2	<0.05	3	0.8	<0.2
1284161	Soil	9	0.03	85	0.004	1	0.57	0.013	0.04	<0.1	0.02	0.2	<0.1	<0.05	3	<0.5	<0.2
1284162	Soil	1	0.02	20	0.007	<1	0.46	0.028	0.02	<0.1	0.01	0.2	<0.1	<0.05	2	<0.5	<0.2
1284163	Soil	2	0.01	19	0.005	<1	0.36	0.024	0.02	<0.1	0.02	0.1	<0.1	0.06	2	<0.5	<0.2
1284164	Soil	17	0.06	106	0.005	<1	0.75	0.006	0.04	<0.1	0.04	0.6	<0.1	<0.05	3	0.7	<0.2
1284165	Soil	6	0.03	44	0.004	<1	0.32	0.016	0.04	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2
1284166	Soil	10	0.04	83	0.005	<1	0.66	0.014	0.04	<0.1	0.03	0.3	<0.1	<0.05	3	<0.5	<0.2
1284167	Soil	15	0.05	454	0.003	<1	0.66	0.008	0.06	<0.1	0.05	0.6	0.2	0.10	3	1.7	<0.2
1284168	Soil	14	0.03	383	0.001	1	0.63	0.005	0.05	<0.1	0.04	0.2	0.1	0.08	3	1.3	<0.2
1284169	Soil	12	0.04	286	0.002	2	0.57	0.010	0.05	<0.1	0.06	0.3	0.2	<0.05	2	1.3	<0.2
1284170	Soil	9	0.03	264	0.003	<1	0.59	0.007	0.04	<0.1	0.02	0.3	0.2	<0.05	3	0.8	<0.2
1284171	Soil	4	0.02	340	<0.001	2	0.35	0.005	0.07	<0.1	0.04	0.6	0.3	<0.05	1	1.2	<0.2
1284172	Soil	12	0.03	486	0.002	<1	0.61	0.007	0.06	<0.1	0.04	0.5	0.3	0.09	3	1.6	<0.2
1284173	Soil	6	0.02	131	0.002	<1	0.44	0.004	0.03	<0.1	0.02	0.8	0.1	<0.05	2	0.8	<0.2
1284174	Soil	9	0.02	342	0.002	<1	0.63	0.005	0.04	<0.1	0.04	0.6	0.2	<0.05	3	0.5	<0.2
1284175	Soil	22	0.11	309	0.004	1	1.04	0.005	0.06	<0.1	0.04	1.6	0.2	<0.05	4	1.2	<0.2
1284176	Soil	2	<0.01	57	0.004	<1	0.40	0.018	0.02	<0.1	0.02	0.2	<0.1	<0.05	1	<0.5	<0.2
1284177	Soil	18	0.04	196	0.002	1	0.92	0.009	0.06	<0.1	0.07	1.2	0.1	<0.05	4	0.8	<0.2
1284178	Soil	12	0.03	282	0.002	<1	0.73	0.006	0.05	<0.1	0.03	1.0	0.1	<0.05	3	0.6	<0.2
1284179	Soil	13	0.03	764	0.001	2	0.58	0.012	0.07	<0.1	0.13	0.4	0.3	0.19	2	4.0	<0.2
1284180	Soil	4	0.01	207	0.004	<1	0.35	0.014	0.03	<0.1	0.04	0.2	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1284351	Soil	1.7	42.8	70.1	99	2.5	19.2	18.5	431	4.22	37.6	5.1	2.7	127	0.1	1.4	0.4	48	0.06	0.151	4
1284352	Soil	1.3	38.4	40.8	109	0.6	33.9	25.0	397	3.55	20.0	1.6	3.8	85	<0.1	0.6	0.3	40	0.04	0.091	3
1284353	Soil	1.9	40.0	31.0	101	0.8	26.1	17.3	490	3.30	19.0	4.7	1.7	44	0.1	0.9	0.3	37	0.06	0.141	3
1284354	Soil	0.4	7.0	3.3	8	0.2	2.1	0.9	29	0.48	2.1	<0.5	0.1	7	<0.1	<0.1	<0.1	7	0.05	0.041	2
1284355	Soil	1.3	20.4	12.6	41	0.4	9.1	3.1	96	2.03	10.2	<0.5	0.4	14	<0.1	0.5	0.2	38	0.02	0.089	4
1284356	Soil	1.4	21.3	12.4	54	0.2	13.6	5.2	176	1.92	11.1	2.5	0.5	12	<0.1	0.6	0.2	31	0.02	0.066	4
1284357	Soil	1.9	22.0	14.6	76	0.2	18.7	6.9	165	3.22	13.0	1.3	0.9	12	0.2	0.8	0.2	44	0.03	0.061	6
1284358	Soil	1.7	23.4	16.6	72	0.3	17.2	6.1	128	3.37	15.6	0.8	1.0	11	0.1	0.7	0.3	48	0.02	0.082	6
1284359	Soil	1.7	30.0	15.2	77	0.2	20.2	9.1	229	2.99	13.9	2.2	1.9	12	0.1	0.8	0.2	43	0.03	0.066	7
1284360	Soil	2.4	23.1	8.7	48	0.1	11.5	2.7	61	1.35	7.2	2.0	0.1	11	<0.1	0.8	0.2	49	0.03	0.060	9
1284361	Soil	2.5	26.9	19.3	88	0.3	21.4	12.4	377	3.32	14.4	1.6	0.8	15	0.1	0.9	0.3	56	0.03	0.081	6
1284362	Soil	0.9	11.5	7.5	34	0.3	8.3	3.3	82	1.26	5.9	1.5	0.1	6	<0.1	0.3	0.1	21	0.02	0.055	3
1284363	Soil	1.8	19.6	13.8	56	0.3	12.9	5.2	140	2.84	11.6	1.4	0.5	9	<0.1	0.6	0.2	45	0.02	0.077	5
1284364	Soil	1.4	33.8	22.4	84	0.7	20.5	6.3	97	3.55	17.7	2.0	1.3	16	<0.1	0.6	0.3	41	0.01	0.100	3
1284365	Soil	1.1	11.3	6.9	28	0.3	5.9	1.9	37	1.02	4.7	0.7	<0.1	9	<0.1	0.4	0.1	23	0.02	0.063	3
1284366	Soil	1.0	13.2	12.3	35	0.3	6.2	2.3	46	1.53	8.4	<0.5	0.4	13	<0.1	0.3	0.2	30	0.01	0.067	3
1284367	Soil	1.1	24.3	22.7	101	0.8	25.9	5.5	190	1.91	7.5	3.2	0.4	26	0.1	0.3	0.2	34	0.11	0.120	3
1284368	Soil	3.4	17.6	11.9	60	0.3	9.0	2.2	39	1.38	9.7	<0.5	0.2	14	0.2	1.1	0.1	48	0.02	0.069	5
1284369	Soil	3.2	17.5	16.9	64	0.4	9.8	2.0	45	2.50	14.7	0.8	0.4	23	0.3	2.0	0.2	37	0.02	0.126	3
1284370	Soil	5.3	15.3	16.4	63	0.5	11.2	2.7	75	3.40	16.9	1.0	0.3	18	<0.1	1.9	0.3	54	0.03	0.150	4
1284371	Soil	4.3	15.6	14.8	66	0.4	10.7	3.1	95	2.52	13.3	1.2	0.2	16	<0.1	1.7	0.3	48	0.03	0.097	5
1284372	Soil	1.9	9.4	6.9	27	0.2	5.2	1.4	38	1.04	6.6	<0.5	0.1	8	<0.1	0.6	0.1	29	0.02	0.066	3
1284373	Soil	2.6	12.2	13.6	52	0.2	8.2	2.4	60	1.30	8.1	1.4	<0.1	17	<0.1	1.7	0.2	39	0.03	0.070	5
1284374	Soil	4.2	23.6	16.6	81	0.5	13.4	4.2	115	2.76	15.4	1.6	0.4	33	0.2	2.6	0.2	44	0.03	0.123	5
1284375	Soil	5.2	10.4	15.1	43	0.4	7.0	1.5	31	1.42	10.7	<0.5	0.1	20	<0.1	2.4	0.2	48	0.02	0.094	6
1284376	Soil	2.8	15.9	15.9	53	0.2	7.8	2.2	36	1.76	13.9	1.4	0.3	22	<0.1	1.2	0.2	50	0.01	0.084	5
1284377	Soil	3.0	18.9	19.4	50	0.3	9.2	2.0	36	1.79	10.6	2.3	0.1	16	<0.1	1.2	0.2	43	0.02	0.119	5
1284378	Soil	1.7	7.8	6.6	31	<0.1	5.0	1.5	25	0.75	5.0	1.3	0.3	9	<0.1	0.7	0.1	28	0.01	0.044	7
1284379	Soil	2.4	11.5	12.6	47	0.4	9.5	2.3	62	1.58	9.6	3.7	0.1	17	0.2	1.2	0.2	32	0.03	0.074	4
1284380	Soil	1.0	6.7	5.6	17	0.2	3.9	1.0	25	0.77	3.6	0.5	<0.1	5	<0.1	0.5	<0.1	15	0.02	0.065	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284351	Soil	28	0.16	476	<0.001	<1	1.25	0.012	0.09	<0.1	0.16	5.1	0.2	0.17	4	1.8	0.2
1284352	Soil	30	0.24	670	0.001	2	1.38	0.008	0.11	<0.1	0.13	5.4	0.2	0.08	4	0.8	<0.2
1284353	Soil	35	0.16	941	0.002	3	1.20	0.010	0.11	<0.1	0.15	6.0	0.2	0.17	3	1.4	<0.2
1284354	Soil	5	0.03	31	0.010	<1	0.64	0.028	0.02	<0.1	0.02	0.5	<0.1	<0.05	2	<0.5	<0.2
1284355	Soil	17	0.07	99	0.003	<1	0.82	0.009	0.04	<0.1	0.03	0.5	<0.1	<0.05	4	<0.5	<0.2
1284356	Soil	17	0.13	111	0.002	<1	0.77	0.007	0.05	<0.1	0.04	1.1	<0.1	<0.05	3	0.7	<0.2
1284357	Soil	25	0.20	100	0.005	<1	1.18	0.005	0.04	<0.1	0.03	1.5	<0.1	<0.05	4	0.7	<0.2
1284358	Soil	24	0.16	100	0.004	<1	1.07	0.004	0.04	<0.1	0.05	1.5	0.1	<0.05	4	0.9	<0.2
1284359	Soil	25	0.23	119	0.004	<1	1.09	0.005	0.05	<0.1	0.04	2.8	0.1	<0.05	3	0.8	<0.2
1284360	Soil	12	0.05	144	0.005	<1	0.89	0.008	0.04	0.1	0.03	0.3	0.1	<0.05	4	<0.5	<0.2
1284361	Soil	26	0.16	299	0.004	1	1.25	0.005	0.06	<0.1	0.04	1.7	0.1	<0.05	5	1.1	<0.2
1284362	Soil	10	0.06	87	0.003	<1	0.62	0.014	0.03	<0.1	0.02	0.4	<0.1	<0.05	2	<0.5	<0.2
1284363	Soil	19	0.09	137	0.003	<1	0.94	0.005	0.05	<0.1	0.04	0.9	<0.1	<0.05	4	0.5	<0.2
1284364	Soil	26	0.16	189	0.001	<1	1.30	0.006	0.06	<0.1	0.10	2.2	0.1	<0.05	4	0.9	<0.2
1284365	Soil	7	0.03	167	0.003	<1	0.51	0.015	0.03	<0.1	0.01	0.2	<0.1	<0.05	2	<0.5	<0.2
1284366	Soil	10	0.03	152	0.002	1	0.65	0.011	0.03	<0.1	0.02	0.6	<0.1	<0.05	3	<0.5	<0.2
1284367	Soil	20	0.16	604	0.001	1	1.18	0.012	0.06	<0.1	0.05	1.4	0.1	<0.05	4	0.6	<0.2
1284368	Soil	11	0.02	160	0.002	2	0.45	0.007	0.05	<0.1	0.03	0.4	0.1	<0.05	3	0.6	<0.2
1284369	Soil	14	0.03	257	0.002	2	0.60	0.007	0.05	<0.1	0.03	0.6	0.1	0.07	2	1.7	<0.2
1284370	Soil	19	0.05	136	0.005	1	0.62	0.005	0.04	<0.1	0.05	0.4	0.1	0.07	4	1.7	<0.2
1284371	Soil	14	0.06	167	0.004	1	0.67	0.006	0.04	<0.1	0.04	0.4	<0.1	<0.05	3	1.4	<0.2
1284372	Soil	6	0.02	68	0.003	2	0.47	0.011	0.02	<0.1	0.02	0.2	<0.1	<0.05	3	0.7	<0.2
1284373	Soil	10	0.04	335	0.005	1	0.53	0.012	0.05	<0.1	0.01	0.4	0.2	<0.05	3	0.8	<0.2
1284374	Soil	15	0.08	414	0.004	2	0.76	0.007	0.05	<0.1	0.04	0.8	0.1	0.07	3	1.5	<0.2
1284375	Soil	9	0.03	213	0.003	<1	0.55	0.010	0.04	<0.1	0.02	0.2	0.2	<0.05	3	1.8	<0.2
1284376	Soil	11	0.02	506	0.002	2	0.52	0.005	0.05	<0.1	0.01	0.6	0.1	<0.05	3	1.1	<0.2
1284377	Soil	12	0.04	268	0.004	1	0.76	0.008	0.06	0.1	0.06	0.6	0.2	<0.05	3	1.7	<0.2
1284378	Soil	6	0.02	154	0.003	1	0.38	0.004	0.03	<0.1	0.01	0.4	0.1	<0.05	3	<0.5	<0.2
1284379	Soil	10	0.05	261	0.004	2	0.52	0.012	0.04	<0.1	0.03	0.4	0.1	<0.05	3	1.3	<0.2
1284380	Soil	6	0.03	61	0.004	<1	0.34	0.015	0.02	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288061	Soil	1.7	15.5	8.5	40	0.1	6.6	3.3	222	1.66	5.1	<0.5	0.1	7	<0.1	0.7	0.1	25	0.02	0.101	4
1288062	Soil	2.3	23.5	17.7	101	<0.1	20.0	10.0	412	3.95	14.7	<0.5	0.5	9	0.2	1.2	0.3	37	0.02	0.086	4
1288063	Soil	2.0	19.1	13.8	82	0.2	21.6	9.2	281	3.42	11.7	<0.5	0.4	9	0.1	0.9	0.2	27	0.02	0.086	3
1288064	Soil	2.2	20.8	15.3	90	<0.1	22.9	10.2	435	3.57	16.3	0.7	0.4	9	0.2	1.4	0.2	39	0.04	0.083	6
1288065	Soil	1.3	12.2	8.0	44	0.1	10.7	4.5	331	1.85	6.8	<0.5	0.1	6	0.2	0.7	0.1	24	0.02	0.083	2
1288066	Soil	2.4	20.3	16.6	124	0.2	26.1	14.8	575	5.00	17.2	<0.5	0.9	8	0.2	1.2	0.2	40	0.03	0.117	4
1288067	Soil	1.7	14.6	10.9	55	<0.1	10.3	6.1	421	2.62	8.8	0.8	0.2	7	0.2	0.9	0.2	30	0.03	0.110	3
1288068	Soil	1.9	33.5	14.5	162	0.1	35.4	14.2	383	4.37	16.4	1.1	1.2	11	0.1	1.0	0.2	36	0.02	0.090	3
1288069	Soil	2.9	33.8	19.6	135	0.2	30.3	12.3	399	4.25	20.7	0.7	2.0	16	0.1	1.3	0.2	33	0.02	0.080	3
1288070	Soil	3.3	20.0	14.6	63	0.4	11.7	3.0	100	3.79	15.5	<0.5	0.5	16	0.1	1.8	0.2	41	0.02	0.093	3
1288071	Soil	2.6	16.8	10.2	46	0.3	6.4	2.0	40	4.05	23.1	0.8	0.4	5	0.2	1.4	0.3	34	0.01	0.093	1
1288072	Soil	4.9	85.2	13.7	670	0.4	127.1	68.9	1239	7.84	16.5	1.1	1.6	24	3.8	2.3	0.2	30	0.09	0.086	3
1288073	Soil	3.0	25.9	11.5	952	0.7	157.1	38.9	697	8.19	13.1	1.0	1.0	37	2.2	1.4	0.1	24	0.42	0.095	3
1288074	Soil	2.3	15.0	16.1	66	0.1	12.9	3.4	52	3.73	13.4	1.7	0.3	8	<0.1	1.1	0.2	35	0.03	0.085	3
1288075	Soil	1.6	8.7	8.8	42	<0.1	6.6	1.7	56	1.25	6.8	<0.5	0.2	12	0.2	0.7	0.1	25	0.03	0.070	3
1288076	Soil	4.2	28.1	22.3	111	0.7	21.7	6.1	133	2.73	20.3	1.3	1.7	47	0.5	2.1	0.3	27	0.08	0.081	3
1288077	Soil	3.8	24.0	18.7	106	0.5	19.9	5.0	114	2.50	19.3	1.0	1.4	34	0.4	2.1	0.2	23	0.08	0.063	2
1288078	Soil	4.3	21.5	21.0	96	0.4	16.3	4.3	135	2.67	18.7	1.8	1.0	31	0.3	2.4	0.3	29	0.02	0.076	2
1288079	Soil	5.0	26.4	20.2	133	0.5	23.2	6.2	124	2.77	22.0	<0.5	1.6	44	0.6	3.1	0.2	24	0.07	0.078	2
1288080	Soil	6.2	19.0	18.2	130	0.8	22.4	4.2	98	2.02	14.6	2.2	0.5	50	0.7	5.2	0.2	32	0.06	0.066	3
1288091	Soil	1.9	33.4	24.0	89	1.0	20.4	5.2	115	3.46	17.4	2.8	2.0	93	0.2	1.1	0.2	26	0.05	0.135	3
1288092	Soil	1.7	43.8	28.2	124	0.7	28.1	6.6	181	5.12	25.5	3.6	2.4	147	0.4	1.1	0.3	35	0.04	0.207	4
1288093	Soil	1.7	19.4	14.6	90	0.2	14.2	4.1	106	1.95	10.9	2.3	0.5	43	0.2	0.9	0.2	33	0.02	0.107	4
1288094	Soil	11.2	24.5	14.7	130	0.5	37.5	4.0	51	1.29	15.4	1.2	0.1	19	0.3	10.4	0.2	41	0.04	0.090	6
1288095	Soil	12.3	75.5	47.1	503	0.2	100.0	11.3	260	2.97	45.9	0.9	0.9	89	1.7	55.4	0.7	81	0.36	0.313	23
1288096	Soil	13.2	92.0	37.0	409	1.3	133.1	10.8	81	3.07	58.1	2.8	0.8	93	1.5	41.4	0.4	81	0.54	0.424	14
1288097	Soil	55.2	84.6	131.0	271	3.4	71.3	5.2	60	3.58	66.0	3.4	0.6	302	0.9	31.0	0.8	322	0.18	0.312	17
1288098	Soil	39.5	38.0	17.7	169	0.3	147.9	10.1	362	3.84	23.2	1.7	1.5	155	0.7	10.5	0.1	63	5.14	0.063	11
1288099	Soil	39.6	35.8	15.3	436	0.2	94.4	8.4	149	2.59	23.5	<0.5	1.6	7	5.5	20.9	0.1	163	0.09	0.034	9
1288100	Soil	4.7	32.7	24.5	219	0.6	56.4	9.2	501	5.30	19.8	1.1	1.1	54	1.6	11.5	0.2	73	1.02	0.123	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288061	Soil	12	0.05	62	0.004	<1	0.86	0.011	0.03	<0.1	0.02	0.3	<0.1	<0.05	4	0.8	<0.2
1288062	Soil	26	0.19	75	0.005	<1	1.15	0.004	0.05	<0.1	0.02	1.2	0.2	<0.05	5	1.3	<0.2
1288063	Soil	21	0.21	60	0.004	2	0.97	0.006	0.04	<0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2
1288064	Soil	26	0.20	65	0.006	<1	1.12	0.005	0.05	<0.1	0.03	0.8	0.2	<0.05	4	0.6	<0.2
1288065	Soil	13	0.07	55	0.004	<1	0.57	0.012	0.03	<0.1	0.03	0.5	<0.1	<0.05	3	0.6	<0.2
1288066	Soil	32	0.20	78	0.005	1	1.36	0.003	0.04	<0.1	0.05	1.4	0.1	<0.05	5	0.7	<0.2
1288067	Soil	18	0.04	79	0.005	<1	0.68	0.008	0.04	<0.1	0.03	0.4	<0.1	<0.05	4	0.6	<0.2
1288068	Soil	22	0.16	85	0.005	2	1.13	0.006	0.05	<0.1	0.03	1.6	0.2	<0.05	5	<0.5	<0.2
1288069	Soil	24	0.25	175	0.003	<1	1.23	0.004	0.06	<0.1	0.02	2.3	0.3	<0.05	4	0.6	<0.2
1288070	Soil	20	0.10	155	0.003	1	0.92	0.005	0.04	<0.1	0.04	0.8	0.2	<0.05	4	1.0	<0.2
1288071	Soil	13	0.02	154	0.001	2	0.59	0.006	0.05	<0.1	0.02	0.8	0.2	<0.05	4	1.2	<0.2
1288072	Soil	10	0.04	638	0.002	3	1.68	0.007	0.07	<0.1	0.08	3.0	0.5	0.06	2	2.7	<0.2
1288073	Soil	12	0.09	338	0.002	2	1.20	0.009	0.04	<0.1	0.10	4.1	0.5	0.06	2	2.2	<0.2
1288074	Soil	17	0.09	112	0.003	2	0.84	0.006	0.03	<0.1	0.03	1.0	0.2	<0.05	4	1.2	<0.2
1288075	Soil	9	0.03	230	0.002	2	0.43	0.008	0.05	<0.1	0.02	0.8	0.2	<0.05	3	<0.5	<0.2
1288076	Soil	12	0.07	983	<0.001	2	0.61	0.007	0.11	<0.1	0.10	3.2	0.3	0.16	2	3.1	<0.2
1288077	Soil	10	0.07	1030	<0.001	2	0.54	0.005	0.09	<0.1	0.06	2.6	0.3	0.12	2	2.4	<0.2
1288078	Soil	13	0.08	564	<0.001	2	0.69	0.005	0.10	<0.1	0.03	2.1	0.3	0.12	2	1.9	<0.2
1288079	Soil	10	0.05	989	<0.001	2	0.52	0.005	0.10	<0.1	0.08	3.2	0.4	0.16	1	3.3	<0.2
1288080	Soil	8	0.04	929	0.001	2	0.45	0.009	0.09	<0.1	0.09	1.6	0.5	0.17	1	2.6	<0.2
1288091	Soil	16	0.04	823	<0.001	4	0.62	0.007	0.14	<0.1	0.08	4.0	0.1	0.26	2	3.4	0.3
1288092	Soil	19	0.06	1110	0.002	4	0.84	0.008	0.14	<0.1	0.05	4.5	0.1	0.25	2	4.9	0.4
1288093	Soil	12	0.03	746	0.003	3	0.63	0.005	0.07	<0.1	0.03	0.8	<0.1	0.07	2	0.9	0.2
1288094	Soil	8	0.02	149	0.002	3	0.26	0.009	0.05	<0.1	0.02	0.3	0.1	<0.05	1	1.3	<0.2
1288095	Soil	22	0.04	251	0.004	5	0.46	0.005	0.08	<0.1	0.05	0.9	0.2	<0.05	2	2.6	0.3
1288096	Soil	21	0.04	365	0.003	5	0.48	0.004	0.12	<0.1	0.06	1.0	0.2	0.05	2	5.3	0.5
1288097	Soil	22	0.06	385	0.005	3	0.39	0.005	0.10	0.2	0.09	0.7	0.8	0.23	3	4.3	0.6
1288098	Soil	13	2.16	515	0.005	3	0.29	0.014	0.03	<0.1	0.19	3.0	0.4	<0.05	<1	1.2	<0.2
1288099	Soil	9	0.03	421	0.001	2	0.27	0.002	0.04	<0.1	0.25	3.3	0.3	<0.05	<1	1.6	<0.2
1288100	Soil	23	0.42	853	0.005	2	0.58	0.009	0.04	<0.1	0.11	3.0	0.1	0.05	1	2.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288101	Soil		15.0	22.8	6.7	160	0.3	43.0	3.6	92	1.12	15.6	<0.5	0.1	20	0.9	9.3	<0.1	42	0.44	0.084	3
1288102	Soil		43.7	40.2	14.5	333	0.2	119.7	6.1	181	1.65	20.6	2.0	0.5	56	3.1	12.0	0.1	72	2.11	0.093	3
1288103	Soil		77.8	60.3	28.1	528	0.6	175.5	8.3	218	2.14	40.5	<0.5	0.9	44	3.5	19.4	0.2	174	1.67	0.060	4
1288104	Soil		59.7	42.9	12.6	167	0.2	149.3	8.1	194	2.20	22.8	<0.5	0.8	45	0.5	20.0	0.1	63	2.75	0.052	3
1288105	Soil		70.6	44.6	14.2	170	0.2	167.8	8.2	203	1.80	25.6	1.2	1.8	83	0.5	30.0	<0.1	56	6.06	0.060	2
1288106	Soil		74.2	50.7	16.6	320	0.1	165.7	7.4	193	1.76	18.8	1.2	1.3	124	3.1	18.6	<0.1	52	6.09	0.068	2
1288107	Soil		33.6	94.7	6.1	130	<0.1	125.8	36.2	473	4.93	17.2	<0.5	0.9	24	0.7	9.8	<0.1	57	0.74	0.074	5
1288108	Soil		73.6	55.8	17.9	173	0.1	197.2	10.1	229	2.12	45.0	<0.5	2.1	71	0.6	31.6	0.1	55	5.03	0.064	3
1288109	Soil		42.9	51.8	19.2	1601	0.3	117.4	8.4	178	2.72	58.3	<0.5	1.3	26	11.4	35.6	0.1	271	2.05	0.048	4
1288110	Soil		25.0	193.1	5.9	795	0.2	105.8	43.6	1062	8.78	54.2	<0.5	1.3	30	0.6	19.2	<0.1	67	0.67	0.065	14
1288111	Soil		28.6	279.8	7.1	623	1.0	178.1	99.1	3369	14.28	7051	302.5	0.6	55	1.7	93.4	<0.1	64	0.99	0.109	9
1288112	Soil		16.7	131.2	7.6	396	0.2	109.8	54.2	1849	7.75	1713	71.8	0.7	79	0.5	80.1	<0.1	70	1.16	0.116	8
1288113	Soil		18.7	186.9	7.3	364	0.7	193.9	92.6	1639	9.80	2118	136.5	1.1	52	1.6	97.1	<0.1	161	1.25	0.122	8
1288114	Soil		15.1	143.7	7.8	221	0.5	174.6	71.9	1264	8.78	1240	44.9	1.6	39	0.7	80.5	<0.1	222	1.19	0.120	7
1288115	Soil		11.6	251.7	10.4	170	1.3	192.9	92.3	846	9.37	1575	219.4	0.8	47	0.9	102.7	<0.1	127	1.85	0.118	7
1288116	Soil		11.1	126.9	9.0	193	0.5	122.8	43.5	817	8.72	1604	149.3	1.0	31	1.5	42.9	<0.1	157	0.70	0.087	8
1288117	Soil		28.1	71.2	17.6	567	0.4	132.3	29.7	748	7.78	460.4	23.9	1.7	20	4.7	34.2	0.1	274	0.35	0.085	8
1288118	Soil		18.6	96.7	12.4	345	0.6	123.5	32.4	549	5.91	580.6	66.9	1.2	34	2.8	35.6	<0.1	161	0.90	0.098	7
1288119	Soil		6.2	53.2	8.5	180	0.5	69.7	18.2	258	3.47	211.8	8.4	0.7	33	1.8	17.6	<0.1	78	0.67	0.089	5
1288120	Soil		13.9	69.9	11.5	265	0.5	81.7	19.3	252	4.02	257.0	19.4	1.1	35	1.7	22.9	0.1	103	0.65	0.111	7
1288121	Soil		23.9	65.5	16.6	489	0.7	100.4	13.2	234	3.55	84.0	2.8	0.9	32	3.6	20.6	0.1	120	0.39	0.112	7
1288122	Soil		21.8	52.6	70.8	151	1.7	98.0	13.8	293	2.55	19.7	1.4	1.1	61	1.5	15.9	0.3	88	0.42	0.074	3
1288123	Soil		24.0	48.3	72.2	120	1.7	100.9	15.7	325	3.09	19.4	1.8	1.1	57	1.2	14.5	0.3	99	0.47	0.081	3
1288124	Soil		19.9	87.0	69.8	278	1.7	231.7	39.2	812	6.25	28.1	3.6	1.0	85	2.5	16.2	0.2	148	0.64	0.203	6
1288125	Soil		5.5	19.9	15.8	94	0.6	25.3	3.9	55	1.32	24.7	3.6	0.2	22	0.4	8.3	0.1	31	0.05	0.092	2
1288126	Soil		9.6	27.7	26.5	156	0.3	36.9	8.1	318	2.51	46.7	4.5	0.2	27	0.3	11.7	0.2	51	0.05	0.096	4
1288127	Soil		11.8	42.1	28.9	222	0.3	63.0	12.2	328	3.22	70.5	5.8	0.2	34	0.7	23.0	0.3	64	0.09	0.105	5
1288128	Soil		12.1	44.5	29.0	268	0.3	65.0	12.3	250	3.93	95.3	10.8	0.4	41	0.8	18.3	0.3	74	0.03	0.125	6
1288129	Soil		5.5	20.9	12.6	149	0.1	40.2	10.1	147	3.28	93.9	4.3	0.3	7	0.2	10.6	0.3	40	0.01	0.055	3
1288130	Soil		9.6	28.1	31.6	120	0.5	32.5	6.1	70	1.94	19.8	<0.5	0.1	22	0.2	7.1	0.2	65	0.01	0.051	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288101	Soil	9	0.09	99	0.003	2	0.38	0.025	0.03	<0.1	0.07	0.5	0.2	<0.05	1	0.9	<0.2
1288102	Soil	12	0.80	190	0.003	3	0.27	0.010	0.03	<0.1	0.39	2.0	0.5	0.05	<1	1.1	<0.2
1288103	Soil	17	0.66	216	0.002	1	0.28	0.006	0.03	0.2	0.39	2.7	0.9	<0.05	<1	3.2	<0.2
1288104	Soil	14	1.35	173	0.001	3	0.25	0.005	0.03	0.1	0.65	3.2	0.9	<0.05	<1	1.0	<0.2
1288105	Soil	12	2.96	138	0.001	3	0.16	0.007	0.03	0.1	0.72	3.4	1.4	<0.05	<1	0.9	<0.2
1288106	Soil	11	2.47	180	0.002	3	0.17	0.006	0.03	<0.1	0.62	2.8	0.8	<0.05	<1	1.4	<0.2
1288107	Soil	35	0.17	321	<0.001	4	0.32	0.003	0.04	<0.1	0.19	16.9	0.5	<0.05	<1	0.7	<0.2
1288108	Soil	12	2.59	189	0.001	3	0.16	0.006	0.03	<0.1	0.33	4.0	1.0	<0.05	<1	1.1	<0.2
1288109	Soil	20	1.04	145	0.001	2	0.31	0.003	0.05	<0.1	0.94	3.7	0.6	<0.05	1	<0.5	<0.2
1288110	Soil	12	0.77	557	0.002	2	2.81	0.003	0.07	<0.1	0.13	48.6	0.2	<0.05	4	1.3	<0.2
1288111	Soil	43	0.68	648	0.004	4	1.62	0.006	0.12	<0.1	0.56	43.2	0.2	0.06	4	0.6	<0.2
1288112	Soil	56	1.45	772	0.012	3	3.06	0.012	0.08	<0.1	0.13	22.8	<0.1	<0.05	6	1.2	<0.2
1288113	Soil	58	0.64	527	0.003	5	1.15	0.007	0.10	<0.1	0.53	31.3	0.2	0.19	2	1.5	<0.2
1288114	Soil	63	0.45	407	0.002	6	0.88	0.009	0.13	<0.1	0.31	30.5	0.2	0.07	2	1.2	<0.2
1288115	Soil	67	0.49	397	0.001	5	0.49	0.008	0.10	<0.1	0.35	37.3	0.3	0.23	1	5.0	<0.2
1288116	Soil	56	0.15	457	<0.001	7	0.62	0.005	0.09	<0.1	0.27	34.7	0.2	<0.05	1	1.4	<0.2
1288117	Soil	44	0.10	317	0.001	3	0.44	0.004	0.06	<0.1	0.21	21.2	0.4	<0.05	1	2.4	<0.2
1288118	Soil	46	0.27	370	0.002	6	0.48	0.007	0.08	<0.1	0.29	21.0	0.3	<0.05	1	1.7	<0.2
1288119	Soil	30	0.09	324	0.002	3	0.58	0.019	0.05	<0.1	0.15	10.4	0.1	<0.05	1	2.0	<0.2
1288120	Soil	36	0.16	344	0.002	4	0.62	0.009	0.08	<0.1	0.24	15.0	0.2	<0.05	1	2.0	<0.2
1288121	Soil	24	0.09	395	0.002	3	0.43	0.007	0.05	<0.1	0.34	7.2	0.3	<0.05	<1	1.0	<0.2
1288122	Soil	25	0.08	621	0.001	3	0.16	0.004	0.10	0.2	0.74	3.6	1.2	0.24	<1	9.0	<0.2
1288123	Soil	34	0.06	513	0.001	3	0.21	0.005	0.12	0.2	0.83	3.9	1.3	0.27	1	9.3	<0.2
1288124	Soil	96	0.07	768	0.004	4	0.36	0.005	0.11	0.1	0.63	8.9	0.9	0.21	1	10.3	<0.2
1288125	Soil	8	0.02	188	0.003	3	0.28	0.017	0.04	<0.1	0.09	0.4	<0.1	<0.05	1	0.6	<0.2
1288126	Soil	13	0.03	279	0.005	2	0.35	0.006	0.06	<0.1	0.04	0.6	0.2	<0.05	2	1.8	<0.2
1288127	Soil	15	0.03	340	0.004	2	0.35	0.004	0.06	<0.1	0.05	1.6	0.2	<0.05	2	2.4	<0.2
1288128	Soil	16	0.03	285	0.006	3	0.47	0.004	0.06	<0.1	0.08	1.0	0.2	<0.05	2	2.1	<0.2
1288129	Soil	10	0.03	95	0.003	1	0.42	0.007	0.04	<0.1	0.02	1.5	0.2	<0.05	2	0.8	<0.2
1288130	Soil	13	0.02	90	0.010	<1	0.26	0.005	0.04	<0.1	0.03	0.4	0.2	<0.05	3	1.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287811	Soil		1.8	9.3	10.1	47	0.1	8.5	2.9	62	1.48	6.3	2.2	0.6	7	0.1	1.0	0.2	36	0.01	0.034	3
1287812	Soil		3.9	22.9	11.1	130	0.1	36.1	8.4	434	1.95	13.4	1.7	1.1	10	0.3	2.6	0.2	39	0.02	0.037	4
1287813	Soil		3.7	14.2	6.9	89	0.2	13.6	4.4	83	1.24	11.3	1.5	1.0	9	0.2	2.2	0.2	62	0.02	0.018	11
1287814	Soil		2.7	8.0	8.1	38	0.4	8.1	2.6	44	1.25	8.8	0.7	0.8	8	0.1	1.7	0.2	38	0.02	0.018	5
1287815	Soil		6.6	9.8	17.0	57	0.4	10.0	1.4	32	2.39	27.5	0.7	1.2	41	0.3	2.8	0.3	53	0.01	0.047	2
1287816	Soil		3.6	18.0	11.7	99	0.1	25.6	5.1	74	1.62	11.3	1.6	1.5	15	0.3	1.9	0.2	32	0.03	0.024	4
1287817	Soil		3.3	13.8	10.0	39	2.0	10.4	2.5	28	1.08	7.5	1.1	0.4	18	0.2	1.3	0.2	41	0.02	0.074	6
1287818	Soil		2.0	38.7	19.1	144	0.5	18.9	3.3	73	3.20	20.0	7.0	1.1	85	1.3	0.8	0.5	47	0.13	0.094	3
1287819	Soil		1.1	29.1	5.5	31	0.9	8.2	1.2	27	0.91	4.0	<0.5	0.1	34	0.7	0.5	0.1	21	0.17	0.045	4
1287820	Soil		0.5	9.9	1.8	9	0.2	10.9	0.8	75	0.28	<0.5	0.8	0.1	269	0.4	0.7	<0.1	5	2.22	0.048	1
1284069	Soil		8.4	42.7	20.7	179	0.5	44.2	7.5	226	3.54	36.7	6.9	2.3	55	0.8	7.1	0.5	123	0.11	0.173	10
1284070	Soil		6.4	25.6	13.2	73	1.3	18.1	2.7	58	1.42	20.6	2.5	0.7	18	0.4	3.1	0.3	99	0.04	0.037	11
1286653	Soil		1.5	21.2	6.3	176	0.5	18.2	2.5	261	0.77	4.7	1.8	0.2	36	1.2	1.2	0.1	43	0.38	0.057	4
1278019	Soil		2.0	30.4	13.3	94	0.3	35.3	7.9	313	1.87	10.5	2.6	0.3	26	0.2	1.1	0.3	31	0.04	0.113	4
1278020	Soil		3.7	50.1	27.8	160	2.1	61.2	10.9	367	3.18	20.4	6.8	2.2	80	0.9	1.8	0.4	32	0.26	0.134	7
1094519	Soil		74.9	40.8	144.1	160	5.9	25.3	2.3	56	4.78	114.9	8.3	1.0	51	0.5	57.4	0.3	356	0.04	0.214	8
1276429	Soil		43.0	164.4	22.2	310	0.5	555.7	88.5	619	6.75	237.8	6.7	13.9	303	2.9	15.4	0.1	115	8.57	0.459	40
1276430	Soil		121.4	84.3	22.3	307	0.2	243.7	15.6	310	3.18	126.3	3.7	7.0	76	2.1	11.5	0.2	75	2.15	0.126	16
1094518	Soil		71.4	39.9	195.9	70	7.9	12.1	1.7	54	4.18	126.7	7.7	1.2	41	0.4	60.3	0.4	309	0.03	0.261	9
1279571	Soil		10.2	33.3	13.7	89	1.1	19.2	3.0	47	1.24	27.6	1.9	0.4	10	0.5	5.4	0.2	21	0.04	0.069	4
1277901	Soil		4.4	78.5	24.2	386	4.0	115.5	20.9	557	4.17	86.4	29.0	2.4	93	2.6	6.2	0.4	48	0.41	0.156	12
1279661	Soil		5.4	14.3	8.3	78	0.2	21.1	3.8	95	1.17	6.1	0.5	1.6	31	1.3	1.2	0.1	66	0.31	0.069	11
1284381	Soil		1.3	10.0	10.3	28	0.3	10.2	2.0	51	1.11	4.3	1.2	0.1	12	<0.1	0.5	0.1	17	0.04	0.081	2
1284382	Soil		9.0	41.3	25.6	480	0.9	83.4	12.5	275	2.91	21.1	3.4	1.8	53	2.6	3.6	0.3	52	0.29	0.146	7
1284383	Soil		14.6	130.0	25.0	857	2.2	166.9	17.4	463	3.66	38.4	2.6	0.9	57	9.4	18.4	0.3	98	0.40	0.202	9
1284384	Soil		14.5	41.9	35.9	220	0.6	50.2	7.5	128	2.39	36.6	1.6	0.3	86	0.4	20.7	0.3	65	0.03	0.161	8
1284385	Soil		4.8	4.9	4.0	27	0.2	8.0	0.7	16	0.35	3.6	0.6	<0.1	6	<0.1	1.2	<0.1	21	0.04	0.064	2
1284386	Soil		30.5	29.3	21.9	345	0.1	67.8	6.8	105	2.84	32.3	1.8	0.3	11	0.7	17.9	0.2	147	0.03	0.138	8
1284387	Soil		7.8	71.5	22.5	210	0.2	84.5	10.1	273	3.62	13.8	1.5	0.6	7	0.5	11.1	0.2	69	0.04	0.113	4
1284388	Soil		63.4	50.4	12.0	262	0.1	154.7	10.2	326	2.71	37.7	1.2	1.5	140	2.0	17.2	0.1	59	6.36	0.108	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287811	Soil	9	0.06	106	0.007	1	0.72	0.010	0.04	<0.1	<0.01	1.3	<0.1	<0.05	4	<0.5	<0.2
1287812	Soil	15	0.17	188	0.003	2	0.85	0.011	0.05	<0.1	0.01	2.0	0.2	<0.05	3	0.5	<0.2
1287813	Soil	9	0.02	145	0.016	1	0.46	0.006	0.03	0.1	<0.01	1.4	<0.1	<0.05	4	<0.5	<0.2
1287814	Soil	6	0.03	122	0.004	2	0.41	0.010	0.04	<0.1	0.01	0.9	<0.1	<0.05	3	<0.5	<0.2
1287815	Soil	9	0.03	2060	0.003	2	0.72	0.008	0.08	<0.1	0.02	1.1	0.3	<0.05	3	1.1	<0.2
1287816	Soil	12	0.13	321	0.003	2	0.92	0.020	0.08	<0.1	0.03	2.1	0.2	<0.05	3	0.6	<0.2
1287817	Soil	7	0.03	227	0.008	<1	0.68	0.011	0.05	<0.1	0.02	0.7	0.1	<0.05	3	0.5	<0.2
1287818	Soil	15	0.09	3444	0.005	5	0.86	0.011	0.13	<0.1	0.02	2.2	0.1	0.09	3	<0.5	0.4
1287819	Soil	6	0.02	713	0.011	2	0.48	0.025	0.04	<0.1	0.05	1.1	<0.1	<0.05	1	<0.5	<0.2
1287820	Soil	2	0.26	576	0.010	4	0.40	0.049	0.03	<0.1	0.02	0.9	<0.1	0.16	<1	2.4	<0.2
1284069	Soil	24	0.17	1835	0.003	3	1.00	0.005	0.07	0.2	0.69	2.2	0.4	0.06	3	2.7	<0.2
1284070	Soil	14	0.04	376	0.006	<1	0.73	0.003	0.05	0.2	0.12	1.0	0.3	<0.05	5	1.2	<0.2
1286653	Soil	10	0.06	367	0.006	2	0.42	0.024	0.06	<0.1	0.29	1.1	0.2	<0.05	1	0.7	<0.2
1278019	Soil	16	0.05	232	0.004	2	0.67	0.011	0.09	<0.1	0.06	0.8	0.1	<0.05	3	1.1	<0.2
1278020	Soil	21	0.11	578	0.007	4	0.70	0.008	0.15	<0.1	0.39	3.4	0.3	0.19	2	2.9	<0.2
1094519	Soil	45	0.09	157	0.017	2	0.73	0.005	0.30	0.4	1.76	2.0	2.7	0.71	5	29.6	0.5
1276429	Soil	134	1.66	718	0.007	14	0.61	0.006	0.17	0.2	0.75	17.0	1.9	0.10	2	2.8	<0.2
1276430	Soil	23	0.90	288	0.010	5	0.35	0.004	0.09	0.3	1.85	5.4	1.7	<0.05	<1	2.8	<0.2
1094518	Soil	36	0.09	168	0.014	2	0.58	0.004	0.31	0.5	1.28	2.5	1.9	0.63	4	28.4	0.6
1279571	Soil	3	0.01	120	0.004	<1	0.26	0.009	0.04	<0.1	0.14	0.6	0.2	<0.05	<1	0.9	<0.2
1277901	Soil	26	0.14	1044	0.006	2	1.49	0.008	0.08	0.1	1.67	4.2	0.3	0.06	3	3.1	<0.2
1279661	Soil	12	0.12	526	0.004	3	0.61	0.008	0.09	<0.1	0.04	1.0	0.2	<0.05	2	<0.5	<0.2
1284381	Soil	7	0.05	151	0.003	1	0.52	0.020	0.04	<0.1	0.05	0.4	0.1	<0.05	2	<0.5	<0.2
1284382	Soil	20	0.23	1008	0.002	2	1.02	0.008	0.10	<0.1	0.40	4.0	0.3	0.07	2	2.2	<0.2
1284383	Soil	33	0.08	352	0.005	2	0.46	0.005	0.08	<0.1	0.40	2.9	0.4	<0.05	1	5.6	<0.2
1284384	Soil	11	0.03	357	0.004	2	0.42	0.008	0.09	<0.1	0.04	0.5	0.3	0.07	2	2.3	<0.2
1284385	Soil	4	0.02	40	0.003	1	0.17	0.021	0.03	<0.1	0.02	0.2	<0.1	<0.05	<1	<0.5	<0.2
1284386	Soil	15	0.03	112	0.004	1	0.46	0.005	0.06	<0.1	0.01	0.4	0.4	<0.05	3	2.1	<0.2
1284387	Soil	24	0.04	147	0.005	<1	0.33	0.002	0.05	<0.1	0.02	1.9	0.2	<0.05	<1	2.8	<0.2
1284388	Soil	16	3.01	146	0.002	3	0.23	0.006	0.04	0.1	0.29	4.6	0.7	0.07	<1	1.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1284389	Soil	56.8	62.4	11.5	236	0.2	141.8	15.6	428	3.64	276.9	4.8	0.9	64	0.8	17.7	0.1	71	2.21	0.081	5
1284390	Soil	109.6	75.9	22.5	523	0.2	219.5	11.9	296	2.67	123.3	3.5	2.4	113	3.9	24.7	0.2	60	6.42	0.084	3
1284391	Soil	33.7	51.6	19.3	840	0.6	116.2	14.0	582	4.57	180.0	5.7	2.2	26	7.7	27.2	0.2	256	0.24	0.113	10
1284392	Soil	53.0	52.9	18.1	432	0.4	129.0	10.4	249	3.23	77.3	3.6	1.1	33	3.6	17.5	0.2	92	0.43	0.114	6
1284393	Soil	30.2	45.1	7.0	267	0.2	67.3	10.1	130	3.15	315.5	2.4	0.3	12	0.7	22.0	0.1	96	0.13	0.104	4
1284394	Soil	7.1	168.6	24.5	402	0.7	109.9	12.3	469	4.13	21.5	3.2	2.5	85	2.9	9.8	0.2	58	3.34	0.067	7
1284395	Soil	3.9	18.4	6.8	60	0.4	23.0	2.9	85	0.94	14.5	3.2	0.2	8	0.2	7.6	0.2	30	0.08	0.082	2
1284396	Soil	48.6	51.8	19.5	443	0.5	123.9	8.1	298	2.42	39.5	1.6	0.6	57	3.2	15.9	0.2	81	1.63	0.105	5
1284397	Soil	8.5	41.4	23.7	143	0.7	50.4	6.8	130	2.39	23.4	1.9	0.2	22	0.4	7.8	0.3	55	0.04	0.114	4
1284398	Soil	27.6	72.3	44.2	276	0.8	120.2	27.7	616	4.41	72.2	4.1	0.6	20	0.6	13.2	0.3	65	0.23	0.071	4
1284399	Soil	9.5	80.8	46.7	235	0.8	108.3	19.5	576	4.29	46.5	11.6	1.0	242	1.7	20.7	0.4	52	0.60	0.312	5
1284400	Soil	5.1	16.4	12.8	82	0.1	34.1	5.7	276	1.41	16.2	1.0	0.1	12	0.4	4.3	0.1	37	0.02	0.094	2
1282951	Soil	14.1	58.2	22.9	286	0.6	79.3	8.6	168	2.75	36.3	1.6	0.7	29	1.4	25.6	0.2	65	0.24	0.103	4
1282952	Soil	9.3	33.6	62.7	287	0.3	64.5	7.5	190	2.42	36.2	3.5	0.4	48	0.8	11.4	0.2	61	0.26	0.099	3
1282953	Soil	10.7	26.2	124.5	271	0.5	57.4	9.4	533	2.83	71.8	10.6	0.9	62	0.5	15.0	0.3	53	0.21	0.120	5
1282954	Soil	6.4	42.1	153.4	333	0.9	48.0	9.4	236	2.60	162.4	8.5	0.2	26	2.3	40.4	0.2	50	0.03	0.063	3
1282955	Soil	5.4	16.8	43.6	63	0.2	19.2	3.7	31	1.31	195.1	4.8	0.1	17	<0.1	16.9	0.3	48	<0.01	0.042	2
1282956	Soil	13.7	13.9	26.1	79	0.2	22.5	3.0	35	0.99	18.1	<0.5	0.1	11	<0.1	8.2	0.2	63	0.02	0.028	4
1282957	Soil	0.8	2.2	2.3	6	1.2	1.6	0.4	11	0.18	2.0	<0.5	<0.1	4	<0.1	0.6	<0.1	6	0.02	0.023	<1
1282958	Soil	2.6	4.3	23.8	10	0.5	2.4	0.4	8	0.30	4.0	1.8	<0.1	9	<0.1	1.9	0.1	14	0.02	0.050	1
1282959	Soil	7.5	9.8	26.5	49	0.2	12.1	2.0	32	0.80	15.5	1.1	0.1	16	<0.1	4.8	0.2	43	0.01	0.028	9
1282960	Soil	10.0	32.7	67.0	165	0.8	38.9	5.5	108	2.32	44.7	3.5	0.4	109	0.4	14.0	0.3	76	0.06	0.212	5
1282901	Soil	11.5	29.8	15.9	100	1.0	17.7	2.6	48	1.78	26.7	1.6	0.2	18	0.3	4.2	0.3	114	0.02	0.074	8
1282902	Soil	7.7	27.6	18.5	152	1.1	27.9	8.5	483	3.59	27.8	3.3	0.7	31	0.9	3.8	0.3	84	0.14	0.212	10
1282903	Soil	4.9	21.4	11.6	65	0.5	13.4	2.1	46	1.20	11.1	0.7	<0.1	14	0.4	1.8	0.2	52	0.02	0.106	5
1282904	Soil	8.9	58.0	17.2	198	0.5	41.9	8.6	329	3.16	24.3	7.6	2.1	49	0.8	4.7	0.3	105	0.11	0.160	11
1282905	Soil	8.6	25.9	14.3	100	0.5	19.0	3.0	51	1.55	17.9	1.1	0.1	21	0.2	3.5	0.2	100	0.02	0.058	7
1282906	Soil	0.7	18.4	15.7	45	0.3	10.9	5.6	360	1.99	8.0	1.3	0.4	10	0.2	0.4	0.2	23	0.02	0.132	1
1282907	Soil	0.7	13.6	10.2	24	0.2	5.7	3.5	205	1.19	12.3	1.1	0.2	6	0.1	0.5	0.1	15	0.03	0.084	1
1282908	Soil	1.0	33.9	22.9	112	0.3	29.5	13.1	202	2.97	18.6	2.0	0.7	14	<0.1	1.2	0.3	44	<0.01	0.086	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284389	Soil	36	0.92	302	0.004	1	0.92	0.009	0.04	<0.1	0.18	6.3	0.7	0.06	2	0.8	<0.2
1284390	Soil	13	1.54	112	0.002	3	0.23	0.004	0.05	0.1	0.39	5.3	0.9	0.06	<1	2.1	<0.2
1284391	Soil	29	0.19	299	0.006	1	0.75	0.005	0.05	0.1	0.53	6.5	0.3	<0.05	2	1.6	<0.2
1284392	Soil	20	0.10	265	0.003	2	0.59	0.007	0.05	0.1	0.27	5.5	0.5	<0.05	1	1.2	<0.2
1284393	Soil	18	0.07	180	0.003	2	0.74	0.005	0.05	<0.1	0.02	2.4	0.3	<0.05	2	1.0	<0.2
1284394	Soil	29	1.74	333	0.002	3	0.25	0.005	0.05	<0.1	0.35	7.0	0.2	0.08	<1	1.4	<0.2
1284395	Soil	7	0.03	85	0.003	1	0.51	0.019	0.02	<0.1	0.08	0.6	<0.1	<0.05	1	0.7	<0.2
1284396	Soil	14	0.67	288	0.002	3	0.24	0.005	0.03	<0.1	0.37	3.2	0.6	0.07	<1	1.8	<0.2
1284397	Soil	13	0.03	250	0.002	4	0.35	0.004	0.03	0.1	0.05	0.8	0.1	<0.05	2	1.7	<0.2
1284398	Soil	14	0.06	533	0.001	1	0.51	0.005	0.04	<0.1	0.11	3.5	0.3	<0.05	<1	1.5	<0.2
1284399	Soil	17	0.06	633	0.002	4	0.32	0.004	0.07	<0.1	0.21	4.9	0.2	0.10	<1	1.8	<0.2
1284400	Soil	19	0.02	83	0.003	<1	0.32	0.010	0.03	<0.1	0.03	0.3	0.1	<0.05	2	0.7	<0.2
1282951	Soil	19	0.04	468	0.002	1	0.31	0.003	0.03	<0.1	0.20	3.3	0.2	<0.05	<1	1.9	<0.2
1282952	Soil	12	0.07	311	0.002	<1	0.37	0.005	0.03	<0.1	0.08	1.6	0.1	<0.05	1	1.7	<0.2
1282953	Soil	15	0.08	243	0.002	2	0.52	0.004	0.04	<0.1	0.19	3.4	0.2	0.06	2	1.7	<0.2
1282954	Soil	10	0.02	276	0.001	1	0.31	0.005	0.03	0.1	0.11	1.2	0.2	<0.05	1	1.2	<0.2
1282955	Soil	5	<0.01	94	0.001	1	0.16	0.002	0.03	<0.1	0.01	0.5	0.2	<0.05	1	1.0	<0.2
1282956	Soil	7	0.01	67	0.003	<1	0.16	0.003	0.02	<0.1	<0.01	0.4	0.1	<0.05	2	1.0	<0.2
1282957	Soil	2	0.01	14	0.006	<1	0.18	0.014	0.02	<0.1	0.03	0.2	<0.1	<0.05	<1	<0.5	<0.2
1282958	Soil	4	<0.01	57	0.001	<1	0.14	0.009	0.02	<0.1	0.04	0.2	0.2	<0.05	1	0.6	<0.2
1282959	Soil	7	0.01	68	0.005	1	0.21	0.003	0.03	<0.1	0.02	0.2	0.2	<0.05	3	0.6	<0.2
1282960	Soil	12	0.03	277	0.002	<1	0.36	0.003	0.05	<0.1	0.04	1.0	0.3	0.06	2	2.6	<0.2
1282901	Soil	15	0.02	494	0.007	1	0.38	0.004	0.04	0.3	0.36	0.6	0.3	<0.05	3	1.8	<0.2
1282902	Soil	25	0.27	481	0.012	2	0.99	0.005	0.07	0.2	0.30	1.3	0.4	0.06	4	2.5	<0.2
1282903	Soil	10	0.02	203	0.002	<1	0.46	0.006	0.04	<0.1	0.04	0.2	0.2	<0.05	2	1.0	<0.2
1282904	Soil	20	0.14	349	0.003	2	0.96	0.002	0.07	<0.1	0.09	2.2	0.3	0.05	3	3.1	<0.2
1282905	Soil	9	0.02	318	0.003	<1	0.35	0.003	0.05	0.1	0.05	0.4	0.3	<0.05	3	2.1	<0.2
1282906	Soil	20	0.05	236	0.002	<1	0.68	0.011	0.03	<0.1	0.05	0.9	<0.1	0.10	2	0.5	<0.2
1282907	Soil	11	0.03	55	0.003	<1	0.68	0.017	0.02	<0.1	0.04	0.5	<0.1	<0.05	2	<0.5	<0.2
1282908	Soil	16	0.04	118	0.001	<1	0.43	0.004	0.05	<0.1	0.08	2.7	<0.1	<0.05	2	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282909	Soil		1.0	32.8	22.5	69	0.3	16.2	6.8	157	2.88	32.8	3.4	1.4	19	<0.1	0.7	0.3	41	0.01	0.095	2
1282910	Soil		1.1	24.6	12.6	67	0.2	12.5	4.4	164	1.93	10.3	0.7	0.3	9	0.6	0.6	0.3	40	0.03	0.129	3
1282911	Soil		1.6	23.9	20.3	85	0.3	17.3	8.8	325	3.19	15.0	0.7	0.8	9	0.2	0.7	0.3	45	0.02	0.132	3
1282912	Soil		1.3	25.0	22.4	73	0.5	16.6	6.2	131	3.65	20.3	1.8	1.1	15	0.1	0.5	0.3	44	0.01	0.112	2
1282913	Soil		0.9	21.6	17.2	61	0.2	14.9	8.2	185	1.93	11.7	2.1	0.8	7	<0.1	0.4	0.2	30	0.01	0.078	2
1282914	Soil		2.0	21.1	15.1	64	0.3	12.5	4.4	75	1.85	18.2	<0.5	0.3	9	0.1	0.8	0.2	47	0.02	0.098	3
1282915	Soil		0.7	12.5	9.7	40	<0.1	9.8	4.2	198	1.55	10.0	1.0	0.3	5	0.1	0.4	0.2	28	0.01	0.091	2
1282916	Soil		1.1	28.4	19.0	94	0.4	24.5	10.4	196	2.73	32.0	2.2	1.3	11	<0.1	0.7	0.3	37	0.02	0.085	2
1282917	Soil		1.4	52.6	27.6	137	0.8	32.8	17.4	309	3.87	54.3	4.4	2.4	15	0.1	0.9	0.3	39	0.03	0.079	2
1282918	Soil		1.5	23.5	44.9	111	0.3	18.5	8.3	255	3.58	34.0	1.1	1.2	23	<0.1	0.9	0.3	40	0.07	0.168	2
1282919	Soil		1.2	28.9	20.3	67	0.3	17.2	6.2	197	2.63	13.8	2.3	0.8	17	<0.1	0.4	0.3	39	0.02	0.086	3
1282920	Soil		1.7	17.1	17.8	46	0.3	9.6	3.5	108	1.85	10.8	0.8	0.2	10	<0.1	0.7	0.2	27	0.02	0.085	3
1282941	Soil		58.3	30.2	21.0	331	<0.1	91.6	11.1	481	2.83	34.3	2.2	0.4	17	2.4	28.1	0.2	119	0.23	0.087	4
1282942	Soil		44.1	73.8	30.7	230	0.2	126.1	12.8	238	5.26	47.1	1.1	0.5	12	2.1	14.8	0.3	160	0.07	0.100	4
1282943	Soil		73.8	47.5	17.5	538	<0.1	128.3	11.0	184	3.60	34.7	<0.5	0.3	9	1.5	32.7	0.2	110	0.12	0.084	5
1282944	Soil		138.9	193.9	38.1	5408	4.2	240.9	6.9	317	2.26	237.8	4.5	0.7	411	52.0	52.6	0.3	667	14.45	0.073	8
1282945	Soil		52.7	35.5	14.1	151	<0.1	79.2	4.5	142	1.75	31.9	1.0	0.3	13	0.9	11.0	0.2	60	0.12	0.052	3
1282946	Soil		26.9	50.5	5.7	310	<0.1	55.0	13.3	200	3.85	74.3	2.2	0.4	7	1.1	49.0	<0.1	138	0.06	0.092	2
1282947	Soil		5.1	36.4	3.6	87	0.1	20.6	10.1	371	2.66	492.0	15.0	0.4	25	0.4	17.4	<0.1	41	0.39	0.071	4
1282948	Soil		36.1	60.5	14.7	489	0.5	103.1	19.9	381	4.00	297.0	19.3	1.3	60	4.9	48.5	0.1	195	2.13	0.066	4
1282949	Soil		23.0	54.2	13.5	486	0.4	86.8	17.0	340	3.39	251.0	13.7	0.8	62	5.2	63.5	0.1	174	1.28	0.091	5
1282950	Soil		15.2	62.0	15.8	376	0.7	76.0	11.1	310	2.76	26.6	2.3	1.2	63	3.2	19.1	0.2	107	0.55	0.132	6
1282931	Soil		2.9	11.7	10.2	55	0.4	10.8	2.6	39	1.22	10.2	0.7	0.2	12	0.5	1.1	0.2	36	0.02	0.057	5
1282932	Soil		5.8	18.3	12.9	86	0.5	17.0	3.4	59	1.67	13.7	1.2	0.5	21	0.2	2.4	0.2	48	0.03	0.073	4
1282933	Soil		7.7	36.9	16.1	191	0.4	39.1	9.2	202	2.65	21.8	1.8	1.0	30	1.3	3.8	0.3	58	0.12	0.099	7
1282934	Soil		7.0	33.7	16.3	165	0.8	36.6	7.0	117	2.57	17.1	2.3	1.3	30	0.7	2.7	0.2	57	0.10	0.094	6
1282935	Soil		6.1	38.1	16.0	142	0.7	37.6	7.7	135	2.32	15.5	3.3	1.1	33	1.1	2.4	0.2	52	0.13	0.105	6
1282936	Soil		4.2	24.9	12.8	77	0.4	21.5	5.5	161	1.71	10.6	1.9	0.9	19	0.7	1.6	0.2	40	0.05	0.062	5
1282937	Soil		4.7	27.9	16.3	145	0.2	30.0	7.2	124	3.08	23.8	2.4	2.0	14	0.5	2.6	0.2	54	0.02	0.062	6
1282938	Soil		1.8	72.1	14.3	33	0.8	49.8	19.1	408	6.43	11.8	2.5	4.9	14	0.2	4.2	0.5	18	0.15	0.059	37

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282909	Soil	18	0.06	255	<0.001	<1	0.75	0.005	0.07	<0.1	0.13	2.3	0.1	0.12	2	0.8	<0.2
1282910	Soil	17	0.05	167	0.002	<1	0.67	0.006	0.06	<0.1	0.05	0.4	<0.1	<0.05	3	<0.5	<0.2
1282911	Soil	22	0.10	119	0.002	1	0.88	0.006	0.05	<0.1	0.05	1.3	<0.1	<0.05	4	0.7	<0.2
1282912	Soil	24	0.13	162	0.001	<1	0.97	0.006	0.06	<0.1	0.06	1.5	<0.1	0.05	4	0.7	<0.2
1282913	Soil	14	0.07	112	<0.001	1	0.70	0.009	0.05	<0.1	0.04	1.6	<0.1	<0.05	2	<0.5	<0.2
1282914	Soil	12	0.03	140	0.002	<1	0.62	0.005	0.05	<0.1	0.02	0.7	<0.1	<0.05	3	0.5	<0.2
1282915	Soil	13	0.05	145	0.002	1	0.65	0.010	0.04	<0.1	0.02	0.7	<0.1	<0.05	3	<0.5	<0.2
1282916	Soil	20	0.13	365	<0.001	<1	0.88	0.005	0.05	<0.1	0.07	3.2	<0.1	<0.05	3	0.7	<0.2
1282917	Soil	24	0.19	291	<0.001	<1	1.04	0.005	0.06	<0.1	0.07	6.3	0.1	<0.05	3	1.2	<0.2
1282918	Soil	14	0.04	290	0.001	<1	0.57	0.007	0.07	<0.1	0.17	2.4	0.1	0.08	2	1.4	<0.2
1282919	Soil	20	0.08	291	<0.001	<1	0.82	0.006	0.07	<0.1	0.08	2.2	0.1	0.08	3	0.7	<0.2
1282920	Soil	14	0.10	84	0.002	<1	0.64	0.012	0.04	<0.1	0.04	0.6	<0.1	<0.05	2	0.7	<0.2
1282941	Soil	14	0.04	177	0.004	2	0.37	0.004	0.04	0.1	0.10	1.5	0.4	0.06	1	1.5	<0.2
1282942	Soil	20	0.04	259	0.002	2	0.33	0.003	0.03	<0.1	0.08	2.1	0.3	0.06	<1	3.2	<0.2
1282943	Soil	22	0.06	155	0.004	1	0.43	0.003	0.04	0.1	0.19	1.7	0.6	<0.05	1	3.0	<0.2
1282944	Soil	41	3.50	352	0.002	2	0.19	0.012	0.04	0.2	12.66	2.7	2.2	<0.05	<1	10.1	<0.2
1282945	Soil	13	0.03	186	0.001	<1	0.33	0.003	0.02	0.1	0.21	1.7	0.7	<0.05	<1	1.3	<0.2
1282946	Soil	34	0.05	161	0.002	1	0.58	0.006	0.05	<0.1	0.07	7.0	0.3	<0.05	2	1.1	<0.2
1282947	Soil	19	0.09	328	0.002	2	0.71	0.026	0.05	<0.1	0.06	8.8	0.1	0.06	2	<0.5	<0.2
1282948	Soil	23	1.05	375	0.003	3	0.30	0.009	0.05	<0.1	0.53	12.1	0.4	0.07	<1	2.0	<0.2
1282949	Soil	23	0.29	402	0.002	4	0.42	0.007	0.04	<0.1	0.41	9.0	0.2	0.08	<1	1.8	<0.2
1282950	Soil	17	0.08	270	0.002	2	0.31	0.004	0.05	<0.1	0.23	4.8	0.2	<0.05	<1	1.9	<0.2
1282931	Soil	7	0.02	387	0.002	1	0.48	0.008	0.05	<0.1	0.03	0.4	<0.1	<0.05	3	0.6	<0.2
1282932	Soil	10	0.06	381	0.001	2	0.55	0.008	0.05	<0.1	0.07	0.9	0.2	<0.05	2	0.8	<0.2
1282933	Soil	17	0.15	820	0.002	3	0.78	0.006	0.07	0.1	0.10	1.8	0.2	<0.05	3	0.8	<0.2
1282934	Soil	16	0.14	762	0.002	2	0.84	0.007	0.07	<0.1	0.17	2.1	0.2	<0.05	2	0.8	<0.2
1282935	Soil	15	0.11	1001	0.002	2	0.85	0.007	0.08	<0.1	0.21	2.5	0.2	<0.05	2	1.3	<0.2
1282936	Soil	11	0.08	585	0.002	2	0.76	0.014	0.06	<0.1	0.14	1.5	0.1	<0.05	2	0.9	<0.2
1282937	Soil	16	0.14	282	0.002	1	0.92	0.004	0.05	<0.1	0.08	2.0	0.2	<0.05	3	0.9	<0.2
1282938	Soil	12	0.07	716	0.003	3	0.45	0.003	0.09	<0.1	0.10	5.8	0.1	<0.05	1	1.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282939	Soil	12.1	61.4	19.0	275	0.4	83.5	9.8	178	2.47	41.6	3.2	1.1	46	2.1	13.1	0.3	57	0.42	0.238	16
1282940	Soil	35.6	28.8	11.6	232	0.2	66.9	6.3	196	1.96	20.2	<0.5	0.3	17	0.8	12.6	0.2	136	0.03	0.097	8
1286131	Soil	6.1	49.0	11.5	327	1.5	55.0	8.3	244	1.85	16.7	4.6	1.7	64	4.6	4.0	0.2	79	0.64	0.098	7
1286132	Soil	10.2	57.9	17.1	380	1.5	69.4	12.2	516	2.69	34.3	1.5	1.8	79	4.8	7.9	0.2	76	0.71	0.120	5
1286133	Soil	6.3	19.9	11.7	126	0.4	19.1	3.0	75	1.54	21.6	1.7	1.1	14	0.5	4.4	0.2	82	0.03	0.057	7
1286134	Soil	11.6	71.3	17.4	382	1.2	70.2	9.8	135	2.58	38.9	0.8	2.4	76	4.3	9.1	0.2	70	0.51	0.115	4
1286135	Soil	8.3	24.4	12.1	74	0.3	32.2	8.7	492	1.74	17.8	0.8	0.3	19	0.6	3.7	0.2	25	0.26	0.085	5
1286136	Soil	9.2	81.2	45.0	38	1.0	73.2	20.4	321	5.39	45.7	6.8	3.8	8	<0.1	8.2	0.5	19	0.07	0.055	16
1286137	Soil	2.0	21.6	6.3	45	<0.1	17.3	4.3	35	1.30	8.9	0.9	0.3	5	<0.1	3.6	0.2	15	0.02	0.060	6
1286138	Soil	14.9	66.4	22.3	268	0.6	77.4	13.6	277	3.72	32.5	2.5	2.9	52	1.4	19.0	0.4	50	0.32	0.161	19
1286139	Soil	12.4	26.5	17.2	156	0.1	37.5	5.2	96	2.19	26.5	0.6	0.3	18	0.4	10.1	0.2	69	0.04	0.156	8
1286140	Soil	25.2	57.5	20.3	714	1.1	113.2	9.7	326	3.12	32.1	2.9	0.9	116	5.3	74.4	0.2	91	1.74	0.151	6
1286141	Soil	16.5	29.9	12.5	181	0.6	46.4	6.7	196	1.86	26.1	1.8	0.3	12	0.5	26.9	0.2	58	0.08	0.098	4
1286142	Soil	7.8	15.1	6.4	100	0.5	21.6	3.8	392	1.18	16.1	0.5	0.3	31	0.9	8.4	0.1	32	0.19	0.136	5
1286143	Soil	22.3	39.8	14.8	299	0.2	55.0	11.3	234	3.49	71.5	3.1	0.7	20	1.5	56.1	0.2	92	0.14	0.136	6
1286144	Soil	19.9	31.3	11.1	271	0.1	43.5	12.1	533	3.53	239.1	0.8	0.4	24	1.0	19.2	0.2	89	0.16	0.136	6
1286145	Soil	20.1	42.5	9.0	302	<0.1	39.9	20.6	1180	5.33	550.2	5.7	0.3	17	0.5	115.2	0.1	107	0.12	0.141	4
1286146	Soil	2.9	110.6	16.4	223	0.4	26.4	49.4	1404	12.76	9195	969.0	0.4	48	0.8	>2000	<0.1	36	0.51	0.152	8
1286147	Soil	13.3	56.5	5.6	209	<0.1	43.3	19.8	520	5.19	308.2	9.2	0.1	7	0.6	279.9	0.2	125	0.08	0.141	3
1286148	Soil	11.0	39.5	3.5	162	0.1	36.5	13.2	236	2.95	120.3	2.9	0.1	6	0.5	81.2	0.1	74	0.05	0.116	2
1286149	Soil	49.3	45.4	14.4	508	0.2	95.8	11.7	335	2.98	74.3	7.0	0.3	29	2.3	73.3	0.2	143	0.47	0.136	7
1286150	Soil	21.9	25.5	5.1	210	<0.1	41.5	6.3	130	1.96	99.2	1.7	0.1	9	0.6	20.1	0.1	80	0.06	0.087	3
1286161	Soil	2.9	25.0	17.4	116	0.8	24.4	8.3	199	3.27	18.0	2.6	1.3	34	0.3	1.5	0.2	43	0.04	0.154	4
1286162	Soil	0.9	5.5	4.5	18	<0.1	5.0	2.4	183	0.50	3.9	0.8	<0.1	7	<0.1	0.9	<0.1	9	0.04	0.048	1
1286163	Soil	1.5	7.8	3.6	25	<0.1	6.1	2.4	134	0.64	4.7	0.7	<0.1	8	<0.1	0.9	<0.1	13	0.06	0.048	2
1286164	Soil	2.7	23.3	20.6	110	0.6	21.0	6.8	153	3.05	19.9	3.0	1.0	49	0.2	2.1	0.3	47	0.02	0.119	5
1286165	Soil	2.2	26.9	22.3	63	0.8	16.1	4.0	153	2.31	12.1	4.3	0.9	53	0.3	0.8	0.2	25	0.03	0.123	3
1286166	Soil	2.4	15.5	16.0	54	0.9	11.7	2.4	42	1.41	8.2	3.4	0.5	88	0.3	0.9	0.2	23	0.15	0.110	3
1286167	Soil	0.5	8.7	4.4	15	0.3	6.4	1.1	19	0.54	2.1	1.1	<0.1	6	0.4	0.2	<0.1	14	0.03	0.053	2
1286168	Soil	3.3	15.5	15.5	78	0.3	14.1	4.1	165	2.42	17.5	0.6	0.2	14	0.3	1.5	0.2	67	0.03	0.100	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282939	Soil	12	0.03	642	0.003	4	0.49	0.006	0.09	<0.1	0.11	1.6	0.2	<0.05	1	1.5	<0.2
1282940	Soil	11	0.03	138	0.004	2	0.43	0.004	0.05	<0.1	0.05	0.7	0.3	<0.05	1	0.7	<0.2
1286131	Soil	17	0.17	1938	0.003	3	0.74	0.005	0.07	0.1	0.85	2.6	0.4	<0.05	2	2.5	<0.2
1286132	Soil	15	0.20	331	0.002	4	0.44	0.004	0.08	0.1	2.61	2.6	0.5	0.48	1	10.9	<0.2
1286133	Soil	9	0.03	371	0.003	1	0.33	0.004	0.05	0.1	0.21	0.9	0.2	<0.05	3	1.6	<0.2
1286134	Soil	15	0.21	180	0.002	3	0.39	0.003	0.08	0.1	1.73	2.9	0.6	1.04	1	10.3	<0.2
1286135	Soil	5	0.05	159	0.006	1	0.33	0.018	0.06	<0.1	0.07	0.8	0.2	<0.05	1	0.8	<0.2
1286136	Soil	8	0.04	151	<0.001	2	0.30	0.002	0.09	<0.1	0.27	5.8	0.4	<0.05	<1	1.2	<0.2
1286137	Soil	4	0.02	64	0.002	1	0.24	0.011	0.04	<0.1	0.03	0.4	<0.1	<0.05	1	<0.5	<0.2
1286138	Soil	10	0.06	636	0.003	3	0.34	0.003	0.08	<0.1	0.09	4.0	0.2	<0.05	<1	1.5	<0.2
1286139	Soil	14	0.05	237	0.004	1	0.56	0.005	0.05	<0.1	0.03	0.4	0.2	<0.05	3	0.7	<0.2
1286140	Soil	18	0.71	382	0.004	3	0.40	0.006	0.05	<0.1	0.31	2.9	0.3	<0.05	1	2.6	<0.2
1286141	Soil	11	0.03	129	0.003	<1	0.36	0.009	0.04	<0.1	0.06	0.6	0.2	<0.05	1	2.0	<0.2
1286142	Soil	7	0.04	337	0.005	1	0.49	0.016	0.05	<0.1	0.02	0.5	0.2	<0.05	1	0.9	<0.2
1286143	Soil	19	0.05	312	0.002	<1	0.53	0.005	0.05	<0.1	0.07	2.8	0.2	<0.05	1	1.1	<0.2
1286144	Soil	16	0.07	343	0.004	1	0.70	0.004	0.07	<0.1	0.01	2.3	0.2	<0.05	2	0.7	<0.2
1286145	Soil	14	0.06	358	0.003	1	0.63	0.007	0.05	<0.1	0.03	4.7	0.2	<0.05	2	1.0	<0.2
1286146	Soil	6	0.08	392	0.003	2	0.30	0.002	0.07	0.3	0.17	29.8	0.2	<0.05	<1	<0.5	<0.2
1286147	Soil	22	0.07	185	0.002	1	0.64	0.007	0.05	<0.1	0.03	4.9	0.2	0.08	2	0.9	<0.2
1286148	Soil	23	0.04	167	0.002	1	0.49	0.011	0.03	<0.1	0.01	2.2	0.2	0.06	2	0.7	<0.2
1286149	Soil	23	0.11	215	0.003	2	0.63	0.005	0.04	0.1	0.15	2.5	0.4	<0.05	2	2.1	<0.2
1286150	Soil	16	0.04	207	0.003	1	0.61	0.011	0.04	<0.1	0.02	1.2	0.3	<0.05	2	1.0	<0.2
1286161	Soil	21	0.16	535	0.002	2	0.98	0.005	0.06	<0.1	0.07	2.0	0.1	0.07	3	1.3	<0.2
1286162	Soil	3	0.02	36	0.004	<1	0.31	0.027	0.03	<0.1	0.02	0.2	<0.1	<0.05	1	<0.5	<0.2
1286163	Soil	4	0.02	43	0.003	<1	0.31	0.021	0.02	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2
1286164	Soil	18	0.10	416	0.002	2	0.76	0.006	0.07	<0.1	0.05	1.8	0.1	0.07	3	1.4	<0.2
1286165	Soil	12	0.04	902	<0.001	2	0.57	0.007	0.07	<0.1	0.09	2.3	0.1	0.09	2	1.4	<0.2
1286166	Soil	13	0.08	1035	<0.001	1	0.47	0.007	0.06	<0.1	0.09	1.2	<0.1	0.10	2	1.6	<0.2
1286167	Soil	4	0.02	259	0.002	<1	0.34	0.020	0.02	<0.1	0.04	0.2	<0.1	<0.05	1	<0.5	<0.2
1286168	Soil	15	0.09	170	0.004	1	0.72	0.005	0.05	0.1	0.02	0.7	0.2	<0.05	5	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286169	Soil	2.7	20.3	12.3	59	0.5	16.1	4.5	112	1.44	10.2	1.7	0.6	20	0.3	0.9	0.2	33	0.07	0.075	6
1286170	Soil	3.5	26.7	16.2	109	0.8	25.1	8.0	233	2.48	16.8	3.1	1.2	37	0.8	1.4	0.2	51	0.20	0.139	7
1283921	Soil	5.1	36.0	10.5	137	0.8	27.5	6.9	303	1.88	24.6	3.0	1.1	66	1.3	1.6	0.2	50	1.31	0.122	7
1283922	Soil	5.9	54.7	12.4	210	0.8	45.8	7.1	293	1.93	14.8	4.5	2.1	54	1.6	4.3	0.2	74	0.57	0.140	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

CERTIFICATE OF ANALYSIS WHI11001423.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286169	Soil	10	0.06	480	0.002	<1	0.60	0.007	0.05	<0.1	0.04	1.0	0.1	<0.05	3	0.7	<0.2
1286170	Soil	18	0.16	1172	0.002	1	1.05	0.008	0.07	<0.1	0.17	2.1	0.2	0.06	4	1.0	<0.2
1283921	Soil	14	0.17	1391	0.002	2	0.87	0.007	0.06	0.1	0.35	1.9	0.2	0.10	3	1.9	<0.2
1283922	Soil	19	0.23	1561	0.002	2	1.03	0.005	0.09	0.1	0.52	2.7	0.2	0.08	3	4.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

QUALITY CONTROL REPORT WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1287598	Soil	18.9	54.6	118.3	225	1.7	55.3	5.8	95	2.37	33.0	3.6	0.1	310	0.9	9.4	0.7	149	0.04	0.309	6
REP 1287598	QC	18.2	53.2	117.6	220	1.6	58.8	5.8	93	2.32	32.5	1.5	0.4	316	0.7	9.6	0.6	150	0.03	0.300	4
1287714	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1287714	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287723	Soil	43.8	60.3	25.1	398	0.7	160.6	16.2	441	4.62	69.6	23.7	2.8	189	2.2	41.7	0.2	212	5.95	0.078	7
REP 1287723	QC	42.6	59.4	25.9	390	0.7	159.9	15.9	445	4.54	69.2	23.6	2.5	188	2.1	42.8	0.1	215	5.85	0.080	7
1287786	Soil	6.7	33.3	14.4	137	0.3	42.1	7.3	85	2.04	15.0	<0.5	0.1	10	0.2	6.5	0.2	46	0.02	0.116	4
REP 1287786	QC	6.5	31.7	13.8	134	0.3	40.6	6.9	83	2.00	14.4	1.3	0.1	9	0.1	6.3	0.1	46	0.02	0.119	3
1284167	Soil	3.9	22.1	16.4	69	0.6	11.6	3.3	75	2.29	14.2	2.1	0.3	40	0.2	1.1	0.2	37	0.02	0.182	4
REP 1284167	QC	4.1	22.7	15.9	68	0.6	11.3	3.6	74	2.28	14.7	2.5	0.3	40	0.2	1.3	0.2	38	0.03	0.190	5
1284168	Soil	2.8	21.0	13.1	59	0.4	10.3	2.6	57	1.85	11.5	1.6	<0.1	24	0.1	1.1	0.3	45	0.02	0.142	5
REP 1284168	QC	2.9	21.3	13.2	59	0.5	10.4	2.6	56	1.93	11.8	2.5	0.1	25	0.1	1.2	0.3	47	0.02	0.190	6
1284356	Soil	1.4	21.3	12.4	54	0.2	13.6	5.2	176	1.92	11.1	2.5	0.5	12	<0.1	0.6	0.2	31	0.02	0.066	4
REP 1284356	QC	1.4	21.8	13.2	56	0.2	14.2	5.1	178	1.95	11.5	1.5	0.6	12	<0.1	0.7	0.2	34	0.02	0.068	4
1284380	Soil	1.0	6.7	5.6	17	0.2	3.9	1.0	25	0.77	3.6	0.5	<0.1	5	<0.1	0.5	<0.1	15	0.02	0.065	3
REP 1284380	QC	1.1	6.6	5.5	17	0.2	3.8	1.1	25	0.76	3.4	<0.5	0.1	5	0.1	0.4	<0.1	15	0.02	0.058	3
1288067	Soil	1.7	14.6	10.9	55	<0.1	10.3	6.1	421	2.62	8.8	0.8	0.2	7	0.2	0.9	0.2	30	0.03	0.110	3
REP 1288067	QC	1.6	13.7	10.3	52	<0.1	10.4	5.6	383	2.54	8.8	<0.5	0.1	8	0.2	0.8	0.1	30	0.03	0.116	3
1288103	Soil	77.8	60.3	28.1	528	0.6	175.5	8.3	218	2.14	40.5	<0.5	0.9	44	3.5	19.4	0.2	174	1.67	0.060	4
REP 1288103	QC	81.6	63.2	30.2	550	0.6	181.4	8.1	235	2.23	42.0	<0.5	0.9	47	3.7	20.9	0.2	195	1.76	0.064	4
1288127	Soil	11.8	42.1	28.9	222	0.3	63.0	12.2	328	3.22	70.5	5.8	0.2	34	0.7	23.0	0.3	64	0.09	0.105	5
REP 1288127	QC	11.9	41.4	30.8	226	0.3	60.6	11.7	329	3.16	68.8	7.0	0.4	34	0.9	22.1	0.3	60	0.09	0.104	5
1287818	Soil	2.0	38.7	19.1	144	0.5	18.9	3.3	73	3.20	20.0	7.0	1.1	85	1.3	0.8	0.5	47	0.13	0.094	3
REP 1287818	QC	2.0	39.3	19.7	149	0.5	20.8	3.5	73	3.18	20.7	8.1	1.1	83	1.4	0.9	0.5	47	0.13	0.095	3
1279661	Soil	5.4	14.3	8.3	78	0.2	21.1	3.8	95	1.17	6.1	0.5	1.6	31	1.3	1.2	0.1	66	0.31	0.069	11
REP 1279661	QC	6.1	15.2	8.9	84	0.2	20.8	4.0	101	1.28	6.8	1.5	1.8	35	1.4	1.4	0.2	69	0.32	0.076	11
1284399	Soil	9.5	80.8	46.7	235	0.8	108.3	19.5	576	4.29	46.5	11.6	1.0	242	1.7	20.7	0.4	52	0.60	0.312	5
REP 1284399	QC	9.4	79.1	46.4	241	0.8	108.1	19.2	564	4.34	45.9	12.3	1.0	240	1.6	20.7	0.4	52	0.61	0.309	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

QUALITY CONTROL REPORT WHI11001423.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1287598	Soil	20	0.01	535	0.003	3	0.44	0.005	0.09	0.1	0.06	0.5	0.4	0.19	3	2.6	0.3
REP 1287598	QC	20	0.01	530	0.003	2	0.43	0.005	0.09	0.1	0.05	0.5	0.3	0.14	3	2.1	0.3
1287714	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
REP 1287714	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287723	Soil	17	3.06	802	0.004	4	0.21	0.013	0.04	<0.1	0.39	6.3	0.6	<0.05	<1	3.5	<0.2
REP 1287723	QC	18	3.05	820	0.004	5	0.22	0.013	0.05	<0.1	0.37	6.2	0.6	<0.05	<1	2.9	<0.2
1287786	Soil	15	0.02	108	0.003	1	0.45	0.009	0.04	<0.1	0.02	0.3	<0.1	<0.05	2	1.5	<0.2
REP 1287786	QC	15	0.02	103	0.004	2	0.43	0.009	0.04	<0.1	0.02	0.5	<0.1	<0.05	2	1.6	<0.2
1284167	Soil	15	0.05	454	0.003	<1	0.66	0.008	0.06	<0.1	0.05	0.6	0.2	0.10	3	1.7	<0.2
REP 1284167	QC	14	0.05	482	0.004	<1	0.67	0.009	0.07	<0.1	0.05	0.5	0.2	<0.05	3	1.8	<0.2
1284168	Soil	14	0.03	383	0.001	1	0.63	0.005	0.05	<0.1	0.04	0.2	0.1	0.08	3	1.3	<0.2
REP 1284168	QC	15	0.03	406	0.003	2	0.64	0.005	0.06	<0.1	0.04	0.2	0.2	<0.05	3	1.3	<0.2
1284356	Soil	17	0.13	111	0.002	<1	0.77	0.007	0.05	<0.1	0.04	1.1	<0.1	<0.05	3	0.7	<0.2
REP 1284356	QC	17	0.13	115	0.003	<1	0.81	0.008	0.05	<0.1	0.03	1.2	<0.1	<0.05	3	0.7	<0.2
1284380	Soil	6	0.03	61	0.004	<1	0.34	0.015	0.02	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2
REP 1284380	QC	7	0.02	61	0.003	1	0.34	0.015	0.02	<0.1	0.03	0.2	<0.1	<0.05	2	<0.5	<0.2
1288067	Soil	18	0.04	79	0.005	<1	0.68	0.008	0.04	<0.1	0.03	0.4	<0.1	<0.05	4	0.6	<0.2
REP 1288067	QC	18	0.05	77	0.006	<1	0.68	0.008	0.04	<0.1	0.02	0.4	<0.1	<0.05	4	0.6	<0.2
1288103	Soil	17	0.66	216	0.002	1	0.28	0.006	0.03	0.2	0.39	2.7	0.9	<0.05	<1	3.2	<0.2
REP 1288103	QC	19	0.72	234	0.003	4	0.34	0.007	0.04	0.2	0.42	3.3	1.1	<0.05	<1	3.8	<0.2
1288127	Soil	15	0.03	340	0.004	2	0.35	0.004	0.06	<0.1	0.05	1.6	0.2	<0.05	2	2.4	<0.2
REP 1288127	QC	14	0.03	324	0.003	2	0.33	0.005	0.05	<0.1	0.06	1.5	0.2	<0.05	2	1.2	<0.2
1287818	Soil	15	0.09	3444	0.005	5	0.86	0.011	0.13	<0.1	0.02	2.2	0.1	0.09	3	<0.5	0.4
REP 1287818	QC	15	0.09	3179	0.003	5	0.85	0.011	0.13	<0.1	0.02	2.2	<0.1	0.12	3	1.0	0.3
1279661	Soil	12	0.12	526	0.004	3	0.61	0.008	0.09	<0.1	0.04	1.0	0.2	<0.05	2	<0.5	<0.2
REP 1279661	QC	13	0.14	558	0.004	3	0.63	0.009	0.09	<0.1	0.05	1.3	0.2	<0.05	2	<0.5	<0.2
1284399	Soil	17	0.06	633	0.002	4	0.32	0.004	0.07	<0.1	0.21	4.9	0.2	0.10	<1	1.8	<0.2
REP 1284399	QC	18	0.06	654	0.003	4	0.36	0.004	0.07	<0.1	0.22	5.0	0.2	0.12	<1	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

QUALITY CONTROL REPORT WHI11001423.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1282905	Soil	8.6	25.9	14.3	100	0.5	19.0	3.0	51	1.55	17.9	1.1	0.1	21	0.2	3.5	0.2	100	0.02	0.058	7
REP 1282905	QC	8.8	25.4	14.0	100	0.5	18.8	2.9	53	1.58	17.7	1.0	<0.1	20	0.1	3.5	0.2	106	0.02	0.058	7
1282948	Soil	36.1	60.5	14.7	489	0.5	103.1	19.9	381	4.00	297.0	19.3	1.3	60	4.9	48.5	0.1	195	2.13	0.066	4
REP 1282948	QC	38.2	61.9	15.2	504	0.4	102.6	19.7	392	4.00	306.2	17.5	1.4	62	4.8	49.3	0.1	192	2.12	0.066	4
1286133	Soil	6.3	19.9	11.7	126	0.4	19.1	3.0	75	1.54	21.6	1.7	1.1	14	0.5	4.4	0.2	82	0.03	0.057	7
REP 1286133	QC	6.5	20.9	11.8	132	0.4	20.9	2.8	79	1.58	22.4	1.7	1.1	15	0.5	4.5	0.2	86	0.03	0.060	7
1286150	Soil	21.9	25.5	5.1	210	<0.1	41.5	6.3	130	1.96	99.2	1.7	0.1	9	0.6	20.1	0.1	80	0.06	0.087	3
REP 1286150	QC	21.8	26.6	4.9	212	<0.1	41.4	6.2	131	1.95	99.9	1.6	0.1	9	0.6	19.4	<0.1	78	0.06	0.086	3
Reference Materials																					
STD DS8	Standard	12.9	110.5	120.3	300	1.7	37.4	7.4	588	2.36	24.7	124.5	6.8	68	2.4	5.4	6.2	42	0.67	0.081	15
STD DS8	Standard	12.6	105.5	117.3	302	1.8	35.2	7.3	584	2.47	23.8	104.9	6.5	67	2.4	5.8	6.4	39	0.66	0.076	15
STD DS8	Standard	11.2	100.4	114.6	283	1.7	35.8	6.9	544	2.22	22.7	106.6	5.2	60	2.2	4.2	6.0	38	0.63	0.075	12
STD DS8	Standard	14.2	109.8	127.9	303	1.8	37.7	7.7	606	2.61	23.9	138.3	7.1	73	2.3	5.1	6.4	44	0.71	0.080	16
STD DS8	Standard	13.2	110.6	124.7	300	1.8	37.7	7.4	605	2.40	22.5	124.6	6.4	60	2.1	5.1	6.1	42	0.65	0.077	15
STD DS8	Standard	12.4	104.4	119.7	288	1.7	35.8	7.2	569	2.28	21.4	101.7	6.1	61	2.1	4.5	5.6	41	0.62	0.073	14
STD DS8	Standard	12.7	109.0	122.5	298	1.7	36.3	7.4	575	2.30	23.8	117.0	6.2	66	2.4	5.4	6.1	40	0.62	0.071	13
STD DS8	Standard	12.4	107.1	125.4	295	1.6	36.6	7.5	563	2.30	23.3	113.0	7.0	72	2.2	5.3	7.5	40	0.66	0.072	13
STD DS8	Standard	14.8	117.2	122.2	303	1.7	41.4	8.4	632	2.48	23.9	111.4	8.0	80	2.2	6.2	7.5	45	0.73	0.076	16
STD DS8	Standard	13.1	108.5	123.6	314	1.9	38.3	7.3	590	2.42	24.0	117.9	6.5	65	2.3	5.4	6.0	43	0.67	0.080	16
STD DS8	Standard	13.7	114.1	128.4	300	1.8	40.6	8.3	632	2.58	25.3	114.3	6.7	66	2.4	6.0	6.9	45	0.71	0.084	15
STD DS8	Standard	13.2	109.3	125.7	315	1.8	38.8	7.4	613	2.45	24.8	115.1	6.7	71	2.5	5.3	6.8	41	0.69	0.079	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

QUALITY CONTROL REPORT WHI11001423.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1282905	Soil	9	0.02	318	0.003	<1	0.35	0.003	0.05	0.1	0.05	0.4	0.3	<0.05	3	2.1	<0.2
REP 1282905	QC	9	0.02	319	0.004	1	0.34	0.003	0.04	0.1	0.03	0.4	0.3	<0.05	3	2.0	<0.2
1282948	Soil	23	1.05	375	0.003	3	0.30	0.009	0.05	<0.1	0.53	12.1	0.4	0.07	<1	2.0	<0.2
REP 1282948	QC	23	1.07	368	0.001	2	0.32	0.010	0.05	<0.1	0.53	12.2	0.4	0.06	<1	1.8	<0.2
1286133	Soil	9	0.03	371	0.003	1	0.33	0.004	0.05	0.1	0.21	0.9	0.2	<0.05	3	1.6	<0.2
REP 1286133	QC	10	0.03	389	0.003	2	0.35	0.005	0.06	0.2	0.16	0.9	0.2	<0.05	3	1.7	<0.2
1286150	Soil	16	0.04	207	0.003	1	0.61	0.011	0.04	<0.1	0.02	1.2	0.3	<0.05	2	1.0	<0.2
REP 1286150	QC	16	0.04	205	0.002	1	0.58	0.010	0.03	<0.1	0.03	1.2	0.3	<0.05	2	0.9	<0.2
Reference Materials																	
STD DS8	Standard	112	0.59	288	0.118	2	0.91	0.099	0.42	3.0	0.18	2.5	5.2	0.11	5	4.4	4.3
STD DS8	Standard	110	0.60	275	0.111	2	0.88	0.079	0.38	2.8	0.17	2.2	5.1	0.12	5	5.1	4.7
STD DS8	Standard	104	0.55	243	0.096	3	0.85	0.095	0.41	2.5	0.18	2.2	4.9	0.13	4	5.9	4.7
STD DS8	Standard	119	0.64	287	0.124	3	0.96	0.105	0.43	3.0	0.21	2.1	5.4	0.13	5	6.0	5.0
STD DS8	Standard	116	0.60	258	0.114	2	0.91	0.083	0.38	3.0	0.19	2.2	5.4	0.17	4	4.6	4.8
STD DS8	Standard	115	0.57	246	0.106	2	0.87	0.094	0.39	2.6	0.18	2.5	5.3	0.13	4	4.6	4.5
STD DS8	Standard	114	0.57	258	0.107	2	0.89	0.100	0.45	2.8	0.19	2.2	5.3	0.13	4	4.7	4.8
STD DS8	Standard	111	0.59	259	0.105	2	0.88	0.098	0.42	2.8	0.19	2.9	5.5	0.13	4	4.8	4.2
STD DS8	Standard	128	0.63	288	0.130	3	0.97	0.105	0.42	2.9	0.21	2.7	5.4	0.14	5	5.5	4.8
STD DS8	Standard	116	0.60	275	0.113	2	0.90	0.093	0.42	2.9	0.19	2.3	5.4	0.16	5	5.2	4.9
STD DS8	Standard	124	0.62	268	0.122	3	0.96	0.099	0.44	3.1	0.21	2.4	5.5	0.17	5	5.2	5.2
STD DS8	Standard	118	0.62	265	0.116	3	0.93	0.106	0.43	2.7	0.19	3.2	5.4	0.15	5	4.6	4.9
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

QUALITY CONTROL REPORT WHI11001423.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 08, 2011

QUALITY CONTROL REPORT WHI11001423.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 09, 2011
Report Date: November 14, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001424.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #25
P.O. Number
Number of Samples: 305

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	304	Sieve soil to 230 mesh			WHI
RJSV	304	Saving all or part of Soil Reject			WHI
1DX2	296	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283923	Soil	5.2	44.2	12.6	457	0.8	68.7	9.0	410	2.26	20.1	3.0	2.7	56	4.8	4.2	0.2	58	0.65	0.171	11
1283924	Soil	31.0	42.8	13.4	520	0.8	94.9	33.2	3707	3.82	54.6	4.4	1.6	54	3.5	6.2	0.2	66	0.71	0.167	9
1283925	Soil	39.2	36.3	7.7	338	0.7	68.1	12.6	621	2.76	29.4	4.1	0.5	40	4.4	4.5	0.2	49	0.70	0.145	5
1283926	Soil	44.3	32.1	12.6	312	<0.1	93.4	9.7	165	2.08	23.0	2.0	1.0	18	1.8	9.9	0.2	65	0.24	0.050	6
1283927	Soil	9.8	20.9	6.5	158	0.3	30.5	5.0	238	1.52	53.3	<0.5	0.1	11	3.8	10.3	0.1	53	0.05	0.103	5
1283928	Soil	12.1	32.0	11.5	232	0.1	50.5	7.5	312	2.22	66.2	1.5	0.2	15	1.9	13.9	0.2	67	0.07	0.126	7
1283929	Soil	9.3	28.1	9.4	162	0.2	42.8	6.7	167	2.00	56.4	1.6	0.2	24	0.9	9.8	0.2	45	0.09	0.117	6
1283930	Soil	7.8	47.5	12.2	135	0.2	43.9	10.0	136	3.05	24.5	2.4	0.4	20	0.5	7.4	0.4	32	0.05	0.143	10
1283931	Soil	2.3	9.4	3.1	20	0.2	8.5	2.2	31	0.67	5.7	<0.5	0.2	5	0.1	1.3	<0.1	10	0.03	0.051	3
1283932	Soil	10.8	55.1	19.6	306	0.3	78.8	8.3	257	2.06	38.7	1.7	<0.1	29	0.7	12.6	0.3	51	0.14	0.207	8
1283933	Soil	12.8	18.6	7.1	151	0.2	30.9	3.9	564	0.84	13.1	<0.5	0.3	57	1.9	6.2	<0.1	46	1.00	0.074	3
1283934	Soil	5.6	12.0	4.3	68	<0.1	21.3	2.3	69	0.78	9.8	0.5	<0.1	8	0.4	3.7	<0.1	29	0.03	0.118	2
1283935	Soil	12.7	24.4	7.5	213	0.2	47.8	5.2	127	1.52	49.7	0.5	0.3	25	2.1	10.1	0.1	53	0.16	0.147	3
1283936	Soil	48.6	23.5	9.3	224	0.1	72.3	6.4	537	1.56	40.6	1.0	<0.1	10	2.1	10.4	<0.1	54	0.09	0.110	2
1283937	Soil	51.7	32.3	10.2	254	0.1	89.3	9.1	252	2.61	129.5	1.4	0.1	9	2.0	15.6	0.1	98	0.10	0.110	3
1283938	Soil	21.6	27.9	10.7	303	0.1	53.2	9.3	362	2.70	309.4	3.5	0.3	19	2.5	16.1	0.1	101	0.24	0.140	5
1283939	Soil	12.4	24.4	4.9	203	0.2	27.3	8.1	367	2.34	505.8	7.4	0.2	13	2.4	15.3	<0.1	102	0.14	0.103	3
1283940	Soil	4.1	23.7	21.4	211	0.3	60.0	8.1	137	3.91	28.4	2.1	1.2	23	0.3	11.9	0.1	66	0.16	0.137	4
1283941	Soil	18.4	20.1	13.3	218	0.1	48.0	6.1	506	2.70	16.5	6.5	0.7	211	3.0	10.9	<0.1	176	6.47	0.069	7
1283942	Soil	98.0	40.8	20.0	643	0.3	109.2	9.3	333	2.86	33.2	0.7	2.3	115	11.9	24.8	0.2	143	4.23	0.060	4
1283943	Soil	38.7	33.3	19.8	582	0.3	72.8	7.8	271	3.26	28.4	1.0	0.8	45	5.7	18.1	0.2	174	1.26	0.080	6
1283944	Soil	28.4	44.8	15.3	799	1.0	78.9	6.9	190	2.85	41.7	1.4	1.1	56	12.9	22.7	0.1	155	1.31	0.091	5
1283945	Soil	24.3	43.8	13.1	559	0.6	79.0	7.9	203	2.48	48.0	3.6	1.0	30	6.4	19.5	0.1	137	0.33	0.108	6
1283946	Soil	9.1	13.7	5.7	108	<0.1	21.5	2.3	36	1.01	12.3	0.8	<0.1	6	0.2	5.6	<0.1	57	0.06	0.063	2
1283947	Soil	14.2	28.8	11.5	309	0.2	54.3	6.4	97	2.48	36.6	1.1	0.2	8	0.9	15.7	0.1	107	0.07	0.079	3
1283948	Soil	8.6	31.3	8.1	249	<0.1	62.8	6.2	62	1.62	27.2	0.6	0.1	9	0.3	14.2	0.1	58	0.07	0.083	3
1283949	Soil	8.0	34.5	14.5	302	0.2	57.5	6.6	73	2.03	29.0	1.0	0.1	7	0.3	17.6	0.2	61	0.04	0.148	3
1283950	Soil	9.6	37.1	13.8	137	0.3	51.2	7.4	148	2.55	26.5	1.2	0.3	14	0.4	8.9	0.2	58	0.09	0.145	5
1287801	Soil	1.8	18.9	14.8	81	<0.1	17.3	7.0	188	2.21	8.8	0.5	0.2	10	<0.1	1.0	0.2	23	0.03	0.086	4
1287802	Soil	0.9	18.1	6.7	70	<0.1	22.0	8.9	172	1.68	7.9	1.0	0.2	9	<0.1	1.0	0.2	16	0.02	0.070	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283923	Soil	18	0.25	1497	0.003	3	0.94	0.005	0.10	0.2	0.42	2.8	0.2	0.08	3	3.9	<0.2
1283924	Soil	18	0.23	1687	0.003	3	0.98	0.006	0.08	0.1	0.46	2.7	0.2	0.09	3	5.0	<0.2
1283925	Soil	11	0.11	869	0.004	2	0.59	0.013	0.04	0.1	0.20	1.3	0.1	0.12	2	4.2	<0.2
1283926	Soil	14	0.07	206	0.002	1	0.38	0.003	0.03	0.1	0.08	2.3	0.3	<0.05	1	2.2	<0.2
1283927	Soil	12	0.02	213	0.003	1	0.45	0.007	0.05	<0.1	0.02	0.3	0.1	0.05	2	1.0	<0.2
1283928	Soil	16	0.04	482	0.002	1	0.56	0.004	0.06	<0.1	0.02	0.4	0.2	0.05	2	1.3	<0.2
1283929	Soil	13	0.03	577	0.005	2	0.52	0.011	0.05	<0.1	0.02	0.7	0.1	0.08	2	1.2	<0.2
1283930	Soil	11	0.03	478	0.003	2	0.42	0.005	0.06	<0.1	0.03	0.8	0.1	0.08	2	1.2	<0.2
1283931	Soil	5	0.01	46	0.004	<1	0.24	0.016	0.02	<0.1	0.02	0.5	<0.1	<0.05	<1	<0.5	<0.2
1283932	Soil	14	0.03	214	0.003	3	0.45	0.007	0.05	<0.1	0.04	0.7	0.2	<0.05	2	2.7	<0.2
1283933	Soil	9	0.13	296	0.006	3	0.46	0.022	0.02	<0.1	0.10	1.0	0.1	0.07	1	0.9	<0.2
1283934	Soil	11	0.02	98	0.003	2	0.38	0.016	0.03	<0.1	0.02	0.3	<0.1	<0.05	1	1.1	<0.2
1283935	Soil	15	0.03	177	0.004	2	0.32	0.008	0.05	<0.1	0.03	1.2	0.2	0.07	1	1.8	<0.2
1283936	Soil	11	0.02	179	0.002	1	0.34	0.009	0.03	<0.1	0.04	0.4	0.7	0.05	1	1.2	<0.2
1283937	Soil	17	0.04	166	0.002	1	0.39	0.004	0.05	<0.1	0.04	0.7	0.6	0.05	2	1.3	<0.2
1283938	Soil	18	0.10	236	0.004	2	0.58	0.007	0.08	0.1	0.05	3.7	0.3	0.05	2	1.2	<0.2
1283939	Soil	12	0.06	182	0.004	2	0.53	0.015	0.05	<0.1	0.08	3.9	0.2	<0.05	2	0.9	<0.2
1283940	Soil	18	0.04	210	0.002	2	0.48	0.001	0.03	<0.1	0.10	2.3	0.1	<0.05	<1	3.2	<0.2
1283941	Soil	13	3.06	1333	0.004	6	0.21	0.014	0.04	<0.1	0.06	2.8	0.2	<0.05	<1	1.3	<0.2
1283942	Soil	13	2.00	750	0.003	3	0.19	0.008	0.05	<0.1	0.63	5.2	0.6	<0.05	<1	1.9	<0.2
1283943	Soil	15	0.50	417	0.006	3	0.42	0.010	0.04	<0.1	0.12	3.9	0.3	0.06	1	1.6	<0.2
1283944	Soil	13	0.51	287	0.005	3	0.34	0.012	0.04	<0.1	0.53	5.0	0.4	0.06	<1	3.3	<0.2
1283945	Soil	18	0.09	308	0.003	1	0.40	0.004	0.04	<0.1	0.29	4.5	0.2	<0.05	1	1.9	<0.2
1283946	Soil	8	0.03	85	0.003	<1	0.46	0.015	0.03	<0.1	0.03	0.5	0.2	<0.05	1	0.6	<0.2
1283947	Soil	13	0.03	106	0.003	<1	0.45	0.010	0.03	<0.1	0.06	0.9	0.2	<0.05	2	2.2	<0.2
1283948	Soil	15	0.03	88	0.002	<1	0.33	0.008	0.03	<0.1	0.02	0.5	0.1	<0.05	1	2.3	<0.2
1283949	Soil	14	0.03	86	0.004	1	0.44	0.010	0.03	<0.1	0.07	0.5	0.2	<0.05	2	2.7	<0.2
1283950	Soil	17	0.03	103	0.003	1	0.46	0.009	0.03	<0.1	0.05	1.2	0.1	<0.05	1	1.5	<0.2
1287801	Soil	17	0.09	64	0.009	<1	0.66	0.010	0.05	<0.1	0.03	0.6	<0.1	0.05	3	<0.5	<0.2
1287802	Soil	13	0.05	39	0.002	<1	0.65	0.011	0.04	<0.1	0.02	0.7	0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287803	Soil	1.0	15.1	11.7	84	0.1	20.4	11.8	261	1.64	8.7	0.9	0.2	9	<0.1	1.2	0.1	14	0.04	0.068	2
1287804	Soil	0.4	7.2	1.8	9	0.2	3.0	1.8	315	0.38	1.2	<0.5	<0.1	7	0.1	0.2	<0.1	7	0.04	0.035	2
1287805	Soil	1.4	27.1	12.1	93	<0.1	35.1	14.1	233	2.36	34.6	0.6	0.5	11	<0.1	2.5	0.3	17	0.04	0.056	2
1287806	Soil	1.3	16.9	10.2	69	<0.1	18.2	7.5	118	1.40	9.5	<0.5	0.2	6	0.3	0.8	0.1	20	0.02	0.066	3
1287807	Soil	1.3	19.8	8.9	51	<0.1	20.6	7.8	103	1.48	13.9	<0.5	<0.1	8	<0.1	0.8	0.2	18	0.03	0.084	2
1287808	Soil	0.6	12.5	5.7	22	<0.1	9.5	3.7	413	0.60	3.7	<0.5	0.1	12	0.2	0.6	<0.1	8	0.17	0.079	2
1287809	Soil	2.9	29.4	42.5	158	0.2	54.3	25.8	1012	3.22	30.7	<0.5	2.6	34	0.3	2.3	0.4	25	0.55	0.105	7
1287810	Soil	6.7	15.9	12.9	88	0.2	25.0	4.6	77	1.58	18.1	0.8	0.4	9	0.1	4.5	0.2	47	0.03	0.033	7
1286351	Soil	12.7	19.2	6.9	121	0.3	32.7	7.1	148	1.70	74.1	2.7	0.1	10	0.4	17.9	<0.1	58	0.07	0.075	3
1286352	Soil	17.4	36.6	7.4	192	0.2	51.0	12.8	250	2.29	85.4	5.9	0.2	9	1.0	32.1	0.1	94	0.09	0.070	4
1286353	Soil	40.3	49.9	13.3	457	0.5	104.5	15.5	369	3.47	67.7	9.0	0.5	25	2.6	37.8	0.2	221	0.32	0.080	6
1286354	Soil	42.2	43.0	12.7	431	0.2	99.1	11.2	385	2.95	60.3	2.9	0.6	27	3.1	27.0	0.1	159	0.37	0.098	7
1286355	Soil	13.1	24.8	6.4	163	0.3	40.4	7.2	207	1.36	46.2	3.6	0.1	16	1.2	13.7	<0.1	68	0.15	0.042	3
1286356	Soil	22.0	44.6	12.1	356	0.4	75.6	14.2	298	2.79	95.3	4.7	0.4	35	3.3	31.8	0.1	136	0.47	0.094	4
1286357	Soil	22.7	27.6	11.8	413	0.1	62.8	7.1	62	2.19	36.2	1.9	0.2	12	0.7	20.8	0.2	141	0.13	0.079	3
1286358	Soil	14.1	44.7	24.2	382	0.5	68.6	8.4	189	2.35	34.7	1.0	0.3	54	2.4	18.4	0.2	95	0.23	0.117	5
1286359	Soil	28.8	63.0	23.2	677	0.8	125.5	13.0	375	2.81	50.9	2.9	0.8	55	6.5	27.0	0.2	138	0.43	0.143	7
1286360	Soil	2.2	13.6	9.6	101	<0.1	17.5	7.5	123	2.61	12.9	0.7	0.9	6	0.1	1.6	0.2	44	0.02	0.046	4
1286361	Soil	2.5	18.8	13.3	83	<0.1	21.6	10.8	220	1.85	11.6	1.2	1.8	16	0.4	1.1	0.2	27	0.10	0.024	5
1286362	Soil	2.5	34.6	19.5	115	0.3	39.6	11.3	190	1.99	11.3	1.2	1.5	38	0.4	1.5	0.2	25	0.40	0.036	5
1286363	Soil	3.5	45.6	19.6	119	0.3	49.3	12.2	274	2.39	13.9	0.8	1.7	70	0.7	2.0	0.2	36	0.79	0.058	6
1286364	Soil	3.6	47.4	17.6	103	0.7	48.3	11.6	367	2.10	14.8	1.2	1.1	94	0.6	2.7	0.2	32	1.26	0.074	5
1286365	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286366	Soil	2.6	16.4	11.4	74	0.1	22.7	3.6	92	1.80	10.4	<0.5	1.6	28	0.7	1.2	0.2	36	0.19	0.024	6
1286367	Soil	3.4	17.2	13.1	79	0.3	25.3	4.6	82	2.32	14.2	2.5	1.8	20	0.1	2.2	0.2	35	0.04	0.034	5
1286368	Soil	4.1	22.8	16.0	92	0.1	28.1	4.2	70	2.18	15.0	0.9	1.9	34	0.2	2.7	0.2	31	0.07	0.031	6
1286369	Soil	3.7	26.5	12.4	94	0.5	34.3	5.9	146	1.82	12.1	2.3	1.2	85	0.2	2.7	0.2	35	0.87	0.058	3
1286370	Soil	1.9	3.7	2.7	16	0.3	4.0	0.5	10	0.21	1.5	<0.5	0.3	6	<0.1	1.2	<0.1	39	0.02	0.010	2
1284401	Soil	69.6	59.8	51.1	867	0.3	133.3	16.2	367	4.72	100.9	38.4	0.3	34	1.6	34.8	0.3	159	0.13	0.130	5
1284402	Soil	2.1	30.8	29.3	94	1.3	27.1	8.2	137	3.64	20.9	3.0	2.0	29	<0.1	0.8	0.3	51	0.03	0.075	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287803	Soil	14	0.14	62	0.004	<1	0.69	0.014	0.04	<0.1	0.02	0.8	0.2	<0.05	2	<0.5	<0.2
1287804	Soil	4	0.02	43	0.005	<1	0.47	0.023	0.02	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2
1287805	Soil	12	0.03	108	0.005	<1	0.36	0.004	0.06	<0.1	0.01	1.8	0.1	<0.05	1	<0.5	<0.2
1287806	Soil	13	0.02	89	0.003	<1	0.46	0.012	0.03	<0.1	0.02	1.1	<0.1	<0.05	1	<0.5	<0.2
1287807	Soil	14	0.02	64	0.006	<1	0.38	0.008	0.04	<0.1	0.02	0.9	<0.1	0.05	2	<0.5	<0.2
1287808	Soil	6	0.03	103	0.003	<1	0.32	0.020	0.04	<0.1	0.02	0.5	<0.1	0.06	1	<0.5	<0.2
1287809	Soil	21	0.13	349	0.004	3	0.70	0.008	0.15	<0.1	0.05	5.5	0.2	0.12	2	<0.5	<0.2
1287810	Soil	15	0.06	92	0.010	<1	0.45	0.005	0.05	0.1	0.02	0.8	0.1	<0.05	3	<0.5	<0.2
1286351	Soil	18	0.04	163	0.002	2	0.49	0.014	0.04	0.1	0.03	1.2	0.2	<0.05	2	<0.5	<0.2
1286352	Soil	20	0.04	224	0.002	1	0.52	0.012	0.04	<0.1	0.09	2.6	0.2	<0.05	2	0.5	<0.2
1286353	Soil	36	0.08	479	0.004	3	0.47	0.011	0.06	0.1	0.25	5.5	0.4	<0.05	1	1.1	<0.2
1286354	Soil	23	0.09	414	0.004	<1	0.59	0.010	0.04	<0.1	0.18	4.8	0.3	<0.05	1	0.6	<0.2
1286355	Soil	13	0.03	206	0.003	<1	0.37	0.026	0.03	<0.1	0.15	2.2	0.2	<0.05	1	<0.5	<0.2
1286356	Soil	28	0.07	342	0.003	1	0.47	0.012	0.05	<0.1	0.24	4.8	0.2	<0.05	1	2.0	<0.2
1286357	Soil	14	0.06	118	0.002	<1	0.31	0.005	0.04	<0.1	0.03	0.6	0.2	<0.05	1	2.2	<0.2
1286358	Soil	18	0.03	254	0.004	1	0.38	0.007	0.05	<0.1	0.16	1.5	0.2	<0.05	1	2.1	<0.2
1286359	Soil	24	0.09	754	0.004	2	0.36	0.005	0.07	<0.1	0.51	3.3	0.4	<0.05	<1	2.8	<0.2
1286360	Soil	19	0.15	64	0.007	<1	0.73	0.011	0.05	<0.1	0.02	1.2	<0.1	<0.05	4	<0.5	<0.2
1286361	Soil	23	0.28	235	0.006	2	0.81	0.009	0.06	0.1	0.03	1.4	0.1	<0.05	3	<0.5	<0.2
1286362	Soil	21	0.29	824	0.002	2	0.90	0.013	0.07	<0.1	0.07	2.4	0.2	<0.05	2	0.9	<0.2
1286363	Soil	27	0.41	507	0.004	2	1.23	0.013	0.08	<0.1	0.14	3.3	0.2	<0.05	3	1.9	<0.2
1286364	Soil	21	0.37	484	0.003	3	1.04	0.012	0.08	<0.1	0.16	2.8	0.2	0.09	3	2.9	<0.2
1286365	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286366	Soil	17	0.18	378	0.005	<1	0.63	0.007	0.05	<0.1	0.02	1.3	<0.1	<0.05	3	0.6	<0.2
1286367	Soil	24	0.22	966	0.007	<1	0.82	0.004	0.06	<0.1	0.05	1.8	<0.1	<0.05	3	0.7	<0.2
1286368	Soil	17	0.22	1369	0.001	<1	0.65	0.003	0.06	<0.1	0.04	1.7	0.2	<0.05	2	1.3	<0.2
1286369	Soil	23	0.30	1390	0.003	3	0.75	0.010	0.08	<0.1	0.07	2.0	0.2	0.10	2	2.7	<0.2
1286370	Soil	7	0.02	359	0.002	1	0.23	0.009	0.03	<0.1	<0.01	0.3	0.2	<0.05	1	<0.5	<0.2
1284401	Soil	27	0.09	154	0.004	1	0.45	0.003	0.05	0.2	0.51	2.0	0.4	<0.05	2	2.0	<0.2
1284402	Soil	31	0.13	273	0.002	<1	1.24	0.007	0.08	<0.1	0.14	2.6	0.1	<0.05	4	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1284403	Soil	1.2	24.0	9.6	37	1.4	13.2	2.5	42	1.17	5.4	1.4	0.7	12	0.1	0.6	0.2	29	0.03	0.054	3
1284404	Soil	2.1	40.0	22.8	85	1.7	29.8	45.9	2162	3.19	18.1	3.1	1.4	21	0.2	1.2	0.3	42	0.03	0.096	3
1284405	Soil	1.6	16.6	14.9	30	1.4	11.8	1.8	50	1.16	8.1	1.1	0.4	11	0.1	0.5	0.2	36	0.02	0.060	2
1284406	Soil	1.6	48.0	19.4	41	1.5	11.3	1.9	65	2.24	12.8	1.4	0.6	10	0.1	0.6	0.2	42	0.02	0.074	3
1284407	Soil	0.4	11.0	4.3	13	0.8	5.9	0.7	19	0.47	3.0	1.1	<0.1	8	<0.1	0.7	<0.1	11	0.03	0.043	2
1284408	Soil	1.3	52.4	29.8	86	0.9	22.1	5.9	148	3.71	20.5	5.9	1.8	36	<0.1	1.0	0.3	45	0.02	0.078	3
1284409	Soil	0.2	2.8	1.3	4	0.5	2.5	0.4	17	0.17	<0.5	<0.5	<0.1	7	<0.1	0.2	<0.1	3	0.03	0.025	<1
1284410	Soil	2.5	32.4	24.6	112	0.8	28.7	9.4	390	2.91	20.1	3.2	1.8	20	0.2	1.7	0.3	50	0.02	0.054	5
1284411	Soil	4.6	44.4	21.4	161	0.5	41.7	12.5	208	2.94	24.5	3.5	3.6	21	0.4	2.7	0.3	49	0.04	0.061	6
1284412	Soil	3.2	25.3	15.5	111	0.2	25.3	5.4	84	2.29	18.3	1.9	0.9	15	0.2	2.0	0.2	43	0.02	0.060	3
1284413	Soil	1.1	12.6	14.8	54	0.4	13.6	3.0	79	1.40	7.5	1.0	0.6	11	0.2	0.6	0.2	35	0.02	0.056	2
1284414	Soil	0.6	6.3	4.5	44	0.8	7.5	3.4	102	0.65	2.7	<0.5	0.3	6	0.1	0.3	<0.1	17	0.02	0.026	2
1284415	Soil	0.3	3.6	4.2	38	0.3	5.1	2.9	65	0.54	3.1	<0.5	0.3	9	<0.1	0.2	<0.1	14	0.04	0.021	1
1284416	Soil	1.3	13.1	16.4	82	0.7	14.7	5.4	89	1.42	9.8	1.2	0.9	11	<0.1	0.9	0.1	34	0.02	0.037	4
1284417	Soil	0.9	11.0	10.9	147	0.3	14.7	7.9	139	2.31	9.1	<0.5	0.8	15	0.3	0.6	0.2	41	0.05	0.066	3
1284418	Soil	2.0	11.1	10.3	46	0.6	10.5	2.3	36	1.11	9.6	0.7	0.4	10	0.2	1.5	0.1	39	0.02	0.035	2
1284419	Soil	2.3	9.7	8.7	35	0.3	9.6	1.8	31	1.00	10.2	1.7	0.3	10	0.1	1.7	0.1	37	0.03	0.035	5
1284420	Soil	2.4	13.6	9.8	58	0.9	10.5	2.4	43	1.27	12.1	1.0	0.6	11	0.5	1.7	0.1	32	0.02	0.038	5
1282961	Soil	6.4	74.5	72.2	222	0.8	69.9	14.8	264	4.16	54.2	5.9	1.1	75	1.0	15.2	0.3	39	0.10	0.141	11
1282962	Soil	1.7	4.1	12.7	19	2.9	6.3	0.7	15	0.31	11.1	<0.5	<0.1	9	<0.1	2.6	<0.1	11	0.02	0.030	1
1282963	Soil	17.3	71.1	128.5	496	0.7	75.6	10.4	260	3.38	228.1	18.8	0.7	58	0.6	48.0	0.3	73	0.17	0.125	3
1282964	Soil	53.4	66.4	36.7	364	1.8	113.3	14.6	256	4.38	30.8	4.9	2.4	41	1.2	14.2	0.2	64	0.41	0.098	9
1282965	Soil	10.2	57.4	31.8	382	0.8	75.6	10.6	195	2.70	33.2	3.8	0.9	48	1.8	9.6	0.2	62	0.34	0.114	6
1282966	Soil	8.7	37.5	61.9	197	0.4	47.1	7.7	108	2.24	76.1	3.7	0.7	28	0.4	14.2	0.2	58	0.06	0.077	5
1282967	Soil	4.6	10.7	14.5	47	0.9	17.0	2.1	28	0.63	15.7	1.6	<0.1	11	0.2	3.7	<0.1	28	0.04	0.059	2
1282968	Soil	11.7	40.3	25.4	403	0.8	83.9	9.7	178	2.22	34.3	5.6	1.3	95	2.8	14.6	0.2	70	0.79	0.150	5
1282969	Soil	15.4	103.9	34.2	398	1.3	132.2	14.4	435	3.57	89.8	1.5	1.9	99	4.7	44.4	0.2	57	3.04	0.058	4
1282970	Soil	0.4	4.6	3.3	10	0.4	3.9	0.8	20	0.34	1.4	1.5	<0.1	7	<0.1	0.2	<0.1	6	0.03	0.037	<1
1282971	Soil	2.6	19.5	16.1	84	0.4	16.0	3.9	102	2.76	18.0	2.4	1.1	19	0.3	1.0	0.2	54	0.04	0.073	5
1282972	Soil	2.7	31.4	17.5	125	0.4	30.8	9.3	151	3.14	19.9	3.2	2.0	17	0.2	1.1	0.2	44	0.03	0.056	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284403	Soil	12	0.03	501	0.004	<1	0.69	0.017	0.04	0.1	0.05	1.3	<0.1	<0.05	3	<0.5	<0.2
1284404	Soil	29	0.13	224	0.003	1	1.21	0.010	0.07	<0.1	0.09	1.8	0.1	0.07	3	1.3	<0.2
1284405	Soil	20	0.03	159	0.002	<1	0.51	0.013	0.06	0.1	0.02	0.7	<0.1	<0.05	3	<0.5	<0.2
1284406	Soil	23	0.04	199	0.004	<1	0.73	0.012	0.05	<0.1	0.06	0.9	<0.1	<0.05	3	0.8	<0.2
1284407	Soil	10	0.02	75	0.004	<1	0.35	0.023	0.03	<0.1	0.02	0.3	<0.1	<0.05	1	<0.5	<0.2
1284408	Soil	31	0.14	502	0.002	<1	0.97	0.010	0.09	<0.1	0.10	5.0	0.1	0.06	3	3.0	0.2
1284409	Soil	4	0.01	77	0.004	<1	0.17	0.032	0.03	<0.1	<0.01	0.3	<0.1	<0.05	<1	<0.5	<0.2
1284410	Soil	28	0.16	635	0.003	1	1.14	0.009	0.08	<0.1	0.08	2.9	0.2	<0.05	3	<0.5	<0.2
1284411	Soil	29	0.26	677	0.003	<1	1.22	0.007	0.08	0.2	0.13	4.0	0.2	<0.05	4	1.5	<0.2
1284412	Soil	20	0.11	310	0.002	<1	0.78	0.007	0.06	<0.1	0.05	1.6	<0.1	<0.05	2	1.0	<0.2
1284413	Soil	18	0.06	192	0.002	<1	0.63	0.010	0.06	<0.1	0.02	0.9	<0.1	<0.05	3	<0.5	<0.2
1284414	Soil	11	0.04	250	0.004	<1	0.50	0.019	0.03	<0.1	0.02	0.6	<0.1	<0.05	2	<0.5	<0.2
1284415	Soil	8	0.05	300	0.005	2	0.43	0.019	0.03	<0.1	<0.01	0.6	<0.1	<0.05	2	<0.5	<0.2
1284416	Soil	21	0.10	396	0.003	3	1.03	0.008	0.05	<0.1	0.03	1.8	<0.1	0.05	3	<0.5	<0.2
1284417	Soil	19	0.15	477	0.002	2	1.01	0.007	0.06	<0.1	0.02	1.6	<0.1	0.06	4	<0.5	<0.2
1284418	Soil	12	0.02	176	0.002	2	0.44	0.007	0.04	<0.1	0.01	0.9	<0.1	0.05	2	<0.5	<0.2
1284419	Soil	13	0.03	160	0.011	3	0.47	0.005	0.03	0.1	<0.01	0.8	0.1	0.06	3	<0.5	<0.2
1284420	Soil	10	0.04	195	0.006	2	0.40	0.007	0.04	<0.1	0.02	1.0	<0.1	<0.05	2	0.5	<0.2
1282961	Soil	12	0.03	512	0.003	3	0.41	0.006	0.04	<0.1	0.08	3.4	0.1	<0.05	1	1.3	<0.2
1282962	Soil	8	0.01	39	0.003	2	0.10	0.018	0.02	0.1	0.02	0.3	<0.1	<0.05	<1	<0.5	<0.2
1282963	Soil	27	0.05	435	0.007	5	0.46	<0.001	0.05	<0.1	0.20	3.7	0.3	0.09	1	2.3	<0.2
1282964	Soil	17	0.07	476	0.003	3	0.30	<0.001	0.05	<0.1	0.51	6.6	0.3	<0.05	<1	2.6	<0.2
1282965	Soil	23	0.07	766	0.004	5	0.42	<0.001	0.05	<0.1	0.15	3.4	0.2	0.09	1	3.0	<0.2
1282966	Soil	14	0.03	232	0.005	5	0.30	<0.001	0.05	0.1	0.03	1.9	0.2	0.05	1	1.8	<0.2
1282967	Soil	12	0.03	102	0.002	1	0.21	0.013	0.03	<0.1	0.06	0.3	<0.1	<0.05	1	<0.5	<0.2
1282968	Soil	28	0.14	456	0.005	4	0.34	<0.001	0.06	<0.1	0.21	5.1	0.2	0.11	1	1.2	<0.2
1282969	Soil	24	1.52	279	0.002	4	0.17	<0.001	0.05	<0.1	0.71	5.9	0.4	0.35	<1	9.8	<0.2
1282970	Soil	6	0.02	65	0.004	<1	0.25	0.029	0.03	<0.1	0.02	0.4	<0.1	0.05	1	<0.5	<0.2
1282971	Soil	22	0.11	211	0.005	2	0.86	<0.001	0.06	0.1	0.05	1.8	<0.1	0.09	4	<0.5	<0.2
1282972	Soil	28	0.26	274	0.003	1	1.09	0.001	0.05	<0.1	0.03	2.7	<0.1	<0.05	3	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1282973	Soil	1.6	19.9	14.4	95	0.2	25.3	7.3	136	1.93	12.2	0.9	1.0	18	0.1	0.6	0.2	35	0.03	0.056	4
1282974	Soil	5.3	31.5	15.4	150	0.5	36.4	9.3	242	2.23	15.8	4.4	1.2	29	0.6	2.1	0.2	58	0.16	0.082	8
1282975	Soil	4.0	32.9	10.7	162	0.3	40.3	12.6	392	2.26	12.7	4.7	3.4	33	0.9	1.9	0.2	48	0.28	0.092	14
1282976	Soil	1.3	14.4	9.5	42	0.3	11.6	2.9	79	1.24	7.3	1.4	0.2	11	<0.1	0.6	0.1	27	0.03	0.061	4
1282977	Soil	1.4	28.9	16.4	106	0.2	22.9	9.3	154	2.62	16.4	3.4	1.7	20	0.1	0.7	0.2	34	0.02	0.053	4
1282978	Soil	1.5	21.7	19.6	86	0.4	22.4	7.5	91	2.43	14.9	1.9	0.7	14	<0.1	0.7	0.2	31	0.03	0.069	3
1282979	Soil	1.2	18.1	8.9	28	0.2	10.4	2.0	27	0.64	4.4	2.2	0.2	12	0.2	0.4	0.1	23	0.03	0.046	5
1282980	Soil	1.8	13.6	10.9	54	0.3	9.8	3.3	58	1.30	9.0	2.1	0.4	10	<0.1	0.8	0.2	40	0.01	0.037	6
1282981	Soil	1.3	9.5	8.9	38	0.2	7.7	2.3	47	0.96	7.2	1.4	0.3	9	<0.1	0.6	0.1	32	0.02	0.038	6
1282982	Soil	1.8	17.6	17.5	71	0.7	15.1	4.9	162	3.24	17.6	1.3	0.7	14	<0.1	1.0	0.3	56	0.02	0.113	3
1282983	Soil	0.9	10.2	6.4	33	0.7	7.6	2.3	40	1.12	6.5	1.6	0.8	8	<0.1	0.6	0.1	27	0.01	0.023	3
1282984	Soil	1.5	43.2	24.8	131	1.1	21.1	6.6	119	4.35	23.9	3.6	1.3	22	0.1	1.0	0.3	50	0.04	0.091	2
1282985	Soil	0.9	10.3	11.6	63	0.2	9.4	3.2	62	1.45	8.8	2.3	1.1	10	0.2	0.7	0.2	33	0.01	0.033	4
1282986	Soil	0.9	15.9	10.6	60	0.3	9.5	2.8	50	1.28	6.4	0.7	0.7	11	0.3	0.4	0.2	30	0.02	0.061	3
1282987	Soil	2.0	22.1	13.6	103	0.1	22.3	7.8	141	2.51	16.4	2.0	1.5	15	0.2	0.9	0.2	40	0.02	0.048	4
1282988	Soil	1.0	13.5	12.3	56	0.7	15.1	6.6	181	1.19	6.5	2.5	0.5	12	0.1	0.5	0.2	23	0.02	0.063	2
1282989	Soil	1.3	16.1	13.8	60	0.3	13.7	4.9	78	1.87	8.9	1.2	0.6	9	<0.1	0.6	0.2	39	0.01	0.064	3
1282990	Soil	1.4	13.2	11.0	41	0.2	8.0	2.2	38	1.88	11.7	0.9	0.2	13	<0.1	0.7	0.2	31	0.03	0.103	2
1282991	Soil	1.0	10.9	9.4	32	0.2	6.1	1.8	25	1.08	6.8	1.3	0.3	7	<0.1	0.5	0.2	37	0.02	0.034	2
1282992	Soil	1.2	18.0	19.4	52	1.8	11.2	3.0	75	2.03	12.3	2.0	0.5	14	0.2	0.6	0.3	40	0.04	0.094	2
1282993	Soil	0.9	16.7	18.8	43	0.5	6.5	1.5	26	1.66	11.2	0.5	0.9	13	0.2	0.4	0.2	43	0.01	0.088	2
1282994	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1282995	Soil	4.5	33.0	25.8	118	1.1	24.5	6.7	111	3.77	23.3	3.7	1.8	50	0.5	1.8	0.3	49	0.03	0.215	4
1282996	Soil	1.1	10.5	5.1	20	1.1	10.6	1.4	17	0.56	2.5	1.2	<0.1	11	0.3	0.4	<0.1	19	0.03	0.068	1
1282997	Soil	8.1	29.8	21.6	62	2.9	17.2	3.8	86	2.31	21.2	2.4	1.7	41	0.3	2.6	0.2	73	0.14	0.322	6
1282998	Soil	0.5	3.6	1.7	6	3.4	1.9	0.6	16	0.29	1.2	<0.5	<0.1	6	<0.1	0.2	<0.1	11	0.03	0.027	<1
1282999	Soil	2.7	9.2	8.0	29	0.7	6.1	1.7	25	0.81	6.4	1.0	<0.1	13	0.1	1.0	<0.1	29	0.02	0.062	2
1283000	Soil	1.7	14.6	11.4	121	0.3	15.9	6.3	130	2.01	10.2	0.5	0.3	8	2.0	1.1	0.2	40	0.02	0.078	3
1278951	Soil	10.8	22.4	6.3	129	0.2	23.6	3.2	38	1.11	10.8	0.7	0.2	9	0.4	3.2	0.1	99	0.02	0.036	12
1278952	Soil	14.3	40.6	17.0	246	0.8	38.9	5.7	164	1.85	20.8	1.9	0.3	31	1.5	5.5	0.3	125	0.14	0.123	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1282973	Soil	20	0.13	168	0.002	2	0.71	0.006	0.04	<0.1	0.03	1.9	<0.1	<0.05	2	<0.5	<0.2
1282974	Soil	27	0.24	596	0.018	5	0.88	0.003	0.10	0.1	0.15	2.3	0.2	0.06	3	<0.5	<0.2
1282975	Soil	23	0.31	673	0.023	2	0.84	0.007	0.07	0.2	0.12	3.0	0.2	<0.05	3	<0.5	<0.2
1282976	Soil	11	0.07	213	0.005	2	0.50	0.009	0.04	<0.1	0.05	0.6	<0.1	0.08	2	<0.5	<0.2
1282977	Soil	16	0.10	202	0.002	1	0.55	0.002	0.05	<0.1	0.05	2.8	<0.1	0.05	2	0.9	<0.2
1282978	Soil	15	0.08	247	0.006	8	0.69	0.006	0.06	<0.1	0.05	2.1	0.1	0.06	2	0.7	<0.2
1282979	Soil	13	0.02	308	0.002	2	0.44	0.008	0.02	<0.1	0.01	0.6	<0.1	<0.05	2	<0.5	<0.2
1282980	Soil	9	0.03	114	0.008	1	0.49	0.004	0.04	<0.1	0.02	0.7	<0.1	<0.05	3	<0.5	<0.2
1282981	Soil	9	0.03	120	0.004	1	0.51	0.005	0.04	<0.1	0.02	0.5	<0.1	<0.05	3	<0.5	<0.2
1282982	Soil	21	0.08	154	0.003	3	0.92	0.002	0.06	<0.1	0.04	1.6	0.1	0.06	4	0.6	<0.2
1282983	Soil	11	0.04	150	0.009	3	0.60	0.008	0.03	<0.1	0.03	0.8	<0.1	<0.05	3	<0.5	<0.2
1282984	Soil	23	0.13	212	0.003	1	1.25	0.003	0.06	<0.1	0.06	2.8	<0.1	<0.05	4	1.2	0.2
1282985	Soil	14	0.06	211	0.003	2	0.65	<0.001	0.05	<0.1	0.01	1.2	<0.1	<0.05	3	<0.5	<0.2
1282986	Soil	11	0.04	223	0.002	2	0.67	0.007	0.05	<0.1	0.01	1.0	<0.1	<0.05	3	<0.5	<0.2
1282987	Soil	18	0.17	217	0.002	1	0.83	0.002	0.05	<0.1	0.03	2.0	<0.1	<0.05	3	0.9	<0.2
1282988	Soil	12	0.05	234	0.003	2	0.61	0.008	0.05	<0.1	0.09	1.3	0.1	<0.05	2	<0.5	<0.2
1282989	Soil	14	0.06	82	0.002	<1	0.56	0.007	0.04	<0.1	0.03	1.2	<0.1	<0.05	3	<0.5	<0.2
1282990	Soil	11	0.04	121	0.003	2	0.54	0.010	0.04	<0.1	0.03	0.7	<0.1	0.06	2	0.6	<0.2
1282991	Soil	9	0.02	150	0.004	2	0.45	0.011	0.03	<0.1	0.02	0.5	<0.1	<0.05	3	<0.5	<0.2
1282992	Soil	15	0.04	177	0.004	5	0.69	0.011	0.05	<0.1	0.05	1.1	<0.1	0.09	3	0.9	<0.2
1282993	Soil	12	0.04	292	0.002	1	0.78	0.006	0.06	<0.1	0.03	0.9	<0.1	<0.05	3	0.6	<0.2
1282994	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1282995	Soil	24	0.10	968	0.002	3	0.96	0.006	0.08	<0.1	0.07	2.4	0.2	0.18	3	3.6	0.2
1282996	Soil	7	0.01	387	0.003	2	0.26	0.015	0.03	<0.1	0.04	0.2	<0.1	<0.05	1	0.6	<0.2
1282997	Soil	21	0.05	891	0.004	2	0.88	0.009	0.07	<0.1	0.08	2.5	0.3	0.09	3	3.3	<0.2
1282998	Soil	4	0.01	55	0.015	<1	0.27	0.026	0.03	<0.1	0.04	0.2	<0.1	<0.05	2	0.6	<0.2
1282999	Soil	7	0.02	176	0.006	1	0.36	0.014	0.04	<0.1	0.04	0.3	0.1	<0.05	2	1.0	<0.2
1283000	Soil	12	0.05	171	0.003	1	0.53	0.009	0.06	<0.1	0.02	1.1	<0.1	<0.05	3	0.6	<0.2
1278951	Soil	12	0.02	230	0.004	2	0.23	0.004	0.04	0.1	0.03	0.4	0.2	<0.05	2	1.8	<0.2
1278952	Soil	19	0.07	836	0.005	2	0.39	0.002	0.06	0.1	0.08	0.5	0.3	<0.05	2	3.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1278953	Soil	11.5	46.8	15.9	236	0.9	40.6	8.9	310	2.11	23.8	2.6	0.3	36	2.1	5.3	0.3	120	0.26	0.133	13
1278954	Soil	15.9	33.6	18.6	203	0.6	40.7	3.9	56	1.75	24.3	1.7	0.2	15	0.5	6.3	0.3	176	0.02	0.086	15
1278955	Soil	19.6	115.6	17.7	514	1.8	88.1	13.6	387	3.26	31.8	7.8	1.5	57	5.7	11.0	0.3	149	0.25	0.229	17
1278956	Soil	14.9	103.0	17.0	435	1.7	81.4	10.5	217	3.09	28.8	9.0	1.0	61	4.4	9.1	0.3	136	0.52	0.240	15
1278957	Soil	35.1	268.6	15.9	>10000	2.0	957.5	46.4	2405	3.94	45.4	3.6	3.0	131	90.9	15.4	0.2	205	2.26	0.230	15
1278958	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1278959	Soil	1.9	46.9	13.3	158	0.9	42.3	10.9	531	1.94	11.6	7.1	1.9	82	0.5	1.0	0.2	30	0.62	0.088	6
1278960	Soil	2.0	33.8	18.7	184	0.6	44.4	15.8	611	2.84	11.2	3.6	2.9	40	0.6	0.8	0.3	35	0.28	0.088	5
1288161	Soil	2.5	16.2	13.1	71	0.2	11.7	3.4	27	2.48	16.1	1.1	0.9	6	<0.1	1.1	0.3	25	0.02	0.039	1
1288162	Soil	0.8	9.5	6.3	57	0.1	8.7	4.2	88	1.12	5.3	<0.5	0.1	9	0.5	0.4	0.1	24	0.03	0.042	2
1288163	Soil	1.4	18.3	8.4	96	0.1	21.1	8.1	91	1.97	10.1	<0.5	0.2	7	0.2	0.7	0.2	29	0.02	0.045	2
1288164	Soil	2.8	14.8	8.8	74	0.8	12.1	4.2	66	1.46	10.0	<0.5	0.1	12	0.3	1.2	0.1	41	0.02	0.054	3
1288165	Soil	4.1	12.0	7.7	62	0.2	10.9	4.1	43	1.38	15.0	0.5	0.4	8	<0.1	1.5	0.2	47	0.02	0.028	4
1288166	Soil	1.3	9.9	4.1	28	0.8	6.6	2.0	30	0.72	4.8	<0.5	0.1	6	0.1	0.6	<0.1	28	0.03	0.024	2
1288167	Soil	3.3	16.5	11.5	85	0.3	19.4	5.8	66	1.88	16.2	<0.5	0.5	6	0.3	1.8	0.2	38	0.02	0.042	3
1288168	Soil	3.9	33.2	15.7	158	<0.1	38.7	15.5	148	3.38	20.6	0.7	1.4	11	0.5	1.7	0.2	27	0.03	0.045	2
1288169	Soil	1.3	13.6	6.7	39	0.2	11.9	3.4	44	1.03	5.4	0.6	0.4	5	1.0	0.6	<0.1	22	0.02	0.043	3
1288170	Soil	1.9	19.0	13.2	129	0.1	24.6	10.4	141	2.63	13.3	1.6	0.6	8	0.8	1.1	0.2	36	0.02	0.070	3
1284101	Soil	80.2	28.8	11.3	1217	0.8	159.1	41.4	5523	2.73	34.5	3.1	1.3	46	21.8	5.5	0.2	81	0.60	0.183	7
1284102	Soil	80.3	50.2	11.5	2109	1.1	258.5	27.5	1649	4.89	58.3	4.4	2.2	60	33.1	8.9	0.2	95	0.84	0.272	9
1284103	Soil	33.8	58.4	12.6	1631	1.0	188.2	21.6	904	3.06	29.0	3.7	2.5	65	26.3	7.3	0.2	91	1.00	0.217	10
1284104	Soil	28.5	43.7	10.4	1380	0.8	144.5	14.3	722	2.65	38.1	2.6	2.2	60	11.2	6.5	0.2	99	0.79	0.238	9
1284105	Soil	22.7	43.3	10.2	731	0.7	86.5	10.6	626	2.11	34.9	2.3	1.9	65	7.3	5.5	0.2	95	0.80	0.218	8
1284106	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284107	Soil	75.7	61.4	10.6	1076	0.9	174.7	20.2	1811	4.89	51.0	4.7	1.9	67	13.3	7.3	0.2	71	1.24	0.210	8
1284108	Soil	30.9	60.0	13.5	849	1.0	111.8	13.1	622	3.20	35.8	3.9	2.9	64	13.0	5.4	0.2	91	0.80	0.173	11
1284109	Soil	26.2	62.7	16.9	748	0.8	111.9	11.6	798	2.81	41.1	6.3	3.2	59	4.0	5.3	0.3	87	0.83	0.186	13
1284110	Soil	30.0	43.0	13.7	598	0.5	77.8	9.6	489	2.21	26.4	3.3	3.6	62	3.2	4.1	0.2	79	0.79	0.180	13
1287731	Soil	1.0	6.3	3.1	24	0.8	4.5	1.7	207	0.41	1.3	<0.5	<0.1	17	0.6	0.5	<0.1	15	0.17	0.059	2
1287732	Soil	13.2	87.3	34.3	536	1.7	113.5	13.7	330	3.58	18.8	6.3	1.9	94	4.3	9.6	0.3	99	0.91	0.166	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1278953	Soil		18	0.06	1115	0.007	2	0.44	0.003	0.06	0.1	0.15	1.0	0.3	0.06	3	2.9	<0.2
1278954	Soil		20	0.03	221	0.005	3	0.45	0.002	0.05	0.2	0.04	0.4	0.3	<0.05	4	3.2	<0.2
1278955	Soil		23	0.06	2027	0.003	3	0.40	0.002	0.07	0.1	0.33	2.7	0.5	<0.05	1	5.8	<0.2
1278956	Soil		23	0.10	1448	0.005	3	0.45	0.004	0.08	0.1	0.35	2.5	0.4	0.08	2	4.3	<0.2
1278957	Soil		32	1.17	1161	0.004	5	1.96	0.004	0.07	<0.1	0.74	4.9	1.0	0.21	1	9.1	<0.2
1278958	Soil		L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1278959	Soil		28	0.33	578	0.003	3	0.99	0.007	0.05	<0.1	0.36	3.7	0.1	0.07	2	1.6	<0.2
1278960	Soil		30	0.50	384	0.001	2	1.45	0.004	0.06	<0.1	0.33	3.2	0.1	<0.05	4	1.5	<0.2
1288161	Soil		14	0.02	238	0.002	<1	0.48	0.008	0.06	<0.1	0.07	1.2	0.2	<0.05	2	0.8	<0.2
1288162	Soil		6	0.03	183	0.004	1	0.55	0.014	0.06	<0.1	0.02	0.6	<0.1	<0.05	2	<0.5	<0.2
1288163	Soil		7	0.02	93	0.004	<1	0.42	0.009	0.03	<0.1	0.02	1.5	<0.1	<0.05	2	<0.5	<0.2
1288164	Soil		7	0.02	131	0.003	<1	0.55	0.011	0.04	<0.1	0.02	0.5	<0.1	<0.05	3	0.6	<0.2
1288165	Soil		6	0.02	188	0.002	<1	0.42	0.004	0.03	<0.1	0.01	0.9	0.1	<0.05	2	<0.5	<0.2
1288166	Soil		6	0.01	128	0.008	1	0.30	0.018	0.03	<0.1	0.03	0.4	<0.1	<0.05	2	<0.5	<0.2
1288167	Soil		12	0.03	160	0.002	1	0.41	0.007	0.05	<0.1	0.04	1.5	0.1	<0.05	2	0.6	<0.2
1288168	Soil		10	0.04	260	<0.001	<1	0.40	0.003	0.06	<0.1	0.12	3.7	0.1	<0.05	1	1.1	<0.2
1288169	Soil		7	0.02	198	0.003	<1	0.54	0.014	0.04	<0.1	0.04	1.1	0.1	<0.05	2	<0.5	<0.2
1288170	Soil		13	0.09	162	0.003	<1	0.60	0.007	0.05	<0.1	0.02	1.8	0.1	<0.05	3	0.6	<0.2
1284101	Soil		18	0.15	1098	0.004	4	0.64	0.007	0.07	0.1	0.40	1.8	0.3	0.09	2	3.8	<0.2
1284102	Soil		20	0.21	1203	0.004	5	0.83	0.004	0.11	0.2	0.52	2.7	0.4	0.09	2	5.6	<0.2
1284103	Soil		20	0.24	1203	0.003	5	0.83	0.007	0.11	0.2	0.60	3.0	0.4	0.11	2	6.3	<0.2
1284104	Soil		18	0.22	937	0.004	4	0.72	0.005	0.10	0.2	0.47	2.3	0.3	0.07	2	4.7	<0.2
1284105	Soil		20	0.19	982	0.003	5	0.66	0.005	0.10	0.2	0.49	2.0	0.3	0.07	2	3.6	<0.2
1284106	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284107	Soil		19	0.19	1586	0.004	4	0.73	0.008	0.07	0.2	0.38	2.7	0.2	0.21	2	7.9	<0.2
1284108	Soil		20	0.25	1109	0.004	6	0.90	0.007	0.12	0.2	0.50	3.0	0.3	0.13	3	4.5	<0.2
1284109	Soil		23	0.29	1253	0.006	9	1.00	0.008	0.18	0.2	0.43	3.7	0.3	0.16	3	5.5	<0.2
1284110	Soil		24	0.29	1490	0.007	8	0.97	0.009	0.16	0.3	0.37	2.8	0.3	0.18	3	5.1	<0.2
1287731	Soil		3	0.03	81	0.014	1	0.64	0.039	0.03	<0.1	0.04	0.7	<0.1	<0.05	2	0.5	<0.2
1287732	Soil		25	0.19	550	0.003	4	0.40	0.004	0.09	<0.1	0.29	6.1	0.3	<0.05	1	6.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287733	Soil	12.9	86.8	31.3	545	1.5	100.2	8.9	202	2.69	15.9	4.7	1.8	116	5.3	8.8	0.2	96	1.15	0.214	4
1287734	Soil	14.0	85.1	35.2	652	1.4	98.8	9.6	273	2.79	20.0	3.3	2.4	106	7.4	10.0	0.2	115	1.11	0.204	4
1287735	Soil	16.0	99.3	45.1	574	1.4	103.6	8.9	244	2.83	21.2	3.4	2.0	94	6.0	11.7	0.2	99	0.74	0.191	4
1287736	Soil	2.6	38.9	11.8	189	0.3	42.7	10.9	332	2.44	7.2	0.6	0.3	10	0.5	2.9	0.2	25	0.09	0.087	3
1287737	Soil	7.2	58.1	31.0	165	0.4	82.7	19.7	588	5.38	16.1	2.9	0.9	47	0.3	4.8	0.3	42	0.82	0.099	6
1287738	Soil	1.1	8.5	4.4	28	0.1	7.9	2.1	63	0.64	2.0	1.0	<0.1	10	0.1	0.6	<0.1	10	0.09	0.052	2
1287739	Soil	3.3	79.9	29.1	322	1.1	118.6	36.4	1055	8.94	21.1	9.4	1.7	46	0.5	6.0	0.6	27	0.28	0.093	9
1287740	Soil	17.9	26.1	22.6	104	0.9	25.7	3.5	50	1.48	15.1	3.3	0.3	20	0.3	4.0	0.2	65	0.02	0.077	6
1287741	Soil	11.4	15.7	25.2	116	0.7	25.8	5.0	174	3.49	24.2	4.3	0.9	19	0.4	6.0	0.2	95	0.09	0.186	9
1287742	Soil	25.9	20.9	21.4	190	0.2	45.2	5.4	70	1.61	25.9	1.2	0.3	16	0.2	7.6	0.2	113	0.01	0.036	8
1287743	Soil	1.9	6.6	5.2	27	0.4	7.5	1.9	58	0.49	3.1	0.6	<0.1	18	0.3	0.8	<0.1	19	0.06	0.034	1
1287744	Soil	6.2	15.1	12.3	70	0.4	20.4	5.7	121	1.12	10.4	0.8	0.1	12	0.2	1.6	0.1	38	0.02	0.042	4
1287745	Soil	16.3	30.5	25.2	185	0.2	45.3	11.9	220	2.80	27.2	1.0	1.2	27	0.3	4.9	0.2	70	0.05	0.076	7
1287746	Soil	7.5	23.1	22.0	123	0.1	28.7	9.7	131	2.89	23.8	2.1	0.4	20	0.2	2.6	0.3	60	0.02	0.089	6
1287747	Soil	5.4	23.8	21.5	114	0.2	25.3	9.0	160	2.67	24.4	1.7	0.8	34	0.3	2.3	0.2	43	0.03	0.048	7
1287748	Soil	0.9	11.7	11.5	56	0.1	13.9	6.0	66	0.90	5.9	0.8	0.5	14	<0.1	0.4	0.2	14	0.08	0.031	3
1287749	Soil	1.6	15.4	10.9	62	<0.1	13.3	6.4	98	1.48	9.5	<0.5	0.3	8	<0.1	0.8	0.2	30	0.02	0.036	6
1287750	Soil	2.5	19.4	19.8	119	0.1	26.6	10.9	213	2.40	13.8	1.3	0.2	17	<0.1	1.4	0.2	22	0.02	0.075	3
1287751	Soil	0.7	10.0	9.2	54	<0.1	12.4	8.5	256	1.13	5.6	0.6	0.2	12	0.1	0.5	<0.1	12	0.03	0.046	2
1287752	Soil	2.2	24.4	35.0	128	0.1	31.6	15.2	344	3.21	18.1	1.2	1.1	32	<0.1	1.5	0.3	24	0.02	0.065	6
1287753	Soil	2.1	30.2	40.9	209	0.1	54.4	21.8	474	3.76	20.2	1.3	1.5	42	0.1	3.3	0.2	13	0.03	0.042	3
1287754	Soil	2.3	20.6	13.0	75	<0.1	14.7	6.9	174	2.26	13.0	0.6	0.2	8	0.2	1.1	0.2	40	0.04	0.059	5
1287755	Soil	1.9	19.6	27.7	111	0.3	28.0	18.6	1098	3.29	23.0	<0.5	0.2	17	0.4	1.4	0.2	39	0.07	0.111	5
1287756	Soil	1.7	24.1	23.1	162	0.2	38.9	23.2	672	4.32	29.8	<0.5	0.6	16	0.3	2.0	0.3	36	0.04	0.078	5
1287757	Soil	0.7	12.4	10.6	56	0.1	11.6	10.5	234	1.20	6.0	<0.5	0.2	8	0.1	0.5	<0.1	16	0.07	0.046	2
1287758	Soil	1.9	29.0	33.0	88	0.4	23.4	15.4	522	3.44	15.3	<0.5	0.5	16	0.2	0.8	0.2	22	0.06	0.105	3
1287759	Soil	1.9	42.1	30.4	189	0.3	44.1	33.9	691	3.27	21.9	0.8	1.7	24	0.2	0.8	0.3	24	0.20	0.149	3
1287760	Soil	0.2	5.4	2.3	12	0.1	3.1	1.6	37	0.41	0.9	<0.5	<0.1	10	<0.1	0.1	<0.1	8	0.08	0.017	1
1287761	Soil	2.1	38.0	26.5	128	0.1	38.2	13.4	214	3.34	22.0	<0.5	2.3	32	<0.1	0.8	0.3	28	0.06	0.077	3
1287762	Soil	0.9	17.1	10.4	43	0.1	7.7	4.1	247	1.16	4.5	2.7	0.3	10	0.5	0.3	0.1	16	0.05	0.109	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287733	Soil	22	0.12	589	0.002	7	0.44	0.006	0.09	<0.1	0.22	4.2	0.2	0.07	1	4.7	<0.2
1287734	Soil	24	0.33	540	0.002	6	0.44	0.005	0.10	<0.1	0.27	5.0	0.2	<0.05	1	4.6	<0.2
1287735	Soil	19	0.10	520	0.002	3	0.42	0.006	0.08	<0.1	0.32	4.9	0.2	<0.05	1	4.0	<0.2
1287736	Soil	10	0.04	163	0.006	3	0.48	0.016	0.05	<0.1	0.06	1.3	<0.1	0.10	2	1.5	<0.2
1287737	Soil	24	0.16	394	0.003	4	0.48	0.005	0.07	<0.1	0.06	4.6	0.1	0.10	2	1.6	<0.2
1287738	Soil	4	0.03	50	0.013	1	0.45	0.035	0.03	<0.1	0.03	0.6	<0.1	0.06	2	<0.5	<0.2
1287739	Soil	11	0.12	287	0.006	3	0.53	0.010	0.05	<0.1	0.20	9.2	0.2	<0.05	1	1.2	0.2
1287740	Soil	13	0.03	259	0.003	2	0.53	0.011	0.06	<0.1	0.17	0.9	0.4	0.08	2	2.0	<0.2
1287741	Soil	25	0.16	183	0.010	2	0.89	0.005	0.06	0.1	0.08	1.1	0.3	<0.05	4	1.7	<0.2
1287742	Soil	10	0.02	105	0.005	2	0.31	0.007	0.04	0.1	0.01	1.0	0.3	<0.05	2	2.3	<0.2
1287743	Soil	4	0.02	64	0.006	<1	0.25	0.029	0.03	<0.1	0.04	0.3	0.1	<0.05	1	0.9	<0.2
1287744	Soil	16	0.02	112	0.004	1	0.51	0.020	0.05	<0.1	0.03	0.6	0.2	<0.05	2	0.8	<0.2
1287745	Soil	14	0.06	161	0.002	1	0.47	0.003	0.06	<0.1	0.02	2.4	0.4	<0.05	2	1.6	<0.2
1287746	Soil	15	0.07	191	0.003	2	0.58	0.004	0.07	<0.1	0.02	1.4	0.2	<0.05	3	1.3	<0.2
1287747	Soil	15	0.10	378	0.004	2	0.61	0.005	0.07	0.1	0.02	1.7	0.2	0.06	2	1.1	<0.2
1287748	Soil	9	0.06	93	0.001	<1	0.33	0.015	0.05	<0.1	0.02	1.3	<0.1	<0.05	1	<0.5	<0.2
1287749	Soil	10	0.05	49	0.004	<1	0.47	0.007	0.04	0.1	0.01	1.0	<0.1	<0.05	3	<0.5	<0.2
1287750	Soil	13	0.04	64	0.002	2	0.36	0.008	0.05	<0.1	0.03	0.9	0.2	<0.05	2	<0.5	<0.2
1287751	Soil	7	0.04	45	0.005	<1	0.32	0.021	0.04	<0.1	0.02	0.6	<0.1	<0.05	1	<0.5	<0.2
1287752	Soil	16	0.08	90	0.004	2	0.61	0.005	0.07	<0.1	0.02	1.8	0.2	<0.05	2	0.8	<0.2
1287753	Soil	13	0.05	196	0.001	<1	0.39	0.005	0.06	<0.1	0.06	2.7	0.1	<0.05	1	<0.5	<0.2
1287754	Soil	14	0.06	79	0.006	1	0.64	0.008	0.04	<0.1	0.04	0.5	0.1	<0.05	4	<0.5	<0.2
1287755	Soil	19	0.08	287	0.005	2	0.76	0.005	0.08	<0.1	0.09	0.8	0.2	0.10	4	<0.5	<0.2
1287756	Soil	20	0.13	183	0.004	1	0.77	0.005	0.07	<0.1	0.04	2.1	0.2	<0.05	3	0.5	<0.2
1287757	Soil	7	0.07	75	0.010	1	0.58	0.020	0.04	<0.1	0.03	0.8	0.1	<0.05	2	<0.5	<0.2
1287758	Soil	21	0.13	127	0.005	1	0.91	0.013	0.06	<0.1	0.06	1.2	0.1	<0.05	3	<0.5	<0.2
1287759	Soil	27	0.25	616	0.002	3	1.14	0.010	0.08	<0.1	0.05	4.2	0.4	<0.05	3	<0.5	<0.2
1287760	Soil	4	0.03	69	0.014	<1	0.33	0.033	0.02	<0.1	0.01	0.6	<0.1	<0.05	1	<0.5	<0.2
1287761	Soil	27	0.40	312	0.010	1	1.35	0.006	0.09	<0.1	0.02	2.7	0.4	<0.05	4	<0.5	<0.2
1287762	Soil	10	0.04	136	0.008	2	0.50	0.020	0.05	<0.1	0.02	1.1	0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287763	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287764	Soil	4.0	20.2	17.9	60	0.3	13.6	3.1	73	2.20	14.7	7.7	2.0	20	<0.1	2.1	0.3	14	0.02	0.034	3
1287765	Soil	7.8	17.9	12.6	89	0.2	18.7	4.2	68	1.53	13.7	1.3	0.6	8	0.8	2.9	0.2	27	0.02	0.026	9
1287766	Soil	7.6	27.2	18.2	123	0.2	26.1	5.1	88	3.14	20.1	0.9	1.8	22	0.2	3.2	0.2	21	0.01	0.040	4
1287767	Soil	12.7	34.5	18.7	179	0.6	43.8	8.1	104	2.52	19.6	3.6	2.3	52	0.7	5.6	0.2	20	0.19	0.094	8
1287768	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287769	Soil	16.7	34.0	24.7	231	0.5	52.3	7.8	148	3.18	30.1	2.0	1.8	48	0.9	8.1	0.4	21	0.16	0.101	9
1287770	Soil	7.9	12.5	10.4	76	0.3	16.3	2.9	48	1.29	13.2	<0.5	0.3	10	0.2	3.1	0.1	21	0.03	0.037	5
1287791	Soil	16.5	73.7	34.0	511	1.0	101.7	11.0	261	2.76	36.3	2.3	2.0	154	5.2	15.0	0.2	41	3.00	0.203	3
1287792	Soil	5.9	33.1	15.8	127	0.4	42.2	7.7	187	2.26	14.8	3.4	0.1	20	0.4	6.9	0.2	14	0.12	0.122	3
1287793	Soil	6.8	43.3	12.8	86	0.1	51.3	13.7	242	2.96	9.7	1.9	0.2	21	0.1	4.9	0.3	21	0.16	0.086	4
1287794	Soil	4.1	125.0	35.4	209	1.8	127.3	44.1	1182	8.58	22.6	11.2	1.0	48	0.3	9.7	0.6	4	0.22	0.076	6
1287795	Soil	3.5	67.6	18.1	169	0.6	75.1	24.0	731	8.62	71.8	22.9	2.4	16	1.4	15.9	0.6	5	0.04	0.066	15
1287796	Soil	1.7	23.9	9.4	83	<0.1	15.7	9.3	134	2.03	11.1	<0.5	0.2	6	<0.1	0.9	0.2	10	0.01	0.075	4
1287797	Soil	1.6	28.1	14.0	101	<0.1	19.1	12.1	559	2.48	12.3	1.7	0.2	8	0.1	1.2	0.3	10	0.02	0.087	5
1287798	Soil	0.9	15.9	6.3	55	<0.1	9.9	5.7	110	1.32	6.4	<0.5	0.2	6	<0.1	0.6	0.1	7	0.02	0.063	3
1287799	Soil	1.8	19.3	7.2	78	<0.1	15.6	7.0	295	1.51	9.9	0.9	0.1	8	<0.1	1.0	0.2	10	0.02	0.051	5
1287800	Soil	1.2	18.0	11.0	79	<0.1	21.6	9.9	266	1.72	14.6	<0.5	0.2	9	<0.1	1.0	0.2	4	0.02	0.063	3
1288141	Soil	4.2	12.2	10.9	38	0.5	6.0	1.4	22	1.23	10.2	<0.5	0.1	25	<0.1	1.7	0.1	13	0.02	0.073	3
1288142	Soil	4.4	13.9	9.3	40	0.3	6.9	1.5	24	0.99	7.5	<0.5	<0.1	18	<0.1	1.3	0.1	18	0.01	0.057	3
1288143	Soil	4.2	23.7	17.5	89	0.6	14.9	3.5	60	2.64	16.0	<0.5	0.3	34	<0.1	1.7	0.2	18	0.03	0.133	4
1288144	Soil	1.4	19.9	11.7	54	0.4	9.4	2.4	60	2.21	11.1	2.3	0.3	14	0.2	0.8	0.2	12	0.02	0.079	2
1288145	Soil	2.8	71.5	24.4	204	0.8	40.6	15.1	411	6.13	27.4	6.5	2.5	26	0.1	1.6	0.2	14	0.03	0.143	4
1288146	Soil	0.5	6.0	4.1	16	0.7	3.5	1.5	21	0.62	2.1	<0.5	<0.1	6	<0.1	0.2	<0.1	5	0.02	0.041	1
1288147	Soil	0.7	17.2	11.9	47	0.4	11.5	3.1	55	1.32	5.5	<0.5	0.3	12	<0.1	0.3	0.2	10	0.03	0.091	2
1288148	Soil	0.5	7.2	5.9	15	1.1	2.5	0.7	18	0.51	2.0	<0.5	0.2	6	<0.1	0.2	<0.1	4	0.02	0.038	1
1288149	Soil	1.2	10.0	5.2	23	0.7	4.6	1.4	23	0.96	4.7	0.6	<0.1	8	<0.1	0.5	<0.1	7	0.02	0.047	2
1288150	Soil	1.9	17.0	12.7	65	0.2	10.8	3.7	68	2.45	13.7	1.0	0.3	13	<0.1	0.8	0.2	17	0.01	0.088	4
1286461	Soil	0.5	8.2	4.8	26	0.2	9.8	3.6	125	0.87	3.2	<0.5	0.4	28	0.1	0.5	<0.1	5	0.28	0.026	2
1286462	Soil	2.2	18.7	13.2	59	0.1	14.9	5.0	75	1.60	13.5	<0.5	0.4	8	0.1	1.1	0.2	9	0.03	0.040	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287763	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287764	Soil	13	0.10	272	0.003	1	0.88	0.007	0.07	<0.1	0.04	1.2	0.2	0.31	3	<0.5	<0.2
1287765	Soil	9	0.03	164	0.008	<1	0.61	0.006	0.03	0.1	0.02	1.0	0.2	0.11	3	<0.5	<0.2
1287766	Soil	17	0.13	287	0.002	<1	0.95	0.004	0.05	<0.1	0.03	1.6	0.3	0.09	3	1.2	<0.2
1287767	Soil	17	0.21	1281	0.004	<1	0.83	0.004	0.05	<0.1	0.14	2.6	0.3	0.08	2	2.5	<0.2
1287768	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287769	Soil	19	0.15	462	0.005	<1	0.94	0.005	0.08	0.2	0.12	2.4	0.5	<0.05	3	1.7	<0.2
1287770	Soil	6	0.03	183	0.004	<1	0.40	0.009	0.03	0.1	0.03	0.3	0.1	<0.05	2	0.5	<0.2
1287791	Soil	15	1.30	411	0.002	5	0.27	0.003	0.07	<0.1	0.25	5.1	0.2	0.16	<1	2.7	<0.2
1287792	Soil	10	0.03	215	0.001	2	0.31	0.008	0.04	<0.1	0.05	0.5	0.1	0.13	1	1.5	<0.2
1287793	Soil	8	0.05	207	0.004	<1	0.46	0.009	0.03	<0.1	0.05	0.7	<0.1	0.07	2	<0.5	<0.2
1287794	Soil	10	0.08	428	0.001	<1	0.24	0.004	0.06	<0.1	0.29	8.1	0.2	<0.05	<1	1.1	0.4
1287795	Soil	12	0.04	313	0.003	4	0.28	0.002	0.05	<0.1	0.24	12.0	0.1	<0.05	<1	1.7	0.3
1287796	Soil	9	0.03	52	0.002	<1	0.36	0.003	0.02	<0.1	0.03	0.7	<0.1	<0.05	2	<0.5	<0.2
1287797	Soil	10	0.04	84	0.003	2	0.39	0.003	0.04	<0.1	0.03	0.8	<0.1	<0.05	2	<0.5	<0.2
1287798	Soil	5	0.03	35	0.002	<1	0.37	0.011	0.03	<0.1	0.04	0.5	<0.1	<0.05	2	<0.5	<0.2
1287799	Soil	7	0.02	63	0.005	<1	0.34	0.008	0.04	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2
1287800	Soil	6	0.02	55	0.003	<1	0.31	0.009	0.04	<0.1	0.04	0.5	<0.1	<0.05	2	<0.5	<0.2
1288141	Soil	6	0.01	191	0.005	<1	0.44	0.010	0.05	<0.1	0.02	0.2	0.2	0.06	2	2.0	<0.2
1288142	Soil	10	0.01	263	0.004	<1	0.33	0.008	0.05	<0.1	0.02	0.4	<0.1	<0.05	2	1.5	<0.2
1288143	Soil	15	0.03	554	0.003	<1	0.59	0.005	0.08	<0.1	0.03	0.7	0.1	<0.05	3	2.4	<0.2
1288144	Soil	12	0.05	179	0.003	<1	0.70	0.010	0.05	<0.1	0.05	0.6	<0.1	<0.05	3	1.0	<0.2
1288145	Soil	25	0.14	438	0.002	1	1.27	0.005	0.08	<0.1	0.13	4.3	0.2	<0.05	3	3.0	0.2
1288146	Soil	3	0.01	67	0.004	<1	0.27	0.021	0.03	<0.1	0.03	0.4	<0.1	<0.05	1	<0.5	<0.2
1288147	Soil	14	0.06	128	0.001	<1	0.97	0.009	0.05	<0.1	0.06	0.6	<0.1	<0.05	3	<0.5	<0.2
1288148	Soil	4	0.01	72	0.002	<1	0.29	0.018	0.03	<0.1	0.04	0.4	<0.1	<0.05	2	<0.5	<0.2
1288149	Soil	5	0.02	80	0.005	<1	0.35	0.016	0.03	<0.1	0.05	0.5	<0.1	<0.05	2	<0.5	<0.2
1288150	Soil	14	0.04	156	0.006	<1	0.62	0.006	0.05	<0.1	0.04	0.6	<0.1	<0.05	3	0.9	<0.2
1286461	Soil	4	0.10	292	0.003	<1	0.51	0.033	0.05	<0.1	0.08	1.2	<0.1	<0.05	1	<0.5	<0.2
1286462	Soil	7	0.03	181	0.003	<1	0.47	0.011	0.05	<0.1	0.09	1.3	0.2	<0.05	2	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286463	Soil	2.6	16.6	6.4	74	<0.1	18.5	5.1	60	1.85	18.4	<0.5	0.4	5	0.1	1.3	0.2	15	0.01	0.034	4
1286464	Soil	2.8	19.6	12.6	100	<0.1	20.6	5.4	103	2.59	22.7	<0.5	0.5	9	0.2	1.7	0.2	14	0.03	0.052	5
1286465	Soil	1.4	19.9	4.1	77	0.1	23.7	11.0	90	1.79	17.7	1.4	0.3	5	<0.1	0.6	0.2	9	0.01	0.027	2
1286466	Soil	1.5	10.1	4.3	31	0.2	10.5	2.8	41	1.20	12.9	1.3	0.1	5	<0.1	1.2	0.1	7	0.02	0.038	3
1286467	Soil	1.7	9.3	6.4	47	0.2	12.3	4.4	85	1.43	11.6	<0.5	0.6	6	<0.1	0.9	0.1	9	0.02	0.020	5
1286468	Soil	1.7	16.5	8.5	83	0.6	19.8	7.3	96	2.36	11.0	<0.5	0.5	6	0.2	0.6	0.2	7	0.02	0.033	2
1286469	Soil	2.0	13.6	12.5	79	<0.1	18.2	5.7	70	2.13	12.5	<0.5	0.6	7	0.5	1.0	0.2	10	0.02	0.028	3
1286470	Soil	1.4	24.2	10.6	166	0.2	33.1	12.9	220	2.34	12.4	<0.5	0.5	55	0.8	1.3	0.3	23	0.56	0.038	2
1286451	Soil	1.8	36.0	14.8	65	0.2	13.7	4.0	40	1.41	18.9	<0.5	0.6	9	0.3	0.9	0.2	33	0.04	0.031	3
1286452	Soil	1.6	25.7	4.3	237	0.3	43.1	16.7	170	3.98	14.4	<0.5	0.5	5	0.1	0.6	0.2	34	0.02	0.049	2
1286453	Soil	2.2	17.9	9.7	89	0.1	18.9	6.1	64	2.54	21.6	<0.5	0.9	5	0.1	1.5	0.2	37	0.02	0.028	4
1286454	Soil	0.9	6.0	3.6	20	<0.1	3.7	1.3	16	0.51	4.8	<0.5	0.3	4	<0.1	0.5	0.1	23	0.02	0.020	3
1286455	Soil	1.5	12.7	10.8	39	0.1	8.5	2.8	44	1.52	10.9	<0.5	0.4	5	<0.1	0.7	0.1	30	0.02	0.041	2
1286456	Soil	0.7	8.6	5.6	35	<0.1	8.5	3.7	52	1.13	5.0	0.5	0.1	4	0.1	0.4	<0.1	20	0.03	0.041	<1
1286457	Soil	1.2	9.7	4.7	43	0.2	7.7	2.5	54	1.18	6.6	<0.5	0.2	5	<0.1	0.5	<0.1	23	0.02	0.034	1
1286458	Soil	1.1	9.8	4.1	48	<0.1	9.2	3.1	34	0.85	7.6	<0.5	0.2	4	<0.1	0.4	<0.1	19	0.03	0.019	1
1286459	Soil	3.9	35.7	15.4	190	0.2	39.7	8.6	156	3.10	29.6	1.6	1.6	20	0.5	2.1	0.2	39	0.10	0.067	5
1286460	Soil	2.4	22.1	10.5	103	<0.1	20.9	7.3	79	2.17	22.8	<0.5	0.6	8	0.3	1.3	0.2	32	0.02	0.035	3
1286191	Soil	3.0	16.2	11.5	80	0.3	14.5	4.1	54	2.62	26.1	<0.5	0.7	12	0.2	1.3	0.2	45	0.04	0.044	3
1286192	Soil	1.6	20.7	15.9	127	0.7	26.3	8.9	167	4.09	12.4	1.0	1.2	12	0.3	0.6	0.3	47	0.03	0.074	2
1286193	Soil	2.2	9.8	7.4	56	0.2	9.9	3.2	42	1.38	15.8	<0.5	0.5	8	<0.1	1.0	0.2	43	0.02	0.047	3
1286194	Soil	2.4	25.0	15.6	77	1.6	17.1	10.2	267	2.23	12.0	<0.5	0.3	14	0.2	1.0	0.2	44	0.03	0.061	4
1286195	Soil	3.5	17.0	12.9	96	0.4	16.7	4.4	80	2.21	23.2	<0.5	1.0	20	0.3	1.7	0.2	48	0.03	0.058	4
1286196	Soil	6.2	27.6	13.4	73	1.0	13.3	3.7	43	1.54	16.1	<0.5	0.7	15	0.2	2.4	0.2	54	0.02	0.041	6
1286197	Soil	5.0	9.4	7.9	27	1.4	6.0	1.6	20	0.70	11.4	<0.5	0.2	26	0.1	2.7	0.1	37	0.03	0.060	2
1286198	Soil	3.7	17.6	11.1	89	<0.1	18.8	5.1	59	2.11	27.3	<0.5	0.6	7	0.2	1.7	0.2	41	0.02	0.042	5
1286199	Soil	1.7	24.5	10.4	51	0.8	27.2	1.8	29	0.87	7.0	<0.5	0.4	32	0.7	1.0	0.2	25	0.27	0.083	2
1286200	Soil	1.4	16.6	7.7	70	0.5	20.5	4.0	69	1.48	5.8	<0.5	0.4	28	1.6	0.6	0.1	28	0.21	0.070	2
1286181	Soil	6.1	33.4	13.9	218	0.5	39.6	10.4	390	2.53	20.3	1.6	1.8	62	2.3	2.7	0.2	58	0.29	0.149	7
1286182	Soil	3.7	21.5	18.0	107	1.1	24.3	4.1	71	1.99	12.0	4.5	1.1	44	0.5	1.4	0.2	46	0.12	0.134	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286463	Soil	7	0.02	52	0.003	<1	0.34	0.007	0.03	0.1	0.04	1.3	0.1	<0.05	2	<0.5	<0.2
1286464	Soil	11	0.07	116	0.003	<1	0.65	0.005	0.04	<0.1	0.05	1.2	0.2	<0.05	3	<0.5	<0.2
1286465	Soil	6	0.02	47	0.001	<1	0.37	0.009	0.04	<0.1	0.03	1.4	0.1	<0.05	2	<0.5	<0.2
1286466	Soil	5	0.01	45	0.003	<1	0.29	0.011	0.03	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2
1286467	Soil	7	0.02	84	0.004	<1	0.44	0.009	0.03	<0.1	0.03	1.2	0.1	<0.05	2	<0.5	<0.2
1286468	Soil	7	0.03	85	0.002	<1	0.45	0.009	0.06	<0.1	0.05	1.9	<0.1	<0.05	2	0.6	<0.2
1286469	Soil	7	0.03	91	0.003	<1	0.45	0.006	0.07	<0.1	0.01	1.4	0.1	<0.05	2	<0.5	<0.2
1286470	Soil	15	0.16	134	0.001	2	0.42	0.008	0.07	<0.1	0.10	2.7	0.1	<0.05	1	1.2	<0.2
1286451	Soil	9	0.03	182	0.002	2	0.68	0.012	0.05	<0.1	0.09	2.0	0.6	<0.05	3	1.8	<0.2
1286452	Soil	10	0.02	91	0.002	2	0.45	0.008	0.03	<0.1	0.02	2.7	<0.1	<0.05	2	<0.5	<0.2
1286453	Soil	11	0.05	97	0.003	1	0.52	0.006	0.03	<0.1	0.02	1.5	<0.1	<0.05	2	0.5	<0.2
1286454	Soil	4	0.02	67	0.005	<1	0.42	0.011	0.03	<0.1	0.02	0.5	<0.1	<0.05	2	<0.5	<0.2
1286455	Soil	8	0.04	71	0.003	1	0.54	0.012	0.05	<0.1	0.02	1.1	0.1	<0.05	3	<0.5	<0.2
1286456	Soil	6	0.03	49	0.003	1	0.43	0.016	0.04	<0.1	0.02	0.8	<0.1	<0.05	2	<0.5	<0.2
1286457	Soil	7	0.02	60	0.004	1	0.36	0.014	0.04	<0.1	0.03	0.9	<0.1	<0.05	2	<0.5	<0.2
1286458	Soil	5	0.02	60	0.002	1	0.32	0.014	0.03	<0.1	0.02	0.8	<0.1	<0.05	2	<0.5	<0.2
1286459	Soil	16	0.14	963	0.003	2	0.68	0.005	0.06	0.1	0.11	2.9	0.2	<0.05	2	1.8	<0.2
1286460	Soil	9	0.05	141	0.002	<1	0.57	0.008	0.04	<0.1	0.03	1.9	0.1	<0.05	2	<0.5	<0.2
1286191	Soil	11	0.04	153	0.001	2	0.71	0.005	0.05	<0.1	0.04	1.5	0.2	<0.05	3	1.2	<0.2
1286192	Soil	24	0.15	209	0.002	3	1.57	0.009	0.07	<0.1	0.02	2.7	0.1	<0.05	5	1.0	<0.2
1286193	Soil	8	0.02	95	0.002	1	0.45	0.008	0.03	<0.1	0.02	0.9	<0.1	<0.05	3	0.5	<0.2
1286194	Soil	16	0.09	312	0.004	2	0.92	0.012	0.06	<0.1	0.08	1.4	0.2	<0.05	4	1.2	<0.2
1286195	Soil	13	0.05	258	0.004	3	0.61	0.006	0.07	<0.1	0.04	1.8	0.2	<0.05	3	1.0	<0.2
1286196	Soil	10	0.02	319	0.002	2	0.49	0.005	0.05	<0.1	0.05	1.6	0.2	<0.05	2	1.5	<0.2
1286197	Soil	5	0.01	207	0.004	2	0.35	0.012	0.04	<0.1	0.04	0.9	0.3	0.07	2	2.1	<0.2
1286198	Soil	8	0.02	93	0.002	1	0.42	0.004	0.03	<0.1	0.01	1.4	0.1	<0.05	2	0.6	<0.2
1286199	Soil	8	0.07	362	0.004	4	0.65	0.013	0.07	<0.1	0.12	1.8	0.3	0.09	3	1.3	<0.2
1286200	Soil	8	0.05	269	0.003	3	0.55	0.015	0.08	<0.1	0.08	2.0	0.3	0.12	2	3.9	<0.2
1286181	Soil	16	0.16	1406	0.002	2	0.77	0.005	0.08	<0.1	0.11	2.6	0.2	0.06	2	2.4	<0.2
1286182	Soil	17	0.09	1706	0.002	5	0.89	0.008	0.09	0.1	0.20	2.4	0.3	0.08	3	3.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286183	Soil	4.3	30.6	17.5	156	0.4	26.9	6.9	144	2.76	16.2	3.0	1.2	42	0.5	1.6	0.2	49	0.08	0.106	6
1286184	Soil	4.1	20.6	19.4	104	0.6	19.5	5.0	103	3.02	23.9	1.9	0.9	66	0.3	1.7	0.2	47	0.05	0.140	4
1286185	Soil	3.3	22.1	13.6	72	1.5	16.1	3.1	52	1.36	10.1	1.0	0.4	39	0.3	1.4	0.2	38	0.04	0.108	3
1286186	Soil	4.6	14.1	11.6	81	0.7	14.5	3.1	57	1.77	15.3	<0.5	0.5	24	0.4	1.7	0.2	54	0.03	0.083	4
1286187	Soil	2.4	14.4	9.1	49	0.8	11.4	2.2	42	1.28	8.8	1.5	0.2	21	0.2	0.9	0.1	32	0.04	0.079	3
1286188	Soil	3.5	14.6	13.5	73	0.4	13.5	3.9	62	1.90	22.0	<0.5	0.3	15	0.1	1.7	0.2	50	0.03	0.070	5
1286189	Soil	3.6	17.7	15.7	76	1.3	13.1	3.6	53	2.16	20.9	<0.5	0.4	16	0.3	1.4	0.2	47	0.02	0.077	3
1286190	Soil	1.3	16.0	8.5	49	0.6	7.2	1.9	31	2.05	10.5	<0.5	0.5	8	0.1	0.6	0.1	37	0.03	0.056	2
1287001	Soil	1.8	21.9	12.3	78	0.3	25.9	10.7	308	1.95	11.1	0.7	0.8	45	0.4	0.9	0.2	28	0.40	0.083	4
1287002	Soil	0.5	5.7	2.4	13	0.2	5.3	1.7	36	0.44	1.9	<0.5	0.1	9	0.1	0.2	<0.1	10	0.05	0.030	1
1287003	Soil	0.9	5.9	4.2	32	<0.1	7.1	1.7	27	0.62	4.0	<0.5	0.1	7	<0.1	0.3	<0.1	18	0.05	0.026	1
1287004	Soil	4.0	20.7	11.8	124	<0.1	21.9	5.7	118	2.22	25.5	1.3	1.1	15	0.2	1.9	0.2	37	0.13	0.050	6
1287005	Soil	4.4	22.5	14.2	100	0.1	23.1	6.5	119	2.24	25.9	1.0	1.5	17	0.2	1.8	0.2	37	0.11	0.070	6
1287006	Soil	1.8	36.3	20.5	113	0.2	24.6	10.8	184	3.34	22.6	6.9	2.6	37	<0.1	1.2	0.3	42	0.03	0.077	5
1287007	Soil	2.3	23.8	16.3	78	0.2	19.8	6.2	159	2.83	12.7	2.5	0.3	19	<0.1	1.1	0.3	44	0.04	0.127	5
1287008	Soil	0.4	8.6	3.4	13	0.1	3.1	1.2	24	0.54	1.9	<0.5	<0.1	7	<0.1	0.2	<0.1	10	0.02	0.046	1
1287009	Soil	1.4	49.1	33.6	184	0.3	37.8	23.0	343	4.91	28.7	2.4	2.8	37	<0.1	0.9	0.4	51	0.01	0.096	4
1287010	Soil	1.6	22.8	15.1	78	0.2	18.5	8.0	218	2.40	11.8	1.8	0.8	16	<0.1	0.9	0.3	38	0.04	0.075	8
1287011	Soil	1.6	26.5	17.2	67	0.2	14.7	5.7	130	2.23	10.0	0.9	0.5	11	<0.1	0.8	0.3	44	0.02	0.119	5
1287012	Soil	2.2	36.1	45.6	107	0.5	24.3	13.0	302	3.34	29.0	4.6	1.9	27	0.1	1.6	0.3	49	0.03	0.117	5
1287013	Soil	1.1	24.7	38.7	93	0.2	28.4	21.4	715	2.74	10.0	<0.5	1.4	11	<0.1	0.5	0.3	33	0.05	0.090	3
1287014	Soil	1.3	26.2	21.4	69	0.5	14.2	3.5	70	2.36	13.0	1.1	1.3	21	<0.1	0.7	0.3	48	0.02	0.115	3
1287015	Soil	1.3	20.5	17.9	51	0.6	11.8	3.1	56	1.58	10.1	1.6	0.5	39	0.2	0.5	0.2	31	0.02	0.158	2
1287016	Soil	1.8	14.3	10.0	36	1.3	8.2	2.2	39	1.03	6.5	<0.5	0.3	24	<0.1	1.0	0.1	19	0.01	0.124	2
1287017	Soil	10.3	23.6	17.7	106	0.4	9.1	1.8	23	5.00	49.6	<0.5	1.1	22	<0.1	6.1	0.3	66	<0.01	0.075	2
1287018	Soil	2.5	12.6	10.4	67	0.3	8.3	2.5	46	1.74	20.4	<0.5	0.8	15	<0.1	1.2	0.2	36	0.02	0.056	3
1287019	Soil	5.0	13.2	18.6	75	0.2	11.5	3.7	93	2.08	18.0	<0.5	0.9	24	0.2	1.8	0.2	28	0.04	0.060	2
1287020	Soil	1.4	44.4	37.9	62	1.3	13.4	5.0	465	3.29	31.2	4.7	1.4	21	<0.1	1.4	0.4	43	0.02	0.127	2
1288131	Soil	8.1	22.7	28.8	86	0.6	20.9	4.1	50	1.43	16.7	<0.5	<0.1	23	<0.1	5.6	0.2	56	<0.01	0.060	4
1288132	Soil	5.1	19.4	19.5	61	0.3	15.1	3.1	50	1.30	10.5	0.8	<0.1	21	<0.1	3.0	0.2	43	0.01	0.060	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286183	Soil	15	0.10	1151	0.003	2	0.73	0.005	0.06	<0.1	0.07	2.1	0.1	0.07	3	1.3	<0.2
1286184	Soil	17	0.06	485	0.003	2	0.57	0.007	0.07	<0.1	0.05	1.6	0.1	0.06	2	2.4	<0.2
1286185	Soil	13	0.03	1198	0.002	4	0.49	0.009	0.07	<0.1	0.10	1.3	0.2	0.12	2	1.5	<0.2
1286186	Soil	13	0.04	416	0.003	2	0.53	0.008	0.05	<0.1	0.04	1.0	0.1	0.05	3	1.3	<0.2
1286187	Soil	10	0.04	389	0.003	2	0.58	0.014	0.05	<0.1	0.11	0.8	0.1	0.06	2	0.6	<0.2
1286188	Soil	9	0.03	156	0.004	1	0.49	0.007	0.05	<0.1	0.02	0.9	0.1	<0.05	3	1.4	<0.2
1286189	Soil	12	0.03	166	0.003	1	0.54	0.007	0.06	<0.1	0.04	1.1	0.2	<0.05	3	1.5	<0.2
1286190	Soil	11	0.03	188	0.003	2	0.71	0.015	0.04	<0.1	0.03	1.0	<0.1	<0.05	3	0.8	<0.2
1287001	Soil	18	0.14	815	0.004	3	0.92	0.015	0.08	<0.1	0.09	2.5	0.2	0.10	3	0.9	<0.2
1287002	Soil	5	0.03	109	0.006	<1	0.26	0.023	0.02	<0.1	0.04	0.7	<0.1	<0.05	<1	0.5	<0.2
1287003	Soil	5	0.03	193	0.002	<1	0.45	0.018	0.03	<0.1	0.03	0.5	<0.1	<0.05	2	<0.5	<0.2
1287004	Soil	13	0.14	363	0.002	<1	0.60	0.006	0.05	<0.1	0.04	1.5	<0.1	<0.05	2	1.4	<0.2
1287005	Soil	14	0.14	635	0.001	<1	0.69	0.004	0.04	<0.1	0.07	1.7	0.1	<0.05	2	1.7	<0.2
1287006	Soil	26	0.23	152	0.002	<1	1.12	0.003	0.05	<0.1	0.05	2.9	0.1	0.06	4	1.0	<0.2
1287007	Soil	29	0.13	250	0.005	<1	0.97	0.008	0.06	<0.1	0.04	0.8	<0.1	0.09	4	1.0	<0.2
1287008	Soil	5	0.02	52	0.004	<1	0.45	0.031	0.02	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2
1287009	Soil	33	0.24	167	0.002	1	1.54	0.004	0.07	<0.1	0.06	4.4	0.1	<0.05	5	1.4	<0.2
1287010	Soil	21	0.21	123	0.005	<1	0.97	0.008	0.05	0.1	0.04	1.4	0.1	0.05	3	0.7	<0.2
1287011	Soil	21	0.06	164	0.003	1	0.97	0.009	0.05	<0.1	0.04	1.0	<0.1	0.06	4	0.8	<0.2
1287012	Soil	30	0.23	259	0.003	<1	1.37	0.008	0.07	<0.1	0.09	3.6	0.3	0.10	4	1.6	<0.2
1287013	Soil	25	0.23	383	0.003	1	1.42	0.017	0.08	<0.1	0.07	3.9	0.1	0.05	4	0.8	<0.2
1287014	Soil	22	0.07	202	0.002	1	1.00	0.005	0.08	<0.1	0.08	1.9	0.1	0.07	4	0.8	<0.2
1287015	Soil	14	0.04	670	0.001	<1	0.77	0.008	0.06	<0.1	0.08	1.0	0.1	0.10	3	1.3	<0.2
1287016	Soil	10	0.04	588	0.003	3	0.42	0.022	0.06	<0.1	0.09	0.7	0.1	0.11	1	1.7	<0.2
1287017	Soil	14	0.02	299	<0.001	1	0.50	0.006	0.09	<0.1	0.05	1.2	0.6	0.15	3	3.4	<0.2
1287018	Soil	11	0.04	237	0.001	1	0.51	0.006	0.07	<0.1	0.03	1.0	0.2	<0.05	2	0.7	<0.2
1287019	Soil	10	0.05	714	<0.001	2	0.51	0.006	0.08	<0.1	0.06	2.0	0.3	0.08	2	1.5	<0.2
1287020	Soil	25	0.12	426	0.002	2	1.20	0.010	0.08	<0.1	0.09	2.4	0.2	0.08	4	2.2	<0.2
1288131	Soil	10	0.02	98	0.002	<1	0.29	0.005	0.03	<0.1	0.03	0.3	0.2	<0.05	3	1.4	<0.2
1288132	Soil	12	0.03	77	0.003	<1	0.41	0.013	0.03	<0.1	0.02	0.2	0.1	<0.05	3	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288133	Soil	12.7	15.2	44.7	36	0.7	8.7	1.6	30	1.12	17.3	<0.5	<0.1	53	<0.1	6.0	0.2	52	0.01	0.049	4
1288134	Soil	1.9	20.5	16.6	111	0.2	18.4	6.6	221	3.19	13.5	<0.5	0.5	18	<0.1	0.9	0.3	36	0.02	0.134	4
1288135	Soil	1.2	40.8	25.2	154	0.3	27.5	8.2	101	2.67	20.2	4.5	1.3	52	0.5	0.7	0.3	18	0.08	0.051	2
1288136	Soil	9.6	24.2	17.6	139	1.7	25.1	5.6	154	3.16	24.9	<0.5	0.6	85	0.2	8.2	0.2	79	0.09	0.252	7
1288137	Soil	4.1	23.2	17.3	101	1.3	16.6	4.0	164	2.00	13.1	1.9	0.5	60	<0.1	2.9	0.2	49	0.04	0.184	5
1288138	Soil	2.5	9.3	10.8	43	0.3	7.1	1.5	27	0.95	7.8	<0.5	0.1	15	<0.1	1.1	0.1	27	0.01	0.075	4
1288139	Soil	3.9	16.1	17.6	57	0.2	7.1	1.5	84	2.55	17.5	<0.5	0.8	16	0.1	1.8	0.4	28	0.02	0.074	3
1288140	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1288151	Soil	2.4	22.2	16.9	83	0.4	13.2	3.9	99	2.78	16.7	<0.5	0.2	18	<0.1	1.5	0.5	47	0.02	0.101	6
1288152	Soil	0.9	5.4	4.5	16	0.1	3.5	1.0	40	0.64	2.9	<0.5	<0.1	8	<0.1	0.5	0.2	11	0.02	0.072	2
1288153	Soil	1.5	14.1	8.6	34	0.4	5.4	1.6	31	1.08	6.4	<0.5	0.2	13	<0.1	0.6	0.2	29	0.01	0.056	3
1288154	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1288155	Soil	3.8	44.4	24.1	129	0.4	19.9	5.6	132	4.31	21.3	1.1	1.8	40	0.1	1.8	0.4	46	0.03	0.104	4
1288156	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1288157	Soil	4.7	17.2	13.0	58	0.8	9.7	2.6	60	1.75	13.2	<0.5	<0.1	40	0.2	1.8	0.3	38	0.02	0.122	4
1288158	Soil	9.8	36.4	29.3	117	1.7	20.1	5.4	117	3.74	29.1	2.3	0.4	80	0.2	3.7	0.4	83	0.04	0.327	9
1288159	Soil	3.4	12.9	10.4	26	3.9	5.9	0.8	11	1.15	5.3	2.2	0.3	41	<0.1	0.9	0.1	23	0.02	0.201	4
1288160	Soil	1.8	15.0	6.2	14	1.0	4.2	0.7	12	0.54	3.0	<0.5	<0.1	33	<0.1	1.1	<0.1	20	0.02	0.099	2
1287571	Soil	4.2	20.3	16.9	78	0.8	21.2	3.0	42	1.52	15.8	1.3	0.5	20	0.4	2.2	0.2	30	0.08	0.069	4
1287572	Soil	5.8	16.4	14.3	85	0.3	20.1	4.3	60	1.42	12.4	3.5	0.8	18	0.9	2.0	0.2	26	0.05	0.037	3
1287573	Soil	6.2	13.6	17.4	64	0.3	14.4	3.3	66	1.60	15.4	4.2	0.9	15	0.6	1.7	0.2	32	0.04	0.048	3
1287574	Soil	3.1	17.3	13.4	128	0.4	25.9	7.5	187	2.28	16.3	2.6	0.9	23	0.5	1.5	0.2	33	0.23	0.045	4
1287575	Soil	2.2	10.5	10.1	83	0.4	16.1	3.7	150	1.96	7.5	2.3	0.5	11	0.2	0.7	0.1	29	0.06	0.045	3
1287576	Soil	3.0	15.0	11.5	99	0.2	19.5	4.8	110	3.37	13.5	2.0	1.5	7	0.2	1.7	0.2	43	0.02	0.045	5
1287577	Soil	3.7	37.4	19.0	111	0.3	25.5	7.1	109	1.94	9.7	2.5	0.9	10	0.4	2.0	0.2	36	0.04	0.070	5
1287578	Soil	1.9	10.7	6.8	61	<0.1	11.9	4.5	87	2.03	10.7	1.0	0.3	5	<0.1	1.4	0.1	38	0.02	0.036	3
1287579	Soil	2.5	13.4	14.8	99	0.1	17.5	7.0	148	1.89	14.7	0.8	0.7	9	0.2	1.9	0.2	31	0.04	0.029	4
1287580	Soil	12.7	34.2	8.9	246	0.3	46.6	5.7	190	1.73	63.0	4.7	0.7	45	2.6	17.0	0.1	64	0.59	0.147	6
1287601	Soil	37.2	118.7	135.3	120	6.7	25.4	2.2	82	2.75	42.0	6.0	0.6	670	2.4	11.0	0.2	617	0.34	0.408	6
1287602	Soil	28.0	116.1	107.7	266	3.2	88.8	9.4	282	2.89	53.6	9.0	0.5	1182	3.9	31.7	0.4	329	0.48	0.439	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288133	Soil	10	0.01	192	0.005	<1	0.27	0.008	0.04	<0.1	0.03	0.3	0.3	0.06	2	1.9	<0.2
1288134	Soil	19	0.07	542	0.003	1	0.86	0.005	0.07	<0.1	0.03	1.0	<0.1	0.08	3	1.1	0.2
1288135	Soil	8	0.05	746	<0.001	2	0.45	0.006	0.11	<0.1	0.05	2.1	<0.1	0.25	1	1.6	0.2
1288136	Soil	19	0.08	602	0.004	1	0.64	0.006	0.10	0.1	0.05	0.6	0.4	0.25	3	5.5	<0.2
1288137	Soil	16	0.05	814	0.003	3	0.65	0.008	0.10	<0.1	0.03	1.0	0.3	0.17	3	3.5	<0.2
1288138	Soil	8	0.02	224	0.003	<1	0.31	0.010	0.05	<0.1	0.02	0.2	0.1	0.06	2	1.0	<0.2
1288139	Soil	11	0.04	299	<0.001	2	0.56	0.005	0.07	<0.1	0.06	1.3	0.3	0.10	2	1.0	<0.2
1288140	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1288151	Soil	17	0.04	168	0.005	4	0.71	0.005	0.06	<0.1	0.05	0.6	0.1	<0.05	3	0.9	<0.2
1288152	Soil	6	0.02	90	0.004	3	0.30	0.020	0.03	<0.1	0.02	0.2	<0.1	<0.05	1	<0.5	<0.2
1288153	Soil	8	0.02	133	0.002	1	0.56	0.013	0.03	<0.1	0.02	0.4	<0.1	<0.05	3	0.6	<0.2
1288154	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1288155	Soil	18	0.09	492	0.002	1	0.94	0.006	0.06	<0.1	0.04	2.5	0.2	0.06	3	2.4	<0.2
1288156	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1288157	Soil	11	0.03	545	<0.001	1	0.54	0.010	0.05	<0.1	0.05	0.2	0.2	0.08	2	2.1	<0.2
1288158	Soil	25	0.06	1221	0.006	2	1.21	0.022	0.11	<0.1	0.13	0.5	0.5	0.23	5	5.1	<0.2
1288159	Soil	16	<0.01	695	0.002	1	0.36	0.005	0.06	<0.1	0.15	0.6	0.2	0.10	1	4.8	<0.2
1288160	Soil	8	0.01	731	0.003	1	0.39	0.019	0.04	<0.1	0.04	0.4	0.1	0.06	1	2.0	<0.2
1287571	Soil	11	0.05	503	0.004	2	0.49	0.007	0.06	<0.1	0.17	1.5	0.4	0.06	2	2.8	<0.2
1287572	Soil	10	0.04	622	<0.001	2	0.47	0.007	0.06	<0.1	0.14	1.8	0.3	0.06	1	2.1	<0.2
1287573	Soil	9	0.04	608	<0.001	2	0.54	0.007	0.06	<0.1	0.23	1.5	0.3	<0.05	2	1.5	<0.2
1287574	Soil	14	0.14	340	0.003	3	0.62	0.018	0.07	<0.1	0.13	1.9	0.2	<0.05	3	1.4	<0.2
1287575	Soil	10	0.05	259	0.001	1	0.71	0.021	0.06	<0.1	0.08	1.2	0.3	<0.05	2	0.6	<0.2
1287576	Soil	16	0.15	86	0.004	<1	0.85	0.010	0.04	<0.1	0.02	1.5	0.1	<0.05	4	0.6	<0.2
1287577	Soil	17	0.14	189	0.003	<1	1.38	0.015	0.06	<0.1	0.10	1.8	0.3	<0.05	4	1.0	<0.2
1287578	Soil	13	0.07	69	0.005	<1	0.60	0.014	0.03	<0.1	<0.01	1.0	<0.1	<0.05	3	<0.5	<0.2
1287579	Soil	11	0.05	145	0.003	<1	0.51	0.009	0.05	<0.1	0.02	1.6	0.1	<0.05	3	0.5	<0.2
1287580	Soil	14	0.11	408	0.006	2	0.88	0.015	0.05	<0.1	0.06	1.9	0.2	0.09	2	1.5	<0.2
1287601	Soil	42	0.02	335	0.006	4	0.73	0.005	0.16	0.2	0.42	1.4	0.5	0.46	3	5.4	0.5
1287602	Soil	49	0.04	1496	0.003	5	0.75	0.006	0.12	0.2	0.91	4.3	0.9	0.13	3	3.5	0.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287603	Soil	11.6	71.2	147.7	116	2.3	20.7	3.3	106	1.63	27.3	3.6	0.3	1251	1.5	24.4	0.2	188	0.43	0.500	4
1287604	Soil	3.3	67.0	29.4	510	1.2	138.6	33.2	1026	8.50	19.7	6.6	1.5	41	2.1	6.2	0.4	25	0.23	0.085	9
1287605	Soil	1.2	8.3	5.8	31	0.1	9.2	2.5	43	0.77	4.8	2.5	<0.1	10	<0.1	0.7	<0.1	20	0.04	0.029	3
1287606	Soil	1.5	13.6	5.6	52	0.6	17.9	4.6	88	0.97	5.5	0.8	0.4	25	0.2	1.1	0.1	17	0.29	0.039	2
1287607	Soil	2.1	29.3	13.4	72	0.8	30.4	13.5	230	1.38	7.4	1.3	0.8	39	0.1	1.2	0.1	27	0.45	0.073	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

CERTIFICATE OF ANALYSIS WHI11001424.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287603	Soil	30	0.04	886	0.008	5	0.73	0.020	0.08	<0.1	0.40	1.7	0.3	0.11	3	5.0	0.3
1287604	Soil	10	0.09	355	0.004	2	0.50	0.011	0.05	<0.1	0.14	7.7	0.2	<0.05	1	2.3	<0.2
1287605	Soil	7	0.02	87	0.003	1	0.26	0.018	0.04	<0.1	0.02	0.4	<0.1	<0.05	2	<0.5	<0.2
1287606	Soil	10	0.11	317	0.003	1	0.49	0.025	0.04	<0.1	0.09	1.2	0.1	<0.05	2	0.9	<0.2
1287607	Soil	18	0.14	432	0.005	2	0.80	0.022	0.07	<0.1	0.19	2.8	0.3	<0.05	2	1.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

QUALITY CONTROL REPORT WHI11001424.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1283939	Soil	12.4	24.4	4.9	203	0.2	27.3	8.1	367	2.34	505.8	7.4	0.2	13	2.4	15.3	<0.1	102	0.14	0.103	3
REP 1283939	QC	11.6	24.2	5.1	199	0.2	27.7	7.9	360	2.36	498.0	6.1	0.1	13	2.4	15.3	<0.1	101	0.13	0.099	3
1287804	Soil	0.4	7.2	1.8	9	0.2	3.0	1.8	315	0.38	1.2	<0.5	<0.1	7	0.1	0.2	<0.1	7	0.04	0.035	2
REP 1287804	QC	0.3	7.4	1.9	9	0.2	3.0	1.8	319	0.38	1.2	<0.5	<0.1	7	<0.1	0.1	<0.1	7	0.04	0.036	2
1286357	Soil	22.7	27.6	11.8	413	0.1	62.8	7.1	62	2.19	36.2	1.9	0.2	12	0.7	20.8	0.2	141	0.13	0.079	3
REP 1286357	QC	23.7	29.0	11.9	412	0.2	63.6	7.0	64	2.20	37.4	0.7	0.2	13	0.8	20.4	0.2	148	0.14	0.080	3
1284402	Soil	2.1	30.8	29.3	94	1.3	27.1	8.2	137	3.64	20.9	3.0	2.0	29	<0.1	0.8	0.3	51	0.03	0.075	3
REP 1284402	QC	1.9	28.4	28.7	91	1.2	28.4	8.0	137	3.48	19.4	2.1	1.9	28	<0.1	0.9	0.3	52	0.03	0.072	3
1284415	Soil	0.3	3.6	4.2	38	0.3	5.1	2.9	65	0.54	3.1	<0.5	0.3	9	<0.1	0.2	<0.1	14	0.04	0.021	1
REP 1284415	QC	0.3	3.8	4.3	38	0.3	5.0	3.0	67	0.55	3.4	<0.5	0.3	9	<0.1	0.2	<0.1	13	0.04	0.023	1
1282976	Soil	1.3	14.4	9.5	42	0.3	11.6	2.9	79	1.24	7.3	1.4	0.2	11	<0.1	0.6	0.1	27	0.03	0.061	4
REP 1282976	QC	1.4	13.6	9.7	42	0.2	11.3	3.1	83	1.31	7.6	2.3	0.2	13	0.1	0.6	0.1	29	0.03	0.068	4
1282995	Soil	4.5	33.0	25.8	118	1.1	24.5	6.7	111	3.77	23.3	3.7	1.8	50	0.5	1.8	0.3	49	0.03	0.215	4
REP 1282995	QC	4.6	32.6	24.7	124	1.2	24.1	6.8	114	3.82	23.5	4.2	1.8	52	0.4	1.8	0.3	52	0.03	0.203	4
1284102	Soil	80.3	50.2	11.5	2109	1.1	258.5	27.5	1649	4.89	58.3	4.4	2.2	60	33.1	8.9	0.2	95	0.84	0.272	9
REP 1284102	QC	83.9	50.7	11.4	2132	1.1	267.7	28.8	1761	5.03	59.8	3.9	2.2	63	34.5	9.4	0.2	94	0.83	0.273	9
1284110	Soil	30.0	43.0	13.7	598	0.5	77.8	9.6	489	2.21	26.4	3.3	3.6	62	3.2	4.1	0.2	79	0.79	0.180	13
REP 1284110	QC	30.3	42.8	12.9	599	0.5	78.0	8.9	490	2.25	28.0	6.2	3.5	64	3.1	4.3	0.2	72	0.81	0.179	13
1287747	Soil	5.4	23.8	21.5	114	0.2	25.3	9.0	160	2.67	24.4	1.7	0.8	34	0.3	2.3	0.2	43	0.03	0.048	7
REP 1287747	QC	5.4	24.6	21.6	110	0.2	25.2	9.2	160	2.63	24.5	1.5	0.9	33	0.2	2.5	0.2	43	0.04	0.050	7
1287795	Soil	3.5	67.6	18.1	169	0.6	75.1	24.0	731	8.62	71.8	22.9	2.4	16	1.4	15.9	0.6	5	0.04	0.066	15
REP 1287795	QC	3.5	68.2	18.3	174	0.6	74.6	23.9	740	8.68	73.7	21.9	2.5	17	1.4	16.2	0.7	4	0.04	0.065	15
1288150	Soil	1.9	17.0	12.7	65	0.2	10.8	3.7	68	2.45	13.7	1.0	0.3	13	<0.1	0.8	0.2	17	0.01	0.088	4
REP 1288150	QC	2.2	17.5	12.3	65	0.2	10.6	3.5	66	2.37	14.6	0.6	0.3	12	<0.1	0.8	0.2	17	0.01	0.083	4
1286460	Soil	2.4	22.1	10.5	103	<0.1	20.9	7.3	79	2.17	22.8	<0.5	0.6	8	0.3	1.3	0.2	32	0.02	0.035	3
REP 1286460	QC	2.2	20.4	9.2	93	<0.1	19.1	6.4	70	2.00	21.8	<0.5	0.6	7	0.2	1.2	0.2	29	0.02	0.031	3
1287004	Soil	4.0	20.7	11.8	124	<0.1	21.9	5.7	118	2.22	25.5	1.3	1.1	15	0.2	1.9	0.2	37	0.13	0.050	6
REP 1287004	QC	4.1	20.5	11.7	116	<0.1	21.7	5.7	112	2.21	26.0	0.9	1.2	15	0.3	2.0	0.1	36	0.12	0.051	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

QUALITY CONTROL REPORT WHI11001424.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1283939	Soil		12	0.06	182	0.004	2	0.53	0.015	0.05	<0.1	0.08	3.9	0.2	<0.05	2	0.9	<0.2
REP 1283939	QC		12	0.06	175	0.006	2	0.51	0.015	0.05	<0.1	0.07	4.1	0.2	<0.05	2	0.8	<0.2
1287804	Soil		4	0.02	43	0.005	<1	0.47	0.023	0.02	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2
REP 1287804	QC		4	0.02	41	0.006	<1	0.47	0.026	0.02	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2
1286357	Soil		14	0.06	118	0.002	<1	0.31	0.005	0.04	<0.1	0.03	0.6	0.2	<0.05	1	2.2	<0.2
REP 1286357	QC		16	0.06	121	0.003	1	0.33	0.005	0.05	<0.1	0.04	0.6	0.2	<0.05	1	2.3	<0.2
1284402	Soil		31	0.13	273	0.002	<1	1.24	0.007	0.08	<0.1	0.14	2.6	0.1	<0.05	4	0.7	<0.2
REP 1284402	QC		31	0.13	278	0.003	<1	1.25	0.007	0.08	<0.1	0.13	2.6	0.2	<0.05	4	<0.5	0.2
1284415	Soil		8	0.05	300	0.005	2	0.43	0.019	0.03	<0.1	<0.01	0.6	<0.1	<0.05	2	<0.5	<0.2
REP 1284415	QC		7	0.05	308	0.005	2	0.46	0.022	0.03	<0.1	<0.01	1.0	<0.1	<0.05	2	<0.5	<0.2
1282976	Soil		11	0.07	213	0.005	2	0.50	0.009	0.04	<0.1	0.05	0.6	<0.1	0.08	2	<0.5	<0.2
REP 1282976	QC		12	0.07	239	0.009	1	0.54	0.007	0.05	<0.1	0.05	0.9	0.1	0.07	2	<0.5	<0.2
1282995	Soil		24	0.10	968	0.002	3	0.96	0.006	0.08	<0.1	0.07	2.4	0.2	0.18	3	3.6	0.2
REP 1282995	QC		24	0.10	1026	0.003	4	0.95	0.006	0.10	<0.1	0.07	2.5	0.2	0.17	3	3.7	<0.2
1284102	Soil		20	0.21	1203	0.004	5	0.83	0.004	0.11	0.2	0.52	2.7	0.4	0.09	2	5.6	<0.2
REP 1284102	QC		19	0.22	1222	0.003	4	0.81	0.004	0.10	0.2	0.56	2.7	0.4	0.07	2	6.4	<0.2
1284110	Soil		24	0.29	1490	0.007	8	0.97	0.009	0.16	0.3	0.37	2.8	0.3	0.18	3	5.1	<0.2
REP 1284110	QC		24	0.29	1479	0.006	10	0.95	0.009	0.14	0.4	0.34	2.9	0.2	0.16	3	5.0	<0.2
1287747	Soil		15	0.10	378	0.004	2	0.61	0.005	0.07	0.1	0.02	1.7	0.2	0.06	2	1.1	<0.2
REP 1287747	QC		14	0.10	373	0.006	3	0.59	0.005	0.07	<0.1	0.02	1.8	0.2	<0.05	2	<0.5	<0.2
1287795	Soil		12	0.04	313	0.003	4	0.28	0.002	0.05	<0.1	0.24	12.0	0.1	<0.05	<1	1.7	0.3
REP 1287795	QC		13	0.05	302	0.002	2	0.29	0.002	0.06	<0.1	0.21	12.4	0.1	<0.05	<1	1.1	<0.2
1288150	Soil		14	0.04	156	0.006	<1	0.62	0.006	0.05	<0.1	0.04	0.6	<0.1	<0.05	3	0.9	<0.2
REP 1288150	QC		12	0.03	150	0.016	<1	0.57	0.006	0.04	<0.1	0.04	0.4	<0.1	<0.05	3	0.6	<0.2
1286460	Soil		9	0.05	141	0.002	<1	0.57	0.008	0.04	<0.1	0.03	1.9	0.1	<0.05	2	<0.5	<0.2
REP 1286460	QC		8	0.04	133	0.002	<1	0.52	0.008	0.04	<0.1	0.03	1.5	0.1	<0.05	2	<0.5	<0.2
1287004	Soil		13	0.14	363	0.002	<1	0.60	0.006	0.05	<0.1	0.04	1.5	<0.1	<0.05	2	1.4	<0.2
REP 1287004	QC		12	0.13	371	0.001	<1	0.59	0.006	0.04	<0.1	0.03	1.5	<0.1	<0.05	2	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

QUALITY CONTROL REPORT WHI11001424.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1287011	Soil	1.6	26.5	17.2	67	0.2	14.7	5.7	130	2.23	10.0	0.9	0.5	11	<0.1	0.8	0.3	44	0.02	0.119	5
REP 1287011	QC	1.6	26.8	17.0	66	0.2	14.2	5.7	132	2.30	10.2	0.9	0.4	11	<0.1	0.8	0.3	46	0.02	0.116	5
1288155	Soil	3.8	44.4	24.1	129	0.4	19.9	5.6	132	4.31	21.3	1.1	1.8	40	0.1	1.8	0.4	46	0.03	0.104	4
REP 1288155	QC	3.7	41.6	23.0	120	0.4	18.8	5.1	125	4.03	20.6	0.5	1.7	39	0.1	1.7	0.4	44	0.03	0.097	4
Reference Materials																					
STD DS8	Standard	14.0	120.5	131.4	329	1.9	41.2	8.3	636	2.59	27.1	118.9	7.2	68	2.7	5.8	7.0	46	0.70	0.087	14
STD DS8	Standard	13.9	112.7	128.6	320	2.0	37.9	7.8	596	2.40	25.9	125.8	7.0	70	2.3	6.2	6.9	41	0.70	0.079	17
STD DS8	Standard	12.4	106.0	115.4	290	1.6	35.4	7.1	567	2.23	23.6	102.1	6.3	67	2.0	5.1	6.2	40	0.65	0.076	14
STD DS8	Standard	12.7	108.8	124.5	306	1.8	37.0	7.6	596	2.43	25.3	121.0	6.4	67	2.5	5.7	6.5	42	0.69	0.078	14
STD DS8	Standard	14.4	117.3	133.3	317	1.8	42.1	7.8	625	2.32	23.2	112.4	7.7	76	2.3	6.2	7.4	45	0.72	0.072	16
STD DS8	Standard	12.9	107.5	120.8	295	1.7	37.6	7.6	575	2.42	23.4	117.4	6.3	67	2.1	5.7	6.8	49	0.66	0.072	14
STD DS8	Standard	13.7	118.8	122.6	318	1.9	40.6	8.3	618	2.42	25.7	117.4	6.5	63	2.5	5.5	6.6	47	0.65	0.086	14
STD DS8	Standard	14.5	113.9	136.9	328	2.0	41.0	7.8	648	2.59	25.4	124.5	7.5	72	2.4	5.4	6.3	45	0.74	0.076	17
STD DS8	Standard	14.0	110.0	126.0	318	1.8	38.2	7.8	589	2.41	23.9	114.5	7.4	77	2.3	6.1	9.0	43	0.70	0.081	19
STD DS8	Standard	13.9	107.7	126.2	313	1.9	37.4	7.4	616	2.69	25.2	152.3	7.6	66	2.1	5.2	6.1	42	0.73	0.078	16
STD DS8	Standard	13.0	107.9	120.9	288	1.8	36.6	7.6	621	2.38	24.5	111.1	6.0	64	2.3	4.8	5.6	42	0.71	0.072	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 14, 2011

QUALITY CONTROL REPORT WHI11001424.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1287011	Soil	21	0.06	164	0.003	1	0.97	0.009	0.05	<0.1	0.04	1.0	<0.1	0.06	4	0.8	<0.2
REP 1287011	QC	20	0.06	168	0.003	<1	0.93	0.009	0.06	<0.1	0.05	1.0	0.1	0.06	4	0.7	<0.2
1288155	Soil	18	0.09	492	0.002	1	0.94	0.006	0.06	<0.1	0.04	2.5	0.2	0.06	3	2.4	<0.2
REP 1288155	QC	17	0.09	468	0.002	2	0.86	0.005	0.05	<0.1	0.03	2.3	0.2	<0.05	3	2.2	0.2
Reference Materials																	
STD DS8	Standard	124	0.64	290	0.124	2	0.95	0.097	0.44	3.2	0.21	2.5	5.8	0.13	5	6.0	5.2
STD DS8	Standard	115	0.60	285	0.126	2	0.92	0.088	0.42	3.0	0.24	2.6	5.8	0.17	5	5.3	5.0
STD DS8	Standard	113	0.58	262	0.117	2	0.96	0.105	0.43	2.7	0.19	2.9	5.0	0.19	5	4.7	4.6
STD DS8	Standard	114	0.60	270	0.113	2	0.95	0.103	0.44	2.9	0.20	3.0	5.5	0.16	5	5.0	4.9
STD DS8	Standard	131	0.67	275	0.126	2	0.92	0.100	0.43	2.8	0.21	2.8	5.4	0.18	5	4.3	4.5
STD DS8	Standard	111	0.58	255	0.116	1	0.89	0.099	0.40	2.9	0.21	2.1	5.2	0.16	5	4.3	5.4
STD DS8	Standard	125	0.62	275	0.120	2	0.87	0.090	0.40	3.0	0.19	2.1	5.4	0.13	5	5.6	4.9
STD DS8	Standard	125	0.64	307	0.129	4	0.97	0.096	0.47	3.1	0.20	3.3	6.0	0.14	5	4.6	4.9
STD DS8	Standard	117	0.59	273	0.131	3	0.88	0.082	0.38	2.8	0.21	2.6	5.4	0.19	5	4.8	4.8
STD DS8	Standard	118	0.64	281	0.122	3	0.94	0.097	0.42	2.9	0.20	2.6	5.5	0.16	5	4.7	5.6
STD DS8	Standard	113	0.61	279	0.116	3	0.95	0.098	0.40	2.9	0.18	2.9	5.3	0.12	4	5.1	4.6
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 09, 2011
Report Date: January 19, 2012
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001425.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #25
P.O. Number
Number of Samples: 309

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	309	Sieve soil to 230 mesh			WHI
RJSV	309	Saving all or part of Soil Reject			WHI
1DX2	300	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Version 2: Sample ID Revision - Sample 1276080 revised to 1286080

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287608	Soil		1.1	11.2	6.9	39	0.4	11.1	2.4	37	0.62	3.6	2.1	0.4	16	0.3	0.7	0.1	11	0.13	0.033	1
1287609	Soil		1.4	8.3	7.2	12	0.2	8.8	8.5	224	0.96	3.5	0.5	<0.1	40	0.1	0.5	<0.1	8	0.46	0.064	2
1287610	Soil		0.8	4.3	2.9	20	0.4	4.8	0.7	15	0.40	2.5	0.6	0.1	14	<0.1	0.4	<0.1	7	0.13	0.021	<1
1287611	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287612	Soil		4.8	23.5	13.5	97	0.9	35.3	19.8	955	1.68	10.3	2.5	0.8	74	0.9	2.4	0.2	25	0.66	0.101	3
1287613	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287614	Soil		7.3	35.2	16.4	154	0.6	39.7	11.5	260	1.61	15.8	2.4	0.9	44	2.4	3.8	0.2	41	0.33	0.105	5
1287615	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287616	Soil		9.6	44.1	38.4	133	1.9	47.7	5.2	94	2.12	39.0	7.0	0.7	48	0.7	4.0	0.2	57	0.18	0.164	5
1287617	Soil		2.5	27.2	30.5	58	1.7	26.8	2.7	83	1.03	15.2	4.5	0.3	58	0.1	1.8	0.1	29	0.61	0.143	2
1287618	Soil		5.3	33.3	29.7	161	0.8	41.8	8.4	142	2.30	21.6	6.0	1.6	49	0.8	3.7	0.2	46	0.40	0.162	7
1287619	Soil		6.4	27.4	22.5	121	0.6	29.3	6.4	111	2.00	21.6	5.1	0.8	27	0.5	3.2	0.2	51	0.15	0.075	6
1287620	Soil		2.2	9.8	6.1	33	1.5	7.6	1.8	29	0.80	6.9	0.8	<0.1	6	0.1	1.1	0.1	22	0.02	0.031	3
1287621	Soil		1.1	9.5	5.3	13	0.8	4.8	0.7	12	0.32	2.7	<0.5	<0.1	6	0.1	0.5	<0.1	8	0.03	0.033	1
1287622	Soil		6.0	34.5	17.6	92	0.8	23.8	4.7	71	2.22	17.3	2.5	0.3	9	0.2	3.6	0.2	37	0.02	0.076	4
1287623	Soil		7.7	54.4	28.9	181	0.6	45.7	7.7	125	2.68	32.4	3.9	1.2	15	0.8	4.6	0.2	52	0.07	0.083	5
1287624	Soil		8.1	94.4	24.3	311	0.9	85.5	20.7	337	6.42	22.8	2.6	1.4	10	1.1	4.9	0.4	82	0.07	0.132	4
1287625	Soil		21.4	164.9	25.9	1508	1.5	185.9	18.5	295	4.94	42.5	6.5	2.2	31	8.9	10.0	0.3	96	0.09	0.108	10
1287626	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287627	Soil		18.9	168.0	18.4	2963	1.4	259.0	19.8	146	5.13	32.1	2.5	3.4	40	21.9	7.1	0.2	88	0.37	0.137	9
1287628	Soil		15.2	85.2	21.7	814	1.1	116.7	18.3	212	3.76	37.9	4.9	3.0	44	5.4	7.9	0.3	73	0.22	0.155	12
1287629	Soil		3.8	13.1	11.9	162	0.3	22.2	5.1	72	1.81	12.0	1.5	0.4	11	0.3	1.9	0.2	43	0.04	0.090	5
1287630	Soil		8.3	41.1	21.1	300	0.4	52.2	12.3	239	3.20	28.1	2.5	3.3	50	1.6	5.1	0.3	48	0.20	0.130	10
1287541	Soil		2.8	25.4	21.2	81	0.2	19.8	5.2	91	3.66	18.1	1.9	1.7	17	<0.1	1.3	0.3	37	0.01	0.065	3
1287542	Soil		3.4	17.8	19.5	82	0.1	18.8	4.9	91	3.98	23.6	<0.5	2.0	10	<0.1	1.9	0.3	49	0.01	0.041	4
1287543	Soil		3.7	21.0	20.3	108	0.1	23.3	5.0	109	3.64	24.4	1.4	1.3	10	0.2	1.9	0.2	38	0.02	0.069	4
1287544	Soil		1.5	9.0	5.6	23	0.1	5.6	1.5	20	0.73	6.0	<0.5	<0.1	5	<0.1	0.5	<0.1	16	0.01	0.046	3
1287545	Soil		3.1	14.1	18.8	57	0.1	12.4	3.3	58	3.69	20.0	<0.5	0.6	10	<0.1	1.6	0.3	54	0.02	0.089	3
1287546	Soil		3.4	13.6	13.5	56	0.1	11.3	2.8	56	3.05	18.1	2.1	1.7	9	<0.1	1.7	0.3	47	0.01	0.041	5
1287547	Soil		2.7	13.6	15.2	53	<0.1	9.3	2.6	60	2.25	14.7	0.6	1.1	10	<0.1	1.2	0.2	51	0.01	0.062	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287608	Soil	8	0.07	276	0.004	2	0.42	0.019	0.04	<0.1	0.10	1.2	0.1	0.10	1	0.8	<0.2
1287609	Soil	4	0.07	358	0.008	2	0.34	0.033	0.02	<0.1	0.07	0.7	<0.1	0.09	1	1.1	<0.2
1287610	Soil	3	0.05	147	0.003	2	0.22	0.029	0.03	<0.1	0.06	0.4	<0.1	<0.05	<1	0.6	<0.2
1287611	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287612	Soil	16	0.18	1041	0.005	5	0.69	0.018	0.05	<0.1	0.18	2.2	0.2	0.14	2	2.8	<0.2
1287613	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287614	Soil	18	0.12	711	0.004	2	0.59	0.008	0.07	0.1	0.07	1.6	0.3	0.10	2	1.9	<0.2
1287615	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287616	Soil	18	0.07	1371	0.005	3	0.95	0.012	0.07	<0.1	0.21	2.2	0.3	0.14	3	3.9	<0.2
1287617	Soil	13	0.09	546	0.004	2	0.50	0.018	0.04	<0.1	0.27	1.7	0.3	0.13	1	2.2	<0.2
1287618	Soil	17	0.15	733	0.007	3	0.59	0.005	0.06	<0.1	0.15	3.1	0.2	0.10	2	2.9	<0.2
1287619	Soil	17	0.08	567	0.004	2	0.53	0.006	0.05	<0.1	0.07	1.8	0.2	0.05	2	1.6	<0.2
1287620	Soil	5	0.02	106	0.006	<1	0.23	0.016	0.03	<0.1	0.04	0.5	<0.1	<0.05	1	0.5	<0.2
1287621	Soil	4	0.01	97	0.004	<1	0.20	0.022	0.03	<0.1	0.04	0.4	<0.1	<0.05	<1	<0.5	<0.2
1287622	Soil	11	0.03	131	0.003	1	0.41	0.006	0.03	<0.1	0.06	1.6	0.2	<0.05	2	1.7	<0.2
1287623	Soil	21	0.06	497	0.006	3	0.55	0.005	0.06	<0.1	0.10	2.9	0.2	0.07	2	1.9	<0.2
1287624	Soil	27	0.06	164	0.006	3	0.49	0.004	0.06	<0.1	0.06	6.4	0.4	0.06	2	2.1	<0.2
1287625	Soil	28	0.11	765	0.004	3	1.24	0.004	0.06	<0.1	0.52	5.3	0.5	<0.05	2	4.0	<0.2
1287626	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287627	Soil	33	0.19	1461	0.006	3	2.94	0.005	0.07	<0.1	0.51	5.8	0.8	<0.05	2	5.8	<0.2
1287628	Soil	21	0.16	2347	0.009	2	0.97	0.005	0.06	0.1	0.36	3.8	0.3	<0.05	2	3.5	<0.2
1287629	Soil	14	0.09	350	0.010	1	0.69	0.009	0.04	0.2	0.08	0.8	0.2	0.06	3	1.0	<0.2
1287630	Soil	19	0.20	2296	0.009	2	0.71	0.003	0.05	0.1	0.13	2.9	0.3	<0.05	2	2.2	<0.2
1287541	Soil	23	0.21	106	0.003	1	1.13	0.006	0.06	<0.1	0.04	1.9	0.2	<0.05	5	1.1	<0.2
1287542	Soil	20	0.15	129	0.004	1	0.96	0.003	0.04	<0.1	0.02	1.9	0.2	<0.05	4	0.8	<0.2
1287543	Soil	19	0.13	123	0.002	2	0.87	0.003	0.04	<0.1	0.03	1.7	0.2	<0.05	3	1.2	<0.2
1287544	Soil	5	0.02	90	0.004	1	0.32	0.013	0.02	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2
1287545	Soil	19	0.08	97	0.004	<1	0.73	0.004	0.04	<0.1	0.03	1.2	0.2	<0.05	5	0.7	<0.2
1287546	Soil	15	0.06	126	0.005	<1	0.75	0.003	0.04	0.1	0.02	1.3	0.1	<0.05	4	0.6	<0.2
1287547	Soil	11	0.04	146	0.003	1	0.82	0.004	0.05	<0.1	0.02	1.4	0.2	<0.05	4	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287548	Soil		1.1	5.3	4.9	21	0.2	3.9	1.1	17	0.54	5.1	0.5	0.1	5	<0.1	0.5	<0.1	20	0.01	0.030	3
1287549	Soil		0.4	2.9	2.7	6	0.3	1.4	0.5	7	0.25	1.2	0.6	<0.1	4	<0.1	0.1	<0.1	7	0.01	0.019	<1
1287550	Soil		3.4	12.8	10.6	46	0.2	12.4	1.8	31	1.22	10.8	3.3	0.7	20	0.3	1.8	0.1	26	0.03	0.044	2
1287551	Soil		5.3	27.2	21.8	964	0.8	202.6	66.9	1293	4.94	15.4	2.9	1.1	98	1.7	5.3	0.2	20	0.28	0.040	2
1287552	Soil		5.1	24.9	23.1	122	0.3	23.8	5.8	104	2.69	30.8	1.5	0.4	15	0.2	3.3	0.3	56	0.02	0.076	7
1287553	Soil		2.2	10.1	8.2	33	<0.1	7.5	1.7	31	0.68	9.2	1.2	0.4	10	<0.1	0.9	0.1	28	0.02	0.029	8
1287554	Soil		4.9	24.2	20.2	128	0.1	23.6	5.4	84	3.26	32.3	2.1	1.6	17	0.4	3.1	0.3	46	0.01	0.069	6
1287555	Soil		2.5	7.0	10.6	22	0.3	7.4	1.3	22	0.95	7.2	2.6	0.6	12	<0.1	0.8	0.1	22	0.02	0.032	2
1287556	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287557	Soil		1.4	6.6	5.6	31	0.5	6.7	1.4	30	0.65	6.3	0.6	0.1	8	0.1	0.7	<0.1	17	0.02	0.032	3
1287558	Soil		0.2	3.6	1.5	6	0.6	2.5	0.6	11	0.31	0.7	1.4	<0.1	6	<0.1	<0.1	<0.1	4	0.02	0.018	<1
1287559	Soil		4.0	21.5	18.6	115	0.2	25.7	6.4	147	2.84	23.2	3.3	0.8	17	0.2	2.4	0.2	44	0.06	0.102	6
1287560	Soil		4.2	22.1	17.6	106	0.2	21.4	6.4	164	2.46	27.5	1.7	0.8	13	0.3	2.5	0.3	43	0.02	0.094	5
1287561	Soil		5.1	17.7	16.1	79	0.7	16.0	4.1	74	1.72	17.2	2.3	0.5	18	0.1	2.0	0.3	43	0.02	0.064	7
1287562	Soil		3.6	15.5	14.2	74	0.2	15.1	3.3	48	2.16	20.6	2.2	0.9	10	<0.1	1.8	0.2	53	0.01	0.058	5
1287563	Soil		3.9	26.7	23.8	122	0.5	25.8	6.0	134	3.33	26.2	3.5	1.3	12	0.2	2.8	0.3	50	0.02	0.096	5
1287564	Soil		4.2	16.7	17.3	96	0.3	16.5	4.4	85	2.99	26.1	2.2	1.2	13	0.1	2.9	0.2	42	0.01	0.072	4
1287565	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287566	Soil		1.0	9.2	4.1	17	0.5	7.4	0.8	11	0.39	2.9	0.6	0.2	7	0.3	0.4	<0.1	11	0.02	0.039	2
1287567	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287568	Soil		1.0	8.9	4.5	11	1.4	4.3	0.6	10	0.28	1.5	0.6	<0.1	8	<0.1	0.4	<0.1	9	0.03	0.048	1
1287569	Soil		<0.1	1.2	1.5	2	0.2	0.9	0.3	5	0.14	<0.5	0.7	<0.1	6	<0.1	<0.1	<0.1	3	0.02	0.024	<1
1287570	Soil		4.2	21.5	14.8	97	0.5	18.4	3.9	62	1.87	20.2	2.3	0.7	11	0.2	2.4	0.2	36	0.02	0.082	5
1288081	Soil		5.5	17.8	18.2	133	0.3	24.1	4.4	79	2.08	17.6	1.5	1.3	43	0.5	4.0	0.2	23	0.09	0.051	2
1288082	Soil		4.2	19.0	14.4	72	0.2	18.8	4.6	82	1.72	16.3	1.0	1.2	43	0.4	2.0	0.2	18	0.09	0.046	3
1288083	Soil		5.7	27.6	19.6	110	0.6	24.9	5.6	92	1.98	19.1	0.6	1.6	79	0.6	4.0	0.2	26	0.15	0.085	3
1288084	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1288085	Soil		23.5	76.2	36.4	540	5.4	136.7	19.7	332	4.59	39.7	2.5	4.8	226	4.2	22.3	0.3	249	1.01	0.583	14
1288086	Soil		2.5	19.5	10.0	22	2.9	10.1	0.7	10	1.10	3.0	3.8	0.7	34	0.1	1.2	0.2	22	0.07	0.030	2
1288087	Soil		2.1	30.3	22.2	110	0.9	28.0	8.3	257	2.67	13.8	3.6	0.9	49	0.2	1.1	0.2	30	0.04	0.143	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287548	Soil	4	0.01	78	0.003	<1	0.34	0.009	0.02	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2
1287549	Soil	2	<0.01	57	0.004	<1	0.17	0.016	0.02	<0.1	0.01	0.3	<0.1	<0.05	<1	<0.5	<0.2
1287550	Soil	14	0.04	594	0.002	3	0.47	0.009	0.05	<0.1	0.08	1.3	0.2	<0.05	2	1.0	<0.2
1287551	Soil	11	0.05	1830	0.001	4	0.54	0.007	0.08	<0.1	0.22	3.5	0.5	0.09	1	2.9	<0.2
1287552	Soil	12	0.05	170	0.006	1	0.49	0.004	0.06	0.1	0.04	1.1	0.3	<0.05	4	1.8	<0.2
1287553	Soil	8	0.02	97	0.003	2	0.33	0.005	0.03	<0.1	0.02	0.5	0.1	<0.05	2	0.5	<0.2
1287554	Soil	13	0.05	180	0.006	1	0.52	0.003	0.05	0.1	0.03	1.6	0.2	0.06	3	1.6	<0.2
1287555	Soil	12	0.04	267	0.003	2	0.52	0.015	0.05	<0.1	0.13	0.9	0.3	0.06	2	1.4	<0.2
1287556	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287557	Soil	6	0.02	103	0.005	<1	0.24	0.010	0.03	<0.1	0.02	0.4	<0.1	<0.05	1	<0.5	<0.2
1287558	Soil	2	0.01	77	0.006	<1	0.23	0.022	0.02	<0.1	0.04	0.5	<0.1	<0.05	<1	<0.5	<0.2
1287559	Soil	19	0.15	362	0.003	<1	0.81	0.004	0.04	0.1	0.05	1.4	0.2	<0.05	3	1.5	<0.2
1287560	Soil	11	0.05	251	0.002	1	0.53	0.003	0.04	<0.1	0.04	1.3	0.1	<0.05	2	1.4	<0.2
1287561	Soil	12	0.05	295	0.004	1	0.49	0.004	0.04	<0.1	0.04	0.9	0.2	<0.05	3	1.6	<0.2
1287562	Soil	13	0.02	167	0.002	2	0.52	0.004	0.03	<0.1	0.02	1.1	0.1	<0.05	4	1.1	<0.2
1287563	Soil	19	0.09	204	0.006	2	0.68	0.006	0.05	0.1	0.06	1.9	0.2	<0.05	3	1.2	<0.2
1287564	Soil	11	0.03	111	0.003	<1	0.45	0.002	0.04	<0.1	0.01	1.6	0.1	<0.05	3	1.5	<0.2
1287565	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287566	Soil	4	0.01	121	0.003	<1	0.28	0.014	0.02	<0.1	0.06	0.3	<0.1	<0.05	1	0.7	<0.2
1287567	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287568	Soil	5	<0.01	100	0.003	1	0.21	0.015	0.03	<0.1	0.02	0.2	<0.1	<0.05	1	0.6	<0.2
1287569	Soil	2	<0.01	32	0.004	<1	0.14	0.021	0.02	<0.1	0.02	0.3	<0.1	<0.05	<1	<0.5	<0.2
1287570	Soil	10	0.04	221	0.002	2	0.50	0.006	0.04	<0.1	0.08	1.3	0.2	<0.05	2	2.1	<0.2
1288081	Soil	13	0.06	1467	0.002	3	0.38	0.006	0.11	<0.1	0.07	2.3	0.5	0.17	1	2.4	<0.2
1288082	Soil	11	0.08	994	0.001	3	0.42	0.006	0.09	<0.1	0.07	2.2	0.3	0.15	2	1.9	<0.2
1288083	Soil	11	0.05	917	<0.001	3	0.44	0.005	0.11	<0.1	0.13	4.3	0.5	0.18	1	2.6	<0.2
1288084	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1288085	Soil	80	0.59	854	0.033	6	1.60	0.018	0.35	0.1	0.30	6.3	0.9	0.40	5	18.1	<0.2
1288086	Soil	15	<0.01	837	<0.001	5	0.22	0.006	0.11	<0.1	0.13	1.1	0.2	0.23	2	6.7	<0.2
1288087	Soil	22	0.12	1072	0.003	3	0.83	0.009	0.13	<0.1	0.07	3.0	0.2	0.14	2	2.6	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288088	Soil	1.0	27.4	20.8	112	0.3	33.6	15.2	548	2.55	14.8	5.1	0.6	23	0.2	0.7	0.3	30	0.05	0.163	4
1288089	Soil	1.3	21.3	20.9	46	0.7	10.6	3.4	140	1.62	12.1	2.1	0.9	46	<0.1	1.2	0.2	24	0.02	0.116	4
1288090	Soil	12.4	20.7	17.9	210	1.1	39.1	6.2	353	2.79	16.1	3.5	0.3	72	2.3	5.5	0.2	65	0.10	0.288	4
1283261	Soil	1.6	12.1	9.7	60	0.3	15.3	5.9	164	1.47	7.9	0.8	0.5	15	0.1	1.2	0.1	22	0.07	0.049	2
1283262	Soil	0.9	9.6	5.6	25	0.1	6.1	1.2	37	0.50	1.2	<0.5	<0.1	7	0.3	0.4	<0.1	12	0.04	0.046	1
1283263	Soil	2.7	25.6	15.0	98	0.1	34.7	11.1	249	1.96	15.0	1.3	1.1	26	0.3	1.9	0.2	19	0.13	0.042	4
1283264	Soil	0.6	6.9	4.3	25	<0.1	5.9	2.1	109	0.60	2.5	<0.5	<0.1	9	0.3	0.3	<0.1	8	0.04	0.073	<1
1283265	Soil	3.6	14.3	17.3	60	<0.1	20.5	5.2	94	1.57	18.7	0.5	1.2	31	0.2	2.5	0.2	10	0.09	0.035	2
1283266	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283267	Soil	0.3	1.7	1.8	9	<0.1	2.2	0.6	12	0.21	1.0	<0.5	<0.1	10	0.1	0.2	<0.1	4	0.05	0.018	<1
1283268	Soil	2.9	18.5	12.4	113	0.4	24.5	4.5	134	1.51	12.6	1.8	0.9	41	0.5	2.4	0.2	26	0.30	0.101	4
1283191	Soil	4.3	42.7	18.8	121	2.0	36.5	5.0	75	3.04	91.4	14.6	0.7	37	0.2	3.4	0.3	46	0.02	0.083	4
1283192	Soil	2.4	31.4	8.9	66	0.9	24.8	3.6	40	1.53	45.6	4.3	0.3	16	0.1	1.9	0.2	29	0.03	0.053	2
1283193	Soil	1.8	14.2	5.0	37	1.0	12.8	1.8	22	0.81	67.8	2.4	<0.1	10	<0.1	2.2	<0.1	19	0.02	0.047	1
1283194	Soil	3.4	42.8	14.9	89	1.1	31.0	4.1	44	2.18	55.0	6.4	0.8	29	0.1	2.7	0.2	35	0.02	0.057	3
1283195	Soil	2.2	14.3	5.7	38	0.4	10.0	1.6	19	0.81	19.1	2.0	0.2	9	<0.1	1.4	0.1	25	<0.01	0.039	5
1283196	Soil	6.5	33.1	11.0	73	3.1	25.4	2.2	34	1.45	26.9	7.2	0.5	37	0.4	2.4	0.3	30	0.02	0.070	3
1283197	Soil	4.1	51.3	19.4	161	1.3	51.3	6.3	145	2.88	339.0	6.3	2.1	103	1.1	22.1	0.3	59	1.72	0.153	6
1276071	Soil	23.1	48.3	21.4	219	0.4	69.3	11.6	120	3.20	43.9	2.6	0.6	35	0.6	8.5	0.3	188	0.06	0.084	9
1276072	Soil	3.8	13.6	3.8	26	0.2	11.3	3.2	43	1.10	6.9	0.7	<0.1	3	<0.1	1.6	<0.1	22	0.01	0.032	3
1276073	Soil	8.2	33.2	11.9	130	<0.1	45.4	6.7	68	1.86	14.6	1.7	0.2	8	0.2	3.4	0.2	62	0.02	0.055	5
1276074	Soil	18.2	47.2	19.1	194	0.5	65.5	10.7	130	2.82	32.3	2.7	0.4	40	0.7	6.9	0.2	137	0.08	0.114	8
1276075	Soil	12.1	79.9	20.3	318	0.9	91.7	14.3	263	3.22	24.9	1.9	2.7	105	1.9	7.2	0.2	78	0.36	0.180	8
1286080	Soil	5.0	24.2	13.2	114	0.4	22.3	3.4	137	1.78	16.7	3.8	0.3	25	0.7	2.2	0.2	77	0.07	0.111	7
1281221	Soil	2.3	20.6	12.9	36	0.2	11.4	11.3	498	1.69	6.1	1.0	1.6	19	0.2	0.6	0.2	27	0.24	0.086	11
1281222	Soil	8.1	102.8	32.2	173	1.0	36.2	8.7	165	4.90	22.8	4.6	1.4	31	0.2	6.3	0.4	67	0.01	0.106	3
1281223	Soil	5.1	42.8	18.5	39	1.6	12.8	2.9	104	2.63	46.0	5.8	1.8	65	0.1	6.6	0.3	47	0.01	0.082	6
1281224	Soil	3.2	31.2	10.8	29	3.0	9.7	2.2	108	1.96	52.2	10.3	1.2	122	<0.1	11.5	0.2	33	0.06	0.131	9
1281225	Soil	5.2	25.0	11.7	39	1.2	8.5	2.3	217	1.71	36.1	3.2	0.2	65	<0.1	3.8	0.2	65	0.03	0.121	6
1274076	Soil	9.7	21.3	19.6	121	0.5	21.0	3.1	90	1.81	23.7	2.0	0.6	36	0.7	4.3	0.2	101	0.15	0.117	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288088	Soil	29	0.15	480	0.004	3	0.90	0.007	0.10	<0.1	0.05	1.7	<0.1	0.10	3	1.5	<0.2
1288089	Soil	17	0.04	939	<0.001	2	0.53	0.005	0.09	<0.1	0.04	2.1	0.1	0.13	2	2.6	<0.2
1288090	Soil	20	0.04	622	0.003	4	0.68	0.010	0.10	<0.1	0.12	0.7	0.2	0.17	2	3.4	<0.2
1283261	Soil	11	0.09	330	0.003	<1	0.55	0.012	0.04	<0.1	0.02	1.0	<0.1	<0.05	2	0.5	<0.2
1283262	Soil	9	0.02	70	0.008	5	0.25	0.015	0.03	<0.1	0.02	0.4	<0.1	<0.05	2	0.6	<0.2
1283263	Soil	12	0.09	215	0.002	<1	0.45	0.006	0.05	<0.1	0.04	2.2	0.2	<0.05	1	1.0	<0.2
1283264	Soil	7	0.02	74	0.002	<1	0.23	0.018	0.03	<0.1	0.02	0.2	<0.1	<0.05	1	<0.5	<0.2
1283265	Soil	9	0.05	290	<0.001	3	0.20	0.003	0.05	<0.1	0.09	2.1	0.2	<0.05	<1	0.8	<0.2
1283266	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283267	Soil	3	0.02	35	0.004	<1	0.10	0.026	0.02	<0.1	<0.01	0.2	<0.1	<0.05	<1	0.5	<0.2
1283268	Soil	11	0.14	482	0.003	2	0.75	0.013	0.06	<0.1	0.19	1.9	0.2	<0.05	2	1.5	<0.2
1283191	Soil	20	0.03	512	0.003	1	0.66	0.003	0.06	<0.1	2.11	1.9	0.2	<0.05	3	3.0	<0.2
1283192	Soil	13	0.02	375	0.002	3	0.50	0.010	0.04	<0.1	0.22	0.9	<0.1	0.08	2	1.1	<0.2
1283193	Soil	8	0.01	135	0.002	2	0.26	0.011	0.03	<0.1	0.44	0.3	<0.1	<0.05	2	0.8	<0.2
1283194	Soil	19	0.02	513	0.001	4	0.49	0.004	0.07	<0.1	0.29	2.2	0.1	0.11	2	2.2	<0.2
1283195	Soil	9	0.01	224	0.002	2	0.35	0.005	0.04	<0.1	0.10	0.3	<0.1	<0.05	2	0.9	<0.2
1283196	Soil	19	0.02	664	0.002	5	0.51	0.009	0.06	<0.1	0.50	1.8	0.1	<0.05	2	2.7	<0.2
1283197	Soil	38	0.09	3189	0.002	9	0.90	0.010	0.14	<0.1	6.01	4.1	0.2	0.20	3	2.0	<0.2
1276071	Soil	26	0.04	561	0.003	2	0.49	0.003	0.08	0.1	0.07	1.6	0.6	0.15	3	3.4	<0.2
1276072	Soil	5	0.02	83	0.003	2	0.20	0.010	0.04	<0.1	0.03	0.3	<0.1	<0.05	1	<0.5	<0.2
1276073	Soil	17	0.03	272	0.002	2	0.45	0.004	0.05	<0.1	0.04	0.9	0.1	<0.05	2	0.7	<0.2
1276074	Soil	22	0.05	657	0.005	2	0.55	0.006	0.08	0.1	0.12	1.5	0.4	0.07	2	2.6	<0.2
1276075	Soil	21	0.07	2185	0.005	4	0.51	0.002	0.08	<0.1	0.24	4.5	0.2	<0.05	1	2.6	<0.2
1286080	Soil	25	0.14	511	0.004	3	0.93	0.009	0.07	0.1	0.27	0.8	0.3	<0.05	4	1.5	<0.2
1281221	Soil	15	0.26	173	0.005	2	0.77	0.012	0.08	<0.1	0.09	2.3	0.1	<0.05	3	<0.5	<0.2
1281222	Soil	22	0.09	197	0.002	1	0.87	0.003	0.10	<0.1	0.06	4.5	0.4	0.07	3	5.2	<0.2
1281223	Soil	16	0.06	471	0.003	2	0.53	0.004	0.15	<0.1	0.02	2.8	0.5	0.24	3	4.5	<0.2
1281224	Soil	15	0.07	257	0.005	2	0.47	0.008	0.07	<0.1	0.05	2.4	0.4	0.13	2	3.7	<0.2
1281225	Soil	20	0.06	927	0.008	2	0.65	0.010	0.08	0.1	0.02	0.7	0.4	0.13	3	4.0	<0.2
1274076	Soil	19	0.08	855	0.004	4	0.63	0.004	0.09	<0.1	0.20	1.4	0.5	<0.05	3	2.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274077	Soil	9.0	28.3	19.4	138	0.8	30.5	8.4	234	2.28	27.1	4.1	0.8	29	0.6	3.7	0.2	74	0.15	0.095	6
1274078	Soil	6.9	30.2	18.7	169	0.7	39.1	8.3	167	3.03	25.2	3.4	0.9	25	0.4	2.9	0.3	45	0.10	0.070	6
1274079	Soil	7.9	34.8	18.3	167	0.5	41.8	9.8	210	2.93	30.3	4.3	0.9	28	0.7	3.8	0.2	40	0.11	0.077	6
1274080	Soil	25.7	27.5	24.4	200	0.9	58.4	12.7	610	3.70	118.0	5.9	0.5	85	4.5	12.1	0.2	115	0.09	0.279	7
1276221	Soil	7.6	44.9	27.3	101	2.0	33.8	4.1	44	2.83	31.7	7.4	0.8	32	1.1	3.6	0.4	96	0.17	0.177	8
1276222	Soil	31.5	73.7	16.4	760	0.7	163.9	17.4	470	4.35	37.0	2.3	2.8	119	6.5	8.8	0.1	144	3.12	0.273	14
1276223	Soil	1.1	11.9	4.1	28	1.0	10.5	1.6	45	0.63	5.0	1.4	0.1	11	0.3	1.0	<0.1	16	0.12	0.069	3
1276224	Soil	6.1	69.0	26.6	157	1.2	77.7	14.3	487	3.29	35.8	6.3	2.7	55	1.2	7.8	0.3	33	0.64	0.144	12
1276225	Soil	11.4	69.6	19.5	230	0.6	87.3	12.4	152	3.37	29.7	3.5	1.8	62	1.2	11.8	0.2	65	0.38	0.192	14
1283311	Soil	4.8	16.8	22.4	117	0.3	32.8	13.3	109	1.72	15.0	1.4	0.3	12	0.3	1.5	0.2	63	0.02	0.049	7
1283312	Soil	6.4	45.1	23.6	199	0.1	57.8	13.9	314	5.30	37.0	1.7	1.7	26	0.7	2.2	0.3	44	0.04	0.129	3
1283313	Soil	15.4	42.1	20.1	259	0.4	55.4	7.5	216	2.96	38.9	4.3	2.2	33	1.6	6.3	0.3	142	0.13	0.121	16
1283314	Soil	15.1	51.2	16.3	269	0.3	59.7	10.2	281	2.58	38.9	5.3	2.8	48	1.7	6.5	0.2	113	0.27	0.128	18
1283315	Soil	14.6	21.6	13.2	95	0.5	21.8	2.6	75	1.70	25.1	2.6	0.4	14	0.6	4.4	0.2	141	0.04	0.053	12
1283316	Soil	11.8	8.7	5.1	66	0.5	18.2	1.2	20	0.51	9.9	1.5	0.1	7	0.3	3.2	<0.1	87	0.02	0.024	6
1283317	Soil	17.9	21.4	21.3	192	0.4	39.8	4.9	138	2.47	40.2	1.4	1.7	19	0.8	5.8	0.2	145	0.04	0.091	12
1283318	Soil	10.3	13.7	12.6	88	0.4	19.8	3.2	77	1.49	24.5	1.9	0.8	12	0.3	3.1	0.2	86	0.04	0.034	14
1283319	Soil	13.8	25.8	18.4	184	0.3	40.2	6.0	170	2.59	35.7	3.4	1.9	19	0.8	4.3	0.2	104	0.05	0.085	13
1283320	Soil	15.4	33.2	13.5	178	0.6	37.8	5.4	150	1.92	38.3	3.2	0.7	27	1.2	5.1	0.2	90	0.13	0.094	12
1283321	Soil	26.3	63.4	14.2	2269	1.2	242.9	11.0	1004	2.42	35.8	4.8	1.6	60	9.5	8.6	0.2	109	0.68	0.119	13
1283322	Soil	14.6	45.3	10.6	501	0.7	83.9	7.6	277	2.07	50.9	5.6	2.0	70	4.1	4.9	0.2	74	0.88	0.121	10
1283323	Soil	13.7	28.4	13.8	273	0.3	63.5	13.5	293	2.32	77.3	3.5	2.0	39	0.9	4.3	0.2	39	0.41	0.072	12
1283324	Soil	50.7	63.4	16.1	532	0.7	164.0	9.0	260	2.83	59.0	3.0	2.1	93	3.9	7.9	0.2	95	2.53	0.127	13
1283325	Soil	17.7	41.4	15.1	300	0.5	67.4	8.8	217	2.43	29.8	2.0	2.2	40	1.7	5.3	0.2	78	0.55	0.112	14
1283326	Soil	28.8	73.3	18.3	507	1.1	120.2	14.2	231	3.43	38.2	2.9	5.2	44	3.6	9.2	0.2	106	1.25	0.094	14
1283327	Soil	11.5	30.0	14.9	169	0.7	39.7	5.9	99	1.94	30.1	3.1	1.1	20	0.5	4.5	0.2	62	0.09	0.074	12
1283328	Soil	4.7	51.5	16.0	112	0.3	41.3	10.0	423	4.34	21.0	3.9	0.4	8	0.3	2.5	0.3	53	0.06	0.077	4
1283329	Soil	3.4	81.0	19.6	32	1.3	51.4	19.2	619	3.91	29.7	4.0	0.8	16	0.1	3.1	0.4	51	0.16	0.093	3
1283330	Soil	3.3	57.3	19.1	33	0.8	30.7	12.2	429	2.99	40.9	2.4	0.6	12	0.1	2.4	0.3	41	0.03	0.072	3
1284421	Soil	1.8	3.9	3.4	32	0.5	4.2	1.0	14	0.46	4.7	0.5	0.3	5	<0.1	1.4	<0.1	30	0.02	0.024	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274077	Soil	17	0.08	1035	0.003	2	0.68	0.004	0.08	<0.1	0.39	2.4	0.6	<0.05	2	2.9	<0.2
1274078	Soil	14	0.09	1221	0.002	<1	0.67	0.004	0.05	<0.1	0.26	2.8	0.6	<0.05	2	2.9	<0.2
1274079	Soil	11	0.07	1945	0.003	1	0.49	0.004	0.07	<0.1	0.27	3.4	0.6	<0.05	1	1.1	<0.2
1274080	Soil	13	0.05	943	0.003	1	0.58	0.005	0.07	<0.1	1.17	1.2	2.0	0.12	2	3.8	<0.2
1276221	Soil	18	0.11	1909	0.004	3	1.12	0.011	0.10	<0.1	0.45	2.4	0.4	0.09	3	4.2	<0.2
1276222	Soil	23	1.13	1785	0.005	3	0.52	0.005	0.06	<0.1	0.25	3.5	0.6	0.16	<1	3.6	<0.2
1276223	Soil	5	0.03	472	0.007	1	0.38	0.024	0.04	<0.1	0.12	0.7	<0.1	0.05	2	<0.5	<0.2
1276224	Soil	14	0.09	1425	0.002	1	0.52	0.007	0.07	<0.1	0.24	5.2	0.2	0.07	1	1.5	<0.2
1276225	Soil	27	0.06	964	0.003	3	0.45	0.005	0.08	<0.1	0.11	3.3	0.2	0.06	1	1.4	<0.2
1283311	Soil	13	0.04	116	0.004	1	0.42	0.006	0.03	<0.1	0.01	1.2	0.2	<0.05	3	<0.5	<0.2
1283312	Soil	17	0.03	321	0.002	2	0.45	0.003	0.05	<0.1	0.06	4.5	0.2	<0.05	1	1.3	<0.2
1283313	Soil	29	0.16	809	0.009	3	1.11	0.005	0.09	0.2	0.24	2.3	0.5	<0.05	3	2.3	<0.2
1283314	Soil	22	0.17	1333	0.006	3	0.87	0.004	0.09	0.2	0.20	2.3	0.4	<0.05	2	1.8	<0.2
1283315	Soil	16	0.08	248	0.011	1	0.72	0.006	0.05	0.2	0.13	0.7	0.5	<0.05	4	1.6	<0.2
1283316	Soil	9	0.02	76	0.005	<1	0.21	0.014	0.04	0.1	0.04	0.2	0.5	<0.05	2	0.7	<0.2
1283317	Soil	19	0.10	270	0.007	2	0.84	0.004	0.07	0.2	0.07	1.3	0.6	<0.05	4	1.1	<0.2
1283318	Soil	14	0.07	246	0.007	2	0.62	0.004	0.06	0.2	0.05	0.8	0.3	<0.05	3	0.8	<0.2
1283319	Soil	19	0.11	415	0.004	2	0.82	0.004	0.07	0.1	0.08	1.4	0.3	<0.05	3	1.2	<0.2
1283320	Soil	16	0.08	743	0.003	3	0.66	0.005	0.08	0.2	0.39	1.3	0.5	<0.05	2	1.2	<0.2
1283321	Soil	15	0.10	610	0.002	4	0.40	0.004	0.08	0.1	0.82	3.2	1.0	<0.05	1	4.7	<0.2
1283322	Soil	16	0.16	906	0.004	5	0.62	0.006	0.08	<0.1	0.41	2.8	0.9	<0.05	2	1.8	<0.2
1283323	Soil	12	0.10	717	0.004	4	0.49	0.006	0.10	0.1	0.17	2.3	0.3	<0.05	2	1.3	<0.2
1283324	Soil	20	1.11	727	0.003	6	0.49	0.007	0.09	0.2	0.49	4.0	0.9	<0.05	1	2.8	<0.2
1283325	Soil	17	0.15	905	0.002	4	0.65	0.005	0.08	0.2	0.19	2.5	0.3	<0.05	2	1.4	<0.2
1283326	Soil	13	0.55	820	0.002	5	0.40	0.004	0.08	<0.1	0.40	6.3	0.3	<0.05	<1	1.3	<0.2
1283327	Soil	15	0.07	321	0.004	2	0.73	0.009	0.06	0.1	0.22	1.4	0.3	<0.05	3	1.4	<0.2
1283328	Soil	15	0.04	198	0.002	2	0.43	0.002	0.04	<0.1	0.06	2.9	0.2	<0.05	2	1.2	<0.2
1283329	Soil	16	0.05	412	0.001	1	0.55	0.003	0.07	<0.1	0.11	6.1	0.3	<0.05	2	1.5	<0.2
1283330	Soil	12	0.02	187	0.002	1	0.43	0.004	0.09	<0.1	0.06	3.6	0.2	0.05	2	1.4	<0.2
1284421	Soil	4	0.01	154	0.002	2	0.27	0.009	0.03	<0.1	0.02	0.4	0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1284422	Soil	1.6	7.6	4.8	34	0.5	6.7	1.8	31	0.85	6.1	<0.5	0.1	7	0.1	0.7	<0.1	23	0.02	0.027	2
1284423	Soil	1.1	12.0	7.2	24	0.7	7.0	1.1	18	0.50	3.3	1.1	0.5	9	0.6	0.3	<0.1	21	0.03	0.021	4
1284424	Soil	2.7	33.0	18.4	249	0.4	64.1	16.9	471	3.20	18.5	1.5	1.9	56	0.8	1.1	0.2	47	0.25	0.084	5
1284425	Soil	15.2	73.6	23.7	366	2.8	68.7	7.0	163	2.59	40.7	4.3	1.6	114	3.3	10.4	0.3	118	0.32	0.146	9
1284426	Soil	17.6	83.0	25.0	368	1.5	88.2	10.2	286	3.21	37.0	7.5	1.7	87	4.0	7.9	0.3	121	0.37	0.150	11
1284427	Soil	17.1	64.7	22.6	246	1.1	52.1	8.8	209	2.79	35.0	6.6	1.4	82	2.0	7.1	0.3	111	0.19	0.142	11
1284428	Soil	13.0	16.7	10.7	98	0.6	21.1	2.6	66	1.44	16.6	2.2	0.5	30	1.4	2.1	0.2	92	0.28	0.108	5
1284429	Soil	9.5	15.0	8.8	64	0.6	15.0	2.3	72	1.36	11.9	0.8	0.8	31	0.8	2.4	0.1	70	0.34	0.101	6
1284430	Soil	11.8	24.6	15.0	160	0.5	32.4	5.6	115	2.26	23.7	3.7	2.5	36	1.6	4.1	0.2	99	0.34	0.097	10
1284431	Soil	7.8	24.4	11.7	179	0.3	37.9	13.7	644	2.25	16.2	<0.5	1.3	51	2.5	2.3	0.2	83	0.53	0.096	8
1284432	Soil	12.1	41.2	24.6	337	0.3	69.6	19.2	271	3.15	26.4	0.8	1.6	32	2.0	3.6	0.2	78	0.16	0.085	9
1284433	Soil	6.2	17.1	9.3	102	0.1	19.1	4.7	66	1.34	18.3	<0.5	0.4	10	0.4	2.1	0.2	66	0.07	0.046	7
1284434	Soil	7.0	14.1	21.2	95	0.8	18.7	2.7	45	1.90	35.6	2.8	0.6	16	0.3	5.6	0.3	92	0.02	0.044	16
1284435	Soil	15.2	14.9	8.8	68	1.3	14.8	2.1	28	0.88	13.4	<0.5	0.3	6	0.4	5.2	0.1	117	0.02	0.025	21
1284436	Soil	16.0	32.1	16.1	279	0.5	47.5	5.8	112	2.27	36.7	3.4	1.3	23	1.5	7.1	0.2	151	0.10	0.107	14
1284437	Soil	8.6	8.5	9.2	105	0.4	16.2	1.7	54	0.91	16.1	<0.5	0.2	8	0.4	2.3	0.2	142	0.03	0.058	12
1284438	Soil	43.1	21.8	12.8	337	0.9	80.5	3.9	36	1.55	22.8	0.5	0.5	10	0.5	13.8	0.2	376	<0.01	0.034	23
1284439	Soil	22.8	10.6	4.5	178	1.3	38.8	1.6	20	0.80	8.7	0.7	0.3	6	0.7	7.4	0.1	294	0.01	0.024	34
1284440	Soil	73.2	19.0	18.1	225	4.4	52.1	0.6	10	0.88	26.8	<0.5	0.3	53	4.7	35.4	0.2	1738	0.02	0.030	54
1286441	Soil	3.2	26.1	11.2	85	0.6	23.2	5.5	366	1.31	11.2	0.9	0.8	45	1.0	1.9	0.1	49	0.45	0.063	5
1286442	Soil	5.3	41.8	15.5	158	0.7	33.5	6.1	210	2.11	22.0	2.1	2.6	57	1.8	3.5	0.2	79	0.40	0.108	10
1286443	Soil	4.9	29.6	14.1	131	0.6	27.1	6.1	282	2.18	17.1	1.6	2.7	48	1.0	2.4	0.2	71	0.30	0.096	10
1286444	Soil	53.3	65.5	14.9	319	0.4	187.2	18.5	320	2.68	65.5	<0.5	2.7	103	4.9	7.0	<0.1	105	4.09	0.181	23
1286445	Soil	21.3	13.0	5.7	99	0.2	27.0	2.3	36	0.86	31.9	<0.5	0.2	6	1.4	3.8	<0.1	93	0.04	0.088	9
1286446	Soil	31.5	68.6	21.5	551	1.1	160.7	13.9	203	3.38	86.9	3.7	1.5	18	5.0	16.1	0.2	78	0.23	0.115	18
1286447	Soil	46.2	30.6	11.7	289	0.2	114.9	12.8	413	2.25	272.2	3.7	0.3	11	1.6	15.9	0.2	103	0.12	0.141	14
1286448	Soil	33.4	46.4	11.4	475	0.2	175.8	22.1	237	3.53	343.4	5.4	0.7	12	1.8	90.8	0.2	129	0.09	0.192	20
1286449	Soil	22.3	34.0	9.8	269	0.5	128.1	16.2	242	2.86	266.7	6.7	0.7	22	1.6	14.0	0.2	110	0.26	0.167	16
1286450	Soil	12.0	89.4	14.2	269	0.5	353.0	56.5	1318	7.02	161.2	8.9	4.7	62	1.8	15.8	0.1	167	0.77	0.338	53
1287051	Soil	4.2	10.6	9.0	46	0.5	9.4	1.2	39	0.70	10.7	1.7	0.2	10	0.5	1.1	0.1	46	0.04	0.062	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284422	Soil	6	0.02	126	0.004	2	0.23	0.015	0.04	<0.1	0.02	0.5	<0.1	<0.05	1	<0.5	<0.2
1284423	Soil	10	0.02	199	0.003	2	0.46	0.013	0.03	<0.1	0.03	0.8	<0.1	<0.05	2	<0.5	<0.2
1284424	Soil	22	0.24	752	0.002	1	1.02	0.007	0.07	<0.1	0.12	3.7	0.1	<0.05	3	1.1	<0.2
1284425	Soil	28	0.11	1645	0.003	5	0.76	0.005	0.11	0.2	1.13	3.2	0.9	0.09	2	4.8	<0.2
1284426	Soil	30	0.16	1640	0.006	5	0.74	0.008	0.11	0.1	0.96	3.7	0.8	0.08	2	3.5	<0.2
1284427	Soil	24	0.11	1607	0.004	4	0.70	0.005	0.09	0.2	0.66	2.7	0.5	0.07	2	3.3	<0.2
1284428	Soil	16	0.09	665	0.003	2	0.68	0.014	0.05	0.1	0.44	1.4	0.5	<0.05	3	2.6	<0.2
1284429	Soil	14	0.08	562	0.003	3	0.56	0.012	0.05	<0.1	0.31	1.8	0.3	<0.05	2	1.4	<0.2
1284430	Soil	18	0.14	688	0.002	2	0.74	0.004	0.07	0.1	0.37	3.3	0.4	<0.05	2	2.2	<0.2
1284431	Soil	17	0.14	784	0.003	2	0.79	0.008	0.06	0.1	0.26	3.1	0.3	<0.05	2	1.3	<0.2
1284432	Soil	20	0.12	242	0.002	2	0.85	0.005	0.06	<0.1	0.14	3.9	0.4	<0.05	2	1.0	<0.2
1284433	Soil	11	0.04	185	0.003	1	0.38	0.008	0.04	<0.1	0.11	1.1	0.2	<0.05	2	0.6	<0.2
1284434	Soil	13	0.02	140	0.003	<1	0.32	0.004	0.04	0.1	0.08	0.7	0.2	<0.05	2	0.8	<0.2
1284435	Soil	12	0.02	131	0.006	2	0.30	0.003	0.03	0.2	0.09	0.4	0.3	<0.05	3	1.1	<0.2
1284436	Soil	19	0.12	355	0.003	3	0.70	0.004	0.07	0.1	0.15	1.7	0.5	<0.05	2	1.7	<0.2
1284437	Soil	14	0.06	160	0.012	2	0.62	0.007	0.05	0.1	0.03	0.3	0.4	<0.05	3	<0.5	<0.2
1284438	Soil	17	0.03	141	0.007	3	0.39	0.002	0.07	0.3	0.10	0.5	1.0	<0.05	4	4.4	<0.2
1284439	Soil	19	0.03	168	0.007	3	0.42	0.003	0.06	0.2	0.03	0.4	0.7	<0.05	4	2.6	<0.2
1284440	Soil	85	0.08	314	0.010	8	0.64	0.003	0.21	0.3	0.07	1.0	2.7	0.06	7	14.9	0.2
1286441	Soil	15	0.10	1108	0.003	3	0.61	0.015	0.06	<0.1	0.39	1.5	0.2	<0.05	2	1.6	<0.2
1286442	Soil	23	0.19	2349	0.003	4	0.90	0.006	0.11	0.2	0.62	2.9	0.3	<0.05	3	3.3	<0.2
1286443	Soil	23	0.22	2077	0.003	3	1.01	0.007	0.11	0.2	0.56	2.7	0.3	<0.05	3	2.4	<0.2
1286444	Soil	37	1.42	543	0.004	8	0.32	0.004	0.09	0.1	0.68	5.0	1.0	<0.05	<1	2.1	<0.2
1286445	Soil	15	0.03	222	0.002	2	0.43	0.009	0.05	<0.1	0.37	0.4	0.6	<0.05	1	0.7	<0.2
1286446	Soil	22	0.05	664	0.002	3	0.37	0.002	0.05	<0.1	0.89	4.0	0.4	<0.05	<1	3.2	<0.2
1286447	Soil	25	0.05	404	0.002	3	0.56	0.005	0.05	0.2	0.53	0.6	0.6	0.05	2	2.2	<0.2
1286448	Soil	55	0.05	506	0.003	4	0.61	0.005	0.06	0.3	0.84	1.2	0.8	0.05	2	3.6	<0.2
1286449	Soil	54	0.09	626	0.003	4	0.69	0.010	0.05	0.3	0.97	2.4	0.7	0.05	2	3.1	<0.2
1286450	Soil	172	0.11	1199	0.005	4	0.77	0.005	0.06	0.3	1.82	16.9	0.6	<0.05	2	3.8	<0.2
1287051	Soil	8	0.04	200	0.005	2	0.48	0.005	0.04	<0.1	0.10	0.3	0.3	<0.05	3	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287052	Soil	12.5	63.7	11.9	235	1.2	90.7	3.7	58	2.16	22.9	1.6	0.2	17	2.3	2.9	0.2	80	0.06	0.114	10
1287053	Soil	22.6	48.1	22.3	434	0.6	91.4	7.6	126	3.14	53.9	4.2	1.7	51	2.7	7.7	0.3	109	0.13	0.154	14
1287054	Soil	12.9	48.6	10.2	2453	0.9	259.9	7.8	420	1.67	28.9	5.9	1.1	70	40.3	6.5	0.2	84	1.21	0.112	7
1287055	Soil	15.2	27.6	12.4	244	0.3	49.3	5.9	117	1.79	28.0	3.2	1.8	34	2.6	4.4	0.2	100	0.34	0.091	12
1287056	Soil	21.4	46.7	12.4	479	0.7	88.5	7.4	141	1.61	22.0	2.1	2.3	46	9.3	5.7	0.2	156	0.60	0.125	15
1287057	Soil	8.4	29.5	9.8	188	0.6	47.1	5.7	257	1.15	14.7	2.3	1.1	65	2.3	2.2	0.1	65	1.17	0.100	8
1287058	Soil	68.3	65.6	10.9	619	0.6	187.3	8.0	187	2.40	65.7	3.6	2.0	52	5.8	9.5	0.2	165	0.62	0.089	15
1287059	Soil	10.7	15.1	6.8	91	0.1	24.2	3.0	46	1.23	12.5	0.7	0.2	19	0.4	1.6	0.1	45	0.33	0.040	10
1287060	Soil	31.9	24.1	12.0	229	0.1	71.7	4.4	70	1.89	35.2	1.3	0.2	9	0.4	5.4	0.2	150	0.04	0.086	9
1287311	Soil	45.4	37.8	21.5	17	2.4	8.2	0.4	10	1.48	53.6	7.8	0.7	98	0.3	42.6	0.2	237	0.04	0.121	4
1287312	Soil	7.8	14.1	13.8	13	1.9	6.1	0.4	11	0.37	9.3	32.5	0.3	37	<0.1	6.3	0.1	86	0.04	0.071	3
1287313	Soil	13.5	27.4	29.3	36	2.1	12.5	1.7	30	0.97	23.2	21.9	0.7	54	0.3	11.4	0.2	87	0.03	0.073	6
1287314	Soil	7.3	9.9	15.2	15	2.1	7.0	0.7	14	0.38	7.5	26.5	<0.1	24	<0.1	5.1	0.1	48	0.02	0.060	3
1287315	Soil	13.6	18.8	19.1	25	1.5	7.0	1.0	19	1.06	25.3	42.7	0.1	68	0.1	9.4	0.2	102	0.03	0.107	5
1287316	Soil	17.1	28.1	29.5	80	1.3	17.3	4.1	69	1.74	41.0	19.5	0.9	94	0.3	12.8	0.3	136	0.03	0.094	9
1287317	Soil	14.9	28.6	27.4	74	1.5	14.6	3.8	67	1.77	38.5	37.5	1.3	89	0.2	13.5	0.2	108	0.03	0.084	6
1287318	Soil	3.7	8.7	10.4	21	1.4	4.3	1.1	18	0.64	11.1	6.2	0.1	15	<0.1	2.0	0.1	30	0.02	0.047	3
1287319	Soil	8.6	15.1	14.9	54	0.6	11.0	2.8	44	0.98	17.4	5.6	0.4	31	<0.1	4.9	0.2	75	0.02	0.049	8
1287320	Soil	12.2	107.7	34.2	240	1.6	56.3	11.3	393	4.48	56.2	23.4	1.7	59	1.1	11.8	0.4	88	0.03	0.113	6
1287321	Soil	3.5	7.3	7.7	28	2.2	6.7	1.4	24	0.47	7.1	2.6	<0.1	16	<0.1	1.9	0.1	38	0.02	0.036	4
1287322	Soil	1.6	7.1	5.5	13	0.9	5.3	0.6	10	0.26	3.6	2.1	<0.1	11	0.1	0.7	<0.1	16	0.02	0.029	2
1287323	Soil	6.2	43.9	21.0	164	0.8	24.6	5.6	141	4.36	67.2	6.3	1.2	34	0.7	4.7	0.2	51	0.04	0.090	4
1287324	Soil	9.2	19.9	18.5	69	0.4	25.4	2.8	53	1.45	60.6	9.3	0.6	23	0.2	3.8	0.2	60	0.02	0.092	7
1287325	Soil	6.0	52.6	27.7	108	0.7	25.5	5.2	161	3.14	94.5	12.5	1.8	63	0.5	3.8	0.3	53	0.03	0.109	4
1287326	Soil	6.6	48.5	16.5	105	1.2	25.9	4.2	52	2.39	45.4	7.9	1.3	35	0.3	3.3	0.2	30	0.05	0.053	4
1287327	Soil	3.7	20.7	8.7	58	0.3	15.9	2.9	43	1.11	36.9	6.7	0.2	18	0.1	4.5	<0.1	42	0.03	0.042	4
1287328	Soil	2.9	14.5	8.5	50	0.2	11.9	2.1	29	1.02	30.0	4.7	0.7	13	<0.1	2.5	0.1	39	0.02	0.038	5
1287329	Soil	4.9	32.6	18.5	112	0.9	26.7	4.4	59	2.45	36.0	6.4	1.0	49	0.1	4.0	0.2	50	0.02	0.080	4
1287330	Soil	8.3	47.5	20.0	181	1.0	46.2	6.4	122	3.09	62.6	8.0	1.5	44	0.5	4.0	0.2	64	0.02	0.116	6
1287201	Soil	2.2	11.6	8.8	35	1.4	10.5	1.1	16	0.75	11.8	7.9	<0.1	22	0.2	1.1	<0.1	18	0.07	0.066	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287052	Soil	16	0.03	560	0.009	2	0.71	0.005	0.05	0.1	0.23	0.4	0.3	<0.05	3	1.8	<0.2
1287053	Soil	23	0.07	564	0.003	3	0.74	0.004	0.08	0.2	0.22	1.8	0.4	<0.05	2	2.5	<0.2
1287054	Soil	15	0.15	677	0.002	5	0.66	0.007	0.06	<0.1	0.71	2.2	1.1	0.06	2	3.4	<0.2
1287055	Soil	15	0.07	443	0.003	2	0.59	0.005	0.06	0.1	0.13	1.6	0.3	<0.05	2	1.7	<0.2
1287056	Soil	21	0.08	602	0.003	3	0.53	0.004	0.06	0.2	0.36	3.4	0.6	<0.05	1	2.8	<0.2
1287057	Soil	15	0.13	859	0.005	3	0.70	0.010	0.04	0.1	0.36	1.8	0.3	0.13	2	1.9	<0.2
1287058	Soil	19	0.13	509	0.003	4	0.55	0.004	0.06	0.3	1.10	3.7	1.1	<0.05	2	2.3	<0.2
1287059	Soil	9	0.07	409	0.004	2	0.48	0.011	0.04	<0.1	0.05	0.4	0.2	<0.05	2	0.7	<0.2
1287060	Soil	18	0.05	221	0.004	3	0.59	0.004	0.05	0.2	0.09	0.3	0.6	<0.05	4	1.8	<0.2
1287311	Soil	20	0.01	908	0.002	8	0.36	0.004	0.17	0.3	7.47	1.4	1.8	0.32	2	19.2	0.2
1287312	Soil	15	0.01	897	0.002	5	0.27	0.003	0.05	<0.1	1.23	0.6	0.6	<0.05	2	2.8	<0.2
1287313	Soil	18	0.01	1243	0.002	4	0.33	0.004	0.08	0.2	1.69	1.6	0.7	0.13	2	5.2	<0.2
1287314	Soil	12	<0.01	574	0.003	5	0.22	0.008	0.03	<0.1	0.70	0.3	0.5	<0.05	1	2.1	<0.2
1287315	Soil	15	0.02	1376	0.002	3	0.44	0.007	0.06	0.2	1.26	0.3	1.0	0.11	3	4.1	<0.2
1287316	Soil	17	0.02	1572	0.003	5	0.38	0.003	0.10	0.2	0.43	1.8	0.8	0.16	3	8.4	0.3
1287317	Soil	14	0.01	829	0.002	3	0.31	0.002	0.09	0.1	1.12	1.8	0.8	0.15	2	5.9	<0.2
1287318	Soil	6	0.01	348	0.003	<1	0.50	0.011	0.03	<0.1	0.15	0.3	0.2	<0.05	2	1.1	<0.2
1287319	Soil	11	0.01	552	0.002	3	0.31	0.004	0.05	0.1	0.11	0.8	0.3	<0.05	2	2.3	<0.2
1287320	Soil	17	0.04	959	0.002	2	0.68	0.003	0.08	0.1	1.87	6.0	0.7	0.10	2	5.1	<0.2
1287321	Soil	6	<0.01	385	0.001	2	0.15	0.009	0.03	<0.1	0.12	0.3	0.2	<0.05	1	0.9	<0.2
1287322	Soil	6	0.01	397	0.002	1	0.15	0.015	0.02	<0.1	0.15	0.2	<0.1	<0.05	<1	<0.5	<0.2
1287323	Soil	17	0.04	706	<0.001	2	0.47	0.004	0.06	<0.1	0.30	2.2	0.2	0.07	2	3.1	<0.2
1287324	Soil	16	0.02	510	0.002	4	0.40	0.004	0.06	0.1	0.22	0.9	0.4	0.05	3	1.0	<0.2
1287325	Soil	21	0.06	1143	0.001	4	0.74	0.004	0.09	<0.1	0.49	2.5	0.3	0.14	2	1.8	0.2
1287326	Soil	24	0.03	1011	<0.001	4	0.39	0.004	0.08	<0.1	2.52	2.6	0.1	0.10	1	8.0	<0.2
1287327	Soil	10	0.01	304	0.002	2	0.31	0.010	0.03	<0.1	0.17	0.6	<0.1	<0.05	2	1.6	<0.2
1287328	Soil	12	0.02	293	0.010	5	0.48	0.005	0.05	<0.1	0.07	1.0	0.1	<0.05	3	1.4	<0.2
1287329	Soil	18	0.02	472	0.001	4	0.43	0.008	0.08	<0.1	0.18	2.3	0.2	0.15	2	3.1	<0.2
1287330	Soil	23	0.03	732	0.002	3	0.67	0.005	0.07	0.1	0.27	2.7	0.3	0.07	2	2.2	0.3
1287201	Soil	9	0.02	1011	0.002	1	0.30	0.019	0.04	<0.1	0.86	0.2	0.2	0.08	1	1.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287202	Soil	5.8	86.0	19.7	213	1.4	54.3	8.6	163	2.80	65.2	12.4	1.4	68	5.9	4.8	0.2	36	0.23	0.146	4
1287203	Soil	5.1	59.5	22.1	159	1.3	40.9	8.5	166	2.61	62.9	12.3	1.2	63	1.6	4.5	0.2	32	0.19	0.160	3
1287204	Soil	6.0	80.6	26.1	222	1.7	65.0	10.7	224	3.36	76.8	13.4	1.9	101	2.6	4.9	0.2	38	0.39	0.142	4
1287205	Soil	5.0	76.0	18.0	216	1.3	66.3	9.3	168	2.75	58.9	11.5	1.4	83	2.2	4.7	0.2	36	0.59	0.154	4
1287206	Soil	6.4	56.8	15.0	290	0.7	69.4	8.5	138	2.37	28.4	7.9	0.9	72	2.0	3.2	0.2	57	0.85	0.154	9
1287207	Soil	11.3	53.1	18.3	470	1.4	89.0	8.2	81	2.42	32.4	18.8	2.1	88	1.6	4.9	0.2	79	0.70	0.143	11
1287208	Soil	35.1	29.4	13.1	185	0.3	47.7	5.0	111	2.74	56.0	3.6	0.3	16	0.4	4.4	0.2	109	0.04	0.121	10
1287209	Soil	12.9	24.7	11.0	135	0.5	33.9	3.8	76	1.95	35.3	3.1	0.4	14	0.4	3.3	0.1	78	0.03	0.117	7
1287210	Soil	1.5	16.7	7.0	129	0.4	20.8	3.0	79	1.09	12.2	4.3	0.3	33	1.5	1.1	0.1	27	0.60	0.153	5
1287211	Soil	20.4	34.8	15.2	253	0.3	60.2	6.5	61	2.21	38.7	4.2	1.0	22	0.6	4.4	0.2	106	0.04	0.070	12
1287212	Soil	5.0	19.3	10.7	110	0.3	25.5	3.1	42	1.25	18.3	2.9	0.4	18	0.5	1.6	0.1	40	0.08	0.068	5
1287213	Soil	3.2	54.7	16.4	172	1.6	46.1	6.7	93	3.11	48.6	14.2	1.3	54	1.0	3.6	0.2	38	0.67	0.109	6
1287214	Soil	3.3	51.8	15.5	201	1.4	48.4	6.6	91	3.09	47.1	11.4	1.2	50	0.9	3.3	0.2	35	0.68	0.104	5
1287215	Soil	3.0	31.5	9.2	174	1.0	29.6	4.8	106	2.01	23.5	9.8	0.6	61	1.3	1.5	0.2	36	1.16	0.109	5
1287216	Soil	3.6	38.7	8.2	174	0.9	42.2	5.2	137	1.60	19.2	9.1	0.5	63	1.8	1.8	0.1	48	1.13	0.118	7
1287217	Soil	5.7	66.3	14.5	272	1.4	72.2	9.4	150	2.70	47.2	24.3	1.3	80	1.5	3.2	0.2	62	1.18	0.128	8
1287218	Soil	3.4	61.6	12.3	208	2.6	65.3	10.8	302	2.44	33.1	19.9	0.9	94	1.8	2.9	0.2	40	1.69	0.137	8
1287219	Soil	4.5	40.8	11.7	208	0.7	51.8	9.7	131	2.54	33.9	11.4	1.3	37	0.9	3.2	0.2	41	0.32	0.085	6
1287220	Soil	1.3	10.0	3.7	28	1.1	7.5	1.6	18	0.68	5.8	3.4	<0.1	9	0.3	0.5	<0.1	21	0.05	0.062	2
1287221	Soil	6.3	48.0	16.6	237	1.8	54.8	7.8	163	2.87	41.0	19.9	1.6	66	1.2	3.4	0.2	68	0.67	0.137	8
1287222	Soil	5.0	42.2	14.5	196	0.9	49.7	9.5	249	2.63	44.6	16.5	1.1	48	0.9	3.2	0.2	50	0.39	0.097	6
1287223	Soil	2.4	42.2	13.1	151	1.2	42.6	6.4	145	2.33	32.2	9.9	1.0	57	0.8	1.9	0.2	34	0.44	0.145	5
1287224	Soil	2.2	24.2	9.1	78	0.5	22.1	4.1	65	1.61	27.0	5.3	0.1	22	0.3	1.7	0.1	30	0.07	0.105	3
1287225	Soil	1.7	17.3	7.6	68	0.3	14.2	2.5	53	1.23	22.7	4.8	0.4	28	0.2	1.0	0.1	32	0.08	0.075	3
1287226	Soil	3.3	47.7	13.6	132	0.9	33.9	7.1	188	2.38	32.5	11.0	0.9	86	0.6	1.6	0.2	35	0.32	0.110	4
1287227	Soil	2.8	65.4	12.3	159	1.3	47.5	7.7	158	2.33	27.2	12.5	1.6	69	0.7	2.7	0.2	45	1.19	0.102	6
1287228	Soil	1.5	39.1	10.5	136	0.8	35.6	5.6	141	1.96	27.7	13.9	1.3	73	0.4	2.4	0.2	27	1.26	0.081	3
1287229	Soil	4.6	46.1	15.2	222	0.8	61.4	16.7	408	3.10	41.0	13.3	1.9	66	1.0	3.7	0.2	54	0.66	0.111	7
1287230	Soil	1.5	53.7	9.6	129	1.3	54.5	6.7	225	1.92	21.4	13.3	1.2	116	0.3	1.5	0.2	27	0.76	0.077	3
1287301	Soil	4.4	35.5	9.4	122	0.8	50.3	16.6	1029	1.72	9.8	1.6	0.5	187	2.5	2.6	<0.1	28	1.60	0.094	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287202	Soil	18	0.05	1485	0.001	4	0.67	0.005	0.08	<0.1	2.18	3.2	0.4	0.11	2	4.8	<0.2
1287203	Soil	17	0.05	1271	0.001	4	0.60	0.005	0.08	<0.1	1.79	2.8	0.4	0.11	2	4.6	<0.2
1287204	Soil	29	0.09	2194	0.001	4	0.78	0.006	0.10	<0.1	2.09	4.3	0.4	0.17	2	6.4	<0.2
1287205	Soil	19	0.09	1281	0.001	3	0.67	0.004	0.07	<0.1	1.68	3.3	0.3	0.12	2	5.4	<0.2
1287206	Soil	22	0.11	1749	0.004	3	0.88	0.010	0.07	<0.1	1.19	2.8	0.5	0.13	2	2.3	<0.2
1287207	Soil	25	0.10	5425	0.005	5	0.86	0.007	0.09	0.1	2.12	4.2	0.5	0.10	2	2.8	<0.2
1287208	Soil	22	0.04	1286	0.006	3	0.46	0.007	0.05	0.2	0.19	0.5	0.4	<0.05	2	1.5	<0.2
1287209	Soil	15	0.04	970	0.004	2	0.54	0.013	0.04	<0.1	0.32	0.3	0.3	<0.05	2	1.1	<0.2
1287210	Soil	14	0.09	753	0.005	4	0.79	0.019	0.05	<0.1	0.41	0.7	0.2	0.07	2	1.4	<0.2
1287211	Soil	23	0.04	1400	0.006	2	0.46	0.004	0.08	0.2	0.20	1.5	0.4	<0.05	2	1.7	<0.2
1287212	Soil	19	0.03	985	0.002	3	0.47	0.009	0.05	<0.1	0.26	1.1	0.2	<0.05	2	0.8	<0.2
1287213	Soil	23	0.11	757	0.002	4	0.75	0.005	0.08	<0.1	1.47	3.1	0.1	<0.05	2	2.9	<0.2
1287214	Soil	21	0.10	892	<0.001	3	0.71	0.005	0.06	<0.1	1.18	2.8	0.1	0.07	2	4.2	<0.2
1287215	Soil	16	0.09	853	0.002	3	0.69	0.010	0.05	<0.1	1.04	1.9	0.1	0.11	2	3.5	<0.2
1287216	Soil	14	0.07	1224	0.003	4	0.82	0.014	0.05	<0.1	0.97	1.8	0.2	0.11	2	2.8	<0.2
1287217	Soil	23	0.12	1362	0.002	5	0.94	0.008	0.08	<0.1	2.29	3.3	0.4	0.11	2	3.5	<0.2
1287218	Soil	21	0.13	918	0.002	6	1.20	0.011	0.07	<0.1	2.60	3.2	0.4	0.18	2	4.2	<0.2
1287219	Soil	17	0.07	1177	0.001	2	0.57	0.004	0.06	<0.1	0.72	2.5	0.2	<0.05	2	2.2	<0.2
1287220	Soil	5	0.02	294	0.002	<1	0.24	0.016	0.03	<0.1	0.39	0.3	<0.1	<0.05	<1	<0.5	<0.2
1287221	Soil	26	0.15	1410	0.003	6	1.17	0.007	0.12	<0.1	2.11	4.2	0.4	<0.05	3	3.0	<0.2
1287222	Soil	21	0.12	925	0.002	4	0.80	0.008	0.09	<0.1	1.61	2.6	0.2	<0.05	2	1.9	<0.2
1287223	Soil	22	0.15	890	0.002	2	0.96	0.008	0.07	<0.1	1.17	2.2	0.2	<0.05	3	1.2	<0.2
1287224	Soil	12	0.05	331	0.002	2	0.57	0.009	0.05	<0.1	0.31	0.3	0.1	<0.05	2	1.0	<0.2
1287225	Soil	14	0.06	270	0.001	2	0.66	0.010	0.04	<0.1	0.30	1.0	0.2	<0.05	2	0.6	<0.2
1287226	Soil	23	0.16	603	0.002	2	0.95	0.010	0.07	<0.1	0.45	1.9	0.2	<0.05	3	1.7	<0.2
1287227	Soil	26	0.15	1041	0.002	5	0.98	0.007	0.09	0.1	1.06	3.5	0.2	0.06	2	2.1	<0.2
1287228	Soil	20	0.20	621	0.002	3	0.90	0.009	0.06	<0.1	0.57	2.3	0.1	0.06	2	1.4	<0.2
1287229	Soil	26	0.15	1037	0.003	5	0.86	0.007	0.09	<0.1	0.82	3.4	0.2	0.06	2	2.3	<0.2
1287230	Soil	22	0.21	1338	0.001	3	0.98	0.011	0.07	<0.1	0.55	2.9	0.1	0.07	2	2.2	<0.2
1287301	Soil	8	0.21	1328	0.005	7	0.66	0.015	0.05	<0.1	0.15	1.2	0.2	0.19	1	4.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287302	Soil	0.5	8.1	2.0	10	1.1	3.5	0.9	19	0.40	0.6	<0.5	<0.1	17	0.2	0.2	<0.1	13	0.09	0.024	2
1287303	Soil	2.0	8.3	4.6	44	0.5	9.9	1.7	29	0.88	4.8	0.7	<0.1	23	0.3	1.1	<0.1	27	0.12	0.033	2
1287304	Soil	0.8	14.3	2.7	23	0.6	21.4	2.3	30	1.14	1.1	0.9	<0.1	109	0.6	0.8	<0.1	10	0.88	0.067	3
1287305	Soil	1.0	14.0	2.9	31	0.8	11.5	1.3	48	0.52	1.5	0.9	<0.1	116	0.5	0.9	<0.1	15	0.96	0.042	2
1287306	Soil	0.5	7.2	1.4	21	<0.1	9.7	1.8	47	0.38	<0.5	0.7	<0.1	85	0.7	0.8	<0.1	12	0.77	0.028	1
1287307	Soil	1.7	7.3	2.1	9	<0.1	8.8	4.0	639	2.04	4.2	0.7	<0.1	88	0.1	0.8	<0.1	8	0.92	0.051	2
1287308	Soil	1.9	14.4	7.3	53	0.2	16.7	9.3	262	2.24	7.6	0.5	0.4	132	0.3	1.6	0.1	14	1.33	0.078	2
1287309	Soil	1.1	11.3	7.8	32	0.2	10.2	2.1	66	1.08	5.3	<0.5	0.1	96	0.3	0.9	0.1	11	0.98	0.059	2
1287310	Soil	18.5	33.9	14.9	6	1.3	7.2	<0.1	2	0.62	15.5	0.7	0.7	73	0.1	14.9	0.2	132	0.03	0.064	3
1283301	Soil	2.8	15.1	9.8	101	0.2	16.0	4.8	77	2.16	19.3	<0.5	0.6	7	0.4	1.9	0.2	36	0.02	0.038	4
1283302	Soil	1.1	8.2	4.2	40	0.2	8.2	2.4	45	1.00	6.9	<0.5	0.2	6	0.2	0.6	<0.1	20	0.02	0.026	2
1283303	Soil	2.9	34.9	15.4	133	0.4	57.8	7.3	135	3.03	19.4	<0.5	1.0	22	2.0	1.6	0.2	36	0.05	0.086	4
1283304	Soil	15.1	62.1	21.3	281	1.3	56.9	8.1	251	2.52	34.1	5.0	2.1	80	2.4	6.9	0.3	103	0.38	0.130	9
1283305	Soil	15.1	39.9	18.3	179	1.0	33.8	8.9	269	2.15	25.1	3.3	1.9	64	2.1	5.4	0.2	98	0.28	0.122	9
1283306	Soil	21.6	46.7	16.9	238	0.8	58.0	7.0	159	2.79	32.6	4.3	1.8	53	3.0	5.2	0.2	105	0.37	0.115	9
1283307	Soil	12.2	39.7	14.5	204	0.7	41.2	5.0	129	1.90	22.4	5.1	2.2	45	3.3	4.7	0.2	89	0.40	0.108	9
1283308	Soil	14.4	41.9	14.7	302	0.7	55.7	8.2	233	2.03	25.5	1.6	2.5	52	3.5	5.6	0.2	109	0.40	0.127	12
1283309	Soil	12.5	37.5	13.4	187	0.7	41.6	5.2	119	1.82	32.2	3.1	1.4	39	3.0	5.1	0.2	107	0.34	0.104	9
1283310	Soil	12.0	28.2	12.0	204	0.5	37.9	5.1	122	1.88	23.5	3.5	0.4	30	1.1	4.2	0.2	105	0.22	0.100	8
1287331	Soil	5.0	30.5	7.6	75	0.8	17.8	3.3	35	1.56	26.7	2.5	0.6	10	0.3	2.1	0.2	51	0.02	0.056	6
1287332	Soil	4.3	44.0	14.4	142	1.1	34.4	4.5	67	2.81	26.9	7.5	1.3	24	0.5	2.7	0.2	41	0.07	0.071	4
1287333	Soil	4.4	35.6	12.7	115	0.6	32.0	4.8	69	2.26	27.6	3.1	1.2	30	0.4	1.9	0.2	32	0.34	0.067	4
1287334	Soil	4.3	46.5	21.7	146	0.6	43.8	9.4	193	3.57	35.9	3.2	1.9	25	0.5	2.0	0.3	37	0.07	0.076	3
1287335	Soil	5.9	24.5	14.1	87	1.4	23.5	4.0	72	1.64	34.9	7.8	0.3	21	0.4	2.2	0.2	40	0.06	0.085	4
1287336	Soil	6.5	32.1	15.7	107	0.9	30.0	5.8	136	1.84	44.8	8.1	0.8	39	0.7	2.9	0.2	46	0.32	0.077	7
1287337	Soil	6.0	13.7	4.5	46	0.9	13.9	2.3	39	0.73	18.8	2.1	<0.1	8	0.3	1.6	0.1	39	0.04	0.031	6
1287338	Soil	12.0	33.6	14.5	110	2.1	34.5	3.9	70	1.75	83.7	26.8	1.2	28	0.6	8.5	0.2	91	0.02	0.095	9
1287339	Soil	11.6	17.7	8.4	85	0.9	25.8	3.3	40	1.10	48.9	7.9	0.8	12	0.1	5.2	0.1	93	0.02	0.035	12
1287340	Soil	9.1	25.0	12.1	116	0.6	30.4	5.0	154	1.58	53.1	9.6	0.4	31	0.7	4.4	0.2	60	0.18	0.090	9
1287341	Soil	3.3	20.2	8.6	80	0.5	22.4	3.8	175	1.39	28.9	6.6	0.3	34	0.5	2.3	0.1	35	0.66	0.088	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287302	Soil	3	0.02	392	0.006	<1	0.29	0.029	0.02	<0.1	0.02	0.1	<0.1	<0.05	1	<0.5	<0.2
1287303	Soil	5	0.04	617	0.008	<1	0.28	0.021	0.03	<0.1	0.02	0.3	<0.1	<0.05	1	0.9	<0.2
1287304	Soil	4	0.09	797	0.009	<1	0.48	0.023	0.01	<0.1	0.08	0.3	<0.1	0.18	1	5.5	<0.2
1287305	Soil	3	0.16	677	0.007	1	0.34	0.024	0.02	<0.1	0.06	0.2	<0.1	0.13	<1	2.7	<0.2
1287306	Soil	2	0.09	242	0.012	1	0.27	0.028	0.02	<0.1	0.02	0.2	<0.1	0.09	<1	2.8	<0.2
1287307	Soil	2	0.13	399	0.012	3	0.43	0.027	0.02	<0.1	0.02	0.3	<0.1	0.23	1	2.6	<0.2
1287308	Soil	7	0.21	535	0.003	5	0.49	0.014	0.03	<0.1	0.06	0.7	<0.1	0.19	1	4.3	<0.2
1287309	Soil	5	0.16	326	0.005	3	0.32	0.017	0.02	<0.1	0.04	0.4	<0.1	0.15	1	2.8	<0.2
1287310	Soil	12	<0.01	1271	0.001	6	0.30	0.002	0.11	0.2	4.76	1.0	0.9	0.19	2	4.8	<0.2
1283301	Soil	8	0.04	119	0.002	<1	0.40	0.005	0.04	<0.1	<0.01	1.1	0.1	<0.05	2	0.6	<0.2
1283302	Soil	4	0.02	149	0.004	<1	0.33	0.014	0.02	<0.1	0.02	0.7	<0.1	<0.05	2	<0.5	<0.2
1283303	Soil	16	0.11	651	0.001	<1	0.75	0.004	0.06	<0.1	0.05	2.2	0.1	<0.05	3	1.0	<0.2
1283304	Soil	21	0.11	1509	0.002	3	0.66	0.004	0.07	0.1	1.03	3.2	0.5	<0.05	2	3.1	<0.2
1283305	Soil	19	0.11	1172	0.002	2	0.64	0.005	0.06	0.2	0.61	2.7	0.4	<0.05	2	3.0	<0.2
1283306	Soil	18	0.13	1185	0.002	3	0.75	0.007	0.07	0.1	0.52	3.2	0.5	<0.05	2	2.4	<0.2
1283307	Soil	15	0.13	913	0.002	2	0.66	0.006	0.06	0.1	0.49	2.8	0.4	<0.05	2	2.2	<0.2
1283308	Soil	17	0.13	1002	0.003	3	0.65	0.005	0.08	0.1	0.43	3.0	0.4	<0.05	2	2.7	<0.2
1283309	Soil	13	0.09	897	0.002	2	0.63	0.007	0.06	0.2	0.42	2.4	0.4	<0.05	2	2.5	<0.2
1283310	Soil	14	0.09	501	0.003	2	0.66	0.008	0.07	0.1	0.18	1.2	0.4	<0.05	2	1.6	<0.2
1287331	Soil	9	0.02	420	0.001	2	0.53	0.005	0.04	<0.1	0.16	1.1	0.1	<0.05	2	2.6	<0.2
1287332	Soil	18	0.04	502	0.002	2	0.71	0.006	0.06	<0.1	0.23	2.6	0.2	<0.05	2	4.0	<0.2
1287333	Soil	19	0.13	927	0.001	2	0.71	0.005	0.06	<0.1	0.22	2.4	0.1	<0.05	2	2.1	<0.2
1287334	Soil	29	0.23	497	<0.001	1	1.24	0.004	0.07	<0.1	0.13	3.4	0.1	<0.05	4	2.2	<0.2
1287335	Soil	13	0.06	537	0.001	2	0.58	0.008	0.05	<0.1	0.63	0.7	0.2	<0.05	2	1.6	<0.2
1287336	Soil	13	0.05	969	0.002	1	0.54	0.005	0.06	<0.1	1.92	1.9	0.2	<0.05	2	2.6	<0.2
1287337	Soil	6	0.02	284	0.005	2	0.22	0.011	0.04	<0.1	0.10	0.2	0.2	<0.05	1	0.7	<0.2
1287338	Soil	12	0.02	831	0.001	3	0.40	0.002	0.06	0.1	1.85	1.5	0.5	0.08	1	2.5	0.2
1287339	Soil	9	0.02	298	0.001	4	0.27	0.002	0.05	0.1	1.07	0.8	0.3	<0.05	2	1.6	<0.2
1287340	Soil	12	0.05	1091	0.002	3	0.44	0.005	0.06	<0.1	0.79	0.8	0.3	0.05	2	1.8	<0.2
1287341	Soil	9	0.03	732	0.003	2	0.49	0.014	0.04	<0.1	0.53	0.8	0.2	0.06	2	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287342	Soil	10.3	22.4	16.5	119	0.3	34.5	4.6	46	1.41	48.2	7.3	0.7	20	0.2	4.9	0.2	79	0.08	0.051	8
1287343	Soil	2.9	33.9	7.6	61	1.1	21.7	2.8	149	0.84	18.0	14.6	0.3	73	1.1	2.4	0.1	25	1.98	0.160	5
1287344	Soil	5.5	34.2	12.4	164	1.0	43.2	6.5	124	2.05	57.0	28.9	1.4	59	1.2	4.4	0.2	46	1.08	0.103	8
1287345	Soil	5.3	38.8	21.8	163	1.3	44.9	8.5	253	2.84	96.3	19.1	1.5	44	1.3	4.8	0.4	54	0.31	0.141	9
1287346	Soil	2.8	16.9	9.4	75	0.6	20.8	3.6	235	1.52	33.3	12.8	0.4	40	0.5	1.8	0.2	42	0.75	0.119	7
1287347	Soil	25.7	48.7	15.0	236	0.7	72.3	5.9	110	2.12	70.3	6.0	0.8	37	3.8	6.0	0.2	133	0.70	0.078	12
1287348	Soil	29.2	60.5	15.9	375	1.1	95.9	11.0	218	2.70	81.4	11.2	1.6	27	3.9	7.5	0.2	149	0.13	0.145	13
1287349	Soil	39.9	46.6	15.5	374	0.6	101.5	9.4	123	2.55	83.7	7.6	1.6	21	1.5	8.0	0.2	194	0.11	0.102	16
1287350	Soil	22.0	43.3	13.7	317	1.3	75.5	9.8	325	2.10	49.7	15.9	2.0	44	3.6	5.7	0.2	136	0.42	0.114	12
1287351	Soil	25.2	41.9	16.1	233	0.2	71.9	8.5	112	2.92	124.6	1.1	0.3	7	0.4	5.8	0.3	129	0.02	0.102	13
1287352	Soil	6.4	19.7	7.6	43	0.6	10.4	1.1	19	0.72	12.9	3.8	0.2	10	0.3	1.1	0.2	106	0.03	0.136	11
1287353	Soil	13.8	26.0	19.7	196	0.2	33.4	4.3	82	1.84	29.7	3.4	0.3	27	0.8	3.8	0.2	67	0.04	0.134	8
1287354	Soil	18.3	43.8	37.7	718	0.4	87.4	7.8	281	2.95	52.8	4.5	0.3	60	8.9	6.9	0.4	84	0.38	0.152	6
1287355	Soil	28.2	54.7	17.4	523	0.6	109.9	13.1	317	2.82	63.7	6.3	1.3	45	5.5	7.5	0.3	100	0.33	0.162	13
1287356	Soil	13.5	67.5	23.8	702	1.1	99.3	11.1	355	2.88	39.0	10.4	1.3	42	9.2	5.0	0.3	51	0.48	0.133	7
1287357	Soil	28.7	111.7	35.0	728	1.6	144.5	24.4	682	5.50	88.5	9.2	2.3	45	6.9	9.9	0.4	134	0.26	0.197	16
1287358	Soil	16.7	27.4	13.7	209	0.2	47.9	5.4	635	1.83	36.8	2.2	0.2	27	2.3	3.7	0.2	86	0.18	0.142	8
1287359	Soil	5.4	30.2	22.0	100	1.5	28.6	1.6	49	1.08	17.1	10.7	0.3	51	2.1	3.0	0.2	46	0.30	0.149	5
1287360	Soil	13.5	44.1	33.8	115	2.3	26.1	2.8	55	2.00	46.2	14.2	0.9	69	1.1	8.2	0.3	86	0.15	0.160	6
1287641	Soil	6.2	40.1	16.0	169	0.9	42.8	9.8	298	2.35	18.0	3.5	1.5	52	1.7	2.3	0.3	59	0.46	0.100	8
1287642	Soil	4.8	26.0	10.8	117	0.7	39.1	6.5	174	1.38	10.0	2.2	0.7	35	0.7	1.7	0.1	44	0.52	0.047	4
1287643	Soil	10.0	17.8	20.4	111	0.1	23.0	4.6	92	2.56	30.0	2.0	2.2	16	0.3	3.2	0.3	110	0.04	0.051	10
1287644	Soil	13.8	36.6	22.3	198	1.1	40.2	8.2	253	2.39	27.0	4.8	1.3	44	1.8	3.8	0.2	99	0.25	0.109	8
1287645	Soil	13.5	31.7	16.5	228	0.5	38.9	9.6	275	2.19	20.2	3.7	1.9	37	1.6	3.0	0.2	79	0.29	0.100	10
1287646	Soil	6.1	27.9	7.2	127	0.7	33.8	3.6	422	0.96	11.6	1.9	0.4	102	3.0	3.2	<0.1	41	2.41	0.101	3
1287647	Soil	16.3	31.3	16.0	246	0.8	49.3	6.3	134	2.73	33.5	2.1	2.2	20	0.7	4.8	0.2	117	0.09	0.131	11
1287648	Soil	21.7	45.2	16.7	281	0.7	58.5	7.1	155	2.31	33.9	2.0	2.0	25	0.9	5.6	0.2	124	0.09	0.109	15
1287649	Soil	21.3	26.6	17.3	261	0.7	54.9	5.7	164	2.61	35.5	1.7	1.5	23	0.8	5.7	0.3	141	0.06	0.111	13
1287650	Soil	23.5	26.6	18.5	228	10.7	48.5	4.6	87	3.20	37.6	1.3	2.0	20	0.5	5.8	0.3	166	0.05	0.175	12
1287771	Soil	4.2	13.7	14.2	75	1.0	15.7	2.8	36	1.35	15.0	0.7	0.4	15	0.2	2.1	0.2	48	0.02	0.053	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287342	Soil	12	0.02	195	0.001	3	0.32	0.005	0.06	0.1	0.48	0.8	0.3	<0.05	2	1.6	<0.2
1287343	Soil	12	0.08	999	0.004	4	0.62	0.015	0.03	<0.1	1.22	1.0	0.2	0.15	2	1.9	<0.2
1287344	Soil	22	0.11	767	0.002	3	0.74	0.006	0.07	0.1	1.22	2.9	0.3	0.06	2	2.1	<0.2
1287345	Soil	21	0.07	707	0.002	3	0.71	0.005	0.08	0.1	1.58	2.7	0.3	0.06	2	2.3	<0.2
1287346	Soil	21	0.05	636	0.002	2	0.68	0.011	0.05	<0.1	1.14	1.5	0.2	0.07	2	1.4	<0.2
1287347	Soil	17	0.06	1366	0.003	3	0.53	0.004	0.05	0.2	0.84	2.2	0.5	<0.05	2	2.3	<0.2
1287348	Soil	21	0.05	1380	0.003	4	0.68	0.007	0.06	0.1	1.34	2.8	0.7	<0.05	2	2.6	<0.2
1287349	Soil	22	0.05	1157	0.003	4	0.52	0.002	0.08	0.2	0.49	2.2	0.7	<0.05	2	2.7	<0.2
1287350	Soil	27	0.08	1875	0.002	4	0.63	0.003	0.08	<0.1	1.98	3.5	0.6	<0.05	2	2.0	<0.2
1287351	Soil	20	0.04	187	0.003	2	0.54	0.006	0.06	0.1	2.11	0.5	0.5	<0.05	3	1.7	<0.2
1287352	Soil	17	0.06	292	0.003	3	0.84	0.006	0.06	<0.1	0.40	0.4	0.7	<0.05	3	0.9	<0.2
1287353	Soil	13	0.03	254	0.003	3	0.41	0.006	0.08	<0.1	0.25	0.5	0.5	0.06	2	2.2	<0.2
1287354	Soil	20	0.08	601	0.005	3	0.59	0.005	0.08	0.1	1.16	1.0	1.0	0.09	2	3.5	<0.2
1287355	Soil	17	0.06	754	0.003	4	0.51	0.004	0.06	0.2	1.14	2.3	0.7	<0.05	1	3.0	<0.2
1287356	Soil	12	0.07	921	0.003	3	0.62	0.006	0.06	<0.1	1.59	3.2	0.5	0.06	2	2.9	<0.2
1287357	Soil	25	0.05	1174	0.003	3	0.65	0.003	0.07	0.1	1.63	5.2	0.7	<0.05	1	3.8	<0.2
1287358	Soil	15	0.04	949	0.003	2	0.44	0.004	0.06	0.2	0.35	0.5	0.4	0.08	2	1.9	<0.2
1287359	Soil	9	0.04	1879	0.003	4	0.55	0.011	0.05	0.1	1.74	0.9	0.7	0.14	2	3.5	<0.2
1287360	Soil	15	0.03	1113	0.002	3	0.54	0.004	0.09	0.2	2.73	1.8	1.2	0.16	2	6.6	<0.2
1287641	Soil	16	0.19	1339	0.003	3	0.73	0.006	0.05	0.1	0.46	4.6	0.3	0.06	2	1.8	<0.2
1287642	Soil	12	0.10	867	0.004	1	0.67	0.020	0.05	<0.1	0.29	2.7	0.3	<0.05	2	1.4	<0.2
1287643	Soil	15	0.09	223	0.007	2	0.83	0.003	0.04	0.2	0.07	1.5	0.3	<0.05	4	1.4	<0.2
1287644	Soil	20	0.13	1011	0.003	3	0.94	0.007	0.06	0.2	0.68	2.3	0.4	<0.05	3	3.3	<0.2
1287645	Soil	19	0.16	804	0.004	2	0.85	0.007	0.05	0.1	0.37	2.2	0.3	<0.05	3	2.3	<0.2
1287646	Soil	13	0.18	1692	0.005	6	0.55	0.012	0.03	<0.1	0.26	0.8	0.2	0.13	2	4.4	<0.2
1287647	Soil	18	0.08	224	0.003	2	0.94	0.004	0.06	0.1	0.19	1.8	0.5	<0.05	3	2.4	<0.2
1287648	Soil	18	0.08	283	0.003	3	0.92	0.003	0.06	0.2	0.38	2.1	0.6	<0.05	3	2.3	<0.2
1287649	Soil	20	0.09	232	0.008	2	0.92	0.004	0.06	0.2	0.11	1.6	0.7	<0.05	4	2.1	<0.2
1287650	Soil	18	0.08	212	0.005	3	0.86	0.003	0.08	0.2	0.19	1.6	1.0	<0.05	4	2.9	0.2
1287771	Soil	7	0.03	195	0.003	<1	0.61	0.006	0.04	<0.1	0.03	0.7	0.1	<0.05	3	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287772	Soil	2.7	14.6	6.5	42	0.5	9.0	1.4	20	0.78	5.4	1.2	0.3	8	0.4	1.0	<0.1	23	0.02	0.040	2
1287773	Soil	7.3	26.9	21.5	140	1.2	41.0	14.7	255	2.25	18.2	3.6	1.2	62	0.8	2.6	0.3	47	0.25	0.089	4
1287774	Soil	5.2	43.0	15.8	282	1.0	78.8	23.7	1796	2.15	11.8	1.0	1.6	127	3.4	2.9	0.2	36	0.68	0.086	5
1287775	Soil	4.3	27.8	16.7	163	1.1	39.3	10.1	367	1.99	12.1	2.0	1.6	76	1.4	2.2	0.2	39	0.35	0.072	5
1287776	Soil	0.5	29.3	5.2	13	0.5	8.4	0.7	12	0.41	2.5	<0.5	0.4	8	0.6	0.2	0.1	13	0.02	0.028	3
1287777	Soil	7.2	37.7	18.3	224	0.2	38.0	6.4	58	3.35	39.1	1.8	0.6	15	0.6	4.0	0.3	48	0.08	0.049	4
1287778	Soil	4.0	40.7	18.5	185	0.9	45.9	8.5	120	2.25	12.7	1.2	1.7	82	1.6	2.1	0.2	37	0.39	0.090	4
1287779	Soil	13.0	43.1	27.3	117	1.9	26.1	2.9	63	1.98	44.7	12.8	0.8	53	0.7	6.4	0.2	80	0.07	0.138	6
1287780	Soil	9.2	19.7	31.1	81	1.1	15.7	2.0	33	1.16	27.2	9.2	0.5	48	0.6	4.3	0.2	67	0.08	0.089	4
1288171	Soil	2.4	13.1	14.3	82	<0.1	17.0	5.3	62	1.92	14.4	0.5	0.3	8	0.3	1.3	0.2	36	0.02	0.049	5
1288172	Soil	0.9	7.5	6.4	31	0.3	6.7	2.5	24	0.70	5.1	1.1	0.2	6	0.3	0.4	<0.1	16	0.01	0.031	2
1288173	Soil	2.4	14.7	9.6	58	0.5	10.8	2.9	35	1.37	13.2	3.6	0.2	6	0.4	1.3	0.1	33	0.02	0.076	5
1288174	Soil	1.5	12.1	7.0	57	0.2	13.4	3.4	47	1.23	12.5	0.8	0.7	6	0.2	1.0	<0.1	19	0.02	0.024	3
1288175	Soil	16.4	167.9	14.8	411	0.6	585.9	103.2	1816	7.74	582.0	18.0	5.4	88	3.9	64.6	0.1	203	2.00	0.340	71
1288176	Soil	12.9	61.5	32.1	198	0.8	108.2	40.9	843	6.17	1373	96.0	12.8	29	1.8	28.4	0.2	51	0.58	0.181	52
1288177	Soil	20.8	51.6	24.4	192	0.6	105.6	23.7	522	4.28	817.2	42.0	5.7	34	1.2	21.8	0.2	55	0.76	0.134	35
1288178	Soil	34.2	76.8	32.7	1051	1.0	249.4	40.4	1031	6.09	1329	69.0	9.3	130	7.5	67.6	0.2	95	2.10	0.250	38
1288179	Soil	53.9	78.4	26.6	841	1.1	255.2	28.1	638	4.11	700.9	40.2	5.7	69	6.9	33.0	0.2	147	1.50	0.218	26
1288180	Soil	50.7	100.7	29.1	820	1.3	252.9	26.0	599	4.30	694.2	35.8	5.7	112	6.9	32.4	0.2	157	3.81	0.224	22
1288181	Soil	10.3	25.8	11.8	70	1.1	26.5	8.9	370	1.97	36.0	3.3	0.4	11	0.2	2.7	0.2	35	0.12	0.127	10
1288182	Soil	11.6	80.4	23.6	180	1.5	69.1	11.9	187	4.23	147.6	9.3	0.9	37	0.5	7.9	0.3	52	0.05	0.177	15
1288183	Soil	6.9	16.5	5.3	73	0.1	29.1	5.0	51	1.36	62.8	<0.5	0.2	6	<0.1	2.4	0.1	48	0.02	0.040	11
1288184	Soil	8.3	29.7	7.3	83	0.1	49.7	10.3	111	2.39	182.8	<0.5	0.5	5	0.1	4.7	0.2	60	0.02	0.056	18
1288185	Soil	9.7	24.1	8.0	75	0.1	42.1	8.5	112	2.17	141.6	1.2	0.7	6	0.1	4.1	0.2	57	0.02	0.050	17
1288186	Soil	10.0	26.9	8.7	68	<0.1	40.2	8.3	145	2.30	109.7	0.8	0.7	5	<0.1	4.0	0.2	38	0.02	0.059	15
1288187	Soil	5.5	46.4	12.3	74	0.2	50.5	14.0	240	3.93	119.5	3.1	0.7	6	0.1	3.5	0.3	26	0.02	0.084	13
1288188	Soil	7.1	97.9	26.6	194	2.2	76.9	18.6	401	4.84	94.2	7.9	3.2	27	0.4	4.0	0.4	22	0.15	0.137	19
1288189	Soil	46.8	52.5	12.2	232	0.2	128.6	11.7	102	2.82	58.3	2.4	1.3	6	0.6	4.9	0.2	49	0.05	0.085	20
1288190	Soil	18.6	21.5	9.5	91	0.4	38.2	4.8	75	1.70	56.5	1.4	0.3	7	0.2	3.0	0.1	57	0.03	0.104	10
1288191	Soil	12.3	34.3	13.1	147	0.1	70.8	10.7	189	2.92	167.9	2.7	1.7	10	0.4	4.8	0.2	51	0.08	0.186	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287772	Soil	5	0.03	233	0.003	<1	0.50	0.015	0.03	<0.1	0.04	0.7	0.1	<0.05	2	<0.5	<0.2
1287773	Soil	16	0.14	2293	0.003	3	0.94	0.013	0.08	0.1	0.21	2.8	0.2	0.06	3	2.8	<0.2
1287774	Soil	17	0.21	2202	0.001	2	1.04	0.008	0.07	<0.1	0.24	3.7	0.2	0.08	2	3.1	<0.2
1287775	Soil	14	0.15	1714	0.002	2	0.86	0.007	0.06	<0.1	0.20	3.2	0.1	0.05	2	2.0	<0.2
1287776	Soil	5	0.02	274	0.002	<1	0.58	0.009	0.02	<0.1	0.04	0.6	<0.1	<0.05	2	<0.5	<0.2
1287777	Soil	12	0.11	178	0.002	<1	0.54	0.003	0.05	<0.1	0.04	1.5	0.1	<0.05	2	2.5	<0.2
1287778	Soil	17	0.18	2229	0.001	2	0.91	0.006	0.06	<0.1	0.23	2.8	0.2	0.07	2	3.2	<0.2
1287779	Soil	14	0.03	1281	0.001	3	0.55	0.004	0.07	0.2	2.07	1.5	0.9	0.12	2	4.6	<0.2
1287780	Soil	9	0.02	1669	0.001	2	0.32	0.004	0.06	0.2	1.12	0.7	0.5	0.11	2	3.2	<0.2
1288171	Soil	9	0.04	155	0.003	1	0.57	0.006	0.04	<0.1	0.02	0.9	0.2	<0.05	3	<0.5	<0.2
1288172	Soil	6	0.02	113	0.002	<1	0.37	0.009	0.04	<0.1	0.04	0.6	<0.1	<0.05	2	<0.5	<0.2
1288173	Soil	7	0.02	125	0.005	<1	0.47	0.009	0.03	<0.1	0.06	0.5	<0.1	<0.05	3	0.6	<0.2
1288174	Soil	7	0.07	223	0.002	1	0.49	0.013	0.03	<0.1	0.06	1.1	<0.1	<0.05	2	0.5	<0.2
1288175	Soil	177	0.57	1186	0.003	6	0.63	0.004	0.07	1.2	4.94	29.1	0.6	<0.05	2	6.3	<0.2
1288176	Soil	45	0.11	945	0.001	3	0.77	0.004	0.07	0.4	5.47	14.1	0.7	<0.05	2	4.4	<0.2
1288177	Soil	33	0.24	668	0.002	4	0.68	0.008	0.06	0.3	3.98	7.8	0.7	<0.05	2	2.6	<0.2
1288178	Soil	48	0.78	869	0.005	7	0.55	0.006	0.11	0.4	9.20	15.4	1.1	0.12	2	6.6	<0.2
1288179	Soil	30	0.48	542	0.003	5	0.33	0.003	0.08	0.3	6.58	7.9	1.0	0.05	1	4.4	<0.2
1288180	Soil	36	1.81	549	0.002	6	0.36	0.005	0.07	0.4	8.60	7.5	1.0	<0.05	1	4.7	<0.2
1288181	Soil	12	0.05	795	0.003	2	0.70	0.008	0.05	<0.1	1.02	0.7	0.2	<0.05	2	2.1	<0.2
1288182	Soil	14	0.04	826	0.002	2	0.72	0.003	0.05	<0.1	7.12	1.3	0.3	<0.05	2	3.5	<0.2
1288183	Soil	9	0.03	121	0.004	<1	0.40	0.009	0.03	<0.1	0.22	0.3	0.2	<0.05	2	<0.5	<0.2
1288184	Soil	15	0.03	126	0.005	2	0.49	0.006	0.05	0.1	0.16	0.8	0.2	<0.05	3	0.7	<0.2
1288185	Soil	12	0.04	363	0.004	2	0.52	0.004	0.06	0.1	0.30	0.9	0.2	<0.05	3	0.7	<0.2
1288186	Soil	9	0.03	211	0.003	2	0.46	0.005	0.06	<0.1	0.21	0.8	0.2	<0.05	2	0.8	<0.2
1288187	Soil	9	0.04	220	0.003	1	0.54	0.008	0.05	<0.1	0.21	1.2	0.2	<0.05	2	0.8	<0.2
1288188	Soil	9	0.05	1763	0.001	2	0.58	0.004	0.08	<0.1	0.95	4.2	0.2	0.05	1	2.2	0.2
1288189	Soil	12	0.04	270	0.002	2	0.37	0.002	0.05	0.2	0.25	1.9	0.6	<0.05	<1	1.4	<0.2
1288190	Soil	10	0.03	208	0.003	2	0.42	0.005	0.05	<0.1	0.20	0.4	0.3	<0.05	2	0.9	<0.2
1288191	Soil	18	0.05	473	0.002	2	0.53	0.003	0.05	<0.1	0.41	1.8	0.2	<0.05	2	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288192	Soil	9.0	17.4	10.2	70	0.1	27.5	4.6	111	1.99	70.3	0.8	0.4	6	0.1	2.5	0.2	47	0.02	0.065	10
1288193	Soil	11.9	15.3	6.3	59	0.3	27.4	3.6	58	1.30	60.0	1.6	0.2	5	<0.1	2.1	0.1	46	0.01	0.051	11
1288194	Soil	15.5	24.8	8.8	110	0.9	44.2	5.8	167	1.74	102.4	1.6	0.5	9	0.3	3.6	0.2	55	0.04	0.081	11
1288195	Soil	17.1	70.3	17.1	451	0.7	209.0	29.2	530	3.76	96.3	4.5	5.1	85	4.4	5.8	0.1	93	1.02	0.294	42
1288196	Soil	14.7	23.2	9.7	146	0.1	46.7	6.0	120	2.05	34.2	1.8	0.4	9	0.2	3.1	0.2	80	0.02	0.099	14
1288197	Soil	16.3	21.7	10.3	145	0.2	40.0	4.8	79	1.70	35.7	1.3	0.2	9	0.3	3.2	0.2	120	0.04	0.065	12
1288198	Soil	22.6	41.7	12.8	596	0.7	96.0	9.2	235	2.69	60.3	5.2	0.8	23	4.5	6.6	0.2	101	0.22	0.145	15
1288199	Soil	31.0	24.8	16.3	417	0.7	80.0	5.1	79	1.92	42.6	8.3	0.5	10	1.1	6.3	0.2	106	0.02	0.089	13
1288200	Soil	24.0	26.0	15.2	217	0.4	52.1	4.7	62	1.68	38.9	3.0	0.2	14	0.4	5.1	0.1	91	0.03	0.088	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288192	Soil	10	0.04	239	0.005	1	0.52	0.006	0.06	<0.1	0.15	0.4	0.2	<0.05	3	0.6	<0.2
1288193	Soil	9	0.03	143	0.004	1	0.52	0.008	0.05	0.1	0.11	0.3	0.3	<0.05	3	0.5	<0.2
1288194	Soil	12	0.04	488	0.003	1	0.55	0.009	0.04	<0.1	0.38	0.6	0.3	<0.05	2	0.8	<0.2
1288195	Soil	43	0.25	1565	0.003	6	0.50	0.004	0.10	<0.1	1.46	6.2	0.4	0.11	1	2.3	<0.2
1288196	Soil	19	0.07	235	0.004	1	0.64	0.003	0.05	0.1	0.17	0.7	0.4	<0.05	3	1.0	<0.2
1288197	Soil	14	0.05	168	0.005	1	0.58	0.005	0.05	0.1	0.10	0.4	0.5	<0.05	3	1.1	<0.2
1288198	Soil	21	0.08	1054	0.003	3	0.53	0.008	0.06	0.1	1.41	1.6	1.0	0.07	2	2.1	<0.2
1288199	Soil	15	0.05	165	0.002	2	0.42	0.003	0.05	0.1	1.44	0.9	1.1	0.05	2	1.6	<0.2
1288200	Soil	11	0.03	174	0.002	2	0.28	0.005	0.05	0.1	0.33	0.4	0.5	0.07	2	1.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001425.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1287609	Soil	1.4	8.3	7.2	12	0.2	8.8	8.5	224	0.96	3.5	0.5	<0.1	40	0.1	0.5	<0.1	8	0.46	0.064	2
REP 1287609	QC	1.5	8.6	7.3	12	0.3	8.0	8.7	226	1.00	3.4	1.2	0.2	41	0.1	0.5	<0.1	9	0.47	0.071	2
1287629	Soil	3.8	13.1	11.9	162	0.3	22.2	5.1	72	1.81	12.0	1.5	0.4	11	0.3	1.9	0.2	43	0.04	0.090	5
REP 1287629	QC	3.9	13.3	12.2	161	0.3	22.7	5.4	72	1.81	11.9	<0.5	0.4	11	0.4	2.1	0.2	41	0.04	0.088	5
1287554	Soil	4.9	24.2	20.2	128	0.1	23.6	5.4	84	3.26	32.3	2.1	1.6	17	0.4	3.1	0.3	46	0.01	0.069	6
REP 1287554	QC	4.5	22.4	18.3	122	0.1	22.2	5.1	78	3.06	29.5	1.6	1.6	16	0.3	2.8	0.3	45	0.01	0.064	6
1283267	Soil	0.3	1.7	1.8	9	<0.1	2.2	0.6	12	0.21	1.0	<0.5	<0.1	10	0.1	0.2	<0.1	4	0.05	0.018	<1
REP 1283267	QC	0.2	1.7	1.9	9	<0.1	2.0	0.6	11	0.21	1.0	0.6	<0.1	10	<0.1	0.2	<0.1	4	0.04	0.017	<1
1283196	Soil	6.5	33.1	11.0	73	3.1	25.4	2.2	34	1.45	26.9	7.2	0.5	37	0.4	2.4	0.3	30	0.02	0.070	3
REP 1283196	QC	6.2	33.0	12.0	73	3.1	25.2	2.3	35	1.41	27.7	7.7	0.6	37	0.4	2.3	0.2	30	0.02	0.068	3
1281225	Soil	5.2	25.0	11.7	39	1.2	8.5	2.3	217	1.71	36.1	3.2	0.2	65	<0.1	3.8	0.2	65	0.03	0.121	6
REP 1281225	QC	5.2	24.8	12.1	38	1.2	8.4	2.4	216	1.68	35.4	3.3	0.2	64	<0.1	3.9	0.2	62	0.03	0.118	6
1283321	Soil	26.3	63.4	14.2	2269	1.2	242.9	11.0	1004	2.42	35.8	4.8	1.6	60	9.5	8.6	0.2	109	0.68	0.119	13
REP 1283321	QC	25.0	61.7	14.3	2199	1.1	235.5	10.7	984	2.36	34.1	4.5	1.7	60	9.3	8.2	0.2	118	0.66	0.114	14
1284427	Soil	17.1	64.7	22.6	246	1.1	52.1	8.8	209	2.79	35.0	6.6	1.4	82	2.0	7.1	0.3	111	0.19	0.142	11
REP 1284427	QC	16.9	64.1	22.5	244	1.1	51.6	8.4	206	2.73	34.0	7.6	1.4	83	1.9	7.1	0.3	111	0.18	0.142	11
1287051	Soil	4.2	10.6	9.0	46	0.5	9.4	1.2	39	0.70	10.7	1.7	0.2	10	0.5	1.1	0.1	46	0.04	0.062	11
REP 1287051	QC	4.1	10.6	9.1	47	0.5	10.3	1.3	41	0.70	10.5	1.5	0.2	10	0.5	1.2	0.1	47	0.04	0.067	11
1287318	Soil	3.7	8.7	10.4	21	1.4	4.3	1.1	18	0.64	11.1	6.2	0.1	15	<0.1	2.0	0.1	30	0.02	0.047	3
REP 1287318	QC	3.6	8.9	10.4	21	1.4	4.4	1.1	18	0.65	11.0	6.0	0.1	16	<0.1	2.0	0.1	30	0.02	0.047	3
1287206	Soil	6.4	56.8	15.0	290	0.7	69.4	8.5	138	2.37	28.4	7.9	0.9	72	2.0	3.2	0.2	57	0.85	0.154	9
REP 1287206	QC	6.3	56.6	14.9	296	0.7	70.2	8.7	137	2.40	28.7	8.6	0.9	71	2.1	3.1	0.2	54	0.87	0.154	9
1287221	Soil	6.3	48.0	16.6	237	1.8	54.8	7.8	163	2.87	41.0	19.9	1.6	66	1.2	3.4	0.2	68	0.67	0.137	8
REP 1287221	QC	5.8	47.6	16.7	240	1.7	54.1	7.8	158	2.80	40.8	17.4	1.6	65	1.4	3.3	0.2	70	0.65	0.134	8
1287332	Soil	4.3	44.0	14.4	142	1.1	34.4	4.5	67	2.81	26.9	7.5	1.3	24	0.5	2.7	0.2	41	0.07	0.071	4
REP 1287332	QC	4.5	42.9	14.5	141	1.1	33.9	4.7	66	2.79	26.4	3.6	1.3	25	0.4	2.6	0.2	42	0.08	0.073	4
1287350	Soil	22.0	43.3	13.7	317	1.3	75.5	9.8	325	2.10	49.7	15.9	2.0	44	3.6	5.7	0.2	136	0.42	0.114	12
REP 1287350	QC	21.9	43.8	13.9	321	1.3	75.2	10.3	329	2.12	49.3	15.3	2.1	45	3.6	5.7	0.2	137	0.41	0.114	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001425.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1287609	Soil		4	0.07	358	0.008	2	0.34	0.033	0.02	<0.1	0.07	0.7	<0.1	0.09	1	1.1	<0.2
REP 1287609	QC		4	0.07	385	0.011	2	0.35	0.034	0.02	<0.1	0.09	0.9	<0.1	0.11	1	1.5	<0.2
1287629	Soil		14	0.09	350	0.010	1	0.69	0.009	0.04	0.2	0.08	0.8	0.2	0.06	3	1.0	<0.2
REP 1287629	QC		14	0.09	356	0.011	2	0.69	0.009	0.04	0.2	0.06	0.8	0.2	<0.05	3	0.7	<0.2
1287554	Soil		13	0.05	180	0.006	1	0.52	0.003	0.05	0.1	0.03	1.6	0.2	0.06	3	1.6	<0.2
REP 1287554	QC		12	0.05	173	0.006	2	0.49	0.004	0.05	0.1	0.04	1.6	0.2	0.07	3	1.6	<0.2
1283267	Soil		3	0.02	35	0.004	<1	0.10	0.026	0.02	<0.1	<0.01	0.2	<0.1	<0.05	<1	0.5	<0.2
REP 1283267	QC		3	0.02	36	0.004	<1	0.10	0.025	0.02	<0.1	0.01	0.3	<0.1	<0.05	<1	<0.5	<0.2
1283196	Soil		19	0.02	664	0.002	5	0.51	0.009	0.06	<0.1	0.50	1.8	0.1	<0.05	2	2.7	<0.2
REP 1283196	QC		22	0.03	688	0.002	5	0.53	0.009	0.07	0.1	0.48	1.8	0.1	<0.05	2	2.5	<0.2
1281225	Soil		20	0.06	927	0.008	2	0.65	0.010	0.08	0.1	0.02	0.7	0.4	0.13	3	4.0	<0.2
REP 1281225	QC		19	0.06	860	0.007	1	0.65	0.008	0.08	<0.1	0.03	0.6	0.4	0.14	4	4.4	<0.2
1283321	Soil		15	0.10	610	0.002	4	0.40	0.004	0.08	0.1	0.82	3.2	1.0	<0.05	1	4.7	<0.2
REP 1283321	QC		16	0.10	625	0.002	7	0.43	0.005	0.08	0.1	0.81	3.2	1.0	0.05	1	4.2	<0.2
1284427	Soil		24	0.11	1607	0.004	4	0.70	0.005	0.09	0.2	0.66	2.7	0.5	0.07	2	3.3	<0.2
REP 1284427	QC		24	0.12	1580	0.003	3	0.71	0.005	0.09	0.2	0.68	2.8	0.5	0.06	2	3.2	<0.2
1287051	Soil		8	0.04	200	0.005	2	0.48	0.005	0.04	<0.1	0.10	0.3	0.3	<0.05	3	0.7	<0.2
REP 1287051	QC		10	0.04	204	0.004	3	0.50	0.005	0.04	0.1	0.08	0.3	0.3	<0.05	3	0.7	<0.2
1287318	Soil		6	0.01	348	0.003	<1	0.50	0.011	0.03	<0.1	0.15	0.3	0.2	<0.05	2	1.1	<0.2
REP 1287318	QC		6	0.01	341	0.002	1	0.50	0.011	0.03	<0.1	0.15	0.2	0.2	<0.05	2	1.2	<0.2
1287206	Soil		22	0.11	1749	0.004	3	0.88	0.010	0.07	<0.1	1.19	2.8	0.5	0.13	2	2.3	<0.2
REP 1287206	QC		22	0.12	1539	0.004	3	0.87	0.010	0.06	0.1	1.20	2.9	0.4	0.14	2	2.4	<0.2
1287221	Soil		26	0.15	1410	0.003	6	1.17	0.007	0.12	<0.1	2.11	4.2	0.4	<0.05	3	3.0	<0.2
REP 1287221	QC		26	0.15	1413	0.002	7	1.23	0.007	0.12	0.1	2.12	4.2	0.4	<0.05	3	2.7	<0.2
1287332	Soil		18	0.04	502	0.002	2	0.71	0.006	0.06	<0.1	0.23	2.6	0.2	<0.05	2	4.0	<0.2
REP 1287332	QC		19	0.04	516	0.002	3	0.74	0.006	0.07	<0.1	0.31	2.5	0.2	0.06	2	5.1	<0.2
1287350	Soil		27	0.08	1875	0.002	4	0.63	0.003	0.08	<0.1	1.98	3.5	0.6	<0.05	2	2.0	<0.2
REP 1287350	QC		27	0.08	1910	0.002	4	0.64	0.003	0.08	0.1	1.91	3.4	0.5	<0.05	2	2.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001425.2

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1287355	Soil	28.2	54.7	17.4	523	0.6	109.9	13.1	317	2.82	63.7	6.3	1.3	45	5.5	7.5	0.3	100	0.33	0.162	13
REP 1287355	QC	29.2	55.4	17.6	527	0.6	112.1	13.1	325	2.89	65.6	8.5	1.3	46	5.7	7.7	0.2	103	0.35	0.168	13
1287780	Soil	9.2	19.7	31.1	81	1.1	15.7	2.0	33	1.16	27.2	9.2	0.5	48	0.6	4.3	0.2	67	0.08	0.089	4
REP 1287780	QC	8.9	19.4	28.7	76	1.1	15.4	2.0	34	1.13	25.7	9.3	0.5	44	0.5	4.0	0.2	60	0.08	0.085	4
1288191	Soil	12.3	34.3	13.1	147	0.1	70.8	10.7	189	2.92	167.9	2.7	1.7	10	0.4	4.8	0.2	51	0.08	0.186	16
REP 1288191	QC	12.0	33.7	13.2	151	0.1	68.4	10.6	180	2.91	168.7	2.9	2.2	11	0.4	4.9	0.2	50	0.08	0.181	15
Reference Materials																					
STD DS8	Standard	13.1	112.8	130.9	310	1.9	38.4	7.7	610	2.46	25.7	121.3	6.7	66	2.3	5.8	6.9	43	0.68	0.087	14
STD DS8	Standard	12.3	107.5	122.2	309	1.8	36.8	7.4	594	2.39	25.4	108.3	6.5	65	2.4	5.8	6.7	41	0.67	0.083	14
STD DS8	Standard	14.3	119.8	122.8	309	1.7	40.2	7.7	614	2.50	24.1	115.3	7.2	69	2.5	5.9	7.0	44	0.70	0.076	16
STD DS8	Standard	14.5	118.1	124.2	314	1.8	39.3	7.8	609	2.45	23.9	116.7	7.1	69	2.4	5.7	6.7	45	0.70	0.083	17
STD DS8	Standard	13.6	107.6	126.4	295	1.7	38.8	7.7	585	2.36	22.3	105.8	6.6	61	2.1	5.2	5.8	42	0.67	0.075	15
STD DS8	Standard	13.2	106.8	119.9	305	1.8	37.3	7.5	597	2.42	24.7	108.3	6.6	67	2.4	5.2	6.3	42	0.67	0.078	15
STD DS8	Standard	12.9	112.3	124.1	316	1.9	38.0	7.7	610	2.48	25.6	113.3	6.6	65	2.4	5.5	6.5	42	0.66	0.081	14
STD DS8	Standard	13.1	107.8	123.5	315	1.7	37.5	7.5	612	2.46	24.9	121.0	6.8	65	2.3	5.3	6.6	42	0.68	0.081	14
STD DS8	Standard	12.9	107.6	126.6	306	1.8	36.7	7.3	602	2.43	24.2	121.2	6.6	68	2.4	5.5	6.4	41	0.70	0.077	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001425.2

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1287355	Soil	17	0.06	754	0.003	4	0.51	0.004	0.06	0.2	1.14	2.3	0.7	<0.05	1	3.0	<0.2
REP 1287355	QC	17	0.06	786	0.003	3	0.53	0.004	0.07	0.2	1.19	2.4	0.6	0.05	1	3.3	<0.2
1287780	Soil	9	0.02	1669	0.001	2	0.32	0.004	0.06	0.2	1.12	0.7	0.5	0.11	2	3.2	<0.2
REP 1287780	QC	9	0.02	1402	0.001	2	0.29	0.003	0.05	0.1	1.09	0.8	0.5	0.10	2	3.4	<0.2
1288191	Soil	18	0.05	473	0.002	2	0.53	0.003	0.05	<0.1	0.41	1.8	0.2	<0.05	2	1.2	<0.2
REP 1288191	QC	17	0.05	477	0.002	2	0.52	0.002	0.05	0.1	0.62	1.7	0.2	<0.05	2	1.1	<0.2
Reference Materials																	
STD DS8	Standard	114	0.60	273	0.116	3	0.91	0.096	0.42	3.0	0.20	2.6	5.7	0.17	5	5.4	5.1
STD DS8	Standard	113	0.59	280	0.114	3	0.90	0.099	0.40	2.9	0.19	2.5	5.3	0.15	5	5.3	4.7
STD DS8	Standard	125	0.61	280	0.129	3	0.93	0.105	0.43	2.9	0.20	2.4	5.2	0.17	5	4.4	4.7
STD DS8	Standard	125	0.61	282	0.133	2	0.96	0.094	0.44	2.9	0.21	2.2	5.5	0.17	5	5.1	5.1
STD DS8	Standard	118	0.58	252	0.114	2	0.90	0.094	0.40	2.7	0.18	2.6	5.3	0.15	5	4.9	4.6
STD DS8	Standard	114	0.60	275	0.118	2	0.90	0.099	0.40	2.8	0.20	2.5	5.4	0.12	5	4.5	4.6
STD DS8	Standard	116	0.60	273	0.115	3	0.89	0.091	0.41	3.0	0.20	2.5	5.4	0.14	5	4.9	5.0
STD DS8	Standard	115	0.63	264	0.113	3	0.90	0.099	0.41	2.8	0.22	2.4	5.3	0.16	5	5.4	4.6
STD DS8	Standard	114	0.59	273	0.117	3	0.93	0.108	0.43	2.7	0.19	2.7	5.5	0.14	5	5.0	5.1
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 26, 2011
Report Date: October 19, 2011
Page: 1 of 11

CERTIFICATE OF ANALYSIS WHI11001471.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #18
P.O. Number
Number of Samples: 290

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	290	Sieve soil to 230 mesh			WHI
RJSV	290	Saving all or part of Soil Reject			WHI
1DX2	288	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280861	Soil	15.1	97.8	25.0	320	0.7	72.1	24.3	761	6.46	37.5	11.7	0.9	25	0.7	3.8	0.5	29	0.07	0.094	5
1280862	Soil	2.9	196.0	25.5	385	0.5	95.0	27.3	1024	16.53	99.9	24.5	2.0	5	0.9	7.7	0.4	71	0.04	0.109	7
1280863	Soil	3.7	73.2	17.5	149	0.2	32.4	8.6	164	2.94	18.1	4.8	0.2	17	0.6	1.9	0.3	48	0.08	0.124	7
1280864	Soil	8.4	84.6	31.0	198	0.4	51.0	15.1	423	4.13	25.1	6.9	0.5	45	0.6	3.5	0.3	42	0.05	0.129	12
1280865	Soil	3.4	104.2	12.8	148	1.2	32.7	6.2	488	2.38	9.4	18.4	0.6	81	0.9	2.0	0.2	37	2.40	0.192	13
1280866	Soil	48.2	148.3	18.9	293	5.3	73.1	2.1	44	2.13	39.0	4.0	2.4	147	4.8	23.6	0.3	191	0.41	0.086	10
1280867	Soil	7.5	103.9	16.8	170	1.1	41.3	8.5	239	2.78	23.0	13.6	1.7	72	1.2	3.6	0.3	71	0.60	0.169	10
1280868	Soil	4.1	79.7	12.9	246	0.7	44.4	6.6	237	2.45	10.4	14.3	0.7	70	1.4	2.3	0.2	55	1.14	0.176	10
1280869	Soil	8.6	89.5	15.6	174	1.6	39.9	5.9	184	2.09	14.0	12.0	0.9	87	1.4	4.3	0.2	108	0.86	0.171	11
1280870	Soil	4.7	58.3	12.5	121	0.4	24.1	6.7	274	2.22	9.9	5.9	0.3	34	0.7	2.0	0.2	49	0.39	0.222	9
1280871	Soil	3.0	34.0	13.1	73	0.4	12.6	3.2	174	1.45	6.9	5.5	0.2	41	0.5	1.1	0.2	42	0.56	0.179	7
1280872	Soil	6.1	103.8	14.3	261	1.4	48.8	7.4	198	2.43	13.2	22.6	0.9	93	2.2	2.9	0.2	63	1.54	0.232	14
1280873	Soil	4.9	92.2	12.6	253	1.3	46.1	6.9	230	2.23	11.0	15.2	0.8	82	2.0	2.6	0.2	53	1.52	0.189	14
1280874	Soil	1.8	50.4	6.3	75	0.6	18.6	3.6	182	1.17	4.4	8.4	0.5	70	0.9	1.1	0.1	29	1.43	0.168	8
1280875	Soil	4.0	79.6	11.5	164	1.1	35.7	6.4	229	2.02	10.3	15.2	1.0	76	0.9	2.2	0.2	56	1.43	0.193	12
1280876	Soil	1.2	33.4	6.3	89	0.2	16.7	5.1	123	1.33	3.5	4.5	1.3	56	0.3	0.8	0.2	34	1.12	0.079	8
1280877	Soil	2.2	49.5	10.3	137	0.7	25.7	8.3	230	2.10	6.8	10.0	2.7	54	0.6	1.2	0.2	55	0.85	0.123	13
1280878	Soil	2.0	41.8	9.3	70	<0.1	11.6	3.4	70	1.95	3.8	4.4	0.7	18	0.6	0.9	0.2	32	0.10	0.094	8
1280879	Soil	1.9	66.7	8.9	153	0.7	32.9	8.0	133	1.99	6.3	11.2	2.9	54	0.9	1.2	0.2	48	0.81	0.131	16
1280880	Soil	3.0	37.8	10.6	121	0.5	24.0	7.9	183	2.13	6.7	8.8	1.8	44	0.4	1.0	0.2	38	0.81	0.078	10
1280881	Soil	20.2	65.2	9.7	254	0.5	39.1	6.0	143	1.84	13.5	6.8	1.4	35	2.6	5.2	0.2	164	0.47	0.083	11
1280882	Soil	7.0	55.0	10.3	276	0.6	38.2	8.6	195	2.31	7.7	12.2	2.0	42	1.3	2.6	0.2	60	0.85	0.069	10
1280883	Soil	6.7	40.5	13.9	143	0.3	26.0	5.9	152	2.87	15.7	4.2	1.5	12	0.3	2.8	0.2	94	0.05	0.095	10
1280884	Soil	2.6	13.7	7.3	43	0.3	7.8	2.0	41	0.78	4.7	<0.5	0.3	8	0.1	1.0	0.2	40	0.03	0.032	10
1280885	Soil	2.6	25.8	6.4	57	0.2	12.6	5.1	141	1.33	5.4	3.6	0.4	11	0.2	1.2	0.1	28	0.03	0.071	5
1280886	Soil	1.6	13.0	4.1	29	0.5	5.6	2.8	106	0.72	3.1	3.3	0.4	14	0.1	0.5	<0.1	21	0.12	0.061	4
1280887	Soil	5.2	59.9	14.0	180	0.3	31.8	11.4	499	2.93	15.8	6.5	1.2	35	0.7	3.1	0.2	68	0.20	0.286	11
1280888	Soil	3.4	56.5	13.2	143	0.8	37.4	8.0	282	2.34	12.9	5.8	0.9	120	1.1	2.2	0.2	51	3.84	0.114	13
1280889	Soil	1.5	94.5	8.6	132	0.8	32.5	6.7	245	1.64	5.6	12.9	0.8	72	1.3	1.8	0.2	32	2.14	0.131	10
1280890	Soil	0.8	16.9	3.7	21	0.3	5.5	1.4	31	0.66	2.1	1.0	<0.1	5	0.1	0.5	<0.1	17	0.04	0.031	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280861	Soil	9	0.06	1682	0.003	3	0.58	0.006	0.07	<0.1	0.27	4.7	0.2	0.06	2	1.8	<0.2
1280862	Soil	23	0.10	84	0.004	3	0.71	0.003	0.05	<0.1	0.23	5.8	0.1	<0.05	3	4.0	<0.2
1280863	Soil	16	0.07	145	0.003	3	0.54	0.005	0.06	0.2	0.08	0.6	0.1	0.10	3	1.7	<0.2
1280864	Soil	15	0.12	290	0.004	3	0.64	0.007	0.13	<0.1	0.13	1.3	0.2	0.12	3	2.4	<0.2
1280865	Soil	17	0.22	818	0.004	7	0.77	0.005	0.08	<0.1	0.61	1.6	0.2	0.16	2	2.4	<0.2
1280866	Soil	15	0.04	603	0.002	3	0.37	0.005	0.13	0.1	1.50	2.7	1.1	0.30	2	11.3	<0.2
1280867	Soil	20	0.27	487	0.006	4	0.92	0.005	0.13	<0.1	0.32	2.4	0.3	0.10	3	3.3	<0.2
1280868	Soil	17	0.18	402	0.005	5	0.91	0.010	0.08	<0.1	0.21	1.4	0.1	0.10	3	2.1	<0.2
1280869	Soil	22	0.16	579	0.004	4	0.81	0.006	0.08	<0.1	0.54	2.0	0.3	0.13	3	2.9	<0.2
1280870	Soil	19	0.22	203	0.002	4	0.91	0.007	0.11	0.1	0.12	0.3	0.1	0.08	3	1.7	<0.2
1280871	Soil	16	0.12	374	0.002	1	0.97	0.004	0.08	<0.1	0.19	0.2	0.2	0.09	4	1.7	<0.2
1280872	Soil	18	0.27	489	0.005	4	1.06	0.008	0.09	0.1	0.51	1.8	0.2	0.13	3	3.1	<0.2
1280873	Soil	16	0.24	500	0.006	5	1.06	0.011	0.08	<0.1	0.46	1.9	0.2	0.09	3	2.9	<0.2
1280874	Soil	12	0.15	539	0.006	3	0.93	0.014	0.05	<0.1	0.24	0.8	<0.1	0.14	3	2.2	<0.2
1280875	Soil	17	0.26	568	0.005	4	1.06	0.009	0.07	<0.1	0.39	2.0	0.2	0.12	3	2.8	<0.2
1280876	Soil	14	0.36	298	0.008	4	0.91	0.010	0.10	<0.1	0.10	1.2	<0.1	0.06	3	1.3	<0.2
1280877	Soil	22	0.57	448	0.007	5	1.34	0.007	0.14	<0.1	0.26	3.0	0.2	<0.05	4	1.4	<0.2
1280878	Soil	17	0.13	240	0.007	3	0.79	0.006	0.10	<0.1	0.06	1.5	<0.1	0.08	4	0.9	<0.2
1280879	Soil	22	0.49	359	0.013	5	1.15	0.006	0.12	0.2	0.35	3.4	0.1	<0.05	4	1.4	<0.2
1280880	Soil	20	0.47	394	0.005	4	1.07	0.006	0.11	<0.1	0.24	2.5	0.1	<0.05	4	1.3	<0.2
1280881	Soil	17	0.23	798	0.004	4	0.77	0.005	0.10	<0.1	0.54	2.2	0.4	0.05	3	2.1	<0.2
1280882	Soil	20	0.45	448	0.005	5	1.05	0.006	0.10	<0.1	0.35	3.0	0.2	<0.05	3	1.9	<0.2
1280883	Soil	22	0.19	218	0.004	2	1.15	0.004	0.08	<0.1	0.09	1.6	0.2	<0.05	5	1.7	<0.2
1280884	Soil	9	0.04	94	0.008	2	0.43	0.005	0.05	0.1	0.03	0.4	0.1	<0.05	4	0.8	<0.2
1280885	Soil	9	0.07	94	0.005	2	0.41	0.009	0.05	<0.1	0.06	0.6	<0.1	<0.05	2	0.7	<0.2
1280886	Soil	8	0.09	210	0.003	1	0.40	0.015	0.05	<0.1	0.12	0.6	<0.1	<0.05	1	<0.5	<0.2
1280887	Soil	21	0.31	250	0.005	4	1.02	0.005	0.11	<0.1	0.09	1.2	0.2	<0.05	3	2.0	<0.2
1280888	Soil	19	0.59	778	0.006	6	0.99	0.008	0.07	<0.1	0.91	1.7	0.1	0.09	3	1.5	<0.2
1280889	Soil	16	0.32	364	0.006	6	0.84	0.008	0.08	0.1	0.54	1.7	0.1	0.13	2	3.4	<0.2
1280890	Soil	5	0.02	37	0.002	1	0.19	0.013	0.03	<0.1	0.04	0.2	<0.1	<0.05	1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280891	Soil	2.8	77.6	12.8	132	0.7	39.2	9.1	300	2.44	9.7	15.4	1.9	63	0.8	1.9	0.2	60	1.52	0.118	16
1280892	Soil	3.5	55.9	16.6	203	0.2	32.0	10.1	262	2.78	8.6	4.1	1.3	44	1.7	1.7	0.3	63	0.96	0.090	9
1280893	Soil	3.3	90.4	13.1	165	<0.1	20.6	7.6	261	3.97	9.9	24.2	1.0	9	1.2	2.1	0.5	96	0.04	0.074	11
1280894	Soil	2.3	33.3	14.3	173	0.6	20.1	4.6	275	1.62	9.1	1.8	0.4	167	1.6	2.1	0.1	28	4.92	0.107	9
1280895	Soil	5.2	56.7	11.6	133	0.6	40.3	7.5	137	2.84	22.0	8.0	2.6	28	0.8	3.1	0.2	94	0.52	0.051	16
1280896	Soil	4.8	34.8	17.0	141	0.4	18.4	6.9	173	3.58	12.0	1.2	1.1	12	1.4	2.1	0.3	90	0.06	0.089	11
1280897	Soil	22.1	67.0	25.0	299	0.9	50.6	9.9	147	3.53	19.9	2.9	1.0	17	1.0	4.0	0.4	82	0.03	0.096	10
1280898	Soil	5.3	44.2	17.1	128	0.4	21.5	6.5	212	3.22	14.4	3.8	1.7	21	0.7	1.9	0.3	86	0.05	0.160	10
1280899	Soil	4.1	71.6	12.3	106	0.5	18.4	3.3	53	1.64	7.3	10.6	0.1	13	0.3	1.8	0.3	63	0.05	0.092	11
1280900	Soil	0.6	15.2	4.4	69	0.2	6.0	2.0	134	0.72	1.9	1.4	0.1	53	1.1	0.4	0.1	22	1.42	0.079	6
1280901	Soil	2.8	23.0	7.7	49	0.2	8.0	2.2	31	0.74	4.5	1.9	0.1	16	0.4	1.2	0.1	36	0.11	0.047	6
1280902	Soil	3.6	32.1	17.8	96	0.3	21.9	10.0	444	3.77	16.6	5.5	3.4	19	0.6	1.7	0.3	72	0.12	0.121	11
1280903	Soil	4.0	76.9	9.1	112	1.0	20.7	5.3	137	1.61	6.0	13.9	0.3	35	0.8	1.7	0.1	34	0.37	0.153	8
1280904	Soil	0.5	7.1	2.1	17	0.2	2.9	0.8	17	0.29	2.9	3.2	<0.1	9	0.1	0.3	<0.1	8	0.11	0.034	2
1280905	Soil	8.0	37.8	57.3	113	0.3	20.8	7.6	710	2.32	25.1	2.8	2.0	147	0.8	2.5	0.6	60	0.52	0.106	18
1280906	Soil	2.4	45.3	10.6	147	0.6	25.8	8.2	428	1.86	8.1	4.9	1.7	49	1.0	1.1	0.2	53	0.79	0.128	14
1280907	Soil	1.8	57.3	9.5	161	0.8	36.5	5.5	144	1.82	7.1	7.5	2.1	86	1.3	1.1	0.2	53	1.83	0.185	16
1280908	Soil	0.4	41.2	8.9	110	0.5	19.3	5.0	240	1.28	7.2	5.6	0.9	92	0.7	0.9	0.2	35	2.38	0.103	11
1280909	Soil	2.4	63.0	26.9	49	1.0	19.9	4.6	228	1.29	10.7	4.3	1.2	58	0.8	1.2	0.3	34	0.60	0.115	12
1280910	Soil	1.7	78.5	11.6	84	0.6	47.5	7.6	290	1.95	9.9	6.9	1.5	82	0.9	2.2	0.2	30	1.74	0.104	13
1280911	Soil	1.7	75.2	13.2	164	0.8	45.3	8.5	354	1.92	9.8	6.0	2.7	72	1.5	1.7	0.2	41	1.36	0.106	15
1280912	Soil	3.6	46.4	10.8	137	0.7	24.5	5.8	111	1.85	51.1	8.1	1.3	48	1.3	3.6	0.2	32	0.54	0.115	9
1280913	Soil	3.6	43.8	14.5	116	0.2	25.3	7.3	241	3.06	9.7	1.1	0.1	9	0.7	2.0	0.3	43	0.04	0.110	5
1280914	Soil	13.7	103.0	35.9	241	0.2	70.9	16.1	310	5.82	27.2	3.8	1.3	15	0.4	5.8	0.5	66	0.02	0.065	6
1280915	Soil	8.4	114.4	21.0	325	0.5	50.6	9.8	116	3.44	14.9	6.9	0.3	12	0.4	4.2	0.3	75	0.01	0.080	9
1280916	Soil	6.4	31.1	11.0	101	0.1	20.5	4.3	60	1.73	11.3	<0.5	0.2	12	0.1	3.1	0.2	84	0.01	0.042	9
1280917	Soil	9.5	99.9	20.6	351	0.3	48.4	8.8	161	3.66	19.8	6.4	0.3	26	1.4	5.1	0.3	80	0.03	0.149	8
1280918	Soil	4.4	75.3	15.0	317	0.5	30.3	8.9	697	3.48	7.7	2.3	0.4	12	13.1	2.0	0.3	45	0.03	0.171	6
1280919	Soil	5.4	127.5	13.4	338	0.3	44.9	11.4	193	4.25	7.9	3.9	0.2	10	2.6	2.0	0.4	48	0.05	0.165	5
1280920	Soil	6.0	123.6	23.4	285	0.4	41.1	14.7	729	5.58	17.5	7.0	0.9	26	1.8	2.9	0.3	46	0.19	0.201	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280891	Soil	23	0.41	768	0.004	4	1.13	0.006	0.09	0.2	0.43	3.7	0.1	<0.05	3	1.5	<0.2
1280892	Soil	18	0.19	292	0.005	2	1.21	0.007	0.08	0.2	0.11	2.0	0.1	0.06	3	1.5	<0.2
1280893	Soil	27	0.08	103	0.007	1	0.93	0.006	0.04	0.1	0.04	1.9	<0.1	<0.05	7	1.2	0.3
1280894	Soil	11	0.99	420	0.004	6	0.64	0.011	0.06	<0.1	0.21	0.7	0.1	0.11	2	1.0	<0.2
1280895	Soil	28	0.25	806	0.002	2	1.47	0.004	0.08	<0.1	0.18	3.5	0.2	<0.05	4	1.5	<0.2
1280896	Soil	20	0.26	259	0.007	2	1.11	0.004	0.10	0.1	0.03	1.2	0.2	<0.05	7	1.1	<0.2
1280897	Soil	15	0.10	216	0.008	3	0.83	0.003	0.11	0.1	0.05	1.8	0.3	0.06	6	1.8	<0.2
1280898	Soil	22	0.25	246	0.007	3	1.32	0.004	0.13	0.1	0.03	1.8	0.2	<0.05	5	1.4	<0.2
1280899	Soil	14	0.03	187	0.004	2	0.56	0.003	0.05	0.1	0.03	0.3	0.1	<0.05	5	1.4	<0.2
1280900	Soil	6	0.05	250	0.008	2	0.58	0.023	0.02	<0.1	0.06	0.6	<0.1	0.10	1	0.9	<0.2
1280901	Soil	8	0.04	204	0.006	2	0.38	0.011	0.05	<0.1	0.05	0.5	0.1	<0.05	2	1.1	<0.2
1280902	Soil	27	0.38	204	0.020	2	1.61	0.006	0.07	0.2	0.08	2.0	0.2	<0.05	5	1.5	<0.2
1280903	Soil	11	0.18	275	0.005	2	0.73	0.017	0.06	<0.1	0.27	1.0	0.2	0.05	2	2.1	<0.2
1280904	Soil	4	0.02	59	0.007	2	0.14	0.017	0.03	<0.1	0.06	0.8	<0.1	<0.05	<1	0.6	<0.2
1280905	Soil	21	0.12	609	0.005	3	0.70	0.005	0.12	0.1	0.08	1.5	0.1	0.11	4	1.7	0.3
1280906	Soil	19	0.40	524	0.006	4	1.12	0.008	0.13	<0.1	0.33	2.8	0.2	0.05	4	1.2	<0.2
1280907	Soil	23	0.47	544	0.005	7	0.98	0.005	0.15	<0.1	0.40	3.4	0.1	0.10	3	1.8	<0.2
1280908	Soil	15	0.28	433	0.006	6	0.75	0.011	0.08	<0.1	0.28	2.2	0.1	0.13	2	1.7	<0.2
1280909	Soil	12	0.10	432	0.003	4	0.68	0.006	0.08	<0.1	0.25	2.6	<0.1	0.06	2	2.0	<0.2
1280910	Soil	16	0.24	833	0.008	4	0.87	0.005	0.08	0.1	0.58	3.2	0.1	0.12	2	4.3	<0.2
1280911	Soil	18	0.41	644	0.005	5	1.06	0.006	0.12	<0.1	0.35	4.1	0.2	0.05	3	2.3	<0.2
1280912	Soil	10	0.17	332	0.004	4	0.56	0.009	0.08	<0.1	0.37	2.2	0.1	0.06	2	2.2	<0.2
1280913	Soil	11	0.04	393	0.003	4	0.48	0.006	0.08	<0.1	0.03	0.3	0.1	<0.05	3	1.0	<0.2
1280914	Soil	12	0.04	1009	0.003	3	0.55	0.003	0.08	<0.1	0.09	3.3	0.3	<0.05	2	2.9	<0.2
1280915	Soil	12	0.04	79	0.004	3	0.39	0.001	0.08	<0.1	0.03	1.4	0.2	<0.05	3	3.7	<0.2
1280916	Soil	10	0.03	93	0.004	2	0.48	0.004	0.04	0.1	0.01	0.4	0.1	<0.05	3	1.2	<0.2
1280917	Soil	15	0.06	165	0.003	4	0.61	0.003	0.09	<0.1	0.08	0.6	0.3	<0.05	3	3.5	<0.2
1280918	Soil	13	0.05	186	0.004	3	0.70	0.005	0.10	<0.1	0.04	0.6	0.1	<0.05	3	1.3	<0.2
1280919	Soil	11	0.06	193	0.004	5	0.60	0.002	0.15	<0.1	0.05	1.2	0.1	<0.05	3	1.5	<0.2
1280920	Soil	13	0.11	281	0.005	3	0.64	0.003	0.14	<0.1	0.09	2.6	0.2	<0.05	2	2.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280921	Soil	8.7	168.8	33.7	1523	2.2	48.4	10.5	1693	8.36	28.1	55.6	1.8	102	9.9	4.6	0.2	66	4.78	0.154	9
1280922	Soil	6.8	108.2	18.6	198	0.2	35.5	7.9	138	3.09	19.1	4.5	0.2	11	0.4	3.7	0.3	84	0.05	0.073	9
1280923	Soil	4.4	170.9	37.5	370	0.4	80.4	18.0	439	5.72	25.7	16.5	0.7	12	0.8	4.4	0.5	59	0.03	0.098	7
1280924	Soil	7.3	85.9	35.0	214	0.3	46.1	18.3	2448	6.09	16.5	3.8	1.2	24	1.6	2.5	0.4	35	0.06	0.127	7
1280925	Soil	2.6	18.4	5.8	57	<0.1	12.5	3.5	112	1.54	5.3	4.2	0.3	7	0.1	1.0	0.2	35	0.04	0.032	10
1280926	Soil	4.2	106.8	14.6	179	<0.1	30.0	6.0	122	2.43	17.0	18.2	0.2	6	0.2	2.2	0.3	58	0.03	0.085	7
1280927	Soil	2.2	44.2	14.7	88	<0.1	20.8	7.0	231	2.61	10.3	51.6	1.0	7	0.1	1.5	0.3	41	0.06	0.053	9
1280928	Soil	6.8	145.3	20.0	1850	1.4	52.6	7.9	582	4.35	18.5	26.9	1.4	71	7.2	3.8	0.2	89	1.58	0.228	10
1280929	Soil	2.7	194.7	32.7	102	0.2	53.2	21.4	592	5.81	19.2	21.4	1.4	8	0.3	3.0	0.5	59	0.04	0.097	7
1280930	Soil	3.4	24.8	8.3	73	0.1	11.4	2.8	59	1.03	7.0	0.8	0.2	9	0.1	1.3	0.2	44	0.04	0.070	8
1280931	Soil	16.9	74.7	33.4	183	0.3	54.0	17.4	1095	5.35	18.6	4.8	2.8	20	0.3	2.2	0.4	34	0.04	0.111	12
1280932	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280933	Soil	2.3	13.3	7.3	37	0.2	7.9	1.8	69	0.76	4.0	<0.5	<0.1	9	0.1	1.0	0.1	27	0.03	0.044	3
1280934	Soil	9.6	51.6	18.7	180	3.7	45.5	4.9	417	2.43	16.7	23.9	0.8	72	3.4	4.7	0.3	139	0.62	0.255	11
1280935	Soil	3.2	15.9	11.3	46	0.5	8.0	1.5	60	0.96	5.1	2.1	<0.1	17	0.2	1.1	0.2	51	0.04	0.094	6
1280936	Soil	3.3	40.5	11.5	86	0.8	19.7	2.9	115	1.47	6.8	4.8	0.2	26	0.9	1.5	0.2	50	0.12	0.189	8
1280937	Soil	2.9	25.5	10.2	55	0.8	13.6	2.0	85	1.06	4.7	2.3	0.3	31	1.0	1.0	0.2	38	0.25	0.202	6
1280938	Soil	2.6	15.3	6.9	36	0.2	7.5	1.4	30	0.62	3.6	1.3	0.2	13	0.4	0.9	0.1	31	0.03	0.071	8
1280939	Soil	3.3	25.5	8.9	66	0.5	12.4	2.7	58	1.23	5.8	2.5	0.1	10	0.2	1.5	0.2	40	0.02	0.083	5
1280940	Soil	3.1	16.0	11.2	51	0.2	9.7	2.2	49	0.94	6.5	<0.5	0.2	9	<0.1	1.4	0.2	46	0.01	0.029	11
1280941	Soil	4.6	20.8	15.1	73	0.2	15.9	3.1	73	1.48	11.5	0.7	<0.1	13	<0.1	2.0	0.3	62	0.02	0.058	8
1280942	Soil	2.4	13.3	9.5	51	0.1	10.8	2.2	77	1.00	6.6	1.2	0.1	10	0.4	1.1	0.2	42	0.03	0.090	9
1280943	Soil	2.4	14.6	10.7	38	<0.1	9.9	1.8	58	0.90	5.5	0.7	0.2	14	0.2	0.8	0.2	50	0.04	0.091	9
1280944	Soil	2.5	12.9	6.2	35	0.2	8.0	1.7	37	0.74	3.9	3.2	0.3	6	<0.1	1.0	0.1	38	0.01	0.030	12
1280945	Soil	2.6	17.8	8.7	50	0.3	11.5	2.4	84	0.95	5.8	1.6	0.1	13	0.3	1.1	0.1	38	0.05	0.064	7
1280946	Soil	3.7	30.9	13.4	75	0.5	17.1	3.4	111	1.80	9.3	4.8	0.2	20	0.4	1.7	0.2	55	0.09	0.169	8
1280947	Soil	0.4	7.3	2.1	20	<0.1	3.9	0.8	31	0.32	0.6	<0.5	0.1	20	0.5	0.2	<0.1	11	0.52	0.017	1
1280948	Soil	4.0	42.1	16.5	252	1.0	35.7	11.1	340	2.51	11.8	2.3	1.4	101	5.9	1.9	0.2	70	2.58	0.144	21
1280949	Soil	3.1	22.7	9.6	67	<0.1	13.8	2.7	85	1.29	14.2	2.9	0.2	8	0.2	1.6	0.2	60	0.04	0.038	9
1280950	Soil	6.7	43.7	23.2	154	0.2	32.3	5.6	167	2.64	17.1	<0.5	0.2	20	0.4	3.5	0.3	92	0.06	0.126	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280921	Soil	14	1.65	386	0.005	5	0.44	0.004	0.11	<0.1	2.09	4.0	0.2	0.07	2	6.0	0.3
1280922	Soil	15	0.04	106	0.006	3	0.47	0.003	0.08	0.1	0.06	0.9	0.2	0.05	4	2.2	<0.2
1280923	Soil	21	0.08	78	0.009	2	0.70	0.003	0.06	0.1	0.10	3.4	0.2	<0.05	3	2.5	<0.2
1280924	Soil	10	0.06	456	0.005	4	0.63	0.003	0.15	<0.1	0.18	4.0	0.2	0.12	2	1.1	<0.2
1280925	Soil	9	0.03	263	0.006	2	0.41	0.002	0.08	0.1	0.03	0.6	<0.1	<0.05	3	<0.5	<0.2
1280926	Soil	12	0.04	95	0.003	3	0.49	0.002	0.06	0.1	0.04	0.6	0.1	<0.05	4	1.7	<0.2
1280927	Soil	14	0.11	136	0.014	3	0.70	0.004	0.09	0.2	0.04	1.7	<0.1	<0.05	3	0.7	<0.2
1280928	Soil	21	0.32	639	0.006	6	0.85	0.006	0.09	0.1	4.28	2.9	0.2	<0.05	3	3.5	0.2
1280929	Soil	18	0.12	88	0.012	2	0.79	0.010	0.06	0.1	0.04	5.6	0.1	<0.05	4	1.8	0.3
1280930	Soil	9	0.03	109	0.005	3	0.42	0.004	0.05	0.1	0.05	0.4	0.1	<0.05	3	0.8	<0.2
1280931	Soil	15	0.14	780	0.004	4	0.99	0.005	0.14	<0.1	0.23	2.6	0.4	0.06	3	1.6	<0.2
1280932	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280933	Soil	6	0.02	119	0.004	3	0.25	0.010	0.04	<0.1	0.05	0.3	0.1	0.05	1	<0.5	<0.2
1280934	Soil	20	0.19	1055	0.006	8	1.23	0.008	0.15	<0.1	1.60	2.7	0.5	0.16	4	4.7	<0.2
1280935	Soil	11	0.05	149	0.003	2	0.55	0.009	0.06	<0.1	0.06	0.2	0.2	<0.05	3	0.7	<0.2
1280936	Soil	13	0.08	587	0.007	3	0.89	0.010	0.08	0.2	0.27	1.0	0.2	0.07	3	1.0	<0.2
1280937	Soil	11	0.09	634	0.008	2	0.75	0.008	0.06	0.1	0.16	0.9	0.2	0.09	3	1.1	<0.2
1280938	Soil	8	0.03	284	0.008	3	0.44	0.006	0.04	0.1	0.03	0.7	0.1	<0.05	3	<0.5	<0.2
1280939	Soil	8	0.03	113	0.006	2	0.47	0.008	0.05	<0.1	0.04	0.3	0.1	<0.05	3	0.9	<0.2
1280940	Soil	7	0.02	93	0.007	2	0.37	0.003	0.04	0.1	0.02	0.4	0.1	<0.05	4	<0.5	<0.2
1280941	Soil	9	0.03	113	0.004	1	0.41	0.004	0.04	0.1	0.03	0.2	0.2	<0.05	4	0.8	<0.2
1280942	Soil	13	0.04	134	0.007	2	0.60	0.005	0.05	0.1	0.03	0.2	0.1	<0.05	4	<0.5	<0.2
1280943	Soil	17	0.06	154	0.004	2	0.76	0.005	0.05	0.1	0.03	0.3	0.2	<0.05	5	<0.5	<0.2
1280944	Soil	9	0.02	71	0.005	2	0.41	0.004	0.04	0.2	0.02	0.4	0.1	<0.05	4	<0.5	<0.2
1280945	Soil	11	0.03	182	0.004	<1	0.49	0.010	0.04	<0.1	0.04	0.3	0.1	<0.05	3	<0.5	<0.2
1280946	Soil	18	0.12	234	0.003	2	0.89	0.007	0.05	<0.1	0.16	0.5	0.2	0.06	3	1.1	<0.2
1280947	Soil	4	0.03	110	0.008	1	0.24	0.031	0.03	<0.1	0.02	0.3	<0.1	<0.05	<1	<0.5	<0.2
1280948	Soil	34	0.27	618	0.013	6	2.05	0.006	0.07	0.2	0.79	3.5	0.2	0.11	3	1.5	<0.2
1280949	Soil	12	0.04	97	0.007	2	0.49	0.003	0.04	0.1	0.02	0.6	0.1	<0.05	4	0.6	<0.2
1280950	Soil	25	0.09	539	0.005	2	0.78	0.003	0.09	0.2	0.04	0.8	0.2	<0.05	5	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1280951	Soil	5.3	35.8	11.4	123	0.1	23.7	5.3	125	2.63	11.4	0.5	0.9	7	0.2	2.5	0.2	77	0.02	0.050	12
1280952	Soil	1.5	9.5	3.0	21	0.1	6.7	1.1	20	0.38	2.3	<0.5	0.1	5	<0.1	0.4	<0.1	20	0.03	0.029	5
1280953	Soil	5.9	47.0	9.2	193	0.2	36.4	7.8	160	1.86	4.2	1.5	0.5	16	0.6	1.8	0.2	30	0.26	0.056	5
1280954	Soil	2.4	17.7	6.0	45	0.1	13.2	1.9	29	0.69	1.9	<0.5	0.6	20	1.0	0.6	<0.1	18	0.19	0.037	4
1280955	Soil	2.7	27.7	5.9	58	1.0	22.8	3.1	151	1.01	3.2	3.3	0.4	55	0.6	1.2	0.1	32	0.97	0.075	4
1280956	Soil	2.0	29.0	6.8	36	0.4	9.2	1.3	28	0.63	2.7	2.2	0.2	8	1.4	0.7	0.1	27	0.02	0.062	13
1280957	Soil	3.1	43.8	30.5	52	0.3	24.2	8.3	953	1.85	10.3	2.6	1.5	87	0.5	1.5	0.4	57	0.78	0.153	14
1280958	Soil	3.1	36.8	13.3	61	0.2	19.2	4.1	120	1.33	4.7	2.8	1.1	18	0.2	1.0	0.1	38	0.10	0.069	8
1280959	Soil	1.4	12.8	4.8	14	0.3	6.7	1.7	579	0.42	1.2	<0.5	0.3	11	1.6	0.3	0.1	21	0.10	0.033	6
1280960	Soil	3.0	70.0	13.5	124	0.3	22.9	5.5	262	1.58	6.8	7.5	1.5	57	1.0	1.4	0.2	53	0.91	0.126	9
1280961	Soil	8.7	62.5	13.1	156	4.3	35.6	3.2	167	1.30	14.1	13.4	1.2	76	1.8	5.6	0.2	97	0.77	0.125	9
1280962	Soil	15.6	44.9	12.6	177	0.2	39.1	7.2	158	2.47	12.1	3.3	3.3	12	0.4	3.6	0.2	112	0.05	0.041	13
1280963	Soil	2.1	52.5	5.8	47	0.5	14.8	2.5	53	0.82	3.7	2.7	0.7	51	0.9	0.8	<0.1	37	1.13	0.064	7
1280964	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280965	Soil	1.7	58.3	10.6	127	1.0	27.9	4.5	168	1.53	13.6	6.1	0.5	92	1.5	1.8	0.2	52	2.73	0.118	7
1280966	Soil	3.8	55.5	10.0	187	1.0	33.3	6.3	129	1.99	10.0	7.4	2.2	72	1.0	2.0	0.2	72	1.28	0.177	11
1280967	Soil	4.1	9.4	5.6	42	0.6	9.4	1.4	25	0.93	7.4	1.3	0.3	7	0.1	2.0	0.1	76	0.03	0.021	7
1280968	Soil	1.6	22.6	6.9	87	0.5	21.8	3.5	220	0.82	4.3	5.5	0.4	63	0.7	1.3	<0.1	23	1.82	0.087	4
1280969	Soil	3.6	68.7	11.3	306	0.3	40.1	12.5	294	2.98	6.9	15.7	2.6	51	0.4	1.4	0.3	42	0.92	0.124	8
1280970	Soil	2.4	52.3	12.7	204	0.7	32.5	8.8	292	1.71	8.5	8.1	2.7	59	1.1	1.6	0.2	51	1.04	0.125	12
1281131	Soil	3.7	42.2	15.5	77	0.2	17.9	6.3	180	1.94	8.0	2.0	1.1	13	0.2	1.7	0.2	62	0.04	0.089	9
1281132	Soil	1.7	42.9	6.8	56	0.6	16.1	4.2	331	1.01	3.3	6.2	0.8	59	0.7	1.1	0.1	33	1.59	0.113	11
1281133	Soil	1.2	50.5	7.5	75	0.5	20.1	6.1	282	1.51	3.5	9.1	1.6	54	0.4	0.9	0.1	41	1.47	0.084	18
1281134	Soil	2.1	41.1	11.2	126	0.3	22.8	7.3	364	1.65	4.2	11.0	2.0	41	0.9	1.0	0.1	48	0.96	0.098	19
1281135	Soil	0.4	23.3	3.1	25	0.2	7.3	1.6	55	0.55	1.0	4.9	0.4	30	0.2	0.4	<0.1	16	0.82	0.050	7
1281136	Soil	2.3	107.2	14.4	124	1.1	33.8	8.6	339	2.04	8.9	16.3	1.8	78	0.9	2.3	0.2	39	2.26	0.145	18
1281137	Soil	1.0	14.6	5.4	18	0.1	5.0	1.1	15	0.39	1.9	1.7	<0.1	3	<0.1	0.5	<0.1	19	0.02	0.019	3
1281138	Soil	1.0	24.9	4.9	37	0.4	9.7	2.6	159	0.65	1.8	2.6	0.3	20	0.5	0.3	<0.1	16	0.27	0.092	6
1281139	Soil	8.0	197.8	12.2	195	1.1	46.2	6.2	177	1.74	10.7	12.1	2.0	425	0.9	2.4	0.2	61	10.17	0.358	14
1281140	Soil	8.3	62.6	14.0	130	0.2	29.5	10.3	309	2.81	12.3	8.2	2.5	24	0.7	2.4	0.2	61	0.37	0.118	23

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1280951	Soil	18	0.09	154	0.007	3	0.82	0.002	0.07	0.1	0.02	1.1	0.2	<0.05	6	1.0	<0.2
1280952	Soil	9	0.03	89	0.004	2	0.25	0.009	0.04	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2
1280953	Soil	10	0.12	453	0.004	3	0.53	0.011	0.07	<0.1	0.06	1.6	0.1	<0.05	2	1.1	<0.2
1280954	Soil	15	0.05	365	0.010	3	0.33	0.010	0.05	<0.1	0.07	1.1	<0.1	0.06	1	1.0	<0.2
1280955	Soil	10	0.25	1069	0.007	3	0.61	0.012	0.05	<0.1	0.31	1.3	<0.1	0.13	2	1.9	<0.2
1280956	Soil	12	0.03	310	0.006	<1	0.63	0.005	0.05	<0.1	0.05	0.3	0.1	<0.05	3	<0.5	<0.2
1280957	Soil	24	0.15	954	0.006	3	1.00	0.005	0.10	0.1	0.16	2.5	0.2	0.09	3	1.7	<0.2
1280958	Soil	15	0.07	324	0.007	5	0.59	0.009	0.09	<0.1	0.06	1.9	0.1	<0.05	3	<0.5	<0.2
1280959	Soil	12	0.04	364	0.007	1	0.50	0.010	0.04	0.1	0.03	0.8	<0.1	<0.05	2	<0.5	<0.2
1280960	Soil	26	0.19	423	0.012	4	0.86	0.006	0.10	0.1	0.12	2.9	0.1	0.07	3	0.8	<0.2
1280961	Soil	22	0.14	617	0.003	3	0.67	0.006	0.08	<0.1	1.91	3.0	0.4	0.09	2	2.7	<0.2
1280962	Soil	26	0.21	444	0.007	2	1.09	0.004	0.11	0.1	0.07	2.2	0.2	<0.05	4	0.7	<0.2
1280963	Soil	14	0.15	466	0.006	3	0.66	0.012	0.05	<0.1	0.17	1.3	0.2	0.06	2	1.0	<0.2
1280964	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1280965	Soil	15	0.25	860	0.004	4	0.68	0.005	0.05	<0.1	0.62	1.5	0.2	0.16	2	2.4	<0.2
1280966	Soil	23	0.49	910	0.007	5	1.13	0.006	0.14	0.1	0.58	2.8	0.2	0.06	4	2.4	<0.2
1280967	Soil	9	0.02	143	0.006	2	0.24	0.004	0.02	0.1	0.04	0.4	0.1	<0.05	3	<0.5	<0.2
1280968	Soil	16	0.10	1462	0.007	4	0.47	0.018	0.04	<0.1	0.29	1.2	0.1	0.10	1	1.2	<0.2
1280969	Soil	24	0.94	466	0.008	7	1.41	0.006	0.16	<0.1	0.18	2.4	<0.1	0.09	4	2.1	<0.2
1280970	Soil	21	0.43	704	0.004	5	0.99	0.007	0.09	0.2	0.30	2.7	0.1	0.06	3	1.9	<0.2
1281131	Soil	20	0.20	159	0.009	4	0.71	0.008	0.07	<0.1	0.06	1.2	0.1	0.06	4	0.7	<0.2
1281132	Soil	17	0.30	520	0.008	4	0.79	0.011	0.06	<0.1	0.20	1.9	0.1	0.09	3	1.4	<0.2
1281133	Soil	21	0.71	510	0.008	4	1.21	0.008	0.09	<0.1	0.24	2.8	0.1	0.08	4	1.5	<0.2
1281134	Soil	28	0.76	462	0.012	4	1.30	0.007	0.12	<0.1	0.15	3.3	0.1	0.06	4	1.3	<0.2
1281135	Soil	8	0.21	192	0.008	2	0.59	0.023	0.05	<0.1	0.09	1.0	<0.1	0.05	2	0.8	<0.2
1281136	Soil	23	0.55	636	0.004	4	1.14	0.005	0.11	<0.1	0.50	3.1	0.2	0.10	3	2.2	<0.2
1281137	Soil	7	0.02	31	0.006	<1	0.15	0.010	0.03	<0.1	0.02	0.2	<0.1	<0.05	1	<0.5	<0.2
1281138	Soil	12	0.16	145	0.006	1	0.55	0.021	0.04	<0.1	0.10	0.6	<0.1	0.05	2	0.9	<0.2
1281139	Soil	18	2.96	380	0.003	6	0.79	0.011	0.14	<0.1	0.14	2.4	0.1	0.05	2	4.6	0.2
1281140	Soil	27	0.94	232	0.006	3	1.60	0.004	0.11	<0.1	0.14	2.6	0.2	0.08	6	1.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281141	Soil	5.5	82.7	13.8	135	1.9	27.5	8.8	143	2.46	8.7	10.8	3.8	28	0.8	1.6	0.2	75	0.23	0.119	28
1281142	Soil	1.5	15.5	5.3	36	<0.1	5.4	2.3	107	0.80	2.6	2.0	0.5	8	0.2	0.4	0.1	23	0.08	0.058	13
1281143	Soil	2.5	40.9	13.3	78	0.2	19.4	11.5	1105	2.69	7.4	8.2	1.3	39	0.5	1.0	0.1	45	1.00	0.115	16
1281144	Soil	1.8	42.9	8.7	133	0.5	29.8	6.4	172	1.80	5.0	7.2	2.1	54	0.8	0.9	0.1	44	1.16	0.132	17
1281145	Soil	1.2	34.1	5.0	62	0.5	15.5	4.2	125	1.24	3.6	8.6	1.4	51	0.3	0.7	<0.1	34	1.47	0.083	12
1281146	Soil	1.8	16.2	5.1	43	0.2	6.6	3.4	104	0.92	3.1	1.6	0.5	8	0.2	0.6	<0.1	23	0.06	0.053	5
1281147	Soil	1.1	47.6	7.2	100	0.5	20.6	5.0	117	1.55	3.8	7.0	1.8	61	0.5	0.7	0.1	39	1.54	0.111	15
1281148	Soil	2.8	33.9	9.9	89	0.3	17.2	5.2	187	1.43	4.8	3.0	0.4	57	1.0	1.0	0.1	39	1.38	0.129	8
1281149	Soil	2.0	32.4	5.9	215	0.3	29.0	4.3	250	1.27	8.0	4.6	0.6	63	1.5	1.5	<0.1	29	1.96	0.085	8
1281150	Soil	8.8	62.9	19.5	138	0.4	45.4	12.9	375	3.18	12.7	6.2	2.2	51	0.3	2.3	0.3	55	0.24	0.077	17
1281531	Soil	2.7	135.2	14.5	141	2.6	58.6	8.1	418	2.06	7.8	25.1	1.5	98	2.5	2.4	0.3	55	0.93	0.110	8
1281532	Soil	7.3	90.4	28.1	242	0.5	51.1	16.3	388	3.81	22.9	12.8	1.5	39	1.4	5.2	0.4	74	0.18	0.098	8
1281533	Soil	0.6	63.7	7.6	110	0.6	25.5	5.0	180	1.36	3.7	8.6	1.1	87	0.7	1.1	0.1	34	2.21	0.081	9
1281534	Soil	0.6	38.5	4.0	34	0.3	10.2	3.6	269	0.72	1.7	4.4	0.3	117	0.8	0.8	<0.1	13	2.96	0.088	5
1281535	Soil	4.1	137.5	12.0	257	1.9	57.9	12.3	354	2.88	12.3	22.1	1.7	142	1.2	3.0	0.2	49	3.00	0.166	13
1281536	Soil	7.2	78.3	21.7	145	0.3	27.8	5.4	90	2.52	18.7	18.7	1.2	20	0.3	3.8	0.4	91	0.05	0.094	11
1281537	Soil	1.2	29.7	10.2	79	1.4	17.1	3.9	61	1.65	3.9	8.1	1.1	18	0.2	0.5	0.2	41	0.12	0.105	10
1281538	Soil	0.8	39.3	7.5	56	0.8	14.9	2.5	42	1.04	1.8	8.0	0.8	24	0.7	0.7	0.1	20	0.31	0.120	7
1281539	Soil	5.2	98.9	15.5	249	1.5	53.7	9.4	202	2.25	15.7	19.1	2.6	96	1.8	4.5	0.2	75	1.26	0.164	12
1281540	Soil	3.2	82.5	15.7	173	0.8	37.4	14.1	562	2.54	10.1	12.7	3.3	57	1.2	1.9	0.3	69	1.09	0.166	20
1281541	Soil	3.0	76.1	11.5	167	0.8	31.3	10.9	419	2.09	8.2	8.3	2.7	64	1.8	1.7	0.2	60	1.24	0.141	16
1281542	Soil	11.9	124.7	21.9	279	1.5	41.9	14.6	294	3.84	19.9	14.3	5.6	45	3.0	6.0	0.3	74	0.58	0.153	26
1281543	Soil	6.5	77.5	15.2	186	0.7	37.1	11.1	385	3.27	14.0	8.9	3.2	57	1.8	2.7	0.2	57	1.00	0.166	22
1281544	Soil	2.6	39.5	7.0	91	0.5	15.8	5.3	117	1.35	5.7	6.0	1.0	21	0.7	1.3	0.1	39	0.19	0.100	10
1281545	Soil	4.2	78.6	12.3	144	1.3	29.2	10.6	555	2.03	8.4	16.5	2.2	53	2.0	2.1	0.3	68	0.67	0.138	18
1281546	Soil	3.2	89.3	11.8	163	0.8	31.5	9.2	349	2.02	8.9	12.1	1.8	75	2.0	2.1	0.2	56	1.35	0.138	15
1281547	Soil	0.4	66.8	10.2	95	0.7	22.7	5.1	183	1.11	5.0	9.2	1.1	82	0.9	1.2	0.2	41	1.87	0.097	10
1281548	Soil	1.4	64.6	10.4	118	0.6	24.7	5.9	291	1.54	6.3	7.2	1.2	80	1.0	1.4	0.2	43	1.80	0.105	11
1281549	Soil	2.6	81.0	12.3	179	0.9	34.0	9.0	353	2.12	8.8	10.6	3.2	69	1.6	2.1	0.2	63	1.03	0.134	13
1281550	Soil	2.0	65.1	9.1	155	0.8	28.8	6.0	191	1.56	7.9	7.6	1.5	82	1.1	1.8	0.2	50	1.63	0.128	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281141	Soil	28	0.92	383	0.004	3	1.60	0.003	0.13	<0.1	0.74	3.9	0.3	0.07	5	2.3	<0.2
1281142	Soil	10	0.15	153	0.004	<1	0.62	0.007	0.06	<0.1	0.03	0.6	<0.1	<0.05	5	<0.5	<0.2
1281143	Soil	23	0.49	209	0.006	3	1.14	0.009	0.07	<0.1	0.07	2.1	<0.1	<0.05	4	1.4	<0.2
1281144	Soil	36	0.79	286	0.007	4	1.35	0.007	0.11	<0.1	0.15	2.7	0.1	0.05	4	1.4	<0.2
1281145	Soil	16	0.58	280	0.008	3	1.11	0.012	0.09	<0.1	0.10	2.3	<0.1	0.08	3	0.8	<0.2
1281146	Soil	9	0.14	66	0.006	<1	0.54	0.015	0.04	<0.1	0.03	0.7	<0.1	<0.05	2	0.5	<0.2
1281147	Soil	20	0.77	260	0.008	4	1.33	0.009	0.11	<0.1	0.19	2.4	0.1	0.07	4	1.3	<0.2
1281148	Soil	22	0.21	356	0.011	3	0.69	0.015	0.08	<0.1	0.05	0.9	0.1	0.07	3	1.3	<0.2
1281149	Soil	12	0.27	261	0.009	2	0.68	0.018	0.06	<0.1	0.22	1.3	<0.1	0.08	2	1.1	<0.2
1281150	Soil	22	0.41	1044	0.005	1	1.24	0.005	0.13	<0.1	0.13	2.5	0.2	0.08	4	1.9	<0.2
1281531	Soil	17	0.25	3094	0.002	4	1.06	0.007	0.09	<0.1	1.34	5.3	0.2	0.13	2	5.7	<0.2
1281532	Soil	18	0.11	220	0.003	3	0.81	0.003	0.09	<0.1	0.16	2.9	0.3	<0.05	3	2.8	<0.2
1281533	Soil	14	0.36	488	0.005	4	0.90	0.006	0.07	<0.1	0.32	2.1	0.2	0.11	2	2.1	<0.2
1281534	Soil	7	0.21	253	0.006	6	0.49	0.014	0.03	<0.1	0.17	0.7	<0.1	0.15	1	3.0	<0.2
1281535	Soil	17	0.79	554	0.003	4	1.01	0.005	0.14	<0.1	0.53	4.1	0.2	0.09	3	3.5	<0.2
1281536	Soil	15	0.06	160	0.009	2	0.57	0.003	0.07	0.1	0.05	1.2	0.2	<0.05	5	2.1	<0.2
1281537	Soil	20	0.40	194	0.005	3	1.18	0.005	0.12	<0.1	0.28	1.3	0.2	<0.05	4	1.4	<0.2
1281538	Soil	13	0.19	219	0.005	2	0.71	0.008	0.07	<0.1	0.26	1.7	0.2	0.10	2	2.4	<0.2
1281539	Soil	21	0.34	991	0.005	4	0.95	0.005	0.10	<0.1	0.52	3.6	0.3	0.07	3	3.3	<0.2
1281540	Soil	29	1.10	354	0.005	5	1.59	0.004	0.13	<0.1	0.35	3.9	0.2	0.07	5	1.8	<0.2
1281541	Soil	23	1.02	332	0.006	4	1.37	0.005	0.12	<0.1	0.30	3.4	0.2	<0.05	5	1.8	<0.2
1281542	Soil	26	1.08	243	0.005	5	1.62	0.003	0.17	<0.1	0.44	3.5	0.3	<0.05	5	3.8	<0.2
1281543	Soil	21	1.06	397	0.005	5	1.38	0.005	0.16	<0.1	0.32	4.1	0.2	0.07	4	2.7	<0.2
1281544	Soil	16	0.27	296	0.003	2	0.73	0.006	0.11	<0.1	0.24	1.3	0.2	<0.05	3	1.2	<0.2
1281545	Soil	23	0.83	393	0.006	6	1.38	0.007	0.13	<0.1	0.44	3.5	0.3	0.10	4	2.0	<0.2
1281546	Soil	18	0.62	578	0.005	6	1.17	0.006	0.13	<0.1	0.33	2.9	0.2	0.12	3	2.0	<0.2
1281547	Soil	14	0.39	446	0.005	6	0.84	0.009	0.09	<0.1	0.41	2.3	0.2	0.14	2	2.0	<0.2
1281548	Soil	16	0.53	405	0.005	6	0.95	0.006	0.10	<0.1	0.35	2.2	0.1	0.16	3	2.0	<0.2
1281549	Soil	22	0.59	803	0.005	5	1.21	0.005	0.14	<0.1	0.52	4.0	0.2	0.07	3	1.9	<0.2
1281550	Soil	17	0.54	502	0.005	6	0.95	0.006	0.12	<0.1	0.37	2.5	0.2	0.13	3	2.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281551	Soil		6.1	82.6	18.0	224	1.4	42.2	11.5	410	3.13	20.3	9.8	2.5	45	2.1	4.1	0.3	77	0.28	0.135	13
1281552	Soil		2.7	39.8	11.8	108	0.7	24.9	7.9	557	1.70	9.4	6.4	2.2	38	1.4	1.5	0.2	49	0.31	0.092	11
1281553	Soil		3.3	41.0	12.0	125	0.6	21.9	10.9	390	1.97	9.1	8.6	1.8	40	1.2	1.7	0.2	48	0.61	0.100	9
1281554	Soil		2.6	51.9	10.1	142	0.6	25.2	6.4	279	1.95	8.2	5.8	2.0	55	0.9	1.8	0.2	54	0.91	0.124	11
1281555	Soil		7.0	63.8	18.2	202	1.1	41.0	10.6	528	2.67	20.3	8.4	2.8	61	2.4	4.4	0.3	81	0.39	0.122	13
1281556	Soil		7.1	39.6	15.7	137	0.9	25.1	13.2	1028	2.79	17.8	7.3	2.5	42	1.0	3.1	0.3	73	0.32	0.108	12
1281557	Soil		4.2	60.9	15.4	173	0.8	34.1	9.7	429	2.62	14.4	10.6	2.8	44	1.0	2.5	0.2	67	0.47	0.124	14
1281558	Soil		5.5	66.4	13.6	176	0.8	38.4	11.9	2071	2.93	21.1	9.0	2.4	57	1.8	3.5	0.2	61	0.88	0.135	12
1281559	Soil		5.0	59.1	9.5	218	0.7	39.2	8.6	413	1.65	8.6	7.7	1.2	50	2.1	2.4	0.2	78	0.72	0.115	11
1281560	Soil		4.6	61.5	16.3	198	1.1	35.8	9.4	349	3.22	22.6	8.4	2.1	74	1.4	3.9	0.3	83	1.01	0.123	10
1281561	Soil		3.4	63.7	13.7	126	1.2	33.4	7.7	359	2.07	13.6	8.4	0.9	83	1.4	2.6	0.2	71	1.54	0.131	10
1281562	Soil		2.5	30.1	9.8	104	0.8	20.0	6.4	891	1.20	6.0	5.9	1.0	63	0.8	1.4	0.1	46	0.92	0.115	8
1281563	Soil		5.0	74.3	15.1	185	1.0	36.6	8.6	301	2.65	13.3	11.2	2.6	79	2.0	3.5	0.2	78	1.35	0.151	14
1281564	Soil		4.5	69.9	16.1	196	1.0	41.0	7.3	185	2.43	18.2	7.3	2.8	65	2.3	3.9	0.2	78	0.63	0.127	12
1281565	Soil		0.6	46.8	5.2	58	0.4	19.1	2.5	136	0.85	3.6	3.6	0.6	96	1.1	1.2	0.1	20	2.45	0.098	9
1281566	Soil		1.4	100.1	9.2	112	0.6	34.2	7.0	330	1.61	6.7	9.5	1.3	99	1.5	1.8	0.2	41	2.17	0.120	12
1281567	Soil		9.1	99.3	22.0	391	1.5	74.5	15.3	452	3.55	31.2	3.8	3.6	82	4.7	6.4	0.3	75	0.73	0.145	12
1281568	Soil		3.3	70.2	14.2	213	0.9	33.2	9.0	391	2.12	16.7	4.8	1.3	92	1.2	3.3	0.2	59	1.66	0.113	10
1281569	Soil		2.8	91.8	15.7	247	1.0	55.4	9.2	216	1.97	16.6	6.4	2.1	100	3.0	4.2	0.3	65	1.99	0.104	10
1281570	Soil		6.6	110.3	14.0	337	1.5	72.3	13.7	381	3.10	20.7	14.5	3.3	75	3.0	4.5	0.2	77	1.09	0.137	13
1281571	Soil		2.8	92.6	12.4	203	1.0	44.2	8.8	216	2.06	12.2	10.5	1.8	116	2.1	2.9	0.2	55	2.32	0.114	11
1281572	Soil		7.5	79.3	13.9	278	1.5	57.6	8.5	304	2.97	22.8	6.2	3.0	110	3.6	4.5	0.2	91	1.55	0.190	20
1281573	Soil		5.6	77.4	14.4	194	1.3	43.2	9.6	259	2.75	15.9	12.3	2.7	74	2.0	3.4	0.2	57	1.09	0.130	13
1281574	Soil		5.6	63.1	17.1	184	0.7	39.9	13.8	488	3.16	20.8	4.8	4.3	51	1.3	2.9	0.3	55	0.86	0.140	18
1281575	Soil		5.6	28.9	16.9	99	0.5	16.9	16.7	765	2.44	13.9	4.3	2.3	39	0.7	1.4	0.2	47	0.63	0.110	11
1281576	Soil		3.4	53.3	14.1	134	0.4	28.3	12.1	559	2.42	11.7	4.1	2.9	46	1.2	1.8	0.2	45	0.81	0.114	16
1281577	Soil		4.8	31.8	17.2	84	0.4	69.5	7.0	235	3.18	54.9	3.1	0.2	21	0.2	5.3	0.3	69	0.02	0.051	8
1281578	Soil		4.1	72.2	22.6	69	1.4	64.4	18.7	781	5.36	32.7	6.4	1.8	36	0.4	4.2	0.4	84	0.19	0.098	5
1281579	Soil		6.8	84.9	20.8	119	1.8	47.1	11.5	259	3.73	19.9	3.7	0.4	35	0.3	4.7	0.4	72	0.02	0.113	2
1281580	Soil		12.0	117.4	29.5	181	4.1	61.2	12.0	339	5.32	39.3	9.2	0.9	249	1.3	11.4	0.4	119	0.09	0.202	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281551	Soil	20	0.28	918	0.004	10	0.94	0.004	0.12	0.1	0.50	3.4	0.3	<0.05	3	2.4	<0.2
1281552	Soil	15	0.26	929	0.004	3	0.84	0.008	0.10	<0.1	0.41	2.5	0.2	0.06	3	1.3	<0.2
1281553	Soil	14	0.36	637	0.004	4	0.85	0.010	0.12	<0.1	0.27	2.5	0.1	0.06	3	1.4	<0.2
1281554	Soil	16	0.50	854	0.004	5	1.12	0.006	0.14	<0.1	0.30	2.8	0.2	0.06	3	1.3	<0.2
1281555	Soil	21	0.31	1779	0.004	4	0.95	0.007	0.11	0.1	0.58	3.3	0.3	0.05	3	2.6	<0.2
1281556	Soil	19	0.34	855	0.004	4	0.97	0.006	0.10	<0.1	0.48	2.5	0.2	<0.05	3	1.8	<0.2
1281557	Soil	21	0.48	1016	0.004	4	1.16	0.005	0.13	<0.1	0.42	3.6	0.2	<0.05	4	1.8	<0.2
1281558	Soil	18	0.51	792	0.005	4	1.11	0.005	0.12	<0.1	0.42	3.1	0.2	0.09	3	2.8	<0.2
1281559	Soil	15	0.28	564	0.007	4	0.83	0.014	0.10	<0.1	0.35	2.3	0.2	0.07	3	2.2	<0.2
1281560	Soil	21	0.28	1080	0.004	4	0.95	0.006	0.08	<0.1	0.73	3.1	0.3	0.10	3	7.1	<0.2
1281561	Soil	16	0.23	932	0.005	4	0.82	0.006	0.07	<0.1	0.65	2.2	0.2	0.13	2	4.0	<0.2
1281562	Soil	14	0.25	462	0.006	3	0.71	0.010	0.07	<0.1	0.44	1.9	0.1	0.09	2	2.3	<0.2
1281563	Soil	21	0.61	617	0.006	5	0.99	0.005	0.12	<0.1	0.56	3.3	0.2	0.12	3	4.2	<0.2
1281564	Soil	21	0.30	1903	0.004	4	0.92	0.006	0.08	0.1	0.65	3.3	0.2	0.05	3	2.8	<0.2
1281565	Soil	11	0.18	377	0.003	5	0.53	0.012	0.06	<0.1	0.26	1.8	<0.1	0.16	1	1.6	<0.2
1281566	Soil	15	0.51	563	0.004	6	0.91	0.006	0.09	<0.1	0.36	2.6	0.2	0.18	2	1.8	<0.2
1281567	Soil	23	0.40	1417	0.006	2	0.94	0.009	0.12	0.2	0.71	4.2	0.4	0.09	3	6.2	<0.2
1281568	Soil	18	0.26	1227	0.004	5	0.87	0.009	0.07	0.1	0.51	2.5	0.2	0.11	3	3.4	<0.2
1281569	Soil	19	0.32	1290	0.004	5	0.91	0.007	0.09	0.1	0.57	3.2	0.2	0.15	2	4.1	<0.2
1281570	Soil	22	0.39	1015	0.005	4	0.92	0.004	0.11	0.1	0.60	4.6	0.3	0.06	3	2.6	<0.2
1281571	Soil	18	0.41	1160	0.005	5	0.82	0.007	0.10	<0.1	0.46	3.3	0.2	0.11	2	2.0	<0.2
1281572	Soil	23	0.45	758	0.004	4	0.93	0.005	0.10	0.1	0.66	3.9	0.2	0.06	2	2.5	<0.2
1281573	Soil	19	0.35	864	0.004	3	0.89	0.005	0.09	<0.1	0.60	3.5	0.3	0.08	3	3.0	<0.2
1281574	Soil	20	0.46	703	0.005	3	1.06	0.008	0.13	0.2	0.31	4.2	0.2	<0.05	3	1.9	<0.2
1281575	Soil	15	0.31	394	0.004	3	0.92	0.011	0.09	0.2	0.24	2.5	0.1	0.08	3	1.3	<0.2
1281576	Soil	18	0.44	518	0.004	3	1.08	0.007	0.12	0.2	0.21	3.4	0.1	<0.05	3	1.8	<0.2
1281577	Soil	15	0.04	112	0.007	1	0.52	0.004	0.04	0.2	0.07	0.8	0.3	<0.05	4	3.2	<0.2
1281578	Soil	23	0.08	1045	0.002	2	0.51	0.002	0.07	<0.1	0.15	7.6	0.2	0.07	2	3.9	<0.2
1281579	Soil	16	0.03	457	0.002	2	0.46	0.003	0.09	<0.1	0.14	3.7	0.2	0.11	2	4.8	<0.2
1281580	Soil	22	0.04	799	0.006	2	0.52	0.005	0.15	<0.1	0.12	5.4	0.6	0.26	2	8.1	0.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281581	Soil		10.5	116.9	30.2	263	3.3	49.2	12.7	314	4.83	39.2	5.1	1.6	148	1.2	8.3	0.4	95	0.04	0.125	2
1281582	Soil		6.7	66.9	26.8	205	0.7	40.4	11.3	215	3.58	19.3	2.0	1.1	25	0.4	4.4	0.4	61	0.03	0.110	3
1281583	Soil		5.2	74.9	34.0	364	0.7	70.5	16.4	230	4.26	19.3	2.3	1.6	25	0.3	5.5	0.4	37	0.01	0.076	2
1281584	Soil		5.1	100.6	68.7	398	1.3	82.1	35.4	1149	6.56	20.5	4.5	2.6	27	2.1	4.8	0.6	29	0.06	0.103	4
1281585	Soil		6.9	84.6	31.2	217	2.1	50.4	15.8	651	3.48	12.0	1.9	0.5	78	1.8	3.5	0.4	49	0.27	0.104	4
1281586	Soil		58.6	213.7	48.0	1066	18.6	175.6	8.9	1405	6.47	96.2	3.7	0.7	672	33.4	46.1	0.3	369	2.69	0.813	10
1281587	Soil		47.5	267.8	38.8	439	12.0	99.6	3.4	191	4.59	70.7	1.3	1.3	716	10.9	38.0	0.3	480	1.13	1.388	15
1281588	Soil		34.2	110.0	18.7	106	5.2	37.0	0.9	65	2.09	38.7	1.7	1.8	292	3.2	14.0	0.2	202	0.46	0.550	15
1281589	Soil		128.8	113.2	39.1	358	8.9	54.4	2.0	60	8.37	278.6	3.1	4.0	449	6.5	66.5	0.4	473	0.49	1.701	14
1281590	Soil		55.1	77.9	33.0	115	4.7	27.1	2.1	49	2.33	26.6	<0.5	0.5	170	1.3	14.0	0.3	221	0.05	0.197	16
1281591	Soil		26.6	86.0	36.2	195	3.3	39.9	12.1	769	3.59	49.4	8.5	1.0	190	3.7	16.9	0.3	254	0.18	0.418	8
1281592	Soil		15.5	29.3	32.6	103	1.4	22.8	2.9	58	1.58	17.1	1.2	0.7	61	0.3	7.8	0.3	181	0.02	0.064	9
1281593	Soil		6.8	22.8	8.4	79	1.1	15.2	3.2	48	1.21	9.3	1.9	0.2	15	0.2	2.9	0.1	87	0.01	0.050	7
1281594	Soil		18.6	69.8	26.1	132	2.7	23.9	3.1	67	2.36	16.4	1.8	0.7	126	1.5	8.4	0.2	127	0.09	0.200	8
1281595	Soil		16.5	66.8	24.1	108	2.8	20.6	2.4	63	1.85	14.4	2.5	0.7	120	3.1	7.3	0.2	109	0.10	0.182	8
1281596	Soil		15.0	42.0	24.2	129	2.1	18.5	2.3	61	2.12	23.6	6.4	0.6	90	0.9	5.9	0.2	135	0.07	0.247	7
1281597	Soil		14.5	40.1	25.8	123	2.5	19.3	2.0	42	1.62	15.7	3.4	0.5	102	1.1	5.9	0.2	117	0.04	0.169	6
1281598	Soil		3.9	40.7	13.0	103	0.2	22.7	6.1	177	2.48	8.1	1.5	0.2	14	5.2	1.9	0.2	43	0.03	0.097	8
1281599	Soil		2.5	22.1	9.6	52	0.2	11.9	3.5	147	1.26	3.4	<0.5	<0.1	7	0.8	1.0	0.2	25	0.02	0.055	3
1281600	Soil		9.2	114.6	28.0	241	0.3	75.6	19.9	900	5.66	15.0	3.8	1.2	20	0.9	4.0	0.6	50	0.03	0.091	7
1281601	Soil		3.6	30.8	12.3	72	0.1	22.2	13.4	954	2.10	4.1	1.5	1.2	10	0.1	1.0	0.1	20	0.05	0.047	5
1281602	Soil		1.3	18.9	6.8	33	0.7	6.4	2.0	50	0.90	2.7	4.1	0.2	12	0.2	0.4	0.1	35	0.04	0.050	8
1281603	Soil		3.4	46.8	9.4	136	<0.1	29.8	7.6	113	2.31	10.2	0.8	0.6	9	0.2	1.3	0.2	48	0.02	0.052	12
1281604	Soil		10.9	57.7	10.3	208	0.7	46.9	8.5	242	2.38	8.6	5.5	2.8	43	0.9	2.9	0.2	89	0.49	0.080	15
1281605	Soil		6.2	70.3	19.6	182	0.4	49.6	13.6	401	4.29	12.2	5.5	2.6	39	0.5	2.0	0.3	54	0.07	0.090	14
1281606	Soil		3.3	34.7	11.7	79	0.1	14.4	3.2	61	1.29	7.4	<0.5	0.6	16	0.2	1.2	0.2	58	0.05	0.040	15
1281607	Soil		3.5	34.6	11.5	77	0.2	13.8	3.3	67	1.29	7.3	1.3	0.5	17	0.2	1.1	0.2	62	0.05	0.043	16
1281608	Soil		5.2	30.3	23.3	100	0.3	24.8	5.3	143	3.37	17.4	2.2	0.6	36	0.2	2.3	0.4	121	0.17	0.076	14
1281609	Soil		0.8	75.3	5.7	41	0.6	16.2	3.7	408	0.92	3.6	3.6	0.2	77	0.5	1.2	0.1	23	2.52	0.129	8
1281610	Soil		1.7	52.0	7.8	81	0.6	24.2	4.8	215	1.38	5.9	9.1	0.6	62	0.5	1.3	0.1	52	1.48	0.151	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281581	Soil	20	0.05	655	0.002	3	0.49	0.006	0.20	<0.1	0.16	5.5	0.5	0.33	2	7.8	0.3
1281582	Soil	13	0.02	407	0.002	3	0.47	0.003	0.11	<0.1	0.12	2.7	0.3	0.10	2	2.9	<0.2
1281583	Soil	13	0.02	228	<0.001	2	0.37	0.003	0.09	<0.1	0.08	3.3	0.3	0.08	1	2.0	<0.2
1281584	Soil	8	0.06	680	0.005	3	0.44	0.003	0.10	<0.1	0.18	6.4	0.5	<0.05	1	3.0	<0.2
1281585	Soil	10	0.11	1657	0.003	6	0.42	0.007	0.11	<0.1	0.44	3.8	0.4	0.13	1	3.7	<0.2
1281586	Soil	70	1.26	97	0.006	13	0.83	0.010	0.30	0.4	1.76	2.7	3.0	0.93	3	32.8	0.7
1281587	Soil	93	0.05	307	0.015	19	1.23	0.009	0.24	0.5	9.48	4.0	2.2	0.56	5	64.4	0.8
1281588	Soil	44	0.03	527	0.004	18	0.53	0.002	0.16	0.3	0.88	2.2	1.0	0.24	3	19.3	0.5
1281589	Soil	94	0.05	178	0.008	8	0.71	0.006	0.25	0.7	2.85	10.1	4.0	0.60	6	86.8	1.2
1281590	Soil	31	0.03	683	0.003	3	0.46	0.006	0.15	0.4	0.66	1.0	3.0	0.40	5	21.9	0.5
1281591	Soil	37	0.05	359	0.005	7	0.60	0.004	0.17	0.3	1.34	2.9	1.5	0.33	3	15.1	0.3
1281592	Soil	15	0.02	510	0.004	4	0.35	0.004	0.07	0.2	0.09	1.0	0.7	0.08	4	6.3	0.2
1281593	Soil	10	0.02	495	0.004	3	0.37	0.006	0.05	<0.1	0.09	0.4	0.2	0.05	2	2.7	<0.2
1281594	Soil	24	0.02	385	0.002	12	0.38	0.004	0.16	0.2	0.56	1.4	1.1	0.41	2	10.6	0.3
1281595	Soil	21	0.02	517	0.002	13	0.34	0.003	0.14	0.2	0.83	2.0	1.0	0.31	2	12.0	0.2
1281596	Soil	22	0.02	817	0.006	6	0.57	0.003	0.10	0.1	0.65	0.8	0.9	0.20	2	6.5	0.2
1281597	Soil	20	0.02	914	0.003	6	0.50	0.005	0.10	0.1	0.94	0.4	1.0	0.21	2	5.7	0.3
1281598	Soil	13	0.03	411	0.007	3	0.43	0.006	0.09	<0.1	0.04	0.7	0.1	0.07	2	0.8	<0.2
1281599	Soil	5	0.03	318	0.004	2	0.38	0.011	0.06	<0.1	0.04	0.4	0.1	<0.05	2	0.7	<0.2
1281600	Soil	11	0.07	2070	0.003	3	0.82	0.003	0.12	<0.1	0.10	4.8	0.2	0.08	2	2.0	0.2
1281601	Soil	9	0.11	415	0.006	2	0.74	0.015	0.10	<0.1	0.06	1.4	0.1	<0.05	2	0.6	<0.2
1281602	Soil	13	0.10	302	0.004	2	0.83	0.012	0.07	<0.1	0.09	0.6	0.1	<0.05	4	<0.5	<0.2
1281603	Soil	15	0.11	296	0.007	4	0.74	0.004	0.13	<0.1	0.04	1.1	0.2	0.07	6	1.1	<0.2
1281604	Soil	23	0.57	755	0.009	4	1.29	0.007	0.16	0.1	0.23	3.2	0.2	0.11	4	2.5	<0.2
1281605	Soil	25	0.40	445	0.007	4	1.44	0.006	0.15	<0.1	0.06	2.8	0.2	0.13	5	1.5	<0.2
1281606	Soil	13	0.06	115	0.008	1	0.58	0.005	0.06	<0.1	0.04	0.8	0.1	0.06	6	0.7	<0.2
1281607	Soil	13	0.06	121	0.010	2	0.59	0.005	0.07	<0.1	0.02	0.9	0.1	0.05	6	1.0	<0.2
1281608	Soil	24	0.14	562	0.012	2	1.12	0.004	0.10	0.1	0.03	1.4	0.2	0.07	7	1.4	<0.2
1281609	Soil	12	0.16	606	0.008	4	0.86	0.021	0.05	<0.1	0.49	0.9	0.1	0.17	2	2.3	<0.2
1281610	Soil	17	0.27	544	0.007	3	1.10	0.013	0.08	<0.1	0.39	1.4	0.1	0.14	3	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281611	Soil	0.5	13.6	3.0	21	0.2	5.5	1.6	96	0.51	1.7	1.7	0.2	71	0.5	0.4	<0.1	14	1.88	0.071	4
1281612	Soil	1.3	29.9	4.3	43	0.5	14.0	3.1	219	0.84	3.0	4.1	0.6	85	0.3	0.9	<0.1	23	1.88	0.108	7
1281613	Soil	0.8	49.1	4.0	40	0.4	12.0	2.8	207	0.78	1.7	4.7	0.4	71	0.3	0.7	<0.1	20	1.49	0.097	6
1281614	Soil	1.1	60.0	4.7	44	0.4	19.0	3.1	98	0.91	2.0	6.4	0.4	77	0.4	1.0	0.1	22	1.81	0.090	6
1281615	Soil	2.5	23.8	10.6	79	0.1	11.3	3.5	101	1.41	6.9	1.6	0.6	17	0.4	0.9	0.2	65	0.10	0.051	15
1281616	Soil	0.9	60.4	8.1	63	0.7	20.8	4.2	404	1.23	5.5	5.2	0.6	84	0.9	0.9	0.2	34	2.15	0.096	11
1281617	Soil	2.8	19.8	12.8	81	<0.1	10.2	4.6	160	1.89	16.9	1.9	0.9	20	0.4	1.2	0.4	70	0.18	0.032	16
1281618	Soil	1.1	42.7	6.1	46	0.3	15.3	4.0	272	1.03	5.4	4.5	0.3	77	0.3	1.1	0.3	19	2.44	0.089	7
1281619	Soil	2.6	18.0	15.2	73	0.6	12.4	5.5	242	3.21	17.3	4.9	1.1	6	0.2	1.4	0.5	73	0.03	0.111	12
1281620	Soil	1.4	37.9	12.9	96	0.3	24.4	10.3	517	2.08	9.8	3.6	1.6	66	0.6	1.3	0.2	33	1.63	0.086	14
1281621	Soil	2.9	47.1	10.2	126	0.7	22.2	7.5	197	1.76	7.6	6.7	2.8	56	1.0	1.6	0.2	50	1.04	0.090	16
1281622	Soil	3.3	40.9	12.4	112	0.5	18.2	11.5	844	2.19	12.0	4.7	2.5	55	0.7	1.2	0.2	48	1.03	0.106	14
1281623	Soil	0.9	10.9	4.8	26	<0.1	4.8	2.7	96	1.02	3.9	2.1	1.2	5	0.1	0.5	<0.1	27	0.04	0.029	7
1281624	Soil	0.8	41.4	6.0	38	0.2	9.4	3.9	303	0.73	3.1	5.3	0.7	145	0.3	0.9	0.2	20	2.50	0.095	12
1281625	Soil	3.0	61.3	10.1	96	0.6	22.4	10.0	503	2.07	8.6	5.8	2.0	73	0.7	1.4	0.1	42	1.37	0.104	15
1281626	Soil	2.7	34.4	10.5	103	0.4	19.6	8.9	447	2.23	9.7	4.7	2.7	59	0.5	1.3	0.2	43	1.05	0.109	16
1281627	Soil	3.5	46.9	13.5	101	0.4	23.4	11.1	576	2.50	11.9	5.0	2.7	51	0.6	1.5	0.2	39	0.97	0.110	17
1281628	Soil	3.1	43.7	13.2	131	0.4	29.8	11.7	673	2.48	12.8	4.8	2.5	61	0.7	1.8	0.3	40	1.21	0.097	16
1281629	Soil	1.7	33.2	9.8	122	0.3	23.4	8.4	437	1.97	9.5	3.1	1.8	72	1.1	1.2	0.2	38	1.50	0.081	12
1281630	Soil	6.0	37.4	18.7	124	0.2	23.4	4.3	135	2.42	14.5	2.7	0.3	15	0.2	2.7	0.3	101	0.03	0.092	11
1281631	Soil	1.7	8.2	7.0	30	<0.1	4.7	1.3	28	0.60	3.6	0.8	0.2	11	<0.1	0.5	0.2	37	0.03	0.060	13
1281632	Soil	3.4	25.7	12.9	82	<0.1	13.3	3.6	120	1.73	9.2	2.2	0.2	12	0.2	1.3	0.3	82	0.03	0.062	14
1281633	Soil	2.0	14.5	6.0	46	<0.1	7.4	1.6	32	0.69	4.2	1.6	0.1	8	0.1	0.8	0.1	44	0.02	0.045	9
1281634	Soil	1.9	16.1	7.1	27	0.2	5.3	1.2	38	0.68	4.8	1.4	0.1	10	0.2	0.5	0.1	33	0.03	0.117	7
1281635	Soil	3.6	26.2	13.2	86	0.2	12.6	3.3	89	1.59	9.6	2.2	0.2	12	0.2	1.3	0.3	82	0.02	0.056	12
1281636	Soil	2.3	20.7	8.8	41	0.1	7.0	1.9	41	0.94	5.3	0.8	0.2	8	0.1	0.7	0.2	53	0.02	0.045	12
1281637	Soil	6.0	53.5	16.2	153	0.5	31.0	7.4	255	2.69	15.1	7.9	0.6	33	0.4	2.3	0.2	85	0.13	0.153	13
1281638	Soil	3.9	31.5	15.0	117	0.2	18.0	5.7	237	3.07	11.4	3.6	0.9	14	0.3	1.5	0.2	77	0.04	0.129	11
1281639	Soil	2.5	27.6	8.6	70	0.3	12.1	2.9	66	1.28	6.5	5.7	0.2	11	0.3	0.9	0.1	49	0.04	0.084	8
1281640	Soil	3.2	21.1	15.0	109	0.3	17.3	6.5	290	2.63	13.1	3.4	0.7	21	0.6	1.4	0.3	66	0.13	0.148	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281611	Soil	6	0.09	286	0.009	2	0.58	0.025	0.03	<0.1	0.07	0.7	<0.1	0.13	2	1.2	<0.2
1281612	Soil	10	0.26	768	0.012	5	0.75	0.025	0.05	0.1	0.18	1.1	<0.1	0.17	2	2.5	<0.2
1281613	Soil	9	0.21	335	0.010	4	0.79	0.023	0.05	<0.1	0.17	1.0	<0.1	0.14	2	2.4	<0.2
1281614	Soil	11	0.17	437	0.011	4	0.98	0.021	0.07	<0.1	0.24	1.1	0.1	0.16	3	3.2	<0.2
1281615	Soil	17	0.13	311	0.007	2	1.05	0.004	0.09	0.1	0.04	0.8	0.1	<0.05	6	0.8	<0.2
1281616	Soil	15	0.22	654	0.009	3	0.87	0.011	0.08	0.2	0.22	1.7	0.1	0.12	3	2.0	<0.2
1281617	Soil	14	0.11	211	0.012	2	0.91	0.005	0.07	0.2	0.01	1.1	0.1	<0.05	6	<0.5	<0.2
1281618	Soil	12	0.17	373	0.007	4	0.84	0.016	0.05	<0.1	0.13	0.7	<0.1	0.10	2	3.2	<0.2
1281619	Soil	20	0.24	137	0.015	2	1.11	0.007	0.07	0.2	0.05	1.3	0.1	<0.05	6	1.3	<0.2
1281620	Soil	16	0.39	442	0.005	3	1.12	0.009	0.09	0.2	0.12	2.3	0.1	<0.05	3	1.7	<0.2
1281621	Soil	19	0.63	323	0.006	3	1.13	0.010	0.11	0.2	0.24	2.8	0.2	<0.05	4	1.9	<0.2
1281622	Soil	19	0.59	422	0.004	4	1.20	0.010	0.10	0.1	0.24	2.5	0.1	<0.05	4	1.5	<0.2
1281623	Soil	9	0.15	93	0.008	2	0.64	0.016	0.05	<0.1	0.02	0.8	<0.1	<0.05	3	0.5	<0.2
1281624	Soil	8	0.47	276	0.008	4	0.66	0.014	0.04	<0.1	0.14	1.1	<0.1	0.15	2	1.3	<0.2
1281625	Soil	16	0.62	433	0.004	5	1.33	0.010	0.15	<0.1	0.17	2.7	0.2	0.07	4	1.9	<0.2
1281626	Soil	18	0.49	408	0.004	4	1.22	0.006	0.14	<0.1	0.17	2.8	0.1	<0.05	3	1.2	<0.2
1281627	Soil	16	0.37	411	0.003	3	1.14	0.007	0.11	0.1	0.19	3.1	0.1	<0.05	3	1.8	<0.2
1281628	Soil	17	0.34	436	0.004	3	1.17	0.007	0.12	0.1	0.17	2.8	0.2	<0.05	3	1.4	<0.2
1281629	Soil	15	0.29	534	0.004	4	1.10	0.010	0.11	0.1	0.14	2.3	0.1	<0.05	3	1.7	<0.2
1281630	Soil	17	0.07	132	0.007	3	0.61	0.003	0.10	0.1	0.05	0.7	0.2	<0.05	6	1.7	<0.2
1281631	Soil	9	0.04	113	0.008	1	0.55	0.006	0.07	<0.1	0.02	0.1	0.2	<0.05	4	<0.5	<0.2
1281632	Soil	18	0.11	162	0.007	3	1.11	0.003	0.11	0.1	0.03	0.5	0.2	<0.05	7	1.0	<0.2
1281633	Soil	9	0.04	109	0.006	1	0.55	0.008	0.06	<0.1	0.03	0.2	0.1	<0.05	4	0.6	<0.2
1281634	Soil	10	0.05	101	0.003	1	0.67	0.009	0.05	<0.1	0.04	0.3	0.2	<0.05	3	0.9	<0.2
1281635	Soil	15	0.10	156	0.009	3	0.91	0.005	0.12	0.1	0.03	0.5	0.2	<0.05	6	1.1	<0.2
1281636	Soil	11	0.06	111	0.008	1	0.88	0.007	0.08	<0.1	0.02	0.3	0.2	<0.05	5	0.8	<0.2
1281637	Soil	25	0.29	239	0.009	2	1.42	0.005	0.15	0.1	0.09	1.1	0.3	<0.05	5	2.9	<0.2
1281638	Soil	20	0.18	146	0.010	2	1.32	0.005	0.11	0.1	0.04	1.4	0.2	<0.05	5	1.4	<0.2
1281639	Soil	13	0.11	308	0.004	3	0.87	0.009	0.10	<0.1	0.06	0.4	0.2	<0.05	4	1.2	<0.2
1281640	Soil	26	0.31	183	0.010	2	1.56	0.004	0.09	0.1	0.06	0.9	0.2	<0.05	5	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281641	Soil	4.9	24.4	14.0	62	0.3	11.4	2.1	46	1.01	9.7	1.4	0.1	23	0.3	1.9	0.2	77	0.03	0.040	13
1281642	Soil	4.5	18.5	13.6	66	0.3	10.8	2.8	116	1.53	7.3	5.0	0.4	14	0.2	1.2	0.2	77	0.04	0.057	13
1281643	Soil	4.1	28.6	10.6	94	0.2	18.3	4.9	104	2.08	7.7	3.3	0.4	11	0.2	1.5	0.2	56	0.03	0.056	7
1281644	Soil	5.9	32.9	15.0	143	0.3	27.5	5.8	188	2.76	12.9	3.6	1.0	20	0.3	2.2	0.2	90	0.16	0.083	11
1281645	Soil	3.8	14.2	8.9	57	<0.1	10.0	2.1	59	0.94	6.6	0.8	0.6	11	0.2	1.3	0.2	57	0.05	0.032	14
1281646	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281647	Soil	5.5	60.9	13.8	122	0.3	31.0	9.9	272	2.37	5.5	5.7	0.3	15	0.3	1.3	0.2	35	0.07	0.084	5
1281648	Soil	8.0	54.8	11.1	229	0.4	40.0	6.3	246	2.27	10.0	7.4	1.5	19	1.5	2.6	0.2	107	0.12	0.095	14
1281649	Soil	2.1	16.8	6.2	32	1.1	12.9	1.3	35	0.55	2.1	3.1	0.1	10	0.4	0.6	<0.1	29	0.09	0.071	6
1281650	Soil	10.3	34.7	15.4	128	0.9	23.9	4.1	104	1.99	11.6	1.4	0.2	19	0.8	3.1	0.3	146	0.04	0.089	13
1281651	Soil	10.2	108.8	41.2	219	0.3	78.1	34.5	1599	6.60	20.5	7.6	1.5	8	0.4	4.4	0.5	52	0.03	0.075	5
1281652	Soil	7.6	70.9	18.0	221	0.2	48.1	14.2	224	4.56	12.8	4.9	1.9	12	0.3	3.2	0.3	78	0.03	0.058	8
1281653	Soil	0.9	11.3	2.6	24	<0.1	6.0	1.9	68	0.66	1.8	<0.5	<0.1	7	<0.1	0.4	0.1	11	0.05	0.041	2
1281654	Soil	18.2	58.3	13.9	328	0.3	58.3	10.2	554	3.06	17.4	5.0	0.8	27	1.5	7.3	0.3	144	0.18	0.154	12
1281655	Soil	28.4	98.3	11.0	959	1.4	138.8	20.0	587	2.74	18.7	5.5	2.2	70	4.8	8.0	0.2	144	0.44	0.158	16
1281656	Soil	6.7	87.6	15.4	292	0.2	54.8	11.3	188	3.56	11.9	10.6	0.7	15	0.6	3.1	0.3	45	0.04	0.113	10
1281657	Soil	7.5	74.6	16.9	283	0.2	55.7	12.4	284	3.72	16.2	3.3	0.8	21	0.4	4.0	0.3	44	0.05	0.109	7
1281658	Soil	7.6	104.1	20.5	215	0.4	32.9	12.0	681	4.17	15.1	5.0	0.9	36	1.4	3.2	0.2	81	0.09	0.335	13
1281659	Soil	3.6	58.1	10.3	106	0.2	16.3	4.0	101	1.79	6.1	8.6	0.2	17	0.4	1.5	0.2	47	0.07	0.146	8
1281660	Soil	5.7	417.1	18.6	639	0.5	105.2	14.9	461	16.40	52.5	16.5	1.4	6	1.1	10.4	0.5	99	0.02	0.180	8
1281661	Soil	4.4	128.9	18.8	260	0.3	45.2	8.6	199	3.20	22.7	20.0	0.9	20	0.7	3.7	0.3	63	0.11	0.127	12
1281662	Soil	3.9	57.7	11.9	151	0.3	20.6	5.2	203	2.06	9.0	4.1	0.6	29	0.4	2.4	0.2	56	0.75	0.086	10
1281663	Soil	4.2	147.0	17.6	140	0.2	45.5	9.2	173	3.75	19.8	20.5	0.6	11	0.2	3.3	0.5	73	0.07	0.101	9
1281664	Soil	3.4	54.5	12.4	76	0.1	21.9	4.6	131	2.54	13.0	5.9	0.3	13	0.1	1.9	0.3	65	0.06	0.123	12
1281665	Soil	5.0	78.6	20.3	339	0.5	69.7	8.6	415	3.81	24.6	17.9	0.8	42	0.6	3.4	0.3	98	0.65	0.149	9
1281666	Soil	6.0	41.7	13.7	123	0.2	25.1	5.0	225	2.32	14.2	3.2	0.5	38	0.3	3.3	0.2	75	0.36	0.204	9
1281667	Soil	3.2	22.5	12.5	69	<0.1	14.1	3.1	82	1.65	12.2	1.0	0.1	16	0.1	1.8	0.3	68	0.09	0.078	11
1281668	Soil	3.4	35.8	8.3	105	<0.1	19.8	4.1	170	1.75	8.4	4.2	0.3	26	0.2	2.0	0.2	70	0.39	0.134	7
1281669	Soil	3.4	61.4	14.5	162	0.2	35.1	10.2	704	2.64	11.5	10.8	0.4	23	0.7	2.0	0.2	61	0.16	0.174	12
1281670	Soil	5.2	45.0	11.5	112	0.2	20.4	3.9	109	1.90	10.2	1.9	0.2	12	0.1	2.1	0.2	73	0.02	0.085	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281641	Soil	14	0.04	155	0.010	1	0.63	0.006	0.05	<0.1	0.03	0.2	0.2	<0.05	5	1.2	<0.2
1281642	Soil	15	0.09	259	0.011	4	0.84	0.005	0.10	0.1	0.03	0.6	0.3	<0.05	5	1.5	<0.2
1281643	Soil	16	0.13	152	0.007	3	0.91	0.009	0.08	0.1	0.03	0.9	0.2	<0.05	4	1.4	<0.2
1281644	Soil	24	0.24	537	0.011	3	1.09	0.005	0.11	0.1	0.06	1.5	0.2	<0.05	5	1.7	<0.2
1281645	Soil	12	0.06	151	0.017	3	0.53	0.004	0.08	0.1	0.02	0.8	0.2	<0.05	4	0.8	<0.2
1281646	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1281647	Soil	18	0.09	304	0.009	4	0.55	0.011	0.09	<0.1	0.06	1.4	0.2	<0.05	2	1.6	<0.2
1281648	Soil	26	0.25	884	0.010	6	1.35	0.006	0.14	0.1	0.31	3.1	0.3	<0.05	4	2.6	<0.2
1281649	Soil	11	0.05	443	0.003	2	0.49	0.018	0.06	<0.1	0.22	0.4	0.1	<0.05	2	0.6	<0.2
1281650	Soil	23	0.11	392	0.006	3	0.96	0.004	0.10	0.1	0.06	0.5	0.3	<0.05	5	1.4	<0.2
1281651	Soil	11	0.07	2097	0.003	3	0.69	0.002	0.13	<0.1	0.16	5.5	0.3	<0.05	2	1.6	<0.2
1281652	Soil	14	0.06	141	0.005	4	0.70	0.002	0.09	<0.1	0.07	2.6	0.2	<0.05	3	2.0	<0.2
1281653	Soil	3	0.03	80	0.007	<1	0.46	0.030	0.04	<0.1	0.03	0.5	<0.1	<0.05	2	<0.5	<0.2
1281654	Soil	19	0.11	917	0.004	3	0.69	0.004	0.09	<0.1	0.13	1.2	0.4	<0.05	3	2.6	<0.2
1281655	Soil	17	0.11	2064	0.006	4	0.48	0.003	0.10	<0.1	0.63	3.8	0.3	<0.05	1	4.9	<0.2
1281656	Soil	17	0.10	222	0.004	2	0.65	0.003	0.13	<0.1	0.07	2.0	0.2	<0.05	3	1.6	<0.2
1281657	Soil	15	0.08	250	0.005	3	0.64	0.003	0.13	<0.1	0.05	2.3	0.2	0.06	3	1.5	<0.2
1281658	Soil	25	0.27	514	0.007	8	1.20	0.005	0.26	<0.1	0.04	1.2	0.3	0.16	5	2.9	<0.2
1281659	Soil	12	0.11	196	0.005	2	0.76	0.009	0.12	<0.1	0.04	0.5	0.2	<0.05	4	2.0	<0.2
1281660	Soil	22	0.08	87	0.011	3	0.65	0.002	0.08	<0.1	0.09	7.8	0.2	<0.05	5	11.4	<0.2
1281661	Soil	21	0.29	115	0.010	3	1.21	0.007	0.11	<0.1	0.25	2.5	0.2	0.07	4	1.8	<0.2
1281662	Soil	12	0.11	289	0.009	4	0.62	0.004	0.11	0.1	0.09	1.4	0.1	0.08	4	1.7	<0.2
1281663	Soil	20	0.14	117	0.009	2	0.81	0.003	0.10	0.1	0.04	2.3	0.2	0.05	4	2.7	<0.2
1281664	Soil	21	0.18	97	0.010	2	1.05	0.006	0.09	<0.1	0.05	0.9	0.2	0.06	5	1.2	<0.2
1281665	Soil	21	0.12	597	0.006	3	1.05	0.003	0.12	0.1	0.15	2.3	0.2	0.08	5	1.4	<0.2
1281666	Soil	17	0.11	203	0.004	1	0.91	0.013	0.07	<0.1	0.05	0.5	0.2	0.08	4	2.2	<0.2
1281667	Soil	14	0.06	184	0.007	2	0.79	0.005	0.05	<0.1	0.05	0.4	0.2	0.08	5	0.9	<0.2
1281668	Soil	15	0.09	364	0.004	2	1.03	0.011	0.07	<0.1	0.01	0.7	0.2	0.08	4	0.8	<0.2
1281669	Soil	21	0.26	200	0.005	3	1.24	0.009	0.13	<0.1	0.07	1.3	0.2	<0.05	4	1.0	<0.2
1281670	Soil	14	0.06	133	0.006	2	0.73	0.006	0.10	0.1	0.02	0.5	0.2	<0.05	5	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281701	Soil	4.7	39.3	9.6	90	0.9	16.6	3.1	64	1.71	9.0	1.1	0.2	13	0.8	2.0	0.2	67	0.03	0.072	11
1281702	Soil	5.5	21.0	21.7	83	0.5	15.0	2.8	94	1.73	11.0	<0.5	0.2	24	0.2	2.9	0.3	115	0.03	0.075	10
1281703	Soil	4.0	45.2	7.8	133	0.8	22.6	3.7	196	1.56	9.0	6.5	0.5	19	2.4	2.2	0.1	55	0.13	0.146	7
1281704	Soil	7.6	46.1	16.0	176	0.7	29.0	5.3	160	2.62	18.6	2.7	0.3	29	0.4	3.5	0.3	109	0.03	0.119	10
1281705	Soil	2.3	15.8	9.3	49	0.3	8.0	2.4	189	1.04	5.7	1.4	0.1	13	0.2	1.0	0.1	39	0.02	0.076	5
1281706	Soil	3.5	37.8	13.5	109	0.3	18.0	3.7	123	2.03	11.5	4.3	0.1	21	0.3	2.1	0.2	82	0.05	0.085	9
1281707	Soil	4.2	36.6	14.3	147	0.5	22.3	5.0	172	2.77	13.6	5.9	0.3	12	0.6	2.6	0.3	76	0.03	0.066	12
1281708	Soil	2.3	52.0	21.8	249	0.6	18.0	23.4	1798	5.43	5.8	4.0	0.7	9	4.7	1.3	0.4	77	0.05	0.189	9
1281709	Soil	0.8	13.0	4.5	77	0.2	6.3	2.5	444	0.71	2.3	<0.5	0.2	45	2.2	0.4	<0.1	18	1.37	0.082	5
1281710	Soil	4.4	58.0	12.0	138	0.2	23.3	6.1	191	2.58	11.1	5.5	0.5	19	0.5	2.1	0.2	81	0.10	0.124	12
1281711	Soil	5.3	134.1	11.9	191	2.4	49.3	4.6	233	1.69	11.0	11.5	0.7	132	2.8	3.1	0.2	98	2.21	0.230	12
1281712	Soil	0.7	59.7	3.6	42	0.5	18.8	2.1	288	0.68	1.2	6.5	0.3	67	0.6	0.7	<0.1	17	1.47	0.127	8
1281713	Soil	7.3	124.4	11.9	260	1.5	43.7	6.9	165	2.28	8.9	19.5	2.2	159	0.9	2.2	0.2	216	2.19	0.450	18
1281714	Soil	4.6	94.4	12.3	216	1.1	31.9	6.0	256	2.07	11.0	15.1	1.1	77	1.5	2.3	0.2	47	1.92	0.188	13
1281715	Soil	1.1	97.2	7.4	81	0.8	21.8	3.3	205	1.22	4.4	14.3	0.3	122	0.7	1.1	0.2	59	3.31	0.158	8
1281716	Soil	3.7	85.7	10.8	279	1.6	46.8	7.3	497	1.85	10.9	11.8	0.7	116	4.4	2.7	0.2	91	2.34	0.170	9
1281717	Soil	8.7	57.1	16.2	215	1.7	30.8	10.2	674	2.25	20.0	5.7	0.8	107	1.8	4.0	0.2	124	1.31	0.158	9
1281718	Soil	8.2	56.0	12.5	233	2.1	33.6	7.0	3384	1.44	13.6	7.7	1.1	100	4.2	3.5	0.2	104	1.44	0.138	9
1281719	Soil	3.3	25.3	5.8	55	0.6	12.3	2.4	285	0.72	4.3	4.1	0.2	84	0.6	1.9	<0.1	40	1.58	0.098	4
1281720	Soil	3.3	15.1	5.0	42	0.1	6.9	1.5	47	0.69	8.9	1.2	0.5	11	0.2	1.6	0.1	57	0.07	0.023	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

CERTIFICATE OF ANALYSIS WHI11001471.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281701	Soil	12	0.03	170	0.007	1	0.46	0.008	0.06	<0.1	0.04	0.3	0.1	0.06	3	0.5	<0.2
1281702	Soil	19	0.07	219	0.008	2	0.59	0.004	0.09	0.1	0.03	0.7	0.2	0.10	5	1.0	<0.2
1281703	Soil	16	0.13	452	0.007	3	0.83	0.009	0.09	0.1	0.08	1.2	0.1	0.12	3	0.9	<0.2
1281704	Soil	23	0.12	228	0.005	4	0.82	0.004	0.13	0.1	0.05	0.9	0.2	0.06	4	1.3	<0.2
1281705	Soil	9	0.04	120	0.004	<1	0.48	0.011	0.06	<0.1	0.02	0.5	<0.1	0.05	2	<0.5	<0.2
1281706	Soil	16	0.07	185	0.005	1	0.77	0.006	0.08	0.1	0.04	0.7	0.2	0.05	4	1.0	<0.2
1281707	Soil	16	0.11	169	0.013	2	0.78	0.003	0.12	0.1	0.01	1.3	0.2	0.06	5	1.0	<0.2
1281708	Soil	32	0.32	514	0.013	5	1.72	0.004	0.20	<0.1	0.05	1.4	0.1	0.11	9	0.9	<0.2
1281709	Soil	6	0.07	260	0.008	<1	0.69	0.035	0.03	<0.1	0.08	0.7	<0.1	0.14	2	0.5	<0.2
1281710	Soil	22	0.27	301	0.005	4	1.26	0.004	0.15	0.1	0.07	1.4	0.2	0.07	5	1.3	<0.2
1281711	Soil	20	0.21	628	0.003	7	0.82	0.007	0.09	<0.1	1.07	1.6	0.3	0.26	2	6.7	<0.2
1281712	Soil	6	0.15	365	0.010	3	1.01	0.025	0.03	<0.1	0.21	0.9	<0.1	0.18	2	3.4	<0.2
1281713	Soil	36	0.82	485	0.008	12	1.64	0.007	0.32	<0.1	0.49	4.0	0.2	0.08	5	1.9	<0.2
1281714	Soil	14	0.40	396	0.005	5	0.88	0.014	0.09	<0.1	0.44	1.8	0.1	0.14	2	2.5	<0.2
1281715	Soil	15	0.31	522	0.005	7	0.76	0.008	0.07	<0.1	0.56	1.3	0.1	0.21	2	4.0	<0.2
1281716	Soil	20	0.22	706	0.004	6	0.78	0.008	0.08	<0.1	0.82	2.1	0.2	0.16	2	5.2	<0.2
1281717	Soil	21	0.16	941	0.003	3	0.80	0.006	0.08	<0.1	0.87	2.1	0.2	0.12	3	3.6	<0.2
1281718	Soil	20	0.15	906	0.003	4	0.79	0.007	0.07	<0.1	1.05	2.6	0.3	0.12	2	2.2	<0.2
1281719	Soil	8	0.13	560	0.008	5	0.52	0.021	0.05	<0.1	0.25	0.9	0.1	0.08	2	1.8	<0.2
1281720	Soil	7	0.02	143	0.008	2	0.30	0.006	0.03	0.1	0.07	0.6	0.1	<0.05	3	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

QUALITY CONTROL REPORT WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1280877	Soil	2.2	49.5	10.3	137	0.7	25.7	8.3	230	2.10	6.8	10.0	2.7	54	0.6	1.2	0.2	55	0.85	0.123	13
REP 1280877	QC	2.2	50.0	9.7	136	0.7	26.0	8.0	224	2.09	7.1	10.8	2.6	54	0.7	1.2	0.2	53	0.87	0.135	13
1280893	Soil	3.3	90.4	13.1	165	<0.1	20.6	7.6	261	3.97	9.9	24.2	1.0	9	1.2	2.1	0.5	96	0.04	0.074	11
REP 1280893	QC	3.3	89.6	13.2	170	<0.1	20.4	7.6	267	4.20	9.9	5.4	0.9	9	1.2	2.0	0.5	93	0.04	0.070	11
1280898	Soil	5.3	44.2	17.1	128	0.4	21.5	6.5	212	3.22	14.4	3.8	1.7	21	0.7	1.9	0.3	86	0.05	0.160	10
REP 1280898	QC	5.3	45.3	17.4	127	0.4	21.0	6.6	213	3.24	14.2	3.6	1.8	21	0.6	1.9	0.3	87	0.05	0.164	10
1280916	Soil	6.4	31.1	11.0	101	0.1	20.5	4.3	60	1.73	11.3	<0.5	0.2	12	0.1	3.1	0.2	84	0.01	0.042	9
REP 1280916	QC	6.6	33.2	10.7	107	0.1	21.8	4.4	60	1.81	12.1	<0.5	0.1	12	0.1	3.1	0.3	90	0.01	0.044	10
1280937	Soil	2.9	25.5	10.2	55	0.8	13.6	2.0	85	1.06	4.7	2.3	0.3	31	1.0	1.0	0.2	38	0.25	0.202	6
REP 1280937	QC	3.2	26.7	10.9	58	0.8	14.3	2.0	80	1.05	4.5	2.7	0.3	32	0.9	1.0	0.2	40	0.25	0.210	7
1280953	Soil	5.9	47.0	9.2	193	0.2	36.4	7.8	160	1.86	4.2	1.5	0.5	16	0.6	1.8	0.2	30	0.26	0.056	5
REP 1280953	QC	5.8	46.7	9.1	199	0.2	37.1	7.7	163	1.91	3.8	2.5	0.8	16	0.6	1.9	0.2	33	0.24	0.058	5
1281135	Soil	0.4	23.3	3.1	25	0.2	7.3	1.6	55	0.55	1.0	4.9	0.4	30	0.2	0.4	<0.1	16	0.82	0.050	7
REP 1281135	QC	0.6	24.1	3.2	24	0.2	6.9	1.6	54	0.53	1.5	3.9	0.6	30	0.2	0.4	<0.1	16	0.78	0.050	8
1281146	Soil	1.8	16.2	5.1	43	0.2	6.6	3.4	104	0.92	3.1	1.6	0.5	8	0.2	0.6	<0.1	23	0.06	0.053	5
REP 1281146	QC	1.8	17.1	5.7	43	0.1	7.3	3.8	109	1.00	3.3	0.9	0.7	9	0.2	0.7	<0.1	27	0.05	0.055	5
1281547	Soil	0.4	66.8	10.2	95	0.7	22.7	5.1	183	1.11	5.0	9.2	1.1	82	0.9	1.2	0.2	41	1.87	0.097	10
REP 1281547	QC	0.4	66.2	10.1	95	0.7	21.8	4.9	177	1.08	4.8	8.8	1.2	82	0.8	1.2	0.2	39	1.86	0.095	10
1281580	Soil	12.0	117.4	29.5	181	4.1	61.2	12.0	339	5.32	39.3	9.2	0.9	249	1.3	11.4	0.4	119	0.09	0.202	2
REP 1281580	QC	11.9	117.5	29.5	184	4.2	62.3	11.9	332	5.30	39.2	10.9	0.9	246	1.2	10.8	0.4	118	0.09	0.204	2
1281592	Soil	15.5	29.3	32.6	103	1.4	22.8	2.9	58	1.58	17.1	1.2	0.7	61	0.3	7.8	0.3	181	0.02	0.064	9
REP 1281592	QC	15.7	28.9	32.4	102	1.5	22.6	2.9	57	1.57	16.8	0.9	0.5	62	0.3	8.0	0.3	180	0.02	0.066	9
1281604	Soil	10.9	57.7	10.3	208	0.7	46.9	8.5	242	2.38	8.6	5.5	2.8	43	0.9	2.9	0.2	89	0.49	0.080	15
REP 1281604	QC	11.3	57.0	9.8	209	0.7	45.6	8.9	248	2.39	8.5	8.2	2.9	43	0.8	3.0	0.2	95	0.48	0.073	15
1281629	Soil	1.7	33.2	9.8	122	0.3	23.4	8.4	437	1.97	9.5	3.1	1.8	72	1.1	1.2	0.2	38	1.50	0.081	12
REP 1281629	QC	1.7	33.9	10.1	122	0.3	23.1	8.5	442	1.99	9.9	2.3	1.7	71	1.0	1.3	0.2	36	1.54	0.084	12
1281639	Soil	2.5	27.6	8.6	70	0.3	12.1	2.9	66	1.28	6.5	5.7	0.2	11	0.3	0.9	0.1	49	0.04	0.084	8
REP 1281639	QC	2.6	27.0	9.1	70	0.3	12.6	2.7	65	1.25	6.3	4.8	0.2	11	0.4	0.9	0.1	52	0.04	0.086	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

QUALITY CONTROL REPORT WHI11001471.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1280877	Soil	22	0.57	448	0.007	5	1.34	0.007	0.14	<0.1	0.26	3.0	0.2	<0.05	4	1.4	<0.2
REP 1280877	QC	21	0.61	446	0.007	5	1.36	0.007	0.15	<0.1	0.28	3.1	0.2	<0.05	4	1.4	<0.2
1280893	Soil	27	0.08	103	0.007	1	0.93	0.006	0.04	0.1	0.04	1.9	<0.1	<0.05	7	1.2	0.3
REP 1280893	QC	27	0.08	98	0.007	1	0.85	0.006	0.04	0.1	0.04	1.9	<0.1	<0.05	7	1.1	0.3
1280898	Soil	22	0.25	246	0.007	3	1.32	0.004	0.13	0.1	0.03	1.8	0.2	<0.05	5	1.4	<0.2
REP 1280898	QC	22	0.24	244	0.006	3	1.36	0.004	0.13	0.1	0.03	1.8	0.2	<0.05	5	1.5	<0.2
1280916	Soil	10	0.03	93	0.004	2	0.48	0.004	0.04	0.1	0.01	0.4	0.1	<0.05	3	1.2	<0.2
REP 1280916	QC	10	0.03	93	0.005	2	0.50	0.004	0.04	<0.1	0.02	0.4	0.1	<0.05	4	1.0	<0.2
1280937	Soil	11	0.09	634	0.008	2	0.75	0.008	0.06	0.1	0.16	0.9	0.2	0.09	3	1.1	<0.2
REP 1280937	QC	12	0.09	642	0.004	3	0.78	0.009	0.07	0.1	0.16	0.8	0.2	0.08	3	1.1	<0.2
1280953	Soil	10	0.12	453	0.004	3	0.53	0.011	0.07	<0.1	0.06	1.6	0.1	<0.05	2	1.1	<0.2
REP 1280953	QC	10	0.12	460	0.007	3	0.56	0.011	0.08	<0.1	0.05	1.7	0.1	0.06	2	1.2	<0.2
1281135	Soil	8	0.21	192	0.008	2	0.59	0.023	0.05	<0.1	0.09	1.0	<0.1	0.05	2	0.8	<0.2
REP 1281135	QC	9	0.20	194	0.009	<1	0.60	0.022	0.05	<0.1	0.09	0.8	<0.1	<0.05	2	1.4	<0.2
1281146	Soil	9	0.14	66	0.006	<1	0.54	0.015	0.04	<0.1	0.03	0.7	<0.1	<0.05	2	0.5	<0.2
REP 1281146	QC	10	0.15	73	0.008	2	0.58	0.013	0.05	<0.1	0.04	0.7	<0.1	<0.05	2	0.6	<0.2
1281547	Soil	14	0.39	446	0.005	6	0.84	0.009	0.09	<0.1	0.41	2.3	0.2	0.14	2	2.0	<0.2
REP 1281547	QC	15	0.39	428	0.004	6	0.83	0.010	0.09	<0.1	0.39	2.1	0.2	0.15	2	1.5	<0.2
1281580	Soil	22	0.04	799	0.006	2	0.52	0.005	0.15	<0.1	0.12	5.4	0.6	0.26	2	8.1	0.3
REP 1281580	QC	22	0.04	845	0.005	2	0.50	0.005	0.15	<0.1	0.12	5.7	0.6	0.28	2	9.1	0.3
1281592	Soil	15	0.02	510	0.004	4	0.35	0.004	0.07	0.2	0.09	1.0	0.7	0.08	4	6.3	0.2
REP 1281592	QC	16	0.02	520	0.004	3	0.40	0.004	0.08	0.1	0.10	1.1	0.7	0.09	4	7.1	<0.2
1281604	Soil	23	0.57	755	0.009	4	1.29	0.007	0.16	0.1	0.23	3.2	0.2	0.11	4	2.5	<0.2
REP 1281604	QC	24	0.54	762	0.009	4	1.27	0.006	0.15	<0.1	0.22	3.0	0.2	0.08	4	1.9	<0.2
1281629	Soil	15	0.29	534	0.004	4	1.10	0.010	0.11	0.1	0.14	2.3	0.1	<0.05	3	1.7	<0.2
REP 1281629	QC	15	0.29	532	0.004	4	1.12	0.015	0.11	<0.1	0.16	2.3	0.1	<0.05	3	1.7	<0.2
1281639	Soil	13	0.11	308	0.004	3	0.87	0.009	0.10	<0.1	0.06	0.4	0.2	<0.05	4	1.2	<0.2
REP 1281639	QC	14	0.12	306	0.004	4	0.90	0.009	0.11	0.1	0.07	0.3	0.1	<0.05	4	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

QUALITY CONTROL REPORT WHI11001471.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1281670	Soil	5.2	45.0	11.5	112	0.2	20.4	3.9	109	1.90	10.2	1.9	0.2	12	0.1	2.1	0.2	73	0.02	0.085	11
REP 1281670	QC	5.2	41.8	11.4	114	0.2	21.1	4.0	109	1.82	10.0	2.8	0.1	12	0.2	2.2	0.3	68	0.02	0.086	10
1281707	Soil	4.2	36.6	14.3	147	0.5	22.3	5.0	172	2.77	13.6	5.9	0.3	12	0.6	2.6	0.3	76	0.03	0.066	12
REP 1281707	QC	4.0	37.9	14.1	146	0.5	23.3	4.9	175	2.68	13.6	3.0	0.4	12	0.4	2.7	0.3	74	0.03	0.066	12
Reference Materials																					
STD DS8	Standard	12.6	115.9	125.1	315	1.8	37.0	7.5	598	2.43	26.0	135.4	6.5	65	2.4	5.9	6.8	42	0.67	0.080	14
STD DS8	Standard	12.4	111.6	122.5	313	1.8	38.8	7.6	560	2.41	25.2	105.7	5.9	63	2.4	5.3	6.5	42	0.64	0.076	12
STD DS8	Standard	12.5	111.2	129.6	313	1.8	39.8	7.6	607	2.36	24.5	109.5	6.5	64	2.3	5.5	6.8	41	0.70	0.077	13
STD DS8	Standard	12.7	109.4	121.5	307	1.7	36.4	7.6	596	2.45	25.7	114.6	6.3	60	2.3	4.7	6.4	39	0.65	0.077	14
STD DS8	Standard	12.9	107.2	119.6	300	1.8	36.4	7.4	598	2.36	24.2	101.3	6.3	64	2.4	5.6	6.3	41	0.65	0.077	14
STD DS8	Standard	13.1	112.1	118.7	316	1.7	37.3	7.6	591	2.49	25.2	118.2	6.4	67	2.2	5.9	6.3	42	0.68	0.074	15
STD DS8	Standard	13.1	107.2	124.2	304	1.8	36.4	7.5	617	2.41	24.7	110.6	6.9	69	2.5	5.4	6.6	43	0.73	0.080	15
STD DS8	Standard	12.9	107.6	129.7	309	1.8	37.4	7.4	614	2.47	25.5	112.8	7.0	71	2.3	5.8	6.9	42	0.71	0.079	17
STD DS8	Standard	13.9	110.5	128.4	318	1.9	37.6	7.7	621	2.50	25.1	106.3	7.2	72	2.3	5.8	6.8	43	0.73	0.080	17
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 19, 2011

QUALITY CONTROL REPORT WHI11001471.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1281670	Soil	14	0.06	133	0.006	2	0.73	0.006	0.10	0.1	0.02	0.5	0.2	<0.05	5	1.3	<0.2
REP 1281670	QC	13	0.06	124	0.003	2	0.70	0.006	0.09	<0.1	0.02	0.5	0.2	<0.05	4	1.5	<0.2
1281707	Soil	16	0.11	169	0.013	2	0.78	0.003	0.12	0.1	0.01	1.3	0.2	0.06	5	1.0	<0.2
REP 1281707	QC	16	0.11	167	0.011	2	0.74	0.003	0.12	0.1	0.02	1.4	0.2	0.06	5	1.2	<0.2
Reference Materials																	
STD DS8	Standard	113	0.60	280	0.118	3	0.87	0.099	0.42	3.1	0.21	2.5	5.4	0.14	5	5.1	4.9
STD DS8	Standard	111	0.60	265	0.102	2	0.89	0.089	0.42	2.8	0.20	2.3	5.4	0.14	4	5.6	4.4
STD DS8	Standard	109	0.61	262	0.106	2	0.91	0.093	0.43	2.9	0.19	2.3	5.6	0.14	5	5.2	5.2
STD DS8	Standard	112	0.58	252	0.103	3	0.80	0.081	0.36	2.8	0.20	2.0	5.5	0.14	5	5.4	5.0
STD DS8	Standard	112	0.60	270	0.116	2	0.91	0.089	0.41	3.0	0.20	2.4	5.1	0.14	4	5.2	4.9
STD DS8	Standard	116	0.57	269	0.115	2	0.89	0.091	0.40	2.6	0.18	2.2	5.1	0.19	5	4.7	5.4
STD DS8	Standard	121	0.60	275	0.119	3	0.93	0.110	0.43	3.0	0.22	3.1	5.4	0.18	5	4.8	4.6
STD DS8	Standard	115	0.60	284	0.123	3	0.93	0.100	0.43	3.0	0.20	2.8	5.7	0.13	5	5.1	4.9
STD DS8	Standard	121	0.61	288	0.128	3	0.96	0.096	0.42	2.9	0.23	2.4	5.7	0.13	5	5.2	5.3
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 22, 2011
Report Date: December 05, 2011
Page: 1 of 9

CERTIFICATE OF ANALYSIS WHI11001855.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #30
P.O. Number
Number of Samples:

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	240	Sieve soil to 230 mesh			VAN
RJSV	240	Saving all or part of Soil Reject			VAN
1DX2	239	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288371	Soil	18.3	54.2	68.2	94	2.0	32.7	3.6	28	2.59	90.0	5.1	1.0	273	0.3	8.4	0.2	102	0.07	0.142	4
1288372	Soil	9.3	36.0	66.9	47	1.3	18.5	2.7	33	1.16	69.7	4.7	0.5	101	0.4	3.6	0.2	50	0.06	0.103	3
1288373	Soil	9.0	30.0	66.6	34	1.6	13.3	1.9	16	1.00	44.4	3.9	0.7	83	0.2	3.7	0.2	42	0.05	0.070	3
1288374	Soil	5.5	64.3	27.8	132	0.9	41.4	17.6	1008	3.83	91.4	3.6	0.3	18	0.5	2.6	0.3	49	0.13	0.122	5
1288375	Soil	9.0	137.9	51.4	963	1.5	126.8	42.5	960	5.66	138.9	6.2	1.2	37	3.0	5.3	0.4	59	0.40	0.131	4
1288376	Soil	9.1	228.3	58.2	536	2.1	114.4	32.7	501	6.03	52.1	7.1	1.4	74	1.0	6.1	0.5	54	0.51	0.114	3
1288377	Soil	6.6	91.1	28.9	328	0.8	55.3	18.8	404	3.34	32.0	4.8	0.7	17	0.6	3.5	0.3	41	0.08	0.082	3
1288378	Soil	7.6	148.2	40.9	498	1.1	83.7	24.6	531	4.67	60.7	5.9	1.2	34	1.2	4.7	0.4	41	0.28	0.094	3
1288379	Soil	6.7	181.4	54.3	630	1.6	118.4	48.9	1108	5.98	38.9	7.2	1.7	32	1.8	5.1	0.4	50	0.21	0.114	4
1288380	Soil	21.9	36.2	18.8	179	0.1	43.2	6.3	80	1.81	35.5	2.0	0.7	8	0.3	4.3	0.2	105	0.02	0.042	4
1288381	Soil	15.9	26.5	12.4	119	0.3	31.0	5.2	87	1.28	33.1	2.0	0.9	8	0.2	3.2	0.2	63	0.03	0.040	6
1288382	Soil	26.2	18.0	8.5	114	<0.1	37.4	3.3	40	0.97	16.8	1.3	0.4	6	0.2	2.8	<0.1	70	0.03	0.027	5
1288383	Soil	9.2	22.0	8.6	95	0.3	22.5	3.8	64	0.97	13.6	1.2	0.2	7	0.2	1.9	0.1	39	0.06	0.046	4
1288384	Soil	17.5	33.6	13.9	165	0.4	39.1	6.7	178	1.81	23.0	2.4	0.4	12	0.4	2.5	0.2	45	0.12	0.055	5
1288385	Soil	21.6	50.1	18.4	187	0.8	53.7	9.2	308	2.11	20.4	3.9	2.0	44	1.7	3.5	0.2	69	0.49	0.099	8
1288386	Soil	27.8	63.1	22.4	378	0.7	79.6	11.8	237	2.62	35.6	4.2	1.2	48	2.0	5.1	0.2	70	0.59	0.108	4
1288387	Soil	18.9	29.0	15.8	164	0.2	42.8	5.8	103	1.93	23.1	2.3	1.1	17	0.4	3.4	0.2	78	0.10	0.068	10
1288388	Soil	35.3	32.7	12.3	200	0.2	74.3	6.4	70	1.94	22.1	1.7	1.2	12	0.9	3.4	0.1	85	0.14	0.047	7
1288389	Soil	36.7	40.1	10.8	219	0.2	86.2	7.3	98	2.10	20.8	2.0	1.6	34	0.7	2.6	0.2	47	0.62	0.085	7
1288390	Soil	49.5	60.8	14.4	255	0.7	143.3	9.6	447	2.65	23.8	3.5	1.7	48	2.0	3.4	0.1	84	1.27	0.091	12
1288571	Soil	44.9	87.0	29.6	873	1.3	143.9	12.3	274	2.66	43.6	1.9	2.2	88	8.6	9.4	0.2	173	2.64	0.129	8
1288572	Soil	37.9	74.5	24.0	603	0.9	100.3	9.5	220	2.17	34.8	1.4	2.5	98	7.0	7.3	0.2	156	2.86	0.136	9
1288573	Soil	27.2	73.3	21.8	662	0.8	107.6	8.5	189	2.16	34.9	1.5	2.6	86	7.1	6.3	0.1	133	2.50	0.155	10
1288574	Soil	14.1	68.6	19.0	500	0.9	113.5	5.3	123	1.44	24.5	3.3	0.5	112	2.6	5.2	0.1	115	3.30	0.095	4
1288575	Soil	25.2	73.8	22.8	606	1.0	83.9	5.3	57	1.80	29.9	1.8	2.4	72	3.2	6.2	0.2	173	1.80	0.141	9
1288576	Soil	21.9	100.7	21.0	660	1.1	120.9	9.7	516	1.94	29.0	1.9	2.5	84	10.2	6.5	0.1	179	2.04	0.136	11
1288577	Soil	24.0	81.0	12.0	598	0.9	155.3	4.3	171	0.95	20.5	2.5	0.4	115	13.4	6.4	<0.1	129	3.88	0.112	6
1288578	Soil	26.9	64.4	11.3	642	1.2	149.2	5.4	179	1.04	21.2	1.7	1.1	86	12.6	6.3	<0.1	146	2.67	0.097	7
1288579	Soil	4.2	19.1	3.7	143	0.2	25.1	1.5	108	0.30	4.3	0.7	0.2	62	3.3	1.4	<0.1	26	1.69	0.037	2
1288580	Soil	1.5	19.6	6.5	78	0.3	22.7	1.7	70	0.86	3.3	2.2	0.3	56	1.2	0.7	<0.1	10	0.78	0.072	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288371	Soil	15	0.02	716	<0.001	3	0.37	0.008	0.15	<0.1	0.37	4.1	1.1	0.33	1	7.6	<0.2
1288372	Soil	9	0.02	833	<0.001	4	0.33	0.006	0.10	<0.1	0.21	2.1	0.6	0.13	1	4.2	<0.2
1288373	Soil	8	0.01	1222	<0.001	3	0.26	0.005	0.09	<0.1	0.22	2.4	0.5	0.12	1	3.9	<0.2
1288374	Soil	17	0.07	300	0.003	1	0.71	0.011	0.06	<0.1	0.11	2.3	0.2	<0.05	3	1.8	<0.2
1288375	Soil	17	0.05	400	0.001	15	0.45	0.004	0.07	<0.1	0.22	4.8	0.2	<0.05	2	2.8	0.3
1288376	Soil	13	0.09	959	0.001	1	0.47	0.004	0.08	<0.1	0.17	5.3	0.2	0.10	2	6.7	<0.2
1288377	Soil	11	0.04	335	<0.001	2	0.38	0.005	0.06	<0.1	0.05	2.8	0.3	<0.05	1	1.8	0.2
1288378	Soil	13	0.07	745	<0.001	2	0.35	0.004	0.08	<0.1	0.17	4.5	0.3	0.05	1	3.0	0.2
1288379	Soil	19	0.08	929	0.001	2	0.40	0.004	0.10	<0.1	0.12	7.1	0.5	0.06	2	3.9	0.2
1288380	Soil	9	0.02	216	0.001	2	0.35	0.004	0.05	<0.1	0.04	1.2	0.3	<0.05	3	1.3	<0.2
1288381	Soil	8	0.03	153	0.002	2	0.43	0.004	0.04	0.1	0.53	1.0	0.2	<0.05	3	1.3	<0.2
1288382	Soil	7	0.02	134	0.001	3	0.27	0.004	0.03	<0.1	0.06	0.7	0.3	<0.05	2	1.0	<0.2
1288383	Soil	7	0.03	109	0.002	2	0.27	0.008	0.04	<0.1	0.06	0.4	0.2	<0.05	2	0.8	<0.2
1288384	Soil	10	0.04	292	0.002	1	0.30	0.007	0.05	<0.1	0.05	1.0	0.2	<0.05	1	1.0	<0.2
1288385	Soil	13	0.11	832	0.002	1	0.54	0.007	0.05	<0.1	0.37	2.8	0.3	<0.05	2	1.4	<0.2
1288386	Soil	13	0.08	429	0.001	2	0.32	0.005	0.07	<0.1	0.22	2.7	0.3	0.06	1	2.4	<0.2
1288387	Soil	13	0.09	404	0.003	2	0.60	0.003	0.05	0.2	0.17	1.2	0.4	<0.05	3	1.7	<0.2
1288388	Soil	15	0.06	338	0.002	1	0.63	0.005	0.04	0.1	0.12	1.7	0.5	<0.05	2	1.5	<0.2
1288389	Soil	14	0.08	514	0.003	2	0.41	0.006	0.05	0.1	0.14	2.7	0.4	<0.05	1	1.5	<0.2
1288390	Soil	25	0.36	622	0.004	2	0.44	0.005	0.05	0.2	0.48	5.1	1.1	<0.05	<1	2.3	<0.2
1288571	Soil	18	1.00	714	0.002	6	0.41	0.005	0.10	0.1	0.58	3.6	1.0	0.11	1	5.8	<0.2
1288572	Soil	16	1.17	848	0.002	6	0.34	0.006	0.10	0.1	0.46	3.2	0.8	0.11	1	5.9	<0.2
1288573	Soil	15	1.10	882	0.002	4	0.34	0.005	0.08	<0.1	0.50	3.3	0.6	0.07	1	2.7	<0.2
1288574	Soil	14	0.43	582	0.002	11	0.28	0.008	0.06	<0.1	0.51	1.4	0.8	0.20	<1	6.3	<0.2
1288575	Soil	16	0.70	600	0.002	6	0.38	0.005	0.09	<0.1	0.44	3.1	0.8	0.07	<1	4.8	<0.2
1288576	Soil	19	0.71	805	0.003	6	0.43	0.007	0.09	0.2	0.53	3.8	0.8	0.07	1	3.6	<0.2
1288577	Soil	15	0.60	706	0.002	8	0.22	0.010	0.05	<0.1	0.50	1.5	0.7	0.15	<1	6.9	<0.2
1288578	Soil	19	0.76	478	0.003	5	0.31	0.016	0.06	0.2	0.43	3.3	0.8	0.10	<1	3.3	<0.2
1288579	Soil	5	0.13	307	0.006	2	0.33	0.025	0.02	<0.1	0.11	0.5	0.2	0.08	<1	3.4	<0.2
1288580	Soil	6	0.06	747	0.005	2	0.37	0.019	0.02	<0.1	0.10	0.9	<0.1	0.13	<1	1.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288581	Soil	2.4	14.0	8.8	77	0.3	18.8	5.1	237	1.15	9.4	1.0	0.9	55	0.3	0.7	<0.1	23	1.09	0.068	3
1288582	Soil	2.8	17.0	7.3	66	0.2	21.0	2.2	36	0.99	6.5	<0.5	0.4	32	0.4	0.7	<0.1	20	0.52	0.038	2
1288583	Soil	10.0	93.8	16.6	954	1.5	218.8	31.2	2172	3.86	16.2	6.7	1.2	73	9.0	1.9	0.1	41	1.23	0.123	5
1288584	Soil	1.9	30.4	9.2	72	0.8	26.7	3.1	91	0.94	4.1	2.8	0.3	24	1.1	0.8	<0.1	13	0.21	0.069	3
1288585	Soil	0.9	12.0	4.2	35	0.4	14.1	1.3	47	0.52	4.5	1.0	<0.1	15	1.0	0.4	<0.1	12	0.24	0.038	2
1288586	Soil	5.4	34.0	10.8	105	0.5	30.1	2.1	52	0.71	6.5	0.5	0.2	27	2.0	0.8	<0.1	46	0.29	0.044	4
1288587	Soil	2.5	9.5	10.4	44	0.5	8.6	2.2	58	1.56	12.9	0.8	0.8	11	0.2	1.2	0.2	50	0.02	0.055	7
1288588	Soil	5.2	40.1	18.0	209	0.4	43.8	14.5	259	3.16	26.8	3.0	1.9	32	1.1	2.5	0.2	46	0.19	0.070	6
1288589	Soil	3.7	9.9	15.7	42	0.7	8.8	2.0	40	1.01	12.2	0.7	0.1	19	0.1	1.2	0.1	34	0.02	0.047	4
1288590	Soil	2.3	5.6	11.7	32	0.5	5.9	1.7	56	1.40	10.9	1.0	2.1	10	0.1	0.9	0.2	50	0.04	0.038	10
1288591	Soil	28.5	69.1	27.9	540	1.4	98.5	6.8	212	1.74	31.8	0.9	1.2	85	6.8	7.1	0.2	182	1.83	0.109	9
1288592	Soil	28.3	83.9	15.0	677	1.0	119.8	6.0	124	1.77	28.8	1.5	1.3	109	7.9	8.2	0.2	226	2.72	0.141	9
1288593	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1288594	Soil	7.4	36.6	11.3	987	0.5	119.2	11.1	702	1.59	12.2	1.9	1.1	94	3.6	2.5	0.1	65	1.81	0.081	5
1288595	Soil	8.7	34.0	10.7	963	0.4	118.7	10.1	83	1.42	14.9	1.9	1.2	85	2.4	2.0	0.2	54	1.29	0.077	5
1288596	Soil	8.1	34.5	11.2	711	0.5	92.5	9.0	161	1.61	11.4	2.6	1.4	79	1.8	2.1	0.2	46	1.30	0.066	5
1288597	Soil	5.6	20.7	5.4	292	0.3	70.5	7.2	206	1.33	8.0	1.9	0.5	93	1.0	1.1	0.1	21	1.46	0.066	3
1288598	Soil	3.7	38.5	10.5	400	0.4	69.4	4.9	54	1.01	7.2	3.3	1.4	70	2.7	2.0	0.1	41	0.85	0.074	7
1288599	Soil	6.4	40.2	11.7	160	0.6	53.3	8.2	159	2.18	14.6	2.4	2.0	76	1.6	2.0	0.2	48	0.83	0.080	7
1288600	Soil	1.0	7.3	2.4	25	0.2	9.1	1.1	22	0.41	1.6	0.6	0.2	56	1.1	0.7	<0.1	14	1.07	0.030	1
1288781	Soil	4.4	105.2	10.0	150	0.2	283.4	63.1	494	5.87	69.9	3.4	4.3	52	0.9	2.3	<0.1	48	2.08	0.224	75
1288782	Soil	4.5	105.6	22.4	120	0.1	388.7	82.5	1501	8.24	11.9	1.0	6.2	41	0.8	0.9	<0.1	244	0.98	0.290	276
1288783	Soil	2.7	46.4	8.4	78	0.1	110.0	24.7	784	3.54	10.2	0.6	1.7	46	0.4	0.7	<0.1	90	1.55	0.188	81
1288784	Soil	1.3	52.4	7.3	54	0.1	101.2	16.0	466	2.73	3.6	<0.5	1.5	53	0.2	0.5	<0.1	80	1.65	0.202	61
1288785	Soil	3.4	62.8	11.0	81	0.1	161.9	32.6	951	4.99	9.0	1.7	3.3	56	0.4	0.9	<0.1	140	1.68	0.230	60
1288786	Soil	3.5	84.6	12.0	81	0.1	223.0	42.9	925	5.81	17.3	1.7	5.1	52	0.3	0.9	<0.1	123	1.83	0.170	109
1288787	Soil	74.2	151.4	17.5	1204	1.8	277.4	24.3	561	4.23	60.8	3.0	1.9	191	13.6	29.0	0.1	617	4.81	0.185	32
1288788	Soil	39.6	54.3	9.5	636	0.5	131.9	11.4	206	2.27	31.7	1.2	0.9	57	7.1	13.3	<0.1	321	0.78	0.159	21
1288789	Soil	50.6	41.9	9.9	503	0.2	120.3	9.1	174	2.38	26.0	<0.5	0.7	23	2.7	8.4	0.1	184	0.30	0.125	19
1288790	Soil	59.6	33.2	9.2	275	<0.1	107.3	7.2	97	1.94	21.4	<0.5	0.4	8	1.3	5.1	0.2	185	0.06	0.140	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288581	Soil	11	0.15	659	0.003	2	0.58	0.015	0.03	<0.1	0.09	1.5	<0.1	0.10	2	1.4	<0.2
1288582	Soil	7	0.08	330	0.004	<1	0.30	0.013	0.03	0.1	0.08	1.0	<0.1	0.10	1	1.4	<0.2
1288583	Soil	17	0.17	901	0.002	3	1.08	0.011	0.04	0.3	0.29	3.3	0.4	0.20	2	13.0	<0.2
1288584	Soil	11	0.05	738	0.002	<1	0.42	0.011	0.03	0.2	0.19	1.3	0.1	0.08	1	2.3	<0.2
1288585	Soil	4	0.04	351	0.003	<1	0.39	0.018	0.02	<0.1	0.03	0.4	<0.1	<0.05	1	0.6	<0.2
1288586	Soil	8	0.04	552	0.002	<1	0.43	0.012	0.03	<0.1	0.07	0.7	0.2	<0.05	2	0.7	<0.2
1288587	Soil	11	0.06	240	0.004	2	0.57	0.004	0.03	0.1	0.04	0.7	0.1	0.07	4	0.6	<0.2
1288588	Soil	16	0.14	1441	0.001	2	0.84	0.003	0.04	0.3	0.16	3.3	0.2	0.11	2	1.4	<0.2
1288589	Soil	5	0.02	180	0.002	1	0.28	0.006	0.02	<0.1	0.03	0.4	0.1	<0.05	2	0.8	<0.2
1288590	Soil	11	0.09	297	0.007	<1	0.86	0.003	0.03	0.2	0.03	0.9	0.2	<0.05	5	<0.5	<0.2
1288591	Soil	17	0.67	754	0.002	6	0.35	0.004	0.07	0.1	0.43	2.5	1.0	0.14	1	2.9	<0.2
1288592	Soil	20	0.85	1054	0.002	8	0.35	0.005	0.09	0.1	0.52	2.6	1.2	0.14	1	4.0	<0.2
1288593	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1288594	Soil	15	0.30	775	0.001	5	0.53	0.006	0.06	0.3	0.28	2.7	0.6	0.18	1	2.3	<0.2
1288595	Soil	15	0.15	813	0.002	4	0.55	0.006	0.05	<0.1	0.18	2.7	0.5	0.21	2	1.8	<0.2
1288596	Soil	14	0.15	848	0.001	4	0.64	0.006	0.05	<0.1	0.20	2.7	0.4	0.20	2	2.1	<0.2
1288597	Soil	12	0.13	736	0.005	5	0.48	0.014	0.04	0.1	0.11	1.2	0.2	0.34	1	1.8	<0.2
1288598	Soil	20	0.21	921	0.004	3	0.67	0.006	0.05	<0.1	0.19	2.7	0.4	0.15	2	1.6	<0.2
1288599	Soil	19	0.19	1691	0.002	2	0.77	0.005	0.05	0.1	0.19	3.2	0.2	0.13	2	1.4	<0.2
1288600	Soil	8	0.07	470	0.005	2	0.25	0.025	0.02	<0.1	0.04	0.5	<0.1	0.15	<1	0.7	<0.2
1288781	Soil	102	0.36	2285	0.002	6	0.98	0.007	0.11	<0.1	0.17	14.3	0.1	0.18	3	<0.5	<0.2
1288782	Soil	544	3.22	2539	0.041	3	3.04	0.005	0.03	0.3	0.06	13.0	0.2	0.09	14	<0.5	<0.2
1288783	Soil	141	0.96	1297	0.006	3	1.49	0.013	0.06	0.2	0.05	9.3	<0.1	0.16	5	<0.5	<0.2
1288784	Soil	150	1.25	5064	0.017	4	1.71	0.013	0.04	0.2	0.04	7.3	<0.1	0.26	5	<0.5	<0.2
1288785	Soil	242	2.32	2273	0.007	4	2.45	0.010	0.04	0.2	0.04	10.1	0.1	0.14	8	<0.5	<0.2
1288786	Soil	221	1.89	2083	0.003	5	2.02	0.005	0.08	0.2	0.07	15.0	0.1	0.12	7	<0.5	<0.2
1288787	Soil	97	2.17	1135	0.003	8	0.81	0.006	0.12	0.3	0.74	8.5	2.1	0.10	2	6.2	<0.2
1288788	Soil	43	0.20	562	0.003	4	0.71	0.015	0.10	0.2	0.18	2.7	1.3	0.13	2	4.1	<0.2
1288789	Soil	35	0.20	432	0.002	3	0.73	0.006	0.10	0.2	0.09	1.2	1.5	0.08	2	3.5	<0.2
1288790	Soil	25	0.20	311	0.004	5	0.88	0.006	0.08	0.2	0.02	0.9	2.0	0.09	3	2.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288861	Soil	4.2	30.5	10.0	52	0.9	38.4	9.1	217	2.32	11.8	2.7	0.9	59	0.2	1.3	0.2	23	0.94	0.078	9
1288862	Soil	19.8	60.6	36.9	104	0.7	85.4	19.4	512	5.39	50.1	4.7	1.6	25	0.2	6.1	0.3	20	0.23	0.069	11
1288863	Soil	3.6	26.7	11.0	82	0.2	26.3	6.7	93	2.07	15.5	1.1	0.2	8	<0.1	2.0	0.2	31	0.03	0.071	7
1288864	Soil	3.5	44.0	20.3	139	1.7	34.3	5.4	61	2.49	9.0	2.3	0.9	71	0.2	1.7	0.2	24	0.08	0.192	6
1288865	Soil	2.9	17.5	6.0	49	0.5	17.1	3.5	43	1.02	7.3	0.7	0.1	16	0.1	1.0	<0.1	23	0.06	0.065	6
1288866	Soil	3.5	12.7	6.2	38	0.2	11.2	2.7	33	0.85	6.3	1.6	0.1	9	0.1	0.9	<0.1	27	0.02	0.063	6
1288867	Soil	2.8	11.1	5.0	33	0.1	11.9	2.3	30	0.76	4.5	0.8	<0.1	7	0.2	0.8	<0.1	19	0.03	0.089	3
1288868	Soil	49.4	56.9	13.8	677	0.6	154.6	9.1	206	1.88	26.5	<0.5	1.2	148	5.8	9.2	<0.1	199	5.28	0.131	7
1288869	Soil	8.1	22.9	19.7	103	0.4	33.1	3.7	60	1.09	7.7	1.2	0.2	71	1.1	1.9	0.2	61	0.25	0.139	10
1288870	Soil	7.6	31.6	13.1	104	1.8	33.9	5.0	77	1.80	14.7	2.4	0.2	18	0.3	2.7	0.2	35	0.05	0.148	6
1288871	Soil	53.2	61.7	18.5	553	0.6	137.4	10.1	217	2.36	29.9	1.6	1.0	51	4.9	8.1	0.1	114	1.48	0.118	5
1288872	Soil	49.8	55.0	16.0	897	0.3	144.6	6.3	168	1.93	17.0	1.4	0.7	43	4.9	4.1	0.1	56	0.66	0.097	10
1288873	Soil	25.0	29.7	9.6	191	0.2	80.1	4.4	123	1.16	9.4	1.1	0.6	56	1.3	3.1	<0.1	34	1.10	0.078	5
1288874	Soil	41.0	20.2	8.9	95	<0.1	79.0	5.3	72	1.69	12.2	1.4	0.6	8	0.3	2.6	0.1	56	0.09	0.053	4
1288875	Soil	8.5	8.0	5.9	51	0.5	16.8	1.5	28	0.57	5.3	0.7	<0.1	8	0.3	1.2	<0.1	42	0.04	0.064	3
1288876	Soil	5.1	7.2	3.6	29	1.4	10.9	0.7	11	0.42	2.8	1.1	<0.1	11	0.4	0.9	<0.1	35	0.04	0.055	1
1288877	Soil	17.8	23.6	14.3	123	0.2	32.3	4.7	74	1.56	12.6	0.6	0.1	14	0.3	2.8	0.2	78	0.04	0.063	5
1288878	Soil	6.2	20.6	11.7	90	0.2	18.5	4.2	58	1.36	8.1	1.9	<0.1	9	0.1	1.6	0.2	43	0.01	0.056	2
1288879	Soil	1.5	6.2	2.3	20	0.1	5.0	1.1	21	0.47	1.9	1.3	<0.1	5	<0.1	0.4	<0.1	14	0.02	0.033	1
1288880	Soil	2.9	29.8	7.7	69	0.1	24.1	7.4	293	2.87	14.0	1.3	0.3	5	<0.1	1.6	0.3	29	0.01	0.068	17
1288881	Soil	2.7	97.8	28.1	122	1.1	80.7	37.8	1584	7.74	14.9	7.6	4.8	15	<0.1	1.8	0.6	13	0.12	0.077	40
1288882	Soil	4.6	71.1	30.1	114	0.6	85.3	33.4	1066	6.81	27.0	7.0	3.0	14	0.2	3.1	0.4	19	0.09	0.079	21
1288883	Soil	11.0	102.1	48.0	407	0.3	158.5	29.9	807	6.83	52.0	4.8	4.0	38	0.5	6.9	0.5	31	0.35	0.263	21
1288884	Soil	1.8	15.8	4.8	54	0.2	21.7	4.2	74	1.08	10.0	0.7	<0.1	4	<0.1	0.8	0.1	14	0.03	0.031	6
1288885	Soil	5.4	57.4	10.3	113	<0.1	63.4	16.4	356	5.34	88.7	3.8	1.3	4	<0.1	3.4	0.4	35	0.02	0.081	18
1288886	Soil	4.9	47.7	8.5	83	<0.1	46.0	12.0	284	3.81	105.3	0.7	0.3	4	<0.1	2.9	0.3	41	0.02	0.066	17
1288887	Soil	10.6	51.1	31.2	152	0.2	67.9	16.7	559	4.82	58.6	2.7	2.4	10	0.2	3.8	0.4	22	0.06	0.081	12
1288888	Soil	20.7	25.0	11.1	462	0.3	56.0	4.7	71	1.69	24.8	1.0	0.3	6	0.9	10.4	0.2	101	0.03	0.057	6
1288889	Soil	24.3	27.2	12.3	373	0.3	53.7	4.2	32	1.41	23.9	1.4	0.4	5	0.4	8.3	0.2	122	0.01	0.040	7
1288890	Soil	59.1	94.8	19.7	895	0.4	169.0	11.9	332	3.10	30.2	2.3	2.2	61	14.5	7.8	0.2	69	1.44	0.145	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288861	Soil	19	0.15	1877	0.006	5	0.49	0.013	0.10	<0.1	0.16	2.9	0.1	0.21	1	<0.5	<0.2
1288862	Soil	7	0.06	1009	0.001	2	0.31	0.003	0.11	<0.1	0.26	5.2	0.3	<0.05	<1	0.7	<0.2
1288863	Soil	12	0.04	432	0.002	2	0.63	0.006	0.06	<0.1	0.03	0.6	0.1	<0.05	3	0.8	<0.2
1288864	Soil	9	0.02	2157	0.002	2	0.65	0.006	0.07	<0.1	0.22	1.6	0.1	0.09	2	3.0	<0.2
1288865	Soil	11	0.03	888	0.002	3	0.32	0.011	0.06	<0.1	0.07	0.3	0.1	0.06	2	0.7	<0.2
1288866	Soil	8	0.03	326	0.002	3	0.30	0.010	0.05	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2
1288867	Soil	7	0.02	389	<0.001	2	0.29	0.012	0.04	<0.1	0.05	0.3	<0.1	<0.05	1	<0.5	<0.2
1288868	Soil	21	2.08	410	0.001	8	0.27	0.006	0.09	0.1	0.41	2.9	0.9	0.12	<1	3.6	<0.2
1288869	Soil	19	0.10	825	0.003	5	0.39	0.011	0.08	<0.1	0.06	0.8	0.2	0.22	2	1.2	<0.2
1288870	Soil	9	0.02	421	0.001	2	0.27	0.009	0.05	<0.1	0.17	0.7	0.2	<0.05	1	1.1	<0.2
1288871	Soil	17	0.55	551	0.001	4	0.32	0.003	0.05	0.1	0.45	3.2	0.6	0.09	<1	2.6	<0.2
1288872	Soil	13	0.07	211	0.003	2	0.47	0.013	0.04	0.2	0.35	2.5	0.7	0.10	1	1.4	<0.2
1288873	Soil	11	0.10	178	0.005	3	0.44	0.015	0.02	0.2	0.15	1.1	0.3	<0.05	1	1.5	<0.2
1288874	Soil	10	0.03	163	0.004	2	0.30	0.007	0.03	0.1	0.06	1.3	0.4	<0.05	1	0.8	<0.2
1288875	Soil	12	0.03	74	0.002	2	0.31	0.011	0.04	<0.1	0.05	0.1	0.3	<0.05	2	0.7	<0.2
1288876	Soil	6	0.02	113	0.002	1	0.23	0.017	0.03	<0.1	0.20	0.2	0.4	<0.05	<1	0.8	<0.2
1288877	Soil	14	0.04	81	0.002	3	0.36	0.005	0.05	<0.1	0.04	0.3	0.4	<0.05	3	1.4	<0.2
1288878	Soil	8	0.02	39	0.002	1	0.26	0.008	0.03	<0.1	0.02	0.3	0.2	<0.05	2	0.7	<0.2
1288879	Soil	5	0.01	20	0.003	1	0.19	0.013	0.02	<0.1	0.03	0.2	<0.1	<0.05	<1	<0.5	<0.2
1288880	Soil	8	0.03	80	0.003	1	0.49	0.009	0.05	<0.1	0.03	0.5	0.1	<0.05	2	0.7	<0.2
1288881	Soil	9	0.11	399	0.002	2	0.60	0.002	0.07	<0.1	0.13	6.9	0.2	<0.05	<1	1.3	0.2
1288882	Soil	19	0.10	568	0.005	3	0.59	0.004	0.11	0.1	0.06	5.2	0.2	<0.05	2	2.3	<0.2
1288883	Soil	17	0.04	490	0.003	3	0.39	0.002	0.08	<0.1	0.11	5.5	0.2	<0.05	<1	3.3	0.2
1288884	Soil	7	0.02	43	0.003	1	0.17	0.010	0.03	<0.1	0.02	0.3	<0.1	<0.05	1	<0.5	<0.2
1288885	Soil	9	0.04	118	0.005	3	0.43	0.004	0.06	<0.1	0.02	2.1	0.1	<0.05	2	1.6	<0.2
1288886	Soil	9	0.03	84	0.003	3	0.32	0.005	0.05	<0.1	0.02	0.7	0.1	<0.05	2	1.4	<0.2
1288887	Soil	9	0.05	352	0.002	2	0.40	0.003	0.09	<0.1	0.08	3.3	0.2	<0.05	1	1.3	<0.2
1288888	Soil	11	0.02	133	0.002	<1	0.27	0.004	0.04	<0.1	0.18	0.4	0.2	<0.05	1	5.3	<0.2
1288889	Soil	10	0.02	71	0.001	2	0.32	0.002	0.04	0.1	0.11	0.4	0.3	<0.05	2	2.7	<0.2
1288890	Soil	19	0.59	584	0.003	3	0.42	0.003	0.06	0.1	0.41	4.4	0.9	<0.05	<1	3.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288391	Soil		70.6	49.7	14.1	390	0.3	165.9	8.3	183	2.34	52.4	0.8	3.4	183	2.3	5.5	0.1	62	7.78	0.072	8
1288392	Soil		16.7	22.7	6.5	98	0.2	31.8	3.0	42	0.80	10.6	1.3	0.5	10	1.4	2.9	0.1	67	0.09	0.039	4
1288393	Soil		7.7	122.9	44.4	401	2.7	101.6	42.8	1226	6.05	40.3	5.2	1.5	35	1.0	5.7	0.6	45	0.39	0.140	4
1288394	Soil		7.8	158.0	49.9	526	2.1	115.8	43.5	1585	6.21	88.2	4.6	1.1	39	4.0	4.5	0.5	53	0.26	0.131	4
1288395	Soil		8.7	156.6	46.0	568	1.6	155.6	64.5	2161	6.11	93.8	3.8	1.3	65	1.4	4.9	0.5	42	0.42	0.114	3
1288396	Soil		9.7	190.2	53.4	345	1.9	95.4	17.9	403	4.53	62.0	5.2	1.7	72	1.1	8.4	0.7	39	0.53	0.118	4
1288397	Soil		5.7	78.7	26.4	245	0.8	56.2	17.4	775	3.98	178.4	1.8	0.4	22	1.2	3.0	0.4	48	0.23	0.105	4
1288398	Soil		4.4	55.4	20.6	221	0.3	42.0	10.7	384	3.92	102.0	2.6	0.2	9	0.3	1.9	0.5	47	0.02	0.106	4
1288399	Soil		16.0	139.0	18.6	181	0.2	410.6	86.4	800	6.99	40.9	2.0	6.1	54	0.7	1.0	<0.1	94	0.65	0.240	67
1288400	Soil		11.8	137.2	16.3	153	0.2	439.0	92.1	816	6.83	37.8	2.1	6.2	59	0.5	0.8	<0.1	78	0.82	0.217	63
1288401	Soil		25.5	166.6	20.6	209	0.3	576.1	120.9	874	8.40	57.5	2.1	7.9	78	0.7	1.4	<0.1	79	1.45	0.253	59
1288402	Soil		8.8	155.4	14.5	205	0.2	501.7	108.5	851	8.29	81.0	2.4	5.2	87	0.6	1.3	<0.1	78	1.91	0.266	68
1288403	Soil		5.7	154.0	14.8	201	0.1	477.0	117.5	1285	8.50	32.6	2.9	6.9	101	0.5	0.7	<0.1	74	2.24	0.285	66
1288404	Soil		1.5	99.6	6.8	135	<0.1	186.2	45.8	1994	5.15	5.0	1.0	2.1	38	0.5	0.4	0.1	194	0.79	0.227	92
1288405	Soil		3.9	118.8	15.5	138	0.1	357.8	71.5	884	8.97	23.9	2.8	4.7	87	0.5	0.7	<0.1	194	1.55	0.291	76
1288406	Soil		4.0	106.4	15.0	129	0.2	291.5	60.3	1376	8.05	14.5	0.9	5.2	77	0.6	1.1	<0.1	163	1.42	0.279	89
1288407	Soil		1.4	40.7	7.5	65	<0.1	149.6	23.1	401	3.77	7.0	<0.5	1.6	34	0.2	0.4	<0.1	69	0.74	0.165	38
1288408	Soil		4.6	89.7	30.1	91	0.2	393.5	71.4	1030	10.08	16.0	3.1	7.1	83	0.4	0.9	<0.1	87	1.67	0.316	59
1288409	Soil		26.9	27.9	7.3	271	0.2	117.0	12.8	194	2.93	25.0	13.4	0.3	19	1.9	13.7	0.1	259	0.24	0.175	13
1288410	Soil		52.1	77.7	17.4	1344	0.5	343.3	35.1	586	6.45	56.2	5.2	2.9	46	8.7	20.0	0.2	342	0.54	0.279	38
1288411	Soil		31.6	160.9	16.9	1702	2.5	423.2	15.5	461	6.12	63.1	9.2	2.7	206	15.5	20.2	0.2	362	2.96	1.234	45
1288412	Soil		97.0	109.0	15.5	1163	1.9	321.1	18.8	393	3.67	60.7	4.4	1.3	63	15.8	21.1	0.2	759	0.74	0.243	35
1288413	Soil		43.5	75.4	12.3	751	0.6	248.7	30.2	650	5.10	73.5	1.8	1.9	72	7.0	12.1	0.1	377	0.91	0.245	42
1288414	Soil		23.5	94.1	13.0	442	0.5	370.8	55.3	1412	8.40	86.3	1.9	4.8	64	3.8	5.8	<0.1	244	1.16	0.264	59
1288415	Soil		47.8	85.5	14.0	780	0.5	272.5	32.2	656	5.26	82.0	3.4	3.1	67	7.7	12.9	0.1	462	0.78	0.289	53
1288416	Soil		44.7	94.5	13.9	686	0.5	360.9	50.4	1664	8.73	86.4	3.3	4.4	69	8.0	10.7	0.1	326	0.96	0.298	64
1288417	Soil		12.3	89.0	24.4	332	1.8	85.9	7.3	107	2.68	33.2	4.1	1.5	56	2.2	5.6	0.2	71	0.16	0.219	14
1288418	Soil		14.4	45.6	25.0	284	1.0	66.6	6.9	79	2.35	28.0	1.6	0.4	38	0.6	4.3	0.2	96	0.03	0.119	8
1288419	Soil		11.1	27.2	20.2	137	0.6	36.2	4.2	68	1.60	17.6	2.8	0.1	31	0.5	3.0	0.2	73	0.05	0.099	11
1288420	Soil		10.7	30.8	9.6	150	0.3	32.4	4.0	41	1.34	15.5	1.7	0.2	8	1.0	2.7	0.1	87	0.01	0.050	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288391	Soil	14	2.96	512	0.003	4	0.18	0.006	0.05	0.1	0.64	3.4	1.8	<0.05	<1	1.6	<0.2
1288392	Soil	9	0.02	413	0.003	2	0.28	0.008	0.03	<0.1	0.08	1.0	0.2	<0.05	1	1.2	<0.2
1288393	Soil	14	0.12	852	0.002	2	0.31	0.003	0.07	<0.1	0.20	8.8	0.6	<0.05	<1	4.0	<0.2
1288394	Soil	15	0.07	1077	0.002	2	0.45	0.002	0.07	<0.1	0.17	7.5	0.5	<0.05	1	3.2	<0.2
1288395	Soil	12	0.07	980	0.001	1	0.39	0.003	0.08	<0.1	0.16	5.8	0.4	<0.05	1	2.7	<0.2
1288396	Soil	16	0.09	515	0.001	2	0.44	0.003	0.11	<0.1	0.18	4.6	0.3	0.09	1	3.7	0.3
1288397	Soil	15	0.06	295	0.003	3	0.44	0.004	0.06	<0.1	0.14	3.4	0.2	<0.05	2	1.9	<0.2
1288398	Soil	15	0.04	84	0.003	<1	0.51	0.004	0.04	<0.1	0.06	1.8	0.2	<0.05	2	1.4	<0.2
1288399	Soil	163	0.70	1586	0.005	6	1.65	0.009	0.13	<0.1	0.09	17.8	0.2	0.10	4	1.3	<0.2
1288400	Soil	144	0.52	1154	0.007	8	1.48	0.012	0.14	<0.1	0.09	16.6	0.2	0.16	3	1.8	<0.2
1288401	Soil	140	0.63	163	0.007	9	1.22	0.009	0.25	<0.1	0.12	18.0	0.4	0.42	3	1.9	<0.2
1288402	Soil	123	0.50	900	0.006	10	1.00	0.006	0.16	<0.1	0.10	20.2	0.1	0.19	2	1.4	<0.2
1288403	Soil	142	0.62	746	0.007	10	1.26	0.011	0.14	<0.1	0.09	21.2	0.2	0.19	3	1.3	<0.2
1288404	Soil	412	0.85	4422	0.012	4	2.07	0.008	0.05	<0.1	0.05	20.5	<0.1	0.05	8	0.7	<0.2
1288405	Soil	354	2.82	2955	0.014	5	2.83	0.008	0.06	<0.1	0.08	19.1	0.1	<0.05	11	1.4	<0.2
1288406	Soil	291	1.67	2601	0.013	6	2.08	0.005	0.08	0.1	0.08	20.4	0.1	<0.05	8	1.0	<0.2
1288407	Soil	126	0.50	1981	0.007	3	1.35	0.018	0.04	0.1	0.04	7.3	<0.1	<0.05	4	0.8	<0.2
1288408	Soil	146	0.65	3701	0.009	5	1.05	0.005	0.09	0.2	0.12	15.7	<0.1	<0.05	4	1.3	<0.2
1288409	Soil	49	0.10	873	0.006	6	0.68	0.014	0.06	0.2	<0.01	1.3	1.0	0.10	3	4.6	<0.2
1288410	Soil	94	0.24	4246	0.005	7	1.10	0.005	0.10	0.2	0.07	8.2	1.2	<0.05	4	11.5	<0.2
1288411	Soil	220	0.18	4707	0.015	13	1.39	0.006	0.19	0.3	0.74	8.5	1.0	<0.05	4	18.6	<0.2
1288412	Soil	104	0.32	2590	0.007	7	1.25	0.007	0.15	0.2	0.55	4.6	1.3	<0.05	3	10.5	<0.2
1288413	Soil	119	0.63	2358	0.009	8	1.36	0.010	0.12	0.2	0.19	6.4	1.1	<0.05	4	4.9	<0.2
1288414	Soil	153	0.56	3880	0.005	7	1.37	0.006	0.10	0.2	0.17	18.7	0.5	0.07	4	2.9	<0.2
1288415	Soil	130	0.57	3536	0.007	9	1.46	0.006	0.12	0.3	0.16	8.3	1.1	<0.05	5	5.8	<0.2
1288416	Soil	135	0.51	3541	0.006	10	1.23	0.007	0.11	0.2	0.18	16.5	0.9	0.06	4	4.7	<0.2
1288417	Soil	25	0.07	382	0.003	4	0.47	0.003	0.09	<0.1	0.37	3.0	0.5	0.05	1	2.4	<0.2
1288418	Soil	18	0.04	164	0.004	3	0.49	0.006	0.06	0.1	0.05	1.0	0.4	0.06	3	1.8	<0.2
1288419	Soil	20	0.06	229	0.004	2	0.46	0.004	0.07	0.1	0.12	0.3	0.5	0.07	3	1.6	<0.2
1288420	Soil	15	0.03	266	0.003	2	0.39	0.003	0.05	0.1	0.04	0.5	0.2	<0.05	3	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288201	Soil		77.7	72.7	10.6	292	0.3	192.1	9.3	201	2.04	55.3	0.6	2.1	134	2.8	9.6	<0.1	91	5.60	0.107	10
1288202	Soil		85.3	102.6	16.3	1223	0.9	210.5	7.3	191	1.89	82.0	2.4	1.1	60	13.0	21.0	0.2	663	1.69	0.083	20
1288203	Soil		101.1	144.4	17.5	1768	2.1	283.6	7.5	165	1.54	82.9	2.0	1.4	208	18.1	33.4	0.1	867	7.27	0.119	18
1288204	Soil		129.7	170.7	21.3	2262	2.3	357.2	9.3	183	1.91	93.4	3.0	1.9	174	17.1	38.4	0.2	773	5.83	0.108	17
1288205	Soil		143.0	155.6	18.6	1802	2.0	326.8	6.7	141	1.47	99.4	1.6	2.9	323	21.5	44.1	0.1	1009	12.61	0.112	16
1288206	Soil		151.6	149.8	18.1	1748	2.5	333.2	6.8	157	1.44	106.1	2.4	3.1	313	20.2	42.7	0.2	1129	12.91	0.123	17
1288207	Soil		142.8	153.8	20.8	1944	3.0	320.1	7.3	196	1.39	111.8	0.7	2.7	309	21.7	44.2	0.2	1215	11.91	0.137	19
1288208	Soil		150.1	143.8	19.0	1822	2.5	302.9	5.3	152	1.30	120.5	2.5	2.8	364	24.8	46.0	0.1	975	14.03	0.141	17
1288209	Soil		132.7	131.7	16.1	1443	2.8	300.0	5.2	154	1.17	86.0	<0.5	2.3	302	18.6	36.1	0.1	944	11.87	0.111	14
1288210	Soil		132.9	135.2	15.6	1460	2.7	302.3	5.2	176	1.21	83.1	3.4	2.2	319	19.2	35.0	0.1	1074	12.16	0.114	16
1288211	Soil		159.4	172.5	21.4	1961	2.6	343.1	6.3	154	1.63	153.0	3.1	3.3	258	21.6	51.5	0.2	958	9.31	0.149	19
1288212	Soil		144.8	154.1	18.6	1633	2.8	292.9	6.0	159	1.48	124.7	1.4	2.6	236	22.2	38.6	0.2	647	9.37	0.125	17
1288213	Soil		23.9	139.7	26.3	1016	0.9	524.1	73.2	1136	8.54	222.3	6.8	7.7	146	14.3	12.2	0.2	304	1.97	0.498	88
1288214	Soil		39.6	128.8	27.4	1178	1.2	446.5	54.3	864	6.60	126.5	4.1	6.4	135	16.4	13.6	0.2	447	2.30	0.426	65
1288215	Soil		120.6	87.5	24.5	933	1.3	371.1	24.1	400	3.80	77.8	2.0	4.9	100	8.0	16.5	0.2	378	1.66	0.161	25
1288216	Soil		12.8	158.4	28.8	75	0.4	846.3	148.6	1289	11.63	250.0	4.3	18.1	218	0.6	4.7	<0.1	127	4.06	0.650	93
1288217	Soil		23.2	126.3	18.8	81	0.4	767.5	104.6	1089	9.05	22.2	1.3	18.5	264	0.7	1.9	0.2	126	4.45	0.788	104
1288218	Soil		17.8	131.8	60.3	73	0.5	834.4	117.7	1284	13.75	71.4	2.7	23.1	315	0.5	3.7	<0.1	87	8.45	0.725	77
1288219	Soil		21.4	132.8	43.4	914	0.8	838.5	122.3	1436	11.96	64.3	2.8	15.5	346	9.8	2.2	<0.1	96	7.84	0.560	49
1288220	Soil		12.1	148.8	58.9	1802	0.7	855.3	123.2	1021	11.13	65.5	2.8	14.6	188	25.6	2.9	<0.1	89	4.36	0.648	71
1288221	Soil		5.2	156.2	55.1	561	0.9	828.0	127.3	1244	11.88	92.7	4.3	21.1	224	5.5	3.0	<0.1	121	3.40	0.821	89
1288222	Soil		6.8	155.6	55.0	784	0.9	824.0	120.1	1341	12.00	120.0	4.9	18.6	205	7.4	3.9	<0.1	135	3.18	0.750	92
1288223	Soil		20.2	126.3	47.8	850	1.1	735.0	106.0	923	10.06	361.0	5.4	17.1	264	5.2	15.2	<0.1	155	3.54	0.683	84
1288224	Soil		19.8	133.7	57.5	773	1.1	809.0	110.3	1257	11.79	258.7	3.7	15.2	156	9.1	10.9	<0.1	164	2.29	0.674	81
1288225	Soil		19.0	134.9	50.1	810	1.0	796.8	101.4	1279	10.69	194.4	5.2	16.0	183	8.9	7.8	0.2	161	2.93	0.707	87
1288226	Soil		14.2	130.5	45.7	759	0.8	738.4	101.7	1247	10.15	130.1	6.1	17.6	246	8.2	5.2	0.2	130	4.74	0.718	79
1288227	Soil		18.4	119.7	38.7	514	1.0	626.8	76.9	1008	8.30	389.2	4.1	11.8	175	4.1	12.5	0.5	187	2.05	0.551	81
1288228	Soil		16.2	127.9	29.5	444	0.9	628.3	82.0	1335	9.29	790.2	7.0	15.1	171	3.9	13.2	0.2	200	2.10	0.631	79
1288229	Soil		22.1	98.9	23.5	621	1.3	355.2	42.8	743	5.72	225.8	4.9	6.9	101	6.8	11.0	0.2	187	1.26	0.340	45
1288230	Soil		16.3	89.0	21.7	508	1.0	291.8	34.4	563	4.79	170.3	3.3	7.4	120	4.4	8.5	0.2	123	2.14	0.307	39

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288201	Soil	19	2.34	326	0.003	5	0.26	0.005	0.07	0.2	0.73	3.1	1.1	<0.05	<1	2.2	<0.2
1288202	Soil	40	0.42	397	0.005	7	0.55	0.004	0.12	0.3	0.63	3.1	2.3	<0.05	2	4.4	<0.2
1288203	Soil	49	1.45	384	0.007	9	0.59	0.009	0.16	0.4	0.62	2.8	3.6	<0.05	2	5.7	<0.2
1288204	Soil	45	1.31	343	0.006	8	0.56	0.006	0.14	0.5	0.69	3.6	4.6	<0.05	2	7.5	0.3
1288205	Soil	51	1.68	300	0.008	9	0.46	0.007	0.15	0.4	0.81	3.0	4.9	<0.05	2	10.0	<0.2
1288206	Soil	57	1.98	323	0.009	12	0.58	0.008	0.18	0.4	0.61	3.1	5.1	<0.05	2	10.5	<0.2
1288207	Soil	65	1.73	337	0.010	14	0.59	0.007	0.19	0.5	0.56	3.2	5.0	<0.05	2	9.2	<0.2
1288208	Soil	49	1.99	361	0.008	10	0.44	0.006	0.14	0.5	0.48	2.7	4.0	<0.05	1	7.9	<0.2
1288209	Soil	50	1.50	435	0.008	11	0.45	0.006	0.15	0.4	0.86	2.6	3.4	<0.05	2	7.9	0.4
1288210	Soil	55	1.48	431	0.010	13	0.55	0.007	0.18	0.4	1.06	2.8	3.5	<0.05	2	7.5	0.2
1288211	Soil	52	1.65	508	0.008	12	0.53	0.006	0.17	0.5	1.47	3.4	4.1	<0.05	2	9.0	0.3
1288212	Soil	36	2.00	390	0.006	9	0.43	0.006	0.12	0.4	1.00	3.1	2.9	<0.05	1	10.5	0.3
1288213	Soil	178	0.46	3673	0.008	16	1.11	0.006	0.13	0.3	1.90	19.3	0.5	0.10	3	5.3	<0.2
1288214	Soil	150	0.68	3267	0.015	12	1.03	0.006	0.13	0.4	1.08	13.8	0.8	0.07	3	4.2	<0.2
1288215	Soil	42	0.57	1419	0.003	9	0.50	0.006	0.12	0.9	1.07	6.0	2.0	0.09	1	8.1	0.2
1288216	Soil	213	0.54	1571	0.008	21	0.95	0.008	0.22	0.2	2.96	25.4	0.4	0.24	3	1.5	<0.2
1288217	Soil	221	0.30	1471	0.005	29	1.24	0.008	0.30	0.2	0.82	22.8	0.5	0.18	4	1.1	<0.2
1288218	Soil	189	0.25	1400	0.008	19	0.78	0.007	0.22	0.2	1.13	22.9	0.5	0.23	3	0.8	<0.2
1288219	Soil	159	1.40	3165	0.007	15	0.87	0.009	0.18	0.2	1.02	20.4	0.9	0.14	2	2.8	<0.2
1288220	Soil	156	0.52	727	0.007	21	0.81	0.007	0.19	0.2	0.87	18.8	0.4	0.31	3	1.7	<0.2
1288221	Soil	223	0.59	1445	0.008	24	0.99	0.007	0.22	0.1	0.62	26.5	0.4	0.22	3	0.7	<0.2
1288222	Soil	228	0.74	2218	0.006	26	1.00	0.007	0.21	0.1	0.65	27.7	0.4	0.21	3	2.0	<0.2
1288223	Soil	170	1.01	3370	0.007	16	1.02	0.008	0.18	0.2	1.37	24.4	0.8	0.30	2	5.3	<0.2
1288224	Soil	161	0.30	1002	0.007	20	1.07	0.008	0.17	0.2	1.00	20.5	0.8	0.26	3	4.9	<0.2
1288225	Soil	190	0.66	527	0.006	29	1.23	0.010	0.23	0.1	1.00	21.9	0.8	0.29	3	4.4	<0.2
1288226	Soil	184	1.26	219	0.006	26	1.01	0.010	0.23	0.2	0.73	21.8	0.6	0.50	3	2.0	<0.2
1288227	Soil	167	0.50	6156	0.007	19	1.34	0.010	0.19	0.2	1.45	19.5	0.8	0.14	3	5.5	<0.2
1288228	Soil	197	0.64	3736	0.004	17	1.47	0.008	0.17	0.1	1.47	25.1	0.6	0.07	3	2.4	<0.2
1288229	Soil	88	0.37	3488	0.004	8	0.88	0.008	0.13	0.1	2.40	11.7	0.5	<0.05	2	2.8	0.2
1288230	Soil	66	0.85	2455	0.003	13	0.70	0.006	0.15	<0.1	1.30	9.4	0.4	0.06	2	2.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288231	Soil	21.3	86.1	18.1	471	0.9	218.5	30.3	470	4.81	127.9	2.5	3.0	48	2.8	7.4	0.2	143	0.35	0.229	38
1288232	Soil	8.7	41.1	9.3	161	0.4	78.5	12.0	120	2.96	54.8	1.6	0.3	10	0.3	3.3	0.2	64	0.05	0.104	18
1288233	Soil	12.0	59.9	20.6	260	0.8	81.0	13.9	260	3.94	47.0	4.2	1.6	17	0.6	3.7	0.3	49	0.11	0.146	20
1288234	Soil	3.7	44.6	11.1	120	0.5	39.5	11.5	295	3.24	31.0	3.6	0.6	12	0.1	1.8	0.2	27	0.04	0.097	12
1288235	Soil	5.9	71.8	17.9	231	0.7	66.6	18.1	382	5.04	42.6	3.8	1.6	13	0.3	2.9	0.3	47	0.06	0.134	22
1288236	Soil	8.9	64.4	21.7	247	2.2	74.4	14.6	367	3.50	23.2	2.2	2.7	30	0.7	3.6	0.3	35	0.14	0.126	18
1288237	Soil	15.7	28.4	9.8	182	0.8	43.3	4.5	52	1.86	26.3	2.7	0.4	11	0.5	4.1	0.2	91	0.06	0.112	11
1288238	Soil	63.8	79.8	14.8	507	0.4	183.2	15.6	428	2.95	37.3	1.8	0.6	23	5.9	4.5	0.1	93	0.37	0.149	13
1288239	Soil	44.3	63.8	16.1	613	0.4	124.2	10.0	218	3.60	91.1	7.0	0.7	46	2.7	11.9	0.2	516	0.31	0.249	16
1288240	Soil	40.1	31.8	7.7	419	0.2	78.3	4.2	72	1.52	37.1	3.2	0.2	14	3.5	7.9	0.1	261	0.14	0.127	9
1288241	Soil	38.4	25.9	14.9	242	0.2	66.1	4.9	62	1.56	40.1	7.3	0.2	20	0.5	6.2	0.3	186	0.12	0.077	10
1288242	Soil	50.2	49.2	40.1	366	0.9	97.6	5.6	74	2.96	81.4	14.4	0.3	52	0.7	14.3	0.3	356	0.07	0.208	9
1288243	Soil	68.7	302.4	26.2	542	2.1	221.5	7.3	120	2.53	177.8	7.3	3.0	34	1.6	32.2	0.2	516	0.20	0.570	13
1288244	Soil	61.4	40.5	13.7	608	0.7	104.6	4.9	75	2.03	67.7	26.0	0.2	17	0.8	13.3	0.2	312	0.03	0.126	8
1288245	Soil	110.5	59.5	26.6	850	1.5	211.6	5.9	96	2.94	113.7	88.0	0.5	36	3.9	34.6	0.2	657	0.09	0.160	13
1288246	Soil	49.1	102.3	29.5	977	2.6	176.1	11.1	493	3.81	111.2	49.0	0.9	55	9.3	28.4	0.3	276	0.32	0.217	14
1288247	Soil	14.0	10.3	10.8	55	0.5	13.5	1.5	24	0.90	20.5	2.3	0.1	13	0.2	4.0	0.1	93	0.05	0.070	5
1288248	Soil	13.1	40.4	24.3	85	1.1	19.3	2.4	34	2.76	68.3	4.7	0.9	52	0.3	6.6	0.2	94	0.04	0.093	5
1288249	Soil	16.2	24.7	37.7	64	1.9	19.6	2.4	34	2.31	68.3	8.7	0.4	64	0.3	9.5	0.2	76	0.06	0.106	4
1288250	Soil	23.7	23.5	51.3	53	2.4	16.5	2.0	34	2.82	56.4	14.7	0.4	57	0.2	9.1	0.3	107	0.05	0.105	4
1288251	Soil	5.5	39.2	12.3	89	1.2	32.6	3.7	95	1.67	28.4	4.9	0.5	97	0.4	1.4	0.1	30	0.22	0.093	5
1288252	Soil	5.8	41.3	11.4	108	1.4	35.5	4.5	46	1.84	59.5	4.9	0.5	117	0.2	1.7	0.1	22	0.09	0.069	4
1288253	Soil	6.4	20.1	10.1	61	0.4	24.9	2.7	32	1.22	34.7	3.8	0.3	52	0.2	1.8	0.1	29	0.12	0.057	3
1288254	Soil	4.2	37.8	12.0	103	1.7	40.1	5.8	65	2.08	85.6	10.2	1.1	86	0.3	3.6	0.2	24	0.19	0.061	4
1288255	Soil	5.4	47.5	18.2	114	1.6	39.5	5.0	71	2.52	51.9	10.5	0.7	89	0.4	3.0	0.2	48	0.28	0.116	6
1288256	Soil	3.1	30.8	9.1	55	1.1	18.5	2.5	32	1.54	58.2	4.7	0.9	84	<0.1	3.3	0.1	21	0.08	0.046	3
1288257	Soil	3.6	178.3	42.2	263	2.7	61.5	8.2	136	7.48	72.3	4.8	1.6	79	0.4	1.9	0.3	58	0.03	0.166	5
1288258	Soil	3.3	46.4	22.9	130	1.7	36.0	8.4	201	3.01	42.8	7.9	1.4	53	0.3	1.6	0.2	38	0.05	0.080	6
1288259	Soil	4.7	63.8	16.5	192	2.1	74.7	11.5	131	2.96	53.4	6.1	0.9	67	0.4	1.8	0.3	27	0.06	0.077	4
1288260	Soil	8.0	31.5	20.2	53	2.1	16.3	2.0	31	1.70	48.6	8.8	0.6	38	0.1	1.8	0.2	27	0.05	0.044	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288231	Soil	60	0.08	2867	0.004	5	0.82	0.004	0.13	<0.1	1.63	5.9	0.3	<0.05	2	2.5	<0.2
1288232	Soil	22	0.04	338	0.004	2	0.68	0.010	0.06	0.1	0.36	0.7	0.2	<0.05	3	<0.5	<0.2
1288233	Soil	18	0.06	738	0.003	4	0.83	0.004	0.08	<0.1	0.96	2.1	0.3	<0.05	2	1.8	<0.2
1288234	Soil	8	0.05	1214	0.008	2	1.01	0.015	0.06	0.1	0.11	1.3	0.2	<0.05	2	1.7	<0.2
1288235	Soil	15	0.11	2448	0.009	2	1.49	0.008	0.09	0.2	0.12	2.8	0.2	0.06	3	2.6	<0.2
1288236	Soil	11	0.07	2333	0.005	3	1.04	0.006	0.11	<0.1	0.86	2.7	0.2	<0.05	2	1.7	<0.2
1288237	Soil	15	0.05	870	0.003	3	0.67	0.011	0.06	0.1	0.28	0.5	0.4	<0.05	2	1.5	<0.2
1288238	Soil	19	0.06	475	0.003	3	0.57	0.007	0.08	0.3	0.45	1.8	2.1	0.06	1	3.6	<0.2
1288239	Soil	60	0.12	961	0.005	9	1.03	0.010	0.11	0.3	0.90	1.1	1.2	0.06	4	3.5	<0.2
1288240	Soil	19	0.07	265	0.004	5	0.50	0.011	0.09	0.3	0.33	0.5	2.3	0.06	2	2.1	<0.2
1288241	Soil	29	0.07	223	0.003	3	0.44	0.004	0.06	0.2	0.49	0.3	1.0	0.15	3	2.1	<0.2
1288242	Soil	38	0.05	187	0.002	2	0.67	0.005	0.07	0.2	16.16	0.4	1.2	0.10	3	5.4	<0.2
1288243	Soil	77	0.06	378	0.003	4	3.80	0.004	0.08	0.4	15.14	5.7	1.8	0.13	3	11.5	<0.2
1288244	Soil	23	0.03	159	0.001	2	0.49	0.009	0.06	0.2	1.17	0.3	1.6	0.10	3	3.9	<0.2
1288245	Soil	49	0.07	452	0.003	3	0.62	0.006	0.10	0.6	16.59	1.2	2.8	0.15	4	8.0	0.3
1288246	Soil	27	0.06	723	0.001	3	0.61	0.007	0.10	0.3	8.83	2.2	1.7	0.13	3	10.8	0.3
1288247	Soil	13	0.03	164	0.002	1	0.28	0.011	0.05	0.1	0.52	0.1	0.5	0.10	2	2.3	<0.2
1288248	Soil	16	0.02	502	0.002	<1	0.38	0.003	0.08	0.1	0.53	1.3	0.8	0.14	3	7.3	<0.2
1288249	Soil	17	0.03	482	0.003	2	0.34	0.007	0.11	0.1	0.82	0.9	1.1	0.20	2	10.3	0.3
1288250	Soil	16	0.02	251	0.002	2	0.30	0.006	0.25	0.1	0.76	0.4	1.8	0.60	2	10.2	0.2
1288251	Soil	24	0.04	646	0.002	2	0.62	0.009	0.06	<0.1	0.42	1.9	0.2	0.07	2	3.1	<0.2
1288252	Soil	18	0.02	565	<0.001	2	0.44	0.005	0.05	<0.1	0.48	2.2	0.1	<0.05	1	4.4	<0.2
1288253	Soil	15	0.02	539	<0.001	2	0.33	0.006	0.05	<0.1	0.32	0.9	0.2	<0.05	2	1.7	<0.2
1288254	Soil	16	0.04	821	<0.001	3	0.36	0.004	0.06	<0.1	2.15	2.3	0.1	0.07	1	3.6	<0.2
1288255	Soil	30	0.07	1711	0.002	4	0.63	0.007	0.09	0.1	0.88	2.0	0.2	0.23	2	4.0	<0.2
1288256	Soil	12	0.03	1262	<0.001	2	0.36	0.003	0.06	<0.1	1.50	1.9	0.1	0.11	1	3.4	<0.2
1288257	Soil	26	0.05	782	0.001	3	1.20	0.004	0.08	<0.1	0.25	4.5	0.1	0.14	3	5.5	<0.2
1288258	Soil	19	0.07	576	0.002	2	0.67	0.004	0.08	<0.1	0.20	2.3	0.1	0.07	2	2.3	<0.2
1288259	Soil	17	0.03	1211	<0.001	2	0.49	0.004	0.08	<0.1	0.34	3.0	0.2	0.12	1	3.6	<0.2
1288260	Soil	18	0.01	1230	<0.001	4	0.30	0.003	0.06	<0.1	0.67	2.3	<0.1	0.12	2	5.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281231	Soil	0.3	7.9	2.7	10	0.1	2.7	0.5	12	0.28	3.2	<0.5	<0.1	5	<0.1	0.1	<0.1	7	0.04	0.023	1
1281232	Soil	7.1	131.8	22.7	665	0.9	100.0	12.8	110	2.12	89.0	6.2	0.3	14	0.7	2.6	0.3	81	0.10	0.085	9
1281233	Soil	10.8	219.6	76.0	999	1.7	165.7	40.3	506	4.26	478.8	27.3	2.6	33	2.6	8.3	0.6	139	0.31	0.156	15
1281234	Soil	0.6	6.9	1.8	20	0.2	3.5	0.6	12	0.23	14.5	<0.5	<0.1	4	<0.1	0.3	<0.1	8	0.03	0.024	<1
1281235	Soil	1.5	13.4	4.4	39	0.5	8.6	1.3	23	0.46	27.3	3.0	<0.1	6	0.2	0.7	<0.1	18	0.09	0.034	2
1281236	Soil	7.1	104.7	23.4	861	0.6	78.2	16.3	262	2.53	289.5	10.4	1.1	10	1.0	3.6	0.3	183	0.19	0.100	9
1281237	Soil	8.5	67.1	14.6	397	1.3	48.5	7.6	117	1.70	181.1	8.5	0.6	12	2.3	3.6	0.2	123	0.18	0.063	5
1281238	Soil	42.9	89.8	32.2	594	2.7	46.3	3.0	85	2.53	79.8	4.2	0.2	10	0.8	14.5	0.4	439	0.21	0.220	10
1281239	Soil	8.1	99.1	20.0	449	0.8	65.4	14.4	333	3.22	129.6	1.8	5.9	72	5.0	4.0	0.6	230	3.48	0.161	11
1281240	Soil	21.1	188.3	41.9	726	2.0	63.2	11.0	186	3.77	326.9	11.6	5.9	11	2.6	12.7	0.3	225	0.53	0.370	21
1281241	Soil	1.6	22.6	6.2	80	0.3	13.1	1.7	36	0.89	35.2	1.5	0.2	7	0.2	0.9	0.1	34	0.07	0.038	3
1281242	Soil	4.9	96.6	23.8	360	0.6	59.2	8.2	184	3.53	358.0	6.6	1.9	18	0.5	3.6	0.5	108	0.14	0.099	10
1281243	Soil	4.7	54.1	14.9	172	0.5	25.6	3.5	81	2.56	122.1	3.1	2.1	10	0.3	2.6	0.5	127	0.10	0.087	9
1281244	Soil	4.0	123.7	22.0	183	0.7	40.4	3.9	85	2.74	252.6	7.6	0.8	11	0.4	2.5	0.5	56	0.07	0.058	9
1281245	Soil	1.1	29.4	3.5	31	0.6	8.2	1.6	41	0.58	53.4	1.7	0.3	8	0.2	0.5	<0.1	16	0.10	0.046	2
1281246	Soil	2.4	54.2	23.3	166	3.4	60.5	8.5	119	2.88	17.5	7.1	2.0	88	0.8	1.4	0.2	41	0.78	0.167	9
1281247	Soil	2.8	27.7	14.0	156	1.8	44.8	6.4	196	2.38	17.0	2.9	0.6	116	1.8	2.0	0.4	45	2.37	0.213	15
1281248	Soil	2.0	23.8	9.6	143	1.6	36.7	4.4	159	1.89	11.1	3.5	0.4	97	1.6	1.3	0.3	39	2.38	0.228	17
1281249	Soil	3.6	38.9	12.9	180	2.0	58.9	7.1	134	2.74	17.2	4.4	1.3	85	1.4	2.0	0.2	47	1.34	0.217	16
1281250	Soil	1.8	25.4	8.7	137	1.3	34.1	4.4	148	1.81	7.8	3.5	0.4	106	1.1	1.0	0.2	31	2.44	0.198	14
1281901	Soil	2.7	65.7	18.6	184	0.9	52.2	10.2	183	3.91	21.8	7.1	2.2	62	0.5	1.6	0.3	24	0.02	0.097	4
1281902	Soil	2.0	38.9	13.1	108	0.7	29.5	5.4	105	2.66	15.4	7.3	1.9	22	0.4	1.9	0.2	28	0.03	0.054	5
1281903	Soil	1.7	28.5	8.3	79	0.3	16.9	4.2	124	1.77	8.4	2.3	0.2	17	1.0	0.9	0.2	26	0.06	0.102	7
1281904	Soil	2.6	27.5	10.5	116	0.3	26.9	5.3	102	2.52	13.3	5.9	0.9	21	0.3	1.4	0.3	31	0.03	0.060	6
1281905	Soil	1.5	21.5	7.7	65	0.6	20.5	3.2	50	1.55	6.6	4.0	0.3	13	0.2	0.7	0.2	19	0.02	0.064	4
1281906	Soil	2.4	36.7	13.6	95	0.9	26.9	3.8	47	2.66	14.9	2.4	0.7	25	0.2	1.2	0.2	33	0.03	0.092	4
1281907	Soil	3.3	22.0	8.9	80	0.9	17.3	4.2	47	1.91	12.2	2.0	1.7	8	<0.1	1.0	0.2	57	<0.01	0.029	6
1281908	Soil	3.4	48.8	17.3	192	0.3	59.1	7.8	113	3.54	20.8	5.3	1.5	22	0.4	1.6	0.3	33	0.02	0.076	5
1281909	Soil	3.2	29.0	11.3	88	0.2	19.8	4.3	112	2.44	14.8	7.0	0.7	14	0.3	1.6	0.2	49	0.03	0.052	8
1281910	Soil	2.0	16.7	7.3	51	0.2	11.6	2.6	65	1.54	8.5	2.2	0.1	9	0.1	0.8	0.2	29	0.02	0.065	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281231	Soil	3	0.02	19	0.012	<1	0.50	0.023	0.02	<0.1	0.04	<0.1	<0.1	<0.05	2	<0.5	<0.2
1281232	Soil	25	0.61	90	0.020	<1	1.50	0.015	0.07	0.5	0.10	0.7	0.2	0.08	4	2.1	<0.2
1281233	Soil	38	0.70	145	0.037	<1	1.90	0.017	0.12	0.5	0.12	1.8	0.4	0.11	4	3.4	<0.2
1281234	Soil	4	0.04	19	0.004	<1	0.17	0.018	0.02	<0.1	0.04	0.1	<0.1	<0.05	<1	<0.5	<0.2
1281235	Soil	9	0.10	48	0.005	<1	0.32	0.021	0.03	<0.1	0.06	0.1	<0.1	<0.05	1	<0.5	<0.2
1281236	Soil	31	1.39	118	0.032	1	1.72	0.009	0.12	0.2	0.04	1.5	0.4	0.05	5	<0.5	<0.2
1281237	Soil	21	0.62	96	0.024	<1	0.86	0.024	0.08	0.2	0.10	0.9	0.2	0.09	3	0.7	<0.2
1281238	Soil	33	0.73	122	0.012	1	1.12	0.007	0.14	0.3	0.09	0.4	0.3	0.11	4	5.5	0.3
1281239	Soil	50	2.49	393	0.092	1	2.99	0.047	0.57	0.2	0.08	3.7	0.6	0.06	8	<0.5	<0.2
1281240	Soil	29	1.67	157	0.042	2	1.62	0.003	0.26	0.2	0.12	2.1	0.4	0.10	4	2.7	<0.2
1281241	Soil	12	0.24	49	0.018	<1	0.75	0.019	0.05	0.2	0.04	0.3	<0.1	0.08	3	<0.5	<0.2
1281242	Soil	32	0.79	129	0.048	1	1.89	0.008	0.14	0.7	0.06	1.9	0.2	0.10	6	1.3	<0.2
1281243	Soil	30	0.77	110	0.062	<1	1.62	0.008	0.12	0.7	0.07	1.8	0.2	0.08	6	0.6	<0.2
1281244	Soil	19	0.37	89	0.031	<1	1.68	0.014	0.08	0.7	0.06	1.3	0.2	0.11	4	1.4	<0.2
1281245	Soil	8	0.10	43	0.013	<1	0.65	0.025	0.04	<0.1	0.04	0.4	<0.1	<0.05	2	<0.5	<0.2
1281246	Soil	27	0.14	442	0.003	4	0.94	0.011	0.15	0.1	0.31	4.4	0.3	0.36	2	3.9	<0.2
1281247	Soil	23	0.17	518	0.004	6	0.69	0.010	0.07	0.1	0.24	1.3	0.3	0.16	2	2.6	<0.2
1281248	Soil	21	0.16	363	0.004	5	0.69	0.010	0.06	0.1	0.18	0.9	0.1	0.13	2	2.5	<0.2
1281249	Soil	26	0.24	393	0.005	4	0.75	0.009	0.08	0.2	0.19	2.7	0.2	0.12	2	2.5	<0.2
1281250	Soil	21	0.15	462	0.003	4	0.73	0.010	0.04	<0.1	0.15	1.0	0.1	0.16	2	1.7	<0.2
1281901	Soil	17	0.06	246	0.001	<1	0.81	0.006	0.10	<0.1	0.08	2.4	0.1	0.13	2	3.2	<0.2
1281902	Soil	16	0.14	172	0.003	2	0.69	0.004	0.06	<0.1	0.06	1.8	0.1	0.09	2	2.2	<0.2
1281903	Soil	10	0.05	387	0.002	2	0.67	0.007	0.06	<0.1	0.04	0.6	<0.1	0.08	2	0.9	<0.2
1281904	Soil	15	0.14	123	0.004	1	0.75	0.003	0.05	0.1	0.06	1.3	0.1	<0.05	3	1.6	<0.2
1281905	Soil	8	0.05	102	0.004	1	0.49	0.008	0.04	<0.1	0.12	0.6	<0.1	<0.05	2	0.9	<0.2
1281906	Soil	18	0.03	288	0.002	3	0.63	0.004	0.09	<0.1	0.06	1.2	0.1	0.09	2	2.8	<0.2
1281907	Soil	15	0.03	269	0.002	3	0.63	0.004	0.06	<0.1	0.05	1.3	0.1	<0.05	4	1.8	<0.2
1281908	Soil	19	0.11	138	0.003	2	1.00	0.003	0.06	<0.1	0.05	1.6	<0.1	<0.05	2	1.8	<0.2
1281909	Soil	17	0.17	121	0.008	1	0.92	0.004	0.05	0.2	0.04	1.1	<0.1	<0.05	4	1.4	<0.2
1281910	Soil	11	0.05	159	0.004	2	0.59	0.010	0.04	<0.1	0.04	0.3	<0.1	0.07	3	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283991	Soil	1.1	21.7	17.7	51	<0.1	19.7	11.5	236	1.64	15.9	1.2	0.6	34	0.1	0.7	0.3	11	0.07	0.052	3
1283992	Soil	1.2	19.0	19.1	48	<0.1	17.3	11.5	291	1.46	16.6	2.2	0.6	31	<0.1	0.7	0.3	11	0.05	0.052	3
1283993	Soil	1.3	18.3	20.9	55	0.1	15.2	8.8	223	1.44	13.9	1.1	0.6	31	0.1	0.5	0.3	11	0.04	0.054	3
1283994	Soil	1.5	17.3	9.9	60	<0.1	11.7	5.5	118	1.65	13.6	1.5	0.5	16	<0.1	0.5	0.2	17	0.04	0.080	3
1283995	Soil	1.5	14.8	12.7	67	<0.1	13.1	7.1	157	1.53	18.6	2.0	0.4	21	<0.1	0.6	0.3	11	0.02	0.081	2
1283996	Soil	1.7	15.9	11.9	98	<0.1	13.2	7.0	222	1.99	19.7	1.8	0.7	15	0.1	0.9	0.3	19	0.01	0.057	2
1283997	Soil	1.4	16.5	18.2	57	<0.1	14.3	6.1	214	1.87	10.8	1.1	0.2	13	0.1	0.8	0.2	18	0.02	0.074	3
1283998	Soil	2.7	6.5	31.0	12	0.8	3.0	0.5	15	0.43	11.0	<0.5	0.2	31	<0.1	1.0	0.2	22	0.02	0.045	1
1283999	Soil	6.7	19.8	41.9	59	2.3	13.2	1.7	158	1.08	15.3	2.2	<0.1	37	0.3	2.0	0.2	42	0.17	0.118	2
1284000	Soil	5.0	13.0	71.9	20	3.0	5.9	1.0	38	0.80	16.4	4.4	0.5	47	0.2	2.1	0.2	43	0.02	0.034	2
1284271	Soil	2.8	57.4	29.9	96	0.9	23.9	7.4	329	3.93	20.4	8.7	1.8	143	0.1	1.1	0.3	28	0.02	0.104	2
1284272	Soil	2.9	36.2	17.3	98	0.3	23.6	8.8	629	2.98	16.8	4.6	0.8	23	0.2	1.3	0.2	40	0.03	0.085	4
1284273	Soil	2.8	85.0	33.8	140	0.4	40.9	34.7	1848	3.79	17.6	7.2	1.7	44	0.1	1.4	0.3	32	0.02	0.135	4
1284274	Soil	3.0	42.2	15.1	68	0.2	17.9	7.1	374	1.96	13.8	3.2	0.3	37	<0.1	1.0	0.2	33	0.06	0.081	6
1284275	Soil	6.2	83.3	61.7	67	2.6	11.9	1.7	67	3.33	37.1	7.8	0.5	228	0.3	4.7	0.2	104	0.03	0.124	4
1284276	Soil	5.4	51.2	56.3	44	3.3	9.5	1.2	40	1.72	27.6	4.8	0.4	105	0.1	3.2	0.1	66	0.02	0.073	4
1284277	Soil	6.5	28.0	52.8	50	4.5	11.2	2.1	76	1.83	37.7	5.2	0.3	65	<0.1	3.0	0.2	80	0.03	0.059	7
1284278	Soil	3.6	21.0	42.2	50	2.8	12.9	3.0	103	1.67	25.6	9.0	1.6	59	0.1	2.9	0.1	47	0.05	0.050	7
1284279	Soil	7.4	21.0	39.8	50	3.0	13.2	2.1	65	1.71	25.5	2.6	0.1	43	<0.1	2.8	0.2	71	0.03	0.067	7
1284280	Soil	3.5	35.3	65.0	18	2.6	2.9	0.2	8	1.14	28.4	1.9	0.4	129	<0.1	2.9	<0.1	52	<0.01	0.065	1
1284281	Soil	4.3	25.3	44.9	29	2.4	7.6	1.5	71	1.17	25.0	5.7	0.4	62	0.2	2.3	0.1	41	0.03	0.051	4
1284282	Soil	13.9	27.2	25.2	118	1.3	33.6	5.7	229	1.92	26.0	6.2	0.5	30	0.4	2.8	0.2	70	0.07	0.067	10
1284283	Soil	7.1	27.8	35.8	78	1.8	17.6	4.4	122	2.50	76.2	4.3	2.8	65	0.2	3.6	0.2	71	0.03	0.055	9
1284284	Soil	5.5	16.0	37.6	58	2.4	13.7	2.3	62	1.44	37.4	1.7	0.7	57	<0.1	2.6	0.2	63	0.02	0.045	6
1284285	Soil	5.0	18.4	35.6	76	1.9	16.3	3.8	116	2.22	42.5	2.9	1.1	72	0.2	2.8	0.2	72	0.05	0.069	8
1284286	Soil	4.8	21.0	23.5	47	1.5	11.0	2.1	69	1.17	14.9	2.3	0.1	38	0.4	1.5	0.2	42	0.02	0.085	5
1284287	Soil	6.4	14.8	45.9	50	1.1	9.9	2.2	55	1.12	25.6	0.7	0.1	112	0.2	1.7	0.2	52	0.04	0.114	5
1284288	Soil	3.2	10.8	17.0	38	0.9	8.2	2.0	60	0.90	11.6	1.7	0.2	42	0.2	1.1	0.1	30	0.03	0.061	4
1284289	Soil	3.2	17.5	13.2	65	0.8	11.7	3.2	217	1.13	9.7	0.8	0.1	20	1.2	1.2	0.2	40	0.02	0.059	6
1284290	Soil	4.5	22.0	20.1	95	0.7	18.6	4.0	76	2.14	19.4	1.1	0.8	28	0.4	1.9	0.2	55	0.02	0.115	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283991	Soil	5	0.07	272	<0.001	<1	0.38	0.005	0.06	<0.1	0.07	1.5	0.1	<0.05	1	<0.5	<0.2
1283992	Soil	6	0.06	205	<0.001	<1	0.38	0.006	0.06	<0.1	0.05	1.3	0.2	0.06	1	<0.5	<0.2
1283993	Soil	5	0.07	286	<0.001	<1	0.45	0.007	0.06	<0.1	0.08	1.1	0.1	0.06	1	<0.5	<0.2
1283994	Soil	7	0.04	129	0.002	<1	0.59	0.010	0.05	<0.1	0.05	0.8	<0.1	<0.05	2	<0.5	<0.2
1283995	Soil	6	0.03	183	<0.001	<1	0.34	0.004	0.05	<0.1	0.08	0.9	0.1	0.07	1	<0.5	<0.2
1283996	Soil	7	0.04	141	<0.001	<1	0.45	0.004	0.06	<0.1	0.11	1.2	<0.1	0.05	2	<0.5	<0.2
1283997	Soil	11	0.09	70	0.003	<1	0.72	0.012	0.05	<0.1	0.09	0.5	0.2	<0.05	2	<0.5	<0.2
1283998	Soil	6	<0.01	96	0.002	2	0.20	0.011	0.03	<0.1	0.07	0.8	0.2	0.06	2	1.4	<0.2
1283999	Soil	10	0.02	186	0.002	3	0.31	0.008	0.06	<0.1	0.20	0.8	0.4	0.13	1	3.3	<0.2
1284000	Soil	10	0.01	194	0.002	3	0.21	0.003	0.07	<0.1	0.08	0.7	0.6	0.15	1	3.8	<0.2
1284271	Soil	25	0.12	324	0.002	2	0.97	0.009	0.07	<0.1	0.21	2.2	0.2	0.10	3	2.9	0.2
1284272	Soil	20	0.13	239	0.004	2	0.84	0.003	0.08	<0.1	0.27	1.5	0.1	0.07	3	1.0	<0.2
1284273	Soil	24	0.28	244	0.004	<1	1.23	0.009	0.06	<0.1	0.11	2.2	0.1	0.05	3	0.9	<0.2
1284274	Soil	18	0.13	169	0.005	1	0.92	0.010	0.06	<0.1	0.08	0.8	0.1	0.06	3	1.0	<0.2
1284275	Soil	26	0.05	1143	0.005	1	0.48	0.002	0.04	<0.1	0.14	1.2	0.2	<0.05	2	9.2	<0.2
1284276	Soil	18	0.03	618	0.005	<1	0.34	0.003	0.04	<0.1	0.19	0.8	0.1	<0.05	2	10.9	<0.2
1284277	Soil	19	0.08	352	0.010	<1	0.48	0.004	0.07	0.2	0.14	0.8	0.4	0.12	4	4.7	0.3
1284278	Soil	17	0.16	314	0.013	<1	0.55	0.004	0.05	0.1	0.16	1.0	0.5	0.09	3	3.6	<0.2
1284279	Soil	18	0.05	240	0.009	<1	0.39	0.004	0.05	0.2	0.12	0.4	0.3	0.09	4	4.1	<0.2
1284280	Soil	18	<0.01	924	0.002	<1	0.23	0.001	0.03	<0.1	0.15	1.0	0.1	<0.05	2	11.2	<0.2
1284281	Soil	14	0.08	361	0.007	<1	0.36	0.004	0.04	<0.1	0.11	0.7	0.3	0.06	2	4.1	<0.2
1284282	Soil	19	0.19	253	0.009	2	0.73	0.005	0.06	0.2	0.34	1.2	0.6	<0.05	3	1.7	<0.2
1284283	Soil	20	0.16	270	0.018	<1	0.95	0.003	0.04	0.2	0.24	1.6	0.4	<0.05	3	3.4	<0.2
1284284	Soil	13	0.05	212	0.010	1	0.41	0.002	0.03	0.1	0.16	0.9	0.5	<0.05	3	2.0	<0.2
1284285	Soil	19	0.15	338	0.015	1	0.72	0.003	0.04	0.2	0.18	1.2	0.4	<0.05	4	2.2	<0.2
1284286	Soil	14	0.03	255	0.005	<1	0.67	0.011	0.04	<0.1	0.13	0.2	0.3	<0.05	3	1.4	<0.2
1284287	Soil	11	0.03	1024	0.006	1	0.43	0.004	0.05	<0.1	0.09	0.4	0.3	<0.05	3	2.2	<0.2
1284288	Soil	7	0.03	296	0.005	1	0.45	0.012	0.03	<0.1	0.06	0.4	0.2	<0.05	2	1.0	<0.2
1284289	Soil	8	0.03	195	0.004	<1	0.47	0.008	0.04	<0.1	0.03	0.4	0.2	<0.05	2	0.6	<0.2
1284290	Soil	13	0.08	220	0.007	1	0.66	0.005	0.04	0.1	0.05	1.4	0.2	<0.05	3	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

QUALITY CONTROL REPORT WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1288383	Soil	9.2	22.0	8.6	95	0.3	22.5	3.8	64	0.97	13.6	1.2	0.2	7	0.2	1.9	0.1	39	0.06	0.046	4
REP 1288383	QC	9.3	22.4	9.1	94	0.3	21.9	3.9	63	0.96	13.5	1.7	0.1	7	0.2	1.8	0.1	38	0.06	0.047	4
1288580	Soil	1.5	19.6	6.5	78	0.3	22.7	1.7	70	0.86	3.3	2.2	0.3	56	1.2	0.7	<0.1	10	0.78	0.072	2
REP 1288580	QC	1.5	20.4	6.4	78	0.3	22.7	1.7	70	0.86	3.4	1.6	0.3	54	1.1	0.7	<0.1	11	0.79	0.072	2
1288596	Soil	8.1	34.5	11.2	711	0.5	92.5	9.0	161	1.61	11.4	2.6	1.4	79	1.8	2.1	0.2	46	1.30	0.066	5
REP 1288596	QC	8.0	34.6	11.2	712	0.5	93.8	9.2	162	1.63	11.5	2.2	1.4	79	1.8	2.1	0.2	46	1.30	0.064	5
1288790	Soil	59.6	33.2	9.2	275	<0.1	107.3	7.2	97	1.94	21.4	<0.5	0.4	8	1.3	5.1	0.2	185	0.06	0.140	9
REP 1288790	QC	58.6	32.4	9.4	282	<0.1	106.8	6.9	92	1.85	21.0	0.7	0.5	9	1.1	5.2	0.1	181	0.06	0.137	9
1288889	Soil	24.3	27.2	12.3	373	0.3	53.7	4.2	32	1.41	23.9	1.4	0.4	5	0.4	8.3	0.2	122	0.01	0.040	7
REP 1288889	QC	24.3	26.4	12.0	380	0.3	53.1	4.0	32	1.39	23.7	1.5	0.4	5	0.4	8.6	0.2	124	0.01	0.041	7
1288407	Soil	1.4	40.7	7.5	65	<0.1	149.6	23.1	401	3.77	7.0	<0.5	1.6	34	0.2	0.4	<0.1	69	0.74	0.165	38
REP 1288407	QC	1.5	41.0	7.5	63	<0.1	145.6	22.8	396	3.71	7.0	1.1	1.5	34	0.2	0.4	<0.1	68	0.73	0.168	38
1288205	Soil	143.0	155.6	18.6	1802	2.0	326.8	6.7	141	1.47	99.4	1.6	2.9	323	21.5	44.1	0.1	1009	12.61	0.112	16
REP 1288205	QC	143.7	161.7	18.6	1841	2.0	339.1	6.9	147	1.53	102.1	1.6	3.0	327	22.1	44.2	0.2	1113	12.49	0.119	17
1288213	Soil	23.9	139.7	26.3	1016	0.9	524.1	73.2	1136	8.54	222.3	6.8	7.7	146	14.3	12.2	0.2	304	1.97	0.498	88
REP 1288213	QC	24.8	139.9	25.6	1029	0.9	529.4	75.8	1138	8.77	222.0	2.7	7.7	147	14.4	12.1	0.2	328	1.98	0.491	89
1288230	Soil	16.3	89.0	21.7	508	1.0	291.8	34.4	563	4.79	170.3	3.3	7.4	120	4.4	8.5	0.2	123	2.14	0.307	39
REP 1288230	QC	15.2	88.7	21.8	507	1.0	297.2	36.3	569	4.84	174.1	2.3	7.5	123	4.0	8.7	0.2	123	2.16	0.303	38
1288249	Soil	16.2	24.7	37.7	64	1.9	19.6	2.4	34	2.31	68.3	8.7	0.4	64	0.3	9.5	0.2	76	0.06	0.106	4
REP 1288249	QC	17.1	25.9	37.9	65	1.9	20.4	2.5	34	2.27	68.8	8.4	0.3	64	0.2	9.4	0.2	72	0.05	0.111	4
1281235	Soil	1.5	13.4	4.4	39	0.5	8.6	1.3	23	0.46	27.3	3.0	<0.1	6	0.2	0.7	<0.1	18	0.09	0.034	2
REP 1281235	QC	1.5	13.2	4.4	38	0.5	8.4	1.3	22	0.45	26.7	1.5	<0.1	7	0.2	0.7	<0.1	19	0.09	0.037	2
1281901	Soil	2.7	65.7	18.6	184	0.9	52.2	10.2	183	3.91	21.8	7.1	2.2	62	0.5	1.6	0.3	24	0.02	0.097	4
REP 1281901	QC	2.6	67.3	18.9	188	0.9	54.6	10.2	182	3.94	22.8	3.0	2.3	60	0.5	1.5	0.3	26	0.02	0.102	4
1283996	Soil	1.7	15.9	11.9	98	<0.1	13.2	7.0	222	1.99	19.7	1.8	0.7	15	0.1	0.9	0.3	19	0.01	0.057	2
REP 1283996	QC	1.8	16.2	12.2	100	<0.1	12.6	7.2	234	1.93	20.3	<0.5	0.7	15	0.2	0.7	0.3	20	0.01	0.056	2
Reference Materials																					
STD DS8	Standard	12.3	118.4	133.4	315	1.9	38.6	7.5	630	2.52	27.1	113.1	7.1	56	2.7	4.8	5.2	42	0.66	0.081	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

QUALITY CONTROL REPORT WHI11001855.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1288383	Soil	7	0.03	109	0.002	2	0.27	0.008	0.04	<0.1	0.06	0.4	0.2	<0.05	2	0.8	<0.2
REP 1288383	QC	7	0.03	107	0.002	1	0.28	0.009	0.04	<0.1	0.05	0.4	0.2	<0.05	2	<0.5	<0.2
1288580	Soil	6	0.06	747	0.005	2	0.37	0.019	0.02	<0.1	0.10	0.9	<0.1	0.13	<1	1.6	<0.2
REP 1288580	QC	6	0.06	745	0.006	2	0.37	0.019	0.02	<0.1	0.10	0.9	<0.1	0.14	<1	1.4	<0.2
1288596	Soil	14	0.15	848	0.001	4	0.64	0.006	0.05	<0.1	0.20	2.7	0.4	0.20	2	2.1	<0.2
REP 1288596	QC	14	0.15	857	0.001	3	0.64	0.006	0.05	<0.1	0.20	2.7	0.4	0.18	2	1.8	<0.2
1288790	Soil	25	0.20	311	0.004	5	0.88	0.006	0.08	0.2	0.02	0.9	2.0	0.09	3	2.2	<0.2
REP 1288790	QC	25	0.20	311	0.004	5	0.87	0.006	0.08	0.2	0.03	0.8	2.1	0.08	3	1.9	<0.2
1288889	Soil	10	0.02	71	0.001	2	0.32	0.002	0.04	0.1	0.11	0.4	0.3	<0.05	2	2.7	<0.2
REP 1288889	QC	10	0.02	78	0.001	2	0.34	0.002	0.04	0.1	0.11	0.5	0.3	<0.05	2	3.1	<0.2
1288407	Soil	126	0.50	1981	0.007	3	1.35	0.018	0.04	0.1	0.04	7.3	<0.1	<0.05	4	0.8	<0.2
REP 1288407	QC	127	0.51	1999	0.009	3	1.35	0.019	0.04	<0.1	0.04	7.3	<0.1	0.05	4	<0.5	<0.2
1288205	Soil	51	1.68	300	0.008	9	0.46	0.007	0.15	0.4	0.81	3.0	4.9	<0.05	2	10.0	<0.2
REP 1288205	QC	57	1.78	310	0.009	12	0.52	0.007	0.17	0.4	0.87	2.9	5.3	0.05	2	9.0	0.3
1288213	Soil	178	0.46	3673	0.008	16	1.11	0.006	0.13	0.3	1.90	19.3	0.5	0.10	3	5.3	<0.2
REP 1288213	QC	193	0.48	3917	0.009	18	1.18	0.006	0.15	0.4	1.91	19.9	0.6	0.08	4	3.7	<0.2
1288230	Soil	66	0.85	2455	0.003	13	0.70	0.006	0.15	<0.1	1.30	9.4	0.4	0.06	2	2.0	<0.2
REP 1288230	QC	65	0.86	2415	0.003	11	0.67	0.007	0.15	<0.1	1.27	9.6	0.4	<0.05	2	1.9	<0.2
1288249	Soil	17	0.03	482	0.003	2	0.34	0.007	0.11	0.1	0.82	0.9	1.1	0.20	2	10.3	0.3
REP 1288249	QC	17	0.03	487	0.002	1	0.33	0.007	0.10	<0.1	0.78	1.0	1.1	0.19	2	9.9	0.2
1281235	Soil	9	0.10	48	0.005	<1	0.32	0.021	0.03	<0.1	0.06	0.1	<0.1	<0.05	1	<0.5	<0.2
REP 1281235	QC	9	0.10	49	0.005	<1	0.32	0.022	0.04	<0.1	0.05	0.1	<0.1	<0.05	1	<0.5	<0.2
1281901	Soil	17	0.06	246	0.001	<1	0.81	0.006	0.10	<0.1	0.08	2.4	0.1	0.13	2	3.2	<0.2
REP 1281901	QC	17	0.07	274	0.002	3	0.83	0.006	0.11	<0.1	0.08	2.8	0.1	0.13	2	2.8	<0.2
1283996	Soil	7	0.04	141	<0.001	<1	0.45	0.004	0.06	<0.1	0.11	1.2	<0.1	0.05	2	<0.5	<0.2
REP 1283996	QC	8	0.04	143	<0.001	4	0.46	0.004	0.06	<0.1	0.10	1.1	<0.1	0.05	2	<0.5	<0.2
Reference Materials																	
STD DS8	Standard	121	0.62	271	0.109	2	0.88	0.086	0.42	2.9	0.18	2.3	5.2	0.17	5	5.6	4.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

QUALITY CONTROL REPORT WHI11001855.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	12.6	110.7	132.6	313	1.8	39.6	7.7	616	2.49	26.8	118.6	6.5	70	2.6	5.9	6.4	44	0.70	0.081	15
STD DS8	Standard	13.2	107.4	126.7	312	1.8	37.6	7.3	598	2.41	26.6	108.1	6.4	64	2.2	5.5	6.3	41	0.70	0.083	16
STD DS8	Standard	12.4	107.8	125.5	289	1.7	35.2	7.3	554	2.25	25.8	102.5	6.5	68	2.3	5.4	6.5	38	0.63	0.072	13
STD DS8	Standard	12.0	104.4	116.9	283	1.8	36.4	7.0	567	2.30	24.9	105.3	6.2	55	2.1	4.9	5.2	41	0.62	0.073	14
STD DS8	Standard	12.1	100.1	122.1	286	1.7	35.4	6.9	589	2.34	24.1	102.7	7.0	76	2.0	5.3	5.8	40	0.69	0.075	16
STD DS8	Standard	12.3	104.4	126.9	298	1.7	38.1	7.3	585	2.36	25.4	111.3	7.2	65	2.2	5.4	6.8	41	0.66	0.076	14
STD DS8	Standard	12.4	101.8	122.8	298	1.6	35.8	6.9	582	2.36	24.9	113.2	6.2	73	2.3	5.2	6.6	41	0.66	0.082	14
STD DS8	Standard	12.6	104.5	124.0	309	1.7	35.5	7.3	674	2.43	25.4	108.3	6.6	63	2.3	5.1	6.2	40	0.71	0.081	16
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

QUALITY CONTROL REPORT WHI11001855.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
STD DS8	Standard	123	0.63	287	0.124	3	0.95	0.097	0.42	3.1	0.20	2.3	5.7	0.17	5	5.3	5.8
STD DS8	Standard	113	0.62	272	0.109	2	0.92	0.101	0.42	2.9	0.20	2.2	5.4	0.19	5	4.7	5.0
STD DS8	Standard	106	0.58	272	0.111	2	0.91	0.112	0.37	2.7	0.21	2.2	5.3	0.10	5	5.0	4.6
STD DS8	Standard	113	0.56	249	0.101	1	0.85	0.082	0.39	2.7	0.21	1.9	5.1	0.13	4	4.8	4.3
STD DS8	Standard	109	0.60	267	0.118	2	0.91	0.095	0.40	2.9	0.19	2.3	5.0	0.08	5	4.3	4.6
STD DS8	Standard	114	0.57	258	0.112	3	0.87	0.087	0.40	2.8	0.18	2.3	5.1	0.12	4	5.0	4.5
STD DS8	Standard	110	0.65	254	0.107	3	0.90	0.092	0.41	3.0	0.21	2.1	5.2	0.17	5	5.5	4.2
STD DS8	Standard	114	0.62	288	0.115	3	0.93	0.092	0.42	3.0	0.20	2.1	5.4	0.18	4	3.9	5.2
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 20, 2011
Report Date: December 02, 2011
Page: 1 of 6

CERTIFICATE OF ANALYSIS WHI11001856.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #28
P.O. Number
Number of Samples: 150

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	150	Sieve soil to 230 mesh			VAN
RJSV	150	Saving all or part of Soil Reject			VAN
1DX2	144	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001856.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286471	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286472	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286473	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286474	Soil	8.1	123.2	36.6	390	5.1	122.0	26.4	690	5.47	18.7	4.5	2.6	221	0.7	3.7	0.3	68	0.90	0.512	11
1286475	Soil	5.0	129.3	38.4	357	4.6	125.8	24.2	806	6.34	26.3	3.7	5.1	257	0.4	3.3	0.4	76	1.45	0.717	13
1286476	Soil	2.9	96.2	20.8	133	0.5	90.2	28.9	338	6.93	110.7	<0.5	0.8	51	0.2	3.2	0.7	37	0.19	0.229	8
1286477	Soil	2.3	108.4	32.6	94	1.3	93.3	49.6	931	7.33	36.4	8.3	3.1	18	0.1	3.7	1.0	23	0.11	0.100	21
1286478	Soil	2.2	192.3	31.6	99	1.7	118.4	52.2	859	8.88	85.6	18.1	4.7	28	<0.1	3.2	0.9	20	0.18	0.082	22
1286479	Soil	2.2	97.6	23.9	86	1.0	95.1	41.5	1052	6.32	66.6	8.9	3.5	22	0.1	2.3	0.6	19	0.21	0.082	21
1286480	Soil	11.0	90.0	45.0	163	1.5	115.4	31.0	623	5.85	51.6	2.1	4.0	31	0.4	3.5	0.4	28	0.36	0.071	20
1286911	Soil	7.7	81.0	17.8	936	1.2	182.1	40.2	1368	4.20	127.0	1.9	2.7	60	8.3	7.6	0.3	45	0.39	0.072	6
1286912	Soil	15.5	75.2	21.2	2203	1.2	561.7	61.4	6342	4.99	295.5	6.3	2.8	66	13.3	13.2	0.4	65	0.58	0.083	8
1286913	Soil	13.4	80.3	19.4	1238	1.3	187.9	16.6	430	2.51	87.9	11.6	2.7	78	8.5	10.9	0.4	75	0.42	0.100	10
1286914	Soil	13.4	66.6	29.8	1542	1.7	235.9	51.1	1345	5.04	257.9	36.2	2.8	77	12.4	14.9	0.9	65	0.53	0.094	9
1286915	Soil	11.9	62.6	45.8	861	2.4	138.8	22.6	749	3.23	264.0	78.9	2.6	70	6.9	18.2	1.4	64	0.41	0.105	11
1286916	Soil	6.5	47.6	23.8	277	1.3	57.9	12.7	410	2.31	95.6	43.2	2.1	42	3.5	8.9	0.6	48	0.21	0.076	10
1286917	Soil	9.7	57.0	59.8	434	3.2	99.1	9.0	656	2.80	377.8	155.4	2.7	76	7.3	23.0	2.3	51	0.82	0.115	13
1286918	Soil	7.5	71.1	45.4	799	2.8	176.7	11.5	904	2.91	299.5	113.6	2.4	86	8.6	21.0	1.6	43	0.96	0.114	11
1286919	Soil	19.5	59.7	79.5	279	3.0	43.2	5.3	201	3.99	748.1	139.8	4.0	114	2.1	37.0	3.2	67	0.44	0.176	18
1286920	Soil	7.5	50.0	38.1	219	2.5	48.4	5.6	211	2.46	244.9	121.9	2.9	54	3.1	20.0	1.3	46	0.24	0.105	13
1284451	Soil	57.2	50.9	38.9	387	1.7	80.7	5.1	129	2.26	133.5	4.5	2.3	113	3.5	25.4	0.3	400	0.27	0.181	13
1284452	Soil	63.8	40.2	35.9	417	1.6	85.2	5.2	147	2.84	155.2	6.2	1.5	90	2.0	22.5	0.3	381	0.12	0.192	10
1284453	Soil	19.8	56.6	11.5	179	2.1	43.7	9.9	246	1.05	43.5	17.2	0.4	38	3.5	11.3	0.1	232	0.14	0.143	4
1284454	Soil	7.1	81.4	37.3	2409	2.4	392.6	6.8	95	2.05	52.6	22.0	2.0	91	32.5	42.8	0.4	540	0.70	0.216	8
1284455	Soil	27.7	25.6	22.4	1225	3.0	108.5	1.3	64	1.19	43.5	1.9	0.5	37	3.5	9.8	0.4	135	0.26	0.093	7
1284456	Soil	45.1	74.0	110.2	684	3.0	88.7	6.1	259	2.94	89.6	5.8	3.0	102	3.0	19.3	0.3	188	0.27	0.161	12
1284457	Soil	33.0	54.8	24.6	340	0.9	74.6	6.4	116	2.60	80.9	6.4	3.1	53	1.4	12.3	0.3	181	0.14	0.141	16
1284458	Soil	59.2	52.5	21.0	499	0.6	139.0	8.5	196	3.09	72.0	1.5	2.5	42	1.8	15.1	0.3	266	0.17	0.248	16
1284459	Soil	63.6	55.0	15.1	627	0.8	144.7	8.9	255	2.81	74.3	4.2	3.2	45	3.8	14.8	0.2	331	0.22	0.217	15
1284460	Soil	39.3	44.8	24.9	315	0.9	90.6	8.4	266	2.78	57.8	1.1	1.9	57	1.1	19.7	0.3	160	0.15	0.296	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001856.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286471	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286472	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286473	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286474	Soil		17	0.06	4222	0.006	5	0.78	0.004	0.15	<0.1	0.71	5.3	0.2	0.08	1	5.7	0.3
1286475	Soil		27	0.08	3466	0.007	7	1.01	0.004	0.20	<0.1	0.49	6.5	0.2	<0.05	2	7.7	0.2
1286476	Soil		15	0.06	939	0.002	2	0.65	0.003	0.09	<0.1	0.06	2.8	0.2	0.06	3	3.7	0.4
1286477	Soil		11	0.10	786	0.009	3	0.70	0.015	0.07	<0.1	0.11	5.9	0.3	<0.05	2	1.9	0.3
1286478	Soil		10	0.10	866	0.003	3	0.44	0.004	0.09	<0.1	0.18	8.8	0.3	0.07	<1	2.7	0.3
1286479	Soil		9	0.10	849	0.004	3	0.47	0.006	0.10	<0.1	0.13	6.5	0.3	<0.05	1	1.8	<0.2
1286480	Soil		9	0.12	979	0.002	2	0.45	0.004	0.09	<0.1	0.38	6.4	0.3	0.06	<1	2.6	<0.2
1286911	Soil		25	0.28	1229	0.002	4	0.95	0.005	0.09	<0.1	1.41	3.9	0.3	0.06	2	7.6	<0.2
1286912	Soil		20	0.22	917	0.001	4	0.81	0.004	0.08	0.2	1.93	3.8	0.5	0.07	2	5.0	<0.2
1286913	Soil		19	0.16	768	0.002	2	0.73	0.004	0.08	0.2	2.27	3.5	0.6	0.07	2	4.5	<0.2
1286914	Soil		16	0.15	643	0.001	3	0.83	0.006	0.08	0.5	5.51	3.4	1.0	0.11	2	6.1	<0.2
1286915	Soil		16	0.12	548	0.001	2	0.75	0.006	0.09	0.6	11.75	2.8	1.2	0.10	2	9.1	<0.2
1286916	Soil		17	0.11	453	0.001	4	0.79	0.004	0.08	0.2	4.97	2.8	0.5	<0.05	2	3.1	0.3
1286917	Soil		15	0.10	478	0.002	5	0.76	0.007	0.10	1.0	16.78	2.2	1.5	0.17	2	10.7	0.2
1286918	Soil		15	0.12	804	0.003	11	0.78	0.010	0.11	0.5	13.11	2.6	1.2	0.22	2	5.9	0.3
1286919	Soil		15	0.10	438	0.003	3	0.62	0.010	0.14	1.5	18.66	1.9	2.4	0.31	2	13.0	0.3
1286920	Soil		17	0.09	570	0.003	2	0.66	0.005	0.07	0.3	16.15	2.7	0.7	0.07	2	7.8	0.3
1284451	Soil		28	0.12	571	0.004	4	0.60	0.004	0.12	0.5	1.84	2.1	2.6	0.13	3	6.3	<0.2
1284452	Soil		25	0.06	448	0.002	3	0.57	0.004	0.11	0.6	2.08	1.7	2.5	0.17	3	9.8	0.3
1284453	Soil		19	0.04	811	0.003	3	0.71	0.015	0.07	0.5	6.36	1.2	2.7	0.08	3	5.4	<0.2
1284454	Soil		33	0.10	2208	0.002	4	1.49	0.009	0.14	0.5	3.58	4.0	1.4	0.10	3	18.2	<0.2
1284455	Soil		17	0.03	541	0.003	2	0.68	0.005	0.10	0.6	0.88	0.7	2.0	0.15	3	3.6	<0.2
1284456	Soil		24	0.08	1112	0.003	6	0.58	0.005	0.18	0.7	2.02	2.9	3.2	0.41	2	6.3	<0.2
1284457	Soil		21	0.08	460	0.002	2	0.92	0.003	0.09	0.4	0.85	2.0	1.2	0.11	2	4.9	<0.2
1284458	Soil		23	0.06	386	0.003	5	0.64	0.003	0.11	0.4	0.39	2.3	1.3	0.05	2	4.2	<0.2
1284459	Soil		26	0.05	449	0.003	4	0.80	0.002	0.10	0.3	0.76	2.7	1.5	<0.05	2	4.7	<0.2
1284460	Soil		17	0.03	414	0.005	3	0.56	0.003	0.09	0.3	1.05	1.8	0.8	0.09	2	2.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001856.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1284181	Soil		2.0	12.5	10.3	58	0.3	6.7	2.8	112	2.51	8.1	<0.5	0.3	10	0.3	0.5	0.3	45	0.03	0.104	3
1284182	Soil		1.6	7.5	6.3	33	0.4	7.0	1.8	27	0.88	7.5	<0.5	<0.1	8	0.1	0.8	0.1	21	0.02	0.034	3
1284183	Soil		3.2	10.4	9.8	49	0.2	10.9	3.2	40	1.23	11.0	<0.5	0.4	8	<0.1	1.1	0.2	43	0.02	0.034	6
1284184	Soil		4.1	16.3	14.0	73	1.5	13.9	3.0	51	2.44	46.6	<0.5	0.4	17	<0.1	3.9	0.2	43	0.03	0.079	3
1284185	Soil		2.1	9.2	6.8	29	0.5	8.4	1.6	22	0.72	5.1	<0.5	<0.1	11	0.4	1.3	<0.1	20	0.02	0.037	1
1284186	Soil		2.1	23.6	12.5	108	0.2	30.7	8.2	141	1.92	12.5	<0.5	0.9	34	1.5	1.5	0.2	25	0.30	0.054	4
1284187	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284188	Soil		3.4	31.6	16.9	203	0.4	51.3	14.5	372	3.03	23.3	1.6	1.7	34	1.0	2.3	0.3	42	0.25	0.075	6
1284189	Soil		152.2	70.5	25.3	443	2.7	104.1	3.3	27	3.30	207.2	2.5	1.9	517	1.5	61.4	0.4	489	0.08	0.257	12
1284190	Soil		181.0	64.6	26.3	562	5.5	133.3	2.3	37	3.17	290.3	47.7	1.6	245	2.8	105.1	0.4	1402	0.09	0.167	19
1284191	Soil		58.1	19.2	21.0	196	1.5	43.5	2.3	27	1.57	92.0	13.7	0.6	92	0.4	32.5	0.3	290	0.02	0.075	15
1284192	Soil		10.6	7.1	106.8	8	3.8	1.9	0.2	2	0.20	18.9	74.6	0.1	9	0.1	36.7	0.2	48	<0.01	0.019	11
1284193	Soil		25.9	15.7	165.6	85	2.8	19.3	1.6	28	1.15	94.6	28.4	0.6	54	0.3	50.5	0.5	181	<0.01	0.049	15
1284194	Soil		32.9	24.1	71.5	135	3.4	36.8	3.8	62	2.10	150.5	37.5	0.8	59	0.4	33.4	0.4	277	0.01	0.081	13
1284195	Soil		35.7	21.3	58.0	90	2.0	20.0	1.6	21	1.15	53.3	12.9	0.2	85	0.5	41.4	0.4	168	0.02	0.058	14
1284196	Soil		32.3	23.4	37.6	162	1.2	42.5	3.1	33	1.27	53.1	17.9	0.4	30	0.4	20.8	0.3	190	<0.01	0.041	14
1284197	Soil		46.2	37.4	41.9	205	4.7	54.5	3.8	76	2.71	164.2	42.5	1.2	94	0.7	37.3	0.3	289	0.04	0.183	14
1284198	Soil		21.8	44.2	34.5	163	1.7	41.3	4.6	150	2.31	152.7	28.4	0.8	51	1.4	31.5	0.3	176	0.03	0.121	11
1284199	Soil		27.9	84.3	30.5	351	1.6	78.3	10.6	182	2.94	88.6	22.6	2.0	80	4.4	20.4	0.3	139	0.30	0.153	12
1284200	Soil		30.2	63.3	31.7	306	1.4	87.7	6.4	84	2.47	83.5	16.8	2.0	64	1.2	24.4	0.3	138	0.10	0.126	12
1284441	Soil		13.9	66.7	15.5	1202	1.2	95.6	7.2	176	2.65	51.3	5.9	2.2	61	15.2	9.1	0.2	128	0.41	0.155	12
1284442	Soil		13.2	89.4	22.9	409	1.4	84.3	6.6	290	2.57	47.1	5.7	1.7	86	7.0	7.4	0.2	135	0.82	0.107	7
1284443	Soil		12.9	19.2	19.5	185	0.2	37.5	6.0	109	2.21	25.3	0.7	0.6	11	0.3	2.9	0.2	52	0.04	0.069	9
1284444	Soil		11.2	19.0	12.6	128	0.2	27.2	4.1	98	2.10	25.4	0.7	1.1	13	0.4	2.9	0.2	93	0.04	0.058	11
1284445	Soil		18.1	19.8	14.9	242	0.1	41.7	6.3	164	2.38	27.9	2.3	1.7	16	1.2	2.7	0.2	103	0.28	0.049	11
1284446	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284447	Soil		10.3	49.7	16.1	258	0.4	60.9	12.2	415	3.48	71.8	2.6	2.6	40	1.4	3.6	0.4	41	0.53	0.067	17
1284448	Soil		24.6	87.7	18.6	2293	1.7	357.7	10.3	283	3.07	54.2	4.6	2.4	70	26.7	10.5	0.3	103	0.95	0.133	12
1284449	Soil		25.0	77.2	20.3	852	1.4	160.3	12.6	165	3.54	61.4	9.1	4.1	52	6.1	12.4	0.3	72	0.34	0.109	14
1284450	Soil		24.3	39.6	11.8	371	0.7	73.9	7.1	170	1.99	34.0	2.4	1.7	43	6.4	7.3	0.2	70	0.60	0.075	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001856.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284181	Soil	13	0.04	180	0.002	<1	0.85	0.009	0.04	<0.1	0.05	0.6	<0.1	<0.05	5	<0.5	<0.2
1284182	Soil	4	0.01	101	0.003	1	0.41	0.010	0.04	<0.1	0.05	0.2	<0.1	<0.05	2	<0.5	<0.2
1284183	Soil	6	0.02	178	0.002	2	0.47	0.004	0.04	<0.1	0.04	0.5	0.1	<0.05	3	0.5	<0.2
1284184	Soil	9	0.03	175	0.002	1	0.46	0.006	0.06	<0.1	0.11	0.9	0.2	<0.05	2	1.9	<0.2
1284185	Soil	3	0.01	407	0.002	2	0.43	0.016	0.03	<0.1	0.07	0.4	0.1	<0.05	2	0.7	<0.2
1284186	Soil	9	0.21	673	0.002	1	0.61	0.011	0.06	<0.1	0.18	2.4	0.1	<0.05	2	1.0	<0.2
1284187	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284188	Soil	19	0.25	804	0.002	2	0.93	0.007	0.09	<0.1	0.24	3.5	0.2	<0.05	3	1.1	<0.2
1284189	Soil	46	0.02	488	0.003	5	0.63	0.004	0.20	1.4	1.05	3.1	7.7	0.45	3	56.2	0.8
1284190	Soil	49	0.04	485	0.005	5	0.78	0.007	0.21	2.3	13.83	1.7	6.9	0.32	6	33.6	0.5
1284191	Soil	17	0.02	246	0.004	3	0.43	0.003	0.07	0.8	1.76	0.7	2.1	0.06	3	6.4	0.3
1284192	Soil	6	<0.01	91	0.001	2	0.17	0.002	0.03	0.6	26.61	0.1	1.5	<0.05	1	3.2	<0.2
1284193	Soil	10	0.01	194	0.004	2	0.31	0.006	0.07	0.9	7.21	0.4	1.5	0.09	3	8.4	<0.2
1284194	Soil	16	0.02	177	0.004	2	0.32	0.003	0.06	0.8	10.00	0.7	1.4	0.07	3	5.8	<0.2
1284195	Soil	21	0.01	317	0.003	2	0.33	0.004	0.08	1.3	3.05	0.3	1.9	0.14	3	8.8	0.2
1284196	Soil	14	0.01	201	0.003	2	0.35	0.003	0.05	0.7	2.91	0.6	0.9	<0.05	3	3.4	<0.2
1284197	Soil	26	0.06	362	0.004	2	0.80	0.004	0.07	0.8	14.93	1.2	1.6	<0.05	3	7.3	0.4
1284198	Soil	18	0.02	399	0.003	2	0.38	0.004	0.06	0.5	9.01	1.1	1.2	0.07	2	5.1	0.2
1284199	Soil	20	0.05	737	0.002	2	0.60	0.004	0.07	0.5	4.30	2.9	1.1	0.08	2	5.6	<0.2
1284200	Soil	17	0.02	425	0.002	3	0.35	0.003	0.07	0.4	2.17	2.0	1.3	0.06	2	6.7	<0.2
1284441	Soil	34	0.20	1314	0.004	3	0.82	0.003	0.08	0.2	0.49	2.4	0.6	<0.05	2	2.5	<0.2
1284442	Soil	29	0.15	2454	0.001	3	1.25	0.007	0.12	0.2	1.06	3.6	0.7	0.09	3	4.1	<0.2
1284443	Soil	9	0.04	117	0.002	1	0.50	0.006	0.06	0.1	0.08	0.8	0.2	<0.05	3	1.4	<0.2
1284444	Soil	13	0.06	278	0.003	1	0.72	0.004	0.04	0.1	0.09	1.0	0.2	<0.05	3	1.0	<0.2
1284445	Soil	16	0.11	253	0.003	<1	0.83	0.003	0.05	0.2	0.07	1.3	0.3	<0.05	3	0.9	<0.2
1284446	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284447	Soil	12	0.10	632	0.001	2	0.58	0.005	0.08	<0.1	0.16	2.9	0.2	0.06	1	1.1	<0.2
1284448	Soil	20	0.09	944	0.002	5	0.49	0.003	0.07	0.2	1.44	4.4	1.4	0.08	1	3.1	<0.2
1284449	Soil	15	0.09	1353	0.002	3	0.51	0.003	0.09	0.2	1.07	4.6	0.9	0.08	1	4.0	<0.2
1284450	Soil	13	0.14	1076	0.003	2	0.47	0.005	0.05	0.2	0.38	1.8	0.6	<0.05	2	1.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001856.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287141	Soil	58.2	49.4	12.7	403	0.1	163.8	12.6	79	2.51	71.0	0.6	0.3	11	0.8	8.7	0.1	372	0.09	0.097	16
1287142	Soil	57.7	76.2	12.2	372	0.5	172.6	10.2	328	2.42	32.1	3.4	0.9	83	3.6	5.7	0.1	103	2.83	0.114	11
1287143	Soil	79.1	90.0	16.9	314	0.4	193.5	9.8	219	2.39	34.4	0.7	1.5	155	2.8	4.7	0.1	52	5.19	0.094	10
1287144	Soil	76.2	78.1	9.8	279	0.4	200.7	9.3	190	1.80	33.7	1.4	1.0	118	2.8	6.0	0.1	102	3.97	0.086	13
1287145	Soil	77.7	88.1	12.9	384	0.5	216.1	11.0	229	2.16	44.4	4.0	1.1	88	3.1	7.6	0.1	121	2.40	0.109	14
1287146	Soil	37.0	68.5	21.9	326	0.4	188.4	23.0	225	2.44	42.2	<0.5	4.4	106	2.9	7.2	0.1	82	3.03	0.132	8
1287147	Soil	5.9	27.1	11.0	88	1.0	26.6	3.7	136	1.04	21.6	11.0	0.5	158	1.1	3.1	0.2	45	2.16	0.095	3
1287148	Soil	4.1	32.6	6.8	103	0.8	28.5	2.0	58	0.94	16.0	7.9	0.5	83	1.6	2.1	0.1	37	1.13	0.078	4
1287149	Soil	21.4	56.8	13.1	297	1.6	80.4	8.5	167	1.99	49.5	14.4	1.7	49	3.1	5.7	0.2	112	0.54	0.120	11
1287150	Soil	12.6	28.4	7.5	142	0.8	39.1	3.5	51	1.12	21.8	8.2	0.6	28	2.6	3.4	<0.1	117	0.32	0.135	6
1287231	Soil	3.5	66.3	15.3	213	1.3	68.5	12.4	413	2.64	46.7	21.5	1.8	119	1.8	2.8	0.2	42	0.84	0.109	7
1287232	Soil	2.8	75.8	17.1	172	2.1	68.0	10.6	239	3.06	26.9	12.3	2.0	102	1.1	2.1	0.2	32	0.89	0.103	5
1287233	Soil	2.0	77.4	13.7	170	1.5	62.2	7.9	194	2.36	14.7	15.3	1.6	201	0.5	1.4	0.3	27	1.15	0.084	3
1287234	Soil	2.0	69.1	9.9	134	0.8	33.2	5.7	110	2.03	10.6	14.4	1.0	138	0.3	1.1	0.2	26	0.61	0.060	2
1287235	Soil	4.3	88.4	14.6	133	0.6	33.9	5.5	100	2.58	15.9	14.5	1.1	88	0.4	1.4	0.2	50	0.22	0.059	2
1287236	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287237	Soil	4.9	56.3	9.1	76	0.9	25.6	2.9	99	0.93	10.7	10.5	0.4	334	0.6	2.0	0.1	31	0.73	0.056	3
1287238	Soil	4.9	65.9	12.7	111	0.9	31.7	5.6	111	2.21	19.3	12.9	0.9	77	0.3	2.0	0.2	40	0.15	0.075	3
1287239	Soil	52.9	194.2	11.5	1586	4.0	354.8	8.2	219	2.38	90.2	5.2	3.1	107	38.3	62.0	0.2	329	3.53	0.268	10
1287240	Soil	55.7	154.0	22.5	597	3.0	119.8	4.7	102	2.33	124.7	19.5	1.9	121	12.2	33.8	0.4	434	0.52	0.176	13
1287241	Soil	5.9	24.9	7.7	66	0.7	22.5	2.9	230	0.85	23.3	7.5	0.6	74	1.9	6.3	0.1	68	1.54	0.065	3
1287242	Soil	54.4	138.0	33.1	636	5.3	112.8	5.3	128	2.45	191.3	10.2	2.0	115	7.6	35.6	0.3	537	0.24	0.220	10
1287243	Soil	47.9	41.4	27.4	264	3.2	55.9	4.9	84	2.91	168.1	17.0	3.9	68	1.2	32.8	0.5	243	0.03	0.086	14
1287244	Soil	208.0	56.3	8.9	486	1.2	294.6	6.2	29	2.22	63.8	3.8	2.0	6	0.8	34.6	0.2	416	<0.01	0.056	13
1287245	Soil	81.0	56.1	23.4	120	4.0	28.3	1.5	39	2.36	57.5	19.0	3.7	69	0.3	10.9	0.4	103	0.02	0.077	15
1287246	Soil	109.1	27.2	48.2	53	3.7	9.9	0.6	30	2.57	125.5	31.2	2.2	68	0.7	69.5	0.6	315	0.02	0.087	10
1287247	Soil	12.3	8.6	37.9	68	0.5	15.6	1.4	19	0.69	22.1	9.5	8.3	17	0.2	15.8	0.5	43	<0.01	0.022	48
1287248	Soil	54.2	75.4	36.1	363	2.0	80.3	7.4	204	3.31	140.8	17.9	5.0	114	2.5	49.4	0.3	313	0.19	0.237	17
1287249	Soil	37.2	77.3	33.8	284	2.7	63.2	4.8	210	2.30	111.5	18.6	3.6	125	3.6	36.5	0.3	205	0.34	0.215	13
1287250	Soil	42.5	44.7	31.0	383	1.7	80.7	6.5	138	3.33	127.4	22.4	5.1	74	0.9	23.4	0.3	314	0.20	0.248	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001856.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287141	Soil	43	0.09	312	0.002	4	0.62	0.003	0.05	0.3	0.08	0.9	1.1	<0.05	3	2.5	<0.2
1287142	Soil	19	1.21	404	0.004	3	0.39	0.008	0.04	0.2	0.26	2.7	1.1	0.09	<1	2.6	<0.2
1287143	Soil	12	1.85	380	0.003	3	0.26	0.005	0.05	0.3	0.25	2.4	1.8	<0.05	<1	2.3	<0.2
1287144	Soil	16	1.20	456	0.003	3	0.31	0.005	0.06	0.3	0.26	2.7	2.0	0.09	<1	3.7	<0.2
1287145	Soil	19	0.71	564	0.003	3	0.41	0.005	0.06	0.4	0.20	2.7	2.0	<0.05	<1	3.9	<0.2
1287146	Soil	16	1.28	200	0.002	4	0.19	0.004	0.06	0.6	0.28	3.4	1.1	<0.05	<1	2.2	<0.2
1287147	Soil	12	0.08	1388	0.002	3	0.50	0.008	0.03	0.1	1.19	1.3	0.2	0.17	1	1.6	<0.2
1287148	Soil	11	0.08	1196	0.003	2	0.40	0.014	0.03	<0.1	0.87	1.3	0.2	0.09	1	1.7	<0.2
1287149	Soil	21	0.08	1878	0.003	3	0.58	0.006	0.06	0.2	1.76	4.3	0.5	0.05	2	2.3	<0.2
1287150	Soil	17	0.05	1173	0.002	3	0.53	0.009	0.04	0.1	1.17	2.6	0.2	0.08	2	1.4	<0.2
1287231	Soil	25	0.18	1392	0.001	3	0.94	0.005	0.07	<0.1	1.08	3.8	0.2	<0.05	2	2.1	<0.2
1287232	Soil	30	0.19	1265	0.002	2	0.99	0.006	0.06	<0.1	0.77	4.1	<0.1	0.08	2	2.7	<0.2
1287233	Soil	28	0.26	768	0.001	2	0.94	0.009	0.06	<0.1	0.65	3.0	<0.1	0.12	2	2.2	<0.2
1287234	Soil	30	0.24	636	0.001	2	0.90	0.010	0.06	<0.1	0.48	1.9	<0.1	0.09	3	2.0	<0.2
1287235	Soil	47	0.26	510	<0.001	3	0.99	0.006	0.06	<0.1	0.20	2.4	0.1	0.07	3	1.8	<0.2
1287236	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287237	Soil	10	0.11	1136	0.005	4	0.44	0.015	0.05	<0.1	0.37	0.9	0.2	0.11	2	2.3	<0.2
1287238	Soil	29	0.18	768	0.001	2	0.74	0.012	0.05	<0.1	0.48	1.7	0.1	0.10	2	1.6	<0.2
1287239	Soil	75	1.70	450	0.004	8	0.44	0.005	0.12	0.2	0.98	3.4	2.0	0.07	1	13.6	<0.2
1287240	Soil	34	0.13	994	0.002	3	1.07	0.005	0.11	0.6	2.43	2.9	2.3	0.13	3	11.0	0.3
1287241	Soil	10	0.06	599	0.002	3	0.49	0.021	0.04	0.1	0.60	1.0	0.2	0.09	1	3.4	<0.2
1287242	Soil	35	0.10	885	0.002	3	1.24	0.007	0.12	0.7	5.00	2.9	3.4	0.13	3	13.7	<0.2
1287243	Soil	22	0.10	393	0.001	2	0.81	0.003	0.09	0.7	2.86	2.0	1.6	0.12	2	8.1	<0.2
1287244	Soil	18	0.02	108	0.001	4	0.38	0.001	0.08	0.8	0.46	2.5	2.8	<0.05	1	16.9	<0.2
1287245	Soil	13	0.02	274	0.002	5	0.50	0.003	0.29	1.1	1.43	1.4	6.6	0.58	1	11.5	<0.2
1287246	Soil	20	0.01	669	0.004	3	0.45	0.007	0.34	2.5	10.38	0.9	12.5	0.75	3	21.4	0.8
1287247	Soil	3	<0.01	99	<0.001	4	0.28	0.002	0.09	0.2	0.38	0.4	0.7	0.07	1	1.8	<0.2
1287248	Soil	36	0.10	617	0.002	3	0.81	0.004	0.14	0.7	5.47	3.2	2.8	0.22	2	14.8	0.3
1287249	Soil	24	0.05	463	0.002	5	0.49	0.005	0.17	0.5	7.33	2.6	2.3	0.22	2	14.2	0.5
1287250	Soil	31	0.07	459	0.003	3	1.12	0.003	0.11	0.4	1.00	2.4	1.4	0.11	2	8.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001856.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287261	Soil		68.7	127.5	13.3	1440	2.1	186.5	7.0	481	1.46	57.8	3.0	0.8	127	30.9	25.8	0.2	786	1.63	0.193	18
1287262	Soil		147.8	90.2	21.7	728	2.0	131.8	6.8	148	3.13	127.3	4.3	1.2	84	4.4	47.8	0.2	618	0.19	0.146	12
1287263	Soil		38.4	68.4	20.3	502	1.3	124.4	14.0	430	3.41	93.5	6.5	2.7	42	4.3	19.0	0.3	339	0.18	0.232	14
1287264	Soil		20.2	28.5	16.1	228	0.8	55.0	5.5	109	2.08	36.9	<0.5	0.3	18	0.7	8.4	0.3	110	0.05	0.091	11
1287265	Soil		26.6	46.4	21.9	343	0.5	94.4	10.7	150	3.05	58.6	2.3	1.5	20	0.7	14.4	0.3	118	0.04	0.114	13
1287266	Soil		35.9	50.1	21.1	385	0.8	101.9	11.9	250	3.28	67.1	3.8	1.6	27	1.5	17.4	0.3	143	0.09	0.142	12
1287267	Soil		21.8	60.8	17.6	386	0.6	104.8	13.9	400	3.59	55.1	2.6	4.6	32	2.2	7.0	0.2	102	0.20	0.200	14
1287268	Soil		28.8	66.2	17.6	1100	1.2	181.2	15.5	636	4.10	74.0	4.6	4.3	37	12.3	10.6	0.2	185	0.36	0.293	18
1287269	Soil		3.1	14.4	3.0	2587	0.4	423.1	1.4	128	0.40	6.6	<0.5	0.4	100	11.8	24.0	<0.1	60	2.13	0.074	2
1287270	Soil		5.0	38.6	6.9	2115	0.9	255.1	4.8	131	1.16	14.3	2.8	0.7	89	48.2	16.2	0.1	42	1.98	0.095	5
1287271	Soil		42.3	52.3	19.2	977	1.7	163.9	11.2	319	2.26	54.6	7.1	2.6	89	7.0	19.7	0.2	202	0.65	0.226	13
1287272	Soil		19.9	50.1	13.2	2935	1.2	461.9	7.6	503	1.46	59.0	10.0	0.7	90	17.5	21.2	0.2	164	1.28	0.156	6
1287273	Soil		43.0	48.9	20.2	942	0.8	147.6	7.6	176	2.38	66.3	4.5	1.9	77	4.8	30.0	0.2	201	0.70	0.193	12
1287274	Soil		27.0	56.6	17.2	848	0.8	100.6	6.1	123	2.32	80.2	7.2	2.8	61	5.0	20.2	0.2	111	0.37	0.120	11
1287275	Soil		15.0	40.6	15.5	409	0.6	104.2	3.8	98	1.50	42.0	2.6	1.4	57	9.1	12.0	0.2	100	0.81	0.112	10
1287276	Soil		45.5	69.4	29.1	924	1.1	153.5	12.2	489	3.28	179.9	5.9	1.4	84	10.5	27.4	0.2	199	0.45	0.255	11
1287277	Soil		47.7	80.6	23.5	1663	1.7	305.1	14.5	958	2.45	118.6	9.0	1.4	86	10.6	31.5	0.2	190	1.05	0.214	9
1287278	Soil		25.4	81.7	16.6	2287	1.2	372.1	14.3	380	2.29	103.9	7.7	1.5	89	16.5	39.7	0.2	160	1.40	0.173	6
1287279	Soil		29.8	87.5	12.9	4602	0.7	770.7	8.4	438	2.84	103.9	7.3	0.9	104	42.6	70.2	0.3	170	2.17	0.131	4
1287280	Soil		31.8	57.3	28.8	1081	1.6	158.2	7.8	234	2.60	314.5	16.4	3.9	81	9.1	34.4	0.4	135	0.41	0.176	15
1287281	Soil		87.1	32.8	12.7	3046	0.9	284.6	16.5	795	5.38	198.7	7.7	1.0	52	22.3	67.1	0.2	186	0.81	0.190	6
1287282	Soil		112.5	23.4	13.9	1473	0.8	185.9	14.8	1301	4.34	197.0	9.7	1.3	50	7.9	38.3	0.2	125	0.69	0.137	6
1287283	Soil		32.8	51.9	27.1	625	1.4	91.9	6.8	189	2.40	183.3	23.6	3.9	68	3.7	21.2	0.3	103	0.41	0.130	14
1287284	Soil		29.6	56.7	23.2	412	1.5	77.1	7.9	230	2.71	176.0	13.8	2.9	74	4.0	13.8	0.3	102	0.44	0.133	10
1287285	Soil		25.6	60.6	20.2	436	1.4	76.2	9.5	169	2.62	77.6	10.8	3.0	78	3.3	13.4	0.3	108	0.38	0.144	12
1287286	Soil		31.5	69.5	29.3	897	1.4	154.0	11.7	509	3.75	229.3	22.2	3.1	80	9.7	30.8	0.5	122	0.52	0.180	16
1287287	Soil		12.2	32.9	32.8	451	1.6	52.5	8.1	574	2.58	187.6	60.2	1.9	54	4.3	18.2	1.0	50	0.44	0.103	12
1287288	Soil		12.1	54.8	14.4	185	0.9	37.2	6.8	183	2.08	34.4	3.5	1.1	77	4.0	7.3	0.2	108	0.19	0.145	7
1287289	Soil		9.2	14.7	13.2	83	0.2	15.8	2.3	38	1.03	18.4	2.1	0.2	17	0.3	2.8	0.2	74	0.02	0.034	10
1287290	Soil		13.0	62.7	15.7	269	0.9	54.9	5.4	111	1.99	35.4	4.9	1.9	90	2.9	8.1	0.2	120	0.22	0.134	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001856.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287261	Soil	57	0.20	672	0.005	6	0.74	0.008	0.12	0.3	0.68	3.0	2.1	0.05	3	8.5	<0.2
1287262	Soil	31	0.05	511	0.003	2	0.54	0.006	0.12	0.8	0.72	2.1	3.9	0.23	3	13.1	0.3
1287263	Soil	25	0.06	647	0.004	5	0.67	0.004	0.10	0.2	0.98	2.6	1.1	0.06	2	5.7	<0.2
1287264	Soil	12	0.05	243	0.005	4	0.44	0.005	0.08	0.1	0.22	0.5	0.5	<0.05	3	2.4	<0.2
1287265	Soil	13	0.04	236	0.003	2	0.45	0.003	0.09	0.2	0.25	1.5	0.6	<0.05	2	3.6	<0.2
1287266	Soil	17	0.06	351	0.004	2	0.51	0.003	0.09	0.2	0.36	1.8	0.7	<0.05	2	4.5	0.2
1287267	Soil	18	0.05	891	0.003	2	0.80	0.003	0.08	0.1	0.48	3.2	0.5	<0.05	1	5.4	<0.2
1287268	Soil	21	0.04	516	0.004	3	0.87	0.005	0.09	0.1	0.53	4.1	0.8	<0.05	1	3.7	<0.2
1287269	Soil	5	0.04	1140	0.006	3	0.45	0.020	0.02	<0.1	0.19	0.5	0.1	0.15	1	4.7	<0.2
1287270	Soil	8	0.04	1294	0.004	2	0.45	0.010	0.03	<0.1	0.59	1.6	0.2	0.18	<1	6.0	<0.2
1287271	Soil	20	0.08	744	0.003	5	0.60	0.005	0.11	0.2	0.72	3.1	1.5	0.11	2	5.8	<0.2
1287272	Soil	15	0.07	1025	0.003	5	0.66	0.016	0.07	0.2	0.89	1.6	1.2	0.09	2	4.0	<0.2
1287273	Soil	20	0.06	535	0.003	5	0.49	0.004	0.10	0.3	0.53	2.6	1.2	0.11	2	4.0	<0.2
1287274	Soil	22	0.20	1274	0.001	3	0.72	0.005	0.08	0.1	0.83	2.9	0.6	<0.05	2	3.3	<0.2
1287275	Soil	14	0.09	498	0.004	3	0.60	0.007	0.07	0.2	0.66	1.7	0.4	<0.05	2	3.4	<0.2
1287276	Soil	25	0.12	930	0.002	5	0.69	0.005	0.12	0.2	0.86	2.4	1.0	0.10	2	6.8	<0.2
1287277	Soil	23	0.17	918	0.002	6	0.85	0.008	0.11	0.2	1.47	3.1	1.6	0.15	2	5.0	<0.2
1287278	Soil	17	0.17	828	0.002	6	0.81	0.007	0.08	0.2	1.28	2.6	1.2	0.15	2	7.3	<0.2
1287279	Soil	9	0.12	1300	0.004	7	0.42	0.006	0.05	0.1	1.46	2.1	0.9	0.20	1	10.8	<0.2
1287280	Soil	17	0.12	1086	0.002	5	0.64	0.005	0.12	0.2	2.99	3.3	1.2	0.06	2	4.3	<0.2
1287281	Soil	13	0.09	640	0.004	3	0.57	0.011	0.05	0.1	1.20	1.8	0.9	0.05	2	10.1	<0.2
1287282	Soil	12	0.08	714	0.003	4	0.58	0.011	0.05	0.2	1.33	1.7	0.7	0.06	2	10.4	<0.2
1287283	Soil	16	0.11	983	0.002	4	0.52	0.004	0.07	0.2	1.28	2.5	0.7	0.05	2	4.8	<0.2
1287284	Soil	19	0.13	1278	0.002	3	0.67	0.005	0.08	0.2	1.36	2.9	0.6	0.08	2	4.6	<0.2
1287285	Soil	21	0.12	1081	0.003	4	0.69	0.005	0.10	0.2	0.97	3.5	0.7	<0.05	2	4.7	<0.2
1287286	Soil	16	0.10	627	0.002	5	0.70	0.005	0.10	0.2	4.57	3.6	1.1	0.10	2	5.8	<0.2
1287287	Soil	16	0.15	344	<0.001	3	0.71	0.006	0.09	0.3	6.45	1.7	0.6	0.09	2	4.6	<0.2
1287288	Soil	21	0.05	1409	0.002	3	0.53	0.004	0.08	0.1	0.67	2.4	0.4	<0.05	1	2.8	<0.2
1287289	Soil	9	0.02	284	0.006	1	0.33	0.005	0.05	0.1	0.17	0.3	0.2	<0.05	3	1.7	<0.2
1287290	Soil	22	0.06	2229	0.002	4	0.46	0.004	0.09	0.1	1.19	3.2	0.4	<0.05	1	3.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001856.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287031	Soil		2.4	14.3	13.2	65	0.2	13.5	4.0	84	1.94	14.3	1.3	0.2	10	0.3	1.2	0.2	44	0.02	0.062	7
1287032	Soil		2.2	11.5	10.9	58	0.2	11.9	3.7	79	2.00	13.3	1.7	0.4	9	0.2	1.1	0.2	35	0.02	0.052	5
1287033	Soil		1.5	9.1	4.9	34	<0.1	6.4	2.2	33	0.84	7.2	1.0	<0.1	6	<0.1	0.8	0.1	25	0.02	0.033	4
1287034	Soil		1.8	18.0	8.3	36	0.2	7.6	1.9	39	0.86	7.0	<0.5	0.1	11	0.5	0.6	0.2	28	0.03	0.053	5
1287035	Soil		0.8	12.5	8.5	28	0.2	6.9	2.0	73	0.78	4.1	<0.5	<0.1	8	0.3	0.4	<0.1	15	0.04	0.074	2
1287036	Soil		1.2	8.6	6.0	29	0.1	5.6	1.7	29	0.79	7.2	1.0	0.1	6	0.1	0.5	0.1	21	0.02	0.029	4
1287037	Soil		2.0	16.0	5.9	69	0.1	16.9	5.9	65	1.84	14.9	<0.5	0.8	4	<0.1	1.2	0.2	39	<0.01	0.029	4
1287038	Soil		31.5	54.4	19.6	402	1.2	88.4	9.8	158	2.97	106.5	16.0	2.5	55	2.6	18.7	0.5	139	0.11	0.152	15
1287039	Soil		0.9	8.2	4.0	34	0.4	7.6	2.4	114	0.85	5.5	<0.5	0.3	5	0.6	0.5	<0.1	18	0.02	0.022	2
1287040	Soil		0.4	5.0	1.8	13	0.3	3.5	1.5	24	0.44	3.4	<0.5	<0.1	4	<0.1	0.8	<0.1	10	0.02	0.014	<1
1287041	Soil		1.5	12.2	7.2	43	0.1	10.5	2.9	40	1.15	8.7	1.3	0.2	5	0.1	1.2	0.1	17	0.02	0.031	3
1287042	Soil		2.9	25.8	15.0	109	0.2	27.6	15.1	346	2.59	18.2	2.0	1.2	11	0.4	2.4	0.2	29	0.04	0.052	6
1287043	Soil		2.3	20.3	12.2	80	0.1	26.8	9.1	136	2.29	24.5	0.8	0.5	10	0.1	5.8	0.2	21	0.04	0.043	2
1287044	Soil		39.4	18.2	9.7	449	1.8	68.6	3.5	103	1.89	34.5	<0.5	0.2	34	2.7	9.7	0.2	153	0.57	0.067	10
1287045	Soil		21.4	29.8	11.0	347	0.5	64.6	5.1	107	1.85	36.4	0.6	0.6	33	3.1	4.6	0.2	104	0.38	0.062	11
1287046	Soil		0.8	5.3	3.5	36	<0.1	7.0	2.5	210	0.78	3.6	<0.5	<0.1	7	<0.1	0.2	<0.1	9	0.05	0.027	<1
1287047	Soil		35.5	32.1	5.8	220	0.8	55.0	1.4	18	0.90	21.1	<0.5	0.2	8	1.8	12.5	0.1	306	0.07	0.067	7
1287048	Soil		43.9	23.7	21.5	150	3.2	36.1	3.4	45	1.94	33.1	1.0	0.5	42	0.7	10.7	0.3	326	0.02	0.051	14
1287049	Soil		23.6	46.6	21.7	449	0.8	99.4	10.9	293	4.46	76.1	3.9	2.0	44	0.8	7.5	0.4	137	0.14	0.272	13
1287050	Soil		47.7	28.7	19.9	77	2.2	15.8	1.5	35	1.37	31.3	<0.5	0.4	117	0.4	15.5	0.3	160	0.05	0.083	18
1287101	Soil		15.5	26.0	42.3	37	0.8	17.3	3.0	80	2.10	21.1	3.2	0.3	53	<0.1	4.3	0.3	74	0.02	0.078	5
1287102	Soil		7.5	41.8	40.2	53	2.0	27.7	5.4	103	3.74	42.1	6.7	0.3	111	0.1	4.2	0.3	64	0.04	0.187	5
1287103	Soil		10.0	141.1	61.7	86	3.3	104.3	15.0	236	7.03	46.4	5.3	1.2	82	0.2	6.9	0.3	105	0.04	0.168	5
1287104	Soil		6.7	237.9	24.4	135	1.5	171.2	22.0	429	6.35	52.1	4.5	2.0	60	0.3	3.0	0.3	95	0.06	0.170	3
1287105	Soil		5.1	94.2	26.0	76	1.1	66.5	13.1	454	3.32	35.2	3.7	0.9	36	0.3	3.6	0.3	63	0.07	0.132	6
1287106	Soil		10.1	98.1	28.0	445	1.1	83.9	25.2	801	3.77	33.4	4.4	0.8	33	2.9	5.1	0.4	55	0.28	0.133	5
1287107	Soil		145.5	100.2	15.2	1488	1.2	367.3	12.3	236	3.18	90.3	1.0	3.8	144	10.0	24.2	0.2	271	4.27	0.113	10
1287108	Soil		4.7	27.9	13.1	80	0.4	19.0	6.1	267	1.32	9.5	1.8	0.2	15	0.6	2.1	0.2	34	0.07	0.099	4
1287109	Soil		8.2	121.5	33.3	141	0.9	94.1	33.6	852	6.81	63.8	6.5	4.9	30	1.0	6.8	0.7	49	0.22	0.100	43
1287110	Soil		6.5	82.8	21.5	92	1.0	55.9	18.4	739	4.63	21.1	5.4	0.7	38	0.6	3.3	0.5	49	0.21	0.186	25

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001856.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287031	Soil	13	0.08	126	0.003	<1	0.54	0.008	0.05	0.1	0.03	0.6	0.1	<0.05	3	0.8	<0.2
1287032	Soil	10	0.07	107	0.003	<1	0.56	0.009	0.04	<0.1	0.04	0.8	0.1	<0.05	3	0.8	<0.2
1287033	Soil	5	0.02	73	0.003	<1	0.38	0.016	0.02	0.1	0.03	0.3	<0.1	<0.05	3	<0.5	<0.2
1287034	Soil	6	0.03	170	0.003	<1	0.56	0.010	0.04	<0.1	0.02	0.2	<0.1	<0.05	3	<0.5	<0.2
1287035	Soil	7	0.04	98	0.002	2	0.45	0.018	0.05	<0.1	0.03	0.3	0.2	<0.05	2	<0.5	<0.2
1287036	Soil	5	0.03	80	0.003	<1	0.41	0.012	0.03	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2
1287037	Soil	6	0.02	65	0.001	<1	0.55	0.006	0.03	<0.1	0.02	1.4	0.1	<0.05	3	<0.5	<0.2
1287038	Soil	18	0.11	612	0.003	1	0.79	0.004	0.09	0.4	5.28	2.3	1.1	0.08	2	5.6	<0.2
1287039	Soil	4	0.02	95	0.002	<1	0.42	0.015	0.04	<0.1	0.01	0.6	<0.1	<0.05	2	<0.5	<0.2
1287040	Soil	2	0.01	35	0.004	<1	0.17	0.023	0.03	<0.1	0.03	0.4	<0.1	<0.05	<1	<0.5	<0.2
1287041	Soil	6	0.04	124	0.002	<1	0.44	0.015	0.04	<0.1	0.08	0.7	0.1	<0.05	2	0.5	<0.2
1287042	Soil	12	0.13	260	0.003	<1	0.67	0.006	0.06	<0.1	0.19	2.0	0.3	<0.05	2	1.3	<0.2
1287043	Soil	8	0.03	137	<0.001	1	0.37	0.006	0.05	<0.1	0.14	2.2	0.2	0.05	2	0.8	<0.2
1287044	Soil	14	0.09	499	0.002	3	0.45	0.010	0.06	0.3	0.23	0.5	1.0	0.09	2	3.7	<0.2
1287045	Soil	13	0.12	1193	0.002	2	0.68	0.008	0.06	0.3	0.30	1.2	0.7	0.07	2	1.4	<0.2
1287046	Soil	3	0.02	64	0.002	<1	0.36	0.020	0.04	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2
1287047	Soil	17	0.03	129	0.006	3	0.31	0.016	0.05	0.2	0.11	0.4	0.8	<0.05	2	4.5	<0.2
1287048	Soil	17	0.03	304	0.008	2	0.45	0.008	0.14	0.5	0.10	0.7	7.8	0.29	3	6.8	<0.2
1287049	Soil	18	0.05	705	0.005	3	0.64	0.005	0.09	0.2	0.27	2.0	0.6	0.12	2	4.4	<0.2
1287050	Soil	13	0.03	410	0.003	3	0.42	0.013	0.13	0.7	0.18	0.4	3.3	0.24	3	8.7	0.4
1287101	Soil	11	0.04	405	0.003	3	0.47	0.006	0.11	<0.1	0.22	0.6	0.8	0.23	2	3.4	<0.2
1287102	Soil	21	0.05	316	0.003	1	0.51	0.008	0.11	0.1	0.15	0.9	0.4	0.28	3	5.0	<0.2
1287103	Soil	30	0.09	192	0.003	2	1.01	0.006	0.10	<0.1	0.20	4.7	0.3	0.25	4	4.0	<0.2
1287104	Soil	26	0.07	124	0.001	<1	1.81	0.004	0.05	<0.1	0.13	8.9	0.3	0.08	3	2.9	<0.2
1287105	Soil	18	0.13	137	0.006	2	1.17	0.013	0.08	<0.1	0.06	3.2	0.3	0.16	3	2.3	<0.2
1287106	Soil	16	0.12	346	0.002	3	0.62	0.007	0.09	<0.1	0.18	4.0	0.4	0.11	2	3.0	0.2
1287107	Soil	17	1.53	497	0.004	4	0.28	0.005	0.08	0.3	2.06	4.0	1.6	0.10	<1	9.4	<0.2
1287108	Soil	8	0.04	130	0.004	2	0.46	0.018	0.05	<0.1	0.07	0.7	0.2	0.14	2	1.3	<0.2
1287109	Soil	10	0.10	858	0.005	4	0.46	0.006	0.11	<0.1	0.24	7.1	0.3	<0.05	1	1.7	0.3
1287110	Soil	10	0.06	412	0.003	4	0.47	0.008	0.07	<0.1	0.20	2.9	0.2	0.11	1	1.4	0.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001856.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1286920	Soil	7.5	50.0	38.1	219	2.5	48.4	5.6	211	2.46	244.9	121.9	2.9	54	3.1	20.0	1.3	46	0.24	0.105	13
REP 1286920	QC	6.9	48.8	35.9	218	2.5	47.8	5.6	198	2.43	248.3	121.3	2.8	52	2.6	22.9	1.3	45	0.23	0.103	12
1284443	Soil	12.9	19.2	19.5	185	0.2	37.5	6.0	109	2.21	25.3	0.7	0.6	11	0.3	2.9	0.2	52	0.04	0.069	9
REP 1284443	QC	12.9	19.9	19.6	183	0.2	37.8	6.2	112	2.20	25.3	1.6	0.7	11	0.4	2.9	0.2	53	0.04	0.073	10
1287142	Soil	57.7	76.2	12.2	372	0.5	172.6	10.2	328	2.42	32.1	3.4	0.9	83	3.6	5.7	0.1	103	2.83	0.114	11
REP 1287142	QC	60.8	77.2	12.4	385	0.5	172.0	10.1	336	2.49	33.3	<0.5	0.9	86	3.8	5.9	0.1	107	2.83	0.113	12
1287148	Soil	4.1	32.6	6.8	103	0.8	28.5	2.0	58	0.94	16.0	7.9	0.5	83	1.6	2.1	0.1	37	1.13	0.078	4
REP 1287148	QC	4.0	31.9	6.5	100	0.9	28.8	1.9	56	0.90	15.8	9.1	0.5	84	1.7	2.1	0.1	38	1.13	0.082	4
1287250	Soil	42.5	44.7	31.0	383	1.7	80.7	6.5	138	3.33	127.4	22.4	5.1	74	0.9	23.4	0.3	314	0.20	0.248	15
REP 1287250	QC	41.6	42.9	31.1	372	1.6	79.0	6.3	138	3.27	121.5	23.0	4.8	73	0.8	21.4	0.3	312	0.18	0.242	14
1287278	Soil	25.4	81.7	16.6	2287	1.2	372.1	14.3	380	2.29	103.9	7.7	1.5	89	16.5	39.7	0.2	160	1.40	0.173	6
REP 1287278	QC	24.7	79.5	16.9	2311	1.2	367.3	13.8	376	2.26	104.7	6.3	1.4	90	14.9	38.6	0.2	155	1.44	0.171	6
1287282	Soil	112.5	23.4	13.9	1473	0.8	185.9	14.8	1301	4.34	197.0	9.7	1.3	50	7.9	38.3	0.2	125	0.69	0.137	6
REP 1287282	QC	117.0	24.1	14.2	1516	0.8	193.9	15.3	1320	4.46	204.6	11.6	1.4	51	8.2	37.6	0.2	128	0.72	0.146	7
1287048	Soil	43.9	23.7	21.5	150	3.2	36.1	3.4	45	1.94	33.1	1.0	0.5	42	0.7	10.7	0.3	326	0.02	0.051	14
REP 1287048	QC	42.7	23.3	21.7	148	3.1	34.9	3.2	44	1.98	33.4	<0.5	0.5	42	0.8	11.1	0.3	328	0.03	0.050	15
1287107	Soil	145.5	100.2	15.2	1488	1.2	367.3	12.3	236	3.18	90.3	1.0	3.8	144	10.0	24.2	0.2	271	4.27	0.113	10
REP 1287107	QC	140.4	99.2	14.9	1491	1.1	361.1	11.9	229	3.06	90.6	0.9	3.9	140	9.7	24.4	0.2	290	4.13	0.107	11
Reference Materials																					
STD DS8	Standard	13.2	110.8	127.7	302	1.8	38.4	7.6	593	2.36	26.3	108.7	7.2	71	2.4	5.8	6.8	43	0.69	0.073	17
STD DS8	Standard	13.5	115.2	122.3	307	1.8	38.6	8.0	616	2.35	25.5	103.9	6.7	73	2.0	5.2	6.7	44	0.67	0.076	14
STD DS8	Standard	12.9	107.2	123.4	295	1.7	37.5	7.2	584	2.26	25.4	101.4	6.4	71	2.2	5.3	6.6	39	0.65	0.073	13
STD DS8	Standard	14.0	106.3	127.6	313	1.9	37.4	7.3	608	2.47	27.4	117.1	6.7	73	2.5	5.5	6.5	40	0.72	0.086	16
STD DS8	Standard	11.3	108.2	117.6	305	1.6	37.0	7.1	571	2.36	25.8	121.8	5.4	62	2.2	5.4	6.2	39	0.62	0.076	11
STD DS8	Standard	12.4	107.8	125.5	289	1.7	35.2	7.3	554	2.25	25.8	102.5	6.5	68	2.3	5.4	6.5	38	0.63	0.072	13
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001856.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1286920	Soil	17	0.09	570	0.003	2	0.66	0.005	0.07	0.3	16.15	2.7	0.7	0.07	2	7.8	0.3
REP 1286920	QC	15	0.09	575	0.001	3	0.65	0.004	0.07	0.5	15.66	2.5	0.7	<0.05	2	7.3	0.2
1284443	Soil	9	0.04	117	0.002	1	0.50	0.006	0.06	0.1	0.08	0.8	0.2	<0.05	3	1.4	<0.2
REP 1284443	QC	10	0.05	124	0.003	1	0.51	0.006	0.06	0.1	0.08	0.8	0.2	<0.05	3	1.0	<0.2
1287142	Soil	19	1.21	404	0.004	3	0.39	0.008	0.04	0.2	0.26	2.7	1.1	0.09	<1	2.6	<0.2
REP 1287142	QC	19	1.24	415	0.004	4	0.40	0.009	0.05	0.2	0.28	2.7	1.2	0.08	<1	2.7	<0.2
1287148	Soil	11	0.08	1196	0.003	2	0.40	0.014	0.03	<0.1	0.87	1.3	0.2	0.09	1	1.7	<0.2
REP 1287148	QC	12	0.09	1243	0.004	3	0.45	0.014	0.04	0.1	0.85	1.5	0.2	0.14	1	1.4	<0.2
1287250	Soil	31	0.07	459	0.003	3	1.12	0.003	0.11	0.4	1.00	2.4	1.4	0.11	2	8.2	<0.2
REP 1287250	QC	30	0.07	435	0.003	3	1.09	0.003	0.11	0.3	1.00	2.4	1.4	0.11	2	6.9	<0.2
1287278	Soil	17	0.17	828	0.002	6	0.81	0.007	0.08	0.2	1.28	2.6	1.2	0.15	2	7.3	<0.2
REP 1287278	QC	17	0.17	803	0.002	6	0.79	0.007	0.08	0.2	1.26	2.5	1.2	0.13	2	7.5	<0.2
1287282	Soil	12	0.08	714	0.003	4	0.58	0.011	0.05	0.2	1.33	1.7	0.7	0.06	2	10.4	<0.2
REP 1287282	QC	13	0.09	742	0.003	3	0.61	0.012	0.05	0.1	1.29	1.8	0.6	0.09	2	10.1	<0.2
1287048	Soil	17	0.03	304	0.008	2	0.45	0.008	0.14	0.5	0.10	0.7	7.8	0.29	3	6.8	<0.2
REP 1287048	QC	17	0.03	318	0.004	2	0.45	0.006	0.14	0.4	0.11	0.7	8.1	0.28	3	7.5	<0.2
1287107	Soil	17	1.53	497	0.004	4	0.28	0.005	0.08	0.3	2.06	4.0	1.6	0.10	<1	9.4	<0.2
REP 1287107	QC	19	1.52	505	0.001	5	0.31	0.005	0.10	0.3	2.03	3.8	1.8	0.09	<1	9.6	0.2
Reference Materials																	
STD DS8	Standard	118	0.60	292	0.126	3	0.96	0.106	0.46	2.8	0.18	2.9	5.7	0.16	5	4.8	5.3
STD DS8	Standard	121	0.65	266	0.113	3	0.92	0.098	0.42	2.7	0.24	2.4	5.2	0.16	5	6.3	4.0
STD DS8	Standard	112	0.63	254	0.105	2	0.88	0.093	0.41	2.8	0.25	2.2	5.2	0.16	4	5.0	4.7
STD DS8	Standard	120	0.60	292	0.126	3	1.02	0.116	0.45	2.9	0.20	2.9	5.6	0.13	5	5.6	5.0
STD DS8	Standard	110	0.58	251	0.109	3	0.85	0.092	0.39	2.8	0.19	1.7	5.3	0.10	4	5.4	4.7
STD DS8	Standard	106	0.58	272	0.111	2	0.91	0.112	0.37	2.7	0.21	2.2	5.3	0.10	5	5.0	4.6
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001856.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001856.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 21, 2011
Report Date: December 02, 2011
Page: 1 of 9

CERTIFICATE OF ANALYSIS WHI11001857.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #29
P.O. Number
Number of Samples:

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	212	Sieve soil to 230 mesh			VAN
RJSV	212	Saving all or part of Soil Reject			VAN
1DX2	212	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279111	Soil	11.7	65.9	15.2	182	0.9	37.6	4.9	98	1.95	34.6	4.9	1.8	64	3.2	7.7	0.2	116	0.14	0.143	7
1279112	Soil	10.8	52.4	15.1	169	0.8	34.8	4.4	98	1.83	33.4	5.5	1.7	60	2.0	6.5	0.2	118	0.14	0.142	7
1279113	Soil	10.6	53.3	13.5	207	0.8	43.7	4.3	78	1.73	29.1	4.6	1.5	68	3.3	6.7	0.2	113	0.19	0.128	6
1279114	Soil	8.5	34.4	13.0	99	0.8	21.1	2.7	52	1.57	24.5	4.9	0.8	43	1.2	5.0	0.2	93	0.10	0.104	7
1279115	Soil	16.0	65.9	19.0	333	1.0	65.1	6.9	153	2.60	48.8	8.9	1.6	88	3.7	10.6	0.2	157	0.30	0.200	7
1279116	Soil	11.3	41.5	16.3	152	0.7	31.8	4.1	93	1.81	33.3	7.1	0.9	53	1.1	6.2	0.2	103	0.13	0.120	8
1279117	Soil	16.5	62.0	17.3	337	1.0	70.5	6.5	138	2.25	40.1	6.8	2.1	92	3.4	9.4	0.2	165	0.36	0.190	7
1279118	Soil	15.4	63.8	18.4	343	1.1	69.2	5.6	119	2.40	43.6	9.2	1.5	85	3.4	10.0	0.2	162	0.35	0.177	7
1279119	Soil	15.8	68.6	18.5	333	0.9	62.4	5.5	116	2.59	48.6	8.3	2.0	77	3.1	10.7	0.2	162	0.31	0.177	7
1279120	Soil	21.1	80.1	19.8	535	1.7	109.1	5.7	134	3.62	55.9	14.0	2.3	91	4.7	13.8	0.2	175	0.42	0.214	7
1281911	Soil	2.3	19.9	9.9	67	0.3	16.6	3.9	77	1.98	10.2	1.2	0.3	10	0.1	0.9	0.2	44	0.06	0.075	7
1281912	Soil	1.8	13.2	5.6	43	0.2	9.7	2.5	320	0.93	5.6	1.0	0.1	8	0.1	0.6	0.1	29	0.05	0.101	4
1281913	Soil	1.4	19.8	7.3	36	0.3	9.0	2.0	37	0.97	6.6	3.0	0.1	8	<0.1	0.7	0.1	23	0.03	0.045	4
1281914	Soil	2.5	18.2	5.7	59	0.1	13.4	3.3	65	1.21	6.9	0.6	0.2	8	0.1	1.0	0.1	49	0.07	0.069	9
1281915	Soil	2.0	25.9	10.3	91	0.4	26.1	5.6	132	2.17	10.5	2.5	0.5	15	0.2	0.7	0.1	29	0.04	0.069	4
1281916	Soil	2.6	33.8	18.7	133	0.8	39.8	8.9	174	2.93	17.9	2.5	1.6	24	0.4	1.2	0.2	30	0.04	0.072	5
1281917	Soil	3.2	73.2	8.0	118	0.8	33.8	3.7	32	2.94	13.2	2.4	2.0	49	0.2	0.7	0.1	30	0.09	0.038	2
1281918	Soil	3.5	51.1	17.1	191	1.2	67.4	12.0	140	3.81	12.5	4.9	0.5	25	0.3	1.5	0.2	39	0.06	0.148	3
1281919	Soil	13.5	27.3	12.8	210	0.5	63.5	7.8	89	2.36	24.4	3.7	0.6	12	0.4	3.2	0.2	35	0.06	0.136	13
1281920	Soil	28.5	48.1	20.1	190	0.8	105.1	61.3	1326	4.47	90.5	2.5	0.9	32	1.6	3.8	0.2	182	0.15	0.991	11
1281931	Soil	84.8	60.9	11.4	290	0.2	178.9	8.5	148	1.85	21.9	2.3	2.0	50	2.4	4.5	<0.1	62	4.40	0.062	4
1281932	Soil	87.1	73.3	13.9	446	0.3	198.4	9.0	235	2.10	22.9	2.4	0.9	57	3.4	4.1	0.1	73	3.30	0.067	5
1281933	Soil	95.5	59.2	10.3	551	0.2	176.3	8.3	91	2.18	23.9	1.1	0.3	9	1.3	6.2	0.1	82	0.13	0.060	5
1281934	Soil	139.3	188.5	25.4	2510	2.5	339.3	16.1	221	2.85	101.6	<0.5	0.9	215	17.7	43.7	0.2	653	8.45	0.095	6
1281935	Soil	24.8	48.6	8.5	1245	0.9	128.6	3.0	61	0.99	14.3	1.6	0.5	56	7.8	5.7	<0.1	122	1.43	0.114	6
1281936	Soil	35.8	13.8	5.0	72	<0.1	32.1	2.4	19	0.64	11.4	<0.5	0.1	3	0.1	1.5	<0.1	89	0.02	0.045	8
1281937	Soil	19.4	126.4	163.1	17	5.5	4.8	0.4	11	3.14	130.5	3.6	1.1	111	<0.1	8.8	0.3	176	0.02	0.097	4
1281938	Soil	4.9	17.8	45.5	17	1.9	5.4	1.0	42	0.78	29.9	1.2	<0.1	34	<0.1	2.1	0.1	35	0.03	0.060	2
1281939	Soil	5.1	25.3	45.6	13	1.5	5.2	0.8	15	1.41	36.8	3.0	0.9	30	<0.1	3.4	0.2	40	0.01	0.032	3
1281940	Soil	4.1	20.9	33.4	17	1.6	5.0	1.0	56	0.94	26.3	2.7	0.2	24	<0.1	2.4	0.2	37	0.02	0.046	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279111	Soil	22	0.04	1343	0.002	4	0.48	0.003	0.09	0.1	1.43	3.6	0.5	<0.05	1	2.1	<0.2
1279112	Soil	21	0.04	1435	0.002	5	0.49	0.002	0.09	0.1	1.03	3.0	0.5	<0.05	1	2.4	<0.2
1279113	Soil	21	0.04	1985	0.002	4	0.44	0.003	0.09	0.1	1.14	2.9	0.5	<0.05	1	1.4	<0.2
1279114	Soil	19	0.05	1400	0.003	2	0.54	0.003	0.07	0.1	0.71	1.6	0.4	<0.05	2	1.5	<0.2
1279115	Soil	26	0.06	2181	0.002	4	0.54	0.003	0.11	0.2	2.03	3.4	0.7	<0.05	2	2.5	<0.2
1279116	Soil	19	0.05	1724	0.003	4	0.53	0.005	0.08	0.2	0.94	2.0	0.5	0.05	2	2.2	<0.2
1279117	Soil	30	0.07	2278	0.003	6	0.58	0.003	0.14	0.1	1.80	3.8	0.7	0.07	2	3.4	<0.2
1279118	Soil	26	0.06	2074	0.002	6	0.55	0.004	0.12	0.1	1.87	3.4	0.7	0.09	2	3.1	<0.2
1279119	Soil	28	0.06	2155	0.003	6	0.58	0.003	0.11	0.1	1.92	4.0	0.6	0.07	2	3.4	0.2
1279120	Soil	30	0.08	1660	0.003	5	0.55	0.003	0.11	0.2	2.16	5.0	0.8	0.06	2	4.9	0.2
1281911	Soil	18	0.10	155	0.005	2	0.93	0.008	0.06	0.1	0.07	0.8	0.1	<0.05	4	1.0	<0.2
1281912	Soil	10	0.03	102	0.006	2	0.41	0.013	0.06	<0.1	0.09	0.3	<0.1	0.09	2	<0.5	<0.2
1281913	Soil	10	0.04	98	0.004	2	0.45	0.012	0.04	<0.1	0.04	0.7	<0.1	0.07	2	0.7	<0.2
1281914	Soil	13	0.04	166	0.004	3	0.56	0.009	0.07	0.1	0.04	0.6	0.1	0.08	3	0.7	<0.2
1281915	Soil	18	0.10	182	0.004	2	0.85	0.011	0.07	<0.1	0.04	1.9	0.1	0.06	3	1.5	<0.2
1281916	Soil	22	0.15	211	0.002	2	0.93	0.004	0.08	<0.1	0.12	2.9	0.1	0.06	2	1.8	<0.2
1281917	Soil	30	0.27	579	0.001	2	1.28	0.004	0.08	<0.1	0.18	5.5	<0.1	<0.05	3	3.0	<0.2
1281918	Soil	19	0.06	345	0.002	5	0.75	0.005	0.07	<0.1	0.17	2.7	0.2	0.12	2	3.5	<0.2
1281919	Soil	8	0.04	194	0.002	5	0.49	0.006	0.09	<0.1	0.16	1.3	0.3	<0.05	2	1.2	<0.2
1281920	Soil	26	0.07	539	0.009	7	1.02	0.004	0.12	0.1	0.31	2.1	0.5	0.14	2	2.6	<0.2
1281931	Soil	16	2.31	100	0.001	5	0.21	0.005	0.06	0.2	0.30	4.6	1.6	0.08	<1	2.1	<0.2
1281932	Soil	17	0.91	121	0.002	4	0.27	0.004	0.06	0.2	0.23	4.0	1.7	0.08	<1	2.2	<0.2
1281933	Soil	18	0.05	134	0.002	2	0.32	0.003	0.05	0.2	0.09	1.8	1.2	0.07	<1	2.2	<0.2
1281934	Soil	28	2.49	189	0.002	7	0.33	0.008	0.10	0.2	0.78	3.0	2.9	0.19	<1	15.0	<0.2
1281935	Soil	16	0.28	253	0.004	4	0.41	0.020	0.05	<0.1	0.52	2.6	0.5	0.09	<1	2.3	<0.2
1281936	Soil	10	0.03	118	0.003	3	0.43	0.005	0.07	0.1	0.02	0.6	0.8	<0.05	2	0.7	<0.2
1281937	Soil	40	<0.01	547	<0.001	2	0.34	0.004	0.13	<0.1	0.85	3.7	0.5	0.24	4	19.2	0.4
1281938	Soil	11	0.02	225	0.004	1	0.34	0.019	0.05	<0.1	0.15	0.7	0.2	0.11	2	3.0	<0.2
1281939	Soil	10	0.01	166	0.002	<1	0.17	0.005	0.11	<0.1	0.11	3.5	0.3	0.22	1	6.0	<0.2
1281940	Soil	11	0.02	136	0.003	2	0.34	0.012	0.08	<0.1	0.11	1.2	0.2	0.16	2	3.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281941	Soil		4.1	29.2	21.0	46	1.3	13.1	3.1	118	1.34	16.4	2.5	0.1	15	0.1	1.7	0.2	37	0.03	0.078	3
1281942	Soil		7.8	182.7	82.0	457	2.5	130.5	64.7	4420	6.76	34.0	8.1	0.9	51	2.9	5.6	0.5	63	0.20	0.164	6
1281943	Soil		139.6	58.6	173.7	511	6.1	104.6	8.9	198	3.32	49.3	5.5	2.9	70	1.1	28.9	0.4	283	0.33	0.098	12
1281944	Soil		7.8	105.3	47.4	198	1.6	53.5	18.1	553	4.18	36.5	4.4	1.6	33	0.8	4.7	0.3	55	0.05	0.089	5
1281945	Soil		49.5	50.0	11.7	403	0.4	138.9	5.5	192	1.43	25.7	1.0	2.6	215	8.6	6.2	0.1	168	12.31	0.053	9
1281946	Soil		87.7	78.0	19.6	406	0.3	237.7	11.0	491	3.02	26.2	0.5	1.8	72	3.6	6.0	0.2	135	2.79	0.086	11
1281947	Soil		128.8	103.3	16.8	1384	0.7	239.4	21.2	312	2.35	299.1	0.9	3.4	116	11.2	41.7	0.2	211	4.49	0.099	8
1281948	Soil		45.2	33.6	11.4	239	0.1	81.4	6.5	215	1.66	23.8	1.1	0.3	23	2.2	4.0	0.1	68	0.28	0.121	6
1281949	Soil		5.9	50.0	67.9	156	0.2	53.4	101.2	2933	3.67	32.7	1.7	1.2	31	0.6	1.8	0.4	34	0.27	0.159	4
1281950	Soil		1.5	18.0	5.8	45	0.2	7.5	6.1	357	1.41	4.8	<0.5	0.1	7	0.5	0.6	0.1	20	0.04	0.105	2
1286971	Soil		8.6	83.7	19.5	1046	1.2	87.5	9.3	177	2.15	55.4	2.4	2.1	30	5.8	5.3	0.6	171	0.94	0.175	8
1286972	Soil		3.9	17.3	9.6	125	0.4	20.1	2.8	76	1.57	36.7	1.6	0.4	12	1.5	2.2	0.2	105	0.15	0.083	13
1286973	Soil		3.0	33.0	12.1	491	4.9	27.2	5.5	150	1.27	35.6	1.2	0.5	20	4.7	1.6	0.6	86	0.48	0.130	6
1286974	Soil		4.6	58.1	15.5	383	0.9	46.2	9.2	185	2.08	210.3	2.4	1.9	31	6.4	2.0	0.8	158	0.87	0.125	8
1286975	Soil		6.4	49.4	14.2	284	0.5	43.7	7.4	162	2.27	62.2	2.0	3.3	17	2.6	3.4	0.4	201	0.52	0.159	14
1286976	Soil		33.9	74.1	18.4	606	0.9	103.6	11.1	263	2.06	35.3	1.1	2.1	139	8.6	7.8	0.2	191	3.74	0.136	10
1286977	Soil		17.4	63.5	15.0	364	1.1	43.3	6.5	137	1.84	48.7	1.8	0.2	7	3.4	8.6	0.5	64	0.13	0.148	7
1286978	Soil		24.2	119.8	37.7	854	1.7	70.2	8.0	204	2.84	275.4	3.9	0.4	22	6.2	9.8	0.4	169	0.65	0.340	10
1286979	Soil		5.7	40.2	8.7	166	0.5	21.3	3.0	137	1.13	32.4	1.6	0.4	16	1.5	2.4	0.2	57	0.27	0.134	5
1286980	Soil		16.5	116.5	22.7	458	1.7	59.0	9.5	160	3.12	210.6	3.8	0.9	21	1.5	7.8	0.3	118	0.50	0.241	10
1286991	Soil		1.7	27.5	4.9	49	0.7	8.6	2.4	51	0.64	8.9	0.8	0.2	16	5.0	0.6	<0.1	40	0.33	0.067	3
1286992	Soil		27.6	64.7	19.5	409	1.1	101.3	5.1	172	1.18	23.6	1.4	0.9	119	7.8	6.7	0.1	146	3.00	0.088	6
1286993	Soil		31.8	85.0	18.0	766	1.0	130.1	9.9	306	2.07	35.3	2.2	1.5	118	11.3	9.3	0.2	227	2.85	0.139	8
1286994	Soil		7.4	25.1	7.8	131	0.4	29.0	19.2	1531	1.93	9.1	1.9	0.6	110	2.9	1.4	0.1	35	1.81	0.091	4
1286995	Soil		4.8	25.7	13.4	132	0.4	25.2	7.3	178	1.72	13.3	1.7	1.5	62	1.3	1.2	0.1	54	0.71	0.078	6
1286996	Soil		5.1	21.2	5.7	95	0.4	28.8	6.7	389	1.47	7.2	1.7	0.4	54	1.6	1.1	0.1	37	0.78	0.078	4
1286997	Soil		4.4	21.0	12.1	120	<0.1	22.8	7.2	178	2.85	14.5	1.1	0.9	14	0.6	1.1	0.2	45	0.11	0.026	3
1286998	Soil		6.1	25.2	12.7	138	0.2	29.4	7.1	119	2.31	13.7	1.8	2.2	36	0.8	1.4	0.2	50	0.29	0.073	6
1286999	Soil		4.3	32.7	14.0	158	0.4	36.2	10.4	196	2.50	14.1	1.9	2.6	45	1.0	1.4	0.2	45	0.42	0.078	6
1287000	Soil		3.3	25.1	14.9	118	0.4	26.8	5.9	97	2.01	15.0	2.3	2.2	39	1.0	1.2	0.2	50	0.52	0.055	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281941	Soil	11	0.03	88	0.003	2	0.38	0.014	0.06	<0.1	0.08	1.1	0.2	0.10	2	1.5	<0.2
1281942	Soil	19	0.08	283	0.002	3	0.62	0.005	0.11	<0.1	0.31	8.5	1.1	0.13	2	4.6	<0.2
1281943	Soil	16	0.04	259	0.001	4	0.37	0.004	0.19	0.2	0.64	4.3	2.9	0.23	1	14.1	0.5
1281944	Soil	14	0.04	139	0.002	1	0.41	0.005	0.09	<0.1	0.14	7.1	0.5	0.13	2	4.7	<0.2
1281945	Soil	19	5.57	161	0.002	8	0.25	0.009	0.10	0.1	0.36	3.6	2.0	0.07	<1	2.2	<0.2
1281946	Soil	19	1.04	240	0.003	4	0.37	0.003	0.09	0.2	0.60	4.9	1.7	<0.05	1	1.6	<0.2
1281947	Soil	19	2.17	734	0.002	7	0.24	0.004	0.08	0.2	2.51	3.1	2.7	0.12	<1	5.9	<0.2
1281948	Soil	11	0.05	229	0.003	2	0.40	0.008	0.04	0.2	0.10	0.8	0.7	0.05	1	1.3	<0.2
1281949	Soil	28	0.46	232	0.003	2	1.53	0.006	0.08	<0.1	0.13	2.7	0.6	0.09	4	0.8	<0.2
1281950	Soil	12	0.04	95	0.003	<1	0.55	0.013	0.04	<0.1	0.03	0.3	<0.1	0.07	3	<0.5	<0.2
1286971	Soil	34	1.75	179	0.045	2	1.86	0.012	0.24	<0.1	0.05	1.8	0.5	0.05	5	2.1	<0.2
1286972	Soil	22	0.57	119	0.013	2	1.09	0.009	0.08	0.1	0.03	0.6	0.2	<0.05	4	0.8	<0.2
1286973	Soil	20	0.91	146	0.019	1	1.54	0.016	0.12	<0.1	0.05	0.8	0.3	0.06	4	1.1	<0.2
1286974	Soil	37	1.75	136	0.038	1	2.10	0.010	0.19	0.2	0.05	2.0	0.3	0.08	6	1.5	<0.2
1286975	Soil	41	1.70	149	0.053	<1	2.08	0.005	0.20	0.2	0.04	2.4	0.4	<0.05	6	1.2	<0.2
1286976	Soil	17	0.99	1036	0.002	7	0.36	0.005	0.12	0.1	0.56	3.6	0.9	0.08	1	3.8	<0.2
1286977	Soil	9	0.09	89	0.004	<1	0.39	0.005	0.09	0.1	0.02	0.3	0.3	0.06	2	2.8	<0.2
1286978	Soil	31	1.34	206	0.014	3	1.43	0.005	0.29	0.7	0.05	0.9	0.6	0.05	4	4.4	<0.2
1286979	Soil	13	0.52	102	0.011	<1	0.84	0.013	0.10	0.1	0.02	0.5	0.2	0.07	3	1.3	<0.2
1286980	Soil	29	1.64	235	0.021	4	1.73	0.005	0.49	0.5	0.05	1.5	0.5	<0.05	5	3.2	<0.2
1286991	Soil	10	0.41	115	0.017	<1	0.81	0.022	0.06	<0.1	0.02	0.5	0.1	0.07	3	1.6	<0.2
1286992	Soil	16	0.74	701	0.002	7	0.25	0.007	0.08	0.1	0.44	2.1	0.8	0.12	1	4.8	<0.2
1286993	Soil	19	0.74	1060	0.003	7	0.36	0.006	0.09	0.1	0.51	2.9	0.9	0.10	1	4.2	<0.2
1286994	Soil	10	0.20	984	0.004	5	0.63	0.014	0.03	<0.1	0.13	1.8	0.2	0.17	1	1.9	<0.2
1286995	Soil	14	0.17	924	0.003	1	0.72	0.009	0.05	<0.1	0.14	2.6	0.1	0.07	2	1.7	<0.2
1286996	Soil	9	0.11	668	0.004	1	0.63	0.021	0.03	<0.1	0.13	2.1	0.1	0.08	2	1.4	<0.2
1286997	Soil	12	0.12	253	0.001	<1	0.45	0.006	0.05	<0.1	0.02	2.6	<0.1	<0.05	2	0.9	<0.2
1286998	Soil	17	0.21	1244	0.003	<1	0.83	0.004	0.05	<0.1	0.08	2.6	0.1	<0.05	3	0.9	<0.2
1286999	Soil	19	0.24	1502	0.002	1	0.92	0.005	0.06	<0.1	0.14	4.1	0.2	<0.05	3	1.2	<0.2
1287000	Soil	18	0.23	1052	0.002	<1	0.95	0.005	0.06	0.1	0.17	3.1	0.2	<0.05	3	2.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288801	Soil		3.3	67.7	25.5	257	4.2	103.9	20.4	381	4.70	30.0	3.3	2.9	97	1.6	1.8	0.2	43	1.57	0.269	13
1288802	Soil		3.0	43.0	18.6	164	3.2	64.1	8.4	162	2.89	17.5	4.3	1.7	82	0.9	1.5	0.3	47	1.39	0.190	13
1288803	Soil		3.5	63.7	21.8	267	3.1	95.2	11.8	145	3.89	22.0	3.5	3.0	90	1.8	2.1	0.3	50	1.47	0.305	15
1288804	Soil		1.5	50.7	13.6	139	1.7	53.6	7.4	124	2.27	11.3	7.3	1.1	58	0.5	0.8	0.2	24	1.44	0.101	8
1288805	Soil		5.5	71.1	28.2	274	2.5	83.6	17.5	305	3.81	26.4	5.2	2.1	92	1.7	2.1	0.3	44	1.15	0.202	12
1288806	Soil		2.9	47.8	16.3	200	1.8	68.7	9.7	143	2.60	15.9	3.0	1.8	89	1.0	1.4	0.2	37	1.50	0.177	9
1288807	Soil		2.8	38.3	24.0	123	0.3	29.2	5.0	228	3.26	189.3	10.9	0.7	32	0.5	6.7	0.2	39	0.05	0.131	6
1288808	Soil		4.6	69.7	28.1	117	2.7	30.7	6.7	154	4.21	99.3	9.5	2.6	94	0.3	3.1	0.3	34	0.04	0.138	5
1288809	Soil		10.9	45.5	9.5	273	0.3	78.9	10.7	126	2.92	16.3	0.8	0.9	9	0.6	3.5	0.2	63	0.14	0.099	11
1288810	Soil		6.1	56.1	6.4	153	0.2	168.4	24.3	377	3.85	42.9	1.0	2.1	36	1.1	2.4	<0.1	66	1.02	0.205	44
1288811	Soil		18.2	100.1	12.3	214	0.4	388.2	74.9	1143	8.66	82.7	1.3	6.5	57	1.9	4.7	<0.1	138	1.10	0.248	62
1288812	Soil		32.6	100.7	18.8	321	0.7	351.1	57.0	685	6.53	98.7	2.7	5.7	92	2.6	8.4	0.1	157	1.57	0.206	49
1288813	Soil		49.4	118.4	17.2	733	0.8	483.7	59.8	787	7.63	227.3	7.5	7.2	108	6.1	11.4	0.2	228	1.13	0.248	58
1288814	Soil		13.4	123.2	14.8	244	0.3	480.0	88.6	1112	8.36	148.7	3.5	16.8	224	1.0	5.1	0.1	108	2.55	0.486	130
1288815	Soil		33.3	101.1	11.6	416	0.5	384.2	50.9	588	6.63	84.1	3.9	5.1	103	3.0	5.8	0.1	271	1.27	0.238	55
1288816	Soil		64.8	83.4	12.5	1011	0.8	343.9	37.6	707	4.97	49.2	2.9	3.8	58	6.9	11.7	0.2	453	0.41	0.241	48
1288817	Soil		160.0	162.7	18.3	1891	2.9	398.4	16.8	325	2.05	74.2	2.6	2.6	201	14.4	32.3	0.3	1228	6.78	0.131	21
1288818	Soil		111.4	78.7	21.7	935	1.3	133.9	4.1	88	1.60	86.3	1.9	0.5	32	12.1	35.7	0.2	1890	0.39	0.130	21
1288819	Soil		139.4	160.8	22.1	2389	2.3	307.8	7.3	157	1.97	89.9	1.9	1.4	86	31.4	37.8	0.3	1389	1.90	0.156	28
1288820	Soil		143.8	83.4	22.7	1163	0.7	180.6	5.3	50	2.05	99.4	1.3	0.7	28	10.5	41.4	0.3	1539	0.40	0.113	30
1288821	Soil		76.9	86.5	9.2	942	0.8	184.7	6.4	109	1.35	39.8	1.2	1.1	70	8.6	12.0	0.1	289	4.56	0.101	12
1288822	Soil		46.1	24.2	7.2	374	0.3	76.2	4.7	66	1.23	20.0	0.8	0.2	8	2.1	5.9	0.1	111	0.17	0.087	5
1288823	Soil		19.5	21.7	5.0	193	0.2	45.2	4.2	64	1.09	12.1	<0.5	0.2	5	0.6	3.0	0.1	64	0.05	0.088	4
1288824	Soil		113.5	86.2	14.9	935	0.5	266.0	12.5	236	2.88	46.4	2.0	1.3	68	6.0	11.1	0.2	203	1.89	0.127	13
1288825	Soil		4.5	44.6	19.0	94	1.2	45.6	11.4	322	3.57	11.8	3.3	0.7	21	0.4	1.5	0.2	21	0.13	0.135	9
1288826	Soil		8.6	53.1	20.8	179	1.0	53.5	12.3	260	3.40	17.5	2.1	0.7	34	0.5	1.8	0.2	23	0.22	0.159	10
1288827	Soil		6.5	59.5	17.9	237	0.9	89.0	22.8	663	5.55	24.0	4.0	0.9	17	0.8	2.3	0.2	21	0.14	0.112	10
1288828	Soil		2.2	17.5	5.2	50	0.1	16.7	5.0	201	1.00	7.7	0.8	0.1	13	0.3	0.6	0.1	17	0.14	0.076	4
1288829	Soil		21.9	41.5	19.8	200	<0.1	88.3	20.4	265	4.93	50.5	<0.5	0.7	5	0.3	3.6	0.3	32	0.03	0.088	9
1288830	Soil		4.0	15.9	6.5	55	0.1	16.9	3.6	160	0.90	7.1	1.6	<0.1	9	<0.1	0.7	0.1	19	0.04	0.118	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288801	Soil	32	0.24	697	0.003	5	0.91	0.009	0.10	<0.1	0.33	5.7	0.3	0.14	2	6.5	<0.2
1288802	Soil	30	0.12	721	0.002	8	0.78	0.007	0.12	<0.1	0.25	3.6	0.3	0.12	2	3.4	<0.2
1288803	Soil	30	0.18	592	0.004	6	0.88	0.008	0.14	<0.1	0.21	4.9	0.3	0.11	2	5.1	<0.2
1288804	Soil	19	0.19	529	<0.001	6	0.64	0.005	0.08	<0.1	0.21	3.6	0.1	0.12	1	2.8	<0.2
1288805	Soil	30	0.21	569	0.003	5	0.97	0.011	0.15	<0.1	0.41	4.1	0.3	0.18	2	3.9	<0.2
1288806	Soil	21	0.10	462	0.002	5	0.78	0.010	0.12	<0.1	0.21	3.7	0.2	0.09	2	3.7	<0.2
1288807	Soil	23	0.09	219	0.004	<1	0.77	0.005	0.08	0.2	0.57	1.7	0.1	0.10	3	1.8	<0.2
1288808	Soil	38	0.11	604	0.002	3	1.02	0.009	0.14	<0.1	0.26	4.0	0.3	0.22	3	4.9	<0.2
1288809	Soil	19	0.05	459	0.005	<1	0.50	0.005	0.05	<0.1	0.08	1.8	0.2	<0.05	2	2.1	<0.2
1288810	Soil	48	0.13	2329	0.006	4	0.93	0.015	0.06	<0.1	0.08	6.9	0.1	0.10	2	1.3	<0.2
1288811	Soil	100	0.28	2097	0.004	7	0.82	0.004	0.13	0.1	0.19	19.5	0.4	<0.05	2	1.8	<0.2
1288812	Soil	76	0.46	1431	0.003	9	0.73	0.007	0.13	0.2	0.34	14.2	1.0	0.10	2	5.2	<0.2
1288813	Soil	91	0.26	1626	0.005	12	0.95	0.008	0.15	0.1	0.40	15.4	1.1	0.13	3	4.0	<0.2
1288814	Soil	143	0.63	1568	0.008	14	1.03	0.004	0.21	0.1	0.15	22.3	0.5	0.15	3	3.3	<0.2
1288815	Soil	191	0.69	2596	0.007	13	1.58	0.005	0.17	0.2	0.27	17.0	1.0	0.12	5	2.7	<0.2
1288816	Soil	130	0.44	2522	0.011	10	1.63	0.004	0.14	0.2	0.14	8.4	2.2	0.05	5	6.7	<0.2
1288817	Soil	76	2.74	677	0.010	15	0.73	0.012	0.16	0.5	0.82	4.9	6.6	0.10	3	12.0	0.2
1288818	Soil	106	0.19	699	0.007	7	1.10	0.006	0.12	0.5	0.40	1.0	3.7	0.11	5	9.7	<0.2
1288819	Soil	83	0.87	671	0.007	9	1.07	0.007	0.19	0.6	0.38	3.4	3.1	0.08	3	8.5	0.2
1288820	Soil	79	0.25	615	0.007	11	0.96	0.004	0.22	0.5	0.24	1.2	4.6	0.08	4	10.6	<0.2
1288821	Soil	21	2.42	213	0.003	5	0.33	0.005	0.06	0.3	0.31	2.8	1.3	<0.05	<1	3.8	0.2
1288822	Soil	9	0.06	150	0.003	2	0.32	0.005	0.04	0.1	0.10	0.5	0.4	<0.05	1	2.1	<0.2
1288823	Soil	8	0.03	131	0.002	2	0.37	0.007	0.05	<0.1	0.05	0.2	0.3	<0.05	2	0.7	<0.2
1288824	Soil	17	0.87	282	0.003	4	0.30	0.003	0.07	0.3	0.51	2.9	1.4	<0.05	<1	3.3	<0.2
1288825	Soil	9	0.05	2271	0.004	2	0.70	0.008	0.06	<0.1	0.29	1.9	0.2	<0.05	1	1.1	<0.2
1288826	Soil	9	0.08	1983	0.004	2	0.80	0.008	0.07	<0.1	0.23	1.4	0.2	<0.05	1	1.8	<0.2
1288827	Soil	10	0.05	1014	0.005	2	0.59	0.010	0.06	<0.1	0.14	3.4	0.2	<0.05	2	1.1	<0.2
1288828	Soil	6	0.05	521	0.005	1	0.47	0.015	0.03	<0.1	0.07	0.6	<0.1	<0.05	2	<0.5	<0.2
1288829	Soil	8	0.03	256	0.003	2	0.44	0.003	0.09	<0.1	0.04	1.1	0.2	<0.05	2	0.7	<0.2
1288830	Soil	5	0.02	213	0.002	1	0.37	0.009	0.06	<0.1	0.05	0.2	<0.1	<0.05	1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288831	Soil		5.8	32.1	14.3	102	0.3	48.1	5.5	133	1.33	23.0	2.3	0.1	29	0.3	1.9	0.1	30	0.06	0.136	4
1288832	Soil		3.9	16.4	7.2	46	0.2	19.9	2.7	55	0.74	9.5	1.0	<0.1	7	0.2	1.0	<0.1	17	0.02	0.091	2
1288833	Soil		13.8	82.1	39.6	360	1.2	64.2	10.3	439	3.12	40.6	3.3	0.3	20	1.2	4.2	0.2	57	0.16	0.259	7
1288834	Soil		5.3	17.1	14.6	49	0.2	13.9	2.3	42	0.94	9.3	1.4	<0.1	14	<0.1	0.9	0.2	42	0.03	0.137	6
1288835	Soil		4.2	13.8	13.0	22	0.3	6.0	1.1	48	0.62	6.4	<0.5	<0.1	13	<0.1	0.6	0.1	31	0.06	0.181	5
1288836	Soil		12.8	25.5	38.9	21	1.2	6.5	1.0	34	0.96	10.4	<0.5	0.4	30	0.2	1.4	0.3	54	0.04	0.244	13
1288837	Soil		11.8	40.3	53.7	179	0.5	42.4	4.4	72	1.84	17.7	<0.5	0.1	39	0.3	1.5	0.5	54	0.02	0.138	10
1288838	Soil		9.1	36.3	21.2	185	0.2	53.8	8.7	166	2.40	22.2	0.6	<0.1	11	0.3	2.3	0.2	53	0.01	0.180	5
1288839	Soil		9.1	37.5	21.7	219	0.2	66.2	10.7	109	2.76	24.8	1.9	<0.1	12	0.2	2.5	0.3	48	0.01	0.139	7
1288840	Soil		13.7	40.3	31.8	193	0.7	56.1	8.3	76	2.59	25.7	2.8	0.2	51	0.3	2.8	0.4	87	0.02	0.147	10
1288841	Soil		7.9	103.0	37.0	203	0.3	71.5	18.8	259	6.57	22.6	7.2	0.9	27	0.5	3.1	0.4	33	0.14	0.103	3
1288842	Soil		9.5	78.6	27.1	327	0.9	66.2	18.7	617	4.53	23.8	7.8	1.3	21	1.4	4.2	0.3	50	0.08	0.103	6
1288843	Soil		50.8	141.9	18.2	1012	2.7	192.9	12.3	271	3.17	44.7	2.4	1.3	83	11.0	16.6	0.2	255	1.40	0.146	15
1288844	Soil		24.2	101.3	30.0	388	0.6	120.3	16.2	688	4.54	30.7	3.7	0.7	35	2.8	5.9	0.4	66	0.26	0.088	7
1288845	Soil		11.6	105.6	46.3	267	0.9	78.8	15.2	869	4.57	28.5	5.1	0.6	139	1.1	4.1	0.5	47	0.21	0.255	10
1288846	Soil		8.4	19.2	6.9	75	0.4	15.0	1.9	30	0.76	10.3	0.6	0.1	8	0.2	2.3	0.1	93	0.01	0.029	10
1288847	Soil		7.3	21.0	12.4	76	0.7	14.4	2.2	37	1.14	15.1	3.0	<0.1	14	0.3	2.2	0.2	100	0.02	0.063	9
1288848	Soil		24.5	105.1	24.2	438	3.0	79.0	13.3	393	3.62	58.5	8.9	0.8	91	5.0	13.1	0.3	217	0.18	0.279	9
1288849	Soil		22.5	129.4	21.8	801	2.9	147.0	11.9	229	3.42	52.3	8.5	1.6	119	8.6	13.2	0.2	218	0.49	0.223	9
1288850	Soil		27.5	150.5	24.8	916	3.9	163.7	13.9	423	3.99	62.1	11.3	1.0	122	13.0	16.5	0.3	253	0.54	0.291	10
1288851	Soil		13.7	61.4	39.0	923	0.2	61.1	9.2	107	4.10	33.7	1.9	0.4	12	1.4	4.1	0.2	61	0.32	0.266	11
1288852	Soil		26.6	73.8	24.5	454	0.4	111.4	11.3	120	3.69	44.7	3.6	0.8	13	1.3	5.8	0.3	83	0.03	0.129	11
1288853	Soil		7.4	11.5	11.7	61	<0.1	16.9	2.5	39	0.84	11.2	<0.5	0.1	6	0.2	1.0	0.2	51	0.02	0.054	8
1288854	Soil		8.3	18.3	8.9	85	0.2	20.8	4.2	41	0.98	11.7	<0.5	0.2	5	0.2	1.0	0.2	54	0.02	0.048	11
1288855	Soil		6.0	26.0	21.6	146	0.3	40.3	5.8	53	1.49	55.0	1.4	0.1	12	0.1	1.6	0.2	33	0.02	0.081	8
1288856	Soil		15.1	64.2	20.5	218	0.7	77.6	9.2	89	2.67	26.5	3.7	1.2	48	0.5	3.2	0.3	53	0.46	0.370	15
1288857	Soil		8.8	37.3	21.2	142	0.4	58.3	12.2	251	2.33	24.6	3.5	0.2	46	0.4	2.4	0.3	32	0.24	0.157	13
1288858	Soil		10.7	34.7	24.8	158	0.7	47.3	8.1	215	2.41	48.5	7.6	0.2	29	0.4	2.9	0.3	51	0.06	0.172	10
1288859	Soil		7.5	52.0	19.9	171	0.8	60.8	8.5	126	2.43	16.2	1.9	0.8	52	0.5	2.2	0.3	40	0.21	0.190	13
1288860	Soil		4.6	34.7	15.4	106	0.6	36.7	7.9	204	2.03	16.4	3.1	0.9	32	0.2	1.7	0.3	24	0.25	0.147	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288831	Soil	8	0.02	191	0.003	1	0.35	0.011	0.04	<0.1	0.05	0.4	<0.1	<0.05	1	0.7	<0.2
1288832	Soil	5	0.01	68	0.001	1	0.31	0.010	0.03	<0.1	0.04	0.4	<0.1	<0.05	1	<0.5	<0.2
1288833	Soil	12	0.03	335	0.003	2	0.35	0.003	0.07	0.1	0.25	1.0	0.3	<0.05	1	2.4	<0.2
1288834	Soil	10	0.02	93	0.003	<1	0.52	0.009	0.04	<0.1	0.04	0.2	0.2	<0.05	2	0.6	<0.2
1288835	Soil	9	0.03	136	0.003	<1	0.35	0.014	0.04	0.1	0.04	0.4	0.1	0.05	2	0.9	<0.2
1288836	Soil	11	0.02	186	0.006	1	0.54	0.011	0.07	0.2	0.06	0.4	0.3	0.12	2	1.8	<0.2
1288837	Soil	12	0.02	269	0.002	3	0.36	0.004	0.10	<0.1	0.05	0.3	0.2	0.08	2	2.5	0.3
1288838	Soil	11	0.02	122	0.002	2	0.45	0.003	0.06	<0.1	0.03	0.3	0.2	<0.05	2	1.4	<0.2
1288839	Soil	8	0.02	141	0.001	2	0.38	0.003	0.06	<0.1	0.06	0.5	0.2	<0.05	2	1.9	<0.2
1288840	Soil	13	0.02	193	0.003	3	0.36	0.002	0.09	<0.1	0.04	0.5	0.3	0.08	2	1.8	<0.2
1288841	Soil	12	0.05	791	0.002	3	0.38	0.003	0.08	<0.1	0.21	4.6	0.2	<0.05	1	2.1	<0.2
1288842	Soil	14	0.05	875	0.002	2	0.54	0.003	0.08	<0.1	0.21	3.9	0.3	<0.05	2	1.8	<0.2
1288843	Soil	27	0.46	1512	0.002	4	0.33	0.003	0.08	0.2	1.27	3.8	0.7	0.05	1	6.0	<0.2
1288844	Soil	11	0.03	2193	0.001	3	0.39	0.003	0.07	<0.1	0.82	3.6	0.3	<0.05	<1	2.2	0.3
1288845	Soil	13	0.03	1780	0.003	3	0.66	0.004	0.10	<0.1	0.49	3.6	0.2	0.13	2	2.6	0.3
1288846	Soil	11	0.01	187	0.004	2	0.25	0.003	0.03	0.1	0.06	0.5	0.2	<0.05	2	1.4	<0.2
1288847	Soil	15	0.03	234	0.005	<1	0.62	0.005	0.03	0.1	0.09	0.5	0.3	<0.05	4	1.5	<0.2
1288848	Soil	32	0.03	1042	0.003	3	0.44	0.003	0.08	0.2	0.96	2.6	0.9	0.11	2	8.1	0.3
1288849	Soil	31	0.07	1766	0.003	4	0.43	0.003	0.10	0.2	1.36	4.0	0.8	0.08	2	7.0	0.2
1288850	Soil	32	0.06	2241	0.003	4	0.44	0.003	0.10	0.2	2.17	3.8	1.1	0.09	2	9.3	0.3
1288851	Soil	13	0.04	175	0.004	3	0.43	0.003	0.06	0.1	0.27	1.9	0.3	<0.05	3	11.0	<0.2
1288852	Soil	12	0.02	226	0.001	2	0.35	0.002	0.05	0.2	0.11	2.0	0.3	<0.05	1	3.6	0.3
1288853	Soil	8	0.03	74	0.004	2	0.40	0.005	0.04	<0.1	0.03	0.4	0.2	<0.05	3	<0.5	<0.2
1288854	Soil	8	0.02	81	0.003	1	0.39	0.003	0.05	0.1	0.02	0.4	0.1	<0.05	3	<0.5	<0.2
1288855	Soil	6	0.01	85	0.003	2	0.26	0.008	0.06	<0.1	0.03	0.7	0.1	<0.05	2	1.3	<0.2
1288856	Soil	13	0.02	443	0.004	5	0.48	0.003	0.13	<0.1	0.33	2.4	0.2	<0.05	1	2.0	<0.2
1288857	Soil	8	0.05	429	0.002	2	0.32	0.004	0.07	<0.1	0.11	0.7	0.2	<0.05	1	1.3	<0.2
1288858	Soil	10	0.03	282	0.002	2	0.33	0.005	0.06	<0.1	0.12	0.6	0.2	<0.05	1	1.5	<0.2
1288859	Soil	16	0.04	548	0.002	4	0.35	0.004	0.08	<0.1	0.19	1.5	0.1	<0.05	1	2.0	<0.2
1288860	Soil	7	0.03	694	0.003	3	0.36	0.010	0.08	<0.1	0.18	1.5	0.1	<0.05	1	1.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288421	Soil		9.3	114.7	31.7	304	0.6	64.6	10.7	235	3.75	24.1	3.4	0.9	16	0.5	3.6	0.3	57	0.04	0.171	9
1288422	Soil		9.8	50.7	23.4	295	0.9	62.3	11.2	349	3.06	27.7	3.9	2.6	39	1.1	4.1	0.3	58	0.69	0.142	12
1288423	Soil		1.6	9.8	6.5	40	<0.1	9.7	4.4	99	1.10	5.3	<0.5	0.3	3	<0.1	0.6	0.2	15	0.01	0.025	5
1288424	Soil		3.8	16.6	21.9	79	0.1	18.6	6.3	225	2.36	13.3	0.6	0.7	9	<0.1	1.8	0.4	33	0.02	0.049	8
1288425	Soil		2.9	14.6	15.4	61	<0.1	19.4	10.4	150	2.40	23.1	<0.5	0.5	4	0.1	1.9	0.4	23	<0.01	0.037	6
1288426	Soil		5.0	23.4	10.8	140	<0.1	22.6	7.4	90	2.35	22.3	<0.5	0.4	3	0.2	2.5	0.3	24	0.01	0.042	4
1288427	Soil		3.1	12.0	9.9	59	0.2	12.0	2.7	53	1.04	8.5	1.6	0.1	7	0.4	1.1	0.2	19	0.03	0.057	5
1288428	Soil		10.4	64.7	30.9	385	0.7	60.1	11.0	360	3.02	32.4	4.0	1.4	30	2.5	4.7	0.3	48	0.53	0.198	11
1288429	Soil		5.7	27.1	17.7	186	0.5	28.0	5.3	257	2.96	19.7	1.3	0.7	17	0.7	2.5	0.2	58	0.08	0.254	7
1288430	Soil		8.7	141.8	37.5	267	1.1	101.0	20.1	598	6.19	41.3	4.2	2.4	45	1.1	7.3	0.4	41	0.27	0.276	8
1288431	Soil		2.8	25.3	12.9	50	0.3	8.8	1.5	43	0.98	8.3	1.4	0.2	11	0.7	1.0	0.2	28	0.07	0.063	9
1288432	Soil		3.5	10.5	12.2	54	0.2	11.0	2.5	48	1.00	9.3	0.7	0.3	10	0.1	1.1	0.2	33	0.02	0.054	7
1288433	Soil		7.0	36.2	19.0	142	0.4	43.5	7.5	110	2.40	17.6	1.3	0.3	21	0.4	2.7	0.3	37	0.04	0.103	11
1288434	Soil		1.7	6.9	9.1	29	0.1	6.4	2.0	79	0.71	5.4	0.7	0.2	11	<0.1	0.6	0.2	21	0.09	0.030	9
1288435	Soil		1.4	24.1	7.1	36	<0.1	23.0	7.1	89	2.52	9.5	1.0	0.9	3	<0.1	1.1	0.3	15	0.01	0.039	4
1288436	Soil		2.6	77.0	38.8	181	1.7	64.6	12.3	213	3.60	12.4	6.0	3.5	145	0.6	2.6	0.4	19	0.28	0.205	12
1288437	Soil		9.7	24.6	17.5	114	0.2	29.6	5.4	110	2.92	16.3	1.0	0.5	12	0.2	2.4	0.2	55	0.03	0.092	7
1288438	Soil		9.3	23.3	16.7	88	0.2	23.6	4.0	90	2.29	12.7	1.2	0.5	9	0.2	1.9	0.3	51	0.02	0.076	7
1288439	Soil		24.8	68.5	24.2	377	0.4	100.8	10.9	374	4.03	23.5	3.3	2.1	33	1.9	5.4	0.2	92	0.14	0.148	9
1288440	Soil		4.5	17.5	10.2	138	0.8	28.9	7.1	358	1.65	8.2	1.4	0.8	22	1.9	1.3	0.1	37	0.17	0.074	6
1288561	Soil		3.2	16.9	13.6	95	0.8	21.1	21.5	1101	2.09	12.4	3.5	0.6	86	1.1	0.9	0.2	36	0.38	0.100	3
1288562	Soil		2.5	21.5	12.6	124	0.8	40.8	18.2	977	1.97	11.1	2.9	0.9	217	1.8	1.4	0.2	31	1.04	0.107	4
1288563	Soil		3.7	28.6	12.9	232	0.9	44.5	22.4	1034	2.81	14.9	1.8	1.2	106	3.6	1.6	0.2	32	0.62	0.097	5
1288564	Soil		2.7	27.3	13.5	143	1.0	36.0	10.0	533	1.87	12.5	3.8	1.1	135	1.4	1.3	0.2	33	1.04	0.091	4
1288565	Soil		3.1	32.3	13.6	178	1.1	40.4	18.5	696	2.64	12.9	3.1	1.0	90	3.2	1.4	0.2	33	0.70	0.102	4
1288566	Soil		4.4	12.0	8.8	167	0.3	23.0	13.4	1356	12.96	17.6	1.7	0.8	43	2.4	1.1	<0.1	23	0.34	0.149	2
1288567	Soil		4.0	29.2	11.7	218	0.8	46.0	10.2	450	6.81	16.9	2.7	1.2	124	2.0	1.6	0.1	30	1.14	0.117	3
1288568	Soil		3.0	25.4	14.7	178	0.4	35.4	12.1	669	3.43	14.0	2.6	1.0	66	3.7	1.2	0.2	32	0.40	0.093	3
1288569	Soil		3.5	36.4	15.6	333	1.1	60.1	18.6	1140	2.90	17.6	3.0	1.4	104	4.6	1.5	0.2	35	0.86	0.096	5
1288570	Soil		32.3	71.1	20.3	634	0.8	102.9	9.9	262	2.26	34.0	1.0	2.6	118	5.8	7.3	0.2	147	3.12	0.153	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288421	Soil	14	0.05	160	0.003	2	0.47	0.003	0.05	<0.1	0.12	1.9	0.3	<0.05	2	2.1	<0.2
1288422	Soil	18	0.22	633	0.003	2	0.82	0.006	0.06	0.1	0.19	3.2	0.2	<0.05	2	1.6	<0.2
1288423	Soil	3	0.01	35	0.002	1	0.21	0.005	0.03	<0.1	0.02	0.5	<0.1	<0.05	2	<0.5	<0.2
1288424	Soil	9	0.06	63	0.006	<1	0.48	0.004	0.04	0.1	0.02	0.8	0.1	<0.05	3	<0.5	<0.2
1288425	Soil	4	0.02	46	0.003	<1	0.25	0.003	0.03	<0.1	0.01	0.7	<0.1	<0.05	2	<0.5	<0.2
1288426	Soil	4	0.02	49	0.004	1	0.22	0.004	0.04	<0.1	0.02	1.1	<0.1	<0.05	2	0.7	<0.2
1288427	Soil	7	0.04	163	0.002	1	0.30	0.008	0.04	<0.1	0.07	0.3	<0.1	<0.05	1	<0.5	<0.2
1288428	Soil	18	0.12	615	0.003	2	0.46	0.004	0.07	<0.1	0.28	3.5	0.2	<0.05	1	1.7	<0.2
1288429	Soil	18	0.06	201	0.004	<1	0.73	0.004	0.04	<0.1	0.11	1.2	0.1	<0.05	3	0.9	<0.2
1288430	Soil	14	0.04	396	0.002	1	0.46	0.002	0.05	<0.1	0.30	4.7	0.3	<0.05	<1	4.2	<0.2
1288431	Soil	9	0.04	270	0.003	<1	0.57	0.004	0.04	<0.1	0.09	0.3	0.2	<0.05	3	<0.5	<0.2
1288432	Soil	7	0.03	117	0.002	<1	0.49	0.004	0.03	<0.1	0.02	0.3	0.2	<0.05	3	0.6	<0.2
1288433	Soil	8	0.02	230	0.002	2	0.35	0.003	0.06	<0.1	0.07	0.8	0.2	<0.05	2	1.2	<0.2
1288434	Soil	6	0.05	245	0.004	<1	0.37	0.005	0.05	<0.1	0.01	0.2	0.1	<0.05	2	<0.5	<0.2
1288435	Soil	4	0.02	473	0.002	1	0.29	0.002	0.06	<0.1	0.02	1.1	<0.1	<0.05	2	<0.5	<0.2
1288436	Soil	11	0.02	2965	0.002	2	1.14	0.002	0.07	<0.1	0.35	4.5	0.1	<0.05	<1	3.6	<0.2
1288437	Soil	11	0.03	1747	0.004	<1	0.53	0.003	0.04	<0.1	0.03	0.8	0.2	<0.05	3	1.0	<0.2
1288438	Soil	9	0.02	1056	0.003	1	0.57	0.003	0.04	<0.1	0.03	0.6	0.1	<0.05	3	1.0	<0.2
1288439	Soil	19	0.04	1079	0.002	2	0.54	0.002	0.05	<0.1	0.19	3.5	0.3	<0.05	1	2.2	<0.2
1288440	Soil	12	0.08	2305	0.003	1	1.08	0.012	0.05	<0.1	0.14	1.8	0.2	<0.05	3	2.0	<0.2
1288561	Soil	12	0.14	699	0.001	1	0.84	0.010	0.06	<0.1	0.14	1.4	0.1	<0.05	3	1.3	<0.2
1288562	Soil	12	0.17	986	0.001	2	0.89	0.010	0.04	<0.1	0.25	2.1	0.1	0.09	2	5.2	<0.2
1288563	Soil	12	0.13	1047	0.001	<1	0.78	0.007	0.04	<0.1	0.27	2.4	0.1	0.08	2	4.0	<0.2
1288564	Soil	13	0.19	940	0.001	2	0.88	0.009	0.04	<0.1	0.27	2.4	0.1	0.11	2	3.0	<0.2
1288565	Soil	12	0.11	990	0.001	2	0.85	0.011	0.04	<0.1	0.28	2.6	0.1	0.07	2	4.0	<0.2
1288566	Soil	8	0.05	324	0.002	1	0.40	0.005	0.02	<0.1	0.18	1.4	0.1	0.17	1	4.5	<0.2
1288567	Soil	11	0.17	786	0.002	3	0.70	0.008	0.04	<0.1	0.26	2.4	0.1	0.14	2	6.6	<0.2
1288568	Soil	11	0.11	785	0.001	2	0.79	0.006	0.04	<0.1	0.33	2.1	0.1	0.08	2	4.5	<0.2
1288569	Soil	13	0.14	1014	0.001	1	0.99	0.006	0.05	<0.1	0.27	3.0	0.1	0.07	2	4.1	<0.2
1288570	Soil	14	1.18	857	0.002	5	0.33	0.005	0.09	<0.1	0.44	3.0	0.6	0.07	<1	3.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288601	Soil		103.7	99.4	14.5	3039	2.2	278.9	13.6	703	4.09	72.3	6.5	3.3	34	65.9	32.9	0.2	195	0.46	0.105	15
1288602	Soil		103.1	101.9	14.2	1947	2.0	232.9	10.5	594	2.71	69.5	5.1	3.5	50	46.5	30.5	0.2	188	1.27	0.082	12
1288603	Soil		98.4	69.4	16.5	613	1.5	139.0	4.5	114	2.12	80.3	5.6	0.8	21	5.9	26.0	0.2	392	0.08	0.080	23
1288604	Soil		166.9	178.2	15.4	995	2.1	166.5	2.8	71	1.80	136.8	3.7	2.4	46	15.1	49.2	0.2	779	0.36	0.133	24
1288605	Soil		171.0	172.4	20.8	1271	2.5	252.1	4.8	90	2.80	147.9	10.6	2.6	73	15.4	50.7	0.2	1109	0.41	0.151	24
1288606	Soil		262.4	69.4	19.2	328	5.2	59.5	3.2	55	8.05	657.1	5.7	2.5	519	5.5	121.0	0.3	1636	0.05	0.334	9
1288607	Soil		350.3	83.1	57.6	438	6.4	58.8	2.2	52	10.30	1031	21.3	4.6	622	8.0	246.9	0.4	1704	0.06	0.439	10
1288608	Soil		41.2	27.3	84.4	121	5.1	28.1	2.2	32	1.80	60.6	5.3	0.8	39	1.3	18.5	0.2	172	0.04	0.112	6
1288609	Soil		135.3	62.8	592.4	159	6.9	26.3	1.7	25	5.85	121.3	8.0	3.3	120	2.6	88.3	0.4	421	0.04	0.138	6
1288610	Soil		61.4	31.5	135.9	126	5.2	26.8	2.3	20	2.31	45.5	4.8	0.4	50	0.7	18.7	0.3	205	0.02	0.080	7
1288641	Soil		9.0	63.0	11.7	419	0.2	61.7	16.4	113	3.12	17.4	6.3	0.2	7	0.6	4.7	0.3	91	0.01	0.086	6
1288642	Soil		5.1	64.3	12.3	283	0.2	40.5	8.2	119	3.04	11.7	4.7	0.2	9	0.6	2.6	0.3	56	0.02	0.073	6
1288643	Soil		1.8	7.1	2.4	23	1.3	4.2	1.0	20	0.41	2.5	2.0	<0.1	5	<0.1	0.9	0.2	25	0.02	0.025	2
1288644	Soil		31.9	100.6	19.9	227	3.4	41.8	4.7	109	2.55	34.1	4.2	1.0	82	3.5	18.9	0.3	320	0.23	0.298	16
1288645	Soil		6.8	31.5	16.3	94	0.5	17.9	5.2	115	2.64	14.6	2.4	0.7	11	0.4	3.4	0.3	78	0.02	0.070	4
1288646	Soil		23.7	119.1	24.1	312	3.7	69.9	4.1	92	2.24	26.7	8.7	0.8	314	3.6	11.1	0.3	199	0.33	0.230	16
1288647	Soil		19.0	66.5	25.8	320	0.5	78.6	14.8	219	4.30	22.1	3.1	1.4	9	0.3	3.7	0.3	36	0.02	0.050	5
1288648	Soil		20.7	96.3	45.7	340	1.3	79.1	11.8	210	5.94	37.6	11.9	1.0	51	0.6	6.3	0.5	82	0.03	0.176	7
1288649	Soil		3.6	33.2	5.8	82	0.2	16.8	3.8	79	1.18	4.3	3.3	<0.1	8	<0.1	1.4	0.1	32	0.03	0.050	2
1288650	Soil		31.1	75.1	46.2	262	2.0	51.1	7.9	155	6.50	56.1	3.8	0.4	134	1.2	10.6	0.4	85	0.04	0.209	7
1288721	Soil		24.1	24.6	52.4	110	2.3	25.5	2.6	73	1.66	146.6	52.9	0.8	58	0.6	33.6	0.4	151	0.04	0.105	16
1288722	Soil		35.6	62.6	28.9	357	1.8	80.9	11.8	285	2.60	123.8	21.8	2.0	101	4.6	29.9	0.3	166	0.21	0.150	14
1288723	Soil		37.5	61.8	29.9	359	2.2	85.8	7.9	180	2.33	124.3	19.8	2.9	124	5.0	39.0	0.3	176	0.35	0.151	15
1288724	Soil		42.8	85.1	39.9	322	1.9	62.6	7.2	181	3.44	138.1	14.8	3.3	212	7.8	36.8	0.3	206	0.27	0.177	14
1288725	Soil		44.9	84.6	31.9	323	1.8	59.7	5.5	148	3.69	150.1	11.6	3.5	194	6.1	38.7	0.3	264	0.26	0.182	14
1288726	Soil		28.1	85.7	27.0	341	1.5	92.5	8.3	119	2.33	87.3	13.4	2.6	62	2.9	22.1	0.3	151	0.14	0.156	15
1288727	Soil		35.0	122.9	22.5	404	1.5	103.7	30.4	326	2.11	90.9	7.1	3.4	76	11.7	24.8	0.2	183	0.22	0.146	15
1288728	Soil		33.2	96.5	23.1	419	1.4	95.3	13.9	187	2.06	89.1	7.4	4.3	85	12.6	25.3	0.2	192	0.31	0.165	15
1288729	Soil		20.5	43.4	21.5	283	1.0	66.6	6.1	108	1.67	65.1	10.7	1.8	72	3.3	16.6	0.3	148	0.24	0.116	14
1288730	Soil		22.5	75.5	24.9	228	1.7	80.1	6.1	95	1.69	71.8	18.2	1.8	89	5.3	19.4	0.4	129	0.40	0.139	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288601	Soil	29	0.16	2140	0.002	4	0.45	0.002	0.09	0.6	3.96	5.5	3.7	<0.05	1	6.7	<0.2
1288602	Soil	26	0.63	1700	0.002	5	0.37	0.003	0.09	0.5	3.89	4.5	3.7	<0.05	1	5.3	<0.2
1288603	Soil	25	0.04	443	0.004	2	0.46	0.002	0.08	0.7	3.90	1.6	2.1	<0.05	3	6.8	0.2
1288604	Soil	33	0.09	378	0.004	5	0.44	0.002	0.11	0.7	1.93	3.8	2.7	0.05	2	13.1	0.3
1288605	Soil	49	0.10	423	0.006	6	0.54	0.002	0.15	1.0	5.19	4.2	3.8	0.07	3	13.9	0.3
1288606	Soil	48	0.02	122	0.006	2	0.89	0.004	0.33	7.2	10.62	2.3	17.9	1.06	4	39.8	1.0
1288607	Soil	48	0.01	103	0.005	3	0.83	0.005	0.32	11.9	18.35	2.7	19.3	1.01	3	53.1	1.0
1288608	Soil	18	0.02	310	0.005	1	0.35	0.007	0.11	1.3	1.52	1.0	2.3	0.32	3	12.4	0.4
1288609	Soil	39	0.01	47	0.006	3	0.32	0.014	0.52	3.5	3.48	1.7	11.6	1.51	4	57.9	0.5
1288610	Soil	23	0.01	379	0.003	2	0.25	0.005	0.18	1.0	0.66	0.8	3.2	0.44	3	18.3	0.4
1288641	Soil	10	0.04	155	0.006	3	0.44	0.005	0.08	<0.1	0.05	0.3	0.1	0.10	3	2.8	<0.2
1288642	Soil	10	0.03	118	0.003	3	0.35	0.006	0.08	<0.1	0.09	0.3	0.1	<0.05	2	1.4	<0.2
1288643	Soil	2	0.01	99	0.002	2	0.14	0.019	0.03	<0.1	0.03	<0.1	0.2	<0.05	<1	<0.5	<0.2
1288644	Soil	54	0.04	912	0.002	5	0.56	0.005	0.14	0.2	0.37	0.7	1.4	0.16	3	19.1	0.3
1288645	Soil	14	0.04	255	0.002	2	0.62	0.005	0.08	<0.1	0.08	0.5	0.3	<0.05	3	2.7	<0.2
1288646	Soil	51	0.06	1144	0.002	4	0.67	0.009	0.14	0.1	3.07	0.8	0.5	0.22	2	10.9	0.2
1288647	Soil	7	0.02	537	<0.001	4	0.47	0.001	0.11	<0.1	0.76	1.4	0.2	<0.05	1	3.6	0.2
1288648	Soil	19	0.03	601	0.001	3	0.54	0.003	0.11	<0.1	0.28	1.1	0.3	0.09	2	5.0	0.2
1288649	Soil	6	0.02	137	0.002	2	0.25	0.012	0.05	<0.1	0.08	0.1	<0.1	<0.05	2	0.9	<0.2
1288650	Soil	16	0.02	426	0.002	6	0.32	0.009	0.21	<0.1	0.17	0.9	0.4	0.35	2	4.6	<0.2
1288721	Soil	17	0.03	294	0.004	3	0.44	0.002	0.09	1.1	15.70	0.3	1.6	0.07	3	6.9	<0.2
1288722	Soil	26	0.06	821	0.001	4	0.62	0.003	0.10	2.9	4.47	1.0	1.8	0.11	2	7.4	0.3
1288723	Soil	37	0.08	845	0.001	4	0.57	0.004	0.12	8.4	5.14	1.1	1.9	0.13	2	9.4	<0.2
1288724	Soil	30	0.05	1016	0.001	5	0.54	0.004	0.12	3.0	5.99	1.6	2.5	0.12	2	12.6	0.3
1288725	Soil	35	0.05	956	0.001	6	0.59	0.003	0.13	4.8	5.44	1.6	2.5	0.13	3	15.0	0.3
1288726	Soil	18	0.04	598	0.001	4	0.54	0.001	0.10	1.4	2.73	1.2	1.6	<0.05	2	7.0	<0.2
1288727	Soil	27	0.04	855	0.002	5	0.59	0.002	0.11	4.9	2.16	1.3	1.7	0.06	2	6.6	0.2
1288728	Soil	82	0.04	840	0.001	6	0.47	0.002	0.14	8.3	2.45	1.4	1.6	0.07	2	7.3	<0.2
1288729	Soil	27	0.09	588	0.004	4	0.59	0.004	0.10	4.7	2.19	0.9	1.1	0.07	2	5.7	<0.2
1288730	Soil	21	0.05	864	0.002	4	0.39	0.003	0.06	4.3	3.62	2.4	1.3	0.11	1	6.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1093744	Soil		4.1	106.9	19.8	73	0.2	505.5	82.4	985	8.02	131.6	3.0	12.7	116	0.4	2.7	0.2	125	1.61	0.513	93
1093745	Soil		9.0	114.9	18.8	68	0.2	618.4	90.2	1050	9.11	77.5	2.5	17.9	126	0.4	2.3	0.2	135	2.05	0.587	96
1093746	Soil		8.2	134.7	18.6	73	0.4	644.9	86.7	1024	8.74	432.8	3.2	11.0	134	0.4	7.0	0.2	144	1.82	0.584	106
1093747	Soil		10.4	126.4	20.8	171	0.5	729.3	92.9	1038	7.41	452.9	2.8	9.2	139	0.5	5.2	0.1	142	1.77	0.641	103
1093748	Soil		6.3	137.8	19.1	36	0.2	770.9	108.6	1012	7.38	76.3	1.7	15.0	189	0.2	2.3	0.1	156	2.55	0.793	128
1093749	Soil		5.1	100.4	14.2	50	0.2	572.5	79.9	803	7.85	155.7	1.6	17.6	224	0.2	2.3	0.1	133	4.02	0.590	98
1093750	Soil		5.6	88.5	13.7	57	0.2	544.9	84.2	820	7.34	141.2	1.6	14.8	253	0.2	2.3	<0.1	131	4.08	0.572	90
1093751	Soil		7.5	81.4	12.6	88	0.2	534.7	83.9	958	7.46	122.8	2.0	11.2	217	0.4	3.3	0.1	131	3.56	0.505	88
1093752	Soil		7.4	79.3	11.6	78	0.2	544.3	79.3	866	7.72	124.8	1.7	10.4	189	0.3	2.7	0.1	135	2.94	0.455	85
1093753	Soil		8.9	118.0	19.8	86	0.3	648.5	98.1	880	8.57	143.6	2.4	14.9	264	0.6	3.2	0.1	155	4.22	0.599	89
1093754	Soil		8.3	116.4	18.8	94	0.3	666.5	92.1	1173	9.25	173.4	1.2	16.4	199	0.7	2.8	0.1	176	2.59	0.585	108
1093755	Soil		11.6	143.0	18.4	149	0.3	715.2	96.2	976	8.09	35.7	2.5	23.4	207	1.1	2.0	0.1	200	3.43	0.733	104
1093756	Soil		13.9	144.5	20.5	253	0.4	689.1	88.3	968	7.97	21.2	2.2	23.0	197	1.2	1.8	0.1	225	2.69	0.859	113
1093757	Soil		10.9	123.4	20.5	158	0.3	587.7	89.7	974	7.40	20.0	1.5	19.9	231	1.0	1.5	0.1	202	3.73	0.724	105
1093758	Soil		10.6	105.7	16.2	137	0.3	490.3	73.3	1060	8.02	21.5	1.9	18.6	174	0.6	1.4	<0.1	186	2.37	0.623	116
1093759	Soil		12.0	127.5	21.2	232	0.4	592.5	83.9	947	7.16	32.5	2.7	25.6	185	1.2	2.0	0.1	205	2.13	0.772	123
1093760	Soil		18.2	108.3	25.9	402	0.8	824.2	99.7	1118	7.80	121.7	4.3	18.7	202	1.9	7.3	0.2	227	3.04	0.713	114
1274431	Soil		1.6	21.1	10.3	72	0.5	18.1	9.1	502	1.87	13.8	<0.5	0.3	11	0.3	0.3	0.2	20	0.10	0.136	2
1274432	Soil		34.2	58.6	23.8	731	1.9	109.6	8.8	152	2.87	97.6	12.6	2.3	72	6.7	30.5	0.3	244	0.36	0.150	13
1274433	Soil		34.9	49.4	23.8	468	1.4	76.9	7.7	133	2.47	73.8	13.0	3.7	63	3.6	18.8	0.4	203	0.36	0.136	18
1274434	Soil		21.8	32.6	19.2	512	0.9	82.8	4.4	88	1.84	51.2	11.4	2.2	47	6.7	15.6	0.2	183	0.33	0.112	14
1274435	Soil		833.6	46.1	6.6	3157	0.6	140.8	9.2	871	29.26	1819	4.4	1.0	29	42.7	381.7	<0.1	2015	0.28	0.577	3
1274436	Soil		814.8	21.3	2.8	3302	0.3	241.5	18.8	2163	28.84	592.3	2.5	0.5	21	41.6	360.9	<0.1	955	0.30	0.365	1
1274437	Soil		751.4	21.6	3.5	3659	0.4	627.8	36.8	2153	19.41	189.5	2.6	0.5	47	110.5	255.3	<0.1	198	0.97	0.260	2
1274438	Soil		396.1	17.3	7.2	3852	0.4	765.0	61.3	4661	16.84	234.4	3.8	0.9	45	66.2	121.3	0.1	339	0.67	0.258	3
1274439	Soil		382.2	19.3	8.6	5628	0.7	601.1	27.9	2488	22.03	362.3	4.7	1.2	47	52.4	185.4	<0.1	446	0.59	0.321	3
1274440	Soil		60.5	26.8	12.8	446	1.1	67.9	3.9	219	3.08	165.5	1.6	4.7	42	5.1	35.7	0.3	84	0.22	0.079	7
1289031	Soil		12.5	36.7	16.8	164	0.9	31.9	7.3	326	3.35	31.6	3.4	1.1	37	0.9	6.2	0.3	132	0.13	0.189	10
1289032	Soil		6.4	45.3	17.6	91	0.8	23.8	4.6	191	1.83	13.2	5.4	0.2	52	0.5	2.6	0.2	74	0.15	0.146	9
1289033	Soil		8.2	50.1	30.9	89	1.0	27.7	4.9	230	2.34	17.1	5.0	1.1	117	0.9	2.5	0.3	61	0.16	0.189	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1093744	Soil	168	0.21	2856	0.005	8	1.12	0.003	0.10	0.2	1.01	19.5	0.2	0.07	3	1.4	<0.2
1093745	Soil	202	0.30	2683	0.007	7	1.06	0.003	0.10	0.2	1.06	23.9	0.2	0.08	3	1.6	<0.2
1093746	Soil	192	0.25	2430	0.005	10	1.06	0.004	0.12	0.2	4.00	21.6	0.3	0.06	3	1.4	<0.2
1093747	Soil	203	0.25	2774	0.003	17	1.38	0.003	0.20	0.1	2.83	7.1	0.4	0.08	5	1.0	<0.2
1093748	Soil	262	0.36	2610	0.003	28	1.54	0.005	0.31	0.1	1.61	10.1	0.4	0.08	6	0.8	<0.2
1093749	Soil	198	0.97	1388	0.005	19	1.10	0.004	0.25	0.1	0.57	10.7	0.3	0.10	4	0.8	<0.2
1093750	Soil	184	1.10	1226	0.003	16	1.05	0.004	0.22	0.1	0.42	9.2	0.3	0.06	4	<0.5	<0.2
1093751	Soil	170	0.86	1381	0.003	13	1.11	0.004	0.22	0.1	0.45	7.9	0.3	0.10	4	0.6	<0.2
1093752	Soil	174	0.66	1448	0.004	14	1.12	0.003	0.18	0.1	0.43	7.8	0.3	0.10	5	0.5	<0.2
1093753	Soil	190	0.81	1528	0.007	19	1.06	0.006	0.23	0.1	0.87	9.7	0.3	0.16	4	1.4	<0.2
1093754	Soil	214	0.43	1939	0.005	22	1.26	0.006	0.23	0.1	0.77	12.1	0.3	0.13	5	1.2	<0.2
1093755	Soil	254	0.36	2277	0.004	27	1.49	0.004	0.31	0.1	2.28	12.8	0.4	0.09	6	1.6	<0.2
1093756	Soil	254	0.37	2806	0.003	30	1.65	0.004	0.31	0.1	3.71	11.9	0.6	0.09	7	1.8	<0.2
1093757	Soil	246	0.56	2150	0.004	26	1.40	0.005	0.29	0.1	2.79	9.5	0.4	0.08	6	1.7	<0.2
1093758	Soil	221	0.38	2020	0.004	14	1.25	0.004	0.19	0.1	2.40	10.0	0.3	0.06	5	1.3	<0.2
1093759	Soil	262	0.19	3189	0.003	22	1.60	0.004	0.27	0.1	6.46	11.3	0.5	<0.05	7	1.6	<0.2
1093760	Soil	255	0.18	2943	0.003	21	1.32	0.004	0.25	0.2	16.46	23.1	0.7	<0.05	4	2.7	<0.2
1274431	Soil	8	0.12	197	0.003	5	0.67	0.010	0.07	<0.1	0.02	0.7	0.1	<0.05	2	0.6	<0.2
1274432	Soil	25	0.10	1061	0.002	6	0.64	0.004	0.14	2.0	3.74	3.0	1.4	0.06	2	5.4	<0.2
1274433	Soil	20	0.09	1398	0.003	8	0.59	0.003	0.16	0.9	1.28	2.5	1.5	<0.05	2	5.0	<0.2
1274434	Soil	19	0.08	1128	0.002	4	0.59	0.004	0.11	1.3	0.96	1.8	1.0	<0.05	2	4.3	<0.2
1274435	Soil	12	0.03	551	0.002	4	0.57	0.003	0.06	0.3	0.69	0.9	1.3	0.05	<1	21.6	<0.2
1274436	Soil	7	0.02	354	0.003	3	0.47	0.004	0.03	0.2	0.49	0.6	1.7	0.06	<1	26.1	<0.2
1274437	Soil	6	0.05	429	0.005	4	0.42	0.006	0.03	<0.1	0.54	0.7	2.7	0.11	<1	>100	<0.2
1274438	Soil	10	0.05	355	0.004	4	0.42	0.005	0.05	0.1	0.84	1.2	4.0	0.10	1	19.4	<0.2
1274439	Soil	13	0.06	642	0.003	7	0.56	0.006	0.09	0.3	0.97	1.2	2.8	0.11	2	9.7	<0.2
1274440	Soil	16	0.03	801	<0.001	5	0.30	0.002	0.08	0.4	2.35	3.0	0.7	0.09	3	11.5	<0.2
1289031	Soil	28	0.18	503	0.008	3	1.08	0.004	0.08	0.2	0.35	1.6	0.4	0.08	3	4.3	<0.2
1289032	Soil	15	0.04	613	0.003	4	0.45	0.006	0.10	<0.1	0.29	0.3	0.2	0.07	3	2.0	<0.2
1289033	Soil	18	0.05	963	0.004	7	0.68	0.006	0.16	<0.1	0.38	1.9	0.2	0.17	2	3.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1289034	Soil	4.2	20.2	13.2	49	0.3	10.3	7.1	721	1.34	8.2	2.4	0.2	13	0.2	1.2	0.2	59	0.02	0.063	12
1289035	Soil	6.7	32.0	16.6	128	0.4	28.4	10.1	484	3.03	13.9	3.6	1.2	28	0.4	2.6	0.2	65	0.08	0.071	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001857.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1289034	Soil	12	0.04	225	0.005	2	0.54	0.004	0.07	<0.1	0.03	0.3	0.2	<0.05	3	0.9	<0.2
1289035	Soil	20	0.14	858	0.008	2	0.86	0.003	0.11	0.1	0.09	1.6	0.3	<0.05	4	1.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001857.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1281914	Soil	2.5	18.2	5.7	59	0.1	13.4	3.3	65	1.21	6.9	0.6	0.2	8	0.1	1.0	0.1	49	0.07	0.069	9
REP 1281914	QC	2.6	18.0	5.3	55	0.1	13.0	3.3	63	1.23	6.6	1.1	0.2	9	0.1	0.9	0.1	47	0.07	0.068	8
1281940	Soil	4.1	20.9	33.4	17	1.6	5.0	1.0	56	0.94	26.3	2.7	0.2	24	<0.1	2.4	0.2	37	0.02	0.046	3
REP 1281940	QC	4.2	20.8	34.6	18	1.6	4.9	1.1	57	0.96	26.3	3.3	0.2	24	<0.1	2.3	0.2	39	0.02	0.048	3
1281950	Soil	1.5	18.0	5.8	45	0.2	7.5	6.1	357	1.41	4.8	<0.5	0.1	7	0.5	0.6	0.1	20	0.04	0.105	2
REP 1281950	QC	1.4	17.3	6.0	44	0.1	7.5	5.9	344	1.33	4.6	0.5	0.1	7	0.4	0.6	0.1	19	0.04	0.093	2
1286995	Soil	4.8	25.7	13.4	132	0.4	25.2	7.3	178	1.72	13.3	1.7	1.5	62	1.3	1.2	0.1	54	0.71	0.078	6
REP 1286995	QC	4.5	25.0	12.8	131	0.4	25.5	7.3	176	1.73	13.3	1.8	1.5	60	1.4	1.2	0.2	54	0.73	0.078	6
1288825	Soil	4.5	44.6	19.0	94	1.2	45.6	11.4	322	3.57	11.8	3.3	0.7	21	0.4	1.5	0.2	21	0.13	0.135	9
REP 1288825	QC	4.6	45.5	19.4	94	1.3	46.3	11.7	326	3.52	11.7	2.9	0.7	22	0.4	1.6	0.2	21	0.12	0.131	9
1288841	Soil	7.9	103.0	37.0	203	0.3	71.5	18.8	259	6.57	22.6	7.2	0.9	27	0.5	3.1	0.4	33	0.14	0.103	3
REP 1288841	QC	8.4	103.3	36.1	207	0.4	69.5	18.5	266	6.65	22.1	8.7	0.8	28	0.5	3.1	0.4	33	0.13	0.105	3
1288860	Soil	4.6	34.7	15.4	106	0.6	36.7	7.9	204	2.03	16.4	3.1	0.9	32	0.2	1.7	0.3	24	0.25	0.147	9
REP 1288860	QC	4.8	35.2	15.6	107	0.6	37.0	8.1	206	2.06	16.5	3.9	0.9	33	0.2	1.7	0.2	24	0.24	0.151	9
1288435	Soil	1.4	24.1	7.1	36	<0.1	23.0	7.1	89	2.52	9.5	1.0	0.9	3	<0.1	1.1	0.3	15	0.01	0.039	4
REP 1288435	QC	1.3	24.8	6.9	37	<0.1	22.5	7.2	90	2.53	9.7	1.0	0.9	3	<0.1	1.1	0.3	15	0.01	0.038	4
1288604	Soil	166.9	178.2	15.4	995	2.1	166.5	2.8	71	1.80	136.8	3.7	2.4	46	15.1	49.2	0.2	779	0.36	0.133	24
REP 1288604	QC	161.4	176.5	15.3	981	2.1	159.1	2.9	71	1.94	136.6	5.2	2.4	46	13.7	46.1	0.2	803	0.36	0.125	23
1288725	Soil	44.9	84.6	31.9	323	1.8	59.7	5.5	148	3.69	150.1	11.6	3.5	194	6.1	38.7	0.3	264	0.26	0.182	14
REP 1288725	QC	47.0	87.0	33.2	325	2.0	60.9	5.7	155	3.86	152.9	11.1	3.5	198	6.4	40.8	0.3	270	0.25	0.185	15
1093744	Soil	4.1	106.9	19.8	73	0.2	505.5	82.4	985	8.02	131.6	3.0	12.7	116	0.4	2.7	0.2	125	1.61	0.513	93
REP 1093744	QC	4.1	112.3	20.1	78	0.2	522.0	84.9	1006	7.81	133.9	2.3	14.0	117	0.5	2.6	0.1	123	1.55	0.518	95
1093754	Soil	8.3	116.4	18.8	94	0.3	666.5	92.1	1173	9.25	173.4	1.2	16.4	199	0.7	2.8	0.1	176	2.59	0.585	108
REP 1093754	QC	8.4	118.0	15.0	94	0.3	659.5	92.3	1189	9.13	172.2	1.7	17.1	189	0.5	2.9	0.1	174	2.67	0.573	105
1274434	Soil	21.8	32.6	19.2	512	0.9	82.8	4.4	88	1.84	51.2	11.4	2.2	47	6.7	15.6	0.2	183	0.33	0.112	14
REP 1274434	QC	22.9	34.0	19.7	537	1.0	85.6	4.6	93	1.91	52.3	11.3	2.3	48	7.0	16.0	0.2	205	0.34	0.121	16
Reference Materials																					
STD DS8	Standard	13.3	103.2	117.5	297	1.8	35.6	7.0	570	2.30	24.9	113.8	6.3	66	2.1	4.9	5.8	41	0.69	0.074	18

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001857.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1281914	Soil	13	0.04	166	0.004	3	0.56	0.009	0.07	0.1	0.04	0.6	0.1	0.08	3	0.7	<0.2
REP 1281914	QC	12	0.04	160	0.005	2	0.50	0.008	0.07	0.1	0.05	0.5	0.1	0.07	3	<0.5	<0.2
1281940	Soil	11	0.02	136	0.003	2	0.34	0.012	0.08	<0.1	0.11	1.2	0.2	0.16	2	3.6	<0.2
REP 1281940	QC	11	0.02	135	0.003	2	0.36	0.013	0.09	<0.1	0.10	1.3	0.3	0.17	2	3.5	<0.2
1281950	Soil	12	0.04	95	0.003	<1	0.55	0.013	0.04	<0.1	0.03	0.3	<0.1	0.07	3	<0.5	<0.2
REP 1281950	QC	12	0.04	91	0.006	1	0.53	0.013	0.04	<0.1	0.04	0.3	<0.1	0.06	3	<0.5	<0.2
1286995	Soil	14	0.17	924	0.003	1	0.72	0.009	0.05	<0.1	0.14	2.6	0.1	0.07	2	1.7	<0.2
REP 1286995	QC	14	0.18	923	0.003	2	0.72	0.008	0.05	<0.1	0.14	2.6	0.2	0.07	2	2.0	<0.2
1288825	Soil	9	0.05	2271	0.004	2	0.70	0.008	0.06	<0.1	0.29	1.9	0.2	<0.05	1	1.1	<0.2
REP 1288825	QC	8	0.05	2292	0.003	2	0.69	0.007	0.05	<0.1	0.28	1.9	0.2	<0.05	1	0.7	<0.2
1288841	Soil	12	0.05	791	0.002	3	0.38	0.003	0.08	<0.1	0.21	4.6	0.2	<0.05	1	2.1	<0.2
REP 1288841	QC	12	0.05	843	0.002	3	0.39	0.003	0.08	<0.1	0.18	4.5	0.2	<0.05	2	2.4	0.2
1288860	Soil	7	0.03	694	0.003	3	0.36	0.010	0.08	<0.1	0.18	1.5	0.1	<0.05	1	1.4	<0.2
REP 1288860	QC	6	0.03	710	0.003	4	0.37	0.010	0.08	<0.1	0.19	1.7	0.1	<0.05	1	1.7	<0.2
1288435	Soil	4	0.02	473	0.002	1	0.29	0.002	0.06	<0.1	0.02	1.1	<0.1	<0.05	2	<0.5	<0.2
REP 1288435	QC	4	0.02	472	0.002	2	0.30	0.002	0.07	<0.1	0.01	1.1	<0.1	<0.05	2	<0.5	<0.2
1288604	Soil	33	0.09	378	0.004	5	0.44	0.002	0.11	0.7	1.93	3.8	2.7	0.05	2	13.1	0.3
REP 1288604	QC	32	0.08	363	0.005	6	0.44	0.001	0.11	0.7	1.92	3.8	2.8	<0.05	2	13.9	0.4
1288725	Soil	35	0.05	956	0.001	6	0.59	0.003	0.13	4.8	5.44	1.6	2.5	0.13	3	15.0	0.3
REP 1288725	QC	37	0.05	989	0.001	5	0.60	0.004	0.13	4.7	5.33	1.7	2.4	0.11	3	14.4	0.3
1093744	Soil	168	0.21	2856	0.005	8	1.12	0.003	0.10	0.2	1.01	19.5	0.2	0.07	3	1.4	<0.2
REP 1093744	QC	166	0.22	2859	0.004	6	1.07	0.003	0.09	0.3	1.11	18.9	0.2	0.06	3	1.2	<0.2
1093754	Soil	214	0.43	1939	0.005	22	1.26	0.006	0.23	0.1	0.77	12.1	0.3	0.13	5	1.2	<0.2
REP 1093754	QC	207	0.41	1799	0.004	15	1.16	0.003	0.20	0.1	0.74	12.6	0.3	0.12	5	1.4	<0.2
1274434	Soil	19	0.08	1128	0.002	4	0.59	0.004	0.11	1.3	0.96	1.8	1.0	<0.05	2	4.3	<0.2
REP 1274434	QC	21	0.09	1218	0.003	5	0.66	0.004	0.11	1.3	0.99	2.0	1.1	<0.05	2	4.6	<0.2
Reference Materials																	
STD DS8	Standard	114	0.58	278	0.112	3	0.96	0.105	0.43	2.8	0.20	3.1	5.3	0.17	5	5.2	4.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001857.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	13.6	110.0	119.7	294	1.7	36.8	7.5	597	2.37	25.7	106.8	6.6	66	2.3	5.4	6.6	42	0.68	0.073	15
STD DS8	Standard	12.4	115.5	120.0	311	1.9	41.1	7.7	604	2.89	27.1	110.5	5.6	56	2.4	4.4	6.3	43	0.66	0.079	12
STD DS8	Standard	12.4	117.2	118.8	323	1.9	38.5	7.7	618	2.47	27.4	111.4	5.9	58	2.6	4.4	5.9	43	0.67	0.077	14
STD DS8	Standard	13.3	108.4	124.7	299	1.7	36.6	7.5	582	2.36	25.2	118.8	6.3	81	1.6	5.4	6.5	41	0.72	0.075	17
STD DS8	Standard	13.0	95.0	123.9	293	1.8	36.1	7.2	595	2.39	24.0	115.4	6.3	58	2.0	4.6	5.7	40	0.70	0.070	15
STD DS8	Standard	11.4	101.0	122.5	299	2.0	35.0	6.8	563	2.35	26.6	111.9	6.1	66	2.2	5.5	6.6	37	0.62	0.076	13
STD DS8	Standard	13.2	109.1	124.8	303	1.6	36.1	7.3	597	2.35	26.7	111.7	7.2	71	2.2	5.7	6.6	42	0.68	0.081	17
STD DS8	Standard	12.4	107.8	125.5	289	1.7	35.2	7.3	554	2.25	25.8	102.5	6.5	68	2.3	5.4	6.5	38	0.63	0.072	13
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001857.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
STD DS8	Standard	114	0.59	272	0.123	1	0.94	0.107	0.42	2.9	0.17	2.3	5.2	0.16	5	5.3	5.2
STD DS8	Standard	120	0.62	255	0.107	3	0.92	0.080	0.41	2.9	0.22	2.7	5.6	0.19	5	4.8	5.4
STD DS8	Standard	123	0.59	257	0.113	3	0.92	0.094	0.43	3.0	0.20	2.1	5.4	0.14	5	4.9	4.6
STD DS8	Standard	115	0.60	304	0.127	4	1.02	0.090	0.47	3.1	0.19	3.7	5.3	0.19	5	4.2	4.8
STD DS8	Standard	114	0.58	262	0.102	3	0.86	0.083	0.39	2.9	0.22	1.8	5.4	0.10	5	4.9	4.6
STD DS8	Standard	104	0.57	262	0.103	2	0.85	0.103	0.41	2.8	0.22	2.0	5.3	0.12	4	4.5	4.7
STD DS8	Standard	111	0.57	282	0.115	3	0.91	0.100	0.40	2.8	0.17	0.8	5.2	0.19	5	4.5	4.7
STD DS8	Standard	106	0.58	272	0.111	2	0.91	0.112	0.37	2.7	0.21	2.2	5.3	0.10	5	5.0	4.6
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 25, 2011
Report Date: December 06, 2011
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI11001883.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #31
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	320	Sieve soil to 230 mesh			WHI
RJSV	320	Saving all or part of Soil Reject			WHI
1DX2	319	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286791	Soil		11.4	48.5	16.6	377	0.6	72.4	10.7	330	3.02	47.8	3.1	3.3	53	3.5	3.0	0.2	79	0.70	0.119	12
1286792	Soil		15.4	68.1	20.1	1075	0.9	148.7	10.6	113	2.26	40.9	3.3	4.4	58	8.6	4.8	0.2	120	0.83	0.188	14
1286281	Soil		3.8	30.2	22.5	146	0.7	33.8	71.9	1756	2.65	18.4	3.8	2.2	48	0.7	1.2	0.2	46	0.38	0.086	4
1286282	Soil		3.4	30.2	16.9	155	0.8	41.1	21.8	276	2.74	14.6	3.4	3.1	40	0.6	1.4	0.2	47	0.16	0.075	7
1286283	Soil		0.5	8.4	4.2	30	0.2	9.6	2.7	39	0.72	3.4	0.6	0.3	17	0.1	0.3	<0.1	16	0.14	0.057	2
1286284	Soil		3.9	22.4	16.8	132	0.5	32.4	10.2	228	2.90	18.9	4.1	2.2	28	0.8	1.3	0.2	50	0.16	0.084	5
1286285	Soil		3.5	28.0	18.4	184	0.2	46.8	15.4	1277	4.15	36.0	1.6	2.6	52	0.6	1.0	0.2	33	0.26	0.064	3
1286761	Soil		8.4	38.7	18.4	173	0.4	39.4	5.7	112	2.46	22.6	3.1	0.9	28	0.8	2.9	0.2	70	0.08	0.092	7
1286762	Soil		25.4	54.0	25.1	317	0.5	60.1	7.1	151	3.17	28.5	5.5	2.1	39	0.6	4.3	0.2	111	0.07	0.088	10
1286763	Soil		14.1	114.1	22.3	922	1.0	155.1	14.7	246	3.15	26.7	6.9	3.8	73	7.0	3.9	0.2	89	0.32	0.123	12
1286764	Soil		10.3	44.7	18.6	170	1.1	51.5	4.8	116	1.68	24.4	5.5	1.4	60	1.6	4.2	0.2	107	0.39	0.102	7
1286765	Soil		3.9	13.3	8.6	56	0.1	9.7	1.3	22	0.53	6.6	1.7	0.2	10	0.4	1.2	0.1	48	0.02	0.038	10
1286766	Soil		9.2	22.5	20.6	150	0.4	25.7	4.4	118	2.39	31.2	2.8	1.2	30	0.5	3.7	0.2	109	0.04	0.067	9
1286767	Soil		4.3	30.0	19.2	241	1.1	36.0	2.4	42	0.99	14.5	5.0	2.3	65	1.8	2.1	0.2	76	0.40	0.105	10
1286768	Soil		13.8	48.1	15.9	335	1.2	56.7	11.9	320	2.36	56.0	11.1	2.0	64	3.3	5.1	0.1	95	0.49	0.153	11
1286769	Soil		10.9	26.5	15.7	114	0.9	22.5	1.6	39	0.99	18.2	6.4	0.8	36	1.8	3.2	0.1	67	0.14	0.080	7
1286770	Soil		21.7	41.6	16.6	418	0.8	62.9	6.4	128	2.10	25.8	2.5	2.6	61	5.1	6.4	0.2	126	0.39	0.137	12
1284321	Soil		2.3	14.1	7.7	58	0.8	11.3	3.3	183	0.91	10.0	3.4	1.1	46	0.5	1.0	0.1	42	0.73	0.064	4
1284322	Soil		3.2	28.2	10.9	115	0.7	23.7	6.2	230	2.14	13.6	2.7	1.3	34	1.5	1.7	0.1	50	0.44	0.084	6
1284323	Soil		5.5	67.3	15.2	223	1.9	58.1	10.9	1306	2.03	22.4	8.5	1.9	58	3.9	3.3	0.2	78	0.97	0.094	7
1284324	Soil		2.1	27.7	8.6	160	1.7	26.1	6.6	243	0.84	9.3	4.8	0.8	38	1.4	1.4	<0.1	42	0.47	0.064	4
1287951	Soil		5.5	40.1	12.3	228	0.8	97.8	11.4	493	1.35	27.8	1.8	1.0	43	2.7	3.7	0.1	81	1.32	0.131	6
1287952	Soil		3.5	28.9	15.8	809	0.8	186.9	4.8	23	0.63	12.6	4.8	1.6	36	1.7	7.3	0.1	75	0.62	0.101	9
1287953	Soil		11.7	61.0	13.5	270	1.0	93.6	6.8	230	2.11	36.0	4.5	1.3	42	1.9	4.8	0.1	146	0.34	0.247	11
1287954	Soil		8.6	103.5	26.0	212	1.7	119.5	8.1	187	2.10	23.5	4.5	1.8	65	3.4	3.5	0.2	99	0.62	0.211	13
1287955	Soil		5.8	42.3	17.4	136	0.9	33.9	5.8	246	1.95	21.7	4.1	1.9	69	1.1	2.5	0.2	80	0.78	0.128	8
1288951	Soil		10.0	15.2	11.7	85	0.1	19.3	3.1	50	1.19	16.2	1.5	1.0	10	0.5	1.6	0.1	81	0.03	0.041	11
1288952	Soil		10.6	42.7	17.3	226	0.2	46.4	9.3	174	2.72	21.5	2.6	2.3	23	0.7	2.4	0.2	58	0.14	0.069	11
1288953	Soil		10.7	32.6	15.1	161	0.2	36.6	5.9	113	2.34	24.2	2.3	2.2	17	0.5	2.4	0.2	63	0.07	0.078	12
1288954	Soil		6.7	19.3	21.6	146	0.4	27.4	4.2	82	2.00	17.3	<0.5	1.4	26	0.4	1.4	0.2	58	0.05	0.114	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286791	Soil		18	0.15	1242	0.003	3	0.81	0.006	0.08	0.1	0.38	3.3	0.3	0.07	2	2.0	<0.2
1286792	Soil		20	0.16	902	0.002	5	0.61	0.005	0.09	<0.1	0.88	4.1	0.6	<0.05	2	3.0	<0.2
1286281	Soil		24	0.23	890	0.001	<1	1.15	0.010	0.07	<0.1	0.17	3.2	0.2	<0.05	3	1.5	<0.2
1286282	Soil		23	0.24	1614	0.002	2	1.20	0.007	0.07	<0.1	0.29	3.9	0.2	<0.05	3	2.6	<0.2
1286283	Soil		5	0.05	384	0.007	1	0.44	0.033	0.04	<0.1	0.05	1.0	<0.1	<0.05	1	0.7	<0.2
1286284	Soil		19	0.20	1024	0.002	2	1.15	0.010	0.08	<0.1	0.15	3.1	0.2	<0.05	3	2.3	<0.2
1286285	Soil		21	0.32	1091	<0.001	<1	1.07	0.005	0.08	<0.1	0.11	3.6	0.1	<0.05	3	0.8	<0.2
1286761	Soil		18	0.11	828	0.003	2	0.71	0.008	0.07	0.2	0.19	1.3	0.4	0.05	3	2.4	<0.2
1286762	Soil		24	0.14	506	0.005	4	1.12	0.007	0.09	0.2	0.43	2.3	0.5	<0.05	4	4.0	<0.2
1286763	Soil		28	0.21	1355	0.004	5	1.17	0.005	0.10	0.1	0.55	4.1	0.4	0.06	3	3.5	<0.2
1286764	Soil		20	0.13	1960	0.003	3	0.85	0.010	0.08	0.2	0.77	2.1	0.5	0.07	3	1.9	<0.2
1286765	Soil		10	0.03	216	0.004	2	0.47	0.007	0.05	<0.1	0.06	0.3	0.2	<0.05	3	0.5	<0.2
1286766	Soil		19	0.09	387	0.004	3	0.79	0.005	0.07	0.1	0.11	1.4	0.4	<0.05	4	2.1	<0.2
1286767	Soil		20	0.14	2547	0.002	4	0.79	0.005	0.08	0.1	1.20	2.3	0.5	0.05	2	1.9	<0.2
1286768	Soil		21	0.12	1137	0.002	3	0.61	0.005	0.08	0.1	1.21	2.7	0.4	0.06	2	4.2	<0.2
1286769	Soil		15	0.05	1120	0.002	<1	0.51	0.005	0.05	0.1	0.49	1.0	0.4	<0.05	2	3.3	<0.2
1286770	Soil		21	0.15	2368	0.004	3	0.74	0.005	0.10	0.1	0.39	2.5	0.4	<0.05	2	3.3	0.2
1284321	Soil		12	0.11	900	0.004	2	0.58	0.021	0.05	0.1	0.30	1.2	0.1	<0.05	2	3.0	<0.2
1284322	Soil		11	0.13	752	0.004	2	0.73	0.018	0.06	<0.1	0.31	1.8	0.2	0.06	2	2.3	<0.2
1284323	Soil		19	0.18	1431	0.005	5	1.08	0.017	0.12	0.2	0.55	3.5	0.4	0.06	3	2.4	0.2
1284324	Soil		10	0.09	775	0.006	2	0.56	0.027	0.05	<0.1	0.44	1.8	0.2	<0.05	2	2.7	<0.2
1287951	Soil		14	0.19	559	0.004	5	0.86	0.016	0.07	0.1	0.56	1.9	0.3	0.12	2	2.9	<0.2
1287952	Soil		16	0.14	644	0.004	3	0.74	0.013	0.08	0.2	0.68	2.1	0.4	0.11	2	4.9	<0.2
1287953	Soil		18	0.13	789	0.005	3	0.74	0.007	0.10	0.2	0.60	2.0	0.5	<0.05	2	2.0	<0.2
1287954	Soil		22	0.13	2106	0.004	3	0.94	0.007	0.11	0.2	0.69	3.3	0.5	0.05	3	2.1	<0.2
1287955	Soil		19	0.20	1089	0.003	2	0.95	0.008	0.08	0.1	0.57	2.5	0.2	0.05	3	1.8	<0.2
1288951	Soil		11	0.07	308	0.004	2	0.72	0.007	0.05	0.1	0.05	1.0	0.3	<0.05	3	0.7	<0.2
1288952	Soil		16	0.18	724	0.003	1	0.76	0.005	0.07	0.1	0.14	2.7	0.2	<0.05	2	1.6	<0.2
1288953	Soil		15	0.14	438	0.002	1	0.73	0.004	0.06	0.1	0.10	2.1	0.2	<0.05	2	1.4	<0.2
1288954	Soil		12	0.08	207	0.004	<1	0.63	0.004	0.09	<0.1	0.03	1.2	0.2	<0.05	3	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288955	Soil		7.2	20.5	18.5	116	0.6	22.2	3.0	62	1.02	18.2	<0.5	0.6	40	0.5	1.8	0.2	76	0.11	0.076	12
1288956	Soil		13.4	34.9	17.4	228	0.4	47.8	7.2	157	2.61	32.9	1.8	1.9	36	1.4	2.9	0.2	89	0.46	0.075	11
1288957	Soil		12.3	44.7	21.3	233	0.4	60.4	11.4	191	2.76	29.9	3.3	3.4	17	0.8	3.2	0.2	62	0.06	0.069	12
1288958	Soil		9.5	32.1	15.4	180	0.8	39.4	6.0	157	1.97	24.4	1.8	1.6	33	1.2	2.2	0.2	78	0.38	0.088	12
1288959	Soil		9.6	36.3	15.8	203	0.5	46.6	8.0	190	2.05	22.4	1.7	2.7	47	1.5	2.5	0.2	73	0.49	0.097	11
1288960	Soil		16.0	52.3	15.4	278	0.6	64.6	9.2	252	2.16	33.6	4.1	3.9	55	2.6	4.9	0.2	95	0.51	0.145	16
1289011	Soil		12.2	50.1	36.3	123	0.5	33.3	8.5	426	3.50	48.2	2.4	0.4	16	0.6	5.0	0.3	44	0.12	0.150	6
1289012	Soil		7.5	45.1	33.0	172	2.1	34.8	9.9	189	2.00	24.1	2.2	0.3	23	1.0	3.9	0.2	34	0.22	0.137	3
1289013	Soil		5.0	31.0	9.5	146	0.1	20.5	5.3	51	1.86	12.8	0.8	<0.1	5	0.1	2.1	0.2	28	<0.01	0.044	2
1289014	Soil		1.0	16.4	15.3	32	<0.1	23.0	13.4	350	2.87	16.5	0.6	1.2	5	<0.1	1.7	0.4	10	0.02	0.044	3
1289015	Soil		1.5	10.3	5.2	48	<0.1	17.5	6.6	105	3.51	30.8	<0.5	0.6	5	<0.1	1.0	0.3	24	<0.01	0.056	3
1289016	Soil		7.3	59.9	30.2	493	0.6	43.0	9.6	811	4.98	25.7	6.4	2.2	22	2.9	4.5	0.2	44	0.58	0.190	12
1289017	Soil		8.5	62.2	33.2	429	0.2	42.7	10.0	1042	6.33	30.4	5.5	1.9	20	2.6	6.4	0.2	51	0.40	0.186	11
1289018	Soil		2.9	63.8	12.5	118	0.4	22.3	6.3	177	1.68	10.8	4.8	0.5	32	0.9	3.7	0.2	18	1.40	0.071	3
1289019	Soil		3.4	45.6	12.3	156	0.3	19.3	4.8	215	2.08	17.1	6.5	0.6	20	0.8	7.8	0.1	21	0.50	0.094	5
1289221	Soil		17.9	78.5	28.1	438	1.3	98.2	9.1	116	3.41	81.9	5.9	2.1	223	1.4	8.1	0.3	116	0.40	0.385	17
1289222	Soil		7.8	43.9	31.9	84	1.4	20.8	4.0	190	2.05	44.0	5.5	3.1	142	5.8	4.9	0.3	140	1.62	1.022	28
1289223	Soil		13.9	44.2	18.8	57	1.7	12.3	1.1	47	0.87	15.0	5.7	1.8	98	1.5	3.6	0.2	136	0.51	0.296	14
1289224	Soil		10.7	134.6	36.8	461	0.7	107.7	13.8	176	4.52	36.2	7.5	5.3	99	2.2	4.1	0.6	42	0.37	0.342	21
1289225	Soil		11.7	146.8	35.6	532	1.5	112.7	14.4	198	3.62	28.7	6.0	7.8	118	0.7	2.8	0.5	48	0.66	0.351	19
1289226	Soil		6.3	81.5	17.7	150	1.0	69.6	24.6	1128	5.07	92.5	3.7	3.9	12	0.3	2.7	0.3	14	0.07	0.060	24
1289227	Soil		9.8	65.0	18.5	215	1.6	81.8	16.6	450	3.19	48.4	3.1	4.8	28	0.9	4.8	0.2	31	0.21	0.124	18
1289228	Soil		33.2	77.8	13.6	924	0.8	170.5	12.6	267	2.96	55.0	2.3	5.6	30	5.2	13.2	0.2	111	0.95	0.100	15
1289371	Soil		1.3	27.1	6.7	46	0.7	23.4	4.8	287	1.28	6.0	2.6	0.3	82	0.7	0.8	0.2	28	2.17	0.098	9
1289372	Soil		1.7	21.3	8.0	66	0.7	23.1	4.5	119	1.46	5.0	4.2	0.6	74	1.6	1.2	0.2	38	2.03	0.081	10
1289373	Soil		0.8	13.7	3.6	34	0.3	12.0	2.0	76	0.75	3.1	0.9	0.2	90	0.7	0.5	0.1	18	2.58	0.071	4
1289374	Soil		2.7	33.6	11.9	145	0.7	36.4	7.6	299	2.23	10.9	3.9	0.9	51	1.3	1.5	0.2	36	1.10	0.134	6
1289375	Soil		3.2	41.2	7.4	117	1.2	31.9	6.6	589	1.97	10.3	5.0	0.5	42	0.9	1.3	0.1	44	0.65	0.117	5
1289376	Soil		3.3	53.4	12.7	174	1.4	52.5	6.7	251	2.64	16.2	6.1	1.3	59	1.1	1.7	0.2	57	1.11	0.103	5
1289377	Soil		4.3	53.9	12.4	141	0.7	34.9	7.1	202	2.52	16.4	5.9	1.7	25	1.2	1.9	0.2	63	0.17	0.097	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288955	Soil	13	0.07	407	0.003	2	0.59	0.008	0.08	<0.1	0.16	0.9	0.3	<0.05	3	0.7	<0.2
1288956	Soil	17	0.17	736	0.002	<1	0.83	0.006	0.07	0.1	0.13	2.2	0.3	<0.05	3	1.5	<0.2
1288957	Soil	17	0.11	292	0.002	2	0.85	0.003	0.07	0.1	0.15	2.4	0.3	<0.05	2	1.7	<0.2
1288958	Soil	15	0.14	1071	0.003	2	0.89	0.008	0.07	0.2	0.17	2.0	0.3	<0.05	3	1.3	<0.2
1288959	Soil	16	0.17	897	0.002	1	0.83	0.007	0.07	0.1	0.28	2.7	0.3	<0.05	2	1.6	<0.2
1288960	Soil	18	0.18	1263	0.005	4	0.75	0.006	0.12	0.1	0.40	3.2	0.3	<0.05	2	2.2	<0.2
1289011	Soil	8	0.03	419	0.002	3	0.36	0.006	0.04	<0.1	0.08	1.5	0.3	<0.05	1	2.4	<0.2
1289012	Soil	6	0.03	308	0.003	2	0.24	0.016	0.04	<0.1	0.27	1.4	0.3	<0.05	1	2.2	<0.2
1289013	Soil	5	0.02	46	0.002	2	0.23	0.006	0.04	<0.1	<0.01	0.4	<0.1	<0.05	1	1.0	<0.2
1289014	Soil	5	0.04	49	0.002	1	0.47	0.006	0.05	<0.1	0.02	1.7	<0.1	<0.05	2	<0.5	<0.2
1289015	Soil	6	0.03	47	0.002	2	0.35	0.003	0.05	<0.1	<0.01	1.9	<0.1	<0.05	3	<0.5	<0.2
1289016	Soil	12	0.08	219	0.003	3	0.53	0.005	0.06	<0.1	0.28	5.2	0.2	<0.05	1	1.7	<0.2
1289017	Soil	14	0.10	261	0.003	3	0.54	0.005	0.05	<0.1	0.21	4.9	0.2	<0.05	2	1.5	<0.2
1289018	Soil	6	0.14	316	0.002	3	0.38	0.009	0.04	<0.1	0.12	1.7	<0.1	<0.05	1	1.0	<0.2
1289019	Soil	6	0.13	335	0.003	2	0.37	0.011	0.04	<0.1	0.14	2.0	<0.1	<0.05	1	1.1	<0.2
1289221	Soil	23	0.05	706	0.006	5	0.65	0.002	0.13	0.5	0.63	2.4	0.6	0.07	2	3.5	<0.2
1289222	Soil	33	0.05	911	0.006	11	0.71	0.005	0.25	0.3	0.60	3.6	0.6	0.14	2	2.5	<0.2
1289223	Soil	17	0.02	394	0.003	5	0.26	0.003	0.14	0.3	0.69	1.1	0.7	0.06	<1	1.5	<0.2
1289224	Soil	15	0.05	548	0.002	7	0.64	0.003	0.20	<0.1	0.22	4.8	0.3	0.07	2	9.2	0.3
1289225	Soil	12	0.05	1105	0.001	7	0.56	0.002	0.21	<0.1	0.48	4.4	0.2	<0.05	1	7.7	0.3
1289226	Soil	6	0.05	478	0.001	4	0.45	0.002	0.10	0.2	0.33	5.3	0.2	<0.05	<1	1.1	<0.2
1289227	Soil	13	0.07	676	0.002	4	0.52	0.003	0.08	1.2	0.65	4.8	0.3	<0.05	<1	1.8	<0.2
1289228	Soil	12	0.44	743	<0.001	4	0.24	0.002	0.08	0.2	1.63	4.3	0.9	<0.05	<1	3.5	<0.2
1289371	Soil	13	0.11	576	0.003	3	0.80	0.012	0.04	<0.1	0.13	0.8	<0.1	0.06	2	0.8	<0.2
1289372	Soil	17	0.12	595	0.005	5	0.78	0.015	0.04	<0.1	0.13	1.6	0.1	0.19	2	1.1	<0.2
1289373	Soil	8	0.06	331	0.006	3	0.56	0.016	0.02	0.1	0.06	0.5	<0.1	<0.05	1	1.1	<0.2
1289374	Soil	17	0.15	630	0.002	4	0.69	0.005	0.07	0.3	0.18	2.2	0.2	0.07	2	1.4	<0.2
1289375	Soil	14	0.13	589	0.004	3	0.97	0.018	0.05	<0.1	0.40	1.8	0.2	<0.05	3	2.9	<0.2
1289376	Soil	20	0.26	694	0.001	4	1.07	0.007	0.09	<0.1	0.62	3.3	0.2	<0.05	3	4.6	<0.2
1289377	Soil	20	0.17	882	0.003	4	0.99	0.006	0.08	0.1	0.45	2.9	0.2	<0.05	3	2.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1289378	Soil	4.2	45.0	10.8	138	1.0	36.6	7.2	668	2.09	12.3	6.1	1.0	57	1.6	1.9	0.2	46	1.42	0.103	6
1289379	Soil	2.9	48.9	12.0	157	0.7	38.7	7.3	276	2.13	13.0	5.9	1.6	57	1.5	2.1	0.2	50	1.16	0.108	7
1289380	Soil	4.1	36.6	13.9	137	1.0	30.4	13.9	735	1.99	12.2	4.9	1.4	53	1.3	1.7	0.2	50	0.96	0.099	6
1289211	Soil	111.7	61.2	11.2	618	0.3	282.6	22.7	468	2.33	53.9	3.0	1.5	30	3.3	5.5	0.2	84	0.33	0.077	25
1289212	Soil	88.6	68.4	10.9	894	0.4	395.5	21.6	569	3.17	71.1	1.1	1.9	127	3.0	3.8	0.1	70	4.87	0.051	9
1289213	Soil	107.0	60.0	7.9	672	0.3	275.9	12.6	324	2.08	63.8	1.2	2.5	118	3.7	3.5	<0.1	46	4.18	0.068	7
1289214	Soil	31.0	60.7	9.1	2663	0.7	202.4	21.4	681	3.25	45.4	1.9	4.6	29	17.5	11.5	0.1	142	0.59	0.123	22
1289215	Soil	47.4	78.4	12.3	853	0.9	139.4	8.8	198	2.06	57.4	1.3	3.9	49	7.6	11.3	0.2	167	1.27	0.231	14
1289216	Soil	9.6	66.1	7.8	486	0.7	119.1	10.9	251	2.09	30.8	3.0	5.2	101	1.4	4.4	0.2	45	3.32	0.142	13
1289217	Soil	7.0	50.9	12.0	2325	0.7	164.1	29.0	977	4.33	32.5	1.1	4.0	327	2.2	5.1	0.1	65	8.34	0.203	10
1289218	Soil	10.8	44.5	12.6	462	0.4	92.2	10.5	225	2.95	30.3	2.5	2.3	15	0.7	6.1	0.2	44	0.09	0.089	17
1289219	Soil	11.8	58.0	12.9	735	1.1	132.8	14.0	436	3.30	32.0	2.2	5.3	19	6.7	8.1	0.2	46	0.19	0.139	20
1289220	Soil	59.7	76.0	60.0	196	6.1	38.9	5.2	149	4.93	60.5	6.0	2.6	137	5.1	6.6	0.4	203	0.06	0.236	6
1286881	Soil	1.6	56.1	9.9	92	1.1	40.2	5.4	166	1.45	7.0	4.6	0.7	52	0.8	1.2	0.3	30	1.43	0.079	6
1286882	Soil	2.3	41.4	13.6	148	0.7	39.0	7.6	141	2.46	13.3	5.3	1.5	38	0.6	1.6	0.2	26	0.54	0.096	4
1286883	Soil	2.3	37.9	13.0	119	0.5	33.3	7.1	122	2.47	14.7	6.3	1.3	31	0.4	1.5	0.2	25	0.38	0.076	4
1286884	Soil	1.2	54.0	9.1	85	1.1	33.3	5.4	190	1.37	6.3	4.2	0.7	62	0.6	1.1	0.3	25	1.76	0.079	4
1286885	Soil	25.5	54.1	14.8	425	0.7	93.4	10.6	298	2.25	49.7	3.8	2.7	95	4.2	7.1	0.2	107	1.75	0.144	13
1286886	Soil	13.9	62.6	14.2	643	0.8	89.4	8.3	235	2.18	39.1	4.9	2.2	64	4.4	5.8	0.2	96	0.45	0.147	13
1286887	Soil	6.7	53.7	12.5	259	1.0	50.0	6.2	120	1.69	16.5	5.5	2.2	56	3.8	3.8	0.2	74	0.45	0.096	12
1286888	Soil	11.2	53.6	14.2	256	0.4	51.5	8.4	111	1.81	28.0	3.9	2.6	61	3.0	5.3	0.2	78	0.29	0.115	9
1286889	Soil	12.6	56.8	14.6	228	0.6	50.2	4.7	44	1.40	24.0	3.9	2.4	48	3.9	4.5	0.2	93	0.33	0.118	12
1286890	Soil	10.3	36.6	14.3	226	0.5	43.6	11.3	340	2.20	18.6	4.3	2.0	47	2.0	3.1	0.2	71	0.51	0.088	9
1286251	Soil	4.4	26.9	13.2	114	0.4	25.4	5.0	107	2.06	18.1	2.5	2.1	42	0.5	2.1	0.2	44	0.27	0.099	8
1286252	Soil	5.6	45.5	15.4	187	0.5	39.8	8.7	269	2.81	20.6	4.6	2.3	44	1.8	3.0	0.2	74	0.24	0.103	10
1286253	Soil	5.8	54.6	17.4	193	0.5	38.3	7.0	216	2.74	21.5	5.5	1.6	46	1.3	3.6	0.3	84	0.25	0.104	10
1286254	Soil	8.3	42.4	13.9	262	0.8	60.9	10.7	298	1.96	16.5	2.9	1.8	69	3.0	3.2	0.2	92	1.03	0.097	7
1286255	Soil	16.5	40.2	15.8	239	0.6	45.1	8.5	185	2.45	23.7	2.9	2.6	48	1.3	3.5	0.2	97	0.39	0.104	11
1286256	Soil	8.7	38.4	9.7	177	0.7	49.6	6.5	263	1.47	12.0	4.1	0.6	39	2.2	2.6	0.1	74	0.46	0.057	5
1286257	Soil	16.8	58.5	17.9	309	0.8	70.5	10.1	236	2.44	26.1	4.9	1.9	62	3.0	4.9	0.2	96	0.54	0.111	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1289378	Soil	17	0.16	719	0.001	4	0.96	0.007	0.07	<0.1	0.34	2.2	0.2	0.06	2	2.9	<0.2
1289379	Soil	17	0.21	947	0.003	5	0.84	0.007	0.08	0.1	0.32	2.7	0.2	<0.05	2	2.8	<0.2
1289380	Soil	17	0.17	901	0.001	3	0.90	0.009	0.07	<0.1	0.32	2.2	0.2	0.06	2	1.7	<0.2
1289211	Soil	19	0.06	478	0.003	4	0.42	0.003	0.06	0.9	0.31	2.6	2.6	<0.05	<1	3.8	<0.2
1289212	Soil	14	1.91	403	0.002	4	0.13	0.005	0.03	0.4	0.52	2.6	1.0	<0.05	<1	4.0	<0.2
1289213	Soil	10	0.67	331	0.001	3	0.13	0.002	0.04	0.5	0.54	2.8	1.6	<0.05	<1	2.8	<0.2
1289214	Soil	12	0.22	890	0.001	6	0.29	0.002	0.09	0.3	1.15	3.8	0.6	<0.05	<1	7.0	<0.2
1289215	Soil	10	0.42	418	0.002	6	0.25	0.002	0.09	0.4	1.41	3.1	0.8	<0.05	<1	3.5	<0.2
1289216	Soil	10	1.70	442	<0.001	6	0.19	0.003	0.07	<0.1	0.64	4.2	0.4	<0.05	<1	3.2	<0.2
1289217	Soil	14	4.38	400	0.002	8	0.24	0.005	0.09	<0.1	0.41	4.0	0.3	<0.05	<1	2.4	<0.2
1289218	Soil	12	0.05	325	0.002	2	0.43	0.002	0.05	0.1	0.21	2.1	0.3	<0.05	<1	3.4	<0.2
1289219	Soil	11	0.04	434	0.002	3	0.27	0.001	0.07	0.2	0.64	5.2	0.3	<0.05	<1	2.7	<0.2
1289220	Soil	26	0.03	60	0.006	4	0.38	0.006	0.46	1.5	1.76	1.6	2.6	1.21	2	9.4	0.4
1286881	Soil	13	0.13	403	0.002	3	0.71	0.008	0.05	<0.1	0.29	2.4	0.1	0.15	2	2.0	<0.2
1286882	Soil	17	0.13	379	0.002	3	0.62	0.004	0.07	<0.1	0.16	3.0	0.1	0.05	2	2.0	<0.2
1286883	Soil	17	0.11	408	0.002	4	0.62	0.007	0.06	<0.1	0.13	2.7	<0.1	0.18	2	2.0	<0.2
1286884	Soil	14	0.17	343	0.002	3	0.64	0.008	0.05	<0.1	0.32	2.0	0.1	0.17	2	2.5	<0.2
1286885	Soil	18	0.81	1132	0.013	4	0.46	0.004	0.08	0.1	1.36	2.9	0.5	0.11	1	2.4	<0.2
1286886	Soil	18	0.10	1331	0.003	4	0.64	0.005	0.07	0.1	0.92	3.0	0.5	0.08	2	2.0	<0.2
1286887	Soil	23	0.20	1445	0.005	3	0.76	0.004	0.08	0.2	0.73	3.5	0.3	0.10	2	1.9	<0.2
1286888	Soil	17	0.10	1232	0.002	3	0.51	0.003	0.06	0.1	0.62	2.6	0.3	<0.05	1	2.6	<0.2
1286889	Soil	19	0.09	1075	0.002	5	0.51	0.003	0.09	<0.1	0.79	2.7	0.3	0.09	1	3.1	<0.2
1286890	Soil	18	0.16	1192	0.002	2	0.86	0.005	0.08	0.1	0.36	3.1	0.2	0.09	2	1.9	<0.2
1286251	Soil	16	0.20	773	0.003	3	0.78	0.004	0.06	<0.1	0.15	1.9	0.2	0.06	2	1.4	<0.2
1286252	Soil	22	0.23	2397	0.005	3	1.08	0.005	0.08	0.1	0.26	2.4	0.2	0.06	3	1.6	<0.2
1286253	Soil	25	0.23	1485	0.003	3	1.06	0.006	0.09	0.2	0.83	1.9	0.2	0.08	3	1.9	<0.2
1286254	Soil	18	0.18	1516	0.001	3	0.83	0.009	0.08	<0.1	0.36	2.9	0.3	0.14	2	2.4	<0.2
1286255	Soil	22	0.20	996	0.002	2	0.88	0.005	0.08	0.1	0.48	2.8	0.2	0.07	3	1.9	<0.2
1286256	Soil	15	0.11	1068	0.003	4	0.67	0.020	0.08	<0.1	0.34	1.6	0.3	0.10	2	1.2	<0.2
1286257	Soil	21	0.16	1525	0.002	3	0.82	0.008	0.08	0.1	0.52	3.0	0.3	0.09	2	2.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286258	Soil	9.7	43.1	18.3	233	0.5	56.2	14.0	564	3.18	25.5	1.7	2.7	42	1.2	2.3	0.2	54	0.39	0.111	6
1286259	Soil	4.9	36.2	15.9	152	0.5	35.4	8.0	275	2.21	13.3	2.9	1.9	38	1.3	1.4	0.2	43	0.47	0.077	5
1286260	Soil	6.4	32.6	19.2	142	0.5	35.2	9.8	289	2.64	17.7	2.2	2.4	36	1.1	1.8	0.2	47	0.22	0.084	6
1286211	Soil	2.0	40.8	9.0	89	1.3	27.9	5.3	185	1.34	8.1	4.2	0.5	50	1.2	1.1	0.2	24	0.72	0.063	5
1286212	Soil	3.1	88.9	14.8	252	1.0	60.9	11.1	511	2.68	14.4	5.7	1.2	109	3.0	1.6	0.2	45	1.66	0.116	8
1286213	Soil	3.7	42.9	15.3	140	0.6	36.1	8.6	229	2.60	14.9	4.7	1.9	23	0.9	1.8	0.2	42	0.12	0.064	7
1286214	Soil	2.7	25.0	13.4	45	2.5	11.6	3.2	64	1.44	10.3	7.7	0.8	24	0.6	0.8	0.2	35	0.34	0.089	4
1286215	Soil	3.9	29.7	10.8	92	1.4	27.4	3.9	138	1.73	11.8	5.7	0.8	32	0.6	1.3	0.2	27	0.86	0.075	3
1286216	Soil	2.8	38.8	13.8	121	1.4	25.6	5.0	176	2.01	11.2	5.8	1.3	45	0.8	1.4	0.2	40	0.99	0.091	5
1286217	Soil	3.5	43.4	16.3	142	1.0	37.8	7.8	232	2.63	17.2	6.8	1.9	36	0.7	1.9	0.2	41	0.60	0.087	7
1286218	Soil	1.9	32.1	15.2	88	0.9	30.1	7.2	223	2.19	11.9	3.4	1.7	28	0.8	0.9	0.2	41	0.31	0.072	6
1286219	Soil	2.5	37.4	15.0	116	0.6	29.7	6.1	187	2.40	13.4	5.3	1.7	23	0.5	1.4	0.2	44	0.21	0.082	8
1286220	Soil	3.2	56.9	20.9	162	0.6	50.1	12.6	308	3.18	20.0	9.0	3.0	40	0.7	2.0	0.3	52	0.32	0.077	7
1289151	Soil	2.4	47.4	12.2	136	0.9	44.0	8.4	360	1.92	10.6	10.7	0.5	88	0.6	2.3	0.2	53	2.73	0.098	9
1289152	Soil	2.4	67.4	10.0	87	1.0	44.9	9.4	292	1.60	10.4	4.8	0.9	76	0.5	1.3	0.1	42	0.88	0.071	7
1289153	Soil	1.3	27.5	10.6	43	1.0	20.8	7.1	367	1.45	7.7	1.7	0.6	77	0.7	1.1	0.2	50	2.97	0.134	6
1289154	Soil	5.6	57.2	13.7	184	0.5	44.7	8.6	199	2.55	19.2	5.2	1.8	40	1.2	2.5	0.2	75	0.43	0.079	9
1289155	Soil	5.0	55.8	11.8	175	0.6	43.5	7.0	178	2.39	16.6	5.6	1.4	44	0.7	2.3	0.2	62	0.44	0.096	7
1289156	Soil	4.6	34.6	13.7	147	0.5	35.4	6.9	202	2.52	15.1	2.7	1.3	32	0.8	2.3	0.3	60	0.20	0.074	8
1289157	Soil	2.6	68.6	8.1	199	0.6	42.4	5.5	151	1.55	9.3	4.9	0.5	79	4.0	1.7	0.3	40	1.74	0.114	5
1289159	Soil	3.2	53.9	10.6	155	0.7	45.1	6.4	201	1.89	12.1	4.3	1.2	98	1.7	3.0	0.2	51	1.75	0.106	7
1289160	Soil	2.5	58.1	11.7	330	0.9	68.4	10.2	509	2.11	14.2	8.4	1.1	118	2.4	2.2	0.2	53	3.90	0.143	10
1283198	Soil	69.3	104.8	11.5	1492	3.0	268.1	17.2	289	4.46	119.3	4.7	1.7	43	17.4	23.2	0.2	545	0.15	0.205	18
1283199	Soil	51.2	69.3	9.5	962	1.4	172.9	7.5	92	2.23	467.6	2.1	2.8	75	10.5	13.6	0.2	447	0.29	0.119	18
1283200	Soil	71.0	147.6	15.5	976	4.3	173.3	10.4	91	3.62	192.2	3.4	3.4	353	5.2	38.2	0.3	1176	0.13	0.402	18
1281226	Soil	3.4	61.5	11.9	456	0.4	70.1	16.8	232	1.93	70.9	3.4	0.7	13	1.3	1.5	0.6	112	0.20	0.102	9
1281227	Soil	17.5	446.4	42.5	753	1.2	131.2	177.7	1618	3.89	80.2	6.8	1.7	31	2.0	6.9	0.4	164	0.31	0.131	20
1281228	Soil	9.4	22.0	8.9	104	0.5	23.7	3.2	61	1.26	18.1	1.9	0.4	18	0.4	2.7	0.1	81	0.15	0.040	6
1281229	Soil	1.4	22.5	6.5	32	0.3	6.5	1.7	33	0.86	10.1	2.4	0.2	11	<0.1	1.0	0.1	19	0.05	0.031	4
1281230	Soil	5.8	262.6	73.3	323	3.0	61.9	6.2	173	9.09	157.5	19.8	4.0	96	0.3	12.5	0.7	72	0.15	0.119	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286258	Soil	19	0.18	1355	0.001	1	0.90	0.006	0.07	<0.1	0.24	3.5	0.2	0.07	2	3.1	<0.2
1286259	Soil	19	0.18	1046	0.001	2	0.90	0.010	0.07	<0.1	0.24	3.1	0.2	0.16	2	2.7	<0.2
1286260	Soil	20	0.19	1357	0.001	2	0.93	0.005	0.07	<0.1	0.29	2.9	0.2	0.07	3	2.3	<0.2
1286211	Soil	14	0.13	1899	0.007	3	0.67	0.021	0.05	<0.1	0.19	2.1	0.1	0.22	2	0.9	<0.2
1286212	Soil	30	0.26	2621	0.007	5	1.03	0.009	0.08	<0.1	0.37	3.2	0.1	0.19	2	3.2	<0.2
1286213	Soil	18	0.16	2195	0.002	2	0.86	0.008	0.05	<0.1	0.15	2.1	0.1	0.06	2	1.1	<0.2
1286214	Soil	15	0.06	403	0.001	2	0.62	0.010	0.07	<0.1	0.34	1.4	0.2	0.10	2	1.9	<0.2
1286215	Soil	16	0.09	374	0.002	3	0.48	0.011	0.06	<0.1	0.26	1.7	0.1	0.13	2	1.8	<0.2
1286216	Soil	19	0.14	580	0.002	4	0.85	0.011	0.08	<0.1	0.21	2.3	0.2	0.16	2	1.3	<0.2
1286217	Soil	18	0.14	422	0.002	6	0.75	0.007	0.09	<0.1	0.24	2.8	0.2	0.07	2	1.2	<0.2
1286218	Soil	17	0.11	422	0.001	2	0.76	0.006	0.06	<0.1	0.14	2.1	0.1	0.09	2	1.3	<0.2
1286219	Soil	21	0.18	539	0.003	3	0.92	0.010	0.08	<0.1	0.14	2.5	0.1	<0.05	3	1.3	<0.2
1286220	Soil	28	0.30	1458	0.002	6	1.20	0.006	0.13	<0.1	0.41	4.7	0.2	<0.05	3	1.6	<0.2
1289151	Soil	30	0.19	2693	0.002	6	1.06	0.009	0.06	<0.1	0.87	1.5	0.2	0.14	2	2.1	<0.2
1289152	Soil	17	0.13	2309	0.006	3	0.84	0.016	0.06	0.1	0.21	2.3	0.1	0.11	2	2.1	<0.2
1289153	Soil	22	0.13	1556	0.008	5	1.02	0.011	0.05	0.1	0.35	1.6	0.1	0.25	3	1.7	<0.2
1289154	Soil	28	0.25	2501	0.002	4	1.13	0.006	0.10	<0.1	0.26	2.5	0.2	0.09	3	1.4	<0.2
1289155	Soil	24	0.23	2156	0.002	2	0.98	0.006	0.08	<0.1	0.22	2.0	0.2	<0.05	3	1.4	<0.2
1289156	Soil	21	0.25	1887	0.003	4	1.02	0.007	0.07	<0.1	0.15	1.5	0.1	0.12	3	1.4	<0.2
1289157	Soil	16	0.18	988	0.006	6	0.88	0.011	0.06	<0.1	0.49	1.7	0.2	0.20	2	3.3	<0.2
1289159	Soil	16	0.23	1367	0.003	6	0.91	0.013	0.11	0.1	0.33	1.8	0.2	0.17	2	1.7	<0.2
1289160	Soil	28	0.32	1063	0.002	8	1.00	0.007	0.11	<0.1	0.61	2.2	0.3	0.24	3	4.2	<0.2
1283198	Soil	48	0.10	553	0.004	7	1.33	0.003	0.12	0.3	0.81	2.7	3.4	0.09	3	17.2	<0.2
1283199	Soil	26	0.12	617	0.002	8	1.03	0.001	0.10	0.3	0.56	2.4	1.7	<0.05	1	6.9	<0.2
1283200	Soil	101	0.14	858	0.006	8	2.11	0.004	0.18	0.6	6.40	3.7	4.1	0.13	4	16.1	0.3
1281226	Soil	29	1.33	135	0.047	1	2.06	0.016	0.08	0.2	0.02	1.1	0.3	<0.05	6	0.9	<0.2
1281227	Soil	31	0.79	107	0.040	1	3.17	0.014	0.15	0.1	0.08	2.2	0.8	0.14	5	5.9	<0.2
1281228	Soil	16	0.59	62	0.031	<1	1.17	0.026	0.06	0.1	0.02	0.7	0.3	<0.05	3	1.1	<0.2
1281229	Soil	5	0.10	28	0.025	<1	0.71	0.029	0.03	<0.1	0.03	0.4	<0.1	<0.05	3	1.0	<0.2
1281230	Soil	26	0.56	157	0.037	1	2.46	0.021	0.14	0.1	0.05	2.4	0.4	0.18	5	12.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286891	Soil		28.0	37.0	12.5	339	0.5	53.6	7.3	259	2.59	31.7	1.7	2.5	60	1.5	4.8	0.2	178	0.69	0.125	10
1286892	Soil		8.9	39.9	12.7	207	0.8	38.3	7.7	276	2.34	19.8	3.3	1.8	43	1.9	3.1	0.2	78	0.30	0.103	9
1286893	Soil		16.3	67.4	16.1	1031	1.0	168.1	14.8	679	2.49	32.2	2.0	1.9	94	10.9	5.2	0.2	138	1.13	0.111	9
1286894	Soil		21.1	52.1	12.3	810	0.7	108.1	7.2	228	1.93	28.0	2.5	1.9	62	5.3	5.4	0.1	182	0.72	0.129	10
1286895	Soil		27.8	48.9	12.6	935	0.5	130.7	8.0	291	1.67	28.7	2.1	1.4	91	7.7	6.9	0.1	229	1.95	0.120	8
1286896	Soil		10.4	56.8	13.8	395	0.8	70.4	7.3	184	2.06	30.1	4.2	1.6	73	3.8	5.1	0.2	106	0.78	0.121	9
1286897	Soil		21.2	54.2	13.9	536	0.7	85.1	9.1	299	2.24	40.2	2.9	2.0	84	4.1	5.6	0.1	113	0.92	0.149	11
1286898	Soil		30.0	27.9	15.7	175	0.8	34.3	13.7	945	3.24	50.1	3.2	1.3	44	2.3	3.9	0.2	124	0.50	0.121	8
1286899	Soil		13.6	33.4	12.6	292	0.4	50.0	9.2	479	2.09	23.5	2.4	2.0	51	2.2	4.2	0.1	99	0.54	0.128	10
1286900	Soil		8.3	37.3	11.9	215	0.6	48.8	7.8	257	1.83	16.8	2.8	2.0	55	2.1	3.9	0.1	79	0.67	0.132	9
1279121	Soil		12.6	65.6	14.4	294	0.9	50.7	5.5	119	2.29	43.7	8.2	2.0	78	2.2	8.8	0.2	128	0.32	0.166	8
1279122	Soil		11.5	59.4	14.1	281	0.9	47.1	5.3	130	2.24	41.4	8.1	1.8	73	2.6	8.5	0.1	120	0.31	0.166	7
1279123	Soil		9.6	55.9	11.9	182	0.6	33.2	4.6	101	1.72	28.2	5.9	1.6	69	2.3	6.8	0.1	111	0.19	0.131	6
1279124	Soil		10.7	53.9	14.4	166	0.6	32.3	4.3	89	1.81	31.3	5.9	1.8	64	1.8	6.7	0.2	105	0.15	0.112	7
1279125	Soil		10.7	53.3	13.0	179	0.8	36.3	5.0	99	1.79	30.8	6.9	1.6	67	1.4	7.0	0.1	117	0.24	0.130	7
1279126	Soil		11.1	67.2	16.0	274	1.1	55.6	6.6	177	2.34	49.3	9.7	2.0	71	2.3	8.6	0.2	101	0.30	0.135	7
1279127	Soil		2.3	52.1	25.4	72	4.1	23.5	2.8	58	1.63	45.4	46.5	1.4	47	1.0	5.4	0.6	45	0.34	0.110	9
1279128	Soil		11.1	58.5	12.8	253	0.8	44.0	4.3	96	2.18	36.0	7.0	1.8	75	2.6	8.3	0.1	117	0.31	0.167	7
1279129	Soil		11.6	105.1	17.1	282	1.1	57.2	6.6	200	2.50	47.9	10.6	1.9	76	2.2	8.9	0.2	113	0.38	0.155	8
1288054	Soil		1.7	17.0	8.8	47	0.1	13.1	7.8	776	1.48	3.8	2.0	0.3	13	0.3	0.8	0.2	27	0.04	0.112	4
1288055	Soil		1.7	16.0	4.0	20	<0.1	8.3	2.5	54	0.79	3.3	1.2	<0.1	5	<0.1	0.7	<0.1	23	0.02	0.035	2
1288056	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1288057	Soil		2.6	37.9	30.6	104	<0.1	28.0	11.2	296	4.00	16.1	1.4	1.9	21	0.1	1.2	0.2	29	0.03	0.092	3
1288058	Soil		2.1	12.8	9.4	48	<0.1	10.0	3.4	81	1.80	7.6	<0.5	0.2	8	<0.1	0.9	0.2	37	0.02	0.054	5
1288059	Soil		2.3	28.2	24.3	133	<0.1	28.9	17.2	823	4.22	17.3	1.4	0.7	10	0.1	1.5	0.4	35	0.03	0.110	4
1288060	Soil		1.6	30.5	30.8	181	0.2	33.7	29.1	889	3.34	17.4	1.5	1.0	13	0.1	1.3	0.3	24	0.02	0.081	3
1288631	Soil		6.9	43.8	14.1	179	0.9	37.8	6.6	206	1.87	19.7	7.0	1.5	121	2.3	3.4	0.2	74	0.79	0.087	7
1288632	Soil		7.2	62.6	16.1	810	1.4	100.7	8.2	266	2.22	20.9	6.7	1.9	164	11.8	5.5	0.3	101	0.96	0.122	10
1288633	Soil		10.6	35.6	18.9	202	0.4	38.5	6.1	150	2.69	28.7	4.4	2.7	30	0.6	4.0	0.2	108	0.06	0.087	11
1288634	Soil		12.2	49.0	25.3	231	0.5	50.9	7.6	127	3.20	36.0	6.5	2.7	38	0.7	4.6	0.3	98	0.06	0.066	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286891	Soil	20	0.20	838	0.002	6	0.71	0.004	0.10	0.2	0.28	2.3	0.6	0.05	2	2.6	<0.2
1286892	Soil	18	0.19	1089	0.002	3	0.91	0.010	0.09	0.1	0.35	2.3	0.3	<0.05	3	1.8	<0.2
1286893	Soil	21	0.24	1376	0.002	7	0.96	0.007	0.11	0.1	0.44	3.0	0.9	0.12	3	3.9	<0.2
1286894	Soil	18	0.15	881	0.002	5	0.61	0.004	0.10	0.1	0.55	2.8	0.8	0.08	2	3.2	<0.2
1286895	Soil	20	0.27	698	0.002	5	0.61	0.005	0.09	0.1	0.47	2.3	1.0	0.13	2	4.2	<0.2
1286896	Soil	20	0.16	1326	0.002	7	0.71	0.005	0.11	0.1	0.88	2.5	0.4	0.09	2	4.1	<0.2
1286897	Soil	18	0.38	910	0.002	5	0.56	0.004	0.10	0.1	0.82	2.5	0.5	0.09	2	3.1	<0.2
1286898	Soil	17	0.13	804	0.003	2	0.84	0.011	0.07	0.1	0.48	2.3	0.3	0.07	3	2.9	<0.2
1286899	Soil	16	0.15	963	0.003	5	0.68	0.006	0.10	0.1	0.33	2.3	0.3	0.09	2	2.7	<0.2
1286900	Soil	16	0.19	975	0.003	4	0.71	0.007	0.09	0.1	0.37	2.8	0.2	0.08	2	2.8	<0.2
1279121	Soil	23	0.07	1305	0.002	6	0.51	0.002	0.10	0.1	1.22	2.8	0.4	0.09	2	3.3	<0.2
1279122	Soil	21	0.06	1270	0.002	5	0.50	0.003	0.09	0.1	1.06	2.6	0.4	0.07	2	3.3	<0.2
1279123	Soil	21	0.05	1775	0.001	5	0.48	0.002	0.10	<0.1	0.91	2.6	0.4	0.08	1	2.6	<0.2
1279124	Soil	20	0.07	1434	0.002	4	0.53	0.003	0.08	<0.1	0.88	2.6	0.4	0.09	2	2.6	<0.2
1279125	Soil	22	0.06	1250	0.002	6	0.49	0.002	0.10	<0.1	1.08	2.5	0.4	0.08	2	2.5	<0.2
1279126	Soil	20	0.08	954	0.001	2	0.49	0.002	0.08	0.1	1.40	2.9	0.3	0.06	1	2.5	<0.2
1279127	Soil	18	0.06	515	<0.001	3	0.81	0.007	0.08	0.1	5.69	3.6	0.5	0.09	2	4.9	<0.2
1279128	Soil	21	0.07	1083	0.001	4	0.46	0.002	0.08	0.1	0.87	2.5	0.4	0.06	1	2.9	<0.2
1279129	Soil	23	0.10	1141	0.002	4	0.61	0.003	0.09	0.1	1.47	3.0	0.4	0.06	2	3.2	<0.2
1288054	Soil	8	0.03	138	0.005	1	0.53	0.014	0.05	<0.1	0.06	0.9	<0.1	0.07	2	<0.5	<0.2
1288055	Soil	5	0.02	51	0.003	2	0.20	0.014	0.04	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2
1288056	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1288057	Soil	23	0.38	76	0.003	1	1.19	0.011	0.07	<0.1	0.04	2.5	0.2	0.06	4	0.6	<0.2
1288058	Soil	12	0.06	53	0.005	<1	0.55	0.010	0.04	<0.1	0.03	0.5	0.1	<0.05	4	<0.5	<0.2
1288059	Soil	24	0.22	114	0.004	3	1.10	0.006	0.05	<0.1	0.04	1.5	0.2	0.08	5	0.6	<0.2
1288060	Soil	22	0.32	101	0.003	3	1.27	0.012	0.05	<0.1	0.02	1.9	0.2	0.06	4	0.5	<0.2
1288631	Soil	18	0.15	1427	0.003	6	0.81	0.012	0.07	0.1	0.59	2.5	0.2	0.10	2	2.3	<0.2
1288632	Soil	23	0.18	2012	0.005	12	1.06	0.010	0.13	0.1	0.50	3.2	1.6	0.19	3	6.9	0.2
1288633	Soil	22	0.14	508	0.007	4	1.06	0.004	0.07	0.1	0.18	2.1	0.4	<0.05	3	2.0	<0.2
1288634	Soil	22	0.14	502	0.004	5	1.05	0.005	0.08	0.1	0.21	2.4	0.4	<0.05	4	2.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288635	Soil		10.5	25.5	17.9	139	0.7	27.0	4.7	126	2.05	25.1	4.9	0.6	33	0.6	3.9	0.2	69	0.08	0.066	9
1288636	Soil		7.3	49.6	11.7	324	0.7	55.1	5.9	162	2.33	19.0	6.5	1.8	49	2.7	4.2	0.2	75	0.44	0.110	9
1288637	Soil		2.9	30.8	15.4	118	1.5	25.4	12.6	299	1.77	12.8	5.4	1.0	71	1.1	1.5	0.2	62	1.14	0.101	4
1288638	Soil		7.5	41.7	13.5	233	0.6	39.4	8.1	248	2.38	18.4	4.0	2.0	54	1.3	3.7	0.2	71	0.41	0.098	8
1288639	Soil		9.8	87.9	11.6	219	0.4	40.3	6.6	120	2.56	19.5	27.2	0.2	11	0.5	4.1	0.2	127	0.02	0.063	5
1288640	Soil		10.5	32.5	14.4	100	0.4	18.4	3.1	58	1.37	13.0	1.5	0.3	18	0.6	4.9	0.2	119	0.01	0.045	11
1287931	Soil		7.7	91.5	19.4	325	2.0	88.5	15.1	232	3.51	18.9	5.0	6.8	53	1.0	2.7	0.3	21	0.76	0.098	15
1287932	Soil		4.1	57.5	17.7	139	2.0	63.0	13.3	308	2.91	14.9	4.3	5.7	143	0.3	2.3	0.2	13	3.87	0.037	7
1287933	Soil		5.1	70.3	22.4	131	2.6	83.3	16.4	383	4.05	19.8	3.6	7.0	155	0.2	2.8	0.3	19	4.28	0.040	13
1287934	Soil		17.9	71.8	19.9	310	1.3	82.3	13.2	161	3.60	31.2	4.1	3.5	18	0.7	4.0	0.3	36	0.28	0.074	21
1287935	Soil		11.3	39.2	13.5	413	1.1	70.5	10.3	376	2.88	23.6	3.0	2.1	19	5.7	4.8	0.2	42	0.32	0.097	23
1287936	Soil		13.4	50.9	12.9	924	0.6	147.4	11.0	478	2.81	41.5	1.2	5.6	86	4.4	13.6	0.1	31	3.92	0.053	15
1287937	Soil		5.4	35.3	11.6	1000	1.3	135.5	19.9	372	2.19	32.6	0.7	6.1	37	1.0	7.8	0.2	13	1.75	0.031	13
1287938	Soil		29.6	36.7	10.3	1834	0.4	310.4	17.2	789	2.97	36.7	1.3	3.6	118	18.7	10.9	0.1	130	5.14	0.115	21
1287939	Soil		23.8	16.8	6.4	876	0.2	230.2	31.6	918	1.71	25.5	1.0	3.2	183	13.2	6.8	<0.1	99	8.17	0.067	15
1287940	Soil		37.0	24.9	7.0	987	0.2	268.0	16.0	590	2.26	30.3	<0.5	3.1	155	15.8	8.4	<0.1	102	7.71	0.064	15
1287191	Soil		1.5	67.6	15.6	220	0.9	49.5	7.4	140	1.48	13.3	6.2	1.8	98	1.9	1.3	0.2	56	0.75	0.089	7
1287192	Soil		3.6	62.3	14.4	255	0.8	63.2	11.0	1099	2.80	17.4	8.2	1.3	123	2.9	1.8	0.2	57	1.25	0.101	6
1287193	Soil		2.6	62.4	13.2	238	0.7	52.8	8.1	609	2.72	14.6	6.2	1.6	99	2.3	1.8	0.2	52	0.73	0.087	7
1287194	Soil		2.1	37.4	9.2	204	0.4	37.6	7.2	185	2.61	12.2	5.0	1.7	77	1.3	1.1	0.1	47	0.56	0.091	6
1287195	Soil		3.7	82.8	12.7	242	0.9	60.7	14.4	111	1.89	10.5	7.8	1.5	137	2.0	1.9	0.2	47	1.13	0.077	6
1287196	Soil		6.1	47.7	11.3	145	1.1	31.2	5.0	164	1.65	14.3	7.2	1.7	132	1.6	4.4	0.2	110	0.79	0.110	8
1287197	Soil		1.8	39.0	11.1	120	0.4	20.3	5.9	155	1.76	8.1	7.6	0.9	62	1.0	0.8	0.2	34	0.77	0.059	5
1287198	Soil		1.3	24.2	9.2	200	0.7	24.8	5.9	277	1.49	9.3	3.3	0.5	90	1.5	1.7	0.2	48	2.56	0.080	6
1287199	Soil		1.2	12.0	27.7	124	0.3	19.0	4.5	164	1.52	11.6	2.9	2.0	66	1.7	0.9	0.6	18	1.85	0.067	13
1287200	Soil		1.3	33.8	10.8	145	0.5	25.3	5.8	426	1.37	8.8	2.9	0.4	104	3.2	1.1	0.2	44	2.86	0.110	12
1287471	Soil		5.0	36.9	31.9	98	0.8	21.5	4.0	74	1.99	43.0	3.4	1.6	29	0.5	4.6	0.3	43	0.05	0.060	19
1287472	Soil		2.8	37.3	60.5	85	0.9	14.0	3.0	61	2.47	121.2	2.1	6.2	51	0.4	5.4	0.8	24	0.02	0.069	29
1287473	Soil		6.3	38.6	17.2	110	0.9	17.2	3.0	72	2.74	162.6	5.0	5.0	30	0.3	6.6	0.8	37	0.01	0.054	21
1287474	Soil		1.8	29.3	8.6	68	0.6	14.7	3.1	51	2.49	307.3	2.0	9.0	57	0.3	5.6	1.6	17	<0.01	0.062	31

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288635	Soil	15	0.11	434	0.006	4	0.61	0.009	0.07	0.1	0.14	0.9	0.3	<0.05	2	2.4	<0.2
1288636	Soil	20	0.18	2808	0.003	5	0.88	0.011	0.09	0.1	0.37	2.5	0.3	0.06	2	2.1	<0.2
1288637	Soil	17	0.23	1773	0.002	4	1.12	0.016	0.07	<0.1	0.42	2.5	0.2	0.10	3	1.4	<0.2
1288638	Soil	19	0.21	3039	0.002	3	0.86	0.004	0.08	<0.1	0.56	2.3	0.2	0.05	2	1.8	<0.2
1288639	Soil	13	0.03	162	0.003	6	0.35	0.004	0.07	<0.1	0.05	1.0	0.3	<0.05	2	2.9	<0.2
1288640	Soil	15	0.02	260	0.004	4	0.35	0.003	0.07	0.1	0.03	0.3	0.4	<0.05	3	3.9	<0.2
1287931	Soil	9	0.36	1968	0.003	9	0.34	0.003	0.11	<0.1	0.53	4.8	0.3	<0.05	<1	3.5	<0.2
1287932	Soil	8	2.16	909	<0.001	5	0.21	0.004	0.08	<0.1	0.49	3.8	0.2	0.11	<1	1.8	<0.2
1287933	Soil	12	2.43	971	0.003	7	0.23	0.004	0.10	<0.1	0.55	4.6	0.2	0.18	<1	2.0	<0.2
1287934	Soil	9	0.10	951	0.002	4	0.42	0.003	0.08	<0.1	0.26	3.1	0.3	0.08	<1	2.7	<0.2
1287935	Soil	15	0.13	2318	0.005	3	0.50	0.003	0.08	0.6	0.23	2.7	0.2	0.06	1	1.5	<0.2
1287936	Soil	9	2.29	228	0.001	5	0.21	0.002	0.07	0.1	1.12	4.9	0.4	0.09	<1	2.7	<0.2
1287937	Soil	9	1.02	136	0.004	6	0.18	0.002	0.07	<0.1	0.61	3.6	0.2	0.11	<1	2.0	<0.2
1287938	Soil	13	3.06	653	0.002	9	0.47	0.006	0.08	0.2	0.60	4.0	1.7	0.10	<1	5.3	<0.2
1287939	Soil	12	5.16	330	0.002	11	0.28	0.008	0.06	0.2	0.10	2.7	1.5	0.12	<1	3.4	<0.2
1287940	Soil	16	4.75	307	0.002	10	0.34	0.007	0.07	0.3	0.12	2.9	1.8	0.13	<1	4.1	<0.2
1287191	Soil	27	0.37	1485	0.004	5	1.34	0.009	0.09	<0.1	0.49	3.1	0.3	0.21	3	3.0	<0.2
1287192	Soil	25	0.37	1401	0.002	6	1.05	0.008	0.08	<0.1	0.51	2.8	0.2	0.21	3	4.0	<0.2
1287193	Soil	26	0.33	1617	0.004	9	1.08	0.007	0.08	0.1	0.41	2.8	0.2	0.19	3	3.5	<0.2
1287194	Soil	22	0.32	1461	0.002	5	0.99	0.005	0.07	<0.1	0.25	2.2	0.1	0.12	3	2.3	<0.2
1287195	Soil	26	0.32	238	0.004	5	1.07	0.009	0.09	<0.1	0.37	3.0	0.2	0.64	3	5.8	<0.2
1287196	Soil	22	0.18	2360	0.004	6	0.83	0.009	0.10	0.1	0.56	2.3	0.3	0.12	2	2.2	<0.2
1287197	Soil	26	0.27	780	0.007	6	0.85	0.012	0.07	<0.1	0.17	2.3	0.1	0.09	2	1.0	<0.2
1287198	Soil	18	0.16	1218	0.003	5	0.78	0.013	0.06	0.1	0.40	1.4	0.1	0.16	2	2.0	<0.2
1287199	Soil	15	0.13	834	0.002	5	0.81	0.008	0.05	<0.1	0.23	1.3	0.1	0.10	2	1.5	<0.2
1287200	Soil	22	0.14	1122	0.009	8	0.94	0.013	0.05	<0.1	0.26	1.5	0.1	0.14	2	2.1	<0.2
1287471	Soil	11	0.08	239	0.005	3	0.59	0.008	0.07	0.3	0.66	1.2	0.2	0.07	2	1.5	<0.2
1287472	Soil	9	0.18	166	<0.001	2	0.66	0.002	0.09	0.1	0.20	2.0	0.2	0.11	2	1.2	<0.2
1287473	Soil	13	0.14	142	0.001	4	0.72	0.003	0.08	0.3	0.53	1.4	0.2	0.07	2	2.0	<0.2
1287474	Soil	14	0.23	106	0.001	2	0.63	0.003	0.08	0.3	0.06	2.1	<0.1	0.07	2	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287475	Soil		2.4	42.2	20.0	79	0.6	23.5	8.6	47	2.80	381.3	3.2	9.3	48	0.1	7.0	2.8	12	<0.01	0.052	32
1287476	Soil		2.0	51.5	8.1	90	0.4	39.9	15.6	107	3.66	203.6	2.1	8.2	17	0.3	3.9	2.7	19	<0.01	0.062	32
1287477	Soil		6.1	19.2	34.5	80	1.5	15.5	3.6	82	2.15	119.3	17.8	1.7	22	0.2	10.1	2.1	52	0.03	0.048	16
1287478	Soil		4.6	38.4	22.8	92	1.3	18.9	4.6	44	2.52	295.7	28.7	2.3	33	0.2	12.7	1.7	32	0.02	0.063	18
1287479	Soil		8.8	49.6	97.6	223	1.3	33.4	8.1	125	3.07	351.2	13.2	5.5	52	0.5	16.6	1.3	45	0.03	0.075	24
1287480	Soil		2.4	27.5	20.5	41	0.4	4.4	0.9	20	1.59	115.4	3.0	6.3	70	0.2	6.3	0.4	16	0.01	0.048	26
1288451	Soil		3.9	67.8	37.0	268	0.7	74.4	26.0	637	4.45	34.1	4.8	2.5	21	0.7	5.7	0.4	21	0.16	0.085	4
1288452	Soil		4.0	90.5	49.9	654	0.9	108.6	37.9	889	5.71	17.2	4.4	3.1	16	1.5	3.6	0.5	18	0.07	0.067	2
1288453	Soil		5.4	79.8	35.8	440	1.1	68.0	19.9	531	4.14	16.1	3.2	2.0	37	2.1	3.6	0.4	31	0.13	0.082	3
1288454	Soil		4.1	77.9	35.7	359	0.7	60.7	21.8	616	4.18	14.6	3.1	2.9	24	1.7	3.5	0.4	23	0.08	0.072	3
1288455	Soil		38.9	326.6	16.1	1474	6.9	235.8	4.8	235	2.34	50.8	0.6	1.3	329	39.0	20.0	0.2	743	1.11	0.369	22
1288456	Soil		3.9	70.3	28.2	274	0.9	52.5	17.3	476	3.30	11.3	2.1	3.0	24	1.8	2.9	0.3	26	0.12	0.063	3
1288457	Soil		3.6	58.2	30.8	213	0.8	42.6	16.2	486	3.25	10.8	1.7	1.3	21	0.5	3.1	0.3	26	0.07	0.061	4
1288458	Soil		2.5	48.9	24.1	181	0.8	36.3	12.8	367	2.55	8.5	2.1	1.6	16	0.5	2.2	0.3	20	0.09	0.057	3
1288459	Soil		6.0	85.5	33.7	265	1.2	58.9	17.4	489	3.81	17.7	4.5	2.7	44	1.4	5.2	0.4	41	0.15	0.084	5
1288460	Soil		3.5	70.0	23.4	200	0.9	41.4	11.8	225	3.20	11.7	3.5	2.6	37	0.5	3.6	0.3	26	0.10	0.060	2
1287941	Soil		75.4	38.1	7.5	1927	0.5	318.0	15.2	304	3.65	37.9	0.7	2.5	37	24.6	11.8	0.1	81	0.82	0.073	14
1287942	Soil		77.9	36.8	8.4	4266	0.5	457.2	23.6	262	7.88	74.1	0.8	3.0	23	27.7	13.8	0.1	101	0.61	0.046	13
1287943	Soil		26.6	49.1	11.6	533	0.5	118.5	9.8	158	2.45	52.8	3.2	3.7	18	1.8	12.0	0.2	92	0.14	0.109	20
1287944	Soil		28.3	69.4	13.6	552	0.7	112.8	10.5	212	2.91	76.0	7.9	4.6	36	3.6	11.6	0.3	114	0.13	0.102	15
1287945	Soil		140.2	290.8	27.1	1758	3.4	196.1	9.0	96	5.36	124.7	7.0	2.0	21	11.3	75.0	0.2	833	0.06	0.135	20
1287946	Soil		113.5	249.5	12.0	4236	1.5	479.2	26.5	440	5.73	222.6	9.0	2.5	74	136.1	22.5	0.2	199	0.83	0.168	11
1287947	Soil		84.2	77.7	8.9	2079	0.7	324.6	21.2	384	4.15	171.2	35.8	4.0	54	77.6	45.2	0.1	96	0.77	0.085	11
1287948	Soil		23.6	167.0	17.0	2167	1.1	307.1	20.9	578	4.47	139.9	18.8	5.9	50	54.1	44.4	0.1	268	0.08	0.135	12
1287949	Soil		16.9	182.2	16.0	826	1.1	162.7	14.7	298	3.68	110.5	20.3	4.7	52	33.3	25.4	0.2	194	1.23	0.099	7
1287950	Soil		79.8	197.3	14.6	673	3.9	150.5	6.9	92	3.56	407.9	9.0	1.4	179	3.3	43.9	0.1	1114	0.26	0.323	13
1287481	Soil		16.4	42.2	37.2	162	1.0	33.6	4.7	67	3.01	181.3	13.7	4.4	58	0.7	13.1	0.9	71	0.03	0.079	17
1287482	Soil		23.6	26.2	28.8	100	0.9	18.1	4.1	108	3.23	244.9	6.0	5.6	68	1.0	18.3	1.0	76	0.02	0.073	15
1287483	Soil		23.7	357.7	22.8	755	0.8	145.0	12.1	2687	8.80	226.6	3.7	4.9	58	62.3	19.9	0.4	165	0.98	0.136	12
1287484	Soil		26.9	1115	18.6	1634	0.7	324.4	36.2	3803	17.21	595.4	2.2	8.0	36	128.6	20.1	0.3	229	0.36	0.241	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287475	Soil	7	<0.01	114	<0.001	2	0.24	0.002	0.08	0.4	0.58	1.3	0.1	0.12	<1	2.2	<0.2
1287476	Soil	13	0.23	87	<0.001	2	0.60	0.002	0.07	0.3	0.74	1.9	0.2	0.11	2	1.8	<0.2
1287477	Soil	12	0.10	131	0.004	2	0.67	0.004	0.05	0.6	3.76	1.0	0.3	0.06	3	1.7	<0.2
1287478	Soil	10	0.02	187	0.002	4	0.45	0.009	0.06	0.5	3.30	1.1	0.4	0.10	2	3.8	<0.2
1287479	Soil	14	0.13	202	0.001	2	0.56	0.004	0.08	0.8	2.04	1.8	0.5	0.11	2	3.0	<0.2
1287480	Soil	9	0.14	116	<0.001	<1	0.41	0.003	0.07	0.1	0.18	1.3	0.2	0.15	1	1.4	<0.2
1288451	Soil	10	0.10	533	<0.001	2	0.41	0.005	0.08	<0.1	0.22	4.3	0.2	0.09	1	1.7	<0.2
1288452	Soil	6	0.08	723	<0.001	2	0.28	0.002	0.08	<0.1	0.12	5.4	0.2	0.06	<1	2.5	<0.2
1288453	Soil	9	0.08	692	0.003	2	0.34	0.003	0.10	<0.1	0.17	5.1	0.4	0.09	1	3.4	<0.2
1288454	Soil	7	0.07	471	<0.001	2	0.29	0.002	0.08	<0.1	0.08	4.5	0.3	0.08	<1	2.6	<0.2
1288455	Soil	110	0.14	684	0.004	11	0.66	0.004	0.14	0.2	1.94	3.6	1.2	0.35	3	35.4	0.3
1288456	Soil	6	0.08	352	<0.001	1	0.30	0.005	0.07	<0.1	0.14	3.6	0.2	<0.05	<1	2.8	<0.2
1288457	Soil	7	0.07	411	0.002	1	0.40	0.008	0.07	<0.1	0.07	2.9	0.3	0.06	2	2.1	<0.2
1288458	Soil	4	0.07	283	0.004	1	0.37	0.012	0.06	<0.1	0.07	2.6	0.2	0.05	1	1.8	<0.2
1288459	Soil	15	0.09	907	0.001	2	0.40	0.005	0.11	<0.1	0.12	4.1	0.4	0.13	1	4.2	<0.2
1288460	Soil	8	0.07	619	0.001	2	0.34	0.005	0.08	<0.1	0.13	3.7	0.2	0.11	1	3.6	<0.2
1287941	Soil	15	0.39	542	0.001	3	0.32	0.002	0.06	0.4	0.26	3.2	3.2	0.08	<1	5.3	<0.2
1287942	Soil	16	0.30	354	0.001	5	0.37	0.002	0.06	0.4	0.96	3.7	3.6	0.08	<1	15.9	<0.2
1287943	Soil	15	0.05	353	0.002	2	0.50	0.002	0.05	0.3	1.07	3.2	0.5	<0.05	1	5.1	<0.2
1287944	Soil	17	0.07	618	0.002	2	0.52	0.002	0.06	0.4	2.05	3.8	0.7	0.06	1	5.6	<0.2
1287945	Soil	50	0.05	967	0.003	4	0.51	0.002	0.10	2.1	4.81	3.7	5.4	<0.05	4	27.9	0.3
1287946	Soil	34	0.13	1575	0.002	4	1.59	0.004	0.06	0.9	5.14	7.7	3.6	0.09	1	11.5	<0.2
1287947	Soil	15	0.29	590	0.001	4	0.77	0.002	0.06	0.7	13.83	3.4	2.6	0.07	<1	9.0	0.2
1287948	Soil	23	0.04	696	0.002	2	1.47	0.002	0.06	0.2	22.89	6.1	2.0	<0.05	<1	5.8	<0.2
1287949	Soil	19	0.53	405	<0.001	3	0.64	0.002	0.06	0.2	14.26	4.7	1.3	0.09	<1	5.1	<0.2
1287950	Soil	53	0.09	1295	0.006	4	1.39	0.008	0.08	0.8	6.30	3.3	2.1	0.13	2	17.1	<0.2
1287481	Soil	15	0.10	334	0.002	2	0.50	0.003	0.08	0.5	2.88	1.9	0.7	0.13	2	5.5	<0.2
1287482	Soil	11	0.03	343	<0.001	<1	0.29	0.005	0.08	0.6	2.08	1.5	0.7	0.12	1	7.6	<0.2
1287483	Soil	17	0.51	599	<0.001	3	1.00	0.005	0.06	0.3	0.53	9.4	0.5	0.12	1	3.1	<0.2
1287484	Soil	36	0.70	580	<0.001	<1	2.41	0.004	0.03	2.8	0.31	24.9	0.3	0.18	2	3.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287485	Soil		27.0	50.1	25.8	111	0.9	17.5	2.0	76	2.54	217.0	2.9	2.5	32	2.9	30.3	0.3	78	0.04	0.062	8
1287486	Soil		15.8	73.7	24.9	143	1.1	26.4	2.8	77	2.22	152.7	10.2	3.2	55	1.8	15.5	0.3	62	0.06	0.070	20
1287487	Soil		10.8	60.9	24.8	99	1.0	21.6	2.3	41	1.61	108.9	7.1	2.8	41	1.0	9.2	0.5	50	0.07	0.056	20
1287488	Soil		11.6	63.4	21.4	177	0.8	34.6	3.8	73	1.87	103.9	8.7	3.1	42	1.6	9.0	0.5	53	0.11	0.067	19
1287489	Soil		12.0	38.1	26.9	110	1.4	24.4	2.7	37	1.81	145.7	33.2	1.3	35	0.9	9.8	0.9	63	0.06	0.089	12
1287490	Soil		12.5	55.7	72.5	107	3.2	15.2	3.1	51	3.51	618.4	124.0	2.1	60	0.6	29.6	3.8	60	0.04	0.123	20
1286221	Soil		3.5	48.2	19.1	156	0.4	42.7	11.9	336	2.95	19.5	6.6	2.6	59	0.9	2.5	0.3	42	0.41	0.103	7
1286222	Soil		2.5	30.2	14.1	98	0.6	27.3	5.1	106	2.49	15.4	6.3	1.1	22	0.3	1.6	0.3	34	0.07	0.064	4
1286223	Soil		2.7	34.3	11.9	104	0.4	27.5	5.7	84	2.93	21.0	7.0	1.0	20	0.2	2.4	0.2	35	0.02	0.068	3
1286224	Soil		2.7	22.2	7.9	61	0.4	17.0	3.3	42	1.56	8.3	1.6	0.2	9	0.4	1.1	0.2	35	0.01	0.053	3
1286225	Soil		2.1	27.0	9.0	78	0.4	17.1	4.0	77	1.76	10.2	1.1	0.2	13	0.9	1.1	0.2	30	0.02	0.065	3
1286226	Soil		5.3	50.6	16.0	188	0.4	63.4	11.9	201	3.82	16.4	3.0	0.6	35	0.5	1.6	0.2	28	0.31	0.083	3
1286227	Soil		2.3	38.5	17.1	165	1.3	60.3	13.6	361	2.86	14.5	3.0	1.5	78	0.8	1.4	0.2	44	0.92	0.124	12
1286228	Soil		2.9	21.4	14.2	94	0.1	23.9	6.6	304	2.62	17.3	2.0	1.5	46	0.5	2.0	0.3	51	0.76	0.065	9
1286229	Soil		1.2	22.6	9.2	122	0.9	30.8	5.2	190	1.73	9.1	1.5	0.4	110	1.5	1.3	0.2	38	2.83	0.148	11
1286230	Soil		1.9	27.5	9.5	137	1.1	41.6	6.1	226	1.77	8.8	4.2	0.3	158	1.3	1.3	0.2	41	3.17	0.171	11
1286871	Soil		2.5	42.8	12.6	86	0.9	25.0	3.5	169	1.94	8.1	4.5	0.7	33	0.6	1.2	0.2	55	0.31	0.107	4
1286872	Soil		2.7	40.5	7.8	97	0.9	25.6	4.5	69	2.16	7.0	<0.5	<0.1	11	0.3	0.8	0.1	39	0.02	0.051	4
1286873	Soil		1.8	17.9	6.6	35	0.6	7.9	1.7	43	0.92	3.3	<0.5	0.1	12	0.7	0.5	0.1	28	0.07	0.076	4
1286874	Soil		1.1	24.9	5.2	25	1.0	13.9	3.7	283	0.99	3.3	1.4	0.3	62	0.4	0.6	0.1	23	0.88	0.085	3
1286875	Soil		1.2	31.8	10.1	112	0.9	34.8	5.0	142	1.82	6.5	2.4	0.7	103	0.7	0.8	0.2	24	1.49	0.080	3
1286876	Soil		0.9	23.5	5.7	36	0.8	19.6	6.1	198	1.07	5.5	2.5	0.2	56	0.6	0.9	<0.1	18	1.00	0.064	3
1286877	Soil		2.0	67.4	7.6	96	1.2	37.7	10.3	157	1.34	4.8	4.2	0.4	32	1.1	1.0	0.1	33	0.47	0.078	5
1286878	Soil		2.3	60.0	7.4	142	1.1	34.6	4.6	164	1.41	6.4	1.9	0.5	42	1.0	1.3	0.3	39	0.94	0.094	5
1286879	Soil		2.5	37.7	12.1	134	1.1	26.7	5.2	255	1.64	9.2	4.8	0.6	58	0.9	2.1	0.2	50	1.52	0.098	5
1286880	Soil		1.6	68.9	9.2	98	1.2	44.0	5.2	233	1.44	6.3	3.4	0.5	64	1.1	1.3	0.2	35	1.66	0.081	6
1288731	Soil		19.2	146.3	20.8	515	1.1	171.3	57.4	871	2.02	67.3	8.8	1.6	61	5.8	14.7	0.2	100	0.16	0.102	11
1288732	Soil		15.4	86.0	26.6	573	1.3	93.3	13.2	303	2.83	77.6	9.2	3.0	81	5.3	13.7	0.3	84	0.57	0.106	10
1288733	Soil		9.6	73.0	20.1	454	1.2	75.6	11.1	239	2.86	67.6	6.1	2.5	63	3.7	9.5	0.3	71	0.26	0.082	8
1288734	Soil		8.7	83.3	18.2	389	1.3	74.5	14.8	266	3.26	238.4	6.7	2.3	56	3.7	10.5	0.3	64	0.27	0.092	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287485	Soil		8	0.02	219	<0.001	1	0.26	0.002	0.04	0.2	0.27	1.6	0.5	<0.05	<1	5.7	<0.2
1287486	Soil		9	0.04	308	<0.001	<1	0.39	0.003	0.05	0.5	0.83	2.2	0.7	<0.05	1	3.8	<0.2
1287487	Soil		10	0.07	324	<0.001	1	0.44	0.003	0.05	0.9	0.98	1.7	0.5	<0.05	1	3.5	<0.2
1287488	Soil		13	0.10	357	<0.001	<1	0.50	0.003	0.05	0.4	0.86	1.7	0.4	<0.05	2	2.7	<0.2
1287489	Soil		12	0.05	406	<0.001	1	0.49	0.004	0.06	0.5	2.66	1.2	0.8	<0.05	2	2.9	<0.2
1287490	Soil		16	0.08	266	0.002	2	0.61	0.008	0.11	2.0	12.06	1.1	2.2	0.19	2	8.0	<0.2
1286221	Soil		21	0.29	1841	0.009	4	0.91	0.008	0.09	0.1	0.50	3.2	0.1	0.07	2	1.8	0.2
1286222	Soil		16	0.15	428	0.003	4	0.71	0.009	0.07	<0.1	0.18	2.0	0.1	0.06	3	1.3	<0.2
1286223	Soil		15	0.06	116	0.002	1	0.45	0.004	0.04	<0.1	0.05	1.8	<0.1	<0.05	2	2.3	<0.2
1286224	Soil		9	0.02	112	0.002	1	0.42	0.010	0.03	<0.1	0.04	0.6	<0.1	<0.05	2	0.9	<0.2
1286225	Soil		10	0.02	126	0.003	<1	0.41	0.011	0.05	<0.1	0.03	0.5	<0.1	<0.05	2	1.5	<0.2
1286226	Soil		19	0.11	239	0.004	2	0.72	0.008	0.07	<0.1	0.08	2.8	0.1	<0.05	2	2.0	<0.2
1286227	Soil		26	0.24	714	0.003	5	1.01	0.007	0.11	<0.1	0.13	2.9	0.1	0.05	3	2.0	<0.2
1286228	Soil		20	0.27	523	0.009	3	0.90	0.006	0.09	0.3	0.09	1.9	0.1	<0.05	4	1.6	0.2
1286229	Soil		21	0.13	459	0.002	5	0.65	0.007	0.04	<0.1	0.13	1.2	<0.1	0.13	1	2.3	<0.2
1286230	Soil		22	0.11	582	0.002	6	0.79	0.007	0.06	<0.1	0.16	1.0	0.1	0.18	1	2.7	<0.2
1286871	Soil		19	0.16	660	0.004	3	1.10	0.014	0.09	0.1	0.17	2.1	0.3	<0.05	4	1.5	<0.2
1286872	Soil		9	0.03	96	0.004	<1	0.48	0.010	0.03	<0.1	0.03	0.8	0.1	<0.05	3	0.8	<0.2
1286873	Soil		8	0.03	284	0.002	1	0.46	0.011	0.03	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2
1286874	Soil		7	0.10	401	0.008	2	0.79	0.027	0.04	<0.1	0.13	0.8	0.1	0.05	2	2.6	<0.2
1286875	Soil		15	0.19	426	0.002	4	0.86	0.009	0.05	<0.1	0.27	2.2	0.1	0.11	2	3.6	<0.2
1286876	Soil		7	0.10	187	0.007	2	0.61	0.022	0.04	<0.1	0.12	0.9	<0.1	0.07	2	1.7	<0.2
1286877	Soil		11	0.13	293	0.005	2	0.86	0.016	0.04	<0.1	0.20	2.0	0.1	<0.05	3	2.2	<0.2
1286878	Soil		13	0.13	423	0.004	2	0.95	0.013	0.05	0.1	0.25	1.7	0.2	0.08	3	2.5	<0.2
1286879	Soil		14	0.12	570	0.004	2	0.93	0.015	0.06	<0.1	0.28	1.8	0.2	0.07	3	2.7	<0.2
1286880	Soil		12	0.14	379	0.003	3	0.78	0.012	0.05	<0.1	0.32	2.0	0.2	0.09	2	2.6	<0.2
1288731	Soil		24	0.08	610	0.002	3	0.78	0.006	0.09	3.0	3.25	3.7	1.0	<0.05	2	4.4	<0.2
1288732	Soil		26	0.17	900	0.001	3	0.79	0.005	0.11	1.3	1.78	3.5	0.7	0.07	2	4.1	<0.2
1288733	Soil		29	0.20	1191	0.001	5	0.97	0.006	0.12	0.7	1.62	3.5	0.4	<0.05	3	3.3	<0.2
1288734	Soil		23	0.17	1028	0.001	9	0.98	0.007	0.09	0.6	1.85	3.1	0.5	<0.05	2	4.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288735	Soil		8.2	106.3	17.2	646	1.3	148.5	26.2	815	3.46	397.0	3.9	2.4	62	13.2	10.5	0.3	62	0.28	0.090	11
1288736	Soil		9.4	109.9	18.2	674	1.3	146.1	24.4	936	2.71	192.2	11.7	2.0	72	12.3	11.1	0.3	78	0.44	0.102	10
1288737	Soil		10.1	76.1	19.9	460	1.2	85.5	14.1	447	3.23	170.1	8.5	2.4	56	5.2	10.1	0.3	71	0.27	0.084	10
1288738	Soil		15.8	54.2	18.6	1527	1.0	165.8	53.0	937	10.11	516.7	6.4	2.9	53	3.1	17.8	0.3	77	0.24	0.081	8
1288739	Soil		15.6	73.9	19.3	2130	1.2	267.2	119.9	2800	9.78	165.1	12.5	2.7	57	28.5	12.5	0.4	93	0.29	0.090	9
1288740	Soil		20.7	127.7	22.8	1875	1.3	232.4	93.5	510	6.46	146.9	7.1	3.4	78	26.6	14.7	0.5	91	0.41	0.103	11
1289351	Soil		2.5	110.0	19.9	265	1.1	75.1	12.9	484	3.25	15.1	5.3	0.9	127	2.8	1.6	0.2	30	1.49	0.135	6
1289352	Soil		1.2	14.0	6.5	52	0.4	9.3	2.3	68	1.02	3.8	1.1	0.3	91	0.7	0.5	0.1	20	0.78	0.049	3
1289353	Soil		2.4	15.4	6.9	77	0.4	12.0	5.0	215	1.21	5.3	<0.5	0.5	134	2.8	0.6	0.1	25	1.09	0.054	3
1289354	Soil		3.4	19.6	12.7	78	0.2	14.3	4.0	195	2.17	9.0	3.5	2.1	10	0.2	1.2	0.2	45	0.05	0.031	11
1289355	Soil		3.1	15.2	4.0	34	0.4	7.0	1.8	85	0.81	3.9	<0.5	0.2	10	0.2	0.9	0.1	29	0.03	0.024	6
1289356	Soil		2.7	8.8	8.5	30	<0.1	8.0	1.6	52	1.14	7.4	<0.5	0.3	10	0.1	0.7	0.1	32	0.03	0.027	5
1289357	Soil		1.2	17.5	9.9	53	<0.1	12.0	3.8	220	2.34	5.8	1.8	0.6	6	0.2	0.4	0.5	38	0.03	0.076	2
1289358	Soil		2.7	8.9	9.5	43	0.2	9.5	2.1	52	1.55	10.1	2.6	0.6	8	0.2	1.2	0.3	52	0.02	0.034	7
1289359	Soil		3.6	12.0	12.5	53	0.2	11.8	2.9	104	1.78	10.4	1.4	0.6	9	0.3	1.0	0.2	59	0.02	0.042	8
1289360	Soil		4.4	15.6	11.9	89	0.5	19.1	3.4	106	1.54	13.0	3.6	0.5	11	0.4	1.8	0.2	44	0.03	0.053	5
1287491	Soil		15.2	64.7	90.6	126	3.1	18.3	3.3	57	4.09	746.8	165.4	1.7	80	0.9	49.1	4.2	60	0.05	0.157	22
1287492	Soil		16.4	56.1	90.8	143	3.1	19.8	6.4	199	4.01	821.6	153.3	4.9	104	0.8	44.5	3.8	74	0.05	0.168	27
1287493	Soil		14.9	57.2	71.4	130	2.7	22.3	4.1	89	3.73	581.7	106.0	2.6	75	0.8	39.6	3.1	64	0.08	0.155	19
1287494	Soil		6.2	46.1	22.9	127	1.4	29.7	4.8	76	2.22	115.2	22.2	1.8	38	1.0	18.9	0.5	31	0.09	0.070	8
1287495	Soil		6.1	50.5	27.9	133	1.6	29.8	5.1	106	2.43	119.0	24.8	1.8	42	0.7	20.8	0.6	32	0.14	0.076	9
1287496	Soil		5.4	49.7	18.5	166	0.9	39.3	9.9	438	2.33	56.1	8.8	2.4	46	1.0	4.8	0.4	52	0.37	0.077	8
1287497	Soil		3.1	37.2	17.8	124	0.5	33.9	8.2	249	2.89	16.8	4.5	1.7	32	0.4	1.7	0.3	45	0.21	0.074	6
1287498	Soil		1.4	20.8	9.6	93	0.5	25.9	5.9	204	1.81	9.6	2.8	0.8	48	0.3	0.7	0.3	26	0.65	0.057	3
1287499	Soil		1.7	24.7	11.6	67	0.6	20.6	4.4	85	1.77	8.5	4.6	0.8	24	0.3	0.7	0.3	29	0.18	0.120	4
1287500	Soil		1.7	29.6	15.0	117	0.6	31.6	6.1	316	2.50	14.0	3.3	1.0	41	0.5	0.8	0.3	35	0.33	0.126	5
1289381	Soil		5.9	43.4	14.7	163	0.9	43.0	7.8	269	2.38	18.3	5.8	2.0	37	0.9	2.0	0.2	46	0.30	0.088	7
1289382	Soil		1.0	24.9	6.6	53	0.8	16.0	4.2	163	1.14	5.8	2.5	0.4	33	0.8	0.7	0.2	22	0.77	0.064	3
1289383	Soil		7.7	55.1	12.8	257	3.9	69.5	9.6	330	2.96	16.0	4.8	1.9	61	1.3	1.7	0.2	32	0.79	0.098	5
1289384	Soil		2.0	38.9	13.0	117	0.8	37.0	6.5	241	2.14	12.3	6.7	1.3	38	0.7	1.3	0.2	30	0.58	0.077	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288735	Soil		27	0.17	987	0.002	3	1.07	0.005	0.09	4.2	2.04	3.5	0.5	<0.05	2	3.1	<0.2
1288736	Soil		24	0.15	853	0.002	2	0.93	0.005	0.08	1.2	1.95	3.5	0.5	0.07	2	5.0	<0.2
1288737	Soil		21	0.16	794	0.002	2	0.97	0.007	0.08	0.8	1.74	3.4	0.4	<0.05	2	3.9	<0.2
1288738	Soil		19	0.15	920	0.001	2	0.68	0.004	0.08	0.4	1.50	3.5	0.6	<0.05	2	3.2	<0.2
1288739	Soil		20	0.13	649	0.002	4	0.97	0.005	0.09	0.6	2.29	3.7	0.8	0.05	2	4.2	<0.2
1288740	Soil		21	0.20	912	0.002	3	1.12	0.004	0.08	0.4	3.26	4.4	1.5	0.12	2	6.7	<0.2
1289351	Soil		21	0.45	480	0.005	3	1.10	0.009	0.05	<0.1	0.31	3.7	0.1	0.10	3	2.4	<0.2
1289352	Soil		11	0.12	371	0.006	<1	0.68	0.018	0.04	<0.1	0.09	0.8	<0.1	0.06	2	0.5	<0.2
1289353	Soil		11	0.15	604	0.010	2	0.58	0.015	0.03	0.2	0.07	1.1	<0.1	0.09	2	1.1	<0.2
1289354	Soil		21	0.14	179	0.006	<1	1.14	0.005	0.04	<0.1	0.05	1.3	0.2	<0.05	4	0.7	<0.2
1289355	Soil		7	0.03	267	0.007	2	0.34	0.013	0.04	0.1	0.03	0.7	<0.1	<0.05	2	<0.5	<0.2
1289356	Soil		11	0.03	56	0.005	<1	0.38	0.010	0.03	0.1	0.03	0.4	<0.1	<0.05	4	<0.5	<0.2
1289357	Soil		15	0.16	74	0.005	3	1.05	0.010	0.03	<0.1	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
1289358	Soil		12	0.05	105	0.009	2	0.61	0.009	0.04	0.1	0.02	0.7	0.1	<0.05	3	0.7	<0.2
1289359	Soil		13	0.06	154	0.004	<1	0.73	0.004	0.03	0.1	0.03	0.6	0.2	<0.05	4	0.9	<0.2
1289360	Soil		15	0.04	132	0.005	4	0.48	0.010	0.05	0.1	0.07	0.8	0.2	<0.05	2	1.3	<0.2
1287491	Soil		19	0.08	361	0.003	4	0.66	0.011	0.14	2.5	17.72	0.8	3.5	0.29	2	10.2	0.3
1287492	Soil		23	0.09	427	0.004	4	0.67	0.009	0.19	3.1	28.67	1.5	3.1	0.27	3	13.5	0.3
1287493	Soil		19	0.08	422	0.002	3	0.68	0.008	0.14	1.4	17.80	1.4	2.6	0.21	3	9.9	0.2
1287494	Soil		22	0.06	513	0.001	3	0.46	0.004	0.08	0.7	8.47	2.0	0.3	<0.05	1	6.2	<0.2
1287495	Soil		18	0.07	547	<0.001	2	0.50	0.004	0.08	0.5	8.95	2.0	0.3	0.08	2	6.1	<0.2
1287496	Soil		24	0.18	971	0.001	3	0.75	0.005	0.07	0.5	1.28	2.6	0.2	<0.05	2	3.1	<0.2
1287497	Soil		23	0.30	475	0.002	2	1.07	0.006	0.07	<0.1	0.28	2.3	0.1	<0.05	3	1.3	<0.2
1287498	Soil		13	0.17	765	0.002	2	0.98	0.021	0.07	<0.1	0.27	2.0	0.1	<0.05	3	1.0	<0.2
1287499	Soil		19	0.11	330	0.004	2	0.98	0.013	0.07	<0.1	0.32	2.4	0.2	<0.05	3	1.2	<0.2
1287500	Soil		21	0.23	514	0.002	2	1.09	0.008	0.08	<0.1	0.18	2.3	0.1	0.06	3	1.0	<0.2
1289381	Soil		23	0.19	721	0.002	3	0.79	0.005	0.09	0.1	0.35	2.3	0.1	<0.05	3	2.1	<0.2
1289382	Soil		9	0.08	377	0.004	2	0.53	0.019	0.04	<0.1	0.22	1.1	<0.1	0.07	2	2.8	<0.2
1289383	Soil		22	0.16	471	<0.001	3	0.73	0.005	0.05	<0.1	0.56	2.9	0.1	0.07	2	5.0	<0.2
1289384	Soil		20	0.13	426	0.003	2	0.72	0.012	0.07	<0.1	0.33	2.6	0.1	0.09	2	2.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1289385	Soil		1.9	47.6	13.5	125	0.8	42.8	7.1	172	2.35	13.0	5.9	1.6	40	0.7	1.5	0.2	29	0.50	0.085	4
1289386	Soil		1.3	51.0	10.7	80	0.7	41.7	4.5	57	1.80	8.8	6.3	0.9	51	0.5	1.2	0.2	23	1.01	0.077	4
1289387	Soil		2.6	40.9	11.8	135	0.7	37.0	6.8	139	2.40	12.6	4.9	1.5	37	0.5	1.7	0.2	30	0.51	0.079	4
1289388	Soil		12.2	21.4	40.5	140	0.5	23.6	4.4	118	2.82	31.8	1.6	3.9	86	1.0	5.6	0.3	108	0.06	0.071	7
1289389	Soil		21.1	40.0	18.2	122	0.8	27.8	2.5	46	1.60	21.8	5.1	1.8	59	1.4	5.3	0.2	100	0.24	0.108	9
1289390	Soil		30.6	38.3	18.4	216	1.1	66.4	7.4	458	2.05	20.2	4.7	2.4	58	3.7	12.0	0.2	217	0.58	0.115	11
1286781	Soil		15.4	39.6	13.9	214	0.3	48.8	7.1	178	2.09	23.3	2.6	2.3	34	1.2	3.7	0.2	71	0.23	0.098	15
1286782	Soil		6.2	22.4	7.4	108	0.5	27.1	3.5	74	1.16	10.3	2.7	0.3	21	0.9	1.7	0.1	44	0.18	0.058	5
1286783	Soil		14.1	47.9	16.0	246	0.3	59.0	9.5	214	2.42	23.2	5.1	2.7	43	1.8	4.4	0.2	84	0.27	0.111	14
1286784	Soil		13.5	48.4	15.0	246	0.4	58.2	9.6	206	2.45	25.3	2.9	2.2	39	1.7	3.9	0.2	72	0.27	0.097	13
1286785	Soil		13.8	42.6	18.1	221	0.3	48.8	10.2	293	2.49	28.1	3.9	1.6	28	1.5	3.7	0.2	82	0.15	0.085	12
1286786	Soil		13.2	47.5	16.7	252	0.5	55.9	10.0	292	2.58	28.8	3.0	2.0	34	1.7	4.0	0.2	83	0.21	0.097	13
1286787	Soil		12.4	43.6	17.7	228	1.2	51.0	8.4	248	2.78	25.7	4.0	2.1	43	1.7	3.5	0.3	99	0.31	0.118	11
1286788	Soil		8.6	35.2	13.1	193	0.9	47.6	8.3	356	1.88	18.3	3.8	1.3	37	1.8	2.7	0.2	55	0.26	0.081	9
1286789	Soil		8.8	35.4	14.9	215	0.4	47.2	10.1	477	2.40	21.4	3.8	2.4	50	2.1	2.9	0.2	63	0.54	0.178	13
1286790	Soil		8.6	54.0	16.2	297	0.9	70.6	15.0	494	2.25	24.1	4.3	2.2	59	5.4	3.5	0.2	63	0.74	0.107	9
1289391	Soil		21.0	19.3	13.3	88	0.2	17.9	3.2	110	1.46	19.8	2.3	1.2	26	0.6	4.6	0.2	114	0.17	0.054	9
1289392	Soil		23.0	51.1	16.0	295	1.0	69.1	8.5	231	2.22	28.2	6.1	2.0	57	1.4	9.4	0.2	172	0.34	0.122	10
1289393	Soil		31.5	55.5	13.9	1530	0.9	195.4	7.3	169	2.36	104.8	3.9	2.5	65	19.8	6.1	0.3	116	0.91	0.207	13
1289394	Soil		173.7	56.2	16.0	2477	0.6	262.6	76.3	2305	5.80	58.1	2.5	1.9	34	12.1	15.6	0.3	126	0.27	0.149	14
1289395	Soil		17.5	28.0	10.7	567	0.8	61.1	5.0	182	1.57	27.9	2.2	0.4	25	5.0	6.4	0.2	168	0.16	0.103	11
1289396	Soil		29.5	20.8	10.5	289	0.7	53.6	2.1	39	1.07	34.9	1.3	0.2	8	0.5	15.4	0.2	463	0.01	0.031	20
1289397	Soil		18.5	24.0	9.9	296	0.4	40.6	3.6	124	1.17	27.1	1.1	0.7	16	4.1	5.1	0.2	424	0.16	0.037	14
1289398	Soil		11.2	25.1	11.3	144	0.4	34.5	4.6	142	1.77	19.0	<0.5	0.8	32	1.7	2.5	0.2	84	0.43	0.064	11
1289399	Soil		15.6	41.4	17.7	282	0.5	68.8	10.1	320	3.04	33.5	3.8	2.4	37	1.9	4.4	0.2	94	0.35	0.145	15
1289400	Soil		28.1	44.2	20.1	227	0.3	62.6	8.0	201	2.80	64.2	4.7	3.3	24	0.7	4.2	0.3	113	0.12	0.111	20
1286771	Soil		10.7	25.4	15.0	169	0.3	28.4	3.8	85	1.97	25.1	3.4	0.6	23	0.9	3.9	0.2	160	0.05	0.083	9
1286772	Soil		12.7	48.5	18.5	223	0.4	42.7	6.8	176	2.67	31.2	4.0	2.2	45	1.3	5.5	0.3	82	0.14	0.116	13
1286773	Soil		9.6	44.7	17.9	242	0.4	50.0	9.4	204	2.74	27.9	4.9	1.6	40	1.5	3.8	0.2	68	0.22	0.093	12
1286774	Soil		10.3	18.7	11.5	131	0.4	21.3	9.6	272	1.76	14.2	1.8	2.4	35	0.6	1.8	0.2	74	0.38	0.103	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1289385	Soil	18	0.13	483	<0.001	1	0.74	0.005	0.06	<0.1	0.30	3.0	0.1	<0.05	2	2.4	<0.2
1289386	Soil	15	0.11	460	0.002	2	0.63	0.012	0.05	<0.1	0.27	2.2	<0.1	0.15	2	4.3	<0.2
1289387	Soil	17	0.13	416	0.002	2	0.67	0.004	0.06	<0.1	0.28	2.7	<0.1	<0.05	2	2.4	<0.2
1289388	Soil	13	0.04	592	0.001	2	0.35	0.005	0.11	0.1	0.44	1.4	0.8	0.22	1	2.4	<0.2
1289389	Soil	19	0.11	1737	0.002	3	0.72	0.003	0.06	0.1	1.00	1.9	0.4	<0.05	2	4.9	<0.2
1289390	Soil	23	0.19	909	0.003	5	0.91	0.006	0.08	0.2	0.80	2.5	0.9	<0.05	3	3.1	<0.2
1286781	Soil	14	0.14	1099	0.003	3	0.64	0.003	0.07	0.1	0.20	1.8	0.2	<0.05	2	1.7	<0.2
1286782	Soil	11	0.09	857	0.003	2	0.57	0.017	0.06	<0.1	0.19	0.8	0.2	<0.05	2	1.6	<0.2
1286783	Soil	23	0.16	1765	0.004	4	0.72	0.005	0.09	0.1	0.31	2.5	0.3	<0.05	2	2.3	<0.2
1286784	Soil	17	0.17	1486	0.004	1	0.75	0.005	0.09	<0.1	0.26	2.5	0.2	<0.05	2	1.7	<0.2
1286785	Soil	18	0.13	867	0.003	2	0.76	0.004	0.08	0.1	0.17	1.7	0.2	<0.05	2	1.4	<0.2
1286786	Soil	18	0.15	1102	0.003	2	0.85	0.004	0.08	0.1	0.24	2.2	0.3	<0.05	3	1.8	<0.2
1286787	Soil	22	0.17	1986	0.002	4	1.08	0.006	0.11	0.1	0.57	3.0	0.4	<0.05	3	1.6	<0.2
1286788	Soil	13	0.11	1502	0.003	4	0.76	0.013	0.06	0.2	0.33	1.9	0.2	<0.05	2	1.6	<0.2
1286789	Soil	15	0.16	1141	0.003	4	0.72	0.008	0.08	0.1	0.24	2.1	0.2	<0.05	2	1.7	<0.2
1286790	Soil	17	0.18	1474	0.002	2	0.86	0.008	0.06	0.2	0.44	3.1	0.2	0.09	2	3.6	<0.2
1289391	Soil	14	0.07	353	0.003	2	0.45	0.007	0.05	0.2	0.12	0.9	0.4	<0.05	3	1.5	<0.2
1289392	Soil	25	0.15	1068	0.003	3	0.85	0.009	0.10	0.3	0.62	2.3	1.1	<0.05	3	3.2	<0.2
1289393	Soil	19	0.17	929	0.003	8	0.60	0.004	0.08	0.2	0.48	3.4	0.6	0.07	2	3.9	<0.2
1289394	Soil	16	0.07	908	0.003	4	0.54	0.003	0.06	0.2	1.12	3.2	0.9	<0.05	2	3.2	<0.2
1289395	Soil	20	0.09	330	0.006	4	0.53	0.010	0.06	0.2	0.18	0.8	0.7	<0.05	3	2.9	<0.2
1289396	Soil	19	0.03	120	0.010	6	0.37	0.003	0.07	0.2	0.05	0.3	0.4	<0.05	4	8.9	<0.2
1289397	Soil	24	0.10	389	0.003	2	0.78	0.007	0.07	0.2	0.14	0.6	0.7	<0.05	3	3.4	<0.2
1289398	Soil	14	0.11	1108	0.003	<1	0.82	0.004	0.05	0.1	0.10	1.1	0.3	<0.05	3	1.2	<0.2
1289399	Soil	21	0.13	1130	0.003	2	0.92	0.004	0.09	0.2	0.25	2.8	0.4	<0.05	2	1.7	<0.2
1289400	Soil	20	0.11	437	0.002	4	1.02	0.004	0.07	0.2	0.25	2.2	0.6	<0.05	3	2.3	<0.2
1286771	Soil	18	0.10	324	0.005	3	0.57	0.006	0.06	0.1	0.10	1.0	0.3	<0.05	2	2.5	0.2
1286772	Soil	20	0.16	807	0.006	2	0.70	0.003	0.07	0.1	0.41	2.4	0.3	<0.05	2	2.8	<0.2
1286773	Soil	17	0.14	942	0.002	3	0.79	0.004	0.06	0.1	0.23	2.1	0.3	<0.05	2	2.8	<0.2
1286774	Soil	14	0.12	676	0.002	4	0.70	0.008	0.06	<0.1	0.24	2.1	0.2	<0.05	2	1.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286775	Soil	9.1	32.0	13.0	161	0.5	28.7	5.6	131	1.63	15.7	2.0	2.6	40	1.2	2.3	0.2	76	0.40	0.113	12
1286776	Soil	14.0	43.0	14.7	169	0.6	38.9	7.5	156	2.18	20.6	1.2	3.1	43	1.9	3.1	0.2	78	0.44	0.135	13
1286777	Soil	21.1	53.5	16.0	434	1.3	67.3	7.7	216	1.87	30.3	3.5	1.8	69	3.6	7.0	0.2	265	0.70	0.116	14
1286778	Soil	10.5	23.5	8.4	153	0.3	33.3	3.4	57	1.15	17.3	1.1	0.2	20	2.1	2.4	0.1	56	0.24	0.050	10
1286779	Soil	36.6	33.7	13.6	337	0.2	86.4	7.7	154	2.11	28.9	1.0	1.3	19	1.3	4.3	0.2	109	0.07	0.052	14
1286780	Soil	9.6	13.0	7.4	83	0.2	17.8	3.0	48	1.25	12.8	<0.5	0.6	9	0.5	2.3	0.1	55	0.03	0.036	6
1286241	Soil	1.7	41.7	22.7	80	0.9	21.6	4.5	176	3.17	30.4	5.4	2.2	80	0.2	0.9	0.3	28	0.28	0.074	3
1286242	Soil	2.7	28.6	19.5	116	0.3	33.2	7.5	257	3.17	19.4	1.8	2.1	51	0.4	1.0	0.2	30	0.21	0.080	4
1286243	Soil	1.8	22.8	16.6	94	0.3	27.0	6.2	226	2.62	13.5	1.6	1.3	43	0.3	0.6	0.2	27	0.19	0.084	4
1286244	Soil	1.0	13.8	10.2	48	0.3	15.4	3.4	103	1.62	6.2	0.7	0.6	20	<0.1	0.3	0.1	20	0.04	0.065	2
1286245	Soil	1.6	27.9	16.8	98	0.5	32.3	6.3	373	2.71	14.6	2.6	1.3	52	0.2	0.6	0.2	32	0.25	0.112	6
1286246	Soil	1.5	12.7	10.8	50	0.3	14.5	3.1	106	1.72	8.4	<0.5	0.4	19	0.1	0.6	0.1	26	0.10	0.057	2
1286247	Soil	3.1	24.5	15.8	118	0.4	31.6	7.6	260	3.09	14.7	1.6	1.3	55	0.3	0.9	0.2	35	0.47	0.102	5
1286248	Soil	3.0	38.4	8.7	86	0.8	33.0	5.9	446	2.05	16.2	4.8	0.9	63	2.0	3.3	0.1	74	1.29	0.096	7
1286249	Soil	4.8	44.3	12.0	171	1.3	35.4	9.4	1340	2.18	15.2	6.2	2.0	72	1.9	3.6	0.2	100	0.87	0.126	10
1286250	Soil	4.4	78.0	15.1	204	0.7	43.3	13.0	361	2.80	18.0	7.6	2.5	74	0.9	2.2	0.2	49	0.54	0.116	8
1287631	Soil	8.1	36.7	18.7	266	0.4	49.7	10.3	227	3.12	24.1	0.7	2.3	50	1.4	4.4	0.2	51	0.23	0.104	10
1287632	Soil	2.9	15.5	7.5	112	0.6	25.0	4.1	79	1.03	6.9	1.0	0.1	21	0.9	1.3	<0.1	24	0.13	0.044	2
1287633	Soil	11.6	33.9	20.0	413	0.8	63.6	7.9	298	2.71	32.4	1.3	1.8	51	2.5	3.9	0.2	67	0.38	0.124	10
1287634	Soil	11.6	39.2	22.9	570	0.4	66.7	11.1	285	3.20	28.1	2.9	1.5	30	2.1	3.4	0.2	85	0.22	0.106	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

CERTIFICATE OF ANALYSIS WHI11001883.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286775	Soil		14	0.13	911	0.002	2	0.76	0.006	0.07	0.1	0.29	2.7	0.3	<0.05	2	1.8	<0.2
1286776	Soil		13	0.13	919	0.002	4	0.67	0.004	0.07	0.1	0.32	3.2	0.3	<0.05	2	1.9	<0.2
1286777	Soil		23	0.18	972	0.004	4	0.77	0.010	0.09	0.2	0.53	2.7	0.7	<0.05	2	2.9	<0.2
1286778	Soil		9	0.06	599	0.003	3	0.48	0.015	0.06	<0.1	0.14	0.4	0.3	<0.05	2	0.6	<0.2
1286779	Soil		19	0.07	409	0.006	4	0.95	0.005	0.06	0.2	0.15	1.7	1.0	<0.05	3	2.3	<0.2
1286780	Soil		8	0.04	313	0.004	3	0.52	0.011	0.04	<0.1	0.05	0.7	0.2	<0.05	2	0.8	<0.2
1286241	Soil		25	0.24	538	0.003	6	0.90	0.009	0.11	<0.1	0.20	3.3	0.1	0.10	3	2.0	0.2
1286242	Soil		22	0.32	480	0.001	<1	1.08	0.007	0.08	<0.1	0.14	3.4	0.1	0.07	3	1.3	<0.2
1286243	Soil		19	0.22	389	0.002	2	1.05	0.013	0.07	<0.1	0.08	2.4	0.1	0.06	3	0.8	<0.2
1286244	Soil		14	0.16	193	0.002	2	0.80	0.018	0.05	<0.1	0.06	1.3	0.1	<0.05	3	0.6	<0.2
1286245	Soil		22	0.21	550	0.003	<1	1.25	0.010	0.09	<0.1	0.16	3.3	0.2	0.06	4	1.4	<0.2
1286246	Soil		13	0.06	113	0.003	<1	0.54	0.013	0.05	<0.1	0.05	0.9	<0.1	<0.05	3	1.2	<0.2
1286247	Soil		21	0.26	394	0.003	3	1.00	0.007	0.07	<0.1	0.07	2.4	<0.1	0.05	3	2.1	<0.2
1286248	Soil		14	0.11	1062	0.005	3	0.62	0.016	0.06	0.2	0.41	1.5	0.1	0.08	2	4.4	<0.2
1286249	Soil		21	0.19	2056	0.004	5	0.98	0.009	0.11	0.2	0.80	2.7	0.3	0.06	3	3.2	<0.2
1286250	Soil		26	0.41	2169	0.004	3	1.16	0.007	0.07	0.1	0.26	3.4	0.3	<0.05	3	1.5	<0.2
1287631	Soil		20	0.22	2206	0.007	3	0.78	0.006	0.07	<0.1	0.13	2.8	0.2	0.05	2	2.5	<0.2
1287632	Soil		7	0.07	954	0.003	<1	0.50	0.026	0.06	<0.1	0.12	0.4	0.2	0.05	2	1.2	<0.2
1287633	Soil		20	0.19	781	0.006	2	0.87	0.010	0.08	0.2	0.25	2.2	0.3	<0.05	3	2.4	<0.2
1287634	Soil		23	0.17	675	0.004	2	1.22	0.009	0.08	0.1	0.25	3.0	0.5	<0.05	3	2.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

QUALITY CONTROL REPORT WHI11001883.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1286792	Soil	15.4	68.1	20.1	1075	0.9	148.7	10.6	113	2.26	40.9	3.3	4.4	58	8.6	4.8	0.2	120	0.83	0.188	14
REP 1286792	QC	14.7	66.8	20.2	1061	0.9	142.1	10.1	114	2.25	40.2	3.4	4.6	59	7.3	4.9	0.2	128	0.83	0.186	16
1284322	Soil	3.2	28.2	10.9	115	0.7	23.7	6.2	230	2.14	13.6	2.7	1.3	34	1.5	1.7	0.1	50	0.44	0.084	6
REP 1284322	QC	3.0	27.5	10.6	105	0.7	22.0	6.4	219	2.06	13.8	3.6	1.3	34	1.4	1.6	0.1	49	0.43	0.086	6
1289223	Soil	13.9	44.2	18.8	57	1.7	12.3	1.1	47	0.87	15.0	5.7	1.8	98	1.5	3.6	0.2	136	0.51	0.296	14
REP 1289223	QC	14.1	44.9	18.6	57	1.7	12.7	1.1	48	0.88	15.2	6.5	1.8	97	1.5	3.6	0.2	140	0.50	0.304	14
1289379	Soil	2.9	48.9	12.0	157	0.7	38.7	7.3	276	2.13	13.0	5.9	1.6	57	1.5	2.1	0.2	50	1.16	0.108	7
REP 1289379	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286882	Soil	2.3	41.4	13.6	148	0.7	39.0	7.6	141	2.46	13.3	5.3	1.5	38	0.6	1.6	0.2	26	0.54	0.096	4
REP 1286882	QC	2.5	42.6	14.4	159	0.7	41.4	8.0	150	2.61	14.2	5.3	1.5	41	0.5	1.6	0.2	25	0.61	0.107	4
1286211	Soil	2.0	40.8	9.0	89	1.3	27.9	5.3	185	1.34	8.1	4.2	0.5	50	1.2	1.1	0.2	24	0.72	0.063	5
REP 1286211	QC	2.1	39.6	8.9	83	1.3	27.5	5.0	174	1.33	6.6	5.1	0.4	47	1.1	1.0	0.2	23	0.71	0.057	5
1283199	Soil	51.2	69.3	9.5	962	1.4	172.9	7.5	92	2.23	467.6	2.1	2.8	75	10.5	13.6	0.2	447	0.29	0.119	18
REP 1283199	QC	51.0	66.8	8.8	973	1.3	174.3	7.4	89	2.23	466.2	0.7	2.8	75	10.6	13.6	0.2	434	0.29	0.114	17
1288054	Soil	1.7	17.0	8.8	47	0.1	13.1	7.8	776	1.48	3.8	2.0	0.3	13	0.3	0.8	0.2	27	0.04	0.112	4
REP 1288054	QC	1.9	17.0	8.7	52	0.1	14.0	7.6	747	1.46	3.4	1.4	0.3	15	0.3	0.8	0.2	28	0.05	0.111	4
1288633	Soil	10.6	35.6	18.9	202	0.4	38.5	6.1	150	2.69	28.7	4.4	2.7	30	0.6	4.0	0.2	108	0.06	0.087	11
REP 1288633	QC	10.4	34.9	19.0	207	0.4	37.9	5.8	154	2.65	28.2	3.1	2.7	30	0.6	3.9	0.3	107	0.07	0.088	11
1287197	Soil	1.8	39.0	11.1	120	0.4	20.3	5.9	155	1.76	8.1	7.6	0.9	62	1.0	0.8	0.2	34	0.77	0.059	5
REP 1287197	QC	1.7	38.7	11.1	123	0.4	20.2	6.1	158	1.78	7.9	7.5	0.9	63	0.9	0.9	0.2	37	0.75	0.063	5
1287942	Soil	77.9	36.8	8.4	4266	0.5	457.2	23.6	262	7.88	74.1	0.8	3.0	23	27.7	13.8	0.1	101	0.61	0.046	13
REP 1287942	QC	76.5	37.0	8.3	4365	0.5	467.5	23.5	263	7.78	73.7	1.0	3.0	23	27.0	14.6	0.1	91	0.63	0.045	13
1287486	Soil	15.8	73.7	24.9	143	1.1	26.4	2.8	77	2.22	152.7	10.2	3.2	55	1.8	15.5	0.3	62	0.06	0.070	20
REP 1287486	QC	15.8	73.3	24.6	143	1.1	28.1	2.9	78	2.25	153.2	9.2	2.9	55	1.8	16.4	0.3	62	0.07	0.070	20
1286228	Soil	2.9	21.4	14.2	94	0.1	23.9	6.6	304	2.62	17.3	2.0	1.5	46	0.5	2.0	0.3	51	0.76	0.065	9
REP 1286228	QC	2.6	20.7	13.9	90	0.2	24.0	6.2	294	2.54	17.0	<0.5	1.3	42	0.5	1.9	0.2	48	0.73	0.064	8
1288735	Soil	8.2	106.3	17.2	646	1.3	148.5	26.2	815	3.46	397.0	3.9	2.4	62	13.2	10.5	0.3	62	0.28	0.090	11
REP 1288735	QC	7.4	107.3	17.2	627	1.4	144.7	25.3	817	3.45	387.2	7.2	2.5	59	13.0	11.2	0.3	61	0.28	0.094	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

QUALITY CONTROL REPORT WHI11001883.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1286792	Soil	20	0.16	902	0.002	5	0.61	0.005	0.09	<0.1	0.88	4.1	0.6	<0.05	2	3.0	<0.2
REP 1286792	QC	21	0.16	955	0.003	7	0.64	0.005	0.10	<0.1	0.91	4.1	0.6	<0.05	2	3.2	<0.2
1284322	Soil	11	0.13	752	0.004	2	0.73	0.018	0.06	<0.1	0.31	1.8	0.2	0.06	2	2.3	<0.2
REP 1284322	QC	12	0.13	738	0.004	2	0.72	0.018	0.06	0.1	0.31	1.9	0.1	0.06	2	2.5	<0.2
1289223	Soil	17	0.02	394	0.003	5	0.26	0.003	0.14	0.3	0.69	1.1	0.7	0.06	<1	1.5	<0.2
REP 1289223	QC	18	0.02	402	0.004	5	0.27	0.003	0.15	0.3	0.68	1.1	0.7	0.09	<1	1.5	<0.2
1289379	Soil	17	0.21	947	0.003	5	0.84	0.007	0.08	0.1	0.32	2.7	0.2	<0.05	2	2.8	<0.2
REP 1289379	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286882	Soil	17	0.13	379	0.002	3	0.62	0.004	0.07	<0.1	0.16	3.0	0.1	0.05	2	2.0	<0.2
REP 1286882	QC	18	0.13	372	0.001	3	0.66	0.004	0.06	<0.1	0.17	3.1	0.1	0.10	2	2.3	<0.2
1286211	Soil	14	0.13	1899	0.007	3	0.67	0.021	0.05	<0.1	0.19	2.1	0.1	0.22	2	0.9	<0.2
REP 1286211	QC	13	0.12	1710	0.005	4	0.61	0.018	0.04	<0.1	0.18	1.7	<0.1	0.10	2	1.6	<0.2
1283199	Soil	26	0.12	617	0.002	8	1.03	0.001	0.10	0.3	0.56	2.4	1.7	<0.05	1	6.9	<0.2
REP 1283199	QC	24	0.11	619	0.002	6	0.96	<0.001	0.09	0.2	0.54	2.4	1.6	<0.05	1	7.2	<0.2
1288054	Soil	8	0.03	138	0.005	1	0.53	0.014	0.05	<0.1	0.06	0.9	<0.1	0.07	2	<0.5	<0.2
REP 1288054	QC	8	0.04	154	0.009	4	0.58	0.015	0.06	<0.1	0.05	0.9	0.1	<0.05	3	0.8	<0.2
1288633	Soil	22	0.14	508	0.007	4	1.06	0.004	0.07	0.1	0.18	2.1	0.4	<0.05	3	2.0	<0.2
REP 1288633	QC	22	0.14	502	0.003	3	1.09	0.004	0.08	0.1	0.14	1.9	0.4	<0.05	4	1.5	<0.2
1287197	Soil	26	0.27	780	0.007	6	0.85	0.012	0.07	<0.1	0.17	2.3	0.1	0.09	2	1.0	<0.2
REP 1287197	QC	26	0.27	803	0.007	4	0.89	0.013	0.07	<0.1	0.14	2.2	0.1	0.11	3	1.5	<0.2
1287942	Soil	16	0.30	354	0.001	5	0.37	0.002	0.06	0.4	0.96	3.7	3.6	0.08	<1	15.9	<0.2
REP 1287942	QC	15	0.28	348	0.001	3	0.33	0.002	0.06	0.5	0.91	3.7	3.7	0.06	<1	15.5	<0.2
1287486	Soil	9	0.04	308	<0.001	<1	0.39	0.003	0.05	0.5	0.83	2.2	0.7	<0.05	1	3.8	<0.2
REP 1287486	QC	10	0.04	309	<0.001	2	0.38	0.003	0.05	0.5	0.75	2.2	0.7	<0.05	1	4.6	<0.2
1286228	Soil	20	0.27	523	0.009	3	0.90	0.006	0.09	0.3	0.09	1.9	0.1	<0.05	4	1.6	0.2
REP 1286228	QC	19	0.26	492	0.008	2	0.82	0.006	0.09	0.3	0.04	1.9	0.1	<0.05	3	2.1	<0.2
1288735	Soil	27	0.17	987	0.002	3	1.07	0.005	0.09	4.2	2.04	3.5	0.5	<0.05	2	3.1	<0.2
REP 1288735	QC	26	0.16	957	0.001	3	0.99	0.005	0.08	4.2	2.04	3.7	0.5	<0.05	2	3.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

QUALITY CONTROL REPORT WHI11001883.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
1289357	Soil	1.2	17.5	9.9	53	<0.1	12.0	3.8	220	2.34	5.8	1.8	0.6	6	0.2	0.4	0.5	38	0.03	0.076	2
REP 1289357	QC	1.3	17.0	9.7	53	<0.1	11.3	3.9	222	2.37	6.6	1.6	0.5	6	0.2	0.6	0.4	37	0.02	0.076	2
1289387	Soil	2.6	40.9	11.8	135	0.7	37.0	6.8	139	2.40	12.6	4.9	1.5	37	0.5	1.7	0.2	30	0.51	0.079	4
REP 1289387	QC	2.5	41.9	12.5	140	0.7	37.8	6.8	137	2.45	12.8	5.5	1.5	37	0.6	1.6	0.2	30	0.54	0.080	5
1289397	Soil	18.5	24.0	9.9	296	0.4	40.6	3.6	124	1.17	27.1	1.1	0.7	16	4.1	5.1	0.2	424	0.16	0.037	14
REP 1289397	QC	18.0	23.7	9.9	291	0.5	39.3	3.6	122	1.18	27.1	0.7	0.7	16	3.8	5.1	0.2	421	0.17	0.038	13
1286241	Soil	1.7	41.7	22.7	80	0.9	21.6	4.5	176	3.17	30.4	5.4	2.2	80	0.2	0.9	0.3	28	0.28	0.074	3
REP 1286241	QC	1.6	41.5	23.0	79	0.9	23.5	4.6	176	3.16	30.3	6.6	2.3	80	<0.1	1.0	0.3	28	0.25	0.075	3
Reference Materials																					
STD DS8	Standard	13.3	105.8	127.1	305	1.9	35.9	7.3	598	2.47	26.4	109.0	6.8	69	2.3	5.7	6.7	41	0.64	0.076	15
STD DS8	Standard	13.1	107.6	135.8	300	1.8	35.0	6.9	595	2.35	25.0	113.9	7.8	66	2.4	4.6	5.1	39	0.69	0.074	16
STD DS8	Standard	12.8	107.5	121.1	290	1.7	35.9	7.2	583	2.32	25.2	101.1	6.9	61	2.1	5.1	5.8	41	0.65	0.074	15
STD DS8	Standard	12.4	102.9	120.6	294	1.7	36.0	7.3	594	2.39	24.7	140.8	6.2	78	2.0	5.7	6.4	42	0.67	0.073	14
STD DS8	Standard	13.4	108.4	128.7	303	1.8	37.6	7.2	601	2.37	26.1	116.2	6.8	69	2.5	5.7	6.4	42	0.66	0.073	15
STD DS8	Standard	13.4	102.2	120.0	290	1.6	35.1	7.1	567	2.31	25.2	119.1	6.7	72	2.2	5.7	5.9	39	0.65	0.073	17
STD DS8	Standard	13.6	102.2	124.5	303	1.6	37.3	7.5	602	2.37	25.6	107.8	7.1	73	2.3	5.7	5.8	43	0.70	0.078	17
STD DS8	Standard	12.5	106.8	126.2	295	1.7	36.1	7.5	566	2.29	25.7	114.7	6.5	71	2.2	5.2	6.2	39	0.65	0.076	15
STD DS8	Standard	11.7	104.2	118.0	296	1.8	36.8	7.1	599	2.36	25.0	117.2	6.3	61	2.2	5.2	5.9	42	0.62	0.075	15
STD DS8	Standard	13.8	119.3	130.7	318	1.7	42.1	8.2	640	2.57	26.7	122.7	7.5	66	2.4	5.8	6.5	45	0.71	0.080	16
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

QUALITY CONTROL REPORT WHI11001883.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1289357	Soil	15	0.16	74	0.005	3	1.05	0.010	0.03	<0.1	0.03	1.0	<0.1	<0.05	4	<0.5	<0.2
REP 1289357	QC	15	0.16	74	0.006	3	1.05	0.012	0.04	<0.1	0.02	1.1	<0.1	<0.05	5	0.6	<0.2
1289387	Soil	17	0.13	416	0.002	2	0.67	0.004	0.06	<0.1	0.28	2.7	<0.1	<0.05	2	2.4	<0.2
REP 1289387	QC	17	0.13	407	0.005	2	0.68	0.004	0.05	<0.1	0.26	2.7	<0.1	0.07	2	3.0	<0.2
1289397	Soil	24	0.10	389	0.003	2	0.78	0.007	0.07	0.2	0.14	0.6	0.7	<0.05	3	3.4	<0.2
REP 1289397	QC	24	0.10	389	0.004	2	0.77	0.006	0.06	0.2	0.14	0.8	0.7	<0.05	3	2.4	<0.2
1286241	Soil	25	0.24	538	0.003	6	0.90	0.009	0.11	<0.1	0.20	3.3	0.1	0.10	3	2.0	0.2
REP 1286241	QC	26	0.23	548	0.002	2	0.91	0.010	0.11	<0.1	0.19	3.1	0.2	0.09	3	2.6	<0.2
Reference Materials																	
STD DS8	Standard	111	0.62	276	0.108	3	0.92	0.089	0.41	3.0	0.18	2.2	5.4	0.14	5	6.2	4.8
STD DS8	Standard	109	0.60	287	0.118	2	0.97	0.107	0.43	3.0	0.20	3.1	5.4	0.14	5	5.0	5.2
STD DS8	Standard	113	0.58	264	0.110	2	0.91	0.089	0.37	2.9	0.17	2.2	5.2	0.18	5	4.7	4.9
STD DS8	Standard	117	0.59	274	0.125	2	0.92	0.103	0.42	2.8	0.19	2.6	5.1	0.14	5	6.0	5.0
STD DS8	Standard	114	0.57	275	0.122	2	0.87	0.102	0.41	3.0	0.19	2.0	5.4	0.13	5	5.2	5.0
STD DS8	Standard	107	0.60	286	0.118	4	0.95	0.103	0.40	3.1	0.17	1.9	5.2	0.13	5	4.9	4.8
STD DS8	Standard	112	0.60	279	0.125	3	0.97	0.114	0.40	2.8	0.17	2.2	5.2	0.17	5	4.7	4.4
STD DS8	Standard	111	0.57	264	0.116	3	0.91	0.107	0.42	2.8	0.19	2.2	5.4	0.15	5	4.7	4.9
STD DS8	Standard	109	0.56	261	0.105	2	0.84	0.081	0.39	3.0	0.18	2.0	5.3	0.05	4	4.8	5.0
STD DS8	Standard	123	0.63	271	0.118	2	0.92	0.094	0.37	3.1	0.20	2.1	5.3	0.17	5	5.2	5.0
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

QUALITY CONTROL REPORT WHI11001883.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 06, 2011

QUALITY CONTROL REPORT WHI11001883.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 25, 2011
Report Date: December 02, 2011
Page: 1 of 9

CERTIFICATE OF ANALYSIS WHI11001884.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #31
P.O. Number
Number of Samples: 239

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	239	Sieve soil to 230 mesh			WHI
RJSV	239	Saving all or part of Soil Reject			WHI
1DX2	238	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287635	Soil		5.5	15.2	5.5	103	0.4	28.0	5.6	329	1.23	6.3	1.9	0.1	17	1.9	1.4	0.1	26	0.23	0.052	3
1287636	Soil		5.8	11.4	6.5	84	<0.1	15.4	3.2	46	1.19	10.8	0.6	0.2	6	0.3	1.9	0.1	36	0.02	0.027	7
1287637	Soil		1.2	17.8	4.0	79	0.5	26.5	2.6	61	0.68	2.7	0.8	<0.1	22	1.6	0.7	0.1	14	0.31	0.034	2
1287639	Soil		11.0	45.8	18.3	178	1.2	42.5	6.0	220	2.25	22.5	5.4	1.6	84	1.4	4.3	0.2	92	0.42	0.104	7
1287640	Soil		10.5	52.1	17.4	240	0.8	49.8	7.2	158	2.45	23.8	4.2	2.3	56	1.7	4.0	0.2	81	0.40	0.109	10
1284348	Soil		0.9	18.8	11.9	51	0.4	14.3	17.3	317	1.55	5.5	1.3	0.2	12	<0.1	0.3	0.2	26	0.04	0.059	2
1284349	Soil		1.6	22.4	14.5	75	0.3	19.6	12.4	275	2.48	9.9	1.9	0.4	17	<0.1	0.6	0.2	37	0.04	0.081	5
1284350	Soil		1.9	26.0	17.3	108	0.2	24.8	16.7	408	3.61	13.1	1.9	1.1	15	0.1	0.8	0.3	46	0.03	0.079	5
1289131	Soil		2.3	52.3	9.4	90	0.3	21.0	4.2	150	2.04	7.3	4.5	0.5	18	0.2	1.0	0.2	44	0.07	0.058	4
1289132	Soil		3.0	43.9	9.9	88	0.2	21.3	5.7	175	2.56	10.4	4.9	1.3	15	0.2	1.1	0.2	52	0.08	0.067	6
1289133	Soil		3.3	29.8	12.0	73	0.2	19.4	4.2	109	3.17	10.7	16.0	1.3	6	0.1	1.1	0.2	60	0.01	0.027	6
1289134	Soil		3.9	38.6	14.0	125	0.4	25.3	4.5	130	3.09	15.6	3.2	0.8	11	0.2	1.2	0.2	46	0.03	0.070	3
1289135	Soil		3.3	25.7	13.9	98	0.4	21.9	4.8	163	2.35	53.1	3.6	0.7	11	0.3	2.2	0.2	51	0.03	0.076	4
1289136	Soil		4.0	35.4	20.4	93	0.3	21.8	4.0	78	2.70	21.4	4.5	1.0	11	0.1	1.8	0.2	56	0.01	0.062	3
1289137	Soil		3.4	46.4	12.9	145	1.2	56.6	13.4	178	2.62	14.4	6.5	1.7	43	1.8	1.6	0.2	57	0.25	0.097	9
1289138	Soil		3.3	15.9	6.6	51	0.1	11.8	2.4	39	1.17	10.5	1.3	0.3	12	0.3	1.1	0.1	56	0.07	0.023	8
1289139	Soil		2.7	73.8	15.9	154	1.6	54.3	16.7	185	2.33	13.3	7.7	1.5	52	0.5	1.0	0.3	74	0.33	0.118	8
1289140	Soil		2.6	47.0	14.7	109	0.9	34.5	6.0	152	2.33	11.7	5.6	2.7	64	0.4	1.6	0.2	91	0.42	0.079	11
1289161	Soil		2.8	36.0	13.4	115	1.8	33.0	4.5	107	2.28	15.8	9.9	1.1	32	0.4	1.1	0.3	33	1.38	0.034	4
1289162	Soil		9.3	25.2	17.7	138	1.6	25.7	4.3	117	3.57	18.3	3.7	2.0	51	0.6	2.4	0.2	78	0.52	0.082	8
1289163	Soil		4.7	16.5	9.1	94	0.3	19.3	4.2	115	1.97	13.2	2.7	0.7	12	0.4	1.5	0.2	75	0.04	0.044	8
1289164	Soil		1.8	42.6	11.7	182	1.2	49.9	7.9	345	2.47	13.7	6.6	0.9	85	1.1	1.2	0.2	42	1.77	0.105	6
1289165	Soil		4.2	43.6	12.4	355	0.9	88.3	24.4	619	4.93	12.0	4.7	1.4	55	1.9	1.5	0.2	42	1.09	0.089	6
1289166	Soil		7.1	36.9	14.4	297	1.6	57.0	9.6	284	2.76	19.3	4.1	1.7	44	1.4	5.2	0.2	68	0.56	0.090	8
1289167	Soil		10.9	38.8	19.0	327	1.0	50.4	10.4	202	2.97	28.4	7.8	2.3	63	1.6	4.3	0.2	115	0.75	0.111	10
1289168	Soil		4.9	29.9	18.8	138	0.8	42.6	7.0	108	1.65	16.1	3.6	0.6	50	1.1	1.7	0.2	68	0.74	0.061	8
1289169	Soil		9.0	31.4	13.1	141	0.3	35.8	5.8	145	2.74	21.5	2.7	0.6	22	0.9	3.0	0.2	86	0.09	0.052	9
1289141	Soil		1.7	77.9	9.0	127	1.4	43.0	10.3	379	1.85	9.5	2.8	0.6	105	0.6	0.5	0.2	43	0.94	0.097	6
1289142	Soil		3.0	25.9	7.7	71	0.4	15.4	4.9	112	2.02	11.6	1.9	0.5	7	<0.1	1.0	0.1	56	0.07	0.024	3
1289143	Soil		3.1	23.5	8.6	85	0.5	25.4	4.8	174	2.88	13.1	0.8	0.5	8	0.2	1.1	0.1	59	0.02	0.036	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287635	Soil		5	0.03	338	0.008	2	0.39	0.025	0.03	<0.1	0.15	0.8	0.1	0.08	2	1.8	<0.2
1287636	Soil		6	0.03	86	0.004	1	0.29	0.006	0.03	0.3	0.02	0.5	0.2	<0.05	2	0.7	<0.2
1287637	Soil		5	0.03	333	0.006	1	0.31	0.023	0.03	<0.1	0.06	0.4	<0.1	0.09	<1	0.9	<0.2
1287639	Soil		21	0.11	1631	0.002	3	0.67	0.005	0.07	0.2	0.91	2.5	0.4	0.09	2	2.6	<0.2
1287640	Soil		18	0.11	1233	0.002	3	0.58	0.003	0.07	0.1	0.71	3.0	0.3	0.07	2	2.5	<0.2
1284348	Soil		15	0.10	141	0.003	1	0.77	0.015	0.06	<0.1	0.05	1.2	<0.1	<0.05	3	0.6	<0.2
1284349	Soil		19	0.14	240	0.003	1	0.96	0.009	0.05	<0.1	0.05	1.2	0.1	<0.05	4	0.7	<0.2
1284350	Soil		26	0.17	136	0.003	1	1.14	0.004	0.06	0.1	0.05	1.7	0.1	<0.05	4	0.9	<0.2
1289131	Soil		19	0.14	923	0.002	1	0.73	0.005	0.06	<0.1	0.18	1.6	0.1	<0.05	3	0.6	<0.2
1289132	Soil		23	0.24	283	0.002	2	1.17	0.007	0.07	<0.1	0.10	1.6	0.1	<0.05	4	1.1	<0.2
1289133	Soil		35	0.23	196	0.003	1	1.13	0.003	0.05	<0.1	0.04	1.3	0.1	<0.05	5	0.9	<0.2
1289134	Soil		20	0.19	327	0.001	1	0.80	0.005	0.05	<0.1	0.11	1.7	0.1	<0.05	3	1.3	<0.2
1289135	Soil		18	0.11	150	0.001	2	0.64	0.005	0.07	<0.1	0.05	1.2	0.2	<0.05	3	1.2	<0.2
1289136	Soil		17	0.13	186	0.001	1	0.80	0.003	0.06	<0.1	0.06	1.5	0.2	<0.05	4	1.3	<0.2
1289137	Soil		23	0.24	2160	0.002	2	1.36	0.006	0.08	<0.1	0.58	3.9	0.3	0.18	3	2.2	<0.2
1289138	Soil		11	0.03	143	0.006	2	0.34	0.005	0.05	0.1	0.02	0.6	<0.1	<0.05	3	0.7	<0.2
1289139	Soil		33	0.32	1102	0.003	3	1.72	0.009	0.10	0.1	0.46	3.9	0.3	0.15	4	3.0	<0.2
1289140	Soil		28	0.30	2294	0.002	4	1.55	0.005	0.16	0.1	0.34	3.6	0.2	0.16	4	2.2	<0.2
1289161	Soil		12	0.11	570	<0.001	3	0.63	0.004	0.07	<0.1	0.32	1.9	0.2	0.11	2	2.6	<0.2
1289162	Soil		25	0.21	667	0.004	3	1.34	0.009	0.10	0.2	0.20	2.0	0.4	0.23	4	4.3	<0.2
1289163	Soil		16	0.10	818	0.003	1	0.88	0.007	0.06	0.1	0.08	1.0	0.2	<0.05	3	0.8	<0.2
1289164	Soil		19	0.22	705	0.002	5	0.90	0.007	0.08	<0.1	0.60	2.0	0.2	0.26	2	7.0	<0.2
1289165	Soil		15	0.18	1080	0.002	5	0.76	0.005	0.09	<0.1	0.42	2.1	0.2	0.23	2	6.6	<0.2
1289166	Soil		20	0.21	1354	0.002	2	1.05	0.006	0.06	0.1	0.51	2.9	0.4	0.09	3	2.4	<0.2
1289167	Soil		28	0.25	1611	0.005	4	1.22	0.005	0.09	0.2	0.57	3.0	0.4	0.20	3	3.4	<0.2
1289168	Soil		12	0.10	1955	0.005	3	0.81	0.017	0.08	0.1	0.40	1.7	0.4	0.23	2	1.9	<0.2
1289169	Soil		17	0.09	844	0.003	1	0.74	0.007	0.07	0.1	0.12	2.1	0.3	0.06	3	1.7	<0.2
1289141	Soil		20	0.23	711	0.009	3	1.13	0.013	0.06	0.1	0.18	2.6	0.2	0.21	3	2.4	<0.2
1289142	Soil		14	0.06	227	0.006	3	0.63	0.008	0.07	<0.1	0.05	1.6	0.1	<0.05	4	0.9	<0.2
1289143	Soil		15	0.08	115	0.006	2	0.75	0.007	0.05	0.1	0.04	1.1	0.1	<0.05	4	0.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1289144	Soil	0.6	3.5	12.8	33	<0.1	6.9	2.4	191	2.54	9.7	0.6	0.7	<1	<0.1	0.9	<0.1	8	<0.01	0.007	<1
1289145	Soil	3.2	7.4	6.8	46	<0.1	10.2	2.6	53	1.47	9.3	1.4	0.6	5	0.2	1.1	0.2	71	0.04	0.017	9
1289146	Soil	2.5	37.2	12.3	235	0.8	37.8	7.6	339	2.25	16.8	5.0	0.7	62	2.1	1.4	0.2	52	1.68	0.125	7
1289147	Soil	1.8	33.5	9.1	94	0.7	34.9	8.6	531	2.32	7.9	2.8	0.5	88	1.6	1.2	0.1	42	2.95	0.105	10
1289148	Soil	3.3	21.2	9.5	181	0.6	29.2	7.9	973	4.16	14.2	1.4	0.6	65	1.9	1.5	0.1	88	1.99	0.140	13
1289149	Soil	5.0	48.3	12.2	178	0.6	44.6	7.9	298	2.70	18.9	6.9	1.9	47	0.9	3.0	0.2	82	0.85	0.106	11
1279305	Soil	4.3	49.5	23.7	103	1.3	27.0	5.0	136	2.53	124.5	77.5	1.1	43	0.5	2.8	0.3	30	0.03	0.077	5
1278958	Soil	46.6	53.5	15.3	858	0.6	80.6	5.5	60	1.34	25.7	3.5	1.2	3	5.7	16.2	0.2	160	0.03	0.023	12
1279310	Soil	2.8	34.6	28.4	108	1.2	28.5	7.6	191	2.76	472.6	99.0	2.1	72	0.7	3.6	0.2	21	0.03	0.069	5
1288901	Soil	4.2	16.2	9.9	76	0.3	15.8	3.1	58	1.34	10.1	2.9	0.2	12	0.3	1.3	0.2	48	0.08	0.050	7
1288961	Soil	12.7	42.5	12.2	271	0.6	61.2	8.1	297	1.92	26.7	5.3	2.1	54	2.5	4.2	0.2	84	0.66	0.129	11
1288962	Soil	6.7	30.7	9.7	171	0.7	42.3	6.0	211	1.40	13.6	5.4	1.1	43	1.3	2.6	0.2	72	0.64	0.075	7
1288963	Soil	19.6	33.6	9.8	1852	0.5	157.2	9.2	384	2.87	43.9	3.1	1.6	75	10.7	4.8	0.1	76	1.43	0.109	8
1288964	Soil	6.7	27.0	15.9	137	0.7	42.1	8.7	153	1.85	21.1	3.9	1.7	54	1.8	2.4	0.2	60	1.17	0.070	10
1288965	Soil	14.0	51.8	16.5	255	0.6	71.4	9.8	222	2.25	24.8	4.2	3.5	39	2.0	4.6	0.2	71	0.41	0.114	12
1286651	Soil	9.7	51.9	10.9	396	1.4	67.6	7.6	818	1.97	13.3	6.5	1.3	117	4.1	3.7	0.2	120	0.65	0.143	7
1286652	Soil	4.1	46.8	8.7	357	1.1	46.9	5.6	291	1.39	9.6	4.8	1.1	58	3.8	1.9	0.2	83	0.41	0.093	8
1286654	Soil	3.8	55.2	11.3	403	1.2	73.3	8.8	584	1.78	10.4	5.8	1.4	101	5.3	2.9	0.2	94	1.12	0.118	7
1286655	Soil	7.3	56.3	10.9	251	0.7	46.4	8.6	308	2.29	16.9	5.3	2.3	75	2.6	4.8	0.2	110	0.35	0.162	10
1286656	Soil	5.0	48.1	10.0	186	1.1	40.8	6.4	248	1.82	12.5	4.3	1.7	74	1.9	3.2	0.2	90	0.56	0.114	8
1286657	Soil	3.5	69.0	11.4	237	1.6	61.0	6.2	166	1.83	12.8	6.9	1.6	93	3.9	3.6	0.2	101	0.98	0.119	8
1286658	Soil	8.0	62.5	11.9	321	1.3	62.7	7.1	458	2.25	22.6	6.6	1.4	92	3.8	4.8	0.2	141	0.58	0.134	8
1286659	Soil	3.4	55.8	10.0	306	1.0	64.9	6.8	247	1.28	7.2	5.0	1.6	100	3.7	2.6	0.1	92	0.86	0.124	8
1286660	Soil	7.2	63.1	11.7	277	1.2	61.8	6.5	488	1.92	16.1	5.9	1.7	89	3.4	4.2	0.2	120	0.53	0.125	9
1274427	Soil	2.5	20.4	17.3	84	0.3	18.2	19.1	1425	3.68	8.9	0.6	0.4	11	0.3	0.8	0.2	36	0.12	0.180	5
1274428	Soil	0.7	5.1	3.5	25	0.1	4.3	3.4	187	0.90	1.5	<0.5	<0.1	5	0.1	0.2	<0.1	16	0.04	0.061	1
1274429	Soil	2.0	32.2	24.2	125	0.2	31.1	26.8	980	3.83	13.0	0.7	0.6	13	0.2	1.0	0.2	33	0.03	0.090	3
1274430	Soil	2.2	23.3	20.5	95	0.2	25.7	11.2	334	4.15	13.5	<0.5	1.3	13	<0.1	1.0	0.2	34	0.02	0.075	2
1287251	Soil	14.8	18.4	10.7	169	0.1	46.7	8.4	361	3.33	31.9	1.4	1.9	6	0.3	2.6	0.2	60	0.03	0.039	16
1287252	Soil	77.0	42.8	10.3	1036	0.4	256.1	12.7	240	2.84	91.8	4.8	1.3	17	2.5	6.9	0.1	135	0.19	0.066	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1289144	Soil	9	0.01	21	<0.001	<1	0.20	0.001	<0.01	<0.1	0.03	0.5	<0.1	<0.05	<1	0.5	<0.2
1289145	Soil	11	0.04	110	0.014	<1	0.57	0.009	0.03	0.1	0.02	0.7	0.1	<0.05	4	<0.5	<0.2
1289146	Soil	19	0.22	640	0.005	6	0.97	0.009	0.10	0.1	0.43	2.0	0.2	0.25	2	2.9	<0.2
1289147	Soil	20	0.20	769	0.008	3	0.80	0.007	0.05	0.1	0.17	1.9	0.1	0.23	2	2.3	<0.2
1289148	Soil	32	0.34	693	0.009	2	1.44	0.008	0.04	0.1	0.25	2.2	0.1	0.10	4	1.4	<0.2
1289149	Soil	23	0.26	1697	0.004	4	1.04	0.006	0.10	0.2	0.48	2.6	0.2	0.10	3	1.4	<0.2
1279305	Soil	20	0.05	287	0.002	3	0.64	0.004	0.15	0.1	0.30	1.7	0.3	0.24	2	4.0	0.2
1278958	Soil	8	0.01	174	0.001	2	0.19	<0.001	0.04	<0.1	0.16	1.8	0.4	<0.05	<1	4.6	<0.2
1279310	Soil	20	0.07	236	0.001	2	0.70	0.003	0.09	0.2	0.24	3.6	0.2	0.09	2	1.8	<0.2
1288901	Soil	11	0.04	321	0.002	1	0.58	0.003	0.05	0.1	0.03	0.4	0.1	<0.05	3	0.6	<0.2
1288961	Soil	16	0.16	1069	0.003	4	0.58	0.004	0.09	0.1	0.44	2.2	0.3	0.08	2	1.5	<0.2
1288962	Soil	14	0.14	1001	0.004	3	0.75	0.016	0.06	0.1	0.31	1.8	0.2	0.08	2	1.1	<0.2
1288963	Soil	11	0.35	664	0.002	4	0.37	0.003	0.05	0.1	0.51	2.0	0.6	0.08	<1	2.0	<0.2
1288964	Soil	13	0.11	1309	0.003	2	0.58	0.003	0.04	0.1	0.37	2.4	0.2	0.09	2	1.6	<0.2
1288965	Soil	14	0.11	1311	0.004	2	0.49	0.003	0.08	0.1	0.55	3.0	0.3	<0.05	1	1.9	<0.2
1286651	Soil	17	0.10	1363	0.002	5	0.59	0.003	0.09	<0.1	1.07	2.8	0.4	0.08	2	3.6	<0.2
1286652	Soil	18	0.10	827	0.003	3	0.61	0.005	0.07	0.1	0.83	2.2	0.3	<0.05	2	2.0	<0.2
1286654	Soil	17	0.15	1040	0.002	5	0.54	0.003	0.09	<0.1	0.83	2.7	0.3	0.08	2	4.3	<0.2
1286655	Soil	20	0.12	1033	0.003	3	0.58	0.002	0.11	0.1	0.45	2.3	0.3	<0.05	2	2.9	<0.2
1286656	Soil	20	0.15	1545	0.003	4	0.68	0.006	0.08	0.1	0.58	2.4	0.3	0.08	2	3.2	<0.2
1286657	Soil	21	0.19	1508	0.003	4	0.81	0.005	0.09	0.1	0.80	2.8	0.3	0.10	2	4.7	<0.2
1286658	Soil	20	0.14	1207	0.002	4	0.67	0.003	0.09	0.1	1.06	2.9	0.3	0.05	2	5.2	<0.2
1286659	Soil	18	0.16	1123	0.002	5	0.61	0.006	0.11	0.2	0.79	2.5	0.3	0.08	2	3.9	<0.2
1286660	Soil	20	0.14	1255	0.002	4	0.67	0.003	0.09	0.2	0.99	2.8	0.3	0.06	2	5.2	<0.2
1274427	Soil	26	0.13	214	0.005	1	1.39	0.006	0.05	<0.1	0.07	0.4	0.1	0.08	5	0.6	<0.2
1274428	Soil	7	0.03	63	0.003	<1	0.27	0.016	0.03	<0.1	0.03	0.1	<0.1	<0.05	1	<0.5	<0.2
1274429	Soil	24	0.26	161	0.003	<1	1.31	0.007	0.06	0.1	0.03	1.6	0.2	<0.05	5	<0.5	<0.2
1274430	Soil	26	0.26	126	0.002	<1	1.21	0.005	0.08	<0.1	0.02	2.0	0.2	<0.05	5	<0.5	<0.2
1287251	Soil	12	0.06	161	0.002	1	0.73	0.003	0.06	0.1	0.06	1.3	0.3	<0.05	3	0.7	<0.2
1287252	Soil	24	0.08	609	0.002	2	0.75	0.003	0.07	0.3	0.45	2.6	1.1	<0.05	2	2.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287253	Soil		27.1	28.7	9.0	178	0.3	66.0	6.1	163	1.66	20.5	1.3	0.9	27	1.0	2.7	0.1	63	0.47	0.044	13
1287254	Soil		9.3	67.4	23.6	315	0.8	83.4	15.5	339	4.40	46.3	7.4	2.9	10	0.6	4.5	0.3	29	0.08	0.070	10
1287255	Soil		11.6	28.1	10.5	160	0.3	47.7	9.8	274	2.67	76.5	3.1	1.5	9	0.7	2.8	0.2	48	0.18	0.043	18
1287256	Soil		45.5	65.5	12.1	1464	1.3	222.5	10.5	625	2.46	33.4	4.4	1.7	31	13.0	9.1	0.2	177	0.51	0.103	17
1287257	Soil		26.8	41.4	17.6	533	1.6	99.4	7.2	294	2.12	54.1	13.8	1.0	47	6.6	14.0	0.2	134	0.57	0.099	13
1287258	Soil		69.0	45.0	9.9	1434	0.7	183.0	9.1	415	2.32	30.6	2.4	1.2	73	47.1	9.3	0.1	114	2.66	0.080	11
1287259	Soil		57.6	39.1	10.9	1030	1.2	194.4	10.1	811	3.00	64.8	2.9	0.9	161	43.4	13.1	0.1	229	3.50	0.076	13
1287260	Soil		59.8	38.7	6.5	419	0.4	135.3	6.8	171	1.57	28.5	1.3	0.2	18	5.7	8.8	0.1	141	0.40	0.045	14
1286671	Soil		7.6	71.0	11.2	363	1.2	57.9	2.4	114	1.14	11.6	4.8	1.3	95	5.6	5.6	0.1	172	0.54	0.112	10
1286672	Soil		7.3	37.2	8.6	158	0.4	27.3	4.9	112	1.56	11.6	4.4	2.5	34	1.5	2.7	0.2	75	0.17	0.092	10
1286673	Soil		8.1	28.3	8.5	258	0.8	36.2	7.2	405	1.65	10.8	4.1	0.8	56	2.3	2.1	0.1	64	0.78	0.077	6
1286674	Soil		9.0	55.4	15.3	286	1.1	48.9	9.1	449	2.35	18.6	5.5	1.8	60	3.2	3.5	0.2	103	0.61	0.108	10
1286675	Soil		4.5	60.1	13.4	173	1.1	46.3	4.9	143	1.64	13.9	4.5	1.4	40	3.4	2.2	0.2	60	0.56	0.061	11
1286676	Soil		4.5	60.9	14.8	183	1.2	28.6	2.5	56	1.59	15.4	4.1	2.7	66	2.7	4.5	0.2	71	0.29	0.120	12
1286677	Soil		4.5	59.3	11.2	205	1.2	41.6	6.7	429	1.60	13.5	6.4	0.8	63	4.3	3.1	0.2	65	0.81	0.099	7
1286678	Soil		3.7	57.7	17.6	154	0.1	41.1	13.6	452	3.65	20.5	6.0	6.7	31	0.6	2.3	0.3	44	0.40	0.070	22
1286679	Soil		3.1	54.0	21.0	151	0.2	36.4	14.1	500	3.69	21.1	4.4	7.9	18	0.6	2.4	0.4	40	0.19	0.094	29
1287021	Soil		1.6	31.6	27.1	52	0.7	11.7	7.4	671	2.73	18.2	2.2	0.7	15	0.1	0.6	0.3	33	0.03	0.101	3
1287022	Soil		0.3	6.0	4.2	7	0.8	1.7	0.6	21	0.73	2.4	0.9	<0.1	6	<0.1	0.1	<0.1	8	0.02	0.050	<1
1287023	Soil		1.0	24.8	15.2	54	0.5	9.2	2.0	85	2.12	10.7	1.1	0.3	14	0.4	0.5	0.2	40	0.03	0.163	2
1287024	Soil		1.4	18.1	12.2	44	2.0	10.0	2.1	94	1.62	11.6	1.3	0.5	10	0.3	0.7	0.2	33	0.03	0.097	4
1287026	Soil		3.7	12.1	12.6	33	0.5	7.1	1.5	28	1.29	34.3	1.4	0.4	23	0.1	1.7	0.2	34	0.03	0.095	4
1287027	Soil		4.5	15.3	15.5	71	0.4	33.3	3.7	71	1.94	19.1	1.4	0.8	14	0.3	1.6	0.2	43	0.03	0.060	7
1287028	Soil		2.7	6.1	4.4	39	0.3	6.4	1.4	31	0.85	9.0	<0.5	0.2	5	<0.1	1.0	<0.1	30	0.01	0.031	2
1287029	Soil		1.6	12.6	7.7	42	0.4	8.6	2.1	30	1.13	17.7	0.9	0.2	12	0.3	1.0	0.1	20	0.01	0.051	3
1287030	Soil		2.0	15.1	9.7	75	0.1	13.5	5.0	67	1.97	13.5	0.7	0.4	7	0.3	1.0	0.2	35	0.02	0.051	3
1279107	Soil		12.5	62.7	15.3	269	0.9	58.3	4.9	100	2.04	34.3	4.5	1.9	92	3.2	8.3	0.2	113	0.30	0.135	6
1279108	Soil		13.2	62.9	16.4	258	1.0	54.7	5.5	113	2.17	37.5	5.2	1.9	87	2.8	9.1	0.2	113	0.24	0.137	7
1279109	Soil		12.0	59.6	14.7	257	0.9	63.2	4.6	97	2.02	35.2	4.7	1.9	85	2.9	8.2	0.2	113	0.28	0.143	6
1279110	Soil		12.8	69.6	16.1	280	1.0	55.8	5.3	118	2.36	42.2	7.7	2.1	87	3.0	9.8	0.2	127	0.25	0.167	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287253	Soil	11	0.07	595	0.002	2	0.48	0.006	0.06	0.2	0.12	1.7	0.3	0.06	2	0.9	<0.2
1287254	Soil	12	0.05	420	0.001	2	0.50	0.002	0.06	<0.1	0.27	3.4	0.3	<0.05	<1	1.4	<0.2
1287255	Soil	10	0.08	223	0.003	2	0.42	0.006	0.05	0.1	0.08	1.4	0.2	<0.05	2	1.0	<0.2
1287256	Soil	19	0.16	464	0.002	3	0.43	0.002	0.08	0.2	1.03	3.3	2.9	<0.05	1	3.2	<0.2
1287257	Soil	20	0.20	772	0.004	4	0.69	0.007	0.10	0.3	2.32	2.1	1.4	0.08	2	3.3	<0.2
1287258	Soil	15	1.47	460	0.002	3	0.33	0.003	0.06	0.3	0.42	2.3	1.7	<0.05	<1	3.3	<0.2
1287259	Soil	31	1.73	1254	0.004	3	0.80	0.014	0.07	0.3	1.04	4.0	1.5	0.05	2	2.6	<0.2
1287260	Soil	14	0.10	597	0.003	2	0.46	0.006	0.05	0.3	0.18	0.7	1.4	<0.05	2	2.1	<0.2
1286671	Soil	20	0.10	1247	0.002	4	0.59	0.003	0.11	<0.1	1.38	2.3	0.5	0.06	2	5.3	<0.2
1286672	Soil	18	0.14	693	0.004	2	0.70	0.002	0.08	0.1	0.66	2.8	0.3	<0.05	2	1.6	<0.2
1286673	Soil	13	0.14	1006	0.003	2	0.59	0.016	0.06	0.1	0.46	1.7	0.2	0.06	2	3.2	<0.2
1286674	Soil	21	0.19	1597	0.002	3	0.86	0.005	0.10	0.1	0.78	2.9	0.3	0.06	2	3.6	<0.2
1286675	Soil	17	0.13	1669	0.005	3	0.87	0.008	0.07	0.2	0.52	2.9	0.2	<0.05	3	2.2	<0.2
1286676	Soil	19	0.17	2505	0.004	5	0.84	0.005	0.11	0.1	0.93	3.3	0.4	0.08	3	6.7	<0.2
1286677	Soil	15	0.11	901	0.005	4	0.68	0.013	0.06	0.1	0.75	2.6	0.3	0.10	2	5.4	<0.2
1286678	Soil	23	0.41	652	0.005	3	1.58	0.010	0.13	0.4	0.17	4.3	0.2	<0.05	4	0.9	<0.2
1286679	Soil	21	0.38	573	0.009	2	1.44	0.008	0.10	0.4	0.14	3.8	0.1	<0.05	4	0.6	<0.2
1287021	Soil	21	0.12	263	0.005	2	1.14	0.015	0.06	<0.1	0.04	2.0	0.1	<0.05	4	0.9	<0.2
1287022	Soil	6	0.02	44	0.005	<1	0.45	0.034	0.03	<0.1	0.03	0.5	<0.1	<0.05	1	<0.5	<0.2
1287023	Soil	18	0.04	267	0.002	2	0.81	0.012	0.06	<0.1	0.06	0.6	<0.1	<0.05	3	0.6	<0.2
1287024	Soil	11	0.04	213	0.003	1	0.66	0.018	0.06	<0.1	0.06	0.9	<0.1	<0.05	3	0.6	<0.2
1287026	Soil	9	0.04	308	0.003	2	0.45	0.014	0.07	<0.1	0.07	0.8	0.3	0.13	2	1.2	<0.2
1287027	Soil	50	0.07	227	0.004	2	0.62	0.006	0.07	0.1	0.03	1.2	0.2	<0.05	3	0.7	<0.2
1287028	Soil	4	0.02	117	0.003	1	0.42	0.017	0.04	<0.1	0.02	0.7	0.1	<0.05	2	<0.5	<0.2
1287029	Soil	6	0.04	153	0.003	1	0.44	0.019	0.05	<0.1	0.03	0.6	0.1	<0.05	2	0.5	<0.2
1287030	Soil	9	0.04	109	0.003	<1	0.69	0.012	0.04	<0.1	0.02	1.3	0.1	<0.05	3	<0.5	<0.2
1279107	Soil	22	0.06	1509	0.003	4	0.46	0.003	0.10	0.1	1.00	3.5	0.5	0.06	1	2.5	<0.2
1279108	Soil	22	0.07	1848	0.004	4	0.49	0.003	0.10	0.2	1.00	3.5	0.5	0.07	1	2.4	<0.2
1279109	Soil	30	0.06	1631	0.003	4	0.45	0.003	0.09	0.1	1.10	3.4	0.5	0.05	1	2.1	<0.2
1279110	Soil	23	0.06	1836	0.003	4	0.50	0.003	0.09	0.2	1.49	4.0	0.5	0.07	2	2.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288611	Soil	45.1	43.4	103.3	100	3.6	71.1	12.6	127	2.45	64.6	5.1	1.1	97	1.0	35.7	0.3	160	0.13	0.118	19
1288612	Soil	57.0	33.4	50.2	60	3.9	14.2	1.6	22	2.03	73.6	2.9	3.4	133	0.9	57.2	0.3	235	0.04	0.086	9
1288613	Soil	31.2	57.2	28.0	383	2.3	100.1	11.9	319	3.02	68.8	8.4	1.3	41	2.7	19.1	0.2	231	0.10	0.142	15
1288614	Soil	53.9	78.2	69.1	484	3.0	112.0	13.6	340	3.76	92.5	12.0	2.1	75	6.0	27.1	0.3	289	0.14	0.166	15
1288615	Soil	40.4	76.3	26.7	546	1.6	118.1	10.2	207	3.23	99.2	12.3	2.6	66	5.6	28.0	0.2	262	0.24	0.162	17
1288616	Soil	47.2	85.2	39.2	696	1.8	150.6	11.1	259	3.62	124.4	11.9	4.6	93	8.4	37.8	0.3	331	0.39	0.160	14
1288617	Soil	21.1	30.4	21.9	249	1.5	59.2	5.2	139	1.87	60.0	8.6	0.5	37	2.4	14.8	0.3	189	0.11	0.121	12
1288618	Soil	21.7	57.8	18.8	319	1.5	90.6	11.8	358	2.97	53.2	4.0	3.0	35	2.4	9.3	0.3	99	0.19	0.235	16
1288619	Soil	33.0	80.7	19.0	398	1.5	106.3	12.6	268	3.24	63.2	3.6	3.7	44	5.2	12.1	0.2	113	0.29	0.215	16
1288620	Soil	24.6	65.2	16.3	885	2.0	150.0	10.1	187	2.39	59.3	4.5	1.8	49	9.9	15.9	0.2	115	0.38	0.189	15
1286271	Soil	4.1	17.7	14.1	102	0.4	20.5	5.1	156	2.80	19.2	2.5	1.4	18	0.4	1.9	0.2	59	0.06	0.094	10
1286272	Soil	3.5	17.0	11.7	68	0.3	21.8	3.5	62	1.51	12.7	0.8	1.4	16	0.3	1.3	0.2	44	0.04	0.046	8
1286273	Soil	3.3	16.7	13.1	72	0.3	16.2	4.2	80	2.12	17.0	0.9	1.4	16	0.3	1.3	0.3	52	0.03	0.054	7
1286274	Soil	2.6	27.1	13.4	119	0.3	31.9	9.7	145	2.29	14.4	2.7	1.9	103	0.5	1.3	0.2	35	0.52	0.067	4
1286275	Soil	2.4	26.7	13.0	112	0.5	28.2	8.7	153	2.47	13.4	1.6	2.5	64	0.5	1.1	0.2	38	0.34	0.066	5
1286276	Soil	3.1	30.0	17.5	102	0.5	33.2	11.1	175	3.25	17.8	1.9	2.3	81	0.4	1.6	0.2	54	0.48	0.067	5
1286277	Soil	2.8	13.9	12.2	37	0.5	11.2	2.0	30	1.90	15.9	1.7	1.2	57	0.3	0.8	0.3	44	0.28	0.072	4
1286278	Soil	4.1	27.4	15.5	139	0.2	28.6	11.8	345	3.09	22.2	1.3	1.9	36	0.3	1.8	0.2	47	0.11	0.075	5
1286279	Soil	4.1	17.3	12.8	103	0.1	20.5	13.2	344	3.34	18.3	<0.5	1.4	41	0.3	1.2	0.4	39	0.25	0.063	4
1286280	Soil	3.7	31.6	17.1	162	0.6	33.1	20.7	375	3.37	17.3	1.8	1.9	37	0.5	0.9	0.3	45	0.22	0.067	5
1289121	Soil	3.4	33.0	10.8	218	1.0	49.8	8.6	175	2.92	11.5	2.0	1.3	30	1.1	1.3	0.2	24	0.52	0.096	3
1289122	Soil	3.1	49.3	14.9	169	1.1	35.7	8.1	323	2.57	18.6	4.9	1.4	56	1.6	2.4	0.3	65	1.15	0.106	8
1289123	Soil	2.7	21.8	10.2	542	0.9	50.7	12.1	424	3.04	17.8	1.5	0.8	85	2.9	2.3	0.2	58	2.43	0.211	17
1289124	Soil	1.8	58.6	11.3	155	1.0	39.4	5.3	251	1.78	12.2	6.4	0.7	91	1.3	2.7	0.3	59	2.51	0.105	7
1289125	Soil	4.1	65.7	13.8	81	0.3	12.4	2.7	51	1.82	13.2	1.9	0.3	27	0.2	1.1	0.2	46	0.06	0.061	6
1289126	Soil	2.5	227.4	14.4	120	0.4	26.7	5.0	118	2.06	9.9	3.9	0.5	26	0.3	1.0	0.2	38	0.10	0.059	5
1289127	Soil	2.9	31.6	8.2	59	0.6	10.1	2.6	67	1.93	9.8	<0.5	0.3	8	0.1	1.0	0.2	45	0.03	0.039	5
1289128	Soil	1.5	105.7	13.8	26	2.6	18.0	3.2	39	1.28	5.7	3.6	0.6	20	0.6	0.4	0.2	25	0.07	0.087	8
1289129	Soil	2.3	155.0	11.4	173	1.7	77.9	41.5	734	1.62	7.9	7.8	0.7	150	0.6	0.9	0.2	39	0.47	0.081	8
1289130	Soil	2.4	25.2	7.7	45	0.2	10.3	1.9	45	1.05	8.9	0.5	0.2	7	0.2	0.9	0.2	35	0.01	0.042	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288611	Soil	48	0.10	771	0.004	6	0.54	0.007	0.17	1.0	1.25	2.6	2.8	0.27	2	17.5	0.3
1288612	Soil	24	0.02	335	0.002	8	0.36	0.006	0.26	0.9	3.40	2.0	4.3	0.44	2	20.4	0.3
1288613	Soil	56	0.08	996	0.005	4	0.78	0.006	0.11	0.6	1.67	2.5	1.3	0.09	3	5.1	<0.2
1288614	Soil	32	0.07	1179	0.004	5	0.77	0.005	0.16	0.8	2.44	3.9	2.9	0.17	2	10.9	0.2
1288615	Soil	26	0.06	1346	0.004	6	0.56	0.003	0.14	0.8	2.36	3.7	1.7	0.12	2	6.1	<0.2
1288616	Soil	28	0.09	1135	0.004	8	0.54	0.004	0.18	0.8	4.34	5.1	2.6	0.14	2	7.9	0.3
1288617	Soil	19	0.06	542	0.007	4	0.64	0.010	0.09	0.6	0.78	1.3	0.9	0.06	3	4.4	<0.2
1288618	Soil	38	0.05	573	0.005	5	0.74	0.004	0.11	0.8	0.64	3.5	0.7	0.06	1	3.1	<0.2
1288619	Soil	19	0.04	1178	0.003	5	0.57	0.003	0.13	2.6	0.90	4.3	0.8	0.06	1	3.9	<0.2
1288620	Soil	18	0.05	1214	0.003	5	0.66	0.006	0.12	1.4	1.04	4.0	0.9	0.07	1	3.5	<0.2
1286271	Soil	21	0.20	319	0.008	2	1.03	0.005	0.07	0.2	0.07	1.7	0.2	<0.05	4	0.8	<0.2
1286272	Soil	26	0.06	365	0.003	<1	0.80	0.007	0.05	0.1	0.09	1.4	0.2	<0.05	3	0.7	<0.2
1286273	Soil	12	0.08	660	0.003	1	0.81	0.005	0.04	0.1	0.05	1.7	0.1	<0.05	3	<0.5	<0.2
1286274	Soil	17	0.22	1815	0.001	2	0.92	0.007	0.05	<0.1	0.14	3.5	<0.1	0.05	3	1.5	<0.2
1286275	Soil	20	0.27	1628	0.002	2	1.03	0.006	0.05	<0.1	0.13	3.7	<0.1	<0.05	3	1.1	<0.2
1286276	Soil	22	0.24	1419	0.002	2	1.32	0.010	0.08	0.1	0.16	4.2	0.1	0.06	3	1.8	<0.2
1286277	Soil	14	0.10	547	0.001	2	0.89	0.008	0.06	<0.1	0.14	1.6	0.2	<0.05	4	1.3	<0.2
1286278	Soil	18	0.19	1007	0.002	1	0.97	0.006	0.06	0.1	0.05	2.4	0.1	<0.05	3	1.3	<0.2
1286279	Soil	20	0.19	775	0.002	1	0.96	0.009	0.06	<0.1	0.09	1.8	0.1	0.10	3	1.8	<0.2
1286280	Soil	22	0.22	503	0.001	2	1.20	0.007	0.06	<0.1	0.14	2.7	0.1	<0.05	3	2.1	<0.2
1289121	Soil	12	0.06	827	0.001	2	0.43	0.004	0.04	<0.1	0.45	2.6	<0.1	0.06	1	1.9	<0.2
1289122	Soil	19	0.21	1888	0.002	3	0.96	0.005	0.06	0.1	0.73	2.9	0.2	0.10	3	2.5	<0.2
1289123	Soil	32	0.20	703	0.005	3	0.84	0.007	0.05	0.1	0.63	2.3	0.1	0.11	2	3.0	<0.2
1289124	Soil	18	0.13	1144	0.004	5	0.70	0.009	0.07	0.2	0.69	2.0	0.1	0.22	2	3.5	<0.2
1289125	Soil	16	0.06	346	0.003	2	0.61	0.006	0.06	0.1	0.15	0.7	0.1	<0.05	4	1.5	<0.2
1289126	Soil	19	0.15	782	0.004	3	0.92	0.012	0.05	<0.1	0.14	1.5	0.1	<0.05	3	1.4	<0.2
1289127	Soil	12	0.05	165	0.011	2	0.48	0.011	0.04	0.1	0.05	0.6	0.1	<0.05	4	1.2	<0.2
1289128	Soil	15	0.04	646	0.002	2	0.77	0.006	0.04	<0.1	0.48	1.1	0.1	0.05	2	1.7	<0.2
1289129	Soil	18	0.17	1498	0.004	4	1.23	0.015	0.07	<0.1	0.40	3.0	0.2	0.05	3	2.2	<0.2
1289130	Soil	10	0.04	143	0.003	3	0.44	0.009	0.04	0.1	0.04	0.4	<0.1	<0.05	3	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1286231	Soil		1.9	31.9	13.4	189	2.8	53.1	4.4	72	1.99	14.3	3.0	1.0	194	1.2	1.1	0.2	51	1.54	0.236	13
1286232	Soil		2.0	56.2	13.2	196	1.9	65.3	8.6	254	3.77	10.4	7.2	0.8	79	1.0	1.3	0.3	30	1.13	0.097	7
1286233	Soil		3.0	50.5	14.1	236	2.4	77.5	10.7	498	4.56	11.8	8.5	1.3	58	1.2	1.6	0.2	41	0.63	0.107	9
1286234	Soil		2.1	43.6	14.4	199	2.1	66.8	9.0	357	4.40	9.8	10.3	0.8	128	0.8	1.4	0.2	36	1.26	0.097	6
1286235	Soil		1.7	23.1	11.1	128	1.8	41.4	5.9	94	2.08	13.0	2.5	1.0	76	0.6	0.8	0.2	25	1.52	0.115	9
1286236	Soil		2.3	44.5	15.6	169	1.2	58.5	10.2	325	3.67	15.7	2.9	2.8	57	0.8	1.4	0.2	38	0.44	0.128	9
1286237	Soil		8.5	89.7	18.7	406	3.7	120.6	15.5	321	4.05	42.5	7.0	2.3	170	2.2	3.2	0.3	52	0.95	0.174	9
1286238	Soil		1.8	34.3	19.4	155	1.7	49.3	12.2	517	2.82	19.0	4.8	0.9	94	1.5	1.1	0.2	26	1.48	0.128	6
1286239	Soil		3.0	48.3	44.7	388	0.8	68.1	20.4	1068	3.57	146.9	11.8	2.5	223	1.9	2.8	0.3	30	0.05	0.081	5
1286240	Soil		2.1	49.0	30.6	171	1.5	53.9	14.7	1163	4.41	49.3	6.0	2.5	123	0.4	1.5	0.3	24	0.19	0.087	4
1286261	Soil		4.9	27.2	14.9	136	0.6	29.7	7.8	132	2.57	17.5	2.2	2.2	41	0.7	1.8	0.2	47	0.29	0.078	5
1286262	Soil		4.8	34.5	17.5	170	0.2	33.8	11.9	257	3.19	27.8	2.6	2.3	30	0.7	2.3	0.2	41	0.10	0.090	6
1286263	Soil		4.0	37.5	13.6	161	0.5	40.4	11.5	332	2.52	17.2	2.8	2.1	47	1.6	1.7	0.2	42	0.47	0.087	6
1286264	Soil		6.8	52.9	17.9	257	0.8	70.2	14.6	601	2.95	20.6	3.1	3.8	53	2.3	2.9	0.3	56	0.65	0.093	10
1286265	Soil		5.4	29.5	15.6	165	0.5	36.1	11.2	567	2.72	18.6	<0.5	1.8	44	1.2	1.5	0.2	41	0.49	0.076	4
1286266	Soil		3.5	27.2	13.9	104	0.4	27.6	6.4	93	2.66	16.7	2.6	2.1	32	0.5	1.3	0.2	39	0.15	0.068	4
1286267	Soil		2.2	18.4	6.2	71	0.5	21.2	5.1	101	1.32	7.0	0.9	0.7	37	0.5	0.7	0.1	24	0.25	0.052	2
1286268	Soil		3.2	30.6	13.1	177	0.7	43.9	29.0	1405	2.72	12.4	1.1	1.5	68	1.6	1.3	0.2	34	0.65	0.087	4
1286269	Soil		3.4	20.5	11.6	69	0.2	15.2	3.5	70	1.58	12.6	0.6	1.2	14	0.2	0.9	0.1	30	0.03	0.037	4
1286270	Soil		7.1	32.3	18.2	178	0.1	40.5	11.5	233	2.85	24.9	2.1	2.2	26	0.6	2.4	0.2	52	0.12	0.084	7
1286851	Soil		0.9	23.6	8.8	94	1.0	48.8	7.2	255	1.58	6.3	2.1	0.5	53	0.1	0.4	0.1	18	0.48	0.085	5
1286852	Soil		1.8	33.8	16.5	73	0.5	20.3	3.8	169	1.94	9.9	0.5	0.6	23	0.7	0.6	0.3	38	0.11	0.157	4
1286853	Soil		1.8	35.4	17.7	107	1.2	35.6	9.9	413	3.19	14.2	4.3	1.1	81	0.3	0.8	0.3	34	0.67	0.138	3
1286854	Soil		1.4	8.8	10.7	44	<0.1	9.0	2.3	67	1.17	6.6	<0.5	0.4	12	0.1	0.5	0.2	31	0.03	0.044	6
1286855	Soil		0.4	4.5	2.4	7	0.2	1.6	0.7	20	0.46	1.0	<0.5	<0.1	5	<0.1	<0.1	<0.1	5	0.02	0.038	<1
1286856	Soil		0.9	6.8	3.3	20	0.1	5.7	1.3	33	0.44	2.4	0.6	<0.1	15	<0.1	0.2	<0.1	14	0.19	0.038	2
1286857	Soil		1.2	9.5	6.5	29	0.6	6.3	1.5	20	0.78	5.7	0.8	<0.1	11	<0.1	0.4	<0.1	17	0.02	0.046	2
1286858	Soil		2.4	10.0	5.6	153	<0.1	31.2	11.5	471	3.23	10.0	<0.5	0.2	10	0.6	1.0	<0.1	41	0.13	0.037	7
1286859	Soil		2.1	8.1	9.6	53	<0.1	8.2	2.1	58	0.78	8.8	<0.5	0.2	10	<0.1	0.8	<0.1	33	0.02	0.034	4
1286860	Soil		0.6	8.2	5.5	31	0.2	6.7	1.2	32	0.48	3.9	1.2	0.2	16	0.2	0.3	<0.1	17	0.17	0.029	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286231	Soil	31	0.21	638	0.002	9	0.97	0.008	0.09	<0.1	0.20	2.3	0.3	0.11	2	5.7	<0.2
1286232	Soil	15	0.09	453	0.002	3	0.56	0.005	0.07	<0.1	0.24	3.7	0.1	0.06	1	2.6	<0.2
1286233	Soil	20	0.10	467	0.002	3	0.59	0.004	0.06	<0.1	0.28	5.5	0.1	0.05	2	2.7	<0.2
1286234	Soil	19	0.09	674	0.002	5	0.63	0.005	0.06	<0.1	0.45	4.0	0.1	0.13	1	2.3	<0.2
1286235	Soil	18	0.06	465	0.001	3	0.49	0.006	0.06	<0.1	0.21	2.7	0.2	0.15	1	3.2	<0.2
1286236	Soil	22	0.15	382	0.002	4	0.92	0.006	0.07	<0.1	0.12	4.1	0.1	<0.05	2	2.9	<0.2
1286237	Soil	22	0.05	473	0.001	4	0.68	0.007	0.14	<0.1	0.45	4.9	0.3	0.21	1	13.6	<0.2
1286238	Soil	19	0.08	781	0.001	5	0.63	0.005	0.09	<0.1	0.36	3.1	0.2	0.17	2	2.8	<0.2
1286239	Soil	20	0.08	321	0.002	4	0.70	0.008	0.15	<0.1	0.22	3.4	0.3	0.21	2	3.4	<0.2
1286240	Soil	19	0.14	616	<0.001	3	0.83	0.008	0.13	<0.1	0.34	5.3	0.2	0.15	2	3.1	<0.2
1286261	Soil	18	0.22	1145	0.001	2	0.93	0.005	0.05	<0.1	0.32	2.7	0.2	<0.05	3	1.6	<0.2
1286262	Soil	17	0.19	946	0.002	<1	0.81	0.003	0.05	<0.1	0.06	2.2	0.1	<0.05	2	2.1	<0.2
1286263	Soil	17	0.22	1573	0.002	2	0.94	0.005	0.06	<0.1	0.19	3.2	0.2	0.06	3	2.1	<0.2
1286264	Soil	27	0.30	1148	0.002	4	1.08	0.007	0.13	0.2	0.25	3.9	0.3	<0.05	3	2.0	<0.2
1286265	Soil	18	0.22	985	0.001	3	0.98	0.008	0.08	<0.1	0.19	2.8	0.2	<0.05	3	2.9	<0.2
1286266	Soil	22	0.23	1055	0.001	<1	0.94	0.005	0.06	<0.1	0.15	2.5	0.1	<0.05	3	1.5	<0.2
1286267	Soil	12	0.17	337	0.002	1	0.62	0.013	0.06	<0.1	0.05	1.1	0.1	<0.05	2	0.8	<0.2
1286268	Soil	26	0.23	1040	<0.001	2	1.10	0.008	0.07	<0.1	0.20	3.3	0.2	<0.05	3	2.2	<0.2
1286269	Soil	11	0.11	195	0.002	<1	0.80	0.010	0.05	<0.1	0.03	1.0	0.2	<0.05	3	0.7	<0.2
1286270	Soil	18	0.22	340	0.001	1	0.90	0.003	0.05	<0.1	0.06	1.9	0.2	<0.05	3	1.3	<0.2
1286851	Soil	11	0.15	209	0.003	3	1.10	0.023	0.05	<0.1	0.13	1.8	0.1	<0.05	3	1.0	<0.2
1286852	Soil	18	0.07	219	0.002	2	0.85	0.006	0.07	<0.1	0.05	1.4	0.1	<0.05	4	0.8	<0.2
1286853	Soil	20	0.22	400	0.001	4	1.36	0.013	0.08	<0.1	0.26	3.6	0.2	0.11	4	1.9	<0.2
1286854	Soil	9	0.05	111	0.003	<1	0.63	0.005	0.05	<0.1	0.02	0.6	0.1	<0.05	4	0.5	<0.2
1286855	Soil	3	0.02	21	0.003	<1	0.22	0.027	0.02	<0.1	0.03	0.2	<0.1	<0.05	<1	<0.5	<0.2
1286856	Soil	6	0.03	169	0.004	2	0.35	0.030	0.04	<0.1	0.04	0.2	<0.1	<0.05	2	<0.5	<0.2
1286857	Soil	6	0.02	97	0.003	1	0.33	0.021	0.03	<0.1	0.04	0.2	<0.1	<0.05	2	<0.5	<0.2
1286858	Soil	9	0.04	98	0.010	2	0.32	0.016	0.03	<0.1	0.04	0.5	<0.1	<0.05	2	0.9	<0.2
1286859	Soil	8	0.04	70	0.007	1	0.48	0.019	0.04	0.1	0.04	0.5	<0.1	<0.05	3	<0.5	<0.2
1286860	Soil	8	0.04	408	0.002	3	0.60	0.030	0.05	<0.1	0.17	0.6	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1289101	Soil		7.7	46.5	14.2	199	0.8	44.9	10.5	569	2.43	27.6	7.9	1.8	67	2.0	4.4	0.2	88	0.54	0.109	9
1289102	Soil		5.9	39.3	12.0	192	0.8	36.5	8.4	224	2.10	16.5	5.7	1.7	69	1.9	3.3	0.2	90	0.56	0.109	8
1289103	Soil		6.3	40.0	11.5	173	0.7	35.7	5.7	156	2.17	17.8	4.2	1.9	55	1.3	3.6	0.1	87	0.23	0.089	9
1289104	Soil		4.9	14.1	13.7	164	0.1	23.7	5.0	117	2.49	17.8	2.2	2.1	19	0.5	2.2	0.2	96	0.08	0.038	10
1289105	Soil		4.1	25.7	12.7	187	0.5	34.3	8.5	188	2.32	17.9	5.4	1.8	47	1.6	2.5	0.2	74	0.68	0.090	9
1289106	Soil		5.7	26.0	19.0	231	0.2	39.4	9.8	314	3.03	27.6	2.6	1.2	27	2.0	3.2	0.2	90	0.14	0.114	10
1289107	Soil		9.1	38.9	23.6	231	0.3	46.0	8.3	207	3.26	39.6	7.4	2.4	41	1.4	4.4	0.2	114	0.11	0.077	11
1289108	Soil		6.8	20.6	16.0	110	0.3	24.8	5.6	122	2.02	19.6	2.1	2.4	24	0.3	2.0	0.2	93	0.09	0.037	14
1289109	Soil		7.8	45.1	16.4	184	0.2	39.9	7.8	169	2.61	23.2	4.7	2.6	26	0.6	3.5	0.2	69	0.07	0.053	14
1289110	Soil		5.5	34.8	17.8	136	0.3	30.7	7.6	260	3.14	17.2	1.8	0.7	18	0.9	1.9	0.2	62	0.03	0.083	7
1286751	Soil		4.6	54.3	18.4	135	0.1	26.9	9.2	281	4.48	11.1	2.5	0.6	23	0.6	1.9	0.3	91	0.10	0.107	9
1286752	Soil		0.9	17.7	3.3	31	<0.1	5.6	1.3	52	0.55	2.2	2.5	0.1	21	0.1	0.4	<0.1	22	0.33	0.042	4
1286753	Soil		2.2	42.4	6.9	140	<0.1	21.8	4.8	113	1.57	7.1	3.5	<0.1	11	0.5	1.1	0.1	43	0.06	0.061	5
1286754	Soil		2.8	39.4	8.4	56	0.7	15.6	3.3	184	1.04	6.3	7.5	0.5	77	0.3	1.9	0.1	68	1.33	0.134	9
1286755	Soil		4.4	23.1	12.7	74	0.5	15.6	3.1	77	2.13	16.3	3.7	1.3	13	0.3	2.0	0.2	73	0.02	0.063	9
1286756	Soil		3.5	10.8	6.6	21	1.0	4.6	0.6	12	1.47	25.6	0.8	0.8	4	<0.1	1.2	0.2	43	<0.01	0.025	6
1286757	Soil		6.5	30.9	17.7	75	1.7	13.9	2.6	70	1.78	15.3	4.1	0.6	16	0.2	2.5	0.2	79	0.02	0.060	10
1286758	Soil		2.2	39.5	8.0	49	2.1	12.1	2.2	54	1.26	10.1	3.6	0.2	13	0.4	2.4	0.1	35	0.05	0.047	5
1286759	Soil		16.0	31.3	21.7	235	1.2	60.8	7.6	95	4.08	20.9	3.7	0.8	172	0.3	3.3	0.2	60	0.17	0.145	10
1286760	Soil		3.3	16.9	15.1	89	0.2	20.2	5.4	173	2.76	12.4	1.0	1.2	25	0.2	1.5	0.2	53	0.11	0.033	10
1287921	Soil		16.3	54.5	19.6	312	0.4	60.8	13.3	512	2.37	21.6	4.8	2.9	54	2.2	4.5	0.2	134	0.55	0.237	20
1287922	Soil		3.3	21.0	3.0	80	0.2	18.7	2.2	256	0.48	4.0	2.4	0.2	152	2.0	2.3	<0.1	26	3.28	0.099	3
1287923	Soil		41.9	75.2	10.1	202	0.5	163.8	8.5	201	1.87	27.3	1.9	0.9	141	2.7	5.2	<0.1	145	3.51	0.098	18
1287924	Soil		11.4	14.3	5.7	91	0.1	26.6	2.7	66	0.80	10.7	<0.5	0.5	22	1.4	1.8	<0.1	78	0.33	0.029	9
1287925	Soil		11.6	45.2	17.3	177	0.7	53.5	5.7	127	1.88	13.4	2.6	0.6	44	1.4	2.6	0.1	121	0.34	0.113	13
1287926	Soil		11.4	43.3	12.8	814	0.6	81.9	8.3	284	2.03	14.4	2.7	1.6	89	9.2	3.0	0.1	78	1.15	0.155	14
1287927	Soil		67.6	61.5	20.4	407	4.6	98.9	8.9	180	3.16	287.7	99.6	3.0	187	2.3	56.6	0.3	1405	0.18	0.215	19
1287928	Soil		43.1	44.5	19.9	346	3.1	82.9	7.6	131	3.00	248.9	65.2	2.3	115	1.3	36.9	0.2	811	0.10	0.152	15
1287929	Soil		6.8	107.3	26.7	319	2.4	57.9	10.4	92	4.10	54.8	12.3	5.0	65	0.3	5.3	0.4	57	0.04	0.083	17
1287930	Soil		8.2	124.8	30.3	862	2.1	204.2	35.7	228	10.09	70.6	6.8	6.4	70	1.0	7.6	0.8	31	0.07	0.112	18

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1289101	Soil	23	0.20	3761	0.003	4	1.04	0.010	0.09	0.2	0.76	2.5	0.3	<0.05	3	1.4	<0.2
1289102	Soil	24	0.19	3378	0.003	5	1.02	0.009	0.12	<0.1	0.47	2.1	0.2	<0.05	3	1.0	<0.2
1289103	Soil	21	0.17	3549	0.004	4	0.97	0.011	0.09	0.1	0.43	2.1	0.3	<0.05	3	0.9	<0.2
1289104	Soil	23	0.21	1464	0.004	2	1.35	0.005	0.06	0.1	0.22	1.7	0.2	<0.05	4	0.6	<0.2
1289105	Soil	20	0.19	3426	0.003	3	1.01	0.007	0.07	0.1	0.24	2.3	0.1	<0.05	3	0.5	<0.2
1289106	Soil	26	0.18	1777	0.006	3	1.18	0.007	0.08	0.2	0.21	1.9	0.3	<0.05	4	0.9	<0.2
1289107	Soil	28	0.19	2360	0.004	3	1.17	0.006	0.11	0.1	0.26	2.1	0.4	<0.05	4	1.9	<0.2
1289108	Soil	22	0.15	1062	0.008	2	1.06	0.005	0.06	0.1	0.08	2.0	0.2	<0.05	4	1.2	<0.2
1289109	Soil	22	0.22	410	0.005	1	0.90	0.005	0.06	0.2	0.23	2.2	0.3	<0.05	3	1.7	<0.2
1289110	Soil	22	0.17	338	0.003	2	1.17	0.009	0.07	<0.1	0.08	1.2	0.2	<0.05	4	1.5	<0.2
1286751	Soil	31	0.76	357	0.014	7	1.74	0.008	0.27	<0.1	0.06	2.1	0.2	<0.05	7	1.4	<0.2
1286752	Soil	6	0.05	108	0.006	1	0.46	0.035	0.05	<0.1	0.02	0.3	<0.1	<0.05	2	<0.5	<0.2
1286753	Soil	14	0.05	94	0.005	2	0.44	0.018	0.08	<0.1	0.03	0.4	<0.1	<0.05	3	<0.5	<0.2
1286754	Soil	19	0.20	430	0.008	4	0.91	0.019	0.09	<0.1	0.21	1.1	0.1	0.10	3	1.0	<0.2
1286755	Soil	17	0.09	279	0.004	2	0.69	0.004	0.07	0.2	0.32	1.2	0.1	<0.05	4	0.6	<0.2
1286756	Soil	9	0.01	246	0.002	2	0.36	0.004	0.05	<0.1	0.02	0.4	<0.1	<0.05	2	<0.5	<0.2
1286757	Soil	16	0.06	248	0.004	2	0.67	0.007	0.07	0.2	0.14	1.0	0.2	<0.05	3	1.0	<0.2
1286758	Soil	12	0.03	402	0.004	1	0.55	0.017	0.04	<0.1	1.23	0.8	<0.1	<0.05	2	1.2	<0.2
1286759	Soil	21	0.16	583	0.004	2	0.84	0.018	0.06	<0.1	0.14	1.4	0.2	0.11	3	3.0	<0.2
1286760	Soil	22	0.18	2723	0.011	4	0.86	0.010	0.07	0.2	0.04	1.3	0.1	0.06	4	0.7	<0.2
1287921	Soil	24	0.13	1369	0.007	8	0.82	0.007	0.17	0.2	0.15	2.9	0.5	<0.05	2	1.6	<0.2
1287922	Soil	8	0.24	412	0.011	7	0.40	0.024	0.03	<0.1	0.10	0.6	<0.1	0.21	1	3.4	<0.2
1287923	Soil	27	1.20	525	0.004	7	0.56	0.007	0.09	0.2	0.48	3.1	1.7	0.05	2	2.6	<0.2
1287924	Soil	12	0.07	354	0.006	3	0.46	0.015	0.05	0.2	0.08	0.8	0.4	<0.05	2	<0.5	<0.2
1287925	Soil	23	0.12	2244	0.005	6	0.98	0.014	0.16	<0.1	0.25	1.5	0.4	<0.05	3	0.8	<0.2
1287926	Soil	16	0.20	1015	0.004	8	0.79	0.007	0.14	0.1	0.21	2.1	0.4	0.11	2	2.1	<0.2
1287927	Soil	89	0.17	1255	0.007	10	1.63	0.004	0.23	0.8	31.06	3.7	4.4	0.06	5	10.1	0.5
1287928	Soil	55	0.11	1229	0.006	7	1.18	0.006	0.18	0.5	13.13	2.6	2.3	0.08	4	6.3	0.4
1287929	Soil	15	0.04	881	0.003	4	0.71	0.007	0.23	0.2	0.69	2.9	0.4	0.23	2	2.6	0.2
1287930	Soil	13	0.03	336	0.003	3	1.41	0.006	0.18	0.2	0.52	8.9	0.5	0.26	1	2.1	0.4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287451	Soil	3.6	42.7	21.2	100	0.6	23.1	6.4	133	1.94	13.2	4.8	0.4	20	0.2	1.6	0.3	35	0.02	0.090	3
1287452	Soil	3.6	20.2	16.3	86	0.1	20.2	4.6	105	2.97	16.3	2.4	1.0	13	0.2	1.3	0.3	64	0.04	0.065	5
1287453	Soil	47.0	61.1	18.4	521	1.2	130.8	6.1	83	1.83	32.0	3.4	1.1	73	6.9	9.9	0.2	317	0.73	0.163	17
1287454	Soil	10.1	55.0	51.6	151	0.8	37.6	4.4	72	2.16	21.9	3.7	1.4	121	1.3	3.6	0.3	96	0.47	0.422	18
1287455	Soil	16.5	51.9	32.3	164	1.3	44.2	6.4	344	2.22	31.8	4.1	1.5	82	1.2	4.0	0.3	89	0.34	0.419	16
1287456	Soil	17.4	64.5	26.3	190	0.8	62.3	12.1	138	3.13	17.9	5.4	2.3	30	0.3	3.4	0.4	29	0.13	0.150	24
1287457	Soil	11.1	50.5	35.1	149	0.3	54.0	20.1	730	3.80	13.7	3.8	3.5	24	0.3	2.5	0.4	27	0.20	0.070	19
1287458	Soil	8.4	29.5	23.4	143	0.2	38.4	9.4	185	3.44	24.9	1.5	2.5	14	0.3	2.7	0.4	78	0.05	0.051	15
1287459	Soil	6.9	43.1	26.1	180	1.4	32.2	6.3	201	2.10	155.4	32.3	2.2	40	2.2	13.7	0.8	39	0.16	0.086	13
1287460	Soil	9.8	46.6	12.5	146	0.5	30.7	4.6	99	1.66	31.6	4.4	1.2	58	1.7	6.3	0.2	88	0.16	0.115	6
1286861	Soil	4.1	19.6	28.5	198	0.2	43.0	9.2	589	6.63	24.2	1.5	1.1	22	1.3	1.1	0.2	73	0.21	0.156	4
1286862	Soil	1.8	17.8	11.3	110	0.2	20.6	4.6	192	2.18	9.9	1.5	0.8	38	0.9	1.0	0.2	43	0.75	0.090	6
1286863	Soil	2.0	20.7	10.7	83	0.6	24.3	5.1	202	2.02	10.7	3.8	1.1	37	1.0	1.1	0.2	44	0.50	0.060	6
1286864	Soil	1.6	24.9	10.4	123	0.7	19.0	5.8	486	1.86	7.3	1.7	0.5	51	1.6	0.9	0.2	47	1.10	0.199	9
1286865	Soil	2.8	27.8	11.6	90	0.5	22.8	3.9	89	2.00	12.0	4.6	0.9	19	0.2	1.6	0.2	29	0.09	0.068	4
1286866	Soil	5.2	13.6	10.8	56	0.3	12.2	2.4	66	1.15	9.9	1.4	0.3	11	0.1	1.4	0.2	75	0.02	0.036	10
1286867	Soil	5.4	23.6	11.5	95	0.3	20.1	2.8	42	1.56	10.0	1.1	0.3	15	0.4	1.7	0.2	51	0.02	0.070	5
1286868	Soil	3.4	13.6	7.9	40	0.3	8.4	1.5	45	0.78	5.7	0.8	<0.1	10	0.2	0.8	0.2	47	0.02	0.043	9
1286869	Soil	3.5	15.1	7.0	42	0.6	9.3	1.8	25	1.41	9.4	<0.5	0.3	8	0.2	1.0	0.2	46	0.01	0.045	9
1286870	Soil	2.7	20.5	8.4	40	0.7	9.6	1.8	52	1.04	5.0	3.1	0.2	11	0.3	0.8	0.2	44	0.03	0.074	4
1286631	Soil	5.4	52.5	14.9	45	4.7	9.7	0.5	36	1.24	12.6	1.9	0.7	402	4.4	2.4	0.2	144	0.25	0.439	6
1286632	Soil	8.8	32.2	13.3	552	0.2	107.3	8.5	64	2.07	28.6	1.6	2.1	7	0.4	4.3	0.2	32	0.04	0.058	13
1286633	Soil	7.3	107.4	12.2	212	2.7	46.0	2.1	51	1.25	17.1	4.4	0.4	277	4.1	4.1	0.2	274	0.32	0.281	6
1286634	Soil	11.9	66.3	10.0	195	1.6	33.3	2.5	60	1.36	16.0	3.6	0.5	127	2.4	5.4	0.1	152	0.18	0.175	6
1286635	Soil	19.2	68.1	14.0	437	1.0	67.2	7.0	339	2.32	26.7	4.9	1.3	113	3.9	7.0	0.2	183	0.29	0.185	9
1286636	Soil	15.9	59.0	12.9	291	1.3	49.8	3.7	113	1.68	18.4	4.0	0.5	105	3.5	5.7	0.2	144	0.27	0.130	8
1286637	Soil	12.1	55.9	14.7	334	2.7	49.3	5.0	211	1.96	19.5	7.5	0.4	107	3.3	5.4	0.2	145	0.26	0.139	7
1286638	Soil	9.4	55.9	11.5	245	1.9	43.4	5.3	193	1.59	14.8	5.6	0.7	114	4.1	4.6	0.2	123	0.36	0.155	6
1286639	Soil	10.4	46.4	10.3	198	0.8	34.6	3.9	121	1.64	16.9	3.7	1.5	105	2.1	5.0	0.1	119	0.21	0.145	7
1286640	Soil	8.0	52.1	9.2	200	1.3	34.3	2.6	70	1.24	13.0	8.4	0.7	123	3.0	4.6	0.2	141	0.29	0.147	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287451	Soil	12	0.03	145	0.002	2	0.49	0.005	0.05	<0.1	0.04	1.5	0.2	0.08	2	1.3	<0.2
1287452	Soil	18	0.12	223	0.003	2	0.96	0.006	0.06	0.1	0.05	1.5	0.2	0.05	5	0.7	<0.2
1287453	Soil	30	0.11	456	0.004	5	0.55	0.004	0.10	0.3	0.65	2.7	1.2	0.09	2	2.9	<0.2
1287454	Soil	18	0.08	662	0.003	5	0.62	0.003	0.14	0.1	0.08	1.6	0.3	0.15	2	2.7	0.2
1287455	Soil	19	0.07	905	0.004	5	0.59	0.003	0.15	0.1	0.19	1.9	0.5	0.14	2	3.1	<0.2
1287456	Soil	8	0.06	619	0.002	4	0.50	0.002	0.15	<0.1	0.19	2.1	0.2	<0.05	1	2.7	<0.2
1287457	Soil	10	0.14	760	0.004	5	0.55	0.005	0.17	<0.1	0.05	3.2	0.2	<0.05	2	1.2	<0.2
1287458	Soil	19	0.29	202	0.014	2	1.27	0.007	0.08	0.4	0.02	1.7	0.3	<0.05	5	1.0	<0.2
1287459	Soil	17	0.09	469	<0.001	2	0.53	0.004	0.08	2.4	5.21	2.0	0.5	<0.05	2	3.7	<0.2
1287460	Soil	19	0.05	1242	0.001	3	0.41	0.002	0.06	0.2	0.80	2.3	0.3	<0.05	1	2.6	<0.2
1286861	Soil	32	0.08	219	0.002	1	0.73	0.005	0.05	<0.1	0.06	3.2	0.1	<0.05	3	1.7	<0.2
1286862	Soil	17	0.12	569	0.002	2	1.00	0.007	0.06	<0.1	0.04	2.0	0.1	<0.05	4	0.7	<0.2
1286863	Soil	18	0.12	702	0.001	2	0.93	0.004	0.04	<0.1	0.12	2.5	0.1	<0.05	3	0.6	<0.2
1286864	Soil	20	0.12	600	0.004	2	1.13	0.009	0.06	<0.1	0.10	1.6	0.2	0.12	3	<0.5	<0.2
1286865	Soil	12	0.09	164	<0.001	1	0.49	0.004	0.05	<0.1	0.05	1.5	0.1	<0.05	2	1.0	<0.2
1286866	Soil	12	0.05	122	0.004	<1	0.69	0.004	0.05	0.1	0.01	0.6	0.2	<0.05	4	0.7	<0.2
1286867	Soil	11	0.03	190	0.002	<1	0.54	0.005	0.05	<0.1	0.02	0.8	0.2	<0.05	3	1.1	<0.2
1286868	Soil	9	0.03	145	0.004	1	0.63	0.009	0.05	<0.1	<0.01	0.2	0.2	<0.05	4	<0.5	<0.2
1286869	Soil	8	0.02	106	0.002	1	0.34	0.004	0.04	0.1	<0.01	0.2	0.2	<0.05	3	0.8	<0.2
1286870	Soil	12	0.05	262	0.002	2	0.67	0.013	0.06	<0.1	0.06	0.5	0.2	<0.05	3	0.6	<0.2
1286631	Soil	60	0.03	1478	0.002	8	0.73	0.002	0.09	<0.1	0.48	1.8	1.0	0.09	2	6.3	<0.2
1286632	Soil	9	0.02	184	<0.001	3	0.29	0.001	0.07	<0.1	0.28	1.7	0.3	<0.05	<1	1.9	<0.2
1286633	Soil	47	0.04	779	0.003	6	0.63	0.003	0.09	0.1	0.98	1.0	0.7	<0.05	2	5.6	<0.2
1286634	Soil	22	0.04	670	0.003	5	0.51	0.004	0.09	<0.1	0.72	1.4	0.4	<0.05	2	4.2	<0.2
1286635	Soil	25	0.09	1159	0.002	7	0.72	0.003	0.12	0.1	1.00	2.6	0.5	<0.05	2	4.4	<0.2
1286636	Soil	22	0.07	1133	0.003	5	0.58	0.004	0.10	<0.1	1.00	1.8	0.5	<0.05	2	3.9	<0.2
1286637	Soil	29	0.10	1357	0.002	5	0.74	0.008	0.11	0.1	1.44	2.1	0.6	0.05	3	3.6	<0.2
1286638	Soil	23	0.10	1495	0.002	8	0.69	0.005	0.11	<0.1	0.94	2.4	0.5	0.08	2	3.9	<0.2
1286639	Soil	21	0.07	1182	0.003	6	0.51	0.002	0.09	<0.1	0.39	2.1	0.3	<0.05	2	3.9	<0.2
1286640	Soil	24	0.05	944	0.003	6	0.50	0.007	0.10	<0.1	0.49	1.7	0.5	0.08	2	4.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283361	Soil	66.8	117.3	52.5	253	4.4	61.0	8.5	127	2.50	39.2	3.8	0.5	110	5.7	11.5	0.3	609	0.37	0.302	16
1283362	Soil	56.2	124.0	74.5	203	4.6	63.1	5.8	141	2.61	39.0	4.4	0.4	206	3.9	9.8	0.3	512	0.41	0.385	17
1283363	Soil	22.4	78.3	46.2	123	2.0	35.8	4.8	267	1.98	26.6	2.9	0.3	177	1.5	5.3	0.3	194	0.17	0.317	19
1283364	Soil	7.4	85.9	21.9	328	1.3	85.0	11.0	190	2.75	23.4	3.1	3.3	29	1.1	3.4	0.2	56	0.40	0.174	22
1283365	Soil	6.4	25.5	9.2	112	0.3	26.9	3.6	126	1.32	13.9	1.3	0.3	13	0.4	1.7	0.2	48	0.08	0.125	11
1283366	Soil	6.2	54.2	14.3	195	0.4	58.8	10.2	454	2.61	57.7	2.7	0.8	23	1.2	3.4	0.2	43	0.23	0.106	11
1283367	Soil	4.3	35.2	24.2	103	0.1	34.1	18.3	2781	2.62	16.6	0.6	0.4	14	0.5	1.8	0.4	29	0.12	0.086	13
1283368	Soil	7.0	94.5	45.4	234	1.2	77.8	9.7	279	2.82	39.9	5.0	1.2	145	0.6	3.4	0.4	75	1.06	0.602	22
1283369	Soil	8.8	255.8	27.4	379	2.0	181.3	10.1	303	2.82	42.6	5.5	1.7	74	1.4	6.4	0.3	119	0.50	0.331	21
1283370	Soil	11.7	39.9	25.0	151	0.4	43.9	6.1	113	1.98	21.7	1.3	0.5	20	0.6	3.1	0.3	91	0.06	0.108	11
1289361	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1289362	Soil	2.8	21.6	8.4	68	1.3	20.8	2.5	43	1.00	6.3	8.1	0.7	23	0.7	0.9	0.3	32	0.13	0.060	3
1289363	Soil	0.7	19.0	4.7	23	0.2	12.1	1.9	114	0.50	2.6	1.8	0.2	76	0.5	0.5	0.2	13	1.69	0.056	2
1289364	Soil	3.9	13.4	7.5	34	0.1	7.8	1.9	30	0.74	6.6	0.7	0.1	9	<0.1	0.7	0.1	39	0.04	0.030	8
1289365	Soil	3.0	14.3	6.3	43	0.2	9.5	1.8	32	0.78	7.1	0.5	0.2	8	0.1	0.9	0.1	38	0.04	0.033	4
1289366	Soil	5.0	15.8	20.5	59	<0.1	14.3	2.5	66	1.56	19.2	2.0	0.3	11	0.3	2.9	0.2	41	0.04	0.051	4
1289367	Soil	0.6	2.0	6.0	11	<0.1	2.2	0.3	12	0.20	6.0	<0.5	0.3	11	0.2	0.7	<0.1	11	0.13	0.011	2
1289368	Soil	1.7	17.9	5.4	258	0.3	28.0	9.9	528	3.81	4.6	<0.5	0.2	121	12.2	0.8	0.1	44	3.57	0.214	11
1289369	Soil	2.5	18.6	10.5	119	0.3	22.6	5.3	161	2.17	10.0	<0.5	1.0	29	1.2	1.3	0.2	70	0.51	0.068	9
1289370	Soil	0.4	7.3	2.1	24	<0.1	6.0	1.7	124	0.59	1.6	<0.5	0.1	38	1.0	0.2	<0.1	15	0.97	0.043	3
1287871	Soil	3.6	51.4	21.1	114	0.6	35.7	9.1	415	3.39	31.0	5.9	2.3	86	0.2	2.3	0.3	34	0.05	0.090	4
1287873	Soil	2.1	34.0	24.5	118	0.2	39.7	15.3	461	3.92	22.3	2.3	3.4	55	0.3	1.3	0.3	30	0.07	0.095	5
1287874	Soil	2.4	42.0	22.4	114	0.4	37.5	9.1	222	3.75	18.5	2.5	2.3	74	0.3	1.3	0.3	32	0.03	0.101	4
1287875	Soil	2.5	47.2	18.9	85	0.8	36.7	6.9	446	2.59	11.2	2.0	1.1	47	0.3	0.9	0.3	43	0.09	0.185	6
1287876	Soil	2.4	23.3	15.0	77	0.2	20.3	5.3	264	2.48	12.6	0.8	0.9	18	0.2	1.1	0.2	41	0.02	0.100	6
1287877	Soil	1.8	34.1	21.6	80	0.3	22.9	6.0	243	3.21	10.5	3.1	2.0	42	0.1	0.8	0.3	32	0.03	0.112	4
1287878	Soil	1.6	38.2	20.2	128	0.3	35.2	12.2	958	4.63	10.5	3.5	2.3	63	0.1	0.7	0.3	27	0.02	0.091	3
1287879	Soil	1.7	57.6	18.6	115	0.3	35.5	8.6	716	3.51	9.4	4.1	1.6	59	0.2	0.7	0.3	23	0.04	0.077	3
1287880	Soil	1.5	36.5	13.6	72	0.7	21.1	4.6	175	2.12	6.4	2.7	0.7	48	0.2	0.7	0.2	21	0.06	0.077	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283361	Soil	27	0.05	459	0.004	6	0.55	0.004	0.19	0.4	0.27	1.0	0.6	0.31	2	5.7	0.4
1283362	Soil	31	0.09	477	0.003	7	0.67	0.008	0.19	0.4	0.28	1.0	0.7	0.27	3	6.0	0.4
1283363	Soil	21	0.04	459	0.003	4	0.59	0.010	0.12	0.2	0.14	0.4	0.5	0.21	2	3.5	0.2
1283364	Soil	16	0.06	444	0.002	6	0.43	0.003	0.13	<0.1	0.27	4.5	0.2	<0.05	1	2.1	<0.2
1283365	Soil	11	0.04	269	0.001	3	0.46	0.006	0.07	<0.1	0.04	0.5	0.2	<0.05	2	0.8	<0.2
1283366	Soil	12	0.05	698	0.002	3	0.36	0.004	0.06	<0.1	0.16	2.7	0.2	<0.05	<1	1.3	<0.2
1283367	Soil	7	0.04	446	0.004	2	0.31	0.011	0.08	<0.1	0.05	0.7	0.2	0.08	1	0.8	0.2
1283368	Soil	23	0.10	1060	0.004	11	0.70	0.004	0.22	<0.1	0.27	2.4	0.2	0.11	2	2.4	0.3
1283369	Soil	20	0.09	505	0.002	9	0.54	0.002	0.20	0.1	1.53	3.4	0.6	0.11	1	3.6	0.3
1283370	Soil	11	0.03	316	0.003	4	0.37	0.006	0.10	0.1	0.12	0.8	0.2	0.10	1	0.9	<0.2
1289361	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1289362	Soil	12	0.07	446	0.004	5	0.56	0.017	0.06	<0.1	0.36	1.4	0.2	<0.05	2	0.8	<0.2
1289363	Soil	6	0.08	266	0.011	4	0.36	0.023	0.02	<0.1	0.11	0.4	<0.1	0.18	1	2.0	<0.2
1289364	Soil	10	0.02	147	0.006	2	0.40	0.009	0.03	<0.1	0.02	0.3	<0.1	0.06	3	<0.5	<0.2
1289365	Soil	9	0.02	126	0.003	3	0.32	0.009	0.04	<0.1	0.02	0.4	<0.1	<0.05	2	0.5	<0.2
1289366	Soil	10	0.02	108	0.002	3	0.30	0.005	0.04	<0.1	0.03	0.5	0.1	0.05	2	<0.5	<0.2
1289367	Soil	5	0.03	163	<0.001	<1	0.28	0.003	0.03	<0.1	0.08	0.3	<0.1	<0.05	<1	<0.5	<0.2
1289368	Soil	25	0.16	467	0.008	3	0.70	0.009	0.01	<0.1	0.07	1.0	<0.1	0.23	1	1.3	<0.2
1289369	Soil	25	0.12	688	0.003	2	1.27	0.005	0.05	<0.1	0.09	1.9	0.2	0.06	3	0.7	<0.2
1289370	Soil	6	0.06	141	0.014	2	0.51	0.027	0.02	<0.1	0.02	0.3	<0.1	0.11	1	0.5	<0.2
1287871	Soil	25	0.27	798	0.001	2	1.03	0.010	0.07	<0.1	0.53	2.8	0.1	0.12	3	2.5	<0.2
1287873	Soil	25	0.39	323	0.003	<1	1.20	0.011	0.07	<0.1	0.23	3.4	0.1	0.06	4	0.8	<0.2
1287874	Soil	25	0.33	585	0.002	1	1.13	0.011	0.07	<0.1	0.17	3.0	0.1	0.09	3	0.9	<0.2
1287875	Soil	21	0.18	258	0.002	2	1.53	0.011	0.08	<0.1	0.17	2.6	0.2	0.06	4	0.9	<0.2
1287876	Soil	19	0.21	151	0.002	2	0.96	0.006	0.06	<0.1	0.05	1.1	0.1	<0.05	4	0.9	<0.2
1287877	Soil	26	0.31	224	0.002	1	1.35	0.008	0.07	<0.1	0.12	2.3	0.1	<0.05	4	0.6	<0.2
1287878	Soil	26	0.33	524	0.002	2	1.38	0.010	0.06	<0.1	0.08	3.1	0.1	0.08	4	0.5	<0.2
1287879	Soil	24	0.21	1027	0.002	3	1.08	0.013	0.07	<0.1	0.08	2.8	0.1	0.09	3	0.7	<0.2
1287880	Soil	18	0.09	868	0.003	3	0.67	0.015	0.06	<0.1	0.10	1.7	<0.1	0.08	2	0.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1289131	Soil	2.3	52.3	9.4	90	0.3	21.0	4.2	150	2.04	7.3	4.5	0.5	18	0.2	1.0	0.2	44	0.07	0.058	4
REP 1289131	QC	2.3	52.1	9.4	90	0.3	20.4	4.1	151	2.05	7.6	4.5	0.5	18	0.2	0.9	0.2	44	0.07	0.058	4
1289139	Soil	2.7	73.8	15.9	154	1.6	54.3	16.7	185	2.33	13.3	7.7	1.5	52	0.5	1.0	0.3	74	0.33	0.118	8
REP 1289139	QC	2.8	72.2	15.3	153	1.6	52.3	15.9	180	2.28	13.8	6.9	1.4	50	0.5	1.0	0.2	76	0.33	0.115	8
1286656	Soil	5.0	48.1	10.0	186	1.1	40.8	6.4	248	1.82	12.5	4.3	1.7	74	1.9	3.2	0.2	90	0.56	0.114	8
REP 1286656	QC	5.0	46.7	9.6	185	1.1	39.2	6.1	237	1.75	12.3	5.1	1.6	64	1.8	3.1	0.2	89	0.54	0.111	8
1287256	Soil	45.5	65.5	12.1	1464	1.3	222.5	10.5	625	2.46	33.4	4.4	1.7	31	13.0	9.1	0.2	177	0.51	0.103	17
REP 1287256	QC	45.9	64.7	12.0	1473	1.3	221.5	10.5	626	2.50	33.6	3.3	1.7	31	12.9	9.3	0.2	192	0.51	0.105	18
1286677	Soil	4.5	59.3	11.2	205	1.2	41.6	6.7	429	1.60	13.5	6.4	0.8	63	4.3	3.1	0.2	65	0.81	0.099	7
REP 1286677	QC	4.3	59.5	11.3	208	1.1	41.6	6.8	428	1.60	13.4	6.9	0.8	62	4.3	3.1	0.2	60	0.84	0.100	7
1288613	Soil	31.2	57.2	28.0	383	2.3	100.1	11.9	319	3.02	68.8	8.4	1.3	41	2.7	19.1	0.2	231	0.10	0.142	15
REP 1288613	QC	30.6	56.8	27.4	385	2.3	99.2	11.7	312	2.97	69.2	9.2	1.5	43	2.8	19.8	0.2	235	0.09	0.140	15
1289125	Soil	4.1	65.7	13.8	81	0.3	12.4	2.7	51	1.82	13.2	1.9	0.3	27	0.2	1.1	0.2	46	0.06	0.061	6
REP 1289125	QC	4.1	62.4	13.9	74	0.3	12.7	2.7	51	1.81	13.0	1.4	0.3	26	0.2	1.1	0.2	45	0.06	0.060	6
1286270	Soil	7.1	32.3	18.2	178	0.1	40.5	11.5	233	2.85	24.9	2.1	2.2	26	0.6	2.4	0.2	52	0.12	0.084	7
REP 1286270	QC	6.9	31.7	17.6	172	0.1	39.6	10.9	237	2.90	24.3	2.2	2.1	25	0.6	2.6	0.2	51	0.12	0.083	7
1286855	Soil	0.4	4.5	2.4	7	0.2	1.6	0.7	20	0.46	1.0	<0.5	<0.1	5	<0.1	<0.1	<0.1	5	0.02	0.038	<1
REP 1286855	QC	0.3	4.5	2.3	7	0.2	1.9	0.7	19	0.47	1.0	<0.5	<0.1	5	<0.1	<0.1	<0.1	6	0.02	0.043	<1
1287923	Soil	41.9	75.2	10.1	202	0.5	163.8	8.5	201	1.87	27.3	1.9	0.9	141	2.7	5.2	<0.1	145	3.51	0.098	18
REP 1287923	QC	39.6	73.6	10.4	210	0.5	162.6	8.0	188	1.78	26.1	2.0	0.9	135	2.9	4.8	<0.1	153	3.48	0.098	18
1287458	Soil	8.4	29.5	23.4	143	0.2	38.4	9.4	185	3.44	24.9	1.5	2.5	14	0.3	2.7	0.4	78	0.05	0.051	15
REP 1287458	QC	8.4	30.2	23.7	147	0.2	39.7	9.6	182	3.42	25.0	1.8	2.3	13	0.3	2.7	0.4	77	0.04	0.051	15
1286632	Soil	8.8	32.2	13.3	552	0.2	107.3	8.5	64	2.07	28.6	1.6	2.1	7	0.4	4.3	0.2	32	0.04	0.058	13
REP 1286632	QC	8.5	32.1	12.9	551	0.2	107.8	8.4	64	2.07	27.9	1.5	2.2	10	0.3	4.2	0.2	33	0.03	0.058	13
1283369	Soil	8.8	255.8	27.4	379	2.0	181.3	10.1	303	2.82	42.6	5.5	1.7	74	1.4	6.4	0.3	119	0.50	0.331	21
REP 1283369	QC	8.8	243.9	28.0	381	2.1	185.7	10.3	307	2.81	42.9	4.7	1.9	76	1.5	6.8	0.3	125	0.52	0.353	21
1287877	Soil	1.8	34.1	21.6	80	0.3	22.9	6.0	243	3.21	10.5	3.1	2.0	42	0.1	0.8	0.3	32	0.03	0.112	4
REP 1287877	QC	1.8	34.9	21.1	78	0.3	24.1	5.9	240	3.16	11.5	2.5	2.0	44	0.1	0.8	0.3	32	0.03	0.112	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001884.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1289131	Soil	19	0.14	923	0.002	1	0.73	0.005	0.06	<0.1	0.18	1.6	0.1	<0.05	3	0.6	<0.2
REP 1289131	QC	19	0.15	915	0.002	1	0.74	0.005	0.05	<0.1	0.16	1.7	0.1	<0.05	4	0.7	<0.2
1289139	Soil	33	0.32	1102	0.003	3	1.72	0.009	0.10	0.1	0.46	3.9	0.3	0.15	4	3.0	<0.2
REP 1289139	QC	33	0.32	1093	0.004	3	1.72	0.009	0.10	<0.1	0.44	3.9	0.3	0.13	4	3.1	<0.2
1286656	Soil	20	0.15	1545	0.003	4	0.68	0.006	0.08	0.1	0.58	2.4	0.3	0.08	2	3.2	<0.2
REP 1286656	QC	19	0.15	1571	0.003	4	0.67	0.006	0.09	0.1	0.58	2.3	0.3	0.07	2	2.9	<0.2
1287256	Soil	19	0.16	464	0.002	3	0.43	0.002	0.08	0.2	1.03	3.3	2.9	<0.05	1	3.2	<0.2
REP 1287256	QC	21	0.17	471	0.003	4	0.47	0.002	0.08	0.2	1.05	3.4	3.0	<0.05	1	3.2	<0.2
1286677	Soil	15	0.11	901	0.005	4	0.68	0.013	0.06	0.1	0.75	2.6	0.3	0.10	2	5.4	<0.2
REP 1286677	QC	14	0.11	897	0.004	4	0.65	0.012	0.06	<0.1	0.75	2.5	0.2	0.09	2	5.2	<0.2
1288613	Soil	56	0.08	996	0.005	4	0.78	0.006	0.11	0.6	1.67	2.5	1.3	0.09	3	5.1	<0.2
REP 1288613	QC	56	0.07	1032	0.006	5	0.75	0.006	0.11	0.6	1.70	2.7	1.3	0.06	2	5.6	<0.2
1289125	Soil	16	0.06	346	0.003	2	0.61	0.006	0.06	0.1	0.15	0.7	0.1	<0.05	4	1.5	<0.2
REP 1289125	QC	17	0.06	331	0.003	1	0.59	0.005	0.05	<0.1	0.11	0.7	0.1	<0.05	4	1.4	<0.2
1286270	Soil	18	0.22	340	0.001	1	0.90	0.003	0.05	<0.1	0.06	1.9	0.2	<0.05	3	1.3	<0.2
REP 1286270	QC	19	0.23	338	0.001	2	0.95	0.003	0.05	<0.1	0.07	1.9	0.2	<0.05	3	1.5	<0.2
1286855	Soil	3	0.02	21	0.003	<1	0.22	0.027	0.02	<0.1	0.03	0.2	<0.1	<0.05	<1	<0.5	<0.2
REP 1286855	QC	3	0.02	23	0.003	<1	0.22	0.026	0.02	<0.1	0.03	0.1	<0.1	<0.05	<1	<0.5	<0.2
1287923	Soil	27	1.20	525	0.004	7	0.56	0.007	0.09	0.2	0.48	3.1	1.7	0.05	2	2.6	<0.2
REP 1287923	QC	27	1.18	531	0.005	6	0.59	0.008	0.10	0.2	0.45	3.2	1.8	0.07	2	1.8	<0.2
1287458	Soil	19	0.29	202	0.014	2	1.27	0.007	0.08	0.4	0.02	1.7	0.3	<0.05	5	1.0	<0.2
REP 1287458	QC	19	0.28	204	0.013	2	1.24	0.007	0.07	0.5	0.03	1.6	0.3	<0.05	5	1.3	<0.2
1286632	Soil	9	0.02	184	<0.001	3	0.29	0.001	0.07	<0.1	0.28	1.7	0.3	<0.05	<1	1.9	<0.2
REP 1286632	QC	9	0.02	183	0.001	3	0.28	0.001	0.07	<0.1	0.28	1.6	0.3	<0.05	<1	2.1	<0.2
1283369	Soil	20	0.09	505	0.002	9	0.54	0.002	0.20	0.1	1.53	3.4	0.6	0.11	1	3.6	0.3
REP 1283369	QC	22	0.09	518	0.003	7	0.54	0.002	0.21	0.2	1.59	3.7	0.6	0.11	1	3.7	0.2
1287877	Soil	26	0.31	224	0.002	1	1.35	0.008	0.07	<0.1	0.12	2.3	0.1	<0.05	4	0.6	<0.2
REP 1287877	QC	26	0.31	230	0.002	2	1.35	0.009	0.07	<0.1	0.10	2.4	0.1	<0.05	4	0.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001884.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
Reference Materials																					
STD DS8	Standard	13.7	116.3	133.0	324	1.9	39.3	7.8	653	2.64	28.2	114.8	6.4	70	2.5	5.8	6.4	44	0.75	0.081	16
STD DS8	Standard	12.9	99.5	134.1	296	1.9	39.1	7.7	594	2.42	21.9	117.7	5.8	54	1.9	4.5	5.4	46	0.67	0.066	14
STD DS8	Standard	14.3	103.6	140.9	310	1.8	41.4	8.1	651	2.62	24.9	118.8	6.3	58	2.0	4.6	5.6	49	0.74	0.073	15
STD DS8	Standard	13.2	110.6	122.7	305	1.7	38.3	7.4	617	2.45	25.5	111.6	7.5	74	2.0	5.5	6.1	43	0.70	0.077	18
STD DS8	Standard	13.0	101.2	117.7	293	1.7	35.7	7.0	583	2.35	24.2	108.7	6.9	67	2.2	5.1	6.0	41	0.69	0.075	17
STD DS8	Standard	13.6	112.0	124.1	318	1.9	38.3	8.0	620	2.47	27.2	126.7	6.8	68	2.4	5.9	6.4	43	0.69	0.076	16
STD DS8	Standard	12.6	107.4	118.1	313	1.8	35.3	7.4	577	2.34	28.0	118.6	6.2	68	2.2	5.7	5.8	39	0.66	0.075	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001884.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
Reference Materials																	
STD DS8	Standard	123	0.64	291	0.128	3	0.97	0.101	0.45	3.1	0.19	3.0	5.5	0.15	5	5.6	5.0
STD DS8	Standard	120	0.61	249	0.102	2	0.89	0.103	0.41	2.9	0.19	2.0	5.4	0.17	5	4.8	5.0
STD DS8	Standard	129	0.65	271	0.110	2	1.02	0.099	0.45	3.0	0.20	2.3	5.6	0.22	5	5.3	5.1
STD DS8	Standard	123	0.61	285	0.138	2	0.96	0.098	0.40	2.8	0.19	2.5	5.4	0.16	5	4.4	5.7
STD DS8	Standard	111	0.57	271	0.115	3	0.85	0.092	0.39	2.7	0.17	2.3	5.1	0.14	5	4.7	4.7
STD DS8	Standard	121	0.57	274	0.123	3	0.92	0.099	0.45	3.0	0.20	2.1	5.3	0.18	5	4.9	5.1
STD DS8	Standard	108	0.59	276	0.115	4	0.87	0.092	0.43	2.7	0.19	2.0	5.0	0.13	5	6.4	4.8
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 22, 2011
Report Date: December 05, 2011
Page: 1 of 9

CERTIFICATE OF ANALYSIS WHI11001945.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #30
P.O. Number
Number of Samples:

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	236	Sieve soil to 230 mesh			VAN
RJSV	236	Saving all or part of Soil Reject			VAN
1DX2	233	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1279101	Soil		9.0	50.5	61.1	99	5.3	13.6	3.0	48	6.68	646.4	133.9	1.5	21	0.4	44.7	3.4	45	0.06	0.173	17
1279102	Soil		15.5	71.0	95.0	152	5.2	15.1	3.5	43	12.22	1375	257.3	5.9	81	0.3	94.1	4.6	58	0.02	0.205	22
1279103	Soil		13.1	46.6	112.5	126	7.1	13.2	2.7	22	11.77	1851	553.2	10.6	163	0.4	156.5	5.2	54	0.01	0.230	25
1279104	Soil		6.2	40.2	85.3	325	5.0	37.6	6.6	21	14.07	2172	757.4	12.2	164	0.5	177.6	4.5	48	0.02	0.274	26
1279105	Soil		2.8	82.4	39.0	359	3.4	48.2	6.6	18	23.18	1442	628.3	12.5	36	0.6	123.6	4.4	46	0.03	0.201	17
1279106	Soil		6.5	53.9	110.1	116	4.4	18.5	4.2	68	10.05	1760	286.6	11.8	119	0.4	98.8	3.4	40	0.02	0.204	23
1288701	Soil		42.4	57.7	12.8	485	2.3	111.8	8.9	211	1.48	96.0	5.0	1.1	87	22.7	23.9	0.2	333	0.07	0.084	13
1288702	Soil		30.7	42.4	15.6	430	2.4	62.8	3.1	75	2.02	92.5	3.7	1.9	109	21.6	25.5	0.3	267	0.13	0.086	12
1288703	Soil		23.0	40.1	15.7	348	1.4	77.9	7.9	201	3.09	60.7	5.3	1.0	32	1.4	9.6	0.3	136	0.13	0.146	16
1288704	Soil		91.0	36.1	24.2	140	4.9	19.6	2.1	60	2.41	92.7	4.0	2.7	89	1.1	75.6	0.5	185	0.03	0.137	17
1288705	Soil		63.8	38.4	31.7	45	4.4	9.0	1.0	31	1.83	65.4	3.3	3.5	63	1.0	52.1	0.5	114	0.03	0.119	16
1288706	Soil		95.1	45.3	29.5	122	4.5	23.7	1.6	36	2.44	110.3	7.1	4.0	127	1.2	97.6	0.5	194	0.05	0.167	21
1288707	Soil		191.6	66.6	13.7	181	1.7	213.5	6.0	17	2.20	140.6	2.9	2.0	48	0.9	83.4	0.2	219	0.08	0.049	7
1288708	Soil		38.6	42.7	14.2	82	2.8	23.9	1.5	17	1.20	48.3	6.7	0.5	70	0.8	26.4	0.3	176	0.03	0.113	13
1288709	Soil		57.0	43.2	17.9	135	2.8	26.7	2.0	25	1.61	74.8	7.0	0.5	96	1.2	37.4	0.3	233	0.03	0.128	15
1288710	Soil		90.5	81.2	24.6	53	4.1	16.5	0.7	20	2.09	308.0	17.4	1.3	228	9.1	50.8	0.3	320	0.04	0.255	16
1288711	Soil		71.2	79.1	19.2	45	2.9	8.5	0.6	14	1.41	164.2	19.0	1.3	216	3.1	39.9	0.2	258	0.05	0.157	17
1288712	Soil		35.1	22.9	87.4	68	2.5	5.4	0.5	19	1.67	236.8	245.1	19.7	509	2.5	112.4	0.6	125	0.06	0.192	87
1288713	Soil		37.0	24.2	92.4	71	2.7	6.0	0.6	22	1.75	263.3	295.3	18.4	483	2.6	114.1	0.6	131	0.06	0.202	91
1288714	Soil		25.8	68.6	119.8	22	4.8	4.9	0.5	9	0.77	62.6	33.0	2.7	137	0.6	61.3	0.3	186	0.03	0.078	17
1288715	Soil		19.8	70.6	245.9	11	7.1	2.8	0.2	4	0.69	30.2	9.2	2.5	99	1.2	51.5	0.6	116	0.02	0.040	10
1288716	Soil		61.9	50.7	206.1	98	3.1	21.2	1.8	38	3.34	240.2	26.2	4.7	239	1.5	81.7	0.5	207	0.06	0.146	9
1288717	Soil		51.4	41.4	120.8	91	2.8	17.5	2.2	44	2.82	261.0	29.2	2.6	151	1.4	85.0	0.4	220	0.04	0.112	11
1288718	Soil		83.9	74.3	155.9	91	6.1	21.8	1.6	49	2.91	330.5	26.8	4.1	155	2.4	73.1	0.4	424	0.05	0.282	12
1288719	Soil		87.4	81.0	179.0	79	6.6	19.3	1.4	50	2.90	353.9	27.9	4.8	158	3.4	82.0	0.4	482	0.05	0.308	15
1288720	Soil		43.2	51.7	73.5	210	3.2	53.2	5.4	170	2.50	232.3	72.1	3.1	102	1.5	62.6	0.4	277	0.11	0.207	19
1281921	Soil		40.6	68.3	15.6	314	0.6	118.3	8.1	101	1.91	25.3	2.6	0.8	57	2.2	4.9	0.2	59	0.53	0.166	12
1281922	Soil		19.1	21.4	15.0	67	0.5	18.9	2.6	35	1.05	13.2	1.1	0.2	14	<0.1	3.3	0.2	103	0.02	0.050	12
1281923	Soil		1.0	2.4	1.9	7	0.6	2.1	0.4	9	0.18	0.7	<0.5	<0.1	5	<0.1	0.2	<0.1	9	0.03	0.039	1
1281924	Soil		7.0	13.8	14.0	43	0.2	12.3	2.3	65	1.03	9.1	0.6	0.3	21	<0.1	1.4	0.2	52	0.03	0.100	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1279101	Soil	15	0.04	166	0.005	6	0.81	0.006	0.10	1.3	16.35	0.6	1.9	0.19	5	13.8	0.4
1279102	Soil	21	0.08	328	0.009	5	0.71	0.014	0.29	1.7	27.87	1.6	5.0	0.67	5	25.0	0.4
1279103	Soil	20	0.05	118	0.003	7	0.60	0.017	0.42	1.7	31.57	2.1	7.9	1.45	4	26.3	0.4
1279104	Soil	28	0.03	84	0.003	16	0.80	0.013	0.57	3.0	28.19	3.4	3.2	2.12	5	21.0	<0.2
1279105	Soil	19	0.03	157	0.004	15	0.94	0.005	0.18	3.5	>50	2.6	1.5	0.46	7	21.8	0.2
1279106	Soil	14	0.10	107	0.005	11	0.65	0.022	0.51	10.6	23.57	2.7	5.0	1.53	3	11.7	<0.2
1288701	Soil	26	0.03	718	0.003	7	0.55	0.004	0.14	1.1	2.17	1.7	3.1	0.23	2	7.0	<0.2
1288702	Soil	38	0.03	481	0.007	10	0.48	0.004	0.23	1.0	1.93	1.7	4.3	0.53	2	9.3	<0.2
1288703	Soil	18	0.06	616	0.007	4	0.54	0.006	0.08	0.5	0.79	1.1	0.8	0.07	2	4.6	<0.2
1288704	Soil	23	0.02	495	0.003	7	0.44	0.003	0.23	3.9	1.43	1.9	12.6	0.47	3	94.4	0.7
1288705	Soil	21	0.02	539	0.003	7	0.35	0.003	0.24	2.5	1.04	2.0	14.2	0.47	2	90.5	0.7
1288706	Soil	34	0.02	975	0.004	10	0.38	0.003	0.28	4.4	1.30	2.3	14.4	0.54	3	97.7	0.9
1288707	Soil	19	0.01	408	0.001	4	0.22	0.002	0.07	2.0	1.28	3.1	4.6	0.11	<1	15.5	0.4
1288708	Soil	20	0.02	331	0.003	4	0.51	0.011	0.09	1.3	3.35	0.7	2.8	0.12	3	14.4	0.2
1288709	Soil	31	0.03	400	0.003	6	0.50	0.009	0.12	3.9	3.61	0.8	3.8	0.17	3	21.0	0.4
1288710	Soil	39	0.02	426	0.005	6	0.64	0.006	0.16	2.8	6.55	2.3	7.5	0.27	5	>100	0.5
1288711	Soil	32	0.02	401	0.003	5	0.48	0.007	0.14	3.4	3.88	1.9	6.8	0.25	4	73.0	0.5
1288712	Soil	21	0.01	307	0.001	6	0.53	0.004	0.18	2.9	>50	1.1	6.6	0.35	3	20.7	0.6
1288713	Soil	28	0.02	362	0.001	8	0.54	0.004	0.19	3.4	>50	1.3	6.6	0.34	3	24.4	0.7
1288714	Soil	20	0.01	459	0.002	5	0.43	0.003	0.09	2.2	9.64	1.3	2.2	0.10	2	20.6	0.4
1288715	Soil	18	<0.01	439	0.002	5	0.27	0.004	0.12	2.4	6.39	1.0	3.0	0.21	1	12.9	0.3
1288716	Soil	34	0.03	256	0.005	5	0.45	0.004	0.40	3.2	9.14	1.8	4.5	0.75	3	39.1	0.4
1288717	Soil	30	0.05	514	0.008	5	0.47	0.005	0.25	3.9	8.79	1.4	3.3	0.45	4	21.8	0.4
1288718	Soil	42	0.03	724	0.004	4	0.68	0.004	0.21	2.6	8.79	5.9	5.2	0.37	4	27.4	0.5
1288719	Soil	47	0.03	863	0.007	7	0.70	0.004	0.23	3.3	7.37	7.0	5.8	0.38	4	29.2	0.3
1288720	Soil	29	0.06	485	0.006	7	0.69	0.003	0.14	2.3	26.28	2.3	2.8	0.14	3	12.2	0.4
1281921	Soil	18	0.08	567	0.003	3	0.44	0.004	0.07	0.1	0.94	2.6	0.7	<0.05	1	2.1	<0.2
1281922	Soil	14	0.02	125	0.006	4	0.32	0.007	0.06	0.1	0.33	0.2	0.3	<0.05	2	1.7	<0.2
1281923	Soil	3	0.01	24	0.003	<1	0.19	0.029	0.02	<0.1	0.24	<0.1	<0.1	<0.05	<1	<0.5	<0.2
1281924	Soil	9	0.02	89	0.008	2	0.43	0.016	0.05	0.2	0.21	0.3	0.2	<0.05	3	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1281925	Soil	11.2	25.9	38.2	57	0.4	16.9	2.2	28	0.99	11.1	1.0	0.2	24	0.2	2.6	0.2	135	0.02	0.064	9
1281926	Soil	6.2	21.9	7.2	74	0.2	22.6	5.1	181	1.47	12.0	<0.5	0.3	11	0.2	1.7	0.1	42	0.03	0.132	5
1281927	Soil	14.7	20.5	12.4	100	0.1	33.4	4.7	121	1.44	12.6	0.5	<0.1	12	0.2	2.1	0.2	49	0.02	0.115	5
1281928	Soil	7.3	30.9	10.5	111	0.3	35.5	5.7	70	1.89	35.1	3.5	0.3	8	0.2	2.3	0.2	40	0.02	0.085	5
1281929	Soil	86.4	75.9	17.2	561	0.5	175.4	7.9	196	1.90	33.9	<0.5	1.5	179	6.1	12.6	0.1	237	7.57	0.090	5
1281930	Soil	79.2	64.4	20.0	485	0.3	173.5	8.8	203	2.39	39.4	1.4	1.2	41	4.2	8.4	0.1	96	1.33	0.105	5
1287851	Soil	4.8	44.8	19.6	221	0.7	47.4	7.8	94	2.62	17.8	4.9	1.7	42	1.3	1.7	0.3	59	0.11	0.086	5
1287852	Soil	3.7	12.2	12.6	60	0.2	11.2	3.1	82	1.73	15.6	0.7	0.3	12	0.2	1.5	0.2	52	0.02	0.057	6
1287853	Soil	4.9	24.2	11.8	107	0.3	21.3	5.5	164	1.69	13.6	3.1	1.1	28	1.4	1.8	0.2	57	0.12	0.056	7
1287854	Soil	3.1	34.3	10.9	151	1.1	32.7	5.1	92	1.66	9.7	3.5	1.4	43	1.5	1.2	0.2	48	0.34	0.084	5
1287855	Soil	8.1	46.1	13.0	525	0.9	115.0	13.7	347	3.80	17.4	3.9	1.3	46	2.5	2.0	0.2	49	0.52	0.119	5
1287856	Soil	6.7	43.4	12.7	408	0.7	100.6	15.7	533	2.97	17.1	13.2	1.4	47	2.0	2.0	0.2	52	0.42	0.109	6
1287857	Soil	6.2	40.6	14.4	323	0.7	67.9	19.0	662	2.49	16.1	3.2	2.3	68	2.9	2.4	0.2	55	0.73	0.106	7
1287858	Soil	4.2	57.0	20.7	302	2.5	77.2	9.2	183	3.14	20.5	2.7	3.2	86	2.3	2.9	0.3	43	0.82	0.229	9
1287859	Soil	3.8	72.3	41.6	233	1.7	70.6	21.4	582	7.43	48.6	6.0	2.6	52	0.6	1.9	0.3	37	0.52	0.119	4
1287860	Soil	2.6	25.4	35.3	95	1.2	26.7	7.1	225	3.72	349.6	104.1	2.0	66	0.5	26.2	0.3	31	0.15	0.100	11
1288361	Soil	102.2	80.1	11.6	559	0.5	237.4	16.7	306	2.18	69.7	<0.5	2.1	181	3.3	8.6	0.2	92	6.50	0.114	9
1288362	Soil	22.5	69.6	31.5	321	0.5	68.0	9.3	158	2.83	179.4	3.4	0.9	53	2.1	6.8	0.4	94	0.10	0.085	5
1288363	Soil	17.4	22.3	9.3	115	0.1	28.8	4.4	61	1.36	23.0	<0.5	0.4	8	0.1	3.5	0.2	69	0.03	0.039	7
1288364	Soil	23.3	27.9	7.5	160	<0.1	42.4	5.5	70	1.67	34.9	0.8	0.5	4	0.1	3.6	0.2	79	0.02	0.037	7
1288365	Soil	29.1	47.9	16.8	286	0.4	84.1	10.7	267	2.51	60.6	2.6	1.5	32	1.6	5.6	0.3	88	0.17	0.095	12
1288366	Soil	3.6	8.8	3.3	38	0.2	11.2	1.4	39	0.43	4.7	<0.5	<0.1	14	0.2	0.9	<0.1	22	0.31	0.029	2
1288367	Soil	4.3	46.7	14.0	106	0.3	27.1	7.8	320	3.77	35.7	1.9	0.3	9	0.5	2.1	0.4	62	0.03	0.103	4
1288368	Soil	3.6	34.9	19.9	83	0.6	22.2	5.3	83	1.74	45.1	1.2	0.3	11	0.2	2.4	0.4	42	0.02	0.072	5
1288369	Soil	3.8	36.0	21.5	77	1.0	20.7	5.0	88	2.13	92.1	2.6	0.2	21	0.3	2.7	0.4	44	0.02	0.079	6
1288370	Soil	4.6	39.0	25.2	49	2.4	23.7	5.5	107	2.91	123.2	7.0	0.6	38	0.1	3.4	0.3	45	0.02	0.074	5
1288261	Soil	2.8	88.5	20.9	246	2.4	102.4	21.1	360	3.63	56.9	9.1	1.7	82	0.8	2.4	0.3	30	0.09	0.111	6
1288262	Soil	4.7	67.0	17.7	138	2.1	50.4	9.0	134	2.81	79.0	8.1	2.1	89	0.3	3.0	0.3	26	0.12	0.064	3
1288263	Soil	2.4	44.4	23.1	112	1.6	34.6	6.9	101	2.83	183.3	18.9	2.0	116	0.3	3.3	0.3	25	0.03	0.080	6
1288264	Soil	2.4	61.6	21.3	124	1.3	37.1	7.7	117	3.15	89.0	5.3	3.1	83	0.3	2.6	0.3	24	0.08	0.071	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1281925	Soil	18	0.01	161	0.004	1	0.30	0.010	0.05	0.2	0.21	0.3	0.2	0.06	2	1.3	0.2
1281926	Soil	8	0.03	210	0.007	2	0.49	0.014	0.06	<0.1	0.19	0.5	0.1	0.06	2	0.7	<0.2
1281927	Soil	10	0.03	170	0.002	4	0.40	0.012	0.06	<0.1	0.16	0.3	0.2	<0.05	2	1.4	<0.2
1281928	Soil	9	0.03	232	0.002	2	0.38	0.012	0.06	<0.1	0.15	0.6	0.1	<0.05	2	1.7	<0.2
1281929	Soil	18	2.10	199	0.002	6	0.25	0.006	0.07	0.2	0.42	3.0	1.0	0.05	<1	4.5	<0.2
1281930	Soil	18	0.34	206	0.002	6	0.25	0.004	0.07	0.2	0.40	4.1	1.3	0.07	<1	2.7	<0.2
1287851	Soil	18	0.12	1403	0.002	5	1.25	0.005	0.09	<0.1	0.37	3.1	0.5	0.08	3	4.1	<0.2
1287852	Soil	8	0.04	183	0.007	1	0.45	0.003	0.04	0.1	0.05	0.6	0.2	<0.05	3	0.6	<0.2
1287853	Soil	12	0.08	1613	0.006	4	0.64	0.006	0.07	0.2	0.15	1.7	0.3	0.06	2	0.8	<0.2
1287854	Soil	14	0.14	1620	0.003	4	0.94	0.008	0.07	<0.1	0.29	2.6	0.2	0.07	2	2.0	<0.2
1287855	Soil	15	0.13	945	0.002	4	1.49	0.006	0.06	<0.1	0.35	2.4	0.7	0.09	2	2.9	<0.2
1287856	Soil	15	0.13	1098	0.002	4	1.29	0.008	0.08	<0.1	0.44	2.3	0.5	0.10	2	2.5	<0.2
1287857	Soil	18	0.20	1486	0.002	5	1.07	0.007	0.10	<0.1	0.44	3.8	0.3	0.10	2	2.6	<0.2
1287858	Soil	23	0.05	497	0.003	8	0.78	0.012	0.16	<0.1	0.45	3.1	0.3	0.29	2	4.9	<0.2
1287859	Soil	27	0.21	388	0.002	3	1.11	0.004	0.10	<0.1	0.50	6.6	0.2	0.08	3	4.3	<0.2
1287860	Soil	23	0.06	1288	0.001	4	0.71	0.005	0.16	0.1	44.05	2.8	0.7	0.27	3	8.3	<0.2
1288361	Soil	14	2.72	237	0.002	5	0.24	0.006	0.07	0.2	0.70	3.2	1.7	0.07	<1	5.6	<0.2
1288362	Soil	12	0.05	293	0.002	4	0.39	0.003	0.07	<0.1	0.13	2.9	0.5	0.07	1	2.7	<0.2
1288363	Soil	6	0.02	183	0.002	2	0.27	0.004	0.04	<0.1	0.05	0.6	0.2	<0.05	2	0.9	<0.2
1288364	Soil	8	0.02	78	0.002	4	0.31	0.003	0.05	<0.1	0.05	0.9	0.2	<0.05	2	1.0	<0.2
1288365	Soil	14	0.10	787	0.006	4	0.58	0.003	0.07	0.1	0.22	2.0	0.5	<0.05	2	1.1	<0.2
1288366	Soil	4	0.04	159	0.004	2	0.25	0.026	0.03	<0.1	0.05	0.3	0.1	<0.05	1	<0.5	<0.2
1288367	Soil	17	0.03	152	0.003	1	0.47	0.003	0.05	<0.1	0.11	2.0	0.1	0.06	2	1.0	<0.2
1288368	Soil	10	0.02	97	0.002	2	0.36	0.003	0.06	<0.1	0.06	0.7	0.2	<0.05	2	0.6	<0.2
1288369	Soil	12	0.02	118	0.003	1	0.42	0.003	0.06	0.1	0.08	0.5	0.2	<0.05	2	1.0	<0.2
1288370	Soil	18	0.07	183	0.006	1	0.61	0.003	0.05	0.1	0.13	1.9	0.3	0.08	2	2.8	<0.2
1288261	Soil	18	0.06	481	0.002	3	0.76	0.005	0.07	<0.1	0.31	4.5	0.1	0.07	2	2.4	<0.2
1288262	Soil	17	0.03	838	<0.001	3	0.45	0.004	0.08	<0.1	0.62	4.5	0.1	0.10	1	3.9	<0.2
1288263	Soil	19	0.04	739	<0.001	3	0.74	0.007	0.12	<0.1	0.43	3.1	0.2	0.20	2	3.7	<0.2
1288264	Soil	17	0.04	846	<0.001	3	0.71	0.008	0.12	<0.1	0.24	3.5	0.1	0.19	1	4.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288265	Soil	2.4	39.5	15.6	181	1.8	76.2	10.5	94	2.52	21.3	5.0	0.8	110	0.8	1.7	0.2	27	1.46	0.091	6
1288266	Soil	4.2	60.9	15.6	153	2.0	51.6	10.1	125	2.40	18.2	2.9	2.1	63	0.3	1.5	0.2	25	0.16	0.063	3
1288267	Soil	2.0	32.2	16.4	140	0.6	41.8	6.7	347	2.29	71.1	29.8	1.7	85	0.8	2.9	0.2	31	0.61	0.121	9
1288268	Soil	3.0	53.1	14.8	72	0.5	22.8	2.6	57	2.59	92.2	42.4	1.3	60	0.2	3.7	0.2	43	0.02	0.070	8
1288269	Soil	3.8	67.6	23.1	119	2.9	37.0	9.0	248	2.83	36.2	12.4	1.3	100	0.3	1.9	0.2	29	0.08	0.100	3
1288270	Soil	2.8	30.2	16.7	86	2.0	23.9	6.0	117	3.17	21.8	2.6	1.2	40	0.1	1.3	0.3	45	0.02	0.082	5
1288501	Soil	98.4	68.8	12.3	1260	0.4	345.5	17.1	437	3.49	60.9	6.7	3.2	63	14.9	9.2	0.2	171	0.33	0.173	16
1288502	Soil	46.8	53.6	19.6	602	0.6	181.5	14.6	323	3.92	112.0	11.5	3.3	29	1.6	17.1	0.3	107	0.12	0.124	19
1288503	Soil	91.8	56.6	11.1	1254	0.6	274.2	15.7	579	3.18	96.7	4.2	3.5	250	16.0	18.4	0.2	84	4.38	0.075	12
1288504	Soil	63.0	102.0	13.6	1031	1.3	189.6	9.5	197	2.42	123.0	17.0	2.5	60	15.2	22.3	0.2	132	0.54	0.113	11
1288505	Soil	48.6	81.4	11.5	812	1.1	156.8	9.1	166	2.23	83.0	8.9	2.9	53	14.2	15.2	0.2	100	0.62	0.089	9
1288506	Soil	3.6	21.4	28.3	17	1.6	4.4	0.3	8	0.68	39.8	13.9	1.6	45	0.7	16.3	0.2	59	0.06	0.031	7
1288507	Soil	1.7	4.0	26.0	5	1.5	1.0	0.1	3	0.24	8.8	13.8	0.7	21	<0.1	5.4	0.2	23	0.01	0.022	7
1288508	Soil	46.3	38.4	16.1	53	6.5	10.8	0.7	25	1.55	131.8	16.1	0.4	154	0.4	31.1	0.2	267	0.09	0.061	6
1288509	Soil	6.5	35.5	32.9	134	1.0	22.7	4.5	70	3.54	514.4	51.8	2.9	48	1.2	19.1	0.9	33	0.04	0.114	17
1288510	Soil	3.8	12.8	26.3	41	1.0	9.8	1.3	22	0.67	58.0	58.9	1.7	33	0.4	10.5	0.3	23	0.04	0.029	30
1288511	Soil	3.4	94.1	20.1	178	0.6	51.0	16.9	298	2.88	187.2	13.9	4.3	28	1.5	7.8	1.9	33	0.06	0.049	20
1288512	Soil	4.2	72.5	19.9	134	0.6	29.5	6.9	113	2.31	180.6	8.8	3.1	23	1.0	7.2	1.8	41	0.02	0.050	23
1288513	Soil	4.0	88.9	25.9	175	0.7	49.3	12.1	184	2.81	180.4	16.2	4.2	27	1.2	7.0	1.5	44	0.02	0.054	19
1288514	Soil	7.8	32.7	23.9	125	0.3	26.5	4.1	71	2.14	104.3	5.1	1.0	21	0.4	6.3	0.6	73	0.02	0.056	20
1288515	Soil	10.8	56.3	63.7	118	1.6	27.6	3.8	99	4.07	154.5	9.2	4.7	38	0.4	10.2	0.8	60	0.02	0.087	17
1288516	Soil	4.0	60.6	22.3	134	0.8	29.2	5.4	141	3.62	190.1	4.9	4.4	24	0.8	4.6	0.7	43	0.02	0.054	17
1288517	Soil	5.1	41.4	29.9	108	1.2	18.8	3.0	37	2.67	528.1	6.8	3.3	49	0.5	5.5	1.6	44	0.02	0.070	23
1288518	Soil	4.0	29.9	22.3	158	0.3	32.7	8.9	74	2.96	198.4	1.3	2.8	27	0.4	3.3	0.5	41	0.03	0.080	28
1288519	Soil	7.2	22.6	131.3	125	1.8	15.1	2.6	44	3.03	724.2	133.9	2.6	54	0.2	34.3	4.2	60	0.02	0.090	24
1288520	Soil	4.2	20.3	34.1	106	0.6	15.0	3.2	34	1.46	160.9	7.2	0.6	22	0.2	10.1	2.3	38	0.02	0.042	23
1288521	Soil	5.7	38.0	21.0	114	1.0	19.7	5.2	83	2.51	263.4	23.3	1.8	30	0.4	7.8	2.0	39	0.03	0.068	18
1288522	Soil	6.4	49.6	23.7	136	1.5	26.0	5.7	50	3.67	559.5	15.6	3.9	34	0.8	9.9	5.3	40	0.02	0.083	23
1288523	Soil	17.6	93.3	33.1	188	1.9	46.2	7.0	142	3.49	390.7	12.5	3.8	57	1.5	16.2	1.6	108	0.06	0.138	14
1288524	Soil	10.2	75.4	30.2	150	1.7	31.6	4.0	69	1.79	130.0	24.1	1.7	46	2.0	8.0	1.2	66	0.07	0.103	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288265	Soil	18	0.11	709	0.002	5	0.75	0.006	0.08	<0.1	0.39	2.7	0.1	0.13	1	2.7	<0.2
1288266	Soil	18	0.06	823	0.001	3	0.56	0.004	0.08	<0.1	0.25	4.7	0.1	0.08	1	3.4	<0.2
1288267	Soil	20	0.07	530	0.002	5	0.63	0.005	0.11	0.1	1.36	2.7	0.1	0.11	2	2.3	<0.2
1288268	Soil	22	0.04	249	0.003	2	0.57	0.002	0.08	0.1	1.38	1.5	0.1	0.07	3	4.3	0.3
1288269	Soil	25	0.09	288	0.002	3	0.80	0.005	0.10	<0.1	0.47	2.5	0.1	0.11	2	2.4	<0.2
1288270	Soil	21	0.07	168	0.004	3	0.72	0.004	0.06	<0.1	0.22	1.6	0.1	0.07	4	1.2	<0.2
1288501	Soil	27	0.08	1228	0.004	8	0.99	0.003	0.11	0.6	0.98	3.7	3.0	<0.05	2	17.0	<0.2
1288502	Soil	20	0.06	356	0.003	5	0.72	0.002	0.08	0.3	2.86	2.4	1.0	0.05	1	5.7	0.2
1288503	Soil	16	2.46	1452	0.009	7	0.55	0.018	0.07	0.4	2.55	3.7	1.4	0.07	<1	4.1	<0.2
1288504	Soil	15	0.13	719	0.003	6	0.47	0.004	0.09	0.4	7.79	2.8	1.5	0.06	<1	5.1	<0.2
1288505	Soil	13	0.09	466	0.003	6	0.59	0.010	0.07	0.3	3.69	3.2	1.3	0.06	<1	4.1	<0.2
1288506	Soil	14	0.02	806	0.003	5	0.17	0.003	0.12	0.4	16.47	0.8	2.2	0.25	1	8.8	<0.2
1288507	Soil	6	<0.01	285	0.003	4	0.19	0.003	0.05	0.2	5.69	0.3	0.9	0.07	1	2.8	<0.2
1288508	Soil	17	0.04	342	0.002	3	0.30	0.005	0.14	1.2	2.49	0.5	3.5	0.25	2	8.8	0.3
1288509	Soil	9	0.07	289	0.002	3	0.46	0.004	0.08	0.3	3.49	1.7	0.6	0.15	1	3.9	<0.2
1288510	Soil	4	0.01	209	<0.001	3	0.21	0.003	0.06	0.7	3.55	0.6	1.0	0.08	<1	1.2	<0.2
1288511	Soil	15	0.14	461	0.002	2	0.97	0.004	0.06	0.7	1.78	2.5	0.2	<0.05	2	2.1	<0.2
1288512	Soil	11	0.11	278	0.002	<1	0.91	0.005	0.06	0.6	1.29	2.0	0.2	<0.05	2	1.8	<0.2
1288513	Soil	15	0.13	300	0.002	2	1.11	0.004	0.06	0.4	1.61	2.9	0.2	<0.05	2	1.8	<0.2
1288514	Soil	11	0.04	122	0.004	2	0.61	0.003	0.05	0.3	0.68	0.9	0.3	<0.05	4	1.9	<0.2
1288515	Soil	19	0.14	156	0.010	1	0.89	0.004	0.07	0.3	0.95	2.4	0.5	0.08	3	3.8	<0.2
1288516	Soil	18	0.22	162	0.002	1	1.19	0.004	0.05	0.1	0.31	2.5	0.2	<0.05	3	1.7	<0.2
1288517	Soil	8	0.04	152	0.002	<1	0.61	0.007	0.06	0.3	0.50	1.3	0.3	0.07	2	1.8	<0.2
1288518	Soil	10	0.06	106	0.002	2	0.58	0.004	0.06	0.2	0.21	1.7	0.2	<0.05	3	0.9	<0.2
1288519	Soil	7	0.03	215	0.008	3	0.42	0.006	0.08	0.9	0.95	0.8	1.1	0.11	3	2.7	<0.2
1288520	Soil	6	0.01	77	0.004	2	0.39	0.010	0.04	0.4	0.82	0.3	0.2	<0.05	2	0.9	<0.2
1288521	Soil	10	0.04	152	0.003	2	0.46	0.006	0.06	0.4	1.36	1.1	0.3	0.05	2	2.4	<0.2
1288522	Soil	10	0.04	184	0.002	2	0.46	0.008	0.06	3.3	1.45	1.5	0.3	0.07	1	2.6	<0.2
1288523	Soil	17	0.06	412	0.003	2	0.82	0.006	0.07	0.7	2.84	2.5	0.9	0.10	2	5.0	<0.2
1288524	Soil	13	0.08	487	0.002	2	0.70	0.008	0.07	0.5	3.33	2.2	0.8	0.07	2	3.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288525	Soil	15.7	41.1	28.9	89	1.8	25.4	2.6	42	2.32	136.5	20.9	2.1	48	1.1	11.9	0.7	96	0.07	0.121	14
1288526	Soil	10.2	41.3	16.0	89	1.1	16.9	2.2	30	1.61	91.3	10.8	2.0	27	0.7	8.2	0.6	42	0.06	0.063	18
1288527	Soil	2.7	39.6	13.6	40	1.0	9.0	1.1	21	0.79	30.5	14.4	0.4	23	0.4	2.5	0.4	23	0.04	0.063	4
1288528	Soil	13.0	55.4	20.5	202	0.7	28.8	29.3	1028	4.97	121.2	10.9	2.8	24	0.9	10.6	0.4	53	0.04	0.065	15
1288529	Soil	15.5	34.8	22.8	144	1.6	22.7	3.7	98	2.73	120.4	12.7	1.9	26	0.9	9.0	0.4	54	0.07	0.088	14
1288530	Soil	15.6	43.2	65.3	150	2.6	20.7	3.7	60	4.28	671.3	162.3	2.0	67	0.6	28.0	3.1	64	0.07	0.146	18
1287061	Soil	17.1	39.5	12.9	343	0.8	73.6	6.6	104	1.99	34.6	1.8	1.6	48	2.8	7.6	0.2	105	0.74	0.106	12
1287062	Soil	3.1	38.8	18.6	66	0.2	25.0	6.5	138	2.42	186.2	3.4	0.3	9	0.2	2.0	0.4	40	0.03	0.058	7
1287063	Soil	3.4	65.8	22.2	47	0.3	48.3	12.2	213	3.94	62.6	2.9	0.2	11	<0.1	3.6	0.4	50	0.02	0.078	4
1287064	Soil	2.8	45.5	26.7	34	2.0	21.5	4.5	120	2.39	163.3	2.9	0.5	30	0.1	3.6	0.4	31	0.04	0.131	2
1287065	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287066	Soil	3.8	10.8	33.8	13	1.8	5.7	1.3	28	0.73	38.0	0.7	0.2	21	<0.1	1.6	0.2	25	0.02	0.044	2
1287067	Soil	1.6	10.0	12.3	43	0.7	19.3	11.1	450	1.64	32.1	1.5	0.1	11	0.2	0.9	0.1	15	0.02	0.050	1
1287068	Soil	4.6	94.1	22.7	248	2.2	151.2	13.9	236	1.47	63.8	30.5	1.4	77	22.9	20.8	0.2	117	0.48	0.153	9
1287069	Soil	10.2	27.9	29.3	270	0.2	42.3	8.6	187	2.63	28.8	1.9	1.5	65	1.3	3.8	0.2	91	0.07	0.079	8
1287070	Soil	14.8	32.6	22.2	234	0.6	40.8	13.8	428	2.47	40.3	4.4	2.1	40	2.5	5.1	0.3	114	0.15	0.089	11
1287071	Soil	17.6	25.1	21.4	178	0.6	31.8	4.2	115	1.86	41.8	4.7	1.6	34	1.1	7.7	0.2	122	0.11	0.079	12
1287072	Soil	11.5	23.2	14.8	130	0.8	28.5	2.4	52	1.30	30.5	3.6	0.2	22	1.2	7.1	0.1	80	0.13	0.079	6
1287073	Soil	20.0	12.1	24.2	71	0.5	14.8	2.3	51	1.48	31.8	1.8	1.7	13	0.2	6.2	0.2	111	0.02	0.044	14
1287074	Soil	15.6	22.5	15.5	128	0.9	31.2	4.6	96	2.41	29.7	2.4	2.0	12	0.4	4.5	0.2	82	0.03	0.041	10
1287075	Soil	17.7	45.2	22.1	440	1.2	77.7	10.5	394	2.59	56.3	6.5	2.2	64	3.2	11.5	0.3	106	0.44	0.119	9
1287076	Soil	15.6	40.7	18.3	195	1.5	62.8	8.0	97	2.80	53.5	4.9	0.8	22	0.3	4.5	0.2	97	0.03	0.119	13
1287077	Soil	6.9	51.6	36.6	132	2.7	40.2	5.5	62	3.30	48.0	4.9	1.7	160	0.2	3.4	0.4	28	0.04	0.160	13
1287078	Soil	17.4	67.3	22.4	260	0.9	105.7	30.8	1144	5.85	143.3	5.8	3.4	48	1.3	6.7	0.4	66	0.14	0.218	16
1287079	Soil	11.3	108.5	32.0	294	2.1	79.3	14.5	254	4.78	85.2	5.3	3.6	97	1.3	5.5	0.4	33	0.13	0.190	20
1287080	Soil	15.5	69.6	22.6	296	1.3	81.6	15.7	418	4.06	94.3	6.7	1.9	59	1.4	5.9	0.3	70	0.13	0.175	17
1287901	Soil	6.5	16.9	37.2	55	1.4	12.6	0.9	42	0.50	33.0	2.9	0.4	39	0.5	2.9	0.2	52	0.17	0.036	2
1287902	Soil	8.3	32.9	34.4	59	1.6	14.9	2.3	63	0.75	37.8	2.6	0.4	18	0.6	2.7	0.2	79	0.03	0.042	2
1287903	Soil	20.6	214.7	40.7	325	2.3	63.3	20.4	595	3.25	80.7	4.0	1.2	26	7.1	6.3	0.4	241	0.07	0.178	5
1287904	Soil	16.3	36.3	16.8	112	0.8	28.8	3.8	66	1.29	15.4	1.5	0.2	14	1.4	3.7	0.2	154	0.05	0.069	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288525	Soil		17	0.08	676	0.001	2	0.74	0.004	0.07	0.3	4.17	2.0	1.0	0.05	2	5.6	<0.2
1288526	Soil		9	0.07	290	0.001	3	0.49	0.005	0.06	0.2	0.81	1.4	0.5	0.06	2	3.2	<0.2
1288527	Soil		8	0.03	234	0.002	2	0.44	0.018	0.06	<0.1	1.27	0.9	0.4	0.07	1	2.0	<0.2
1288528	Soil		12	0.06	233	0.001	2	0.61	0.003	0.06	0.2	0.62	2.0	0.6	<0.05	2	4.6	<0.2
1288529	Soil		12	0.07	391	0.001	2	0.63	0.004	0.06	0.2	1.35	1.6	0.6	<0.05	2	3.6	<0.2
1288530	Soil		13	0.08	344	0.002	2	0.62	0.009	0.12	1.4	14.65	1.2	2.2	0.23	2	9.3	<0.2
1287061	Soil		16	0.14	684	0.004	4	0.53	0.005	0.07	0.2	0.56	3.0	0.6	0.05	1	2.0	<0.2
1287062	Soil		11	0.03	98	0.004	<1	0.41	0.004	0.04	0.1	0.10	0.9	0.2	<0.05	2	0.9	<0.2
1287063	Soil		14	0.03	142	0.003	<1	0.51	0.002	0.05	<0.1	0.05	1.6	0.3	<0.05	2	1.4	<0.2
1287064	Soil		12	0.02	173	0.002	4	0.41	0.004	0.08	<0.1	0.16	2.5	0.2	0.12	2	1.6	<0.2
1287065	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287066	Soil		5	<0.01	131	0.002	2	0.24	0.008	0.05	<0.1	0.06	0.4	0.3	0.05	2	1.4	<0.2
1287067	Soil		4	0.02	147	0.005	1	0.32	0.015	0.03	<0.1	0.06	0.3	0.2	<0.05	2	0.6	<0.2
1287068	Soil		28	0.06	2782	0.006	5	0.74	0.007	0.07	0.4	5.54	3.8	1.0	0.16	2	10.9	<0.2
1287069	Soil		19	0.10	300	0.002	2	0.78	0.004	0.07	0.1	0.24	2.7	0.4	<0.05	3	1.3	<0.2
1287070	Soil		21	0.15	679	0.002	3	1.04	0.005	0.09	0.2	0.65	2.4	0.9	<0.05	3	2.3	<0.2
1287071	Soil		17	0.11	713	0.003	5	0.73	0.006	0.09	0.2	0.44	1.7	0.7	<0.05	3	1.8	<0.2
1287072	Soil		11	0.05	547	0.002	4	0.54	0.014	0.08	0.2	0.49	0.5	0.8	0.06	2	1.5	<0.2
1287073	Soil		9	0.04	219	0.004	2	0.57	0.004	0.05	0.2	0.10	0.6	0.9	<0.05	3	1.6	<0.2
1287074	Soil		15	0.10	192	0.005	2	0.86	0.003	0.05	0.2	0.20	1.3	0.4	<0.05	3	1.4	<0.2
1287075	Soil		21	0.14	1372	0.002	4	0.91	0.005	0.08	0.2	0.93	3.4	0.7	<0.05	2	2.8	<0.2
1287076	Soil		16	0.04	405	0.004	2	0.61	0.004	0.06	0.1	0.37	1.1	0.3	0.06	2	2.2	<0.2
1287077	Soil		9	0.01	775	0.002	2	0.38	0.003	0.14	<0.1	1.69	1.8	0.3	0.31	<1	3.0	<0.2
1287078	Soil		14	0.07	1094	0.003	3	1.02	0.005	0.09	0.1	0.74	3.7	0.4	0.08	1	3.2	<0.2
1287079	Soil		10	0.04	1922	0.002	2	0.71	0.003	0.11	<0.1	2.72	3.5	0.3	0.10	<1	3.6	<0.2
1287080	Soil		14	0.07	1330	0.004	3	0.77	0.005	0.09	0.1	1.21	2.3	0.4	0.07	1	3.1	<0.2
1287901	Soil		11	0.05	140	0.002	<1	0.24	0.002	0.03	<0.1	0.11	0.6	0.5	<0.05	1	2.7	<0.2
1287902	Soil		13	0.02	104	0.003	1	0.26	0.002	0.04	<0.1	0.08	0.9	0.4	0.07	2	2.5	<0.2
1287903	Soil		37	0.07	238	0.005	2	1.52	0.006	0.07	0.1	0.18	4.7	0.8	0.10	5	3.8	0.2
1287904	Soil		13	0.03	128	0.004	1	0.57	0.011	0.04	0.1	0.09	0.6	0.5	0.05	2	1.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287905	Soil		11.8	31.8	22.1	133	0.5	27.8	12.7	603	1.85	13.3	2.2	0.3	29	1.6	3.0	0.2	102	0.08	0.063	4
1287906	Soil		21.5	48.5	19.6	290	0.9	61.7	8.4	288	1.94	18.1	2.1	0.7	30	2.9	4.1	0.3	103	0.14	0.062	6
1287907	Soil		63.0	101.0	17.0	838	1.3	208.6	13.5	199	2.38	45.8	3.5	1.5	76	7.8	12.8	0.2	240	1.22	0.108	13
1287908	Soil		117.5	150.4	18.9	1241	2.1	271.8	6.5	141	1.99	81.5	1.7	1.2	235	17.0	38.0	0.2	394	5.80	0.123	12
1287909	Soil		74.2	81.7	20.7	828	1.5	209.1	8.3	142	1.67	40.5	2.6	1.4	83	7.9	13.8	0.2	282	0.92	0.094	11
1287910	Soil		19.1	16.9	11.0	101	1.2	24.3	2.1	24	0.57	9.5	0.6	0.2	13	0.3	3.4	0.1	136	0.03	0.041	8
1287911	Soil		14.1	30.8	17.8	118	2.1	29.2	1.9	60	0.80	13.2	5.0	0.4	24	0.7	2.1	0.2	102	0.23	0.093	4
1287912	Soil		10.5	27.9	19.2	87	1.0	20.8	2.5	36	0.72	10.2	2.6	0.6	24	1.1	1.5	0.2	97	0.06	0.071	6
1287913	Soil		7.5	18.1	12.9	66	0.1	17.3	5.4	130	1.23	8.7	0.7	1.8	12	0.3	1.4	0.3	54	0.03	0.040	6
1287914	Soil		6.2	7.3	11.0	40	<0.1	8.1	1.7	42	0.68	12.1	0.7	1.2	18	<0.1	1.4	0.2	93	0.02	0.020	12
1287915	Soil		14.9	26.8	15.4	150	0.4	34.8	7.2	128	1.96	17.3	2.6	0.9	18	0.6	3.1	0.4	81	0.11	0.142	12
1287916	Soil		5.6	13.4	12.4	56	0.2	12.6	2.5	53	0.87	8.6	1.2	0.6	23	0.3	1.0	0.2	53	0.06	0.044	6
1287917	Soil		11.5	23.1	4.8	139	1.8	26.3	1.9	51	0.53	8.7	1.5	0.1	12	3.0	2.9	<0.1	155	0.10	0.086	4
1287918	Soil		5.8	10.0	8.4	47	0.2	10.0	1.8	33	0.67	6.7	4.5	0.3	12	0.1	1.0	0.1	58	0.03	0.035	12
1287919	Soil		4.8	17.9	13.6	88	0.3	18.9	3.3	139	1.00	7.9	2.1	0.6	50	0.9	1.4	0.2	51	0.47	0.082	5
1287920	Soil		5.9	27.2	15.7	97	0.7	23.0	5.9	239	1.30	10.7	3.4	2.1	44	0.9	1.6	0.2	59	0.37	0.091	10
1288271	Soil		2.9	47.1	16.7	90	1.6	26.2	6.3	176	3.82	20.0	6.3	0.8	32	0.2	1.5	0.3	44	0.03	0.098	4
1288272	Soil		3.7	60.0	16.3	95	1.8	26.0	6.5	202	3.06	17.5	6.6	0.9	49	0.2	1.5	0.3	51	0.02	0.104	4
1288273	Soil		2.9	48.8	20.4	97	1.3	26.2	8.7	678	3.92	14.7	5.4	0.6	22	0.3	1.6	0.3	47	0.04	0.090	5
1288274	Soil		2.5	51.3	24.4	108	0.5	30.6	15.2	962	3.02	17.5	6.3	0.7	36	0.3	1.5	0.3	35	0.09	0.128	4
1288275	Soil		2.6	55.3	22.5	116	0.4	35.5	17.4	936	3.27	17.1	6.4	1.2	30	0.2	1.5	0.4	37	0.03	0.112	4
1288276	Soil		4.6	93.0	24.0	251	1.1	150.2	64.1	1768	6.25	40.2	17.6	4.1	125	0.4	2.6	0.4	35	0.02	0.102	4
1288277	Soil		1.0	24.5	11.7	16	0.1	14.4	5.2	64	1.25	7.3	1.0	1.8	40	1.1	0.4	0.2	22	0.24	0.037	4
1288278	Soil		2.0	24.3	10.7	99	0.3	25.7	6.3	106	1.85	11.9	3.2	1.8	61	0.4	1.3	0.2	31	0.41	0.050	5
1288279	Soil		2.9	30.1	16.1	130	<0.1	27.5	6.7	124	2.59	18.9	1.0	1.8	28	0.4	1.2	0.2	36	0.10	0.037	4
1288280	Soil		1.9	16.8	9.8	69	0.4	21.5	6.1	91	1.90	11.0	1.1	1.5	51	0.6	0.6	0.2	34	0.78	0.052	5
1288281	Soil		3.8	22.5	13.6	80	0.1	15.2	4.1	73	2.06	22.5	0.9	0.2	11	0.2	1.4	0.2	47	0.03	0.059	5
1288282	Soil		2.4	20.9	9.0	119	<0.1	21.5	7.7	97	2.41	15.4	1.2	0.8	7	0.2	0.9	0.2	36	0.03	0.032	4
1288283	Soil		3.2	33.6	18.3	162	0.4	55.6	11.6	155	3.41	16.7	2.3	1.7	45	0.5	1.0	0.3	34	0.39	0.068	4
1288284	Soil		6.2	43.6	20.2	67	1.0	22.0	3.5	43	2.52	16.8	4.0	1.2	33	0.3	1.7	0.2	69	0.16	0.106	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287905	Soil	12	0.03	232	0.002	2	0.36	0.008	0.08	0.1	0.07	1.2	0.4	0.13	2	1.4	<0.2
1287906	Soil	13	0.05	329	0.002	3	0.50	0.005	0.07	0.1	0.16	2.3	0.6	0.06	2	2.1	<0.2
1287907	Soil	31	0.58	564	0.004	4	0.83	0.005	0.09	0.2	0.38	4.8	1.5	<0.05	2	4.1	<0.2
1287908	Soil	26	1.05	407	0.003	6	0.40	0.006	0.08	0.4	0.91	3.0	2.1	0.06	1	5.8	<0.2
1287909	Soil	21	0.11	396	0.003	5	0.47	0.005	0.09	0.2	0.38	3.2	2.1	<0.05	2	4.5	<0.2
1287910	Soil	14	0.05	144	0.003	4	0.39	0.004	0.05	0.1	0.04	0.4	0.5	<0.05	3	0.8	<0.2
1287911	Soil	16	0.07	345	0.004	4	0.69	0.015	0.09	0.1	0.34	1.6	0.7	0.05	2	1.0	<0.2
1287912	Soil	13	0.04	360	0.002	5	0.51	0.005	0.06	<0.1	0.19	1.7	0.7	<0.05	2	0.9	<0.2
1287913	Soil	8	0.05	319	0.003	9	0.67	0.005	0.17	<0.1	0.05	1.6	0.3	<0.05	3	0.7	<0.2
1287914	Soil	7	0.02	121	0.006	2	0.36	0.002	0.03	0.1	0.02	0.6	0.3	<0.05	4	0.6	<0.2
1287915	Soil	12	0.10	501	0.005	6	0.77	0.005	0.17	0.1	0.07	1.6	0.5	<0.05	2	1.1	<0.2
1287916	Soil	9	0.04	385	0.003	3	0.44	0.007	0.09	<0.1	0.05	1.1	0.2	<0.05	2	<0.5	<0.2
1287917	Soil	13	0.04	452	0.002	2	0.39	0.018	0.07	<0.1	0.36	0.9	0.8	<0.05	1	1.4	<0.2
1287918	Soil	6	0.03	125	0.007	1	0.37	0.005	0.04	<0.1	0.02	0.4	0.2	<0.05	3	<0.5	<0.2
1287919	Soil	9	0.12	2069	0.007	2	0.71	0.017	0.07	0.1	0.09	1.2	0.3	<0.05	2	0.9	<0.2
1287920	Soil	13	0.11	1077	0.003	3	0.61	0.008	0.09	<0.1	0.27	2.5	0.3	<0.05	2	1.2	<0.2
1288271	Soil	26	0.09	144	0.006	2	0.79	0.004	0.06	0.1	0.21	1.6	0.1	0.07	4	1.7	<0.2
1288272	Soil	27	0.06	235	0.004	2	1.01	0.005	0.07	<0.1	0.24	1.8	0.2	<0.05	4	1.7	<0.2
1288273	Soil	31	0.14	161	0.008	2	1.06	0.004	0.07	0.1	0.20	1.4	0.1	0.05	5	0.9	<0.2
1288274	Soil	26	0.21	335	0.006	2	1.19	0.005	0.09	0.1	0.25	1.4	0.1	0.08	4	0.8	<0.2
1288275	Soil	27	0.18	314	0.005	3	1.20	0.005	0.08	<0.1	0.22	1.8	0.2	0.07	4	1.0	<0.2
1288276	Soil	26	0.15	714	0.003	2	1.61	0.021	0.05	<0.1	0.69	4.1	0.2	0.09	2	2.0	<0.2
1288277	Soil	11	0.04	616	0.002	<1	0.68	0.007	0.04	<0.1	0.05	2.1	0.1	0.05	2	0.9	<0.2
1288278	Soil	12	0.17	2545	0.004	2	0.76	0.008	0.06	<0.1	0.13	2.4	0.1	0.09	2	1.1	<0.2
1288279	Soil	14	0.14	1506	0.003	1	0.70	0.005	0.04	<0.1	0.05	2.2	<0.1	<0.05	2	1.2	<0.2
1288280	Soil	17	0.27	636	0.006	2	0.90	0.008	0.05	0.1	0.08	2.3	<0.1	0.05	3	1.2	<0.2
1288281	Soil	9	0.02	191	0.006	1	0.42	0.004	0.04	0.2	0.03	0.8	<0.1	<0.05	3	0.9	<0.2
1288282	Soil	9	0.07	216	0.003	1	0.48	0.003	0.05	<0.1	0.02	2.3	0.1	<0.05	2	1.2	<0.2
1288283	Soil	14	0.16	1336	0.002	1	0.72	0.005	0.05	<0.1	0.13	5.1	0.1	<0.05	2	3.0	<0.2
1288284	Soil	13	0.08	1449	0.002	1	0.61	0.004	0.06	<0.1	0.27	2.6	0.4	<0.05	1	4.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288285	Soil	4.1	47.2	16.5	116	0.8	27.5	5.7	69	2.63	18.7	2.0	0.7	16	0.4	1.2	0.2	40	0.02	0.079	3
1288286	Soil	4.9	46.6	18.3	169	0.6	37.8	8.4	115	3.30	19.7	1.9	1.3	16	0.5	1.6	0.3	43	0.02	0.066	4
1288287	Soil	2.6	30.4	10.6	86	0.1	18.2	4.1	77	1.80	9.7	1.7	0.3	8	0.3	0.7	0.2	32	0.02	0.052	3
1288288	Soil	4.1	41.6	18.1	171	0.2	30.5	9.2	148	4.03	21.3	1.6	1.2	9	0.4	1.4	0.3	44	<0.01	0.055	3
1288289	Soil	3.1	35.5	17.4	156	0.1	27.3	8.2	128	3.87	19.5	2.0	1.3	9	0.3	1.2	0.3	44	0.02	0.055	4
1288290	Soil	5.0	23.1	12.8	106	0.4	17.1	4.6	51	2.53	17.4	0.5	0.8	10	0.2	1.4	0.2	67	0.01	0.054	5
1288291	Soil	4.2	40.7	17.8	175	0.3	28.8	6.3	94	3.37	18.9	1.2	0.8	14	0.5	1.4	0.2	49	0.02	0.083	3
1288292	Soil	4.8	25.4	11.7	67	0.3	13.8	3.4	48	1.76	15.6	0.7	1.1	13	0.2	1.0	0.2	64	0.03	0.050	6
1288293	Soil	3.1	60.4	14.0	164	0.4	39.6	12.3	249	2.74	11.0	2.1	1.8	37	0.7	1.0	0.2	36	0.43	0.062	3
1288294	Soil	7.1	35.5	17.8	212	0.3	40.4	21.7	632	3.23	14.9	1.1	2.2	36	1.2	1.6	0.2	45	0.25	0.098	4
1288295	Soil	7.4	37.5	14.3	292	0.4	48.1	16.5	703	2.74	12.7	2.0	1.8	34	1.9	1.2	0.2	50	0.28	0.089	5
1288296	Soil	8.1	35.4	18.7	1128	0.5	169.6	7.8	200	2.52	25.2	2.2	1.6	75	11.4	1.5	0.2	74	0.68	0.082	4
1288297	Soil	5.6	58.2	17.7	1290	0.7	128.8	12.0	459	2.20	15.2	2.7	1.3	73	5.4	1.6	0.2	53	0.67	0.090	5
1288298	Soil	13.5	35.5	14.9	155	0.4	47.0	12.1	300	2.54	14.9	1.8	2.0	53	0.9	1.4	0.2	69	0.64	0.071	9
1288299	Soil	4.6	33.8	12.8	133	0.3	28.1	7.2	199	1.84	12.0	1.3	0.5	59	3.3	1.1	0.2	78	0.93	0.073	5
1288300	Soil	5.7	25.5	14.0	118	0.2	21.7	4.6	72	2.44	17.7	0.8	1.1	15	0.6	1.2	0.2	50	0.03	0.050	4
1288301	Soil	4.5	23.1	16.2	114	<0.1	27.4	7.6	155	3.60	21.3	<0.5	1.1	15	0.3	1.4	0.2	63	0.03	0.045	5
1288302	Soil	8.5	17.7	8.7	72	0.3	18.6	3.4	50	1.28	11.7	0.8	0.2	13	0.4	0.8	0.1	53	0.08	0.052	4
1288303	Soil	7.9	24.1	15.0	108	<0.1	20.0	4.9	89	2.69	21.8	0.6	1.2	13	0.3	1.4	0.2	67	0.03	0.047	5
1288304	Soil	15.1	32.6	19.9	154	0.4	43.9	6.0	103	2.08	18.3	2.1	0.9	38	0.7	1.9	0.2	69	0.21	0.076	6
1288305	Soil	12.9	48.5	15.5	393	0.9	95.6	7.3	195	1.81	18.8	2.1	1.6	76	3.2	3.4	0.2	143	1.02	0.123	9
1288306	Soil	12.8	34.3	14.4	153	0.5	34.6	8.7	356	2.17	13.3	1.8	1.4	47	1.6	1.5	0.2	57	0.53	0.094	6
1288307	Soil	4.3	29.2	12.9	317	0.4	57.2	2.9	101	1.35	8.1	6.2	1.1	64	7.2	1.5	0.2	56	1.11	0.079	5
1288308	Soil	10.9	41.3	16.2	280	1.1	73.3	8.6	565	1.90	15.3	1.7	1.4	59	2.2	1.8	0.2	73	0.83	0.057	7
1288309	Soil	9.5	24.5	9.1	102	0.4	30.4	4.2	238	1.56	13.5	1.8	0.6	55	2.8	1.9	0.3	52	0.79	0.073	4
1288310	Soil	13.6	38.2	20.9	194	0.4	48.6	8.1	190	1.83	15.7	3.3	2.1	68	1.2	2.8	0.2	66	0.44	0.113	8
1287161	Soil	19.5	52.9	109.5	169	3.5	24.5	4.4	101	4.08	855.7	238.4	2.7	100	1.1	54.1	3.4	91	0.13	0.177	26
1287162	Soil	9.3	54.7	60.5	147	2.5	42.2	6.4	180	2.27	355.4	148.8	2.2	53	2.9	18.6	2.8	54	0.39	0.113	17
1287163	Soil	5.8	34.6	29.8	235	1.6	48.1	2.3	43	1.51	144.1	88.5	1.0	40	3.7	15.0	1.0	31	0.43	0.066	9
1287164	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288285	Soil	11	0.06	512	0.004	1	0.66	0.007	0.04	<0.1	0.12	2.4	0.2	<0.05	2	2.2	<0.2
1288286	Soil	13	0.09	900	0.002	<1	0.59	0.003	0.05	<0.1	0.07	3.2	0.1	<0.05	2	1.8	<0.2
1288287	Soil	8	0.04	288	0.004	1	0.51	0.008	0.04	<0.1	0.03	1.3	<0.1	<0.05	2	0.9	<0.2
1288288	Soil	14	0.09	196	0.002	<1	0.66	0.003	0.04	<0.1	0.04	3.5	0.1	<0.05	2	2.0	<0.2
1288289	Soil	13	0.09	147	0.003	<1	0.59	0.003	0.04	<0.1	0.03	3.3	0.1	<0.05	2	1.7	<0.2
1288290	Soil	8	0.03	372	0.003	<1	0.61	0.003	0.03	<0.1	0.03	2.3	0.1	<0.05	3	1.4	<0.2
1288291	Soil	10	0.05	358	0.002	<1	0.51	0.003	0.04	<0.1	0.02	3.6	0.1	<0.05	2	1.3	<0.2
1288292	Soil	8	0.03	213	0.006	<1	0.66	0.004	0.03	0.1	0.02	1.7	0.2	<0.05	3	1.0	<0.2
1288293	Soil	14	0.13	1010	0.002	<1	0.65	0.005	0.04	<0.1	0.10	5.0	<0.1	<0.05	2	2.7	<0.2
1288294	Soil	15	0.14	1055	0.002	1	0.64	0.003	0.05	<0.1	0.10	4.4	0.2	<0.05	2	2.7	<0.2
1288295	Soil	15	0.14	1244	<0.001	2	0.76	0.006	0.05	<0.1	0.13	4.1	0.2	<0.05	2	2.5	<0.2
1288296	Soil	14	0.14	1176	<0.001	2	0.74	0.006	0.06	<0.1	0.21	4.6	0.6	0.09	2	2.3	<0.2
1288297	Soil	13	0.11	1123	0.001	2	0.63	0.006	0.05	<0.1	0.14	4.6	0.5	0.11	2	2.8	<0.2
1288298	Soil	19	0.18	949	0.002	3	0.79	0.006	0.06	<0.1	0.09	3.7	0.3	0.07	2	1.0	<0.2
1288299	Soil	12	0.12	934	0.002	2	0.66	0.010	0.04	<0.1	0.06	2.0	0.2	0.10	2	1.3	<0.2
1288300	Soil	11	0.08	333	<0.001	<1	0.54	0.004	0.04	<0.1	0.04	2.1	0.2	<0.05	2	1.0	<0.2
1288301	Soil	21	0.14	261	0.002	2	0.67	0.003	0.04	<0.1	0.01	2.3	0.2	<0.05	3	1.0	<0.2
1288302	Soil	10	0.04	354	0.002	2	0.51	0.009	0.04	<0.1	0.04	0.6	0.2	<0.05	2	0.5	<0.2
1288303	Soil	11	0.07	199	0.001	1	0.56	0.003	0.04	<0.1	0.02	1.9	0.2	<0.05	3	1.3	<0.2
1288304	Soil	13	0.06	929	<0.001	2	0.55	0.004	0.05	<0.1	0.10	2.4	0.3	<0.05	2	1.3	<0.2
1288305	Soil	19	0.13	1333	0.001	3	0.75	0.007	0.05	0.2	0.37	3.7	0.4	0.11	2	1.8	<0.2
1288306	Soil	14	0.12	1100	<0.001	2	0.66	0.006	0.05	<0.1	0.13	3.4	0.2	0.10	2	1.2	<0.2
1288307	Soil	14	0.18	733	0.001	2	0.65	0.007	0.04	<0.1	0.18	2.9	0.3	0.16	2	2.2	<0.2
1288308	Soil	14	0.11	833	0.001	2	0.68	0.006	0.06	<0.1	0.22	3.6	0.3	0.11	2	1.0	<0.2
1288309	Soil	10	0.09	679	0.002	2	0.49	0.012	0.04	<0.1	0.14	1.6	0.1	0.10	1	1.8	<0.2
1288310	Soil	14	0.10	1254	0.002	3	0.43	0.003	0.07	<0.1	0.18	3.1	0.2	0.08	1	1.4	<0.2
1287161	Soil	19	0.08	353	0.009	6	0.63	0.016	0.22	2.2	32.62	1.4	3.7	0.32	3	16.0	<0.2
1287162	Soil	13	0.07	364	0.002	3	0.67	0.013	0.08	1.1	14.85	1.5	2.0	0.10	2	8.4	<0.2
1287163	Soil	13	0.05	235	0.003	5	0.40	0.017	0.10	0.4	8.24	1.2	0.7	0.10	2	5.6	<0.2
1287164	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287165	Soil		12.8	52.5	49.1	167	1.6	29.3	5.2	119	3.45	488.9	84.1	4.3	71	1.1	29.8	1.7	59	0.21	0.127	20
1287166	Soil		9.6	51.3	24.9	196	1.4	42.2	8.5	169	2.77	86.1	16.3	1.7	57	1.0	9.0	0.6	74	0.27	0.096	11
1287167	Soil		6.0	51.2	15.9	210	1.0	58.0	5.7	166	1.70	47.2	16.5	1.6	70	2.0	10.6	0.5	84	1.10	0.075	8
1287168	Soil		5.6	54.6	25.7	151	2.0	39.2	5.4	161	2.32	106.4	41.4	2.1	66	1.0	15.7	0.6	52	0.62	0.087	11
1287169	Soil		9.4	72.0	96.0	93	0.7	14.8	1.9	43	3.13	50.5	4.6	0.9	239	0.3	7.1	0.2	89	0.06	0.132	3
1287170	Soil		11.6	60.6	84.0	77	4.7	15.5	3.2	57	2.90	35.0	4.2	1.6	147	0.2	3.6	0.4	96	0.05	0.092	5
1287171	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287172	Soil		17.0	70.6	39.2	218	1.9	50.6	9.6	215	2.42	25.0	3.3	1.5	86	1.2	4.5	0.3	76	0.40	0.079	7
1287173	Soil		44.4	99.4	29.6	500	1.4	123.5	13.1	318	2.95	38.9	3.4	1.8	94	3.4	8.6	0.4	174	0.92	0.077	9
1287174	Soil		140.4	165.5	18.9	2231	2.5	323.8	8.8	107	1.97	88.0	<0.5	1.5	281	18.7	44.0	0.2	953	8.10	0.100	9
1287175	Soil		118.6	157.9	17.4	1753	2.9	344.2	7.2	136	1.78	69.7	2.0	1.2	273	16.3	31.3	0.2	824	7.64	0.111	11
1287176	Soil		67.1	68.5	9.2	270	0.3	162.5	7.8	198	2.29	42.6	1.0	2.4	237	2.7	4.4	<0.1	63	8.91	0.065	9
1287177	Soil		103.2	167.9	28.1	2534	2.5	305.1	10.4	191	2.21	86.5	1.2	2.3	222	18.6	38.3	0.2	712	6.97	0.163	15
1287178	Soil		84.1	276.4	70.7	8281	4.2	188.4	15.8	475	4.30	57.2	6.0	3.8	69	50.8	18.0	0.3	224	1.89	0.133	10
1287179	Soil		58.5	110.8	25.8	705	0.9	142.8	12.0	214	3.32	39.3	0.9	3.4	124	4.3	9.2	0.2	108	3.70	0.141	8
1287180	Soil		18.5	200.1	67.7	235	3.4	58.7	11.6	232	5.86	51.8	10.6	2.3	105	1.6	6.9	0.3	84	0.84	0.661	18
1287821	Soil		18.4	56.0	105.3	141	4.0	19.1	3.5	72	4.62	867.0	205.0	2.6	95	0.7	47.6	4.4	72	0.08	0.180	25
1287822	Soil		14.9	49.5	78.0	129	3.4	20.4	2.9	56	3.73	664.9	143.2	1.3	78	0.5	34.7	3.5	53	0.17	0.141	21
1287823	Soil		7.7	45.9	29.0	117	2.1	27.2	4.3	89	2.24	138.3	30.8	1.6	49	0.6	21.3	0.6	40	0.11	0.081	11
1287824	Soil		9.5	81.9	31.2	223	5.8	80.9	6.1	187	3.13	107.9	41.1	1.7	76	1.1	12.5	0.6	45	0.57	0.109	9
1287825	Soil		2.0	29.3	14.0	67	1.0	24.1	2.8	61	1.07	29.5	13.5	0.8	39	1.3	3.4	0.3	31	0.61	0.055	5
1287826	Soil		4.5	53.7	14.4	157	1.2	44.8	6.2	85	2.01	43.5	12.8	2.2	49	0.9	4.1	0.3	42	0.45	0.074	7
1287827	Soil		13.4	137.7	15.8	603	0.9	68.8	7.1	101	2.48	48.5	2.1	0.7	13	2.6	7.1	0.2	256	0.41	0.236	15
1287828	Soil		54.1	87.8	73.0	1158	1.4	136.0	10.6	199	2.75	163.4	2.7	5.0	36	10.2	17.8	0.3	543	0.57	0.148	19
1287829	Soil		12.0	73.5	24.1	679	0.9	77.2	8.2	166	2.23	49.4	1.5	4.2	21	5.6	6.0	0.2	260	0.63	0.148	14
1287830	Soil		7.8	94.2	18.8	695	0.7	69.7	10.4	192	2.44	31.7	3.6	2.3	19	2.3	4.2	0.2	222	0.29	0.132	6
1287831	Soil		12.9	170.9	32.3	1180	1.9	132.9	23.4	276	3.88	45.9	4.2	4.9	30	5.8	6.6	0.3	276	0.43	0.164	8
1287832	Soil		7.4	133.1	19.3	733	1.9	75.3	14.1	187	2.91	32.2	3.7	3.2	34	5.9	4.2	0.2	200	0.69	0.139	6
1287833	Soil		8.9	118.1	25.2	898	1.5	87.7	17.1	197	2.88	38.4	3.6	3.5	40	7.8	4.8	0.2	268	0.88	0.121	6
1287834	Soil		9.5	137.7	26.7	1084	1.1	108.4	13.7	187	3.14	54.1	2.3	5.2	37	6.4	6.7	0.2	395	0.90	0.164	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287165	Soil	17	0.11	446	0.002	4	0.65	0.007	0.12	1.1	11.43	1.8	1.5	0.17	2	8.8	<0.2
1287166	Soil	20	0.14	623	0.002	4	0.84	0.005	0.09	0.2	2.43	2.6	0.5	0.06	2	3.7	<0.2
1287167	Soil	20	0.14	614	0.003	5	0.71	0.010	0.08	0.1	3.05	2.4	1.5	0.09	2	3.5	<0.2
1287168	Soil	22	0.12	680	0.002	8	0.71	0.008	0.10	0.2	6.56	2.5	0.8	0.05	2	4.9	<0.2
1287169	Soil	30	0.05	992	0.005	3	0.61	0.003	0.05	<0.1	0.22	1.5	0.1	0.06	2	12.1	<0.2
1287170	Soil	28	0.03	843	0.001	4	0.38	0.008	0.23	<0.1	0.34	3.3	0.7	0.53	3	13.4	<0.2
1287171	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287172	Soil	18	0.11	524	0.010	5	0.35	0.006	0.15	<0.1	0.29	4.4	0.6	0.23	2	5.1	<0.2
1287173	Soil	23	0.21	524	0.002	8	0.43	0.006	0.15	0.1	0.40	4.3	1.1	0.17	2	5.9	<0.2
1287174	Soil	56	1.28	519	0.003	12	0.61	0.005	0.18	0.3	0.95	2.1	2.1	0.18	3	14.5	<0.2
1287175	Soil	51	1.06	822	0.006	9	0.55	0.005	0.17	0.4	0.76	2.7	3.7	0.22	2	10.2	<0.2
1287176	Soil	12	2.78	253	0.001	5	0.20	0.005	0.07	0.1	0.66	2.3	1.3	0.13	<1	3.0	<0.2
1287177	Soil	42	1.65	342	0.005	13	0.52	0.006	0.21	0.2	1.03	3.1	2.5	0.21	2	7.9	<0.2
1287178	Soil	20	0.76	1503	0.002	7	0.58	0.004	0.13	0.2	1.22	4.4	0.8	0.21	3	5.9	0.2
1287179	Soil	17	1.59	365	0.002	9	0.38	0.005	0.14	<0.1	0.80	3.6	0.6	0.24	<1	7.7	<0.2
1287180	Soil	16	0.07	2155	0.006	9	0.89	0.005	0.18	<0.1	0.54	4.5	0.6	0.37	2	6.6	<0.2
1287821	Soil	17	0.09	312	0.003	4	0.63	0.010	0.18	1.9	23.00	1.2	3.9	0.39	3	13.9	0.2
1287822	Soil	14	0.08	510	0.002	4	0.59	0.011	0.15	1.6	17.38	0.8	2.7	0.32	3	8.8	<0.2
1287823	Soil	16	0.07	703	0.002	4	0.54	0.004	0.10	0.2	12.38	2.0	0.5	0.12	2	7.6	<0.2
1287824	Soil	26	0.12	1060	0.001	5	0.75	0.006	0.10	0.1	8.46	3.4	0.4	0.12	2	8.9	<0.2
1287825	Soil	11	0.06	442	0.002	3	0.45	0.011	0.05	<0.1	1.28	1.5	0.2	0.08	1	3.1	<0.2
1287826	Soil	23	0.18	964	0.001	4	0.79	0.007	0.08	<0.1	0.85	2.9	0.2	0.05	2	2.0	<0.2
1287827	Soil	44	1.55	105	0.026	2	1.91	0.009	0.13	0.1	0.08	1.3	0.7	<0.05	6	2.1	<0.2
1287828	Soil	65	1.89	172	0.063	2	1.87	0.008	0.39	0.3	0.15	3.1	1.2	0.11	6	10.0	<0.2
1287829	Soil	44	1.92	166	0.072	1	2.18	0.006	0.19	0.2	0.07	2.0	0.7	<0.05	6	1.9	<0.2
1287830	Soil	40	1.46	296	0.066	1	2.65	0.015	0.24	0.1	0.03	1.5	0.4	<0.05	7	2.9	<0.2
1287831	Soil	52	2.21	297	0.084	2	3.82	0.011	0.41	0.1	0.07	2.7	0.6	0.06	8	3.4	<0.2
1287832	Soil	40	1.72	305	0.075	2	2.98	0.016	0.38	0.1	0.07	2.1	0.4	0.06	8	3.7	<0.2
1287833	Soil	47	2.27	300	0.079	2	3.07	0.021	0.43	<0.1	0.06	2.6	0.4	0.06	8	3.0	<0.2
1287834	Soil	64	2.85	401	0.118	2	3.61	0.018	0.64	0.2	0.07	3.4	0.6	0.08	10	2.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287835	Soil		3.0	70.6	16.9	410	0.7	64.1	13.5	327	2.74	21.2	3.2	3.2	40	2.6	1.7	0.2	200	1.12	0.113	10
1287836	Soil		1.1	21.1	12.4	156	0.3	28.6	6.3	206	1.76	13.1	3.4	3.6	69	0.9	1.5	0.2	82	1.23	0.076	7
1287837	Soil		0.9	12.5	8.7	68	0.2	15.9	5.5	274	1.36	5.7	1.0	2.9	302	0.6	0.8	0.1	36	9.86	0.076	6
1287838	Soil		0.3	6.3	6.8	31	<0.1	8.7	3.3	232	1.29	2.9	0.8	2.5	166	0.1	0.6	<0.1	38	2.04	0.034	6
1287839	Soil		1.0	37.7	10.4	135	0.2	21.1	7.0	296	1.64	8.7	3.9	2.8	59	1.1	0.8	0.1	66	1.32	0.091	8
1287840	Soil		1.0	44.9	10.8	100	0.4	29.1	12.1	385	2.63	18.8	5.3	2.5	102	0.8	0.9	0.2	64	5.39	0.075	9
1287841	Soil		1.8	52.0	12.5	94	0.3	32.8	15.5	607	3.00	50.4	13.8	2.0	188	1.0	1.6	0.2	47	11.56	0.080	9
1287842	Soil		2.2	47.4	10.8	120	0.3	37.8	13.8	503	2.53	19.6	4.1	2.8	42	1.0	1.4	0.2	154	1.34	0.072	8
1287843	Soil		22.7	44.2	18.3	457	0.5	107.9	9.4	203	1.92	53.5	0.9	6.1	19	3.5	6.0	0.3	408	1.16	0.084	12
1287844	Soil		13.0	46.9	15.8	484	0.7	99.9	9.3	207	1.96	30.8	1.0	3.4	24	3.5	4.7	0.2	329	0.95	0.184	15
1287845	Soil		30.9	45.3	34.4	670	0.5	86.5	8.8	143	2.00	57.4	1.6	1.0	11	2.9	8.6	0.3	496	0.10	0.069	13
1287846	Soil		0.7	17.0	4.0	15	0.1	3.2	1.0	26	0.50	5.0	1.3	0.1	6	<0.1	0.4	0.1	13	0.04	0.026	2
1287847	Soil		1.9	43.5	12.3	42	0.7	9.0	2.1	69	1.68	24.6	19.9	0.5	11	<0.1	2.3	0.2	27	0.08	0.067	4
1287848	Soil		1.2	20.0	4.9	18	0.5	4.7	1.4	36	0.79	10.0	1.8	0.2	9	0.1	0.7	<0.1	20	0.11	0.056	3
1287849	Soil		8.1	175.6	62.4	206	1.2	42.6	6.3	239	8.80	116.1	9.1	9.2	32	0.1	10.3	0.6	92	0.03	0.181	13
1287850	Soil		0.2	6.1	0.9	3	0.1	1.0	0.4	11	0.17	0.8	<0.5	<0.1	5	<0.1	<0.1	<0.1	3	0.02	0.011	<1
1287891	Soil		1.5	29.0	11.4	112	0.8	33.1	4.6	161	2.23	10.8	4.1	0.6	60	0.9	1.0	0.2	48	1.54	0.215	18
1287892	Soil		1.0	16.9	4.5	36	0.4	8.8	2.4	83	0.98	4.7	1.6	<0.1	9	0.1	0.4	0.2	14	0.04	0.049	2
1287893	Soil		2.6	49.7	11.6	123	0.4	40.6	7.6	168	2.57	19.5	8.6	1.2	19	0.3	1.9	0.2	37	0.06	0.070	8
1287894	Soil		3.0	30.9	11.8	82	0.7	21.9	4.3	115	2.51	24.7	15.8	0.3	12	0.2	2.3	0.2	52	0.04	0.077	7
1287895	Soil		1.6	16.3	19.7	18	0.9	4.8	1.1	36	1.63	11.1	2.7	1.2	15	<0.1	2.3	0.2	19	0.05	0.023	2
1287896	Soil		1.6	18.7	15.0	34	0.6	9.8	2.3	44	1.30	9.1	2.5	0.6	15	<0.1	1.3	0.2	24	0.02	0.047	4
1287897	Soil		2.3	20.3	16.2	51	0.8	12.2	2.1	44	1.42	11.7	3.9	0.6	18	0.1	0.9	0.3	37	0.02	0.066	4
1287898	Soil		2.5	40.8	16.4	121	1.0	38.2	8.6	211	3.02	21.1	3.0	1.4	26	0.3	2.5	0.3	31	0.08	0.121	4
1287899	Soil		2.4	40.7	17.7	92	1.1	25.9	4.3	150	2.54	20.8	4.0	1.0	33	0.2	1.7	0.3	36	0.02	0.081	5
1287900	Soil		2.7	40.4	10.3	100	0.6	32.3	6.9	152	2.22	10.8	4.4	1.7	19	0.3	1.3	0.2	31	0.06	0.057	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001945.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287835	Soil	50	2.92	379	0.087	1	3.14	0.024	0.15	<0.1	0.02	4.1	0.4	<0.05	9	<0.5	<0.2
1287836	Soil	28	2.56	644	0.085	1	2.59	0.054	0.33	<0.1	0.01	3.2	0.4	<0.05	7	<0.5	<0.2
1287837	Soil	22	2.09	669	0.042	1	1.86	0.048	0.26	<0.1	0.01	2.5	0.2	0.07	5	<0.5	<0.2
1287838	Soil	27	2.87	384	0.050	<1	2.51	0.106	0.09	<0.1	0.01	2.9	0.2	<0.05	7	<0.5	<0.2
1287839	Soil	24	2.13	477	0.057	1	2.08	0.059	0.22	<0.1	<0.01	2.9	0.3	<0.05	6	<0.5	<0.2
1287840	Soil	28	2.41	421	0.080	1	2.14	0.019	0.21	<0.1	0.02	3.7	0.2	0.08	7	<0.5	<0.2
1287841	Soil	22	1.65	400	0.073	1	1.68	0.017	0.24	<0.1	0.02	3.4	0.2	0.10	5	0.6	<0.2
1287842	Soil	39	1.88	213	0.128	2	2.12	0.035	0.18	0.1	0.02	3.8	0.3	<0.05	7	<0.5	<0.2
1287843	Soil	57	2.88	135	0.071	1	2.10	0.005	0.30	0.2	0.04	3.2	1.3	<0.05	6	1.0	<0.2
1287844	Soil	55	2.23	93	0.039	2	1.78	0.010	0.23	0.2	0.03	2.7	0.7	<0.05	5	1.4	<0.2
1287845	Soil	39	1.37	69	0.041	2	1.37	0.009	0.10	0.3	0.08	1.8	0.6	<0.05	4	3.6	<0.2
1287846	Soil	4	0.04	14	0.019	<1	0.50	0.023	0.02	<0.1	0.01	0.2	<0.1	<0.05	2	<0.5	<0.2
1287847	Soil	11	0.15	41	0.022	<1	0.79	0.018	0.06	0.1	0.03	0.7	0.2	<0.05	2	1.4	<0.2
1287848	Soil	6	0.06	24	0.022	<1	0.41	0.023	0.03	<0.1	0.03	0.4	<0.1	<0.05	1	0.6	<0.2
1287849	Soil	42	0.61	167	0.056	<1	1.93	0.008	0.29	0.1	0.05	3.7	0.6	0.20	6	8.5	0.2
1287850	Soil	<1	0.01	13	0.007	<1	0.25	0.021	0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
1287891	Soil	30	0.20	596	0.005	4	0.99	0.007	0.06	<0.1	0.12	1.9	<0.1	0.25	2	1.4	<0.2
1287892	Soil	5	0.05	77	0.004	1	0.49	0.015	0.03	<0.1	0.04	0.3	<0.1	<0.05	2	0.5	<0.2
1287893	Soil	19	0.20	117	0.007	1	1.13	0.009	0.05	0.1	0.06	2.1	0.1	<0.05	3	0.9	<0.2
1287894	Soil	20	0.09	132	0.006	1	0.79	0.004	0.04	0.2	0.10	0.8	0.1	<0.05	3	1.6	<0.2
1287895	Soil	11	0.04	368	<0.001	2	0.29	0.007	0.12	<0.1	0.20	1.1	0.2	0.17	2	3.5	<0.2
1287896	Soil	15	0.08	274	0.002	2	0.66	0.008	0.06	<0.1	0.06	0.8	0.1	<0.05	3	1.5	<0.2
1287897	Soil	15	0.03	253	0.001	<1	0.50	0.005	0.07	<0.1	0.07	0.6	0.2	<0.05	2	1.8	<0.2
1287898	Soil	23	0.06	569	0.002	3	0.76	0.006	0.11	<0.1	0.15	2.6	0.2	<0.05	2	2.8	<0.2
1287899	Soil	19	0.07	257	0.002	1	0.69	0.005	0.10	<0.1	0.07	1.3	0.2	0.08	3	2.3	<0.2
1287900	Soil	16	0.16	118	0.005	<1	0.68	0.003	0.05	0.1	0.08	1.8	0.1	<0.05	2	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

QUALITY CONTROL REPORT WHI11001945.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1279103	Soil	13.1	46.6	112.5	126	7.1	13.2	2.7	22	11.77	1851	553.2	10.6	163	0.4	156.5	5.2	54	0.01	0.230	25
REP 1279103	QC	13.3	45.2	110.2	129	6.9	12.7	2.6	22	11.60	1842	557.0	10.5	161	0.4	155.2	5.1	54	0.01	0.235	25
1288714	Soil	25.8	68.6	119.8	22	4.8	4.9	0.5	9	0.77	62.6	33.0	2.7	137	0.6	61.3	0.3	186	0.03	0.078	17
REP 1288714	QC	25.4	69.1	119.5	22	4.8	4.8	0.5	9	0.77	62.3	26.9	2.6	132	0.6	60.3	0.3	189	0.03	0.077	16
1287859	Soil	3.8	72.3	41.6	233	1.7	70.6	21.4	582	7.43	48.6	6.0	2.6	52	0.6	1.9	0.3	37	0.52	0.119	4
REP 1287859	QC	3.6	74.3	41.4	239	1.6	71.0	21.5	572	7.22	48.2	7.8	2.5	53	0.7	1.9	0.3	38	0.53	0.123	4
1288268	Soil	3.0	53.1	14.8	72	0.5	22.8	2.6	57	2.59	92.2	42.4	1.3	60	0.2	3.7	0.2	43	0.02	0.070	8
REP 1288268	QC	3.0	52.2	15.1	74	0.5	22.7	2.7	57	2.61	92.8	43.5	1.3	61	0.2	3.7	0.2	42	0.02	0.067	9
1288514	Soil	7.8	32.7	23.9	125	0.3	26.5	4.1	71	2.14	104.3	5.1	1.0	21	0.4	6.3	0.6	73	0.02	0.056	20
REP 1288514	QC	8.0	30.9	23.9	119	0.3	24.8	4.0	67	2.03	102.0	7.1	1.2	21	0.4	6.1	0.6	69	0.02	0.056	21
1287062	Soil	3.1	38.8	18.6	66	0.2	25.0	6.5	138	2.42	186.2	3.4	0.3	9	0.2	2.0	0.4	40	0.03	0.058	7
REP 1287062	QC	3.3	38.8	18.9	69	0.2	25.3	6.5	144	2.50	190.6	2.8	0.2	9	0.2	2.0	0.3	41	0.03	0.059	7
1287906	Soil	21.5	48.5	19.6	290	0.9	61.7	8.4	288	1.94	18.1	2.1	0.7	30	2.9	4.1	0.3	103	0.14	0.062	6
REP 1287906	QC	20.3	44.7	19.5	271	0.9	58.8	7.9	276	1.82	17.6	3.0	0.7	29	3.1	3.9	0.3	97	0.14	0.063	6
1287910	Soil	19.1	16.9	11.0	101	1.2	24.3	2.1	24	0.57	9.5	0.6	0.2	13	0.3	3.4	0.1	136	0.03	0.041	8
REP 1287910	QC	18.8	16.8	11.2	101	1.2	22.5	2.0	24	0.56	9.7	1.0	0.2	15	0.3	3.2	0.1	147	0.03	0.041	9
1288286	Soil	4.9	46.6	18.3	169	0.6	37.8	8.4	115	3.30	19.7	1.9	1.3	16	0.5	1.6	0.3	43	0.02	0.066	4
REP 1288286	QC	4.7	46.6	18.6	170	0.6	37.0	8.2	113	3.26	19.3	2.1	1.3	17	0.5	1.6	0.3	42	0.01	0.066	4
1287172	Soil	17.0	70.6	39.2	218	1.9	50.6	9.6	215	2.42	25.0	3.3	1.5	86	1.2	4.5	0.3	76	0.40	0.079	7
REP 1287172	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287830	Soil	7.8	94.2	18.8	695	0.7	69.7	10.4	192	2.44	31.7	3.6	2.3	19	2.3	4.2	0.2	222	0.29	0.132	6
REP 1287830	QC	8.6	95.9	18.3	735	0.6	68.0	10.8	198	2.49	33.3	4.7	2.1	20	2.5	4.5	0.2	220	0.29	0.137	6
1287845	Soil	30.9	45.3	34.4	670	0.5	86.5	8.8	143	2.00	57.4	1.6	1.0	11	2.9	8.6	0.3	496	0.10	0.069	13
REP 1287845	QC	30.8	47.5	33.2	684	0.5	86.8	8.9	143	1.96	57.6	1.4	1.2	11	2.9	9.0	0.3	486	0.10	0.068	15
1287891	Soil	1.5	29.0	11.4	112	0.8	33.1	4.6	161	2.23	10.8	4.1	0.6	60	0.9	1.0	0.2	48	1.54	0.215	18
REP 1287891	QC	1.5	27.6	10.7	105	0.8	32.1	4.5	153	2.19	9.0	3.5	0.5	57	0.8	0.8	0.2	43	1.45	0.194	17
Reference Materials																					
STD DS8	Standard	12.7	118.0	129.1	311	1.7	40.6	7.8	600	2.44	25.5	114.0	6.9	67	2.4	5.2	6.8	45	0.69	0.074	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

QUALITY CONTROL REPORT WHI11001945.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1279103	Soil	20	0.05	118	0.003	7	0.60	0.017	0.42	1.7	31.57	2.1	7.9	1.45	4	26.3	0.4
REP 1279103	QC	20	0.05	132	0.014	8	0.61	0.018	0.45	1.6	30.79	2.2	7.7	1.48	4	24.4	0.3
1288714	Soil	20	0.01	459	0.002	5	0.43	0.003	0.09	2.2	9.64	1.3	2.2	0.10	2	20.6	0.4
REP 1288714	QC	20	0.01	456	0.004	5	0.44	0.003	0.09	2.2	8.60	1.3	2.1	0.12	2	20.4	0.2
1287859	Soil	27	0.21	388	0.002	3	1.11	0.004	0.10	<0.1	0.50	6.6	0.2	0.08	3	4.3	<0.2
REP 1287859	QC	27	0.20	371	0.001	3	1.06	0.005	0.09	<0.1	0.49	6.5	0.2	0.09	3	4.3	<0.2
1288268	Soil	22	0.04	249	0.003	2	0.57	0.002	0.08	0.1	1.38	1.5	0.1	0.07	3	4.3	0.3
REP 1288268	QC	22	0.04	253	0.004	2	0.57	0.002	0.08	0.2	1.42	1.5	0.1	0.06	3	3.7	<0.2
1288514	Soil	11	0.04	122	0.004	2	0.61	0.003	0.05	0.3	0.68	0.9	0.3	<0.05	4	1.9	<0.2
REP 1288514	QC	10	0.04	125	0.003	1	0.62	0.003	0.05	0.3	0.73	0.9	0.3	<0.05	3	1.8	<0.2
1287062	Soil	11	0.03	98	0.004	<1	0.41	0.004	0.04	0.1	0.10	0.9	0.2	<0.05	2	0.9	<0.2
REP 1287062	QC	11	0.03	98	0.004	1	0.41	0.002	0.04	0.1	0.08	0.8	0.2	<0.05	2	1.5	<0.2
1287906	Soil	13	0.05	329	0.002	3	0.50	0.005	0.07	0.1	0.16	2.3	0.6	0.06	2	2.1	<0.2
REP 1287906	QC	13	0.05	336	0.001	3	0.49	0.005	0.07	<0.1	0.15	2.2	0.5	0.06	1	1.6	<0.2
1287910	Soil	14	0.05	144	0.003	4	0.39	0.004	0.05	0.1	0.04	0.4	0.5	<0.05	3	0.8	<0.2
REP 1287910	QC	15	0.05	137	0.003	3	0.39	0.004	0.05	0.1	0.04	0.4	0.5	<0.05	3	0.7	<0.2
1288286	Soil	13	0.09	900	0.002	<1	0.59	0.003	0.05	<0.1	0.07	3.2	0.1	<0.05	2	1.8	<0.2
REP 1288286	QC	13	0.09	911	0.002	1	0.59	0.002	0.05	<0.1	0.07	3.2	0.1	<0.05	2	1.4	<0.2
1287172	Soil	18	0.11	524	0.010	5	0.35	0.006	0.15	<0.1	0.29	4.4	0.6	0.23	2	5.1	<0.2
REP 1287172	QC	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287830	Soil	40	1.46	296	0.066	1	2.65	0.015	0.24	0.1	0.03	1.5	0.4	<0.05	7	2.9	<0.2
REP 1287830	QC	39	1.42	297	0.072	<1	2.67	0.018	0.24	0.2	0.06	1.3	0.4	0.08	7	3.0	<0.2
1287845	Soil	39	1.37	69	0.041	2	1.37	0.009	0.10	0.3	0.08	1.8	0.6	<0.05	4	3.6	<0.2
REP 1287845	QC	39	1.38	69	0.046	1	1.38	0.009	0.10	0.3	0.06	1.8	0.7	<0.05	5	3.5	<0.2
1287891	Soil	30	0.20	596	0.005	4	0.99	0.007	0.06	<0.1	0.12	1.9	<0.1	0.25	2	1.4	<0.2
REP 1287891	QC	29	0.16	564	0.003	3	0.91	0.006	0.05	<0.1	0.11	1.6	<0.1	0.13	2	1.0	<0.2
Reference Materials																	
STD DS8	Standard	124	0.61	267	0.120	3	0.98	0.111	0.44	2.9	0.20	4.7	5.5	0.16	5	5.2	5.1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

QUALITY CONTROL REPORT WHI11001945.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	12.6	103.3	122.4	291	1.8	36.5	6.9	573	2.23	25.5	101.3	7.1	65	2.1	5.8	6.9	40	0.66	0.078	14
STD DS8	Standard	12.9	108.0	117.6	302	1.8	37.5	7.3	589	2.40	26.1	110.2	7.0	69	2.4	5.7	6.9	42	0.68	0.079	15
STD DS8	Standard	13.6	113.3	120.5	313	1.8	37.9	7.6	620	2.45	27.3	105.4	6.8	71	2.4	6.1	6.7	43	0.71	0.076	17
STD DS8	Standard	11.7	99.5	122.3	291	1.8	35.9	7.1	565	2.33	25.4	116.0	6.6	69	2.1	5.4	6.4	38	0.66	0.075	15
STD DS8	Standard	13.3	106.5	124.4	292	1.8	36.6	7.0	587	2.39	24.7	112.1	6.7	62	2.2	5.0	6.3	40	0.68	0.079	16
STD DS8	Standard	12.4	102.5	119.3	295	1.7	35.1	7.1	584	2.39	25.7	99.0	6.5	65	2.2	5.4	5.5	39	0.66	0.074	15
STD DS8	Standard	12.6	104.3	117.1	271	1.6	36.2	7.2	547	2.23	24.0	101.6	6.6	58	2.1	4.7	5.7	40	0.63	0.069	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

QUALITY CONTROL REPORT WHI11001945.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
STD DS8	Standard	111	0.59	278	0.105	2	0.89	0.102	0.42	2.8	0.20	2.1	5.4	0.16	4	4.3	4.9
STD DS8	Standard	115	0.60	287	0.113	2	0.93	0.105	0.43	3.1	0.20	2.6	5.2	0.15	5	5.1	4.8
STD DS8	Standard	120	0.60	290	0.130	4	0.99	0.090	0.44	3.0	0.09	2.7	5.4	0.16	5	5.3	4.5
STD DS8	Standard	107	0.58	265	0.109	2	0.88	0.091	0.40	2.9	0.21	2.2	5.2	0.16	4	4.9	4.6
STD DS8	Standard	109	0.58	274	0.109	3	0.87	0.102	0.40	3.1	0.19	2.4	5.3	0.16	5	4.7	4.7
STD DS8	Standard	113	0.58	260	0.110	3	0.90	0.096	0.44	2.7	0.23	2.0	4.8	0.12	5	4.3	4.6
STD DS8	Standard	111	0.55	251	0.108	2	0.83	0.080	0.36	2.7	0.18	2.1	5.1	0.13	4	4.6	4.6
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 22, 2011
Report Date: December 01, 2011
Page: 1 of 9

CERTIFICATE OF ANALYSIS WHI11001946.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #30
P.O. Number
Number of Samples:

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	220	Sieve soil to 230 mesh			VAN
RJSV	220	Saving all or part of Soil Reject			VAN
1DX2	220	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1284481	Soil		11.7	57.5	15.5	204	0.7	45.9	5.6	103	1.90	33.0	4.9	1.6	70	1.9	6.9	0.2	90	0.19	0.113
1284482	Soil		17.5	39.9	11.7	370	0.5	98.0	10.5	139	3.09	57.2	2.9	1.0	11	0.6	5.9	0.3	99	0.04	0.111
1284483	Soil		50.2	54.7	11.3	548	0.5	174.5	12.9	238	2.87	56.7	2.4	1.5	27	4.4	5.8	0.2	158	0.32	0.074
1284484	Soil		111.6	130.2	11.4	1194	0.4	361.9	19.5	388	2.79	74.1	2.1	1.8	35	31.8	9.4	0.2	172	0.29	0.118
1284485	Soil		61.5	33.7	32.1	76	7.4	13.4	1.3	23	1.62	38.3	5.5	0.6	134	3.6	37.4	0.6	310	0.03	0.104
1284486	Soil		32.2	21.9	16.1	40	2.3	7.5	1.0	27	0.94	51.6	5.9	0.3	64	0.4	40.1	0.3	229	0.03	0.064
1284487	Soil		55.3	29.5	11.8	24	3.3	8.5	0.5	10	0.97	183.1	24.2	0.8	35	0.4	27.3	0.2	161	0.01	0.052
1284488	Soil		54.1	52.1	34.2	99	4.1	17.2	1.1	15	1.52	424.7	116.6	3.2	150	1.8	217.1	0.2	260	0.03	0.066
1284489	Soil		88.5	82.3	48.8	43	6.6	9.8	1.1	24	2.34	212.2	13.0	2.5	443	1.0	182.2	0.4	361	0.07	0.171
1284490	Soil		18.8	55.7	27.2	15	3.6	4.4	0.4	7	0.69	42.6	17.0	0.6	45	0.2	43.9	0.3	158	0.03	0.059
1286901	Soil		20.9	48.3	27.8	267	1.2	74.7	8.9	173	1.84	57.9	17.5	1.6	60	2.1	17.3	0.2	132	0.16	0.117
1286902	Soil		13.5	50.6	19.3	144	1.8	54.4	5.2	201	1.79	82.9	22.0	1.0	65	3.5	12.2	0.3	168	0.29	0.137
1286903	Soil		5.8	42.8	9.3	112	1.2	46.2	4.2	70	1.20	26.6	12.4	0.7	36	3.1	5.2	0.1	57	0.23	0.098
1286904	Soil		15.1	120.3	18.4	458	1.2	109.4	70.2	1517	1.99	52.9	15.2	1.6	48	4.6	11.0	0.2	132	0.17	0.127
1286905	Soil		8.6	93.8	17.9	303	0.9	67.0	16.3	288	2.34	72.5	9.0	2.4	43	2.8	7.6	0.3	75	0.16	0.101
1286906	Soil		9.2	46.7	16.7	267	0.8	55.2	17.8	341	2.32	82.2	10.5	2.1	38	2.2	8.5	0.3	82	0.17	0.089
1286907	Soil		6.7	55.8	23.7	428	0.8	92.9	23.5	2988	2.67	178.6	12.8	3.5	30	8.3	14.0	0.3	65	0.12	0.070
1286908	Soil		8.0	60.2	16.0	341	1.0	70.8	9.9	217	2.29	62.6	10.3	2.6	56	4.2	7.4	0.3	85	0.23	0.085
1286909	Soil		11.2	55.3	18.7	416	1.3	77.9	16.8	609	2.35	87.3	13.4	2.2	58	6.3	9.3	0.3	112	0.29	0.101
1286910	Soil		9.3	91.5	17.7	489	1.3	109.0	15.7	579	2.89	156.9	15.6	1.9	62	5.5	8.4	0.3	79	0.27	0.101
1286931	Soil		4.9	12.9	10.6	54	0.4	11.4	3.1	45	1.58	46.5	6.2	0.2	21	0.4	4.1	0.2	50	0.04	0.066
1286932	Soil		9.9	23.3	41.1	110	0.5	21.5	4.9	138	2.59	66.9	10.4	1.9	57	0.8	6.5	0.3	83	0.06	0.071
1286933	Soil		7.9	16.4	34.4	80	0.7	12.5	3.7	60	1.86	71.0	13.6	0.7	43	0.2	7.9	0.3	55	0.01	0.081
1286934	Soil		3.4	27.4	14.9	48	0.8	10.8	2.4	39	1.61	89.4	14.8	0.5	19	0.4	4.4	0.3	27	0.03	0.099
1286935	Soil		3.9	41.8	24.2	84	1.5	14.1	3.1	162	4.94	302.8	8.5	1.0	15	0.8	9.4	0.8	61	0.07	0.130
1286936	Soil		7.9	49.0	43.4	72	1.9	10.7	3.2	35	5.63	620.0	95.9	8.5	14	0.3	19.0	5.7	46	0.01	0.081
1286937	Soil		4.7	25.0	43.9	59	2.1	9.5	2.1	79	4.31	479.4	5.4	2.2	19	0.4	8.0	3.8	70	0.02	0.104
1286938	Soil		2.9	23.2	19.4	40	0.6	6.2	1.5	80	2.71	186.2	3.8	1.8	13	0.3	4.9	2.6	51	0.03	0.077
1286939	Soil		8.2	31.0	35.9	85	1.5	15.4	3.6	105	6.76	443.4	10.5	3.9	32	0.2	10.4	2.5	93	0.03	0.129
1286940	Soil		3.9	23.1	13.0	40	0.5	11.5	2.4	41	1.34	85.7	7.0	0.4	12	0.3	3.4	0.6	36	0.06	0.074

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284481	Soil	8	18	0.07	1077	0.004	2	0.44	0.003	0.06	0.1	0.74	2.5	0.4	0.09	1	2.2	<0.2
1284482	Soil	19	14	0.03	291	0.005	3	0.44	0.004	0.06	0.1	0.25	1.4	0.4	<0.05	2	2.5	<0.2
1284483	Soil	16	29	0.12	556	0.007	3	0.97	0.004	0.06	0.4	0.21	2.1	1.4	<0.05	3	2.6	<0.2
1284484	Soil	15	22	0.05	477	0.003	4	1.13	0.005	0.06	0.6	0.48	3.2	2.1	<0.05	1	3.8	<0.2
1284485	Soil	17	25	0.02	701	0.005	4	0.47	0.006	0.21	1.9	4.07	0.8	12.2	0.41	4	17.6	0.3
1284486	Soil	10	16	0.02	313	0.005	4	0.39	0.016	0.11	1.8	3.99	0.4	4.9	0.15	3	11.2	0.4
1284487	Soil	8	10	0.02	247	0.001	3	0.48	0.003	0.08	1.1	12.00	0.9	3.0	0.06	1	8.2	<0.2
1284488	Soil	12	15	0.01	614	0.002	4	0.36	0.003	0.17	2.5	>50	1.2	8.8	0.24	2	14.6	1.5
1284489	Soil	22	37	0.02	486	0.004	5	0.46	0.006	0.20	5.2	13.51	1.7	5.5	0.44	4	30.7	1.0
1284490	Soil	15	16	<0.01	304	0.002	4	0.31	0.002	0.07	1.2	9.65	0.6	2.3	0.07	2	9.3	0.4
1286901	Soil	15	16	0.04	872	0.005	3	0.49	0.004	0.09	0.4	3.00	2.2	1.2	<0.05	2	5.8	<0.2
1286902	Soil	9	20	0.06	1218	0.003	3	0.60	0.007	0.06	0.3	3.07	2.3	1.0	0.11	2	4.6	<0.2
1286903	Soil	5	13	0.05	749	0.002	2	0.57	0.012	0.06	0.1	1.74	2.5	0.6	0.05	2	2.5	<0.2
1286904	Soil	13	22	0.13	798	0.003	5	1.05	0.007	0.10	0.2	1.90	3.9	1.0	<0.05	2	3.4	<0.2
1286905	Soil	15	20	0.15	768	0.002	3	0.91	0.004	0.08	0.2	1.22	3.5	0.6	<0.05	2	2.6	<0.2
1286906	Soil	11	19	0.15	1068	0.002	2	0.85	0.006	0.07	0.1	1.20	2.5	0.4	<0.05	2	1.9	<0.2
1286907	Soil	15	17	0.15	545	0.002	4	0.87	0.005	0.09	0.1	1.27	2.7	0.4	<0.05	2	1.8	<0.2
1286908	Soil	11	24	0.18	1695	0.002	4	0.90	0.004	0.09	0.1	1.37	3.6	0.4	<0.05	2	2.7	<0.2
1286909	Soil	12	24	0.16	1147	0.002	4	0.98	0.007	0.10	0.2	1.77	3.2	0.6	<0.05	3	3.5	<0.2
1286910	Soil	8	23	0.13	1098	0.001	4	1.34	0.008	0.10	0.1	1.66	4.3	0.6	<0.05	3	3.0	<0.2
1286931	Soil	11	6	0.01	476	0.003	4	0.26	0.014	0.05	0.1	0.58	0.6	0.3	<0.05	1	1.3	<0.2
1286932	Soil	10	15	0.06	482	0.004	3	0.81	0.003	0.09	0.2	1.05	2.3	0.6	0.05	2	3.0	<0.2
1286933	Soil	13	9	0.02	313	0.002	2	0.34	0.006	0.08	0.1	1.68	1.0	0.5	0.09	2	2.2	<0.2
1286934	Soil	8	7	0.03	202	0.004	2	0.72	0.013	0.05	0.1	1.15	0.8	0.4	<0.05	2	1.2	<0.2
1286935	Soil	14	23	0.08	209	0.007	3	0.91	0.005	0.07	0.2	1.08	1.2	0.2	0.07	4	2.4	<0.2
1286936	Soil	19	11	0.03	112	0.001	4	0.61	0.002	0.08	0.9	2.82	1.9	0.3	<0.05	2	3.7	<0.2
1286937	Soil	24	17	0.09	160	0.004	1	0.85	0.005	0.07	1.5	0.56	1.2	0.2	0.07	5	1.9	<0.2
1286938	Soil	13	14	0.13	111	0.007	1	0.76	0.014	0.05	1.6	0.39	1.0	0.2	0.06	3	1.1	<0.2
1286939	Soil	19	27	0.14	214	0.006	1	1.04	0.003	0.07	0.9	0.94	1.6	0.5	0.07	6	3.5	0.2
1286940	Soil	10	8	0.03	195	0.005	1	0.45	0.015	0.04	0.4	0.59	0.4	0.2	<0.05	2	1.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1286941	Soil		12.9	63.7	34.0	112	0.9	24.6	4.9	108	3.86	267.6	29.6	2.4	44	0.4	13.3	2.5	91	0.03	0.108
1286942	Soil		12.9	60.6	48.3	88	1.1	18.7	3.9	95	3.20	241.7	26.9	2.4	54	0.5	15.9	1.2	85	0.04	0.096
1286943	Soil		8.9	58.0	22.0	103	0.7	21.7	3.9	82	2.62	300.3	18.9	1.4	29	0.5	10.1	1.0	80	0.04	0.092
1286944	Soil		4.7	38.5	13.1	81	0.5	17.9	4.5	100	2.40	162.7	15.3	1.0	26	0.2	5.6	1.3	50	0.07	0.074
1286945	Soil		8.7	54.1	28.6	130	0.9	25.4	4.7	110	3.35	290.7	18.8	1.6	46	0.5	9.5	4.3	78	0.04	0.092
1286946	Soil		8.4	37.6	38.7	121	0.8	22.4	4.1	85	2.65	305.9	22.1	1.6	41	0.4	11.2	3.0	67	0.03	0.102
1286947	Soil		11.4	28.0	35.0	126	0.9	24.1	4.6	81	2.42	280.9	26.6	1.0	35	0.2	13.3	3.5	92	0.02	0.078
1286948	Soil		6.4	21.4	23.7	73	0.7	14.7	2.7	51	1.72	180.0	17.0	0.4	29	0.2	7.2	2.1	51	0.02	0.075
1286949	Soil		4.3	21.4	16.5	54	0.8	10.9	2.4	31	1.28	141.1	9.5	0.4	19	0.1	7.8	2.9	46	0.03	0.052
1286950	Soil		19.6	70.2	86.2	247	1.7	62.3	9.4	178	2.91	203.7	34.4	3.8	87	1.6	16.6	1.2	98	0.11	0.123
1288351	Soil		7.8	30.3	20.2	77	0.5	25.2	5.4	77	1.70	64.8	2.8	0.2	29	0.2	2.8	0.3	49	0.12	0.062
1288352	Soil		7.8	34.3	25.3	45	1.1	16.6	2.5	79	1.67	33.5	2.3	0.3	37	0.1	4.1	0.3	67	0.04	0.098
1288353	Soil		4.9	46.9	19.6	165	0.2	33.2	7.9	130	2.60	92.6	1.7	0.3	18	0.2	2.8	0.4	48	0.02	0.062
1288354	Soil		4.0	20.5	19.5	60	0.2	15.2	3.7	77	1.65	32.9	0.5	0.6	20	0.1	1.6	0.3	52	0.03	0.053
1288355	Soil		5.4	86.6	32.6	95	1.1	57.2	24.5	991	5.00	106.9	3.1	1.3	29	0.2	3.4	0.5	71	0.06	0.085
1288356	Soil		5.3	51.8	17.8	70	0.5	28.6	10.2	713	2.24	41.9	1.0	0.2	25	0.1	2.1	0.3	48	0.14	0.096
1288357	Soil		7.1	208.6	40.4	453	1.7	137.1	45.8	1251	10.01	78.4	7.4	2.0	58	5.4	6.2	0.6	135	0.31	0.170
1288358	Soil		51.4	191.4	56.1	467	5.4	116.8	3.1	81	2.09	130.6	<0.5	2.5	588	6.6	34.5	0.4	450	0.32	0.200
1288359	Soil		20.7	83.2	118.3	108	2.9	45.7	4.2	104	2.01	118.1	0.6	1.0	133	2.0	20.2	0.5	222	0.14	0.058
1288360	Soil		160.6	148.1	29.5	2577	3.2	390.5	15.2	344	2.96	133.7	0.6	1.3	374	21.1	36.6	0.2	436	7.55	0.139
1284291	Soil		2.4	11.0	12.3	39	0.8	7.9	2.1	38	0.83	3.1	<0.5	0.1	10	0.7	0.9	0.2	36	0.03	0.037
1284292	Soil		7.3	22.4	29.4	64	2.2	17.3	4.0	94	1.73	18.6	1.3	0.2	48	0.5	2.2	0.3	66	0.04	0.076
1284293	Soil		2.9	11.7	11.2	22	2.5	7.7	1.3	21	0.51	4.9	<0.5	0.1	17	0.6	0.8	<0.1	28	0.02	0.050
1284294	Soil		7.6	19.9	34.1	54	1.9	14.3	3.0	54	1.25	17.6	1.2	0.1	52	0.3	2.1	0.2	74	0.05	0.065
1284295	Soil		8.3	27.0	44.2	79	1.6	22.3	4.8	121	1.63	21.1	3.5	0.4	83	1.5	2.7	0.2	63	0.09	0.089
1284296	Soil		7.9	27.5	41.3	92	1.2	22.7	4.7	107	1.64	21.0	3.9	0.4	74	1.6	2.8	0.2	64	0.10	0.074
1284297	Soil		6.1	39.4	18.3	137	0.5	36.8	6.9	130	2.14	16.6	2.4	1.2	46	0.6	2.1	0.2	51	0.42	0.067
1284298	Soil		8.0	44.6	16.1	161	0.6	40.8	10.0	254	2.26	17.3	2.2	1.3	51	0.8	2.4	0.2	62	0.31	0.099
1284299	Soil		8.5	46.9	16.8	184	0.6	41.2	10.2	315	2.39	17.5	2.8	1.3	41	2.6	2.3	0.2	69	0.18	0.108
1284300	Soil		6.8	40.7	19.1	183	0.8	42.5	9.1	279	2.09	16.3	2.8	1.2	68	2.0	2.0	0.2	60	0.64	0.106

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286941	Soil	15	19	0.12	305	0.004	3	0.90	0.005	0.10	1.0	3.35	1.7	0.7	0.13	3	4.2	<0.2
1286942	Soil	16	16	0.11	393	0.004	4	0.84	0.006	0.11	0.6	4.84	1.7	0.9	0.13	3	4.2	<0.2
1286943	Soil	15	15	0.10	235	0.005	2	0.98	0.010	0.08	0.4	1.52	1.5	0.6	<0.05	3	3.0	<0.2
1286944	Soil	10	12	0.15	153	0.011	2	0.76	0.019	0.11	0.6	0.69	1.4	0.4	0.09	3	1.6	<0.2
1286945	Soil	18	16	0.13	246	0.005	2	0.97	0.009	0.11	1.2	2.57	1.5	0.7	0.17	3	3.0	0.2
1286946	Soil	17	12	0.05	201	0.004	2	0.86	0.010	0.07	0.4	3.21	0.8	0.5	0.09	2	3.1	0.2
1286947	Soil	18	10	0.03	164	0.004	2	0.64	0.006	0.06	0.6	2.64	0.7	0.5	0.05	3	3.1	<0.2
1286948	Soil	11	7	0.03	110	0.004	1	0.46	0.011	0.04	0.5	2.30	0.4	0.4	<0.05	2	2.6	<0.2
1286949	Soil	13	6	0.02	87	0.004	2	0.34	0.011	0.04	0.6	2.66	0.4	0.2	<0.05	2	1.4	<0.2
1286950	Soil	16	19	0.07	581	0.002	3	0.65	0.003	0.09	0.6	4.34	2.7	1.4	0.08	2	5.5	<0.2
1288351	Soil	5	9	0.06	691	0.003	2	0.45	0.005	0.05	<0.1	0.15	0.7	0.3	<0.05	2	1.4	<0.2
1288352	Soil	5	12	0.06	2094	0.005	1	0.84	0.005	0.05	<0.1	0.19	0.8	0.3	<0.05	3	3.5	<0.2
1288353	Soil	7	11	0.02	484	0.004	2	0.37	0.003	0.05	<0.1	0.04	1.1	0.2	<0.05	2	1.2	<0.2
1288354	Soil	7	11	0.03	254	0.002	1	0.56	0.003	0.05	0.1	0.04	1.0	0.2	<0.05	3	0.9	<0.2
1288355	Soil	5	18	0.08	260	0.005	2	0.51	0.007	0.08	<0.1	0.10	7.6	0.3	<0.05	2	3.2	<0.2
1288356	Soil	4	11	0.04	270	0.003	2	0.57	0.015	0.05	<0.1	0.10	1.9	0.3	0.05	2	1.5	<0.2
1288357	Soil	5	37	0.16	616	0.003	3	0.83	0.006	0.07	<0.1	0.31	14.3	0.5	0.12	2	5.4	<0.2
1288358	Soil	6	26	0.03	462	0.003	5	0.53	0.003	0.15	0.3	5.61	4.8	1.7	0.20	2	31.9	0.8
1288359	Soil	4	16	0.02	550	0.001	4	0.27	0.004	0.15	0.1	2.19	3.0	1.1	0.30	2	14.9	0.3
1288360	Soil	7	24	2.34	321	0.003	6	0.37	0.006	0.09	0.3	2.24	3.8	1.9	0.08	<1	10.9	0.2
1284291	Soil	8	8	0.02	136	0.006	2	0.37	0.006	0.03	<0.1	0.04	0.2	0.1	<0.05	3	<0.5	<0.2
1284292	Soil	6	14	0.06	303	0.003	3	0.54	0.004	0.05	0.1	0.12	0.4	0.4	<0.05	3	2.2	<0.2
1284293	Soil	4	7	0.02	328	0.003	1	0.27	0.009	0.03	<0.1	0.07	0.1	0.1	<0.05	2	1.0	<0.2
1284294	Soil	5	15	0.04	411	0.002	4	0.49	0.004	0.04	0.1	0.07	0.6	0.4	<0.05	3	2.6	<0.2
1284295	Soil	7	17	0.10	665	0.005	2	0.56	0.005	0.06	0.1	0.24	1.2	0.4	<0.05	2	3.0	<0.2
1284296	Soil	7	17	0.10	615	0.005	2	0.56	0.004	0.06	0.1	0.19	1.2	0.4	<0.05	3	3.3	<0.2
1284297	Soil	7	14	0.12	905	0.002	2	0.71	0.006	0.06	<0.1	0.13	2.6	0.2	<0.05	2	2.6	<0.2
1284298	Soil	6	15	0.11	1733	0.002	4	0.64	0.004	0.09	<0.1	0.12	2.7	0.3	<0.05	2	3.0	<0.2
1284299	Soil	6	18	0.11	1216	0.002	4	0.87	0.006	0.11	<0.1	0.14	3.0	0.3	<0.05	3	2.5	<0.2
1284300	Soil	6	16	0.14	1015	0.002	3	0.78	0.006	0.09	<0.1	0.21	2.8	0.3	<0.05	2	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1288551	Soil		0.9	24.6	10.9	72	0.8	21.4	6.3	400	1.16	4.2	1.7	0.7	77	1.8	0.3	0.2	24	0.83	0.089
1288552	Soil		1.0	17.2	4.8	41	0.2	15.5	4.8	138	0.88	3.3	0.8	0.4	148	0.8	0.7	0.1	10	2.01	0.073
1288553	Soil		2.4	16.9	9.6	73	<0.1	15.2	5.7	141	2.70	14.1	<0.5	0.9	12	0.1	0.8	0.2	33	0.02	0.040
1288554	Soil		4.6	17.1	13.0	96	<0.1	17.8	7.7	192	2.54	18.1	0.6	1.4	19	0.2	1.9	0.2	59	0.02	0.031
1288555	Soil		4.7	16.1	10.3	65	0.2	15.6	3.8	63	1.55	12.5	0.9	1.0	18	0.1	1.2	0.2	54	0.04	0.032
1288556	Soil		3.5	23.0	10.2	85	1.0	20.8	3.0	47	1.58	8.2	1.8	0.7	29	0.4	1.0	0.1	42	0.05	0.048
1288557	Soil		2.0	18.0	6.3	69	0.8	27.8	5.0	249	0.95	4.2	2.0	0.4	694	1.2	1.1	0.1	23	2.06	0.102
1288558	Soil		3.1	28.3	11.1	92	1.0	37.4	8.5	233	1.79	7.6	2.7	0.6	439	1.6	1.2	0.2	30	1.35	0.124
1288559	Soil		6.5	26.9	9.7	87	0.8	16.2	5.0	70	1.81	18.9	0.7	0.2	15	0.4	2.0	0.2	78	0.03	0.067
1288560	Soil		4.6	34.6	15.8	114	4.5	56.7	24.2	1380	4.46	15.1	8.2	0.8	152	1.9	1.3	0.2	44	0.52	0.232
1286951	Soil		19.5	41.3	65.6	111	1.6	13.2	2.9	47	2.93	396.6	77.5	0.9	47	0.4	24.9	2.6	47	0.04	0.140
1286952	Soil		2.8	28.7	30.4	115	0.3	28.5	7.9	77	1.29	37.3	3.0	1.5	25	0.3	1.8	0.4	28	0.04	0.041
1286953	Soil		7.2	32.3	40.6	101	0.8	23.6	4.1	119	2.21	76.8	16.3	1.7	50	0.4	6.5	0.5	68	0.16	0.076
1286954	Soil		3.4	25.8	24.6	68	2.0	17.0	2.6	63	1.31	44.1	19.7	1.1	33	0.2	3.4	0.6	31	0.16	0.059
1286955	Soil		1.8	26.5	12.1	50	1.4	13.1	1.8	101	0.71	42.2	51.7	0.6	44	0.5	7.8	0.5	17	0.86	0.081
1286956	Soil		7.0	38.5	36.6	97	3.0	23.0	3.2	81	1.82	130.3	69.4	1.4	51	0.7	21.9	0.9	42	0.23	0.078
1286957	Soil		4.8	26.1	9.4	113	0.6	28.4	2.8	32	1.14	17.0	5.2	0.9	38	0.5	2.6	0.2	35	0.69	0.040
1286958	Soil		4.0	19.3	8.3	144	0.4	16.9	2.2	93	0.96	8.6	1.4	0.2	7	0.6	1.8	0.2	91	0.06	0.148
1286959	Soil		7.9	25.8	11.6	405	0.3	44.0	4.9	172	1.78	15.3	1.3	0.2	12	1.4	3.0	0.3	249	0.26	0.120
1286960	Soil		7.0	69.7	14.2	1710	1.4	94.6	6.6	109	1.99	18.6	2.3	2.7	14	4.6	5.2	0.1	155	0.42	0.150
1286961	Soil		9.6	76.7	17.6	943	1.0	69.6	13.2	237	2.51	11.3	2.1	1.6	9	2.0	6.3	0.2	149	0.31	0.121
1286962	Soil		9.3	54.8	13.4	355	1.4	44.3	7.9	165	2.27	9.6	1.9	1.4	9	1.8	6.1	0.2	140	0.23	0.133
1286963	Soil		9.1	35.1	14.5	698	0.4	54.0	6.6	197	1.89	10.7	1.4	0.4	18	6.7	4.5	0.2	118	0.42	0.155
1286964	Soil		6.4	65.0	12.9	1269	1.2	132.1	8.6	149	2.01	17.0	2.5	1.3	20	6.0	3.2	0.2	246	0.75	0.172
1286965	Soil		8.5	29.0	13.2	248	0.3	38.8	3.9	120	1.79	23.0	1.0	0.3	9	1.6	4.0	0.2	215	0.24	0.143
1286966	Soil		4.6	44.3	11.7	429	0.8	46.3	6.8	130	2.23	11.0	2.4	3.4	13	0.9	3.1	0.1	149	0.40	0.138
1286967	Soil		4.6	43.8	13.7	536	0.6	40.6	7.8	204	2.19	18.4	1.3	1.6	18	3.9	2.6	0.2	239	0.49	0.151
1286968	Soil		6.7	53.0	14.7	329	0.5	48.3	7.4	178	2.48	36.4	3.3	4.2	20	3.3	3.7	0.2	184	0.55	0.167
1286969	Soil		3.2	23.8	11.6	276	0.7	24.2	4.5	131	1.17	20.7	<0.5	0.9	18	2.0	1.4	0.4	109	0.47	0.106
1286970	Soil		5.4	61.4	23.3	1417	0.7	96.1	8.2	197	2.13	56.7	1.4	1.9	15	4.3	2.9	0.9	197	0.51	0.164

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288551	Soil		4	10	0.11	1412	0.003	1	0.80	0.018	0.04	<0.1	0.21	3.1	0.1	0.10	2	3.1	<0.2
1288552	Soil		1	4	0.17	550	0.002	4	0.32	0.014	0.03	<0.1	0.09	1.7	<0.1	0.16	<1	1.6	<0.2
1288553	Soil		3	10	0.07	170	0.002	2	0.59	0.005	0.08	<0.1	0.02	1.8	0.1	<0.05	3	0.8	<0.2
1288554	Soil		7	11	0.06	1019	0.004	2	0.66	0.003	0.05	<0.1	0.02	1.3	0.2	<0.05	4	0.9	<0.2
1288555	Soil		7	9	0.06	740	0.003	2	0.66	0.005	0.05	0.1	0.03	1.2	0.2	<0.05	3	<0.5	<0.2
1288556	Soil		5	11	0.06	1252	0.002	2	0.86	0.013	0.06	<0.1	0.09	1.7	0.2	<0.05	3	0.9	<0.2
1288557	Soil		2	7	0.14	787	0.002	5	0.63	0.015	0.05	<0.1	0.13	1.2	0.2	0.19	2	1.6	<0.2
1288558	Soil		4	10	0.16	686	0.002	3	0.77	0.013	0.05	<0.1	0.13	1.8	0.1	0.15	2	2.1	<0.2
1288559	Soil		6	9	0.02	335	0.003	3	0.36	0.006	0.05	<0.1	0.02	0.7	0.1	<0.05	3	1.2	<0.2
1288560	Soil		7	15	0.10	1401	0.003	3	1.23	0.013	0.07	<0.1	0.96	3.5	0.3	0.12	3	11.6	<0.2
1286951	Soil		18	9	0.04	308	0.003	4	0.61	0.012	0.11	0.8	8.29	0.6	1.2	0.16	3	4.9	0.2
1286952	Soil		4	9	0.03	183	<0.001	2	0.54	0.005	0.09	<0.1	0.23	1.4	0.2	<0.05	2	1.7	<0.2
1286953	Soil		13	16	0.14	600	0.003	2	0.90	0.004	0.07	0.3	1.33	1.9	0.5	0.08	3	3.0	<0.2
1286954	Soil		7	12	0.05	662	0.001	3	0.56	0.007	0.07	0.2	1.70	1.3	0.2	0.10	2	1.6	<0.2
1286955	Soil		5	8	0.05	493	0.004	3	0.53	0.019	0.04	0.2	4.63	1.0	0.2	0.13	2	3.0	<0.2
1286956	Soil		13	14	0.08	609	0.003	2	0.68	0.007	0.07	0.3	12.00	1.9	0.5	0.11	2	4.7	<0.2
1286957	Soil		3	9	0.06	263	0.001	3	0.34	0.008	0.05	<0.1	0.68	1.3	0.2	0.09	1	1.7	<0.2
1286958	Soil		7	21	0.49	71	0.006	<1	1.18	0.013	0.07	0.1	0.06	0.3	0.3	0.05	5	0.6	<0.2
1286959	Soil		9	44	1.59	154	0.017	2	1.92	0.006	0.13	0.3	0.04	0.6	0.4	0.05	6	0.9	<0.2
1286960	Soil		16	27	1.35	165	0.031	2	1.63	0.007	0.21	1.4	0.08	1.9	0.5	<0.05	4	1.1	<0.2
1286961	Soil		14	33	2.00	216	0.030	2	2.12	0.003	0.30	<0.1	0.05	1.4	0.6	<0.05	5	1.4	<0.2
1286962	Soil		12	31	1.75	234	0.030	3	1.87	0.004	0.29	<0.1	0.05	1.2	0.5	<0.05	5	1.3	<0.2
1286963	Soil		11	20	0.80	132	0.008	2	1.24	0.012	0.13	0.1	0.02	0.4	0.3	0.05	4	1.4	<0.2
1286964	Soil		13	51	1.87	152	0.035	2	2.21	0.008	0.16	0.2	0.06	1.9	0.4	<0.05	6	1.0	<0.2
1286965	Soil		8	35	1.19	118	0.021	<1	1.57	0.008	0.10	0.1	0.03	0.7	0.5	<0.05	5	1.4	<0.2
1286966	Soil		9	35	2.11	238	0.048	2	2.28	0.004	0.21	<0.1	0.03	1.3	0.4	<0.05	5	1.1	<0.2
1286967	Soil		11	43	1.85	178	0.048	1	2.29	0.007	0.18	<0.1	0.03	1.4	0.3	<0.05	6	1.1	<0.2
1286968	Soil		19	41	1.40	164	0.043	1	1.85	0.005	0.17	0.2	0.06	2.3	0.4	<0.05	5	0.9	<0.2
1286969	Soil		5	22	1.06	122	0.031	1	1.33	0.018	0.11	<0.1	0.03	0.9	0.2	<0.05	4	1.4	<0.2
1286970	Soil		9	42	2.08	153	0.053	2	2.36	0.004	0.20	0.1	0.03	1.9	0.4	<0.05	6	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1286981	Soil		5.0	42.5	6.9	75	1.6	18.5	3.0	79	1.18	9.1	4.1	0.3	6	1.0	2.4	0.1	39	0.07	0.117
1286982	Soil		8.7	48.2	10.2	219	0.7	34.0	6.5	174	2.13	27.5	2.2	0.4	16	2.9	3.8	0.2	82	0.23	0.190
1286983	Soil		59.7	199.3	37.2	1079	2.0	124.0	8.7	266	3.72	127.2	4.8	0.6	31	3.7	20.3	0.3	258	0.82	0.530
1286984	Soil		2.7	19.9	3.7	35	0.3	7.2	1.6	112	0.38	2.8	<0.5	<0.1	11	2.8	0.9	<0.1	10	0.20	0.087
1286985	Soil		12.5	50.7	17.4	325	1.4	47.3	5.6	101	1.81	24.3	2.3	0.4	17	1.1	6.1	0.2	110	0.38	0.257
1286986	Soil		11.1	44.0	10.2	171	0.6	22.0	2.7	75	1.16	20.6	1.4	0.1	6	1.1	4.6	0.2	51	0.05	0.138
1286987	Soil		10.1	46.7	15.1	238	0.4	31.8	5.4	199	2.03	31.2	2.0	0.3	11	1.0	5.3	0.2	78	0.13	0.154
1286988	Soil		1.1	8.8	3.5	23	0.3	4.7	0.8	23	0.38	3.8	<0.5	0.1	11	0.3	0.5	<0.1	17	0.23	0.100
1286989	Soil		3.2	15.5	6.4	79	0.3	10.7	1.7	36	0.82	20.2	0.9	0.2	7	0.7	1.7	0.1	34	0.09	0.077
1286990	Soil		4.3	130.6	13.9	642	1.1	51.6	11.2	270	2.58	17.5	2.3	2.3	25	6.6	2.1	0.2	170	0.59	0.089
1287431	Soil		8.8	41.4	33.3	146	0.9	28.6	8.0	155	3.19	161.5	17.6	2.3	47	0.8	9.6	1.1	74	0.04	0.084
1287432	Soil		15.7	84.2	274.3	185	6.9	42.8	6.2	104	4.43	370.4	26.6	5.9	67	0.8	20.3	1.1	137	0.04	0.238
1287433	Soil		6.1	51.5	35.0	115	0.9	24.3	5.2	83	3.77	167.9	8.1	2.1	30	0.6	10.0	0.7	65	0.03	0.107
1287434	Soil		12.6	25.1	29.0	117	0.8	23.0	3.5	58	1.84	61.5	5.6	0.4	36	0.4	5.7	0.4	121	0.03	0.075
1287435	Soil		9.3	74.8	31.6	161	1.2	33.9	7.6	101	3.35	231.3	9.3	3.1	47	0.7	9.2	1.0	58	0.04	0.096
1287436	Soil		7.5	48.0	22.7	77	1.2	15.5	3.4	93	2.65	126.0	8.8	1.4	28	0.6	5.6	1.2	70	0.02	0.057
1287437	Soil		8.3	100.0	20.5	94	1.0	18.6	3.9	95	6.43	209.0	7.1	4.6	27	0.4	7.6	2.2	64	0.02	0.118
1287438	Soil		4.5	51.1	41.9	87	1.6	14.1	3.0	49	3.24	518.2	5.7	3.9	57	0.4	12.0	5.6	54	0.02	0.087
1287439	Soil		7.4	58.3	34.3	90	1.0	17.1	4.0	96	3.49	201.6	17.3	1.9	37	0.4	9.3	1.4	57	0.03	0.074
1287440	Soil		5.9	40.1	34.3	76	2.6	14.8	3.2	55	2.43	269.5	57.4	0.8	41	0.5	13.8	4.0	35	0.02	0.084
1287441	Soil		4.3	28.2	24.1	132	1.8	27.1	8.3	70	2.69	575.1	9.1	1.9	45	0.4	11.6	3.1	33	0.03	0.076
1287442	Soil		6.4	30.8	44.1	127	0.6	23.8	6.2	81	3.55	299.7	8.1	3.8	41	0.3	9.7	1.1	47	0.02	0.073
1287443	Soil		14.6	67.3	65.7	243	2.3	38.9	5.6	90	3.62	604.9	31.2	5.7	97	1.6	20.9	5.5	78	0.03	0.106
1287444	Soil		15.6	60.0	54.0	170	1.6	30.9	4.8	100	2.97	209.5	20.7	3.7	93	1.2	14.1	1.5	76	0.06	0.108
1287445	Soil		11.8	45.7	35.9	163	1.1	29.9	5.9	159	2.86	165.1	15.6	3.3	50	1.0	12.0	1.3	81	0.08	0.104
1287446	Soil		13.1	25.0	36.1	96	1.3	19.1	3.3	86	2.91	218.3	15.4	2.7	64	0.6	16.8	0.8	88	0.06	0.114
1287447	Soil		13.8	45.2	76.1	125	2.1	21.7	5.3	134	3.10	306.0	102.5	9.5	193	1.1	25.4	1.0	86	0.05	0.143
1287448	Soil		11.1	55.3	40.7	219	1.3	36.2	8.5	266	2.41	226.5	26.9	2.8	55	2.1	15.2	1.0	55	0.08	0.098
1287449	Soil		16.0	34.3	27.3	161	0.8	31.4	3.4	80	1.76	127.7	9.5	1.7	48	1.0	14.6	0.7	90	0.02	0.072
1287450	Soil		10.9	46.2	60.6	114	2.5	12.9	3.4	86	3.52	659.5	103.9	1.9	61	0.5	26.0	3.4	59	0.02	0.145

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286981	Soil	3	11	0.45	65	0.006	2	0.70	0.018	0.12	<0.1	0.04	0.4	0.2	<0.05	2	1.3	<0.2
1286982	Soil	8	20	0.92	164	0.010	2	1.22	0.011	0.27	0.2	0.02	0.5	0.4	0.05	4	2.1	<0.2
1286983	Soil	14	35	0.38	208	0.011	4	0.97	0.008	0.29	0.7	0.10	0.6	0.6	0.09	3	12.0	<0.2
1286984	Soil	2	3	0.05	55	0.006	<1	0.24	0.022	0.04	<0.1	0.02	0.3	<0.1	0.07	<1	<0.5	<0.2
1286985	Soil	14	25	0.66	109	0.007	2	1.19	0.009	0.17	<0.1	0.06	0.4	0.4	0.06	3	2.5	<0.2
1286986	Soil	6	9	0.08	82	0.003	1	0.42	0.010	0.08	<0.1	0.03	0.2	0.2	<0.05	2	2.1	<0.2
1286987	Soil	8	17	0.43	111	0.009	2	0.94	0.016	0.14	0.3	0.03	0.3	0.3	<0.05	4	2.1	<0.2
1286988	Soil	2	5	0.17	66	0.003	<1	0.39	0.024	0.03	<0.1	0.01	0.2	0.1	<0.05	1	0.7	<0.2
1286989	Soil	5	10	0.40	80	0.006	1	0.56	0.015	0.08	0.1	0.01	0.2	0.1	<0.05	2	<0.5	<0.2
1286990	Soil	8	46	3.13	204	0.093	1	3.76	0.011	0.21	0.2	0.04	3.7	0.3	<0.05	10	2.3	<0.2
1287431	Soil	18	15	0.09	317	0.003	2	0.79	0.006	0.09	0.4	1.99	2.0	0.5	0.10	2	3.4	<0.2
1287432	Soil	21	25	0.13	300	0.005	3	1.30	0.004	0.10	0.4	5.00	3.2	0.8	0.15	3	5.9	<0.2
1287433	Soil	15	17	0.13	208	0.005	2	0.84	0.007	0.08	0.2	0.82	1.6	0.3	0.08	3	2.2	<0.2
1287434	Soil	16	14	0.06	263	0.009	3	0.64	0.004	0.06	0.2	0.45	0.4	0.4	0.06	3	1.8	<0.2
1287435	Soil	19	17	0.13	203	0.004	3	0.77	0.005	0.10	0.3	2.13	2.9	0.4	0.13	2	3.2	<0.2
1287436	Soil	19	17	0.17	154	0.010	2	0.84	0.004	0.07	0.2	1.43	1.2	0.4	0.07	4	1.9	<0.2
1287437	Soil	20	21	0.21	164	0.007	2	0.83	0.004	0.10	0.4	1.12	2.5	0.3	0.23	3	2.8	<0.2
1287438	Soil	30	12	0.09	169	0.003	2	0.69	0.005	0.10	1.1	0.88	1.8	0.3	0.22	3	3.3	0.2
1287439	Soil	17	17	0.16	167	0.007	2	0.76	0.004	0.07	0.5	2.73	1.6	0.5	0.10	3	2.2	<0.2
1287440	Soil	15	10	0.09	173	0.005	3	0.63	0.010	0.07	1.4	7.06	0.7	0.5	0.08	2	3.3	<0.2
1287441	Soil	25	9	0.04	143	0.002	3	0.37	0.007	0.08	9.1	1.27	1.0	0.4	0.09	2	1.4	<0.2
1287442	Soil	28	11	0.05	141	0.002	3	0.50	0.006	0.09	0.3	0.99	1.2	0.4	0.08	3	2.1	<0.2
1287443	Soil	25	15	0.13	348	0.002	3	0.69	0.004	0.09	1.0	5.92	2.3	0.8	0.09	2	4.6	0.2
1287444	Soil	18	15	0.18	445	0.004	3	0.69	0.005	0.11	0.5	3.61	2.6	1.0	0.16	2	4.5	<0.2
1287445	Soil	16	22	0.26	335	0.007	4	1.25	0.005	0.08	0.4	3.51	2.3	0.6	<0.05	3	3.8	<0.2
1287446	Soil	18	16	0.15	334	0.005	3	0.73	0.005	0.10	0.3	3.99	1.4	0.9	0.10	3	6.5	<0.2
1287447	Soil	32	11	0.04	525	0.002	4	0.58	0.005	0.12	0.4	4.49	1.6	2.2	0.18	2	6.6	<0.2
1287448	Soil	18	11	0.10	313	0.002	2	0.64	0.007	0.08	0.3	1.87	1.6	0.8	0.07	2	3.9	<0.2
1287449	Soil	18	11	0.06	271	0.002	3	0.40	0.004	0.07	0.3	1.06	1.1	0.7	<0.05	2	4.4	<0.2
1287450	Soil	18	13	0.08	237	0.003	4	0.64	0.011	0.13	1.3	12.12	0.8	1.9	0.23	2	7.4	0.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1286481	Soil		10.6	176.2	108.4	1087	1.9	323.5	34.9	700	6.93	79.9	8.4	6.6	261	1.8	7.8	0.6	114	2.29	0.828
1286482	Soil		18.0	155.2	177.7	473	4.1	106.3	12.4	148	5.29	79.0	8.1	6.2	315	1.4	9.2	0.8	232	1.48	1.048
1286483	Soil		80.3	217.8	117.1	136	14.7	88.3	1.8	29	4.39	67.3	2.1	4.7	217	3.8	24.8	0.6	818	0.69	0.669
1286484	Soil		72.0	136.4	165.7	174	9.4	65.6	2.9	52	4.29	70.0	1.6	3.4	311	4.4	22.3	0.5	603	0.48	0.872
1286485	Soil		21.4	123.2	25.4	191	3.7	57.7	4.4	145	2.40	32.7	3.0	0.2	363	3.2	9.9	0.3	337	0.56	0.622
1286486	Soil		6.0	936.2	34.3	434	2.6	333.7	15.4	1881	6.14	53.2	4.5	2.7	303	3.1	8.4	0.2	201	3.92	0.752
1286487	Soil		18.5	114.5	34.4	150	2.9	43.7	4.3	126	3.89	34.5	3.7	0.5	112	1.0	5.3	0.3	176	0.22	0.452
1286488	Soil		15.0	42.8	19.1	121	1.0	34.0	3.0	57	1.67	20.8	1.1	<0.1	41	0.9	3.2	0.2	93	0.12	0.142
1286489	Soil		53.4	79.4	57.3	116	4.3	32.3	2.4	86	3.16	44.8	3.8	0.8	218	3.0	11.3	0.4	361	0.31	0.635
1286490	Soil		31.0	47.8	78.6	123	2.0	26.6	3.0	214	2.06	20.9	1.8	<0.1	105	1.1	4.9	0.5	223	0.09	0.224
1286391	Soil		7.2	151.7	20.9	296	0.5	604.9	98.4	1084	7.82	232.9	4.6	19.9	160	2.6	6.4	<0.1	157	1.85	0.651
1286392	Soil		7.7	106.7	13.8	300	0.5	415.3	63.6	1040	7.88	201.2	3.6	12.5	162	2.9	4.8	<0.1	168	1.16	0.500
1286393	Soil		5.9	306.6	27.7	156	0.5	952.1	192.4	2111	16.91	50.1	3.0	22.3	649	1.5	3.2	0.1	209	1.39	0.736
1286394	Soil		10.6	110.3	15.1	200	0.3	406.4	60.6	768	6.64	128.7	2.2	9.9	165	1.3	4.1	<0.1	210	1.24	0.532
1286395	Soil		7.8	135.6	17.8	172	0.3	521.3	75.4	814	7.54	127.9	3.9	16.5	203	1.1	4.6	<0.1	193	1.53	0.678
1286396	Soil		11.5	123.1	16.7	263	0.5	462.2	63.5	710	6.89	69.2	2.3	11.5	146	1.3	5.5	0.1	168	1.14	0.566
1286397	Soil		13.7	127.1	15.9	347	0.5	430.1	62.6	1121	7.71	468.6	3.2	14.9	155	3.1	9.8	0.1	186	1.20	0.575
1286398	Soil		13.0	50.8	11.3	309	0.4	127.9	19.1	312	3.49	95.8	1.8	1.6	25	1.9	5.7	0.2	114	0.31	0.181
1286399	Soil		11.3	76.9	14.6	339	0.7	178.4	27.4	471	3.93	79.5	2.1	5.1	75	2.0	5.7	0.2	108	0.64	0.253
1286400	Soil		19.4	59.2	15.2	265	0.4	110.1	15.6	131	3.25	69.6	1.8	0.8	10	0.4	5.4	0.3	124	0.05	0.098
1286381	Soil		122.7	157.4	23.2	3475	4.0	374.5	11.1	320	2.47	195.3	10.0	4.1	189	40.9	52.8	0.2	1069	5.88	0.180
1286382	Soil		27.4	124.3	19.4	600	0.8	408.7	58.7	788	6.65	77.9	2.6	5.5	232	7.3	11.2	0.1	256	5.98	0.397
1286383	Soil		6.5	171.1	15.5	65	0.4	786.1	127.4	1289	11.99	12.0	<0.5	13.1	242	0.6	3.3	<0.1	157	5.49	0.422
1286384	Soil		20.6	117.5	26.0	733	0.9	432.8	78.2	988	7.70	111.1	4.0	9.7	275	6.5	12.6	<0.1	266	6.67	0.407
1286385	Soil		24.9	119.7	21.3	565	0.9	573.1	76.4	1030	8.65	123.2	4.8	8.4	143	5.6	12.8	0.2	234	2.55	0.459
1286386	Soil		21.9	89.4	17.7	388	0.6	371.8	55.4	855	6.98	108.6	1.1	5.5	102	4.2	7.1	0.2	247	1.51	0.417
1286387	Soil		15.5	99.8	21.2	309	0.6	466.7	67.4	977	7.68	145.7	1.8	7.9	134	3.1	8.5	0.1	177	1.95	0.462
1286388	Soil		11.0	118.6	19.3	373	0.5	637.5	80.5	1085	7.84	390.7	5.1	17.3	163	3.7	10.1	0.1	166	2.13	0.651
1286389	Soil		10.8	115.8	18.9	844	0.6	586.5	78.3	763	7.11	284.4	5.7	14.2	151	7.9	7.5	0.1	159	2.03	0.615
1286390	Soil		15.0	135.5	23.2	836	0.7	586.0	84.3	1142	8.77	269.0	5.6	13.7	183	9.4	8.0	0.1	187	2.42	0.611

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286481	Soil	30	58	0.36	596	0.008	19	0.73	0.004	0.29	<0.1	1.37	8.3	0.5	0.20	2	8.0	0.3
1286482	Soil	31	42	0.08	199	0.011	17	0.85	0.007	0.47	0.2	1.54	5.4	0.9	0.71	3	7.1	0.4
1286483	Soil	31	57	0.06	74	0.013	9	0.69	0.008	0.43	1.2	2.28	5.2	0.8	1.09	4	38.1	0.9
1286484	Soil	30	41	0.09	145	0.015	6	0.67	0.012	0.34	1.1	0.97	4.2	2.0	0.63	3	21.6	1.0
1286485	Soil	16	27	0.10	857	0.004	6	0.91	0.005	0.17	0.3	0.50	0.5	0.7	0.21	2	8.6	0.3
1286486	Soil	28	59	1.75	1079	0.012	5	1.65	0.010	0.17	0.1	1.46	8.2	0.7	0.27	2	5.8	0.2
1286487	Soil	18	34	0.09	233	0.005	3	0.71	0.005	0.37	0.2	0.52	1.0	1.2	0.87	3	6.5	0.2
1286488	Soil	9	15	0.05	373	0.001	3	0.39	0.004	0.14	0.1	0.13	0.1	0.6	0.25	2	2.5	<0.2
1286489	Soil	23	27	0.11	583	0.006	3	0.61	0.005	0.22	0.5	0.34	0.9	1.5	0.38	3	6.6	0.7
1286490	Soil	13	23	0.05	510	0.001	3	0.59	0.006	0.18	0.1	0.14	0.1	1.0	0.30	3	3.7	0.3
1286391	Soil	93	232	0.35	6645	0.007	26	1.49	0.008	0.26	0.1	2.45	28.1	0.5	<0.05	4	0.9	<0.2
1286392	Soil	87	245	0.60	5154	0.005	10	1.65	0.006	0.13	0.1	0.97	26.2	0.4	<0.05	4	0.9	<0.2
1286393	Soil	62	372	0.87	2652	0.009	12	1.62	0.003	0.16	0.1	0.29	56.5	0.3	<0.05	5	1.3	<0.2
1286394	Soil	69	208	0.45	3748	0.007	17	1.59	0.009	0.19	0.2	0.40	18.7	0.5	<0.05	5	1.5	<0.2
1286395	Soil	91	241	0.39	3532	0.009	26	1.71	0.008	0.27	0.2	0.50	26.9	0.5	<0.05	5	1.3	<0.2
1286396	Soil	70	161	0.22	2517	0.008	15	1.25	0.005	0.21	0.2	1.36	19.6	0.4	<0.05	3	1.5	<0.2
1286397	Soil	89	182	0.42	2961	0.005	14	1.35	0.005	0.17	0.1	1.95	18.7	0.5	<0.05	4	2.0	<0.2
1286398	Soil	27	59	0.20	1430	0.003	5	0.88	0.008	0.08	0.1	0.89	3.2	0.4	<0.05	2	2.4	<0.2
1286399	Soil	36	68	0.19	1871	0.003	9	0.77	0.003	0.12	<0.1	3.47	8.3	0.3	<0.05	2	5.1	<0.2
1286400	Soil	22	28	0.07	256	0.004	3	0.69	0.004	0.07	<0.1	0.59	1.3	0.4	<0.05	3	2.5	<0.2
1286381	Soil	17	62	2.94	871	0.012	14	0.60	0.007	0.18	0.4	1.93	4.6	4.3	0.06	2	20.4	<0.2
1286382	Soil	39	150	2.93	899	0.006	13	0.68	0.008	0.14	0.2	0.62	13.8	0.9	0.10	2	3.5	<0.2
1286383	Soil	57	178	2.36	1014	0.010	15	0.54	0.005	0.17	0.1	0.15	21.7	0.4	0.07	2	1.9	<0.2
1286384	Soil	35	148	3.50	992	0.006	13	0.76	0.006	0.14	<0.1	0.96	14.7	0.7	0.11	2	3.4	<0.2
1286385	Soil	62	136	0.70	1428	0.008	9	0.71	0.008	0.12	0.2	0.99	16.3	0.7	<0.05	2	4.5	<0.2
1286386	Soil	64	131	0.17	2211	0.007	8	0.88	0.006	0.09	0.1	0.74	15.2	0.5	<0.05	2	4.4	<0.2
1286387	Soil	67	127	0.26	1695	0.006	10	0.80	0.007	0.10	0.1	1.00	15.1	0.5	<0.05	2	3.1	<0.2
1286388	Soil	110	161	0.28	2288	0.014	14	1.13	0.009	0.14	0.3	2.44	22.0	0.4	<0.05	3	1.9	<0.2
1286389	Soil	89	171	0.26	1897	0.007	15	1.05	0.008	0.15	0.2	2.47	19.1	0.4	<0.05	3	1.5	<0.2
1286390	Soil	84	168	0.55	2658	0.007	12	0.98	0.008	0.13	0.2	4.50	22.2	0.5	<0.05	3	2.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1286921	Soil		7.0	58.4	29.8	165	1.9	42.6	8.2	143	3.14	238.8	42.7	2.2	62	1.5	10.8	0.9	61	0.63	0.129
1286922	Soil		11.2	46.7	17.5	207	1.0	39.5	5.7	124	2.24	36.0	8.7	1.5	85	1.7	7.5	0.2	116	0.23	0.117
1286923	Soil		8.6	77.8	17.0	270	1.3	65.7	8.9	316	3.06	44.7	11.1	1.8	68	2.8	6.9	0.3	66	0.48	0.118
1286924	Soil		6.6	44.1	27.6	156	2.6	36.9	4.2	96	2.14	97.3	44.1	1.3	68	1.6	17.9	0.8	42	0.56	0.082
1286925	Soil		43.1	42.4	44.2	58	8.7	13.0	1.7	31	1.61	57.2	32.3	0.5	82	0.4	17.5	0.4	497	0.06	0.109
1286926	Soil		57.9	54.9	66.6	77	9.3	13.2	1.7	40	4.06	207.1	60.0	1.3	71	0.6	31.2	0.6	418	0.02	0.145
1286927	Soil		16.3	59.4	40.9	235	0.9	34.5	6.4	203	3.99	192.0	10.6	1.3	44	1.9	12.9	0.4	148	0.02	0.107
1286928	Soil		13.1	155.0	83.0	407	2.0	59.0	13.4	226	10.34	325.9	11.1	7.0	262	0.7	24.4	0.8	294	0.03	0.258
1286929	Soil		168.4	68.5	4934	33	31.3	12.5	1.1	31	3.59	342.8	21.8	1.3	191	0.3	105.8	0.6	979	0.06	0.263
1286930	Soil		7.6	20.9	20.2	89	0.8	15.8	3.8	93	1.89	89.9	9.7	<0.1	50	0.4	5.3	0.2	49	0.03	0.097
1287181	Soil		18.4	172.9	51.3	63	2.8	70.8	18.4	494	6.89	42.5	12.6	4.5	81	0.9	5.7	0.3	95	1.04	0.351
1287182	Soil		15.2	98.7	20.2	169	1.0	65.1	18.9	215	3.79	36.5	17.6	4.2	30	0.6	4.2	0.3	89	0.34	0.130
1287183	Soil		14.5	127.1	32.9	928	1.5	54.3	11.6	356	4.56	42.6	6.8	2.0	25	4.9	3.9	0.2	82	0.67	0.156
1287184	Soil		32.3	31.8	24.9	219	0.6	54.3	5.2	91	1.99	31.6	2.1	0.1	20	0.3	5.0	0.3	224	0.05	0.065
1287185	Soil		11.5	32.7	15.2	149	0.3	40.7	8.4	175	2.74	19.3	1.1	0.2	12	0.2	2.2	0.3	70	0.05	0.053
1287186	Soil		58.7	86.7	29.3	752	0.7	160.7	13.7	272	3.40	59.2	3.3	2.1	66	1.9	12.0	0.3	454	0.60	0.101
1287187	Soil		134.8	202.4	28.6	2597	3.3	334.9	6.4	138	1.98	119.4	3.0	2.4	327	29.6	53.4	0.2	1660	10.48	0.141
1287188	Soil		103.8	122.6	35.4	963	2.2	256.1	10.2	161	2.91	64.6	3.2	2.4	186	9.2	20.7	0.2	485	4.35	0.193
1287189	Soil		7.1	60.0	22.5	286	1.0	72.9	11.9	114	2.59	24.1	7.3	3.1	70	3.2	4.0	0.3	91	0.46	0.085
1287190	Soil		4.6	31.4	11.7	153	0.9	28.8	7.4	146	1.87	20.8	6.2	0.7	85	0.9	3.5	0.2	39	1.18	0.077
1288621	Soil		6.1	72.2	42.3	152	0.5	28.0	11.0	279	5.35	20.9	5.2	2.1	80	0.5	3.0	0.4	37	0.06	0.097
1288622	Soil		5.3	41.0	29.0	106	0.7	18.1	6.0	124	3.21	13.7	2.8	0.7	53	0.2	2.6	0.4	42	0.03	0.086
1288623	Soil		36.6	82.5	22.8	138	6.2	29.6	2.8	103	3.16	40.3	8.5	0.7	105	0.9	17.0	0.3	181	0.18	0.430
1288624	Soil		94.6	274.4	43.5	367	9.1	78.9	2.7	107	3.86	110.8	3.0	1.0	198	21.6	64.3	0.4	664	0.49	0.659
1288625	Soil		30.6	126.8	23.3	233	6.2	54.2	8.0	238	3.33	35.9	4.6	0.7	99	2.5	13.2	0.3	234	0.14	0.228
1288626	Soil		14.9	58.6	11.0	93	2.7	19.8	2.7	57	1.43	14.6	1.6	<0.1	49	1.5	8.8	0.2	139	0.08	0.145
1288627	Soil		30.9	94.6	26.1	201	3.6	43.1	6.8	157	3.34	35.4	4.0	0.9	89	1.8	14.1	0.3	294	0.17	0.291
1288628	Soil		14.3	38.1	18.0	148	1.2	41.8	8.1	304	1.68	38.5	5.7	0.7	75	1.9	4.0	0.2	65	0.73	0.121
1288629	Soil		10.9	65.7	16.9	401	1.5	77.7	10.3	388	2.54	48.0	7.5	1.5	90	4.1	6.4	0.2	95	0.46	0.156
1288630	Soil		5.5	28.0	12.9	78	1.0	17.3	4.5	246	1.17	16.7	4.7	0.4	69	2.2	2.2	0.2	66	0.44	0.074

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286921	Soil	10	19	0.11	981	0.002	3	0.86	0.005	0.06	0.3	4.69	3.1	0.5	<0.05	2	4.1	<0.2
1286922	Soil	7	21	0.07	1697	0.004	3	0.63	0.003	0.07	0.2	0.70	2.4	0.5	<0.05	2	2.9	<0.2
1286923	Soil	7	21	0.20	1791	0.003	3	0.70	0.006	0.06	0.1	1.32	3.1	0.4	<0.05	2	3.4	<0.2
1286924	Soil	10	17	0.12	596	0.002	5	0.51	0.004	0.08	0.2	13.18	2.2	0.5	0.08	1	7.2	0.3
1286925	Soil	9	39	0.03	518	0.005	5	0.50	0.004	0.18	0.4	3.20	1.3	2.5	0.28	4	6.8	0.2
1286926	Soil	7	38	0.03	193	0.004	4	0.57	0.005	0.39	0.4	6.35	1.7	3.2	0.89	4	13.9	0.2
1286927	Soil	5	18	0.03	298	0.002	7	0.51	0.003	0.16	0.2	0.36	2.2	0.8	0.25	2	3.7	<0.2
1286928	Soil	9	51	0.03	481	0.003	3	0.88	0.004	0.17	0.1	0.50	11.2	1.1	0.43	3	5.4	<0.2
1286929	Soil	14	54	0.02	154	0.006	9	0.76	0.007	0.31	4.3	6.03	1.1	17.6	1.00	5	51.4	0.9
1286930	Soil	3	8	0.02	384	0.003	4	0.37	0.013	0.06	0.2	1.38	0.9	0.5	0.08	1	2.5	<0.2
1287181	Soil	15	17	0.17	1232	0.006	12	0.62	0.004	0.18	<0.1	0.84	10.0	0.4	0.21	2	3.6	<0.2
1287182	Soil	19	17	0.14	1488	0.004	8	0.69	0.003	0.12	<0.1	0.24	6.8	0.4	<0.05	2	2.5	<0.2
1287183	Soil	15	14	0.25	1521	0.005	7	0.53	0.003	0.10	<0.1	1.02	5.5	0.3	0.05	2	2.5	<0.2
1287184	Soil	14	19	0.07	159	0.006	2	0.66	0.003	0.07	0.2	0.08	0.7	0.8	<0.05	4	2.0	<0.2
1287185	Soil	10	12	0.08	220	0.007	3	0.78	0.009	0.07	0.1	0.05	1.0	0.3	<0.05	3	1.2	<0.2
1287186	Soil	21	41	0.33	938	0.004	5	1.37	0.004	0.11	0.2	0.49	3.1	1.9	<0.05	3	5.0	0.2
1287187	Soil	18	84	1.48	533	0.022	15	0.64	0.008	0.18	0.7	2.61	3.9	8.1	<0.05	3	9.1	0.2
1287188	Soil	15	42	1.46	443	0.009	10	0.57	0.006	0.14	0.4	1.28	4.5	2.7	<0.05	2	4.7	0.3
1287189	Soil	10	22	0.18	2408	0.002	3	1.09	0.006	0.07	0.1	0.66	4.0	0.4	<0.05	3	4.6	<0.2
1287190	Soil	5	13	0.13	760	0.003	4	0.60	0.009	0.05	0.1	0.29	2.0	0.1	0.05	2	2.7	<0.2
1288621	Soil	2	15	0.05	412	0.003	4	0.68	0.004	0.18	<0.1	0.20	5.0	0.6	0.24	2	3.4	<0.2
1288622	Soil	3	13	0.03	655	0.003	4	0.55	0.006	0.13	<0.1	0.19	1.6	0.5	0.14	2	1.5	<0.2
1288623	Soil	17	45	0.04	270	0.010	6	0.84	0.015	0.22	0.4	0.64	2.7	2.4	0.48	4	20.3	0.4
1288624	Soil	21	91	0.07	312	0.007	10	0.90	0.008	0.19	0.8	24.61	3.7	5.5	0.44	6	90.8	1.4
1288625	Soil	16	71	0.07	849	0.004	3	0.60	0.004	0.11	0.2	0.75	2.2	1.2	0.17	3	19.5	0.3
1288626	Soil	8	29	0.02	710	0.003	2	0.33	0.015	0.06	0.1	0.37	0.5	0.9	0.06	2	10.0	<0.2
1288627	Soil	14	49	0.06	787	0.010	3	0.76	0.005	0.13	0.2	0.84	1.9	1.5	0.17	4	17.9	0.4
1288628	Soil	7	16	0.11	1085	0.002	5	0.70	0.009	0.06	0.1	0.83	1.8	0.5	<0.05	2	3.3	<0.2
1288629	Soil	9	24	0.12	1894	0.002	5	0.67	0.004	0.08	0.2	1.92	3.1	0.5	<0.05	2	4.3	<0.2
1288630	Soil	5	15	0.05	1105	0.003	2	0.55	0.007	0.05	0.1	0.56	1.4	0.3	<0.05	2	2.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1288491	Soil		2.1	56.8	8.5	71	0.6	20.7	3.6	162	1.55	7.5	4.2	0.7	42	0.5	1.2	0.2	46	0.90	0.211
1288492	Soil		2.6	27.2	7.9	75	0.2	11.6	2.9	111	1.03	5.0	2.6	0.1	20	0.4	1.1	0.2	37	0.20	0.107
1288493	Soil		3.7	36.9	13.4	94	0.2	15.7	3.7	91	1.67	9.7	1.2	0.1	17	0.2	1.7	0.2	58	0.06	0.087
1288494	Soil		4.6	42.9	13.2	86	0.4	18.9	4.8	289	1.65	8.8	6.0	0.2	28	0.6	1.5	0.3	68	0.26	0.102
1288495	Soil		3.2	37.1	15.1	132	0.2	22.2	5.7	274	2.42	11.2	4.4	0.9	37	1.1	1.7	0.3	82	0.39	0.117
1288496	Soil		6.5	126.5	22.6	286	1.5	57.2	12.8	858	3.80	18.4	16.1	1.1	95	2.7	3.6	0.3	84	0.80	0.255
1288497	Soil		9.1	38.0	19.2	148	1.2	35.2	5.0	146	3.07	21.7	2.5	0.3	36	1.8	3.3	0.3	77	0.07	0.202
1288498	Soil		4.5	26.2	19.9	159	0.3	28.8	7.7	287	3.55	45.7	2.7	0.8	20	0.9	2.2	0.5	58	0.06	0.171
1288499	Soil		5.6	70.2	19.2	252	1.6	51.1	8.4	281	3.18	21.0	6.6	1.3	43	3.8	3.0	0.3	78	0.16	0.231
1288500	Soil		8.0	28.2	15.5	208	0.2	38.6	8.4	232	2.69	19.8	2.3	1.6	42	1.2	2.3	0.3	51	0.27	0.091
1289201	Soil		33.9	42.0	71.3	92	3.9	15.8	2.5	49	2.76	195.3	22.7	3.3	241	0.6	33.0	0.5	262	0.13	0.423
1289202	Soil		51.0	63.9	62.5	211	3.9	44.5	3.5	61	3.00	279.2	23.2	2.4	233	1.0	36.1	0.4	432	0.13	0.420
1289203	Soil		30.5	41.4	66.3	77	3.7	15.2	2.3	60	2.91	207.9	11.8	4.5	262	0.7	34.4	0.5	253	0.18	0.478
1289204	Soil		6.4	45.0	36.7	143	1.0	27.2	7.8	174	3.87	327.4	22.3	4.0	57	0.9	15.7	0.7	48	0.04	0.122
1289205	Soil		3.8	50.5	27.1	140	0.5	30.9	6.1	124	3.68	86.1	1.6	4.3	26	1.1	4.7	0.4	86	0.03	0.089
1289206	Soil		3.0	116.1	24.4	280	0.2	63.7	21.1	221	3.46	56.8	1.1	6.9	34	1.2	3.0	0.4	93	0.05	0.075
1289207	Soil		6.8	174.6	41.2	193	1.6	42.1	11.2	125	6.00	582.3	8.1	10.4	104	1.2	13.1	0.5	139	0.06	0.146
1289208	Soil		127.7	112.0	9.9	1364	1.5	328.6	14.2	344	2.43	89.6	2.3	2.8	163	38.2	24.3	0.1	184	4.68	0.084
1289209	Soil		132.6	123.6	14.3	1486	2.5	295.2	6.5	120	1.89	88.8	3.0	1.4	120	16.1	31.7	0.2	1094	3.23	0.114
1289210	Soil		112.8	79.7	11.6	849	2.2	373.2	16.5	284	2.98	71.6	3.1	2.5	122	8.0	12.0	0.2	145	2.45	0.095
1286201	Soil		4.1	46.1	11.1	489	0.7	70.5	12.5	112	3.39	16.6	2.6	1.8	73	5.6	2.2	0.2	59	0.89	0.137
1286202	Soil		11.0	32.0	17.4	210	1.1	57.6	11.2	304	3.41	26.6	2.4	2.4	58	1.5	2.8	0.2	82	0.48	0.113
1286203	Soil		3.8	54.0	13.8	191	1.1	46.9	7.9	234	1.91	11.2	4.6	1.2	96	4.0	2.3	0.2	52	1.41	0.105
1286204	Soil		4.0	54.3	16.7	180	0.9	63.9	13.4	351	3.07	11.7	4.9	2.2	67	1.0	1.7	0.3	17	1.09	0.044
1286205	Soil		10.6	56.6	13.6	270	0.8	53.1	8.2	151	2.31	29.0	6.6	3.6	74	2.3	6.0	0.2	89	0.47	0.136
1286206	Soil		4.7	67.8	15.6	200	0.9	43.0	10.0	443	2.28	18.8	7.4	1.6	118	1.6	2.8	0.3	69	1.24	0.089
1286207	Soil		4.5	71.0	19.1	305	1.2	54.2	7.3	181	2.40	20.6	5.9	1.9	118	4.2	2.8	0.3	97	1.05	0.110
1286208	Soil		8.8	75.3	16.4	285	1.0	68.6	8.6	211	2.26	22.1	7.5	2.3	102	2.1	3.9	0.3	86	0.84	0.080
1286209	Soil		3.7	59.0	12.4	319	1.0	59.8	9.0	647	2.47	15.7	5.5	1.2	92	3.7	2.2	0.2	54	1.60	0.123
1286210	Soil		3.9	45.2	15.3	208	0.7	63.7	12.8	846	3.41	15.0	7.0	2.9	71	1.8	1.5	0.3	50	0.61	0.099

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288491	Soil	11	15	0.20	1425	0.008	5	1.15	0.013	0.08	<0.1	0.29	1.4	0.2	0.11	3	1.3	<0.2
1288492	Soil	6	9	0.07	232	0.004	5	0.55	0.013	0.09	<0.1	0.05	0.3	0.1	<0.05	3	0.9	<0.2
1288493	Soil	10	14	0.09	153	0.004	4	0.76	0.006	0.10	<0.1	0.04	0.3	0.2	<0.05	5	0.9	<0.2
1288494	Soil	14	19	0.15	499	0.008	4	1.00	0.007	0.11	0.1	0.11	0.8	0.3	<0.05	4	1.1	<0.2
1288495	Soil	15	25	0.25	467	0.012	4	1.37	0.005	0.12	0.2	0.14	1.7	0.3	<0.05	5	1.3	<0.2
1288496	Soil	15	22	0.30	597	0.007	7	1.33	0.009	0.18	<0.1	0.37	2.5	0.3	0.12	4	2.5	<0.2
1288497	Soil	7	29	0.12	885	0.004	5	1.08	0.009	0.09	0.1	0.35	0.7	0.3	0.07	4	3.4	<0.2
1288498	Soil	8	24	0.15	639	0.004	2	1.27	0.006	0.06	0.2	0.09	1.3	0.3	<0.05	4	1.7	<0.2
1288499	Soil	12	32	0.18	2817	0.004	9	1.68	0.009	0.12	0.1	0.53	3.6	0.4	0.05	4	3.4	<0.2
1288500	Soil	7	21	0.21	1760	0.002	3	0.98	0.005	0.05	<0.1	0.09	2.0	0.1	<0.05	3	1.5	<0.2
1289201	Soil	18	36	0.02	913	0.003	9	0.65	0.004	0.19	1.1	9.80	4.3	1.6	0.30	3	15.7	<0.2
1289202	Soil	15	47	0.03	886	0.003	9	0.82	0.005	0.17	1.1	9.95	4.1	1.6	0.26	3	16.9	0.2
1289203	Soil	20	37	0.02	875	0.003	9	0.68	0.005	0.18	1.2	10.66	4.9	1.6	0.29	3	15.8	0.2
1289204	Soil	24	16	0.10	530	0.004	5	0.63	0.005	0.12	0.6	3.68	3.2	0.6	0.13	2	3.1	<0.2
1289205	Soil	27	24	0.16	226	0.002	2	1.07	0.006	0.08	0.3	0.33	2.7	0.2	<0.05	3	1.0	<0.2
1289206	Soil	36	20	0.18	389	0.002	2	1.06	0.004	0.11	0.2	0.15	3.9	0.2	<0.05	2	1.3	<0.2
1289207	Soil	27	34	0.18	358	0.002	2	1.10	0.004	0.11	0.3	0.57	7.1	0.4	0.13	3	2.8	<0.2
1289208	Soil	12	21	1.55	552	0.003	8	0.68	0.005	0.09	0.7	0.66	4.0	2.9	<0.05	<1	4.2	<0.2
1289209	Soil	22	61	1.15	430	0.006	12	0.86	0.006	0.19	0.5	0.96	3.8	3.0	<0.05	3	6.0	<0.2
1289210	Soil	15	30	0.66	629	0.002	6	0.58	0.004	0.10	0.6	0.80	6.3	3.8	<0.05	1	6.2	<0.2
1286201	Soil	9	22	0.19	1966	0.005	5	1.05	0.009	0.06	0.1	0.42	3.0	0.2	0.10	2	6.1	<0.2
1286202	Soil	13	31	0.23	4113	0.006	5	1.56	0.007	0.06	0.1	0.28	3.8	0.2	<0.05	3	1.1	<0.2
1286203	Soil	8	20	0.22	1900	0.004	6	0.97	0.010	0.07	<0.1	0.36	2.8	0.2	0.10	2	3.2	<0.2
1286204	Soil	13	16	0.22	2533	0.001	5	0.68	0.007	0.06	<0.1	0.18	4.2	0.1	0.06	1	1.8	<0.2
1286205	Soil	15	20	0.20	2153	0.006	5	0.76	0.005	0.10	0.2	0.48	3.2	0.3	<0.05	2	1.9	<0.2
1286206	Soil	7	26	0.26	1298	0.003	4	1.02	0.008	0.08	0.1	0.45	2.7	0.2	0.05	3	2.4	<0.2
1286207	Soil	10	26	0.25	1254	0.003	4	1.21	0.008	0.11	<0.1	0.71	3.6	0.4	0.05	3	2.4	<0.2
1286208	Soil	10	23	0.20	990	0.003	5	0.99	0.009	0.09	0.1	0.66	3.9	0.3	<0.05	3	2.1	<0.2
1286209	Soil	8	23	0.25	1535	0.003	8	0.99	0.009	0.09	<0.1	0.64	2.7	0.2	0.12	2	4.0	<0.2
1286210	Soil	9	32	0.55	1134	0.003	2	1.63	0.007	0.08	<0.1	0.43	4.1	0.2	<0.05	4	1.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1289111	Soil		4.1	30.6	23.5	118	0.2	29.0	11.2	448	4.31	23.2	1.0	1.8	29	0.4	1.4	0.3	53	0.03	0.117
1289112	Soil		5.7	25.9	19.2	114	0.2	27.7	6.4	213	3.65	21.2	0.7	0.6	17	0.3	2.1	0.3	68	0.03	0.079
1289113	Soil		5.4	25.2	21.7	122	<0.1	27.1	8.1	348	3.86	24.6	1.2	0.3	15	0.4	2.0	0.3	73	0.04	0.121
1289114	Soil		5.1	105.6	13.4	193	1.2	52.3	7.3	255	2.47	14.9	10.4	1.6	75	1.8	2.3	0.3	56	1.14	0.083
1289115	Soil		4.6	29.9	11.1	104	0.5	18.1	4.1	123	1.54	10.3	7.3	0.7	24	1.1	1.7	0.2	54	0.23	0.061
1289116	Soil		8.1	57.1	13.8	222	1.5	45.9	7.5	222	2.37	19.4	6.8	2.5	95	1.9	5.8	0.2	143	0.68	0.152
1289117	Soil		6.7	41.2	12.9	203	1.7	34.3	7.3	269	1.95	15.5	6.3	1.8	110	1.9	5.0	0.2	112	0.95	0.138
1289118	Soil		8.6	59.8	15.7	316	1.4	56.7	10.9	471	2.66	24.0	7.2	3.1	93	3.2	6.7	0.2	134	0.50	0.158
1289119	Soil		3.0	42.1	12.8	172	1.8	40.3	7.1	246	2.09	17.1	12.0	1.2	69	1.1	3.9	0.2	92	1.80	0.126
1289120	Soil		1.7	26.6	8.8	122	0.8	26.5	5.0	190	1.46	10.9	5.0	0.6	81	1.1	2.0	0.1	32	2.48	0.133

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001946.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1289111	Soil	4	25	0.31	393	0.003	3	1.48	0.008	0.10	<0.1	0.07	2.5	0.2	<0.05	5	1.2	<0.2
1289112	Soil	7	23	0.18	224	0.007	3	1.14	0.006	0.07	0.1	0.06	1.2	0.2	<0.05	5	1.5	<0.2
1289113	Soil	7	24	0.21	256	0.006	2	1.13	0.006	0.07	0.1	0.07	0.7	0.2	<0.05	5	0.9	<0.2
1289114	Soil	7	28	0.27	1235	0.003	5	1.24	0.013	0.09	<0.1	0.42	3.7	0.3	0.07	3	2.0	<0.2
1289115	Soil	6	17	0.10	663	0.005	3	0.69	0.011	0.06	0.2	0.13	1.3	0.2	<0.05	3	0.6	<0.2
1289116	Soil	12	26	0.21	2464	0.004	6	1.05	0.006	0.12	0.2	0.72	3.2	0.4	0.05	3	3.3	<0.2
1289117	Soil	9	21	0.18	1473	0.003	4	0.93	0.007	0.09	0.2	0.65	2.5	0.4	0.11	3	4.4	<0.2
1289118	Soil	12	26	0.21	2038	0.003	5	1.14	0.006	0.13	0.2	0.94	3.4	0.4	0.10	3	4.6	<0.2
1289119	Soil	15	30	0.23	2014	0.004	4	0.96	0.007	0.08	0.1	5.97	2.7	0.2	0.10	3	2.6	<0.2
1289120	Soil	8	17	0.15	1034	0.004	2	0.68	0.014	0.04	<0.1	1.37	1.6	0.1	0.13	1	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

QUALITY CONTROL REPORT WHI11001946.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1286907	Soil		6.7	55.8	23.7	428	0.8	92.9	23.5	2988	2.67	178.6	12.8	3.5	30	8.3	14.0	0.3	65	0.12	0.070
REP 1286907	QC		7.1	51.3	22.6	409	0.8	90.4	22.9	2882	2.60	171.1	12.3	3.4	29	8.6	13.2	0.3	59	0.12	0.066
1286944	Soil		4.7	38.5	13.1	81	0.5	17.9	4.5	100	2.40	162.7	15.3	1.0	26	0.2	5.6	1.3	50	0.07	0.074
REP 1286944	QC		4.9	40.3	13.4	83	0.6	18.9	4.3	101	2.49	166.1	12.0	1.0	26	0.2	5.9	1.4	52	0.07	0.076
1284292	Soil		7.3	22.4	29.4	64	2.2	17.3	4.0	94	1.73	18.6	1.3	0.2	48	0.5	2.2	0.3	66	0.04	0.076
REP 1284292	QC		6.7	21.6	32.0	64	2.2	18.0	4.0	95	1.74	18.1	2.1	0.2	48	0.4	2.1	0.2	69	0.03	0.074
1288556	Soil		3.5	23.0	10.2	85	1.0	20.8	3.0	47	1.58	8.2	1.8	0.7	29	0.4	1.0	0.1	42	0.05	0.048
REP 1288556	QC		4.0	22.7	10.7	84	1.1	20.8	3.1	49	1.52	7.4	2.4	0.9	30	0.5	1.1	0.2	44	0.05	0.050
1286960	Soil		7.0	69.7	14.2	1710	1.4	94.6	6.6	109	1.99	18.6	2.3	2.7	14	4.6	5.2	0.1	155	0.42	0.150
REP 1286960	QC		6.9	66.5	13.2	1656	1.4	91.6	6.3	103	1.90	17.6	1.5	2.7	13	4.5	4.9	0.1	152	0.40	0.155
1286988	Soil		1.1	8.8	3.5	23	0.3	4.7	0.8	23	0.38	3.8	<0.5	0.1	11	0.3	0.5	<0.1	17	0.23	0.100
REP 1286988	QC		1.2	9.0	3.6	23	0.4	4.5	0.8	24	0.40	3.9	<0.5	<0.1	12	0.3	0.6	<0.1	17	0.23	0.098
1287439	Soil		7.4	58.3	34.3	90	1.0	17.1	4.0	96	3.49	201.6	17.3	1.9	37	0.4	9.3	1.4	57	0.03	0.074
REP 1287439	QC		8.0	62.2	35.1	98	1.1	18.3	4.3	103	3.71	211.9	19.0	2.1	38	0.2	9.7	1.5	62	0.03	0.078
1286395	Soil		7.8	135.6	17.8	172	0.3	521.3	75.4	814	7.54	127.9	3.9	16.5	203	1.1	4.6	<0.1	193	1.53	0.678
REP 1286395	QC		7.7	135.7	17.6	165	0.4	518.0	74.0	781	7.42	129.3	2.9	16.5	192	1.1	4.7	<0.1	186	1.51	0.665
1287182	Soil		15.2	98.7	20.2	169	1.0	65.1	18.9	215	3.79	36.5	17.6	4.2	30	0.6	4.2	0.3	89	0.34	0.130
REP 1287182	QC		15.2	99.3	20.4	177	1.0	67.1	18.8	211	3.69	37.5	7.2	4.1	30	0.8	4.3	0.3	89	0.34	0.132
1287188	Soil		103.8	122.6	35.4	963	2.2	256.1	10.2	161	2.91	64.6	3.2	2.4	186	9.2	20.7	0.2	485	4.35	0.193
REP 1287188	QC		103.3	126.2	36.3	990	2.3	257.1	10.5	163	2.89	63.9	1.6	2.3	191	9.9	20.7	0.2	477	4.29	0.197
1288492	Soil		2.6	27.2	7.9	75	0.2	11.6	2.9	111	1.03	5.0	2.6	0.1	20	0.4	1.1	0.2	37	0.20	0.107
REP 1288492	QC		2.7	29.2	8.1	78	0.2	12.2	3.0	114	1.08	5.3	1.4	0.2	21	0.4	1.2	0.2	39	0.22	0.114
1289114	Soil		5.1	105.6	13.4	193	1.2	52.3	7.3	255	2.47	14.9	10.4	1.6	75	1.8	2.3	0.3	56	1.14	0.083
REP 1289114	QC		5.2	107.0	14.0	194	1.3	51.8	7.2	257	2.51	15.3	7.7	1.6	74	1.6	2.4	0.3	58	1.14	0.082
Reference Materials																					
STD DS8	Standard		13.2	110.8	127.7	302	1.8	38.4	7.6	593	2.36	26.3	108.7	7.2	71	2.4	5.8	6.8	43	0.69	0.073
STD DS8	Standard		12.9	103.3	112.8	285	1.6	34.4	7.2	554	2.27	23.2	97.1	6.9	70	2.1	5.1	5.9	42	0.69	0.076
STD DS8	Standard		14.9	115.5	125.5	320	1.9	40.9	8.0	630	2.50	24.8	114.7	7.1	74	2.4	5.6	6.5	44	0.72	0.081

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

QUALITY CONTROL REPORT WHI11001946.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1286907	Soil	15	17	0.15	545	0.002	4	0.87	0.005	0.09	0.1	1.27	2.7	0.4	<0.05	2	1.8	<0.2
REP 1286907	QC	15	16	0.14	509	0.003	4	0.80	0.005	0.08	0.2	1.18	2.6	0.4	<0.05	2	2.5	<0.2
1286944	Soil	10	12	0.15	153	0.011	2	0.76	0.019	0.11	0.6	0.69	1.4	0.4	0.09	3	1.6	<0.2
REP 1286944	QC	11	12	0.15	155	0.013	2	0.77	0.023	0.11	0.6	0.76	1.4	0.5	0.12	3	1.5	<0.2
1284292	Soil	6	14	0.06	303	0.003	3	0.54	0.004	0.05	0.1	0.12	0.4	0.4	<0.05	3	2.2	<0.2
REP 1284292	QC	6	14	0.06	320	0.005	2	0.53	0.005	0.05	0.1	0.12	0.6	0.4	<0.05	3	2.8	<0.2
1288556	Soil	5	11	0.06	1252	0.002	2	0.86	0.013	0.06	<0.1	0.09	1.7	0.2	<0.05	3	0.9	<0.2
REP 1288556	QC	5	11	0.06	1361	0.003	3	0.92	0.019	0.08	<0.1	0.09	1.8	0.2	<0.05	3	1.0	<0.2
1286960	Soil	16	27	1.35	165	0.031	2	1.63	0.007	0.21	1.4	0.08	1.9	0.5	<0.05	4	1.1	<0.2
REP 1286960	QC	16	27	1.36	171	0.029	2	1.57	0.007	0.22	<0.1	0.07	1.8	0.5	<0.05	4	1.0	<0.2
1286988	Soil	2	5	0.17	66	0.003	<1	0.39	0.024	0.03	<0.1	0.01	0.2	0.1	<0.05	1	0.7	<0.2
REP 1286988	QC	2	5	0.16	65	0.003	<1	0.39	0.022	0.03	<0.1	0.01	0.2	0.1	<0.05	1	0.5	<0.2
1287439	Soil	17	17	0.16	167	0.007	2	0.76	0.004	0.07	0.5	2.73	1.6	0.5	0.10	3	2.2	<0.2
REP 1287439	QC	18	19	0.17	184	0.008	3	0.82	0.004	0.08	0.5	2.68	1.8	0.5	0.09	4	2.6	<0.2
1286395	Soil	91	241	0.39	3532	0.009	26	1.71	0.008	0.27	0.2	0.50	26.9	0.5	<0.05	5	1.3	<0.2
REP 1286395	QC	87	227	0.38	3495	0.008	23	1.62	0.008	0.25	0.2	0.47	26.4	0.5	<0.05	5	0.9	<0.2
1287182	Soil	19	17	0.14	1488	0.004	8	0.69	0.003	0.12	<0.1	0.24	6.8	0.4	<0.05	2	2.5	<0.2
REP 1287182	QC	18	16	0.13	1374	0.005	6	0.64	0.003	0.11	<0.1	0.24	6.9	0.4	<0.05	1	3.2	<0.2
1287188	Soil	15	42	1.46	443	0.009	10	0.57	0.006	0.14	0.4	1.28	4.5	2.7	<0.05	2	4.7	0.3
REP 1287188	QC	15	39	1.51	439	0.008	9	0.58	0.006	0.15	0.4	1.34	4.4	2.8	<0.05	2	5.8	<0.2
1288492	Soil	6	9	0.07	232	0.004	5	0.55	0.013	0.09	<0.1	0.05	0.3	0.1	<0.05	3	0.9	<0.2
REP 1288492	QC	6	9	0.07	234	0.004	5	0.58	0.018	0.09	<0.1	0.05	0.3	0.1	<0.05	3	0.9	<0.2
1289114	Soil	7	28	0.27	1235	0.003	5	1.24	0.013	0.09	<0.1	0.42	3.7	0.3	0.07	3	2.0	<0.2
REP 1289114	QC	7	29	0.28	1312	0.003	4	1.22	0.009	0.09	<0.1	0.40	3.8	0.3	0.07	3	1.5	<0.2
Reference Materials																		
STD DS8	Standard	17	118	0.60	292	0.126	3	0.96	0.106	0.46	2.8	0.18	2.9	5.7	0.16	5	4.8	5.3
STD DS8	Standard	16	112	0.57	269	0.129	3	0.94	0.111	0.41	2.6	0.20	3.3	4.8	0.10	4	4.6	4.7
STD DS8	Standard	16	123	0.61	284	0.130	2	0.99	0.115	0.42	3.0	0.21	3.2	5.7	0.12	5	4.9	5.8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

QUALITY CONTROL REPORT WHI11001946.1

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
STD DS8	Standard		12.8	107.0	121.6	294	1.6	36.8	7.4	570	2.27	24.2	104.7	7.1	68	2.4	5.4	6.4	40	0.68	0.072
STD DS8	Standard		12.1	101.9	123.8	284	1.8	33.3	6.9	560	2.30	23.4	103.2	7.0	69	2.3	5.4	6.8	39	0.64	0.073
STD DS8	Standard		14.4	112.3	132.0	309	1.8	39.2	7.6	616	2.46	26.7	116.0	7.7	77	2.6	5.8	7.2	44	0.73	0.076
STD DS8	Standard		13.1	111.5	124.8	312	1.8	38.8	7.7	614	2.49	25.8	104.9	6.4	72	2.3	5.5	6.3	43	0.69	0.074
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

QUALITY CONTROL REPORT WHI11001946.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
STD DS8	Standard	16	115	0.59	276	0.129	3	0.93	0.102	0.39	3.0	0.18	2.4	5.2	0.13	4	4.1	4.8
STD DS8	Standard	15	107	0.57	274	0.118	3	0.89	0.094	0.38	2.7	0.19	2.0	5.5	0.13	4	4.2	5.1
STD DS8	Standard	18	121	0.61	294	0.133	3	0.98	0.118	0.43	3.2	0.20	2.8	5.6	0.13	5	5.3	4.9
STD DS8	Standard	15	121	0.61	274	0.115	3	0.98	0.096	0.44	3.0	0.21	2.9	5.5	0.15	5	4.8	5.3
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 20, 2011
Report Date: December 02, 2011
Page: 1 of 6

CERTIFICATE OF ANALYSIS WHI11001947.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #28
P.O. Number
Number of Samples:

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	150	Sieve soil to 230 mesh			VAN
RJSV	150	Saving all or part of Soil Reject			VAN
1DX2	142	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001947.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287111	Soil		13.9	191.6	50.5	393	1.6	134.5	9.0	126	4.43	55.4	2.4	0.5	184	1.0	5.8	0.4	90	0.24	0.523	21
1287112	Soil		6.8	60.0	13.5	141	1.4	54.3	2.9	51	1.36	19.1	2.6	0.6	96	2.4	3.4	0.2	96	0.42	0.201	13
1287113	Soil		7.3	21.9	9.4	102	0.4	25.2	2.5	64	1.52	14.3	2.9	0.1	24	0.3	1.8	0.2	63	0.08	0.247	9
1287114	Soil		13.5	43.2	22.6	285	0.7	67.3	10.7	553	3.59	38.5	2.5	0.4	44	1.1	4.6	0.3	96	0.08	0.181	13
1287115	Soil		36.0	33.0	13.0	255	0.3	90.7	7.1	83	2.51	41.0	<0.5	0.2	22	0.5	7.2	0.3	153	0.02	0.136	15
1287116	Soil		11.7	124.3	21.8	258	1.4	64.8	4.7	60	3.19	60.9	2.8	0.4	333	1.4	6.8	0.4	141	0.47	0.475	23
1287117	Soil		15.8	130.1	59.7	194	1.9	203.1	41.7	568	7.71	157.3	6.8	5.2	27	0.6	5.0	0.7	37	0.34	0.159	24
1287118	Soil		25.1	115.1	47.6	472	2.3	125.3	13.6	374	4.04	79.7	3.5	1.0	112	2.9	7.3	0.4	274	0.55	0.399	18
1287119	Soil		5.7	56.8	22.1	128	0.4	44.0	14.0	404	4.10	37.5	5.8	0.9	14	0.1	2.6	0.3	39	0.04	0.142	11
1287120	Soil		11.2	38.7	19.1	181	0.1	47.1	7.9	94	2.62	283.2	1.7	0.2	14	0.3	3.9	0.4	71	0.02	0.073	9
1287121	Soil		9.2	96.4	46.4	232	1.9	86.1	27.4	638	6.97	67.7	5.9	2.4	35	0.8	3.4	0.4	53	0.18	0.219	18
1287122	Soil		9.0	48.9	30.6	189	0.4	56.5	10.3	260	4.43	139.3	3.2	0.6	62	0.4	3.9	0.4	72	0.09	0.326	14
1287123	Soil		9.7	66.6	43.7	156	0.5	58.0	18.8	370	5.50	32.9	2.5	1.7	11	0.3	2.8	0.4	23	0.03	0.105	14
1287124	Soil		15.2	82.8	22.4	383	1.2	120.1	15.2	295	3.55	25.0	2.7	2.7	59	3.7	4.4	0.3	59	0.33	0.195	29
1287125	Soil		23.1	209.1	17.9	1213	2.0	208.7	18.7	377	5.56	54.1	4.4	3.5	36	4.9	6.0	0.3	163	0.42	0.167	14
1287126	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287127	Soil		3.1	27.9	20.6	262	0.1	44.5	29.1	1552	4.64	58.0	<0.5	3.1	7	2.0	1.9	0.7	19	0.04	0.067	5
1287128	Soil		2.1	88.1	34.8	89	<0.1	35.0	29.5	1255	4.40	54.3	0.5	1.9	11	0.3	3.8	1.2	13	0.11	0.080	4
1287129	Soil		1.5	20.7	38.9	40	<0.1	21.8	13.5	209	2.87	8.9	0.9	1.7	13	<0.1	0.8	0.4	9	0.02	0.052	9
1287130	Soil		1.8	11.1	7.1	35	<0.1	9.9	4.0	190	1.35	4.8	<0.5	0.1	5	<0.1	0.8	0.2	18	0.01	0.032	5
1287131	Soil		0.9	23.2	27.8	57	<0.1	22.5	14.4	275	2.85	9.6	<0.5	3.2	14	<0.1	0.9	0.5	7	0.01	0.040	12
1287132	Soil		15.0	54.3	40.3	1010	0.1	52.6	11.8	941	5.62	47.8	3.8	0.4	21	3.0	24.9	0.2	114	0.31	0.417	8
1287133	Soil		5.3	67.5	19.3	130	<0.1	33.0	10.4	137	2.71	15.2	1.2	0.7	9	0.2	2.6	0.3	33	0.03	0.065	7
1287134	Soil		55.0	275.5	111.7	2713	3.3	135.8	21.0	617	5.81	73.5	8.2	1.1	22	16.9	12.5	0.4	160	0.35	0.309	16
1287135	Soil		14.8	47.5	16.8	177	0.8	39.0	3.9	58	1.68	27.2	3.4	0.8	11	0.8	3.6	0.2	60	0.04	0.061	13
1287136	Soil		16.1	74.5	26.3	413	1.9	112.7	16.2	191	3.73	21.9	2.3	2.4	34	3.0	4.0	0.3	24	0.09	0.113	19
1287137	Soil		13.4	59.3	19.2	485	1.5	108.0	10.4	186	2.77	22.0	4.6	3.2	50	3.1	4.2	0.3	46	0.42	0.146	18
1287138	Soil		52.4	65.1	11.1	299	0.6	140.6	7.4	193	1.87	31.8	1.8	1.9	140	3.6	5.5	0.1	99	4.54	0.133	13
1287139	Soil		22.5	15.8	6.8	92	0.2	37.6	2.9	55	0.92	16.0	<0.5	0.4	11	0.6	2.3	0.2	93	0.10	0.113	13
1287140	Soil		52.9	56.7	9.4	329	0.2	156.7	7.2	207	1.55	26.4	1.3	1.6	93	3.9	5.6	0.1	165	3.24	0.130	23

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001947.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287111	Soil	16	0.04	594	0.007	5	0.61	0.007	0.36	0.2	0.58	1.2	1.2	0.71	2	5.4	0.2
1287112	Soil	11	0.05	468	0.004	5	0.34	0.008	0.11	0.1	0.44	1.4	0.4	0.16	<1	2.8	<0.2
1287113	Soil	14	0.04	220	0.005	5	0.67	0.007	0.08	<0.1	0.07	0.7	0.4	0.05	2	1.8	<0.2
1287114	Soil	19	0.11	245	0.014	4	0.76	0.004	0.11	0.2	0.12	1.5	0.7	<0.05	3	2.4	<0.2
1287115	Soil	15	0.02	170	0.008	6	0.46	0.004	0.10	0.3	0.05	0.9	0.6	<0.05	2	2.0	0.2
1287116	Soil	19	0.04	641	0.008	8	0.56	0.005	0.16	0.2	0.34	1.8	0.3	0.26	2	17.3	<0.2
1287117	Soil	26	0.07	514	0.003	5	0.38	0.002	0.16	<0.1	0.74	11.0	0.5	<0.05	<1	2.4	0.2
1287118	Soil	21	0.06	981	0.008	9	0.47	0.007	0.16	0.2	0.57	2.8	0.4	0.17	1	5.7	0.3
1287119	Soil	15	0.09	1086	0.011	4	0.84	0.007	0.08	<0.1	0.10	2.6	0.2	<0.05	3	2.0	<0.2
1287120	Soil	11	0.03	363	0.005	3	0.57	0.007	0.07	0.1	0.05	0.7	0.2	<0.05	3	1.8	<0.2
1287121	Soil	12	0.09	4010	0.006	4	0.97	0.003	0.12	<0.1	0.31	5.0	0.3	<0.05	2	3.0	0.2
1287122	Soil	19	0.12	434	0.009	3	0.80	0.004	0.11	0.2	0.07	1.7	0.3	<0.05	3	3.1	0.2
1287123	Soil	9	0.05	384	0.003	3	0.50	0.003	0.10	0.1	0.12	3.1	0.3	<0.05	2	1.2	<0.2
1287124	Soil	19	0.05	3799	0.005	6	0.61	0.003	0.15	<0.1	0.28	3.9	0.3	<0.05	1	2.4	<0.2
1287125	Soil	33	0.04	1342	0.004	6	0.37	0.002	0.10	0.1	0.73	8.4	0.8	<0.05	<1	8.2	<0.2
1287126	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287127	Soil	7	0.04	410	0.003	5	0.47	0.004	0.16	<0.1	0.04	5.2	0.2	<0.05	2	0.8	<0.2
1287128	Soil	6	0.04	639	0.005	5	0.38	0.004	0.13	<0.1	0.05	4.0	0.1	<0.05	2	0.8	<0.2
1287129	Soil	4	0.01	66	0.002	5	0.32	0.003	0.10	<0.1	0.04	2.2	<0.1	<0.05	1	<0.5	<0.2
1287130	Soil	5	0.02	64	0.008	2	0.29	0.019	0.06	<0.1	0.01	0.7	<0.1	<0.05	2	<0.5	<0.2
1287131	Soil	4	0.02	91	0.001	2	0.28	0.002	0.10	<0.1	0.04	2.9	<0.1	<0.05	<1	0.5	<0.2
1287132	Soil	13	0.06	181	0.010	4	0.50	0.010	0.08	0.1	0.10	1.8	0.3	<0.05	2	2.6	<0.2
1287133	Soil	7	0.03	90	0.004	2	0.47	0.007	0.06	<0.1	0.04	1.4	0.1	<0.05	2	1.6	<0.2
1287134	Soil	21	0.03	758	0.006	5	0.45	0.003	0.12	0.1	0.59	3.5	0.5	<0.05	3	5.9	<0.2
1287135	Soil	12	0.02	200	0.002	3	0.39	0.004	0.06	<0.1	0.12	1.6	0.3	<0.05	1	1.2	<0.2
1287136	Soil	9	0.03	2330	0.002	3	0.55	0.003	0.08	<0.1	0.42	3.6	0.2	<0.05	<1	1.6	<0.2
1287137	Soil	12	0.10	6121	0.007	6	0.83	0.005	0.12	<0.1	0.39	4.6	0.4	<0.05	2	1.8	<0.2
1287138	Soil	14	2.08	950	0.007	6	0.26	0.006	0.09	0.2	0.45	4.1	1.0	0.06	<1	3.4	<0.2
1287139	Soil	12	0.08	208	0.007	2	0.39	0.007	0.08	0.2	0.08	1.1	0.7	<0.05	2	1.2	<0.2
1287140	Soil	20	1.69	384	0.006	6	0.50	0.005	0.10	0.2	0.18	2.7	1.3	<0.05	1	1.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001947.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1284461	Soil	31.6	76.1	14.9	418	1.2	99.5	6.6	150	1.94	44.7	4.3	3.4	77	4.7	12.3	0.2	190	0.52	0.235	19
1284462	Soil	26.6	51.0	18.4	342	1.0	73.0	9.3	191	2.23	44.6	7.8	2.2	62	2.5	12.1	0.2	168	0.38	0.165	18
1284463	Soil	29.3	62.8	19.0	400	1.0	81.8	7.2	125	2.31	61.9	7.8	3.8	71	5.5	13.6	0.2	176	0.40	0.164	21
1284464	Soil	25.3	26.0	16.2	509	0.7	69.3	7.3	223	2.25	56.3	5.4	1.9	49	1.2	12.5	0.3	160	0.44	0.154	14
1284465	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284466	Soil	25.5	60.2	25.0	2335	1.1	506.8	4.5	978	0.86	23.0	6.6	0.9	95	21.9	15.9	0.2	105	1.78	0.111	7
1284467	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284468	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284469	Soil	28.9	52.2	20.3	541	1.5	85.7	4.7	111	1.55	85.4	3.2	2.2	62	4.7	13.3	0.2	160	0.43	0.119	14
1284470	Soil	22.6	49.9	15.0	429	2.2	93.9	4.1	73	1.48	69.5	7.4	0.6	33	5.5	11.2	0.1	118	0.37	0.098	4
1284471	Soil	154.8	95.2	20.9	1759	2.9	245.9	20.4	1385	5.82	979.2	8.9	2.3	155	6.2	37.6	0.2	154	0.47	0.220	9
1284472	Soil	189.4	143.3	16.6	2661	2.8	281.4	29.4	1511	11.98	5460	8.1	1.8	90	14.4	46.4	0.2	211	0.41	0.344	7
1284473	Soil	94.9	70.2	13.1	4064	1.8	782.6	32.1	3109	4.15	600.1	10.6	0.9	72	20.3	54.1	0.1	122	1.27	0.253	6
1284474	Soil	60.1	68.0	13.7	3078	2.0	511.8	27.0	2368	2.70	310.0	7.1	1.1	77	11.4	27.8	0.2	93	1.19	0.167	6
1284475	Soil	59.2	59.6	4.8	3116	0.7	730.8	26.7	3957	1.30	226.3	4.7	0.2	63	16.2	22.2	<0.1	35	1.74	0.137	3
1284476	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284477	Soil	47.1	46.8	13.4	2969	1.6	417.8	17.0	1404	2.41	504.3	12.5	0.6	65	10.7	23.1	0.2	73	1.35	0.192	5
1284478	Soil	17.6	56.0	16.2	439	1.5	70.1	9.8	233	2.29	51.0	7.1	1.2	76	3.5	7.1	0.2	136	0.46	0.173	7
1284479	Soil	12.0	54.4	14.5	195	0.8	40.2	4.7	76	1.94	32.8	3.9	1.5	62	2.2	6.0	0.2	90	0.13	0.114	7
1284480	Soil	11.9	60.2	14.2	268	0.9	59.5	5.2	100	1.89	36.8	6.1	1.7	78	3.2	6.2	0.2	107	0.26	0.134	6
1283331	Soil	2.9	60.9	105.4	51	1.9	23.0	5.0	141	2.60	276.2	1.1	0.5	24	0.2	4.1	1.6	24	0.04	0.098	2
1283332	Soil	5.2	86.2	33.0	51	1.5	50.2	11.4	200	4.34	116.1	5.7	1.0	37	0.2	3.1	0.4	46	0.02	0.094	4
1283333	Soil	7.7	29.3	46.6	33	1.8	14.5	1.9	41	1.29	68.3	1.9	0.1	68	0.2	2.8	0.4	47	0.05	0.090	2
1283334	Soil	0.7	16.9	19.3	22	0.1	8.0	3.4	57	0.57	11.0	<0.5	0.7	28	0.1	0.3	0.2	8	0.05	0.024	3
1283335	Soil	2.0	12.0	12.3	67	<0.1	13.0	5.0	57	0.98	14.1	0.8	0.6	9	<0.1	0.6	0.2	11	<0.01	0.024	2
1283336	Soil	1.8	26.4	15.2	77	0.1	24.1	8.2	112	1.85	12.4	1.1	1.3	22	0.2	0.7	0.2	17	0.03	0.033	3
1283337	Soil	4.3	39.2	27.8	38	1.3	30.4	4.3	118	1.08	8.9	4.0	1.0	43	0.3	2.5	0.2	36	0.15	0.035	3
1283338	Soil	5.9	94.7	54.6	77	3.9	100.6	14.2	897	4.47	35.3	2.5	1.0	143	0.6	4.4	0.2	93	0.25	0.288	4
1283339	Soil	4.1	53.1	27.2	47	1.3	39.0	9.2	309	1.96	17.9	3.5	0.5	57	0.2	2.2	0.2	42	0.05	0.110	5
1283340	Soil	5.4	30.2	27.2	37	1.2	19.5	3.8	63	1.56	13.1	1.6	0.4	32	<0.1	2.3	0.2	42	0.02	0.077	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001947.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284461	Soil		19	0.05	1217	0.006	6	0.45	0.003	0.12	0.2	1.00	3.3	0.8	0.05	1	2.1	<0.2
1284462	Soil		24	0.11	965	0.036	5	0.80	0.005	0.11	0.3	0.61	2.9	0.9	0.06	2	2.8	0.2
1284463	Soil		23	0.10	1201	0.007	4	0.59	0.004	0.12	0.3	0.60	4.2	1.2	0.08	2	3.2	<0.2
1284464	Soil		25	0.21	657	0.010	4	0.98	0.008	0.10	0.3	0.61	2.9	0.9	<0.05	3	1.4	<0.2
1284465	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284466	Soil		16	0.06	710	0.011	8	0.56	0.013	0.07	0.3	0.74	2.3	1.1	0.21	2	4.7	0.2
1284467	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284468	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284469	Soil		21	0.09	1604	0.005	7	0.61	0.005	0.11	0.3	1.32	2.7	1.4	<0.05	2	4.5	<0.2
1284470	Soil		15	0.06	773	0.003	3	0.70	0.016	0.07	0.2	1.29	2.4	0.9	<0.05	2	5.1	<0.2
1284471	Soil		21	0.06	3682	0.005	6	0.57	0.004	0.12	0.2	1.73	3.3	1.5	<0.05	2	5.8	<0.2
1284472	Soil		21	0.06	3174	0.006	6	1.01	0.005	0.10	0.2	1.77	3.5	1.3	<0.05	2	8.2	<0.2
1284473	Soil		14	0.08	1226	0.005	8	0.62	0.007	0.06	0.2	1.79	2.2	1.2	0.13	2	7.6	<0.2
1284474	Soil		16	0.09	937	0.005	5	0.68	0.007	0.05	0.1	1.41	2.3	1.0	<0.05	2	4.6	<0.2
1284475	Soil		6	0.05	631	0.008	5	0.48	0.019	0.02	<0.1	0.73	0.8	0.4	0.13	1	4.4	<0.2
1284476	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1284477	Soil		9	0.08	769	0.005	6	0.68	0.010	0.04	0.1	1.58	1.8	0.8	0.09	2	3.8	<0.2
1284478	Soil		24	0.08	2396	0.002	5	0.57	0.004	0.10	0.1	1.12	3.0	0.7	<0.05	2	3.7	<0.2
1284479	Soil		18	0.05	1076	0.004	3	0.44	0.002	0.08	0.1	0.72	2.7	0.5	<0.05	1	2.1	0.2
1284480	Soil		21	0.05	1699	0.002	4	0.40	0.003	0.09	0.1	1.00	3.1	0.4	<0.05	1	1.6	<0.2
1283331	Soil		8	0.02	162	0.004	2	0.65	0.010	0.05	<0.1	0.16	1.4	0.3	<0.05	2	1.5	<0.2
1283332	Soil		14	0.04	176	0.004	<1	0.57	0.003	0.08	<0.1	0.04	4.5	0.3	<0.05	2	2.9	<0.2
1283333	Soil		8	0.01	382	0.001	3	0.29	0.007	0.08	<0.1	0.18	0.6	0.5	0.10	2	5.0	<0.2
1283334	Soil		3	0.03	162	<0.001	<1	0.24	0.003	0.06	<0.1	0.02	1.1	0.3	0.06	<1	<0.5	<0.2
1283335	Soil		4	<0.01	231	<0.001	<1	0.25	0.003	0.06	<0.1	0.02	1.3	0.2	<0.05	<1	<0.5	<0.2
1283336	Soil		6	0.02	475	0.001	<1	0.29	0.005	0.06	<0.1	0.05	3.4	0.2	<0.05	<1	0.8	<0.2
1283337	Soil		7	0.01	904	0.002	3	0.26	0.004	0.06	<0.1	0.73	2.5	0.6	0.06	1	1.4	<0.2
1283338	Soil		23	0.05	333	0.010	2	1.19	0.011	0.05	<0.1	0.09	7.9	0.5	0.10	2	2.0	<0.2
1283339	Soil		12	0.05	261	0.004	<1	0.46	0.005	0.09	<0.1	0.08	2.1	0.3	<0.05	2	1.6	<0.2
1283340	Soil		9	0.01	289	0.003	1	0.33	0.004	0.11	<0.1	0.08	1.5	0.3	0.14	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001947.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283351	Soil		32.7	82.8	72.0	305	2.7	75.3	6.2	85	3.20	65.8	3.2	0.4	317	3.1	11.3	0.3	322	0.39	0.582	21
1283352	Soil		4.7	154.6	10.1	229	1.6	138.7	4.2	60	1.28	27.4	1.3	2.6	141	1.5	3.2	0.2	84	1.06	0.260	17
1283353	Soil		4.7	147.9	10.5	272	2.3	107.4	4.0	101	1.50	24.3	3.4	1.0	149	1.4	3.6	0.2	73	0.95	0.456	28
1283354	Soil		29.0	140.0	40.0	2711	3.0	290.5	27.2	597	6.22	100.9	2.9	2.1	412	14.5	8.7	0.2	186	3.78	0.354	19
1283355	Soil		34.6	179.4	29.5	1276	2.9	420.1	42.0	679	8.12	61.4	12.2	4.0	141	14.8	9.2	0.2	259	0.58	0.265	26
1283356	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283357	Soil		25.0	96.0	19.5	376	2.3	151.4	10.6	253	4.72	44.6	3.0	0.4	127	5.7	7.8	0.3	339	0.68	0.465	14
1283358	Soil		3.5	214.2	12.3	302	0.8	207.1	10.1	90	1.47	22.5	1.6	1.7	104	0.9	2.1	0.2	62	0.66	0.248	12
1283359	Soil		12.8	257.0	13.0	640	5.0	239.8	10.1	242	2.45	59.9	6.1	1.4	101	0.7	6.4	0.2	150	1.08	0.561	17
1283360	Soil		95.6	158.1	68.3	375	7.5	96.6	12.2	171	2.86	55.5	2.1	0.3	185	7.9	16.1	0.4	831	0.56	0.417	19
1283341	Soil		7.1	94.8	54.3	76	4.4	86.7	16.6	717	4.45	23.2	8.5	0.9	69	0.4	3.6	0.3	60	0.12	0.146	5
1283342	Soil		7.8	211.8	34.2	133	3.0	83.1	26.9	1035	6.11	31.6	4.2	1.5	46	0.9	3.9	0.3	78	0.09	0.155	6
1283343	Soil		8.5	134.8	51.7	565	2.7	109.9	28.3	767	4.77	31.8	6.3	1.4	63	1.9	5.7	0.5	66	0.38	0.140	4
1283344	Soil		12.7	138.0	50.1	444	2.0	103.9	29.1	956	4.88	35.9	2.8	1.4	98	1.6	6.7	0.5	107	0.43	0.225	7
1283345	Soil		8.5	127.7	48.0	392	2.2	101.2	34.1	1181	4.84	29.4	5.3	2.1	50	1.5	4.9	0.6	58	0.29	0.140	5
1283346	Soil		10.1	113.1	45.2	323	1.9	93.0	30.4	1188	4.99	28.2	2.7	2.0	46	1.3	5.2	0.6	70	0.28	0.139	5
1283347	Soil		33.1	40.6	11.2	601	0.5	79.9	5.8	121	1.90	25.1	<0.5	1.5	35	4.5	14.6	0.2	154	0.46	0.081	8
1283348	Soil		32.6	108.9	77.3	359	4.1	89.1	11.0	165	3.40	95.6	1.6	1.0	479	4.0	15.9	0.5	264	0.57	0.558	24
1283349	Soil		68.6	210.5	140.6	501	6.2	146.5	7.4	85	5.68	187.3	4.3	5.0	634	8.6	32.1	0.8	545	0.98	1.132	37
1283350	Soil		79.2	236.8	115.4	367	10.3	174.2	4.4	46	4.16	89.6	<0.5	4.0	662	9.9	22.6	0.6	783	1.29	1.043	32
1283371	Soil		36.2	50.0	25.5	230	1.4	71.7	5.8	229	2.46	57.5	<0.5	0.2	40	1.4	7.2	0.3	131	0.14	0.198	7
1283372	Soil		38.4	101.5	31.9	577	3.3	167.0	19.1	697	3.81	64.9	4.1	0.8	85	6.2	10.6	0.4	130	0.44	0.290	12
1283373	Soil		46.6	122.6	28.1	1156	5.6	255.0	12.9	323	3.60	80.3	3.1	2.5	111	12.1	13.7	0.3	169	0.72	0.175	10
1283374	Soil		36.0	61.0	16.1	384	3.2	123.6	7.7	201	2.50	48.2	0.6	0.4	72	5.0	10.1	0.2	164	0.16	0.169	7
1283375	Soil		31.8	250.9	363.3	2292	2.1	97.0	18.8	739	4.47	38.6	5.5	1.2	38	13.2	7.5	0.3	138	0.33	0.257	14
1283376	Soil		4.3	32.0	27.7	281	0.2	18.8	2.7	275	1.11	8.9	<0.5	<0.1	10	0.4	1.4	<0.1	29	0.06	0.140	3
1283377	Soil		8.6	72.1	41.1	859	0.2	47.1	7.4	457	3.30	25.8	1.0	0.3	23	2.1	2.8	0.2	74	0.22	0.381	8
1283378	Soil		10.8	65.8	48.9	372	0.2	48.8	7.3	189	2.80	32.4	2.8	0.5	24	0.4	3.3	0.3	80	0.04	0.154	10
1283379	Soil		8.3	167.8	19.9	404	0.2	68.5	11.9	97	3.15	48.7	2.2	0.4	6	0.4	3.1	0.3	47	0.05	0.114	5
1283380	Soil		26.3	133.5	72.3	107	2.7	63.0	9.0	249	3.10	67.1	2.6	4.2	36	0.3	11.2	0.3	64	0.51	0.095	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001947.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283351	Soil	24	0.08	772	0.013	3	0.71	0.004	0.15	0.5	0.44	1.2	0.7	0.20	3	7.3	0.4
1283352	Soil	12	0.20	397	0.003	6	0.33	0.003	0.16	<0.1	2.06	3.7	0.3	0.10	<1	4.0	<0.2
1283353	Soil	18	0.05	603	0.007	7	0.55	0.007	0.18	<0.1	1.75	2.2	0.7	0.15	1	5.1	<0.2
1283354	Soil	48	1.59	703	0.005	6	0.41	0.004	0.16	0.2	4.48	5.3	1.9	0.29	2	3.8	<0.2
1283355	Soil	60	0.05	481	0.004	4	0.48	0.002	0.12	0.2	1.99	9.9	3.4	0.15	1	4.8	0.4
1283356	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1283357	Soil	22	0.10	768	0.006	6	0.74	0.004	0.17	0.3	0.50	1.4	0.9	0.15	2	5.3	<0.2
1283358	Soil	13	0.05	345	0.004	5	0.43	0.002	0.11	<0.1	0.61	4.5	0.1	0.08	<1	3.2	0.2
1283359	Soil	29	0.08	616	0.006	6	0.62	0.003	0.17	0.1	1.70	5.0	0.4	0.14	1	9.6	<0.2
1283360	Soil	36	0.06	562	0.009	8	0.67	0.006	0.26	0.6	0.33	1.5	0.8	0.42	3	9.7	0.9
1283341	Soil	17	0.04	342	0.003	2	0.75	0.008	0.14	<0.1	0.12	5.8	0.6	0.20	2	3.8	<0.2
1283342	Soil	23	0.06	262	0.005	1	1.00	0.010	0.11	<0.1	0.16	6.9	0.5	0.11	3	2.5	0.3
1283343	Soil	18	0.10	392	0.002	<1	0.89	0.011	0.09	<0.1	0.20	5.4	0.3	0.08	3	3.3	<0.2
1283344	Soil	21	0.09	546	0.003	4	0.95	0.007	0.13	0.1	0.22	5.4	0.5	0.17	3	3.4	<0.2
1283345	Soil	18	0.10	625	0.002	2	0.82	0.007	0.09	<0.1	0.19	6.0	0.4	0.07	2	2.6	<0.2
1283346	Soil	20	0.10	569	0.002	2	0.83	0.006	0.09	<0.1	0.23	6.1	0.4	0.09	2	2.8	0.3
1283347	Soil	11	0.09	384	0.003	4	0.38	0.010	0.07	<0.1	0.37	3.3	0.3	0.08	<1	1.7	<0.2
1283348	Soil	30	0.05	535	0.008	5	0.68	0.008	0.20	0.2	0.32	1.9	0.7	0.35	2	9.1	0.5
1283349	Soil	44	0.05	219	0.013	5	0.81	0.007	0.32	0.6	0.92	4.8	1.0	0.48	2	16.3	0.8
1283350	Soil	59	0.05	181	0.010	7	0.73	0.007	0.36	0.8	1.03	4.3	0.7	0.50	3	15.1	1.0
1283371	Soil	13	0.04	309	0.002	3	0.45	0.007	0.11	0.3	0.10	0.3	1.9	0.19	1	2.2	0.3
1283372	Soil	16	0.06	645	0.003	4	0.58	0.006	0.16	0.4	0.54	1.7	2.0	0.21	1	3.9	<0.2
1283373	Soil	18	0.04	260	0.002	6	0.46	0.003	0.21	0.5	0.64	3.8	2.2	0.34	<1	5.1	<0.2
1283374	Soil	15	0.07	211	0.002	3	0.44	0.008	0.11	0.4	0.45	0.9	1.4	0.19	<1	2.9	<0.2
1283375	Soil	20	0.09	933	0.005	7	0.72	0.004	0.16	0.2	0.36	3.8	0.5	0.05	3	6.0	0.3
1283376	Soil	6	0.02	415	0.001	<1	0.45	0.014	0.04	<0.1	0.05	0.2	0.1	0.06	2	1.7	<0.2
1283377	Soil	16	0.07	1499	0.005	1	0.86	0.005	0.06	0.1	0.27	0.7	0.2	0.09	3	2.0	<0.2
1283378	Soil	18	0.09	181	0.007	2	0.85	0.006	0.06	0.1	0.16	0.7	0.3	<0.05	4	1.9	<0.2
1283379	Soil	10	0.03	177	0.002	4	0.43	0.004	0.09	<0.1	0.15	1.2	0.2	<0.05	2	2.7	<0.2
1283380	Soil	5	0.12	2123	0.001	3	0.32	0.003	0.09	<0.1	0.66	4.3	0.5	<0.05	<1	4.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001947.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1283381	Soil	20.6	106.0	77.0	107	2.1	36.3	5.0	184	2.26	46.9	0.8	2.1	28	0.6	10.0	0.3	37	0.42	0.096	5
1283382	Soil	20.6	119.0	76.3	359	2.3	72.7	14.0	502	4.13	106.6	1.6	2.4	29	1.4	13.1	0.3	58	0.65	0.164	8
1283383	Soil	16.9	98.3	69.2	163	1.9	44.9	6.5	222	2.63	58.5	3.2	1.4	30	0.6	10.0	0.3	45	0.59	0.133	6
1283384	Soil	16.8	113.3	68.1	224	2.5	54.9	7.4	292	3.24	56.3	5.0	1.7	40	0.9	10.1	0.3	55	0.80	0.181	7
1283385	Soil	29.0	204.3	91.9	398	4.9	102.5	15.6	233	3.84	84.8	2.4	2.2	39	1.4	17.1	0.3	82	0.54	0.225	7
1283386	Soil	23.2	158.4	58.2	649	2.5	131.4	12.9	412	3.86	75.6	4.5	1.6	65	5.0	10.7	0.3	94	0.79	0.231	10
1283387	Soil	9.6	76.1	23.6	376	0.1	42.3	7.1	49	2.22	38.2	9.3	0.1	10	0.7	9.7	0.2	42	0.05	0.153	4
1283388	Soil	1.3	4.5	2.8	21	0.5	5.0	0.7	57	0.34	2.8	<0.5	<0.1	7	0.1	0.3	<0.1	13	0.03	0.100	1
1283389	Soil	15.8	115.4	53.5	679	0.3	103.3	10.0	141	3.70	39.7	4.3	0.8	36	1.0	5.5	0.2	91	0.09	0.205	11
1283390	Soil	18.9	29.7	26.3	113	0.7	36.0	3.9	32	1.46	26.6	<0.5	<0.1	18	0.2	4.0	0.2	123	0.01	0.048	11
1287411	Soil	17.2	54.2	22.3	280	1.2	60.6	8.5	246	2.35	85.6	7.2	1.9	60	2.2	11.8	0.2	135	0.31	0.116	9
1287412	Soil	19.4	53.7	21.3	323	1.1	65.7	9.7	195	2.49	216.1	11.7	2.2	67	3.0	14.1	0.3	110	0.27	0.148	11
1287413	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287414	Soil	13.6	80.0	21.4	433	1.2	92.4	13.8	286	2.62	136.1	8.3	2.9	61	3.8	11.2	0.4	106	0.27	0.128	10
1287415	Soil	8.8	50.2	17.5	269	1.0	53.4	11.2	543	1.81	85.3	8.9	1.9	46	2.9	7.5	0.3	80	0.18	0.101	9
1287416	Soil	10.0	62.5	18.9	308	1.3	72.7	13.9	627	2.07	166.7	10.1	2.1	47	2.9	7.8	0.3	91	0.31	0.111	8
1287417	Soil	15.4	70.8	22.4	447	1.3	82.5	15.9	379	2.88	186.8	7.6	2.6	62	3.2	11.5	0.3	105	0.38	0.112	8
1287418	Soil	8.7	93.7	16.5	592	1.4	172.4	16.9	730	2.57	129.2	10.9	1.7	56	8.0	7.7	0.3	80	0.34	0.098	7
1287419	Soil	10.4	78.4	18.9	955	1.2	203.4	32.6	1435	3.80	167.4	11.3	2.4	66	13.9	9.0	0.3	62	0.67	0.089	8
1287420	Soil	10.8	80.3	18.8	1091	1.2	206.5	15.9	514	3.05	112.7	13.5	2.2	75	7.7	10.6	0.3	74	0.85	0.094	8
1287401	Soil	51.3	99.2	92.4	564	2.9	158.5	9.5	257	3.57	81.4	5.5	5.1	103	6.9	34.8	0.3	315	0.52	0.199	13
1287402	Soil	39.9	73.6	36.7	510	1.8	131.6	14.9	488	3.97	123.3	5.4	4.5	49	3.3	22.2	0.3	250	0.21	0.295	14
1287403	Soil	62.6	63.3	94.7	261	2.7	57.8	6.4	166	3.03	118.2	10.1	3.5	153	5.0	31.8	0.4	274	0.16	0.205	12
1287404	Soil	69.9	57.8	65.9	695	2.5	209.5	11.6	908	2.80	138.6	20.7	1.8	139	16.2	49.9	0.3	349	0.30	0.194	10
1287405	Soil	123.9	64.2	54.8	901	2.6	419.6	31.7	2068	3.42	290.1	38.2	2.2	122	14.9	124.4	0.3	429	0.81	0.311	10
1287406	Soil	50.7	61.4	54.6	520	3.0	169.2	7.4	565	2.56	156.9	34.8	2.4	135	10.0	64.8	0.4	316	0.51	0.210	13
1287407	Soil	73.8	62.7	39.6	841	2.3	272.4	12.2	526	4.43	211.5	19.1	2.7	93	7.5	86.3	0.4	294	0.45	0.239	13
1287408	Soil	52.0	52.3	30.2	579	1.9	133.5	8.4	410	3.47	143.2	25.2	2.6	80	4.8	52.8	0.3	256	0.35	0.184	14
1287409	Soil	90.5	50.5	30.5	760	2.2	192.3	13.0	748	4.03	232.7	22.9	1.5	77	6.9	86.0	0.3	254	0.53	0.270	9
1287410	Soil	42.5	67.8	32.9	561	2.2	145.1	12.0	795	3.19	137.1	30.5	1.8	76	6.6	31.7	0.3	170	0.45	0.192	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001947.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283381	Soil	5	0.06	1019	0.002	3	0.35	0.005	0.09	<0.1	0.88	3.0	0.7	0.10	<1	6.5	<0.2
1283382	Soil	9	0.13	783	0.002	6	0.41	0.004	0.10	<0.1	0.75	4.8	0.8	0.07	<1	8.3	<0.2
1283383	Soil	7	0.08	780	0.002	3	0.37	0.005	0.08	<0.1	0.65	2.8	0.6	0.07	<1	5.7	<0.2
1283384	Soil	8	0.11	993	0.002	4	0.46	0.006	0.08	<0.1	0.77	3.2	0.6	0.11	<1	5.1	<0.2
1283385	Soil	10	0.07	781	0.002	4	0.48	0.003	0.09	<0.1	0.60	4.6	0.6	<0.05	1	8.2	<0.2
1283386	Soil	14	0.17	690	0.003	6	0.44	0.005	0.12	0.1	0.81	3.5	0.7	0.14	1	5.4	<0.2
1283387	Soil	7	0.02	166	0.004	2	0.34	0.007	0.06	<0.1	0.17	0.6	0.2	0.05	2	2.5	<0.2
1283388	Soil	3	0.01	39	0.002	<1	0.20	0.016	0.03	<0.1	0.03	0.1	<0.1	<0.05	<1	<0.5	<0.2
1283389	Soil	16	0.03	178	0.002	3	0.46	0.003	0.09	0.1	0.09	1.7	0.3	0.08	1	2.2	<0.2
1283390	Soil	12	0.01	93	0.002	2	0.21	0.002	0.08	0.2	0.04	0.2	0.4	0.07	1	0.7	<0.2
1287411	Soil	22	0.14	908	0.001	2	0.73	0.007	0.09	0.2	1.28	2.7	0.7	<0.05	2	3.6	<0.2
1287412	Soil	18	0.11	995	0.002	3	0.59	0.006	0.09	0.3	1.66	2.5	0.8	0.06	2	3.1	<0.2
1287413	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287414	Soil	25	0.20	1093	0.001	4	0.93	0.004	0.08	0.2	2.02	3.7	0.7	0.05	2	4.3	<0.2
1287415	Soil	20	0.14	963	0.001	3	0.80	0.006	0.08	0.2	1.24	2.3	0.6	<0.05	2	2.0	<0.2
1287416	Soil	22	0.15	941	<0.001	4	0.94	0.009	0.09	0.2	1.77	3.2	0.7	<0.05	2	3.4	<0.2
1287417	Soil	24	0.20	1075	0.001	3	0.90	0.005	0.09	0.2	1.71	3.5	0.7	<0.05	2	3.3	<0.2
1287418	Soil	24	0.18	1004	<0.001	3	1.09	0.006	0.09	0.2	1.57	3.5	0.6	0.05	2	4.5	<0.2
1287419	Soil	21	0.20	824	0.002	5	1.02	0.006	0.07	0.2	1.44	4.1	0.4	<0.05	2	2.9	<0.2
1287420	Soil	22	0.20	866	0.004	9	0.93	0.006	0.09	0.2	1.54	4.1	0.6	<0.05	2	4.1	<0.2
1287401	Soil	29	0.11	1052	0.007	9	0.38	0.004	0.18	0.5	2.45	5.1	3.0	0.10	2	13.9	<0.2
1287402	Soil	27	0.04	646	0.006	5	0.67	0.003	0.10	0.3	1.66	4.3	1.5	<0.05	1	5.9	0.3
1287403	Soil	26	0.05	629	0.005	5	0.63	0.005	0.19	0.6	1.89	3.7	3.8	0.30	2	16.0	0.3
1287404	Soil	30	0.06	916	0.005	6	0.71	0.007	0.16	0.6	4.22	2.8	4.1	0.17	2	12.0	0.4
1287405	Soil	24	0.09	741	0.005	6	0.70	0.006	0.11	0.6	4.13	3.0	5.7	<0.05	2	9.9	0.4
1287406	Soil	28	0.10	856	0.004	6	0.78	0.005	0.13	0.5	4.91	3.3	4.0	<0.05	2	6.4	0.4
1287407	Soil	26	0.12	682	0.005	5	0.80	0.005	0.11	0.4	2.33	4.2	3.0	<0.05	2	5.0	<0.2
1287408	Soil	25	0.10	913	0.005	5	0.64	0.004	0.10	0.4	2.62	3.4	1.7	<0.05	2	5.5	<0.2
1287409	Soil	22	0.09	598	0.005	5	0.89	0.010	0.10	0.3	3.25	2.7	3.1	<0.05	2	5.1	0.3
1287410	Soil	23	0.10	1007	0.004	3	0.93	0.007	0.10	0.3	4.38	3.2	1.9	<0.05	2	4.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001947.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287371	Soil		7.5	111.6	32.1	294	2.6	116.3	20.6	353	5.35	35.3	3.8	4.4	177	0.8	4.0	0.4	32	1.50	0.161	10
1287372	Soil		7.8	90.0	33.3	244	1.8	139.6	40.2	810	9.83	70.4	5.6	5.5	278	0.2	3.8	0.5	14	3.60	0.043	13
1287373	Soil		5.0	117.5	35.8	259	4.5	90.3	18.4	280	5.09	33.3	5.5	3.2	226	0.8	3.9	0.5	24	0.87	0.199	11
1287374	Soil		4.5	132.0	47.9	395	6.0	129.9	27.9	315	7.77	63.5	7.8	4.8	151	0.4	5.5	0.6	28	0.38	0.206	12
1287375	Soil		7.3	156.3	35.4	404	3.6	177.9	59.9	1100	10.22	251.2	15.1	3.2	81	0.8	25.1	0.7	30	0.48	0.117	12
1287376	Soil		3.3	248.9	40.3	128	2.2	196.1	97.0	1862	17.10	127.2	34.2	4.7	53	0.2	4.3	1.4	18	0.50	0.104	17
1287377	Soil		18.3	84.2	49.9	264	1.5	119.5	29.4	913	6.98	62.1	6.1	4.0	29	0.4	3.5	0.5	27	0.36	0.077	16
1287378	Soil		3.8	86.5	20.3	126	0.2	64.6	24.4	426	6.74	143.8	3.1	0.9	9	0.2	2.9	0.6	20	0.04	0.098	17
1287379	Soil		12.5	74.4	25.5	154	1.3	93.0	14.9	327	3.83	46.6	5.3	1.6	48	0.4	3.1	0.3	38	0.47	0.185	16
1287380	Soil		10.8	114.1	21.7	299	2.0	131.5	8.3	277	2.66	50.4	3.7	0.7	127	1.8	5.3	0.3	132	0.55	0.370	18
1287361	Soil		142.0	200.8	20.5	2859	3.3	371.9	7.4	150	1.69	126.6	1.9	1.4	266	22.6	50.4	0.2	935	10.50	0.126	17
1287362	Soil		129.0	193.3	20.4	2474	2.8	334.7	9.6	230	1.77	120.8	1.8	0.8	178	19.6	40.5	0.2	926	6.72	0.126	20
1287363	Soil		93.2	121.3	19.4	1037	1.3	281.2	9.3	207	2.48	103.8	<0.5	1.4	278	9.8	24.8	0.2	367	10.76	0.113	14
1287364	Soil		80.7	110.9	15.4	711	1.0	232.9	10.2	229	2.15	77.5	1.3	2.2	312	8.1	19.0	0.1	290	11.29	0.100	13
1287365	Soil		113.9	83.4	12.3	215	0.3	210.4	11.7	206	2.36	34.4	0.7	3.6	192	2.2	4.6	0.1	45	6.80	0.080	6
1287366	Soil		101.6	45.8	12.0	222	0.1	185.9	9.1	152	2.13	34.6	<0.5	4.0	47	1.8	5.6	0.1	68	1.66	0.076	7
1287367	Soil		110.2	60.7	14.8	298	0.2	217.0	12.0	189	2.52	31.1	<0.5	4.4	103	2.1	6.9	0.2	114	3.42	0.082	5
1287368	Soil		127.0	48.9	10.8	363	0.1	209.1	13.3	194	2.06	34.3	<0.5	4.3	69	3.3	7.2	0.2	108	2.63	0.086	7
1287369	Soil		85.7	86.5	20.1	467	1.0	193.1	12.7	207	2.81	33.7	1.0	4.7	80	2.8	6.9	0.2	79	1.04	0.118	10
1287370	Soil		19.7	110.7	22.7	537	2.6	136.2	16.8	270	3.19	34.2	2.3	3.1	59	4.0	8.9	0.3	61	0.60	0.146	15
1287391	Soil		15.0	124.1	76.3	401	2.3	139.5	12.0	234	3.80	74.7	6.5	1.7	198	1.6	6.8	0.5	128	2.41	0.634	22
1287392	Soil		14.9	113.6	22.8	362	2.9	135.9	9.9	487	2.46	72.0	3.4	0.7	425	4.7	9.4	0.2	163	11.22	0.234	13
1287393	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287394	Soil		4.0	32.1	53.5	133	0.4	40.7	5.0	134	1.88	38.4	0.8	0.1	44	0.2	2.5	0.4	36	0.11	0.203	12
1287395	Soil		3.4	46.6	10.4	73	0.2	59.1	14.2	275	3.41	159.0	3.0	0.6	8	0.1	1.9	0.3	35	0.07	0.080	19
1287396	Soil		3.3	78.6	22.6	73	0.7	67.4	26.0	1447	4.80	49.8	7.8	3.0	20	0.2	1.7	0.5	26	0.19	0.086	32
1287397	Soil		3.0	101.5	26.9	179	0.6	204.7	51.3	1302	8.08	74.7	9.9	8.7	16	0.1	2.8	0.5	27	0.23	0.078	23
1287398	Soil		15.2	28.7	14.8	127	0.2	48.7	10.8	279	3.00	32.1	2.1	0.6	7	0.1	1.8	0.2	44	0.07	0.078	7
1287399	Soil		3.2	46.7	8.7	82	<0.1	41.3	13.3	256	3.76	33.9	2.7	0.5	6	0.1	1.9	0.3	29	0.04	0.065	13
1287400	Soil		3.2	80.6	19.1	88	<0.1	59.4	29.9	624	5.71	27.9	5.6	1.4	17	0.2	2.6	0.5	33	0.10	0.066	18

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

CERTIFICATE OF ANALYSIS WHI11001947.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287371	Soil	13	0.60	4069	0.003	6	0.69	0.005	0.19	<0.1	0.33	7.4	0.3	<0.05	<1	4.7	0.3
1287372	Soil	9	1.77	1753	0.003	5	0.46	0.004	0.11	<0.1	0.38	10.8	0.3	0.12	<1	4.5	<0.2
1287373	Soil	11	0.16	3640	0.004	5	0.80	0.005	0.20	<0.1	0.81	6.7	0.3	0.08	1	7.2	<0.2
1287374	Soil	13	0.08	4888	0.004	3	1.04	0.004	0.23	<0.1	1.04	8.1	0.3	<0.05	1	9.0	0.3
1287375	Soil	12	0.16	1808	0.003	4	0.99	0.003	0.12	<0.1	2.06	9.1	0.6	<0.05	1	3.2	0.3
1287376	Soil	9	0.16	935	0.003	5	0.68	0.004	0.17	<0.1	0.38	11.5	0.5	0.20	1	2.1	0.6
1287377	Soil	8	0.09	679	0.002	4	0.37	0.002	0.14	<0.1	0.49	8.3	0.4	<0.05	<1	1.4	<0.2
1287378	Soil	7	0.03	191	0.005	2	0.46	0.006	0.07	<0.1	0.07	1.9	0.2	<0.05	2	0.8	0.2
1287379	Soil	9	0.07	833	0.005	5	0.48	0.005	0.11	<0.1	0.45	3.9	0.2	<0.05	1	1.9	0.2
1287380	Soil	21	0.12	646	0.007	5	0.62	0.006	0.16	0.4	0.64	2.0	0.5	0.15	2	4.1	<0.2
1287361	Soil	49	1.45	379	0.007	9	0.47	0.005	0.14	0.5	1.03	3.1	5.2	<0.05	2	8.4	0.3
1287362	Soil	52	1.31	438	0.008	10	0.56	0.005	0.16	0.5	0.88	3.1	4.1	<0.05	2	7.9	0.2
1287363	Soil	25	2.30	360	0.004	7	0.37	0.005	0.10	0.4	0.63	3.0	4.3	<0.05	<1	4.6	<0.2
1287364	Soil	22	2.42	431	0.004	6	0.32	0.005	0.10	0.3	0.43	3.5	4.3	<0.05	<1	4.6	<0.2
1287365	Soil	11	1.89	189	0.003	5	0.16	0.004	0.06	0.3	0.21	4.2	1.6	<0.05	<1	2.6	<0.2
1287366	Soil	9	0.54	151	0.002	3	0.15	0.002	0.04	0.2	0.26	3.9	1.1	<0.05	<1	1.3	<0.2
1287367	Soil	10	0.88	162	0.002	3	0.17	0.003	0.05	0.2	0.34	4.0	1.2	<0.05	<1	2.2	<0.2
1287368	Soil	9	0.79	149	0.002	4	0.17	0.003	0.05	0.2	0.40	3.6	1.0	<0.05	<1	2.1	<0.2
1287369	Soil	9	0.28	1260	0.002	4	0.27	0.002	0.09	0.2	0.50	4.5	0.7	<0.05	<1	4.0	<0.2
1287370	Soil	10	0.11	1064	0.002	5	0.31	0.002	0.09	<0.1	0.38	4.1	0.3	<0.05	<1	3.5	<0.2
1287391	Soil	26	0.95	1594	0.009	14	0.72	0.007	0.24	0.2	0.81	3.0	0.4	0.18	2	7.4	0.3
1287392	Soil	19	7.18	3517	0.005	7	0.58	0.019	0.06	0.5	0.74	2.1	0.4	0.16	2	6.4	0.2
1287393	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287394	Soil	11	0.02	261	0.003	2	0.44	0.011	0.08	<0.1	0.08	0.4	0.2	0.08	2	2.4	0.3
1287395	Soil	12	0.07	186	0.002	2	0.63	0.005	0.07	<0.1	0.09	1.1	0.2	0.08	3	0.7	<0.2
1287396	Soil	10	0.13	311	0.009	3	0.65	0.013	0.08	<0.1	0.15	5.2	0.2	0.07	2	1.1	<0.2
1287397	Soil	12	0.16	1097	0.005	4	0.91	0.006	0.08	<0.1	0.14	9.5	0.3	<0.05	3	0.7	<0.2
1287398	Soil	9	0.05	280	0.002	2	0.59	0.006	0.07	<0.1	0.08	1.2	0.2	0.05	2	0.7	<0.2
1287399	Soil	10	0.05	199	0.003	2	0.60	0.006	0.09	<0.1	0.06	1.3	0.1	<0.05	3	0.5	<0.2
1287400	Soil	12	0.09	1048	0.006	3	0.57	0.003	0.10	0.1	0.06	3.0	0.2	0.06	2	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001947.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1287122	Soil	9.0	48.9	30.6	189	0.4	56.5	10.3	260	4.43	139.3	3.2	0.6	62	0.4	3.9	0.4	72	0.09	0.326	14
REP 1287122	QC	9.4	48.7	31.4	194	0.4	57.2	10.2	261	4.51	140.3	4.8	0.6	63	0.3	3.8	0.4	75	0.09	0.316	14
1287136	Soil	16.1	74.5	26.3	413	1.9	112.7	16.2	191	3.73	21.9	2.3	2.4	34	3.0	4.0	0.3	24	0.09	0.113	19
REP 1287136	QC	16.5	76.9	25.7	420	2.0	117.6	16.8	189	3.76	23.5	4.1	2.6	35	3.2	4.2	0.3	26	0.08	0.117	19
1284479	Soil	12.0	54.4	14.5	195	0.8	40.2	4.7	76	1.94	32.8	3.9	1.5	62	2.2	6.0	0.2	90	0.13	0.114	7
REP 1284479	QC	11.5	54.2	14.0	196	0.7	40.6	5.1	75	2.00	31.7	7.6	1.5	63	2.0	5.8	0.2	94	0.14	0.112	7
1283337	Soil	4.3	39.2	27.8	38	1.3	30.4	4.3	118	1.08	8.9	4.0	1.0	43	0.3	2.5	0.2	36	0.15	0.035	3
REP 1283337	QC	4.0	40.2	27.2	39	1.4	31.1	4.3	122	1.08	8.3	4.4	1.0	43	0.3	2.5	0.2	34	0.14	0.035	2
1283375	Soil	31.8	250.9	363.3	2292	2.1	97.0	18.8	739	4.47	38.6	5.5	1.2	38	13.2	7.5	0.3	138	0.33	0.257	14
REP 1283375	QC	30.9	255.4	354.9	2320	2.0	99.0	18.3	746	4.59	36.8	3.2	1.2	37	12.1	7.7	0.3	137	0.31	0.264	14
1287401	Soil	51.3	99.2	92.4	564	2.9	158.5	9.5	257	3.57	81.4	5.5	5.1	103	6.9	34.8	0.3	315	0.52	0.199	13
REP 1287401	QC	49.5	97.2	93.5	566	2.9	159.0	9.5	257	3.59	82.4	4.8	5.2	102	6.6	36.2	0.3	317	0.52	0.199	14
1287367	Soil	110.2	60.7	14.8	298	0.2	217.0	12.0	189	2.52	31.1	<0.5	4.4	103	2.1	6.9	0.2	114	3.42	0.082	5
REP 1287367	QC	114.3	62.8	15.0	309	0.3	220.5	12.0	188	2.57	32.0	1.0	4.5	102	2.0	7.2	0.2	114	3.51	0.084	6
Reference Materials																					
STD DS8	Standard	13.7	109.3	120.9	289	1.7	38.2	7.6	584	2.38	23.9	108.3	6.2	59	2.0	4.5	5.2	44	0.66	0.072	16
STD DS8	Standard	14.1	125.3	133.2	335	1.9	42.9	8.7	654	2.67	28.8	136.5	6.8	73	2.5	5.9	7.0	46	0.70	0.083	15
STD DS8	Standard	15.5	118.6	128.5	311	1.9	40.8	8.3	627	2.51	26.7	109.7	7.3	73	2.3	5.8	6.8	47	0.71	0.076	17
STD DS8	Standard	13.6	106.5	116.2	310	1.8	37.8	7.3	614	2.44	24.9	112.4	6.2	60	2.2	4.8	5.7	41	0.69	0.074	16
STD DS8	Standard	11.8	112.0	124.6	306	1.7	37.8	7.4	592	2.35	24.6	118.4	6.2	70	2.0	5.0	6.5	42	0.67	0.073	13
STD DS8	Standard	10.4	110.1	123.5	303	1.8	37.7	7.4	582	2.38	25.7	116.0	6.6	65	2.3	6.1	7.6	39	0.63	0.078	11
STD DS8	Standard	11.3	108.2	117.6	305	1.6	37.0	7.1	571	2.36	25.8	121.8	5.4	62	2.2	5.4	6.2	39	0.62	0.076	11
STD DS8	Standard	12.4	113.8	122.3	305	1.8	35.8	7.6	625	2.41	23.9	108.6	6.6	69	2.4	5.3	6.2	41	0.66	0.073	14
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001947.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1287122	Soil		19	0.12	434	0.009	3	0.80	0.004	0.11	0.2	0.07	1.7	0.3	<0.05	3	3.1	0.2
REP 1287122	QC		19	0.12	449	0.009	5	0.82	0.005	0.12	0.1	0.06	1.4	0.3	<0.05	3	3.3	<0.2
1287136	Soil		9	0.03	2330	0.002	3	0.55	0.003	0.08	<0.1	0.42	3.6	0.2	<0.05	<1	1.6	<0.2
REP 1287136	QC		9	0.03	2455	0.003	3	0.58	0.003	0.09	<0.1	0.45	3.9	0.3	<0.05	<1	1.6	<0.2
1284479	Soil		18	0.05	1076	0.004	3	0.44	0.002	0.08	0.1	0.72	2.7	0.5	<0.05	1	2.1	0.2
REP 1284479	QC		19	0.05	1205	0.005	4	0.44	0.002	0.08	0.1	0.74	2.7	0.4	<0.05	1	2.1	<0.2
1283337	Soil		7	0.01	904	0.002	3	0.26	0.004	0.06	<0.1	0.73	2.5	0.6	0.06	1	1.4	<0.2
REP 1283337	QC		7	0.01	856	0.002	3	0.25	0.004	0.06	<0.1	0.66	2.6	0.6	0.05	1	1.6	<0.2
1283375	Soil		20	0.09	933	0.005	7	0.72	0.004	0.16	0.2	0.36	3.8	0.5	0.05	3	6.0	0.3
REP 1283375	QC		21	0.09	922	0.005	5	0.73	0.004	0.15	0.2	0.34	3.4	0.4	<0.05	3	4.0	<0.2
1287401	Soil		29	0.11	1052	0.007	9	0.38	0.004	0.18	0.5	2.45	5.1	3.0	0.10	2	13.9	<0.2
REP 1287401	QC		30	0.11	1052	0.007	7	0.39	0.004	0.19	0.5	2.52	5.6	2.9	0.14	1	13.0	0.4
1287367	Soil		10	0.88	162	0.002	3	0.17	0.003	0.05	0.2	0.34	4.0	1.2	<0.05	<1	2.2	<0.2
REP 1287367	QC		10	0.91	166	0.002	4	0.18	0.004	0.06	0.3	0.35	3.8	1.2	<0.05	<1	2.5	<0.2
Reference Materials																		
STD DS8	Standard		118	0.58	256	0.110	2	0.90	0.100	0.38	2.7	0.11	2.5	5.3	0.16	5	4.9	4.8
STD DS8	Standard		132	0.62	290	0.121	3	0.91	0.109	0.44	3.2	0.20	3.7	5.6	0.13	5	4.6	5.4
STD DS8	Standard		126	0.61	297	0.127	2	0.95	0.102	0.43	3.2	0.19	3.8	5.4	0.13	5	5.1	4.8
STD DS8	Standard		115	0.59	282	0.123	2	0.91	0.088	0.41	3.0	0.19	2.7	5.5	0.09	4	3.8	5.0
STD DS8	Standard		118	0.66	254	0.108	2	0.91	0.099	0.42	2.7	0.20	2.4	5.5	0.15	5	2.8	4.8
STD DS8	Standard		113	0.59	252	0.112	2	0.83	0.081	0.40	2.9	0.18	2.1	5.3	0.14	4	4.4	5.0
STD DS8	Standard		110	0.58	251	0.109	3	0.85	0.092	0.39	2.8	0.19	1.7	5.3	0.10	4	5.4	4.7
STD DS8	Standard		114	0.58	283	0.119	2	0.97	0.115	0.46	2.8	0.19	2.8	5.3	0.12	5	5.1	4.9
STD DS8 Expected			115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank		<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank		<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank		<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank		<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001947.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 02, 2011

QUALITY CONTROL REPORT WHI11001947.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 21, 2011
Report Date: December 05, 2011
Page: 1 of 9

CERTIFICATE OF ANALYSIS WHI11001948.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #29
P.O. Number
Number of Samples:

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	215	Sieve soil to 230 mesh			VAN
RJSV	215	Saving all or part of Soil Reject			VAN
1DX2	215	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1289036	Soil	7.2	49.0	20.9	118	0.3	26.6	6.4	159	2.38	14.3	3.2	0.4	25	0.5	3.1	0.3	69	0.03	0.137	8
1289037	Soil	1.6	60.6	6.1	89	0.5	20.9	4.7	122	1.74	4.8	2.4	0.2	6	0.3	1.5	0.2	35	0.02	0.040	5
1289038	Soil	1.0	24.5	3.0	51	0.2	9.1	2.2	129	0.79	2.2	2.1	<0.1	8	0.3	0.7	<0.1	16	0.07	0.050	2
1289039	Soil	3.0	70.5	12.9	140	0.4	21.0	5.5	448	1.78	6.5	5.1	<0.1	24	0.6	1.8	0.2	31	0.19	0.085	3
1289040	Soil	8.4	459.4	18.4	779	0.5	83.5	15.2	279	8.39	153.5	41.3	1.1	14	1.7	12.2	0.5	75	0.06	0.125	10
1287681	Soil	3.2	38.7	8.5	84	1.0	33.5	4.7	237	2.75	53.4	7.6	0.2	16	0.2	5.1	0.2	51	0.03	0.099	4
1287682	Soil	1.1	22.1	6.1	32	1.4	7.8	4.0	204	1.20	6.7	2.4	0.1	9	0.3	1.2	<0.1	17	0.06	0.061	2
1287683	Soil	6.4	77.9	33.3	217	1.4	56.7	25.9	875	4.95	38.1	5.6	1.3	26	1.1	6.7	0.4	80	0.14	0.127	5
1287684	Soil	5.3	51.6	19.2	120	1.0	38.2	10.9	449	3.38	26.6	4.3	0.4	21	0.6	5.0	0.3	55	0.07	0.117	3
1287685	Soil	8.5	82.9	36.3	207	1.0	56.8	29.2	820	5.78	35.6	6.1	1.7	24	0.5	7.5	0.4	69	0.02	0.125	4
1287686	Soil	5.6	94.8	31.6	194	1.9	78.5	17.3	704	5.84	36.3	8.4	2.8	44	0.8	7.1	0.4	74	0.19	0.100	4
1287687	Soil	1.9	27.2	13.0	52	0.3	16.3	6.0	388	1.84	8.7	1.8	0.3	10	0.2	1.8	0.2	27	0.04	0.083	2
1287688	Soil	4.3	59.7	41.8	121	0.5	29.7	22.2	1425	5.49	18.0	3.1	1.4	17	0.3	3.0	0.5	68	0.04	0.197	5
1287689	Soil	2.8	28.6	17.7	55	0.5	12.2	6.0	425	2.24	8.3	2.3	0.4	11	0.2	1.7	0.2	51	0.03	0.087	3
1287690	Soil	2.9	35.3	20.2	76	0.6	16.8	6.5	319	2.28	8.7	3.2	0.5	12	0.4	2.0	0.3	41	0.02	0.133	4
1288471	Soil	11.6	75.3	24.2	303	0.3	60.1	14.4	590	4.99	25.4	2.1	1.1	19	2.7	4.8	0.5	55	0.02	0.086	6
1288472	Soil	10.7	53.8	13.6	323	0.3	57.3	15.4	761	3.65	19.4	6.3	0.6	9	0.8	5.3	0.3	42	0.01	0.057	5
1288473	Soil	8.9	237.3	53.4	629	2.1	124.8	25.9	524	8.84	42.4	23.3	1.2	46	2.2	9.1	0.7	102	0.04	0.148	7
1288474	Soil	73.2	208.1	14.6	1839	1.8	187.2	5.3	94	2.34	70.4	2.6	1.9	70	27.9	51.7	0.3	363	0.75	0.089	29
1288475	Soil	22.1	76.0	15.0	389	0.7	80.3	9.6	140	2.90	20.4	4.9	1.2	38	1.7	9.4	0.3	133	0.45	0.076	13
1288476	Soil	7.9	32.0	7.2	155	0.2	25.2	4.6	67	1.43	8.7	1.6	0.2	11	0.5	3.1	0.1	65	0.03	0.061	7
1288477	Soil	13.8	105.0	26.3	354	1.2	58.4	12.7	182	4.11	21.5	12.0	2.2	57	1.3	6.0	0.3	77	0.05	0.158	14
1288478	Soil	12.4	146.5	32.1	342	0.4	60.3	17.0	346	5.30	24.4	11.7	1.7	78	0.8	5.8	0.4	75	0.20	0.243	12
1288479	Soil	10.1	81.0	25.4	181	0.7	33.0	9.6	235	4.92	21.9	10.4	1.2	54	0.5	4.5	0.3	106	0.13	0.214	14
1288480	Soil	9.2	239.0	26.2	433	0.9	61.2	19.5	694	5.10	22.7	45.4	3.4	137	4.5	6.3	0.3	81	0.18	0.232	16
1289071	Soil	10.1	30.1	21.2	130	0.1	38.0	7.3	120	3.09	25.4	0.8	0.3	14	0.1	3.6	0.3	73	0.03	0.049	16
1289072	Soil	15.4	60.2	40.8	206	1.0	76.7	22.4	559	5.05	26.6	4.7	1.7	11	0.2	4.5	0.4	23	0.11	0.067	16
1289073	Soil	10.9	68.5	28.3	140	0.4	63.4	14.5	282	3.68	59.9	6.2	3.1	34	0.2	5.1	0.4	26	0.06	0.061	28
1289074	Soil	1.1	9.3	17.9	34	0.1	8.3	0.7	14	0.60	5.2	2.4	0.8	15	0.1	1.4	0.1	12	0.01	0.017	7
1289075	Soil	3.7	54.1	30.1	118	0.2	56.4	6.8	87	2.48	17.1	6.7	0.8	12	0.4	2.9	0.2	31	0.09	0.119	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1289036	Soil	15	0.07	232	0.006	5	0.72	0.011	0.08	<0.1	0.08	0.5	0.2	0.06	4	1.9	<0.2
1289037	Soil	9	0.03	112	0.011	3	0.56	0.020	0.05	<0.1	0.06	0.8	<0.1	<0.05	3	0.7	<0.2
1289038	Soil	5	0.02	57	0.004	2	0.21	0.025	0.03	<0.1	0.03	0.4	<0.1	<0.05	1	<0.5	<0.2
1289039	Soil	11	0.05	311	0.008	3	0.39	0.014	0.06	<0.1	0.21	1.2	0.1	0.12	2	1.7	<0.2
1289040	Soil	20	0.08	136	0.007	3	0.65	0.004	0.10	<0.1	0.12	3.7	0.2	<0.05	4	6.5	0.3
1287681	Soil	13	0.04	163	0.006	3	0.64	0.020	0.04	<0.1	0.17	0.6	0.3	0.08	3	2.3	<0.2
1287682	Soil	6	0.03	122	0.009	1	0.87	0.028	0.02	<0.1	0.11	0.8	<0.1	0.06	2	1.3	<0.2
1287683	Soil	23	0.11	625	0.005	3	1.00	0.013	0.10	<0.1	0.12	3.2	0.4	0.08	3	3.7	0.2
1287684	Soil	15	0.07	234	0.005	2	0.85	0.019	0.05	<0.1	0.11	1.1	0.3	0.09	3	3.0	<0.2
1287685	Soil	18	0.09	230	0.004	2	0.87	0.011	0.09	<0.1	0.09	3.9	0.4	<0.05	3	3.6	<0.2
1287686	Soil	24	0.19	734	0.004	3	0.76	0.005	0.10	<0.1	0.35	7.3	0.3	0.06	2	3.6	<0.2
1287687	Soil	12	0.06	100	0.007	2	0.81	0.023	0.05	<0.1	0.09	0.6	0.1	0.07	3	1.3	<0.2
1287688	Soil	35	0.20	849	0.006	2	1.31	0.006	0.10	<0.1	0.11	2.0	0.2	0.06	7	1.8	<0.2
1287689	Soil	14	0.05	118	0.005	2	0.82	0.022	0.05	<0.1	0.07	0.6	0.1	0.05	4	1.3	<0.2
1287690	Soil	15	0.05	214	0.004	3	0.73	0.018	0.06	<0.1	0.11	0.6	0.2	0.08	3	1.7	<0.2
1288471	Soil	13	0.06	510	0.003	6	0.74	0.003	0.16	<0.1	0.16	3.2	0.2	0.05	3	2.5	0.2
1288472	Soil	9	0.04	187	0.008	3	0.54	0.013	0.08	<0.1	0.08	1.9	0.2	<0.05	2	1.6	<0.2
1288473	Soil	34	0.11	190	0.008	4	0.93	0.007	0.13	<0.1	0.25	11.7	0.5	0.08	4	5.7	0.2
1288474	Soil	19	0.17	1069	0.003	7	0.51	0.004	0.12	0.1	3.60	4.1	0.7	0.07	2	8.9	<0.2
1288475	Soil	17	0.14	1035	0.005	5	0.55	0.005	0.12	0.1	0.30	2.5	0.4	0.07	3	4.5	<0.2
1288476	Soil	9	0.04	297	0.005	3	0.49	0.021	0.06	<0.1	0.10	0.5	0.2	<0.05	2	1.3	<0.2
1288477	Soil	15	0.11	342	0.004	3	0.89	0.004	0.12	<0.1	0.37	3.7	0.3	0.07	2	3.9	<0.2
1288478	Soil	18	0.26	435	0.007	6	1.04	0.005	0.20	<0.1	0.15	2.6	0.3	0.09	3	4.2	<0.2
1288479	Soil	27	0.37	306	0.011	5	1.40	0.004	0.17	<0.1	0.16	1.8	0.4	0.09	5	3.5	<0.2
1288480	Soil	19	0.14	421	0.006	6	1.02	0.004	0.30	<0.1	0.20	5.1	0.4	0.16	3	5.9	0.2
1289071	Soil	14	0.08	205	0.011	2	0.78	0.007	0.06	0.1	0.03	0.9	0.2	<0.05	5	1.6	<0.2
1289072	Soil	8	0.08	474	0.002	4	0.51	0.003	0.12	<0.1	0.20	3.3	0.3	<0.05	1	1.4	<0.2
1289073	Soil	7	0.04	368	0.001	2	0.36	0.002	0.08	<0.1	0.16	4.1	0.2	<0.05	1	2.8	<0.2
1289074	Soil	8	0.02	109	0.005	4	0.18	0.003	0.08	<0.1	0.02	0.4	0.2	0.07	<1	1.9	<0.2
1289075	Soil	13	0.03	164	0.002	2	0.31	0.005	0.06	<0.1	0.06	1.6	0.1	<0.05	1	1.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1289076	Soil	5.3	102.1	16.5	233	0.3	48.2	11.1	260	2.73	12.8	3.9	1.0	17	0.9	2.3	0.2	25	0.56	0.100	5
1289077	Soil	10.5	42.8	18.2	236	0.5	53.0	8.5	189	2.40	21.6	2.6	0.8	40	1.9	4.2	0.2	61	0.64	0.147	12
1289078	Soil	5.5	34.5	13.2	131	1.0	31.2	4.1	109	1.29	11.5	3.0	0.5	32	1.1	2.1	0.1	36	0.23	0.166	9
1289079	Soil	7.8	203.9	36.7	288	0.6	63.6	16.4	176	3.93	18.9	11.8	1.3	7	1.4	4.0	0.3	31	0.08	0.110	14
1289080	Soil	5.6	94.0	13.3	103	0.2	36.3	9.7	71	2.31	14.7	2.5	0.7	3	0.1	2.6	0.2	47	0.01	0.045	14
1289081	Soil	5.0	160.2	16.0	76	0.5	48.6	10.9	99	2.72	13.4	8.8	1.3	14	0.5	2.3	0.2	17	0.48	0.064	13
1289082	Soil	3.4	50.8	9.2	106	1.3	57.5	7.8	169	2.21	16.2	5.1	0.4	45	0.2	4.2	0.2	22	0.44	0.125	4
1289083	Soil	15.6	79.1	40.9	641	1.3	57.7	7.0	191	3.17	47.2	7.3	0.8	31	7.2	11.2	0.2	62	0.41	0.139	6
1289084	Soil	32.8	181.8	60.2	263	4.0	87.0	6.3	85	2.83	64.0	8.2	0.9	517	3.7	14.9	0.5	258	0.40	0.324	24
1289085	Soil	9.2	22.9	12.8	81	0.2	29.0	4.9	53	1.23	14.0	0.8	0.2	15	0.1	2.6	0.2	66	0.01	0.045	7
1289086	Soil	8.3	24.9	33.9	120	0.3	37.5	5.2	57	1.61	16.3	2.0	0.4	28	0.1	2.4	0.4	72	0.01	0.048	12
1289087	Soil	4.5	22.1	6.5	42	0.3	25.7	6.5	143	2.07	8.9	1.4	0.3	5	<0.1	1.4	0.2	38	0.01	0.045	13
1289088	Soil	3.5	62.8	22.4	70	0.2	59.2	21.6	399	5.31	23.2	3.5	1.2	5	<0.1	4.2	0.4	24	<0.01	0.079	8
1289089	Soil	6.8	70.9	42.2	201	0.3	79.7	14.7	223	3.81	35.7	3.6	2.7	99	0.2	4.0	0.5	58	0.49	0.382	17
1289090	Soil	1.9	40.4	9.0	25	0.4	31.3	10.4	115	3.77	32.7	3.3	0.7	12	<0.1	1.9	0.3	15	0.06	0.050	10
1287651	Soil	17.6	12.6	7.3	101	1.5	21.6	2.2	29	0.92	13.7	<0.5	0.3	15	0.4	3.4	0.1	116	0.01	0.027	16
1287652	Soil	14.3	22.6	10.6	153	0.2	37.4	4.4	98	1.61	21.2	2.4	1.0	17	0.8	2.7	0.1	106	0.07	0.062	12
1287653	Soil	12.3	28.0	10.2	378	1.0	78.5	3.4	111	1.44	18.1	4.8	0.3	28	2.2	2.8	0.2	116	0.25	0.082	7
1287654	Soil	19.5	39.9	14.7	286	0.4	60.3	7.9	289	2.29	32.2	5.4	1.1	31	2.0	4.1	0.2	138	0.22	0.094	15
1287655	Soil	21.9	36.8	15.4	266	0.7	56.8	8.1	291	2.41	33.3	6.3	1.5	32	2.0	4.6	0.2	131	0.21	0.104	15
1287656	Soil	19.8	32.4	15.3	263	0.7	51.1	9.5	485	2.40	28.8	2.8	1.5	29	1.8	3.9	0.2	118	0.17	0.113	12
1287657	Soil	4.3	25.3	9.0	132	0.6	24.9	2.3	77	0.98	10.4	4.6	0.9	28	2.1	1.5	0.1	79	0.20	0.117	12
1287658	Soil	16.3	24.1	16.8	198	0.3	41.7	6.2	195	2.94	42.3	2.0	1.4	16	0.6	3.6	0.3	123	0.03	0.077	12
1287659	Soil	13.7	22.1	11.0	167	0.5	39.6	6.2	153	2.18	32.1	3.0	1.9	14	0.4	3.0	0.2	78	0.04	0.058	17
1287660	Soil	3.4	14.7	10.6	79	0.2	15.7	3.8	72	1.93	16.2	2.3	0.9	16	0.3	1.1	0.2	41	0.04	0.064	5
1287661	Soil	5.8	38.0	15.3	180	0.4	39.9	9.1	135	2.99	19.6	3.7	1.5	26	0.9	2.0	0.2	43	0.05	0.074	6
1287662	Soil	6.3	45.4	12.6	165	0.4	41.2	10.3	214	2.35	16.4	4.3	1.5	40	1.1	1.8	0.2	47	0.19	0.071	6
1287663	Soil	2.2	13.4	5.5	65	0.6	22.5	4.8	196	1.11	6.2	3.5	0.4	36	0.5	0.8	0.1	28	0.27	0.042	2
1287664	Soil	1.4	12.5	4.4	47	0.3	17.6	2.9	64	0.56	2.7	1.5	0.1	34	1.5	0.6	<0.1	15	0.31	0.042	2
1287665	Soil	0.6	10.7	4.5	21	0.4	7.0	1.0	17	0.31	1.8	1.9	0.3	14	0.3	0.4	<0.1	9	0.06	0.025	3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1289076	Soil	9	0.13	300	0.003	3	0.38	0.014	0.07	<0.1	0.08	2.5	0.1	<0.05	2	3.8	<0.2
1289077	Soil	17	0.15	916	0.006	3	0.57	0.009	0.07	0.1	0.08	1.8	0.2	0.05	2	1.8	<0.2
1289078	Soil	9	0.06	681	0.004	3	0.45	0.023	0.06	<0.1	0.18	0.9	0.2	<0.05	1	1.3	<0.2
1289079	Soil	9	0.05	146	0.002	3	0.50	0.004	0.09	<0.1	0.26	3.5	0.2	<0.05	2	2.4	<0.2
1289080	Soil	7	0.04	97	0.003	3	0.48	0.006	0.08	<0.1	0.03	1.2	0.1	<0.05	3	1.3	<0.2
1289081	Soil	7	0.11	327	0.002	4	0.36	0.013	0.09	<0.1	0.13	3.2	0.1	<0.05	1	1.9	<0.2
1289082	Soil	6	0.06	1171	0.003	2	0.39	0.015	0.04	<0.1	0.26	1.8	0.1	<0.05	2	1.6	<0.2
1289083	Soil	10	0.09	418	0.002	4	0.36	0.005	0.06	<0.1	1.40	2.6	0.4	<0.05	1	2.5	<0.2
1289084	Soil	31	0.05	887	0.004	2	0.63	0.006	0.16	0.4	0.73	2.7	1.4	0.30	2	7.1	0.4
1289085	Soil	8	0.02	72	0.003	2	0.24	0.008	0.05	0.1	0.04	0.3	0.2	0.06	2	1.3	<0.2
1289086	Soil	11	0.03	121	0.006	2	0.44	0.003	0.06	0.1	0.03	0.6	0.2	<0.05	4	1.9	<0.2
1289087	Soil	7	0.03	72	0.004	1	0.32	0.009	0.04	0.1	0.03	0.6	0.1	<0.05	2	0.7	<0.2
1289088	Soil	9	0.05	119	0.003	2	0.53	0.004	0.09	0.1	0.22	2.8	0.3	<0.05	2	1.6	<0.2
1289089	Soil	21	0.06	422	0.005	7	0.67	0.003	0.15	<0.1	0.10	3.1	0.2	<0.05	2	1.5	<0.2
1289090	Soil	6	0.04	449	0.004	1	0.50	0.014	0.06	<0.1	0.09	2.2	0.1	<0.05	2	0.7	<0.2
1287651	Soil	7	0.03	129	0.004	1	0.32	0.004	0.06	0.2	0.05	0.4	1.4	0.06	3	1.4	<0.2
1287652	Soil	14	0.08	507	0.002	2	0.78	0.006	0.07	0.2	0.08	1.0	0.4	<0.05	3	0.8	<0.2
1287653	Soil	20	0.14	903	0.003	4	0.98	0.017	0.09	0.2	0.29	1.1	0.5	<0.05	3	1.2	<0.2
1287654	Soil	20	0.15	1069	0.003	3	0.92	0.005	0.09	0.2	0.25	1.7	0.4	<0.05	3	1.7	<0.2
1287655	Soil	20	0.15	935	0.003	3	0.98	0.005	0.11	0.2	0.36	2.2	0.5	<0.05	3	1.9	<0.2
1287656	Soil	19	0.14	839	0.002	2	0.94	0.005	0.08	0.2	0.31	1.9	0.4	<0.05	3	1.5	<0.2
1287657	Soil	16	0.10	888	0.002	2	0.89	0.006	0.07	0.1	0.43	1.5	0.4	<0.05	2	0.7	<0.2
1287658	Soil	16	0.10	291	0.005	3	0.96	0.004	0.08	0.2	0.07	1.4	0.4	<0.05	4	1.9	<0.2
1287659	Soil	14	0.09	357	0.003	3	0.86	0.003	0.08	0.2	0.12	1.2	0.3	<0.05	3	0.8	<0.2
1287660	Soil	10	0.07	900	0.001	<1	0.67	0.003	0.04	<0.1	0.06	1.2	0.2	<0.05	3	1.1	<0.2
1287661	Soil	14	0.12	1539	0.001	2	0.66	0.003	0.05	<0.1	0.12	2.8	0.2	0.06	2	1.5	<0.2
1287662	Soil	14	0.15	1992	0.002	3	0.77	0.007	0.06	<0.1	0.13	2.5	0.2	<0.05	2	1.9	<0.2
1287663	Soil	7	0.06	1162	0.002	2	0.62	0.024	0.05	<0.1	0.13	1.4	0.2	<0.05	2	0.8	<0.2
1287664	Soil	7	0.04	1157	0.003	1	0.38	0.017	0.03	<0.1	0.13	0.7	<0.1	0.12	<1	<0.5	<0.2
1287665	Soil	6	0.06	382	0.003	<1	0.30	0.014	0.03	<0.1	0.15	0.7	0.1	<0.05	<1	1.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1287666	Soil	1.2	12.0	2.5	33	0.2	10.7	1.7	70	0.69	3.8	2.2	0.1	24	0.6	0.4	<0.1	13	0.22	0.029	2
1287667	Soil	2.3	54.0	14.1	148	0.4	55.3	8.8	114	1.85	14.5	4.2	1.5	50	2.2	1.0	0.2	34	0.37	0.067	4
1287668	Soil	0.8	19.8	2.4	86	0.2	28.3	4.2	112	0.67	1.6	0.5	0.2	151	1.6	0.8	<0.1	8	2.27	0.039	1
1287669	Soil	1.0	28.0	10.6	83	0.7	17.7	3.3	53	1.44	9.8	4.1	1.1	44	2.1	0.9	0.1	35	0.40	0.075	4
1287670	Soil	4.0	32.3	8.2	97	0.9	33.4	6.6	184	2.61	20.1	5.7	0.9	70	1.4	1.3	0.1	33	0.77	0.077	3
1287691	Soil	4.9	53.1	16.1	197	2.1	51.4	7.6	254	2.03	51.8	16.1	1.2	64	1.7	7.1	0.3	53	0.83	0.087	7
1287692	Soil	5.9	54.6	20.3	223	1.6	47.9	7.2	195	2.43	77.9	23.7	1.7	62	1.5	9.0	0.3	62	0.51	0.104	9
1287693	Soil	75.7	68.1	13.1	614	1.0	219.7	12.6	234	3.07	56.2	3.7	2.1	30	4.8	11.1	0.2	73	0.40	0.092	15
1287694	Soil	101.8	66.4	13.2	557	1.6	248.7	12.7	214	3.06	59.2	3.5	2.7	21	5.0	12.7	0.2	67	0.30	0.074	17
1287695	Soil	64.0	90.2	10.7	616	2.0	190.6	8.8	241	2.44	44.4	1.3	1.5	42	10.8	12.0	0.1	258	0.73	0.125	12
1287696	Soil	9.3	26.8	12.5	98	1.0	29.9	2.8	84	1.03	39.6	11.3	0.8	64	2.4	8.7	0.2	77	1.09	0.069	5
1287697	Soil	36.6	43.4	46.7	197	1.8	48.0	4.9	97	2.32	169.9	23.7	2.1	103	1.6	37.7	0.3	187	0.20	0.119	15
1287698	Soil	61.5	268.5	16.1	675	1.9	167.5	8.6	205	2.39	69.1	2.3	2.4	34	12.7	19.5	0.3	290	0.18	0.124	11
1287699	Soil	67.0	176.4	13.9	815	1.8	189.5	7.7	194	2.37	62.2	2.6	1.4	29	20.5	20.2	0.2	265	0.19	0.109	12
1287700	Soil	67.6	66.1	17.1	1740	1.7	231.8	11.1	454	3.38	96.2	9.4	2.7	35	43.7	24.0	0.2	198	0.23	0.114	18
1288761	Soil	30.6	63.0	18.2	2531	1.2	263.7	17.0	448	2.16	23.9	3.3	1.4	136	12.1	7.0	0.2	191	3.56	0.091	6
1288762	Soil	24.9	62.0	16.4	1336	1.0	166.2	10.0	219	2.22	21.3	2.6	1.5	99	7.7	5.3	0.2	160	0.89	0.120	8
1288763	Soil	2.7	30.0	12.8	56	1.6	18.8	2.8	57	1.26	9.1	2.0	0.3	32	0.7	0.8	0.2	34	0.13	0.109	4
1288764	Soil	2.6	14.7	9.8	49	0.4	8.6	2.1	39	1.37	11.1	0.6	0.2	9	0.2	0.8	0.2	44	0.02	0.067	4
1288765	Soil	5.5	35.9	16.1	170	0.5	35.6	6.5	100	3.06	22.8	4.0	1.9	24	0.5	2.1	0.2	49	0.03	0.069	7
1288766	Soil	4.7	27.1	18.3	158	0.5	31.4	7.2	125	3.99	30.8	2.0	2.2	19	0.5	2.0	0.3	62	0.02	0.171	6
1288767	Soil	3.3	26.1	16.3	102	0.7	29.7	8.4	148	3.09	28.2	4.1	1.9	18	0.7	1.6	0.3	47	0.08	0.074	10
1288768	Soil	3.6	24.7	13.7	116	0.4	28.3	7.5	160	2.69	29.5	3.2	2.4	37	0.7	2.4	0.3	44	0.16	0.090	12
1288769	Soil	5.5	24.5	14.3	103	0.3	28.6	7.1	167	2.64	29.9	1.9	1.8	28	0.5	1.9	0.3	60	0.20	0.057	11
1288770	Soil	3.4	47.3	15.5	99	0.8	35.6	6.2	106	2.62	14.5	2.8	1.9	39	0.8	1.0	0.3	39	0.16	0.088	6
1288771	Soil	1.7	22.9	15.5	112	1.0	27.2	9.7	232	2.08	13.6	3.1	1.6	46	0.7	0.9	0.3	36	0.35	0.069	6
1288772	Soil	1.4	24.7	2.3	26	0.5	26.4	4.8	226	1.85	8.6	2.1	0.3	58	1.8	0.9	<0.1	10	0.61	0.081	2
1288773	Soil	4.0	27.8	15.9	132	0.5	35.2	12.0	657	2.70	20.1	2.0	2.1	60	0.7	1.3	0.2	45	0.40	0.078	5
1288774	Soil	1.0	37.0	3.8	69	1.8	51.1	7.8	86	1.18	8.0	4.5	0.3	57	7.2	1.4	<0.1	14	0.50	0.095	5
1288775	Soil	15.4	129.2	7.8	218	0.3	532.3	116.5	1453	9.80	317.0	<0.5	5.5	166	1.6	7.1	<0.1	137	2.69	0.319	42

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287666	Soil		4	0.03	309	0.002	1	0.23	0.016	0.03	<0.1	0.05	0.5	<0.1	<0.05	<1	<0.5	<0.2
1287667	Soil		13	0.13	1095	<0.001	2	0.84	0.005	0.05	<0.1	0.19	2.8	0.4	0.09	2	2.1	<0.2
1287668	Soil		5	0.12	282	0.003	3	0.38	0.009	0.01	0.1	0.14	0.9	<0.1	0.26	<1	2.1	<0.2
1287669	Soil		12	0.11	798	0.001	2	0.77	0.007	0.04	0.2	0.29	2.8	0.2	0.15	2	2.6	<0.2
1287670	Soil		10	0.13	995	0.001	2	0.84	0.016	0.06	0.1	0.31	2.5	0.2	0.12	2	1.3	<0.2
1287691	Soil		20	0.15	876	0.002	4	0.71	0.008	0.07	4.9	2.31	2.3	0.4	0.06	2	2.9	<0.2
1287692	Soil		26	0.16	1212	0.002	4	0.81	0.005	0.09	0.5	4.82	2.9	0.5	0.08	2	3.8	<0.2
1287693	Soil		17	0.10	984	0.002	5	0.38	0.003	0.06	0.8	0.99	3.3	1.1	<0.05	1	3.1	<0.2
1287694	Soil		34	0.07	788	0.002	4	0.27	0.002	0.06	1.8	1.00	3.5	1.3	<0.05	<1	2.0	<0.2
1287695	Soil		25	0.12	1257	0.003	4	0.64	0.004	0.08	1.9	1.40	3.8	1.6	0.06	2	3.6	<0.2
1287696	Soil		14	0.07	588	0.003	3	0.62	0.018	0.06	1.1	1.07	1.4	0.5	0.09	2	2.9	<0.2
1287697	Soil		24	0.07	743	0.002	4	0.65	0.005	0.11	2.1	4.67	1.9	1.9	0.12	2	8.4	<0.2
1287698	Soil		23	0.06	500	0.005	3	1.51	0.004	0.07	0.8	1.17	3.0	3.3	<0.05	2	4.8	<0.2
1287699	Soil		23	0.06	602	0.005	4	1.18	0.005	0.07	0.7	1.39	3.1	3.3	<0.05	2	5.2	<0.2
1287700	Soil		27	0.08	956	0.002	3	0.74	0.002	0.07	0.9	1.96	3.9	1.9	<0.05	1	3.9	<0.2
1288761	Soil		18	0.53	692	0.002	5	0.49	0.005	0.06	0.1	0.36	3.6	1.3	0.11	1	3.9	<0.2
1288762	Soil		20	0.08	884	0.002	4	0.57	0.004	0.06	0.1	0.35	4.5	0.7	<0.05	1	2.3	<0.2
1288763	Soil		10	0.06	529	0.003	<1	0.84	0.016	0.06	<0.1	0.17	0.9	0.3	<0.05	2	1.3	<0.2
1288764	Soil		7	0.03	177	0.005	<1	0.45	0.008	0.03	0.1	0.03	0.7	0.1	<0.05	3	1.0	<0.2
1288765	Soil		16	0.13	1171	0.003	1	0.96	0.002	0.04	<0.1	0.09	2.4	0.2	<0.05	3	2.1	<0.2
1288766	Soil		21	0.15	270	0.004	1	1.25	0.004	0.05	0.1	0.06	2.3	0.2	<0.05	4	2.1	<0.2
1288767	Soil		18	0.16	739	0.006	1	1.35	0.007	0.06	0.2	0.08	2.0	0.2	<0.05	4	1.8	<0.2
1288768	Soil		17	0.22	1069	0.009	<1	1.00	0.007	0.07	0.3	0.06	2.1	0.2	<0.05	3	2.0	<0.2
1288769	Soil		19	0.23	702	0.009	1	1.07	0.007	0.07	0.2	0.06	2.0	0.2	<0.05	4	2.0	<0.2
1288770	Soil		17	0.15	1604	0.002	1	1.25	0.006	0.07	<0.1	0.22	3.1	0.5	0.06	3	1.8	<0.2
1288771	Soil		16	0.17	1228	0.003	1	0.99	0.011	0.07	0.2	0.23	3.0	0.3	0.07	3	2.2	<0.2
1288772	Soil		4	0.06	925	0.008	2	0.40	0.024	0.02	<0.1	0.20	1.7	<0.1	0.11	<1	1.9	<0.2
1288773	Soil		17	0.19	1801	0.002	1	0.87	0.006	0.07	<0.1	0.19	3.3	0.2	<0.05	2	1.5	<0.2
1288774	Soil		6	0.07	2383	0.006	1	0.56	0.021	0.03	<0.1	0.55	3.5	0.1	0.14	<1	3.0	<0.2
1288775	Soil		117	0.90	410	0.012	10	1.09	0.005	0.16	<0.1	0.09	19.8	0.4	0.41	3	1.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1288776	Soil		11.1	116.3	6.7	144	0.2	516.1	117.6	1248	9.25	332.5	1.4	4.5	198	0.8	6.8	<0.1	100	4.48	0.314	35
1288777	Soil		16.4	133.3	8.2	246	0.2	502.7	124.5	1648	11.80	74.2	2.7	2.0	141	1.0	3.4	<0.1	89	2.69	0.242	31
1288778	Soil		4.9	152.3	13.5	277	0.2	604.2	140.6	1322	12.66	34.9	2.7	5.6	43	1.2	3.9	<0.1	77	1.23	0.299	55
1288779	Soil		3.5	75.2	10.6	93	0.2	205.1	57.9	1684	6.61	108.8	3.2	1.2	55	0.3	2.0	<0.1	100	1.83	0.159	35
1288780	Soil		2.8	139.6	10.4	157	0.3	354.2	90.4	943	8.26	294.8	5.2	2.2	87	0.6	4.2	<0.1	116	3.24	0.314	37
1288791	Soil		47.4	32.5	7.8	191	<0.1	97.6	5.8	95	1.39	16.8	0.9	0.3	14	1.8	2.7	<0.1	82	0.28	0.070	9
1288792	Soil		44.5	44.6	12.0	531	0.4	160.3	11.4	348	2.36	19.5	<0.5	1.0	39	5.2	5.7	0.1	116	0.73	0.124	16
1288793	Soil		21.4	37.4	13.0	275	0.3	69.3	7.2	87	2.17	18.6	<0.5	0.3	6	0.6	4.6	0.1	101	0.02	0.107	8
1288794	Soil		13.8	52.9	21.0	224	0.9	68.7	10.4	151	3.38	20.2	2.6	0.8	20	0.7	3.5	0.2	59	0.03	0.162	13
1288795	Soil		6.8	76.2	21.0	283	1.9	72.9	11.2	127	3.61	16.1	3.2	1.3	48	0.5	2.2	0.3	24	0.06	0.154	15
1288796	Soil		6.6	70.7	40.8	207	1.7	70.4	12.8	143	4.35	25.0	3.4	0.8	62	0.4	3.2	0.3	31	0.05	0.176	14
1288797	Soil		7.8	24.5	12.7	97	0.4	29.2	4.7	49	1.45	11.5	1.1	0.2	25	0.3	1.7	0.1	34	0.08	0.135	7
1288798	Soil		8.0	20.6	10.8	83	0.3	27.1	3.8	48	1.23	10.7	1.5	0.3	14	0.2	1.7	0.1	44	0.02	0.083	8
1288799	Soil		12.9	28.2	17.2	113	0.7	36.7	5.7	93	1.79	17.1	1.4	0.2	28	0.5	2.3	0.2	53	0.09	0.099	12
1288800	Soil		13.0	118.4	39.4	1137	1.6	82.3	12.4	381	3.81	33.4	8.4	1.5	17	7.3	4.6	0.2	40	0.47	0.245	15
1287461	Soil		19.3	77.3	19.7	371	1.3	73.5	7.9	207	2.89	52.7	10.0	1.7	105	4.3	12.2	0.3	175	0.38	0.212	7
1287462	Soil		21.2	80.8	19.7	438	1.4	83.7	8.2	249	3.11	54.8	10.2	2.0	100	4.3	13.2	0.3	169	0.39	0.221	8
1287463	Soil		16.0	71.6	17.9	236	1.0	49.4	9.8	242	2.33	42.3	6.6	2.0	88	2.9	9.4	0.2	137	0.23	0.194	7
1287464	Soil		15.1	65.6	17.4	273	1.0	59.7	6.8	169	2.33	39.6	7.3	1.4	91	2.8	9.4	0.2	127	0.30	0.181	7
1287465	Soil		15.3	63.9	19.3	203	0.7	45.3	7.2	224	2.55	46.1	10.4	1.8	77	1.4	8.9	0.2	126	0.16	0.196	7
1287466	Soil		20.3	82.9	20.0	456	1.2	89.4	9.7	306	3.11	52.8	7.2	2.5	112	4.8	11.7	0.3	172	0.41	0.240	7
1287467	Soil		15.2	69.9	17.5	325	1.1	75.4	6.5	151	2.31	41.3	6.0	2.2	104	3.7	9.4	0.2	128	0.42	0.180	5
1287468	Soil		12.5	64.1	15.7	272	1.2	58.5	5.3	120	1.98	34.0	4.6	2.1	96	3.3	8.2	0.2	113	0.44	0.160	5
1287469	Soil		13.7	75.5	16.4	356	1.6	67.1	5.8	140	2.31	38.7	9.0	2.1	101	3.6	9.3	0.2	132	0.46	0.168	6
1287470	Soil		18.5	98.8	18.6	520	2.2	84.0	7.7	177	3.11	51.1	10.5	2.3	106	3.9	12.6	0.2	166	0.55	0.206	7
1274441	Soil		64.2	65.8	31.0	1092	1.8	280.2	13.6	1048	4.07	242.8	24.3	1.9	77	14.9	52.9	0.4	174	0.72	0.189	10
1274442	Soil		18.0	45.8	19.9	250	1.2	53.3	6.9	150	1.93	74.7	10.5	1.6	47	2.3	9.6	0.2	96	0.23	0.102	9
1274443	Soil		12.7	64.5	25.1	334	1.7	72.6	13.7	419	2.20	90.9	10.1	2.2	59	3.8	10.4	0.3	143	0.25	0.131	11
1274444	Soil		11.9	60.3	25.3	281	1.3	60.7	8.5	216	2.24	110.0	13.2	2.6	60	3.5	10.7	0.3	120	0.25	0.123	10
1274445	Soil		13.7	58.9	21.9	338	0.9	67.5	10.5	235	2.59	99.0	8.9	2.9	54	4.3	11.3	0.3	87	0.28	0.114	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288776	Soil	118	1.09	276	0.005	6	1.10	0.005	0.14	<0.1	0.10	17.0	0.3	0.55	3	1.5	<0.2
1288777	Soil	107	0.64	668	0.007	7	1.30	0.005	0.10	<0.1	0.18	19.8	0.2	0.24	3	2.0	<0.2
1288778	Soil	126	0.51	170	0.012	9	1.23	0.007	0.16	<0.1	0.19	25.6	0.2	0.87	3	1.2	<0.2
1288779	Soil	164	0.87	4936	0.006	5	2.01	0.007	0.05	<0.1	0.11	13.4	<0.1	0.08	5	1.7	<0.2
1288780	Soil	255	1.16	202	0.004	7	2.07	0.008	0.09	<0.1	0.20	20.2	<0.1	0.48	6	2.9	<0.2
1288791	Soil	14	0.10	328	0.004	3	0.43	0.009	0.07	0.2	0.06	0.8	1.2	<0.05	2	2.2	<0.2
1288792	Soil	33	0.24	572	0.005	4	0.55	0.006	0.09	0.2	0.26	3.3	1.2	0.05	1	3.9	<0.2
1288793	Soil	18	0.04	194	0.003	1	0.44	0.006	0.05	<0.1	0.05	0.6	0.4	<0.05	2	2.1	<0.2
1288794	Soil	16	0.07	1269	0.008	2	0.68	0.005	0.07	<0.1	0.16	1.0	0.3	0.06	2	2.7	<0.2
1288795	Soil	9	0.03	1826	0.004	2	0.59	0.006	0.08	<0.1	0.18	1.9	0.2	<0.05	1	2.9	<0.2
1288796	Soil	11	0.05	735	0.006	2	0.70	0.006	0.07	<0.1	0.11	1.2	0.2	<0.05	2	3.1	<0.2
1288797	Soil	8	0.04	703	0.002	2	0.41	0.009	0.06	<0.1	0.07	0.5	0.2	0.06	2	1.1	<0.2
1288798	Soil	10	0.03	377	0.003	2	0.47	0.008	0.06	<0.1	0.08	0.5	0.2	<0.05	2	1.0	<0.2
1288799	Soil	13	0.06	730	0.004	4	0.50	0.004	0.09	<0.1	0.14	0.5	0.3	<0.05	2	1.7	<0.2
1288800	Soil	13	0.05	440	0.003	2	0.45	0.003	0.07	<0.1	1.17	5.3	0.3	<0.05	1	3.9	<0.2
1287461	Soil	32	0.07	1940	0.003	5	0.55	0.003	0.10	1.1	1.96	3.5	0.7	0.06	2	3.8	<0.2
1287462	Soil	33	0.07	2039	0.004	4	0.55	0.003	0.10	1.5	2.00	3.3	0.8	0.07	2	4.5	<0.2
1287463	Soil	26	0.06	1568	0.003	4	0.59	0.002	0.09	0.4	1.63	3.6	0.6	0.05	2	3.6	0.2
1287464	Soil	28	0.06	1642	0.003	4	0.52	0.003	0.09	0.8	1.28	2.7	0.6	0.05	1	2.8	<0.2
1287465	Soil	24	0.06	1346	0.003	3	0.58	0.004	0.08	0.3	1.32	3.1	0.6	<0.05	2	3.2	<0.2
1287466	Soil	28	0.06	1642	0.003	5	0.52	0.003	0.10	0.6	2.00	3.9	0.8	<0.05	2	3.9	<0.2
1287467	Soil	22	0.05	1144	0.002	4	0.39	0.003	0.08	0.2	1.61	3.4	0.7	<0.05	1	3.4	<0.2
1287468	Soil	21	0.05	980	0.002	3	0.35	0.002	0.08	0.1	1.31	3.3	0.6	<0.05	1	2.9	<0.2
1287469	Soil	24	0.07	1075	0.003	5	0.46	0.003	0.09	0.2	1.15	3.8	0.6	0.06	1	2.7	0.2
1287470	Soil	28	0.08	1114	0.003	6	0.51	0.003	0.10	0.3	1.28	4.8	0.7	0.07	2	4.0	<0.2
1274441	Soil	19	0.10	723	0.003	4	0.73	0.006	0.09	0.9	3.91	2.5	1.9	0.07	2	5.7	<0.2
1274442	Soil	19	0.12	1121	0.002	3	0.74	0.007	0.08	0.7	1.13	2.3	0.7	<0.05	2	2.9	<0.2
1274443	Soil	27	0.15	1233	0.002	5	1.02	0.004	0.11	0.4	2.07	3.7	1.0	<0.05	3	4.9	<0.2
1274444	Soil	23	0.14	1143	0.002	4	0.89	0.004	0.09	0.4	1.81	3.4	0.8	<0.05	2	3.7	<0.2
1274445	Soil	19	0.14	1471	0.002	4	0.62	0.004	0.08	0.9	1.03	3.5	0.6	0.05	2	3.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1274446	Soil		9.2	87.3	18.6	511	1.5	120.0	18.1	448	2.77	136.1	10.8	1.8	54	4.7	7.4	0.3	85	0.63	0.096	8
1274447	Soil		8.9	78.0	18.4	776	1.3	158.5	22.9	986	3.17	128.6	41.1	2.1	59	8.8	7.6	0.3	73	0.62	0.096	8
1274448	Soil		13.9	68.1	19.4	206	0.6	43.3	6.4	130	2.48	42.7	4.3	1.6	72	1.6	8.2	0.2	119	0.12	0.112	8
1274449	Soil		17.1	76.7	19.0	436	1.5	94.4	7.1	249	2.83	60.4	8.5	2.1	110	4.1	10.9	0.2	159	0.44	0.185	7
1274450	Soil		6.1	59.9	32.4	209	2.3	44.2	6.1	198	2.22	145.5	39.8	2.4	47	2.6	13.2	0.9	41	0.20	0.092	14
1288461	Soil		14.1	37.5	17.6	123	3.4	23.4	2.3	73	1.95	30.4	2.3	0.2	56	0.8	7.0	0.2	127	0.04	0.157	5
1288462	Soil		16.3	44.4	19.4	134	2.7	26.7	3.1	64	2.15	33.2	3.1	0.3	52	0.4	6.4	0.2	167	0.04	0.130	8
1288463	Soil		28.2	70.6	18.7	197	2.5	38.5	2.5	44	1.90	30.0	1.0	0.3	78	1.0	13.2	0.2	333	0.04	0.090	22
1288464	Soil		2.1	16.6	3.2	27	0.7	10.2	2.3	47	0.80	2.8	0.7	<0.1	6	0.1	0.9	<0.1	22	0.03	0.048	1
1288465	Soil		4.1	52.6	7.6	112	0.4	34.8	9.9	126	3.34	11.6	1.1	1.2	6	0.2	2.0	0.3	48	<0.01	0.041	6
1288466	Soil		6.0	106.4	16.8	228	0.3	65.7	21.8	371	6.40	17.1	9.7	1.3	17	0.3	3.6	0.4	33	0.02	0.098	5
1288467	Soil		10.1	47.9	22.0	176	1.2	33.4	7.1	312	3.30	34.0	3.3	0.4	50	1.0	5.9	0.3	119	0.05	0.207	8
1288468	Soil		6.4	24.6	15.0	85	2.1	19.9	3.8	196	1.86	12.8	1.6	0.2	28	0.3	3.2	0.2	86	0.01	0.116	5
1288469	Soil		10.7	65.7	33.3	210	0.7	47.3	13.1	228	4.50	19.8	3.4	1.1	42	0.6	3.9	0.4	122	0.01	0.102	10
1288470	Soil		10.2	52.1	16.1	234	1.6	38.5	8.2	177	3.08	9.7	0.5	0.2	22	0.6	2.8	0.3	88	0.02	0.102	7
1287671	Soil		0.9	24.1	6.5	66	0.5	19.7	3.2	254	1.17	7.0	1.7	0.5	84	2.0	0.8	<0.1	23	1.16	0.069	3
1287672	Soil		2.1	29.3	12.0	121	0.4	29.0	10.1	173	2.18	11.8	2.7	1.7	51	1.0	1.1	0.2	37	0.70	0.064	4
1287673	Soil		6.9	49.5	26.2	67	2.2	16.0	3.8	95	3.23	55.5	4.6	0.6	66	0.4	8.6	0.3	74	0.03	0.135	2
1287674	Soil		23.0	28.5	25.7	81	2.0	15.5	2.0	63	3.33	31.3	2.7	0.7	44	0.3	9.4	0.3	156	0.04	0.207	2
1287675	Soil		25.9	34.9	23.9	78	1.5	18.0	2.3	61	4.44	36.5	1.5	0.2	35	0.1	6.5	0.3	153	0.04	0.284	2
1287676	Soil		30.4	49.7	35.3	179	2.3	38.1	5.7	146	5.53	33.7	1.1	0.7	77	0.9	9.3	0.3	248	0.09	0.342	1
1287677	Soil		21.5	46.1	31.9	150	2.3	32.3	4.5	149	3.69	22.7	2.3	0.3	76	0.6	7.5	0.3	203	0.05	0.251	2
1287678	Soil		4.1	10.9	6.6	30	1.2	9.6	1.3	46	1.06	6.7	1.3	<0.1	19	0.1	1.6	<0.1	36	0.09	0.073	1
1287679	Soil		25.0	33.0	28.4	93	3.4	21.8	2.7	118	4.02	60.6	8.9	0.3	66	0.2	11.4	0.3	157	0.02	0.190	3
1287680	Soil		4.4	36.4	12.0	115	1.2	44.6	5.5	261	2.55	75.3	11.5	0.2	25	0.5	4.5	0.2	53	0.07	0.091	4
1289091	Soil		5.7	28.3	12.4	79	0.5	32.8	11.2	266	2.03	14.8	2.3	0.7	28	0.5	2.1	0.2	23	0.24	0.053	5
1289092	Soil		3.6	20.6	10.9	35	0.6	18.8	4.2	88	1.57	8.4	<0.5	0.3	11	0.2	1.0	0.2	15	0.12	0.067	4
1289093	Soil		11.7	28.0	10.1	406	0.5	52.9	3.9	101	1.26	11.9	1.9	0.2	22	6.7	4.7	0.1	89	0.35	0.051	3
1289094	Soil		31.1	28.0	17.9	278	0.1	66.5	6.4	147	2.49	22.5	1.3	0.3	11	0.7	5.8	0.2	170	0.04	0.072	5
1289095	Soil		12.7	13.0	9.0	101	<0.1	22.0	2.8	50	1.09	8.8	0.7	<0.1	8	0.3	2.4	0.1	63	0.05	0.059	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274446	Soil		25	0.20	949	0.002	4	1.13	0.006	0.11	0.2	1.79	4.3	0.6	<0.05	3	3.6	<0.2
1274447	Soil		24	0.19	1019	0.002	4	0.97	0.006	0.09	0.6	1.55	4.0	0.5	<0.05	2	3.5	<0.2
1274448	Soil		23	0.08	1733	0.002	2	0.70	0.003	0.08	0.2	1.01	2.9	0.5	<0.05	2	2.9	<0.2
1274449	Soil		30	0.09	1828	0.002	5	0.56	0.003	0.11	2.8	1.91	3.7	0.7	0.05	2	3.0	<0.2
1274450	Soil		19	0.12	697	0.002	3	0.67	0.004	0.09	0.7	7.48	2.5	0.6	<0.05	2	4.1	0.3
1288461	Soil		18	0.02	1065	0.002	3	0.29	0.009	0.06	0.1	0.30	0.5	0.6	0.08	2	5.0	<0.2
1288462	Soil		21	0.03	458	0.005	2	0.50	0.006	0.08	0.2	0.32	0.9	0.6	0.05	3	4.0	<0.2
1288463	Soil		58	0.02	399	0.005	4	0.45	0.004	0.09	0.2	0.23	0.8	1.2	0.09	3	11.9	0.3
1288464	Soil		5	0.02	120	0.003	3	0.25	0.017	0.03	<0.1	0.04	0.3	<0.1	<0.05	1	0.7	<0.2
1288465	Soil		8	0.03	162	0.003	2	0.45	0.002	0.07	<0.1	0.04	2.1	0.1	<0.05	2	1.3	<0.2
1288466	Soil		11	0.04	684	0.003	3	0.58	0.007	0.08	<0.1	0.08	3.2	0.2	<0.05	2	2.3	<0.2
1288467	Soil		22	0.04	1325	0.006	3	0.49	0.005	0.10	0.1	0.15	0.5	0.6	0.08	3	3.9	<0.2
1288468	Soil		13	0.02	853	0.009	3	0.41	0.012	0.06	<0.1	0.07	0.6	0.3	<0.05	2	1.9	<0.2
1288469	Soil		13	0.03	405	0.004	3	0.47	0.002	0.11	<0.1	0.04	2.2	0.3	0.06	2	2.1	<0.2
1288470	Soil		15	0.03	365	0.004	3	0.46	0.005	0.11	<0.1	0.05	0.7	0.2	<0.05	2	1.4	<0.2
1287671	Soil		8	0.14	614	0.004	3	0.50	0.017	0.03	<0.1	0.17	2.0	0.1	0.31	1	1.6	<0.2
1287672	Soil		15	0.19	753	0.002	2	0.68	0.004	0.07	<0.1	0.18	4.0	0.1	0.05	2	1.4	<0.2
1287673	Soil		21	0.03	367	0.002	4	0.35	0.005	0.12	<0.1	1.24	4.2	1.0	0.24	2	7.5	<0.2
1287674	Soil		22	0.10	484	0.002	2	0.48	0.005	0.08	0.1	0.31	2.1	1.1	0.10	2	7.3	<0.2
1287675	Soil		21	0.04	437	0.003	3	0.32	0.007	0.08	0.2	0.26	0.8	0.7	0.16	2	5.8	<0.2
1287676	Soil		33	0.14	656	0.003	3	0.63	0.006	0.10	0.2	0.23	2.1	1.0	0.17	2	7.2	0.2
1287677	Soil		25	0.09	509	0.003	3	0.51	0.010	0.09	0.1	0.24	1.5	1.1	0.12	2	5.2	0.2
1287678	Soil		8	0.03	164	0.005	1	0.34	0.026	0.03	<0.1	0.18	0.6	0.3	<0.05	2	2.1	<0.2
1287679	Soil		20	0.04	494	0.003	2	0.46	0.007	0.10	0.1	0.50	1.3	1.3	0.17	2	6.3	0.2
1287680	Soil		15	0.06	287	0.006	3	0.75	0.012	0.04	0.1	0.16	1.1	0.3	0.09	3	2.2	<0.2
1289091	Soil		9	0.05	1179	0.006	2	0.37	0.008	0.06	<0.1	0.08	2.0	0.1	0.07	1	0.8	<0.2
1289092	Soil		5	0.03	352	0.004	3	0.36	0.013	0.04	<0.1	0.10	1.4	0.1	0.07	1	0.6	<0.2
1289093	Soil		9	0.08	412	0.004	2	0.47	0.020	0.04	<0.1	0.19	1.5	0.3	<0.05	1	1.3	<0.2
1289094	Soil		16	0.06	153	0.004	2	0.46	0.006	0.05	0.1	0.06	1.2	0.4	<0.05	2	1.6	<0.2
1289095	Soil		9	0.03	129	0.007	2	0.39	0.007	0.04	<0.1	0.04	0.4	0.2	<0.05	2	0.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1289096	Soil	22.8	37.9	21.1	249	1.3	65.1	9.4	428	2.74	17.7	1.8	0.3	32	1.3	3.5	0.2	114	0.44	0.156	7
1289097	Soil	120.4	124.5	23.2	242	<0.1	295.9	15.3	707	4.66	32.7	0.6	3.0	19	1.9	1.9	0.2	143	0.24	0.099	14
1289098	Soil	1.6	13.9	2.8	30	0.3	9.0	1.5	58	0.55	1.8	0.9	<0.1	25	0.4	0.4	<0.1	11	0.36	0.071	4
1289099	Soil	9.7	28.8	5.8	81	0.2	50.0	4.3	206	0.85	7.3	0.7	0.4	54	1.6	1.7	0.1	33	1.34	0.075	5
1289100	Soil	25.8	39.3	7.3	215	0.4	84.4	4.2	136	1.07	12.8	0.6	0.4	49	3.0	4.2	0.1	117	1.05	0.096	8
1288741	Soil	7.7	69.9	30.5	318	3.3	63.6	22.4	253	2.53	115.8	55.6	2.2	44	3.3	10.1	0.8	45	0.20	0.097	11
1288742	Soil	5.4	63.3	24.1	516	1.5	127.2	12.8	240	4.79	52.2	14.2	2.1	28	4.8	4.9	0.4	39	0.43	0.086	6
1288743	Soil	4.9	56.8	16.4	209	0.7	66.3	10.2	132	3.37	23.3	4.1	1.4	19	0.8	3.0	0.2	33	0.10	0.070	4
1288744	Soil	8.6	92.5	22.4	326	1.5	94.9	12.9	160	3.52	63.2	17.0	2.6	70	1.9	11.5	0.3	60	1.11	0.125	8
1288745	Soil	3.9	52.3	25.9	135	2.0	43.3	5.7	166	2.02	102.7	56.4	2.4	61	1.2	13.4	0.7	38	0.79	0.075	11
1288746	Soil	7.3	56.2	32.8	114	2.8	28.8	3.8	95	2.24	196.1	79.4	1.7	81	0.9	27.6	1.1	38	0.68	0.103	9
1288747	Soil	6.4	68.2	34.6	163	3.7	40.4	5.8	118	2.44	174.8	77.4	2.0	75	1.5	21.2	1.1	45	0.58	0.106	12
1288748	Soil	6.6	68.9	21.4	176	2.3	54.5	7.5	178	2.47	103.2	30.4	1.5	67	1.8	14.9	0.5	45	0.58	0.093	7
1288749	Soil	9.2	64.7	19.5	220	1.7	59.5	8.3	206	2.28	53.9	14.5	1.5	83	1.9	9.2	0.3	55	0.57	0.100	6
1288750	Soil	11.0	71.4	22.2	253	2.1	66.0	9.3	208	2.50	59.9	14.4	1.8	93	2.2	10.2	0.4	67	0.56	0.108	7
1288751	Soil	9.7	27.0	14.1	191	0.5	35.7	9.4	192	2.83	18.4	2.5	2.0	33	1.3	1.8	0.3	68	0.25	0.074	7
1288752	Soil	8.3	40.2	14.0	332	0.3	55.3	13.0	216	2.80	19.4	2.0	1.4	51	1.1	1.8	0.2	45	0.58	0.062	4
1288753	Soil	13.6	49.0	11.0	1259	0.5	156.7	15.5	959	1.85	17.3	2.8	1.0	93	6.4	3.6	0.2	65	1.79	0.087	5
1288754	Soil	8.2	35.9	12.2	816	0.8	140.2	14.0	297	2.59	17.7	2.5	2.3	70	2.3	2.2	0.2	50	1.66	0.074	5
1288755	Soil	3.9	17.7	14.5	102	0.2	22.1	5.6	108	2.31	20.4	1.6	1.8	30	0.3	2.1	0.3	45	0.24	0.069	6
1288756	Soil	4.1	36.3	14.1	505	1.3	98.1	7.7	222	2.04	12.7	3.3	1.0	99	3.0	1.4	0.2	57	1.22	0.067	5
1288757	Soil	5.0	28.7	13.9	625	0.8	95.2	10.6	250	2.33	15.3	2.6	2.1	74	3.0	1.5	0.2	50	1.06	0.079	7
1288758	Soil	2.9	29.1	13.5	171	1.2	33.7	13.7	340	1.64	9.2	3.5	1.4	60	2.1	1.5	0.2	30	0.43	0.075	5
1288759	Soil	2.9	85.4	33.5	205	3.1	72.9	9.3	128	1.90	18.2	6.3	2.1	200	4.1	2.5	0.3	58	1.03	0.117	5
1288760	Soil	11.0	44.8	14.7	340	0.8	63.8	7.3	339	1.45	11.9	3.1	1.0	73	5.1	3.0	0.2	101	0.57	0.100	6
1289001	Soil	8.0	39.2	27.4	161	0.2	42.6	11.9	217	4.45	23.7	1.5	0.6	17	0.4	2.9	0.3	44	0.04	0.098	5
1289002	Soil	2.8	22.8	60.6	8	1.7	3.9	0.3	5	0.49	4.2	3.5	0.8	28	<0.1	2.7	0.3	36	0.01	0.021	2
1289003	Soil	8.6	14.2	39.2	92	0.5	15.3	2.8	102	1.06	11.5	1.7	0.3	35	0.2	1.6	0.2	26	<0.01	0.033	2
1289004	Soil	6.8	57.3	21.3	149	0.4	35.5	8.4	113	3.10	17.1	1.0	0.5	9	<0.1	3.5	0.3	60	<0.01	0.065	5
1289005	Soil	4.7	22.6	11.2	66	0.5	16.4	3.9	61	1.38	9.4	1.2	0.2	7	<0.1	1.4	0.2	35	<0.01	0.043	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1289096	Soil	21	0.10	834	0.006	3	1.00	0.009	0.07	0.1	0.29	2.0	0.6	0.07	3	1.3	<0.2
1289097	Soil	26	0.07	563	0.003	3	1.14	0.002	0.03	0.3	1.15	6.5	1.4	<0.05	2	1.8	<0.2
1289098	Soil	4	0.03	718	0.008	1	0.50	0.023	0.03	<0.1	0.06	0.8	<0.1	0.06	1	<0.5	<0.2
1289099	Soil	8	0.09	338	0.008	3	0.47	0.020	0.03	<0.1	0.09	1.4	0.2	0.08	1	1.8	<0.2
1289100	Soil	19	0.11	290	0.006	3	0.56	0.015	0.05	0.1	0.25	2.1	1.2	0.08	1	2.9	<0.2
1288741	Soil	22	0.08	517	0.003	3	0.64	0.005	0.06	0.7	6.49	3.2	0.8	<0.05	2	4.2	<0.2
1288742	Soil	22	0.11	368	0.002	3	0.76	0.005	0.08	0.6	1.91	6.1	0.3	0.05	2	4.0	<0.2
1288743	Soil	16	0.05	487	0.002	2	0.57	0.005	0.06	0.2	0.32	4.3	0.1	<0.05	2	2.5	<0.2
1288744	Soil	29	0.26	1525	0.003	5	0.81	0.005	0.07	0.7	1.36	4.4	1.1	0.07	2	2.7	<0.2
1288745	Soil	20	0.13	632	0.002	5	0.63	0.004	0.07	0.5	10.18	3.1	0.6	0.10	2	4.7	<0.2
1288746	Soil	17	0.09	715	0.001	4	0.54	0.005	0.07	0.8	17.56	2.2	0.7	0.15	2	8.1	0.2
1288747	Soil	21	0.11	623	0.001	4	0.66	0.004	0.07	1.5	16.24	2.6	0.7	0.09	2	7.3	<0.2
1288748	Soil	20	0.15	1187	0.002	4	0.73	0.006	0.06	1.6	4.63	2.5	0.4	0.09	2	5.0	<0.2
1288749	Soil	18	0.12	1160	0.003	4	0.61	0.010	0.06	0.8	1.66	2.4	0.4	0.09	2	3.5	<0.2
1288750	Soil	23	0.13	1367	0.003	5	0.67	0.010	0.08	2.2	1.83	3.0	0.5	0.09	2	4.0	<0.2
1288751	Soil	19	0.19	910	0.003	2	0.92	0.006	0.06	0.1	0.24	2.5	0.3	<0.05	3	1.2	<0.2
1288752	Soil	13	0.10	576	0.001	2	0.48	0.005	0.05	<0.1	0.15	4.0	0.2	<0.05	1	1.1	<0.2
1288753	Soil	13	0.16	829	0.002	5	0.49	0.005	0.04	<0.1	0.33	2.6	0.4	0.15	1	2.5	<0.2
1288754	Soil	18	0.21	1150	0.003	3	0.79	0.005	0.08	<0.1	0.22	3.9	0.3	0.07	2	2.1	<0.2
1288755	Soil	15	0.16	220	0.006	1	0.64	0.005	0.05	0.1	0.06	1.6	0.1	<0.05	3	1.1	<0.2
1288756	Soil	14	0.12	841	0.002	2	0.74	0.007	0.05	<0.1	0.22	3.3	0.4	0.11	2	2.5	<0.2
1288757	Soil	18	0.26	478	0.006	3	0.83	0.008	0.06	0.1	0.13	3.2	0.2	<0.05	3	1.7	<0.2
1288758	Soil	15	0.13	874	0.002	2	0.74	0.006	0.06	0.1	0.18	2.5	0.3	<0.05	2	1.0	<0.2
1288759	Soil	23	0.16	2277	0.002	4	1.22	0.007	0.08	<0.1	0.60	4.6	0.4	0.13	3	3.8	<0.2
1288760	Soil	14	0.07	894	0.003	3	0.55	0.010	0.05	0.1	0.23	3.0	0.7	0.06	2	2.2	<0.2
1289001	Soil	22	0.08	91	0.003	<1	0.78	0.003	0.05	<0.1	0.08	1.7	0.2	<0.05	2	1.0	<0.2
1289002	Soil	8	<0.01	456	<0.001	2	0.20	0.003	0.06	<0.1	0.30	1.2	0.4	<0.05	1	1.3	<0.2
1289003	Soil	6	0.02	2123	<0.001	2	0.37	0.004	0.04	<0.1	0.16	0.8	0.3	<0.05	1	0.9	<0.2
1289004	Soil	10	0.01	76	0.003	1	0.34	0.003	0.04	0.1	0.04	1.9	0.2	<0.05	3	1.3	<0.2
1289005	Soil	7	0.01	101	0.002	1	0.36	0.004	0.03	<0.1	0.04	0.7	0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1289006	Soil		61.5	59.8	10.1	1081	1.4	154.9	4.4	101	1.26	30.0	3.3	0.6	45	11.3	21.1	0.2	267	0.69	0.091	10
1289007	Soil		3.6	20.1	8.7	49	0.3	19.3	5.5	134	1.77	14.1	0.7	0.1	6	<0.1	1.6	0.2	25	0.02	0.060	11
1289008	Soil		6.3	63.0	36.8	130	0.4	65.8	32.1	927	5.75	49.9	4.3	3.1	5	0.1	5.3	0.5	21	0.02	0.067	18
1289009	Soil		3.0	51.4	10.3	53	0.1	47.1	13.9	215	3.65	36.4	1.1	0.4	4	<0.1	2.6	0.3	25	0.02	0.083	24
1289010	Soil		1.8	12.2	5.5	26	<0.1	12.9	3.7	91	0.94	6.3	0.6	<0.1	4	<0.1	0.9	<0.1	14	0.02	0.047	6
1289021	Soil		11.8	40.9	15.3	171	1.2	33.1	4.8	108	2.05	29.9	4.6	0.4	44	1.1	7.4	0.2	130	0.06	0.140	9
1289022	Soil		19.9	83.7	17.9	353	2.5	63.1	8.9	168	2.80	51.8	11.2	1.4	108	5.1	16.3	0.2	182	0.23	0.221	7
1289023	Soil		27.3	136.0	31.1	861	3.0	141.1	13.2	468	5.15	124.1	19.7	2.7	136	10.4	26.0	0.4	254	0.51	0.287	8
1289024	Soil		11.8	34.4	14.6	194	1.1	29.1	2.6	51	1.75	27.0	2.9	0.2	32	0.5	7.4	0.2	135	0.02	0.088	5
1289025	Soil		9.2	26.2	12.0	77	0.7	15.7	1.6	24	1.70	29.2	6.1	1.2	52	0.5	6.7	0.2	111	0.02	0.147	3
1289026	Soil		16.6	33.4	21.6	204	1.5	36.3	3.5	141	2.80	57.2	5.6	0.6	46	0.4	11.5	0.3	213	0.05	0.185	6
1289027	Soil		17.0	59.8	19.7	356	3.0	55.4	4.5	88	2.93	51.8	10.9	0.5	65	2.0	14.2	0.2	168	0.10	0.213	6
1289028	Soil		18.5	79.0	23.1	316	2.5	49.6	7.2	146	3.19	54.7	10.0	0.9	71	3.3	15.4	0.3	173	0.11	0.249	7
1289029	Soil		7.2	32.5	10.6	522	1.1	56.1	3.9	284	1.63	18.0	2.8	0.7	58	2.3	3.3	0.2	121	0.60	0.145	8
1289030	Soil		3.2	12.3	8.3	43	0.5	8.2	1.4	25	0.65	7.1	2.1	<0.1	10	0.1	1.6	0.2	47	0.02	0.029	8
1289051	Soil		37.7	56.0	7.9	302	0.3	149.0	17.3	373	2.89	22.7	1.0	2.2	128	3.6	5.0	<0.1	139	4.51	0.137	16
1289052	Soil		1.8	9.2	1.6	50	<0.1	13.4	3.3	105	0.55	1.9	<0.5	0.1	18	0.4	0.4	<0.1	23	0.27	0.052	4
1289053	Soil		12.9	74.6	5.9	361	0.3	259.5	52.3	1001	7.44	29.0	0.5	1.6	79	3.1	3.0	0.1	130	1.07	0.170	27
1289054	Soil		51.7	109.8	14.8	609	0.8	587.5	73.2	1198	8.34	94.5	1.3	3.7	119	5.7	7.5	0.2	353	1.21	0.179	33
1289055	Soil		7.0	138.4	31.4	151	0.3	419.3	103.8	921	11.24	16.5	2.9	18.0	40	0.3	1.0	0.1	63	1.41	0.159	59
1289056	Soil		3.0	150.4	25.6	78	0.2	441.7	130.7	708	9.30	13.4	1.4	13.4	84	0.3	1.1	<0.1	65	5.09	0.150	43
1289057	Soil		1.8	91.0	10.2	49	0.1	258.3	65.7	982	6.67	24.3	1.4	6.7	72	0.2	0.8	<0.1	66	3.11	0.250	86
1289058	Soil		4.1	73.9	9.8	48	<0.1	217.6	48.3	826	6.02	81.8	0.8	5.9	35	0.2	1.2	0.1	81	0.62	0.230	80
1289059	Soil		4.3	95.8	14.1	78	0.2	263.6	58.5	870	7.33	28.0	0.9	7.6	51	0.3	0.9	0.1	65	1.19	0.276	101
1289060	Soil		3.9	45.5	12.9	112	0.1	139.9	41.6	1330	5.99	20.0	0.6	1.8	35	0.6	1.0	0.2	169	0.53	0.298	54
1289061	Soil		17.3	78.4	15.5	281	0.2	266.2	55.0	1411	7.06	51.9	2.9	2.7	47	2.8	4.2	0.1	219	0.47	0.230	61
1289062	Soil		13.0	54.5	10.9	298	0.2	179.2	39.7	1001	5.80	33.8	1.0	1.2	29	1.8	3.2	0.1	192	0.28	0.231	27
1289063	Soil		15.9	91.5	9.9	251	0.3	362.1	58.1	886	8.22	53.6	1.5	4.1	66	2.4	3.1	<0.1	176	1.25	0.238	47
1289064	Soil		27.3	65.9	13.3	660	0.3	192.0	23.5	494	4.82	41.7	1.8	1.5	29	4.1	7.1	0.2	358	0.31	0.277	35
1289065	Soil		119.1	78.2	21.5	1402	0.6	230.7	7.2	139	2.68	69.3	0.7	0.8	22	9.2	21.5	0.2	1063	0.24	0.134	22

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1289006	Soil	21	0.32	311	0.004	3	0.56	0.007	0.07	0.2	0.55	1.6	1.8	<0.05	2	3.5	<0.2
1289007	Soil	6	0.02	508	0.005	1	0.30	0.007	0.04	<0.1	0.04	0.2	0.1	<0.05	2	<0.5	<0.2
1289008	Soil	7	0.05	206	0.002	2	0.42	0.003	0.08	<0.1	0.11	3.9	0.2	<0.05	1	0.7	<0.2
1289009	Soil	6	0.04	123	0.003	2	0.39	0.006	0.05	<0.1	0.04	0.9	0.1	<0.05	2	<0.5	<0.2
1289010	Soil	4	0.02	60	0.003	1	0.16	0.013	0.04	<0.1	0.02	0.2	<0.1	<0.05	1	<0.5	<0.2
1289021	Soil	18	0.03	1173	0.008	3	0.45	0.005	0.06	0.2	0.37	0.8	0.4	0.06	3	2.5	<0.2
1289022	Soil	26	0.04	1853	0.003	4	0.43	0.003	0.08	0.2	1.36	3.3	0.8	0.07	1	6.2	<0.2
1289023	Soil	31	0.07	1868	0.004	4	0.46	0.003	0.10	0.2	2.48	5.1	1.1	0.09	2	9.1	0.3
1289024	Soil	14	0.02	1557	0.003	3	0.36	0.007	0.05	0.1	0.28	0.5	0.4	0.08	2	3.3	<0.2
1289025	Soil	11	0.01	1440	0.003	3	0.30	0.002	0.05	<0.1	0.22	1.1	0.4	<0.05	1	2.8	<0.2
1289026	Soil	22	0.03	933	0.003	2	0.46	0.005	0.06	0.2	0.19	1.2	0.6	0.06	3	4.8	<0.2
1289027	Soil	25	0.03	1561	0.004	3	0.43	0.007	0.06	0.2	0.97	1.5	0.7	0.07	2	7.3	<0.2
1289028	Soil	25	0.04	1584	0.003	4	0.48	0.003	0.08	0.2	1.38	2.7	0.7	0.08	2	6.6	<0.2
1289029	Soil	24	0.20	2016	0.004	3	0.84	0.005	0.06	0.1	0.47	1.8	0.4	<0.05	3	2.1	<0.2
1289030	Soil	8	0.02	194	0.005	2	0.33	0.007	0.04	<0.1	0.04	0.1	0.2	<0.05	3	<0.5	<0.2
1289051	Soil	33	2.22	2486	0.005	6	0.47	0.006	0.08	0.1	0.14	5.2	0.7	0.10	1	1.6	<0.2
1289052	Soil	6	0.05	464	0.011	2	0.42	0.033	0.03	<0.1	0.02	0.6	<0.1	0.06	1	<0.5	<0.2
1289053	Soil	54	0.22	542	0.004	5	0.88	0.014	0.07	0.1	0.07	12.8	0.3	0.34	2	1.4	<0.2
1289054	Soil	59	0.47	2439	0.005	8	0.79	0.008	0.11	<0.1	0.26	16.1	1.0	0.10	2	5.7	<0.2
1289055	Soil	113	0.27	852	0.011	11	0.60	0.005	0.15	<0.1	0.27	23.2	0.3	0.26	1	<0.5	<0.2
1289056	Soil	115	1.11	1029	0.009	13	0.67	0.005	0.12	<0.1	0.10	19.7	0.2	0.24	1	<0.5	<0.2
1289057	Soil	88	0.80	1391	0.004	9	0.67	0.004	0.14	0.1	0.06	15.2	<0.1	0.11	2	<0.5	<0.2
1289058	Soil	120	0.29	2151	0.004	7	1.55	0.010	0.08	0.3	0.04	11.5	0.2	0.10	4	<0.5	<0.2
1289059	Soil	96	0.16	1785	0.006	8	0.87	0.007	0.13	0.3	0.10	16.2	0.2	0.11	2	<0.5	<0.2
1289060	Soil	280	1.80	2509	0.020	3	2.68	0.005	0.06	0.3	0.04	3.6	0.2	0.11	9	<0.5	<0.2
1289061	Soil	191	1.17	2260	0.015	5	1.94	0.007	0.10	0.2	0.06	9.4	0.5	0.08	6	2.0	<0.2
1289062	Soil	176	0.82	1765	0.008	4	1.64	0.005	0.08	0.1	0.03	3.5	0.5	0.07	6	1.3	<0.2
1289063	Soil	88	0.33	2410	0.003	9	0.89	0.005	0.13	<0.1	0.16	16.7	0.4	0.14	2	1.6	<0.2
1289064	Soil	132	0.45	1804	0.005	5	1.36	0.005	0.10	0.1	0.05	3.2	0.8	0.08	5	4.5	<0.2
1289065	Soil	74	0.17	712	0.005	5	0.99	0.004	0.12	0.3	0.15	1.3	2.9	<0.05	3	10.0	0.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1289066	Soil	72.4	62.1	18.8	777	0.2	151.9	16.2	361	3.47	62.2	0.9	0.5	11	3.5	17.3	0.2	607	0.04	0.132	27
1289067	Soil	50.1	76.0	15.9	643	0.1	193.0	29.9	650	5.51	61.0	1.3	2.3	43	2.4	9.4	0.1	371	0.40	0.194	55
1289068	Soil	96.5	52.9	9.2	665	0.1	141.7	7.5	56	1.91	28.6	0.6	2.2	10	5.4	14.6	0.1	93	0.09	0.032	23
1289069	Soil	6.4	28.6	9.8	217	0.6	46.2	5.4	61	1.80	20.1	0.5	0.3	3	0.2	6.2	0.2	47	0.02	0.068	8
1289070	Soil	6.0	58.8	28.3	252	1.6	59.8	10.1	87	3.19	43.1	2.5	0.8	54	0.5	3.0	0.3	39	0.10	0.251	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

CERTIFICATE OF ANALYSIS WHI11001948.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1289066	Soil	54	0.16	400	0.005	3	0.84	0.003	0.11	0.2	0.05	0.9	2.1	<0.05	4	4.9	<0.2
1289067	Soil	105	0.72	766	0.006	4	1.48	0.006	0.11	0.2	0.05	4.7	1.7	<0.05	6	2.2	<0.2
1289068	Soil	5	0.03	127	0.001	2	0.16	0.002	0.04	<0.1	0.26	2.2	0.5	<0.05	<1	3.9	<0.2
1289069	Soil	10	0.03	69	0.001	1	0.40	0.005	0.04	<0.1	0.12	0.5	0.1	<0.05	2	2.0	<0.2
1289070	Soil	13	0.05	1609	0.002	2	0.92	0.006	0.08	<0.1	0.34	1.2	0.2	0.10	2	4.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

QUALITY CONTROL REPORT WHI11001948.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1287682	Soil	1.1	22.1	6.1	32	1.4	7.8	4.0	204	1.20	6.7	2.4	0.1	9	0.3	1.2	<0.1	17	0.06	0.061	2
REP 1287682	QC	1.1	21.7	6.0	31	1.4	7.5	3.8	202	1.18	6.5	2.0	0.1	9	0.2	1.2	0.1	17	0.06	0.058	2
1288479	Soil	10.1	81.0	25.4	181	0.7	33.0	9.6	235	4.92	21.9	10.4	1.2	54	0.5	4.5	0.3	106	0.13	0.214	14
REP 1288479	QC	9.6	79.0	25.5	180	0.7	31.9	9.8	232	4.85	21.1	10.1	1.3	53	0.5	4.4	0.3	107	0.13	0.223	14
1289082	Soil	3.4	50.8	9.2	106	1.3	57.5	7.8	169	2.21	16.2	5.1	0.4	45	0.2	4.2	0.2	22	0.44	0.125	4
REP 1289082	QC	3.2	49.2	9.0	109	1.3	57.8	7.5	169	2.20	16.1	4.5	0.3	45	0.4	4.1	0.2	21	0.44	0.125	4
1287695	Soil	64.0	90.2	10.7	616	2.0	190.6	8.8	241	2.44	44.4	1.3	1.5	42	10.8	12.0	0.1	258	0.73	0.125	12
REP 1287695	QC	63.1	92.7	10.8	618	1.8	193.2	9.1	244	2.50	44.0	3.9	1.5	41	10.7	11.6	0.2	270	0.77	0.128	12
1288769	Soil	5.5	24.5	14.3	103	0.3	28.6	7.1	167	2.64	29.9	1.9	1.8	28	0.5	1.9	0.3	60	0.20	0.057	11
REP 1288769	QC	5.9	25.4	14.2	103	0.3	29.4	7.4	174	2.71	30.7	1.7	1.7	30	0.4	2.0	0.3	63	0.21	0.055	11
1288797	Soil	7.8	24.5	12.7	97	0.4	29.2	4.7	49	1.45	11.5	1.1	0.2	25	0.3	1.7	0.1	34	0.08	0.135	7
REP 1288797	QC	7.5	26.2	13.1	98	0.4	30.6	4.7	53	1.52	11.6	1.4	0.3	27	0.3	1.9	0.2	36	0.08	0.160	8
1274445	Soil	13.7	58.9	21.9	338	0.9	67.5	10.5	235	2.59	99.0	8.9	2.9	54	4.3	11.3	0.3	87	0.28	0.114	11
REP 1274445	QC	14.2	59.8	21.2	340	1.0	71.4	11.0	234	2.66	97.9	7.9	2.8	53	3.6	11.1	0.3	83	0.29	0.116	10
1288463	Soil	28.2	70.6	18.7	197	2.5	38.5	2.5	44	1.90	30.0	1.0	0.3	78	1.0	13.2	0.2	333	0.04	0.090	22
REP 1288463	QC	29.4	68.0	18.3	192	2.6	39.6	2.4	43	1.80	30.0	1.0	0.4	78	0.9	13.1	0.3	321	0.04	0.085	21
1289098	Soil	1.6	13.9	2.8	30	0.3	9.0	1.5	58	0.55	1.8	0.9	<0.1	25	0.4	0.4	<0.1	11	0.36	0.071	4
REP 1289098	QC	1.7	13.7	2.7	32	0.3	9.4	1.5	59	0.54	2.3	<0.5	0.1	25	0.5	0.3	<0.1	13	0.36	0.072	4
1288749	Soil	9.2	64.7	19.5	220	1.7	59.5	8.3	206	2.28	53.9	14.5	1.5	83	1.9	9.2	0.3	55	0.57	0.100	6
REP 1288749	QC	9.1	66.0	19.9	227	1.8	61.9	8.5	217	2.26	55.1	16.8	1.5	83	2.1	9.5	0.4	59	0.60	0.103	7
1289006	Soil	61.5	59.8	10.1	1081	1.4	154.9	4.4	101	1.26	30.0	3.3	0.6	45	11.3	21.1	0.2	267	0.69	0.091	10
REP 1289006	QC	58.1	58.7	9.6	1047	1.3	149.5	4.1	97	1.23	28.9	2.4	0.5	42	10.8	20.2	0.2	274	0.65	0.088	10
1289058	Soil	4.1	73.9	9.8	48	<0.1	217.6	48.3	826	6.02	81.8	0.8	5.9	35	0.2	1.2	0.1	81	0.62	0.230	80
REP 1289058	QC	4.5	74.0	10.8	50	<0.1	223.6	48.3	831	5.97	85.2	0.8	5.4	37	0.2	1.3	0.1	82	0.62	0.236	83
Reference Materials																					
STD DS8	Standard	14.1	115.6	127.7	322	1.8	40.7	8.4	646	2.58	28.3	162.7	7.8	70	2.6	6.5	7.0	46	0.74	0.077	19
STD DS8	Standard	12.7	118.0	129.1	311	1.7	40.6	7.8	600	2.44	25.5	114.0	6.9	67	2.4	5.2	6.8	45	0.69	0.074	14
STD DS8	Standard	12.7	102.9	124.0	293	1.7	35.0	7.0	597	2.38	26.0	109.2	6.4	71	2.3	5.5	6.3	40	0.68	0.077	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

QUALITY CONTROL REPORT WHI11001948.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1287682	Soil		6	0.03	122	0.009	1	0.87	0.028	0.02	<0.1	0.11	0.8	<0.1	0.06	2	1.3	<0.2
REP 1287682	QC		6	0.03	117	0.008	2	0.82	0.031	0.03	<0.1	0.10	0.8	<0.1	<0.05	2	1.6	<0.2
1288479	Soil		27	0.37	306	0.011	5	1.40	0.004	0.17	<0.1	0.16	1.8	0.4	0.09	5	3.5	<0.2
REP 1288479	QC		27	0.37	311	0.012	5	1.46	0.005	0.18	<0.1	0.16	1.8	0.4	0.08	5	2.7	<0.2
1289082	Soil		6	0.06	1171	0.003	2	0.39	0.015	0.04	<0.1	0.26	1.8	0.1	<0.05	2	1.6	<0.2
REP 1289082	QC		6	0.06	1177	0.006	2	0.39	0.016	0.05	<0.1	0.29	1.8	0.1	<0.05	2	1.5	<0.2
1287695	Soil		25	0.12	1257	0.003	4	0.64	0.004	0.08	1.9	1.40	3.8	1.6	0.06	2	3.6	<0.2
REP 1287695	QC		26	0.12	1281	0.003	5	0.66	0.004	0.09	1.9	1.39	3.7	1.7	0.05	2	3.7	<0.2
1288769	Soil		19	0.23	702	0.009	1	1.07	0.007	0.07	0.2	0.06	2.0	0.2	<0.05	4	2.0	<0.2
REP 1288769	QC		20	0.23	689	0.009	1	1.08	0.007	0.08	0.3	0.07	2.1	0.2	<0.05	4	1.8	<0.2
1288797	Soil		8	0.04	703	0.002	2	0.41	0.009	0.06	<0.1	0.07	0.5	0.2	0.06	2	1.1	<0.2
REP 1288797	QC		9	0.04	763	0.004	1	0.44	0.009	0.07	<0.1	0.08	0.9	0.2	<0.05	2	2.1	<0.2
1274445	Soil		19	0.14	1471	0.002	4	0.62	0.004	0.08	0.9	1.03	3.5	0.6	0.05	2	3.8	<0.2
REP 1274445	QC		18	0.13	1349	0.002	3	0.60	0.003	0.08	0.9	1.02	3.3	0.6	<0.05	2	3.5	<0.2
1288463	Soil		58	0.02	399	0.005	4	0.45	0.004	0.09	0.2	0.23	0.8	1.2	0.09	3	11.9	0.3
REP 1288463	QC		55	0.02	389	0.004	3	0.43	0.004	0.09	0.2	0.24	0.7	1.1	0.09	3	11.5	0.3
1289098	Soil		4	0.03	718	0.008	1	0.50	0.023	0.03	<0.1	0.06	0.8	<0.1	0.06	1	<0.5	<0.2
REP 1289098	QC		4	0.03	694	0.008	2	0.50	0.021	0.03	<0.1	0.07	0.8	<0.1	<0.05	1	<0.5	<0.2
1288749	Soil		18	0.12	1160	0.003	4	0.61	0.010	0.06	0.8	1.66	2.4	0.4	0.09	2	3.5	<0.2
REP 1288749	QC		19	0.12	1303	0.003	4	0.64	0.010	0.07	0.8	1.82	2.6	0.5	0.08	2	3.6	<0.2
1289006	Soil		21	0.32	311	0.004	3	0.56	0.007	0.07	0.2	0.55	1.6	1.8	<0.05	2	3.5	<0.2
REP 1289006	QC		22	0.31	306	0.004	3	0.56	0.010	0.07	0.2	0.50	1.6	1.8	<0.05	2	3.5	<0.2
1289058	Soil		120	0.29	2151	0.004	7	1.55	0.010	0.08	0.3	0.04	11.5	0.2	0.10	4	<0.5	<0.2
REP 1289058	QC		125	0.31	2293	0.005	10	1.61	0.012	0.10	0.4	0.05	11.1	0.2	0.08	5	<0.5	<0.2
Reference Materials																		
STD DS8	Standard		123	0.62	297	0.124	3	1.04	0.103	0.44	3.2	0.21	3.1	5.6	0.16	5	5.8	5.5
STD DS8	Standard		124	0.61	267	0.120	3	0.98	0.111	0.44	2.9	0.20	4.7	5.5	0.16	5	5.2	5.1
STD DS8	Standard		111	0.61	272	0.125	2	0.96	0.104	0.41	2.9	0.19	2.4	5.3	0.14	5	4.8	4.8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

QUALITY CONTROL REPORT WHI11001948.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	14.2	113.1	127.3	321	1.8	40.4	7.9	635	2.53	26.6	99.0	6.9	72	2.3	5.6	6.9	44	0.70	0.083	16
STD DS8	Standard	13.0	114.5	124.3	316	1.8	39.2	7.5	613	2.46	26.3	105.2	6.9	73	2.2	5.5	6.6	43	0.71	0.081	16
STD DS8	Standard	12.1	108.6	121.5	301	1.8	37.0	7.3	572	2.34	26.6	109.7	6.4	65	2.3	5.8	6.7	40	0.62	0.078	13
STD DS8	Standard	13.3	106.5	124.4	292	1.8	36.6	7.0	587	2.39	24.7	112.1	6.7	62	2.2	5.0	6.3	40	0.68	0.079	16
STD DS8	Standard	12.4	107.8	125.5	289	1.7	35.2	7.3	554	2.25	25.8	102.5	6.5	68	2.3	5.4	6.5	38	0.63	0.072	13
STD DS8	Standard	13.6	107.5	134.6	306	1.7	37.0	7.1	600	2.40	25.4	111.5	7.4	80	2.0	6.1	6.9	41	0.71	0.075	17
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 05, 2011

QUALITY CONTROL REPORT WHI11001948.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
STD DS8	Standard	128	0.64	284	0.128	2	0.98	0.107	0.43	2.9	0.20	3.0	5.5	0.14	5	4.5	5.0
STD DS8	Standard	120	0.62	289	0.130	2	0.96	0.110	0.44	2.9	0.19	3.0	5.4	0.12	5	6.2	4.8
STD DS8	Standard	113	0.58	256	0.109	2	0.87	0.090	0.40	2.8	0.23	1.8	5.3	0.14	4	5.1	4.9
STD DS8	Standard	109	0.58	274	0.109	3	0.87	0.102	0.40	3.1	0.19	2.4	5.3	0.16	5	4.7	4.7
STD DS8	Standard	106	0.58	272	0.111	2	0.91	0.112	0.37	2.7	0.21	2.2	5.3	0.10	5	5.0	4.6
STD DS8	Standard	113	0.60	281	0.130	2	0.96	0.096	0.42	2.9	0.18	2.5	5.5	0.15	5	4.3	5.0
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 21, 2011
Report Date: December 01, 2011
Page: 1 of 11

CERTIFICATE OF ANALYSIS WHI11001949.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #29
P.O. Number
Number of Samples:

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
S230	280	Sieve soil to 230 mesh			VAN
RJSV	280	Saving all or part of Soil Reject			VAN
1DX2	275	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1288311	Soil		8.8	38.0	11.9	162	0.5	47.4	6.7	271	1.39	11.9	4.5	1.1	64	3.4	2.1	0.2	52	1.28	0.084
1288312	Soil		9.6	33.5	15.8	104	0.3	27.4	4.2	48	0.95	5.8	3.8	2.2	39	1.1	1.5	0.2	43	0.32	0.102
1288313	Soil		15.8	49.0	14.8	239	0.8	67.8	9.1	229	1.96	16.2	5.4	1.1	56	2.8	2.8	0.2	68	0.86	0.080
1288314	Soil		19.9	49.6	18.0	226	0.5	63.7	8.5	185	2.24	22.6	5.2	0.8	37	2.2	3.1	0.2	75	0.35	0.099
1288315	Soil		8.6	82.2	39.1	155	0.7	38.4	10.0	120	3.80	34.6	8.1	0.7	26	0.4	4.7	0.4	61	0.05	0.098
1288316	Soil		4.4	52.7	20.6	150	0.2	35.9	12.2	282	2.88	54.9	3.1	0.3	17	0.5	2.4	0.3	34	0.04	0.068
1288317	Soil		6.5	44.3	22.8	122	0.2	34.0	10.3	280	2.73	77.5	3.1	0.3	18	0.3	2.3	0.3	54	0.05	0.089
1288318	Soil		20.1	59.0	30.4	241	0.9	46.6	5.9	161	1.95	81.9	3.5	0.7	101	1.3	8.2	0.3	105	0.09	0.070
1288319	Soil		108.1	96.9	10.9	381	0.4	259.7	9.1	120	2.20	46.9	2.9	3.2	243	4.7	9.6	0.1	107	6.52	0.098
1288320	Soil		49.2	63.4	9.7	241	0.4	146.0	7.2	158	1.85	35.0	4.3	1.8	113	2.8	5.6	0.1	84	3.63	0.105
1288321	Soil		80.9	73.7	9.4	417	0.5	175.0	6.3	160	1.68	71.2	3.1	2.5	241	5.2	11.7	<0.1	157	9.00	0.111
1288322	Soil		20.6	22.1	9.5	132	<0.1	37.5	4.6	81	1.34	25.0	1.0	0.6	13	0.3	2.2	0.2	56	0.20	0.038
1288323	Soil		19.6	14.4	5.7	94	<0.1	25.6	3.1	45	0.98	16.4	0.7	0.2	9	0.2	2.0	0.1	61	0.07	0.028
1288324	Soil		34.7	18.8	7.0	112	<0.1	59.4	3.9	36	1.08	13.5	1.4	0.2	15	0.4	1.7	<0.1	49	0.33	0.038
1288325	Soil		32.8	20.6	8.7	132	0.3	51.9	3.6	40	1.05	18.7	2.2	0.1	20	0.6	3.0	0.1	65	0.37	0.049
1288326	Soil		11.3	23.1	3.1	67	0.1	43.0	1.9	63	0.53	5.6	2.7	0.2	53	1.1	1.1	<0.1	23	1.30	0.040
1288327	Soil		23.9	32.9	9.6	95	0.2	80.8	6.4	257	1.89	14.0	2.1	0.9	69	0.9	1.8	0.1	59	1.54	0.078
1288328	Soil		72.8	65.2	10.9	314	0.2	178.7	10.4	201	2.35	24.3	2.8	2.2	95	1.5	2.8	0.1	41	3.13	0.104
1288329	Soil		77.7	72.1	9.2	607	0.4	196.3	7.7	159	1.91	28.2	1.3	1.7	115	2.7	5.2	0.1	89	3.97	0.100
1288330	Soil		99.4	64.9	13.0	1167	0.5	208.1	6.1	220	2.00	30.6	1.5	2.0	135	13.3	9.4	0.1	120	6.48	0.093
1288331	Soil		22.1	22.1	12.0	127	0.2	36.0	4.7	55	1.57	24.4	1.8	0.7	7	0.1	2.6	0.2	79	0.03	0.032
1288332	Soil		43.1	31.3	12.1	237	0.6	110.6	6.8	172	2.42	31.5	3.0	0.9	38	1.2	2.7	0.1	72	0.55	0.075
1288333	Soil		29.7	59.0	13.7	747	1.9	125.8	6.0	163	1.57	80.0	5.4	0.2	96	15.3	11.6	0.2	225	0.72	0.192
1288334	Soil		6.5	20.3	11.0	57	0.2	14.0	3.0	50	0.96	54.9	3.8	0.3	10	0.2	1.6	0.2	45	0.04	0.036
1288335	Soil		4.6	43.8	18.2	105	0.5	24.6	8.9	330	1.96	45.6	3.0	0.4	29	0.6	1.8	0.3	42	0.23	0.079
1288336	Soil		2.5	20.4	9.9	49	0.4	11.8	5.2	214	0.96	18.0	0.8	<0.1	13	0.2	1.0	0.1	21	0.07	0.058
1288337	Soil		6.0	49.5	17.1	136	0.4	35.2	10.9	359	4.22	28.7	4.2	0.4	12	0.8	2.2	0.3	79	0.06	0.088
1288338	Soil		4.8	42.3	16.1	158	0.3	27.9	7.6	198	3.00	26.4	2.3	0.4	11	0.4	2.4	0.3	58	0.06	0.100
1288339	Soil		4.8	33.8	16.1	116	0.2	25.3	6.3	118	2.10	44.1	3.9	0.6	10	<0.1	2.4	0.3	45	0.02	0.036
1288340	Soil		4.7	35.4	20.5	80	0.6	19.6	5.1	87	2.06	37.9	3.5	0.3	18	0.2	1.8	0.3	47	0.03	0.073

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288311	Soil		6	14	0.14	788	0.003	3	0.50	0.012	0.04	<0.1	0.26	3.0	0.2	0.11	1	2.0	<0.2
1288312	Soil		12	13	0.11	815	0.002	1	0.52	0.005	0.05	0.1	0.22	2.1	0.2	<0.05	2	0.8	<0.2
1288313	Soil		7	16	0.22	1256	0.004	4	0.80	0.013	0.08	0.1	0.20	2.4	0.3	0.06	2	0.7	<0.2
1288314	Soil		9	14	0.13	793	0.003	4	0.57	0.007	0.07	<0.1	0.17	1.9	0.3	<0.05	2	1.6	<0.2
1288315	Soil		5	17	0.02	188	0.005	3	0.41	0.005	0.07	<0.1	0.13	3.2	0.1	<0.05	2	3.6	0.4
1288316	Soil		3	10	0.03	126	0.002	1	0.38	0.007	0.05	<0.1	0.04	1.8	0.2	0.07	2	1.4	<0.2
1288317	Soil		5	15	0.04	326	0.002	1	0.47	0.003	0.05	<0.1	0.03	1.4	0.2	0.08	3	1.1	<0.2
1288318	Soil		4	13	0.03	1037	0.002	3	0.42	0.004	0.06	0.1	0.21	2.5	1.0	0.13	2	4.3	<0.2
1288319	Soil		9	14	1.73	355	0.006	5	0.14	0.006	0.05	0.3	0.60	3.5	1.8	0.06	<1	3.0	<0.2
1288320	Soil		8	15	1.61	675	0.003	4	0.24	0.012	0.05	0.2	0.34	3.2	1.2	0.12	<1	2.6	<0.2
1288321	Soil		9	16	3.28	356	0.002	5	0.18	0.008	0.05	0.2	0.64	3.0	1.5	0.14	<1	2.3	<0.2
1288322	Soil		8	9	0.07	142	0.006	1	0.42	0.005	0.04	<0.1	0.04	0.9	0.3	0.07	2	1.3	<0.2
1288323	Soil		7	8	0.03	164	0.002	1	0.40	0.005	0.04	<0.1	<0.01	0.4	0.2	0.07	3	<0.5	<0.2
1288324	Soil		6	8	0.06	656	0.002	1	0.40	0.011	0.04	0.1	0.04	0.6	0.4	0.09	2	1.1	<0.2
1288325	Soil		4	10	0.07	590	0.002	<1	0.36	0.011	0.04	0.1	0.11	0.4	0.4	0.07	2	1.6	<0.2
1288326	Soil		4	8	0.24	248	0.005	2	0.35	0.028	0.03	<0.1	0.14	0.7	0.4	0.06	<1	<0.5	<0.2
1288327	Soil		8	15	0.22	660	0.004	2	0.40	0.011	0.04	0.1	0.33	2.4	0.4	0.12	<1	1.3	<0.2
1288328	Soil		10	15	1.28	525	0.003	4	0.30	0.007	0.05	0.1	0.23	4.0	0.9	0.10	<1	1.9	<0.2
1288329	Soil		9	17	1.69	403	0.003	4	0.28	0.008	0.05	0.2	0.31	3.1	1.1	0.11	<1	2.9	<0.2
1288330	Soil		8	16	3.20	231	0.002	5	0.17	0.007	0.04	0.2	0.55	3.4	1.4	0.12	<1	3.4	<0.2
1288331	Soil		6	9	0.02	227	0.001	2	0.38	0.003	0.04	0.1	0.02	0.8	0.2	0.11	3	0.9	<0.2
1288332	Soil		9	17	0.07	1098	0.003	2	0.61	0.007	0.04	0.1	0.27	2.1	0.5	0.10	1	1.2	<0.2
1288333	Soil		6	21	0.06	541	0.004	3	0.80	0.022	0.04	0.1	2.19	0.9	1.2	0.09	2	3.8	<0.2
1288334	Soil		4	8	0.02	108	0.002	2	0.24	0.005	0.04	0.1	0.03	0.3	<0.1	<0.05	2	0.5	<0.2
1288335	Soil		5	14	0.10	428	0.004	1	0.66	0.015	0.04	<0.1	0.10	1.5	0.2	0.07	3	1.7	<0.2
1288336	Soil		2	7	0.03	137	0.004	<1	0.37	0.020	0.03	<0.1	0.07	0.4	<0.1	<0.05	2	<0.5	<0.2
1288337	Soil		5	20	0.06	194	0.004	2	0.50	0.005	0.05	<0.1	0.09	2.4	0.1	0.06	3	1.1	<0.2
1288338	Soil		4	16	0.04	191	0.002	2	0.49	0.005	0.06	<0.1	0.11	1.8	0.1	0.11	3	1.0	<0.2
1288339	Soil		6	10	0.02	61	0.002	<1	0.32	0.003	0.04	0.1	0.02	1.2	0.1	0.06	2	1.0	<0.2
1288340	Soil		5	12	0.02	175	0.002	1	0.44	0.004	0.06	<0.1	0.06	0.7	0.1	0.09	3	1.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1288341	Soil		6.3	32.2	22.3	71	0.8	23.3	4.7	84	1.91	111.0	3.8	0.5	29	0.1	2.6	0.2	43	0.09	0.042
1288342	Soil		4.1	36.1	21.4	92	0.3	30.7	10.5	169	2.40	56.9	6.0	1.1	23	0.3	1.7	0.2	30	0.07	0.062
1288343	Soil		3.8	26.2	21.4	78	0.3	24.7	8.1	118	2.11	43.1	2.0	0.8	34	0.2	1.5	0.3	35	0.04	0.052
1288344	Soil		12.6	43.3	50.4	56	1.3	19.2	4.0	52	2.08	84.0	5.2	0.5	130	0.3	3.7	0.3	60	0.04	0.117
1288345	Soil		4.1	25.2	22.2	71	0.3	23.0	6.5	138	1.72	21.3	4.7	0.4	33	0.4	1.2	0.3	30	0.05	0.073
1288346	Soil		2.1	13.0	11.2	40	0.3	11.6	3.5	40	0.96	7.5	1.0	0.2	16	0.1	0.6	0.1	19	0.04	0.053
1288347	Soil		1.8	15.7	9.0	76	0.1	18.1	6.6	67	1.47	20.3	0.5	0.4	9	0.1	0.8	0.2	20	0.02	0.039
1288348	Soil		2.6	25.3	17.6	104	0.1	26.4	9.2	112	2.40	27.7	1.2	1.1	18	0.2	1.4	0.3	24	0.02	0.033
1288349	Soil		1.8	14.5	7.0	34	<0.1	7.3	2.3	38	0.86	11.6	1.1	0.3	8	<0.1	0.6	0.2	28	0.01	0.065
1288350	Soil		3.3	36.6	16.5	88	0.3	26.5	6.7	137	2.10	52.5	3.3	0.7	21	0.4	2.2	0.2	32	0.10	0.077
1288531	Soil		17.6	57.7	81.0	91	2.7	12.1	2.2	31	3.99	731.4	157.0	1.9	54	0.5	38.3	4.4	63	0.02	0.130
1288532	Soil		17.0	48.1	83.6	144	3.3	19.0	5.0	103	3.63	724.0	189.9	4.0	82	0.9	47.9	3.1	71	0.05	0.165
1288533	Soil		15.5	44.0	64.5	125	2.8	16.1	5.4	136	3.06	617.7	168.4	3.3	74	0.7	40.5	2.7	61	0.05	0.163
1288534	Soil		8.8	48.1	41.0	102	2.6	24.8	5.7	152	2.43	257.2	77.8	1.6	52	1.2	23.4	1.7	37	0.18	0.103
1288535	Soil		7.2	45.0	28.1	147	2.0	37.8	6.0	166	2.24	115.1	33.0	1.6	53	1.5	21.7	0.7	31	0.36	0.087
1288536	Soil		7.7	37.7	32.2	118	1.5	26.3	4.5	75	2.09	201.2	31.6	2.4	38	1.0	43.8	1.1	28	0.18	0.056
1288537	Soil		7.0	42.6	27.7	119	2.2	26.4	4.3	77	2.25	137.4	42.2	1.5	43	0.9	19.1	0.7	38	0.17	0.091
1288538	Soil		4.2	36.7	33.0	227	0.9	37.0	7.9	110	2.91	22.4	2.8	0.5	31	0.6	2.2	0.3	47	0.02	0.066
1288539	Soil		3.8	50.1	21.7	94	1.3	23.5	5.1	92	1.76	15.4	1.5	0.4	22	0.9	1.6	0.3	42	0.09	0.115
1288540	Soil		4.9	29.7	32.2	80	1.8	19.3	4.6	125	1.77	15.7	1.5	0.5	35	0.3	2.1	0.3	58	0.05	0.081
1288541	Soil		6.3	21.6	83.9	62	2.2	13.9	3.3	56	1.45	17.1	1.7	0.2	108	0.2	2.1	0.3	67	0.03	0.106
1288542	Soil		4.5	16.0	33.1	30	1.7	6.9	1.3	62	0.86	7.5	1.1	0.1	69	0.2	1.4	0.3	36	0.02	0.079
1288543	Soil		3.5	12.4	86.0	36	1.8	7.2	1.7	33	0.88	6.9	0.5	0.7	134	0.2	1.3	0.3	48	0.03	0.085
1288544	Soil		4.0	14.2	15.0	53	1.0	10.4	2.7	42	1.14	8.5	0.9	0.6	15	0.3	1.2	0.2	48	0.01	0.044
1288545	Soil		6.4	41.9	20.3	156	2.6	34.2	6.5	76	2.96	19.5	2.6	1.1	27	0.4	3.1	0.2	70	0.02	0.102
1288546	Soil		1.1	5.8	9.1	25	0.4	6.6	1.2	27	0.38	2.0	2.1	0.2	20	0.4	0.4	<0.1	14	0.11	0.029
1288547	Soil		1.7	13.6	18.3	44	0.3	8.3	2.7	67	0.99	6.7	1.2	0.2	19	0.4	0.6	0.2	31	0.04	0.045
1288548	Soil		1.5	12.9	7.3	46	0.9	13.3	2.4	42	1.13	5.4	3.3	0.3	100	0.5	0.4	0.1	18	0.36	0.061
1288549	Soil		1.4	19.6	8.1	54	2.1	23.9	2.6	87	1.13	4.7	3.6	0.3	106	1.7	0.7	0.1	14	0.41	0.125
1288550	Soil		2.1	40.5	18.3	68	0.5	30.8	6.5	95	1.82	10.7	1.3	1.0	42	2.0	0.8	0.2	39	0.32	0.075

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288341	Soil	5	11	0.07	217	0.003	2	0.37	0.004	0.04	<0.1	0.09	1.3	0.2	<0.05	2	2.6	<0.2
1288342	Soil	6	13	0.10	176	0.002	<1	0.51	0.004	0.05	<0.1	0.07	2.4	0.2	0.06	2	1.0	<0.2
1288343	Soil	5	12	0.06	390	0.003	1	0.44	0.004	0.05	0.1	0.04	1.5	0.2	0.08	2	0.7	<0.2
1288344	Soil	4	13	0.02	722	0.001	1	0.47	0.009	0.11	<0.1	0.15	1.3	0.6	0.25	2	5.2	<0.2
1288345	Soil	5	13	0.06	694	0.002	2	0.57	0.011	0.07	<0.1	0.09	1.5	0.2	0.17	2	1.4	<0.2
1288346	Soil	3	6	0.02	262	0.001	1	0.36	0.011	0.05	<0.1	0.04	0.5	0.1	0.09	2	1.0	<0.2
1288347	Soil	2	5	0.02	194	0.001	3	0.36	0.004	0.03	<0.1	0.01	1.2	<0.1	<0.05	1	<0.5	<0.2
1288348	Soil	4	8	0.07	169	0.002	2	0.45	0.002	0.05	<0.1	0.01	2.1	0.2	<0.05	1	1.2	<0.2
1288349	Soil	4	6	0.02	143	0.016	2	0.50	0.006	0.02	<0.1	<0.01	0.2	<0.1	<0.05	2	<0.5	<0.2
1288350	Soil	5	10	0.10	394	0.003	2	0.45	0.004	0.04	0.1	0.03	1.5	0.2	<0.05	2	1.4	<0.2
1288531	Soil	18	13	0.07	302	0.002	2	0.55	0.004	0.07	1.7	13.89	1.0	2.4	0.09	2	9.1	0.3
1288532	Soil	20	14	0.06	312	0.003	7	0.50	0.008	0.14	1.8	27.58	1.5	2.9	0.24	2	13.2	0.3
1288533	Soil	21	14	0.05	290	0.002	5	0.45	0.006	0.14	1.2	24.53	1.2	2.5	0.22	2	10.2	0.3
1288534	Soil	10	13	0.07	480	0.002	2	0.53	0.005	0.08	0.7	9.31	1.8	1.1	0.12	2	6.9	<0.2
1288535	Soil	8	14	0.07	632	0.003	6	0.42	0.004	0.09	0.2	7.70	2.1	0.4	0.10	1	6.3	<0.2
1288536	Soil	11	11	0.08	434	0.001	3	0.38	0.003	0.06	0.3	12.14	1.8	0.4	0.08	1	7.1	<0.2
1288537	Soil	9	14	0.07	591	0.002	4	0.48	0.005	0.09	0.3	10.60	1.9	0.5	0.09	2	5.3	0.2
1288538	Soil	3	15	0.04	165	0.003	<1	0.54	0.002	0.04	<0.1	0.19	1.6	0.2	<0.05	2	1.8	<0.2
1288539	Soil	2	9	0.01	207	0.002	3	0.34	0.004	0.05	<0.1	0.32	1.7	0.2	<0.05	2	1.3	<0.2
1288540	Soil	3	11	0.02	264	0.003	3	0.31	0.003	0.07	0.1	0.21	1.8	0.2	<0.05	2	1.8	<0.2
1288541	Soil	3	13	0.01	380	0.002	1	0.40	0.003	0.04	0.1	0.12	0.7	0.2	0.07	3	1.1	<0.2
1288542	Soil	4	10	0.01	474	0.002	1	0.44	0.007	0.05	<0.1	0.09	0.3	0.2	0.08	3	3.6	<0.2
1288543	Soil	3	8	0.01	898	0.003	<1	0.40	0.004	0.05	<0.1	0.08	0.8	0.4	0.06	2	4.5	<0.2
1288544	Soil	4	6	0.02	423	0.005	2	0.36	0.005	0.03	0.1	0.11	0.8	0.1	<0.05	2	1.0	<0.2
1288545	Soil	3	11	0.04	866	<0.001	1	0.37	0.002	0.05	<0.1	0.18	3.8	0.4	0.05	1	3.0	<0.2
1288546	Soil	<1	3	0.02	485	0.003	1	0.28	0.014	0.03	<0.1	0.16	0.6	<0.1	<0.05	1	1.3	<0.2
1288547	Soil	5	9	0.07	299	0.002	1	0.46	0.004	0.05	<0.1	0.04	0.6	0.1	<0.05	2	0.7	<0.2
1288548	Soil	2	6	0.06	433	0.002	1	0.50	0.012	0.03	<0.1	0.15	1.1	<0.1	0.06	2	1.2	<0.2
1288549	Soil	3	7	0.06	657	0.002	2	0.51	0.011	0.03	<0.1	0.34	0.8	<0.1	0.09	2	1.9	<0.2
1288550	Soil	4	12	0.05	1485	0.001	<1	0.66	0.003	0.04	<0.1	0.12	2.8	<0.1	<0.05	2	2.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1286371	Soil		6.1	28.2	10.5	327	1.5	49.5	4.9	79	1.95	13.7	1.2	1.4	72	1.3	3.5	0.2	39	0.60	0.168
1286372	Soil		5.7	27.6	15.9	183	1.0	33.5	6.8	200	2.08	15.1	2.5	1.1	69	1.1	2.6	0.2	36	0.45	0.096
1286373	Soil		5.7	17.1	10.7	110	0.8	21.3	3.4	117	1.48	25.1	4.1	0.7	37	0.6	3.4	0.2	67	0.20	0.101
1286374	Soil		9.1	17.8	14.7	115	0.3	22.4	2.8	85	1.03	17.6	1.4	0.5	24	0.7	4.3	0.2	68	0.05	0.041
1286375	Soil		17.1	48.2	15.9	306	2.0	75.2	14.5	1076	2.98	81.3	8.7	1.0	66	5.0	12.9	0.2	78	0.61	0.134
1286376	Soil		16.4	49.5	17.0	645	1.9	198.3	13.0	2069	1.95	92.7	5.9	0.9	66	10.9	20.5	0.2	75	1.05	0.116
1286377	Soil		14.5	38.3	16.2	837	1.2	180.9	12.8	1522	2.15	89.0	4.3	1.2	82	7.4	10.8	0.2	70	1.29	0.119
1286378	Soil		12.4	47.3	22.3	251	1.9	48.2	8.5	304	1.96	34.1	6.6	1.7	61	3.1	9.0	0.2	91	0.48	0.117
1286379	Soil		117.1	200.3	20.7	3112	2.7	416.6	15.3	207	1.94	142.4	<0.5	2.1	329	17.2	54.8	0.2	890	10.53	0.120
1286380	Soil		118.1	159.5	25.6	2403	2.1	310.1	17.7	409	2.36	308.4	<0.5	3.9	236	22.6	39.0	0.2	519	8.98	0.098
1286491	Soil		24.0	107.5	54.1	137	2.2	43.0	4.2	108	3.53	43.3	3.9	0.7	115	1.3	7.8	0.4	235	0.44	0.722
1286492	Soil		18.8	70.4	45.1	210	1.4	57.5	5.4	49	2.86	30.0	3.6	0.7	85	0.7	8.5	0.4	149	0.33	0.509
1286493	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286494	Soil		7.2	69.4	23.1	178	0.5	73.1	20.7	1011	5.47	40.2	5.9	1.9	11	0.6	5.2	0.5	25	0.04	0.130
1286495	Soil		7.8	74.2	21.5	130	0.8	82.0	12.4	288	4.27	25.6	2.8	0.6	19	0.3	2.4	0.3	61	0.20	0.339
1286496	Soil		108.7	167.3	16.3	2323	2.2	324.7	6.2	154	1.42	117.1	1.9	0.9	230	14.8	39.9	0.2	718	8.65	0.113
1286497	Soil		119.7	181.8	17.5	2831	2.6	399.8	7.7	154	1.58	144.8	2.0	1.2	253	17.0	42.9	0.2	772	9.41	0.121
1286498	Soil		103.3	181.9	18.1	2260	2.6	373.4	6.3	149	1.39	132.4	2.5	0.9	288	15.0	42.4	0.2	827	9.43	0.135
1286499	Soil		92.4	205.1	20.1	2370	3.4	330.0	6.2	162	1.27	145.6	4.0	0.8	244	21.8	42.7	0.2	974	8.38	0.144
1286500	Soil		81.4	157.6	16.6	2198	2.3	368.6	8.3	166	1.40	114.8	1.1	1.4	367	15.6	37.4	0.2	939	12.81	0.132
1283391	Soil		8.1	24.6	23.3	78	1.2	21.6	2.3	28	1.06	16.9	1.4	0.2	43	0.3	2.4	0.2	54	0.04	0.101
1283392	Soil		13.0	51.5	19.5	190	0.2	75.5	11.7	276	2.71	50.7	5.2	1.5	24	0.5	4.7	0.3	25	0.22	0.112
1283393	Soil		24.0	34.2	17.3	376	0.3	68.5	5.6	276	1.75	24.7	3.3	1.1	16	2.2	8.2	0.2	80	0.14	0.138
1283394	Soil		10.4	30.1	16.6	146	0.1	49.7	9.5	726	2.46	27.0	1.7	0.6	25	0.8	2.7	0.3	33	0.21	0.170
1283395	Soil		47.6	61.2	26.9	410	0.2	118.7	15.5	197	3.85	54.2	3.4	1.1	39	3.0	9.4	0.4	84	0.19	0.142
1283396	Soil		26.9	19.9	11.1	170	0.2	45.9	4.7	45	1.40	23.0	0.9	0.1	5	0.1	5.6	0.2	116	0.02	0.069
1283397	Soil		39.4	50.2	21.6	438	0.4	109.0	12.3	173	3.43	54.5	2.7	1.4	9	0.9	10.0	0.3	126	0.17	0.113
1283398	Soil		72.5	66.6	11.0	329	0.3	173.1	8.1	203	1.75	46.7	1.3	1.9	188	3.8	8.4	0.1	100	7.23	0.114
1283399	Soil		110.9	77.7	13.0	271	0.2	227.7	11.0	168	2.17	36.6	1.0	3.3	152	2.4	4.8	0.1	42	5.79	0.157
1283400	Soil		73.3	74.3	10.8	274	0.3	188.3	6.9	206	1.68	40.7	1.7	2.6	278	3.6	9.0	0.1	94	9.79	0.102

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1286371	Soil	3	12	0.21	2682	0.001	2	1.00	0.008	0.05	<0.1	0.11	1.7	0.2	<0.05	2	2.7	<0.2
1286372	Soil	3	13	0.17	2042	0.002	<1	0.72	0.007	0.06	0.1	0.13	1.7	0.2	0.08	2	3.0	<0.2
1286373	Soil	5	13	0.07	483	0.002	1	0.46	0.005	0.04	0.1	0.29	0.9	0.2	<0.05	2	1.1	<0.2
1286374	Soil	5	8	0.02	261	0.003	1	0.30	0.003	0.04	0.1	0.08	0.6	0.3	<0.05	2	1.8	<0.2
1286375	Soil	5	15	0.11	1157	0.003	2	0.75	0.011	0.04	0.2	0.85	2.4	0.5	0.08	2	4.4	<0.2
1286376	Soil	5	14	0.15	893	0.003	2	0.77	0.009	0.05	0.2	0.93	2.0	0.5	0.13	2	3.8	<0.2
1286377	Soil	5	14	0.17	982	0.002	2	0.65	0.006	0.05	0.1	0.60	2.1	0.4	0.10	2	2.7	<0.2
1286378	Soil	7	17	0.14	1243	0.006	2	0.67	0.005	0.07	0.2	0.75	2.2	0.4	<0.05	2	2.5	<0.2
1286379	Soil	14	47	1.31	349	0.006	7	0.37	0.007	0.10	0.5	0.68	3.1	6.5	0.07	2	10.9	0.3
1286380	Soil	11	31	1.85	338	0.002	4	0.32	0.005	0.09	0.4	4.62	3.5	2.3	0.06	1	9.3	<0.2
1286491	Soil	24	21	0.05	695	0.004	2	0.68	0.004	0.15	0.3	0.27	0.9	0.7	0.34	2	7.0	0.3
1286492	Soil	21	14	0.03	582	0.005	2	0.43	0.003	0.12	0.2	0.20	0.5	0.6	0.22	2	9.1	0.3
1286493	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1286494	Soil	21	8	0.03	408	0.001	1	0.29	0.002	0.05	<0.1	0.25	4.2	0.2	<0.05	<1	1.6	0.3
1286495	Soil	12	12	0.03	496	0.003	2	0.40	0.004	0.06	<0.1	0.09	1.6	0.2	0.07	1	2.8	<0.2
1286496	Soil	13	36	1.38	368	0.003	6	0.37	0.005	0.10	0.4	0.78	2.3	3.6	0.05	1	7.9	0.2
1286497	Soil	13	38	1.36	328	0.004	6	0.37	0.005	0.10	0.5	1.04	2.5	4.5	0.06	2	7.7	<0.2
1286498	Soil	14	41	1.31	347	0.003	6	0.37	0.006	0.10	0.5	0.93	2.2	4.4	0.06	1	8.0	<0.2
1286499	Soil	14	47	1.38	330	0.003	7	0.42	0.006	0.11	0.5	1.18	2.2	3.1	0.06	2	9.2	0.3
1286500	Soil	13	42	1.46	260	0.005	8	0.36	0.007	0.10	0.5	0.66	2.7	5.0	0.08	2	7.3	<0.2
1283391	Soil	7	8	0.01	150	0.003	1	0.26	0.008	0.06	0.1	0.04	0.2	0.3	0.09	1	2.0	<0.2
1283392	Soil	16	6	0.03	807	0.001	2	0.35	0.002	0.06	<0.1	0.20	2.0	0.2	<0.05	<1	1.9	<0.2
1283393	Soil	12	9	0.04	265	0.002	2	0.30	0.003	0.07	<0.1	0.06	1.4	0.4	<0.05	<1	4.4	<0.2
1283394	Soil	7	9	0.05	647	0.004	2	0.43	0.004	0.07	<0.1	0.03	1.0	0.2	0.06	2	1.2	<0.2
1283395	Soil	8	9	0.05	993	0.002	3	0.35	0.003	0.06	<0.1	0.07	1.7	0.4	0.08	<1	2.4	<0.2
1283396	Soil	5	7	0.02	75	0.001	<1	0.25	0.005	0.03	0.1	0.02	0.2	0.3	<0.05	2	1.3	<0.2
1283397	Soil	10	12	0.08	147	0.002	3	0.34	0.003	0.06	0.1	0.08	1.7	0.4	<0.05	1	2.5	<0.2
1283398	Soil	8	13	2.73	258	0.002	2	0.16	0.004	0.04	0.2	0.65	2.6	1.2	<0.05	<1	2.2	<0.2
1283399	Soil	7	11	1.18	214	0.003	3	0.16	0.003	0.05	0.3	0.29	3.1	1.7	<0.05	<1	2.6	<0.2
1283400	Soil	10	13	3.75	244	0.002	3	0.16	0.006	0.04	0.2	0.42	2.9	1.6	<0.05	<1	1.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1284491	Soil		144.7	45.5	201.0	87	3.5	18.2	1.4	30	3.71	273.1	11.6	2.0	257	0.6	104.7	0.6	562	0.07	0.154
1284492	Soil		17.0	61.0	46.5	296	1.7	53.9	7.4	175	3.10	156.8	18.8	2.9	93	4.6	18.0	0.5	89	0.22	0.149
1284493	Soil		17.6	65.3	39.3	396	1.5	63.5	8.4	205	3.58	237.2	26.4	2.6	80	7.2	20.6	0.6	87	0.23	0.139
1284494	Soil		27.3	23.8	63.2	118	1.1	23.9	2.8	42	1.38	78.3	18.3	1.2	97	0.8	27.3	0.4	134	0.10	0.086
1284495	Soil		14.5	54.1	48.2	259	1.5	55.9	39.4	1089	1.99	88.7	25.6	2.3	72	3.7	16.9	0.5	107	0.14	0.096
1284496	Soil		14.4	31.5	15.9	111	0.6	31.7	3.9	63	0.89	32.7	6.6	0.4	40	1.1	8.9	0.2	65	0.13	0.050
1284497	Soil		38.4	39.2	32.7	251	0.9	72.4	6.2	86	1.77	75.1	12.2	1.2	82	2.1	21.7	0.3	164	0.15	0.083
1284498	Soil		45.7	45.9	33.2	303	1.7	88.1	5.9	77	2.42	92.8	17.0	2.0	68	0.8	25.4	0.4	239	0.07	0.165
1284499	Soil		41.0	107.3	47.2	192	2.3	52.4	5.1	92	1.80	132.5	25.0	3.2	159	2.5	38.8	0.3	169	0.09	0.156
1284500	Soil		27.4	186.6	31.9	266	2.0	85.1	29.7	620	2.29	116.2	20.6	3.8	69	7.1	25.5	0.3	162	0.15	0.229
1287881	Soil		2.7	96.6	29.1	148	1.0	43.0	14.1	453	4.73	17.0	9.2	3.7	36	0.1	1.4	0.4	21	0.02	0.109
1287882	Soil		6.1	99.2	43.4	135	5.7	40.7	29.7	878	5.02	30.7	20.7	3.4	58	0.1	2.1	0.7	66	0.10	0.191
1287883	Soil		1.6	42.0	13.2	67	0.8	22.4	9.4	405	1.81	9.4	4.2	1.3	22	<0.1	0.7	0.2	17	0.02	0.060
1287884	Soil		2.9	35.3	25.7	100	1.9	23.1	6.5	149	2.68	41.0	7.9	2.1	42	0.2	1.7	0.3	26	0.03	0.066
1287885	Soil		1.9	47.1	12.5	67	1.3	20.0	5.6	98	2.32	9.7	5.3	0.5	40	<0.1	0.9	0.2	25	0.02	0.089
1287886	Soil		2.6	21.2	11.6	64	0.4	13.9	3.6	153	2.30	17.7	3.7	0.3	17	0.1	1.1	0.2	30	0.02	0.105
1287887	Soil		2.1	34.6	28.1	82	1.9	20.2	4.5	88	3.23	75.5	13.3	2.1	68	0.2	1.2	0.3	21	0.02	0.108
1287888	Soil		3.0	53.9	20.3	96	0.8	24.7	8.4	185	3.35	25.5	5.1	1.0	37	0.1	1.5	0.3	40	0.07	0.126
1287889	Soil		3.1	49.3	20.3	126	0.9	32.6	8.9	292	3.28	98.3	12.6	2.1	56	0.4	1.9	0.4	35	0.31	0.112
1287890	Soil		3.0	36.7	18.8	98	1.0	22.1	5.2	115	2.82	113.8	10.4	1.3	51	0.3	2.1	0.3	30	0.18	0.087
1287861	Soil		4.1	60.0	148.5	258	0.8	57.8	8.4	188	7.35	1871	1112	3.8	144	3.3	180.3	0.3	26	0.06	0.091
1287862	Soil		3.9	78.6	31.8	252	1.7	88.6	15.8	219	5.42	179.2	4.7	4.6	122	1.1	9.9	0.3	25	0.91	0.121
1287863	Soil		3.4	74.9	26.1	406	1.5	142.9	26.3	252	4.81	52.5	14.6	3.9	87	1.4	2.9	0.3	36	0.76	0.194
1287864	Soil		3.0	43.3	51.7	220	1.0	52.5	10.8	284	4.17	93.0	7.8	3.3	55	0.7	4.2	0.3	24	0.13	0.089
1287865	Soil		2.8	63.5	32.4	201	1.5	83.7	14.8	784	3.36	140.1	95.1	2.4	67	1.0	5.7	0.3	34	0.47	0.104
1287866	Soil		2.9	52.6	45.8	93	2.8	20.9	4.5	107	4.55	45.7	4.4	4.1	68	<0.1	2.8	0.3	27	0.02	0.095
1287867	Soil		2.6	183.5	16.0	146	1.2	47.9	9.9	176	5.48	50.8	9.7	3.9	36	0.5	2.5	0.1	17	0.12	0.070
1287868	Soil		2.9	63.4	29.6	201	1.5	58.7	12.8	313	3.65	98.0	10.4	2.9	70	0.8	4.0	0.3	27	0.37	0.107
1287869	Soil		4.2	70.4	21.1	84	0.7	25.8	5.2	242	3.44	16.7	7.1	2.6	97	0.2	1.0	0.3	29	0.16	0.077
1287870	Soil		3.6	51.7	21.6	96	0.8	25.3	6.6	249	3.41	19.4	6.7	1.9	79	0.2	1.3	0.3	35	0.06	0.097

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284491	Soil	9	37	0.01	826	0.005	2	0.45	0.006	0.22	2.8	1.32	1.3	4.4	0.47	6	31.8	0.6
1284492	Soil	13	15	0.06	556	0.002	5	0.47	0.004	0.09	0.3	4.80	2.7	1.0	0.16	1	5.8	<0.2
1284493	Soil	12	15	0.08	501	0.002	3	0.53	0.004	0.09	0.3	5.28	2.8	1.0	0.16	1	6.4	<0.2
1284494	Soil	11	12	0.02	367	0.003	2	0.33	0.005	0.07	0.8	3.96	0.8	1.3	0.07	3	10.5	0.3
1284495	Soil	14	13	0.05	576	0.002	1	0.73	0.004	0.05	0.6	2.03	1.7	0.9	0.07	2	4.5	<0.2
1284496	Soil	7	8	0.02	347	0.004	<1	0.30	0.008	0.04	0.4	1.31	0.6	0.6	<0.05	2	2.7	<0.2
1284497	Soil	10	15	0.02	418	0.003	2	0.34	0.004	0.06	0.6	2.52	1.0	1.4	0.05	2	6.1	0.2
1284498	Soil	11	18	0.02	251	0.004	1	0.44	0.004	0.08	0.7	2.56	1.6	1.8	0.07	2	7.1	<0.2
1284499	Soil	10	19	0.02	553	0.001	1	0.56	0.002	0.07	0.9	6.89	2.7	2.9	0.12	2	10.2	0.4
1284500	Soil	10	19	0.02	298	0.004	2	1.92	0.003	0.05	0.5	4.40	3.6	1.4	0.05	1	6.9	0.2
1287881	Soil	2	27	0.30	945	0.002	1	0.98	0.006	0.05	<0.1	0.19	5.5	0.1	0.07	2	2.5	<0.2
1287882	Soil	7	56	0.31	877	0.003	2	1.97	0.009	0.13	0.1	0.78	4.8	0.3	<0.05	7	4.8	<0.2
1287883	Soil	2	16	0.12	204	0.001	<1	0.62	0.003	0.04	<0.1	0.14	1.9	<0.1	<0.05	2	1.3	<0.2
1287884	Soil	4	21	0.09	506	<0.001	<1	0.61	0.005	0.09	<0.1	0.21	2.0	0.2	0.14	2	3.6	<0.2
1287885	Soil	2	18	0.07	109	0.004	<1	0.71	0.008	0.03	<0.1	0.12	1.1	0.1	0.06	3	1.3	<0.2
1287886	Soil	4	18	0.07	153	0.004	<1	0.65	0.006	0.05	<0.1	0.07	0.5	0.1	0.07	3	0.8	<0.2
1287887	Soil	2	21	0.05	452	0.001	2	0.65	0.006	0.12	<0.1	0.18	2.0	0.2	0.24	2	2.4	<0.2
1287888	Soil	4	24	0.09	394	0.003	1	0.89	0.005	0.06	0.1	0.09	2.3	0.2	0.08	4	2.2	<0.2
1287889	Soil	5	27	0.20	610	0.003	4	0.92	0.006	0.10	0.1	0.07	1.3	0.2	0.24	3	1.9	<0.2
1287890	Soil	4	25	0.07	477	0.001	2	0.62	0.005	0.10	0.1	0.19	0.8	0.2	0.13	2	2.4	<0.2
1287861	Soil	8	28	0.04	500	0.002	3	0.51	0.006	0.17	0.3	>50	1.2	1.9	0.34	4	36.0	0.2
1287862	Soil	5	23	0.19	383	<0.001	6	0.63	0.008	0.20	<0.1	4.33	3.1	0.5	0.52	2	8.6	<0.2
1287863	Soil	6	28	0.23	406	0.001	2	1.27	0.006	0.11	<0.1	1.72	2.5	0.3	0.21	2	3.5	<0.2
1287864	Soil	9	21	0.16	335	0.001	2	0.67	0.005	0.14	<0.1	0.75	1.4	0.2	0.24	2	4.4	<0.2
1287865	Soil	9	29	0.16	1007	0.001	6	0.78	0.007	0.15	0.1	5.83	2.0	0.3	0.30	2	3.4	<0.2
1287866	Soil	2	27	0.13	338	<0.001	3	0.65	0.010	0.14	<0.1	0.51	1.9	0.3	0.34	2	5.4	<0.2
1287867	Soil	3	65	0.09	94	0.002	3	8.05	0.006	0.08	<0.1	1.16	7.7	0.1	1.83	2	1.9	<0.2
1287868	Soil	5	21	0.16	541	<0.001	3	0.75	0.007	0.13	<0.1	1.83	1.8	0.3	0.28	2	4.3	<0.2
1287869	Soil	3	26	0.18	864	<0.001	3	0.94	0.021	0.10	<0.1	0.35	1.4	<0.1	0.26	2	1.3	<0.2
1287870	Soil	4	23	0.20	682	<0.001	2	1.03	0.013	0.09	<0.1	0.25	1.0	0.1	0.19	3	1.4	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1289041	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1289042	Soil		2.1	65.7	8.9	105	0.6	15.1	6.7	787	1.59	7.0	8.2	0.7	57	2.2	1.2	0.2	29	1.38	0.158
1289043	Soil		4.8	78.5	9.8	115	0.4	25.3	7.9	184	2.50	11.5	10.3	2.7	34	0.8	1.4	0.2	63	0.79	0.103
1289044	Soil		7.0	91.4	13.5	175	0.6	28.4	11.9	256	3.62	13.6	9.2	2.8	36	0.6	2.2	0.2	64	0.20	0.230
1289045	Soil		4.9	84.7	22.2	190	0.5	34.3	13.2	931	3.47	16.3	8.7	0.8	37	1.5	2.3	0.3	56	0.40	0.199
1289046	Soil		3.4	89.2	16.9	143	0.2	34.0	9.4	288	3.91	17.1	5.3	0.9	14	0.5	2.2	0.3	54	0.07	0.092
1289047	Soil		3.5	283.9	48.1	280	0.6	83.9	41.7	1523	7.92	29.2	41.1	3.5	24	0.5	3.3	0.7	69	0.09	0.132
1289048	Soil		4.2	215.8	24.1	199	0.4	55.5	15.0	510	6.00	23.3	26.4	2.6	15	0.3	2.5	0.5	76	0.04	0.109
1289049	Soil		2.1	153.6	27.5	830	1.6	122.9	29.8	747	5.61	21.5	39.1	1.8	11	2.2	2.0	0.3	23	0.03	0.083
1289050	Soil		2.7	56.7	13.8	245	0.4	33.6	6.5	353	2.20	9.6	4.8	0.6	71	9.1	1.5	0.3	60	1.38	0.152
1288481	Soil		9.3	108.0	20.9	516	0.3	59.8	10.1	166	3.86	25.6	4.8	0.3	18	0.9	3.6	0.3	65	0.02	0.107
1288482	Soil		1.6	49.2	10.5	123	0.3	22.8	4.4	104	1.72	12.1	7.7	0.2	23	0.4	1.8	0.2	23	0.16	0.147
1288483	Soil		3.1	81.3	9.8	123	0.4	22.4	7.0	264	1.75	8.5	9.0	0.7	35	0.6	1.6	0.2	32	0.74	0.203
1288484	Soil		4.4	136.7	14.9	244	2.0	37.9	16.4	697	3.56	13.0	17.9	1.3	41	2.3	1.9	0.3	44	0.86	0.276
1288485	Soil		15.4	120.3	29.9	256	2.9	46.5	5.6	128	2.89	36.3	20.1	0.8	155	1.8	9.6	0.3	122	0.59	0.227
1288486	Soil		6.8	97.4	17.0	449	1.1	44.3	10.6	556	5.36	20.1	13.6	2.8	45	2.1	3.5	0.2	62	0.67	0.232
1288487	Soil		2.2	21.0	7.9	67	0.2	10.7	2.5	93	1.26	7.0	1.4	0.3	16	0.3	1.1	0.2	36	0.18	0.108
1288488	Soil		3.9	75.1	11.3	209	0.7	33.7	6.2	224	2.47	12.9	10.7	1.1	41	1.2	2.1	0.2	50	0.59	0.220
1288489	Soil		2.7	64.3	9.3	145	0.7	28.7	5.1	249	2.20	9.8	9.6	1.2	45	1.0	1.6	0.2	39	0.90	0.163
1288490	Soil		7.5	85.5	17.1	238	0.5	42.4	9.5	369	3.38	22.9	9.1	1.1	54	2.2	3.6	0.3	69	0.59	0.213
1288891	Soil		32.5	55.3	18.2	241	0.2	86.8	8.7	168	2.67	28.7	2.4	1.2	16	0.8	3.7	0.2	75	0.09	0.097
1288892	Soil		30.2	63.4	15.6	327	0.4	110.9	10.6	273	2.55	29.4	2.2	3.2	83	2.8	5.8	0.1	71	2.76	0.154
1288893	Soil		8.7	114.9	18.4	343	2.1	144.9	18.8	751	5.65	107.4	64.4	1.6	95	2.9	12.9	0.3	72	0.46	0.175
1288894	Soil		9.6	120.1	18.2	441	2.2	191.5	22.3	794	6.42	152.0	57.4	1.8	97	3.4	16.6	0.3	82	0.32	0.165
1288895	Soil		9.7	126.2	18.4	429	2.1	192.8	22.1	754	6.32	165.3	86.9	1.8	94	3.7	17.7	0.3	83	0.26	0.145
1288896	Soil		5.6	77.1	14.0	240	1.9	125.4	15.4	611	4.54	134.2	33.6	0.6	78	1.8	15.1	0.2	68	0.35	0.120
1288897	Soil		6.4	93.7	27.2	208	1.4	74.5	19.0	692	4.99	52.8	8.3	1.2	47	0.7	8.4	0.3	66	0.05	0.138
1288898	Soil		5.1	74.5	20.7	194	0.8	51.3	13.3	279	4.11	24.0	6.4	0.8	12	0.6	4.1	0.3	44	0.02	0.093
1288899	Soil		5.8	87.6	17.2	200	0.7	57.2	12.9	191	4.39	19.8	7.2	0.2	16	1.5	3.9	0.3	35	0.07	0.106
1288900	Soil		6.1	98.3	18.9	186	1.0	67.3	15.8	280	4.36	22.2	10.0	0.9	23	0.5	3.4	0.3	26	0.21	0.062

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1289041	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1289042	Soil	21	11	0.20	482	0.005	3	0.99	0.014	0.05	<0.1	0.23	0.5	0.2	0.24	3	1.5	<0.2
1289043	Soil	20	23	0.80	401	0.004	4	1.43	0.005	0.15	<0.1	0.26	1.3	0.2	0.11	5	1.0	<0.2
1289044	Soil	13	26	0.84	389	0.007	5	1.64	0.004	0.17	<0.1	0.17	1.2	0.3	0.13	5	1.7	<0.2
1289045	Soil	11	19	0.24	418	0.007	3	1.00	0.006	0.13	0.1	0.12	0.9	0.2	0.13	4	1.5	<0.2
1289046	Soil	10	22	0.16	168	0.009	1	0.78	0.004	0.08	0.1	0.08	0.8	0.1	0.08	4	0.9	<0.2
1289047	Soil	18	42	0.23	487	0.003	1	1.49	0.004	0.11	<0.1	0.11	3.2	0.2	0.12	6	3.3	0.4
1289048	Soil	14	30	0.13	172	0.005	1	1.20	0.003	0.09	0.1	0.06	1.6	0.2	0.06	6	1.6	0.2
1289049	Soil	9	10	0.05	113	0.008	<1	1.13	0.011	0.05	<0.1	0.12	2.3	0.1	0.08	2	1.6	<0.2
1289050	Soil	8	16	0.16	590	0.005	2	0.86	0.006	0.06	0.1	0.10	0.4	0.1	0.23	3	1.1	<0.2
1288481	Soil	8	10	0.04	111	0.005	2	0.43	0.002	0.07	<0.1	0.07	0.2	0.2	0.08	4	2.1	<0.2
1288482	Soil	5	10	0.10	358	0.002	1	0.76	0.010	0.05	<0.1	0.07	0.4	0.1	0.06	2	0.7	<0.2
1288483	Soil	8	8	0.12	497	0.004	2	0.72	0.018	0.06	<0.1	0.23	0.6	0.1	0.14	2	1.4	<0.2
1288484	Soil	12	11	0.14	817	0.002	3	0.70	0.006	0.09	<0.1	0.46	2.3	0.2	0.21	2	1.8	<0.2
1288485	Soil	15	22	0.07	583	0.003	4	0.57	0.007	0.12	<0.1	0.56	1.1	0.6	0.28	3	4.3	<0.2
1288486	Soil	13	16	0.18	461	0.002	3	0.84	0.003	0.10	<0.1	0.66	1.8	0.2	0.11	3	2.4	<0.2
1288487	Soil	5	9	0.06	165	0.003	<1	0.61	0.012	0.04	<0.1	0.02	<0.1	0.1	0.07	3	0.8	<0.2
1288488	Soil	11	15	0.19	475	0.004	2	0.99	0.009	0.08	0.1	0.27	0.8	0.2	0.13	3	1.3	<0.2
1288489	Soil	11	13	0.18	454	0.004	3	0.85	0.011	0.08	<0.1	0.22	0.8	0.1	0.14	2	1.1	<0.2
1288490	Soil	10	17	0.20	471	0.004	3	0.87	0.005	0.13	<0.1	0.17	0.8	0.2	0.16	3	2.4	<0.2
1288891	Soil	12	14	0.05	356	0.001	1	0.54	0.002	0.05	0.1	0.15	0.7	0.4	<0.05	2	1.8	<0.2
1288892	Soil	11	13	1.23	1283	0.003	4	0.32	0.004	0.09	<0.1	0.46	1.4	0.7	0.14	1	1.9	<0.2
1288893	Soil	2	21	0.08	860	<0.001	4	0.46	0.004	0.10	<0.1	0.88	2.3	0.4	0.20	1	7.7	<0.2
1288894	Soil	2	22	0.07	689	<0.001	3	0.52	0.003	0.11	<0.1	1.01	2.6	0.5	0.16	2	8.5	<0.2
1288895	Soil	2	24	0.06	818	0.001	7	0.55	0.003	0.12	<0.1	1.06	6.0	0.5	0.14	1	7.5	<0.2
1288896	Soil	2	20	0.08	582	0.002	6	0.70	0.010	0.09	<0.1	0.58	3.3	0.6	0.15	2	6.6	<0.2
1288897	Soil	3	17	0.05	499	0.004	3	0.66	0.008	0.10	<0.1	0.16	3.4	0.4	0.13	2	3.5	<0.2
1288898	Soil	3	13	0.04	372	0.001	4	0.40	0.003	0.08	<0.1	0.12	2.8	0.2	0.05	1	2.4	<0.2
1288899	Soil	2	11	0.04	298	0.002	4	0.40	0.005	0.08	<0.1	0.12	1.5	0.2	0.07	2	2.0	<0.2
1288900	Soil	3	10	0.08	947	0.002	5	0.38	0.004	0.09	<0.1	0.45	5.5	0.2	0.07	1	1.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1288441	Soil		12.8	30.9	14.5	248	0.3	57.0	9.7	258	2.63	18.5	0.8	1.8	28	1.3	3.2	0.2	76	0.25	0.092
1288442	Soil		6.6	17.4	7.0	133	0.9	29.9	5.3	202	1.29	7.4	2.2	0.4	16	1.0	1.7	<0.1	41	0.17	0.062
1288443	Soil		6.8	17.2	8.5	123	0.2	26.5	5.6	116	1.28	8.7	0.8	0.4	16	0.9	1.6	0.1	42	0.14	0.052
1288444	Soil		8.5	30.5	11.4	208	0.4	41.9	9.3	211	2.19	14.3	1.7	1.3	31	2.3	2.2	0.2	54	0.38	0.110
1288445	Soil		11.6	29.9	11.9	190	0.2	50.5	9.5	248	2.10	16.1	2.0	1.5	34	1.3	2.5	0.2	53	0.50	0.071
1288446	Soil		3.7	33.1	12.1	67	0.4	68.7	6.5	368	5.01	39.8	3.8	0.2	13	0.6	5.7	0.2	79	0.06	0.141
1288447	Soil		4.1	49.8	14.5	73	0.8	61.0	9.6	1214	6.91	50.0	8.9	0.8	24	0.5	5.5	0.2	109	0.34	0.134
1288448	Soil		4.9	72.3	14.1	67	0.9	38.9	9.6	280	3.68	26.4	5.1	0.4	21	0.3	4.9	0.3	75	0.05	0.169
1288449	Soil		8.3	105.0	27.7	257	2.2	47.1	11.0	253	3.86	23.2	4.3	2.3	119	1.6	9.6	0.3	57	0.13	0.135
1288450	Soil		6.7	81.1	26.9	228	2.5	39.5	9.9	143	3.63	17.7	4.6	0.8	66	0.9	6.1	0.3	44	0.04	0.169
1283951	Soil		96.6	109.7	21.2	1451	1.7	228.5	11.9	373	2.67	116.6	2.5	1.3	147	21.6	21.8	0.2	522	3.12	0.162
1283952	Soil		26.8	168.5	11.6	1357	4.9	306.3	10.0	187	2.21	98.8	4.0	2.1	113	11.1	25.8	0.2	312	2.78	0.352
1283953	Soil		103.2	115.0	18.6	1031	4.6	211.9	11.8	271	2.46	127.8	5.1	0.3	32	23.7	73.9	0.3	1157	0.29	0.182
1283954	Soil		5.7	41.4	12.3	94	1.2	20.1	3.7	36	2.45	16.3	4.1	0.7	13	<0.1	1.4	0.2	46	0.02	0.084
1283955	Soil		2.7	27.8	18.0	83	0.8	21.0	4.0	80	2.49	93.9	5.6	1.2	40	0.2	2.5	0.3	39	0.03	0.074
1283956	Soil		3.2	26.2	11.3	75	0.8	18.7	3.7	50	1.87	18.4	1.9	0.8	16	0.1	1.3	0.2	42	0.03	0.052
1283957	Soil		3.1	35.0	13.7	77	1.3	19.6	4.5	137	2.29	24.9	5.1	0.4	24	0.1	1.5	0.2	39	0.04	0.072
1283958	Soil		2.5	36.2	15.7	104	1.6	34.2	6.5	145	2.35	32.6	33.3	1.7	54	0.4	1.9	0.3	36	0.15	0.082
1283959	Soil		1.4	26.3	9.9	94	1.7	33.6	5.1	137	1.73	12.0	12.1	0.9	56	0.4	0.7	0.1	15	0.88	0.090
1283960	Soil		<0.1	3.4	1.5	4	0.3	1.7	0.5	21	0.19	0.6	1.4	<0.1	10	<0.1	<0.1	<0.1	2	0.12	0.032
1283961	Soil		1.3	13.6	4.3	21	1.5	6.4	1.0	38	0.59	4.0	1.8	<0.1	19	0.1	0.4	<0.1	12	0.20	0.070
1283962	Soil		3.8	34.5	15.0	69	1.3	14.6	3.0	83	3.47	26.9	2.6	1.0	19	0.1	1.6	0.3	53	0.03	0.081
1283963	Soil		6.0	27.1	14.4	82	0.3	18.0	3.1	53	1.79	24.0	1.9	0.2	17	<0.1	2.4	0.2	64	0.02	0.059
1283964	Soil		5.0	23.3	11.6	227	1.1	52.5	9.2	556	3.03	22.4	5.4	0.3	32	0.8	2.3	0.2	27	0.20	0.132
1283965	Soil		7.0	20.1	10.2	159	0.9	24.6	8.3	231	2.71	23.6	3.1	0.2	32	0.9	3.2	0.2	32	0.31	0.161
1283966	Soil		16.1	19.6	22.1	84	1.1	19.3	2.8	128	1.65	41.5	10.2	0.4	21	0.5	9.1	0.2	83	0.10	0.087
1283967	Soil		26.8	167.1	10.9	1332	7.7	268.1	15.3	820	2.72	195.4	6.3	3.2	58	30.2	26.0	0.2	360	0.31	0.914
1283968	Soil		74.4	75.1	19.9	477	0.2	151.0	10.3	165	3.74	63.3	3.4	0.9	15	1.8	9.0	0.2	195	0.08	0.130
1283969	Soil		4.5	51.1	16.0	64	0.1	53.2	11.9	497	7.64	75.7	1.2	1.8	4	0.1	2.0	0.4	19	0.03	0.098
1283970	Soil		33.5	95.6	15.2	337	1.3	120.7	10.1	206	2.67	68.8	1.9	3.0	81	1.6	9.5	0.2	75	3.02	0.097

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1288441	Soil	9	22	0.18	1451	0.004	4	0.89	0.005	0.06	<0.1	0.12	3.0	0.2	<0.05	2	1.3	<0.2
1288442	Soil	5	11	0.06	956	0.003	2	0.70	0.018	0.05	<0.1	0.20	1.5	0.2	0.05	2	1.0	<0.2
1288443	Soil	5	9	0.06	945	0.002	3	0.75	0.018	0.04	<0.1	0.07	1.2	0.2	<0.05	2	0.7	<0.2
1288444	Soil	7	22	0.20	1221	0.004	2	0.96	0.005	0.05	<0.1	0.12	3.0	0.2	<0.05	3	1.3	<0.2
1288445	Soil	6	16	0.22	732	0.002	2	0.77	0.006	0.05	<0.1	0.12	2.2	0.2	<0.05	2	0.9	<0.2
1288446	Soil	6	23	0.06	171	0.006	2	0.45	0.003	0.05	0.1	0.15	0.8	0.2	0.11	3	1.6	<0.2
1288447	Soil	6	30	0.17	466	0.005	3	0.79	0.005	0.06	0.1	0.13	3.0	0.2	0.06	3	2.1	<0.2
1288448	Soil	3	21	0.05	437	0.003	4	0.63	0.005	0.10	<0.1	0.09	4.1	0.3	0.15	2	3.4	<0.2
1288449	Soil	1	11	0.03	505	<0.001	1	0.35	0.005	0.13	<0.1	0.19	4.8	0.4	0.24	1	6.1	<0.2
1288450	Soil	2	10	0.02	832	0.001	2	0.39	0.005	0.11	<0.1	0.29	3.7	0.3	0.21	1	6.0	<0.2
1283951	Soil	20	45	1.30	720	0.003	4	0.58	0.005	0.09	0.7	0.84	2.9	1.0	0.06	1	29.4	<0.2
1283952	Soil	18	128	1.18	616	0.005	9	0.69	0.004	0.14	0.3	1.92	5.2	1.5	<0.05	2	16.2	0.3
1283953	Soil	24	69	0.09	713	0.007	8	0.74	0.004	0.15	0.7	1.99	1.4	4.3	0.08	4	17.9	0.3
1283954	Soil	3	28	0.03	485	0.002	4	0.63	0.005	0.08	<0.1	0.13	2.0	0.1	0.08	3	5.2	<0.2
1283955	Soil	6	18	0.05	374	0.002	4	0.72	0.007	0.09	<0.1	0.15	1.5	0.1	0.13	3	2.5	<0.2
1283956	Soil	8	15	0.03	228	0.004	3	0.42	0.004	0.07	0.1	0.08	1.2	<0.1	0.06	3	2.0	<0.2
1283957	Soil	7	19	0.09	235	0.006	3	0.71	0.007	0.07	0.1	0.16	1.0	0.1	0.08	3	1.9	<0.2
1283958	Soil	9	23	0.10	647	0.003	5	0.96	0.007	0.10	<0.1	0.52	3.1	0.2	0.09	3	1.7	<0.2
1283959	Soil	5	14	0.09	568	0.003	3	0.64	0.010	0.06	<0.1	0.33	2.4	<0.1	0.09	2	1.9	<0.2
1283960	Soil	1	2	0.02	105	0.008	1	0.21	0.055	0.03	<0.1	0.06	0.3	<0.1	<0.05	<1	<0.5	<0.2
1283961	Soil	2	6	0.02	422	0.002	2	0.41	0.022	0.03	<0.1	0.12	0.4	<0.1	0.06	1	0.7	<0.2
1283962	Soil	5	17	0.04	201	0.004	2	0.69	0.004	0.06	<0.1	0.12	1.4	0.1	<0.05	4	1.8	<0.2
1283963	Soil	5	10	0.02	260	0.002	2	0.35	0.003	0.05	<0.1	0.06	0.7	0.2	<0.05	2	1.9	<0.2
1283964	Soil	3	15	0.05	464	0.003	3	0.57	0.011	0.06	<0.1	0.32	0.5	0.2	0.07	2	2.4	<0.2
1283965	Soil	4	12	0.06	558	0.004	4	0.48	0.009	0.07	<0.1	0.18	0.7	0.9	0.12	2	4.4	<0.2
1283966	Soil	6	10	0.07	402	0.004	3	0.44	0.005	0.09	0.1	1.36	0.8	0.8	0.17	2	4.5	<0.2
1283967	Soil	18	216	0.05	642	0.006	3	4.07	0.003	0.06	0.2	1.40	5.9	1.4	0.08	2	9.5	<0.2
1283968	Soil	15	19	0.07	422	0.003	5	0.58	0.003	0.08	0.3	0.30	1.6	1.4	<0.05	2	2.9	<0.2
1283969	Soil	21	6	0.04	114	0.003	4	0.49	0.005	0.08	<0.1	0.09	2.1	0.3	<0.05	2	1.2	<0.2
1283970	Soil	15	14	1.35	650	0.002	6	0.33	0.004	0.08	0.1	2.78	3.9	0.8	<0.05	<1	3.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1283971	Soil		9.5	70.6	25.7	158	2.0	75.6	13.8	238	3.96	53.8	3.9	4.6	65	0.6	4.0	0.4	24	0.76	0.111
1283972	Soil		4.7	42.9	15.3	157	1.5	45.5	8.3	90	2.64	35.7	4.5	0.3	28	0.3	2.5	0.3	25	0.09	0.158
1283973	Soil		12.0	105.2	14.1	307	0.9	331.7	52.1	969	6.36	197.0	1.9	9.6	193	3.0	6.9	0.2	126	1.65	0.305
1283974	Soil		19.0	161.3	18.8	251	0.7	646.7	108.0	1462	10.38	1003	7.6	14.2	435	1.8	16.5	0.1	217	4.51	0.461
1283975	Soil		16.3	111.3	19.4	320	0.5	458.1	66.6	707	7.09	1597	9.5	7.6	344	2.5	16.4	<0.1	232	3.91	0.392
1283976	Soil		121.9	99.4	14.4	1137	1.8	436.7	26.4	296	3.70	235.8	2.8	5.1	157	9.8	24.6	0.2	747	2.08	0.192
1283977	Soil		177.4	154.1	16.3	3418	3.3	508.1	11.1	201	2.48	194.1	3.2	3.9	129	45.3	56.6	0.2	1146	2.47	0.151
1283978	Soil		12.7	73.5	17.5	151	1.2	51.4	8.8	361	2.52	34.2	6.2	0.5	68	0.8	4.9	0.3	69	0.24	0.261
1283979	Soil		13.8	88.2	19.0	168	1.3	58.5	8.7	357	2.63	30.4	6.5	0.6	75	0.9	5.2	0.3	94	0.18	0.232
1283980	Soil		71.5	76.4	21.4	1110	1.4	168.7	9.8	171	3.19	73.9	4.8	1.9	71	10.7	25.6	0.2	302	1.26	0.123
1283981	Soil		61.4	80.6	18.1	492	1.2	150.6	10.4	215	3.12	48.2	5.8	1.2	66	4.2	12.5	0.2	153	0.65	0.135
1283982	Soil		23.1	34.9	8.6	167	0.4	66.3	4.3	111	1.20	12.5	1.3	0.2	32	2.3	3.1	0.1	39	0.52	0.072
1283983	Soil		55.1	75.9	20.8	432	0.8	164.2	14.7	580	3.13	30.8	4.1	1.1	61	4.3	6.6	0.3	82	2.39	0.107
1283984	Soil		5.7	47.0	18.6	129	0.3	48.4	15.3	548	3.71	23.2	2.1	0.4	10	0.4	4.1	0.3	37	0.07	0.108
1283985	Soil		7.6	177.0	43.4	334	1.3	330.3	87.7	3876	7.11	43.7	5.8	2.3	23	2.5	5.2	0.5	56	0.09	0.134
1283986	Soil		7.1	52.4	33.0	62	0.7	30.2	7.6	215	4.38	24.5	5.5	1.1	40	0.1	4.3	0.3	53	0.02	0.095
1283987	Soil		2.5	21.3	10.0	32	0.4	13.1	3.4	187	1.23	6.0	1.8	0.2	12	<0.1	1.1	0.1	23	0.03	0.088
1283988	Soil		4.9	27.1	20.6	71	0.3	22.4	5.9	192	2.44	15.8	1.0	0.3	19	0.1	2.2	0.3	45	0.03	0.083
1283989	Soil		4.1	24.1	14.2	23	1.4	8.5	1.8	51	1.39	9.7	2.8	<0.1	17	<0.1	2.2	0.2	29	0.02	0.067
1283990	Soil		4.8	63.7	31.5	88	0.6	29.0	14.7	372	3.21	26.4	5.1	0.9	61	0.6	2.0	0.3	40	0.06	0.118
1284261	Soil		1.5	33.5	12.3	198	1.0	50.5	7.3	236	1.92	32.0	14.2	0.7	112	1.4	2.4	0.2	38	2.35	0.184
1284262	Soil		1.5	31.9	10.5	90	1.0	33.4	5.2	88	1.92	131.4	57.6	1.1	58	0.3	3.9	0.2	23	0.46	0.060
1284263	Soil		1.2	19.5	6.1	43	0.8	14.2	2.2	46	1.23	28.7	14.2	0.3	71	0.4	1.3	0.2	19	1.44	0.169
1284264	Soil		3.4	43.7	21.9	160	2.3	62.4	10.4	356	3.63	110.4	41.4	2.4	135	0.5	3.9	0.3	35	0.52	0.130
1284265	Soil		2.0	38.7	17.7	146	1.9	38.4	5.9	323	2.34	106.9	43.2	0.8	150	0.8	3.9	0.2	35	0.40	0.136
1284266	Soil		2.1	53.3	21.1	180	1.7	61.6	8.7	190	2.90	128.5	35.1	1.9	151	0.7	4.8	0.3	33	0.47	0.129
1284267	Soil		1.1	19.5	12.3	68	0.7	21.7	4.3	124	1.30	52.1	16.4	0.2	66	0.2	2.1	0.2	18	0.15	0.085
1284268	Soil		1.4	30.6	9.1	69	2.0	21.4	4.1	85	1.66	17.8	7.6	0.4	40	0.1	1.1	0.1	18	0.02	0.072
1284269	Soil		1.4	11.8	8.9	34	0.8	9.5	2.5	92	1.87	10.9	4.2	0.3	14	<0.1	0.7	0.1	20	0.04	0.078
1284270	Soil		2.2	24.9	12.4	59	2.2	13.8	3.0	106	2.68	14.9	2.9	0.8	42	0.2	1.0	0.2	40	0.04	0.094

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1283971	Soil	23	8	0.24	2179	0.003	7	0.41	0.003	0.11	<0.1	1.67	5.2	0.2	0.07	<1	3.4	<0.2
1283972	Soil	8	10	0.05	1292	0.002	3	0.54	0.011	0.06	<0.1	0.70	1.0	0.1	0.13	1	1.6	<0.2
1283973	Soil	35	102	0.58	2207	0.003	10	0.72	0.004	0.13	<0.1	1.32	14.9	0.3	0.13	2	3.3	<0.2
1283974	Soil	59	175	2.24	2212	0.006	17	1.02	0.007	0.19	0.2	4.69	25.4	0.9	0.28	3	4.2	<0.2
1283975	Soil	56	212	3.03	1331	0.004	14	1.50	0.008	0.10	0.2	1.69	16.1	0.6	0.22	5	3.4	<0.2
1283976	Soil	33	78	0.83	5849	0.053	10	0.90	0.006	0.18	0.6	2.65	7.9	2.5	0.13	3	11.2	0.3
1283977	Soil	18	65	1.10	2281	0.038	14	0.64	0.006	0.18	0.7	4.66	5.4	5.4	0.11	3	21.8	0.3
1283978	Soil	22	13	0.08	557	0.004	3	0.51	0.007	0.17	0.3	0.52	1.7	0.7	0.29	1	2.6	<0.2
1283979	Soil	22	14	0.06	600	0.003	4	0.56	0.005	0.15	0.2	0.59	1.4	0.5	0.18	1	4.2	<0.2
1283980	Soil	11	20	0.47	489	0.003	6	0.52	0.007	0.10	0.2	1.82	4.1	1.1	0.10	2	6.0	<0.2
1283981	Soil	9	19	0.11	825	0.002	3	0.70	0.008	0.08	0.2	0.81	3.5	1.1	0.15	2	5.5	<0.2
1283982	Soil	4	7	0.12	194	0.004	2	0.31	0.033	0.06	<0.1	0.23	0.8	0.4	0.06	1	1.3	<0.2
1283983	Soil	8	16	1.22	700	0.003	4	0.55	0.015	0.08	0.2	0.40	3.3	0.9	0.07	2	3.2	<0.2
1283984	Soil	3	11	0.05	123	0.004	2	0.57	0.015	0.08	<0.1	0.07	1.3	0.2	0.10	3	2.0	<0.2
1283985	Soil	6	23	0.15	724	0.004	3	1.42	0.009	0.10	<0.1	0.16	6.0	0.5	0.07	4	2.5	0.2
1283986	Soil	6	17	0.08	340	0.002	1	0.67	0.005	0.08	<0.1	0.06	1.8	0.3	0.13	3	4.0	<0.2
1283987	Soil	2	7	0.03	139	0.003	2	0.48	0.022	0.05	<0.1	0.03	0.7	0.1	0.09	2	1.1	<0.2
1283988	Soil	6	12	0.06	237	0.005	<1	0.60	0.009	0.08	<0.1	0.04	0.6	0.2	0.11	4	1.4	<0.2
1283989	Soil	2	7	0.02	112	0.004	2	0.40	0.017	0.05	<0.1	0.07	0.5	0.2	0.08	2	1.3	<0.2
1283990	Soil	5	15	0.06	1771	0.001	<1	0.62	0.009	0.07	<0.1	0.16	5.2	0.5	0.16	2	1.7	<0.2
1284261	Soil	11	23	0.11	723	0.003	8	0.87	0.012	0.09	<0.1	0.91	2.4	0.2	0.23	2	3.1	<0.2
1284262	Soil	6	18	0.09	803	<0.001	2	0.66	0.005	0.08	<0.1	5.26	2.6	0.1	0.08	2	2.8	<0.2
1284263	Soil	3	13	0.08	1031	0.002	4	0.87	0.016	0.05	<0.1	1.20	1.1	0.1	0.19	2	3.0	<0.2
1284264	Soil	9	26	0.10	893	0.002	5	0.81	0.006	0.16	<0.1	3.80	4.2	0.5	0.17	2	4.3	<0.2
1284265	Soil	7	23	0.05	897	0.001	3	0.74	0.009	0.11	0.1	2.28	2.4	0.4	0.15	2	3.1	<0.2
1284266	Soil	8	24	0.07	829	0.002	4	0.84	0.006	0.13	0.1	1.67	4.2	0.4	0.13	2	2.9	<0.2
1284267	Soil	5	10	0.03	429	0.002	2	0.58	0.019	0.08	<0.1	0.67	1.0	0.3	<0.05	2	1.3	<0.2
1284268	Soil	3	13	0.08	163	0.003	2	0.67	0.019	0.05	<0.1	0.78	0.7	0.2	<0.05	2	1.0	<0.2
1284269	Soil	2	14	0.04	107	0.005	1	0.57	0.017	0.05	<0.1	0.16	0.8	0.1	<0.05	2	0.7	<0.2
1284270	Soil	4	19	0.06	252	0.003	3	0.75	0.007	0.09	<0.1	0.16	1.2	0.2	0.06	4	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1284251	Soil		13.6	52.6	28.6	136	2.0	33.5	6.3	183	2.62	86.4	7.2	1.4	58	1.5	10.7	0.3	87	0.07	0.139
1284252	Soil		2.1	44.0	19.3	130	1.1	34.9	5.6	70	2.89	100.1	8.4	1.1	98	0.3	2.2	0.2	25	0.14	0.083
1284253	Soil		2.2	43.6	12.3	103	1.4	32.1	5.0	78	2.10	24.1	9.8	0.6	49	0.4	1.3	0.2	23	0.35	0.090
1284254	Soil		7.1	93.8	29.8	260	2.3	72.7	10.7	193	4.38	84.6	32.8	2.6	96	1.1	6.5	0.3	49	0.22	0.118
1284255	Soil		3.2	38.6	14.8	149	0.7	35.3	7.4	134	3.32	47.7	6.0	1.0	37	0.5	2.1	0.3	34	0.06	0.076
1284256	Soil		2.1	16.5	10.3	49	0.9	14.5	2.4	33	1.50	24.7	6.9	0.4	30	0.1	1.1	0.2	26	0.23	0.084
1284257	Soil		1.6	26.7	8.9	70	1.0	27.7	3.7	110	1.47	34.2	9.5	0.6	52	0.3	1.4	0.2	18	0.69	0.072
1284258	Soil		2.7	38.0	9.4	108	1.4	29.1	3.2	68	1.78	38.1	6.8	0.6	66	0.4	1.8	0.2	20	0.92	0.082
1284259	Soil		7.1	33.1	14.5	146	0.5	48.2	5.4	84	2.63	55.9	5.3	0.7	35	0.5	2.9	0.2	44	0.29	0.074
1284260	Soil		3.8	56.8	24.4	237	1.2	77.6	14.8	283	3.74	103.2	18.7	2.5	91	0.7	3.8	0.3	31	0.20	0.123
1287081	Soil		35.4	29.7	10.5	854	0.4	102.5	6.3	350	2.07	73.7	11.7	0.6	40	9.3	10.8	0.2	330	0.40	0.128
1287082	Soil		17.9	21.1	9.5	878	0.8	82.6	4.2	312	1.90	59.6	13.4	0.6	50	3.9	5.6	0.2	180	0.59	0.141
1287083	Soil		8.0	6.9	5.8	92	0.3	14.7	1.5	24	0.58	13.2	1.1	0.2	19	0.3	1.2	0.1	94	0.17	0.060
1287084	Soil		41.4	35.3	12.3	386	0.3	97.4	7.8	75	2.20	50.4	2.7	0.5	15	1.3	6.8	0.2	217	0.07	0.093
1287085	Soil		20.7	21.4	10.0	144	0.6	45.7	4.5	87	1.50	30.5	2.7	0.2	13	0.3	3.0	0.2	85	0.09	0.054
1287086	Soil		22.2	18.2	8.1	265	0.7	56.4	5.8	60	1.85	58.0	<0.5	0.3	4	0.1	3.8	0.2	58	0.02	0.057
1287087	Soil		60.7	24.9	9.4	202	<0.1	120.6	5.9	90	1.97	38.9	1.7	0.8	4	0.2	4.5	0.1	133	0.02	0.053
1287088	Soil		43.6	31.5	13.7	340	0.1	145.6	10.2	122	3.54	48.7	2.4	1.7	7	0.4	5.8	0.2	233	0.03	0.043
1287089	Soil		122.1	37.9	12.2	628	0.4	166.9	3.0	27	1.56	56.7	1.2	0.3	6	0.4	21.4	0.2	962	0.02	0.044
1287090	Soil		106.9	80.3	15.2	370	1.4	88.3	5.2	87	2.40	76.2	6.0	0.8	96	2.7	31.6	0.2	282	0.06	0.094
1287091	Soil		3.3	6.8	8.1	14	0.2	3.4	0.3	5	0.15	4.5	10.5	0.5	3	0.1	1.7	0.1	31	0.01	0.027
1287092	Soil		13.5	7.8	26.8	69	0.4	13.3	0.7	7	0.40	11.3	29.2	0.7	8	<0.1	3.5	0.1	97	<0.01	0.017
1287093	Soil		16.6	8.5	19.3	82	0.5	34.5	1.0	8	0.43	14.8	7.9	0.4	18	0.1	3.7	0.1	135	0.01	0.035
1287094	Soil		3.4	15.8	13.4	21	0.3	5.0	0.9	17	1.02	64.9	4.4	0.3	50	0.1	2.3	0.1	37	0.05	0.077
1287095	Soil		7.2	61.9	22.0	83	0.8	30.3	7.7	201	2.37	61.0	2.5	0.3	44	0.3	3.4	0.4	60	0.04	0.126
1287096	Soil		9.5	94.3	22.8	159	2.0	50.7	14.8	236	4.30	35.4	3.2	0.7	25	0.3	3.5	0.4	68	0.02	0.146
1287097	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287098	Soil		11.5	21.4	26.8	78	0.5	16.2	2.4	41	1.52	37.1	8.7	0.4	33	0.2	5.6	0.3	79	0.02	0.082
1287099	Soil		30.5	93.0	67.4	60	3.8	12.9	1.4	44	3.42	274.6	26.4	2.2	175	0.9	18.7	0.5	205	0.22	0.831
1287100	Soil		8.0	84.1	8.9	160	1.0	27.0	6.1	118	2.89	38.3	8.4	1.7	14	1.4	6.2	<0.1	54	0.07	0.059

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284251	Soil	5	16	0.05	1559	0.001	3	0.68	0.005	0.11	<0.1	1.91	3.0	0.9	0.13	2	7.4	<0.2
1284252	Soil	4	18	0.04	675	<0.001	2	0.69	0.011	0.14	<0.1	0.42	2.4	0.1	0.19	2	4.0	<0.2
1284253	Soil	4	18	0.08	1004	0.002	4	0.98	0.021	0.08	<0.1	0.64	3.0	0.2	0.10	3	3.3	<0.2
1284254	Soil	6	20	0.11	1171	0.001	3	0.75	0.005	0.08	<0.1	4.33	7.6	0.7	0.06	2	5.8	<0.2
1284255	Soil	4	16	0.06	698	0.001	3	0.63	0.007	0.08	<0.1	0.10	2.0	0.1	0.07	2	2.8	<0.2
1284256	Soil	3	11	0.05	394	0.001	2	0.66	0.015	0.05	<0.1	0.34	1.1	0.2	0.07	2	0.9	<0.2
1284257	Soil	4	11	0.05	609	0.002	3	0.62	0.014	0.05	<0.1	0.63	1.9	<0.1	0.08	2	1.3	<0.2
1284258	Soil	3	12	0.06	475	0.002	4	0.55	0.007	0.05	<0.1	0.56	2.1	<0.1	0.11	1	1.8	<0.2
1284259	Soil	4	17	0.14	495	0.003	2	0.70	0.006	0.06	<0.1	0.43	2.0	0.2	<0.05	2	1.0	<0.2
1284260	Soil	12	19	0.09	1059	0.003	3	0.83	0.011	0.10	0.1	1.28	3.5	0.2	0.14	2	1.9	<0.2
1287081	Soil	11	29	0.10	424	0.005	4	0.58	0.005	0.10	0.2	1.36	1.4	1.2	0.07	2	2.8	<0.2
1287082	Soil	9	21	0.12	296	0.006	5	0.77	0.014	0.08	0.1	1.95	1.9	1.3	0.08	2	2.0	<0.2
1287083	Soil	10	11	0.05	196	0.004	3	0.57	0.011	0.05	<0.1	0.09	0.2	0.5	<0.05	3	0.7	<0.2
1287084	Soil	13	21	0.06	420	0.005	4	0.48	0.003	0.08	0.2	0.20	0.8	0.8	<0.05	2	2.3	<0.2
1287085	Soil	10	11	0.05	143	0.007	2	0.49	0.008	0.05	0.1	0.23	0.4	0.5	<0.05	2	1.2	<0.2
1287086	Soil	17	8	0.03	89	0.003	4	0.36	0.005	0.06	0.1	0.05	0.6	0.3	<0.05	2	0.8	<0.2
1287087	Soil	13	15	0.08	102	0.004	3	0.59	0.002	0.07	0.3	0.23	0.9	1.1	<0.05	2	1.3	<0.2
1287088	Soil	15	22	0.10	220	0.005	3	1.00	0.002	0.08	0.2	0.50	1.4	1.0	<0.05	3	2.0	<0.2
1287089	Soil	28	42	0.06	167	0.006	7	0.52	0.002	0.11	0.4	0.20	0.6	3.4	<0.05	3	4.6	<0.2
1287090	Soil	14	20	0.05	607	0.006	3	0.41	0.003	0.11	0.4	0.87	1.4	2.6	0.19	2	9.9	0.4
1287091	Soil	12	5	0.02	135	0.002	4	0.28	0.003	0.05	<0.1	1.56	0.6	0.6	<0.05	2	<0.5	<0.2
1287092	Soil	10	7	0.01	82	0.001	3	0.25	0.002	0.05	<0.1	3.86	0.4	0.5	<0.05	2	1.0	<0.2
1287093	Soil	10	9	0.02	125	0.002	5	0.35	0.003	0.07	0.1	3.88	0.7	0.7	<0.05	2	1.0	<0.2
1287094	Soil	3	10	0.02	371	0.006	1	0.57	0.017	0.04	<0.1	0.18	0.6	0.3	0.07	2	2.0	<0.2
1287095	Soil	3	12	0.02	185	0.002	4	0.43	0.004	0.08	<0.1	0.25	1.1	0.5	0.06	3	1.7	<0.2
1287096	Soil	4	14	0.03	135	0.004	3	0.47	0.003	0.08	0.1	0.20	2.7	0.5	0.08	2	2.4	<0.2
1287097	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287098	Soil	4	8	0.01	218	0.005	2	0.25	0.005	0.07	0.2	0.29	0.7	0.5	0.07	2	4.4	<0.2
1287099	Soil	7	58	0.02	745	0.007	3	0.74	0.006	0.12	0.5	>50	6.8	2.0	0.22	7	13.3	0.4
1287100	Soil	5	9	0.03	280	0.002	3	0.48	0.003	0.03	0.2	1.30	1.8	0.4	<0.05	<1	2.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1287151	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287152	Soil		9.2	129.7	14.4	183	2.2	56.2	5.0	120	2.18	57.5	15.0	1.0	37	3.2	5.5	0.2	78	0.18	0.126
1287153	Soil		6.5	167.6	17.1	245	1.9	68.5	30.9	1150	2.08	436.8	16.2	1.5	27	2.6	7.8	0.3	46	0.09	0.103
1287154	Soil		10.0	77.8	23.0	297	1.4	60.1	43.9	1169	2.65	179.2	14.7	2.2	48	2.5	8.7	0.4	87	0.14	0.093
1287155	Soil		11.5	178.9	26.3	287	2.0	64.9	22.7	672	2.93	416.6	18.6	2.2	45	2.0	10.4	0.5	85	0.08	0.105
1287156	Soil		11.9	58.2	22.1	235	2.3	51.4	18.1	671	2.86	210.3	19.4	1.2	47	2.4	8.8	1.0	96	0.12	0.097
1287157	Soil		18.1	75.4	25.5	995	1.4	207.1	87.9	2888	9.41	376.4	12.6	2.8	47	3.9	12.4	0.6	77	0.16	0.093
1287158	Soil		16.5	67.7	22.2	1097	1.6	144.7	79.3	2630	10.52	218.4	19.6	2.9	62	8.3	11.6	0.8	97	0.23	0.103
1287159	Soil		17.2	73.7	24.0	777	1.6	103.5	45.3	1189	7.12	242.4	17.9	2.8	53	7.7	12.3	0.5	97	0.27	0.093
1287160	Soil		9.7	30.8	23.9	205	1.3	34.2	5.2	119	2.17	78.4	13.5	2.0	40	0.7	6.9	0.3	91	0.15	0.094
1287291	Soil		11.5	55.7	14.0	209	0.8	44.9	5.2	109	1.70	29.5	4.6	1.0	77	2.8	6.9	0.2	118	0.19	0.134
1287292	Soil		9.7	54.6	14.0	320	1.4	71.2	5.9	125	2.13	29.6	12.0	0.8	75	2.3	6.2	0.2	103	0.52	0.126
1287293	Soil		14.9	58.6	15.9	312	1.5	65.8	5.6	116	2.44	37.9	10.8	1.0	65	2.1	8.4	0.2	132	0.23	0.156
1287294	Soil		19.7	61.0	19.5	324	1.1	62.9	9.0	221	3.37	57.6	9.9	2.0	78	1.8	11.6	0.3	199	0.44	0.344
1287295	Soil		12.6	75.3	17.8	267	0.9	68.7	6.8	117	2.33	41.8	8.6	2.4	77	1.5	7.4	0.2	103	0.30	0.113
1287296	Soil		15.0	48.6	30.8	208	1.3	43.7	7.6	243	2.76	243.6	58.2	1.5	48	1.3	15.4	0.9	79	0.21	0.124
1287297	Soil		5.5	38.3	17.3	156	1.1	46.6	5.9	204	1.58	79.8	37.1	1.2	35	1.9	6.5	0.5	36	0.41	0.062
1287298	Soil		74.1	36.9	16.1	484	0.2	212.2	9.1	56	2.57	40.8	2.6	1.5	43	0.9	9.5	0.2	103	0.27	0.120
1287299	Soil		50.7	28.9	9.0	517	0.2	192.6	11.0	236	2.54	46.9	1.9	0.6	12	1.3	7.6	0.2	89	0.12	0.072
1287300	Soil		53.1	66.3	15.3	867	0.5	246.2	17.6	299	3.74	68.6	5.0	2.9	14	3.8	10.3	0.3	139	0.07	0.076
1287381	Soil		21.6	55.5	26.3	232	1.2	68.8	5.7	70	5.67	83.3	1.5	0.8	98	0.5	4.7	0.3	92	0.09	0.178
1287382	Soil		5.6	61.6	8.5	105	0.6	42.4	3.6	110	1.59	23.0	1.5	0.2	40	0.6	1.8	0.1	56	0.31	0.142
1287383	Soil		21.9	38.2	10.3	179	1.5	58.0	4.9	268	1.61	36.2	1.6	0.2	46	2.7	4.5	0.1	93	0.21	0.140
1287384	Soil		4.4	376.8	10.4	234	0.7	174.9	18.7	698	8.64	36.0	1.4	1.6	159	2.6	2.5	0.2	49	2.43	0.094
1287385	Soil		7.1	310.4	11.9	241	0.3	114.2	14.8	803	7.18	27.3	1.4	1.6	16	1.3	3.1	0.1	58	0.14	0.172
1287386	Soil		20.0	197.1	49.7	1016	1.4	316.4	20.8	676	5.62	81.3	5.9	2.2	40	8.7	7.8	0.2	110	1.19	0.312
1287387	Soil		24.9	84.0	14.2	646	3.0	170.4	8.0	293	2.47	65.7	2.5	1.1	63	6.6	6.4	0.2	112	0.54	0.121
1287388	Soil		39.0	155.9	40.9	539	4.1	179.4	13.0	437	3.54	86.5	3.5	1.0	95	3.8	12.0	0.3	211	0.76	0.455
1287389	Soil		8.5	149.6	27.2	681	2.2	210.4	16.9	222	2.82	40.2	1.6	1.5	115	2.8	5.3	0.4	103	0.87	0.341
1287390	Soil		11.4	108.6	22.6	548	2.4	188.0	12.4	83	3.52	80.6	1.8	2.1	119	2.7	9.2	0.2	97	0.59	0.267

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287151	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1287152	Soil	7	15	0.07	589	0.003	4	0.97	0.009	0.06	0.2	2.72	2.6	1.1	0.10	2	2.7	<0.2
1287153	Soil	11	16	0.07	311	0.003	3	1.19	0.012	0.06	0.2	2.21	2.8	0.7	0.06	2	1.9	<0.2
1287154	Soil	12	22	0.12	671	0.002	5	1.04	0.007	0.10	0.3	2.31	3.4	0.7	<0.05	3	2.7	<0.2
1287155	Soil	13	24	0.09	913	0.002	4	1.23	0.007	0.10	0.3	2.94	4.1	0.9	0.05	2	2.5	<0.2
1287156	Soil	8	18	0.07	489	0.003	5	0.88	0.016	0.09	0.4	2.67	2.6	0.8	<0.05	2	3.8	<0.2
1287157	Soil	15	18	0.09	663	0.003	5	0.90	0.009	0.09	0.4	1.71	5.1	0.6	0.05	2	4.5	0.2
1287158	Soil	10	21	0.09	789	0.002	4	0.87	0.006	0.09	0.4	3.32	4.5	0.6	<0.05	2	4.2	<0.2
1287159	Soil	13	21	0.12	545	0.004	7	1.11	0.008	0.11	0.3	1.80	4.6	0.9	0.07	3	5.0	<0.2
1287160	Soil	14	20	0.11	586	0.002	4	0.89	0.004	0.09	0.2	1.82	2.6	0.7	<0.05	3	3.0	<0.2
1287291	Soil	7	22	0.05	1673	0.003	5	0.47	0.004	0.09	0.1	0.89	2.4	0.5	0.06	2	2.3	<0.2
1287292	Soil	6	22	0.09	2134	0.003	6	0.71	0.010	0.10	0.1	0.95	2.5	0.5	0.07	2	2.7	<0.2
1287293	Soil	7	24	0.06	1249	0.002	3	0.44	0.003	0.08	0.1	0.90	2.4	0.6	0.07	2	2.9	<0.2
1287294	Soil	9	31	0.07	1634	0.003	6	0.72	0.004	0.12	0.2	1.00	3.3	0.8	0.10	2	3.8	<0.2
1287295	Soil	9	23	0.11	1452	0.002	3	0.61	0.004	0.07	0.2	1.02	3.4	0.5	0.08	2	2.6	<0.2
1287296	Soil	14	19	0.09	392	0.002	3	0.63	0.005	0.09	0.3	5.36	1.6	0.8	0.13	2	5.1	<0.2
1287297	Soil	8	12	0.09	413	0.001	1	0.56	0.011	0.05	0.2	2.35	1.7	0.5	0.11	2	2.7	<0.2
1287298	Soil	23	18	0.07	250	0.001	4	0.52	0.003	0.08	0.3	0.07	1.5	1.1	0.05	2	5.1	<0.2
1287299	Soil	13	16	0.06	330	0.003	2	0.57	0.004	0.06	0.2	0.36	1.0	1.0	<0.05	2	3.1	<0.2
1287300	Soil	20	21	0.07	534	0.001	1	0.82	0.002	0.06	0.3	1.50	4.0	0.8	<0.05	2	4.6	<0.2
1287381	Soil	8	21	0.04	77	0.002	2	0.44	0.004	0.47	0.2	0.09	0.7	1.2	1.25	2	3.6	<0.2
1287382	Soil	7	14	0.14	190	0.002	1	0.50	0.015	0.05	<0.1	0.20	0.5	0.3	0.12	1	1.6	<0.2
1287383	Soil	6	14	0.05	197	0.002	2	0.41	0.013	0.10	0.2	0.38	0.5	0.8	0.16	1	1.7	<0.2
1287384	Soil	13	58	1.06	196	0.001	3	0.65	0.004	0.06	<0.1	0.28	8.9	0.4	0.18	<1	3.3	<0.2
1287385	Soil	10	43	0.06	168	0.002	2	0.89	0.005	0.07	<0.1	0.18	4.8	0.4	0.16	2	2.8	<0.2
1287386	Soil	26	31	0.08	464	0.002	5	0.49	0.003	0.13	<0.1	1.53	6.2	0.8	0.11	1	3.2	<0.2
1287387	Soil	10	16	0.10	280	0.001	4	0.29	0.002	0.12	0.3	0.62	2.3	1.3	0.17	<1	2.6	<0.2
1287388	Soil	21	27	0.12	548	0.004	4	0.65	0.006	0.14	0.3	1.11	1.6	1.4	0.23	2	4.3	0.2
1287389	Soil	22	31	0.19	418	0.002	9	0.63	0.004	0.21	0.1	0.98	3.2	0.5	0.21	2	4.4	<0.2
1287390	Soil	26	25	0.17	620	0.005	8	0.36	0.003	0.18	0.2	1.16	3.2	0.6	0.21	<1	4.6	0.3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1287421	Soil		7.3	91.1	19.9	870	1.6	167.0	12.4	209	2.02	61.2	16.6	1.7	62	7.4	7.4	0.4	75	0.60	0.098
1287422	Soil		11.8	68.6	41.2	554	2.1	128.0	23.0	817	2.87	284.8	96.7	2.3	66	6.9	18.9	1.2	69	0.51	0.118
1287423	Soil		71.7	69.5	69.1	1006	2.3	156.8	15.1	411	2.86	112.4	37.8	0.8	65	9.8	19.3	0.2	245	0.09	0.104
1287424	Soil		106.4	197.5	17.0	1283	5.0	182.3	11.0	287	4.15	289.2	158.2	2.3	98	13.3	50.3	0.2	726	0.69	0.227
1287425	Soil		124.6	247.2	12.7	393	1.3	96.9	2.8	11	1.83	114.1	2.0	1.9	25	0.6	37.5	0.1	1009	0.02	0.087
1287426	Soil		109.7	75.5	37.4	24	3.2	9.9	0.3	7	2.15	807.7	59.9	5.8	358	0.5	67.3	0.4	531	0.13	0.525
1287427	Soil		37.5	19.1	80.8	16	4.2	4.4	0.2	4	1.20	76.8	52.0	5.2	124	0.2	37.3	0.4	98	0.04	0.111
1287428	Soil		31.3	22.1	88.9	22	4.7	5.6	0.5	9	1.63	159.2	127.8	2.7	131	0.3	30.4	0.6	132	0.04	0.155
1287429	Soil		4.7	27.5	26.8	126	0.7	20.8	4.5	101	3.27	150.5	7.4	3.0	79	0.6	13.6	0.3	35	0.02	0.074
1287430	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

CERTIFICATE OF ANALYSIS WHI11001949.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1287421	Soil	9	23	0.17	970	0.001	3	1.08	0.008	0.08	0.3	2.34	3.5	0.6	0.15	2	4.2	<0.2
1287422	Soil	12	18	0.12	530	0.001	3	0.87	0.009	0.08	0.6	9.30	2.8	1.4	0.20	2	6.4	<0.2
1287423	Soil	12	26	0.06	457	0.002	3	0.75	0.010	0.09	0.5	4.03	1.8	2.3	0.16	2	6.6	0.2
1287424	Soil	15	45	0.30	909	0.001	2	1.28	0.003	0.07	1.1	36.52	6.1	3.3	0.07	3	14.1	0.6
1287425	Soil	10	34	0.06	240	0.002	4	0.61	0.001	0.09	0.6	7.68	2.8	1.7	<0.05	2	22.8	0.2
1287426	Soil	25	60	0.02	536	<0.001	4	0.66	0.003	0.14	2.2	>50	14.6	5.1	0.17	7	36.2	0.4
1287427	Soil	10	23	0.01	513	<0.001	4	0.38	0.002	0.18	0.8	26.26	2.9	2.9	0.31	3	13.1	0.4
1287428	Soil	10	23	0.01	770	0.002	5	0.35	0.003	0.17	1.0	36.63	2.5	2.5	0.38	4	11.8	0.3
1287429	Soil	22	11	0.01	363	<0.001	2	0.28	0.002	0.07	<0.1	1.18	2.7	0.4	0.07	1	1.7	<0.2
1287430	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

QUALITY CONTROL REPORT WHI11001949.1

		Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																						
1288315	Soil			8.6	82.2	39.1	155	0.7	38.4	10.0	120	3.80	34.6	8.1	0.7	26	0.4	4.7	0.4	61	0.05	0.098
REP 1288315	QC			8.5	83.3	39.7	159	0.7	40.3	10.0	124	3.86	33.5	7.7	0.6	25	0.5	4.2	0.4	59	0.05	0.103
1288331	Soil			22.1	22.1	12.0	127	0.2	36.0	4.7	55	1.57	24.4	1.8	0.7	7	0.1	2.6	0.2	79	0.03	0.032
REP 1288331	QC			22.1	21.2	11.7	127	0.2	34.5	4.7	54	1.54	24.0	1.2	0.7	9	0.1	2.7	0.2	78	0.02	0.033
1288544	Soil			4.0	14.2	15.0	53	1.0	10.4	2.7	42	1.14	8.5	0.9	0.6	15	0.3	1.2	0.2	48	0.01	0.044
REP 1288544	QC			3.6	14.2	14.7	52	0.9	10.8	2.7	43	1.14	8.8	0.7	0.6	16	0.3	1.3	0.1	49	0.02	0.040
1286379	Soil			117.1	200.3	20.7	3112	2.7	416.6	15.3	207	1.94	142.4	<0.5	2.1	329	17.2	54.8	0.2	890	10.53	0.120
REP 1286379	QC			117.2	198.0	20.5	3093	2.7	413.8	15.2	203	1.86	139.5	<0.5	2.1	326	16.5	53.8	0.2	876	10.30	0.115
1286497	Soil			119.7	181.8	17.5	2831	2.6	399.8	7.7	154	1.58	144.8	2.0	1.2	253	17.0	42.9	0.2	772	9.41	0.121
REP 1286497	QC			123.0	178.0	16.2	2840	2.5	399.6	7.8	149	1.57	144.5	2.1	1.2	251	16.4	42.1	0.2	701	9.21	0.123
1284495	Soil			14.5	54.1	48.2	259	1.5	55.9	39.4	1089	1.99	88.7	25.6	2.3	72	3.7	16.9	0.5	107	0.14	0.096
REP 1284495	QC			14.7	55.9	45.9	274	1.6	55.6	40.1	1097	1.99	90.7	28.8	2.5	73	3.4	17.3	0.5	103	0.14	0.097
1287889	Soil			3.1	49.3	20.3	126	0.9	32.6	8.9	292	3.28	98.3	12.6	2.1	56	0.4	1.9	0.4	35	0.31	0.112
REP 1287889	QC			3.1	49.3	19.4	123	0.9	32.9	9.0	292	3.30	96.4	13.3	2.1	55	0.4	2.0	0.3	36	0.31	0.111
1288485	Soil			15.4	120.3	29.9	256	2.9	46.5	5.6	128	2.89	36.3	20.1	0.8	155	1.8	9.6	0.3	122	0.59	0.227
REP 1288485	QC			15.5	118.8	30.6	250	2.9	44.5	5.7	126	2.87	36.9	20.9	0.8	160	1.7	9.3	0.3	123	0.57	0.222
1288895	Soil			9.7	126.2	18.4	429	2.1	192.8	22.1	754	6.32	165.3	86.9	1.8	94	3.7	17.7	0.3	83	0.26	0.145
REP 1288895	QC			9.2	124.1	18.1	426	2.2	194.7	22.3	737	6.26	163.5	65.8	2.0	92	3.8	17.6	0.3	84	0.26	0.143
1283959	Soil			1.4	26.3	9.9	94	1.7	33.6	5.1	137	1.73	12.0	12.1	0.9	56	0.4	0.7	0.1	15	0.88	0.090
REP 1283959	QC			1.7	27.4	10.2	95	1.7	35.6	5.2	140	1.74	12.5	9.9	0.8	56	0.6	0.7	0.2	15	0.88	0.094
1283973	Soil			12.0	105.2	14.1	307	0.9	331.7	52.1	969	6.36	197.0	1.9	9.6	193	3.0	6.9	0.2	126	1.65	0.305
REP 1283973	QC			11.6	108.2	14.0	309	1.0	329.2	53.5	959	6.38	196.4	2.1	9.7	203	3.0	7.5	0.2	134	1.65	0.319
1284254	Soil			7.1	93.8	29.8	260	2.3	72.7	10.7	193	4.38	84.6	32.8	2.6	96	1.1	6.5	0.3	49	0.22	0.118
REP 1284254	QC			7.0	94.1	28.1	251	2.2	73.7	10.6	193	4.07	82.4	31.4	2.4	97	1.2	6.1	0.3	50	0.22	0.122
1284260	Soil			3.8	56.8	24.4	237	1.2	77.6	14.8	283	3.74	103.2	18.7	2.5	91	0.7	3.8	0.3	31	0.20	0.123
REP 1284260	QC			3.7	56.7	25.9	241	1.2	79.1	15.0	277	3.70	107.3	18.9	2.5	91	0.6	3.8	0.3	30	0.20	0.126
1287295	Soil			12.6	75.3	17.8	267	0.9	68.7	6.8	117	2.33	41.8	8.6	2.4	77	1.5	7.4	0.2	103	0.30	0.113
REP 1287295	QC			12.5	75.5	17.3	270	0.9	68.3	6.7	118	2.31	42.0	9.5	2.3	77	1.5	7.4	0.2	103	0.31	0.112

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

QUALITY CONTROL REPORT WHI11001949.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1288315	Soil	5	17	0.02	188	0.005	3	0.41	0.005	0.07	<0.1	0.13	3.2	0.1	<0.05	2	3.6	0.4
REP 1288315	QC	5	17	0.02	193	0.003	2	0.39	0.005	0.07	<0.1	0.14	3.1	0.1	0.13	2	3.1	0.2
1288331	Soil	6	9	0.02	227	0.001	2	0.38	0.003	0.04	0.1	0.02	0.8	0.2	0.11	3	0.9	<0.2
REP 1288331	QC	7	9	0.03	239	0.002	1	0.40	0.003	0.04	0.1	0.03	0.8	0.3	0.09	3	1.4	<0.2
1288544	Soil	4	6	0.02	423	0.005	2	0.36	0.005	0.03	0.1	0.11	0.8	0.1	<0.05	2	1.0	<0.2
REP 1288544	QC	4	6	0.02	416	0.005	2	0.37	0.005	0.03	0.1	0.08	0.9	0.1	<0.05	2	<0.5	<0.2
1286379	Soil	14	47	1.31	349	0.006	7	0.37	0.007	0.10	0.5	0.68	3.1	6.5	0.07	2	10.9	0.3
REP 1286379	QC	14	46	1.27	344	0.008	8	0.37	0.006	0.10	0.5	0.67	2.9	6.5	0.05	2	11.7	0.2
1286497	Soil	13	38	1.36	328	0.004	6	0.37	0.005	0.10	0.5	1.04	2.5	4.5	0.06	2	7.7	<0.2
REP 1286497	QC	13	35	1.32	324	0.003	5	0.33	0.005	0.08	0.5	1.01	2.5	4.0	<0.05	1	7.7	0.2
1284495	Soil	14	13	0.05	576	0.002	1	0.73	0.004	0.05	0.6	2.03	1.7	0.9	0.07	2	4.5	<0.2
REP 1284495	QC	14	13	0.05	598	0.004	2	0.68	0.004	0.06	0.7	1.87	1.7	0.9	<0.05	2	4.1	0.2
1287889	Soil	5	27	0.20	610	0.003	4	0.92	0.006	0.10	0.1	0.07	1.3	0.2	0.24	3	1.9	<0.2
REP 1287889	QC	6	27	0.20	623	0.005	4	0.95	0.006	0.10	0.1	0.09	1.3	0.2	0.24	3	2.0	<0.2
1288485	Soil	15	22	0.07	583	0.003	4	0.57	0.007	0.12	<0.1	0.56	1.1	0.6	0.28	3	4.3	<0.2
REP 1288485	QC	15	21	0.07	581	0.005	3	0.60	0.007	0.12	<0.1	0.57	0.9	0.6	0.31	3	4.4	<0.2
1288895	Soil	2	24	0.06	818	0.001	7	0.55	0.003	0.12	<0.1	1.06	6.0	0.5	0.14	1	7.5	<0.2
REP 1288895	QC	2	23	0.06	741	0.001	6	0.55	0.003	0.11	<0.1	1.03	6.0	0.5	0.14	2	8.3	<0.2
1283959	Soil	5	14	0.09	568	0.003	3	0.64	0.010	0.06	<0.1	0.33	2.4	<0.1	0.09	2	1.9	<0.2
REP 1283959	QC	5	14	0.09	609	0.003	5	0.70	0.011	0.06	<0.1	0.31	2.4	<0.1	0.12	2	1.6	<0.2
1283973	Soil	35	102	0.58	2207	0.003	10	0.72	0.004	0.13	<0.1	1.32	14.9	0.3	0.13	2	3.3	<0.2
REP 1283973	QC	40	110	0.63	2470	0.005	14	0.86	0.004	0.16	<0.1	1.35	15.3	0.3	0.14	3	2.8	<0.2
1284254	Soil	6	20	0.11	1171	0.001	3	0.75	0.005	0.08	<0.1	4.33	7.6	0.7	0.06	2	5.8	<0.2
REP 1284254	QC	6	21	0.11	1240	0.001	3	0.79	0.005	0.08	<0.1	4.37	7.9	0.6	0.11	2	6.5	<0.2
1284260	Soil	12	19	0.09	1059	0.003	3	0.83	0.011	0.10	0.1	1.28	3.5	0.2	0.14	2	1.9	<0.2
REP 1284260	QC	12	19	0.09	1079	0.002	3	0.83	0.011	0.10	0.1	1.25	3.6	0.2	0.15	2	1.9	<0.2
1287295	Soil	9	23	0.11	1452	0.002	3	0.61	0.004	0.07	0.2	1.02	3.4	0.5	0.08	2	2.6	<0.2
REP 1287295	QC	9	23	0.11	1439	0.002	3	0.60	0.004	0.07	0.1	1.04	3.3	0.4	0.10	2	2.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

QUALITY CONTROL REPORT WHI11001949.1

		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1287422	Soil		11.8	68.6	41.2	554	2.1	128.0	23.0	817	2.87	284.8	96.7	2.3	66	6.9	18.9	1.2	69	0.51	0.118
REP 1287422	QC		12.0	71.2	41.7	573	2.1	128.8	23.4	844	2.93	289.5	108.5	2.4	67	6.9	20.7	1.2	78	0.52	0.120
Reference Materials																					
STD DS8	Standard		13.7	109.3	120.9	289	1.7	38.2	7.6	584	2.38	23.9	108.3	6.2	59	2.0	4.5	5.2	44	0.66	0.072
STD DS8	Standard		12.3	113.1	128.5	319	1.8	40.8	7.8	624	2.50	27.7	114.3	6.7	64	2.3	5.4	7.0	41	0.64	0.079
STD DS8	Standard		11.6	108.2	116.7	296	1.8	37.7	7.5	580	2.35	25.8	118.7	5.6	62	2.3	5.3	6.3	41	0.64	0.077
STD DS8	Standard		12.7	100.6	113.1	283	1.6	34.4	6.8	559	2.26	24.1	106.1	6.2	65	2.4	5.1	6.2	37	0.65	0.070
STD DS8	Standard		13.4	110.8	128.9	314	1.8	38.8	8.0	637	2.51	26.0	109.5	6.6	70	2.5	5.3	6.6	44	0.67	0.078
STD DS8	Standard		13.6	111.5	118.0	305	1.6	38.6	7.5	605	2.40	25.8	106.9	6.9	66	2.1	7.5	6.2	43	0.69	0.075
STD DS8	Standard		12.9	114.0	123.9	309	1.8	38.4	7.6	624	2.45	25.7	104.1	6.4	63	2.5	5.5	6.4	43	0.66	0.080
STD DS8	Standard		14.6	113.7	126.8	322	1.7	38.2	7.5	644	2.56	28.3	117.7	6.7	78	2.2	5.9	6.7	44	0.78	0.080
STD DS8	Standard		10.4	110.1	123.5	303	1.8	37.7	7.4	582	2.38	25.7	116.0	6.6	65	2.3	6.1	7.6	39	0.63	0.078
STD DS8	Standard		11.3	108.2	117.6	305	1.6	37.0	7.1	571	2.36	25.8	121.8	5.4	62	2.2	5.4	6.2	39	0.62	0.076
STD DS8	Standard		10.6	104.5	121.4	310	1.8	35.7	7.1	598	2.41	27.3	112.6	5.9	65	2.4	5.8	6.7	40	0.63	0.081
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: December 01, 2011

QUALITY CONTROL REPORT WHI11001949.1

		1DX15 La ppm 1	1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
1287422	Soil	12	18	0.12	530	0.001	3	0.87	0.009	0.08	0.6	9.30	2.8	1.4	0.20	2	6.4	<0.2
REP 1287422	QC	14	20	0.12	570	0.002	4	0.91	0.009	0.10	0.8	8.37	2.8	1.6	0.24	2	7.0	<0.2
Reference Materials																		
STD DS8	Standard	16	118	0.58	256	0.110	2	0.90	0.100	0.38	2.7	0.11	2.5	5.3	0.16	5	4.9	4.8
STD DS8	Standard	12	119	0.60	264	0.103	2	0.91	0.103	0.42	3.0	0.21	2.2	5.6	0.16	4	5.6	4.9
STD DS8	Standard	12	114	0.60	260	0.108	2	0.89	0.103	0.45	2.8	0.19	2.1	5.0	0.14	4	4.5	4.4
STD DS8	Standard	15	106	0.57	266	0.113	2	0.90	0.108	0.40	2.7	0.16	2.1	4.9	0.15	4	4.4	4.8
STD DS8	Standard	14	122	0.60	256	0.121	3	0.92	0.094	0.42	3.0	0.17	2.5	5.4	0.17	5	5.5	4.8
STD DS8	Standard	17	119	0.60	271	0.130	3	0.90	0.084	0.38	2.7	0.18	2.3	5.2	0.16	5	4.7	5.0
STD DS8	Standard	14	119	0.62	260	0.115	3	0.88	0.082	0.41	2.9	0.21	1.9	5.3	0.16	4	4.7	4.7
STD DS8	Standard	17	119	0.66	298	0.132	2	1.02	0.097	0.46	3.2	0.15	3.0	5.7	0.15	5	5.4	5.3
STD DS8	Standard	11	113	0.59	252	0.112	2	0.83	0.081	0.40	2.9	0.18	2.1	5.3	0.14	4	4.4	5.0
STD DS8	Standard	11	110	0.58	251	0.109	3	0.85	0.092	0.39	2.8	0.19	1.7	5.3	0.10	4	5.4	4.7
STD DS8	Standard	13	114	0.60	263	0.105	4	0.88	0.083	0.40	2.9	0.20	1.8	5.3	0.16	4	5.0	4.5
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 18, 2011
Report Date: September 25, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001184.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #13
P.O. Number
Number of Samples: 5

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	5	Dry at 60C			WHI
SS80	5	Dry at 60C sieve 100g to -80 mesh			WHI
RJSV	5	Saving all or part of Soil Reject			VAN
1DX2	5	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

CERTIFICATE OF ANALYSIS WHI11001184.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1095538	Silt	84.4	93.3	9.1	922	0.8	220.7	7.2	161	1.52	34.3	1.9	4.3	145	12.4	16.6	0.2	337	2.66	0.157	22
1095539	Silt	11.5	24.5	13.0	73	1.0	23.2	1.0	8	6.65	53.4	2.4	1.1	14	1.3	3.8	0.2	131	0.04	0.138	4
1095541	Silt	12.0	76.2	15.6	382	1.4	94.8	13.4	336	3.13	13.3	3.9	3.7	77	3.2	5.5	0.2	58	0.64	0.137	18
1095542	Silt	9.1	31.1	19.4	84	0.4	26.5	2.8	38	2.10	22.3	3.0	2.3	42	<0.1	2.7	0.2	36	0.02	0.067	10
1274348	Silt	14.0	66.9	17.7	393	0.4	99.1	12.2	335	3.86	52.1	2.8	1.6	47	4.3	5.1	0.2	96	0.24	0.121	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

CERTIFICATE OF ANALYSIS WHI11001184.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1095538	Silt	19	1.19	765	0.003	6	0.26	0.002	0.08	0.3	1.05	3.5	1.5	<0.05	<1	4.7	<0.2
1095539	Silt	12	0.01	253	0.003	2	0.49	0.001	0.06	<0.1	0.12	1.1	0.9	0.32	<1	13.0	<0.2
1095541	Silt	13	0.19	437	0.002	5	0.27	0.001	0.09	<0.1	0.39	5.8	0.3	<0.05	<1	2.9	<0.2
1095542	Silt	7	0.01	1661	0.001	2	0.69	0.001	0.06	<0.1	0.13	3.0	0.6	0.10	1	2.9	<0.2
1274348	Silt	12	0.03	657	0.003	1	0.35	0.002	0.05	<0.1	0.22	2.9	0.7	0.05	1	3.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

QUALITY CONTROL REPORT WHI11001184.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Reference Materials																					
STD DS8	Standard	14.0	114.2	128.6	317	1.8	39.2	7.7	611	2.51	24.7	130.0	7.1	65	2.2	4.8	6.6	42	0.70	0.080	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: September 25, 2011

QUALITY CONTROL REPORT WHI11001184.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Reference Materials																	
STD DS8	Standard	123	0.61	273	0.116	2	0.91	0.085	0.42	2.8	0.20	2.4	5.6	0.09	5	5.7	4.6
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: August 18, 2011
Report Date: October 06, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001185.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #14
P.O. Number
Number of Samples: 10

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	10	Dry at 60C			WHI
SS80	10	Dry at 60C sieve 100g to -80 mesh			WHI
RJSV	10	Saving all or part of Soil Reject			WHI
1DX2	9	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
1DX1	1	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1DX1 analysis included

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001185.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1094016	Silt	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1094030	Silt	224.3	1.6	1.0	266	<0.1	14.6	2.9	74	>40	769.8	<0.5	<0.1	5	1.7	38.4	<0.1	4	0.05	0.130	<1
1095117	Silt	12.6	62.8	19.6	939	1.2	142.9	20.3	584	3.04	120.1	13.9	2.0	54	7.3	8.9	0.4	75	0.42	0.099	8
1095540	Silt	1.0	256.8	10.8	202	0.7	27.9	6.6	78	33.02	4.6	2.3	0.7	9	<0.1	1.0	<0.1	5	0.05	0.021	<1
1095812	Silt	16.5	71.7	17.4	500	0.7	154.6	16.4	395	3.49	37.8	1.0	2.0	132	4.1	6.3	0.2	80	4.39	0.333	4
1279201	Silt	1.7	48.1	15.7	190	1.5	58.5	8.8	230	2.35	17.2	13.0	1.7	73	1.1	1.6	0.2	41	1.25	0.197	9
1279202	Silt	33.1	98.0	21.5	1107	1.6	232.1	19.1	464	3.19	58.5	7.3	2.0	102	11.2	11.4	0.2	144	1.84	0.241	14
1279401	Silt	15.7	136.7	44.3	780	0.9	160.7	17.9	321	3.84	98.2	11.1	0.8	132	7.5	114.9	0.2	120	0.65	0.256	9
1277558	Silt	28.8	134.6	22.0	1273	3.4	162.7	8.0	216	2.23	22.3	0.5	2.2	136	18.1	14.3	0.2	287	0.85	0.298	12
1277567	Silt	24.2	107.1	29.1	2135	0.6	285.1	40.1	123	4.68	155.9	3.7	1.0	20	43.5	8.6	0.3	62	0.20	0.116	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001185.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
1094016	Silt	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	10.0	0.9	2.7	205
1094030	Silt	2	<0.01	34	<0.001	2	0.19	<0.001	<0.01	<0.1	0.06	0.2	0.3	1.45	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095117	Silt	17	0.13	548	0.002	4	0.75	0.003	0.06	0.2	1.99	3.1	0.6	<0.05	2	4.6	<0.2	N.A.	N.A.	N.A.	N.A.
1095540	Silt	7	0.03	42	<0.001	2	5.14	0.001	0.02	<0.1	0.03	5.3	<0.1	3.17	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
1095812	Silt	14	1.42	416	0.004	4	0.24	0.003	0.07	<0.1	0.31	4.6	0.2	0.09	<1	2.2	<0.2	N.A.	N.A.	N.A.	N.A.
1279201	Silt	27	0.13	511	0.003	5	0.98	0.008	0.10	<0.1	0.62	3.3	0.2	0.07	2	1.9	<0.2	N.A.	N.A.	N.A.	N.A.
1279202	Silt	20	0.64	479	0.004	4	0.37	0.003	0.11	0.1	0.81	3.8	1.0	0.06	<1	3.3	<0.2	N.A.	N.A.	N.A.	N.A.
1279401	Silt	35	0.19	397	0.008	2	1.00	0.004	0.06	0.1	0.25	3.6	0.4	<0.05	3	3.0	<0.2	N.A.	N.A.	N.A.	N.A.
1277558	Silt	46	0.14	600	0.004	11	0.41	0.003	0.14	0.2	1.89	3.3	1.2	0.25	2	24.5	0.3	N.A.	N.A.	N.A.	N.A.
1277567	Silt	14	0.04	115	0.002	<1	0.89	0.005	0.05	<0.1	0.65	6.5	1.0	0.11	2	4.9	<0.2	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001185.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
Unit		ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
MDL		0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
1094016	Silt	0.3	11.0	1.1	16	>40	35.1	0.8	0.2	3	0.1	8.1	<0.1	<2	0.07	0.215	<1	3	0.03	15	0.001
1094030	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095117	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095540	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095812	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279201	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279202	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279401	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277558	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277567	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

CERTIFICATE OF ANALYSIS WHI11001185.2

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1094016	Silt	<20	0.07	0.005	0.02	<0.1	0.01	<0.1	<0.1	1.75	<1	0.6	<0.2
1094030	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095117	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095540	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1095812	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279201	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279202	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1279401	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277558	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
1277567	Silt	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001185.2

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																						
1095540	Silt		1.0	256.8	10.8	202	0.7	27.9	6.6	78	33.02	4.6	2.3	0.7	9	<0.1	1.0	<0.1	5	0.05	0.021	<1
REP 1095540	QC		1.2	259.3	11.6	199	0.7	29.1	6.8	80	33.93	4.2	2.9	0.7	10	0.1	0.9	<0.1	6	0.06	0.023	<1
Reference Materials																						
STD DS8	Standard		12.6	110.2	127.3	308	1.8	38.4	7.5	619	2.46	24.7	112.9	6.3	71	2.4	5.9	6.5	42	0.68	0.081	14
STD DS8	Standard		14.0	114.2	128.6	317	1.8	39.2	7.7	611	2.51	24.7	130.0	7.1	65	2.2	4.8	6.6	42	0.70	0.080	15
STD DS8	Standard																					
STD OREAS45CA	Standard																					
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
STD OREAS45CA Expected																						
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank																					

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001185.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX	1DX	1DX	1DX
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te	Mo	Cu	Pb	Zn
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2	0.1	0.1	0.1	1
Pulp Duplicates																					
1095540	Silt	7	0.03	42	<0.001	2	5.14	0.001	0.02	<0.1	0.03	5.3	<0.1	3.17	<1	2.0	<0.2	N.A.	N.A.	N.A.	N.A.
REP 1095540	QC	7	0.03	45	<0.001	2	5.31	0.001	0.02	<0.1	0.06	5.6	<0.1	3.25	<1	1.4	<0.2				
Reference Materials																					
STD DS8	Standard	117	0.64	278	0.111	2	0.95	0.107	0.43	3.2	0.18	3.4	5.5	0.15	5	7.0	5.2				
STD DS8	Standard	123	0.61	273	0.116	2	0.91	0.085	0.42	2.8	0.20	2.4	5.6	0.09	5	5.7	4.6				
STD DS8	Standard																	14.2	119.9	125.1	325
STD OREAS45CA	Standard																	0.9	570.7	22.2	69
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5	13.44	110	123	312
STD OREAS45CA Expected																		1	494	20	60
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2				
BLK	Blank																	<0.1	<0.1	<0.1	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001185.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La	Cr	Mg	Ba	Ti
		Unit	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm	ppm	%	ppm	%
		MDL	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1	1	0.01	1	0.001
Pulp Duplicates																						
1095540	Silt		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095540	QC																					
Reference Materials																						
STD DS8	Standard																					
STD DS8	Standard																					
STD DS8	Standard		1.7	41.1	8.3	652	2.53	27.0	136.8	7.2	76	2.4	5.4	7.4	47	0.73	0.081	17	128	0.61	304	0.123
STD OREAS45CA	Standard		0.3	271.0	97.9	970	17.25	3.5	43.2	7.3	16	<0.1	<0.1	0.2	218	0.43	0.039	17	793	0.16	172	0.144
STD DS8 Expected			1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7	0.08	14.6	115	0.6045	279	0.113
STD OREAS45CA Expected			0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265	0.0385	15.9	709	0.1358	164	0.128
BLK	Blank																					
BLK	Blank																					
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1	<1	<0.01	<1	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 06, 2011

QUALITY CONTROL REPORT WHI11001185.2

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	20	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates														
1095540	Silt		N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.	N.A.
REP 1095540	QC													
Reference Materials														
STD DS8	Standard													
STD DS8	Standard													
STD DS8	Standard		<20	0.94	0.096	0.43	2.3	0.19	2.4	5.5	0.17	5	4.4	5.4
STD OREAS45CA	Standard		<20	3.94	0.013	0.08	<0.1	0.03	39.8	<0.1	0.05	19	0.9	<0.2
STD DS8 Expected			2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
STD OREAS45CA Expected				3.592	0.0075	0.0717		0.03	39.7	0.07	0.021	18.4	0.5	
BLK	Blank													
BLK	Blank													
BLK	Blank		<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 05, 2011
Report Date: January 19, 2012
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001401.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #21
P.O. Number
Number of Samples: 17

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	16	Dry at 60C sieve 100g to -80 mesh			WHI
RJSV	16	Saving all or part of Soil Reject			WHI
1DX2	16	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Version 2: Sample ID revised - 1095853 revised to 1279253

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001401.2

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1095592	Silt	0.932	11.8	28.4	23.2	48	1.8	12.6	1.1	33	1.50	10.1	4.3	0.5	34	0.2	3.5	0.2	65	0.03	0.047
1095805	Silt	1.908	2.6	64.7	17.5	275	0.5	76.8	16.6	702	3.49	13.7	3.5	2.7	62	0.7	1.3	0.2	37	0.36	0.114
1095807	Silt	1.196	13.8	83.8	25.6	746	1.1	118.9	10.3	409	2.41	22.3	4.7	1.7	67	6.2	4.5	0.2	67	0.84	0.220
1095813	Silt	1.41	25.6	70.2	12.2	473	0.4	73.1	6.2	180	1.41	16.7	<0.5	2.6	123	4.0	4.4	<0.1	67	4.34	0.177
1095851	Silt	0.676	15.1	50.2	15.3	1072	0.7	95.0	8.9	255	2.31	16.6	4.2	2.2	64	8.4	3.8	0.2	76	0.75	0.176
1095852	Silt	1.09	45.7	81.4	67.8	3068	0.9	366.8	18.5	1355	3.72	87.5	8.8	1.9	75	31.1	12.0	0.2	189	0.81	0.176
1279253	Silt	1.618	38.0	74.6	13.5	1646	0.7	238.7	15.4	345	2.55	38.4	2.5	1.2	82	20.5	14.6	0.1	381	1.69	0.221
1095854	Silt	1.006	3.7	70.2	10.3	301	2.2	107.6	22.3	4553	4.39	83.1	5.5	0.5	74	4.1	1.3	0.2	35	1.94	0.182
1279250	Silt	2.284	10.7	57.5	15.5	149	3.7	50.4	2.7	57	3.02	64.5	23.1	1.1	95	0.7	5.7	0.2	30	0.27	0.089
1279251	Silt	2.206	3.7	58.4	13.5	82	1.0	28.4	2.8	31	1.97	99.2	19.9	1.3	58	0.5	6.7	0.2	17	0.17	0.054
1279252	Silt	1.998	45.3	95.4	10.6	1255	1.1	245.6	21.2	402	2.79	44.3	1.7	3.4	142	18.7	17.9	0.1	432	3.36	0.344
1279254	Silt	0.684	38.9	54.9	16.5	1385	0.6	311.7	54.6	2942	6.71	228.1	4.2	0.9	38	18.1	8.3	0.2	115	0.34	0.181
1279255	Silt	1.736	16.4	38.1	12.9	1862	1.1	450.8	61.5	4203	7.86	73.1	6.4	0.7	53	38.1	6.5	0.1	216	0.65	0.303
1279256	Silt	1.586	31.4	62.6	14.5	1225	0.6	165.9	17.4	630	2.63	40.1	1.7	2.6	118	16.0	10.0	0.1	222	3.13	0.185
1279257	Silt	1.008	65.4	56.6	13.3	905	0.5	138.1	9.1	240	1.99	39.8	1.2	1.0	60	11.1	12.7	0.1	280	1.24	0.148
1279258	Silt	1.286	33.9	89.7	25.1	1759	1.6	336.3	54.8	1572	4.88	104.2	2.7	2.7	70	9.4	11.1	0.2	170	0.55	0.872

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001401.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1095592	Silt	2	14	0.01	818	<0.001	3	0.30	0.001	0.05	<0.1	0.34	1.9	1.3	0.11	1	6.2	<0.2
1095805	Silt	5	28	0.59	563	0.003	3	1.41	0.006	0.07	<0.1	0.33	3.7	0.1	0.26	4	1.9	<0.2
1095807	Silt	14	13	0.12	608	0.002	5	0.54	0.004	0.10	0.2	0.45	2.5	0.6	0.14	1	2.2	<0.2
1095813	Silt	8	10	1.51	301	0.002	5	0.24	0.005	0.08	<0.1	0.25	2.6	0.5	0.18	<1	2.7	<0.2
1095851	Silt	17	15	0.17	985	0.004	7	0.71	0.004	0.12	0.2	0.32	2.6	0.6	0.13	2	2.3	<0.2
1095852	Silt	12	22	0.21	593	0.004	5	0.78	0.004	0.10	0.2	0.88	3.0	2.1	0.13	2	6.0	<0.2
1279253	Silt	20	52	0.60	1143	0.004	7	0.58	0.004	0.11	0.2	0.72	3.3	1.3	0.13	2	6.0	<0.2
1095854	Silt	5	24	0.14	610	0.005	7	0.98	0.006	0.05	<0.1	0.71	1.9	0.2	0.36	2	11.2	<0.2
1279250	Silt	3	29	0.02	654	0.001	4	0.36	0.004	0.10	<0.1	1.53	3.9	0.2	0.17	1	9.4	<0.2
1279251	Silt	1	12	0.02	431	<0.001	4	0.28	0.002	0.09	<0.1	1.02	2.8	0.1	0.09	1	6.9	<0.2
1279252	Silt	25	73	1.29	1438	0.006	9	0.64	0.004	0.14	0.2	0.39	5.1	1.3	0.12	2	7.4	<0.2
1279254	Silt	3	14	0.05	971	0.001	2	0.41	0.002	0.05	<0.1	0.79	2.8	1.8	0.17	1	5.6	<0.2
1279255	Silt	3	19	0.12	1418	0.003	3	0.63	0.003	0.07	<0.1	0.83	2.4	1.6	0.15	1	8.7	<0.2
1279256	Silt	13	31	1.29	899	0.003	5	0.39	0.004	0.09	<0.1	0.67	3.5	0.8	0.17	1	3.9	<0.2
1279257	Silt	21	19	0.47	409	0.008	3	0.35	0.002	0.07	0.2	0.37	1.8	0.9	0.09	1	5.3	<0.2
1279258	Silt	12	26	0.10	848	0.005	5	1.35	0.002	0.13	0.2	0.76	2.7	1.2	0.26	2	5.7	0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001401.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1095805	Silt	1.908	2.6	64.7	17.5	275	0.5	76.8	16.6	702	3.49	13.7	3.5	2.7	62	0.7	1.3	0.2	37	0.36	0.114
REP 1095805	QC		2.6	63.3	17.3	282	0.4	74.5	16.1	672	3.48	13.6	4.3	2.7	61	0.7	1.2	0.2	36	0.34	0.114
Reference Materials																					
STD DS8	Standard		14.5	122.2	136.0	344	2.0	40.8	8.2	659	2.63	26.3	133.9	7.2	71	2.4	6.0	6.9	49	0.74	0.094
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001401.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1095805	Silt	5	28	0.59	563	0.003	3	1.41	0.006	0.07	<0.1	0.33	3.7	0.1	0.26	4	1.9	<0.2
REP 1095805	QC	5	28	0.58	539	0.002	3	1.40	0.006	0.07	<0.1	0.22	3.5	0.1	0.30	4	1.8	<0.2
Reference Materials																		
STD DS8	Standard	17	122	0.71	290	0.134	4	1.08	0.107	0.51	3.2	0.21	3.2	6.2	0.19	5	5.4	5.4
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 05, 2011
Report Date: January 19, 2012
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001407.2

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #22
P.O. Number
Number of Samples: 11

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	11	Dry at 60C sieve 100g to -80 mesh			WHI
RJSV	11	Saving all or part of Soil Reject			WHI
1DX2	11	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Version 2: Sample ID revised - Sample 1095655 revised to 1095855

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001407.2

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1284501	Silt	1.34	2.0	26.6	14.8	153	0.3	37.7	8.9	183	2.34	11.2	1.6	1.2	94	0.7	1.5	0.2	21	0.71	0.049
1095544	Silt	1.5	1.4	15.4	6.4	105	0.3	22.7	3.3	92	0.76	16.0	2.5	0.7	22	0.7	0.9	<0.1	28	0.33	0.026
1095545	Silt	2	3.0	30.4	16.9	135	0.5	44.2	10.4	237	2.39	12.0	2.1	1.9	84	0.8	3.1	0.2	30	0.52	0.077
1274353	Silt	1.716	23.2	42.1	12.6	476	0.5	93.3	7.6	291	1.82	20.1	1.2	2.3	122	3.5	4.2	0.1	66	3.39	0.120
1095806	Silt	1.106	24.9	60.3	19.8	1420	0.6	166.2	12.7	734	2.55	28.2	3.3	2.3	83	10.6	5.8	0.2	104	1.43	0.181
1095814	Silt	2.566	21.1	56.7	16.2	859	0.4	93.3	8.5	292	2.08	21.0	1.1	3.2	77	6.0	4.7	0.1	89	1.74	0.173
1095853	Silt	1.088	19.9	54.8	58.1	1201	1.2	189.6	17.7	430	2.20	26.4	3.8	1.5	79	10.4	8.5	0.2	141	0.57	0.111
1095855	Silt	1.856	2.6	37.0	15.9	193	0.4	61.8	16.2	1307	3.16	10.1	2.1	2.7	106	1.2	0.9	0.2	33	0.51	0.092
1095856	Silt	2.142	1.9	77.1	15.1	301	0.5	135.5	22.9	1253	2.80	17.4	4.7	2.3	72	0.9	1.3	0.2	23	0.64	0.090
1277553	Silt	1.724	23.6	113.3	18.1	2489	2.0	203.4	8.5	250	2.36	23.0	1.1	1.6	128	16.6	13.2	0.2	179	1.57	0.197
1279301	Silt	1.554	11.3	59.7	14.2	884	0.7	138.6	15.8	320	3.12	23.6	1.8	2.7	41	4.0	6.7	0.2	72	0.53	0.138

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

CERTIFICATE OF ANALYSIS WHI11001407.2

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1284501	Silt	3	10	0.20	1257	0.002	2	0.55	0.004	0.06	<0.1	0.10	3.1	0.2	0.15	1	1.8	<0.2
1095544	Silt	3	8	0.09	170	0.001	2	0.32	0.002	0.03	<0.1	0.20	0.9	0.1	0.05	<1	0.6	<0.2
1095545	Silt	4	14	0.26	948	0.002	2	0.69	0.005	0.06	<0.1	0.28	3.1	0.2	0.12	2	2.0	<0.2
1274353	Silt	10	12	1.06	531	0.003	4	0.36	0.004	0.07	0.1	0.42	2.5	0.5	0.13	<1	1.3	<0.2
1095806	Silt	17	14	0.44	566	0.004	4	0.48	0.004	0.11	0.2	0.38	2.6	0.8	0.12	1	3.0	<0.2
1095814	Silt	14	13	0.56	581	0.005	5	0.43	0.004	0.10	0.2	0.32	2.5	0.4	0.15	1	2.5	<0.2
1095853	Silt	6	22	0.17	702	0.003	4	0.88	0.004	0.09	0.2	2.29	2.1	1.4	0.16	2	6.5	<0.2
1095855	Silt	5	26	0.56	493	0.002	2	1.44	0.005	0.06	<0.1	0.21	3.0	0.1	0.09	4	1.5	<0.2
1095856	Silt	4	22	0.28	397	0.001	1	0.94	0.005	0.06	<0.1	0.17	2.9	<0.1	0.11	2	1.9	<0.2
1277553	Silt	9	28	0.59	504	0.002	6	0.27	0.003	0.09	0.2	1.47	3.1	0.7	0.35	1	12.0	0.3
1279301	Silt	18	29	0.21	903	0.003	2	0.41	0.002	0.07	<0.1	0.32	3.9	0.3	0.08	<1	2.2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001407.2

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1277553	Silt	1.724	23.6	113.3	18.1	2489	2.0	203.4	8.5	250	2.36	23.0	1.1	1.6	128	16.6	13.2	0.2	179	1.57	0.197
REP 1277553	QC		24.4	113.5	17.4	2509	2.0	211.4	8.4	263	2.36	23.0	1.4	1.7	130	16.8	13.3	0.2	188	1.57	0.199
Reference Materials																					
STD DS8	Standard		13.0	113.2	125.1	306	1.7	37.5	7.8	624	2.50	23.9	107.5	7.1	72	2.5	6.1	7.3	42	0.68	0.076
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: January 19, 2012

QUALITY CONTROL REPORT WHI11001407.2

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1277553	Silt	9	28	0.59	504	0.002	6	0.27	0.003	0.09	0.2	1.47	3.1	0.7	0.35	1	12.0	0.3
REP 1277553	QC	10	29	0.59	527	0.002	6	0.30	0.003	0.10	0.1	1.44	3.0	0.7	0.34	1	12.3	<0.2
Reference Materials																		
STD DS8	Standard	14	120	0.60	273	0.114	2	0.90	0.091	0.42	2.8	0.20	2.5	5.3	0.17	5	4.6	5.0
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 17, 2011
Report Date: October 28, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001414.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #24
P.O. Number
Number of Samples: 6

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	6	Dry at 60C sieve 100g to -80 mesh			WHI
RJSV	6	Saving all or part of Soil Reject			WHI
1DX2	6	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 28, 2011

CERTIFICATE OF ANALYSIS WHI11001414.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1095591	Silt	2.452	2.0	45.8	21.0	99	2.3	25.5	16.2	405	3.01	17.8	3.5	1.6	17	0.2	1.1	0.3	39	0.05	0.096
1095600	Silt	1.856	2.1	62.8	23.5	130	3.0	37.3	31.1	744	3.60	20.7	6.3	1.9	18	<0.1	1.2	0.3	39	0.02	0.098
1095815	Silt	2.712	1.3	17.7	12.5	120	0.2	24.8	4.5	71	0.98	7.6	1.7	1.3	28	0.7	1.0	<0.1	32	0.40	0.057
1274354	Silt	3.648	23.0	55.1	14.7	710	0.4	89.5	7.7	208	1.70	19.0	1.7	2.7	78	5.3	4.4	0.1	72	2.48	0.146
1284502	Silt	1.428	5.2	20.4	8.6	74	0.4	20.9	2.3	92	0.65	8.0	0.5	0.9	51	1.0	2.9	0.1	55	0.37	0.041
1284503	Silt	2.162	3.1	37.4	9.2	185	0.6	29.2	5.8	342	1.30	11.5	2.6	1.7	53	2.4	2.7	0.1	49	0.61	0.133

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 28, 2011

CERTIFICATE OF ANALYSIS WHI11001414.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1095591	Silt	4	24	0.18	609	0.002	<1	1.13	0.004	0.05	<0.1	0.09	3.4	0.1	0.05	3	1.0	<0.2
1095600	Silt	3	24	0.16	331	0.002	<1	1.24	0.003	0.06	<0.1	0.13	4.6	0.1	0.05	3	1.2	0.2
1095815	Silt	4	9	0.19	475	0.001	<1	0.40	0.002	0.03	<0.1	0.15	1.1	0.1	<0.05	1	0.5	<0.2
1274354	Silt	8	11	0.81	409	0.002	2	0.32	0.003	0.07	<0.1	0.24	2.5	0.5	0.06	<1	1.8	<0.2
1284502	Silt	2	7	0.08	471	<0.001	2	0.21	0.002	0.06	<0.1	0.14	1.3	0.4	<0.05	<1	1.4	<0.2
1284503	Silt	7	12	0.15	654	0.002	1	0.53	0.002	0.06	0.1	0.51	1.6	0.2	<0.05	1	2.8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 28, 2011

QUALITY CONTROL REPORT WHI11001414.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Reference Materials																					
STD DS8	Standard	12.3	106.9	120.0	300	1.6	37.6	7.4	569	2.34	22.6	103.7	6.4	64	2.1	5.3	6.6	44	0.64	0.073	13
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 28, 2011

QUALITY CONTROL REPORT WHI11001414.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Reference Materials																	
STD DS8	Standard	110	0.57	242	0.099	2	0.87	0.108	0.40	2.5	0.19	2.7	5.0	0.08	4	4.6	4.5
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 14, 2011
Report Date: November 10, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001432.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #25
P.O. Number
Number of Samples: 3

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	3	Dry at 60C sieve 100g to -80 mesh			WHI
RJSV	3	Saving all or part of Soil Reject			WHI
1DX2	3	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 10, 2011

CERTIFICATE OF ANALYSIS WHI11001432.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1095597	Silt	3.9	27.9	16.4	280	0.3	69.1	14.6	348	3.07	21.0	2.0	1.3	35	1.5	2.6	0.2	32	0.24	0.088	4
1095118	Silt	5.7	28.5	16.3	193	0.4	32.2	10.3	223	2.80	22.5	2.0	1.3	46	0.5	4.5	0.2	31	0.20	0.089	2
1095808	Silt	4.5	32.8	13.7	176	0.4	42.9	11.2	372	2.39	14.7	3.9	2.1	49	0.9	2.1	0.2	48	0.29	0.096	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 10, 2011

CERTIFICATE OF ANALYSIS WHI11001432.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1095597	Silt	13	0.15	757	0.001	4	0.71	0.004	0.07	<0.1	0.13	2.9	0.2	0.10	2	2.7	<0.2
1095118	Silt	12	0.14	661	<0.001	3	0.61	0.004	0.09	<0.1	0.07	2.4	0.3	0.14	2	3.2	<0.2
1095808	Silt	19	0.30	776	0.007	2	0.88	0.006	0.07	0.1	0.15	2.9	0.1	<0.05	3	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 10, 2011

QUALITY CONTROL REPORT WHI11001432.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Reference Materials																					
STD DS8	Standard	11.4	98.1	118.1	287	1.8	33.9	6.5	565	2.28	23.6	103.5	6.0	68	2.3	5.5	6.3	37	0.64	0.073	14
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: November 10, 2011

QUALITY CONTROL REPORT WHI11001432.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Reference Materials																	
STD DS8	Standard	103	0.56	269	0.105	3	0.89	0.102	0.42	2.8	0.20	2.9	5.1	0.13	5	4.6	5.0
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Submitted By: Linda Dandy
Receiving Lab: Canada-Whitehorse
Received: September 22, 2011
Report Date: October 29, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11001472.1

CLIENT JOB INFORMATION

Project: Oro Property
Shipment ID: #19
P.O. Number
Number of Samples: 7

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
STOR-RJT-SOIL Store Soil Reject - RJSV Charges Apply

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
SS80	7	Dry at 60C sieve 100g to -80 mesh			WHI
RJSV	7	Saving all or part of Soil Reject			WHI
1DX2	7	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Colorado Resources Ltd.
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6
Canada

CC: Dugald Dunlop
Adam Travis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 29, 2011

CERTIFICATE OF ANALYSIS WHI11001472.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1274352	Silt	2.126	13.5	100.1	22.0	1366	2.1	128.8	12.2	519	2.91	16.8	13.2	1.1	106	7.4	5.4	0.3	171	0.67	0.224
1095800	Silt	1.61	7.4	91.5	12.8	521	1.0	72.3	7.9	289	2.33	12.2	10.1	1.9	75	3.4	3.7	0.2	114	1.02	0.158
1095801	Silt	1.804	25.7	44.9	11.2	1292	0.7	180.9	6.7	212	1.56	23.3	1.3	1.2	71	8.5	6.0	0.1	176	0.96	0.112
1095802	Silt	2.286	7.3	85.1	11.9	270	1.0	45.9	6.5	203	1.92	10.9	7.6	1.9	89	1.8	4.0	0.2	100	0.82	0.167
1095803	Silt	1.558	26.9	169.8	13.5	9020	1.8	754.6	86.2	3039	2.88	28.1	4.1	2.6	105	53.6	11.1	0.2	193	1.47	0.212
1095589	Silt	1.204	11.1	53.5	19.6	137	1.8	32.6	5.5	127	2.74	18.0	3.2	1.1	39	0.3	3.2	0.2	66	0.09	0.100
1095590	Silt	1.018	5.9	44.7	12.2	330	0.5	99.5	14.6	634	2.05	13.4	2.7	1.5	46	2.3	2.1	0.2	56	0.72	0.102

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 29, 2011

CERTIFICATE OF ANALYSIS WHI11001472.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1274352	Silt	13	20	0.16	1123	0.003	4	0.62	0.003	0.12	<0.1	0.96	3.1	0.4	0.13	2	8.3	<0.2
1095800	Silt	13	20	0.40	638	0.004	5	0.96	0.004	0.13	<0.1	0.62	2.9	0.4	0.07	3	2.1	<0.2
1095801	Silt	8	15	0.13	496	0.002	3	0.56	0.003	0.07	0.2	0.47	1.9	2.2	0.07	2	3.2	<0.2
1095802	Silt	11	17	0.33	574	0.003	4	0.80	0.003	0.14	0.1	0.50	2.4	0.3	0.08	3	2.4	<0.2
1095803	Silt	14	28	0.65	863	0.002	5	1.10	0.003	0.10	<0.1	0.90	3.5	0.7	0.17	2	9.9	<0.2
1095589	Silt	5	19	0.08	688	0.002	2	0.67	0.002	0.06	<0.1	0.37	3.0	1.1	0.06	2	4.0	<0.2
1095590	Silt	7	14	0.16	918	0.002	2	0.73	0.004	0.07	0.1	0.28	2.4	0.2	0.07	2	2.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 29, 2011

QUALITY CONTROL REPORT WHI11001472.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1095800	Silt	1.61	7.4	91.5	12.8	521	1.0	72.3	7.9	289	2.33	12.2	10.1	1.9	75	3.4	3.7	0.2	114	1.02	0.158
REP 1095800	QC		7.2	91.2	12.7	513	1.0	73.0	8.0	281	2.32	12.2	8.8	1.9	74	3.3	3.6	0.2	111	1.00	0.160
Reference Materials																					
STD DS8	Standard		13.9	113.9	129.3	326	1.8	40.9	8.1	642	2.58	24.2	117.6	6.9	65	2.3	5.5	6.1	46	0.71	0.081
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Colorado Resources Ltd.**
110 - 2300 Carrington Road
West Kelowna BC V4T 2N6 Canada

Project: Oro Property
Report Date: October 29, 2011

QUALITY CONTROL REPORT WHI11001472.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1095800	Silt	13	20	0.40	638	0.004	5	0.96	0.004	0.13	<0.1	0.62	2.9	0.4	0.07	3	2.1	<0.2
REP 1095800	QC	13	19	0.39	638	0.004	4	0.96	0.003	0.13	<0.1	0.64	2.9	0.3	0.06	3	2.3	<0.2
Reference Materials																		
STD DS8	Standard	16	124	0.64	272	0.118	2	0.95	0.097	0.43	3.1	0.18	2.0	5.6	0.14	5	5.3	5.2
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.