Assessment report for fieldwork carried out on the VIP claims, nts 115J13

Dawson Range, Yukon

June 12th through July 5th, 2011

For Goldspike Exploration

Work done by Druid Exploration Inc.

Dawson City, YK

Stuart Fraser, P. Geol.

July 16, 2011

Appended: November, 2012

TABLE OF CONTENTS

1.0 INTRODUCTION 1
- 1.1 Location and Access 1
- 1.2 Physiography, Drainage and Climate 2
- 1.3 Claim Status 2
- 1.4 Permitting 2

2.0 PREVIOUS HISTORY 6

3.0 GEOLOGICAL SETTING 7
- 3.1 Regional Geology 7
- 3.2 Property Geology 7, 8
- 3.3 Geophysics 8
- 3.4 Mineralization and structure 8

4.0 2011 FIELDWORK 14
- 4.1 Methodology 14
- 4.2 Fieldwork mapping and sampling 14
- 4.3 Fieldwork results 14, 15

5.0 CONCLUSIONS AND RECOMMENDATIONS 23

6.0 COSTS 23, 24

7.0 STATEMENT OF QUALIFICATIONS 25

References 26

RESULTS ADDENDUM 27

FIGURES

Figure 1: Regional Location Map 3
Figure 2: Glaciation in the Dawson Range (Bond and Lipovsky, 2011) 4
Figure 3: Claim Map 5
Figure 4: Dawson Range Mineral Belt (after Bennett et al., 2010) 9
Figure 5: Regional geology (after Bremner, 2010) 10
Figure 6a, 6b: Coffee Gold project, property geology & mag (Wainwright et al., 2010) 11
Figure 7: VIP mag interpretation (from Sheldrake, pers comm.) 13
Figure 8: Grab samples & silts collected from 2011 fieldwork at VIP 16
Figure 9: Tempelman-Kluit GSC map, modified from Vivian (2011) 20
Figure 10: Silt and grab sample locations, 2011 VIP fieldwork 21
Figure 11: 2011 VIP soil sample lines and prospector's soil sampling 22
Figure 12: Sample geochemistry - Gold 28
Figure 13: Sample geochemistry - Arsenic 29
Figure 14: Sample geochemistry - Antimony 30
Figure 15: Sample geochemistry - Copper 31

PLATES

Plate 1: Hand staked boulders along tributary draining south into Big Creek 6
Plate 2: View looking northwest toward Franz Cu occurrence 12
Plate 3: Sericitized schist from the Franz Cu occurrence with chalcedonic quartz 16
Plate 4: Strongly silicified and sericitized schist with fine grained pyrite.....17
Plate 5: Large outcrop of silicified schist west of the Mick claims, VIP property.....17
Plate 6: Sheared and silicified schist.....18
Plate 7: Stibnite-filled fractures in silicified schist from VIP property.....19

APPENDICIES

Appendix 1: Claim status 32
Appendix 2A: Rock sample descriptions and locations 51
Appendix 2B: Silt sample descriptions and locations 65
Appendix 2C: Prospector's soil sample descriptions and locations 67
Appendix 2D: Soil sample locations.....71
Appendix 3A: Rock sample assay certificates.....95
Appendix 3B: Silt sample assay certificates.....148
Appendix 3C: Soil sample assay certificates 164

1.0 INTRODUCTION

This technical report on the VIP claims includes soil, silt and rock geochemical sampling and mapping completed during the period June 12 through July 5, 2011. This report is a follow-up to a geophysical survey carried out by Precision GeoSurveys of Vancouver in December of 2010. The above survey consisted of a magnetometer as well as a radiometric survey. The magnetic data from the 2010 geophysical survey was processed by Aurora Geosciences Ltd of Yellowknife. As the geophysical work was done in December, 2010, the radiometric data was not incorporated into the technical report (Vivian, 2011).

Vivian (2011) completed a NI 43-101 report on the VIP property, citing this property as a property of merit. Vivian (2011) based this view on geophysical interpretations of the magnetic 2010 survey and proximity to both Kaminak's Coffee Creek gold project, (12km to the east) and Kinross's White Gold project to the north.

During the 2011 period, a total of 1000+ soil samples, 60 silts and 324 rock samples were collected from within the VIP claim block. The author ran several traverses and collected attitudes from numerous outcrops available. Soil sampling was mainly carried out by two soil sampling teams using augers and using GPS units preloaded with 50m spaced locations along designated lines.

In 2011, geophysicist Ron Sheldrake, (pers. comm.) reviewed the raw data from the 2010 Precision geophysical survey and a copy of his interpretation is illustrated below. Sheldrake interpreted distinct linear features trending northwesterly and suggested a probable fold to the east of the Mick claims. The Mick claims consist of a block of claims which lie within the VIP block of claims. The Mick claims are held by Shawn Ryan of Dawson. Sheldrake also interpreted a strong magnetic feature in the northern portion of the VIP claims as well as a potential alteration zone or breccia, (mainly within the Mick Claims), extending northerly into the VIP claim block near the headwaters of Wolf Creek. Sheldrake interpreted this alteration zone, based on a break of linear features.

1.1 Location and Access

The VIP property is located within NTS mapsheet 115J13 and parts of 115O/4 and 115K/16 in western Yukon. The property is situated ~120km south of Dawson City, to the east of the White River, Figure 1. The claim group lies within the Whitehorse Mining District. Access to the property at present is only by helicopter. A narrow, gravel airstrip at Thistle Creek, just north of the Yukon River is ~25km north of the VIP property. There is river access (five months of the year) provided by a barge landing on the Yukon River, approximately five km west of the Thistle airstrip. Winter road access to Thistle airstrip may be available from Pelly Farm.

1.2 Physiography, Drainage and Climate

The VIP property falls within the Dawson Range which is a northwest-trending mountain range in western Yukon, stretching for over 100km (Bond and Lipovsky, 2011). The area consists mostly of broad, rounded, unglaciated valleys (Figure 2). Permafrost is commonly found on north-facing slopes, particularly where there has been no recent forest fires. Bond and Lipovsky (2011) recently completed a three year study to provide baseline surficial geology applicable to mineral exploration in the northern Dawson Range. The authors suggest that widespread Pleistocene eolian loess deposits, (wind blown silt), form close to the White River and may complicate the collection and interpretation of geochemical data. The VIP property is protected from this wind blown silt from the White River and is therefore an effective area for soil sampling residual soils.

The climate of the region is described as cold and semi arid. Mean annual temperature is between -4 and -8 deg C and annual precipitation estimated at 300mm (Bond and Lipovsky, 2011).

1.3 Claim Status


The VIP property is comprised of 772 claims covering some 156 sq km. In addition the property consists of several other claims (XT claims) acquired as part of an agreement with adjoining property holder SilverQuest Resources. The technical report by Vivian (2011) included 403 claims, while the present report includes an expanded VIP block of claims as illustrated in Figure 3. Claim status and particulars are listed in Appendix 1.

All claims listed within the block of VIP claims were ground staked and conform to regulations under the Yukon Quartz Mining Act. The locations of posts were recorded in NAD83 with handheld global positioning units.

Three additional claims were staked on open fractions within the VIP block by Franz Vidmar on June 16, 2011. The details for these claims are not included here, at this time.

1.4 Permitting

Fieldwork at VIP carried out in June and July 2011 fell under a Class 1 exploration permit and as such there was a minimal environmental footprint. No fuel spills occurred and no trenching was carried out. Sampling consisted of auger work for soil sampling targeting C Horizon soils and grab rock chip samples recorded in GPS units.



Regional Location Map

Figure 1

.




Figure 2 Glaciation in the Dawson Range (Bond and Lipovsky, 2011)

VIP Property

Fig. 3: Claim Map

Goldspike Exploration Inc.

White River area,
Whitehorse Mining District

Group 1 (748 claims)

Group 2 (24 claims)

Legend

- VIP property
- Yukon quartz claims

1:35,000

0 700 1,400 2,800 4,200 5,600 Meters

Author: Dan Ferraro
Date: June, 2012
Mapsheets: 115J13, 115K16, 115O04
Datum: UTM NAD83 Zone 7

2.0 PREVIOUS HISTORY

The VIP property has had no previous documented hardrock or placer claim activity, or fieldwork reported in Yukon assessment files. While no placer work was reported, Tom Morgan, a Dawson prospector and staker of the VIP claims, noted boulders placed along the edge of a tributary flowing into Big Creek (Plate 1). Morgan interpreted the stacking of these boulders as reasoning for early, undocumented placer activity within the VIP property.

Vivian, (2011) has documented Minfile mineral occurrences in the area regionally.

Prospector International Resources Inc. working in the Coffee Creek area delineated a gold anomaly of 400 x 900 meters defined by gold-in-soil values up to 694ppb Au with co-incident As, Sb and Hg, (Jaworski and Vanwermeskerken, 2001). That area is now part of Kaminak's Coffee Gold project (Wainwright et al, 2011) where diamond drilling has confirmed gold mineralization in several zones.



Plate 1 Hand stacked boulders found at creek north of the VIP camp suggesting early undocumented placer activity.

3.0 GEOLOGICAL SETTING

3.1 Regional Geology

The VIP property lies within the Yukon-Tanana Terrane, which extends from British Columbia through the Yukon into Alaska. This terrane is bounded to the northeast by the Tintina Fault and to the southwest by the Denali Fault (Figure 4).

The Yukon Tanana Terrane was accreted to the western North American craton between the late Paleozoic and early Cenozoic. During middle Paleozoic time, this terrane rifted southward causing a right lateral displacement of greater than 125km along this major fault. Quartz rich schists and gneisses make up much of this terrane with amphibolitic grade metamorphism.

Mid Cretaceous intrusive rocks such as the Klotassin Batholith to the south of the VIP property (Tempelman-Kluit, 1974) have been associated with mineralization within the Tintina Gold belt which forms an arcuate belt extending from Alaska through central Yukon and including deposits such as Pogo, Fort Knox and Dublin Gulch (Figure 5, after Bremner, 2010). More recently these Cretaceous intrusions host gold mineralization which is interpreted to be structurally controlled as at the Kaminak Coffee Creek project within what is now referred to as the White Gold District, Yukon (Figure 6).

3.2 Property Geology

The VIP property geology consists of mainly quartz feldspar muscovite and chlorite schist, locally biotite gneisses and mafic schists. In addition intrusive rocks including biotite granodiorite to granite have been identified as well as ultramafic rocks including variably serpentinized peridotite. In the northern part of the property, granodiorite has been mapped and its continuance to the east is not clear.

A peridotite intrusion with a strong magnetic signature is well illustrated in Sheldrake's (Figure 7) interpretation of the raw geophysical flight data from the 2010 magnetic survey flown by Precision Geosurveys (Vivian, 2011). The peridotite is weakly serpentinized and magnetite rich. Tempelman-Kluit's (1975, Figure 8) mapping illustrates additional ultramafic units/complexes, but from the 2011 fieldwork, only thin, highly deformed and very strongly, chloritized schists are mapped.

From the geophysics, (Sheldrake, pers comm.) it is very clear there are northwesterly structures which show magnetic trends with co-incident magnetic lows. Foliation attitudes within the quartz muscovite $\pm$ feldspar-bearing schists typically reflect these attitudes (generally 320

degrees). A marble unit mapped up to 10m thickness, is shown on our mapping and is consistent with this same 320 degree attitude. Folding is also apparent (Plate 2) and is also

illustrated from Tempelman-Kluit's (1974) fieldwork where he documents folding within the present Mick claims and in the VIP ground north of the Mick claims (Figure 9).

3.3 Geophysics

As mentioned above, Ron Sheldrake (pers comm.) re-interpreted the raw geophysical data from the Precision GeoSurveys data carried out in December 2010. Vivian's (2011) NI 43-101 report with his interpreted geophysics is reproduced as Appendix 3 in this report.

In addition to the magnetic high illustrated in the northern portion of the VIP property, Sheldrake (pers comm.) interpreted an alteration zone (Figure 7) within the Mick Claims which he suggests extends north into the VIP claims. Sheldrake based this possible alteration or breccia zone on disruption of linear features in this area. Sheldrake further interpreted a fold structure from the linear features.

3.4 Mineralization and structure

From exploration results from 2008 through 2010, a regional framework has developed suggesting mineralization in the White Gold District is Early to mid Cretaceous (Bennett et al, 2010). They suggest an intimate association between mineralization and prominent long lived first order NW trending regional structures and related coeval north and east trending structures. Structurally controlled mineralization at Kaminak's Coffee Gold project appears consistent with this (Figure 7).




Figure 4 Simplified terrane map of the central Yukon. Red polygon outlines the Dawson Range Mineral Belt of western Yukon (Bennett et al., 2010).




Figure 5 Regional geology of the area (after Bremner, 2010).




Figure 6 (a) Coffee Gold project property geology map displaying lithologies, structures and drill collar locations. **(b)** map of ground magnetic data and interpreted structures. Coordinate system is UTM NAD83 zone 7; taken from Yukon Exploration and Geology, Wainwright et al, (2010).




Plate 2 View looking northwest toward Franz Cu occurrence, VIP property. Folding evident in schist with possible axial fold mineralization in hinge of possible syncline.




Figure 7 VIP magnetic interpretation

4.0 2011 FIELDWORK

4.1 Methodology

Mapping at the VIP property in June and July 2011 revealed mainly quartz muscovite and quartz chlorite to biotite schists generally trending 320 to 330 degrees. A magnetic declination of 25 degrees East was used for compasses, determined through a menu in a Garmin GPS instrument.

Soil sample lines were constructed using ArcMap software with sample locations at 50m intervals. Permafrost was found to be present on north facing slopes, so these areas were generally avoided. Soil samples were collected by auger and attempts made to collect C horizon soils. An Acme Labs tag was inserted into a Kraft envelope and samples dried prior to shipping. The soil sample sites were flagged and the Acme Lab tag number marked on the flagging. The soil sampler would record relevant data at each site including NAD83 UTM coordinates and description of the soil and environment. The GPS data was daily downloaded into a Garmin software program (D.R. Garmin) and data recorded into an excel spreadsheet.

Silt samples were generally collected where prospectors or soil samplers encountered creeks. A sieve was used for selected creeks, but generally fines were taken from drainages without a sieve and collected in plastic bags.

4.2 Fieldwork mapping and sampling

A total of 324 rock samples were collected as grab samples for gold analysis. A total of 1095 soil samples were collected by the soil sampling teams with an additional 89 soil samples collected by the prospectors and the author, for a total of 1184 soil samples. In addition, 60 silt samples were collected.

Soil as well as rock samples submitted to date (July 10, 2011) to Acme Labs have had no insertion of blanks or standards for quality assurance.

4.3 Fieldwork Results

A list of rock sample numbers as well as description and UTM coordinates in NAD83 is listed in Appendix 2 of this report. At the time this report was completed, no analyses are available.

A structure to the northeast of the Mick Claims was recognized early and is referred to as the Franz Cu Occurrence. Here malachite and azurite were found in silicified schist and oxidized quartz veining by prospector Franz Vidmar. The immediate area of this occurrence has no outcrop, but is flat lying. Float here in the Dawson Ranges is effective in mapping as it has not been glaciated. Locally pervasive sericitization is also noted within quartz sericite schist with

chalcedonic quartz as quartz augens (Plate 3). The Franz Cu Occurrence lies along a northwesterly structure which is apparent on the geophysics (Figure 8). A second northwesterly trending structure lies to the southwest of the Franz structure.

To the southwest of the Mick Claims, float within strongly silicified and chloritized (sericitized ?) schist with fine grained pyrite was noted (plate 4). More of this same strongly silicified and sericitized schist with fine grained pyrite is exposed in a large outcrop to the west of the Mick Claims (Plate 5). No shearing was noted in this outcrop, but float at the top of the ridge clearly indicates shearing with slickensides (Plate 6).

Traverses carried out to the east of the Mick Claims also revealed the presence of radiating stibnite crystals as well as stibnite filling fractures (sample 1204301, Plate 7) cutting silicified quartz muscovite schist. No outcrop with stibnite was recognized, but stibnite in float is abundant.

Sample 1202259, from float, has 6-8% disseminated pyrite within quartz chlorite schist and is located approximately 1.5km north of the north end of the Mick Claims. Follow-up on this rock sample consisted of several soil samples collected down slope. Within these soil sample sites, rock debris generally consists of strongly silicified and sericitized schist with fine grained pyrite.

To help define stratigraphic relationships within the schist package, a marble (marker) bed has been traced intermittently for several kilometers northeast of the Mick Claims and within the Carlisle Creek drainage. See figure 8 below.

Figure 8 below shows grab sample locations with superimposed geophysics and northwesterly trending structures. Figure 10 shows grab sample locations throughout the VIP property and Figure 11 shows the soil sample lines (auger sampling at 50 meter intervals).




Figure 8 Grab samples and silts (in blue) collected during 2011 fieldwork at VIP.



Plate 3 Sericitized schist from the Franz Cu Occurrence with chalcedonic quartz forming augens.

Plate 4, strongly silicified and sericitized schist with py & crenulations.





Plate 5 Large outcrop of silicified schist west of the Mick Claims, VIP property.



Plate 6 Sheared and silicified schist along ridge top from previous photo from Plate 5.



Plate 7– Stibnite filling fractures in silicified schist in sample 1204301




Figure 9 Regional geology GSC mapping(from Tempelman-Kluit, 1974, and modifies from Vivian, 2011).




Figure 10 Silt and grab sample locations, VIP fieldwork, July 2011.




Figure 11 Soil sample (auger sampling) lines and prospector soil sampling, VIP property, June, July 2011.

5.0 CONCLUSIONS & RECOMMENDATIONS

Several structures trending northwesterly are defined from airborne magnetic and copper and stibnite mineralization have been detected from the VIP property. There is significant silicification and sericitization locally with fine grained pyrite in several areas of the property. Analyses are pending.

Over 1100 soil sample were collected and these samples cover areas of interest at 50m spacing.

No recommendations can be made until analyses are available. The Franz Cu Occurrence looks significant with the presence of malachite (with lesser azurite) and pervasive sericite alteration with chalcedonic quartz forming augens. Trenching in the Franz area is recommended pending favorable analytical results from this zone. Several other areas on the property appear significant based on alteration with strong silicification and sericitization. Based on the presence of stibnite located in the 2011 fieldwork at VIP and known associations of As, Sb, Ba and Mo at Kaminak's Coffee Creek Gold project, it is anticipated there will be significant gold values discovered at VIP.

6.0 COSTS

Table 1 VIP expenses

Helicopter costs	# of hrs	hourly rate	Fuel charges	**GST**	**Total costs**	
Set up VIP camp June 3 to 11th	16.7	$20, 040.00	4,785.00	1241.25	26, 966.25	
Fieldwork June 12 to July 5	50.7	48, 597.00	12,693.00	3064.68	64,355.58	
Demob VIP camp, July 6 to 9th	7.5	7,012.50	1,852.50	443.60	$9308.26	
Total helicopter hrs & charges	**74.9 hr**	**$75649.50**	**19, 330.50**	**4749.53**	**99,730.09**	**99,730.09**
Grocery charges (June)					**3675.09**	**3675.09**
Grocery charges (July)					**1,020.00**	**1,020.00**
Great River Air(fixed wing)				**777.03**	**16,317.43**	**16,317.43**
Acme Labs						
330 rocks @$28.88/sample	@5.48/sample for prep work + $23.40 for analysis				**9,530.40**	
1183 soil samples @$18.00/sample	@2.80/sample for prep work + 15.20 for analysis				**21,294.00**	
60 silt samples @$18.00/sample	@2.80/sample for prep work + 15.20 for analysis				**1,080.00**	
Estimated Acme charges						**31,904.40**

Salaries						
Stuart Fraser, P. Geol.	May 30 travel day				**600**	
	May 31 to June 11, field preparation, 12 days @600/day				**7200**	
	Fieldwork, project supervision, June 12 to July 5, 2011, 24 days @				**14,400**	
	Report writing, July 6 through July 11, 6 days @600/day				**3600**	
	July 12, Travel day, Whitehorse to Edmonton				**600**	
Ryan Liebke, Jr Geologist	Field preparation, June 5 through June 10, 6 days @$500 /day				**3000**	
	Fieldwork & tech work at VIP, June 11 though June 22, 12 days @ 500				**6000**	
Richard Daigle, technician	June 22 to July 6th @500/day				**7500**	
Catherine Dworak, sampler	June 12 to July 5, 24 days @$370				**8880**	
Thomas Barrette, sampler	June 15 to July 5, 21 days @$370				**7770**	
Myles Rusk, sampler	June 9 through July 5, including 4 days camp construction 27 days @$370				**9990**	
Conner MacKay, sampler	June 9 through July 5; including 4 days camp construction, 27 days @370				**9990**	
Marc Goldenberg, prospector	June 8 through July 5; including 5 days camp construction 28 days @$500/day				**14,000**	
Inyo Youngreen, prospector	June 8 through June 26; including 5 days camp construction 19 days @$500/day				**9,500**	
Franz Vidmar, prospector	June 12 through June 28, 17 days @500 /day				**8500**	
Tom Morgan, prospector	June 26 – June 28, July 2 –July 5, 7days @500/day				**3500**	
Trevor Fredrick	June 5 through June 15, 9 days @$350				**3150**	
Dustin Blampin	June 5 through June 12th, 7 days @350/day				**2450**	
Sam Lewis	June 11, 12th 2 days @350				**700**	
Brad Osmond	June 5 through June 12th, 7 days @350/day				**2450**	
Richard Daigle	June 22 through July 6th 15 days @$400				**6000**	
Total salaries						**$126,630**
Geological supplies	Plastic bags, Acme Labs sample tags, printers, paper, Kraft envelopes, air photos				**1000**	**1000**
Fuel (diesel, gas, propane)	2 barrels diesel fuel, 2 barrels gas, 12 20lb propane bottles				**~1000**	**1000**
Computer rental to Goldspike, pro-rated	1500/month				**1377**	**1377**
Airfares						
S. Fraser return ticket	To Whitehorse & return ticket to Edmonton				**1400**	
R. Liebke one way ticket	One way ticket to Whitehorse				**700**	**2100**
Vehicle rental (rent-a wreck), Whitehorse	1500/month				**1500**	**1500**
Charges to Goldspike	202 mandays @$100/day per manday				**$20,200**	**20,200**
Total to July 12th						***$306,452***

7.0 STATEMENT OF QUALIFICATIONS

I, Stuart Campbell Fraser of 10705-139 Street, Edmonton, Alberta Canada do hereby certify that:

1.) I am a registered professional geologist with the Association of Professional Engineers, Geologists and Geophysicists of Alberta, member number M47638.

2.) I am a graduate of Dalhousie University, Halifax, Nova Scotia with a B. Sc. In geology, 1973 and a M. Sc. in geology from the University of Alberta, 1996.

3.) I have been practicing my profession as a geologist since 1973, excluding the period to complete a Master's program at the University of Alberta.

4.) I have work experience in most areas of Canada and have worked in Honduras, Argentina and Mexico as well as three countries in Africa. As a result of my experience, working in base and precious metals, uranium and diamond exploration, I am a qualified person as defined in National Instrument 43-101.

5.) I have no direct or indirect interest, nor do I expect to receive any interest in the properties of any junior mining company and/or its subsidiaries. I am independent of any junior mining company in accordance with the application of Section 1.5 of National Instrument 43-101, nor do I expect to receive any interest in any work.

6.) I have authored several technical as well as assessment reports and have based these reports on field data collected personally & previous exploration and mining experience in Canada.

7.) I have read National Instrument 43-101, Form 43-101F1 and believe my reporting is in compliance with National Instrument 43-101.

PROFESSIONAL GEOLOGIST ALBERTA
STUART C. FRASER

Dated July 15, 2011

Stuart Campbell Fraser, P. Geol.

10705-139 Street,

Edmonton, Alberta, T5M 1P6

780-454-0266

References

Bennett, V., Colpron, M., and Burke, M., 2010, Current thinking on Dawson Range tectonics and metallogeny. Yukon Geological Survey, Misc report 2, 12p.

Bond, J. D. and Lipovsky, P.S, 2011, Surficial geology, soils and permafrost of the northern Dawson Range. *In*: Yukon Exploration and Geology 2010, K.E. MacFarlane, L. H. Weston and C. Relf (eds.), Yukon Geological Survey, p. 19-32.

Bremner, T., 2010, Overview of Goldspike Exploration properties in Yukon, Unpublished report.

Jaworski, B.J. and Vanwermeskerken, M., 2001, Geological and geochemical report on the Coffee Creek intrusion-related gold target, West central Yukon Territory: Yukon Assessment Report 094207, 53p.

Tempelman-Kluit, 1974, GSC Open File Map 16-1973, Snag, YK.

Vivian, Gary, 2011, Technical report, VIP claims, Yukon Territory, Canada prepared for Goldspike Exploration Inc, 70p.

Wainwright, A.J., Simmons, A.T., Finnigan, C.S., Smith, T.R., and Carpenter, R.L., 2011. Geology of the new gold discoveries in the Coffee Creek area, White Gold District, west-central Yukon. *In:* Yukon Exploration and Geology 2010, K.E. MacFarlane, L.H. Weston and C. Relf (eds.), Yukon Geological Survey, p. 233-247.

RESULTS ADDENDUM

Assay results were received in the months following the writing of this report. The highest gold value returned from soil sampling was 47.7 ppb Au (Figure 12). Unfortunately, no defining gold trend can be observed in the soil geochemistry. Silt samples showed more promising results. One sample assayed 1211 ppb Au and is draining an area in the south-central portion of the property. Silt samples from two tributaries draining the north-central area of the property were anomalous, returning values of 41.5 ppb Au and 21.8 ppb Au. The highest gold result in rock was 76 ppb Au; in a silicified mafic volcanic with disseminated pyrite. Other elevated gold results are found in the chlorite schists with malachite and pyrite. Arsenic is weakly concordant with gold across the property but has no strongly anomalous results (Figure 13).

Although stibnite was observed in multiple grab samples, no antimony signature was expressed in the soil geochemistry (Figure 14).

Numerous trends of weakly anomalous copper are seen on the property (Figure 15). Malachite and chalcopyrite mineralization were observed in outcrop, most frequently in the north-central area of the property. Zinc values are concordant with copper. Lead and molybdenum also show weakly anomalous signatures across the property.

Sample descriptions and results can be found in appendices 2 and 3.

Although results were not ideal in this first pass program, numerous areas of interest have been outlined. Detailed prospecting and ground geophysics (IP) may help to define a zone in the north-central area. Furthermore, much of the property has not seen any exploration. As exploration along the Coffee Creek trend continues, more information about the style of mineralization will come to light and the VIP Property should prove to be a strategic claim package.


Dan Ferraro
HBSc. Geology
Consulting Geologist
November, 2012

VIP Property

Goldspike Exploration Inc.

Gold Results

White River area,
Whitehorse Mining District



Legend

Rock samples

Au_ppb

- 0.500000 - 10.000000
- 10.000000 - 20.000000
- 20.000000 - 50.000000
- 50.000000 - 76.600000

Silt samples

Au_ppb

- 0.600000 - 10.000000
- 10.000001 - 20.000000
- 20.000001 - 50.000000
- 50.000001 - 100.000000
- 100.000001 - 1211.000000

Soil samples

Au_ppb

- 0.500000 - 10.000000
- 10.000001 - 20.000000
- 20.000001 - 30.000000
- 30.000001 - 40.000000
- 40.000001 - 47.700000
- VIP property
- VIP claims

N

1:30,000

0 600 1,200 2,400 3,600 4,800 Meters

Date: November, 2012
Mapsheets: 115J13, 115K16, 115O04
Datum: UTM NAD83 Zone 7

Fig. 13

VIP Property

Goldspike Exploration Inc.

Arsenic Results

White River area,
Whitehorse Mining District

Legend

Rock samples

As_ppm

- 0.5000 - 10.00
- 10.01 - 25.00
- 25.01 - 50.00
- 50.01 - 100.0
- 100.1 - 160.7

Silt samples

As_ppm

- 2.200000 - 2.900000
- 2.900001 - 3.600000
- 3.600001 - 4.700000
- 4.700001 - 6.300000
- 6.300001 - 9.000000

Soil samples

As_ppm

- 0.500000 - 5.000000
- 5.000001 - 10.000000
- 10.000001 - 25.000000
- 25.000001 - 50.000000
- 50.000001 - 68.800000

VIP property

VIP claims

N

1:30,000

0 600 1,200 2,400 3,600 4,800
Meters

Date: November, 2012
Mapsheets: 115J13, 115K16, 115O04
Datum: UTM NAD83 Zone 7

Fig. 14

VIP Property

Goldspike Exploration Inc.

Antimony Results

White River area,
Whitehorse Mining District

Legend

Rock samples

Sb_ppm

- 0.100000 - 0.200000
- 0.200000 - 0.700000
- 0.700000 - 1.100000
- 1.100000 - 5.500000

Silt samples

Sb_ppm

- 0.100000
- 0.100001 - 0.200000
- 0.200001 - 0.300000
- 0.300001 - 0.400000
- 0.400001 - 0.600000

Soil samples

Sb_ppm

- 0.100000 - 5.000000
- 5.000001 - 10.000000
- 10.000001 - 20.000000
- 20.000001 - 30.000000
- 30.000001 - 43.100000

- VIP property
- VIP claims

N

1:30,000

0 600 1,200 2,400 3,600 4,800 Meters

Date: November, 2012
Mapsheets: 115J13, 115K16, 115O04
Datum: UTM NAD83 Zone 7

Fig. 15

VIP Property

Goldspike Exploration Inc.

Copper Results

White River area, Whitehorse Mining District

Legend

Rock samples

Cu_ppm

- 0.300000 - 30.000000
- 30.000001 - 100.000000
- 100.000001 - 500.000000
- 500.000001 - 1000.000000
- 1000.000001 - 1260.100000

Silt samples

Cu_ppm

- 11.100000 - 14.600000
- 14.600001 - 20.000000
- 20.000001 - 24.900000
- 24.900001 - 34.500000
- 34.500001 - 62.100000

Soil samples

Cu_ppm

- 2.500000 - 30.000000
- 30.000001 - 50.000000
- 50.000001 - 75.000000
- 75.000001 - 100.000000
- 100.000001 - 155.300000

- VIP property
- VIP claims

N

1:30,000

0 600 1,200 2,400 3,600 4,800 Meters

Date: November, 2012
Mapsheets: 115J13, 115K16, 115O04
Datum: UTM NAD83 Zone 7

Appendix 1: Claim Status

Appendix 1: Claim Status

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	1	YD61501	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	2	YD61502	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	3	YD61503	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	4	YD61504	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	5	YD61505	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	6	YD61506	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	7	YD61507	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	8	YD61508	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	9	YD61509	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	10	YD61510	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	11	YD61511	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	12	YD61512	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	13	YD61513	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	14	YD61514	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	15	YD61515	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	16	YD61516	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	17	YD61517	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	18	YD61518	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	19	YD61519	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	20	YD61520	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	21	YD61521	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	22	YD61522	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	23	YD61523	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	24	YD61524	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	25	YD61525	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	26	YD61526	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	27	YD61527	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	28	YD61528	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	29	YD61529	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	30	YD61530	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	31	YD61531	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	32	YD61532	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	33	YD61533	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	34	YD61534	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	35	YD61535	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	36	YD61536	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	37	YD61537	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	38	YD61538	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	39	YD61539	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	40	YD61540	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	41	YD61541	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	42	YD61542	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	43	YD61543	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	44	YD61544	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	45	YD61545	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	46	YD61546	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	47	YD61547	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	48	YD61548	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	49	YD61549	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	50	YD61550	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	51	YD61551	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	52	YD61552	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	53	YD61553	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	54	YD61554	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	55	YD61555	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	56	YD61556	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	57	YD61557	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	58	YD61558	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	59	YD61559	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	60	YD61560	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	61	YD61561	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	62	YD61562	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	63	YD61563	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	64	YD61564	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	65	YD61565	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	66	YD61566	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	67	YD61567	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	68	YD61568	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	69	YD61569	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	70	YD61570	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	71	YD61571	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	72	YD61572	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	73	YD61573	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	74	YD61574	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	75	YD61575	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	76	YD61576	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	77	YD61577	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	78	YD61578	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	79	YD61579	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	80	YD61580	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	81	YD61581	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	82	YD61582	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	83	YD61583	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	84	YD61584	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	85	YD61585	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	86	YD61586	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	87	YD61587	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	88	YD61588	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	89	YD61589	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	90	YD61590	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	91	YD61591	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	92	YD61592	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	93	YD61593	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	94	YD61594	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	95	YD61595	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	96	YD61596	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	97	YD61597	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	98	YD61598	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	99	YD61599	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	100	YD61600	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	101	YD61631	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	102	YD61632	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	103	YD61483	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	104	YD61484	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	105	YD61485	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	106	YD61486	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	107	YD61487	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	108	YD61488	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	109	YD61489	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	110	YD61490	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	111	YD61491	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	112	YD61492	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	113	YD61493	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	114	YD61494	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	115	YD61495	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	116	YD61496	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	117	YD61497	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	118	YD61498	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	119	YD61499	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	120	YD61500	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	121	YD61477	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	122	YD61478	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	123	YD61479	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	124	YD61480	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	125	YD61481	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	126	YD61482	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	127	YD12527	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	128	YD12528	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	129	YD12529	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	130	YD12530	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	131	YD12531	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	132	YD12532	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	133	YD12533	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	134	YD12534	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	135	YD12535	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	136	YD12536	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	137	YD12537	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	138	YD12538	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	139	YD12539	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	140	YD12540	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	141	YD12541	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	142	YD12542	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	143	YD12543	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	144	YD12544	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	145	YD12545	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	146	YD12546	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	147	YD12547	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	148	YD12548	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	149	YD12549	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	150	YD12550	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	151	YD12551	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	152	YD12552	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	153	YD12553	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	154	YD12554	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	155	YD12555	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	156	YD12556	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	157	YD12557	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	158	YD12558	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	159	YD12559	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	160	YD12560	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	161	YD12561	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	162	YD12562	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	163	YD62103	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	164	YD62104	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	165	YD62105	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	166	YD62106	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	167	YD62107	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	168	YD62108	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	169	YD62109	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	170	YD62110	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	172	YD12572	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	173	YD12573	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	174	YD12574	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	175	YD12575	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	176	YD12576	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	177	YD12577	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	178	YD12578	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	179	YD12579	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	180	YD12580	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	181	YD12581	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	182	YD62112	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	183	YD62113	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	184	YD62114	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	185	YD62115	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	186	YD62116	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	187	YD62117	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	188	YD62118	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	189	YD62119	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	190	YD62120	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	191	YD62121	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	192	YD62122	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	193	YD62123	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	194	YD62124	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	195	YD62125	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	196	YD62126	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	197	YD62127	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	198	YD62128	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	199	YD62129	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	200	YD62130	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	201	YD62131	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	202	YD62132	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	203	YD62133	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	204	YD62134	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	205	YD62135	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	206	YD62136	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	207	YD62137	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	208	YD62138	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	209	YD62139	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	210	YD62140	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	211	YD62141	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	212	YD62142	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	213	YD62143	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	214	YD62144	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	215	YD62145	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	216	YD62146	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	217	YD62147	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	218	YD62148	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	219	YD62149	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	220	YD62150	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	221	YD62151	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	222	YD62152	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	223	YD62153	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	225	YD62155	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	226	YD62156	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	227	YD62157	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	228	YD62158	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	229	YD62159	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	230	YD62160	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	231	YD62161	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	232	YD62162	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	233	YD62163	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	234	YD62164	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	235	YD62165	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	236	YD62166	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	237	YD62167	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	238	YD62168	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	239	YD62169	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	240	YD62170	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	241	YD62171	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	242	YD62312	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	243	YD62313	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	244	YD62314	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	245	YD62315	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	246	YD62316	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	247	YD62317	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	248	YD62318	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	249	YD62319	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	250	YD62320	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	251	YD62321	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	252	YD62322	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	253	YD62323	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	254	YD62324	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	255	YD62325	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	256	YD62326	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	257	YD62327	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	258	YD62328	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	259	YD62329	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	260	YD62330	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	261	YD62331	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	262	YD62332	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	263	YD62333	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	264	YD62334	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	265	YD62335	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	266	YD62336	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	267	YD62337	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	268	YD62338	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	269	YD62339	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	270	YD62340	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	271	YD62341	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	272	YD62342	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	273	YD62343	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	274	YD62344	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	275	YD62345	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	276	YD62346	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	277	YD62347	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	278	YD62348	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	279	YD62349	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	280	YD62350	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	281	YD62351	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	282	YD62352	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	283	YD62353	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	284	YD62354	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	285	YD62355	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	286	YD62356	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	287	YD62357	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	288	YD62358	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	289	YD62359	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	290	YD62360	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	291	YD62361	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	292	YD62362	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	293	YD62363	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	294	YD62364	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	295	YD62365	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	296	YD62366	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	297	YD62367	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	298	YD62368	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	299	YD62369	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	300	YD62370	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	301	YD62371	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	306	YD62376	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	307	YD62377	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	308	YD61648	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	309	YD61649	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	310	YD61650	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	311	YD61651	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	312	YD61652	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	313	YD61653	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	314	YD61654	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	315	YD61655	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	316	YD61656	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	317	YD61657	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	318	YD61658	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	319	YD61659	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	320	YD61660	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	321	YD61661	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	322	YD61662	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	323	YD61663	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	324	YD61664	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	325	YD61665	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	332	YD62172	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	333	YD62173	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	334	YD62174	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	335	YD62175	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	336	YD62176	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	337	YD62177	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	338	YD62178	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	339	YD62179	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	340	YD62180	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	341	YD62181	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	372	YD61672	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	373	YD61673	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	374	YD61674	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	375	YD61675	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	376	YD61676	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	377	YD61647	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	378	YD62378	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	379	YD62379	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	380	YD62380	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	381	YD62381	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	382	YD62382	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	383	YD62383	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	400	YD62100	Goldspike Exploration Inc.	Active	Whitehorse	115J13	10/06/2017
VIP	401	YD62201	Goldspike Exploration Inc.	Active	Whitehorse	115J13	10/06/2017
VIP	402	YD62202	Goldspike Exploration Inc.	Active	Whitehorse	115J13	10/06/2017
VIP	403	YD62203	Goldspike Exploration Inc.	Active	Whitehorse	115J13	10/06/2017
VIP	404	YD62204	Goldspike Exploration Inc.	Active	Whitehorse	115J13	10/06/2017
VIP	405	YD62205	Goldspike Exploration Inc.	Active	Whitehorse	115J13	10/06/2017
VIP	406	YD62206	Goldspike Exploration Inc.	Active	Whitehorse	115J13	10/06/2017
VIP	407	YD62207	Goldspike Exploration Inc.	Active	Whitehorse	115J13	10/06/2017
VIP	408	YD62208	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	409	YD62209	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	410	YD62210	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	411	YD62211	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	412	YD62212	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	413	YD62213	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	417	YD62217	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	418	YD62218	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	419	YD62219	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	420	YD62220	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	423	YD62223	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	424	YD62224	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	425	YD62225	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	426	YD62226	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	427	YD62227	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	428	YD62228	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	429	YD62229	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	430	YD62230	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	431	YD62231	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	432	YD62232	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	447	YD62247	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	448	YD62248	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	449	YD62249	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	450	YD62250	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	451	YD62251	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	452	YD62252	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	453	YD62253	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	454	YD62254	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	455	YD62255	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	456	YD62256	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	473	YD62273	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/07/2017
VIP	474	YD62274	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/07/2017
VIP	475	YD62275	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	476	YD62276	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	477	YD62277	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	478	YD62278	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	479	YD62279	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	480	YD62280	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	481	YD62281	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	482	YD62282	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	483	YD62283	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	484	YD62284	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	485	YD62285	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	486	YD62286	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	493	YD62293	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	494	YD62294	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	495	YD62295	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	496	YD62296	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	497	YD62297	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	498	YD62298	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	507	YD12587	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	508	YD12588	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	509	YD12589	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	510	YD12590	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	511	YD12591	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	512	YD12592	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	513	YD12593	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	514	YD12594	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	515	YD12595	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	516	YD12596	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	517	YD12597	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	518	YD12598	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	519	YD12599	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	521	YD62101	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	522	YD62102	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	523	YD63653	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	524	YD63654	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	525	YD63655	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	526	YD63656	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	527	YD63657	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	528	YD63658	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	531	YD63661	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	532	YD63662	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	533	YD63663	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	534	YD63664	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	535	YD63665	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	536	YD63666	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	537	YD63667	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	538	YD63668	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	539	YD63669	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	540	YD63670	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	541	YD63671	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	542	YD63672	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	543	YD63673	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	544	YD63674	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	545	YD63675	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	546	YD63676	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	547	YD63677	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	548	YD63678	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	549	YD63679	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	550	YD63680	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	551	YD63681	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	552	YD63682	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	553	YD63683	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	554	YD63684	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	555	YD63685	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	556	YD63686	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	557	YD63687	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	558	YD63688	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	559	YD63689	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	560	YD63690	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	561	YD63691	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	562	YD63692	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	563	YD63693	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	564	YD63694	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	565	YD63695	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	566	YD63696	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	567	YD63697	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	568	YD63698	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	570	YD63700	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	571	YD63699	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	572	YD64002	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	573	YD64003	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	574	YD64004	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	575	YD64005	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	576	YD64006	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	577	YD64007	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	578	YD64008	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	579	YD64009	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	580	YD64010	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	581	YD64011	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	582	YD64012	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	583	YD64013	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	584	YD64014	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	585	YD64015	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	586	YD64016	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	587	YD64017	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	588	YD64018	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	589	YD64019	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	590	YD64020	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	591	YD64021	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	592	YD64022	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	593	YD64023	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	594	YD64024	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	595	YD64025	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	596	YD64026	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	597	YD64027	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	598	YD64028	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	599	YD64029	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	600	YD64030	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	601	YD64031	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	602	YD64032	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	603	YD64033	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	604	YD64034	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	605	YD64035	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	606	YD64036	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	607	YD64037	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	608	YD64038	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	609	YD64039	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	610	YD64040	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	611	YD64041	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	612	YD64042	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	613	YD64043	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	614	YD64044	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	615	YD64045	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	616	YD64046	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	617	YD64047	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	618	YD64048	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	619	YD64049	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	620	YD64050	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	621	YD64051	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	622	YD63902	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	623	YD63903	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	624	YD63904	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	625	YD63905	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	626	YD63906	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	627	YD63907	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	628	YD63908	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	629	YD63909	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	630	YD63910	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	631	YD63911	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	632	YD63912	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	633	YD63913	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	634	YD63914	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	635	YD63915	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	636	YD63916	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	637	YD63917	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	638	YD63918	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	639	YD63919	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	640	YD63920	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	641	YD63921	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	642	YD63922	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	643	YD63923	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	644	YD63924	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	645	YD63925	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	646	YD63926	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	647	YD63927	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	648	YD63928	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	649	YD63929	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	650	YD63930	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	651	YD63931	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	652	YD63932	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	653	YD63933	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	654	YD63934	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	655	YD63935	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	656	YD63936	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	657	YD63937	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	658	YD63938	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	659	YD63939	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	660	YD63940	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	661	YD63941	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	662	YD63942	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	663	YD63943	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	664	YD63944	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	665	YD63945	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	666	YD63946	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	667	YD63947	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	668	YD63948	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	669	YD63949	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	670	YD63950	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	671	YD63951	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	672	YD63952	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	673	YD63953	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	674	YD63954	Goldspike Exploration Inc.	Active	Whitehorse	115K16	01/06/2016
VIP	675	YD63955	Goldspike Exploration Inc.	Active	Whitehorse	115K16	01/06/2016
VIP	676	YD63956	Goldspike Exploration Inc.	Active	Whitehorse	115K16	01/06/2016
VIP	677	YD63957	Goldspike Exploration Inc.	Active	Whitehorse	115K16	01/06/2016
VIP	678	YD63958	Goldspike Exploration Inc.	Active	Whitehorse	115K16	01/06/2016
VIP	679	YD63959	Goldspike Exploration Inc.	Active	Whitehorse	115K16	01/06/2016
VIP	680	YD63960	Goldspike Exploration Inc.	Active	Whitehorse	115K16	01/06/2016
VIP	681	YD63961	Goldspike Exploration Inc.	Active	Whitehorse	115K16	01/06/2016
VIP	682	YD63962	Goldspike Exploration Inc.	Active	Whitehorse	115K16	01/06/2016
VIP	683	YD63963	Goldspike Exploration Inc.	Active	Whitehorse	115K16	01/06/2016
VIP	684	YD63964	Goldspike Exploration Inc.	Active	Whitehorse	115K16	01/06/2016
VIP	685	YD63965	Goldspike Exploration Inc.	Active	Whitehorse	115K16	01/06/2016
VIP	686	YD63966	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	687	YD63967	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	688	YD63968	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	689	YD63969	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	690	YD63970	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	691	YD63971	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	692	YD63972	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	693	YD63973	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	694	YD63974	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	695	YD63975	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	696	YD63976	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	697	YD63977	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	698	YD63978	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	699	YD63979	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	700	YD63980	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	701	YD63981	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	702	YD63982	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	703	YD63983	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	704	YD63984	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	705	YD63985	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	706	YD63986	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	707	YD63987	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	708	YD63988	Goldspike Exploration Inc.	Active	Whitehorse	115J13	07/06/2017
VIP	709	YD63989	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	710	YD63990	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	711	YD63991	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	712	YD63992	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	713	YD63993	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	714	YD63994	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	715	YD63995	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	716	YD63996	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	717	YD63997	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	718	YD63998	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	719	YD63999	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	720	YD64000	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	721	YD63801	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	722	YD63802	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	723	YD63803	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	724	YD63804	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	725	YD63805	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	726	YD63816	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	727	YD63817	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	728	YD63818	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	729	YD63819	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	730	YD63820	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	731	YD63821	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	732	YD63822	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	733	YD63823	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	734	YD63824	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	735	YD63825	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	737	YD63827	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	738	YD63828	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	739	YD63829	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	740	YD63830	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	741	YD63831	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	742	YD63832	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	743	YD63833	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	744	YD63834	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	745	YD63835	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	746	YD63836	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	747	YD63837	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	748	YD63838	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	749	YD63839	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	750	YD63840	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	751	YD62221	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	752	YD62222	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	753	YD63883	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	754	YD63884	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	755	YD63885	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	756	YD63886	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	757	YD63887	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	758	YD63888	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	759	YD63889	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	760	YD63890	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	761	YD63891	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	762	YD63892	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	763	YD63893	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	764	YD63894	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	765	YD63855	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	766	YD63856	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	767	YD63857	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	768	YD63858	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	769	YD63859	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	770	YD63860	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	771	YD63861	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	772	YD63862	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	773	YD63863	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	774	YD63864	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	775	YD63865	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	776	YD63866	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	777	YD63867	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	778	YD63868	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	779	YD63869	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	780	YD63870	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	781	YD63871	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	782	YD63872	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	783	YD63873	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	784	YD63874	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	785	YD63875	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	786	YD63876	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	787	YD63877	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	788	YD63878	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	789	YD63879	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	790	YD63880	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	791	YD63881	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	792	YD63882	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	793	YD62873	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	794	YD62874	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	795	YD62215	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	796	YD62216	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	797	YD63717	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	798	YD63718	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	799	YD63719	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	800	YD63720	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	801	YD63721	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	802	YD63722	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	803	YD63723	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	804	YD63724	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	805	YD63725	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	806	YD63726	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	807	YD63727	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	808	YD63728	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	809	YD63729	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	810	YD63730	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	811	YD63731	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	812	YD63732	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	813	YD63733	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	814	YD63734	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	815	YD63735	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
VIP	816	YD63736	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	817	YD63737	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	818	YD63738	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	819	YD63739	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	820	YD63740	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	825	YD63895	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	826	YD63896	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	827	YD63897	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	828	YD63898	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	829	YD63899	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	830	YD63900	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	831	YC86541	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	832	YC86542	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	833	YC86543	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	834	YD65754	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	835	YD65755	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	836	YD65756	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	837	YD65757	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	838	YD65758	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	839	YD65759	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	840	YD65760	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	841	YD65761	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	842	YD65762	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	843	YD65763	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	844	YD65764	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	845	YD65765	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	846	YD65766	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	847	YD65767	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	850	YD63770	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	851	YD63771	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	852	YD63772	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	853	YD63773	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	854	YD63774	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	855	YD63775	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	856	YD63776	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	857	YD63777	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	858	YD14048	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	859	YD14049	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	860	YD14050	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	861	YD14051	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	862	YD14052	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	863	YD14053	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	864	YD14054	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	865	YD14055	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	866	YD14056	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	867	YD63787	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	869	YD63789	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016

Claim Name	Claim Number	Grant Number	Claim Owner (100%)	Status	District	NTS Map Number	Claim Expiry Date
XT	7	YD51007	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	8	YD51008	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	9	YD51009	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	10	YD51010	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	11	YD51011	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	12	YD51012	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	265	YD51265	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	266	YD51266	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	267	YD51267	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	268	YD51268	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	299	YD51299	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	300	YD51300	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	329	YD51329	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	330	YD51330	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	359	YD51359	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
XT	360	YD51360	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	1000F	YD129240	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	1001F	YD129241	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	1002F	YD129242	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	1003F	YD129243	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	1004F	YD129244	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016
VIP	1005F	YD129245	Goldspike Exploration Inc.	Active	Whitehorse	115J13	01/06/2016

Appendix 2: Sample Descriptions and Locations

APPENDIX 2

Appendix 2A Rock sample locations & descriptions

Sample #	Name	Date	UTM NAD 83, Zn 7 V		Descriptions
			Easting	Northing	
1202151	SF	June 12	558048	6982983	limonite stained muscovite chlorite schist 338/68 SW; replaces wpt SF16
1202152	SF	June 12	558183	6983060	Qtz boulder0.5m in thickness with minor oxidation; replaces wpt SF18
1202157	SF	June 12	558400	6983111	replaces SF23
1202153	SF	June 12	558481	6983112	smokey qtz interbedded with musc schist; float; replaces wpt SF25
1202154	SF	June 14	558818	6983169	silicified qtz musc schist; contact aureole adjacent peridotite intrusion
1202155	SF	June 14	558836	6983150	oxidized rock (weathered?) from soil location at SF01-soil location
1202156	SF	June 14	559383	6983178	peridotite intrusion; dark greenish black, strongly magnetic, weakly serpentinized
1202158	SF	June 14	558848	6983080	peridotite inrusion, weakly serpentinized, fine grained; formerly wpt SF30
1202051	MG	June 12	558165	6983042	Quartzite with pyrite
1202054	MG	June 14	559887	6982322	Rusty fractured Qtz with K-spar
1202055	MG	June 14	559995	6982411	rusty fractured qtz with qtz musc schist
1202056	MG	June 14	560089	6982640	peridotite in part serpentinized
1202057	MG	June 14	560089	6982639	rusty fractured schist with smokey qtz
1202058	MG	June 14	559806	6982285	rusty fractured qtz within qtz musc schist
1202059	MG	June 14	559518	6982203	Marble (with qtz) with epidote & chlorite alteration
1202101	IY	June 13	560725	6980863	Quartz rock sample; 1.5m thick,230/50degSW
1202103	IY	June 13	559960	6982327	Qtz carbonate rock ; trends 340/75SW
1202104	IY	June 14	559904	6982326	Rusty fractured qtz with K-spar
1202106	IY	June 14	559983	6982594	rock sample
1202107	IY	June 14	559817	6982334	weakly brecciated qtz, fractured & rusty; frost heaved
1202108	IY	June 14	559710	6982247	chlorite & epidote alteration with qtz interbedded with marble
1202109	IY	June	559400	6983174	rusty schist with qtz; 110/49deg SW

		14			
1202110	IY	June 14	559340	6982178	mafic schist; rusty
1202111	IY	June 14	559302	6982183	smokey qtz with oxidation
1202013	FV	June 12	557859	6982976	
1202211	FV	June 14	561659	6980629	
1202002	FV	June 12	557413	6982668	rusty qtz with pyrite; chloritized
1202003	FV	June 12	557657	6982804	Qtz musc schist with epidote & py
1202004	FV	June 12	557746	6982853	Qtz vein vuggy, with limonite
1202005	FV	June 15	556438	6980304	
1202006	FV	June 12	557861	6982975	Qtz vein with malachite
1202007	FV	June 12	557838	6982957	rusty qtz vein
1202008	FV	June 12	**557862**	**6982973**	**Qtz vein with sulfides**
1202009	FV	June 12	557867	6982971	
1202010	FV	June 12	557860	6982974	Qtz vein with epidote
1202011	FV	June 12	557846	6982986	Qtz vein
1202012	FV	June 12	557855	6982977	Qtz vein with malachite & cpy trends 304deg (?)
1202014	FV	June 12	557869	6982963	schist with azurite, malachite
1202015	FV	June 12	557873	6982960	Qtz feldspar mica schist with pyrite
1202016	FV	June 12	557999	6982899	schist with qtz vein with pyrite, limonite, chlorite
1202018	FV	June 12	558152	6983035	schist with pyrite veinlet
1202019	FV	june 13	560673	6980766	start of breccia, qtz boulder
1202020	FV	june 13	560714	6980842	vuggy qtz vein with limonite
1202021	FV	june 13	560712	6980802	vuggy breccia
1202022	FV	june 13	560727	6980736	Breccia with vuggy qtz vein
1202023	FV	june 13	560768	6980714	breccia with green mineral (?)
1202201	FV	June 12	558018	6982899	rusty qtz vein with sulfides
1202202	FV	June 12	557825	6982890	schist with limonite, sulfides
1202205	FV	June 14	561588	6980790	schist with quartz, manganese, limonite
1202208	FV	June 14	561602	6980826	qtz with pyrite
1202211	FV	June 14	561659	6980629	qtz with pyrite

1202212	FV		561674	6980674	schist with oxidized breccia
1202024	FV	June 15	556191	6980451	Qtz chlorite schist, oxidized; Qtz veining shows microfolding with diss py.
1202025	FV	June 15	556182	6980484	Strongly oxidized schist; completely oxidized & partially brecciated. Rock shows evidence of shearing, NVS.
1202026	FV	June 15	556191	6980446	Chloritized schist, in part sericitized; irregular qtz veining & oxidized fractures; appears sheared; minor py.
1202027	FV	June 15	556189	6980446	Vuggy qtz musc schist, appears brecciated, has weak hematite alteration & diss py; abunt qtz overgrowths.
1202028	FV	June 15	556120	6980459	Chloritized schist with diss py 1 cm irregular quartz vein; has minor graphite & locally vugs with drusy qtz; sheared in part.
1202029	FV	June 15	556180	6980489	Qtz sericite (?) schist with shearing and moderate to strong hematite staining (alteration?) & diss py. Rock shows microfolding and is locally silicified.
1202030	FV	June 15	556147	6980735	Qtz chlorite schist with hematization & minor py as cubes. Abundant healed oxidized fractures; rock appears brecciatedis vuggy locally.
1202031	FV	June 15	556146	6980735	Chloritized schist; rock has clear & cream colored irregular qtz veining. Vuggy sections are common and have strong oxidation; appears weakly sheared.
1202032	FV	June 15	556149	6980738	Strongly oxidized & moderately brecciated chloritized schist. Minor py as cubes; minor healed fractures.
1202033	FV	June 15	556113	6980744	Chloritized schist, oxidized & having irregular qtz veining; abunt healed & oxidized fractures. Minor py.
1202063	MG	June 16	557473	6982535	chloritic altn with mics schist (close to sample 1202119)
1202064	MG	June 16	557274	6982742	apprx 50m SE of older sample # FV10052R7; breccia boulders; NVS.
1202065	MG	June 16	556992	6982635	Qtz veining within muscovite schist
1202066	MG	June 16	556847	6982614	chlorite schist next to quartzite
1202067	MG	June 16	556594	6982869	rusty with small vug in qtz; minor py.
1202068	MG	June 16	557430	6982414	breccia boulder 1m long, 5m thick; total area of brecciation ~400 x 300m
1202159	SF	June 16	555142	6972891	qtz veining and py in adjacent schist; float; **traverse run in very southeast portion of VIP claims.**
1202166	SF	June 16	557462	6973679	amphibolite float
1202070	MG	June 17	555837	6977593	Qtz muscovite schist & sulfide staining; hematite alteration throughout; strikes 151/42deg SW
1202071	MG	June 17	555848	6977554	ultramafic rock weakly serpentinized; 39m from gossan

1202072	MG	June 18	557077	6984347	dolomitic rock with sulfides; minor pyrite; minor chlorite altn
1202073	MG	June 18	557082	6984348	dolomitic rock with sulfides
1202074	MG	June 18	557089	6984344	Qtz mica schist with rusty blebs
1202075	MG	June 18	557102	6984337	rusty rock (dolomitic ?);
1202077	MG	June 18	557193	6984253	chloritized schist rock from soil sample
1202078	MG	June 18	557393	6983777	Qtz & mica schist with pyrite; strikes 330/47NE
1202127	IY	June 17	555894	6977352	Mica schist with rusty qtz & hematite alteration; minor py.
1202128	IY	June 17	555836	6977590	Qtz & mica schist with hematite staining; strike 151/42degS
1202129	IY	June 18	557092	6984306	Qtz with mica schist & chlorite alteration in boulders.
1202130	IY	June 18	557085	6984340	dolomitic rock with rusty staining; minor py.
1202131	IY	June 18	557086	6984342	Silicified breccia with sulfide; strikes 290NW
1202132	IY	June 18	557103	6984335	dolomitic rock brecciated; sulfides?
1202133	IY	June 18	557225	6984136	large qtz boulder with rusty fractures
1202134	IY	June 18	557384	6983730	fractured qtz with rusty vugs
1202135	IY	June 18	557237	6983818	rusty qtz with visible sulfides
1202136	IY	June 18	557239	6983777	chlorite alteration in mica schist with qtz vugs.
1202174	SF	June 18	557462	6983867	o/c, oxidized (partially chloritized) schist
1202175	SF	June 18	557513	6983903	Gossanous rock with magnetite still preserved; float
1202651	FV	June 17	556515	6979687	Qtz rich (chlorite) schist with abunt healed fractures (often with oxidation). Formerly wpt 049.
55py	FV	June 18	555766	6977275	Qtz veing with oxidation along fractures, minor vuggy sections, NVS noted.
1202652	FV	June 18	555766	6977281	Oxidized intrusive (?) may be partially brecciated & chloritized; NVS; formerly wpt 056.
1202653			555710	6977490	Oxidized & brecciated Qtz mus (sericite ?) schist & highly fractured & oxidized qtz veining. Abunt vuggy sections with qtz overgrowths, NVS. **Formerly wpt 058/2**
1202654	FV	June 18	555680	6977493	Qtz veining predominantly with abunt vuggy, oxidized sections with qtz overgrowths within qtz musc schist. Boxwork cavities suggest weathered sulfides. Formerly wpt 059.

1202655	FV	June 18	555678	6977498	Musc (in part chloritized) schist, NVS, strongly oxidized; boxwork cavities suggests weathered pyrite/sulfides. Formerly wpt 060.
1202656	FV	June 18	555597	6977385	Oxidized musc schist with Qtz vein boudins, minor py and commonly selvegeswhere py has weathered out. Formerly wpt 061.
1202657	FV	June 18	555596	6977387	Qtz vein highly fractured with oxidation along fractures suggest strong brecciation; abunt cavities & possibly weathered sulfide. Formerly wpt 062.
1202658	FV	June 18	555597	6977383	Cream colored & highly ffractured qtz veining with abunt vugs having strong oxidation & boxwork cavities suggestive of sulfide having weathered. Formerly wpt 063.
1202659	FV	June 18	555591	6977389	Cream colored qtz veining with abunt vugs as above, (063). Formerly wpt 064.
1202660	FV	June 18	555581	6977399	Qtz chlorite schist with irregular qtz veining & boxwork cavities, minor pyrite.
1202661	FV	June 18	555552	6977454	Qtz vein with abunt fractures & hematite staining/alteration & in part graphitic along fractures. Formerly wpt 066.
1202662	FV	June 18	555509	6977537	Qtz chlorite schist strongly oxidized with boudinaged qtz veining & abunt vugs with drusy qtz; associated shearing. Formerly wpt 069.
1202663	FV	June 18	555500	6977555	formerly wpt 070; goethite developed within oxidized muscovite (lesser qtz) schist; qtz as boudins.
1202664	FV	June 18	555537	6977594	Oxidized qtz vein within musc schist; minor vuggy sections.
1202665	FV	June 18	555583	6977613	o/c 290/65; formerly wpt 072; strongly fractured qtz vein with oxidation with musc schist; minor vuggy sections.
1202666	FV	June 18	555593	6977619	Quartz vein in o/c; formerly wpt 073. Qtz veining with strongly oxidized musc schistwallrock. Qtz vein highly broken & healed; abunt vuggy sections.
1202667	FV	June 18	555602	6977641	Formerly wpt 074; Oxidized qtz musc schist with qtz veining with cavities.
1202668	FV	June 18	555639	6977598	Quartz vein
1202672	FV	June 18	555645	6977595	Formerly 076; strongly oxidized & chloritized schist with limonite stained qtz veining; fractures with cavities & drusy qtz, NVS.
1202669	FV	June 19	555297	6986552	Light to dark grey qtz (smokey qtz) with pyrite & oxidized wallrock contacts with schist. Formerly wpt 080.
1202670	FV	June 19	555304	6986546	Formerly 081; Qtz veining with limonite staining along fractures; minor fine gr py cubes.
1202671	FV	June 19	555294	6986521	Qtz veining in contact with Qtz musc schist; formerly wpt 085.

1202673	FV	June 19	555294	6986523	Formerly wpt 086; dark green, amphibolitic (?), rock taken from creek bed; minor py.
1202674	FV	June 19	555288	6986517	Strongly hematized intrusive (?), unclear as to host rock, qtz vein has limonite stain & oxidized fractures.
1202675	FV	June 19	555291	6986515	Formerly wpt 088; qtz chlorite schist with rodded lineation & minor py.
1202676	FV	June 19	555304	6986504	Formerly wpt 089; Light brown to pink colored, quartzite (?), fracture surface has vuggy sections with abunt specular hematite; float.
1202677	FV	June 19	555334	6986401	formerly wpt 090; Qtz chlorite schist with qtz veining & tr Cpy in vein.
1202678	FV	June 19	555359	6986378	Formerly 091; Cream colored qtz veinin, highly fractured & having grey qtz veining with oxidation along fractures.
1202679	FV	June 19	555359	6986378	Formerly wpt 092; strongly silicified & brecciated rock with limonite stain. Minor py with irregular qtz veining.
1202680	FV	June 19	555376	6986281	Formerly wpt 093; Light to dark grey, banded quartzite with microfractures; NVS.
1202681	FV	June 19	555580	6984186	Formerly wpt 094. Partially oxidized biotite granodiorite; same intrusion as noted by Marc & Stu on June 20th (see wpts SF100 to 128) and SF32 o/c exposed on a ridge to the east and north of the Cu occurrence noted by Franz.
1202080	MG	June 19	557070	6984438	Dolomitic marble with pyrite @299/80NE
1202081	MG	June 19	557051	6984496	Chlorite schist wih cs gr py cubes; minor carbonate alteration; strikes 344/42degNE
1202082	MG	June 19	558085	6986000	granitic boulders with qtz & oxidation
1202083	MG	June 19	558141	6986339	black, graphitic schist with oxidation
1202084	MG	June 19	558129	6986408	possible rhyolite
1202145	IY	June 20	561981	6980762	rusty vuggy qtz, within mica & chlorite schist; close to soil sample 1033384 (Silverquest sample).
1202146	IY	June 20	561974	6980755	Banded rock with qtz; limonite stain along fractures
1202147	IY	June 20	562028	6980751	chlorite alteration with qtz veining; rusty; 325deg/85deg E.
1202148	IY	June 20	562044	6980743	Chlorite schist with vugs & limonite.
1202149	IY	June 20	562093	6980735	Brecciated & rusty qtz veining.
1202150	IY	June 20	562091	6980735	rusty qtz veining from below surface; pyrite.
1202086	MG	June 20	558282	6986410	rock sample, meta-granite with oxidation

1202190	SF	June 20	558174	6986293	dark grey, graphitic schist (resembles chert), very siliceous; locally light brown, very well banded, highly siliceous.
1202191	SF	June 20	557937	6986351	Qtz musc schist with oxidation; float.
1202192	SF	June 20	558015	6985272	
1203702	IY	June 21	557949	6981586	Qtz & musc & chlorite schist; limonite stained qtz with vuggy sections; malachite and py present
1203703	IY	June 21	557975	6981454	Qtz vein with rusty fractures; strikes 330deg; 10" wide.
1203704	IY	June 21	557947	6981552	Qtz musc schist with visible sulfides; very rusty.
1203705	IY	June 21	558074	6981738	brecciated qtz float.
1203707	IY	June 21	558796	6982015	large 24" qtz vein adjacent to marble which is interbedded with musc schist;strikes 310deg/dips ??
1203708	IY	June 21	558797	6982014	chlorite schist; slightly rusty, next to qtz vein above.
1203709	IY	June 21	558965	6982066	fractured qtz with limonite stain in schist
1203710	IY	June 21	558994	6982102	fractured chlorite schist
1202093	MG	June 21	557968	6981461	Qtz vein ~1 foot wide with oxidized ffractures; trends 330
1202094	MG	June 21	557946	6981602	Chlorite (qtz) schist with cs gr py
1202095	MG	June 21	558198	6981757	qtz with graphite as float
1202096	MG	June 21	558765	6981994	marble o/c @330/22deg E
I033381	FV	June 20	561980	6980761	Silverquest sampling
1202036	FV	June 21	552715	6978593	Altered felsic igneous rock with sulfides& hematite
1202037	FV	June 21	553015	6978002	Altered felsic igneous rock, rusty (formerly wpt 102)
1202038	FV	June 21	553452	6977096	Qtz vein with limonite in musc qtz schist
1202039	FV	June 21	553498	6977113	altered felsic igneous rock, greensh colour with diss sulfides
1202040	FV	June 21	553909	6977161	Qtz vein float
1202041	FV	June 21	553922	6977166	altered felsic igneous rock with sulfides (formerly wpt 106)
1202042	FV	June 21	553924	6977191	schist with limonite
1202043	FV	June 21	553898	6977176	formerly wpt 109; altered felsic igneous rock
1202044	FV	June 21	553894	6977180	altered felsic igneous rock
1202034	FV	June 21	552846	6978456	**quartz vein with sulfide, limonite float

1202035	FV	June 21	552915	6978328	**Quartz with limonite, sulfide in folded schist; float
1202196	SF	June 23	553350	6977325	chloritized & silicified schist; NVS.
1202197	SF	June 23	553325	6977327	chloritized & silicified schist with fn gr py.
1202198	SF	June 23	553297	6977331	as above with abunt py.
1202199	SF	June 23	552600	6977500	Strongly chloritized & silicified schist (?); has light greenish mineral (?); abunt py.
1202200	SF	June 23	552999	6978047	Strongly oxidized & silicifies schist with oxidation; minor fine grained py.
1202097	MG	June 23	553139	6977568	mica schist with oxidation
1202099	MG	June 23	553080	6977740	epidote alteration of chlorite schist; shows strong crenulation folding
1202100	MG	June 23	553063	6977788	chlorite mica schist with augite (?)
1202601	MG	June 23	552956	6977988	oxidized micaceous schist
1203711	IY	June 23	553131	6977565	rusty schist with qtz
1203713	IY	June 23	553081	6977705	chlorite schist; rusty section; NVS. Miceous schist, float.
1203714	IY	June 23	553037	6977891	Float; same chlorite schist with yellow sulfide stain.
1203715	IY	June 23	553034	6977900	oxidized chlorite mica schist
1203716	IY	June 23	552981	6977951	qtz with mica schist, oxidized fractures.
1203717	IY	June 23	552948	6978125	Qtz boulder with cavities; oxidized fractures with drusy qtz.
1203719	IY	June 24	558980	6983145	granite or gneiss with chlorite alteration ?
1203721	IY	June 24	559429	6983151	marble, re-crystallized ls.
1203722	IY	June 24	559804	6983174	mafic unit, with oxidation along fractures.
1203723	IY	June 24	559975	6983200	qtz veining? Oxidation
1203724	IY	June 24	**560100**	**6983193**	**Qtz and schist; strike 018/60SE ?**
1202603	MG	June 24	559792	6983181	mafic unit ??
1202604	MG	June 24	559981	6983199	muscovite schist; 036/76NW
1202605	MG	June 24	560102	6983198	silicified felsic dyke; strikes 018/60deg ESE
MARBLE	MG	June 24	559989	6983204	strikes 024 deg; float
1202046	FV	June 23	553397	6977304	silicified folded & chloritized rock (schist?) w/ sulfides
1202047	FV	June 23	553367	6977309	schist with limonite

1202048	FV	June 23	553036	6977585	dark chlorite schist with pyrite
1202049	FV	June 23	553052	6977877	dense quartz, chlorite schist epidotized with veinlets containing specular hematite and malachite
1202050	FV	June 23	552861	6978482	vein qtz with py
1202219	FV	June 24	558765	6980934	chloritized schist with microfractures.
1202220	FV	June 24	559258	6981228	schist with chlorite, weakly magnetic
1202221	FV	June 24	557182	6982600	vein qtz with py
1202222	FV	June 24	556998	6982747	brecciated chlorite schist with drusy quartz & py.
1202683	SF	June 24	552050	6979093	Strongly silicified & chloritized schist with crenulation folding & fn gr py.
1202684	SF	June 24	552023	6979063	3m composite grab from o/c.
1202685	SF	June 24	552021	6979065	composite grab
1202687	SF	June 24	551579	6979332	strongly chloritized & silicified schist float with py (next to creek).
1202688	SF	June 24	551342	6979238	qtz chlorite schist float.
1202606	MG	June 25	551939	6980514	chlorite schist with very little qtz.
1202608	MG	June 25	551746	6980819	chlorite shist with epidote and abunt folding
1202610	MG	June 25	551433	6981118	Qtz chlorite schist with crenulation folding
1203726	IY	June 25	552156	6980196	Chlorite musc schist with brown calcite filling vugs & qtz boudins; NVS.
1203730	IY	June 25	551693	6980898	Musc chlorite schist with oxidation, float
1203731	IY	June 25	551444	6981168	rusty chlorite mica schist with vugs; minor epidote & qtz veining.
1203733	IY	June 25	550002	6981414	Chlorite schist
1203734	IY	June 26	550022	6981571	Qtz chlorite schist with microfolding, moderately oxidized.
1203735	IY	June 26	550024	6981572	Qtz veining with rusty vugs and oxidized fractures.
1203738	IY	June 26	549073	6981064	Rock taken from creek; mica schist with py
1202612	MG	June 26	550024	6981570	float as chlorite schist with epidote with sulfides; qtz boudins
1202613	MG	June 26	549989	6981860	vuggy qtz rock in creek with minor carbonate, minor galena
1202614	MG	June 26	549365	6981267	peridotite rock (magnetic) as float in Wolf Creek
1202692	SF	June 26	557153	6983377	Qtz chlorite schist with minor py, subcrop.

1202693	CM	June 26	557172	6983344	vein with drusy qtz; sulfide along oxidized fractures
1202698	SF	June 26	557243	6983756	Qtz chlorite schist with pyrite
1202699	SF	June 26	557267	6983722	strongly chloritized & silicified schist with fn gr py; crenulation folding
1202254	SF/CM	June 26	557251	6983760	chlorite (jarosite rich ?) schist; NVS.
1202700	CM	June 26	557202	6983797	Qtz veining; highly oxidized along fractures with minor py.
1202256	CM	June 26	556401	6983706	Formerly labelled CM06; qtz chlorite schist, with minor py & specularite (?);325deg/41deg SW.
1202257	SF/CM	June 26	555558	6983626	formerly labelled CM07; highly silicified & highly oxidized schist; locally vuggy.
1202259	SF/CM	June 26	555367	6983147	formerly labelled SF168; float; pyrite rich quartzite with epidote.
1202223	FV	June 25	557110	6979977	Rock silicified & chloritized (?) w/ diss py; float
1202224	FV	June 25	557164	6979793	silicified & chloritized schist with sulfides
1202225	FV	June 25	557173	6979576	silicified schist from gossanous outcrop
MC showing	MR/CM	June 25	557068	6983702	Myles_Connor showing; minor malachite in qtz musc schist
1202231	FV	June 26	559403	6978430	float
1202232	FV	June 26	559424	6978431	float
1202234	FV	June 26	560867	6979006	limonite float next to limestone (marble ?)
1202235	FV	June 26	561321	6978418	breccia outcrop, graphitic, stockwork
1202236	FV	June 26	561308	6978413	stockwork
GAL1	TM	June 27	554583	6983598	
PY1	TM	June 27	555367	6983147	
QTZ1	TM	June 27	554578	6983825	
VIP	TM	June 27	557158	6982686	
VIP-R15	TM	June 27	554695	6983436	resample of 2010 qtz vein
1202616	MG	June 27	554670	6983466	Vuggy qtz with sulfides, fractured & oxidized.
1202617	MG	June 27	**554584**	**6983598**	**Bull qtz with sulfides including galena**
1202618	MG	June 27	555786	6983294	Gossan area with sulfides in qtz & schist
1202242	SF	June 29	558584	6980607	Qtz chl schist
1202243	SF	June 29	558610	6980642	Qtz chl schist with minor py

1202245	SF	June 29	558622	6980889	qtz chl schist with abunt pyrite (2-3%)
1202246	SF	June 29	558654	6980894	Qtz chl schist with strong oxidation; subcrop
1202250	SF	June 29	559300	6981230	qtz musc schist
1202260	SF	June 29	559387	6981244	qtz musc schist
Marble	SF	June 29	559336	6981260	4m exposed in o/c; gps reading at north end of o/c
1202619	MG	June 29	558573	6980532	Qtz chlorite schist with qtz boudins & minor py
1202620	MG	June 29	558564	6980688	Qtz chl schist with boudins, epidote & hematite alteration
1202621	MG	June 29	558539	6980789	**specular hemate in qtz; probable stibnite
1202622	MG	June 29	558689	6980851	Qtz chl schist with epidote altn and py
1202623	MG	June 29	558829	6980999	Oxidized vuggy qtz & hematite altn; strikes 300deg
1202624	MG	June 29	558969	6981093	Qtz chl schist; strokes 334deg; minor py.
1202625	MG	June 29	559280	6981236	chl musc schist with qrz boudins; minor oxidation.
1202626	MG	June 30	556698	6984765	Qtz chlorite musc schist with qtz boudins & minor py.
1202627	MG	June 30	556675	6984734	large qtz vein outcropping on hillside 1.5m x 3m in length; minor oxidation with tr py.
1202628	MG	June 30	556603	6984769	Large boulder of white qtz with abunt fractures & cs py cubes to 12cm
1202629	MG	June 30	556275	6984703	Qtz musc schist with qtz boudins; float; NVS.
1202275	SF	June 30	555148	6983116	strongly silicified & chloritized schist with very fn gr py.
1202265	SF	June 30	555114	6983133	Float; strongly crenulated & siicified (sericitized ?), chlorite schist; with fn gr py.
1202269	SF	June 30	555008	6983201	Strongly chloritized schist with cs gr py cubes.
1202270	SF	June 30	554980	6983211	Float, strongly silicified, Qtz chlorite schist with crenulations & minor py.
1202273	SF	June 30	554487	6983443	Float; qtz musc schist with minor py.
1202276	SF	June 30	554912	6984234	float, replaces wpts SF231; oxidized & hematized schist
1202277	SF	June 30	558717	6980895	rock from soil sample location 1202247; chlorite schist strongly contorted within a fault zone.
1203651	MR	July 1	556396	6980225	chlorite schist with cs gr py, minor biotite & epidote; foliation 252/48degSE.
1203652	CM	July 1	556398	6980222	from same o/c as above
1203653	MR	July 1	556351	6980271	O/c; Chlorite musc schist with quartz & py xtals to 1mm; foliation 248/52SE

1203654	MR	July 1	556271	6980439	O/c; qtz chlorite schist with fn gr py & tr malachite (?)
1203655	CM	July 1	556189	6980476	O/C; Qtz musc schist with oxidation & highly silicified; fn gr sulfide.
1203656	CM	July 1	555890	6980854	Float; Qtz musc schist with fn gr sulfide; highly strained.
1203657	CM	July 1	555736	6980903	Qtz vein cutting serpentinized schist with minor py in qtz veining.
1203570	MR	July 1	554895	6981688	
1202631	MG	July 1	555850	6984950	boulder float; sulfides & magnetite near creek; probable calc-silicate (possibly vesuvianite, skarn mineral ?).
1202632	MG	July 1	555851	6984811	highly silicified musc schist with hematite stain, chlorite; specular hematite along joints,
1202633	MG	July 1	556003	6984465	Hematite alteration of highly silicified musc (± chlorite) schist
1202635	MG	July 2	563942	6982615	Chlorite altered biotite schist with qtz boudins; has dark grey to black xtals (?), strike 353/59degNE
1202637	MG	July 2	563827	6982621	granodiorite, very fn gr.
1202640	MG	July 2	563165	6982977	highly silicified musc schist with qtz fracture fillings
1202278	SF	July 2	555559	6984323	Qtz feldspar biotite schist (foliated granite ?) with oxidation
1202280	SF	July 2	555336	6984805	Qtz feldspar biotite granite
1203754	TM	July 3	555447	6977391	Qtz vein grab in sericitized rock with open space limonite fill
1203755	TM	July 3	555598	6977519	Oxidized schist sericite schist with qtz veining and limonite in o/c.
1203756	TM	July 3	555598	6977519	Qtz grab out of limonitic schist with goethite and open space filling; same o/c as above.
1203758	TM	July 3	556142	6977462	Augen gneiss with open space quartz filling & blebs of epidote & stibnite
1202644	MG	July 3	550175	6978754	Chlorite mica schist with qtz boudins & py.
1202645	MG	July 3	550417	6978494	o/c; strongly crenulated chlorite schist with qtz boudins & epidote; strikes 320 deg/84degNE
1202646	MG	July 3	550532	6978483	chlorite mica schist with qtz stringers
1202648	MG	July 3	551458	6978020	Qtz musc schist with minor sulfides; minor chlorite; strikes 310/70degNE
MG-4	MG	July 4	558195	6980538	stibnite mineralization here as well
MG-5	MG	July 4	558156	6980503	broken rock in scree slope.
1202649	MG	July 4	558541	6980785	more stnibite in float here
1202650	MG	July 4	558349	6980658	muscovite mica schist with oxidized pockets in qtz stringers.
1204301	MG	July 4	558271	6980590	hematite alteration in a very silicified rock & having stibnite mineralization in fractures cutting foliation.

1204201	CM	July 4	558424	6980663	Quartz rich chlorite musc, garnet bearing schist; float
1204202	CM	July 4	558289	6980614	hematite stained breccia (?) with stibnite along fractures; float
1204203	CM	July 4	558255	6980558	hematite stained breccia with stibnite throughout
Cm12	CM	July 4	558271	6980585	Hematite stained breccia rich in stibnite
1203759	TM	July 4	558770	6976160	qtz stockwork with sulfide & goethite; 5m dorite ? Plug
1203760	TM	July 4	558592	6976276	Qtz vein in mafic schist; bright green oxide & stibnite mineraization.
1203761	TM	July 4	558237	6976606	goethite rich oxidized & sericite schist, minor qtz.
1203762	TM	July 4	558028	6976697	Qtz sericite, silvery grey schist with py, grey sulfide, (stibnite), along fracture planes
1203763	TM	July 4	558027	6976698	**8m from 1203762**; qtz sericite schist with qtz vein & oxidation with sulfides
1203764	TM	July 4	557971	6976749	Silt sample
1203765	TM	July 4	557936	6976776	silt on seep cutting continuation of mag low.
1203766	TM	July 4	557936	6976776	gneiss with silver sulfide on fracture taken at sample site 1203765
1202287	SF	July 4	556445	6975128	Qtz musc schist
1202288	SF	July 4	556979	6975468	strongly oxidized qtz musc schist
1202289	SF	July 4	557024	6975661	oxidized qtz musc schist; foliation 286/80deg S
1204193	MR	July 3	552487	6983795	Qtz musc schsit
1204194	MR	July 4	558554	6980778	Qtz musc schist with hematite alteration & minor py & stibnite xtals
1204195	MR	July 4	558499	6980757	Qtz boudins in a musc schist with visible sulfides.
1204196	MR	July 4	558495	6980751	Quartz with epidote along fractures; visible py.
1204197	MR	July 4	558256	6980580	Quartz with limonite, stibnite xtals & minor hematite hematite alteration; minor epidote.
1204198	MR	July 4	558203	6980559	Quartz with hematite staining & stibnite xtals.
1204676	MR	July 2	555733	6983172	
1203767	TM	July 5	556147	6980556	Augen gneiss with disseminated py, from float
1203768	TM	July 5	555891	6981183	Silicified & sericitized schist with disseminated pyrite from 2m of exposed outcrop
1202293	RD				Qtz musc schist with minor py & oxidation, minor vuggy sections
1202294	RD				Very strongly oxidized & crenulated limonite rich schist with pyrite. Taken from small pit, subcrop?
1202295	RD				Strongly oxidized, predominantly quartz with sericitized wallrock; subcrop from small pit.
1202296	RD				Quartz vein boulder from Big Creek; abundant musc schist.
1202297	RD				Weakly serpentinized ultramafic, moderately magnetic, tr pyrite; boulder from Big Creek.
1202298	RD				Highly siliceous & oxidized with pyrite.

1202299	FV				Replaces sample 1202208, tag lost; strongly oxidized musc schist with pyrite.
1202300	FV				Replaces wpt 096; Qtz veining with oxidation, minor vuggy sections
1202391	FV				Replaces wpt 099; Qtz veining with oxidation within silicified musc schist
1202392	FV				Replaces wpt 098; strongly silicified & sericitized schist with oxidation
1202393	FV				Replaces wpt 100; Qtz veining with abunt oxidation
1202394	FV				Replaces tag # 095; cs grained amphibolite (?)

Appendix 2B Silt sample locations

Sample #/wpt	Name	Date	UTM NAD 83, 7 V		Elev.	Description
			Easting	Northing	(m)	
SILT 001	MG	June 13	560078	6982245	881	Silt sample
1202053	MG	June 13	559865	6982304	960	Silt
1202069	MG	June 17	556121	6976968	733	silt sample; along tributary to Big Creek, old placer creek ?
1202188	SF	June 14	559704	6982515	900	silt sample; first marked SF01-silt; south of Cu occurrence located by FV June 12th
1202189	SF	June 14	559516	6982503	921	silt sample, marked as SF02-silt earlier; as above
1202053	MG	June 13	560078	6982245	881	
1202102	IY	June 13	560068	6982259	879	
1202105	IY	June 14	560071	6982535	864	.
1202126	IY	june 17	556181	6977077	747	Silt sample; placer creek draining into Big Creek
1202251	MR	june 17	556140	6976797		silt sample along Big Creek below VIP camp
1202252	MR	June 17	556426	6976601		as above
1202253	MR	June 17	556634	6976387		silt sample along Big Creek
1202182	SF	June 18	558512	6983699	1038	silt sample; drainage north of Cu occurrence located by FV
1202183	SF	June 18	558262	6983637	1073	silt sample
1202184	SF	June 18	558016	6983480	1126	silt sample
1202185	SF	June 18	557644	6983154	1263	silt sample; north of Cu occurrence located by FV, June 12th
1202137	IY, RL	June 19	556262	6977212	765	silt sample
1202138	IY, RL	June 19	556373	6977434	788	silt sample
1202139	IY, RL	June 19	556554	6977694	826	silt sample
1202140	IY, RL	June 19	556724	6977941	856	silt sample
1202141	IY, RL	June 19	556785	6978244	895	silt sample
1202142	IY, RL	June 19	556796	6978370	919	silt sample
1202143	IY, RL	June 19	556763	6978374	927	silt sample
1202144	IY, RL	June 19	556915	6978513	948	silt sample
1202213	FV	June 16	556388	6976144		silt sample
1202214	FV	June 19	555305	6986545	806	silt sample
1202215	FV	June 19				not recorded, half way between silt samples 1202214 & 1202216
1202216	FV	June 19	555431	6986128	838	

1202218		June 20	561,627	6980745		silt;
1203725	IY	June 24	560591	6984282	800	Silt sample; NE tributary along Carlisle Cr.
1202682	SF	June 24	552092	6979122	1048	silt sample
1202686	SF	June 24	551585	6979337	879	silt sample
1202689	SF	June 24	551221	6979150	825	silt sample
1202690	SF	June 24	551037	6979317	793	silt sample
1203736	IY	June 26	549988	6981867	633	Wolf Creek, silt sample; 3.5m wide creek; good silt location
1203737	IY	June 26	549365	6981275	602	Wolf Creek, silt sample, 4m wide.
1203739	IY	June 26	549165	6981005	598	Tributary to Wolf Creek, Silt sample; 1.5 to 2m wide.
1202615	MG	June 26	549070	6981075	599	Silt sample, main tributary into Wolf Creek.
1202255	SF/CM	June 26	556577	6983726		Formerly sample # CM05; silt sample; moderate flow, 10-15 slope
1202228	FV	June 25	556627	6978743	1004	Silt
1202229	FV	June 25	556783	6978333	910	silt
1202230	FV	June 25	556787	6978337	909	silt
1202630	MG	June 30	555919	6984691	1002	Silt sample on a tributary of Wolf Creek; 0.5m wide where sample taken.
1202641	MG	July 2	563451	6983276	926	Silt sample; only 30cm wide creek
1202274	SF	June 30	554717	6984229	940	Silt sample
1203659	CM	July 1	554895	6981688	846	silt sample, moderate flow
1202634	MG	July 1	556155	6984340	1043	Silt sample
1202759	CD/TB	July 2	553245	6981677		Silt sample
1203145	CD/TB	July 2	5522918	6980989		Silt sample
1203753	TM	July 3	554588	6977029	738	Silt sample
1203757	TM	July 3	555881	6977615	818	Silt from small tributary on edge of limonitic & chloritic schists.
1202643	MG	July 3	550106	6978824	1087	Silt sample
1202290	SF	July 4	557152	6976117	792	silt sample, Big Creek; qtz musc schist exposed along creek bank, foliation 282/30deg S.
1202291	SF	July 4	557147	6976264	795	silt sample
1203769	TM	July 5	556689	6981386	1074	silt

All samples from Zone 7 V, UTM NAD 83

Appendix 2C Soil samples from prospectors

Sample	Name	date	UTM Zone 7 V		Elevation	Description
			Easting	Northing		
1202167	SF	June 14	558834	6983180	1140	replaces soil sample SF01
1202168	SF	June 14	559023	6983186	1117	replaces soil sample SF02
1202169	SF	June 14	559233	6983207	1095	replaces soil sample SF03
1202170	SF	June 14	559383	6983182	1087	replaces soil sample SF04
1202171	SF	June 14	559559	6983156	1081	replaces soil sample SF05
1202172	SF	June 14	559281	6982588	970	replaces soil sample SF06
1202203	FV	June 12	557866	6982973	1291	Soil sample
1202206	FV	June 14	561588	6980790	945	soil
1202207	FV	June 14	561537	6980808	952	soil sample
1202209	FV	June 14	561656	6980629	992	soil sample
1202210	FV	June 14	561675	6980209	979	soil sample
1202160	SF	June 16	555423	6973033	1206	soil sample
1202161	SF	June 16	555502	6973101	1201	soil sample; clay rich, grey brown soil, 15cm depth, C Horizon.
1202162	SF	June 16	555618	6973130	1196	soil sample, 15cm depth, B/C Horizon
1202163	SF	June 16	555714	6973152	1194	soil sample; 20cm deep B horizon, hit permafrost at 20cm.
1202164	SF	June 16	555910	6973179	1191	soil sample with biotite granodiorite rock debris
1202165	SF	June 16	556786	6973305	1208	soil sample, hit permafrost at18cm; collected B horizon
1202076	MG	June 18	557193	7E+06	1284	soil sample
1202079	MG	June 18	557240	7E+06	1336	soil sample, to 30cm depth; grey clay.
1202173	SF	June 18	557241	6983747	1333	soil sample, 15cm, grey clay, C horizon, flat slope on ridge top.
1202176	SF	June 18	557547	6983914	1253	soil sample; 30cm depth, 10deg slope, predominantly qtz musc schist debris
1202177	SF	June 18	557640	6983944	1239	soil sample; 15cm depth, mainly grey clay; B, C horizon; qtz musc schist rock in hole
1202178	SF	June 18	557758	6984017	1217	soil sample; permafrost at 15cm, B horizon sampled

1202179	SF	June 18	557888	6983987	1196	soil sample; permafrost at 20cm depth; sampled only 5cm of B horizon
1202180	SF	June 18	557989	6983966	1183	soil sample from frost boil; B, C horizons (mainly grey clay)
1202181	SF	June 18	558174	6984030	1151	soil sample; 40cm depth, 5-8% slope, B horizon, predominant rocks quartzite
1202085	MG	June 20	558281	6986411	1200	soil sample; 30cm depth, light brown soil, B horizon
1202087	MG	June 20	558254	6986318	1200	soilsample; 40cm depth, lt brown soil, b horizon
1202088	MG	June 20	558053	6986194	1178	soil sample; 45cm depth, brown , B horizon
1202089	MG	June 20	558135	6985295	1146	soil sample, 25cm depth, B horizon, dk brown.
1202090	MG	June 20	558112	6985241	1143	soil sample; 25cm depth, lt brown, B horizon;
1202091	MG	June 20	558091	6985217	1142	soil sample, 40cm depth, grey brown, B,C horizon
1202193	SF	June 20	557897	6985291	1129	soil sample; 15-20cm, 8 deg slope, B horizon
1202194	SF	June 20	558519	6984802	1076	soil sample; rock in hole is more silicified, partially hornfelsed (?)
1203701	IY	June 21	557811	6981584	1449	soil sample; brown, 25cm depth; mostly silt, sand
1203706	IY	June 21	558202	6981755	1370	soil sample; brown, 20% organics, 14" depth, east side of slope.
RL003	RL	June 21				soil sample; in R Libke's notes ??
1202092	MG	June 21	557843	6981513	1450	Soil sample, 15-20cm depth, b horizon
1202217	FV	June 20				soil; need location
1202195	SF	June 23	553415	6977315	1127	soil sample; 40cm depth, brown soil, 15deg slope.
1202098	MG	June 23	553138	6977566	1194	soil sample, 25cm depth, brown , B horizon.
1203712	IY	June 23	553131	6977565	1196	soil sample; grey brown, 10 cm, flat SE exposure, silty clay with pebbles
1203720	IY	June 24	559230	6983156	1105	Soil sample brown, 25cm, B horizon

1202602	MG	June 24	559159	6983168	1111	Soil sample; 40cm, B horizon.
1202045	FV	June 23	553426	6977313	1127	soil sample;
1202607	MG	June 25	551867	6980610	1106	soil sample; 30cm, B horizon, grey clay; rock consisting of oxidized mica schist
1202609	MG	June 25	551746	6980820	1083	Soil sample, 40cm depth, B horizon.
1202611	MG	June 25	550591	6981285	898	Soil sample; 35cm depth, B horizon, green grey in color.
1203727	IY	June 25	551922	6980531	1109	Soil sample, 30cm depth, brown clay, with schist rck debris.
1203728	IY	June 25	551849	6980628	1106	Soil sample, 20cm depth, brown clay rich soil; B horizon.
1203729	IY	June 25	551722	6980860	1082	Soil sample; 30cm depth, brown clay, B horizon.
1203732	IY	June 25	550392	6981327	867	Soil sample, 35cm, greenish brown clay, B horizon
1202694	SF	June 26	557173	6983422	1394	soil sample, 25cm depth, brown soil, B, C horizon
1202695	SF	June 26	557180	6983535	1372	soil sample, 20cm depth, grey clay, includes qtz vein debris.
1202696	SF	June 26	557185	6983573	1368	Soil sample, 35-40cm depth, brown soil, B horizon
1202697	CM	June 26	557195	6983614	1367	Soil sample, 35cm depth, light brown, B horizon
1202258	SF/CM	June 26	555395	6983163	1268	Formerly labelled CM11; Soil sample, 15cm,light brown, frost boil
1202226	FV	June 25	557180	6979577	1332	soil
1202227	FV	June 25	557185	6979600	1334	soil
1202233	FV	June 26	559659	6978461	1358	soil
1202244	SF	June 29	558604	6980803	1396	soil sample
1202247	SF	June 29	558717	6980895	1369	soil sample
1202248	SF	June 29	558778	6980939	1350	soil sample; 30cm depth, brown , B horizon
1202249	SF	June 29	559266	6981225	1180	Soil sample; 15cm depth
1202261	SF	June 30	555326	6983130	1261	Soil sample, brown, B horizon, 25cm depth, mainly mafic schist
1202262	SF	June 30	555235	6983130	1249	soil sample; 25cm depth, brown soil, B Horizon, mainly chlorite schist.

1202263	SF	June 30	555148	6983116	1243	soil sample; 35cm, B horizon, has strongly silicified & chloritized schist with fn gr py.
1202264	SF	June 30	555129	6983128	1234	Soil sample; 40cm depth, grey clay, C horizon.
1202266	SF	June 30	555091	6983142	1233	Soil sample.
1202267	SF	June 30	555091	6983142	1252	Soil sample; 30cm, B horizon.
1202268	SF	June 30	555019	6983184	1229	Soil sample, 30cm, brown soil, B horizon.
1202271	SF	June 30	554960	6983224	1224	Soil sample ; 15cm brown soil, B horizon.
1202272	SF	June 30	554762	6983409	1230	Soil sample.
1202636	MG	July 2	563861	6982614	1111	Soil sample; 20cm depth, brown soil, B horizon
1202638	MG	July 2	563667	6982687	1071	Soil sample; 30cm depth, brown, granodiorite & chl musc schist rock debris
1202639	MG	July 2	563445	6982823	1021	Soil sample; brown soil, B horizon
1202642	MG	July 2	563305	6983275	940	Soil sample; 35cm depth. B horizon
1202279	SF	July 2	555336	6984805	1127	soil sample; 8-15cm depth, brown soil, much qtz feldspar biotite schist debris
1202281	SF	July 2	555259	6984825		Soil sample 10-15cm depth; poor soil development within mainly subcrop.
1202282	SF	July 2	555211	6984880	1131	Soil sample, brown soil, B horizon
1202283	SF	July 2	555216	6985212	1113	Soil sample, brown soil, B horizon
1202284	SF	July 2	555054	6985546	1073	Soil sample, brown soil, B horizon
1202285	SF	July 2	554965	6985688	1056	Soil sample, brown soil, B horizon
1202286	SF	July 2	554849	6985890		Soil sample; 30cm depth, brown soil, B horizon
1202647	MG	July 3	550934	6978319	1097	Soil sample; 30cm depth, grey tan colored, B Horizon

Appendix 2D: Soil sample locations

UTM NAD83 Zone 7

Sample ID	Type	Job#	Easting	Northing
1202301	Soil	WHI11000291	558938	6976128
1202302	Soil	WHI11000291	558897	6976107
1202303	Soil	WHI11000291	558860	6976084
1202304	Soil	WHI11000291	558815	6976061
1202305	Soil	WHI11000291	558762	6976038
1202306	Soil	WHI11000291	558716	6976017
1202307	Soil	WHI11000291	558674	6975993
1202308	Soil	WHI11000291	558624	6975970
1202309	Soil	WHI11000291	558580	6975961
1202310	Soil	WHI11000291	558533	6975938
1202311	Soil	WHI11000291	558489	6975914
1202313	Soil	WHI11000291	558402	6975881
1202317	Soil	WHI11000291	558258	6975819
1202318	Soil	WHI11000291	558206	6975804
1202319	Soil	WHI11000291	558165	6975769
1202320	Soil	WHI11000291	558128	6975758
1202321	Soil	WHI11000291	559825	6976772
1202322	Soil	WHI11000291	559872	6976797
1202323	Soil	WHI11000291	559923	6976834
1202324	Soil	WHI11000291	559965	6976842
1202325	Soil	WHI11000291	560006	6976857
1202326	Soil	WHI11000291	560055	6976880
1202327	Soil	WHI11000291	560104	6976896
1202328	Soil	WHI11000291	560155	6976920
1202329	Soil	WHI11000291	560193	6976931
1202331	Soil	WHI11000291	560240	6976950
1202332	Soil	WHI11000291	560286	6976973
1202333	Soil	WHI11000291	560333	6976996
1202334	Soil	WHI11000291	560377	6977009
1202335	Soil	WHI11000291	560431	6977037
1202336	Soil	WHI11000291	560471	6977049
1202337	Soil	WHI11000291	560521	6977070
1202338	Soil	WHI11000291	560566	6977080
1202339	Soil	WHI11000291	560615	6977095
1202340	Soil	WHI11000291	560663	6977105
1202341	Soil	WHI11000291	560713	6977117
1202342	Soil	WHI11000291	560759	6977132
1202343	Soil	WHI11000291	560803	6977151
1202344	Soil	WHI11000291	560856	6977162
1202345	Soil	WHI11000291	560908	6977176
1202346	Soil	WHI11000291	560952	6977178
1202347	Soil	WHI11000291	561002	6977199
1202401	Soil	WHI11000291	556804	6974852
1202402	Soil	WHI11000291	556840	6974891
1202404	Soil	WHI11000291	556903	6974986

Sample ID	Type	Job#	Easting	Northing
1202406	Soil	WHI11000291	556967	6975052
1202408	Soil	WHI11000291	557029	6975126
1202409	Soil	WHI11000291	557766	6975584
1202410	Soil	WHI11000291	557792	6975617
1202411	Soil	WHI11000291	557978	6975692
1202412	Soil	WHI11000291	558114	6975762
1202413	Soil	WHI11000291	561055	6977211
1202414	Soil	WHI11000291	558348	6975862
1202415	Soil	WHI11000291	558305	6975042
1202416	Soil	WHI11000291	558306	6975841
1202417	Soil	WHI11000291	561243	6977266
1202418	Soil	WHI11000291	561292	6977280
1202419	Soil	WHI11000291	561344	6977290
1202420	Soil	WHI11000291	561392	6977302
1202421	Soil	WHI11000291	561487	6977329
1202422	Soil	WHI11000291	561437	6977313
1202423	Soil	WHI11000291	561535	6977338
1202424	Soil	WHI11000291	561581	6977366
1202425	Soil	WHI11000291	561629	6977369
1202426	Soil	WHI11000291	561683	6977380
1202427	Soil	WHI11000291	561724	6977400
1202428	Soil	WHI11000291	561781	6977404
1202429	Soil	WHI11000291	561820	6977420
1202430	Soil	WHI11000291	561870	6977435
1202431	Soil	WHI11000291	561922	6977453
1202432	Soil	WHI11000291	561978	6977458
1202433	Soil	WHI11000291	562020	6977481
1202434	Soil	WHI11000291	562062	6977488
1202435	Soil	WHI11000291	562110	6977504
1202436	Soil	WHI11000291	562159	6977518
1202437	Soil	WHI11000291	562210	6977528
1202438	Soil	WHI11000291	562248	6977548
1202439	Soil	WHI11000291	562296	6977558
1202440	Soil	WHI11000291	562350	6977575
1202441	Soil	WHI11000291	562401	6977586
1202442	Soil	WHI11000291	562445	6977610
1202443	Soil	WHI11000291	562503	6977612
1202444	Soil	WHI11000291	562493	6977631
1202501	Soil	WHI11000291	556165	6976920
1202502	Soil	WHI11000291	557983	6980290
1202503	Soil	WHI11000291	557921	6980269
1202504	Soil	WHI11000291	557891	6980268
1202505	Soil	WHI11000291	557842	6980246
1202506	Soil	WHI11000291	557854	6980044
1202507	Soil	WHI11000291	557822	6980005
1202508	Soil	WHI11000291	557772	6979980
1202509	Soil	WHI11000291	557737	6979965
1202510	Soil	WHI11000291	557700	6979922
1202511	Soil	WHI11000291	557661	6979879

Sample ID	Type	Job#	Easting	Northing
1202512	Soil	WHI11000291	558086	6980240
1202513	Soil	WHI11000291	558047	6980213
1202514	Soil	WHI11000291	558000	6980175
1202515	Soil	WHI11000291	557968	6980148
1202516	Soil	WHI11000291	557934	6980118
1202517	Soil	WHI11000291	557893	6980079
1202518	Soil	WHI11000291	557628	6979865
1202519	Soil	WHI11000291	557578	6979826
1202520	Soil	WHI11000291	557543	6979802
1202521	Soil	WHI11000291	557503	6979770
1202522	Soil	WHI11000291	557455	6979740
1202523	Soil	WHI11000291	557420	6979715
1202524	Soil	WHI11000291	557379	6979690
1202525	Soil	WHI11000291	557334	6979654
1202526	Soil	WHI11000291	557297	6979630
1202527	Soil	WHI11000291	557242	6979580
1202528	Soil	WHI11000291	557198	6979557
1202529	Soil	WHI11000291	557174	6979541
1202530	Soil	WHI11000291	557132	6979510
1202531	Soil	WHI11000291	557095	6979486
1202532	Soil	WHI11000291	557053	6979456
1202533	Soil	WHI11000291	557017	6979421
1202534	Soil	WHI11000291	556972	6979392
1202551	Soil	WHI11000291	558205	6980246
1202552	Soil	WHI11000291	558303	6980260
1202553	Soil	WHI11000291	558347	6980273
1202554	Soil	WHI11000291	558396	6980281
1202555	Soil	WHI11000291	558445	6980292
1202556	Soil	WHI11000291	558496	6980303
1202557	Soil	WHI11000291	558548	6980312
1202558	Soil	WHI11000291	558593	6980322
1202559	Soil	WHI11000291	558647	6980337
1202560	Soil	WHI11000291	558689	6980344
1202561	Soil	WHI11000291	558743	6980352
1202562	Soil	WHI11000291	558813	6980332
1202563	Soil	WHI11000291	558850	6980350
1202564	Soil	WHI11000291	558892	6980407
1202586	Soil	WHI11000291	558251	6980249
1202587	Soil	WHI11000291	558923	6980432
1202588	Soil	WHI11000291	558973	6980452
1202589	Soil	WHI11000291	559009	6980498
1202590	Soil	WHI11000291	559060	6980496
1202591	Soil	WHI11000291	559105	6980525
1202592	Soil	WHI11000291	559147	6980541
1202593	Soil	WHI11000291	559188	6980564
1202594	Soil	WHI11000291	559237	6980591
1202595	Soil	WHI11000291	559280	6980611
1202596	Soil	WHI11000291	559326	6980636
1202597	Soil	WHI11000291	559373	6980661

Sample ID	Type	Job#	Easting	Northing
1202598	Soil	WHI11000291	559415	6980680
1202599	Soil	WHI11000291	559455	6980701
1202076	Soil	WHI11000342	557193	6984253
1202079	Soil	WHI11000342	557240	6983772
1202085	Soil	WHI11000342	558281	6986411
1202087	Soil	WHI11000342	558254	6986318
1202088	Soil	WHI11000342	558053	6986194
1202089	Soil	WHI11000342	558135	6985295
1202090	Soil	WHI11000342	558112	6985241
1202091	Soil	WHI11000342	558091	6985217
1202092	Soil	WHI11000342	557843	6981513
1202173	Soil	WHI11000342	557241	6983747
1202176	Soil	WHI11000342	557547	6983914
1202177	Soil	WHI11000342	557640	6983944
1202178	Soil	WHI11000342	557758	6984017
1202179	Soil	WHI11000342	557888	6983987
1202180	Soil	WHI11000342	557989	6983966
1202181	Soil	WHI11000342	558174	6984030
1202203	Soil	WHI11000342	557866	6982973
1202203	Soil	WHI11000342	557866	6982973
1202206	Soil	WHI11000342	561588	6980790
1202206	Soil	WHI11000342	561588	6980790
1202207	Soil	WHI11000342	561537	6980808
1202207	Soil	WHI11000342	561537	6980808
1202209	Soil	WHI11000342	561656	6980629
1202209	Soil	WHI11000342	561656	6980629
1202210	Soil	WHI11000342	561675	6980209
1202388	Soil	WHI11000342	564265	6980589
1202389	Soil	WHI11000342	564284	6980635
1202390	Soil	WHI11000342	564305	6980680
1202831	Soil	WHI11000342	562321	6982176
1202832	Soil	WHI11000342	562377	6982187
1202833	Soil	WHI11000342	562419	6982197
1202834	Soil	WHI11000342	562469	6982198
1202835	Soil	WHI11000342	562522	6982206
1202836	Soil	WHI11000342	562556	6982217
1202837	Soil	WHI11000342	563959	6983368
1202838	Soil	WHI11000342	563928	6983332
1202839	Soil	WHI11000342	563897	6983298
1202840	Soil	WHI11000342	563867	6983261
1202841	Soil	WHI11000342	563831	6983223
1202842	Soil	WHI11000342	563802	6983188
1202843	Soil	WHI11000342	563763	6983151
1202844	Soil	WHI11000342	563729	6983112
1202845	Soil	WHI11000342	563695	6983079
1202846	Soil	WHI11000342	563655	6983044
1202847	Soil	WHI11000342	563622	6983004
1202848	Soil	WHI11000342	563586	6982969
1202849	Soil	WHI11000342	563555	6982934

Sample ID	Type	Job#	Easting	Northing
1202850	Soil	WHI11000342	563514	6982900
1202851	Soil	WHI11000342	563486	6982862
1202852	Soil	WHI11000342	563448	6982821
1202853	Soil	WHI11000342	563417	6982790
1202854	Soil	WHI11000342	563382	6982749
1202855	Soil	WHI11000342	563350	6982714
1202856	Soil	WHI11000342	563316	6982674
1202857	Soil	WHI11000342	563282	6982645
1202858	Soil	WHI11000342	563250	6982608
1202859	Soil	WHI11000342	563213	6982568
1202860	Soil	WHI11000342	563171	6982550
1202861	Soil	WHI11000342	563125	6982524
1202862	Soil	WHI11000342	563081	6982503
1202863	Soil	WHI11000342	563037	6982480
1202864	Soil	WHI11000342	562994	6982453
1202865	Soil	WHI11000342	562950	6982429
1202866	Soil	WHI11000342	562905	6982395
1202867	Soil	WHI11000342	562869	6982367
1202868	Soil	WHI11000342	562827	6982335
1202869	Soil	WHI11000342	562784	6982309
1202870	Soil	WHI11000342	562744	6982271
1202871	Soil	WHI11000342	557772	6981792
1202872	Soil	WHI11000342	557788	6981838
1202873	Soil	WHI11000342	557805	6981885
1202874	Soil	WHI11000342	557826	6981930
1202875	Soil	WHI11000342	557839	6981981
1202876	Soil	WHI11000342	557861	6982021
1202877	Soil	WHI11000342	557882	6982069
1202878	Soil	WHI11000342	557899	6982118
1202879	Soil	WHI11000342	557917	6982163
1202880	Soil	WHI11000342	557934	6982209
1202881	Soil	WHI11000342	557952	6982252
1202882	Soil	WHI11000342	557978	6982299
1202883	Soil	WHI11000342	558001	6982344
1202884	Soil	WHI11000342	558028	6982377
1202885	Soil	WHI11000342	558054	6982423
1202886	Soil	WHI11000342	558081	6982465
1202887	Soil	WHI11000342	558116	6982510
1202888	Soil	WHI11000342	558139	6982555
1202889	Soil	WHI11000342	558163	6982599
1202890	Soil	WHI11000342	558191	6982641
1202891	Soil	WHI11000342	558211	6982679
1202892	Soil	WHI11000342	558243	6982720
1202893	Soil	WHI11000342	558278	6982755
1202894	Soil	WHI11000342	558315	6982791
1202895	Soil	WHI11000342	558356	6982824
1202896	Soil	WHI11000342	558389	6982860
1202897	Soil	WHI11000342	558426	6982897
1202898	Soil	WHI11000342	558459	6982931

Sample ID	Type	Job#	Easting	Northing
1202899	Soil	WHI11000342	558495	6982960
1202900	Soil	WHI11000342	558536	6982996
1202901	Soil	WHI11000342	558567	6983034
1202902	Soil	WHI11000342	558609	6983069
1202903	Soil	WHI11000342	558641	6983107
1202904	Soil	WHI11000342	558678	6983137
1202905	Soil	WHI11000342	558809	6983199
1202906	Soil	WHI11000342	558860	6983196
1202907	Soil	WHI11000342	558911	6983193
1202908	Soil	WHI11000342	558955	6983193
1202909	Soil	WHI11000342	559008	6983192
1202910	Soil	WHI11000342	558695	6983152
1202993	Soil	WHI11000342	551162	6977969
1202994	Soil	WHI11000342	551118	6977955
1203601	Soil	WHI11000342	563364	6979227
1203602	Soil	WHI11000342	563398	6979265
1203603	Soil	WHI11000342	563421	6979304
1203604	Soil	WHI11000342	563457	6979339
1203605	Soil	WHI11000342	563492	6979379
1203606	Soil	WHI11000342	563524	6979416
1203607	Soil	WHI11000342	563559	6979454
1203608	Soil	WHI11000342	563583	6979496
1203609	Soil	WHI11000342	563611	6979539
1203610	Soil	WHI11000342	563646	6979578
1203611	Soil	WHI11000342	563668	6979623
1203612	Soil	WHI11000342	563695	6979663
1203613	Soil	WHI11000342	563726	6979706
1203614	Soil	WHI11000342	563757	6979742
1203615	Soil	WHI11000342	563787	6979785
1203616	Soil	WHI11000342	563814	6979823
1203617	Soil	WHI11000342	563859	6979858
1203618	Soil	WHI11000342	563890	6979889
1203619	Soil	WHI11000342	563930	6979929
1203620	Soil	WHI11000342	563956	6979967
1203621	Soil	WHI11000342	563985	6980005
1203622	Soil	WHI11000342	564001	6980053
1203623	Soil	WHI11000342	564018	6980111
1203624	Soil	WHI11000342	564044	6980146
1203625	Soil	WHI11000342	564063	6980189
1203626	Soil	WHI11000342	564086	6980234
1203627	Soil	WHI11000342	564104	6980280
1203628	Soil	WHI11000342	564125	6980325
1203629	Soil	WHI11000342	564153	6980368
1203630	Soil	WHI11000342	564176	6980411
1203631	Soil	WHI11000342	564200	6980455
1203632	Soil	WHI11000342	564221	6980503
1203633	Soil	WHI11000342	564242	6980546
1203634	Soil	WHI11000342	556275	6980152
1203635	Soil	WHI11000342	556274	6980206

Sample ID	Type	Job#	Easting	Northing
1203636	Soil	WHI11000342	556292	6980250
1203637	Soil	WHI11000342	556308	6980299
1203638	Soil	WHI11000342	556316	6980345
1203639	Soil	WHI11000342	556329	6980395
1203640	Soil	WHI11000342	556343	6980444
1203641	Soil	WHI11000342	556355	6980495
1203642	Soil	WHI11000342	556368	6980543
1203643	Soil	WHI11000342	556376	6980589
1203644	Soil	WHI11000342	556391	6980636
1203644	Soil	WHI11000342	556391	6980636
1203645	Soil	WHI11000342	556400	6980684
1203645	Soil	WHI11000342	556400	6980684
1203646	Soil	WHI11000342	556431	6980730
1203646	Soil	WHI11000342	556448	6980782
1203647	Soil	WHI11000342	556448	6980782
1203647	Soil	WHI11000342	556448	6980782
1203648	Soil	WHI11000342	556467	6980821
1203648	Soil	WHI11000342	556467	6980821
1203649	Soil	WHI11000342	556482	6980870
1203649	Soil	WHI11000342	556482	6980870
1203650	Soil	WHI11000342	556504	6980915
1203650	Soil	WHI11000342	556504	6980915
1203701	Soil	WHI11000342	557811	6981584
1203706	Soil	WHI11000342	558202	6981755
1204001	Soil	WHI11000342	556519	6980963
1204001	Soil	WHI11000342	556519	6980963
1204002	Soil	WHI11000342	556540	6981004
1204002	Soil	WHI11000342	556540	6981004
1204003	Soil	WHI11000342	556559	6981058
1204003	Soil	WHI11000342	556559	6981058
1204004	Soil	WHI11000342	556575	6981102
1204005	Soil	WHI11000342	556592	6981148
1204006	Soil	WHI11000342	556609	6981200
1204007	Soil	WHI11000342	556626	6981243
1204008	Soil	WHI11000342	556643	6981289
1204009	Soil	WHI11000342	556662	6981341
1204010	Soil	WHI11000342	556691	6981408
1204010	Soil	WHI11000342	556696	6981423
1204011	Soil	WHI11000342	556696	6981423
1204011	Soil	WHI11000342	556696	6981423
1204012	Soil	WHI11000342	556717	6981468
1204012	Soil	WHI11000342	556717	6981468
1202161	Soil	WHI11000350	555502	6973101
1202162	Soil	WHI11000350	555618	6973130
1202163	Soil	WHI11000350	555714	6973152
1202164	Soil	WHI11000350	555910	6973179
1202165	Soil	WHI11000350	556786	6973305
1202167	Soil	WHI11000350	558834	6983180
1202168	Soil	WHI11000350	559023	6983186

Sample ID	Type	Job#	Easting	Northing
1202169	Soil	WHI11000350	559233	6983207
1202170	Soil	WHI11000350	559383	6983182
1202171	Soil	WHI11000350	559559	6983156
1202172	Soil	WHI11000350	559281	6982588
1202348	Soil	WHI11000350	559689	6978259
1202349	Soil	WHI11000350	559725	6978283
1202350	Soil	WHI11000350	559769	6978309
1202351	Soil	WHI11000350	559815	6978328
1202352	Soil	WHI11000350	559858	6978348
1202353	Soil	WHI11000350	559898	6978375
1202354	Soil	WHI11000350	559939	6978406
1202355	Soil	WHI11000350	559986	6978433
1202356	Soil	WHI11000350	560026	6978457
1202357	Soil	WHI11000350	560066	6978484
1202358	Soil	WHI11000350	560109	6978514
1202359	Soil	WHI11000350	560153	6978541
1202360	Soil	WHI11000350	560194	6978570
1202361	Soil	WHI11000350	560236	6978597
1202362	Soil	WHI11000350	560282	6978624
1202363	Soil	WHI11000350	560320	6978647
1202364	Soil	WHI11000350	560364	6978677
1202365	Soil	WHI11000350	560402	6978703
1202366	Soil	WHI11000350	560452	6978732
1202367	Soil	WHI11000350	560488	6978755
1202368	Soil	WHI11000350	560534	6978771
1202369	Soil	WHI11000350	560585	6978785
1202370	Soil	WHI11000350	560630	6978811
1202371	Soil	WHI11000350	560677	6978818
1202372	Soil	WHI11000350	560729	6978832
1202373	Soil	WHI11000350	560769	6978847
1202374	Soil	WHI11000350	560821	6978863
1202375	Soil	WHI11000350	560867	6978876
1202376	Soil	WHI11000350	560914	6978893
1202377	Soil	WHI11000350	560964	6978911
1202378	Soil	WHI11000350	561011	6978927
1202379	Soil	WHI11000350	561060	6978938
1202380	Soil	WHI11000350	561106	6978959
1202381	Soil	WHI11000350	561153	6978976
1202382	Soil	WHI11000350	561200	6978990
1202383	Soil	WHI11000350	561248	6979004
1202384	Soil	WHI11000350	561297	6979019
1202385	Soil	WHI11000350	561343	6979035
1202386	Soil	WHI11000350	561390	6979055
1202387	Soil	WHI11000350	561431	6979066
1202445	Soil	WHI11000350	561588	6979109
1202446	Soil	WHI11000350	561629	6979127
1202447	Soil	WHI11000350	561674	6979152
1202448	Soil	WHI11000350	561718	6979174
1202449	Soil	WHI11000350	561764	6979193

Sample ID	Type	Job#	Easting	Northing
1202450	Soil	WHI11000350	561807	6979219
1202451	Soil	WHI11000350	561853	6979243
1202452	Soil	WHI11000350	561904	6979260
1202453	Soil	WHI11000350	561945	6979275
1202454	Soil	WHI11000350	561986	6979308
1202455	Soil	WHI11000350	562039	6979325
1202456	Soil	WHI11000350	562075	6979351
1202457	Soil	WHI11000350	562126	6979366
1202458	Soil	WHI11000350	562166	6979387
1202459	Soil	WHI11000350	562218	6979415
1202460	Soil	WHI11000350	562257	6979438
1202461	Soil	WHI11000350	562285	6979446
1202462	Soil	WHI11000350	563089	6976503
1202463	Soil	WHI11000350	563116	6976532
1202464	Soil	WHI11000350	563171	6976565
1202465	Soil	WHI11000350	563209	6976596
1202466	Soil	WHI11000350	563257	6976618
1202467	Soil	WHI11000350	563291	6976653
1202468	Soil	WHI11000350	563327	6976683
1202469	Soil	WHI11000350	563367	6976714
1202470	Soil	WHI11000350	563410	6976741
1202471	Soil	WHI11000350	563449	6976773
1202472	Soil	WHI11000350	563488	6976800
1202473	Soil	WHI11000350	563517	6976844
1202474	Soil	WHI11000350	563535	6976889
1202475	Soil	WHI11000350	563552	6976934
1202476	Soil	WHI11000350	563570	6976981
1202477	Soil	WHI11000350	563590	6977028
1202478	Soil	WHI11000350	563608	6977073
1202479	Soil	WHI11000350	563627	6977118
1202480	Soil	WHI11000350	563650	6977155
1202481	Soil	WHI11000350	563659	6977216
1202482	Soil	WHI11000350	563677	6977264
1202483	Soil	WHI11000350	563702	6977313
1202484	Soil	WHI11000350	563712	6977355
1202485	Soil	WHI11000350	563729	6977400
1202486	Soil	WHI11000350	563734	6977448
1202487	Soil	WHI11000350	563729	6977501
1202488	Soil	WHI11000350	563732	6977549
1202489	Soil	WHI11000350	563732	6977600
1202490	Soil	WHI11000350	563737	6977650
1202491	Soil	WHI11000350	563739	6977701
1202492	Soil	WHI11000350	563742	6977750
1202493	Soil	WHI11000350	563735	6977801
1202494	Soil	WHI11000350	563731	6977848
1202495	Soil	WHI11000350	563726	6977901
1202496	Soil	WHI11000350	563725	6977950
1202497	Soil	WHI11000350	563724	6977996
1202498	Soil	WHI11000350	563717	6978049

Sample ID	Type	Job#	Easting	Northing
1202499	Soil	WHI11000350	563711	6978106
1202500	Soil	WHI11000350	563711	6978143
1202535	Soil	WHI11000350	560440	6981305
1202536	Soil	WHI11000350	560464	6981327
1202537	Soil	WHI11000350	560494	6981178
1202538	Soil	WHI11000350	560529	6981148
1202539	Soil	WHI11000350	560562	6981107
1202540	Soil	WHI11000350	560606	6981069
1202541	Soil	WHI11000350	560636	6981045
1202542	Soil	WHI11000350	560676	6981007
1202543	Soil	WHI11000350	560715	6980975
1202544	Soil	WHI11000350	560743	6980939
1202545	Soil	WHI11000350	560784	6980901
1202546	Soil	WHI11000350	560815	6980869
1202547	Soil	WHI11000350	560861	6980840
1202548	Soil	WHI11000350	560899	6980817
1202549	Soil	WHI11000350	560940	6980804
1202550	Soil	WHI11000350	560990	6980768
1202565	Soil	WHI11000350	559573	6980765
1202566	Soil	WHI11000350	559600	6980772
1202567	Soil	WHI11000350	559691	6980812
1202568	Soil	WHI11000350	559635	6980791
1202569	Soil	WHI11000350	559719	6980844
1202570	Soil	WHI11000350	559761	6980867
1202571	Soil	WHI11000350	559806	6980897
1202572	Soil	WHI11000350	559845	6980924
1202573	Soil	WHI11000350	559892	6980954
1202574	Soil	WHI11000350	559938	6980986
1202575	Soil	WHI11000350	559969	6981007
1202576	Soil	WHI11000350	560022	6981037
1202577	Soil	WHI11000350	560056	6981064
1202578	Soil	WHI11000350	560101	6981091
1202579	Soil	WHI11000350	560146	6981123
1202580	Soil	WHI11000350	560185	6981145
1202581	Soil	WHI11000350	560228	6981171
1202582	Soil	WHI11000350	560271	6981199
1202583	Soil	WHI11000350	560314	6981224
1202584	Soil	WHI11000350	560353	6981255
1202585	Soil	WHI11000350	560396	6981277
1202600	Soil	WHI11000350	559501	6980725
1202701	Soil	WHI11000350	561030	6980732
1202702	Soil	WHI11000350	561068	6980704
1202703	Soil	WHI11000350	561119	6980678
1202704	Soil	WHI11000350	561156	6980667
1202705	Soil	WHI11000350	561210	6980654
1202706	Soil	WHI11000350	561253	6980625
1202707	Soil	WHI11000350	561306	6980615
1202708	Soil	WHI11000350	561348	6980598
1202709	Soil	WHI11000350	561394	6980577

Sample ID	Type	Job#	Easting	Northing
1202710	Soil	WHI11000350	561441	6980589
1202711	Soil	WHI11000350	561491	6980596
1202712	Soil	WHI11000350	561539	6980609
1202713	Soil	WHI11000350	561592	6980620
1202714	Soil	WHI11000350	561640	6980633
1202715	Soil	WHI11000350	561694	6980640
1202716	Soil	WHI11000350	561738	6980650
1202717	Soil	WHI11000350	561786	6980656
1202718	Soil	WHI11000350	561838	6980670
1202719	Soil	WHI11000350	561886	6980679
1202720	Soil	WHI11000350	561939	6980692
1202721	Soil	WHI11000350	561985	6980699
1202722	Soil	WHI11000350	562006	6980704
1202723	Soil	WHI11000350	562106	6980697
1202724	Soil	WHI11000350	562126	6980710
1202725	Soil	WHI11000350	562168	6980730
1202726	Soil	WHI11000350	562216	6980748
1202727	Soil	WHI11000350	562262	6980768
1202728	Soil	WHI11000350	562311	6980785
1202729	Soil	WHI11000350	562348	6980809
1202730	Soil	WHI11000350	562406	6980825
1202731	Soil	WHI11000350	562441	6980844
1202732	Soil	WHI11000350	562492	6980865
1202733	Soil	WHI11000350	562541	6980886
1202734	Soil	WHI11000350	562576	6980912
1202735	Soil	WHI11000350	562615	6980945
1202736	Soil	WHI11000350	562652	6980977
1202737	Soil	WHI11000350	562689	6981011
1202738	Soil	WHI11000350	562732	6981047
1202739	Soil	WHI11000350	562770	6981077
1202740	Soil	WHI11000350	562807	6981110
1202741	Soil	WHI11000350	562843	6981140
1202742	Soil	WHI11000350	562882	6981181
1202743	Soil	WHI11000350	562914	6981212
1202744	Soil	WHI11000350	562952	6981246
1202745	Soil	WHI11000350	562990	6981275
1202746	Soil	WHI11000350	563032	6981312
1202748	Soil	WHI11000350	560739	6981799
1202749	Soil	WHI11000350	560783	6981828
1202750	Soil	WHI11000350	560830	6981845
1202801	Soil	WHI11000350	560875	6981870
1202802	Soil	WHI11000350	560923	6981892
1202803	Soil	WHI11000350	560965	6981917
1202804	Soil	WHI11000350	561008	6981933
1202805	Soil	WHI11000350	561053	6981961
1202806	Soil	WHI11000350	561090	6981988
1202807	Soil	WHI11000350	561141	6981995
1202808	Soil	WHI11000350	561193	6981999
1202809	Soil	WHI11000350	561243	6982007

Sample ID	Type	Job#	Easting	Northing
1202810	Soil	WHI11000350	561290	6982009
1202811	Soil	WHI11000350	561340	6982010
1202812	Soil	WHI11000350	561391	6982017
1202813	Soil	WHI11000350	561439	6982022
1202814	Soil	WHI11000350	561491	6982026
1202815	Soil	WHI11000350	561539	6982025
1202816	Soil	WHI11000350	561588	6982028
1202817	Soil	WHI11000350	561639	6982033
1202818	Soil	WHI11000350	561691	6982034
1202819	Soil	WHI11000350	561742	6982038
1202820	Soil	WHI11000350	561792	6982049
1202821	Soil	WHI11000350	561836	6982066
1202822	Soil	WHI11000350	561887	6982076
1202823	Soil	WHI11000350	561935	6982091
1202824	Soil	WHI11000350	561981	6982100
1202825	Soil	WHI11000350	562035	6982113
1202826	Soil	WHI11000350	562075	6982124
1202827	Soil	WHI11000350	562130	6982135
1202828	Soil	WHI11000350	562179	6982152
1202829	Soil	WHI11000350	562227	6982159
1202830	Soil	WHI11000350	562276	6982168
1203111	Soil	WHI11000490	551141	6979741
1203112	Soil	WHI11000490	551092	6979728
1203113	Soil	WHI11000490	551046	6979709
1203114	Soil	WHI11000490	550997	6979697
1203115	Soil	WHI11000490	550953	6979678
1203116	Soil	WHI11000490	550904	6979664
1203117	Soil	WHI11000490	550851	6979643
1203118	Soil	WHI11000490	550804	6979626
1203119	Soil	WHI11000490	550758	6979614
1203120	Soil	WHI11000490	550708	6979591
1203121	Soil	WHI11000490	552171	6980112
1203122	Soil	WHI11000490	552203	6980147
1203123	Soil	WHI11000490	552241	6980177
1203124	Soil	WHI11000490	552279	6980205
1203125	Soil	WHI11000490	552315	6980237
1203126	Soil	WHI11000490	552354	6980269
1203127	Soil	WHI11000490	552396	6980297
1203128	Soil	WHI11000490	552429	6980332
1203129	Soil	WHI11000490	552466	6980361
1203130	Soil	WHI11000490	552509	6980389
1203131	Soil	WHI11000490	552546	6980424
1203132	Soil	WHI11000490	552584	6980458
1203133	Soil	WHI11000490	552626	6980480
1203134	Soil	WHI11000490	552663	6980517
1203135	Soil	WHI11000490	552697	6980549
1203136	Soil	WHI11000490	552738	6980587
1203137	Soil	WHI11000490	552776	6980618
1203138	Soil	WHI11000490	552753	6980686

Sample ID	Type	Job#	Easting	Northing
1203139	Soil	WHI11000490	552777	6980731
1203140	Soil	WHI11000490	552801	6980777
1203141	Soil	WHI11000490	552823	6980821
1203142	Soil	WHI11000490	552854	6980875
1203143	Soil	WHI11000490	552869	6980914
1203144	Soil	WHI11000490	552896	6980956
1203145	Soil	WHI11000490	552920	6980989
1203146	Soil	WHI11000490	552951	6981045
1203147	Soil	WHI11000490	552961	6981087
1203148	Soil	WHI11000490	552983	6981133
1203149	Soil	WHI11000490	553006	6981179
1203150	Soil	WHI11000490	553027	6981221
1202045	Soil	WHI11000493	553426	6977313
1202098	Soil	WHI11000493	553138	6977566
1202226	Soil	WHI11000493	557180	6979577
1202227	Soil	WHI11000493	557185	6979600
1202258	Soil	WHI11000493	555395	6983163
1202602	Soil	WHI11000493	559159	6983168
1202607	Soil	WHI11000493	551867	6980610
1202609	Soil	WHI11000493	551746	6980820
1202611	Soil	WHI11000493	550591	6981285
1202694	Soil	WHI11000493	557173	6983422
1202695	Soil	WHI11000493	557180	6983535
1202696	Soil	WHI11000493	557185	6983573
1202697	Soil	WHI11000493	557195	6983614
1202911	Soil	WHI11000493	559059	6983194
1202912	Soil	WHI11000493	559108	6983186
1202913	Soil	WHI11000493	559162	6983185
1202914	Soil	WHI11000493	559208	6983184
1202915	Soil	WHI11000493	559257	6983180
1202916	Soil	WHI11000493	559310	6983175
1202917	Soil	WHI11000493	559358	6983175
1202918	Soil	WHI11000493	559406	6983176
1202919	Soil	WHI11000493	559461	6983174
1202920	Soil	WHI11000493	559510	6983173
1202921	Soil	WHI11000493	559559	6983177
1202922	Soil	WHI11000493	559609	6983179
1202923	Soil	WHI11000493	559655	6983190
1202924	Soil	WHI11000493	559707	6983192
1202925	Soil	WHI11000493	559759	6983198
1202926	Soil	WHI11000493	559809	6983203
1202927	Soil	WHI11000493	559851	6983208
1202928	Soil	WHI11000493	559904	6983209
1202929	Soil	WHI11000493	559956	6983215
1202930	Soil	WHI11000493	560006	6983222
1202931	Soil	WHI11000493	560060	6983230
1202932	Soil	WHI11000493	560104	6983233
1202933	Soil	WHI11000493	560155	6983238
1202934	Soil	WHI11000493	560202	6983251

Sample ID	Type	Job#	Easting	Northing
1202935	Soil	WHI11000493	560255	6983263
1202936	Soil	WHI11000493	560300	6983276
1202937	Soil	WHI11000493	560348	6983284
1202938	Soil	WHI11000493	560397	6983300
1202939	Soil	WHI11000493	560445	6983312
1202940	Soil	WHI11000493	560492	6983328
1202941	Soil	WHI11000493	560539	6983345
1202942	Soil	WHI11000493	560590	6983360
1202943	Soil	WHI11000493	560633	6983367
1202944	Soil	WHI11000493	560686	6983373
1202945	Soil	WHI11000493	560738	6983383
1202946	Soil	WHI11000493	560784	6983391
1202947	Soil	WHI11000493	560832	6983398
1202948	Soil	WHI11000493	560882	6983406
1202949	Soil	WHI11000493	560933	6983412
1202950	Soil	WHI11000493	560983	6983417
1202951	Soil	WHI11000493	561032	6983416
1202952	Soil	WHI11000493	561087	6983430
1202953	Soil	WHI11000493	561134	6983441
1202954	Soil	WHI11000493	561180	6983453
1202955	Soil	WHI11000493	561229	6983464
1202956	Soil	WHI11000493	561279	6983474
1202957	Soil	WHI11000493	552741	6978732
1202958	Soil	WHI11000493	552711	6978702
1202959	Soil	WHI11000493	552670	6978671
1202960	Soil	WHI11000493	552631	6978639
1202961	Soil	WHI11000493	552597	6978608
1202962	Soil	WHI11000493	552559	6978577
1202963	Soil	WHI11000493	552515	6978544
1202964	Soil	WHI11000493	552475	6978512
1202965	Soil	WHI11000493	552437	6978477
1202966	Soil	WHI11000493	552403	6978446
1202967	Soil	WHI11000493	552364	6978412
1202968	Soil	WHI11000493	552323	6978378
1202969	Soil	WHI11000493	552285	6978348
1202970	Soil	WHI11000493	552247	6978319
1202971	Soil	WHI11000493	552201	6978299
1202972	Soil	WHI11000493	552152	6978281
1202973	Soil	WHI11000493	552104	6978263
1202974	Soil	WHI11000493	552061	6978243
1202975	Soil	WHI11000493	552018	6978216
1202976	Soil	WHI11000493	551970	6978197
1202977	Soil	WHI11000493	551927	6978178
1202978	Soil	WHI11000493	551882	6978157
1202979	Soil	WHI11000493	551837	6978133
1202980	Soil	WHI11000493	551787	6978116
1202981	Soil	WHI11000493	551745	6978092
1202982	Soil	WHI11000493	551699	6978075
1202983	Soil	WHI11000493	551654	6978059

Sample ID	Type	Job#	Easting	Northing
1202984	Soil	WHI11000493	551604	6978042
1202985	Soil	WHI11000493	551557	6978031
1202986	Soil	WHI11000493	551508	6978033
1202987	Soil	WHI11000493	551451	6978024
1202988	Soil	WHI11000493	551408	6978022
1202989	Soil	WHI11000493	551359	6978017
1202990	Soil	WHI11000493	551309	6978013
1202991	Soil	WHI11000493	551251	6978001
1202992	Soil	WHI11000493	551206	6977988
1202993	Soil	WHI11000493	551162	6977969
1202994	Soil	WHI11000493	551118	6977955
1202995	Soil	WHI11000493	551069	6977936
1202996	Soil	WHI11000493	551027	6977922
1202997	Soil	WHI11000493	550973	6977909
1202998	Soil	WHI11000493	550941	6977896
1202999	Soil	WHI11000493	552924	6978207
1203000	Soil	WHI11000493	552914	6978161
1203001	Soil	WHI11000493	552905	6978112
1203002	Soil	WHI11000493	552897	6978061
1203003	Soil	WHI11000493	552887	6978010
1203004	Soil	WHI11000493	552876	6977963
1203005	Soil	WHI11000493	552870	6977915
1203006	Soil	WHI11000493	552860	6977862
1203007	Soil	WHI11000493	552858	6977814
1203008	Soil	WHI11000493	552839	6977765
1203009	Soil	WHI11000493	552824	6977712
1203010	Soil	WHI11000493	552815	6977669
1203011	Soil	WHI11000493	552804	6977619
1203012	Soil	WHI11000493	552793	6977573
1203013	Soil	WHI11000493	552776	6977521
1203014	Soil	WHI11000493	552768	6977475
1203015	Soil	WHI11000493	552755	6977426
1203016	Soil	WHI11000493	552744	6977378
1203017	Soil	WHI11000493	552732	6977324
1203018	Soil	WHI11000493	552724	6977281
1203019	Soil	WHI11000493	552694	6977236
1203020	Soil	WHI11000493	552675	6977196
1203021	Soil	WHI11000493	552647	6977144
1203022	Soil	WHI11000493	552619	6977109
1203023	Soil	WHI11000493	552597	6977065
1203024	Soil	WHI11000493	552571	6977025
1203025	Soil	WHI11000493	552544	6976974
1203026	Soil	WHI11000493	552518	6976941
1203027	Soil	WHI11000493	552493	6976895
1203028	Soil	WHI11000493	552463	6976848
1203029	Soil	WHI11000493	552439	6976804
1203030	Soil	WHI11000493	552416	6976761
1203031	Soil	WHI11000493	552393	6976721
1203032	Soil	WHI11000493	552338	6976639

Sample ID	Type	Job#	Easting	Northing
1203033	Soil	WHI11000493	552364	6976679
1203034	Soil	WHI11000493	552296	6976604
1203035	Soil	WHI11000493	552264	6976571
1203036	Soil	WHI11000493	552225	6976539
1203037	Soil	WHI11000493	552180	6976510
1203038	Soil	WHI11000493	552140	6976481
1203039	Soil	WHI11000493	552133	6976473
1203637	Soil	WHI11000493	556308	6980299
1203712	Soil	WHI11000493	553131	6977565
1203720	Soil	WHI11000493	559230	6983156
1203727	Soil	WHI11000493	551922	6980531
1203728	Soil	WHI11000493	551849	6980628
1203729	Soil	WHI11000493	551722	6980860
1203732	Soil	WHI11000493	550392	6981327
1203732	Soil	WHI11000493	550392	6981327
1204013	Soil	WHI11000493	557046	6982951
1204014	Soil	WHI11000493	557052	6983001
1204015	Soil	WHI11000493	557046	6983053
1204016	Soil	WHI11000493	557058	6983106
1204017	Soil	WHI11000493	557055	6983152
1204018	Soil	WHI11000493	557060	6983199
1204019	Soil	WHI11000493	557059	6983251
1204020	Soil	WHI11000493	557053	6983301
1204021	Soil	WHI11000493	557059	6983350
1204022	Soil	WHI11000493	557058	6983398
1204023	Soil	WHI11000493	557060	6983448
1204024	Soil	WHI11000493	557065	6983502
1204025	Soil	WHI11000493	557064	6983550
1204026	Soil	WHI11000493	557065	6983602
1204027	Soil	WHI11000493	557070	6983653
1204028	Soil	WHI11000493	557070	6983702
1204029	Soil	WHI11000493	557068	6983748
1204030	Soil	WHI11000493	557070	6983799
1204031	Soil	WHI11000493	557069	6983853
1204032	Soil	WHI11000493	557071	6983901
1204033	Soil	WHI11000493	557080	6983955
1204034	Soil	WHI11000493	557081	6984001
1204035	Soil	WHI11000493	557095	6984048
1204036	Soil	WHI11000493	557102	6984096
1204037	Soil	WHI11000493	557109	6984152
1204038	Soil	WHI11000493	557116	6984198
1204039	Soil	WHI11000493	557122	6984247
1204040	Soil	WHI11000493	557136	6984302
1204041	Soil	WHI11000493	557139	6984347
1204042	Soil	WHI11000493	557155	6984391
1204043	Soil	WHI11000493	557184	6984431
1204044	Soil	WHI11000493	557223	6984467
1204045	Soil	WHI11000493	557252	6984500
1204046	Soil	WHI11000493	557292	6984543

Sample ID	Type	Job#	Easting	Northing
1204047	Soil	WHI11000493	557326	6984575
1204048	Soil	WHI11000493	557355	6984612
1204049	Soil	WHI11000493	557390	6984652
1204050	Soil	WHI11000493	557431	6984677
1204051	Soil	WHI11000493	557045	6982905
1204052	Soil	WHI11000493	557051	6982853
1204053	Soil	WHI11000493	557047	6982836
1204054	Soil	WHI11000493	557046	6982763
1204055	Soil	WHI11000493	557046	6982712
1204056	Soil	WHI11000493	557043	6982666
1204057	Soil	WHI11000493	557033	6982617
1204058	Soil	WHI11000493	557029	6982564
1204059	Soil	WHI11000493	557023	6982514
1204060	Soil	WHI11000493	557021	6982465
1204061	Soil	WHI11000493	557016	6982414
1204062	Soil	WHI11000493	557012	6982367
1204063	Soil	WHI11000493	557011	6982317
1204064	Soil	WHI11000493	557001	6982269
1204065	Soil	WHI11000493	556995	6982215
1204066	Soil	WHI11000493	556995	6982168
1204067	Soil	WHI11000493	556972	6982119
1204068	Soil	WHI11000493	556958	6982075
1204069	Soil	WHI11000493	556950	6982027
1204070	Soil	WHI11000493	556929	6981980
1204071	Soil	WHI11000493	556913	6981930
1204072	Soil	WHI11000493	556894	6981882
1204073	Soil	WHI11000493	556877	6981838
1204074	Soil	WHI11000493	556864	6981789
1204075	Soil	WHI11000493	556849	6981736
1204076	Soil	WHI11000493	556829	6981695
1204077	Soil	WHI11000493	556808	6981650
1204078	Soil	WHI11000493	556790	6981605
1204079	Soil	WHI11000493	556770	6981560
1202195	Soil	WHI11000495	553415	6977315
1202244	Soil	WHI11000495	558604	6980803
1202247	Soil	WHI11000495	558717	6980895
1202248	Soil	WHI11000495	558778	6980939
1202249	Soil	WHI11000495	559266	6981225
1202261	Soil	WHI11000495	555326	6983130
1202262	Soil	WHI11000495	555235	6983130
1202263	Soil	WHI11000495	555148	6983116
1202264	Soil	WHI11000495	555129	6983128
1202266	Soil	WHI11000495	555091	6983142
1202267	Soil	WHI11000495	555091	6983142
1202268	Soil	WHI11000495	555019	6983184
1202271	Soil	WHI11000495	554960	6983224
1203040	Soil	WHI11000495	556645	6974829
1203041	Soil	WHI11000495	556556	6974889
1203042	Soil	WHI11000495	556482	6974937

Sample ID	Type	Job#	Easting	Northing
1203043	Soil	WHI11000495	556392	6974992
1203044	Soil	WHI11000495	556304	6975018
1203045	Soil	WHI11000495	556203	6975051
1203046	Soil	WHI11000495	556106	6975091
1203047	Soil	WHI11000495	556017	6975111
1203048	Soil	WHI11000495	555920	6975141
1203049	Soil	WHI11000495	555823	6975163
1203050	Soil	WHI11000495	555725	6975192
1203051	Soil	WHI11000495	555627	6975218
1203052	Soil	WHI11000495	555528	6975229
1203053	Soil	WHI11000495	555432	6975239
1203054	Soil	WHI11000495	555331	6975249
1203055	Soil	WHI11000495	555228	6975258
1203056	Soil	WHI11000495	555132	6975270
1203057	Soil	WHI11000495	555030	6975280
1203058	Soil	WHI11000495	554932	6975298
1203059	Soil	WHI11000495	554834	6975320
1203060	Soil	WHI11000495	554735	6975333
1203061	Soil	WHI11000495	554640	6975349
1203062	Soil	WHI11000495	554544	6975372
1203063	Soil	WHI11000495	554443	6975388
1203064	Soil	WHI11000495	554354	6975438
1203065	Soil	WHI11000495	554267	6975482
1203066	Soil	WHI11000495	554181	6975538
1203067	Soil	WHI11000495	554100	6975001
1203068	Soil	WHI11000495	554032	6975670
1203069	Soil	WHI11000495	553970	6975741
1203070	Soil	WHI11000495	553930	6975775
1203071	Soil	WHI11000495	549906	6979015
1203072	Soil	WHI11000495	549946	6979052
1203073	Soil	WHI11000495	549979	6979088
1203074	Soil	WHI11000495	550006	6979126
1203075	Soil	WHI11000495	550032	6979162
1203076	Soil	WHI11000495	550075	6979193
1203077	Soil	WHI11000495	550120	6979235
1203078	Soil	WHI11000495	550157	6979251
1203079	Soil	WHI11000495	550196	6979281
1203080	Soil	WHI11000495	550234	6979305
1203081	Soil	WHI11000495	550278	6979339
1203082	Soil	WHI11000495	550315	6979371
1203083	Soil	WHI11000495	550361	6979396
1203084	Soil	WHI11000495	550408	6979418
1203085	Soil	WHI11000495	550442	6979449
1203086	Soil	WHI11000495	550488	6979475
1203087	Soil	WHI11000495	550530	6979500
1203088	Soil	WHI11000495	550570	6979526
1203089	Soil	WHI11000495	550619	6979553
1203090	Soil	WHI11000495	550662	6979578
1203091	Soil	WHI11000495	552105	6980073

Sample ID	Type	Job#	Easting	Northing
1203092	Soil	WHI11000495	552058	6980053
1203093	Soil	WHI11000495	552012	6980033
1203094	Soil	WHI11000495	551966	6980015
1203095	Soil	WHI11000495	551916	6980002
1203096	Soil	WHI11000495	551871	6979986
1203097	Soil	WHI11000495	551822	6979973
1203098	Soil	WHI11000495	551775	6979953
1203099	Soil	WHI11000495	551727	6979939
1203100	Soil	WHI11000495	551677	6979922
1203101	Soil	WHI11000495	551626	6979906
1203102	Soil	WHI11000495	551577	6979887
1203103	Soil	WHI11000495	551530	6979871
1203104	Soil	WHI11000495	551479	6979848
1203105	Soil	WHI11000495	551428	6979834
1203106	Soil	WHI11000495	551383	6979817
1203107	Soil	WHI11000495	551335	6979805
1203108	Soil	WHI11000495	551288	6979786
1203109	Soil	WHI11000495	551240	6979773
1203110	Soil	WHI11000495	551189	6979755
1204080	Soil	WHI11000495	551531	6984219
1204081	Soil	WHI11000495	551483	6984209
1204082	Soil	WHI11000495	551429	6984206
1204083	Soil	WHI11000495	551376	6984201
1204084	Soil	WHI11000495	551331	6984197
1204085	Soil	WHI11000495	551281	6984192
1204086	Soil	WHI11000495	551234	6984192
1204087	Soil	WHI11000495	551180	6984184
1204088	Soil	WHI11000495	551136	6984185
1204089	Soil	WHI11000495	551083	6984177
1204090	Soil	WHI11000495	551028	6984177
1204091	Soil	WHI11000495	550978	6984169
1204092	Soil	WHI11000495	550935	6984164
1204093	Soil	WHI11000495	550882	6984161
1204094	Soil	WHI11000495	550834	6984150
1204095	Soil	WHI11000495	550786	6984141
1204096	Soil	WHI11000495	550737	6984128
1204097	Soil	WHI11000495	550689	6984113
1204098	Soil	WHI11000495	550641	6984101
1204099	Soil	WHI11000495	550589	6984095
1204100	Soil	WHI11000495	550545	6984080
1204101	Soil	WHI11000495	550499	6984069
1204102	Soil	WHI11000495	550445	6984054
1204103	Soil	WHI11000495	550397	6984040
1204104	Soil	WHI11000495	550344	6984031
1204105	Soil	WHI11000495	550301	6984026
1204106	Soil	WHI11000495	550254	6984010
1204107	Soil	WHI11000495	550204	6983997
1204108	Soil	WHI11000495	550156	6983982
1204109	Soil	WHI11000495	550108	6983974

Sample ID	Type	Job#	Easting	Northing
1204110	Soil	WHI11000495	550059	6983959
1204111	Soil	WHI11000495	550017	6983932
1204112	Soil	WHI11000495	549972	6983912
1204113	Soil	WHI11000495	549928	6983884
1204114	Soil	WHI11000495	549884	6983860
1204115	Soil	WHI11000495	549837	6983843
1204116	Soil	WHI11000495	549791	6983824
1204117	Soil	WHI11000495	549749	6983797
1204118	Soil	WHI11000495	549703	6983774
1204119	Soil	WHI11000495	549658	6983753
1204120	Soil	WHI11000495	549614	6983730
1204121	Soil	WHI11000495	549567	6983712
1204122	Soil	WHI11000495	549525	6983691
1204123	Soil	WHI11000495	549479	6983668
1204124	Soil	WHI11000495	549434	6983643
1204125	Soil	WHI11000495	549393	6983616
1204126	Soil	WHI11000495	549347	6983604
1204127	Soil	WHI11000495	549300	6983573
1204128	Soil	WHI11000495	549259	6983545
1204129	Soil	WHI11000495	549221	6983511
1204130	Soil	WHI11000495	549179	6983488
1204131	Soil	WHI11000495	549135	6983467
1204132	Soil	WHI11000495	549094	6983432
1204133	Soil	WHI11000495	549050	6983400
1204134	Soil	WHI11000495	549011	6983372
1204135	Soil	WHI11000495	548971	6983343
1204136	Soil	WHI11000495	548931	6983321
1204137	Soil	WHI11000495	548889	6983287
1204138	Soil	WHI11000495	548847	6983267
1204139	Soil	WHI11000495	548805	6983236
1204140	Soil	WHI11000495	548767	6983205
1204141	Soil	WHI11000495	548749	6983202
1202233	Soil	WHI11000681	559659	6978461
1202272	Soil	WHI11000681	554762	6983409
1202279	Soil	WHI11000681	555336	6984805
1202281	Soil	WHI11000681	555259	6984825
1202282	Soil	WHI11000681	555211	6984880
1202283	Soil	WHI11000681	555216	6985212
1202284	Soil	WHI11000681	555054	6985546
1202285	Soil	WHI11000681	554965	6985688
1202286	Soil	WHI11000681	554849	6985890
1202636	Soil	WHI11000681	563861	6982614
1202638	Soil	WHI11000681	563667	6982687
1202639	Soil	WHI11000681	563445	6982823
1202642	Soil	WHI11000681	563305	6983275
1202647	Soil	WHI11000681	550934	6978319
1202751	Soil	WHI11000681	553055	6981266
1202752	Soil	WHI11000681	553078	6981310
1202753	Soil	WHI11000681	553102	6981354

Sample ID	Type	Job#	Easting	Northing
1202754	Soil	WHI11000681	553122	6981402
1202755	Soil	WHI11000681	553146	6981442
1202756	Soil	WHI11000681	553170	6981486
1202757	Soil	WHI11000681	553199	6981529
1202758	Soil	WHI11000681	553210	6981577
1202760	Soil	WHI11000681	553246	6981677
1202761	Soil	WHI11000681	553239	6981736
1202762	Soil	WHI11000681	553267	6981773
1202763	Soil	WHI11000681	553282	6981823
1202764	Soil	WHI11000681	553285	6981875
1202765	Soil	WHI11000681	553295	6981913
1202766	Soil	WHI11000681	553309	6981969
1202767	Soil	WHI11000681	553317	6982019
1202768	Soil	WHI11000681	553324	6982072
1202769	Soil	WHI11000681	553334	6982122
1202770	Soil	WHI11000681	554405	6983363
1202771	Soil	WHI11000681	554377	6983333
1202772	Soil	WHI11000681	554343	6983299
1202773	Soil	WHI11000681	554306	6983261
1202774	Soil	WHI11000681	554275	6983219
1202775	Soil	WHI11000681	554246	6983182
1202776	Soil	WHI11000681	554220	6983143
1202777	Soil	WHI11000681	554184	6983103
1202778	Soil	WHI11000681	554149	6983067
1202779	Soil	WHI11000681	554117	6983030
1202780	Soil	WHI11000681	554086	6982989
1202781	Soil	WHI11000681	554049	6982951
1202782	Soil	WHI11000681	554014	6982916
1202783	Soil	WHI11000681	553984	6982872
1202784	Soil	WHI11000681	553954	6982836
1202785	Soil	WHI11000681	553921	6982796
1202786	Soil	WHI11000681	553891	6982763
1202787	Soil	WHI11000681	553858	6982724
1202788	Soil	WHI11000681	553827	6982689
1202789	Soil	WHI11000681	553795	6982647
1202790	Soil	WHI11000681	553760	6982605
1202791	Soil	WHI11000681	553728	6982577
1202792	Soil	WHI11000681	556379	6977785
1202793	Soil	WHI11000681	556385	6977737
1202794	Soil	WHI11000681	556391	6977688
1202795	Soil	WHI11000681	556387	6977639
1202796	Soil	WHI11000681	556391	6977582
1202797	Soil	WHI11000681	556405	6977534
1202798	Soil	WHI11000681	556408	6977482
1202799	Soil	WHI11000681	556406	6977412
1203201	Soil	WHI11000681	553696	6982543
1203202	Soil	WHI11000681	553662	6982509
1203203	Soil	WHI11000681	553631	6982471
1203204	Soil	WHI11000681	553597	6982429

Sample ID	Type	Job#	Easting	Northing
1203205	Soil	WHI11000681	553563	6982393
1203206	Soil	WHI11000681	553533	6982353
1203208	Soil	WHI11000681	553466	6982279
1203209	Soil	WHI11000681	553436	6982237
1203210	Soil	WHI11000681	553397	6982198
1203211	Soil	WHI11000681	553366	6982158
1203212	Soil	WHI11000681	556966	6979387
1203213	Soil	WHI11000681	556945	6979360
1203214	Soil	WHI11000681	556916	6979333
1203215	Soil	WHI11000681	556877	6979300
1203216	Soil	WHI11000681	556839	6979264
1203217	Soil	WHI11000681	556805	6979226
1203218	Soil	WHI11000681	556769	6979191
1203219	Soil	WHI11000681	556736	6979157
1203220	Soil	WHI11000681	556699	6979118
1203221	Soil	WHI11000681	556665	6979088
1203222	Soil	WHI11000681	556628	6979049
1203223	Soil	WHI11000681	556590	6979018
1203224	Soil	WHI11000681	556555	6978975
1203225	Soil	WHI11000681	556522	6978945
1203226	Soil	WHI11000681	556491	6978902
1203227	Soil	WHI11000681	556451	6978872
1203228	Soil	WHI11000681	556412	6978830
1203229	Soil	WHI11000681	556381	6978799
1203231	Soil	WHI11000681	556344	6978765
1203232	Soil	WHI11000681	556311	6978730
1203233	Soil	WHI11000681	556311	6978678
1203234	Soil	WHI11000681	556322	6978626
1203235	Soil	WHI11000681	556323	6978577
1203236	Soil	WHI11000681	556329	6978529
1203237	Soil	WHI11000681	556331	6978478
1203238	Soil	WHI11000681	556333	6978428
1203239	Soil	WHI11000681	556332	6978379
1203240	Soil	WHI11000681	556340	6978334
1203241	Soil	WHI11000681	556340	6978280
1203242	Soil	WHI11000681	556348	6978235
1203243	Soil	WHI11000681	556353	6978177
1203244	Soil	WHI11000681	556354	6978127
1203245	Soil	WHI11000681	556360	6978083
1203246	Soil	WHI11000681	556360	6978033
1203247	Soil	WHI11000681	556371	6977984
1203248	Soil	WHI11000681	556373	6977930
1203249	Soil	WHI11000681	556378	6977884
1203250	Soil	WHI11000681	556381	6977834
1203660	Soil	WHI11000681	556506	6982997
1203661	Soil	WHI11000681	556467	6983007
1203662	Soil	WHI11000681	556421	6983028
1203663	Soil	WHI11000681	556371	6983040
1203664	Soil	WHI11000681	556321	6983051

Sample ID	Type	Job#	Easting	Northing
1203665	Soil	WHI11000681	556273	6983062
1203666	Soil	WHI11000681	556224	6983071
1203667	Soil	WHI11000681	556175	6983076
1203668	Soil	WHI11000681	556126	6983091
1203669	Soil	WHI11000681	556077	6983099
1203670	Soil	WHI11000681	556028	6983110
1203671	Soil	WHI11000681	555980	6983121
1203672	Soil	WHI11000681	555931	6983133
1203673	Soil	WHI11000681	555883	6983146
1203674	Soil	WHI11000681	555836	6983163
1203675	Soil	WHI11000681	555784	6983163
1203677	Soil	WHI11000681	555685	6983171
1203678	Soil	WHI11000681	555637	6983163
1203679	Soil	WHI11000681	555582	6983167
1203680	Soil	WHI11000681	555538	6983163
1203681	Soil	WHI11000681	555491	6983167
1203682	Soil	WHI11000681	555434	6983171
1203683	Soil	WHI11000681	555386	6983169
1203684	Soil	WHI11000681	555336	6983168
1203685	Soil	WHI11000681	555285	6983167
1203686	Soil	WHI11000681	555236	6983170
1203687	Soil	WHI11000681	555182	6983171
1203688	Soil	WHI11000681	555134	6983167
1203689	Soil	WHI11000681	555084	6983166
1203690	Soil	WHI11000681	555037	6983171
1203691	Soil	WHI11000681	554987	6983164
1203692	Soil	WHI11000681	554943	6983185
1203693	Soil	WHI11000681	554897	6983203
1203694	Soil	WHI11000681	554847	6983224
1203695	Soil	WHI11000681	554802	6983242
1203696	Soil	WHI11000681	554756	6983260
1203697	Soil	WHI11000681	554709	6983280
1203698	Soil	WHI11000681	554660	6983294
1203699	Soil	WHI11000681	554614	6983315
1203700	Soil	WHI11000681	554568	6983338
1204142	Soil	WHI11000681	556934	6982840
1204143	Soil	WHI11000681	556890	6982850
1204144	Soil	WHI11000681	556844	6982874
1204145	Soil	WHI11000681	556794	6982882
1204146	Soil	WHI11000681	556746	6982901
1204147	Soil	WHI11000681	556700	6982921
1204148	Soil	WHI11000681	556657	6982936
1204149	Soil	WHI11000681	556601	6982951
1204150	Soil	WHI11000681	556557	6982970
1204151	Soil	WHI11000681	554525	6983358
1204152	Soil	WHI11000681	554475	6983373
1204153	Soil	WHI11000681	554424	6983394
1204154	Soil	WHI11000681	554382	6983412
1204155	Soil	WHI11000681	554333	6983423

Sample ID	Type	Job#	Easting	Northing
1204156	Soil	WHI11000681	554289	6983442
1204157	Soil	WHI11000681	554238	6983457
1204158	Soil	WHI11000681	554190	6983475
1204159	Soil	WHI11000681	554144	6983489
1204160	Soil	WHI11000681	554097	6983503
1204161	Soil	WHI11000681	554046	6983523
1204162	Soil	WHI11000681	554046	6983523
1204163	Soil	WHI11000681	553952	6983552
1204164	Soil	WHI11000681	563910	6983570
1204165	Soil	WHI11000681	553861	6983586
1204166	Soil	WHI11000681	553813	6983599
1204167	Soil	WHI11000681	553767	6983617
1204168	Soil	WHI11000681	553716	6983629
1204169	Soil	WHI11000681	553670	6983644
1204170	Soil	WHI11000681	553623	6983661
1204171	Soil	WHI11000681	553672	6985672
1204172	Soil	WHI11000681	553519	6983678
1204173	Soil	WHI11000681	553476	6983678
1204174	Soil	WHI11000681	553426	6983688
1204175	Soil	WHI11000681	553525	6983698
1204176	Soil	WHI11000681	553325	6983696
1204177	Soil	WHI11000681	553277	6983708
1204178	Soil	WHI11000681	553220	6983708
1204179	Soil	WHI11000681	553177	6983711
1204180	Soil	WHI11000681	553125	6983721
1204181	Soil	WHI11000681	552076	6983726
1204181	Soil	WHI11000681	552076	6983726
1204182	Soil	WHI11000681	553025	6983736
1204183	Soil	WHI11000681	557978	6983736
1204184	Soil	WHI11000681	552932	6983741
1204185	Soil	WHI11000681	552877	6983743
1204186	Soil	WHI11000681	552828	6983743
1204187	Soil	WHI11000681	552778	6983742
1204188	Soil	WHI11000681	552728	6983743
1204189	Soil	WHI11000681	552678	6983748
1204190	Soil	WHI11000681	552642	6983747
1204192	Soil	WHI11000681	552529	6983771
1204193	Soil	WHI11000681	552487	6983795

Appendix 3A: Rock Sample Assay Certificates

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Submitted By: Bruce Durham
Receiving Lab: Canada-Whitehorse
Received: June 21, 2011
Report Date: August 09, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11000273.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID: VIP-1
P.O. Number
Number of Samples: 52

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	52	Crush, split and pulverize 250 g rock to 200 mesh			WHI
1DX2	52	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Daithi Mac Gearailt
Don Christie
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000273.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1202002	Rock	0.74	0.2	22.5	10.7	19	0.2	2.5	0.9	77	1.09	1.1	<0.5	5.9	12	<0.1	0.1	<0.1	23	0.08	0.028
1202003	Rock	0.72	0.6	4.9	4.0	8	<0.1	1.1	3.0	334	0.79	1.4	<0.5	3.1	23	<0.1	0.1	<0.1	4	0.38	0.061
1202004	Rock	2.04	0.3	25.3	38.4	129	0.2	0.7	0.9	70	0.83	0.9	<0.5	1.3	4	<0.1	<0.1	0.5	4	0.01	0.009
1202006	Rock	2.31	0.4	632.9	9.7	3367	4.0	4.7	10.2	651	0.87	4.1	71.1	0.8	6	21.7	<0.1	0.5	7	0.96	0.027
1202007	Rock	2.74	0.4	5.0	4.5	15	<0.1	6.0	2.2	420	0.65	<0.5	<0.5	0.9	18	0.2	<0.1	<0.1	7	1.56	0.020
1202008	Rock	1.08	1.5	25.1	3.2	58	0.2	0.9	0.7	320	0.45	3.2	4.4	0.4	4	0.4	<0.1	0.2	<2	0.47	0.003
1202009	Rock	0.86	0.3	14.7	2.8	24	<0.1	16.0	5.9	710	1.20	0.6	0.6	1.1	25	<0.1	<0.1	<0.1	11	2.01	0.012
1202010	Rock	0.58	<0.1	2.0	2.8	18	<0.1	1.5	1.9	245	0.59	<0.5	<0.5	1.7	30	<0.1	<0.1	<0.1	5	0.33	0.019
1202011	Rock	1.63	0.4	66.0	2.1	1245	0.7	0.8	1.7	316	0.35	2.7	10.8	0.3	4	8.0	<0.1	<0.1	<2	0.69	0.002
1202012	Rock	0.81	0.5	186.1	3.5	1140	2.0	0.8	2.7	518	0.37	3.3	35.2	0.4	5	7.6	<0.1	0.2	<2	0.99	0.004
1202013	Rock	0.48	0.2	279.7	15.1	652	2.3	2.1	3.0	433	1.18	4.5	20.8	2.5	23	0.8	<0.1	1.5	3	0.91	0.014
1202014	Rock	1.04	0.6	1260	8.2	4397	9.4	0.6	2.2	266	0.53	1.8	18.7	0.2	3	19.4	0.1	2.1	<2	0.12	0.001
1202015	Rock	1.04	4.5	37.5	3.7	61	1.0	2.1	3.0	143	2.63	45.1	41.0	3.1	7	0.3	0.5	0.4	<2	0.22	0.021
1202016	Rock	0.56	0.1	5.1	4.6	31	<0.1	4.2	2.9	358	1.35	0.8	<0.5	6.2	11	0.1	<0.1	<0.1	12	0.97	0.045
1202018	Rock	1.28	0.4	9.2	1.8	17	<0.1	0.9	6.4	155	2.58	1.8	<0.5	0.1	9	<0.1	<0.1	0.1	11	0.18	0.026
1202019	Rock	0.62	1.5	3.2	2.8	23	<0.1	4.5	0.7	62	0.63	3.7	<0.5	1.4	17	<0.1	0.1	0.2	17	0.02	0.016
1202020	Rock	0.92	0.9	61.3	9.0	50	0.1	15.7	8.3	472	2.66	3.4	<0.5	1.7	6	0.2	<0.1	0.2	56	0.15	0.050
1202021	Rock	0.57	0.2	2.6	39.0	19	0.2	3.4	1.4	69	0.47	2.6	<0.5	0.3	1	0.1	<0.1	0.4	9	<0.01	0.003
1202022	Rock	1.14	2.8	5.7	7.5	89	0.2	27.3	1.9	77	1.32	14.3	<0.5	1.6	17	0.1	0.3	0.5	53	0.02	0.043
1202023	Rock	0.60	2.6	22.9	3.7	104	0.2	17.7	1.7	32	1.74	6.1	<0.5	1.7	14	0.3	0.1	0.1	66	0.01	0.041
1202201	Rock	1.06	0.2	1.1	0.7	3	<0.1	0.9	0.5	73	0.36	1.0	<0.5	0.1	2	<0.1	<0.1	<0.1	<2	0.09	0.006
1202202	Rock	0.78	<0.1	12.3	5.8	33	<0.1	6.3	4.9	1004	2.01	1.3	<0.5	1.8	10	0.3	<0.1	<0.1	35	1.60	0.024
1202204	Rock	0.33	1.4	10.2	3.7	5	0.2	1.2	0.3	43	0.64	4.0	<0.5	0.3	6	0.3	<0.1	<0.1	7	0.01	0.045
1202205	Rock	0.61	0.9	16.6	11.0	51	0.1	15.8	4.9	707	0.83	31.6	<0.5	5.4	11	1.4	0.3	<0.1	9	0.22	0.041
1202208	Rock	0.99	1.1	1.9	21.9	32	0.2	1.0	0.3	31	0.95	160.7	23.6	24.6	3	0.1	0.5	0.5	<2	0.01	0.003
1202211	Rock	0.38	0.3	3.1	5.5	5	0.1	2.2	0.4	36	0.45	2.0	<0.5	0.3	3	<0.1	<0.1	0.2	5	<0.01	0.005
1202212	Rock	0.26	7.3	104.3	4.8	144	0.4	40.1	6.2	133	3.49	70.5	<0.5	3.3	26	0.9	0.6	0.1	21	0.02	0.089
1202101	Rock	1.03	0.1	1.5	20.2	5	<0.1	1.2	0.7	42	0.37	1.9	<0.5	<0.1	5	0.9	<0.1	<0.1	4	<0.01	0.002
1202103	Rock	2.38	0.2	4.6	50.6	28	<0.1	8.2	4.2	143	0.89	8.0	0.5	8.0	200	0.5	1.1	0.1	9	5.05	0.025
1202104	Rock	0.89	0.2	4.1	15.4	15	<0.1	11.7	3.6	107	1.07	1.4	<0.5	1.9	8	0.7	<0.1	<0.1	11	0.14	0.013

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000273.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202002	Rock	8	29	0.13	64	0.138	3	0.34	0.119	0.03	<0.1	<0.01	1.8	<0.1	0.11	2	1.3	<0.2
1202003	Rock	7	1	0.14	47	0.024	2	0.37	0.070	0.05	0.2	<0.01	2.2	<0.1	<0.05	2	<0.5	<0.2
1202004	Rock	3	2	0.07	84	0.003	1	0.30	0.057	<0.01	<0.1	<0.01	1.4	<0.1	<0.05	1	<0.5	<0.2
1202006	Rock	3	1	0.29	103	<0.001	1	0.40	0.011	0.04	<0.1	4.35	1.4	<0.1	0.10	1	1.0	<0.2
1202007	Rock	3	4	0.38	34	<0.001	2	0.41	0.007	0.04	<0.1	<0.01	1.4	<0.1	<0.05	1	<0.5	<0.2
1202008	Rock	3	<1	0.03	134	<0.001	2	0.12	0.013	0.04	<0.1	0.03	0.2	<0.1	0.15	<1	<0.5	<0.2
1202009	Rock	3	8	0.75	193	<0.001	1	0.62	0.004	0.06	<0.1	<0.01	1.4	<0.1	0.38	2	<0.5	<0.2
1202010	Rock	5	1	0.15	68	0.016	1	0.41	0.032	0.05	<0.1	<0.01	1.2	<0.1	<0.05	2	<0.5	<0.2
1202011	Rock	2	<1	0.05	158	<0.001	<1	0.13	0.015	0.04	<0.1	0.70	0.2	<0.1	0.13	<1	<0.5	<0.2
1202012	Rock	3	<1	0.05	137	<0.001	<1	0.12	0.015	0.03	<0.1	0.68	0.2	<0.1	0.18	<1	<0.5	<0.2
1202013	Rock	14	<1	0.24	516	<0.001	1	0.46	0.019	0.11	<0.1	1.91	1.0	0.1	0.31	2	0.7	<0.2
1202014	Rock	2	<1	0.07	196	<0.001	2	0.15	0.008	0.04	<0.1	2.85	0.2	<0.1	0.13	<1	1.5	<0.2
1202015	Rock	4	1	0.05	41	<0.001	1	0.30	0.025	0.12	<0.1	0.03	0.7	<0.1	1.86	<1	1.1	<0.2
1202016	Rock	15	5	0.47	63	0.002	<1	0.67	0.070	0.04	<0.1	<0.01	3.0	<0.1	<0.05	5	<0.5	<0.2
1202018	Rock	<1	1	0.25	43	0.017	<1	0.59	0.089	0.04	<0.1	<0.01	1.8	<0.1	0.52	2	0.8	0.3
1202019	Rock	6	7	<0.01	97	<0.001	<1	0.14	0.016	0.08	<0.1	<0.01	0.9	<0.1	0.06	<1	1.1	<0.2
1202020	Rock	7	52	0.79	111	0.004	<1	1.14	0.015	0.12	<0.1	<0.01	4.9	<0.1	<0.05	5	<0.5	<0.2
1202021	Rock	<1	3	0.01	27	<0.001	<1	0.05	0.002	0.03	<0.1	<0.01	0.6	<0.1	<0.05	<1	<0.5	<0.2
1202022	Rock	6	21	0.02	90	<0.001	<1	0.14	0.003	0.06	<0.1	<0.01	2.1	<0.1	<0.05	<1	3.9	0.3
1202023	Rock	4	28	0.02	339	<0.001	<1	0.25	0.053	0.18	0.2	<0.01	2.5	<0.1	0.33	2	2.0	<0.2
1202201	Rock	<1	1	0.02	35	<0.001	<1	0.04	0.003	0.01	0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
1202202	Rock	4	4	1.05	110	0.038	<1	0.91	0.065	0.31	<0.1	<0.01	3.0	<0.1	0.25	3	<0.5	<0.2
1202204	Rock	1	4	<0.01	45	<0.001	<1	0.05	0.014	0.03	<0.1	<0.01	0.3	<0.1	0.05	<1	1.0	<0.2
1202205	Rock	20	4	0.09	107	<0.001	2	0.36	0.022	0.15	<0.1	<0.01	1.1	<0.1	<0.05	1	2.4	<0.2
1202208	Rock	9	1	0.01	62	<0.001	<1	0.20	0.074	0.08	<0.1	<0.01	0.4	<0.1	0.18	<1	2.6	<0.2
1202211	Rock	1	4	<0.01	17	0.002	<1	0.06	0.007	<0.01	<0.1	<0.01	0.3	<0.1	<0.05	<1	<0.5	<0.2
1202212	Rock	12	9	0.03	94	0.001	2	0.33	0.004	0.13	<0.1	<0.01	3.1	<0.1	<0.05	1	2.9	<0.2
1202101	Rock	<1	2	<0.01	25	<0.001	<1	0.05	0.008	0.01	<0.1	<0.01	0.5	<0.1	<0.05	<1	<0.5	<0.2
1202103	Rock	18	11	0.23	15	0.066	<1	1.50	0.033	0.05	0.2	<0.01	2.1	<0.1	<0.05	5	<0.5	<0.2
1202104	Rock	4	17	0.27	23	0.027	<1	0.49	0.017	0.09	<0.1	<0.01	1.2	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000273.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1202106	Rock	1.00	0.4	21.4	8.8	59	<0.1	20.8	21.2	646	3.74	2.0	<0.5	2.4	80	0.4	0.1	<0.1	89	2.16	0.054
1202107	Rock	1.16	0.2	1.0	2.9	5	<0.1	1.9	0.8	237	0.81	0.9	<0.5	0.3	24	0.2	<0.1	<0.1	3	0.60	0.002
1202108	Rock	1.57	0.1	37.0	10.2	23	<0.1	9.4	12.4	727	2.78	1.2	<0.5	3.6	144	<0.1	<0.1	0.5	12	2.53	0.085
1202109	Rock	1.87	0.4	14.3	7.8	69	<0.1	43.7	17.1	511	3.33	2.5	0.7	7.9	125	<0.1	<0.1	0.1	29	4.33	0.011
1202110	Rock	1.36	24.6	27.2	10.8	100	0.2	30.4	1.2	37	1.08	13.7	<0.5	3.3	33	0.2	0.1	0.2	230	0.15	0.067
1202111	Rock	1.85	0.1	2.7	1.8	13	<0.1	6.9	2.5	98	0.63	0.7	<0.5	0.4	6	<0.1	<0.1	<0.1	5	0.09	0.003
1202051	Rock	2.11	0.2	7.5	0.9	20	<0.1	2.6	4.4	183	1.89	1.2	1.5	0.1	8	<0.1	<0.1	<0.1	18	0.21	0.024
1202052	Rock	0.60	1.2	41.1	4.4	47	<0.1	18.3	11.2	459	2.10	1.5	<0.5	2.1	8	0.2	<0.1	0.2	41	0.13	0.054
1202054	Rock	1.32	0.1	2.8	0.8	2	<0.1	2.6	0.9	32	0.29	1.2	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
1202055	Rock	0.79	0.2	15.6	0.6	4	<0.1	3.7	1.6	76	0.70	0.8	<0.5	0.6	3	<0.1	<0.1	<0.1	5	0.04	0.008
1202056	Rock	0.74	0.3	7.5	3.0	27	<0.1	7.3	8.7	192	1.52	1.4	0.9	0.3	25	<0.1	<0.1	<0.1	31	1.01	0.067
1202057	Rock	0.71	0.3	5.9	1.0	14	<0.1	5.7	2.0	142	0.74	1.8	<0.5	1.4	2	<0.1	<0.1	<0.1	4	0.03	0.011
1202058	Rock	2.16	0.4	1.9	9.2	61	<0.1	11.5	6.8	408	2.03	1.3	<0.5	3.9	13	<0.1	<0.1	<0.1	37	0.30	0.083
1202059	Rock	2.18	0.1	25.1	16.6	50	0.1	17.7	6.5	604	1.46	2.8	<0.5	7.3	425	0.2	<0.1	0.3	33	11.74	0.036
1202151	Rock	1.78	0.3	5.6	3.3	11	<0.1	1.2	2.8	157	1.35	0.7	<0.5	2.0	12	<0.1	<0.1	<0.1	10	0.20	0.023
1202152	Rock	0.56	0.1	2.2	0.5	1	<0.1	1.7	0.2	25	0.25	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
1202153	Rock	1.62	0.2	2.3	1.0	3	<0.1	7.1	1.8	47	0.34	0.9	<0.5	<0.1	3	<0.1	<0.1	<0.1	<2	0.04	0.001
1202154	Rock	1.13	0.4	13.8	3.6	13	<0.1	3.7	3.9	160	1.33	5.3	<0.5	22.9	4	<0.1	<0.1	0.1	9	0.06	0.023
1202155	Rock	0.58	<0.1	5.4	1.1	20	<0.1	1254	63.4	878	2.85	5.7	4.8	0.3	7	<0.1	0.1	0.2	20	0.32	0.001
1202156	Rock	0.37	4.0	35.2	6.0	74	0.2	24.4	6.7	219	1.46	10.3	2.0	2.7	7	0.4	0.4	0.1	35	0.16	0.028
1202157	Rock	0.60	<0.1	4.2	1.7	79	<0.1	11.9	16.9	571	3.93	1.4	<0.5	0.2	11	<0.1	<0.1	<0.1	122	0.60	0.040
1202158	Rock	0.84	<0.1	1.5	2.4	25	<0.1	1216	63.7	649	3.77	2.6	0.7	0.1	1	<0.1	0.1	0.2	4	0.03	0.002

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000273.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202106	Rock	4	44	2.39	175	0.143	<1	2.38	0.041	0.32	<0.1	<0.01	8.5	<0.1	0.09	7	<0.5	<0.2
1202107	Rock	2	1	0.20	19	<0.001	<1	0.04	0.002	0.02	<0.1	<0.01	1.0	<0.1	<0.05	<1	<0.5	<0.2
1202108	Rock	9	11	0.21	29	0.041	<1	1.19	0.024	0.03	0.2	<0.01	1.6	<0.1	<0.05	5	<0.5	<0.2
1202109	Rock	17	43	1.16	37	0.172	<1	1.97	0.019	0.31	<0.1	<0.01	2.5	0.2	<0.05	5	<0.5	<0.2
1202110	Rock	10	19	0.18	100	0.002	<1	0.31	0.010	0.14	0.5	<0.01	1.4	<0.1	0.05	3	2.0	<0.2
1202111	Rock	1	5	0.17	28	0.035	<1	0.29	0.015	0.13	<0.1	<0.01	0.3	<0.1	<0.05	<1	<0.5	<0.2
1202051	Rock	<1	1	0.44	60	0.043	<1	0.69	0.070	0.07	<0.1	<0.01	1.9	<0.1	0.39	2	<0.5	<0.2
1202052	Rock	5	43	0.67	80	0.005	<1	0.94	0.004	0.10	<0.1	<0.01	4.3	<0.1	<0.05	4	0.5	<0.2
1202054	Rock	<1	1	0.01	5	<0.001	<1	0.03	0.002	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
1202055	Rock	<1	8	0.12	13	0.021	<1	0.15	0.003	0.02	<0.1	<0.01	0.5	<0.1	<0.05	<1	<0.5	<0.2
1202056	Rock	2	58	0.80	18	0.136	<1	1.17	0.100	0.05	<0.1	<0.01	3.8	<0.1	<0.05	3	<0.5	<0.2
1202057	Rock	3	3	0.02	22	0.001	<1	0.09	0.005	0.03	<0.1	<0.01	0.4	<0.1	<0.05	<1	<0.5	<0.2
1202058	Rock	9	43	0.86	205	0.099	<1	1.37	0.024	0.80	<0.1	<0.01	3.0	0.3	<0.05	5	<0.5	<0.2
1202059	Rock	14	26	0.51	50	0.014	3	0.86	0.004	0.12	0.4	<0.01	2.8	<0.1	<0.05	4	<0.5	<0.2
1202151	Rock	2	1	0.35	86	0.062	<1	0.70	0.049	0.24	<0.1	<0.01	1.2	<0.1	<0.05	2	<0.5	<0.2
1202152	Rock	<1	<1	<0.01	2	<0.001	<1	0.01	0.003	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
1202153	Rock	<1	2	0.02	7	0.001	<1	0.10	0.023	0.01	<0.1	<0.01	0.1	<0.1	<0.05	<1	<0.5	<0.2
1202154	Rock	27	5	0.30	29	0.006	<1	0.50	0.044	0.13	<0.1	<0.01	1.6	<0.1	<0.05	5	<0.5	<0.2
1202155	Rock	2	613	11.84	4	0.005	16	0.22	<0.001	0.02	0.1	<0.01	8.3	<0.1	<0.05	<1	<0.5	<0.2
1202156	Rock	7	8	0.33	41	0.003	<1	0.47	0.003	0.10	<0.1	<0.01	1.4	<0.1	<0.05	2	0.6	<0.2
1202157	Rock	1	6	1.48	49	0.102	<1	2.01	0.097	0.31	<0.1	<0.01	5.8	0.1	<0.05	6	<0.5	<0.2
1202158	Rock	<1	389	9.94	4	0.003	14	0.10	0.001	<0.01	0.1	<0.01	2.0	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000273.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
REP 1202103	QC		0.2	4.4	43.5	27	<0.1	8.7	4.0	141	0.91	7.7	<0.5	7.9	206	<0.1	1.1	<0.1	9	4.71	0.024
1202056	Rock	0.74	0.3	7.5	3.0	27	<0.1	7.3	8.7	192	1.52	1.4	0.9	0.3	25	<0.1	<0.1	<0.1	31	1.01	0.067
REP 1202056	QC		0.2	7.3	3.0	27	<0.1	7.5	8.2	193	1.51	1.4	<0.5	0.3	23	<0.1	<0.1	<0.1	31	0.99	0.067
Core Reject Duplicates																					
1202103	Rock	2.38	0.2	4.6	50.6	28	<0.1	8.2	4.2	143	0.89	8.0	0.5	8.0	200	0.5	1.1	0.1	9	5.05	0.025
DUP 1202103	QC		0.1	4.3	50.8	27	<0.1	8.9	4.5	146	0.88	7.0	<0.5	8.5	204	<0.1	1.1	0.1	9	4.99	0.025
Reference Materials																					
STD DS8	Standard		12.5	108.7	129.1	305	1.8	39.5	7.5	608	2.44	25.2	119.5	6.9	62	2.2	5.5	6.9	39	0.68	0.074
STD DS8	Standard		12.8	111.4	131.2	319	1.9	38.4	7.7	600	2.44	26.1	106.6	6.9	64	2.4	5.6	7.0	40	0.69	0.078
STD DS8	Standard		12.8	103.5	120.8	307	1.9	37.7	7.4	606	2.50	27.5	113.8	6.4	62	2.5	5.4	6.6	42	0.69	0.076
STD DS8	Standard		13.1	103.0	122.8	317	1.7	36.7	7.6	608	2.46	27.0	108.5	6.4	66	2.6	5.5	6.6	42	0.72	0.075
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
Prep Wash																					
G1	Prep Blank		0.1	1.6	2.7	49	<0.1	3.8	4.5	554	2.01	<0.5	<0.5	4.7	52	<0.1	0.2	<0.1	37	0.47	0.072
G1	Prep Blank		<0.1	1.4	2.7	49	<0.1	4.2	4.4	568	2.02	0.6	<0.5	5.2	55	<0.1	<0.1	<0.1	38	0.45	0.078

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000273.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
REP 1202103	QC	18	11	0.23	15	0.066	<1	1.39	0.029	0.05	0.2	<0.01	2.1	<0.1	<0.05	5	<0.5	<0.2
1202056	Rock	2	58	0.80	18	0.136	<1	1.17	0.100	0.05	<0.1	<0.01	3.8	<0.1	<0.05	3	<0.5	<0.2
REP 1202056	QC	2	60	0.78	18	0.133	<1	1.18	0.098	0.05	<0.1	<0.01	3.7	<0.1	<0.05	3	<0.5	<0.2
Core Reject Duplicates																		
1202103	Rock	18	11	0.23	15	0.066	<1	1.50	0.033	0.05	0.2	<0.01	2.1	<0.1	<0.05	5	<0.5	<0.2
DUP 1202103	QC	19	11	0.24	15	0.067	<1	1.42	0.027	0.05	0.2	<0.01	2.2	<0.1	<0.05	5	<0.5	<0.2
Reference Materials																		
STD DS8	Standard	12	116	0.59	248	0.116	2	0.89	0.082	0.40	2.8	0.20	1.8	5.3	0.16	4	4.3	5.1
STD DS8	Standard	13	116	0.60	255	0.122	2	0.89	0.083	0.40	2.8	0.22	1.9	5.4	0.16	4	4.4	5.0
STD DS8	Standard	14	115	0.59	280	0.103	4	0.88	0.082	0.41	3.1	0.16	2.1	5.1	0.17	5	6.1	5.4
STD DS8	Standard	14	110	0.60	283	0.107	4	0.92	0.089	0.41	3.2	0.17	2.2	5.1	0.17	5	5.4	4.9
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
Prep Wash																		
G1	Prep Blank	8	6	0.57	219	0.110	2	0.97	0.088	0.51	<0.1	<0.01	1.9	0.3	<0.05	5	<0.5	<0.2
G1	Prep Blank	10	7	0.59	225	0.111	2	0.99	0.087	0.50	<0.1	<0.01	1.9	0.3	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Submitted By: Daithi Mac Gerailt
Receiving Lab: Canada-Whitehorse
Received: July 05, 2011
Report Date: August 11, 2011
Page: 1 of 4

CERTIFICATE OF ANALYSIS WHI11000461.1

CLIENT JOB INFORMATION

Project:
Shipment ID:
P.O. Number
Number of Samples: 83

SAMPLE DISPOSAL

STOR-PLP	Store After 90 days Invoice for Storage
DISP-RJT	Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	83	Crush, split and pulverize 250 g rock to 200 mesh			VAN
3B	83	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	83	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Don Christie
Bruce Durham
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000461.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1202034	Rock	0.62	<2	0.4	3.4	10.8	18	<0.1	1.1	0.7	423	0.89	1.4	2.1	13.1	34	0.1	0.1	<0.1	<2	0.65
1202035	Rock	0.45	<2	0.4	4.3	7.8	15	<0.1	1.3	0.4	177	0.53	2.4	2.8	29.5	13	0.3	0.4	0.4	<2	0.06
1202036	Rock	0.48	<2	1.0	10.0	3.7	7	<0.1	0.8	0.2	32	0.86	3.1	3.1	22.6	1	<0.1	5.5	0.2	<2	<0.01
1202037	Rock	0.39	9	3.8	105.8	4.7	31	0.2	0.7	0.5	56	3.13	2.8	10.1	9.3	5	<0.1	<0.1	1.4	2	<0.01
1202038	Rock	0.61	<2	4.6	4.6	5.6	29	<0.1	1.0	0.2	36	1.24	1.9	1.2	12.5	4	0.1	0.2	0.4	<2	<0.01
1202039	Rock	0.55	6	2.3	15.0	27.7	5	0.1	0.9	0.2	35	1.73	4.1	6.6	12.9	9	<0.1	0.2	0.5	<2	<0.01
1202040	Rock	0.80	<2	0.3	8.8	1.4	27	<0.1	1.4	0.7	108	0.75	1.2	<0.5	1.5	1	<0.1	0.1	<0.1	<2	<0.01
1202041	Rock	0.48	7	0.6	135.9	6.9	8	0.7	2.5	1.4	60	1.19	3.2	9.0	1.3	7	<0.1	1.1	2.0	<2	<0.01
1202042	Rock	0.28	<2	0.7	94.3	10.1	39	0.1	1.2	0.4	78	3.26	2.4	3.3	33.1	6	0.1	0.2	1.4	<2	<0.01
1202043	Rock	0.50	<2	1.7	64.2	70.9	81	0.2	2.9	1.0	120	2.21	3.6	0.9	40.8	23	0.2	0.2	0.4	3	<0.01
1202044	Rock	0.77	<2	2.5	20.3	2.3	8	<0.1	0.8	0.6	26	1.22	1.7	<0.5	33.5	23	<0.1	0.5	0.2	<2	<0.01
1202070	Rock	1.58	4	4.2	20.3	20.0	88	<0.1	3.2	2.1	144	6.06	3.7	6.7	2.7	15	<0.1	<0.1	1.3	34	0.03
1202071	Rock	0.73	<2	0.2	31.5	12.9	64	<0.1	148.5	33.9	1108	4.05	2.9	0.7	2.1	54	0.4	<0.1	0.1	89	1.85
1202072	Rock	0.51	<2	0.1	1.0	3.6	69	<0.1	9.5	5.7	1897	3.42	7.2	0.7	0.5	87	0.1	<0.1	<0.1	3	19.71
1202073	Rock	1.24	<2	0.2	1.1	4.6	74	<0.1	9.0	7.7	1871	3.72	13.4	1.0	0.5	96	0.2	0.1	<0.1	2	18.31
1202074	Rock	0.54	<2	0.2	1.8	2.0	34	<0.1	1.6	2.9	307	1.37	2.0	1.1	2.6	15	0.1	<0.1	<0.1	4	0.85
1202075	Rock	0.69	<2	<0.1	2.9	5.5	75	<0.1	11.3	8.3	2533	3.88	33.6	1.8	0.2	109	0.3	0.2	<0.1	<2	20.86
1202077	Rock	1.37	<2	0.4	14.4	1.2	6	<0.1	14.4	7.8	204	1.32	0.9	1.0	3.6	16	<0.1	<0.1	<0.1	22	0.62
1202078	Rock	0.52	<2	0.4	1.9	1.5	7	<0.1	1.1	1.3	313	0.49	0.6	<0.5	2.5	11	<0.1	<0.1	<0.1	<2	0.35
1202060	Rock	1.61	<2	1.1	4.0	10.5	28	<0.1	3.2	0.8	48	0.82	0.9	<0.5	21.9	6	<0.1	<0.1	0.1	5	0.01
1202061	Rock	0.96	<2	1.0	4.3	8.4	16	<0.1	1.1	2.1	474	1.10	1.5	<0.5	10.2	3	0.1	<0.1	<0.1	7	0.05
1202062	Rock	2.60	<2	4.6	4.1	12.6	5	0.1	1.7	0.3	39	0.72	0.8	0.6	0.7	9	<0.1	0.1	0.1	10	0.06
1202063	Rock	0.83	<2	0.3	31.7	2.1	22	<0.1	61.0	14.7	291	1.54	1.0	<0.5	0.9	35	0.1	0.1	<0.1	26	1.03
1202064	Rock	1.23	<2	2.0	5.2	1.9	4	<0.1	1.3	0.3	50	0.69	1.3	<0.5	0.5	6	0.2	<0.1	<0.1	12	0.02
1202065	Rock	0.62	<2	0.2	8.7	2.1	18	<0.1	1.5	1.1	329	0.94	3.5	0.9	9.6	8	0.1	<0.1	<0.1	<2	0.31
1202066	Rock	1.03	<2	<0.1	27.0	0.8	46	<0.1	34.9	25.7	518	3.12	0.9	0.8	0.2	51	<0.1	<0.1	<0.1	66	0.85
1202067	Rock	0.81	<2	0.3	19.6	0.3	3	<0.1	1.5	0.9	54	0.62	3.1	<0.5	0.1	<1	<0.1	<0.1	<0.1	<2	0.01
1202068	Rock	1.25	<2	0.7	2.4	1.2	2	<0.1	1.2	0.3	38	0.54	1.2	<0.5	0.5	4	<0.1	<0.1	<0.1	3	<0.01
1202112	Rock	1.02	<2	0.9	1.9	124.7	149	0.2	2.9	2.0	546	0.78	1.6	1.3	19.3	15	1.4	<0.1	1.6	<2	0.15
1202113	Rock	0.93	<2	2.3	1.4	5.1	7	<0.1	0.9	0.3	36	0.66	1.0	<0.5	20.3	6	<0.1	<0.1	1.6	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000461.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1202034	Rock	0.001	74	2	0.35	12	0.001	<20	0.13	0.087	0.02	0.1	<0.01	<0.1	0.10	0.2	<0.5	<1	<0.2
1202035	Rock	0.001	49	2	0.05	21	0.002	<20	0.16	0.029	0.16	0.1	<0.01	<0.1	0.08	0.3	<0.5	<1	<0.2
1202036	Rock	0.001	12	1	0.01	21	0.002	<20	0.20	0.006	0.21	0.6	0.02	<0.1	0.07	0.1	<0.5	<1	<0.2
1202037	Rock	0.016	36	2	0.14	83	0.002	<20	0.28	0.090	0.04	<0.1	<0.01	<0.1	0.07	0.2	0.7	3	0.3
1202038	Rock	0.002	7	2	0.02	871	0.002	<20	0.25	0.003	0.22	0.2	<0.01	<0.1	<0.05	0.1	<0.5	<1	<0.2
1202039	Rock	0.003	25	2	<0.01	210	0.002	<20	0.18	0.051	0.33	0.1	<0.01	<0.1	0.47	0.1	<0.5	<1	<0.2
1202040	Rock	0.001	1	<1	0.01	35	<0.001	<20	0.06	0.003	0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
1202041	Rock	0.003	3	3	<0.01	145	<0.001	<20	0.03	0.003	0.02	<0.1	<0.01	<0.1	0.10	0.1	0.7	<1	<0.2
1202042	Rock	0.014	82	2	0.07	56	0.006	<20	0.40	0.012	0.31	<0.1	0.01	0.1	<0.05	0.2	1.1	2	0.3
1202043	Rock	0.027	42	2	0.02	116	0.001	<20	0.24	0.004	0.27	<0.1	<0.01	<0.1	0.14	0.6	0.7	<1	<0.2
1202044	Rock	0.007	24	1	0.03	684	0.001	<20	0.29	0.003	0.26	<0.1	0.07	<0.1	0.35	0.1	1.6	<1	<0.2
1202070	Rock	0.019	4	4	0.92	52	0.002	<20	1.37	0.018	0.10	<0.1	0.04	<0.1	<0.05	2.0	9.4	4	0.5
1202071	Rock	0.051	7	209	4.22	44	0.202	<20	3.71	0.042	0.02	<0.1	0.02	<0.1	<0.05	6.0	0.7	8	<0.2
1202072	Rock	0.005	1	<1	8.29	8	0.002	<20	0.27	0.005	<0.01	<0.1	<0.01	<0.1	0.29	0.8	0.7	<1	<0.2
1202073	Rock	0.006	1	<1	7.60	14	<0.001	<20	0.33	0.002	0.01	<0.1	<0.01	<0.1	0.47	0.9	0.7	<1	<0.2
1202074	Rock	0.018	3	2	0.60	119	0.002	<20	0.99	0.047	0.14	<0.1	<0.01	<0.1	0.15	1.2	<0.5	2	<0.2
1202075	Rock	0.006	<1	<1	7.70	18	<0.001	<20	0.12	0.001	<0.01	<0.1	<0.01	<0.1	0.56	0.4	0.7	<1	<0.2
1202077	Rock	0.036	5	19	0.86	54	0.015	<20	0.91	0.038	0.10	<0.1	<0.01	<0.1	<0.05	1.5	<0.5	3	<0.2
1202078	Rock	0.009	4	1	0.13	240	0.002	<20	0.44	0.053	0.13	<0.1	<0.01	<0.1	<0.05	0.7	<0.5	1	<0.2
1202060	Rock	0.008	14	2	0.02	23	0.001	<20	0.20	0.102	0.09	<0.1	<0.01	<0.1	<0.05	1.2	0.6	<1	<0.2
1202061	Rock	0.010	18	2	0.02	166	0.009	<20	0.30	0.063	0.18	<0.1	<0.01	<0.1	<0.05	2.7	<0.5	1	<0.2
1202062	Rock	0.059	2	5	<0.01	50	<0.001	<20	0.10	0.036	0.03	<0.1	<0.01	<0.1	0.06	0.4	1.3	<1	<0.2
1202063	Rock	0.053	3	118	1.06	186	0.143	<20	1.17	0.046	0.10	<0.1	<0.01	<0.1	<0.05	2.0	<0.5	2	<0.2
1202064	Rock	0.031	3	5	0.01	75	0.001	<20	0.13	0.012	0.08	<0.1	<0.01	<0.1	0.07	0.5	1.3	<1	<0.2
1202065	Rock	0.005	13	2	0.05	176	0.002	<20	0.42	0.055	0.15	<0.1	<0.01	<0.1	<0.05	0.9	<0.5	1	<0.2
1202066	Rock	0.044	<1	44	2.60	40	0.231	<20	2.62	0.019	0.06	<0.1	<0.01	<0.1	<0.05	3.0	<0.5	4	<0.2
1202067	Rock	<0.001	<1	2	0.02	10	0.002	<20	0.04	0.002	0.01	<0.1	<0.01	<0.1	<0.05	0.2	<0.5	<1	<0.2
1202068	Rock	0.007	2	3	0.01	39	0.002	<20	0.06	0.019	0.02	<0.1	<0.01	<0.1	<0.05	0.2	0.5	<1	<0.2
1202112	Rock	0.028	23	2	0.06	118	0.003	<20	0.20	0.020	0.24	<0.1	<0.01	0.2	0.08	0.4	<0.5	<1	<0.2
1202113	Rock	0.008	41	1	0.04	46	0.002	<20	0.23	0.059	0.19	<0.1	<0.01	<0.1	0.10	0.4	<0.5	<1	0.5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000461.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1202114	Rock	1.50	<2	0.4	1.5	2.8	3	<0.1	0.7	0.3	42	0.67	0.5	<0.5	12.9	2	<0.1	<0.1	<0.1	<2	0.01
1202115	Rock	0.34	<2	1.2	1.4	8.5	8	<0.1	0.5	0.7	171	0.85	0.8	<0.5	9.5	11	<0.1	<0.1	<0.1	3	0.25
1202116	Rock	0.94	<2	1.4	2.6	13.6	7	0.2	1.7	0.3	44	0.77	1.6	<0.5	0.9	4	<0.1	<0.1	0.3	7	<0.01
1202117	Rock	0.78	<2	0.5	8.0	1.3	8	<0.1	2.5	7.8	104	0.78	16.6	3.1	<0.1	1	<0.1	<0.1	<0.1	<2	0.10
1202118	Rock	1.56	<2	2.7	8.1	4.1	4	0.3	1.1	0.2	31	0.59	1.1	1.5	1.2	7	0.1	<0.1	0.1	12	0.03
1202119	Rock	0.72	<2	0.2	45.3	2.4	23	<0.1	82.5	19.6	328	1.81	<0.5	<0.5	0.6	31	0.2	<0.1	<0.1	27	0.97
1202120	Rock	0.80	<2	3.5	1.8	1.7	1	0.3	0.7	0.2	29	0.34	11.3	3.2	0.9	2	<0.1	<0.1	<0.1	12	<0.01
1202121	Rock	1.12	<2	1.0	1.9	2.0	2	<0.1	1.2	0.3	33	0.46	1.4	0.6	0.7	3	<0.1	<0.1	<0.1	6	0.01
1202122	Rock	1.00	<2	0.6	3.1	2.0	41	<0.1	6.9	6.0	381	1.52	<0.5	<0.5	1.5	56	0.1	<0.1	<0.1	29	0.81
1202123	Rock	0.98	<2	0.7	17.5	35.5	5	0.5	1.5	0.2	27	0.36	<0.5	0.8	0.3	4	<0.1	<0.1	0.5	5	0.01
1202124	Rock	0.74	<2	0.1	3.3	5.9	7	<0.1	0.9	1.3	128	0.72	<0.5	<0.5	5.3	8	<0.1	<0.1	<0.1	<2	0.17
1202125	Rock	1.22	<2	0.2	14.9	2.3	36	<0.1	16.7	12.5	377	2.14	<0.5	<0.5	7.7	83	<0.1	<0.1	0.3	33	1.36
1202127	Rock	1.29	4	0.3	7.9	4.7	46	<0.1	2.8	1.1	241	4.26	2.3	4.8	1.1	3	<0.1	<0.1	1.3	39	0.02
1202128	Rock	0.98	<2	0.2	16.5	37.8	146	<0.1	7.5	2.2	169	6.29	2.7	2.6	3.0	20	<0.1	<0.1	0.8	54	0.07
1202129	Rock	0.94	<2	0.2	4.8	2.3	49	<0.1	1.2	2.5	289	1.08	0.7	<0.5	2.3	20	<0.1	<0.1	<0.1	7	0.44
1202130	Rock	2.03	<2	0.2	2.4	4.5	42	<0.1	10.9	7.3	2617	3.74	47.5	2.3	0.4	81	0.1	0.2	0.1	<2	14.25
1202131	Rock	1.43	<2	0.2	1.8	4.9	37	<0.1	13.3	9.7	2349	3.45	38.0	3.9	0.2	88	0.1	0.2	0.2	<2	15.45
1202132	Rock	0.89	3	0.1	4.6	6.6	53	0.1	11.1	10.6	2544	4.21	63.8	4.5	<0.1	91	0.2	0.3	0.2	<2	15.01
1202133	Rock	0.77	<2	0.1	18.7	0.3	5	<0.1	0.6	0.4	53	0.35	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	0.16
1202134	Rock	0.63	<2	<0.1	14.6	0.7	4	<0.1	0.8	0.5	182	0.33	<0.5	<0.5	0.2	1	<0.1	<0.1	<0.1	<2	0.15
1202135	Rock	0.87	<2	0.2	1.7	0.2	<1	<0.1	0.5	0.3	42	0.41	0.6	0.9	0.1	1	<0.1	<0.1	<0.1	<2	0.03
1202136	Rock	0.77	<2	0.3	4.4	2.3	39	<0.1	4.4	5.0	289	1.74	<0.5	<0.5	2.9	18	<0.1	<0.1	<0.1	14	0.23
1202145	Rock	0.25	<2	0.8	29.4	7.1	60	<0.1	21.2	12.2	423	3.31	<0.5	<0.5	8.5	16	<0.1	<0.1	<0.1	30	0.37
1202146	Rock	0.25	<2	0.6	29.5	5.9	87	<0.1	20.7	6.9	405	2.72	<0.5	0.6	3.3	22	0.5	<0.1	0.2	58	1.01
1202147	Rock	0.54	<2	0.2	50.3	10.5	32	<0.1	52.3	14.8	302	1.97	6.2	1.3	3.1	28	<0.1	<0.1	<0.1	46	1.53
1202148	Rock	0.53	2	0.2	28.2	4.6	34	<0.1	17.2	17.2	1721	3.55	<0.5	<0.5	5.5	71	0.2	<0.1	<0.1	13	1.76
1202149	Rock	0.85	<2	2.1	24.5	135.8	47	0.4	20.9	7.2	492	1.27	18.6	0.6	1.6	10	0.1	0.5	1.6	18	0.13
1202150	Rock	0.80	<2	14.2	86.7	141.2	75	0.6	42.8	11.4	823	2.02	37.5	2.1	4.2	23	0.8	0.6	0.9	29	0.36
1202093	Rock	0.62	<2	0.2	3.3	1.8	10	<0.1	5.7	2.6	804	0.58	<0.5	<0.5	<0.1	2	0.2	<0.1	<0.1	<2	0.12
1202094	Rock	1.08	<2	4.3	7.5	3.9	34	0.4	10.9	1.0	57	1.04	11.7	<0.5	1.4	8	<0.1	<0.1	<0.1	22	0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000461.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1202114	Rock	0.004	2	1	<0.01	100	0.006	<20	0.23	0.088	0.20	<0.1	<0.01	<0.1	<0.05	0.7	<0.5	<1	<0.2
1202115	Rock	0.004	23	1	0.02	322	0.008	<20	0.30	0.066	0.22	<0.1	<0.01	<0.1	<0.05	2.0	<0.5	1	<0.2
1202116	Rock	0.010	3	4	<0.01	79	<0.001	<20	0.09	0.007	0.08	<0.1	<0.01	<0.1	0.08	0.2	1.4	<1	<0.2
1202117	Rock	0.005	<1	<1	0.03	17	<0.001	<20	0.08	0.002	0.01	<0.1	<0.01	<0.1	<0.05	0.3	<0.5	<1	<0.2
1202118	Rock	0.038	5	6	0.01	97	0.001	<20	0.12	0.008	0.09	<0.1	0.01	<0.1	0.09	0.4	1.7	<1	<0.2
1202119	Rock	0.055	2	121	1.46	232	0.123	<20	1.50	0.024	0.11	<0.1	<0.01	<0.1	<0.05	1.8	<0.5	2	<0.2
1202120	Rock	0.035	8	3	0.01	183	0.002	<20	0.11	0.004	0.08	<0.1	<0.01	<0.1	<0.05	2.4	0.9	<1	<0.2
1202121	Rock	0.024	3	4	0.02	54	0.002	<20	0.09	0.010	0.07	<0.1	<0.01	<0.1	0.06	0.5	0.6	<1	<0.2
1202122	Rock	0.053	5	12	0.46	53	0.091	<20	0.80	0.055	0.02	<0.1	<0.01	<0.1	<0.05	3.2	<0.5	5	<0.2
1202123	Rock	0.019	1	2	<0.01	107	<0.001	<20	0.07	0.006	0.03	<0.1	<0.01	<0.1	<0.05	0.2	0.8	<1	<0.2
1202124	Rock	0.009	12	2	0.02	109	0.002	<20	0.22	0.031	0.16	<0.1	<0.01	<0.1	<0.05	1.0	<0.5	1	<0.2
1202125	Rock	0.018	15	22	1.05	254	0.148	<20	1.85	0.020	0.31	0.1	<0.01	<0.1	<0.05	2.8	<0.5	7	<0.2
1202127	Rock	0.014	4	1	1.38	64	0.002	<20	1.50	0.017	0.11	<0.1	0.03	<0.1	<0.05	1.5	1.4	5	0.6
1202128	Rock	0.037	4	14	1.85	62	0.003	<20	2.30	0.019	0.11	<0.1	0.04	<0.1	<0.05	4.8	3.9	7	0.8
1202129	Rock	0.022	8	<1	0.19	81	0.003	<20	0.58	0.040	0.07	<0.1	<0.01	<0.1	<0.05	2.3	<0.5	2	<0.2
1202130	Rock	0.006	2	<1	8.78	34	<0.001	<20	0.20	0.007	0.02	<0.1	<0.01	<0.1	1.22	0.6	1.5	<1	<0.2
1202131	Rock	0.004	<1	<1	9.31	16	<0.001	<20	0.10	0.005	0.01	<0.1	<0.01	<0.1	1.19	0.4	1.4	<1	<0.2
1202132	Rock	0.005	<1	<1	8.00	15	<0.001	<20	0.03	0.005	<0.01	<0.1	<0.01	<0.1	1.37	0.3	1.3	<1	<0.2
1202133	Rock	0.004	<1	<1	0.07	17	<0.001	<20	0.07	0.006	0.02	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
1202134	Rock	0.003	<1	<1	0.10	22	<0.001	<20	0.06	0.002	0.01	<0.1	<0.01	<0.1	<0.05	0.1	<0.5	<1	<0.2
1202135	Rock	0.008	<1	1	0.01	11	<0.001	<20	0.03	0.001	0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
1202136	Rock	0.035	9	2	0.20	116	0.029	<20	0.54	0.060	0.12	<0.1	<0.01	<0.1	<0.05	3.1	<0.5	3	<0.2
1202145	Rock	0.138	13	32	1.38	33	0.038	<20	1.77	0.054	0.07	<0.1	<0.01	<0.1	<0.05	2.8	<0.5	7	<0.2
1202146	Rock	0.110	12	66	0.97	60	0.096	<20	1.49	0.118	0.09	0.2	<0.01	<0.1	<0.05	5.4	0.6	8	<0.2
1202147	Rock	0.204	17	79	1.24	39	0.259	<20	0.96	0.090	0.11	0.1	<0.01	<0.1	<0.05	2.9	<0.5	4	<0.2
1202148	Rock	0.044	16	12	0.40	68	0.076	<20	1.41	0.061	0.04	0.1	<0.01	<0.1	<0.05	1.6	0.7	5	<0.2
1202149	Rock	0.061	6	9	0.03	38	0.003	<20	0.17	0.014	0.04	<0.1	<0.01	<0.1	<0.05	1.8	0.8	<1	<0.2
1202150	Rock	0.088	16	16	0.08	94	0.003	<20	0.35	0.028	0.13	<0.1	0.02	<0.1	<0.05	3.3	2.6	2	0.2
1202093	Rock	0.004	1	1	0.06	17	<0.001	<20	0.07	0.005	<0.01	<0.1	<0.01	<0.1	<0.05	0.3	<0.5	<1	<0.2
1202094	Rock	0.013	6	9	0.01	344	<0.001	<20	0.11	0.026	0.06	<0.1	<0.01	<0.1	0.10	0.8	1.9	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000461.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1202095	Rock	1.02	<2	0.5	5.6	1.8	78	<0.1	3.0	12.1	538	2.62	<0.5	<0.5	2.1	28	<0.1	<0.1	<0.1	24	0.90
1202096	Rock	0.37	<2	<0.1	0.5	3.2	2	<0.1	<0.1	0.7	133	0.13	4.4	<0.5	<0.1	154	<0.1	<0.1	<0.1	<2	32.42
1203702	Rock	0.66	<2	0.2	2.0	1.6	38	<0.1	2.3	6.7	347	1.30	4.0	<0.5	2.8	21	<0.1	<0.1	<0.1	9	1.03
1203703	Rock	0.29	<2	0.1	3.8	2.6	5	<0.1	5.3	2.1	738	0.56	<0.5	<0.5	<0.1	3	0.2	<0.1	<0.1	<2	0.36
1203704	Rock	0.51	12	6.8	472.5	10.4	1325	4.1	1.2	13.1	488	7.31	40.3	21.8	2.3	9	9.1	<0.1	4.9	11	0.69
1203705	Rock	0.27	<2	2.2	6.6	1.1	4	0.1	1.5	0.3	60	0.46	<0.5	0.7	0.4	7	<0.1	<0.1	0.2	15	0.04
1203707	Rock	0.31	<2	0.4	13.1	1.2	13	<0.1	26.0	4.5	119	0.64	<0.5	1.7	<0.1	1	<0.1	<0.1	<0.1	3	0.08
1203708	Rock	0.70	<2	8.9	9.5	3.0	5	<0.1	4.9	10.9	443	1.19	0.5	<0.5	0.1	35	<0.1	<0.1	<0.1	<2	8.30
1203709	Rock	0.30	<2	0.2	16.3	2.3	39	<0.1	17.4	7.5	172	1.97	<0.5	<0.5	2.5	23	<0.1	<0.1	<0.1	18	0.48
1203710	Rock	1.71	<2	0.4	40.4	15.2	39	<0.1	136.5	22.4	303	2.66	1.2	0.9	2.0	195	<0.1	<0.1	0.1	74	2.38
1203711	Rock	0.21	<2	1.5	224.9	15.4	64	<0.1	6.7	23.1	1796	4.39	1.1	0.7	2.3	24	0.2	<0.1	<0.1	37	0.25
1203713	Rock	0.87	8	<0.1	38.1	12.1	90	<0.1	56.1	31.0	891	4.64	<0.5	43.0	6.9	144	<0.1	<0.1	0.1	43	3.07
1203714	Rock	0.70	<2	0.1	3.2	8.2	50	<0.1	3.7	19.8	703	3.47	0.6	1.1	10.0	115	<0.1	<0.1	<0.1	32	1.66
1203715	Rock	0.50	3	0.1	7.0	7.4	141	<0.1	9.0	32.6	2370	8.33	0.7	2.8	5.5	60	0.4	<0.1	<0.1	102	1.12
1203716	Rock	0.99	<2	0.2	4.9	2.7	15	<0.1	1.2	1.4	277	0.82	0.5	<0.5	2.0	6	<0.1	<0.1	<0.1	<2	0.49
1203717	Rock	0.70	<2	0.3	9.3	3.2	11	<0.1	1.4	0.8	748	0.59	0.7	<0.5	0.7	2	0.3	<0.1	<0.1	<2	0.04
1203718	Rock	1.29	<2	0.2	4.4	1.6	7	<0.1	1.0	0.5	290	0.46	1.7	<0.5	6.6	3	<0.1	0.2	<0.1	<2	0.02
1203719	Rock	0.65	<2	0.1	1.6	11.8	15	<0.1	51.8	7.6	631	0.51	1.5	0.5	1.6	224	<0.1	<0.1	<0.1	19	2.80
1202683	Rock	0.61	<2	0.5	24.1	8.5	2	<0.1	1.2	0.8	212	0.55	1.4	<0.5	15.6	60	<0.1	<0.1	0.2	<2	0.97
1202684	Rock	2.01	<2	0.7	1.3	8.2	3	<0.1	0.9	0.2	25	1.02	1.4	2.1	12.5	16	<0.1	<0.1	0.3	<2	0.02
1202685	Rock	1.90	<2	0.6	4.5	7.2	5	<0.1	0.5	0.2	24	0.80	2.2	<0.5	13.3	7	<0.1	<0.1	0.2	<2	0.01
1202687	Rock	0.64	<2	1.0	6.7	5.2	4	<0.1	0.6	1.6	31	0.83	2.5	0.6	28.3	2	<0.1	0.7	0.4	<2	<0.01
1202688	Rock	0.94	<2	1.5	4.3	7.9	8	<0.1	0.7	0.3	39	1.04	1.5	1.2	16.6	2	<0.1	<0.1	0.2	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000461.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1202095	Rock	0.049	6	4	0.90	86	0.040	<20	1.34	0.051	0.08	<0.1	<0.01	<0.1	0.36	3.3	<0.5	5	<0.2
1202096	Rock	0.003	<1	<1	1.34	4	<0.001	<20	0.01	0.004	<0.01	<0.1	<0.01	<0.1	<0.05	0.1	<0.5	<1	<0.2
1203702	Rock	0.039	6	1	0.31	69	0.004	<20	0.80	0.050	0.13	<0.1	<0.01	<0.1	0.17	2.8	<0.5	3	<0.2
1203703	Rock	0.003	<1	1	0.03	23	<0.001	<20	0.04	0.003	0.01	<0.1	<0.01	<0.1	<0.05	0.2	<0.5	<1	<0.2
1203704	Rock	0.030	4	1	0.28	120	0.005	<20	1.07	0.017	0.13	<0.1	0.15	<0.1	2.42	2.5	23.9	4	2.3
1203705	Rock	0.047	3	7	<0.01	64	<0.001	<20	0.12	0.035	0.03	<0.1	0.01	<0.1	<0.05	0.3	<0.5	<1	<0.2
1203707	Rock	0.004	<1	2	0.06	15	0.004	<20	0.12	0.006	0.03	<0.1	<0.01	<0.1	<0.05	0.2	<0.5	<1	<0.2
1203708	Rock	0.146	<1	<1	0.30	7	0.001	<20	0.04	0.005	<0.01	<0.1	<0.01	<0.1	<0.05	0.2	<0.5	<1	<0.2
1203709	Rock	0.004	4	23	0.64	99	0.154	<20	1.09	0.029	0.64	<0.1	<0.01	0.2	<0.05	0.9	<0.5	3	<0.2
1203710	Rock	0.025	6	90	2.23	129	0.179	<20	4.20	0.516	0.24	0.2	<0.01	0.3	<0.05	3.6	<0.5	9	<0.2
1203711	Rock	0.142	12	4	0.31	198	0.020	<20	0.83	0.016	0.21	<0.1	<0.01	<0.1	<0.05	3.8	<0.5	2	<0.2
1203713	Rock	0.081	18	37	1.84	342	0.018	<20	2.40	0.017	0.22	<0.1	<0.01	<0.1	0.23	3.7	<0.5	7	<0.2
1203714	Rock	0.305	29	<1	1.07	151	0.028	<20	1.67	0.025	0.36	<0.1	<0.01	<0.1	0.06	2.1	<0.5	4	<0.2
1203715	Rock	0.248	35	2	1.52	234	0.027	<20	2.27	0.025	0.07	<0.1	0.01	<0.1	<0.05	9.1	<0.5	8	<0.2
1203716	Rock	0.011	3	2	0.02	29	0.001	<20	0.10	0.014	0.06	0.5	<0.01	<0.1	<0.05	0.4	<0.5	<1	<0.2
1203717	Rock	0.002	3	2	0.01	31	<0.001	<20	0.03	0.003	<0.01	<0.1	<0.01	<0.1	<0.05	0.2	<0.5	<1	<0.2
1203718	Rock	0.002	23	2	0.02	14	0.001	<20	0.10	0.050	0.03	0.3	<0.01	<0.1	<0.05	0.3	<0.5	<1	<0.2
1203719	Rock	0.306	5	29	0.29	53	0.100	<20	0.85	0.014	0.01	0.5	0.01	<0.1	<0.05	1.5	<0.5	3	<0.2
1202683	Rock	0.002	14	<1	0.16	27	0.001	<20	0.27	0.028	0.21	<0.1	<0.01	<0.1	0.32	0.3	<0.5	<1	<0.2
1202684	Rock	0.005	43	1	0.03	130	0.003	<20	0.33	0.040	0.36	<0.1	<0.01	<0.1	0.37	0.4	<0.5	<1	<0.2
1202685	Rock	0.002	17	<1	0.02	88	0.002	<20	0.26	0.017	0.29	0.3	0.01	<0.1	0.18	0.3	<0.5	<1	<0.2
1202687	Rock	0.001	11	<1	0.01	122	0.004	<20	0.22	0.016	0.21	1.1	<0.01	<0.1	0.18	0.1	0.6	<1	<0.2
1202688	Rock	0.005	35	1	0.02	25	0.002	<20	0.22	0.032	0.19	0.1	<0.01	<0.1	<0.05	0.3	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:

Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000461.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1202036	Rock	0.48	<2	1.0	10.0	3.7	7	<0.1	0.8	0.2	32	0.86	3.1	3.1	22.6	1	<0.1	5.5	0.2	<2	<0.01
REP 1202036	QC		<2																		
1202115	Rock	0.34	<2	1.2	1.4	8.5	8	<0.1	0.5	0.7	171	0.85	0.8	<0.5	9.5	11	<0.1	<0.1	<0.1	3	0.25
REP 1202115	QC			0.9	1.2	7.9	8	<0.1	0.6	0.7	164	0.84	0.7	<0.5	9.2	11	<0.1	<0.1	<0.1	3	0.26
1202122	Rock	1.00	<2	0.6	3.1	2.0	41	<0.1	6.9	6.0	381	1.52	<0.5	<0.5	1.5	56	0.1	<0.1	<0.1	29	0.81
REP 1202122	QC		<2																		
1202133	Rock	0.77	<2	0.1	18.7	0.3	5	<0.1	0.6	0.4	53	0.35	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	0.16
REP 1202133	QC			<0.1	17.6	0.4	5	<0.1	0.6	0.4	57	0.35	<0.5	1.1	<0.1	1	<0.1	<0.1	<0.1	<2	0.15
Core Reject Duplicates																					
1202066	Rock	1.03	<2	<0.1	27.0	0.8	46	<0.1	34.9	25.7	518	3.12	0.9	0.8	0.2	51	<0.1	<0.1	<0.1	66	0.85
DUP 1202066	QC		<2	<0.1	27.4	0.8	46	<0.1	35.6	26.3	535	3.16	1.3	1.9	0.3	51	<0.1	<0.1	<0.1	66	0.87
1202095	Rock	1.02	<2	0.5	5.6	1.8	78	<0.1	3.0	12.1	538	2.62	<0.5	<0.5	2.1	28	<0.1	<0.1	<0.1	24	0.90
DUP 1202095	QC		<2	0.3	5.2	1.6	73	<0.1	2.9	11.2	506	2.53	0.5	<0.5	1.9	24	<0.1	<0.1	<0.1	23	0.83
Reference Materials																					
STD DS8	Standard			13.4	112.0	116.6	310	1.6	38.2	7.8	636	2.50	25.5	115.6	6.7	68	2.0	3.8	5.6	42	0.75
STD DS8	Standard			13.6	109.5	117.2	310	1.9	39.9	7.8	601	2.46	26.1	99.4	6.3	65	2.3	3.8	6.2	42	0.73
STD DS8	Standard			12.9	104.5	104.4	305	1.7	36.6	7.3	573	2.37	24.0	102.5	7.0	76	1.9	5.0	7.5	39	0.66
STD OREAS45CA	Standard			0.7	524.8	20.6	62	0.3	271.1	89.8	942	16.67	3.5	40.1	6.8	16	<0.1	<0.1	0.2	216	0.43
STD OREAS45CA	Standard			0.9	540.9	20.9	67	0.3	267.8	94.2	888	16.29	3.7	41.8	7.1	16	0.1	<0.1	0.2	211	0.45
STD OREAS45CA	Standard			0.8	508.5	16.7	59	0.3	246.4	88.7	927	15.27	3.3	34.3	7.6	16	0.1	0.1	0.2	220	0.41
STD OXC88	Standard		194																		
STD OXC88	Standard		190																		
STD OXC88	Standard		201																		
STD OXC88	Standard		183																		
STD OXC88	Standard		203																		
STD OXH82	Standard		1258																		
STD OXH82	Standard		1289																		
STD OXH82	Standard		1355																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:

Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000461.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1202036	Rock	0.001	12	1	0.01	21	0.002	<20	0.20	0.006	0.21	0.6	0.02	<0.1	0.07	0.1	<0.5	<1	<0.2
REP 1202036	QC																		
1202115	Rock	0.004	23	1	0.02	322	0.008	<20	0.30	0.066	0.22	<0.1	<0.01	<0.1	<0.05	2.0	<0.5	1	<0.2
REP 1202115	QC	0.005	22	1	0.03	304	0.008	<20	0.29	0.065	0.22	<0.1	<0.01	<0.1	<0.05	2.1	<0.5	1	<0.2
1202122	Rock	0.053	5	12	0.46	53	0.091	<20	0.80	0.055	0.02	<0.1	<0.01	<0.1	<0.05	3.2	<0.5	5	<0.2
REP 1202122	QC																		
1202133	Rock	0.004	<1	<1	0.07	17	<0.001	<20	0.07	0.006	0.02	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
REP 1202133	QC	0.004	<1	1	0.07	17	<0.001	<20	0.07	0.005	0.02	<0.1	<0.01	<0.1	<0.05	0.1	<0.5	<1	<0.2
Core Reject Duplicates																			
1202066	Rock	0.044	<1	44	2.60	40	0.231	<20	2.62	0.019	0.06	<0.1	<0.01	<0.1	<0.05	3.0	<0.5	4	<0.2
DUP 1202066	QC	0.044	<1	46	2.60	41	0.242	<20	2.63	0.017	0.07	<0.1	<0.01	<0.1	<0.05	3.2	<0.5	4	<0.2
1202095	Rock	0.049	6	4	0.90	86	0.040	<20	1.34	0.051	0.08	<0.1	<0.01	<0.1	0.36	3.3	<0.5	5	<0.2
DUP 1202095	QC	0.048	5	4	0.90	80	0.037	<20	1.31	0.048	0.07	<0.1	<0.01	<0.1	0.33	3.0	<0.5	5	<0.2
Reference Materials																			
STD DS8	Standard	0.078	16	120	0.62	294	0.121	<20	0.94	0.092	0.41	2.5	0.20	5.3	0.17	2.2	4.6	5	5.6
STD DS8	Standard	0.084	15	110	0.61	284	0.115	<20	0.92	0.091	0.41	2.8	0.19	5.2	0.16	2.1	4.8	5	4.5
STD DS8	Standard	0.076	14	108	0.59	292	0.124	<20	0.84	0.077	0.39	2.5	0.19	5.1	0.16	1.7	5.7	5	4.4
STD OREAS45CA	Standard	0.042	15	751	0.15	166	0.141	<20	3.91	0.010	0.08	<0.1	0.05	<0.1	<0.05	37.3	<0.5	20	<0.2
STD OREAS45CA	Standard	0.038	16	698	0.15	171	0.154	<20	4.13	0.007	0.08	<0.1	0.03	<0.1	<0.05	36.9	<0.5	21	<0.2
STD OREAS45CA	Standard	0.037	16	609	0.15	157	0.168	<20	3.74	0.006	0.07	<0.1	0.04	<0.1	<0.05	33.8	<0.5	18	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:

Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000461.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
STD OXH82	Standard		1239																		
STD OXH82	Standard		1268																		
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		3	0.2	1.8	22.7	47	<0.1	4.0	4.1	530	1.99	0.8	4.4	5.6	86	0.2	<0.1	0.1	36	0.49
G1	Prep Blank		<2	0.2	1.5	11.6	46	<0.1	3.3	4.0	545	1.97	0.9	4.9	6.0	81	<0.1	<0.1	0.1	36	0.48

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:

Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000461.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXC88 Expected																			
STD OXH82 Expected																			
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																			
G1	Prep Blank	0.069	11	7	0.57	221	0.154	<20	0.98	0.093	0.48	<0.1	<0.01	0.3	<0.05	1.9	<0.5	5	<0.2
G1	Prep Blank	0.067	10	7	0.55	219	0.153	<20	0.98	0.092	0.46	<0.1	<0.01	0.2	<0.05	1.8	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Submitted By: Bruce Durham
Receiving Lab: Canada-Whitehorse
Received: July 05, 2011
Report Date: August 09, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11000468.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID: VIP-3
P.O. Number
Number of Samples: 59

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	59	Crush, split and pulverize 250 g rock to 200 mesh			WHI
1DX2	59	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Daithi Mac Gearailt
Don Christie
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000468.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1202001	Rock	0.57	0.2	1.1	2.1	18	<0.1	0.9	3.7	140	1.95	5.3	1.0	4.5	7	<0.1	<0.1	0.7	3	0.13	0.017
1202005	Rock	1.29	3.1	2.2	2.9	3	<0.1	0.5	2.8	42	1.16	0.7	2.5	22.7	11	<0.1	<0.1	0.4	3	0.10	0.005
1202017	Rock	0.97	3.4	15.7	8.1	28	<0.1	1.5	1.6	80	1.09	1.1	<0.5	6.3	<1	<0.1	<0.1	0.4	3	<0.01	0.004
1202024	Rock	0.77	2.9	1.0	41.1	2	0.2	0.4	1.1	19	0.94	0.6	2.4	14.4	6	<0.1	<0.1	0.9	<2	<0.01	0.004
1202025	Rock	0.66	2.6	2.0	18.9	3	<0.1	0.4	1.2	26	2.21	4.3	2.1	6.4	7	<0.1	<0.1	0.3	<2	<0.01	0.001
1202026	Rock	0.38	1.8	4.3	39.2	6	0.1	0.5	<0.1	18	0.23	<0.5	1.6	16.1	2	<0.1	<0.1	0.3	<2	<0.01	0.004
1202027	Rock	0.57	6.2	8.7	150.5	15	0.1	0.3	0.4	32	0.70	0.8	1.2	11.0	1	<0.1	<0.1	1.8	2	<0.01	0.005
1202028	Rock	0.65	2.7	18.3	30.9	73	<0.1	5.5	5.0	1523	0.58	0.8	<0.5	24.4	17	0.7	<0.1	0.4	<2	0.03	0.004
1202029	Rock	0.81	2.2	2.3	6.4	5	<0.1	0.4	0.1	39	0.85	1.9	<0.5	19.0	6	<0.1	0.1	0.2	<2	<0.01	0.003
1202030	Rock	0.57	0.9	2.7	15.7	52	<0.1	0.7	1.2	76	1.14	0.9	0.9	24.8	5	0.2	<0.1	0.2	<2	0.03	0.004
1202031	Rock	0.42	0.4	2.8	3.3	18	<0.1	0.8	0.7	335	0.92	0.8	<0.5	21.5	7	<0.1	<0.1	<0.1	<2	0.01	0.003
1202032	Rock	0.46	0.8	1.8	13.7	26	<0.1	0.4	0.4	32	0.68	0.7	<0.5	21.0	5	0.1	<0.1	0.2	<2	0.02	0.004
1202033	Rock	1.24	1.1	5.5	7.8	1	<0.1	0.4	<0.1	18	0.44	<0.5	<0.5	11.5	4	<0.1	<0.1	0.1	<2	<0.01	0.002
1202651	Rock	0.76	0.3	2.1	1.2	11	<0.1	1.2	1.0	229	0.53	<0.5	1.1	19.2	1	<0.1	<0.1	<0.1	2	0.02	0.002
1202652	Rock	1.08	0.3	70.1	6.3	82	<0.1	18.8	22.3	592	5.58	2.6	<0.5	2.0	95	0.2	0.3	<0.1	161	0.47	0.033
1202653	Rock	0.86	<0.1	10.3	1.5	5	<0.1	0.5	0.4	29	0.57	0.7	0.7	0.2	2	<0.1	<0.1	<0.1	<2	<0.01	0.004
1202654	Rock	0.97	0.2	11.8	7.4	11	<0.1	1.0	1.1	31	0.84	1.0	<0.5	0.2	10	<0.1	0.2	<0.1	3	0.01	0.006
1202655	Rock	0.64	0.2	24.2	10.7	88	0.5	4.3	0.8	239	6.41	5.0	29.3	0.5	2	<0.1	0.2	5.6	61	0.02	0.004
1202656	Rock	0.27	0.3	193.7	25.4	110	0.2	4.4	3.8	236	5.52	2.8	3.4	0.3	12	<0.1	0.2	0.9	31	0.02	0.023
1202657	Rock	0.66	0.2	24.1	6.6	16	<0.1	2.0	1.0	42	0.96	0.9	<0.5	<0.1	<1	<0.1	<0.1	0.4	2	<0.01	0.004
1202658	Rock	0.93	0.1	54.6	4.5	18	<0.1	4.2	1.8	82	0.66	<0.5	0.9	<0.1	6	<0.1	0.1	<0.1	2	<0.01	0.002
1202659	Rock	0.88	<0.1	47.8	5.6	17	<0.1	3.2	1.6	61	0.65	<0.5	0.8	<0.1	2	<0.1	<0.1	<0.1	3	0.01	0.004
1202660	Rock	0.46	<0.1	19.5	8.9	114	<0.1	5.4	4.9	388	1.81	1.0	<0.5	0.2	5	0.4	<0.1	0.2	11	0.11	0.026
1202661	Rock	0.88	0.2	3.7	3.2	23	<0.1	1.3	2.9	1278	0.71	0.5	<0.5	0.6	3	0.3	0.1	<0.1	3	0.02	0.010
1202662	Rock	0.77	0.7	148.0	7.2	60	0.8	6.2	1.8	121	3.93	2.0	23.3	0.2	11	<0.1	0.4	6.4	23	<0.01	0.016
1202159	Rock	1.26	1.7	14.0	4.7	24	<0.1	1.5	1.7	231	1.24	1.0	<0.5	8.9	15	<0.1	0.1	0.3	18	0.17	0.045
1202166	Rock	0.56	0.2	30.8	3.4	49	<0.1	1.6	14.8	353	4.29	0.8	<0.5	1.4	308	0.2	<0.1	<0.1	176	2.67	0.253
1202190	Rock	0.81	0.2	7.2	1.4	80	<0.1	26.6	1.9	65	0.36	3.6	<0.5	1.8	16	0.2	<0.1	0.1	34	0.44	0.061
1202191	Rock	0.64	1.0	21.2	2.5	13	0.2	4.2	1.2	51	0.63	5.0	0.5	2.3	3	0.1	0.2	<0.1	9	0.02	0.016
1202192	Rock	1.08	1.5	7.1	165.7	4	0.2	2.2	<0.1	20	0.40	8.3	3.8	21.6	9	<0.1	<0.1	0.5	2	0.01	0.014

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000468.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202001	Rock	6	<1	0.73	24	0.080	<1	0.72	0.044	0.08	0.2	<0.01	1.3	<0.1	0.94	3	0.6	0.6
1202005	Rock	9	<1	0.03	47	0.015	<1	0.20	0.052	0.09	0.2	<0.01	0.3	<0.1	0.98	<1	<0.5	<0.2
1202017	Rock	7	<1	0.03	25	0.001	<1	0.19	0.010	0.15	<0.1	<0.01	0.6	0.1	<0.05	<1	0.8	<0.2
1202024	Rock	14	<1	0.02	224	0.002	<1	0.19	0.048	0.15	0.2	<0.01	0.2	<0.1	0.54	<1	<0.5	<0.2
1202025	Rock	14	<1	0.01	99	0.002	2	0.16	0.019	0.38	<0.1	<0.01	0.1	<0.1	1.23	<1	<0.5	<0.2
1202026	Rock	36	<1	0.02	27	0.001	<1	0.20	0.030	0.15	0.1	<0.01	0.2	<0.1	<0.05	<1	0.6	<0.2
1202027	Rock	21	2	<0.01	24	0.001	<1	0.14	0.073	0.07	0.2	<0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2
1202028	Rock	30	<1	0.02	887	0.001	1	0.23	0.046	0.15	<0.1	<0.01	0.1	<0.1	0.11	<1	<0.5	<0.2
1202029	Rock	26	<1	0.01	130	0.003	<1	0.21	0.035	0.25	0.2	<0.01	0.3	<0.1	0.22	<1	<0.5	<0.2
1202030	Rock	36	<1	0.10	27	<0.001	<1	0.30	0.006	0.16	<0.1	<0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2
1202031	Rock	29	<1	0.11	56	0.001	<1	0.12	0.015	0.13	<0.1	<0.01	0.2	<0.1	<0.05	<1	<0.5	<0.2
1202032	Rock	34	<1	0.06	29	<0.001	<1	0.26	0.019	0.17	<0.1	<0.01	0.4	<0.1	<0.05	<1	<0.5	<0.2
1202033	Rock	18	<1	0.02	47	<0.001	<1	0.21	0.009	0.21	<0.1	<0.01	<0.1	<0.1	0.22	<1	<0.5	<0.2
1202651	Rock	5	<1	0.23	18	0.007	<1	0.29	0.081	0.09	0.1	<0.01	0.5	0.1	<0.05	2	<0.5	<0.2
1202652	Rock	4	24	2.15	166	0.269	1	4.89	0.019	0.09	<0.1	<0.01	9.9	<0.1	0.05	9	0.6	<0.2
1202653	Rock	<1	<1	0.02	49	<0.001	<1	0.07	0.004	0.02	<0.1	0.02	0.4	<0.1	<0.05	<1	<0.5	<0.2
1202654	Rock	<1	1	0.02	293	0.004	<1	0.11	0.007	<0.01	<0.1	0.01	1.2	<0.1	<0.05	<1	<0.5	<0.2
1202655	Rock	2	18	1.38	65	0.002	<1	1.62	0.008	0.09	<0.1	0.13	2.3	<0.1	<0.05	6	6.5	2.9
1202656	Rock	1	6	0.96	778	0.001	<1	1.34	0.013	0.12	<0.1	0.04	1.7	<0.1	<0.05	3	0.6	0.2
1202657	Rock	<1	1	<0.01	7	<0.001	<1	0.10	0.002	<0.01	<0.1	0.02	0.6	<0.1	<0.05	<1	<0.5	1.4
1202658	Rock	<1	1	0.01	179	<0.001	<1	0.23	0.001	<0.01	<0.1	0.03	1.3	<0.1	<0.05	<1	<0.5	<0.2
1202659	Rock	<1	1	<0.01	67	<0.001	<1	0.22	0.007	<0.01	<0.1	0.04	1.0	<0.1	<0.05	<1	<0.5	<0.2
1202660	Rock	1	2	0.24	131	0.001	<1	0.42	0.013	0.02	<0.1	0.01	2.0	<0.1	<0.05	<1	<0.5	<0.2
1202661	Rock	2	<1	0.04	63	<0.001	<1	0.13	0.009	0.04	<0.1	0.02	0.9	<0.1	<0.05	<1	<0.5	<0.2
1202662	Rock	<1	10	0.88	430	<0.001	<1	1.08	0.012	0.06	<0.1	0.17	1.9	<0.1	<0.05	2	0.5	2.1
1202159	Rock	19	2	0.22	207	0.072	<1	0.49	0.075	0.28	0.3	<0.01	1.7	<0.1	0.09	2	<0.5	<0.2
1202166	Rock	16	<1	1.13	724	0.205	<1	4.01	0.525	0.53	<0.1	<0.01	6.5	0.1	0.11	10	<0.5	<0.2
1202190	Rock	8	21	0.03	6	0.045	1	0.36	0.002	<0.01	<0.1	<0.01	1.7	<0.1	<0.05	1	0.7	<0.2
1202191	Rock	7	4	0.01	98	0.002	<1	0.19	0.005	0.08	<0.1	<0.01	0.7	<0.1	<0.05	<1	1.7	<0.2
1202192	Rock	34	<1	0.01	1149	<0.001	<1	0.37	0.026	0.14	<0.1	0.08	0.8	0.1	<0.05	<1	0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000468.1

Method		WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
Unit		kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
MDL		0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
1202174	Rock	0.79	1.3	134.7	5.6	35	0.4	6.2	0.4	68	2.39	54.0	6.2	8.5	23	<0.1	0.3	2.8	8	0.03	0.020
1202175	Rock	1.84	0.3	242.3	3.3	25	0.8	5.1	10.6	211	29.66	2.8	50.9	0.5	1	<0.1	<0.1	0.8	38	0.02	0.011
1202186	Rock	1.27	0.1	3.2	3.8	9	<0.1	1.5	1.5	105	0.83	1.2	2.2	1.7	44	<0.1	<0.1	0.1	7	0.45	0.020
1202187	Rock	0.81	0.1	1.0	0.9	21	<0.1	0.9	2.8	128	1.22	1.1	2.6	2.9	11	<0.1	<0.1	<0.1	7	0.27	0.024
1202080	Rock	0.68	0.7	9.0	5.0	9	0.4	10.3	7.2	208	2.59	4.9	4.7	3.0	124	<0.1	0.3	0.1	26	1.15	0.026
1202081	Rock	1.06	0.2	31.4	2.0	42	<0.1	20.3	17.2	1628	5.05	1.9	2.0	6.3	47	<0.1	<0.1	0.2	31	7.88	0.118
1202082	Rock	0.87	0.2	2.1	22.2	9	<0.1	0.6	0.3	70	0.66	2.0	22.2	16.8	2	<0.1	<0.1	1.9	<2	0.11	0.003
1202083	Rock	0.72	4.3	30.7	1.9	60	0.2	20.0	1.1	51	0.78	0.7	1.9	2.4	9	<0.1	<0.1	0.2	65	0.42	0.198
1202084	Rock	1.80	0.6	12.1	4.9	239	1.6	64.3	1.8	130	0.92	16.1	<0.5	2.0	6	0.9	0.1	0.4	22	0.60	0.067
1202086	Rock	0.59	0.1	38.2	19.2	57	<0.1	1.8	1.2	143	0.73	2.1	1.2	30.9	4	0.1	<0.1	0.3	2	0.05	0.005
1202663	Rock	0.65	0.9	155.4	8.6	95	0.3	7.0	5.4	229	17.68	3.8	11.7	0.2	4	0.2	0.1	3.1	63	0.03	0.062
1202664	Rock	0.58	<0.1	18.4	1.6	7	<0.1	0.9	0.5	39	1.38	0.5	<0.5	0.2	<1	<0.1	<0.1	0.2	5	<0.01	0.006
1202665	Rock	0.62	0.4	50.3	2.6	13	<0.1	1.3	0.9	53	3.26	1.1	2.9	0.3	<1	<0.1	0.2	1.6	13	<0.01	0.020
1202666	Rock	0.80	0.1	11.8	1.6	13	<0.1	1.3	0.3	52	0.64	1.6	<0.5	<0.1	<1	<0.1	<0.1	0.3	3	<0.01	0.003
1202667	Rock	0.45	0.1	130.7	11.0	54	<0.1	1.9	1.8	85	7.66	1.7	3.4	0.4	2	<0.1	0.1	0.6	30	0.01	0.044
1202668	Rock	0.97	<0.1	13.2	1.9	19	<0.1	4.1	5.2	1476	0.87	1.3	<0.5	<0.1	2	0.4	0.1	<0.1	<2	<0.01	0.001
1202669	Rock	0.58	0.6	17.1	2.4	35	0.1	1.6	3.9	547	1.44	4.1	<0.5	3.0	11	0.4	<0.1	0.2	5	0.38	0.022
1202670	Rock	0.70	2.6	1.6	8.3	9	<0.1	0.6	0.6	71	0.65	0.7	<0.5	7.0	2	<0.1	<0.1	<0.1	<2	0.02	0.001
1202671	Rock	0.45	0.1	18.2	2.8	20	0.1	1.2	2.1	136	0.99	1.1	3.8	3.3	16	<0.1	<0.1	0.1	4	0.23	0.018
1202672	Rock	0.59	0.1	68.1	1.9	25	<0.1	3.6	4.5	195	3.30	1.6	1.7	0.2	<1	<0.1	<0.1	0.4	10	<0.01	0.020
1202673	Rock	0.47	0.4	12.0	5.7	130	0.1	4.9	13.5	1106	3.97	3.9	<0.5	3.1	34	0.4	<0.1	0.6	56	2.47	0.062
1202674	Rock	0.29	0.2	2.1	4.4	14	<0.1	0.8	0.8	61	0.76	2.0	<0.5	6.5	5	<0.1	<0.1	<0.1	<2	0.05	0.005
1202675	Rock	0.46	0.7	59.9	1.6	12	0.2	8.2	8.0	130	0.97	3.1	<0.5	0.8	4	<0.1	<0.1	<0.1	6	0.07	0.022
1202676	Rock	0.37	1.2	2.5	19.4	8	0.1	0.8	0.5	48	0.57	1.9	<0.5	9.4	4	<0.1	<0.1	0.2	<2	0.04	0.002
1202677	Rock	0.66	0.5	215.8	7.7	7	0.2	2.7	2.5	404	0.42	4.5	<0.5	6.4	15	0.2	<0.1	0.2	2	0.24	0.091
1202678	Rock	0.65	1.0	7.3	6.1	9	0.2	2.1	1.9	189	0.73	3.7	<0.5	2.8	33	<0.1	<0.1	<0.1	6	0.01	0.017
1202679	Rock	0.39	0.5	5.2	6.6	6	0.3	1.6	0.8	42	1.01	16.6	4.0	12.2	7	<0.1	0.2	0.2	<2	<0.01	0.007
1202680	Rock	0.33	0.1	25.3	0.8	14	<0.1	10.1	3.1	616	0.89	4.3	<0.5	0.7	21	<0.1	<0.1	<0.1	4	0.63	0.013
1202681	Rock	0.65	1.3	9.6	17.0	65	<0.1	0.3	0.3	122	2.13	1.2	<0.5	24.9	<1	<0.1	<0.1	0.2	<2	0.01	0.001

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000468.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202174	Rock	18	15	0.39	230	0.002	<1	0.88	0.019	0.15	<0.1	0.02	1.7	<0.1	0.10	4	4.2	<0.2
1202175	Rock	3	<1	0.07	16	0.004	<1	0.45	<0.001	<0.01	<0.1	<0.01	1.0	<0.1	<0.05	12	1.0	0.3
1202186	Rock	4	1	0.09	29	0.027	<1	0.57	0.091	0.02	<0.1	<0.01	1.0	<0.1	<0.05	3	0.7	<0.2
1202187	Rock	6	1	0.26	85	0.036	1	0.74	0.044	0.11	<0.1	<0.01	1.3	<0.1	<0.05	3	<0.5	<0.2
1202080	Rock	5	15	0.94	15	0.071	1	1.71	0.018	0.02	<0.1	<0.01	1.7	<0.1	<0.05	7	2.0	0.3
1202081	Rock	12	31	2.64	25	0.010	1	2.50	<0.001	0.05	<0.1	<0.01	3.6	<0.1	0.97	6	<0.5	<0.2
1202082	Rock	2	1	0.02	9	0.002	1	0.25	0.034	0.16	0.2	<0.01	0.8	<0.1	<0.05	2	<0.5	<0.2
1202083	Rock	5	13	0.14	345	0.032	<1	0.39	0.006	0.13	<0.1	<0.01	2.0	<0.1	<0.05	2	1.8	<0.2
1202084	Rock	8	20	0.07	55	0.032	1	0.25	<0.001	<0.01	0.2	<0.01	2.3	<0.1	<0.05	1	<0.5	<0.2
1202086	Rock	10	2	0.06	32	0.009	<1	0.33	0.081	0.10	<0.1	<0.01	0.8	<0.1	<0.05	3	<0.5	<0.2
1202663	Rock	<1	14	0.53	117	0.001	<1	1.17	0.011	0.11	<0.1	0.14	2.3	<0.1	<0.05	4	9.8	1.8
1202664	Rock	<1	3	0.05	59	<0.001	<1	0.12	0.004	0.03	<0.1	<0.01	0.4	<0.1	<0.05	<1	0.8	<0.2
1202665	Rock	<1	4	0.08	26	<0.001	<1	0.23	0.006	0.05	0.1	0.04	0.8	<0.1	<0.05	1	2.1	0.6
1202666	Rock	<1	1	0.17	10	<0.001	<1	0.21	0.004	0.02	<0.1	<0.01	0.4	<0.1	<0.05	<1	<0.5	<0.2
1202667	Rock	1	11	0.28	83	0.001	<1	0.63	0.008	0.08	<0.1	0.04	1.7	<0.1	<0.05	3	2.0	0.3
1202668	Rock	<1	1	<0.01	81	<0.001	<1	0.21	0.002	<0.01	<0.1	0.01	4.1	<0.1	<0.05	<1	<0.5	<0.2
1202669	Rock	8	1	0.23	196	0.005	<1	0.63	0.046	0.11	<0.1	<0.01	2.2	<0.1	0.40	2	0.7	<0.2
1202670	Rock	6	1	<0.01	109	0.005	<1	0.13	0.055	0.10	<0.1	<0.01	2.5	<0.1	<0.05	<1	<0.5	<0.2
1202671	Rock	7	1	0.13	193	0.026	<1	0.48	0.035	0.16	<0.1	<0.01	2.0	<0.1	<0.05	2	<0.5	<0.2
1202672	Rock	<1	4	0.16	36	<0.001	<1	0.44	0.004	0.04	<0.1	<0.01	1.6	<0.1	<0.05	1	0.5	0.2
1202673	Rock	10	4	1.16	109	0.005	2	2.09	0.039	0.09	<0.1	<0.01	8.7	<0.1	0.25	7	<0.5	<0.2
1202674	Rock	14	2	0.03	73	0.003	<1	0.22	0.061	0.10	<0.1	<0.01	1.9	<0.1	<0.05	1	<0.5	<0.2
1202675	Rock	1	4	0.14	156	0.006	<1	0.26	0.012	0.05	<0.1	<0.01	1.0	<0.1	0.21	1	0.8	<0.2
1202676	Rock	10	1	0.02	150	0.008	1	0.15	0.065	0.11	<0.1	<0.01	0.9	<0.1	<0.05	<1	<0.5	<0.2
1202677	Rock	18	2	0.03	423	0.001	2	0.27	0.028	0.26	<0.1	0.03	0.5	<0.1	0.10	<1	<0.5	<0.2
1202678	Rock	6	4	<0.01	1022	<0.001	<1	0.13	0.106	0.02	<0.1	<0.01	2.1	<0.1	0.11	<1	1.1	<0.2
1202679	Rock	72	1	<0.01	454	<0.001	<1	0.14	0.102	0.02	<0.1	<0.01	0.8	<0.1	0.21	<1	1.5	<0.2
1202680	Rock	3	2	0.23	100	<0.001	1	0.08	0.005	0.05	<0.1	<0.01	1.2	<0.1	0.06	<1	<0.5	<0.2
1202681	Rock	29	1	0.02	22	0.010	<1	0.18	0.063	0.13	0.2	<0.01	0.4	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000468.1

	Method	WGHT	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Wgt	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P
	Unit	kg	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%
	MDL	0.01	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001
Pulp Duplicates																					
1202654	Rock	0.97	0.2	11.8	7.4	11	<0.1	1.0	1.1	31	0.84	1.0	<0.5	0.2	10	<0.1	0.2	<0.1	3	0.01	0.006
REP 1202654	QC		0.1	11.7	7.4	12	<0.1	0.9	1.1	33	0.86	1.3	<0.5	0.2	10	<0.1	0.2	<0.1	3	0.01	0.005
1202676	Rock	0.37	1.2	2.5	19.4	8	0.1	0.8	0.5	48	0.57	1.9	<0.5	9.4	4	<0.1	<0.1	0.2	<2	0.04	0.002
REP 1202676	QC		1.2	2.6	20.6	8	0.1	0.8	0.5	49	0.58	2.1	<0.5	9.9	4	<0.1	<0.1	0.3	<2	0.04	0.003
Core Reject Duplicates																					
1202657	Rock	0.66	0.2	24.1	6.6	16	<0.1	2.0	1.0	42	0.96	0.9	<0.5	<0.1	<1	<0.1	<0.1	0.4	2	<0.01	0.004
DUP 1202657	QC		0.2	23.7	6.4	17	<0.1	1.8	1.0	40	0.92	0.7	<0.5	<0.1	<1	<0.1	0.1	0.3	2	<0.01	0.004
1202677	Rock	0.66	0.5	215.8	7.7	7	0.2	2.7	2.5	404	0.42	4.5	<0.5	6.4	15	0.2	<0.1	0.2	2	0.24	0.091
DUP 1202677	QC		0.4	221.8	8.1	8	0.2	2.7	2.6	406	0.39	4.7	<0.5	6.7	15	0.1	<0.1	0.2	3	0.26	0.091
Reference Materials																					
STD DS8	Standard		13.2	111.2	128.8	305	1.8	38.2	7.8	614	2.48	27.2	126.4	6.8	63	2.4	5.0	6.1	41	0.71	0.077
STD DS8	Standard		14.0	114.9	127.7	317	1.7	38.6	7.9	624	2.52	28.5	106.2	6.8	64	2.5	5.1	6.1	41	0.73	0.082
STD DS8	Standard		12.0	106.7	118.4	294	1.7	37.1	7.3	582	2.35	24.3	105.6	6.7	60	2.1	5.6	5.6	40	0.67	0.076
STD DS8	Standard		12.6	100.5	114.0	290	1.7	35.7	6.8	576	2.29	24.7	99.4	6.4	64	2.3	5.1	5.6	39	0.66	0.073
STD DS8 Expected			13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
BLK	Blank		<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	2.0	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001
Prep Wash																					
G1	Prep Blank		<0.1	1.6	3.1	43	<0.1	3.5	3.6	474	1.65	<0.5	1.1	4.6	54	<0.1	<0.1	0.1	32	0.41	0.065
G1	Prep Blank		<0.1	2.1	2.9	44	<0.1	3.6	4.1	506	1.77	<0.5	0.9	4.8	60	<0.1	<0.1	<0.1	34	0.45	0.067

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000468.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																		
1202654	Rock	<1	1	0.02	293	0.004	<1	0.11	0.007	<0.01	<0.1	0.01	1.2	<0.1	<0.05	<1	<0.5	<0.2
REP 1202654	QC	<1	1	0.02	306	0.004	<1	0.11	0.008	<0.01	<0.1	<0.01	1.2	<0.1	<0.05	<1	<0.5	<0.2
1202676	Rock	10	1	0.02	150	0.008	1	0.15	0.065	0.11	<0.1	<0.01	0.9	<0.1	<0.05	<1	<0.5	<0.2
REP 1202676	QC	10	1	0.02	157	0.009	<1	0.15	0.065	0.12	<0.1	<0.01	1.0	<0.1	<0.05	<1	<0.5	<0.2
Core Reject Duplicates																		
1202657	Rock	<1	1	<0.01	7	<0.001	<1	0.10	0.002	<0.01	<0.1	0.02	0.6	<0.1	<0.05	<1	<0.5	1.4
DUP 1202657	QC	<1	<1	<0.01	10	<0.001	<1	0.10	0.002	<0.01	<0.1	0.02	0.5	<0.1	<0.05	<1	0.6	1.1
1202677	Rock	18	2	0.03	423	0.001	2	0.27	0.028	0.26	<0.1	0.03	0.5	<0.1	0.10	<1	<0.5	<0.2
DUP 1202677	QC	19	2	0.03	443	0.002	1	0.29	0.032	0.30	<0.1	0.02	0.6	<0.1	0.10	1	<0.5	<0.2
Reference Materials																		
STD DS8	Standard	14	117	0.61	273	0.108	3	0.91	0.084	0.41	2.9	0.18	2.2	5.3	0.16	5	5.4	5.4
STD DS8	Standard	15	117	0.62	274	0.116	3	0.93	0.089	0.42	2.9	0.20	2.3	5.3	0.16	5	6.0	5.0
STD DS8	Standard	14	114	0.57	265	0.118	3	0.88	0.084	0.39	2.7	0.20	1.8	4.9	0.17	5	4.7	4.0
STD DS8	Standard	15	110	0.56	263	0.114	2	0.89	0.086	0.38	2.9	0.19	1.8	5.1	0.15	5	4.0	4.4
STD DS8 Expected		14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
Prep Wash																		
G1	Prep Blank	9	5	0.48	188	0.114	1	0.86	0.082	0.40	<0.1	<0.01	1.5	0.3	<0.05	4	<0.5	<0.2
G1	Prep Blank	9	6	0.52	206	0.121	2	0.97	0.094	0.44	<0.1	<0.01	1.6	0.3	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Submitted By: Bruce Durham
Receiving Lab: Canada-Whitehorse
Received: July 06, 2011
Report Date: August 09, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11000485.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID: JULY-1st-2011
P.O. Number
Number of Samples: 57

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	56	Crush, split and pulverize 250 g rock to 200 mesh			WHI
3B	56	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	56	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Don Christie
Daithi Mac Gearailt
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000485.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1202097	Rock	0.56	<2	0.2	29.6	4.3	108	<0.1	11.4	25.3	674	3.17	<0.5	<0.5	7.1	21	0.1	<0.1	<0.1	37	0.48
1202099	Rock	0.81	7	0.2	27.0	19.2	83	0.1	103.3	26.0	908	3.51	3.0	4.8	7.0	289	<0.1	<0.1	0.3	79	5.41
1202100	Rock	0.37	<2	1.5	43.3	5.2	28	<0.1	37.4	12.8	257	1.00	0.6	1.4	2.5	61	<0.1	<0.1	<0.1	17	0.70
1202196	Rock	0.81	<2	1.8	2.8	4.2	13	<0.1	0.8	0.2	25	0.33	<0.5	2.2	10.4	6	<0.1	0.2	0.2	<2	<0.01
1202197	Rock	1.18	3	22.9	6.1	13.3	26	<0.1	0.6	0.2	20	0.55	1.6	2.9	20.9	4	<0.1	0.2	0.2	<2	<0.01
1202198	Rock	0.56	2	5.3	1.3	20.5	11	0.1	1.1	0.6	19	1.18	8.0	1.7	17.7	32	<0.1	<0.1	0.6	<2	<0.01
1202199	Rock	0.74	2	2.9	1.9	11.0	8	<0.1	0.3	0.1	15	1.27	8.4	2.0	17.5	40	<0.1	<0.1	0.9	<2	<0.01
1202200	Rock	1.38	<2	5.0	12.3	3.5	16	<0.1	2.5	1.7	74	1.14	<0.5	2.2	10.9	5	<0.1	0.2	0.5	<2	<0.01
1202219	Rock	0.75	<2	1.3	13.2	1.0	62	<0.1	6.2	4.6	290	1.59	<0.5	<0.5	2.9	13	<0.1	<0.1	<0.1	12	0.20
1202220	Rock	0.80	<2	<0.1	27.2	2.5	43	<0.1	4.8	14.9	301	2.35	11.9	3.6	0.1	34	<0.1	0.1	<0.1	52	0.74
1202221	Rock	0.52	<2	0.2	54.4	31.4	23	1.4	9.1	1.6	35	0.90	8.1	<0.5	2.2	2	<0.1	<0.1	0.7	9	<0.01
1202222	Rock	1.02	<2	<0.1	7.9	4.5	59	<0.1	2.2	5.7	462	2.45	<0.5	0.5	2.7	5	<0.1	<0.1	<0.1	26	0.07
1202223	Rock	1.09	<2	1.5	2.4	10.8	6	<0.1	0.4	0.2	20	0.62	0.8	1.3	8.8	2	<0.1	<0.1	0.2	<2	<0.01
1202224	Rock	0.44	<2	3.6	1.1	8.0	4	<0.1	0.3	0.2	20	0.45	<0.5	<0.5	4.7	3	<0.1	<0.1	0.2	<2	<0.01
1202225	Rock	0.58	<2	2.0	2.4	3.2	6	<0.1	0.6	0.3	27	0.47	0.5	1.1	14.1	10	<0.1	<0.1	0.7	<2	<0.01
1202231	Rock	0.47	<2	0.1	1.6	5.4	26	<0.1	1.9	1.5	507	0.61	<0.5	0.7	5.9	33	<0.1	<0.1	0.1	4	0.77
1202232	Rock	0.52	<2	<0.1	1.0	5.5	8	<0.1	0.4	0.5	32	0.43	<0.5	<0.5	10.7	4	<0.1	<0.1	<0.1	<2	<0.01
1202233	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202234	Rock	0.58	<2	2.1	689.7	17.8	81	0.7	15.6	67.6	652	27.79	7.1	1.4	1.0	29	0.3	0.1	1.0	35	0.22
1202235	Rock	0.70	<2	0.8	16.6	7.2	29	<0.1	9.2	2.0	53	0.75	4.1	1.1	2.7	9	<0.1	<0.1	<0.1	20	<0.01
1202236	Rock	0.95	<2	0.6	38.1	8.3	47	<0.1	22.0	4.6	122	1.24	3.8	1.0	3.7	5	0.1	0.1	0.1	60	0.02
1202046	Rock	0.66	10	6.1	2.3	24.5	<1	0.5	0.4	0.2	20	0.44	<0.5	5.7	10.4	7	<0.1	0.1	0.6	<2	<0.01
1202047	Rock	0.76	<2	12.6	50.0	12.6	46	1.6	0.7	0.7	23	3.31	<0.5	<0.5	19.4	6	<0.1	<0.1	5.1	<2	<0.01
1202048	Rock	1.40	12	2.2	795.2	25.3	282	0.5	5.3	15.2	450	13.40	19.1	12.1	1.1	31	<0.1	0.3	2.3	75	0.12
1202049	Rock	0.96	<2	<0.1	30.4	3.4	38	<0.1	14.1	15.4	503	1.96	<0.5	2.3	0.6	95	<0.1	<0.1	<0.1	52	1.27
1202050	Rock	0.83	<2	0.6	5.1	13.5	4	<0.1	0.5	0.7	115	0.66	1.2	1.0	23.4	<1	<0.1	0.4	0.3	<2	<0.01
1203721	Rock	0.67	<2	<0.1	0.8	2.2	<1	<0.1	<0.1	0.5	104	0.06	2.0	0.6	<0.1	286	<0.1	<0.1	<0.1	<2	35.05
1203722	Rock	0.38	<2	8.1	39.2	1.9	220	<0.1	74.9	1.6	36	0.70	3.5	1.3	1.3	3	0.5	0.1	<0.1	366	0.28
1203723	Rock	0.60	<2	0.1	5.0	3.3	25	<0.1	19.2	6.0	130	1.28	<0.5	1.3	1.5	17	<0.1	<0.1	<0.1	14	0.34
1203724	Rock	0.37	<2	0.2	10.8	11.1	7	<0.1	5.2	2.1	54	0.71	<0.5	<0.5	15.4	7	<0.1	<0.1	0.9	4	0.11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000485.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1202097	Rock	0.239	32	6	0.89	104	0.029	<20	1.23	0.015	0.27	0.1	<0.01	<0.1	<0.05	2.8	<0.5	3	<0.2
1202099	Rock	0.087	15	281	3.12	86	0.013	<20	2.58	0.016	0.05	<0.1	0.01	<0.1	<0.05	11.0	<0.5	7	<0.2
1202100	Rock	0.109	5	69	0.73	143	0.103	<20	0.72	0.020	0.12	<0.1	<0.01	<0.1	<0.05	1.0	<0.5	2	<0.2
1202196	Rock	0.002	15	6	0.04	198	0.001	<20	0.23	0.021	0.17	0.1	<0.01	<0.1	0.05	0.3	<0.5	<1	<0.2
1202197	Rock	0.004	19	5	0.03	145	<0.001	<20	0.25	0.006	0.20	<0.1	0.02	<0.1	0.10	0.2	<0.5	<1	<0.2
1202198	Rock	0.010	27	7	0.02	349	0.003	<20	0.21	0.048	0.23	<0.1	<0.01	<0.1	0.56	0.3	0.5	<1	<0.2
1202199	Rock	0.016	28	3	0.02	346	0.003	<20	0.20	0.037	0.33	<0.1	<0.01	<0.1	0.45	0.3	<0.5	<1	<0.2
1202200	Rock	0.021	16	9	0.04	72	<0.001	<20	0.14	0.070	<0.01	<0.1	0.04	<0.1	<0.05	0.8	<0.5	<1	<0.2
1202219	Rock	0.027	4	11	0.67	136	0.033	<20	0.91	0.040	0.12	<0.1	<0.01	<0.1	<0.05	1.6	<0.5	4	<0.2
1202220	Rock	0.018	<1	6	1.28	192	0.109	<20	1.68	0.016	0.43	<0.1	0.01	<0.1	0.17	3.4	<0.5	3	<0.2
1202221	Rock	0.007	2	24	0.08	125	0.005	<20	0.39	0.032	0.02	<0.1	<0.01	<0.1	<0.05	1.0	1.3	2	<0.2
1202222	Rock	0.034	6	9	0.42	63	0.009	<20	0.91	0.048	0.09	<0.1	0.01	<0.1	<0.05	3.5	<0.5	4	<0.2
1202223	Rock	<0.001	6	9	0.01	32	<0.001	<20	0.17	0.019	0.20	<0.1	<0.01	<0.1	0.32	0.2	<0.5	<1	<0.2
1202224	Rock	<0.001	2	6	<0.01	253	0.001	<20	0.19	0.018	0.20	0.1	<0.01	<0.1	0.21	0.2	<0.5	<1	<0.2
1202225	Rock	0.003	20	11	0.01	90	0.001	<20	0.17	0.056	0.13	<0.1	<0.01	<0.1	0.11	0.4	<0.5	<1	<0.2
1202231	Rock	0.022	10	7	0.02	87	0.002	<20	0.41	0.042	0.09	<0.1	<0.01	<0.1	<0.05	1.4	<0.5	2	<0.2
1202232	Rock	0.003	4	7	<0.01	255	0.002	<20	0.19	0.052	0.10	<0.1	<0.01	<0.1	<0.05	0.9	<0.5	<1	<0.2
1202233	Rock	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202234	Rock	0.070	10	27	0.09	33	0.017	<20	0.45	0.012	0.07	<0.1	0.01	<0.1	0.15	1.4	44.3	5	0.6
1202235	Rock	0.017	9	18	<0.01	54	<0.001	<20	0.08	0.002	0.02	<0.1	0.02	<0.1	<0.05	1.2	<0.5	<1	<0.2
1202236	Rock	0.018	11	34	0.15	24	0.002	<20	0.35	0.032	0.02	<0.1	0.08	<0.1	<0.05	2.9	<0.5	2	<0.2
1202046	Rock	0.009	42	7	0.01	205	<0.001	<20	0.18	0.007	0.15	<0.1	0.01	<0.1	0.17	0.4	<0.5	<1	<0.2
1202047	Rock	0.002	5	5	0.01	250	<0.001	<20	0.19	0.004	0.13	0.2	0.01	<0.1	0.82	0.2	1.6	<1	0.8
1202048	Rock	0.200	3	3	1.44	54	0.007	<20	2.55	0.010	0.13	<0.1	0.06	<0.1	2.31	3.7	1.9	8	<0.2
1202049	Rock	0.114	3	32	1.13	57	0.221	<20	1.18	0.068	0.06	<0.1	<0.01	<0.1	<0.05	2.6	<0.5	4	<0.2
1202050	Rock	0.003	11	5	0.01	24	0.002	<20	0.16	0.009	0.14	0.7	<0.01	<0.1	0.05	0.2	<0.5	<1	<0.2
1203721	Rock	0.002	1	<1	0.35	17	0.002	<20	0.02	0.002	<0.01	<0.1	<0.01	<0.1	0.18	0.2	<0.5	<1	<0.2
1203722	Rock	0.043	8	25	0.09	63	0.003	<20	0.25	0.002	0.11	0.3	<0.01	<0.1	<0.05	0.8	0.6	1	<0.2
1203723	Rock	0.016	3	29	0.48	90	0.049	<20	0.84	0.029	0.31	<0.1	<0.01	<0.1	<0.05	0.8	<0.5	2	<0.2
1203724	Rock	0.016	13	10	0.08	24	0.013	<20	0.32	0.025	0.17	<0.1	<0.01	<0.1	<0.05	0.6	<0.5	2	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000485.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1203726	Rock	0.62	<2	0.2	6.7	8.9	14	<0.1	1.8	2.0	1779	1.35	0.6	<0.5	1.4	102	0.2	<0.1	<0.1	3	7.35
1203730	Rock	0.39	<2	0.1	3.5	3.4	44	<0.1	50.8	15.3	442	2.59	<0.5	0.6	4.4	7	<0.1	<0.1	<0.1	37	0.30
1203731	Rock	0.45	<2	<0.1	19.5	2.1	115	<0.1	15.5	26.9	1026	3.47	<0.5	<0.5	0.2	26	<0.1	0.1	<0.1	44	0.37
1203733	Rock	0.70	<2	<0.1	17.6	5.0	49	<0.1	87.9	21.3	2028	3.22	<0.5	<0.5	0.5	162	0.2	<0.1	<0.1	68	6.19
1203734	Rock	0.81	2	0.1	22.0	3.7	23	<0.1	14.9	9.8	262	1.31	1.1	<0.5	4.2	13	<0.1	<0.1	<0.1	24	0.59
1203735	Rock	0.31	<2	0.2	2.1	1.0	3	<0.1	0.8	0.6	155	0.37	1.0	<0.5	0.9	3	<0.1	<0.1	<0.1	<2	0.33
1202254	Rock	0.70	<2	0.3	11.4	2.6	89	<0.1	11.1	6.0	285	1.94	1.8	<0.5	2.1	45	0.3	<0.1	<0.1	15	0.56
1202256	Rock	0.60	<2	0.2	2.9	2.3	6	<0.1	0.5	0.5	52	0.48	<0.5	<0.5	5.7	10	<0.1	<0.1	<0.1	<2	0.09
1202257	Rock	0.97	<2	1.5	2.3	9.4	5	<0.1	0.5	0.2	23	0.97	0.7	0.8	5.2	3	<0.1	<0.1	1.1	<2	<0.01
1202259	Rock	1.45	<2	1.0	4.7	0.9	29	<0.1	1.6	17.8	228	3.37	0.5	1.1	0.4	12	<0.1	<0.1	0.3	25	0.26
1202608	Rock	0.30	<2	0.2	3.6	1.6	24	<0.1	3.6	6.1	561	1.28	<0.5	1.0	1.5	32	0.1	0.1	<0.1	15	0.44
1202610	Rock	0.31	<2	<0.1	1.4	1.5	29	<0.1	10.6	4.3	326	0.75	<0.5	0.6	5.0	15	<0.1	<0.1	<0.1	3	0.30
1202612	Rock	0.27	<2	0.1	12.2	6.6	27	<0.1	0.8	9.7	249	2.17	<0.5	<0.5	0.2	56	<0.1	0.1	<0.1	7	0.52
1202613	Rock	0.45	2	0.5	9.2	2209	292	0.9	1.0	0.5	600	1.09	1.4	1.1	1.9	30	3.1	0.3	1.9	<2	1.26
1202614	Rock	0.31	<2	0.4	32.1	11.8	32	<0.1	138.0	28.4	858	3.76	5.3	<0.5	2.3	131	<0.1	<0.1	<0.1	114	3.30
1202691	Rock	0.30	30	0.2	879.6	12.0	9067	0.5	8.0	33.8	3458	0.65	3.3	4.5	1.6	18	31.7	0.1	0.5	3	0.37
1202692	Rock	0.79	<2	0.5	3.5	4.7	28	<0.1	10.4	3.8	147	0.64	1.3	<0.5	3.0	29	0.1	<0.1	<0.1	7	0.67
1202693	Rock	0.88	3	0.6	27.8	9.6	99	<0.1	2.0	5.0	92	1.42	24.8	1.4	1.9	19	0.4	0.2	0.2	3	0.03
1202698	Rock	0.97	<2	0.9	3.7	4.3	16	0.1	3.4	3.2	192	1.19	21.2	<0.5	6.3	6	<0.1	<0.1	0.2	4	0.15
1202699	Rock	1.22	<2	0.1	1.7	3.4	23	<0.1	3.3	4.5	252	0.78	0.7	<0.5	3.0	25	<0.1	<0.1	<0.1	4	0.30
1202700	Rock	1.00	<2	<0.1	1.7	0.4	5	<0.1	1.7	0.6	40	0.33	1.1	<0.5	0.1	1	<0.1	<0.1	<0.1	<2	0.01
1203738	Rock	0.62	4	0.8	59.4	5.7	95	0.2	47.3	15.4	441	2.97	12.1	5.5	2.8	13	0.4	0.2	<0.1	40	0.76
1202601	Rock	0.33	<2	0.4	1.5	26.3	10	<0.1	1.5	1.4	255	0.78	<0.5	<0.5	17.6	40	<0.1	<0.1	0.3	<2	0.46
1202603	Rock	0.31	<2	4.4	28.9	2.4	110	0.1	51.6	1.4	45	0.66	9.9	<0.5	1.0	7	0.3	0.1	<0.1	455	0.29
1202604	Rock	0.33	<2	0.2	7.0	5.5	38	<0.1	33.4	11.0	248	2.59	<0.5	<0.5	6.4	22	<0.1	<0.1	<0.1	38	0.43
1202605	Rock	0.34	<2	0.1	8.3	19.2	4	<0.1	2.1	0.9	27	0.42	<0.5	<0.5	27.3	1	<0.1	<0.1	0.6	3	0.01
1202606	Rock	0.15	<2	0.2	1.4	3.6	68	<0.1	23.2	26.9	1227	5.19	1.0	<0.5	0.5	39	0.1	0.2	<0.1	178	1.24

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000485.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1203726	Rock	0.022	4	7	0.23	53	0.002	<20	0.29	0.015	0.05	<0.1	<0.01	<0.1	0.06	3.9	<0.5	1	<0.2
1203730	Rock	0.069	7	47	1.95	65	0.070	<20	1.81	0.024	0.16	<0.1	<0.01	<0.1	<0.05	4.1	<0.5	6	<0.2
1203731	Rock	0.031	<1	15	3.17	47	0.082	<20	2.80	0.009	0.07	<0.1	<0.01	<0.1	<0.05	2.6	<0.5	6	<0.2
1203733	Rock	0.039	2	284	3.61	56	0.035	<20	2.81	0.002	<0.01	<0.1	<0.01	<0.1	<0.05	10.2	<0.5	5	<0.2
1203734	Rock	0.023	7	36	0.85	34	0.035	<20	0.90	0.039	0.13	<0.1	<0.01	<0.1	<0.05	2.4	<0.5	2	<0.2
1203735	Rock	0.013	2	2	0.04	25	0.002	<20	0.16	0.009	0.10	<0.1	<0.01	<0.1	<0.05	0.2	<0.5	<1	<0.2
1202254	Rock	0.047	5	7	0.40	243	0.046	<20	1.11	0.035	0.21	<0.1	<0.01	<0.1	<0.05	2.0	<0.5	4	<0.2
1202256	Rock	0.005	5	6	<0.01	351	0.003	<20	0.24	0.048	0.19	<0.1	<0.01	<0.1	<0.05	0.8	<0.5	1	<0.2
1202257	Rock	0.002	1	7	0.01	40	0.002	<20	0.14	0.062	0.15	<0.1	<0.01	<0.1	0.21	0.2	1.7	<1	0.3
1202259	Rock	0.053	1	4	0.97	32	0.090	<20	1.02	0.072	0.04	<0.1	<0.01	<0.1	2.13	2.7	1.2	4	0.4
1202608	Rock	0.015	4	5	0.44	113	0.073	<20	0.79	0.030	0.14	0.2	<0.01	<0.1	<0.05	1.3	<0.5	3	<0.2
1202610	Rock	0.023	6	25	0.54	71	0.030	<20	0.65	0.041	0.11	<0.1	<0.01	<0.1	<0.05	0.7	<0.5	2	<0.2
1202612	Rock	0.063	1	3	0.78	84	0.083	<20	1.15	0.030	0.16	0.1	0.02	<0.1	<0.05	1.9	<0.5	3	<0.2
1202613	Rock	0.001	5	10	1.68	23	<0.001	<20	0.05	0.004	0.03	<0.1	0.02	<0.1	<0.05	0.5	<0.5	<1	0.2
1202614	Rock	0.033	7	71	3.44	182	0.241	<20	3.89	0.345	0.15	<0.1	<0.01	<0.1	0.10	6.5	<0.5	8	<0.2
1202691	Rock	0.018	3	5	0.21	220	0.020	<20	0.41	0.029	0.08	<0.1	<0.01	<0.1	<0.05	1.0	<0.5	2	<0.2
1202692	Rock	0.056	4	9	0.36	355	0.021	<20	0.61	0.038	0.22	<0.1	<0.01	<0.1	0.05	1.2	<0.5	2	<0.2
1202693	Rock	0.020	7	13	0.07	167	0.007	<20	0.22	0.061	0.02	<0.1	<0.01	<0.1	0.10	1.7	<0.5	<1	<0.2
1202698	Rock	0.018	16	6	0.07	228	0.005	<20	0.43	0.036	0.22	<0.1	<0.01	<0.1	0.23	2.2	<0.5	1	<0.2
1202699	Rock	0.033	5	6	0.18	251	0.037	<20	0.57	0.033	0.19	<0.1	<0.01	<0.1	<0.05	1.1	<0.5	2	<0.2
1202700	Rock	0.002	<1	18	0.02	17	0.003	<20	0.06	0.005	0.01	<0.1	<0.01	<0.1	<0.05	0.1	<0.5	<1	<0.2
1203738	Rock	0.077	9	46	1.39	420	0.018	<20	1.51	0.008	0.08	<0.1	0.07	<0.1	<0.05	2.0	1.2	4	<0.2
1202601	Rock	0.017	42	6	0.18	482	0.001	<20	0.16	0.018	0.16	<0.1	<0.01	<0.1	<0.05	1.4	<0.5	<1	<0.2
1202603	Rock	0.141	8	47	0.05	66	0.004	<20	0.26	0.003	0.13	0.3	<0.01	<0.1	<0.05	1.1	0.7	2	<0.2
1202604	Rock	0.071	7	61	0.88	193	0.154	<20	1.60	0.049	0.72	<0.1	<0.01	0.2	<0.05	1.9	<0.5	5	<0.2
1202605	Rock	0.005	4	10	<0.01	9	0.002	<20	0.16	0.054	0.09	<0.1	<0.01	<0.1	<0.05	1.0	<0.5	<1	<0.2
1202606	Rock	0.035	2	53	3.60	20	0.299	<20	3.49	0.040	0.01	0.1	<0.01	<0.1	<0.05	13.4	<0.5	10	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000485.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1202196	Rock	0.81	<2	1.8	2.8	4.2	13	<0.1	0.8	0.2	25	0.33	<0.5	2.2	10.4	6	<0.1	0.2	0.2	<2	<0.01
REP 1202196	QC		2																		
1202614	Rock	0.31	<2	0.4	32.1	11.8	32	<0.1	138.0	28.4	858	3.76	5.3	<0.5	2.3	131	<0.1	<0.1	<0.1	114	3.30
REP 1202614	QC		<2																		
1202601	Rock	0.33	<2	0.4	1.5	26.3	10	<0.1	1.5	1.4	255	0.78	<0.5	<0.5	17.6	40	<0.1	<0.1	0.3	<2	0.46
REP 1202601	QC			0.4	1.7	27.9	11	<0.1	1.6	1.7	263	0.82	<0.5	<0.5	18.9	42	<0.1	<0.1	0.3	<2	0.54
Core Reject Duplicates																					
1203730	Rock	0.39	<2	0.1	3.5	3.4	44	<0.1	50.8	15.3	442	2.59	<0.5	0.6	4.4	7	<0.1	<0.1	<0.1	37	0.30
DUP 1203730	QC		<2	0.2	3.5	3.6	45	<0.1	53.4	15.6	451	2.79	<0.5	<0.5	5.0	11	<0.1	<0.1	<0.1	43	0.38
Reference Materials																					
STD DS8	Standard			12.8	98.2	121.0	306	1.7	37.1	7.3	603	2.44	25.8	101.1	6.2	62	2.5	3.9	6.0	41	0.72
STD DS8	Standard			13.5	108.2	129.4	289	1.6	37.9	7.4	558	2.29	24.5	99.8	6.7	63	2.1	4.4	6.1	40	0.66
STD DS8	Standard			14.1	114.2	129.7	320	1.7	40.4	7.8	610	2.52	26.1	110.2	6.3	66	2.2	4.2	6.1	43	0.70
STD DS8	Standard			15.2	123.4	118.2	341	1.9	43.7	8.4	654	2.54	31.2	107.1	5.9	59	2.6	3.6	6.2	40	0.72
STD DS8	Standard			13.1	111.2	119.2	321	1.7	40.2	8.0	611	2.51	27.4	109.1	6.2	62	2.4	4.0	5.8	41	0.70
STD OREAS45CA	Standard			0.8	500.4	18.3	63	0.3	250.7	87.3	908	16.26	3.6	40.9	6.6	15	<0.1	<0.1	0.2	209	0.44
STD OREAS45CA	Standard			0.9	503.9	22.4	59	0.2	247.3	91.7	900	15.14	3.1	38.1	7.8	16	<0.1	<0.1	0.2	206	0.39
STD OREAS45CA	Standard			1.0	505.6	21.9	63	0.3	245.3	92.9	901	16.09	2.8	35.6	7.2	15	<0.1	<0.1	0.2	208	0.38
STD OREAS45CA	Standard			0.8	489.8	18.4	60	0.3	243.4	88.2	905	16.43	3.7	35.6	5.9	13	0.1	<0.1	0.2	207	0.45
STD OREAS45CA	Standard			1.0	466.9	18.8	59	0.3	233.3	89.0	887	15.60	3.9	35.1	6.5	15	0.1	0.2	0.2	199	0.39
STD OXC88	Standard		201																		
STD OXC88	Standard		193																		
STD OXC88	Standard		197																		
STD OXH82	Standard		1315																		
STD OXH82	Standard		1380																		
STD OXH82	Standard		1406																		
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000485.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
1202196	Rock	0.002	15	6	0.04	198	0.001	<20	0.23	0.021	0.17	0.1	<0.01	<0.1	0.05	0.3	<0.5	<1	<0.2
REP 1202196	QC																		
1202614	Rock	0.033	7	71	3.44	182	0.241	<20	3.89	0.345	0.15	<0.1	<0.01	<0.1	0.10	6.5	<0.5	8	<0.2
REP 1202614	QC																		
1202601	Rock	0.017	42	6	0.18	482	0.001	<20	0.16	0.018	0.16	<0.1	<0.01	<0.1	<0.05	1.4	<0.5	<1	<0.2
REP 1202601	QC	0.017	43	6	0.19	515	0.002	<20	0.17	0.019	0.17	<0.1	<0.01	<0.1	<0.05	1.5	<0.5	<1	<0.2
Core Reject Duplicates																			
1203730	Rock	0.069	7	47	1.95	65	0.070	<20	1.81	0.024	0.16	<0.1	<0.01	<0.1	<0.05	4.1	<0.5	6	<0.2
DUP 1203730	QC	0.070	9	51	2.01	112	0.111	<20	2.03	0.060	0.26	0.1	<0.01	<0.1	<0.05	4.8	<0.5	7	<0.2
Reference Materials																			
STD DS8	Standard	0.081	13	110	0.59	293	0.102	<20	0.89	0.087	0.41	3.0	0.18	5.4	0.17	1.9	5.2	5	5.2
STD DS8	Standard	0.069	12	116	0.57	265	0.114	<20	0.86	0.078	0.37	2.4	0.21	5.0	0.16	1.8	4.7	4	4.9
STD DS8	Standard	0.080	13	121	0.61	286	0.116	<20	0.90	0.083	0.39	3.2	0.22	5.0	0.17	2.1	6.2	4	4.8
STD DS8	Standard	0.090	14	123	0.62	322	0.097	<20	0.90	0.086	0.44	2.8	0.24	5.8	0.18	2.1	5.2	5	4.9
STD DS8	Standard	0.077	13	119	0.61	291	0.111	<20	0.89	0.086	0.40	2.6	0.19	5.0	0.17	2.0	5.2	4	5.0
STD OREAS45CA	Standard	0.038	15	710	0.13	169	0.116	<20	3.57	0.009	0.08	<0.1	0.03	<0.1	<0.05	33.9	0.7	20	<0.2
STD OREAS45CA	Standard	0.032	15	690	0.11	163	0.145	<20	3.55	0.014	0.07	<0.1	0.04	<0.1	<0.05	34.9	0.6	18	<0.2
STD OREAS45CA	Standard	0.036	16	699	0.13	166	0.137	<20	3.56	0.014	0.07	<0.1	0.01	<0.1	<0.05	36.7	<0.5	18	<0.2
STD OREAS45CA	Standard	0.042	15	835	0.12	170	0.106	<20	3.56	0.010	0.08	<0.1	0.02	0.1	<0.05	35.7	<0.5	19	<0.2
STD OREAS45CA	Standard	0.035	15	694	0.12	158	0.117	<20	3.35	0.009	0.07	<0.1	0.03	<0.1	<0.05	34.5	0.8	18	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXC88 Expected																			
STD OXH82 Expected																			

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000485.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		2	<0.1	1.4	2.6	71	<0.1	3.9	4.2	535	1.85	<0.5	<0.5	4.4	53	<0.1	<0.1	<0.1	35	0.40
G1	Prep Blank		<2	<0.1	1.3	3.7	71	<0.1	3.6	4.5	551	1.91	<0.5	<0.5	4.9	59	<0.1	<0.1	<0.1	37	0.42

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000485.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	0.005	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																			
G1	Prep Blank	0.074	7	12	0.57	206	0.123	<20	0.92	0.067	0.43	<0.1	<0.01	0.1	<0.05	1.8	<0.5	5	<0.2
G1	Prep Blank	0.076	8	13	0.58	216	0.131	<20	0.94	0.071	0.46	<0.1	<0.01	0.1	<0.05	1.8	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Submitted By: Bruce Durham
Receiving Lab: Canada-Whitehorse
Received: July 08, 2011
Report Date: August 09, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11000507.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID: July-3-2011
P.O. Number
Number of Samples: 49

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	49	Crush, split and pulverize 250 g rock to 200 mesh			WHI
3B	49	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	49	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Don Christie
Daithi Mac Gearailt
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000507.1

Method		WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
Unit		kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
MDL		0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1202260	Rock	0.66	<2	<0.1	20.4	14.4	54	<0.1	32.7	11.0	292	2.70	1.6	<0.5	9.7	7	0.1	<0.1	0.1	22	0.23
1202265	Rock	0.80	<2	1.4	12.1	7.7	12	<0.1	0.4	0.4	85	0.47	<0.5	<0.5	19.9	2	<0.1	<0.1	0.1	<2	<0.01
1202269	Rock	0.72	<2	6.2	64.7	12.6	58	0.1	53.3	11.3	199	2.07	0.8	1.3	6.6	15	0.2	<0.1	0.3	26	0.43
1202270	Rock	1.01	16	0.7	9.5	40.0	20	0.3	0.7	0.4	52	0.53	<0.5	<0.5	24.0	1	<0.1	<0.1	0.7	<2	<0.01
1202273	Rock	0.82	<2	0.1	2.5	2.4	9	<0.1	3.1	1.3	164	0.62	<0.5	<0.5	11.0	4	<0.1	<0.1	<0.1	4	0.03
1202275	Rock	0.68	<2	6.3	48.2	387.5	277	0.8	1.7	0.9	26	1.07	1.5	0.6	24.3	23	2.5	<0.1	1.8	<2	0.07
1202276	Rock	0.61	<2	0.2	14.0	5.9	54	<0.1	0.7	0.5	198	1.67	<0.5	<0.5	36.2	5	<0.1	<0.1	0.3	3	0.03
1202277	Rock	0.77	4	0.5	35.9	9.1	108	<0.1	58.2	16.2	191	3.78	0.6	<0.5	10.2	4	<0.1	<0.1	0.2	35	0.17
1202238	Rock	0.38	<2	0.5	3.5	4.4	34	<0.1	14.0	3.7	308	1.34	0.7	<0.5	2.3	4	<0.1	0.2	0.1	51	0.08
1202239	Rock	0.85	<2	0.7	29.7	6.5	59	<0.1	18.2	3.6	88	1.76	3.1	1.1	5.4	8	<0.1	<0.1	0.2	32	0.02
1202240	Rock	0.48	4	1.4	44.2	3.7	18	0.1	11.6	5.0	791	1.10	4.5	1.4	0.8	7	<0.1	0.2	<0.1	24	0.02
1202241	Rock	0.87	<2	0.4	6.1	7.0	18	<0.1	7.1	8.0	326	0.96	1.2	<0.5	4.0	4	<0.1	0.6	<0.1	10	0.01
1202242	Rock	1.05	<2	0.1	1.7	1.9	45	<0.1	2.7	3.7	362	1.16	0.8	<0.5	3.0	14	<0.1	<0.1	<0.1	6	0.60
1202243	Rock	0.78	<2	<0.1	9.7	4.5	63	<0.1	1.9	4.6	614	1.38	<0.5	<0.5	2.9	23	0.1	<0.1	<0.1	6	1.71
1202616	Rock	0.54	<2	0.4	42.4	55.0	50	0.1	5.4	3.6	212	0.97	<0.5	<0.5	1.0	<1	<0.1	<0.1	0.5	8	0.02
1202617	Rock	0.74	<2	0.1	2.3	1939	1	6.1	0.7	0.2	39	0.32	<0.5	3.2	1.1	1	0.3	<0.1	22.8	<2	0.01
1202618	Rock	0.74	<2	2.3	1.7	11.5	5	<0.1	0.7	0.3	44	0.52	0.9	<0.5	11.9	7	<0.1	<0.1	1.4	<2	<0.01
1202619	Rock	0.97	<2	1.3	25.7	20.8	87	0.5	2.9	8.1	703	3.01	3.0	0.5	2.5	12	0.3	<0.1	0.3	14	0.74
1202620	Rock	0.45	<2	<0.1	2.7	3.5	7	<0.1	0.5	0.7	87	0.42	<0.5	<0.5	5.5	7	<0.1	<0.1	<0.1	2	0.10
1202621	Rock	0.57	7	1.2	2.8	14.3	4	0.1	0.6	0.3	38	0.61	<0.5	<0.5	8.5	1	<0.1	<0.1	0.7	3	0.01
1202622	Rock	0.62	<2	0.2	5.9	7.1	42	<0.1	3.2	9.8	652	1.47	6.0	1.7	3.4	25	0.2	<0.1	0.2	12	1.57
1202623	Rock	0.55	<2	1.9	3.3	3.8	2	<0.1	1.2	7.4	34	1.03	9.8	1.5	0.8	4	<0.1	<0.1	<0.1	<2	0.01
1202624	Rock	0.65	2	0.3	1.0	4.7	26	<0.1	2.4	2.5	160	0.81	<0.5	<0.5	2.7	23	<0.1	<0.1	<0.1	5	0.67
1202625	Rock	0.38	15	0.5	37.2	4.9	102	<0.1	51.1	10.7	311	3.79	<0.5	<0.5	9.2	4	<0.1	<0.1	0.1	63	0.15
1202626	Rock	0.41	<2	0.3	1.8	2.2	26	<0.1	2.7	2.5	325	0.67	<0.5	<0.5	3.9	17	<0.1	<0.1	<0.1	4	0.84
1202627	Rock	0.63	<2	<0.1	0.9	0.8	6	<0.1	1.0	0.6	84	0.32	<0.5	<0.5	0.3	2	<0.1	<0.1	<0.1	<2	0.04
1202628	Rock	0.57	<2	0.1	1.6	1.1	2	<0.1	4.2	17.3	36	1.15	2.5	<0.5	0.4	2	<0.1	<0.1	<0.1	<2	0.02
1202629	Rock	0.41	<2	0.1	1.2	2.0	13	<0.1	1.8	2.1	89	0.66	0.7	<0.5	3.7	11	<0.1	<0.1	<0.1	3	0.15
1202631	Rock	1.28	<2	<0.1	0.3	2.6	4	<0.1	0.2	1.0	1345	0.96	<0.5	<0.5	5.2	64	<0.1	<0.1	<0.1	3	5.78
1202632	Rock	0.78	3	0.4	0.3	1.2	6	<0.1	0.4	0.3	59	0.33	<0.5	<0.5	4.9	8	<0.1	<0.1	<0.1	<2	0.08

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000507.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1202260	Rock	0.044	16	34	0.89	44	0.042	<20	1.57	0.044	0.20	<0.1	<0.01	<0.1	<0.05	2.1	<0.5	5	<0.2
1202265	Rock	0.004	33	3	0.16	35	0.002	<20	0.40	0.010	0.29	<0.1	<0.01	<0.1	0.07	0.4	<0.5	2	<0.2
1202269	Rock	0.039	16	19	0.53	229	0.028	<20	0.88	0.012	0.36	<0.1	<0.01	0.1	1.08	1.2	<0.5	2	<0.2
1202270	Rock	0.002	3	3	0.13	65	0.003	<20	0.33	0.035	0.28	0.1	0.02	0.1	0.14	0.2	<0.5	1	<0.2
1202273	Rock	0.012	20	5	0.39	50	0.002	<20	0.49	0.088	0.11	<0.1	<0.01	<0.1	<0.05	0.8	<0.5	2	<0.2
1202275	Rock	0.039	25	3	0.08	136	0.003	<20	0.29	0.037	0.22	<0.1	0.41	<0.1	0.52	0.3	<0.5	1	0.3
1202276	Rock	0.004	20	3	0.14	16	0.008	<20	0.44	0.058	0.23	<0.1	0.02	<0.1	<0.05	0.3	<0.5	4	<0.2
1202277	Rock	0.079	13	37	1.23	74	0.007	<20	2.10	0.013	0.23	<0.1	0.02	<0.1	<0.05	2.7	<0.5	6	<0.2
1202238	Rock	0.041	8	18	0.45	56	0.002	<20	0.69	0.038	0.02	<0.1	0.01	<0.1	<0.05	1.6	<0.5	4	<0.2
1202239	Rock	0.017	17	17	0.02	174	0.001	<20	0.30	0.007	0.14	<0.1	0.05	<0.1	<0.05	1.4	<0.5	1	<0.2
1202240	Rock	0.022	3	16	0.01	102	<0.001	<20	0.14	0.002	<0.01	<0.1	0.05	<0.1	<0.05	1.4	0.8	<1	<0.2
1202241	Rock	0.006	3	16	0.02	41	<0.001	<20	0.27	0.024	0.05	<0.1	0.01	<0.1	<0.05	1.1	<0.5	<1	<0.2
1202242	Rock	0.024	5	7	0.28	238	0.003	<20	0.68	0.058	0.15	<0.1	0.01	<0.1	0.07	2.1	<0.5	2	<0.2
1202243	Rock	0.044	6	6	0.36	78	0.003	<20	0.75	0.083	0.08	<0.1	<0.01	<0.1	0.12	2.7	<0.5	2	<0.2
1202616	Rock	0.005	2	10	0.86	8	0.001	<20	0.67	0.031	0.02	<0.1	0.02	<0.1	<0.05	0.8	0.6	2	<0.2
1202617	Rock	<0.001	<1	15	<0.01	14	<0.001	<20	0.06	0.005	0.06	<0.1	<0.01	<0.1	<0.05	<0.1	2.1	<1	0.5
1202618	Rock	0.002	2	9	0.01	508	0.001	<20	0.10	0.042	0.06	<0.1	<0.01	<0.1	<0.05	0.1	<0.5	<1	1.0
1202619	Rock	0.056	4	6	0.55	167	0.012	<20	1.28	0.037	0.17	<0.1	<0.01	<0.1	0.72	2.4	0.6	3	<0.2
1202620	Rock	0.006	5	5	<0.01	136	0.002	<20	0.28	0.036	0.20	<0.1	0.01	<0.1	<0.05	1.5	<0.5	1	<0.2
1202621	Rock	0.003	3	8	0.01	63	0.008	<20	0.18	0.058	0.11	<0.1	0.01	<0.1	<0.05	1.2	<0.5	<1	<0.2
1202622	Rock	0.039	10	6	0.46	198	0.011	<20	0.82	0.078	0.11	<0.1	<0.01	<0.1	0.27	3.0	<0.5	3	<0.2
1202623	Rock	0.006	1	13	0.01	44	0.001	<20	0.09	0.020	0.03	<0.1	<0.01	<0.1	<0.05	0.5	<0.5	<1	<0.2
1202624	Rock	0.021	7	8	0.31	157	0.007	<20	0.60	0.072	0.08	<0.1	0.01	<0.1	<0.05	1.2	<0.5	2	<0.2
1202625	Rock	0.060	5	72	1.76	164	0.085	<20	2.45	0.010	0.68	<0.1	<0.01	0.3	<0.05	2.8	0.7	7	<0.2
1202626	Rock	0.034	5	5	0.17	186	0.029	<20	0.58	0.056	0.27	<0.1	0.02	0.1	<0.05	0.9	<0.5	2	<0.2
1202627	Rock	0.005	<1	9	0.08	57	0.001	<20	0.12	0.005	0.04	<0.1	<0.01	<0.1	<0.05	0.2	<0.5	<1	<0.2
1202628	Rock	0.004	<1	16	0.01	49	<0.001	<20	0.06	0.005	0.03	<0.1	<0.01	<0.1	0.22	0.2	<0.5	<1	<0.2
1202629	Rock	0.025	4	5	0.15	144	0.009	<20	0.47	0.048	0.17	<0.1	0.01	<0.1	<0.05	0.9	<0.5	2	<0.2
1202631	Rock	0.010	11	2	0.06	279	0.002	<20	0.66	0.017	0.24	<0.1	0.02	<0.1	0.10	1.0	<0.5	2	<0.2
1202632	Rock	0.007	10	7	0.01	179	0.011	<20	0.23	0.047	0.21	<0.1	0.01	<0.1	<0.05	0.9	<0.5	1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000507.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1202633	Rock	0.57	<2	0.4	1.1	3.6	7	<0.1	0.5	0.5	72	0.52	<0.5	<0.5	3.0	9	<0.1	<0.1	<0.1	<2	0.13
1202635	Rock	0.39	<2	0.3	8.2	3.5	57	<0.1	9.4	4.6	260	2.88	<0.5	<0.5	11.4	8	<0.1	<0.1	0.1	26	0.06
1202637	Rock	0.36	<2	0.2	1.5	6.3	26	<0.1	1.0	0.7	140	0.85	0.7	<0.5	12.4	2	<0.1	<0.1	<0.1	3	0.03
1202640	Rock	0.35	<2	0.4	8.0	3.3	46	<0.1	1.6	6.2	427	2.04	<0.5	<0.5	9.4	15	<0.1	<0.1	<0.1	22	0.20
1203651	Rock	0.78	<2	0.1	44.8	8.9	53	<0.1	2.8	15.2	612	4.76	0.8	1.4	0.1	127	<0.1	<0.1	0.4	64	0.81
1203652	Rock	1.12	<2	0.1	57.9	6.9	60	<0.1	3.4	17.2	621	4.70	1.3	<0.5	0.1	85	<0.1	<0.1	0.3	67	0.60
1203653	Rock	1.07	<2	1.0	12.6	2.4	14	<0.1	2.6	12.6	152	1.47	5.7	2.3	4.9	10	<0.1	<0.1	0.8	10	0.16
1203654	Rock	0.72	<2	0.5	103.3	1.5	51	<0.1	14.2	22.5	900	3.75	1.4	0.8	<0.1	35	<0.1	0.1	<0.1	94	3.09
1203655	Rock	1.02	<2	4.3	2.8	26.5	4	<0.1	0.5	0.2	29	0.74	2.1	2.4	15.0	7	<0.1	<0.1	0.3	<2	<0.01
1203656	Rock	0.82	<2	0.7	6.1	6.5	61	<0.1	3.2	3.7	292	1.42	1.1	0.6	15.7	12	0.1	<0.1	0.1	2	0.09
1203657	Rock	1.10	<2	0.4	4.2	12.1	31	<0.1	1.4	0.6	282	1.30	3.5	<0.5	19.1	8	0.2	<0.1	0.2	<2	0.02
1203660	Rock	0.98	<2	0.4	33.4	10.9	52	<0.1	11.3	8.3	476	2.14	1.0	0.6	10.3	29	<0.1	<0.1	<0.1	29	0.32
1202278	Rock	1.06	<2	1.3	2.9	39.6	105	0.2	0.8	0.2	275	2.24	1.1	0.9	47.6	2	0.5	<0.1	0.4	<2	0.18
1202280	Rock	0.79	<2	0.4	5.7	4.7	3	<0.1	1.1	0.8	103	0.55	1.1	1.5	15.0	4	<0.1	<0.1	0.3	<2	<0.01
1203751	Rock	1.17	<2	0.2	108.1	2.7	9	<0.1	2.1	2.7	770	0.96	1.2	1.4	2.2	10	0.2	<0.1	<0.1	3	1.00
1203752	Rock	1.13	<2	0.3	3.3	0.8	14	<0.1	7.5	4.5	143	0.49	1.2	<0.5	4.0	29	<0.1	<0.1	<0.1	6	0.55
1202245	Rock	0.76	<2	0.5	41.2	5.4	85	0.2	2.9	7.9	664	4.21	19.9	<0.5	7.2	33	0.2	0.1	0.3	36	0.90
1202246	Rock	0.88	<2	0.3	9.5	1.7	10	<0.1	0.8	1.1	102	1.41	2.2	<0.5	4.1	21	<0.1	<0.1	0.6	8	0.33
1202250	Rock	0.36	<2	0.5	44.6	6.6	106	<0.1	75.3	12.7	176	3.64	1.3	1.8	9.6	9	<0.1	<0.1	0.1	71	0.24

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000507.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1202633	Rock	0.005	2	5	0.02	382	0.002	<20	0.25	0.038	0.16	<0.1	0.02	<0.1	<0.05	1.0	<0.5	1	<0.2
1202635	Rock	0.027	5	20	0.67	170	0.200	<20	1.52	0.024	1.18	<0.1	0.01	0.4	<0.05	1.5	<0.5	5	<0.2
1202637	Rock	0.007	4	9	0.07	16	0.024	<20	0.36	0.044	0.22	<0.1	0.01	0.2	<0.05	1.0	<0.5	3	<0.2
1202640	Rock	0.032	14	5	0.59	172	0.112	<20	1.13	0.056	0.76	<0.1	<0.01	0.2	<0.05	2.1	<0.5	4	<0.2
1203651	Rock	0.029	<1	3	1.90	19	0.229	<20	2.58	0.028	0.14	<0.1	0.01	<0.1	0.05	5.8	<0.5	7	<0.2
1203652	Rock	0.026	<1	5	2.13	37	0.215	<20	2.53	0.022	0.25	<0.1	0.02	<0.1	0.10	5.2	<0.5	7	<0.2
1203653	Rock	0.020	8	5	0.82	33	0.083	<20	0.79	0.077	0.14	<0.1	0.01	<0.1	0.62	2.1	<0.5	3	0.8
1203654	Rock	0.023	<1	14	2.33	9	0.141	<20	2.64	0.018	0.02	<0.1	<0.01	<0.1	<0.05	4.8	<0.5	6	<0.2
1203655	Rock	0.003	30	6	0.03	103	0.003	<20	0.32	0.079	0.22	0.2	<0.01	<0.1	0.16	0.3	<0.5	<1	<0.2
1203656	Rock	0.029	23	3	0.46	56	0.003	<20	0.47	0.011	0.29	<0.1	<0.01	<0.1	0.33	0.6	<0.5	1	<0.2
1203657	Rock	0.002	85	<1	0.43	123	0.003	<20	0.40	0.004	0.36	0.3	<0.01	0.1	0.26	0.2	<0.5	2	<0.2
1203660	Rock	0.014	19	29	1.28	95	0.045	<20	1.46	0.015	0.17	<0.1	<0.01	<0.1	0.06	2.4	<0.5	4	<0.2
1202278	Rock	0.001	100	9	0.10	32	0.008	<20	0.41	0.106	0.25	<0.1	0.03	<0.1	<0.05	0.4	<0.5	4	<0.2
1202280	Rock	0.002	1	5	0.02	629	0.003	<20	0.29	0.056	0.21	<0.1	<0.01	<0.1	<0.05	0.3	<0.5	1	<0.2
1203751	Rock	0.030	4	7	0.44	16	0.001	<20	0.40	0.112	0.01	<0.1	0.01	<0.1	<0.05	2.1	<0.5	1	<0.2
1203752	Rock	0.021	3	13	0.16	58	0.052	<20	0.45	0.085	0.05	<0.1	0.01	<0.1	<0.05	1.5	<0.5	2	<0.2
1202245	Rock	0.037	34	4	0.82	156	0.024	<20	2.02	0.060	0.16	<0.1	<0.01	<0.1	0.57	7.2	<0.5	6	<0.2
1202246	Rock	0.022	8	13	0.16	181	0.052	<20	0.69	0.049	0.15	<0.1	0.01	<0.1	<0.05	1.7	<0.5	3	<0.2
1202250	Rock	0.078	9	88	2.03	208	0.120	<20	2.62	0.024	0.60	<0.1	<0.01	0.3	<0.05	4.4	<0.5	8	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000507.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
1202616	Rock	0.54	<2	0.4	42.4	55.0	50	0.1	5.4	3.6	212	0.97	<0.5	<0.5	1.0	<1	<0.1	<0.1	0.5	8	0.02
REP 1202616	QC			0.3	41.7	54.9	49	0.1	5.5	3.5	210	0.93	<0.5	<0.5	1.0	<1	<0.1	<0.1	0.4	8	0.02
1202629	Rock	0.41	<2	0.1	1.2	2.0	13	<0.1	1.8	2.1	89	0.66	0.7	<0.5	3.7	11	<0.1	<0.1	<0.1	3	0.15
REP 1202629	QC		<2																		
1203655	Rock	1.02	<2	4.3	2.8	26.5	4	<0.1	0.5	0.2	29	0.74	2.1	2.4	15.0	7	<0.1	<0.1	0.3	<2	<0.01
REP 1203655	QC			3.8	2.8	25.8	4	<0.1	0.5	0.2	29	0.72	2.0	1.1	14.8	7	<0.1	<0.1	0.3	<2	<0.01
Core Reject Duplicates																					
1202617	Rock	0.74	<2	0.1	2.3	1939	1	6.1	0.7	0.2	39	0.32	<0.5	3.2	1.1	1	0.3	<0.1	22.8	<2	0.01
DUP 1202617	QC		5	0.1	2.4	2237	1	6.9	0.4	0.1	24	0.17	<0.5	0.5	1.2	1	0.3	<0.1	25.4	<2	<0.01
Reference Materials																					
STD DS8	Standard			14.3	110.2	127.9	351	2.0	38.0	7.1	634	2.53	28.4	104.8	6.9	72	2.5	4.5	6.4	41	0.75
STD DS8	Standard			14.1	108.6	129.5	323	1.9	37.7	7.1	630	2.47	26.6	133.9	6.7	64	2.0	4.4	6.0	43	0.69
STD OREAS45CA	Standard			0.7	524.7	19.9	63	0.3	259.8	86.8	947	16.93	4.2	45.7	7.2	16	<0.1	<0.1	0.2	209	0.42
STD OREAS45CA	Standard			0.9	495.7	20.5	60	0.3	240.1	86.2	878	15.82	3.6	42.2	6.6	14	0.1	0.1	0.2	204	0.45
STD OXC88	Standard		211																		
STD OXC88	Standard		183																		
STD OXC88	Standard		206																		
STD OXH82	Standard		1331																		
STD OXH82	Standard		1185																		
STD OXH82	Standard		1316																		
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000507.1

		Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
		Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
		Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
		MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																				
1202616	Rock		0.005	2	10	0.86	8	0.001	<20	0.67	0.031	0.02	<0.1	0.02	<0.1	<0.05	0.8	0.6	2	<0.2
REP 1202616	QC		0.005	2	9	0.84	7	0.001	<20	0.67	0.033	0.02	<0.1	0.01	<0.1	<0.05	0.8	<0.5	2	<0.2
1202629	Rock		0.025	4	5	0.15	144	0.009	<20	0.47	0.048	0.17	<0.1	0.01	<0.1	<0.05	0.9	<0.5	2	<0.2
REP 1202629	QC																			
1203655	Rock		0.003	30	6	0.03	103	0.003	<20	0.32	0.079	0.22	0.2	<0.01	<0.1	0.16	0.3	<0.5	<1	<0.2
REP 1203655	QC		0.003	29	7	0.04	100	0.003	<20	0.32	0.079	0.21	0.2	0.01	<0.1	0.15	0.3	<0.5	<1	<0.2
Core Reject Duplicates																				
1202617	Rock		<0.001	<1	15	<0.01	14	<0.001	<20	0.06	0.005	0.06	<0.1	<0.01	<0.1	<0.05	<0.1	2.1	<1	0.5
DUP 1202617	QC		<0.001	<1	11	<0.01	12	<0.001	<20	0.07	0.004	0.07	<0.1	<0.01	<0.1	<0.05	<0.1	2.8	<1	0.5
Reference Materials																				
STD DS8	Standard		0.086	16	117	0.63	309	0.121	<20	0.94	0.099	0.45	2.4	0.22	5.4	0.17	2.1	4.9	5	5.0
STD DS8	Standard		0.077	12	120	0.61	301	0.105	20	0.92	0.087	0.43	2.7	0.21	5.8	0.17	1.9	5.3	5	5.2
STD OREAS45CA	Standard		0.041	15	693	0.14	166	0.138	<20	3.95	0.015	0.08	<0.1	0.02	<0.1	<0.05	37.1	<0.5	20	<0.2
STD OREAS45CA	Standard		0.040	15	717	0.14	150	0.122	<20	3.45	0.015	0.08	<0.1	0.03	<0.1	<0.05	35.0	<0.5	18	<0.2
STD OXC88	Standard																			
STD OXC88	Standard																			
STD OXC88	Standard																			
STD OXH82	Standard																			
STD OXH82	Standard																			
STD OXH82	Standard																			
STD OXC88 Expected																				
STD OXH82 Expected																				
STD DS8 Expected			0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected			0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000507.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		<2	<0.1	1.4	2.9	51	<0.1	4.1	4.5	579	1.99	<0.5	2.1	5.3	55	<0.1	<0.1	<0.1	40	0.51
G1	Prep Blank		<2	<0.1	1.7	2.9	51	<0.1	4.0	4.3	595	2.05	<0.5	0.9	4.6	64	<0.1	<0.1	<0.1	40	0.49

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000507.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																			
G1	Prep Blank	0.075	8	11	0.62	248	0.122	<20	1.10	0.113	0.52	<0.1	<0.01	0.3	<0.05	2.0	<0.5	6	<0.2
G1	Prep Blank	0.077	8	14	0.60	229	0.122	<20	1.09	0.102	0.48	<0.1	0.02	0.3	<0.05	1.8	<0.5	5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Submitted By: Bruce Durham
Receiving Lab: Canada-Whitehorse
Received: July 14, 2011
Report Date: September 02, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11000584.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID: July-5-2011
P.O. Number
Number of Samples: 41

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT Dispose of Reject After 90 days

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	41	Crush, split and pulverize 250 g rock to 200 mesh			WHI
3B	41	Fire assay fusion Au by ICP-ES	30	Completed	VAN
1DX	41	1:1:1 Aqua Regia digestion ICP-MS analysis	0.5	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Don Christie
Daithi Mac Gearailt
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000584.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1204194	Rock	0.45	<2	2.7	4.4	3.0	7	<0.1	0.9	0.8	57	0.59	0.6	<0.5	10.5	5	<0.1	<0.1	<0.1	<2	0.05
1204195	Rock	1.06	<2	<0.1	2.0	1.3	15	<0.1	1.4	3.2	100	0.95	1.0	<0.5	4.3	29	<0.1	<0.1	<0.1	6	0.40
1204196	Rock	1.02	<2	0.8	9.1	3.3	18	<0.1	0.9	2.1	106	0.94	<0.5	<0.5	5.1	41	<0.1	<0.1	<0.1	3	0.26
1204197	Rock	1.47	<2	0.5	3.6	5.9	4	<0.1	0.7	0.8	85	0.60	0.8	<0.5	11.5	8	<0.1	<0.1	<0.1	<2	0.07
1204198	Rock	1.05	<2	0.4	17.5	3.9	8	<0.1	0.9	1.3	103	0.59	1.0	<0.5	8.5	17	<0.1	<0.1	<0.1	2	0.17
1202287	Rock	0.49	<2	<0.1	66.8	5.0	76	<0.1	14.7	18.0	434	3.28	1.5	<0.5	0.4	39	0.2	0.5	<0.1	89	0.83
1202288	Rock	0.54	11	1.3	212.3	43.0	74	0.7	3.1	1.8	230	7.04	4.6	9.4	0.4	9	<0.1	1.3	2.3	71	0.06
1202289	Rock	0.51	<2	1.8	21.6	13.1	23	<0.1	15.8	2.6	37	0.70	12.0	<0.5	12.1	6	<0.1	0.3	<0.1	6	0.05
1202644	Rock	0.43	<2	<0.1	32.0	6.2	102	<0.1	20.0	29.4	1296	4.60	0.6	<0.5	1.5	95	0.3	<0.1	<0.1	129	2.71
1202645	Rock	0.55	<2	<0.1	46.4	8.0	92	<0.1	59.0	26.4	972	3.84	0.9	<0.5	0.3	47	0.2	0.1	<0.1	105	1.54
1202646	Rock	0.41	<2	<0.1	44.5	13.1	102	<0.1	77.4	20.7	1468	3.32	0.7	<0.5	0.6	96	0.6	<0.1	0.1	60	4.25
1202648	Rock	0.38	<2	0.7	11.9	49.6	47	0.4	1.9	1.3	93	0.36	2.6	0.7	27.3	5	0.1	0.1	0.2	<2	0.06
1202649	Rock	0.98	<2	0.4	2.4	4.5	9	<0.1	1.0	1.0	138	0.70	0.6	<0.5	7.1	13	<0.1	<0.1	<0.1	4	0.22
1202650	Rock	0.54	35	0.9	49.8	100.4	23	5.5	0.8	0.4	52	1.03	9.9	31.9	1.8	6	<0.1	0.2	4.6	<2	<0.01
1204201	Rock	1.13	<2	1.4	11.4	1.7	72	0.1	3.5	8.3	341	2.61	1.2	1.1	2.9	22	0.3	<0.1	<0.1	17	1.10
1204202	Rock	1.94	<2	0.3	10.3	8.4	9	<0.1	0.5	1.1	65	0.79	<0.5	2.8	8.0	6	<0.1	<0.1	0.2	3	0.06
1204203	Rock	1.34	<2	0.4	2.6	4.3	5	<0.1	0.4	0.6	57	0.54	<0.5	0.8	9.0	6	<0.1	<0.1	<0.1	<2	0.07
1204301	Rock	0.80	<2	0.6	6.4	3.9	15	<0.1	0.7	1.6	117	1.25	<0.5	0.6	8.6	6	<0.1	<0.1	<0.1	8	0.07
1203755	Rock	1.27	7	1.0	63.3	10.5	62	0.3	5.8	1.8	196	6.57	2.9	8.5	0.4	3	<0.1	<0.1	1.8	43	0.02
1203756	Rock	0.98	<2	0.2	19.9	1.7	11	<0.1	2.1	0.5	56	1.64	0.7	<0.5	0.1	3	<0.1	<0.1	0.6	9	<0.01
1203758	Rock	1.41	<2	0.3	1.8	4.1	3	<0.1	0.7	1.4	74	0.64	<0.5	<0.5	7.0	8	<0.1	<0.1	<0.1	3	0.09
1203759	Rock	1.18	<2	0.2	13.8	3.4	27	<0.1	7.8	12.3	357	2.07	1.3	1.0	0.3	70	<0.1	0.2	0.1	65	1.37
1203760	Rock	1.51	<2	0.2	9.8	0.3	6	<0.1	4.3	2.3	207	0.61	<0.5	<0.5	<0.1	7	<0.1	<0.1	<0.1	6	0.62
1203761	Rock	0.74	2	1.7	22.9	6.4	83	<0.1	15.8	11.6	623	8.44	2.4	1.4	1.0	25	0.2	<0.1	0.7	73	0.12
1203762	Rock	1.35	<2	0.3	174.7	3.1	36	0.3	6.5	13.4	1152	3.44	1.6	1.4	0.3	40	<0.1	<0.1	0.3	46	2.81
1203763	Rock	1.50	<2	0.2	35.4	3.3	13	<0.1	2.6	7.3	1032	2.29	1.9	0.7	0.3	31	<0.1	0.3	0.3	12	2.67
1203766	Rock	0.91	<2	0.8	7.2	5.4	3	<0.1	0.9	0.7	57	0.60	<0.5	<0.5	10.1	6	<0.1	<0.1	0.2	<2	0.11
1202293	Rock	0.61	<2	0.3	2.1	1.4	12	<0.1	1.6	3.3	287	0.82	1.2	<0.5	3.5	25	<0.1	0.1	<0.1	4	0.25
1202294	Rock	0.95	7	<0.1	47.0	2.7	82	<0.1	8.9	2.1	308	4.30	1.1	7.2	0.5	2	<0.1	<0.1	0.4	47	0.01
1202295	Rock	0.75	2	0.2	12.4	0.7	8	<0.1	1.7	0.6	62	1.03	0.9	0.8	<0.1	1	<0.1	<0.1	0.1	5	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000584.1

Method		1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
Analyte		P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
Unit		%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
MDL		0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1204194	Rock	0.003	2	1	0.02	51	0.005	<20	0.20	0.060	0.12	<0.1	<0.01	<0.1	<0.05	1.9	<0.5	1	<0.2
1204195	Rock	0.022	3	1	0.20	252	0.019	<20	0.64	0.053	0.14	<0.1	<0.01	<0.1	0.09	1.4	<0.5	2	<0.2
1204196	Rock	0.007	3	1	0.07	53	0.005	<20	0.46	0.070	0.06	<0.1	<0.01	<0.1	<0.05	1.2	<0.5	3	<0.2
1204197	Rock	0.005	8	1	0.02	118	0.005	<20	0.31	0.060	0.22	<0.1	0.01	<0.1	<0.05	1.5	<0.5	1	<0.2
1204198	Rock	0.007	4	2	0.02	208	0.003	<20	0.38	0.047	0.25	<0.1	<0.01	<0.1	<0.05	1.7	<0.5	2	<0.2
1202287	Rock	0.017	<1	14	1.73	105	0.046	<20	2.66	0.101	0.13	<0.1	<0.01	<0.1	0.07	4.7	<0.5	6	<0.2
1202288	Rock	0.043	1	14	0.71	182	0.004	<20	1.24	0.018	0.25	<0.1	0.03	<0.1	0.41	4.5	6.1	5	0.7
1202289	Rock	0.018	7	10	0.10	101	0.085	<20	0.45	0.022	0.35	<0.1	<0.01	0.1	<0.05	1.0	<0.5	1	<0.2
1202644	Rock	0.053	6	73	3.60	85	0.098	<20	3.11	0.019	0.12	<0.1	0.02	<0.1	<0.05	14.9	<0.5	9	<0.2
1202645	Rock	0.057	1	103	3.47	46	0.114	<20	3.15	0.020	0.05	<0.1	<0.01	<0.1	<0.05	5.0	<0.5	7	<0.2
1202646	Rock	0.050	3	110	3.01	65	0.046	<20	2.76	0.011	0.07	<0.1	<0.01	<0.1	<0.05	6.8	<0.5	6	<0.2
1202648	Rock	0.009	33	<1	0.08	29	0.002	<20	0.30	0.026	0.22	<0.1	0.02	<0.1	<0.05	0.3	<0.5	<1	<0.2
1202649	Rock	0.008	8	2	0.04	140	0.006	<20	0.39	0.045	0.25	<0.1	<0.01	<0.1	<0.05	1.5	<0.5	2	<0.2
1202650	Rock	0.007	3	2	<0.01	47	0.002	<20	0.13	0.008	0.06	<0.1	0.06	<0.1	<0.05	0.4	7.2	<1	0.4
1204201	Rock	0.047	5	2	0.70	251	0.040	<20	1.57	0.059	0.18	<0.1	<0.01	0.8	<0.05	2.4	<0.5	5	<0.2
1204202	Rock	0.006	3	1	0.03	127	0.006	<20	0.35	0.056	0.23	<0.1	<0.01	<0.1	<0.05	2.4	<0.5	2	<0.2
1204203	Rock	0.003	2	<1	<0.01	112	0.003	<20	0.28	0.051	0.19	<0.1	<0.01	<0.1	<0.05	1.5	<0.5	1	<0.2
1204301	Rock	0.010	4	1	0.08	112	0.005	<20	0.41	0.058	0.14	<0.1	<0.01	<0.1	<0.05	2.1	<0.5	3	<0.2
1203755	Rock	0.023	1	19	1.19	83	0.001	<20	1.37	0.009	0.10	<0.1	0.04	<0.1	<0.05	2.4	3.9	4	1.1
1203756	Rock	0.006	<1	8	0.23	148	<0.001	<20	0.27	0.005	0.03	<0.1	0.02	<0.1	<0.05	0.6	0.9	<1	0.3
1203758	Rock	0.010	9	2	0.02	117	0.020	<20	0.27	0.075	0.15	<0.1	<0.01	<0.1	<0.05	1.8	<0.5	1	<0.2
1203759	Rock	0.131	<1	5	0.88	16	0.152	<20	1.39	0.027	0.02	0.1	<0.01	<0.1	<0.05	3.6	<0.5	4	<0.2
1203760	Rock	0.007	<1	10	0.23	5	0.018	<20	0.23	0.007	<0.01	<0.1	0.01	<0.1	<0.05	0.4	<0.5	<1	<0.2
1203761	Rock	0.044	3	76	1.90	91	0.011	<20	2.21	0.039	0.05	<0.1	0.20	<0.1	0.10	6.5	4.0	7	0.6
1203762	Rock	0.033	<1	3	1.46	317	0.009	<20	1.01	0.089	0.03	<0.1	0.10	<0.1	0.43	7.4	<0.5	3	<0.2
1203763	Rock	0.027	<1	2	0.88	105	0.002	<20	0.34	0.027	0.04	<0.1	0.08	<0.1	0.60	5.0	<0.5	<1	<0.2
1203766	Rock	0.006	6	2	0.02	111	0.004	<20	0.30	0.045	0.23	<0.1	<0.01	<0.1	<0.05	0.9	<0.5	1	<0.2
1202293	Rock	0.018	7	2	0.11	188	0.042	<20	0.46	0.062	0.15	<0.1	<0.01	<0.1	<0.05	1.3	<0.5	2	<0.2
1202294	Rock	0.002	1	16	1.80	85	0.001	<20	2.16	0.012	0.13	<0.1	0.19	<0.1	<0.05	2.7	1.2	5	0.6
1202295	Rock	0.010	<1	3	0.16	37	<0.001	<20	0.21	0.005	0.02	<0.1	0.03	<0.1	<0.05	0.6	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000584.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
1202296	Rock	0.48	<2	0.1	1.5	1.0	2	<0.1	0.7	0.3	45	0.36	<0.5	<0.5	0.2	<1	<0.1	<0.1	<0.1	<2	<0.01
1202297	Rock	0.48	<2	0.5	9.5	3.9	17	<0.1	30.1	8.0	377	2.05	1.0	<0.5	4.0	56	<0.1	0.1	0.1	52	1.76
1202298	Rock	0.79	99	0.4	24.4	18.6	26	1.3	89.8	11.6	175	1.66	3.5	76.6	5.3	1027	<0.1	0.2	0.3	80	1.01
1202299	Rock	0.84	71	4.5	47.4	5.4	81	1.4	1.9	2.0	43	3.08	49.0	53.0	3.3	3	0.3	0.3	0.5	<2	0.07
1202300	Rock	0.48	<2	0.7	20.3	10.2	14	<0.1	14.6	5.9	88	0.73	1.5	1.6	0.6	13	<0.1	<0.1	0.2	7	0.15
1202391	Rock	0.83	13	1.4	41.0	76.6	71	0.2	32.4	7.9	581	1.90	107.4	8.4	3.6	10	0.4	0.4	0.4	18	0.12
1202392	Rock	0.59	4	0.5	17.7	33.7	39	0.3	35.3	17.8	234	3.29	10.1	3.7	17.4	11	0.6	1.7	1.3	59	0.18
1202393	Rock	0.56	4	1.6	79.5	63.6	113	0.3	44.6	18.6	782	2.55	50.8	2.8	5.2	13	0.5	0.3	0.8	24	0.28
1202394	Rock	0.52	<2	0.1	3.8	9.0	93	<0.1	24.1	10.2	558	2.71	<0.5	<0.5	5.4	85	0.4	<0.1	0.3	41	1.41
1203754	Rock	0.76	<2	0.1	12.7	0.4	19	<0.1	3.1	4.4	230	1.23	0.7	<0.5	<0.1	2	<0.1	<0.1	<0.1	12	0.07
1203768	Rock	1.08	<2	1.5	2.6	3.9	4	<0.1	0.3	0.2	26	0.38	1.1	<0.5	13.8	6	<0.1	<0.1	0.1	<2	<0.01

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: September 02, 2011

CERTIFICATE OF ANALYSIS WHI11000584.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
1202296	Rock	<0.001	<1	2	<0.01	27	<0.001	<20	0.05	0.004	0.04	<0.1	<0.01	<0.1	<0.05	0.1	<0.5	<1	<0.2
1202297	Rock	0.053	9	73	0.88	88	0.083	<20	2.38	0.209	0.35	<0.1	<0.01	<0.1	0.10	4.3	<0.5	6	<0.2
1202298	Rock	0.051	8	45	0.91	283	0.059	<20	2.39	0.127	0.58	<0.1	0.01	0.3	0.77	4.4	0.7	7	0.7
1202299	Rock	0.025	3	2	0.04	32	<0.001	<20	0.28	0.031	0.14	<0.1	0.06	<0.1	1.79	0.7	2.4	<1	<0.2
1202300	Rock	0.066	1	6	0.07	25	0.003	<20	0.21	0.032	0.06	<0.1	<0.01	<0.1	<0.05	0.6	<0.5	<1	<0.2
1202391	Rock	0.061	18	7	0.05	96	0.001	<20	0.34	0.002	0.20	<0.1	0.02	<0.1	<0.05	2.7	1.6	<1	<0.2
1202392	Rock	0.057	25	56	0.49	73	0.078	<20	0.88	0.058	0.12	<0.1	<0.01	<0.1	<0.05	4.8	2.1	6	0.4
1202393	Rock	0.130	21	18	0.05	112	0.003	<20	0.45	0.020	0.17	<0.1	0.01	<0.1	<0.05	3.8	2.7	1	<0.2
1202394	Rock	0.115	14	27	1.13	42	0.107	<20	1.88	0.083	0.09	0.2	<0.01	<0.1	<0.05	2.9	<0.5	8	<0.2
1203754	Rock	0.003	<1	3	0.33	27	0.022	<20	0.60	0.012	0.03	<0.1	<0.01	<0.1	<0.05	0.8	<0.5	1	<0.2
1203768	Rock	0.002	13	<1	0.02	22	0.001	<20	0.26	0.028	0.25	0.2	<0.01	<0.1	0.18	0.3	<0.5	<1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000584.1

	Method	WGHT	3B	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca
	Unit	kg	ppb	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%
	MDL	0.01	2	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01
Pulp Duplicates																					
REP G1	QC			0.1	4.3	3.4	49	<0.1	4.1	4.8	594	2.11	<0.5	<0.5	6.2	83	<0.1	<0.1	<0.1	41	0.57
1204201	Rock	1.13	<2	1.4	11.4	1.7	72	0.1	3.5	8.3	341	2.61	1.2	1.1	2.9	22	0.3	<0.1	<0.1	17	1.10
REP 1204201	QC			1.2	10.8	1.7	70	0.1	3.5	8.2	333	2.60	1.1	2.0	2.9	21	0.2	<0.1	<0.1	18	1.09
1203763	Rock	1.50	<2	0.2	35.4	3.3	13	<0.1	2.6	7.3	1032	2.29	1.9	0.7	0.3	31	<0.1	0.3	0.3	12	2.67
REP 1203763	QC		<2																		
1203768	Rock	1.08	<2	1.5	2.6	3.9	4	<0.1	0.3	0.2	26	0.38	1.1	<0.5	13.8	6	<0.1	<0.1	0.1	<2	<0.01
REP 1203768	QC			1.4	2.3	3.9	3	<0.1	0.4	0.2	25	0.44	1.1	<0.5	12.8	5	<0.1	<0.1	0.1	<2	<0.01
Core Reject Duplicates																					
1203758	Rock	1.41	<2	0.3	1.8	4.1	3	<0.1	0.7	1.4	74	0.64	<0.5	<0.5	7.0	8	<0.1	<0.1	<0.1	3	0.09
DUP 1203758	QC		<2	0.3	1.6	3.9	2	<0.1	0.8	1.3	70	0.60	<0.5	<0.5	6.8	8	<0.1	<0.1	<0.1	2	0.09
Reference Materials																					
STD DS8	Standard			14.5	113.1	127.3	309	1.9	38.6	7.4	596	2.41	26.1	115.6	7.0	65	2.2	3.5	6.5	41	0.69
STD DS8	Standard			13.4	118.6	128.9	317	1.6	40.3	7.7	616	2.49	25.6	98.1	7.0	74	2.5	4.0	6.6	44	0.73
STD DS8	Standard			13.1	119.6	130.0	332	1.8	41.9	8.2	653	2.65	26.4	100.8	7.3	80	2.3	5.0	7.2	45	0.78
STD OREAS45CA	Standard			0.8	495.1	20.7	61	0.3	244.8	90.4	910	16.05	3.0	38.0	7.0	15	0.1	0.1	0.2	209	0.42
STD OREAS45CA	Standard			0.8	540.5	20.4	61	0.3	258.5	91.1	916	15.69	3.1	40.2	7.2	18	<0.1	<0.1	0.2	217	0.41
STD OREAS45CA	Standard			0.8	515.6	22.0	68	0.3	260.6	91.2	957	17.19	3.8	38.5	7.9	17	<0.1	<0.1	0.2	208	0.46
STD OXC88	Standard		192																		
STD OXC88	Standard		200																		
STD OXC88	Standard		205																		
STD OXH82	Standard		1300																		
STD OXH82	Standard		1370																		
STD OXC88 Expected			203																		
STD OXH82 Expected			1278																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	4.8	6.67	41.1	0.7
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	43	7	15	0.1	0.13	0.19	215	0.4265
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank		<2																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000584.1

	Method	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX	1DX
	Analyte	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Tl	S	Sc	Se	Ga	Te
	Unit	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	MDL	0.001	1	1	0.01	1	0.001	20	0.01	0.001	0.01	0.1	0.01	0.1	0.05	0.1	0.5	1	0.2
Pulp Duplicates																			
REP G1	QC	0.077	10	8	0.62	248	0.157	<20	1.11	0.102	0.50	<0.1	<0.01	0.3	<0.05	2.3	<0.5	6	<0.2
1204201	Rock	0.047	5	2	0.70	251	0.040	<20	1.57	0.059	0.18	<0.1	<0.01	0.8	<0.05	2.4	<0.5	5	<0.2
REP 1204201	QC	0.045	5	2	0.69	247	0.039	<20	1.50	0.056	0.18	<0.1	<0.01	0.9	<0.05	2.4	<0.5	5	<0.2
1203763	Rock	0.027	<1	2	0.88	105	0.002	<20	0.34	0.027	0.04	<0.1	0.08	<0.1	0.60	5.0	<0.5	<1	<0.2
REP 1203763	QC																		
1203768	Rock	0.002	13	<1	0.02	22	0.001	<20	0.26	0.028	0.25	0.2	<0.01	<0.1	0.18	0.3	<0.5	<1	<0.2
REP 1203768	QC	0.002	12	<1	0.02	21	0.001	<20	0.23	0.028	0.22	0.1	<0.01	<0.1	0.18	0.2	<0.5	<1	<0.2
Core Reject Duplicates																			
1203758	Rock	0.010	9	2	0.02	117	0.020	<20	0.27	0.075	0.15	<0.1	<0.01	<0.1	<0.05	1.8	<0.5	1	<0.2
DUP 1203758	QC	0.010	9	1	0.01	115	0.021	<20	0.26	0.067	0.14	<0.1	<0.01	<0.1	<0.05	1.8	<0.5	<1	<0.2
Reference Materials																			
STD DS8	Standard	0.079	14	120	0.61	283	0.116	<20	0.90	0.091	0.40	2.6	0.19	5.2	0.16	2.1	5.8	5	4.8
STD DS8	Standard	0.075	13	122	0.62	297	0.123	<20	0.93	0.088	0.40	2.8	0.21	5.5	0.18	2.1	5.2	5	4.7
STD DS8	Standard	0.082	17	123	0.66	306	0.121	<20	1.01	0.107	0.45	2.2	0.25	5.5	0.18	2.4	4.8	5	4.9
STD OREAS45CA	Standard	0.038	15	701	0.14	162	0.136	<20	3.51	0.005	0.07	<0.1	0.03	<0.1	<0.05	37.7	<0.5	18	<0.2
STD OREAS45CA	Standard	0.035	14	696	0.14	159	0.146	<20	3.74	0.014	0.07	<0.1	0.03	<0.1	<0.05	37.7	0.5	17	<0.2
STD OREAS45CA	Standard	0.038	17	668	0.17	168	0.125	<20	3.93	0.010	0.08	<0.1	0.04	<0.1	<0.05	42.3	<0.5	19	<0.2
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXC88	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXC88 Expected																			
STD OXH82 Expected																			
STD DS8 Expected		0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	5.4	0.1679	2.3	5.23	4.7	5
STD OREAS45CA Expected		0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.03	0.07	0.021	39.7	0.5	18.4	
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000584.1

		WGHT Wgt kg 0.01	3B Au ppb 2	1DX Mo ppm 0.1	1DX Cu ppm 0.1	1DX Pb ppm 0.1	1DX Zn ppm 1	1DX Ag ppm 0.1	1DX Ni ppm 0.1	1DX Co ppm 0.1	1DX Mn ppm 1	1DX Fe % 0.01	1DX As ppm 0.5	1DX Au ppb 0.5	1DX Th ppm 0.1	1DX Sr ppm 1	1DX Cd ppm 0.1	1DX Sb ppm 0.1	1DX Bi ppm 0.1	1DX V ppm 2	1DX Ca % 0.01
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank		<2																		
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
BLK	Blank			<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01
Prep Wash																					
G1	Prep Blank		<2																		
G1	Prep Blank		<2	0.2	1.5	3.4	51	<0.1	3.9	4.7	612	2.12	1.6	<0.5	7.3	82	<0.1	<0.1	<0.1	41	0.57
G1	Prep Blank			0.1	4.1	3.6	50	<0.1	4.0	4.6	593	2.09	0.5	<0.5	5.6	82	<0.1	<0.1	<0.1	41	0.57

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: September 02, 2011

QUALITY CONTROL REPORT WHI11000584.1

		1DX P % 0.001	1DX La ppm 1	1DX Cr ppm 1	1DX Mg % 0.01	1DX Ba ppm 1	1DX Ti % 0.001	1DX B ppm 20	1DX Al % 0.01	1DX Na % 0.001	1DX K % 0.01	1DX W ppm 0.1	1DX Hg ppm 0.01	1DX Tl ppm 0.1	1DX S % 0.05	1DX Sc ppm 0.1	1DX Se ppm 0.5	1DX Ga ppm 1	1DX Te ppm 0.2
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
BLK	Blank	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.05	<0.1	<0.5	<1	<0.2
Prep Wash																			
G1	Prep Blank																		
G1	Prep Blank	0.074	10	8	0.62	238	0.153	<20	1.11	0.100	0.49	<0.1	<0.01	0.3	<0.05	2.1	<0.5	6	<0.2
G1	Prep Blank	0.075	9	8	0.62	236	0.157	<20	1.11	0.102	0.49	<0.1	0.01	0.3	<0.05	2.2	<0.5	6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Appendix 3B: Silt Sample Assay Certificates

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Submitted By: Daithi Mac Gerailt
Receiving Lab: Canada-Whitehorse
Received: June 29, 2011
Report Date: August 11, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11000338.1

CLIENT JOB INFORMATION

Project:
Shipment ID:
P.O. Number
Number of Samples: 28

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	28	Dry at 60C			WHI
SS80	28	Dry at 60C sieve 100g to -80 mesh			WHI
1DX2	28	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Don Christie
Bruce Durham
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000338.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202053	Silt	0.7	17.3	8.2	85	<0.1	19.9	12.1	666	2.26	3.2	2.5	2.5	30	0.4	0.2	0.1	47	0.61	0.065	15
1202069	Silt	0.5	18.6	3.3	50	<0.1	18.8	10.2	397	2.22	2.8	2.4	2.3	28	0.1	0.2	0.1	52	0.60	0.062	10
1202102	Silt	0.7	18.0	8.7	81	<0.1	20.6	11.9	634	2.35	3.6	0.8	4.3	16	0.3	0.1	0.1	33	0.34	0.056	12
1202105	Silt	0.4	28.7	6.3	73	0.1	41.0	13.0	557	2.42	4.0	1.3	2.6	47	0.3	0.3	0.1	50	1.24	0.061	15
1202126	Silt	0.4	18.0	3.5	49	<0.1	20.2	10.7	429	2.64	4.7	5.0	2.2	32	0.1	0.3	<0.1	64	0.68	0.076	9
1202137	Silt	0.5	17.4	3.3	50	<0.1	17.1	11.1	436	2.18	2.5	5.6	2.0	24	0.1	0.2	<0.1	46	0.52	0.057	10
1202138	Silt	0.7	22.8	5.7	61	<0.1	20.7	13.3	530	2.45	3.3	0.6	3.3	21	0.2	0.2	0.2	49	0.45	0.055	15
1202139	Silt	0.8	21.9	4.9	58	<0.1	19.1	13.3	486	2.33	2.8	1.1	3.4	17	0.2	0.2	0.2	48	0.39	0.051	13
1202140	Silt	0.7	24.2	6.2	64	<0.1	21.4	12.4	592	2.44	3.7	<0.5	2.6	28	0.2	0.2	0.2	57	0.57	0.056	22
1202141	Silt	0.7	19.9	5.5	58	<0.1	19.2	13.3	467	2.29	3.3	1.1	2.8	20	0.2	0.2	0.2	50	0.40	0.054	15
1202142	Silt	0.8	30.2	8.3	75	0.1	23.8	14.3	575	2.58	4.0	2.3	2.7	34	0.4	0.2	0.1	56	0.65	0.063	29
1202143	Silt	1.5	33.4	11.5	67	<0.1	27.8	15.2	678	2.76	3.6	7.1	4.6	20	0.2	0.2	0.3	54	0.48	0.054	34
1202144	Silt	0.8	19.4	6.5	59	<0.1	17.9	11.7	541	2.27	3.8	2.9	2.5	21	0.2	0.2	<0.1	57	0.38	0.056	14
1202182	Silt	1.0	18.6	8.1	81	<0.1	27.8	13.1	736	2.55	3.9	6.0	2.8	23	0.3	0.2	0.1	52	0.51	0.072	12
1202183	Silt	0.6	22.0	8.2	81	0.1	32.0	12.4	481	2.55	3.7	3.5	2.3	24	0.3	0.2	0.1	53	0.60	0.069	13
1202184	Silt	1.0	20.0	6.9	72	0.1	22.9	10.9	506	2.32	4.3	4.1	1.7	24	0.3	0.3	0.1	51	0.52	0.072	13
1202185	Silt	1.4	31.6	6.7	75	0.4	25.5	10.3	403	2.82	6.1	3.8	1.8	20	0.2	0.3	0.1	66	0.31	0.087	14
1202188	Silt	0.6	24.9	7.7	84	<0.1	44.1	13.1	502	2.58	4.0	3.4	3.1	35	0.4	0.3	<0.1	50	0.87	0.070	16
1202189	Silt	0.5	21.4	5.8	81	<0.1	45.4	13.3	562	2.40	3.4	2.1	2.7	37	0.4	0.2	<0.1	47	0.90	0.063	15
1202216	Silt	0.9	50.0	8.8	59	<0.1	49.3	16.1	264	3.05	5.5	3.4	6.7	27	0.2	0.3	0.2	89	0.47	0.070	25
1202251	Silt	0.6	30.1	6.3	98	<0.1	16.0	17.4	542	3.08	3.3	2.4	2.1	17	0.3	0.6	0.2	66	0.38	0.065	8
1202252	Silt	1.0	50.4	9.0	135	0.1	20.2	26.1	1515	3.62	4.7	2.9	2.3	22	0.7	0.5	0.3	65	0.47	0.057	9
1202253	Silt	0.8	46.3	12.2	135	0.1	18.4	22.6	839	3.33	4.0	2.6	2.2	21	0.5	0.6	0.3	66	0.42	0.057	9
1202682	Silt	1.5	28.4	11.1	54	<0.1	36.5	12.6	573	2.36	2.2	1.3	3.0	16	<0.1	0.3	0.2	46	0.43	0.065	8
1202686	Silt	1.7	42.5	26.9	70	<0.1	38.0	15.7	750	2.81	3.7	3.3	3.3	19	0.2	0.4	0.2	50	0.44	0.053	10
1202689	Silt	1.4	23.6	24.9	85	<0.1	28.3	15.8	977	2.59	6.3	3.6	5.6	35	0.4	0.3	0.1	49	0.52	0.125	20
1202690	Silt	1.3	34.5	30.7	88	<0.1	30.8	16.5	889	2.91	5.3	4.4	4.6	29	0.5	0.3	0.2	55	0.51	0.086	16
1203725	Silt	0.3	13.4	5.8	63	<0.1	22.9	10.8	288	2.32	2.2	1.8	5.7	30	0.1	0.1	<0.1	40	0.62	0.112	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000338.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202053	Silt	27	0.59	181	0.062	2	1.45	0.012	0.06	0.2	0.04	3.0	0.1	<0.05	5	0.5	<0.2
1202069	Silt	25	0.71	113	0.074	2	1.26	0.022	0.05	0.2	0.02	2.8	<0.1	<0.05	4	<0.5	<0.2
1202102	Silt	22	0.55	96	0.022	<1	1.05	0.005	0.09	<0.1	0.02	2.3	0.1	<0.05	3	0.7	<0.2
1202105	Silt	35	0.68	158	0.074	3	1.47	0.018	0.08	0.1	0.04	3.4	<0.1	<0.05	4	0.7	<0.2
1202126	Silt	27	0.70	107	0.095	2	1.32	0.026	0.05	0.2	0.03	3.2	<0.1	<0.05	4	<0.5	<0.2
1202137	Silt	25	0.82	103	0.065	<1	1.42	0.011	0.04	0.1	0.03	2.8	<0.1	<0.05	4	0.5	<0.2
1202138	Silt	31	0.95	124	0.055	<1	1.46	0.007	0.06	0.1	0.03	3.0	<0.1	<0.05	4	0.8	<0.2
1202139	Silt	29	0.88	114	0.048	1	1.33	0.006	0.07	0.2	0.02	3.0	<0.1	<0.05	4	<0.5	<0.2
1202140	Silt	31	0.73	202	0.065	1	1.64	0.010	0.07	0.1	0.04	3.8	<0.1	<0.05	5	0.8	<0.2
1202141	Silt	29	0.74	132	0.062	<1	1.38	0.006	0.06	0.2	0.02	3.0	<0.1	<0.05	4	0.5	<0.2
1202142	Silt	32	0.74	214	0.059	1	1.80	0.008	0.09	<0.1	0.06	4.0	<0.1	<0.05	5	1.4	<0.2
1202143	Silt	41	1.24	145	0.055	1	1.67	0.006	0.11	0.3	0.03	4.0	<0.1	<0.05	5	1.1	<0.2
1202144	Silt	28	0.58	184	0.064	<1	1.51	0.008	0.06	0.1	0.02	3.2	<0.1	<0.05	5	0.5	<0.2
1202182	Silt	34	0.75	179	0.065	1	1.64	0.009	0.07	<0.1	0.02	3.1	<0.1	<0.05	5	<0.5	<0.2
1202183	Silt	38	0.81	191	0.066	<1	1.66	0.009	0.07	0.2	0.04	3.2	<0.1	<0.05	5	<0.5	<0.2
1202184	Silt	32	0.60	221	0.059	1	1.63	0.010	0.05	0.1	0.06	3.3	<0.1	<0.05	5	0.7	<0.2
1202185	Silt	35	0.62	213	0.070	1	1.81	0.011	0.05	0.1	0.06	4.0	0.1	<0.05	6	0.6	<0.2
1202188	Silt	41	0.77	154	0.074	2	1.56	0.014	0.09	0.1	0.03	3.4	<0.1	<0.05	5	<0.5	<0.2
1202189	Silt	37	0.72	145	0.077	2	1.55	0.015	0.07	0.1	0.03	3.2	<0.1	<0.05	5	0.5	<0.2
1202216	Silt	79	1.11	234	0.169	1	2.55	0.027	0.21	0.2	0.05	6.0	0.1	<0.05	7	0.5	<0.2
1202251	Silt	23	0.80	91	0.061	<1	1.40	0.011	0.04	<0.1	0.09	2.8	<0.1	<0.05	4	0.7	<0.2
1202252	Silt	26	0.95	144	0.068	<1	1.78	0.014	0.07	0.1	0.19	3.8	<0.1	<0.05	5	0.7	<0.2
1202253	Silt	24	0.90	136	0.077	<1	1.78	0.013	0.07	<0.1	0.07	3.8	<0.1	<0.05	5	0.6	<0.2
1202682	Silt	80	1.26	72	0.042	<1	1.39	0.006	0.02	0.1	0.02	2.6	<0.1	<0.05	3	0.5	<0.2
1202686	Silt	83	1.34	94	0.048	1	1.58	0.007	0.04	<0.1	0.03	3.2	<0.1	<0.05	4	0.7	<0.2
1202689	Silt	39	0.98	156	0.064	1	1.34	0.008	0.07	0.2	0.03	2.9	<0.1	<0.05	4	<0.5	<0.2
1202690	Silt	48	1.15	156	0.053	<1	1.54	0.010	0.07	0.2	0.03	3.6	<0.1	<0.05	4	<0.5	<0.2
1203725	Silt	34	0.71	89	0.077	<1	1.43	0.009	0.25	0.1	0.01	2.5	0.2	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:

Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000338.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1202183	Silt	0.6	22.0	8.2	81	0.1	32.0	12.4	481	2.55	3.7	3.5	2.3	24	0.3	0.2	0.1	53	0.60	0.069	13
REP 1202183	QC	0.6	20.6	7.8	76	0.1	29.9	11.5	450	2.41	3.2	1.8	2.2	22	0.3	0.2	<0.1	49	0.54	0.064	12
1202251	Silt	0.6	30.1	6.3	98	<0.1	16.0	17.4	542	3.08	3.3	2.4	2.1	17	0.3	0.6	0.2	66	0.38	0.065	8
REP 1202251	QC	0.6	31.2	7.0	103	<0.1	18.7	18.2	570	3.24	3.6	1.6	2.2	18	0.3	0.6	0.2	70	0.40	0.068	8
Reference Materials																					
STD DS8	Standard	14.4	113.6	123.3	313	1.8	39.3	8.0	613	2.46	26.8	115.2	6.9	66	2.4	5.6	6.3	43	0.69	0.080	15
STD DS8	Standard	14.6	115.3	124.9	306	1.7	38.5	7.7	613	2.47	25.5	129.3	6.8	65	2.3	5.4	6.1	43	0.69	0.074	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:

Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000338.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1202183	Silt	38	0.81	191	0.066	<1	1.66	0.009	0.07	0.2	0.04	3.2	<0.1	<0.05	5	<0.5	<0.2
REP 1202183	QC	36	0.77	180	0.065	1	1.59	0.009	0.07	0.1	0.04	3.0	<0.1	<0.05	5	<0.5	<0.2
1202251	Silt	23	0.80	91	0.061	<1	1.40	0.011	0.04	<0.1	0.09	2.8	<0.1	<0.05	4	0.7	<0.2
REP 1202251	QC	25	0.88	97	0.066	<1	1.52	0.012	0.05	0.2	0.11	3.2	<0.1	0.06	4	<0.5	<0.2
Reference Materials																	
STD DS8	Standard	119	0.63	280	0.115	3	0.92	0.093	0.42	3.0	0.21	2.2	5.3	0.12	5	5.0	5.3
STD DS8	Standard	121	0.61	289	0.119	2	0.91	0.088	0.41	3.1	0.22	2.3	5.4	0.11	5	5.3	4.5
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Submitted By: Daithi Mac Gerailt
Receiving Lab: Canada-Whitehorse
Received: July 07, 2011
Report Date: August 11, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11000496.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID: July-1st-2011
P.O. Number
Number of Samples: 12

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	12	Dry at 60C			WHI
SS80	12	Dry at 60C sieve 100g to -80 mesh			WHI
1DX2	12	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Don Christie
Bruce Durham
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000496.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202214	Silt	0.5	14.6	5.4	51	<0.1	18.9	9.0	299	2.02	4.0	21.8	2.4	29	<0.1	0.2	<0.1	46	0.62	0.059	9
1202215	Silt	0.9	15.4	7.0	57	<0.1	18.0	10.0	445	2.01	4.5	2.3	2.6	22	0.2	0.2	0.1	41	0.38	0.049	13
1202216	Silt	0.8	15.5	7.3	56	<0.1	16.2	10.5	505	2.01	4.0	7.9	2.4	22	0.2	0.1	0.1	43	0.37	0.051	13
1202218	Silt	0.7	19.8	14.5	59	0.2	18.7	5.1	135	1.41	4.1	6.6	1.0	22	0.3	0.3	0.2	32	0.24	0.061	11
1202228	Silt	1.3	28.9	9.5	65	<0.1	26.8	16.2	647	2.70	4.2	3.1	4.1	22	0.3	0.2	0.3	60	0.42	0.053	25
1202229	Silt	0.9	30.5	8.6	70	<0.1	21.9	13.5	645	2.43	4.1	2.7	3.8	25	0.3	0.2	0.3	52	0.56	0.064	36
1202230	Silt	0.9	24.7	8.4	66	<0.1	20.8	12.0	582	2.31	4.5	3.7	1.9	28	0.2	0.2	0.1	56	0.52	0.055	20
1202255	Silt	1.5	18.6	9.1	73	<0.1	20.7	11.8	625	2.77	9.0	5.8	1.4	19	0.3	0.3	0.1	62	0.26	0.053	11
1203736	Silt	0.6	18.4	7.8	58	<0.1	18.3	11.8	375	2.07	2.8	0.8	3.4	19	<0.1	0.2	0.2	37	0.35	0.079	9
1203737	Silt	0.5	18.2	7.5	51	<0.1	17.3	11.2	354	2.07	3.2	1.2	3.3	20	0.1	0.1	0.1	40	0.39	0.097	9
1203739	Silt	0.4	23.3	9.7	65	<0.1	23.1	12.2	512	2.25	3.1	<0.5	2.7	20	0.1	0.2	0.1	44	0.41	0.086	9
1202615	Silt	0.4	19.8	8.3	61	<0.1	21.0	12.0	443	2.23	2.9	5.4	2.8	20	0.2	0.1	0.1	41	0.40	0.101	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000496.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202214	Silt	25	0.49	112	0.081	1	1.24	0.020	0.04	0.2	0.03	2.3	<0.1	<0.05	4	<0.5	<0.2
1202215	Silt	23	0.46	160	0.057	<1	1.18	0.013	0.05	0.1	0.02	2.2	<0.1	<0.05	3	<0.5	<0.2
1202216	Silt	22	0.44	151	0.060	1	1.19	0.013	0.06	0.1	0.03	2.3	<0.1	<0.05	3	0.6	<0.2
1202218	Silt	27	0.33	84	0.050	<1	1.12	0.012	0.04	<0.1	0.04	2.4	<0.1	<0.05	4	0.6	<0.2
1202228	Silt	40	1.10	160	0.070	<1	1.77	0.012	0.11	0.1	0.04	3.8	0.1	<0.05	5	0.6	<0.2
1202229	Silt	33	0.92	168	0.060	1	1.55	0.012	0.09	0.1	0.05	3.5	0.1	<0.05	4	<0.5	<0.2
1202230	Silt	31	0.62	214	0.062	<1	1.66	0.013	0.06	0.1	0.04	3.0	<0.1	<0.05	5	0.6	<0.2
1202255	Silt	26	0.48	204	0.047	<1	1.46	0.007	0.05	<0.1	0.03	2.3	<0.1	<0.05	5	1.1	<0.2
1203736	Silt	29	0.93	57	0.050	<1	1.13	0.007	0.04	0.1	0.02	2.3	<0.1	<0.05	3	<0.5	<0.2
1203737	Silt	28	0.83	55	0.051	<1	1.06	0.008	0.04	0.2	0.01	2.1	<0.1	<0.05	3	<0.5	<0.2
1203739	Silt	37	1.06	81	0.047	<1	1.28	0.008	0.04	<0.1	<0.01	2.8	<0.1	<0.05	4	<0.5	<0.2
1202615	Silt	33	1.00	71	0.046	<1	1.22	0.007	0.04	0.1	0.04	2.7	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000496.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1203737	Silt	0.5	18.2	7.5	51	<0.1	17.3	11.2	354	2.07	3.2	1.2	3.3	20	0.1	0.1	0.1	40	0.39	0.097	9
REP 1203737	QC	0.4	17.1	7.0	53	<0.1	17.9	11.4	356	2.12	3.1	1.5	3.3	20	<0.1	0.1	0.1	40	0.40	0.098	9
Reference Materials																					
STD DS8	Standard	12.9	109.6	128.4	301	1.8	36.5	7.1	567	2.27	25.8	109.5	6.8	61	2.0	5.4	6.4	40	0.63	0.078	13
STD DS8	Standard	13.4	111.6	124.1	314	1.8	39.0	7.8	610	2.45	26.6	103.9	6.5	64	2.4	5.4	6.2	43	0.69	0.080	14
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000496.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1203737	Silt	28	0.83	55	0.051	<1	1.06	0.008	0.04	0.2	0.01	2.1	<0.1	<0.05	3	<0.5	<0.2
REP 1203737	QC	28	0.86	56	0.054	<1	1.08	0.009	0.04	0.2	<0.01	2.2	<0.1	<0.05	3	<0.5	<0.2
Reference Materials																	
STD DS8	Standard	113	0.59	263	0.110	2	0.85	0.082	0.40	2.9	0.23	1.9	5.5	0.13	4	4.8	4.9
STD DS8	Standard	121	0.60	260	0.119	3	0.90	0.083	0.39	2.9	0.18	2.0	5.3	0.17	4	5.0	4.7
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Submitted By: Bruce Durham
Receiving Lab: Canada-Whitehorse
Received: July 18, 2011
Report Date: August 09, 2011
Page: 1 of 2

CERTIFICATE OF ANALYSIS WHI11000644.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID: July-5-2011
P.O. Number
Number of Samples: 19

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	17	Dry at 60C			WHI
SS80	17	Dry at 60C sieve 100g to -80 mesh			WHI
1DX2	15	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Don Christie
Daithi Mac Gearailt
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000644.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202230	Silt	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202274	Silt	1.0	14.6	9.3	68	<0.1	21.0	12.7	746	2.27	2.6	<0.5	3.3	17	0.2	0.1	0.2	44	0.29	0.058	10
1202290	Silt	1.1	33.5	28.3	88	0.2	23.2	17.4	840	3.15	4.3	1.0	2.5	38	0.5	0.4	0.3	69	0.68	0.065	15
1204291	Silt	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202630	Silt	0.7	11.1	5.2	45	<0.1	13.3	9.0	494	1.84	3.8	2.3	2.1	19	0.1	0.2	<0.1	42	0.31	0.052	9
1202634	Silt	0.7	13.2	5.8	52	<0.1	14.9	8.0	436	1.80	3.3	2.3	1.2	22	0.2	0.2	<0.1	38	0.32	0.055	10
1202641	Silt	1.1	12.6	33.5	85	<0.1	11.9	6.5	292	1.65	2.6	4.9	5.0	18	0.3	0.2	0.3	34	0.25	0.037	18
1202643	Silt	0.3	62.1	12.9	86	0.1	25.2	13.0	714	2.81	2.5	1.8	1.6	31	0.3	0.3	0.2	54	1.06	0.053	13
1202659	Silt	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203145	Silt	1.0	16.9	9.1	66	<0.1	23.2	14.9	728	2.68	3.7	1.0	2.9	16	<0.1	0.2	<0.1	41	0.37	0.066	8
1203759	Silt	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203753	Silt	0.7	29.3	32.1	98	0.3	24.5	12.8	556	2.53	3.1	1211	4.4	24	0.3	0.3	0.2	42	0.48	0.066	13
1203753	Silt	0.8	32.5	24.6	107	<0.1	24.3	18.1	1061	2.80	3.6	2.7	3.9	34	0.7	0.2	0.2	52	0.53	0.066	16
1203757	Silt	0.7	27.7	7.8	53	0.2	16.6	10.5	424	2.54	3.5	2.3	1.9	22	0.1	0.3	0.2	47	0.44	0.044	9
1203764	Silt	0.6	12.7	4.8	43	<0.1	13.7	7.9	366	1.82	3.4	6.6	2.1	17	0.2	0.2	0.1	39	0.33	0.041	9
1203765	Silt	0.6	16.0	5.4	45	<0.1	17.0	10.4	442	2.14	4.4	8.3	2.2	33	0.2	0.2	0.1	51	0.56	0.043	11
1203659	Silt	0.7	43.1	9.9	125	0.1	30.6	19.3	803	2.81	3.4	41.5	2.3	20	0.5	0.1	0.2	61	0.39	0.065	14
1202759	Silt	0.3	18.6	4.8	42	<0.1	27.8	7.1	147	1.79	3.8	8.5	2.5	18	0.1	0.1	0.2	45	0.31	0.048	10
1203769	Silt	0.9	12.6	29.7	79	<0.1	12.2	6.8	284	1.61	2.7	3.6	4.7	16	0.2	0.2	0.3	40	0.25	0.037	18

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000644.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202230	Silt	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202274	Silt	39	1.04	90	0.060	<1	1.39	0.007	0.05	0.1	0.02	2.5	<0.1	0.05	4	<0.5	<0.2
1202290	Silt	33	1.02	229	0.112	<1	2.19	0.022	0.12	0.2	0.05	4.9	0.1	0.12	6	0.5	<0.2
1204291	Silt	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202630	Silt	19	0.41	129	0.060	<1	1.25	0.011	0.04	0.1	0.02	2.6	<0.1	<0.05	4	<0.5	<0.2
1202634	Silt	22	0.42	173	0.058	<1	1.39	0.011	0.04	<0.1	0.02	2.3	<0.1	0.06	4	<0.5	<0.2
1202641	Silt	18	0.43	109	0.064	<1	1.03	0.010	0.05	0.1	0.02	2.0	<0.1	<0.05	4	0.7	<0.2
1202643	Silt	43	1.45	111	0.029	2	2.11	0.010	0.04	<0.1	0.05	5.9	<0.1	0.06	5	<0.5	<0.2
1202659	Silt	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203145	Silt	30	1.25	88	0.052	<1	1.56	0.005	0.05	<0.1	0.01	2.7	<0.1	<0.05	5	<0.5	<0.2
1203759	Silt	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203753	Silt	45	1.14	99	0.059	1	1.52	0.011	0.05	<0.1	0.04	3.1	<0.1	0.06	4	0.5	<0.2
1203753	Silt	39	1.25	143	0.072	<1	1.60	0.008	0.10	0.1	0.03	3.7	<0.1	0.05	5	<0.5	<0.2
1203757	Silt	26	0.73	152	0.061	<1	1.73	0.011	0.04	<0.1	0.11	3.5	<0.1	<0.05	5	<0.5	<0.2
1203764	Silt	20	0.38	128	0.055	1	1.19	0.010	0.04	0.1	0.02	2.3	<0.1	<0.05	4	<0.5	<0.2
1203765	Silt	26	0.37	185	0.067	1	1.53	0.013	0.06	0.1	0.03	3.0	<0.1	<0.05	4	<0.5	<0.2
1203659	Silt	52	1.26	142	0.071	1	1.77	0.009	0.09	0.2	0.04	3.9	0.1	<0.05	5	<0.5	<0.2
1202759	Silt	42	0.58	118	0.081	<1	1.28	0.014	0.08	<0.1	0.03	2.7	0.1	<0.05	4	<0.5	<0.2
1203769	Silt	19	0.38	110	0.059	1	1.06	0.012	0.04	0.2	0.04	2.0	<0.1	<0.05	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000644.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1203659	Silt	0.7	43.1	9.9	125	0.1	30.6	19.3	803	2.81	3.4	41.5	2.3	20	0.5	0.1	0.2	61	0.39	0.065	14
REP 1203659	QC	0.7	41.4	9.6	122	<0.1	30.8	19.5	763	2.77	3.0	6.9	2.1	22	0.5	0.2	0.2	58	0.38	0.060	13
Reference Materials																					
STD DS8	Standard	13.5	114.7	121.1	310	1.7	39.3	8.1	626	2.54	27.7	118.5	6.6	65	2.4	5.3	6.0	42	0.68	0.079	15
STD DS8	Standard	12.0	114.1	118.4	293	1.6	39.7	7.6	608	2.36	25.3	112.3	6.5	61	2.2	5.3	5.8	35	0.67	0.080	14
STD DS8	Standard	11.5	99.8	120.5	299	1.7	33.1	6.8	552	2.25	26.3	96.4	6.2	65	2.0	5.1	6.7	36	0.64	0.077	13
STD DS8	Standard	12.3	103.8	125.9	304	1.9	36.1	7.3	596	2.43	26.6	115.4	7.0	71	2.3	5.7	7.1	35	0.68	0.076	14
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	0.6	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000644.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1203659	Silt	52	1.26	142	0.071	1	1.77	0.009	0.09	0.2	0.04	3.9	0.1	<0.05	5	<0.5	<0.2
REP 1203659	QC	49	1.26	138	0.065	<1	1.79	0.009	0.09	0.1	0.04	3.7	0.1	<0.05	5	<0.5	<0.2
Reference Materials																	
STD DS8	Standard	125	0.60	287	0.114	2	0.92	0.092	0.43	2.8	0.21	2.2	5.6	0.16	5	5.1	4.8
STD DS8	Standard	116	0.58	271	0.113	3	0.90	0.092	0.43	2.8	0.19	2.1	5.6	0.12	5	4.5	4.4
STD DS8	Standard	107	0.58	256	0.101	2	0.84	0.093	0.42	2.8	0.18	2.4	5.0	0.17	5	4.6	3.8
STD DS8	Standard	113	0.59	269	0.113	2	0.92	0.106	0.43	3.1	0.19	2.5	5.2	0.16	5	4.2	5.4
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Appendix 3C: Soil Sample Assay Certificates

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Submitted By: Bruce Durham
Receiving Lab: Canada-Whitehorse
Received: June 22, 2011
Report Date: August 09, 2011
Page: 1 of 7

CERTIFICATE OF ANALYSIS WHI11000291.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID: VIP
P.O. Number
Number of Samples: 151

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	145	Dry at 60C			WHI
SS80	145	Dry at 60C sieve 100g to -80 mesh			WHI
1DX2	145	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Daithi Mac Gearailt
Don Christie
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000291.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202301	Soil	1.6	19.2	7.4	28	0.2	10.3	5.2	121	2.15	5.0	4.0	0.3	15	0.1	0.5	0.2	67	0.17	0.052	5
1202303	Soil	0.8	47.5	8.0	64	0.1	32.2	14.9	408	3.23	6.8	5.3	2.1	21	0.1	0.4	0.2	77	0.36	0.063	11
1202304	Soil	0.8	52.5	6.9	67	0.1	43.7	19.9	688	3.52	6.0	1.8	1.9	21	0.1	0.3	0.1	82	0.39	0.059	9
1202305	Soil	1.3	48.6	9.6	71	0.1	42.9	22.7	1083	4.06	8.7	3.9	2.4	20	<0.1	0.4	0.2	80	0.40	0.066	12
1202306	Soil	1.0	45.1	8.3	62	0.1	38.3	18.9	725	3.46	7.3	2.9	2.4	21	<0.1	0.3	0.2	79	0.39	0.054	10
1202307	Soil	1.0	35.9	6.2	64	0.2	33.4	15.3	731	3.07	5.1	3.2	1.2	34	0.2	0.3	0.1	69	0.92	0.077	9
1202308	Soil	0.8	36.5	6.4	66	0.1	35.6	16.6	673	3.28	6.2	3.2	1.7	26	0.2	0.4	0.1	76	0.64	0.059	10
1202309	Soil	0.9	51.2	8.6	75	0.2	40.4	19.3	911	3.75	6.3	3.8	3.4	31	0.2	0.3	0.2	76	0.65	0.057	15
1202310	Soil	1.0	31.7	6.4	56	0.2	21.8	9.6	321	2.36	4.2	2.3	0.9	29	0.2	0.3	0.1	52	0.72	0.084	12
1202311	Soil	0.9	37.5	8.2	80	0.2	27.0	11.4	418	2.43	5.3	3.6	1.0	44	0.3	0.4	0.2	54	1.40	0.080	14
1202312	Soil	1.1	27.7	10.8	59	0.2	24.3	13.4	704	2.40	4.9	1.4	1.3	34	0.2	0.3	0.2	55	1.15	0.065	12
1202313	Soil	1.4	36.9	14.9	88	0.2	30.3	18.5	1446	3.25	7.1	2.6	1.7	36	0.3	0.3	0.2	64	1.21	0.084	14
1202314	Soil	1.0	39.7	15.6	69	0.2	26.0	13.5	1038	2.56	6.0	3.4	1.4	44	0.5	0.5	0.2	50	1.59	0.080	22
1202316	Soil	1.1	37.9	25.2	99	0.2	26.5	15.1	912	2.86	7.5	3.3	2.1	34	0.3	0.3	0.2	53	1.16	0.078	16
1202317	Soil	1.0	41.4	23.4	91	0.3	28.1	14.7	844	2.76	7.3	6.2	2.0	38	0.3	0.4	0.3	53	1.27	0.072	21
1202318	Soil	1.1	37.6	16.8	81	0.2	27.2	15.3	886	2.89	7.1	3.4	2.0	30	0.3	0.3	0.2	58	0.97	0.074	15
1202319	Soil	0.9	37.2	17.4	82	0.2	28.2	15.7	971	2.93	7.0	4.7	2.4	33	0.2	0.3	0.2	61	1.01	0.069	17
1202320	Soil	0.8	33.7	14.2	75	0.2	26.1	14.6	732	2.78	6.1	3.1	2.3	32	0.3	0.3	0.2	57	0.99	0.063	14
1202321	Soil	1.5	20.3	7.2	51	<0.1	20.0	8.3	313	2.62	6.5	2.2	1.6	23	0.4	0.5	0.1	74	0.37	0.066	8
1202322	Soil	1.6	22.5	12.7	64	<0.1	21.9	10.0	554	3.00	7.7	1.6	1.9	17	0.2	0.6	0.2	75	0.21	0.064	12
1202323	Soil	0.9	15.7	7.7	42	<0.1	15.5	6.7	300	2.27	5.0	1.9	1.5	17	0.1	0.3	0.1	60	0.24	0.047	12
1202324	Soil	0.5	11.1	4.1	27	<0.1	10.3	5.0	196	1.57	2.5	1.3	0.7	10	<0.1	0.2	<0.1	45	0.17	0.034	5
1202325	Soil	0.9	24.3	9.0	58	0.1	20.7	7.6	354	2.60	5.5	4.1	1.3	28	0.2	0.4	0.2	69	0.48	0.093	26
1202326	Soil	0.9	27.9	9.6	69	0.1	27.7	11.7	603	3.00	7.1	3.4	2.9	33	0.2	0.4	0.1	78	0.61	0.081	30
1202327	Soil	1.1	20.7	9.0	54	<0.1	23.7	13.8	625	3.26	7.3	6.8	2.6	25	0.2	0.3	0.2	87	0.38	0.051	11
1202328	Soil	0.5	8.8	2.4	11	<0.1	4.7	2.1	51	0.76	1.1	0.5	0.2	21	<0.1	0.1	<0.1	18	0.32	0.054	12
1202329	Soil	1.0	30.7	8.3	63	0.1	26.9	12.4	624	2.99	6.7	2.7	2.1	29	0.1	0.4	0.1	79	0.47	0.078	23
1202302	Soil	1.1	66.7	10.6	53	0.2	30.2	16.2	236	2.75	5.6	5.4	2.4	23	<0.1	0.4	0.2	77	0.42	0.078	11
1202331	Soil	0.7	23.0	7.8	62	0.1	22.8	10.5	606	2.62	5.3	1.7	2.5	28	0.2	0.3	0.1	72	0.50	0.071	21
1202332	Soil	1.1	20.4	6.2	45	0.1	17.7	6.2	220	2.25	4.9	2.4	1.0	28	0.1	0.4	0.1	62	0.39	0.067	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000291.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202301	Soil	24	0.22	64	0.055	2	1.16	0.010	0.03	<0.1	0.07	1.7	<0.1	0.09	6	<0.5	<0.2
1202303	Soil	50	0.99	148	0.099	2	2.50	0.016	0.06	0.1	0.04	4.9	<0.1	<0.05	8	<0.5	<0.2
1202304	Soil	74	1.28	149	0.094	2	2.66	0.013	0.05	<0.1	0.05	4.9	0.1	<0.05	7	<0.5	<0.2
1202305	Soil	60	1.22	155	0.079	1	2.73	0.016	0.06	<0.1	0.04	4.9	<0.1	<0.05	8	<0.5	<0.2
1202306	Soil	58	1.08	163	0.083	1	2.43	0.017	0.05	0.1	0.03	4.6	<0.1	<0.05	7	<0.5	<0.2
1202307	Soil	58	1.08	203	0.063	2	2.33	0.026	0.05	<0.1	0.05	3.9	0.1	0.06	7	<0.5	<0.2
1202308	Soil	57	1.12	261	0.082	2	2.42	0.021	0.06	0.1	0.03	4.6	<0.1	<0.05	7	<0.5	<0.2
1202309	Soil	59	1.30	187	0.081	2	2.51	0.025	0.05	0.1	0.04	6.0	<0.1	<0.05	7	<0.5	<0.2
1202310	Soil	41	0.71	150	0.054	2	1.78	0.023	0.05	0.1	0.07	3.7	<0.1	0.12	5	<0.5	<0.2
1202311	Soil	40	0.74	189	0.054	3	1.72	0.027	0.07	0.1	0.09	3.7	<0.1	0.11	6	<0.5	<0.2
1202312	Soil	38	0.73	163	0.051	2	1.73	0.026	0.05	<0.1	0.06	3.6	<0.1	0.10	5	<0.5	<0.2
1202313	Soil	45	0.99	191	0.049	2	2.13	0.024	0.06	<0.1	0.06	4.5	<0.1	0.08	6	<0.5	<0.2
1202314	Soil	35	0.74	178	0.040	2	1.89	0.025	0.05	<0.1	0.08	3.7	<0.1	0.11	5	<0.5	<0.2
1202316	Soil	36	0.88	150	0.044	1	1.88	0.021	0.06	<0.1	0.07	3.7	<0.1	0.08	5	<0.5	<0.2
1202317	Soil	36	0.86	169	0.047	2	1.95	0.022	0.06	<0.1	0.07	3.9	<0.1	0.07	6	<0.5	<0.2
1202318	Soil	38	1.03	120	0.054	2	2.03	0.020	0.05	<0.1	0.05	4.0	<0.1	0.08	6	0.6	<0.2
1202319	Soil	38	0.93	169	0.058	2	1.96	0.022	0.05	<0.1	0.05	4.1	<0.1	0.07	6	0.5	<0.2
1202320	Soil	37	0.96	131	0.060	2	1.92	0.023	0.05	<0.1	0.04	4.0	<0.1	0.06	5	<0.5	<0.2
1202321	Soil	31	0.46	165	0.087	2	1.39	0.021	0.08	0.1	0.07	2.7	<0.1	0.08	6	<0.5	<0.2
1202322	Soil	36	0.51	170	0.072	1	1.72	0.014	0.07	0.1	0.03	2.7	<0.1	<0.05	7	0.6	<0.2
1202323	Soil	24	0.37	151	0.074	1	1.44	0.020	0.06	0.1	0.04	2.5	<0.1	<0.05	6	0.5	<0.2
1202324	Soil	17	0.22	56	0.071	<1	0.78	0.020	0.04	0.1	0.02	1.2	<0.1	<0.05	3	<0.5	<0.2
1202325	Soil	36	0.47	352	0.063	1	1.95	0.023	0.07	0.2	0.06	3.9	<0.1	0.08	6	0.5	<0.2
1202326	Soil	39	0.63	359	0.090	2	2.44	0.027	0.09	0.1	0.06	5.0	<0.1	0.05	6	<0.5	<0.2
1202327	Soil	37	0.58	277	0.106	1	2.21	0.019	0.08	0.1	0.03	3.5	<0.1	<0.05	7	0.5	<0.2
1202328	Soil	9	0.08	217	0.027	<1	0.56	0.027	0.02	<0.1	0.03	1.0	<0.1	0.08	2	<0.5	<0.2
1202329	Soil	42	0.59	336	0.083	2	2.55	0.022	0.07	0.1	0.05	5.5	<0.1	<0.05	7	<0.5	<0.2
1202302	Soil	43	0.84	151	0.109	1	2.52	0.020	0.05	0.2	0.07	4.6	<0.1	<0.05	7	<0.5	<0.2
1202331	Soil	38	0.59	287	0.089	2	1.97	0.020	0.07	0.1	0.04	4.3	<0.1	<0.05	6	<0.5	<0.2
1202332	Soil	29	0.39	217	0.074	1	1.48	0.020	0.07	0.2	0.07	2.8	<0.1	0.08	5	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000291.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202333	Soil	0.9	27.7	7.4	54	<0.1	27.1	11.1	403	2.80	5.5	4.6	2.5	21	0.2	0.3	0.1	76	0.34	0.060	12
1202334	Soil	1.1	23.8	25.1	69	<0.1	26.1	10.3	398	2.73	5.8	6.4	2.8	27	0.1	0.3	0.1	77	0.42	0.049	13
1202335	Soil	1.0	24.4	5.8	29	0.3	14.9	8.1	446	1.75	3.0	2.6	0.4	19	0.2	0.2	0.1	43	0.24	0.062	13
1202336	Soil	0.8	13.8	8.0	24	0.1	9.1	3.4	103	1.21	2.1	1.2	0.6	13	0.2	0.2	0.1	41	0.15	0.028	5
1202337	Soil	1.2	26.3	10.6	50	0.2	20.1	9.6	420	2.31	5.7	5.3	1.0	28	0.2	0.3	0.1	62	0.45	0.074	25
1202338	Soil	0.9	16.2	10.3	46	0.1	17.7	7.0	204	2.16	4.6	3.0	2.0	17	0.2	0.3	0.2	59	0.25	0.047	10
1202339	Soil	1.1	16.9	8.1	61	0.1	21.2	7.6	230	2.40	6.4	1.5	1.9	22	0.3	0.3	0.2	65	0.36	0.036	9
1202340	Soil	1.6	25.5	14.0	52	0.2	19.5	12.8	514	3.24	7.8	1.9	2.6	15	0.3	0.4	0.2	83	0.16	0.033	10
1202341	Soil	1.1	13.8	7.6	38	0.1	11.8	4.7	172	1.72	6.6	2.8	0.6	13	0.3	0.3	0.2	50	0.18	0.045	5
1202342	Soil	1.7	17.1	13.3	50	0.1	16.7	25.7	1306	3.04	8.3	1.8	1.8	21	0.3	0.4	0.2	78	0.26	0.039	7
1202343	Soil	1.1	29.8	8.9	62	0.2	17.4	11.1	524	2.39	5.8	4.0	1.1	24	0.3	0.3	0.1	59	0.31	0.047	14
1202344	Soil	1.2	18.9	9.9	47	0.1	16.8	7.4	297	2.68	7.2	7.5	1.9	15	0.4	0.4	0.2	81	0.17	0.038	10
1202345	Soil	0.6	22.0	6.4	54	<0.1	22.6	10.5	440	2.56	5.0	2.5	3.2	20	0.2	0.3	0.1	71	0.37	0.059	11
1202346	Soil	0.7	17.1	5.4	21	0.1	9.5	6.2	213	1.09	2.5	1.2	0.4	14	0.2	0.2	0.1	29	0.15	0.035	12
1202347	Soil	0.7	17.9	7.4	46	<0.1	18.5	8.2	199	2.05	3.7	5.0	3.1	24	0.2	0.3	<0.1	53	0.57	0.057	13
1202401	Soil	0.7	24.4	11.9	58	<0.1	23.7	11.5	330	2.80	5.3	2.6	3.7	25	0.1	0.4	0.1	70	0.31	0.049	14
1202402	Soil	1.2	29.5	10.9	59	0.1	30.8	11.2	268	2.92	5.0	3.0	4.3	32	0.1	0.3	0.1	71	0.40	0.054	13
1202403	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202404	Soil	0.5	8.3	6.8	19	0.1	6.5	2.7	60	0.78	1.2	<0.5	0.3	14	<0.1	0.2	<0.1	21	0.14	0.040	4
1202405	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202406	Soil	0.9	18.5	7.4	40	0.2	14.5	5.4	146	1.76	3.7	1.3	0.8	20	0.2	0.4	0.1	44	0.22	0.068	10
1202407	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202408	Soil	0.8	12.0	11.3	58	0.1	18.5	8.3	207	1.90	2.6	3.9	1.6	21	0.1	0.2	0.1	45	0.26	0.046	7
1202409	Soil	0.8	23.7	9.0	49	0.1	12.9	7.4	198	2.36	3.2	3.5	0.8	19	0.2	0.3	0.2	56	0.20	0.052	6
1202410	Soil	0.8	26.1	17.7	61	0.1	14.5	8.7	254	2.72	3.3	3.9	1.1	20	<0.1	0.3	0.2	71	0.19	0.048	6
1202411	Soil	0.8	25.6	8.4	54	<0.1	20.7	11.2	484	2.06	4.1	1.5	1.0	41	0.3	0.3	0.1	39	1.61	0.063	6
1202412	Soil	0.8	38.1	16.0	73	0.2	27.6	15.6	829	2.64	5.5	2.4	2.2	33	0.3	0.3	0.2	53	1.21	0.062	12
1202413	Soil	0.6	16.5	7.2	45	<0.1	19.4	8.4	407	1.84	3.0	2.6	2.2	28	0.1	0.3	<0.1	49	0.61	0.058	11
1202414	Soil	0.8	21.9	8.7	62	0.3	18.5	6.8	311	1.94	3.2	2.9	0.6	28	0.4	0.3	0.2	46	0.49	0.080	15
1202415	Soil	1.1	29.9	5.9	55	0.2	13.8	11.0	990	1.27	3.1	0.6	0.3	15	0.8	0.3	0.1	36	0.20	0.051	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000291.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202333	Soil	40	0.66	167	0.109	1	2.08	0.017	0.07	0.1	0.03	3.9	<0.1	<0.05	6	0.5	<0.2
1202334	Soil	38	0.60	213	0.111	1	1.87	0.022	0.08	0.1	0.05	3.4	<0.1	<0.05	6	<0.5	<0.2
1202335	Soil	24	0.28	152	0.044	<1	1.50	0.024	0.04	<0.1	0.06	1.9	<0.1	<0.05	5	<0.5	<0.2
1202336	Soil	16	0.17	78	0.060	<1	0.66	0.021	0.05	<0.1	0.04	1.2	<0.1	<0.05	4	<0.5	<0.2
1202337	Soil	31	0.42	244	0.070	1	1.76	0.029	0.07	0.1	0.06	3.5	<0.1	0.06	6	<0.5	<0.2
1202338	Soil	30	0.39	161	0.071	2	1.53	0.015	0.05	0.1	0.05	2.4	<0.1	<0.05	5	<0.5	<0.2
1202339	Soil	32	0.47	168	0.078	2	1.74	0.013	0.06	0.1	0.04	2.5	<0.1	<0.05	6	<0.5	<0.2
1202340	Soil	34	0.37	182	0.060	<1	2.52	0.011	0.04	0.1	0.05	3.1	0.1	<0.05	8	<0.5	<0.2
1202341	Soil	19	0.22	99	0.050	1	1.08	0.013	0.04	<0.1	0.05	1.4	<0.1	<0.05	5	<0.5	<0.2
1202342	Soil	30	0.37	145	0.075	1	1.86	0.016	0.06	<0.1	0.04	2.3	<0.1	<0.05	8	<0.5	<0.2
1202343	Soil	28	0.33	205	0.058	2	1.89	0.018	0.06	<0.1	0.05	2.9	<0.1	<0.05	6	<0.5	<0.2
1202344	Soil	26	0.35	175	0.068	2	1.51	0.010	0.05	0.1	0.03	2.4	<0.1	<0.05	7	<0.5	<0.2
1202345	Soil	32	0.49	156	0.098	1	1.54	0.017	0.04	<0.1	0.02	2.9	<0.1	<0.05	4	<0.5	<0.2
1202346	Soil	15	0.14	93	0.033	<1	1.00	0.019	0.03	<0.1	0.03	1.5	<0.1	<0.05	3	<0.5	<0.2
1202347	Soil	31	0.45	205	0.084	2	1.59	0.021	0.04	0.1	0.05	3.2	<0.1	<0.05	4	<0.5	<0.2
1202401	Soil	44	0.84	229	0.111	1	2.69	0.018	0.12	<0.1	0.02	3.8	0.1	<0.05	7	<0.5	<0.2
1202402	Soil	55	0.89	255	0.128	2	2.79	0.019	0.15	0.1	0.02	4.9	0.1	<0.05	7	<0.5	<0.2
1202403	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202404	Soil	14	0.16	72	0.031	<1	0.60	0.019	0.04	<0.1	0.04	0.9	<0.1	<0.05	3	<0.5	<0.2
1202405	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202406	Soil	29	0.36	128	0.046	2	1.51	0.023	0.04	<0.1	0.11	1.8	<0.1	0.06	6	<0.5	<0.2
1202407	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202408	Soil	35	0.52	128	0.075	2	1.62	0.021	0.05	<0.1	0.04	2.3	<0.1	<0.05	6	<0.5	<0.2
1202409	Soil	24	0.53	102	0.050	2	1.66	0.016	0.05	<0.1	0.06	3.0	<0.1	<0.05	5	<0.5	<0.2
1202410	Soil	25	0.74	115	0.056	1	1.88	0.015	0.06	0.1	0.06	3.6	<0.1	<0.05	6	<0.5	<0.2
1202411	Soil	32	0.66	106	0.027	2	1.28	0.015	0.04	<0.1	0.06	2.2	<0.1	0.09	4	<0.5	<0.2
1202412	Soil	37	0.94	118	0.042	2	1.77	0.016	0.04	<0.1	0.05	3.5	<0.1	<0.05	5	<0.5	<0.2
1202413	Soil	30	0.47	289	0.068	1	1.60	0.022	0.04	0.1	0.03	2.8	<0.1	<0.05	4	<0.5	<0.2
1202414	Soil	30	0.36	372	0.039	1	1.71	0.023	0.07	0.1	0.07	2.8	<0.1	<0.05	5	<0.5	<0.2
1202415	Soil	22	0.16	140	0.033	1	0.91	0.019	0.04	<0.1	0.04	1.3	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000291.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202416	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202417	Soil	0.6	15.1	5.7	17	<0.1	7.6	2.9	62	0.86	1.9	0.8	1.0	8	0.2	0.1	<0.1	29	0.08	0.015	5
1202418	Soil	1.0	15.9	5.4	20	<0.1	10.8	3.4	71	1.05	2.0	1.7	0.5	12	0.2	0.2	<0.1	40	0.12	0.024	4
1202419	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202420	Soil	1.0	27.9	21.9	65	0.1	36.2	15.0	505	3.00	14.8	2.8	4.0	37	0.3	0.3	0.1	68	1.09	0.064	16
1202421	Soil	0.7	28.0	9.4	67	<0.1	32.0	12.0	256	2.73	4.6	15.1	3.3	44	0.2	0.2	<0.1	62	1.50	0.057	13
1202422	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202423	Soil	0.8	24.7	10.0	103	<0.1	27.7	11.7	603	2.17	4.1	0.9	1.5	58	0.5	0.3	0.1	43	2.65	0.074	9
1202424	Soil	1.1	28.5	7.5	76	0.1	25.0	10.8	514	2.10	3.9	1.1	1.3	65	0.6	0.4	0.1	47	2.30	0.074	14
1202425	Soil	1.2	34.8	13.5	77	0.2	31.8	15.2	467	3.17	4.8	2.2	3.6	39	0.2	0.5	0.2	76	1.09	0.074	23
1202426	Soil	1.7	20.9	12.1	92	<0.1	31.3	14.1	442	3.03	4.5	1.3	5.7	29	0.4	0.4	0.3	76	0.56	0.042	10
1202427	Soil	1.9	26.3	16.2	84	0.3	32.6	15.6	750	3.02	5.0	2.0	5.7	31	0.2	0.4	0.3	72	0.65	0.063	20
1202428	Soil	1.5	29.7	11.4	76	0.2	39.7	13.8	402	3.19	5.2	1.0	5.2	29	0.2	0.4	0.2	75	0.55	0.055	15
1202429	Soil	1.5	23.6	15.2	68	<0.1	38.4	13.9	387	3.41	6.7	1.7	4.9	19	0.2	0.4	0.2	83	0.29	0.040	13
1202430	Soil	1.6	33.7	9.2	73	0.1	42.5	14.7	441	3.68	8.8	1.8	3.9	22	0.2	0.4	0.1	98	0.36	0.069	13
1202431	Soil	1.4	41.5	10.4	80	<0.1	43.2	14.8	363	3.72	6.7	1.9	4.8	16	0.1	0.3	0.2	100	0.28	0.035	9
1202432	Soil	1.7	37.0	8.4	70	0.3	37.6	12.9	534	3.04	4.9	2.5	4.0	16	0.2	0.3	0.2	74	0.27	0.059	25
1202433	Soil	1.2	23.1	7.9	64	0.3	25.3	9.0	300	2.42	3.5	2.5	2.0	25	0.2	0.4	0.1	60	0.44	0.039	11
1202434	Soil	1.3	20.4	8.2	74	0.2	35.8	11.1	276	3.06	7.2	2.1	4.4	27	0.1	0.2	0.2	52	0.52	0.041	8
1202435	Soil	0.6	8.0	4.6	19	0.1	6.1	1.8	42	0.71	0.8	1.2	0.4	5	<0.1	0.2	<0.1	21	0.05	0.013	3
1202436	Soil	1.7	35.9	10.7	80	<0.1	37.4	11.2	331	2.98	17.7	2.9	3.1	16	0.4	0.6	0.2	64	0.15	0.050	11
1202437	Soil	0.6	4.8	4.4	18	<0.1	5.2	3.1	89	1.03	2.2	1.4	1.0	7	0.1	0.1	0.1	27	0.06	0.012	3
1202438	Soil	2.4	19.4	11.8	55	0.2	19.7	8.0	265	2.69	8.5	1.2	2.7	16	0.2	0.4	0.2	82	0.17	0.026	8
1202439	Soil	1.2	15.0	7.0	40	<0.1	16.4	7.9	196	2.38	5.0	5.4	1.9	13	0.2	0.3	0.1	60	0.10	0.016	5
1202440	Soil	1.7	18.4	10.6	55	<0.1	25.2	12.3	340	3.45	7.7	2.1	4.9	22	0.1	0.4	0.2	77	0.26	0.021	17
1202441	Soil	1.4	30.8	13.2	77	<0.1	41.4	15.7	343	3.99	6.9	0.7	6.1	19	0.1	0.4	0.2	67	0.23	0.030	11
1202442	Soil	1.5	20.8	9.8	65	0.2	33.3	10.8	237	3.20	7.1	1.0	2.1	16	0.2	0.4	0.1	75	0.21	0.020	6
1202443	Soil	1.5	28.1	7.0	67	<0.1	38.5	15.9	234	3.78	7.4	1.0	6.9	14	0.2	0.3	0.2	68	0.17	0.047	16
1202444	Soil	1.2	17.6	9.1	46	<0.1	19.3	8.5	256	2.92	7.0	1.4	4.6	10	0.2	0.3	0.1	71	0.12	0.041	15
1202501	Soil	1.2	17.3	9.4	56	<0.1	16.3	7.7	339	2.32	5.7	1.7	1.0	11	0.2	0.3	0.1	55	0.13	0.039	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000291.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202416	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202417	Soil		11	0.10	43	0.050	1	0.51	0.014	0.03	<0.1	0.02	0.8	<0.1	<0.05	3	<0.5	<0.2
1202418	Soil		16	0.12	45	0.045	1	0.54	0.013	0.03	<0.1	0.03	0.9	<0.1	<0.05	3	<0.5	<0.2
1202419	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202420	Soil		48	0.85	139	0.086	2	1.94	0.026	0.07	<0.1	0.05	4.0	<0.1	<0.05	6	<0.5	<0.2
1202421	Soil		43	0.83	133	0.093	3	1.85	0.024	0.12	<0.1	0.06	3.5	0.1	<0.05	5	<0.5	<0.2
1202422	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202423	Soil		31	0.50	149	0.053	4	1.26	0.025	0.09	<0.1	0.06	2.2	<0.1	0.12	3	<0.5	<0.2
1202424	Soil		33	0.43	261	0.041	4	1.26	0.024	0.06	<0.1	0.07	3.7	<0.1	0.10	4	<0.5	<0.2
1202425	Soil		52	0.56	286	0.051	3	1.71	0.017	0.06	<0.1	0.06	6.6	0.1	<0.05	5	<0.5	<0.2
1202426	Soil		48	0.55	218	0.081	2	1.74	0.014	0.09	<0.1	0.03	4.1	0.1	<0.05	5	<0.5	<0.2
1202427	Soil		45	0.51	297	0.046	2	1.87	0.015	0.07	<0.1	0.10	4.8	0.1	<0.05	6	<0.5	<0.2
1202428	Soil		56	0.79	221	0.084	2	2.05	0.014	0.08	<0.1	0.04	3.9	0.2	<0.05	6	<0.5	<0.2
1202429	Soil		54	0.74	163	0.094	2	2.29	0.012	0.07	<0.1	0.02	3.8	0.1	<0.05	7	<0.5	<0.2
1202430	Soil		57	0.70	160	0.104	2	2.09	0.014	0.10	<0.1	0.02	4.6	0.1	<0.05	8	<0.5	<0.2
1202431	Soil		61	0.85	152	0.116	1	2.47	0.012	0.13	<0.1	0.03	3.7	0.2	<0.05	7	<0.5	<0.2
1202432	Soil		47	0.54	226	0.060	<1	1.61	0.011	0.09	<0.1	0.04	4.9	0.1	<0.05	6	<0.5	<0.2
1202433	Soil		35	0.41	188	0.029	<1	1.17	0.014	0.05	0.1	0.05	3.8	<0.1	<0.05	5	<0.5	<0.2
1202434	Soil		47	0.73	136	0.040	<1	1.49	0.013	0.10	<0.1	0.02	3.0	0.1	<0.05	6	<0.5	<0.2
1202435	Soil		9	0.10	28	0.031	<1	0.30	0.011	0.04	<0.1	<0.01	0.5	<0.1	<0.05	2	<0.5	<0.2
1202436	Soil		33	0.39	154	0.043	<1	1.98	0.010	0.04	0.1	0.03	3.8	<0.1	<0.05	5	<0.5	<0.2
1202437	Soil		11	0.18	46	0.049	<1	0.61	0.012	0.05	<0.1	0.01	0.7	<0.1	<0.05	4	<0.5	<0.2
1202438	Soil		30	0.41	119	0.085	<1	1.23	0.009	0.09	0.1	0.01	2.2	0.1	<0.05	7	<0.5	<0.2
1202439	Soil		27	0.41	88	0.076	<1	1.30	0.012	0.07	<0.1	<0.01	1.4	0.1	<0.05	6	<0.5	<0.2
1202440	Soil		39	0.75	227	0.119	1	1.94	0.015	0.25	0.1	<0.01	3.0	0.1	<0.05	8	<0.5	<0.2
1202441	Soil		53	0.97	135	0.110	<1	2.40	0.011	0.23	<0.1	0.01	2.4	0.2	<0.05	7	<0.5	<0.2
1202442	Soil		53	0.59	179	0.074	<1	1.87	0.010	0.12	<0.1	<0.01	2.3	<0.1	<0.05	6	<0.5	<0.2
1202443	Soil		41	0.86	151	0.117	<1	2.41	0.011	0.26	<0.1	0.01	3.0	0.3	<0.05	7	<0.5	<0.2
1202444	Soil		31	0.46	88	0.090	2	1.59	0.011	0.13	0.1	0.02	2.0	0.1	<0.05	7	<0.5	<0.2
1202501	Soil		28	0.44	92	0.050	<1	1.38	0.012	0.04	<0.1	0.02	2.0	<0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000291.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202502	Soil	1.1	23.4	28.6	55	<0.1	23.8	10.8	376	2.72	7.1	6.3	3.1	12	0.3	0.4	0.1	63	0.18	0.035	16
1202503	Soil	1.4	21.3	25.4	47	<0.1	18.3	7.8	278	2.42	6.1	4.1	2.4	11	0.2	0.3	0.1	60	0.16	0.047	16
1202504	Soil	1.7	24.1	34.5	57	<0.1	21.0	8.9	384	2.55	6.9	6.8	4.4	14	0.2	0.3	0.2	57	0.22	0.059	27
1202505	Soil	2.2	44.4	14.7	60	<0.1	17.0	9.2	568	2.79	16.0	3.4	2.6	13	0.2	0.4	0.4	52	0.15	0.048	39
1202506	Soil	0.8	7.6	5.8	16	<0.1	4.6	1.7	40	0.66	<0.5	1.3	<0.1	11	<0.1	0.2	0.1	20	0.13	0.038	5
1202507	Soil	1.3	13.1	9.3	35	<0.1	10.7	4.5	143	1.76	3.4	4.1	0.7	11	0.1	0.3	0.2	48	0.10	0.057	13
1202508	Soil	1.8	19.8	13.1	51	<0.1	21.0	9.4	349	2.82	5.5	6.8	4.0	17	0.2	0.4	0.2	76	0.22	0.040	15
1202509	Soil	2.1	21.6	11.5	51	<0.1	20.5	8.9	301	2.89	8.6	7.6	2.9	12	0.2	0.5	0.2	73	0.13	0.037	16
1202510	Soil	1.1	10.8	7.1	32	<0.1	7.9	4.8	203	1.68	5.0	2.0	0.7	9	<0.1	0.2	<0.1	38	0.10	0.035	7
1202511	Soil	1.7	13.1	8.2	46	<0.1	11.5	5.5	512	1.87	4.8	5.1	1.2	11	0.1	0.3	0.1	51	0.17	0.051	12
1202512	Soil	1.3	23.5	12.5	59	<0.1	23.7	9.9	470	2.61	6.7	4.3	2.5	14	0.3	0.4	0.2	67	0.21	0.048	18
1202513	Soil	1.6	17.9	12.1	43	<0.1	14.8	6.7	296	2.39	6.1	3.2	1.0	12	0.2	0.4	0.2	63	0.13	0.042	8
1202514	Soil	1.0	17.3	20.7	50	<0.1	19.8	9.0	488	2.86	5.9	2.2	6.4	13	0.2	0.3	0.3	72	0.25	0.064	36
1202515	Soil	1.5	22.7	36.8	77	<0.1	19.5	9.6	414	2.88	18.6	4.3	2.9	12	0.3	0.4	0.5	65	0.17	0.043	16
1202516	Soil	2.9	27.1	40.0	65	0.2	24.7	10.1	595	3.24	9.5	0.9	2.7	23	0.1	0.4	0.2	71	0.32	0.097	52
1202517	Soil	1.6	19.5	13.0	55	<0.1	19.0	8.7	367	3.06	8.1	6.0	2.0	13	0.1	0.4	0.2	83	0.16	0.033	9
1202518	Soil	1.7	25.6	10.5	54	0.2	18.6	8.2	400	2.54	6.5	1.6	1.0	17	0.2	0.4	0.2	55	0.20	0.082	36
1202519	Soil	1.7	31.2	10.1	60	0.1	22.3	10.3	729	2.54	5.5	2.2	0.8	24	0.3	0.3	0.1	62	0.40	0.082	27
1202520	Soil	1.5	8.4	8.6	20	<0.1	6.4	2.7	94	1.24	3.2	6.1	0.6	16	<0.1	0.3	0.2	38	0.17	0.027	4
1202521	Soil	2.7	28.6	43.7	86	<0.1	52.9	17.9	787	3.86	3.7	4.9	36.5	19	0.1	0.2	0.5	99	0.24	0.073	151
1202522	Soil	1.7	11.0	14.0	24	<0.1	7.9	3.9	282	1.48	3.1	8.2	1.8	9	0.1	0.2	0.2	43	0.09	0.026	5
1202523	Soil	4.0	32.7	74.9	83	<0.1	55.5	18.1	705	4.06	7.2	6.7	19.5	20	0.1	0.3	0.5	88	0.17	0.040	37
1202524	Soil	1.8	20.4	13.2	38	<0.1	12.7	5.4	292	2.61	6.7	4.9	1.3	13	0.2	0.5	0.3	74	0.11	0.031	8
1202525	Soil	0.9	33.5	12.1	111	<0.1	103.4	31.7	1393	6.03	1.1	1.7	5.9	28	<0.1	0.2	0.7	154	0.44	0.112	26
1202526	Soil	0.6	28.4	18.0	108	<0.1	40.5	20.2	767	5.42	1.6	0.6	12.1	16	0.1	0.2	0.6	139	0.18	0.049	167
1202527	Soil	7.7	45.5	148.1	140	0.2	33.8	14.4	492	4.70	7.4	11.3	245.3	35	0.4	0.4	1.4	68	0.20	0.047	69
1202528	Soil	3.7	30.0	111.3	188	0.3	82.6	27.2	1651	6.05	5.4	5.2	371.5	24	0.4	0.2	1.7	120	0.31	0.033	322
1202529	Soil	5.3	27.3	92.6	69	0.2	22.1	10.6	685	4.46	12.2	11.5	25.3	19	0.4	0.7	1.1	83	0.17	0.053	18
1202530	Soil	2.5	14.8	16.4	40	<0.1	12.7	5.6	226	3.09	8.3	5.4	2.9	14	0.2	0.7	0.3	88	0.12	0.035	7
1202531	Soil	1.3	24.8	15.8	51	<0.1	34.2	13.0	365	3.30	8.7	5.7	7.9	19	0.3	0.4	0.3	86	0.27	0.031	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000291.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202502	Soil	29	0.48	116	0.069	<1	1.88	0.013	0.07	0.1	0.03	3.0	0.1	<0.05	5	<0.5	<0.2
1202503	Soil	28	0.47	101	0.064	<1	1.70	0.010	0.06	0.1	0.03	2.9	0.2	<0.05	5	<0.5	<0.2
1202504	Soil	29	0.45	150	0.059	<1	1.60	0.012	0.08	<0.1	0.03	3.2	0.3	<0.05	5	0.5	<0.2
1202505	Soil	26	0.31	159	0.038	1	1.54	0.011	0.09	<0.1	0.02	2.7	0.2	<0.05	5	0.5	<0.2
1202506	Soil	10	0.06	76	0.020	<1	0.31	0.015	0.03	<0.1	0.02	0.5	<0.1	0.07	2	<0.5	<0.2
1202507	Soil	21	0.21	99	0.040	<1	1.11	0.012	0.04	<0.1	0.03	1.5	<0.1	0.07	5	<0.5	<0.2
1202508	Soil	32	0.36	150	0.084	<1	1.42	0.013	0.06	0.2	0.04	2.3	<0.1	<0.05	6	<0.5	<0.2
1202509	Soil	31	0.42	147	0.066	1	1.77	0.009	0.05	0.2	0.04	2.6	<0.1	<0.05	7	<0.5	<0.2
1202510	Soil	15	0.24	64	0.042	1	1.17	0.014	0.03	0.1	0.04	1.1	<0.1	<0.05	4	<0.5	<0.2
1202511	Soil	20	0.25	142	0.052	<1	0.87	0.015	0.06	0.1	0.04	1.6	<0.1	<0.05	5	<0.5	<0.2
1202512	Soil	31	0.48	142	0.071	1	1.67	0.017	0.07	0.1	0.04	2.6	<0.1	<0.05	5	<0.5	<0.2
1202513	Soil	26	0.29	106	0.045	<1	1.21	0.011	0.04	<0.1	0.03	1.9	<0.1	<0.05	6	<0.5	<0.2
1202514	Soil	30	0.41	116	0.073	4	1.50	0.010	0.07	0.1	0.03	3.9	0.1	<0.05	4	<0.5	<0.2
1202515	Soil	30	0.49	105	0.064	<1	1.74	0.011	0.07	0.1	0.04	2.9	0.1	<0.05	6	<0.5	<0.2
1202516	Soil	42	0.50	302	0.033	<1	2.42	0.013	0.12	0.1	0.05	3.9	0.2	0.08	7	0.7	<0.2
1202517	Soil	33	0.40	119	0.084	1	1.59	0.010	0.05	0.2	0.03	2.5	0.1	<0.05	7	<0.5	<0.2
1202518	Soil	30	0.46	238	0.041	1	1.86	0.016	0.06	0.2	0.07	2.3	0.1	0.07	5	<0.5	<0.2
1202519	Soil	35	0.55	316	0.037	1	1.65	0.015	0.07	<0.1	0.05	2.3	<0.1	0.08	6	<0.5	<0.2
1202520	Soil	14	0.12	72	0.046	2	0.51	0.012	0.03	<0.1	0.03	0.7	<0.1	0.05	4	<0.5	<0.2
1202521	Soil	89	1.81	253	0.062	<1	2.32	0.016	0.37	<0.1	0.02	6.5	0.3	0.14	7	<0.5	0.2
1202522	Soil	16	0.18	61	0.057	<1	0.65	0.016	0.04	<0.1	0.05	1.0	<0.1	0.05	4	<0.5	<0.2
1202523	Soil	89	1.35	199	0.087	3	2.27	0.026	0.36	0.1	0.03	6.5	0.5	0.25	6	<0.5	<0.2
1202524	Soil	25	0.25	106	0.068	1	1.43	0.011	0.04	0.1	0.04	1.7	<0.1	<0.05	7	<0.5	<0.2
1202525	Soil	170	3.94	388	0.068	4	3.63	0.008	0.81	<0.1	<0.01	14.3	0.5	0.19	11	<0.5	0.2
1202526	Soil	84	3.00	245	0.097	1	3.09	0.006	0.79	<0.1	<0.01	13.3	0.8	<0.05	9	<0.5	<0.2
1202527	Soil	37	0.66	230	0.087	2	1.93	0.028	0.36	0.2	0.04	6.0	0.5	0.32	4	0.7	0.7
1202528	Soil	269	2.28	381	0.084	3	2.99	0.017	1.02	<0.1	0.07	17.1	1.0	0.14	7	0.6	0.8
1202529	Soil	35	0.52	207	0.089	1	1.93	0.027	0.21	0.2	0.05	3.1	0.2	0.33	7	<0.5	0.4
1202530	Soil	25	0.26	115	0.100	<1	1.10	0.010	0.05	0.1	0.03	1.6	<0.1	<0.05	8	<0.5	<0.2
1202531	Soil	39	0.57	141	0.144	3	2.32	0.017	0.06	0.2	0.05	3.4	<0.1	<0.05	5	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000291.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202532	Soil		1.8	22.9	18.0	49	<0.1	21.6	9.4	316	3.11	6.9	13.2	9.7	16	0.2	0.4	0.3	88	0.22	0.052	12
1202533	Soil		1.7	15.8	16.9	42	<0.1	13.7	6.7	261	2.69	6.2	2.3	7.1	14	0.2	0.4	0.3	71	0.14	0.028	8
1202534	Soil		1.9	24.1	17.4	59	<0.1	25.8	9.6	378	2.91	6.2	6.1	16.9	21	0.4	0.4	0.3	79	0.32	0.062	23
1202551	Soil		1.4	19.2	44.7	60	<0.1	23.1	8.8	437	2.38	5.7	2.3	9.4	16	0.2	0.5	0.6	59	0.21	0.032	33
1202552	Soil		2.4	24.3	17.8	84	<0.1	15.7	7.8	458	2.87	7.3	3.0	0.9	18	0.2	0.7	0.3	64	0.18	0.073	12
1202553	Soil		2.1	23.5	19.8	89	0.1	20.1	9.3	519	3.20	7.1	7.7	4.0	20	0.3	0.6	0.2	69	0.28	0.077	26
1202554	Soil		1.1	20.1	15.5	68	<0.1	18.3	9.2	406	2.98	6.1	5.2	2.4	17	0.1	0.3	0.4	67	0.24	0.067	12
1202555	Soil		1.4	19.0	10.9	57	<0.1	12.5	6.1	290	2.42	5.9	2.2	0.7	15	0.2	0.5	0.2	55	0.14	0.060	12
1202556	Soil		0.7	20.2	9.1	68	<0.1	19.7	9.2	394	2.78	5.7	7.2	3.4	19	0.1	0.4	0.1	67	0.29	0.068	17
1202557	Soil		1.0	19.3	17.4	98	<0.1	18.6	8.1	480	2.75	3.9	1.7	5.2	19	0.3	0.3	0.1	57	0.27	0.058	27
1202558	Soil		0.4	4.0	2.3	12	<0.1	2.1	1.3	101	0.55	<0.5	<0.5	<0.1	8	<0.1	<0.1	<0.1	16	0.07	0.024	3
1202559	Soil		1.6	26.3	14.4	87	<0.1	21.4	10.0	545	3.24	7.7	4.2	1.7	19	0.2	0.5	0.3	73	0.20	0.063	15
1202560	Soil		0.8	7.6	3.1	18	0.1	3.7	2.4	81	1.00	1.1	7.3	0.1	10	<0.1	0.1	<0.1	24	0.09	0.034	2
1202561	Soil		1.2	20.4	34.1	140	0.1	16.2	8.5	666	3.25	5.3	6.7	3.2	18	0.4	0.3	0.2	60	0.31	0.065	12
1202562	Soil		1.8	21.8	16.3	71	<0.1	18.3	18.6	1299	3.72	7.4	5.7	2.1	20	0.3	0.4	0.2	75	0.24	0.082	10
1202563	Soil		1.9	31.1	16.7	54	0.6	14.9	18.5	1924	2.50	4.1	4.1	0.4	31	0.2	0.4	0.2	49	0.39	0.170	26
1202564	Soil		0.4	4.4	2.5	16	0.2	3.1	4.0	275	0.85	<0.5	0.9	0.2	9	0.1	0.1	<0.1	18	0.09	0.039	3
1202586	Soil		1.2	26.8	11.3	71	<0.1	25.4	10.5	320	2.89	5.9	5.1	5.9	23	0.2	0.4	0.1	76	0.35	0.078	28
1202587	Soil		1.5	21.6	18.5	75	0.4	18.8	10.2	726	2.88	5.1	2.8	1.2	25	0.3	0.4	0.2	69	0.27	0.088	12
1202588	Soil		0.8	13.6	5.5	33	0.1	8.1	3.6	162	1.38	2.2	1.9	0.2	15	0.1	0.2	<0.1	35	0.16	0.061	6
1202589	Soil		1.2	19.5	12.0	100	<0.1	21.6	11.1	582	3.09	6.1	5.0	2.0	25	0.4	0.4	0.2	75	0.33	0.053	8
1202590	Soil		1.4	14.6	8.1	47	0.2	11.6	6.4	495	1.98	4.3	4.7	0.4	20	0.3	0.5	0.2	57	0.21	0.067	5
1202591	Soil		0.8	18.2	9.8	60	<0.1	22.1	8.8	306	2.52	4.7	2.5	2.4	29	0.2	0.3	0.2	66	0.44	0.045	12
1202592	Soil		1.1	15.5	10.1	46	0.1	17.9	6.3	235	2.29	5.2	2.1	1.3	25	0.2	0.4	0.2	67	0.29	0.050	13
1202593	Soil		1.7	16.4	10.0	47	<0.1	19.3	8.0	318	2.95	6.9	13.2	1.4	27	0.2	0.4	0.2	82	0.32	0.050	7
1202594	Soil		1.1	17.0	9.1	53	<0.1	22.2	10.5	323	3.11	8.3	2.5	2.5	21	0.1	0.5	0.2	71	0.26	0.048	12
1202595	Soil		1.4	18.2	8.7	49	<0.1	18.8	7.1	292	2.86	7.9	5.4	1.8	16	0.2	0.4	0.2	85	0.23	0.035	7
1202596	Soil		1.2	17.2	7.7	58	<0.1	21.6	9.8	352	2.56	8.2	3.4	1.3	19	0.1	0.3	0.1	65	0.36	0.053	9
1202597	Soil		0.7	18.8	5.6	51	<0.1	22.1	10.8	577	2.54	5.9	1.1	2.2	17	0.2	0.3	0.1	68	0.30	0.036	7
1202598	Soil		1.0	12.1	6.0	31	<0.1	10.4	4.0	138	1.51	4.1	3.7	0.6	13	0.1	0.2	0.4	43	0.16	0.043	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000291.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202532	Soil	35	0.48	139	0.111	1	1.65	0.015	0.06	0.2	0.05	2.3	<0.1	<0.05	6	<0.5	<0.2
1202533	Soil	25	0.30	97	0.095	<1	1.55	0.013	0.04	0.1	0.03	1.8	<0.1	<0.05	7	<0.5	0.2
1202534	Soil	36	0.55	158	0.126	<1	1.76	0.019	0.07	0.2	0.04	3.1	<0.1	<0.05	5	<0.5	<0.2
1202551	Soil	26	0.43	118	0.077	<1	1.61	0.013	0.08	<0.1	0.03	2.6	<0.1	<0.05	4	<0.5	<0.2
1202552	Soil	30	0.42	188	0.044	1	1.58	0.013	0.08	<0.1	0.05	2.5	0.1	0.06	6	<0.5	<0.2
1202553	Soil	33	0.47	291	0.068	2	1.51	0.016	0.10	0.3	0.05	4.7	0.1	0.05	5	<0.5	<0.2
1202554	Soil	36	0.63	162	0.064	<1	1.93	0.010	0.09	0.1	0.04	4.2	<0.1	<0.05	6	<0.5	<0.2
1202555	Soil	23	0.34	152	0.046	<1	1.31	0.014	0.06	<0.1	0.04	2.4	<0.1	<0.05	6	<0.5	<0.2
1202556	Soil	30	0.57	123	0.101	<1	1.50	0.012	0.07	0.1	0.03	3.6	<0.1	<0.05	5	<0.5	<0.2
1202557	Soil	40	0.54	182	0.089	<1	1.43	0.013	0.15	<0.1	0.02	5.6	<0.1	<0.05	5	<0.5	<0.2
1202558	Soil	5	0.06	48	0.030	<1	0.22	0.018	0.02	<0.1	0.03	0.3	<0.1	<0.05	2	<0.5	<0.2
1202559	Soil	35	0.46	175	0.071	2	1.70	0.013	0.09	0.1	0.03	3.7	<0.1	<0.05	7	<0.5	<0.2
1202560	Soil	8	0.10	40	0.042	<1	0.51	0.020	0.02	<0.1	0.03	0.6	<0.1	<0.05	3	<0.5	<0.2
1202561	Soil	23	0.39	148	0.061	<1	1.05	0.012	0.04	<0.1	0.02	6.8	0.2	<0.05	3	<0.5	<0.2
1202562	Soil	40	0.55	141	0.074	2	2.03	0.012	0.07	0.1	0.07	4.6	0.1	0.05	7	<0.5	<0.2
1202563	Soil	30	0.32	254	0.047	1	1.58	0.021	0.04	0.1	0.09	4.2	0.1	0.20	4	0.8	<0.2
1202564	Soil	10	0.10	48	0.037	<1	0.27	0.023	0.02	<0.1	0.04	1.1	<0.1	<0.05	2	<0.5	<0.2
1202586	Soil	36	0.62	147	0.125	1	2.00	0.017	0.10	0.2	0.04	4.8	0.1	<0.05	5	0.5	<0.2
1202587	Soil	37	0.46	222	0.075	1	1.78	0.017	0.05	0.1	0.08	4.0	0.1	0.06	7	0.6	<0.2
1202588	Soil	19	0.24	102	0.044	<1	0.75	0.021	0.03	<0.1	0.04	1.4	<0.1	0.06	3	<0.5	<0.2
1202589	Soil	36	0.58	190	0.102	<1	1.47	0.014	0.07	0.1	0.03	3.3	<0.1	<0.05	6	<0.5	<0.2
1202590	Soil	22	0.29	144	0.058	<1	0.92	0.017	0.05	<0.1	0.06	1.7	<0.1	0.08	5	<0.5	<0.2
1202591	Soil	36	0.57	214	0.105	<1	1.44	0.021	0.05	0.1	0.02	3.4	<0.1	<0.05	5	<0.5	<0.2
1202592	Soil	30	0.50	176	0.103	<1	1.36	0.014	0.05	0.1	0.04	2.9	<0.1	<0.05	6	<0.5	<0.2
1202593	Soil	33	0.51	144	0.113	<1	1.30	0.010	0.05	0.1	0.05	2.5	<0.1	<0.05	7	<0.5	<0.2
1202594	Soil	36	0.59	123	0.101	1	2.29	0.015	0.05	0.1	0.04	3.3	<0.1	<0.05	6	<0.5	<0.2
1202595	Soil	32	0.49	110	0.100	1	1.50	0.011	0.05	0.2	0.03	2.8	<0.1	0.08	7	<0.5	<0.2
1202596	Soil	31	0.56	166	0.071	1	1.45	0.014	0.06	0.1	0.03	2.4	<0.1	0.09	6	<0.5	<0.2
1202597	Soil	29	0.61	126	0.098	1	1.50	0.017	0.06	0.1	0.03	2.9	<0.1	<0.05	4	<0.5	<0.2
1202598	Soil	19	0.27	135	0.050	<1	0.93	0.014	0.04	<0.1	0.03	1.5	<0.1	0.06	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000291.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202599	Soil	1.1	24.3	7.3	53	0.2	20.3	11.9	587	2.40	6.7	0.6	1.0	29	0.2	0.4	0.2	56	0.55	0.083	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000291.1

Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202599 Soil	28	0.50	236	0.054	2	1.68	0.021	0.06	0.1	0.05	3.1	<0.1	0.08	5	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000291.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1202301	Soil	1.6	19.2	7.4	28	0.2	10.3	5.2	121	2.15	5.0	4.0	0.3	15	0.1	0.5	0.2	67	0.17	0.052	5
REP 1202301	QC	1.5	19.1	7.3	28	0.1	10.6	5.3	125	2.16	5.3	2.3	0.4	15	0.1	0.4	0.2	68	0.18	0.054	5
1202336	Soil	0.8	13.8	8.0	24	0.1	9.1	3.4	103	1.21	2.1	1.2	0.6	13	0.2	0.2	0.1	41	0.15	0.028	5
REP 1202336	QC	0.9	12.6	7.6	25	0.1	8.5	3.3	108	1.13	2.0	3.6	0.6	14	0.3	0.2	0.1	41	0.15	0.028	5
1202340	Soil	1.6	25.5	14.0	52	0.2	19.5	12.8	514	3.24	7.8	1.9	2.6	15	0.3	0.4	0.2	83	0.16	0.033	10
REP 1202340	QC	1.7	25.8	14.5	52	0.2	19.2	12.9	516	3.32	8.0	8.1	2.4	15	0.3	0.4	0.3	85	0.16	0.034	10
1202418	Soil	1.0	15.9	5.4	20	<0.1	10.8	3.4	71	1.05	2.0	1.7	0.5	12	0.2	0.2	<0.1	40	0.12	0.024	4
REP 1202418	QC	1.2	16.7	5.5	21	<0.1	11.0	3.5	74	1.08	2.2	3.5	0.5	12	0.2	0.2	0.1	42	0.13	0.023	4
1202503	Soil	1.4	21.3	25.4	47	<0.1	18.3	7.8	278	2.42	6.1	4.1	2.4	11	0.2	0.3	0.1	60	0.16	0.047	16
REP 1202503	QC	1.3	20.5	24.2	47	<0.1	17.9	7.9	261	2.37	5.7	2.8	2.4	11	0.1	0.4	0.1	57	0.17	0.046	16
1202524	Soil	1.8	20.4	13.2	38	<0.1	12.7	5.4	292	2.61	6.7	4.9	1.3	13	0.2	0.5	0.3	74	0.11	0.031	8
REP 1202524	QC	2.0	20.3	13.6	40	<0.1	13.3	5.4	295	2.60	6.6	6.7	1.4	13	0.3	0.6	0.3	75	0.11	0.035	8
1202556	Soil	0.7	20.2	9.1	68	<0.1	19.7	9.2	394	2.78	5.7	7.2	3.4	19	0.1	0.4	0.1	67	0.29	0.068	17
REP 1202556	QC	0.6	20.1	8.9	66	<0.1	20.1	9.2	382	2.78	6.1	2.3	3.5	18	0.1	0.4	0.1	67	0.30	0.066	17
Reference Materials																					
STD DS8	Standard	13.4	115.6	131.1	333	1.8	38.6	7.8	618	2.55	27.2	124.4	6.9	73	2.4	6.2	7.1	43	0.69	0.076	14
STD DS8	Standard	13.3	115.2	134.0	330	1.9	40.5	7.7	611	2.54	27.4	115.9	7.2	72	2.3	6.2	7.1	45	0.70	0.083	15
STD DS8	Standard	13.8	118.4	130.9	331	1.8	40.8	8.3	627	2.52	28.0	107.5	6.6	62	2.2	5.7	6.7	45	0.69	0.084	13
STD DS8	Standard	13.8	123.0	134.1	339	1.8	40.8	8.3	643	2.57	27.9	115.0	6.6	62	2.7	5.9	6.5	48	0.71	0.089	13
STD DS8	Standard	12.6	111.6	114.7	313	1.8	39.5	7.4	587	2.40	25.1	126.5	5.9	59	2.2	4.9	6.1	42	0.65	0.074	12
STD DS8	Standard	13.1	117.1	116.2	325	1.9	40.2	7.8	623	2.48	26.9	105.6	5.9	58	2.4	5.5	6.3	45	0.66	0.088	13
STD DS8	Standard	14.4	119.7	114.3	337	2.0	43.3	8.7	667	2.66	28.6	109.9	6.1	65	2.6	5.6	6.5	47	0.73	0.093	15
STD DS8	Standard	14.0	114.8	125.2	333	1.8	40.8	8.0	624	2.48	26.4	116.7	6.9	64	2.4	5.6	6.8	45	0.74	0.083	16
STD DS8	Standard	15.2	123.6	120.0	327	1.9	42.2	8.5	645	2.59	27.1	121.7	7.1	68	2.5	5.6	6.5	48	0.77	0.085	17
STD DS8	Standard	13.5	120.6	124.5	320	1.7	41.3	8.1	633	2.52	26.5	120.4	6.3	64	2.4	5.2	6.2	43	0.70	0.084	14
STD DS8	Standard	13.8	118.6	120.6	320	1.7	41.6	8.1	624	2.51	26.8	117.8	6.4	63	2.3	5.1	6.1	44	0.76	0.088	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000291.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1202301	Soil	24	0.22	64	0.055	2	1.16	0.010	0.03	<0.1	0.07	1.7	<0.1	0.09	6	<0.5	<0.2
REP 1202301	QC	25	0.23	65	0.058	2	1.19	0.010	0.03	0.1	0.07	1.7	<0.1	0.08	7	<0.5	<0.2
1202336	Soil	16	0.17	78	0.060	<1	0.66	0.021	0.05	<0.1	0.04	1.2	<0.1	<0.05	4	<0.5	<0.2
REP 1202336	QC	16	0.18	80	0.071	<1	0.64	0.023	0.06	0.1	0.04	1.3	<0.1	<0.05	4	<0.5	<0.2
1202340	Soil	34	0.37	182	0.060	<1	2.52	0.011	0.04	0.1	0.05	3.1	0.1	<0.05	8	<0.5	<0.2
REP 1202340	QC	35	0.37	187	0.066	1	2.53	0.011	0.04	0.1	0.03	3.0	0.1	<0.05	8	<0.5	<0.2
1202418	Soil	16	0.12	45	0.045	1	0.54	0.013	0.03	<0.1	0.03	0.9	<0.1	<0.05	3	<0.5	<0.2
REP 1202418	QC	17	0.12	48	0.049	1	0.58	0.014	0.03	<0.1	0.03	0.9	<0.1	<0.05	3	<0.5	<0.2
1202503	Soil	28	0.47	101	0.064	<1	1.70	0.010	0.06	0.1	0.03	2.9	0.2	<0.05	5	<0.5	<0.2
REP 1202503	QC	27	0.45	97	0.064	<1	1.63	0.010	0.06	0.1	0.04	2.7	0.2	<0.05	5	0.6	<0.2
1202524	Soil	25	0.25	106	0.068	1	1.43	0.011	0.04	0.1	0.04	1.7	<0.1	<0.05	7	<0.5	<0.2
REP 1202524	QC	25	0.26	105	0.063	1	1.44	0.011	0.04	0.1	0.03	1.6	<0.1	0.05	8	0.5	<0.2
1202556	Soil	30	0.57	123	0.101	<1	1.50	0.012	0.07	0.1	0.03	3.6	<0.1	<0.05	5	<0.5	<0.2
REP 1202556	QC	30	0.58	117	0.106	<1	1.49	0.012	0.07	0.2	0.04	3.7	<0.1	<0.05	5	<0.5	<0.2
Reference Materials																	
STD DS8	Standard	120	0.58	278	0.126	2	0.88	0.081	0.42	3.2	0.22	2.0	5.6	0.17	5	5.1	5.0
STD DS8	Standard	122	0.60	287	0.131	2	0.97	0.088	0.42	3.2	0.23	2.0	5.6	0.17	5	6.0	4.7
STD DS8	Standard	125	0.54	276	0.117	3	0.90	0.076	0.42	3.0	0.21	1.8	5.3	0.12	5	4.7	5.6
STD DS8	Standard	129	0.56	276	0.123	2	0.94	0.088	0.42	3.1	0.21	1.9	5.3	0.15	5	4.3	5.2
STD DS8	Standard	119	0.59	261	0.106	2	0.86	0.079	0.40	2.9	0.21	1.8	5.4	0.17	5	5.6	4.9
STD DS8	Standard	121	0.63	277	0.111	2	0.89	0.086	0.43	3.0	0.21	2.0	5.2	0.18	5	5.5	5.3
STD DS8	Standard	124	0.69	283	0.123	2	1.01	0.094	0.46	3.2	0.20	2.3	5.3	0.24	5	5.7	5.2
STD DS8	Standard	121	0.64	295	0.118	4	0.99	0.092	0.43	3.2	0.21	2.3	6.0	0.17	5	5.6	6.0
STD DS8	Standard	130	0.63	298	0.133	3	1.00	0.097	0.47	3.1	0.20	2.3	5.5	0.17	5	5.7	6.0
STD DS8	Standard	123	0.61	276	0.114	3	0.95	0.098	0.44	2.8	0.19	2.1	5.5	0.15	5	4.6	5.0
STD DS8	Standard	123	0.62	294	0.123	2	0.96	0.103	0.42	3.1	0.17	2.2	5.1	0.15	5	4.8	5.0
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000291.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000291.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Submitted By: Daithi Mac Gerailt
Receiving Lab: Canada-Whitehorse
Received: June 29, 2011
Report Date: August 11, 2011
Page: 1 of 8

CERTIFICATE OF ANALYSIS WHI11000342.1

CLIENT JOB INFORMATION

Project:
Shipment ID:
P.O. Number
Number of Samples: 190

SAMPLE DISPOSAL

STOR-PLP	Store After 90 days Invoice for Storage
DISP-RJT-SOIL	Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	155	Dry at 60C			WHI
SS80	155	Dry at 60C sieve 100g to -80 mesh			WHI
1DX2	152	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Don Christie
Bruce Durham
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202871	Soil	1.3	45.1	10.3	68	0.2	34.0	14.9	527	3.18	6.0	2.5	3.8	28	0.2	0.3	0.1	74	0.42	0.071	17
1202872	Soil	0.9	26.5	7.8	64	<0.1	34.7	14.6	578	3.39	7.7	3.8	2.1	20	0.2	0.4	0.1	81	0.30	0.038	8
1202873	Soil	0.8	19.8	5.4	51	<0.1	18.2	11.9	423	2.61	4.7	4.1	1.8	17	<0.1	0.3	<0.1	62	0.28	0.067	10
1202874	Soil	1.2	25.3	8.6	69	0.1	25.1	13.3	610	3.22	5.7	9.0	3.1	23	0.2	0.4	0.1	69	0.37	0.067	14
1202875	Soil	1.6	21.8	11.4	65	0.1	29.4	13.3	454	3.38	8.5	9.0	1.6	19	0.2	0.5	0.2	79	0.21	0.062	9
1202876	Soil	1.5	16.5	10.4	36	0.1	11.1	3.8	729	0.55	1.0	1.2	0.3	54	1.4	0.3	<0.1	13	0.99	0.098	7
1202877	Soil	2.4	27.4	9.5	67	0.4	23.9	9.2	295	2.76	6.8	8.9	1.4	20	0.3	0.3	0.2	68	0.26	0.084	11
1202878	Soil	3.9	36.3	15.2	109	0.4	45.5	16.1	1116	2.66	9.3	7.9	1.5	21	0.7	0.3	0.2	61	0.25	0.085	13
1202879	Soil	1.7	20.2	6.6	60	0.3	23.4	6.2	316	1.39	3.9	1.2	0.4	19	0.7	0.2	0.1	34	0.24	0.072	8
1202880	Soil	2.4	25.1	12.5	101	0.3	36.3	19.2	1074	2.60	6.7	3.4	1.3	22	0.5	0.3	0.1	64	0.31	0.079	13
1202881	Soil	1.5	30.2	8.5	91	0.4	37.1	20.8	1841	2.50	5.7	3.1	1.2	26	0.6	0.3	0.1	61	0.41	0.090	15
1202882	Soil	1.6	33.8	9.1	90	0.3	33.2	12.2	615	3.02	6.2	4.5	1.0	23	0.4	0.4	0.1	73	0.32	0.081	16
1202883	Soil	1.4	22.8	7.8	71	0.1	21.5	9.1	442	2.68	5.1	3.3	0.7	21	0.2	0.3	0.1	66	0.30	0.071	11
1202884	Soil	1.4	25.7	8.3	82	0.1	25.6	12.1	569	2.77	5.6	4.1	1.2	23	0.4	0.3	0.1	68	0.33	0.065	11
1202885	Soil	1.4	34.6	7.2	80	0.3	26.5	11.9	547	2.80	5.3	3.2	1.3	21	0.3	0.3	0.1	66	0.26	0.069	12
1202886	Soil	0.8	24.4	7.9	52	0.2	20.6	9.7	410	2.19	4.2	1.7	1.4	22	0.1	0.3	0.1	54	0.38	0.058	15
1202887	Soil	0.8	17.1	8.1	31	0.2	12.7	4.5	200	1.29	2.7	4.2	0.3	41	0.2	0.4	0.1	31	0.66	0.104	14
1202888	Soil	0.8	15.5	6.3	27	<0.1	9.6	6.0	403	0.68	1.4	<0.5	0.3	46	0.3	0.3	<0.1	17	0.77	0.086	16
1202889	Soil	1.1	18.8	8.0	56	0.1	22.1	10.5	518	2.37	4.2	3.4	1.6	24	0.1	0.3	0.1	62	0.39	0.065	9
1202890	Soil	0.8	26.6	7.4	56	0.1	23.2	9.1	368	2.18	3.6	6.2	1.0	40	0.1	0.3	<0.1	52	0.84	0.084	17
1202891	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202892	Soil	0.8	26.8	7.8	53	0.1	26.6	9.8	363	2.25	4.4	5.8	1.9	38	0.2	0.3	0.1	56	0.91	0.065	15
1204001	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1204002	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1204003	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1204010	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1204011	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1204012	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203644	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203645	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202871	Soil	43	0.67	167	0.117	<1	1.94	0.022	0.08	<0.1	0.03	5.8	<0.1	<0.05	5	<0.5	<0.2
1202872	Soil	42	0.75	110	0.121	1	2.23	0.017	0.06	0.1	0.06	4.1	<0.1	<0.05	6	<0.5	<0.2
1202873	Soil	26	0.57	91	0.078	1	1.45	0.016	0.04	<0.1	0.03	3.2	<0.1	<0.05	5	<0.5	<0.2
1202874	Soil	36	0.69	155	0.086	1	1.68	0.019	0.06	0.1	0.04	4.3	<0.1	<0.05	5	0.6	<0.2
1202875	Soil	48	0.58	128	0.090	<1	2.08	0.012	0.06	0.1	0.07	2.9	<0.1	<0.05	7	<0.5	<0.2
1202876	Soil	14	0.17	163	0.018	4	0.42	0.021	0.07	<0.1	0.19	1.2	<0.1	0.17	1	0.7	<0.2
1202877	Soil	40	0.54	123	0.077	2	1.62	0.013	0.06	0.1	0.06	3.3	<0.1	<0.05	6	0.8	<0.2
1202878	Soil	37	0.51	156	0.064	<1	1.48	0.017	0.06	0.1	0.06	2.8	0.1	<0.05	5	0.9	<0.2
1202879	Soil	22	0.25	156	0.037	<1	0.78	0.018	0.04	<0.1	0.05	1.6	<0.1	0.06	3	0.8	<0.2
1202880	Soil	34	0.56	224	0.066	<1	1.68	0.016	0.06	<0.1	0.06	3.2	0.1	<0.05	6	0.6	<0.2
1202881	Soil	36	0.55	230	0.070	1	1.72	0.017	0.06	<0.1	0.07	3.5	0.1	0.05	5	0.8	<0.2
1202882	Soil	38	0.63	230	0.066	1	1.94	0.013	0.05	0.1	0.04	3.9	0.1	<0.05	6	0.7	<0.2
1202883	Soil	34	0.58	216	0.066	<1	1.75	0.013	0.05	0.1	0.02	2.8	0.1	<0.05	6	0.5	<0.2
1202884	Soil	35	0.61	357	0.077	<1	1.83	0.014	0.05	0.1	0.02	3.0	<0.1	<0.05	6	0.7	<0.2
1202885	Soil	36	0.60	210	0.072	<1	1.89	0.013	0.05	<0.1	0.03	3.6	0.1	<0.05	6	1.1	<0.2
1202886	Soil	29	0.53	218	0.072	<1	1.55	0.015	0.05	0.1	0.04	4.1	<0.1	<0.05	5	<0.5	<0.2
1202887	Soil	22	0.26	223	0.042	<1	0.93	0.019	0.04	0.1	0.10	2.1	<0.1	0.12	3	0.7	<0.2
1202888	Soil	11	0.20	254	0.028	2	0.57	0.015	0.06	<0.1	0.12	1.3	<0.1	0.14	2	0.9	<0.2
1202889	Soil	36	0.57	190	0.084	<1	1.67	0.015	0.06	0.1	0.03	3.0	<0.1	<0.05	6	<0.5	<0.2
1202890	Soil	32	0.54	184	0.065	<1	1.66	0.020	0.04	<0.1	0.05	3.6	<0.1	0.06	4	<0.5	<0.2
1202891	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202892	Soil	33	0.58	179	0.085	<1	1.63	0.022	0.06	0.1	0.03	3.5	<0.1	<0.05	5	<0.5	<0.2
1204001	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1204002	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1204003	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1204010	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1204011	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1204012	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203644	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203645	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203646	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203647	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203648	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203649	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203650	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202203	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202206	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202207	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202209	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202210	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202213	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203701	Soil	1.4	24.6	8.8	66	<0.1	21.6	8.5	355	3.01	8.4	11.3	0.6	18	0.3	0.5	0.1	77	0.21	0.052	8
1203706	Soil	2.8	33.6	11.2	64	0.3	28.9	10.6	359	3.33	9.9	4.4	1.5	15	0.4	0.5	0.2	77	0.16	0.049	9
1202831	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202832	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202833	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202834	Soil	1.0	30.2	10.5	65	0.1	36.6	15.2	517	2.95	3.2	1.7	2.6	30	0.1	0.1	0.1	80	0.48	0.057	10
1202835	Soil	0.9	35.5	9.7	60	<0.1	72.6	16.6	332	2.94	2.4	2.8	2.6	30	0.1	0.2	0.2	75	0.51	0.044	9
1202836	Soil	0.9	76.4	8.1	74	0.2	59.3	26.0	736	3.63	2.1	1.4	2.2	41	0.1	0.2	0.2	95	0.84	0.096	9
1202837	Soil	0.6	32.5	22.4	65	0.1	36.2	17.5	451	3.40	5.4	1.5	13.7	15	<0.1	0.2	0.2	51	0.37	0.052	64
1202838	Soil	4.1	52.2	12.7	86	0.5	28.0	7.7	353	2.81	9.5	2.6	2.9	27	0.4	0.3	0.2	107	0.24	0.096	11
1202839	Soil	1.6	46.5	10.7	79	0.5	41.8	12.8	325	3.41	12.3	7.1	5.4	24	0.2	0.5	0.2	78	0.27	0.047	21
1202840	Soil	2.6	36.1	14.5	99	0.2	39.4	11.0	313	3.93	62.1	4.6	3.9	18	0.4	0.6	0.7	106	0.21	0.044	14
1202841	Soil	1.5	33.7	15.5	93	0.1	42.8	15.8	517	4.36	9.8	2.0	7.3	22	0.2	0.4	0.2	81	0.32	0.046	16
1202842	Soil	1.7	26.9	20.7	76	<0.1	28.8	13.2	460	3.48	7.9	1.3	5.6	15	0.3	0.3	0.2	74	0.21	0.056	20
1202843	Soil	2.1	29.2	26.0	106	0.1	42.3	20.3	862	4.02	12.0	3.1	11.3	23	0.3	0.5	0.3	82	0.26	0.055	31
1202844	Soil	1.8	18.0	13.7	31	0.2	12.6	3.5	100	1.33	3.3	0.9	0.4	17	0.4	0.2	0.2	22	0.15	0.068	12
1202845	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202846	Soil	2.6	9.7	4.9	57	<0.1	8.9	2.1	1148	0.49	<0.5	<0.5	0.4	27	0.2	0.2	0.1	13	0.62	0.081	3
1202847	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203646	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203647	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203648	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203649	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203650	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202203	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202206	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202207	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202209	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202210	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1202213	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203701	Soil	37	0.50	116	0.081	<1	1.79	0.012	0.05	0.1	0.07	2.6	<0.1	<0.05	7	0.5	<0.2
1203706	Soil	37	0.52	100	0.086	<1	2.16	0.012	0.06	<0.1	0.06	2.9	0.1	<0.05	7	0.8	<0.2
1202831	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202832	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202833	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202834	Soil	95	1.02	170	0.121	<1	1.78	0.020	0.10	<0.1	0.02	3.2	0.1	<0.05	7	0.7	<0.2
1202835	Soil	174	1.47	213	0.182	1	1.96	0.020	0.15	<0.1	0.02	2.6	0.2	<0.05	7	<0.5	<0.2
1202836	Soil	132	1.68	343	0.172	2	2.19	0.023	0.36	<0.1	0.03	3.3	0.2	<0.05	7	<0.5	<0.2
1202837	Soil	139	1.16	149	0.143	1	2.00	0.009	0.45	<0.1	<0.01	4.4	0.3	<0.05	6	<0.5	<0.2
1202838	Soil	64	0.78	658	0.124	<1	1.81	0.014	0.33	0.1	0.03	3.1	0.2	0.10	7	1.6	<0.2
1202839	Soil	51	0.69	367	0.114	<1	2.24	0.015	0.14	<0.1	0.05	5.2	0.2	<0.05	6	<0.5	<0.2
1202840	Soil	62	0.68	253	0.102	2	2.12	0.010	0.10	0.1	0.02	4.6	0.1	<0.05	9	0.7	<0.2
1202841	Soil	60	0.88	186	0.172	1	2.33	0.017	0.20	<0.1	0.02	5.4	0.2	<0.05	11	<0.5	<0.2
1202842	Soil	44	0.63	155	0.128	3	2.15	0.015	0.15	<0.1	0.02	4.3	0.2	<0.05	10	<0.5	<0.2
1202843	Soil	52	0.72	176	0.120	3	2.32	0.013	0.16	0.1	0.02	4.6	0.2	<0.05	9	<0.5	<0.2
1202844	Soil	22	0.18	118	0.041	2	0.84	0.014	0.07	<0.1	0.09	1.6	0.1	0.09	4	<0.5	<0.2
1202845	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202846	Soil	11	0.09	113	0.010	2	0.18	0.020	0.08	<0.1	0.19	1.0	<0.1	0.09	<1	<0.5	<0.2
1202847	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202848	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202849	Soil	0.5	95.9	5.4	46	<0.1	64.8	16.9	297	2.68	2.7	6.1	2.3	30	<0.1	0.2	<0.1	75	0.41	0.053	10
1202850	Soil	0.6	76.3	5.9	42	<0.1	38.0	12.8	308	2.61	3.2	1.0	1.1	28	<0.1	0.2	<0.1	68	0.32	0.044	11
1202851	Soil	1.1	57.9	4.8	74	<0.1	35.3	21.8	442	3.87	1.9	1.4	1.7	38	<0.1	<0.1	0.1	100	0.51	0.095	4
1202852	Soil	0.6	46.5	4.6	70	<0.1	16.5	21.0	509	4.40	2.0	0.5	1.9	19	<0.1	0.1	<0.1	94	0.34	0.070	5
1202853	Soil	0.4	47.2	2.1	78	<0.1	16.7	22.8	496	3.87	1.2	<0.5	2.6	31	<0.1	<0.1	<0.1	89	0.42	0.080	4
1202854	Soil	0.8	31.8	6.0	66	<0.1	22.8	16.8	405	3.72	5.9	10.8	2.8	24	0.1	0.3	<0.1	83	0.29	0.051	8
1202855	Soil	1.7	45.7	9.2	86	<0.1	21.0	24.1	638	5.18	5.2	0.6	2.9	26	<0.1	0.2	<0.1	118	0.30	0.061	6
1202856	Soil	1.0	17.3	6.0	62	<0.1	12.8	14.3	440	3.46	3.7	<0.5	2.1	26	0.1	0.2	<0.1	91	0.26	0.040	6
1202857	Soil	1.2	25.5	7.6	65	0.1	18.4	17.8	862	3.57	4.5	<0.5	3.8	32	0.1	0.2	0.1	77	0.39	0.043	14
1202858	Soil	0.9	16.4	5.8	40	0.1	9.9	9.2	240	2.40	2.7	1.3	2.1	27	<0.1	0.2	<0.1	58	0.31	0.025	11
1202859	Soil	1.0	29.2	7.4	62	<0.1	27.1	16.9	463	3.54	5.6	<0.5	4.6	26	<0.1	0.3	<0.1	78	0.26	0.035	11
1202860	Soil	0.9	30.7	5.8	56	<0.1	23.5	16.9	472	3.73	4.6	<0.5	5.3	27	<0.1	0.2	<0.1	75	0.39	0.036	13
1204001	Soil	2.0	22.0	30.6	84	0.1	18.3	9.3	517	3.47	7.8	2.1	8.6	23	0.3	0.4	0.4	61	0.24	0.051	20
1204002	Soil	2.1	22.4	28.6	85	0.2	19.5	23.3	2113	3.32	7.3	2.8	5.5	29	0.3	0.5	0.3	68	0.27	0.086	23
1204003	Soil	1.0	19.2	18.0	99	<0.1	18.9	11.9	500	2.76	4.2	1.6	5.3	22	0.3	0.3	0.3	62	0.25	0.048	15
1204010	Soil	0.8	17.4	10.9	60	0.1	25.0	9.9	344	2.08	2.1	3.1	1.5	21	<0.1	0.2	0.3	54	0.28	0.049	9
1204011	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1204012	Soil	1.0	20.7	14.0	66	0.2	24.0	10.5	598	2.47	3.5	1.3	1.9	21	0.2	0.2	0.4	68	0.28	0.053	11
1202203	Soil	0.6	30.1	12.5	63	0.1	17.1	10.0	566	2.37	5.9	3.4	8.5	15	0.2	0.2	0.2	31	0.28	0.057	31
1202206	Soil	2.0	33.6	12.2	137	0.3	39.5	23.9	1301	3.31	16.6	3.0	2.3	19	0.5	0.5	0.2	79	0.21	0.059	14
1202207	Soil	4.8	88.3	20.6	224	0.3	85.7	28.8	1381	4.66	68.7	2.8	1.8	33	0.9	1.6	0.2	106	0.21	0.074	16
1202209	Soil	2.4	59.2	10.5	123	0.4	42.0	13.6	336	3.25	9.1	4.4	2.8	31	0.2	0.4	0.2	72	0.27	0.056	17
1202210	Soil	2.2	47.1	9.2	114	0.3	40.0	10.2	295	2.83	15.7	10.1	3.4	30	0.8	0.5	0.2	62	0.29	0.066	15
1202213	Soil	0.6	35.9	4.9	49	0.1	16.3	16.0	343	2.15	3.1	6.6	1.1	19	0.1	0.2	0.2	51	0.31	0.043	7
1203634	Soil	3.2	37.3	9.7	61	0.1	20.8	18.0	1108	3.16	3.7	2.2	4.3	35	0.1	0.3	0.8	56	0.42	0.107	43
1203635	Soil	0.9	43.1	5.8	48	0.2	33.7	15.1	437	4.30	7.4	1.9	0.9	17	<0.1	0.2	1.7	77	0.26	0.059	2
1203636	Soil	3.4	100.8	6.6	58	0.1	46.3	30.4	694	3.95	7.3	1.7	1.2	19	<0.1	0.3	3.0	79	0.59	0.055	4
1203637	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203638	Soil	0.4	48.5	8.5	65	<0.1	85.2	22.3	481	3.76	3.1	3.6	3.6	18	<0.1	0.2	0.3	93	0.33	0.050	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202848	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202849	Soil	95	0.94	163	0.124	<1	1.78	0.021	0.17	<0.1	0.02	4.2	0.1	<0.05	5	<0.5	<0.2
1202850	Soil	77	0.74	160	0.095	1	1.80	0.025	0.06	<0.1	0.03	5.3	<0.1	<0.05	6	<0.5	<0.2
1202851	Soil	86	1.59	373	0.219	<1	2.77	0.031	0.59	<0.1	<0.01	4.3	0.2	<0.05	7	<0.5	<0.2
1202852	Soil	35	1.32	305	0.130	4	2.93	0.023	0.61	<0.1	0.01	5.7	0.2	<0.05	6	<0.5	<0.2
1202853	Soil	27	2.06	420	0.304	<1	2.84	0.020	1.07	<0.1	<0.01	1.7	0.2	<0.05	6	<0.5	<0.2
1202854	Soil	34	1.21	272	0.186	1	2.49	0.019	0.39	<0.1	0.01	3.0	0.1	<0.05	7	<0.5	<0.2
1202855	Soil	34	1.79	331	0.287	1	3.21	0.016	0.74	0.1	<0.01	3.3	0.2	<0.05	9	<0.5	<0.2
1202856	Soil	22	1.28	254	0.241	1	1.97	0.014	0.48	<0.1	0.01	2.3	0.1	<0.05	8	<0.5	<0.2
1202857	Soil	31	1.11	300	0.178	2	2.39	0.020	0.28	<0.1	0.02	3.8	0.1	<0.05	8	<0.5	<0.2
1202858	Soil	18	0.77	184	0.187	<1	1.54	0.021	0.28	<0.1	0.02	1.6	0.1	<0.05	6	<0.5	<0.2
1202859	Soil	51	1.29	184	0.189	1	2.30	0.018	0.40	<0.1	<0.01	2.9	0.2	<0.05	6	<0.5	<0.2
1202860	Soil	48	1.24	183	0.193	2	2.20	0.018	0.42	<0.1	<0.01	4.1	0.2	<0.05	7	<0.5	<0.2
1204001	Soil	31	0.50	91	0.093	1	1.41	0.014	0.08	0.1	0.05	2.6	<0.1	<0.05	5	<0.5	<0.2
1204002	Soil	37	0.52	163	0.083	1	1.62	0.018	0.06	0.1	0.07	3.4	0.1	0.08	5	<0.5	<0.2
1204003	Soil	32	0.56	100	0.108	1	1.44	0.016	0.05	0.1	0.05	2.9	<0.1	<0.05	5	<0.5	<0.2
1204010	Soil	58	0.85	167	0.085	1	1.93	0.017	0.06	0.1	0.07	4.5	0.1	<0.05	6	<0.5	<0.2
1204011	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1204012	Soil	61	0.91	182	0.091	1	1.74	0.018	0.08	0.1	0.03	5.6	0.1	<0.05	5	<0.5	<0.2
1202203	Soil	20	0.51	320	0.042	<1	1.33	0.010	0.06	<0.1	0.02	4.2	<0.1	<0.05	4	<0.5	<0.2
1202206	Soil	43	0.57	115	0.062	<1	1.65	0.012	0.05	<0.1	0.03	4.0	0.1	<0.05	6	0.5	<0.2
1202207	Soil	75	0.89	115	0.055	1	1.75	0.012	0.10	<0.1	0.02	4.4	0.1	0.06	7	2.3	<0.2
1202209	Soil	48	0.64	201	0.087	1	2.24	0.014	0.07	<0.1	0.05	5.1	0.2	<0.05	7	<0.5	<0.2
1202210	Soil	40	0.53	150	0.069	<1	1.58	0.014	0.06	<0.1	0.02	4.8	<0.1	<0.05	5	0.8	<0.2
1202213	Soil	20	0.51	81	0.078	<1	1.42	0.015	0.04	<0.1	0.04	2.6	<0.1	<0.05	5	<0.5	<0.2
1203634	Soil	34	0.77	200	0.054	2	1.40	0.019	0.16	<0.1	0.07	3.5	0.2	0.15	5	0.7	0.3
1203635	Soil	83	1.93	98	0.115	2	1.79	0.013	0.37	<0.1	0.03	2.1	0.2	0.22	5	1.7	0.8
1203636	Soil	117	1.84	93	0.084	<1	1.97	0.019	0.19	<0.1	0.04	3.2	0.2	0.11	7	1.0	1.9
1203637	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203638	Soil	209	2.92	86	0.102	<1	3.06	0.010	0.05	<0.1	0.04	6.9	<0.1	<0.05	8	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203639	Soil	0.8	39.5	5.2	54	<0.1	59.7	24.1	1050	2.90	2.6	3.6	1.1	19	0.1	0.2	0.2	64	0.38	0.099	6
1203640	Soil	0.8	32.0	9.2	73	<0.1	43.2	17.1	602	3.49	4.3	2.0	2.3	20	<0.1	0.3	0.2	80	0.32	0.040	5
1203641	Soil	0.8	68.9	15.8	94	<0.1	42.5	19.5	623	3.96	3.9	8.9	4.0	22	0.1	0.3	0.4	90	0.51	0.055	11
1203642	Soil	0.5	21.8	21.8	90	<0.1	21.7	8.1	287	2.06	1.1	4.0	6.9	15	<0.1	0.2	0.3	41	0.37	0.039	8
1203643	Soil	0.6	36.5	17.6	57	<0.1	14.6	9.1	538	1.53	0.6	3.5	5.2	9	<0.1	0.2	0.3	30	0.19	0.040	13
1204004	Soil	1.3	21.5	17.3	96	0.1	16.3	15.3	1373	2.36	4.8	5.6	2.8	26	0.5	0.3	0.3	61	0.29	0.069	17
1204005	Soil	1.0	31.1	11.7	116	<0.1	55.0	22.1	1162	2.85	3.6	3.1	2.7	18	0.3	0.2	0.2	63	0.21	0.041	13
1204006	Soil	1.1	56.5	13.7	126	0.1	30.8	21.2	2178	2.88	4.8	7.4	3.0	34	0.7	0.3	0.3	75	0.49	0.068	20
1204007	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1204008	Soil	1.0	38.9	16.0	128	0.1	30.2	22.0	1842	2.92	5.6	4.3	3.2	27	0.3	0.3	0.3	70	0.39	0.069	16
1204009	Soil	0.8	31.2	13.0	118	0.1	25.5	19.3	1108	2.81	3.8	3.1	2.3	29	0.4	0.2	0.2	68	0.44	0.060	16
1202993	Soil	1.8	45.6	11.5	81	0.4	29.4	10.0	319	3.01	15.2	5.2	2.5	24	0.2	0.3	0.4	62	0.24	0.068	15
1202994	Soil	0.7	29.0	10.7	48	<0.1	22.3	10.3	304	2.98	5.7	1.6	14.0	29	<0.1	0.2	0.2	58	0.39	0.060	41
1202085	Soil	0.8	30.1	31.9	86	<0.1	13.5	8.3	472	2.32	9.4	3.0	45.2	10	0.1	0.2	0.8	29	0.11	0.026	66
1203601	Soil	1.2	22.6	11.6	88	<0.1	16.1	11.2	340	3.32	5.0	2.0	4.5	20	<0.1	0.2	0.2	72	0.32	0.049	11
1203602	Soil	1.0	41.5	4.5	120	<0.1	39.7	24.7	429	4.60	6.0	0.7	1.7	29	<0.1	0.2	<0.1	105	0.40	0.097	6
1203603	Soil	0.8	13.3	4.6	62	<0.1	22.2	18.1	429	3.89	5.4	1.1	2.6	21	<0.1	0.2	<0.1	77	0.29	0.043	7
1203604	Soil	1.0	18.5	4.7	36	<0.1	22.0	13.7	229	3.29	5.7	0.8	1.0	15	<0.1	0.4	0.1	86	0.21	0.041	4
1203605	Soil	1.1	18.4	8.1	79	<0.1	28.7	13.6	538	3.96	6.5	0.8	1.9	20	0.2	0.5	0.2	76	0.19	0.033	6
1203606	Soil	1.0	43.3	4.8	52	<0.1	14.9	14.4	813	3.36	4.0	1.5	1.5	20	<0.1	0.3	0.1	73	0.22	0.031	5
1203607	Soil	1.2	41.2	7.5	60	<0.1	30.4	15.5	362	3.87	8.2	1.8	3.6	25	<0.1	0.4	0.1	90	0.31	0.063	9
1203608	Soil	1.2	27.0	7.6	47	<0.1	29.1	12.8	252	3.30	8.1	2.7	3.0	21	<0.1	0.4	0.1	81	0.23	0.019	8
1203609	Soil	1.1	12.4	6.7	43	<0.1	9.8	9.6	217	2.42	3.9	0.6	1.7	18	<0.1	0.2	0.1	79	0.18	0.025	6
1203610	Soil	0.7	13.1	4.7	62	<0.1	10.6	14.2	400	3.12	2.8	<0.5	3.4	22	<0.1	0.1	<0.1	72	0.22	0.024	6
1203611	Soil	1.1	13.3	5.6	31	<0.1	8.4	6.9	200	1.96	3.2	1.8	2.1	13	<0.1	0.3	0.1	58	0.12	0.025	5
1203612	Soil	0.7	19.1	4.1	49	<0.1	10.6	12.7	304	2.71	3.3	<0.5	1.8	24	<0.1	0.1	<0.1	81	0.23	0.037	5
1203613	Soil	1.0	33.0	5.6	48	0.1	12.7	12.6	315	2.58	3.1	0.6	2.2	30	<0.1	0.2	<0.1	66	0.34	0.054	10
1203614	Soil	0.8	8.9	3.7	24	<0.1	5.6	5.4	142	1.79	3.6	0.7	0.8	13	<0.1	0.2	<0.1	63	0.12	0.021	3
1203615	Soil	0.8	38.6	4.5	68	<0.1	20.8	21.5	505	4.46	4.1	<0.5	2.3	29	<0.1	0.2	<0.1	99	0.30	0.042	4
1203616	Soil	1.2	27.5	5.2	45	<0.1	14.1	13.4	313	3.78	6.0	0.5	1.1	29	<0.1	0.4	0.1	93	0.24	0.026	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203639	Soil	161	2.08	75	0.037	<1	2.23	0.009	0.04	<0.1	0.05	4.3	<0.1	0.11	6	<0.5	<0.2
1203640	Soil	92	1.66	79	0.106	1	2.13	0.010	0.08	<0.1	0.03	3.9	0.1	<0.05	6	<0.5	<0.2
1203641	Soil	97	2.02	111	0.094	1	2.61	0.012	0.12	<0.1	0.06	7.5	0.1	0.08	7	<0.5	<0.2
1203642	Soil	41	1.17	80	0.072	1	1.55	0.009	0.07	<0.1	0.05	4.4	0.2	0.06	5	<0.5	<0.2
1203643	Soil	30	1.06	116	0.018	<1	1.21	0.004	0.06	<0.1	0.04	2.8	0.2	0.07	4	<0.5	<0.2
1204004	Soil	31	0.58	120	0.072	1	1.33	0.019	0.06	0.1	0.10	2.7	<0.1	<0.05	5	<0.5	<0.2
1204005	Soil	203	1.60	79	0.077	<1	1.69	0.010	0.05	0.1	0.03	3.0	<0.1	<0.05	5	<0.5	<0.2
1204006	Soil	68	1.06	157	0.086	1	1.84	0.021	0.06	0.1	0.06	4.7	0.1	0.07	5	0.6	<0.2
1204007	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1204008	Soil	71	0.98	156	0.079	1	1.82	0.017	0.06	0.1	0.06	4.5	0.1	<0.05	5	<0.5	<0.2
1204009	Soil	49	1.11	148	0.089	2	1.89	0.016	0.06	0.1	0.08	4.2	0.1	<0.05	6	<0.5	<0.2
1202993	Soil	39	0.51	215	0.064	<1	2.20	0.014	0.08	0.1	0.06	4.3	0.1	<0.05	7	<0.5	<0.2
1202994	Soil	41	0.72	157	0.090	1	2.06	0.012	0.17	0.1	0.02	5.9	0.1	<0.05	7	<0.5	<0.2
1202085	Soil	25	0.39	73	0.059	<1	1.43	0.009	0.30	<0.1	0.01	2.7	0.2	<0.05	6	<0.5	<0.2
1203601	Soil	32	0.93	138	0.172	<1	2.13	0.013	0.18	0.1	0.03	3.7	0.2	<0.05	7	<0.5	<0.2
1203602	Soil	129	1.61	162	0.220	<1	2.68	0.022	0.14	<0.1	0.01	4.2	<0.1	<0.05	8	<0.5	<0.2
1203603	Soil	36	1.19	149	0.214	1	2.54	0.016	0.21	<0.1	0.01	2.7	0.1	<0.05	7	<0.5	<0.2
1203604	Soil	81	0.95	164	0.187	<1	1.97	0.016	0.16	<0.1	0.01	2.1	<0.1	<0.05	7	<0.5	<0.2
1203605	Soil	52	0.76	215	0.172	1	2.35	0.013	0.18	0.1	0.02	2.7	0.2	<0.05	8	<0.5	<0.2
1203606	Soil	28	0.84	253	0.183	<1	1.93	0.024	0.36	<0.1	0.01	2.3	0.1	<0.05	7	<0.5	<0.2
1203607	Soil	50	0.98	193	0.152	2	2.60	0.017	0.06	0.1	0.02	3.6	<0.1	<0.05	7	<0.5	<0.2
1203608	Soil	75	0.90	156	0.167	<1	2.24	0.014	0.06	<0.1	0.01	2.7	<0.1	<0.05	7	<0.5	<0.2
1203609	Soil	20	0.86	195	0.211	<1	1.64	0.017	0.19	<0.1	<0.01	1.3	<0.1	<0.05	7	<0.5	<0.2
1203610	Soil	20	1.40	275	0.294	<1	2.33	0.012	0.58	<0.1	<0.01	1.3	0.2	<0.05	9	<0.5	<0.2
1203611	Soil	17	0.51	105	0.172	<1	1.11	0.014	0.17	<0.1	0.02	1.2	<0.1	<0.05	6	<0.5	<0.2
1203612	Soil	18	1.14	221	0.217	<1	1.69	0.021	0.43	<0.1	0.01	1.9	0.1	<0.05	6	<0.5	<0.2
1203613	Soil	23	1.01	257	0.165	<1	1.76	0.026	0.25	<0.1	0.02	2.3	<0.1	<0.05	6	<0.5	<0.2
1203614	Soil	15	0.42	47	0.127	<1	0.91	0.018	0.07	<0.1	0.01	1.4	<0.1	<0.05	6	<0.5	<0.2
1203615	Soil	43	1.80	185	0.254	1	3.06	0.017	0.33	<0.1	0.02	2.6	0.1	<0.05	7	<0.5	<0.2
1203616	Soil	40	0.94	162	0.128	<1	2.03	0.016	0.08	<0.1	0.02	3.7	<0.1	<0.05	8	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203617	Soil	0.7	50.7	5.8	34	<0.1	19.7	8.3	212	2.59	5.5	0.6	0.9	18	<0.1	0.3	0.1	66	0.15	0.032	4
1203618	Soil	0.9	27.7	5.6	57	<0.1	43.7	14.5	514	2.78	4.8	2.2	1.2	24	0.1	0.5	0.2	78	0.30	0.026	5
1203619	Soil	0.7	18.9	6.4	43	<0.1	14.5	13.6	748	2.16	2.4	1.3	0.7	14	<0.1	0.4	0.1	63	0.16	0.021	3
1203620	Soil	0.8	34.6	6.5	40	<0.1	16.4	9.3	205	2.36	6.6	2.6	0.9	13	<0.1	0.3	0.1	57	0.14	0.072	5
1203621	Soil	1.0	20.5	9.7	39	<0.1	22.8	17.1	349	2.97	5.5	2.1	1.4	17	<0.1	0.6	0.1	68	0.27	0.016	5
1203622	Soil	0.8	17.8	5.9	35	<0.1	20.5	11.3	138	2.30	5.3	<0.5	1.0	11	0.1	0.4	0.1	54	0.15	0.012	3
1203623	Soil	1.0	57.4	9.5	41	<0.1	43.7	13.8	196	2.77	10.9	1.4	1.7	18	<0.1	0.3	0.1	69	0.23	0.018	6
1203624	Soil	0.9	57.4	7.7	46	<0.1	41.8	15.0	248	3.13	9.4	3.5	3.0	25	<0.1	0.3	0.1	74	0.43	0.040	10
1203625	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203626	Soil	0.7	32.0	6.7	39	<0.1	24.7	11.4	267	2.59	8.0	3.4	1.7	20	<0.1	0.3	0.1	58	0.30	0.036	8
1203627	Soil	0.7	30.5	9.0	52	<0.1	27.7	12.0	266	2.48	7.9	2.3	2.3	20	0.2	0.2	0.1	60	0.32	0.043	8
1203628	Soil	0.7	19.5	8.9	43	<0.1	21.0	8.6	237	1.96	7.6	1.2	1.3	21	<0.1	0.3	0.1	50	0.31	0.037	6
1203629	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203630	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203631	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203632	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203633	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202388	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202389	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202390	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202173	Soil	1.6	58.7	11.6	95	0.5	25.8	7.8	170	3.34	13.1	3.3	8.6	24	0.2	0.3	0.2	52	0.27	0.059	24
1202176	Soil	1.1	23.2	12.2	135	<0.1	20.8	8.2	377	2.96	7.2	4.0	2.3	19	0.4	0.5	0.3	59	0.31	0.058	10
1202177	Soil	0.5	29.1	7.5	87	<0.1	24.6	14.1	417	2.64	5.5	4.2	4.0	27	0.4	0.5	0.2	73	0.41	0.063	14
1202178	Soil	0.4	28.3	11.1	86	0.1	22.8	12.0	235	2.47	4.7	2.8	3.6	20	0.2	0.3	0.2	54	0.32	0.063	13
1202179	Soil	0.5	21.8	8.9	83	<0.1	25.1	9.9	207	2.56	4.8	3.2	2.4	19	0.2	0.3	0.2	54	0.33	0.057	9
1202180	Soil	0.6	28.7	10.1	79	0.1	37.4	9.8	229	3.06	3.7	2.8	2.6	20	0.2	0.3	0.2	57	0.33	0.069	13
1202181	Soil	0.5	34.7	9.5	73	<0.1	44.1	13.2	407	3.13	4.2	4.1	4.5	24	0.2	0.2	0.1	56	0.44	0.072	13
1202861	Soil	1.0	23.6	8.1	56	<0.1	19.7	14.6	451	3.88	3.6	2.1	5.6	25	0.1	0.2	<0.1	65	0.43	0.044	17
1202862	Soil	1.1	25.3	6.4	56	0.1	19.9	12.9	433	3.49	4.2	<0.5	3.9	31	<0.1	0.2	<0.1	66	0.52	0.038	21
1202863	Soil	0.9	19.3	7.9	60	0.1	15.1	10.6	426	3.19	3.0	2.3	4.3	25	0.2	0.2	<0.1	62	0.46	0.056	21

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203617	Soil	44	0.48	86	0.102	1	1.46	0.018	0.03	<0.1	0.02	2.2	<0.1	<0.05	6	<0.5	<0.2
1203618	Soil	91	0.72	171	0.090	<1	2.06	0.020	0.03	<0.1	0.01	3.0	0.1	<0.05	7	<0.5	<0.2
1203619	Soil	27	0.33	144	0.073	1	1.25	0.018	0.03	<0.1	0.01	2.0	<0.1	<0.05	5	<0.5	<0.2
1203620	Soil	28	0.37	92	0.079	<1	1.36	0.013	0.05	0.1	0.02	2.1	<0.1	<0.05	6	<0.5	<0.2
1203621	Soil	36	0.41	127	0.069	<1	1.76	0.014	0.03	<0.1	0.01	2.4	<0.1	<0.05	6	<0.5	<0.2
1203622	Soil	29	0.43	82	0.092	<1	1.44	0.015	0.02	<0.1	0.02	1.7	<0.1	<0.05	6	<0.5	<0.2
1203623	Soil	62	0.67	103	0.101	<1	1.83	0.015	0.03	<0.1	0.02	3.0	<0.1	<0.05	6	<0.5	<0.2
1203624	Soil	52	0.75	148	0.116	1	2.17	0.019	0.04	0.1	0.02	3.8	<0.1	<0.05	6	<0.5	<0.2
1203625	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203626	Soil	33	0.53	109	0.077	<1	1.53	0.019	0.04	0.1	0.02	3.1	<0.1	<0.05	5	<0.5	<0.2
1203627	Soil	46	0.68	138	0.096	<1	1.58	0.016	0.06	0.1	0.03	2.9	<0.1	<0.05	6	<0.5	<0.2
1203628	Soil	33	0.50	95	0.075	1	1.21	0.018	0.04	0.1	0.04	2.4	<0.1	<0.05	5	<0.5	<0.2
1203629	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203630	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203631	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203632	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203633	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202388	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202389	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202390	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202173	Soil	37	0.70	306	0.066	<1	1.76	0.014	0.12	<0.1	0.03	4.5	0.1	<0.05	5	1.3	<0.2
1202176	Soil	33	0.62	168	0.075	<1	1.73	0.016	0.05	0.1	0.05	3.2	<0.1	<0.05	6	<0.5	<0.2
1202177	Soil	35	0.60	227	0.112	1	1.80	0.023	0.05	<0.1	0.02	5.4	<0.1	<0.05	5	<0.5	<0.2
1202178	Soil	36	0.65	187	0.088	<1	2.00	0.014	0.04	0.1	0.05	4.6	<0.1	<0.05	6	<0.5	<0.2
1202179	Soil	36	0.74	135	0.084	1	2.04	0.013	0.05	<0.1	0.03	3.7	<0.1	<0.05	7	<0.5	<0.2
1202180	Soil	50	0.80	133	0.090	1	2.24	0.013	0.07	<0.1	0.04	3.5	0.1	<0.05	7	<0.5	<0.2
1202181	Soil	50	0.97	155	0.122	<1	2.12	0.017	0.10	0.1	0.03	4.1	<0.1	<0.05	6	<0.5	<0.2
1202861	Soil	40	1.07	209	0.130	2	2.18	0.016	0.40	<0.1	0.02	4.9	0.2	<0.05	8	<0.5	<0.2
1202862	Soil	41	0.95	242	0.133	2	1.97	0.015	0.36	<0.1	0.02	4.0	0.2	<0.05	7	<0.5	<0.2
1202863	Soil	29	0.92	175	0.123	<1	1.72	0.022	0.32	<0.1	0.02	4.6	0.1	<0.05	7	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202864	Soil	0.8	29.2	5.9	51	<0.1	28.0	14.0	365	3.11	5.6	4.7	3.9	25	<0.1	0.4	<0.1	67	0.43	0.028	10
1202865	Soil	1.1	31.8	8.9	72	0.1	20.4	13.7	441	3.38	3.5	3.5	4.3	19	0.1	0.3	0.1	69	0.36	0.026	17
1202866	Soil	0.8	33.1	6.5	66	<0.1	18.8	12.3	472	2.95	6.1	1.1	3.6	26	<0.1	0.3	<0.1	64	0.46	0.020	14
1202867	Soil	1.0	33.5	10.3	61	0.1	17.2	9.7	372	2.72	4.6	1.2	2.9	28	0.2	0.3	0.1	49	0.45	0.024	17
1202868	Soil	1.0	48.6	4.3	74	<0.1	15.4	13.4	466	3.60	2.7	1.8	2.4	28	<0.1	0.2	<0.1	86	0.50	0.036	14
1202869	Soil	0.9	54.2	4.7	69	0.2	16.2	12.2	569	2.62	2.7	2.5	2.7	53	0.3	0.3	<0.1	48	1.22	0.060	24
1202870	Soil	1.3	38.2	9.9	54	0.2	16.1	10.9	419	2.62	3.3	3.2	4.2	42	0.1	0.3	0.1	50	0.86	0.042	48
1202076	Soil	0.5	23.7	5.4	44	<0.1	22.9	12.7	249	2.78	3.7	2.6	3.5	22	0.1	0.3	0.1	63	0.39	0.064	15
1202079	Soil	2.6	46.0	11.6	93	0.4	27.9	9.5	290	3.00	6.3	6.6	5.5	39	0.3	0.5	0.2	50	0.44	0.074	18
1202087	Soil	0.8	9.1	40.7	22	<0.1	11.0	5.7	341	1.56	4.5	1.4	24.0	13	<0.1	0.3	0.3	20	0.10	0.019	27
1202088	Soil	1.1	20.0	13.2	47	<0.1	18.0	7.4	185	2.48	6.1	1.6	1.9	20	0.5	0.3	0.2	62	0.25	0.044	19
1202089	Soil	1.0	30.6	11.3	72	<0.1	31.6	10.3	274	2.88	11.4	2.6	6.2	21	<0.1	0.4	0.2	52	0.27	0.045	19
1202090	Soil	1.1	36.1	11.4	71	<0.1	41.2	17.8	406	3.29	10.7	2.9	5.0	20	0.2	0.4	0.2	66	0.28	0.051	15
1202091	Soil	0.3	43.4	21.1	100	0.2	51.5	15.9	435	4.25	3.0	<0.5	16.3	39	0.2	0.3	0.3	56	1.33	0.095	67
1202092	Soil	1.2	23.3	12.1	69	<0.1	20.1	9.5	483	2.96	7.3	1.3	1.2	16	0.3	0.5	0.2	60	0.20	0.045	8
1202893	Soil	0.8	45.7	8.1	104	0.2	31.1	13.9	330	2.67	4.7	4.5	2.5	26	0.3	0.3	0.1	51	0.65	0.055	15
1202894	Soil	1.3	46.3	12.1	74	0.2	51.3	14.5	506	2.92	6.2	4.0	3.2	31	0.3	0.3	0.4	65	0.65	0.067	16
1202895	Soil	0.9	38.3	8.0	71	0.1	44.9	13.9	465	2.87	4.2	2.3	3.2	41	0.2	0.3	0.2	55	1.22	0.079	15
1202896	Soil	0.7	31.3	23.1	111	0.1	40.2	15.3	370	3.16	3.8	2.4	3.9	41	0.2	0.2	0.2	55	0.82	0.072	16
1202897	Soil	1.0	35.4	10.1	71	0.1	37.8	16.6	512	3.17	5.6	3.8	3.1	29	0.2	0.3	0.2	70	0.47	0.055	14
1202898	Soil	0.7	35.3	13.8	70	0.1	28.2	11.0	520	2.13	4.5	1.5	1.2	52	0.1	0.3	0.2	45	1.37	0.073	18
1202899	Soil	1.1	38.1	12.4	70	0.1	35.9	14.6	496	2.89	5.3	1.9	2.9	44	0.1	0.3	0.2	58	1.18	0.058	14
1202900	Soil	1.2	49.3	12.1	78	0.1	42.2	19.8	438	3.44	6.0	5.4	4.5	28	0.2	0.3	0.3	73	0.71	0.068	18
1202901	Soil	0.7	28.6	8.2	56	0.1	31.3	10.8	332	2.27	3.8	2.3	2.3	37	0.2	0.3	0.1	55	1.02	0.060	13
1202902	Soil	1.0	35.4	10.1	60	0.1	37.9	14.6	498	2.89	5.9	3.4	4.4	36	0.1	0.3	0.2	58	1.14	0.081	17
1202903	Soil	0.7	48.0	13.5	84	0.1	49.3	15.4	572	3.60	5.0	4.0	5.0	40	0.2	0.3	0.5	65	1.33	0.088	22
1202904	Soil	0.7	22.7	10.8	57	<0.1	30.2	12.6	348	3.03	6.3	2.4	3.3	30	<0.1	0.2	0.2	67	0.55	0.051	11
1202905	Soil	0.8	29.0	13.4	68	0.1	38.9	14.0	541	2.94	4.7	1.2	3.5	50	0.2	0.2	0.1	59	1.25	0.091	12
1202906	Soil	0.4	28.8	11.0	55	<0.1	243.6	26.1	334	2.86	9.5	4.2	3.9	35	0.1	0.6	0.1	60	0.75	0.047	14
1202907	Soil	0.4	25.7	11.0	47	<0.1	184.0	20.8	332	2.76	5.3	3.8	2.6	30	<0.1	0.2	0.3	65	0.49	0.062	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202864	Soil	48	0.86	198	0.145	1	1.86	0.024	0.27	<0.1	0.02	4.2	0.1	<0.05	5	<0.5	<0.2
1202865	Soil	32	0.99	373	0.166	1	2.04	0.016	0.59	<0.1	0.02	5.9	0.2	<0.05	6	<0.5	<0.2
1202866	Soil	32	0.93	315	0.119	2	1.83	0.019	0.49	<0.1	0.04	6.0	0.1	<0.05	6	<0.5	<0.2
1202867	Soil	25	0.63	424	0.084	2	1.57	0.019	0.24	<0.1	0.03	5.1	<0.1	<0.05	6	<0.5	<0.2
1202868	Soil	22	1.13	535	0.148	1	2.03	0.017	0.78	<0.1	0.04	5.7	0.2	<0.05	7	<0.5	<0.2
1202869	Soil	21	0.83	578	0.098	3	1.46	0.022	0.39	<0.1	0.07	5.2	0.1	<0.05	5	<0.5	<0.2
1202870	Soil	29	0.74	328	0.091	2	1.43	0.024	0.25	<0.1	0.06	4.8	0.1	<0.05	5	<0.5	<0.2
1202076	Soil	36	1.09	157	0.112	2	1.84	0.021	0.13	0.1	0.02	4.1	0.1	<0.05	5	<0.5	<0.2
1202079	Soil	30	0.57	528	0.085	1	1.48	0.030	0.14	0.1	0.03	4.4	<0.1	<0.05	4	1.4	<0.2
1202087	Soil	15	0.19	83	0.024	<1	1.04	0.008	0.06	<0.1	0.02	1.7	<0.1	<0.05	2	<0.5	<0.2
1202088	Soil	29	0.47	172	0.058	<1	1.89	0.012	0.05	<0.1	0.04	2.8	<0.1	<0.05	7	<0.5	<0.2
1202089	Soil	33	0.52	149	0.081	1	1.80	0.013	0.06	<0.1	0.04	4.9	<0.1	<0.05	5	<0.5	<0.2
1202090	Soil	40	0.81	201	0.089	2	2.43	0.015	0.10	0.1	0.02	4.2	0.1	<0.05	7	<0.5	<0.2
1202091	Soil	68	1.75	110	0.011	4	2.80	0.012	0.09	<0.1	0.04	9.9	<0.1	<0.05	11	<0.5	<0.2
1202092	Soil	28	0.53	115	0.068	2	1.82	0.014	0.07	<0.1	0.06	3.3	<0.1	<0.05	7	<0.5	<0.2
1202893	Soil	39	0.97	145	0.084	2	2.06	0.020	0.07	<0.1	0.06	4.4	0.1	<0.05	5	<0.5	<0.2
1202894	Soil	42	0.82	182	0.085	2	2.03	0.021	0.06	<0.1	0.06	4.9	<0.1	<0.05	6	0.8	<0.2
1202895	Soil	44	0.91	128	0.095	3	1.80	0.024	0.10	<0.1	0.04	3.6	0.1	0.06	5	<0.5	<0.2
1202896	Soil	41	0.96	119	0.111	2	1.93	0.024	0.09	0.1	0.04	3.7	0.1	<0.05	5	<0.5	<0.2
1202897	Soil	44	0.82	157	0.109	2	1.93	0.016	0.08	<0.1	0.03	3.5	<0.1	<0.05	6	<0.5	<0.2
1202898	Soil	32	0.56	155	0.065	3	1.73	0.024	0.06	<0.1	0.07	2.9	0.1	0.10	5	<0.5	<0.2
1202899	Soil	43	0.83	141	0.098	2	1.88	0.022	0.06	<0.1	0.05	4.0	<0.1	0.06	5	1.0	<0.2
1202900	Soil	50	1.07	188	0.096	2	2.36	0.017	0.08	<0.1	0.04	5.9	<0.1	<0.05	6	<0.5	<0.2
1202901	Soil	36	0.65	144	0.083	2	1.60	0.023	0.06	0.1	0.04	3.1	0.1	<0.05	5	0.6	<0.2
1202902	Soil	37	0.83	169	0.104	2	1.76	0.021	0.09	0.1	0.04	3.8	0.1	<0.05	5	<0.5	<0.2
1202903	Soil	55	1.50	125	0.111	2	2.22	0.030	0.11	0.1	0.04	5.4	0.2	<0.05	6	<0.5	<0.2
1202904	Soil	39	0.81	132	0.117	2	2.20	0.018	0.07	0.1	0.03	3.8	0.1	<0.05	6	<0.5	<0.2
1202905	Soil	50	1.02	134	0.103	2	1.93	0.022	0.08	0.1	0.04	3.4	0.1	<0.05	6	<0.5	<0.2
1202906	Soil	115	1.36	156	0.121	2	1.88	0.025	0.06	0.2	0.04	4.8	0.1	<0.05	6	<0.5	<0.2
1202907	Soil	87	1.22	146	0.119	2	2.00	0.022	0.05	0.1	0.03	4.1	0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202908	Soil	0.7	52.1	11.3	91	0.2	215.6	22.1	425	3.58	6.2	4.3	5.1	43	0.3	0.4	0.2	79	0.71	0.073	19
1202909	Soil	0.4	21.5	8.4	53	<0.1	127.5	16.3	320	2.76	6.3	2.3	2.3	36	<0.1	0.2	0.2	58	0.57	0.059	9
1202910	Soil	0.6	32.0	14.9	70	<0.1	37.6	13.0	303	3.25	5.8	1.9	4.1	26	<0.1	0.2	0.2	65	0.49	0.050	18
1203644	Soil	1.1	51.3	34.2	112	<0.1	22.7	8.3	423	2.89	3.2	2.4	8.3	9	<0.1	0.3	0.5	43	0.13	0.025	12
1203645	Soil	1.1	32.0	42.9	91	<0.1	20.9	11.8	787	2.91	5.2	3.8	8.6	22	0.3	0.3	0.5	53	0.23	0.036	17
1203646	Soil	1.3	36.8	46.9	103	0.1	21.6	10.7	623	2.81	6.3	4.1	10.2	27	0.3	0.4	0.6	54	0.35	0.051	18
1203647	Soil	1.1	17.6	33.2	66	<0.1	15.9	6.4	240	2.72	5.2	2.0	7.5	20	0.2	0.3	0.5	49	0.22	0.040	17
1203648	Soil	1.2	24.2	26.8	63	<0.1	16.3	7.4	326	3.48	8.2	2.3	7.8	18	0.1	0.4	0.5	54	0.21	0.044	16
1203649	Soil	1.2	11.9	22.8	58	<0.1	13.1	4.9	162	2.12	4.2	4.5	10.2	20	0.1	0.3	0.7	40	0.21	0.036	21
1203650	Soil	1.9	22.7	41.3	87	0.2	21.5	14.1	1531	2.98	5.6	2.4	10.8	28	0.3	0.4	0.5	58	0.30	0.063	43

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202908	Soil	94	1.50	190	0.148	2	2.16	0.032	0.24	0.2	0.04	5.7	0.3	<0.05	6	<0.5	<0.2
1202909	Soil	69	1.02	135	0.091	2	1.84	0.021	0.05	0.1	0.03	3.3	0.1	<0.05	5	<0.5	<0.2
1202910	Soil	45	1.00	146	0.123	2	2.20	0.018	0.09	<0.1	0.02	3.9	0.2	<0.05	6	<0.5	<0.2
1203644	Soil	38	1.73	48	0.042	<1	2.01	0.004	0.08	<0.1	0.03	3.6	0.1	<0.05	5	<0.5	<0.2
1203645	Soil	28	0.53	111	0.085	2	1.34	0.017	0.07	0.1	0.04	2.8	<0.1	0.05	4	<0.5	<0.2
1203646	Soil	33	0.62	144	0.084	2	1.70	0.018	0.08	<0.1	0.07	4.0	0.1	0.06	4	<0.5	<0.2
1203647	Soil	27	0.49	89	0.075	<1	1.28	0.012	0.07	0.1	0.09	2.3	<0.1	<0.05	4	<0.5	<0.2
1203648	Soil	29	0.51	93	0.072	<1	1.54	0.010	0.07	0.1	0.06	2.9	<0.1	0.07	4	<0.5	<0.2
1203649	Soil	23	0.47	92	0.064	1	1.24	0.009	0.07	0.1	0.05	2.1	0.1	<0.05	4	<0.5	<0.2
1203650	Soil	31	0.47	152	0.077	1	1.64	0.017	0.07	0.1	0.08	3.4	0.1	0.06	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:

Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1202884	Soil	1.4	25.7	8.3	82	0.1	25.6	12.1	569	2.77	5.6	4.1	1.2	23	0.4	0.3	0.1	68	0.33	0.065	11
REP 1202884	QC	1.3	23.9	8.3	79	0.1	24.3	11.1	528	2.54	4.9	3.6	1.2	22	0.4	0.2	0.1	64	0.31	0.061	10
1202843	Soil	2.1	29.2	26.0	106	0.1	42.3	20.3	862	4.02	12.0	3.1	11.3	23	0.3	0.5	0.3	82	0.26	0.055	31
REP 1202843	QC	2.0	28.6	25.8	106	<0.1	40.8	19.3	830	3.88	11.7	3.1	10.9	22	0.3	0.4	0.3	75	0.26	0.055	30
1202213	Soil	0.6	35.9	4.9	49	0.1	16.3	16.0	343	2.15	3.1	6.6	1.1	19	0.1	0.2	0.2	51	0.31	0.043	7
REP 1202213	QC	0.6	36.1	5.4	49	<0.1	16.0	16.0	360	2.19	3.4	2.9	1.1	20	0.1	0.3	0.1	49	0.31	0.045	7
1203638	Soil	0.4	48.5	8.5	65	<0.1	85.2	22.3	481	3.76	3.1	3.6	3.6	18	<0.1	0.2	0.3	93	0.33	0.050	8
REP 1203638	QC	0.4	47.7	8.9	65	<0.1	84.7	21.8	473	3.65	3.1	4.6	3.5	17	<0.1	0.2	0.3	90	0.33	0.050	8
1203618	Soil	0.9	27.7	5.6	57	<0.1	43.7	14.5	514	2.78	4.8	2.2	1.2	24	0.1	0.5	0.2	78	0.30	0.026	5
REP 1203618	QC	0.9	27.9	5.6	57	<0.1	44.5	14.8	518	2.81	4.8	1.3	1.2	24	0.2	0.4	0.2	74	0.29	0.025	5
1202861	Soil	1.0	23.6	8.1	56	<0.1	19.7	14.6	451	3.88	3.6	2.1	5.6	25	0.1	0.2	<0.1	65	0.43	0.044	17
REP 1202861	QC	1.1	23.9	8.1	56	<0.1	19.0	14.2	476	3.85	3.7	1.1	5.6	25	<0.1	0.2	<0.1	65	0.40	0.043	17
1202865	Soil	1.1	31.8	8.9	72	0.1	20.4	13.7	441	3.38	3.5	3.5	4.3	19	0.1	0.3	0.1	69	0.36	0.026	17
REP 1202865	QC	0.8	33.3	7.9	71	0.1	19.4	14.1	438	3.46	5.3	<0.5	4.4	19	<0.1	0.3	<0.1	71	0.36	0.026	17
1202901	Soil	0.7	28.6	8.2	56	0.1	31.3	10.8	332	2.27	3.8	2.3	2.3	37	0.2	0.3	0.1	55	1.02	0.060	13
REP 1202901	QC	0.7	28.9	8.4	56	0.2	31.6	11.0	327	2.28	3.7	1.5	2.3	36	0.1	0.3	0.1	52	0.99	0.057	12
Reference Materials																					
STD DS8	Standard	13.6	120.1	126.0	316	1.9	40.6	8.1	634	2.54	27.6	131.3	6.5	63	2.4	5.6	6.4	44	0.70	0.085	15
STD DS8	Standard	13.6	113.4	122.2	304	1.8	39.4	8.0	619	2.45	26.8	111.2	6.5	64	2.4	5.2	6.1	44	0.69	0.079	16
STD DS8	Standard	12.8	113.2	123.7	315	1.7	39.1	7.7	628	2.52	26.1	135.4	6.8	64	2.2	5.7	6.3	38	0.67	0.074	14
STD DS8	Standard	12.8	103.7	120.7	293	1.7	35.4	7.2	574	2.30	24.9	114.7	6.7	62	2.1	5.6	6.4	35	0.60	0.073	14
STD DS8	Standard	14.2	118.6	129.1	318	1.8	41.0	7.8	622	2.47	25.7	102.3	7.2	70	2.4	5.4	6.4	41	0.69	0.078	16
STD DS8	Standard	14.0	112.4	124.1	313	1.9	38.2	8.1	597	2.44	25.3	105.8	7.0	69	2.3	5.3	6.4	41	0.70	0.078	15
STD DS8	Standard	14.0	113.7	122.6	313	1.8	39.3	8.0	595	2.46	26.2	112.4	7.0	70	2.2	5.7	6.3	43	0.69	0.077	16
STD DS8	Standard	14.3	114.0	120.3	308	1.8	39.4	8.2	604	2.50	26.1	107.9	6.8	69	2.3	6.0	6.1	42	0.69	0.076	16
STD DS8	Standard	14.5	119.4	132.1	323	1.8	39.7	8.0	640	2.60	27.2	105.7	7.1	68	2.3	5.7	6.9	45	0.69	0.082	16
STD DS8	Standard	13.9	118.1	129.6	321	1.9	39.8	7.9	648	2.57	27.6	160.0	7.3	71	2.7	6.0	6.8	43	0.71	0.084	17
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:

Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000342.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1202884	Soil	35	0.61	357	0.077	<1	1.83	0.014	0.05	0.1	0.02	3.0	<0.1	<0.05	6	0.7	<0.2
REP 1202884	QC	33	0.56	335	0.073	<1	1.72	0.012	0.05	0.1	0.03	2.8	<0.1	<0.05	5	0.7	<0.2
1202843	Soil	52	0.72	176	0.120	3	2.32	0.013	0.16	0.1	0.02	4.6	0.2	<0.05	9	<0.5	<0.2
REP 1202843	QC	49	0.71	162	0.121	2	2.24	0.012	0.16	<0.1	0.01	4.4	0.2	<0.05	8	<0.5	<0.2
1202213	Soil	20	0.51	81	0.078	<1	1.42	0.015	0.04	<0.1	0.04	2.6	<0.1	<0.05	5	<0.5	<0.2
REP 1202213	QC	22	0.52	83	0.081	1	1.47	0.016	0.04	0.1	0.03	2.8	<0.1	<0.05	5	<0.5	<0.2
1203638	Soil	209	2.92	86	0.102	<1	3.06	0.010	0.05	<0.1	0.04	6.9	<0.1	<0.05	8	<0.5	<0.2
REP 1203638	QC	201	2.80	86	0.104	1	2.96	0.010	0.05	<0.1	0.04	6.9	<0.1	<0.05	8	<0.5	<0.2
1203618	Soil	91	0.72	171	0.090	<1	2.06	0.020	0.03	<0.1	0.01	3.0	0.1	<0.05	7	<0.5	<0.2
REP 1203618	QC	92	0.71	172	0.087	<1	1.98	0.019	0.03	<0.1	0.01	2.9	<0.1	<0.05	7	<0.5	<0.2
1202861	Soil	40	1.07	209	0.130	2	2.18	0.016	0.40	<0.1	0.02	4.9	0.2	<0.05	8	<0.5	<0.2
REP 1202861	QC	41	1.01	205	0.136	2	2.09	0.015	0.38	<0.1	0.02	4.7	0.2	<0.05	7	<0.5	<0.2
1202865	Soil	32	0.99	373	0.166	1	2.04	0.016	0.59	<0.1	0.02	5.9	0.2	<0.05	6	<0.5	<0.2
REP 1202865	QC	32	1.04	361	0.164	1	2.04	0.016	0.54	<0.1	0.03	5.8	0.2	<0.05	7	<0.5	<0.2
1202901	Soil	36	0.65	144	0.083	2	1.60	0.023	0.06	0.1	0.04	3.1	0.1	<0.05	5	0.6	<0.2
REP 1202901	QC	35	0.63	146	0.082	1	1.56	0.024	0.06	0.1	0.04	3.0	<0.1	<0.05	5	0.5	<0.2
Reference Materials																	
STD DS8	Standard	123	0.64	277	0.117	4	0.94	0.088	0.43	2.9	0.21	2.2	5.6	0.17	5	5.5	5.1
STD DS8	Standard	121	0.61	282	0.118	2	0.91	0.088	0.42	2.8	0.21	2.2	5.3	0.16	5	5.4	5.0
STD DS8	Standard	123	0.61	264	0.118	2	0.91	0.091	0.41	2.7	0.19	2.5	5.1	0.10	5	5.2	5.1
STD DS8	Standard	108	0.59	255	0.106	2	0.89	0.091	0.36	2.6	0.20	2.3	5.2	0.06	5	4.9	5.2
STD DS8	Standard	119	0.63	279	0.133	3	0.96	0.098	0.42	3.0	0.22	2.2	5.4	0.11	5	5.3	5.2
STD DS8	Standard	120	0.63	271	0.133	3	0.96	0.096	0.40	2.8	0.21	2.3	5.4	0.12	5	5.5	4.6
STD DS8	Standard	121	0.61	286	0.130	2	0.93	0.093	0.41	3.0	0.21	2.2	5.6	0.14	5	5.6	5.1
STD DS8	Standard	119	0.63	290	0.128	3	0.97	0.089	0.41	2.9	0.21	2.3	5.5	0.14	5	4.7	4.5
STD DS8	Standard	126	0.63	289	0.134	2	0.93	0.091	0.41	3.1	0.21	2.2	5.6	0.13	5	5.6	5.1
STD DS8	Standard	122	0.64	288	0.138	2	0.96	0.093	0.43	3.1	0.23	2.3	5.6	0.12	5	5.4	5.4
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:

Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000342.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project:

Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000342.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Submitted By: Bruce Durham
Receiving Lab: Canada-Whitehorse
Received: June 29, 2011
Report Date: August 09, 2011
Page: 1 of 9

CERTIFICATE OF ANALYSIS WHI11000350.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID: VIP-4
P.O. Number
Number of Samples: 225

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	209	Dry at 60C			WHI
SS80	209	Dry at 60C sieve 100g to -80 mesh			WHI
1DX2	208	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Daithi Mac Gearailt
Don Christie
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202348	Soil	0.9	8.5	12.3	33	<0.1	7.2	3.6	202	1.47	3.4	1.5	0.6	9	0.3	0.3	0.2	48	0.10	0.038	4
1202349	Soil	1.4	21.8	11.5	71	0.2	22.4	15.7	1567	2.69	6.4	6.1	1.8	27	0.4	0.4	0.2	68	0.47	0.117	20
1202350	Soil	1.2	25.4	8.3	45	0.2	18.2	6.3	324	2.05	5.5	2.8	0.8	34	0.2	0.4	0.2	51	0.48	0.113	30
1202351	Soil	0.8	8.1	5.2	19	<0.1	5.7	2.4	77	1.28	2.6	<0.5	0.5	9	0.1	0.2	0.1	30	0.08	0.030	4
1202352	Soil	0.5	12.2	4.5	25	<0.1	6.6	3.0	96	1.19	2.4	0.9	0.6	13	0.1	0.2	0.2	34	0.13	0.039	10
1202353	Soil	1.3	19.8	61.5	129	0.1	20.5	10.3	492	3.71	10.2	6.6	3.2	27	0.7	0.4	0.2	94	0.39	0.055	10
1202354	Soil	1.5	14.3	9.6	39	0.1	11.4	6.2	232	2.22	6.2	3.5	1.5	14	0.2	0.4	0.2	76	0.15	0.042	7
1202355	Soil	0.2	4.4	1.9	8	<0.1	1.7	1.2	50	0.38	0.9	<0.5	0.3	8	<0.1	<0.1	<0.1	11	0.08	0.015	5
1202356	Soil	0.5	6.2	3.3	14	<0.1	2.8	1.8	77	0.84	2.3	<0.5	0.3	8	<0.1	0.1	0.1	22	0.07	0.020	3
1202357	Soil	1.0	26.8	10.2	48	0.2	12.8	6.6	227	2.11	7.5	4.7	1.5	17	0.3	0.3	0.5	67	0.21	0.042	8
1202358	Soil	0.9	36.7	22.1	82	0.1	23.4	10.4	416	3.31	10.4	1.4	2.7	21	0.2	0.4	0.3	79	0.27	0.058	16
1202359	Soil	0.8	31.4	13.9	75	0.1	21.4	9.1	341	2.86	7.7	3.3	2.4	22	0.2	0.4	0.4	73	0.34	0.076	13
1202360	Soil	0.4	30.8	9.4	62	<0.1	23.0	9.5	285	2.47	4.5	8.6	4.4	30	0.2	0.4	0.2	66	0.50	0.089	18
1202361	Soil	0.6	25.3	8.7	59	<0.1	21.1	11.0	627	2.59	5.8	3.5	2.4	28	0.2	0.4	0.2	65	0.50	0.088	14
1202362	Soil	0.6	22.8	8.4	60	<0.1	21.4	10.1	363	2.60	7.1	7.3	2.2	24	0.2	0.3	0.6	67	0.37	0.076	11
1202363	Soil	0.9	18.6	8.8	44	<0.1	13.3	6.3	192	2.26	5.8	3.2	1.2	15	0.1	0.3	0.2	66	0.18	0.037	9
1202364	Soil	0.8	19.3	8.7	53	<0.1	18.1	8.7	279	2.56	7.1	1.8	2.1	19	0.1	0.4	0.3	66	0.27	0.063	17
1202365	Soil	0.5	14.6	9.8	55	<0.1	19.9	8.6	184	2.26	6.2	3.8	2.2	22	0.1	0.3	0.4	60	0.33	0.065	12
1202366	Soil	0.3	21.0	8.6	48	<0.1	20.3	10.5	267	2.50	5.8	2.6	3.6	23	0.1	0.3	0.5	62	0.37	0.076	16
1202367	Soil	0.9	23.5	4.7	26	0.2	12.3	3.0	102	1.54	3.2	2.3	0.4	41	0.2	0.3	0.2	23	0.57	0.168	32
1202368	Soil	0.8	19.4	7.3	46	0.2	17.1	6.4	171	2.14	5.3	3.4	1.4	22	0.1	0.3	0.2	52	0.29	0.059	10
1202369	Soil	0.6	19.2	6.0	45	<0.1	17.0	7.1	216	2.23	5.7	5.7	2.2	26	<0.1	0.3	0.1	57	0.42	0.069	11
1202370	Soil	0.8	19.9	6.8	47	<0.1	17.0	7.5	277	2.43	6.0	1.9	1.6	19	0.1	0.3	0.1	61	0.26	0.065	9
1202371	Soil	0.8	9.9	3.6	18	0.1	4.3	2.0	78	0.87	2.5	1.6	0.2	10	<0.1	0.2	0.1	28	0.07	0.036	3
1202372	Soil	0.5	9.0	4.1	19	0.1	5.4	2.7	77	0.94	2.1	<0.5	0.4	9	<0.1	0.2	<0.1	30	0.09	0.026	3
1202373	Soil	1.1	19.6	8.5	45	<0.1	14.4	6.3	205	2.54	6.5	1.1	1.6	16	0.2	0.4	0.2	71	0.20	0.034	6
1202374	Soil	0.9	27.2	8.8	63	0.1	22.5	11.4	418	2.71	6.5	3.8	1.7	23	0.2	0.4	0.1	72	0.35	0.070	9
1202375	Soil	0.7	35.4	15.0	74	<0.1	25.8	12.2	403	2.88	6.2	3.5	3.3	25	0.2	0.3	0.2	72	0.39	0.067	11
1202376	Soil	0.7	37.4	10.4	101	0.2	19.6	7.3	262	1.94	3.8	1.1	1.1	27	0.3	0.2	0.2	45	0.50	0.055	10
1202377	Soil	1.1	24.8	13.7	81	0.2	26.6	10.0	286	2.89	6.7	1.6	2.4	17	0.2	0.3	0.3	76	0.22	0.034	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202348	Soil	15	0.18	49	0.053	1	0.53	0.012	0.04	0.1	0.04	1.4	<0.1	0.06	4	<0.5	<0.2
1202349	Soil	37	0.63	244	0.064	2	1.98	0.018	0.09	0.2	0.07	4.7	0.1	0.13	6	0.5	<0.2
1202350	Soil	28	0.35	225	0.048	2	1.54	0.021	0.07	0.1	0.07	3.2	<0.1	0.15	5	<0.5	<0.2
1202351	Soil	12	0.13	44	0.046	<1	0.69	0.017	0.03	<0.1	0.03	1.1	<0.1	<0.05	4	<0.5	<0.2
1202352	Soil	13	0.20	76	0.045	<1	0.81	0.018	0.03	<0.1	0.03	1.5	<0.1	<0.05	3	<0.5	<0.2
1202353	Soil	32	0.53	149	0.128	2	1.85	0.014	0.08	0.1	0.04	3.6	<0.1	0.06	8	<0.5	<0.2
1202354	Soil	21	0.26	82	0.094	2	1.12	0.014	0.06	0.1	0.05	2.3	<0.1	<0.05	7	<0.5	<0.2
1202355	Soil	4	0.05	40	0.022	<1	0.25	0.023	0.03	<0.1	0.02	0.5	<0.1	<0.05	1	<0.5	<0.2
1202356	Soil	6	0.11	34	0.044	<1	0.36	0.021	0.02	<0.1	0.02	0.6	<0.1	<0.05	3	<0.5	<0.2
1202357	Soil	25	0.39	94	0.100	2	1.07	0.015	0.07	0.1	0.04	2.6	<0.1	<0.05	6	<0.5	<0.2
1202358	Soil	36	0.68	173	0.093	2	2.17	0.018	0.07	0.1	0.04	4.3	<0.1	<0.05	7	<0.5	<0.2
1202359	Soil	34	0.57	162	0.093	2	1.73	0.017	0.06	0.1	0.04	4.3	<0.1	0.06	6	0.5	<0.2
1202360	Soil	36	0.65	308	0.124	2	1.67	0.026	0.07	0.1	0.03	5.6	<0.1	<0.05	5	<0.5	<0.2
1202361	Soil	34	0.58	259	0.084	1	1.89	0.016	0.05	0.1	0.04	4.5	<0.1	<0.05	6	<0.5	<0.2
1202362	Soil	32	0.65	161	0.092	2	1.91	0.014	0.06	0.1	0.03	3.8	<0.1	<0.05	6	<0.5	<0.2
1202363	Soil	25	0.44	110	0.072	1	1.54	0.014	0.05	0.1	0.03	2.8	0.1	<0.05	7	<0.5	<0.2
1202364	Soil	29	0.49	195	0.075	<1	1.66	0.015	0.06	0.1	0.02	3.7	<0.1	<0.05	6	<0.5	<0.2
1202365	Soil	31	0.64	238	0.079	2	1.95	0.015	0.06	0.1	0.04	3.6	<0.1	<0.05	7	<0.5	<0.2
1202366	Soil	34	0.62	341	0.086	2	2.16	0.018	0.06	0.1	0.03	5.1	<0.1	<0.05	6	<0.5	<0.2
1202367	Soil	19	0.22	482	0.030	3	1.36	0.021	0.03	<0.1	0.14	3.7	<0.1	0.17	3	0.8	<0.2
1202368	Soil	28	0.43	266	0.067	1	1.70	0.016	0.05	<0.1	0.04	3.0	<0.1	<0.05	5	<0.5	<0.2
1202369	Soil	26	0.48	174	0.086	2	1.57	0.022	0.05	0.1	0.02	3.4	<0.1	<0.05	5	<0.5	<0.2
1202370	Soil	26	0.50	135	0.084	<1	1.60	0.020	0.05	0.1	0.02	2.7	<0.1	<0.05	6	<0.5	<0.2
1202371	Soil	9	0.07	50	0.039	<1	0.41	0.017	0.03	<0.1	0.04	0.7	<0.1	<0.05	3	<0.5	<0.2
1202372	Soil	10	0.15	51	0.047	<1	0.57	0.017	0.03	<0.1	0.03	1.0	<0.1	<0.05	3	<0.5	<0.2
1202373	Soil	24	0.38	99	0.093	1	1.51	0.015	0.05	0.1	0.04	2.4	<0.1	<0.05	7	<0.5	<0.2
1202374	Soil	32	0.54	193	0.089	1	1.89	0.022	0.06	0.1	0.03	3.4	<0.1	<0.05	6	<0.5	<0.2
1202375	Soil	35	0.75	176	0.113	<1	2.18	0.019	0.05	0.1	0.03	4.0	<0.1	<0.05	6	<0.5	<0.2
1202376	Soil	27	0.52	167	0.062	1	1.51	0.024	0.06	<0.1	0.04	2.9	<0.1	<0.05	5	<0.5	<0.2
1202377	Soil	35	0.62	146	0.089	<1	2.06	0.014	0.05	<0.1	0.03	3.4	0.1	<0.05	7	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202378	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202379	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202380	Soil		0.5	32.8	10.8	79	0.1	36.5	15.4	272	3.38	6.6	2.2	5.8	32	0.2	0.3	0.2	69	0.76	0.088	18
1202381	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202382	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202383	Soil		1.0	30.6	8.5	108	0.1	30.9	13.6	587	3.07	4.7	3.1	3.2	52	0.5	0.3	0.2	70	1.46	0.131	16
1202384	Soil		1.1	34.3	12.3	104	0.2	31.5	14.6	616	3.14	6.3	1.0	3.8	42	0.6	0.3	0.2	74	1.06	0.113	19
1202385	Soil		1.3	29.0	9.9	90	0.2	27.5	11.7	517	2.63	6.1	3.1	2.9	42	0.5	0.3	0.2	65	0.87	0.092	14
1202386	Soil		1.4	36.2	10.3	79	0.3	29.5	13.0	682	2.47	6.2	0.9	1.7	49	0.8	0.4	0.2	61	1.04	0.110	18
1202387	Soil		1.7	31.3	9.3	96	0.4	32.9	12.4	470	2.58	4.2	1.9	1.7	38	0.7	0.3	0.2	64	0.79	0.078	12
1202565	Soil		1.1	22.4	8.0	64	<0.1	18.6	8.5	238	2.21	3.5	4.5	1.7	18	0.2	0.3	0.2	57	0.33	0.049	6
1202566	Soil		0.7	41.5	7.7	56	<0.1	21.4	9.7	178	2.77	7.1	2.9	3.1	19	0.2	0.5	0.2	74	0.31	0.062	11
1202567	Soil		0.9	14.9	2.3	33	0.1	6.2	6.9	344	0.83	<0.5	<0.5	<0.1	33	0.5	0.3	0.1	8	0.71	0.130	4
1202568	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202569	Soil		0.8	12.1	7.7	50	<0.1	16.8	6.8	139	2.37	9.0	2.3	1.4	18	<0.1	0.3	0.1	81	0.33	0.057	6
1202570	Soil		1.5	11.8	2.1	36	<0.1	6.8	9.5	379	0.83	<0.5	<0.5	0.2	32	0.4	0.2	<0.1	6	0.61	0.115	5
1202571	Soil		1.5	9.9	2.2	28	<0.1	6.2	3.1	157	0.56	<0.5	<0.5	0.1	32	0.3	0.5	<0.1	8	0.46	0.109	5
1202572	Soil		1.3	14.4	4.6	18	0.2	7.6	4.9	153	1.06	<0.5	2.2	0.1	21	0.3	0.2	<0.1	10	0.31	0.125	7
1202573	Soil		1.9	15.6	6.9	42	0.2	13.7	8.6	327	1.51	<0.5	3.7	0.2	30	0.3	0.3	0.1	23	0.47	0.128	10
1202574	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202575	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202576	Soil		0.7	24.0	9.8	67	<0.1	22.1	11.9	294	3.06	4.9	2.5	3.7	20	0.1	0.3	0.1	58	0.31	0.054	12
1202577	Soil		0.5	23.0	9.3	60	<0.1	19.3	9.6	196	2.05	2.1	1.0	3.8	20	0.2	0.3	0.1	52	0.30	0.043	13
1202578	Soil		1.0	42.6	10.3	87	0.1	47.4	16.0	314	4.05	3.4	2.2	8.0	34	0.2	0.3	0.1	74	0.49	0.084	20
1202579	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202580	Soil		1.1	17.5	8.0	70	0.1	45.8	15.1	346	3.87	5.1	1.6	3.7	18	0.1	0.3	0.1	77	0.24	0.034	8
1202581	Soil		1.7	28.4	12.8	73	0.1	38.1	19.6	1243	3.90	3.9	4.3	5.9	34	0.2	0.2	0.3	73	0.59	0.068	21
1202582	Soil		1.0	26.2	13.7	56	0.2	27.6	12.0	365	3.17	7.5	4.5	5.8	21	0.1	0.4	0.2	71	0.26	0.032	34
1202583	Soil		2.0	39.6	11.1	93	0.8	39.6	12.7	505	3.52	9.0	4.5	3.3	21	0.6	0.4	0.2	74	0.23	0.078	14
1202584	Soil		1.9	48.8	12.3	130	<0.1	39.4	12.8	542	2.87	9.5	1.0	4.7	22	0.3	0.3	0.2	26	0.07	0.055	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202378	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202379	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202380	Soil	44	0.90	166	0.098	1	2.17	0.026	0.07	0.1	0.03	4.5	<0.1	<0.05	7	0.6	<0.2
1202381	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202382	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202383	Soil	47	0.77	225	0.069	2	1.74	0.024	0.09	0.1	0.10	4.9	<0.1	0.09	6	0.6	<0.2
1202384	Soil	45	0.75	208	0.075	2	1.94	0.023	0.07	<0.1	0.07	5.3	<0.1	0.08	6	0.8	<0.2
1202385	Soil	36	0.63	194	0.065	2	1.63	0.021	0.06	0.1	0.07	4.1	<0.1	0.07	5	0.7	<0.2
1202386	Soil	37	0.54	270	0.052	1	1.61	0.023	0.06	<0.1	0.08	3.7	<0.1	0.11	5	0.7	<0.2
1202387	Soil	39	0.64	208	0.044	3	1.53	0.016	0.06	0.1	0.06	3.0	<0.1	0.09	5	0.8	<0.2
1202565	Soil	29	0.58	115	0.076	2	1.38	0.015	0.06	0.2	0.04	2.2	<0.1	<0.05	5	<0.5	<0.2
1202566	Soil	34	0.62	169	0.083	2	1.87	0.015	0.04	0.1	0.04	3.8	<0.1	<0.05	5	<0.5	<0.2
1202567	Soil	8	0.08	130	0.011	4	0.33	0.032	0.07	<0.1	0.14	0.8	<0.1	0.24	<1	<0.5	<0.2
1202568	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202569	Soil	29	0.52	127	0.073	1	1.55	0.012	0.05	0.2	0.05	2.3	<0.1	<0.05	6	<0.5	<0.2
1202570	Soil	9	0.08	121	0.009	5	0.29	0.025	0.08	<0.1	0.13	0.9	<0.1	0.21	<1	<0.5	<0.2
1202571	Soil	9	0.08	118	0.012	4	0.32	0.022	0.07	<0.1	0.15	1.0	<0.1	0.16	<1	1.0	<0.2
1202572	Soil	14	0.07	93	0.008	2	0.44	0.018	0.04	<0.1	0.14	0.6	<0.1	0.17	<1	0.6	<0.2
1202573	Soil	19	0.26	130	0.028	3	0.82	0.026	0.07	<0.1	0.15	1.5	<0.1	0.12	3	<0.5	<0.2
1202574	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202575	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202576	Soil	36	0.68	158	0.077	<1	1.91	0.011	0.05	<0.1	0.03	3.7	<0.1	<0.05	6	<0.5	<0.2
1202577	Soil	33	0.62	171	0.087	<1	1.60	0.012	0.05	<0.1	0.01	3.8	<0.1	<0.05	5	<0.5	<0.2
1202578	Soil	64	1.03	223	0.125	<1	2.33	0.012	0.39	<0.1	0.03	5.2	0.3	<0.05	7	0.6	<0.2
1202579	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202580	Soil	66	1.04	161	0.117	<1	2.59	0.011	0.29	0.1	0.01	2.5	0.2	<0.05	7	<0.5	<0.2
1202581	Soil	55	0.95	196	0.084	2	2.39	0.012	0.16	<0.1	0.04	4.8	0.5	<0.05	8	0.7	<0.2
1202582	Soil	42	0.65	208	0.083	2	2.32	0.013	0.06	0.1	0.04	4.9	0.1	<0.05	6	0.6	<0.2
1202583	Soil	45	0.60	207	0.042	2	2.21	0.011	0.08	<0.1	0.07	5.1	0.4	<0.05	6	1.0	<0.2
1202584	Soil	19	0.12	108	0.004	<1	0.46	0.003	0.08	<0.1	0.03	3.2	0.1	<0.05	1	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202585	Soil	0.4	7.7	3.9	14	<0.1	6.8	2.9	61	0.99	0.6	2.3	0.2	9	<0.1	0.1	<0.1	22	0.08	0.034	4
1202445	Soil	1.9	26.6	11.0	102	0.2	33.1	13.3	459	2.94	7.4	2.9	3.6	28	0.6	0.3	0.2	76	0.43	0.055	12
1202446	Soil	2.0	28.9	11.2	92	0.3	27.9	13.4	495	2.69	6.7	1.4	2.4	25	0.5	0.3	0.2	72	0.37	0.075	12
1202447	Soil	1.4	26.4	10.3	90	0.2	26.4	13.8	443	2.66	6.5	2.7	2.8	27	0.4	0.3	0.2	67	0.39	0.064	14
1202448	Soil	1.4	23.0	8.9	87	0.2	25.0	11.0	414	2.77	5.8	3.6	2.7	30	0.3	0.3	0.2	67	0.48	0.077	12
1202449	Soil	2.5	42.7	11.0	91	0.3	34.1	9.9	474	2.30	9.1	2.8	4.0	70	0.6	0.3	0.2	45	1.34	0.065	27
1202450	Soil	2.0	47.1	13.5	85	0.3	40.9	11.7	586	2.62	9.2	11.2	8.0	57	0.9	0.5	0.2	48	0.99	0.067	61
1202451	Soil	1.9	52.0	11.5	116	<0.1	61.2	21.9	431	4.34	2.9	0.9	19.8	28	0.2	0.1	0.2	53	0.41	0.118	34
1202452	Soil	2.6	40.8	15.7	94	0.3	36.4	12.5	393	3.49	30.8	1.3	10.0	33	1.0	0.6	0.4	52	0.45	0.060	48
1202453	Soil	1.6	35.9	8.6	64	0.2	29.1	12.6	469	2.75	5.4	0.9	5.1	42	0.5	0.2	0.2	69	0.62	0.046	25
1202454	Soil	1.5	34.5	9.6	87	0.1	39.6	14.1	388	3.48	4.9	0.7	6.7	32	0.4	0.2	0.2	72	0.49	0.066	24
1202455	Soil	1.5	33.1	8.6	92	0.2	38.2	14.0	404	3.10	6.0	2.1	6.5	31	0.3	0.2	0.3	65	0.49	0.065	19
1202456	Soil	2.3	41.9	12.0	130	0.4	43.8	20.7	932	3.26	6.7	1.3	7.9	42	0.9	0.3	0.2	71	0.69	0.082	41
1202457	Soil	1.4	25.4	5.5	70	0.3	24.0	6.4	190	1.80	3.8	<0.5	1.9	37	0.7	0.2	0.2	45	0.71	0.044	14
1202458	Soil	1.9	36.8	9.1	101	0.2	45.1	17.7	452	3.61	9.6	1.3	4.6	27	0.4	0.3	0.2	83	0.41	0.057	16
1202459	Soil	1.3	54.9	8.2	67	0.1	53.1	18.3	329	3.51	6.9	2.0	5.1	25	0.1	0.3	0.1	78	0.40	0.085	19
1202460	Soil	1.3	50.7	7.1	74	<0.1	75.8	23.0	315	4.43	5.5	1.2	5.2	21	<0.1	0.2	0.1	113	0.34	0.107	15
1202461	Soil	1.1	23.0	9.4	62	<0.1	30.8	15.1	216	3.46	7.4	1.5	9.1	11	0.1	0.4	0.2	67	0.12	0.034	8
1202462	Soil	0.7	54.3	7.2	61	0.1	25.1	12.5	279	2.65	5.9	2.9	1.5	22	0.2	0.3	0.1	63	0.37	0.087	10
1202463	Soil	0.8	57.0	5.6	51	<0.1	28.2	12.5	330	2.90	6.8	3.0	2.2	22	0.1	0.4	<0.1	70	0.32	0.029	8
1202464	Soil	0.8	40.3	8.3	53	<0.1	37.9	15.0	364	3.19	7.7	1.4	4.0	21	<0.1	0.3	0.1	77	0.28	0.037	12
1202465	Soil	0.5	28.4	11.6	59	<0.1	38.5	15.9	486	3.46	5.2	<0.5	3.5	18	<0.1	0.4	<0.1	87	0.33	0.059	18
1202466	Soil	1.0	17.0	8.1	64	<0.1	16.4	9.8	333	3.13	7.7	3.7	2.3	16	0.1	0.3	0.2	73	0.21	0.059	7
1202467	Soil	0.2	44.6	7.3	57	<0.1	26.6	11.7	311	2.37	5.6	21.8	1.5	39	0.3	0.3	0.2	60	1.85	0.061	8
1202468	Soil	0.9	27.9	6.0	37	0.1	13.7	6.1	166	1.98	5.4	5.3	0.8	22	<0.1	0.2	0.1	47	0.21	0.042	7
1202469	Soil	0.5	63.9	3.6	65	0.1	15.1	12.6	329	2.35	2.5	2.3	0.4	11	<0.1	0.1	<0.1	75	0.14	0.030	2
1202470	Soil	0.7	46.8	8.2	47	0.3	16.0	8.5	251	2.23	3.8	3.8	0.3	20	0.1	0.1	0.1	50	0.22	0.065	11
1202471	Soil	1.3	26.1	7.2	61	<0.1	17.0	11.5	320	3.03	8.1	1.7	2.3	16	1.0	1.1	2.1	76	0.17	0.033	7
1202472	Soil	4.1	110.3	7.9	62	0.2	14.8	8.4	270	3.61	5.0	4.7	2.7	37	0.2	0.4	0.7	76	0.19	0.038	9
1202473	Soil	0.7	18.7	6.9	47	<0.1	13.2	9.5	260	2.51	5.0	1.7	1.5	12	0.2	0.2	0.3	74	0.14	0.031	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202585	Soil	11	0.11	49	0.032	1	0.66	0.016	0.05	<0.1	0.03	0.7	<0.1	<0.05	3	<0.5	<0.2
1202445	Soil	45	0.68	182	0.071	1	1.69	0.015	0.06	0.1	0.03	3.7	0.1	<0.05	6	0.6	<0.2
1202446	Soil	40	0.52	155	0.048	<1	1.54	0.015	0.05	0.1	0.04	3.6	<0.1	<0.05	5	1.3	<0.2
1202447	Soil	37	0.56	179	0.053	2	1.49	0.015	0.05	0.1	0.05	3.4	<0.1	<0.05	5	1.1	<0.2
1202448	Soil	38	0.66	164	0.070	2	1.66	0.020	0.05	0.1	0.03	3.3	<0.1	<0.05	5	0.8	<0.2
1202449	Soil	30	0.50	272	0.039	3	1.16	0.013	0.17	<0.1	0.05	2.9	0.1	0.09	4	3.4	<0.2
1202450	Soil	37	0.64	331	0.058	1	1.47	0.013	0.23	<0.1	0.06	3.9	0.1	<0.05	5	2.4	<0.2
1202451	Soil	61	1.48	212	0.131	1	2.40	0.008	0.77	<0.1	0.02	3.5	0.5	<0.05	8	1.2	<0.2
1202452	Soil	32	0.50	268	0.034	2	1.46	0.011	0.18	<0.1	0.02	4.1	<0.1	<0.05	5	<0.5	<0.2
1202453	Soil	40	0.68	406	0.096	1	1.77	0.019	0.18	<0.1	0.04	3.5	0.1	<0.05	7	<0.5	<0.2
1202454	Soil	50	0.96	390	0.118	<1	2.07	0.014	0.34	<0.1	0.02	3.3	0.2	<0.05	7	0.5	<0.2
1202455	Soil	49	0.86	252	0.097	<1	1.81	0.013	0.32	<0.1	0.01	3.2	0.2	<0.05	6	0.6	<0.2
1202456	Soil	58	0.80	449	0.084	2	2.00	0.017	0.25	<0.1	0.02	4.4	0.1	<0.05	7	0.6	<0.2
1202457	Soil	30	0.45	201	0.047	1	1.08	0.019	0.09	0.1	0.04	2.3	<0.1	<0.05	4	0.6	<0.2
1202458	Soil	51	0.71	243	0.081	<1	2.14	0.013	0.11	0.1	0.02	3.3	<0.1	<0.05	6	<0.5	<0.2
1202459	Soil	76	0.98	239	0.122	<1	2.23	0.013	0.21	<0.1	0.02	3.3	0.2	<0.05	7	0.8	<0.2
1202460	Soil	154	1.95	317	0.223	<1	3.02	0.012	0.65	<0.1	<0.01	3.9	0.3	<0.05	12	<0.5	<0.2
1202461	Soil	34	0.66	161	0.082	<1	2.50	0.008	0.13	0.1	0.02	2.2	0.2	<0.05	7	<0.5	<0.2
1202462	Soil	38	0.72	155	0.083	1	2.12	0.015	0.07	0.1	0.03	3.0	<0.1	<0.05	6	<0.5	<0.2
1202463	Soil	43	0.78	152	0.078	<1	2.06	0.017	0.05	<0.1	0.02	3.4	<0.1	<0.05	6	<0.5	<0.2
1202464	Soil	86	0.97	163	0.102	<1	2.72	0.011	0.08	0.1	0.02	3.8	0.1	<0.05	7	<0.5	<0.2
1202465	Soil	85	1.40	99	0.012	<1	2.37	0.006	0.03	<0.1	0.04	9.3	<0.1	<0.05	8	<0.5	<0.2
1202466	Soil	34	0.73	142	0.093	<1	2.30	0.010	0.15	<0.1	0.03	2.4	0.2	<0.05	7	<0.5	<0.2
1202467	Soil	42	0.74	139	0.066	2	1.88	0.024	0.04	0.1	0.06	3.5	<0.1	0.07	5	0.8	<0.2
1202468	Soil	26	0.45	158	0.067	<1	1.72	0.016	0.07	<0.1	0.03	1.9	<0.1	<0.05	6	<0.5	<0.2
1202469	Soil	21	1.13	157	0.143	<1	1.71	0.013	0.34	<0.1	0.02	1.0	0.1	<0.05	6	<0.5	<0.2
1202470	Soil	27	0.56	283	0.061	<1	1.78	0.020	0.16	<0.1	0.05	2.6	0.1	<0.05	5	<0.5	<0.2
1202471	Soil	30	0.64	170	0.096	9	2.21	0.014	0.20	<0.1	0.02	3.0	0.1	<0.05	8	<0.5	<0.2
1202472	Soil	30	0.91	250	0.092	3	2.48	0.081	0.37	<0.1	0.02	4.3	0.2	0.47	6	1.8	<0.2
1202473	Soil	28	0.79	152	0.111	2	2.03	0.013	0.13	<0.1	0.02	2.6	<0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202474	Soil	0.7	27.7	6.0	122	<0.1	15.1	8.1	205	2.46	3.0	<0.5	1.9	11	0.4	0.2	0.2	61	0.14	0.048	11
1202475	Soil	0.9	11.9	6.8	35	<0.1	8.9	4.4	102	2.25	6.9	2.3	1.4	10	0.1	0.3	0.2	52	0.09	0.024	5
1202476	Soil	0.9	35.6	7.0	52	<0.1	18.7	11.1	235	3.31	7.8	2.2	2.4	13	0.2	0.4	0.2	84	0.16	0.027	6
1202477	Soil	1.1	14.5	8.9	50	<0.1	15.6	10.1	348	3.08	8.1	1.2	1.8	14	0.1	0.5	0.2	82	0.17	0.037	6
1202478	Soil	0.6	37.6	6.0	64	<0.1	23.6	14.7	461	2.97	5.8	7.8	1.8	22	0.1	0.3	0.1	78	0.35	0.060	7
1202479	Soil	0.7	37.6	8.6	61	<0.1	17.4	13.9	325	3.07	6.3	1.3	1.6	16	0.4	0.3	0.1	89	0.28	0.044	5
1202480	Soil	0.9	18.9	8.0	47	<0.1	13.8	8.4	267	2.70	5.6	1.2	1.6	14	0.1	0.3	0.1	74	0.19	0.027	6
1202481	Soil	0.5	19.9	5.2	64	<0.1	13.9	8.5	295	2.65	4.3	1.7	1.1	10	0.1	0.2	<0.1	62	0.14	0.030	4
1202482	Soil	0.9	17.4	8.4	39	<0.1	11.2	7.0	231	2.16	4.3	1.5	2.5	18	<0.1	0.2	0.1	50	0.17	0.028	14
1202483	Soil	0.8	38.5	8.5	71	<0.1	25.3	17.8	372	3.95	7.0	2.7	2.8	28	<0.1	0.3	0.2	86	0.24	0.045	8
1202484	Soil	2.0	52.4	7.4	54	<0.1	12.6	8.3	241	3.87	5.6	5.6	2.1	30	0.1	0.3	0.3	95	0.14	0.047	7
1202485	Soil	2.1	82.5	4.8	67	0.2	11.9	7.9	225	4.91	4.3	5.9	2.6	41	<0.1	0.2	0.3	116	0.18	0.060	9
1202486	Soil	0.9	35.2	8.8	77	0.1	18.6	15.8	437	3.97	6.6	1.8	3.0	15	0.1	0.3	0.3	100	0.21	0.046	11
1202487	Soil	0.8	24.8	5.4	60	<0.1	15.1	11.4	375	3.24	5.9	1.8	1.7	21	0.1	0.3	<0.1	77	0.23	0.056	8
1202488	Soil	1.0	19.4	6.4	71	0.1	16.9	12.2	335	3.83	7.0	1.8	2.6	14	<0.1	0.3	0.1	83	0.18	0.038	10
1202489	Soil	0.8	31.2	6.1	81	<0.1	14.6	11.3	446	3.09	4.4	2.3	2.0	26	0.2	0.2	<0.1	69	0.32	0.057	6
1202490	Soil	0.8	16.2	6.4	43	<0.1	15.7	9.0	243	2.58	5.4	0.9	1.8	18	0.1	0.3	0.1	64	0.23	0.031	5
1202491	Soil	1.1	23.8	11.1	75	<0.1	25.6	14.9	464	3.40	6.5	<0.5	3.4	18	0.1	0.3	0.1	80	0.30	0.032	10
1202492	Soil	1.0	32.8	6.9	48	<0.1	17.6	12.2	231	3.01	6.8	2.7	1.3	17	<0.1	0.4	<0.1	81	0.27	0.030	4
1202493	Soil	0.6	16.8	4.2	56	<0.1	10.4	8.7	319	2.18	2.7	<0.5	0.6	11	<0.1	0.1	<0.1	65	0.18	0.035	3
1202494	Soil	0.6	9.0	8.7	37	<0.1	8.3	3.6	106	1.29	2.3	3.9	0.9	14	<0.1	0.2	0.1	45	0.20	0.027	5
1202495	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202496	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202497	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202498	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202499	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202500	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202161	Soil	0.8	30.6	9.9	60	<0.1	41.8	17.5	412	3.39	4.7	2.4	7.5	28	0.1	0.2	0.1	89	0.55	0.087	20
1202162	Soil	0.7	48.1	7.8	100	0.1	40.3	20.8	675	4.49	4.4	3.9	4.0	42	0.2	0.2	0.2	117	0.75	0.078	13
1202163	Soil	1.2	59.1	13.9	69	0.3	31.2	12.6	447	3.70	6.2	17.1	9.2	45	0.1	0.4	5.7	88	0.60	0.070	29

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202474	Soil	19	0.57	175	0.072	1	1.39	0.019	0.22	<0.1	0.02	2.0	0.2	<0.05	5	<0.5	<0.2
1202475	Soil	20	0.19	110	0.057	<1	1.57	0.013	0.04	<0.1	0.02	1.5	<0.1	<0.05	6	<0.5	<0.2
1202476	Soil	34	0.76	112	0.119	1	2.47	0.014	0.08	0.1	0.04	2.8	<0.1	<0.05	7	<0.5	<0.2
1202477	Soil	29	0.40	154	0.065	<1	1.81	0.011	0.06	<0.1	0.02	1.9	0.1	<0.05	7	<0.5	<0.2
1202478	Soil	30	0.90	206	0.109	<1	1.94	0.017	0.16	<0.1	0.01	2.7	<0.1	<0.05	5	<0.5	<0.2
1202479	Soil	25	0.71	108	0.108	<1	2.05	0.019	0.09	<0.1	0.03	2.9	<0.1	<0.05	6	<0.5	<0.2
1202480	Soil	24	0.45	147	0.103	<1	1.73	0.016	0.08	<0.1	0.03	2.6	<0.1	<0.05	7	<0.5	<0.2
1202481	Soil	23	0.53	88	0.098	<1	1.54	0.014	0.13	<0.1	0.02	2.5	<0.1	<0.05	5	<0.5	<0.2
1202482	Soil	22	0.34	160	0.077	<1	1.61	0.017	0.10	<0.1	0.04	2.5	<0.1	<0.05	6	<0.5	<0.2
1202483	Soil	38	1.12	220	0.096	<1	2.91	0.025	0.14	<0.1	0.03	4.9	0.1	<0.05	7	<0.5	<0.2
1202484	Soil	37	0.76	354	0.104	<1	2.05	0.044	0.36	<0.1	0.03	5.8	0.1	0.30	8	1.2	<0.2
1202485	Soil	22	1.03	288	0.104	<1	2.63	0.131	0.57	<0.1	0.03	7.2	0.2	0.75	8	2.7	0.4
1202486	Soil	23	1.02	213	0.124	<1	2.22	0.011	0.31	<0.1	0.03	4.7	0.2	<0.05	8	<0.5	<0.2
1202487	Soil	26	0.92	205	0.104	<1	2.12	0.018	0.22	<0.1	0.02	3.4	<0.1	<0.05	7	<0.5	<0.2
1202488	Soil	26	0.94	344	0.133	<1	2.35	0.012	0.18	0.1	0.02	4.2	0.1	<0.05	8	<0.5	<0.2
1202489	Soil	23	0.94	352	0.115	<1	1.90	0.028	0.26	<0.1	0.03	3.8	0.1	0.08	6	<0.5	<0.2
1202490	Soil	28	0.49	154	0.080	<1	1.78	0.016	0.08	<0.1	0.01	2.3	<0.1	<0.05	5	<0.5	<0.2
1202491	Soil	41	0.97	239	0.100	<1	2.21	0.015	0.25	<0.1	0.02	3.4	0.1	<0.05	7	<0.5	<0.2
1202492	Soil	25	0.60	158	0.090	<1	1.92	0.015	0.11	<0.1	0.02	2.1	<0.1	<0.05	6	<0.5	<0.2
1202493	Soil	29	0.59	78	0.090	<1	0.96	0.016	0.20	<0.1	0.02	1.4	<0.1	<0.05	5	<0.5	<0.2
1202494	Soil	21	0.34	63	0.099	<1	0.92	0.012	0.06	0.1	0.04	1.7	<0.1	<0.05	6	<0.5	<0.2
1202495	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202496	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202497	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202498	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202499	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202500	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202161	Soil	99	1.61	268	0.166	<1	2.51	0.022	0.53	0.1	0.03	5.7	0.3	<0.05	8	<0.5	<0.2
1202162	Soil	81	2.56	166	0.209	4	3.55	0.039	0.82	0.1	0.03	12.6	0.7	0.12	9	<0.5	<0.2
1202163	Soil	83	1.25	189	0.155	3	2.65	0.037	0.32	0.2	0.04	8.7	0.3	0.07	7	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202164	Soil	0.8	40.8	9.5	65	<0.1	33.5	14.7	509	3.59	4.8	4.5	4.6	30	0.2	0.4	0.3	100	0.48	0.068	20
1202165	Soil	0.9	37.1	9.5	53	0.1	27.9	17.3	395	2.51	3.8	2.5	2.0	51	<0.1	0.4	0.2	74	0.46	0.083	9
1202167	Soil	0.6	59.3	23.7	79	0.1	331.2	30.3	409	3.38	21.0	6.4	4.8	30	0.2	2.0	0.2	66	0.47	0.055	17
1202168	Soil	0.5	35.6	12.5	71	0.2	157.1	28.5	564	3.62	7.7	4.2	4.4	40	0.1	0.3	0.3	77	0.59	0.061	15
1202169	Soil	1.0	29.0	11.6	51	0.1	26.1	11.2	182	3.05	7.1	5.6	3.0	34	0.2	0.4	0.2	71	0.63	0.029	18
1202170	Soil	1.1	37.7	12.2	79	0.3	42.9	17.8	488	4.01	7.8	3.0	6.6	27	0.2	0.4	0.1	70	0.26	0.036	17
1202171	Soil	0.7	38.9	11.4	76	<0.1	42.7	17.3	445	3.99	7.3	2.6	10.3	25	0.2	0.3	0.2	76	0.28	0.026	28
1202172	Soil	0.4	32.6	6.6	62	<0.1	38.9	12.9	340	2.87	5.0	1.6	3.3	39	0.1	0.4	0.1	70	0.59	0.082	13
1202600	Soil	1.1	18.0	9.8	85	<0.1	15.8	8.4	405	2.19	5.1	2.9	1.0	33	0.4	0.4	0.2	50	0.60	0.064	9
1202741	Soil	0.8	64.6	10.8	78	<0.1	35.0	15.8	646	3.06	4.3	6.0	2.1	57	0.3	0.3	0.1	76	1.48	0.077	10
1202742	Soil	0.7	55.2	5.8	75	<0.1	34.0	15.9	542	2.98	4.3	5.0	1.8	44	0.2	0.2	<0.1	78	1.30	0.088	7
1202743	Soil	0.6	54.8	5.7	89	<0.1	21.4	15.9	515	3.14	4.7	0.8	1.6	46	0.3	12.8	<0.1	76	1.35	0.087	8
1202744	Soil	0.7	37.2	6.0	92	<0.1	20.1	16.4	397	3.53	6.5	2.1	1.8	38	<0.1	0.2	<0.1	88	0.68	0.081	6
1202745	Soil	1.2	35.7	8.3	86	0.1	21.1	14.4	493	3.54	6.3	4.4	2.3	39	0.2	0.3	0.1	86	0.62	0.067	11
1202746	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202747	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202748	Soil	2.1	21.2	10.5	58	0.2	16.4	5.2	216	2.33	10.3	1.2	0.8	18	0.5	0.3	0.2	73	0.17	0.071	10
1202749	Soil	1.8	44.8	8.1	39	0.8	15.2	7.6	425	1.98	6.6	2.9	2.0	15	0.4	0.3	0.2	42	0.10	0.044	12
1202750	Soil	2.5	45.4	11.7	78	0.1	31.8	11.6	432	3.76	13.1	4.2	3.6	23	0.3	0.6	0.2	80	0.19	0.039	13
1202801	Soil	1.4	35.0	8.2	42	0.2	16.5	5.7	188	2.28	10.2	5.9	1.5	21	0.3	0.4	0.2	53	0.17	0.034	9
1202802	Soil	3.5	34.5	12.8	56	0.4	20.2	8.0	247	2.99	11.6	3.5	2.9	23	0.3	0.6	0.2	85	0.18	0.039	12
1202803	Soil	3.4	31.0	14.3	58	0.4	21.3	8.1	219	3.91	13.9	4.1	2.6	23	0.3	0.8	0.2	113	0.17	0.051	11
1202804	Soil	3.6	67.2	13.2	107	0.6	44.4	13.4	699	3.58	14.0	3.4	3.7	39	1.0	0.7	0.2	91	0.34	0.062	12
1202805	Soil	1.8	43.8	13.3	89	0.2	38.1	15.5	352	3.98	12.0	3.0	4.2	23	0.5	0.6	0.2	87	0.18	0.042	13
1202806	Soil	1.5	32.2	16.3	73	0.3	29.3	8.4	245	2.80	11.7	2.2	4.3	18	0.4	0.7	0.2	46	0.15	0.040	18
1202807	Soil	3.1	33.1	13.8	78	0.2	24.6	7.5	326	3.00	16.8	1.6	3.1	21	0.4	0.7	0.2	65	0.06	0.080	19
1202808	Soil	1.5	38.6	13.2	88	0.3	35.9	9.5	333	3.04	5.7	3.8	3.8	21	0.3	0.5	0.2	68	0.17	0.039	20
1202809	Soil	1.7	29.8	15.6	82	0.1	32.8	11.6	222	3.53	11.5	<0.5	4.7	19	0.4	0.8	0.2	71	0.13	0.038	19
1202810	Soil	1.2	18.3	13.7	63	0.1	17.6	6.1	190	2.68	28.8	2.8	2.2	15	0.4	0.5	0.2	63	0.09	0.036	12
1202701	Soil	0.4	30.3	8.8	69	<0.1	23.3	10.0	186	2.99	7.1	3.3	2.4	26	0.2	0.5	0.2	66	0.36	0.083	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202164	Soil	68	1.10	302	0.142	2	2.46	0.026	0.11	<0.1	0.03	8.2	0.2	0.05	7	<0.5	<0.2
1202165	Soil	45	0.92	272	0.089	1	3.51	0.037	0.07	<0.1	0.03	3.2	0.3	0.09	8	<0.5	<0.2
1202167	Soil	174	2.00	138	0.113	4	2.34	0.023	0.07	0.1	0.03	5.1	0.2	0.09	7	<0.5	<0.2
1202168	Soil	85	1.32	172	0.098	2	2.42	0.023	0.05	0.1	0.03	5.7	0.1	0.08	7	<0.5	<0.2
1202169	Soil	37	0.59	152	0.080	2	2.28	0.016	0.07	<0.1	0.03	3.4	0.1	0.06	8	<0.5	<0.2
1202170	Soil	53	0.98	200	0.138	2	2.79	0.018	0.38	<0.1	0.03	5.2	0.3	<0.05	7	<0.5	<0.2
1202171	Soil	54	0.94	218	0.121	1	2.84	0.016	0.16	<0.1	0.02	6.0	0.2	<0.05	8	<0.5	<0.2
1202172	Soil	34	0.74	124	0.105	2	1.56	0.041	0.05	0.1	0.02	4.0	<0.1	<0.05	5	<0.5	<0.2
1202600	Soil	23	0.45	161	0.053	3	1.39	0.033	0.06	0.1	0.07	2.7	<0.1	<0.05	5	<0.5	<0.2
1202741	Soil	66	1.40	256	0.127	2	2.11	0.028	0.16	<0.1	0.04	4.8	0.1	<0.05	6	<0.5	<0.2
1202742	Soil	65	1.24	252	0.140	2	1.83	0.027	0.30	<0.1	0.03	3.7	0.1	<0.05	6	<0.5	<0.2
1202743	Soil	38	1.10	411	0.151	2	2.06	0.029	0.32	<0.1	0.02	3.6	0.1	0.05	6	0.5	<0.2
1202744	Soil	34	1.30	288	0.183	<1	2.32	0.024	0.27	<0.1	0.01	3.4	0.1	<0.05	7	<0.5	<0.2
1202745	Soil	36	0.98	359	0.161	2	2.24	0.025	0.24	<0.1	0.02	4.4	0.1	<0.05	7	0.6	<0.2
1202746	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202747	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202748	Soil	29	0.34	125	0.079	1	1.38	0.016	0.08	<0.1	0.03	2.3	<0.1	0.12	8	0.5	<0.2
1202749	Soil	23	0.24	158	0.057	<1	1.73	0.022	0.04	<0.1	0.05	3.0	<0.1	<0.05	5	<0.5	<0.2
1202750	Soil	45	0.64	155	0.094	1	2.42	0.012	0.06	<0.1	0.05	3.8	0.1	<0.05	8	0.7	<0.2
1202801	Soil	23	0.35	139	0.055	<1	1.62	0.020	0.05	<0.1	0.02	2.7	<0.1	<0.05	6	<0.5	<0.2
1202802	Soil	35	0.42	296	0.078	2	1.94	0.012	0.06	<0.1	0.03	4.0	<0.1	<0.05	7	0.7	<0.2
1202803	Soil	43	0.45	319	0.094	<1	2.33	0.013	0.05	<0.1	0.04	4.2	0.1	<0.05	10	<0.5	<0.2
1202804	Soil	43	0.54	519	0.072	2	2.54	0.014	0.12	<0.1	0.05	4.5	0.1	<0.05	7	0.9	<0.2
1202805	Soil	52	0.67	254	0.084	<1	3.06	0.014	0.06	<0.1	0.03	4.8	0.1	<0.05	8	0.6	<0.2
1202806	Soil	27	0.28	129	0.040	<1	1.39	0.013	0.07	<0.1	0.03	2.7	<0.1	<0.05	5	<0.5	<0.2
1202807	Soil	27	0.19	182	0.037	<1	0.95	0.010	0.08	<0.1	0.01	2.6	<0.1	<0.05	5	1.2	<0.2
1202808	Soil	46	0.48	243	0.064	<1	1.94	0.013	0.08	<0.1	0.04	3.9	0.2	<0.05	7	0.5	<0.2
1202809	Soil	31	0.36	145	0.054	<1	1.86	0.012	0.06	<0.1	0.01	3.4	<0.1	<0.05	7	0.6	<0.2
1202810	Soil	22	0.26	83	0.060	<1	1.31	0.012	0.06	<0.1	<0.01	1.7	<0.1	<0.05	6	<0.5	<0.2
1202701	Soil	38	0.67	210	0.093	<1	1.98	0.021	0.07	0.1	0.03	4.7	<0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202702	Soil		1.0	10.2	8.3	20	<0.1	4.7	2.3	90	1.38	3.0	2.3	0.2	10	0.1	0.3	0.2	44	0.06	0.025	6
1202703	Soil		1.7	26.1	11.2	67	0.1	18.0	7.5	224	3.35	9.2	9.2	1.8	18	0.3	0.7	0.2	71	0.13	0.057	12
1202704	Soil		0.8	26.1	21.1	74	0.1	24.4	7.8	269	2.51	20.2	4.0	1.4	15	0.4	0.7	0.2	34	0.13	0.069	26
1202705	Soil		0.9	29.9	9.7	65	0.2	23.6	11.7	438	2.49	6.1	<0.5	1.6	27	0.3	0.4	0.1	58	0.31	0.070	13
1202706	Soil		1.6	19.6	9.7	58	<0.1	18.5	8.2	286	2.87	7.8	3.3	1.6	16	0.3	0.4	0.2	68	0.15	0.057	9
1202707	Soil		1.3	32.8	12.1	71	0.2	29.3	10.9	295	3.50	8.6	2.2	5.1	18	0.2	0.4	0.2	79	0.17	0.034	16
1202708	Soil		2.7	34.0	13.1	63	0.2	21.5	5.3	242	2.98	9.9	1.8	1.8	21	0.2	0.4	0.2	84	0.13	0.056	17
1202709	Soil		2.3	41.7	12.7	98	0.3	32.3	9.7	326	3.24	10.0	3.3	3.5	24	0.5	0.4	0.2	80	0.17	0.051	14
1202710	Soil		3.1	58.7	13.7	160	0.3	66.2	16.8	787	4.18	13.1	4.1	5.6	28	0.5	0.5	0.2	98	0.28	0.074	18
1202711	Soil		2.5	39.7	13.7	101	0.2	40.3	13.0	544	3.51	12.0	5.5	3.0	28	0.5	0.5	0.2	89	0.28	0.052	13
1202712	Soil		2.6	57.9	13.0	133	0.3	43.9	16.1	584	3.61	25.2	9.8	4.3	36	0.8	0.7	0.3	84	0.27	0.069	14
1202713	Soil		1.7	36.4	11.0	90	0.1	35.1	12.9	398	3.52	13.2	7.4	3.9	22	0.3	0.6	0.2	82	0.21	0.041	11
1202714	Soil		3.4	64.4	10.4	141	0.4	46.0	11.2	326	3.44	9.1	7.3	3.9	43	0.6	0.8	0.2	69	0.27	0.081	16
1202715	Soil		2.0	27.7	11.9	81	0.2	28.0	9.3	262	3.21	8.9	3.4	4.0	24	0.3	0.5	0.2	75	0.23	0.052	13
1202716	Soil		1.3	28.9	17.4	70	<0.1	29.9	10.5	285	3.30	7.0	2.3	5.6	22	0.4	0.3	0.2	76	0.22	0.055	15
1202717	Soil		1.1	39.4	8.5	90	<0.1	40.0	15.0	356	3.38	6.6	1.4	5.1	20	0.2	0.4	0.1	76	0.21	0.048	11
1202718	Soil		1.9	28.2	13.8	73	<0.1	38.7	13.3	474	3.72	9.9	3.7	7.5	21	0.4	0.6	0.3	81	0.22	0.069	20
1202719	Soil		1.8	26.8	12.6	79	0.2	27.6	12.1	359	3.43	8.4	3.3	4.4	25	0.9	0.5	0.3	84	0.25	0.063	13
1202720	Soil		1.3	29.4	9.2	55	<0.1	33.9	14.7	414	3.65	8.3	2.9	10.6	23	0.2	0.4	0.2	77	0.28	0.069	22
1202721	Soil		1.1	38.7	17.2	83	0.1	30.6	11.5	329	3.75	4.4	1.1	14.1	22	0.1	0.2	0.2	59	0.19	0.040	57
1202722	Soil		1.4	38.8	17.4	64	0.1	46.5	20.7	401	4.24	5.3	1.3	9.2	25	0.1	0.3	0.2	88	0.30	0.079	24
1202723	Soil		1.9	34.9	12.6	89	0.1	38.7	12.1	408	4.29	20.5	2.8	7.1	16	0.2	0.7	0.2	95	0.15	0.041	18
1202724	Soil		1.2	33.8	10.2	77	0.2	38.5	12.7	467	3.32	7.2	1.7	6.4	26	0.3	0.4	0.2	76	0.28	0.062	17
1202725	Soil		1.1	35.1	9.0	93	<0.1	44.6	16.7	384	3.74	4.6	0.8	6.3	21	0.2	0.2	<0.1	80	0.26	0.056	14
1202726	Soil		1.6	22.9	11.5	69	<0.1	30.4	10.6	296	3.61	9.0	3.3	4.1	20	0.2	0.5	0.2	87	0.17	0.051	17
1202727	Soil		1.2	35.7	11.4	78	<0.1	33.0	12.0	382	3.87	4.2	<0.5	9.2	24	0.2	0.2	0.2	65	0.24	0.047	16
1202728	Soil		1.6	33.4	16.2	90	<0.1	34.0	14.2	481	3.81	7.9	2.0	10.1	21	0.2	0.5	0.6	64	0.24	0.052	28
1202729	Soil		0.4	96.5	5.2	69	<0.1	50.9	20.7	643	4.06	3.3	1.9	3.3	32	<0.1	0.2	0.1	126	0.59	0.058	14
1202730	Soil		0.3	43.5	4.9	86	<0.1	37.0	20.7	776	4.52	2.5	4.0	2.8	45	<0.1	0.1	0.1	117	0.74	0.061	11
1202731	Soil		0.3	55.0	12.5	82	<0.1	87.2	24.5	759	4.37	1.5	1.4	8.2	35	0.1	<0.1	0.1	110	0.84	0.114	22

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202702	Soil	15	0.12	50	0.040	<1	0.79	0.013	0.03	<0.1	0.02	0.9	<0.1	<0.05	6	<0.5	<0.2
1202703	Soil	34	0.48	99	0.073	<1	1.92	0.018	0.10	<0.1	0.03	2.7	0.1	0.11	8	0.7	<0.2
1202704	Soil	23	0.38	70	0.036	<1	1.13	0.017	0.13	<0.1	0.02	1.6	<0.1	0.08	4	<0.5	<0.2
1202705	Soil	33	0.54	167	0.072	<1	1.87	0.019	0.07	<0.1	0.04	3.6	<0.1	<0.05	6	<0.5	<0.2
1202706	Soil	28	0.45	94	0.083	<1	1.63	0.014	0.07	<0.1	0.02	2.6	<0.1	<0.05	8	<0.5	<0.2
1202707	Soil	42	0.66	136	0.096	<1	2.36	0.010	0.07	<0.1	<0.01	3.6	<0.1	0.08	7	<0.5	<0.2
1202708	Soil	32	0.35	146	0.060	<1	1.26	0.010	0.08	<0.1	<0.01	2.3	<0.1	0.11	6	0.9	<0.2
1202709	Soil	39	0.50	174	0.074	1	1.84	0.010	0.05	0.1	0.03	3.8	<0.1	<0.05	6	<0.5	<0.2
1202710	Soil	63	0.77	206	0.071	<1	2.54	0.013	0.06	<0.1	0.04	5.7	<0.1	<0.05	7	<0.5	<0.2
1202711	Soil	48	0.63	197	0.087	2	2.37	0.014	0.06	0.1	0.02	3.8	<0.1	<0.05	8	<0.5	<0.2
1202712	Soil	48	0.71	190	0.094	1	2.30	0.014	0.10	0.1	0.03	3.5	0.1	0.08	7	0.6	<0.2
1202713	Soil	47	0.69	155	0.099	<1	2.51	0.013	0.06	0.1	0.03	3.6	0.1	<0.05	7	<0.5	<0.2
1202714	Soil	40	0.56	151	0.073	<1	1.47	0.013	0.07	0.1	0.02	4.2	0.2	0.07	4	1.0	<0.2
1202715	Soil	40	0.59	153	0.083	<1	2.01	0.011	0.07	<0.1	0.04	3.1	<0.1	<0.05	7	<0.5	<0.2
1202716	Soil	41	0.69	217	0.096	<1	2.30	0.012	0.11	<0.1	0.04	3.4	0.1	<0.05	8	<0.5	<0.2
1202717	Soil	49	0.84	193	0.128	1	2.36	0.014	0.19	0.1	0.02	3.0	0.2	<0.05	7	<0.5	<0.2
1202718	Soil	48	0.57	218	0.082	3	2.49	0.012	0.09	0.1	0.03	4.0	0.2	<0.05	8	<0.5	<0.2
1202719	Soil	42	0.53	304	0.087	<1	2.36	0.016	0.08	0.1	0.04	3.6	0.1	<0.05	8	<0.5	<0.2
1202720	Soil	56	0.84	186	0.134	1	2.40	0.014	0.24	0.1	0.04	3.2	0.2	<0.05	7	<0.5	<0.2
1202721	Soil	43	0.92	131	0.101	1	2.25	0.010	0.34	<0.1	<0.01	3.4	0.3	<0.05	8	<0.5	<0.2
1202722	Soil	89	1.08	206	0.125	<1	2.90	0.014	0.27	<0.1	0.02	4.9	0.2	<0.05	9	<0.5	<0.2
1202723	Soil	49	0.58	147	0.079	1	2.41	0.011	0.08	<0.1	<0.01	4.1	0.1	<0.05	7	0.8	<0.2
1202724	Soil	48	0.77	222	0.099	1	2.30	0.014	0.24	<0.1	0.02	3.1	0.2	<0.05	7	0.5	<0.2
1202725	Soil	59	1.04	235	0.164	1	2.56	0.010	0.59	0.1	<0.01	2.7	0.3	<0.05	7	<0.5	<0.2
1202726	Soil	44	0.54	197	0.090	1	2.06	0.013	0.08	0.1	<0.01	3.3	<0.1	<0.05	8	<0.5	<0.2
1202727	Soil	59	1.04	155	0.152	<1	2.31	0.008	0.69	<0.1	<0.01	2.8	0.5	<0.05	9	<0.5	<0.2
1202728	Soil	46	0.72	149	0.068	2	2.11	0.010	0.23	<0.1	0.02	3.8	0.2	<0.05	8	<0.5	<0.2
1202729	Soil	125	1.61	196	0.142	2	2.44	0.024	0.30	<0.1	<0.01	6.8	0.1	<0.05	8	<0.5	<0.2
1202730	Soil	103	1.69	206	0.104	2	2.77	0.015	0.40	<0.1	<0.01	8.2	0.2	<0.05	9	<0.5	<0.2
1202731	Soil	266	2.31	463	0.141	3	2.80	0.012	0.69	<0.1	<0.01	9.7	0.4	<0.05	11	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202732	Soil	0.4	40.6	9.2	69	<0.1	74.5	21.5	659	3.57	2.3	1.4	7.0	41	<0.1	0.1	<0.1	77	0.87	0.097	18
1202733	Soil	0.9	39.6	8.4	64	0.1	35.3	22.4	1187	3.49	4.1	1.3	2.9	61	0.2	0.3	0.1	73	0.89	0.072	18
1202734	Soil	0.6	42.4	9.1	75	<0.1	32.9	15.6	453	3.27	3.6	1.3	2.7	55	0.2	0.3	0.1	77	0.76	0.073	11
1202735	Soil	1.1	38.1	7.8	76	<0.1	29.9	18.1	678	3.20	3.6	1.7	2.0	58	0.2	0.4	<0.1	73	0.86	0.073	10
1202736	Soil	0.5	28.1	7.0	66	<0.1	31.5	16.2	644	2.76	3.1	1.1	2.3	43	0.1	0.2	0.1	69	0.71	0.074	10
1202737	Soil	0.6	24.2	6.7	52	<0.1	28.4	12.5	433	2.45	4.3	1.8	3.2	34	0.1	0.2	<0.1	62	0.54	0.073	11
1202738	Soil	0.9	25.1	9.4	50	<0.1	32.5	11.3	268	2.77	6.8	7.7	3.1	35	0.1	0.3	0.1	71	0.48	0.052	10
1202739	Soil	1.0	35.2	6.6	61	<0.1	28.5	13.4	324	3.18	11.1	1.4	2.7	34	<0.1	0.3	<0.1	78	0.42	0.053	10
1202740	Soil	0.8	46.7	9.9	67	<0.1	36.1	12.6	406	3.06	6.0	2.0	3.4	35	0.1	0.3	0.1	77	0.73	0.055	12
1202811	Soil	0.9	11.4	6.2	30	<0.1	10.8	1.7	58	0.99	1.4	<0.5	<0.1	10	0.3	0.2	0.1	24	0.07	0.029	7
1202812	Soil	2.8	59.9	10.4	141	0.3	56.2	14.6	334	4.00	10.7	3.0	4.7	32	0.6	0.7	0.2	100	0.23	0.061	18
1202813	Soil	1.6	59.1	7.6	85	0.1	31.8	10.7	428	2.40	6.5	4.4	2.8	17	0.1	0.4	0.1	84	0.18	0.037	7
1202814	Soil	1.7	47.4	8.8	114	0.2	44.7	15.5	605	4.20	18.9	2.9	3.7	36	0.3	0.6	0.1	100	0.45	0.129	17
1202815	Soil	0.5	16.4	9.4	52	<0.1	24.6	9.2	294	3.00	5.2	1.4	6.9	19	0.1	0.3	0.3	47	0.25	0.053	27
1202816	Soil	0.9	37.9	8.8	79	<0.1	31.5	9.6	196	3.07	3.0	1.3	7.1	16	0.1	0.2	0.2	53	0.20	0.041	32
1202817	Soil	3.5	66.5	16.5	131	0.2	44.9	14.8	704	4.33	3.9	1.7	6.1	29	0.4	0.5	0.2	45	0.30	0.093	36
1202818	Soil	0.7	12.8	4.3	14	0.1	4.5	1.1	29	0.77	1.4	1.3	<0.1	10	0.5	0.1	0.1	19	0.07	0.042	4
1202819	Soil	3.6	96.7	6.7	202	0.2	58.2	13.0	667	4.83	9.6	5.6	4.1	38	1.0	1.2	0.1	131	0.59	0.241	25
1202820	Soil	1.7	62.2	6.1	93	0.5	36.1	6.6	126	2.48	3.9	3.7	0.1	25	0.9	0.8	0.1	50	0.23	0.102	12
1202821	Soil	2.5	48.5	6.7	99	0.2	38.7	16.5	549	4.19	3.6	3.3	1.1	22	0.3	0.2	0.2	127	0.39	0.110	13
1202822	Soil	2.1	40.4	8.9	95	<0.1	30.9	14.8	436	3.97	3.9	<0.5	7.4	27	0.4	0.2	0.7	73	0.16	0.071	33
1202823	Soil	1.1	16.1	11.3	48	<0.1	25.0	9.5	222	2.71	2.9	1.3	6.5	11	0.2	0.1	0.2	50	0.14	0.053	21
1202824	Soil	0.7	11.3	4.1	19	<0.1	8.3	3.0	61	1.21	1.9	1.5	0.3	13	0.1	0.1	0.1	27	0.12	0.043	18
1202825	Soil	1.0	18.4	8.5	51	<0.1	19.2	9.8	296	3.00	5.7	10.1	6.4	16	0.1	0.3	0.2	62	0.16	0.047	30
1202826	Soil	0.8	20.7	8.2	66	<0.1	26.4	13.2	367	3.34	5.9	2.4	9.9	18	<0.1	0.3	0.2	64	0.21	0.044	21
1202827	Soil	0.9	22.9	10.6	49	0.1	21.3	9.1	238	2.58	4.3	6.6	8.2	19	<0.1	0.2	0.3	47	0.21	0.043	34
1202828	Soil	0.8	19.1	9.5	55	<0.1	22.1	8.9	224	2.58	4.6	2.8	4.8	19	0.1	0.2	0.2	55	0.22	0.040	16
1202829	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202830	Soil	1.0	28.5	9.0	78	0.2	30.0	9.1	244	2.74	3.3	2.1	4.7	21	0.1	0.2	0.2	62	0.29	0.066	17
1202535	Soil	0.6	29.6	8.6	70	<0.1	29.1	11.8	232	2.94	4.3	3.7	3.1	22	<0.1	0.3	0.1	60	0.31	0.074	18

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202732	Soil	223	1.68	380	0.117	2	2.17	0.016	0.36	<0.1	<0.01	6.0	0.2	<0.05	7	<0.5	<0.2
1202733	Soil	85	0.93	429	0.086	2	1.68	0.025	0.11	<0.1	0.06	4.6	0.1	0.05	6	<0.5	<0.2
1202734	Soil	71	1.10	348	0.111	2	1.69	0.028	0.15	<0.1	0.03	5.3	<0.1	<0.05	6	<0.5	<0.2
1202735	Soil	59	1.03	298	0.089	2	1.76	0.026	0.10	<0.1	0.03	5.7	<0.1	<0.05	6	<0.5	<0.2
1202736	Soil	81	0.98	241	0.096	1	1.69	0.021	0.08	<0.1	0.02	3.6	<0.1	<0.05	6	<0.5	<0.2
1202737	Soil	67	0.75	199	0.095	1	1.64	0.017	0.09	0.1	<0.01	3.2	<0.1	<0.05	6	<0.5	<0.2
1202738	Soil	80	0.86	197	0.134	2	2.08	0.020	0.08	0.1	<0.01	2.8	<0.1	<0.05	7	<0.5	<0.2
1202739	Soil	63	0.93	178	0.117	1	1.92	0.021	0.08	<0.1	<0.01	3.5	<0.1	<0.05	6	<0.5	<0.2
1202740	Soil	74	1.05	244	0.141	1	2.06	0.022	0.20	<0.1	0.02	4.7	0.1	<0.05	6	0.5	<0.2
1202811	Soil	16	0.12	63	0.025	<1	0.51	0.014	0.07	<0.1	<0.01	0.4	<0.1	<0.05	3	<0.5	<0.2
1202812	Soil	56	0.59	279	0.055	1	2.33	0.014	0.11	<0.1	0.03	6.1	0.1	0.07	6	1.9	<0.2
1202813	Soil	33	0.65	113	0.074	<1	1.46	0.006	0.05	<0.1	<0.01	2.3	<0.1	<0.05	5	0.9	<0.2
1202814	Soil	62	0.87	161	0.034	<1	2.34	0.009	0.07	<0.1	0.02	6.6	<0.1	<0.05	8	1.0	<0.2
1202815	Soil	26	0.64	170	0.012	<1	1.82	0.007	0.07	<0.1	<0.01	3.5	<0.1	<0.05	6	<0.5	<0.2
1202816	Soil	34	0.75	138	0.089	<1	1.72	0.009	0.35	<0.1	0.01	3.5	0.3	<0.05	5	<0.5	<0.2
1202817	Soil	26	0.40	241	0.026	<1	1.63	0.007	0.09	<0.1	0.03	5.9	<0.1	<0.05	4	0.8	<0.2
1202818	Soil	11	0.04	69	0.022	<1	0.54	0.016	0.03	<0.1	0.02	0.4	<0.1	<0.05	3	<0.5	<0.2
1202819	Soil	52	1.34	601	0.100	<1	2.46	0.007	0.80	<0.1	<0.01	4.6	0.3	<0.05	8	3.0	<0.2
1202820	Soil	30	0.21	203	0.012	<1	1.28	0.013	0.08	<0.1	0.05	1.8	<0.1	<0.05	4	1.6	<0.2
1202821	Soil	50	0.98	281	0.121	<1	2.06	0.016	0.42	0.1	0.03	4.5	0.1	<0.05	9	0.8	<0.2
1202822	Soil	37	0.57	214	0.078	<1	1.76	0.008	0.21	<0.1	0.01	3.8	0.1	<0.05	7	1.4	<0.2
1202823	Soil	30	0.68	98	0.107	<1	1.54	0.009	0.38	<0.1	0.02	1.6	0.3	<0.05	7	<0.5	<0.2
1202824	Soil	14	0.15	119	0.029	<1	0.91	0.017	0.05	<0.1	0.03	0.9	<0.1	<0.05	3	<0.5	<0.2
1202825	Soil	35	0.56	183	0.102	<1	1.79	0.013	0.25	<0.1	0.02	2.9	0.1	<0.05	7	0.7	<0.2
1202826	Soil	39	0.71	174	0.115	<1	2.18	0.011	0.25	<0.1	0.02	3.0	0.2	<0.05	6	0.5	<0.2
1202827	Soil	32	0.51	168	0.094	<1	1.83	0.013	0.18	0.1	0.03	3.7	0.2	<0.05	6	0.8	<0.2
1202828	Soil	32	0.61	145	0.104	<1	1.62	0.012	0.14	0.1	0.02	2.5	0.1	<0.05	6	<0.5	<0.2
1202829	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1202830	Soil	49	0.82	170	0.116	<1	1.80	0.011	0.29	0.1	0.05	3.2	0.2	<0.05	7	0.7	<0.2
1202535	Soil	44	0.81	141	0.104	<1	2.08	0.014	0.11	<0.1	0.05	3.5	0.2	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202536	Soil		0.9	68.6	8.7	61	0.2	43.3	18.7	373	3.11	5.7	3.0	2.7	27	0.2	0.3	0.2	66	0.34	0.075	40
1202537	Soil		1.0	31.5	6.8	79	<0.1	47.2	22.5	496	4.22	7.1	9.1	4.4	22	<0.1	0.3	0.1	76	0.26	0.050	12
1202538	Soil		0.7	36.2	11.7	67	<0.1	40.7	14.4	357	3.47	4.9	2.0	6.1	26	0.2	0.3	0.2	68	0.36	0.051	27
1202539	Soil		1.6	37.0	10.2	61	<0.1	42.2	22.7	574	4.57	10.5	1.7	7.2	16	<0.1	0.5	0.2	88	0.15	0.027	17
1202540	Soil		0.8	32.7	6.1	78	<0.1	38.8	17.0	466	3.46	6.6	1.9	3.6	29	<0.1	0.3	0.2	74	0.47	0.082	13
1202541	Soil		1.2	27.0	11.7	78	<0.1	45.5	16.9	359	4.74	7.5	2.6	4.7	16	<0.1	0.3	0.2	86	0.19	0.031	10
1202542	Soil		0.9	27.6	11.0	78	<0.1	40.5	19.3	491	4.25	7.0	3.4	6.2	19	0.1	0.3	0.3	75	0.22	0.044	13
1202543	Soil		0.7	10.9	6.4	27	<0.1	10.3	4.1	152	1.19	2.7	2.3	1.2	18	0.2	0.2	0.1	28	0.26	0.019	5
1202544	Soil		0.9	11.3	5.7	29	0.3	8.4	4.2	126	1.51	4.5	1.4	0.8	14	0.1	0.2	0.1	41	0.11	0.024	5
1202545	Soil		1.6	11.1	30.6	71	<0.1	22.6	13.0	364	2.86	5.0	1.4	2.1	11	0.1	0.3	0.3	42	0.10	0.045	17
1202546	Soil		0.6	5.4	4.8	14	<0.1	3.2	1.5	67	0.92	1.8	1.0	0.3	5	<0.1	0.1	0.1	30	0.04	0.023	4
1202547	Soil		0.6	24.4	7.6	53	0.1	21.2	9.2	300	2.28	4.6	3.7	2.1	24	<0.1	0.3	0.1	48	0.38	0.059	12
1202548	Soil		1.4	20.8	13.3	50	<0.1	22.2	11.4	323	3.15	9.0	1.8	3.2	19	0.2	0.4	0.2	79	0.17	0.032	11
1202549	Soil		0.9	35.0	24.7	67	0.5	27.5	11.3	339	3.15	6.9	3.9	2.3	32	<0.1	0.4	0.2	66	0.42	0.092	49
1202550	Soil		0.8	9.1	5.0	20	<0.1	6.2	2.9	84	1.24	3.4	2.5	0.5	11	<0.1	0.2	0.1	40	0.10	0.022	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000350.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202536	Soil	46	0.75	191	0.094	<1	2.19	0.014	0.15	<0.1	0.04	4.8	0.2	<0.05	7	0.8	<0.2
1202537	Soil	60	1.21	163	0.162	<1	2.82	0.012	0.55	<0.1	0.02	3.2	0.3	<0.05	7	<0.5	<0.2
1202538	Soil	52	0.89	126	0.103	<1	2.09	0.016	0.11	<0.1	0.02	4.4	0.1	<0.05	6	<0.5	<0.2
1202539	Soil	70	0.94	148	0.088	<1	2.96	0.010	0.18	<0.1	0.02	5.5	0.2	<0.05	9	0.8	<0.2
1202540	Soil	51	0.93	206	0.128	<1	2.18	0.014	0.14	0.1	0.02	3.4	0.2	<0.05	6	0.6	<0.2
1202541	Soil	72	1.10	99	0.130	1	2.68	0.010	0.27	<0.1	0.02	4.3	0.2	<0.05	10	0.5	<0.2
1202542	Soil	50	0.86	112	0.097	<1	2.62	0.011	0.13	<0.1	0.02	4.1	0.1	<0.05	8	<0.5	<0.2
1202543	Soil	16	0.18	49	0.041	<1	0.56	0.020	0.04	<0.1	0.02	1.5	<0.1	<0.05	3	0.5	<0.2
1202544	Soil	17	0.21	62	0.054	<1	0.94	0.017	0.04	<0.1	0.03	1.4	<0.1	<0.05	4	<0.5	<0.2
1202545	Soil	22	0.20	82	0.023	<1	1.35	0.010	0.08	<0.1	0.02	2.1	<0.1	<0.05	5	<0.5	<0.2
1202546	Soil	8	0.06	34	0.036	<1	0.39	0.013	0.03	<0.1	0.02	0.6	<0.1	<0.05	3	<0.5	<0.2
1202547	Soil	30	0.57	213	0.093	<1	1.57	0.024	0.13	0.1	0.03	3.1	0.1	<0.05	4	0.7	<0.2
1202548	Soil	40	0.46	148	0.099	1	2.32	0.013	0.06	<0.1	0.04	3.9	0.1	<0.05	7	<0.5	<0.2
1202549	Soil	42	0.54	273	0.078	<1	2.82	0.018	0.09	0.1	0.10	5.9	0.2	<0.05	7	1.1	<0.2
1202550	Soil	16	0.19	86	0.069	<1	0.73	0.014	0.04	0.1	0.02	1.1	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1202363	Soil	0.9	18.6	8.8	44	<0.1	13.3	6.3	192	2.26	5.8	3.2	1.2	15	0.1	0.3	0.2	66	0.18	0.037	9
REP 1202363	QC	1.0	17.7	8.9	41	<0.1	12.8	6.2	190	2.27	5.9	1.3	1.3	15	0.1	0.4	0.2	66	0.18	0.035	9
1202365	Soil	0.5	14.6	9.8	55	<0.1	19.9	8.6	184	2.26	6.2	3.8	2.2	22	0.1	0.3	0.4	60	0.33	0.065	12
REP 1202365	QC	0.5	15.0	9.5	55	<0.1	20.0	8.6	191	2.34	6.2	3.9	2.0	22	0.1	0.3	0.4	61	0.33	0.061	12
1202566	Soil	0.7	41.5	7.7	56	<0.1	21.4	9.7	178	2.77	7.1	2.9	3.1	19	0.2	0.5	0.2	74	0.31	0.062	11
REP 1202566	QC	0.7	42.2	7.8	56	<0.1	21.0	9.2	175	2.72	7.5	4.2	3.1	18	0.2	0.5	0.2	74	0.29	0.059	11
1202446	Soil	2.0	28.9	11.2	92	0.3	27.9	13.4	495	2.69	6.7	1.4	2.4	25	0.5	0.3	0.2	72	0.37	0.075	12
REP 1202446	QC	1.9	28.7	11.2	94	0.3	27.4	13.2	488	2.73	6.7	1.8	2.5	25	0.6	0.3	0.2	71	0.37	0.074	12
1202475	Soil	0.9	11.9	6.8	35	<0.1	8.9	4.4	102	2.25	6.9	2.3	1.4	10	0.1	0.3	0.2	52	0.09	0.024	5
REP 1202475	QC	1.0	11.6	7.1	34	<0.1	9.0	4.6	103	2.17	7.0	2.9	1.4	10	0.1	0.4	0.2	49	0.08	0.025	5
1202490	Soil	0.8	16.2	6.4	43	<0.1	15.7	9.0	243	2.58	5.4	0.9	1.8	18	0.1	0.3	0.1	64	0.23	0.031	5
REP 1202490	QC	0.8	16.8	6.3	47	<0.1	16.9	9.3	241	2.54	5.5	4.3	1.9	19	0.1	0.3	0.1	61	0.24	0.033	5
1202163	Soil	1.2	59.1	13.9	69	0.3	31.2	12.6	447	3.70	6.2	17.1	9.2	45	0.1	0.4	5.7	88	0.60	0.070	29
REP 1202163	QC	1.1	62.2	13.7	69	0.3	32.0	13.1	473	4.05	6.3	25.7	9.2	43	0.1	0.4	5.7	90	0.62	0.072	30
1202810	Soil	1.2	18.3	13.7	63	0.1	17.6	6.1	190	2.68	28.8	2.8	2.2	15	0.4	0.5	0.2	63	0.09	0.036	12
REP 1202810	QC	1.2	18.2	13.5	63	0.1	17.6	6.2	191	2.63	28.7	1.7	2.1	15	0.4	0.5	0.2	60	0.09	0.033	12
1202708	Soil	2.7	34.0	13.1	63	0.2	21.5	5.3	242	2.98	9.9	1.8	1.8	21	0.2	0.4	0.2	84	0.13	0.056	17
REP 1202708	QC	2.7	33.9	12.6	66	0.3	23.2	5.6	240	2.97	9.9	2.6	1.6	21	0.2	0.3	0.2	88	0.13	0.059	17
1202729	Soil	0.4	96.5	5.2	69	<0.1	50.9	20.7	643	4.06	3.3	1.9	3.3	32	<0.1	0.2	0.1	126	0.59	0.058	14
REP 1202729	QC	0.5	96.5	5.4	71	<0.1	53.2	21.5	662	4.21	3.3	3.2	3.5	31	<0.1	0.2	0.1	127	0.58	0.057	15
1202826	Soil	0.8	20.7	8.2	66	<0.1	26.4	13.2	367	3.34	5.9	2.4	9.9	18	<0.1	0.3	0.2	64	0.21	0.044	21
REP 1202826	QC	0.7	20.1	8.2	63	<0.1	25.6	12.5	352	3.25	5.7	3.8	9.3	17	<0.1	0.3	0.2	60	0.20	0.045	20
1202536	Soil	0.9	68.6	8.7	61	0.2	43.3	18.7	373	3.11	5.7	3.0	2.7	27	0.2	0.3	0.2	66	0.34	0.075	40
REP 1202536	QC	0.9	66.5	8.3	59	0.2	43.2	17.5	365	3.01	5.1	6.5	2.8	26	0.2	0.3	0.1	66	0.33	0.067	39
Reference Materials																					
STD DS8	Standard	13.7	117.6	123.6	329	2.0	39.4	8.2	646	2.54	29.0	107.2	7.1	65	2.9	6.0	6.9	46	0.71	0.089	15
STD DS8	Standard	13.8	117.9	127.6	334	1.9	39.5	8.1	622	2.52	29.8	107.8	7.4	67	2.6	6.1	7.3	45	0.72	0.094	16
STD DS8	Standard	12.5	99.1	117.1	302	1.7	35.2	7.4	579	2.36	26.4	114.1	6.4	63	2.3	5.4	6.2	42	0.66	0.078	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000350.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1202363	Soil	25	0.44	110	0.072	1	1.54	0.014	0.05	0.1	0.03	2.8	0.1	<0.05	7	<0.5	<0.2
REP 1202363	QC	24	0.42	110	0.077	1	1.48	0.014	0.05	<0.1	0.03	2.7	<0.1	<0.05	7	<0.5	<0.2
1202365	Soil	31	0.64	238	0.079	2	1.95	0.015	0.06	0.1	0.04	3.6	<0.1	<0.05	7	<0.5	<0.2
REP 1202365	QC	31	0.60	233	0.083	1	1.89	0.016	0.06	0.1	0.03	3.6	<0.1	<0.05	6	<0.5	<0.2
1202566	Soil	34	0.62	169	0.083	2	1.87	0.015	0.04	0.1	0.04	3.8	<0.1	<0.05	5	<0.5	<0.2
REP 1202566	QC	34	0.63	171	0.082	2	1.88	0.014	0.04	0.2	0.04	3.7	<0.1	<0.05	5	<0.5	<0.2
1202446	Soil	40	0.52	155	0.048	<1	1.54	0.015	0.05	0.1	0.04	3.6	<0.1	<0.05	5	1.3	<0.2
REP 1202446	QC	40	0.53	153	0.044	1	1.44	0.014	0.05	0.1	0.04	3.4	<0.1	<0.05	5	1.1	<0.2
1202475	Soil	20	0.19	110	0.057	<1	1.57	0.013	0.04	<0.1	0.02	1.5	<0.1	<0.05	6	<0.5	<0.2
REP 1202475	QC	19	0.19	108	0.054	<1	1.56	0.012	0.04	<0.1	0.02	1.5	<0.1	<0.05	6	<0.5	<0.2
1202490	Soil	28	0.49	154	0.080	<1	1.78	0.016	0.08	<0.1	0.01	2.3	<0.1	<0.05	5	<0.5	<0.2
REP 1202490	QC	29	0.54	157	0.084	<1	1.86	0.017	0.08	<0.1	0.02	2.6	<0.1	<0.05	6	<0.5	<0.2
1202163	Soil	83	1.25	189	0.155	3	2.65	0.037	0.32	0.2	0.04	8.7	0.3	0.07	7	<0.5	<0.2
REP 1202163	QC	86	1.18	192	0.154	2	2.45	0.038	0.33	0.2	0.04	9.1	0.4	0.06	8	<0.5	<0.2
1202810	Soil	22	0.26	83	0.060	<1	1.31	0.012	0.06	<0.1	<0.01	1.7	<0.1	<0.05	6	<0.5	<0.2
REP 1202810	QC	22	0.27	80	0.061	<1	1.28	0.012	0.06	<0.1	0.01	1.8	<0.1	<0.05	6	<0.5	<0.2
1202708	Soil	32	0.35	146	0.060	<1	1.26	0.010	0.08	<0.1	<0.01	2.3	<0.1	0.11	6	0.9	<0.2
REP 1202708	QC	32	0.35	150	0.063	<1	1.23	0.011	0.08	<0.1	0.03	2.4	<0.1	0.10	7	0.5	<0.2
1202729	Soil	125	1.61	196	0.142	2	2.44	0.024	0.30	<0.1	<0.01	6.8	0.1	<0.05	8	<0.5	<0.2
REP 1202729	QC	125	1.58	205	0.134	<1	2.42	0.021	0.30	<0.1	<0.01	6.6	0.1	<0.05	8	<0.5	<0.2
1202826	Soil	39	0.71	174	0.115	<1	2.18	0.011	0.25	<0.1	0.02	3.0	0.2	<0.05	6	0.5	<0.2
REP 1202826	QC	37	0.70	178	0.108	<1	2.08	0.010	0.24	<0.1	0.01	2.9	0.2	<0.05	6	<0.5	<0.2
1202536	Soil	46	0.75	191	0.094	<1	2.19	0.014	0.15	<0.1	0.04	4.8	0.2	<0.05	7	0.8	<0.2
REP 1202536	QC	45	0.72	183	0.090	<1	2.14	0.013	0.14	<0.1	0.04	4.7	0.2	<0.05	7	0.9	<0.2
Reference Materials																	
STD DS8	Standard	115	0.61	285	0.123	2	0.93	0.091	0.46	3.0	0.20	2.2	5.5	0.19	5	5.1	4.9
STD DS8	Standard	115	0.62	302	0.122	2	0.93	0.096	0.47	3.0	0.21	2.2	5.5	0.20	5	5.5	5.3
STD DS8	Standard	112	0.59	279	0.113	2	0.88	0.090	0.41	2.9	0.19	2.1	5.0	0.16	5	4.6	4.9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000350.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	13.2	101.1	118.4	306	1.8	36.4	7.5	595	2.34	26.7	108.5	6.4	62	2.2	5.3	6.2	42	0.68	0.075	15
STD DS8	Standard	12.5	103.9	119.1	307	1.8	38.2	7.7	596	2.38	25.5	114.1	6.0	59	2.5	5.4	6.0	42	0.66	0.080	13
STD DS8	Standard	13.3	116.2	130.8	336	1.9	41.5	8.3	625	2.54	27.5	110.9	6.4	63	2.6	5.6	6.6	44	0.68	0.086	13
STD DS8	Standard	13.4	115.9	134.4	334	1.8	37.4	8.1	638	2.53	28.8	112.5	7.1	69	2.5	5.8	7.1	40	0.68	0.088	14
STD DS8	Standard	13.6	119.6	133.7	333	1.8	38.6	7.8	590	2.40	27.6	118.1	6.7	70	2.4	6.1	7.0	41	0.71	0.084	15
STD DS8	Standard	14.0	109.2	130.5	328	1.8	38.1	7.6	646	2.48	25.6	118.3	7.3	72	1.9	6.2	7.1	44	0.66	0.076	16
STD DS8	Standard	13.3	114.2	130.9	318	1.8	39.1	7.6	650	2.50	26.0	116.0	7.7	74	2.4	6.3	7.1	44	0.71	0.079	17
STD DS8	Standard	13.4	95.8	128.4	312	1.8	38.2	7.4	630	2.39	26.0	114.7	7.1	61	2.2	5.5	6.2	44	0.71	0.083	14
STD DS8	Standard	12.6	92.8	121.4	301	1.7	37.5	7.0	580	2.36	26.6	115.1	6.8	60	2.2	5.3	5.9	38	0.65	0.077	14
STD DS8	Standard	13.4	114.6	123.5	317	1.8	38.9	7.7	615	2.47	27.4	108.8	6.3	61	2.3	5.6	6.5	42	0.67	0.081	13
STD DS8	Standard	13.8	115.8	122.9	319	1.8	39.2	7.8	606	2.47	27.5	103.7	6.5	63	2.3	5.5	6.4	44	0.69	0.083	14
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	0.02	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000350.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
STD DS8	Standard	118	0.59	284	0.115	<1	0.87	0.086	0.42	2.9	0.21	1.9	5.1	0.14	5	5.3	4.8
STD DS8	Standard	116	0.60	281	0.106	4	0.89	0.092	0.42	3.0	0.20	1.8	5.1	0.17	4	5.1	4.5
STD DS8	Standard	120	0.63	280	0.105	2	0.92	0.091	0.44	3.0	0.21	1.9	5.5	0.16	5	5.6	5.1
STD DS8	Standard	114	0.64	264	0.112	2	0.87	0.094	0.40	3.1	0.19	2.1	5.4	0.24	5	5.3	5.5
STD DS8	Standard	114	0.62	273	0.113	3	0.90	0.088	0.42	3.1	0.21	2.1	5.4	0.11	5	6.1	5.2
STD DS8	Standard	120	0.64	280	0.123	3	0.84	0.092	0.42	3.1	0.19	1.9	5.5	0.21	5	5.8	5.7
STD DS8	Standard	122	0.65	293	0.128	3	0.91	0.089	0.43	3.2	0.20	2.0	5.4	0.17	5	5.9	5.5
STD DS8	Standard	116	0.61	290	0.104	2	0.97	0.095	0.43	3.1	0.21	1.8	5.3	0.15	5	5.3	5.4
STD DS8	Standard	109	0.62	275	0.093	2	0.89	0.089	0.40	2.9	0.19	1.7	5.1	0.11	5	5.2	5.0
STD DS8	Standard	117	0.61	278	0.110	2	0.88	0.083	0.43	3.0	0.22	2.1	5.4	0.15	5	5.2	4.7
STD DS8	Standard	118	0.61	292	0.112	3	0.90	0.086	0.43	3.1	0.20	1.9	5.1	0.16	5	5.1	5.2
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Submitted By: Bruce Durham
Receiving Lab: Canada-Whitehorse
Received: July 07, 2011
Report Date: August 09, 2011
Page: 1 of 3

CERTIFICATE OF ANALYSIS WHI11000490.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID: july-3-2011
P.O. Number
Number of Samples: 40

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	39	Dry at 60C			WHI
SS80	39	Dry at 60C sieve 100g to -80 mesh			WHI
1DX2	39	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Don Christie
Daithi Mac Gearailt
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000490.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203111	Soil	0.7	44.7	8.7	75	0.1	25.6	12.0	445	2.95	3.1	4.0	3.0	23	0.2	0.2	0.2	63	0.36	0.053	12
1203112	Soil	0.7	26.5	7.6	58	<0.1	18.1	24.0	824	2.28	2.3	1.7	1.9	18	<0.1	0.2	0.2	51	0.29	0.039	8
1203113	Soil	0.7	32.4	7.1	63	<0.1	20.7	12.3	418	2.50	2.7	0.7	2.0	22	<0.1	0.2	0.2	56	0.31	0.043	9
1203114	Soil	0.7	30.1	9.3	63	0.1	19.5	11.6	440	2.28	2.5	1.4	1.7	22	<0.1	0.3	0.2	49	0.34	0.049	10
1203115	Soil	0.7	30.9	7.2	65	0.1	22.0	10.9	332	2.54	2.5	2.6	2.1	23	0.1	0.2	0.3	55	0.32	0.046	11
1203116	Soil	0.7	27.2	8.2	57	0.1	18.9	11.6	376	2.52	2.9	1.2	2.2	21	0.1	0.2	0.2	56	0.31	0.048	12
1203117	Soil	0.7	27.9	8.1	62	0.1	19.1	10.7	330	2.56	3.1	0.8	2.5	21	0.1	0.2	0.2	53	0.30	0.051	13
1203118	Soil	0.8	28.3	10.1	64	<0.1	20.1	12.7	428	2.74	3.7	2.5	2.8	20	<0.1	0.2	0.2	59	0.29	0.046	14
1203119	Soil	0.7	29.2	11.7	59	<0.1	18.0	9.1	290	2.39	3.0	4.2	2.4	17	<0.1	0.2	0.2	57	0.25	0.035	11
1203120	Soil	0.8	31.1	15.8	62	<0.1	18.3	10.3	359	2.46	3.3	1.8	2.9	19	<0.1	0.2	0.2	53	0.28	0.038	11
1203121	Soil	0.7	35.1	10.0	54	<0.1	23.4	10.0	341	2.78	4.6	2.8	5.1	28	<0.1	0.3	0.3	64	0.42	0.060	19
1203122	Soil	0.8	23.9	17.4	48	<0.1	23.8	11.3	322	2.59	5.4	2.8	9.1	24	<0.1	0.3	0.2	63	0.34	0.045	25
1203123	Soil	0.8	28.2	17.3	61	<0.1	26.9	11.0	372	2.76	5.4	3.0	7.9	28	<0.1	0.3	0.2	69	0.46	0.058	22
1203124	Soil	1.0	21.4	13.6	54	<0.1	25.4	11.0	242	2.74	6.0	4.1	6.1	24	<0.1	0.3	0.2	68	0.41	0.053	15
1203125	Soil	1.6	20.7	14.1	50	0.1	22.2	23.8	1318	4.25	7.6	11.3	6.7	35	0.2	0.3	0.2	63	0.68	0.061	22
1203126	Soil	1.4	27.0	8.1	66	<0.1	27.0	16.5	842	2.70	3.3	1.5	2.6	42	0.1	0.3	0.1	52	0.93	0.068	12
1203127	Soil	1.0	21.4	8.1	51	0.1	19.8	12.9	1235	2.13	3.5	1.2	2.2	32	0.2	0.2	0.1	48	0.59	0.072	9
1203128	Soil	2.2	39.9	11.7	58	0.2	20.5	9.1	2630	1.25	2.1	3.7	0.5	85	0.6	0.6	<0.1	26	1.96	0.102	15
1203129	Soil	2.2	33.7	12.8	74	0.1	33.3	27.5	2426	2.80	5.1	1.7	2.0	45	0.4	0.4	0.1	66	0.91	0.079	11
1203130	Soil	1.1	23.0	7.0	64	<0.1	27.5	13.9	674	2.53	3.9	3.4	2.0	39	0.1	0.3	<0.1	61	0.83	0.066	10
1203131	Soil	1.0	21.8	7.9	76	<0.1	27.7	16.6	985	2.66	3.7	3.7	2.3	40	0.1	0.3	<0.1	63	0.79	0.064	10
1203132	Soil	0.9	20.3	7.5	75	<0.1	25.8	16.9	793	2.69	4.2	2.0	2.4	33	0.1	0.2	<0.1	66	0.57	0.056	11
1203133	Soil	0.9	19.6	7.1	68	<0.1	24.4	13.6	599	2.69	4.0	1.3	1.8	26	<0.1	0.2	<0.1	70	0.40	0.057	9
1203134	Soil	1.2	20.2	8.3	67	<0.1	25.3	14.8	568	2.62	4.2	2.0	1.8	25	0.1	0.2	<0.1	67	0.39	0.063	10
1203135	Soil	1.2	17.5	9.4	67	<0.1	22.3	19.9	1100	2.81	3.6	7.5	2.2	21	0.1	0.2	0.1	70	0.33	0.056	9
1203136	Soil	0.7	11.8	5.6	54	<0.1	16.5	9.9	401	2.27	2.8	2.3	1.6	17	0.1	0.2	<0.1	46	0.33	0.057	7
1203137	Soil	0.7	11.3	5.4	55	<0.1	16.3	12.7	609	2.17	3.3	2.8	1.2	17	<0.1	0.2	<0.1	43	0.33	0.053	6
1203138	Soil	0.7	13.8	4.5	60	<0.1	20.4	13.0	658	2.63	4.7	6.7	1.7	25	0.1	0.2	<0.1	54	0.58	0.080	8
1203139	Soil	0.6	12.9	4.7	55	<0.1	18.3	11.9	560	2.48	3.5	1.4	1.3	20	0.1	0.2	<0.1	51	0.44	0.061	7
1203140	Soil	0.5	11.6	4.9	55	<0.1	18.5	11.1	487	2.37	3.3	1.3	1.3	18	<0.1	0.2	<0.1	51	0.38	0.048	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000490.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203111	Soil	50	1.15	150	0.070	2	2.14	0.018	0.06	0.1	0.06	4.6	<0.1	<0.05	6	<0.5	<0.2
1203112	Soil	34	0.88	95	0.066	1	1.49	0.013	0.05	0.1	0.04	3.1	<0.1	<0.05	5	<0.5	<0.2
1203113	Soil	39	0.99	117	0.068	2	1.78	0.016	0.05	0.1	0.05	3.5	<0.1	0.07	5	<0.5	<0.2
1203114	Soil	38	0.84	119	0.067	1	1.63	0.016	0.06	0.1	0.06	3.3	<0.1	<0.05	5	<0.5	<0.2
1203115	Soil	46	1.05	119	0.059	1	1.91	0.016	0.06	<0.1	0.05	3.8	<0.1	0.07	6	<0.5	<0.2
1203116	Soil	38	0.89	102	0.066	1	1.74	0.016	0.06	0.1	0.05	3.3	<0.1	<0.05	5	<0.5	<0.2
1203117	Soil	38	0.91	116	0.065	1	1.85	0.016	0.05	0.1	0.06	3.5	<0.1	<0.05	6	<0.5	<0.2
1203118	Soil	39	0.87	128	0.072	2	1.75	0.015	0.05	0.1	0.04	3.5	<0.1	<0.05	5	<0.5	<0.2
1203119	Soil	35	0.82	99	0.069	1	1.58	0.014	0.05	0.1	0.04	3.0	<0.1	<0.05	5	<0.5	<0.2
1203120	Soil	34	0.80	100	0.068	<1	1.54	0.014	0.05	0.1	0.04	3.0	<0.1	<0.05	5	<0.5	<0.2
1203121	Soil	43	0.68	165	0.120	2	2.06	0.020	0.05	<0.1	0.03	7.0	<0.1	<0.05	6	<0.5	<0.2
1203122	Soil	37	0.53	168	0.101	1	2.17	0.017	0.06	<0.1	0.03	4.1	<0.1	<0.05	6	<0.5	<0.2
1203123	Soil	39	0.59	165	0.121	2	1.93	0.022	0.05	0.1	0.03	5.0	<0.1	<0.05	6	<0.5	<0.2
1203124	Soil	37	0.59	187	0.111	2	2.04	0.017	0.06	0.1	0.03	3.9	<0.1	<0.05	6	<0.5	<0.2
1203125	Soil	33	0.49	235	0.070	1	1.77	0.021	0.04	<0.1	0.03	4.9	<0.1	<0.05	5	<0.5	<0.2
1203126	Soil	39	1.30	172	0.054	2	1.84	0.018	0.06	0.1	0.03	4.1	<0.1	0.07	5	<0.5	<0.2
1203127	Soil	32	0.73	164	0.060	<1	1.44	0.024	0.05	<0.1	0.04	3.4	<0.1	0.05	5	<0.5	<0.2
1203128	Soil	24	0.35	263	0.025	3	0.87	0.021	0.03	<0.1	0.11	1.9	<0.1	0.20	2	0.8	<0.2
1203129	Soil	51	1.03	200	0.066	2	1.80	0.022	0.05	0.1	0.06	4.5	<0.1	0.12	5	0.5	<0.2
1203130	Soil	45	1.05	161	0.068	2	1.78	0.021	0.04	0.1	0.05	4.2	<0.1	0.06	5	<0.5	<0.2
1203131	Soil	41	1.12	195	0.078	2	1.90	0.023	0.05	<0.1	0.05	4.1	<0.1	0.09	5	<0.5	<0.2
1203132	Soil	41	1.04	175	0.091	1	1.93	0.023	0.05	<0.1	0.04	4.5	<0.1	0.07	6	<0.5	<0.2
1203133	Soil	45	1.00	163	0.083	2	1.91	0.021	0.05	0.1	0.03	3.9	<0.1	0.05	6	<0.5	<0.2
1203134	Soil	44	0.96	166	0.080	1	1.90	0.019	0.05	<0.1	0.04	4.1	<0.1	<0.05	6	<0.5	<0.2
1203135	Soil	41	0.93	145	0.073	1	1.88	0.016	0.05	<0.1	0.03	4.0	<0.1	<0.05	6	<0.5	<0.2
1203136	Soil	25	0.82	109	0.043	3	1.50	0.011	0.04	0.1	0.03	2.8	<0.1	<0.05	5	<0.5	<0.2
1203137	Soil	24	0.80	115	0.044	3	1.52	0.013	0.04	0.1	0.04	2.6	<0.1	<0.05	5	<0.5	<0.2
1203138	Soil	30	0.90	123	0.057	5	1.49	0.019	0.04	0.2	0.03	3.2	<0.1	<0.05	4	<0.5	<0.2
1203139	Soil	30	0.92	126	0.046	4	1.60	0.014	0.04	0.1	0.03	3.2	<0.1	<0.05	5	<0.5	<0.2
1203140	Soil	28	0.92	123	0.047	4	1.53	0.013	0.04	0.1	0.02	3.0	<0.1	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000490.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203141	Soil	0.6	15.8	5.4	59	<0.1	19.3	12.9	716	2.61	3.8	1.7	1.2	18	0.1	0.2	<0.1	54	0.37	0.059	7
1203142	Soil	0.8	13.6	5.6	53	<0.1	20.2	15.9	862	2.71	3.8	3.6	1.3	17	0.1	0.1	<0.1	54	0.38	0.064	6
1203143	Soil	0.5	15.2	5.6	58	<0.1	18.2	16.2	1014	2.58	3.7	2.6	1.2	17	0.1	0.2	<0.1	55	0.34	0.060	7
1203144	Soil	0.6	15.2	5.3	56	<0.1	19.0	13.0	664	2.44	3.7	2.4	1.3	17	<0.1	0.2	0.1	49	0.34	0.048	7
1203145	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203146	Soil	0.6	46.4	13.4	116	0.2	27.5	16.6	542	2.78	3.8	5.9	1.7	18	0.5	0.2	0.2	46	0.45	0.046	6
1203147	Soil	0.7	39.2	3.7	57	<0.1	61.6	15.2	542	2.54	3.1	1.8	1.0	23	0.1	0.2	<0.1	51	0.75	0.048	5
1203148	Soil	0.4	44.5	3.4	52	<0.1	56.8	15.0	522	2.41	3.3	3.9	1.2	27	<0.1	0.2	<0.1	49	1.04	0.046	6
1203149	Soil	0.7	22.9	4.6	52	<0.1	36.5	15.6	577	2.47	4.0	4.7	2.2	23	0.1	0.2	0.1	48	0.51	0.055	7
1203150	Soil	0.4	14.0	4.1	39	<0.1	20.4	8.4	177	1.91	3.4	1.0	0.9	17	<0.1	0.2	<0.1	38	0.35	0.030	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000490.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203141	Soil	32	0.95	124	0.044	5	1.68	0.014	0.04	0.1	0.02	3.2	<0.1	<0.05	5	<0.5	<0.2
1203142	Soil	32	1.07	109	0.046	4	1.64	0.012	0.04	0.1	0.03	3.0	<0.1	<0.05	5	<0.5	<0.2
1203143	Soil	31	1.02	123	0.046	1	1.70	0.012	0.05	0.1	0.04	3.3	<0.1	<0.05	5	<0.5	<0.2
1203144	Soil	30	1.00	121	0.043	3	1.64	0.013	0.04	<0.1	0.03	3.2	<0.1	<0.05	5	0.5	<0.2
1203145	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203146	Soil	42	1.25	87	0.055	1	1.70	0.014	0.04	0.1	0.03	3.3	<0.1	<0.05	4	<0.5	<0.2
1203147	Soil	125	1.77	108	0.046	3	2.01	0.016	0.03	0.1	0.04	3.0	<0.1	<0.05	5	<0.5	<0.2
1203148	Soil	123	1.65	126	0.038	3	2.02	0.015	0.04	0.1	0.04	2.7	<0.1	<0.05	5	<0.5	<0.2
1203149	Soil	62	1.21	117	0.051	<1	1.77	0.017	0.06	0.1	0.03	2.8	<0.1	<0.05	5	<0.5	<0.2
1203150	Soil	39	0.75	91	0.055	2	1.39	0.018	0.03	0.2	0.04	2.3	<0.1	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000490.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1203123	Soil	0.8	28.2	17.3	61	<0.1	26.9	11.0	372	2.76	5.4	3.0	7.9	28	<0.1	0.3	0.2	69	0.46	0.058	22
REP 1203123	QC	0.8	29.1	17.4	62	<0.1	27.2	10.9	374	2.78	5.7	3.3	8.0	29	0.1	0.3	0.2	69	0.48	0.059	22
1203149	Soil	0.7	22.9	4.6	52	<0.1	36.5	15.6	577	2.47	4.0	4.7	2.2	23	0.1	0.2	0.1	48	0.51	0.055	7
REP 1203149	QC	0.7	22.5	4.3	52	<0.1	34.1	14.9	568	2.41	3.7	1.9	2.1	21	<0.1	0.2	<0.1	46	0.49	0.051	7
Reference Materials																					
STD DS8	Standard	13.6	121.8	130.8	330	1.8	42.5	8.0	644	2.48	25.6	102.1	7.4	68	2.4	5.8	6.8	46	0.70	0.083	15
STD DS8	Standard	14.6	125.3	133.3	331	1.9	42.4	8.1	654	2.54	26.6	111.4	7.7	71	2.4	5.8	6.7	46	0.72	0.084	16
STD DS8	Standard	12.9	107.9	110.7	322	1.9	39.4	7.3	631	2.53	28.9	120.2	5.7	61	2.3	4.8	6.2	41	0.71	0.087	13
STD DS8	Standard	13.1	109.2	110.2	326	1.8	39.3	7.7	656	2.63	29.6	118.1	5.9	62	2.2	5.0	6.2	42	0.73	0.089	13
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000490.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1203123	Soil	39	0.59	165	0.121	2	1.93	0.022	0.05	0.1	0.03	5.0	<0.1	<0.05	6	<0.5	<0.2
REP 1203123	QC	40	0.60	167	0.127	2	1.97	0.023	0.06	0.1	0.03	5.2	<0.1	<0.05	6	<0.5	<0.2
1203149	Soil	62	1.21	117	0.051	<1	1.77	0.017	0.06	0.1	0.03	2.8	<0.1	<0.05	5	<0.5	<0.2
REP 1203149	QC	58	1.15	113	0.047	2	1.66	0.016	0.05	0.1	0.03	2.6	<0.1	<0.05	5	<0.5	<0.2
Reference Materials																	
STD DS8	Standard	126	0.65	271	0.139	4	0.94	0.093	0.44	3.1	0.22	2.2	5.5	0.20	5	4.8	4.8
STD DS8	Standard	131	0.65	292	0.145	2	0.95	0.098	0.45	3.1	0.22	2.1	5.7	0.19	5	5.7	5.0
STD DS8	Standard	116	0.63	295	0.100	3	0.94	0.093	0.43	3.2	0.21	2.1	5.6	0.16	5	5.1	5.7
STD DS8	Standard	121	0.64	300	0.102	5	0.92	0.093	0.44	3.1	0.19	2.1	5.7	0.14	5	5.5	5.6
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Submitted By: Daithi Mac Gerailt
Receiving Lab: Canada-Whitehorse
Received: July 07, 2011
Report Date: August 11, 2011
Page: 1 of 9

CERTIFICATE OF ANALYSIS WHI11000493.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID: July-1st-2011
P.O. Number
Number of Samples: 218

SAMPLE DISPOSAL

DISP-PLP Dispose of Pulp After 90 days
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	213	Dry at 60C			WHI
SS80	213	Dry at 60C sieve 100g to -80 mesh			WHI
1DX2	213	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Don Christie
Bruce Durham
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202911	Soil		0.5	28.0	7.7	55	<0.1	86.5	15.6	363	3.08	6.2	1.7	3.3	39	<0.1	0.2	0.1	56	0.70	0.053	13
1202912	Soil		0.5	28.7	7.5	69	0.1	64.0	16.9	518	3.69	7.1	1.4	2.7	32	0.1	0.2	0.1	67	0.79	0.071	11
1202913	Soil		0.7	33.9	8.9	76	0.2	59.9	16.1	593	3.96	7.4	1.5	5.3	29	<0.1	0.3	0.1	68	0.71	0.088	24
1202914	Soil		0.6	60.4	33.8	127	0.4	42.1	15.1	484	3.45	6.6	1.9	3.2	45	0.3	0.3	0.4	57	1.05	0.056	11
1202915	Soil		0.8	37.9	11.5	69	0.1	38.5	16.1	564	3.60	9.6	3.9	3.6	29	<0.1	0.3	0.2	67	0.67	0.055	17
1202916	Soil		0.8	29.2	10.2	70	0.1	35.8	14.1	445	3.74	9.1	2.8	4.0	26	<0.1	0.3	0.2	73	0.52	0.050	18
1202917	Soil		1.5	39.3	17.1	106	<0.1	58.8	18.3	730	4.49	4.7	1.0	9.6	24	0.3	0.2	0.2	63	0.62	0.081	30
1202918	Soil		0.6	33.2	9.4	94	<0.1	52.4	21.0	538	4.59	4.3	2.3	5.3	33	0.1	0.1	0.1	55	0.64	0.058	13
1202919	Soil		0.6	40.2	12.8	74	0.1	46.8	18.2	723	3.95	7.3	2.3	3.8	42	0.1	0.3	0.1	61	1.11	0.071	18
1202920	Soil		0.5	42.4	10.8	70	0.2	46.8	20.8	565	4.00	7.9	3.2	3.6	27	0.2	0.2	0.1	67	0.62	0.063	28
1202921	Soil		0.8	34.6	9.9	77	0.2	40.4	14.9	510	3.78	8.5	1.3	3.6	28	0.1	0.3	0.1	71	0.80	0.075	19
1202922	Soil		0.9	45.4	6.7	77	<0.1	187.9	23.1	545	4.06	5.9	1.2	3.8	27	<0.1	0.2	0.1	63	0.62	0.066	12
1202923	Soil		0.9	36.9	8.7	70	0.2	38.8	13.3	520	3.11	11.6	6.7	2.6	27	0.1	0.3	0.2	62	0.55	0.089	15
1202924	Soil		1.2	29.5	8.1	59	0.3	40.2	14.0	390	3.76	37.3	2.5	3.9	19	0.2	0.7	0.1	72	0.19	0.044	14
1202925	Soil		1.2	25.2	10.8	56	0.2	29.2	15.4	627	3.60	7.3	1.3	6.2	26	<0.1	0.3	0.2	61	0.42	0.056	18
1202926	Soil		0.7	55.4	9.7	165	0.1	67.1	17.1	642	4.15	6.1	0.6	4.4	38	0.6	0.2	0.1	80	0.76	0.092	21
1202927	Soil		0.4	27.3	8.6	68	<0.1	35.9	15.1	520	3.24	8.7	2.5	2.6	30	<0.1	0.2	0.1	66	0.68	0.069	13
1202928	Soil		0.7	37.6	7.1	84	<0.1	42.3	18.4	451	3.97	5.7	0.5	3.8	17	0.2	0.2	0.2	65	0.23	0.032	8
1202929	Soil		0.5	53.8	7.2	81	0.2	41.7	16.3	735	3.58	5.7	0.6	1.9	32	0.2	0.2	<0.1	67	1.77	0.078	15
1202930	Soil		1.0	42.0	11.8	138	<0.1	44.6	16.9	635	4.97	5.8	<0.5	4.2	15	0.3	0.2	0.1	79	0.48	0.165	10
1202931	Soil		0.5	46.5	8.4	79	<0.1	53.3	18.5	386	3.59	6.1	2.1	4.7	44	<0.1	0.2	0.1	58	0.80	0.081	24
1202932	Soil		0.6	40.6	9.5	99	<0.1	68.0	24.4	673	5.02	3.1	<0.5	6.5	18	<0.1	0.2	0.5	49	0.35	0.057	10
1202933	Soil		0.4	66.9	12.6	100	0.3	42.3	14.7	340	3.00	5.7	5.8	4.8	30	0.2	0.4	0.4	67	0.57	0.076	17
1202934	Soil		0.7	31.2	6.7	65	<0.1	37.4	12.6	254	2.90	7.5	3.6	5.8	20	0.1	0.4	0.2	57	0.29	0.062	23
1202935	Soil		0.8	12.1	5.9	23	<0.1	9.1	3.6	109	1.43	4.8	1.2	1.1	11	<0.1	0.2	0.3	43	0.12	0.020	6
1202936	Soil		1.1	41.9	13.3	92	<0.1	40.6	14.8	340	3.83	4.1	4.3	9.3	24	0.2	0.2	0.3	64	0.39	0.064	33
1202937	Soil		1.0	24.7	9.6	51	<0.1	30.7	12.2	275	3.35	11.3	1.6	4.8	17	0.1	0.7	0.3	67	0.18	0.042	15
1202938	Soil		1.4	33.2	11.5	47	<0.1	23.9	8.8	213	3.80	8.9	2.0	2.7	14	0.1	0.5	0.4	79	0.13	0.034	12
1202939	Soil		1.0	33.6	9.1	70	<0.1	34.0	12.9	256	3.35	8.5	<0.5	4.1	13	0.2	0.4	0.3	67	0.14	0.029	10
1202940	Soil		1.7	22.7	11.3	42	<0.1	22.8	9.1	184	3.35	9.3	2.9	3.9	13	0.1	0.5	0.3	65	0.13	0.032	31

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202911	Soil	54	0.90	140	0.075	3	1.94	0.020	0.06	0.1	0.04	4.5	0.1	<0.05	6	<0.5	<0.2
1202912	Soil	58	0.87	152	0.056	3	1.99	0.017	0.05	0.2	0.04	4.2	<0.1	<0.05	6	<0.5	<0.2
1202913	Soil	66	0.95	200	0.059	2	2.09	0.015	0.06	<0.1	0.05	5.3	0.2	<0.05	6	0.6	<0.2
1202914	Soil	43	0.85	179	0.068	6	2.04	0.019	0.05	<0.1	0.04	3.8	<0.1	<0.05	6	<0.5	<0.2
1202915	Soil	40	0.67	221	0.056	4	2.07	0.021	0.06	0.1	0.07	5.2	0.1	<0.05	6	<0.5	<0.2
1202916	Soil	41	0.70	193	0.057	2	2.35	0.016	0.06	0.1	0.04	4.7	0.1	<0.05	7	<0.5	<0.2
1202917	Soil	56	1.21	162	0.027	2	2.80	0.009	0.13	<0.1	0.02	4.9	0.1	<0.05	9	0.8	<0.2
1202918	Soil	59	1.30	124	0.122	3	2.74	0.011	0.30	<0.1	0.02	3.2	0.3	<0.05	8	<0.5	<0.2
1202919	Soil	47	1.04	169	0.094	3	2.24	0.028	0.11	<0.1	0.04	4.9	0.1	<0.05	7	<0.5	<0.2
1202920	Soil	52	0.90	182	0.087	2	2.64	0.019	0.07	<0.1	0.04	5.1	0.2	<0.05	7	<0.5	<0.2
1202921	Soil	46	0.89	175	0.071	4	2.60	0.018	0.10	0.1	0.04	4.9	0.1	<0.05	7	<0.5	<0.2
1202922	Soil	108	1.31	193	0.128	3	2.62	0.016	0.34	<0.1	0.02	3.2	0.3	<0.05	7	0.6	<0.2
1202923	Soil	43	0.58	232	0.049	2	2.09	0.017	0.05	0.1	0.04	5.1	0.1	<0.05	6	<0.5	<0.2
1202924	Soil	44	0.48	155	0.054	4	2.45	0.012	0.07	<0.1	0.04	4.3	0.1	<0.05	7	0.8	<0.2
1202925	Soil	36	0.61	203	0.025	<1	2.52	0.012	0.06	<0.1	0.02	3.6	0.1	<0.05	8	0.5	<0.2
1202926	Soil	50	2.01	180	0.125	<1	3.59	0.014	0.25	0.1	0.02	3.2	0.4	<0.05	8	<0.5	<0.2
1202927	Soil	39	0.86	186	0.076	2	2.29	0.026	0.06	0.1	0.03	4.3	0.1	<0.05	6	0.6	<0.2
1202928	Soil	49	1.08	147	0.113	2	2.78	0.010	0.27	0.2	0.01	2.6	0.2	<0.05	8	<0.5	<0.2
1202929	Soil	50	1.12	214	0.089	5	2.02	0.016	0.20	0.1	0.05	2.8	0.3	<0.05	6	0.6	<0.2
1202930	Soil	49	1.33	101	0.114	2	2.84	0.010	0.39	<0.1	0.02	3.0	0.3	<0.05	8	0.5	<0.2
1202931	Soil	51	0.94	165	0.102	5	2.11	0.024	0.15	0.1	0.05	4.0	0.2	<0.05	6	0.6	<0.2
1202932	Soil	67	1.71	143	0.157	2	2.84	0.009	1.02	<0.1	<0.01	1.4	0.7	<0.05	6	<0.5	<0.2
1202933	Soil	42	0.79	172	0.051	<1	1.79	0.015	0.05	0.1	0.05	4.2	<0.1	<0.05	6	<0.5	<0.2
1202934	Soil	35	0.60	138	0.077	2	1.55	0.011	0.10	0.1	0.02	2.7	<0.1	<0.05	4	<0.5	<0.2
1202935	Soil	15	0.21	61	0.059	1	0.83	0.014	0.04	<0.1	0.02	1.5	<0.1	<0.05	5	<0.5	<0.2
1202936	Soil	50	0.89	196	0.053	2	2.07	0.010	0.19	<0.1	0.02	4.6	0.2	<0.05	7	0.8	<0.2
1202937	Soil	34	0.48	165	0.058	<1	2.11	0.011	0.05	0.1	0.03	3.2	<0.1	<0.05	6	<0.5	<0.2
1202938	Soil	37	0.45	144	0.075	1	2.18	0.009	0.06	<0.1	0.03	3.2	<0.1	<0.05	8	<0.5	<0.2
1202939	Soil	35	0.54	140	0.062	1	1.79	0.008	0.06	<0.1	0.02	2.6	<0.1	<0.05	7	<0.5	<0.2
1202940	Soil	26	0.42	135	0.063	<1	1.67	0.009	0.05	0.1	0.02	2.2	<0.1	<0.05	7	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202941	Soil	1.5	16.1	10.1	55	<0.1	17.8	9.6	308	3.44	9.4	2.3	2.4	14	0.2	0.5	0.3	75	0.12	0.052	7
1202942	Soil	0.8	25.1	6.6	92	<0.1	28.1	14.5	608	4.04	3.5	1.2	1.9	15	0.1	0.2	0.1	71	0.25	0.124	6
1202943	Soil	0.6	22.0	7.6	56	<0.1	30.5	12.3	402	3.07	6.1	1.5	2.8	21	<0.1	0.3	0.2	59	0.31	0.076	10
1202944	Soil	0.5	26.4	5.8	117	<0.1	24.2	17.1	710	4.32	4.0	0.7	4.0	17	0.1	0.2	<0.1	69	0.38	0.148	17
1202945	Soil	1.1	21.9	12.7	63	<0.1	23.0	10.8	378	3.51	7.8	1.5	3.3	18	<0.1	0.5	0.2	68	0.21	0.040	11
1202946	Soil	1.3	34.3	11.7	70	0.2	30.0	10.6	313	3.61	13.2	2.2	3.8	18	<0.1	0.6	0.2	71	0.18	0.053	16
1202947	Soil	0.4	25.9	5.6	113	<0.1	27.8	16.8	671	4.05	3.9	0.7	5.0	17	<0.1	0.2	<0.1	61	0.36	0.115	13
1202948	Soil	0.7	19.1	10.8	82	<0.1	24.0	11.9	439	3.31	6.5	2.2	3.7	17	<0.1	0.4	0.1	65	0.24	0.055	11
1202949	Soil	1.0	27.4	10.3	88	0.1	27.4	13.7	527	3.27	14.8	3.6	4.2	18	0.2	1.1	0.1	61	0.26	0.081	13
1202950	Soil	1.9	72.5	6.5	112	0.1	62.9	22.2	661	5.99	4.8	2.7	3.8	27	0.2	0.4	<0.1	120	0.47	0.182	24
1202951	Soil	1.4	55.2	7.5	84	0.4	39.9	16.2	462	4.40	7.2	1.2	2.7	27	0.3	0.4	0.1	88	0.44	0.135	15
1202952	Soil	1.2	43.9	10.3	75	0.2	41.0	13.3	382	3.33	6.9	1.3	2.8	24	0.2	0.4	0.2	65	0.21	0.075	12
1202953	Soil	1.5	32.3	8.7	53	0.2	26.2	11.6	311	2.97	7.4	0.6	3.0	20	<0.1	0.4	0.1	51	0.22	0.061	12
1202954	Soil	2.9	128.0	13.6	115	2.2	51.4	12.1	814	3.67	11.1	11.2	1.6	36	1.1	1.4	0.2	45	0.90	0.130	22
1202955	Soil	1.5	44.5	19.3	93	0.3	39.8	15.5	1068	3.42	12.7	8.8	6.3	26	0.4	0.9	0.2	49	0.31	0.047	20
1202956	Soil	1.8	50.2	12.0	74	0.3	24.9	11.9	533	3.20	26.1	16.2	2.4	34	0.2	1.0	0.1	58	0.56	0.093	12
1202957	Soil	0.8	56.3	8.5	55	<0.1	18.7	13.4	571	3.10	3.3	1.7	3.0	9	<0.1	0.3	0.4	47	0.18	0.046	8
1202958	Soil	1.7	33.1	25.6	42	0.2	21.2	8.2	191	2.67	8.4	12.7	7.3	14	<0.1	1.0	0.7	46	0.16	0.044	27
1202959	Soil	1.8	17.1	11.9	47	<0.1	21.5	10.1	297	3.70	10.5	3.1	2.7	15	0.1	0.7	0.1	68	0.15	0.051	8
1202960	Soil	1.3	21.2	13.3	48	<0.1	24.9	13.1	395	2.84	9.3	2.9	4.4	15	<0.1	3.1	0.3	53	0.16	0.039	9
1202961	Soil	0.5	9.0	5.6	26	<0.1	4.5	3.9	307	1.10	2.6	<0.5	0.5	10	<0.1	0.2	<0.1	23	0.09	0.028	5
1202962	Soil	3.0	31.0	100.0	67	0.4	17.6	8.3	467	2.82	8.8	5.6	5.8	29	0.2	1.0	0.3	60	0.27	0.062	88
1202963	Soil	1.2	23.4	43.2	53	0.2	19.3	8.8	430	2.48	7.0	7.4	5.7	21	0.2	0.6	0.1	52	0.23	0.042	33
1202964	Soil	1.5	36.2	51.1	80	0.3	20.7	8.3	373	2.61	6.6	2.0	7.4	20	0.2	0.6	0.2	51	0.22	0.042	34
1202965	Soil	1.0	33.6	39.1	63	0.2	20.6	8.3	325	2.55	6.2	3.9	4.8	23	0.1	0.7	<0.1	52	0.29	0.053	32
1202966	Soil	1.0	32.5	30.6	57	0.1	21.7	8.6	238	2.62	5.8	1.8	6.5	21	<0.1	0.5	<0.1	53	0.27	0.057	24
1202967	Soil	1.5	38.9	34.8	65	0.1	18.8	8.8	274	2.73	5.4	1.9	6.9	17	0.1	0.6	0.3	56	0.23	0.044	17
1202968	Soil	1.5	65.5	64.0	120	0.2	22.8	11.7	556	3.07	6.7	4.3	2.8	24	0.2	0.6	0.3	57	0.25	0.045	18
1202969	Soil	0.6	48.0	11.3	64	<0.1	22.4	15.4	521	3.04	4.0	4.2	3.8	21	<0.1	0.3	0.1	58	0.36	0.094	21
1202970	Soil	0.5	47.6	9.4	48	<0.1	30.9	13.1	371	2.40	2.9	2.7	2.6	25	0.1	0.2	0.1	47	0.40	0.092	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202941	Soil		35	0.53	190	0.083	<1	1.91	0.009	0.11	0.1	0.02	2.1	<0.1	<0.05	8	<0.5	<0.2
1202942	Soil		72	1.52	294	0.187	<1	2.59	0.008	0.75	0.1	0.02	1.6	0.5	<0.05	7	0.5	<0.2
1202943	Soil		55	0.83	232	0.102	2	1.97	0.012	0.16	0.2	0.03	2.5	0.2	<0.05	5	<0.5	<0.2
1202944	Soil		93	1.73	907	0.141	<1	2.85	0.008	1.06	<0.1	0.02	2.3	0.4	<0.05	7	0.7	<0.2
1202945	Soil		50	0.75	386	0.097	<1	2.19	0.013	0.15	0.1	0.03	2.9	0.1	<0.05	6	<0.5	<0.2
1202946	Soil		47	0.59	378	0.084	2	2.52	0.012	0.10	0.1	0.04	3.8	0.1	<0.05	7	0.7	<0.2
1202947	Soil		89	1.80	569	0.165	<1	2.78	0.008	1.10	0.1	<0.01	1.3	0.5	<0.05	6	<0.5	<0.2
1202948	Soil		55	1.01	309	0.137	<1	2.19	0.008	0.43	0.1	<0.01	1.9	0.3	<0.05	6	<0.5	<0.2
1202949	Soil		46	0.76	242	0.094	<1	1.70	0.008	0.25	0.1	0.02	2.6	0.2	<0.05	5	0.6	<0.2
1202950	Soil		93	1.76	914	0.214	<1	3.07	0.010	1.22	<0.1	0.02	6.8	0.2	<0.05	10	0.6	<0.2
1202951	Soil		56	1.25	559	0.158	<1	2.41	0.012	0.55	<0.1	0.03	4.7	0.1	<0.05	8	<0.5	<0.2
1202952	Soil		45	0.61	232	0.084	<1	1.68	0.010	0.20	0.1	0.02	3.6	<0.1	<0.05	5	<0.5	<0.2
1202953	Soil		42	0.54	216	0.077	1	1.49	0.012	0.23	<0.1	0.03	2.8	<0.1	<0.05	5	1.1	<0.2
1202954	Soil		33	0.58	257	0.022	5	1.37	0.023	0.16	0.1	0.25	5.7	0.1	0.21	3	3.3	<0.2
1202955	Soil		34	0.42	134	0.045	2	1.19	0.014	0.15	0.1	0.05	5.6	<0.1	<0.05	3	<0.5	<0.2
1202956	Soil		32	0.53	158	0.050	1	1.26	0.019	0.09	0.1	0.05	4.3	<0.1	0.06	4	0.6	<0.2
1202957	Soil		26	1.05	102	0.034	<1	1.73	0.006	0.04	<0.1	0.08	4.0	<0.1	<0.05	5	0.5	<0.2
1202958	Soil		26	0.42	95	0.059	<1	1.56	0.009	0.05	0.1	0.07	3.4	<0.1	<0.05	4	<0.5	<0.2
1202959	Soil		36	0.46	118	0.062	<1	2.55	0.010	0.03	0.1	0.04	3.1	<0.1	<0.05	7	<0.5	<0.2
1202960	Soil		29	0.53	125	0.064	1	2.14	0.012	0.06	0.1	0.04	2.9	<0.1	<0.05	5	<0.5	<0.2
1202961	Soil		8	0.12	51	0.034	<1	0.73	0.014	0.03	<0.1	0.02	0.7	<0.1	<0.05	3	<0.5	<0.2
1202962	Soil		26	0.41	150	0.053	1	1.86	0.013	0.05	0.1	0.08	2.2	<0.1	0.06	6	<0.5	<0.2
1202963	Soil		25	0.44	117	0.066	<1	1.51	0.012	0.05	0.1	0.04	2.2	<0.1	<0.05	5	<0.5	<0.2
1202964	Soil		27	0.47	219	0.065	1	1.65	0.017	0.04	0.1	0.06	2.7	<0.1	<0.05	4	<0.5	<0.2
1202965	Soil		27	0.51	189	0.064	1	1.64	0.012	0.05	0.1	0.03	2.9	<0.1	<0.05	4	0.5	<0.2
1202966	Soil		30	0.54	172	0.073	<1	1.82	0.011	0.05	0.1	0.04	3.0	<0.1	<0.05	5	<0.5	<0.2
1202967	Soil		28	0.56	178	0.058	2	1.77	0.010	0.05	0.1	0.03	3.0	<0.1	<0.05	5	<0.5	<0.2
1202968	Soil		32	0.62	316	0.049	2	1.81	0.011	0.05	0.1	0.11	4.0	<0.1	<0.05	5	<0.5	<0.2
1202969	Soil		35	1.37	200	0.048	<1	2.11	0.008	0.06	<0.1	0.04	4.6	<0.1	0.06	6	<0.5	<0.2
1202970	Soil		47	1.03	217	0.051	<1	1.62	0.007	0.06	0.1	<0.01	2.5	<0.1	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202971	Soil	0.5	38.3	10.7	57	<0.1	22.1	16.3	453	3.37	3.7	2.3	5.3	42	<0.1	0.2	0.1	75	0.53	0.165	23
1202972	Soil	0.7	32.7	10.0	66	0.1	18.4	16.9	752	3.64	2.0	5.7	3.7	69	0.1	0.2	0.1	44	0.48	0.166	13
1202973	Soil	2.3	61.7	15.4	85	0.3	76.9	18.3	489	3.41	7.7	2.0	2.1	24	0.3	0.3	0.2	74	0.26	0.061	13
1202974	Soil	1.9	42.9	14.2	81	0.1	47.9	16.5	541	3.78	41.1	3.2	2.9	14	0.5	0.9	0.2	61	0.17	0.045	8
1202975	Soil	1.9	42.6	13.3	59	0.2	38.4	16.4	413	3.94	50.4	7.1	3.8	9	0.2	0.9	0.2	55	0.11	0.035	11
1202976	Soil	1.7	24.9	10.1	46	0.2	20.4	7.9	214	2.68	20.4	6.9	1.8	15	0.2	0.5	0.2	55	0.18	0.043	8
1202977	Soil	0.9	29.1	7.4	52	<0.1	29.8	13.2	369	3.09	13.6	6.3	2.8	18	0.2	0.4	0.1	65	0.21	0.027	8
1202978	Soil	1.5	31.8	52.2	71	0.2	20.9	9.1	262	2.77	6.5	4.7	4.6	16	0.1	0.3	0.2	36	0.17	0.034	15
1202979	Soil	0.8	28.8	17.0	46	<0.1	20.9	12.0	368	2.56	4.0	2.6	7.4	16	<0.1	0.3	0.2	37	0.21	0.041	42
1202980	Soil	1.5	19.4	24.5	43	<0.1	15.6	8.9	361	2.50	9.1	5.4	10.0	11	0.1	0.4	0.4	31	0.12	0.032	28
1202981	Soil	0.9	40.3	35.8	46	0.2	35.1	13.7	564	2.72	6.9	5.5	5.6	20	0.2	0.4	0.5	30	0.26	0.052	21
1202982	Soil	1.9	12.1	70.6	62	<0.1	8.3	3.8	118	1.78	3.4	5.9	16.6	8	0.2	0.3	0.8	29	0.08	0.018	55
1202983	Soil	2.5	41.5	29.4	53	0.3	6.0	3.3	263	1.34	1.1	2.9	23.0	5	0.2	0.1	3.0	9	0.04	0.011	67
1202984	Soil	2.5	19.9	21.5	26	<0.1	7.3	3.5	70	1.07	2.2	5.0	23.9	5	<0.1	0.2	0.8	21	0.06	0.012	28
1202985	Soil	0.9	10.7	25.2	26	<0.1	12.1	5.8	119	1.69	4.4	1.2	15.2	7	<0.1	0.3	0.2	32	0.07	0.020	12
1202986	Soil	0.4	6.6	25.9	23	<0.1	5.0	2.0	72	0.68	1.4	1.6	21.5	5	<0.1	0.2	0.2	14	0.06	0.009	25
1202987	Soil	0.5	16.5	44.0	34	<0.1	9.5	3.7	99	1.29	2.4	1.5	9.9	12	<0.1	0.2	0.3	31	0.14	0.024	28
1202988	Soil	0.5	44.6	7.6	28	<0.1	25.6	9.9	237	1.61	3.1	19.7	2.6	14	<0.1	0.2	0.1	35	0.26	0.043	8
1202989	Soil	0.5	39.7	4.6	22	<0.1	26.3	11.1	214	1.87	2.9	1.2	3.1	11	<0.1	0.2	<0.1	36	0.23	0.057	6
1202990	Soil	0.5	34.4	9.8	42	<0.1	25.5	14.4	393	2.57	3.6	1.8	6.0	17	<0.1	0.2	<0.1	57	0.24	0.071	31
1202991	Soil	0.3	3.2	6.0	9	<0.1	1.4	1.0	34	0.37	<0.5	0.8	0.2	5	<0.1	<0.1	<0.1	9	0.05	0.009	2
1202992	Soil	0.6	28.7	15.2	44	<0.1	18.1	8.8	304	2.27	4.8	3.7	3.7	20	0.1	0.2	0.1	54	0.28	0.062	12
1202993	Soil	1.0	21.4	18.6	42	<0.1	13.7	7.1	274	2.29	5.4	1.8	2.8	16	0.2	0.3	0.2	55	0.22	0.050	10
1202994	Soil	0.8	22.3	19.6	46	<0.1	17.2	6.8	248	1.93	3.5	1.8	2.6	16	0.1	0.2	0.2	42	0.22	0.038	7
1202995	Soil	0.5	40.1	11.5	55	<0.1	41.6	13.7	485	2.83	3.3	2.5	3.2	23	0.2	0.2	0.1	62	0.34	0.050	14
1202996	Soil	0.6	40.5	13.7	60	<0.1	34.3	12.1	443	2.87	3.9	2.6	3.5	21	<0.1	0.2	0.2	61	0.36	0.049	14
1202997	Soil	0.5	51.2	11.1	62	<0.1	38.8	14.1	582	3.33	3.4	3.7	3.0	20	0.2	0.2	0.1	68	0.38	0.055	12
1202998	Soil	0.6	40.6	12.2	59	0.1	30.7	11.2	450	2.98	3.6	2.7	2.6	22	0.2	0.2	0.2	58	0.35	0.051	12
1202999	Soil	1.5	27.8	66.4	63	<0.1	14.6	6.7	242	2.65	7.1	5.3	5.5	15	0.2	1.6	0.3	45	0.16	0.036	24
1203000	Soil	1.4	30.3	59.1	77	0.1	18.9	8.2	285	2.68	8.9	4.5	5.1	17	0.2	2.6	0.3	52	0.20	0.043	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202971	Soil		29	1.28	525	0.077	<1	1.91	0.007	0.27	0.1	0.02	3.8	0.2	<0.05	7	<0.5	<0.2
1202972	Soil		18	0.91	413	0.052	<1	1.57	0.009	0.15	<0.1	0.02	3.5	0.2	<0.05	5	<0.5	<0.2
1202973	Soil		144	1.36	211	0.057	<1	2.06	0.009	0.05	<0.1	0.03	4.7	0.1	<0.05	7	0.9	<0.2
1202974	Soil		42	0.55	136	0.058	1	1.93	0.008	0.04	0.1	0.02	3.2	<0.1	<0.05	6	0.8	<0.2
1202975	Soil		33	0.62	107	0.043	<1	1.96	0.006	0.03	<0.1	0.05	2.8	<0.1	<0.05	6	<0.5	<0.2
1202976	Soil		27	0.46	127	0.054	<1	1.77	0.009	0.04	0.1	0.06	2.7	<0.1	<0.05	6	0.6	<0.2
1202977	Soil		36	0.66	162	0.090	1	2.50	0.014	0.04	0.1	0.04	4.5	<0.1	<0.05	6	0.5	<0.2
1202978	Soil		24	0.44	145	0.035	<1	1.47	0.007	0.05	<0.1	0.06	2.8	<0.1	<0.05	4	<0.5	<0.2
1202979	Soil		25	0.51	708	0.026	<1	1.48	0.010	0.05	<0.1	0.02	3.2	<0.1	<0.05	4	<0.5	<0.2
1202980	Soil		18	0.27	155	0.027	1	1.25	0.007	0.06	<0.1	0.02	2.3	<0.1	<0.05	3	<0.5	<0.2
1202981	Soil		29	0.65	121	0.024	1	1.21	0.011	0.07	<0.1	0.03	2.8	0.1	<0.05	3	<0.5	<0.2
1202982	Soil		13	0.17	74	0.030	<1	1.00	0.007	0.04	0.3	0.01	1.1	<0.1	<0.05	4	<0.5	<0.2
1202983	Soil		6	0.10	56	0.007	<1	0.38	0.005	0.05	0.1	0.02	1.4	<0.1	<0.05	1	<0.5	<0.2
1202984	Soil		12	0.32	51	0.022	<1	0.89	0.007	0.04	1.3	0.02	1.0	<0.1	<0.05	3	<0.5	<0.2
1202985	Soil		18	0.29	62	0.035	<1	1.42	0.009	0.03	0.3	0.03	1.5	<0.1	<0.05	4	<0.5	<0.2
1202986	Soil		8	0.24	48	0.014	<1	0.69	0.003	0.04	0.4	<0.01	0.6	<0.1	<0.05	2	<0.5	<0.2
1202987	Soil		17	0.36	89	0.030	<1	1.19	0.007	0.07	0.2	0.02	1.4	<0.1	<0.05	4	<0.5	<0.2
1202988	Soil		40	0.86	91	0.052	<1	1.54	0.009	0.04	<0.1	0.02	1.9	<0.1	<0.05	4	<0.5	<0.2
1202989	Soil		38	1.10	58	0.064	<1	1.46	0.004	0.04	0.1	0.01	2.8	<0.1	<0.05	4	<0.5	<0.2
1202990	Soil		36	1.43	122	0.060	<1	2.08	0.007	0.04	0.1	0.02	5.6	<0.1	<0.05	6	<0.5	<0.2
1202991	Soil		4	0.07	22	0.025	<1	0.24	0.017	0.02	<0.1	0.01	0.4	<0.1	<0.05	2	<0.5	<0.2
1202992	Soil		26	0.60	146	0.078	<1	1.72	0.012	0.06	0.1	0.01	3.0	<0.1	<0.05	5	<0.5	<0.2
1202993	Soil		23	0.43	122	0.075	<1	1.50	0.011	0.07	0.1	0.03	2.2	<0.1	<0.05	6	<0.5	<0.2
1202994	Soil		26	0.53	134	0.058	<1	1.31	0.013	0.05	0.1	0.02	2.2	<0.1	<0.05	5	<0.5	<0.2
1202995	Soil		76	1.17	209	0.054	<1	1.99	0.011	0.04	<0.1	0.03	4.8	<0.1	<0.05	6	<0.5	<0.2
1202996	Soil		54	1.10	167	0.060	1	2.13	0.010	0.05	<0.1	0.04	4.1	<0.1	<0.05	6	<0.5	<0.2
1202997	Soil		71	1.31	174	0.047	<1	2.11	0.009	0.03	0.1	0.04	5.9	<0.1	<0.05	6	<0.5	<0.2
1202998	Soil		51	0.95	169	0.047	<1	1.95	0.010	0.04	0.1	0.05	4.7	<0.1	<0.05	6	<0.5	<0.2
1202999	Soil		23	0.37	108	0.055	2	1.53	0.012	0.05	<0.1	0.04	2.2	<0.1	<0.05	5	0.5	<0.2
1203000	Soil		27	0.47	148	0.066	<1	1.84	0.012	0.04	<0.1	0.04	2.9	<0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203001	Soil		1.5	34.1	30.5	62	<0.1	19.2	9.7	329	2.88	6.2	3.7	6.9	13	0.2	0.6	0.3	54	0.18	0.041	16
1203002	Soil		1.4	34.3	14.8	59	<0.1	17.4	10.0	336	2.69	7.1	4.5	4.0	17	0.1	0.7	0.2	55	0.20	0.047	13
1203003	Soil		1.0	36.0	12.0	62	<0.1	20.1	11.3	364	3.14	7.1	6.3	3.3	20	0.1	0.3	0.3	52	0.25	0.060	13
1203004	Soil		1.0	11.6	7.7	22	<0.1	6.3	3.7	197	1.22	4.4	1.6	0.7	16	<0.1	0.2	0.2	31	0.14	0.027	10
1203005	Soil		0.4	35.9	7.9	63	<0.1	29.9	18.5	622	3.24	5.2	3.5	2.6	27	<0.1	0.2	<0.1	64	0.48	0.114	16
1203006	Soil		0.5	51.9	13.8	50	<0.1	38.1	15.4	595	2.72	5.4	3.2	6.0	41	<0.1	0.2	0.1	52	0.50	0.124	27
1203007	Soil		1.1	25.5	7.2	33	0.2	18.8	12.5	837	2.03	5.3	3.2	0.3	30	<0.1	0.2	0.1	43	0.42	0.087	9
1203008	Soil		0.4	50.1	12.8	48	<0.1	44.3	14.9	481	2.50	5.6	13.1	3.8	37	0.1	0.2	0.1	51	0.52	0.094	17
1203009	Soil		0.4	44.5	9.7	53	<0.1	54.8	22.6	894	3.00	5.9	6.6	2.2	39	<0.1	0.2	0.1	61	0.62	0.094	11
1203010	Soil		0.5	43.9	6.2	59	<0.1	39.7	18.0	863	2.58	4.4	5.0	0.8	47	0.2	0.2	0.1	53	0.85	0.077	10
1203011	Soil		0.5	13.0	3.8	16	0.2	3.9	2.7	109	0.96	4.7	7.6	0.1	19	<0.1	0.1	<0.1	21	0.19	0.051	5
1203012	Soil		1.3	28.6	14.9	58	0.1	18.7	9.9	386	4.05	11.9	3.6	2.4	20	0.2	0.4	0.2	77	0.19	0.032	10
1203013	Soil		2.2	49.8	54.2	72	0.3	16.2	7.0	256	2.95	7.2	5.7	6.9	27	<0.1	0.6	0.5	45	0.26	0.051	18
1203014	Soil		1.7	36.0	16.0	60	0.1	16.8	7.9	257	2.51	7.8	2.7	3.9	24	0.3	0.4	0.3	50	0.23	0.054	17
1203015	Soil		0.6	7.7	4.3	15	<0.1	3.2	1.5	54	0.77	3.6	1.6	0.3	7	<0.1	0.1	<0.1	18	0.04	0.017	3
1203016	Soil		1.6	19.5	22.7	51	0.1	11.3	7.3	392	2.70	9.4	2.3	2.2	13	0.2	0.4	0.2	64	0.13	0.026	8
1203017	Soil		1.2	17.9	23.8	37	0.2	8.9	4.0	212	1.18	5.8	8.9	1.0	19	0.4	0.7	0.1	25	0.17	0.030	8
1203018	Soil		2.5	23.4	33.5	54	0.2	17.0	7.3	252	2.83	11.8	13.3	5.7	15	0.3	1.3	0.2	61	0.16	0.026	12
1203019	Soil		2.4	34.2	24.2	75	0.2	22.3	11.0	401	3.53	12.3	17.1	6.8	19	0.4	1.0	0.2	75	0.19	0.033	14
1203020	Soil		2.0	41.6	36.3	59	0.2	22.3	8.7	340	2.85	11.2	9.0	3.9	19	0.3	0.7	0.3	63	0.17	0.034	13
1203021	Soil		1.0	21.3	15.9	42	<0.1	14.5	6.4	232	2.18	8.0	4.0	3.7	19	0.1	0.4	0.2	49	0.20	0.025	10
1203022	Soil		1.5	19.9	13.3	39	0.2	12.8	5.4	188	1.90	7.0	2.0	2.0	17	0.2	0.3	0.2	44	0.16	0.039	9
1203023	Soil		1.1	13.2	14.0	37	0.2	8.3	4.0	216	1.65	6.3	3.6	1.7	20	0.2	0.3	0.2	40	0.18	0.030	6
1203024	Soil		1.8	29.5	36.8	78	0.2	20.9	10.5	443	3.04	10.4	2.3	6.2	31	0.2	0.5	0.3	70	0.29	0.037	15
1203025	Soil		1.1	26.3	24.1	49	0.1	16.0	6.3	251	2.19	8.0	1.7	3.4	26	0.2	0.3	0.2	48	0.25	0.024	10
1203026	Soil		2.2	43.8	78.4	89	0.1	16.2	8.0	321	2.29	8.1	3.3	9.8	29	0.2	0.6	0.3	46	0.20	0.034	20
1203027	Soil		1.9	33.5	57.3	62	0.1	20.7	8.8	323	2.64	9.6	3.0	7.4	26	0.2	0.5	0.2	60	0.26	0.030	16
1203028	Soil		1.8	35.5	40.5	58	0.3	19.3	7.0	246	2.65	9.2	1.1	4.7	21	0.2	0.3	0.3	59	0.20	0.027	11
1203029	Soil		1.3	25.3	28.0	56	0.3	17.2	8.8	394	2.34	7.7	1.6	4.9	24	0.2	0.3	0.2	48	0.23	0.030	11
1203030	Soil		2.3	22.3	41.4	63	0.1	18.7	7.7	326	2.55	9.3	1.3	8.5	20	0.2	0.3	0.3	59	0.21	0.030	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203001	Soil		29	0.54	128	0.073	<1	1.96	0.010	0.04	0.1	0.03	3.0	<0.1	<0.05	6	<0.5	<0.2
1203002	Soil		26	0.51	167	0.075	2	1.81	0.014	0.04	<0.1	0.04	3.0	<0.1	<0.05	5	<0.5	<0.2
1203003	Soil		29	0.54	256	0.079	2	1.86	0.016	0.05	0.1	0.04	3.3	<0.1	<0.05	5	0.6	<0.2
1203004	Soil		12	0.14	246	0.045	1	0.64	0.018	0.03	<0.1	0.02	1.0	<0.1	<0.05	4	<0.5	<0.2
1203005	Soil		42	1.20	251	0.090	2	1.93	0.010	0.07	<0.1	0.03	4.4	0.1	<0.05	6	<0.5	<0.2
1203006	Soil		53	1.10	254	0.080	1	1.80	0.014	0.10	0.1	0.01	3.6	0.1	<0.05	6	<0.5	<0.2
1203007	Soil		30	0.47	201	0.040	2	1.41	0.022	0.04	<0.1	0.05	1.8	0.1	0.07	5	0.6	<0.2
1203008	Soil		68	1.22	282	0.068	1	1.92	0.013	0.07	0.1	0.03	3.9	<0.1	<0.05	6	<0.5	<0.2
1203009	Soil		81	1.57	300	0.075	1	2.08	0.013	0.07	0.1	0.03	4.6	0.1	<0.05	6	0.8	<0.2
1203010	Soil		57	1.41	500	0.054	2	1.89	0.013	0.07	<0.1	0.04	3.4	0.1	<0.05	6	0.8	<0.2
1203011	Soil		8	0.15	83	0.032	<1	0.57	0.021	0.03	<0.1	0.04	0.9	<0.1	<0.05	3	0.6	<0.2
1203012	Soil		30	0.66	225	0.114	2	2.33	0.014	0.09	<0.1	0.02	3.2	<0.1	<0.05	9	<0.5	<0.2
1203013	Soil		27	0.85	296	0.069	1	1.81	0.013	0.08	<0.1	0.05	3.4	<0.1	<0.05	6	0.8	<0.2
1203014	Soil		26	0.50	134	0.077	1	1.74	0.014	0.06	0.1	0.04	2.8	<0.1	<0.05	6	<0.5	<0.2
1203015	Soil		7	0.08	28	0.039	<1	0.43	0.020	0.03	<0.1	0.03	0.7	<0.1	<0.05	2	<0.5	<0.2
1203016	Soil		23	0.32	103	0.089	1	1.60	0.022	0.04	<0.1	0.04	2.3	<0.1	<0.05	7	<0.5	<0.2
1203017	Soil		14	0.21	119	0.051	<1	0.90	0.019	0.05	<0.1	0.07	1.4	<0.1	<0.05	4	0.6	<0.2
1203018	Soil		27	0.42	96	0.107	2	1.73	0.013	0.06	0.1	0.07	2.5	<0.1	<0.05	6	<0.5	<0.2
1203019	Soil		36	0.52	146	0.118	2	2.46	0.014	0.06	<0.1	0.09	3.8	<0.1	<0.05	7	0.8	<0.2
1203020	Soil		31	0.42	242	0.089	1	2.35	0.018	0.07	<0.1	0.07	3.8	0.1	<0.05	7	0.8	<0.2
1203021	Soil		25	0.41	123	0.097	2	1.59	0.019	0.04	<0.1	0.05	2.8	<0.1	<0.05	5	0.6	<0.2
1203022	Soil		22	0.35	110	0.078	<1	1.50	0.019	0.05	<0.1	0.04	2.4	<0.1	<0.05	6	<0.5	<0.2
1203023	Soil		15	0.22	86	0.069	<1	0.94	0.017	0.05	<0.1	0.03	1.5	<0.1	<0.05	5	<0.5	<0.2
1203024	Soil		31	0.49	153	0.106	1	2.05	0.019	0.08	0.1	0.02	3.1	<0.1	<0.05	7	0.6	<0.2
1203025	Soil		23	0.38	128	0.081	<1	1.56	0.020	0.06	<0.1	0.03	2.4	<0.1	<0.05	5	<0.5	<0.2
1203026	Soil		26	0.36	199	0.091	<1	1.45	0.015	0.06	0.1	0.05	2.7	<0.1	<0.05	5	0.5	<0.2
1203027	Soil		33	0.50	199	0.107	<1	1.94	0.016	0.06	0.1	0.04	3.4	<0.1	<0.05	6	<0.5	<0.2
1203028	Soil		30	0.44	218	0.105	<1	2.15	0.017	0.06	<0.1	0.04	3.3	<0.1	<0.05	8	<0.5	<0.2
1203029	Soil		26	0.42	198	0.093	1	1.70	0.021	0.05	<0.1	0.04	2.9	<0.1	<0.05	5	<0.5	<0.2
1203030	Soil		31	0.44	186	0.100	<1	1.76	0.016	0.07	<0.1	0.03	2.9	<0.1	<0.05	6	0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203031	Soil		1.0	22.9	24.9	54	<0.1	20.2	10.4	479	2.32	6.8	1.4	5.8	21	0.1	0.3	0.2	51	0.21	0.018	12
1203032	Soil		1.3	47.0	18.3	70	0.2	26.9	11.3	779	2.66	7.8	1.3	4.1	39	0.3	0.3	0.2	58	0.72	0.033	14
1203033	Soil		1.2	37.8	27.7	64	0.1	25.3	11.1	488	2.83	8.8	4.1	6.4	37	0.1	0.4	0.2	68	0.51	0.030	16
1203034	Soil		1.7	51.7	22.7	79	0.1	43.9	16.2	709	3.42	9.6	6.0	6.6	28	0.1	0.3	0.2	65	0.42	0.041	17
1203035	Soil		1.3	38.3	18.6	63	<0.1	42.8	14.9	513	3.36	8.1	3.2	6.2	33	0.1	0.2	0.2	62	0.47	0.037	18
1203036	Soil		1.1	45.7	15.2	67	<0.1	54.7	19.1	782	3.78	8.8	4.4	11.2	40	<0.1	0.2	0.2	71	0.59	0.067	35
1203037	Soil		0.9	28.4	14.8	52	<0.1	36.9	15.4	535	3.22	4.9	2.6	8.0	39	<0.1	0.3	0.2	84	0.52	0.050	20
1203038	Soil		1.3	35.0	18.5	65	<0.1	45.3	18.3	524	3.69	5.2	13.4	12.1	37	0.1	0.4	0.3	64	0.41	0.045	28
1203039	Soil		1.2	35.2	18.2	60	<0.1	56.6	20.0	409	3.70	5.3	21.8	9.0	35	<0.1	0.3	0.3	73	0.44	0.026	22
1204013	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1204014	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1204015	Soil		1.3	21.3	6.5	58	0.1	15.5	8.1	416	2.20	5.2	4.6	0.8	15	0.4	0.4	0.2	50	0.18	0.061	7
1204016	Soil		2.5	36.8	10.5	54	0.3	18.4	6.6	232	2.60	7.7	3.6	1.3	22	0.2	0.5	0.2	61	0.19	0.067	13
1204017	Soil		1.2	15.2	6.0	34	<0.1	14.7	7.4	272	1.92	4.5	2.8	1.3	16	0.1	0.3	0.2	44	0.24	0.054	8
1204018	Soil		1.0	21.3	7.3	49	<0.1	21.8	10.9	405	2.70	7.8	6.1	2.8	21	0.1	0.4	0.2	64	0.32	0.070	13
1204019	Soil		1.0	16.9	11.3	72	<0.1	20.7	10.9	476	2.58	6.6	10.2	2.1	19	0.2	0.4	0.2	63	0.30	0.072	10
1204020	Soil		1.8	29.5	12.1	68	0.3	25.4	8.7	339	2.70	8.5	3.9	1.1	26	0.4	0.5	0.2	55	0.52	0.091	15
1204021	Soil		1.5	23.1	9.3	69	<0.1	21.4	9.8	503	3.72	9.1	3.7	1.0	19	0.2	0.7	0.2	88	0.21	0.045	8
1204022	Soil		2.1	26.1	9.9	77	<0.1	20.9	10.0	501	3.38	9.9	2.6	0.7	19	0.2	0.8	0.2	73	0.19	0.062	7
1204023	Soil		1.9	24.8	8.1	116	0.4	15.2	8.4	594	1.88	8.0	11.5	0.6	30	1.0	0.4	0.3	38	0.66	0.096	15
1204024	Soil		1.2	16.0	11.9	50	<0.1	14.1	9.8	539	2.78	11.4	1.0	2.9	14	0.1	0.4	0.3	53	0.23	0.038	8
1204025	Soil		0.6	11.3	4.3	44	<0.1	12.7	7.3	256	1.85	3.2	1.5	1.3	17	0.1	0.3	<0.1	45	0.25	0.044	7
1204026	Soil		1.0	17.7	8.1	57	<0.1	19.1	11.0	528	2.54	6.8	5.0	2.4	20	0.1	0.4	0.1	58	0.29	0.063	11
1204027	Soil		0.6	15.1	6.6	66	<0.1	21.9	11.5	332	2.68	6.2	6.0	3.4	25	0.2	0.2	0.1	68	0.43	0.076	11
1204028	Soil		0.9	12.5	5.6	83	<0.1	11.5	5.9	288	1.83	4.3	2.4	1.1	17	0.4	0.3	0.1	51	0.25	0.061	9
1204029	Soil		1.0	23.8	8.3	151	0.1	18.4	10.0	415	2.55	20.3	4.9	1.8	20	0.7	0.5	0.4	62	0.27	0.057	9
1204030	Soil		0.8	14.5	4.6	62	<0.1	9.1	5.9	240	1.57	4.4	1.6	1.1	15	0.2	0.2	0.2	34	0.23	0.040	7
1204031	Soil		1.4	22.4	8.0	64	0.1	20.1	9.8	379	2.38	4.9	5.5	2.0	25	0.4	0.3	0.1	61	0.37	0.057	9
1204032	Soil		0.6	15.9	6.2	63	<0.1	19.4	10.0	384	2.51	5.5	9.3	2.9	24	0.2	0.3	0.1	68	0.39	0.067	9
1204033	Soil		1.2	44.9	8.2	50	0.1	21.9	10.6	354	2.71	7.1	2.7	1.6	22	0.1	0.4	0.2	59	0.32	0.070	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203031	Soil	36	0.63	165	0.093	<1	1.80	0.019	0.06	<0.1	0.03	3.6	<0.1	<0.05	6	<0.5	<0.2
1203032	Soil	43	0.78	234	0.081	<1	1.93	0.021	0.05	<0.1	0.04	5.2	<0.1	<0.05	5	<0.5	<0.2
1203033	Soil	41	0.67	233	0.107	<1	2.04	0.021	0.05	0.1	0.05	5.2	<0.1	<0.05	6	0.5	<0.2
1203034	Soil	68	1.26	212	0.072	<1	2.21	0.018	0.07	<0.1	0.05	7.3	<0.1	<0.05	6	<0.5	<0.2
1203035	Soil	71	1.21	208	0.089	<1	2.20	0.019	0.07	<0.1	0.02	6.8	0.1	<0.05	6	0.6	<0.2
1203036	Soil	95	1.94	176	0.143	<1	2.52	0.014	0.40	<0.1	0.02	8.8	0.4	<0.05	8	0.7	<0.2
1203037	Soil	65	1.42	132	0.149	2	2.12	0.013	0.11	0.2	0.01	4.0	0.1	<0.05	7	<0.5	<0.2
1203038	Soil	67	1.42	153	0.177	2	2.19	0.013	0.31	0.1	0.01	7.3	0.4	<0.05	7	<0.5	<0.2
1203039	Soil	82	1.65	172	0.198	1	2.28	0.014	0.24	<0.1	0.02	7.9	0.4	<0.05	7	0.6	<0.2
1204013	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1204014	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1204015	Soil	24	0.38	95	0.060	2	1.14	0.017	0.05	<0.1	0.06	2.2	<0.1	0.05	5	0.7	<0.2
1204016	Soil	26	0.38	209	0.058	2	1.17	0.018	0.10	<0.1	0.07	2.1	0.1	0.14	5	1.1	<0.2
1204017	Soil	19	0.36	110	0.058	2	1.16	0.020	0.04	0.1	0.04	2.2	<0.1	<0.05	4	0.7	<0.2
1204018	Soil	29	0.55	141	0.088	2	1.71	0.017	0.05	0.2	0.04	3.2	<0.1	<0.05	5	0.6	<0.2
1204019	Soil	28	0.48	112	0.093	2	1.29	0.016	0.05	0.2	0.03	2.4	<0.1	<0.05	5	<0.5	<0.2
1204020	Soil	27	0.46	206	0.053	3	1.55	0.023	0.07	0.1	0.09	3.0	<0.1	0.13	5	1.5	<0.2
1204021	Soil	36	0.49	124	0.090	2	1.77	0.011	0.05	0.1	0.06	2.7	<0.1	<0.05	8	0.6	<0.2
1204022	Soil	31	0.40	110	0.070	2	1.78	0.014	0.05	<0.1	0.08	2.3	<0.1	0.05	7	<0.5	<0.2
1204023	Soil	24	0.39	282	0.048	4	1.06	0.027	0.07	0.1	0.12	1.9	<0.1	0.12	4	1.5	<0.2
1204024	Soil	20	0.41	173	0.035	2	1.24	0.008	0.07	0.2	0.03	4.0	<0.1	<0.05	5	<0.5	<0.2
1204025	Soil	21	0.47	84	0.077	2	0.95	0.018	0.06	0.1	0.04	2.3	<0.1	<0.05	3	<0.5	<0.2
1204026	Soil	29	0.52	141	0.082	2	1.49	0.018	0.06	0.1	0.04	2.9	<0.1	<0.05	5	<0.5	<0.2
1204027	Soil	31	0.65	119	0.119	2	1.39	0.023	0.06	0.2	0.03	3.0	<0.1	<0.05	4	<0.5	<0.2
1204028	Soil	21	0.31	106	0.065	1	0.81	0.018	0.05	0.1	0.07	2.0	<0.1	0.07	4	<0.5	<0.2
1204029	Soil	26	0.44	138	0.084	2	1.35	0.017	0.05	0.1	0.06	2.7	<0.1	<0.05	5	0.5	<0.2
1204030	Soil	14	0.27	107	0.057	1	0.69	0.027	0.04	<0.1	0.02	1.6	<0.1	<0.05	3	<0.5	<0.2
1204031	Soil	31	0.51	149	0.108	2	1.35	0.021	0.09	0.1	0.04	3.1	<0.1	0.05	5	0.7	<0.2
1204032	Soil	29	0.50	90	0.124	2	1.13	0.023	0.07	0.2	0.02	2.8	<0.1	<0.05	4	<0.5	<0.2
1204033	Soil	30	0.55	190	0.068	2	1.92	0.020	0.06	0.1	0.06	3.1	0.1	<0.05	6	0.6	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1204034	Soil	0.9	14.6	7.8	33	0.2	10.7	4.7	184	1.69	5.0	2.3	0.5	18	0.1	0.3	0.1	42	0.23	0.050	10
1204035	Soil	1.3	16.3	10.7	50	<0.1	20.7	10.0	333	3.20	20.0	5.9	2.9	20	0.2	0.4	0.1	86	0.29	0.044	8
1204036	Soil	1.5	16.3	31.0	74	0.1	17.3	10.6	398	3.09	15.2	12.0	3.7	28	0.3	0.4	0.1	59	0.28	0.062	13
1204037	Soil	0.6	19.4	9.5	47	<0.1	19.4	8.0	207	2.44	6.0	2.3	3.0	18	<0.1	0.3	0.1	49	0.30	0.056	10
1204038	Soil	2.0	18.7	12.4	57	<0.1	23.6	10.3	474	4.82	13.3	3.4	2.2	18	0.1	0.7	0.2	105	0.23	0.035	8
1204039	Soil	1.0	11.5	8.1	56	<0.1	13.7	8.5	267	2.18	3.3	2.4	3.8	25	0.1	0.3	0.1	38	0.54	0.059	12
1204040	Soil	1.1	21.0	8.8	135	0.2	15.2	8.3	503	2.41	8.0	3.5	1.4	19	0.5	0.4	0.5	50	0.30	0.048	11
1204041	Soil	0.9	32.9	10.0	69	0.4	27.6	20.4	828	6.56	35.2	4.5	3.3	19	0.3	0.5	0.3	47	0.48	0.060	21
1204042	Soil	0.8	25.4	10.6	65	0.1	26.4	15.9	308	3.66	9.6	3.2	4.4	25	0.2	0.4	0.2	71	0.44	0.068	16
1204043	Soil	1.0	57.6	12.3	98	0.2	38.5	14.5	368	3.94	9.3	4.0	5.2	28	0.5	0.5	0.3	72	0.51	0.072	20
1204044	Soil	0.8	33.8	9.4	78	0.2	33.3	14.4	657	3.21	7.8	3.2	2.9	25	0.2	0.4	0.3	68	0.40	0.072	12
1204045	Soil	1.0	34.5	9.2	76	<0.1	29.2	15.9	602	3.34	6.7	15.0	2.3	21	0.2	0.3	0.2	64	0.37	0.056	10
1204046	Soil	0.8	46.4	8.8	80	0.1	39.0	13.7	562	3.47	8.0	8.4	3.8	23	0.2	0.4	0.2	68	0.38	0.053	15
1204047	Soil	0.7	44.3	10.4	71	0.1	33.4	15.6	630	3.32	6.4	4.1	4.0	23	0.2	0.4	0.3	67	0.36	0.069	17
1204048	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1204049	Soil	0.3	18.5	4.7	31	0.1	11.9	4.4	135	1.04	1.9	1.9	0.6	20	<0.1	0.2	0.1	21	0.37	0.068	8
1204050	Soil	0.1	18.2	3.0	13	0.1	5.5	1.8	40	0.36	<0.5	1.8	0.2	14	<0.1	0.1	<0.1	13	0.25	0.054	6
1204051	Soil	1.0	17.9	5.2	39	<0.1	9.8	4.2	146	1.46	3.3	2.9	0.2	16	0.2	0.4	0.1	37	0.17	0.062	4
1204052	Soil	0.7	25.7	6.7	59	<0.1	25.4	11.7	337	3.14	6.6	5.8	2.3	21	0.1	0.4	0.1	69	0.34	0.078	8
1204053	Soil	0.5	19.9	6.0	67	<0.1	23.4	10.5	273	2.60	5.0	2.6	2.0	23	0.4	0.3	0.1	52	0.36	0.068	7
1204054	Soil	0.4	31.6	8.1	58	<0.1	24.1	10.1	240	2.60	6.4	3.9	3.0	27	0.2	0.5	0.2	69	0.45	0.075	12
1204055	Soil	0.4	35.8	9.0	62	0.1	27.5	11.2	275	2.63	6.1	3.2	4.0	34	0.3	0.5	0.1	63	0.63	0.068	14
1204056	Soil	0.9	14.2	6.0	42	<0.1	15.3	7.3	259	2.22	5.8	3.5	1.6	15	0.3	0.4	0.1	53	0.18	0.034	7
1204057	Soil	1.2	25.1	11.4	80	<0.1	22.3	11.3	583	3.03	7.5	6.6	1.3	24	0.5	0.5	0.1	70	0.33	0.057	10
1204058	Soil	1.9	17.8	8.9	45	<0.1	10.4	4.6	198	2.02	5.1	5.8	0.8	18	0.2	0.6	0.2	68	0.19	0.038	5
1204059	Soil	1.1	28.9	9.9	63	<0.1	20.6	11.2	560	3.04	7.9	2.1	2.2	23	0.2	0.4	0.2	65	0.31	0.062	10
1204060	Soil	0.7	23.2	10.9	89	0.1	21.3	9.1	439	2.63	9.1	8.0	2.6	23	0.6	0.4	0.2	59	0.35	0.070	13
1204061	Soil	0.9	24.3	11.3	69	<0.1	23.9	13.0	503	3.32	9.3	5.4	3.1	20	0.3	0.4	0.2	69	0.26	0.057	12
1204062	Soil	1.3	13.3	8.6	32	<0.1	9.1	4.5	177	1.71	5.7	6.3	0.9	13	0.1	0.2	0.2	49	0.14	0.035	7
1204063	Soil	1.4	18.7	15.0	45	<0.1	15.7	7.0	296	3.03	8.9	2.9	3.4	16	0.1	0.4	0.3	67	0.16	0.039	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1204034	Soil		19	0.29	88	0.052	1	1.13	0.019	0.04	<0.1	0.05	1.6	<0.1	<0.05	4	<0.5	<0.2
1204035	Soil		31	0.54	116	0.133	2	1.71	0.016	0.06	0.1	0.03	3.4	<0.1	<0.05	7	0.6	<0.2
1204036	Soil		26	0.46	123	0.100	2	1.39	0.029	0.07	0.1	0.04	2.8	<0.1	0.08	5	0.7	<0.2
1204037	Soil		30	0.58	100	0.083	2	1.97	0.012	0.06	<0.1	0.05	3.4	<0.1	0.06	5	<0.5	<0.2
1204038	Soil		41	0.62	123	0.145	1	1.82	0.011	0.05	0.1	0.04	3.2	<0.1	<0.05	11	<0.5	<0.2
1204039	Soil		22	0.53	185	0.065	1	1.45	0.020	0.05	0.1	0.02	3.5	<0.1	<0.05	4	<0.5	<0.2
1204040	Soil		22	0.35	114	0.069	2	1.17	0.026	0.04	<0.1	0.04	2.3	<0.1	<0.05	5	<0.5	<0.2
1204041	Soil		21	0.53	149	0.064	2	1.32	0.023	0.04	0.1	0.06	5.8	<0.1	<0.05	4	1.1	<0.2
1204042	Soil		39	0.79	186	0.112	2	2.08	0.020	0.05	0.1	0.04	5.3	<0.1	<0.05	6	0.9	<0.2
1204043	Soil		46	0.90	215	0.122	2	2.12	0.024	0.08	0.1	0.03	7.4	<0.1	<0.05	6	0.7	<0.2
1204044	Soil		48	0.91	177	0.100	2	2.10	0.016	0.06	<0.1	0.04	4.9	<0.1	<0.05	6	0.5	<0.2
1204045	Soil		44	0.87	124	0.086	1	1.92	0.015	0.06	0.1	0.03	4.2	<0.1	<0.05	6	<0.5	<0.2
1204046	Soil		45	0.91	201	0.115	2	2.22	0.019	0.06	<0.1	0.03	5.1	<0.1	<0.05	6	<0.5	<0.2
1204047	Soil		44	0.84	194	0.088	1	2.05	0.015	0.06	0.1	0.03	5.3	<0.1	<0.05	6	<0.5	<0.2
1204048	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1204049	Soil		18	0.35	102	0.039	<1	0.94	0.025	0.03	<0.1	0.04	1.7	<0.1	0.05	3	<0.5	<0.2
1204050	Soil		9	0.16	61	0.028	<1	0.50	0.026	0.02	<0.1	0.05	1.0	<0.1	0.05	2	<0.5	<0.2
1204051	Soil		16	0.23	65	0.032	<1	0.92	0.021	0.03	<0.1	0.05	1.2	<0.1	0.07	4	<0.5	<0.2
1204052	Soil		35	0.69	123	0.108	1	2.42	0.016	0.05	0.1	0.03	3.9	<0.1	<0.05	6	<0.5	<0.2
1204053	Soil		29	0.68	105	0.092	2	2.03	0.017	0.04	0.1	0.04	3.4	<0.1	<0.05	6	<0.5	<0.2
1204054	Soil		37	0.71	159	0.107	1	2.06	0.020	0.05	0.1	0.05	4.9	<0.1	<0.05	6	<0.5	<0.2
1204055	Soil		38	0.68	198	0.114	1	1.79	0.032	0.07	0.1	0.04	5.8	<0.1	<0.05	5	<0.5	<0.2
1204056	Soil		23	0.41	102	0.091	<1	1.31	0.015	0.04	0.1	0.03	2.2	<0.1	<0.05	5	<0.5	<0.2
1204057	Soil		31	0.57	140	0.100	2	1.56	0.015	0.07	0.1	0.04	2.7	<0.1	<0.05	6	<0.5	<0.2
1204058	Soil		19	0.18	114	0.082	<1	0.84	0.013	0.04	0.1	0.05	1.6	<0.1	<0.05	6	<0.5	<0.2
1204059	Soil		27	0.67	181	0.099	1	1.67	0.015	0.14	0.1	0.04	3.0	<0.1	<0.05	6	<0.5	<0.2
1204060	Soil		28	0.53	144	0.093	2	1.59	0.016	0.08	0.2	0.05	2.9	<0.1	<0.05	5	<0.5	<0.2
1204061	Soil		31	0.69	174	0.096	2	2.33	0.013	0.10	0.1	0.06	3.7	0.1	<0.05	7	<0.5	<0.2
1204062	Soil		17	0.22	107	0.052	<1	0.85	0.010	0.06	0.1	0.05	1.9	<0.1	<0.05	5	<0.5	<0.2
1204063	Soil		28	0.39	121	0.078	<1	1.84	0.012	0.07	0.1	0.05	3.3	<0.1	<0.05	8	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1204064	Soil	1.2	26.8	11.2	69	0.1	22.4	13.2	731	3.10	9.0	5.9	2.6	32	0.2	0.4	0.2	65	0.48	0.061	28
1204065	Soil	1.0	22.6	9.5	70	0.1	20.1	11.1	640	2.84	7.8	7.3	1.6	28	0.2	0.3	0.2	60	0.39	0.071	17
1204066	Soil	0.8	16.7	6.8	44	<0.1	14.5	7.1	299	2.14	6.2	2.5	1.6	17	<0.1	0.2	0.1	48	0.19	0.036	10
1204067	Soil	0.8	26.0	14.2	65	0.2	20.1	8.7	393	2.36	6.3	3.8	1.4	30	0.2	0.3	0.2	49	0.44	0.076	27
1204068	Soil	1.2	24.6	14.3	63	0.2	19.4	10.7	679	2.50	7.4	3.7	1.6	30	0.1	0.3	0.2	57	0.49	0.084	16
1204069	Soil	1.2	19.6	15.5	73	0.2	19.2	13.6	1063	2.79	7.3	2.9	1.5	24	0.2	0.3	0.2	54	0.33	0.072	13
1204070	Soil	1.3	25.9	9.8	64	0.2	18.3	8.2	653	2.71	5.8	5.3	0.9	31	0.2	0.3	0.1	53	0.44	0.095	11
1204071	Soil	0.5	18.6	10.8	58	0.1	18.4	6.2	188	1.97	5.2	4.4	1.6	23	0.2	0.2	0.1	51	0.34	0.061	10
1204072	Soil	0.9	18.9	10.2	60	0.1	17.3	9.7	447	2.87	6.3	4.2	1.5	24	0.2	0.3	0.1	53	0.34	0.063	11
1204073	Soil	0.9	20.8	9.7	67	0.1	17.2	8.2	507	2.12	5.9	3.2	1.1	27	0.2	0.3	0.1	49	0.38	0.068	13
1204074	Soil	0.5	4.7	4.8	29	<0.1	5.0	4.1	212	1.31	3.6	2.1	0.8	10	0.1	0.1	<0.1	30	0.10	0.019	4
1204075	Soil	1.5	20.8	9.0	60	0.1	17.8	19.1	1638	2.57	7.2	3.6	1.1	31	0.1	0.3	0.2	64	0.42	0.072	10
1204076	Soil	0.7	17.0	7.2	34	0.1	11.9	3.7	105	1.62	4.4	2.1	0.4	21	0.2	0.2	0.1	38	0.22	0.050	11
1204077	Soil	0.3	6.9	3.9	21	<0.1	5.5	2.8	128	0.99	3.2	1.0	0.3	12	<0.1	0.1	<0.1	26	0.12	0.024	5
1204078	Soil	1.0	18.0	8.1	63	<0.1	19.1	12.3	669	2.54	6.7	5.7	2.5	27	<0.1	0.2	0.2	62	0.38	0.061	12
1204079	Soil	1.1	16.9	10.8	65	<0.1	19.8	11.2	670	2.75	8.0	3.7	2.2	24	0.1	0.3	0.2	65	0.32	0.049	11
1203637	Soil	0.7	43.7	7.3	71	<0.1	50.8	25.1	943	4.63	6.4	1.0	2.2	19	<0.1	0.2	0.8	97	0.37	0.044	7
1202045	Soil	2.6	55.9	57.3	153	0.5	21.0	12.1	548	3.38	7.1	6.7	10.1	24	0.3	0.8	0.5	43	0.21	0.048	19
1202098	Soil	0.7	103.1	13.1	72	<0.1	28.2	19.5	598	3.84	5.9	3.5	3.2	30	<0.1	0.3	0.2	64	0.40	0.092	33
1202217	Soil	1.9	50.3	21.6	102	<0.1	50.0	13.7	404	4.28	41.0	3.2	9.2	10	0.2	0.9	0.5	73	0.09	0.035	23
1202226	Soil	9.0	47.4	192.4	127	0.2	18.7	10.8	601	5.27	15.7	5.6	281.0	20	0.1	0.5	1.9	60	0.12	0.059	27
1202227	Soil	9.6	42.6	165.2	132	0.2	16.4	12.7	769	4.75	16.0	9.7	292.3	24	0.2	0.7	1.6	38	0.15	0.065	56
1202258	Soil	1.8	101.4	65.6	197	0.2	70.1	16.9	849	5.08	6.8	3.1	15.9	11	0.2	0.2	1.7	67	0.15	0.027	20
1202607	Soil	0.8	31.6	7.4	55	<0.1	27.7	13.3	403	3.02	8.5	2.7	4.9	23	<0.1	0.4	0.3	67	0.28	0.034	23
1202611	Soil	0.1	40.4	0.6	41	<0.1	18.1	23.8	670	3.41	1.5	<0.5	0.3	9	<0.1	<0.1	0.1	74	0.25	0.027	1
1202694	Soil	0.5	30.3	6.7	54	<0.1	25.2	10.0	348	2.78	7.5	7.2	3.4	20	<0.1	0.4	0.2	59	0.26	0.025	13
1202695	Soil	0.4	22.7	9.4	49	<0.1	18.3	9.9	264	2.14	4.1	3.1	6.3	25	0.1	0.4	0.2	47	0.42	0.070	26
1202696	Soil	1.3	24.4	19.6	59	0.1	24.0	10.5	325	2.62	7.3	4.6	2.3	17	0.2	0.4	0.3	60	0.23	0.052	9
1202697	Soil	0.6	16.0	6.0	43	<0.1	16.8	10.3	493	2.24	8.7	2.2	3.2	14	<0.1	0.3	0.2	40	0.19	0.029	9
1203732	Soil	0.2	30.6	9.1	74	<0.1	18.8	19.2	1092	2.99	2.1	2.0	5.4	10	<0.1	0.1	0.2	44	0.28	0.038	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1204064	Soil	36	0.63	305	0.081	2	1.89	0.018	0.09	0.1	0.05	4.5	<0.1	<0.05	7	0.7	<0.2
1204065	Soil	35	0.61	218	0.071	1	1.92	0.017	0.08	0.1	0.04	3.9	<0.1	<0.05	6	<0.5	<0.2
1204066	Soil	21	0.38	138	0.079	2	1.40	0.016	0.05	0.1	0.04	2.5	<0.1	<0.05	5	<0.5	<0.2
1204067	Soil	31	0.54	321	0.052	1	1.99	0.020	0.07	0.1	0.05	3.8	0.1	<0.05	6	0.6	<0.2
1204068	Soil	31	0.55	256	0.061	2	1.72	0.018	0.07	0.1	0.07	4.1	<0.1	0.06	5	<0.5	<0.2
1204069	Soil	32	0.57	293	0.064	2	1.83	0.015	0.06	<0.1	0.05	3.6	0.1	<0.05	6	<0.5	<0.2
1204070	Soil	35	0.55	307	0.066	2	1.76	0.017	0.06	0.1	0.07	3.5	<0.1	0.08	6	<0.5	<0.2
1204071	Soil	30	0.56	172	0.089	1	1.76	0.019	0.06	0.1	0.05	3.1	0.1	<0.05	6	<0.5	<0.2
1204072	Soil	31	0.55	178	0.084	2	1.64	0.018	0.06	0.1	0.07	3.7	<0.1	<0.05	6	0.5	<0.2
1204073	Soil	32	0.53	220	0.075	2	1.71	0.016	0.06	0.1	0.05	3.7	<0.1	0.06	6	<0.5	<0.2
1204074	Soil	11	0.20	56	0.065	<1	0.84	0.020	0.03	<0.1	0.04	1.1	<0.1	<0.05	4	<0.5	<0.2
1204075	Soil	32	0.48	229	0.072	1	1.56	0.019	0.06	0.1	0.05	3.2	0.1	<0.05	6	<0.5	<0.2
1204076	Soil	20	0.29	144	0.054	2	1.33	0.018	0.04	<0.1	0.06	1.9	<0.1	0.05	5	<0.5	<0.2
1204077	Soil	12	0.15	71	0.045	<1	0.62	0.017	0.04	<0.1	0.02	1.1	<0.1	<0.05	3	<0.5	<0.2
1204078	Soil	32	0.55	217	0.095	2	1.67	0.017	0.07	0.1	0.02	3.5	<0.1	<0.05	6	<0.5	<0.2
1204079	Soil	33	0.56	205	0.095	2	1.78	0.014	0.07	0.1	0.03	3.3	<0.1	<0.05	6	<0.5	<0.2
1203637	Soil	99	2.72	122	0.130	1	2.95	0.010	0.34	0.1	0.04	5.7	0.3	<0.05	9	<0.5	0.4
1202045	Soil	27	0.69	200	0.074	2	1.79	0.012	0.07	<0.1	0.06	3.0	<0.1	<0.05	5	<0.5	<0.2
1202098	Soil	31	0.86	383	0.070	2	2.44	0.014	0.07	<0.1	0.05	7.6	<0.1	<0.05	7	<0.5	<0.2
1202217	Soil	50	0.51	112	0.043	2	2.26	0.006	0.11	<0.1	0.02	4.3	0.1	<0.05	6	0.9	<0.2
1202226	Soil	25	0.36	242	0.067	2	1.74	0.038	0.25	0.3	0.06	5.9	0.9	0.55	5	0.8	0.6
1202227	Soil	17	0.30	198	0.046	4	1.31	0.030	0.19	0.2	0.04	3.9	0.6	0.35	4	0.6	0.6
1202258	Soil	152	2.51	125	0.143	2	2.55	0.007	0.82	<0.1	0.01	8.7	0.5	<0.05	7	1.1	0.7
1202607	Soil	40	0.70	191	0.097	3	2.36	0.016	0.05	0.1	0.03	5.5	<0.1	<0.05	6	0.6	<0.2
1202611	Soil	91	4.42	24	0.101	1	3.16	0.002	0.03	<0.1	<0.01	3.7	<0.1	<0.05	6	<0.5	<0.2
1202694	Soil	34	0.74	182	0.104	3	2.14	0.013	0.06	<0.1	0.02	4.4	<0.1	<0.05	5	<0.5	<0.2
1202695	Soil	31	0.63	156	0.092	2	1.51	0.018	0.06	<0.1	0.01	4.7	<0.1	<0.05	4	<0.5	<0.2
1202696	Soil	38	0.60	91	0.095	3	2.23	0.013	0.06	0.1	0.04	3.2	<0.1	<0.05	5	<0.5	<0.2
1202697	Soil	23	0.54	135	0.064	2	1.54	0.013	0.05	<0.1	0.02	2.4	<0.1	<0.05	4	<0.5	<0.2
1203732	Soil	54	2.61	62	0.041	<1	2.48	0.004	0.03	<0.1	<0.01	6.1	<0.1	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202602	Soil	0.7	44.1	11.2	66	0.1	81.2	21.3	808	4.11	10.5	2.9	4.8	30	0.1	0.3	0.2	75	0.67	0.072	22
1202609	Soil	1.1	35.6	7.6	63	0.2	26.7	15.1	474	3.57	9.6	3.4	3.0	20	<0.1	0.5	0.2	71	0.36	0.039	12
1203712	Soil	0.8	91.2	17.0	94	0.1	23.1	24.1	638	4.28	4.6	0.9	3.4	31	<0.1	0.3	0.3	68	0.46	0.171	22
1203720	Soil	0.8	31.1	13.6	57	0.1	34.5	15.3	473	2.92	7.3	3.2	2.9	35	<0.1	0.3	0.4	65	0.72	0.050	16
1203727	Soil	0.7	74.9	6.1	58	<0.1	39.0	18.0	528	3.38	5.8	1.7	2.0	18	<0.1	0.3	0.2	73	0.27	0.039	9
1203728	Soil	1.1	23.7	13.5	50	<0.1	24.2	11.4	312	3.48	9.2	2.4	3.1	20	0.1	0.5	0.2	81	0.26	0.040	10
1203729	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203732	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000493.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202602	Soil	61	0.79	225	0.074	2	2.15	0.021	0.05	0.1	0.09	6.5	<0.1	<0.05	6	0.5	<0.2
1202609	Soil	42	0.96	385	0.105	3	2.81	0.014	0.05	0.1	0.04	5.4	<0.1	<0.05	7	0.7	<0.2
1203712	Soil	25	1.36	236	0.050	2	2.35	0.009	0.07	<0.1	0.03	6.1	<0.1	<0.05	7	<0.5	<0.2
1203720	Soil	39	0.68	180	0.085	2	2.15	0.017	0.05	<0.1	0.03	3.7	0.1	<0.05	6	<0.5	<0.2
1203727	Soil	78	1.69	131	0.093	2	2.88	0.010	0.03	0.1	0.02	5.0	<0.1	<0.05	8	<0.5	<0.2
1203728	Soil	38	0.70	142	0.121	2	2.34	0.015	0.05	0.1	0.01	4.1	<0.1	<0.05	8	<0.5	<0.2
1203729	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.
1203732	Soil	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.	L.N.R.

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000493.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1202929	Soil	0.5	53.8	7.2	81	0.2	41.7	16.3	735	3.58	5.7	0.6	1.9	32	0.2	0.2	<0.1	67	1.77	0.078	15
REP 1202929	QC	0.4	55.0	7.4	85	0.2	43.5	16.9	743	3.74	6.2	2.1	2.0	35	0.2	0.2	<0.1	70	1.81	0.081	15
1202946	Soil	1.3	34.3	11.7	70	0.2	30.0	10.6	313	3.61	13.2	2.2	3.8	18	<0.1	0.6	0.2	71	0.18	0.053	16
REP 1202946	QC	1.1	34.8	11.8	69	0.2	29.0	10.6	306	3.53	13.4	2.7	3.8	19	0.1	0.5	0.2	74	0.18	0.047	16
1202964	Soil	1.5	36.2	51.1	80	0.3	20.7	8.3	373	2.61	6.6	2.0	7.4	20	0.2	0.6	0.2	51	0.22	0.042	34
REP 1202964	QC	1.6	38.2	53.1	88	0.2	21.2	8.5	386	2.75	7.1	3.4	7.7	21	0.2	0.7	0.2	55	0.22	0.039	35
1202968	Soil	1.5	65.5	64.0	120	0.2	22.8	11.7	556	3.07	6.7	4.3	2.8	24	0.2	0.6	0.3	57	0.25	0.045	18
REP 1202968	QC	1.6	66.5	65.6	124	0.2	23.0	12.0	561	3.13	7.1	3.5	2.9	24	0.2	0.5	0.3	57	0.25	0.046	17
1202988	Soil	0.5	44.6	7.6	28	<0.1	25.6	9.9	237	1.61	3.1	19.7	2.6	14	<0.1	0.2	0.1	35	0.26	0.043	8
REP 1202988	QC	0.5	43.4	7.5	28	<0.1	25.7	10.5	239	1.62	3.2	2.1	2.6	13	<0.1	0.2	<0.1	35	0.26	0.043	8
1203013	Soil	2.2	49.8	54.2	72	0.3	16.2	7.0	256	2.95	7.2	5.7	6.9	27	<0.1	0.6	0.5	45	0.26	0.051	18
REP 1203013	QC	2.5	48.6	54.3	72	0.3	15.3	6.9	260	2.93	7.1	3.2	7.2	27	<0.1	0.6	0.4	48	0.26	0.051	19
1203032	Soil	1.3	47.0	18.3	70	0.2	26.9	11.3	779	2.66	7.8	1.3	4.1	39	0.3	0.3	0.2	58	0.72	0.033	14
REP 1203032	QC	1.3	46.7	18.0	70	0.1	27.9	11.9	778	2.68	8.2	3.1	4.2	39	0.2	0.3	0.2	58	0.72	0.032	14
1203038	Soil	1.3	35.0	18.5	65	<0.1	45.3	18.3	524	3.69	5.2	13.4	12.1	37	0.1	0.4	0.3	64	0.41	0.045	28
REP 1203038	QC	1.1	35.4	18.5	64	<0.1	45.4	18.1	530	3.60	5.5	13.0	12.0	37	<0.1	0.3	0.3	66	0.43	0.046	27
1204046	Soil	0.8	46.4	8.8	80	0.1	39.0	13.7	562	3.47	8.0	8.4	3.8	23	0.2	0.4	0.2	68	0.38	0.053	15
REP 1204046	QC	0.7	45.3	8.4	76	0.1	38.1	13.5	563	3.44	8.0	4.3	3.6	23	0.2	0.4	0.2	72	0.36	0.053	15
1204056	Soil	0.9	14.2	6.0	42	<0.1	15.3	7.3	259	2.22	5.8	3.5	1.6	15	0.3	0.4	0.1	53	0.18	0.034	7
REP 1204056	QC	0.7	13.6	6.1	43	<0.1	15.7	7.3	251	2.14	5.3	2.2	1.5	15	0.2	0.3	0.1	49	0.18	0.033	6
1204066	Soil	0.8	16.7	6.8	44	<0.1	14.5	7.1	299	2.14	6.2	2.5	1.6	17	<0.1	0.2	0.1	48	0.19	0.036	10
REP 1204066	QC	0.8	17.3	6.9	44	<0.1	13.4	7.0	296	2.09	5.7	3.5	1.6	17	0.2	0.3	0.1	47	0.18	0.038	10
1202697	Soil	0.6	16.0	6.0	43	<0.1	16.8	10.3	493	2.24	8.7	2.2	3.2	14	<0.1	0.3	0.2	40	0.19	0.029	9
REP 1202697	QC	0.6	15.5	6.1	45	<0.1	16.6	10.3	487	2.24	8.6	2.1	3.1	14	<0.1	0.2	0.2	42	0.20	0.027	9
Reference Materials																					
STD DS8	Standard	12.9	107.9	110.7	322	1.9	39.4	7.3	631	2.53	28.9	120.2	5.7	61	2.3	4.8	6.2	41	0.71	0.087	13
STD DS8	Standard	13.1	109.2	110.2	326	1.8	39.3	7.7	656	2.63	29.6	118.1	5.9	62	2.2	5.0	6.2	42	0.73	0.089	13
STD DS8	Standard	11.5	104.2	117.1	291	1.7	35.4	7.0	567	2.31	25.4	108.0	5.7	56	2.3	5.2	6.2	37	0.58	0.069	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000493.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1202929	Soil	50	1.12	214	0.089	5	2.02	0.016	0.20	0.1	0.05	2.8	0.3	<0.05	6	0.6	<0.2
REP 1202929	QC	50	1.16	220	0.096	3	2.13	0.017	0.20	0.1	0.05	2.9	0.2	<0.05	6	0.8	<0.2
1202946	Soil	47	0.59	378	0.084	2	2.52	0.012	0.10	0.1	0.04	3.8	0.1	<0.05	7	0.7	<0.2
REP 1202946	QC	48	0.59	385	0.089	1	2.48	0.013	0.10	<0.1	0.04	3.6	0.1	<0.05	7	0.5	<0.2
1202964	Soil	27	0.47	219	0.065	1	1.65	0.017	0.04	0.1	0.06	2.7	<0.1	<0.05	4	<0.5	<0.2
REP 1202964	QC	28	0.48	228	0.070	1	1.70	0.012	0.04	0.1	0.07	2.9	<0.1	<0.05	5	<0.5	<0.2
1202968	Soil	32	0.62	316	0.049	2	1.81	0.011	0.05	0.1	0.11	4.0	<0.1	<0.05	5	<0.5	<0.2
REP 1202968	QC	32	0.63	313	0.050	<1	1.88	0.011	0.05	<0.1	0.11	3.9	<0.1	<0.05	5	0.6	<0.2
1202988	Soil	40	0.86	91	0.052	<1	1.54	0.009	0.04	<0.1	0.02	1.9	<0.1	<0.05	4	<0.5	<0.2
REP 1202988	QC	39	0.85	92	0.051	<1	1.52	0.007	0.04	0.1	0.02	1.9	<0.1	<0.05	4	<0.5	<0.2
1203013	Soil	27	0.85	296	0.069	1	1.81	0.013	0.08	<0.1	0.05	3.4	<0.1	<0.05	6	0.8	<0.2
REP 1203013	QC	27	0.85	294	0.070	1	1.83	0.013	0.08	<0.1	0.05	3.5	<0.1	<0.05	6	0.8	<0.2
1203032	Soil	43	0.78	234	0.081	<1	1.93	0.021	0.05	<0.1	0.04	5.2	<0.1	<0.05	5	<0.5	<0.2
REP 1203032	QC	43	0.78	233	0.083	2	1.99	0.021	0.05	0.1	0.06	5.1	<0.1	<0.05	5	<0.5	<0.2
1203038	Soil	67	1.42	153	0.177	2	2.19	0.013	0.31	0.1	0.01	7.3	0.4	<0.05	7	<0.5	<0.2
REP 1203038	QC	67	1.42	151	0.177	2	2.22	0.013	0.30	<0.1	<0.01	7.3	0.4	<0.05	7	<0.5	<0.2
1204046	Soil	45	0.91	201	0.115	2	2.22	0.019	0.06	<0.1	0.03	5.1	<0.1	<0.05	6	<0.5	<0.2
REP 1204046	QC	45	0.90	199	0.114	2	2.20	0.017	0.06	<0.1	0.03	4.9	<0.1	<0.05	6	<0.5	<0.2
1204056	Soil	23	0.41	102	0.091	<1	1.31	0.015	0.04	0.1	0.03	2.2	<0.1	<0.05	5	<0.5	<0.2
REP 1204056	QC	24	0.40	99	0.085	1	1.26	0.014	0.04	0.1	0.02	2.0	<0.1	<0.05	5	<0.5	<0.2
1204066	Soil	21	0.38	138	0.079	2	1.40	0.016	0.05	0.1	0.04	2.5	<0.1	<0.05	5	<0.5	<0.2
REP 1204066	QC	22	0.38	140	0.073	1	1.35	0.016	0.05	0.1	0.04	2.4	<0.1	<0.05	5	<0.5	<0.2
1202697	Soil	23	0.54	135	0.064	2	1.54	0.013	0.05	<0.1	0.02	2.4	<0.1	<0.05	4	<0.5	<0.2
REP 1202697	QC	22	0.54	129	0.065	1	1.53	0.010	0.05	<0.1	0.02	2.5	<0.1	<0.05	4	<0.5	<0.2
Reference Materials																	
STD DS8	Standard	116	0.63	295	0.100	3	0.94	0.093	0.43	3.2	0.21	2.1	5.6	0.16	5	5.1	5.7
STD DS8	Standard	121	0.64	300	0.102	5	0.92	0.093	0.44	3.1	0.19	2.1	5.7	0.14	5	5.5	5.6
STD DS8	Standard	109	0.54	258	0.092	2	0.81	0.083	0.38	2.8	0.23	1.8	5.3	0.12	4	5.9	4.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000493.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	12.7	101.6	119.2	286	1.7	34.1	6.8	560	2.27	25.2	120.1	6.2	59	2.4	5.2	6.2	39	0.63	0.073	13
STD DS8	Standard	11.1	109.2	131.9	311	1.9	36.2	7.1	575	2.44	25.9	110.1	6.2	62	2.0	5.7	7.2	40	0.61	0.082	11
STD DS8	Standard	11.9	107.6	127.6	316	1.8	38.1	7.2	579	2.53	26.5	111.0	6.3	66	2.3	5.5	6.7	39	0.62	0.079	12
STD DS8	Standard	12.5	111.5	124.9	323	1.7	38.4	7.7	636	2.56	28.9	108.9	7.0	74	2.4	6.0	7.1	40	0.71	0.079	15
STD DS8	Standard	13.6	111.0	122.3	316	1.8	38.8	7.6	651	2.51	29.7	121.4	7.2	74	2.5	5.6	6.8	38	0.73	0.082	16
STD DS8	Standard	12.9	113.0	125.2	305	1.7	38.2	7.6	608	2.42	26.5	101.1	6.8	66	2.2	6.0	6.8	41	0.65	0.078	14
STD DS8	Standard	14.0	116.0	128.7	315	1.9	39.7	7.8	633	2.51	28.1	111.8	7.3	71	2.4	6.1	6.6	43	0.72	0.082	16
STD DS8	Standard	12.8	111.5	126.4	320	1.8	39.0	7.6	635	2.54	28.0	117.2	7.0	70	2.5	6.2	7.0	40	0.69	0.082	15
STD DS8	Standard	13.2	111.9	123.3	314	1.8	39.3	7.5	639	2.51	29.0	107.6	7.1	73	2.2	6.1	7.2	39	0.73	0.080	16
STD DS8	Standard	13.1	118.2	126.3	321	1.7	39.2	7.8	619	2.53	27.3	116.0	7.0	66	2.2	5.7	6.7	41	0.68	0.080	14
STD DS8	Standard	13.2	113.5	125.1	319	1.7	38.9	8.0	623	2.47	26.4	113.5	7.0	70	2.5	6.1	6.5	40	0.70	0.082	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000493.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
STD DS8	Standard	104	0.60	278	0.099	3	0.87	0.084	0.37	3.0	0.21	1.7	5.3	0.12	5	5.4	5.0
STD DS8	Standard	115	0.57	255	0.098	3	0.87	0.090	0.43	2.8	0.22	2.1	5.5	0.15	4	5.1	4.8
STD DS8	Standard	115	0.57	268	0.101	3	0.87	0.090	0.42	3.1	0.22	2.1	5.5	0.15	4	4.5	5.0
STD DS8	Standard	119	0.64	283	0.127	3	0.96	0.101	0.45	2.7	0.21	2.7	5.4	0.14	5	5.1	4.8
STD DS8	Standard	120	0.63	291	0.131	3	1.00	0.104	0.43	3.0	0.20	2.8	5.4	0.14	5	5.0	4.6
STD DS8	Standard	116	0.61	273	0.118	4	0.90	0.099	0.40	2.9	0.19	2.1	5.1	0.12	4	5.0	5.2
STD DS8	Standard	121	0.62	285	0.133	3	0.96	0.101	0.42	3.1	0.20	2.4	5.6	0.14	5	4.7	5.1
STD DS8	Standard	119	0.63	277	0.124	3	0.95	0.095	0.43	2.9	0.21	2.5	5.4	0.14	5	5.0	5.3
STD DS8	Standard	119	0.61	283	0.126	3	0.98	0.094	0.42	3.1	0.18	2.4	5.4	0.15	5	5.3	5.2
STD DS8	Standard	123	0.61	266	0.130	4	0.90	0.090	0.42	3.2	0.18	2.0	5.6	0.12	5	5.3	4.8
STD DS8	Standard	121	0.61	279	0.130	2	0.95	0.096	0.42	3.1	0.20	2.2	5.5	0.14	5	5.9	5.2
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Submitted By: Daithi Mac Gerailt
Receiving Lab: Canada-Whitehorse
Received: July 07, 2011
Report Date: August 11, 2011
Page: 1 of 6

CERTIFICATE OF ANALYSIS WHI11000495.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID:
P.O. Number
Number of Samples: 146

SAMPLE DISPOSAL

STOR-PLP Store After 90 days Invoice for Storage
DISP-RJT-SOIL Immediate Disposal of Soil Reject

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	146	Dry at 60C			WHI
SS80	146	Dry at 60C sieve 100g to -80 mesh			WHI
1DX2	145	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Don Christie
Bruce Durham
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
RAYMOND CHAN
CHIEF ASSAYER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000495.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203040	Soil		0.9	22.3	8.3	55	0.1	21.8	9.6	340	2.64	5.1	1.8	2.7	24	0.1	0.3	0.2	68	0.27	0.048	10
1203041	Soil		1.0	24.5	10.6	57	0.1	23.1	10.3	287	2.39	4.8	8.9	3.1	31	0.1	0.4	0.1	59	0.47	0.079	14
1203042	Soil		0.6	25.8	8.5	57	0.1	23.9	10.2	275	2.68	5.6	3.5	3.9	28	<0.1	0.3	0.2	63	0.38	0.066	17
1203043	Soil		0.5	30.3	18.8	70	0.2	23.4	12.5	251	3.09	6.5	3.0	3.6	30	<0.1	1.1	0.2	68	0.37	0.053	13
1203044	Soil		1.0	50.0	24.3	48	0.6	10.3	5.0	204	2.03	5.5	2.0	0.3	22	<0.1	2.7	0.6	42	0.21	0.055	5
1203045	Soil		1.0	69.6	6.8	96	0.2	18.1	12.9	427	2.86	7.3	2.8	0.7	30	0.4	0.5	0.1	52	0.49	0.053	8
1203046	Soil		2.4	68.9	32.4	73	0.4	16.3	8.3	225	4.82	13.8	8.9	4.2	13	0.1	5.4	0.8	57	0.36	0.037	12
1203047	Soil		10.2	155.3	164.1	109	3.5	20.5	8.7	160	2.80	68.8	47.7	7.3	29	0.2	43.1	2.7	39	0.22	0.045	31
1203048	Soil		0.8	59.9	16.7	94	<0.1	25.2	14.4	650	3.41	6.8	5.1	7.2	24	0.2	0.5	0.3	66	0.32	0.039	12
1203049	Soil		1.2	78.5	22.2	93	0.1	26.7	12.0	456	3.19	13.6	3.9	8.5	29	0.2	0.6	0.3	59	0.35	0.042	18
1203050	Soil		1.0	17.8	6.9	28	0.2	11.0	2.5	107	0.95	2.8	<0.5	0.4	11	0.2	0.2	0.2	30	0.11	0.031	5
1203051	Soil		1.9	79.6	14.3	65	0.3	75.8	19.3	310	3.46	15.2	3.6	4.4	31	<0.1	0.5	0.1	77	0.39	0.073	13
1203052	Soil		1.6	31.0	32.1	59	0.2	29.3	12.6	416	3.11	11.6	2.5	10.9	27	0.2	0.4	0.3	64	0.41	0.049	33
1203053	Soil		1.2	26.7	17.6	60	0.2	25.9	10.4	403	3.08	11.2	8.3	5.0	27	0.1	0.4	0.3	67	0.41	0.045	20
1203054	Soil		1.3	42.2	11.7	87	<0.1	32.4	22.9	1083	4.17	4.9	8.2	3.9	17	0.1	0.3	0.2	83	0.29	0.063	8
1203055	Soil		0.2	4.9	1.7	12	<0.1	3.0	1.5	48	0.61	<0.5	<0.5	0.3	7	<0.1	<0.1	<0.1	13	0.09	0.008	2
1203056	Soil		0.9	40.1	15.8	60	<0.1	30.1	12.2	459	3.29	6.2	3.9	3.4	21	0.1	0.3	0.1	82	0.38	0.037	12
1203057	Soil		0.8	38.7	10.2	60	0.1	26.8	10.2	352	2.75	3.8	2.2	1.3	28	0.3	0.2	0.2	64	0.55	0.047	11
1203058	Soil		0.9	44.7	10.6	59	0.1	31.1	11.5	432	2.93	5.2	2.0	3.4	22	0.1	0.3	0.2	71	0.40	0.042	17
1203059	Soil		0.6	75.8	8.4	72	<0.1	56.0	17.9	598	3.32	4.0	6.6	3.0	21	<0.1	0.3	<0.1	78	0.41	0.050	10
1203060	Soil		0.6	67.0	10.5	83	<0.1	74.3	20.3	777	3.48	2.9	3.8	2.9	22	0.2	0.2	<0.1	82	0.70	0.058	14
1203061	Soil		0.4	74.4	13.7	75	<0.1	64.2	21.8	1078	3.54	4.1	1.9	2.0	21	0.2	0.2	<0.1	86	0.73	0.047	10
1203062	Soil		0.6	71.3	14.2	88	0.1	63.6	19.6	716	3.46	3.2	1.4	2.6	23	0.2	0.2	0.1	81	0.83	0.057	12
1203063	Soil		0.6	52.6	17.5	78	<0.1	38.4	15.4	605	3.47	4.2	2.9	2.6	20	0.2	0.2	0.1	84	0.53	0.045	10
1203064	Soil		0.5	57.0	11.0	81	0.1	39.9	16.6	699	3.28	2.7	2.2	1.8	23	0.2	0.2	0.1	76	0.84	0.053	10
1203065	Soil		0.3	61.2	12.2	84	0.1	42.7	16.8	860	2.79	2.6	3.2	2.2	30	0.4	0.2	<0.1	64	1.17	0.058	12
1203066	Soil		0.5	53.2	22.2	82	0.1	40.3	16.2	606	2.91	3.1	3.6	2.4	25	0.2	0.2	0.1	67	0.79	0.056	13
1203067	Soil		0.3	43.0	15.7	75	<0.1	28.0	12.3	318	2.42	2.5	1.4	2.3	27	0.3	0.2	0.1	56	0.91	0.048	14
1203068	Soil		0.5	51.6	23.1	80	0.1	40.1	16.2	581	2.94	3.0	2.8	2.5	25	0.3	0.3	0.1	70	0.80	0.054	13
1203069	Soil		0.4	52.3	7.0	58	<0.1	45.1	15.5	679	2.51	1.7	0.5	1.1	36	0.3	0.2	<0.1	58	1.57	0.051	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000495.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203040	Soil		37	0.73	149	0.114	2	1.95	0.017	0.09	0.1	0.03	2.8	0.1	<0.05	6	<0.5	<0.2
1203041	Soil		40	0.63	156	0.126	2	1.65	0.033	0.11	0.2	0.02	3.0	0.1	<0.05	5	<0.5	<0.2
1203042	Soil		41	0.69	158	0.127	2	2.06	0.017	0.10	0.2	0.03	3.7	0.1	<0.05	6	<0.5	<0.2
1203043	Soil		43	0.74	186	0.143	2	2.21	0.020	0.08	0.1	0.06	4.7	0.1	<0.05	6	<0.5	<0.2
1203044	Soil		18	0.39	105	0.041	1	1.29	0.018	0.04	<0.1	0.09	1.7	<0.1	<0.05	4	0.7	0.2
1203045	Soil		25	0.54	115	0.057	2	2.00	0.020	0.05	<0.1	0.03	2.9	<0.1	<0.05	5	<0.5	<0.2
1203046	Soil		22	0.61	139	0.026	1	1.52	0.010	0.08	<0.1	0.95	9.0	<0.1	<0.05	5	<0.5	0.2
1203047	Soil		26	0.49	1273	0.055	<1	1.65	0.008	0.05	0.1	1.33	3.1	<0.1	<0.05	5	2.6	1.1
1203048	Soil		38	0.88	190	0.095	2	2.31	0.011	0.06	<0.1	0.06	4.1	<0.1	<0.05	7	<0.5	<0.2
1203049	Soil		33	0.77	164	0.106	2	1.88	0.022	0.07	<0.1	0.04	4.0	<0.1	<0.05	5	<0.5	<0.2
1203050	Soil		26	0.31	88	0.042	<1	0.64	0.018	0.08	<0.1	0.02	1.3	<0.1	<0.05	4	0.5	<0.2
1203051	Soil		153	1.48	166	0.085	1	2.36	0.010	0.05	0.1	0.03	5.0	<0.1	<0.05	6	0.6	<0.2
1203052	Soil		36	0.72	218	0.096	2	2.40	0.016	0.05	0.1	0.03	4.2	<0.1	<0.05	6	0.5	<0.2
1203053	Soil		34	0.64	150	0.111	2	2.05	0.016	0.05	0.1	0.03	3.8	<0.1	<0.05	7	<0.5	<0.2
1203054	Soil		52	1.98	161	0.095	1	3.15	0.010	0.10	<0.1	0.01	5.5	<0.1	<0.05	8	<0.5	<0.2
1203055	Soil		5	0.11	29	0.044	<1	0.32	0.019	0.03	<0.1	<0.01	0.6	<0.1	<0.05	2	<0.5	<0.2
1203056	Soil		45	1.01	176	0.105	2	2.51	0.016	0.05	0.1	0.03	4.7	<0.1	<0.05	7	0.5	<0.2
1203057	Soil		41	0.93	196	0.059	2	2.49	0.018	0.06	0.1	0.05	4.7	<0.1	<0.05	7	<0.5	<0.2
1203058	Soil		53	0.90	287	0.076	2	2.74	0.017	0.04	0.2	0.05	5.4	<0.1	<0.05	7	<0.5	<0.2
1203059	Soil		112	1.91	162	0.088	1	2.80	0.013	0.06	0.1	0.03	4.9	<0.1	<0.05	7	<0.5	<0.2
1203060	Soil		192	2.42	193	0.065	3	2.93	0.014	0.05	<0.1	0.04	5.9	<0.1	<0.05	7	<0.5	<0.2
1203061	Soil		170	2.25	185	0.066	1	2.78	0.014	0.04	<0.1	0.04	6.4	<0.1	<0.05	7	<0.5	<0.2
1203062	Soil		151	2.26	179	0.055	2	2.89	0.015	0.04	<0.1	0.07	7.1	<0.1	<0.05	7	0.6	<0.2
1203063	Soil		79	1.54	187	0.067	1	2.69	0.016	0.04	<0.1	0.05	6.6	<0.1	<0.05	7	<0.5	<0.2
1203064	Soil		91	1.87	135	0.053	1	2.53	0.014	0.03	<0.1	0.05	7.6	<0.1	<0.05	6	<0.5	<0.2
1203065	Soil		95	1.68	138	0.050	2	2.22	0.016	0.03	<0.1	0.05	6.4	<0.1	0.06	6	0.6	<0.2
1203066	Soil		82	1.57	172	0.060	1	2.46	0.020	0.04	0.1	0.06	6.4	<0.1	<0.05	7	<0.5	<0.2
1203067	Soil		56	1.19	154	0.058	1	2.24	0.025	0.05	<0.1	0.07	5.3	<0.1	<0.05	6	<0.5	<0.2
1203068	Soil		86	1.56	172	0.060	2	2.61	0.022	0.04	<0.1	0.07	6.7	<0.1	<0.05	6	<0.5	<0.2
1203069	Soil		115	1.62	150	0.049	3	1.95	0.022	0.04	<0.1	0.06	4.6	<0.1	0.05	5	1.1	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000495.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203070	Soil	0.5	81.0	9.2	67	<0.1	60.4	22.3	737	3.80	2.3	1.1	1.3	17	0.1	0.1	0.1	91	0.52	0.038	6
1203071	Soil	0.7	61.7	11.1	71	0.2	34.9	14.6	621	3.03	4.6	10.8	2.0	22	0.2	0.3	0.2	71	0.41	0.054	12
1203072	Soil	0.3	105.2	11.7	99	0.2	46.5	15.0	544	3.02	3.4	1.2	2.1	24	0.3	0.2	0.1	70	0.50	0.069	9
1203073	Soil	0.3	104.3	9.6	85	0.1	48.0	16.6	757	2.79	2.9	3.4	1.5	24	0.4	0.2	0.1	63	0.51	0.071	9
1203074	Soil	0.4	81.3	9.1	75	0.1	39.4	14.5	724	2.74	3.0	3.4	1.4	24	0.2	0.2	0.1	64	0.54	0.061	6
1203075	Soil	0.5	57.9	10.5	76	0.1	32.0	13.3	594	2.62	3.8	1.9	1.3	23	0.2	0.2	0.2	61	0.49	0.053	6
1203076	Soil	0.5	59.6	11.4	72	0.2	30.0	11.7	434	2.61	3.2	2.5	1.2	25	0.3	0.2	0.2	61	0.53	0.058	8
1203077	Soil	1.0	84.3	17.0	146	0.2	36.4	12.7	601	3.05	3.8	4.9	1.9	25	0.6	0.2	0.2	68	0.56	0.084	10
1203078	Soil	0.5	60.6	12.0	80	<0.1	28.8	12.6	478	2.87	3.4	6.8	1.7	22	0.2	0.2	0.1	71	0.45	0.064	7
1203079	Soil	0.6	59.5	11.4	77	0.1	31.6	13.2	667	2.85	2.7	1.9	1.3	27	0.2	0.2	0.2	64	0.70	0.059	8
1203080	Soil	0.5	55.9	11.5	83	0.1	32.9	12.8	573	2.76	3.1	4.3	0.8	26	0.2	0.2	0.1	63	0.60	0.063	7
1203081	Soil	0.6	65.5	11.4	87	0.2	33.2	13.7	616	3.11	3.6	9.4	1.4	26	0.2	0.2	0.1	70	0.62	0.071	8
1203082	Soil	0.7	57.4	14.4	93	0.2	34.5	13.8	634	3.25	3.3	4.0	1.6	27	0.3	0.2	0.2	66	0.59	0.072	11
1203083	Soil	1.9	145.5	37.1	91	0.4	42.9	21.7	1065	4.27	5.0	15.1	1.5	24	0.3	0.3	0.5	90	0.81	0.059	12
1203084	Soil	0.6	111.5	29.3	85	0.3	40.4	21.3	903	3.96	4.1	4.9	1.8	22	0.3	0.3	0.3	80	0.92	0.050	9
1203085	Soil	0.7	30.1	7.1	57	0.1	17.8	8.2	305	2.19	1.8	2.7	1.8	17	0.1	0.2	0.2	47	0.28	0.040	8
1203086	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203087	Soil	0.6	28.3	8.0	57	<0.1	22.2	10.7	460	2.42	4.0	3.7	2.2	55	0.2	0.3	0.1	63	1.17	0.067	10
1203088	Soil	0.5	15.6	7.3	43	<0.1	17.2	7.9	204	2.15	3.3	<0.5	1.6	27	<0.1	0.2	<0.1	59	0.51	0.049	8
1203089	Soil	0.8	33.8	7.4	61	<0.1	28.9	12.9	753	2.52	4.8	4.2	1.6	47	0.2	0.3	<0.1	67	1.23	0.065	10
1203090	Soil	0.7	21.6	12.3	61	<0.1	22.7	17.1	921	2.83	3.0	1.4	3.3	22	0.1	0.2	0.1	68	0.39	0.068	11
1203091	Soil	0.8	14.4	6.4	35	<0.1	13.9	5.5	150	1.89	2.0	4.2	1.8	18	0.1	0.3	0.2	45	0.31	0.033	8
1203092	Soil	1.0	23.5	9.4	48	<0.1	22.7	9.0	267	2.34	3.8	6.1	5.4	28	0.2	0.4	0.2	53	0.53	0.057	19
1203093	Soil	0.7	15.3	7.6	48	<0.1	18.8	9.5	292	2.62	4.4	8.7	3.3	27	<0.1	0.3	0.1	60	0.53	0.049	10
1203094	Soil	1.0	17.6	6.9	47	<0.1	18.3	8.2	301	2.24	2.8	7.9	3.6	23	<0.1	0.3	0.2	55	0.42	0.044	12
1203095	Soil	0.6	26.9	9.1	58	0.1	21.1	9.7	289	2.09	0.5	6.1	1.3	19	<0.1	0.3	0.1	50	0.28	0.047	8
1203096	Soil	1.5	27.9	7.9	60	0.1	22.2	15.9	1035	2.46	5.1	9.4	2.1	42	0.2	0.4	0.2	59	0.86	0.078	16
1203097	Soil	1.2	21.2	11.9	49	<0.1	19.0	8.7	299	2.45	4.3	4.9	3.6	26	<0.1	0.3	0.2	61	0.51	0.051	16
1203098	Soil	1.0	21.3	7.8	58	<0.1	20.1	10.7	460	2.61	3.4	3.4	2.1	27	<0.1	0.2	0.1	61	0.51	0.050	8
1203099	Soil	1.0	33.1	8.4	64	0.1	24.2	11.9	517	2.86	3.4	3.0	2.0	27	0.1	0.2	0.1	61	0.52	0.063	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000495.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203070	Soil		161	2.62	115	0.056	1	2.78	0.015	0.04	<0.1	0.05	6.4	<0.1	<0.05	7	<0.5	<0.2
1203071	Soil		51	1.20	185	0.067	2	2.63	0.020	0.05	<0.1	0.07	6.1	<0.1	<0.05	7	<0.5	<0.2
1203072	Soil		76	1.80	128	0.074	2	2.67	0.020	0.05	<0.1	0.06	6.2	<0.1	<0.05	6	<0.5	<0.2
1203073	Soil		74	1.70	142	0.065	2	2.42	0.019	0.04	<0.1	0.06	4.8	<0.1	<0.05	6	<0.5	<0.2
1203074	Soil		61	1.51	123	0.058	1	2.23	0.015	0.04	0.1	0.05	4.2	<0.1	<0.05	6	<0.5	<0.2
1203075	Soil		50	1.16	134	0.064	1	2.12	0.021	0.04	0.1	0.04	3.7	<0.1	<0.05	6	<0.5	<0.2
1203076	Soil		50	1.18	164	0.054	2	2.23	0.021	0.04	<0.1	0.07	4.2	<0.1	<0.05	6	<0.5	<0.2
1203077	Soil		57	1.41	123	0.071	2	2.33	0.022	0.04	0.1	0.16	5.2	<0.1	<0.05	6	0.6	<0.2
1203078	Soil		50	1.31	103	0.076	2	2.18	0.021	0.04	0.1	0.05	4.2	<0.1	<0.05	6	<0.5	<0.2
1203079	Soil		54	1.36	145	0.039	<1	2.14	0.019	0.05	<0.1	0.06	4.4	<0.1	<0.05	6	<0.5	<0.2
1203080	Soil		54	1.39	140	0.052	1	2.17	0.020	0.06	<0.1	0.05	3.9	<0.1	<0.05	6	<0.5	<0.2
1203081	Soil		54	1.55	146	0.054	2	2.36	0.021	0.05	<0.1	0.06	4.7	<0.1	<0.05	6	<0.5	<0.2
1203082	Soil		55	1.55	127	0.055	2	2.28	0.020	0.06	<0.1	0.07	4.5	<0.1	<0.05	6	<0.5	<0.2
1203083	Soil		75	1.93	107	0.039	2	2.80	0.017	0.05	<0.1	0.13	8.4	<0.1	0.05	7	<0.5	<0.2
1203084	Soil		78	1.91	90	0.040	2	2.54	0.019	0.04	<0.1	0.06	9.2	<0.1	<0.05	6	<0.5	<0.2
1203085	Soil		33	0.89	126	0.046	<1	1.72	0.015	0.05	<0.1	0.06	3.3	<0.1	<0.05	5	<0.5	<0.2
1203086	Soil		I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203087	Soil		32	0.75	195	0.087	2	1.49	0.037	0.07	<0.1	0.04	3.7	<0.1	<0.05	5	<0.5	<0.2
1203088	Soil		27	0.55	107	0.096	2	1.35	0.032	0.05	0.1	0.04	3.0	<0.1	<0.05	5	<0.5	<0.2
1203089	Soil		41	0.81	284	0.076	3	1.50	0.033	0.06	0.1	0.06	4.5	<0.1	<0.05	5	<0.5	<0.2
1203090	Soil		37	1.04	110	0.077	1	1.70	0.018	0.06	<0.1	0.03	3.5	<0.1	<0.05	6	<0.5	<0.2
1203091	Soil		22	0.32	100	0.075	1	1.37	0.016	0.06	0.1	0.02	2.2	<0.1	0.06	5	0.8	<0.2
1203092	Soil		35	0.43	192	0.091	<1	1.68	0.019	0.07	0.1	0.02	4.6	<0.1	<0.05	5	<0.5	<0.2
1203093	Soil		32	0.48	180	0.086	2	1.84	0.017	0.05	0.2	0.02	3.1	<0.1	<0.05	5	<0.5	<0.2
1203094	Soil		29	0.41	167	0.064	<1	1.67	0.016	0.04	<0.1	0.02	3.4	<0.1	<0.05	5	<0.5	<0.2
1203095	Soil		39	0.84	131	0.051	<1	1.72	0.015	0.05	0.1	0.02	3.0	<0.1	<0.05	5	<0.5	<0.2
1203096	Soil		37	0.49	229	0.080	2	1.98	0.023	0.06	0.2	0.03	4.5	<0.1	<0.05	5	1.0	<0.2
1203097	Soil		34	0.43	179	0.075	1	1.86	0.017	0.04	0.1	0.03	3.8	<0.1	<0.05	5	<0.5	<0.2
1203098	Soil		37	0.79	152	0.067	<1	1.82	0.017	0.05	0.1	0.02	3.3	<0.1	<0.05	6	<0.5	<0.2
1203099	Soil		42	1.23	155	0.071	1	2.08	0.016	0.05	0.1	0.03	4.2	<0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000495.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203100	Soil		0.7	36.2	7.1	65	0.2	22.1	11.0	489	2.66	1.9	6.5	1.9	24	0.2	0.2	0.1	60	0.47	0.047	9
1203101	Soil		0.7	41.4	7.9	70	0.1	22.9	12.0	494	2.95	2.8	5.0	1.8	22	0.1	0.2	0.2	63	0.42	0.053	10
1203102	Soil		0.8	37.0	6.3	75	0.1	23.7	12.1	497	3.01	2.0	3.4	1.9	22	0.1	0.2	0.1	63	0.40	0.053	9
1203103	Soil		0.7	39.9	9.3	91	0.2	22.3	12.2	568	3.08	2.4	3.4	2.4	21	0.2	0.2	0.2	66	0.38	0.047	10
1203104	Soil		0.6	35.2	8.2	78	0.1	23.0	11.9	466	3.00	2.2	4.0	2.7	20	0.2	0.2	0.2	60	0.35	0.050	12
1203105	Soil		0.6	29.9	8.5	73	<0.1	20.7	10.4	394	2.76	1.8	2.3	2.1	18	<0.1	0.2	0.1	57	0.31	0.040	9
1203106	Soil		0.6	30.2	8.8	69	<0.1	23.4	11.7	470	2.95	2.3	4.9	3.0	19	0.1	0.2	0.1	64	0.34	0.041	10
1203107	Soil		0.4	30.8	9.1	75	<0.1	27.3	14.1	478	3.15	2.5	3.1	3.5	20	<0.1	0.2	<0.1	65	0.33	0.046	10
1203108	Soil		0.8	41.9	13.5	60	<0.1	32.4	12.4	549	2.16	2.6	4.6	3.1	52	0.1	0.3	<0.1	46	1.24	0.061	17
1203109	Soil		0.7	35.3	7.7	66	<0.1	20.1	10.0	400	2.73	2.0	2.4	2.4	18	0.1	0.2	0.1	57	0.29	0.039	8
1203110	Soil		0.8	57.2	14.7	59	0.1	43.0	12.8	387	2.28	4.4	3.5	2.0	63	0.3	0.3	<0.1	45	1.74	0.056	13
1202261	Soil		0.8	56.0	7.7	113	<0.1	62.8	27.9	971	4.54	2.1	2.0	4.5	14	0.2	0.2	0.2	113	0.20	0.033	13
1202262	Soil		0.9	66.8	6.7	128	<0.1	30.1	21.4	742	4.75	4.0	2.2	1.7	14	0.2	0.3	0.1	112	0.18	0.045	7
1202263	Soil		1.7	51.7	92.4	186	0.1	38.8	9.6	416	3.30	3.3	1.5	9.1	16	0.2	0.3	0.6	51	0.18	0.040	20
1202264	Soil		1.0	102.3	77.5	275	0.2	108.5	25.6	1216	4.74	1.0	2.1	11.1	11	0.3	0.1	1.0	57	0.17	0.072	24
1202266	Soil		2.5	76.6	19.7	182	0.2	60.4	14.4	835	4.35	1.7	0.7	11.0	20	0.3	0.2	0.5	72	0.23	0.064	27
1202267	Soil		2.3	53.1	35.0	113	0.1	22.6	6.7	295	2.66	3.4	1.0	11.6	17	0.1	0.3	0.6	49	0.21	0.041	21
1202268	Soil		2.3	72.9	20.2	117	<0.1	17.3	8.2	443	3.20	0.9	2.1	14.8	12	0.1	0.2	0.3	40	0.14	0.048	22
1202271	Soil		3.3	26.4	70.5	65	0.1	8.6	3.2	181	2.50	<0.5	1.6	18.2	23	0.1	0.1	0.4	12	0.07	0.049	33
1202244	Soil		0.7	25.0	11.3	69	<0.1	18.6	7.1	237	2.52	2.3	3.1	4.2	16	0.2	0.3	<0.1	60	0.33	0.067	13
1202247	Soil		0.3	27.7	11.3	64	<0.1	23.2	11.3	198	2.18	1.7	5.6	4.4	29	0.3	0.4	<0.1	65	0.49	0.069	17
1202248	Soil		0.5	27.9	46.1	72	0.1	31.9	10.2	248	2.96	2.9	3.0	4.8	30	0.1	0.3	0.2	69	0.59	0.084	16
1202249	Soil		2.1	62.1	33.9	110	0.2	87.7	24.7	411	4.82	6.4	1.0	12.7	9	0.3	0.3	0.2	52	0.12	0.065	27
1202195	Soil		2.8	45.9	40.4	93	0.2	20.4	12.9	514	3.32	4.2	3.3	11.4	22	0.1	0.7	0.4	50	0.19	0.044	20
1204080	Soil		0.8	53.9	32.7	75	0.2	85.9	23.8	868	3.58	2.5	9.8	16.5	21	<0.1	0.3	0.3	48	0.46	0.088	28
1204081	Soil		0.7	24.5	19.1	54	<0.1	35.4	10.4	276	2.43	2.8	<0.5	10.2	25	<0.1	0.3	0.2	48	0.36	0.032	27
1204082	Soil		0.9	21.3	16.9	47	<0.1	21.9	8.9	269	2.64	5.3	4.0	9.3	18	<0.1	0.4	0.3	56	0.19	0.021	22
1204083	Soil		0.7	9.7	10.0	27	0.1	9.4	4.1	167	1.47	1.8	2.5	3.8	13	<0.1	0.2	0.2	34	0.13	0.023	8
1204084	Soil		1.0	12.1	11.8	33	<0.1	13.4	5.3	182	2.49	5.2	3.0	4.3	13	<0.1	0.4	0.2	53	0.12	0.024	16
1204085	Soil		0.8	32.7	18.6	67	<0.1	63.0	14.4	434	3.09	2.4	2.5	9.7	23	<0.1	0.3	0.3	53	0.26	0.058	40

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000495.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203100	Soil		39	1.21	135	0.054	<1	1.97	0.015	0.05	0.1	<0.01	3.9	<0.1	<0.05	6	<0.5	<0.2
1203101	Soil		44	1.45	134	0.054	<1	2.29	0.014	0.05	<0.1	0.02	4.5	<0.1	<0.05	7	<0.5	<0.2
1203102	Soil		47	1.63	133	0.049	<1	2.32	0.013	0.05	0.1	0.02	4.5	<0.1	<0.05	7	0.7	<0.2
1203103	Soil		46	1.66	155	0.054	<1	2.38	0.013	0.06	0.1	0.02	5.2	<0.1	<0.05	7	<0.5	<0.2
1203104	Soil		43	1.41	152	0.064	<1	2.27	0.013	0.06	<0.1	0.02	4.7	<0.1	<0.05	6	<0.5	<0.2
1203105	Soil		40	1.25	141	0.069	1	2.15	0.013	0.06	<0.1	0.02	4.1	<0.1	<0.05	7	<0.5	<0.2
1203106	Soil		45	1.26	149	0.079	<1	2.28	0.012	0.05	0.1	0.01	4.6	<0.1	<0.05	7	<0.5	<0.2
1203107	Soil		60	1.49	139	0.086	<1	2.23	0.013	0.04	0.1	<0.01	4.8	<0.1	<0.05	6	<0.5	<0.2
1203108	Soil		51	0.96	256	0.059	2	1.66	0.023	0.11	0.1	0.02	3.9	<0.1	<0.05	5	1.1	<0.2
1203109	Soil		39	1.07	125	0.067	<1	1.83	0.012	0.06	0.1	0.01	3.7	<0.1	<0.05	6	0.6	<0.2
1203110	Soil		64	1.04	294	0.049	<1	1.67	0.019	0.08	0.1	0.03	4.4	<0.1	<0.05	4	<0.5	<0.2
1202261	Soil		125	2.71	85	0.076	<1	2.93	0.007	0.09	<0.1	<0.01	8.9	<0.1	<0.05	9	<0.5	<0.2
1202262	Soil		59	2.11	105	0.112	1	2.64	0.008	0.24	<0.1	0.02	4.9	0.1	<0.05	9	0.8	<0.2
1202263	Soil		67	1.73	86	0.100	1	2.20	0.009	0.24	<0.1	0.02	3.7	0.2	<0.05	7	0.8	<0.2
1202264	Soil		226	4.72	113	0.052	<1	3.45	0.003	0.21	<0.1	0.02	6.2	0.1	<0.05	10	0.5	<0.2
1202266	Soil		102	3.08	187	0.080	1	3.09	0.008	0.23	<0.1	<0.01	8.4	0.1	<0.05	9	0.6	<0.2
1202267	Soil		41	1.32	136	0.099	1	2.08	0.012	0.10	0.1	0.04	2.9	<0.1	<0.05	7	<0.5	<0.2
1202268	Soil		32	1.44	113	0.083	1	1.85	0.007	0.14	<0.1	<0.01	2.5	<0.1	<0.05	6	<0.5	<0.2
1202271	Soil		13	0.58	79	0.027	<1	0.89	0.027	0.20	0.1	<0.01	1.2	<0.1	0.31	3	<0.5	<0.2
1202244	Soil		33	0.46	96	0.099	<1	1.54	0.011	0.07	0.1	0.02	3.8	<0.1	<0.05	4	<0.5	<0.2
1202247	Soil		34	0.53	223	0.120	<1	1.66	0.026	0.07	0.2	<0.01	5.1	<0.1	<0.05	5	0.5	<0.2
1202248	Soil		55	0.62	271	0.110	<1	1.61	0.028	0.07	0.1	0.01	4.9	<0.1	<0.05	4	<0.5	<0.2
1202249	Soil		49	0.86	80	0.037	<1	2.53	0.007	0.13	<0.1	0.03	3.3	0.2	<0.05	6	1.2	<0.2
1202195	Soil		28	0.55	179	0.066	2	1.76	0.010	0.08	<0.1	0.03	2.8	0.1	<0.05	5	0.5	<0.2
1204080	Soil		116	2.15	153	0.042	2	2.35	0.008	0.10	<0.1	0.02	5.3	0.1	<0.05	6	<0.5	<0.2
1204081	Soil		50	0.93	170	0.075	<1	1.83	0.011	0.08	0.1	<0.01	3.3	0.1	<0.05	5	<0.5	<0.2
1204082	Soil		29	0.63	147	0.072	2	1.89	0.014	0.07	0.1	<0.01	3.3	0.1	<0.05	6	<0.5	<0.2
1204083	Soil		16	0.31	77	0.052	<1	0.96	0.021	0.04	<0.1	0.02	1.4	<0.1	<0.05	4	<0.5	<0.2
1204084	Soil		23	0.41	96	0.062	1	1.49	0.014	0.05	0.1	0.02	1.9	<0.1	<0.05	5	<0.5	<0.2
1204085	Soil		94	1.67	136	0.061	<1	2.24	0.009	0.12	<0.1	0.02	4.6	0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000495.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1204086	Soil		0.6	30.6	11.1	71	<0.1	24.1	13.7	405	3.43	5.0	2.3	3.4	32	<0.1	0.3	0.1	62	0.34	0.087	10
1204087	Soil		1.9	43.4	75.8	141	<0.1	48.7	14.6	476	3.81	28.3	3.3	12.6	24	0.1	0.6	0.3	57	0.18	0.046	23
1204088	Soil		0.6	38.6	11.4	41	<0.1	19.3	10.0	273	1.93	4.6	6.7	2.5	45	<0.1	0.5	<0.1	35	0.40	0.122	15
1204089	Soil		0.2	54.2	3.0	85	<0.1	23.8	20.6	572	3.64	3.6	1.8	2.0	47	<0.1	0.2	<0.1	55	0.54	0.178	16
1204090	Soil		1.0	67.3	178.1	279	<0.1	64.3	16.8	624	3.76	6.6	3.0	12.2	41	0.2	0.3	0.3	52	0.25	0.056	49
1204091	Soil		0.9	26.2	14.6	44	<0.1	29.8	11.9	291	3.30	8.7	3.9	6.5	20	<0.1	0.5	0.2	78	0.21	0.021	12
1204092	Soil		0.2	45.8	3.4	34	<0.1	126.8	20.8	327	2.32	0.8	3.1	0.6	14	<0.1	0.1	<0.1	40	0.26	0.041	3
1204093	Soil		0.5	31.6	13.1	57	<0.1	25.5	10.8	440	3.32	5.1	2.4	8.1	35	<0.1	0.3	0.2	64	0.26	0.077	21
1204094	Soil		0.5	21.3	10.1	62	<0.1	26.8	13.2	424	3.09	2.6	5.2	10.5	61	<0.1	0.2	0.1	50	0.42	0.118	41
1204095	Soil		0.7	24.0	40.5	55	<0.1	26.5	13.0	453	3.43	6.3	3.0	15.9	39	0.2	0.4	0.2	59	0.29	0.080	74
1204096	Soil		0.7	23.9	7.9	48	<0.1	29.5	14.6	449	3.67	7.2	3.9	2.5	19	0.1	0.4	0.2	85	0.25	0.038	16
1204097	Soil		1.1	25.1	21.1	45	<0.1	22.3	12.5	371	3.97	7.8	2.4	3.5	13	<0.1	0.4	0.6	81	0.15	0.030	8
1204098	Soil		0.5	6.9	9.1	17	<0.1	4.3	2.4	97	1.29	1.9	3.3	0.5	7	<0.1	0.2	0.1	31	0.07	0.016	3
1204099	Soil		0.3	2.5	2.2	9	<0.1	1.6	1.1	40	0.71	<0.5	1.0	<0.1	6	<0.1	<0.1	<0.1	18	0.03	0.008	1
1204100	Soil		0.7	11.0	7.2	27	<0.1	11.4	4.8	188	2.11	4.2	3.1	1.4	14	<0.1	0.3	0.2	49	0.13	0.017	5
1204101	Soil		0.7	17.1	8.1	33	<0.1	17.6	7.5	270	2.53	4.6	4.4	2.4	18	<0.1	0.3	0.2	59	0.20	0.024	13
1204102	Soil		0.7	15.3	7.5	32	<0.1	17.6	7.7	215	2.34	4.1	3.5	2.4	15	<0.1	0.3	0.1	51	0.15	0.023	11
1204103	Soil		1.5	22.6	9.6	54	<0.1	26.1	12.4	336	3.51	9.9	3.8	3.2	20	0.1	0.7	0.2	81	0.18	0.035	10
1204104	Soil		1.1	24.8	9.0	45	<0.1	34.8	16.2	366	3.60	8.6	2.8	3.5	18	0.1	0.5	0.1	76	0.19	0.032	9
1204105	Soil		1.6	21.4	15.1	47	0.1	22.0	8.4	332	3.85	9.1	12.0	4.0	19	0.1	0.5	0.2	87	0.18	0.046	13
1204106	Soil		1.2	22.5	9.3	50	<0.1	27.0	12.2	342	3.83	9.3	3.5	3.8	18	0.1	0.6	0.2	83	0.17	0.036	9
1204107	Soil		1.5	43.8	59.9	75	0.3	32.3	17.7	468	3.86	7.5	7.6	3.3	21	0.3	0.5	0.2	79	0.25	0.035	11
1204108	Soil		1.3	12.3	37.1	91	0.1	13.8	8.3	397	3.75	4.7	2.0	2.1	14	0.3	0.4	0.3	80	0.17	0.027	7
1204109	Soil		1.6	26.8	12.1	56	0.2	25.6	12.2	335	3.53	10.8	2.9	4.7	21	<0.1	0.6	0.2	81	0.19	0.024	11
1204110	Soil		0.6	37.4	22.3	68	<0.1	29.9	13.5	366	3.74	9.5	1.8	6.2	12	<0.1	0.2	0.1	54	0.20	0.025	23
1204111	Soil		0.5	25.3	48.2	54	<0.1	24.2	11.4	304	2.94	4.7	2.8	9.2	16	<0.1	0.2	0.2	54	0.14	0.026	27
1204112	Soil		1.3	47.4	12.5	63	0.2	19.3	14.9	483	4.32	8.2	6.3	3.2	17	0.2	0.4	0.2	97	0.17	0.029	8
1204113	Soil		1.0	73.1	12.1	62	0.3	23.9	18.1	512	4.81	8.5	10.6	2.4	16	<0.1	0.4	0.1	107	0.16	0.030	8
1204114	Soil		0.9	62.3	24.7	86	0.4	34.7	17.3	577	4.37	4.9	7.4	3.5	15	0.1	0.3	0.2	88	0.19	0.036	11
1204115	Soil		2.0	44.9	6.0	70	<0.1	6.7	5.1	451	2.45	1.4	2.4	7.6	8	<0.1	0.2	0.4	20	0.08	0.024	30

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000495.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
		Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
		MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1204086	Soil		24	1.06	151	0.138	1	2.14	0.010	0.18	0.1	0.02	2.2	0.2	<0.05	7	<0.5	<0.2
1204087	Soil		59	1.66	144	0.129	<1	2.40	0.010	0.34	<0.1	0.02	3.8	0.7	<0.05	7	<0.5	<0.2
1204088	Soil		21	0.60	113	0.093	<1	1.13	0.009	0.21	<0.1	0.02	1.6	0.3	<0.05	4	<0.5	<0.2
1204089	Soil		10	1.47	410	0.163	<1	1.93	0.009	0.90	0.1	<0.01	1.5	0.4	<0.05	7	<0.5	<0.2
1204090	Soil		75	2.77	133	0.243	<1	2.77	0.010	1.04	<0.1	0.02	4.6	1.1	<0.05	7	<0.5	<0.2
1204091	Soil		41	0.63	117	0.118	2	2.72	0.016	0.05	0.1	0.03	3.9	<0.1	<0.05	7	<0.5	<0.2
1204092	Soil		360	2.81	39	0.078	<1	2.24	0.006	0.03	<0.1	0.01	1.8	<0.1	<0.05	5	<0.5	<0.2
1204093	Soil		29	1.04	115	0.115	1	1.95	0.011	0.28	0.1	0.01	3.7	0.3	<0.05	7	<0.5	<0.2
1204094	Soil		33	1.72	191	0.138	<1	1.98	0.008	0.57	<0.1	<0.01	3.2	0.3	<0.05	7	<0.5	<0.2
1204095	Soil		31	0.98	185	0.108	2	2.23	0.012	0.33	0.1	0.02	5.0	0.5	<0.05	6	0.7	<0.2
1204096	Soil		43	1.09	132	0.080	1	2.85	0.018	0.03	<0.1	0.03	6.0	<0.1	<0.05	7	0.6	<0.2
1204097	Soil		38	1.03	114	0.093	<1	2.51	0.009	0.04	<0.1	0.01	4.0	<0.1	<0.05	8	0.6	<0.2
1204098	Soil		9	0.16	25	0.055	<1	0.60	0.018	0.02	<0.1	0.02	0.9	<0.1	<0.05	4	<0.5	<0.2
1204099	Soil		5	0.06	13	0.035	<1	0.24	0.017	0.02	<0.1	<0.01	0.3	<0.1	<0.05	2	<0.5	<0.2
1204100	Soil		19	0.33	55	0.083	1	1.22	0.017	0.03	<0.1	0.02	1.9	<0.1	<0.05	5	<0.5	<0.2
1204101	Soil		27	0.53	114	0.084	<1	1.82	0.016	0.04	<0.1	0.02	3.8	<0.1	<0.05	6	0.5	<0.2
1204102	Soil		24	0.40	89	0.076	<1	1.68	0.018	0.03	<0.1	0.02	2.2	<0.1	<0.05	5	<0.5	<0.2
1204103	Soil		40	0.60	150	0.099	1	3.02	0.018	0.04	<0.1	0.03	4.0	<0.1	<0.05	7	1.0	<0.2
1204104	Soil		41	0.61	148	0.108	2	3.30	0.017	0.04	<0.1	0.04	4.5	<0.1	<0.05	6	0.7	<0.2
1204105	Soil		37	0.50	151	0.095	<1	2.76	0.015	0.05	<0.1	0.04	4.4	<0.1	<0.05	9	0.6	<0.2
1204106	Soil		41	0.74	127	0.118	2	2.97	0.015	0.04	<0.1	0.04	4.4	<0.1	<0.05	8	0.5	<0.2
1204107	Soil		43	0.79	196	0.091	1	2.85	0.018	0.04	<0.1	0.09	5.4	<0.1	<0.05	7	0.7	<0.2
1204108	Soil		25	1.39	90	0.062	<1	2.59	0.008	0.03	<0.1	0.03	3.9	<0.1	<0.05	9	0.9	<0.2
1204109	Soil		38	0.72	140	0.111	1	2.70	0.016	0.05	<0.1	0.04	3.6	<0.1	<0.05	7	0.6	<0.2
1204110	Soil		44	1.81	104	0.090	3	2.49	0.007	0.13	<0.1	0.02	5.3	0.3	<0.05	6	0.6	<0.2
1204111	Soil		45	1.64	95	0.037	<1	2.10	0.007	0.05	<0.1	0.03	5.3	<0.1	<0.05	5	0.6	<0.2
1204112	Soil		28	0.91	118	0.082	2	2.62	0.011	0.04	<0.1	0.04	4.8	<0.1	<0.05	8	0.8	<0.2
1204113	Soil		29	1.13	113	0.079	1	2.94	0.014	0.04	<0.1	0.06	7.1	<0.1	<0.05	7	0.5	<0.2
1204114	Soil		48	1.61	244	0.016	<1	2.32	0.008	0.06	<0.1	0.04	7.5	<0.1	<0.05	6	0.8	<0.2
1204115	Soil		9	0.99	107	0.025	<1	1.49	0.007	0.08	<0.1	0.02	1.1	<0.1	<0.05	4	0.9	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000495.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1204116	Soil		0.8	7.4	7.0	24	<0.1	8.6	4.3	127	1.60	2.4	3.9	1.4	10	<0.1	0.2	0.1	40	0.08	0.015	4
1204117	Soil		0.4	15.7	4.7	63	<0.1	12.7	17.5	586	3.50	2.2	1.2	1.2	9	<0.1	0.4	0.2	48	0.08	0.010	3
1204118	Soil		0.3	83.1	9.6	68	<0.1	40.5	16.2	582	3.27	2.9	10.0	2.6	14	<0.1	0.2	0.2	51	0.22	0.032	13
1204119	Soil		1.5	20.0	216.8	203	0.7	13.6	8.7	356	3.17	2.9	11.7	4.6	12	1.8	0.6	0.7	30	0.19	0.037	26
1204120	Soil		0.3	5.4	7.1	15	<0.1	3.4	1.7	118	0.68	1.0	2.1	0.9	8	0.1	<0.1	0.1	12	0.10	0.021	10
1204121	Soil		0.6	13.3	16.8	36	<0.1	9.3	5.8	223	1.81	3.7	1.0	3.2	11	<0.1	0.2	0.2	27	0.13	0.032	13
1204122	Soil		0.6	17.2	43.4	59	<0.1	17.4	8.8	216	2.50	4.2	4.5	7.6	14	0.2	0.3	0.2	36	0.18	0.067	26
1204123	Soil		0.8	12.9	34.1	33	0.2	10.4	5.8	160	1.90	7.1	2.3	10.3	21	<0.1	0.3	0.2	35	0.18	0.036	17
1204124	Soil		0.7	14.9	31.5	29	0.1	12.9	5.8	143	1.99	10.4	3.4	4.5	16	0.1	0.4	0.2	51	0.15	0.016	8
1204125	Soil		0.6	12.8	22.6	28	<0.1	12.3	5.6	161	1.55	5.4	2.1	3.8	13	0.1	0.4	0.2	36	0.12	0.017	12
1204126	Soil		0.5	39.2	89.9	78	0.2	16.2	7.0	209	2.25	6.8	6.3	6.0	23	0.3	0.3	0.1	44	0.23	0.021	19
1204127	Soil		1.0	20.2	19.4	67	0.1	16.9	10.8	255	2.71	5.8	3.0	6.2	15	<0.1	0.4	0.2	43	0.13	0.034	18
1204128	Soil		0.4	12.2	11.1	121	0.1	8.2	7.2	427	2.06	2.0	2.6	7.1	23	0.1	0.3	0.1	22	0.20	0.070	34
1204129	Soil		0.6	19.6	103.8	58	0.1	13.4	5.4	154	2.06	12.9	7.6	5.2	15	0.2	0.4	0.2	42	0.17	0.020	14
1204130	Soil		0.9	23.4	142.3	102	0.7	16.8	8.5	352	2.27	8.9	5.9	2.6	21	0.7	0.4	0.2	47	0.20	0.038	10
1204131	Soil		0.8	33.0	56.0	194	0.5	14.0	7.0	391	2.38	7.2	10.2	3.9	24	0.5	0.4	0.2	39	0.25	0.032	20
1204132	Soil		1.0	23.6	41.7	59	<0.1	19.9	8.0	183	2.54	8.3	2.8	6.7	21	0.3	0.4	0.4	53	0.22	0.039	18
1204133	Soil		0.5	21.5	16.5	52	<0.1	27.2	10.9	338	2.78	6.3	1.0	7.1	41	0.1	0.2	0.2	37	0.31	0.033	23
1204134	Soil		1.0	13.8	32.0	37	0.1	11.6	5.0	230	1.70	14.1	3.5	8.2	13	0.3	0.3	0.3	28	0.11	0.040	29
1204135	Soil		1.0	18.4	10.7	24	<0.1	7.8	3.3	129	1.65	4.7	3.6	1.5	19	0.1	0.3	0.2	44	0.18	0.015	9
1204136	Soil		0.4	51.3	5.9	58	<0.1	69.6	19.6	577	3.68	3.1	3.9	2.0	19	<0.1	0.2	<0.1	102	0.22	0.017	8
1204137	Soil		0.5	120.2	8.8	79	<0.1	35.5	22.7	893	5.17	3.5	2.7	2.7	6	0.1	0.2	0.1	84	0.09	0.026	10
1204138	Soil		0.4	81.6	7.2	82	0.2	33.2	25.3	1239	5.77	2.6	6.1	2.2	15	0.2	0.2	0.1	114	0.39	0.030	9
1204139	Soil		0.5	19.2	38.9	90	0.1	10.3	5.9	168	1.81	10.7	3.1	5.3	31	0.6	0.4	0.2	27	0.16	0.026	17
1204140	Soil		0.6	17.4	21.9	43	<0.1	14.6	5.2	180	1.81	5.2	5.2	10.4	26	0.1	0.3	0.1	32	0.26	0.041	36
1204141	Soil		0.5	20.2	40.2	27	<0.1	16.5	5.5	192	1.41	5.0	1.5	22.0	14	0.1	0.3	0.2	24	0.13	0.022	56

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

CERTIFICATE OF ANALYSIS WHI11000495.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1204116	Soil	16	0.30	62	0.064	1	1.05	0.018	0.02	<0.1	0.02	1.4	<0.1	<0.05	5	<0.5	<0.2
1204117	Soil	9	1.80	59	0.013	1	2.18	0.010	0.03	<0.1	<0.01	5.3	<0.1	<0.05	5	<0.5	<0.2
1204118	Soil	61	1.62	185	0.032	2	2.30	0.011	0.05	<0.1	0.04	7.7	<0.1	<0.05	6	1.2	<0.2
1204119	Soil	20	0.54	115	0.015	2	1.15	0.008	0.05	<0.1	0.04	3.3	<0.1	<0.05	3	1.2	0.2
1204120	Soil	5	0.08	37	0.020	1	0.34	0.017	0.03	<0.1	0.01	0.5	<0.1	<0.05	2	0.8	<0.2
1204121	Soil	11	0.24	124	0.025	2	0.98	0.007	0.07	<0.1	0.02	1.9	<0.1	<0.05	3	<0.5	<0.2
1204122	Soil	24	0.37	143	0.030	2	1.22	0.006	0.07	<0.1	0.03	2.4	<0.1	<0.05	4	0.9	<0.2
1204123	Soil	18	0.29	91	0.069	1	1.22	0.016	0.14	<0.1	0.02	2.0	0.2	<0.05	4	0.7	<0.2
1204124	Soil	22	0.30	95	0.079	2	1.50	0.014	0.05	<0.1	0.02	2.4	0.1	<0.05	6	0.6	<0.2
1204125	Soil	19	0.28	97	0.056	2	1.46	0.013	0.05	<0.1	0.01	1.9	<0.1	<0.05	4	1.1	<0.2
1204126	Soil	27	0.43	162	0.075	1	1.46	0.017	0.05	<0.1	0.03	4.1	<0.1	<0.05	4	0.8	<0.2
1204127	Soil	25	0.41	166	0.050	2	1.86	0.009	0.06	<0.1	0.02	3.8	0.1	<0.05	5	0.6	<0.2
1204128	Soil	11	0.31	131	0.052	1	0.93	0.009	0.20	<0.1	0.02	2.1	0.2	<0.05	3	0.7	<0.2
1204129	Soil	21	0.34	108	0.063	2	1.59	0.010	0.13	0.1	0.02	2.5	0.2	<0.05	4	0.9	<0.2
1204130	Soil	23	0.35	166	0.049	1	1.78	0.012	0.08	0.1	0.04	2.6	0.1	<0.05	5	1.3	<0.2
1204131	Soil	22	0.34	144	0.046	3	1.23	0.015	0.09	<0.1	0.05	4.3	0.1	<0.05	4	<0.5	<0.2
1204132	Soil	28	0.47	133	0.083	2	2.05	0.015	0.07	<0.1	0.04	3.3	<0.1	<0.05	6	<0.5	<0.2
1204133	Soil	42	1.25	143	0.067	2	2.05	0.007	0.05	<0.1	<0.01	4.1	<0.1	<0.05	6	1.1	<0.2
1204134	Soil	13	0.19	107	0.028	2	0.95	0.007	0.16	<0.1	0.02	1.8	0.1	<0.05	4	1.2	<0.2
1204135	Soil	18	0.20	197	0.060	<1	1.04	0.014	0.05	<0.1	0.03	2.2	<0.1	<0.05	5	1.0	<0.2
1204136	Soil	223	2.36	119	0.058	1	2.75	0.019	0.03	<0.1	0.04	15.6	<0.1	<0.05	7	<0.5	<0.2
1204137	Soil	104	2.48	61	0.014	1	3.49	0.008	0.02	<0.1	0.05	18.0	<0.1	<0.05	8	0.8	<0.2
1204138	Soil	79	2.01	95	0.021	3	3.03	0.009	0.02	<0.1	0.07	18.2	<0.1	<0.05	8	<0.5	<0.2
1204139	Soil	18	0.22	187	0.032	2	0.93	0.008	0.08	<0.1	0.04	3.3	<0.1	<0.05	3	0.7	<0.2
1204140	Soil	23	0.33	135	0.051	2	1.24	0.010	0.11	<0.1	0.01	3.2	0.1	<0.05	3	0.6	<0.2
1204141	Soil	18	0.28	102	0.036	1	1.08	0.009	0.09	<0.1	0.02	3.4	<0.1	<0.05	3	1.0	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000495.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1203052	Soil	1.6	31.0	32.1	59	0.2	29.3	12.6	416	3.11	11.6	2.5	10.9	27	0.2	0.4	0.3	64	0.41	0.049	33
REP 1203052	QC	1.5	29.8	30.4	57	0.2	30.1	12.2	407	3.08	11.1	5.1	10.5	27	0.2	0.4	0.5	65	0.40	0.045	33
1203056	Soil	0.9	40.1	15.8	60	<0.1	30.1	12.2	459	3.29	6.2	3.9	3.4	21	0.1	0.3	0.1	82	0.38	0.037	12
REP 1203056	QC	1.0	40.2	15.7	60	<0.1	29.7	12.2	468	3.24	5.6	1.4	3.4	20	0.1	0.3	0.1	80	0.38	0.039	12
1203077	Soil	1.0	84.3	17.0	146	0.2	36.4	12.7	601	3.05	3.8	4.9	1.9	25	0.6	0.2	0.2	68	0.56	0.084	10
REP 1203077	QC	0.9	82.6	17.1	138	0.2	35.0	12.6	608	3.02	3.6	1.9	2.0	24	0.5	0.2	0.2	70	0.55	0.080	10
1203095	Soil	0.6	26.9	9.1	58	0.1	21.1	9.7	289	2.09	0.5	6.1	1.3	19	<0.1	0.3	0.1	50	0.28	0.047	8
REP 1203095	QC	0.5	26.7	9.9	61	0.1	20.9	9.9	298	2.18	<0.5	5.2	1.3	20	0.1	0.2	0.1	46	0.29	0.052	8
1202244	Soil	0.7	25.0	11.3	69	<0.1	18.6	7.1	237	2.52	2.3	3.1	4.2	16	0.2	0.3	<0.1	60	0.33	0.067	13
REP 1202244	QC	0.7	24.4	11.0	70	<0.1	16.9	6.9	227	2.41	2.5	5.3	4.1	17	0.1	0.3	<0.1	58	0.32	0.068	13
1204092	Soil	0.2	45.8	3.4	34	<0.1	126.8	20.8	327	2.32	0.8	3.1	0.6	14	<0.1	0.1	<0.1	40	0.26	0.041	3
REP 1204092	QC	0.3	48.6	4.0	36	<0.1	129.7	22.1	332	2.41	0.9	0.8	0.7	15	<0.1	0.1	<0.1	41	0.26	0.039	3
1204110	Soil	0.6	37.4	22.3	68	<0.1	29.9	13.5	366	3.74	9.5	1.8	6.2	12	<0.1	0.2	0.1	54	0.20	0.025	23
REP 1204110	QC	0.5	36.1	21.0	67	<0.1	28.8	12.8	351	3.58	8.7	3.1	5.9	12	<0.1	0.1	<0.1	51	0.19	0.025	22
1204116	Soil	0.8	7.4	7.0	24	<0.1	8.6	4.3	127	1.60	2.4	3.9	1.4	10	<0.1	0.2	0.1	40	0.08	0.015	4
REP 1204116	QC	0.8	7.2	6.7	24	<0.1	8.5	4.2	125	1.59	1.8	1.8	1.4	10	<0.1	0.3	0.1	41	0.07	0.014	4
1204125	Soil	0.6	12.8	22.6	28	<0.1	12.3	5.6	161	1.55	5.4	2.1	3.8	13	0.1	0.4	0.2	36	0.12	0.017	12
REP 1204125	QC	0.7	12.9	22.0	28	<0.1	11.6	5.8	158	1.52	5.2	2.9	3.6	13	0.2	0.4	0.2	36	0.12	0.016	12
Reference Materials																					
STD DS8	Standard	13.1	118.2	126.3	321	1.7	39.2	7.8	619	2.53	27.3	116.0	7.0	66	2.2	5.7	6.7	41	0.68	0.080	14
STD DS8	Standard	13.2	113.5	125.1	319	1.7	38.9	8.0	623	2.47	26.4	113.5	7.0	70	2.5	6.1	6.5	40	0.70	0.082	15
STD DS8	Standard	11.5	91.6	111.3	275	1.6	32.6	6.5	535	2.20	23.0	104.6	6.3	69	2.1	5.0	6.0	35	0.65	0.071	15
STD DS8	Standard	11.7	93.0	110.0	276	1.6	30.9	6.1	551	2.17	23.3	101.2	6.5	69	2.2	5.3	6.1	36	0.67	0.071	15
STD DS8	Standard	13.4	116.4	129.4	329	1.8	41.7	7.7	633	2.51	26.7	109.4	7.0	61	2.5	5.3	6.2	43	0.68	0.080	14
STD DS8	Standard	13.5	112.2	129.8	320	1.8	38.6	7.7	621	2.53	26.4	125.4	7.0	64	2.3	5.2	6.4	43	0.72	0.079	15
STD DS8	Standard	13.9	113.5	118.5	328	2.0	41.0	7.6	642	2.57	26.8	114.6	6.9	64	2.4	5.9	6.5	44	0.73	0.087	15
STD DS8	Standard	14.4	109.9	123.4	300	1.8	40.4	7.7	627	2.50	24.2	107.5	7.4	68	2.3	5.6	6.4	43	0.74	0.076	16
STD DS8	Standard	14.1	112.0	134.0	317	1.8	39.6	7.6	663	2.60	25.7	120.6	6.7	76	2.5	6.4	7.5	44	0.70	0.080	15

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000495.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1203052	Soil	36	0.72	218	0.096	2	2.40	0.016	0.05	0.1	0.03	4.2	<0.1	<0.05	6	0.5	<0.2
REP 1203052	QC	36	0.67	223	0.092	2	2.29	0.016	0.05	0.1	0.02	4.0	0.1	<0.05	6	<0.5	<0.2
1203056	Soil	45	1.01	176	0.105	2	2.51	0.016	0.05	0.1	0.03	4.7	<0.1	<0.05	7	0.5	<0.2
REP 1203056	QC	43	1.02	172	0.086	2	2.56	0.017	0.04	0.1	0.04	4.6	<0.1	<0.05	7	<0.5	<0.2
1203077	Soil	57	1.41	123	0.071	2	2.33	0.022	0.04	0.1	0.16	5.2	<0.1	<0.05	6	0.6	<0.2
REP 1203077	QC	58	1.36	124	0.071	1	2.22	0.020	0.04	0.1	0.16	5.1	<0.1	<0.05	6	<0.5	<0.2
1203095	Soil	39	0.84	131	0.051	<1	1.72	0.015	0.05	0.1	0.02	3.0	<0.1	<0.05	5	<0.5	<0.2
REP 1203095	QC	42	0.89	135	0.056	2	1.80	0.017	0.05	0.2	<0.01	3.3	<0.1	<0.05	6	<0.5	<0.2
1202244	Soil	33	0.46	96	0.099	<1	1.54	0.011	0.07	0.1	0.02	3.8	<0.1	<0.05	4	<0.5	<0.2
REP 1202244	QC	33	0.45	95	0.102	<1	1.53	0.011	0.07	0.2	0.01	3.6	<0.1	<0.05	5	<0.5	<0.2
1204092	Soil	360	2.81	39	0.078	<1	2.24	0.006	0.03	<0.1	0.01	1.8	<0.1	<0.05	5	<0.5	<0.2
REP 1204092	QC	351	2.92	40	0.078	1	2.30	0.006	0.03	<0.1	0.02	1.9	<0.1	<0.05	5	<0.5	<0.2
1204110	Soil	44	1.81	104	0.090	3	2.49	0.007	0.13	<0.1	0.02	5.3	0.3	<0.05	6	0.6	<0.2
REP 1204110	QC	41	1.76	99	0.082	2	2.41	0.007	0.13	<0.1	0.01	4.8	0.2	<0.05	6	0.9	<0.2
1204116	Soil	16	0.30	62	0.064	1	1.05	0.018	0.02	<0.1	0.02	1.4	<0.1	<0.05	5	<0.5	<0.2
REP 1204116	QC	16	0.27	58	0.062	<1	1.06	0.016	0.02	<0.1	0.02	1.3	<0.1	<0.05	4	0.5	<0.2
1204125	Soil	19	0.28	97	0.056	2	1.46	0.013	0.05	<0.1	0.01	1.9	<0.1	<0.05	4	1.1	<0.2
REP 1204125	QC	18	0.28	95	0.056	1	1.43	0.014	0.05	<0.1	<0.01	1.9	<0.1	<0.05	4	0.5	<0.2
Reference Materials																	
STD DS8	Standard	123	0.61	266	0.130	4	0.90	0.090	0.42	3.2	0.18	2.0	5.6	0.12	5	5.3	4.8
STD DS8	Standard	121	0.61	279	0.130	2	0.95	0.096	0.42	3.1	0.20	2.2	5.5	0.14	5	5.9	5.2
STD DS8	Standard	101	0.54	262	0.107	3	0.87	0.095	0.40	2.7	0.17	2.5	4.8	0.14	4	5.1	4.1
STD DS8	Standard	103	0.53	272	0.109	3	0.89	0.099	0.40	2.8	0.15	2.6	4.7	0.14	4	5.0	4.5
STD DS8	Standard	119	0.61	276	0.115	3	0.91	0.091	0.42	3.1	0.21	2.2	5.4	0.16	5	6.9	4.8
STD DS8	Standard	119	0.65	286	0.117	2	0.97	0.096	0.42	3.0	0.23	2.1	5.6	0.16	5	5.6	5.0
STD DS8	Standard	122	0.57	292	0.121	3	0.90	0.093	0.45	3.2	0.20	2.0	5.2	0.16	5	6.9	5.1
STD DS8	Standard	122	0.55	290	0.127	2	0.92	0.090	0.42	3.1	0.20	2.1	5.4	0.17	5	6.0	4.5
STD DS8	Standard	122	0.64	283	0.132	2	0.94	0.093	0.43	3.1	0.21	2.0	5.7	0.11	5	5.3	4.7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000495.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	13.7	112.8	129.5	313	1.9	40.3	7.9	631	2.65	26.2	110.8	6.8	78	2.4	6.4	7.6	44	0.69	0.079	15
STD DS8	Standard	11.5	96.6	111.3	277	1.6	33.1	6.7	545	2.14	23.1	100.7	6.0	53	1.8	4.3	5.2	37	0.63	0.069	13
STD DS8	Standard	12.1	98.3	113.8	280	1.6	33.0	6.7	551	2.17	23.0	99.4	6.0	53	2.0	4.3	5.2	36	0.63	0.068	13
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Druid Exploration**
Box 1485
Dawson City YT Y0B 1G0 Canada

Project: VIP
Report Date: August 11, 2011

QUALITY CONTROL REPORT WHI11000495.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
STD DS8	Standard	119	0.65	279	0.133	1	0.93	0.095	0.43	3.2	0.21	2.0	5.7	0.12	5	5.8	5.4
STD DS8	Standard	101	0.54	239	0.097	3	0.84	0.084	0.37	2.6	0.17	2.3	4.9	0.11	4	5.0	4.4
STD DS8	Standard	102	0.53	247	0.096	2	0.83	0.079	0.37	2.5	0.16	2.1	5.0	0.11	4	4.9	4.5
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Submitted By: Bruce Durham
Receiving Lab: Canada-Whitehorse
Received: July 20, 2011
Report Date: August 09, 2011
Page: 1 of 8

CERTIFICATE OF ANALYSIS WHI11000681.1

CLIENT JOB INFORMATION

Project: VIP
Shipment ID: july-5-2011
P.O. Number
Number of Samples: 206

SAMPLE DISPOSAL

RTRN-PLP Return
RTRN-RJT Return

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	204	Dry at 60C			WHI
SS80	204	Dry at 60C sieve 100g to -80 mesh			WHI
RJSV	204	Saving all or part of Soil Reject			VAN
1DX2	203	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN

ADDITIONAL COMMENTS

Invoice To: Goldspike Exploration Inc.
56th Floor - 100 King Street West
Toronto ON M5X 1C9
Canada

CC: Don Christie
Daithi Mac Gearailt
Randy Sedore

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203671	Soil	3.5	61.5	25.0	219	<0.1	16.5	5.3	838	4.07	5.0	1.9	21.1	29	0.1	0.3	0.8	51	0.17	0.058	69
1203672	Soil	3.0	14.3	9.6	90	<0.1	14.8	7.5	604	4.18	4.5	7.6	18.7	23	0.1	0.3	0.5	50	0.16	0.045	68
1203673	Soil	1.7	23.9	12.2	68	<0.1	21.7	9.1	423	3.02	9.6	6.1	1.1	21	0.2	0.5	0.2	65	0.23	0.052	6
1203674	Soil	1.4	20.4	10.5	46	<0.1	18.5	8.9	266	2.79	8.5	7.3	2.7	14	0.1	0.5	0.2	60	0.13	0.032	8
1203675	Soil	1.9	29.8	18.7	149	<0.1	41.5	18.6	852	5.77	4.6	2.4	7.3	10	0.2	0.2	1.0	118	0.10	0.034	15
1203676	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203677	Soil	0.5	27.7	10.6	57	<0.1	23.9	10.7	216	2.82	5.3	7.0	7.8	22	0.2	0.4	0.2	74	0.32	0.046	22
1203678	Soil	0.8	77.6	69.1	450	<0.1	55.5	19.6	1277	4.42	5.7	4.3	7.1	8	0.2	0.2	1.8	72	0.13	0.023	11
1203679	Soil	0.6	27.2	21.3	87	<0.1	34.3	9.6	269	3.13	5.2	1.9	6.1	14	<0.1	0.2	0.8	58	0.25	0.031	11
1203680	Soil	0.5	41.2	5.1	78	<0.1	37.7	21.3	688	4.12	2.1	2.0	2.0	13	<0.1	0.1	0.1	110	0.23	0.031	7
1203681	Soil	0.8	29.6	4.4	39	<0.1	16.4	11.4	462	2.35	2.8	3.5	0.9	21	<0.1	0.2	<0.1	55	0.45	0.057	9
1203682	Soil	1.1	98.6	25.9	174	<0.1	68.2	17.4	1017	6.09	3.7	3.1	5.1	6	<0.1	<0.1	1.7	68	0.07	0.013	12
1203683	Soil	1.4	81.2	45.5	186	0.1	69.3	39.1	1440	5.82	6.2	3.9	11.9	9	0.2	0.2	1.2	85	0.10	0.026	20
1203684	Soil	1.3	57.4	10.2	67	<0.1	38.8	17.9	460	3.85	4.2	2.9	3.6	12	0.2	0.3	0.3	78	0.16	0.050	14
1203685	Soil	0.6	75.9	4.8	59	<0.1	80.9	17.2	375	2.85	2.5	2.9	1.2	14	<0.1	0.2	<0.1	64	0.16	0.060	7
1203686	Soil	0.7	76.2	6.9	107	0.1	28.3	15.5	421	3.70	4.5	3.5	2.2	14	0.1	0.3	0.1	85	0.19	0.046	8
1203687	Soil	0.9	98.3	6.1	72	0.1	27.7	17.9	753	4.73	3.8	4.0	1.1	10	<0.1	0.3	0.4	90	0.10	0.055	5
1203688	Soil	1.8	72.9	179.7	224	0.3	61.6	17.8	466	3.37	4.0	4.2	9.9	12	0.3	0.2	1.6	46	0.17	0.059	23
1203689	Soil	2.0	52.3	11.1	112	<0.1	60.5	13.1	707	3.61	2.0	2.6	6.6	12	0.2	0.1	0.5	47	0.11	0.043	21
1203690	Soil	0.7	134.0	5.2	155	<0.1	45.9	31.8	984	3.73	3.5	1.8	1.9	12	0.2	0.2	0.1	65	0.20	0.069	8
1203691	Soil	1.0	117.2	22.5	102	0.3	35.2	17.7	510	3.74	4.6	9.1	3.0	11	0.6	0.3	0.4	60	0.15	0.046	20
1203692	Soil	3.3	37.8	35.7	108	<0.1	16.4	5.4	475	2.21	1.2	1.8	23.3	4	<0.1	<0.1	1.0	11	0.05	0.019	7
1203693	Soil	3.5	71.4	8.7	79	0.3	14.8	9.7	448	4.68	4.2	12.9	4.6	6	<0.1	0.2	1.0	39	0.04	0.047	7
1203694	Soil	1.2	16.4	12.1	43	<0.1	19.0	10.2	329	2.96	7.1	3.2	2.9	12	0.1	0.4	0.2	49	0.13	0.026	9
1203695	Soil	1.2	14.9	7.8	36	<0.1	13.4	7.4	344	2.44	4.8	3.0	3.4	11	<0.1	0.2	0.1	43	0.11	0.024	11
1203696	Soil	1.4	16.5	9.0	44	<0.1	17.7	8.0	224	3.35	8.4	4.2	2.3	15	0.1	0.4	0.1	75	0.15	0.027	8
1203697	Soil	1.3	14.6	7.0	32	<0.1	10.8	6.1	243	2.37	5.6	3.7	1.1	11	<0.1	0.3	0.1	52	0.11	0.032	8
1203698	Soil	2.5	16.3	6.1	40	<0.1	14.3	9.1	388	3.33	4.6	3.4	2.0	10	<0.1	0.2	0.2	47	0.11	0.039	9
1203699	Soil	1.7	24.5	20.9	57	0.1	17.3	9.3	377	3.30	6.3	6.9	3.0	13	0.2	0.3	0.2	64	0.15	0.040	14
1203700	Soil	0.4	5.1	5.3	9	<0.1	2.3	1.1	38	0.53	0.9	2.4	<0.1	6	<0.1	<0.1	<0.1	18	0.04	0.015	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203671	Soil	63	1.80	132	0.147	3	2.12	0.018	0.60	0.1	0.03	3.3	0.5	0.25	10	<0.5	<0.2
1203672	Soil	27	1.04	132	0.119	3	1.79	0.020	0.50	0.1	0.03	3.3	0.4	0.20	7	<0.5	<0.2
1203673	Soil	31	0.48	139	0.051	2	1.85	0.015	0.05	0.1	0.06	2.0	<0.1	0.06	7	<0.5	<0.2
1203674	Soil	29	0.42	115	0.055	2	1.96	0.014	0.03	0.1	0.04	2.6	<0.1	<0.05	6	<0.5	<0.2
1203675	Soil	107	2.23	185	0.084	1	2.56	0.013	0.47	0.1	0.02	13.1	0.2	0.14	9	<0.5	0.6
1203676	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203677	Soil	47	0.86	127	0.113	2	2.00	0.017	0.06	0.1	0.04	5.1	<0.1	<0.05	5	<0.5	<0.2
1203678	Soil	152	2.51	63	0.047	2	2.66	0.005	0.07	<0.1	0.04	7.9	<0.1	<0.05	6	0.6	0.3
1203679	Soil	71	1.68	75	0.124	2	2.13	0.008	0.22	<0.1	0.05	5.5	0.3	<0.05	6	<0.5	<0.2
1203680	Soil	76	2.79	135	0.146	<1	2.98	0.010	0.47	<0.1	0.03	4.9	0.3	<0.05	8	<0.5	<0.2
1203681	Soil	30	1.03	187	0.056	2	1.49	0.015	0.14	<0.1	0.04	2.9	0.1	0.06	5	<0.5	<0.2
1203682	Soil	166	1.97	66	0.043	<1	2.33	0.004	0.28	<0.1	0.03	8.0	0.2	<0.05	6	<0.5	0.3
1203683	Soil	178	2.40	132	0.114	2	2.64	0.006	0.57	<0.1	0.04	10.2	0.4	<0.05	7	1.3	0.6
1203684	Soil	82	1.69	93	0.064	<1	2.62	0.007	0.07	<0.1	0.05	7.0	<0.1	<0.05	7	0.8	<0.2
1203685	Soil	136	2.23	77	0.044	1	2.38	0.006	0.04	<0.1	0.03	4.4	<0.1	<0.05	7	<0.5	<0.2
1203686	Soil	51	1.64	103	0.090	2	2.49	0.008	0.16	<0.1	0.04	4.7	0.1	<0.05	8	0.6	<0.2
1203687	Soil	63	2.27	57	0.023	<1	2.67	0.005	0.05	<0.1	0.03	5.7	<0.1	<0.05	8	<0.5	<0.2
1203688	Soil	121	2.58	93	0.049	1	2.41	0.005	0.07	<0.1	0.06	4.1	0.1	<0.05	7	<0.5	<0.2
1203689	Soil	98	2.87	139	0.046	<1	2.73	0.003	0.08	<0.1	0.02	4.8	0.1	<0.05	7	<0.5	<0.2
1203690	Soil	88	2.38	134	0.112	<1	2.56	0.006	0.17	<0.1	0.04	3.8	0.1	<0.05	7	<0.5	<0.2
1203691	Soil	53	1.60	102	0.056	1	2.17	0.007	0.05	<0.1	0.05	5.7	<0.1	<0.05	5	<0.5	<0.2
1203692	Soil	21	1.96	48	0.046	<1	1.72	0.003	0.27	<0.1	0.01	1.4	0.2	<0.05	5	<0.5	<0.2
1203693	Soil	26	1.38	57	0.016	<1	1.70	0.004	0.03	<0.1	0.03	3.7	<0.1	<0.05	4	0.9	0.5
1203694	Soil	25	0.52	118	0.061	<1	1.91	0.009	0.03	<0.1	0.04	3.2	<0.1	<0.05	5	<0.5	<0.2
1203695	Soil	20	0.35	104	0.054	1	1.27	0.010	0.03	<0.1	0.02	2.9	<0.1	<0.05	4	<0.5	<0.2
1203696	Soil	32	0.47	99	0.086	<1	1.87	0.010	0.03	0.1	0.03	2.8	<0.1	<0.05	7	0.5	<0.2
1203697	Soil	21	0.34	68	0.057	<1	1.12	0.009	0.03	<0.1	0.03	1.8	<0.1	<0.05	5	<0.5	<0.2
1203698	Soil	27	1.05	66	0.036	<1	1.72	0.007	0.03	<0.1	0.03	3.3	<0.1	<0.05	6	0.5	<0.2
1203699	Soil	29	0.88	91	0.049	1	1.87	0.007	0.04	<0.1	0.03	3.8	<0.1	<0.05	7	<0.5	<0.2
1203700	Soil	6	0.07	26	0.016	<1	0.28	0.013	0.02	<0.1	0.02	0.2	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1204153	Soil	0.8	35.9	16.4	54	<0.1	22.2	10.5	401	3.10	5.8	3.8	3.6	16	0.1	0.2	0.2	65	0.20	0.040	13
1204154	Soil	0.8	30.8	12.5	52	<0.1	22.0	9.7	288	2.67	5.9	6.8	3.7	15	0.1	0.3	0.1	58	0.20	0.037	14
1204155	Soil	0.9	47.9	12.4	153	<0.1	22.8	14.4	450	3.97	5.9	3.3	2.4	11	0.2	0.3	<0.1	85	0.18	0.040	8
1204156	Soil	0.8	29.8	13.1	52	0.1	17.7	11.4	502	2.26	4.0	5.8	0.8	12	0.2	0.3	<0.1	53	0.15	0.039	7
1204157	Soil	0.6	62.5	14.7	90	<0.1	26.1	12.8	574	3.24	3.3	3.8	5.3	8	<0.1	0.2	<0.1	55	0.14	0.030	17
1204158	Soil	0.7	36.8	18.3	54	<0.1	25.3	12.6	325	2.55	4.4	6.4	6.0	14	0.1	0.3	<0.1	50	0.21	0.030	26
1204159	Soil	0.7	38.4	7.8	60	<0.1	47.1	15.3	568	3.18	1.9	<0.5	4.5	16	<0.1	0.2	0.2	56	0.25	0.035	11
1204160	Soil	0.3	52.5	13.5	80	<0.1	25.1	19.4	786	3.46	1.4	1.8	7.8	45	0.1	0.3	0.1	50	0.55	0.171	21
1204161	Soil	0.9	18.0	24.9	55	<0.1	17.9	10.2	364	2.79	4.9	3.4	9.1	14	<0.1	0.3	0.3	45	0.18	0.040	19
1204162	Soil	1.0	16.3	14.4	42	<0.1	19.2	8.2	261	2.59	5.1	6.7	9.8	15	<0.1	0.4	0.3	48	0.21	0.040	51
1204163	Soil	0.9	19.9	36.5	106	<0.1	20.7	12.5	578	3.50	3.2	0.7	7.6	14	<0.1	0.2	0.5	60	0.21	0.042	20
1204164	Soil	0.5	31.6	35.7	62	<0.1	47.5	15.2	330	2.85	4.5	4.6	15.4	18	0.1	0.3	0.4	53	0.26	0.049	60
1204165	Soil	0.4	47.9	30.8	65	<0.1	84.9	23.7	525	3.68	2.8	1.1	12.0	29	<0.1	0.2	0.2	59	0.50	0.086	45
1204166	Soil	0.5	37.7	15.8	59	<0.1	64.0	19.5	430	3.47	4.6	4.7	9.0	22	<0.1	0.3	0.6	59	0.34	0.050	29
1204167	Soil	0.8	20.5	10.4	52	<0.1	36.9	12.9	283	2.95	4.8	1.9	4.0	25	0.1	0.3	0.1	60	0.37	0.054	11
1204168	Soil	0.5	15.9	8.2	34	<0.1	17.2	8.1	193	2.04	2.2	1.2	1.2	22	<0.1	0.2	0.1	41	0.28	0.047	8
1204169	Soil	0.7	25.9	14.5	56	<0.1	39.8	15.5	446	2.96	3.3	0.9	7.3	25	<0.1	0.2	0.2	55	0.35	0.061	18
1204170	Soil	0.7	22.3	14.7	45	<0.1	22.0	11.6	366	2.50	4.3	2.5	4.6	25	<0.1	0.2	0.2	50	0.31	0.046	16
1204171	Soil	0.3	35.7	9.8	50	<0.1	51.8	15.5	399	2.71	2.9	2.6	5.9	25	<0.1	0.2	<0.1	48	0.37	0.058	18
1204172	Soil	0.5	34.4	17.2	53	<0.1	43.5	13.9	396	2.54	2.8	2.8	8.8	22	<0.1	0.2	0.1	48	0.35	0.059	29
1204173	Soil	0.6	24.8	28.8	48	<0.1	38.1	12.0	346	2.25	2.5	3.2	7.9	22	0.1	0.3	0.1	45	0.37	0.054	22
1204174	Soil	0.7	24.7	35.3	67	<0.1	37.1	14.5	539	2.67	2.5	17.3	9.0	29	0.1	0.3	0.2	45	0.49	0.061	24
1204175	Soil	0.4	37.1	44.8	72	<0.1	47.8	16.9	379	3.28	3.9	2.8	18.8	25	0.1	0.4	0.2	45	0.42	0.072	55
1204176	Soil	0.7	25.7	37.7	57	0.2	27.5	13.1	488	2.52	3.7	4.4	9.0	33	0.1	0.4	0.2	47	0.52	0.057	41
1204177	Soil	1.4	33.7	42.7	67	0.1	37.9	14.5	388	2.83	5.1	2.1	10.8	24	<0.1	0.3	0.3	46	0.38	0.071	40
1204178	Soil	0.7	30.2	11.0	41	<0.1	33.2	12.1	335	2.11	1.5	3.5	4.4	33	<0.1	0.2	<0.1	34	0.43	0.098	15
1204179	Soil	0.4	46.1	22.0	57	0.1	55.3	18.8	434	2.74	3.5	2.7	10.3	39	0.2	0.2	0.1	38	0.58	0.097	34
1204180	Soil	1.0	34.1	23.2	66	<0.1	65.7	21.5	360	3.54	4.7	3.6	10.3	29	0.1	0.2	0.2	50	0.47	0.091	31
1204181	Soil	1.1	25.0	24.3	54	<0.1	37.0	13.2	501	2.44	5.5	2.0	8.0	35	0.2	0.1	0.2	32	0.43	0.075	25
1204182	Soil	1.1	33.6	26.6	56	0.2	44.4	14.1	481	2.96	4.7	6.3	8.3	28	0.2	0.2	0.2	46	0.34	0.072	30

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1204153	Soil	37	0.72	114	0.064	<1	1.86	0.009	0.06	<0.1	0.03	4.8	<0.1	<0.05	6	0.6	<0.2
1204154	Soil	35	0.69	105	0.080	<1	2.04	0.011	0.05	<0.1	0.04	3.7	<0.1	<0.05	5	<0.5	<0.2
1204155	Soil	47	1.81	91	0.077	1	2.61	0.007	0.10	<0.1	0.04	8.1	0.1	<0.05	8	<0.5	<0.2
1204156	Soil	30	0.86	88	0.053	1	1.50	0.013	0.04	<0.1	0.04	3.6	<0.1	<0.05	5	<0.5	<0.2
1204157	Soil	45	1.96	108	0.051	<1	2.38	0.006	0.08	<0.1	0.03	5.4	<0.1	<0.05	6	<0.5	<0.2
1204158	Soil	35	0.85	169	0.057	1	1.86	0.014	0.06	<0.1	0.04	4.6	<0.1	<0.05	5	<0.5	<0.2
1204159	Soil	59	1.26	159	0.082	<1	2.18	0.007	0.10	<0.1	0.02	5.0	0.2	<0.05	6	<0.5	<0.2
1204160	Soil	23	1.24	231	0.082	<1	1.88	0.005	0.54	<0.1	0.02	3.2	0.4	<0.05	6	<0.5	<0.2
1204161	Soil	24	0.80	101	0.100	<1	1.95	0.009	0.15	<0.1	0.03	2.8	0.2	<0.05	6	<0.5	<0.2
1204162	Soil	25	0.52	290	0.078	<1	1.71	0.010	0.12	<0.1	0.03	3.4	0.2	<0.05	6	<0.5	<0.2
1204163	Soil	27	1.65	128	0.147	<1	2.08	0.008	0.42	<0.1	0.01	4.6	0.4	<0.05	7	<0.5	<0.2
1204164	Soil	66	1.26	177	0.106	1	2.26	0.011	0.11	<0.1	0.04	4.7	0.3	<0.05	6	<0.5	<0.2
1204165	Soil	122	2.28	214	0.120	<1	2.62	0.008	0.19	<0.1	<0.01	6.4	0.3	<0.05	7	<0.5	<0.2
1204166	Soil	80	1.51	198	0.103	1	2.54	0.011	0.13	<0.1	0.03	5.9	0.3	<0.05	7	<0.5	<0.2
1204167	Soil	52	1.07	131	0.106	<1	2.01	0.010	0.10	0.1	0.03	3.1	0.2	<0.05	7	<0.5	<0.2
1204168	Soil	21	0.67	93	0.076	<1	1.26	0.013	0.11	<0.1	0.02	2.0	0.1	<0.05	5	<0.5	<0.2
1204169	Soil	52	1.13	138	0.101	<1	1.97	0.010	0.16	<0.1	0.03	3.4	0.2	<0.05	6	<0.5	<0.2
1204170	Soil	29	0.73	151	0.091	<1	1.68	0.014	0.09	<0.1	0.02	2.8	0.2	<0.05	5	<0.5	<0.2
1204171	Soil	90	1.42	153	0.099	<1	1.95	0.011	0.06	<0.1	0.02	3.5	0.1	<0.05	5	<0.5	<0.2
1204172	Soil	75	1.03	173	0.075	<1	1.95	0.010	0.07	0.1	0.02	4.7	0.2	<0.05	6	<0.5	<0.2
1204173	Soil	72	0.99	114	0.087	<1	1.60	0.010	0.09	<0.1	0.03	3.3	0.2	<0.05	5	<0.5	<0.2
1204174	Soil	60	1.22	168	0.091	<1	1.78	0.015	0.26	<0.1	0.04	3.5	0.3	<0.05	5	<0.5	<0.2
1204175	Soil	71	1.47	180	0.104	<1	1.95	0.009	0.43	<0.1	0.01	5.0	0.5	<0.05	6	<0.5	<0.2
1204176	Soil	41	0.85	247	0.068	<1	1.80	0.015	0.10	<0.1	0.05	4.0	0.2	<0.05	5	<0.5	<0.2
1204177	Soil	53	1.29	159	0.080	<1	2.06	0.010	0.08	<0.1	0.01	3.9	0.2	<0.05	5	<0.5	<0.2
1204178	Soil	54	1.00	113	0.056	<1	1.43	0.007	0.07	<0.1	0.02	3.1	<0.1	<0.05	4	<0.5	<0.2
1204179	Soil	86	1.57	131	0.063	<1	1.99	0.010	0.08	<0.1	0.02	4.5	0.1	<0.05	5	<0.5	<0.2
1204180	Soil	95	1.66	182	0.058	<1	2.16	0.010	0.08	<0.1	0.02	5.0	0.1	<0.05	6	<0.5	<0.2
1204181	Soil	57	1.14	122	0.049	<1	1.55	0.007	0.08	<0.1	0.01	3.2	0.1	<0.05	4	<0.5	<0.2
1204182	Soil	81	1.36	175	0.034	<1	2.19	0.007	0.06	<0.1	0.05	3.9	0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1204183	Soil		1.4	18.3	10.0	40	0.2	26.3	9.7	249	1.90	22.0	1.9	2.3	20	0.1	0.2	<0.1	41	0.23	0.042	11
1204184	Soil		0.4	32.7	8.8	37	<0.1	32.5	13.6	274	2.01	0.9	1.4	3.2	40	<0.1	0.1	<0.1	27	0.39	0.099	9
1204185	Soil		0.6	32.7	15.0	54	<0.1	60.1	17.3	419	2.65	1.7	1.9	7.6	28	<0.1	<0.1	0.1	32	0.35	0.081	20
1204186	Soil		0.3	24.8	7.3	31	<0.1	20.9	9.9	202	1.76	1.1	1.0	1.3	29	<0.1	<0.1	<0.1	26	0.30	0.078	6
1204187	Soil		0.5	34.4	8.2	47	<0.1	23.5	12.5	274	2.44	1.6	5.6	4.0	35	<0.1	0.2	<0.1	42	0.41	0.094	13
1204188	Soil		0.5	48.9	34.0	78	<0.1	70.2	18.6	529	3.70	3.8	1.7	12.7	19	0.1	0.2	0.3	55	0.32	0.063	35
1204189	Soil		2.6	25.4	18.0	59	<0.1	35.4	14.2	299	3.60	10.3	1.0	4.0	19	0.3	0.7	0.2	77	0.19	0.028	13
1204190	Soil		1.3	27.9	19.9	53	<0.1	26.8	12.4	277	3.12	7.4	3.1	7.8	19	0.1	0.5	0.2	62	0.18	0.034	12
1202751	Soil		0.6	19.3	7.0	44	<0.1	25.6	10.0	236	1.78	1.0	3.5	0.9	21	0.1	0.2	0.1	42	0.41	0.050	5
1202752	Soil		0.6	28.2	6.8	50	<0.1	34.7	14.7	554	2.18	1.2	9.2	1.3	30	<0.1	0.2	0.2	54	0.75	0.050	6
1202753	Soil		0.5	71.1	7.3	71	0.1	58.9	19.8	667	3.02	1.1	2.7	1.4	35	0.2	0.2	0.1	71	1.00	0.054	6
1202754	Soil		0.5	43.9	7.7	57	<0.1	38.4	15.2	475	2.45	4.0	3.9	1.6	36	0.1	0.3	0.1	65	0.88	0.057	6
1202755	Soil		0.6	55.1	15.9	94	0.1	37.3	17.6	345	3.00	5.8	5.6	2.6	33	<0.1	0.4	0.2	80	0.63	0.071	10
1202756	Soil		0.9	21.7	15.5	66	<0.1	37.1	14.3	374	3.21	7.5	3.7	2.2	24	<0.1	0.2	0.2	79	0.40	0.043	6
1202757	Soil		0.5	18.5	12.7	74	<0.1	22.8	11.8	324	1.99	4.4	2.8	1.9	28	0.1	0.2	0.1	54	0.56	0.067	7
1202758	Soil		1.0	33.8	15.6	100	0.1	25.5	21.1	737	3.86	5.1	2.8	2.8	43	0.1	0.2	0.1	101	1.03	0.153	9
1202760	Soil		1.5	34.7	24.8	98	0.1	29.1	16.6	626	2.76	6.0	3.5	4.2	32	0.4	0.2	0.2	56	0.50	0.067	17
1202272	Soil		1.3	48.7	21.0	54	0.4	15.1	8.1	193	4.22	12.0	23.0	5.0	12	0.2	0.3	0.5	45	0.07	0.057	27
1202279	Soil		2.2	22.1	15.4	51	<0.1	25.3	11.6	423	3.35	9.6	2.9	15.1	19	0.2	0.4	0.3	81	0.21	0.032	12
1202281	Soil		1.2	33.6	15.2	48	<0.1	29.9	12.9	371	3.22	10.7	6.4	7.6	26	0.2	0.4	0.2	80	0.30	0.017	13
1202282	Soil		1.9	21.3	13.4	50	<0.1	18.6	11.1	528	3.57	12.2	2.6	4.2	18	0.2	0.5	0.3	94	0.18	0.033	9
1202283	Soil		1.7	27.9	12.8	57	<0.1	29.8	10.8	266	2.61	6.8	3.8	10.9	32	0.2	0.3	0.2	68	0.43	0.062	26
1202284	Soil		0.6	36.1	6.6	60	<0.1	26.5	12.7	353	2.72	5.7	1.9	4.3	27	<0.1	0.2	0.1	69	0.38	0.041	14
1202285	Soil		0.7	38.6	5.4	76	<0.1	42.1	17.6	685	3.81	7.9	2.4	3.3	20	<0.1	0.3	0.1	102	0.30	0.036	9
1202286	Soil		1.1	43.3	7.7	75	<0.1	33.8	18.1	673	3.52	7.3	0.7	2.8	19	0.1	0.3	0.1	84	0.26	0.041	7
1204142	Soil		1.3	29.2	9.6	72	<0.1	27.8	11.8	598	2.95	8.8	2.2	0.9	24	0.2	0.5	0.2	67	0.32	0.060	8
1204143	Soil		0.8	40.4	11.0	75	0.2	25.8	14.4	408	3.05	7.5	3.7	4.0	25	0.3	0.5	0.2	69	0.41	0.083	17
1204144	Soil		0.7	29.2	10.0	58	0.1	21.4	10.2	283	2.62	6.2	4.5	3.1	26	0.1	0.4	0.2	66	0.39	0.060	14
1204145	Soil		0.7	23.7	11.5	57	<0.1	21.1	8.5	313	2.53	7.8	2.0	3.0	22	0.1	0.3	0.2	66	0.34	0.059	12
1204146	Soil		0.7	20.2	11.7	48	<0.1	19.8	7.1	217	1.97	5.7	6.8	3.5	21	0.2	0.3	0.1	56	0.34	0.050	19

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1204183	Soil	48	0.78	93	0.056	<1	1.38	0.015	0.03	0.1	0.03	2.6	<0.1	<0.05	5	<0.5	<0.2
1204184	Soil	69	1.16	104	0.046	<1	1.51	0.004	0.05	<0.1	<0.01	2.3	<0.1	<0.05	4	<0.5	<0.2
1204185	Soil	99	1.81	96	0.050	<1	2.01	0.006	0.06	<0.1	0.01	3.0	0.1	<0.05	6	<0.5	<0.2
1204186	Soil	38	0.86	76	0.053	<1	1.28	0.005	0.05	<0.1	<0.01	1.4	<0.1	<0.05	4	0.7	<0.2
1204187	Soil	40	1.10	137	0.064	<1	1.87	0.006	0.06	<0.1	0.01	4.5	<0.1	<0.05	5	<0.5	<0.2
1204188	Soil	131	2.23	119	0.098	<1	2.93	0.007	0.15	<0.1	0.03	4.7	0.4	<0.05	8	<0.5	<0.2
1204189	Soil	39	0.48	164	0.097	<1	2.25	0.013	0.06	<0.1	<0.01	3.7	0.1	<0.05	7	<0.5	<0.2
1204190	Soil	37	0.54	135	0.096	<1	2.54	0.011	0.07	0.1	0.05	3.3	0.2	<0.05	6	<0.5	<0.2
1202751	Soil	47	0.80	90	0.062	<1	1.46	0.018	0.04	0.1	0.05	2.3	<0.1	<0.05	5	<0.5	<0.2
1202752	Soil	66	1.11	124	0.067	<1	1.74	0.022	0.04	<0.1	0.06	2.6	<0.1	<0.05	5	0.7	<0.2
1202753	Soil	147	2.26	156	0.060	<1	2.44	0.018	0.04	<0.1	0.04	4.8	<0.1	<0.05	6	<0.5	<0.2
1202754	Soil	88	1.32	120	0.078	3	1.71	0.021	0.04	<0.1	0.04	3.7	<0.1	<0.05	4	<0.5	<0.2
1202755	Soil	75	1.55	150	0.101	2	2.05	0.020	0.05	0.1	0.06	4.9	0.1	<0.05	6	<0.5	<0.2
1202756	Soil	99	1.45	97	0.061	2	1.76	0.012	0.04	<0.1	0.04	3.3	<0.1	<0.05	5	<0.5	<0.2
1202757	Soil	47	0.92	92	0.069	2	1.23	0.020	0.04	0.1	0.04	2.9	<0.1	<0.05	4	<0.5	<0.2
1202758	Soil	39	1.48	329	0.139	2	1.90	0.019	0.30	0.1	0.03	4.1	0.2	<0.05	7	<0.5	<0.2
1202760	Soil	46	1.17	129	0.074	2	1.69	0.014	0.08	<0.1	0.04	3.6	<0.1	<0.05	5	<0.5	<0.2
1202272	Soil	21	0.26	69	0.037	<1	0.94	0.030	0.09	<0.1	0.02	3.9	0.1	0.18	3	0.5	<0.2
1202279	Soil	40	0.50	339	0.145	2	2.12	0.014	0.05	<0.1	0.03	3.7	<0.1	<0.05	6	<0.5	<0.2
1202281	Soil	46	0.65	259	0.138	1	2.73	0.018	0.05	<0.1	0.03	5.2	<0.1	<0.05	6	<0.5	<0.2
1202282	Soil	36	0.43	168	0.120	2	1.73	0.017	0.04	<0.1	0.03	2.9	<0.1	<0.05	8	<0.5	<0.2
1202283	Soil	44	0.61	315	0.134	2	1.84	0.024	0.07	0.1	0.03	5.0	<0.1	<0.05	5	<0.5	<0.2
1202284	Soil	46	1.07	190	0.147	1	1.97	0.020	0.06	<0.1	0.02	3.9	<0.1	<0.05	5	<0.5	<0.2
1202285	Soil	70	1.95	243	0.215	1	2.94	0.017	0.42	<0.1	0.01	4.0	0.2	<0.05	7	<0.5	<0.2
1202286	Soil	48	1.64	187	0.184	<1	2.68	0.012	0.40	<0.1	0.02	3.2	0.2	<0.05	7	<0.5	<0.2
1204142	Soil	37	0.58	133	0.081	1	1.75	0.018	0.07	0.1	0.05	2.8	<0.1	<0.05	6	<0.5	<0.2
1204143	Soil	38	0.70	153	0.112	2	2.05	0.020	0.06	0.1	0.04	4.8	<0.1	<0.05	6	<0.5	<0.2
1204144	Soil	39	0.61	190	0.096	2	1.95	0.020	0.07	<0.1	0.04	4.9	<0.1	<0.05	5	<0.5	<0.2
1204145	Soil	34	0.52	133	0.109	1	1.69	0.017	0.08	0.1	0.03	3.4	<0.1	<0.05	5	<0.5	<0.2
1204146	Soil	33	0.53	161	0.108	<1	1.61	0.017	0.08	0.1	0.04	3.5	<0.1	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1204147	Soil	0.7	21.5	13.7	48	<0.1	19.2	7.7	276	2.24	7.1	6.3	4.3	21	0.1	0.3	0.3	57	0.29	0.039	23
1204148	Soil	0.5	7.3	4.0	19	<0.1	5.0	2.5	103	0.97	4.1	0.6	0.1	9	<0.1	0.2	<0.1	24	0.09	0.038	3
1204149	Soil	1.2	23.5	12.2	73	<0.1	25.3	13.3	588	3.43	8.5	8.9	2.9	18	0.2	0.4	0.2	83	0.25	0.044	23
1204150	Soil	0.8	21.7	6.4	50	<0.1	19.7	8.7	297	2.38	7.0	2.7	2.6	22	0.1	0.3	0.1	65	0.32	0.050	16
1204151	Soil	0.9	33.5	24.1	55	<0.1	41.5	14.3	378	3.20	7.5	5.4	4.0	16	<0.1	0.3	0.2	78	0.25	0.057	13
1204152	Soil	1.1	33.1	19.3	62	<0.1	38.2	14.9	557	3.55	8.3	3.8	4.3	19	0.2	0.3	0.2	89	0.26	0.042	13
1203660	Soil	1.0	15.7	11.1	53	<0.1	20.0	9.5	364	2.49	8.3	11.6	2.7	21	0.2	0.4	0.2	70	0.31	0.051	10
1203661	Soil	1.3	21.7	7.9	45	<0.1	20.8	9.3	330	2.63	7.5	7.3	1.8	21	0.2	0.4	0.1	77	0.31	0.056	10
1203662	Soil	1.1	20.9	10.6	53	<0.1	24.5	10.3	420	2.60	8.2	4.7	3.3	20	0.3	0.4	0.1	73	0.27	0.048	14
1203663	Soil	1.5	21.7	16.3	53	0.1	23.7	14.0	225	3.04	9.8	4.0	4.1	20	<0.1	0.4	0.2	69	0.27	0.082	26
1203664	Soil	0.6	17.5	7.9	63	<0.1	32.8	15.2	339	2.68	5.1	3.5	1.7	21	0.1	0.3	0.1	67	0.34	0.058	7
1203665	Soil	1.2	15.1	10.2	61	<0.1	28.2	14.2	474	2.60	6.2	4.4	2.8	25	<0.1	0.3	0.2	71	0.43	0.066	8
1203666	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203667	Soil	1.2	25.4	9.4	61	<0.1	32.0	13.7	383	2.92	7.1	2.6	6.0	25	0.1	0.3	0.2	81	0.38	0.060	14
1203668	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203669	Soil	2.5	47.5	22.3	65	0.2	31.7	13.2	524	3.42	8.4	6.3	9.9	21	0.2	0.4	0.3	79	0.26	0.087	35
1203670	Soil	0.9	26.7	12.7	140	<0.1	42.5	16.9	1378	5.19	5.5	0.6	31.6	31	<0.1	0.1	0.6	69	0.24	0.069	70
1202761	Soil	0.8	39.1	10.3	66	0.1	24.9	11.8	326	2.85	4.3	4.6	4.0	23	0.1	0.2	0.1	55	0.38	0.067	14
1202762	Soil	0.7	42.6	10.5	64	0.1	24.8	11.5	293	2.67	4.5	4.4	3.1	20	0.1	0.2	0.1	49	0.32	0.066	14
1202763	Soil	0.8	41.3	11.0	63	0.1	25.0	10.4	266	2.53	4.0	3.8	3.6	22	0.1	0.2	0.1	48	0.36	0.061	14
1202764	Soil	0.8	28.4	11.6	57	<0.1	21.7	9.6	242	2.26	3.6	2.7	3.3	18	0.1	0.1	0.1	45	0.29	0.060	12
1202765	Soil	0.7	30.7	12.5	63	<0.1	22.9	10.1	260	2.42	4.4	4.3	4.7	20	0.1	0.1	0.1	48	0.30	0.056	14
1202766	Soil	1.5	31.9	17.7	64	<0.1	25.8	9.5	276	2.43	5.2	2.3	6.0	19	<0.1	0.2	0.1	45	0.30	0.050	17
1202767	Soil	1.3	30.6	17.4	60	0.1	24.8	9.6	262	2.52	7.2	12.4	7.6	19	0.1	0.2	0.1	46	0.28	0.043	18
1202768	Soil	0.9	25.5	12.9	64	0.1	22.6	9.7	356	2.41	6.7	3.9	5.0	21	0.1	0.2	0.1	44	0.32	0.053	16
1202769	Soil	0.6	27.0	10.0	60	0.1	25.3	9.9	284	2.42	3.6	3.1	5.2	24	<0.1	0.1	0.1	42	0.39	0.076	16
1202770	Soil	0.4	11.8	3.5	12	<0.1	4.4	1.9	54	0.60	0.6	<0.5	<0.1	8	<0.1	<0.1	<0.1	14	0.09	0.034	5
1203201	Soil	1.2	28.1	23.4	52	0.1	29.6	9.3	220	2.52	5.0	1.8	7.1	23	<0.1	0.2	0.1	55	0.26	0.058	15
1203202	Soil	1.0	22.8	25.2	55	<0.1	21.6	8.2	273	2.16	3.8	4.2	8.2	17	0.2	0.1	0.2	43	0.22	0.040	18
1203203	Soil	1.0	33.9	21.8	72	<0.1	25.9	11.9	510	2.85	4.1	2.6	11.2	14	0.1	0.2	0.3	50	0.22	0.047	24

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1204147	Soil	31	0.47	239	0.094	<1	1.50	0.018	0.11	0.1	0.03	3.4	<0.1	<0.05	4	<0.5	<0.2
1204148	Soil	11	0.13	38	0.042	<1	0.65	0.026	0.03	<0.1	0.02	0.6	<0.1	<0.05	3	<0.5	<0.2
1204149	Soil	43	0.63	155	0.103	2	1.81	0.013	0.14	0.1	0.05	3.5	<0.1	<0.05	6	<0.5	<0.2
1204150	Soil	33	0.47	98	0.119	2	1.44	0.021	0.06	<0.1	0.03	2.9	<0.1	<0.05	4	<0.5	<0.2
1204151	Soil	68	1.26	84	0.109	1	2.30	0.011	0.06	<0.1	0.02	4.7	<0.1	<0.05	7	<0.5	<0.2
1204152	Soil	69	1.13	123	0.104	2	2.45	0.011	0.06	<0.1	0.02	6.3	<0.1	<0.05	7	<0.5	<0.2
1203660	Soil	33	0.48	104	0.112	1	1.43	0.017	0.07	0.1	0.05	2.7	<0.1	<0.05	5	<0.5	<0.2
1203661	Soil	34	0.48	108	0.124	<1	1.48	0.016	0.05	0.1	0.03	2.7	<0.1	<0.05	5	<0.5	<0.2
1203662	Soil	35	0.45	126	0.114	2	1.56	0.018	0.06	0.1	0.05	3.0	<0.1	<0.05	5	<0.5	<0.2
1203663	Soil	39	0.49	248	0.065	<1	2.07	0.014	0.07	0.1	0.08	4.5	0.1	<0.05	6	0.5	<0.2
1203664	Soil	59	1.44	109	0.128	1	2.22	0.011	0.05	0.1	0.04	2.8	<0.1	<0.05	6	<0.5	<0.2
1203665	Soil	55	1.04	134	0.145	2	1.89	0.020	0.06	0.2	0.05	3.1	<0.1	0.05	6	<0.5	<0.2
1203666	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203667	Soil	56	0.89	106	0.145	2	1.73	0.024	0.07	0.2	0.04	3.4	<0.1	<0.05	5	<0.5	<0.2
1203668	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
1203669	Soil	57	0.85	154	0.102	<1	1.98	0.024	0.14	0.1	0.08	3.0	0.1	0.15	6	<0.5	<0.2
1203670	Soil	85	3.43	455	0.212	2	3.50	0.021	1.59	0.2	0.02	5.3	1.1	0.19	10	<0.5	<0.2
1202761	Soil	37	0.95	163	0.068	<1	1.72	0.015	0.06	0.1	0.03	4.1	<0.1	0.05	5	0.9	<0.2
1202762	Soil	37	1.04	161	0.058	<1	1.84	0.011	0.05	<0.1	0.02	4.2	<0.1	0.06	5	0.7	<0.2
1202763	Soil	38	1.04	174	0.064	<1	1.76	0.014	0.06	<0.1	0.02	4.1	<0.1	<0.05	5	0.7	<0.2
1202764	Soil	33	0.89	135	0.062	<1	1.61	0.010	0.07	<0.1	0.02	3.2	<0.1	<0.05	5	<0.5	<0.2
1202765	Soil	34	0.90	150	0.068	<1	1.72	0.010	0.07	<0.1	0.02	3.6	<0.1	<0.05	5	<0.5	<0.2
1202766	Soil	38	0.90	133	0.060	<1	1.52	0.008	0.07	<0.1	0.02	3.7	<0.1	<0.05	5	0.6	<0.2
1202767	Soil	36	0.82	144	0.063	<1	1.67	0.009	0.06	<0.1	0.02	3.3	<0.1	<0.05	5	<0.5	<0.2
1202768	Soil	32	0.85	141	0.065	<1	1.65	0.011	0.07	0.1	0.02	3.4	<0.1	<0.05	5	<0.5	<0.2
1202769	Soil	33	0.91	136	0.069	<1	1.56	0.009	0.14	<0.1	0.02	3.3	<0.1	<0.05	5	<0.5	<0.2
1202770	Soil	9	0.12	39	0.021	<1	0.49	0.020	0.02	<0.1	0.03	0.6	<0.1	<0.05	2	<0.5	<0.2
1203201	Soil	47	0.81	126	0.085	<1	1.61	0.010	0.08	0.1	0.02	2.4	0.2	<0.05	6	<0.5	<0.2
1203202	Soil	30	0.74	116	0.064	<1	1.45	0.008	0.06	<0.1	<0.01	2.6	<0.1	<0.05	5	<0.5	<0.2
1203203	Soil	38	1.14	122	0.062	<1	1.95	0.008	0.07	<0.1	0.01	3.5	0.1	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203204	Soil		1.6	33.2	22.5	63	0.2	23.0	10.8	704	2.71	5.1	3.9	8.6	22	0.1	0.2	0.2	50	0.29	0.044	31
1203205	Soil		1.2	37.7	19.4	68	<0.1	28.6	11.4	433	2.76	2.6	2.1	10.3	17	0.1	0.1	0.2	50	0.22	0.035	25
1203206	Soil		1.1	32.3	16.2	74	0.1	26.6	11.2	403	2.82	3.6	8.6	8.1	22	<0.1	0.2	0.2	50	0.34	0.055	20
1203207	Soil		0.7	35.3	11.7	60	<0.1	33.6	11.9	357	2.49	2.2	5.3	5.6	24	<0.1	0.1	0.1	43	0.37	0.079	15
1203208	Soil		0.8	34.4	14.5	60	0.2	27.8	11.0	330	2.42	2.6	4.3	5.2	26	0.1	0.2	0.1	39	0.40	0.090	16
1203209	Soil		1.0	33.3	15.4	61	0.2	33.0	10.7	339	2.72	2.6	3.7	4.7	24	0.2	0.1	0.2	50	0.41	0.072	17
1203210	Soil		0.6	25.0	14.7	63	<0.1	24.9	10.0	347	2.47	3.0	1.4	6.8	23	<0.1	0.1	0.1	44	0.37	0.066	19
1202771	Soil		1.0	32.8	12.4	63	<0.1	22.6	10.3	372	2.94	6.0	4.1	3.4	13	<0.1	0.3	0.1	63	0.19	0.035	11
1202772	Soil		0.7	17.8	8.2	30	<0.1	11.7	5.8	304	1.33	1.6	3.5	0.9	11	0.1	0.2	<0.1	30	0.16	0.026	6
1202773	Soil		0.9	42.0	26.9	87	0.2	28.1	12.8	538	2.92	4.4	5.8	2.4	15	0.2	0.2	<0.1	60	0.31	0.047	12
1202774	Soil		0.9	28.2	9.5	52	0.1	21.1	10.1	410	2.61	4.0	1.3	1.4	15	0.2	0.2	0.1	56	0.27	0.043	8
1202775	Soil		0.7	49.6	9.9	85	0.1	24.0	14.6	695	2.95	2.6	1.5	1.9	17	0.1	0.1	<0.1	63	0.38	0.043	12
1202776	Soil		0.7	45.0	14.4	84	<0.1	37.0	14.2	571	3.14	3.3	4.2	5.2	16	<0.1	0.1	0.1	62	0.36	0.040	14
1202777	Soil		0.7	35.0	13.0	69	<0.1	35.5	14.7	552	3.12	3.8	8.1	4.4	21	<0.1	0.1	0.1	63	0.43	0.056	12
1202778	Soil		0.5	37.4	8.4	67	<0.1	29.7	14.4	497	2.78	1.8	0.8	3.7	25	<0.1	0.1	<0.1	47	0.59	0.115	15
1202779	Soil		0.7	37.7	14.8	70	0.1	36.3	14.5	518	2.71	2.3	1.5	4.0	27	<0.1	0.1	<0.1	48	0.58	0.093	18
1202780	Soil		0.8	31.1	20.0	75	0.1	27.9	13.0	554	2.47	2.2	4.9	3.3	29	0.2	0.1	0.2	46	0.55	0.081	15
1202781	Soil		1.1	24.9	24.6	69	0.2	19.7	9.6	481	2.31	2.2	1.3	8.5	26	<0.1	<0.1	0.3	34	0.41	0.058	27
1202782	Soil		1.1	18.4	18.0	49	0.1	17.4	7.6	318	2.19	3.7	6.6	6.4	19	0.1	0.2	0.2	43	0.27	0.046	22
1202783	Soil		1.2	21.4	21.9	57	0.1	19.0	8.7	456	2.41	3.5	<0.5	8.7	24	<0.1	0.2	0.2	44	0.35	0.049	38
1202784	Soil		0.8	18.3	21.6	59	0.1	20.2	7.8	357	2.19	2.7	1.8	9.5	20	0.1	0.2	0.2	36	0.29	0.057	35
1202785	Soil		0.9	20.3	24.4	68	0.1	29.8	9.5	408	2.39	1.9	0.6	10.1	23	0.1	0.1	0.2	38	0.35	0.058	39
1202786	Soil		0.7	23.4	30.6	72	0.1	27.7	12.8	573	2.68	2.1	<0.5	10.1	25	0.1	0.2	0.4	51	0.33	0.053	35
1202787	Soil		1.1	20.5	22.0	59	0.1	23.5	9.4	455	2.41	2.1	0.7	9.1	25	<0.1	0.2	0.3	47	0.34	0.048	35
1202788	Soil		0.7	16.6	18.8	52	<0.1	20.3	7.6	243	2.24	2.8	<0.5	9.1	17	<0.1	0.2	0.2	50	0.23	0.027	22
1202789	Soil		1.0	22.8	24.8	73	0.1	27.7	10.7	578	2.60	4.6	4.3	8.0	23	0.2	0.2	0.4	52	0.33	0.052	28
1202790	Soil		0.9	18.5	26.0	65	0.1	22.3	10.6	461	2.13	2.5	<0.5	9.4	29	0.2	0.1	0.3	46	0.38	0.033	26
1203231	Soil		1.4	17.6	10.9	41	0.2	15.5	6.8	398	2.20	5.5	1.1	1.5	20	<0.1	0.3	0.2	57	0.30	0.047	16
1203232	Soil		0.8	20.9	8.0	51	<0.1	22.0	9.9	440	2.81	6.9	2.8	3.1	20	0.1	0.3	0.1	67	0.30	0.049	13
1203233	Soil		1.4	17.6	10.7	48	<0.1	20.4	8.4	387	2.53	6.8	2.0	2.3	21	0.2	0.3	0.3	66	0.30	0.034	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203204	Soil	35	0.69	205	0.045	<1	1.89	0.011	0.06	<0.1	0.06	3.6	<0.1	<0.05	6	<0.5	<0.2
1203205	Soil	42	1.20	139	0.071	<1	1.82	0.008	0.14	0.1	0.02	3.9	0.2	<0.05	5	<0.5	<0.2
1203206	Soil	40	1.23	141	0.081	<1	1.94	0.009	0.15	<0.1	0.02	3.9	0.2	<0.05	6	<0.5	<0.2
1203207	Soil	44	1.28	122	0.083	<1	1.69	0.007	0.23	<0.1	0.01	3.4	0.2	<0.05	5	<0.5	<0.2
1203208	Soil	37	0.96	152	0.074	<1	1.60	0.008	0.21	<0.1	0.03	2.9	0.1	<0.05	5	<0.5	<0.2
1203209	Soil	50	1.22	165	0.070	<1	1.94	0.008	0.26	<0.1	0.05	4.5	0.2	<0.05	6	<0.5	<0.2
1203210	Soil	33	0.97	124	0.082	<1	1.54	0.009	0.18	<0.1	<0.01	3.3	0.1	<0.05	5	<0.5	<0.2
1202771	Soil	36	0.80	101	0.070	<1	2.03	0.009	0.04	<0.1	0.02	4.0	<0.1	<0.05	6	0.5	<0.2
1202772	Soil	18	0.34	83	0.042	<1	0.96	0.017	0.03	<0.1	0.01	1.9	<0.1	<0.05	4	<0.5	<0.2
1202773	Soil	40	1.04	162	0.053	<1	2.12	0.010	0.04	<0.1	0.07	5.6	<0.1	<0.05	5	<0.5	<0.2
1202774	Soil	33	0.76	148	0.051	<1	1.85	0.012	0.04	<0.1	0.04	3.5	<0.1	<0.05	6	<0.5	<0.2
1202775	Soil	42	1.51	152	0.064	<1	2.17	0.010	0.10	<0.1	0.02	4.4	0.1	<0.05	6	<0.5	<0.2
1202776	Soil	64	1.67	140	0.088	<1	2.40	0.010	0.16	<0.1	0.01	4.9	0.3	<0.05	7	<0.5	<0.2
1202777	Soil	52	1.50	175	0.095	<1	2.22	0.009	0.16	<0.1	0.02	4.5	0.2	<0.05	6	<0.5	<0.2
1202778	Soil	34	1.33	233	0.069	<1	1.78	0.008	0.31	<0.1	0.01	3.3	0.2	<0.05	6	0.6	<0.2
1202779	Soil	44	1.28	245	0.070	<1	1.74	0.009	0.21	<0.1	0.03	3.5	0.2	<0.05	6	<0.5	<0.2
1202780	Soil	35	1.12	244	0.065	<1	1.60	0.012	0.14	<0.1	0.03	3.0	0.1	<0.05	5	<0.5	<0.2
1202781	Soil	26	0.87	213	0.062	<1	1.42	0.009	0.20	<0.1	<0.01	3.0	0.2	<0.05	5	<0.5	<0.2
1202782	Soil	25	0.57	189	0.066	<1	1.40	0.011	0.11	<0.1	0.01	2.4	<0.1	<0.05	5	<0.5	<0.2
1202783	Soil	28	0.60	325	0.053	<1	1.59	0.011	0.13	0.1	0.04	3.1	0.2	<0.05	5	<0.5	<0.2
1202784	Soil	26	0.79	219	0.058	<1	1.47	0.009	0.23	<0.1	0.02	2.8	0.2	<0.05	5	<0.5	<0.2
1202785	Soil	38	1.12	283	0.069	<1	1.61	0.010	0.30	<0.1	0.03	3.4	0.3	<0.05	6	0.7	<0.2
1202786	Soil	39	1.18	224	0.088	2	1.79	0.009	0.22	<0.1	0.03	3.4	0.2	<0.05	6	0.5	<0.2
1202787	Soil	34	0.82	222	0.070	2	1.60	0.010	0.13	0.1	0.04	3.0	0.1	<0.05	5	<0.5	<0.2
1202788	Soil	27	0.73	124	0.079	<1	1.57	0.009	0.09	<0.1	0.03	2.2	0.1	<0.05	5	0.6	<0.2
1202789	Soil	38	0.91	197	0.076	2	1.70	0.010	0.12	<0.1	0.05	3.3	0.2	<0.05	6	0.5	<0.2
1202790	Soil	32	0.75	225	0.066	<1	1.47	0.011	0.10	<0.1	0.04	2.4	<0.1	<0.05	5	<0.5	<0.2
1203231	Soil	26	0.33	265	0.051	<1	1.47	0.012	0.05	0.1	0.03	2.5	<0.1	<0.05	6	0.8	<0.2
1203232	Soil	33	0.51	260	0.078	2	2.05	0.011	0.06	0.1	0.04	3.6	<0.1	<0.05	6	<0.5	<0.2
1203233	Soil	34	0.43	269	0.084	1	1.78	0.012	0.08	<0.1	0.02	2.8	<0.1	<0.05	6	0.7	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

		Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
		Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
		Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
		MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1203234	Soil		1.0	19.5	9.1	42	<0.1	21.4	9.0	343	2.62	5.9	5.8	2.6	18	<0.1	0.3	0.1	67	0.26	0.030	10
1203235	Soil		1.0	21.7	7.6	44	<0.1	24.2	10.0	331	2.76	6.8	2.6	3.9	16	0.1	0.4	0.1	69	0.22	0.032	9
1203236	Soil		0.8	23.4	8.1	47	<0.1	24.7	11.7	387	2.98	7.7	4.4	3.7	18	<0.1	0.3	0.1	74	0.25	0.039	10
1203237	Soil		1.0	18.6	8.9	44	<0.1	21.7	11.2	438	2.75	5.5	1.0	3.1	17	<0.1	0.3	0.1	69	0.24	0.039	10
1203238	Soil		0.9	17.0	10.0	45	<0.1	20.4	10.8	481	2.63	5.1	1.6	3.6	20	<0.1	0.2	0.1	66	0.33	0.042	11
1203239	Soil		1.3	17.4	9.2	49	<0.1	21.5	10.2	455	2.92	6.4	2.2	3.0	16	0.1	0.3	0.1	76	0.22	0.033	9
1203240	Soil		0.8	23.7	8.2	38	0.2	18.7	8.3	335	2.46	4.3	<0.5	1.8	26	0.1	0.3	0.2	58	0.42	0.050	19
1203241	Soil		0.9	16.0	7.3	44	<0.1	17.1	8.0	431	2.16	3.1	1.5	3.2	19	<0.1	0.2	<0.1	52	0.33	0.041	12
1203242	Soil		0.9	16.4	9.1	44	<0.1	18.7	8.1	369	2.26	3.9	0.5	3.2	20	<0.1	0.2	0.1	57	0.33	0.043	12
1203243	Soil		1.0	17.4	9.0	43	<0.1	21.9	9.0	359	2.55	4.2	<0.5	3.5	21	<0.1	0.2	<0.1	66	0.35	0.035	11
1203244	Soil		0.7	18.3	6.8	47	<0.1	19.6	8.4	336	2.41	3.3	3.4	3.0	20	<0.1	0.2	<0.1	60	0.33	0.039	10
1203245	Soil		0.8	19.3	9.4	50	<0.1	22.2	9.7	337	2.47	2.8	0.5	2.9	18	0.1	0.2	<0.1	54	0.30	0.035	9
1203246	Soil		0.7	22.1	6.7	46	<0.1	21.4	9.1	357	2.48	3.2	<0.5	3.1	20	<0.1	0.2	<0.1	57	0.35	0.042	10
1203247	Soil		1.0	27.4	10.8	69	<0.1	20.3	10.7	348	2.43	3.1	5.6	3.1	20	0.3	0.2	<0.1	55	0.34	0.037	10
1203248	Soil		0.9	30.8	7.4	57	<0.1	24.7	10.9	354	2.63	3.2	<0.5	2.5	20	0.1	0.2	<0.1	59	0.36	0.045	10
1203249	Soil		0.9	24.6	8.8	55	0.1	21.4	10.7	376	2.72	4.3	1.5	2.1	22	0.1	0.2	<0.1	64	0.39	0.048	10
1203250	Soil		1.4	28.6	9.6	67	<0.1	27.7	13.1	510	3.01	5.4	3.6	2.5	22	0.2	0.2	0.1	73	0.41	0.039	10
1202791	Soil		0.7	20.9	21.0	63	0.2	24.2	8.6	278	2.32	2.9	3.6	8.2	23	0.1	0.2	0.2	49	0.30	0.040	24
1202792	Soil		1.1	20.4	8.1	51	<0.1	23.6	11.3	428	2.53	2.5	<0.5	1.7	19	0.1	0.2	<0.1	56	0.39	0.047	7
1202793	Soil		1.0	25.7	9.4	61	0.1	23.6	10.7	377	3.05	4.8	0.6	2.0	21	0.1	0.2	<0.1	74	0.35	0.042	8
1202794	Soil		0.9	21.5	6.3	55	<0.1	25.3	13.5	489	3.15	2.9	<0.5	2.0	18	<0.1	0.2	<0.1	67	0.37	0.037	6
1202795	Soil		0.7	29.8	7.5	56	<0.1	23.2	11.5	384	2.76	2.8	<0.5	1.9	18	0.1	0.1	<0.1	61	0.34	0.038	7
1202796	Soil		0.7	45.3	6.4	59	0.1	26.3	14.4	570	2.88	2.6	0.7	3.2	20	0.1	0.2	0.1	55	0.40	0.048	17
1202797	Soil		0.8	41.4	6.0	56	0.1	24.2	14.3	793	2.70	3.7	3.5	2.2	26	0.2	0.2	0.1	55	0.55	0.060	16
1202798	Soil		1.1	32.9	8.6	76	0.1	24.0	13.3	531	2.27	2.8	8.6	1.6	43	0.6	0.2	0.1	52	0.91	0.063	35
1202799	Soil		0.6	20.7	5.5	51	<0.1	17.0	13.0	617	2.32	2.1	2.9	1.7	27	0.1	0.2	0.1	53	0.64	0.054	7
1202233	Soil		0.5	28.4	8.7	59	<0.1	24.8	12.2	258	2.63	3.5	5.1	5.1	24	0.2	0.3	<0.1	70	0.39	0.068	18
1202237	Soil		3.4	44.4	26.7	161	<0.1	51.2	29.1	1534	5.02	26.3	1.5	13.9	16	0.5	2.2	0.2	69	0.09	0.071	38
1202636	Soil		2.7	46.8	11.8	125	0.1	49.6	16.1	506	3.63	38.9	2.9	3.0	18	0.4	0.7	0.2	94	0.20	0.062	14
1202638	Soil		0.9	27.9	9.0	47	<0.1	25.5	9.3	194	2.80	5.2	3.9	4.6	18	0.1	0.2	0.1	57	0.20	0.062	19

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1203234	Soil	32	0.45	218	0.083	<1	1.79	0.013	0.05	<0.1	0.03	3.1	<0.1	<0.05	6	0.7	<0.2
1203235	Soil	34	0.54	171	0.097	2	2.15	0.011	0.04	<0.1	0.04	3.3	<0.1	<0.05	6	<0.5	<0.2
1203236	Soil	37	0.57	170	0.098	2	2.34	0.011	0.04	<0.1	0.04	3.8	<0.1	<0.05	6	<0.5	<0.2
1203237	Soil	33	0.52	170	0.088	<1	1.94	0.010	0.04	0.1	0.02	3.4	<0.1	<0.05	6	<0.5	<0.2
1203238	Soil	32	0.51	263	0.083	<1	1.93	0.011	0.04	<0.1	0.02	3.0	<0.1	<0.05	6	0.7	<0.2
1203239	Soil	32	0.48	174	0.098	2	1.93	0.012	0.05	0.1	0.04	2.9	<0.1	<0.05	7	<0.5	<0.2
1203240	Soil	28	0.37	383	0.054	<1	1.97	0.014	0.04	0.1	0.06	3.3	<0.1	<0.05	6	1.1	<0.2
1203241	Soil	28	0.48	232	0.068	<1	1.55	0.012	0.03	<0.1	0.02	2.7	<0.1	<0.05	5	<0.5	<0.2
1203242	Soil	31	0.50	228	0.082	<1	1.66	0.012	0.04	0.1	0.04	3.0	<0.1	<0.05	5	0.5	<0.2
1203243	Soil	37	0.54	240	0.096	1	1.96	0.014	0.05	<0.1	0.03	3.6	<0.1	<0.05	5	<0.5	<0.2
1203244	Soil	31	0.54	191	0.084	1	1.75	0.012	0.04	<0.1	0.03	3.1	<0.1	<0.05	5	0.9	<0.2
1203245	Soil	35	0.78	161	0.077	<1	1.79	0.011	0.04	<0.1	0.03	2.9	<0.1	<0.05	5	<0.5	<0.2
1203246	Soil	36	0.78	170	0.082	1	1.74	0.011	0.03	<0.1	0.03	3.6	<0.1	<0.05	5	0.6	<0.2
1203247	Soil	34	0.88	166	0.083	<1	1.78	0.010	0.05	<0.1	0.03	3.4	<0.1	<0.05	5	<0.5	<0.2
1203248	Soil	39	0.89	173	0.081	<1	1.90	0.012	0.05	<0.1	0.05	4.0	<0.1	<0.05	5	0.6	<0.2
1203249	Soil	35	0.79	182	0.083	<1	1.95	0.011	0.04	0.1	0.05	3.6	<0.1	<0.05	6	0.9	<0.2
1203250	Soil	46	0.79	203	0.086	1	2.15	0.015	0.05	0.1	0.06	4.1	<0.1	<0.05	6	0.6	<0.2
1202791	Soil	35	0.76	173	0.083	<1	1.69	0.010	0.09	0.1	0.04	2.9	0.1	<0.05	6	0.9	<0.2
1202792	Soil	37	1.00	126	0.082	<1	1.80	0.011	0.05	<0.1	0.04	2.8	<0.1	<0.05	6	0.7	<0.2
1202793	Soil	37	0.88	151	0.090	<1	2.07	0.011	0.06	0.1	0.04	3.4	<0.1	<0.05	7	0.9	<0.2
1202794	Soil	40	1.23	123	0.091	<1	2.22	0.010	0.05	<0.1	0.04	3.3	<0.1	<0.05	7	<0.5	<0.2
1202795	Soil	36	1.00	125	0.084	<1	1.86	0.011	0.04	0.1	0.07	3.1	<0.1	<0.05	5	<0.5	<0.2
1202796	Soil	39	1.39	154	0.054	<1	2.20	0.011	0.04	0.1	0.09	4.4	<0.1	<0.05	6	0.6	<0.2
1202797	Soil	32	1.06	170	0.049	<1	2.01	0.012	0.04	0.1	0.14	4.2	<0.1	<0.05	6	<0.5	<0.2
1202798	Soil	31	0.72	212	0.053	<1	1.72	0.014	0.05	0.1	0.05	3.4	<0.1	<0.05	4	0.6	<0.2
1202799	Soil	28	0.86	114	0.061	<1	1.59	0.014	0.03	<0.1	0.06	3.3	<0.1	<0.05	5	0.7	<0.2
1202233	Soil	36	0.50	218	0.109	<1	1.60	0.019	0.10	0.1	0.04	5.5	<0.1	<0.05	5	0.6	<0.2
1202237	Soil	38	0.15	135	0.005	1	1.38	0.005	0.05	<0.1	0.02	4.6	0.2	<0.05	4	0.7	<0.2
1202636	Soil	60	0.76	318	0.076	1	2.12	0.009	0.15	0.1	0.02	3.4	0.1	<0.05	7	1.0	<0.2
1202638	Soil	41	0.64	171	0.078	<1	1.85	0.010	0.16	<0.1	0.02	2.8	0.1	<0.05	7	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
1202639	Soil	0.6	25.7	5.0	55	<0.1	17.6	13.7	332	3.04	4.3	1.5	2.2	17	<0.1	0.2	<0.1	76	0.25	0.045	6
1202642	Soil	0.6	26.7	3.5	85	<0.1	15.0	20.6	554	3.82	2.3	2.5	6.0	21	<0.1	<0.1	<0.1	76	0.34	0.081	15
1203211	Soil	0.6	24.0	9.9	49	0.1	21.0	9.0	245	2.33	4.1	4.1	3.5	24	<0.1	0.2	0.1	46	0.37	0.055	14
1203212	Soil	1.9	20.4	17.5	53	<0.1	23.5	9.3	297	2.55	6.0	22.4	17.3	16	0.2	0.3	0.3	68	0.25	0.049	21
1203213	Soil	2.2	21.1	20.7	52	<0.1	23.2	9.5	349	2.78	6.5	10.0	19.3	14	0.3	0.3	0.4	74	0.24	0.054	17
1203214	Soil	0.9	11.1	8.9	27	<0.1	11.8	4.9	232	1.35	2.8	4.4	3.8	7	0.1	0.2	0.1	38	0.10	0.032	9
1203215	Soil	2.5	26.5	24.2	61	0.1	30.8	11.5	432	2.55	4.5	4.6	16.8	18	0.2	0.2	0.4	67	0.23	0.068	88
1203216	Soil	2.4	20.7	18.4	55	<0.1	22.4	11.8	463	3.55	8.4	1.8	8.6	12	0.3	0.4	0.4	85	0.13	0.037	16
1203217	Soil	1.2	28.1	10.3	77	<0.1	26.1	13.2	590	2.85	5.2	8.4	4.5	18	0.3	0.2	0.2	80	0.30	0.050	22
1203218	Soil	1.2	12.2	8.4	36	<0.1	12.1	7.3	277	2.29	5.7	1.7	1.8	10	0.2	0.3	0.2	57	0.12	0.029	5
1203219	Soil	1.9	14.6	12.6	35	<0.1	14.5	6.5	178	2.94	7.8	3.3	3.0	12	0.2	0.4	0.2	80	0.12	0.032	8
1203220	Soil	1.0	32.7	7.3	73	<0.1	26.0	13.7	802	3.03	5.1	3.6	4.5	20	0.3	0.3	0.1	77	0.35	0.071	22
1203221	Soil	0.8	8.1	4.2	16	<0.1	4.2	3.1	384	1.22	2.0	1.9	0.6	5	<0.1	0.1	<0.1	36	0.05	0.018	3
1203222	Soil	0.8	26.4	7.3	56	<0.1	25.4	11.2	410	2.61	5.2	6.5	4.6	18	0.2	0.2	0.1	73	0.31	0.064	18
1203223	Soil	1.0	48.7	6.9	76	0.1	22.1	13.9	569	2.61	4.6	5.5	2.1	19	0.2	0.2	0.2	63	0.38	0.064	12
1203224	Soil	0.9	81.3	6.5	62	0.3	23.2	12.7	533	2.81	4.3	2.2	1.2	29	0.2	0.3	0.2	63	0.74	0.064	12
1203225	Soil	0.6	35.2	5.8	60	0.1	21.9	12.6	473	2.50	3.9	4.4	1.3	27	0.1	0.2	0.1	60	0.93	0.056	10
1203226	Soil	0.8	27.4	6.2	38	0.1	14.9	7.6	375	1.78	4.3	1.4	1.1	34	0.3	0.2	0.1	44	0.96	0.054	18
1203227	Soil	0.8	14.5	6.3	39	<0.1	16.3	8.4	393	2.04	4.6	2.0	2.8	16	0.1	0.2	0.1	55	0.27	0.041	12
1203228	Soil	0.3	2.7	2.5	6	<0.1	1.2	0.6	24	0.26	0.8	<0.5	<0.1	4	<0.1	<0.1	<0.1	12	0.04	0.011	2
1203229	Soil	0.9	14.7	8.1	30	<0.1	12.0	6.3	208	2.19	5.8	0.9	2.8	10	<0.1	0.3	0.1	65	0.15	0.027	9
1204181	Soil	0.9	17.7	15.9	40	<0.1	20.1	9.5	206	2.51	6.7	4.0	5.6	13	0.1	0.3	0.1	56	0.14	0.025	15
1204192	Soil	1.0	21.2	8.6	49	0.1	29.3	13.6	368	3.05	9.1	3.5	3.8	17	0.2	0.4	0.1	72	0.20	0.038	9
1204193	Soil	1.0	12.7	12.9	29	<0.1	12.8	5.6	142	2.09	5.5	1.6	4.0	13	<0.1	0.4	0.1	56	0.15	0.017	14
1202292	Soil	2.1	15.8	5.7	43	<0.1	1.6	3.0	128	4.89	2.9	10.0	1.0	18	<0.1	0.1	1.1	8	0.01	0.043	3
1202647	Soil	0.8	19.8	29.9	30	0.1	11.9	6.5	139	1.44	3.2	2.0	6.4	14	<0.1	0.2	0.3	29	0.20	0.041	29

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

CERTIFICATE OF ANALYSIS WHI11000681.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
1202639	Soil	33	0.91	177	0.104	1	2.04	0.013	0.15	<0.1	0.01	3.0	<0.1	<0.05	5	<0.5	<0.2
1202642	Soil	26	1.53	329	0.192	<1	2.51	0.010	0.89	<0.1	0.01	1.8	0.2	<0.05	6	<0.5	<0.2
1203211	Soil	31	0.80	128	0.063	1	1.59	0.011	0.08	<0.1	0.03	2.7	<0.1	<0.05	5	<0.5	<0.2
1203212	Soil	32	0.47	124	0.097	<1	1.42	0.015	0.06	0.2	0.04	2.4	<0.1	0.06	4	0.7	<0.2
1203213	Soil	31	0.49	117	0.101	1	1.52	0.014	0.06	0.3	0.06	2.4	<0.1	<0.05	5	<0.5	<0.2
1203214	Soil	20	0.28	56	0.053	<1	0.72	0.013	0.04	<0.1	0.02	1.4	<0.1	<0.05	3	<0.5	<0.2
1203215	Soil	57	0.71	217	0.060	<1	1.53	0.012	0.10	0.1	0.04	3.9	0.2	0.06	6	0.7	<0.2
1203216	Soil	42	0.51	135	0.077	<1	2.47	0.009	0.05	0.1	0.03	3.0	0.1	<0.05	8	<0.5	<0.2
1203217	Soil	47	0.98	151	0.092	<1	1.74	0.011	0.09	0.2	0.02	3.2	<0.1	<0.05	6	<0.5	<0.2
1203218	Soil	23	0.25	86	0.068	<1	1.48	0.013	0.03	0.1	0.04	1.6	<0.1	<0.05	6	<0.5	<0.2
1203219	Soil	30	0.32	96	0.088	1	2.03	0.010	0.04	0.1	0.04	2.3	<0.1	<0.05	9	<0.5	<0.2
1203220	Soil	38	1.10	162	0.094	<1	1.96	0.012	0.11	0.1	0.03	3.9	<0.1	<0.05	6	<0.5	<0.2
1203221	Soil	11	0.11	32	0.051	<1	0.55	0.014	0.02	<0.1	0.03	0.8	<0.1	<0.05	4	<0.5	<0.2
1203222	Soil	36	0.72	137	0.093	<1	1.65	0.011	0.05	0.2	0.02	3.4	<0.1	<0.05	5	<0.5	<0.2
1203223	Soil	36	0.91	155	0.061	<1	1.87	0.012	0.05	0.1	0.05	3.3	<0.1	<0.05	5	<0.5	<0.2
1203224	Soil	38	0.99	175	0.055	<1	1.92	0.013	0.06	<0.1	0.05	3.7	<0.1	0.07	6	0.5	<0.2
1203225	Soil	35	0.86	147	0.053	<1	1.70	0.014	0.04	<0.1	0.03	3.4	<0.1	0.08	5	<0.5	<0.2
1203226	Soil	22	0.37	253	0.038	<1	1.27	0.015	0.05	<0.1	0.04	2.3	<0.1	0.08	4	<0.5	<0.2
1203227	Soil	24	0.43	251	0.067	<1	1.31	0.014	0.05	<0.1	0.03	2.3	<0.1	<0.05	4	<0.5	<0.2
1203228	Soil	3	0.03	32	0.020	<1	0.20	0.011	0.03	<0.1	<0.01	0.3	<0.1	<0.05	2	<0.5	<0.2
1203229	Soil	22	0.31	161	0.071	<1	1.30	0.008	0.04	<0.1	0.02	2.0	<0.1	<0.05	6	<0.5	<0.2
1204181	Soil	28	0.41	115	0.063	<1	1.91	0.010	0.05	<0.1	0.02	2.4	<0.1	<0.05	5	<0.5	<0.2
1204192	Soil	40	0.57	167	0.096	1	2.86	0.013	0.05	0.1	0.05	3.8	<0.1	<0.05	6	<0.5	<0.2
1204193	Soil	21	0.27	108	0.056	<1	1.41	0.011	0.05	<0.1	0.02	1.9	<0.1	<0.05	6	<0.5	<0.2
1202292	Soil	3	0.71	146	<0.001	<1	0.99	0.020	0.43	<0.1	0.04	1.1	<0.1	0.92	3	1.1	0.7
1202647	Soil	17	0.34	285	0.025	1	1.21	0.009	0.07	<0.1	0.02	2.1	<0.1	<0.05	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000681.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
1203684	Soil	1.3	57.4	10.2	67	<0.1	38.8	17.9	460	3.85	4.2	2.9	3.6	12	0.2	0.3	0.3	78	0.16	0.050	14
REP 1203684	QC	1.3	56.4	10.1	66	<0.1	37.4	17.9	455	3.76	4.1	3.0	3.5	12	0.1	0.3	0.3	76	0.15	0.049	14
1204154	Soil	0.8	30.8	12.5	52	<0.1	22.0	9.7	288	2.67	5.9	6.8	3.7	15	0.1	0.3	0.1	58	0.20	0.037	14
REP 1204154	QC	0.8	31.1	12.4	54	<0.1	21.7	9.4	285	2.63	5.8	3.1	3.7	14	0.1	0.3	<0.1	60	0.19	0.037	14
1204174	Soil	0.7	24.7	35.3	67	<0.1	37.1	14.5	539	2.67	2.5	17.3	9.0	29	0.1	0.3	0.2	45	0.49	0.061	24
REP 1204174	QC	0.6	23.9	34.3	64	0.1	35.2	14.1	531	2.61	1.8	3.3	8.7	29	0.1	0.3	0.2	45	0.48	0.060	24
1204183	Soil	1.4	18.3	10.0	40	0.2	26.3	9.7	249	1.90	22.0	1.9	2.3	20	0.1	0.2	<0.1	41	0.23	0.042	11
REP 1204183	QC	1.5	19.1	11.9	37	0.2	26.6	10.0	254	1.96	21.2	1.9	2.3	19	0.1	0.2	<0.1	40	0.24	0.046	10
1202758	Soil	1.0	33.8	15.6	100	0.1	25.5	21.1	737	3.86	5.1	2.8	2.8	43	0.1	0.2	0.1	101	1.03	0.153	9
REP 1202758	QC	1.0	33.8	14.9	100	0.1	25.5	20.9	712	3.88	5.1	3.5	2.9	42	0.2	0.2	0.1	97	1.04	0.154	10
1204150	Soil	0.8	21.7	6.4	50	<0.1	19.7	8.7	297	2.38	7.0	2.7	2.6	22	0.1	0.3	0.1	65	0.32	0.050	16
REP 1204150	QC	0.8	21.3	6.4	50	<0.1	19.9	8.4	295	2.36	6.7	2.6	2.6	22	0.1	0.3	0.1	65	0.34	0.051	16
1203202	Soil	1.0	22.8	25.2	55	<0.1	21.6	8.2	273	2.16	3.8	4.2	8.2	17	0.2	0.1	0.2	43	0.22	0.040	18
REP 1203202	QC	0.9	23.6	25.6	56	<0.1	22.9	8.3	283	2.23	4.0	3.8	8.5	18	0.1	0.2	0.2	44	0.23	0.041	18
1202778	Soil	0.5	37.4	8.4	67	<0.1	29.7	14.4	497	2.78	1.8	0.8	3.7	25	<0.1	0.1	<0.1	47	0.59	0.115	15
REP 1202778	QC	0.4	38.7	8.6	71	<0.1	31.4	14.5	506	2.86	2.1	2.1	3.7	27	<0.1	0.2	<0.1	51	0.59	0.112	15
1202787	Soil	1.1	20.5	22.0	59	0.1	23.5	9.4	455	2.41	2.1	0.7	9.1	25	<0.1	0.2	0.3	47	0.34	0.048	35
REP 1202787	QC	1.1	20.5	21.8	59	0.2	23.6	9.6	460	2.43	2.1	6.6	8.8	25	<0.1	0.2	0.3	48	0.35	0.049	35
1202793	Soil	1.0	25.7	9.4	61	0.1	23.6	10.7	377	3.05	4.8	0.6	2.0	21	0.1	0.2	<0.1	74	0.35	0.042	8
REP 1202793	QC	1.0	23.3	9.2	57	<0.1	22.2	10.2	366	2.93	4.2	<0.5	1.8	20	0.1	0.2	<0.1	72	0.35	0.039	8
1203212	Soil	1.9	20.4	17.5	53	<0.1	23.5	9.3	297	2.55	6.0	22.4	17.3	16	0.2	0.3	0.3	68	0.25	0.049	21
REP 1203212	QC	1.9	20.0	17.5	53	<0.1	23.0	9.0	281	2.47	5.7	13.9	18.0	16	0.2	0.3	0.3	66	0.24	0.046	21
1203222	Soil	0.8	26.4	7.3	56	<0.1	25.4	11.2	410	2.61	5.2	6.5	4.6	18	0.2	0.2	0.1	73	0.31	0.064	18
REP 1203222	QC	0.8	26.8	7.4	58	<0.1	26.1	11.8	413	2.73	5.3	2.7	4.8	19	0.2	0.3	0.1	76	0.32	0.066	19
Reference Materials																					
STD DS8	Standard	12.8	103.7	123.7	300	1.7	35.7	7.2	581	2.35	24.8	118.6	6.3	62	2.2	4.9	5.9	41	0.66	0.078	14
STD DS8	Standard	13.1	105.2	124.4	308	1.7	36.9	7.1	595	2.36	25.1	125.9	6.6	60	2.3	5.0	6.0	41	0.67	0.080	15
STD DS8	Standard	12.3	100.2	122.1	287	1.7	38.3	7.5	571	2.35	26.0	111.5	5.8	56	2.2	5.1	6.0	40	0.60	0.076	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000681.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
1203684	Soil	82	1.69	93	0.064	<1	2.62	0.007	0.07	<0.1	0.05	7.0	<0.1	<0.05	7	0.8	<0.2
REP 1203684	QC	82	1.68	89	0.062	1	2.59	0.008	0.07	<0.1	0.04	7.0	<0.1	<0.05	7	<0.5	<0.2
1204154	Soil	35	0.69	105	0.080	<1	2.04	0.011	0.05	<0.1	0.04	3.7	<0.1	<0.05	5	<0.5	<0.2
REP 1204154	QC	35	0.68	102	0.081	2	2.05	0.011	0.05	<0.1	0.04	3.8	<0.1	<0.05	6	<0.5	<0.2
1204174	Soil	60	1.22	168	0.091	<1	1.78	0.015	0.26	<0.1	0.04	3.5	0.3	<0.05	5	<0.5	<0.2
REP 1204174	QC	59	1.19	168	0.094	<1	1.75	0.016	0.25	<0.1	0.03	3.4	0.3	<0.05	5	<0.5	<0.2
1204183	Soil	48	0.78	93	0.056	<1	1.38	0.015	0.03	0.1	0.03	2.6	<0.1	<0.05	5	<0.5	<0.2
REP 1204183	QC	48	0.82	91	0.058	<1	1.42	0.016	0.04	<0.1	0.03	2.5	<0.1	<0.05	5	<0.5	<0.2
1202758	Soil	39	1.48	329	0.139	2	1.90	0.019	0.30	0.1	0.03	4.1	0.2	<0.05	7	<0.5	<0.2
REP 1202758	QC	38	1.47	319	0.138	1	1.85	0.019	0.30	<0.1	0.03	3.9	0.2	<0.05	7	<0.5	<0.2
1204150	Soil	33	0.47	98	0.119	2	1.44	0.021	0.06	<0.1	0.03	2.9	<0.1	<0.05	4	<0.5	<0.2
REP 1204150	QC	33	0.48	98	0.120	1	1.41	0.021	0.06	0.1	0.03	3.0	<0.1	<0.05	4	<0.5	<0.2
1203202	Soil	30	0.74	116	0.064	<1	1.45	0.008	0.06	<0.1	<0.01	2.6	<0.1	<0.05	5	<0.5	<0.2
REP 1203202	QC	31	0.75	119	0.069	<1	1.49	0.009	0.07	0.1	<0.01	2.8	0.1	<0.05	5	0.5	<0.2
1202778	Soil	34	1.33	233	0.069	<1	1.78	0.008	0.31	<0.1	0.01	3.3	0.2	<0.05	6	0.6	<0.2
REP 1202778	QC	36	1.33	237	0.077	<1	1.80	0.008	0.31	<0.1	0.02	3.5	0.2	<0.05	6	<0.5	<0.2
1202787	Soil	34	0.82	222	0.070	2	1.60	0.010	0.13	0.1	0.04	3.0	0.1	<0.05	5	<0.5	<0.2
REP 1202787	QC	34	0.82	223	0.068	<1	1.62	0.010	0.14	<0.1	0.05	2.9	0.1	<0.05	5	<0.5	<0.2
1202793	Soil	37	0.88	151	0.090	<1	2.07	0.011	0.06	0.1	0.04	3.4	<0.1	<0.05	7	0.9	<0.2
REP 1202793	QC	35	0.81	140	0.088	<1	2.02	0.010	0.05	0.1	0.04	3.3	<0.1	<0.05	7	<0.5	<0.2
1203212	Soil	32	0.47	124	0.097	<1	1.42	0.015	0.06	0.2	0.04	2.4	<0.1	0.06	4	0.7	<0.2
REP 1203212	QC	30	0.44	124	0.090	1	1.31	0.016	0.06	0.2	0.04	2.3	<0.1	<0.05	4	<0.5	<0.2
1203222	Soil	36	0.72	137	0.093	<1	1.65	0.011	0.05	0.2	0.02	3.4	<0.1	<0.05	5	<0.5	<0.2
REP 1203222	QC	37	0.72	137	0.098	<1	1.65	0.016	0.05	0.2	0.03	3.6	<0.1	<0.05	5	<0.5	<0.2
Reference Materials																	
STD DS8	Standard	108	0.61	273	0.106	4	0.90	0.086	0.40	2.9	0.18	1.9	5.3	0.18	4	5.3	4.6
STD DS8	Standard	109	0.61	272	0.107	3	0.91	0.088	0.40	2.8	0.22	2.0	5.2	0.18	5	5.0	5.0
STD DS8	Standard	111	0.56	239	0.098	2	0.83	0.078	0.39	2.8	0.20	1.7	5.3	0.16	4	5.7	4.8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000681.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
STD DS8	Standard	12.4	100.2	119.3	296	1.7	37.1	7.7	563	2.29	24.1	101.1	6.0	58	2.1	4.9	6.1	40	0.64	0.082	12
STD DS8	Standard	12.4	105.1	126.1	298	1.9	37.0	7.0	557	2.26	25.1	106.5	6.5	52	2.4	4.3	5.5	38	0.62	0.073	12
STD DS8	Standard	12.3	106.8	122.4	301	1.7	37.2	7.2	593	2.34	25.1	103.9	6.4	53	2.0	4.3	5.4	39	0.65	0.074	13
STD DS8	Standard	13.6	114.1	119.3	305	1.7	39.8	8.1	628	2.45	28.9	119.8	6.8	70	2.3	6.2	6.5	47	0.69	0.076	15
STD DS8	Standard	13.8	115.5	126.1	304	1.7	39.6	7.8	594	2.38	28.1	102.9	7.3	72	2.2	5.5	6.6	44	0.70	0.077	16
STD DS8	Standard	12.4	107.8	120.7	310	1.7	38.5	7.4	600	2.44	26.1	106.7	6.0	62	2.6	5.4	6.2	40	0.65	0.082	13
STD DS8	Standard	12.5	103.7	117.0	300	1.8	36.3	7.1	595	2.35	25.3	109.3	6.2	62	2.1	5.1	6.0	40	0.66	0.076	13
STD DS8	Standard	12.6	109.2	123.3	311	1.7	38.6	7.2	614	2.46	25.3	97.3	6.5	62	2.2	5.2	6.0	43	0.68	0.075	13
STD DS8	Standard	11.8	106.2	120.0	301	1.7	38.1	7.3	580	2.37	25.3	116.1	6.9	63	2.4	5.2	6.0	42	0.65	0.076	13
STD DS8	Standard	12.8	106.8	122.3	301	1.7	36.2	7.5	610	2.39	26.0	108.2	6.6	63	2.3	5.3	6.0	40	0.72	0.074	15
STD DS8	Standard	14.1	109.3	123.7	286	1.7	37.4	7.8	611	2.46	24.6	101.7	7.1	64	2.2	4.9	6.0	39	0.68	0.077	16
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Goldspike Exploration Inc.**
56th Floor - 100 King Street West
Toronto ON M5X 1C9 Canada

Project: VIP
Report Date: August 09, 2011

QUALITY CONTROL REPORT WHI11000681.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
STD DS8	Standard	115	0.56	235	0.104	2	0.82	0.077	0.40	2.9	0.20	1.7	5.3	0.16	4	4.7	4.9
STD DS8	Standard	106	0.56	268	0.095	1	0.85	0.080	0.38	2.9	0.18	1.9	5.1	0.12	4	4.5	4.9
STD DS8	Standard	110	0.57	267	0.101	2	0.86	0.083	0.40	3.0	0.19	2.0	4.9	0.15	4	5.0	4.0
STD DS8	Standard	122	0.60	265	0.131	3	0.91	0.097	0.43	2.7	0.19	2.3	5.0	0.14	5	5.1	4.6
STD DS8	Standard	121	0.61	276	0.135	2	0.93	0.096	0.41	2.7	0.19	2.3	5.4	0.13	5	5.1	5.0
STD DS8	Standard	112	0.61	279	0.108	2	0.88	0.085	0.41	3.1	0.23	2.0	5.4	0.14	5	5.6	5.0
STD DS8	Standard	112	0.59	267	0.108	3	0.85	0.082	0.40	2.9	0.21	1.9	5.1	0.13	5	5.6	4.9
STD DS8	Standard	119	0.53	255	0.113	1	0.89	0.089	0.41	3.0	0.21	2.2	5.2	0.09	5	5.7	5.0
STD DS8	Standard	111	0.53	256	0.111	2	0.88	0.095	0.39	2.8	0.21	2.0	5.1	0.08	4	5.4	4.5
STD DS8	Standard	115	0.53	271	0.120	2	0.87	0.087	0.42	3.0	0.21	2.0	5.3	0.17	5	5.8	4.8
STD DS8	Standard	115	0.54	282	0.119	1	0.89	0.088	0.41	2.8	0.19	2.0	5.3	0.13	5	5.5	4.8
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.