ASSESSMENT REPORT, 2011 GEOCHEMICAL SAMPLING AND SURFICIAL GEOLOGY MAPPING PROGRAM, LIVINGSTONE PROPERTY

WHITEHORSE MINING DIVISION, YUKON, CANADA
NTS MAP SHEET: 105E/08, 105E/09, AND 105F/08, NAD83 ZONE 8
543900 E, 6818700 N (NAD83)

PERIOD OF WORK: MAY 30, 2011 TO FEBRUARY 28, 2012

OPERATOR:
GOLDEN PREDATOR CANADA CORP.

1 Lindeman Road
Whitehorse, Yukon
Y1A 5Z7

December 4, 2012

Prepared by:

Golden Predator Canada Corp.
Erin O'Brien, M.Sc., P.Geo.

CLAIMS AND OWNER:

Grant Number	Claim Name	Claim Number	Registered Owner
YD36601 - YD37000	DAC	1 - 400	Golden Predator Canada Corp - 100%
YD36133 - YD36139	DAC	401 - 407	Golden Predator Canada Corp - 100%
YD41821 - YD41859	DACX	1 - 39	Golden Predator Canada Corp - 100%
YD41860 - YD41862	DACX	40 - 42	Golden Predator Canada Corp - 100%
YD41863	DACX	43	Golden Predator Canada Corp - 100%
YD41864 - YD41875	DACX	44 - 55	Golden Predator Canada Corp - 100%
YD41876 - YD41877	DACX	56 - 57	Golden Predator Canada Corp - 100%
YD36201 - YD36600	JJW	1 - 400	Golden Predator Canada Corp - 100%
YD36141 - YD36158	JJW	401 - 418	Golden Predator Canada Corp - 100%
YD146503 - YD146652	MCPN	1 - 150	Golden Predator Canada Corp - 100%
YD142761 - YD142783	OVS	1 - 23	Golden Predator Canada Corp - 100%
YD146821 - YD146822	RNB	1 - 2	Golden Predator Canada Corp - 100%
YD148003 - YD148004	RNB	3 - 4	Golden Predator Canada Corp - 100%
YD148005 - YD148082	RNB	4 - 82	Golden Predator Canada Corp - 100%
YD148083 - YD148096	RNB	83 - 96	Golden Predator Canada Corp - 100%
YD148097 - YD148126	RNB	97 - 126	Golden Predator Canada Corp - 100%
YD148127 - YD148273	RNB	127 - 273	Golden Predator Canada Corp - 100%
YD140701 - YD140823	RWH	1 - 123	Golden Predator Canada Corp - 100%
YD140848 - YD140885	RWH	148 - 185	Golden Predator Canada Corp - 100%
YD146661 - YD146700	SRVA	1 - 40	Golden Predator Canada Corp - 100%
YD147211 - YD147326	SRVA	41 - 156	Golden Predator Canada Corp - 100%
YD147327 - YD147442	SRVA	157 - 272	Golden Predator Canada Corp - 100%
YD147443 - YD147498	SRVA	273 - 328	Golden Predator Canada Corp - 100%
YD143101 - YD143166	SRVB	1 - 66	Golden Predator Canada Corp - 100%
YD143168 - YD143356	SRVB	68 - 256	Golden Predator Canada Corp - 100%
YD41901 - YD42060	SRVC	1 - 160	Golden Predator Canada Corp - 100%
YD42101 - YD42494	SRVD	1 - 394	Golden Predator Canada Corp - 100%
YD41401 - YD41600	SRVE	1 - 200	Golden Predator Canada Corp - 100%
YD41601	SRVE	201	Golden Predator Canada Corp - 100%
YD41602 - YD41688	SRVE	202 - 288	Golden Predator Canada Corp - 100%
YD41689 - YD41692	SRVE	289 - 292	Golden Predator Canada Corp - 100%
YD41693 - YD41816	SRVE	293 - 416	Golden Predator Canada Corp - 100%
YD35601 - YD35672	SRVF	1 - 72	Golden Predator Canada Corp - 100%
YD35673 - YD35690	SRVF	73 - 90	Golden Predator Canada Corp - 100%
YD35691 - YD36132	SRVF	91 - 532	Golden Predator Canada Corp - 100%

TABLE OF CONTENTS

TABLE OF CONTENTS I
LIST OF FIGURES II
LIST OF TABLES II
LIST OF APPENDICES II
1.0 INTRODUCTION 1
2.0 PROPERTY LOCATION AND DESCRIPTION 1
3.0 INFRASTRUCTURE, CLIMATE AND PHYSIOGRAPHY 5
4.0 EXPLORATION HISTORY 5
5.0 GEOLOGY 6
5.1 Regional Geology 6
5.2 Property Geology 8
5.3 Structure 8
5.4 Mineralization 10
6.0 EXPLORATION 11
6.1 Exploration Program 11
6.2 Sampling Methodology and Protocols 14
Stream Geochemical Program 14
Soil Auger Samples 15
Rock Samples 15
6.3 Results 16
Stream Sediments 16
Rocks 16
Soils 17
7.0 CONCLUSIONS AND RECOMMENDATIONS 18
8.0 2011 EXPENDITURES 19
9.0 STATEMENT OF AUTHORSHIP 20
10.0 REFERENCES 20

LIST OF FIGURES

Figure 2-1. Livingstone Property Location, Yukon Territory 1
Figure 2-2. Livingstone Project Claim Map – Northern Half 3
Figure 2-3. Livingstone Project Claim Map – Southern Half 4
Figure 5-1. Generalised Regional Geology of the Livingstone Area (after Gordey & Makepeace, 1999) 7
Figure 5-2. Geology of the Livingstone Area (105 E/08; after Colpron, 2006) ……..……...9

Figure 6-1. Sample Locations, Livingstone Property 12
-Figure 6-2. Aerial Photograph Compilation, Livingstone Property 13

LIST OF TABLES

Table 2-1. Livingstone claim information 2
Table 8-1. 2011 Expenditures 19

LIST OF APPENDICES

Appendix 1 Certificate of Author
Appendix 2 Analytical Summary and Sample Descriptions
Appendix 3 Assay Certificates
Appendix 4 Description of Analytical Methods and Detection Limits
Appendix 5 Silt Geochemical Plots for Select Elements
Appendix 6 Soil Geochemical Plots for Select Elements
Appendix 7 Rock Sample Locations

1.0 INTRODUCTION

The Livingstone property consists of 3,574 contiguous mineral claims covering an area of 72,216 hectares, located in the Livingstone district in central Yukon Territory. Golden Predator Canada Corp. (Golden Predator) has an agreement with 18526 Yukon Inc. for the majority of claims in the property. The remaining claims are owned and controlled by Golden Predator. The company is targeting lode gold deposits in areas with significant historical placer gold production and no known bedrock sources.

This report describes the work completed in the 2011 and early 2012 field seasons. Work was performed in four stages from May 30th 2011 to February 21st, 2012. The programs included stream sediment sampling, rock sampling, soil sampling; and aerial photography and surficial geology mapping.

2.0 PROPERTY LOCATION AND DESCRIPTION



Figure 2-1. Livingstone Property Location, Yukon Territory

The property is located on the south central Yukon. The southern edge of the property lies 80 km northeast of Whitehorse, YT (Figure 2-1). It is accessed by one hour helicopter trip from Whitehorse or by a 30 minute fixed wing flight to Livingstone airstrip located near Lake Creek and servicing several placer creeks (approximate co-ordinates 533500 E, 6804000 N, NAD83, zone 8). Alternatively, access can be gained by a ~120 km Livingstone winter road from Whitehorse via Lake Laberge.

The property is located in the Whitehorse Mining District, and consists of 3,574 contiguous mineral claims covering an aggregate area of 72,216 hectares (Table 2-1, Figures 2-2, 2-3).

Table 2-1. Livingstone claim information

Grant Number	Claim Name	Claim Number	Registered Owner	Expiry Date
YD36601 - YD37000	DAC	1 - 400	Golden Predator Canada Corp - 100%	01/04/2012
YD36133 - YD36139	DAC	401 - 407	Golden Predator Canada Corp - 100%	01/04/2012
YD41821 - YD41859	DACX	1 - 39	Golden Predator Canada Corp - 100%	11/04/2012
YD41860 - YD41862	DACX	40 - 42	Golden Predator Canada Corp - 100%	02/04/2012
YD41863	DACX	43	Golden Predator Canada Corp - 100%	11/04/2012
YD41864 - YD41875	DACX	44 - 55	Golden Predator Canada Corp - 100%	02/04/2012
YD41876 - YD41877	DACX	56 - 57	Golden Predator Canada Corp - 100%	11/04/2012
YD36201 - YD36600	JJW	1 - 400	Golden Predator Canada Corp - 100%	11/04/2012
YD36141 - YD36158	JJW	401 - 418	Golden Predator Canada Corp - 100%	11/04/2012
YD146503 - YD146652	MCPN	1 - 150	Golden Predator Canada Corp - 100%	28/02/2012
YD142761 - YD142783	OVS	1 - 23	Golden Predator Canada Corp - 100%	13/05/2012
YD146821 - YD146822	RNB	1 - 2	Golden Predator Canada Corp - 100%	01/04/2012
YD148003 - YD148004	RNB	3 - 4	Golden Predator Canada Corp - 100%	01/04/2012
YD148005 - YD148082	RNB	4 – 82	Golden Predator Canada Corp - 100%	07/03/2012
YD148083 - YD148096	RNB	83 – 96	Golden Predator Canada Corp - 100%	01/04/2012
YD148097 - YD148126	RNB	97 - 126	Golden Predator Canada Corp - 100%	07/03/2012
YD148127 - YD148273	RNB	127 - 273	Golden Predator Canada Corp - 100%	01/04/2012
YD140701 - YD140823	RWH	1 – 123	Golden Predator Canada Corp - 100%	11/04/2012
YD140848 - YD140885	RWH	148 - 185	Golden Predator Canada Corp - 100%	11/04/2012
YD146661 - YD146700	SRVA	1 – 40	Golden Predator Canada Corp - 100%	28/02/2012
YD147211 - YD147326	SRVA	41 - 156	Golden Predator Canada Corp - 100%	28/02/2012
YD147327 - YD147442	SRVA	157 - 272	Golden Predator Canada Corp - 100%	01/03/2012
YD147443 - YD147498	SRVA	273 - 328	Golden Predator Canada Corp - 100%	28/02/2012
YD143101 - YD143166	SRVB	1 – 66	Golden Predator Canada Corp - 100%	07/03/2012
YD143168 - YD143356	SRVB	68 - 256	Golden Predator Canada Corp - 100%	07/03/2012
YD41901 - YD42060	SRVC	1 – 160	Golden Predator Canada Corp - 100%	07/03/2012
YD42101 - YD42494	SRVD	1 – 394	Golden Predator Canada Corp - 100%	07/03/2012
YD41401 - YD41600	SRVE	1 – 200	Golden Predator Canada Corp - 100%	07/03/2012
YD41601	SRVE	201	Golden Predator Canada Corp - 100%	01/03/2012
YD41602 - YD41688	SRVE	202 - 288	Golden Predator Canada Corp - 100%	07/03/2012
YD41689 - YD41692	SRVE	289 - 292	Golden Predator Canada Corp - 100%	04/03/2012
YD41693 - YD41816	SRVE	293 - 416	Golden Predator Canada Corp - 100%	07/03/2012
YD35601 - YD35672	SRVF	1 – 72	Golden Predator Canada Corp - 100%	11/04/2012
YD35673 - YD35690	SRVF	73 – 90	Golden Predator Canada Corp - 100%	22/03/2012
YD35691 - YD36132	SRVF	91 - 532	Golden Predator Canada Corp - 100%	11/04/2012

530,000

540,000

550,000


560,000

6,840,000

6,830,000

6,820,000

N



Legend

- Golden Predator Property Outline
- Quartz Claim with Grant #
- Watercourse

GOLDEN PREDATOR

Livingstone Property

Claim Map with
Grant Number
Northern Half

0 1 2 3 4

Kilometers

Scale:	1:50,000	Map ID:	--
Draw Date:	2012/11/30	Rev. Date:	--
Version:	1	Figure:	2-2
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District, Yukon Territory		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121130_Claim2-2		


530,000

540,000

550,000

6,810,000

6,800,000



Legend

- Golden Predator Property Outline
- Quartz Claim with Grant #
- Watercourse

GOLDEN PREDATOR

Livingstone Property

Claim Map with
Grant Number
Southern Half

0 1 2 3 4

Kilometers

Scale:	1:50,000	Map ID:	--
Draw Date:	2012/11/30	Rev. Date:	--
Version:	1	Figure:	2-3
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District, Yukon Territory		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121130_Claim2-3		

3.0 INFRASTRUCTURE, CLIMATE AND PHYSIOGRAPHY

The centre of the property is located at 543900 E, 6818700 N (NAD83, zone 8). The nearest settlement is Whitehorse which is located approximately 80 km to the southwest.

Access to the property is via one hour helicopter trip from Whitehorse or by a 30 minute fixed wing flight to Livingstone airstrip located near Lake Creek and servicing placer creeks Little Violet, Cottoneva, Lake and Summit (approximate co-ordinates 533500 E, 6804000 N, NAD83, zone 8). Alternatively, access can be gained by a ~120 km Livingstone winter road from Whitehorse via Lake Laberge.

The property is located within the Big Salmon Range, the southwest extension of the Pelly Mountains. The property is located in the Boreal Cordillera Ecozone. The region consists of extensive mountains and valleys separated by wide lowlands. The property lies within the Pelly Mountains ecoregion. The mean annual temperature for the area is approximately -3°C with a summer mean of 10.5°C and a winter mean of -17.5°C. Mean annual precipitation is 500-1000 mm, varying with elevation (http://ecozones.ca/english/region/178.html).

The ecoregion is characterized by boreal forests of white spruce, black spruce, lodgepole pine and aspen in the lower-elevation valley bottoms. However, much of the ecoregion lies above the treeline and is characterized by alpine tundra communities including lichens, shrubs, birch, and willows. Black and white spruce, and alpine fir are prevalent in the subalpine region (http://ecozones.ca/english/region/178.html).

The Big Salmon Range experienced several glaciations within the Quaternary Period. Bond (2007) describes the phases of glaciation during the late Wisconsinan McConnell glaciation. The glacial history has resulted in the deposition and partial erosion of a complex assemblage of surficial materials and landforms across the Livingstone claims. The landscape consists of exposed bedrock, blockfields of weathered bedrock, veneers to blankets of till and colluvium, glaciofluvial terraces, alluvial floodplains and organic wetlands (AECOM and Palmer Environmental Consulting Group Inc., 2012 – Appendix 8). Highland areas have discontinuous permafrost. The region has moderate relief with elevations on the property range from 700 to 2,020 metres above mean sea level.

4.0 EXPLORATION HISTORY

Little is known about the early historical work carried out around the Livingstone District although there is evidence of hard rock exploration likely associated with the placer activity as far back as the early 1900s, when a settlement of up to 300 people resided in Livingstone. Placer gold recovered from the area is postulated to have come from quartz veins in metasedimentary rocks. The placer gold has been reported to come in large, rough nuggets.

Small claim groups were staked intermittently in the area between 1980 and 2000 and small programs including, mapping, sampling, ground geophysics, and trenching were carried out.

Goldstrike Resources holds the rectangle of land in the headwaters of Cottoneva, Lake and Summit creeks, nestled between Golden Predator`s DACX, DAC and RNB claims. Goldstrike is currently exploring northwest trending recessive structures carrying up to 8.23 g/t Au in sulphidic quartz subcrop samples (http://www.goldstrikeresources.com/files/pdf/LIV_PR_Map.pdf). A second vein returned grab samples from outcrop 2 km to the north returned values up to 0.8 g/t Au with copper and lead mineralization.

The CAM claims, located immediately south of DACX were originally staked in 1997 to cover areas of placer mining activities in the Livingstone area. The claims are currently held by prospector/ geologist Larry Carlyle and his partner Max Fuerstner Jr.. The CAM block consists of 79 claims and covers the lower reaches of Livingstone, Summit and Lake creeks. The best result from Mr. Carlyle's recent work (2010-2011) is 4.5 g/t Au over 14.5 m in a quartz boudin near in Livingstone Creek (http://www.yukonprospectors.ca/pdf/YPA%20Website%20Livingstone%20Summary.pdf).

5.0 GEOLOGY


5.1 Regional Geology

The property is located in the Livingstone district, the area bound to the southwest by the Big Salmon Fault, to the north by Little Salmon Lake, and paralleling the d'Abbadie fault zone (Figure 5-1; Gordey and Makepeace, 1999). Placer gold was discovered in the area in 1898 and the area has seen intermittent activities since that time. An estimated 50,000 ounces of placer gold has been mined (Yukon Placer Mining Industry 2007-2009). The gold is generally coarse-grained, and is commonly associated magnetite suggesting a nearby source of possible skarn style mineralization (Colpron, 2006).

Livingstone occurs near the boundary between pericratonic Yukon-Tanana terrane and the Quesnellia and Stikinia arcs to the west, in central Yukon. Yukon-Tanana terrane hosts the majority of rocks at Livingstone.

Yukon-Tanana rocks at Livingstone consist of five successions of metasedimentary and metavolcanic rocks ranging in age from pre-Upper Devonian to Lower Mississippian (Colpron, 2006). Yukon-Tanana rocks have experienced at least five intrusive events ranging in age from Early Mississippian to Late Cretaceous/Early Tertiary (Colpron, 2006).

Rocks of the Quesnellia and Stikinia terranes underlie the western part of the Livingstone district. Both terranes are comprised of arc volcanic rocks formed offshore from Laurentia (distal to Yukon-Tanana terrane) during the Early Mesozoic (Nelson and Colpron, 2007). The



Bedrock Legend

QUATERNARY
- *Q: QUATERNARY: unconsolidated glacial, glaciofluvial and glaciolacustrine, fluvial, organics volcanic ash deposits*

PLIOCENE
- *PW1: WALSH: massive rhyolite (Walsh Creek)*
- *PW2: WALSH: conglomerate (Walsh Creek)*

LATE CRETACEOUS TO TERTIARY
- *LKgP: PROSPECTOR MOUNTAIN SUITE: hbnde-bio granodiorite, diorite (Wheaton Valley Granodiorite)*

MID-CRETACEOUS
- *mKgC: CASSIAR SUITE: granodiorite, bio-musc granodiorite, quartz diorite, bio quartz monzonite, granite (Cassiar Suite)*
- *mKqC: CASSIAR SUITE: medium to coarse grained, granite & bio quartz monzonite; and granodiorite (Cassiar Suite)*
- *mKgW: WHITEHORSE SUITE: granodiorite, diorite*
- *mKqS: SELWYN SUITE: granite, monzonite and grano-diorite; porphyritic granite (Selwyn Suite)*
- *mKN: MOUNT NANSEN: andesite to dacite flows, breccia and tuff; felsic lapilli tuff; flow-banded rhyolite and quartz-feldspar porphyry plugs,and breccia (Mount Nansen Gp., Byng Creek Volcanics, Hutshi Gp.)*

UPPER CRETACEOUS
- *uKC1: CARMACKS: basalt and breccia; porphyric andesite; vesicular andesite and trachyte; (Carmacks Gp., Little Ridge Volcanics, Casino Volcanics)*
- *uKW: WINDY-TABLE: dacite flows, ash and lapilli tuff; epiclastic rocks; (Open Creek Volcanics)*

UPPER JURASSIC AND LOWER CRETACEOUS
- *uJKT: TANTALUS: chert pebble conglomerate and gritty sandstone; shale, siltstone, arkose and coal; (Tantalus)*

MID-JURASSIC
- *MJqB: BRYDE SUITE: leucocratic monzonite, syenite & granite, & dykes of dacite - andesite (Teslin Crossing Stock)*

EARLY JURASSIC
- *EJgA: AISHIHIK SUITE: granodiorite; diorite to monzodiorite*

LOWER AND MIDDLE JURASSIC, HETTANGIAN TO BAJOCIAN
- *JL: LABERGE: arkosic sandstone and minor shale with interbeds of pebble and boulder conglomerate; silty shale (Laberge Gp.)*

LOWER JURASSIC, PLEINSBACHIAN TO TOARCIAN
- *lJN: NORDENSKIOLD: dacite tuff; grades locally to sandstone; interbedded conglomerate (Nordenskiold Dacite)*

LATE TRIASSIC
- *LTrgS: STIKINE SUITE: gabbroic orthogneiss; granodiorite; diorite (Tally Ho Leucogabbro, Little River Batholith, Friday Creek diorite)*

UPPER TRIASSIC
- *TrJC: JONES LAKE - CASSIAR: siltstone & shale; limestone*

UPPER TRIASSIC, CARNIAN TO NORIAN
- *uTrAK1: AKSALA: shale, siltstone, argillaceous limestone; pebble & cobble conglomerate; laharic debris flows;(Casca mb. of Aksala)*
- *uTrAK2: AKSALA: limestone; argillaceous limestone; dolostone; limestone conglomerate debris flows (Hancock mb. of Aksala)*
- *uTrAK3: AKSALA: greywacke & pebble conglomerate; siltstone; greywacke and shale; lithic arenite (Mandanna mb. of Aksala)*

UPPER TRIASSIC, CARNIAN AND OLDER (?)
- *uTrP: POVOAS: andesitic basalt flows, breccia, tuff, sandstone & argillite; dacitic breccia & tuff, greenschist (Povoas)*

MIDDLE TRIASSIC
- *mTrJ: JOE MOUNTAIN: basalt flows; andesite; microdiorite; gabbro and diorite (Joe Mountain Volcanics)*

PROTEROZOIC AND PALEOZOIC
- *PPa: AMPHIBOLITE: metamorphosed mafic rocks*
- *PPa1: AMPHIBOLITE: chlorite schist, amphibolite.*
- *PPa2: AMPHIBOLITE: serpentinized ultramafic rocks*

DEVONIAN, MISSISSIPPIAN AND(?) OLDER
- *DMN2: NASINA: marble (Nasina assem.)*
- *DMN4: NASINA: quartzite, schist (inc. Klondike Schist Assemblage)*

UPPER CARBONIFEROUS, LOWER AND MIDDLE PENNSYLVANIAN
- *uCB1: BOSWELL: slate, phyllite, conglomerate, volcanic breccia*
- *uCB2: BOSWELL: altered basalt, volcanic breccia & greenstone*
- *uCB3: BOSWELL: hornblendite-gabbro (Boswell)*
- *uCB4: BOSWELL: micritic limestone (Boswell)*
- *uCS: SEMENOF: andesite & basalt, volcanic breccia & greenstone*

CARBONIFEROUS TO PERMIAN
- *CPA1: ANVIL: basalt, diorite & gabbro, amphibolitic greenstone*
- *CPA4: ANVIL: dunite, peridotite, gabbro; serpentinite; carbonate*
- *CPA6: ANVIL: eclogite*

MISSISSIPPIAN
- *MyP: PELLY MNTS SUITE: syenite; intrusive felsic Earn volcanics*

UPPER DEVONIAN TO LOWER MISSISSIPPIAN
- *DMEC1: EARN - CASSIAR: slate, grit & chert pebble conglomerate*
- *DMEC2: EARN - CASSIAR: chert & cherty tuff; local bedded barite*
- *DMEC3: EARN - CASSIAR: rhyolite to andesite flows & tuffs*

MIDDLE SILURIAN TO MIDDLE DEVONIAN
- *SDA1: ASKIN: dolomitic siltstone and dolomitic sandstone (Askin Gp.)*
- *SDA2: ASKIN: dolostone, limestone; orthoquartzite; (Askin Gp.)*
- *SDA3: ASKIN: lapilli tuff & volcanic breccia with interbedded dolomite*

ORDOVICIAN TO DEVONIAN, LOCALLY ?MISSISSIPPIAN
- *ODRC1: ROAD RIVER - CASSIAR: shale; local interbeds of quartz arenite; includes thin sills or flows of basalt undifferentiated*
- *ODRC2: ROAD RIVER - CASSIAR: limy graphitic siltstone & quartzite with interbedded graphitic silty shale (Nasina)*

CAMBRIAN TO DEVONIAN OR YOUNGER
- *CDS1: ST. CYR: laminated calcareous shale and silty limestone*
- *CDS3: ST. CYR: calcareous graphitic slate and silty shale*
- *CDS4: ST. CYR: calcareous quartz siltstone & orthoquartzite*
- *CDS5: ST. CYR: phyllite & laminated phyllitic limestone*

UPPER CAMBRIAN AND ORDOVICIAN
- *COK1: KECHIKA: slate, phyllite, limestone (Kechika)*
- *COK2: KECHIKA: amygdaloidal basalt & volcaniclastics; diabase sills*

LOWER CAMBRIAN
- *ICR: ROSELLA: limestone and argillaceous limestone*

UPPER PROTEROZOIC TO LOWER CAMBRIAN
- *PCI1: INGENIKA: calcareous sandstone, shale, quartzite (Swannel and Tsaydiz of the Ingenika Gp.)*
- *PCI4: INGENIKA: slate, siltstone, quartzite (Ketza Gp., Harvey Gp.)*

Faults

NORMAL / REVERSE
- defined
- approximate

THRUST UPRIGHT
- defined
- approximate
- assumed

MOVEMENT UNDEFINED
- defined
- approximate
- assumed
- extrapolated

Legend

- GPD Property Outline
- Watercourse

GOLDEN PREDATOR

Livingstone

Regional Geology

0 4 8 12 16
Kilometers

Scale:	1:375,000	Map ID:	--
Draw Date:	2012/11/20	Rev. Date:	
Version:	1	Figure:	5-1
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121120_2011Fig5-1		

two arcs were accreted offshore during the mid-Jurassic and then joined continental North American by around 175 Ma (Nelson and Colpron, 2007).

Most geologic units have a general NNW strike, parallel to the Teslin Fault Zone and regional foliation. Adjacent to the d'Abbadie fault, foliations and map patterns are generally parallel to the north-trending shear zone.

5.2 Property Geology

The westernmost of the five successions of rocks in the Yukon-Tanana terrain at Livingstone is the Snowcap Complex. This succession consists of Upper Devonian to Lower Mississippian quartzites to quartz-muscovite schists with minor carbonaceous phyllites, marbles and amphibolites (Colpron, 2006). The Snowcap Complex is interpreted as the basement to the overlaying Yukon-Tanana rocks and is intruded in the Livingstone area by a regionally extensive body of tonalite gneiss of Early Mississippian age (Figure 5-2). Historical and current placer areas occur mainly in these geologic units.

The Mendocina greenstones crop out near the d'Abbadie fault in southwest central Livingstone. Fine-grained phyllitic greenstones occur with minor serpentinite, both with minor magnetite along foliation planes (Colpron, 2006). The assemblage has been interpreted as Permian and a similarity to the VMS-prone upper Devonian Fire Lake formation in the Finlayson district has been suggested (Colpron, 2006).

Yukon-Tanana at Livingstone also includes the Last Peak and Livingstone assemblages, belts of phyllites and schist and quartzite to quartz-plagioclase-chlorite schist with dolomitic marble, respectively. The Livingstone Creek assemblage is considered a possible distal facies to the Mendocina greenstones (Colpron, 2006).

Intrusive rocks in the area can be divided into two groups: older, deformed bodies like the Early Mississippian gneisses cutting Yukon Tanana rocks and the Jurassic and younger, weakly or undeformed plutons formed in the Quesnellian and Stikinian arcs and inbound of the continental margin during terrane accretion (Nelson and Colpron, 2007). The Jurassic and younger plutons present potential porphyry targets (*e.g.* Red Mountain), and pluton margin Au-bearing vein systems.

5.3 Structure

Livingstone is defined primarily on the basis of the major faults at its margins, the d'Abbadie and the Big Salmon. The area has previously been referred to as the Teslin Suture Zone (Colpron, 2006) and defined on the basis of a strong regional transposition foliation and complex lithologic




Figure 5-2. Geology of the Livingstone Area (105 E/08; after Colpron, 2006)

relationships. Interpretations of the Teslin Zone include a subduction complex or a Permian thrust fault system, amongst others (Colpron *et al.*, 2005).

The pervasive transposition foliation strongly influences the map pattern of units, which generally strike NW and dip steeply to the SW or NE, except where affected by localized strain as those adjacent the D'Abbadie. The regional foliation is folded by NE-verging folds (Colpron, 2006).

The d'Abbadie fault is a brittle-ductile, steeply dipping to vertical north-south striking shear zone. It has a well-defined dextral sense of motion and shallow lineations that suggest a minor amount of vertical displacement, with horizontal offset along the fault estimated at around 4 km (Colpron, 2006). The d'Abbadie was active during the Cretaceous and was coeval with plutonism (Colpron et al., 2011).

5.4 Mineralization

Major structures at Livingstone have yet to be linked with mineralization. Colpron (2007) suggests that skarn mineralization adjacent to the upper Mississippian tonalite gneiss bodies intruding Yukon Tanana rocks as a source for placer gold.

The Mendocina greenstones have been described as similar or equivalent to the Fire Lake formation in the Finlayson district (Colpron, 2007). The Fire Lake formation hosts the upper Permian Fyre Lake Cu-Co-Au deposit in mafic schists, and the Finlayson districts contains numerous other VMS occurrences including Kudz Ze Kayah, Wolverine, and Ice (105G 034).

Lode gold systems comprised of orogenic veins are characterized by their metal content (Au dominant); mode of occurrence, consisting of large quartz vein systems (Ash and Aldrick, 1996); and by their association with greenstones, especially Archean belts (Dubé and Gosselin, 2007). The deposit type encompasses the massive Archean greenstone-hosted deposits of the Canadian Shield.

Lode gold systems contain native gold along with various subordinate metal minerals (typically pyrite>pyrrhotite>chalcopyrite) in quartz-carbonate veins formed from H_2O-CO_2-rich fluids (Dubé and Gosselin, 2007). They are associated with steeply dipping brittle-ductile structures in major fault systems, especially those formed as part of terrane collisions. Controlling faults, however, can be compressional to transpressional (Robb, 2005). Host rocks are commonly greenstone to lower amphibolite facies mafic rocks, which is likely related to the interpreted 6-12 km formation window for these vein systems (Robb, 2005). Nearby VMS deposits have been identified as a potentially significant factor in the development of these deposits, as well as the presence of regional unconformities (Dubé and Gosselin, 2007).

In comparing to other significant lode gold camps, Livingstone features crustal-scale brittle ductile faults, multiple/complex collision events, and adjacent mafic, locally serpentinized units. Unlike these other camps, however, Livingstone is missing regionally extensive ophiolite bodies and associated listwanites. Ash (2001) suggests that rich placer districts are only viable targets for lode mineralization when appreciable amounts of ophiolite and listwanite are still present.

6.0EXPLORATION

6.1 Exploration Program

The exploration program was carried out in four phases:

1. May 31 to June 6, 2011 - stream sediment sampling (Golden Predator);
2. September 19 to 23, 2011 – rock sampling to follow up on Phase 1(Golden Predator);
3. February 15 to February 21, 2012 – auger soil sampling (Kryotek Arctic Innovation Inc.); and,
4. January 2, 2012 to February 28, 2012 – aerial photograph interpretation and commencement of a desktop surficial geology mapping (AECOM and Palmer Environmental Consulting Group Inc.)

For the stream sampling program, crews of approximately ten samplers, plus a cook and helicopter pilot were based in the Little Violet placer camp owned by Wilfred Phillips. All the work was helicopter assisted using a NOTAR supplied by Fireweed Helicopters of Whitehorse, YT. Golden Predator collected 158 silt samples from active stream beds.

During the rock sampling second phase of the program, geologists were based in Whitehorse and flew in to Livingstone daily via helicopter. Golden Predator collected 142 rock samples on the Livingstone main block.

Kryotek used a Whitehorse-based crew of four, with helicopter support to complete its specialized borehole soil sampling program. Kryotek collected 459 ridge and spur soil samples. Trans-North supplied the A-Star helicopter used for this program. All sample sites are shown in Figure 6-1.

The work completed by AECOM and Palmer Environmental Consulting Group Inc. consisted of creating a digital aerial photograph mosaic of 1:50,000 scale black and white aerial photographs for the entire property. This mosaic was later used to complete terrain mapping, aerial photograph interpretation and ultimately soil sampling suitability maps to assist with the 2012 field program (Figure 6-2). The entire property was glaciated during the last glaciation leaving variable amounts of surfical cover.


510,000 520,000 530,000 540,000 550,000 560,000 570,000 580,000

6,840,000
6,830,000
6,820,000
6,810,000
6,800,000

105E15 105E16 105F13 105F14
105E10 105E09 105F12 105F11
105E07 105E08 105F05 105F06
105E02 105E01 105F04

North Big Salmon River
Northern Lake
South Big Salmon River
Big Salmon River
Sheep Creek
Summit Creek
Mendocina Creek
Scurvy Creek
Gray Creek

SRVF
SRVB
SRVE
SRVA
JJW
MCPN
DAC
DACX
SRVD
SRVC
OVS
RNB
RWH



Legend

- GPD Property Outline
- NTS Mapsheet
- 2012 Kyrotek Soil Samples
- 2011 Stream Samples
- 2011 Rock Samples
- Watercourse


GOLDEN PREDATOR

Livingstone

Sample Locations

0 3 6 9 12
Kilometers

Scale:	1:230,000	Map ID:	--
Draw Date:	2012/11/15	Rev. Date:	
Version:	1	Figure:	6-1
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121115_2011Assessment		





Legend

- Golden Predator Property Outline
- Quartz Claim with Grant #
- Watercourse

GOLDEN PREDATOR

Livingstone Property

Aerial Photograph Compliation

0 2 4 6 8

Kilometers

Scale:	1:100,000	Map ID:	--
Draw Date:	2012/12/03	Rev. Date:	--
Version:	1	Figure:	6-2
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District, Yukon Territory		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121203_orthophoto		

6.2 Sampling Methodology and Protocols

Stream Geochemical Program

Stream sediment samples were collected at intervals of approximately 750 m along first, second and third order streams, and immediately upstream of confluences. Samples were also collected in the vicinity of historical RGS stream anomalies, to test repeatability.

Each sample was collected from several points along the active stream bed to produce a representative composite sample. The uppermost sediment was discarded to avoid spurious high content of Fe and Mn oxide coating. The active silt and fine to medium sand that has been recently transported by the stream was the target sediment. This type of sediment was generally located: 1) in the lee of large boulders or logs; 2) in low energy pools at the tail-end of bars; and 3) infilling voids below the surface of cobble-gravel bars.

Samples were sieved in the field to a fraction of less than one-eight inch (<1/8" or 3.36 mm) and placed in labelled, double layered plastic sample bags. Sample sites were flagged and photographed. The sample weights varied between 4-12 kg. Large sample sizes were required to obtain sufficient fine material for the selected assay techniques.

If the drainage contained seasonal stream sediment deposition, but was currently dry, a sediment sample was collected by dry sieving the material. Occasionally the south-facing slopes had underground drainage that sporadically comes to surface, in which case sample spacing sometimes varied.

Sample data was recorded on data cards and included the following: geographic location, sample color, angularity of the clasts, sediment composition (percentage of gravel, sand, silt, clay and organics), slope direction, slope angle, stream flow, vegetation type and comments.

Samples were transported by air from Little Violet Camp/ Livingstone airstrip to Whitehorse by Alkan Air. Samples were delivered by in-house personnel or insured professional expeditors to ALS Chemex's ISO 9001 certified preparation facility in Whitehorse. Samples were dried and screened to 180 microns (80 mesh).

The pulps were analyzed at ALS Chemex's ISO 9001 certified laboratory in North Vancouver using the ultra-trace ME-MS41 package. A 0.5 g sample is digested by aqua regia techniques and 51 elements are analyzed through a combination of ICP-AES and ICP-MS.

The Au-ST44 method was used to analyze gold using a 50 g sample of <80 micron material. This method provides the lowest possible detection limit for gold of 0.0001 – 0.1 ppm, using aqua regia digestion with analysis by ICP-MS. The larger sample size for the gold analysis is used in an effort to reduce potential nugget effects. Samples exceeding the upper limit of Au detection

(0.1 ppm) were re-analyzed using Au-OG44, an ore grade assay technique. A 50 g sample of 180 microns sediment is digested in an aqua regia solution and finished with ICP-MS methods to provide an Au detection range between 0.01 – 100 ppm.

ALS completes quality assurance/ quality control (QA/QC) data verification of their assays through internally inserted duplicates, standards and blanks. In addition, Golden Predator's QA/QC program included the insertion of field duplicates, blanks and standard reference material obtained from CDN Resource Laboratories of Langley, BC. Assay certificates for all analytical programs are compiled in Appendix 3 and the detailed methodology and detection limits are in Appendix 4. Appendix 5 presents the sample locations geochemical plots for select elements for the stream sediment samples collected by Golden Predator in 2011.

Stream sediment samples were ranked by percentile to determine statistical anomalies for the property. Blue circles plot samples ranking in the lower 50th percentile, green circles are samples in the 50th – 75th percentile, yellow circles are 75th - 90th, orange circles are 90 – 95th (labelled) and red circles (labelled) are the upper 5 percentile.

Soil Auger Samples

In February 2012, Kryotek Arctic Innovation Inc. ("Kryotek") of Whitehorse, YT was contracted to collected soil samples using their proprietary handheld drills and tooling. Two crews of two people collected 459 soil samples from a depth of approximately 0.85 m and spaced approximately 50 m apart. The geographic locations and brief description of the samples were recorded at each site. Samples collected were hauled in a small toboggan. Sampling was restricted to the windswept, alpine ridges because snow depth made sampling impossible in other areas. Samples were brought to Acme Analytical's ISO 9001 certified preparation facility in Whitehorse where they were dried, screened and split. The pulps were analyzed at Acme's ISO 9001 certified laboratory in Vancouver. Samples were dissolved in an aqua regia acid solution and then analyzed by ICP-MS methods (package 1DX2-15g). Acme completes quality assurance/ quality control data verification of their assays through internally inserted duplicates, standards and blanks. Assay certificates are compiled in Appendix 3 and the detailed methodology are in Appendix 4. Appendix 6 presents the sample locations and geochemical plots for select elements.

Soil samples were ranked by percentile to determine statistical anomalies for the property. Dark blue circles plot samples ranking in the lower 50th percentile, green circles are samples ranking in the 50th – 75th percentile, yellow circles represent samples in the 75th - 90th percentile, orange circles indicate 90 – 95th percentile and red circles are the upper 5th percentile.

Rock Samples

A total of 142 rock samples were collected to follow up initial results from the stream sediment program. Samples were grabs (float), subcrop or outcrop. The geographic locations and detailed

description of the rocks were recorded at each site. Samples were brought to Acme Analytical's ISO 9001 certified preparation facility in Whitehorse to be crushed, split and pulverized. The pulps were analyzed at Acme's ISO 9001 certified laboratory in Vancouver. Samples were analysed using a four acid digestion with ICP-ES analysis (package 1D) for 25 elements. Gold was analysed using fire assay procedures with an AAS finish (package G6). Assay certificates are compiled in Appendix 3 and the detailed methodology are in Appendix 4. Appendix 7 presents the sample locations for the rocks samples.

6.3 Results

Stream Sediments

Results from the stream sampling program outline several multi-element geochemical anomalies (Appendix 5). The geochemical plot for gold-in-stream sediments identifies several highs (up to 880 ppb; Appendix 5-2). On the SRVF claim group in the northern portion of the property, two top 5 percentile anomalies occurring about 1.5 km apart on the D'Abbadie Creek (100 ppb and 94.2 ppb). Tributaries and samples in the D'Abbadie are also highly anomalous in arsenic, molybdenum, lead, antimony and zinc. The second anomalous gold in streams area occurs in an unnamed creek on the southwestern portion of the SRVF claim block/ northwestern portion of the SRVE claim block. Two of five samples collected have gold values in the top 5 percentile (100 ppb and 98 ppb Au). A third sample has a value in the top 10 percentile for gold. These drainages are also anomalous in arsenic and lead. The highest gold value (860 ppb) occurs in Lake Creek on the DACX claim block. The sample was collected downstream of an inactive placer creek and just upstream of the junction with Cottoneva Creek, which is being actively placer mined. No other elements of interest were also anomalous in the drainage. A tributary to Martin Creek (Martin Creek is immediately south of Livingstone Creek), located on the western side of the RNB claim block assayed 100 ppb Au. The tributary had top 10 percentile values for arsenic and antimony.

Anomalous silver (up to 0.63 ppm), occur in two areas: 1. on a north-south trending unnamed creek occurring on the east side of the SRVE claim block and 2. on the upper reaches of Mendocina Creek and its tributaries, on the SRVC claim block. Area 1 is also highly anomalous in copper and molybdenum whereas Area 2 is highly anomalous in molybdenum, lead, antimony and zinc.

Rocks

Approximately four days were spent conducting preliminary follow-up field work on the Livingstone claim blocks in mid-September. The fieldwork was designed to complete an initial assessment gold-in-stream sediment anomalies resulting from GPD regional sampling program completed in May, 2011. The 142 rock samples were collected in as many target areas as possible but efforts to complete the work were hampered by early snowfall.

Mineralization from hand samples collected in 2011 included:

(i) syngenetic hybrid VMS-SEDEX that has undergone ductile deformation and amphibolite facies metamorphism. Visible mineralization consisted of coarse-grained quartz-galena veins and foliation parallel pyrite ± galena ± sphalerite mineralization (Bennett, 2011). Mineralization was hosted in both graphitic schists of sedimentary origin and intermediate hornblende-biotite schists of probable volcanogenic origin (Bennett, 2011). The best example of this style of mineralization was observed on the MCPN claim block where a grab of subcrop assayed up to 88.6 g/t Ag and 3.17% Pb (sample J971722) and the best outcrop sample assayed 22 g/t Ag and 6.68% Pb (sample J91846; Appendix 7-5).This showing is located at minfile occurrence 105E 064, a lead silver showing.

(ii) Northerly trending shear zones in Cottoneva Creek (DACX claim, Appendix 7-7). Host rock is sericite schist. No visible sulphides were observed. Shear was measured at 340/90. Sample K948206 assayed 1.077 g/t Au and 35 g/t Ag in an outcrop.

Soils

Nine traverse lines were carried out on the DAC, RNB, OVS and SRVD claim block for a total of 459 soil auger samples over approximately 23 line kilometers. Soil samples lines were designed to follow-up from the stream sediment anomalies. Due to poor weather in September, 2011, several areas with gold-in-stream sediment anomalies could not be ground truthed or prospected.

Gold-in-soil anomalies are best on the southern-most soil line, occurring in the RNB and SRVD claim blocks (Appendix 6-8). The stream sediments collected in the drainage basins both north and south of this ridge line were not highly anomalous in any elements of interest. Seventeen soil samples however ranked in the top 10 percentile for gold. The eastern portion of the soil line is very anomalous in silver and zinc, and there are weak anomalies for lead and arsenic. According to the detailed geologic map, the area is underlain by Livingstone succession metavolcanic rocks and marble (Colpron, 2006, Figure 5-2). This area is highly prospective and warrants follow-up.

The ridge line approximately 1.5 km to the north also has several anomalous gold-in-soils anomalous values and is also highly anomalous in silver (particularly on the eastern side), lead with weak arsenic and zinc anomalies. The eastern portion of the soil line is underlain by Livingstone succession metavolcanic rocks and marble and the western portion is underlain by Snowcap Complex quartzites and psammitic schists (Colpron, 2006, Figure 5-2). This area is moderate-highly prospective and warrants follow-up.

The ridge line to the furthest southwest, on the RNB claims lies between former placer producing creeks Martin to the north and Sylvia to the south. The soil line has a few anomalous gold-in-soils samples and is also anomalous in arsenic and antimony with weak coinciding lead anomalies. Underlying rocks consist of Snowcap Complex quartzites and psammitic schists and

chlorite schist units (Colpron, 2006, Figure 5-2). This area is moderately prospective and warrants follow-up.

The soil ridge line north of Martin Creek had weak gold-in soils and moderate lead anomalies and would be considered a tertiary target for follow up. The remainder of the areas covered by the February 2012 soil program are not anomalous in gold and have weak or no other anomalies for elements of interest.

7.0 CONCLUSIONS AND RECOMMENDATIONS

Livingstone is a large property consisting of 3,574 mineral claims covering an area of ~72,216 hectares in the Livingstone placer district in south central Yukon. The property is in the grassroots stages of exploration and has perspective lode gold systems.

The 2011 – early 2012 field program included the collection of 158 stream samples, 142 rock samples, 459 soil auger samples and the beginnings of a surfical geology mapping program. The stream sediment program was effective at identifying several prospective areas. Most of these areas were followed-up with either prospecting/ rock sampling, or with soil sampling. However, some of the areas that warranted follow up did not receive adequate work due to time and weather constraints and should be investigated further.

Most of the results from the rock sampling program were disappointing. Mineralization was found in a few locations but the best gold assay occurred in a northerly trending and vertically dipping shear zone in Cottoneva Creek The host rock is a sericite schist which assayed 1.077 g/t Au and 35 g/t Ag in an outcrop (DACX claim, Appendix 7-7). Silver and lead mineralization occurring in) syngenetic hybrid VMS-SEDEX best results were a grab of subcrop which assayed 88.6 g/t Ag and 3.17% Pb and the best outcrop sample assayed 22 g/t Ag and 6.68% Pb (MCPN block, Appendix 7-5).

Soil samples collected in the headwaters of several placer creeks and areas with stream sediment geochemical anomalies produced several areas that warrant follow-up work that should involve prospecting, rock sampling and additional soil lines. This work will be guided and aided by the terrain mapping and soil suitable maps created by AECOM/ Palmer Environmental to focus soil sampling programs in areas with the most locally-derived cover.

Historic placer production; and favourable host rocks, structures and metamorphic grade make Livingstone a potential lode gold target area, particularly in greenstone belts. The lack of historic exploration and the Quaternary cover make exploring in this district a challenge.

8.0 2011 EXPENDITURES

Expenditures for the four phases of work completed in 2011 and early 2012 were $240,241.12 as summarized in Table 8-1.

Table 8-1. 2011 Expenditures

Phase 1 – Stream Sediment Sampling	**Units**	**Unit Cost**	**Per**	**Cost**
Wages				
Golden Predator Canada Corp.	158	$ 224.14	sample	$ 35,414.12
Management and report writing	10	$ 500.00	day	$ 5,000.00
Transportation				
Helicopter	158	$ 308.17	sample	$ 48,690.86
Fuel	158	$ 78.49	sample	$ 12,401.42
Consumables				
Camp, food, fixed wing etc.	158	$ 162.20	sample	25,627.60
Samples				
Stream Sediment Samples	158	$ 55.00	sample	$ 8,690.00
Total				**$ 135,824.00**
Phase 2 – Rock Sampling/ Prospecting	**Units**	**Unit Cost**	**Per**	**Cost**
Wages				
Golden Predator Canada Corp.	3.5	$ 1,400.00	day	$ 4,900.00
Transportation				
Helicopter	8.1	$ 1,100.00	hour	$ 8,910.00
Fuel	8.1	$ 300.00	hour	$ 2,430.00
Consumables				
Camp, food, fixed wing etc.	3.5	$ 1,062.00	day	3,717.00
Samples				
Rock Sample	142	$ 50.00	sample	$ 7,100.00
Total				**$ 27,057.00**
Phase 3 – Soil Auger Sampling	**Units**	**Unit Cost**	**Per**	**Cost**
Kryotek Arctic Innovation Inc.	459	$ 65.00	sample	$ 29,835.00
Transportation				
Helicopter + Fuel (A-Star)	459	$ 43.00	sample	$ 19,737.00
Consumables				
Sample Bags	459	$ 2.75	bag	$ 1,262.25
Assays				
Acme Analytical Laboratory	459	$ 25.00	sample	$ 11,475.00
Golden Predator Management				
Planning	8	$ 500.00	man days	2,000.00
Reporting	6	$ 500.00	man days	$ 1,500.00
Total				**$ 65,809.25**
Phase 4 - Aerial Photo Compilation	**Units**	**Unit Cost**	**Per**	**Cost**
Terrain Mapping (2151 of 4685 claims)	2151	$ 5.37	claim	$ 11,550.87
Total				**$ 11,550.87**

Phases 1-4 TOTAL	**$ 240,241.12**

9.0 STATEMENT OF AUTHORSHIP

This Report titled "Assessment Report, 2011 Geochemical Sampling and Surficial Geology Mapping Program, Livingstone Project, Whitehorse Mining Division, Yukon Territory, Canada", and dated December 4th, 2012 was prepared and signed by the following author:

Erin O'Brien, M.Sc., P.Geo.
Dated: December 4th, 2012
Vancouver, British Columbia



10.0 REFERENCES

Ash, C. H., 2001: Relationship between Ophiolites and Gold-Quartz Veins in the North American Cordillera. Department of Energy, Mines and Petroleum Resources, Bulletin 108, 140 p.

Ash, C. and Aldrick, D., 1996: Au-quartz Veins, in Selected British Columbia Mineral Deposit Profiles, Volume 2 - Metallic Deposits, Lefebure, D.V. and Höy, T., Editors, British Columbia Ministry of Employment and Investment, Open File 1996-13, p. 53-56.

Bennett, V, 2011: Livingstone Follow-up Fieldwork – Summary Memo. In-house memo prepared for Golden Predator Canada Corp., dated September 29, 2011.

AECOM and Palmer Environmental Consulting Group Inc., 2012: Surficial Terrain Assessment and Mapping for Strategic Exploratory Sampling at the Livingstone District, Yukon. In-house report prepared for Golden Predator Canada Corp., dated June 12, 2012, 47 p. and appendices.

Bond, J.D., 2007: Late Wisconsinan McConnell Glaciation of the Big Salmon Range, Yukon. In: Yukon Exploration and Geology 2006, D.S. Emond, L.L. Lewis and L.H. Heston (eds.),Yukon Geological Survey, p. 105-122.

Colpron, M., 2006. Geology and Mineral Potential of Yukon-Tanana Terrane in the Livingstone Creek Area (NTS 105E/8), south-central Yukon. In: Yukon Exploration and Geology 2005, D.S. Emond, G.D. Bradshaw, L.L. Lewis and L.H. Weston (eds.), Yukon Geological Survey, p. 93-107.

Colpron, M., Gladwin, K., Johnston, S. T., Mortensen, J. K. and Gehrels, G. E., 2005, Geology and Juxtaposition History of Yukon-Tanana, Slide Mountain and Cassiar Terranes in the Glenlyon area of Central Yukon: Canadian Journal of Earth Sciences, v. 42, p. 1431-1448.

Colpron, M., Murphy, D., and Nelson, J.L., 2011. Cretaceous Crustal Structures in Yukon and Implications for Gold mineralization in the Northern Cordillera. Poster, Roundup, Vancouver 2011. Retrieved from: http://ygsftp.gov.yk.ca/publications/posters/Round_Up_2011/Colpron%20Roundup%202011.pdf.

Dubé, B., and Gosselin, P., 2007, Greenstone-hosted Quartz-Carbonate Vein deposits. Mineral Deposits of Canada: A Synthesis of Major Deposit-Types, District Metallogeny, the Evolution of Geological Provinces, and Exploration

Methods, Goodfellow, W.D. (ed.), Mineral Deposits Division, Geological Association of Canada, Special Publication 5, p. 49-73.

Gordey, S.P. and Makepeace, A.J. (compilers), 2001. Bedrock Geology, Yukon Territory; Geological Survey of Canada. Open File 3754 and Exploration, Exploration and Geological Services Division, Yukon and Northern Affairs Canada, Open File 2001-1, scale 1: 1,000,000.

Nelson, J.L. and Colpron, M., 2007. Tectonics and Metallogeny of the Canadian and Alaskan Cordillera, 1.8 Ga to Present. In: Mineral Deposits of Canada: A Synthesis of Major Deposit Types, District Metallogeny, the Evolution of Geological Provinces, and Exploration Methods, W.D. Goodfellow (ed.), Mineral Deposit Division, Geological Association of Canada, Special Publication 5, p. 755-791.

Robb, L.J. (2005) Introduction to ore-forming processes. Blackwell, Malden, p.190-197.Yukon Placer Mining Industry 2007-2009. W.P. LeBarge and M.G. Nordling (compilers), 2011. Yukon Geological Survey, 151 p.

Yukon Placer Mining Industry 2007-2009. W.P. LeBarge and M.G. Nordling (compilers), 2011. Yukon Geological Survey, 151 p.

Appendix 1
Statement of Qualifications

Erin Kathleen O'Brien
501 – 77 Walter Hardwick Ave.
Vancouver, British Columbia
V5Y 0C6
Telephone: 778-928-7232
E-mail: eobrien@goldenpredator.com

CERTIFICATE OF AUTHOR

I, Erin Kathleen O'Brien of Vancouver, British Columbia, certify that:

1. I am a graduate of McGill University of Quebec with a B.Sc. Joint Major in Geology and Environmental Studies, in 1994 and a M.Sc. in Geology from the University of New Brunswick in 1996;
2. I have practiced my profession as a mineral exploration or environmental geologist with Caracle Creek International Consultants Inc., Golder Associates Ltd., Morrow Environmental Consultants Inc. (SNC Lavalin Environment) and as a geological consultant for 15 years, where I have been involved with the geological exploration of precious and base metal properties and deposits in a variety of capacities;
3. I have been operating a business as a geological consultant under my own name since 1996, and consulted for Golden Predator Canada Corp. between September, 2009 and March 2010. I became a full time employee of Golden Predator Canada Corp. in April, 2010.
4. I am a Professional Geoscientist registered with the Association of Professional Geoscientists and Engineers of British Columbia and have been since 2001;
5. I am author of this Report "Assessment Report, 2011 Geochemical Sampling and Surficial Geology Mapping Program, Livingstone Project, Whitehorse Mining Division, Yukon Territory, Canada" dated December 4th, 2012; and
6. I have reviewed the geological data and am not aware of any material facts or change in facts at the time this certification is dated.

E O'Brien

Erin Kathleen O'Brien, M.Sc., P.Geo.

PROFESSIONAL ENGINEERS PROVINCE OF BRITISH COLUMBIA E.K. O'BRIEN 25531 dec 4 2012 GEOSCIENTIST

Vancouver, British Columbia
Dated this 4th Day of December, 2012

Appendix 2
Analytical Summary

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Ang	Colr	Grvl %	Sand %	Silt %	Org %	Slope Dir	Slope Ang	Strm Flow	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRVA	K735001	SSed	548515	6813785	1280	30-May-11	SA	GYD	20	70	10		S	2	4	0.7	0.08	13.2	12.2	121	Schist, qtz, granite
SRVA	K735002	SSed	548955	6813463	1337	30-May-11	SA	BK	30	40	20	10	SW	1	2	1.2	0.06	9.9	6.8	92	Granite
MCPN	K735003	SSed	548180	6812644	1156	30-May-11	SA	GY	50	40	10		SW	2	4	0.4	0.09	12.2	9.8	93	SS, granite
SRVA	K735004	SSed	548871	6811884	1177	30-May-11	SA	GY		40	40	20	SW	2	5	0.1	0.05	6.3	8.6	82	Phyllite, Organics (mix)
JJW	K735005	SSed	538100	6812385	932	31-May-11	SA	GRD	60	30	10		S	3	4	2.9	0.07	36.1	4.4	52	Abundant qtz boulders
JJW	K735006	SSed	538805	6812706	895	31-May-11	SA	BRL	70	20	10		SE	2	4	0.5	0.04	14	3.7	47	waterfall, cliff
JJW	K735007	SSed	538396	6818034	906	31-May-11	SR	GRL	10	70	20		NE	1	3	6.1	0.13	20.8	7	47	Possible lake bottom quartz w pyrite
JJW	K735008	SSed	538573	6817889	908	31-May-11	SR	GYL	40	50	10		NW	2	5	65.8	0.08	15.7	6.2	52	
JJW	K735009	SSed	537036	6819605	1035	31-May-11	SA	GYL	40	50	10		E	2	5	1	0.05	12.2	6	51	Many channels diverted from main
JJW	K735010	SSed	536988	6819838	1043	31-May-11	SR	OR	40	50	10		SE	2	4	1.1	0.04	14	7.8	49	Granite, qtzite, phyllite
JJW	K735011	SSed	538856	6819471	862	31-May-11	SA	RDD	30	60	10		NE	2	4	17.9	0.07	15.2	7.5	50	
MCPN	K735012	SSed	543427	6819145	1247	01-Jun-11	SR	ORL	40	50	10		SW	2	4	26.4	0.07	17.3	15.2	97	Creek diverted
JJW	K735013	SSed	543106	6818887	1212	01-Jun-11	A	BRL	50	30	20		NW	2	3	1.2	0.06	18.1	12.8	83	Creek diverted
JJW	K735014	SSed	542909	6818832	1206	01-Jun-11	A	BRL	60	20	20		NW	3	3	1	0.1	23.5	10.6	86	Creek diverted
JJW	K735016	SSed	542634	6819024	1161	01-Jun-11	SA	GYD	70	30			NW	3	5	1.3	0.07	15.8	11.3	80	
JJW	K735017	SSed	541872	6818619	1136	01-Jun-11	SA	BRL	50	30	20		N	2	4	2.8	0.08	18.1	10.4	64	Permafrost in creek, sample sites switched
JJW	K735018	SSed	542008	6818718	1123	01-Jun-11	SA	ORL	50	40	10		NW	2	3	1.5	0.07	17.9	9.9	64	Permafrost in creek, sample sites switched
JJW	K735019	SSed	540003	6819683	909	01-Jun-11	SR	BRL	50	50			N	2	5	6.3	0.05	14.5	8.2	59	
SRVE	K735020	SSed	545305	6833975	1169	02-Jun-11	SA	BRL	70	20	10		S	2	4	1	0.25	66.6	8.5	175	
SRVE	K735021	SSed	545633	6833741	1176	02-Jun-11	SA	GRD	60	40			W	3	5	1.7	0.13	76.6	5.1	99	
SRVE	K735022	SSed	545536	6832277	1062	02-Jun-11	SR	GR	70	20	10		W	2	5	0.9	0.05	72.5	2.4	41	

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Ang	Colr	Grvl %	Sand %	Silt %	Org %	Slope Dir	Slope Ang	Strm Flow	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRVE	K735023	SSed	545213	6832323	1036	02-Jun-11	SR	BR	60	30	20		S	2	5	2.6	0.13	57.4	6.9	114	Very fast - taken where possible (side)
SRVE	K735024	SSed	545077	6830743	957	02-Jun-11	SR	GR	60	40	10		S	2	5	0.8	0.19	48.4	5.1	81	
SRVE	K735025	SSed	544856	6830309	951	02-Jun-11	SR	GY	50	40	10		SE	3	4	5.2	0.4	47.3	12.8	149	Big qtz boulders
SRVF	K735026	SSed	538933	6841727	1144	03-Jun-11	SA	BRL	50	30	20		N	3	4	5.1	0.24	26.9	16.5	90	
SRVF	K735027	SSed	540221	6842848	1020	03-Jun-11	SR	GRL	40	60			NE	2	4	94.2	0.24	31.9	12.1	127	
SRVF	K735028	SSed	539728	6845760	1126	03-Jun-11	SA	GRD	40	40	20		N	1	3	4.5	0.1	14.1	6.8	60	Dry, sample from upper pond (lake)
SRVF	K735029	SSed	537360	6836116	881	03-Jun-11	SR	BRL	40	50	10		W	2	3	42.1	0.04	22.6	11.1	55	
SRVB	K735031	SSed	540817	6837315	954	03-Jun-11	SA	BRL	50	50			S	3	3	3.8	0.19	37.5	14.6	84	
SRVD	K735032	SSed	550546	6808651	1346	04-Jun-11	SA	GYD	70	20	10		NW	2	4	0.3	0.14	21	7	129	intrusives, subalpine, willows
SRVD	K735033	SSed	550381	6808498	1341	04-Jun-11	SA	GYD	80	20	0		N	3	4	27.6	0.18	17.1	7.4	131	intrusives, subalpine, willows
SRVD	K735034	SSed	550659	6809481	1234	04-Jun-11	SA	GYD	80	20	0		E	3	4	0.3	0.16	17.7	7.4	129	willows
SRVD	K735035	SSed	550334	6810259	1229	04-Jun-11	SR	BRL	80	20	0		NW	2	4	0.05	0.07	5.6	6.8	93	intrusives
SRVD	K735036	SSed	546504	6803827	1090	05-Jun-11	SA	BRL	90	10	0		N	3	4	0.2	0.09	26.5	3.9	72	schist
SRVD	K735037	SSed	549715	6803369	1192	05-Jun-11	SR	GYL	80	20	0		SW	3	4	1.5	0.09	41.6	4.5	89	intrusives, siltstone, qtzite
SRVD	K735038	SSed	548705	6803546	1119	05-Jun-11	SR	GYD	80	10	10		S	2	3	3	0.13	29	6.7	118	schist, creek besides Lone Wolf Outfitter cabin
SRVD	K735039	SSed	547072	6804124	1094	05-Jun-11	SR	OR	80	20	0		N	3	3	1.6	0.09	30	6.7	74	qtzite, schist
DAC	K735040	SSed	545668	6804462	1101	05-Jun-11	SR	GYL	70	30	0		S	3	3	1.1	0.1	19	5.3	68	schist, qtzite, gneiss
SRVD	K735041	SSed	546564	6803302	1171	05-Jun-11	SR	GYL	80	10	10		S	3	4	2.6	0.13	29.4	4.6	87	gneiss
SRVD	K735042	SSed	548187	6803210	1126	05-Jun-11	SR	GYL	80	20	0		NE	3	4	0.5	0.06	14	4	59	muscovite schist
SRVD	K735043	SSed	548760	6795746	1375	06-Jun-11	SR	BRL	90	10	0		S	3	4	0.7	0.08	25.3	5.2	57	green schist, intrusives
SRVD	K735044	SSed	549089	6795629	1387	06-Jun-11	SR	BRL	80	20	0		W	3	3	0.1	0.06	10.4	4.3	35	mafics. Has a Duplicate

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Ang	Colr	Grvl %	Sand %	Silt %	Org %	Slope Dir	Slope Ang	Strm Flow	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRVD	K735046	SSed	551472	6794926	1216	06-Jun-11	SR	BRL	80	20	0		SW	3	4	0.05	0.03	11.3	2.9	30	gneiss
SRVD	K735047	SSed	550601	6795050	1234	06-Jun-11	SA	RD	90	10	0		SW	3	4	0.7	0.23	30.6	16.3	98	granite, green schist, avalanche path
RWH	K735048	SSed	549042	6794261	1161	06-Jun-11	SA	BRL	80	20	0		S	4	4	0.4	0.06	18.7	5.2	46	intrusives
RWH	K735049	SSed	548502	6793559	1159	06-Jun-11	SA	BRL	90	10	0		NW	3	4	6.2	0.04	8.6	3.4	35	intrusives, gneiss
OVS	K735050	SSed	546009	6795319	1382	06-Jun-11	SA	BRL	90	10	0		S	3	4	20.1	0.11	15.6	7.8	44	gneiss, granite
MCPN	K735051	SSed	545768	6812574	1102	31-May-11	SA	GYD	40	30	30		S	2	4	0.6	0.06	17.1	9.3	78	
MCPN	K735052	SSed	545088	6812662	1081	31-May-11	SA	BR	20	50	30		S	1	3	1.4	0.04	8.8	9.1	40	
JJW	K735053	SSed	543208	6812745	1043	31-May-11	SA	BRL	10	50	40		S	1	3	1.7	0.04	6.6	5.5	33	
MCPN	K735054	SSed	544915	6816946	1321	31-May-11	SA	BRD	50	30	20		W	2	4	1.8	0.15	31.7	11.9	111	Deep pools
MCPN	K735055	SSed	544930	6816772	1306	31-May-11	A	BR	40	30	30		NW	2	4	0.7	0.11	30.1	25.8	103	Fast water - silt hard to collect
MCPN	K735056	SSed	544576	6816749	1267	31-May-11	SA	BR	10	50	40		N	2	5	0.3	0.03	13.6	9.5	82	
MCPN	K735057	SSed	544313	6816960	1231	31-May-11	SA	BRD	30	30	10		W	2	5	9.4	0.07	18.2	13.2	87	
JJW	K735058	SSed	544210	6817079	1225	31-May-11	SA	BR	30	40	30		S	2	4	0.6	0.09	17.5	11.7	145	
JJW	K735059	SSed	540854	6816238	997	31-May-11	SA	GYD	10	40	50		N	2	4	3.4	0.07	28.6	9.2	76	
JJW	K735060	SSed	540213	6816537	978	31-May-11	SA	GYD	20	40	40		NW	2	4	0.4	0.05	34.5	8.8	69	
SRVA	K735061	SSed	547430	6816224	1372	01-Jun-11	SA	BRL	50	30	20		N	2	4	0.4	0.21	26.5	11	90	Quartzite
SRVA	K735062	SSed	547469	6816517	1361	01-Jun-11	A	BR	30	40	20	1	NE	2	4	1.5	0.12	18.7	9.6	83	Ground frozen
SRVA	K735063	SSed	548837	6816405	1136	01-Jun-11	SR	GYD	50	30	20		NE	2	4	0.1	0.15	20.1	10.6	151	
SRVA	K735064	SSed	548926	6816314	1128	01-Jun-11	SR	GYD	40	30	30		N	2	4	0.3	0.14	20.8	15.1	131	
SRVA	K735066	SSed	549151	6816941	1027	01-Jun-11	SR	BR	50	30	20		N	2	5	1.1	0.12	16.1	10.3	102	
SRVA	K735067	SSed	549080	6817414	1006	01-Jun-11	SR	BR	30	40	30		W	2	4	0.2	0.05	9.5	10.4	67	

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Ang	Colr	Grvl %	Sand %	Silt %	Org %	Slope Dir	Slope Ang	Strm Flow	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
JJW	K735068	SSed	543538	6816853	1190	01-Jun-11	A	BR	50	30	20		S	2	1	0.7	0.07	19.8	9.3	49	No water
JJW	K735069	SSed	541831	6815866	1096	01-Jun-11	A	BR	20	50	30		N	2	4	3.1	0.06	21	9.9	46	
SRVA	K735070	SSed	535948	6823131	972	02-Jun-11	SA	BRL	20	40	40		NE	2	4	0.9	0.04	14.6	10.2	42	
SRVA	K735071	SSed	540128	6822963	735	02-Jun-11	SR	GY	20	20	60		N	2	5	0.3	0.11	13.9	5.4	40	Underground downstream - sampled higher than mark
SRVE	K735072	SSed	541597	6824744	803	02-Jun-11	SA	GY	30	40	20	10	S	2	4	0.1	0.1	16.3	8.1	41	
SRVE	K735073	SSed	543518	6824756	749	02-Jun-11	SA	GY	30	40	30		SW	2	4	1.4	0.12	24.6	7.2	83	
SRVE	K735074	SSed	545996	6824622	710	02-Jun-11	SR	GY	30	30	40		SE	2	5	8.8	0.19	32.2	7.9	99	
SRVA	K735075	SSed	544459	6823912	725	02-Jun-11	SR	GY	30	40	30		N	2	4	0.4	0.21	25.5	9.5	130	
SRVA	K735076	SSed	543273	6824041	697	02-Jun-11	SR	BR	30	40	30		N	2	4	2	0.08	15.3	7	65	
SRVB	K735077	SSed	547120	6837019	1114	03-Jun-11	SA	GYL	10	50	40		W	2	3	0.2	0.06	15.5	8	63	
SRVB	K735078	SSed	545030	6837704	1056	03-Jun-11	SA	GY	30	40	30		SW	2	4	0.2	0.14	17.3	18.8	485	
SRVB	K735079	SSed	544334	6837729	1039	03-Jun-11	SA	GY	20	40	40		NE	2	4	9.4	0.11	41.1	5.4	122	Location not same as on given map, not from main channel
SRVB	K735081	SSed	543599	6837984	1013	03-Jun-11	SA	GY	40	30	30		S	2	4	0.3	0.18	21.1	15.4	133	
SRVB	K735082	SSed	542264	6837892	993	03-Jun-11	SA	GY	30	30	40		S	2	3	44.2	0.14	24.5	11.7	88	
SRVD	K735083	SSed	546604	6811549	1177	04-Jun-11	SA	GYL	60	20	20		N	2	5	1.2	0.14	16.2	8.3	106	Granite boulders
MCPN	K735084	SSed	546583	6811685	1155	04-Jun-11		GYD	10	10	40	40	NW	2	3	0.7	0.07	11.4	7.2	58	Creek very overgrown with moss, not in map location
SRVD	K735085	SSed	549017	6810701	1194	04-Jun-11	SA	BRD	30	40	30		N	2	4	0.7	0.21	23.4	10.4	154	Small granite boulders and phyllite
SRVD	K735086	SSed	549329	6810452	1206	04-Jun-11	SA	BRD	10	30	30	30	N	2	1	0.6	0.38	19.3	12.1	317	Dry creek, not in lower valley. Granite boulders
SRVC	K735087	SSed	554022	6801521	1224	05-Jun-11	SA	GRD	60	30		10	SW	2	3	0.1	0.27	25.2	9.4	252	Schist, minor granite coarse gr
SRVC	K735088	SSed	552837	6801549	1204	05-Jun-11	SA	GRD	70	30			SW	2	3	0.5	0.34	42	10.9	224	Small gravel chips of metaseds

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Ang	Colr	Grvl %	Sand %	Silt %	Org %	Slope Dir	Slope Ang	Strm Flow	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRVC	K735089	SSed	553303	6801125	1219	05-Jun-11	SA	BR	70	30			N	2	3	0.1	0.45	23.3	19.5	374	Rusty schist with oxide stained qtz sweats along folitation
SRVC	K735090	SSed	552362	6801117	1203	05-Jun-11	SA	BR	70	30			N	2	3	0.3	0.63	39.7	16.1	336	Mixed boulders, schist, granodiorite
SRVC	K735091	SSed	551613	6801245	1188	05-Jun-11	SR	BR	70	20	10		N	2	3	0.2	0.38	41.1	14.6	418	Metaseds, mica schist, bull moose nearby, 2% qtz
SRVC	K735092	SSed	550619	6801667	1169	05-Jun-11	SA	BR	70	20	10		N	2	3	0.05	0.26	25.2	10.2	222	Metaseds, bio qtz schist
SRVD	K735093	SSed	549795	6802141	1129	05-Jun-11	SA	BR	60	30	10		N	2	3	0.05	0.09	15.9	5.8	113	500m outcrop along main river rusty stained metaseds
SRVD	K735094	SSed	549269	6802538	1142	05-Jun-11	SA	BRL	50	40	10		N	2	3	0.1	0.13	15.3	5.8	121	
SRVC	K735096	SSed	552546	6799046	1457	05-Jun-11	SA	BRL	60	20	20		S	3	3	0.05	0.04	6.8	4.8	34	
RWH	K735097	SSed	547507	6791889	1115	06-Jun-11	SR	BRL			100		N	2	4	0.1	0.03	7.4	3.1	23	
RWH	K735098	SSed	546293	6793190	1110	06-Jun-11	SR	BRL			80	20	S	2	3	3.2	0.05	9.9	6.1	24	Small granite boulders
RNB	K735099	SSed	541648	6793164	1099	06-Jun-11	SA	BR	60	20	20		S	4	4	5.1	0.08	26.9	6.1	56	Mica, Granite boulders
RNB	K735100	SSed	540995	6794713	1349	06-Jun-11	SA	BR	70	20	10		W	4	4	1.8	0.03	10.1	3.5	33	Granite, schists, muscovite
MCPN	K735101	SSed	546278	6812187	1091	31-May-11	R	GYD	90	10			N	2	5	0.3	0.13	16	7.2	94	Small sample, big boulders
MCPN	K735102	SSed	545817	6812193	1081	31-May-11	SR	GYD	80	20			N	3	5	0.9	0.05	8.2	6.2	56	1/3 sample taken 100m upstream
JJW	K735103	SSed	544509	6812383	1074	31-May-11	R	GYL	10	40	50		N	2	4	0.05	0.08	11.8	6.3	45	Presence of muck
JJW	K735104	SSed	543212	6812300	1061	31-May-11	SA	GY	40	40	20		N	3	5	0.5	0.08	12.7	6.4	56	
JJW	K735105	SSed	543162	6816189	1160	31-May-11	SR	BR	80	20			NW	2	4	1.1	0.03	15.4	8.8	50	1/3 of sample from up stream of point
JJW	K735106	SSed	542918	6816373	1119	31-May-11	SA	GY	70	20			NW	2	1	1.2	0.06	28.7	13.4	72	Dry sample
SRVA	K735107	SSed	548029	6818406	1058	01-Jun-11	SR	GYD	70	20	10		E	3	3	0.8	0.1	34.1	6.2	185	Small creek, Schist
SRVA	K735108	SSed	548102	6818214	1036	01-Jun-11	SR	GYL	70	30			E	3	5	0.7	0.11	33.7	8.4	127	Intrusives, Schist
SRVA	K735109	SSed	548239	6818075	1031	01-Jun-11	SR	GY	60	30	10		NE	4	5	0.4	0.12	24.5	9	160	Quartzite, Schist (Limestone?)

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Ang	Colr	Grvl %	Sand %	Silt %	Org %	Slope Dir	Slope Ang	Strm Flow	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRVA	K735110	SSed	548550	6818329	970	01-Jun-11	SR	GY	70	20	10		E	4	5	0.1	0.12	21.6	9.9	133	Siltstone, sandstone, granite
SRVA	K735111	SSed	549041	6818566	989	01-Jun-11	SR	BR	60	20	20		W	3	5	0.05	0.05	5.3	7.3	37	Has a Duplicate
SRVA	K735113	SSed	548134	6820214	875	01-Jun-11	SR	BR	70	20	10		N	3	5	9.3	0.11	17.3	7.4	139	Augen gneiss
SRVA	K735114	SSed	547480	6822783	745	01-Jun-11	SR	BR	60	30	10		NW	3	5	0.5	0.13	18.5	8.5	140	Bear den
SRVE	K735116	SSed	538224	6826524	785	02-Jun-11	SR	GYD	70	20	10		W	3	5	26.8	0.05	16	10.4	44	Intrusives
SRVE	K735117	SSed	537764	6826715	781	02-Jun-11	SR	BR	80	10	10		SW	3	5	0.4	0.04	11.6	8.2	33	Intrusives + schist
SRVE	K735118	SSed	537013	6829187	824	02-Jun-11	SR	GY	80	10	10		NW	3	5	1.3	0.04	14.2	7.3	35	Intrusives
SRVE	K735119	SSed	536938	6829410	806	02-Jun-11	R	GYD	80	10	10		S	3	5	60	0.06	19.1	10.2	46	Intrusives
SRVF	K735120	SSed	537729	6831176	933	02-Jun-11	SR	BR	80	10	10		S	3	5	22.9	0.04	14.6	8.1	41	Intrusives
SRVF	K735121	SSed	538013	6830889	921	02-Jun-11	SR	BR	80	20			W	3	5	98	0.08	18.4	16.2	47	Intrusives + sltst
SRVB	K735122	SSed	540570	6831427	1151	02-Jun-11	SR	BR	80	10	10		W	3	5	61	0.19	18.9	19.9	61	Intrusives + sltst
SRVF	K735123	SSed	544208	6841405	1199	03-Jun-11	SR	BR	70	20	10		NW	2	5	1.3	0.13	23.1	16.2	125	Quartzite, siltstone, intrusives, muscovite, schist
SRVF	K735124	SSed	544065	6841148	1227	03-Jun-11	SR	GY	60	30	10		N	3	5	3.9	0.1	50.2	23.9	302	Quartzite and gneiss
SRVF	K735125	SSed	543625	6841839	1193	03-Jun-11	SA	BK	70	20	10		S	3	5	1.2	0.28	35.5	14.3	198	shale, carbononaceous
SRVF	K735126	SSed	543276	6841821	1141	03-Jun-11	SR	BR	90	10			W	3	5	3.1	0.12	28.8	13.4	125	intrusives, gneiss, muscovite schist
SRVF	K735127	SSed	542459	6842178	1129	03-Jun-11	SA	GYD	80	20			SW	3	4	3.3	0.3	41.7	13.2	138	schist
DAC	K735128	SSed	540151	6811276	912	04-Jun-11	SA	BR	60	30	20		NE	2	4	0.6	0.07	49.6	5	65	Stream offset south of map
DAC	K735129	SSed	537686	6811342	853	04-Jun-11	SA	BR	30	40	30		N	3	1	0.4	0.04	22	3.6	49	No water in stream, granite, gneiss, qtzite
DAC	K735130	SSed	537011	6811587	852	04-Jun-11	SA	BR	50	20	20	10	N	3	1	1.2	0.04	24.8	3.9	54	No water in stream
DAC	K735131	SSed	534204	6811624	819	04-Jun-11	SA	BR	10	40	50		N	3	3	1.9	0.04	16.6	3.8	38	Qtzite
DAC	K735132	SSed	543486	6804308	1028	05-Jun-11	SR	GY	70	30			E	1	5	0.1	0.17	26	8.2	186	Taken at downstream tip of island of main drainage

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Ang	Colr	Grvl %	Sand %	Silt %	Org %	Slope Dir	Slope Ang	Strm Flow	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
DAC	K735133	SSed	542014	6804949	1007	05-Jun-11	SA	BRL	10	50	40		NE	2	4	0.2	0.05	13.6	3.8	53	Plenty of fines, metaseds
RNB	K735134	SSed	541024	6806204	1017	05-Jun-11	SR	BRD	30	30	30	10	E	2	4	1.4	0.08	19.6	5.2	66	most fines in moss
DAC	K735135	SSed	540726	6807206	1024	05-Jun-11	SR	BRD	80	20			SE	3	5	0.5	0.07	24.4	3.8	63	
DAC	K735136	SSed	541508	6808257	991	05-Jun-11	A	GYD	70	20	10		W	4	5	1.9	0.13	30.2	6.6	89	large boulders in stream, mafic volc outcrops
DAC	K735137	SSed	541050	6809660	942	05-Jun-11	SA	GYD	60	30	10		W	3	4	1	0.12	43.7	7.3	120	
DAC	K735138	SSed	543944	6807943	1183	05-Jun-11	SA	BRD	70	20	10		S	2	4	0.8	0.14	25.6	8.2	83	
DAC	K735139	SSed	544048	6807826	1185	05-Jun-11	SA	GYD	70	30			W	2	5	1.3	0.11	23.7	8.3	96	
DAC	K735140	SSed	545395	6797607	1499	06-Jun-11	A	BRL	10	50	40		SW	3	4	9.6	0.19	32.8	13.4	45	Alpine many fines
DAC	K735141	SSed	545202	6797570	1484	06-Jun-11	A	BR	80	20			SW	3	5	8.2	0.19	22.9	10.9	53	Alpine
DAC	K735142	SSed	544110	6800637	1370	06-Jun-11	SA	OR	40	40	20		NW	2	4	0.6	0.05	12.2	3.5	36	Stream offset from map
RNB	K735143	SSed	539810	6801138	1256	06-Jun-11	SA	BR	20	50	20	10	S	2	4	5	0.05	7.3	3	49	
DAC	K735144	SSed	546152	6799840	1494	06-Jun-11	A	BR	70	20	10		NW	3	4	0.5	0.05	20.1	4.1	46	Alpine
RNB	K735146	SSed	543557	6802533	1267	06-Jun-11	SA	BR	70	20	10		N	4	5	0.5	0.09	14.9	3.7	58	
JJW	K735151	SSed	541652	6820689	1121	01-Jun-11	SA	GYD	20	50	20	10	NW	4	4	16.4	0.07	15.9	9.9	62	Main drainage to fast - sample from side drainage
SRVA	K735152	SSed	540148	6821553	844	01-Jun-11	SR	BR	40	50	10		NW	3	4	2.1	0.05	11.6	7.3	50	Heterogeneous mix of clasts
SRVA	K735153	SSed	539578	6821604	788	01-Jun-11	SR	GY	60	30	10		N	2	5	2.2	0.11	14	5.6	40	Fast flowing creek to big to cross
SRVE	K735154	SSed	545219	6828429	876	02-Jun-11	SA	GYD	50	40	10		W	2	4	0.7	0.19	23.5	7.9	116	Abundant qtz boulders predominantly qtz phyllite
SRVE	K735155	SSed	545131	6828575	863	02-Jun-11	SR	GYD	30	40	20		S	2	5	2.1	0.34	42.3	9.5	120	Fast flowing creek, abundant fines, phyllite, qtz boulders, minor clay
SRVE	K735156	SSed	545535	6826957	799	02-Jun-11	SR	GYD	30	40	30		S	2	5	6.6	0.25	39.7	9	110	Difficult to sample - fast, abundant silt
SRVE	K735157	SSed	543686	6829072	1132	02-Jun-11	SA	GY	40	40	20		S	2	4	1.1	0.15	29	7.7	112	Fast flow narrow channel, Phyllite and qtz

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Ang	Colr	Grvl %	Sand %	Silt %	Org %	Slope Dir	Slope Ang	Strm Flow	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRVE	K735158	SSed	543512	6826717	957	02-Jun-11	SA	PKL	70	30			S	3	4	1.4	0.1	27.3	6.7	95	Large porphyritic granite boulders in creek, few fines
SRVF	K735159	SSed	543776	6845386	1270	03-Jun-11	SA	OR	40	50	10		NW	2	3	0.6	0.06	6.4	4.9	51	75% orange stained intrusive, 23% phyllite, 2%qtz
SRVF	K735160	SSed	543873	6845605	1267	03-Jun-11	SA	OR	40	50	10		NW	2	3	1.2	0.07	8.3	6.2	67	Similar to previous, creek offset on map
SRVF	K735161	SSed	544810	6843749	1444	03-Jun-11	SA	OR	50	40	10		W	2	3	4	0.06	14.9	7.7	55	Alpine cg granodiorite, 5% qtz with ox str
SRVF	K735162	SSed	541509	6842227	1060	03-Jun-11	SR	GY	70	30			W	2	3	70	0.24	36.7	12.7	148	Very few fines, tough to sample
SRVF	K735163	SSed	540752	6842574	1047	03-Jun-11	SR	GY	60	30	10		N	2	3	51.7	0.23	34.7	13.5	121	Abundant coarse intrusive gravel, 5% rusty qtz
SRVF	K735164	SSed	536831	6838594	1129	03-Jun-11	SA	GYD	60	30	10		SW	3	3	1.5	0.07	22.8	13	77	Small creek, abundant mica phyllite and qtz
DACX	K735166	SSed	533929	6808922	828	06-Jun-11	SR	BRL	60	20	10		N	2	3	3.7	0.06	31.5	4.9	40	Disturbed site below place camp. Minor clay
DACX	K735167	SSed	533866	6806667	807	06-Jun-11	SR	BR	60	30	10		W	2	4	860	0.09	37.6	10.4	34	Abundant qtz boulders in creek, some with oxide stain
DACX	K735168	SSed	534094	6806218	816	06-Jun-11	SA	OR	30	60	10		N	1	3	10.9	0.05	20.9	5	38	swampy area, abundant fines.
RNB	K735251	SSed	537105	6796658	1014	06-Jun-11	SR	BRL	70	20	10		W	3	4	10	0.06	22	10.4	41	Sampled at intersection of main creek (placer workings)
RNB	K735252	SSed	540042	6797101	1366	06-Jun-11	SA	BRL	40	40	20		W	3	4	7.5	0.03	14.1	2.8	27	
RNB	K735253	SSed	539662	6798553	1253	06-Jun-11	SA	BR	50	30	20		NW	3	3	4.5	0.08	19.8	6.6	65	
RNB	K735254	SSed	539848	6798728	1241	06-Jun-11	SR	BRD	80	10	10		SW	3	3	29.8	0.06	13.9	4	44	

Key

Color				
D	dark		YE	yellow
L	light		OR	orange
GY	grey		GR	green
BK	black		PK	pink
RD	red		TA	tan
BR	brown		CW	cream
RBR	red brown			

Clast angularity	
WR	well rounded
R	rounded
SR	subrounded
SA	subangular
A	angular

Slope Angle	
1	flat (<5°)
2	gentle (<5-15°)
3	moderate (<15-25
4	steep (>25°)

Stream Flow	
1	dry
2	stagnant
3	slow
4	moderate
5	fast

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRV	K960051	soil	545242	6795179	1639	17-Feb-12	0.25	0.7	7.9	6.8	28	
SRV	K960052	soil	545249	6795122	1643	17-Feb-12	2.8	0.5	24.1	7.4	50	
SRV	K960053	soil	545250	6795080	1645	17-Feb-12	154.6	0.6	18.8	7.2	34	
SRV	K960054	soil	545255	6795025	1645	17-Feb-12	1.8	0.7	11.5	7.4	45	
SRV	K960055	soil	545247	6794980	1642	17-Feb-12	5.8	0.5	32.9	11.1	54	
SRV	K960056	soil	545276	6794929	1647	17-Feb-12	0.25	0.4	8	6.3	36	
SRV	K960057	soil	545280	6794881	1644	17-Feb-12	7.1	0.5	36.6	12.5	53	
SRV	K960058	soil	545292	6794837	1641	17-Feb-12	1.6	0.4	11.3	11.7	41	
SRV	K960059	soil	540177	6796486	1474	17-Feb-12	3.3	0.3	19.5	10.4	58	
SRV	K960060	soil	540128	6796473	1475	17-Feb-12	3	0.4	24.2	6.5	47	
SRV	K960061	soil	540079	6796446	1477	17-Feb-12	13.1	0.6	49.9	15.7	67	
SRV	K960062	soil	540049	6796403	1464	17-Feb-12	8.9	0.5	43.3	10.6	55	
SRV	K960063	soil	540003	6796383	1456	17-Feb-12	3.1	0.4	27.4	7.1	45	
SRV	K960064	soil	539967	6796351	1441	17-Feb-12	2.8	0.8	25	9.5	44	
SRV	K960065	soil	539945	6796308	1425	17-Feb-12	0.9	0.3	8.4	7.5	47	
SRV	K960066	soil	539912	6796273	1409	17-Feb-12	16.3	0.9	142	9.1	84	
SRV	K960067	soil	539880	6796232	1407	17-Feb-12	3.6	0.7	24.3	10.1	43	
SRV	K960068	soil	539834	6796241	1385	17-Feb-12	4.1	0.2	41.6	5	55	
SRV	K960069	soil	539800	6796198	1398	17-Feb-12	4	0.7	12.1	8.2	38	
SRV	K960070	soil	539756	6796174	1397	17-Feb-12	19.4	0.4	20.8	7.3	45	
SRV	K960071	soil	539729	6796135	1391	17-Feb-12	28.6	0.4	26.8	10.6	51	
SRV	K960072	soil	539688	6796105	1390	17-Feb-12	3.3	0.8	27.1	6.6	45	
SRV	K960073	soil	539636	6796089	1399	17-Feb-12	14	0.4	31.8	7.9	63	
SRV	K960074	soil	539608	6796047	1403	17-Feb-12	0.25	0.4	13.5	8	35	
SRV	K960075	soil	539580	6796014	1394	17-Feb-12	6.3	0.4	39.5	18	240	
SRV	K960076	soil	539530	6796017	1394	17-Feb-12	17.4	0.9	17.4	6.6	36	
SRV	K960077	soil	539480	6795945	1395	17-Feb-12	4.5	0.3	15.8	6.4	37	
SRV	k960078	soil	539403	6795979	1397	17-Feb-12	1.6	0.2	24.6	9.9	75	
SRV	K960079	soil	539352	6795971	1398	17-Feb-12	3.6	0.2	76.2	8.4	58	
SRV	K960080	soil	539304	6795956	1395	17-Feb-12	0.25	0.3	19.5	8	33	
SRV	K960081	soil	539264	6795924	1389	17-Feb-12	1.3	0.3	19.4	9.1	41	
SRV	K960082	soil	539217	6795899	1387	17-Feb-12	2	0.7	17.1	8.6	36	
SRV	K960083	soil	539182	6795861	1392	17-Feb-12	1.4	0.3	12.9	7.9	31	
SRV	K960084	soil	539128	6795856	1398	17-Feb-12	1.2	0.5	12.4	10.4	33	
SRV	K960085	soil	539079	6795865	1406	17-Feb-12	0.8	0.4	12.5	7.4	37	
SRV	K960086	soil	539028	6795872	1406	17-Feb-12	9.8	0.2	26.1	18.2	54	
SRV	K960087	soil	538974	6795876	1413	17-Feb-12	0.25	0.9	15.8	8.6	39	
SRV	K960088	soil	538929	6795899	1419	17-Feb-12	1.5	0.2	12.5	9.6	29	
SRV	K960089	soil	538877	6795912	1416	17-Feb-12	2.4	0.5	25.1	16.2	47	
SRV	K960090	soil	538837	6795936	1420	17-Feb-12	8.8	0.2	12.6	12.2	41	
SRV	K960091	soil	540295	6802937	1594	18-Feb-12	1.1	0.2	18.1	6.7	44	
SRV	K960092	soil	540346	6802945	1583	18-Feb-12	2.2	0.2	41.4	6.9	38	
SRV	K960093	soil	540398	6802963	1556	18-Feb-12	1.5	0.1	46.6	16.9	76	
SRV	K960094	soil	540446	6802966	1544	18-Feb-12	1.8	0.4	47.3	7.2	58	
SRV	K960095	soil	540482	6802978	1536	18-Feb-12	1.2	0.2	22.3	5.6	39	
SRV	K960096	soil	540536	6802978	1529	18-Feb-12	0.9	0.3	14.4	7.5	38	
SRV	K960097	soil	540594	6802986	1524	18-Feb-12	1.1	0.2	17.7	8.9	47	
SRV	K960099	soil	540645	6803007	1521	18-Feb-12	1.7	0.3	30.5	7.9	78	
SRV	K960100	soil	540691	6803010	1520	18-Feb-12	0.9	0.3	30.7	9.9	47	
SRV	K960101	soil	546672	6796747	1775	15-Feb-12	22.3	5.6	59	6.2	45	
SRV	K960102	soil	546631	6796742	1769	15-Feb-12	3.8	4.9	128	6.6	80	
SRV	K960103	soil	546584	6796733	1743	15-Feb-12	4.6	4.3	69.1	9.7	57	
SRV	K960104	soil	546534	6796729	1714	15-Feb-12	5	3.6	130.7	7.2	104	
SRV	K960105	soil	546479	6796714	1691	15-Feb-12	1.2	2.1	52.4	10.8	72	
SRV	K960106	soil	546433	6796699	1680	15-Feb-12	2.9	3.8	32.6	11.8	57	
SRV	K960107	soil	546392	6796685	1659	15-Feb-12	4.4	2.5	44.2	5	101	
SRV	K960108	soil	546331	6796682	1653	15-Feb-12	3.9	2.6	17.6	7.4	46	
SRV	K960109	soil	546265	6796655	1640	15-Feb-12	18.2	1.9	15.8	8.9	72	
SRV	K960110	soil	546224	6796671	1635	15-Feb-12	0.25	1.4	30.9	10.7	118	

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRV	K960111	soil	546185	6796659	1628	15-Feb-12	2.3	0.7	36.2	10.7	73	
SRV	K960112	soil	546158	6796594	1630	15-Feb-12	0.25	1.2	42.9	5.4	98	
SRV	K960113	soil	546131	6796553	1632	15-Feb-12	0.25	1.2	55.7	6.3	68	
SRV	K960114	soil	546064	6796540	1629	15-Feb-12	47.5	2.6	119.7	12.6	92	
SRV	K960115	soil	546027	6796588	1638	15-Feb-12	12.7	3.4	44.6	26.8	58	
SRV	k960116	soil	545975	6796601	1641	15-Feb-12	7.3	2.3	40.2	12.8	50	
SRV	K960117	soil	545933	6796593	1646	15-Feb-12	9	1.4	45.4	20.6	64	
SRV	K960118	soil	545899	6796575	1653	15-Feb-12	25	1	48.4	13.5	58	
SRV	K960119	soil	545827	6796516	1657	15-Feb-12	13.4	1.1	43.9	7.7	97	
SRV	K960120	soil	545747	6796533	1671	15-Feb-12	3.4	1.5	73.4	8	70	
SRV	K960121	soil	545703	6796516	1672	15-Feb-12	2.1	1.1	52.1	8.8	53	
SRV	K960122	soil	545679	6796474	1679	15-Feb-12	1.6	2.4	23.2	13	44	
SRV	K960123	soil	545653	6796430	1683	15-Feb-12	0.6	2.9	13.6	8.6	54	
SRV	K960124	soil	545610	6796390	1680	15-Feb-12	4.8	1	61.4	17	56	
SRV	K960125	soil	545575	6796349	1679	15-Feb-12	3	1.7	55.5	16.8	73	
SRV	K960126	soil	545558	6796318	1679	15-Feb-12	5.6	0.6	42.6	10.8	70	
SRV	K960127	soil	545524	6796274	1679	15-Feb-12	22.2	1.2	37.5	15.7	52	
SRV	K960128	soil	545498	6796234	1673	15-Feb-12	5.2	1	20.2	8.1	50	
SRV	K960129	soil	545458	6796192	1669	15-Feb-12	1.4	1.7	41.8	9.2	49	
SRV	K960130	soil	545434	6796151	1667	15-Feb-12	2.6	1.1	46.8	9.8	55	
SRV	K960131	soil	545393	6796123	1665	15-Feb-12	1.3	1.1	26.3	10.9	48	
SRV	K960132	soil	545369	6796079	1663	15-Feb-12	175.4	1.4	31.4	11.8	39	
SRV	K960133	soil	545350	6796032	1660	15-Feb-12	3.3	1	40.2	8.9	46	
SRV	K960134	soil	545329	6795980	1660	15-Feb-12	14.3	0.6	21.8	13.4	43	
SRV	K960135	soil	545311	6795936	1659	15-Feb-12	10.4	1.3	45.6	13.2	47	
SRV	K960136	soil	545290	6795892	1659	15-Feb-12	11.8	1.3	30.6	15.2	53	
SRV	K960137	soil	545269	6795847	1659	15-Feb-12	1.9	0.8	10.8	10.2	34	
SRV	K960138	soil	545247	6795803	1659	15-Feb-12	0.25	0.6	10.6	10.3	29	
SRV	K960139	soil	545239	6795757	1663	15-Feb-12	1.1	0.5	10.5	10.6	40	
SRV	K960140	soil	545206	6795709	1661	15-Feb-12	8.8	0.7	60.8	10.4	61	
SRV	K960141	soil	545177	6795670	1642	17-Feb-12	0.6	1	10.7	7.2	33	
SRV	K960142	soil	545214	6795627	1647	17-Feb-12	8.8	0.9	52.3	12.9	54	
SRV	K960143	soil	545175	6795585	1643	17-Feb-12	39.3	1	18.9	10.5	45	
SRV	k960144	soil	545181	6795519	1643	17-Feb-12	2.8	0.5	11.7	6.6	28	
SRV	K960145	soil	545182	6795471	1640	17-Feb-12	19.2	0.3	12	9.4	48	
SRV	K960146	soil	545178	6795420	1639	17-Feb-12	4.4	0.7	10.3	10.6	37	
SRV	K960147	soil	545174	6795369	1634	17-Feb-12	1.5	0.3	11.9	4.6	38	
SRV	k960148	soil	545177	6795318	1632	17-Feb-12	2.3	0.7	15.9	9.3	50	
SRV	K960149	soil	545193	6795258	1631	17-Feb-12	0.25	0.5	8.8	6.4	41	
SRV	K960150	soil	545216	6795225	1637	17-Feb-12	1.9	0.6	28.4	11.2	52	
SRV	K960201	soil	547534	6800039	1829	18-Feb-12	4	0.4	19.2	49.1	43	
SRV	K960202	soil	547547	6800092	1826	18-Feb-12	0.25	0.2	18.4	12.5	45	
SRV	K960203	soil	547555	6800144	1827	18-Feb-12	0.25	0.2	25.8	6.9	54	
SRV	K960204	soil	547542	6800195	1830	18-Feb-12	0.25	0.05	24	3.6	43	
SRV	K960205	soil	547500	6800224	1837	18-Feb-12	0.25	0.2	22.2	6.9	48	
SRV	K960207	soil	547454	6800318	1856	18-Feb-12	0.25	0.1	30.7	4.5	50	
SRV	K960208	soil	547426	6800363	1868	18-Feb-12	0.25	0.1	38.2	4.4	54	
SRV	K960209	soil	547400	6800409	1872	18-Feb-12	0.25	0.1	20.5	5.1	53	
SRV	K960210	soil	547357	6800457	1862	18-Feb-12	0.5	0.3	27.2	7	56	
SRV	K960211	soil	547351	6800511	1857	18-Feb-12	0.25	0.1	33	3.4	42	
SRV	K960212	soil	547344	6800566	1860	18-Feb-12	0.25	0.05	31.1	4.4	64	
SRV	K960213	soil	547319	6800616	1859	18-Feb-12	0.25	0.2	33.1	4.2	51	
SRV	K960214	soil	547284	6800659	1858	18-Feb-12	0.5	0.2	28.6	4.7	50	
SRV	K960215	soil	547252	6800708	1851	18-Feb-12	1.1	0.2	18.2	7.5	53	
SRV	K960216	soil	547214	6800747	1846	18-Feb-12	0.8	0.2	16	4.4	50	
SRV	K960217	soil	547176	6800779	1846	18-Feb-12	0.25	0.2	16.5	5.6	46	
SRV	K960218	soil	547132	6800810	1842	18-Feb-12	2.8	0.1	49.3	3.8	74	
SRV	K960221	soil	547015	6800920	1846	18-Feb-12	0.5	0.1	24.9	4.1	50	
SRV	K960222	soil	546974	6800958	1848	18-Feb-12	0.9	0.2	25.9	6.8	56	

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRV	K960223	soil	546933	6800993	1849	18-Feb-12	0.6	0.2	28.5	4.7	54	
SRV	K960224	soil	546883	6801018	1845	18-Feb-12	0.25	0.05	17.8	2.6	70	
SRV	K960225	soil	546832	6801017	1835	18-Feb-12	0.25	0.05	17.8	2.4	59	
SRV	K960226	soil	546786	6801044	1830	18-Feb-12	0.8	0.3	26.5	3.1	55	
SRV	K960227	soil	546739	6801065	1830	18-Feb-12	0.25	0.2	26.5	7.3	79	
SRV	K960228	soil	546688	6801079	1823	18-Feb-12	0.5	0.1	38.3	4.3	53	
SRV	K960229	soil	546637	6801095	1815	18-Feb-12	0.25	0.1	37.5	4.7	55	
SRV	K960230	soil	546587	6801112	1811	18-Feb-12	0.25	0.2	36.4	3.3	43	
SRV	K960231	soil	546535	6801116	1801	18-Feb-12	0.25	0.3	30.8	5.4	62	
SRV	K960232	soil	546484	6801104	1801	18-Feb-12	0.25	0.2	25.7	5.2	57	
SRV	K960233	soil	546434	6801118	1804	18-Feb-12	0.6	0.2	14.9	5.9	46	
SRV	K960234	soil	546368	6801128	1803	18-Feb-12	0.25	0.1	21	5.1	49	
SRV	K960235	soil	546315	6801154	1798	18-Feb-12	0.25	0.2	73.7	3	52	
SRV	K960236	soil	546284	6801197	1796	18-Feb-12	0.25	0.1	25.9	3.7	48	
SRV	K960237	soil	546244	6801238	1786	18-Feb-12	1.2	0.2	20.2	5.4	54	
SRV	K960238	soil	546217	6801285	1783	18-Feb-12	0.25	0.2	33	3	46	
SRV	K960239	soil	546191	6801336	1777	18-Feb-12	0.25	0.2	35.2	5	59	
SRV	K960240	soil	546149	6801382	1775	18-Feb-12	0.25	0.05	11.7	6.3	43	
SRV	K960241	soil	546115	6801425	1774	18-Feb-12	0.25	0.1	26.1	5.4	56	
SRV	K960242	soil	546068	6801463	1770	18-Feb-12	0.25	0.2	19.3	5.3	58	
SRV	K960243	soil	546036	6801512	1772	18-Feb-12	0.25	0.1	19.4	5.7	63	
SRV	K960244	soil	546046	6801573	1779	18-Feb-12	0.25	0.1	12.5	2.8	39	
SRV	K960245	soil	546038	6801619	1788	18-Feb-12	0.25	0.1	12.3	6.2	41	
SRV	K960246	soil	546024	6801669	1786	18-Feb-12	0.25	0.1	14.8	15.8	42	
SRV	K960247	soil	546001	6801720	1792	18-Feb-12	1	0.1	38.2	10.4	47	
SRV	K960248	soil	545977	6801767	1794	18-Feb-12	0.6	0.2	23.1	10.5	48	
SRV	K960249	soil	545938	6801801	1796	18-Feb-12	0.25	0.05	16.1	13.6	36	
SRV	K960250	soil	545887	6801795	1785	18-Feb-12	1	0.05	24.6	5.4	35	
SRV	K960301	soil	546795	6798449	1830	15-Feb-12	0.25	13.6	33.8	2.9	45	
SRV	K960302	soil	546759	6798516	1817	15-Feb-12	1.6	1.4	41.4	4.6	52	
SRV	K960303	soil	546742	6798559	1816	15-Feb-12	0.6	3.1	19.8	7.2	52	
SRV	K960304	soil	546733	6798603	1813	15-Feb-12	7.6	4.9	29.4	4.3	45	
SRV	k960305	soil	546670	6798624	1786	15-Feb-12	2.4	7.1	49.7	7.8	56	
SRV	K960306	soil	546598	6798629	1778	15-Feb-12	4.3	1.3	45.2	7.5	78	
SRV	K960307	soil	546544	6798643	1785	15-Feb-12	0.25	2.9	21.3	9.9	87	
SRV	K960308	soil	546497	6798675	1776	15-Feb-12	0.9	3.3	18.9	4.8	43	
SRV	K960309	soil	546447	6798713	1754	15-Feb-12	2	1.1	33.6	14.3	120	
SRV	K960310	soil	546406	6798758	1746	15-Feb-12	3.3	4.3	39.9	8.7	98	
SRV	K960311	soil	546367	6798779	1740	15-Feb-12	3.6	3.9	34.1	8.4	53	
SRV	k960312	soil	546315	6798800	1735	15-Feb-12	2.7	3.7	39.2	10.7	41	
SRV	K960313	soil	546269	6798811	1735	15-Feb-12	7.6	2.3	50.4	10.7	48	
SRV	K960314	soil	546219	6798824	1743	15-Feb-12	4.8	1.6	31	5.4	45	
SRV	K960315	soil	546171	6798836	1742	15-Feb-12	1.2	0.6	7.8	2.7	37	
SRV	K960316	soil	546122	6798848	1740	15-Feb-12	1.1	2.1	11.4	5	55	
SRV	K960317	soil	546070	6798868	1741	15-Feb-12	1.6	2.4	24.6	5.7	49	
SRV	K960318	soil	546024	6798873	1742	15-Feb-12	3.9	1.4	55.6	5.8	54	
SRV	K960319	soil	545977	6798886	1750	15-Feb-12	2.3	2.1	31.8	7.2	44	
SRV	K960320	soil	545927	6798900	1758	15-Feb-12	4.4	1.8	31	6.3	38	
SRV	K960321	soil	545869	6798912	1752	15-Feb-12	1.7	1.3	30.7	10	58	
SRV	K960322	soil	545830	6798922	1752	15-Feb-12	2.4	0.8	29.1	6.8	45	
SRV	K960323	soil	545780	6798934	1744	15-Feb-12	2.9	1.6	27.3	13.8	43	
SRV	K960324	soil	545724	6798906	1737	15-Feb-12	3.1	1.3	41.3	6.3	68	
SRV	K960326	soil	545640	6798892	1724	15-Feb-12	3.9	0.9	84.9	10.7	52	
SRV	K960327	soil	545589	6798874	1718	15-Feb-12	2.5	1.4	20.3	8.4	39	
SRV	K960328	soil	545541	6798838	1710	15-Feb-12	1.5	0.8	18.4	14	52	
SRV	K960329	soil	545468	6798849	1688	15-Feb-12	129.8	1.5	31.2	11.5	74	
SRV	K960330	soil	545425	6798841	1701	15-Feb-12	1.1	0.9	42.1	10.6	63	
SRV	K960331	soil	545382	6798828	1704	15-Feb-12	3.6	1.4	10.9	6.2	33	
SRV	K960332	soil	545340	6798813	1710	15-Feb-12	1.6	0.5	21.5	7.1	53	

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRV	K960333	soil	545294	6798800	1716	15-Feb-12	1.5	1.2	27.9	8.2	47	
SRV	K960334	soil	545249	6798788	1719	15-Feb-12	3.2	1.5	22.7	26.5	80	
SRV	K960335	soil	545201	6798771	1718	15-Feb-12	4.5	0.8	33	9.9	77	
SRV	K960336	soil	545148	6798758	1722	15-Feb-12	68.3	1.7	44.8	135.7	158	
SRV	K960337	soil	545114	6798724	1715	15-Feb-12	5.7	0.8	32.6	9.8	62	
SRV	K960338	soil	545074	6798705	1726	15-Feb-12	2.4	0.9	29.5	16.2	54	
SRV	K960339	soil	545032	6798670	1719	15-Feb-12	0.25	1.3	13.9	6.8	23	
SRV	K960340	soil	544988	6798637	1703	15-Feb-12	0.8	1.1	13.6	8.4	48	
SRV	K960341	soil	544958	6798609	1749	17-Feb-12	1.3	0.8	9.4	7.1	39	
SRV	K960342	soil	544916	6798580	1732	17-Feb-12	3	0.9	26.6	15.1	73	
SRV	K960343	soil	544876	6798548	1726	17-Feb-12	3.4	1.1	34.1	11	56	
SRV	K960344	soil	544835	6798520	1724	17-Feb-12						Insufficient material
SRV	K960345	soil	544793	6798490	1724	17-Feb-12	8.5	1.2	39.7	14.2	71	
SRV	K960346	soil	544756	6798462	1727	17-Feb-12	5.5	0.6	31.6	13.5	67	
SRV	K960347	soil	544711	6798427	1722	17-Feb-12	2.1	0.8	14.9	7.1	45	
SRV	K960348	soil	544677	6798401	1726	17-Feb-12	5.3	0.5	55	15.8	64	
SRV	K960349	soil	544634	6798372	1731	17-Feb-12	4	0.5	29.1	12	56	
SRV	K960350	soil	544597	6798339	1735	17-Feb-12	0.6	1.2	40.5	9.7	39	
SRV	K960351	soil	544558	6798308	1734	17-Feb-12	9.8	0.7	26.9	21.1	61	
SRV	K960352	soil	544525	6798275	1736	17-Feb-12	2.2	0.8	21.7	15.4	56	
SRV	K960353	soil	544487	6798239	1735	17-Feb-12						Insufficient material
SRV	K960354	soil	544449	6798207	1730	17-Feb-12	11.5	0.7	34.6	17.6	55	
SRV	K960355	soil	544409	6798174	1724	17-Feb-12	14.7	1	26.8	12.4	47	
SRV	K960356	soil	544373	6798142	1719	17-Feb-12	4.5	0.7	26.6	12.3	57	
SRV	K960357	soil	544332	6798112	1714	17-Feb-12	4.5	0.7	22.5	13.6	67	
SRV	K960358	soil	544293	6798077	1706	17-Feb-12	34.2	0.9	42.1	19.9	69	
SRV	K960359	soil	544253	6798054	1700	17-Feb-12	5.6	0.5	23.3	7.1	53	
SRV	K960360	soil	544214	6798100	1703	17-Feb-12	50.5	0.5	35.7	16.7	70	
SRV	K960361	soil	544169	6798128	1701	17-Feb-12	49.6	0.8	37	32.6	91	
SRV	K960362	soil	544123	6798155	1698	17-Feb-12	3.4	0.5	25.7	8.2	54	
SRV	K960363	soil	544079	6798189	1693	17-Feb-12	2.1	0.5	9.1	8.1	31	
SRV	K960364	soil	540009	6797476	1418	17-Feb-12	1.4	0.4	20.5	5.5	19	
SRV	K960365	soil	539993	6797421	1415	17-Feb-12	132.8	1.5	105	28.1	219	
SRV	K960366	soil	539931	6797425	1424	17-Feb-12	1.5	0.2	44.1	3.1	69	
SRV	K960367	soil	539874	6797460	1429	17-Feb-12	13.3	0.4	42.4	5.2	61	
SRV	K960368	soil	539811	6797489	1431	17-Feb-12	0.8	1	15.4	7.5	32	
SRV	K960369	soil	539737	6797504	1424	17-Feb-12	2.3	0.7	17.4	6.7	58	
SRV	K960370	soil	539685	6797503	1425	17-Feb-12	3.8	1.1	31.9	7.1	36	
SRV	K960371	soil	539639	6797485	1422	17-Feb-12	0.6	1.1	11.3	6.2	36	
SRV	K960372	soil	539594	6797467	1410	17-Feb-12	5.5	0.4	38.1	18.3	170	
SRV	K960373	soil	539581	6797406	1399	17-Feb-12	1.9	0.05	38.8	1.1	66	
SRV	K960374	soil	539535	6797394	1386	17-Feb-12	0.25	0.3	36.1	1.9	39	
SRV	K960375	soil	539496	6797442	1391	17-Feb-12	0.6	1.3	10.7	7.5	33	
SRV	K960376	soil	539444	6797459	1398	17-Feb-12	0.25	0.7	6.9	4.6	31	
SRV	K960377	soil	539399	6797485	1405	17-Feb-12	2.8	0.3	47.3	12.1	43	
SRV	K960378	soil	539360	6797536	1408	17-Feb-12	4.9	1.3	27	13.3	48	
SRV	K960379	soil	539306	6797517	1411	17-Feb-12	2.6	0.5	53.7	8.4	70	
SRV	K960380	soil	539256	6797484	1418	17-Feb-12	0.9	0.5	11.4	7	32	
SRV	K960381	soil	539213	6797504	1409	17-Feb-12	7.5	0.4	30.2	8.3	54	
SRV	K960382	soil	539139	6797522	1396	17-Feb-12	1.5	0.6	15.6	10.2	59	
SRV	K960383	soil	539094	6797590	1405	17-Feb-12	0.25	0.1	2.7	9.7	39	
SRV	K960384	soil	539052	6797609	1413	17-Feb-12	1.8	0.05	17.5	29.1	37	
SRV	K960385	soil	539009	6797654	1423	17-Feb-12	3.2	0.5	15.6	9.4	44	
SRV	K960386	soil	538960	6797672	1427	17-Feb-12	0.6	0.7	11.6	9.5	35	
SRV	K960387	soil	538900	6797672	1431	17-Feb-12	4.9	0.6	19.2	8.3	42	
SRV	K960388	soil	538852	6797687	1435	17-Feb-12	0.25	0.3	11.5	7.2	39	
SRV	K960389	soil	538802	6797710	1435	17-Feb-12	6.3	0.4	17	8.8	56	
SRV	K960390	soil	538749	6797722	1435	17-Feb-12	5.5	0.3	25.9	13.4	55	
SRV	K960391	soil	547783	6799659	1869	18-Feb-12	0.25	0.5	24.5	7	51	

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRV	K960392	soil	547816	6799621	1871	18-Feb-12	0.8	0.3	55.3	5	38	
SRV	K960393	soil	547735	6799686	1859	18-Feb-12	0.8	0.2	33.6	7.1	47	
SRV	K960394	soil	547689	6799715	1854	18-Feb-12	0.25	0.05	32.7	5.2	45	
SRV	k960395	soil	547653	6799752	1849	18-Feb-12	0.25	0.05	23.1	3.2	37	
SRV	K960396	soil	547618	6799792	1849	18-Feb-12	0.25	0.1	12	4.7	33	
SRV	K960397	soil	547584	6799831	1843	18-Feb-12	0.25	0.2	16.3	5	42	
SRV	K960398	soil	547568	6799888	1837	18-Feb-12	0.8	0.3	13.5	5.3	31	
SRV	K960399	soil	547571	6799941	1834	18-Feb-12	0.25	0.4	15.2	5.6	36	
SRV	K960400	soil	547563	6799996	1833	18-Feb-12	0.7	0.2	13.4	5.3	41	
SRV	K960401	soil	540014	6803495	1572	19-Feb-12	3.6	0.2	20.4	6.1	38	
SRV	K960402	soil	540025	6803447	1574	19-Feb-12	1.6	0.1	19.7	5.1	49	
SRV	K960403	soil	540056	6803410	1570	19-Feb-12	1	0.1	16.5	6.6	39	
SRV	K960404	soil	540096	6803378	1565	19-Feb-12	0.25	0.2	20.5	7.1	42	
SRV	K960405	soil	540121	6803334	1563	19-Feb-12	7.4	0.7	23.6	7.9	36	
SRV	K960406	soil	540140	6803288	1550	19-Feb-12	0.7	0.4	18.7	5.5	33	
SRV	K960407	soil	540178	6803254	1553	19-Feb-12	3.1	0.2	28.6	9.6	46	
SRV	K960408	soil	540193	6803208	1548	19-Feb-12	0.6	0.2	19.7	6.8	50	
SRV	K960409	soil	540202	6803160	1549	19-Feb-12	2.4	0.2	27.4	9.5	44	
SRV	K960410	soil	540243	6803137	1552	19-Feb-12	3.1	0.2	26.1	6.7	43	
SRV	K960411	soil	540262	6803092	1562	19-Feb-12	0.25	0.2	21.1	7.3	38	
SRV	K960412	soil	540258	6803043	1569	19-Feb-12	0.6	0.1	30.8	6.4	40	
SRV	K960413	soil	540273	6802992	1574	19-Feb-12	1.6	0.1	34.1	6.5	43	
SRV	K960414	soil	540284	6802943	1577	19-Feb-12	1.5	0.05	45.8	6.3	30	
SRV	K960415	soil	540296	6802893	1576	19-Feb-12	1.1	0.05	25.7	5.6	46	
SRV	K960416	soil	540297	6802843	1571	19-Feb-12	1.6	0.3	19.8	7.9	43	
SRV	K960417	soil	540288	6802765	1562	19-Feb-12	0.9	0.1	25.4	22.7	48	
SRV	K960418	soil	540288	6802716	1559	19-Feb-12	1.1	0.2	15.6	8.2	38	
SRV	K960419	soil	540275	6802667	1557	19-Feb-12	0.25	0.2	14	6.7	43	
SRV	K960420	soil	540274	6802612	1553	19-Feb-12	1.5	0.1	17.4	7	35	
SRV	K960421	soil	540276	6802561	1547	19-Feb-12	1.7	0.2	16.6	6.4	41	
SRV	K960422	soil	540268	6802517	1540	19-Feb-12	1	0.1	14.9	5	34	
SRV	K960423	soil	539352	6804621	1500	19-Feb-12	0.9	0.1	25.8	7.3	49	
SRV	K960424	soil	539331	6804673	1493	19-Feb-12	2.2	0.1	21.2	4.8	49	
SRV	K960425	soil	539289	6804712	1491	19-Feb-12	1.2	0.2	19.2	6.7	50	
SRV	K960426	soil	539256	6804753	1488	19-Feb-12	1.7	0.5	24.9	8.2	52	
SRV	K960427	soil	539231	6804798	1485	19-Feb-12	3.1	0.1	33.3	7.2	58	
SRV	K960428	soil	539232	6804850	1475	19-Feb-12	0.25	0.1	19	5.8	42	
SRV	K960429	soil	539281	6804893	1463	19-Feb-12	0.6	0.1	20.4	5.8	38	
SRV	K960430	soil	539251	6804938	1455	19-Feb-12	1.3	0.2	23.4	7.9	50	
SRV	K960431	soil	539210	6804961	1449	19-Feb-12	5.4	0.4	42	14.7	81	
SRV	K960432	soil	539177	6805002	1445	19-Feb-12	0.25	0.2	21.8	5.3	43	
SRV	K960433	soil	539147	6805046	1441	19-Feb-12	1.1	0.05	19.7	3.7	45	
SRV	K960434	soil	539124	6805088	1444	19-Feb-12	0.9	0.2	22.9	6	37	
SRV	K960435	soil	539131	6805134	1445	19-Feb-12	1.2	0.2	19.9	6	43	
SRV	K960436	soil	539195	6805165	1439	19-Feb-12	0.25	0.1	18.8	5.3	40	
SRV	K960437	soil	539235	6805201	1427	19-Feb-12	1.9	0.2	9.2	10.6	37	
SRV	K960438	soil	539272	6805236	1424	19-Feb-12	0.9	0.2	16.8	5.2	45	
SRV	k960439	soil	539263	6805291	1419	19-Feb-12	30.1	0.3	21.8	5	38	
SRV	K960440	soil	539286	6805344	1410	19-Feb-12	1.2	0.1	18.5	6.6	58	
SRV	K960441	soil	539310	6805400	1407	19-Feb-12	0.25	0.2	24	7	49	
SRV	K960451	soil	546856	6798122	1795	20-Feb-12	1.5	0.2	39.6	3.3	37	
SRV	K960452	soil	546825	6798085	1786	20-Feb-12	1	0.1	44	3.4	43	
SRV	K960453	soil	546782	6798054	1774	20-Feb-12	0.5	0.2	40.1	4	37	
SRV	K960454	soil	546771	6797979	1763	20-Feb-12	1	0.2	40.8	3.4	40	
SRV	K960455	soil	546723	6797896	1753	20-Feb-12	8.6	0.5	48.4	14.7	63	
SRV	K960456	soil	546683	6797860	1746	20-Feb-12	2.7	0.3	30.7	12.7	46	
SRV	K960457	soil	546641	6797807	1743	20-Feb-12	3.7	0.2	82.6	6.1	47	
DAC	K960458	soil	538785	6809017	1463	21-Feb-12	1.2	0.05	43.7	3.6	43	
DAC	K960459	soil	538730	6809048	1468	21-Feb-12	3	0.3	46.9	8.5	71	

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
DAC	K960460	soil	538693	6809016	1478	21-Feb-12	0.6	0.05	56.5	4.3	39	
DAC	K960461	soil	538646	6809010	1473	21-Feb-12	0.9	0.1	54.1	2.6	40	
DAC	K960462	soil	538616	6808977	1476	21-Feb-12	0.25	0.1	25.3	13.3	60	
DAC	K960463	soil	538558	6808973	1472	21-Feb-12	0.7	0.2	26.2	6.9	51	
DAC	K960464	soil	538527	6808935	1461	21-Feb-12	0.25	0.1	20.1	6.4	52	
DAC	K960465	soil	538479	6808941	1455	21-Feb-12	2.6	0.2	24.9	4.2	50	
DAC	K960466	soil	538430	6808938	1448	21-Feb-12	0.5	0.2	23.1	5.5	49	
DAC	K960467	soil	538383	6808927	1437	21-Feb-12	1.1	0.1	19	6.1	40	
DAC	K960468	soil	538336	6808914	1432	21-Feb-12	1.4	0.2	24.3	7.5	45	
DAC	K960469	soil	538291	6808903	1418	21-Feb-12	12.5	0.2	41.3	3.5	79	
DAC	K960470	soil	538243	6808878	1407	21-Feb-12	0.5	0.05	11.1	3.9	59	
DAC	K960471	soil	538187	6808868	1400	21-Feb-12	0.9	0.05	9.8	1.8	32	
DAC	K960472	soil	538133	6808866	1404	21-Feb-12	1.2	0.2	19.6	6.4	40	
DAC	K960473	soil	538085	6808875	1399	21-Feb-12	0.25	0.1	13.9	5	44	
DAC	K960474	soil	538021	6808876	1390	21-Feb-12	1	0.2	22.4	7.3	51	
DAC	K960475	soil	537967	6808881	1384	21-Feb-12	12.7	0.3	21.6	6.4	44	
DAC	K960476	soil	537915	6808905	1371	21-Feb-12	1.7	0.1	16.3	2.7	20	
DAC	K960477	soil	537860	6808860	1351	21-Feb-12	3.7	0.4	26.1	8.4	58	
DAC	K960478	soil	537810	6808845	1346	21-Feb-12	2.3	0.4	19.2	7.8	37	
DAC	K960479	soil	537766	6808813	1343	21-Feb-12	1.2	0.3	24.9	5.3	34	
DAC	K960481	soil	537662	6808738	1326	21-Feb-12	0.25	0.3	22.8	7.2	44	
DAC	K960482	soil	537619	6808711	1313	21-Feb-12	0.25	0.7	8.3	4.7	20	
DAC	K960484	soil	537520	6808675	1296	21-Feb-12	0.25	0.3	21.3	6.6	46	
DAC	K960486	soil	537486	6808575	1290	21-Feb-12	8.7	0.4	17.4	7.3	42	
SRV	K960651	soil	540743	6803026	1518	18-Feb-12	0.25	0.2	18.8	5.1	42	
SRV	K960652	soil	540790	6803011	1517	18-Feb-12	0.25	0.2	25.3	7.7	52	
SRV	K960653	soil	540833	6802994	1513	18-Feb-12	0.25	0.2	21.3	7.9	47	
SRV	K960654	soil	540881	6802980	1512	18-Feb-12	1.9	0.3	28.5	5.1	58	
SRV	K960655	soil	540930	6802966	1509	18-Feb-12	1	0.6	16.2	4.8	36	
SRV	K960656	soil	540976	6802950	1503	18-Feb-12	0.25	0.3	21.8	7.9	40	
SRV	K960657	soil	541023	6802937	1502	18-Feb-12	0.25	0.3	19	8.5	51	
SRV	K960658	soil	541070	6802916	1504	18-Feb-12	0.25	0.1	16.7	7.7	54	
SRV	K960659	soil	541119	6802903	1507	18-Feb-12	1.3	0.2	41.6	6.4	46	
SRV	K960660	soil	541169	6802881	1507	18-Feb-12	0.9	0.2	24.1	7.1	41	
SRV	K960661	soil	541215	6802880	1506	18-Feb-12	0.6	0.2	25.8	6	55	
SRV	K960662	soil	541273	6802881	1504	18-Feb-12	0.7	0.6	19.7	6.5	46	
SRV	K960663	soil	541323	6802885	1505	18-Feb-12	0.7	0.2	18.4	10.5	53	
SRV	K960664	soil	541372	6802883	1572	18-Feb-12	1.7	0.3	15.8	5.7	49	
SRV	K960665	soil	541426	6802892	1509	18-Feb-12	0.6	0.1	22.5	6.2	42	
SRV	K960666	soil	541476	6802884	1498	18-Feb-12	0.25	0.2	17	4.5	73	
SRV	K960667	soil	541526	6802868	1490	18-Feb-12	1.3	0.3	20.2	6.6	54	
SRV	K960668	soil	541575	6802866	1484	18-Feb-12	0.25	0.4	24.7	9.1	58	
SRV	K960669	soil	541618	6802838	1486	18-Feb-12	0.25	0.3	24.8	5.7	58	
SRV	K960670	soil	541654	6802804	1487	18-Feb-12	0.25	0.3	62.1	4.9	73	
SRV	K960671	soil	541702	6802791	1487	18-Feb-12	0.5	0.4	36.4	6.2	71	
SRV	K960672	soil	541738	6802754	1486	18-Feb-12	1.3	0.2	30	7	69	
SRV	K960673	soil	541786	6802737	1482	18-Feb-12	1.1	0.1	24.9	5.6	79	
SRV	k960674	soil	541811	6802699	1475	18-Feb-12	2	0.3	31.9	7.9	78	
SRV	K960675	soil	541841	6802661	1479	18-Feb-12	1.2	0.4	30.4	7.5	76	
SRV	K960676	soil	541853	6802615	1481	18-Feb-12	0.25	0.3	25.2	6.1	55	
SRV	K960677	soil	541885	6802568	1485	18-Feb-12	1.7	0.3	20.4	5.8	54	
SRV	K960678	soil	541919	6802538	1490	18-Feb-12	2.3	0.3	13.1	5.8	47	
SRV	K960679	soil	541920	6802486	1498	18-Feb-12	1.2	0.3	24.3	6.7	58	
SRV	K960680	soil	541968	6802469	1496	18-Feb-12	1	0.3	27	7.3	50	
SRV	K960681	soil	542020	6802463	1487	18-Feb-12	0.9	0.5	20.5	8	50	
SRV	K960682	soil	542073	6802458	1478	18-Feb-12	0.25	0.1	24.2	3.8	58	
SRV	K960683	soil	542112	6802428	1478	18-Feb-12	0.8	0.3	23.7	7.5	63	
SRV	K960684	soil	542152	6802395	1474	18-Feb-12	0.25	0.2	24.4	7.1	68	
SRV	K960685	soil	542193	6802364	1470	18-Feb-12	1	0.6	35.6	8.8	71	

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRV	K960686	soil	542242	6802337	1469	18-Feb-12	0.5	0.3	29.2	6.6	63	
SRV	K960687	soil	542291	6802318	1472	18-Feb-12	0.25	0.05	33.4	11.8	59	
SRV	K960688	soil	542338	6802300	1480	18-Feb-12	0.25	0.3	32.4	7.9	70	
SRV	K960689	soil	542388	6802285	1487	18-Feb-12	0.25	0.2	28	6.6	65	
SRV	K960690	soil	542432	6802263	1493	18-Feb-12	0.7	0.1	43.7	6	69	
SRV	K960691	soil	539651	6803847	1592	19-Feb-12	0.25	0.2	33.6	6.2	44	
SRV	K960692	soil	539690	6803816	1599	19-Feb-12	3.2	0.2	39.2	6.4	45	
SRV	K960693	soil	539729	6803782	1600	19-Feb-12	1	0.2	27.5	6.8	32	
SRV	K960694	soil	539774	6803755	1595	19-Feb-12	1.7	0.2	51	6.2	45	
SRV	K960695	soil	539800	6803711	1597	19-Feb-12	0.25	0.05	30.7	2.5	27	
SRV	K960696	soil	539833	6803673	1591	19-Feb-12	2.6	0.2	42.5	6.5	50	
SRV	K960697	soil	539876	6803646	1580	19-Feb-12	0.25	0.1	61.6	6.6	50	
SRV	K960698	soil	539914	6803613	1575	19-Feb-12	2	0.2	39.5	6.1	55	
SRV	K960699	soil	539946	6803571	1576	19-Feb-12	0.25	0.05	29.7	4.8	45	
SRV	K960700	soil	539983	6803535	1574	19-Feb-12	0.8	0.1	42.3	6.7	44	
SRV	K960701	soil	545856	6801838	1774	19-Feb-12	7.5	0.1	20.5	3.5	38	
SRV	K960702	soil	545822	6801861	1762	19-Feb-12	0.25	0.1	23.1	1.5	32	
SRV	K960703	soil	537336	6798262	1444	19-Feb-12	13.9	0.2	31.1	12.9	54	
SRV	K960704	soil	537370	6798223	1436	19-Feb-12	5.2	0.1	17.8	10.2	42	
SRV	K960705	soil	537419	6798212	1437	19-Feb-12	1	0.05	9.7	5.2	19	
SRV	K960706	soil	537472	6798199	1446	19-Feb-12	1.9	0.05	19.6	13.4	40	
SRV	K960707	soil	537518	6798170	1446	19-Feb-12	1.8	0.05	20.7	13.9	47	
SRV	K960708	soil	537548	6798129	1444	19-Feb-12	3.8	0.05	40.8	17.4	75	
SRV	K960709	soil	537584	6798090	1445	19-Feb-12	7.4	0.2	25.1	15.5	40	
SRV	K960710	soil	537638	6798071	1453	19-Feb-12	4.2	0.3	28.8	18.1	46	
SRV	K960711	soil	537648	6798005	1460	19-Feb-12	6.1	0.1	20.8	9.3	43	
SRV	K960712	soil	537699	6797996	1473	19-Feb-12	3.1	0.1	31.8	9	43	
SRV	K960713	soil	537749	6798000	1476	19-Feb-12	4.9	0.1	21.6	12.5	31	
SRV	K960714	soil	537798	6798018	1478	19-Feb-12	4.1	0.2	20.7	29.9	40	
SRV	K960715	soil	537852	6798022	1482	19-Feb-12	3	0.1	23.3	16.2	51	
SRV	K960716	soil	537908	6798033	1485	19-Feb-12	3.5	0.1	31.3	13.1	59	
SRV	K960717	soil	537953	6798052	1488	19-Feb-12	3.6	0.1	19.2	13.3	43	
SRV	K960718	soil	538005	6798038	1492	19-Feb-12	2.6	0.1	18.7	11.4	38	
SRV	K960719	soil	538059	6798024	1498	19-Feb-12	1.9	0.05	13.6	9.4	23	
SRV	K960720	soil	538113	6798006	1494	19-Feb-12	16.4	0.05	13.1	15.6	24	
SRV	K960721	soil	538163	6797995	1494	19-Feb-12	8	0.1	19.4	13.9	45	
SRV	K960722	soil	538210	6797973	1492	19-Feb-12	2.6	0.3	23.3	9.6	52	
SRV	K960723	soil	538239	6797931	1492	19-Feb-12	1.8	0.2	65.5	8.3	72	
SRV	K960724	soil	538282	6797904	1500	19-Feb-12	3.5	0.05	14.9	10	28	
SRV	K960725	soil	538324	6797873	1500	19-Feb-12	1.1	0.4	9.7	6.9	47	
SRV	K960726	soil	538372	6797851	1497	19-Feb-12	2.2	0.2	16.9	10.6	46	
SRV	K960727	soil	538421	6797834	1497	19-Feb-12	2	0.1	27.3	19.1	50	
SRV	K960728	soil	538458	6797798	1492	19-Feb-12	2.3	0.1	27.6	10.2	40	
SRV	K960729	soil	538481	6797752	1488	19-Feb-12	0.25	0.05	60.2	7	50	
SRV	k960730	soil	538527	6797733	1481	19-Feb-12	2.9	0.1	15.4	11.9	50	
SRV	K960731	soil	538578	6797729	1465	19-Feb-12	7.7	0.1	17.4	11.2	39	
SRV	K960732	soil	538629	6797705	1453	19-Feb-12	8.6	0.2	45.4	8.6	53	
SRV	K960733	soil	538718	6797696	1444	19-Feb-12	3.4	0.3	11.4	14.6	39	
SRV	K960734	soil	538664	6795815	1412	19-Feb-12	7.8	0.1	42.1	8.2	46	
SRV	K960735	soil	538597	6795846	1401	19-Feb-12	1.8	0.1	28.4	37.3	51	
SRV	K960736	soil	538558	6795899	1393	19-Feb-12	0.5	0.05	6.2	7.7	7	
SRV	K960737	soil	538502	6795931	1381	19-Feb-12	1.5	0.6	13.8	10.9	36	
SRV	K960738	soil	538440	6795950	1361	19-Feb-12	4.2	0.2	9.1	9.9	57	
SRV	K960739	soil	538383	6795989	1351	19-Feb-12	8.1	0.4	21.8	8.5	43	
SRV	K960740	soil	538345	6796025	1348	19-Feb-12	3.3	0.5	18.2	10.2	41	
SRV	K960741	soil	538332	6796067	1347	19-Feb-12	14.9	0.2	19.4	10.9	46	
SRV	K960742	soil	538843	6795865	1421	19-Feb-12	9.6	0.2	15.8	9.3	32	
SRV	K960743	soil	538791	6795855	1417	19-Feb-12	2.5	0.2	17.3	11.5	38	
SRV	K960744	soil	538744	6795867	1408	19-Feb-12	4.9	0.1	16.7	20.1	49	

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)	Comment
SRV	K960745	soil	546781	6798401	1879	20-Feb-12	3.3	0.2	67.8	5.3	52	
SRV	K960746	soil	546813	6798362	1860	20-Feb-12	0.8	0.05	9.4	1.5	47	
SRV	K960747	soil	546829	6798312	1848	20-Feb-12	0.8	0.2	43.7	2.2	39	
SRV	K960748	soil	546834	6798262	1835	20-Feb-12	0.9	0.1	20.1	2.9	31	
SRV	K960749	soil	546853	6798223	1811	20-Feb-12	0.8	0.2	27.1	2.4	51	
SRV	K960750	soil	546876	6798170	1806	20-Feb-12	0.25	0.2	30.3	2.9	42	
DAC	K960780	soil	537712	6808764	1330	21-Feb-12						Insufficient material
DAC	K960783	soil	537569	6808699	1299	21-Feb-12						Insufficient material
DAC	K960785	soil	537488	6808624	1288	21-Feb-12						Insufficient material
SRV	K960951	soil	546728	6796789	1817	20-Feb-12	3.3	0.2	43.9	5.4	62	
SRV	K960952	soil	546763	6796759	1789	20-Feb-12	5	0.3	39	9.6	57	
SRV	K960953	soil	546814	6796744	1769	20-Feb-12	4.3	0.3	58.9	11.3	61	
SRV	K960954	soil	546856	6796711	1756	20-Feb-12	2.1	0.1	36.3	9.8	43	
SRV	K960955	soil	546906	6796685	1740	20-Feb-12	42.8	1.3	52.9	19.7	142	
SRV	K960956	soil	546955	6796656	1736	20-Feb-12	13	0.4	30.4	16.2	47	
SRV	K960957	soil	547007	6796668	1741	20-Feb-12	17.4	0.8	7.3	10.2	40	
SRV	K960958	soil	547027	6796702	1752	20-Feb-12	248.4	2.8	68.2	31.9	62	
SRV	K960959	soil	547071	6796696	1754	20-Feb-12	0.25	0.2	29.2	8.8	38	
DAC	K960960	soil	538677	6809084	1529	21-Feb-12	5.1	0.1	36.3	5.2	57	
DAC	K960961	soil	538645	6809129	1519	21-Feb-12	1.2	0.05	29.8	4	38	
DAC	K960962	soil	538637	6809185	1495	21-Feb-12	1.1	0.1	68.1	4.6	77	
DAC	K960963	soil	538624	6809217	1652	21-Feb-12	1.2	0.1	44.7	4.8	70	
DAC	K960964	soil	538651	6809281	1440	21-Feb-12	3.8	0.05	25.1	6.8	41	
DAC	K960965	soil	538646	6809326	1433	21-Feb-12	1.1	0.2	31.5	6	40	
DAC	K960966	soil	538615	6809371	1433	21-Feb-12	0.25	0.05	54.5	5	47	
DAC	K960967	soil	538591	6809418	1429	21-Feb-12	2.2	0.2	36.9	4.4	43	
DAC	K960968	soil	538565	6809453	1420	21-Feb-12	0.25	0.2	24.2	3.2	23	
DAC	K960969	soil	538538	6809509	1412	21-Feb-12	1.4	0.2	36	3.9	47	
DAC	K960970	soil	538507	6809545	1414	21-Feb-12	0.7	0.1	24.3	2.8	32	
DAC	K960971	soil	538485	6809591	1413	21-Feb-12	2.2	0.1	60	4.3	50	
DAC	K960972	soil	538445	6809634	1411	21-Feb-12	2.3	0.1	71.2	4.6	69	
DAC	K960973	soil	538437	6809694	1411	21-Feb-12	0.25	0.05	35.1	4.8	58	
DAC	K960974	soil	538401	6809735	1413	21-Feb-12	1.2	0.1	35.4	3.8	48	
DAC	K960975	soil	538357	6809786	1398	21-Feb-12	0.6	0.05	21.9	3.9	69	
DAC	K960976	soil	538686	6809045	1488	21-Feb-12	0.25	0.1	36.8	3.1	34	
DAC	K960977	soil	538827	6809082	1460	21-Feb-12	1.1	0.2	37.2	7.4	77	
DAC	K960978	soil	538876	6809084	1454	21-Feb-12	1.6	0.3	18.6	9	68	
DAC	K960979	soil	538927	6809096	1442	21-Feb-12	2	0.1	71.4	5.1	113	
DAC	K960980	soil	538968	6809111	1437	21-Feb-12	1.6	0.05	42.2	6.9	51	
DAC	K960981	soil	539014	6809123	1421	21-Feb-12	0.6	0.3	22.2	8.1	89	
DAC	K960982	soil	539055	6809141	1411	21-Feb-12	4	0.2	14.3	7.4	65	
DAC	K960983	soil	539091	6809153	1408	21-Feb-12	1.4	0.1	115.5	5.2	55	
DAC	K960984	soil	539119	6809114	1403	21-Feb-12	2.1	0.3	28.2	8.4	59	
DAC	K960985	soil	539156	6809083	1394	21-Feb-12	3.2	0.2	108.7	1.6	71	
DAC	K960986	soil	539194	6809098	1386	21-Feb-12	1.8	0.4	15.6	6.3	42	
DAC	K960987	soil	539229	6809121	1391	21-Feb-12	3.1	0.2	35	5.6	61	

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Comment	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)
SRVF	J971652	Rx-OCP	540650	6840464	1593	19-Sep-11	Mafic volcanic, Pervasive Chl alteration and quartz veining associated with Devono-Missippian mafic volcanic sequence; Potential VMS host rock.	24	0.15	312	1.5	77
SRVF	J971653	Rx-OCP	540650	6840464	1593	19-Sep-11	Graphitic schist, Disseminated sulphide within carbonaceous schist, probable metasedimentary orgin.	2.5	0.15	191	4	61
SRVF	J971654	Rx-OCP	540650	6840464	1593	19-Sep-11	Graphitic schist, Coarse-grained disseminated sulphide mineralization in metasedimentary schist	2.5	0.15	7	19	70
SRVF	J971655	Rx-OCP	540598	6840446	1574	19-Sep-11	Quartzite/schist, Disseminated sulphide (Limonite after Py) within quartzite with minor phyllitic lenses	2.5	0.15	7	8	37
SRVF	J971656	Rx-OCP	540550	6840414	1540	19-Sep-11	Phyllitic siltstone, Disseminated sulphide (Limonite after Py) within quartzite with 50% phyllitic material	2.5	0.15	5	4	25
SRVF	J971657	Rx-OCP	540550	6840414	1540	19-Sep-11	Graphitic schist, Coarse-grained Qtz-galena veins sub-parallel to parallel to foliation in graphitic phyllite; pervasive sericite alteration	11	0.15	33	20	73
SRVF	J971658	Rx-OCP	540550	6840414	1540	19-Sep-11	Graphitic schist, Late-stage Qtz-galena veins crosscutting foliation in graphitic phyllite	2.5	0.15	6	1.5	19
SRVF	J971659	Rx-OCP	540550	6840414	1540	19-Sep-11	Graphitic schist, Coarse-grained Qtz-galena veins sub-parallel to parallel to foliation in graphitic phyllite; pervasive sericite alteration	2.5	0.15	5	4	37
SRVF	J971660	Rx-OCP	540550	6840414	1540	19-Sep-11	Graphitic schist, Disseminated sulphide within graphitic schist, probable metasedimentary orgin.	7	0.15	6	17	42
SRVF	J971661	Rx-OCP	540550	6840414	1540	19-Sep-11	(ppm)	2.5	0.15	47	10	70
SRVF	J971662	Rx-SCP	540550	6840414	1540	19-Sep-11	Graphitic schist, Sericite altered graphitic schist with 5% disseminated sulphide (oxidized to limonite)	6	0.15	23	1.5	112
SRVF	J971663	Rx-SCP	540462	6840379	1548	19-Sep-11	Quartzite/schist, Disseminated sulphide (Limonite after Py) within quartzite with minor phyllitic lenses	77	1.7	7483	127	225
SRVF	J971664	Rx-SCP	540462	6840379	1548	19-Sep-11	Graphitic schist, Coarse-grained disseminated sulphide mineralization in metasedimentary schist (graphitic schist)	9	0.9	354	320	85
SRVF	J971665	Rx-SCP	539673	6840089	1615	19-Sep-11	Graphitic schist, Chlorite-epidote veining crosscutting sericite-altered graphitic schist; Vein halo characterized by bleaching.	2.5	0.15	12	1.5	66
SRVF	J971666	Rx-SCP	539673	6840089	1615	19-Sep-11	Phyllitic siltstone, Late-stage limonite veins crosscutting phyllitic-siltstone; limonite after sulphide	2.5	0.15	15	1.5	7
SRVF	J971667	Rx-SCP	539673	6840089	1615	19-Sep-11	Phyllitic siltstone, Qtz-galena veins crosscutting foliation in graphitic phyllite/siltstone unite	2.5	0.15	10	11	52
SRVF	J971668	Rx-SCP	539627	6839949	1630	19-Sep-11	Graphitic schist, Late-stage Qtz-galena veins crosscutting foliation in graphitic phyllite/siltstone unit	7	0.15	9	61	45
SRVF	J971669	Rx-SCP	539627	6839949	1630	19-Sep-11	Graphitic schist, Late-stage Qtz-galena veins crosscutting foliation in graphitic phyllite/siltstone unit	2.5	0.15	10	24	31
SRVF	J971670	Rx-SCP	539591	6839908	1633	19-Sep-11	Phyllitic siltstone, Qtz-galena veins crosscutting foliation in graphitic phyllite/siltstone unite	2.5	0.15	2	1.5	3
SRVF	J971671	Rx-SCP	539467	6839799	1650	19-Sep-11	Quartz vein, Quartz vein with open-space fill quartz growth within graphitic schist unit	2.5	0.15	83	10	73

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Comment	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)
SRVB	J971672	Rx-SCP	543075	6835752	1653	19-Sep-11	Chlorite-sericite-schist, Disseminated sulphide oxidized to limonite within foliated chlorite-sericite schist (intermediate composition); probable volcaniclastic origin	2.5	0.15	2	1.5	9
SRVB	J971675	Rx-SCP	543075	6835752	1653	19-Sep-11	Sericite schist	5	0.15	3	1.5	14
SRVB	J971676	Rx-SCP	543075	6835752	1653	19-Sep-11	Quartzite	2.5	0.15	3	1.5	6
SRVB	J971677	Rx-OCP	543051	6835759	1642	19-Sep-11	Phyllitic siltstone, Disseminated sulphide (Limonite after Py) within quartzite with 20% phyllitic material	2.5	0.15	1	1.5	6
SRVB	J971678	Rx-SCP	542870	6835862	1598	19-Sep-11	Quartzite, Silicified quarztite unit with disseminated sulphide and quartz veining; minor oxidiation of sulphide; possible Arsenopyrite	8	0.15	0.5	3	0.5
SRVB	J971679	Rx-SCP	542870	6835862	1598	19-Sep-11	Quartzite, Silicified quarztite unit with disseminated sulphide and quartz veining; minor oxidiation of sulphide; possible Arsenopyrite	22	0.15	0.5	11	1
SRVB	J971680	Rx-OCP	542855	6835841	1610	19-Sep-11	Chlorite-sericite-schist, Disseminated sulphide oxidized to limonite within foliated chlorite-sericite schist (intermediate composition); probable volcaniclastic origin	2.5	0.15	1	5	1
SRVB	J971681	Rx-OCP	542855	6835841	1610	19-Sep-11	Sericite-schist, Disseminated sulphide oxidized to limonite within foliated sericite schist (intermediate composition); probable volcaniclastic origin; Moderate silicification	7	0.15	2	7	0.5
SRVB	J971682	Rx-SCP	542855	6835841	1610	19-Sep-11	Sericite-talc schist, Strongly silicified sericite+/-talc schist with disseminated pyrite	12	0.15	2	12	1
SRVB	J971683	Rx-SCP	542855	6835841	1610	19-Sep-11	Sericite-schist, Disseminated sulphide oxidized to limonite within foliated sericite schist (intermediate composition); probable volcaniclastic origin; Moderate silicification	2.5	0.15	1	5	0.5
SRVB	J971684	Rx-SCP	542803	6835838	1659	19-Sep-11	Mafic schist, Pervasive Chl alteration and quartz veining associated with Devono-Missippian mafic volcanic sequence; Potential VMS host rock.	10	0.4	307	129	522
SRVB	J971685	Rx-OCP	542803	6835838	1659	19-Sep-11	Phyllitic siltstone, Disseminated sulphide (Limonite after Py) within quartzite with 20% phyllitic material	2.5	0.15	192	20	133
SRVB	J971686	Rx-OCP	542803	6835838	1659	19-Sep-11	Sericite-schist, Disseminated sulphide oxidized to limonite within foliated sericite schist (intermediate composition); probable volcaniclastic origin; Moderate silicification	16	0.5	495	72	381
SRVB	J971687	Rx-OCP	542803	6835838	1659	19-Sep-11	Mafic volcanic schist, Mafic volcanic schist with minor Qtz-galena veins; pervasive chlorite alteration	2.5	0.15	150	7	685
SRVB	J971688	Rx-OCP	542673	6835901	1590	19-Sep-11	Qtz-sericite schist, Qtz-sercite schist with disseminated Py; minor limonite alteration	2.5	0.15	19	11	9
SRVB	J971689	Rx-OCP	538625	6834072	1532	19-Sep-11	Qtz-sericite schist, Qtz-sercite-talc schist with disseminated Py; minor limonite alteration	2.5	0.15	6	21	16
SRVF	J971690	Rx-OCP	538570	6834092	1520	19-Sep-11	Qtz-sericite schist, Qtz-sercite-talc schist with disseminated Py; minor limonite alteration	2.5	0.15	13	15	21
SRVF	J971691	Rx-SCP	538570	6834092	1520	19-Sep-11	Qtz-sericite schist, Qtz-sericite schist (bleached) crosscut by late Qtz-galena vein	2.5	0.15	51	11	8
SRVF	J971692	Rx-SCP	538297	6833838	1466	19-Sep-11	Graphitic schist, Disseminated sulphide within graphitic schist, probable metasedimentary orgin;	2.5	1.4	136	13	19

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Comment	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)
SRVB	J971693	Rx-SCP	542457	6830715	1629	20-Sep-11	Fault breccia, Silicified fault breccia with late silcification and open space fill quartz growth; Limonite in voids potentially after sulphide.	2.5	0.15	0.5	3	3
SRVB	J971694	Rx-SCP	542457	6830715	1629	20-Sep-11	Fault breccia, Silicified fault breccia with late silcification and open space fill quartz growth; Limonite in voids potentially after sulphide.	2.5	0.15	2	5	7
SRVB	J971695	Rx-SCP	542457	6830715	1629	20-Sep-11	Carbonate vein, Punky yellow carbonate (?) vein +/- limonite alteration; Boxwork textures	7	0.15	4	1.5	11
SRVB	J971696	Rx-SCP	542457	6830715	1629	20-Sep-11	Carbonate vein, Punky yellow carbonate (?) vein +/- limonite alteration; Boxwork textures; Minor secondary silicification	2.5	0.15	1	1.5	2
SRVB	J971697	Rx-SCP	542457	6830715	1629	20-Sep-11	Carbonate vein, Punky yellow carbonate (?) vein +/- limonite alteration; Boxwork textures; Minor secondary silicification	2.5	0.15	0.5	1.5	0.5
SRVB	J971698	Rx-SCP	542457	6830715	1629	20-Sep-11	Fault breccia, Silicified fault breccia with late silcification and open space fill quartz growth; Limonite in voids potentially after sulphide.	2.5	0.15	7	30	5
SRVB	J971699	Rx-SCP	542457	6830715	1629	20-Sep-11	Quartzite, Coarse-grained Qtz-galena vein in quartzite (5% sericite)	2.5	0.15	0.5	9	22
SRVB	J971700	Rx-SCP	542457	6830715	1629	20-Sep-11	Carbonate vein, Punky yellow carbonate (?) vein +/- limonite alteration; Collorform epithermal textures; Secondry calcite filling voids	2.5	0.15	2	1.5	4
SRVB	J971701	Rx-OCP	542457	6830715	1629	20-Sep-11	Qtz-sericite schist, Qtz-sercite-schist with disseminated Py; minor limonite alteration	6	0.6	44	36	33
SRVB	J971702	Rx-OCP	541892	6830781	1535	20-Sep-11	Quartzite, Coarse-grained Qtz-galena vein in quartzite (5% sericite)	2.5	0.15	58	32	25
SRVB	J971703	Rx-FL	541807	6830740	1532	20-Sep-11	Quartzite, Coarse-grained Qtz-galena vein in quartzite (5% sericite)	2.5	0.15	49	80	96
SRVB	J971704	Rx-SCP	541787	6830726	1530	20-Sep-11	Graphitic schist, Late-stage Qtz-galena veins crosscutting foliation in graphitic phyllite/siltstone unit	2.5	0.15	19	22	78
SRVB	J971705	Rx-OCP	541299	6830962	1438	20-Sep-11	Quartzite, Coarse-grained Qtz-galena vein in quartzite (5% sericite)	2.5	0.15	56	22	51
SRVB	J971706	Rx-SCP	541255	6829517	1940	20-Sep-11	Mafic volcanic schist, Mafic volcanic schist with minor Qtz-galena veins; pervasive chlorite-sericite alteration	14	0.15	217	1.5	125
SRVB	J971707	Rx-SCP	541302	6829522	1915	20-Sep-11	Chlorite-sericite-schist, Disseminated sulphide oxidized to limonite within foliated chlorite-sericite schist (intermediate composition); probable volcaniclastic origin	2.5	0.15	115	30	256
SRVB	J971708	Rx-SCP	541302	6829522	1915	20-Sep-11	Chlorite-sericite-schist, Disseminated sulphide oxidized to limonite within foliated chlorite-sericite schist (intermediate composition); probable volcaniclastic origin	2.5	0.15	47	32	171
SRVB	J971709	Rx-SCP	541317	6829539	1878	20-Sep-11	Qtz-sericite schist, Limonite+Hematite alteration of Qtz-sericite schist; Fault zone	6	0.15	123	10	58
SRVB	J971710	Rx-SCP	541317	6829539	1878	20-Sep-11	Qtz-sericite schist, Disseminated oxidized sulphide (limonite) within sericite schist	2.5	0.15	90	13	59
SRVB	J971711	Rx-SCP	541317	6829539	1878	20-Sep-11	Qtz-sericite schist, Late-stage Qtz-galena veins crosscutting foliation in graphitic phyllite/siltstone unit	2.5	0.15	67	1.5	183
SRVB	J971712	Rx-SCP	541317	6829539	1878	20-Sep-11	Qtz-sericite schist, Disseminated sulphide in qtz-sericite schist	2.5	0.15	3	1.5	66

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Comment	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)
SRVB	J971713	Rx-OCP	541347	6829538	1863	20-Sep-11	Qtz vein, Quartz-galena vein crosscutting graphitic schist	2.5	0.15	12	6	15
SRVB	J971714	Rx-OCP	541347	6829538	1863	20-Sep-11	Qtz vein, Quartz-galena vein crosscutting graphitic schist	2.5	0.15	6	1.5	6
SRVB	J971715	Rx-OCP	542292	6832666	1913	20-Sep-11	Qtz-sericite schist, Qtz-sercite-schist with disseminated Py and Qtz-galena veins; minor limonite alteration	2.5	0.15	5	8	47
SRVB	J971716	Rx-SCP	542292	6832666	1913	20-Sep-11	Carbonate vein, Porous and punky textured carbonate; dark blue-grey to black colour	2.5	0.15	2	6	7
SRVB	J971717	Rx-OCP	540527	6832445	1698	20-Sep-11	Qtz-sericite schist, Qtz-sercite-schist with disseminated Py; Sulphide oxidized to limonite	51	0.15	8	9	22
SRVB	J971718	Rx-OCP	540408	6832349	1658	20-Sep-11	Qtz-sericite schist, Qtz-sercite-schist with disseminated Py and Qtz-galena veins; minor limonite alteration	7	0.15	1	1.5	13
SRVB	J971719	Rx-OCP	540144	6832260	1605	20-Sep-11	Graphitic schist, Disseminated sulphide within graphitic schist, probable metasedimentary orgin.	2.5	0.15	109	8	109
JJW	J971720	Rx-SCP	543282	6818154	1491	21-Sep-11	Qtz-sericite schist, Qtz-sercite-schist with disseminated Py; Sulphide oxidized to limonite; Late-stage crosscutting limonite fracture network	2.5	0.15	14	14	46
JJW	J971721	Rx-OCP	543095	6818180	1472	21-Sep-11	Quartzite, Disseminated Py-Po in light blue-grey coloured quartzite	2.5	1.5	10	1.5	322
MCPN	J971722	Rx-SCP	546185	6816418	1712	21-Sep-11	Qtz-sericite schist, Late-stage Qtz-galena veins crosscutting foliation in graphitic phyllite/siltstone unit	2.5	88.6	123	31700	10
MCPN	J971723	Rx-SCP	546150	6816464	1708	21-Sep-11	Graphitic schist, Siliceous siltstone/ graphitic with disseminate Po-Py an quartz veining	2.5	0.8	41	283	102
MCPN	J971726	Rx-OCP	546150	6816464	1708	21-Sep-11	Quartzite, Fine-grained quartzite with disseminated sulphide and galena-qtz veining;	2.5	10.6	97	4163	31
MCPN	J971727	Rx-OCP	546150	6816464	1708	21-Sep-11	Qtz-sericite schist, coarse-grained galena-quartz vein in qtz-sericite schist	2.5	44	19	13200	0.5
MCPN	J971728	Rx-OCP	546267	6816270	1737	21-Sep-11	Qtz-sericite-biotite-schist, Qtz-sercite schist with disseminated sulphide and overprinted by secondary Bt (contact metamorphism)	2.5	2.6	89	757	24
MCPN	J971729	Rx-OCP	546267	6816270	1737	21-Sep-11	Qtz-sericite-biotite-schist, Qtz-sercite schist with disseminated galena	2.5	0.15	21	16	20
MCPN	J971730	Rx-OCP	546267	6816270	1737	21-Sep-11	Qtz-sericite schist, Coarse-grained galena-quartz vein in qtz-sericite schist	16	29.9	93	18300	9
SRVD	J971731	Rx-SCP	550688	6807117	1576	21-Sep-11	Graphitic schist, Qtz-galena veins in graphitic phyllite/siltstone unit; Disseminated pyrite within graphitic siltstone	2.5	0.8	27	177	152
SRVD	J971732	Rx-SCP	550688	6807117	1576	21-Sep-11	Carbonaceous shale, Black carbonaceous shale crosscut by polyphase calcite veining; fault related.	2.5	0.15	6	57	115
SRVD	J971733	Rx-SCP	550688	6807117	1576	21-Sep-11	Graphitic schist, Qtz-galena veins in graphitic phyllite/siltstone unit; Disseminated pyrite within graphitic siltstone	2.5	0.3	32	21	88
SRVD	J971734	Rx-SCP	550688	6807117	1576	21-Sep-11	Carbonaceous shale, Black carbonaceous shale crosscut by polyphase calcite and quartz veining; fault related.	2.5	1.2	13	25	121
DACX	J971755	Rx-OCP	534234	6809079	1081	23-Sep-11	fault breccia, Silicified and limonite altered fault breccia within sericite-qtz schist	2.5	0.15	3	18	36

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Comment	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)
DACX	J971756	Rx-OCP	534234	6809079	1081	23-Sep-11	fault breccia, Strongly clay altered and brecciated fault gouge within sericite-qtz schist.	2.5	0.15	41	8	97
DACX	J971757	Rx-OCP	534234	6809079	1081	23-Sep-11	fault breccia, Strongly clay altered and brecciated fault gouge within sericite-qtz schist.	2.5	0.15	38	6	86
DACX	J971758	Rx-OCP	534234	6809079	1081	23-Sep-11	Sericite-qtz schist, Limonite altered qtz-sericite schist within main N-trending fault zone; immediately adajcent to strong gouge zones	2.5	0.15	61	3	92
SRVF	J971803	Rx-OCP	540646.73	6840461.79	1589	19-Sep-11	Quartz-cb vein, Quartz-carbonate veining hosted in sheared mafic / ultramafic rocks. Veining is coarse grained, moderately vuggy, vugs lined with dark brown oxides; sericite and spotty lim (hem). Located on slopes to the south and above anomalous stream sediment samples K735162 (>100 ppb Au), K735163 (51.7 ppb Au), K735027 (94.2 ppb Au).	10	1	4	1.5	16
SRVF	J971804	Rx-FL	540555.26	6840403.67	1550.7	19-Sep-11	Quartz vein, Quartz veining in quartz muscovite schist. Angular float. Quartz is sugary textured, glassy, with 2-4% limonite clots. No visible sulphides. Located on slopes to the south and above anomalous stream sediment samples K735162 (>100 ppb Au), K735163 (51.7 ppb Au), K735027 (94.2 ppb Au).	14	1	11	17	47
SRVF	J971805	Rx-OCP	540561.42	6840396.73	1553.7	19-Sep-11	Quartz vein, Quartz veining, pods and lenses in quartz muscovite schist. Quartz is sugary textured, glassy, vuggy with 5-8% limonite clots; frequent late fractures. Trace visible galena. Located on slopes to the south and above anomalous stream sediment samples K735162 (>100 ppb Au), K735163 (51.7 ppb), K735027 (94.2 ppb Au).	32	1	39	40	44
SRVF	J971806	Rx-FL	539636.53	6839960.27	1633.8	19-Sep-11	Quartz vein, Quartz vein float (angular); qtz is sugary textured, opaque to glassy with lim oxidized fractures and pods. Trace to 1% fine grained blue-grey silvery sulphide (possibly galena?). Hosted in qtz-mus-chl-schist. Located on slopes to the south and above anomalous stream sediment samples K735162 (>100 ppb Au), K735163 (51.7 ppb), K735027 (94.2 ppb Au).	16	1	7	8	6
SRVF	J971807	Rx-FL	539585.98	6839924.6	1637.7	19-Sep-11	Quartz vein, Quartz vein float (angular); qtz is coarse grained, opaque to glassy with lim oxidized pods. Trace fine grained blue-grey silvery sulphide (possibly galena?). Hosted in qtz-mus-chl-schist. Located on slopes to the south and above anomalous stream sediment samples K735162 (>100 ppb Au), K735163 (51.7 ppb).	13	1	4	10	10
SRVB	J971808	Rx-FL	543134.11	6835671.26	1665.8	19-Sep-11	Quartz vein, Quartz vein float (angular); qtz is sugary textured, opaque to glassy with lim fractures. Trace fine grained blue-grey silvery sulphide. Hosted in qtz-mus-chl-schist. Located on slopes to the south and above anomalous stream sediment sample K735082 (44.2 ppb Au, 172.5 Ni).	13	1	1	1.5	11
SRVB	J971809	Rx-SCP	543050.22	6835766.58	1644.6	19-Sep-11	Ultramafic, Strongly altered rock, difficult to say the original rock type. Angular float close to source. Variably bleached cream color with frequent oxidized fractures along previous foliation; siliceous. Spotted with small vugs lined with limonite.	18	1	2	1.5	9

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Comment	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)
SRVB	J971810	Rx-FL	542926.23	6835849.37	1611.8	19-Sep-11	Quartz sericite schist, Angular float of quartz sericite schist, close to source. Rusty orange-brown weathering, fresh surface has a yellow-green color. Strongly siliceous, with 5% discontinuous vuggy stringers lined with limonite.	13	1	2	1.5	4
SRVB	J971811	Rx-FL	542869.75	6835862.37	1600.8	19-Sep-11	Quartz chlorite schist, Angular float of quartz chlorite schist, close to source. Rusty orange-brown weathering, fresh surface has a yellow-green color; 1% disseminated pyrite.	47	1	12	23	45
SRVB	J971812	Rx-FL	542837.08	6835848.37	1604.8	19-Sep-11	Quartz muscovite schist, Angular float of quartz muscovite schist. Strong yellow to orange-brown weathering, strongly siliceous. Pock-marked, vuggy texture with 3% weathered out sulphides (some are pyrite cubes). The rock has a rotten, crumbly look.	20	1	3	10	1
SRVB	J971813	Rx-FL	542837.08	6835848.37	1604.8	19-Sep-11	Quartz muscovite schist, Angular float of quartz muscovite schist. Strong yellow to orange-brown weathering, oxidized lenses to 1mm as well as siliceous bands. Possibly VMS-type mineralization? 2% oxidized sulphides.	9	1	7	5	10
SRVB	J971814	Rx-FL	542819.86	6835840.84	1608.5	19-Sep-11	Quartz muscovite schist, Angular float of quartz muscovite schist. Strong yellow to orange-brown weathering, oxidized lenses to 1mm as well as siliceous bands. Possibly VMS-type mineralization? 5% oxidized sulphide pods and lenses.	34	1	577	13	374
SRVB	J971815	Rx-FL	542797.63	6835830.28	1611.5	19-Sep-11	VMS, Angular float; dense, heavy rock, chlorite schist with 10% fine grained layered sulphides. Magnetite for sure as rock is strongly magnetic. Also possible black sphalerite? Rusty, weakly oxidized lenses are dark brown in color.	6	1	1203	7	1574
SRVB	J971816	Rx-FL	542797.63	6835830.28	1611.5	19-Sep-11	VMS, Angular float; dense, heavy rock, chlorite schist. Slightly more oxidized than the previous sample with 15% fine grained layered sulphides. Rock is strongly magnetic with magnetite and possible sphalerite (?).	8	1	89	18	469
SRVB	J971817	Rx-FL	542797.63	6835830.28	1611.5	19-Sep-11	Quartz muscovite schist, Angular float of quartz muscovite schist. Strong yellow to orange-brown weathering, oxidized lenses to 1mm as well as siliceous bands. Possibly VMS-type mineralization? 5% oxidized sulphide pods and lenses. Not magnetic like the two previous samples.	23	1	499	52	702
SRVB	J971818	Rx-FL	542797.63	6835830.28	1611.5	19-Sep-11	VMS-oxidized, Angular float, strongly oxidized quartz muscovite schist, punky, vuggy, non-magnetic. 8-10% limonite.	59	5	913	278	59
SRVB	J971819	Rx-FL	542745.81	6835860.39	1603.6	19-Sep-11	Quartz muscovite schist, Angular float of quartz muscovite schist. Moderate yellow to orange-brown weathering, oxidized lenses to 1mm as well as siliceous bands. Possibly VMS-type mineralization? 5% oxidized sulphide pods and lenses. Not magnetic.	27	1	368	17	52
SRVB	J971820	Rx-FL	542664.04	6835905.72	1588.6	19-Sep-11	Ultramafic, Angular float of ultramafic-looking rock, 2% oxidized fractures and discontinuous pods, 1% disseminated pyrite.	6	1	56	5	74
SRVF	J971821	Rx-FL	538698.11	6834062.53	1582.8	19-Sep-11	Quartz-cb vein, Quartz-carbonate veining hosted in quartz muscovite schist. Veining is sugary textured, fractured,moderately vuggy, vugs lined with dark brown oxides. Located on slopes to the southeast and above anomalous stream sediment sample K735029 (4	2.5	1	10	1.5	18

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Comment	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)
SRVF	J971822	Rx-FL	538597.61	6834072.77	1566.2	19-Sep-11	Quartz vein, Distinctive tan, rough textured Fe-carbonate weathering style, quartz-fe-carb veining in quartzite. Limonite pods and fracture coating. Located on slopes to the southeast and above anomalous stream sediment sample K735029 (42.1 ppb Au).	7	1	17	26	39
SRVF	J971823	Rx-FL	538526.05	6834068.41	1536.4	19-Sep-11	Quartz-cb vein, More quartz vein angular float, both sugar textured and coarser grained with 5-7% powdery limonite pods with carbonate. Trace unoxidized silvery-blue sulphide. Located on slopes to the southeast and above anomalous stream sediment sample K735029 (42.1 ppb Au).	5	1	2	9	22
SRVB	J971824	Rx-SCP	542518.32	6830778.91	1568.6	20-Sep-11	Quartz sericite schist, Pervaisive limonite in quartz sericite schist. Located on the slopes above several anomalous stream sediment samples (K735121 - 98 ppb Au, K735122 - 61 ppb Au and K735119 - >100 ppb Au - all weakly elevated in arsenic).	5	1	27	19	65
SRVB	J971825	Rx-SCP	542460.63	6830715.37	1578	20-Sep-11	Fault, Probable fault zone with coarse grained calcite crystals as well as epithermal style colloform quartz-cb open-space fill. Located on the slopes above several anomalous stream sediment samples (K735121 - 98 ppb Au, K735122 - 61 ppb Au and K735119 - >100 ppb Au - all weakly elevated in arsenic).	8	1	3	1.5	5
SRVB	J971826	Rx-SCP	542439.16	6830699.43	1583	20-Sep-11	Quartz vein, Semi-opaque coarse grained quartz veining in quartz muscovite schist. 3-5% powdery limonite clots, vugs and fractures. Weak fe-carbonate. Located on the slopes above several anomalous stream sediment samples (K735121 - 98 ppb Au, K735122 - 61 ppb Au and K735119 - >100 ppb Au - all weakly elevated in arsenic).	6	1	2	23	30
SRVB	J971827	Rx-SCP	542399.06	6830674.29	1594	20-Sep-11	Quartz-cb vein, Quartz-cb vein, vuggy, coarse grained calcite to 2cm. Some areas show vague banding / epithermal-type veining. 2-3% pale orange oxide filling vugs. Located on the slopes above several anomalous stream sediment samples (K735121 - 98 ppb Au , K735122 - 61 ppb Au and K735119 - >100 ppb Au - all weakly elevated in arsenic).	7	1	0.5	8	3
SRVB	J971828	Rx-SCP	542238.13	6830714.98	1581.1	20-Sep-11	Quartz vein, Semi-opaque coarse grained quartz veining in quartz muscovite schist. 3-5% powdery limonite clots, vugs and fractures. Located on the slopes above several anomalous stream sediment samples (K735121 - 98 ppb Au, K735122 - 61 ppb Au and K735119 - >100 ppb Au - all weakly elevated in arsenic).	5	1	1	81	7
SRVB	J971829	Rx-FL	541993.86	6830732.84	1560.6	20-Sep-11	Quartz muscovite schist, Angular float of quartz veined, Fe-cb altered quartz muscovite schist. 3-5% powdery limonite vugs. Located on the slopes above several anomalous stream sediment samples (K735121 - 98 ppb Au, K735122 - 61 ppb Au and K735119 - >100 ppb Au - all weakly elevated in arsenic).	7	1	11	30	43
SRVB	J971830	Rx-FL	541940.2	6830734.53	1555.8	20-Sep-11	Quartz-cb vein, Quartz-cb vein, vuggy, net-textured cross-cutting stringers. in quartz muscovite schist. 3-5% orange-brown oxide filling vugs. Located on the slopes above several anomalous stream sediment samples (K735121 - 98 ppb Au, K735122 - 61 ppb Au and K735119 - >100 ppb Au - all weakly elevated in arsenic).	2.5	1	5	15	26

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Comment	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)
SRVB	J971831	Rx-FL	541294.23	6830954.46	1440.4	20-Sep-11	Quartzite, layered quartz-rich rock. Layers ~1 cm thick and alternate between glassy grey quartz, coarser grained and white, opaque, sugar-textured quartz layers. Spotted with 1% dissem sulphides (py and a dark grey-black sulphide - gn or sph?). vertical to layering, oxidized microfractures. Located on the slopes above several anomalous stream sediment samples (K735121 - 98 ppb Au, K735122 - 61 ppb Au and K735119 - >100 ppb Au - all weakly elevated in arsenic).	2.5	1	7	5	24
SRVB	J971832	Rx-SCP	541243.61	6829515.39	1824.7	20-Sep-11	Fault breccia, Orange-cream colored angular to sub-angular fragments of sericite schist, 2 - 15mm in a brown ground up mica matrix, with weak hematite stain. Borders between a clast and matrix supported breccia. Multi-phase as some of the breccia frags have been previously healed and then re-fractured. No visible sulphides. Located on the slopes above anomalous stream sediment sample (K735119 - >100 ppb Au).	9	1	108	11	102
SRVB	J971833	Rx-FL	541243.61	6829515.39	1824.7	20-Sep-11	Quartz vein, Angular scree, fractured coarsed grained quartz vein in quartz mus schist, patchy hematite, limonite and manganeese stain. Trace finely disseminated sulphide (py?). Sampled near the previous sample. Located on the slopes above anomalous stream sediment sample (K735119 - >100 ppb Au).	8	1	95	5	57
SRVB	J971834	Rx-SCP	541205.23	6829511.04	1815.8	20-Sep-11	Quartz vein, Fractured to weakly brecciated quartz vein, limonite and manganeese stain. Located on the slopes above anomalous stream sediment sample (K735119 - >100 ppb Au).	9	1	145	25	69
SRVB	J971835	Rx-SCP	541205.23	6829511.04	1815.8	20-Sep-11	Quartz vein, Fractured to weakly brecciated quartz vein, limonite and manganeese stain. Some rainbow colored stain also. Frequent inclusions of quartz chlorite (sericite) schist. Located on the slopes above anomalous stream sediment sample (K735119 - >100 ppb Au).	9	1	35	6	35
SRVB	J971836	Rx-SCP	541230.81	6829511.12	1812.3	20-Sep-11	Quartz muscovite schist, Sheared, quartz veined quartz muscovite (sericite) schist; vuggy intervals strongly stained dark brown or limonitic orange. Quartz is granular, sugary-textured. No visible sulphides. Located on the slopes above anomalous stream sediment sample (K735119 - >100 ppb Au).	7	1	54	16	50
SRVB	J971837	Rx-FL	540362.39	6832330.21	1645.2	20-Sep-11	Quartz muscovite schist, Quartz muscovite schist, moderate carbonate altered (strong fizz with acid), spotted with patches of a very bright apple green mineral - fuchsite?? No visible sulphides. Located on the slopes above several anomalous stream sediment samples (K735121 - 98 ppb Au and K735122 - 61 ppb Au, weakly elevated in arsenic).	7	1	2	6	49
SRVB	J971838	Rx-FL	539933.76	6832118.79	1561	20-Sep-11	Quartz sericite schist, Quartz-rich rock - possibly quartzite, limonite stained, foliated with sericite along foliation. Located on the slopes above several anomalous stream sediment samples (K735121 - 98 ppb Au and K735122 - 61 ppb Au, weakly elevated in arsenic).	2.5	1	5	4	27
MCPN	J971839	Rx-OCP	544171.74	6818376.17	1460	21-Sep-11	Quartzite, Foliated quartzite with sericite, limonite along foliation 330/85. Sparse vugs have hematite coating. Trace disseminated py. Located on slopes above weakly anomalous gold, but predominantly anomalous Pb-Zn.	8	1	47	4	45

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Comment	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)
MCPN	J971840	Rx-FL	544415.17	6818593.06	1461.6	21-Sep-11	Quartz muscovite schist, Float of foliated quartz muscovite schist with sericite, limonite and yellowish stain along foliation . Sparse vugs have hematite coating. Trace disseminated py. Located on slopes above weakly anomalous gold, but predominantly anomalous Pb-Zn.	7	1	46	46	60
MCPN	J971841	Rx-FL	544531.93	6818750.86	1483.9	21-Sep-11	Quartz-cb vein, Quartz (carbonate) vein in schist - angular float. Moderate limonite stain. No visible sulphides. Located on slopes above weakly anomalous gold, but predominantly anomalous Pb-Zn.	5	1	3	23	28
MCPN	J971842	Rx-SCP	544701	6818814.31	1528.2	21-Sep-11	Quartz muscovite schist, Angular float of quartz muscovite schist with irregular quartz carbonate stringers. Moderate-strong limonite oxidation. Trace visible disseminated py. Located on slopes above weakly anomalous gold, but predominantly anomalous Pb-Zn	7	1	12	8	47
MCPN	J971843	Rx-FL	544741.49	6818824.63	1543.2	21-Sep-11	Quartzite, Called a quartzite, but may be some type of siliceous fe-carbonate rich rock. Pale orange, fine grained, weak pervasive reaction with HCL. No visible sulphides. Located on slopes above weakly anomalous gold, but predominantly anomalous Pb-Zn.	6	1	1	1.5	0.5
MCPN	J971844	Rx-FL	544750.65	6818828.43	1543.6	21-Sep-11	Quartz vein, Coarse sugary textured quartz vein float, moderate-strong limonite along fractures. Trace visible fine grained sulphides (py?). Located on slopes above weakly anomalous gold, but predominantly anomalous Pb-Zn.	2.5	1	13	1.5	3
MCPN	J971845	Rx-OCP	546188.44	6816417.18	1715.8	21-Sep-11	Outcrop of quartz vein with galena mineralization (Minfile Occurrence 105E 064, discovered in 2005 by M. Colpron of YGS). Galena mineralization in quartz vein cuts calcareous quartzite (Upper Devonian). Galena occurs as pods, fine to medium grained, 0.5 - 5cm pods. The quartz veins vary from 0.4 - 4 m wide, are discontinuous and often split into smaller veins. Trend ~330 dipping steeply.	8	16	28	5323	6
MCPN	J971846	Rx-OCP	546149.26	6816467.02	1707.1	21-Sep-11	Quartz gn vein, High grade sample. Outcrop of quartz vein with galena mineralization (Minfile Occurrence 105E 064, discovered in 2005 by M. Colpron of YGS). Galena mineralization in quartz vein cuts calcareous quartzite (Upper Devonian). Galena occurs as pods, fine to medium grained, 0.5 - 5cm pods. The quartz veins vary from 0.4 - 4 m wide, are discontinuous and often split into smaller veins. Trend ~330 dipping steeply.	22	84	65	66800	0.5
MCPN	J971847	Rx-OCP	546141.41	6816468.02	1698.3	21-Sep-11	Quartz sericite schist, Host rock of the quartz galena veins. Some graphite along foliation of the quartz sericite schist; moderate limonite.	2.5	1	144	176	62
MCPN	K948201	Rx-OCP	546183.32	6816385.25	1706.1	21-Sep-11	Quartz gn vein, Outcrop of quartz vein with galena mineralization (Minfile Occurrence 105E 064, discovered in 2005 by M. Colpron of YGS). The sample here has much less gn (.5%) but has possible scorodite stain. Galena mineralization in quartz vein cuts calcareous quartzite (Upper Devonian), and quartz sericite schist. Galena occurs as pods, fine to medium grained, 0.5 - 5cm pods. The quartz veins vary from 0.4 - 4 m wide, are discontinuous and often split into smaller veins.	8	1	91	101	19

Claim	Sample ID	Samp Code	Easting (NAD83-8)	Northing (NAD83-8)	Elv'n (m)	Date	Comment	Au (ppb)	Ag (ppm)	Cu (ppm)	Pb (ppm)	Zn (ppm)
SRVD	K948202	Rx-FL	550565.73	6807085.98	1598.1	21-Sep-11	Quartz-cb vein, Angular float of quartz-carbonate veined graphitic schist; spotted with rusty limonitic vugs. Located on the slopes above anomalous stream sediment sample K735033 with 27 ppb Au and elevated zinc.	7	2	3	139	6
SRVD	K948203	Rx-FL	550567.03	6807106.94	1593.4	21-Sep-11	Limestone, Angular float of dark grey weathering carbonaceous limestone / calcareous carbonaceous siltstone; 3% cross-cutting conjugate quartz stringers, 0.5-5mm in width. No visible sulphides. Located on the slopes above anomalous stream sediment sample K735033 with 27 ppb Au and elevated zinc.	18	1	4	51	233
SRVD	K948204	Rx-OCP	550568.49	6807116.99	1587.4	21-Sep-11	Quartz muscovite schist, Quartz-carbonate veined quartz muscovite schist (graphitic); weak rusty fractures, no visible sulphides. Foliation 160/35 SW. Located on the slopes above anomalous stream sediment sample K735033 with 27 ppb Au and elevated zinc.	9	1	2	21	8
SRVD	K948205	Rx-OCP	550536	6807163	1595	21-Sep-11	Quartz muscovite schist, Mike Burke sample. Boudinaged quartz pods that are cut by later vertical quartz stringers / fractures. Pods are strongly oxidized with limonite, rare unoxidized sulphides present. Located on the slopes above anomalous stream sediment sample K735033 with 27 ppb Au and elevated zinc.	10	1	14	5	77
DACX	K948206	Rx-OCP	535745.03	6806818.27	1000	21-Sep-11	Shear Zone, Shear zone in friable sericite schist; 160/90. No visible sulphides. Occurs along Cotteneva Creek as past producing placer mine. Above anomalous stream sediment sample K735167 with 860 ppb Au, also elevated in Pb and Zn.	1077	35	73	16	104
DACX	K948220	Rx-OCP	534229.87	6809068.79	886.3	23-Sep-11	Fault breccia, One meter chip sample; fault breccia, gouge, strongly limonite altered in north-south trending fault through sericite-quartz schist.	7	1	144	6	109
DACX	K948221	Rx-OCP	534229.87	6809068.79	886.3	23-Sep-11	Fault gouge, Grab sample of a portion of the previous sample, distinctive pale green clay altered pod of material.	17	1	124	10	150
DACX	K948222	Rx-OCP	534231.47	6809068.24	885.3	23-Sep-11	Fault breccia, One meter chip sample; fault breccia, gouge, strongly limonite altered in north-south trending fault through sericite-quartz schist.	6	1	85	5	173
DACX	K948223	Rx-OCP	534230.87	6809070.13	885.4	23-Sep-11	Fault breccia, One meter chip sample; fault breccia, gouge, strongly limonite altered in north-south trending fault through sericite-quartz schist.	10	1	160	9	140
DACX	K948224	Rx-OCP	534230.02	6809069.57	884.3	23-Sep-11	Fault breccia, One meter chip sample; fault breccia, partly strongly silicified, strongly limonite altered in north-south trending fault through sericite-quartz schist.	6	1	140	5	93
DACX	K948225	Rx-OCP	534233.11	6809070.38	882.5	23-Sep-11	Fault breccia, One meter chip sample; fault breccia, partly strongly silicified, strongly limonite altered in north-south trending fault through sericite-quartz schist.	10	1	249	4	65
DACX	K948226	Rx-OCP	534233.15	6809071.16	881.7	23-Sep-11	Fault breccia, One meter chip sample; fault breccia, gouge, strongly limonite altered in north-south trending fault through sericite-quartz schist.	10	1	223	5	88

Appendix 3
Assay Certificates

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

CERTIFICATE WH11109441

Project: Stream seds

P.O. No.: GPD2011LIV003

This report is for 100 Stream Sediment samples submitted to our lab in Whitehorse, YT, Canada on 16- JUN- 2011.

The following have access to data associated with this certificate:

MIKE BURKE LINDA LEWIS	ANDREW CALDWELL MIKE MASLOWSKI	JACK COTE

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI- 21	Received Sample Weight
LOG- 21d	Sample logging - ClientBarCode Dup
SPL- 34	Pulp Splitting Charge
LOG- 22	Sample login - Rcd w/o BarCode
LOG- 23	Pulp Login - Rcvd with Barcode
SCR- 41	Screen to - 180um and save both

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au- OG44	Ore Grade Au - 50g AR	ICP- MS
Au- ST44	Super Trace Au - 50g AR	ICP- MS
ME- MS41	51 anal. aqua regia ICPMS	

To: GOLDEN PREDATOR CANADA CORP.
ATTN: JACK COTE
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Sample Description	Method	WEI- 21	Au- ST44	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr	
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	
	LOR	.02	0.0001	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1	
K735176		7.40	0.0009	0.04	0.61	1.4	<0.2	<10	30	0.10	0.07	0.32	0.19	21.2	6.3	9	
K735177		5.86	0.0012	0.06	0.78	3.5	<0.2	<10	40	0.18	0.16	0.35	0.32	33.4	9.4	14	
K735178		7.80	0.0478	0.04	0.94	3.7	<0.2	<10	130	0.35	0.10	0.46	0.17	28.7	10.7	28	
K735179		6.94	0.0020	0.05	1.58	9.9	<0.2	<10	150	0.36	0.08	1.21	0.23	25.7	17.6	35	
K735180		5.76	0.0016	0.03	1.27	4.4	<0.2	<10	120	0.31	0.06	0.86	0.13	18.55	10.0	25	
K735181		5.00	0.0024	0.03	1.31	5.7	<0.2	<10	80	0.38	0.08	1.02	0.16	18.65	11.4	26	
K735182		6.54	0.0034	0.03	1.61	7.1	<0.2	<10	100	0.44	1.57	1.21	0.21	22.6	15.6	40	
K735183		5.08	0.0029	0.03	1.26	3.9	<0.2	<10	80	0.32	0.05	1.01	0.07	17.55	10.0	25	
K735184		7.82	0.0311	0.02	1.43	5.5	<0.2	<10	80	0.41	0.08	1.15	0.14	18.15	13.1	37	
K735185		5.84	0.0022	0.03	1.51	7.3	<0.2	<10	130	0.31	0.05	1.03	0.12	16.70	16.3	55	
K735186		6.02	0.0013	0.04	0.97	4.8	<0.2	<10	110	0.25	0.05	0.90	0.11	14.60	8.7	37	
K735187		7.06	0.0017	0.27	0.65	24.8	<0.2	<10	80	0.18	0.21	0.25	1.93	18.25	10.0	26	
K735188		6.58	0.0012	0.11	0.88	8.0	<0.2	<10	90	0.17	0.07	0.45	0.47	12.90	14.3	62	
K735189		6.74	0.0011	0.17	0.75	14.4	<0.2	<10	180	0.19	0.10	0.76	0.66	15.75	12.3	44	
K735190		6.26	0.0004	0.08	0.91	6.0	<0.2	<10	60	0.13	0.09	0.40	0.27	12.70	9.8	60	
K735191		6.70	0.0025	0.11	0.92	43.4	<0.2	<10	460	0.36	0.08	0.63	0.47	17.25	16.7	49	
K735192		5.66	0.0011	0.14	1.79	6.4	<0.2	<10	110	0.31	0.07	1.31	0.45	16.55	11.3	52	
K735193		7.04	0.0008	0.05	1.89	4.0	<0.2	<10	90	0.26	0.05	0.81	0.19	15.60	13.8	46	
K735194		7.24	0.0011	0.09	1.53	4.9	<0.2	<10	90	0.26	0.06	1.54	0.21	14.80	10.5	43	
K735195		0.18	0.0012	0.19	1.06	3.8	<0.2	<10	80	0.20	0.05	0.66	0.16	10.45	7.3	30	
K735196		5.84	0.0045	0.06	2.05	30.4	<0.2	<10	60	0.25	0.07	0.68	0.26	16.60	19.9	74	
K735197		5.90	0.0034	0.11	2.25	25.8	<0.2	10	60	0.36	0.07	1.06	0.32	15.10	21.3	85	
K735205		5.30	0.0016	0.05	1.05	7.9	<0.2	<10	220	0.66	0.11	0.72	0.25	36.7	12.0	41	
K735219		6.16	0.0014	0.05	0.53	4.3	<0.2	<10	40	0.21	0.23	0.47	0.22	47.5	7.9	16	
K735220		6.88	0.0014	0.15	0.75	7.6	<0.2	<10	20	0.19	0.18	0.82	0.27	30.2	10.4	19	
K735221		6.86	0.0057	0.11	0.63	5.0	<0.2	<10	20	0.15	0.17	0.59	0.19	26.3	8.5	17	
K735222		5.04	0.0008	0.06	0.53	4.3	<0.2	<10	40	0.19	0.22	3.06	0.29	25.9	5.7	16	
K735223		4.04	0.0038	0.07	1.72	6.3	<0.2	<10	220	0.40	0.10	1.10	0.26	16.95	17.9	28	
K735224		7.06	0.0039	0.03	1.62	4.6	<0.2	10	120	0.30	0.06	1.06	0.09	13.70	13.6	23	
K735225		6.60	0.0043	0.04	1.16	6.6	<0.2	<10	140	0.34	0.05	2.66	0.13	17.85	12.6	30	
K735226		4.62	0.0013	0.06	1.34	8.8	<0.2	<10	180	0.30	0.11	0.88	0.18	19.45	12.3	31	
K735227		6.46	0.0009	0.04	1.19	4.9	<0.2	<10	110	0.23	0.06	0.72	0.15	19.10	10.3	27	
K735228		5.54	0.0009	0.03	1.15	3.7	<0.2	<10	90	0.25	0.10	0.78	0.13	17.65	9.7	31	
K735229		4.42	0.0079	0.13	0.93	5.2	<0.2	<10	50	0.27	0.17	0.45	1.10	38.6	9.9	23	
K735230		0.16	>0.1000	0.16	0.17	471	0.2	<10	1920	0.19	0.16	1.10	0.35	2.36	2.5	23	
K735231		6.12	0.0508	0.16	0.64	11.6	<0.2	<10	40	0.20	0.16	0.36	0.33	27.2	11.7	19	
K735232		4.94	0.0027	0.11	0.99	4.4	<0.2	<10	100	0.20	0.12	0.38	0.26	27.2	10.9	28	
K735233		5.28	0.0179	0.14	0.81	22.5	<0.2	<10	60	0.22	0.16	0.35	0.39	27.7	9.8	20	
K735234		5.12	0.0010	0.08	0.79	4.8	<0.2	<10	70	0.24	0.13	0.53	0.28	42.2	7.3	21	
K735235		4.52	0.0021	0.09	1.23	32.0	<0.2	<10	100	0.23	0.11	0.48	0.20	20.9	10.6	48	

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26-JUL-2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Sample Description	Method	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41	ME-MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
K735176		0.49	6.6	1.48	2.02	0.05	0.03	0.02	0.007	0.04	11.1	5.1	0.41	289	0.19	<0.01
K735177		0.64	16.1	2.29	2.58	0.07	0.04	0.01	0.011	0.05	17.0	7.6	0.49	342	0.49	<0.01
K735178		0.46	13.1	2.45	2.75	0.07	0.17	0.01	0.016	0.04	13.9	7.0	0.59	382	0.49	0.02
K735179		0.61	35.8	3.76	5.83	0.09	0.19	0.03	0.025	0.06	12.6	12.7	1.02	792	0.81	0.02
K735180		0.42	23.5	2.59	4.81	0.08	0.12	0.02	0.019	0.04	8.9	10.2	0.70	457	0.36	0.01
K735181		0.32	27.0	3.23	5.45	0.12	0.26	0.03	0.021	0.04	9.4	10.7	0.79	323	0.53	0.01
K735182		0.52	34.4	4.41	6.43	0.14	0.29	0.06	0.027	0.05	10.5	12.7	1.05	647	0.69	0.02
K735183		0.30	19.3	2.73	4.95	0.09	0.24	0.01	0.018	0.04	8.7	9.8	0.82	343	0.39	0.01
K735184		0.37	30.3	4.05	5.80	0.13	0.27	0.02	0.022	0.04	8.6	10.3	0.89	448	0.59	0.02
K735185		0.57	24.1	3.65	5.66	0.10	0.14	0.04	0.020	0.05	7.9	10.3	1.22	388	0.73	0.02
K735186		0.47	17.3	2.22	3.64	0.07	0.08	0.03	0.014	0.04	7.5	7.2	0.65	418	0.53	0.02
K735187		3.37	30.3	2.66	1.82	0.06	0.03	0.01	0.020	0.04	9.6	6.7	0.39	413	3.42	0.01
K735188		4.11	32.9	2.31	2.64	0.06	0.03	0.01	0.012	0.04	6.4	7.7	0.71	330	1.06	0.01
K735189		4.25	29.6	2.73	2.34	0.06	0.03	0.02	0.015	0.05	8.4	6.4	0.58	454	1.58	0.01
K735190		1.83	25.9	2.02	2.45	0.07	0.03	0.01	0.014	0.03	6.6	7.0	0.71	237	0.95	0.01
K735191		11.20	45.7	3.76	3.38	0.07	<0.02	0.05	0.021	0.07	8.8	8.9	0.59	776	0.58	0.01
K735192		2.01	49.5	3.42	5.93	0.09	0.05	0.04	0.023	0.08	10.7	18.8	1.14	466	0.69	0.02
K735193		0.50	24.8	3.61	7.02	0.08	0.10	0.03	0.023	0.05	8.4	23.2	1.26	393	0.38	0.01
K735194		0.77	37.3	2.99	5.36	0.08	0.07	0.03	0.021	0.07	8.5	18.2	1.00	323	0.64	0.02
K735195		0.30	20.7	2.05	4.07	0.07	0.22	0.02	0.016	0.06	4.7	7.7	0.49	320	4.06	0.05
K735196		2.09	47.0	4.32	7.23	0.12	0.10	0.01	0.026	0.06	9.2	17.4	1.60	525	0.67	0.01
K735197		3.35	62.2	4.40	7.83	0.12	0.09	0.05	0.033	0.06	8.9	19.9	1.71	515	0.92	0.01
K735205		1.49	81.4	3.84	3.68	0.06	0.04	0.02	0.019	0.07	18.3	11.6	0.61	526	1.31	0.01
K735219		1.41	12.4	1.97	2.17	0.06	0.03	0.01	0.009	0.07	24.3	8.5	0.38	277	0.62	<0.01
K735220		0.41	30.7	2.47	2.27	0.06	0.07	0.01	0.014	0.03	14.9	11.1	0.43	218	0.87	<0.01
K735221		0.43	20.7	2.05	1.93	0.06	0.06	0.02	0.009	0.04	13.2	6.6	0.41	206	0.58	<0.01
K735222		1.34	15.5	1.62	2.15	0.06	0.04	0.01	0.011	0.06	14.3	10.3	0.41	159	0.68	0.01
K735223		0.59	84.6	3.70	6.10	0.07	0.06	0.04	0.017	0.09	8.1	12.2	1.08	2080	0.82	0.03
K735224		0.40	42.8	3.33	5.62	0.07	0.14	0.01	0.017	0.06	6.0	12.0	1.09	533	0.35	0.02
K735225		0.37	40.3	3.60	4.22	0.10	0.27	0.02	0.021	0.04	8.5	8.8	1.07	571	0.60	0.01
K735226		0.72	27.9	2.75	4.53	0.05	0.06	0.05	0.018	0.05	9.5	11.2	0.73	872	0.75	0.01
K735227		0.65	20.3	2.35	4.30	0.07	0.08	0.01	0.016	0.04	9.5	9.5	0.70	368	0.52	0.01
K735228		0.44	19.8	2.51	4.40	0.07	0.09	0.02	0.016	0.03	8.8	8.3	0.65	342	0.34	0.01
K735229		2.06	16.5	2.40	3.08	0.05	0.02	<0.01	0.011	0.07	20.2	14.4	0.60	269	0.91	<0.01
K735230		0.38	62.0	3.88	0.80	<0.05	0.36	2.91	0.007	0.06	1.6	2.2	0.02	105	16.80	0.01
K735231		1.47	19.4	2.35	2.08	0.05	0.03	<0.01	0.009	0.06	13.9	6.3	0.48	277	0.69	<0.01
K735232		2.62	19.4	2.11	3.00	0.05	<0.02	<0.01	0.012	0.14	12.9	11.2	0.73	253	0.51	<0.01
K735233		3.58	17.7	2.15	2.48	<0.05	0.02	<0.01	0.011	0.07	14.0	9.9	0.55	381	0.72	<0.01
K735234		1.76	13.0	1.93	2.77	0.06	0.03	<0.01	0.011	0.10	22.1	11.3	0.48	353	0.49	0.01
K735235		1.20	31.0	2.72	4.16	0.07	0.05	<0.01	0.017	0.09	11.7	13.5	0.89	389	0.77	0.01

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
K735176		0.22	13.9	830	4.3	4.1	0.001	0.02	0.08	1.0	0.7	0.2	22.3	<0.01	0.01	2.9
K735177		0.35	23.2	800	8.7	6.4	<0.001	0.02	0.16	1.4	1.0	0.3	22.3	<0.01	0.04	3.4
K735178		0.28	25.9	670	6.3	5.3	<0.001	0.01	0.15	3.7	0.6	0.3	63.1	<0.01	0.02	3.4
K735179		1.50	27.8	870	4.9	4.9	0.001	0.03	0.56	7.4	0.9	0.5	41.6	<0.01	0.01	2.6
K735180		1.18	18.4	740	3.4	4.9	<0.001	0.02	0.31	5.4	0.6	0.4	30.7	0.01	0.01	1.7
K735181		1.21	19.8	740	4.2	4.0	<0.001	0.01	0.38	6.2	0.9	0.5	30.4	0.01	<0.01	1.7
K735182		1.20	24.8	860	4.4	7.2	<0.001	0.01	0.45	8.6	0.7	0.6	32.2	0.01	0.02	2.2
K735183		1.22	17.4	690	3.0	3.7	<0.001	0.02	0.26	5.7	0.3	0.5	25.9	<0.01	0.01	2.1
K735184		1.11	20.2	760	3.7	4.7	0.001	0.02	0.46	7.5	0.9	0.6	33.5	<0.01	0.02	1.6
K735185		0.91	45.5	860	4.2	5.5	<0.001	0.04	0.46	5.9	0.7	0.4	36.6	<0.01	0.01	1.6
K735186		0.78	23.9	650	3.2	4.1	0.001	0.04	0.38	4.2	0.5	0.3	40.0	<0.01	0.02	1.5
K735187		0.29	32.7	590	20.2	3.3	0.001	0.04	1.79	1.8	1.9	0.2	13.3	<0.01	0.07	3.1
K735188		0.51	34.7	610	4.4	3.7	<0.001	0.03	0.83	3.8	1.0	0.2	15.7	<0.01	0.03	1.5
K735189		0.49	30.0	770	8.8	4.1	0.001	0.03	1.22	3.6	1.5	0.2	24.7	<0.01	0.03	3.1
K735190		0.46	33.6	490	5.0	3.5	0.001	0.01	0.46	3.0	0.6	0.2	13.5	<0.01	0.01	1.8
K735191		0.56	33.1	910	7.8	9.4	<0.001	0.04	5.86	6.8	1.4	0.3	20.7	<0.01	0.02	0.8
K735192		0.80	26.4	780	4.6	8.7	<0.001	0.07	0.50	7.0	1.5	0.3	78.6	<0.01	0.03	1.0
K735193		0.88	24.8	510	3.8	7.0	0.001	0.02	0.21	7.2	0.7	0.4	50.6	<0.01	0.01	1.6
K735194		0.88	25.2	650	5.5	5.9	0.001	0.04	0.39	6.3	1.2	0.3	77.8	<0.01	<0.01	1.4
K735195		0.28	21.1	470	2.4	2.8	0.001	0.05	0.32	4.0	0.4	0.4	27.8	<0.01	0.03	1.0
K735196		0.90	38.7	660	4.2	4.7	0.001	0.03	1.34	8.8	1.0	0.3	22.4	0.01	0.02	3.6
K735197		0.78	50.5	740	5.6	5.7	0.001	0.04	1.45	11.2	1.6	0.4	33.6	<0.01	0.03	1.9
K735205		0.98	24.1	880	5.6	6.9	0.001	0.01	0.79	6.0	0.7	0.5	38.1	<0.01	0.03	14.1
K735219		0.86	17.4	1140	6.2	7.4	<0.001	0.01	0.27	1.7	0.6	0.5	17.7	<0.01	0.02	9.7
K735220		0.24	31.9	840	8.8	2.6	<0.001	0.01	0.23	1.4	1.5	0.2	30.5	<0.01	0.05	4.9
K735221		0.25	23.6	960	8.0	2.9	<0.001	0.01	0.19	1.3	1.0	0.2	24.2	<0.01	0.05	4.4
K735222		1.23	16.1	760	5.2	8.6	0.001	0.03	0.31	2.0	1.5	0.5	68.0	<0.01	0.04	4.4
K735223		1.05	23.1	890	3.0	8.6	0.001	0.02	0.26	7.1	0.8	0.4	58.4	<0.01	0.04	1.4
K735224		0.75	16.7	820	2.7	4.7	<0.001	0.01	0.25	7.3	0.6	0.4	45.3	<0.01	0.03	1.1
K735225		0.29	20.9	740	3.2	1.8	<0.001	0.01	0.32	7.6	0.3	0.4	52.4	<0.01	0.02	1.5
K735226		1.16	23.1	790	4.7	5.7	0.001	0.02	0.39	5.3	0.6	0.4	38.7	<0.01	0.02	2.1
K735227		0.84	20.2	810	3.3	4.7	<0.001	0.01	0.34	4.8	0.5	0.3	28.5	<0.01	0.02	5.1
K735228		1.06	19.6	730	3.1	4.9	<0.001	0.01	0.27	4.6	0.5	0.4	38.9	<0.01	0.01	1.5
K735229		0.66	31.0	1210	10.0	10.0	0.001	0.02	0.30	2.0	0.9	0.4	22.8	<0.01	0.02	5.0
K735230		0.13	17.0	60	17.4	2.8	0.001	0.15	26.2	0.7	1.7	2.7	31.6	<0.01	0.08	0.8
K735231		0.40	25.9	1150	12.3	5.3	0.001	0.01	0.79	1.5	0.9	0.2	15.0	<0.01	0.02	5.2
K735232		0.54	25.1	1130	9.6	12.9	<0.001	0.01	0.42	2.4	0.6	0.3	16.6	<0.01	0.01	3.4
K735233		0.48	23.8	880	13.3	7.3	<0.001	0.01	0.85	1.6	1.1	0.2	18.0	<0.01	0.02	3.5
K735234		0.94	19.4	1410	7.3	12.0	0.001	0.01	0.66	2.3	1.0	0.4	20.7	<0.01	0.01	9.0
K735235		0.68	31.6	760	5.5	7.5	<0.001	0.01	1.18	4.7	0.7	0.3	30.4	<0.01	0.02	3.5

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	Au- OG44
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr	Au
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5	0.01
K735176		0.015	0.04	0.30	13	0.08	4.80	40	1.2	
K735177		0.019	0.05	0.51	22	0.97	6.30	61	1.4	
K735178		0.027	0.05	0.64	51	0.08	6.86	59	6.8	
K735179		0.158	0.05	0.60	102	0.16	10.30	62	7.5	
K735180		0.145	0.04	0.39	82	0.13	7.59	50	4.4	
K735181		0.193	0.04	0.53	109	0.11	9.04	56	9.9	
K735182		0.258	0.04	0.45	152	0.13	10.75	75	12.5	
K735183		0.191	0.02	0.38	85	0.23	8.33	40	9.1	
K735184		0.258	0.04	0.49	140	0.36	9.93	60	11.7	
K735185		0.129	0.05	0.42	92	0.27	6.95	66	5.7	
K735186		0.090	0.04	0.40	62	0.16	6.12	40	3.1	
K735187		0.021	0.05	1.00	37	0.22	5.00	198	1.4	
K735188		0.068	0.06	0.44	58	0.28	6.00	51	0.9	
K735189		0.050	0.06	0.54	60	1.11	6.91	104	1.5	
K735190		0.061	0.05	0.68	45	2.30	4.93	53	0.8	
K735191		0.049	0.33	0.41	103	0.69	9.26	72	<0.5	
K735192		0.102	0.07	0.75	84	0.17	9.88	97	1.4	
K735193		0.130	0.06	0.41	88	0.13	7.36	78	3.3	
K735194		0.099	0.09	0.43	69	0.28	8.53	63	2.3	
K735195		0.112	0.05	0.29	47	11.55	7.06	35	7.2	
K735196		0.165	0.05	1.70	110	0.19	12.40	78	3.5	
K735197		0.154	0.07	0.59	115	0.20	15.10	104	3.3	
K735205		0.066	0.05	2.06	102	0.66	8.12	62	1.1	
K735219		0.031	0.06	10.15	31	0.26	7.81	37	1.6	
K735220		0.013	0.03	0.55	24	0.07	5.08	77	4.2	
K735221		0.017	0.03	0.42	22	0.07	5.12	55	3.7	
K735222		0.033	0.07	0.69	25	0.74	6.63	40	1.5	
K735223		0.131	0.06	0.29	102	0.13	7.61	65	2.1	
K735224		0.150	0.03	0.30	105	0.13	6.91	58	4.3	
K735225		0.135	0.02	0.43	124	0.07	8.09	48	9.2	
K735226		0.093	0.06	0.57	65	0.20	6.87	51	2.2	
K735227		0.100	0.04	0.64	62	0.10	6.13	53	3.1	
K735228		0.112	0.03	0.36	76	0.10	5.23	48	3.3	
K735229		0.035	0.07	1.20	27	0.07	7.32	114	0.6	
K735230		0.011	10.35	1.06	11	3.80	2.12	18	11.1	0.16
K735231		0.027	0.05	0.65	22	1.42	6.12	66	1.8	
K735232		0.044	0.12	1.07	25	0.07	7.04	65	0.5	
K735233		0.027	0.07	0.94	23	0.07	6.23	67	0.7	
K735234		0.048	0.11	1.90	32	0.15	7.95	47	1.1	
K735235		0.074	0.07	0.62	65	0.15	6.56	50	1.4	

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Sample Description	Method	WEI- 21	Au- ST44	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	.02	0.0001	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
K735236		6.14	0.0022	0.15	1.52	48.0	<0.2	<10	200	0.25	0.17	0.57	0.21	19.85	14.0	55
K735237		5.52	0.0027	0.13	0.97	24.9	<0.2	<10	120	0.21	0.15	2.11	0.23	22.9	8.5	31
K735238		9.42	0.0013	0.09	1.59	10.6	<0.2	<10	60	0.22	0.11	0.57	0.26	22.0	13.4	63
K735239		<0.02	0.0021	0.05	1.56	10.5	<0.2	<10	70	0.25	0.08	0.54	0.27	18.60	13.2	59
K735240		4.64	0.0020	0.06	0.80	9.0	<0.2	<10	70	0.20	0.10	0.63	0.15	18.45	6.9	29
K735274		4.92	0.0032	0.06	1.04	2.3	<0.2	<10	40	0.90	0.56	0.43	0.09	63.0	3.8	14
K735275		4.40	0.0104	0.02	0.67	1.7	<0.2	<10	50	0.32	0.29	0.41	0.08	45.8	4.3	18
K735276		5.34	0.0018	0.03	0.67	4.4	<0.2	<10	140	0.19	0.10	0.73	0.20	18.45	10.5	55
K735277		6.36	0.0020	0.02	1.46	5.3	<0.2	<10	70	0.32	0.05	1.02	0.10	16.60	14.8	31
K735278		4.80	0.0021	0.02	1.33	5.9	<0.2	<10	150	0.31	0.06	1.12	0.20	15.30	11.3	28
K735279		4.72	0.0062	0.03	1.39	5.3	<0.2	<10	100	0.29	0.07	0.99	0.10	15.95	12.3	27
K735280		0.22	0.0030	0.19	0.96	3.3	<0.2	<10	70	0.18	0.06	0.58	0.16	9.64	7.1	29
K735281		6.26	0.0030	0.04	1.30	8.7	<0.2	<10	120	0.43	0.05	2.25	0.16	17.70	13.2	28
K735282		5.02	0.0030	0.03	1.38	5.8	<0.2	10	100	0.40	0.09	1.40	0.14	18.45	12.6	31
K735283		4.92	0.0015	0.04	1.37	7.2	<0.2	<10	150	0.32	0.07	0.99	0.15	20.1	11.9	33
K735284		5.00	0.0018	0.03	1.27	5.7	<0.2	<10	150	0.36	0.06	1.29	0.13	15.55	11.2	24
K735285		6.38	0.0012	0.03	1.00	4.8	<0.2	<10	100	0.20	0.06	0.74	0.13	14.55	9.0	31
K735286		5.22	0.0021	0.03	0.92	4.5	<0.2	<10	100	0.23	0.04	0.81	0.10	14.65	8.3	32
K735287		5.66	0.0033	0.06	1.17	5.5	<0.2	<10	150	0.31	0.08	2.04	0.27	15.30	11.4	42
K735288		6.74	0.0068	0.06	1.18	13.1	<0.2	<10	150	0.33	0.07	1.30	0.20	18.00	13.8	42
K735289		5.54	0.0139	0.04	0.93	5.5	<0.2	<10	110	0.27	0.05	0.70	0.11	18.20	9.2	33
K735290		5.40	0.0075	0.03	0.69	11.0	<0.2	<10	120	0.32	0.06	0.60	0.07	18.05	8.4	43
K735291		6.40	0.0023	0.03	0.81	8.5	<0.2	<10	240	0.39	0.07	1.04	0.10	19.15	10.8	22
K735292		5.14	0.0035	0.04	0.86	19.1	<0.2	<10	160	0.34	0.08	0.69	0.11	20.9	10.5	28
K735293		4.36	0.0305	0.04	0.64	164.0	<0.2	<10	150	0.30	0.10	0.43	0.09	20.7	11.2	23
K735294		10.96	0.0047	0.03	0.82	11.7	<0.2	<10	130	0.20	0.07	0.62	0.09	15.70	10.8	29
K735295		<0.02	0.0050	0.03	0.86	13.8	<0.2	<10	150	0.24	0.06	0.65	0.11	16.40	12.5	33
K735296		6.56	0.0161	0.05	0.68	2.8	<0.2	<10	80	0.14	0.15	0.40	0.11	38.5	6.5	41
K735297		4.90	0.0357	0.06	0.86	17.3	<0.2	<10	90	0.25	0.18	0.50	0.24	39.7	11.5	57
K735298		7.02	0.0382	0.08	1.12	27.2	<0.2	<10	150	0.22	0.14	0.64	0.34	21.9	13.3	40
K735299		4.84	0.0012	0.05	0.72	4.5	<0.2	<10	100	0.18	0.09	0.47	0.14	30.5	6.4	28
K735300		7.04	0.0012	0.04	0.62	2.8	<0.2	<10	100	0.15	0.10	0.40	0.09	30.0	5.1	20
K735311		5.96	0.0013	0.05	0.90	3.0	<0.2	<10	90	0.51	1.36	0.53	0.21	39.4	10.2	25
K735312		4.98	0.0005	0.06	0.73	4.5	<0.2	<10	80	0.25	0.21	0.44	0.28	25.4	8.8	24
K735313		5.66	0.0015	0.06	0.86	5.4	<0.2	<10	100	0.33	0.25	0.52	0.19	26.4	10.4	28
K735314		4.12	0.0011	0.05	1.45	8.9	<0.2	<10	150	0.41	0.08	1.03	0.26	22.6	14.5	34
K735315		0.16	0.0395	0.68	0.50	234	<0.2	<10	90	1.10	9.22	15.75	2.15	22.6	4.4	23
K735316		7.40	0.0108	0.06	1.57	10.6	<0.2	<10	180	0.47	0.11	1.04	0.36	26.2	19.2	40
K735317		5.76	0.0040	0.03	1.27	5.9	<0.2	<10	100	0.38	0.05	1.83	0.16	18.60	12.1	33
K735318		3.74	0.0018	0.03	1.17	3.9	<0.2	<10	100	0.30	0.05	1.05	0.13	18.45	10.1	26

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
K735236		2.09	52.5	3.05	5.03	0.08	0.03	<0.01	0.015	0.20	10.9	17.5	1.00	477	0.69	0.03
K735237		1.03	32.4	2.15	3.43	0.08	0.06	<0.01	0.011	0.09	13.2	10.7	0.57	332	0.64	0.04
K735238		0.84	32.9	3.43	5.47	0.11	0.09	0.01	0.018	0.06	11.2	14.8	1.11	436	1.85	0.02
K735239		0.82	28.1	3.34	5.33	0.09	0.10	<0.01	0.017	0.06	9.5	14.4	1.09	426	0.79	0.02
K735240		0.98	19.7	1.69	2.92	0.05	0.04	<0.01	0.009	0.05	9.6	8.3	0.53	282	0.37	0.02
K735274		7.78	7.3	1.54	4.35	0.10	<0.02	0.03	0.012	0.16	30.8	42.9	0.33	199	0.18	0.01
K735275		2.84	6.1	1.21	2.65	0.08	0.03	<0.01	0.009	0.06	23.0	17.0	0.38	157	0.23	0.02
K735276		6.62	21.3	2.76	2.31	<0.05	0.03	0.02	0.010	0.04	9.2	6.2	0.65	264	0.44	0.01
K735277		0.26	16.6	3.85	6.61	0.11	0.41	<0.01	0.022	0.02	7.0	10.6	1.10	437	0.38	0.01
K735278		0.30	36.1	3.36	5.01	0.11	0.27	0.10	0.022	0.04	6.0	9.7	0.92	592	0.54	0.02
K735279		0.32	23.0	3.11	5.18	0.10	0.23	0.01	0.021	0.03	6.7	10.6	0.94	404	0.44	0.01
K735280		0.30	20.5	1.95	3.54	0.08	0.23	0.01	0.015	0.06	4.1	7.2	0.47	291	3.86	0.04
K735281		0.40	44.6	3.30	5.33	0.10	0.35	0.01	0.024	0.03	7.5	10.8	0.98	503	0.62	0.01
K735282		0.36	36.6	3.49	5.27	0.13	0.25	0.02	0.021	0.03	8.6	10.4	1.03	396	0.61	0.01
K735283		0.42	29.9	3.20	4.77	0.07	0.14	0.02	0.016	0.04	9.5	10.2	0.81	616	0.49	0.02
K735284		0.35	33.1	3.21	4.68	0.10	0.20	0.02	0.021	0.04	6.9	9.5	0.95	444	0.44	0.02
K735285		0.56	16.4	2.40	3.60	0.07	0.08	0.01	0.015	0.03	6.7	7.6	0.67	331	0.51	0.01
K735286		0.57	13.9	2.20	3.21	0.05	0.10	0.02	0.011	0.04	6.7	6.5	0.60	462	0.99	0.01
K735287		0.70	30.0	2.46	4.12	0.10	0.09	0.06	0.018	0.07	8.1	7.8	0.78	690	0.61	0.03
K735288		0.63	33.4	2.71	4.35	0.11	0.09	0.13	0.018	0.07	8.6	7.6	0.83	863	0.86	0.03
K735289		0.48	13.8	2.34	3.66	0.11	0.13	0.07	0.014	0.04	10.0	7.1	0.57	281	0.37	0.02
K735290		4.92	14.9	3.22	3.22	0.11	0.03	0.04	0.013	0.06	10.1	7.5	0.45	295	0.26	0.01
K735291		12.55	20.7	2.62	3.10	0.10	0.02	0.08	0.017	0.13	11.0	7.8	0.59	523	0.50	0.01
K735292		12.85	26.6	2.69	3.12	0.11	0.02	0.06	0.017	0.10	11.6	8.7	0.57	477	0.37	0.01
K735293		7.85	24.7	2.47	1.99	0.10	0.02	0.14	0.015	0.08	10.1	5.3	0.46	443	0.40	0.01
K735294		6.25	35.4	2.20	2.70	0.10	0.02	0.02	0.011	0.06	7.7	7.3	0.68	370	0.29	0.02
K735295		6.99	33.8	2.29	2.95	0.09	0.02	0.11	0.013	0.06	8.0	7.7	0.72	391	0.31	0.02
K735296		1.07	15.5	2.83	2.96	0.11	0.03	0.01	0.009	0.04	23.3	5.7	0.40	212	0.46	0.01
K735297		1.86	26.4	4.72	4.26	0.13	0.03	0.01	0.011	0.05	25.0	9.3	0.60	364	4.49	0.01
K735298		3.84	27.1	4.33	4.11	0.10	0.03	0.02	0.016	0.03	14.8	10.9	0.71	664	1.57	0.02
K735299		1.21	8.5	1.91	2.95	0.11	0.02	0.02	0.010	0.02	18.6	7.6	0.45	458	0.60	0.01
K735300		0.85	8.6	1.29	2.56	0.09	0.02	0.01	0.024	0.03	18.0	6.2	0.37	185	0.56	0.01
K735311		2.54	15.2	2.18	3.28	0.11	0.08	0.02	0.013	0.08	18.5	16.5	0.50	552	0.94	0.02
K735312		1.36	15.7	2.08	2.71	0.11	0.09	0.01	0.013	0.05	12.9	8.0	0.42	446	0.78	0.02
K735313		0.98	21.6	2.19	2.76	0.10	0.12	0.01	0.015	0.06	12.9	7.7	0.49	435	0.75	0.02
K735314		0.63	36.0	3.10	5.28	0.10	0.15	0.04	0.020	0.05	11.2	10.8	0.87	927	0.77	0.02
K735315		2.58	76.5	2.27	3.13	0.12	0.21	2.01	0.617	0.15	14.7	5.9	3.13	1560	74.0	0.02
K735316		0.71	43.0	3.48	5.78	0.12	0.22	0.06	0.029	0.07	12.2	10.8	0.94	904	0.99	0.02
K735317		0.35	34.5	3.05	4.90	0.14	0.30	0.03	0.020	0.04	9.7	8.5	0.84	510	0.75	0.02
K735318		0.29	24.1	2.50	4.81	0.11	0.19	0.03	0.016	0.04	9.4	8.2	0.67	402	0.40	0.02

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
K735236		0.58	38.1	960	5.0	12.9	<0.001	0.01	1.85	5.6	0.5	0.3	44.7	<0.01	0.03	3.4
K735237		0.59	23.7	820	4.7	7.1	<0.001	0.01	1.40	3.4	0.8	0.3	132.0	<0.01	0.02	4.5
K735238		0.50	32.2	730	3.9	4.5	0.001	<0.01	0.75	6.4	0.9	0.3	36.0	<0.01	0.05	5.3
K735239		0.54	31.5	660	3.6	4.4	<0.001	<0.01	0.69	6.4	0.6	0.3	36.1	<0.01	0.03	3.2
K735240		0.63	22.0	590	4.6	4.6	<0.001	<0.01	0.55	3.2	0.4	0.2	32.3	<0.01	0.02	3.2
K735274		1.39	7.6	1280	5.0	29.4	<0.001	0.01	0.47	2.1	1.1	1.1	41.0	<0.01	0.01	9.4
K735275		0.92	13.1	960	3.0	13.0	<0.001	<0.01	0.14	2.0	0.7	0.5	20.4	<0.01	<0.01	10.7
K735276		0.57	38.8	710	3.8	5.7	<0.001	0.02	0.68	3.5	0.8	0.3	22.4	<0.01	0.02	3.0
K735277		1.02	20.8	840	2.7	3.4	<0.001	<0.01	0.17	7.4	0.5	0.6	22.7	<0.01	0.02	1.3
K735278		0.95	21.5	710	4.4	6.2	<0.001	0.01	0.33	6.9	0.6	0.5	28.0	<0.01	0.01	1.0
K735279		1.07	20.5	780	3.5	3.6	<0.001	0.01	0.22	6.6	0.5	0.5	25.0	<0.01	0.01	1.2
K735280		0.24	20.6	490	2.2	2.7	0.001	0.04	0.26	4.0	0.4	0.4	28.1	<0.01	0.01	0.9
K735281		0.43	24.3	700	3.3	2.2	<0.001	<0.01	0.43	8.3	0.5	0.5	41.5	<0.01	0.01	1.2
K735282		0.95	24.0	720	3.6	3.4	0.001	0.01	0.30	7.7	0.7	0.5	31.4	<0.01	0.01	1.4
K735283		1.20	20.6	850	4.0	4.6	0.001	0.02	0.32	6.4	0.5	0.4	36.2	<0.01	0.02	1.7
K735284		0.87	18.9	710	3.6	3.2	0.001	0.02	0.29	7.1	0.8	0.4	33.0	<0.01	0.04	1.1
K735285		0.59	22.7	640	3.6	3.9	0.001	0.01	0.36	4.1	0.5	0.3	31.3	<0.01	0.01	1.5
K735286		0.57	20.0	780	2.8	3.2	0.001	0.01	0.34	3.9	0.5	0.3	30.9	<0.01	0.01	1.5
K735287		1.06	31.3	730	5.5	5.6	0.002	0.05	0.47	5.2	1.1	0.3	65.1	<0.01	0.03	1.5
K735288		0.89	28.2	780	4.7	6.3	0.002	0.04	0.55	5.9	0.3	0.3	51.0	<0.01	0.02	1.6
K735289		1.16	21.6	800	3.4	4.0	0.001	0.03	0.30	3.9	0.3	0.3	31.3	<0.01	0.01	2.1
K735290		0.71	13.5	1280	3.3	5.8	<0.001	0.02	0.96	3.5	0.4	0.3	32.8	<0.01	0.02	2.6
K735291		0.69	13.9	1010	4.2	11.7	0.002	0.04	1.53	4.7	0.8	0.3	42.5	<0.01	0.02	2.5
K735292		0.60	16.2	1360	4.1	8.3	<0.001	0.04	1.73	4.7	0.5	0.3	30.3	<0.01	0.02	2.2
K735293		0.42	19.7	930	5.3	7.0	<0.001	0.03	4.06	3.6	<0.2	0.2	19.7	<0.01	0.03	2.9
K735294		0.49	21.0	1270	2.5	4.8	<0.001	0.05	0.80	3.8	0.3	0.2	24.9	<0.01	0.02	1.8
K735295		0.56	23.3	1320	2.7	5.3	<0.001	0.05	0.85	4.3	<0.2	0.2	27.1	<0.01	0.01	1.9
K735296		0.57	12.9	820	3.9	4.8	<0.001	<0.01	0.33	2.2	<0.2	0.2	13.7	<0.01	0.03	7.6
K735297		0.94	22.5	970	6.0	5.6	0.001	0.01	0.60	3.9	0.6	0.3	15.1	<0.01	0.05	16.3
K735298		0.70	23.1	680	6.0	5.3	0.002	0.04	0.42	4.5	0.7	0.3	24.9	<0.01	0.04	2.6
K735299		0.94	13.9	700	3.6	5.3	0.001	0.02	0.17	2.5	0.4	0.2	16.3	<0.01	0.02	8.1
K735300		0.96	12.0	780	3.2	4.7	<0.001	0.02	0.16	2.3	<0.2	0.2	15.0	<0.01	0.01	7.2
K735311		0.83	23.2	950	6.7	11.7	<0.001	0.02	0.09	3.2	0.5	0.5	36.0	<0.01	0.02	5.1
K735312		0.67	24.0	780	6.9	7.5	<0.001	0.02	0.11	2.5	0.3	0.3	31.4	<0.01	0.03	3.4
K735313		0.68	28.3	860	7.0	6.5	0.001	0.01	0.19	3.6	0.8	0.3	33.3	<0.01	0.04	3.7
K735314		1.71	24.9	930	4.9	5.2	0.001	0.02	0.43	6.4	0.6	0.4	39.7	<0.01	0.02	2.0
K735315		0.06	72.3	1070	21.4	14.4	0.052	0.92	6.82	3.6	3.2	3.0	200	<0.01	0.39	3.5
K735316		1.54	31.6	870	6.7	5.2	0.001	0.02	0.56	7.6	0.5	0.5	42.7	<0.01	0.02	2.7
K735317		0.70	21.1	810	3.8	2.6	0.001	0.02	0.36	6.1	0.5	0.4	50.8	<0.01	0.02	1.7
K735318		1.47	16.8	720	3.2	3.8	0.001	0.03	0.18	5.2	0.4	0.4	42.9	<0.01	0.02	27.6

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	Au- OG44
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr	Au
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5	0.01
K735236		0.102	0.13	0.80	79	0.19	7.22	56	1.0	
K735237		0.068	0.07	0.62	49	1.51	7.05	40	2.3	
K735238		0.112	0.06	0.65	81	0.15	8.38	62	3.4	
K735239		0.111	0.05	0.49	78	0.15	8.11	60	3.3	
K735240		0.049	0.05	0.46	39	0.22	5.06	36	1.1	
K735274		0.058	0.22	27.0	28	0.49	14.80	37	<0.5	
K735275		0.048	0.09	3.00	26	2.19	9.78	28	0.9	
K735276		0.043	0.06	0.46	56	0.39	5.58	38	0.8	
K735277		0.258	0.02	0.30	121	0.36	10.40	66	13.7	
K735278		0.195	0.02	0.35	121	0.12	7.53	64	7.5	
K735279		0.193	0.02	0.37	104	0.08	7.64	57	7.8	
K735280		0.096	0.04	0.24	43	10.05	6.10	34	6.3	
K735281		0.167	0.03	0.33	109	0.08	11.15	51	12.9	
K735282		0.201	0.03	0.39	122	0.08	10.05	59	9.6	
K735283		0.145	0.04	0.48	97	0.12	7.47	56	5.4	
K735284		0.160	0.03	0.35	97	0.07	9.38	49	7.6	
K735285		0.084	0.03	0.31	63	0.13	4.95	45	3.1	
K735286		0.082	0.04	0.29	59	0.12	5.23	41	3.1	
K735287		0.090	0.06	0.38	63	0.28	7.60	59	3.1	
K735288		0.094	0.07	0.45	78	0.30	7.41	54	3.4	
K735289		0.095	0.04	0.38	61	0.12	6.28	44	4.6	
K735290		0.048	0.05	0.76	97	0.11	7.65	30	0.9	
K735291		0.041	0.11	0.48	48	0.13	8.53	45	0.6	
K735292		0.037	0.09	0.99	63	0.15	9.82	44	0.5	
K735293		0.025	0.07	0.58	37	0.17	5.56	41	0.5	
K735294		0.042	0.04	0.49	47	0.12	4.95	33	0.5	
K735295		0.048	0.06	0.56	52	0.63	5.56	37	0.6	
K735296		0.066	0.05	1.05	73	2.17	4.75	22	0.8	
K735297		0.066	0.07	2.44	109	11.55	8.35	35	0.8	
K735298		0.064	0.07	2.06	72	0.42	8.94	54	0.7	
K735299		0.066	0.05	1.88	46	1.96	5.51	33	0.8	
K735300		0.056	0.05	3.93	31	1.52	4.96	22	0.8	
K735311		0.051	0.08	4.20	44	2.50	10.05	46	4.0	
K735312		0.049	0.06	1.06	45	0.17	6.20	57	4.1	
K735313		0.037	0.06	0.90	36	0.32	7.58	55	5.1	
K735314		0.131	0.05	0.59	88	0.30	9.50	62	5.5	
K735315		0.005	0.87	14.65	147	14.75	20.2	413	8.3	
K735316		0.149	0.06	0.67	102	0.21	10.65	65	7.0	
K735317		0.155	0.03	0.48	103	0.08	9.83	48	10.8	
K735318		0.140	0.03	2.76	83	0.09	7.70	43	6.6	

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Sample Description	Method	WEI- 21	Au- ST44	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	.02	0.0001	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
K735319		7.74	0.0058	0.03	1.31	6.6	<0.2	<10	160	0.41	0.05	2.07	0.16	18.70	11.2	30
K735320		4.38	0.0093	0.06	1.03	6.9	<0.2	<10	130	0.26	0.07	0.91	0.20	15.55	9.7	31
K735321		3.90	0.0093	0.04	1.06	5.0	<0.2	<10	110	0.23	0.06	0.74	0.16	13.15	9.4	38
K735322		5.42	0.0014	0.07	1.49	5.8	<0.2	<10	230	0.37	0.08	0.98	0.51	22.5	11.1	39
K735323		5.40	0.0205	0.07	1.19	8.1	<0.2	<10	110	0.35	0.07	1.00	0.23	16.80	11.8	47
K735324		5.60	0.0032	0.07	1.54	13.3	<0.2	<10	240	0.54	0.07	0.93	0.28	15.05	20.8	48
K735325		5.86	0.0028	0.03	0.99	3.0	<0.2	<10	100	0.15	0.05	0.63	0.08	8.85	18.3	40
K735326		4.62	>0.1000	0.06	1.22	36.9	<0.2	<10	240	0.29	0.08	0.57	0.20	18.85	15.7	49
K735327		5.28	0.0247	0.05	1.54	37.7	<0.2	<10	250	0.21	0.04	0.54	0.12	8.97	15.6	61
K735328		5.78	0.0223	0.07	1.80	66.6	<0.2	<10	360	0.32	0.04	0.70	0.28	12.35	21.0	73
K735329		8.00	0.0046	0.06	1.37	7.3	<0.2	<10	270	0.28	0.09	0.75	0.26	14.35	17.0	40
K735330		<0.02	0.0024	0.06	1.36	7.5	<0.2	<10	270	0.31	0.08	0.74	0.25	13.85	17.5	39
K735331		4.96	0.0017	0.19	2.08	18.6	<0.2	<10	130	0.54	0.23	0.62	0.34	26.3	22.2	53
K735332		6.10	0.0192	0.04	1.43	25.3	<0.2	<10	70	0.41	0.15	0.72	0.25	25.8	24.2	55
K735333		5.16	0.0078	0.09	1.30	15.3	<0.2	<10	80	0.30	0.15	0.44	0.28	25.6	11.9	39
K735334		5.00	0.0008	0.07	1.03	5.7	<0.2	<10	140	0.23	0.16	0.38	0.11	26.0	9.1	43
K735335		5.64	0.0032	0.09	1.40	14.2	<0.2	<10	110	0.31	0.14	0.60	0.17	23.3	15.8	48
K735336		6.70	>0.1000	0.07	1.10	26.2	<0.2	<10	90	0.21	0.10	0.51	0.28	24.7	12.9	83
K735359		6.36	0.0620	0.08	1.14	23.3	<0.2	<10	140	0.25	0.10	0.84	0.17	24.9	9.2	47
K735218		Not Recvd														

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
K735319		0.35	35.2	3.15	5.03	0.13	0.34	0.03	0.020	0.04	9.0	8.5	0.87	557	0.54	0.02
K735320		0.45	24.2	2.28	3.87	0.10	0.06	0.04	0.014	0.05	7.6	6.7	0.59	486	0.70	0.02
K735321		0.34	20.9	2.34	4.03	0.09	0.06	0.03	0.013	0.04	6.7	6.4	0.72	495	0.55	0.02
K735322		0.71	27.9	2.52	4.48	0.10	0.05	0.05	0.016	0.05	11.8	11.9	0.60	789	0.83	0.02
K735323		0.75	34.1	2.85	4.70	0.10	0.07	0.07	0.020	0.05	8.5	8.6	0.76	387	0.68	0.02
K735324		16.90	60.8	3.37	4.47	0.09	0.02	0.04	0.022	0.08	9.3	15.0	1.03	591	0.53	0.02
K735325		2.75	71.1	2.66	2.98	0.09	<0.02	0.01	0.008	0.06	4.0	8.1	0.90	285	0.23	0.03
K735326		2.33	35.4	3.21	4.20	0.09	0.03	0.03	0.018	0.07	9.0	10.2	0.91	769	0.60	0.01
K735327		2.27	60.8	2.40	3.98	0.08	<0.02	0.01	0.012	0.04	4.2	10.9	1.14	527	0.34	0.01
K735328		4.30	76.6	3.39	4.68	0.10	<0.02	0.02	0.012	0.06	5.5	13.0	1.36	2070	0.81	0.01
K735329		5.86	73.4	2.83	4.04	0.09	<0.02	0.01	0.014	0.09	6.9	11.5	1.14	616	0.45	0.02
K735330		5.89	76.3	2.86	4.13	0.09	<0.02	0.01	0.015	0.09	6.7	12.0	1.13	616	0.73	0.02
K735331		6.73	52.0	3.51	6.53	0.11	0.03	0.03	0.023	0.08	13.3	13.8	0.85	589	0.67	0.03
K735332		2.76	37.7	4.64	6.22	0.13	0.08	0.03	0.027	0.05	13.8	9.8	0.83	513	0.87	0.03
K735333		3.17	29.4	2.63	4.86	0.15	0.02	0.02	0.022	0.04	14.9	11.6	0.63	408	1.62	0.02
K735334		3.89	24.0	3.21	3.81	0.13	<0.02	0.02	0.016	0.07	14.6	11.5	0.45	305	1.51	0.02
K735335		3.04	31.7	3.66	5.61	0.16	0.04	0.03	0.023	0.07	12.5	13.2	0.77	364	0.80	0.03
K735336		2.66	27.8	4.49	4.31	0.17	0.03	0.02	0.021	0.04	14.3	12.1	0.70	601	1.35	0.01
K735359		1.36	30.5	2.76	4.20	0.20	0.06	0.01	0.018	0.15	14.5	10.5	0.84	332	0.56	0.02
K735218																

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
K735319		0.76	21.1	730	3.7	3.0	<0.001	0.01	0.30	7.0	0.3	0.4	47.7	<0.01	0.01	1.6
K735320		0.91	22.4	810	4.9	5.2	0.001	0.02	0.34	4.1	0.4	0.3	34.3	<0.01	0.03	1.1
K735321		0.70	29.4	760	4.8	4.3	0.001	0.02	0.20	3.5	0.2	0.2	31.6	<0.01	0.02	1.0
K735322		1.22	24.0	830	4.0	6.6	0.003	0.04	0.28	4.2	0.8	0.4	45.2	<0.01	0.03	1.0
K735323		1.01	31.0	770	5.4	5.5	0.001	0.03	0.39	5.8	0.8	0.3	38.8	<0.01	0.03	1.3
K735324		0.64	37.6	1690	4.4	8.6	<0.001	0.04	0.99	6.5	0.8	0.3	42.0	<0.01	0.04	0.9
K735325		0.33	21.6	1460	1.7	3.8	<0.001	0.01	0.32	4.2	0.3	0.2	24.5	<0.01	0.02	0.8
K735326		0.95	29.7	990	3.5	7.2	0.002	0.03	1.06	4.9	0.6	0.3	28.6	<0.01	0.04	2.2
K735327		0.52	25.5	1040	1.8	5.3	0.001	0.02	0.97	5.2	0.2	0.2	24.6	<0.01	0.02	0.6
K735328		0.58	33.7	1110	1.8	6.3	0.001	0.02	0.94	6.4	0.5	0.2	31.3	<0.01	0.02	0.7
K735329		0.61	24.8	1390	3.9	8.4	0.001	0.03	0.41	4.4	0.5	0.2	32.9	<0.01	0.03	0.9
K735330		0.61	25.0	1400	3.9	8.6	0.001	0.03	0.43	4.5	0.6	0.2	33.6	<0.01	0.03	0.9
K735331		0.89	36.7	920	8.5	8.7	<0.001	0.03	1.04	7.3	0.8	0.4	22.1	<0.01	0.04	1.5
K735332		0.73	33.1	840	5.5	4.3	<0.001	0.02	1.55	7.1	0.5	0.5	17.2	<0.01	0.03	3.3
K735333		0.65	27.2	660	5.5	5.4	0.001	0.03	0.76	5.1	0.5	0.3	17.6	<0.01	0.02	1.6
K735334		0.62	20.2	650	4.9	8.1	0.001	0.02	0.45	4.9	0.5	0.3	15.0	<0.01	0.02	3.5
K735335		0.76	28.6	740	5.2	6.3	0.001	0.02	0.89	6.7	0.7	0.4	17.9	<0.01	0.02	3.4
K735336		0.58	33.3	750	3.8	4.2	0.001	0.02	1.31	6.1	1.1	0.3	16.9	<0.01	0.01	3.6
K735359		0.65	27.8	730	4.8	8.9	0.001	0.01	0.98	5.0	0.7	0.2	40.4	<0.01	0.02	6.9
K735218																

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	Au- OG44
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr	Au
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5	0.01
K735319		0.172	0.03	0.40	108	0.06	9.90	48	11.7	
K735320		0.078	0.04	0.45	63	0.15	7.29	48	2.1	
K735321		0.074	0.03	0.29	66	0.13	5.23	51	2.3	
K735322		0.097	0.07	0.68	73	0.18	9.24	90	1.4	
K735323		0.094	0.05	0.38	84	0.21	7.79	55	2.4	
K735324		0.046	0.08	1.16	69	0.22	11.95	83	<0.5	
K735325		0.058	0.03	0.17	75	0.12	3.52	27	<0.5	
K735326		0.060	0.04	0.72	63	0.24	6.15	53	0.8	0.10
K735327		0.044	0.03	0.41	55	0.12	4.40	49	<0.5	
K735328		0.050	0.04	0.43	72	0.13	6.29	64	<0.5	
K735329		0.066	0.07	0.66	68	0.21	6.73	59	0.5	
K735330		0.064	0.07	0.62	68	4.14	7.27	58	0.5	
K735331		0.101	0.14	1.36	88	0.50	14.45	61	0.8	
K735332		0.163	0.08	1.11	125	0.27	13.35	58	2.3	
K735333		0.071	0.09	1.05	70	3.64	12.00	52	0.6	
K735334		0.060	0.07	2.49	87	1.28	9.68	46	<0.5	
K735335		0.127	0.08	1.79	97	0.68	13.05	56	1.1	
K735336		0.073	0.07	0.73	117	1.90	9.36	62	0.9	0.05
K735359		0.074	0.08	0.74	70	0.18	7.12	49	2.0	
K735218										

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11109441

Method	CERTIFICATE COMMENTS
ME- MS41	Interference: Ca> 10% on ICP- MS As,ICP- AES results shown.
ME- MS41	Gold determinations by this method are semi- quantitative due to the small sample weight used (0.5g).

ALS Canada Ltd
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

CERTIFICATE WH11100820

Project: Stream seds

P.O. No.: GPD2011LIV001

This report is for 117 Stream Sediment samples submitted to our lab in Whitehorse, YT, Canada on 5- JUN- 2011.

The following have access to data associated with this certificate:

MIKE BURKE LINDA LEWIS	ANDREW CALDWELL MIKE MASLOWSKI	JACK COTE

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
TRA- 21	Transfer sample
DRY- 22	Drying - Maximum Temp 60C
SPL- 34	Pulp Splitting Charge
LOG- 21d	Sample logging - ClientBarCode Dup
LOG- 22	Sample login - Rcd w/o BarCode
WEI- 21	Received Sample Weight
SCR- 41	Screen to - 180um and save both

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au- ST44	Super Trace Au - 50g AR	ICP- MS
ME- MS41	51 anal. aqua regia ICPMS	
Au- OG44	Ore Grade Au - 50g AR	ICP- MS

To: GOLDEN PREDATOR CANADA CORP.
ATTN: ANDREW CALDWELL
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Sample Description	Method Analyte Units LOR	WEI- 21 Recvd Wt. kg 0.02	Au- ST44 Au ppm 0.0001	ME- MS41 Ag ppm 0.01	ME- MS41 Al % 0.01	ME- MS41 As ppm 0.1	ME- MS41 Au ppm 0.2	ME- MS41 B ppm 10	ME- MS41 Ba ppm 10	ME- MS41 Be ppm 0.05	ME- MS41 Bi ppm 0.01	ME- MS41 Ca % 0.01	ME- MS41 Cd ppm 0.01	ME- MS41 Ce ppm 0.02	ME- MS41 Co ppm 0.1	ME- MS41 Cr ppm 1
K735001		11.38	0.0007	0.08	1.88	24.4	<0.2	<10	180	0.48	0.18	1.26	0.66	29.3	8.5	29
K735002		6.79	0.0012	0.06	0.76	5.1	<0.2	<10	160	0.39	0.26	0.63	1.20	31.3	4.4	11
K735003		6.53	0.0004	0.09	1.28	16.3	<0.2	<10	200	0.40	0.21	1.14	0.68	30.8	6.9	19
K735004		6.46	0.0001	0.05	0.30	5.9	<0.2	<10	420	0.15	0.09	2.57	0.95	13.25	2.4	5
K735005		4.96	0.0029	0.07	1.03	6.5	<0.2	<10	190	0.26	0.06	0.78	0.47	18.30	11.2	38
K735006		5.78	0.0005	0.04	0.66	2.4	<0.2	<10	80	0.15	0.08	0.51	0.30	15.35	7.0	25
K735007		6.40	0.0061	0.13	0.50	6.6	<0.2	<10	90	0.17	0.16	2.14	0.47	20.3	9.5	19
K735008		6.61	0.0658	0.08	0.66	5.1	<0.2	<10	80	0.18	0.14	1.22	0.39	25.1	8.0	22
K735009		6.27	0.0010	0.05	0.78	4.4	<0.2	<10	70	0.20	0.13	0.49	0.25	30.8	7.9	17
K735010		6.37	0.0011	0.04	0.75	4.5	<0.2	<10	50	0.18	0.17	0.36	0.20	35.6	9.3	16
K735011		6.28	0.0179	0.07	0.86	8.6	<0.2	<10	70	0.22	0.16	1.37	0.25	29.8	7.9	20
K735012		5.45	0.0264	0.07	2.11	6.3	<0.2	<10	140	0.53	0.21	0.61	0.67	33.7	10.9	47
K735013		5.84	0.0012	0.06	1.69	6.5	<0.2	<10	120	0.46	0.32	0.53	0.35	36.8	9.9	40
K735014		4.18	0.0010	0.10	1.67	9.4	<0.2	<10	100	0.42	0.31	0.67	0.44	40.3	10.6	36
K735015		0.12	>0.1000	0.15	0.18	504	0.2	<10	1230	0.13	0.14	1.14	0.36	2.37	2.2	24
K735016		4.98	0.0013	0.07	1.63	5.6	<0.2	<10	120	0.45	0.34	0.57	0.50	32.0	9.6	37
K735017		5.03	0.0028	0.08	1.29	19.3	<0.2	<10	80	0.34	0.21	0.61	0.26	30.1	10.0	29
K735018		5.36	0.0015	0.07	1.30	11.6	<0.2	<10	70	0.32	0.26	0.55	0.22	35.5	10.4	27
K735019		6.52	0.0063	0.05	0.98	10.2	<0.2	<10	60	0.25	0.16	0.49	0.29	25.4	8.2	20
K735020		4.40	0.0010	0.25	2.73	5.5	<0.2	<10	290	0.50	0.42	0.75	1.56	21.9	22.9	131
K735021		5.94	0.0017	0.13	1.30	6.5	<0.2	<10	130	0.16	0.10	1.15	0.59	12.90	27.0	258
K735022		5.60	0.0009	0.05	1.18	6.6	<0.2	<10	90	0.11	0.10	0.51	0.24	5.26	34.3	261
K735023		5.77	0.0026	0.13	1.27	7.9	<0.2	<10	210	0.25	0.18	0.76	0.81	15.20	22.2	145
K735024		6.14	0.0008	0.19	1.13	6.9	<0.2	<10	140	0.18	0.11	0.59	0.57	13.00	24.1	183
K735025		5.98	0.0052	0.40	1.68	15.1	<0.2	<10	160	0.42	0.20	1.18	1.50	40.9	14.5	51
K735026		4.78	0.0051	0.24	1.25	24.7	<0.2	<10	90	0.36	0.75	0.45	0.64	21.7	13.2	34
K735027		4.68	0.0942	0.24	1.19	14.3	<0.2	<10	190	0.35	0.26	0.65	0.98	22.0	12.5	41
K735028		4.71	0.0045	0.10	0.88	4.8	<0.2	<10	80	0.18	0.18	0.29	0.31	16.45	8.1	25
K735029		6.10	0.0421	0.04	0.82	6.6	<0.2	<10	70	0.19	0.14	0.50	0.20	30.2	11.7	23
K735030		0.17	0.0013	0.22	1.06	3.3	<0.2	<10	80	0.18	0.04	0.67	0.14	9.91	7.5	30
K735031		4.81	0.0038	0.19	1.64	11.4	<0.2	<10	120	0.36	0.29	0.98	0.51	19.90	16.4	48
K735032		6.05	0.0003	0.14	0.92	2.9	<0.2	<10	170	0.24	0.14	0.62	1.12	20.8	9.6	23
K735033		4.65	0.0276	0.18	1.10	5.0	<0.2	<10	140	0.32	0.15	0.55	1.23	26.3	10.4	27
K735034		5.03	0.0003	0.16	0.82	4.1	<0.2	<10	150	0.25	0.15	1.31	1.52	18.40	8.4	19
K735035		7.29	<0.0001	0.07	0.59	5.8	<0.2	<10	180	0.33	0.22	1.44	1.01	22.3	2.9	8
K735051		3.92	0.0006	0.06	1.67	3.6	<0.2	<10	140	0.44	0.22	0.94	0.41	26.6	8.3	34
K735052		5.02	0.0014	0.04	1.22	3.9	<0.2	<10	110	0.37	0.18	0.64	0.19	27.8	6.1	18
K735053		4.77	0.0017	0.04	0.75	2.3	<0.2	<10	80	0.23	0.14	1.27	0.13	22.3	5.2	11
K735054		4.07	0.0018	0.15	2.38	2.7	<0.2	<10	180	0.66	0.26	0.81	1.65	31.3	13.2	64
K735055		4.40	0.0007	0.11	2.13	3.6	<0.2	<10	150	0.58	0.28	0.76	0.84	32.5	12.9	59

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Sample Description	Method Analyte Units LOR	ME- MS41 Cs ppm 0.05	ME- MS41 Cu ppm 0.2	ME- MS41 Fe % 0.01	ME- MS41 Ga ppm 0.05	ME- MS41 Ge ppm 0.05	ME- MS41 Hf ppm 0.02	ME- MS41 Hg ppm 0.01	ME- MS41 In ppm 0.005	ME- MS41 K % 0.01	ME- MS41 La ppm 0.2	ME- MS41 Li ppm 0.1	ME- MS41 Mg % 0.01	ME- MS41 Mn ppm 5	ME- MS41 Mo ppm 0.05	ME- MS41 Na % 0.01
K735001		2.57	13.2	2.22	5.71	0.09	0.03	0.01	0.017	0.17	15.9	22.8	1.04	381	1.31	0.08
K735002		2.02	9.9	1.37	3.19	0.06	0.03	0.02	0.009	0.09	16.1	20.3	0.33	192	0.88	0.01
K735003		2.33	12.2	1.75	4.43	0.08	0.03	0.02	0.014	0.12	16.5	20.5	0.71	243	0.98	0.04
K735004		1.15	6.3	0.72	1.25	<0.05	0.03	0.01	0.006	0.04	7.3	7.4	1.32	121	1.69	0.01
K735005		1.55	36.1	2.35	3.18	0.06	0.03	0.01	0.011	0.15	10.1	8.1	0.85	710	0.53	0.01
K735006		0.78	14.0	1.41	2.28	0.05	0.02	0.01	0.008	0.08	8.1	7.7	0.46	237	0.59	0.01
K735007		0.87	20.8	1.53	1.76	0.05	0.09	0.01	0.008	0.09	10.1	6.8	0.48	284	1.80	0.01
K735008		0.88	15.7	1.79	2.24	0.06	0.05	0.01	0.009	0.09	12.4	7.4	0.51	363	1.21	0.01
K735009		0.96	12.2	1.71	2.78	0.07	0.04	0.01	0.009	0.07	15.1	9.8	0.51	378	0.51	0.01
K735010		0.84	14.0	1.99	2.86	0.07	0.04	0.01	0.010	0.07	16.8	7.5	0.54	382	0.55	<0.01
K735011		1.24	15.2	1.86	2.85	0.06	0.05	0.01	0.010	0.11	14.9	9.8	0.55	351	0.70	0.02
K735012		4.05	17.3	2.73	7.35	0.10	0.03	0.01	0.025	0.41	16.5	26.3	1.24	545	0.94	0.04
K735013		3.89	18.1	2.41	6.09	0.08	0.02	0.01	0.020	0.25	19.1	24.0	0.85	323	1.21	0.04
K735014		3.83	23.5	2.58	5.57	0.10	0.04	0.01	0.020	0.28	19.4	23.1	0.93	381	1.05	0.04
K735015		0.34	60.4	3.99	0.74	0.05	0.43	2.74	0.007	0.07	1.7	2.1	0.02	111	16.85	0.03
K735016		3.15	15.8	2.23	5.58	0.09	0.03	0.01	0.018	0.29	15.6	20.7	0.91	490	0.85	0.04
K735017		2.26	18.1	2.27	4.53	0.07	0.03	0.01	0.018	0.13	15.5	16.6	0.67	307	0.60	0.03
K735018		2.27	17.9	2.32	4.55	0.08	0.03	0.01	0.014	0.15	16.8	17.3	0.75	303	0.64	0.02
K735019		1.47	14.5	1.82	3.36	0.06	0.03	0.01	0.011	0.12	13.0	11.9	0.53	232	0.56	0.02
K735020		8.47	66.6	4.08	8.31	0.11	0.02	0.02	0.029	0.39	10.8	30.8	1.99	582	4.08	0.05
K735021		1.66	76.6	3.53	3.28	0.09	0.04	0.01	0.011	0.05	6.4	7.9	2.30	466	1.83	0.02
K735022		0.66	72.5	3.00	2.83	0.07	0.02	0.01	0.006	0.03	2.7	5.6	2.69	389	0.50	0.01
K735023		2.60	57.4	2.83	3.77	0.07	0.02	0.02	0.013	0.11	8.1	11.2	1.62	435	1.94	0.03
K735024		1.44	48.4	2.75	3.43	0.07	0.02	0.01	0.011	0.08	6.7	8.6	1.93	358	1.41	0.02
K735025		1.68	47.3	3.40	5.01	0.12	0.06	0.01	0.020	0.19	20.5	22.3	1.20	548	7.30	0.04
K735026		2.09	26.9	2.47	3.88	0.06	0.03	0.01	0.020	0.08	10.4	13.2	0.70	801	1.40	0.03
K735027		2.28	31.9	2.43	3.90	0.07	0.04	0.01	0.019	0.12	11.3	14.8	0.94	380	3.52	0.03
K735028		0.62	14.1	1.85	3.11	<0.05	0.04	0.02	0.010	0.05	8.4	11.8	0.68	163	1.54	<0.01
K735029		0.63	22.6	2.35	2.66	0.06	0.03	0.01	0.009	0.06	14.1	6.8	0.63	443	0.89	<0.01
K735030		0.31	21.8	2.11	4.01	0.08	0.26	0.02	0.014	0.07	4.6	6.8	0.48	320	4.24	0.03
K735031		7.14	37.5	3.04	4.81	0.07	0.03	0.02	0.019	0.20	10.3	17.8	1.56	533	1.02	<0.01
K735032		0.87	21.0	2.25	3.07	0.05	0.03	0.01	0.009	0.07	11.9	10.5	0.66	422	2.26	<0.01
K735033		1.38	17.1	2.49	3.76	0.07	0.03	0.02	0.014	0.07	13.9	14.9	0.72	442	2.91	<0.01
K735034		1.03	17.7	2.11	2.69	0.06	0.02	0.02	0.011	0.07	9.8	10.3	0.99	486	2.34	<0.01
K735035		2.05	5.6	1.07	2.55	0.06	0.02	0.01	0.008	0.08	12.1	15.5	0.41	149	0.89	<0.01
K735051		4.29	17.1	2.07	5.77	0.09	<0.02	0.02	0.019	0.36	15.2	22.3	0.90	272	0.53	0.03
K735052		2.08	8.8	1.64	4.09	0.07	0.02	<0.01	0.012	0.25	14.3	13.1	0.69	282	0.53	0.01
K735053		1.27	6.6	1.33	2.62	0.05	0.03	0.01	0.009	0.12	11.9	8.0	0.56	197	0.29	<0.01
K735054		7.67	31.7	2.76	8.10	0.12	<0.02	0.03	0.025	0.43	24.1	29.8	1.22	385	1.30	0.04
K735055		6.75	30.1	2.87	7.54	0.11	<0.02	0.02	0.028	0.41	17.4	24.8	1.13	366	1.32	0.03

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
K735001		1.07	21.9	970	12.2	27.2	0.001	0.02	1.15	3.2	0.8	0.5	60.1	<0.01	0.02	4.6
K735002		1.12	12.1	1050	6.8	22.3	<0.001	0.03	0.60	1.3	0.9	0.6	20.2	<0.01	0.01	3.6
K735003		1.06	18.2	1150	9.8	22.9	0.001	0.03	0.88	2.4	1.1	0.5	42.1	<0.01	0.02	4.5
K735004		0.46	19.6	820	8.6	9.0	0.001	0.02	0.93	0.7	1.0	0.2	26.4	<0.01	0.01	1.6
K735005		0.59	30.7	870	4.4	14.4	0.001	0.01	0.33	2.8	0.5	0.2	40.4	<0.01	0.02	2.8
K735006		0.59	23.2	880	3.7	9.6	<0.001	0.01	0.22	1.8	0.5	0.2	18.5	<0.01	0.01	2.2
K735007		0.37	25.9	1190	7.0	6.7	0.001	0.09	0.58	1.7	0.9	0.2	50.2	<0.01	0.01	4.2
K735008		0.59	25.0	1080	6.2	8.2	<0.001	0.01	0.35	1.8	0.8	0.2	33.3	<0.01	0.02	3.9
K735009		0.61	22.1	960	6.0	9.3	<0.001	0.01	0.19	1.7	0.4	0.2	24.6	<0.01	0.01	4.2
K735010		0.36	22.7	790	7.8	8.4	<0.001	<0.01	0.18	1.5	0.4	0.2	17.2	<0.01	0.02	4.5
K735011		0.76	21.3	890	7.5	10.6	<0.001	<0.01	0.30	2.0	0.5	0.3	51.0	<0.01	0.02	4.5
K735012		1.33	31.4	860	15.2	45.9	<0.001	0.01	0.16	5.0	0.6	1.0	30.5	<0.01	0.02	5.7
K735013		1.48	28.9	990	12.8	31.8	<0.001	0.02	0.27	4.0	0.7	0.8	32.1	<0.01	0.02	5.1
K735014		1.39	31.9	980	10.6	31.5	<0.001	0.02	0.74	4.1	0.7	0.9	38.3	<0.01	0.02	6.4
K735015		0.10	15.6	60	16.6	2.7	0.001	0.14	28.0	0.6	1.6	2.7	29.4	<0.01	0.07	0.8
K735016		1.36	27.7	750	11.3	33.3	<0.001	0.02	0.22	3.9	0.7	0.7	32.8	<0.01	0.02	4.8
K735017		1.32	27.5	730	10.4	20.8	<0.001	0.01	0.28	2.9	0.6	0.5	40.5	<0.01	0.02	4.7
K735018		1.12	28.8	930	9.9	22.7	<0.001	0.02	0.27	2.7	0.6	0.5	33.2	<0.01	0.02	5.1
K735019		0.81	23.1	680	8.2	14.9	<0.001	0.01	0.18	2.2	0.6	0.4	29.3	<0.01	0.02	3.9
K735020		1.32	107.5	920	8.5	36.2	0.001	0.06	0.38	6.0	1.8	1.6	42.5	<0.01	0.06	2.2
K735021		0.31	233	830	5.1	4.4	<0.001	0.02	0.85	2.9	0.8	0.2	31.9	<0.01	0.03	2.1
K735022		0.24	248	500	2.4	2.5	<0.001	0.02	0.50	3.5	0.7	<0.2	20.5	<0.01	0.03	0.9
K735023		0.63	148.5	920	6.9	9.4	<0.001	0.03	0.93	3.5	1.0	0.4	34.6	<0.01	0.04	2.8
K735024		0.43	176.5	810	5.1	6.5	<0.001	0.02	0.74	3.3	0.7	0.3	26.8	<0.01	0.03	1.9
K735025		0.39	62.4	910	12.8	16.6	0.001	0.06	0.43	3.4	3.1	0.4	61.3	<0.01	0.06	7.5
K735026		0.44	42.1	670	16.5	9.4	<0.001	0.02	0.42	3.0	0.7	0.4	32.7	<0.01	0.04	2.9
K735027		0.63	49.5	870	12.1	13.0	0.001	0.03	0.97	3.4	1.2	0.5	32.2	<0.01	0.04	3.8
K735028		0.54	22.9	750	6.8	4.6	<0.001	0.02	0.44	1.8	1.0	0.3	14.1	<0.01	<0.01	2.8
K735029		0.35	30.7	760	11.1	5.5	<0.001	<0.01	0.35	1.9	0.5	0.2	22.9	<0.01	0.05	4.6
K735030		0.22	20.7	500	2.4	2.8	0.001	0.03	0.33	4.0	0.5	0.4	27.7	<0.01	0.02	0.9
K735031		0.65	61.1	830	14.6	16.8	<0.001	0.02	0.34	4.4	0.8	0.7	27.7	<0.01	0.03	3.4
K735032		0.84	26.4	2020	7.0	9.0	0.001	0.01	0.30	2.3	0.8	0.2	19.0	<0.01	0.02	3.4
K735033		0.73	29.4	1590	7.4	10.5	0.003	<0.01	0.38	2.5	1.5	0.3	22.6	<0.01	0.02	3.6
K735034		0.80	25.8	1550	7.4	9.5	0.002	0.02	0.59	2.0	1.2	0.2	25.0	<0.01	0.02	2.9
K735035		1.31	10.0	1240	6.8	17.6	<0.001	<0.01	0.72	1.1	0.9	0.6	17.9	<0.01	0.01	4.9
K735051		1.55	22.5	700	9.3	45.4	<0.001	0.01	0.18	4.2	0.7	0.8	24.6	<0.01	0.01	4.4
K735052		0.93	15.1	840	9.1	28.4	<0.001	<0.01	0.26	2.5	0.6	0.5	22.4	<0.01	0.02	4.9
K735053		0.61	11.1	770	5.5	15.9	<0.001	<0.01	0.14	1.4	0.6	0.3	29.9	<0.01	0.01	3.7
K735054		2.02	41.4	790	11.9	43.6	0.001	0.05	0.27	6.2	1.9	1.0	41.0	<0.01	0.03	3.9
K735055		1.63	38.9	960	25.8	37.5	<0.001	0.03	0.40	6.2	1.4	0.9	32.8	<0.01	0.03	4.6

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	Au- OG44
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr	Au
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5	0.01
K735001		0.061	0.16	1.02	55	0.32	7.15	121	1.0	
K735002		0.046	0.11	1.10	29	5.95	9.00	92	0.5	
K735003		0.048	0.14	1.39	39	3.51	9.04	93	0.8	
K735004		0.018	0.06	0.79	17	1.17	6.96	82	0.8	
K735005		0.063	0.08	0.54	44	0.10	6.33	52	0.9	
K735006		0.046	0.07	1.37	31	0.59	5.42	47	0.5	
K735007		0.040	0.07	11.90	28	1.25	7.98	47	2.9	
K735008		0.040	0.07	0.66	31	0.52	7.25	52	1.7	
K735009		0.035	0.08	0.44	24	0.49	6.36	51	1.3	
K735010		0.029	0.08	0.36	23	0.58	6.08	49	1.6	
K735011		0.042	0.10	0.57	30	1.05	6.94	50	1.5	
K735012		0.112	0.35	1.09	64	3.04	7.47	97	0.8	
K735013		0.093	0.26	1.86	59	4.92	7.73	83	0.6	
K735014		0.080	0.28	1.24	53	1.64	9.06	86	1.5	
K735015		0.011	10.45	1.04	11	3.21	2.11	19	12.5	NSS
K735016		0.082	0.26	0.98	50	0.50	6.92	80	0.8	
K735017		0.064	0.17	0.88	39	0.61	7.80	64	1.1	
K735018		0.054	0.18	0.87	37	0.51	7.72	64	1.1	
K735019		0.040	0.12	0.69	28	0.71	5.78	59	1.0	
K735020		0.110	0.42	2.37	117	0.15	8.15	175	0.6	
K735021		0.077	0.06	0.72	62	0.35	5.07	99	1.5	
K735022		0.077	0.03	0.27	53	0.07	3.26	41	0.5	
K735023		0.067	0.12	1.02	59	0.51	5.82	114	0.8	
K735024		0.070	0.09	0.77	57	0.44	4.65	81	0.9	
K735025		0.042	0.22	1.56	53	1.53	10.20	149	2.7	
K735026		0.037	0.13	0.95	42	1.67	5.04	90	1.0	
K735027		0.046	0.17	1.61	48	1.37	6.64	127	1.2	
K735028		0.066	0.05	1.06	32	0.06	4.22	60	1.4	
K735029		0.034	0.06	0.60	28	0.41	5.78	55	1.3	
K735030		0.110	0.05	0.26	47	10.25	6.90	35	7.0	
K735031		0.063	0.18	0.69	52	0.32	6.16	84	0.9	
K735032		0.062	0.07	1.50	46	1.83	7.14	129	0.9	
K735033		0.044	0.10	1.24	49	0.61	7.92	131	0.8	
K735034		0.043	0.08	1.21	35	4.73	7.68	129	0.7	
K735035		0.039	0.10	3.19	21	6.53	11.20	93	0.6	
K735051		0.104	0.27	1.27	41	2.16	10.15	78	<0.5	
K735052		0.065	0.19	9.98	26	1.15	7.27	40	0.8	
K735053		0.036	0.10	0.49	18	1.06	6.35	33	0.9	
K735054		0.137	0.33	3.28	73	0.82	16.40	111	<0.5	
K735055		0.129	0.29	1.38	76	1.16	10.30	103	<0.5	

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Sample Description	Method	WEI- 21	Au- ST44	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.0001	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
K735056		5.32	0.0003	0.03	2.45	3.7	<0.2	<10	140	0.68	0.17	0.70	0.27	33.3	10.3	42
K735057		4.73	0.0094	0.07	2.00	3.5	<0.2	<10	130	0.54	0.23	0.69	0.50	30.7	10.8	45
K735058		4.39	0.0006	0.09	1.82	3.8	<0.2	<10	150	0.52	0.30	0.63	1.83	29.6	9.5	44
K735059		5.84	0.0034	0.07	1.03	4.1	<0.2	<10	60	0.23	0.19	0.87	0.26	41.0	11.5	31
K735060		5.14	0.0004	0.05	1.07	2.6	<0.2	<10	60	0.27	0.15	0.46	0.22	34.8	10.3	41
K735061		4.70	0.0004	0.21	1.63	6.3	<0.2	<10	150	0.99	0.86	0.73	0.54	46.5	11.0	34
K735062		4.41	0.0015	0.12	1.47	6.1	<0.2	<10	110	0.71	0.50	0.73	0.55	44.1	7.6	26
K735063		4.61	0.0001	0.15	1.42	18.5	<0.2	<10	160	0.55	0.37	1.25	0.96	32.9	8.8	26
K735064		4.69	0.0003	0.14	2.48	22.3	<0.2	<10	210	0.66	0.17	1.47	1.32	38.5	11.0	35
K735065		0.11	0.0444	0.09	1.21	48.8	0.2	<10	110	0.25	0.09	1.31	0.34	11.85	6.5	24
K735066		5.34	0.0011	0.12	1.43	14.5	<0.2	<10	130	0.59	0.27	1.88	0.71	33.9	7.9	21
K735067		6.53	0.0002	0.05	1.03	5.5	<0.2	<10	180	0.31	0.24	1.75	0.29	35.1	6.1	14
K735068		2.00	0.0007	0.07	1.62	3.8	<0.2	<10	100	0.48	0.22	0.83	0.29	36.4	8.0	32
K735069		4.23	0.0031	0.06	1.12	4.9	<0.2	<10	60	0.28	0.17	1.01	0.17	36.3	10.7	24
K735070		6.55	0.0009	0.04	0.62	12.2	<0.2	<10	50	0.23	0.19	0.67	0.13	28.4	8.5	11
K735071		7.42	0.0003	0.11	0.52	5.6	<0.2	<10	90	0.18	0.14	1.83	0.33	19.30	6.0	13
K735072		4.85	0.0001	0.10	1.05	6.8	<0.2	<10	60	0.33	0.22	2.37	0.23	28.2	7.4	16
K735073		5.39	0.0014	0.12	1.48	5.9	<0.2	<10	160	0.41	0.20	1.28	0.68	21.7	11.0	45
K735074		7.86	0.0088	0.19	1.16	9.1	<0.2	<10	170	0.32	0.18	2.48	0.94	23.8	14.8	78
K735075		4.94	0.0004	0.21	1.55	4.9	<0.2	<10	160	0.78	0.32	1.06	1.93	33.0	11.5	45
K735076		4.45	0.0020	0.08	1.35	4.5	<0.2	<10	120	0.40	0.19	0.73	0.37	21.7	8.5	37
K735077		6.35	0.0002	0.06	1.12	3.1	<0.2	<10	130	0.42	0.20	0.71	0.25	38.5	8.7	22
K735078		4.03	0.0002	0.14	0.99	4.6	<0.2	<10	310	0.27	0.24	1.52	1.66	30.7	8.6	21
K735079		6.17	0.0094	0.11	1.39	5.3	<0.2	<10	220	0.31	0.23	0.71	1.49	18.20	21.1	163
K735080		0.18	0.0013	0.19	0.95	3.0	<0.2	<10	80	0.19	0.05	0.60	0.13	8.97	6.3	30
K735081		7.12	0.0003	0.18	1.09	8.1	<0.2	<10	380	0.36	0.19	0.66	0.92	18.70	9.9	38
K735082		7.73	0.0442	0.14	0.77	7.7	<0.2	<10	360	0.28	0.57	2.79	0.91	18.10	16.0	86
K735083		5.91	0.0012	0.14	1.15	5.4	<0.2	<10	100	0.41	0.18	0.64	0.91	30.9	8.8	25
K735084		4.86	0.0007	0.07	1.33	4.2	<0.2	<10	90	0.46	0.28	0.64	0.39	30.5	5.7	21
K735085		5.35	0.0007	0.21	1.34	8.9	<0.2	<10	150	0.54	0.19	0.56	1.53	32.6	13.1	32
K735086		2.28	0.0006	0.38	0.92	13.9	<0.2	<10	150	0.56	0.45	0.59	3.10	25.1	6.4	15
K735101		3.27	0.0003	0.13	1.11	4.6	<0.2	<10	100	0.39	0.19	0.82	0.69	25.7	7.7	24
K735102		3.18	0.0009	0.05	1.17	3.8	<0.2	<10	80	0.38	0.16	0.69	0.30	28.6	6.1	21
K735103		8.65	<0.0001	0.08	0.54	5.2	<0.2	<10	60	0.24	0.21	0.73	0.36	25.7	4.2	10
K735104		8.60	0.0005	0.08	0.68	5.6	<0.2	<10	70	0.26	0.17	0.48	0.41	26.4	5.8	13
K735105		8.29	0.0011	0.03	1.25	4.2	<0.2	<10	60	0.39	0.16	0.62	0.11	39.3	7.9	19
K735106		3.95	0.0012	0.06	1.35	5.5	<0.2	<10	40	0.32	0.22	0.64	0.20	47.1	12.2	20
K735107		6.29	0.0008	0.10	1.88	3.6	<0.2	<10	250	0.39	0.16	0.85	1.40	23.8	21.4	72
K735108		4.65	0.0007	0.11	1.98	5.3	<0.2	<10	270	0.58	0.24	0.94	0.82	29.7	16.1	52
K735109		5.60	0.0004	0.12	2.06	9.5	<0.2	<10	210	0.60	0.15	1.70	1.12	41.2	17.0	41

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
K735056		3.48	13.6	2.70	8.55	0.12	0.02	0.01	0.030	0.51	16.9	23.2	1.45	399	0.40	0.05
K735057		4.01	18.2	2.59	7.08	0.09	<0.02	0.01	0.025	0.38	16.4	22.9	1.11	334	0.87	0.03
K735058		3.84	17.5	2.52	5.96	0.07	<0.02	0.01	0.020	0.30	16.2	23.6	0.86	672	1.45	0.04
K735059		0.87	28.6	2.52	3.74	0.05	0.02	0.01	0.019	0.09	21.2	8.1	0.66	352	1.09	0.01
K735060		0.87	34.5	2.50	3.79	0.06	0.04	0.01	0.014	0.09	17.0	7.2	0.69	296	0.81	0.01
K735061		8.40	26.5	3.07	5.93	0.09	0.02	0.03	0.034	0.32	24.2	43.3	0.80	517	2.03	0.02
K735062		5.21	18.7	2.37	5.02	0.07	<0.02	0.04	0.021	0.23	27.5	25.4	0.59	305	1.14	0.03
K735063		4.45	20.1	2.33	4.74	0.07	0.03	0.01	0.022	0.20	17.6	23.1	0.95	301	2.34	0.03
K735064		2.11	20.8	2.57	7.77	0.09	0.04	0.01	0.024	0.30	20.3	21.7	1.37	408	1.62	0.12
K735065		0.45	50.0	2.83	4.70	0.07	0.32	0.42	0.022	0.10	5.6	11.1	0.55	402	10.05	0.07
K735066		3.46	16.1	2.09	4.83	0.07	0.03	0.01	0.019	0.19	18.0	19.7	1.27	294	1.97	0.04
K735067		2.06	9.5	1.73	3.77	0.06	<0.02	0.01	0.014	0.19	18.1	15.3	0.80	226	1.18	0.03
K735068		2.84	19.8	1.93	5.41	0.07	0.03	0.01	0.017	0.35	18.4	17.1	0.81	426	0.74	0.06
K735069		1.06	21.0	2.27	4.01	0.05	0.05	0.01	0.014	0.11	17.8	9.1	0.78	648	0.59	0.02
K735070		0.84	14.6	2.02	2.27	0.05	0.04	0.01	0.012	0.07	13.9	6.3	0.40	438	0.47	0.01
K735071		0.80	13.9	1.21	1.79	<0.05	0.05	0.01	0.007	0.08	9.1	6.6	0.46	263	1.24	0.02
K735072		1.80	16.3	1.71	3.44	<0.05	0.02	0.01	0.011	0.14	15.2	12.1	0.69	296	0.63	0.04
K735073		3.27	24.6	2.23	5.01	0.08	0.02	0.02	0.016	0.22	10.9	18.1	1.02	361	1.69	0.03
K735074		1.67	32.2	2.52	3.79	0.07	0.04	0.01	0.015	0.14	11.9	12.3	1.42	366	4.04	0.02
K735075		4.92	25.5	2.19	5.54	0.09	0.02	0.03	0.021	0.22	17.6	30.6	0.77	474	2.69	0.03
K735076		2.39	15.3	2.03	4.75	0.07	0.02	0.01	0.013	0.24	10.5	16.7	0.87	285	0.66	0.02
K735077		3.08	15.5	2.09	4.65	0.09	<0.02	0.01	0.013	0.21	17.3	35.0	0.87	254	0.67	<0.01
K735078		2.33	17.3	2.13	3.55	0.08	<0.02	0.02	0.013	0.12	15.3	12.0	1.05	295	1.81	0.01
K735079		3.68	41.1	3.23	4.89	0.10	0.03	0.01	0.018	0.26	8.6	16.4	2.03	438	2.34	0.02
K735080		0.26	19.2	1.95	3.68	0.07	0.21	0.03	0.015	0.06	3.7	6.8	0.48	307	3.75	0.03
K735081		2.22	21.1	1.87	3.63	0.06	0.02	0.02	0.014	0.12	9.5	12.0	1.06	381	2.57	<0.01
K735082		2.96	24.5	2.22	2.58	0.06	0.02	0.02	0.014	0.13	8.5	11.0	2.79	317	2.35	<0.01
K735083		2.11	16.2	2.11	4.58	0.08	0.02	0.02	0.018	0.17	16.6	18.2	0.75	331	1.56	<0.01
K735084		2.61	11.4	1.69	5.29	0.08	0.02	0.02	0.020	0.28	17.4	20.5	0.67	217	0.69	0.02
K735085		1.96	23.4	2.72	4.89	0.06	0.02	0.02	0.020	0.14	16.8	20.4	0.93	480	3.13	<0.01
K735086		1.88	19.3	1.77	3.46	0.05	0.04	0.06	0.017	0.13	12.4	21.5	0.35	257	3.05	<0.01
K735101		2.09	16.0	2.05	4.38	0.07	<0.02	0.01	0.017	0.20	14.4	17.6	0.78	225	1.30	<0.01
K735102		1.60	8.2	1.70	4.35	0.07	0.02	0.01	0.016	0.21	14.1	13.6	0.66	204	0.48	0.02
K735103		0.96	11.8	1.20	2.16	0.05	0.03	<0.01	0.008	0.11	12.7	7.1	0.35	150	1.65	<0.01
K735104		1.11	12.7	1.55	2.80	0.05	0.03	0.01	0.009	0.09	12.3	10.3	0.41	233	1.78	<0.01
K735105		1.42	15.4	2.03	4.50	0.09	0.03	<0.01	0.014	0.15	17.9	10.9	0.86	265	0.25	0.01
K735106		1.21	28.7	2.60	4.75	0.09	0.05	0.02	0.015	0.14	22.8	9.9	1.05	407	0.50	0.01
K735107		2.99	34.1	3.51	7.04	0.09	<0.02	0.02	0.019	0.41	12.0	26.2	1.33	455	2.15	0.02
K735108		6.53	33.7	3.23	7.10	0.10	0.02	0.02	0.020	0.40	15.6	31.4	1.19	412	1.84	0.03
K735109		2.51	24.5	3.01	7.12	0.11	0.06	0.01	0.021	0.27	20.7	24.0	1.61	385	3.59	0.03

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
K735056		1.48	24.3	630	9.5	45.9	<0.001	<0.01	0.10	6.1	0.6	1.0	26.8	<0.01	0.02	5.5
K735057		1.49	28.1	880	13.2	37.7	<0.001	0.01	0.21	5.1	0.8	0.9	28.9	<0.01	0.03	4.9
K735058		1.78	39.5	820	11.7	34.6	0.002	0.03	0.24	4.2	0.6	0.9	33.1	<0.01	<0.01	4.7
K735059		0.58	35.2	970	9.2	8.4	<0.001	0.01	0.27	2.7	0.6	0.3	41.0	<0.01	0.03	5.7
K735060		0.67	37.1	1030	8.8	9.5	<0.001	0.01	0.14	3.0	0.5	0.3	33.9	<0.01	0.02	5.1
K735061		1.67	30.0	1430	11.0	38.2	<0.001	0.02	1.07	5.1	1.0	1.8	35.7	<0.01	<0.01	8.0
K735062		1.66	21.2	1500	9.6	28.4	<0.001	0.02	1.69	3.6	0.7	1.0	51.4	<0.01	<0.01	6.0
K735063		1.28	34.1	1260	10.6	23.5	0.002	0.03	1.89	3.4	0.7	0.8	45.7	<0.01	<0.01	5.6
K735064		1.32	30.4	870	15.1	30.9	0.001	0.02	2.00	4.3	1.2	0.6	82.3	<0.01	<0.01	6.1
K735065		0.27	31.7	720	2.8	4.2	0.003	0.11	0.94	4.7	1.5	1.8	40.8	<0.01	0.04	1.3
K735066		1.27	23.5	1310	10.3	21.8	0.001	0.02	1.48	3.0	1.0	0.7	56.8	<0.01	0.01	5.5
K735067		1.43	14.6	1770	10.4	22.6	<0.001	0.01	0.23	2.4	0.6	0.6	65.6	<0.01	<0.01	6.2
K735068		1.85	23.9	680	9.3	31.3	<0.001	0.02	0.20	3.9	0.6	0.8	44.7	<0.01	<0.01	6.0
K735069		0.59	30.5	770	9.9	13.0	<0.001	0.01	0.20	2.6	0.5	0.3	37.6	<0.01	0.01	5.2
K735070		0.50	18.4	620	10.2	8.0	0.001	0.02	0.66	1.7	0.3	0.2	34.6	<0.01	<0.01	4.1
K735071		0.54	17.9	980	5.4	7.0	0.001	0.03	0.39	1.5	0.6	0.3	47.6	<0.01	<0.01	3.2
K735072		1.10	18.6	790	8.1	15.1	0.001	0.02	0.22	2.1	0.9	0.4	89.9	<0.01	<0.01	3.9
K735073		1.11	35.8	960	7.2	21.3	<0.001	0.02	0.36	4.0	0.9	0.5	60.0	<0.01	0.02	3.4
K735074		0.48	85.5	960	7.9	11.9	0.001	0.04	0.52	3.0	1.6	0.3	92.1	<0.01	0.05	4.2
K735075		1.82	49.2	1040	9.5	29.3	0.002	0.06	0.50	4.3	2.0	0.8	67.7	<0.01	0.03	3.8
K735076		1.08	24.1	830	7.0	24.2	0.001	0.01	0.23	3.5	0.5	0.5	35.0	<0.01	0.02	3.3
K735077		1.60	32.6	1000	8.0	24.9	0.001	0.01	0.14	2.8	0.8	0.6	23.2	<0.01	0.02	6.7
K735078		0.83	34.7	1350	18.8	15.0	0.001	0.05	0.41	2.3	1.0	0.3	40.9	<0.01	0.02	3.7
K735079		0.79	174.5	1250	5.4	18.7	<0.001	0.02	0.46	4.6	0.8	0.9	29.8	<0.01	0.05	2.8
K735080		0.17	19.5	470	2.1	2.4	0.001	0.03	0.26	3.4	0.4	0.3	24.6	<0.01	0.04	0.8
K735081		0.77	64.8	1260	15.4	13.8	0.002	0.03	3.19	2.7	1.0	0.6	26.8	<0.01	0.03	2.5
K735082		0.36	172.5	920	11.7	13.1	<0.001	0.02	0.53	2.5	0.8	0.6	51.5	<0.01	0.03	3.1
K735083		1.16	24.4	1320	8.3	22.8	<0.001	0.01	0.56	3.2	1.4	0.5	22.7	<0.01	0.02	3.9
K735084		1.33	15.4	870	7.2	34.6	<0.001	<0.01	0.37	3.4	0.5	0.8	23.4	<0.01	0.01	4.5
K735085		0.71	36.8	1280	10.4	17.6	0.002	0.01	1.55	3.6	1.5	0.5	26.5	<0.01	0.03	4.4
K735086		1.27	33.8	1290	12.1	24.2	0.002	0.02	1.96	1.8	1.2	0.5	24.4	<0.01	0.03	2.4
K735101		1.19	21.4	1240	7.2	24.9	<0.001	<0.01	0.45	3.1	1.2	0.6	25.9	<0.01	0.02	3.8
K735102		1.08	15.5	920	6.2	24.2	<0.001	<0.01	0.19	2.7	0.8	0.6	26.4	<0.01	0.01	4.6
K735103		0.61	14.4	1230	6.3	10.1	<0.001	<0.01	1.49	1.4	0.6	0.4	22.0	<0.01	0.02	4.5
K735104		0.71	18.1	1150	6.4	13.7	0.001	<0.01	0.50	1.6	0.8	0.3	18.8	<0.01	0.02	3.9
K735105		0.63	20.0	720	8.8	20.2	<0.001	<0.01	0.15	2.3	0.3	0.4	23.3	<0.01	0.02	4.8
K735106		0.45	32.8	860	13.4	18.5	<0.001	0.01	0.16	2.6	0.5	0.3	25.2	<0.01	0.03	6.3
K735107		1.62	48.9	2140	6.2	26.1	0.001	0.01	0.93	5.2	0.8	0.5	29.5	<0.01	0.02	3.2
K735108		1.89	38.1	1750	8.4	28.3	<0.001	0.01	1.23	5.2	1.0	0.7	45.0	<0.01	0.01	4.7
K735109		1.04	44.4	1290	9.0	25.2	0.001	0.02	2.16	4.1	0.9	0.4	51.7	<0.01	0.05	6.4

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	Au- OG44
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr	Au
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5	0.01
K735056		0.138	0.30	1.13	51	0.35	8.53	82	0.6	
K735057		0.113	0.25	1.22	57	0.76	9.91	87	0.5	
K735058		0.101	0.30	2.23	60	0.94	7.51	145	0.5	
K735059		0.040	0.06	1.45	36	0.53	8.67	76	1.3	
K735060		0.043	0.08	0.69	40	0.15	7.26	69	1.9	
K735061		0.085	0.38	3.96	56	1.19	14.65	90	0.9	
K735062		0.071	0.32	3.15	50	9.05	14.80	83	<0.5	
K735063		0.062	0.26	2.30	59	0.53	10.00	151	1.2	
K735064		0.071	0.22	1.40	75	0.20	8.44	131	1.5	
K735065		0.099	0.57	0.55	46	0.64	8.23	47	8.9	
K735066		0.053	0.19	1.79	49	1.16	9.74	102	1.2	
K735067		0.056	0.17	1.22	32	3.86	10.55	67	0.6	
K735068		0.082	0.25	1.83	40	0.51	8.45	49	1.5	
K735069		0.030	0.09	0.70	23	0.15	7.07	46	2.4	
K735070		0.024	0.07	1.56	17	0.18	5.75	42	1.7	
K735071		0.035	0.06	0.90	21	0.44	6.33	40	2.2	
K735072		0.037	0.10	0.98	26	0.43	7.27	41	1.1	
K735073		0.069	0.20	0.98	55	0.90	6.27	83	0.7	
K735074		0.050	0.15	1.10	49	1.19	7.58	99	1.5	
K735075		0.073	0.27	12.40	59	2.37	12.05	130	0.6	
K735076		0.072	0.18	0.65	49	0.75	5.11	65	0.6	
K735077		0.080	0.16	1.60	26	0.91	9.73	63	<0.5	
K735078		0.053	0.14	1.10	45	0.25	8.51	485	<0.5	
K735079		0.092	0.20	1.53	90	0.28	6.02	122	1.2	
K735080		0.098	0.05	0.23	44	10.05	5.46	34	5.5	
K735081		0.048	0.18	1.19	76	0.41	6.24	133	0.7	
K735082		0.042	0.15	0.88	41	27.7	6.34	88	0.8	
K735083		0.062	0.16	1.15	43	2.31	9.58	106	0.6	
K735084		0.086	0.23	1.54	33	1.62	10.45	58	<0.5	
K735085		0.042	0.17	1.48	58	0.26	9.06	154	0.9	
K735086		0.038	0.14	3.27	33	0.88	10.30	317	0.9	
K735101		0.065	0.16	0.96	40	7.29	9.41	94	0.5	
K735102		0.072	0.14	0.68	28	3.50	6.93	56	0.7	
K735103		0.034	0.09	1.01	19	2.21	7.92	45	1.7	
K735104		0.034	0.09	0.62	23	3.35	6.64	56	1.1	
K735105		0.049	0.13	0.67	25	0.42	6.23	50	1.2	
K735106		0.034	0.11	0.73	21	0.12	9.04	72	2.1	
K735107		0.130	0.24	1.11	116	2.06	8.62	185	0.5	
K735108		0.126	0.28	2.25	95	6.15	10.85	127	0.7	
K735109		0.073	0.28	1.56	93	0.76	10.25	160	2.3	

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Sample Description	Method	WEI- 21	Au- ST44	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Recvd Wt.	Au	Ag	Al	As	Au	B	Ba	Be	Bi	Ca	Cd	Ce	Co	Cr
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm
	LOR	0.02	0.0001	0.01	0.01	0.1	0.2	10	10	0.05	0.01	0.01	0.01	0.02	0.1	1
K735110		4.07	0.0001	0.12	1.68	11.8	<0.2	<10	160	0.54	0.25	1.10	0.99	34.3	11.7	34
K735111		13.74	<0.0001	0.05	0.80	4.6	<0.2	<10	50	0.23	0.30	2.30	0.13	39.5	4.8	11
K735112		<0.02	0.0009	0.03	0.78	5.2	<0.2	<10	50	0.24	0.40	2.32	0.12	40.4	4.8	10
K735113		5.91	0.0093	0.11	1.33	4.6	<0.2	<10	130	0.47	0.25	1.04	0.97	26.3	7.9	30
K735114		8.10	0.0005	0.13	1.04	4.6	<0.2	<10	110	0.48	0.24	1.32	0.92	27.9	6.7	21
K735115		0.12	0.0088	0.76	0.48	241	<0.2	<10	90	1.06	8.46	17.25	2.19	24.1	4.3	24
K735116		6.30	0.0268	0.05	0.78	7.5	<0.2	<10	60	0.19	0.16	0.98	0.18	29.7	7.9	17
K735117		7.33	0.0004	0.04	0.58	5.2	<0.2	<10	50	0.21	0.15	3.08	0.15	27.8	6.1	11
K735118		4.79	0.0013	0.04	0.60	5.2	<0.2	<10	40	0.17	0.14	1.28	0.18	27.0	6.7	13
K735119		5.16	>0.1000	0.06	0.75	13.4	<0.2	<10	40	0.18	0.20	0.82	0.17	30.9	9.4	19
K735120		4.81	0.0229	0.04	0.71	6.1	<0.2	<10	70	0.20	0.13	0.72	0.14	27.7	7.3	18
K735121		4.17	0.0980	0.08	0.73	19.5	<0.2	<10	40	0.15	0.14	0.50	0.18	33.7	9.2	19
K735122		5.59	0.0610	0.19	0.77	34.9	0.2	<10	40	0.18	0.14	0.31	0.30	32.2	10.3	22
K735123		4.94	0.0013	0.13	1.00	11.3	<0.2	<10	220	0.36	0.28	1.66	0.72	26.0	11.2	27
K735124		4.72	0.0039	0.10	1.16	23.9	<0.2	<10	120	0.23	0.26	0.38	0.80	22.0	20.7	54
K735125		4.55	0.0012	0.28	0.75	26.0	<0.2	<10	150	0.20	0.15	0.78	2.53	20.9	10.4	31
K735126		4.67	0.0031	0.12	0.96	15.6	<0.2	<10	190	0.33	0.21	1.07	0.80	22.5	11.9	33
K735127		4.15	0.0033	0.30	0.94	15.0	<0.2	<10	80	0.30	0.24	0.43	1.56	28.9	14.8	29
K735128		4.54	0.0006	0.07	1.55	2.9	<0.2	<10	90	0.29	0.11	0.68	0.36	18.55	18.6	111
K735129		3.87	0.0004	0.04	0.75	2.5	<0.2	<10	140	0.17	0.08	0.47	0.21	16.15	9.5	21
K735130		4.94	0.0012	0.04	0.74	2.4	<0.2	<10	170	0.17	0.11	0.55	0.32	17.35	9.2	23
K735131		6.99	0.0019	0.04	0.67	5.1	<0.2	<10	100	0.18	0.09	0.47	0.17	19.10	8.4	21
K735151		4.57	0.0164	0.07	1.15	15.1	<0.2	<10	50	0.29	0.22	0.73	0.24	30.0	9.4	25
K735152		6.17	0.0021	0.05	1.08	10.9	<0.2	<10	40	0.32	0.17	0.96	0.20	23.2	6.8	20
K735153		5.25	0.0022	0.11	0.49	6.2	<0.2	<10	60	0.16	0.15	1.56	0.35	17.55	6.7	15
K735154		5.52	0.0007	0.19	0.61	5.7	<0.2	<10	150	0.15	0.19	3.73	1.12	27.5	7.4	24
K735155		6.74	0.0021	0.34	1.48	13.6	<0.2	<10	150	0.40	0.20	1.06	1.19	29.9	16.0	86
K735156		6.31	0.0066	0.25	1.42	10.2	<0.2	<10	160	0.30	0.17	1.30	1.05	28.3	14.6	79
K735157		5.30	0.0011	0.15	1.78	7.3	<0.2	<10	250	0.38	0.16	0.61	1.07	25.4	13.4	70
K735158		4.52	0.0014	0.10	1.67	7.1	<0.2	<10	150	0.41	0.22	0.87	0.78	21.2	12.1	54
K735159		7.41	0.0006	0.06	0.72	4.9	<0.2	<10	50	0.30	0.22	0.37	0.19	33.1	4.3	16
K735160		6.71	0.0012	0.07	0.84	9.2	<0.2	<10	90	0.35	0.31	0.43	0.41	31.9	5.4	15
K735161		5.72	0.0040	0.06	0.97	5.0	<0.2	<10	60	0.68	0.67	0.29	0.29	37.3	5.5	16
K735162		5.85	>0.1000	0.24	1.12	22.6	<0.2	<10	160	0.42	0.31	0.87	1.34	21.6	13.0	36
K735163		6.14	0.0517	0.23	1.77	21.6	<0.2	<10	170	0.61	0.57	0.51	1.44	19.40	12.0	48
K735164		5.19	0.0015	0.07	0.88	9.6	<0.2	<10	50	0.19	0.18	0.45	0.44	31.6	11.4	21
K735165		0.16	0.0013	0.13	1.02	3.4	<0.2	<10	60	0.21	0.07	0.57	0.14	9.31	7.0	30

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
K735110		4.92	21.6	2.64	5.76	0.09	0.03	0.02	0.019	0.22	18.8	26.8	1.15	317	2.53	0.03
K735111		1.56	5.3	1.40	3.17	0.07	<0.02	<0.01	0.012	0.14	19.4	13.2	0.40	206	0.59	0.02
K735112		1.59	5.0	1.35	3.24	0.07	0.02	<0.01	0.009	0.14	19.9	13.3	0.39	204	0.46	0.02
K735113		5.53	17.3	2.32	4.21	0.07	0.02	0.01	0.017	0.23	13.8	17.2	0.67	233	2.12	0.03
K735114		3.48	18.5	1.89	3.74	0.08	0.02	0.01	0.013	0.19	13.8	16.2	0.57	215	2.19	0.03
K735115		2.35	79.3	2.26	3.24	0.07	0.19	2.25	0.640	0.15	15.2	6.0	3.30	1630	78.9	<0.01
K735116		1.05	16.0	1.80	2.59	0.06	0.02	0.01	0.011	0.08	13.8	8.7	0.57	363	0.65	0.01
K735117		0.84	11.6	1.46	2.03	0.06	0.04	<0.01	0.012	0.07	14.0	6.7	0.52	247	0.43	0.01
K735118		0.63	14.2	1.59	2.10	<0.05	0.03	0.01	0.010	0.06	13.5	6.2	0.42	258	0.56	0.01
K735119		0.58	19.1	1.94	2.62	0.06	0.03	0.01	0.010	0.05	14.7	7.7	0.60	328	0.64	<0.01
K735120		0.63	14.6	1.83	2.49	0.05	0.02	0.01	0.008	0.05	13.8	7.6	0.49	274	0.49	<0.01
K735121		0.49	18.4	2.05	2.48	0.07	0.03	0.01	0.011	0.05	16.8	7.2	0.56	380	0.60	<0.01
K735122		0.43	18.9	2.28	2.66	0.05	0.03	0.01	0.012	0.04	15.5	7.1	0.49	449	0.82	<0.01
K735123		2.33	23.1	2.28	3.26	0.12	0.02	0.04	0.023	0.12	12.9	17.5	1.30	443	1.88	<0.01
K735124		1.72	50.2	2.95	3.29	0.09	0.02	0.02	0.024	0.04	9.6	10.8	0.88	443	0.78	<0.01
K735125		2.22	35.5	2.11	2.19	0.10	0.04	0.03	0.024	0.06	9.7	7.1	0.77	387	5.87	<0.01
K735126		1.95	28.8	2.24	3.04	0.11	0.02	0.02	0.019	0.09	10.6	13.5	1.01	359	2.30	<0.01
K735127		1.02	41.7	2.75	3.00	0.10	0.04	0.02	0.031	0.05	13.1	14.2	0.54	504	6.63	<0.01
K735128		2.18	49.6	2.69	4.54	0.12	0.03	0.04	0.020	0.17	7.8	14.5	1.29	520	0.99	<0.01
K735129		0.61	22.0	1.72	2.44	0.09	0.02	<0.01	0.012	0.09	7.0	6.2	0.56	329	0.58	<0.01
K735130		0.59	24.8	2.22	2.16	0.10	0.02	0.01	0.012	0.13	7.8	5.1	0.52	371	0.69	<0.01
K735131		0.58	16.6	1.67	2.31	0.09	0.03	0.01	0.012	0.11	8.4	5.8	0.44	299	0.66	<0.01
K735151		1.54	15.9	1.94	3.56	0.10	0.04	0.01	0.012	0.12	13.1	11.5	0.55	267	0.53	0.01
K735152		1.74	11.6	1.66	3.54	0.09	0.02	0.01	0.014	0.13	10.2	13.4	0.56	216	0.54	0.02
K735153		0.82	14.0	1.18	1.62	0.08	0.05	0.02	0.010	0.07	7.8	6.5	0.43	274	1.11	<0.01
K735154		0.87	23.5	1.47	1.78	0.10	0.04	0.02	0.012	0.05	13.0	7.2	1.07	231	4.49	<0.01
K735155		1.83	42.3	2.78	4.36	0.13	0.04	0.01	0.017	0.16	15.1	16.8	1.37	432	4.86	0.02
K735156		2.05	39.7	2.63	4.03	0.12	0.04	0.01	0.014	0.17	12.7	14.5	1.33	404	4.15	0.02
K735157		2.66	29.0	2.68	5.30	0.12	0.03	0.01	0.022	0.22	11.4	18.7	1.12	618	3.14	0.02
K735158		3.71	27.3	2.41	4.82	0.11	0.02	0.01	0.015	0.20	9.5	17.8	1.03	396	1.80	0.03
K735159		2.19	6.4	1.26	2.98	0.10	0.02	0.02	0.011	0.05	15.4	21.5	0.32	259	1.07	<0.01
K735160		1.84	8.3	1.92	3.42	0.10	0.02	0.02	0.012	0.07	14.6	22.0	0.31	643	0.60	<0.01
K735161		2.32	14.9	1.62	3.65	0.11	0.02	0.02	0.015	0.10	15.5	26.7	0.28	364	0.72	<0.01
K735162		2.47	36.7	2.51	3.42	0.11	0.02	0.01	0.018	0.12	10.3	15.1	0.95	380	3.93	<0.01
K735163		3.52	34.7	2.55	5.33	0.13	0.04	0.01	0.025	0.19	8.8	18.2	1.04	507	3.33	0.04
K735164		0.65	22.8	2.39	2.51	0.09	0.04	0.02	0.011	0.06	15.5	9.8	0.44	786	0.58	<0.01
K735165		0.30	20.6	1.88	3.66	0.11	0.25	0.02	0.015	0.06	4.3	7.4	0.45	298	3.92	0.03

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
K735110		1.29	33.7	1290	9.9	23.4	0.001	0.02	1.56	3.7	1.0	0.6	46.2	<0.01	0.03	5.7
K735111		0.95	10.7	2560	7.3	18.9	<0.001	<0.01	0.14	1.6	0.4	0.4	109.5	<0.01	0.01	7.4
K735112		0.92	10.1	2550	7.7	19.0	<0.001	<0.01	0.12	1.6	0.6	0.4	111.5	<0.01	<0.01	7.0
K735113		1.35	25.3	1810	7.4	20.0	<0.001	0.02	0.72	3.2	1.1	0.6	53.1	<0.01	0.03	5.0
K735114		1.12	23.3	1390	8.5	18.6	<0.001	0.02	0.91	2.8	1.2	0.5	70.3	<0.01	0.02	5.0
K735115		0.06	81.1	1110	21.2	11.9	0.053	0.94	7.66	3.8	3.6	3.1	213	<0.01	0.39	3.4
K735116		0.68	20.9	740	10.4	8.1	0.001	0.01	0.27	1.5	0.4	0.2	40.3	<0.01	0.02	4.3
K735117		0.56	16.3	750	8.2	6.5	0.001	<0.01	0.21	1.2	0.5	0.2	102.0	<0.01	0.01	4.1
K735118		0.41	17.4	650	7.3	5.0	<0.001	<0.01	0.19	1.2	0.4	0.2	42.9	<0.01	0.02	3.9
K735119		0.38	24.1	730	10.2	5.0	<0.001	0.01	0.34	1.6	0.8	0.2	30.2	<0.01	0.03	4.0
K735120		0.55	19.9	710	8.1	5.7	<0.001	0.01	0.31	1.4	0.6	0.2	33.1	<0.01	0.02	3.7
K735121		0.28	24.1	700	16.2	4.4	<0.001	0.01	0.29	1.4	0.6	<0.2	18.9	<0.01	0.03	4.8
K735122		0.28	27.2	770	19.9	4.3	<0.001	<0.01	0.49	1.5	0.5	0.2	13.8	<0.01	0.02	3.5
K735123		1.21	33.0	1220	16.2	13.3	0.001	0.09	0.61	3.0	1.3	0.4	34.2	<0.01	0.03	4.2
K735124		0.40	43.7	560	23.9	5.9	0.002	0.02	0.71	4.4	0.6	0.2	27.1	<0.01	0.04	2.9
K735125		0.39	47.6	800	14.3	6.6	0.001	0.04	4.25	2.6	1.8	0.4	24.8	<0.01	0.05	2.6
K735126		0.92	33.5	1150	13.4	9.9	0.001	0.05	1.85	3.2	0.9	0.3	26.6	<0.01	0.02	3.9
K735127		0.63	49.4	830	13.2	6.7	0.001	0.02	1.82	2.7	1.8	0.3	30.1	<0.01	0.07	3.2
K735128		0.79	100.0	860	5.0	18.8	<0.001	0.02	0.22	5.9	0.5	0.3	22.3	<0.01	0.05	2.3
K735129		0.50	20.2	960	3.6	8.6	0.001	0.02	0.19	2.1	0.5	0.2	17.1	<0.01	0.03	2.1
K735130		0.55	17.9	1320	3.9	10.8	<0.001	0.03	0.21	2.1	0.4	0.2	23.3	<0.01	0.05	2.1
K735131		0.66	20.3	1050	3.8	8.4	0.001	0.01	0.29	2.2	0.3	0.2	31.7	<0.01	0.02	2.7
K735151		1.11	23.2	800	9.9	14.6	<0.001	0.02	0.19	2.3	0.5	0.4	39.4	<0.01	0.01	3.3
K735152		1.12	18.1	740	7.3	15.3	<0.001	0.01	0.25	2.4	<0.2	0.5	49.4	<0.01	0.01	3.5
K735153		0.54	19.9	970	5.6	6.7	0.001	0.03	0.41	1.5	0.6	0.2	40.4	<0.01	0.02	2.8
K735154		0.43	51.4	900	7.9	6.1	0.001	0.02	1.10	1.5	0.8	<0.2	107.0	<0.01	0.03	3.7
K735155		0.58	102.0	890	9.5	13.8	0.001	0.04	0.59	3.6	2.3	0.4	48.9	<0.01	0.06	4.7
K735156		0.62	88.5	930	9.0	13.4	0.001	0.03	0.57	3.4	1.7	0.4	50.9	<0.01	0.04	4.3
K735157		1.03	54.0	990	7.7	21.7	0.001	0.04	0.28	5.2	1.1	0.5	32.9	<0.01	0.02	2.9
K735158		1.02	40.6	970	6.7	20.6	<0.001	0.03	0.35	4.2	1.2	0.4	50.5	<0.01	0.01	2.7
K735159		1.28	11.6	1280	4.9	9.4	<0.001	0.01	0.16	1.7	0.4	0.6	12.9	<0.01	0.01	4.9
K735160		1.68	12.0	1160	6.2	15.7	<0.001	0.02	0.19	2.1	0.3	0.8	17.3	<0.01	0.01	3.3
K735161		1.38	14.2	1200	7.7	16.0	<0.001	0.01	0.41	2.1	0.2	0.7	10.5	<0.01	0.01	4.9
K735162		0.81	47.9	920	12.7	13.4	0.001	0.12	1.76	3.6	2.0	0.5	33.4	<0.01	0.05	3.3
K735163		0.77	54.7	680	13.5	19.1	0.001	0.03	0.44	4.6	0.9	0.7	40.7	<0.01	0.04	3.4
K735164		0.38	36.2	630	13.0	6.0	<0.001	0.02	0.27	1.7	0.7	0.2	25.9	<0.01	0.04	2.7
K735165		0.29	21.3	490	2.2	2.8	0.001	0.04	0.31	3.8	0.5	0.4	26.4	<0.01	0.02	0.9

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	Au- OG44
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr	Au
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5	0.01
K735110		0.068	0.23	2.10	65	1.23	10.65	133	1.0	
K735111		0.045	0.12	1.22	19	7.01	13.30	37	<0.5	
K735112		0.044	0.13	1.20	18	0.30	13.55	34	<0.5	
K735113		0.070	0.21	1.94	68	4.06	9.59	139	0.7	
K735114		0.056	0.19	1.68	51	1.24	9.02	140	0.9	
K735115		<0.005	1.03	14.15	148	16.40	20.5	422	8.1	
K735116		0.027	0.08	0.68	19	0.20	5.17	44	1.1	
K735117		0.020	0.06	0.46	15	0.46	5.93	33	1.5	
K735118		0.020	0.05	0.43	15	0.31	4.66	35	1.5	
K735119		0.021	0.05	0.54	19	0.33	5.23	46	1.1	0.06
K735120		0.025	0.05	0.58	19	0.50	5.17	41	1.0	
K735121		0.017	0.05	0.67	17	0.14	4.79	47	1.2	
K735122		0.018	0.04	0.72	21	0.86	4.80	61	0.9	
K735123		0.056	0.16	2.91	37	1.09	7.93	125	0.7	
K735124		0.036	0.08	0.50	46	0.08	5.07	302	0.7	
K735125		0.022	0.09	1.32	38	0.27	6.53	198	1.2	
K735126		0.048	0.12	1.40	40	0.57	6.91	125	1.0	
K735127		0.034	0.08	1.03	35	0.23	6.01	138	2.0	
K735128		0.085	0.15	0.67	63	0.30	5.45	65	1.2	
K735129		0.048	0.06	0.49	30	0.32	4.74	49	0.8	
K735130		0.048	0.06	0.60	38	1.09	5.37	54	0.6	
K735131		0.051	0.05	0.47	33	0.14	4.61	38	1.1	
K735151		0.048	0.14	1.15	34	1.89	6.92	62	1.1	
K735152		0.049	0.12	0.74	31	2.03	5.64	50	0.8	
K735153		0.032	0.07	0.82	21	0.29	6.10	40	1.9	
K735154		0.023	0.08	1.30	24	0.15	8.28	116	1.8	
K735155		0.053	0.17	1.34	51	0.23	7.61	120	2.0	
K735156		0.057	0.16	1.65	53	0.87	7.10	110	1.8	
K735157		0.072	0.22	0.92	80	1.15	6.77	112	0.8	
K735158		0.073	0.21	1.00	61	0.42	6.08	95	0.6	
K735159		0.043	0.09	10.55	24	0.36	8.82	51	<0.5	
K735160		0.050	0.14	9.25	26	0.26	9.19	67	0.6	
K735161		0.052	0.15	13.55	28	0.49	10.35	55	0.6	
K735162		0.044	0.19	1.93	45	1.39	7.25	148	1.2	0.07
K735163		0.059	0.32	1.72	65	4.74	5.23	121	1.2	
K735164		0.021	0.05	1.24	21	0.09	6.51	77	1.1	
K735165		0.104	0.06	0.27	45	10.10	6.18	35	6.8	

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 1- AUG- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11100820

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non- sufficient sample.
ME- MS41	Interference: Ca> 10% on ICP- MS As,ICP- AES results shown.
ME- MS41	Gold determinations by this method are semi- quantitative due to the small sample weight used (0.5g).

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

CERTIFICATE WH11105622

Project: Stream seds

P.O. No.: GPD2011LIV002

This report is for 116 Stream Sediment samples submitted to our lab in Whitehorse, YT, Canada on 11- JUN- 2011.

The following have access to data associated with this certificate:

MIKE BURKE LINDA LEWIS	ANDREW CALDWELL MIKE MASLOWSKI	JACK COTE

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI- 21	Received Sample Weight
TRA- 21	Transfer sample
DRY- 22	Drying - Maximum Temp 60C
LOG- 21d	Sample logging - ClientBarCode Dup
SPL- 34	Pulp Splitting Charge
LOG- 22	Sample login - Rcd w/o BarCode
LOG- 23	Pulp Login - Rcvd with Barcode
SCR- 41	Screen to - 180um and save both

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au- OG44	Ore Grade Au - 50g AR	ICP- MS
Au- ST44	Super Trace Au - 50g AR	ICP- MS
ME- MS41	51 anal. aqua regia ICPMS	

To: GOLDEN PREDATOR CANADA CORP.
ATTN: JACK COTE
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Sample Description	Method Analyte Units LOR	WEI- 21 Recvd Wt. kg 0.02	Au- ST44 Au ppm 0.0001	ME- MS41 Ag ppm 0.01	ME- MS41 Al % 0.01	ME- MS41 As ppm 0.1	ME- MS41 Au ppm 0.2	ME- MS41 B ppm 10	ME- MS41 Ba ppm 10	ME- MS41 Be ppm 0.05	ME- MS41 Bi ppm 0.01	ME- MS41 Ca % 0.01	ME- MS41 Cd ppm 0.01	ME- MS41 Ce ppm 0.02	ME- MS41 Co ppm 0.1	ME- MS41 Cr ppm 1
K735036		5.58	0.0002	0.09	0.94	3.1	<0.2	<10	60	0.17	0.11	0.57	0.51	22.1	12.8	47
K735037		4.68	0.0015	0.09	1.69	3.5	<0.2	<10	250	0.28	0.07	0.79	0.33	14.35	22.0	53
K735038		5.42	0.0030	0.13	0.93	9.3	<0.2	<10	110	0.24	0.10	0.62	1.13	19.75	13.5	35
K735039		6.74	0.0016	0.09	1.03	5.2	<0.2	<10	70	0.29	0.13	0.49	0.42	20.8	11.5	18
K735040		6.88	0.0011	0.10	0.75	3.6	<0.2	<10	50	0.14	0.08	0.37	0.38	17.55	8.8	17
K735041		6.18	0.0026	0.13	1.03	5.0	<0.2	<10	70	0.20	0.11	0.57	0.70	19.85	13.5	49
K735042		5.66	0.0005	0.06	0.84	1.7	<0.2	<10	60	0.21	0.13	0.50	0.38	20.4	9.8	37
K735043		4.40	0.0007	0.08	1.34	7.3	<0.2	<10	60	0.57	0.56	0.57	0.25	27.9	13.2	56
K735044		10.78	0.0001	0.06	0.85	12.1	<0.2	<10	50	0.54	0.40	0.56	0.13	25.2	5.9	14
K735045		<0.02	0.0002	0.05	0.86	12.3	<0.2	<10	50	0.57	0.62	0.53	0.14	25.8	5.9	14
K735046		6.06	<0.0001	0.03	0.87	3.9	<0.2	<10	30	0.42	0.66	0.78	0.12	23.8	5.4	15
K735047		3.78	0.0007	0.23	2.08	51.4	<0.2	<10	110	1.79	1.36	0.96	0.41	28.7	12.9	34
K735048		5.12	0.0004	0.06	1.32	12.8	<0.2	<10	40	0.65	0.60	0.59	0.20	28.7	10.3	44
K735049		4.68	0.0062	0.04	0.93	3.1	<0.2	<10	30	0.72	0.65	0.48	0.15	25.2	4.7	15
K735050		5.64	0.0201	0.11	0.81	14.5	<0.2	<10	100	0.34	0.44	1.17	0.41	18.10	8.8	65
K735087		4.38	0.0001	0.27	1.05	6.9	<0.2	<10	120	0.31	0.25	1.38	2.01	30.8	8.7	21
K735088		5.54	0.0005	0.34	1.02	11.5	<0.2	<10	120	0.28	0.16	1.96	2.66	28.1	10.1	18
K735089		5.72	0.0001	0.45	1.19	4.4	<0.2	<10	110	0.41	0.25	1.06	3.00	33.1	9.2	19
K735090		5.04	0.0003	0.63	1.11	18.7	<0.2	<10	90	0.51	0.24	1.46	3.17	43.8	10.8	16
K735091		4.52	0.0002	0.38	1.63	5.5	<0.2	<10	160	0.53	0.24	1.14	3.80	42.2	14.7	30
K735092		5.92	<0.0001	0.26	1.26	3.8	<0.2	<10	350	0.42	0.21	0.78	1.57	29.4	10.8	36
K735093		4.46	<0.0001	0.09	1.01	2.5	<0.2	<10	90	0.35	0.31	0.53	1.50	26.6	7.7	27
K735094		9.16	0.0001	0.13	1.15	2.6	<0.2	<10	90	0.39	0.17	0.55	1.26	25.7	8.7	39
K735095		<0.02	0.0008	0.12	1.15	2.1	<0.2	<10	80	0.29	0.15	0.52	1.18	22.8	8.0	40
K735096		4.20	<0.0001	0.04	1.06	1.1	<0.2	<10	60	0.41	0.22	0.44	0.09	33.7	5.2	13
K735097		4.82	0.0001	0.03	0.68	1.5	<0.2	<10	40	0.52	0.33	0.36	0.05	24.2	4.1	12
K735098		5.28	0.0032	0.05	0.60	11.5	<0.2	<10	90	0.32	0.37	0.85	0.19	13.70	4.7	26
K735099		6.28	0.0051	0.08	0.66	9.0	<0.2	<10	170	0.29	0.15	0.67	0.18	23.3	14.0	17
K735100		5.32	0.0018	0.03	0.65	5.7	<0.2	<10	60	0.24	0.10	0.33	0.08	16.65	5.5	16
K735132		6.68	0.0001	0.17	1.14	4.7	<0.2	<10	130	0.34	0.17	0.71	1.78	25.3	10.7	32
K735133		7.36	0.0002	0.05	0.83	1.4	<0.2	<10	130	0.20	0.09	0.49	0.24	16.15	7.2	28
K735134		6.16	0.0014	0.08	0.81	2.3	<0.2	<10	140	0.26	0.10	0.57	0.42	23.6	7.4	27
K735135		5.00	0.0005	0.07	0.92	1.6	<0.2	<10	340	0.21	0.07	0.66	0.46	14.35	8.6	47
K735136		4.68	0.0019	0.13	1.13	3.8	<0.2	<10	90	0.29	0.11	0.60	0.83	21.7	11.6	35
K735137		4.72	0.0010	0.12	1.70	4.5	<0.2	<10	80	0.31	0.11	0.72	0.93	22.7	18.9	72
K735138		6.16	0.0008	0.14	1.04	4.2	<0.2	<10	80	0.27	0.11	0.55	0.59	25.3	11.0	27
K735139		5.68	0.0013	0.11	1.29	3.8	<0.2	<10	70	0.35	0.15	0.43	0.79	29.1	9.1	23
K735140		6.92	0.0096	0.19	0.98	13.7	<0.2	<10	130	0.27	0.18	0.67	0.36	14.55	20.5	216
K735141		7.12	0.0082	0.19	1.07	13.7	<0.2	<10	220	0.37	0.34	0.96	0.50	18.60	13.9	110
K735142		6.62	0.0006	0.05	0.86	1.8	<0.2	<10	120	0.20	0.09	0.51	0.15	17.35	10.2	68

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
K735036		1.59	26.5	2.11	4.02	0.10	0.03	0.01	0.012	0.11	10.6	11.9	0.69	237	0.98	0.01
K735037		1.67	41.6	3.50	6.49	0.11	0.02	0.01	0.013	0.35	7.1	16.5	1.44	523	0.84	0.01
K735038		1.35	29.0	2.51	4.42	0.10	0.02	0.01	0.011	0.10	9.5	14.2	0.73	406	3.19	<0.01
K735039		1.41	30.0	2.20	4.83	0.10	0.02	0.01	0.015	0.14	9.8	13.7	0.70	320	1.03	<0.01
K735040		0.69	19.0	1.92	2.67	0.07	0.03	0.02	0.011	0.06	8.3	7.9	0.51	239	1.03	0.01
K735041		1.70	29.4	2.44	3.55	0.09	0.03	0.02	0.014	0.12	9.6	12.8	0.77	277	1.28	0.01
K735042		1.90	14.0	1.59	3.25	0.07	0.02	0.01	0.012	0.10	10.7	13.7	0.56	193	0.61	0.02
K735043		6.05	25.3	2.37	4.84	0.11	0.03	0.04	0.018	0.18	13.9	42.7	0.92	310	0.57	0.03
K735044		7.42	10.4	1.59	3.53	0.08	0.03	0.02	0.014	0.22	12.6	42.8	0.36	186	0.36	0.02
K735045		7.32	10.7	1.59	3.60	0.09	0.03	0.01	0.014	0.23	12.8	42.5	0.37	194	0.34	0.02
K735046		4.81	11.3	1.49	3.38	0.11	0.03	0.05	0.012	0.24	10.9	31.2	0.36	174	0.27	0.01
K735047		15.65	30.6	3.01	7.18	0.16	<0.02	0.03	0.031	0.36	13.3	92.3	0.76	309	0.82	0.03
K735048		9.09	18.7	2.34	4.77	0.12	0.02	0.02	0.019	0.31	13.5	51.8	0.71	283	0.45	0.01
K735049		9.76	8.6	1.30	3.68	0.12	<0.02	0.01	0.017	0.28	10.7	52.7	0.36	190	0.30	<0.01
K735050		3.14	15.6	1.77	2.78	0.10	<0.02	0.02	0.015	0.10	8.5	21.5	0.97	347	0.29	<0.01
K735087		2.88	25.2	1.78	3.16	0.13	0.02	0.02	0.016	0.20	16.5	12.1	1.13	282	4.72	<0.01
K735088		1.37	42.0	2.05	3.30	0.11	0.02	0.01	0.020	0.18	13.6	11.6	1.34	434	6.06	<0.01
K735089		2.82	23.3	2.01	3.59	0.12	0.02	0.02	0.017	0.20	18.1	14.2	0.98	233	4.57	<0.01
K735090		2.98	39.7	2.50	3.49	0.13	<0.02	0.02	0.027	0.27	23.6	15.7	1.27	278	14.45	<0.01
K735091		5.59	41.1	3.28	6.28	0.14	0.03	0.03	0.033	0.40	21.8	24.5	1.36	395	6.13	0.01
K735092		2.16	25.2	2.90	4.44	0.20	0.02	0.02	0.023	0.21	15.4	15.5	0.86	349	2.34	0.02
K735093		2.19	15.9	1.88	3.49	0.17	<0.02	0.02	0.015	0.13	14.7	15.9	0.58	266	1.13	0.01
K735094		2.51	15.3	2.07	3.88	0.18	<0.02	0.02	0.018	0.16	14.9	18.5	0.66	242	1.02	0.01
K735095		2.36	13.6	1.97	3.62	0.10	<0.02	0.01	0.015	0.16	12.7	16.8	0.62	235	0.86	0.01
K735096		3.74	6.8	1.51	3.99	0.13	<0.02	0.01	0.011	0.25	19.3	25.8	0.44	195	0.32	0.01
K735097		3.39	7.4	1.28	2.67	0.10	<0.02	0.01	0.007	0.07	13.0	23.1	0.36	201	0.61	0.01
K735098		3.69	9.9	1.13	2.11	0.09	0.02	<0.01	0.007	0.09	7.0	13.8	0.62	182	0.17	0.02
K735099		2.06	26.9	2.82	2.22	0.10	0.02	0.02	0.015	0.07	11.5	8.8	0.49	1550	0.80	0.01
K735100		2.00	10.1	1.33	2.21	0.08	<0.02	0.01	0.007	0.06	9.6	10.6	0.41	202	0.36	0.01
K735132		2.44	26.0	2.16	3.60	0.13	0.02	0.03	0.014	0.17	14.6	13.3	0.91	310	2.91	0.02
K735133		1.26	13.6	1.55	2.85	0.10	<0.02	0.01	0.009	0.13	9.0	9.7	0.54	211	0.47	0.01
K735134		1.00	19.6	1.73	2.52	0.11	0.02	0.03	0.010	0.11	13.3	8.1	0.49	436	0.64	0.01
K735135		0.90	24.4	1.81	2.97	0.10	0.02	0.02	0.011	0.12	7.9	8.5	0.69	303	0.47	0.02
K735136		1.07	30.2	2.28	3.30	0.11	0.02	0.01	0.014	0.13	11.4	9.9	0.77	521	1.15	0.01
K735137		1.62	43.7	3.29	4.85	0.13	0.03	0.01	0.018	0.19	11.9	14.7	1.29	665	1.26	0.01
K735138		1.15	25.6	2.57	3.26	0.11	0.03	0.01	0.013	0.16	13.1	9.2	0.70	369	1.52	0.01
K735139		1.49	23.7	2.25	3.96	0.11	0.02	0.01	0.016	0.16	14.9	12.8	0.75	376	0.88	0.01
K735140		1.50	32.8	2.68	2.96	0.11	0.02	0.02	0.013	0.07	7.1	12.6	1.94	466	0.15	0.01
K735141		2.50	22.9	2.42	3.50	0.11	<0.02	0.01	0.014	0.10	9.8	22.9	1.31	511	0.24	0.02
K735142		1.15	12.2	2.16	2.86	0.09	<0.02	<0.01	0.010	0.07	8.9	10.1	0.71	350	0.64	0.01

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
K735036		0.83	74.8	1640	3.9	14.5	<0.001	0.03	0.24	3.4	0.9	0.4	16.5	<0.01	0.01	3.7
K735037		1.00	35.8	1860	4.5	22.5	<0.001	0.02	0.31	5.0	0.6	0.2	21.6	<0.01	0.02	2.4
K735038		0.81	44.4	1650	6.7	13.6	0.001	0.01	0.51	3.4	1.4	0.2	24.7	<0.01	0.03	2.9
K735039		0.70	23.1	1380	6.7	18.2	0.001	0.04	0.24	3.4	0.7	0.3	18.9	<0.01	0.03	3.4
K735040		0.64	20.8	940	5.3	7.0	0.001	0.02	0.29	2.2	0.6	0.2	15.2	<0.01	0.02	2.5
K735041		0.84	68.2	1410	4.6	13.8	0.001	0.17	0.33	3.4	1.7	0.4	17.0	<0.01	0.03	3.8
K735042		1.02	65.6	1460	4.0	17.9	<0.001	0.01	0.16	2.4	0.5	0.5	14.7	<0.01	0.01	3.3
K735043		1.46	78.3	1200	5.2	24.7	<0.001	0.02	0.62	3.8	0.7	0.8	30.6	<0.01	0.02	4.3
K735044		1.03	11.0	1790	4.3	27.3	<0.001	0.01	3.74	2.6	0.4	0.9	23.9	<0.01	0.01	4.1
K735045		1.01	11.5	1700	4.2	28.0	<0.001	0.01	2.44	2.7	0.4	0.9	23.6	<0.01	0.01	4.3
K735046		1.44	9.3	2780	2.9	24.7	<0.001	0.02	0.50	2.6	0.6	0.8	27.7	<0.01	0.01	3.9
K735047		2.67	28.3	1330	16.3	52.0	<0.001	0.04	6.61	5.6	0.4	2.0	84.4	<0.01	0.02	3.5
K735048		1.34	35.6	1950	5.2	37.7	<0.001	0.02	2.22	3.9	0.6	1.1	24.3	<0.01	0.01	4.6
K735049		2.27	9.7	1790	3.4	40.5	0.001	0.02	0.43	2.4	0.5	2.3	12.0	<0.01	<0.01	3.6
K735050		1.29	95.3	1260	7.8	16.7	<0.001	0.02	0.41	2.6	0.5	0.6	25.6	<0.01	0.01	2.5
K735087		0.98	40.7	2230	9.4	16.9	0.005	0.05	0.99	2.1	1.9	0.3	37.0	<0.01	0.04	4.2
K735088		1.08	40.8	2060	10.9	16.2	0.003	0.07	1.90	2.6	1.8	0.4	60.2	<0.01	0.05	3.3
K735089		1.05	44.8	1950	19.5	23.2	0.002	0.06	1.08	2.5	1.8	0.6	31.6	<0.01	0.04	4.5
K735090		1.30	72.5	1950	16.1	23.7	0.006	0.44	3.62	2.5	3.9	0.6	35.5	<0.01	0.07	4.6
K735091		1.17	56.7	2430	14.6	37.1	0.003	0.14	0.77	4.5	3.2	0.9	33.1	<0.01	0.05	6.1
K735092		1.66	48.0	2200	10.2	19.6	0.001	0.06	0.61	4.3	1.9	0.7	22.9	<0.01	0.04	4.7
K735093		1.54	33.5	1540	5.8	19.1	<0.001	0.01	0.36	2.7	1.0	0.6	16.1	<0.01	0.02	3.5
K735094		1.49	75.0	1710	5.8	25.2	<0.001	0.01	0.23	3.3	0.8	0.7	17.8	<0.01	0.01	3.3
K735095		1.22	72.6	1770	5.5	22.8	<0.001	0.01	0.24	2.9	0.8	0.6	16.3	<0.01	0.02	3.2
K735096		1.67	9.4	1560	4.8	31.7	<0.001	0.01	0.15	2.0	0.7	0.8	15.6	<0.01	0.01	3.3
K735097		1.89	6.7	1180	3.1	15.9	<0.001	0.01	0.12	1.5	0.3	0.9	14.4	<0.01	0.02	3.3
K735098		0.87	23.1	900	6.1	14.9	<0.001	0.01	0.32	1.6	0.5	0.4	21.9	<0.01	0.02	2.1
K735099		0.51	18.3	1370	6.1	8.4	0.002	0.14	0.99	3.8	0.7	0.3	25.0	<0.01	0.04	3.3
K735100		0.60	11.8	920	3.5	7.7	<0.001	0.01	0.31	1.6	0.6	0.3	15.1	<0.01	0.01	1.7
K735132		1.07	58.5	1470	8.2	18.3	0.002	0.03	0.58	2.6	1.5	0.4	25.2	<0.01	0.03	3.9
K735133		1.02	29.1	970	3.8	17.1	<0.001	0.01	0.20	2.1	0.3	0.4	27.9	<0.01	0.01	2.4
K735134		0.73	27.2	1110	5.2	12.2	<0.001	0.03	0.21	2.5	0.8	0.3	38.0	<0.01	0.02	2.5
K735135		0.75	29.4	900	3.8	13.1	<0.001	0.04	0.17	2.4	0.9	0.2	27.1	<0.01	0.02	1.5
K735136		0.67	35.2	960	6.6	13.0	<0.001	0.03	0.27	3.0	1.1	0.2	26.3	<0.01	0.03	2.5
K735137		0.72	68.6	1070	7.3	18.0	0.001	0.05	0.19	5.2	1.4	0.3	31.0	<0.01	0.04	2.8
K735138		0.89	30.8	1220	8.2	15.8	<0.001	0.02	0.31	2.5	1.1	0.3	26.7	<0.01	0.03	3.6
K735139		0.83	27.8	950	8.3	19.2	<0.001	0.02	0.20	2.7	0.9	0.3	25.0	<0.01	0.03	3.4
K735140		0.45	224	1180	13.4	9.2	<0.001	0.01	0.44	3.6	0.5	0.3	21.8	<0.01	0.01	3.0
K735141		1.13	141.5	1370	10.9	16.3	<0.001	0.03	0.38	3.3	0.7	0.6	28.6	<0.01	0.02	2.3
K735142		0.87	67.5	1530	3.5	10.3	<0.001	0.01	0.12	2.3	0.8	0.4	17.5	<0.01	0.01	2.3

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	Au- OG44
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr	Au
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5	0.01
K735036		0.068	0.11	0.96	42	0.15	9.25	72	0.7	
K735037		0.122	0.10	0.41	93	0.11	4.34	89	<0.5	
K735038		0.055	0.09	0.77	59	0.37	6.18	118	0.5	
K735039		0.048	0.11	0.51	43	0.56	6.90	74	0.7	
K735040		0.038	0.05	0.46	34	0.10	4.58	68	1.0	
K735041		0.084	0.11	0.89	45	0.21	8.28	87	1.3	
K735042		0.067	0.12	0.89	35	0.19	8.06	59	<0.5	
K735043		0.081	0.16	1.36	40	6.49	8.85	57	0.9	
K735044		0.070	0.19	3.12	26	10.55	11.55	35	0.7	
K735045		0.072	0.19	2.93	26	10.95	10.85	35	0.8	
K735046		0.089	0.18	3.50	30	11.50	12.90	30	0.8	
K735047		0.124	0.37	12.75	60	14.85	9.05	98	0.5	
K735048		0.102	0.25	2.34	41	21.1	11.35	46	0.9	
K735049		0.076	0.31	3.78	20	9.43	12.00	35	<0.5	
K735050		0.053	0.12	0.85	26	6.07	8.62	44	0.6	
K735087		0.050	0.18	2.40	112	0.29	9.89	252	0.8	
K735088		0.060	0.13	2.21	63	0.59	9.74	224	0.8	
K735089		0.053	0.27	3.29	109	3.07	10.15	374	0.7	
K735090		0.060	0.32	8.58	113	2.05	12.35	336	0.7	
K735091		0.120	0.33	6.48	138	0.38	15.00	418	0.9	
K735092		0.069	0.20	2.44	69	0.25	12.50	222	0.7	
K735093		0.063	0.16	1.56	43	0.22	9.68	113	<0.5	
K735094		0.078	0.17	1.67	47	0.37	11.85	121	<0.5	
K735095		0.077	0.16	1.51	47	0.58	10.50	119	<0.5	
K735096		0.093	0.20	3.63	26	0.25	11.15	34	<0.5	
K735097		0.051	0.11	7.23	23	0.44	9.47	23	<0.5	
K735098		0.038	0.14	0.67	21	2.05	6.50	24	0.6	
K735099		0.030	0.08	0.60	36	0.14	7.91	56	0.7	
K735100		0.034	0.06	1.44	21	1.16	4.37	33	<0.5	
K735132		0.062	0.19	2.47	72	0.26	9.30	186	0.6	
K735133		0.067	0.11	1.31	38	0.12	5.50	53	<0.5	
K735134		0.049	0.09	1.14	30	0.22	8.66	66	<0.5	
K735135		0.058	0.08	0.65	40	0.11	5.23	63	0.6	
K735136		0.056	0.10	0.88	45	0.21	6.69	89	0.8	
K735137		0.083	0.11	0.61	67	0.06	7.50	120	1.0	
K735138		0.059	0.11	0.72	44	0.09	6.47	83	1.1	
K735139		0.050	0.13	1.09	39	0.11	7.46	96	0.6	
K735140		0.056	0.08	0.58	44	1.85	5.89	45	0.7	
K735141		0.060	0.12	1.09	41	1.65	9.32	53	<0.5	
K735142		0.062	0.08	1.12	37	0.15	7.55	36	<0.5	

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

ALS Minerals

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Sample Description	Method Analyte Units LOR	WEI- 21 Recvd Wt. kg 0.02	Au- ST44 Au ppm 0.0001	ME- MS41 Ag ppm 0.01	ME- MS41 Al % 0.01	ME- MS41 As ppm 0.1	ME- MS41 Au ppm 0.2	ME- MS41 B ppm 10	ME- MS41 Ba ppm 10	ME- MS41 Be ppm 0.05	ME- MS41 Bi ppm 0.01	ME- MS41 Ca % 0.01	ME- MS41 Cd ppm 0.01	ME- MS41 Ce ppm 0.02	ME- MS41 Co ppm 0.1	ME- MS41 Cr ppm 1
K735143		6.24	0.0050	0.05	0.66	18.0	<0.2	<10	190	0.15	0.05	0.57	0.32	18.55	6.8	26
K735144		6.76	0.0005	0.05	1.20	2.5	<0.2	<10	130	0.30	0.13	0.50	0.28	19.65	14.9	114
K735145		0.18	0.0009	0.14	1.00	3.1	<0.2	<10	70	0.18	0.04	0.59	0.13	9.34	6.2	30
K735146		7.02	0.0005	0.09	0.88	1.7	<0.2	<10	110	0.20	0.10	0.48	0.37	20.6	10.5	55
K735147		4.08	0.0018	0.13	1.00	26.7	<0.2	<10	180	0.36	0.07	1.12	0.62	13.50	14.9	30
K735148		6.64	0.0032	0.12	0.91	14.3	<0.2	<10	240	0.30	0.06	4.64	0.75	12.80	11.4	32
K735149		7.98	0.0017	0.06	1.07	15.1	<0.2	<10	110	0.23	0.06	0.72	0.22	14.70	11.1	29
K735150		4.80	0.0026	0.16	0.76	29.3	<0.2	<10	200	0.31	0.07	2.65	0.81	9.85	15.4	31
K735166		4.52	0.0037	0.06	0.82	11.6	<0.2	<10	130	0.30	0.09	1.35	0.12	21.1	11.1	27
K735167		7.26	>0.1000	0.09	0.58	18.8	<0.2	<10	90	0.14	0.23	1.19	0.13	24.2	54.1	44
K735168		9.90	0.0109	0.05	0.72	18.2	<0.2	<10	70	0.17	0.14	0.87	0.09	35.3	12.8	32
K735169		<0.02	0.0090	0.07	0.71	18.9	<0.2	<10	70	0.17	0.18	0.88	0.10	35.5	13.0	31
K735170		4.50	0.0007	0.13	0.83	2.5	<0.2	<10	50	0.41	0.92	0.40	0.39	35.4	5.5	17
K735171		6.80	0.0006	0.06	0.77	7.3	<0.2	<10	90	0.32	0.33	0.56	0.36	31.6	9.0	28
K735172		6.94	0.0090	0.06	0.78	5.3	<0.2	<10	80	0.31	2.94	0.49	0.38	31.9	8.1	26
K735173		6.58	0.0008	0.06	0.78	2.2	<0.2	<10	140	0.18	0.11	0.41	0.80	17.35	8.0	34
K735174		8.14	0.0010	0.04	0.69	3.1	<0.2	<10	170	0.17	0.08	0.47	0.21	15.95	8.5	28
K735175		8.96	>0.1000	0.03	0.65	2.9	<0.2	<10	110	0.15	0.08	0.42	0.18	18.80	8.7	36
K735201		5.60	0.0026	0.09	1.74	10.1	<0.2	<10	200	0.47	0.07	0.74	0.42	27.0	14.7	41
K735202		5.34	0.0010	0.06	1.34	8.6	<0.2	<10	230	0.42	0.06	0.70	0.21	33.9	12.5	29
K735203		4.96	0.0010	0.05	1.67	22.0	<0.2	<10	250	0.47	0.06	0.77	0.24	26.5	14.2	32
K735204		6.16	0.0014	0.07	1.25	8.6	<0.2	<10	190	0.40	0.08	0.77	0.26	24.0	12.7	38
K735206		5.96	0.0217	0.07	1.59	8.0	<0.2	<10	170	0.34	0.07	0.96	0.35	20.3	17.3	49
K735207		5.36	0.0020	0.05	1.27	8.0	<0.2	<10	170	0.33	0.07	0.73	0.31	21.1	13.4	37
K735208		5.94	0.0011	0.04	1.66	6.4	<0.2	<10	140	0.30	0.04	0.96	0.22	20.6	18.2	52
K735209		6.38	0.0015	0.03	2.14	3.3	<0.2	<10	80	0.31	0.04	0.88	0.14	16.30	22.0	31
K735210		4.48	0.0009	0.06	1.27	7.2	<0.2	<10	130	0.26	0.06	1.02	0.34	15.60	15.0	40
K735211		4.96	0.0005	0.06	1.48	6.0	<0.2	<10	240	0.35	0.07	0.81	0.16	24.8	14.2	35
K735212		5.48	0.0005	0.07	1.21	3.5	<0.2	<10	100	0.41	0.28	0.67	0.35	46.7	12.2	48
K735213		4.46	<0.0001	0.07	1.16	2.6	<0.2	<10	80	0.70	0.26	0.42	2.43	33.8	21.2	32
K735214		5.96	0.0018	0.07	1.13	6.3	<0.2	<10	140	0.48	0.25	0.35	0.41	37.1	8.6	41
K735215		0.16	NSS	10.20	1.12	4130	2.4	<10	110	0.32	4.42	2.39	7.79	22.5	19.8	85
K735216		4.46	0.0014	0.06	0.75	3.1	<0.2	<10	110	0.24	0.19	0.41	0.23	29.1	6.9	29
K735217		7.32	0.0029	0.04	0.62	1.6	<0.2	<10	80	0.22	0.13	0.65	0.28	46.3	5.2	24
K735218		6.86	0.0004	0.03	0.66	2.1	<0.2	<10	100	0.22	0.10	0.55	0.26	51.9	5.6	19
K735251		4.68	>0.1000	0.06	0.90	20.0	<0.2	<10	70	0.27	0.16	0.50	0.10	42.2	14.7	40
K735252		5.44	0.0075	0.03	0.49	24.6	<0.2	<10	70	0.19	0.06	0.30	0.11	16.15	9.0	12
K735253		4.96	0.0045	0.08	0.79	47.6	<0.2	<10	230	0.32	0.16	0.43	0.24	35.2	10.2	19
K735254		3.56	0.0298	0.06	0.77	20.1	<0.2	<10	110	0.25	0.07	0.32	0.16	23.1	9.2	16
K735255		4.72	0.0030	0.06	1.34	7.9	<0.2	<10	180	0.59	0.07	0.80	0.19	29.8	13.1	32

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
K735143		0.54	7.3	1.81	2.24	0.10	<0.02	0.01	0.007	0.04	9.6	6.5	0.42	1290	0.56	0.01
K735144		2.21	20.1	2.46	4.35	0.11	<0.02	<0.01	0.013	0.13	10.8	16.7	1.13	452	0.59	0.02
K735145		0.28	19.0	1.89	3.49	0.12	0.23	0.02	0.013	0.07	4.1	6.7	0.46	293	3.74	0.05
K735146		1.16	14.9	1.62	2.75	0.10	<0.02	0.01	0.010	0.08	10.7	9.7	0.64	220	0.56	0.01
K735147		0.61	35.5	3.54	3.12	0.08	0.04	0.47	0.025	0.07	6.9	7.6	0.63	1460	2.96	0.02
K735148		0.59	32.9	3.07	2.83	0.10	0.05	0.18	0.019	0.07	7.4	6.4	0.67	516	2.75	0.02
K735149		0.54	22.0	2.69	3.48	0.09	0.03	0.29	0.018	0.04	7.7	9.5	0.65	342	0.99	0.02
K735150		0.48	48.6	3.66	2.30	0.09	0.04	7.03	0.024	0.07	4.6	5.1	0.46	799	6.70	0.02
K735166		0.60	31.5	2.23	2.60	0.10	0.04	0.03	0.011	0.12	10.6	6.1	0.58	1560	0.71	0.01
K735167		0.45	37.6	4.16	2.29	0.11	0.09	0.03	0.012	0.07	12.5	4.3	0.56	354	0.79	<0.01
K735168		0.63	20.9	2.35	3.07	0.09	0.11	0.03	0.014	0.06	17.1	6.3	0.64	705	0.57	<0.01
K735169		0.63	21.8	2.36	3.06	0.10	0.10	0.03	0.014	0.06	17.7	6.5	0.64	680	0.62	<0.01
K735170		3.91	7.2	1.46	3.69	0.08	0.02	0.01	0.017	0.09	19.2	38.2	0.33	210	0.79	<0.01
K735171		2.76	14.3	2.53	3.49	0.09	0.05	0.02	0.012	0.11	16.1	23.3	0.51	347	0.88	<0.01
K735172		2.64	13.3	2.13	3.39	0.09	0.04	0.02	0.015	0.11	16.5	24.2	0.48	302	0.77	<0.01
K735173		1.02	15.6	2.05	2.85	0.07	0.03	0.01	0.013	0.10	8.7	8.2	0.46	301	0.92	<0.01
K735174		0.59	15.0	1.89	2.50	0.07	0.05	0.07	0.011	0.07	7.5	6.3	0.43	539	0.43	<0.01
K735175		0.58	43.1	2.38	2.71	0.07	0.05	0.01	0.011	0.05	8.9	6.2	0.45	279	0.86	<0.01
K735201		0.96	61.8	3.70	5.52	0.09	0.03	0.05	0.025	0.07	13.7	17.3	0.95	589	1.21	0.01
K735202		0.60	51.8	3.43	4.41	0.08	0.04	0.04	0.020	0.06	17.8	14.3	0.64	425	0.82	0.01
K735203		0.72	57.1	3.70	5.60	0.09	0.03	0.04	0.024	0.06	13.6	16.7	0.87	457	0.94	0.01
K735204		1.17	53.7	3.39	4.24	0.08	0.04	0.05	0.023	0.08	12.7	15.3	0.76	435	1.33	<0.01
K735206		0.81	47.6	4.08	5.54	0.11	0.08	0.15	0.024	0.06	9.2	16.8	1.17	602	1.08	0.01
K735207		0.74	40.1	3.16	4.34	0.09	0.04	0.03	0.022	0.07	9.6	14.6	0.83	446	1.05	<0.01
K735208		0.60	35.8	3.83	5.88	0.12	0.12	0.04	0.018	0.05	9.4	19.1	1.43	786	0.63	<0.01
K735209		0.77	73.8	4.52	7.90	0.12	0.10	0.02	0.017	0.07	7.4	24.5	2.23	688	0.38	<0.01
K735210		1.17	33.1	3.27	4.63	0.10	0.08	0.05	0.022	0.05	7.4	13.9	0.98	487	1.03	0.01
K735211		0.73	12.8	3.33	5.18	0.10	0.26	0.04	0.020	0.08	13.8	12.3	0.76	595	0.68	0.01
K735212		2.66	22.6	2.87	5.16	0.11	0.04	0.04	0.021	0.18	23.3	21.6	0.73	406	1.58	0.01
K735213		2.65	18.2	2.19	4.55	0.09	0.02	0.02	0.019	0.12	17.0	20.3	0.51	772	13.10	<0.01
K735214		2.85	14.4	2.49	4.40	0.09	0.02	0.01	0.016	0.11	21.2	22.4	0.52	445	1.34	<0.01
K735215		1.13	327	6.06	4.49	0.11	0.33	1.47	0.571	0.20	10.6	9.1	1.25	887	12.00	0.04
K735216		1.17	13.1	1.96	3.04	0.07	0.02	0.01	0.012	0.11	15.2	11.7	0.38	282	0.62	<0.01
K735217		1.17	8.3	1.31	2.58	0.08	0.02	<0.01	0.010	0.05	25.0	11.2	0.29	277	0.75	<0.01
K735218		1.33	7.6	1.47	2.85	0.09	0.02	0.01	0.011	0.09	28.1	15.9	0.35	277	0.58	<0.01
K735251		0.97	22.0	3.27	3.80	0.12	0.04	0.03	0.016	0.07	20.7	11.0	0.65	427	0.54	<0.01
K735252		1.12	14.1	1.41	1.72	0.05	<0.02	0.01	0.007	0.05	8.2	6.9	0.30	356	0.32	0.02
K735253		1.16	19.8	2.19	2.68	0.07	0.03	0.10	0.014	0.05	17.5	13.3	0.34	434	0.87	<0.01
K735254		1.07	13.9	1.82	2.49	0.06	<0.02	0.02	0.007	0.08	11.0	11.8	0.47	850	1.00	<0.01
K735255		0.84	66.5	3.46	5.02	0.09	0.03	0.04	0.023	0.09	15.3	15.6	0.74	522	0.98	0.01

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Sample Description	Method Analyte Units LOR	ME- MS41 Nb ppm 0.05	ME- MS41 Ni ppm 0.2	ME- MS41 P ppm 10	ME- MS41 Pb ppm 0.2	ME- MS41 Rb ppm 0.1	ME- MS41 Re ppm 0.001	ME- MS41 S % 0.01	ME- MS41 Sb ppm 0.05	ME- MS41 Sc ppm 0.1	ME- MS41 Se ppm 0.2	ME- MS41 Sn ppm 0.2	ME- MS41 Sr ppm 0.2	ME- MS41 Ta ppm 0.01	ME- MS41 Te ppm 0.01	ME- MS41 Th ppm 0.2
K735143		0.60	28.0	1420	3.0	7.9	<0.001	0.03	0.24	1.8	0.8	0.2	27.3	<0.01	0.01	2.3
K735144		1.14	125.5	1370	4.1	19.6	<0.001	0.02	0.19	3.3	0.9	0.6	17.7	<0.01	0.01	2.3
K735145		0.25	19.9	480	2.1	2.7	<0.001	0.05	0.27	3.4	0.4	0.3	26.6	<0.01	0.04	0.9
K735146		1.02	80.5	1220	3.7	12.4	<0.001	0.01	0.18	2.3	0.8	0.4	15.4	<0.01	0.01	2.4
K735147		0.48	35.4	800	5.3	4.7	0.004	0.07	1.72	5.5	2.1	0.3	54.6	<0.01	0.04	1.0
K735148		0.46	27.9	640	4.7	3.2	0.002	0.09	1.39	5.5	1.4	0.2	97.2	<0.01	0.05	1.4
K735149		0.62	20.0	730	3.6	4.6	<0.001	0.02	1.19	4.3	0.6	0.3	42.5	<0.01	0.03	1.4
K735150		0.30	50.7	600	5.6	3.7	0.004	0.09	1.79	5.5	2.4	0.3	48.0	<0.01	0.06	1.1
K735166		0.65	27.4	880	4.9	7.6	<0.001	0.03	0.51	3.0	0.7	0.2	47.0	<0.01	0.05	3.2
K735167		0.32	34.4	1180	10.4	4.6	<0.001	0.05	1.22	2.7	0.6	<0.2	34.1	<0.01	0.08	5.1
K735168		0.62	36.0	1060	5.0	5.3	<0.001	<0.01	0.58	3.1	0.3	0.2	33.3	<0.01	0.08	5.6
K735169		0.63	36.0	1010	5.0	5.2	<0.001	<0.01	0.58	3.1	0.3	0.2	32.3	<0.01	0.07	5.6
K735170		2.75	13.6	1070	5.7	18.3	<0.001	<0.01	0.18	2.2	0.5	1.1	16.5	<0.01	0.01	8.0
K735171		1.38	24.2	1360	5.2	13.4	<0.001	0.06	0.45	2.3	0.6	0.5	18.5	<0.01	0.02	7.8
K735172		1.76	23.5	1260	5.0	14.6	<0.001	0.02	0.37	2.4	0.5	0.6	18.1	0.01	0.02	7.7
K735173		1.08	27.2	650	3.2	10.0	0.001	0.01	0.19	3.2	0.7	0.3	17.8	<0.01	0.02	3.0
K735174		1.10	23.9	500	3.1	5.8	0.001	<0.01	0.23	2.6	0.4	0.2	19.1	<0.01	0.01	2.4
K735175		0.96	25.0	590	3.4	4.9	0.002	0.01	0.34	2.4	0.3	0.3	16.8	<0.01	0.01	3.2
K735201		1.02	28.7	1010	5.4	8.9	0.001	0.01	1.07	6.2	0.8	0.4	39.5	<0.01	0.02	1.1
K735202		0.91	19.6	1150	5.4	9.9	0.003	0.01	0.50	4.5	0.5	0.4	34.9	<0.01	0.02	2.3
K735203		0.87	20.6	980	5.4	8.0	0.001	0.01	1.28	5.8	0.5	0.4	40.8	<0.01	0.02	1.0
K735204		0.95	25.3	850	5.4	9.2	0.001	0.01	0.96	6.1	0.8	0.4	43.7	<0.01	0.02	2.3
K735206		0.84	31.2	850	5.0	5.5	0.001	0.01	0.84	7.1	0.7	0.4	38.6	<0.01	0.03	2.4
K735207		0.81	25.4	710	4.8	7.0	0.001	<0.01	0.76	5.7	0.5	0.3	34.9	<0.01	0.03	2.0
K735208		1.10	33.1	1060	3.1	6.0	0.001	<0.01	0.40	6.4	0.5	0.3	37.7	<0.01	0.01	2.2
K735209		0.53	22.0	910	2.5	4.8	<0.001	<0.01	0.36	6.6	0.4	0.3	30.3	<0.01	0.01	1.8
K735210		0.81	28.6	740	3.9	5.9	0.002	0.03	0.80	6.1	1.0	0.3	42.0	<0.01	0.02	1.5
K735211		0.69	22.4	710	4.7	8.1	0.001	0.02	0.38	6.5	0.5	0.4	48.0	<0.01	0.01	3.1
K735212		2.29	37.9	1890	4.9	21.6	0.001	0.01	0.26	4.6	0.8	0.7	22.5	<0.01	0.04	9.1
K735213		2.06	67.0	1120	4.6	20.2	0.006	0.02	0.17	3.7	1.3	0.5	13.5	<0.01	0.03	6.9
K735214		1.56	25.7	870	6.7	14.1	<0.001	0.01	0.18	3.5	0.6	0.5	22.6	<0.01	0.02	7.8
K735215		0.16	70.9	600	683	8.4	0.005	2.44	142.0	6.6	2.0	4.8	103.0	<0.01	0.99	2.9
K735216		1.14	19.4	1060	4.0	11.4	<0.001	0.01	0.21	2.8	0.4	0.3	18.9	<0.01	0.02	4.7
K735217		1.09	16.5	2220	2.9	7.2	<0.001	<0.01	0.11	2.4	0.4	0.4	27.8	<0.01	0.01	14.4
K735218		1.03	12.9	1830	3.0	12.0	<0.001	<0.01	0.08	2.5	0.4	0.4	33.4	<0.01	0.01	14.3
K735251		1.16	36.8	1110	10.4	8.1	<0.001	0.01	2.03	3.2	0.4	0.3	23.8	<0.01	0.02	5.5
K735252		0.48	11.7	930	2.8	5.1	<0.001	0.02	1.81	2.1	0.2	0.2	16.8	<0.01	0.02	2.4
K735253		0.57	21.1	1050	6.6	9.5	0.001	0.02	3.56	2.8	0.7	0.3	22.2	<0.01	0.04	2.9
K735254		0.65	14.2	730	4.0	8.7	<0.001	0.01	1.36	2.3	0.3	0.2	19.6	<0.01	0.01	3.1
K735255		1.08	22.3	990	5.0	7.6	0.001	0.01	0.74	6.1	0.6	0.4	45.0	<0.01	0.02	1.4

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	Au- OG44
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr	Au
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5	0.01
K735143		0.036	0.05	0.69	25	0.10	5.06	49	0.6	
K735144		0.085	0.13	1.13	49	0.26	9.08	46	<0.5	
K735145		0.106	0.05	0.26	44	9.66	5.81	32	6.0	
K735146		0.065	0.10	1.21	34	0.15	7.70	58	<0.5	
K735147		0.041	0.17	0.39	68	0.12	7.08	99	1.2	
K735148		0.053	0.14	0.40	77	0.11	7.66	91	1.7	
K735149		0.052	0.08	0.35	59	0.14	5.44	68	1.1	
K735150		0.035	0.22	0.59	74	0.24	7.83	141	1.6	
K735166		0.048	0.05	0.56	34	0.13	5.93	40	1.4	
K735167		0.045	0.04	0.74	55	0.20	7.37	34	3.7	0.86
K735168		0.049	0.05	0.51	31	0.13	7.54	38	4.4	
K735169		0.051	0.06	0.51	31	0.14	7.24	37	4.3	
K735170		0.059	0.15	23.5	23	0.38	12.00	42	<0.5	
K735171		0.065	0.13	10.65	44	7.43	10.25	46	1.6	
K735172		0.068	0.13	7.13	38	5.12	9.97	47	1.4	
K735173		0.069	0.11	1.52	54	0.27	5.63	68	1.0	
K735174		0.064	0.06	0.45	39	0.39	5.03	34	1.6	
K735175		0.076	0.05	0.46	57	1.42	4.98	31	1.9	0.01
K735201		0.090	0.06	0.64	98	0.18	9.11	103	0.9	
K735202		0.068	0.05	1.09	77	0.14	7.93	88	1.1	
K735203		0.073	0.05	0.52	94	0.15	8.07	76	0.7	
K735204		0.080	0.07	0.75	83	0.16	8.31	68	1.3	
K735206		0.121	0.06	0.65	130	0.18	8.84	66	2.7	
K735207		0.085	0.07	0.47	79	0.12	7.09	65	1.5	
K735208		0.144	0.04	0.60	97	0.12	8.09	77	4.0	
K735209		0.150	0.03	0.27	123	0.10	7.84	79	2.9	
K735210		0.091	0.06	0.42	89	0.17	7.30	67	2.6	
K735211		0.083	0.09	0.56	89	0.09	8.53	54	9.9	
K735212		0.117	0.20	18.25	75	29.3	15.40	59	1.1	
K735213		0.097	0.28	8.91	56	3.01	13.60	140	<0.5	
K735214		0.077	0.17	24.7	62	1.10	8.55	55	<0.5	
K735215		0.029	0.57	1.10	44	9.57	8.11	1160	12.1	
K735216		0.064	0.12	8.32	50	0.38	7.40	45	<0.5	
K735217		0.059	0.08	5.30	35	1.67	9.16	34	0.6	
K735218		0.062	0.12	4.24	34	0.91	9.24	37	0.5	
K735251		0.069	0.06	0.98	49	0.20	7.80	41	1.5	0.01
K735252		0.028	0.06	0.76	20	1.62	4.11	27	<0.5	
K735253		0.027	0.14	1.30	27	0.22	8.95	65	0.5	
K735254		0.033	0.07	1.66	24	0.29	4.79	44	<0.5	
K735255		0.079	0.05	0.47	89	0.15	9.59	60	1.0	

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Sample Description	Method Analyte Units LOR	WEI- 21 Recvd Wt. kg 0.02	Au- ST44 Au ppm 0.0001	ME- MS41 Ag ppm 0.01	ME- MS41 Al % 0.01	ME- MS41 As ppm 0.1	ME- MS41 Au ppm 0.2	ME- MS41 B ppm 10	ME- MS41 Ba ppm 10	ME- MS41 Be ppm 0.05	ME- MS41 Bi ppm 0.01	ME- MS41 Ca % 0.01	ME- MS41 Cd ppm 0.01	ME- MS41 Ce ppm 0.02	ME- MS41 Co ppm 0.1	ME- MS41 Cr ppm 1
K735256		5.56	0.0083	0.07	1.31	8.5	<0.2	<10	180	0.50	0.07	0.85	0.21	29.3	12.7	38
K735257		6.84	0.0016	0.08	1.11	11.6	<0.2	<10	190	0.39	0.07	0.97	0.33	26.3	13.6	40
K735258		4.98	0.0017	0.10	1.14	12.1	<0.2	<10	240	0.36	0.07	0.98	0.40	19.80	14.5	43
K735259		5.26	0.0121	0.27	1.05	17.0	<0.2	<10	400	0.31	0.07	1.33	1.03	15.35	12.5	30
K735260		7.16	0.0016	0.07	1.02	9.0	<0.2	<10	160	0.36	0.05	1.08	0.23	22.5	12.0	34
K735261		6.24	0.0015	0.07	0.97	8.9	<0.2	<10	160	0.36	0.05	1.32	0.24	23.0	10.7	34
K735262		1.58	0.0008	0.06	1.32	5.5	<0.2	<10	150	0.25	0.05	0.85	0.16	15.20	13.2	34
K735263		5.06	0.0014	0.04	1.38	4.5	<0.2	<10	110	0.25	0.04	0.92	0.08	16.60	13.6	30
K735264		2.88	0.0142	0.05	1.02	7.1	<0.2	<10	110	0.26	0.15	0.50	0.18	24.7	10.7	30
K735265		0.16	0.0015	0.19	1.02	3.4	<0.2	<10	80	0.19	0.05	0.69	0.13	9.85	7.2	30
K735266		3.52	>0.1000	0.14	0.95	2.1	<0.2	<10	110	0.31	0.20	0.45	0.43	23.9	6.3	41
K735267		5.38	>0.1000	0.05	0.81	2.4	<0.2	<10	100	0.26	0.17	0.54	0.31	44.8	5.9	28
K735268		5.68	0.0082	0.09	0.69	4.2	<0.2	<10	130	0.19	0.21	0.33	0.75	18.90	7.4	29
K735269		5.16	0.0111	0.07	0.74	3.3	<0.2	<10	140	0.15	0.08	0.40	0.87	17.25	7.2	39
K735270		5.98	0.0583	0.05	1.24	3.6	<0.2	<10	140	0.26	0.11	0.85	0.17	23.9	12.9	63
K735271		6.88	0.0049	0.02	0.63	2.7	<0.2	<10	90	0.15	0.06	0.40	0.10	14.85	6.9	25
K735272		5.26	0.0011	0.02	0.60	1.4	<0.2	<10	80	0.12	0.07	0.31	0.10	16.55	5.3	16
K735273		5.46	0.0098	0.06	0.72	1.4	<0.2	<10	90	0.15	0.10	0.37	0.12	23.9	6.3	19
K735301		7.42	0.0528	0.08	1.15	7.4	<0.2	<10	180	0.29	0.05	0.88	0.33	19.00	12.5	44
K735302		5.52	0.0011	0.06	1.02	5.2	<0.2	<10	170	0.21	0.04	0.82	0.30	16.80	9.7	37
K735303		4.40	0.0019	0.06	1.67	3.7	<0.2	<10	130	0.27	0.05	1.06	0.23	14.10	17.2	122
K735304		5.72	0.0026	0.06	1.77	5.7	<0.2	<10	160	0.31	0.05	2.21	0.18	22.2	19.5	67
K735305		5.60	0.0100	0.04	0.79	5.5	<0.2	<10	60	0.37	0.42	0.47	0.21	33.9	6.4	18
K735306		6.94	0.0027	0.07	0.78	11.7	<0.2	<10	90	0.37	0.27	0.37	0.72	33.6	8.5	17
K735307		4.40	0.0041	0.10	1.03	13.9	<0.2	<10	130	0.44	0.63	0.36	0.90	27.0	9.3	34
K735308		9.76	0.0046	0.04	0.64	3.7	<0.2	<10	100	0.18	0.10	0.50	0.13	20.8	9.3	34
K735309		5.42	0.0033	0.05	0.81	4.1	<0.2	<10	100	0.21	0.16	0.42	0.27	22.7	13.2	39
K735310		4.24	0.0058	0.13	1.20	23.0	<0.2	<10	190	0.41	0.28	0.84	1.09	19.30	14.8	72
K735351		4.32	0.0032	0.18	1.23	13.7	<0.2	<10	180	0.29	0.08	0.83	0.35	16.75	14.4	40
K735352		4.40	0.0015	0.12	1.10	15.4	<0.2	<10	230	0.27	0.07	0.97	0.63	18.85	14.3	30
K735353		6.54	0.0276	0.05	1.00	9.2	<0.2	<10	230	0.23	0.04	0.88	0.31	16.80	10.9	34
K735354		6.12	0.0017	0.07	1.18	7.9	<0.2	<10	170	0.27	0.05	1.09	0.32	14.45	12.7	38
K735355		10.92	0.0011	0.06	1.03	8.5	<0.2	<10	180	0.26	0.04	0.81	0.30	16.35	11.7	34
K735356		<0.02	0.0024	0.06	1.06	8.5	<0.2	<10	190	0.21	0.04	0.83	0.29	14.30	11.9	35
K735357		6.80	0.0211	0.09	0.94	10.8	<0.2	<10	170	0.30	0.05	0.79	0.30	13.40	12.0	34
K735358		4.16	0.0025	0.10	0.96	7.7	<0.2	<10	180	0.26	0.05	1.79	0.34	15.70	9.0	28

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Cs	Cu	Fe	Ga	Ge	Hf	Hg	In	K	La	Li	Mg	Mn	Mo	Na
	Units	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	%	ppm	ppm	%
	LOR	0.05	0.2	0.01	0.05	0.05	0.02	0.01	0.005	0.01	0.2	0.1	0.01	5	0.05	0.01
K735256		0.65	70.5	3.59	4.64	0.09	0.04	0.06	0.022	0.07	14.8	14.5	0.75	517	1.07	0.01
K735257		0.63	47.6	3.57	4.14	0.10	0.06	0.07	0.022	0.07	13.8	11.3	0.70	462	1.75	0.01
K735258		0.78	43.6	3.07	4.09	0.09	0.05	0.14	0.024	0.07	9.3	11.8	0.77	490	1.92	0.01
K735259		0.82	32.9	3.12	3.61	0.08	0.05	0.16	0.023	0.06	8.0	9.6	0.57	2840	2.32	0.01
K735260		0.53	48.6	2.92	3.89	0.10	0.07	0.05	0.019	0.06	10.7	10.6	0.68	396	1.28	0.01
K735261		0.52	42.7	2.85	3.39	0.08	0.07	0.06	0.018	0.06	11.5	8.4	0.66	429	1.36	0.02
K735262		0.98	26.5	3.00	4.41	0.07	0.06	0.05	0.019	0.05	7.0	12.1	0.95	524	0.78	0.02
K735263		0.44	20.0	3.22	4.65	0.11	0.19	0.03	0.016	0.04	7.7	13.2	1.21	466	0.30	0.02
K735264		0.89	24.0	2.47	3.68	0.06	0.04	0.02	0.015	0.06	11.3	11.4	0.54	562	0.63	0.02
K735265		0.31	20.2	2.01	3.77	0.09	0.24	0.02	0.016	0.06	4.6	7.9	0.48	310	3.85	0.06
K735266		3.14	13.7	1.71	3.29	0.07	<0.02	0.02	0.014	0.10	13.4	24.5	0.50	225	1.03	0.02
K735267		1.30	10.5	2.10	3.26	0.08	0.02	0.01	0.015	0.12	23.4	12.6	0.45	354	1.03	0.01
K735268		1.02	17.6	1.93	2.47	0.07	<0.02	0.01	0.013	0.10	10.0	8.0	0.42	302	1.58	0.01
K735269		0.81	13.4	2.35	2.76	0.08	0.02	0.01	0.014	0.07	9.2	6.9	0.42	226	0.99	0.01
K735270		1.07	19.6	2.72	3.95	0.08	0.02	0.01	0.013	0.17	11.9	7.9	1.02	770	0.52	0.01
K735271		0.47	10.6	1.79	2.33	0.06	0.02	0.01	0.008	0.07	7.5	5.0	0.40	352	0.30	0.01
K735272		0.41	9.6	1.71	2.32	0.07	0.02	0.01	0.008	0.10	8.8	4.8	0.40	249	0.28	0.01
K735273		0.67	10.7	2.17	2.86	0.07	0.02	0.01	0.009	0.13	12.8	6.3	0.44	269	0.53	0.01
K735301		0.67	33.7	3.50	4.18	0.09	0.05	0.06	0.018	0.05	9.6	10.9	0.79	494	1.09	0.02
K735302		0.81	21.5	2.77	3.54	0.08	0.06	0.12	0.016	0.05	8.6	8.9	0.68	364	0.71	0.02
K735303		0.53	59.4	2.92	4.80	0.09	0.06	0.05	0.015	0.06	7.1	13.6	1.60	467	0.77	0.02
K735304		0.71	68.0	3.87	4.61	0.11	0.09	0.04	0.020	0.12	10.2	9.8	1.71	762	0.91	0.02
K735305		2.11	7.8	1.75	3.12	0.07	0.02	0.02	0.011	0.08	17.2	27.0	0.39	420	0.78	0.01
K735306		1.86	9.1	1.85	2.94	0.07	<0.02	0.02	0.011	0.08	15.5	20.5	0.32	744	0.79	0.01
K735307		5.25	26.9	2.16	3.66	0.08	0.02	0.01	0.017	0.15	13.6	22.8	0.54	327	2.11	0.02
K735308		0.60	16.3	2.51	2.49	0.07	0.04	0.01	0.010	0.07	11.0	4.9	0.48	300	0.42	0.01
K735309		0.70	22.5	3.26	3.06	0.08	0.03	0.01	0.011	0.09	11.9	5.9	0.60	354	0.46	0.01
K735310		3.24	30.9	3.08	4.00	0.10	0.02	0.16	0.020	0.16	9.7	16.9	1.05	449	1.74	0.02
K735351		0.86	39.4	3.45	4.04	0.09	0.07	0.11	0.023	0.06	8.0	10.2	0.78	554	1.98	0.02
K735352		0.88	26.7	2.95	3.68	0.08	0.05	0.11	0.020	0.06	9.2	9.7	0.65	2320	3.62	0.02
K735353		0.69	17.5	3.05	3.31	0.09	0.06	0.07	0.016	0.05	8.4	7.8	0.67	1320	1.26	0.02
K735354		0.85	32.3	3.22	3.98	0.10	0.06	0.07	0.019	0.05	7.0	10.1	0.85	568	0.97	0.02
K735355		0.67	19.0	2.97	3.51	0.09	0.07	0.07	0.016	0.04	8.1	8.6	0.71	1180	1.11	0.02
K735356		0.69	19.2	3.11	3.51	0.09	0.07	0.07	0.016	0.05	7.0	8.9	0.74	1220	1.06	0.02
K735357		0.84	24.3	3.08	3.38	0.08	0.07	0.11	0.017	0.05	6.5	7.4	0.63	1210	1.54	0.02
K735358		0.70	23.5	2.41	3.19	0.06	0.05	0.08	0.017	0.05	7.9	9.0	0.59	375	1.25	0.02

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41
	Analyte	Nb	Ni	P	Pb	Rb	Re	S	Sb	Sc	Se	Sn	Sr	Ta	Te	Th
	Units	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.05	0.2	10	0.2	0.1	0.001	0.01	0.05	0.1	0.2	0.2	0.2	0.01	0.01	0.2
K735256		1.23	25.1	1080	4.7	5.6	0.001	0.01	0.76	5.4	0.5	0.4	42.0	<0.01	0.02	1.9
K735257		0.82	27.3	990	5.0	5.3	0.001	0.01	1.11	5.8	0.7	0.3	42.9	<0.01	0.02	2.6
K735258		0.83	38.1	870	5.0	6.1	0.002	0.02	0.99	5.9	1.1	0.3	47.4	<0.01	0.03	1.9
K735259		0.67	35.7	820	4.7	6.5	0.006	0.04	1.16	5.5	2.1	0.2	58.4	<0.01	0.04	1.2
K735260		0.87	24.6	950	4.0	4.2	0.001	0.01	0.82	5.1	0.6	0.3	41.0	<0.01	0.02	2.1
K735261		0.72	21.0	990	3.8	3.9	0.001	<0.01	0.84	4.8	0.7	0.3	44.6	<0.01	0.01	2.2
K735262		0.64	21.9	740	3.6	5.9	0.002	0.02	0.49	5.9	0.8	0.3	36.1	<0.01	0.01	1.1
K735263		0.61	18.9	760	3.3	3.0	0.001	<0.01	0.28	5.2	0.4	0.3	32.9	<0.01	0.01	1.7
K735264		0.96	23.5	630	5.9	8.2	<0.001	<0.01	0.37	3.1	0.5	0.3	26.8	<0.01	0.02	2.6
K735265		0.27	19.9	480	2.1	2.8	0.001	0.02	0.32	4.0	0.4	0.4	26.4	<0.01	0.03	0.9
K735266		1.09	36.3	1040	3.2	15.2	0.004	<0.01	0.14	2.5	1.2	0.6	16.8	<0.01	0.01	1.9
K735267		1.80	19.7	1610	3.4	17.2	<0.001	<0.01	0.15	2.8	0.7	0.5	15.4	<0.01	0.02	16.7
K735268		0.78	21.2	610	4.7	9.0	<0.001	0.01	0.23	2.6	0.9	0.3	17.6	<0.01	0.04	5.2
K735269		0.73	20.3	690	4.3	7.8	0.001	<0.01	0.20	2.6	0.9	0.3	19.7	<0.01	0.02	2.7
K735270		0.95	39.4	880	4.9	15.9	<0.001	0.06	0.23	3.2	0.5	0.3	31.0	<0.01	0.03	3.9
K735271		0.74	13.9	640	2.0	6.0	<0.001	<0.01	0.19	2.2	0.3	0.2	16.1	<0.01	0.01	2.6
K735272		0.79	10.2	480	2.1	7.2	<0.001	<0.01	0.13	2.1	0.2	0.2	13.1	<0.01	0.01	3.2
K735273		1.00	10.9	770	2.3	7.7	<0.001	<0.01	0.10	2.5	0.2	0.3	13.2	<0.01	0.01	5.1
K735301		0.93	24.1	860	3.6	4.9	0.002	<0.01	0.81	5.3	1.2	0.3	40.9	<0.01	0.02	1.9
K735302		0.69	19.4	800	3.1	4.8	0.004	<0.01	0.59	4.6	1.4	0.3	37.9	<0.01	0.01	1.9
K735303		1.18	63.8	1070	2.5	6.3	0.001	<0.01	0.34	4.9	0.8	0.3	37.3	<0.01	0.02	1.2
K735304		0.88	35.1	950	2.8	6.7	0.002	0.02	0.49	7.4	0.8	0.3	71.9	<0.01	0.05	1.6
K735305		1.43	14.1	1430	3.7	13.1	<0.001	<0.01	0.20	2.0	0.4	0.6	16.3	<0.01	0.01	5.5
K735306		1.48	17.4	1040	5.0	13.0	<0.001	<0.01	0.32	1.8	0.6	0.5	17.1	<0.01	0.01	4.0
K735307		1.42	29.3	630	8.1	18.7	0.001	0.01	0.30	3.5	0.9	0.5	17.6	<0.01	0.03	6.9
K735308		0.68	21.1	780	3.7	5.4	<0.001	<0.01	0.27	2.1	0.3	0.2	18.8	<0.01	0.03	3.4
K735309		0.68	26.1	740	4.7	7.4	<0.001	<0.01	0.27	2.5	0.4	0.3	18.3	<0.01	0.04	4.1
K735310		1.14	48.1	910	7.3	14.9	0.001	0.16	3.24	5.0	1.5	0.4	28.4	<0.01	0.04	5.2
K735351		0.70	30.7	720	5.0	5.0	0.003	<0.01	1.29	6.3	1.5	0.3	46.6	<0.01	0.03	2.1
K735352		0.78	28.0	730	4.3	5.3	0.003	0.01	0.91	5.5	2.7	0.3	42.6	<0.01	0.03	2.0
K735353		0.61	20.9	740	2.9	3.8	0.003	<0.01	0.67	4.3	1.0	0.3	36.4	<0.01	0.02	4.4
K735354		0.67	24.8	750	3.6	4.3	0.003	<0.01	0.86	5.7	1.2	0.3	42.2	<0.01	0.03	1.7
K735355		0.62	22.4	740	2.9	3.7	0.003	0.01	0.68	4.5	0.9	0.3	33.6	<0.01	0.02	2.1
K735356		0.58	22.1	750	3.1	3.7	0.003	0.01	0.72	4.7	0.9	0.3	32.7	<0.01	0.01	1.6
K735357		0.54	24.8	700	3.4	3.7	0.003	0.01	1.00	4.8	1.1	0.3	35.1	<0.01	0.02	1.5
K735358		0.64	19.1	750	3.7	5.4	0.005	0.01	0.73	4.3	1.2	0.3	59.3	<0.01	0.02	1.3

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Sample Description	Method	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	ME- MS41	Au- OG44
	Analyte	Ti	Tl	U	V	W	Y	Zn	Zr	Au
	Units	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	LOR	0.005	0.02	0.05	1	0.05	0.05	2	0.5	0.01
K735256		0.093	0.05	0.53	90	0.15	8.69	57	1.4	
K735257		0.083	0.08	0.54	93	0.14	8.80	65	2.2	
K735258		0.076	0.11	0.52	76	0.95	7.83	69	1.9	
K735259		0.058	0.13	0.47	65	0.14	8.13	91	1.4	
K735260		0.090	0.05	0.47	75	0.14	8.06	52	2.6	
K735261		0.094	0.05	0.49	76	0.14	7.79	51	2.7	
K735262		0.083	0.04	0.35	74	0.09	6.49	66	1.7	
K735263		0.140	0.03	0.32	79	0.36	7.25	55	5.8	
K735264		0.066	0.05	0.57	48	0.18	4.73	55	1.2	
K735265		0.111	0.05	0.25	46	11.05	6.49	33	6.7	
K735266		0.065	0.12	3.44	47	7.04	7.98	71	<0.5	0.02
K735267		0.079	0.15	3.60	51	3.51	13.05	44	<0.5	0.04
K735268		0.060	0.10	1.97	51	0.52	5.02	61	0.5	
K735269		0.066	0.09	0.73	65	4.59	4.91	87	0.7	
K735270		0.083	0.13	0.77	45	0.13	6.16	56	0.7	
K735271		0.059	0.05	0.48	40	0.16	4.14	27	0.8	
K735272		0.058	0.05	0.56	39	0.12	3.91	24	0.7	
K735273		0.073	0.06	1.07	49	0.89	5.22	30	0.5	
K735301		0.103	0.05	1.29	104	0.12	7.75	55	1.9	
K735302		0.091	0.05	0.48	83	0.19	6.54	54	1.8	
K735303		0.150	0.03	0.31	76	0.09	6.31	68	1.9	
K735304		0.133	0.06	0.32	102	0.07	8.52	67	2.7	
K735305		0.060	0.12	4.33	26	6.21	10.20	40	<0.5	
K735306		0.046	0.12	6.04	29	0.84	9.13	54	<0.5	
K735307		0.073	0.19	26.3	58	1.54	8.77	110	<0.5	
K735308		0.072	0.05	1.94	53	0.15	5.56	31	1.8	
K735309		0.072	0.06	0.71	67	0.16	5.97	39	1.1	
K735310		0.075	0.37	5.85	69	0.79	10.20	95	0.5	
K735351		0.086	0.08	0.44	93	0.16	8.22	72	2.6	
K735352		0.074	0.11	0.71	68	0.20	7.32	66	1.5	
K735353		0.091	0.07	0.93	82	0.15	5.94	55	2.2	
K735354		0.096	0.05	0.41	92	0.15	6.91	57	2.1	
K735355		0.089	0.06	0.56	81	0.15	6.17	53	2.4	
K735356		0.095	0.07	0.41	85	0.16	5.97	55	2.4	
K735357		0.082	0.10	0.36	85	0.16	6.40	60	2.4	
K735358		0.070	0.06	0.38	60	0.20	6.12	54	1.4	

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: GOLDEN PREDATOR CANADA CORP.
888 DUNSMUIR STREET
11TH FLOOR
VANCOUVER BC V6C 3K4

Finalized Date: 26- JUL- 2011
Account: GOPRED

Project: Stream seds

CERTIFICATE OF ANALYSIS WH11105622

Method	CERTIFICATE COMMENTS
ALL METHODS	NSS is non- sufficient sample.
ME- MS41	Gold determinations by this method are semi- quantitative due to the small sample weight used (0.5g).

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Submitted By: Andrew Caldwell
Receiving Lab: Canada-Whitehorse
Received: March 08, 2012
Report Date: March 21, 2012
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI12000008.1

CLIENT JOB INFORMATION

Project: LIVINGSTONE
Shipment ID: SRV-2012-AC-2140
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

RTRN-PLP Return
RTRN-RJT Return

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	320	Dry at 60C			WHI
SS80	320	Dry at 60C sieve 100g to -80 mesh			WHI
1DX2	320	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
RJSV	320	Saving all or part of Soil Reject			WHI

ADDITIONAL COMMENTS

Invoice To: Predator Mining Group
11th Floor- 888 Dunsmuir Street
Vancouver BC V6C 3K4
Canada

CC: Jack Cote
Linda Lewis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K954001	Soil	0.8	44.2	28.3	51	0.4	38.4	16.5	546	2.81	3.9	<0.5	1.3	43	0.3	0.5	<0.1	73	3.59	0.060	7
K954002	Soil	0.8	40.8	32.5	55	0.5	33.8	14.8	451	2.80	5.8	0.9	2.9	14	0.2	0.6	0.1	80	0.69	0.067	6
K954003	Soil	0.5	41.8	36.8	59	0.4	27.7	15.0	525	3.00	3.6	<0.5	1.4	14	0.2	0.8	<0.1	80	0.71	0.113	5
K954004	Soil	0.5	37.1	6.2	52	0.2	35.4	16.5	579	2.89	4.1	1.8	1.1	17	0.2	0.4	<0.1	87	0.46	0.052	5
K954005	Soil	0.1	6.1	4.9	29	0.2	8.5	6.4	282	1.64	0.7	<0.5	2.6	135	<0.1	<0.1	0.2	55	0.48	0.083	5
K954006	Soil	<0.1	8.9	14.9	30	<0.1	11.9	8.1	312	2.08	2.3	<0.5	2.7	49	<0.1	0.2	<0.1	67	0.56	0.080	6
K954007	Soil	0.2	6.5	5.2	38	0.2	11.8	8.4	461	2.11	2.7	<0.5	1.5	24	<0.1	0.3	<0.1	60	0.34	0.081	6
K954008	Soil	<0.1	2.9	2.0	25	<0.1	6.3	5.2	232	1.51	<0.5	<0.5	2.9	60	<0.1	<0.1	<0.1	53	0.50	0.088	5
K954009	Soil	3.2	27.4	9.3	42	0.3	6.5	3.1	224	3.07	2.1	<0.5	2.0	34	0.1	0.1	0.3	43	0.04	0.077	7
K954010	Soil	1.5	16.5	26.1	71	0.2	25.7	8.5	405	1.94	4.5	<0.5	7.4	23	0.7	0.2	0.6	50	0.27	0.045	14
K954011	Soil	0.4	6.6	10.8	73	0.2	5.4	2.1	113	0.67	1.5	<0.5	6.2	5	0.3	<0.1	0.4	16	0.05	0.015	8
K954012	Soil	0.6	9.9	10.7	69	0.2	10.2	4.7	328	1.50	1.2	<0.5	8.7	8	0.5	<0.1	0.4	38	0.15	0.055	14
K954013	Soil	<0.1	7.7	9.6	40	0.2	2.7	3.5	301	0.99	<0.5	<0.5	12.8	10	<0.1	<0.1	4.0	23	0.13	0.045	20
K954014	Soil	1.7	18.7	6.5	126	0.1	15.4	5.1	1315	1.30	1.2	<0.5	10.7	10	4.3	0.1	0.6	35	0.18	0.061	18
K954015	Soil	7.0	28.4	9.6	73	0.2	29.8	9.5	402	2.40	3.0	2.6	3.3	14	1.3	0.2	0.6	79	0.22	0.035	9
K954016	Soil	1.6	32.4	26.3	84	0.2	36.2	11.4	403	2.53	3.5	0.9	1.9	17	0.6	0.3	0.4	76	0.20	0.053	11
K954017	Soil	1.8	16.7	11.4	60	0.1	6.3	2.9	227	1.18	0.6	<0.5	8.2	7	0.4	<0.1	0.4	28	0.15	0.062	22
K954018	Soil	5.5	60.0	11.7	365	0.2	57.1	6.6	386	3.93	0.8	<0.5	4.8	36	1.8	<0.1	0.2	238	0.25	0.046	17
K954019	Soil	1.3	27.2	9.3	80	0.2	46.5	11.9	364	2.65	4.0	0.6	3.1	16	0.4	0.3	0.2	84	0.17	0.028	10
K954020	Soil	3.1	21.5	4.9	44	0.4	7.0	2.5	194	1.81	<0.5	<0.5	4.4	19	0.2	<0.1	0.6	111	0.14	0.045	15
K954021	Soil	0.5	19.8	8.8	38	0.2	25.4	11.5	251	1.72	0.6	<0.5	4.9	117	0.2	<0.1	0.1	42	2.05	0.071	9
K954022	Soil	0.3	14.5	7.3	47	0.3	17.7	12.1	545	2.62	12.4	0.9	2.8	24	<0.1	0.8	<0.1	71	0.43	0.085	8
K954023	Soil	5.5	23.0	7.4	159	0.3	48.9	9.3	254	2.10	3.9	<0.5	2.3	14	2.1	0.3	0.2	84	0.23	0.028	7
K954024	Soil	2.5	15.0	6.9	120	0.4	25.8	8.6	432	1.84	0.7	<0.5	2.9	45	0.8	<0.1	0.1	94	0.47	0.050	13
K954025	Soil	2.4	27.4	9.5	94	0.3	48.5	11.5	379	2.92	4.8	<0.5	2.9	23	0.7	0.3	0.1	88	0.24	0.052	10
K954026	Soil	32.9	44.4	50.0	318	0.7	21.0	5.2	151	1.93	<0.5	<0.5	1.1	30	23.4	0.3	0.3	244	0.14	0.040	5
K954027	Soil	7.3	29.5	164.2	57	0.7	32.3	7.2	230	2.73	2.0	0.9	2.9	48	0.7	0.3	2.2	66	0.15	0.070	9
K954301	Soil	0.6	65.3	9.0	58	0.6	28.4	24.9	961	4.26	9.6	0.9	0.9	110	0.3	0.3	<0.1	166	2.36	0.036	3
K954302	Soil	1.3	26.0	11.3	40	0.1	26.5	13.4	366	2.83	19.3	3.0	2.0	19	0.2	1.0	0.1	81	0.26	0.042	10
K954303	Soil	1.1	42.2	8.2	99	0.1	41.5	39.5	1650	5.94	25.9	1.8	0.7	19	0.2	1.3	<0.1	183	0.61	0.076	6

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K954001	Soil	83	1.55	205	0.099	<1	1.62	0.020	0.09	1.1	0.02	6.1	<0.1	<0.05	5	<0.5	<0.2
K954002	Soil	65	1.07	132	0.095	1	1.35	0.026	0.10	1.7	0.01	5.1	0.1	<0.05	5	<0.5	<0.2
K954003	Soil	52	1.32	144	0.065	<1	1.54	0.023	0.13	1.5	0.02	5.4	<0.1	<0.05	6	<0.5	<0.2
K954004	Soil	87	1.40	106	0.117	1	1.78	0.021	0.12	1.1	0.01	5.0	<0.1	<0.05	5	<0.5	<0.2
K954005	Soil	24	0.50	88	0.087	<1	0.78	0.046	0.08	2.1	<0.01	2.4	<0.1	<0.05	4	<0.5	<0.2
K954006	Soil	35	0.62	58	0.080	<1	0.87	0.050	0.06	1.3	<0.01	3.0	<0.1	<0.05	4	<0.5	<0.2
K954007	Soil	32	0.74	41	0.077	<1	1.12	0.032	0.05	1.7	<0.01	3.1	<0.1	<0.05	5	<0.5	<0.2
K954008	Soil	23	0.45	69	0.082	<1	0.64	0.040	0.05	1.8	<0.01	1.4	<0.1	<0.05	3	<0.5	<0.2
K954009	Soil	35	0.47	142	0.032	<1	1.05	0.061	0.21	11.4	<0.01	1.5	0.4	0.25	3	1.4	<0.2
K954010	Soil	31	0.66	128	0.080	1	1.35	0.016	0.22	9.0	0.01	3.1	0.3	<0.05	5	0.6	<0.2
K954011	Soil	9	0.12	40	0.023	<1	0.45	0.021	0.08	7.6	0.01	1.1	0.1	<0.05	2	<0.5	<0.2
K954012	Soil	19	0.43	63	0.102	<1	0.96	0.019	0.34	6.3	0.01	2.9	0.4	<0.05	5	<0.5	<0.2
K954013	Soil	7	0.32	79	0.095	<1	0.73	0.067	0.48	11.7	<0.01	3.0	0.7	<0.05	4	<0.5	<0.2
K954014	Soil	19	0.35	225	0.039	<1	0.85	0.011	0.11	4.1	<0.01	2.6	0.2	<0.05	3	<0.5	<0.2
K954015	Soil	39	0.63	159	0.085	<1	1.48	0.019	0.13	5.3	0.01	3.6	0.2	<0.05	4	0.7	<0.2
K954016	Soil	51	0.74	132	0.072	<1	1.72	0.017	0.17	3.8	0.02	3.4	0.2	<0.05	5	0.7	<0.2
K954017	Soil	11	0.33	65	0.082	<1	0.72	0.033	0.33	6.4	<0.01	2.4	0.4	<0.05	4	<0.5	<0.2
K954018	Soil	62	1.50	125	0.114	<1	3.09	0.053	0.76	3.9	<0.01	7.0	1.0	<0.05	9	3.6	<0.2
K954019	Soil	57	0.86	175	0.095	<1	1.87	0.016	0.14	4.5	0.02	4.2	0.2	<0.05	6	<0.5	<0.2
K954020	Soil	23	0.51	79	0.131	<1	0.86	0.065	0.35	2.8	<0.01	4.0	0.4	0.16	3	2.5	<0.2
K954021	Soil	36	0.74	68	0.092	1	3.81	0.209	0.53	7.1	<0.01	2.5	0.5	0.07	10	<0.5	<0.2
K954022	Soil	36	0.84	82	0.056	<1	1.24	0.023	0.08	2.5	0.04	4.2	<0.1	<0.05	5	<0.5	<0.2
K954023	Soil	65	0.73	121	0.062	<1	1.25	0.029	0.12	5.8	<0.01	3.2	0.2	0.05	4	1.9	<0.2
K954024	Soil	38	0.66	68	0.074	<1	1.64	0.070	0.42	5.1	0.01	3.5	0.4	0.07	6	1.0	<0.2
K954025	Soil	106	0.97	213	0.109	<1	1.80	0.033	0.12	3.6	0.04	4.2	0.2	<0.05	6	0.8	<0.2
K954026	Soil	35	0.32	115	0.065	<1	0.85	0.036	0.15	10.7	0.06	1.8	0.4	0.08	3	14.9	<0.2
K954027	Soil	52	0.46	167	0.070	<1	0.95	0.057	0.07	6.2	0.02	2.9	0.2	0.18	3	3.3	0.2
K954301	Soil	77	1.89	27	0.171	4	4.72	0.023	0.09	0.7	0.03	21.3	<0.1	<0.05	10	<0.5	<0.2
K954302	Soil	38	0.54	83	0.066	1	1.51	0.021	0.07	1.0	0.03	5.0	0.1	<0.05	5	<0.5	<0.2
K954303	Soil	55	0.70	61	0.111	5	2.15	0.043	0.08	0.3	0.07	18.5	0.1	<0.05	8	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K954028	Soil	6.1	20.6	7.9	50	0.6	8.9	3.0	274	2.77	2.8	0.6	2.1	9	0.2	0.2	0.1	66	0.06	0.042	5
K954029	Soil	5.5	9.9	4.6	17	0.6	1.0	0.8	202	2.76	<0.5	0.9	1.4	7	<0.1	0.1	0.5	72	<0.01	0.036	3
K954030	Soil	10.6	27.7	13.7	41	0.8	4.4	1.3	253	4.27	<0.5	1.9	3.6	24	0.1	0.1	0.2	292	0.04	0.065	7
K954031	Soil	8.5	46.0	4.9	92	0.8	11.6	4.3	337	3.79	<0.5	4.1	1.6	30	0.4	<0.1	0.1	114	0.22	0.065	4
K954032	Soil	1.8	26.5	11.0	41	1.0	9.5	3.3	190	4.58	0.8	0.7	1.3	20	0.1	0.3	<0.1	89	0.13	0.112	5
K954033	Soil	3.1	45.3	8.2	166	0.4	40.1	8.9	340	2.53	3.1	2.2	2.4	17	0.7	0.3	0.2	100	0.23	0.039	7
K954034	Soil	10.3	29.4	20.5	137	0.4	34.2	8.2	214	1.76	1.8	4.9	1.6	30	0.9	0.3	0.7	77	0.21	0.036	6
K954035	Soil	3.1	19.0	5.7	108	0.3	17.9	7.4	275	1.56	0.9	2.9	2.4	13	0.5	<0.1	0.3	63	0.14	0.034	6
K954036	Soil	6.8	21.4	7.9	40	0.6	1.9	1.4	432	3.33	<0.5	5.4	1.1	16	<0.1	<0.1	0.2	195	0.07	0.049	2
K954037	Soil	0.9	7.5	10.7	42	0.2	7.6	5.2	310	1.84	1.6	2.2	1.3	27	0.1	0.2	0.2	43	0.10	0.067	18
K954038	Soil	1.4	19.8	6.7	55	0.2	24.3	8.2	295	1.83	2.1	1.1	6.4	13	0.2	0.1	0.2	61	0.18	0.047	13
K954039	Soil	1.5	15.8	6.4	49	0.3	19.3	6.8	253	1.81	1.9	1.1	1.8	20	0.3	0.2	0.8	65	0.20	0.048	7
K954040	Soil	1.3	16.5	6.7	63	0.2	14.1	5.9	303	1.92	2.0	1.6	1.7	9	0.2	0.2	0.4	64	0.12	0.043	6
K954041	Soil	1.6	20.2	8.2	55	0.6	22.7	8.3	307	2.18	2.4	1.6	1.4	21	0.2	0.2	0.3	77	0.28	0.079	11
K954042	Soil	1.5	24.2	6.7	62	0.2	35.0	10.0	313	2.21	2.0	1.3	3.3	30	0.2	0.1	0.3	72	0.39	0.036	9
K954043	Soil	0.6	9.0	5.9	40	0.1	111.0	10.7	280	1.56	1.3	1.3	12.7	12	0.2	<0.1	0.1	37	0.14	0.041	12
K954044	Soil	0.4	5.6	7.2	46	0.1	9.6	4.6	287	1.41	0.6	<0.5	9.3	13	0.1	<0.1	0.1	40	0.21	0.068	29
K954045	Soil	1.2	15.8	7.8	45	0.1	16.4	6.7	316	1.55	1.8	0.7	3.7	10	0.1	0.2	0.2	49	0.14	0.030	11
K954046	Soil	1.2	17.9	11.6	58	0.6	24.0	7.9	340	1.79	2.4	1.2	5.3	20	0.3	0.1	0.2	56	0.13	0.039	12
K954047	Soil	1.6	20.8	7.9	58	0.2	29.0	8.8	332	2.02	2.5	0.8	2.7	15	0.2	0.2	0.3	75	0.17	0.041	10
K954048	Soil	3.4	49.2	6.2	57	0.3	32.4	9.8	345	2.09	1.1	<0.5	2.7	26	0.3	<0.1	0.2	132	0.53	0.054	5
K954049	Soil	1.8	21.3	5.2	55	0.3	27.3	8.5	326	2.10	2.5	<0.5	2.1	17	0.2	0.2	0.3	113	0.26	0.052	7
K954050	Soil	0.4	5.0	12.0	37	0.1	5.3	3.9	238	1.20	0.8	<0.5	4.9	19	<0.1	<0.1	0.1	26	0.19	0.051	14
K954351	Soil	0.6	35.4	4.6	80	0.2	35.7	20.7	703	4.79	5.9	<0.5	1.3	18	0.2	0.6	<0.1	167	0.66	0.049	6
K954352	Soil	0.7	31.2	6.5	65	0.3	25.0	16.9	517	3.71	6.7	<0.5	7.2	13	0.1	0.8	<0.1	126	0.90	0.059	8
K954353	Soil	0.2	29.3	2.9	55	0.2	27.2	16.8	590	3.34	4.5	<0.5	1.3	22	0.2	0.4	<0.1	97	0.70	0.040	4
K954354	Soil	0.6	33.5	5.3	64	0.2	28.3	20.0	863	4.20	9.2	1.2	3.0	14	0.2	0.6	<0.1	130	0.55	0.060	9
K954355	Soil	0.7	34.1	6.6	56	0.5	28.5	16.3	663	3.21	6.9	5.9	2.2	21	0.2	0.5	<0.1	99	0.62	0.057	9
K954356	Soil	0.5	41.1	3.5	80	0.2	36.1	21.3	873	4.86	3.6	0.7	1.2	18	0.3	0.1	<0.1	146	1.28	0.062	6
K954357	Soil	0.6	26.3	6.6	47	0.1	24.5	14.2	440	3.04	6.3	1.6	3.1	18	0.1	0.6	<0.1	100	0.57	0.058	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K954028	Soil	18	0.46	152	0.049	<1	0.81	0.016	0.21	7.4	0.01	3.6	0.5	0.11	3	4.1	<0.2
K954029	Soil	11	0.46	223	0.046	<1	0.59	0.031	0.40	4.4	<0.01	3.2	1.0	0.44	3	9.0	<0.2
K954030	Soil	132	1.11	199	0.086	<1	1.27	0.049	0.90	4.6	<0.01	6.1	1.1	0.60	6	12.0	<0.2
K954031	Soil	16	0.61	263	0.071	<1	1.33	0.041	0.47	9.7	0.01	4.8	1.1	0.55	4	6.7	<0.2
K954032	Soil	72	0.65	219	0.063	<1	0.96	0.019	0.36	7.6	0.02	3.8	0.6	0.18	4	4.7	<0.2
K954033	Soil	42	0.60	183	0.076	<1	1.55	0.020	0.17	7.1	0.01	4.7	0.2	<0.05	5	1.8	<0.2
K954034	Soil	29	0.47	160	0.057	1	1.16	0.015	0.11	8.7	0.03	2.5	0.2	0.06	4	2.6	<0.2
K954035	Soil	25	0.38	137	0.043	1	0.88	0.018	0.15	9.6	0.02	2.2	0.2	<0.05	3	2.2	<0.2
K954036	Soil	25	1.13	439	0.106	<1	1.42	0.041	0.66	4.7	<0.01	10.3	0.8	0.36	6	7.3	<0.2
K954037	Soil	24	0.36	109	0.025	<1	1.50	0.012	0.12	7.8	0.05	1.1	0.4	<0.05	7	<0.5	<0.2
K954038	Soil	36	0.54	151	0.075	<1	1.16	0.019	0.18	7.1	0.02	3.0	0.2	<0.05	4	<0.5	<0.2
K954039	Soil	32	0.48	176	0.076	<1	1.11	0.017	0.13	5.4	0.06	2.4	0.2	<0.05	5	<0.5	<0.2
K954040	Soil	25	0.47	79	0.066	<1	1.07	0.017	0.07	4.7	0.04	3.1	0.2	<0.05	5	<0.5	<0.2
K954041	Soil	38	0.53	174	0.072	1	1.29	0.020	0.16	5.1	0.03	2.5	0.2	<0.05	6	<0.5	<0.2
K954042	Soil	47	0.73	232	0.091	1	1.70	0.028	0.20	5.2	0.01	3.2	0.2	<0.05	5	0.7	<0.2
K954043	Soil	44	1.25	105	0.045	<1	0.84	0.019	0.15	4.7	0.01	2.5	0.2	<0.05	3	<0.5	<0.2
K954044	Soil	18	0.45	129	0.081	<1	0.88	0.040	0.38	6.2	<0.01	2.7	0.5	<0.05	5	<0.5	<0.2
K954045	Soil	27	0.44	122	0.054	<1	1.03	0.013	0.12	8.4	<0.01	2.1	0.2	<0.05	4	<0.5	<0.2
K954046	Soil	32	0.50	231	0.072	<1	1.17	0.019	0.18	8.8	0.02	2.7	0.2	<0.05	4	<0.5	<0.2
K954047	Soil	41	0.58	148	0.068	<1	1.42	0.019	0.14	5.3	0.03	3.2	0.2	<0.05	5	<0.5	<0.2
K954048	Soil	40	0.66	171	0.097	<1	1.39	0.046	0.14	5.9	0.02	3.7	<0.1	<0.05	4	1.3	<0.2
K954049	Soil	40	0.58	149	0.080	<1	1.32	0.026	0.11	6.1	0.02	3.2	0.1	<0.05	5	<0.5	<0.2
K954050	Soil	13	0.33	75	0.012	<1	1.06	0.015	0.10	6.1	0.01	1.4	0.2	<0.05	4	<0.5	<0.2
K954351	Soil	72	1.48	85	0.304	3	2.42	0.029	0.05	0.6	0.03	11.3	<0.1	<0.05	11	<0.5	<0.2
K954352	Soil	43	1.16	64	0.227	2	1.82	0.119	0.07	1.0	0.01	7.9	<0.1	<0.05	7	<0.5	<0.2
K954353	Soil	43	1.27	125	0.161	3	2.05	0.038	0.05	0.8	<0.01	6.8	<0.1	<0.05	7	<0.5	<0.2
K954354	Soil	53	1.09	100	0.216	2	2.26	0.028	0.05	1.1	0.02	8.7	<0.1	<0.05	8	<0.5	<0.2
K954355	Soil	52	0.93	109	0.109	2	1.90	0.034	0.06	2.0	0.03	6.5	<0.1	<0.05	7	<0.5	<0.2
K954356	Soil	73	2.06	77	0.327	3	2.78	0.047	0.02	0.9	0.06	10.0	<0.1	<0.05	10	<0.5	<0.2
K954357	Soil	47	0.90	69	0.158	2	1.43	0.038	0.04	1.9	0.02	5.9	<0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K954358	Soil	0.4	21.5	7.0	44	0.3	16.5	10.6	298	2.40	3.4	0.9	1.0	14	0.1	0.3	<0.1	80	0.50	0.053	8
K954359	Soil	0.6	21.5	3.7	44	0.1	24.2	12.7	396	2.84	5.1	<0.5	9.0	14	0.2	0.4	<0.1	92	0.46	0.065	17
K954360	Soil	0.6	36.5	5.4	49	0.3	32.9	16.4	588	3.43	6.5	4.9	2.8	18	0.1	0.5	<0.1	115	0.71	0.054	9
K954361	Soil	1.0	39.6	10.8	67	0.2	30.2	18.5	783	4.05	7.3	4.5	7.1	19	0.1	0.5	<0.1	125	0.75	0.063	13
K954362	Soil	0.7	33.4	7.1	53	0.4	30.7	16.5	616	3.42	10.3	1.1	3.3	16	0.2	0.7	<0.1	103	0.61	0.050	10
K954363	Soil	0.6	26.1	7.1	46	0.3	31.9	13.5	402	2.76	7.0	2.0	3.1	18	0.1	0.5	<0.1	83	0.57	0.055	9
K954364	Soil	0.5	44.5	5.3	64	0.4	40.0	21.2	665	4.16	6.2	3.4	2.4	21	0.2	0.5	<0.1	133	0.88	0.056	8
K954365	Soil	0.6	31.8	8.7	46	0.6	31.2	16.1	532	3.47	6.9	1.1	3.5	17	<0.1	0.5	<0.1	116	0.53	0.056	11
K954366	Soil	1.0	27.3	5.9	46	0.3	32.4	13.6	519	2.72	5.9	10.0	3.5	20	0.2	0.4	0.1	73	0.66	0.071	14
K954367	Soil	0.5	35.8	6.6	47	0.2	34.6	16.6	558	3.33	5.6	0.9	3.2	18	0.1	0.4	<0.1	114	0.80	0.054	9
K954368	Soil	1.1	33.8	6.3	48	0.5	33.6	13.0	430	2.94	6.7	2.2	3.6	17	0.2	0.6	<0.1	98	0.47	0.046	11
K954369	Soil	0.6	19.1	19.0	45	0.3	22.2	11.7	447	2.85	3.7	0.7	7.0	16	0.1	0.3	<0.1	94	0.80	0.075	14
K954370	Soil	1.0	39.7	9.0	54	0.4	32.5	18.6	1611	3.01	7.7	2.4	2.8	22	0.2	0.7	0.1	97	0.59	0.054	7
K954371	Soil	0.7	29.0	10.2	50	0.2	23.0	11.7	375	2.72	7.0	1.3	3.3	13	0.2	0.4	0.1	82	0.37	0.046	8
K954372	Soil	0.6	45.9	4.9	61	0.2	20.1	15.1	542	3.79	5.5	1.1	2.6	82	0.2	0.5	0.1	146	1.02	0.054	6
K954373	Soil	0.8	29.7	8.0	40	0.4	23.8	9.9	209	2.35	7.7	2.1	3.8	14	0.1	0.6	0.1	75	0.28	0.046	12
K954374	Soil	0.6	29.1	4.6	80	0.2	24.7	19.4	680	4.38	10.1	2.4	1.8	24	0.2	0.6	<0.1	147	1.34	0.075	6
K954651	Soil	0.7	20.3	7.8	38	0.4	17.4	10.1	338	2.10	7.5	2.2	1.1	12	0.1	0.5	0.2	52	0.26	0.039	7
K954652	Soil	0.7	24.7	43.7	57	0.1	49.0	15.9	619	2.59	2.1	<0.5	21.6	88	0.2	0.2	0.2	38	1.99	0.142	89
K954653	Soil	0.8	25.7	10.9	43	0.5	21.6	12.1	344	2.58	8.4	1.8	3.2	14	0.1	0.6	0.3	74	0.35	0.051	12
K954654	Soil	0.8	40.8	64.6	67	0.5	31.7	17.3	471	2.94	15.8	3.2	3.0	17	0.3	0.7	0.3	79	0.48	0.053	13
K954655	Soil	0.9	37.6	19.1	71	0.5	28.2	15.0	650	2.93	10.6	1.8	1.2	25	0.3	0.9	0.4	78	0.87	0.093	9
K954656	Soil	0.4	34.5	31.3	47	0.8	24.1	16.6	426	2.47	14.6	2.4	2.2	31	0.2	0.7	0.2	84	1.05	0.070	8
K954657	Soil	0.6	38.9	7.9	69	0.3	23.7	9.6	525	2.20	10.0	2.2	1.2	27	0.3	1.0	0.4	48	1.02	0.090	10
K954658	Soil	0.4	32.9	46.3	80	0.6	38.5	15.7	899	3.32	18.9	1.2	0.6	42	0.3	1.4	<0.1	51	3.41	0.060	5
K954659	Soil	0.5	24.7	6.4	66	0.3	25.5	14.9	569	2.81	13.1	1.5	2.3	12	0.1	0.8	<0.1	71	0.50	0.060	6
K954660	Soil	0.8	33.2	37.4	52	0.4	31.6	16.7	522	3.07	13.8	2.1	1.3	21	0.1	0.9	0.2	94	0.48	0.048	6
K954661	Soil	0.6	39.1	8.5	50	0.3	35.3	16.9	477	3.00	13.0	2.4	1.3	22	0.1	0.8	0.3	98	0.79	0.055	6
K954662	Soil	0.5	33.2	124.6	51	0.5	27.7	15.7	561	3.00	9.6	5.3	0.7	21	0.2	0.6	0.1	89	0.62	0.057	5
K954663	Soil	0.5	55.2	8.5	55	0.5	35.8	19.7	687	3.48	9.7	2.2	1.2	32	0.2	0.7	0.7	107	1.46	0.053	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K954358	Soil	32	0.73	67	0.151	2	1.58	0.028	0.04	1.3	0.05	3.5	0.1	<0.05	6	<0.5	<0.2
K954359	Soil	47	0.90	84	0.156	2	1.60	0.041	0.12	2.2	0.01	5.5	<0.1	<0.05	6	<0.5	<0.2
K954360	Soil	65	1.27	81	0.143	2	1.80	0.042	0.04	1.7	0.02	8.2	<0.1	<0.05	6	<0.5	<0.2
K954361	Soil	65	1.37	112	0.155	2	2.33	0.038	0.06	1.5	0.04	10.0	0.1	<0.05	8	<0.5	<0.2
K954362	Soil	59	1.07	85	0.135	2	1.81	0.053	0.06	1.8	0.02	7.8	<0.1	<0.05	6	<0.5	<0.2
K954363	Soil	49	0.86	94	0.122	1	1.46	0.056	0.06	2.3	0.02	5.3	<0.1	<0.05	5	<0.5	<0.2
K954364	Soil	73	1.55	101	0.215	3	2.20	0.064	0.04	1.1	0.02	8.3	<0.1	<0.05	8	<0.5	<0.2
K954365	Soil	55	1.03	103	0.160	2	1.85	0.032	0.04	1.9	0.03	7.7	<0.1	<0.05	6	<0.5	<0.2
K954366	Soil	48	0.94	100	0.127	1	1.33	0.039	0.06	3.4	0.02	5.6	<0.1	<0.05	5	<0.5	<0.2
K954367	Soil	75	1.29	95	0.143	3	2.01	0.044	0.04	1.2	<0.01	8.4	<0.1	<0.05	6	<0.5	<0.2
K954368	Soil	56	0.97	88	0.095	2	1.93	0.023	0.05	1.8	0.03	7.0	<0.1	<0.05	6	<0.5	<0.2
K954369	Soil	39	0.94	76	0.112	2	1.27	0.081	0.08	1.6	0.02	6.3	<0.1	<0.05	5	<0.5	<0.2
K954370	Soil	59	1.02	112	0.123	3	1.58	0.034	0.04	1.9	0.03	6.9	<0.1	<0.05	6	<0.5	<0.2
K954371	Soil	43	0.84	78	0.125	2	1.53	0.024	0.05	1.6	0.02	5.7	<0.1	<0.05	6	<0.5	<0.2
K954372	Soil	35	1.17	65	0.212	3	2.59	0.220	0.04	0.8	0.02	6.6	<0.1	<0.05	8	<0.5	<0.2
K954373	Soil	42	0.63	87	0.086	1	1.43	0.020	0.05	2.1	0.02	4.4	<0.1	<0.05	5	<0.5	<0.2
K954374	Soil	33	1.24	124	0.193	2	1.79	0.150	0.05	1.0	0.02	12.0	<0.1	<0.05	7	<0.5	<0.2
K954651	Soil	31	0.53	58	0.051	1	1.16	0.039	0.05	6.6	0.03	3.8	<0.1	<0.05	5	<0.5	<0.2
K954652	Soil	59	1.45	103	0.012	4	1.54	0.032	0.13	0.7	0.04	3.6	<0.1	<0.05	5	<0.5	<0.2
K954653	Soil	46	0.68	60	0.081	1	1.37	0.049	0.07	4.6	0.03	4.1	<0.1	<0.05	5	<0.5	<0.2
K954654	Soil	55	0.92	72	0.055	2	1.66	0.037	0.06	3.7	0.02	7.6	<0.1	<0.05	6	<0.5	<0.2
K954655	Soil	49	0.79	119	0.055	3	1.57	0.053	0.08	2.3	0.05	5.3	0.1	0.08	6	<0.5	<0.2
K954656	Soil	39	0.78	111	0.108	2	1.43	0.110	0.06	2.9	0.03	6.8	<0.1	<0.05	5	<0.5	<0.2
K954657	Soil	36	0.58	120	0.024	2	1.23	0.018	0.06	1.8	0.05	4.9	<0.1	0.08	5	<0.5	<0.2
K954658	Soil	47	1.09	46	0.008	3	1.36	0.020	0.06	1.8	0.05	7.8	<0.1	0.06	5	0.6	<0.2
K954659	Soil	49	0.92	57	0.083	2	1.33	0.035	0.07	3.2	0.11	6.0	<0.1	<0.05	5	<0.5	<0.2
K954660	Soil	50	1.05	93	0.104	2	1.84	0.051	0.08	3.1	0.06	5.4	<0.1	<0.05	6	<0.5	<0.2
K954661	Soil	67	0.98	92	0.110	2	1.73	0.129	0.07	1.8	0.05	7.1	<0.1	<0.05	6	<0.5	<0.2
K954662	Soil	56	1.08	70	0.104	2	1.70	0.061	0.07	1.7	0.06	5.4	<0.1	<0.05	6	<0.5	<0.2
K954663	Soil	71	1.56	69	0.097	3	2.15	0.065	0.07	1.6	0.04	10.3	<0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K954664	Soil	0.6	26.5	49.6	71	0.3	40.3	18.2	582	3.01	17.7	1.4	6.2	44	0.4	0.9	0.2	75	0.71	0.097	34
K954665	Soil	0.9	44.8	11.3	141	0.2	39.4	19.4	612	3.46	16.9	2.7	3.4	26	1.0	0.9	0.2	90	0.60	0.066	16
K954666	Soil	0.8	32.8	20.8	47	0.2	36.6	15.6	485	2.67	9.8	0.6	4.8	40	<0.1	0.7	0.1	79	0.86	0.071	20
K954667	Soil	0.7	24.6	4.9	63	0.7	22.9	13.4	550	2.80	7.2	1.0	0.6	16	0.1	0.6	0.1	91	0.49	0.060	5
K954668	Soil	1.1	40.7	24.6	64	0.5	30.5	19.1	685	3.11	14.6	1.2	0.9	23	0.2	0.9	0.1	85	0.83	0.069	7
K954669	Soil	0.9	32.0	4.5	87	0.5	28.9	16.7	666	3.52	13.1	<0.5	0.7	16	0.2	0.9	<0.1	87	0.59	0.053	5
K954670	Soil	1.3	41.2	63.2	106	0.4	32.9	14.0	785	2.70	42.3	2.6	0.9	21	0.4	1.4	0.2	52	0.71	0.059	8
K954671	Soil	1.2	52.7	5.8	81	0.5	116.3	28.9	1167	3.92	34.1	1.5	1.1	53	0.3	0.8	0.1	97	0.89	0.083	9
K954672	Soil	1.1	59.9	41.7	76	0.5	29.8	18.8	761	3.65	37.0	2.6	1.3	28	0.2	1.0	0.2	105	0.87	0.059	8
K954673	Soil	0.6	45.5	3.4	58	0.3	27.9	20.1	728	3.79	9.3	0.7	1.4	27	0.2	0.3	<0.1	112	0.74	0.025	5
K954674	Soil	0.7	34.1	9.5	41	0.7	27.0	15.0	461	2.66	13.5	2.7	2.2	15	0.1	0.8	<0.1	78	0.47	0.045	7
K954675	Soil	0.6	35.0	3.5	51	0.4	29.5	21.5	385	3.76	8.8	1.6	2.3	19	0.2	0.4	<0.1	102	0.61	0.052	8
K954676	Soil	0.4	42.8	12.9	98	0.1	22.9	14.7	726	3.48	21.4	4.4	0.6	5	0.2	0.8	<0.1	59	0.20	0.026	4
K954677	Soil	0.8	66.3	4.9	56	0.1	39.8	20.8	714	3.98	14.7	3.2	1.1	16	0.1	0.7	0.1	108	0.45	0.055	7
K954678	Soil	1.0	47.8	84.2	54	0.3	27.7	16.4	708	3.18	9.9	4.7	1.1	24	0.2	0.6	<0.1	84	0.55	0.063	8
K954679	Soil	0.6	31.4	10.7	37	0.3	21.3	11.5	352	2.16	6.6	2.0	2.7	70	<0.1	0.4	<0.1	58	0.55	0.044	12
K954680	Soil	0.9	26.1	43.6	59	0.3	29.0	20.1	593	3.71	15.3	1.0	1.6	40	0.1	0.7	0.2	126	1.13	0.055	6
K954681	Soil	0.5	21.9	6.5	48	0.2	113.0	17.9	706	3.37	8.9	1.8	0.9	19	<0.1	1.0	0.1	80	0.63	0.050	6
K954682	Soil	0.7	16.6	6.3	78	0.4	27.3	16.5	602	3.29	13.7	2.4	1.3	17	0.2	0.6	0.1	79	0.55	0.041	6
K954683	Soil	0.6	29.3	6.4	50	0.2	33.2	18.0	540	3.27	12.6	3.6	1.2	15	0.2	0.8	0.2	105	0.50	0.042	7
K954684	Soil	0.9	29.1	10.8	61	0.7	28.0	19.0	941	3.30	9.8	2.0	0.8	40	0.2	0.6	0.3	108	1.03	0.084	6
K954685	Soil	0.9	26.4	5.7	44	0.5	26.6	17.0	514	3.24	13.2	3.3	0.8	18	0.1	0.7	0.2	97	0.85	0.051	5
K954686	Soil	1.1	30.5	5.8	48	0.3	27.4	20.5	699	3.49	15.0	5.1	1.0	15	0.1	0.8	0.2	93	0.44	0.047	7
K954687	Soil	0.8	38.4	7.5	59	0.5	32.7	20.4	681	3.63	13.1	1.2	1.3	19	0.2	0.7	<0.1	103	0.71	0.051	8
K954688	Soil	0.8	30.3	9.6	54	0.3	25.8	16.1	582	2.87	8.0	1.7	2.7	18	0.1	0.4	0.1	82	0.92	0.058	13
K954689	Soil	0.3	69.0	3.4	48	0.9	32.6	21.3	767	3.56	4.0	2.5	0.5	31	0.1	0.3	<0.1	96	2.17	0.031	2
K954690	Soil	1.1	27.9	6.8	46	0.4	27.0	15.0	506	3.10	9.5	7.7	1.0	12	0.1	0.8	0.1	93	0.48	0.039	6
K954691	Soil	0.3	60.4	2.6	60	<0.1	60.2	29.1	975	5.06	4.3	3.4	0.5	18	0.1	0.4	<0.1	141	1.14	0.032	2
K954692	Soil	1.4	26.2	6.1	37	0.2	23.2	14.4	432	3.09	12.2	2.2	1.8	10	<0.1	1.1	0.1	87	0.33	0.047	8
K954693	Soil	1.0	32.6	8.9	45	0.3	27.7	14.6	451	3.01	9.5	4.5	2.4	11	<0.1	0.5	0.1	87	0.31	0.046	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K954664	Soil	57	1.36	90	0.051	3	1.74	0.037	0.12	2.3	0.02	5.3	<0.1	<0.05	6	<0.5	<0.2
K954665	Soil	63	1.24	97	0.077	3	1.78	0.042	0.08	1.8	0.03	7.7	<0.1	<0.05	6	<0.5	<0.2
K954666	Soil	68	1.13	78	0.073	2	1.46	0.066	0.09	1.5	0.02	7.2	<0.1	<0.05	5	<0.5	<0.2
K954667	Soil	36	0.63	96	0.072	2	1.00	0.060	0.13	2.3	0.03	4.9	<0.1	<0.05	5	<0.5	<0.2
K954668	Soil	59	0.91	88	0.071	3	1.44	0.039	0.07	3.0	0.05	7.7	<0.1	<0.05	5	<0.5	<0.2
K954669	Soil	53	1.10	49	0.109	3	1.80	0.047	0.08	3.1	0.04	7.9	<0.1	<0.05	7	<0.5	<0.2
K954670	Soil	44	0.67	67	0.027	3	1.33	0.033	0.08	3.3	0.05	6.1	<0.1	<0.05	5	<0.5	<0.2
K954671	Soil	157	1.40	130	0.084	3	2.18	0.045	0.09	1.4	0.05	8.9	0.1	<0.05	7	<0.5	<0.2
K954672	Soil	51	1.12	95	0.066	3	2.00	0.076	0.11	1.6	0.04	9.1	0.1	<0.05	8	<0.5	<0.2
K954673	Soil	72	0.97	86	0.043	2	2.23	0.088	0.05	1.3	0.03	13.2	<0.1	<0.05	6	<0.5	<0.2
K954674	Soil	46	0.69	51	0.103	2	1.30	0.053	0.05	2.6	0.01	6.3	<0.1	<0.05	5	<0.5	<0.2
K954675	Soil	43	1.24	50	0.157	2	1.81	0.062	0.05	1.2	0.05	7.0	<0.1	<0.05	7	<0.5	<0.2
K954676	Soil	41	0.14	25	0.010	3	0.49	0.014	0.03	2.6	0.86	7.6	<0.1	<0.05	2	<0.5	<0.2
K954677	Soil	81	1.03	61	0.046	3	1.81	0.027	0.05	0.9	0.04	11.6	<0.1	0.11	6	<0.5	<0.2
K954678	Soil	58	0.83	70	0.057	3	1.71	0.035	0.05	2.2	0.03	9.5	<0.1	<0.05	6	<0.5	<0.2
K954679	Soil	43	0.70	97	0.058	5	1.71	0.043	0.07	1.7	0.04	4.5	<0.1	<0.05	4	<0.5	<0.2
K954680	Soil	67	0.99	84	0.186	2	1.98	0.076	0.09	2.0	0.05	8.6	<0.1	0.05	7	<0.5	<0.2
K954681	Soil	101	1.61	69	0.078	3	1.48	0.081	0.06	1.7	0.04	5.5	<0.1	<0.05	5	<0.5	<0.2
K954682	Soil	50	1.11	105	0.062	2	1.72	0.055	0.17	2.5	0.04	5.9	0.1	<0.05	8	<0.5	<0.2
K954683	Soil	52	0.94	87	0.097	1	1.68	0.051	0.08	2.6	0.02	6.0	<0.1	<0.05	6	<0.5	<0.2
K954684	Soil	66	0.92	117	0.076	2	2.21	0.172	0.09	1.5	0.11	7.0	<0.1	<0.05	7	<0.5	<0.2
K954685	Soil	51	0.80	59	0.074	1	1.77	0.115	0.07	2.5	0.02	6.3	<0.1	<0.05	7	<0.5	<0.2
K954686	Soil	49	0.92	78	0.062	<1	1.60	0.046	0.07	2.3	0.04	7.4	<0.1	<0.05	7	<0.5	<0.2
K954687	Soil	51	1.08	80	0.093	1	1.74	0.086	0.08	2.0	0.01	7.5	<0.1	<0.05	6	<0.5	<0.2
K954688	Soil	45	0.91	100	0.080	2	1.60	0.142	0.13	1.7	0.02	6.2	<0.1	<0.05	6	<0.5	<0.2
K954689	Soil	66	1.95	54	0.103	3	2.66	0.110	0.12	1.1	0.02	7.0	<0.1	<0.05	6	<0.5	<0.2
K954690	Soil	51	0.80	76	0.084	<1	1.43	0.061	0.07	2.7	0.03	5.4	<0.1	<0.05	6	<0.5	<0.2
K954691	Soil	115	2.49	57	0.052	1	2.80	0.028	0.05	0.7	<0.01	13.0	<0.1	<0.05	7	<0.5	<0.2
K954692	Soil	41	0.60	65	0.063	<1	1.35	0.045	0.06	3.4	0.03	5.3	<0.1	<0.05	5	<0.5	<0.2
K954693	Soil	46	0.63	68	0.064	<1	1.49	0.036	0.08	2.2	0.03	4.7	0.1	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K954694	Soil	0.8	38.8	5.8	41	0.1	30.1	14.8	473	2.77	13.0	2.0	1.2	14	0.1	0.6	0.1	78	0.39	0.042	7
K954695	Soil	0.8	23.5	6.4	56	<0.1	32.0	15.7	531	3.07	13.6	1.2	0.7	8	<0.1	0.6	<0.1	68	0.26	0.049	8
K954696	Soil	1.3	48.1	4.0	69	0.5	27.4	16.2	874	3.46	23.3	0.5	0.7	20	0.3	0.9	<0.1	80	0.91	0.046	4
K954697	Soil	0.9	26.5	6.0	33	0.7	23.4	12.1	413	2.35	10.8	3.5	0.7	16	0.1	0.6	<0.1	72	0.44	0.054	6
K954698	Soil	0.6	38.1	7.1	50	0.6	27.3	15.5	601	2.81	13.0	1.7	1.4	27	<0.1	0.7	<0.1	85	0.54	0.036	6
K954699	Soil	0.5	49.6	9.8	50	0.6	35.3	19.8	640	3.25	15.0	1.2	1.2	53	0.1	0.5	<0.1	118	1.07	0.039	4
K954700	Soil	0.5	32.6	20.8	58	0.4	30.6	17.0	854	3.12	14.8	4.1	2.8	25	0.3	1.0	<0.1	76	0.72	0.085	18
K960051	Soil	0.2	7.9	6.8	28	0.7	4.7	3.3	155	0.81	1.5	<0.5	1.2	6	<0.1	<0.1	1.1	13	0.08	0.033	5
K960052	Soil	0.3	24.1	7.4	50	0.5	10.7	7.6	544	2.18	3.2	2.8	2.7	34	0.2	<0.1	0.3	38	1.44	0.057	9
K960053	Soil	0.3	18.8	7.2	34	0.6	10.8	6.9	325	1.42	3.0	154.6	0.9	5	<0.1	0.1	1.0	27	0.14	0.043	4
K960054	Soil	0.7	11.5	7.4	45	0.7	10.7	6.4	273	1.66	5.4	1.8	3.0	25	0.2	0.2	0.7	30	0.18	0.058	15
K960055	Soil	0.8	32.9	11.1	54	0.5	17.2	10.1	464	2.30	8.5	5.8	3.3	10	0.2	0.2	0.7	40	0.17	0.055	13
K960056	Soil	0.5	8.0	6.3	36	0.4	7.8	5.2	247	1.52	3.5	<0.5	5.9	7	0.1	0.2	0.7	22	0.15	0.059	14
K960057	Soil	0.8	36.6	12.5	53	0.5	17.5	9.3	455	2.14	6.8	7.1	4.2	9	0.1	0.3	0.7	36	0.15	0.052	13
K960058	Soil	0.3	11.3	11.7	41	0.4	11.9	6.2	261	1.67	3.8	1.6	6.1	8	0.1	0.4	1.0	23	0.18	0.069	16
K960059	Soil	0.6	19.5	10.4	58	0.3	15.1	14.6	629	3.28	44.0	3.3	3.3	6	0.2	16.4	0.2	47	0.10	0.050	10
K960060	Soil	0.4	24.2	6.5	47	0.4	12.2	10.5	527	2.57	53.2	3.0	2.8	10	0.1	5.3	0.1	39	0.16	0.054	11
K960061	Soil	0.7	49.9	15.7	67	0.6	17.4	12.8	496	2.40	214.1	13.1	3.7	7	0.3	12.2	0.4	28	0.10	0.046	12
K960062	Soil	0.6	43.3	10.6	55	0.5	14.3	12.5	633	2.67	80.0	8.9	3.7	17	0.4	8.7	0.3	38	0.74	0.050	12
K960063	Soil	1.0	27.4	7.1	45	0.4	15.3	16.8	971	2.84	39.8	3.1	3.0	12	0.2	5.5	0.2	46	0.21	0.072	9
K960064	Soil	1.1	25.0	9.5	44	0.8	20.3	9.1	457	2.33	40.1	2.8	3.8	8	0.1	4.6	0.3	37	0.11	0.039	14
K960065	Soil	0.5	8.4	7.5	47	0.3	7.1	4.1	263	1.27	18.0	0.9	6.6	6	0.1	1.7	0.3	13	0.10	0.039	18
K960066	Soil	3.5	142.0	9.1	84	0.9	27.6	24.6	1001	5.05	86.3	16.3	2.0	12	0.2	24.6	0.3	59	0.34	0.072	12
K960067	Soil	0.6	24.3	10.1	43	0.7	30.1	12.4	377	2.36	23.2	3.6	7.5	10	<0.1	1.9	0.2	30	0.18	0.061	26
K960068	Soil	0.3	41.6	5.0	55	0.2	15.2	12.8	541	2.65	5.8	4.1	2.9	14	0.1	0.8	0.7	48	0.31	0.066	9
K960069	Soil	0.6	12.1	8.2	38	0.7	13.5	9.8	511	1.94	8.2	4.0	3.5	7	<0.1	0.6	0.3	38	0.13	0.090	12
K960070	Soil	0.6	20.8	7.3	45	0.4	29.2	11.4	366	2.39	16.8	19.4	6.5	9	<0.1	1.4	0.3	33	0.18	0.073	17
K960071	Soil	0.7	26.8	10.6	51	0.4	47.7	17.2	570	2.84	45.3	28.6	7.9	12	<0.1	4.2	0.3	38	0.22	0.091	25
K960072	Soil	0.7	27.1	6.6	45	0.8	36.6	14.2	493	2.55	12.9	3.3	4.2	11	0.1	1.8	0.5	43	0.27	0.101	14
K960073	Soil	1.2	31.8	7.9	63	0.4	53.5	21.9	634	3.37	20.3	14.0	6.6	34	0.2	3.2	0.3	50	0.98	0.134	28

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K954694	Soil	46	0.57	81	0.055	<1	1.41	0.033	0.06	1.8	0.02	5.4	<0.1	<0.05	5	<0.5	<0.2
K954695	Soil	37	0.45	54	0.030	<1	1.06	0.035	0.05	2.1	0.04	6.1	<0.1	<0.05	4	<0.5	<0.2
K954696	Soil	49	0.69	78	0.042	<1	1.26	0.054	0.07	2.9	0.08	9.4	0.1	<0.05	5	<0.5	<0.2
K954697	Soil	43	0.56	92	0.073	<1	1.29	0.041	0.08	3.4	0.05	3.8	<0.1	<0.05	5	<0.5	<0.2
K954698	Soil	59	0.87	84	0.090	<1	1.73	0.065	0.10	1.9	0.02	4.7	<0.1	<0.05	6	<0.5	<0.2
K954699	Soil	77	1.47	107	0.140	2	2.73	0.156	0.20	1.1	0.03	7.3	<0.1	<0.05	8	<0.5	<0.2
K954700	Soil	42	0.87	65	0.017	2	1.80	0.041	0.06	1.2	0.05	6.3	<0.1	<0.05	6	<0.5	<0.2
K960051	Soil	11	0.22	28	0.029	<1	0.50	0.023	0.13	7.9	<0.01	0.9	0.2	<0.05	2	<0.5	<0.2
K960052	Soil	19	0.74	395	0.064	<1	1.10	0.014	0.24	3.4	<0.01	3.8	0.1	<0.05	4	<0.5	<0.2
K960053	Soil	22	0.60	64	0.015	<1	0.86	0.024	0.06	7.2	<0.01	1.9	<0.1	<0.05	3	<0.5	<0.2
K960054	Soil	18	0.46	74	0.062	<1	1.23	0.014	0.19	5.2	<0.01	1.8	0.2	<0.05	5	<0.5	<0.2
K960055	Soil	33	0.87	100	0.069	<1	1.55	0.011	0.18	4.0	<0.01	2.9	0.2	<0.05	5	<0.5	<0.2
K960056	Soil	14	0.39	56	0.068	<1	1.01	0.017	0.24	5.8	<0.01	1.6	0.2	<0.05	4	<0.5	<0.2
K960057	Soil	28	0.83	86	0.056	<1	1.35	0.013	0.13	6.5	<0.01	2.9	0.2	<0.05	5	<0.5	<0.2
K960058	Soil	17	0.47	70	0.085	<1	1.26	0.010	0.23	6.2	<0.01	2.1	0.3	<0.05	4	<0.5	<0.2
K960059	Soil	18	0.73	104	0.006	<1	1.22	0.006	0.08	3.8	0.11	5.2	0.1	<0.05	3	<0.5	<0.2
K960060	Soil	15	0.74	98	0.016	<1	1.32	0.009	0.07	3.5	0.04	3.7	<0.1	<0.05	4	<0.5	<0.2
K960061	Soil	17	0.49	74	0.009	<1	0.99	0.006	0.09	5.4	0.11	2.6	<0.1	<0.05	3	<0.5	<0.2
K960062	Soil	17	0.73	185	0.013	<1	1.24	0.007	0.11	4.0	0.04	4.1	<0.1	<0.05	4	<0.5	<0.2
K960063	Soil	28	0.92	194	0.025	<1	1.27	0.006	0.10	2.4	0.08	3.3	<0.1	<0.05	4	<0.5	<0.2
K960064	Soil	23	0.44	66	0.031	<1	1.03	0.006	0.10	3.7	0.02	2.3	0.1	<0.05	4	<0.5	<0.2
K960065	Soil	9	0.25	44	0.022	<1	0.62	0.018	0.15	6.3	<0.01	0.9	0.2	<0.05	3	<0.5	<0.2
K960066	Soil	10	0.43	279	0.006	<1	1.04	0.004	0.07	2.8	0.09	5.5	<0.1	<0.05	3	0.7	0.6
K960067	Soil	32	0.57	68	0.028	<1	1.18	0.008	0.08	4.0	0.01	2.4	<0.1	<0.05	4	<0.5	<0.2
K960068	Soil	16	0.85	228	0.031	3	1.32	0.021	0.22	2.7	<0.01	4.4	<0.1	<0.05	5	<0.5	<0.2
K960069	Soil	23	0.39	53	0.042	2	0.88	0.009	0.12	3.2	0.03	2.0	0.1	<0.05	5	<0.5	<0.2
K960070	Soil	34	0.66	82	0.020	2	1.23	0.007	0.12	5.1	0.01	2.9	0.1	<0.05	5	<0.5	<0.2
K960071	Soil	52	0.79	92	0.022	3	1.35	0.012	0.09	4.1	0.02	3.8	<0.1	<0.05	4	<0.5	0.3
K960072	Soil	44	0.79	59	0.034	2	1.20	0.014	0.12	5.7	0.04	3.0	0.1	<0.05	5	<0.5	<0.2
K960073	Soil	50	1.12	124	0.026	2	1.43	0.008	0.07	4.1	0.06	5.0	<0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960074	Soil	0.7	13.5	8.0	35	0.4	22.8	10.1	430	2.24	17.3	<0.5	5.3	8	0.2	1.3	0.3	34	0.15	0.056	14
K960075	Soil	1.2	39.5	18.0	240	0.4	60.8	28.6	986	5.79	9.8	6.3	7.8	9	0.7	19.6	0.4	83	0.20	0.091	18
K960076	Soil	0.8	17.4	6.6	36	0.9	26.9	10.0	230	2.18	15.6	17.4	5.5	7	0.1	1.3	0.3	27	0.10	0.050	17
K960077	Soil	0.9	15.8	6.4	37	0.3	17.4	8.2	291	1.86	9.5	4.5	5.6	10	<0.1	0.6	1.5	28	0.17	0.053	14
K960078	Soil	1.3	24.6	9.9	75	0.2	70.8	24.1	794	4.44	35.1	1.6	7.0	24	<0.1	2.6	0.3	82	0.43	0.117	29
K960079	Soil	1.2	76.2	8.4	58	0.2	92.3	26.0	731	5.53	159.8	3.6	16.0	75	0.2	4.7	0.3	89	2.10	0.166	72
K960080	Soil	0.9	19.5	8.0	33	0.3	24.0	9.1	347	2.16	87.1	<0.5	7.2	16	<0.1	7.0	0.3	19	0.19	0.036	18
K960081	Soil	0.5	19.4	9.1	41	0.3	23.8	10.2	416	2.00	278.6	1.3	7.0	11	<0.1	7.4	0.4	19	0.17	0.063	22
K960082	Soil	0.7	17.1	8.6	36	0.7	18.5	9.6	347	1.98	49.8	2.0	6.4	9	<0.1	27.1	0.4	25	0.15	0.059	15
K960083	Soil	0.4	12.9	7.9	31	0.3	15.7	7.6	317	1.61	16.7	1.4	4.8	12	<0.1	3.8	0.3	23	0.19	0.058	17
K960084	Soil	0.6	12.4	10.4	33	0.5	15.9	7.4	264	2.15	27.4	1.2	5.5	9	<0.1	10.3	0.3	33	0.12	0.039	17
K960085	Soil	0.4	12.5	7.4	37	0.4	17.0	8.0	370	1.67	16.3	0.8	5.4	11	<0.1	3.9	0.4	19	0.20	0.062	16
K960086	Soil	0.6	26.1	18.2	54	0.2	22.0	12.7	345	3.01	36.0	9.8	9.8	11	0.1	6.4	0.2	17	0.12	0.063	46
K960087	Soil	0.7	15.8	8.6	39	0.9	18.2	9.1	440	2.22	22.8	<0.5	5.3	9	<0.1	6.4	0.4	31	0.13	0.049	15
K960088	Soil	0.6	12.5	9.6	29	0.2	17.6	8.2	288	1.86	159.3	1.5	6.9	7	<0.1	15.7	0.2	15	0.08	0.032	22
K960089	Soil	0.6	25.1	16.2	47	0.5	31.3	18.7	243	2.10	42.7	2.4	9.4	7	<0.1	11.6	0.2	6	0.04	0.028	36
K960091	Soil	0.6	18.1	6.7	44	0.2	24.7	11.7	404	2.41	4.4	1.1	4.3	13	0.1	0.5	<0.1	38	0.22	0.074	15
K960092	Soil	0.7	41.4	6.9	38	0.2	28.4	14.8	436	2.02	6.4	2.2	2.6	12	<0.1	0.5	<0.1	38	0.35	0.054	10
K960093	Soil	0.5	46.6	16.9	76	0.1	38.6	17.9	739	3.61	22.2	1.5	12.0	10	0.1	0.6	0.2	48	0.26	0.054	17
K960094	Soil	0.8	47.3	7.2	58	0.4	60.5	23.1	704	3.30	12.8	1.8	4.8	13	0.2	0.6	<0.1	54	0.35	0.064	14
K960095	Soil	0.8	22.3	5.6	39	0.2	52.7	13.1	812	2.14	6.5	1.2	1.8	32	0.3	0.5	<0.1	28	0.73	0.094	8
K960096	Soil	0.9	14.4	7.5	38	0.3	12.9	6.2	238	1.92	3.9	0.9	3.4	14	<0.1	0.4	0.1	35	0.31	0.051	9
K960097	Soil	1.5	17.7	8.9	47	0.2	21.9	8.5	921	2.01	4.0	1.1	2.5	15	0.2	0.5	0.1	34	0.30	0.086	10
K960099	Soil	3.8	30.5	7.9	78	0.3	34.9	11.4	397	2.06	5.4	1.7	4.0	12	0.3	0.7	0.1	42	0.24	0.077	15
K960100	Soil	1.3	30.7	9.9	47	0.3	36.4	12.7	513	2.16	3.0	0.9	4.1	18	0.2	0.3	0.1	36	0.33	0.099	14
K960101	Soil	0.2	59.0	6.2	45	5.6	97.0	29.6	520	2.65	6.5	22.3	0.8	12	<0.1	0.3	0.2	53	0.25	0.042	4
K960102	Soil	0.2	128.0	6.6	80	4.9	94.6	31.0	1002	4.40	6.4	3.8	1.5	31	0.2	0.3	0.1	105	0.64	0.118	5
K960103	Soil	0.3	69.1	9.7	57	4.3	158.5	25.5	739	3.27	7.8	4.6	1.3	16	0.2	0.3	0.2	74	0.36	0.059	6
K960104	Soil	0.5	130.7	7.2	104	3.6	40.3	24.2	1013	4.81	4.2	5.0	1.5	47	0.4	0.8	<0.1	97	0.74	0.168	16
K960105	Soil	0.4	52.4	10.8	72	2.1	21.3	16.6	602	3.60	4.8	1.2	1.6	14	0.2	0.3	0.1	74	0.24	0.078	7

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960074	Soil	33	0.44	79	0.036	2	1.56	0.007	0.08	3.4	0.01	2.5	0.1	<0.05	4	<0.5	<0.2
K960075	Soil	116	2.28	76	0.011	2	2.77	0.006	0.07	2.3	0.01	7.3	<0.1	0.05	9	<0.5	<0.2
K960076	Soil	35	0.49	51	0.023	2	1.10	0.005	0.10	7.4	0.03	2.2	0.1	<0.05	4	<0.5	<0.2
K960077	Soil	26	0.47	65	0.044	2	0.99	0.015	0.15	5.7	0.01	2.0	0.2	<0.05	4	<0.5	<0.2
K960078	Soil	110	1.48	182	0.106	2	2.38	0.014	0.26	1.8	0.01	6.4	0.2	<0.05	9	<0.5	<0.2
K960079	Soil	124	1.92	154	0.019	2	2.50	0.008	0.06	1.1	0.03	6.6	<0.1	<0.05	10	0.5	<0.2
K960080	Soil	25	0.29	118	0.013	2	0.79	0.005	0.09	3.7	0.08	2.4	0.1	<0.05	3	<0.5	<0.2
K960081	Soil	22	0.36	59	0.017	2	0.93	0.007	0.10	4.4	0.04	2.3	0.1	<0.05	3	<0.5	<0.2
K960082	Soil	25	0.37	42	0.032	2	0.98	0.006	0.11	4.7	0.03	2.1	<0.1	<0.05	3	<0.5	<0.2
K960083	Soil	19	0.36	67	0.034	2	0.86	0.011	0.10	3.8	0.02	1.5	<0.1	<0.05	3	<0.5	<0.2
K960084	Soil	24	0.36	53	0.034	2	1.10	0.005	0.09	4.2	0.02	2.2	<0.1	<0.05	4	<0.5	<0.2
K960085	Soil	20	0.40	51	0.030	1	0.85	0.010	0.15	4.1	0.02	1.5	0.1	<0.05	3	<0.5	<0.2
K960086	Soil	13	0.17	50	0.010	2	0.78	0.004	0.09	2.3	0.02	1.5	<0.1	<0.05	2	<0.5	<0.2
K960087	Soil	29	0.41	49	0.037	2	1.12	0.007	0.12	5.5	0.03	2.1	0.1	<0.05	4	<0.5	<0.2
K960088	Soil	29	0.22	49	0.009	1	0.66	0.005	0.07	6.0	0.04	1.5	<0.1	<0.05	2	<0.5	<0.2
K960089	Soil	10	0.05	35	0.001	3	0.35	0.002	0.13	6.5	0.15	1.3	<0.1	<0.05	<1	<0.5	<0.2
K960091	Soil	35	0.65	162	0.067	2	1.10	0.010	0.23	5.7	0.02	3.0	0.2	<0.05	4	<0.5	<0.2
K960092	Soil	51	0.65	74	0.051	2	0.88	0.013	0.09	2.7	0.02	3.0	<0.1	<0.05	3	<0.5	<0.2
K960093	Soil	47	1.25	80	0.018	1	1.55	0.006	0.15	1.9	<0.01	7.0	0.1	<0.05	6	<0.5	<0.2
K960094	Soil	88	1.81	100	0.034	2	1.60	0.007	0.11	1.9	0.01	5.7	<0.1	<0.05	4	<0.5	<0.2
K960095	Soil	64	0.92	130	0.018	3	0.86	0.010	0.09	3.5	0.05	2.3	<0.1	0.08	3	<0.5	<0.2
K960096	Soil	20	0.46	151	0.016	1	0.90	0.005	0.07	4.5	<0.01	2.3	<0.1	<0.05	3	<0.5	<0.2
K960097	Soil	25	0.52	202	0.032	1	0.99	0.006	0.10	2.4	0.02	2.6	<0.1	<0.05	3	<0.5	<0.2
K960099	Soil	30	0.59	111	0.044	1	1.16	0.009	0.11	5.4	0.02	2.6	<0.1	<0.05	3	<0.5	<0.2
K960100	Soil	34	0.63	103	0.061	2	1.03	0.015	0.15	4.1	0.02	2.5	<0.1	<0.05	3	<0.5	<0.2
K960101	Soil	186	1.90	69	0.037	<1	1.70	0.006	0.04	3.4	0.01	3.9	<0.1	<0.05	4	<0.5	<0.2
K960102	Soil	105	2.37	150	0.082	2	2.31	0.010	0.06	2.2	0.03	5.2	<0.1	<0.05	8	<0.5	<0.2
K960103	Soil	181	2.53	149	0.051	3	1.70	0.006	0.08	4.5	0.04	4.7	0.1	<0.05	6	<0.5	<0.2
K960104	Soil	48	1.27	546	0.039	2	1.95	0.040	0.12	0.3	0.03	8.4	<0.1	<0.05	7	<0.5	<0.2
K960105	Soil	42	1.59	144	0.043	<1	1.86	0.005	0.09	2.2	0.03	3.9	<0.1	<0.05	7	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960106	Soil	0.4	32.6	11.8	57	3.8	45.2	13.7	453	2.73	3.7	2.9	2.9	14	0.2	0.3	0.6	49	0.21	0.058	10
K960107	Soil	0.2	44.2	5.0	101	2.5	13.3	14.9	547	3.04	2.2	4.4	4.2	14	1.1	0.2	0.1	46	0.31	0.070	14
K960108	Soil	0.5	17.6	7.4	46	2.6	14.3	8.2	269	1.82	3.0	3.9	4.4	26	0.2	0.3	4.1	34	0.39	0.068	12
K960109	Soil	0.3	15.8	8.9	72	1.9	14.0	8.5	357	1.95	4.1	18.2	5.6	20	0.4	0.2	0.7	27	0.31	0.068	13
K960110	Soil	0.4	30.9	10.7	118	1.4	10.8	12.7	831	3.00	2.4	<0.5	3.9	17	0.2	0.2	0.2	52	0.30	0.101	11
K960111	Soil	0.4	36.2	10.7	73	0.7	16.2	15.6	812	3.39	3.3	2.3	5.0	15	0.1	0.3	0.3	47	0.25	0.093	16
K960112	Soil	0.2	42.9	5.4	98	1.2	11.0	17.8	989	5.07	1.4	<0.5	4.9	39	0.1	0.1	<0.1	150	0.31	0.102	14
K960113	Soil	0.2	55.7	6.3	68	1.2	17.0	18.0	856	3.77	2.3	<0.5	3.6	12	0.2	0.2	0.2	80	0.29	0.096	12
K960114	Soil	0.4	119.7	12.6	92	2.6	27.8	27.7	1052	5.26	86.0	47.5	3.0	92	0.4	0.9	0.2	135	1.79	0.079	9
K960115	Soil	0.6	44.6	26.8	58	3.4	42.8	19.3	789	3.55	48.3	12.7	3.3	25	0.2	1.1	0.7	65	0.31	0.091	24
K960116	Soil	0.4	40.2	12.8	50	2.3	19.5	12.9	492	2.53	26.5	7.3	2.1	20	0.2	0.7	2.7	47	0.31	0.053	7
K960117	Soil	0.4	45.4	20.6	64	1.4	23.0	13.3	507	2.91	33.6	9.0	2.0	22	0.2	0.6	1.1	53	0.31	0.054	8
K960118	Soil	0.4	48.4	13.5	58	1.0	35.3	18.6	671	3.51	66.5	25.0	1.4	11	0.1	0.7	0.6	74	0.19	0.046	6
K960119	Soil	0.6	43.9	7.7	97	1.1	46.8	20.4	824	4.49	19.2	13.4	1.7	92	0.1	0.2	0.1	74	0.89	0.220	32
K960120	Soil	0.2	73.4	8.0	70	1.5	11.7	16.9	826	3.31	7.4	3.4	1.7	26	0.1	0.4	0.3	89	0.41	0.083	5
K960121	Soil	0.2	52.1	8.8	53	1.1	20.2	14.9	479	2.62	3.5	2.1	2.5	47	<0.1	0.2	1.7	68	0.53	0.058	7
K960122	Soil	0.2	23.2	13.0	44	2.4	9.2	7.3	309	1.60	2.5	1.6	1.8	25	<0.1	0.2	1.7	33	0.21	0.060	8
K960123	Soil	0.3	13.6	8.6	54	2.9	13.2	6.6	330	1.56	2.6	0.6	3.2	35	<0.1	0.3	1.4	23	0.25	0.056	11
K960124	Soil	0.5	61.4	17.0	56	1.0	17.5	14.8	569	3.15	10.3	4.8	1.4	14	0.1	0.4	0.3	72	0.22	0.072	8
K960125	Soil	0.2	55.5	16.8	73	1.7	25.8	17.1	659	3.59	9.4	3.0	2.5	21	0.2	0.5	0.7	70	0.24	0.073	10
K960126	Soil	0.3	42.6	10.8	70	0.6	13.5	13.7	705	3.47	9.2	5.6	2.4	21	0.2	0.2	0.4	83	0.57	0.128	11
K960127	Soil	0.3	37.5	15.7	52	1.2	16.8	11.2	510	2.62	11.7	22.2	3.5	11	0.2	0.4	0.4	45	0.17	0.060	12
K960128	Soil	0.2	20.2	8.1	50	1.0	7.5	7.7	402	2.34	7.1	5.2	6.4	9	0.1	0.2	0.2	45	0.14	0.054	15
K960129	Soil	0.3	41.8	9.2	49	1.7	14.0	10.5	529	2.45	6.7	1.4	2.4	10	0.1	0.2	0.3	53	0.19	0.070	10
K960130	Soil	0.3	46.8	9.8	55	1.1	19.9	13.4	602	2.78	5.9	2.6	2.5	10	0.1	0.4	0.3	56	0.21	0.072	10
K960131	Soil	0.2	26.3	10.9	48	1.1	12.7	8.8	575	2.08	4.0	1.3	6.5	17	0.1	0.2	0.4	32	0.26	0.093	16
K960132	Soil	0.3	31.4	11.8	39	1.4	16.5	9.6	418	2.08	5.4	175.4	3.2	8	0.1	0.3	0.4	40	0.16	0.062	11
K960133	Soil	0.3	40.2	8.9	46	1.0	19.2	10.6	500	2.29	6.1	3.3	5.3	9	0.1	0.2	0.3	41	0.20	0.074	16
K960134	Soil	0.2	21.8	13.4	43	0.6	13.6	8.2	394	1.83	9.0	14.3	6.9	7	0.1	0.2	0.3	31	0.20	0.076	17
K960135	Soil	0.3	45.6	13.2	47	1.3	14.0	8.3	504	2.19	6.4	10.4	4.5	10	0.1	0.3	0.3	34	0.16	0.065	18

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960106	Soil	67	1.25	114	0.080	2	1.65	0.012	0.18	4.6	<0.01	3.2	0.2	<0.05	6	<0.5	<0.2
K960107	Soil	22	1.41	143	0.053	1	1.60	0.006	0.13	4.0	<0.01	3.2	<0.1	<0.05	6	<0.5	<0.2
K960108	Soil	23	0.52	77	0.087	1	1.59	0.041	0.30	9.4	<0.01	2.6	0.3	<0.05	6	<0.5	<0.2
K960109	Soil	24	0.68	286	0.079	<1	1.16	0.020	0.23	7.7	<0.01	2.6	0.2	<0.05	4	<0.5	<0.2
K960110	Soil	17	1.23	265	0.112	<1	1.67	0.009	0.52	2.3	<0.01	3.0	0.3	<0.05	6	<0.5	<0.2
K960111	Soil	23	1.41	311	0.031	<1	1.92	0.006	0.10	2.6	<0.01	4.3	<0.1	<0.05	6	<0.5	<0.2
K960112	Soil	13	2.52	1509	0.152	<1	2.67	0.010	0.66	2.3	<0.01	14.0	0.4	<0.05	13	<0.5	<0.2
K960113	Soil	20	1.88	224	0.100	<1	2.21	0.010	0.44	2.4	<0.01	6.2	0.2	<0.05	8	<0.5	<0.2
K960114	Soil	62	2.30	478	0.029	<1	2.31	0.022	0.07	1.5	0.03	13.3	<0.1	0.08	9	<0.5	<0.2
K960115	Soil	70	1.16	200	0.041	<1	1.62	0.010	0.09	3.3	0.02	5.5	0.2	<0.05	6	<0.5	<0.2
K960116	Soil	42	1.15	222	0.050	<1	1.55	0.013	0.10	5.0	<0.01	3.8	0.2	<0.05	4	<0.5	<0.2
K960117	Soil	47	1.23	116	0.060	<1	1.92	0.019	0.09	2.9	<0.01	3.7	0.1	<0.05	6	<0.5	<0.2
K960118	Soil	78	1.74	118	0.052	<1	2.10	0.007	0.05	3.0	<0.01	5.1	0.1	<0.05	6	<0.5	<0.2
K960119	Soil	77	1.16	465	0.118	<1	1.99	0.066	0.13	0.6	0.02	8.4	<0.1	<0.05	6	<0.5	<0.2
K960120	Soil	16	1.26	126	0.069	<1	1.61	0.014	0.08	2.8	0.01	3.5	<0.1	<0.05	6	<0.5	<0.2
K960121	Soil	45	1.59	124	0.083	<1	2.01	0.026	0.12	3.2	<0.01	5.0	0.1	<0.05	6	<0.5	<0.2
K960122	Soil	14	0.46	71	0.031	2	1.04	0.030	0.10	6.5	<0.01	2.0	0.1	<0.05	4	<0.5	<0.2
K960123	Soil	20	0.34	99	0.055	<1	1.28	0.031	0.18	4.9	0.02	2.0	0.2	<0.05	5	<0.5	<0.2
K960124	Soil	33	1.26	135	0.054	<1	1.87	0.006	0.07	2.6	0.02	3.6	0.1	<0.05	6	<0.5	<0.2
K960125	Soil	64	1.60	314	0.043	<1	2.16	0.013	0.08	3.0	0.02	5.8	0.1	<0.05	7	<0.5	<0.2
K960126	Soil	32	1.43	487	0.058	<1	1.83	0.012	0.14	2.0	<0.01	8.0	0.1	<0.05	8	<0.5	<0.2
K960127	Soil	31	0.97	159	0.058	<1	1.53	0.007	0.14	3.8	<0.01	4.0	0.2	<0.05	5	<0.5	<0.2
K960128	Soil	18	0.93	131	0.079	<1	1.25	0.009	0.18	2.4	<0.01	4.7	0.1	<0.05	6	<0.5	<0.2
K960129	Soil	24	0.86	163	0.059	<1	1.35	0.008	0.11	4.4	0.01	3.3	0.1	<0.05	5	<0.5	<0.2
K960130	Soil	39	1.15	97	0.056	<1	1.63	0.007	0.09	3.4	0.01	3.5	0.1	<0.05	5	<0.5	<0.2
K960131	Soil	24	0.75	133	0.064	<1	1.42	0.016	0.19	4.6	<0.01	3.1	0.2	<0.05	5	<0.5	<0.2
K960132	Soil	32	0.74	102	0.046	<1	1.26	0.009	0.10	5.2	0.01	2.9	0.2	<0.05	4	<0.5	<0.2
K960133	Soil	36	0.93	118	0.055	<1	1.43	0.010	0.14	4.8	<0.01	3.3	0.2	<0.05	5	<0.5	<0.2
K960134	Soil	24	0.69	102	0.056	<1	1.06	0.011	0.22	5.4	<0.01	2.8	0.2	<0.05	4	<0.5	<0.2
K960135	Soil	29	0.75	211	0.046	<1	1.22	0.008	0.12	4.9	0.02	3.3	0.2	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960136	Soil	0.4	30.6	15.2	53	1.3	13.7	10.0	560	2.29	9.8	11.8	4.8	8	0.2	0.2	0.3	34	0.17	0.068	14
K960137	Soil	0.4	10.8	10.2	34	0.8	8.2	4.6	262	1.50	3.9	1.9	3.9	6	<0.1	0.2	0.4	23	0.13	0.053	14
K960138	Soil	0.2	10.6	10.3	29	0.6	10.3	5.1	247	1.27	2.5	<0.5	5.0	5	<0.1	0.2	0.3	16	0.15	0.074	18
K960139	Soil	0.1	10.5	10.6	40	0.5	10.5	5.2	420	1.44	2.8	1.1	8.7	5	0.2	0.2	0.3	13	0.17	0.078	23
K960140	Soil	0.2	60.8	10.4	61	0.7	17.7	14.3	600	3.21	5.0	8.8	4.0	10	0.2	0.3	0.1	54	0.23	0.088	14
K960141	Soil	0.2	10.7	7.2	33	1.0	9.5	4.7	246	1.32	2.5	0.6	4.2	6	<0.1	0.2	0.5	20	0.15	0.067	17
K960142	Soil	0.3	52.3	12.9	54	0.9	23.1	12.9	725	2.61	8.4	8.8	5.0	12	0.1	0.4	0.5	47	0.24	0.092	15
K960143	Soil	0.4	18.9	10.5	45	1.0	12.6	7.0	386	1.71	13.6	39.3	4.0	10	0.1	0.3	0.5	27	0.16	0.080	15
K960144	Soil	0.2	11.7	6.6	28	0.5	6.2	5.1	365	1.06	2.5	2.8	2.7	8	<0.1	0.2	0.8	16	0.14	0.064	11
K960145	Soil	0.2	12.0	9.4	48	0.3	10.0	6.1	539	1.92	9.8	19.2	1.2	71	0.3	0.3	<0.1	13	0.41	0.130	8
K960146	Soil	0.6	10.3	10.6	37	0.7	6.6	4.9	298	1.33	5.4	4.4	5.0	6	0.1	0.3	0.6	16	0.16	0.079	13
K960147	Soil	0.4	11.9	4.6	38	0.3	11.3	6.4	394	2.26	1.7	1.5	4.6	11	<0.1	0.1	0.4	29	0.14	0.054	16
K960148	Soil	0.4	15.9	9.3	50	0.7	14.3	6.7	332	1.71	3.2	2.3	7.1	6	0.2	0.2	0.6	23	0.17	0.086	19
K960149	Soil	0.4	8.8	6.4	41	0.5	6.5	6.6	584	1.31	2.7	<0.5	2.4	6	0.1	0.2	0.8	28	0.16	0.074	8
K960150	Soil	0.4	28.4	11.2	52	0.6	19.5	9.1	437	2.05	5.9	1.9	3.9	10	0.2	0.3	0.6	40	0.15	0.059	11
K960151	Soil	0.6	10.8	5.7	39	0.1	11.8	5.1	265	1.11	3.7	<0.5	4.3	8	0.1	0.5	0.5	23	0.14	0.045	9
K960152	Soil	0.3	6.8	6.8	33	0.5	4.5	3.9	264	0.94	1.0	<0.5	7.0	8	<0.1	0.2	0.8	19	0.14	0.051	15
K960153	Soil	0.2	28.2	4.2	19	0.2	3.1	2.8	209	0.53	1.4	0.7	3.8	6	<0.1	0.6	0.6	12	0.06	0.021	6
K960154	Soil	0.3	7.1	5.0	39	0.4	5.3	4.1	219	1.03	1.3	0.6	5.4	9	0.1	0.2	0.5	22	0.10	0.030	10
K960155	Soil	0.3	19.3	6.1	52	0.5	11.3	7.2	309	1.58	1.2	<0.5	2.9	11	0.1	0.4	0.8	41	0.10	0.034	9
K960156	Soil	12.0	34.3	28.8	60	0.4	15.1	4.2	325	2.00	16.3	<0.5	5.5	39	0.4	2.2	0.6	81	0.08	0.035	12
K960157	Soil	0.3	8.3	4.1	44	0.1	3.3	3.6	228	1.08	1.0	<0.5	2.5	12	0.1	0.2	0.5	22	0.14	0.068	10
K960158	Soil	0.8	12.0	8.8	48	0.3	12.8	6.5	360	1.62	3.1	2.4	6.1	31	0.2	0.4	0.6	34	0.24	0.084	16
K960159	Soil	0.2	6.8	2.1	40	0.2	2.6	3.8	227	1.09	0.5	<0.5	3.2	10	<0.1	0.1	0.3	22	0.12	0.056	11
K960160	Soil	0.4	10.8	7.2	46	0.3	10.2	5.8	317	1.57	2.8	1.4	4.6	22	<0.1	0.4	0.6	30	0.17	0.055	14
K960161	Soil	0.3	5.4	5.1	31	0.1	4.6	3.7	240	0.95	1.2	<0.5	4.6	13	<0.1	0.2	0.4	20	0.12	0.041	10
K960162	Soil	0.3	10.0	9.7	60	0.3	4.9	7.2	1074	1.85	1.2	<0.5	6.7	16	<0.1	0.4	0.3	26	0.19	0.085	20
K960163	Soil	0.2	6.7	3.1	46	0.3	3.3	3.9	279	1.15	0.5	<0.5	7.6	13	<0.1	0.2	0.2	21	0.15	0.059	14
K960164	Soil	0.4	11.1	9.6	50	0.7	7.4	5.8	397	1.44	1.5	<0.5	5.5	40	<0.1	0.5	0.6	26	0.25	0.067	21
K960165	Soil	<0.1	8.9	3.5	43	0.2	3.8	4.1	249	1.11	0.8	<0.5	5.8	12	<0.1	0.4	0.5	22	0.14	0.051	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960136	Soil	26	0.80	154	0.036	<1	1.33	0.007	0.09	4.9	0.03	2.7	0.2	<0.05	4	<0.5	<0.2
K960137	Soil	14	0.34	72	0.042	<1	0.83	0.008	0.13	5.6	<0.01	1.3	0.2	<0.05	4	<0.5	<0.2
K960138	Soil	13	0.35	64	0.040	<1	0.89	0.009	0.14	5.5	0.02	1.2	0.2	<0.05	3	<0.5	<0.2
K960139	Soil	10	0.35	81	0.040	<1	0.89	0.009	0.16	5.1	<0.01	1.1	0.2	<0.05	3	<0.5	<0.2
K960140	Soil	23	1.12	149	0.034	<1	1.57	0.007	0.11	2.9	<0.01	3.3	0.1	<0.05	5	<0.5	<0.2
K960141	Soil	14	0.37	88	0.050	<1	0.88	0.013	0.21	5.0	0.01	1.4	0.3	<0.05	4	<0.5	<0.2
K960142	Soil	41	0.90	227	0.044	<1	1.35	0.006	0.10	4.2	0.01	3.8	0.2	<0.05	4	<0.5	<0.2
K960143	Soil	20	0.42	87	0.045	<1	1.03	0.008	0.13	5.7	<0.01	1.8	0.2	<0.05	4	<0.5	<0.2
K960144	Soil	9	0.36	64	0.027	<1	0.65	0.013	0.12	4.8	<0.01	1.0	0.1	<0.05	3	<0.5	<0.2
K960145	Soil	10	0.44	180	0.047	<1	0.87	0.023	0.07	1.0	<0.01	1.2	<0.1	<0.05	3	<0.5	<0.2
K960146	Soil	11	0.29	72	0.048	<1	0.68	0.009	0.16	4.6	<0.01	1.4	0.2	<0.05	3	<0.5	<0.2
K960147	Soil	29	0.60	172	0.119	<1	1.42	0.017	0.63	3.4	<0.01	2.9	0.6	<0.05	6	<0.5	<0.2
K960148	Soil	17	0.70	41	0.058	<1	1.25	0.008	0.15	4.4	0.01	1.6	0.2	<0.05	4	<0.5	<0.2
K960149	Soil	13	0.32	54	0.061	<1	0.90	0.015	0.18	3.6	<0.01	1.5	0.2	<0.05	4	<0.5	<0.2
K960150	Soil	39	0.85	119	0.053	<1	1.37	0.009	0.12	9.7	<0.01	3.3	0.2	<0.05	5	<0.5	<0.2
K960151	Soil	15	0.34	61	0.048	<1	0.85	0.011	0.14	7.1	<0.01	1.8	0.2	<0.05	4	<0.5	<0.2
K960152	Soil	10	0.27	60	0.067	<1	0.85	0.015	0.28	7.4	<0.01	1.9	0.3	<0.05	4	<0.5	<0.2
K960153	Soil	6	0.13	41	0.028	<1	0.55	0.019	0.13	6.9	<0.01	0.9	0.2	<0.05	2	<0.5	<0.2
K960154	Soil	11	0.27	65	0.075	<1	0.92	0.012	0.28	6.9	0.01	2.0	0.3	<0.05	4	<0.5	<0.2
K960155	Soil	27	0.62	135	0.110	<1	1.72	0.014	0.34	5.9	<0.01	3.3	0.4	<0.05	6	<0.5	<0.2
K960156	Soil	36	0.62	105	0.104	<1	1.72	0.015	0.30	5.9	0.02	4.0	0.4	<0.05	7	1.1	<0.2
K960157	Soil	8	0.28	53	0.049	<1	0.76	0.017	0.25	4.9	0.01	1.5	0.2	<0.05	4	<0.5	<0.2
K960158	Soil	23	0.42	66	0.067	<1	1.28	0.015	0.19	5.8	0.02	2.1	0.3	<0.05	5	<0.5	<0.2
K960159	Soil	6	0.30	45	0.070	<1	0.75	0.041	0.40	7.1	0.02	1.8	0.3	<0.05	4	<0.5	<0.2
K960160	Soil	17	0.39	62	0.063	<1	1.30	0.014	0.18	5.8	0.02	2.0	0.3	<0.05	5	<0.5	<0.2
K960161	Soil	11	0.24	39	0.049	<1	0.76	0.021	0.23	6.5	<0.01	1.7	0.2	<0.05	4	<0.5	<0.2
K960162	Soil	12	0.47	48	0.010	<1	1.31	0.016	0.07	4.6	0.01	1.7	0.1	<0.05	7	<0.5	<0.2
K960163	Soil	10	0.35	46	0.053	<1	0.87	0.025	0.30	5.7	<0.01	1.7	0.3	<0.05	5	<0.5	<0.2
K960164	Soil	15	0.42	52	0.036	<1	1.36	0.013	0.13	5.9	0.02	2.3	0.3	<0.05	6	<0.5	<0.2
K960165	Soil	7	0.31	53	0.068	<1	0.80	0.035	0.31	7.9	0.01	1.9	0.3	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960166	Soil	0.3	9.5	6.8	39	0.5	8.1	5.4	296	1.34	1.9	1.5	7.7	16	0.1	0.6	0.3	26	0.27	0.085	18
K960167	Soil	0.2	7.0	6.7	43	0.5	5.7	5.1	276	1.26	1.6	<0.5	5.4	17	<0.1	1.0	0.4	26	0.21	0.056	13
K960168	Soil	0.4	12.6	10.5	45	0.6	7.7	4.4	352	1.08	1.9	<0.5	2.1	22	0.1	0.7	0.5	21	0.24	0.067	12
K960169	Soil	0.6	17.6	11.3	62	0.4	12.9	8.8	1130	2.21	5.0	<0.5	1.1	22	0.2	0.8	0.6	45	0.18	0.088	12
K960170	Soil	<0.1	8.4	7.1	36	0.1	2.4	3.3	192	0.87	0.5	<0.5	6.2	8	<0.1	<0.1	0.3	17	0.10	0.039	12
K960171	Soil	0.4	10.4	6.2	40	0.2	11.4	5.8	263	1.35	2.7	<0.5	5.3	15	<0.1	0.3	0.7	26	0.24	0.052	14
K960172	Soil	0.4	10.8	7.5	39	0.5	11.2	5.9	276	1.25	2.6	0.8	6.3	15	0.1	0.3	0.4	26	0.23	0.052	13
K960173	Soil	0.3	12.1	6.4	33	0.2	14.1	6.9	280	1.20	3.6	<0.5	4.4	34	<0.1	0.3	0.5	26	0.57	0.050	14
K960174	Soil	0.5	18.7	10.5	52	0.2	21.3	9.4	278	1.87	4.7	<0.5	4.4	19	0.2	0.4	0.8	42	0.33	0.054	16
K960175	Soil	0.4	14.7	7.3	43	0.1	16.9	7.5	278	1.43	3.6	<0.5	6.6	19	0.1	0.3	0.8	31	0.35	0.043	17
K960176	Soil	0.9	7.9	5.6	23	0.2	8.7	4.5	200	0.86	1.5	<0.5	5.6	11	<0.1	0.2	0.7	17	0.24	0.029	9
K960177	Soil	0.2	5.3	3.1	18	<0.1	4.6	2.6	203	0.57	0.8	<0.5	4.0	6	<0.1	0.1	0.3	11	0.10	0.019	6
K960178	Soil	0.3	18.0	8.9	51	0.2	22.6	10.3	347	1.90	4.7	0.9	8.0	26	0.1	0.4	1.5	39	0.42	0.054	22
K960179	Soil	0.1	6.6	4.7	34	0.1	8.0	4.5	210	0.97	2.0	0.8	4.8	8	<0.1	0.2	0.5	17	0.16	0.036	9
K960180	Soil	0.3	13.3	6.9	40	0.2	13.9	7.0	210	1.39	1.8	0.9	4.8	11	0.1	0.2	0.7	25	0.21	0.048	13
K960181	Soil	0.5	15.7	7.7	33	0.2	15.5	7.4	190	1.21	3.6	1.5	4.9	17	0.1	0.3	2.0	25	0.40	0.046	16
K960182	Soil	0.4	12.1	8.3	46	0.2	9.9	6.6	361	1.99	1.6	<0.5	19.5	35	<0.1	0.1	0.4	59	0.47	0.143	59
K960183	Soil	0.3	12.0	7.3	58	<0.1	11.6	6.0	373	2.57	0.9	<0.5	6.0	11	<0.1	<0.1	0.4	42	0.12	0.046	12
K960184	Soil	0.4	10.7	7.6	45	0.3	12.5	6.5	294	1.63	2.8	3.2	14.1	17	0.1	0.2	0.5	30	0.28	0.089	24
K960185	Soil	0.4	23.6	8.9	48	0.2	21.9	9.7	582	2.11	3.9	0.8	6.2	35	<0.1	0.3	0.8	51	0.40	0.073	18
K960186	Soil	0.8	34.7	7.4	70	<0.1	32.6	13.9	326	3.04	1.7	<0.5	7.1	30	<0.1	0.1	0.5	70	0.73	0.060	19
K960187	Soil	0.7	14.6	7.5	46	0.2	17.0	7.7	298	2.09	2.9	<0.5	6.9	17	<0.1	0.2	0.6	56	0.29	0.078	18
K960188	Soil	0.2	9.3	4.1	33	0.1	5.9	4.2	261	1.09	1.0	<0.5	7.7	9	<0.1	0.1	1.2	21	0.16	0.049	16
K960189	Soil	0.4	15.0	8.6	45	0.2	17.0	7.8	319	1.52	2.5	<0.5	5.4	17	0.1	0.2	1.6	32	0.36	0.054	15
K960190	Soil	0.8	15.4	8.6	42	0.5	15.5	8.3	309	1.69	3.6	0.6	10.8	14	<0.1	0.2	1.2	32	0.22	0.057	20
K960191	Soil	0.6	14.8	10.1	39	0.4	17.5	7.6	204	1.88	5.4	0.5	4.6	13	<0.1	0.4	1.0	45	0.18	0.045	14
K960192	Soil	1.3	13.6	6.0	38	0.2	14.3	6.6	221	1.80	2.4	1.5	5.0	20	0.1	0.2	0.6	42	0.43	0.060	13
K960193	Soil	0.6	17.7	7.5	31	0.4	15.9	7.2	242	1.71	3.9	0.9	5.4	16	0.1	0.3	2.0	38	0.29	0.044	12
K960194	Soil	0.4	20.5	9.5	52	0.2	22.7	10.1	359	2.13	5.9	0.6	6.8	16	0.1	0.5	1.6	46	0.32	0.055	19
K960195	Soil	0.3	12.8	7.7	42	0.2	15.7	8.1	290	1.68	2.9	<0.5	6.9	15	0.1	0.3	1.0	32	0.29	0.045	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960166	Soil	14	0.30	54	0.061	<1	0.83	0.013	0.14	6.0	<0.01	2.1	0.2	<0.05	4	<0.5	<0.2
K960167	Soil	12	0.31	57	0.059	<1	1.00	0.011	0.17	6.8	0.02	2.1	0.2	<0.05	5	<0.5	<0.2
K960168	Soil	13	0.25	87	0.037	<1	0.85	0.015	0.15	6.9	0.04	2.0	0.2	<0.05	4	<0.5	<0.2
K960169	Soil	22	0.43	115	0.040	<1	1.88	0.010	0.15	1.7	0.03	1.9	0.4	<0.05	7	<0.5	<0.2
K960170	Soil	4	0.23	50	0.056	<1	0.65	0.030	0.30	7.5	<0.01	1.6	0.3	<0.05	3	<0.5	<0.2
K960171	Soil	19	0.39	63	0.066	<1	1.17	0.023	0.17	6.1	0.01	2.2	0.2	<0.05	5	<0.5	<0.2
K960172	Soil	19	0.33	74	0.065	<1	0.89	0.014	0.16	7.0	<0.01	2.3	0.2	<0.05	4	<0.5	<0.2
K960173	Soil	20	0.35	76	0.054	<1	1.58	0.060	0.13	7.4	0.02	2.4	0.2	<0.05	5	<0.5	<0.2
K960174	Soil	36	0.75	76	0.091	<1	2.04	0.046	0.34	7.0	0.02	3.5	0.3	<0.05	7	<0.5	<0.2
K960175	Soil	27	0.63	72	0.086	<1	1.64	0.044	0.34	6.3	<0.01	2.7	0.4	<0.05	5	<0.5	<0.2
K960176	Soil	16	0.32	26	0.053	<1	0.92	0.043	0.20	6.8	<0.01	1.3	0.2	<0.05	4	<0.5	<0.2
K960177	Soil	9	0.19	25	0.034	<1	0.54	0.026	0.16	8.0	<0.01	1.1	0.1	<0.05	3	<0.5	<0.2
K960178	Soil	36	0.86	59	0.107	<1	1.87	0.040	0.39	4.8	<0.01	3.9	0.4	<0.05	7	<0.5	<0.2
K960179	Soil	12	0.30	38	0.048	<1	0.90	0.020	0.23	6.2	<0.01	1.7	0.3	<0.05	4	<0.5	<0.2
K960180	Soil	20	0.49	47	0.056	<1	1.34	0.022	0.21	7.2	0.01	2.0	0.2	<0.05	5	<0.5	<0.2
K960181	Soil	23	0.42	44	0.069	<1	1.07	0.024	0.12	7.2	0.01	1.8	0.1	<0.05	4	<0.5	<0.2
K960182	Soil	18	0.72	208	0.156	<1	1.28	0.033	0.57	4.5	0.02	4.0	0.3	0.06	6	<0.5	<0.2
K960183	Soil	41	0.88	190	0.194	<1	1.82	0.034	0.98	6.5	<0.01	5.2	0.5	<0.05	6	<0.5	<0.2
K960184	Soil	17	0.46	92	0.103	<1	1.15	0.014	0.39	4.6	<0.01	3.0	0.3	<0.05	5	<0.5	<0.2
K960185	Soil	33	0.72	136	0.096	<1	2.13	0.030	0.28	4.9	0.02	3.7	0.3	<0.05	7	<0.5	<0.2
K960186	Soil	55	1.35	149	0.228	<1	2.94	0.114	1.29	3.3	<0.01	6.1	0.9	0.08	11	<0.5	<0.2
K960187	Soil	31	0.85	173	0.143	<1	1.87	0.027	0.51	4.3	<0.01	5.1	0.4	<0.05	7	<0.5	<0.2
K960188	Soil	13	0.35	54	0.075	<1	0.88	0.037	0.33	6.4	<0.01	1.9	0.3	<0.05	4	<0.5	<0.2
K960189	Soil	26	0.60	64	0.078	<1	1.36	0.044	0.25	7.6	<0.01	2.5	0.3	<0.05	6	<0.5	<0.2
K960190	Soil	26	0.49	69	0.077	<1	1.44	0.021	0.22	8.9	0.01	2.9	0.3	<0.05	5	<0.5	<0.2
K960191	Soil	31	0.59	76	0.092	<1	1.54	0.017	0.17	6.9	0.03	2.7	0.2	<0.05	7	<0.5	<0.2
K960192	Soil	28	0.52	64	0.166	<1	1.57	0.047	0.49	4.8	0.01	4.0	0.4	<0.05	8	<0.5	<0.2
K960193	Soil	29	0.56	68	0.086	<1	1.52	0.035	0.24	5.8	0.02	2.7	0.2	<0.05	6	<0.5	<0.2
K960194	Soil	40	0.90	72	0.103	<1	2.55	0.030	0.34	5.0	0.01	4.1	0.4	<0.05	8	<0.5	<0.2
K960195	Soil	25	0.68	68	0.098	<1	1.76	0.047	0.31	8.4	<0.01	3.1	0.3	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960196	Soil	1.7	20.2	8.7	44	0.3	23.2	10.1	368	2.03	4.9	<0.5	7.1	28	0.1	0.2	1.1	39	0.56	0.055	16
K960197	Soil	0.6	21.1	10.5	57	0.1	24.1	11.4	487	2.25	5.5	<0.5	4.2	16	<0.1	0.2	0.7	40	0.27	0.057	20
K960198	Soil	0.8	15.6	7.1	32	0.3	19.1	8.2	217	1.41	2.8	<0.5	6.3	31	0.1	0.2	3.3	30	1.37	0.043	17
K960199	Soil	0.3	15.3	6.9	44	0.3	14.5	7.1	256	1.57	3.4	<0.5	5.3	12	0.1	0.2	1.2	37	0.25	0.043	14
K960200	Soil	0.5	16.5	8.1	44	0.2	20.7	8.2	270	1.92	2.4	0.6	6.2	19	0.1	0.1	1.0	37	0.35	0.054	16
K960201	Soil	0.5	19.2	49.1	43	0.4	21.0	9.9	300	2.16	1.4	4.0	8.9	12	0.1	0.2	0.9	36	0.30	0.096	20
K960202	Soil	0.4	18.4	12.5	45	0.2	25.5	10.7	300	2.39	1.9	<0.5	8.2	9	0.1	0.2	0.3	42	0.26	0.089	18
K960203	Soil	0.6	25.8	6.9	54	0.2	28.3	12.0	342	2.54	4.9	<0.5	6.0	10	0.1	0.8	0.2	54	0.24	0.063	14
K960204	Soil	0.4	24.0	3.6	43	<0.1	26.1	14.8	426	2.75	1.6	<0.5	6.4	7	<0.1	0.2	0.1	60	0.30	0.073	11
K960205	Soil	0.7	22.2	6.9	48	0.2	24.2	11.4	325	2.38	3.8	<0.5	6.8	9	0.2	0.3	0.3	49	0.22	0.060	14
K960206	Soil	0.4	27.1	1.5	65	0.1	32.0	23.8	696	4.56	0.8	<0.5	0.9	6	<0.1	0.1	<0.1	132	0.58	0.085	3
K960207	Soil	0.5	30.7	4.5	50	0.1	24.5	17.6	339	3.10	1.8	<0.5	3.5	9	0.1	0.2	0.1	69	0.31	0.059	8
K960208	Soil	0.3	38.2	4.4	54	0.1	32.4	18.4	469	3.50	1.6	<0.5	4.2	11	0.1	0.1	<0.1	82	0.36	0.060	9
K960209	Soil	0.5	20.5	5.1	53	0.1	29.4	12.7	383	2.69	2.0	<0.5	6.1	14	0.1	0.3	0.2	42	0.34	0.091	13
K960210	Soil	0.7	27.2	7.0	56	0.3	36.8	13.6	371	2.66	3.1	0.5	6.1	12	<0.1	0.4	0.2	58	0.29	0.076	14
K960211	Soil	0.5	33.0	3.4	42	0.1	45.9	15.0	342	2.32	0.9	<0.5	4.0	10	<0.1	0.2	<0.1	58	0.36	0.059	9
K960212	Soil	0.7	31.1	4.4	64	<0.1	58.7	20.3	510	3.90	1.9	<0.5	3.3	11	0.1	0.2	0.1	84	0.32	0.057	7
K960213	Soil	0.5	33.1	4.2	51	0.2	46.9	19.3	476	3.31	1.7	<0.5	3.0	9	<0.1	0.2	0.2	82	0.28	0.047	7
K960214	Soil	1.3	28.6	4.7	50	0.2	31.9	14.4	418	2.57	1.9	0.5	8.3	7	0.1	<0.1	<0.1	42	0.26	0.070	13
K960215	Soil	1.1	18.2	7.5	53	0.2	24.5	9.6	293	2.52	2.0	1.1	7.5	8	<0.1	0.1	0.1	36	0.21	0.065	17
K960216	Soil	5.7	16.0	4.4	50	0.2	42.8	11.1	283	2.16	1.5	0.8	6.6	8	0.2	<0.1	0.4	29	0.19	0.074	12
K960217	Soil	0.9	16.5	5.6	46	0.2	29.9	10.9	314	2.01	3.2	<0.5	4.5	12	0.2	0.4	0.2	40	0.30	0.077	12
K960218	Soil	1.7	49.3	3.8	74	0.1	70.3	19.9	600	3.64	2.3	2.8	3.2	13	0.2	0.2	0.1	93	0.32	0.068	10
K960219	Soil	1.4	39.3	5.2	76	0.3	59.1	19.3	426	2.96	2.9	1.6	3.5	10	0.3	0.3	0.1	60	0.37	0.076	10
K960220	Soil	1.3	28.8	5.1	58	0.1	76.1	16.2	374	2.47	2.6	<0.5	6.7	10	0.2	0.3	0.1	46	0.31	0.077	16
K960221	Soil	0.8	24.9	4.1	50	0.1	51.8	17.6	406	2.86	1.4	0.5	3.6	10	0.1	0.2	0.1	56	0.38	0.072	9
K960222	Soil	1.7	25.9	6.8	56	0.2	47.6	13.8	344	2.27	2.5	0.9	3.6	13	0.2	0.3	0.2	44	0.29	0.053	9
K960223	Soil	1.0	28.5	4.7	54	0.2	86.0	16.3	336	2.50	2.3	0.6	5.1	9	0.2	0.2	0.1	45	0.25	0.064	11
K960224	Soil	0.6	17.8	2.6	70	<0.1	53.5	22.4	589	3.69	1.5	<0.5	1.1	9	<0.1	<0.1	<0.1	82	0.40	0.060	2
K960225	Soil	0.9	17.8	2.4	59	<0.1	50.0	21.5	571	3.47	1.0	<0.5	0.7	8	<0.1	0.1	<0.1	73	0.41	0.064	2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960196	Soil	34	0.91	89	0.109	<1	2.46	0.084	0.37	4.9	0.02	3.8	0.3	<0.05	8	<0.5	<0.2
K960197	Soil	31	0.72	79	0.065	<1	1.68	0.017	0.19	4.0	0.01	2.8	0.2	<0.05	6	<0.5	<0.2
K960198	Soil	29	0.63	63	0.082	<1	1.66	0.096	0.32	6.1	0.02	2.0	0.3	0.06	5	<0.5	<0.2
K960199	Soil	25	0.60	63	0.098	<1	1.63	0.047	0.35	4.7	0.01	3.0	0.3	0.06	6	<0.5	<0.2
K960200	Soil	30	0.73	69	0.102	<1	1.89	0.053	0.38	6.7	0.02	3.4	0.3	<0.05	7	<0.5	<0.2
K960201	Soil	37	0.82	71	0.140	<1	1.56	0.017	0.50	4.5	<0.01	3.4	0.3	0.06	6	<0.5	<0.2
K960202	Soil	42	0.81	55	0.140	<1	1.53	0.013	0.44	5.0	<0.01	3.6	0.3	<0.05	6	<0.5	<0.2
K960203	Soil	42	0.92	60	0.142	<1	1.65	0.010	0.32	4.6	0.02	3.8	0.2	<0.05	6	<0.5	<0.2
K960204	Soil	59	1.30	35	0.154	<1	1.71	0.014	0.29	2.9	<0.01	3.1	0.2	<0.05	6	<0.5	<0.2
K960205	Soil	33	0.79	54	0.133	<1	1.59	0.012	0.22	4.9	0.01	3.1	0.2	<0.05	5	<0.5	<0.2
K960206	Soil	81	1.64	11	0.281	<1	2.06	0.030	0.05	0.6	<0.01	3.7	<0.1	<0.05	8	<0.5	<0.2
K960207	Soil	41	0.98	32	0.168	<1	1.53	0.015	0.12	3.1	<0.01	3.5	0.1	<0.05	5	<0.5	<0.2
K960208	Soil	55	1.33	47	0.190	<1	1.69	0.015	0.21	2.3	0.01	3.7	0.2	<0.05	6	<0.5	<0.2
K960209	Soil	40	0.98	90	0.127	<1	1.49	0.015	0.29	3.8	<0.01	3.6	0.2	<0.05	5	<0.5	<0.2
K960210	Soil	56	1.07	73	0.154	<1	1.76	0.013	0.35	3.7	0.01	3.8	0.3	<0.05	6	<0.5	<0.2
K960211	Soil	91	1.32	43	0.175	<1	1.52	0.019	0.20	2.4	<0.01	2.7	0.1	<0.05	5	<0.5	<0.2
K960212	Soil	109	2.02	42	0.197	<1	2.57	0.012	0.17	2.5	0.01	3.7	0.1	<0.05	7	<0.5	<0.2
K960213	Soil	104	1.71	46	0.177	<1	2.16	0.008	0.15	2.0	0.02	4.1	0.1	<0.05	6	<0.5	<0.2
K960214	Soil	77	1.15	52	0.126	<1	1.53	0.016	0.36	2.2	<0.01	3.1	0.3	<0.05	5	<0.5	<0.2
K960215	Soil	43	0.79	76	0.107	<1	1.41	0.013	0.36	4.2	<0.01	3.6	0.2	<0.05	5	<0.5	<0.2
K960216	Soil	33	0.66	59	0.094	<1	1.06	0.015	0.37	4.8	<0.01	2.8	0.2	<0.05	5	<0.5	<0.2
K960217	Soil	42	0.73	69	0.077	<1	1.21	0.011	0.18	5.6	0.02	2.9	0.2	<0.05	4	<0.5	<0.2
K960218	Soil	118	1.92	101	0.126	<1	2.09	0.010	0.37	1.8	<0.01	5.0	0.2	<0.05	7	<0.5	<0.2
K960219	Soil	85	1.36	65	0.106	<1	1.67	0.008	0.13	3.1	0.01	3.1	0.1	<0.05	5	0.5	<0.2
K960220	Soil	81	1.17	76	0.107	<1	1.49	0.014	0.30	3.2	<0.01	3.4	0.2	<0.05	5	0.5	<0.2
K960221	Soil	70	1.50	45	0.114	<1	1.80	0.022	0.19	3.6	0.01	3.4	0.1	<0.05	6	<0.5	<0.2
K960222	Soil	68	0.98	53	0.115	<1	1.57	0.013	0.19	3.7	0.02	2.8	0.2	<0.05	5	0.5	<0.2
K960223	Soil	101	1.38	57	0.115	<1	1.54	0.013	0.26	3.5	0.01	3.2	0.2	<0.05	5	<0.5	<0.2
K960224	Soil	122	1.69	30	0.205	<1	1.94	0.014	0.06	1.3	0.01	2.6	<0.1	<0.05	7	<0.5	<0.2
K960225	Soil	117	1.78	24	0.175	<1	1.96	0.015	0.02	1.1	<0.01	2.7	<0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960226	Soil	1.7	26.5	3.1	55	0.3	65.1	20.9	429	2.79	1.5	0.8	2.5	8	0.2	0.1	<0.1	57	0.28	0.054	6
K960227	Soil	7.3	26.5	7.3	79	0.2	66.3	14.4	306	2.44	3.9	<0.5	6.2	12	0.4	0.3	0.1	40	0.25	0.080	12
K960228	Soil	2.5	38.3	4.3	53	0.1	79.0	16.4	328	2.48	2.1	0.5	1.6	11	0.2	0.2	<0.1	46	0.25	0.042	5
K960229	Soil	1.9	37.5	4.7	55	0.1	85.7	19.7	348	2.62	2.4	<0.5	2.7	9	0.2	0.2	<0.1	49	0.26	0.050	7
K960230	Soil	0.7	36.4	3.3	43	0.2	69.4	19.0	349	2.32	1.4	<0.5	3.9	10	0.2	0.1	<0.1	41	0.34	0.053	7
K960231	Soil	3.1	30.8	5.4	62	0.3	122.8	19.1	387	2.55	3.2	<0.5	4.1	16	0.4	0.3	<0.1	41	0.31	0.082	11
K960232	Soil	2.1	25.7	5.2	57	0.2	126.6	16.4	310	2.21	2.5	<0.5	5.6	12	0.2	0.3	0.2	41	0.25	0.071	16
K960233	Soil	0.7	14.9	5.9	46	0.2	120.1	16.3	313	2.33	2.1	0.6	4.0	8	0.1	0.3	0.2	40	0.21	0.063	9
K960234	Soil	0.6	21.0	5.1	49	0.1	254.9	24.3	341	2.38	1.8	<0.5	3.8	7	0.2	0.2	0.1	44	0.22	0.046	9
K960235	Soil	0.6	73.7	3.0	52	0.2	222.5	26.6	406	2.83	1.4	<0.5	3.2	8	0.2	0.3	<0.1	54	0.33	0.070	9
K960236	Soil	0.8	25.9	3.7	48	0.1	414.5	38.2	426	2.92	2.0	<0.5	2.9	7	0.2	0.2	<0.1	57	0.25	0.050	6
K960237	Soil	1.2	20.2	5.4	54	0.2	161.6	19.2	347	2.21	2.7	1.2	4.6	9	0.2	0.3	0.1	46	0.27	0.070	13
K960238	Soil	1.5	33.0	3.0	46	0.2	94.5	18.8	337	2.22	1.5	<0.5	2.6	8	0.2	0.2	<0.1	45	0.43	0.070	6
K960239	Soil	2.1	35.2	5.0	59	0.2	192.0	26.2	529	2.93	2.7	<0.5	2.7	11	0.3	0.2	<0.1	61	0.39	0.077	8
K960240	Soil	0.4	11.7	6.3	43	<0.1	38.7	9.1	257	1.99	0.8	<0.5	10.3	14	<0.1	<0.1	0.3	25	0.25	0.080	20
K960241	Soil	1.0	26.1	5.4	56	0.1	191.7	25.1	519	3.05	2.2	<0.5	3.3	7	0.2	0.3	0.1	63	0.28	0.059	8
K960242	Soil	0.8	19.3	5.3	58	0.2	163.6	18.7	313	2.49	2.1	<0.5	3.7	7	0.2	0.3	0.1	48	0.25	0.068	9
K960243	Soil	0.9	19.4	5.7	63	0.1	173.9	19.9	322	2.43	2.3	<0.5	4.3	8	0.2	0.3	0.1	49	0.24	0.070	11
K960244	Soil	0.3	12.5	2.8	39	0.1	54.3	10.0	281	2.00	<0.5	<0.5	9.5	10	<0.1	<0.1	<0.1	26	0.32	0.069	20
K960245	Soil	0.5	12.3	6.2	41	0.1	400.6	30.4	338	2.84	2.1	<0.5	4.9	7	0.2	0.2	0.2	34	0.20	0.065	10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

CERTIFICATE OF ANALYSIS WHI12000008.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960226	Soil	115	1.41	49	0.130	<1	1.52	0.008	0.09	1.3	0.02	2.7	<0.1	<0.05	5	0.8	<0.2
K960227	Soil	68	1.06	2537	0.097	<1	1.51	0.011	0.23	3.3	0.02	2.7	0.2	<0.05	4	1.3	<0.2
K960228	Soil	126	1.71	44	0.098	<1	1.62	0.010	0.05	2.0	0.01	2.4	<0.1	<0.05	4	0.6	<0.2
K960229	Soil	134	1.59	50	0.111	<1	1.82	0.009	0.14	2.1	<0.01	2.9	0.1	<0.05	5	<0.5	<0.2
K960230	Soil	97	1.38	36	0.121	<1	1.61	0.012	0.16	1.5	<0.01	2.9	<0.1	<0.05	4	<0.5	<0.2
K960231	Soil	133	1.64	150	0.097	<1	1.44	0.013	0.13	2.5	<0.01	3.2	0.1	<0.05	4	0.6	<0.2
K960232	Soil	106	1.38	68	0.091	<1	1.40	0.012	0.22	2.9	<0.01	3.3	0.2	<0.05	4	0.6	<0.2
K960233	Soil	126	1.62	54	0.088	<1	1.27	0.014	0.24	5.1	0.02	3.0	0.2	<0.05	4	<0.5	<0.2
K960234	Soil	194	2.41	52	0.094	3	1.28	0.015	0.19	2.7	<0.01	3.8	0.2	<0.05	4	<0.5	<0.2
K960235	Soil	140	2.10	36	0.098	2	1.52	0.012	0.14	1.8	<0.01	3.6	<0.1	<0.05	4	<0.5	<0.2
K960236	Soil	320	4.56	43	0.081	2	1.26	0.016	0.15	1.7	<0.01	4.4	0.1	<0.05	4	<0.5	<0.2
K960237	Soil	98	1.39	64	0.087	<1	1.17	0.013	0.17	3.6	<0.01	3.3	0.2	<0.05	4	<0.5	<0.2
K960238	Soil	102	1.52	34	0.104	<1	1.31	0.018	0.10	2.1	<0.01	2.5	<0.1	<0.05	4	<0.5	<0.2
K960239	Soil	151	2.11	87	0.119	2	1.59	0.012	0.11	1.6	<0.01	3.8	0.1	<0.05	5	<0.5	<0.2
K960240	Soil	48	0.83	59	0.133	<1	1.22	0.025	0.56	4.0	<0.01	3.0	0.3	<0.05	5	<0.5	<0.2
K960241	Soil	216	2.56	54	0.097	2	1.57	0.014	0.16	3.0	<0.01	4.8	0.1	<0.05	5	<0.5	<0.2
K960242	Soil	155	1.85	58	0.096	2	1.43	0.012	0.21	3.4	<0.01	3.5	0.2	<0.05	5	<0.5	<0.2
K960243	Soil	159	1.97	74	0.094	1	1.56	0.013	0.21	3.5	<0.01	3.7	0.2	<0.05	5	<0.5	<0.2
K960244	Soil	63	0.96	57	0.142	<1	1.21	0.029	0.65	4.1	<0.01	3.8	0.3	<0.05	5	<0.5	<0.2
K960245	Soil	196	3.53	43	0.080	10	1.08	0.013	0.27	2.9	<0.01	3.3	0.2	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

QUALITY CONTROL REPORT WHI12000008.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
K954028	Soil	6.1	20.6	7.9	50	0.6	8.9	3.0	274	2.77	2.8	0.6	2.1	9	0.2	0.2	0.1	66	0.06	0.042	5
REP K954028	QC	5.7	20.7	7.4	50	0.6	9.0	3.0	273	2.75	3.0	<0.5	2.1	9	0.1	0.2	<0.1	66	0.06	0.044	5
K954031	Soil	8.5	46.0	4.9	92	0.8	11.6	4.3	337	3.79	<0.5	4.1	1.6	30	0.4	<0.1	0.1	114	0.22	0.065	4
REP K954031	QC	8.4	46.9	4.8	95	0.9	10.9	4.2	334	3.87	<0.5	4.3	1.7	31	0.5	0.1	0.1	117	0.22	0.066	4
K954034	Soil	10.3	29.4	20.5	137	0.4	34.2	8.2	214	1.76	1.8	4.9	1.6	30	0.9	0.3	0.7	77	0.21	0.036	6
REP K954034	QC	9.8	29.6	20.2	137	0.4	35.1	8.3	221	1.78	1.9	3.3	1.6	30	1.0	0.3	0.7	78	0.21	0.035	7
K954356	Soil	0.5	41.1	3.5	80	0.2	36.1	21.3	873	4.86	3.6	0.7	1.2	18	0.3	0.1	<0.1	146	1.28	0.062	6
REP K954356	QC	0.5	41.6	3.4	79	0.2	37.9	21.5	870	4.88	3.8	1.0	1.2	17	0.3	0.2	<0.1	146	1.29	0.062	6
K954669	Soil	0.9	32.0	4.5	87	0.5	28.9	16.7	666	3.52	13.1	<0.5	0.7	16	0.2	0.9	<0.1	87	0.59	0.053	5
REP K954669	QC	1.0	33.4	4.3	88	0.7	30.7	16.9	677	3.63	13.0	2.1	0.8	17	0.2	0.8	<0.1	88	0.61	0.056	5
K954675	Soil	0.6	35.0	3.5	51	0.4	29.5	21.5	385	3.76	8.8	1.6	2.3	19	0.2	0.4	<0.1	102	0.61	0.052	8
REP K954675	QC	0.7	35.3	3.7	51	0.5	30.0	21.4	397	3.92	8.8	1.8	2.3	19	0.1	0.4	<0.1	103	0.59	0.053	9
K954686	Soil	1.1	30.5	5.8	48	0.3	27.4	20.5	699	3.49	15.0	5.1	1.0	15	0.1	0.8	0.2	93	0.44	0.047	7
REP K954686	QC	0.9	31.6	5.7	50	0.4	27.8	20.2	695	3.50	15.8	2.9	1.0	15	0.2	0.8	0.2	96	0.45	0.046	7
K960064	Soil	1.1	25.0	9.5	44	0.8	20.3	9.1	457	2.33	40.1	2.8	3.8	8	0.1	4.6	0.3	37	0.11	0.039	14
REP K960064	QC	1.0	25.0	9.5	43	0.7	20.1	9.3	456	2.32	39.6	4.0	3.9	8	0.1	4.6	0.2	38	0.11	0.038	14
K960096	Soil	0.9	14.4	7.5	38	0.3	12.9	6.2	238	1.92	3.9	0.9	3.4	14	<0.1	0.4	0.1	35	0.31	0.051	9
REP K960096	QC	0.9	14.5	7.5	38	0.3	12.9	6.3	229	1.90	3.7	1.0	3.4	14	<0.1	0.5	0.1	33	0.31	0.051	9
K960097	Soil	1.5	17.7	8.9	47	0.2	21.9	8.5	921	2.01	4.0	1.1	2.5	15	0.2	0.5	0.1	34	0.30	0.086	10
REP K960097	QC	1.6	18.7	10.4	51	0.2	23.5	8.8	959	2.07	4.1	0.7	2.7	15	0.2	0.4	<0.1	35	0.32	0.092	11
K960109	Soil	0.3	15.8	8.9	72	1.9	14.0	8.5	357	1.95	4.1	18.2	5.6	20	0.4	0.2	0.7	27	0.31	0.068	13
REP K960109	QC	0.3	15.8	8.4	74	2.0	14.4	8.6	352	1.94	4.5	1.2	5.4	20	0.4	0.2	0.6	27	0.30	0.068	13
K960135	Soil	0.3	45.6	13.2	47	1.3	14.0	8.3	504	2.19	6.4	10.4	4.5	10	0.1	0.3	0.3	34	0.16	0.065	18
REP K960135	QC	0.3	44.5	12.8	46	1.3	14.5	8.6	493	2.19	6.4	11.9	4.5	10	<0.1	0.2	0.3	35	0.17	0.064	18
K960154	Soil	0.3	7.1	5.0	39	0.4	5.3	4.1	219	1.03	1.3	0.6	5.4	9	0.1	0.2	0.5	22	0.10	0.030	10
REP K960154	QC	0.3	6.8	5.3	37	0.3	5.1	4.4	212	1.05	1.2	<0.5	5.4	10	0.1	0.2	0.5	22	0.10	0.030	10
K960170	Soil	<0.1	8.4	7.1	36	0.1	2.4	3.3	192	0.87	0.5	<0.5	6.2	8	<0.1	<0.1	0.3	17	0.10	0.039	12
REP K960170	QC	<0.1	7.8	7.5	35	0.1	2.4	3.2	191	0.87	<0.5	<0.5	6.4	8	<0.1	<0.1	0.3	16	0.11	0.040	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

QUALITY CONTROL REPORT WHI12000008.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
K954028	Soil	18	0.46	152	0.049	<1	0.81	0.016	0.21	7.4	0.01	3.6	0.5	0.11	3	4.1	<0.2
REP K954028	QC	18	0.46	151	0.049	<1	0.84	0.019	0.21	7.4	0.03	3.4	0.5	0.10	3	3.5	<0.2
K954031	Soil	16	0.61	263	0.071	<1	1.33	0.041	0.47	9.7	0.01	4.8	1.1	0.55	4	6.7	<0.2
REP K954031	QC	17	0.63	262	0.070	<1	1.35	0.045	0.48	10.1	0.01	4.7	1.1	0.56	4	7.0	<0.2
K954034	Soil	29	0.47	160	0.057	1	1.16	0.015	0.11	8.7	0.03	2.5	0.2	0.06	4	2.6	<0.2
REP K954034	QC	30	0.47	162	0.059	<1	1.14	0.015	0.12	8.8	0.02	2.3	0.1	<0.05	3	2.8	<0.2
K954356	Soil	73	2.06	77	0.327	3	2.78	0.047	0.02	0.9	0.06	10.0	<0.1	<0.05	10	<0.5	<0.2
REP K954356	QC	73	2.05	77	0.340	4	2.83	0.043	0.02	0.9	0.04	9.8	<0.1	<0.05	10	<0.5	<0.2
K954669	Soil	53	1.10	49	0.109	3	1.80	0.047	0.08	3.1	0.04	7.9	<0.1	<0.05	7	<0.5	<0.2
REP K954669	QC	54	1.06	51	0.108	3	1.80	0.046	0.07	3.1	0.04	7.7	<0.1	<0.05	8	<0.5	<0.2
K954675	Soil	43	1.24	50	0.157	2	1.81	0.062	0.05	1.2	0.05	7.0	<0.1	<0.05	7	<0.5	<0.2
REP K954675	QC	43	1.21	52	0.155	2	1.85	0.064	0.04	1.1	0.04	7.1	<0.1	<0.05	7	<0.5	<0.2
K954686	Soil	49	0.92	78	0.062	<1	1.60	0.046	0.07	2.3	0.04	7.4	<0.1	<0.05	7	<0.5	<0.2
REP K954686	QC	50	0.90	78	0.070	1	1.66	0.049	0.06	2.3	0.03	7.8	<0.1	<0.05	6	<0.5	<0.2
K960064	Soil	23	0.44	66	0.031	<1	1.03	0.006	0.10	3.7	0.02	2.3	0.1	<0.05	4	<0.5	<0.2
REP K960064	QC	24	0.44	66	0.032	<1	1.02	0.006	0.10	3.5	0.03	2.2	<0.1	<0.05	4	<0.5	<0.2
K960096	Soil	20	0.46	151	0.016	1	0.90	0.005	0.07	4.5	<0.01	2.3	<0.1	<0.05	3	<0.5	<0.2
REP K960096	QC	20	0.45	150	0.015	2	0.87	0.006	0.07	4.4	0.02	2.3	<0.1	<0.05	3	<0.5	<0.2
K960097	Soil	25	0.52	202	0.032	1	0.99	0.006	0.10	2.4	0.02	2.6	<0.1	<0.05	3	<0.5	<0.2
REP K960097	QC	26	0.44	210	0.040	2	1.03	0.007	0.11	2.9	0.01	2.8	<0.1	<0.05	4	<0.5	<0.2
K960109	Soil	24	0.68	286	0.079	<1	1.16	0.020	0.23	7.7	<0.01	2.6	0.2	<0.05	4	<0.5	<0.2
REP K960109	QC	24	0.66	278	0.077	1	1.13	0.019	0.24	8.3	<0.01	2.5	0.2	<0.05	4	<0.5	<0.2
K960135	Soil	29	0.75	211	0.046	<1	1.22	0.008	0.12	4.9	0.02	3.3	0.2	<0.05	4	<0.5	<0.2
REP K960135	QC	30	0.74	209	0.046	<1	1.20	0.008	0.12	4.7	0.01	3.2	0.2	<0.05	4	<0.5	<0.2
K960154	Soil	11	0.27	65	0.075	<1	0.92	0.012	0.28	6.9	0.01	2.0	0.3	<0.05	4	<0.5	<0.2
REP K960154	QC	10	0.26	64	0.073	<1	0.92	0.011	0.26	7.1	0.01	2.0	0.3	<0.05	4	<0.5	<0.2
K960170	Soil	4	0.23	50	0.056	<1	0.65	0.030	0.30	7.5	<0.01	1.6	0.3	<0.05	3	<0.5	<0.2
REP K960170	QC	4	0.24	50	0.057	<1	0.68	0.029	0.28	7.8	<0.01	1.7	0.3	<0.05	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

QUALITY CONTROL REPORT WHI12000008.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
K960178	Soil	0.3	18.0	8.9	51	0.2	22.6	10.3	347	1.90	4.7	0.9	8.0	26	0.1	0.4	1.5	39	0.42	0.054	22
REP K960178	QC	0.3	17.6	8.6	51	0.2	22.2	9.4	344	1.84	4.5	<0.5	7.5	24	<0.1	0.4	1.4	39	0.38	0.052	22
K960188	Soil	0.2	9.3	4.1	33	0.1	5.9	4.2	261	1.09	1.0	<0.5	7.7	9	<0.1	0.1	1.2	21	0.16	0.049	16
REP K960188	QC	0.2	10.0	4.2	35	0.1	6.2	4.5	267	1.10	1.0	<0.5	7.7	9	<0.1	0.1	1.1	21	0.17	0.050	15
K960222	Soil	1.7	25.9	6.8	56	0.2	47.6	13.8	344	2.27	2.5	0.9	3.6	13	0.2	0.3	0.2	44	0.29	0.053	9
REP K960222	QC	1.7	25.4	6.7	55	0.2	45.5	13.8	333	2.27	2.6	<0.5	3.7	13	0.2	0.3	0.2	45	0.31	0.053	9
K960244	Soil	0.3	12.5	2.8	39	0.1	54.3	10.0	281	2.00	<0.5	<0.5	9.5	10	<0.1	<0.1	<0.1	26	0.32	0.069	20
REP K960244	QC	0.4	12.0	2.7	37	0.2	52.6	9.6	268	1.95	0.5	<0.5	9.1	10	<0.1	<0.1	<0.1	25	0.31	0.069	19
Reference Materials																					
STD DS8	Standard	13.8	117.6	121.8	317	1.9	38.7	7.8	572	2.28	26.3	118.7	7.1	66	2.6	6.2	6.3	43	0.64	0.082	15
STD DS8	Standard	14.4	112.9	128.0	314	1.8	39.2	7.9	645	2.53	27.2	164.1	7.4	68	2.7	6.2	6.7	44	0.71	0.083	16
STD DS8	Standard	12.3	114.3	107.5	289	1.6	37.0	7.0	532	2.22	21.6	95.7	6.3	64	1.9	5.6	6.5	40	0.63	0.080	14
STD DS8	Standard	13.0	105.8	119.4	311	1.7	36.7	7.2	583	2.36	23.6	123.5	6.3	62	2.1	5.2	6.0	42	0.67	0.075	15
STD DS8	Standard	13.2	108.2	122.6	312	1.7	37.9	7.4	594	2.38	23.8	111.2	6.4	64	2.3	5.3	6.2	42	0.67	0.075	15
STD DS8	Standard	13.2	101.3	120.7	297	1.8	36.2	7.0	597	2.37	22.8	113.2	6.6	60	2.1	5.4	6.2	41	0.68	0.072	15
STD DS8	Standard	13.6	107.6	124.1	308	1.8	39.8	7.3	598	2.41	23.9	117.6	6.3	66	2.1	5.2	6.1	43	0.67	0.074	16
STD DS8	Standard	13.1	112.7	122.9	311	1.7	38.8	7.5	602	2.39	23.8	107.8	6.5	63	2.1	5.2	5.9	45	0.69	0.073	15
STD DS8	Standard	13.5	110.7	119.6	317	1.7	38.7	7.7	606	2.46	24.2	129.2	6.4	63	2.2	4.9	6.5	42	0.68	0.078	14
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 21, 2012

QUALITY CONTROL REPORT WHI12000008.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
K960178	Soil	36	0.86	59	0.107	<1	1.87	0.040	0.39	4.8	<0.01	3.9	0.4	<0.05	7	<0.5	<0.2
REP K960178	QC	36	0.86	59	0.099	<1	1.73	0.036	0.36	4.7	<0.01	3.9	0.4	<0.05	7	<0.5	<0.2
K960188	Soil	13	0.35	54	0.075	<1	0.88	0.037	0.33	6.4	<0.01	1.9	0.3	<0.05	4	<0.5	<0.2
REP K960188	QC	12	0.36	53	0.075	<1	0.90	0.032	0.37	6.5	<0.01	1.9	0.3	<0.05	4	<0.5	<0.2
K960222	Soil	68	0.98	53	0.115	<1	1.57	0.013	0.19	3.7	0.02	2.8	0.2	<0.05	5	0.5	<0.2
REP K960222	QC	69	0.99	54	0.117	<1	1.61	0.014	0.19	3.6	0.02	2.6	0.2	<0.05	5	0.6	<0.2
K960244	Soil	63	0.96	57	0.142	<1	1.21	0.029	0.65	4.1	<0.01	3.8	0.3	<0.05	5	<0.5	<0.2
REP K960244	QC	61	0.92	57	0.135	<1	1.21	0.028	0.61	3.7	<0.01	3.5	0.3	<0.05	5	<0.5	<0.2
Reference Materials																	
STD DS8	Standard	118	0.62	283	0.107	3	0.89	0.087	0.39	3.0	0.22	2.2	5.5	0.10	5	4.7	5.4
STD DS8	Standard	122	0.62	296	0.128	2	0.95	0.093	0.44	3.1	0.21	3.0	5.6	0.20	5	5.7	4.9
STD DS8	Standard	115	0.54	243	0.123	2	0.81	0.072	0.35	2.5	0.17	2.4	4.7	0.12	4	4.4	4.9
STD DS8	Standard	118	0.59	261	0.110	2	0.88	0.083	0.39	3.1	0.21	2.3	5.4	0.09	5	5.3	4.8
STD DS8	Standard	119	0.61	268	0.110	2	0.91	0.095	0.38	3.0	0.21	2.6	5.6	0.08	5	5.5	5.3
STD DS8	Standard	115	0.60	267	0.107	2	0.87	0.084	0.38	2.9	0.20	2.5	5.3	0.09	4	5.3	4.7
STD DS8	Standard	118	0.61	263	0.111	2	0.94	0.095	0.40	3.0	0.19	2.8	5.6	0.08	5	5.1	5.0
STD DS8	Standard	120	0.60	258	0.117	<1	0.90	0.085	0.42	3.0	0.20	2.6	5.4	0.09	5	4.4	4.9
STD DS8	Standard	118	0.60	287	0.100	4	0.95	0.118	0.43	2.9	0.20	3.6	5.7	0.15	5	5.4	5.0
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	0.06	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Submitted By: Andrew Caldwell
Receiving Lab: Canada-Whitehorse
Received: March 08, 2012
Report Date: March 20, 2012
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI12000009.1

CLIENT JOB INFORMATION

Project: LIVINGSTONE
Shipment ID: SRV-2012-AC-2140
P.O. Number
Number of Samples: 320

SAMPLE DISPOSAL

RTRN-PLP Return
RTRN-RJT Return

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	320	Dry at 60C			WHI
SS80	320	Dry at 60C sieve 100g to -80 mesh			WHI
1DX2	318	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
RJSV	320	Saving all or part of Soil Reject			WHI

ADDITIONAL COMMENTS

Invoice To: Predator Mining Group
11th Floor- 888 Dunsmuir Street
Vancouver BC V6C 3K4
Canada

CC: Jack Cote
Linda Lewis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960246	Soil	0.5	14.8	15.8	42	0.1	152.8	16.7	291	2.01	2.1	<0.5	5.2	7	0.1	0.2	0.4	39	0.21	0.061	11
K960247	Soil	0.5	38.2	10.4	47	0.1	196.3	26.6	450	3.19	1.9	1.0	2.4	10	0.2	0.2	<0.1	76	0.42	0.071	5
K960248	Soil	0.6	23.1	10.5	48	0.2	321.5	26.8	354	2.67	4.5	0.6	5.2	9	0.3	0.7	0.2	55	0.27	0.053	13
K960249	Soil	0.4	16.1	13.6	36	<0.1	351.3	27.0	344	2.17	3.1	<0.5	4.8	5	0.1	0.1	0.1	49	0.27	0.055	6
K960250	Soil	0.6	24.6	5.4	35	<0.1	463.9	35.4	336	2.86	2.0	1.0	2.4	7	0.2	0.2	<0.1	70	0.24	0.040	7
K960251	Soil	1.1	14.9	17.7	30	0.2	11.1	5.9	281	1.44	1.4	4.0	6.1	30	0.1	<0.1	1.7	31	0.37	0.064	18
K960252	Soil	0.9	13.0	13.4	36	0.4	14.7	5.7	257	1.43	2.3	2.8	5.0	14	<0.1	0.2	1.0	34	0.19	0.047	16
K960253	Soil	0.7	16.2	27.3	37	0.1	16.2	6.0	294	1.31	5.2	0.6	6.3	16	0.1	0.3	0.7	33	0.28	0.039	14
K960254	Soil	0.9	12.2	11.1	39	0.3	12.8	7.0	414	1.51	2.4	<0.5	3.3	11	0.1	0.2	0.5	31	0.19	0.055	16
K960255	Soil	1.1	14.1	17.1	36	0.2	17.8	6.5	219	1.70	2.4	1.2	2.4	16	<0.1	0.2	0.6	40	0.28	0.050	15
K960256	Soil	0.3	6.8	8.6	29	0.2	20.0	7.1	299	1.18	<0.5	2.6	7.2	66	0.1	<0.1	3.8	29	1.62	0.052	20
K960257	Soil	2.1	43.6	17.9	46	15.6	17.2	23.1	245	1.42	4.6	2.8	6.1	11	0.3	0.4	1.2	32	0.18	0.045	13
K960258	Soil	0.5	27.6	16.4	46	5.1	18.1	11.7	425	1.56	4.4	9.1	6.8	61	0.3	0.2	1.9	26	1.31	0.056	19
K960259	Soil	1.0	18.2	9.9	24	2.9	11.5	9.4	268	0.96	1.4	0.6	3.0	12	0.1	0.2	1.5	17	0.13	0.044	14
K960260	Soil	1.7	29.0	12.8	48	2.9	21.0	10.7	368	2.22	4.4	2.0	4.8	13	0.1	0.3	2.1	30	0.13	0.054	16
K960261	Soil	1.7	22.3	8.7	44	2.7	17.9	8.9	405	1.43	3.9	0.6	5.4	141	0.2	0.3	1.7	26	0.37	0.049	14
K960262	Soil	1.5	10.0	7.1	12	2.9	4.1	2.3	55	0.46	1.4	3.0	0.8	2	<0.1	0.1	2.1	12	0.05	0.024	4
K960263	Soil	2.9	29.1	10.8	49	2.2	22.1	10.7	409	2.07	6.7	2.5	7.9	15	<0.1	0.4	4.6	40	0.21	0.043	20
K960264	Soil	2.7	27.8	13.4	55	1.6	24.6	12.4	476	2.57	6.8	<0.5	6.5	17	0.2	0.4	4.5	60	0.34	0.056	18
K960265	Soil	2.4	17.6	9.1	33	1.5	14.6	6.1	185	1.66	5.1	0.5	6.3	11	<0.1	0.4	4.4	40	0.16	0.042	18
K960266	Soil	2.6	33.0	9.7	39	1.8	18.0	8.1	266	1.80	6.8	1.0	4.1	11	<0.1	0.5	6.0	36	0.16	0.038	15
K960267	Soil	2.1	29.5	12.1	53	0.8	23.4	9.6	332	2.23	7.0	0.7	5.0	11	<0.1	0.4	5.3	34	0.16	0.047	19
K960268	Soil	2.4	26.6	10.1	42	1.2	20.0	8.2	284	1.94	7.1	0.8	4.2	15	<0.1	0.4	4.9	37	0.23	0.052	16
K960269	Soil	2.2	24.8	11.4	47	2.2	17.4	8.4	400	2.01	4.1	<0.5	2.1	12	<0.1	0.3	5.7	44	0.16	0.054	12
K960270	Soil	5.2	31.6	11.5	46	1.0	20.9	10.1	337	2.21	9.4	0.8	6.9	12	0.1	0.6	9.0	35	0.18	0.050	18
K960271	Soil	2.7	47.9	10.4	54	1.1	36.6	13.8	469	2.18	21.0	<0.5	6.0	29	0.2	1.2	2.5	54	0.57	0.055	15
K960272	Soil	2.4	25.2	11.3	45	1.0	22.4	10.9	417	2.02	3.4	1.0	9.2	8	<0.1	0.3	7.5	26	0.14	0.039	23
K960273	Soil	3.7	21.6	11.6	44	0.9	19.5	8.6	275	1.93	2.8	<0.5	6.1	11	<0.1	0.2	5.3	41	0.16	0.032	14
K960274	Soil	6.0	30.9	7.7	56	1.1	25.0	10.0	261	2.35	2.6	<0.5	5.5	17	<0.1	0.2	6.1	45	0.38	0.041	13
K960275	Soil	1.5	38.6	19.1	51	0.6	25.8	13.6	724	2.56	1.5	5.7	4.6	22	<0.1	0.1	0.3	20	0.08	0.060	20

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960246	Soil	97	1.23	48	0.100	3	1.00	0.015	0.30	3.7	<0.01	2.8	0.2	<0.05	4	<0.5	<0.2
K960247	Soil	134	1.71	34	0.148	3	1.54	0.022	0.11	1.5	<0.01	3.6	<0.1	<0.05	5	<0.5	<0.2
K960248	Soil	194	2.39	56	0.086	5	1.12	0.016	0.18	2.1	0.21	4.4	0.2	<0.05	4	<0.5	<0.2
K960249	Soil	267	2.94	33	0.084	3	1.19	0.014	0.21	1.5	<0.01	4.3	0.1	<0.05	4	<0.5	<0.2
K960250	Soil	468	3.98	26	0.099	9	1.35	0.010	0.09	0.8	<0.01	4.0	<0.1	<0.05	4	<0.5	<0.2
K960251	Soil	20	0.46	136	0.097	<1	1.17	0.036	0.36	10.6	<0.01	1.8	0.2	<0.05	4	<0.5	<0.2
K960252	Soil	27	0.45	74	0.084	<1	1.10	0.019	0.24	7.3	<0.01	2.3	0.2	<0.05	5	<0.5	<0.2
K960253	Soil	27	0.51	64	0.070	<1	1.39	0.042	0.22	6.9	<0.01	2.5	0.2	<0.05	5	<0.5	<0.2
K960254	Soil	24	0.45	71	0.056	<1	1.25	0.021	0.23	4.1	<0.01	2.0	0.3	<0.05	5	<0.5	<0.2
K960255	Soil	36	0.53	61	0.092	<1	1.48	0.034	0.27	5.0	0.01	2.4	0.3	<0.05	6	<0.5	<0.2
K960256	Soil	32	0.62	37	0.103	1	2.29	0.239	0.31	2.8	<0.01	2.2	0.2	<0.05	7	<0.5	<0.2
K960257	Soil	20	0.33	73	0.072	<1	1.12	0.012	0.16	8.0	<0.01	1.8	0.2	0.09	5	<0.5	<0.2
K960258	Soil	22	0.75	70	0.067	<1	1.27	0.012	0.28	8.5	<0.01	2.0	0.2	0.07	4	<0.5	<0.2
K960259	Soil	12	0.24	64	0.032	<1	0.60	0.011	0.14	11.0	<0.01	0.9	<0.1	<0.05	2	<0.5	<0.2
K960260	Soil	25	0.61	65	0.050	<1	1.53	0.008	0.15	6.8	0.01	2.1	0.2	<0.05	4	<0.5	<0.2
K960261	Soil	21	0.48	99	0.052	<1	1.21	0.014	0.16	8.1	<0.01	2.2	0.2	<0.05	4	<0.5	<0.2
K960262	Soil	9	0.08	15	0.015	<1	0.36	0.017	0.10	7.2	<0.01	0.5	<0.1	<0.05	2	<0.5	<0.2
K960263	Soil	33	0.62	85	0.089	<1	1.54	0.016	0.27	5.7	0.01	2.8	0.3	<0.05	5	<0.5	<0.2
K960264	Soil	32	0.68	120	0.093	<1	1.64	0.014	0.21	5.4	0.02	4.6	0.3	<0.05	5	<0.5	<0.2
K960265	Soil	27	0.50	58	0.096	<1	1.27	0.013	0.26	5.4	0.01	2.9	0.2	<0.05	5	<0.5	<0.2
K960266	Soil	29	0.49	60	0.072	<1	1.29	0.010	0.22	6.7	0.01	2.1	0.2	<0.05	5	<0.5	<0.2
K960267	Soil	33	0.80	66	0.065	<1	1.57	0.008	0.22	5.4	<0.01	2.2	0.3	<0.05	5	<0.5	<0.2
K960268	Soil	29	0.55	82	0.062	<1	1.38	0.015	0.16	6.6	<0.01	2.3	0.2	<0.05	5	<0.5	<0.2
K960269	Soil	29	0.55	92	0.068	<1	1.31	0.010	0.19	5.4	0.02	2.3	0.2	0.06	5	<0.5	<0.2
K960270	Soil	31	0.68	85	0.081	<1	1.59	0.011	0.26	7.0	0.01	2.9	0.4	0.06	5	<0.5	<0.2
K960271	Soil	43	0.59	61	0.092	<1	1.26	0.032	0.16	4.9	<0.01	4.3	0.2	<0.05	5	<0.5	<0.2
K960272	Soil	25	0.55	99	0.087	<1	1.40	0.007	0.41	4.8	<0.01	1.8	0.4	<0.05	4	<0.5	<0.2
K960273	Soil	30	0.70	86	0.094	<1	1.42	0.012	0.30	9.8	<0.01	2.3	0.3	<0.05	5	<0.5	<0.2
K960274	Soil	44	1.06	92	0.134	<1	1.79	0.040	0.66	5.1	0.03	2.3	0.6	0.09	6	<0.5	<0.2
K960275	Soil	17	0.60	64	0.022	<1	1.07	0.004	0.14	5.5	<0.01	1.4	0.1	0.07	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960276	Soil	1.0	44.5	13.6	51	0.4	28.8	13.7	657	2.56	1.8	2.7	7.1	24	0.1	0.1	0.2	19	0.13	0.071	26
K960277	Soil	1.1	38.1	13.8	53	0.4	28.7	14.2	621	2.66	2.1	3.5	3.6	16	<0.1	0.1	0.3	20	0.07	0.049	16
K960278	Soil	1.2	28.8	10.7	51	0.5	25.0	12.3	471	2.15	2.1	1.1	5.9	11	0.2	<0.1	0.1	13	0.08	0.049	16
K960279	Soil	1.0	44.7	14.6	62	0.5	30.0	13.3	455	3.04	1.8	8.3	6.4	14	<0.1	<0.1	0.2	19	0.07	0.067	24
K960280	Soil	1.7	38.2	17.4	49	0.4	25.5	12.5	373	2.37	1.6	1.5	5.4	11	<0.1	<0.1	0.3	15	0.07	0.051	15
K960281	Soil	<0.1	24.2	3.1	75	0.1	39.8	14.9	214	3.25	<0.5	1.3	17.9	8	<0.1	<0.1	<0.1	16	0.10	0.049	8
K960282	Soil	1.0	32.7	7.6	53	0.2	17.6	9.1	407	2.49	1.3	3.7	5.2	7	<0.1	<0.1	0.3	12	0.03	0.040	15
K960283	Soil	0.7	26.6	12.4	50	0.3	24.1	11.1	401	2.36	1.3	7.2	6.2	10	<0.1	<0.1	0.3	16	0.08	0.051	21
K960284	Soil	<0.1	5.0	1.5	22	0.3	8.9	5.0	273	1.05	<0.5	0.8	7.1	5	<0.1	<0.1	<0.1	5	0.05	0.019	15
K960285	Soil	0.2	2.9	18.8	17	0.2	11.3	5.3	1114	1.26	0.8	<0.5	6.8	14	<0.1	<0.1	<0.1	4	1.01	0.028	16
K960286	Soil	0.5	39.3	14.2	63	0.9	40.3	18.8	567	3.00	7.8	2.7	2.1	21	0.2	0.4	<0.1	80	0.56	0.075	8
K960287	Soil	0.8	30.2	10.1	50	0.6	41.4	14.3	529	2.45	5.2	2.4	2.8	19	0.1	0.4	0.1	57	0.31	0.067	10
K960288	Soil	0.6	45.7	14.1	55	2.7	38.7	15.4	497	2.53	4.6	2.4	1.9	19	0.2	0.4	0.2	64	0.66	0.050	7
K960289	Soil	1.6	45.9	6.3	50	0.7	48.9	19.9	531	2.90	9.5	1.5	1.2	20	0.1	0.6	<0.1	84	0.54	0.049	5
K960290	Soil	0.4	67.1	8.2	55	0.5	46.4	23.7	578	3.66	8.2	1.1	1.1	13	<0.1	0.5	<0.1	107	0.42	0.045	5
K960291	Soil	0.6	69.0	3.3	53	0.7	45.5	25.3	519	3.50	5.5	<0.5	1.0	14	0.1	0.3	<0.1	101	0.51	0.058	4
K960292	Soil	0.6	58.9	9.5	52	0.4	53.4	21.9	598	3.43	4.8	4.5	2.5	17	0.1	0.5	<0.1	97	0.51	0.077	7
K960293	Soil	1.3	54.5	7.5	57	0.8	39.8	15.5	464	2.85	8.1	1.6	2.5	18	0.3	0.6	<0.1	88	0.47	0.073	9
K960294	Soil	0.6	50.5	5.2	53	0.6	32.0	15.1	491	3.08	4.3	2.3	1.5	27	0.1	0.5	<0.1	124	0.51	0.077	6
K960295	Soil	0.4	73.8	9.1	47	1.5	32.2	17.7	559	2.95	5.9	0.8	1.9	24	0.1	1.1	<0.1	97	0.50	0.082	6
K960296	Soil	0.5	35.2	4.4	46	0.4	28.5	12.6	466	2.54	6.4	1.7	1.6	20	0.2	1.2	<0.1	76	0.39	0.090	8
K960297	Soil	0.8	54.9	8.2	62	0.5	61.3	19.4	1192	2.55	7.4	0.9	2.0	23	0.5	0.9	<0.1	66	1.00	0.048	10
K960298	Soil	1.0	33.2	3.1	41	0.3	23.0	11.1	542	2.24	17.4	<0.5	0.6	23	0.2	1.0	<0.1	47	4.33	0.038	8
K960299	Soil	0.8	57.8	6.9	47	0.3	52.5	19.4	484	2.68	6.4	2.1	1.5	15	0.2	0.8	<0.1	72	0.49	0.066	7
K960300	Soil	1.2	49.0	4.7	69	0.6	38.0	16.6	497	2.69	6.4	<0.5	2.1	16	0.5	0.6	0.1	80	0.44	0.065	5
K960301	Soil	0.1	33.8	2.9	45	13.6	501.1	70.7	757	3.90	1.1	<0.5	0.3	12	0.1	0.1	<0.1	76	0.47	0.064	2
K960302	Soil	0.4	41.4	4.6	52	1.4	259.8	34.8	718	3.85	1.4	1.6	0.4	18	0.2	0.2	<0.1	116	0.45	0.072	3
K960303	Soil	0.3	19.8	7.2	52	3.1	333.5	47.1	840	4.80	1.1	0.6	0.5	22	0.2	0.1	<0.1	122	0.72	0.089	2
K960304	Soil	0.2	29.4	4.3	45	4.9	370.5	36.7	840	3.53	0.8	7.6	0.8	35	0.4	0.1	<0.1	75	1.69	0.068	3
K960305	Soil	0.4	49.7	7.8	56	7.1	185.2	24.8	858	3.35	1.2	2.4	1.0	31	0.2	0.2	<0.1	79	0.65	0.117	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960276	Soil	17	0.62	77	0.030	<1	1.12	0.005	0.20	4.5	<0.01	1.9	0.1	0.08	3	<0.5	<0.2
K960277	Soil	19	0.59	58	0.021	<1	1.13	0.004	0.13	5.2	<0.01	1.4	0.1	<0.05	3	<0.5	<0.2
K960278	Soil	14	0.43	53	0.014	<1	0.89	0.004	0.11	6.2	<0.01	1.4	<0.1	<0.05	2	<0.5	<0.2
K960279	Soil	19	0.72	51	0.018	<1	1.28	0.003	0.14	4.3	<0.01	1.6	0.1	0.05	4	<0.5	<0.2
K960280	Soil	15	0.54	43	0.015	<1	1.01	0.003	0.11	6.1	0.01	1.2	<0.1	0.06	3	<0.5	<0.2
K960281	Soil	18	0.87	40	0.013	<1	1.44	0.005	0.10	1.4	<0.01	1.6	<0.1	<0.05	4	<0.5	<0.2
K960282	Soil	13	0.44	39	0.009	<1	0.90	0.002	0.10	5.1	<0.01	0.8	<0.1	<0.05	3	<0.5	<0.2
K960283	Soil	18	0.51	48	0.016	1	1.11	0.003	0.09	4.8	<0.01	1.1	<0.1	<0.05	3	<0.5	<0.2
K960284	Soil	9	0.22	25	0.015	2	0.40	0.008	0.10	5.2	<0.01	0.4	<0.1	<0.05	1	<0.5	<0.2
K960285	Soil	8	0.24	17	0.006	<1	0.44	0.006	0.06	4.0	<0.01	0.6	<0.1	<0.05	1	<0.5	<0.2
K960286	Soil	71	1.29	220	0.106	2	1.53	0.030	0.10	2.7	0.01	4.2	<0.1	<0.05	6	<0.5	<0.2
K960287	Soil	55	0.80	164	0.084	2	1.35	0.011	0.08	3.8	0.03	3.2	<0.1	<0.05	4	<0.5	<0.2
K960288	Soil	58	0.93	170	0.073	2	1.30	0.018	0.07	4.1	0.03	4.4	0.1	0.05	5	<0.5	<0.2
K960289	Soil	91	1.31	104	0.102	1	1.51	0.045	0.07	1.3	0.01	5.8	<0.1	<0.05	5	0.7	<0.2
K960290	Soil	96	1.70	92	0.089	2	2.07	0.034	0.07	0.7	0.01	8.3	<0.1	<0.05	7	<0.5	<0.2
K960291	Soil	91	1.69	109	0.116	1	1.85	0.040	0.09	0.7	0.02	7.0	<0.1	<0.05	7	<0.5	<0.2
K960292	Soil	88	1.73	215	0.128	<1	1.95	0.046	0.16	0.7	0.02	6.7	0.1	<0.05	6	<0.5	<0.2
K960293	Soil	60	1.06	150	0.097	1	1.35	0.027	0.09	2.5	0.02	5.2	<0.1	<0.05	5	<0.5	<0.2
K960294	Soil	39	0.82	115	0.082	<1	1.23	0.029	0.09	2.0	0.02	4.3	<0.1	<0.05	5	<0.5	<0.2
K960295	Soil	45	0.98	169	0.102	1	1.29	0.040	0.09	3.7	0.01	5.7	<0.1	<0.05	4	<0.5	<0.2
K960296	Soil	44	0.68	132	0.065	2	1.04	0.015	0.09	1.9	0.01	3.6	<0.1	<0.05	3	<0.5	<0.2
K960297	Soil	97	1.22	141	0.077	2	1.68	0.016	0.06	1.8	0.05	5.6	0.1	<0.05	4	<0.5	<0.2
K960298	Soil	30	0.47	58	0.018	1	0.59	0.004	0.05	2.1	0.02	6.5	<0.1	<0.05	2	<0.5	<0.2
K960299	Soil	114	1.43	127	0.090	1	1.78	0.016	0.07	0.9	0.02	5.6	<0.1	<0.05	5	<0.5	<0.2
K960300	Soil	77	1.18	128	0.111	<1	1.58	0.023	0.13	1.7	0.01	4.4	0.1	<0.05	5	0.6	<0.2
K960301	Soil	635	7.01	60	0.045	3	1.70	0.007	0.02	1.1	<0.01	9.2	<0.1	<0.05	5	<0.5	<0.2
K960302	Soil	395	4.04	204	0.101	1	2.21	0.017	0.12	1.0	0.02	9.2	0.3	0.08	8	<0.5	<0.2
K960303	Soil	336	6.59	40	0.084	2	2.80	0.004	0.03	1.0	0.01	18.2	<0.1	<0.05	6	<0.5	<0.2
K960304	Soil	536	4.43	169	0.021	<1	1.71	0.003	0.03	2.9	<0.01	8.6	<0.1	<0.05	5	<0.5	<0.2
K960305	Soil	301	2.60	203	0.030	1	1.69	0.012	0.09	1.4	0.02	7.8	<0.1	0.14	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960306	Soil	0.3	45.2	7.5	78	1.3	93.2	21.3	708	3.27	2.0	4.3	3.1	25	0.2	0.3	<0.1	48	0.84	0.172	14
K960307	Soil	0.8	21.3	9.9	87	2.9	98.6	19.2	818	4.78	1.1	<0.5	4.0	33	0.3	<0.1	<0.1	40	1.27	0.171	9
K960308	Soil	0.3	18.9	4.8	43	3.3	63.9	10.3	230	1.62	1.7	0.9	3.6	13	0.2	0.2	2.6	36	0.25	0.074	11
K960309	Soil	3.7	33.6	14.3	120	1.1	41.1	17.5	924	4.52	6.0	2.0	5.5	23	1.5	0.2	0.1	46	0.75	0.199	23
K960310	Soil	3.1	39.9	8.7	98	4.3	171.5	20.8	330	2.82	10.6	3.3	3.2	101	6.4	0.9	0.2	63	3.27	0.251	11
K960311	Soil	0.3	34.1	8.4	53	3.9	273.2	30.0	644	3.20	6.5	3.6	1.5	11	0.3	0.3	<0.1	73	0.41	0.081	5
K960312	Soil	1.8	39.2	10.7	41	3.7	86.8	10.5	412	1.37	8.9	2.7	2.2	6	0.2	0.5	0.4	24	0.17	0.068	10
K960313	Soil	0.4	50.4	10.7	48	2.3	70.1	12.4	617	2.11	4.7	7.6	2.3	6	0.3	0.4	<0.1	25	0.13	0.057	10
K960314	Soil	0.2	31.0	5.4	45	1.6	227.0	27.5	522	2.82	6.9	4.8	1.3	13	0.2	0.4	<0.1	55	0.30	0.046	4
K960315	Soil	0.2	7.8	2.7	37	0.6	28.3	4.6	164	0.67	1.2	1.2	2.6	2	<0.1	0.1	1.6	8	0.09	0.036	4
K960316	Soil	0.3	11.4	5.0	55	2.1	28.4	10.1	336	2.33	1.7	1.1	5.7	16	<0.1	0.1	0.7	39	0.22	0.058	13
K960317	Soil	0.2	24.6	5.7	49	2.4	108.7	17.1	463	1.95	2.9	1.6	2.5	9	<0.1	0.2	0.5	42	0.19	0.079	6
K960318	Soil	0.1	55.6	5.8	54	1.4	234.9	28.4	733	3.21	18.2	3.9	1.0	12	0.1	0.4	0.1	60	0.40	0.058	4
K960319	Soil	0.2	31.8	7.2	44	2.1	388.7	36.2	613	3.24	8.8	2.3	0.7	8	0.2	0.2	0.1	57	0.16	0.047	3
K960320	Soil	0.2	31.0	6.3	38	1.8	437.0	39.3	523	3.21	6.1	4.4	0.9	6	0.2	0.2	<0.1	52	0.12	0.034	3
K960321	Soil	0.3	30.7	10.0	58	1.3	231.9	25.0	662	3.02	10.9	1.7	2.3	9	0.2	0.3	0.4	46	0.18	0.058	8
K960322	Soil	0.2	29.1	6.8	45	0.8	204.7	26.1	533	2.86	17.2	2.4	1.1	8	0.3	0.2	0.3	52	0.26	0.049	4
K960323	Soil	0.3	27.3	13.8	43	1.6	272.1	28.5	603	2.95	10.7	2.9	1.1	10	0.2	0.3	0.2	50	0.19	0.050	5
K960324	Soil	0.3	41.3	6.3	68	1.3	237.6	28.7	840	3.88	4.1	3.1	2.4	11	0.2	0.3	<0.1	56	0.33	0.123	6
K960325	Soil	0.2	24.8	8.0	71	0.7	87.5	17.9	597	3.26	4.4	8.5	3.3	10	0.1	0.2	<0.1	36	0.23	0.086	7
K960326	Soil	0.2	84.9	10.7	52	0.9	60.1	21.3	613	4.28	9.1	3.9	4.2	23	<0.1	0.4	<0.1	52	0.61	0.132	12
K960327	Soil	0.5	20.3	8.4	39	1.4	191.8	24.4	537	2.82	6.0	2.5	0.9	9	0.1	0.3	0.2	57	0.28	0.056	5
K960328	Soil	0.1	18.4	14.0	52	0.8	65.8	9.2	362	1.98	4.5	1.5	6.9	6	0.1	0.3	0.2	19	0.11	0.042	22
K960329	Soil	0.9	31.2	11.5	74	1.5	54.1	14.0	747	3.43	63.1	129.8	6.9	21	0.2	0.9	0.1	24	0.43	0.083	22
K960330	Soil	0.5	42.1	10.6	63	0.9	71.4	24.5	1034	4.15	3.0	1.1	3.6	21	0.1	0.5	<0.1	56	0.51	0.087	9
K960331	Soil	0.4	10.9	6.2	33	1.4	47.0	8.1	229	1.79	6.5	3.6	6.1	9	<0.1	0.2	1.1	15	0.17	0.065	19
K960332	Soil	0.5	21.5	7.1	53	0.5	35.3	11.8	582	2.83	3.6	1.6	3.9	13	<0.1	0.3	0.2	41	0.23	0.083	9
K960333	Soil	0.2	27.9	8.2	47	1.2	25.1	8.4	657	1.81	2.3	1.5	7.3	5	<0.1	0.2	0.1	16	0.10	0.041	19
K960334	Soil	0.4	22.7	26.5	80	1.5	54.2	11.4	741	2.49	5.5	3.2	5.7	20	0.3	0.3	0.4	35	0.32	0.066	16
K960335	Soil	0.4	33.0	9.9	77	0.8	45.6	13.8	1068	3.23	4.1	4.5	4.6	21	0.3	0.3	0.1	36	0.31	0.058	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960306	Soil	76	1.80	127	0.033	<1	1.84	0.005	0.06	2.4	0.01	5.6	<0.1	<0.05	5	0.5	<0.2
K960307	Soil	62	2.34	112	0.067	<1	2.61	0.007	0.05	2.0	<0.01	4.3	<0.1	0.12	7	<0.5	<0.2
K960308	Soil	51	0.69	52	0.086	<1	1.24	0.017	0.27	11.2	<0.01	2.6	0.3	<0.05	5	<0.5	<0.2
K960309	Soil	33	1.56	109	0.008	<1	2.06	0.003	0.03	2.3	0.02	4.5	<0.1	<0.05	6	1.8	<0.2
K960310	Soil	139	2.45	88	0.048	2	1.48	0.009	0.04	3.8	0.05	5.6	<0.1	<0.05	4	2.1	<0.2
K960311	Soil	283	3.65	353	0.065	2	1.61	0.034	0.03	1.6	0.02	6.5	<0.1	<0.05	5	<0.5	<0.2
K960312	Soil	79	0.75	215	0.023	<1	0.58	0.006	0.06	6.6	0.16	2.4	0.2	<0.05	2	<0.5	<0.2
K960313	Soil	52	0.45	391	0.011	1	0.57	0.002	0.05	5.7	0.02	4.1	<0.1	<0.05	2	<0.5	<0.2
K960314	Soil	285	4.14	106	0.041	2	1.64	0.012	0.06	1.5	0.01	4.6	<0.1	<0.05	5	<0.5	<0.2
K960315	Soil	41	0.37	16	0.013	2	0.39	0.027	0.13	12.1	<0.01	0.8	0.2	<0.05	2	<0.5	<0.2
K960316	Soil	55	0.85	138	0.165	<1	1.64	0.046	0.75	4.2	<0.01	4.8	0.4	<0.05	6	<0.5	<0.2
K960317	Soil	166	1.65	65	0.059	<1	1.07	0.013	0.18	4.9	<0.01	3.4	0.3	<0.05	4	<0.5	<0.2
K960318	Soil	240	2.93	171	0.029	3	1.45	0.006	0.06	2.3	0.01	5.6	<0.1	<0.05	5	<0.5	<0.2
K960319	Soil	475	4.45	82	0.032	6	1.28	0.006	0.04	1.2	0.01	4.4	<0.1	<0.05	4	<0.5	<0.2
K960320	Soil	499	6.11	57	0.034	2	1.10	0.008	0.03	1.0	<0.01	4.5	<0.1	<0.05	4	<0.5	<0.2
K960321	Soil	257	2.73	213	0.037	2	1.34	0.010	0.11	1.7	0.02	4.3	0.2	<0.05	5	<0.5	<0.2
K960322	Soil	263	2.84	71	0.057	<1	1.44	0.010	0.04	1.9	<0.01	3.8	<0.1	<0.05	4	<0.5	<0.2
K960323	Soil	387	3.43	130	0.030	2	1.17	0.008	0.04	2.0	0.01	4.1	<0.1	<0.05	4	<0.5	<0.2
K960324	Soil	280	3.16	209	0.026	2	1.39	0.010	0.09	1.5	0.01	5.1	<0.1	<0.05	6	<0.5	<0.2
K960325	Soil	118	2.17	133	0.019	1	1.58	0.005	0.09	2.0	0.02	4.3	<0.1	<0.05	5	<0.5	<0.2
K960326	Soil	87	1.60	306	0.067	<1	1.24	0.018	0.17	1.2	0.01	4.6	<0.1	0.11	5	0.7	<0.2
K960327	Soil	256	2.53	98	0.040	1	1.25	0.013	0.05	1.4	0.03	3.8	<0.1	<0.05	4	<0.5	<0.2
K960328	Soil	72	1.33	112	0.027	<1	0.98	0.012	0.15	1.5	<0.01	2.9	<0.1	<0.05	4	<0.5	<0.2
K960329	Soil	53	0.75	527	0.008	1	0.86	0.004	0.12	1.9	0.03	4.8	<0.1	<0.05	3	<0.5	<0.2
K960330	Soil	83	1.91	216	0.016	<1	1.73	0.006	0.11	1.1	<0.01	8.4	<0.1	<0.05	4	<0.5	<0.2
K960331	Soil	54	0.68	132	0.019	<1	0.74	0.010	0.10	3.6	<0.01	2.1	<0.1	<0.05	3	<0.5	0.4
K960332	Soil	50	1.17	315	0.082	<1	1.35	0.012	0.31	2.9	0.01	4.6	0.1	<0.05	7	<0.5	<0.2
K960333	Soil	31	0.38	178	0.010	<1	0.61	0.006	0.08	3.4	<0.01	2.2	<0.1	<0.05	2	<0.5	<0.2
K960334	Soil	71	0.92	273	0.029	<1	1.13	0.008	0.08	2.4	0.03	4.3	<0.1	<0.05	4	<0.5	<0.2
K960335	Soil	50	0.94	421	0.012	1	1.09	0.016	0.08	2.3	<0.01	7.6	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960336	Soil	0.3	44.8	135.7	158	1.7	27.8	15.2	765	3.43	13.4	68.3	3.1	10	0.6	0.7	0.2	19	0.18	0.055	11
K960337	Soil	0.3	32.6	9.8	62	0.8	43.3	15.1	673	2.72	5.3	5.7	2.6	8	0.2	0.3	0.1	43	0.16	0.057	8
K960338	Soil	0.3	29.5	16.2	54	0.9	34.2	9.8	541	2.14	4.6	2.4	3.3	8	0.2	0.2	0.2	33	0.21	0.047	10
K960339	Soil	0.8	13.9	6.8	23	1.3	10.4	3.7	180	1.00	1.1	<0.5	1.0	63	0.2	0.1	0.8	14	0.33	0.085	12
K960340	Soil	0.7	13.6	8.4	48	1.1	14.6	7.8	487	1.93	4.0	0.8	3.3	11	<0.1	0.3	0.7	28	0.15	0.054	13
K960341	Soil	0.4	9.4	7.1	39	0.8	11.8	6.5	287	1.67	2.9	1.3	4.4	7	0.1	0.1	0.5	25	0.17	0.064	14
K960342	Soil	0.5	26.6	15.1	73	0.9	22.0	11.2	685	2.86	7.5	3.0	2.8	11	0.2	0.3	0.4	44	0.16	0.072	12
K960343	Soil	0.2	34.1	11.0	56	1.1	37.9	12.4	691	2.33	9.9	3.4	3.6	13	0.2	0.4	0.2	35	0.23	0.069	12
K960344	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
K960345	Soil	0.3	39.7	14.2	71	1.2	33.2	11.8	518	2.82	15.1	8.5	3.3	15	0.1	0.3	0.2	55	0.22	0.065	12
K960346	Soil	0.3	31.6	13.5	67	0.6	28.4	12.4	531	2.75	18.2	5.5	3.1	16	0.1	0.5	0.1	50	0.22	0.070	9
K960347	Soil	0.3	14.9	7.1	45	0.8	32.7	10.2	394	2.00	12.6	2.1	4.8	26	0.1	0.2	0.5	39	0.32	0.068	18
K960348	Soil	0.5	55.0	15.8	64	0.5	47.1	16.7	636	2.78	19.5	5.3	4.5	23	0.2	0.4	0.1	46	0.48	0.108	12
K960349	Soil	0.2	29.1	12.0	56	0.5	30.7	12.1	626	2.40	16.3	4.0	4.2	15	0.2	0.5	0.1	43	0.21	0.079	11
K960350	Soil	0.3	40.5	9.7	39	1.2	87.7	15.8	510	2.58	11.3	0.6	4.3	23	0.2	0.4	0.6	44	0.36	0.087	8
K960351	Soil	2.2	26.9	21.1	61	0.7	34.4	13.8	536	2.83	44.7	9.8	9.8	36	0.1	0.6	0.2	40	0.35	0.112	25
K960352	Soil	0.4	21.7	15.4	56	0.8	25.1	11.7	445	2.54	23.9	2.2	2.6	25	0.2	0.5	0.2	36	0.35	0.110	12
K960353	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
K960354	Soil	0.4	34.6	17.6	55	0.7	34.2	15.5	481	2.82	40.0	11.5	8.6	31	0.2	0.7	0.2	40	0.37	0.091	19
K960355	Soil	0.7	26.8	12.4	47	1.0	40.3	17.1	540	3.07	33.0	14.7	4.6	38	0.3	0.6	0.2	46	0.57	0.112	13
K960356	Soil	0.5	26.6	12.3	57	0.7	20.3	12.0	458	2.28	28.6	4.5	6.0	48	0.2	1.3	0.1	25	0.41	0.086	12
K960357	Soil	0.4	22.5	13.6	67	0.7	22.0	12.6	653	2.20	15.6	4.5	8.7	29	0.3	0.6	<0.1	21	0.70	0.061	18
K960358	Soil	1.1	42.1	19.9	69	0.9	43.8	15.9	698	3.40	116.0	34.2	7.6	40	0.7	2.0	0.2	27	0.63	0.105	32
K960359	Soil	0.5	23.3	7.1	53	0.5	21.7	10.2	607	1.80	36.4	5.6	4.4	22	0.4	0.7	<0.1	23	0.27	0.054	10
K960360	Soil	0.9	35.7	16.7	70	0.5	24.9	12.6	606	2.96	241.0	50.5	4.1	28	0.3	1.6	<0.1	30	0.29	0.101	17
K960361	Soil	0.8	37.0	32.6	91	0.8	32.2	15.7	733	3.29	429.5	49.6	3.5	14	0.4	3.8	<0.1	41	0.13	0.056	12
K960362	Soil	0.9	25.7	8.2	54	0.5	24.3	15.8	724	3.25	27.1	3.4	3.6	22	0.1	1.5	0.2	42	0.32	0.092	16
K960363	Soil	0.3	9.1	8.1	31	0.5	10.6	5.9	283	1.41	8.1	2.1	6.4	6	<0.1	0.8	0.4	16	0.21	0.095	18
K960364	Soil	2.2	20.5	5.5	19	0.4	9.8	4.1	108	1.61	40.2	1.4	1.8	5	<0.1	2.9	<0.1	28	0.04	0.053	7
K960365	Soil	6.3	105.0	28.1	219	1.5	86.7	17.3	247	3.95	233.0	132.8	3.8	17	0.8	7.2	0.2	52	0.16	0.150	18

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960336	Soil	28	0.44	381	0.007	<1	0.85	0.004	0.12	2.3	0.06	5.8	<0.1	<0.05	2	<0.5	<0.2
K960337	Soil	56	1.20	134	0.022	<1	1.21	0.006	0.09	2.6	0.01	4.8	<0.1	<0.05	4	<0.5	<0.2
K960338	Soil	42	0.95	87	0.031	<1	1.13	0.012	0.13	3.4	0.01	3.6	<0.1	<0.05	4	<0.5	<0.2
K960339	Soil	17	0.15	62	0.012	<1	1.26	0.059	0.12	6.7	0.03	0.8	0.2	0.05	5	<0.5	<0.2
K960340	Soil	22	0.58	102	0.035	<1	1.09	0.010	0.10	5.1	0.01	2.6	0.1	<0.05	4	<0.5	<0.2
K960341	Soil	21	0.44	57	0.086	<1	1.10	0.013	0.37	7.6	<0.01	2.7	0.3	<0.05	5	<0.5	<0.2
K960342	Soil	31	0.97	120	0.045	<1	1.37	0.009	0.13	4.2	<0.01	3.6	0.1	<0.05	5	<0.5	<0.2
K960343	Soil	43	0.92	187	0.029	<1	1.12	0.007	0.12	5.2	0.01	3.5	0.1	<0.05	4	<0.5	<0.2
K960344	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
K960345	Soil	42	1.25	197	0.071	<1	1.60	0.006	0.28	3.5	0.01	4.1	0.1	<0.05	5	<0.5	<0.2
K960346	Soil	41	1.11	126	0.047	<1	1.39	0.006	0.11	3.3	<0.01	4.0	0.1	<0.05	5	<0.5	<0.2
K960347	Soil	65	0.82	167	0.093	<1	1.40	0.022	0.22	4.3	<0.01	3.3	0.2	<0.05	6	<0.5	<0.2
K960348	Soil	36	0.81	133	0.039	<1	1.13	0.009	0.15	4.0	<0.01	4.1	0.1	<0.05	4	<0.5	<0.2
K960349	Soil	42	1.01	125	0.041	<1	1.15	0.009	0.14	4.8	<0.01	3.7	<0.1	<0.05	4	<0.5	<0.2
K960350	Soil	84	1.37	153	0.064	2	1.07	0.014	0.19	2.5	<0.01	3.0	0.1	<0.05	4	<0.5	<0.2
K960351	Soil	43	0.92	164	0.064	<1	1.24	0.015	0.21	3.6	<0.01	4.0	0.2	<0.05	5	<0.5	<0.2
K960352	Soil	25	0.69	148	0.029	<1	1.12	0.008	0.13	3.7	0.01	2.9	0.1	<0.05	4	<0.5	<0.2
K960353	Soil	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.	I.S.
K960354	Soil	42	0.95	152	0.054	<1	1.18	0.009	0.17	3.2	<0.01	4.1	0.2	<0.05	4	<0.5	<0.2
K960355	Soil	57	0.93	147	0.028	1	1.29	0.007	0.11	2.2	0.02	4.9	0.1	<0.05	4	<0.5	<0.2
K960356	Soil	20	0.72	74	0.023	<1	0.95	0.008	0.08	3.2	<0.01	2.9	<0.1	0.13	3	<0.5	<0.2
K960357	Soil	19	0.61	69	0.021	<1	0.92	0.008	0.11	3.7	<0.01	2.9	<0.1	0.19	3	<0.5	<0.2
K960358	Soil	36	0.45	199	0.007	1	0.96	0.003	0.10	3.2	0.06	4.6	0.1	0.15	3	0.6	<0.2
K960359	Soil	20	0.52	92	0.026	<1	0.78	0.020	0.08	6.1	<0.01	2.2	<0.1	0.06	3	<0.5	<0.2
K960360	Soil	25	0.67	144	0.015	<1	1.06	0.007	0.10	3.3	0.01	3.6	<0.1	<0.05	4	<0.5	<0.2
K960361	Soil	30	0.58	74	0.015	1	1.01	0.007	0.08	4.5	0.02	4.7	<0.1	<0.05	3	<0.5	<0.2
K960362	Soil	24	0.61	143	0.028	1	1.09	0.008	0.13	3.2	0.02	4.2	0.2	<0.05	4	<0.5	<0.2
K960363	Soil	13	0.28	28	0.049	1	0.79	0.007	0.21	5.9	<0.01	1.5	0.2	<0.05	3	<0.5	<0.2
K960364	Soil	17	0.11	143	0.011	<1	0.29	0.002	0.03	12.6	0.04	2.1	<0.1	<0.05	2	<0.5	<0.2
K960365	Soil	32	0.02	125	0.001	1	0.21	0.001	0.04	7.6	0.04	5.4	<0.1	<0.05	<1	2.4	0.8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960366	Soil	0.4	44.1	3.1	69	0.2	21.2	29.6	527	5.04	16.2	1.5	1.4	14	<0.1	1.5	<0.1	208	0.42	0.064	5
K960367	Soil	0.5	42.4	5.2	61	0.4	23.3	17.3	392	4.13	19.7	13.3	3.5	16	0.1	1.9	0.1	68	0.43	0.118	10
K960368	Soil	0.8	15.4	7.5	32	1.0	14.4	6.2	209	1.88	10.0	0.8	2.3	11	<0.1	0.7	0.1	40	0.14	0.041	10
K960369	Soil	1.7	17.4	6.7	58	0.7	14.8	7.7	5459	1.39	23.9	2.3	0.3	25	0.6	1.1	<0.1	31	1.29	0.073	6
K960370	Soil	0.9	31.9	7.1	36	1.1	18.9	10.1	488	1.91	20.0	3.8	5.0	11	0.2	2.9	<0.1	28	0.20	0.066	13
K960371	Soil	0.3	11.3	6.2	36	1.1	16.6	6.7	283	1.44	6.3	0.6	6.1	7	<0.1	1.2	0.3	22	0.17	0.061	13
K960372	Soil	1.1	38.1	18.3	170	0.4	26.4	15.3	627	2.28	11.5	5.5	4.7	8	0.5	1.1	0.6	30	0.21	0.099	7
K960373	Soil	0.8	38.8	1.1	66	<0.1	7.6	14.5	450	2.90	0.8	1.9	0.3	44	<0.1	0.2	<0.1	64	0.62	0.097	1
K960374	Soil	1.7	36.1	1.9	39	0.3	8.6	11.4	416	1.86	2.0	<0.5	0.3	36	<0.1	0.2	<0.1	31	0.44	0.060	4
K960375	Soil	0.5	10.7	7.5	33	1.3	10.6	4.8	224	1.54	4.5	0.6	2.5	7	0.1	0.3	0.5	36	0.12	0.058	10
K960376	Soil	0.5	6.9	4.6	31	0.7	6.5	3.5	168	1.22	3.0	<0.5	3.7	7	<0.1	0.2	0.2	23	0.13	0.051	9
K960377	Soil	0.4	47.3	12.1	43	0.3	25.2	14.6	732	2.60	9.4	2.8	5.9	10	<0.1	1.5	0.4	29	0.24	0.099	19
K960378	Soil	0.9	27.0	13.3	48	1.3	36.9	14.0	721	2.74	22.2	4.9	9.9	14	0.1	3.4	0.2	29	0.21	0.079	20
K960379	Soil	0.6	53.7	8.4	70	0.5	131.0	26.2	678	4.42	2.3	2.6	3.3	19	<0.1	0.8	<0.1	90	0.27	0.087	19
K960380	Soil	0.4	11.4	7.0	32	0.5	16.2	6.6	247	1.40	8.4	0.9	6.0	9	<0.1	0.9	0.5	21	0.18	0.055	14
K960381	Soil	0.9	30.2	8.3	54	0.4	81.5	19.5	543	3.10	17.8	7.5	7.5	20	<0.1	2.0	0.1	50	0.31	0.085	24
K960382	Soil	1.3	15.6	10.2	59	0.6	17.5	7.3	592	2.01	15.5	1.5	3.6	21	0.2	0.7	0.6	22	0.55	0.104	16
K960383	Soil	0.2	2.7	9.7	39	0.1	11.2	6.4	336	1.51	4.1	<0.5	15.6	6	<0.1	<0.1	<0.1	6	0.05	0.026	30
K960384	Soil	0.3	17.5	29.1	37	<0.1	31.6	23.2	2559	1.91	26.6	1.8	8.6	27	0.2	0.9	0.2	7	4.31	0.051	20
K960385	Soil	0.5	15.6	9.4	44	0.5	20.9	10.1	406	2.25	8.3	3.2	7.6	10	<0.1	0.6	0.2	21	0.13	0.050	20
K960386	Soil	0.6	11.6	9.5	35	0.7	15.0	7.7	453	1.76	7.4	0.6	6.1	8	0.2	0.3	0.4	27	0.14	0.050	15
K960387	Soil	1.1	19.2	8.3	42	0.6	21.4	11.0	280	2.23	7.1	4.9	6.2	15	<0.1	0.4	0.2	38	0.22	0.051	18
K960388	Soil	0.4	11.5	7.2	39	0.3	14.9	7.4	332	1.67	6.9	<0.5	7.3	7	<0.1	0.4	0.2	28	0.16	0.062	16
K960389	Soil	0.4	17.0	8.8	56	0.4	28.9	18.2	1219	2.45	6.4	6.3	11.4	14	0.1	0.4	<0.1	19	0.12	0.058	32
K960390	Soil	0.6	25.9	13.4	55	0.3	40.9	12.4	531	2.69	3.7	5.5	2.2	59	0.2	0.3	1.2	57	0.58	0.065	15
K960391	Soil	0.9	24.5	7.0	51	0.5	25.7	10.9	340	2.39	2.8	<0.5	6.2	11	<0.1	0.6	0.3	50	0.22	0.081	16
K960392	Soil	0.5	55.3	5.0	38	0.3	21.7	9.2	284	2.22	1.6	0.8	9.3	13	0.1	0.2	0.3	37	0.27	0.085	17
K960393	Soil	0.5	33.6	7.1	47	0.2	27.0	12.6	372	2.62	2.0	0.8	7.8	11	<0.1	0.2	0.2	61	0.33	0.103	14
K960394	Soil	0.4	32.7	5.2	45	<0.1	32.7	14.2	400	2.77	1.5	<0.5	5.1	10	0.1	0.1	0.2	71	0.29	0.072	11
K960395	Soil	0.3	23.1	3.2	37	<0.1	24.2	14.3	410	2.60	1.5	<0.5	3.7	7	<0.1	<0.1	0.1	67	0.34	0.061	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960366	Soil	13	1.25	86	0.056	<1	2.25	0.021	0.06	1.5	0.01	9.8	<0.1	<0.05	8	<0.5	<0.2
K960367	Soil	19	0.67	149	0.043	<1	1.33	0.017	0.06	2.2	0.01	5.7	<0.1	<0.05	5	<0.5	<0.2
K960368	Soil	24	0.35	76	0.048	<1	1.10	0.006	0.06	2.6	0.02	2.1	<0.1	<0.05	4	<0.5	<0.2
K960369	Soil	19	0.19	950	0.023	2	0.67	0.004	0.05	1.5	0.11	1.1	<0.1	0.19	3	<0.5	<0.2
K960370	Soil	20	0.44	64	0.027	<1	1.03	0.009	0.08	5.2	0.02	2.9	<0.1	<0.05	3	<0.5	<0.2
K960371	Soil	22	0.40	49	0.064	<1	0.95	0.014	0.23	5.2	0.02	2.1	0.3	<0.05	4	<0.5	<0.2
K960372	Soil	26	0.70	67	0.017	<1	1.15	0.004	0.07	5.7	0.02	2.8	<0.1	<0.05	3	0.5	<0.2
K960373	Soil	10	1.12	67	0.096	<1	1.57	0.027	0.15	1.1	<0.01	3.1	<0.1	<0.05	4	<0.5	<0.2
K960374	Soil	12	0.92	132	0.032	<1	1.14	0.014	0.02	3.2	0.02	2.0	<0.1	0.09	3	<0.5	<0.2
K960375	Soil	20	0.28	41	0.064	<1	1.08	0.011	0.13	3.0	0.02	1.6	0.2	0.05	5	<0.5	<0.2
K960376	Soil	14	0.24	26	0.050	<1	0.64	0.016	0.15	3.6	<0.01	1.4	0.2	<0.05	3	<0.5	<0.2
K960377	Soil	24	0.52	72	0.011	<1	1.15	0.005	0.06	3.4	<0.01	4.6	<0.1	<0.05	3	<0.5	<0.2
K960378	Soil	34	0.47	93	0.030	<1	1.29	0.006	0.12	6.2	0.03	3.4	0.1	<0.05	3	<0.5	<0.2
K960379	Soil	268	1.31	95	0.035	<1	1.60	0.005	0.07	0.5	<0.01	4.3	<0.1	<0.05	7	<0.5	<0.2
K960380	Soil	24	0.34	41	0.048	<1	0.83	0.016	0.15	5.8	<0.01	1.6	0.2	<0.05	4	<0.5	<0.2
K960381	Soil	107	0.89	107	0.059	<1	1.27	0.006	0.13	2.9	0.01	4.3	0.1	<0.05	5	<0.5	<0.2
K960382	Soil	24	0.35	49	0.012	2	0.95	0.010	0.07	9.9	0.06	1.7	<0.1	0.17	3	<0.5	<0.2
K960383	Soil	7	0.19	31	0.003	<1	0.49	0.005	0.07	4.9	<0.01	0.7	<0.1	<0.05	1	<0.5	<0.2
K960384	Soil	7	0.13	134	0.004	<1	0.49	0.004	0.05	3.1	0.03	2.6	<0.1	<0.05	<1	<0.5	<0.2
K960385	Soil	20	0.39	55	0.027	<1	1.18	0.006	0.09	5.6	0.02	1.9	<0.1	<0.05	3	<0.5	<0.2
K960386	Soil	21	0.37	45	0.050	<1	0.97	0.010	0.11	5.8	0.02	2.0	0.1	<0.05	4	<0.5	<0.2
K960387	Soil	23	0.47	58	0.041	<1	1.09	0.008	0.08	4.3	0.02	2.1	<0.1	<0.05	4	<0.5	<0.2
K960388	Soil	21	0.45	59	0.065	<1	1.16	0.010	0.21	5.0	0.02	2.1	0.3	<0.05	4	<0.5	<0.2
K960389	Soil	21	0.43	39	0.031	<1	0.82	0.004	0.07	3.3	0.07	1.4	<0.1	<0.05	2	<0.5	<0.2
K960390	Soil	64	0.77	245	0.017	2	1.25	0.013	0.06	1.9	0.03	4.1	<0.1	<0.05	5	<0.5	<0.2
K960391	Soil	34	0.76	56	0.091	<1	1.32	0.010	0.25	7.0	0.01	3.6	0.2	<0.05	5	<0.5	<0.2
K960392	Soil	33	0.82	52	0.101	<1	1.35	0.021	0.42	4.0	<0.01	2.7	0.2	<0.05	5	<0.5	<0.2
K960393	Soil	43	1.03	53	0.126	1	1.52	0.016	0.30	3.5	<0.01	3.9	0.2	<0.05	5	<0.5	<0.2
K960394	Soil	69	1.30	46	0.145	1	1.64	0.013	0.27	3.7	0.01	3.9	0.2	<0.05	6	<0.5	<0.2
K960395	Soil	50	1.21	29	0.143	1	1.45	0.019	0.19	4.4	<0.01	4.1	<0.1	<0.05	5	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960396	Soil	0.3	12.0	4.7	33	0.1	17.9	7.6	266	1.69	1.1	<0.5	9.4	10	0.1	0.1	0.1	31	0.26	0.079	16
K960397	Soil	0.4	16.3	5.0	42	0.2	14.6	7.7	231	1.94	1.2	<0.5	10.3	9	<0.1	<0.1	0.2	34	0.27	0.093	19
K960398	Soil	0.4	13.5	5.3	31	0.3	12.8	7.0	249	1.58	1.2	0.8	7.3	10	<0.1	0.1	0.3	30	0.26	0.086	18
K960399	Soil	0.4	15.2	5.6	36	0.4	16.9	8.6	282	1.79	1.2	<0.5	8.7	18	0.1	0.2	0.3	37	0.40	0.118	21
K960400	Soil	0.3	13.4	5.3	41	0.2	14.7	7.3	289	1.96	0.7	0.7	10.4	9	<0.1	<0.1	0.2	28	0.24	0.081	17
K960401	Soil	0.9	20.4	6.1	38	0.2	24.7	10.5	371	1.93	3.3	3.6	5.1	14	<0.1	0.5	0.1	33	0.19	0.054	15
K960402	Soil	0.7	19.7	5.1	49	0.1	76.9	16.8	600	2.89	2.4	1.6	2.4	36	0.1	0.4	<0.1	61	0.34	0.042	6
K960403	Soil	0.6	16.5	6.6	39	0.1	19.9	10.8	741	1.47	4.8	1.0	4.1	58	0.1	0.5	0.1	30	0.60	0.064	14
K960404	Soil	0.7	20.5	7.1	42	0.2	23.4	8.2	328	1.93	3.8	<0.5	6.2	14	0.1	0.3	0.1	32	0.18	0.056	12
K960405	Soil	0.6	23.6	7.9	36	0.7	73.9	10.9	329	1.96	4.7	7.4	3.3	19	0.1	0.3	<0.1	33	0.17	0.044	11
K960406	Soil	0.5	18.7	5.5	33	0.4	22.1	8.3	277	1.61	3.6	0.7	4.1	14	0.1	0.3	0.1	27	0.19	0.058	14
K960407	Soil	0.8	28.6	9.6	46	0.2	41.4	11.6	390	2.03	8.4	3.1	4.8	15	0.1	0.4	0.2	36	0.20	0.049	18
K960408	Soil	0.7	19.7	6.8	50	0.2	59.9	12.7	406	2.07	3.5	0.6	4.2	15	0.1	0.3	0.2	38	0.25	0.067	13
K960409	Soil	0.9	27.4	9.5	44	0.2	27.5	10.8	360	2.10	11.7	2.4	5.9	16	0.2	0.6	0.2	36	0.23	0.066	20
K960410	Soil	0.6	26.1	6.7	43	0.2	29.1	11.7	414	1.90	14.7	3.1	5.3	17	0.2	1.0	0.1	30	0.26	0.088	15
K960411	Soil	0.8	21.1	7.3	38	0.2	21.2	10.0	347	2.03	5.4	<0.5	3.8	13	<0.1	0.9	0.2	32	0.18	0.058	13
K960412	Soil	0.6	30.8	6.4	40	0.1	19.4	13.0	490	2.43	7.0	0.6	3.6	31	<0.1	0.4	<0.1	36	0.32	0.081	11
K960413	Soil	0.5	34.1	6.5	43	0.1	27.1	13.1	419	2.25	7.4	1.6	6.4	21	<0.1	0.6	0.1	32	0.27	0.058	13
K960414	Soil	0.5	45.8	6.3	30	<0.1	24.4	13.7	337	1.81	5.3	1.5	3.2	13	<0.1	0.8	0.2	39	0.18	0.035	8
K960415	Soil	0.6	25.7	5.6	46	<0.1	28.0	13.2	356	2.27	3.8	1.1	3.2	13	0.2	0.4	0.1	46	0.29	0.055	10
K960416	Soil	0.7	19.8	7.9	43	0.3	24.2	10.9	402	2.27	8.6	1.6	3.3	12	0.2	0.5	0.2	42	0.15	0.046	11
K960417	Soil	0.9	25.4	22.7	48	0.1	27.7	12.4	450	2.45	7.2	0.9	4.0	23	0.1	0.6	0.2	46	0.24	0.064	12
K960418	Soil	0.7	15.6	8.2	38	0.2	14.6	9.3	390	2.39	5.6	1.1	2.9	14	<0.1	0.5	0.2	48	0.15	0.045	11
K960419	Soil	0.5	14.0	6.7	43	0.2	13.2	10.7	602	2.19	4.0	<0.5	8.7	12	<0.1	0.5	0.1	30	0.18	0.068	14
K960420	Soil	0.8	17.4	7.0	35	0.1	16.3	9.6	453	1.97	1.8	1.5	6.1	9	<0.1	0.4	<0.1	28	0.09	0.033	11
K960421	Soil	0.6	16.6	6.4	41	0.2	14.3	10.3	405	2.20	3.0	1.7	5.4	13	<0.1	0.5	0.1	36	0.14	0.044	13
K960422	Soil	0.4	14.9	5.0	34	0.1	16.6	8.0	328	1.70	1.3	1.0	4.5	11	<0.1	0.2	<0.1	30	0.16	0.052	10
K960423	Soil	0.7	25.8	7.3	49	0.1	36.8	13.1	442	2.37	8.7	0.9	5.0	17	0.1	0.4	0.1	37	0.23	0.050	14
K960424	Soil	0.7	21.2	4.8	49	0.1	15.2	19.1	619	3.14	5.8	2.2	1.8	15	<0.1	1.5	<0.1	64	0.38	0.095	6
K960425	Soil	1.1	19.2	6.7	50	0.2	24.4	9.6	390	2.34	5.5	1.2	3.5	15	0.1	0.6	<0.1	41	0.21	0.062	9

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960396	Soil	30	0.64	45	0.116	1	1.08	0.020	0.42	4.3	<0.01	2.8	0.3	<0.05	4	<0.5	<0.2
K960397	Soil	21	0.67	72	0.121	<1	1.22	0.020	0.50	4.9	<0.01	3.1	0.3	<0.05	5	<0.5	<0.2
K960398	Soil	19	0.56	67	0.096	<1	1.07	0.017	0.35	6.4	0.01	2.4	0.2	<0.05	4	<0.5	<0.2
K960399	Soil	25	0.66	70	0.113	<1	1.20	0.016	0.38	4.8	<0.01	2.9	0.2	<0.05	4	<0.5	<0.2
K960400	Soil	20	0.57	58	0.147	<1	1.16	0.019	0.62	5.6	<0.01	3.1	0.3	<0.05	5	<0.5	<0.2
K960401	Soil	28	0.54	75	0.042	<1	0.83	0.014	0.11	6.0	0.01	2.5	<0.1	<0.05	2	<0.5	<0.2
K960402	Soil	91	1.93	57	0.063	<1	1.52	0.012	0.07	2.2	0.01	3.6	<0.1	<0.05	5	<0.5	<0.2
K960403	Soil	26	0.45	102	0.044	1	0.83	0.007	0.06	3.4	0.02	2.2	<0.1	<0.05	3	<0.5	<0.2
K960404	Soil	28	0.58	183	0.061	<1	0.94	0.013	0.19	4.2	<0.01	2.3	0.1	<0.05	4	<0.5	<0.2
K960405	Soil	109	1.10	509	0.042	<1	0.92	0.007	0.11	4.9	0.02	2.0	<0.1	<0.05	3	0.7	<0.2
K960406	Soil	24	0.44	99	0.028	1	0.70	0.008	0.10	7.6	0.02	1.9	<0.1	<0.05	3	<0.5	<0.2
K960407	Soil	45	0.67	85	0.059	<1	0.98	0.010	0.12	4.7	0.02	2.3	<0.1	<0.05	3	<0.5	<0.2
K960408	Soil	76	0.87	92	0.071	1	1.05	0.009	0.14	3.8	0.02	2.5	<0.1	<0.05	4	<0.5	<0.2
K960409	Soil	34	0.62	105	0.051	<1	0.95	0.008	0.12	4.1	0.01	2.7	<0.1	<0.05	3	<0.5	<0.2
K960410	Soil	38	0.61	80	0.041	1	0.80	0.011	0.12	4.6	0.02	2.4	<0.1	<0.05	2	<0.5	<0.2
K960411	Soil	32	0.48	65	0.039	1	0.81	0.008	0.15	4.8	0.02	2.4	0.1	<0.05	3	<0.5	<0.2
K960412	Soil	37	0.90	84	0.055	1	1.22	0.017	0.12	2.8	0.01	2.8	<0.1	<0.05	4	<0.5	<0.2
K960413	Soil	32	0.69	81	0.061	1	1.02	0.013	0.20	3.7	0.01	2.7	<0.1	<0.05	3	<0.5	<0.2
K960414	Soil	58	0.70	52	0.058	2	0.89	0.010	0.10	2.6	0.02	2.4	<0.1	<0.05	3	0.7	<0.2
K960415	Soil	40	0.76	111	0.083	<1	1.03	0.009	0.09	3.8	0.01	2.5	<0.1	<0.05	3	<0.5	<0.2
K960416	Soil	44	0.64	91	0.048	2	1.11	0.007	0.10	2.5	0.02	2.4	<0.1	<0.05	4	<0.5	<0.2
K960417	Soil	35	0.76	324	0.051	1	1.29	0.010	0.14	4.3	0.02	2.7	<0.1	<0.05	4	<0.5	<0.2
K960418	Soil	24	0.46	126	0.038	2	1.08	0.008	0.07	2.8	0.02	3.1	0.1	<0.05	4	<0.5	<0.2
K960419	Soil	18	0.59	73	0.028	<1	1.15	0.011	0.11	3.6	0.01	2.3	<0.1	<0.05	4	<0.5	<0.2
K960420	Soil	21	0.54	68	0.015	2	0.87	0.014	0.08	4.9	0.01	2.2	<0.1	<0.05	2	<0.5	<0.2
K960421	Soil	21	0.61	70	0.036	<1	1.20	0.008	0.13	4.6	<0.01	2.5	<0.1	<0.05	4	<0.5	<0.2
K960422	Soil	26	0.57	69	0.049	2	0.89	0.010	0.15	5.9	0.02	2.0	<0.1	<0.05	3	<0.5	<0.2
K960423	Soil	50	0.99	67	0.049	2	1.25	0.011	0.12	5.0	0.02	2.6	<0.1	<0.05	3	<0.5	<0.2
K960424	Soil	42	0.66	72	0.025	3	1.08	0.020	0.13	1.6	0.05	8.4	<0.1	<0.05	3	<0.5	<0.2
K960425	Soil	26	0.63	87	0.045	3	1.07	0.014	0.09	6.2	0.02	2.9	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960426	Soil	1.1	24.9	8.2	52	0.5	31.2	10.9	376	2.06	25.4	1.7	3.4	14	0.2	0.5	0.2	41	0.22	0.058	12
K960427	Soil	1.5	33.3	7.2	58	0.1	32.2	11.5	417	1.99	8.4	3.1	4.1	15	0.2	0.6	0.1	36	0.24	0.066	14
K960428	Soil	0.4	19.0	5.8	42	0.1	31.4	9.7	319	1.82	7.3	<0.5	6.4	13	0.1	0.4	0.2	29	0.22	0.061	12
K960429	Soil	0.4	20.4	5.8	38	0.1	24.3	11.4	339	2.05	3.7	0.6	3.0	14	0.1	0.3	<0.1	41	0.24	0.065	9
K960430	Soil	0.7	23.4	7.9	50	0.2	33.8	13.2	455	2.37	9.6	1.3	3.3	19	0.2	0.7	<0.1	39	0.27	0.060	12
K960431	Soil	1.3	42.0	14.7	81	0.4	39.6	13.5	935	2.99	47.0	5.4	4.6	18	0.3	1.9	0.1	35	0.38	0.071	36
K960432	Soil	0.7	21.8	5.3	43	0.2	22.6	12.5	391	2.53	4.9	<0.5	2.7	10	0.1	0.5	<0.1	46	0.16	0.042	9
K960433	Soil	0.4	19.7	3.7	45	<0.1	50.3	13.5	467	2.23	3.3	1.1	4.9	10	0.1	0.2	<0.1	42	0.20	0.040	12
K960434	Soil	0.6	22.9	6.0	37	0.2	40.0	11.1	345	1.85	3.6	0.9	2.5	15	0.1	0.4	<0.1	35	0.27	0.078	12
K960435	Soil	0.6	19.9	6.0	43	0.2	74.7	14.5	384	2.14	3.9	1.2	3.5	12	<0.1	0.3	<0.1	36	0.21	0.060	16
K960436	Soil	0.8	18.8	5.3	40	0.1	31.5	10.4	300	1.85	2.7	<0.5	3.2	14	0.2	0.3	0.1	37	0.28	0.072	10
K960437	Soil	0.6	9.2	10.6	37	0.2	12.5	7.0	659	1.61	2.8	1.9	2.9	23	0.1	0.2	0.2	40	0.23	0.040	7
K960438	Soil	0.5	16.8	5.2	45	0.2	16.8	10.6	377	2.16	2.7	0.9	2.4	15	0.2	0.2	<0.1	47	0.24	0.049	6
K960439	Soil	0.7	21.8	5.0	38	0.3	31.0	12.2	354	1.95	2.9	30.1	4.0	14	0.2	0.5	<0.1	39	0.28	0.078	12
K960440	Soil	0.9	18.5	6.6	58	0.1	41.3	11.7	337	1.97	2.6	1.2	6.0	10	0.2	0.2	0.1	40	0.26	0.087	13
K960441	Soil	0.9	24.0	7.0	49	0.2	36.9	11.6	407	2.16	3.0	<0.5	3.2	13	0.2	0.3	0.2	46	0.27	0.072	11
K960451	Soil	0.2	39.6	3.3	37	0.2	484.6	39.1	519	3.50	2.0	1.5	0.7	11	0.1	0.1	0.2	83	0.32	0.056	3
K960452	Soil	0.2	44.0	3.4	43	0.1	491.8	39.2	574	3.47	1.8	1.0	0.8	10	0.1	<0.1	<0.1	79	0.29	0.057	3
K960453	Soil	<0.1	40.1	4.0	37	0.2	452.5	37.3	360	2.97	2.6	0.5	1.2	9	<0.1	0.2	<0.1	67	0.25	0.048	4
K960454	Soil	0.2	40.8	3.4	40	0.2	487.4	39.6	408	3.03	2.9	1.0	1.5	10	0.1	0.2	0.1	69	0.28	0.042	5
K960455	Soil	0.3	48.4	14.7	63	0.5	313.5	27.5	881	2.69	7.4	8.6	1.5	12	0.3	0.4	0.4	55	0.32	0.057	7
K960456	Soil	0.3	30.7	12.7	46	0.3	230.7	23.5	621	2.37	6.9	2.7	2.0	10	0.2	0.3	0.1	42	0.22	0.053	8
K960457	Soil	<0.1	82.6	6.1	47	0.2	234.4	28.9	557	3.24	3.9	3.7	0.7	12	0.2	0.2	<0.1	84	0.27	0.056	3
K960458	Soil	0.3	43.7	3.6	43	<0.1	5.6	15.3	892	3.39	0.6	1.2	4.0	10	<0.1	<0.1	<0.1	42	0.56	0.213	15
K960459	Soil	1.6	46.9	8.5	71	0.3	34.8	14.2	594	2.65	4.4	3.0	3.4	18	0.2	0.5	0.1	58	0.41	0.106	12
K960460	Soil	0.5	56.5	4.3	39	<0.1	34.1	12.3	350	2.71	12.9	0.6	1.9	29	<0.1	0.2	<0.1	56	0.53	0.071	4
K960461	Soil	0.7	54.1	2.6	40	0.1	37.9	15.3	462	2.13	4.9	0.9	3.1	17	0.1	0.3	<0.1	40	0.35	0.095	9
K960462	Soil	0.4	25.3	13.3	60	0.1	32.0	13.6	504	2.75	1.9	<0.5	8.0	5	0.1	<0.1	0.1	21	0.17	0.052	17
K960463	Soil	0.9	26.2	6.9	51	0.2	17.4	10.2	389	2.23	2.8	0.7	2.7	15	0.1	0.2	0.1	46	0.29	0.092	12
K960464	Soil	0.6	20.1	6.4	52	0.1	16.3	13.1	331	2.54	2.3	<0.5	4.2	14	0.1	0.1	<0.1	54	0.25	0.080	11

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960426	Soil	31	0.58	94	0.050	1	1.15	0.012	0.09	4.2	0.02	2.2	<0.1	<0.05	3	<0.5	<0.2
K960427	Soil	28	0.60	91	0.041	1	0.96	0.008	0.09	5.2	0.02	2.1	<0.1	<0.05	3	<0.5	<0.2
K960428	Soil	26	0.61	69	0.068	2	0.93	0.018	0.21	4.9	<0.01	2.0	0.2	<0.05	3	<0.5	<0.2
K960429	Soil	25	0.70	153	0.057	2	1.11	0.009	0.12	2.6	0.01	1.8	<0.1	<0.05	3	<0.5	<0.2
K960430	Soil	32	0.65	82	0.039	2	1.16	0.008	0.11	3.5	0.01	2.5	<0.1	<0.05	3	<0.5	<0.2
K960431	Soil	34	0.53	164	0.020	2	1.02	0.008	0.12	4.4	0.03	4.4	0.1	<0.05	3	<0.5	<0.2
K960432	Soil	30	0.70	84	0.049	2	1.14	0.010	0.14	4.3	0.01	2.8	<0.1	<0.05	4	<0.5	<0.2
K960433	Soil	22	0.91	99	0.065	1	1.22	0.012	0.22	4.1	<0.01	2.0	<0.1	<0.05	3	<0.5	<0.2
K960434	Soil	42	0.58	109	0.048	2	0.72	0.009	0.09	4.3	<0.01	2.0	<0.1	<0.05	2	<0.5	<0.2
K960435	Soil	78	1.11	69	0.042	1	0.98	0.010	0.10	4.2	0.02	2.0	<0.1	<0.05	3	<0.5	<0.2
K960436	Soil	37	0.61	70	0.060	1	0.98	0.010	0.09	4.0	0.01	2.0	<0.1	<0.05	3	<0.5	<0.2
K960437	Soil	18	0.43	43	0.068	1	0.71	0.009	0.13	3.9	<0.01	1.5	<0.1	<0.05	4	<0.5	<0.2
K960438	Soil	27	0.80	89	0.072	1	1.18	0.009	0.19	3.6	0.02	1.7	<0.1	<0.05	3	<0.5	<0.2
K960439	Soil	32	0.62	77	0.061	1	0.99	0.013	0.10	4.6	<0.01	2.2	0.1	<0.05	3	<0.5	<0.2
K960440	Soil	38	0.66	78	0.076	<1	1.13	0.012	0.26	5.2	<0.01	2.8	0.2	<0.05	4	<0.5	<0.2
K960441	Soil	41	0.74	99	0.063	<1	1.04	0.011	0.12	4.2	0.03	2.6	0.1	<0.05	3	<0.5	<0.2
K960451	Soil	554	4.05	158	0.073	2	1.78	0.010	0.04	0.8	<0.01	5.7	0.1	<0.05	5	<0.5	<0.2
K960452	Soil	561	4.42	137	0.054	2	1.98	0.009	0.07	0.4	<0.01	5.3	<0.1	<0.05	6	<0.5	<0.2
K960453	Soil	451	3.43	83	0.064	2	1.58	0.012	0.04	0.9	<0.01	5.3	<0.1	<0.05	4	<0.5	<0.2
K960454	Soil	481	3.73	96	0.065	2	1.65	0.014	0.03	1.0	<0.01	6.3	<0.1	<0.05	5	<0.5	<0.2
K960455	Soil	287	2.55	188	0.045	2	1.56	0.010	0.07	2.9	<0.01	4.9	0.1	<0.05	4	<0.5	<0.2
K960456	Soil	290	2.80	164	0.033	2	1.08	0.010	0.09	2.6	0.01	3.9	0.1	<0.05	3	<0.5	<0.2
K960457	Soil	302	3.50	78	0.062	1	1.96	0.012	0.03	0.7	<0.01	4.9	<0.1	<0.05	6	<0.5	<0.2
K960458	Soil	9	1.00	132	0.020	<1	1.57	0.011	0.10	2.0	<0.01	3.8	<0.1	<0.05	5	<0.5	<0.2
K960459	Soil	32	0.89	176	0.059	1	1.51	0.012	0.10	3.9	<0.01	3.1	<0.1	<0.05	4	<0.5	<0.2
K960460	Soil	49	1.06	219	0.109	<1	1.58	0.034	0.30	1.1	<0.01	3.1	0.1	<0.05	4	<0.5	<0.2
K960461	Soil	27	0.69	107	0.059	<1	0.91	0.012	0.13	2.1	<0.01	2.5	<0.1	<0.05	3	<0.5	<0.2
K960462	Soil	35	0.54	78	0.066	1	0.96	0.008	0.18	1.5	<0.01	2.7	0.2	<0.05	2	<0.5	<0.2
K960463	Soil	24	0.68	116	0.064	<1	1.12	0.010	0.13	2.6	<0.01	2.3	<0.1	<0.05	4	<0.5	<0.2
K960464	Soil	17	0.75	92	0.072	<1	1.21	0.017	0.26	2.8	<0.01	3.2	0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960465	Soil	0.8	24.9	4.2	50	0.2	1.1	1.7	91	2.01	1.9	2.6	3.3	13	<0.1	<0.1	0.6	3	0.02	0.007	6
K960466	Soil	0.7	23.1	5.5	49	0.2	14.9	9.5	364	2.17	3.4	0.5	3.9	11	0.2	0.5	0.1	33	0.18	0.056	12
K960467	Soil	0.3	19.0	6.1	40	0.1	14.6	8.5	310	1.81	2.8	1.1	3.3	11	0.2	0.4	<0.1	27	0.17	0.051	8
K960468	Soil	0.8	24.3	7.5	45	0.2	14.6	7.4	311	2.04	4.2	1.4	3.6	22	0.1	0.2	0.1	47	0.20	0.049	13
K960469	Soil	0.3	41.3	3.5	79	0.2	1.9	1.4	419	3.15	<0.5	12.5	6.7	15	<0.1	<0.1	0.3	20	0.04	0.027	14
K960470	Soil	0.4	11.1	3.9	59	<0.1	24.7	12.3	476	2.65	2.0	0.5	2.9	10	<0.1	0.2	<0.1	52	0.13	0.027	8
K960471	Soil	0.6	9.8	1.8	32	<0.1	7.5	6.7	275	1.65	0.6	0.9	4.2	12	<0.1	<0.1	0.1	16	0.15	0.025	6
K960472	Soil	0.7	19.6	6.4	40	0.2	51.0	10.1	266	2.02	2.4	1.2	4.1	13	0.1	0.2	0.2	34	0.19	0.046	10
K960473	Soil	0.2	13.9	5.0	44	0.1	6.2	5.5	291	1.43	1.2	<0.5	6.4	11	<0.1	<0.1	0.1	20	0.12	0.030	7
K960474	Soil	0.6	22.4	7.3	51	0.2	21.2	11.1	329	2.11	2.7	1.0	4.8	16	<0.1	0.2	0.1	41	0.24	0.054	12
K960475	Soil	0.8	21.6	6.4	44	0.3	13.8	10.0	349	2.27	2.9	12.7	3.2	14	<0.1	0.3	0.1	48	0.21	0.031	7
K960476	Soil	0.3	16.3	2.7	20	0.1	3.8	5.1	178	1.02	1.5	1.7	1.5	15	<0.1	0.1	0.4	24	0.18	0.011	4
K960477	Soil	0.8	26.1	8.4	58	0.4	16.3	12.3	444	2.51	3.3	3.7	2.8	21	0.2	0.2	0.3	53	0.24	0.072	10
K960478	Soil	0.7	19.2	7.8	37	0.4	15.3	8.1	262	1.79	3.0	2.3	3.6	14	<0.1	0.2	0.1	36	0.21	0.056	10
K960479	Soil	0.7	24.9	5.3	34	0.3	15.0	8.7	305	1.69	2.8	1.2	3.6	16	0.1	0.2	<0.1	37	0.27	0.065	10
K960480	Soil	1.2	16.0	5.7	46	0.4	12.1	6.4	226	1.77	3.8	1.4	2.1	16	0.1	0.2	0.2	40	0.18	0.046	8
K960481	Soil	0.4	22.8	7.2	44	0.3	13.0	12.0	420	2.29	2.1	<0.5	1.4	16	<0.1	0.1	<0.1	58	0.34	0.048	4
K960482	Soil	0.7	8.3	4.7	20	0.7	7.0	4.1	138	1.03	1.7	<0.5	0.4	10	<0.1	0.1	<0.1	31	0.12	0.025	5
K960483	Soil	0.9	21.6	7.6	37	0.4	23.8	7.4	267	1.62	2.7	3.0	2.4	11	0.1	0.2	<0.1	37	0.16	0.040	7
K960484	Soil	0.6	21.3	6.6	46	0.3	17.3	9.2	385	1.96	2.0	<0.5	4.3	15	<0.1	0.2	<0.1	39	0.29	0.082	15
K960485	Soil	0.9	22.3	6.4	41	0.4	17.3	7.8	305	1.74	2.1	1.9	3.9	12	0.2	0.3	<0.1	40	0.26	0.078	14
K960486	Soil	1.2	17.4	7.3	42	0.4	19.9	7.8	251	1.98	4.0	8.7	3.2	12	0.2	0.4	<0.1	42	0.22	0.062	10
K960487	Soil	0.5	10.2	6.0	45	0.2	11.1	5.5	269	1.77	2.6	1.0	3.8	16	<0.1	0.2	1.3	39	0.21	0.065	13
K960488	Soil	0.3	8.5	3.9	35	0.1	9.1	5.1	255	1.35	2.5	0.9	4.9	13	<0.1	0.2	0.6	30	0.19	0.058	12
K960489	Soil	0.3	9.2	3.8	35	0.2	5.4	4.0	259	1.14	1.5	<0.5	3.4	9	<0.1	0.1	0.8	24	0.15	0.045	10
K960490	Soil	0.3	7.8	4.2	39	0.2	7.6	4.4	278	1.35	1.7	<0.5	4.3	11	0.1	0.2	0.6	29	0.20	0.062	12
K960491	Soil	0.3	7.1	4.7	34	0.1	5.7	4.1	252	1.13	1.9	1.2	3.7	9	<0.1	0.1	0.7	22	0.13	0.044	11
K960492	Soil	0.2	6.9	4.0	40	<0.1	5.1	3.7	293	1.07	1.4	<0.5	4.9	7	<0.1	<0.1	0.5	20	0.15	0.056	12
K960493	Soil	0.1	5.5	2.3	32	<0.1	3.3	3.1	230	0.96	0.9	<0.5	4.9	14	<0.1	0.1	0.2	21	0.14	0.049	11
K960494	Soil	0.4	7.0	4.2	35	0.1	6.2	4.0	252	1.17	1.7	<0.5	5.7	10	<0.1	0.2	0.4	24	0.14	0.044	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960465	Soil	2	0.07	315	0.009	1	0.32	0.017	0.16	3.6	<0.01	0.9	<0.1	<0.05	2	0.7	0.6
K960466	Soil	18	0.62	121	0.063	<1	1.13	0.009	0.17	3.6	<0.01	2.6	<0.1	<0.05	3	<0.5	<0.2
K960467	Soil	19	0.55	136	0.058	1	0.87	0.011	0.21	2.8	<0.01	2.0	<0.1	<0.05	3	<0.5	<0.2
K960468	Soil	27	0.58	115	0.090	1	1.17	0.009	0.26	2.2	0.01	2.0	0.2	<0.05	5	<0.5	<0.2
K960469	Soil	4	1.03	252	0.123	<1	1.38	0.012	0.91	1.4	<0.01	3.6	0.3	0.06	6	1.4	<0.2
K960470	Soil	84	1.75	145	0.084	<1	2.03	0.007	0.25	2.1	<0.01	4.1	0.1	<0.05	5	<0.5	<0.2
K960471	Soil	14	0.64	174	0.039	<1	1.01	0.035	0.32	1.9	<0.01	2.0	<0.1	0.18	3	<0.5	<0.2
K960472	Soil	66	0.83	106	0.066	2	1.00	0.023	0.20	4.0	<0.01	2.4	0.1	0.16	3	<0.5	<0.2
K960473	Soil	10	0.54	117	0.054	<1	0.79	0.027	0.31	4.4	<0.01	1.8	0.1	0.18	2	<0.5	<0.2
K960474	Soil	34	0.73	141	0.087	<1	1.22	0.016	0.14	2.9	<0.01	2.3	0.2	0.16	3	<0.5	<0.2
K960475	Soil	22	0.81	94	0.082	1	1.37	0.011	0.17	3.2	0.01	2.7	<0.1	0.17	4	<0.5	<0.2
K960476	Soil	9	0.35	260	0.044	<1	0.62	0.017	0.13	12.5	<0.01	1.6	0.2	0.10	2	<0.5	<0.2
K960477	Soil	31	0.80	228	0.082	<1	1.41	0.011	0.17	1.6	<0.01	2.4	0.1	0.16	5	<0.5	<0.2
K960478	Soil	26	0.58	113	0.057	<1	1.06	0.016	0.11	3.3	0.01	2.1	<0.1	0.19	3	<0.5	<0.2
K960479	Soil	21	0.63	150	0.062	<1	0.93	0.018	0.12	3.8	<0.01	2.1	<0.1	0.17	3	<0.5	<0.2
K960480	Soil	20	0.49	106	0.057	<1	0.99	0.012	0.10	1.4	0.02	1.7	<0.1	0.17	3	<0.5	<0.2
K960481	Soil	18	0.78	60	0.056	<1	1.25	0.040	0.11	1.6	<0.01	3.9	<0.1	0.18	4	<0.5	<0.2
K960482	Soil	13	0.26	78	0.046	<1	0.54	0.018	0.08	2.1	<0.01	1.0	<0.1	0.18	3	<0.5	<0.2
K960483	Soil	43	0.67	101	0.055	<1	0.86	0.007	0.14	3.1	0.01	1.9	0.1	0.16	3	<0.5	<0.2
K960484	Soil	24	0.69	138	0.056	<1	1.08	0.013	0.10	3.0	<0.01	2.7	<0.1	0.17	3	<0.5	<0.2
K960485	Soil	24	0.56	143	0.066	<1	0.90	0.010	0.17	3.4	<0.01	2.2	<0.1	0.16	3	<0.5	<0.2
K960486	Soil	29	0.55	102	0.062	<1	1.11	0.010	0.12	1.7	<0.01	2.3	<0.1	0.16	4	<0.5	<0.2
K960487	Soil	22	0.42	66	0.084	<1	1.39	0.015	0.22	3.5	0.03	2.3	0.3	0.19	6	<0.5	<0.2
K960488	Soil	16	0.36	60	0.072	<1	1.01	0.019	0.22	6.3	<0.01	1.9	0.3	0.16	4	<0.5	<0.2
K960489	Soil	13	0.29	44	0.065	<1	0.83	0.019	0.25	6.5	0.01	1.4	0.3	0.19	4	<0.5	<0.2
K960490	Soil	14	0.35	62	0.076	<1	1.08	0.017	0.27	5.2	0.01	1.7	0.3	0.16	4	<0.5	<0.2
K960491	Soil	13	0.25	42	0.054	<1	0.85	0.022	0.22	6.9	0.02	1.3	0.3	0.17	4	<0.5	<0.2
K960492	Soil	11	0.26	39	0.059	<1	0.76	0.018	0.25	7.4	0.02	1.5	0.3	0.16	4	<0.5	<0.2
K960493	Soil	9	0.28	37	0.064	<1	0.76	0.028	0.29	5.4	<0.01	1.7	0.3	0.16	4	<0.5	<0.2
K960494	Soil	13	0.30	41	0.058	<1	0.88	0.023	0.22	6.2	<0.01	1.7	0.3	0.15	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960495	Soil	0.4	6.8	3.7	31	0.1	5.2	3.6	235	1.13	1.2	<0.5	6.1	8	<0.1	0.2	1.0	23	0.13	0.042	12
K960496	Soil	0.3	6.9	4.5	37	<0.1	5.8	4.4	261	1.40	1.6	<0.5	6.2	16	<0.1	0.1	0.6	30	0.20	0.061	14
K960497	Soil	0.4	8.9	4.8	39	0.2	10.9	4.4	243	1.15	7.1	<0.5	8.7	10	0.1	0.4	0.3	23	0.20	0.060	18
K960498	Soil	0.7	9.8	6.6	41	0.1	9.9	5.2	311	1.45	3.1	1.4	4.3	8	0.1	0.3	0.6	27	0.12	0.039	13
K960499	Soil	0.4	9.9	4.4	21	0.2	6.5	3.0	235	0.67	1.6	<0.5	4.8	8	<0.1	0.3	0.4	12	0.09	0.023	8
K960500	Soil	0.1	6.8	4.6	20	0.1	3.5	2.5	150	0.58	0.9	<0.5	3.9	7	0.1	0.2	0.5	12	0.11	0.029	7
K960501	Soil	1.1	15.9	12.2	32	0.3	13.7	6.6	259	1.48	2.7	1.7	2.4	15	<0.1	0.2	1.1	32	0.27	0.047	12
K960502	Soil	1.0	38.1	5.6	35	0.1	23.2	12.0	388	2.22	2.7	0.6	5.9	7	<0.1	0.2	0.5	33	0.11	0.027	12
K960503	Soil	2.0	22.7	6.8	36	0.2	22.5	9.6	267	2.16	2.6	<0.5	3.1	10	<0.1	0.1	1.0	39	0.23	0.062	12
K960504	Soil	1.3	35.2	7.1	51	0.2	25.5	11.6	304	2.70	2.1	<0.5	5.6	11	<0.1	0.1	1.0	50	0.27	0.041	15
K960505	Soil	1.5	57.1	7.8	212	0.3	42.4	15.1	1213	3.53	3.6	<0.5	6.1	14	0.2	0.2	3.7	63	0.28	0.043	18
K960506	Soil	2.9	22.4	8.4	40	0.4	20.9	9.0	255	1.83	3.7	<0.5	2.8	19	<0.1	0.2	2.2	39	0.42	0.042	14
K960507	Soil	1.5	25.7	9.4	64	0.2	34.4	12.0	321	2.60	4.0	<0.5	6.5	25	<0.1	0.2	0.7	54	0.45	0.045	19
K960508	Soil	2.8	57.2	7.4	80	0.1	47.1	17.8	420	3.79	1.5	<0.5	7.7	14	<0.1	0.1	0.6	51	0.37	0.027	22
K960509	Soil	1.7	22.8	8.5	43	0.1	14.2	7.3	330	1.53	4.0	0.6	6.5	13	<0.1	0.4	1.0	24	0.16	0.037	14
K960510	Soil	1.2	22.5	9.8	42	0.4	23.5	10.2	311	1.83	4.2	0.8	5.8	28	<0.1	0.2	1.7	33	0.27	0.036	17
K960511	Soil	2.5	26.5	9.7	42	0.3	13.5	7.9	483	1.64	3.6	<0.5	5.4	16	0.1	0.3	2.6	31	0.34	0.043	14
K960512	Soil	1.5	30.3	7.8	73	0.5	46.4	13.5	437	2.75	3.4	2.2	4.9	21	0.3	0.3	0.5	84	0.28	0.061	14
K960513	Soil	1.1	18.2	5.7	49	0.6	18.0	8.0	310	2.10	1.9	2.8	5.1	15	0.1	0.1	0.3	68	0.27	0.050	14
K960514	Soil	1.1	25.2	8.3	80	0.5	31.6	11.2	490	2.61	2.2	1.5	8.5	19	0.2	0.2	0.3	81	0.31	0.087	20
K960515	Soil	1.2	28.8	7.7	64	0.5	38.0	10.3	343	2.57	2.7	2.2	3.9	21	0.2	0.2	0.4	80	0.24	0.052	17
K960516	Soil	0.8	25.5	6.7	63	0.2	31.5	10.5	336	2.29	1.8	<0.5	5.6	26	0.4	0.1	0.3	78	0.43	0.101	15
K960517	Soil	1.1	21.8	7.6	60	0.2	29.9	9.2	309	2.41	2.8	1.4	6.3	20	0.3	0.2	0.6	76	0.27	0.067	17
K960518	Soil	1.4	21.2	6.5	57	0.2	25.0	9.2	321	2.02	1.8	1.2	4.4	23	0.3	0.1	1.3	70	0.32	0.070	13
K960519	Soil	1.3	20.5	6.2	52	0.6	25.1	8.6	275	2.01	3.3	1.5	3.5	16	0.2	0.2	0.4	63	0.23	0.049	10
K960520	Soil	1.1	19.9	7.9	59	0.6	24.7	8.9	304	2.40	2.1	0.5	5.9	18	0.3	0.2	0.4	81	0.23	0.059	13
K960521	Soil	2.6	30.2	6.2	176	0.4	27.2	9.1	325	2.41	1.4	<0.5	6.1	27	1.8	0.2	0.4	101	0.52	0.060	13
K960522	Soil	1.4	25.7	6.1	64	0.4	32.5	10.4	365	2.39	2.4	2.3	3.3	19	0.2	0.2	0.4	79	0.28	0.048	10
K960523	Soil	1.6	23.1	5.3	54	0.4	27.6	9.4	295	2.30	2.2	0.6	3.2	14	0.3	0.2	0.2	83	0.25	0.038	10
K960524	Soil	2.8	28.4	6.3	84	0.4	32.3	10.4	303	2.55	1.9	3.3	2.7	22	0.7	0.2	0.3	101	0.47	0.110	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960495	Soil	12	0.28	39	0.067	<1	0.74	0.023	0.23	6.9	0.01	1.6	0.3	0.16	4	<0.5	<0.2
K960496	Soil	13	0.37	62	0.083	<1	1.20	0.025	0.31	6.8	<0.01	2.4	0.4	0.18	5	<0.5	<0.2
K960497	Soil	13	0.27	61	0.059	<1	0.67	0.026	0.19	7.1	0.02	1.5	0.2	0.16	3	<0.5	<0.2
K960498	Soil	16	0.34	55	0.050	<1	1.01	0.014	0.17	6.4	0.02	1.7	0.3	0.16	4	<0.5	<0.2
K960499	Soil	10	0.17	46	0.026	<1	0.56	0.018	0.11	6.3	<0.01	1.0	0.1	0.17	2	<0.5	<0.2
K960500	Soil	7	0.14	37	0.024	<1	0.50	0.020	0.11	5.9	<0.01	1.1	0.2	0.15	2	<0.5	<0.2
K960501	Soil	26	0.50	48	0.070	<1	1.08	0.042	0.23	6.7	0.02	1.4	0.3	0.20	5	<0.5	<0.2
K960502	Soil	33	0.89	75	0.098	<1	1.60	0.019	0.61	8.9	<0.01	2.8	0.3	0.18	5	<0.5	<0.2
K960503	Soil	35	0.67	58	0.087	<1	1.47	0.018	0.34	7.8	0.03	2.5	0.2	0.17	5	<0.5	<0.2
K960504	Soil	56	1.11	44	0.105	<1	1.77	0.037	0.26	6.6	<0.01	2.3	0.2	0.17	7	<0.5	<0.2
K960505	Soil	72	2.65	100	0.161	<1	3.16	0.023	1.20	4.9	0.02	5.0	2.2	0.14	15	<0.5	<0.2
K960506	Soil	35	0.71	41	0.072	<1	1.55	0.030	0.19	8.6	0.01	2.1	0.4	0.22	6	<0.5	<0.2
K960507	Soil	55	1.35	80	0.143	1	2.41	0.066	0.76	5.5	0.02	3.2	0.9	<0.05	8	<0.5	<0.2
K960508	Soil	40	1.08	130	0.193	1	2.70	0.020	1.08	4.0	<0.01	4.3	0.7	<0.05	8	<0.5	<0.2
K960509	Soil	20	0.45	48	0.071	1	1.22	0.020	0.28	6.5	0.04	1.7	0.3	<0.05	4	<0.5	<0.2
K960510	Soil	32	0.66	58	0.080	<1	1.80	0.032	0.29	7.5	0.02	2.0	0.4	<0.05	6	<0.5	<0.2
K960511	Soil	25	0.56	78	0.085	1	1.35	0.048	0.46	6.9	0.02	2.3	0.6	<0.05	5	<0.5	<0.2
K960512	Soil	59	0.87	205	0.109	2	2.06	0.019	0.24	4.4	0.02	4.9	0.3	<0.05	6	<0.5	<0.2
K960513	Soil	32	0.62	126	0.099	<1	1.21	0.024	0.18	4.4	0.01	3.4	0.2	<0.05	5	<0.5	<0.2
K960514	Soil	44	0.81	155	0.113	<1	1.72	0.019	0.25	3.9	<0.01	4.7	0.3	<0.05	7	0.6	<0.2
K960515	Soil	58	0.75	199	0.097	<1	1.91	0.017	0.13	3.4	0.02	4.1	0.2	<0.05	6	<0.5	<0.2
K960516	Soil	46	0.76	155	0.113	<1	1.73	0.029	0.17	3.6	<0.01	4.1	0.2	<0.05	5	0.6	<0.2
K960517	Soil	54	0.78	129	0.106	1	1.74	0.017	0.13	3.7	0.02	3.7	0.2	<0.05	6	<0.5	<0.2
K960518	Soil	42	0.71	147	0.098	<1	1.54	0.022	0.16	3.8	0.02	3.2	0.2	<0.05	5	<0.5	<0.2
K960519	Soil	42	0.58	129	0.080	<1	1.32	0.019	0.11	7.4	0.01	3.5	0.1	<0.05	4	<0.5	<0.2
K960520	Soil	49	0.70	146	0.123	<1	1.60	0.016	0.22	4.3	0.03	3.7	0.2	<0.05	6	<0.5	<0.2
K960521	Soil	37	0.65	170	0.090	<1	1.72	0.045	0.22	6.4	<0.01	4.6	0.3	0.26	6	1.6	<0.2
K960522	Soil	52	0.74	199	0.107	1	1.57	0.019	0.13	4.4	0.02	4.3	0.2	<0.05	5	<0.5	<0.2
K960523	Soil	43	0.56	157	0.114	<1	1.24	0.021	0.10	3.5	0.01	3.6	0.1	<0.05	4	<0.5	<0.2
K960524	Soil	59	0.68	232	0.105	1	1.84	0.022	0.14	4.6	0.01	4.2	0.2	0.07	6	1.3	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960525	Soil	1.2	15.7	3.8	40	0.6	21.5	6.8	211	1.43	2.4	<0.5	1.3	12	0.2	0.2	0.2	47	0.20	0.040	7
K960526	Soil	1.3	28.5	6.1	63	0.2	33.9	11.1	377	2.40	2.9	1.6	3.9	18	0.3	0.2	0.3	75	0.26	0.045	12
K960527	Soil	1.6	23.4	5.9	63	0.5	34.7	9.5	308	2.30	2.6	0.5	3.3	15	0.3	0.2	0.4	80	0.24	0.050	10
K960528	Soil	0.4	14.8	5.2	54	0.2	10.4	6.4	372	1.82	1.0	<0.5	21.4	19	0.2	<0.1	<0.1	50	0.48	0.111	48
K960529	Soil	1.5	21.0	6.3	57	0.3	28.2	9.3	304	2.14	2.6	1.1	5.3	17	0.2	0.2	0.3	68	0.25	0.044	12
K960530	Soil	0.5	18.4	7.3	40	0.2	14.7	6.9	307	1.79	1.8	2.3	15.1	19	0.2	0.1	0.4	50	0.32	0.092	29
K960531	Soil	1.2	19.4	7.1	54	0.4	19.9	9.1	339	2.12	2.2	3.5	10.4	15	0.2	0.2	0.2	70	0.29	0.073	26
K960532	Soil	1.3	19.0	9.4	61	0.3	24.9	8.9	386	2.36	3.0	2.2	3.0	17	0.3	0.2	0.3	69	0.31	0.052	11
K960533	Soil	1.4	28.9	7.3	80	0.4	32.0	11.1	408	2.64	2.5	0.9	4.7	25	0.6	0.2	0.3	87	0.33	0.077	14
K960534	Soil	0.4	12.6	6.5	50	0.2	10.7	5.9	322	1.81	0.7	<0.5	17.8	21	<0.1	<0.1	0.1	51	0.29	0.111	35
K960535	Soil	0.6	21.8	8.1	64	0.3	21.6	7.8	443	2.23	2.0	<0.5	11.7	22	0.2	0.1	0.2	64	0.31	0.091	28
K960536	Soil	0.6	41.3	4.9	76	0.2	21.1	16.6	576	3.32	1.5	1.1	4.6	28	0.2	0.1	0.2	92	0.43	0.083	12
K960537	Soil	0.2	10.5	5.5	42	<0.1	4.7	4.6	294	1.57	0.7	<0.5	20.4	15	0.1	<0.1	<0.1	42	0.32	0.113	39
K960538	Soil	0.4	12.9	6.7	52	0.2	16.9	7.4	352	2.04	1.5	<0.5	15.0	18	<0.1	<0.1	0.4	59	0.37	0.112	29
K960539	Soil	1.2	11.0	9.4	47	0.4	12.6	5.0	218	1.15	1.7	<0.5	6.1	9	0.4	<0.1	0.5	31	0.10	0.025	8
K960540	Soil	4.0	57.2	6.5	53	0.5	9.8	2.2	186	5.57	20.6	27.4	2.9	16	0.2	0.4	1.7	48	0.03	0.087	7
K960541	Soil	2.4	23.2	4.0	53	0.3	5.8	2.4	196	2.60	<0.5	<0.5	3.3	29	0.2	<0.1	0.5	47	0.03	0.052	9
K960542	Soil	5.7	20.4	12.8	81	0.5	11.6	4.5	210	2.16	2.8	1.7	6.0	15	0.3	0.2	1.6	62	0.07	0.033	9
K960543	Soil	0.9	15.4	9.8	44	0.2	18.7	7.4	285	1.54	3.2	1.7	12.0	15	0.1	0.2	0.3	47	0.19	0.037	14
K960544	Soil	1.6	33.8	7.4	79	0.1	40.4	11.9	381	2.54	3.6	1.4	4.1	19	0.6	0.2	0.4	80	0.23	0.042	10
K960545	Soil	1.9	23.4	8.2	66	0.2	25.7	8.4	292	2.25	3.3	1.1	4.5	15	0.5	0.2	0.4	76	0.17	0.044	10
K960546	Soil	1.6	26.9	6.5	61	0.3	34.6	10.5	304	2.13	3.5	1.1	3.4	17	0.2	0.3	0.3	73	0.22	0.044	9
K960547	Soil	1.2	32.9	6.1	61	0.3	38.1	10.5	296	2.06	3.2	1.7	4.1	20	0.2	0.2	0.3	71	0.19	0.036	10
K960548	Soil	1.6	29.0	8.1	85	0.2	36.9	10.9	330	2.42	3.7	1.5	4.2	18	0.4	0.2	0.4	70	0.26	0.052	10
K960549	Soil	2.8	24.3	6.9	89	0.3	31.5	10.1	294	2.27	3.9	0.9	2.1	18	0.6	0.3	0.3	94	0.24	0.046	8
K960550	Soil	1.4	22.0	6.5	62	0.2	28.3	9.2	320	2.12	3.0	8.3	3.4	15	0.2	0.2	0.3	70	0.24	0.047	8
K960551	Soil	0.3	7.5	5.1	33	0.2	4.7	4.0	202	1.06	2.6	<0.5	6.6	12	<0.1	0.3	0.4	22	0.12	0.040	13
K960552	Soil	0.4	6.1	5.4	24	0.2	4.8	3.0	151	0.93	2.7	<0.5	3.9	6	<0.1	0.3	0.3	18	0.09	0.038	10
K960553	Soil	0.3	8.9	4.6	26	0.2	3.5	3.0	183	0.87	2.3	0.5	4.8	6	<0.1	0.3	0.2	18	0.09	0.036	11
K960554	Soil	0.3	5.4	3.9	21	0.1	3.0	2.6	175	0.58	2.3	<0.5	4.5	4	<0.1	0.3	0.9	10	0.08	0.031	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960525	Soil	32	0.43	95	0.056	<1	1.13	0.014	0.10	14.1	0.01	2.1	0.1	<0.05	3	<0.5	<0.2
K960526	Soil	45	0.66	203	0.104	<1	1.50	0.017	0.12	3.8	<0.01	3.8	0.2	<0.05	5	0.5	<0.2
K960527	Soil	54	0.68	146	0.094	<1	1.54	0.018	0.14	4.6	0.02	3.8	0.2	<0.05	5	<0.5	<0.2
K960528	Soil	21	0.56	169	0.122	<1	1.05	0.039	0.55	3.5	<0.01	4.0	0.5	<0.05	5	<0.5	<0.2
K960529	Soil	39	0.56	165	0.077	<1	1.47	0.018	0.14	4.2	0.01	3.5	0.2	<0.05	5	0.6	<0.2
K960530	Soil	26	0.54	145	0.096	<1	1.19	0.020	0.32	3.9	<0.01	3.7	0.3	<0.05	5	<0.5	<0.2
K960531	Soil	31	0.64	179	0.118	<1	1.44	0.025	0.28	5.1	0.02	4.0	0.3	<0.05	5	<0.5	<0.2
K960532	Soil	35	0.62	206	0.090	<1	1.78	0.030	0.17	3.2	0.02	4.2	0.2	<0.05	6	<0.5	<0.2
K960533	Soil	41	0.70	205	0.124	<1	1.73	0.022	0.13	3.2	0.02	4.5	0.2	<0.05	5	0.6	<0.2
K960534	Soil	19	0.55	134	0.113	<1	1.14	0.032	0.47	3.5	0.01	3.8	0.5	<0.05	5	<0.5	<0.2
K960535	Soil	31	0.66	156	0.108	<1	1.53	0.018	0.31	3.4	<0.01	4.2	0.4	<0.05	6	<0.5	<0.2
K960536	Soil	27	1.60	231	0.102	<1	2.26	0.020	0.28	1.9	0.02	3.8	0.2	<0.05	6	<0.5	<0.2
K960537	Soil	12	0.49	113	0.111	<1	0.91	0.029	0.47	3.4	0.01	3.5	0.4	<0.05	5	<0.5	<0.2
K960538	Soil	26	0.59	145	0.114	<1	1.39	0.020	0.44	3.8	0.01	4.0	0.5	<0.05	6	<0.5	<0.2
K960539	Soil	20	0.32	78	0.048	<1	0.79	0.022	0.13	7.4	<0.01	1.8	0.1	<0.05	3	<0.5	<0.2
K960540	Soil	37	0.44	91	0.045	<1	1.16	0.011	0.20	3.7	<0.01	1.8	0.2	<0.05	4	1.0	<0.2
K960541	Soil	47	0.52	164	0.091	<1	1.03	0.028	0.48	4.8	<0.01	1.6	0.9	0.31	3	1.4	<0.2
K960542	Soil	30	0.38	111	0.071	<1	1.11	0.016	0.14	6.3	<0.01	2.8	0.2	<0.05	5	0.6	<0.2
K960543	Soil	29	0.41	124	0.062	<1	1.07	0.019	0.11	5.2	0.01	2.6	0.1	<0.05	3	0.5	<0.2
K960544	Soil	52	0.75	190	0.098	<1	1.92	0.016	0.18	3.8	0.02	4.6	0.2	<0.05	5	0.7	<0.2
K960545	Soil	42	0.59	133	0.085	<1	1.52	0.015	0.16	4.7	0.03	3.8	0.2	<0.05	5	0.8	<0.2
K960546	Soil	49	0.65	166	0.084	<1	1.47	0.018	0.13	4.7	0.01	3.7	0.1	<0.05	4	0.6	<0.2
K960547	Soil	52	0.63	174	0.082	1	1.49	0.023	0.13	4.4	0.01	3.7	0.2	<0.05	5	<0.5	<0.2
K960548	Soil	44	0.62	167	0.091	1	1.63	0.015	0.15	4.6	0.02	3.8	0.2	0.08	5	1.4	<0.2
K960549	Soil	45	0.64	198	0.081	<1	1.50	0.016	0.15	4.9	0.02	3.5	0.2	0.06	5	1.3	<0.2
K960550	Soil	43	0.63	156	0.096	<1	1.45	0.016	0.16	5.3	0.02	3.9	0.2	<0.05	5	0.7	<0.2
K960551	Soil	11	0.24	63	0.059	<1	0.93	0.018	0.23	7.7	<0.01	1.6	0.3	<0.05	4	<0.5	<0.2
K960552	Soil	12	0.19	33	0.040	<1	0.78	0.021	0.14	6.2	0.01	1.2	0.2	<0.05	3	<0.5	<0.2
K960553	Soil	8	0.18	38	0.043	<1	0.67	0.018	0.20	7.0	0.01	1.0	0.3	<0.05	4	<0.5	<0.2
K960554	Soil	7	0.14	28	0.027	<1	0.58	0.016	0.15	8.4	<0.01	0.9	0.2	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960555	Soil	0.4	10.6	6.8	37	<0.1	9.9	5.2	264	1.30	4.0	<0.5	7.8	10	0.1	0.3	0.8	25	0.17	0.049	14
K960556	Soil	0.3	6.3	6.1	40	0.5	3.6	3.2	359	0.94	1.1	<0.5	6.3	7	0.2	0.2	0.3	19	0.13	0.047	12
K960557	Soil	0.4	7.4	5.2	31	0.4	3.8	3.1	185	0.99	2.6	<0.5	6.9	5	<0.1	0.2	0.5	20	0.11	0.047	12
K960558	Soil	0.5	6.2	6.1	24	0.1	4.9	3.1	162	0.87	2.0	1.0	4.0	6	0.1	0.2	0.4	19	0.08	0.032	10
K960559	Soil	0.3	6.5	7.7	36	0.2	4.1	3.3	295	0.83	1.8	<0.5	7.9	5	0.1	0.3	1.7	15	0.10	0.041	12
K960560	Soil	0.6	10.4	11.5	48	0.6	7.3	4.4	252	1.17	3.4	<0.5	6.6	7	0.2	0.3	5.0	22	0.15	0.045	14
K960561	Soil	1.0	30.7	12.2	43	0.2	21.7	14.3	602	2.14	2.6	1.3	3.7	14	<0.1	0.1	0.2	16	0.06	0.045	16
K960562	Soil	0.8	33.5	10.0	50	0.2	25.0	12.5	573	2.15	1.5	4.2	6.1	18	0.1	<0.1	0.2	16	0.10	0.058	23
K960563	Soil	1.1	37.5	13.1	51	0.3	23.4	13.0	585	2.46	1.5	3.0	6.5	14	<0.1	<0.1	0.1	18	0.08	0.056	25
K960564	Soil	0.9	28.0	10.4	43	0.2	19.9	10.9	462	2.32	1.3	1.8	4.0	10	<0.1	<0.1	0.1	16	0.04	0.043	18
K960565	Soil	0.4	10.4	9.9	14	0.2	5.9	3.0	118	0.61	<0.5	4.7	3.4	11	<0.1	<0.1	0.3	6	0.06	0.042	19
K960566	Soil	0.4	20.6	8.0	45	0.2	21.1	10.4	591	2.04	1.2	3.6	5.6	7	<0.1	<0.1	0.1	15	0.06	0.037	20
K960567	Soil	0.7	27.2	8.5	58	0.1	26.7	13.2	429	2.34	1.3	5.9	7.7	11	<0.1	<0.1	0.2	15	0.13	0.083	28
K960568	Soil	1.4	23.1	6.0	30	0.2	14.7	11.9	546	1.56	1.1	2.4	9.1	8	<0.1	<0.1	0.1	8	0.06	0.033	23
K960569	Soil	0.3	17.3	9.6	42	0.1	14.5	8.0	909	1.93	<0.5	1.0	6.0	262	0.1	<0.1	<0.1	5	5.00	0.044	22
K960570	Soil	0.9	57.5	9.4	73	0.2	33.9	14.2	1128	2.77	0.8	4.2	8.0	32	0.2	<0.1	0.1	32	0.28	0.088	26
K960571	Soil	0.6	61.2	4.4	77	0.1	26.9	18.1	1291	3.02	<0.5	2.3	5.6	42	0.1	<0.1	<0.1	56	0.55	0.099	17
K960572	Soil	0.5	32.0	16.0	59	0.2	31.7	13.9	744	2.95	3.9	24.1	9.9	31	0.2	0.2	0.2	20	0.97	0.066	32
K960573	Soil	0.3	10.9	10.4	20	0.1	9.6	6.2	727	1.38	0.7	<0.5	5.7	110	0.1	<0.1	<0.1	6	3.93	0.049	23
K960574	Soil	0.3	15.6	12.5	43	0.1	23.1	9.9	474	2.22	0.9	<0.5	7.1	72	<0.1	<0.1	0.1	9	2.46	0.054	26

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

CERTIFICATE OF ANALYSIS WHI12000009.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960555	Soil	19	0.46	77	0.071	<1	1.32	0.023	0.28	6.5	<0.01	2.1	0.4	<0.05	5	<0.5	<0.2
K960556	Soil	8	0.24	33	0.052	<1	0.60	0.016	0.21	5.5	0.01	1.4	0.2	<0.05	4	<0.5	<0.2
K960557	Soil	13	0.22	28	0.055	<1	0.77	0.016	0.21	7.4	0.02	1.5	0.3	<0.05	4	<0.5	<0.2
K960558	Soil	12	0.18	38	0.043	155	0.61	0.040	0.14	5.5	<0.01	1.2	0.2	<0.05	3	<0.5	<0.2
K960559	Soil	10	0.23	34	0.047	<1	0.70	0.026	0.26	10.1	<0.01	1.1	0.3	<0.05	3	<0.5	<0.2
K960560	Soil	14	0.29	40	0.066	<1	0.83	0.018	0.29	8.3	<0.01	1.6	0.3	<0.05	4	<0.5	<0.2
K960561	Soil	14	0.44	61	0.017	<1	0.88	0.004	0.13	9.7	0.01	1.2	0.1	<0.05	2	<0.5	<0.2
K960562	Soil	16	0.54	64	0.020	<1	0.95	0.004	0.14	6.5	<0.01	1.4	<0.1	<0.05	3	<0.5	<0.2
K960563	Soil	16	0.55	63	0.017	<1	1.13	0.003	0.13	6.3	<0.01	1.6	0.1	<0.05	3	<0.5	<0.2
K960564	Soil	16	0.48	46	0.012	<1	0.95	0.003	0.11	6.5	<0.01	1.0	<0.1	<0.05	3	<0.5	<0.2
K960565	Soil	5	0.11	54	0.006	<1	0.36	0.004	0.15	4.5	0.01	0.5	<0.1	<0.05	1	<0.5	<0.2
K960566	Soil	15	0.42	49	0.012	<1	0.86	0.004	0.12	6.8	<0.01	1.2	<0.1	<0.05	2	<0.5	<0.2
K960567	Soil	16	0.54	42	0.014	<1	0.95	0.003	0.11	4.5	<0.01	1.1	<0.1	<0.05	3	<0.5	<0.2
K960568	Soil	9	0.19	48	0.006	<1	0.51	0.004	0.13	8.8	<0.01	1.0	<0.1	<0.05	1	<0.5	<0.2
K960569	Soil	5	1.23	28	0.004	<1	0.25	0.003	0.08	3.6	<0.01	0.9	<0.1	<0.05	<1	<0.5	<0.2
K960570	Soil	25	0.93	65	0.047	<1	1.22	0.007	0.27	2.8	0.01	2.9	0.2	<0.05	4	<0.5	<0.2
K960571	Soil	27	1.37	119	0.075	<1	1.64	0.007	0.39	2.3	0.01	3.3	0.2	<0.05	5	<0.5	<0.2
K960572	Soil	18	0.82	69	0.022	2	1.23	0.006	0.14	6.1	<0.01	2.6	0.1	<0.05	3	<0.5	<0.2
K960573	Soil	8	0.44	56	0.006	<1	0.32	0.007	0.12	4.6	<0.01	1.1	<0.1	<0.05	<1	<0.5	<0.2
K960574	Soil	13	0.94	50	0.011	<1	0.73	0.005	0.11	4.6	<0.01	1.3	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

QUALITY CONTROL REPORT WHI12000009.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
K960249	Soil	0.4	16.1	13.6	36	<0.1	351.3	27.0	344	2.17	3.1	<0.5	4.8	5	0.1	0.1	0.1	49	0.27	0.055	6
REP K960249	QC	0.4	17.6	11.5	36	<0.1	374.8	28.6	361	2.32	3.1	<0.5	4.8	5	0.2	0.1	0.1	53	0.26	0.053	6
K960252	Soil	0.9	13.0	13.4	36	0.4	14.7	5.7	257	1.43	2.3	2.8	5.0	14	<0.1	0.2	1.0	34	0.19	0.047	16
REP K960252	QC	0.8	13.2	13.5	39	0.4	15.4	6.3	266	1.54	2.5	1.2	5.4	14	<0.1	0.2	1.4	36	0.20	0.046	15
K960292	Soil	0.6	58.9	9.5	52	0.4	53.4	21.9	598	3.43	4.8	4.5	2.5	17	0.1	0.5	<0.1	97	0.51	0.077	7
REP K960292	QC	0.6	57.3	9.1	52	0.4	54.0	22.9	603	3.42	5.1	1.3	2.5	18	0.2	0.5	<0.1	98	0.53	0.071	7
K960313	Soil	0.4	50.4	10.7	48	2.3	70.1	12.4	617	2.11	4.7	7.6	2.3	6	0.3	0.4	<0.1	25	0.13	0.057	10
REP K960313	QC	0.4	50.6	10.8	47	2.1	69.8	12.5	621	2.10	4.6	8.9	2.4	6	0.2	0.4	0.1	25	0.12	0.054	10
K960321	Soil	0.3	30.7	10.0	58	1.3	231.9	25.0	662	3.02	10.9	1.7	2.3	9	0.2	0.3	0.4	46	0.18	0.058	8
REP K960321	QC	0.2	29.0	9.6	57	1.2	228.8	24.9	655	3.02	11.1	2.8	2.3	9	0.2	0.3	0.4	46	0.18	0.057	8
K960350	Soil	0.3	40.5	9.7	39	1.2	87.7	15.8	510	2.58	11.3	0.6	4.3	23	0.2	0.4	0.6	44	0.36	0.087	8
REP K960350	QC	0.3	40.4	10.1	39	1.2	90.1	16.1	537	2.67	11.4	0.7	4.5	23	0.1	0.4	0.6	45	0.38	0.087	8
K960360	Soil	0.9	35.7	16.7	70	0.5	24.9	12.6	606	2.96	241.0	50.5	4.1	28	0.3	1.6	<0.1	30	0.29	0.101	17
REP K960360	QC	0.8	35.8	17.0	65	0.6	23.9	12.8	621	3.10	241.8	51.8	4.2	28	0.3	1.6	<0.1	29	0.28	0.095	16
K960367	Soil	0.5	42.4	5.2	61	0.4	23.3	17.3	392	4.13	19.7	13.3	3.5	16	0.1	1.9	0.1	68	0.43	0.118	10
REP K960367	QC	0.6	41.0	5.5	62	0.4	23.6	17.7	397	4.16	20.3	2.4	3.7	16	<0.1	2.0	0.1	69	0.46	0.119	11
K960391	Soil	0.9	24.5	7.0	51	0.5	25.7	10.9	340	2.39	2.8	<0.5	6.2	11	<0.1	0.6	0.3	50	0.22	0.081	16
REP K960391	QC	1.0	26.3	6.8	54	0.5	27.2	11.6	347	2.41	2.9	<0.5	6.1	12	0.1	0.6	0.3	49	0.24	0.076	17
K960417	Soil	0.9	25.4	22.7	48	0.1	27.7	12.4	450	2.45	7.2	0.9	4.0	23	0.1	0.6	0.2	46	0.24	0.064	12
REP K960417	QC	0.9	25.8	22.6	50	0.1	28.7	13.0	483	2.52	6.9	1.9	4.0	23	0.1	0.5	0.2	48	0.25	0.061	13
K960428	Soil	0.4	19.0	5.8	42	0.1	31.4	9.7	319	1.82	7.3	<0.5	6.4	13	0.1	0.4	0.2	29	0.22	0.061	12
REP K960428	QC	0.4	19.9	5.9	41	0.2	32.5	10.2	323	1.85	7.8	1.6	6.3	13	0.1	0.4	0.2	30	0.23	0.060	13
K960454	Soil	0.2	40.8	3.4	40	0.2	487.4	39.6	408	3.03	2.9	1.0	1.5	10	0.1	0.2	0.1	69	0.28	0.042	5
REP K960454	QC	0.2	39.3	3.6	41	0.2	476.0	40.8	415	3.09	3.2	1.0	1.5	10	0.1	0.3	0.1	69	0.27	0.041	5
K960488	Soil	0.3	8.5	3.9	35	0.1	9.1	5.1	255	1.35	2.5	0.9	4.9	13	<0.1	0.2	0.6	30	0.19	0.058	12
REP K960488	QC	0.3	8.8	3.9	36	0.1	8.9	5.3	260	1.37	2.7	5.2	5.0	13	<0.1	0.2	0.6	30	0.20	0.058	12
K960499	Soil	0.4	9.9	4.4	21	0.2	6.5	3.0	235	0.67	1.6	<0.5	4.8	8	<0.1	0.3	0.4	12	0.09	0.023	8
REP K960499	QC	0.4	9.5	4.6	21	0.2	6.4	3.1	231	0.67	1.2	<0.5	4.8	9	<0.1	0.4	0.5	12	0.09	0.023	8

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

QUALITY CONTROL REPORT WHI12000009.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
K960249	Soil	267	2.94	33	0.084	3	1.19	0.014	0.21	1.5	<0.01	4.3	0.1	<0.05	4	<0.5	<0.2
REP K960249	QC	276	2.76	31	0.091	3	1.20	0.013	0.21	1.6	<0.01	4.3	0.1	<0.05	4	<0.5	<0.2
K960252	Soil	27	0.45	74	0.084	<1	1.10	0.019	0.24	7.3	<0.01	2.3	0.2	<0.05	5	<0.5	<0.2
REP K960252	QC	29	0.45	75	0.085	1	1.06	0.018	0.28	7.5	<0.01	2.4	0.2	<0.05	5	<0.5	<0.2
K960292	Soil	88	1.73	215	0.128	<1	1.95	0.046	0.16	0.7	0.02	6.7	0.1	<0.05	6	<0.5	<0.2
REP K960292	QC	92	1.66	210	0.127	1	1.89	0.045	0.15	0.7	0.01	6.3	<0.1	<0.05	6	<0.5	<0.2
K960313	Soil	52	0.45	391	0.011	1	0.57	0.002	0.05	5.7	0.02	4.1	<0.1	<0.05	2	<0.5	<0.2
REP K960313	QC	50	0.45	392	0.010	<1	0.55	0.002	0.05	5.6	0.03	4.1	<0.1	<0.05	2	<0.5	<0.2
K960321	Soil	257	2.73	213	0.037	2	1.34	0.010	0.11	1.7	0.02	4.3	0.2	<0.05	5	<0.5	<0.2
REP K960321	QC	255	2.72	212	0.038	2	1.29	0.012	0.11	1.8	<0.01	4.4	0.2	<0.05	5	<0.5	<0.2
K960350	Soil	84	1.37	153	0.064	2	1.07	0.014	0.19	2.5	<0.01	3.0	0.1	<0.05	4	<0.5	<0.2
REP K960350	QC	89	1.42	159	0.067	<1	1.08	0.014	0.19	2.6	<0.01	3.3	0.1	<0.05	4	<0.5	<0.2
K960360	Soil	25	0.67	144	0.015	<1	1.06	0.007	0.10	3.3	0.01	3.6	<0.1	<0.05	4	<0.5	<0.2
REP K960360	QC	25	0.67	141	0.016	2	1.04	0.007	0.10	3.2	0.02	3.6	0.1	<0.05	4	<0.5	<0.2
K960367	Soil	19	0.67	149	0.043	<1	1.33	0.017	0.06	2.2	0.01	5.7	<0.1	<0.05	5	<0.5	<0.2
REP K960367	QC	20	0.69	155	0.046	<1	1.38	0.018	0.07	2.4	0.02	6.2	<0.1	<0.05	5	<0.5	<0.2
K960391	Soil	34	0.76	56	0.091	<1	1.32	0.010	0.25	7.0	0.01	3.6	0.2	<0.05	5	<0.5	<0.2
REP K960391	QC	33	0.76	56	0.095	<1	1.35	0.011	0.26	7.4	0.02	3.9	0.2	<0.05	5	<0.5	<0.2
K960417	Soil	35	0.76	324	0.051	1	1.29	0.010	0.14	4.3	0.02	2.7	<0.1	<0.05	4	<0.5	<0.2
REP K960417	QC	36	0.72	325	0.052	2	1.25	0.009	0.13	4.3	0.02	2.8	0.1	<0.05	4	0.6	<0.2
K960428	Soil	26	0.61	69	0.068	2	0.93	0.018	0.21	4.9	<0.01	2.0	0.2	<0.05	3	<0.5	<0.2
REP K960428	QC	26	0.60	68	0.069	1	0.93	0.021	0.21	5.2	<0.01	2.0	0.2	<0.05	3	<0.5	<0.2
K960454	Soil	481	3.73	96	0.065	2	1.65	0.014	0.03	1.0	<0.01	6.3	<0.1	<0.05	5	<0.5	<0.2
REP K960454	QC	497	3.78	94	0.069	3	1.67	0.014	0.03	1.0	<0.01	6.3	<0.1	<0.05	5	<0.5	<0.2
K960488	Soil	16	0.36	60	0.072	<1	1.01	0.019	0.22	6.3	<0.01	1.9	0.3	0.16	4	<0.5	<0.2
REP K960488	QC	16	0.36	60	0.071	<1	0.98	0.019	0.23	6.6	<0.01	1.8	0.3	0.17	4	<0.5	<0.2
K960499	Soil	10	0.17	46	0.026	<1	0.56	0.018	0.11	6.3	<0.01	1.0	0.1	0.17	2	<0.5	<0.2
REP K960499	QC	10	0.17	46	0.026	<1	0.55	0.021	0.11	6.4	<0.01	0.9	0.1	0.14	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

QUALITY CONTROL REPORT WHI12000009.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
K960509	Soil	1.7	22.8	8.5	43	0.1	14.2	7.3	330	1.53	4.0	0.6	6.5	13	<0.1	0.4	1.0	24	0.16	0.037	14
REP K960509	QC	1.5	20.9	7.9	42	0.1	13.0	7.1	320	1.47	3.7	<0.5	6.5	13	<0.1	0.4	0.8	23	0.15	0.037	14
K960532	Soil	1.3	19.0	9.4	61	0.3	24.9	8.9	386	2.36	3.0	2.2	3.0	17	0.3	0.2	0.3	69	0.31	0.052	11
REP K960532	QC	1.2	19.6	9.6	64	0.4	25.4	9.0	387	2.35	2.7	1.0	2.9	17	0.2	0.2	0.3	70	0.34	0.055	11
K960567	Soil	0.7	27.2	8.5	58	0.1	26.7	13.2	429	2.34	1.3	5.9	7.7	11	<0.1	<0.1	0.2	15	0.13	0.083	28
REP K960567	QC	0.8	26.0	8.2	60	0.2	25.9	12.7	424	2.30	1.4	5.6	8.1	10	<0.1	<0.1	0.2	15	0.12	0.074	26
K960570	Soil	0.9	57.5	9.4	73	0.2	33.9	14.2	1128	2.77	0.8	4.2	8.0	32	0.2	<0.1	0.1	32	0.28	0.088	26
REP K960570	QC	0.9	60.4	9.3	75	0.2	35.3	14.5	1156	2.84	0.6	4.3	8.1	37	0.2	<0.1	0.1	31	0.31	0.091	27
Reference Materials																					
STD DS8	Standard	13.1	109.1	124.7	317	1.8	37.6	7.6	602	2.40	22.6	126.6	6.6	62	2.1	5.2	5.3	46	0.67	0.073	15
STD DS8	Standard	12.7	107.6	121.5	310	1.8	37.4	7.4	605	2.42	23.9	113.1	6.7	62	2.2	5.1	5.9	41	0.68	0.078	15
STD DS8	Standard	13.4	114.3	118.7	309	1.7	36.9	7.3	574	2.30	24.2	107.9	7.2	61	2.5	5.5	6.2	42	0.63	0.079	14
STD DS8	Standard	12.1	102.8	117.0	287	1.8	35.9	7.1	579	2.31	22.0	105.8	7.0	66	2.1	5.5	6.6	42	0.67	0.074	15
STD DS8	Standard	13.2	111.5	115.0	304	1.7	36.0	7.1	594	2.33	25.6	106.9	6.8	62	2.5	5.5	6.1	41	0.67	0.079	15
STD DS8	Standard	12.5	106.7	121.5	305	1.8	38.0	7.2	587	2.36	23.0	114.0	6.2	61	2.2	5.4	5.9	42	0.65	0.075	15
STD DS8	Standard	13.4	110.9	123.8	311	1.8	40.0	7.8	625	2.51	23.2	103.0	6.4	67	2.3	5.4	6.1	45	0.71	0.075	17
STD DS8	Standard	14.0	117.9	117.6	306	1.8	40.3	8.4	612	2.50	25.7	108.0	7.6	68	2.6	6.0	6.4	47	0.72	0.077	17
STD DS8	Standard	14.0	113.5	117.9	304	1.7	38.6	8.0	600	2.38	24.6	101.6	7.4	69	2.5	5.9	6.5	46	0.71	0.078	16
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	3	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	0.5	<1	<0.1	<0.1	<0.1	<1	0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 20, 2012

QUALITY CONTROL REPORT WHI12000009.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
K960509	Soil	20	0.45	48	0.071	1	1.22	0.020	0.28	6.5	0.04	1.7	0.3	<0.05	4	<0.5	<0.2
REP K960509	QC	19	0.43	48	0.065	1	1.17	0.022	0.29	6.6	0.02	1.6	0.3	<0.05	4	<0.5	<0.2
K960532	Soil	35	0.62	206	0.090	<1	1.78	0.030	0.17	3.2	0.02	4.2	0.2	<0.05	6	<0.5	<0.2
REP K960532	QC	36	0.65	203	0.095	<1	1.88	0.029	0.16	3.5	0.02	4.2	0.2	<0.05	6	0.5	<0.2
K960567	Soil	16	0.54	42	0.014	<1	0.95	0.003	0.11	4.5	<0.01	1.1	<0.1	<0.05	3	<0.5	<0.2
REP K960567	QC	16	0.53	40	0.015	<1	0.91	0.004	0.11	4.1	<0.01	1.1	<0.1	<0.05	3	<0.5	<0.2
K960570	Soil	25	0.93	65	0.047	<1	1.22	0.007	0.27	2.8	0.01	2.9	0.2	<0.05	4	<0.5	<0.2
REP K960570	QC	24	0.96	69	0.050	14	1.24	0.009	0.28	2.9	<0.01	3.1	0.2	0.07	4	<0.5	<0.2
Reference Materials																	
STD DS8	Standard	124	0.60	262	0.115	2	0.89	0.098	0.43	3.2	0.20	2.5	5.4	0.28	5	5.6	5.0
STD DS8	Standard	115	0.60	281	0.102	3	0.91	0.097	0.41	3.1	0.18	2.8	5.2	0.10	5	4.7	4.8
STD DS8	Standard	113	0.61	269	0.113	3	0.86	0.078	0.37	3.1	0.17	2.2	5.7	0.11	5	5.1	5.1
STD DS8	Standard	113	0.60	260	0.119	3	0.87	0.078	0.38	2.8	0.20	2.4	4.9	0.15	4	4.3	4.2
STD DS8	Standard	113	0.58	275	0.110	3	0.91	0.084	0.40	2.9	0.20	2.3	5.2	0.21	4	5.4	4.3
STD DS8	Standard	117	0.59	267	0.112	2	0.86	0.071	0.35	2.9	0.18	2.2	5.4	0.08	5	6.1	4.8
STD DS8	Standard	123	0.62	279	0.123	3	0.93	0.085	0.41	3.0	0.17	2.8	5.4	0.09	5	5.0	4.9
STD DS8	Standard	125	0.61	290	0.125	2	0.93	0.085	0.39	2.8	0.19	2.6	5.1	0.18	5	5.3	5.1
STD DS8	Standard	125	0.62	292	0.122	3	0.94	0.106	0.45	2.9	0.20	3.0	5.2	0.18	5	5.3	4.8
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	0.18	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Submitted By: Andrew Caldwell
Receiving Lab: Canada-Whitehorse
Received: March 05, 2012
Report Date: March 28, 2012
Page: 1 of 12

CERTIFICATE OF ANALYSIS WHI12000010.1

CLIENT JOB INFORMATION

Project: LIVINGSTONE
Shipment ID: SRV-2012-AC-2140
P.O. Number
Number of Samples: 302

SAMPLE DISPOSAL

RTRN-PLP Return
RTRN-RJT Return

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
Dry at 60C	302	Dry at 60C			WHI
SS80	302	Dry at 60C sieve 100g to -80 mesh			WHI
1DX2	302	1:1:1 Aqua Regia digestion ICP-MS analysis	15	Completed	VAN
RJSV	302	Saving all or part of Soil Reject			WHI

ADDITIONAL COMMENTS

Invoice To: Predator Mining Group
11th Floor- 888 Dunsmuir Street
Vancouver BC V6C 3K4
Canada

CC: Jack Cote
Linda Lewis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960575	Soil	0.4	22.9	15.3	54	0.1	29.0	11.6	557	2.66	2.9	2.5	6.2	11	<0.1	0.1	0.3	20	0.18	0.046	27
K960576	Soil	0.4	25.6	15.7	54	0.2	29.1	12.5	580	2.86	3.1	4.1	7.3	13	0.1	0.2	0.2	18	0.34	0.056	22
K960577	Soil	0.2	45.0	5.8	98	<0.1	42.7	17.1	187	3.77	<0.5	<0.5	9.7	10	<0.1	<0.1	<0.1	21	0.19	0.063	20
K960578	Soil	0.3	25.2	16.6	63	<0.1	30.8	13.9	516	2.90	3.0	3.1	9.5	8	0.1	<0.1	0.2	17	0.14	0.060	21
K960579	Soil	0.3	28.2	16.4	63	<0.1	33.3	13.3	467	2.81	2.8	1.6	8.6	13	<0.1	0.1	0.2	20	0.14	0.054	23
K960580	Soil	0.4	11.9	8.5	42	0.2	14.3	7.3	302	1.97	2.9	1.7	7.4	18	0.1	0.2	0.5	42	0.24	0.073	25
K960581	Soil	<0.1	10.4	9.9	21	<0.1	15.6	7.3	477	1.51	<0.5	<0.5	5.7	204	0.1	<0.1	<0.1	4	6.20	0.040	19
K960582	Soil	0.1	18.4	31.3	64	<0.1	32.9	13.5	477	2.87	1.9	1.0	7.8	22	<0.1	<0.1	0.2	16	0.37	0.043	26
K960583	Soil	0.6	22.2	16.3	56	0.1	24.7	9.8	368	2.40	2.9	0.8	4.3	10	0.1	0.1	<0.1	22	0.23	0.042	20
K960584	Soil	0.6	35.1	9.2	59	<0.1	29.2	11.6	749	3.24	0.7	1.1	9.3	12	0.1	<0.1	<0.1	12	0.74	0.061	26
K960585	Soil	1.4	37.9	17.2	50	0.1	25.4	13.0	576	2.46	1.5	2.0	4.9	17	<0.1	<0.1	<0.1	18	0.09	0.052	13
K960586	Soil	2.7	56.8	17.8	65	0.2	36.8	17.3	1037	2.91	1.2	19.6	4.9	61	0.2	<0.1	0.1	44	0.32	0.094	16
K960587	Soil	1.4	24.1	11.2	31	0.2	14.4	9.0	393	1.68	1.7	3.9	1.7	12	<0.1	0.1	<0.1	16	0.05	0.039	9
K960588	Soil	0.3	17.5	17.7	30	<0.1	11.2	5.8	186	1.24	<0.5	1.6	6.2	3	<0.1	<0.1	<0.1	7	0.04	0.026	12
K960589	Soil	1.2	36.3	16.8	55	0.2	17.5	9.0	400	2.41	1.4	0.8	6.4	13	0.1	<0.1	0.2	20	0.07	0.052	22
K960590	Soil	0.5	15.3	3.5	27	<0.1	15.3	14.7	367	1.12	<0.5	110.8	5.6	7	<0.1	<0.1	<0.1	10	0.04	0.022	10
K960591	Soil	2.1	30.6	10.5	37	0.3	13.9	8.7	1178	1.30	0.6	5.5	1.3	30	0.2	0.2	<0.1	17	0.46	0.099	17
K960592	Soil	0.5	30.2	13.3	48	0.1	27.4	10.9	697	2.08	1.3	17.0	5.0	30	0.1	<0.1	<0.1	25	0.89	0.047	21
K960593	Soil	0.5	28.2	15.3	55	0.3	30.1	13.0	653	2.54	1.1	4.0	5.9	17	0.1	<0.1	0.2	39	0.25	0.059	23
K960594	Soil	0.6	35.1	14.8	66	0.2	34.1	14.2	747	2.75	3.4	2.3	7.5	23	0.2	<0.1	0.1	46	0.36	0.050	23
K960595	Soil	0.6	44.4	5.1	60	0.1	8.1	4.8	274	3.88	<0.5	0.9	9.7	11	<0.1	<0.1	<0.1	36	0.02	0.035	17
K960596	Soil	0.8	31.3	11.6	53	0.1	19.2	10.2	600	2.17	<0.5	0.8	4.1	12	0.2	<0.1	<0.1	32	0.20	0.051	10
K960597	Soil	0.1	30.6	8.3	63	<0.1	30.7	18.1	479	2.81	<0.5	3.7	8.6	4	<0.1	<0.1	<0.1	31	0.06	0.038	22
K960598	Soil	0.4	17.2	5.9	49	0.1	11.4	7.1	446	1.98	1.1	0.8	4.1	11	<0.1	<0.1	<0.1	22	0.06	0.036	14
K960599	Soil	0.3	12.2	6.1	72	<0.1	22.2	12.5	537	2.95	0.6	5.5	5.0	9	<0.1	<0.1	<0.1	35	0.15	0.056	14
K960600	Soil	0.5	46.4	9.6	44	<0.1	17.6	8.9	509	1.92	1.1	1.3	5.7	10	0.1	<0.1	<0.1	39	0.10	0.042	12
K960601	Soil	1.5	22.7	7.4	62	0.2	30.9	10.1	322	2.04	2.9	1.5	7.2	15	0.3	0.3	0.2	69	0.19	0.040	10
K960602	Soil	0.3	2.6	16.1	28	<0.1	2.7	3.5	240	0.93	1.8	<0.5	17.8	6	0.1	0.1	1.8	9	0.11	0.061	16
K960603	Soil	1.4	36.6	6.2	111	0.3	32.6	16.1	564	3.70	2.0	1.3	2.6	51	0.3	0.2	0.2	129	1.04	0.045	4
K960604	Soil	1.4	18.8	5.8	36	0.3	15.1	5.9	232	1.23	1.7	1.2	2.2	10	0.2	0.2	0.4	40	0.14	0.037	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960575	Soil	19	0.82	79	0.022	<1	1.28	0.006	0.10	4.4	<0.01	2.0	0.1	<0.05	4	<0.5	<0.2
K960576	Soil	19	0.74	84	0.031	<1	1.21	0.006	0.10	5.7	0.01	2.1	0.1	<0.05	3	<0.5	<0.2
K960577	Soil	25	1.53	46	0.023	<1	1.97	0.005	0.23	0.9	<0.01	1.5	0.2	<0.05	6	<0.5	<0.2
K960578	Soil	19	0.86	47	0.017	1	1.25	0.005	0.12	4.5	<0.01	1.6	0.2	<0.05	4	<0.5	<0.2
K960579	Soil	20	0.85	83	0.021	<1	1.51	0.005	0.13	4.2	<0.01	1.9	0.2	<0.05	4	<0.5	<0.2
K960580	Soil	21	0.58	113	0.084	<1	1.21	0.016	0.30	4.6	0.01	2.6	0.3	<0.05	5	<0.5	<0.2
K960581	Soil	4	0.83	26	0.006	1	0.29	0.007	0.12	2.9	<0.01	1.1	<0.1	0.07	<1	<0.5	<0.2
K960582	Soil	20	1.00	52	0.030	<1	1.31	0.004	0.16	3.4	<0.01	1.8	0.2	<0.05	4	<0.5	<0.2
K960583	Soil	21	0.82	54	0.017	1	1.27	0.005	0.10	4.4	0.01	1.7	0.1	<0.05	4	<0.5	<0.2
K960584	Soil	12	0.49	58	0.017	1	0.82	0.005	0.19	1.6	<0.01	1.9	0.2	<0.05	3	<0.5	<0.2
K960585	Soil	18	0.58	57	0.023	<1	1.01	0.004	0.13	7.4	<0.01	1.3	0.1	<0.05	3	<0.5	<0.2
K960586	Soil	20	1.01	160	0.045	<1	1.55	0.011	0.43	5.3	<0.01	3.1	0.2	0.16	5	0.8	<0.2
K960587	Soil	11	0.28	41	0.017	<1	0.55	0.003	0.10	10.2	0.01	0.8	<0.1	<0.05	2	<0.5	<0.2
K960588	Soil	11	0.37	41	0.015	<1	0.65	0.003	0.16	8.2	<0.01	0.7	<0.1	<0.05	2	<0.5	<0.2
K960589	Soil	22	0.56	59	0.029	1	1.02	0.006	0.16	4.9	0.01	1.5	0.2	<0.05	3	<0.5	<0.2
K960590	Soil	10	0.26	64	0.029	<1	0.54	0.003	0.27	9.9	<0.01	0.7	0.1	0.09	2	<0.5	<0.2
K960591	Soil	17	0.40	98	0.020	<1	0.88	0.006	0.09	16.5	0.04	1.2	0.1	0.14	3	1.3	<0.2
K960592	Soil	26	0.98	105	0.051	<1	1.39	0.004	0.27	5.7	<0.01	2.3	0.2	<0.05	4	<0.5	<0.2
K960593	Soil	36	1.24	128	0.068	<1	1.59	0.007	0.34	7.5	<0.01	4.0	0.2	<0.05	5	<0.5	<0.2
K960594	Soil	41	1.44	175	0.103	1	1.94	0.017	0.52	4.9	<0.01	4.1	0.3	<0.05	7	<0.5	<0.2
K960595	Soil	26	0.94	190	0.106	<1	1.79	0.012	0.75	2.0	<0.01	3.1	0.3	0.33	6	2.8	<0.2
K960596	Soil	23	0.77	91	0.049	<1	1.19	0.009	0.31	7.1	0.01	2.4	0.1	0.07	4	<0.5	<0.2
K960597	Soil	27	0.96	98	0.104	<1	1.81	0.005	0.80	3.9	<0.01	2.9	0.3	<0.05	6	<0.5	<0.2
K960598	Soil	23	0.62	85	0.055	<1	1.15	0.009	0.36	8.0	<0.01	2.0	0.1	0.05	4	<0.5	<0.2
K960599	Soil	28	0.98	88	0.087	<1	1.91	0.007	0.65	3.6	<0.01	2.4	0.4	0.06	6	<0.5	<0.2
K960600	Soil	25	0.96	151	0.070	<1	1.44	0.008	0.45	7.3	<0.01	2.9	0.2	<0.05	4	<0.5	<0.2
K960601	Soil	45	0.61	162	0.079	<1	1.46	0.016	0.12	6.6	0.01	4.0	0.1	0.07	4	0.6	<0.2
K960602	Soil	6	0.10	44	0.003	<1	0.58	0.015	0.09	5.5	0.01	1.3	<0.1	<0.05	2	<0.5	<0.2
K960603	Soil	50	1.30	481	0.172	<1	3.32	0.124	0.78	3.7	0.01	7.1	0.4	0.14	8	0.6	<0.2
K960604	Soil	24	0.31	130	0.046	<1	0.84	0.015	0.10	5.8	0.02	2.2	0.1	0.06	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960605	Soil	0.2	13.1	4.2	36	0.2	15.6	9.7	352	1.95	3.9	1.1	1.7	54	0.1	0.4	<0.1	63	0.35	0.073	5
K960606	Soil	<0.1	3.5	4.7	38	0.1	9.0	7.9	396	2.28	0.7	<0.5	1.9	40	<0.1	0.1	<0.1	66	0.43	0.102	5
K960607	Soil	0.2	19.4	3.9	38	0.3	14.9	10.2	422	2.14	6.2	<0.5	1.6	41	<0.1	0.5	<0.1	64	0.51	0.079	6
K960608	Soil	0.2	16.8	3.9	52	0.3	16.1	11.7	571	2.38	3.8	2.2	2.2	35	<0.1	0.3	<0.1	68	0.48	0.107	7
K960609	Soil	0.3	36.8	8.3	46	0.3	26.5	15.5	600	2.78	15.0	4.4	2.5	23	<0.1	1.1	<0.1	65	0.39	0.081	8
K960610	Soil	0.3	21.3	4.3	43	0.2	17.4	10.7	463	2.52	11.0	1.9	1.4	21	<0.1	1.0	<0.1	65	0.30	0.061	7
K960611	Soil	<0.1	14.4	3.8	30	<0.1	11.7	8.6	381	1.85	4.1	4.4	2.8	33	<0.1	0.3	<0.1	54	0.44	0.087	6
K960612	Soil	0.2	16.7	4.1	41	0.3	16.9	10.3	449	2.49	16.7	2.9	1.2	18	<0.1	1.0	<0.1	56	0.24	0.054	6
K960613	Soil	<0.1	26.5	3.9	38	0.3	16.0	9.9	463	2.36	9.8	2.8	1.3	18	<0.1	0.6	<0.1	61	0.46	0.086	5
K960614	Soil	<0.1	18.1	3.4	43	0.2	16.9	10.7	517	2.40	10.0	2.3	1.7	36	<0.1	0.5	<0.1	60	0.60	0.091	6
K960615	Soil	0.2	12.0	4.8	36	0.2	33.6	12.4	380	2.52	10.3	2.6	1.5	26	<0.1	0.8	<0.1	61	0.30	0.065	5
K960616	Soil	0.2	19.2	8.8	43	0.3	32.3	12.9	572	2.70	13.2	2.7	1.0	20	<0.1	0.9	<0.1	62	0.31	0.060	6
K960617	Soil	0.1	19.1	5.0	41	0.3	29.8	11.4	470	2.49	14.9	3.3	1.9	21	<0.1	1.1	<0.1	59	0.42	0.086	7
K960618	Soil	<0.1	2.3	3.6	49	<0.1	12.0	10.3	591	2.56	<0.5	0.7	2.1	39	<0.1	<0.1	<0.1	69	0.58	0.108	5
K960619	Soil	<0.1	7.9	3.1	25	<0.1	11.5	7.5	321	1.84	0.6	0.8	2.3	41	<0.1	<0.1	<0.1	64	0.53	0.082	5
K960620	Soil	<0.1	2.1	1.3	28	<0.1	6.5	5.5	290	1.55	<0.5	0.6	3.1	35	<0.1	<0.1	<0.1	53	0.47	0.084	5
K960621	Soil	<0.1	23.4	3.6	40	<0.1	28.2	13.7	406	2.40	5.6	0.8	1.6	27	<0.1	0.5	<0.1	54	0.38	0.063	4
K960622	Soil	0.2	10.5	3.6	36	0.2	12.2	7.8	405	1.88	1.9	1.0	1.1	25	<0.1	0.2	<0.1	51	0.36	0.080	5
K960623	Soil	<0.1	4.2	3.4	50	<0.1	12.8	10.2	486	2.51	1.3	<0.5	1.9	28	<0.1	<0.1	<0.1	69	0.33	0.077	5
K960624	Soil	<0.1	2.7	2.1	32	<0.1	7.2	5.8	289	1.61	<0.5	<0.5	2.3	36	<0.1	<0.1	<0.1	47	0.43	0.089	4
K960625	Soil	<0.1	3.1	4.5	43	0.1	8.3	7.3	431	2.08	1.0	1.2	1.9	59	<0.1	0.1	<0.1	54	0.71	0.093	5
K960651	Soil	0.5	18.8	5.1	42	0.2	22.7	10.4	317	2.05	2.7	<0.5	4.4	11	<0.1	0.2	<0.1	39	0.20	0.059	11
K960652	Soil	0.6	25.3	7.7	52	0.2	31.0	13.3	429	2.50	2.6	<0.5	3.5	13	0.1	0.3	0.2	39	0.22	0.070	11
K960653	Soil	0.6	21.3	7.9	47	0.2	32.3	11.0	308	2.32	3.1	<0.5	4.1	18	<0.1	0.3	0.1	39	0.25	0.069	12
K960654	Soil	0.4	28.5	5.1	58	0.3	30.1	14.4	427	2.41	1.4	1.9	9.4	14	0.3	0.1	<0.1	38	0.23	0.063	21
K960655	Soil	0.7	16.2	4.8	36	0.6	18.4	8.7	268	1.46	1.9	1.0	5.6	12	<0.1	0.2	<0.1	24	0.21	0.069	13
K960656	Soil	0.7	21.8	7.9	40	0.3	18.8	10.8	361	1.92	1.6	<0.5	3.1	34	0.1	0.3	<0.1	36	0.33	0.070	9
K960657	Soil	0.6	19.0	8.5	51	0.3	24.2	9.6	290	2.29	2.9	<0.5	4.9	17	<0.1	0.7	<0.1	34	0.31	0.089	16
K960658	Soil	0.6	16.7	7.7	54	0.1	28.3	11.9	352	2.44	3.2	<0.5	3.1	20	<0.1	0.3	0.1	46	0.29	0.083	9
K960659	Soil	0.4	41.6	6.4	46	0.2	34.5	12.6	340	2.58	4.3	1.3	6.7	17	<0.1	0.6	<0.1	31	0.23	0.055	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960605	Soil	40	0.62	61	0.061	<1	1.04	0.023	0.05	4.4	0.02	2.3	<0.1	0.05	4	<0.5	<0.2
K960606	Soil	32	0.71	56	0.072	<1	0.85	0.044	0.05	1.8	<0.01	3.6	<0.1	<0.05	4	<0.5	<0.2
K960607	Soil	32	0.78	79	0.068	1	1.37	0.022	0.06	3.2	0.02	3.3	<0.1	<0.05	5	<0.5	<0.2
K960608	Soil	37	0.93	104	0.070	2	1.39	0.027	0.09	2.7	0.03	3.8	<0.1	<0.05	5	<0.5	<0.2
K960609	Soil	53	1.10	121	0.056	1	1.67	0.013	0.07	2.1	0.01	4.2	<0.1	<0.05	4	<0.5	<0.2
K960610	Soil	39	0.77	81	0.055	1	1.36	0.017	0.07	2.3	0.03	3.0	<0.1	<0.05	5	<0.5	<0.2
K960611	Soil	30	0.66	84	0.059	<1	0.93	0.041	0.06	1.6	<0.01	3.3	<0.1	<0.05	4	<0.5	<0.2
K960612	Soil	31	0.77	50	0.044	1	1.18	0.016	0.06	2.2	0.01	3.1	<0.1	<0.05	4	<0.5	<0.2
K960613	Soil	29	0.66	80	0.060	<1	1.10	0.041	0.09	2.4	0.04	3.2	<0.1	<0.05	4	<0.5	<0.2
K960614	Soil	30	0.84	96	0.068	<1	1.50	0.027	0.08	2.3	0.01	4.3	<0.1	<0.05	5	<0.5	<0.2
K960615	Soil	37	1.03	51	0.056	<1	1.15	0.027	0.05	2.3	0.02	2.7	<0.1	<0.05	5	<0.5	<0.2
K960616	Soil	39	0.92	141	0.039	2	1.34	0.019	0.06	2.6	0.01	3.5	<0.1	<0.05	5	<0.5	<0.2
K960617	Soil	38	0.89	89	0.052	1	1.25	0.020	0.06	2.2	0.01	3.9	<0.1	<0.05	4	<0.5	<0.2
K960618	Soil	32	1.27	41	0.043	1	1.62	0.023	0.04	1.4	<0.01	6.9	<0.1	<0.05	7	<0.5	<0.2
K960619	Soil	26	0.58	67	0.097	<1	0.76	0.051	0.06	2.1	<0.01	2.6	<0.1	<0.05	4	<0.5	<0.2
K960620	Soil	22	0.47	56	0.087	1	0.67	0.080	0.10	2.5	<0.01	2.6	<0.1	<0.05	3	<0.5	<0.2
K960621	Soil	58	1.17	44	0.070	<1	1.64	0.021	0.05	2.2	0.01	3.1	<0.1	<0.05	5	<0.5	<0.2
K960622	Soil	27	0.65	67	0.064	<1	1.03	0.029	0.05	3.1	0.01	1.7	<0.1	<0.05	4	<0.5	<0.2
K960623	Soil	30	0.76	50	0.121	<1	1.28	0.024	0.05	1.9	<0.01	4.9	<0.1	<0.05	7	<0.5	<0.2
K960624	Soil	22	0.58	61	0.073	<1	0.75	0.054	0.06	2.1	<0.01	2.3	<0.1	<0.05	4	<0.5	<0.2
K960625	Soil	25	0.70	58	0.071	<1	1.33	0.026	0.06	2.2	0.04	3.7	<0.1	<0.05	6	<0.5	<0.2
K960651	Soil	27	0.73	79	0.080	<1	1.20	0.011	0.27	4.3	<0.01	2.0	<0.1	<0.05	4	0.5	<0.2
K960652	Soil	47	0.87	83	0.065	<1	1.23	0.012	0.13	4.7	0.02	2.7	<0.1	<0.05	4	<0.5	<0.2
K960653	Soil	45	0.68	72	0.064	<1	1.12	0.010	0.15	4.4	0.02	2.3	<0.1	<0.05	4	<0.5	<0.2
K960654	Soil	29	0.79	195	0.076	<1	1.25	0.019	0.32	3.5	<0.01	3.1	0.1	<0.05	4	<0.5	<0.2
K960655	Soil	25	0.47	74	0.049	<1	0.80	0.010	0.15	11.6	<0.01	1.7	<0.1	<0.05	2	<0.5	<0.2
K960656	Soil	24	0.67	126	0.066	<1	1.08	0.013	0.26	6.8	<0.01	2.1	<0.1	<0.05	3	<0.5	<0.2
K960657	Soil	35	0.72	69	0.047	<1	1.12	0.012	0.13	4.1	0.02	2.5	<0.1	<0.05	3	<0.5	<0.2
K960658	Soil	42	0.86	86	0.077	1	1.31	0.014	0.16	3.3	<0.01	2.4	0.1	<0.05	5	<0.5	<0.2
K960659	Soil	48	0.76	79	0.060	1	1.22	0.015	0.19	4.3	<0.01	2.6	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960660	Soil	0.3	24.1	7.1	41	0.2	25.8	11.5	306	2.07	2.8	0.9	5.1	23	<0.1	0.1	<0.1	32	0.24	0.056	13
K960661	Soil	0.3	25.8	6.0	55	0.2	34.5	13.3	377	2.46	2.6	0.6	5.5	19	<0.1	0.2	<0.1	35	0.26	0.066	14
K960662	Soil	0.3	19.7	6.5	46	0.6	30.9	14.1	339	2.18	2.0	0.7	3.9	32	<0.1	0.2	<0.1	39	0.43	0.086	8
K960663	Soil	0.4	18.4	10.5	53	0.2	26.1	10.8	408	2.26	3.1	0.7	5.1	15	0.1	0.3	0.1	37	0.27	0.080	13
K960664	Soil	0.6	15.8	5.7	49	0.3	50.1	10.9	304	2.20	2.1	1.7	3.2	15	<0.1	0.4	<0.1	37	0.23	0.046	10
K960665	Soil	0.5	22.5	6.2	42	0.1	22.1	9.7	266	1.75	2.5	0.6	6.9	12	0.1	0.3	0.3	28	0.21	0.066	15
K960666	Soil	0.5	17.0	4.5	73	0.2	22.5	11.6	524	2.45	1.9	<0.5	4.3	15	0.1	0.2	<0.1	46	0.28	0.066	13
K960667	Soil	0.9	20.2	6.6	54	0.3	25.4	9.9	327	1.89	3.2	1.3	4.1	25	<0.1	0.3	<0.1	32	0.32	0.081	12
K960668	Soil	0.9	24.7	9.1	58	0.4	36.9	12.3	345	2.03	5.6	<0.5	5.1	13	0.4	0.6	0.1	38	0.25	0.080	15
K960669	Soil	0.7	24.8	5.7	58	0.3	28.6	11.2	418	2.35	2.3	<0.5	4.6	12	0.1	0.2	<0.1	45	0.26	0.075	13
K960670	Soil	0.7	62.1	4.9	73	0.3	33.0	16.2	606	3.34	5.2	<0.5	1.8	22	<0.1	0.3	<0.1	64	0.39	0.061	7
K960671	Soil	0.7	36.4	6.2	71	0.4	35.8	11.0	380	2.04	21.9	0.5	5.6	12	0.2	0.4	0.1	42	0.29	0.088	20
K960672	Soil	1.7	30.0	7.0	69	0.2	30.1	10.2	379	1.92	5.2	1.3	3.4	17	0.4	0.8	0.2	39	0.26	0.089	14
K960673	Soil	0.6	24.9	5.6	79	0.1	12.9	6.7	317	1.70	5.2	1.1	5.1	16	0.2	0.4	0.1	18	0.20	0.052	9
K960674	Soil	2.3	31.9	7.9	78	0.3	34.5	11.9	412	2.35	6.8	2.0	4.6	16	0.4	1.1	0.2	50	0.31	0.123	18
K960675	Soil	1.9	30.4	7.5	76	0.4	36.7	10.2	350	1.91	4.8	1.2	5.2	15	0.5	0.7	0.2	39	0.30	0.096	19
K960676	Soil	1.2	25.2	6.1	55	0.3	29.9	9.1	285	1.64	2.7	<0.5	4.6	14	0.3	0.4	0.2	34	0.31	0.101	13
K960677	Soil	1.0	20.4	5.8	54	0.3	26.6	8.2	248	1.68	2.4	1.7	3.4	11	0.3	0.4	0.2	35	0.27	0.095	12
K960678	Soil	0.8	13.1	5.8	47	0.3	17.2	6.3	211	1.40	2.6	2.3	5.7	10	0.3	0.3	0.1	30	0.19	0.059	13
K960679	Soil	1.0	24.3	6.7	58	0.3	33.0	9.8	322	1.86	2.8	1.2	4.3	13	0.2	0.4	0.4	39	0.28	0.101	15
K960680	Soil	0.7	27.0	7.3	50	0.3	23.6	9.1	289	1.90	2.5	1.0	1.6	10	0.2	0.3	0.1	42	0.22	0.067	11
K960681	Soil	1.0	20.5	8.0	50	0.5	19.4	8.5	346	1.92	3.3	0.9	2.4	11	0.1	0.4	0.2	43	0.20	0.071	13
K960682	Soil	0.4	24.2	3.8	58	0.1	19.6	7.9	323	2.07	3.5	<0.5	8.3	13	0.1	0.3	<0.1	28	0.18	0.072	15
K960683	Soil	1.1	23.7	7.5	63	0.3	24.1	8.5	337	1.83	2.9	0.8	4.9	13	0.2	0.5	0.2	35	0.27	0.102	14
K960684	Soil	1.1	24.4	7.1	68	0.2	19.9	9.0	397	1.98	2.5	<0.5	4.1	19	0.2	0.5	0.2	40	0.33	0.123	12
K960685	Soil	1.5	35.6	8.8	71	0.6	24.4	8.6	290	2.04	3.8	1.0	4.3	13	0.4	0.5	0.2	46	0.27	0.096	17
K960686	Soil	0.8	29.2	6.6	63	0.3	25.8	12.9	388	2.68	2.0	0.5	4.7	16	0.2	0.3	0.1	61	0.37	0.105	12
K960687	Soil	0.3	33.4	11.8	59	<0.1	23.5	9.2	420	2.16	4.5	<0.5	9.9	16	0.2	0.1	0.1	24	0.24	0.090	15
K960688	Soil	0.9	32.4	7.9	70	0.3	29.0	10.7	408	2.17	2.3	<0.5	5.6	18	0.2	0.3	0.2	43	0.26	0.087	17
K960689	Soil	0.7	28.0	6.6	65	0.2	25.1	10.7	464	1.98	2.1	<0.5	3.3	22	0.3	0.3	0.1	40	0.26	0.088	13

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960660	Soil	41	0.74	51	0.061	<1	1.22	0.011	0.15	3.7	0.02	2.0	0.1	<0.05	4	<0.5	<0.2
K960661	Soil	51	0.94	83	0.072	<1	1.43	0.012	0.21	3.9	0.01	2.4	0.1	<0.05	4	<0.5	<0.2
K960662	Soil	37	1.03	98	0.080	<1	1.40	0.026	0.20	4.2	<0.01	2.4	<0.1	<0.05	4	<0.5	<0.2
K960663	Soil	39	0.80	104	0.076	<1	1.14	0.011	0.24	3.9	<0.01	3.1	0.2	<0.05	4	<0.5	<0.2
K960664	Soil	90	1.27	85	0.069	<1	1.04	0.011	0.15	2.8	0.01	2.5	<0.1	<0.05	4	<0.5	<0.2
K960665	Soil	30	0.64	62	0.075	<1	1.00	0.012	0.24	4.5	<0.01	2.4	0.2	<0.05	3	<0.5	<0.2
K960666	Soil	29	1.07	111	0.087	<1	1.29	0.017	0.19	3.3	<0.01	3.3	0.1	<0.05	5	<0.5	<0.2
K960667	Soil	35	0.65	121	0.067	1	1.04	0.011	0.22	5.8	0.02	2.0	0.1	<0.05	3	<0.5	<0.2
K960668	Soil	38	0.68	89	0.065	<1	1.24	0.011	0.13	5.4	0.01	2.7	0.1	<0.05	3	<0.5	<0.2
K960669	Soil	34	0.95	151	0.084	<1	1.26	0.011	0.25	3.4	0.02	2.9	0.2	<0.05	4	<0.5	<0.2
K960670	Soil	42	1.29	125	0.073	<1	1.66	0.024	0.11	3.1	0.02	4.3	<0.1	<0.05	5	<0.5	<0.2
K960671	Soil	37	0.81	134	0.071	<1	1.05	0.013	0.16	5.0	0.02	2.7	0.2	<0.05	3	<0.5	<0.2
K960672	Soil	30	0.64	122	0.063	<1	0.97	0.010	0.11	3.6	0.01	2.5	<0.1	<0.05	3	<0.5	<0.2
K960673	Soil	12	0.52	202	0.050	<1	0.83	0.010	0.20	3.7	0.01	1.9	0.1	<0.05	3	<0.5	<0.2
K960674	Soil	34	0.72	127	0.070	1	1.07	0.012	0.15	4.1	0.02	3.6	0.1	<0.05	3	0.5	<0.2
K960675	Soil	35	0.63	127	0.070	1	1.03	0.012	0.11	3.9	0.02	3.0	0.1	<0.05	3	<0.5	<0.2
K960676	Soil	38	0.63	81	0.074	<1	0.91	0.014	0.15	3.7	0.02	2.3	0.1	<0.05	3	<0.5	<0.2
K960677	Soil	33	0.56	61	0.065	<1	0.85	0.010	0.10	5.3	0.02	2.0	0.1	<0.05	3	0.6	<0.2
K960678	Soil	23	0.44	58	0.068	<1	0.79	0.016	0.12	5.3	0.02	1.8	<0.1	<0.05	3	<0.5	<0.2
K960679	Soil	37	0.67	107	0.065	<1	0.95	0.010	0.09	4.2	0.02	2.3	0.1	<0.05	3	0.5	<0.2
K960680	Soil	36	0.64	80	0.073	<1	1.01	0.013	0.09	4.6	0.02	2.2	<0.1	<0.05	4	<0.5	<0.2
K960681	Soil	32	0.56	83	0.068	<1	1.08	0.009	0.11	4.3	0.02	2.3	<0.1	<0.05	4	<0.5	<0.2
K960682	Soil	21	0.58	132	0.076	<1	1.07	0.013	0.33	2.4	<0.01	2.2	0.1	<0.05	3	<0.5	<0.2
K960683	Soil	29	0.59	94	0.070	<1	0.93	0.013	0.15	5.2	0.02	2.3	0.1	<0.05	3	<0.5	<0.2
K960684	Soil	27	0.70	110	0.078	<1	1.08	0.012	0.15	4.3	0.02	2.4	0.1	<0.05	3	<0.5	<0.2
K960685	Soil	32	0.69	114	0.075	<1	1.10	0.009	0.14	4.9	0.02	3.0	0.1	<0.05	4	<0.5	<0.2
K960686	Soil	37	1.05	124	0.088	<1	1.29	0.011	0.10	3.5	<0.01	3.9	0.1	<0.05	4	<0.5	<0.2
K960687	Soil	21	0.77	75	0.070	<1	1.13	0.013	0.22	2.6	0.01	2.5	0.1	<0.05	3	<0.5	<0.2
K960688	Soil	36	0.80	128	0.083	<1	1.20	0.011	0.15	3.9	0.01	3.0	0.1	<0.05	4	<0.5	<0.2
K960689	Soil	34	0.74	97	0.084	<1	1.09	0.011	0.22	4.2	0.02	2.4	0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960690	Soil	0.4	43.7	6.0	69	0.1	20.3	12.4	516	2.15	1.9	0.7	10.1	19	0.3	0.2	<0.1	47	0.30	0.082	15
K960691	Soil	0.7	33.6	6.2	44	0.2	21.4	12.8	506	2.46	8.5	<0.5	1.4	18	0.1	0.9	<0.1	57	0.31	0.076	6
K960692	Soil	0.6	39.2	6.4	45	0.2	27.9	13.7	493	2.14	5.9	3.2	2.3	22	0.2	1.8	0.1	47	0.29	0.074	6
K960693	Soil	0.5	27.5	6.8	32	0.2	23.1	10.3	308	1.37	3.5	1.0	3.4	44	<0.1	0.5	0.2	28	0.18	0.054	12
K960694	Soil	0.8	51.0	6.2	45	0.2	31.6	16.0	446	2.38	8.6	1.7	2.6	18	0.1	1.4	0.1	51	0.30	0.067	9
K960695	Soil	0.3	30.7	2.5	27	<0.1	47.7	14.3	259	1.62	1.7	<0.5	1.3	8	<0.1	0.2	<0.1	43	0.23	0.041	4
K960696	Soil	0.7	42.5	6.5	50	0.2	24.0	13.7	399	2.21	4.7	2.6	2.3	22	0.1	0.5	<0.1	52	0.27	0.077	9
K960697	Soil	0.8	61.6	6.6	50	0.1	35.7	15.8	447	2.23	18.4	<0.5	2.3	52	0.2	0.5	0.2	49	0.32	0.087	7
K960698	Soil	0.7	39.5	6.1	55	0.2	27.3	12.1	393	2.05	8.4	2.0	3.5	17	0.1	0.6	0.1	42	0.22	0.064	13
K960699	Soil	0.5	29.7	4.8	45	<0.1	21.4	11.2	379	1.93	4.1	<0.5	3.6	12	0.2	0.4	<0.1	33	0.19	0.050	12
K960700	Soil	1.0	42.3	6.7	44	0.1	40.4	14.9	477	2.30	6.1	0.8	3.1	17	<0.1	0.6	<0.1	48	0.23	0.052	10
K960701	Soil	0.6	20.5	3.5	38	0.1	216.6	22.9	309	2.48	2.7	7.5	3.5	9	0.2	0.2	0.2	54	0.27	0.061	7
K960702	Soil	0.4	23.1	1.5	32	0.1	260.4	25.1	365	2.44	1.3	<0.5	1.2	8	0.1	0.1	<0.1	70	0.60	0.061	3
K960703	Soil	0.4	31.1	12.9	54	0.2	47.4	16.9	499	2.93	12.8	13.9	5.0	11	<0.1	0.8	0.2	41	0.12	0.070	25
K960704	Soil	0.3	17.8	10.2	42	0.1	34.7	13.3	765	2.45	9.6	5.2	5.4	9	<0.1	0.6	0.1	23	0.10	0.038	21
K960705	Soil	0.3	9.7	5.2	19	<0.1	13.9	6.6	407	1.20	3.4	1.0	5.8	6	<0.1	0.3	<0.1	12	0.04	0.019	18
K960706	Soil	0.3	19.6	13.4	40	<0.1	26.5	11.6	359	2.16	8.0	1.9	5.1	8	<0.1	0.8	0.3	23	0.08	0.035	23
K960707	Soil	0.3	20.7	13.9	47	<0.1	28.1	12.0	367	2.41	8.7	1.8	4.7	9	<0.1	0.7	0.3	25	0.08	0.041	27
K960708	Soil	0.3	40.8	17.4	75	<0.1	52.9	20.6	717	4.18	11.6	3.8	13.2	10	<0.1	0.7	0.4	26	0.09	0.053	46
K960709	Soil	0.6	25.1	15.5	40	0.2	36.9	13.5	488	2.31	11.0	7.4	6.7	10	<0.1	0.9	0.2	26	0.14	0.060	25
K960710	Soil	0.4	28.8	18.1	46	0.3	28.9	12.4	565	2.14	12.4	4.2	6.9	7	<0.1	0.6	0.3	22	0.09	0.037	28
K960711	Soil	0.6	20.8	9.3	43	0.1	39.5	13.8	1401	3.73	5.3	6.1	4.4	26	<0.1	0.4	0.1	40	1.64	0.085	33
K960712	Soil	0.2	31.8	9.0	43	0.1	36.1	15.5	589	2.72	9.8	3.1	6.6	31	<0.1	0.7	0.1	53	0.42	0.048	22
K960713	Soil	0.4	21.6	12.5	31	0.1	23.2	11.1	415	2.08	18.2	4.9	6.3	5	<0.1	0.9	0.3	21	0.05	0.023	22
K960714	Soil	0.3	20.7	29.9	40	0.2	26.9	14.0	503	2.15	12.0	4.1	6.5	8	<0.1	1.0	0.5	20	0.12	0.047	21
K960715	Soil	0.5	23.3	16.2	51	0.1	35.1	15.0	404	2.88	9.2	3.0	6.9	9	<0.1	1.1	0.3	25	0.09	0.042	35
K960716	Soil	0.3	31.3	13.1	59	0.1	39.0	19.3	790	3.14	7.1	3.5	6.8	11	<0.1	0.6	0.4	35	0.13	0.053	28
K960717	Soil	0.6	19.2	13.3	43	0.1	46.5	14.3	477	2.53	12.8	3.6	6.3	8	<0.1	0.7	0.2	30	0.10	0.031	26
K960718	Soil	0.4	18.7	11.4	38	0.1	46.4	12.9	321	2.25	9.8	2.6	4.8	10	0.1	0.9	0.2	30	0.12	0.042	19
K960719	Soil	0.3	13.6	9.4	23	<0.1	34.4	10.3	455	1.51	4.4	1.9	5.4	5	<0.1	0.3	0.1	16	0.06	0.023	22

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960690	Soil	32	0.95	122	0.095	<1	1.17	0.016	0.22	3.3	<0.01	3.1	0.2	<0.05	4	<0.5	<0.2
K960691	Soil	53	1.08	69	0.050	1	1.31	0.014	0.07	2.6	0.03	3.5	<0.1	<0.05	4	<0.5	<0.2
K960692	Soil	53	0.91	88	0.060	<1	1.13	0.016	0.09	2.4	0.03	3.2	<0.1	<0.05	3	<0.5	<0.2
K960693	Soil	43	0.51	889	0.048	<1	0.77	0.014	0.12	6.3	0.02	2.3	<0.1	<0.05	3	<0.5	<0.2
K960694	Soil	69	0.94	81	0.050	<1	1.17	0.013	0.06	2.9	0.02	4.1	<0.1	<0.05	4	<0.5	<0.2
K960695	Soil	183	0.84	29	0.055	<1	0.81	0.013	0.09	1.0	0.02	2.4	<0.1	<0.05	3	<0.5	<0.2
K960696	Soil	53	0.94	76	0.052	<1	1.16	0.012	0.09	3.3	0.02	3.7	<0.1	<0.05	4	<0.5	<0.2
K960697	Soil	49	0.95	678	0.055	<1	1.18	0.017	0.09	2.9	0.03	3.3	<0.1	<0.05	3	<0.5	<0.2
K960698	Soil	45	0.71	66	0.054	<1	1.00	0.012	0.09	3.7	0.02	3.1	<0.1	<0.05	3	<0.5	<0.2
K960699	Soil	33	0.67	64	0.061	<1	0.96	0.011	0.15	3.3	<0.01	2.8	<0.1	<0.05	3	<0.5	<0.2
K960700	Soil	72	0.98	70	0.056	<1	1.12	0.013	0.09	2.4	<0.01	3.7	<0.1	<0.05	4	<0.5	<0.2
K960701	Soil	174	2.07	44	0.111	2	1.14	0.019	0.18	2.5	<0.01	3.7	0.1	<0.05	4	<0.5	<0.2
K960702	Soil	202	2.34	25	0.152	5	1.21	0.070	0.07	0.8	<0.01	5.9	<0.1	<0.05	3	<0.5	<0.2
K960703	Soil	54	0.91	44	0.016	<1	1.48	0.004	0.07	5.1	0.02	3.0	<0.1	<0.05	5	<0.5	<0.2
K960704	Soil	31	0.63	55	0.017	<1	1.16	0.006	0.08	5.4	<0.01	2.0	<0.1	<0.05	3	<0.5	<0.2
K960705	Soil	17	0.32	37	0.009	<1	0.61	0.010	0.07	5.7	<0.01	1.1	<0.1	<0.05	2	<0.5	<0.2
K960706	Soil	28	0.57	61	0.019	<1	1.12	0.007	0.08	4.7	0.01	1.7	<0.1	<0.05	3	<0.5	<0.2
K960707	Soil	32	0.66	59	0.015	<1	1.12	0.005	0.08	4.4	<0.01	2.0	<0.1	<0.05	4	<0.5	<0.2
K960708	Soil	48	0.95	48	0.009	<1	1.79	0.007	0.08	2.3	<0.01	3.0	<0.1	<0.05	6	<0.5	<0.2
K960709	Soil	30	0.59	46	0.017	<1	1.19	0.005	0.08	4.8	0.02	1.8	<0.1	<0.05	4	<0.5	<0.2
K960710	Soil	28	0.53	42	0.027	<1	1.05	0.005	0.08	4.8	0.01	1.7	<0.1	<0.05	3	<0.5	<0.2
K960711	Soil	36	0.82	111	0.032	<1	1.37	0.014	0.06	2.9	0.01	3.1	<0.1	<0.05	5	<0.5	<0.2
K960712	Soil	38	0.97	48	0.021	<1	1.42	0.009	0.09	5.3	0.02	5.8	<0.1	<0.05	4	<0.5	<0.2
K960713	Soil	26	0.43	37	0.021	<1	0.89	0.004	0.09	7.3	<0.01	1.6	<0.1	<0.05	3	<0.5	<0.2
K960714	Soil	23	0.60	52	0.034	<1	1.06	0.007	0.11	5.9	0.01	1.5	<0.1	<0.05	3	<0.5	<0.2
K960715	Soil	43	0.64	46	0.021	<1	1.36	0.004	0.09	2.8	0.02	2.0	<0.1	<0.05	5	<0.5	<0.2
K960716	Soil	37	0.95	41	0.038	<1	1.57	0.008	0.07	3.7	0.02	2.6	<0.1	<0.05	5	<0.5	<0.2
K960717	Soil	47	0.69	51	0.037	<1	1.23	0.004	0.09	4.9	0.02	2.2	<0.1	<0.05	4	<0.5	<0.2
K960718	Soil	53	0.68	52	0.045	<1	1.16	0.007	0.10	5.7	0.01	1.9	<0.1	<0.05	4	<0.5	<0.2
K960719	Soil	43	0.47	63	0.022	8	0.72	0.005	0.11	8.5	<0.01	1.6	<0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960720	Soil	0.4	13.1	15.6	24	<0.1	19.9	8.7	609	1.45	8.1	16.4	6.1	5	<0.1	0.4	0.2	13	0.05	0.023	21
K960721	Soil	0.4	19.4	13.9	45	0.1	47.5	16.1	484	2.69	15.6	8.0	7.0	13	<0.1	0.9	0.2	37	0.19	0.043	25
K960722	Soil	0.2	23.3	9.6	52	0.3	140.3	27.2	722	3.62	8.7	2.6	7.9	23	<0.1	0.8	0.2	57	0.33	0.071	26
K960723	Soil	0.4	65.5	8.3	72	0.2	29.8	14.4	387	2.82	6.6	1.8	2.8	28	<0.1	0.4	0.2	88	0.39	0.124	18
K960724	Soil	0.3	14.9	10.0	28	<0.1	56.9	12.4	501	1.65	4.4	3.5	4.7	7	<0.1	0.4	0.1	26	0.12	0.034	19
K960725	Soil	0.6	9.7	6.9	47	0.4	27.4	12.2	498	2.76	5.5	1.1	2.6	13	<0.1	0.4	0.2	48	0.21	0.069	14
K960726	Soil	0.5	16.9	10.6	46	0.2	43.7	13.5	658	2.13	9.4	2.2	6.8	10	<0.1	0.9	0.3	27	0.13	0.043	22
K960727	Soil	0.4	27.3	19.1	50	0.1	74.1	20.0	516	2.96	10.6	2.0	5.4	12	<0.1	0.9	0.9	43	0.22	0.054	22
K960728	Soil	0.4	27.6	10.2	40	0.1	26.3	13.0	1360	2.17	16.2	2.3	8.9	12	0.1	0.9	0.2	14	0.07	0.031	29
K960729	Soil	0.5	60.2	7.0	50	<0.1	23.3	10.6	338	2.52	7.6	<0.5	11.1	7	<0.1	1.0	0.1	13	0.07	0.028	37
K960730	Soil	0.5	15.4	11.9	50	0.1	20.0	9.4	416	2.33	11.6	2.9	7.5	11	0.1	0.7	0.3	24	0.09	0.030	24
K960731	Soil	0.3	17.4	11.2	39	0.1	20.4	10.4	541	1.80	9.3	7.7	7.8	11	<0.1	0.7	0.3	15	0.18	0.044	23
K960732	Soil	0.2	45.4	8.6	53	0.2	39.4	15.7	738	2.19	29.5	8.6	9.5	9	<0.1	1.4	0.3	18	0.10	0.034	28
K960733	Soil	0.7	11.4	14.6	39	0.3	18.2	10.5	714	2.18	13.1	3.4	6.4	9	0.1	0.8	0.5	28	0.11	0.039	20
K960734	Soil	0.6	42.1	8.2	46	0.1	35.0	16.3	400	2.89	52.2	7.8	5.8	15	<0.1	2.9	0.2	44	0.24	0.058	19
K960735	Soil	0.4	28.4	37.3	51	0.1	38.8	21.6	989	3.09	33.1	1.8	5.9	271	0.2	1.5	0.5	24	8.19	0.032	21
K960736	Soil	0.3	6.2	7.7	7	<0.1	4.9	3.8	655	0.62	2.3	0.5	6.8	57	<0.1	0.5	<0.1	3	1.21	0.009	15
K960737	Soil	0.5	13.8	10.9	36	0.6	22.2	8.1	304	2.13	13.0	1.5	1.2	10	<0.1	0.6	0.4	30	0.15	0.043	14
K960738	Soil	0.9	9.1	9.9	57	0.2	60.6	14.4	669	3.58	28.7	4.2	4.2	16	<0.1	0.4	0.2	49	0.29	0.067	23
K960739	Soil	0.8	21.8	8.5	43	0.4	46.3	15.4	340	3.23	10.9	8.1	5.3	16	0.1	0.6	0.2	55	0.24	0.080	18
K960740	Soil	0.9	18.2	10.2	41	0.5	41.3	12.9	336	2.72	9.1	3.3	2.5	17	0.1	0.4	0.2	58	0.33	0.084	14
K960741	Soil	0.6	19.4	10.9	46	0.2	26.5	10.2	354	2.44	15.1	14.9	5.0	13	0.1	0.8	0.2	45	0.21	0.065	18
K960742	Soil	1.1	15.8	9.3	32	0.2	17.1	10.2	429	2.27	40.1	9.6	6.0	14	<0.1	7.7	2.9	20	0.08	0.036	21
K960743	Soil	0.6	17.3	11.5	38	0.2	28.5	11.0	323	2.21	42.3	2.5	6.3	10	<0.1	5.7	0.3	21	0.07	0.029	21
K960744	Soil	0.8	16.7	20.1	49	0.1	18.5	11.5	195	2.18	358.8	4.9	7.1	10	0.2	34.4	0.1	8	0.03	0.015	20
K960745	Soil	0.2	67.8	5.3	52	0.2	446.8	42.6	684	4.20	2.7	3.3	1.2	16	0.3	0.2	<0.1	82	0.44	0.081	5
K960746	Soil	<0.1	9.4	1.5	47	<0.1	161.5	27.9	921	4.56	0.8	0.8	0.2	15	<0.1	0.1	<0.1	135	0.61	0.177	4
K960747	Soil	0.2	43.7	2.2	39	0.2	385.3	34.3	612	3.40	1.6	0.8	0.5	23	0.1	0.2	<0.1	75	0.97	0.043	2
K960748	Soil	0.2	20.1	2.9	31	0.1	374.3	28.0	517	2.99	1.4	0.9	0.6	17	0.1	0.2	<0.1	54	0.65	0.072	3
K960749	Soil	0.2	27.1	2.4	51	0.2	312.8	30.8	747	3.28	1.7	0.8	1.0	21	0.1	0.1	<0.1	68	0.41	0.077	4

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960720	Soil	20	0.25	52	0.017	<1	0.62	0.004	0.12	7.1	0.02	1.3	<0.1	<0.05	2	<0.5	<0.2
K960721	Soil	44	0.72	74	0.123	<1	1.13	0.005	0.09	4.8	0.02	2.4	<0.1	<0.05	4	<0.5	<0.2
K960722	Soil	201	1.97	105	0.047	<1	1.96	0.005	0.09	3.3	0.01	5.6	<0.1	<0.05	7	<0.5	<0.2
K960723	Soil	27	0.99	89	0.064	<1	1.49	0.012	0.09	2.6	0.02	3.9	<0.1	<0.05	7	<0.5	<0.2
K960724	Soil	64	0.94	50	0.053	<1	1.02	0.010	0.11	5.8	0.02	1.8	<0.1	<0.05	3	<0.5	<0.2
K960725	Soil	36	0.87	63	0.066	<1	1.46	0.008	0.08	3.5	0.02	2.8	<0.1	<0.05	6	<0.5	<0.2
K960726	Soil	47	0.64	54	0.051	<1	1.09	0.007	0.09	4.2	0.02	2.3	<0.1	<0.05	4	<0.5	<0.2
K960727	Soil	73	1.20	44	0.101	<1	1.54	0.006	0.09	3.6	0.01	2.6	<0.1	<0.05	5	<0.5	<0.2
K960728	Soil	21	0.35	70	0.018	<1	0.87	0.004	0.11	4.4	0.02	1.7	<0.1	<0.05	2	<0.5	<0.2
K960729	Soil	14	0.24	58	0.013	1	0.65	0.005	0.19	3.3	0.05	1.3	0.1	<0.05	2	<0.5	<0.2
K960730	Soil	21	0.48	60	0.047	<1	1.14	0.006	0.17	3.8	0.03	1.7	0.1	<0.05	4	<0.5	<0.2
K960731	Soil	18	0.42	36	0.029	<1	0.81	0.008	0.08	5.9	0.01	1.5	<0.1	<0.05	3	<0.5	<0.2
K960732	Soil	22	0.55	44	0.034	<1	1.04	0.004	0.07	4.1	0.02	1.6	<0.1	<0.05	3	<0.5	<0.2
K960733	Soil	23	0.28	70	0.033	<1	1.11	0.005	0.07	4.6	0.03	1.9	0.1	<0.05	4	<0.5	<0.2
K960734	Soil	40	0.76	107	0.064	<1	1.32	0.008	0.13	3.9	<0.01	2.5	<0.1	<0.05	4	<0.5	<0.2
K960735	Soil	25	1.02	59	0.022	<1	1.39	0.003	0.10	1.2	<0.01	5.3	<0.1	<0.05	3	<0.5	<0.2
K960736	Soil	7	0.08	27	0.007	<1	0.24	0.009	0.05	15.9	<0.01	1.5	<0.1	<0.05	<1	<0.5	<0.2
K960737	Soil	27	0.44	50	0.039	<1	0.89	0.009	0.05	1.7	0.02	1.3	<0.1	<0.05	4	<0.5	<0.2
K960738	Soil	64	1.13	86	0.074	<1	1.90	0.005	0.06	1.6	0.01	2.7	<0.1	<0.05	8	<0.5	<0.2
K960739	Soil	52	0.79	70	0.154	<1	1.50	0.007	0.07	1.4	0.01	2.9	<0.1	<0.05	6	<0.5	<0.2
K960740	Soil	52	0.72	80	0.094	<1	1.51	0.015	0.06	0.8	0.02	2.8	<0.1	<0.05	6	<0.5	<0.2
K960741	Soil	37	0.59	64	0.082	<1	1.45	0.006	0.07	1.2	0.02	2.5	<0.1	<0.05	5	<0.5	<0.2
K960742	Soil	18	0.20	52	0.013	<1	0.72	0.007	0.12	6.0	0.05	1.9	0.1	<0.05	3	<0.5	<0.2
K960743	Soil	26	0.27	54	0.013	<1	0.79	0.008	0.08	7.0	0.06	1.8	<0.1	<0.05	2	<0.5	<0.2
K960744	Soil	9	0.08	58	0.003	2	0.35	0.003	0.16	2.1	0.21	0.9	<0.1	<0.05	1	<0.5	<0.2
K960745	Soil	528	4.47	212	0.054	2	2.03	0.013	0.07	1.0	0.01	9.8	<0.1	<0.05	6	<0.5	<0.2
K960746	Soil	222	5.07	101	0.053	<1	2.68	0.003	<0.01	0.2	<0.01	17.3	<0.1	<0.05	5	<0.5	<0.2
K960747	Soil	560	4.07	126	0.084	2	1.72	0.022	0.07	0.5	<0.01	7.1	<0.1	<0.05	5	<0.5	<0.2
K960748	Soil	409	3.93	159	0.025	3	1.42	0.009	0.07	1.1	0.02	5.0	<0.1	0.08	4	<0.5	<0.2
K960749	Soil	382	3.79	92	0.044	2	1.93	0.012	0.04	0.7	<0.01	5.8	<0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960750	Soil	<0.1	30.3	2.9	42	0.2	527.0	43.7	828	4.06	1.4	<0.5	0.5	15	<0.1	0.1	<0.1	87	0.62	0.074	2
K960801	Soil	1.6	26.2	6.5	69	0.3	28.9	9.7	328	2.34	3.2	1.5	5.5	15	0.2	0.2	0.3	69	0.24	0.051	11
K960802	Soil	1.5	21.8	5.4	68	0.2	30.7	9.1	384	2.08	3.0	1.5	4.0	14	0.3	0.2	0.3	60	0.22	0.051	9
K960803	Soil	0.3	4.2	4.6	40	0.1	4.7	3.6	239	1.31	0.7	<0.5	11.3	10	<0.1	<0.1	0.1	31	0.23	0.087	20
K960804	Soil	1.3	22.3	8.8	61	0.2	28.6	9.3	315	2.12	2.3	1.9	6.7	12	0.2	0.2	0.4	63	0.22	0.054	10
K960805	Soil	<0.1	3.7	6.7	22	0.1	35.2	4.4	144	0.80	0.7	<0.5	11.5	7	<0.1	<0.1	<0.1	18	0.13	0.050	19
K960806	Soil	6.1	38.9	7.4	393	0.4	43.7	10.3	449	2.22	5.4	3.0	2.3	14	4.5	0.3	0.3	87	0.23	0.058	6
K960807	Soil	0.2	7.6	12.9	44	0.2	3.0	3.7	263	1.14	1.4	0.8	19.6	12	0.1	<0.1	0.2	28	0.22	0.082	29
K960808	Soil	<0.1	4.5	5.4	34	0.1	2.1	3.3	276	1.15	<0.5	<0.5	24.8	28	<0.1	<0.1	<0.1	28	0.33	0.074	35
K960809	Soil	0.3	20.5	3.1	38	0.2	15.0	11.1	452	2.08	4.5	1.6	2.3	29	<0.1	0.5	<0.1	51	0.47	0.098	6
K960810	Soil	0.1	3.9	2.6	39	<0.1	9.4	8.1	469	1.84	1.1	<0.5	2.9	26	<0.1	<0.1	<0.1	54	0.45	0.109	5
K960811	Soil	0.1	3.2	3.2	52	<0.1	11.6	10.1	662	2.38	0.7	1.0	1.9	29	<0.1	0.1	<0.1	55	0.37	0.093	4
K960812	Soil	0.1	7.5	4.1	47	0.1	14.7	10.7	578	2.31	1.9	2.3	2.4	63	0.1	0.2	<0.1	56	0.91	0.088	6
K960813	Soil	<0.1	3.3	3.3	32	0.1	7.5	6.4	309	1.73	0.6	0.8	2.8	42	<0.1	<0.1	<0.1	51	0.50	0.075	5
K960814	Soil	0.2	2.7	5.9	37	<0.1	9.9	8.2	525	2.25	1.5	0.9	2.8	29	<0.1	0.2	<0.1	64	0.34	0.083	5
K960815	Soil	0.2	10.4	3.9	46	0.2	15.5	11.0	441	2.60	4.8	1.5	2.0	23	<0.1	0.4	<0.1	65	0.37	0.075	5
K960816	Soil	0.2	14.7	3.9	43	<0.1	15.0	11.2	520	2.54	7.9	6.2	2.5	20	<0.1	0.6	<0.1	62	0.34	0.079	6
K960817	Soil	0.5	35.1	6.6	45	0.3	19.8	13.0	334	3.02	3.1	2.4	4.3	33	<0.1	0.3	<0.1	111	0.63	0.123	15
K960818	Soil	0.4	28.2	4.8	41	0.4	28.3	12.6	387	2.59	4.5	2.9	3.4	32	0.1	0.5	<0.1	85	1.16	0.066	11
K960819	Soil	0.5	30.3	8.1	53	0.4	24.4	14.4	572	2.99	5.1	1.4	5.4	24	<0.1	0.4	<0.1	93	0.62	0.068	12
K960820	Soil	0.5	34.9	4.9	39	0.4	30.7	13.2	295	2.66	5.7	1.2	3.8	40	<0.1	0.5	<0.1	92	1.09	0.082	10
K960821	Soil	0.5	34.7	4.4	40	0.5	26.6	13.3	345	2.65	7.2	1.6	3.6	29	<0.1	0.6	<0.1	86	0.60	0.059	10
K960822	Soil	1.5	22.1	10.6	51	0.3	20.3	12.3	661	2.76	3.6	0.6	4.8	27	0.2	0.4	<0.1	80	0.59	0.089	17
K960823	Soil	1.3	28.3	11.5	57	0.8	24.8	14.5	608	3.39	4.2	0.7	7.6	28	0.2	0.4	<0.1	94	0.84	0.093	19
K960824	Soil	0.5	60.3	5.4	59	0.5	45.2	20.0	581	3.21	8.1	3.3	2.0	47	0.1	0.4	<0.1	110	1.35	0.056	9
K960825	Soil	0.8	35.0	4.7	50	0.3	30.1	15.7	536	2.70	24.2	0.7	2.2	31	0.1	3.2	0.3	85	1.01	0.082	12
K960826	Soil	0.7	43.2	6.1	53	0.5	34.3	16.6	433	2.86	5.5	1.7	5.7	43	0.2	0.5	<0.1	84	0.86	0.069	11
K960827	Soil	1.1	32.5	4.2	64	0.4	23.5	11.2	504	2.17	2.7	0.9	2.3	35	0.4	0.3	<0.1	86	0.66	0.104	15
K960828	Soil	0.7	33.7	6.9	58	0.4	29.9	14.2	578	2.85	5.5	2.2	4.5	29	0.2	0.7	<0.1	89	0.78	0.085	14
K960829	Soil	0.8	36.1	6.5	46	0.4	24.8	13.2	407	2.97	7.6	1.9	6.7	41	0.1	0.6	<0.1	94	0.61	0.092	17

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960750	Soil	506	5.79	134	0.048	2	2.12	0.003	0.05	0.2	0.01	11.9	<0.1	<0.05	7	<0.5	<0.2
K960801	Soil	43	0.69	179	0.080	1	1.62	0.025	0.19	4.4	0.01	4.4	0.3	0.05	5	<0.5	<0.2
K960802	Soil	40	0.70	216	0.081	<1	1.51	0.017	0.20	4.4	<0.01	4.0	0.2	<0.05	4	<0.5	<0.2
K960803	Soil	13	0.35	121	0.067	1	0.68	0.031	0.41	5.1	0.01	2.7	0.5	<0.05	4	<0.5	<0.2
K960804	Soil	39	0.69	140	0.077	<1	1.46	0.025	0.20	4.1	<0.01	3.9	0.3	<0.05	5	<0.5	<0.2
K960805	Soil	42	0.34	91	0.038	<1	0.55	0.022	0.23	5.2	<0.01	1.7	0.3	<0.05	3	<0.5	<0.2
K960806	Soil	44	0.64	181	0.065	1	1.34	0.016	0.12	5.0	0.02	3.6	0.2	0.20	5	2.9	<0.2
K960807	Soil	10	0.35	115	0.080	<1	0.75	0.033	0.42	5.1	<0.01	2.7	0.5	<0.05	4	<0.5	<0.2
K960808	Soil	8	0.34	132	0.079	<1	0.67	0.044	0.44	6.2	<0.01	3.1	0.5	<0.05	4	<0.5	<0.2
K960809	Soil	34	0.83	81	0.053	<1	1.14	0.028	0.06	5.8	<0.01	3.6	<0.1	<0.05	4	<0.5	<0.2
K960810	Soil	25	0.92	38	0.084	1	1.01	0.037	0.05	2.4	<0.01	4.2	<0.1	<0.05	5	<0.5	<0.2
K960811	Soil	31	1.23	93	0.049	1	1.05	0.039	0.05	2.6	0.02	7.4	<0.1	<0.05	5	<0.5	<0.2
K960812	Soil	30	1.06	299	0.044	<1	1.15	0.026	0.07	2.4	<0.01	5.4	<0.1	<0.05	5	<0.5	<0.2
K960813	Soil	26	0.51	53	0.067	2	0.75	0.063	0.08	3.9	0.02	2.4	<0.1	<0.05	4	<0.5	<0.2
K960814	Soil	31	0.75	55	0.066	<1	0.91	0.033	0.05	2.8	0.01	3.0	<0.1	<0.05	5	<0.5	<0.2
K960815	Soil	39	0.92	75	0.055	<1	1.43	0.020	0.05	3.1	0.02	4.5	<0.1	<0.05	6	<0.5	<0.2
K960816	Soil	34	0.85	86	0.043	1	1.51	0.023	0.06	3.2	0.01	4.2	<0.1	<0.05	5	<0.5	<0.2
K960817	Soil	39	1.00	97	0.069	2	1.51	0.072	0.09	2.1	0.01	4.5	<0.1	<0.05	6	<0.5	<0.2
K960818	Soil	62	0.96	103	0.094	5	2.12	0.065	0.09	1.6	0.03	7.0	0.1	<0.05	6	<0.5	<0.2
K960819	Soil	46	0.97	105	0.061	1	1.88	0.063	0.05	1.8	0.02	6.0	<0.1	<0.05	7	<0.5	<0.2
K960820	Soil	53	0.69	119	0.063	8	1.86	0.083	0.10	1.9	0.03	3.7	<0.1	<0.05	6	<0.5	<0.2
K960821	Soil	49	0.78	104	0.072	4	1.80	0.052	0.06	2.2	0.01	5.2	<0.1	<0.05	5	<0.5	<0.2
K960822	Soil	40	0.88	171	0.053	2	1.45	0.049	0.07	1.6	0.03	4.8	<0.1	<0.05	7	<0.5	<0.2
K960823	Soil	49	1.03	101	0.062	2	1.59	0.066	0.07	1.2	0.01	7.4	<0.1	<0.05	7	<0.5	<0.2
K960824	Soil	117	1.46	83	0.139	3	3.03	0.080	0.07	1.2	0.04	8.2	<0.1	<0.05	7	<0.5	<0.2
K960825	Soil	59	0.86	116	0.052	43	1.88	0.042	0.09	2.0	0.03	5.6	<0.1	<0.05	5	<0.5	<0.2
K960826	Soil	51	0.94	126	0.074	2	2.20	0.106	0.10	2.1	0.03	6.2	<0.1	0.13	7	0.6	<0.2
K960827	Soil	35	0.70	102	0.036	2	1.27	0.077	0.21	2.1	0.03	3.4	0.1	<0.05	4	<0.5	<0.2
K960828	Soil	49	0.91	106	0.065	2	1.54	0.029	0.09	1.9	0.03	6.2	<0.1	<0.05	5	<0.5	<0.2
K960829	Soil	46	0.89	87	0.052	2	1.68	0.053	0.05	2.1	0.02	6.6	<0.1	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960830	Soil	0.6	37.7	9.4	53	0.3	34.6	15.6	458	3.28	6.9	2.3	4.5	29	<0.1	0.6	0.2	106	0.63	0.063	14
K960831	Soil	0.5	34.3	3.9	31	<0.1	21.0	10.9	206	2.25	2.1	<0.5	5.5	20	<0.1	0.2	<0.1	84	0.60	0.159	16
K960832	Soil	0.2	64.3	2.8	55	0.2	43.8	22.3	757	4.42	3.0	2.0	0.9	14	0.5	0.8	<0.1	202	2.23	0.031	4
K960833	Soil	0.6	36.7	4.6	50	0.1	37.3	15.7	443	3.15	7.4	2.3	3.3	27	0.2	0.6	<0.1	107	0.55	0.064	11
K960834	Soil	0.5	53.8	5.7	47	0.2	31.7	16.0	394	3.31	5.1	1.6	4.9	26	0.2	0.9	0.1	112	0.69	0.077	12
K960835	Soil	0.5	35.1	5.3	46	0.3	30.5	13.0	409	2.66	13.4	<0.5	3.8	43	<0.1	0.9	0.1	83	0.63	0.064	12
K960836	Soil	0.5	29.8	5.6	44	0.3	30.0	13.0	346	2.89	6.8	1.6	3.8	24	<0.1	0.6	<0.1	99	0.54	0.064	12
K960837	Soil	0.5	28.4	2.7	82	0.8	19.6	21.5	620	5.67	2.7	<0.5	1.3	13	0.2	0.2	<0.1	135	1.07	0.127	7
K960838	Soil	0.4	38.1	5.0	48	0.5	31.2	14.3	402	3.13	6.3	1.1	3.8	27	0.2	0.5	<0.1	98	0.54	0.059	12
K960839	Soil	0.6	46.5	5.3	49	0.3	28.9	17.5	395	2.86	6.0	1.7	4.4	23	<0.1	0.5	<0.1	92	0.58	0.072	13
K960840	Soil	0.5	36.0	4.9	42	0.2	27.7	13.3	542	2.94	5.5	1.1	3.9	21	0.2	0.4	<0.1	99	0.65	0.064	12
K960841	Soil	0.5	35.3	4.3	47	0.4	30.8	17.0	522	3.54	5.6	<0.5	2.3	23	0.1	0.4	<0.1	119	0.66	0.052	9
K960842	Soil	0.4	29.5	4.9	50	0.2	25.2	13.8	517	2.88	6.5	0.7	3.2	17	0.2	0.5	<0.1	90	0.47	0.054	11
K960843	Soil	0.6	30.0	4.8	54	0.2	24.4	16.1	652	3.49	6.6	1.3	2.6	16	<0.1	0.5	<0.1	118	0.63	0.051	10
K960844	Soil	0.5	30.9	5.7	44	0.7	24.8	14.3	446	3.28	5.5	<0.5	2.9	15	0.1	0.5	<0.1	147	0.47	0.051	7
K960845	Soil	0.9	23.5	6.3	36	0.1	20.7	10.5	294	2.42	3.2	<0.5	10.0	18	<0.1	0.3	<0.1	79	0.38	0.063	17
K960846	Soil	0.5	23.2	5.4	37	0.2	21.3	11.5	342	2.71	5.3	11.2	4.2	16	<0.1	0.5	<0.1	96	0.48	0.072	15
K960847	Soil	0.6	31.3	5.4	44	0.2	25.1	14.3	443	3.05	5.5	1.2	4.4	18	<0.1	0.5	<0.1	103	0.53	0.064	13
K960848	Soil	0.5	28.0	5.7	46	0.1	22.7	13.3	448	2.88	6.2	1.8	3.9	18	0.1	0.5	<0.1	96	0.53	0.062	11
K960849	Soil	0.5	35.1	4.1	41	0.1	20.2	13.8	459	3.62	4.7	2.9	3.9	17	<0.1	0.4	<0.1	93	0.47	0.064	12
K960850	Soil	0.6	31.4	6.4	49	0.1	24.9	15.0	527	3.16	7.4	2.7	4.9	22	<0.1	0.7	<0.1	105	0.60	0.068	15
K960851	Soil	0.5	7.7	5.9	34	0.4	9.3	4.9	200	1.40	2.5	0.5	3.4	8	<0.1	0.3	0.2	31	0.12	0.040	9
K960852	Soil	1.5	29.4	9.6	66	0.3	24.5	8.6	424	1.80	4.4	<0.5	7.1	12	0.2	0.8	0.3	30	0.27	0.099	18
K960853	Soil	1.0	19.5	7.3	56	0.1	23.7	10.2	481	2.18	3.7	<0.5	4.0	9	0.1	0.5	0.3	33	0.16	0.050	14
K960854	Soil	1.5	21.8	8.9	54	0.3	27.2	9.6	406	2.13	5.4	1.2	5.0	12	0.1	0.8	0.4	36	0.18	0.052	18
K960855	Soil	1.2	16.1	9.2	45	0.2	19.6	7.7	281	2.18	6.4	4.4	1.9	11	0.1	0.5	0.5	44	0.19	0.064	15
K960856	Soil	0.6	14.7	5.2	50	0.1	17.2	8.6	336	2.03	2.1	<0.5	3.6	24	0.1	0.2	0.5	48	0.31	0.069	13
K960857	Soil	1.6	19.0	11.3	50	0.2	19.4	9.3	412	2.03	4.2	<0.5	4.6	9	<0.1	0.4	0.3	30	0.15	0.047	15
K960858	Soil	3.4	19.9	9.9	41	0.2	14.6	7.2	359	1.61	2.8	<0.5	5.6	8	<0.1	0.4	0.6	32	0.11	0.032	18
K960859	Soil	0.4	19.3	8.2	52	0.3	4.6	3.2	298	0.91	1.9	0.7	7.8	5	0.3	0.8	0.8	10	0.12	0.036	18

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960830	Soil	81	1.04	97	0.083	2	1.92	0.031	0.05	1.6	0.03	8.0	<0.1	<0.05	7	<0.5	<0.2
K960831	Soil	37	0.80	63	0.049	1	0.98	0.049	0.16	0.8	<0.01	2.4	0.1	<0.05	4	<0.5	<0.2
K960832	Soil	103	2.22	44	0.198	11	3.77	0.013	0.02	0.4	0.02	21.3	<0.1	<0.05	10	<0.5	<0.2
K960833	Soil	87	1.02	84	0.085	2	1.63	0.035	0.04	1.3	0.01	7.5	<0.1	<0.05	6	<0.5	<0.2
K960834	Soil	55	0.96	87	0.107	2	1.61	0.076	0.06	1.5	0.04	5.8	<0.1	<0.05	6	<0.5	<0.2
K960835	Soil	58	0.73	186	0.057	4	1.89	0.062	0.09	1.3	0.02	6.0	0.1	<0.05	5	<0.5	<0.2
K960836	Soil	73	0.97	87	0.083	3	1.63	0.040	0.05	1.5	0.02	6.4	<0.1	<0.05	5	<0.5	<0.2
K960837	Soil	22	1.18	38	0.287	2	1.50	0.049	0.02	1.5	<0.01	7.9	<0.1	0.12	8	<0.5	<0.2
K960838	Soil	63	1.08	105	0.096	2	1.75	0.042	0.05	1.5	0.03	7.2	<0.1	<0.05	6	<0.5	<0.2
K960839	Soil	49	0.84	107	0.097	1	1.48	0.043	0.05	1.7	0.03	6.6	<0.1	0.14	5	<0.5	<0.2
K960840	Soil	60	0.93	77	0.100	2	1.52	0.052	0.05	1.4	0.01	7.2	<0.1	<0.05	5	<0.5	<0.2
K960841	Soil	57	1.11	92	0.164	2	1.71	0.068	0.04	2.2	0.02	7.2	<0.1	<0.05	7	<0.5	<0.2
K960842	Soil	46	0.86	76	0.133	1	1.49	0.032	0.04	1.5	0.01	6.6	<0.1	<0.05	5	<0.5	<0.2
K960843	Soil	48	0.98	92	0.215	1	1.83	0.027	0.04	1.1	0.02	8.3	<0.1	<0.05	7	<0.5	<0.2
K960844	Soil	55	0.88	75	0.151	2	1.57	0.050	0.05	1.5	0.02	6.0	<0.1	<0.05	6	<0.5	<0.2
K960845	Soil	41	0.72	76	0.112	<1	1.09	0.048	0.14	2.5	0.02	4.1	0.1	<0.05	5	<0.5	<0.2
K960846	Soil	48	0.65	73	0.096	1	1.20	0.028	0.04	1.7	0.01	5.3	<0.1	<0.05	4	<0.5	<0.2
K960847	Soil	51	0.81	90	0.101	<1	1.30	0.038	0.05	1.4	0.02	6.3	<0.1	<0.05	5	<0.5	<0.2
K960848	Soil	47	0.83	96	0.129	1	1.38	0.029	0.06	1.5	0.01	6.1	<0.1	<0.05	5	<0.5	<0.2
K960849	Soil	44	0.78	70	0.082	<1	1.20	0.038	0.05	1.4	0.01	5.4	<0.1	<0.05	5	<0.5	<0.2
K960850	Soil	53	0.84	94	0.131	1	1.49	0.035	0.04	1.4	<0.01	7.4	<0.1	<0.05	6	<0.5	<0.2
K960851	Soil	17	0.37	45	0.052	<1	1.03	0.011	0.15	5.9	0.03	1.9	0.2	<0.05	5	<0.5	<0.2
K960852	Soil	20	0.44	110	0.042	<1	0.85	0.015	0.14	5.2	0.04	2.4	0.2	<0.05	3	<0.5	<0.2
K960853	Soil	23	0.62	70	0.027	<1	1.07	0.009	0.09	5.0	<0.01	2.4	0.1	<0.05	3	<0.5	<0.2
K960854	Soil	28	0.55	93	0.045	<1	1.12	0.010	0.09	5.2	0.02	2.6	0.1	<0.05	4	<0.5	<0.2
K960855	Soil	32	0.52	70	0.044	<1	1.44	0.008	0.08	2.3	0.02	2.1	0.1	<0.05	5	<0.5	<0.2
K960856	Soil	31	0.71	92	0.077	<1	1.23	0.043	0.12	4.0	0.01	3.5	0.1	<0.05	4	<0.5	<0.2
K960857	Soil	22	0.51	56	0.048	<1	1.08	0.011	0.13	8.7	0.01	2.0	0.2	<0.05	4	<0.5	<0.2
K960858	Soil	20	0.52	62	0.040	<1	0.96	0.011	0.12	10.2	0.01	2.3	0.2	<0.05	3	<0.5	<0.2
K960859	Soil	8	0.13	51	0.008	<1	0.48	0.019	0.11	4.0	0.01	0.7	0.1	<0.05	2	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960860	Soil	1.0	19.0	6.3	48	0.1	20.2	9.6	354	2.24	3.6	0.8	4.3	10	0.1	0.4	0.6	43	0.18	0.047	10
K960861	Soil	0.7	14.2	5.6	44	0.3	17.0	9.1	354	1.83	2.4	<0.5	3.1	10	0.1	0.3	0.3	38	0.17	0.049	10
K960862	Soil	1.0	16.7	7.2	47	0.2	19.2	8.3	368	2.15	4.3	<0.5	5.0	11	0.2	0.4	0.3	45	0.20	0.049	13
K960863	Soil	0.8	18.5	6.4	54	0.2	21.8	9.6	377	2.16	3.1	<0.5	4.7	21	0.3	0.3	0.2	54	0.27	0.076	15
K960864	Soil	0.5	14.7	4.5	56	<0.1	14.3	7.3	428	1.66	2.1	<0.5	5.2	9	0.1	0.2	0.3	30	0.18	0.056	13
K960865	Soil	0.6	28.6	4.7	48	0.4	19.2	8.7	300	1.50	1.0	<0.5	5.9	15	0.2	0.2	3.1	25	0.37	0.061	16
K960866	Soil	3.0	16.1	5.8	47	0.2	23.7	10.3	478	2.08	2.0	1.1	5.3	20	0.3	0.2	3.4	36	0.82	0.052	14
K960867	Soil	2.2	12.1	4.3	48	<0.1	17.7	8.6	385	2.04	1.1	0.6	11.5	20	<0.1	0.1	0.4	36	0.44	0.072	28
K960868	Soil	5.2	30.8	6.8	70	0.1	36.7	13.3	519	3.03	1.8	<0.5	7.1	28	0.2	0.2	0.9	57	0.54	0.071	16
K960869	Soil	1.7	26.6	6.7	54	<0.1	26.0	13.2	471	2.82	1.9	<0.5	9.2	9	<0.1	0.2	1.0	29	0.11	0.044	22
K960870	Soil	0.7	10.5	5.5	42	0.2	27.5	9.7	465	1.65	1.4	0.7	7.0	8	0.1	0.1	0.5	29	0.10	0.036	15
K960871	Soil	1.3	31.2	7.6	56	0.2	29.0	12.4	445	2.77	3.1	2.5	7.5	15	<0.1	0.3	1.4	38	0.15	0.051	23
K960872	Soil	3.2	30.1	5.8	51	0.2	26.4	8.7	197	3.60	1.8	<0.5	8.4	4	<0.1	0.2	0.4	19	0.04	0.033	25
K960873	Soil	1.1	27.5	7.5	56	0.2	30.8	12.9	533	2.60	3.0	1.1	4.6	17	0.2	0.2	0.4	58	0.25	0.053	11
K960874	Soil	0.9	25.4	6.8	56	0.2	41.0	13.6	527	2.63	3.7	1.0	4.6	29	0.2	0.3	0.7	44	0.38	0.094	14
K960875	Soil	0.3	8.0	4.4	44	0.2	6.9	4.9	314	1.29	1.2	0.9	2.2	14	0.1	0.2	0.4	29	0.13	0.049	10
K960876	Soil	0.3	7.4	3.2	35	0.1	4.3	3.2	230	1.18	0.7	0.5	1.5	7	<0.1	0.1	0.6	23	0.13	0.061	13
K960877	Soil	<0.1	4.2	1.8	38	<0.1	2.1	2.8	254	0.96	<0.5	<0.5	6.1	11	<0.1	<0.1	0.2	18	0.14	0.056	16
K960878	Soil	0.3	6.2	3.8	34	0.1	5.0	3.6	208	1.20	1.3	0.7	4.8	9	<0.1	0.2	0.7	26	0.13	0.042	13
K960879	Soil	0.1	7.4	2.7	38	0.1	2.6	3.6	326	1.10	<0.5	<0.5	5.4	8	<0.1	0.1	0.3	23	0.16	0.057	14
K960880	Soil	0.3	6.8	3.6	38	0.1	5.2	3.6	247	1.18	0.7	1.2	7.0	8	<0.1	0.1	15.1	23	0.16	0.060	16
K960881	Soil	0.2	9.9	3.4	34	0.1	10.1	5.1	225	1.23	1.4	<0.5	2.3	10	0.1	0.2	0.5	29	0.19	0.055	11
K960882	Soil	0.1	8.9	2.4	53	0.1	16.2	5.8	295	1.44	1.0	<0.5	2.6	41	0.5	<0.1	0.1	66	1.54	0.050	3
K960883	Soil	0.3	15.0	3.6	37	0.2	14.5	5.5	266	1.10	1.6	<0.5	4.4	16	0.2	0.2	0.4	24	0.50	0.057	11
K960884	Soil	0.4	16.0	6.0	50	0.5	19.5	7.8	333	1.85	3.6	0.9	5.4	28	0.2	0.2	0.5	41	0.46	0.057	16
K960885	Soil	0.6	21.5	5.5	54	0.6	23.7	8.6	276	1.94	3.8	0.8	5.9	25	0.2	0.2	1.8	46	0.51	0.061	18
K960886	Soil	0.7	18.2	3.3	28	0.2	15.9	6.7	147	1.18	<0.5	0.7	5.6	16	<0.1	<0.1	<0.1	23	0.44	0.057	16
K960887	Soil	0.6	16.4	5.6	43	0.2	24.0	8.7	253	1.84	4.1	1.0	4.9	22	<0.1	0.2	0.5	45	0.40	0.053	16
K960888	Soil	0.4	10.5	3.9	29	0.2	10.9	5.2	238	1.07	1.9	<0.5	5.0	13	<0.1	0.2	0.3	23	0.25	0.042	11
K960889	Soil	0.6	21.3	6.3	49	0.1	25.4	9.8	316	1.98	4.6	2.2	6.1	25	0.1	0.2	1.4	46	0.47	0.062	19

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960860	Soil	27	0.70	81	0.064	<1	1.34	0.015	0.11	4.8	0.01	2.8	0.1	<0.05	5	<0.5	<0.2
K960861	Soil	27	0.59	60	0.046	<1	1.11	0.011	0.12	5.7	0.02	2.6	0.1	<0.05	4	<0.5	<0.2
K960862	Soil	27	0.52	78	0.069	<1	1.32	0.011	0.13	3.8	0.02	2.7	0.2	<0.05	5	<0.5	<0.2
K960863	Soil	27	0.59	96	0.080	<1	1.33	0.034	0.14	3.3	0.02	2.9	0.1	<0.05	4	<0.5	<0.2
K960864	Soil	16	0.49	56	0.066	<1	1.18	0.026	0.27	5.3	0.02	2.3	0.2	<0.05	4	<0.5	<0.2
K960865	Soil	20	0.69	64	0.080	<1	1.23	0.035	0.35	4.2	<0.01	1.9	0.4	<0.05	4	<0.5	<0.2
K960866	Soil	35	1.04	85	0.080	1	1.72	0.023	0.22	12.6	<0.01	3.1	0.3	<0.05	6	<0.5	<0.2
K960867	Soil	27	0.96	74	0.097	<1	1.51	0.051	0.41	10.3	<0.01	3.0	0.5	<0.05	6	<0.5	<0.2
K960868	Soil	51	1.62	133	0.126	2	2.44	0.090	1.01	54.5	<0.01	3.3	1.1	0.08	8	<0.5	<0.2
K960869	Soil	25	0.63	75	0.050	<1	1.42	0.007	0.29	4.5	<0.01	2.5	0.3	<0.05	4	<0.5	<0.2
K960870	Soil	26	0.74	138	0.057	<1	1.51	0.011	0.30	11.9	<0.01	2.1	0.2	<0.05	4	<0.5	<0.2
K960871	Soil	30	0.76	98	0.055	<1	1.64	0.007	0.31	5.6	0.01	3.2	0.3	<0.05	5	<0.5	<0.2
K960872	Soil	15	0.21	38	0.011	<1	0.64	0.003	0.12	6.2	0.01	1.7	0.1	<0.05	2	<0.5	<0.2
K960873	Soil	30	0.89	92	0.073	<1	1.60	0.022	0.16	5.2	0.01	3.5	0.2	<0.05	5	<0.5	<0.2
K960874	Soil	30	1.22	160	0.104	<1	1.60	0.047	0.27	3.9	0.02	3.5	0.2	<0.05	5	<0.5	<0.2
K960875	Soil	11	0.33	60	0.055	<1	0.90	0.018	0.22	7.1	0.01	1.8	0.2	<0.05	5	<0.5	<0.2
K960876	Soil	11	0.30	47	0.048	<1	0.84	0.021	0.31	2.7	0.01	1.5	0.3	<0.05	4	<0.5	<0.2
K960877	Soil	5	0.28	48	0.070	<1	0.72	0.055	0.40	5.0	0.02	1.7	0.4	<0.05	4	<0.5	<0.2
K960878	Soil	11	0.29	50	0.064	<1	0.86	0.022	0.24	5.6	<0.01	1.9	0.2	<0.05	4	<0.5	<0.2
K960879	Soil	6	0.30	55	0.080	<1	0.70	0.044	0.41	5.6	0.01	2.1	0.3	<0.05	4	<0.5	<0.2
K960880	Soil	10	0.35	49	0.071	<1	0.89	0.031	0.33	5.3	0.02	2.0	0.4	<0.05	4	<0.5	<0.2
K960881	Soil	18	0.46	69	0.052	<1	1.05	0.021	0.23	7.4	0.02	1.9	0.2	<0.05	4	<0.5	<0.2
K960882	Soil	23	2.42	166	0.118	1	2.28	0.062	1.00	1.7	<0.01	5.6	0.8	<0.05	6	<0.5	<0.2
K960883	Soil	21	0.44	66	0.057	<1	1.09	0.035	0.23	5.4	0.02	2.0	0.3	<0.05	4	<0.5	<0.2
K960884	Soil	32	0.86	97	0.086	<1	1.72	0.037	0.33	4.7	<0.01	3.8	0.4	<0.05	6	<0.5	<0.2
K960885	Soil	39	0.89	97	0.095	<1	1.80	0.042	0.30	5.2	0.01	4.4	0.4	<0.05	6	<0.5	<0.2
K960886	Soil	24	0.47	47	0.071	<1	0.82	0.064	0.27	4.8	0.01	1.9	0.3	<0.05	3	<0.5	<0.2
K960887	Soil	39	0.82	125	0.090	<1	1.93	0.054	0.27	6.0	0.01	3.6	0.3	<0.05	6	<0.5	<0.2
K960888	Soil	20	0.45	50	0.051	<1	1.01	0.043	0.21	6.0	0.01	2.0	0.2	<0.05	4	<0.5	<0.2
K960889	Soil	40	0.93	81	0.099	<1	2.00	0.062	0.40	4.2	0.01	4.2	0.4	<0.05	7	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960890	Soil	0.9	21.7	5.8	44	0.3	24.5	9.7	316	1.68	3.8	1.9	4.1	23	0.2	0.3	1.2	37	0.51	0.062	15
K960891	Soil	0.6	14.1	7.1	40	0.1	19.4	7.9	232	1.69	3.2	0.6	4.4	15	0.1	0.2	0.5	40	0.30	0.039	13
K960892	Soil	0.5	8.2	3.6	33	<0.1	8.0	4.7	309	1.11	1.1	<0.5	4.7	10	0.1	0.2	0.4	23	0.22	0.053	13
K960893	Soil	0.3	16.0	5.5	27	0.1	14.6	6.2	267	1.19	1.4	1.3	2.5	18	<0.1	0.1	0.2	26	0.49	0.055	12
K960894	Soil	0.7	12.8	6.1	37	<0.1	13.3	9.4	825	1.31	2.9	1.4	2.1	12	0.2	0.1	0.3	22	0.28	0.042	8
K960895	Soil	0.4	11.9	4.5	35	<0.1	11.5	5.8	218	1.38	1.9	1.1	4.7	11	<0.1	0.1	0.4	27	0.24	0.046	10
K960896	Soil	0.4	13.3	5.8	38	<0.1	20.1	7.6	246	1.81	2.8	1.3	6.2	23	<0.1	0.2	0.5	41	0.30	0.078	15
K960897	Soil	0.4	10.6	14.6	37	0.5	15.2	7.2	252	1.57	2.2	0.8	4.4	12	<0.1	0.1	0.7	35	0.20	0.047	14
K960898	Soil	0.6	12.2	7.6	38	0.2	15.2	6.8	242	1.77	2.5	0.8	4.0	26	0.1	0.2	0.3	40	0.23	0.054	15
K960899	Soil	0.3	12.0	7.3	39	0.2	17.8	9.0	323	1.97	1.6	0.7	12.7	84	<0.1	<0.1	0.1	59	0.52	0.142	39
K960900	Soil	0.5	11.2	6.8	35	0.2	16.3	6.9	240	1.54	2.8	1.5	5.6	10	<0.1	0.2	0.9	31	0.20	0.049	13
K960951	Soil	0.1	43.9	5.4	62	0.2	41.4	17.0	656	2.97	4.8	3.3	0.7	14	0.2	0.3	<0.1	43	0.60	0.042	2
K960952	Soil	0.2	39.0	9.6	57	0.3	53.2	18.3	644	2.66	8.8	5.0	0.4	13	0.2	0.3	0.2	48	0.18	0.051	2
K960953	Soil	0.1	58.9	11.3	61	0.3	84.6	22.9	688	3.45	10.6	4.3	1.0	14	0.2	0.4	0.1	81	0.32	0.080	4
K960954	Soil	<0.1	36.3	9.8	43	0.1	89.9	19.8	614	2.41	3.7	2.1	0.4	13	0.2	0.2	0.9	60	0.23	0.052	1
K960955	Soil	0.2	52.9	19.7	142	1.3	82.4	21.7	797	3.71	77.3	42.8	2.0	9	1.6	1.2	0.1	77	0.22	0.082	6
K960956	Soil	0.1	30.4	16.2	47	0.4	192.2	23.4	590	2.64	39.5	13.0	1.3	13	0.4	0.8	0.1	55	0.24	0.039	4
K960957	Soil	0.1	7.3	10.2	40	0.8	34.7	5.5	483	0.81	6.9	17.4	0.3	165	1.1	0.3	<0.1	10	14.40	0.030	3
K960958	Soil	0.3	68.2	31.9	62	2.8	87.9	13.0	566	3.91	302.6	248.4	5.8	28	0.8	4.8	0.1	19	0.30	0.062	13
K960959	Soil	0.2	29.2	8.8	38	0.2	294.0	29.3	528	2.59	7.1	<0.5	0.7	8	0.5	0.3	0.1	42	0.22	0.049	3
K960960	Soil	0.8	36.3	5.2	57	0.1	34.0	13.7	472	2.64	2.7	5.1	2.0	13	0.2	0.3	<0.1	51	0.29	0.083	7
K960961	Soil	0.6	29.8	4.0	38	<0.1	12.2	12.8	334	2.95	5.8	1.2	1.9	13	0.1	0.1	0.1	55	0.24	0.067	6
K960962	Soil	0.3	68.1	4.6	77	0.1	9.1	17.2	855	4.38	0.7	1.1	3.0	23	0.1	<0.1	0.1	105	0.65	0.097	10
K960963	Soil	0.5	44.7	4.8	70	0.1	13.4	15.4	622	3.05	2.0	1.2	2.2	14	<0.1	0.1	0.1	85	0.30	0.090	6
K960964	Soil	0.9	25.1	6.8	41	<0.1	7.9	6.7	319	2.97	2.7	3.8	3.3	10	0.2	0.2	0.1	44	0.21	0.071	8
K960965	Soil	0.8	31.5	6.0	40	0.2	9.4	8.9	405	2.39	3.0	1.1	4.4	13	0.1	0.1	0.1	42	0.24	0.074	10
K960966	Soil	0.5	54.5	5.0	47	<0.1	11.3	12.7	643	3.11	1.8	<0.5	5.2	13	<0.1	0.1	0.2	45	0.37	0.134	12
K960967	Soil	0.4	36.9	4.4	43	0.2	9.1	10.6	550	2.45	1.5	2.2	2.7	11	<0.1	0.1	0.1	41	0.28	0.106	8
K960968	Soil	0.2	24.2	3.2	23	0.2	5.6	5.4	230	1.23	<0.5	<0.5	0.5	8	<0.1	<0.1	<0.1	32	0.13	0.049	2
K960969	Soil	0.4	36.0	3.9	47	0.2	16.0	11.8	572	3.06	1.7	1.4	3.9	16	<0.1	<0.1	0.1	41	0.38	0.151	12

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960890	Soil	37	0.74	69	0.071	<1	1.59	0.056	0.31	6.3	0.02	3.2	0.3	<0.05	6	<0.5	<0.2
K960891	Soil	34	0.74	67	0.077	<1	1.66	0.036	0.23	5.8	0.01	3.1	0.2	<0.05	5	<0.5	<0.2
K960892	Soil	14	0.36	53	0.060	<1	0.85	0.023	0.27	6.6	0.02	1.7	0.3	<0.05	4	<0.5	<0.2
K960893	Soil	22	0.42	62	0.051	<1	1.11	0.078	0.18	5.0	<0.01	1.8	0.2	<0.05	4	<0.5	<0.2
K960894	Soil	16	0.33	102	0.039	<1	0.67	0.012	0.18	6.6	0.01	1.7	0.2	<0.05	3	<0.5	<0.2
K960895	Soil	20	0.49	55	0.065	<1	1.15	0.032	0.24	5.6	0.01	2.0	0.2	<0.05	4	<0.5	<0.2
K960896	Soil	35	0.73	114	0.081	<1	1.69	0.032	0.34	6.0	0.02	3.4	0.3	<0.05	5	<0.5	<0.2
K960897	Soil	28	0.61	74	0.072	<1	1.38	0.030	0.35	8.5	0.02	3.0	0.2	<0.05	5	<0.5	<0.2
K960898	Soil	27	0.65	129	0.076	<1	1.40	0.023	0.32	5.8	0.02	2.6	0.3	<0.05	5	<0.5	<0.2
K960899	Soil	26	0.99	223	0.122	<1	1.50	0.041	0.60	2.2	0.02	3.4	0.3	<0.05	5	<0.5	<0.2
K960900	Soil	25	0.51	71	0.063	<1	1.52	0.024	0.19	6.0	0.02	2.5	0.2	<0.05	5	<0.5	<0.2
K960951	Soil	51	1.69	68	0.042	<1	1.88	0.009	0.05	1.8	0.02	3.0	<0.1	<0.05	4	<0.5	<0.2
K960952	Soil	105	1.67	59	0.034	<1	1.56	0.004	0.05	3.0	0.03	2.3	<0.1	0.06	4	<0.5	<0.2
K960953	Soil	168	2.49	45	0.046	1	2.11	0.007	0.03	1.4	0.02	6.3	<0.1	<0.05	7	<0.5	<0.2
K960954	Soil	174	2.27	48	0.038	<1	1.51	0.007	0.03	1.9	0.01	2.8	<0.1	<0.05	4	<0.5	<0.2
K960955	Soil	136	1.85	192	0.016	1	1.58	0.008	0.07	3.2	0.02	7.0	<0.1	<0.05	6	<0.5	<0.2
K960956	Soil	249	2.66	93	0.036	<1	1.62	0.005	0.04	2.7	0.02	5.1	<0.1	<0.05	4	<0.5	<0.2
K960957	Soil	51	2.14	219	0.012	3	0.31	0.003	0.04	2.6	<0.01	1.9	<0.1	<0.05	<1	<0.5	<0.2
K960958	Soil	81	0.77	415	0.003	<1	1.17	0.005	0.04	2.6	0.08	7.4	<0.1	<0.05	3	<0.5	<0.2
K960959	Soil	501	2.85	69	0.020	2	1.03	0.005	0.05	2.8	0.02	3.2	<0.1	<0.05	3	<0.5	<0.2
K960960	Soil	42	0.96	121	0.058	<1	1.33	0.008	0.10	3.4	0.02	2.5	<0.1	<0.05	4	<0.5	<0.2
K960961	Soil	18	0.81	241	0.098	<1	1.54	0.006	0.24	1.8	<0.01	2.7	0.1	<0.05	5	<0.5	<0.2
K960962	Soil	10	1.08	256	0.036	<1	1.46	0.017	0.08	1.1	0.02	6.2	<0.1	<0.05	7	<0.5	<0.2
K960963	Soil	19	1.09	263	0.073	<1	1.57	0.008	0.24	2.1	<0.01	3.5	<0.1	<0.05	5	<0.5	<0.2
K960964	Soil	15	0.57	88	0.043	<1	1.33	0.004	0.07	1.7	0.03	2.2	<0.1	<0.05	5	<0.5	<0.2
K960965	Soil	17	0.52	121	0.047	<1	1.21	0.007	0.08	1.5	0.02	2.7	<0.1	<0.05	4	<0.5	<0.2
K960966	Soil	12	0.77	156	0.030	<1	1.30	0.006	0.09	2.2	0.02	4.0	<0.1	<0.05	4	<0.5	<0.2
K960967	Soil	12	0.64	120	0.034	<1	1.09	0.011	0.08	1.9	<0.01	3.3	<0.1	<0.05	4	<0.5	<0.2
K960968	Soil	8	0.42	85	0.042	<1	0.70	0.020	0.10	0.8	0.02	1.3	<0.1	<0.05	3	<0.5	<0.2
K960969	Soil	21	0.88	297	0.039	<1	1.26	0.007	0.14	2.0	<0.01	3.3	<0.1	<0.05	4	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K960970	Soil	0.6	24.3	2.8	32	0.1	7.4	10.7	783	3.63	1.3	0.7	4.0	8	<0.1	<0.1	<0.1	29	1.58	0.095	10
K960971	Soil	0.5	60.0	4.3	50	0.1	10.8	13.1	741	3.26	1.6	2.2	4.4	12	0.1	<0.1	0.2	48	0.33	0.108	13
K960972	Soil	0.6	71.2	4.6	69	0.1	16.1	15.8	794	3.82	2.5	2.3	4.3	12	0.2	0.5	0.2	75	0.39	0.113	9
K960973	Soil	0.6	35.1	4.8	58	<0.1	14.8	13.3	776	3.39	1.6	<0.5	3.7	11	<0.1	0.1	0.2	64	0.37	0.095	10
K960974	Soil	0.3	35.4	3.8	48	0.1	8.6	11.1	616	2.82	1.4	1.2	4.8	13	0.2	<0.1	0.2	45	0.35	0.112	13
K960975	Soil	0.3	21.9	3.9	69	<0.1	16.3	13.4	716	2.70	1.6	0.6	2.7	22	<0.1	0.1	0.1	60	0.42	0.088	7
K960976	Soil	0.5	36.8	3.1	34	0.1	13.8	10.4	397	3.25	3.7	<0.5	4.1	19	<0.1	0.2	0.3	55	0.32	0.085	11
K960977	Soil	1.3	37.2	7.4	77	0.2	23.0	12.6	651	2.58	3.1	1.1	2.9	15	0.2	0.3	0.1	51	0.41	0.090	9
K960978	Soil	1.1	18.6	9.0	68	0.3	19.4	10.1	408	2.32	3.9	1.6	2.8	13	0.3	0.3	0.1	51	0.23	0.060	9
K960979	Soil	0.1	71.4	5.1	113	0.1	13.7	13.3	1004	2.70	0.7	2.0	2.5	21	0.2	<0.1	<0.1	43	1.02	0.058	5
K960980	Soil	0.7	42.2	6.9	51	<0.1	2.2	4.3	1215	1.54	<0.5	1.6	6.9	40	0.2	<0.1	0.1	4	1.95	0.052	21
K960981	Soil	1.2	22.2	8.1	89	0.3	19.7	11.1	500	2.47	4.7	0.6	3.6	13	0.3	0.4	0.1	53	0.34	0.098	10
K960982	Soil	1.5	14.3	7.4	65	0.2	11.8	6.1	310	2.20	3.7	4.0	5.3	13	0.3	0.3	0.2	30	0.14	0.063	11
K960983	Soil	0.3	115.5	5.2	55	0.1	24.0	21.6	534	2.55	0.9	1.4	1.2	29	0.1	0.1	<0.1	64	0.45	0.068	4
K960984	Soil	1.3	28.2	8.4	59	0.3	22.1	9.8	434	2.07	4.5	2.1	4.8	15	0.2	0.3	0.2	40	0.28	0.088	14
K960985	Soil	0.2	108.7	1.6	71	0.2	17.4	25.0	770	3.72	0.6	3.2	0.6	50	0.1	0.1	<0.1	69	1.02	0.089	2
K960986	Soil	0.7	15.6	6.3	42	0.4	15.6	6.0	197	1.64	3.7	1.8	1.0	12	0.2	0.2	0.1	35	0.22	0.068	10
K960987	Soil	0.9	35.0	5.6	61	0.2	21.7	14.2	404	2.89	4.0	3.1	2.6	16	0.2	0.3	<0.1	58	0.26	0.063	7
K960988	Soil	1.2	13.0	9.3	40	0.2	9.9	4.8	281	1.44	4.5	3.3	2.4	7	<0.1	0.5	0.6	35	0.11	0.044	9
K960989	Soil	0.4	7.7	5.8	27	<0.1	5.8	3.1	172	0.89	2.2	1.3	2.2	3	<0.1	0.3	0.7	18	0.07	0.030	5
K960990	Soil	0.4	8.6	5.2	43	0.2	6.7	3.9	237	1.14	2.6	0.8	5.8	6	0.1	0.2	0.6	19	0.15	0.064	13
K960991	Soil	0.8	17.6	14.7	48	0.3	17.1	7.0	338	1.45	5.7	1.3	4.8	8	0.2	0.7	0.6	24	0.16	0.052	11
K960992	Soil	1.1	11.3	9.6	35	0.2	6.1	4.1	263	1.32	7.5	<0.5	22.7	4	<0.1	0.3	0.5	16	0.09	0.045	25
K960993	Soil	1.3	17.4	8.3	55	0.2	20.7	7.7	343	1.72	5.5	1.3	4.6	11	0.1	0.5	0.4	30	0.20	0.068	12
K960994	Soil	1.1	15.2	8.6	50	0.3	22.0	7.1	312	1.59	6.1	2.5	4.5	11	0.2	0.6	0.3	32	0.20	0.070	13
K960995	Soil	0.6	7.9	6.3	41	0.2	10.6	5.3	269	1.60	3.1	<0.5	11.2	7	0.1	0.2	0.4	25	0.16	0.055	16
K960996	Soil	0.4	12.2	4.5	45	0.2	9.1	5.4	329	1.34	1.9	<0.5	5.7	9	<0.1	0.2	0.4	26	0.18	0.063	16
K960997	Soil	3.9	42.9	14.7	30	0.2	10.9	6.9	704	1.40	3.6	2.9	2.6	5	0.1	0.6	0.5	18	0.06	0.030	6
K960998	Soil	1.0	14.4	7.1	36	0.3	12.6	6.1	282	1.39	2.3	1.0	4.3	7	<0.1	0.3	0.6	24	0.11	0.041	10
K960999	Soil	0.2	4.6	2.8	27	0.2	3.0	2.6	165	0.80	0.6	<0.5	8.6	4	<0.1	<0.1	0.1	15	0.08	0.028	14

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K960970	Soil	10	0.66	139	0.019	<1	1.25	0.010	0.13	1.6	<0.01	3.0	<0.1	<0.05	3	<0.5	<0.2
K960971	Soil	18	0.91	184	0.043	<1	1.41	0.008	0.13	2.0	<0.01	4.4	<0.1	<0.05	4	<0.5	<0.2
K960972	Soil	22	1.10	159	0.069	<1	1.62	0.006	0.22	2.6	<0.01	5.0	<0.1	<0.05	6	<0.5	<0.2
K960973	Soil	17	1.07	205	0.057	<1	1.62	0.008	0.14	2.2	<0.01	4.2	<0.1	<0.05	5	<0.5	<0.2
K960974	Soil	9	0.88	196	0.050	<1	1.29	0.006	0.19	2.3	<0.01	3.7	<0.1	<0.05	4	<0.5	<0.2
K960975	Soil	27	1.17	396	0.089	<1	1.49	0.013	0.32	1.9	<0.01	3.8	<0.1	<0.05	5	<0.5	<0.2
K960976	Soil	19	0.87	265	0.141	<1	1.45	0.013	0.53	2.2	0.02	3.6	0.2	<0.05	6	<0.5	<0.2
K960977	Soil	22	0.83	187	0.038	<1	1.30	0.009	0.08	3.7	0.01	3.2	<0.1	<0.05	4	<0.5	<0.2
K960978	Soil	28	0.66	99	0.066	<1	1.20	0.008	0.10	3.8	0.01	2.4	<0.1	<0.05	4	<0.5	<0.2
K960979	Soil	7	1.11	96	0.015	<1	1.48	0.012	0.05	1.3	<0.01	3.8	<0.1	<0.05	4	<0.5	<0.2
K960980	Soil	5	0.10	405	0.013	<1	0.30	0.015	0.08	3.0	0.02	1.5	<0.1	0.10	<1	<0.5	<0.2
K960981	Soil	22	0.83	172	0.059	<1	1.39	0.006	0.17	3.1	0.01	2.9	<0.1	<0.05	5	<0.5	<0.2
K960982	Soil	15	0.46	125	0.045	<1	0.93	0.012	0.16	2.9	<0.01	2.2	<0.1	0.10	4	<0.5	<0.2
K960983	Soil	50	1.41	412	0.102	<1	1.46	0.019	0.09	0.8	<0.01	2.2	<0.1	<0.05	5	<0.5	<0.2
K960984	Soil	29	0.65	196	0.045	<1	1.04	0.010	0.08	2.9	0.02	2.5	<0.1	<0.05	3	<0.5	<0.2
K960985	Soil	10	1.95	509	0.097	<1	2.31	0.011	0.04	1.4	<0.01	3.0	<0.1	<0.05	5	<0.5	<0.2
K960986	Soil	22	0.43	95	0.036	<1	1.00	0.012	0.06	2.5	0.01	1.5	<0.1	<0.05	3	0.5	<0.2
K960987	Soil	26	1.15	99	0.077	<1	1.61	0.006	0.08	2.5	<0.01	2.6	<0.1	<0.05	5	<0.5	<0.2
K960988	Soil	18	0.33	49	0.064	1	0.93	0.011	0.21	5.7	0.01	2.0	0.2	<0.05	4	<0.5	<0.2
K960989	Soil	11	0.21	50	0.041	2	0.68	0.021	0.14	5.2	0.01	1.6	0.1	<0.05	3	<0.5	<0.2
K960990	Soil	11	0.25	36	0.051	1	0.76	0.014	0.25	5.6	0.01	1.4	0.3	<0.05	4	<0.5	<0.2
K960991	Soil	22	0.31	57	0.033	1	0.79	0.012	0.12	6.9	0.01	1.7	0.2	<0.05	3	<0.5	<0.2
K960992	Soil	9	0.18	35	0.040	1	0.60	0.011	0.22	7.9	<0.01	1.8	0.4	<0.05	4	<0.5	<0.2
K960993	Soil	22	0.42	67	0.040	1	0.93	0.010	0.12	6.7	0.01	2.1	0.2	<0.05	3	<0.5	<0.2
K960994	Soil	23	0.37	65	0.046	<1	0.92	0.008	0.08	5.5	0.02	1.8	0.1	<0.05	3	<0.5	<0.2
K960995	Soil	15	0.31	53	0.069	<1	0.97	0.013	0.21	5.9	0.01	2.2	0.3	<0.05	4	<0.5	<0.2
K960996	Soil	11	0.37	72	0.068	<1	0.85	0.028	0.32	5.0	0.01	2.3	0.3	<0.05	4	<0.5	<0.2
K960997	Soil	12	0.25	42	0.017	<1	0.68	0.005	0.07	6.8	0.02	1.4	0.1	<0.05	2	<0.5	<0.2
K960998	Soil	15	0.36	55	0.025	<1	0.74	0.008	0.10	9.5	0.01	1.9	0.2	<0.05	2	<0.5	<0.2
K960999	Soil	7	0.22	33	0.055	<1	0.62	0.024	0.28	6.7	0.01	1.6	0.3	<0.05	3	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
MDL		0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
K961000	Soil	0.3	9.6	4.6	41	0.3	9.2	5.8	313	1.57	2.2	<0.5	3.7	8	0.1	0.4	0.2	33	0.14	0.057	10
K960090	Soil	0.6	12.6	12.2	41	0.2	17.1	11.9	691	2.15	223.6	8.8	7.0	23	0.1	20.8	0.2	12	0.16	0.039	22

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

CERTIFICATE OF ANALYSIS WHI12000010.1

Method		1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
Analyte		Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
Unit		ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
MDL		1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
K961000	Soil	17	0.43	54	0.075	<1	0.95	0.013	0.26	5.8	0.01	2.5	0.3	<0.05	4	<0.5	<0.2
K960090	Soil	10	0.29	88	0.007	<1	0.61	0.006	0.08	4.5	0.12	2.1	<0.1	<0.05	1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

QUALITY CONTROL REPORT WHI12000010.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	Au	Th	Sr	Cd	Sb	Bi	V	Ca	P	La
	Unit	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppb	ppm	ppm	ppm	ppm	ppm	ppm	%	%	ppm
	MDL	0.1	0.1	0.1	1	0.1	0.1	0.1	1	0.01	0.5	0.5	0.1	1	0.1	0.1	0.1	2	0.01	0.001	1
Pulp Duplicates																					
K960605	Soil	0.2	13.1	4.2	36	0.2	15.6	9.7	352	1.95	3.9	1.1	1.7	54	0.1	0.4	<0.1	63	0.35	0.073	5
REP K960605	QC	0.2	13.1	4.0	36	0.2	14.8	9.3	336	1.96	3.8	<0.5	1.5	54	<0.1	0.3	<0.1	60	0.34	0.072	5
K960608	Soil	0.2	16.8	3.9	52	0.3	16.1	11.7	571	2.38	3.8	2.2	2.2	35	<0.1	0.3	<0.1	68	0.48	0.107	7
REP K960608	QC	0.2	16.4	3.8	52	0.3	16.1	11.6	558	2.37	3.7	1.4	2.1	36	0.1	0.3	<0.1	64	0.49	0.101	7
K960611	Soil	<0.1	14.4	3.8	30	<0.1	11.7	8.6	381	1.85	4.1	4.4	2.8	33	<0.1	0.3	<0.1	54	0.44	0.087	6
REP K960611	QC	<0.1	16.0	3.7	34	0.1	12.4	8.7	381	1.93	3.8	1.2	2.9	33	<0.1	0.3	<0.1	52	0.44	0.088	6
K960658	Soil	0.6	16.7	7.7	54	0.1	28.3	11.9	352	2.44	3.2	<0.5	3.1	20	<0.1	0.3	0.1	46	0.29	0.083	9
REP K960658	QC	0.5	17.6	7.1	54	0.2	27.5	11.6	355	2.42	3.4	0.5	3.0	20	0.1	0.3	<0.1	46	0.28	0.082	9
K960697	Soil	0.8	61.6	6.6	50	0.1	35.7	15.8	447	2.23	18.4	<0.5	2.3	52	0.2	0.5	0.2	49	0.32	0.087	7
REP K960697	QC	0.7	59.0	6.4	51	0.2	36.6	15.9	451	2.22	18.1	0.8	2.3	51	0.1	0.5	0.2	48	0.31	0.082	7
K960701	Soil	0.6	20.5	3.5	38	0.1	216.6	22.9	309	2.48	2.7	7.5	3.5	9	0.2	0.2	0.2	54	0.27	0.061	7
REP K960701	QC	0.6	19.9	3.8	36	0.1	210.1	21.3	292	2.41	2.3	12.5	3.5	9	0.1	0.2	0.2	52	0.25	0.060	7
K960714	Soil	0.3	20.7	29.9	40	0.2	26.9	14.0	503	2.15	12.0	4.1	6.5	8	<0.1	1.0	0.5	20	0.12	0.047	21
REP K960714	QC	0.3	21.0	30.3	41	0.2	26.5	13.8	517	2.16	12.0	7.5	6.5	8	<0.1	1.0	0.5	20	0.12	0.046	21
K960743	Soil	0.6	17.3	11.5	38	0.2	28.5	11.0	323	2.21	42.3	2.5	6.3	10	<0.1	5.7	0.3	21	0.07	0.029	21
REP K960743	QC	0.7	17.2	11.6	38	0.2	27.8	11.1	330	2.22	42.6	5.6	6.3	10	<0.1	6.1	0.3	20	0.07	0.028	22
K960815	Soil	0.2	10.4	3.9	46	0.2	15.5	11.0	441	2.60	4.8	1.5	2.0	23	<0.1	0.4	<0.1	65	0.37	0.075	5
REP K960815	QC	0.2	10.1	3.8	45	0.2	15.2	11.1	450	2.58	4.5	1.1	1.9	22	<0.1	0.4	<0.1	64	0.35	0.081	5
K960824	Soil	0.5	60.3	5.4	59	0.5	45.2	20.0	581	3.21	8.1	3.3	2.0	47	0.1	0.4	<0.1	110	1.35	0.056	9
REP K960824	QC	0.3	60.3	5.2	58	0.3	44.8	19.6	557	3.14	7.9	2.0	2.0	46	0.2	0.5	<0.1	108	1.35	0.059	9
K960841	Soil	0.5	35.3	4.3	47	0.4	30.8	17.0	522	3.54	5.6	<0.5	2.3	23	0.1	0.4	<0.1	119	0.66	0.052	9
REP K960841	QC	0.5	35.4	4.1	47	0.4	30.5	17.4	520	3.57	5.4	6.1	2.5	23	0.1	0.4	<0.1	121	0.66	0.052	9
K960860	Soil	1.0	19.0	6.3	48	0.1	20.2	9.6	354	2.24	3.6	0.8	4.3	10	0.1	0.4	0.6	43	0.18	0.047	10
REP K960860	QC	0.9	19.1	6.4	47	0.1	20.5	9.9	354	2.24	3.6	0.9	4.2	10	0.2	0.3	0.5	43	0.19	0.051	10
K960876	Soil	0.3	7.4	3.2	35	0.1	4.3	3.2	230	1.18	0.7	0.5	1.5	7	<0.1	0.1	0.6	23	0.13	0.061	13
REP K960876	QC	0.3	7.2	3.5	35	0.1	4.1	3.2	222	1.15	0.8	<0.5	1.6	7	<0.1	0.2	0.6	23	0.13	0.059	13
K960884	Soil	0.4	16.0	6.0	50	0.5	19.5	7.8	333	1.85	3.6	0.9	5.4	28	0.2	0.2	0.5	41	0.46	0.057	16
REP K960884	QC	0.5	16.1	6.0	49	0.4	18.9	7.5	316	1.85	3.6	<0.5	5.6	27	<0.1	0.2	0.5	42	0.45	0.055	16

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

QUALITY CONTROL REPORT WHI12000010.1

	Method	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15	1DX15
	Analyte	Cr	Mg	Ba	Ti	B	Al	Na	K	W	Hg	Sc	Tl	S	Ga	Se	Te
	Unit	ppm	%	ppm	%	ppm	%	%	%	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm
	MDL	1	0.01	1	0.001	1	0.01	0.001	0.01	0.1	0.01	0.1	0.1	0.05	1	0.5	0.2
Pulp Duplicates																	
K960605	Soil	40	0.62	61	0.061	<1	1.04	0.023	0.05	4.4	0.02	2.3	<0.1	0.05	4	<0.5	<0.2
REP K960605	QC	39	0.65	63	0.058	<1	1.04	0.022	0.05	4.7	0.02	2.2	<0.1	<0.05	4	<0.5	<0.2
K960608	Soil	37	0.93	104	0.070	2	1.39	0.027	0.09	2.7	0.03	3.8	<0.1	<0.05	5	<0.5	<0.2
REP K960608	QC	36	0.89	101	0.070	1	1.35	0.027	0.09	2.6	0.03	3.8	<0.1	0.07	5	<0.5	<0.2
K960611	Soil	30	0.66	84	0.059	<1	0.93	0.041	0.06	1.6	<0.01	3.3	<0.1	<0.05	4	<0.5	<0.2
REP K960611	QC	29	0.63	87	0.059	1	0.89	0.042	0.06	1.7	<0.01	3.3	<0.1	<0.05	4	<0.5	<0.2
K960658	Soil	42	0.86	86	0.077	1	1.31	0.014	0.16	3.3	<0.01	2.4	0.1	<0.05	5	<0.5	<0.2
REP K960658	QC	40	0.89	82	0.074	<1	1.33	0.016	0.17	3.1	0.01	2.2	<0.1	<0.05	5	<0.5	<0.2
K960697	Soil	49	0.95	678	0.055	<1	1.18	0.017	0.09	2.9	0.03	3.3	<0.1	<0.05	3	<0.5	<0.2
REP K960697	QC	47	0.96	668	0.056	<1	1.12	0.016	0.08	3.0	0.02	3.1	<0.1	<0.05	3	<0.5	<0.2
K960701	Soil	174	2.07	44	0.111	2	1.14	0.019	0.18	2.5	<0.01	3.7	0.1	<0.05	4	<0.5	<0.2
REP K960701	QC	165	2.08	45	0.107	2	1.13	0.019	0.17	2.4	<0.01	3.5	0.1	<0.05	3	<0.5	<0.2
K960714	Soil	23	0.60	52	0.034	<1	1.06	0.007	0.11	5.9	0.01	1.5	<0.1	<0.05	3	<0.5	<0.2
REP K960714	QC	23	0.61	52	0.036	<1	1.08	0.005	0.11	5.7	0.01	1.6	<0.1	<0.05	3	<0.5	<0.2
K960743	Soil	26	0.27	54	0.013	<1	0.79	0.008	0.08	7.0	0.06	1.8	<0.1	<0.05	2	<0.5	<0.2
REP K960743	QC	25	0.27	55	0.013	1	0.80	0.007	0.08	7.1	0.05	2.0	<0.1	<0.05	2	<0.5	<0.2
K960815	Soil	39	0.92	75	0.055	<1	1.43	0.020	0.05	3.1	0.02	4.5	<0.1	<0.05	6	<0.5	<0.2
REP K960815	QC	38	0.93	75	0.053	<1	1.44	0.022	0.05	3.0	0.02	4.4	<0.1	<0.05	5	<0.5	<0.2
K960824	Soil	117	1.46	83	0.139	3	3.03	0.080	0.07	1.2	0.04	8.2	<0.1	<0.05	7	<0.5	<0.2
REP K960824	QC	113	1.54	83	0.131	4	2.97	0.079	0.06	1.2	0.03	7.8	<0.1	<0.05	7	<0.5	<0.2
K960841	Soil	57	1.11	92	0.164	2	1.71	0.068	0.04	2.2	0.02	7.2	<0.1	<0.05	7	<0.5	<0.2
REP K960841	QC	58	1.11	92	0.165	1	1.67	0.066	0.04	2.0	0.01	7.2	<0.1	<0.05	7	<0.5	<0.2
K960860	Soil	27	0.70	81	0.064	<1	1.34	0.015	0.11	4.8	0.01	2.8	0.1	<0.05	5	<0.5	<0.2
REP K960860	QC	27	0.71	83	0.064	<1	1.37	0.015	0.11	5.0	0.01	3.0	0.1	<0.05	5	<0.5	<0.2
K960876	Soil	11	0.30	47	0.048	<1	0.84	0.021	0.31	2.7	0.01	1.5	0.3	<0.05	4	<0.5	<0.2
REP K960876	QC	11	0.30	46	0.047	<1	0.81	0.020	0.30	2.7	<0.01	1.3	0.3	<0.05	4	<0.5	<0.2
K960884	Soil	32	0.86	97	0.086	<1	1.72	0.037	0.33	4.7	<0.01	3.8	0.4	<0.05	6	<0.5	<0.2
REP K960884	QC	32	0.88	98	0.090	<1	1.78	0.036	0.34	4.9	0.01	3.7	0.4	<0.05	6	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

QUALITY CONTROL REPORT WHI12000010.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
K960957	Soil	0.1	7.3	10.2	40	0.8	34.7	5.5	483	0.81	6.9	17.4	0.3	165	1.1	0.3	<0.1	10	14.40	0.030	3
REP K960957	QC	<0.1	7.6	10.5	42	0.7	38.7	5.6	513	0.91	6.0	7.1	0.4	181	1.1	0.3	<0.1	14	14.11	0.030	4
K960967	Soil	0.4	36.9	4.4	43	0.2	9.1	10.6	550	2.45	1.5	2.2	2.7	11	<0.1	0.1	0.1	41	0.28	0.106	8
REP K960967	QC	0.5	38.6	4.4	45	0.2	9.2	10.6	544	2.53	1.6	1.2	2.7	11	<0.1	0.1	0.1	42	0.29	0.105	8
K960980	Soil	0.7	42.2	6.9	51	<0.1	2.2	4.3	1215	1.54	<0.5	1.6	6.9	40	0.2	<0.1	0.1	4	1.95	0.052	21
REP K960980	QC	0.6	42.0	6.6	51	<0.1	2.1	4.2	1196	1.52	<0.5	0.9	6.7	39	0.2	<0.1	0.1	4	1.91	0.054	21
K960995	Soil	0.6	7.9	6.3	41	0.2	10.6	5.3	269	1.60	3.1	<0.5	11.2	7	0.1	0.2	0.4	25	0.16	0.055	16
REP K960995	QC	0.6	7.7	6.3	40	0.2	9.7	5.1	265	1.53	3.0	<0.5	11.6	7	0.1	0.2	0.4	24	0.15	0.057	18
K960998	Soil	1.0	14.4	7.1	36	0.3	12.6	6.1	282	1.39	2.3	1.0	4.3	7	<0.1	0.3	0.6	24	0.11	0.041	10
REP K960998	QC	1.1	14.1	6.9	39	0.3	12.3	6.2	283	1.36	2.2	2.5	4.2	6	<0.1	0.3	0.6	23	0.11	0.042	9
Reference Materials																					
STD DS8	Standard	12.0	103.6	120.4	287	1.7	36.2	6.9	566	2.30	23.3	105.9	6.7	65	2.3	5.7	7.0	40	0.63	0.071	14
STD DS8	Standard	12.6	113.0	120.4	309	1.7	39.6	7.8	628	2.48	25.9	111.1	7.0	63	2.4	5.7	6.4	41	0.67	0.084	14
STD DS8	Standard	12.9	112.8	127.3	318	1.7	39.5	7.3	597	2.41	24.1	122.2	6.6	62	2.4	5.2	6.5	43	0.68	0.076	14
STD DS8	Standard	12.4	117.8	117.2	298	1.7	35.1	6.8	545	2.20	22.7	107.1	6.7	70	2.4	5.8	7.1	41	0.64	0.081	15
STD DS8	Standard	13.6	102.6	122.5	297	1.8	37.2	7.4	587	2.33	23.8	110.2	6.9	66	2.4	5.5	6.1	41	0.68	0.073	15
STD DS8	Standard	12.3	102.8	123.9	312	1.8	38.1	7.5	610	2.41	23.8	115.6	6.4	61	2.4	5.6	6.3	40	0.70	0.076	14
STD DS8	Standard	13.2	104.7	115.6	313	1.7	37.8	7.8	615	2.43	22.9	111.6	6.5	63	2.3	5.3	6.1	44	0.70	0.076	14
STD DS8	Standard	13.6	111.5	121.9	310	1.7	38.6	7.3	599	2.37	23.4	109.2	6.5	63	2.1	5.7	6.5	43	0.65	0.078	14
STD DS8	Standard	13.0	107.4	121.3	306	1.8	37.9	7.6	588	2.36	23.1	114.0	6.5	62	2.1	5.0	5.4	42	0.66	0.073	15
STD DS8	Standard	12.9	106.2	118.4	306	1.7	36.2	7.4	587	2.36	23.3	114.0	6.6	62	2.2	4.9	5.6	41	0.67	0.077	15
STD DS8 Expected		13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	107	6.89	67.7	2.38	5.7	6.67	41.1	0.7	0.08	14.6
BLK	Blank	<0.1	<0.1	0.2	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	0.1	<0.1	<1	<0.1	<0.1	<0.1	1	0.02	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	0.2	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

QUALITY CONTROL REPORT WHI12000010.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
K960957	Soil	51	2.14	219	0.012	3	0.31	0.003	0.04	2.6	<0.01	1.9	<0.1	<0.05	<1	<0.5	<0.2
REP K960957	QC	58	2.18	232	0.017	3	0.33	0.003	0.04	3.0	0.01	2.1	<0.1	0.08	1	<0.5	<0.2
K960967	Soil	12	0.64	120	0.034	<1	1.09	0.011	0.08	1.9	<0.01	3.3	<0.1	<0.05	4	<0.5	<0.2
REP K960967	QC	12	0.66	128	0.036	<1	1.14	0.009	0.08	1.9	0.02	3.1	<0.1	<0.05	4	<0.5	<0.2
K960980	Soil	5	0.10	405	0.013	<1	0.30	0.015	0.08	3.0	0.02	1.5	<0.1	0.10	<1	<0.5	<0.2
REP K960980	QC	5	0.10	433	0.015	<1	0.31	0.020	0.08	2.9	0.01	1.6	<0.1	0.12	1	<0.5	<0.2
K960995	Soil	15	0.31	53	0.069	<1	0.97	0.013	0.21	5.9	0.01	2.2	0.3	<0.05	4	<0.5	<0.2
REP K960995	QC	15	0.29	51	0.063	<1	0.91	0.013	0.20	6.0	0.01	2.2	0.3	<0.05	4	<0.5	<0.2
K960998	Soil	15	0.36	55	0.025	<1	0.74	0.008	0.10	9.5	0.01	1.9	0.2	<0.05	2	<0.5	<0.2
REP K960998	QC	15	0.37	53	0.023	<1	0.70	0.008	0.10	9.1	0.01	1.8	0.2	<0.05	2	<0.5	<0.2
Reference Materials																	
STD DS8	Standard	112	0.57	265	0.117	3	0.82	0.086	0.37	3.0	0.19	2.3	5.1	0.14	4	4.2	4.4
STD DS8	Standard	119	0.61	264	0.106	3	0.88	0.085	0.40	2.9	0.19	2.4	5.4	0.20	4	5.3	4.5
STD DS8	Standard	118	0.67	272	0.117	2	0.91	0.106	0.41	3.1	0.21	2.9	5.7	0.17	4	5.8	5.2
STD DS8	Standard	112	0.58	261	0.122	3	0.86	0.081	0.36	2.7	0.17	2.4	5.0	0.14	4	4.8	4.6
STD DS8	Standard	115	0.60	278	0.109	3	0.92	0.098	0.43	2.9	0.19	3.2	5.6	0.12	5	4.9	4.7
STD DS8	Standard	120	0.63	268	0.105	3	0.91	0.084	0.42	3.1	0.19	2.7	5.6	0.18	5	5.4	5.1
STD DS8	Standard	120	0.61	279	0.106	2	0.93	0.097	0.43	2.8	0.20	3.1	5.4	0.15	5	4.8	5.0
STD DS8	Standard	121	0.57	261	0.115	2	0.89	0.087	0.38	2.9	0.19	2.6	5.3	0.15	4	5.3	4.5
STD DS8	Standard	119	0.59	265	0.108	1	0.89	0.087	0.39	2.7	0.20	2.6	5.4	0.16	5	4.7	4.4
STD DS8	Standard	114	0.59	279	0.101	2	0.91	0.098	0.41	2.9	0.21	3.1	5.3	0.16	5	4.4	5.0
STD DS8 Expected		115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.192	2.3	5.4	0.1679	4.7	5.23	5
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

QUALITY CONTROL REPORT WHI12000010.1

		1DX15 Mo ppm 0.1	1DX15 Cu ppm 0.1	1DX15 Pb ppm 0.1	1DX15 Zn ppm 1	1DX15 Ag ppm 0.1	1DX15 Ni ppm 0.1	1DX15 Co ppm 0.1	1DX15 Mn ppm 1	1DX15 Fe % 0.01	1DX15 As ppm 0.5	1DX15 Au ppb 0.5	1DX15 Th ppm 0.1	1DX15 Sr ppm 1	1DX15 Cd ppm 0.1	1DX15 Sb ppm 0.1	1DX15 Bi ppm 0.1	1DX15 V ppm 2	1DX15 Ca % 0.01	1DX15 P % 0.001	1DX15 La ppm 1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1
BLK	Blank	<0.1	<0.1	<0.1	<1	<0.1	<0.1	<0.1	<1	<0.01	<0.5	<0.5	<0.1	<1	<0.1	<0.1	<0.1	<2	<0.01	<0.001	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: March 28, 2012

QUALITY CONTROL REPORT WHI12000010.1

		1DX15 Cr ppm 1	1DX15 Mg % 0.01	1DX15 Ba ppm 1	1DX15 Ti % 0.001	1DX15 B ppm 1	1DX15 Al % 0.01	1DX15 Na % 0.001	1DX15 K % 0.01	1DX15 W ppm 0.1	1DX15 Hg ppm 0.01	1DX15 Sc ppm 0.1	1DX15 Tl ppm 0.1	1DX15 S % 0.05	1DX15 Ga ppm 1	1DX15 Se ppm 0.5	1DX15 Te ppm 0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2
BLK	Blank	<1	<0.01	<1	<0.001	<1	<0.01	<0.001	<0.01	<0.1	<0.01	<0.1	<0.1	<0.05	<1	<0.5	<0.2

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Submitted By: Andrew Caldwell
Receiving Lab: Canada-Whitehorse
Received: September 30, 2011
Report Date: October 28, 2011
Page: 1 of 5

CERTIFICATE OF ANALYSIS WHI11001565.2

CLIENT JOB INFORMATION

Project: LIVINGSTONE
Shipment ID: GPD2011LIV-005
P.O. Number
Number of Samples: 91

SAMPLE DISPOSAL

RTRN-PLP Return
RTRN-RJT Return

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	89	Crush, split and pulverize 250 g rock to 200 mesh			WHI
G601	91	Lead Collection Fire - Assay Fusion - AAS Finish	30	Completed	VAN
7TD1	91	4-acid Digestion ICP-ES Finish	0.5	Completed	VAN
1D01-1D02-1D03	91	1:1:1 Aqua Regia digestion ICP-ES analysis	0.5	Completed	VAN
7AR	1	1:1:1 Aqua Regia Digestion ICP-ES Finish	0.4	Completed	VAN

ADDITIONAL COMMENTS

Version 2: 1D01-1D02-1D03 included.

Invoice To: Golden Predator Canada Corp.
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4
Canada

CC: Jack Cote
Linda Lewis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

CERTIFICATE OF ANALYSIS WHI11001565.2

Method		WGHT	G6	7TD	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
Analyte		Wgt	Au	Ag	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi
Unit		kg	ppm	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		0.01	0.005	2	1	1	3	1	0.3	1	1	2	0.01	2	8	2	2	1	0.5	3	3
J971802	Rock	0.61	0.015	<2	<1	6	<3	47	<0.3	33	28	566	2.77	<2	<8	<2	<2	182	<0.5	<3	<3
J971803	Rock	0.92	0.010	<2	<1	4	<3	16	<0.3	7	2	279	0.51	<2	<8	<2	<2	82	<0.5	<3	<3
J971804	Rock	1.27	0.014	<2	<1	11	17	47	<0.3	22	9	1583	3.09	5	<8	<2	4	7	<0.5	<3	<3
J971805	Rock	0.99	0.032	<2	1	39	40	44	0.4	16	9	333	2.57	9	<8	<2	<2	7	<0.5	<3	<3
J971806	Rock	1.23	0.016	<2	1	7	8	6	<0.3	2	1	40	0.72	13	<8	<2	<2	1	<0.5	<3	<3
J971807	Rock	0.63	0.013	<2	<1	4	10	10	<0.3	4	2	647	0.98	49	<8	<2	<2	2	<0.5	<3	<3
J971808	Rock	0.72	0.013	<2	<1	1	<3	11	<0.3	1	1	165	0.37	<2	<8	<2	13	76	<0.5	<3	<3
J971809	Rock	1.11	0.018	<2	<1	2	<3	9	<0.3	2	13	264	1.32	<2	<8	<2	5	11	<0.5	<3	<3
J971810	Rock	0.65	0.013	<2	1	2	<3	4	<0.3	<1	2	50	1.75	<2	<8	<2	6	12	<0.5	<3	<3
J971811	Rock	0.66	0.047	<2	23	12	23	45	0.3	12	21	813	7.72	4	<8	<2	<2	12	<0.5	<3	<3
J971812	Rock	1.00	0.020	<2	112	3	10	1	<0.3	1	5	26	2.60	5	<8	<2	3	10	<0.5	<3	<3
J971813	Rock	0.55	0.009	<2	6	7	5	10	<0.3	6	4	149	3.04	<2	<8	<2	9	27	<0.5	<3	<3
J971814	Rock	0.89	0.034	<2	1	577	13	374	1.0	9	3	769	8.68	<2	<8	<2	<2	57	<0.5	<3	3
J971815	Rock	0.27	0.006	<2	<1	1203	7	1574	<0.3	22	29	6461	6.80	<2	<8	<2	<2	16	11.5	<3	<3
J971816	Rock	0.44	0.008	<2	<1	89	18	469	<0.3	17	27	3798	7.94	<2	<8	<2	<2	28	1.5	<3	4
J971817	Rock	0.48	0.023	<2	2	499	52	702	0.4	11	4	1408	7.65	<2	<8	<2	<2	21	<0.5	<3	<3
J971818	Rock	0.36	0.059	5	48	913	278	59	4.4	4	11	621	19.88	4	<8	<2	<2	154	<0.5	<3	13
J971819	Rock	0.86	0.027	<2	<1	368	17	52	0.4	10	25	1950	4.26	<2	<8	<2	<2	71	0.6	<3	<3
J971820	Rock	0.75	0.006	<2	<1	56	5	74	0.7	46	31	315	3.68	<2	<8	<2	<2	36	<0.5	<3	<3
J971821	Rock	0.68	<0.005	<2	<1	10	<3	18	<0.3	4	2	1350	0.96	<2	<8	<2	<2	14	<0.5	<3	<3
J971822	Rock	0.57	0.007	<2	4	17	26	39	<0.3	45	8	1078	2.80	18	<8	<2	<2	175	0.5	<3	<3
J971823	Rock	0.65	0.005	<2	<1	2	9	22	<0.3	7	2	993	1.48	4	<8	<2	<2	11	<0.5	<3	<3
J971824	Rock	0.50	0.005	<2	<1	27	19	65	<0.3	37	19	723	3.73	34	<8	<2	10	5	<0.5	<3	<3
J971825	Rock	0.87	0.008	<2	<1	3	<3	5	<0.3	6	2	527	2.28	190	<8	<2	<2	69	<0.5	<3	<3
J971826	Rock	0.78	0.006	<2	<1	2	23	30	<0.3	40	9	398	1.54	44	<8	<2	<2	30	<0.5	<3	<3
J971827	Rock	0.71	0.007	<2	<1	<1	8	3	<0.3	6	2	593	1.79	10	9	<2	<2	201	<0.5	<3	<3
J971828	Rock	0.76	0.005	<2	<1	1	81	7	<0.3	2	1	518	0.66	<2	<8	<2	<2	2	<0.5	<3	<3
J971829	Rock	0.59	0.007	<2	<1	11	30	43	<0.3	23	10	2797	4.97	22	15	<2	<2	330	1.3	<3	<3
J971830	Rock	0.62	<0.005	<2	<1	5	15	26	<0.3	16	5	2034	1.74	<2	<8	<2	<2	16	<0.5	<3	<3
J971831	Rock	0.43	<0.005	<2	<1	7	5	24	<0.3	12	6	509	1.67	<2	<8	<2	7	4	<0.5	<3	<3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

CERTIFICATE OF ANALYSIS WHI11001565.2

	Method	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	7AR
	Analyte	V	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga	Pb
	Unit	ppm	%	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm	%
	MDL	1	0.01	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5	0.01
J971802	Rock	79	1.91	0.150	8	33	1.81	15	0.180	<20	2.23	0.02	0.03	<2	<0.05	<1	<5	<5	5	
J971803	Rock	4	3.03	0.012	2	10	0.15	20	0.008	<20	0.21	<0.01	0.03	<2	<0.05	<1	<5	<5	<5	
J971804	Rock	5	0.53	0.024	10	13	0.19	75	0.002	<20	0.50	0.02	0.11	<2	<0.05	<1	<5	<5	<5	
J971805	Rock	3	0.05	0.023	4	15	0.11	23	0.003	<20	0.31	0.04	0.02	<2	<0.05	<1	<5	<5	<5	
J971806	Rock	1	<0.01	0.014	3	13	<0.01	14	<0.001	<20	0.13	<0.01	0.05	<2	<0.05	<1	<5	<5	<5	
J971807	Rock	1	0.01	0.006	<1	12	0.03	23	<0.001	<20	0.07	0.01	0.02	<2	<0.05	<1	<5	<5	<5	
J971808	Rock	1	0.03	0.005	14	9	0.08	2251	0.002	<20	0.26	0.05	0.14	<2	0.06	<1	<5	<5	<5	
J971809	Rock	4	0.02	0.018	16	3	0.38	221	0.026	<20	0.59	0.09	0.07	<2	0.08	<1	<5	<5	<5	
J971810	Rock	4	0.01	0.020	22	3	0.15	207	0.058	<20	0.36	0.10	0.28	<2	0.34	<1	<5	<5	<5	
J971811	Rock	105	0.29	0.121	1	9	2.87	91	0.279	<20	3.04	<0.01	0.35	<2	1.26	<1	<5	<5	<5	
J971812	Rock	3	<0.01	0.004	9	3	0.04	102	0.002	<20	0.26	0.05	0.22	<2	0.88	<1	<5	<5	<5	
J971813	Rock	10	<0.01	0.020	14	9	0.37	686	0.008	<20	0.65	0.02	0.38	<2	0.27	<1	<5	<5	<5	
J971814	Rock	231	0.18	0.112	6	19	2.63	233	0.014	<20	2.91	0.11	0.16	<2	0.71	<1	<5	18	14	
J971815	Rock	169	0.40	0.158	14	16	3.91	201	0.031	<20	4.18	<0.01	0.20	<2	<0.05	<1	<5	13	13	
J971816	Rock	320	2.15	0.165	10	13	2.50	305	0.054	<20	2.52	0.02	0.36	<2	<0.05	<1	<5	16	11	
J971817	Rock	140	0.24	0.146	8	13	3.06	371	0.034	<20	3.35	0.04	0.29	<2	0.47	<1	<5	9	11	
J971818	Rock	117	0.08	0.188	10	5	0.09	153	0.042	<20	0.38	0.35	0.14	<2	1.40	<1	<5	9	<5	
J971819	Rock	66	5.04	0.103	6	4	0.79	193	0.015	<20	0.66	0.02	0.31	<2	0.36	<1	<5	10	<5	
J971820	Rock	159	0.90	0.088	2	101	1.65	53	0.184	<20	2.44	0.15	1.13	<2	1.24	<1	<5	14	7	
J971821	Rock	2	0.53	0.027	1	17	0.04	55	<0.001	<20	0.08	0.02	0.03	<2	<0.05	<1	<5	<5	<5	
J971822	Rock	11	8.22	0.286	4	18	4.61	42	0.001	<20	0.13	0.01	0.06	<2	<0.05	<1	<5	<5	<5	
J971823	Rock	2	1.23	0.025	2	9	0.06	21	<0.001	<20	0.11	0.06	<0.01	<2	<0.05	<1	<5	<5	<5	
J971824	Rock	11	0.33	0.056	31	15	0.16	76	<0.001	<20	0.65	<0.01	0.16	<2	<0.05	<1	<5	<5	<5	
J971825	Rock	4	28.74	0.011	2	2	1.32	16	<0.001	<20	0.12	<0.01	0.03	<2	0.07	<1	<5	<5	<5	
J971826	Rock	9	1.63	0.030	2	101	0.97	17	<0.001	<20	0.40	<0.01	0.04	<2	<0.05	<1	<5	<5	<5	
J971827	Rock	1	14.04	0.022	4	4	4.27	13	<0.001	<20	0.06	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
J971828	Rock	<1	0.05	0.011	1	15	0.02	12	<0.001	<20	0.08	0.02	0.01	<2	<0.05	<1	<5	<5	<5	
J971829	Rock	9	9.06	0.009	9	13	3.71	18	0.004	<20	0.34	<0.01	0.08	<2	<0.05	<1	<5	<5	<5	
J971830	Rock	1	1.32	0.035	4	7	0.13	47	<0.001	<20	0.23	0.05	0.01	<2	<0.05	<1	<5	<5	<5	
J971831	Rock	3	0.09	0.018	14	21	0.15	19	<0.001	<20	0.35	0.05	0.03	<2	<0.05	<1	<5	<5	<5	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

CERTIFICATE OF ANALYSIS WHI11001565.2

Method		WGHT	G6	7TD	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
Analyte		Wgt	Au	Ag	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi
Unit		kg	ppm	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		0.01	0.005	2	1	1	3	1	0.3	1	1	2	0.01	2	8	2	2	1	0.5	3	3
J971832	Rock	1.19	0.009	<2	4	108	11	102	<0.3	35	33	>10000	12.62	151	<8	<2	5	24	0.7	3	<3
J971833	Rock	0.78	0.008	<2	1	95	5	57	<0.3	21	11	179	4.89	31	<8	<2	5	1	<0.5	<3	<3
J971834	Rock	0.67	0.009	<2	2	145	25	69	<0.3	55	10	314	4.70	406	<8	<2	3	28	0.6	<3	<3
J971835	Rock	0.90	0.009	<2	<1	35	6	35	<0.3	16	3	130	1.97	145	<8	<2	<2	42	<0.5	<3	<3
J971836	Rock	1.17	0.007	<2	1	54	16	50	<0.3	34	16	3193	2.42	28	<8	<2	3	5	<0.5	<3	<3
J971837	Rock	0.66	0.007	<2	<1	2	6	49	<0.3	267	18	1602	3.60	32	14	<2	<2	247	<0.5	<3	<3
J971838	Rock	0.73	<0.005	<2	<1	5	4	27	<0.3	9	3	102	1.83	<2	<8	<2	4	4	<0.5	<3	<3
J971839	Rock	0.65	0.008	<2	<1	47	4	45	<0.3	26	7	110	2.39	<2	<8	<2	5	6	<0.5	<3	<3
J971840	Rock	0.49	0.007	<2	19	46	46	60	0.6	15	4	465	2.31	<2	<8	<2	10	74	<0.5	<3	<3
J971841	Rock	0.52	0.005	<2	<1	3	23	28	<0.3	2	1	324	0.73	<2	<8	<2	<2	21	<0.5	<3	<3
J971842	Rock	0.34	0.007	<2	2	12	8	47	<0.3	6	6	476	2.88	<2	<8	<2	7	53	<0.5	<3	<3
J971843	Rock	0.53	0.006	<2	<1	1	<3	<1	<0.3	3	1	270	1.49	<2	15	<2	<2	251	<0.5	<3	<3
J971844	Rock	0.88	<0.005	<2	<1	13	<3	3	<0.3	7	3	65	0.56	<2	<8	<2	<2	9	<0.5	<3	<3
J971845	Rock	0.88	0.008	16	44	28	5323	6	14.4	7	3	125	0.84	<2	<8	<2	4	9	1.4	<3	31
J971846	Rock	0.81	0.022	84	<1	65	>10000	<1	45.3	2	<1	26	0.45	<2	<8	<2	<2	3	22.9	10	169
J971847	Rock	0.65	<0.005	<2	9	144	176	62	0.7	93	20	614	3.70	<2	<8	<2	<2	110	<0.5	<3	<3
J971848	Rock Pulp	0.14	0.458	<2	9	44	5	50	<0.3	32	7	388	2.64	52	<8	<2	<2	36	<0.5	<3	<3
J971849	Rock	1.07	0.010	<2	<1	2	119	<1	<0.3	2	<1	192	0.42	<2	<8	<2	<2	34	<0.5	<3	<3
K948201	Rock	0.78	0.008	<2	124	91	101	19	<0.3	8	3	290	2.17	<2	<8	<2	8	20	<0.5	<3	<3
K948202	Rock	1.00	0.007	2	<1	3	139	6	0.9	4	2	624	0.66	<2	<8	<2	<2	454	<0.5	<3	<3
K948203	Rock	2.20	0.018	<2	8	4	51	233	0.6	14	1	302	1.00	<2	13	<2	<2	427	4.8	5	<3
K948204	Rock	0.63	0.009	<2	<1	2	21	8	<0.3	4	2	780	0.80	<2	<8	<2	<2	482	<0.5	<3	<3
K948205	Rock	1.27	0.010	<2	1	14	5	77	<0.3	14	7	113	2.90	<2	<8	<2	13	13	<0.5	<3	<3
K948206	Rock	0.37	1.077	35	3	73	16	104	32.3	3	4	192	3.62	7	<8	<2	2	46	<0.5	<3	19
K948208	Rock	0.63	<0.005	2	<1	<1	<3	2	<0.3	1964	95	552	4.01	<2	<8	<2	<2	1	<0.5	<3	<3
K948209	Rock	0.88	0.008	<2	<1	172	6	17	<0.3	1215	79	432	3.92	<2	<8	<2	<2	2	<0.5	<3	<3
K948210	Rock	0.32	0.013	<2	4	7	64	13	2.0	15	1	32	2.39	<2	<8	<2	<2	55	<0.5	<3	<3
K948211	Rock	0.81	0.014	<2	3	42	9	75	0.5	6	2	77	12.64	4	<8	<2	<2	26	<0.5	<3	<3
K948212	Rock	0.73	0.013	<2	1	17	11	11	0.7	5	<1	30	1.73	<2	<8	<2	<2	31	<0.5	<3	<3
K948213	Rock	0.75	0.019	<2	60	84	20	568	1.1	61	4	88	1.49	12	<8	<2	4	21	9.7	<3	<3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

CERTIFICATE OF ANALYSIS WHI11001565.2

	Method	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	7AR
	Analyte	V	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga	Pb
	Unit	ppm	%	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm	%
	MDL	1	0.01	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5	0.01
J971832	Rock	7	0.02	0.138	11	8	0.04	210	<0.001	<20	0.45	<0.01	0.14	<2	<0.05	<1	<5	<5	<5	
J971833	Rock	8	<0.01	0.049	11	11	0.27	44	0.001	<20	0.88	<0.01	0.16	<2	<0.05	<1	<5	<5	<5	
J971834	Rock	39	0.01	0.093	17	25	0.83	46	0.001	<20	1.75	<0.01	0.14	<2	<0.05	<1	<5	<5	5	
J971835	Rock	19	0.02	0.064	7	14	0.38	46	0.001	<20	0.92	<0.01	0.12	<2	<0.05	<1	<5	<5	<5	
J971836	Rock	8	0.01	0.026	11	13	0.30	191	<0.001	<20	0.62	<0.01	0.19	<2	<0.05	<1	<5	<5	<5	
J971837	Rock	69	3.99	0.047	2	568	3.93	35	0.003	<20	2.11	<0.01	0.02	<2	<0.05	<1	<5	13	<5	
J971838	Rock	4	0.04	0.018	9	11	0.07	26	<0.001	<20	0.36	<0.01	0.13	<2	<0.05	<1	<5	<5	<5	
J971839	Rock	19	0.11	0.041	13	27	0.88	57	0.011	<20	1.30	0.01	0.26	<2	<0.05	<1	<5	<5	<5	
J971840	Rock	177	0.50	0.078	22	88	1.84	271	0.137	<20	2.83	0.17	1.51	<2	0.54	<1	<5	11	11	
J971841	Rock	2	0.57	0.012	<1	12	0.20	18	0.001	<20	0.15	<0.01	0.01	<2	<0.05	<1	<5	<5	<5	
J971842	Rock	28	1.42	0.035	22	10	0.74	292	0.102	<20	1.97	0.20	0.76	<2	0.51	<1	<5	9	8	
J971843	Rock	9	18.97	0.005	3	2	8.00	59	<0.001	<20	0.08	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5	
J971844	Rock	1	0.26	0.009	<1	17	0.02	11	<0.001	<20	0.21	0.01	0.02	<2	0.05	<1	<5	<5	<5	
J971845	Rock	12	0.26	0.032	16	26	0.13	13	0.026	<20	0.20	0.01	0.05	<2	0.12	<1	<5	<5	<5	
J971846	Rock	<1	<0.01	0.001	<1	19	<0.01	3	<0.001	<20	0.02	<0.01	<0.01	<2	1.04	<1	<5	<5	<5	6.68
J971847	Rock	185	2.30	0.085	5	240	1.80	247	0.200	<20	5.18	0.28	1.53	<2	0.77	<1	<5	14	13	
J971848	Rock Pulp	50	1.28	0.067	5	27	0.56	102	0.094	<20	1.17	0.07	0.10	<2	0.10	<1	<5	<5	<5	
J971849	Rock	1	15.67	0.015	1	1	11.27	15	0.001	<20	0.02	<0.01	0.01	<2	<0.05	<1	<5	<5	<5	
K948201	Rock	43	0.42	0.070	18	66	0.42	42	0.121	<20	0.61	0.08	0.30	<2	0.32	<1	<5	<5	<5	
K948202	Rock	2	10.23	0.006	5	6	0.24	16	<0.001	<20	0.15	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
K948203	Rock	115	11.40	0.029	3	6	7.98	914	0.002	<20	0.08	0.01	0.04	<2	<0.05	<1	<5	<5	<5	
K948204	Rock	2	14.66	0.009	7	8	0.32	21	<0.001	<20	0.21	<0.01	0.03	<2	<0.05	<1	<5	<5	<5	
K948205	Rock	12	0.09	0.042	33	22	0.92	104	<0.001	<20	1.68	<0.01	0.18	<2	<0.05	<1	<5	<5	<5	
K948206	Rock	34	0.33	0.029	3	3	0.40	138	0.004	<20	0.77	0.04	0.18	<2	0.22	4	<5	<5	<5	
K948208	Rock	15	0.03	0.001	2	603	19.77	2	0.001	<20	0.30	<0.01	<0.01	<2	<0.05	<1	<5	7	<5	
K948209	Rock	35	0.47	0.007	1	478	7.33	8	0.047	<20	0.68	<0.01	0.04	<2	0.59	<1	<5	<5	<5	
K948210	Rock	96	0.17	0.132	5	37	0.15	219	0.022	<20	0.09	0.02	0.09	<2	0.67	<1	<5	<5	<5	
K948211	Rock	93	0.35	0.254	3	35	0.40	50	0.042	<20	0.46	0.01	0.05	<2	0.73	<1	<5	<5	<5	
K948212	Rock	40	0.22	0.065	2	25	0.07	93	0.017	<20	0.11	<0.01	0.03	<2	0.50	<1	<5	<5	<5	
K948213	Rock	200	0.16	0.025	5	31	0.32	292	0.042	<20	0.64	0.03	0.28	<2	0.71	<1	<5	<5	<5	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

CERTIFICATE OF ANALYSIS WHI11001565.2

Method		WGHT	G6	7TD	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
Analyte		Wgt	Au	Ag	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi
Unit		kg	ppm	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		0.01	0.005	2	1	1	3	1	0.3	1	1	2	0.01	2	8	2	2	1	0.5	3	3
K948214	Rock	0.52	0.025	<2	3	138	4	30	<0.3	9	6	139	2.20	4	<8	<2	<2	112	<0.5	<3	<3
K948215	Rock	0.57	0.008	<2	<1	2	18	50	<0.3	1	2	386	1.35	<2	<8	<2	14	7	<0.5	<3	<3
K948216	Rock	0.66	0.009	<2	<1	9	4	28	<0.3	8	5	1337	3.39	9	<8	<2	<2	128	<0.5	<3	<3
K948217	Rock	0.90	0.011	<2	<1	5	8	24	<0.3	3	4	2947	2.36	4	12	<2	<2	302	0.6	<3	<3
K948218	Rock	0.71	0.027	<2	<1	16	5	36	<0.3	6	6	1467	2.54	33	<8	<2	<2	77	<0.5	<3	<3
K948219	Rock	0.81	0.006	<2	1	15	32	58	<0.3	68	12	1652	4.36	90	19	<2	23	318	0.8	<3	<3
K948220	Rock	0.73	0.007	<2	3	144	6	109	<0.3	23	15	599	3.84	16	<8	<2	10	14	<0.5	<3	<3
K948221	Rock	0.31	0.017	<2	4	124	10	150	<0.3	25	19	321	4.57	12	<8	<2	14	20	<0.5	<3	<3
K948222	Rock	0.88	0.006	<2	3	85	5	173	<0.3	22	12	591	3.01	9	<8	<2	12	10	<0.5	<3	<3
K948223	Rock	0.86	0.010	<2	7	160	9	140	<0.3	31	24	872	4.38	19	<8	<2	11	12	<0.5	<3	<3
K948224	Rock	1.87	0.006	<2	5	140	5	93	<0.3	18	15	211	2.95	9	<8	<2	10	7	<0.5	<3	<3
K948225	Rock	1.37	0.010	<2	6	249	4	65	<0.3	17	20	234	2.63	10	<8	<2	7	4	<0.5	<3	<3
K948226	Rock	1.32	0.010	<2	3	223	5	88	<0.3	17	15	325	2.93	4	<8	<2	9	10	<0.5	<3	<3
K948227	Rock	0.78	0.007	<2	<1	36	29	33	<0.3	18	8	332	1.78	<2	<8	<2	3	181	<0.5	<3	<3
K948228	Rock	0.48	<0.005	<2	<1	4	17	30	<0.3	6	2	271	0.89	3	<8	<2	15	16	<0.5	<3	<3
K948229	Rock	0.61	0.008	<2	<1	89	4	42	<0.3	43	23	1137	3.93	4	<8	<2	<2	134	0.7	<3	<3
K948230	Rock	0.50	<0.005	<2	<1	108	4	57	<0.3	76	29	902	5.45	2	<8	<2	<2	86	0.7	<3	<3
K948231	Rock	1.76	0.014	<2	3	20	5	42	<0.3	9	15	253	4.45	5	<8	<2	2	97	<0.5	<3	<3
K948232	Rock	0.70	0.009	<2	3	21	4	44	<0.3	10	15	250	4.36	5	<8	<2	<2	92	0.6	<3	<3
K948233	Rock	0.27	0.006	<2	<1	1	<3	14	<0.3	12	5	3269	0.49	<2	14	<2	<2	230	<0.5	<3	<3
K948234	Rock	0.15	0.008	<2	1	3	15	45	<0.3	8	8	484	1.89	12	<8	<2	12	181	<0.5	<3	<3
K948235	Rock	0.80	0.005	<2	<1	67	4	39	<0.3	55	24	959	3.45	<2	<8	<2	<2	158	0.6	<3	<3
K948236	Rock	0.70	<0.005	<2	<1	108	4	52	<0.3	80	35	1108	4.48	<2	<8	<2	<2	95	0.7	<3	<3
K948237	Rock	0.64	0.006	<2	<1	119	<3	39	<0.3	49	20	713	4.03	3	<8	<2	2	33	0.6	<3	<3
K948238	Rock	0.62	0.006	<2	<1	36	5	31	<0.3	32	22	1227	6.27	3	<8	<2	<2	146	1.0	<3	<3
K948239	Rock	0.95	<0.005	<2	<1	99	9	146	<0.3	40	36	884	3.64	83	<8	<2	<2	29	<0.5	<3	<3
K948240	Rock	0.50	<0.005	<2	<1	74	<3	98	<0.3	54	41	1351	7.75	71	<8	<2	<2	19	<0.5	<3	<3
K948241	Rock	0.64	<0.005	<2	<1	37	5	91	<0.3	42	36	2547	8.25	114	<8	<2	<2	48	0.8	<3	<3
K948242	Rock Pulp	0.14	3.002	13	11	299	629	1102	11.5	70	20	882	5.16	3807	<8	<2	2	89	7.5	83	5
K948243	Rock	0.96	<0.005	<2	<1	<1	<3	<1	<0.3	2	<1	190	0.42	8	<8	<2	<2	33	<0.5	<3	<3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

CERTIFICATE OF ANALYSIS WHI11001565.2

Method		1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	7AR
Analyte		V	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga	Pb
Unit		ppm	%	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm	%
MDL		1	0.01	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5	0.01
K948214	Rock	39	0.23	0.020	3	19	0.81	150	0.071	<20	1.23	0.04	0.15	<2	<0.05	<1	<5	<5	<5	
K948215	Rock	12	0.09	0.030	33	3	0.26	317	0.076	<20	0.64	0.07	0.28	<2	<0.05	<1	<5	<5	<5	
K948216	Rock	16	8.07	0.024	7	5	1.96	88	<0.001	<20	0.27	0.01	0.09	<2	0.07	<1	<5	<5	<5	
K948217	Rock	14	22.08	0.010	9	2	1.19	218	<0.001	<20	0.12	<0.01	0.06	<2	<0.05	<1	<5	<5	<5	
K948218	Rock	16	7.42	0.023	8	4	0.97	83	<0.001	<20	0.21	<0.01	0.13	<2	0.06	<1	<5	<5	<5	
K948219	Rock	34	12.24	0.084	37	33	2.96	1581	<0.001	<20	0.25	<0.01	0.06	<2	0.06	<1	<5	5	<5	
K948220	Rock	45	0.27	0.041	33	23	0.21	126	<0.001	<20	0.98	0.01	0.12	<2	0.05	<1	<5	9	<5	
K948221	Rock	72	0.36	0.058	86	36	0.24	182	<0.001	<20	1.34	<0.01	0.16	<2	<0.05	<1	<5	13	<5	
K948222	Rock	43	0.22	0.039	50	27	0.16	82	0.003	<20	0.78	<0.01	0.09	<2	0.07	<1	<5	7	<5	
K948223	Rock	65	0.22	0.039	57	40	0.10	210	<0.001	<20	0.79	<0.01	0.05	<2	0.11	<1	<5	10	<5	
K948224	Rock	36	0.14	0.027	29	20	0.09	29	<0.001	<20	0.63	<0.01	0.04	<2	0.05	<1	<5	6	<5	
K948225	Rock	33	0.12	0.021	17	12	0.05	22	<0.001	<20	0.43	<0.01	0.06	<2	0.11	<1	<5	6	<5	
K948226	Rock	54	0.27	0.050	19	26	0.21	81	0.002	<20	0.91	0.01	0.14	<2	<0.05	<1	<5	10	<5	
K948227	Rock	14	4.02	0.023	8	20	1.02	18	0.002	<20	1.00	0.01	0.08	<2	<0.05	<1	<5	<5	<5	
K948228	Rock	4	0.11	0.019	24	2	0.04	51	<0.001	<20	0.36	0.02	0.18	<2	<0.05	<1	<5	<5	<5	
K948229	Rock	122	9.41	0.065	11	97	2.89	985	0.006	<20	0.59	<0.01	0.06	<2	<0.05	<1	<5	17	<5	
K948230	Rock	170	3.90	0.112	16	180	3.21	140	0.007	<20	2.74	<0.01	0.07	<2	<0.05	<1	<5	20	11	
K948231	Rock	22	1.21	0.286	6	<1	0.31	65	0.009	<20	1.26	0.03	0.30	<2	2.75	<1	<5	<5	<5	
K948232	Rock	20	1.53	0.290	5	<1	0.31	39	0.009	<20	1.21	0.03	0.28	<2	2.80	<1	<5	<5	<5	
K948233	Rock	3	8.65	0.005	6	6	0.39	2350	0.001	<20	0.10	<0.01	0.04	<2	0.08	<1	<5	<5	<5	
K948234	Rock	14	3.14	0.070	18	6	1.18	160	<0.001	<20	0.73	0.02	0.22	<2	0.24	<1	<5	<5	<5	
K948235	Rock	87	8.24	0.040	4	52	4.10	337	0.001	<20	0.46	0.01	0.17	<2	<0.05	<1	<5	13	<5	
K948236	Rock	184	7.28	0.101	14	170	2.95	59	0.007	<20	1.51	<0.01	0.06	<2	<0.05	<1	<5	27	7	
K948237	Rock	175	5.04	0.113	5	186	1.36	153	0.015	<20	0.59	<0.01	0.02	<2	<0.05	<1	<5	24	<5	
K948238	Rock	173	8.73	0.040	14	87	2.59	101	0.003	<20	1.02	<0.01	0.07	<2	<0.05	<1	<5	17	<5	
K948239	Rock	114	0.51	0.108	5	74	0.10	1352	<0.001	<20	0.98	<0.01	0.08	<2	0.08	7	<5	11	5	
K948240	Rock	145	0.71	0.050	4	92	0.22	1427	0.002	<20	0.71	<0.01	0.13	<2	0.10	>50	<5	26	<5	
K948241	Rock	155	5.06	0.037	3	65	1.98	865	<0.001	<20	0.53	<0.01	0.09	<2	0.15	33	<5	31	<5	
K948242	Rock Pulp	42	2.18	0.056	8	83	1.17	40	0.020	<20	1.03	0.04	0.19	3	2.09	2	<5	6	5	
K948243	Rock	2	16.25	0.014	1	1	10.99	16	<0.001	<20	0.02	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

CERTIFICATE OF ANALYSIS WHI11001565.2

Method	WGHT	G6	7TD	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
Analyte	Wgt	Au	Ag	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi
Unit	kg	ppm	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL	0.01	0.005	2	1	1	3	1	0.3	1	1	2	0.01	2	8	2	2	1	0.5	3	3
K948244 Rock	0.86	0.006	<2	14	24	8	498	2.3	4	<1	25	0.88	17	17	<2	<2	490	3.0	16	<3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

CERTIFICATE OF ANALYSIS WHI11001565.2

	Method	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	7AR
	Analyte	V	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga	Pb
	Unit	ppm	%	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm	%
	MDL	1	0.01	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5	0.01
K948244	Rock	1350	0.33	2.930	9	59	0.02	>10000	0.002	<20	3.47	<0.01	0.10	<2	<0.05	3	<5	<5	<5	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

QUALITY CONTROL REPORT WHI11001565.2

	Method	WGHT	G6	7TD	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
	Analyte	Wgt	Au	Ag	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi
	Unit	kg	ppm	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	0.01	0.005	2	1	1	3	1	0.3	1	1	2	0.01	2	8	2	2	1	0.5	3	3
Pulp Duplicates																					
J971805	Rock	0.99	0.032	<2	1	39	40	44	0.4	16	9	333	2.57	9	<8	<2	<2	7	<0.5	<3	<3
REP J971805	QC		0.034																		
J971816	Rock	0.44	0.008	<2	<1	89	18	469	<0.3	17	27	3798	7.94	<2	<8	<2	<2	28	1.5	<3	4
REP J971816	QC			<2																	
J971819	Rock	0.86	0.027	<2	<1	368	17	52	0.4	10	25	1950	4.26	<2	<8	<2	<2	71	0.6	<3	<3
REP J971819	QC				<1	378	15	53	0.5	11	25	1964	4.25	<2	<8	<2	<2	68	0.6	<3	<3
J971820	Rock	0.75	0.006	<2	<1	56	5	74	0.7	46	31	315	3.68	<2	<8	<2	<2	36	<0.5	<3	<3
REP J971820	QC		<0.005																		
K948219	Rock	0.81	0.006	<2	1	15	32	58	<0.3	68	12	1652	4.36	90	19	<2	23	318	0.8	<3	<3
REP K948219	QC			<2																	
K948221	Rock	0.31	0.017	<2	4	124	10	150	<0.3	25	19	321	4.57	12	<8	<2	14	20	<0.5	<3	<3
REP K948221	QC				4	124	8	149	<0.3	25	19	321	4.56	13	<8	<2	13	20	<0.5	<3	<3
K948228	Rock	0.48	<0.005	<2	<1	4	17	30	<0.3	6	2	271	0.89	3	<8	<2	15	16	<0.5	<3	<3
REP K948228	QC				<1	4	17	30	<0.3	6	2	271	0.90	3	<8	<2	16	16	<0.5	<3	<3
K948232	Rock	0.70	0.009	<2	3	21	4	44	<0.3	10	15	250	4.36	5	<8	<2	<2	92	0.6	<3	<3
REP K948232	QC		0.013																		
K948233	Rock	0.27	0.006	<2	<1	1	<3	14	<0.3	12	5	3269	0.49	<2	14	<2	<2	230	<0.5	<3	<3
REP K948233	QC			<2																	
Core Reject Duplicates																					
J971802	Rock	0.61	0.015	<2	<1	6	<3	47	<0.3	33	28	566	2.77	<2	<8	<2	<2	182	<0.5	<3	<3
DUP J971802	QC		0.014	<2	<1	6	<3	48	<0.3	36	29	592	2.92	<2	<8	<2	<2	126	<0.5	<3	<3
J971837	Rock	0.66	0.007	<2	<1	2	6	49	<0.3	267	18	1602	3.60	32	14	<2	<2	247	<0.5	<3	<3
DUP J971837	QC		0.006	<2	<1	2	5	46	<0.3	260	17	1539	3.47	32	<8	<2	<2	256	<0.5	<3	<3
K948224	Rock	1.87	0.006	<2	5	140	5	93	<0.3	18	15	211	2.95	9	<8	<2	10	7	<0.5	<3	<3
DUP K948224	QC		0.008	<2	4	131	6	87	<0.3	17	14	202	2.80	9	<8	<2	10	7	<0.5	<3	<3
Reference Materials																					
STD DS8	Standard				14	101	121	306	1.6	37	8	600	2.38	25	<8	<2	8	65	2.2	4	7
STD DS8	Standard				14	102	124	306	1.7	37	8	596	2.38	26	<8	<2	6	65	2.2	<3	5

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

QUALITY CONTROL REPORT WHI11001565.2

	Method	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	7AR
	Analyte	V	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga	Pb
	Unit	ppm	%	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm	%
	MDL	1	0.01	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5	0.01
Pulp Duplicates																				
J971805	Rock	3	0.05	0.023	4	15	0.11	23	0.003	<20	0.31	0.04	0.02	<2	<0.05	<1	<5	<5	<5	
REP J971805	QC																			
J971816	Rock	320	2.15	0.165	10	13	2.50	305	0.054	<20	2.52	0.02	0.36	<2	<0.05	<1	<5	16	11	
REP J971816	QC																			
J971819	Rock	66	5.04	0.103	6	4	0.79	193	0.015	<20	0.66	0.02	0.31	<2	0.36	<1	<5	10	<5	
REP J971819	QC	63	5.02	0.107	6	5	0.81	53	0.013	<20	0.63	0.02	0.30	<2	0.37	<1	<5	10	<5	
J971820	Rock	159	0.90	0.088	2	101	1.65	53	0.184	<20	2.44	0.15	1.13	<2	1.24	<1	<5	14	7	
REP J971820	QC																			
K948219	Rock	34	12.24	0.084	37	33	2.96	1581	<0.001	<20	0.25	<0.01	0.06	<2	0.06	<1	<5	5	<5	
REP K948219	QC																			
K948221	Rock	72	0.36	0.058	86	36	0.24	182	<0.001	<20	1.34	<0.01	0.16	<2	<0.05	<1	<5	13	<5	
REP K948221	QC	71	0.37	0.059	84	35	0.23	180	<0.001	<20	1.29	<0.01	0.15	<2	<0.05	<1	<5	13	<5	
K948228	Rock	4	0.11	0.019	24	2	0.04	51	<0.001	<20	0.36	0.02	0.18	<2	<0.05	<1	<5	<5	<5	
REP K948228	QC	4	0.11	0.020	24	2	0.04	51	<0.001	<20	0.36	0.02	0.18	<2	<0.05	<1	<5	<5	<5	
K948232	Rock	20	1.53	0.290	5	<1	0.31	39	0.009	<20	1.21	0.03	0.28	<2	2.80	<1	<5	<5	<5	
REP K948232	QC																			
K948233	Rock	3	8.65	0.005	6	6	0.39	2350	0.001	<20	0.10	<0.01	0.04	<2	0.08	<1	<5	<5	<5	
REP K948233	QC																			
Core Reject Duplicates																				
J971802	Rock	79	1.91	0.150	8	33	1.81	15	0.180	<20	2.23	0.02	0.03	<2	<0.05	<1	<5	<5	5	
DUP J971802	QC	79	1.70	0.140	8	29	1.95	19	0.162	<20	2.03	0.03	0.04	<2	<0.05	<1	<5	<5	<5	
J971837	Rock	69	3.99	0.047	2	568	3.93	35	0.003	<20	2.11	<0.01	0.02	<2	<0.05	<1	<5	13	<5	
DUP J971837	QC	67	4.08	0.046	2	562	3.92	30	0.003	<20	2.05	<0.01	0.02	<2	<0.05	<1	<5	12	<5	
K948224	Rock	36	0.14	0.027	29	20	0.09	29	<0.001	<20	0.63	<0.01	0.04	<2	0.05	<1	<5	6	<5	
DUP K948224	QC	33	0.14	0.026	28	19	0.08	27	<0.001	<20	0.59	<0.01	0.04	<2	0.05	<1	<5	5	<5	
Reference Materials																				
STD DS8	Standard	42	0.70	0.078	16	115	0.60	281	0.109	<20	0.90	0.08	0.40	<2	0.16	<1	<5	<5	<5	
STD DS8	Standard	41	0.69	0.077	16	114	0.60	282	0.110	<20	0.91	0.09	0.40	<2	0.16	<1	<5	<5	<5	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

QUALITY CONTROL REPORT WHI11001565.2

		WGHT	G6	7TD	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
		Wgt	Au	Ag	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi
		kg	ppm	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
		0.01	0.005	2	1	1	3	1	0.3	1	1	2	0.01	2	8	2	2	1	0.5	3	3
STD DS8	Standard				15	105	124	313	1.9	39	8	616	2.46	26	<8	<2	7	68	2.0	4	6
STD GC-7	Standard																				
STD GC-7	Standard																				
STD OREAS131B	Standard			34																	
STD OREAS153A	Standard			<2																	
STD OREAS131B	Standard			35																	
STD OREAS153A	Standard			2																	
STD OREAS131B	Standard			34																	
STD OREAS153A	Standard			<2																	
STD OREAS131B	Standard			33																	
STD OREAS153A	Standard			<2																	
STD OREAS45CA	Standard				<1	494	19	57	<0.3	252	91	895	15.95	4	<8	<2	7	14	<0.5	<3	<3
STD OREAS45CA	Standard				1	509	21	61	<0.3	254	91	899	15.71	3	<8	<2	7	15	<0.5	<3	<3
STD OREAS45CA	Standard				1	510	22	85	<0.3	261	94	902	15.84	5	<8	<2	7	14	<0.5	<3	<3
STD OXH82	Standard		1.291																		
STD OXH82	Standard		1.281																		
STD OXH82	Standard		1.287																		
STD OXH82	Standard		1.296																		
STD OXH82	Standard		1.211																		
STD OXK79	Standard		3.590																		
STD OXK79	Standard		3.575																		
STD OXK79	Standard		3.367																		
STD OXK79	Standard		3.672																		
STD OXK79	Standard		3.354																		
STD SU-1B	Standard			6																	
STD SU-1B	Standard			7																	
STD SU-1B	Standard			7																	
STD SU-1B	Standard			6																	
STD OXH82 Expected			1.278																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

QUALITY CONTROL REPORT WHI11001565.2

		1D V ppm 1	1D Ca % 0.01	1D P % 0.001	1D La ppm 1	1D Cr ppm 1	1D Mg % 0.01	1D Ba ppm 1	1D Ti % 0.001	1D B ppm 20	1D Al % 0.01	1D Na % 0.01	1D K % 0.01	1D W ppm 2	1D S % 0.05	1D Hg ppm 1	1D Tl ppm 5	1D Sc ppm 5	1D Ga ppm 5	7AR Pb % 0.01
STD DS8	Standard	43	0.72	0.079	16	121	0.61	288	0.107	<20	0.94	0.09	0.41	<2	0.16	<1	<5	<5	<5	
STD GC-7	Standard																			>10
STD GC-7	Standard																			>10
STD OREAS131B	Standard																			
STD OREAS153A	Standard																			
STD OREAS131B	Standard																			
STD OREAS153A	Standard																			
STD OREAS131B	Standard																			
STD OREAS153A	Standard																			
STD OREAS131B	Standard																			
STD OREAS153A	Standard																			
STD OREAS45CA	Standard	202	0.43	0.034	16	722	0.14	147	0.128	<20	3.74	<0.01	0.07	<2	<0.05	<1	<5	46	11	
STD OREAS45CA	Standard	200	0.42	0.036	16	730	0.14	156	0.119	<20	3.86	<0.01	0.07	<2	<0.05	<1	<5	47	5	
STD OREAS45CA	Standard	205	0.42	0.037	17	751	0.14	156	0.109	<20	3.92	<0.01	0.08	<2	<0.05	<1	<5	47	15	
STD OXH82	Standard																			
STD OXH82	Standard																			
STD OXH82	Standard																			
STD OXH82	Standard																			
STD OXH82	Standard																			
STD OXK79	Standard																			
STD OXK79	Standard																			
STD OXK79	Standard																			
STD OXK79	Standard																			
STD OXK79	Standard																			
STD SU-1B	Standard																			
STD SU-1B	Standard																			
STD SU-1B	Standard																			
STD SU-1B	Standard																			
STD OXH82 Expected																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

QUALITY CONTROL REPORT WHI11001565.2

		WGHT Wgt kg 0.01	G6 Au ppm 0.005	7TD Ag gm/t 2	1D Mo ppm 1	1D Cu ppm 1	1D Pb ppm 3	1D Zn ppm 1	1D Ag ppm 0.3	1D Ni ppm 1	1D Co ppm 1	1D Mn ppm 2	1D Fe % 0.01	1D As ppm 2	1D U ppm 8	1D Au ppm 2	1D Th ppm 2	1D Sr ppm 1	1D Cd ppm 0.5	1D Sb ppm 3	1D Bi ppm 3
STD OXK79 Expected			3.532																		
STD OREAS131B Expected				33.3																	
STD SU-1B Expected				6.4																	
STD DS8 Expected					13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	2.8	0.107	6.89	67.7	2.38	4.8	6.67
STD OREAS45CA Expected					1	494	20	60	0.275	240	92	943	15.69	3.8	1.2	0.043	7	15	0.1	0.13	0.19
STD GC-7 Expected																					
BLK	Blank		0.006																		
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank		0.006																		
BLK	Blank		<0.005																		
BLK	Blank		0.007																		
BLK	Blank			<2																	
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank		0.006																		
BLK	Blank		0.006																		
BLK	Blank			<2																	
BLK	Blank			<2																	
BLK	Blank			<2																	
BLK	Blank				<1	<1	<3	<1	<0.3	<1	<1	<2	<0.01	<2	<8	<2	<2	<1	<0.5	<3	<3
BLK	Blank				<1	<1	<3	<1	<0.3	<1	<1	<2	<0.01	<2	<8	<2	<2	<1	<0.5	<3	<3
BLK	Blank				<1	<1	<3	<1	<0.3	<1	<1	<2	<0.01	<2	<8	<2	<2	<1	<0.5	<3	<3
BLK	Blank																				
Prep Wash																					
G1	Prep Blank		0.007	<2	<1	1	4	45	<0.3	3	5	562	1.95	<2	<8	<2	6	74	<0.5	<3	<3
G1	Prep Blank		0.012	<2	<1	2	5	47	<0.3	3	5	559	2.01	<2	<8	<2	7	70	<0.5	<3	<3

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: October 28, 2011

QUALITY CONTROL REPORT WHI11001565.2

		1D V ppm 1	1D Ca % 0.01	1D P % 0.001	1D La ppm 1	1D Cr ppm 1	1D Mg % 0.01	1D Ba ppm 1	1D Ti % 0.001	1D B ppm 20	1D Al % 0.01	1D Na % 0.01	1D K % 0.01	1D W ppm 2	1D S % 0.05	1D Hg ppm 1	1D Tl ppm 5	1D Sc ppm 5	1D Ga ppm 5	7AR Pb % 0.01
STD OXK79 Expected																				
STD OREAS131B Expected																				
STD SU-1B Expected																				
STD DS8 Expected		41.1	0.7	0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.1679	0.192	5.4	2.3	4.7	
STD OREAS45CA Expected		215	0.4265	0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.021	0.03	0.07			
STD GC-7 Expected																				10.44
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank																			
BLK	Blank	<1	<0.01	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5	
BLK	Blank	<1	<0.01	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5	
BLK	Blank	<1	<0.01	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5	
BLK	Blank																			<0.01
Prep Wash																				
G1	Prep Blank	39	0.62	0.074	13	8	0.55	190	0.127	<20	1.06	0.10	0.49	<2	<0.05	<1	<5	<5	<5	
G1	Prep Blank	42	0.59	0.081	20	9	0.58	203	0.130	<20	1.03	0.10	0.50	<2	<0.05	<1	<5	<5	<5	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada

www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Submitted By: Andrew Caldwell
Receiving Lab: Canada-Whitehorse
Received: October 15, 2011
Report Date: November 09, 2011
Page: 1 of 6

CERTIFICATE OF ANALYSIS WHI11001715.2

CLIENT JOB INFORMATION

Project: LIVINGSTONE
Shipment ID: GPD2011LIV-004
P.O. Number
Number of Samples: 133

SAMPLE DISPOSAL

RTRN-PLP Return
RTRN-RJT Return

Acme does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

Method Code	Number of Samples	Code Description	Test Wgt (g)	Report Status	Lab
R200-250	130	Crush, split and pulverize 250 g rock to 200 mesh			WHI
G601	133	Fire Assay fusion Au by ICP-ES	30	Completed	VAN
1D01-1D02-1D03	133	1:1:1 Aqua Regia digestion ICP-ES analysis	0.5	Completed	VAN
7AR	3	1:1:1 Aqua Regia Digestion ICP-ES Finish	0.4	Completed	VAN

ADDITIONAL COMMENTS

Version 2 : Revised sample type.

Invoice To: Golden Predator Canada Corp.
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4
Canada

CC: Jack Cote
Linda Lewis

BRITISH COLUMBIA CERTIFIED ASSAYER
CLARENCE LEONG
GENERAL MANAGER

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Acme assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001715.2

Method		WGHT	G6	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V
Unit		kg	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		0.01	0.005	1	1	3	1	0.3	1	1	2	0.01	2	8	2	2	1	0.5	3	3	1
J971650	Rock	0.27	0.015	2	84	51	127	<0.3	20	22	2172	5.71	17	<8	<2	<2	68	1.5	<3	<3	218
J971651	Rock	0.60	<0.005	<1	37	6	30	<0.3	23	14	466	2.63	7	18	<2	<2	419	<0.5	<3	<3	85
J971652	Rock	0.81	0.024	<1	312	<3	77	<0.3	34	31	910	2.76	<2	<8	<2	<2	43	<0.5	<3	<3	71
J971653	Rock	0.45	<0.005	<1	191	4	61	<0.3	1	18	367	3.93	3	<8	<2	6	50	<0.5	<3	<3	139
J971654	Rock	0.34	<0.005	2	7	19	70	<0.3	539	32	1734	4.48	85	<8	<2	<2	46	1.1	<3	<3	66
J971655	Rock	1.00	<0.005	1	7	8	37	<0.3	10	3	685	2.87	3	<8	<2	<2	6	<0.5	<3	<3	5
J971656	Rock	0.28	<0.005	3	5	4	25	<0.3	11	6	781	1.26	6	<8	<2	6	5	<0.5	<3	<3	3
J971657	Rock	1.59	0.011	<1	33	20	73	<0.3	30	13	895	2.75	3	<8	<2	6	14	<0.5	<3	<3	11
J971658	Rock	0.83	<0.005	<1	6	<3	19	<0.3	9	3	471	1.60	4	<8	<2	8	3	<0.5	<3	<3	2
J971659	Rock	0.60	<0.005	<1	5	4	37	<0.3	12	5	971	1.49	5	<8	<2	<2	4	<0.5	<3	<3	3
J971660	Rock	0.79	0.007	<1	6	17	42	<0.3	25	11	1705	3.92	22	<8	<2	6	9	<0.5	<3	<3	3
J971661	Rock	0.16	<0.005	<1	47	10	70	<0.3	27	16	137	3.81	19	<8	<2	14	10	<0.5	<3	<3	11
J971662	Rock	0.52	0.006	<1	23	<3	112	<0.3	39	14	370	3.32	12	<8	<2	3	17	0.6	<3	<3	12
J971663	Rock	0.51	0.077	<1	7483	127	225	1.7	24	38	4327	6.80	2	<8	<2	<2	32	6.5	<3	4	120
J971664	Rock	1.45	0.009	5	354	320	85	0.9	145	49	2741	12.88	6	11	<2	2	62	0.5	<3	<3	7
J971665	Rock	0.59	<0.005	<1	12	<3	66	<0.3	7	2	515	2.82	2	<8	<2	10	13	<0.5	<3	<3	18
J971666	Rock	0.85	<0.005	<1	15	<3	7	<0.3	1	3	207	0.79	<2	<8	<2	8	19	<0.5	<3	<3	4
J971667	Rock	0.66	<0.005	<1	10	11	52	<0.3	16	10	525	1.90	14	<8	<2	4	7	<0.5	<3	<3	3
J971668	Rock	0.75	0.007	<1	9	61	45	<0.3	13	11	1536	0.94	29	<8	<2	5	7	<0.5	<3	<3	2
J971669	Rock	0.47	<0.005	<1	10	24	31	<0.3	8	5	860	1.36	52	<8	<2	4	4	<0.5	<3	<3	3
J971670	Rock	0.43	<0.005	<1	2	<3	3	<0.3	4	5	167	0.29	5	<8	<2	<2	2	<0.5	<3	<3	<1
J971671	Rock	0.57	<0.005	<1	83	10	73	<0.3	42	16	3096	5.31	45	<8	<2	<2	52	1.2	<3	<3	62
J971672	Rock	0.47	<0.005	<1	2	<3	9	<0.3	2	7	164	1.57	<2	<8	<2	8	20	<0.5	<3	<3	10
J971673	Rock Pulp	0.14	1.126	70	74	25	363	<0.3	80	5	1683	2.27	250	23	<2	3	181	2.4	4	4	167
J971674	Rock	0.94	0.005	<1	2	<3	9	<0.3	2	<1	191	0.41	3	10	<2	<2	37	<0.5	<3	<3	1
J971675	Rock	0.60	0.005	<1	3	<3	14	<0.3	1	3	171	2.40	<2	<8	<2	6	31	<0.5	<3	<3	25
J971676	Rock	0.96	<0.005	1	3	<3	6	<0.3	<1	4	86	2.54	<2	<8	<2	5	38	<0.5	<3	<3	19
J971677	Rock	0.96	<0.005	<1	1	<3	6	<0.3	<1	2	110	1.57	<2	<8	<2	8	7	<0.5	<3	<3	3
J971678	Rock	1.05	0.008	4	<1	3	<1	<0.3	<1	<1	16	0.64	<2	<8	<2	2	8	<0.5	<3	<3	<1
J971679	Rock	0.79	0.022	4	<1	11	1	<0.3	<1	<1	19	1.24	<2	<8	<2	2	9	<0.5	<3	<3	<1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001715.2

	Method	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	7AR
	Analyte	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga	Pb
	Unit	%	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5	0.01
J971650	Rock	5.49	0.108	7	48	2.64	29	0.033	<20	3.23	0.02	0.07	<2	<0.05	<1	<5	11	14	
J971651	Rock	5.45	0.166	23	33	0.74	10	0.152	<20	3.54	0.03	0.02	<2	<0.05	<1	<5	<5	12	
J971652	Rock	2.66	0.031	<1	95	1.80	13	0.230	<20	1.78	0.02	<0.01	<2	<0.05	<1	<5	6	<5	
J971653	Rock	0.82	0.101	12	3	0.93	73	0.149	<20	2.32	0.22	0.73	<2	0.92	<1	<5	11	8	
J971654	Rock	4.07	0.023	2	717	3.59	103	0.005	<20	1.92	0.01	0.10	<2	<0.05	<1	<5	12	7	
J971655	Rock	1.35	0.022	3	6	0.08	40	<0.001	<20	0.24	0.03	0.04	<2	<0.05	<1	<5	<5	<5	
J971656	Rock	0.46	0.019	15	7	0.06	97	<0.001	<20	0.35	0.02	0.17	<2	<0.05	<1	<5	<5	<5	
J971657	Rock	0.17	0.075	14	25	0.31	79	0.004	<20	0.86	0.04	0.14	<2	<0.05	<1	<5	<5	<5	
J971658	Rock	0.01	0.011	16	5	0.02	122	<0.001	<20	0.25	0.01	0.15	<2	<0.05	<1	<5	<5	<5	
J971659	Rock	0.03	0.011	4	16	0.09	36	0.001	<20	0.31	0.03	0.04	<2	<0.05	<1	<5	<5	<5	
J971660	Rock	2.79	0.004	15	7	0.07	84	<0.001	<20	0.13	<0.01	0.08	<2	<0.05	<1	<5	<5	<5	
J971661	Rock	0.08	0.039	36	13	0.28	310	0.001	<20	1.12	0.02	0.34	<2	<0.05	<1	<5	<5	<5	
J971662	Rock	2.35	0.040	7	4	0.10	182	<0.001	<20	0.39	0.04	0.17	<2	<0.05	<1	<5	<5	<5	
J971663	Rock	6.31	0.055	5	21	2.99	100	0.015	<20	0.77	0.02	0.19	<2	1.94	<1	<5	17	<5	
J971664	Rock	5.11	0.042	17	8	0.53	30	<0.001	<20	0.23	0.01	0.11	<2	<0.05	<1	<5	<5	<5	
J971665	Rock	0.40	0.015	36	4	1.22	188	0.107	<20	1.74	0.06	0.43	<2	<0.05	<1	<5	<5	15	
J971666	Rock	0.20	0.012	18	3	0.03	1280	0.001	<20	0.30	0.05	0.16	<2	0.06	<1	<5	<5	<5	
J971667	Rock	0.07	0.037	9	8	0.06	44	<0.001	<20	0.31	0.03	0.16	<2	<0.05	<1	<5	<5	<5	
J971668	Rock	0.05	0.024	9	10	0.02	36	<0.001	<20	0.15	0.02	0.10	<2	<0.05	<1	<5	<5	<5	
J971669	Rock	<0.01	0.015	10	10	0.02	53	<0.001	<20	0.21	<0.01	0.15	<2	<0.05	<1	<5	<5	<5	
J971670	Rock	<0.01	0.005	<1	11	<0.01	21	<0.001	<20	0.04	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
J971671	Rock	2.63	0.278	6	26	0.16	243	<0.001	<20	0.66	0.04	0.15	<2	0.14	<1	<5	11	<5	
J971672	Rock	0.06	0.018	25	2	0.45	227	0.058	<20	0.81	0.03	0.34	<2	0.14	<1	<5	<5	<5	
J971673	Rock Pulp	16.03	0.106	14	28	3.20	106	0.002	<20	0.61	<0.01	0.16	8	0.74	2	<5	<5	<5	
J971674	Rock	17.55	0.015	1	<1	11.66	19	0.001	<20	0.03	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
J971675	Rock	0.07	0.021	14	2	0.38	253	0.122	<20	0.75	0.06	0.36	<2	0.29	<1	<5	<5	<5	
J971676	Rock	0.16	0.019	10	4	0.18	187	0.112	<20	0.33	0.08	0.05	<2	1.00	<1	<5	<5	<5	
J971677	Rock	0.01	0.012	14	2	0.23	102	0.091	<20	0.46	0.06	0.14	<2	0.12	<1	<5	<5	<5	
J971678	Rock	0.01	0.003	11	6	<0.01	271	0.001	<20	0.10	0.11	0.01	<2	0.15	<1	<5	<5	<5	
J971679	Rock	<0.01	0.005	15	5	<0.01	353	0.002	<20	0.13	0.11	0.04	<2	0.17	<1	<5	<5	<5	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001715.2

Method		WGHT	G6	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V
Unit		kg	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		0.01	0.005	1	1	3	1	0.3	1	1	2	0.01	2	8	2	2	1	0.5	3	3	1
J971680	Rock	0.88	<0.005	1	1	5	1	<0.3	<1	1	27	2.58	<2	<8	<2	5	12	<0.5	<3	<3	3
J971681	Rock	0.68	0.007	3	2	7	<1	<0.3	<1	<1	25	2.62	<2	<8	<2	4	17	<0.5	<3	<3	2
J971682	Rock	0.87	0.012	32	2	12	1	<0.3	<1	6	12	2.79	2	<8	<2	5	6	<0.5	<3	<3	1
J971683	Rock	1.13	<0.005	2	1	5	<1	<0.3	<1	<1	15	2.84	<2	<8	<2	7	20	<0.5	<3	<3	2
J971684	Rock	0.47	0.010	<1	307	129	522	0.4	40	44	6066	6.66	<2	<8	<2	<2	10	3.0	<3	6	167
J971685	Rock	0.41	<0.005	<1	192	20	133	<0.3	10	7	1625	7.51	<2	<8	<2	3	16	0.6	<3	<3	165
J971686	Rock	1.23	0.016	1	495	72	381	0.5	11	2	1355	7.81	<2	<8	2	<2	27	0.7	<3	7	187
J971687	Rock	1.28	<0.005	<1	150	7	685	<0.3	23	28	3637	5.55	<2	<8	<2	3	31	2.2	<3	<3	130
J971688	Rock	0.54	<0.005	2	19	11	9	<0.3	<1	2	43	1.82	<2	<8	<2	11	38	<0.5	<3	<3	5
J971689	Rock	0.78	<0.005	<1	6	21	16	<0.3	13	3	239	0.56	<2	<8	<2	6	37	<0.5	<3	<3	9
J971690	Rock	0.91	<0.005	<1	13	15	21	<0.3	17	6	203	0.79	<2	<8	<2	5	28	<0.5	<3	<3	10
J971691	Rock	0.86	<0.005	1	51	11	8	<0.3	1	3	67	0.83	<2	<8	<2	<2	65	<0.5	<3	<3	6
J971692	Rock	0.59	<0.005	33	136	13	19	1.4	25	5	52	1.89	<2	21	<2	<2	122	<0.5	<3	<3	317
J971693	Rock	0.78	<0.005	<1	<1	3	3	<0.3	4	3	2233	2.46	5	18	<2	<2	211	0.5	<3	<3	2
J971694	Rock	0.46	<0.005	<1	2	5	7	<0.3	9	7	3797	2.63	4	14	<2	<2	224	0.6	<3	<3	3
J971695	Rock	0.23	0.007	<1	4	<3	11	<0.3	11	6	531	1.97	147	<8	<2	<2	43	<0.5	<3	<3	3
J971696	Rock	0.32	<0.005	<1	1	<3	2	<0.3	4	2	3103	2.24	10	19	<2	<2	217	<0.5	<3	<3	2
J971697	Rock	0.34	<0.005	<1	<1	<3	<1	<0.3	<1	<1	180	1.29	6	11	<2	<2	237	<0.5	<3	<3	<1
J971698	Rock	0.69	<0.005	<1	7	30	5	<0.3	7	3	2238	2.84	5	13	<2	<2	193	0.6	<3	<3	2
J971699	Rock	0.38	<0.005	<1	<1	9	22	<0.3	5	2	2000	1.86	<2	<8	<2	<2	60	<0.5	<3	<3	1
J971700	Rock	0.90	<0.005	<1	2	<3	4	<0.3	4	2	627	2.15	5	17	<2	<2	223	<0.5	<3	<3	3
J971701	Rock	0.58	0.006	<1	44	36	33	0.6	16	6	123	3.11	16	<8	<2	<2	22	<0.5	<3	<3	13
J971702	Rock	0.64	<0.005	<1	58	32	25	<0.3	11	7	1565	1.70	2	<8	<2	4	20	<0.5	<3	<3	3
J971703	Rock	0.21	<0.005	<1	49	80	96	<0.3	35	18	3741	4.79	10	<8	<2	4	5	0.9	<3	<3	5
J971704	Rock	0.50	<0.005	<1	19	22	78	<0.3	35	11	547	2.39	62	<8	<2	6	14	<0.5	<3	<3	8
J971705	Rock	0.68	<0.005	<1	56	22	51	<0.3	65	49	894	4.69	9	<8	<2	17	8	<0.5	<3	<3	9
J971706	Rock	0.99	0.014	<1	217	<3	125	<0.3	60	47	2465	3.14	<2	<8	<2	<2	9	<0.5	<3	<3	5
J971707	Rock	0.41	<0.005	2	115	30	256	<0.3	112	16	531	9.39	100	<8	<2	<2	<1	1.3	<3	<3	90
J971708	Rock	0.86	<0.005	1	47	32	171	<0.3	84	17	449	5.25	36	<8	<2	<2	1	0.5	<3	<3	83
J971709	Rock	0.58	0.006	<1	123	10	58	<0.3	16	6	206	6.34	4	<8	<2	8	3	<0.5	4	<3	19

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001715.2

	Method	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	7AR
	Analyte	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga	Pb
	Unit	%	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5	0.01
J971680	Rock	0.02	0.018	17	3	0.02	324	0.026	<20	0.18	0.11	0.37	<2	0.77	<1	<5	<5	<5	
J971681	Rock	0.01	0.016	25	2	0.03	339	0.019	<20	0.22	0.14	0.46	<2	0.93	<1	<5	<5	<5	
J971682	Rock	<0.01	0.005	6	2	0.02	50	0.001	<20	0.16	0.04	0.15	<2	2.50	<1	<5	<5	<5	
J971683	Rock	0.02	0.023	30	3	0.01	267	0.030	<20	0.12	0.13	0.40	<2	0.98	<1	<5	<5	<5	
J971684	Rock	0.32	0.114	9	53	4.15	250	0.023	<20	4.32	<0.01	0.08	<2	<0.05	<1	<5	22	16	
J971685	Rock	0.19	0.102	7	17	3.31	361	0.329	<20	3.44	0.02	0.17	<2	0.36	<1	<5	12	7	
J971686	Rock	0.21	0.116	15	17	3.15	375	0.122	<20	3.48	0.04	0.27	<2	0.59	<1	<5	13	14	
J971687	Rock	1.00	0.164	18	15	3.23	202	0.099	<20	3.41	<0.01	0.14	<2	<0.05	<1	<5	10	11	
J971688	Rock	0.01	0.017	20	3	0.07	215	0.005	<20	0.22	0.04	0.16	<2	0.59	<1	<5	<5	<5	
J971689	Rock	0.74	0.063	16	9	0.15	43	0.069	<20	0.53	0.01	0.13	<2	<0.05	<1	<5	<5	<5	
J971690	Rock	0.56	0.063	13	9	0.18	62	0.058	<20	0.52	0.02	0.22	<2	<0.05	<1	<5	<5	<5	
J971691	Rock	0.30	0.065	1	3	0.05	85	0.027	<20	0.40	0.02	0.16	<2	<0.05	<1	<5	<5	<5	
J971692	Rock	2.51	0.191	5	50	0.19	50	0.098	<20	3.30	0.11	0.14	<2	0.67	<1	<5	<5	10	
J971693	Rock	17.22	0.008	6	2	6.07	14	<0.001	<20	0.09	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
J971694	Rock	21.34	0.004	9	3	6.80	16	<0.001	<20	0.11	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
J971695	Rock	31.55	0.007	2	2	1.02	16	<0.001	<20	0.17	<0.01	<0.01	<2	0.08	<1	<5	<5	<5	
J971696	Rock	21.48	0.005	10	2	6.84	20	<0.001	<20	0.12	<0.01	0.01	<2	<0.05	<1	<5	<5	<5	
J971697	Rock	21.26	0.002	1	<1	8.69	10	<0.001	<20	0.04	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5	
J971698	Rock	17.22	0.009	6	2	6.00	12	<0.001	<20	0.10	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
J971699	Rock	5.41	0.050	4	5	2.77	13	<0.001	<20	0.04	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
J971700	Rock	22.59	0.005	4	3	5.85	15	<0.001	<20	0.09	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
J971701	Rock	0.28	0.087	4	8	0.36	39	0.001	<20	0.67	<0.01	0.14	<2	<0.05	<1	<5	<5	<5	
J971702	Rock	1.28	0.043	10	10	0.15	24	0.004	<20	0.30	0.04	0.04	<2	<0.05	<1	<5	<5	<5	
J971703	Rock	0.04	0.009	9	5	0.11	56	<0.001	<20	0.64	<0.01	0.03	<2	<0.05	<1	<5	<5	<5	
J971704	Rock	1.17	0.061	19	12	0.70	68	0.001	<20	1.10	<0.01	0.19	<2	<0.05	<1	<5	<5	<5	
J971705	Rock	0.11	0.061	31	74	0.45	40	0.003	<20	1.01	0.04	0.08	<2	0.32	<1	<5	<5	<5	
J971706	Rock	0.08	0.050	3	14	0.69	22	0.002	<20	1.11	<0.01	0.10	<2	<0.05	<1	<5	<5	<5	
J971707	Rock	<0.01	0.208	3	228	1.77	47	0.004	<20	2.82	<0.01	0.11	<2	<0.05	<1	<5	16	6	
J971708	Rock	0.01	0.093	5	193	1.82	48	0.003	<20	2.81	<0.01	0.11	<2	<0.05	<1	<5	16	7	
J971709	Rock	<0.01	0.085	17	15	0.35	49	0.002	<20	1.25	<0.01	0.18	<2	<0.05	<1	<5	<5	5	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001715.2

Method		WGHT	G6	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V
Unit		kg	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		0.01	0.005	1	1	3	1	0.3	1	1	2	0.01	2	8	2	2	1	0.5	3	3	1
J971710	Rock	0.21	<0.005	2	90	13	59	<0.3	47	29	2195	4.80	34	<8	<2	<2	2	<0.5	<3	<3	31
J971711	Rock	0.30	<0.005	1	67	<3	183	<0.3	35	11	408	11.22	17	<8	<2	7	2	<0.5	<3	<3	10
J971712	Rock	0.57	<0.005	<1	3	<3	66	<0.3	35	13	726	2.86	<2	<8	<2	7	3	<0.5	<3	<3	9
J971713	Rock	0.38	<0.005	<1	12	6	15	<0.3	6	4	537	0.96	<2	<8	<2	3	2	<0.5	<3	<3	3
J971714	Rock	1.49	<0.005	<1	6	<3	6	<0.3	3	2	120	0.59	<2	<8	<2	<2	<1	<0.5	<3	<3	2
J971715	Rock	1.03	<0.005	<1	5	8	47	<0.3	16	3	198	1.16	14	<8	<2	<2	37	3.9	<3	<3	4
J971716	Rock	0.46	<0.005	<1	2	6	7	<0.3	3	<1	175	0.29	2	<8	<2	<2	5	<0.5	<3	<3	2
J971717	Rock	0.89	0.051	<1	8	9	22	<0.3	12	7	611	1.39	16	<8	<2	<2	3	<0.5	<3	<3	2
J971718	Rock	1.07	0.007	<1	1	<3	13	<0.3	5	2	1726	1.16	2	<8	<2	3	4	<0.5	<3	<3	3
J971719	Rock	0.74	<0.005	<1	109	8	109	<0.3	166	32	3034	6.29	24	<8	<2	4	79	1.1	<3	<3	152
J971720	Rock	0.63	<0.005	<1	14	14	46	<0.3	17	6	422	1.72	2	<8	<2	8	120	<0.5	<3	<3	11
J971721	Rock	0.87	<0.005	<1	10	<3	322	1.5	<1	<1	37	1.21	5	12	<2	6	3	5.1	<3	4	<1
J971722	Rock	0.70	<0.005	22	123	>10000	10	88.6	22	6	111	1.75	<2	<8	<2	2	14	10.5	5	187	5
J971723	Rock	0.71	<0.005	8	41	283	102	0.8	38	8	474	1.67	<2	<8	<2	4	34	2.1	<3	<3	101
J971724	Rock Pulp	0.14	3.020	12	327	699	1186	11.3	77	20	940	5.81	4134	<8	<2	<2	97	8.4	81	<3	46
J971725	Rock	0.83	<0.005	<1	3	72	6	0.3	2	<1	210	0.43	37	<8	<2	<2	37	<0.5	<3	<3	<1
J971726	Rock	1.21	<0.005	50	97	4163	31	10.6	22	5	411	1.94	<2	<8	<2	3	15	4.2	<3	18	15
J971727	Rock	1.82	<0.005	<1	19	>10000	<1	44.0	<1	<1	19	0.26	<2	<8	<2	<2	<1	6.7	<3	101	<1
J971728	Rock	0.57	<0.005	101	89	757	24	2.6	5	1	301	1.96	<2	<8	<2	6	20	<0.5	<3	4	26
J971729	Rock	1.12	<0.005	5	21	16	20	<0.3	9	2	148	0.99	<2	<8	<2	<2	31	<0.5	<3	<3	30
J971730	Rock	0.55	0.016	53	93	>10000	9	29.9	19	4	142	1.08	<2	<8	<2	2	10	4.6	4	53	23
J971731	Rock	0.80	<0.005	4	27	177	152	0.8	26	5	280	1.94	<2	<8	<2	<2	29	3.2	<3	<3	26
J971732	Rock	0.75	<0.005	7	6	57	115	<0.3	25	5	528	1.56	3	<8	<2	<2	196	1.5	4	<3	53
J971733	Rock	0.67	<0.005	4	32	21	88	0.3	17	3	35	0.88	<2	<8	<2	3	92	0.9	<3	<3	90
J971734	Rock	0.84	<0.005	3	13	25	121	1.2	17	11	373	0.86	3	<8	<2	<2	118	4.6	4	<3	34
J971735	Rock	0.72	<0.005	1	<1	<3	22	<0.3	389	62	554	6.96	<2	<8	<2	<2	<1	0.7	<3	<3	76
J971736	Rock	0.95	<0.005	2	33	<3	16	<0.3	1432	71	333	2.79	<2	<8	<2	<2	1	<0.5	<3	<3	22
J971737	Rock	0.69	<0.005	<1	5	<3	17	<0.3	5	<1	48	0.61	<2	<8	<2	<2	8	<0.5	<3	<3	21
J971738	Rock	0.72	0.005	2	14	11	11	2.4	4	<1	42	3.81	<2	<8	<2	<2	17	<0.5	<3	<3	80
J971739	Rock	0.65	<0.005	7	20	9	34	0.5	7	1	224	2.29	<2	<8	<2	4	9	0.5	<3	<3	160

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001715.2

	Method	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	7AR
	Analyte	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga	Pb
	Unit	%	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5	0.01
J971710	Rock	<0.01	0.181	6	97	0.29	58	0.002	<20	1.24	<0.01	0.18	<2	<0.05	<1	<5	6	5	
J971711	Rock	<0.01	0.118	15	10	0.02	43	<0.001	<20	0.53	<0.01	0.16	<2	<0.05	<1	<5	<5	<5	
J971712	Rock	<0.01	0.030	17	13	0.50	72	0.002	<20	1.23	<0.01	0.23	<2	<0.05	<1	<5	<5	<5	
J971713	Rock	<0.01	0.016	9	16	0.09	19	<0.001	<20	0.24	<0.01	0.07	<2	<0.05	<1	<5	<5	<5	
J971714	Rock	<0.01	0.009	6	16	0.02	11	<0.001	<20	0.11	<0.01	0.05	<2	<0.05	<1	<5	<5	<5	
J971715	Rock	9.67	0.030	3	8	1.52	42	<0.001	<20	0.19	<0.01	0.08	<2	<0.05	<1	<5	<5	<5	
J971716	Rock	0.98	0.010	1	5	0.56	15	0.002	<20	0.11	<0.01	0.03	<2	<0.05	<1	<5	<5	<5	
J971717	Rock	0.14	0.036	3	8	0.02	55	<0.001	<20	0.16	<0.01	0.10	<2	0.08	<1	<5	<5	<5	
J971718	Rock	0.01	0.017	9	9	0.07	39	<0.001	<20	0.24	<0.01	0.10	<2	<0.05	<1	<5	<5	<5	
J971719	Rock	2.96	0.362	22	135	2.24	104	0.004	<20	3.02	<0.01	0.08	<2	<0.05	<1	<5	12	12	
J971720	Rock	5.12	0.053	20	17	0.11	37	<0.001	<20	0.33	<0.01	0.15	<2	<0.05	<1	<5	<5	<5	
J971721	Rock	0.14	0.068	5	4	0.02	37	0.001	<20	0.40	0.02	0.29	<2	0.82	<1	<5	<5	<5	
J971722	Rock	0.11	0.020	4	15	0.07	20	0.017	<20	0.29	0.05	0.08	<2	0.63	<1	<5	<5	<5	3.17
J971723	Rock	0.64	0.036	7	44	0.52	82	0.055	<20	1.79	0.09	0.34	<2	0.32	<1	<5	<5	<5	
J971724	Rock Pulp	2.31	0.058	8	95	1.26	83	0.022	<20	1.14	0.05	0.21	5	2.20	2	<5	6	<5	
J971725	Rock	17.15	0.013	1	<1	11.29	11	<0.001	<20	<0.01	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5	
J971726	Rock	0.37	0.028	7	33	0.35	66	0.099	<20	0.56	0.07	0.23	<2	0.19	<1	<5	<5	<5	
J971727	Rock	<0.01	<0.001	<1	21	<0.01	2	<0.001	<20	<0.01	<0.01	<0.01	<2	0.24	<1	<5	<5	<5	1.32
J971728	Rock	0.38	0.092	11	35	0.54	64	0.108	<20	0.74	0.10	0.44	<2	0.35	<1	<5	<5	<5	
J971729	Rock	0.54	0.035	4	22	0.33	69	0.031	<20	0.96	0.06	0.24	<2	0.11	<1	<5	<5	<5	
J971730	Rock	0.21	0.029	6	29	0.14	22	0.034	<20	0.23	0.03	0.07	<2	0.38	<1	<5	<5	<5	1.83
J971731	Rock	1.91	0.140	7	13	0.25	116	0.001	<20	0.35	<0.01	0.13	<2	<0.05	<1	<5	<5	<5	
J971732	Rock	7.02	0.015	3	7	3.54	196	<0.001	<20	0.16	<0.01	0.08	<2	<0.05	<1	<5	<5	<5	
J971733	Rock	1.52	0.722	14	29	0.06	151	0.003	<20	0.59	0.01	0.18	<2	<0.05	<1	<5	<5	<5	
J971734	Rock	6.00	0.024	4	8	1.86	115	<0.001	<20	0.30	0.02	0.05	<2	<0.05	<1	<5	<5	<5	
J971735	Rock	0.05	0.010	<1	202	8.68	2	0.020	<20	1.50	<0.01	0.04	2	<0.05	<1	<5	15	<5	
J971736	Rock	0.05	0.006	<1	805	7.66	6	0.008	<20	0.81	<0.01	0.02	<2	0.25	<1	<5	<5	<5	
J971737	Rock	0.27	0.080	1	19	0.11	9	0.004	<20	0.06	<0.01	<0.01	<2	0.19	<1	<5	<5	<5	
J971738	Rock	0.10	0.104	2	25	0.09	39	0.014	<20	0.10	<0.01	0.03	<2	0.60	<1	<5	<5	<5	
J971739	Rock	0.11	0.074	6	58	1.00	103	0.086	<20	0.99	0.03	0.63	<2	0.71	<1	<5	<5	<5	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001715.2

Method		WGHT	G6	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V
Unit		kg	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		0.01	0.005	1	1	3	1	0.3	1	1	2	0.01	2	8	2	2	1	0.5	3	3	1
J971740	Rock	0.37	<0.005	31	114	7	585	<0.3	233	17	483	3.98	6	<8	<2	<2	23	6.4	<3	<3	444
J971741	Rock	1.30	0.005	17	47	<3	430	<0.3	35	7	252	2.24	5	<8	<2	<2	6	6.0	<3	<3	164
J971742	Rock	1.19	<0.005	<1	10	<3	58	<0.3	69	33	870	4.72	<2	<8	<2	<2	73	0.7	<3	<3	172
J971743	Rock	0.95	<0.005	<1	134	<3	59	<0.3	10	8	355	2.12	3	<8	<2	2	112	<0.5	<3	<3	47
J971744	Rock	0.75	<0.005	<1	15	4	67	<0.3	9	12	796	3.55	6	<8	<2	2	84	<0.5	<3	<3	111
J971745	Rock	0.53	<0.005	<1	1	3	27	<0.3	1	<1	548	0.76	<2	<8	<2	17	8	<0.5	<3	<3	4
J971746	Rock	0.53	0.008	<1	25	<3	32	<0.3	13	6	766	2.25	24	<8	<2	<2	26	<0.5	<3	<3	12
J971747	Rock	0.61	<0.005	<1	5	10	84	<0.3	11	10	1936	2.91	2	<8	<2	<2	173	0.8	<3	<3	28
J971748	Rock	0.59	<0.005	<1	8	6	90	<0.3	14	12	2135	3.53	<2	<8	<2	<2	180	1.0	<3	<3	26
J971749	Rock	0.62	<0.005	<1	4	5	30	<0.3	4	5	2327	3.75	15	15	<2	<2	255	0.7	<3	<3	13
J971750	Rock	0.46	<0.005	<1	7	4	61	<0.3	9	9	1999	2.94	25	<8	<2	<2	97	0.8	<3	<3	26
J971751	Rock	0.22	0.421	<1	7	16	41	<0.3	9	11	1884	4.67	3653	15	<2	<2	204	0.8	11	<3	14
J971752	Rock	0.56	<0.005	<1	68	<3	147	<0.3	22	17	625	6.91	13	<8	<2	3	8	<0.5	<3	<3	123
J971753	Rock	0.87	<0.005	<1	26	34	51	<0.3	53	13	1321	3.80	95	<8	<2	48	175	0.5	3	<3	37
J971754	Rock	0.72	<0.005	1	28	27	36	<0.3	65	14	1778	4.49	148	17	<2	48	376	0.8	8	3	32
J971755	Rock	1.03	<0.005	2	3	18	36	<0.3	6	6	4830	2.18	<2	11	<2	<2	407	1.1	<3	<3	34
J971756	Rock	1.06	<0.005	1	41	8	97	<0.3	22	19	1219	3.69	3	<8	<2	8	137	0.5	<3	<3	53
J971757	Rock	1.00	<0.005	1	38	6	86	<0.3	21	16	1190	3.58	<2	<8	<2	10	119	<0.5	<3	<3	62
J971758	Rock	0.25	<0.005	4	61	3	92	<0.3	19	14	442	3.30	3	<8	<2	5	16	<0.5	<3	<3	52
J971759	Rock	0.71	<0.005	<1	2	<3	4	<0.3	2	<1	94	0.40	<2	<8	<2	<2	2	<0.5	<3	<3	1
J971760	Rock	0.38	<0.005	<1	1	12	52	<0.3	4	2	280	1.01	2	<8	<2	17	9	<0.5	<3	<3	4
J971761	Rock	0.51	<0.005	<1	32	21	21	<0.3	26	9	785	2.23	<2	14	<2	4	205	<0.5	<3	<3	6
J971762	Rock	0.54	<0.005	<1	7	23	33	<0.3	12	4	521	1.12	<2	<8	<2	<2	69	<0.5	<3	<3	4
J971763	Rock	0.33	<0.005	<1	1	20	24	<0.3	5	3	330	0.73	<2	<8	<2	18	12	<0.5	<3	<3	5
J971764	Rock	0.50	<0.005	<1	51	6	28	<0.3	31	22	1253	4.44	3	14	<2	<2	281	1.0	<3	<3	121
J971765	Rock	0.71	<0.005	<1	125	6	60	<0.3	43	24	878	4.32	2	<8	<2	3	59	<0.5	<3	<3	141
J971766	Rock	0.91	<0.005	<1	72	6	39	<0.3	39	18	856	3.47	2	12	<2	<2	269	<0.5	<3	<3	138
J971767	Rock	1.05	<0.005	<1	69	5	43	<0.3	43	25	1142	4.12	4	18	<2	<2	254	0.9	<3	<3	77
J971768	Rock	0.70	<0.005	<1	53	4	43	<0.3	46	23	1114	4.59	3	<8	<2	<2	82	0.6	<3	<3	191
J971769	Rock	0.45	<0.005	<1	33	<3	23	<0.3	14	10	629	1.84	<2	<8	<2	<2	29	<0.5	<3	<3	49

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001715.2

	Method	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	7AR
	Analyte	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga	Pb
	Unit	%	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5	0.01
J971740	Rock	0.27	0.066	3	735	3.86	46	0.126	<20	3.12	0.03	1.58	<2	2.14	<1	<5	<5	<5	
J971741	Rock	0.23	0.063	3	25	0.71	216	0.065	<20	1.06	0.06	0.44	<2	1.20	<1	<5	<5	<5	
J971742	Rock	3.56	0.066	3	238	3.72	44	0.106	<20	3.01	0.04	0.03	<2	<0.05	<1	<5	22	<5	
J971743	Rock	0.59	0.147	12	19	0.92	141	0.042	<20	1.41	0.05	0.16	<2	<0.05	<1	<5	<5	<5	
J971744	Rock	3.54	0.119	9	15	0.87	89	0.002	<20	0.99	<0.01	0.15	<2	<0.05	<1	<5	14	<5	
J971745	Rock	0.11	0.007	14	1	0.13	72	0.002	<20	0.85	0.03	0.18	<2	<0.05	<1	<5	<5	<5	
J971746	Rock	1.41	0.010	7	5	0.52	213	<0.001	<20	0.23	<0.01	0.08	<2	0.08	<1	<5	<5	<5	
J971747	Rock	10.23	0.003	12	3	2.76	72	<0.001	<20	0.25	<0.01	0.04	3	<0.05	<1	<5	<5	<5	
J971748	Rock	12.29	0.008	15	3	2.17	90	<0.001	<20	0.20	<0.01	0.06	<2	<0.05	<1	<5	<5	<5	
J971749	Rock	10.45	0.018	7	3	3.39	60	<0.001	<20	0.18	<0.01	0.11	<2	<0.05	<1	<5	<5	<5	
J971750	Rock	14.31	0.019	19	3	0.51	81	<0.001	<20	0.23	<0.01	0.11	<2	0.07	<1	<5	<5	<5	
J971751	Rock	13.65	0.030	6	<1	1.10	115	<0.001	<20	0.28	<0.01	0.13	<2	0.14	<1	<5	<5	<5	
J971752	Rock	0.81	0.136	13	48	0.13	31	0.007	<20	0.65	<0.01	0.18	<2	<0.05	<1	<5	13	<5	
J971753	Rock	7.65	0.159	74	47	2.84	36	<0.001	<20	0.29	<0.01	0.10	<2	0.08	<1	<5	8	<5	
J971754	Rock	10.68	0.152	68	57	3.72	601	0.001	<20	0.29	<0.01	0.06	<2	0.14	<1	<5	8	<5	
J971755	Rock	19.83	0.005	19	5	1.22	159	<0.001	<20	0.22	<0.01	0.03	<2	0.05	<1	<5	<5	<5	
J971756	Rock	4.50	0.064	44	35	1.07	149	0.005	<20	2.16	<0.01	0.32	<2	<0.05	<1	<5	8	7	
J971757	Rock	4.95	0.064	44	45	0.89	155	0.004	<20	1.96	<0.01	0.26	<2	<0.05	<1	<5	11	<5	
J971758	Rock	0.45	0.029	15	16	0.25	86	0.002	<20	0.75	<0.01	0.08	<2	<0.05	<1	<5	7	<5	
J971759	Rock	0.05	0.004	<1	8	0.02	23	<0.001	<20	0.04	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
J971760	Rock	0.12	0.033	37	3	0.03	68	<0.001	<20	0.31	0.04	0.21	<2	<0.05	<1	<5	<5	<5	
J971761	Rock	6.46	0.041	12	6	0.75	56	0.003	<20	0.41	0.01	0.26	<2	0.08	<1	<5	<5	<5	
J971762	Rock	1.78	0.025	8	10	0.26	43	0.002	<20	0.40	<0.01	0.11	<2	<0.05	<1	<5	<5	<5	
J971763	Rock	0.22	0.024	24	3	0.04	129	<0.001	<20	0.27	0.03	0.17	<2	<0.05	<1	<5	<5	<5	
J971764	Rock	10.42	0.043	17	70	4.61	401	0.004	<20	0.63	<0.01	0.06	<2	<0.05	<1	<5	14	<5	
J971765	Rock	5.02	0.169	34	43	2.21	149	0.005	<20	2.11	<0.01	0.20	<2	<0.05	<1	<5	14	9	
J971766	Rock	7.58	0.074	8	146	3.45	48	0.006	<20	0.82	0.01	0.07	<2	<0.05	<1	<5	21	<5	
J971767	Rock	10.49	0.052	7	29	4.29	63	<0.001	<20	0.35	<0.01	0.12	<2	<0.05	<1	<5	11	<5	
J971768	Rock	6.89	0.110	8	168	2.67	252	0.017	<20	0.60	<0.01	0.09	<2	<0.05	<1	<5	24	<5	
J971769	Rock	4.83	0.016	6	7	1.16	94	0.003	<20	0.21	<0.01	0.01	<2	<0.05	<1	<5	<5	<5	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001715.2

Method		WGHT	G6	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
Analyte		Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V
Unit		kg	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
MDL		0.01	0.005	1	1	3	1	0.3	1	1	2	0.01	2	8	2	2	1	0.5	3	3	1
J971770	Rock	0.44	<0.005	1	583	5	50	<0.3	69	29	1253	4.73	2	<8	<2	3	81	0.8	5	<3	210
J971771	Rock	1.09	0.009	<1	90	3	30	<0.3	42	22	1201	3.55	<2	<8	<2	<2	107	0.6	<3	<3	135
J971772	Rock	0.70	<0.005	2	358	5	66	<0.3	113	40	1692	6.37	6	<8	<2	3	97	0.8	9	<3	324
J971773	Rock	0.56	<0.005	<1	45	3	54	<0.3	78	33	1162	4.70	4	<8	<2	3	122	0.7	<3	<3	179
J971774	Rock	0.59	<0.005	4	80	<3	203	<0.3	80	41	2535	13.96	14	<8	<2	<2	8	0.6	<3	<3	278
J971775	Rock	0.54	<0.005	3	153	19	84	<0.3	44	11	149	3.28	541	<8	<2	<2	63	<0.5	16	<3	57
J971776	Rock	0.35	<0.005	<1	109	<3	87	<0.3	72	49	2214	9.11	13	<8	<2	<2	7	<0.5	<3	<3	162
J971777	Rock	0.75	<0.005	<1	112	<3	54	<0.3	48	30	1081	5.69	12	<8	<2	<2	7	<0.5	<3	<3	139
J971778	Rock	0.51	<0.005	<1	54	<3	86	<0.3	44	54	1197	6.34	10	<8	<2	<2	38	<0.5	<3	<3	145
J971779	Rock	0.54	<0.005	1	102	<3	127	<0.3	78	64	2261	10.87	80	<8	<2	<2	7	<0.5	<3	<3	226
J971780	Rock	0.33	<0.005	1	15	8	75	<0.3	54	15	419	3.67	328	<8	<2	<2	16	<0.5	<3	<3	65
J971781	Rock Pulp	0.14	0.464	10	48	<3	54	<0.3	35	8	421	2.84	57	<8	<2	<2	39	<0.5	<3	<3	53
J971782	Rock	0.64	<0.005	<1	1	<3	6	<0.3	2	<1	204	0.41	<2	<8	<2	<2	35	<0.5	<3	<3	1

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

CERTIFICATE OF ANALYSIS WHI11001715.2

	Method	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	7AR
	Analyte	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga	Pb
	Unit	%	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5	0.01
J971770	Rock	7.59	0.187	27	198	0.41	380	0.012	<20	0.70	<0.01	0.10	<2	<0.05	<1	<5	28	<5	
J971771	Rock	7.81	0.055	15	110	4.38	918	0.011	<20	0.91	<0.01	0.06	<2	<0.05	<1	<5	20	<5	
J971772	Rock	7.79	0.198	19	226	0.36	206	0.019	<20	0.81	<0.01	0.05	<2	<0.05	<1	<5	34	<5	
J971773	Rock	8.46	0.081	14	187	3.18	38	0.002	<20	2.35	<0.01	0.13	<2	<0.05	<1	<5	30	8	
J971774	Rock	0.28	0.059	6	130	0.32	45	0.006	<20	0.90	<0.01	0.16	<2	<0.05	3	<5	44	<5	
J971775	Rock	0.12	0.016	2	14	0.04	4479	<0.001	<20	0.27	<0.01	0.02	<2	0.13	4	<5	<5	<5	
J971776	Rock	0.32	0.061	5	96	0.21	119	0.004	<20	0.72	<0.01	0.15	<2	<0.05	>50	<5	37	<5	
J971777	Rock	0.50	0.054	4	81	0.21	48	0.002	<20	0.77	<0.01	0.10	<2	<0.05	14	<5	36	<5	
J971778	Rock	0.68	0.099	6	89	0.26	2947	0.003	<20	0.91	<0.01	0.15	<2	0.15	>50	<5	28	<5	
J971779	Rock	0.31	0.040	5	122	0.36	63	0.003	<20	0.91	<0.01	0.33	<2	<0.05	10	<5	54	6	
J971780	Rock	0.12	0.017	2	14	0.04	267	<0.001	<20	0.62	<0.01	0.10	<2	<0.05	12	<5	6	<5	
J971781	Rock Pulp	1.39	0.074	6	29	0.62	113	0.102	<20	1.24	0.07	0.11	<2	0.11	<1	<5	<5	<5	
J971782	Rock	15.09	0.014	1	<1	11.18	16	<0.001	<20	<0.01	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

QUALITY CONTROL REPORT WHI11001715.2

	Method	WGHT	G6	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D
	Analyte	Wgt	Au	Mo	Cu	Pb	Zn	Ag	Ni	Co	Mn	Fe	As	U	Au	Th	Sr	Cd	Sb	Bi	V
	Unit	kg	gm/t	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm
	MDL	0.01	0.005	1	1	3	1	0.3	1	1	2	0.01	2	8	2	2	1	0.5	3	3	1
Pulp Duplicates																					
J971657	Rock	1.59	0.011	<1	33	20	73	<0.3	30	13	895	2.75	3	<8	<2	6	14	<0.5	<3	<3	11
REP J971657	QC		0.008																		
J971681	Rock	0.68	0.007	3	2	7	<1	<0.3	<1	<1	25	2.62	<2	<8	<2	4	17	<0.5	<3	<3	2
REP J971681	QC			3	2	6	<1	<0.3	<1	<1	25	2.56	<2	<8	<2	6	17	<0.5	<3	<3	2
J971698	Rock	0.69	<0.005	<1	7	30	5	<0.3	7	3	2238	2.84	5	13	<2	<2	193	0.6	<3	<3	2
REP J971698	QC		<0.005																		
J971713	Rock	0.38	<0.005	<1	12	6	15	<0.3	6	4	537	0.96	<2	<8	<2	3	2	<0.5	<3	<3	3
REP J971713	QC			<1	12	9	15	<0.3	6	4	528	0.96	<2	<8	<2	3	2	<0.5	<3	<3	3
J971718	Rock	1.07	0.007	<1	1	<3	13	<0.3	5	2	1726	1.16	2	<8	<2	3	4	<0.5	<3	<3	3
REP J971718	QC		<0.005																		
J971760	Rock	0.38	<0.005	<1	1	12	52	<0.3	4	2	280	1.01	2	<8	<2	17	9	<0.5	<3	<3	4
REP J971760	QC			<1	1	11	51	<0.3	4	2	270	0.99	3	<8	<2	18	9	<0.5	<3	<3	4
REP J971770	QC		<0.005																		
Core Reject Duplicates																					
J971665	Rock	0.59	<0.005	<1	12	<3	66	<0.3	7	2	515	2.82	2	<8	<2	10	13	<0.5	<3	<3	18
DUP J971665	QC		<0.005	<1	15	<3	72	<0.3	7	3	581	3.10	<2	<8	<2	10	14	<0.5	<3	<3	20
J971700	Rock	0.90	<0.005	<1	2	<3	4	<0.3	4	2	627	2.15	5	17	<2	<2	223	<0.5	<3	<3	3
DUP J971700	QC		<0.005	<1	2	<3	4	<0.3	4	2	599	2.01	5	12	<2	<2	211	<0.5	<3	<3	2
J971735	Rock	0.72	<0.005	1	<1	<3	22	<0.3	389	62	554	6.96	<2	<8	<2	<2	<1	0.7	<3	<3	76
DUP J971735	QC		<0.005	<1	<1	<3	23	<0.3	404	64	560	7.48	<2	<8	<2	<2	1	0.7	<3	<3	88
J971770	Rock	0.44	<0.005	1	583	5	50	<0.3	69	29	1253	4.73	2	<8	<2	3	81	0.8	5	<3	210
DUP J971770	QC		<0.005	1	592	4	49	<0.3	69	28	1267	4.78	3	<8	<2	2	81	0.8	5	<3	211
Reference Materials																					
STD DS8	Standard			15	108	117	331	1.5	39	7	624	2.53	26	<8	<2	8	71	2.7	6	3	44
STD DS8	Standard			15	110	133	333	1.6	40	8	646	2.53	28	<8	<2	7	70	2.5	5	6	44
STD DS8	Standard			15	106	120	316	1.5	38	8	622	2.44	27	<8	<2	7	67	2.3	5	7	43
STD DS8	Standard			14	108	119	319	1.9	39	8	624	2.51	23	<8	<2	7	71	2.3	<3	4	43
STD GC-7	Standard																				

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

QUALITY CONTROL REPORT WHI11001715.2

	Method	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	1D	7AR
	Analyte	Ca	P	La	Cr	Mg	Ba	Ti	B	Al	Na	K	W	S	Hg	Tl	Sc	Ga	Pb
	Unit	%	%	ppm	ppm	%	ppm	%	ppm	%	%	%	ppm	%	ppm	ppm	ppm	ppm	%
	MDL	0.01	0.001	1	1	0.01	1	0.001	20	0.01	0.01	0.01	2	0.05	1	5	5	5	0.01
Pulp Duplicates																			
J971657	Rock	0.17	0.075	14	25	0.31	79	0.004	<20	0.86	0.04	0.14	<2	<0.05	<1	<5	<5	<5	
REP J971657	QC																		
J971681	Rock	0.01	0.016	25	2	0.03	339	0.019	<20	0.22	0.14	0.46	<2	0.93	<1	<5	<5	<5	
REP J971681	QC	0.01	0.017	26	3	0.03	272	0.019	<20	0.21	0.14	0.45	<2	0.93	<1	<5	<5	<5	
J971698	Rock	17.22	0.009	6	2	6.00	12	<0.001	<20	0.10	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
REP J971698	QC																		
J971713	Rock	<0.01	0.016	9	16	0.09	19	<0.001	<20	0.24	<0.01	0.07	<2	<0.05	<1	<5	<5	<5	
REP J971713	QC	<0.01	0.016	10	13	0.09	19	<0.001	<20	0.24	<0.01	0.07	<2	<0.05	<1	<5	<5	<5	
J971718	Rock	0.01	0.017	9	9	0.07	39	<0.001	<20	0.24	<0.01	0.10	<2	<0.05	<1	<5	<5	<5	
REP J971718	QC																		
J971760	Rock	0.12	0.033	37	3	0.03	68	<0.001	<20	0.31	0.04	0.21	<2	<0.05	<1	<5	<5	<5	
REP J971760	QC	0.12	0.032	36	3	0.03	66	<0.001	<20	0.30	0.04	0.21	<2	<0.05	<1	<5	<5	<5	
REP J971770	QC																		
Core Reject Duplicates																			
J971665	Rock	0.40	0.015	36	4	1.22	188	0.107	<20	1.74	0.06	0.43	<2	<0.05	<1	<5	<5	15	
DUP J971665	QC	0.48	0.015	37	6	1.34	187	0.112	<20	1.93	0.06	0.41	<2	<0.05	<1	<5	<5	17	
J971700	Rock	22.59	0.005	4	3	5.85	15	<0.001	<20	0.09	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
DUP J971700	QC	22.51	0.006	3	3	5.59	14	<0.001	<20	0.09	<0.01	0.02	<2	<0.05	<1	<5	<5	<5	
J971735	Rock	0.05	0.010	<1	202	8.68	2	0.020	<20	1.50	<0.01	0.04	2	<0.05	<1	<5	15	<5	
DUP J971735	QC	0.07	0.010	<1	234	8.76	3	0.023	<20	1.60	<0.01	0.04	2	<0.05	<1	<5	16	<5	
J971770	Rock	7.59	0.187	27	198	0.41	380	0.012	<20	0.70	<0.01	0.10	<2	<0.05	<1	<5	28	<5	
DUP J971770	QC	7.69	0.184	26	199	0.40	349	0.013	<20	0.76	<0.01	0.10	<2	<0.05	<1	<5	28	<5	
Reference Materials																			
STD DS8	Standard	0.76	0.081	17	124	0.63	304	0.109	<20	0.95	0.09	0.43	3	0.17	<1	<5	<5	<5	
STD DS8	Standard	0.74	0.084	16	124	0.64	304	0.114	<20	0.97	0.09	0.43	<2	0.18	<1	<5	<5	<5	
STD DS8	Standard	0.72	0.082	15	118	0.63	295	0.117	<20	0.94	0.09	0.42	3	0.17	<1	<5	<5	5	
STD DS8	Standard	0.75	0.067	17	127	0.63	300	0.087	<20	0.97	0.09	0.43	<2	0.17	<1	<5	<5	<5	
STD GC-7	Standard																		>10

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

QUALITY CONTROL REPORT WHI11001715.2

		WGHT Wgt kg 0.01	G6 Au gm/t 0.005	1D Mo ppm 1	1D Cu ppm 1	1D Pb ppm 3	1D Zn ppm 1	1D Ag ppm 0.3	1D Ni ppm 1	1D Co ppm 1	1D Mn ppm 2	1D Fe % 0.01	1D As ppm 2	1D U ppm 8	1D Au ppm 2	1D Th ppm 2	1D Sr ppm 1	1D Cd ppm 0.5	1D Sb ppm 3	1D Bi ppm 3	1D V ppm 1
STD GC-7	Standard																				
STD OREAS45CA	Standard			3	520	35	62	<0.3	260	91	915	16.14	4	<8	<2	7	15	0.9	<3	<3	200
STD OREAS45CA	Standard			1	544	21	63	<0.3	268	96	959	16.51	4	<8	<2	8	16	<0.5	<3	<3	214
STD OREAS45CA	Standard			1	549	22	62	<0.3	263	96	982	16.15	5	<8	<2	7	15	<0.5	<3	<3	218
STD OREAS45CA	Standard			3	530	28	60	<0.3	265	95	929	16.14	3	<8	<2	7	15	<0.5	<3	<3	188
STD OXH82	Standard		1.251																		
STD OXH82	Standard		1.354																		
STD OXH82	Standard		1.359																		
STD OXH82	Standard		1.236																		
STD OXH82	Standard		1.318																		
STD OXK79	Standard		3.675																		
STD OXK79	Standard		3.531																		
STD OXK79	Standard		3.764																		
STD OXK79	Standard		3.566																		
STD OXK79	Standard		3.215																		
STD DS8 Expected				13.44	110	123	312	1.69	38.1	7.5	615	2.46	26	2.8	0.107	6.89	67.7	2.38	4.8	6.67	41.1
STD OREAS45CA Expected				1	494	20	60	0.275	240	92	943	15.69	3.8	1.2	0.043	7	15	0.1	0.13	0.19	215
STD OXH82 Expected			1.278																		
STD OXK79 Expected			3.532																		
STD GC-7 Expected																					
BLK	Blank			<1	<1	<3	<1	<0.3	<1	<1	<2	<0.01	<2	<8	<2	<2	<1	<0.5	<3	<3	<1
BLK	Blank			<1	<1	<3	<1	<0.3	<1	<1	<2	<0.01	<2	<8	<2	<2	<1	<0.5	<3	<3	<1
BLK	Blank			<1	<1	<3	<1	<0.3	<1	<1	<2	<0.01	<2	<8	<2	<2	<1	<0.5	<3	<3	<1
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

QUALITY CONTROL REPORT WHI11001715.2

		1D Ca % 0.01	1D P % 0.001	1D La ppm 1	1D Cr ppm 1	1D Mg % 0.01	1D Ba ppm 1	1D Ti % 0.001	1D B ppm 20	1D Al % 0.01	1D Na % 0.01	1D K % 0.01	1D W ppm 2	1D S % 0.05	1D Hg ppm 1	1D Tl ppm 5	1D Sc ppm 5	1D Ga ppm 5	7AR Pb % 0.01
STD GC-7	Standard																		>10
STD OREAS45CA	Standard	0.43	0.040	17	756	0.15	162	0.106	<20	4.01	<0.01	0.08	<2	<0.05	<1	<5	48	<5	
STD OREAS45CA	Standard	0.45	0.040	18	769	0.15	164	0.132	<20	3.98	<0.01	0.08	<2	<0.05	<1	<5	49	12	
STD OREAS45CA	Standard	0.48	0.041	18	771	0.15	165	0.144	<20	3.94	<0.01	0.08	<2	<0.05	<1	<5	47	15	
STD OREAS45CA	Standard	0.43	0.039	17	761	0.15	167	0.079	<20	4.05	<0.01	0.08	<2	<0.05	<1	<5	49	13	
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXH82	Standard																		
STD OXK79	Standard																		
STD OXK79	Standard																		
STD OXK79	Standard																		
STD OXK79	Standard																		
STD OXK79	Standard																		
STD DS8 Expected		0.7	0.08	14.6	115	0.6045	279	0.113	2.6	0.93	0.0883	0.41	3	0.1679	0.192	5.4	2.3	4.7	
STD OREAS45CA Expected		0.4265	0.0385	15.9	709	0.1358	164	0.128		3.592	0.0075	0.0717		0.021	0.03	0.07			
STD OXH82 Expected																			
STD OXK79 Expected																			
STD GC-7 Expected																			10.44
BLK	Blank	<0.01	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5	
BLK	Blank	<0.01	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5	
BLK	Blank	<0.01	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5	
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

QUALITY CONTROL REPORT WHI11001715.2

		WGHT Wgt kg 0.01	G6 Au gm/t 0.005	1D Mo ppm 1	1D Cu ppm 1	1D Pb ppm 3	1D Zn ppm 1	1D Ag ppm 0.3	1D Ni ppm 1	1D Co ppm 1	1D Mn ppm 2	1D Fe % 0.01	1D As ppm 2	1D U ppm 8	1D Au ppm 2	1D Th ppm 2	1D Sr ppm 1	1D Cd ppm 0.5	1D Sb ppm 3	1D Bi ppm 3	1D V ppm 1
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank			<1	<1	<3	<1	<0.3	<1	<1	<2	<0.01	<2	<8	<2	<2	<1	<0.5	<3	<3	<1
BLK	Blank		<0.005																		
BLK	Blank		<0.005																		
BLK	Blank																				
Prep Wash																					
G1	Prep Blank		0.005	<1	1	4	56	<0.3	4	4	571	1.98	35	<8	<2	6	63	<0.5	<3	<3	38
G1	Prep Blank		<0.005	<1	<1	3	50	<0.3	4	5	573	2.01	2	<8	<2	6	73	<0.5	<3	<3	38

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Acme Analytical Laboratories (Vancouver) Ltd.
1020 Cordova St. East Vancouver BC V6A 4A3 Canada
Phone (604) 253-3158 Fax (604) 253-1716
www.acmelab.com

Client: **Golden Predator Canada Corp.**
11th Floor, 888 Dunsmuir Street
Vancouver BC V6C 3K4 Canada

Project: LIVINGSTONE
Report Date: November 09, 2011

QUALITY CONTROL REPORT WHI11001715.2

		1D Ca % 0.01	1D P % 0.001	1D La ppm 1	1D Cr ppm 1	1D Mg % 0.01	1D Ba ppm 1	1D Ti % 0.001	1D B ppm 20	1D Al % 0.01	1D Na % 0.01	1D K % 0.01	1D W ppm 2	1D S % 0.05	1D Hg ppm 1	1D Tl ppm 5	1D Sc ppm 5	1D Ga ppm 5	7AR Pb % 0.01
BLK	Blank																		
BLK	Blank																		
BLK	Blank	<0.01	<0.001	<1	<1	<0.01	<1	<0.001	<20	<0.01	<0.01	<0.01	<2	<0.05	<1	<5	<5	<5	
BLK	Blank																		
BLK	Blank																		
BLK	Blank																		<0.01
Prep Wash																			
G1	Prep Blank	0.54	0.057	12	9	0.57	250	0.084	<20	0.97	0.07	0.47	<2	<0.05	<1	<5	<5	<5	
G1	Prep Blank	0.56	0.065	13	10	0.60	230	0.095	<20	1.05	0.07	0.50	<2	<0.05	<1	<5	<5	<5	

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Appendix 4
Analytical Methods and Detection Limits

PREP- 41


Standard Preparation: Dry sample and dry- sieve to –180 micron

Sample preparation is the most critical step in the entire laboratory operation. The purpose of preparation is to produce a homogeneous analytical sub-sample that is fully representative of the material submitted to the laboratory.

An entire sample is dried and then dry-sieved using a 180 micron (Tyler 80 mesh) screen. The plus fraction is retained unless disposal is requested. This method is appropriate for soil or sediment samples up to 1 kg in weight.

Method Code	Description
LOG-22	Sample is logged in tracking system and a bar code label is attached.
DRY-22	Low temperature drying of excessively wet samples where the oven temperature is not to exceed 60°C. This method is suitable for more soil and sediment samples that are analyzed for volatile elements.
SCR-41	Sample is dry-sieved to – 180 micron and both the plus and minus fractions are retained.

Sample Preparation Flowchart Package –PREP- 41





Geochemical Procedure

ME- MS41
Ultra- Trace Level Methods Using ICP- MS and ICP- AES

Sample Decomposition:

Aqua Regia Digestion (GEO-AR01)

Analytical Method:

Inductively Coupled Plasma-Atomic Emission Spectroscopy (ICP-AES) Inductively Coupled Plasma - Mass Spectrometry (ICP-MS)

A prepared sample (0.50 g) is digested with aqua regia in a graphite heating block. After cooling, the resulting solution is diluted to with deionized water, mixed and analyzed by inductively coupled plasma-atomic emission spectrometry. Following this analysis, the results are reviewed for high concentrations of bismuth, mercury, molybdenum, silver and tungsten and diluted accordingly. Samples are then analysed by ICP-MS for the remaining suite of elements. The analytical results are corrected for inter-element spectral interferences.

Element	Symbol	Units	Lower Limit	Upper Limit
Silver	Ag	ppm	0.01	100
Aluminum	Al	%	0.01	25
Arsenic	As	ppm	0.1	10 000
Gold	Au	ppm	0.2	25
Boron	B	ppm	10	10 000
Barium	Ba	ppm	10	10 000
Beryllium	Be	ppm	0.05	1 000
Bismuth	Bi	ppm	0.01	10 000
Calcium	Ca	%	0.01	25
Cadmium	Cd	ppm	0.01	1 000
Cerium	Ce	ppm	0.02	500
Cobalt	Co	ppm	0.1	10 000
Chromium	Cr	ppm	1	10 000



Geochemical Procedure

Element	Symbol	Units	Lower Limit	Upper Limit
Cesium	Cs	ppm	0.05	500
Copper	Cu	ppm	0.2	10 000
Iron	Fe	%	0.01	50
Gallium	Ga	ppm	0.05	10 000
Germanium	Ge	ppm	0.05	500
Hafnium	Hf	ppm	0.02	500
Mercury	Hg	ppm	0.01	10 000
Indium	In	ppm	0.005	500
Potassium	K	%	0.01	10
Lanthanum	La	ppm	0.2	10 000
Lithium	Li	ppm	0.1	10 000
Magnesium	Mg	%	0.01	25
Manganese	Mn	ppm	5	50 000
Molybdenum	Mo	ppm	0.05	10 000
Sodium	Na	%	0.01	10
Niobium	Nb	ppm	0.05	500
Nickel	Ni	ppm	0.2	10 000
Phosphorus	P	ppm	10	10 000
Lead	Pb	ppm	0.2	10 000
Rubidium	Rb	ppm	0.1	10 000
Rhenium	Re	ppm	0.001	50
Sulphur	S	%	0.01	10
Antimony	Sb	ppm	0.05	10 000
Scandium	Sc	ppm	0.1	10 000
Selenium	Se	ppm	0.2	1 000
Tin	Sn	ppm	0.2	500
Strontium	Sr	ppm	0.2	10 000



Element	Symbol	Units	Lower Limit	Upper Limit
Tantalum	Ta	ppm	0.01	500
Tellurium	Te	ppm	0.01	500
Thorium	Th	ppm	0.2	10000
Titanium	Ti	%	0.005	10
Thallium	Tl	ppm	0.02	10 000
Uranium	U	ppm	0.05	10 000
Vanadium	V	ppm	1	10 000
Tungsten	W	ppm	0.05	10 000
Yttrium	Y	ppm	0.05	500
Zinc	Zn	ppm	2	10 000
Zirconium	Zr	ppm	0.5	500

NOTE: In the majority of geological matrices, data reported from an aqua regia leach should be considered as representing only the leachable portion of the particular analyte.

ALS Minerals

GEOCHEMICAL PROCEDURE

Au-TL43, Au-TL44

DETERMINATION OF TRACE LEVEL GOLD BY SOLVENT EXTRACTION – GRAPHITE FURNACE AAS OR ICPMS FINISH

SAMPLE DECOMPOSITION

Aqua regia gold digestion (GEO-AuAR01/02)

ANALYTICAL METHOD

Inductively coupled mass spectrometry (ICPMS) or Atomic absorption spectrometry (AAS)

A finely pulverised sample (25 – 50 g) is digested in a mixture of 3 parts hydrochloric acid and 1 part nitric acid (aqua regia). This acid mixture generates nascent chlorine and nitrosyl chloride, which will dissolve free gold and gold compounds such as calaverite, $AuTe_2$.

The dissolved gold is complexed and extracted with Kerosene/DBS and determined by graphite furnace AAS. Alternatively gold is determined by ICPMS directly from the digestion liquor. This method allows for the simple and economical addition of extra elements by running the digestion liquor through the ICPAES or ICPMS.

NOTE: Samples high in sulphide or carbon content may lead to low gold recoveries unless they are roasted prior to digestion.

METHOD CODE	ELEMENT	SYMBOL	UNITS	SAMPLE MASS (G)	LOWER LIMIT	UPPER LIMIT	DEFAULT OVERLIMIT METHOD
Au-TL43	Gold	Au	ppm	25	0.001	1	Au-OG43
Au-TL44	Gold	Au	ppm	50	0.001	1	Au-OG44



Geochemical Procedure

Au- OG43, Au- OG44
Determination of Gold by Aqua Regia Digestion / Solvent Extraction – Flame AAS or ICPMS finish

Sample Decomposition:

Aqua regia gold digestion (GEO-AuAR01/02)

Analytical Method:

Inductively coupled mass spectrometry (ICPMS) or Atomic absorption spectrometry (AAS)

A finely pulverised sample (25 – 50 g) is digested in a mixture of 3 parts hydrochloric acid and 1 part nitric acid (aqua regia). This acid mixture generates nascent chlorine and nitrosyl chloride, which will dissolve free gold and gold compounds such as calaverite ($AuTe_2$).

The dissolved gold is complexed and extracted into Aliquat 336/DIBK and determined by Flame AAS. Alternatively gold is determined by ICPMS directly from the digestion liquor. This method allows for the simple and economical addition of extra elements by running the digestion liquor through the ICPAES or ICPMS.

Note: Samples high in sulphide or carbon content may lead to low gold recoveries unless they are roasted prior to digestion.

Method	Element	Sample Mass	Units	Lower Limit	Upper Limit
Au-OG43	Gold	25 g	ppm	0.01	100
Au-OG44	Gold	50 g	ppm	0.01	100

AcmeLabs
CARECOMMITMENTPERFORMANCE

METHOD SPECIFICATIONS
GROUP 1D AND 1F – GEOCHEMICAL AQUA REGIA DIGESTION

Package Codes: 1D01 to 1D03, 1DX1 to 1DX3, 1F01 to 1F07
Sample Digestion: HNO3-HCl acid digestion
Instrumentation Method: ICP-ES (1D), ICP-MS (1DX, 1F)
Applicability: Sediment, Soil, Non-mineralized Rock and Drill Core

Method Description:

Prepared sample is digested with a modified Aqua Regia solution of equal parts concentrated HCl, HNO3 and DI H2O for one hour in a heating block of hot water bath. Sample is made up to volume with dilute HCl. Sample splits of 0.5g, 15g or 30g can be analyzed.

For 1F07, Lead isotopes (Pb_{204}, Pb_{206}, Pb_{207}, Pb_{208}) are suitable for geochemical exploration of U and other commodities where gross differences in natural to radiogenic Pb ratios, is a benefit. Isotope values can be reported in both concentrations and intensities. Sample splits of 0.25g, 0.5g, 15g or 30g can be analyzed.

Element	Group 1D Detection	Group 1DX Detection	Group 1F Detection	Upper Limit
Ag	0.3 ppm	0.1 ppm	2 ppb	100 ppm
Al*	0.01%	0.01%	0.01%	10%
As	2 ppm	0.5 ppm	0.1 ppm	10000 ppm
Au	2 ppm	0.5 ppb	0.2 ppb	100 ppm
B*^	20 ppm	20 ppm	20 ppm	2000 ppm
Ba*	1 ppm	1 ppm	0.5 ppm	10000 ppm
Bi	3 ppm	0.1 ppm	0.02 ppm	2000 ppm
Ca*	0.01%	0.01%	0.01%	40%
Cd	0.5 ppm	0.1 ppm	0.01 ppm	2000 ppm
Co	1 ppm	0.1 ppm	0.1 ppm	2000 ppm
Cr*	1 ppm	1 ppm	0.5 ppm	10000 ppm
Cu	1 ppm	0.1 ppm	0.01 ppm	10000 ppm
Fe*	0.01%	0.01%	0.01%	40%
Ga*	-	1 ppm	0.1 ppm	1000 ppm
Hg	1 ppm	0.01 ppm	5 ppb	50 ppm
K*	0.01%	0.01%	0.01%	10%
La*	1 ppm	1 ppm	0.5 ppm	10000 ppm
Mg*	0.01%	0.01%	0.01%	30%
Mn*	2 ppm	1 ppm	1 ppm	10000 ppm
Mo	1 ppm	0.1 ppm	0.01 ppm	2000 ppm

Element	Group 1D Detection	Group 1DX Detection	Group 1F Detection	Upper Limit
Na*	0.01%	0.001%	0.001%	5%
Ni	1 ppm	0.1 ppm	0.1 ppm	10000 ppm
P*	0.001%	0.001%	0.001%	5%
Pb	3 ppm	0.1 ppm	0.01 ppm	10000 ppm
S	0.05%	0.05%	0.02%	10%
Sb	3 ppm	0.1 ppm	0.02 ppm	2000 ppm
Sc	-	0.1 ppm	0.1 ppm	100 ppm
Se	-	0.5 ppm	0.1 ppm	100 ppm
Sr*	1 ppm	1 ppm	0.5 ppm	10000 ppm
Te	-	0.2 ppm	0.02 ppm	1000 ppm
Th*	2 ppm	0.1 ppm	0.1 ppm	2000 ppm
Ti*	0.01%	0.001%	0.001%	5%
Tl	5 ppm	0.1 ppm	0.02 ppm	1000 ppm
U*	8 ppm	0.1 ppm	0.05 ppm	2000 ppm
V*	1 ppm	2 ppm	2 ppm	10000 ppm
W*	2 ppm	0.1 ppm	0.05 ppm	100 ppm
Zn	1 ppm	1 ppm	0.1 ppm	10000 ppm
Be*	-	-	0.1 ppm	1000 ppm
Ce*	-	-	0.1 ppm	2000 ppm
Cs*	-	-	0.02 ppm	2000 ppm
Ge*	-	-	0.1 ppm	100 ppm
Hf*	-	-	0.02 ppm	1000 ppm
In	-	-	0.02 ppm	1000 ppm
Li*	-	-	0.1 ppm	2000 ppm
Nb*	-	-	0.02 ppm	2000 ppm
Rb*	-	-	0.1 ppm	2000 ppm
Re	-	-	1 ppb	1000 ppb
Sn*	-	-	0.1 ppm	100 ppm
Ta*	-	-	0.05 ppm	2000 ppm
Y*	-	-	0.01 ppm	2000 ppm
Zr*	-	-	0.1 ppm	2000 ppm
Pt*	-	-	2 ppb	100 ppm
Pd*	-	-	10 ppb	100 ppm
Pb_{204}	-	-	0.01 ppm	10000 ppm
Pb_{206}	-	-	0.01 ppm	10000 ppm
Pb_{207}	-	-	0.01 ppm	10000 ppm
Pb_{208}	-	-	0.01 ppm	10000 ppm

* Solubility of some elements will be limited by mineral species present.
^Detection limit = 1 ppm for 15g / 30g analysis.

Limitations:

Au solubility can be limited by refractory and graphitic samples.

AcmeLabs
CARECOMMITMENTPERFORMANCE

METHOD SPECIFICATIONS
GROUP 3B AND G6 – PRECIOUS METALS BY FIRE ASSAY FUSION

Package Codes: 3B01 to 3B04, G601 to G614
Sample Digestion: Lead-collection fire assay fusion
Instrumentation Method: ICP-ES (3B, G6), ICP-MS (3B-MS), AA (3B, G6), Gravimetric (G6)
Applicability: Rock, Drill Core

Method Description:


Prepared sample is custom-blended with fire-assay fluxes, PbO litharge and a Ag inquart. Firing the charge at 1050 ^{o}C liberates Ag ± Au ± PGEs that report to the molten Pb-metal phase. After cooling the Pb button is recovered, placed in a cupel and fired at 950 ^{o}C to render a Ag ± Au ± PGEs dore bead. The bead is digested for ICP analysis or weighed and parted in ACS grade HNO_3 to dissolve Ag leaving a Au sponge. Au is weighed for Gravimetric determination; ACS grade HCl is added dissolving the Au ± PGE sponge for Instrument determination.


Element	3B Detection	3B Upper Limit	3B-MS Detection	3B-MS Upper Limit
Au	2 ppb	10000 ppb	1 ppb	10000 ppb
Pt	3 ppb	10000 ppb	0.1 ppb	10000 ppb
Pd	2 ppb	10000 ppb	0.5 ppb	10000 ppb

Element	G6 (Inst) Detection	G6 (Inst) Upper Limit	G6 (Grav) Detection	G6 (Grav) Upper Limit
Ag	--	--	50 g/t	1 ton
Au	0.005 g/t	10 g/t	0.9 g/t	1 ton
Pt	0.01 g/t	100 g/t	--	--
Pd	0.01 g/t	100 g/t	--	--

Note:
*Sulphide-rich samples require a 15g or smaller sample for proper fusion.

Appendix 5
Silt Geochemical Plots
for Select Elements





Legend

- GPD Property Outline
- NTS Mapsheet
- Watercourse

GOLDEN PREDATOR

Livingstone

Stream Sediment Sample Locations

0 3 6 9 12

Kilometers

Scale:	1:230,000	Map ID:	--
Draw Date:	2012/11/15	Rev. Date:	
Version:	1	Figure:	Appendix 5-1
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121115_2011App5-1		

510,000 520,000 530,000 540,000 550,000 560,000 570,000 580,000

6,840,000 6,830,000 6,820,000 6,810,000 6,800,000

N

North Big Salmon River

South Big Salmon River

Northern Lake

Big Salmon River

Sheep Creek

Summit Creek

Mendocina Creek

Scurvy Creek

Gray Creek

94.2

100

98

100

860

100

SRVF

SRVB

SRVE

SRVA

JJW

MCPN

DAC

DACX


SRVD

SRVC

OVS

RNB

RWH



Legend

- GPD Property Outline
- NTS Mapsheet
- Watercourse

Au (ppb)

- 0.1 - 1.2
- 1.3 - 3.8
- 3.9 - 23.0
- 23.1 - 61.0
- 61.1 - 860.0

GOLDEN PREDATOR

Livingstone

Stream Sediment Sample Locations

0 3 6 9 12

Kilometers

Scale:	1:230,000	Map ID:	--
Draw Date:	2012/11/15	Rev. Date:	
Version:	1	Figure:	Appendix 5-2
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121115_2011App5-2t		

510,000 520,000 530,000 540,000 550,000 560,000 570,000 580,000

6,840,000 6,830,000 6,820,000 6,810,000 6,800,000

N

North Big Salmon River

Northern Lake

Big Salmon River

South Big Salmon River

Sheep Creek

Summit Creek

Mendocina Creek

Scurvy Creek

Gray Creek

SRVF

SRVB

SRVE

SRVA

JJW

MCPN

DAC

DACX

SRVD


SRVC

OVS

RNB

RWH

0.3 0.28 0.25 0.4 0.34 0.25 0.38 0.26 0.38 0.63 0.27



Legend

- GPD Property Outline
- NTS Mapsheet
- Watercourse

Ag (ppm)

- 0.03 - 0.09
- 0.10 - 0.14
- 0.15 - 0.24
- 0.25 - 0.30
- 0.31 - 0.63

GOLDEN PREDATOR

Livingstone

Stream Sediment Sample Locations

0 3 6 9 12

Kilometers

Scale:	1:230,000	Map ID:	--
Draw Date:	2012/11/15	Rev. Date:	
Version:	1	Figure:	Appendix 5-3
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121115_2011App5-3		

510,000 520,000 530,000 540,000 550,000 560,000 570,000 580,000

6,840,000 6,830,000 6,820,000 6,810,000 6,800,000

N

North Big Salmon River

South Big Salmon River

Northern Lake

Big Salmon River

Sheep Creek

Summit Creek

Mendocina Creek

Scurvy Creek

Gray Creek

SRVF

SRVB

SRVE

SRVA

JJW

MCPN

DAC

DACX

SRVD


SRVC

OVS

RNB

RWH

21.6
24.7
22.6
26
23.9
34.9
19.5
19.3
22.3
24.4
47.6
20.1
24.6
20
51.4



Legend

- GPD Property Outline
- NTS Mapsheet
- Watercourse

As (ppm)

- 1.1 - 5.7
- 5.8 - 11.5
- 11.6 - 18.9
- 19.0 - 23.9
- 24.0 - 51.4

GOLDEN PREDATOR

Livingstone

Stream Sediment Sample Locations

0 3 6 9 12

Kilometers

Scale:	1:230,000	Map ID:	--
Draw Date:	2012/11/15	Rev. Date:	
Version:	1	Figure:	Appendix 5-4
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121115_2011App5-4		

510,000 520,000 530,000 540,000 550,000 560,000 570,000 580,000

6,840,000 6,830,000 6,820,000 6,810,000 6,800,000

N

North Big Salmon River

South Big Salmon River

Northern Lake

Big Salmon River

Sheep Creek

Summit Creek

Mendocina Creek

Scurvy Creek

Gray Creek

SRVF

SRVB

SRVE

SRVA

JJW

MCPN

DAC

DACX

SRVD

SRVC

OVS

RNB

RWH

41.7

50.2

41.1

66.6

76.6

72.5

57.4

48.4

47.3

42.3

49.6

43.7

41.6

41.1

42



Legend

- GPD Property Outline
- NTS Mapsheet
- Watercourse

Cu (ppm)

- 5.3 - 19.7
- 19.8 - 28.7
- 28.8 - 39.8
- 39.9 - 47.4
- 47.5 - 76.6

GOLDEN PREDATOR

Livingstone

Stream Sediment Sample Locations

0 3 6 9 12

Kilometers

Scale:	1:230,000	Map ID:	--
Draw Date:	2012/11/15	Rev. Date:	
Version:	1	Figure:	Appendix 5-5
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121115_2011App5-5		

510,000 520,000 530,000 540,000 550,000 560,000 570,000 580,000

6,840,000 6,830,000 6,820,000 6,810,000 6,800,000

N

North Big Salmon River

Northern Lake

Big Salmon River

South Big Salmon River

Sheep Creek

Summit Creek

Mendocina Creek

Scurvy Creek

Gray Creek

SRVF

SRVB

SRVE

SRVA

JJW

MCPN

DAC

DACX

SRVD

SRVC

OVS

RNB

RWH

3.93 6.63 5.87

4.08

7.3

4.49 4.86

4.15

4.04

6.13 6.06 4.72

14.45



Legend

- GPD Property Outline
- NTS Mapsheet
- Watercourse

Mo (ppm)

- 0.2 - 1.0
- 1.1 - 1.9
- 2.0 - 3.9
- 4.0 - 4.7
- 4.8 - 14.5

GOLDEN PREDATOR


Livingstone

Stream Sediment Sample Locations

0 2.5 5 7.5 10

Kilometers

Scale:	1:230,000	Map ID:	--
Draw Date:	2012/11/15	Rev. Date:	
Version:	1	Figure:	Appendix 5-6
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121115_2011App5-6		


510,000
520,000
530,000
540,000
550,000
560,000
570,000
580,000
6,840,000
6,830,000
6,820,000
6,810,000
6,800,000
N
North Big Salmon River
Northern Lake
Big Salmon River
South Big Salmon River
Sheep Creek
Summit Creek
Mendocina Creek
Scurvy Creek
Gray Creek
SRVF
SRVB
SRVE
SRVA
JJW
MCPN
DAC
DACX
SRVD
SRVC
OVS
RNB
RWH
16.5
14.3
23.9
16.2
15.4
18.8
14.6
19.9
16.2
15.2
25.8
15.1
14.6
16.1
16.3
0
250
Km
YUKON
Dawson City
Faro
Map Location
Whitehorse
Watson Lake
Legend
GPD Property Outline
NTS Mapsheet
Watercourse
Pb (ppm)
2 - 8
9 - 10
11 - 14
15 - 16
17 - 26
GOLDEN PREDATOR
Livingstone
Stream Sediment
Sample Locations
0 3 6 9 12
Kilometers
Scale: 1:230,000
Map ID: --
Draw Date: 2012/11/15
Rev. Date:
Version: 1
Figure: Appendix 5-7
Author: E. O'Brien
Office: Vancouver
Location: Livingstone District
Projection: NAD 1983 UTM Zone 8N
Filename: LIV_20121115_2011App5-7

510,000 520,000 530,000 540,000 550,000 560,000 570,000 580,000

6,840,000 6,830,000 6,820,000 6,810,000 6,800,000

N

North Big Salmon River

Northern Lake

Big Salmon River

South Big Salmon River

Sheep Creek

Summit Creek

Mendocina Creek

Scurvy Creek

Gray Creek

SRVF

SRVB

SRVE

SRVA

JJW

MCPN

DAC

DACX

SRVD


SRVC

OVS

RNB

RWH

1.82
1.85
4.25
3.19
2.16
1.89
2
1.96
1.9
3.62
3.56
1.81
2.03
3.74
6.61
2.22



Legend

- GPD Property Outline
- NTS Mapsheet
- Watercourse

Sb (ppm)

- 0.1 - 0.4
- 0.5 - 0.7
- 0.8 - 1.8
- 1.9 - 2.2
- 2.3 - 6.6

GOLDEN PREDATOR


Livingstone

Stream Sediment Sample Locations

0 3 6 9 12

Kilometers

Scale:	1:230,000	Map ID:	--
Draw Date:	2012/11/15	Rev. Date:	
Version:	1	Figure:	Appendix 5-8
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121115_2011App5-8		


510,000
520,000
530,000
540,000
550,000
560,000
570,000
580,000
6,840,000
6,830,000
6,820,000
6,810,000
6,800,000
N
North Big Salmon River
Northern Lake
Big Salmon River
South Big Salmon River
Sheep Creek
Summit Creek
Mendocina Creek
Scurvy Creek
Gray Creek
SRVF
SRVB
SRVE
SRVA
JJW
MCPN
DAC
DACX
SRVD
SRVC
OVS
RNB
RWH
198
302
485
175
185
160
154
317
186
222
418
336
224
252
374
0
250
Km
YUKON
Dawson City
Faro
Map Location
Whitehorse
Watson Lake
Legend
GPD Property Outline
NTS Mapsheet
Watercourse
Zn (ppm)
23 - 75
76 - 118
119 - 151
152 - 225
226 - 485
GOLDEN PREDATOR
Livingstone
Stream Sediment
Sample Locations
0
3
6
9
12
Kilometers
Scale: 1:230,000
Map ID: --
Draw Date: 2012/11/15
Rev. Date:
Version: 1
Figure: Appendix 5-9
Author: E. O'Brien
Office: Vancouver
Location: Livingstone District
Projection: NAD 1983 UTM Zone 8N
Filename: LIV_20121115_2011App5-9

Appendix 6
Soil Geochemical Plots
for Select Elements

538,000


539,000

6,809,000

DAC

K960975
K960974
K960973
K960972
K960971
K960970
K960969
K960968
K960967
K960966
K960965
K960964
K960963
K960962
K960961
K960960
K960976
K960459
K960461
K960458
K960977
K960978
K960979
K960980
K960981
K960982
K960983
K960984
K960985
K960986
K960987
K960463
K960462
K960460
K960464
K960465
K960466
K960467
K960468
K960469
K960470
K960471
K960472
K960473
K960474
K960475
K960476
K960477
K960478
K960479
K960780
K960481
K960482
K960783
K960484
K960785
K960486

1220
1240
1260
1280
1300
1320
1340
1360
1380
1400
1420
1440
1460
1480



Legend

- GPD Property Outline
- 2012 Kyrotek Soil Samples
- Watercourse

Contour (20m)

- Elevation

GOLDEN PREDATOR

Livingstone

Kyrotek Soil
Sample Locations
DAC

0 75 150 225 300
Meters

Scale:	1:6,000	Map ID:	--
Draw Date:	2012/11/16	Rev. Date:	
Version:	1	Figure:	Appendix 6-1
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121116_2011App6-1An		

539,000 540,000 541,000 542,000 543,000

6,805,000 6,804,000 6,803,000 6,802,000

N


DAC

RNB

K960441 K960440 K960438 k960439 K960437 K960435 K960436 K960434 K960433 K960432 K960431 K960430 K960429 K960428 K960427 K960426 K960425 K960424 K960423

K960691 K960692 K960693 K960694 K960696 K960697 K960695 K960699 K960700 K960698 K960401 K960403 K960404 K960405 K960407 K960402 K960406 K960410 K960408 K960411 K960409 K960412 K960413 K960414 K960092 K960093 K960094 K960095 K960096 K960099 K960100 K960651 K960652 K960654 K960655 K960656 K960658 K960659 K960660 K960661 K960662 K960663 K960664 K960666 K960667 K960669 K960670 K960671 K960672 K960674 K960675 K960677 K960678 K960680 K960681 K960682 K960683 K960685 K960686 K960687 K960688 K960689 K960690 K960684 K960673 K960676 K960679 K960668 K960665 K960657 K960653 K960097 K960091 K960415 K960416 K960417 K960418 K960419 K960420 K960421 K960422

1340 1240 1140 1220 1040 1300 1020 1060 1100 1220 1080 1160 1200 1400 1440 1260 1280 1320 1360 1340 1420 1500 1540 1520 1560 1480 1460 1380 1300 1240 1320 1280 1360 1400 1420 1440 1460 1380 1340 1260 1200



Legend

- GPD Property Outline
- 2012 Kyrotek Soil Samples
- Watercourse

Contour (20m)

- Elevation

GOLDEN PREDATOR

Livingstone

Kyrotek Soil
Sample Locations
RNB

0 190 380 570 760


Meters

Scale:	1:15,000	Map ID:	--
Draw Date:	2012/11/16	Rev. Date:	
Version:	1	Figure:	Appendix 6-2
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121116_2011App6-2An		

537,000 538,000 539,000 540,000

6,798,000 6,797,000 6,796,000

RNB



Legend

- GPD Property Outline
- 2012 Kyrotek Soil Samples
- Watercourse

Contour (20m)

- Elevation


GOLDEN PREDATOR

Livingstone

Kyrotek Soil
Sample Locations
RNB - 2

0 160 320 480 640
Meters

Scale:	1:12,500	Map ID:	--
Draw Date:	2012/11/16	Rev. Date:	
Version:	1	Figure:	Appendix 6-3
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121116_2011App6-3An		



Legend

- GPD Property Outline
- 2012 Kyrotek Soil Samples
- Watercourse

Contour (20m)

- Elevation


GOLDEN PREDATOR


Livingstone

Kyrotek Soil
Sample Locations
SRVD - OVS

0 200 400 600 800
Meters

Scale:	1:17,500	Map ID:	--
Draw Date:	2012/11/16	Rev. Date:	
Version:	1	Figure:	Appendix 6-4
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121116_2011App6-4		





Legend

- GPD Property Outline
- 2012 Kyrotek Soil Samples
- Watercourse

Contour (20m)

- Elevation


GOLDEN PREDATOR


Livingstone

Kyrotek Soil
Sample Locations
SRVD - OVS - RNB

0 110 220 330 440
Meters

Scale:	1:10,000	Map ID:	--
Draw Date:	2012/11/19	Rev. Date:	
Version:	1	Figure:	Appendix 6-5
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121116_2011App6-5		





Legend

- GPD Property Outline
- Watercourse
- Elevation (100 m)

Au (ppb)

- 0.0 - 1.6
- 1.7 - 3.6
- 3.7 - 8.8
- 8.9 - 16.4
- 16.5 - 248.4

GOLDEN PREDATOR

Livingstone


Kyrotek


Soil Sample Results

0 0.7 1.4 2.1 2.8

Kilometers

Scale:	1:63,298	Map ID:	--
Draw Date:	2012/11/19	Rev. Date:	
Version:	1	Figure:	Appendix 6-6
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121119_2011App6-6		





Legend

- GPD Property Outline
- Watercourse
- Elevation (100 m)

Ag (ppm)

- 0.0 - 0.3
- 0.4 - 0.7
- 0.8 - 1.3
- 1.4 - 2.3
- 2.4 - 15.6

GOLDEN PREDATOR

Livingstone


Kyrotek


Soil Sample Results

0 0.75 1.5 2.25 3

Kilometers

Scale:	1:63,298	Map ID:	--
Draw Date:	2012/11/19	Rev. Date:	
Version:	1	Figure:	Appendix 6-7
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121119_2011App6-7		





Legend

- GPD Property Outline
- Watercourse
- Elevation (100 m)

As (ppm)

- 0.0 - 4.1
- 4.2 - 9.6
- 9.7 - 26.6
- 26.7 - 47.0
- 47.1 - 429.5

GOLDEN PREDATOR

Livingstone


Kyrotek


Soil Sample Results

0 0.75 1.5 2.25 3

Kilometers

Scale:	1:63,298	Map ID:	--
Draw Date:	2012/11/19	Rev. Date:	
Version:	1	Figure:	Appendix 6-8
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121119_2011App6-8		





Legend

- GPD Property Outline
- Watercourse
- Elevation (100 m)

Mo (ppm)

- 0.0 - 0.5
- 0.6 - 0.8
- 0.9 - 1.1
- 1.2 - 1.7
- 1.8 - 7.3

GOLDEN PREDATOR

Livingstone


Kyrotek


Soil Sample Results

0 0.75 1.5 2.25 3

Kilometers

Scale:	1:63,298	Map ID:	--
Draw Date:	2012/11/19	Rev. Date:	
Version:	1	Figure:	Appendix 6-10
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121119_2011App6-10		





Legend

- GPD Property Outline
- Watercourse
- Elevation (100 m)

Pb (ppm)

- 0.0 - 7.2
- 7.3 - 10.2
- 10.3 - 14.0
- 14.1 - 17.4
- 17.5 - 135.0

GOLDEN PREDATOR

Livingstone


Kyrotek


Soil Sample Results

0 0.75 1.5 2.25 3

Kilometers

Scale:	1:63,298	Map ID:	--
Draw Date:	2012/11/19	Rev. Date:	
Version:	1	Figure:	Appendix 6-11
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121119_2011App6-11		





Legend

- GPD Property Outline
- Watercourse
- Elevation (100 m)

Sb (ppm)

- 0.0 - 0.3
- 0.4 - 0.6
- 0.7 - 1.5
- 1.6 - 4.6
- 4.7 - 34.4

GOLDEN PREDATOR

Livingstone


Kyrotek


Soil Sample Results

0 0.75 1.5 2.25 3

Kilometers

Scale:	1:63,298	Map ID:	--
Draw Date:	2012/11/19	Rev. Date:	
Version:	1	Figure:	Appendix 6-12
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121119_2011App6-12		





Legend

- GPD Property Outline
- Watercourse
- Elevation (100 m)

Zn (ppm)

- 0 - 48
- 49 - 58
- 59 - 71
- 72 - 79
- 80 - 240

GOLDEN PREDATOR

Livingstone

Kyrotek


Soil Sample Results


0 0.75 1.5 2.25 3

Kilometers

Scale:	1:63,298	Map ID:	--
Draw Date:	2012/11/19	Rev. Date:	
Version:	1	Figure:	Appendix 6-13
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121119_2011App6-13		

Appendix 7
Rock Location Plots





Legend

- GPD Property Outline
- Watercourse
- Rock Sample ID

Imperial Contour (100ft)

- Elevation


Livingstone


2011 Rock Sample Locations - SRVF

0 50 100 150 200

Meters

Scale:	1:5,000	Map ID:	--
Draw Date:	2012/11/20	Rev. Date:	
Version:	1	Figure:	Appendix 7-1
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121120_2011App7-1		





Legend

- GPD Property Outline
- Watercourse
- Rock Sample ID

Imperial Contour (100ft)

- Elevation

GOLDEN PREDATOR


Livingstone


2011 Rock Sample Locations - SRVB

0 20 40 60 80

Meters

Scale:	1:2,000	Map ID:	--
Draw Date:	2012/11/20	Rev. Date:	
Version:	1	Figure:	Appendix 7-2
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121120_2011App7-2		





Legend

- GPD Property Outline
- Watercourse
- Rock Sample ID

Imperial Contour (100ft)

- Elevation

GOLDEN PREDATOR

Livingstone

2011 Rock Sample Locations - SRVF + SRVB

0 140 280 420 560

Meters

Scale:	1:12,501	Map ID:	--
Draw Date:	2012/11/20	Rev. Date:	
Version:	1	Figure:	Appendix 7-3
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121120_2011App7-3		

541,000

542,000

543,000

6,831,000


6,830,000

J971705
J971831
J971702
J971703
J971704
J971830
J971829
J971828
J971824
J971826
J971827
J971693 J971698
J971694 J971700
J971695 J971701
J971696 J971699
J971697 J971825

SRVB

J971709
J971710
J971711
J971712
J971832
J971833
J971836
J971713
J971714
J971834
J971835
J971707
J971708
J971706

4300 4400 4500 4600 4700 4100 4000 4200 4900 4800 5200 5400 5300 5700 5800 5600 5000 5100 5500 5900 6000 6100 5800



Legend

- GPD Property Outline
- Watercourse
- Rock Sample ID

Imperial Contour (100ft)

- Elevation

GOLDEN PREDATOR


Livingstone


2011 Rock Sample Locations - SRVB (south)

0 75 150 225 300

Meters

Scale:	1:7,500	Map ID:	--
Draw Date:	2012/11/20	Rev. Date:	
Version:	1	Figure:	Appendix 7-4
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121120_2011App7-4		





Legend

- GPD Property Outline
- NTS Mapsheet
- Watercourse
- Rock Sample ID

Imperial Contour (100ft)

- Elevation

Contour (20m)

- Elevation

GOLDEN PREDATOR


Livingstone


2011 Rock Sample Locations - JJW + MCPN

0 125 250 375 500

Meters

Scale:	1:12,500	Map ID:	--
Draw Date:	2012/11/20	Rev. Date:	
Version:	1	Figure:	Appendix 7-5
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121120_2011App7-5		





Legend

- GPD Property Outline
- NTS Mapsheet
- Watercourse
- Rock Sample ID

Imperial Contour (100ft)

- Elevation

Contour (20m)

- Elevation

GOLDEN PREDATOR

Livingstone

2011 Rock Sample Locations - SRVD

0 50 100 150 200

Meters

Scale:	1:5,000	Map ID:	--
Draw Date:	2012/11/20	Rev. Date:	
Version:	1	Figure:	Appendix 7-6
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121120_2011App7-6		

534,000
535,000
536,000
6,809,000
6,808,000
6,807,000

N


K948220
K948221
K948222
K948223
K948224
K948225
K948226

J971755
J971756
J971757
J971758

DAC

DACX

K948206
K948207



Legend

- GPD Property Outline
- Watercourse
- Rock Sample ID

Contour (20m)

- Elevation

GOLDEN PREDATOR

Livingstone

2011 Rock Sample Locations - DAC + DACX

0 100 200 300 400
Meters

Scale:	1:10,000	Map ID:	--
Draw Date:	2012/11/20	Rev. Date:	
Version:	1	Figure:	Appendix 7-7
Author:	E. O'Brien	Office:	Vancouver
Location:	Livingstone District		
Projection:	NAD 1983 UTM Zone 8N		
Filename:	LIV_20121120_2011App7-7		