Sumac Mines Ltd.

2013 GEOLOGICAL AND GEOCHEMICAL REPORT ON THE POLLY PROPERTY

Whitehorse Mining District
NTS 115G/09
61° 40.25' North Latitude
138° 20.40' West Longitude

-prepared for-

SUMAC MINES LTD.
901 – 700 West Pender St.
Vancouver, BC
V6C 1G8

-prepared by-

Murray Jones, M.Sc., P.Geo.
EQUITY EXPLORATION CONSULTANTS LTD.
Suite 200, 900 West Hastings Street
Vancouver, British Columbia, Canada, V6C 1G8

December, 2013

EQUITY

TABLE OF CONTENTS

TABLE OF CONTENTS i
LIST OF APPENDICES i
LIST OF TABLES i
LIST OF FIGURES ii
LIST OF PLATES ii
1.0 SUMMARY 1
2.0 INTRODUCTION 1
3.0 RELIANCE ON OTHER EXPERTS 1
4.0 PROPERTY DESCRIPTION AND LOCATION 4
5.0 ACCESSIBILITY, CLIMATE, LOCAL RESOURCES, INFRASTRUCTURE, PHYSIOGRAPHY 4
6.0 HISTORY 4
6.1 2013 Exploration Program 5
7.0 REGIONAL GEOLOGY AND MINERALIZATION 6
8.0 PROPERTY GEOLOGY AND MINERALIZATION 8
9.0 SOIL SAMPLING 10
10.0 DISCUSSION AND CONCLUSIONS 11
11.0 RECOMMENDATIONS 12

LIST OF APPENDICES

Appendix A: Bibliography
Appendix B: Statement of Expenditures
Appendix C: Rock Descriptions
Appendix D: Geochemical Certificates
Appendix E: Quality Assurance/Quality Control
Appendix F: Geologist's Certificate

LIST OF TABLES

Table 1: Claim Data, Polly Property 4
Table 2: Statigraphy of the Nisling and Ruby Ranges Area (after Israel et al, 2011b) 6
Table 3: Significant 2013 Rock Samples, Polly Property 10
Table 4: Polly* Soil Geochemistry Statistics 10
Table 5: Polly Soil Geochemistry Correlation Matrix 10

LIST OF FIGURES

Figure 1: Location Map 2
Figure 2: Tenure Map 3
Figure 3: Regional Geology 7
Figure 4: Property Geology and Compilation (1:10,000) ..... pocket
Figure 5a: Rock and Soil Geochemistry, Sample Location (1:10,000) ..... pocket
Figure 5b: Rock and Soil Geochemistry, Copper (1:10,000) ..... pocket
Figure 5c: Rock and Soil Geochemistry, Gold (1:10,000) ..... pocket
Figure 5d: Rock and Soil Geochemistry, Molybdenum (1:10,000) ..... pocket
Figure 5d: Rock and Soil Geochemistry, Zinc (1:10,000) ..... pocket

LIST OF PLATES

Plate 1: Dänna Jaw Showing in Polly Soil area. Showing is delineated by yellow dashed lines. Grab and select samples in 2013 from this zone returned up to 0.50% Zn. View looking south-east from central ridge. 9

1.0 SUMMARY

The Polly property (Figure 1) consists of 196 quartz mining claims in the Talbot Creek-Dwarf Birch Creek area of southwest Yukon. The property lies within the Yukon Coast Belt and includes rocks of the Yukon Tanana terrane, Ruby Range intrusive rocks and younger felsic volcanic and sub-volcanic intrusive rocks. The north half of the property is underlain primarily by siliciclastic metamorphosed rocks of the Yukon-Tanana, whereas the south half is underlain by medium to coarse grained monzonite, monzo-diorite and granodiorite intrusive rocks of the Ruby Range suite. Variably feldspar and quartz porphyritic intermediate to felsic sub-volcanic and volcanic rocks occur in throughout the property. Bands of calc-silicate-rich quartzite and garnet-pyroxene skarn, with local concentrations of pyrrhotite and magnetite and minor disseminations of chalcopyrite and sphalerite occur mostly in the northwest portion of the property. Fracture-controlled molybdenum mineralization is present at the margins of the Ruby Range intrusive rocks in the south half of the property.

In 2013 Sumac Mines Ltd. (Sumac) contracted Equity Exploration Consultants Ltd. (Equity) to manage a geological mapping, prospecting, and rock and soil sampling program on the property. Soil sampling and geological mapping in the north Polly area was designed to search for extensions to the copper-gold-zinc mineralization, the Dänna Jaw Showing, identified in earlier reconnaissance work. Soil sampling has identified a discontinuous Zn-Ag anomaly covering about 800 by 450 metres, possibly stratigraphic in nature, with scattered gold and copper results in the southeast part of the grid. As well, a distinct gold anomaly follows the lineament in the central part of the grid for about 1200 metres. In the south area, there is a gold-copper-molybdenum anomaly in the roof pendant just east of the Polly Moly Showing. A roughly 500 by 500 metre molybdenum-only soil anomaly is present in the extreme southeast corner of the property.

There are limited recommendations for more work on the Polly property. Before any further fieldwork is done, the release in early 2014 of processed airborne geophysical data by the Yukon government should be checked for coverage of the Polly property and examined for interesting correlations with any of the soil anomalies or known showings. The gold soil anomaly on the Polly Soil grid should be prospected in detail. If there is a structure that is responsible for the large strike length of the anomaly there may be potential for economic mineralization within it. The molybdenum anomaly in the southeast corner of the property should be given a cursory look as there has been no prospecting or mapping in that immediate area. There is room to do some additional work to expand the Dänna Jaw Showing particularly to the north where the soil results are more interesting. Overall, prospecting and geological mapping work would only require a few days of helicopter supported field work.

2.0 INTRODUCTION

This report has been prepared to describe a geological mapping, prospecting, and soil sampling program conducted on the Polly Property between August 3rd and 11th, 2013. The material in this report is a result of this work which builds upon work documented in previous reports (Jones, 2012; Bressler and Corbett, 2009). The author was involved in the planning and execution of the 2013 field program.

3.0 RELIANCE ON OTHER EXPERTS

Other than data gleaned from previous reports on the property and government geological and geochemical survey reports, the author has not relied upon other experts for the information in this report.




SUMAC MINES LTD.

Polly Property

LOCATION MAP

EQUITY	Date: DEC 2013	Scale: 1:7,000,000	Figure 1
	U.T.M. Zone: UTM7 - NAD83	Mining District: WHITEHORSE	
	N.T.S.: 115G/09	State/Province: YUKON	



2,000 m

SUMAC MINES LTD.

Polly Property

TENURE MAP

EQUITY	Date: DEC 2013	Scale 1:50,000	Figure
	U.T.M. Zone UTM7 - NAD83	Mining District WHITEHORSE	2
	N.T.S. 115G/09	State/Province YUKON	

4.0 PROPERTY DESCRIPTION AND LOCATION

The Polly property is situated about 18 kilometres east-northeast of the north end of Talbot Arm on Kluane Lake in the southwestern Yukon and is roughly centred at 61° 40.25' north latitude and 138° 40.20' west longitude (Figure 1).

The Polly property (Figure 2) consists of one hundred ninety-six contiguous quartz mineral claims for a total of 3,987.9 hectares (9,854 acres) in the Whitehorse Mining District of the Yukon, as summarized in Table 1 below.

Yukon government records indicate that the claims are owned 100% by Equity Exploration Consultants Ltd. and separate documents indicate that the claims are beneficially held in trust for Sumac Mines Ltd.

Table 1: Claim Data, Polly Property

Claim Name	Tenure Number	Recorded Owner	Recording Date	Expiry Date
Polly 1-196	YF36501-696	Equity Exploration Consultants Ltd.	July 23, 2012	July 23, 2014

5.0 ACCESSIBILITY, CLIMATE, LOCAL RESOURCES, INFRASTRUCTURE, PHYSIOGRAPHY

The Polly property covers ground of moderate relief near the headwaters of Talbot and Dwarf Birch Creeks. Elevation ranges from 1250 metres on Dwarf Birch Creek to over 1950 metres at Nisling Peak on the ridge in the southeast part of the property. The property is about 50 kilometres from the community of Burwash Landing to the southwest and can be accessed by helicopter from bases in Carmacks (120 kms east) or Haines Junction (106 kilometres to the south). The property is primarily above treeline but the lower and south facing slopes do have growth of black spruce and alders. The Polly property has a northern continental climatic regime, with warm, fairly brief summers and long, cold winters. Precipitation is generally moderate. Fieldwork is most efficiently carried out during the summer season as logistics and access to water are a problem the rest of the year.

6.0 HISTORY

The area was explored in the 1970's at the height of porphyry copper exploration activities in the southwest Yukon. The Dwarf Minfile occurrence (#115G 076, Porphyry Mo, Low F-type) is located in the south Polly area. There was work done on the Polly claims in the past, mostly on the north half of the property. In 1972, Dynasty Explorations (Dean, 1972) followed up reconnaissance results from 1971 with 1:15,840 scale geological mapping and soil sampling in the north half of the Polly claims, north of Dwarf Birch Creek. They analysed for Cu, Pb, Zn in soils, and Cu in a few rocks, primarily to establish a background value in the intrusive rocks. Dean (1972) noted rhyolite-cemented breccia pipes, sparse chalcopyrite and molybdenite in dry fractures in alaskite and quartzite but found no alteration or mineralization indicative of economic mineralization. Overall, soil results were deemed to reflect weak base metal mineralization in contact metamorphic zones around an alaskite intrusion. They worked the Polly Soil area but did not examine the area of Polly Moly Showing.

Also in 1972, Canadian Occidental Petroleum Ltd. conducted similar exploration work on the adjacent BIR claims primarily east of the current Polly claims (Winfield and Gleeson, 1972). In 1973, Canadian Occidental staked and explored the RIB claims to the south of the BIR property, conducting geological mapping, soil geochemical sampling, and ground magnetometer surveying, as well as ground magnetometer

work on adjacent BIR claims. The work on these claims in 1972 and 1973 led to the discovery of numerous zones of low grade molybdenum mineralization, with copper and zinc, in fractures and watery quartz veins in the local granitic intrusion. Skarn mineralization consisting of chalcopyrite and pyrite mineralization, with minor sphalerite was also discovered in the overlying meta-sedimentary rocks of the Yukon Tanana terrane.

In 1987, United Keno Hill Mines did a very small program on the 4 TAL claims, covering the Polly Soil area (Ouellette, 1988). They completed a one day, two person survey doing prospecting and soil sampling. They re-examined the showings from 1972, did not collect any rock samples and took 10 soil samples on two wide spaced lines. The best result was a soil that ran 25 ppb Au. Overall, very minimal work was done and the results were inconclusive.

Regional geochemical sampling by Pathfinder Minerals (PFM) on behalf of Sumac detected a series of coincident molybdenum-copper-arsenic stream silt anomalies in the south half of the Polly property focused on the contact between the large granitic body in this area to the south and quartzite and phyllite to the north. Additionally, anomalous copper and gold silt results were found in the Polly Soil area on the north side of the Dwarf Birch Creek valley and ridge and spur soil samples taken in 2008 returned anomalous Au, Zn and Cu on the ridge above Cracker Creek. Geological mapping and prospecting turned up zinc-copper-gold mineralization associated with garnet-pyroxene-magnetite skarn within the Yukon Tanana meta-sedimentary rocks.

In 2012, Equity spent two crew days (8 person-days) investigating the geology and a number of geochemical anomalies in the uppermost Dwarf Birch drainage area. The area was divided into two parts for investigation: the Polly Contact area, on the south side of Dwarf Birch Creek, centred on the contact between Ruby Range botholith to the south and quartzite and phyllite to the north, and; the Polly Soil area, on the north side of the Dwarf Birch Creek valley where soils taken in 2008 returned anomalous Au, Zn and Cu. In the Polly Soil area (2 person-days), 7 rock and 41 soil samples were taken. In the Polly Contact area (6 person-days), 15 rock and 132 soil samples were taken in 2012. In the course of this work an area of low grade copper-molybdenum mineralization that occurs in fractures and skarn over an area of 300 by 250 metres, dubbed the Polly Moly Showing, was discovered at the contact between granitic intrusion and calc-silicate meta–sedimentary rocks along a spur west of the main peak. Following this work a total of 196 mineral claims were staked to cover the two Polly areas (Figure 2).

6.1 2013 Exploration Program

In 2013, a four person crew from Equity (geologist, prospector, 2 soil samplers) carried out geological mapping, prospecting and soil sampling on the Polly Property. The work was done in two areas, the Polly Moly area to the south of Dwarf Birch Creek and the Polly Soil area (north half of the property). Fieldwork was based out of two fly camps on the property with helicopter support. A magnetic declination of 21.5° East was used for all measurements and maps use the NAD-83 datum.

Four crew days were spent in the Polly Moly area resulting in 228 grid (400 by 100 m) and contour (100 metre spacing) soil samples and 16 rock samples. Five crew days were spent in the Polly Soil area producing 291 soil samples on a 200 metre by 100 metre grid and 27 rock samples. All totals include duplicates and blanks.

Soil lines were indicated in the field with orange flagging and soil sample sites by a combination of blue and orange flagging and a tyvek tag marked with the sample number. Rock sample sites were indicated in the field by a combination of blue and pink flagging and sample information, including sample number, type, date and sampler's initials, were written on the aluminum tag. All samples were submitted to the ALS Minerals Division prep facility in Whitehorse, Yukon and analysed by ALS Minerals at their North Vancouver lab for gold (30 g aliquot) by FA-AA (fire assay-atomic absorption) and for 35 elements by ICP-AES (inductively coupled plasma-atomic emission spectroscopy). Rock sample descriptions can be found in Appendix C and analytical certificates can be found in Appendix D. A discussion of the quality control and quality assurance program is included in Appendix E.


7.0 REGIONAL GEOLOGY AND MINERALIZATION

The regional geology of the Aishihik Lake-Kluane Lake area of the southwestern Yukon (Figure 3) is depicted in a compilation by Gordey and Makepeace (1999) primarily based on earlier 1:250,000 scale regional geological mapping. More recently, the local geology has been summarized by (Israel et al, 2011a, b). The main geological elements of the area are the Yukon-Tanana terrane, the Kluane Schist, a gneissic unit of unknown affinity, intrusions of the Ruby Range batholith, and younger volcanic rocks of the Rhyolite Creek volcano-plutonic complex.

The Yukon-Tanana terrane occupies the highest structural level in the area, overlying the Ruby Range Batholith, but is probably the oldest unit. Ages of 351 to 343 Ma reported from meta-igneous rocks provide a minimum age constraint. The terrane consists of psammitic schist, quartzite, marble, garnet amphibolites and rare meta-plutonic rocks. Locally, the quartzite and schist units are carbonaceous and contain minor carbonate layers. In the east, the Yukon-Tanana rocks are more strongly metamorphosed in the aureole of the Aishihik Batholith. The rocks in the east area are dominantly schist with carbonaceous quartzite and garnet amphibolite.

Table 2: Statigraphy of the Nisling and Ruby Ranges Area (after Israel et al, 2011b)

Age/Unit	Description
PALEOCENE	
Rhyolite Creek Complex	Volcanic rocks; light grey to green intermediate to felsic flows, tuff, local breccia
(ca 57 Ma)	Plutonic rocks; light grey to purple quartz, feldspar porphyry, thin dykes to large intrusive bodies
Ruby Range batholith	Fine to coarse grained, salt and pepper, hornblende+/-biotite, quartz diorite; medium-grained light grey to pink biotite+/-hornblende granodiorite; fine to medium-grained beige to grey tonalite; pinkish grey biotite granite
(ca. 64-57 Ma)	
LATE CRETACEOUS	
Kluane Schist	Dark grey to black, fine grained quart-biotite schist and light to dark grey, fine grained, quartz-muscovite schist, variably carbonaceous, rare carbonate lenses
LATE CRETACEOUS OR OLDER	
Gneiss	Beige to orange to grey-black, medium to coarse grained orthogneiss, abundant garnet up to 2 cm, age uncertain
UPPER DEVONIAN AND OLDER	
Yukon-Tanana Terrane	
Finlayson Assemblage	Polydeformed and metamorphosed mafic to felsic metavolcanic rocks, carbonaceous pelite, quartzite and psammite, quartz-muscovite schist, light grey to beige marble, rare meta-plutonic rocks; garnet common
Snowcap Assemblage	Polydeformed and metamorphosed quartzite, psammite, pelite and marble, minor garnet amphibolite, quartz-muscovite schist, rare meta-plutonic rocks



Stratigraphic Rocks

Quaternary

- Q — silt/sand/gravel

Lower Eocene

- PgTK — mudstone/sandstone

Devonian to Cretaceous?

- DKWR — limestone/marble

Upper Cretaceous

- uKC — tuff/plugs/necks/flows/porphyry

Devonian, Mississippian and(?) older

- DMN — quartzite/qt-ms-schist

Proterozoic and Paleozoic

- PPN — marble
- PPa — cl-bi-schist/amphibolite

Intrusive Rocks

Early Tertiary

- ETqB — granite/alaskite/quartz monzonite/granodiorite
- ETg — granodiorite/quartz monzonite/quartz diorite

Late Cretaceous to Tertiary

- LKqS — porphyry

mid-Cretaceous

- mKS — andesite/dacite/breccia/tuffs/rhyolite/porphyry
- mKgW — granodiorite/quartz diorite

Early Jurassic

- EJgB — granodiorite/diorite/monzodiorite
- EJqL — quartz monzonite/granite/aplite/pegmatite

Carboniferous and Permian

- DTrS — dunite/peridotite/harzburgite/diabase/serpentinite

Late Devonian to Mississippian

- DMgM — orthogneiss

Proterozoic to Mesozoic

- m — cd-st-hornfels/qt-se-cl-schist

From: Gordey, S.P. and Makepeace, A.J. (comp.) 1999

SUMAC MINES LTD.

Polly Property

Regional Geology MAP

EQUITY

Date: DEC 2013	Scale: 1:500,000	Figure 3
U.T.M. Zone: UTM7 - NAD83	Mining District: WHITEHORSE	
N.T.S.: 115G/09	State/Province: YUKON	

The Kluane Schist unit represents metamorphic rocks that primarily lie between the Denali Fault and the Ruby Range batholith. The age of the unit is poorly constrained but is thought to be younger than ~95 Ma and older than ~82 Ma (Israel et al, 2011b). The Kluane Schist comprises monotonous meta-pelitic quartz-mica schist, separable into quartz-muscovite schist lying between two layers of quartz-biotite schist, with rare bodies of ultramafic and carbonate rocks. The schist is variably carbonaceous, increasing to the northwest. Quartz veining is ubiquitous in the schist and garnet and feldspar porphyroblasts occur locally.

The gneissic unit occurs structurally between the Kluane Schist and the Yukon-Tanana rocks and lies along the lower contact of the Ruby Range Batholith. It is fine to medium grained and banded with darker layers of biotite-hornblende and lighter layers of plagioclase-quartz-potassium feldspar-biotite and appears to be igneous in origin. This unit is not constrained by age dates.

The Ruby Range batholith is a large plutonic complex stretching roughly east-west between Aishihik Lake and Talbot Arm of Kluane Lake. The designation includes smaller, similar intrusions away from the main body. The batholith is composed of quartz-diorite, tonalite and granodiorite with lesser diorite, gabbro and granite. The batholith appears to be tilted on its side with its top to the north. The base of the batholith is characterized by locally strongly foliated quartz-diorite and the complex becomes more felsic and undeformed towards the top. The upper part of the batholith is texturally and compositionally variable. The batholith is locally cut by post-tectonic intrusions of indeterminate age. Magnetite occurs locally in most compositional phases. The age of the Ruby Range batholith ranges from ~64 Ma near the base to 57 Ma in the more felsic and coarse grained phases near the top of the complex. However, local dates suggest portions of the complex may be as old as 71 Ma (Israel et al, 2011b).

The Rhyolite Creek complex is the youngest, porphyritic phase of the Ruby Range batholith and its volcanic equivalents and represents the youngest rocks in the area. The complex includes both intrusive and extrusive rocks. The volcanic rocks are intermediate to felsic flows, breccias and tuffs. The felsic volcanic rocks are normally associated with purple to beige weathering, quartz and feldspar porphyritic intrusions and dome structures. Age dating has pegged these rocks at ~57 Ma.

Structural relationships indicate south-westward thrusting of the Yukon-Tanana terrane over the Kluane Schist with syn- to post-deformation intrusion of the Ruby Range batholith.

Known mineralization in the region of the Polly property consists of two main styles; porphyry-epithermal and orogenic gold mineralization as seen in several occurrences throughout the area (Israel et al, 2011b). The upper level of the Ruby Range batholith appears to most prospective for Cu-Mo-Au porphyry and Au-Ag epithermal mineralization. Orogenic gold occurrences are concentrated within the Kluane Schist.

8.0 PROPERTY GEOLOGY AND MINERALIZATION

The geology in the middle and south part of the Polly claims (Figure 4) is dominated by a large granitic or granodioritic intrusion (**GRNT**) and its thermal metamorphic aureole. The intrusion is a mega-crystic K-spar porphyry with significant hornblende phenocrysts and clots throughout and it is weakly magnetic locally. This intrusion is part of the Ruby Range batholith that underlies a large proportion of the area between Aishihik Lake and Kluane Lake. There is generally greater than 10% quartz in the groundmass and quartz veinlets are common. The intrusion is apparently quite high level as small rafts of quartzite and biotite-quartz schist occur within the intrusion and the rocks surrounding the intrusion are likely situated in the intrusive carapace.

The predominant rock type outside of the intrusion is variably micaceous quartzite (**QRTZ**) and it is commonly gossanous due to hornfels effects, indicated by fine grained biotite (mauve colouration) and the presence of disseminated pyrrhotite and pyrite locally. The intrusion contacts calcareous quartzite (**caQRTZ**) on the ridge west of the south-central peak, resulting in minor magnetite-pyroxene skarn (**SKRN**) formation.

The granite intrusion and meta-sedimentary rocks are cut by large dykes, generally of porphyritic dacite (**DACT**), or intermediate composition. Locally, the dykes are rhyodacitic to rhyolitic, especially in the north part of the property. These intermediate to felsic dykes are part of the Rhyolite Creek complex, which is

wide spread in the region. There does not appear to be any of the extrusive equivalent rocks present on the Polly property. A number of late mafic dykes cut through all units, generally oriented north-south, and these are also commonly gossanous.

The geology in the extreme north part of this area consists primarily of meta-sedimentary rocks, micaceous quartzite, dark quartzite (**dkQRTZ**) phyllitic quartzite (**QRTZ phy**) and calcareous quartzite, with minor pyroxene-garnet skarn. Minor granite (or alaskite) and abundant porphyritic dykes of the Rhyolite Creek Complex cut through the area. As well, there is a large, roughly north-northwest trending fault/lineament in the east half of the Polly Soil grid. East of the fault, there is a section of quartzite and limestone (marble) that is intruded by granite. Bedding dips shallowly to moderately west and southwest. Several 0.5 to 1.0 metre wide, vuggy and layered quartz veins/breccias were observed in this area, sub-parallel to the fault/lineament. Fluorite is a common constituent of the veins. The fault appears to offset the granite in a left lateral sense although the offset is only on the order of 10's of metres.

Surface mineralization occurs in several areas of the Polly property including the Polly Moly Showing in the south area and the Polly Soil occurrence to the north (Jones, 2012). An occurrence of sphalerite in veins and disseminations in skarn near the Polly Soil that was originally sampled in 2012 was extended by prospecting in 2013. A zone of highly oxidized pyroxene-garnet altered skarn extends for approximately 60m along an E-W strike originating from a sample taken in 2012 that contained 1.6% Zn. This newly discovered showing has a variable width of 5-10m and contains samples with significant sphalerite and pyrite in dry fractures. The showing has been dubbed Dänna Jaw (pronounced donna ja-oww, "Where's the Money" in the Southern Tuchone language). Results are summarized in Table 3.

To the south of the Dänna Jaw Showing, along the trend of a calcareous quartzite unit, there is a small area of pyroxene-garnet skarn. A grab sample from this area returned 4.22% Zn, 1260 ppm Cu, 0.668 g/t Au and 12.2 g/t Ag. Soils in this area are elevated in Zn and Ag.



Plate 1: Dänna Jaw Showing in Polly Soil area. Showing is delineated by yellow dashed lines. Grab and select samples in 2013 from this zone returned up to 0.50% Zn. View looking north-east from central ridge.

Table 3: Significant 2013 Rock Samples, Polly Property

Sample Number	Showing	Type	Width m	Au ppm	Ag ppm	As ppm	Cu ppm	Mo ppm	Pb ppm	Zn %
L646639	Dänna Jaw	Float	n.a.	<0.005	9.0	25	2090	<1	1325	0.21
L646643	Dänna Jaw	Float	n.a.	0.028	1.3	10	10	2	25	0.50
L647758	n.a.	Grab	0.10	0.668	12.2	19	1260	1	36	4.22
L647757	n.a.	Grab	0.10	0.098	1.0	1745	81	3	32	0.02
L646614	Polly Moly	Grab	2.0	<0.005	0.2	3	12	377	11	0.01

9.0 SOIL SAMPLING

Soil sampling was done in two main areas with 280 sites in the south half of the property, including 75 grid samples on 4 lines around the Polly Moly Showing and 205 contour soil samples in the southeast part of the property, and 260 sites covering 24.9 line kilometres on the Polly Soil grid in the north half of the property Soil locations are shown on Figure 5a, results on Figures 5b-d and the complete results are found in Appendix D.

Table 4: Polly* Soil Geochemistry Statistics

	Au(ppm)	Ag(ppm)	As(ppm)	Cu(ppm)	Mo(ppm)	Pb(ppm)	Zn(ppm)
Population	833	835	835	835	835	835	835
Max Value	0.118	6.1	566	576	81	1760	5947
Min Value	<0.005	<0.2	<2	<1	<1	<2	<2
98th	0.027	1.4	46	168	22	88	492
95th	0.021	1.1	29	122	9	51	348
90th	0.013	0.7	21	89	7	35	238
85th	0.010	0.6	17	75	5	28	186
70th	0.006	0.3	13	54	3	19	131
50th	<0.005	0.2	10	40	2	13	99

*-includes samples from previous work in Polly area

Table 5: Polly Soil Geochemistry Correlation Matrix

	Au	Ag	As	Cu	Mo	Pb	Zn
Au	1.00						
Ag	0.21	1.00					
As	0.19	0.16	1.00				
Cu	0.32	0.30	0.19	1.00			
Mo	0.06	0.07	0.06	0.40	1.00		
Pb	0.10	0.27	0.07	0.13	0.04	1.00	
Zn	0.32	0.24	0.10	0.31	0.09	0.20	1.00

Most significant soil sample results are found within the Polly Soil grid. There is an anomalous gold trend in the south central part of the grid that follows a creek gully/lineament north 1200 metres from the southernmost grid line. An earlier reconnaissance silt sample from this creek returned highly anomalous results (greater than the 95th percentile) for gold and copper (Corbett and Bressler, 2008). Scattered anomalous gold results covering about 600 by 200 metres are also found in the central part of the grid in the Cracker Creek drainage, with minor associated silver, arsenic and copper. These results are centred on a

large dyke that cuts through the area but may be more likely associated with a skarn horizon that outcrops locally.

There is a large, roughly coincident zinc, silver, barium, lead anomaly, stretching about 1000 by 300 metres in the southeast corner of the Polly Soil grid. This anomaly covers some skarn exposures, including the outcrop that produced sample L647758 (Table 3), and gives the appearance of stratigraphic control as it wraps around the mountain, loosely following the trend of stratigraphy in the area. Another soil anomaly with a similar geochemical signature occurs in the northeast part of the Polly Soil Grid and may be associated with the same stratigraphic horizon. This anomaly covers and area of 800 by 300 metres and contains elevated copper results as well.

Interestingly, the skarn mineralization that has returned the best metal grades in rock samples, at the Danna Jaw and Polly Soil showings and sample L647758, is not consistently associated with anomalous soil results, even for zinc.

In the south part of the Polly property, grid soil sampling around ridge hosting the Polly Moly Showing did not definitively extend this mineralization in any direction although there are a few patchy molybdenum soil anomalies to the north and south. Several hundred metres to the east of the Polly Moly, there is a coincident Cu-Au-Mo-As-Ag soil anomaly that stretches 500 metres along a soil line crossing a roof pendant of quartzite. As well, molybdenum is elevated in soils within the intrusion north of the pendant.

In the extreme southeast part of the property, within the Ruby Range intrusion is a 500 by 250 metre molybdenum-only anomaly that is crossed by two contour lines and remains open to the south and east. This may be the source of the anomalous molybdenum in silt samples from the creeks that drain this area (Bressler and Corbett, 2008). This is the only significant soil anomaly in this part of the Polly Property. A rock sample adjacent to a mafic dyke, about 500 metres west of this anomaly returned 377 ppm Mo, the highest molybdenum value on the property to date.

10.0 DISCUSSION AND CONCLUSIONS

The Polly property is underlain primarily by quartzite and schist of the Yukon-Tanana terrane and medium to coarse grained granodiorite to granite of the Ruby Range batholith. These rocks are in turn intruded by dykes of the late stage Rhyolite Creek Complex that, regionally, includes intrusive and extrusive volcanic rocks. The contact zone of the Ruby Range intrusion is the locus of scattered mineralization, including sheeted quartz veins with molybdenite and chalcopyrite within the intrusion and skarn-disseminated sulphide mineralization, including pyrite, pyrrhotite, sphalerite and chalcopyrite, in the country rocks. Minor late quartz veins and breccia zones containing fluorite cross cut all rock types.

Geochemical work on the property has outlined a large zinc-lead-silver soil anomaly in the southeast part of the Polly Soil grid, associated with dark (carbonaceous) quartzite and zinc-copper mineralization in skarn within calcareous quartzite in the aureole to the Ruby Range intrusion. This anomaly is consistent with identification of similar geochemical anomaly by Corbett and Bressler (2009) that covers a much larger area. The anomaly seems to indicate a stratigraphic control based on the wide spread distribution of anomalous results.

The gold geochemical anomaly in the south-central part of the Polly Soil grid has considerable extent but the values in soil only range up to 0.04 ppm Au. With no rock samples or other coincident anomalous elements for back-up, it is difficult to ascribe significance to the gold geochem.

Scattered molybdenite mineralization is present within and immediately adjacent to the Ruby Range intrusion but does not amount to significant grade where it has been sampled. No rock samples were taken from the large molybdenum soil geochemical anomaly within the intrusion in the extreme southeast part of the property.

In conclusion, exploration in 2013 on the Polly Property has detected a number of large, multi-element soil geochemical anomalies, primarily in the north part of the property in hornfels meta-sedimentary rocks. Bedrock mineralization within these anomalies is either sparse or not observed. The generally diffuse nature


of the anomalies generally does not indicate strongly mineralized source rocks. Copper-gold mineralization on the Polly property primarily lies in the thermal aureole of the Ruby Range intrusion and the best results to date are found in skarn that appears to be of limited extent. The potential for a stratigraphic target has not been investigated

11.0 RECOMMENDATIONS

Prior to any more fieldwork, the results of the Yukon government's processing of the regional airborne magnetic data by Mira Geosciences should be examined for clues to mineralization on the property. There may be details in the results of Mira's work that can be tied to and extrapolated to mineralization on the Polly property, generating potential targets for further work.

Additional work on the Polly property should be limited at this time until indications of a significant mineralizing system can be located. Further prospecting and geological mapping is recommended to investigate a few of the geochemical anomalies. In particular, the cause of the gold geochemical anomaly in the south central Polly soil grid should be determined. The coherent molybdenum in soil anomaly in the southeast corner of the property could be coming from a concentrated source and should be prospected in detail.

Respectfully submitted,



_____

Murray Jones, M.Sc., P.Geo.

EQUITY EXPLORATION CONSULTANTS LTD.

Vancouver, British Columbia

December 2013

Appendix A: Bibliography

Bressler, J.R and Corbett, T.J., 2009. 2008 Western Canada Compilation, Annual Report; internal company report prepared for Sumac Mines Ltd..

Corbett, T.J. and Bressler, J.R., 2008. 2007 Western Canada Compilation, Southwest Yukon Reconnaissance, Annual Report; internal company report prepared for Sumac Mines Ltd., 2 volumes.

Corbett, T.J. and Bressler, J.R., 2009. 2008 Western Canada Compilation, Annual Report; internal company report prepared for Sumac Mines Ltd., 3 volumes.

Dean, P., 1972. Geological and Geochemical Evaluation of the Blue “L”. Mineral Claims, Yukon Territory, Dynasty Explorations Ltd.: Yukon Assessment Report #0620997, 11p., 7 maps, Appendices.

Gordey, S.P. and Makepeace, A.J. (comp.) 1999: Yukon bedrock geology in Yukon digital geology, S.P. Gordey and A.J. Makepeace (comp.); Geological Survey of Canada Open File D3826 and Exploration and Geological Services Division, Yukon, Indian and Northern Affairs Canada, Open File 1999-1(D)

Israel, S. and Westburg, E., 2012. Geology and mineral potential of the northwestern Aishihik lake map area, parts of NTS 115H/12 and 13; in, Yukon Exploration and Geology 2011, K.E. MacFarlane and P.J. Sack (eds.), Yukon Geological Survey, p. 103-113.

Israel, S. and Westburg, E., 2011. Preliminary geological map of the northwestern Aishihilk Lake area, parts of NTS 115H/12 and 13 (1:50,000 scale): Yukon Geological Survey, Open File 2011-31.

Israel, S., Cobbett, R., Westberg, E., Stanley, B., and Hayward, N., 2011b. Preliminary bedrock geology of the Ruby Ranges, southwest Yukon (parts of NTS 115G, 115H, 115A, and 115B) (1:50,000 scale), Yukon Geology Survey, Open File 2011-2.

Israel, S., Murphy, D., Bennett, V., Mortensen, J., and Crowley, J., 2011a. New insights into the geology and mineral potential of the Coast Belt in southwestern Yukon; In: Yukon Exploration and Geology 2010, K.E. MacFarlane, L.H. Weston and C. Relf (eds.), Yukon Geology Survey, p. 101-123..

Jones, M.I., 2012. Geological, Geochemical Report on the Regional Reconnaissance Program, southwest Yukon; internal company report prepared for Sumac Mines Ltd..

Kiss, F. and Coyle, M., 2011. Residual Total Magnetic Field, Aeromagnetic Survey of the Nisling River area, NTS 115G/16 and 115H/13, Yukon; Yukon Geological Survey, Open File 2011-13, scale 1:50,000.

Saracoglu, N., 1973. Geology, Geochemistry and Ground Magnetometry of the RIB Claims, RIB 1-18 Claims, Ground Magnetometry of the BIR Claims (partial), Canadian Occidental Petroleum Ltd.: Yukon Assessment Report #062034, 31 p., 4 maps, Appendices.

Winfield, W.D.B. and Gleeson, C.F., 1972. Geology and Geochemistry of the BIR Claim Group, BIR 1-122 Claims, Canadian Occidental Petroleum Ltd.: Yukon Assessment Report #062034, no maps included in .pdf online.

Yukon Geological Survey, 2011. Bouguer gravity anomaly (regional trend removed) of the Aishihik Lake area, Yukon (parts of NTS 115H, I, and G) (1:50,000 scale); Yukon Geological Survey, Open File 2011-27, 2 maps and data files.

Appendix B: Statement of Expenditures

DAILY FIELD ACCOUNTING SUMMARY

Project: Polly-Raft Field

		UNITS	RATE	SUBTOTAL	TOTAL
WAGES:					
	Project Geologist, Murray Jones.	9.5	$ 700	$ 6,650	
	Geologist, Jesse Kirkby	21.125	$ 575	$ 12,147	
	Prospector, Tom Bell	15	$ 525	$ 7,875	
	Senior Samplers, Whitney Johnson-Ward, Mitch Garrison	27	$ 325	$ 8,775	
	GIS/Logistics (hours)	16	$ 75	$ 1,200	
					$ 36,647
RENTALS (EQUITY AND NON EQUITY)					
Equity Rentals					
	Camp (mandays)	44	$ 40	$ 1,760	
	Chainsaw	2	$ 30	$ 60	
	Field Computer	13	$ 40	$ 520	
	First Aid (Level III)	11	$ 30	$ 330	
	Generator (1kvA)	11	$ 20	$ 220	
	Iridium satphone (minutes)	264	$ 2	$ 499	
	Iridium satphone (weeks)	2	$ 75	$ 150	
Non-Equity Rentals				$ -	
	Hand-held radios, Canadawide Communications	85	$ 3	$ 255	
	Truck 1, K&K Truck Rentals, Whitehorse	14	$ 160	$ 2,240	
	Truck 2 - Eagle Eye Ventures, Smithers, BC	3	$ 100	$ 300	
					$ 6,334
SUBCONTRACTS					
5360	Helicopter, Trans North Helicopters, Whitehorse			$ 17,614	
					$ 17,614
ANALYSES					
	Soils, Au+mulit-element ICP, ALS Labs, Whitehorse	519	23.59	$ 12,243	
	Rock Geochem, Au+mulit-element ICP, ALS Labs, Whitehorse	43	33.45	$ 1,438	
	Assays	2	$ 18	$ 36	
					$ 13,718
EXPENSES					
5370	Airfare (@25%)			$ 427	
5330	Automotive Fuel			$ 704	
5260	Camp Food			$ 1,956	
5250	Camp Supplies			$ 469	
5560	Expediting, Small's Expediting, Whitehorse			$ 636	
5100	Field Supplies			$ 390	
5420	Freight			$ 4,729	
5280	Meals			$ 391	
5180	Printing & Repro			$ 105	
5308	Taxis, Buses, Ferries, Parking, Tolls			$ 87	
	Motels			$ 248	
					$ 10,142
ESTIMATED POST-FIELD EXPENSES					
	Report supplies			$ 200	
					$ 200
SUBTOTAL					$ 84,655
PROJECT SUPERVISION CHARGE					
	10% on expenditures			$ 8,465	
					$ 8,465
TOTAL					$ 93,120

Appendix C: Rock Descriptions

MINERALS AND ALTERATION TYPES

AC	Actinolite	FP	feldspar	PF	plagioclase
AL	alunite	GA	garnet	PH	phlogopite
AM	amphibole	GE	goethite	PL	pyrolusite
AS	arsenopyrite	GL	galena	PO	pyrrhotite
AU	augite	GR	graphite	PY	pyrite
AZ	azurite	HB	hornblende	QZ	quartz veining
BA	barite	HE	haematite	RE	realgar
BI	biotite	HS	specularite	RN	rhodonite
BO	bornite	HZ	hydrozincite	SB	stibnite
BT	pyrobitumen	IL	illite	SD	siderite
CA	calcite	JA	jarosite	SI	silicification
CB	Fe-carbonate	KF	potassium feldspar	SK	skarn
CC	chalcocite	MC	malachite	SM	smithsonite
CD	chalcedony	MG	magnetite	SP	sphalerite
CL	chlorite	MI	mica	SR	scorodite
CP	chalcopyrite	MN	Mn-oxides	SS	sulphosalts
CU	native copper	MO	molybdenite	ST	smectite
CV	covellite	MR	mariposite/fuchsite	TP	topaz
CY	clay	MS	sericite	TT	tetrahedrite
DC	dickite	MT	marcasite	VG	gold
DS	diaspore	MU	muscovite	ZE	Zeolite
DU	dumortierite	NA	natroalunite	ZN	zunyite
EP	epidote	NE	neotocite		
FL	fluorite	PA	pyrargyrite		

ALTERATION INTENSITY

w	weak	s	strong
m	moderate	i	intense

Rock Sample Descriptions

Polly Moly

L646612
SUM13-02

Sampler:
Tom Bell
03/08/2013

Easting:	641205 mE	SampleType:	float	Alteration:	
Northing:	6838422 mN	Sample Width:	m	Metallics:	
Elevation:	m	True Width:	m	Secondaries:	mJA
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	QZ		

Au g/t	Cu ppm	Mo ppm	As ppm
-0.005	1	-1	2
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
-0.2	10	-2	10

Sample glassy,vuggy QZ in garanite-quartzite talus

L646613
SUM13-02

Sampler:
Tom Bell
03/08/2013

Easting:	641314 mE	SampleType:	float	Alteration:	sQZ
Northing:	6838427 mN	Sample Width:	m	Metallics:	trPY
Elevation:	m	True Width:	m	Secondaries:	wGE, wHE, mJA
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	QRTZ		

Au g/t	Cu ppm	Mo ppm	As ppm
-0.005	3	-1	-2
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
-0.2	25	-2	20

Sample talus, 1-10 cm Qtz stringers

L646614
SUM13-02

Sampler:
Tom Bell
03/08/2013

Easting:	641847 mE	SampleType:	float	Alteration:	wQZ
Northing:	6837585 mN	Sample Width:	m	Metallics:	0.5%MO
Elevation:	m	True Width:	m	Secondaries:	wHE, mJA
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	Granite		

Au g/t	Cu ppm	Mo ppm	As ppm
-0.005	12	377	3
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
0.2	26	-2	80

Fine Moly on chill margins of Qtz veins, 1-2cm stringers. Sample over 2m, fair amount in area

L646615
SUM13-02

Sampler:
Tom Bell
03/08/2013

Easting:	641898 mE	SampleType:	float	Alteration:	wQZ
Northing:	6837601 mN	Sample Width:	m	Metallics:	2.5%MG
Elevation:	m	True Width:	m	Secondaries:	sGE, mHE, wJA
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	Granite		

Au g/t	Cu ppm	Mo ppm	As ppm
-0.005	17	21	2
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
1.9	23	-2	70

1-2cm wide glassy qtz veins with clots of Mg, 1m grab of talus

Rock Sample Descriptions

L646616	Easting:	639042 mE	SampleType:	float	Alteration:	sQZ	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6839773 mN	Sample Width:	m	Metallics:	trMO	-0.005	7	3	4
	Elevation:	m	True Width:	m	Secondaries:		**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		-0.2	27	-2	130
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
04/08/2013	Sample with a trace of Mo in talus. Some veining here									
L646617	Easting:	638829 mE	SampleType:	float	Alteration:	sMS	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6839881 mN	Sample Width:	m	Metallics:	0.5%MO, 4%HS	-0.005	87	78	10
	Elevation:	m	True Width:	m	Secondaries:	wGE, mHE, mJA	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		-0.2	93	-2	380
Tom Bell	UTMZone:	7	HostRock:	Schist						
04/08/2013	Traces of Mo on fractures.Grab over 1m in talus									
L646618	Easting:	638589 mE	SampleType:	float	Alteration:	sMS	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6839846 mN	Sample Width:	m	Metallics:	1%PO, 1%PY	-0.005	126	1	4
	Elevation:	m	True Width:	m	Secondaries:	sGE, sJA, sHE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		0.5	24	-2	40
Tom Bell	UTMZone:	7	HostRock:	Granite						
04/08/2013	Disseminated sulfides plus Qtz stringers in talus									
L646619	Easting:	637909 mE	SampleType:	float	Alteration:	sMS	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6840362 mN	Sample Width:	1 m	Metallics:	4%HS, 1.5%PO, 1.5%PY	-0.005	19	3	19
	Elevation:	m	True Width:	m	Secondaries:	sGE, sJA, sHE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		0.5	116	-2	240
Tom Bell	UTMZone:	7	HostRock:	Schist						
04/08/2013	Disseminated sulfides with good oxides in sidehill float, 1m grab									

Rock Sample Descriptions

L646620	Easting:	637950 mE	SampleType:	float	Alteration:	sSI	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6840395 mN	Sample Width:	m	Metallics:	1.5%PO, trPY	-0.005	116	2	3
	Elevation:	m	True Width:	m	Secondaries:	sGE, sJA, sHE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		0.8	70	-2	100
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
04/08/2013	Good Po with oxides in talus.Lots here									
L646621	Easting:	638725 mE	SampleType:	float	Alteration:	wMS	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6840703 mN	Sample Width:	m	Metallics:	7%HS, 2.5%PO, 1.5%PY	0.023	280	7	392
	Elevation:	m	True Width:	m	Secondaries:	sGE, sJA, sHE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		5.6	737	-2	160
Tom Bell	UTMZone:	7	HostRock:	Schist						
04/08/2013	Grab over 2m, good sx and ox in south sidehill talus									
L646622	Easting:	639895 mE	SampleType:	float	Alteration:	wQZ	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6839562 mN	Sample Width:	m	Metallics:	trHS, trPY	-0.005	20	13	2
	Elevation:	m	True Width:	m	Secondaries:	wHE, wJA, wGE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		0.2	61	-2	90
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
05/08/2013	Sample disseminated PY+HS in talus									
L646623	Easting:	640092 mE	SampleType:	float	Alteration:	sCY	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6838452 mN	Sample Width:	m	Metallics:	trPY	-0.005	6	2	3
	Elevation:	m	True Width:	m	Secondaries:	wGE, sHE, sJA	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		-0.2	116	-2	30
Tom Bell	UTMZone:	7	HostRock:	Granite						
05/08/2013	Sample stockwork type qtz in CY alt'd intrusion, Dark glassy, vuggy Qtz, 2-3 rocks									

Rock Sample Descriptions

L646624	Easting:	639627 mE	SampleType:	float	Alteration:	sMS	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6838105 mN	Sample Width:	m	Metallics:	4%PO, 1.5%PY	0.028	345	1	16
	Elevation:	m	True Width:	m	Secondaries:	sGE, sJA, sHE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		0.4	163	-2	100
Tom Bell	UTMZone:	7	HostRock:	BI Schist						
05/08/2013	Gab over 1m area in talus with good sx									
L646625	Easting:	641181 mE	SampleType:	grab	Alteration:	sSI	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6842875 mN	Sample Width:	0.5 m	Metallics:	1.5%PO, 1%PY	-0.005	211	3	6
	Elevation:	m	True Width:	0.5 m	Secondaries:	sGE, sJA, sHE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		1	76	-2	380
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
07/08/2013	Altered Quartzite with milky frothy Qtz stringers, oc sample									
L646626	Easting:	641019 mE	SampleType:	float	Alteration:	sSI	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6843256 mN	Sample Width:	m	Metallics:		0.007	5	-1	16
	Elevation:	m	True Width:	m	Secondaries:	sHE, sJA	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		0.2	106	-2	50
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
07/08/2013	Vuggy Qtz stringers in Quartzite talus. Grab from one talus rock									
L646627	Easting:	640670 mE	SampleType:	float	Alteration:	sSI	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6843657 mN	Sample Width:	m	Metallics:	trCP, trSP	0.005	61	-1	12
	Elevation:	m	True Width:	m	Secondaries:	sHZ, mMC	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		0.3	202	-2	390
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
07/08/2013	Traces of Cpy+Zn in 1 by 1m boulder									

Rock Sample Descriptions

L646628
SUM13-02

Sampler:
Tom Bell
08/08/2013

Easting:	640063 mE	SampleType:	float	Alteration:	sSI
Northing:	6843840 mN	Sample Width:	m	Metallics:	
Elevation:	m	True Width:	m	Secondaries:	sGE, sHE, sJA
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	Quartzite		

Sample heavy oxides in talus from several rocks

Au g/t	Cu ppm	Mo ppm	As ppm
0.008	194	2	140
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
1	713	-2	120

L646629
SUM13-02

Sampler:
Tom Bell
08/08/2013

Easting:	640518 mE	SampleType:	float	Alteration:	sSI
Northing:	6844547 mN	Sample Width:	m	Metallics:	6%HS, trSP
Elevation:	m	True Width:	m	Secondaries:	mGE, sHE, sJA, sMN
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	Quartzite		

sample baked Quartzite(skarney), possible trace zinc?

Au g/t	Cu ppm	Mo ppm	As ppm
0.005	3	1	-2
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
0.8	173	-2	630

L646630
SUM13-02

Sampler:
Tom Bell
08/08/2013

Easting:	640646 mE	SampleType:	float	Alteration:	sMS
Northing:	6844520 mN	Sample Width:	m	Metallics:	1.5%HS
Elevation:	m	True Width:	m	Secondaries:	wJA, sHE, sGE
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	Schist		

Sample strong oxides in schist talus

Au g/t	Cu ppm	Mo ppm	As ppm
0.077	73	3	572
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
1.7	24	-2	180

L646631
SUM13-02

Sampler:
Tom Bell
08/08/2013

Easting:	640646 mE	SampleType:	float	Alteration:	wMS
Northing:	6844520 mN	Sample Width:	m	Metallics:	1.5%HS
Elevation:	m	True Width:	m	Secondaries:	sGE, sHE, wJA
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	Schist		

duplicate of L646630

Au g/t	Cu ppm	Mo ppm	As ppm
0.063	91	3	848
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
1.6	25	-2	240

Rock Sample Descriptions

L646632	Easting:	639385 mE	SampleType:	float	Alteration:	sSI	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6844455 mN	Sample Width:	m	Metallics:	2.5%HS	-0.005	23	3	8
	Elevation:	m	True Width:	m	Secondaries:	sGE, sJA, sHE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		0.3	96	-2	440
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
09/08/2013	Good oxides on fractures with Qtz in Quartzite									
L646633	Easting:	639657 mE	SampleType:	float	Alteration:	sSI, sMS	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6844506 mN	Sample Width:	m	Metallics:		0.81	459	15	150
	Elevation:	m	True Width:	m	Secondaries:	sGE, sHE, sJA	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		75.3	3400	-2	100
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
09/08/2013	Sample heavy Ge with good He,Ja along fractures, common in this area									
L646634	Easting:	639660 mE	SampleType:	float	Alteration:	sSI, sMS	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6844499 mN	Sample Width:	m	Metallics:		0.062	173	3	172
	Elevation:	m	True Width:	m	Secondaries:	sGE, sJA, sHE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		20	1800	5	410
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
09/08/2013	10M from 633 sample lots of rock with good oxides in talus									
L646635	Easting:	639948 mE	SampleType:	float	Alteration:	sMS	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6844470 mN	Sample Width:	m	Metallics:	2.5%HS, 0.5%SP	0.009	52	1	15
	Elevation:	m	True Width:	m	Secondaries:	sGE, sJA, sHE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		1.4	201	-2	110
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
09/08/2013	Sample poss. sphalerite on fractures in 1 football size boulder									

Rock Sample Descriptions

L646636	Easting:	639947 mE	SampleType:	float	Alteration:	sMS	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6844469 mN	Sample Width:	m	Metallics:	2.5%HS, trSP	-0.005	33	1	9
	Elevation:	m	True Width:	m	Secondaries:	sGE, sJA, sHE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		0.7	82	-2	110
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
09/08/2013	1m from 635, sample more traces of Sphalerite in talus									
L646637	Easting:	640131 mE	SampleType:	O.C.	Alteration:	mMS	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6843288 mN	Sample Width:	m	Metallics:	2.5%HS, 1%PY	-0.005	55	5	9
	Elevation:	m	True Width:	m	Secondaries:	mJA, sGE, sHE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		0.5	32	-2	690
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
10/08/2013	Disseminated Py in O.C. in creek bank beside camp									
L646638	Easting:	640208 mE	SampleType:	float	Alteration:	mSI	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6843128 mN	Sample Width:	m	Metallics:	3.5%HS, 1.5%PY	0.006	154	74	85
	Elevation:	m	True Width:	m	Secondaries:	sGE, sJA, sHE	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		0.8	110	-2	290
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
10/08/2013	Disseminated Py in talus. Good oxides									
L646639	Easting:	641155 mE	SampleType:	float	Alteration:	MS, SI	**Au g/t**	**Cu ppm**	**Mo ppm**	**As ppm**
SUM13-02	Northing:	6843456 mN	Sample Width:	m	Metallics:	1%CP, 1%GL, 1%SP	-0.005	2090	-1	25
	Elevation:	m	True Width:	m	Secondaries:	GE, sHE, wMN	**Ag ppm**	**Zn ppm**	**Sb ppm**	**Ba_ppm**
Sampler:	Projection:	NAD83	Structure:		Strike/Dip:		9	2100	-2	190
Tom Bell	UTMZone:	7	HostRock:	Quartzite						
10/08/2013	Deseminated sulfides.5m above Murry's sample									

Rock Sample Descriptions

L646640
SUM13-02

Sampler:
Tom Bell
11/08/2013

Easting:	641148 mE	SampleType:	float	Alteration:	sMS, sEP, sGA
Northing:	6843447 mN	Sample Width:	m	Metallics:	2.5%SP
Elevation:	m	True Width:	m	Secondaries:	sGE, sHE, sMN, wHZ
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	SKRN		

Sample big skarn float with Sph

Au g/t	Cu ppm	Mo ppm	As ppm
0.006	17	6	5
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
0.8	2410	-2	390

L646641
SUM13-02

Sampler:
Tom Bell
11/08/2013

Easting:	641144 mE	SampleType:	float	Alteration:	sMS, sEP, sGA
Northing:	6843447 mN	Sample Width:	m	Metallics:	1%SP
Elevation:	m	True Width:	m	Secondaries:	sGE, sHE, wMN, wHZ
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	SKRN		

Skarn float, semi-mx EP, with Sph. Grab from a few different rocks

Au g/t	Cu ppm	Mo ppm	As ppm
-0.005	29	-1	-2
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
0.4	1940	-2	270

L646642
SUM13-02

Sampler:
Tom Bell
11/08/2013

Easting:	641137 mE	SampleType:	float	Alteration:	sMS, sEP, sGA
Northing:	6843444 mN	Sample Width:	m	Metallics:	0.5%PY, 1%SP
Elevation:	m	True Width:	m	Secondaries:	wGE, wMN, wJA, wHZ
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	SKRN		

Skarn-Qtzite float with Sph+Py. Taken from 2 boulders

Au g/t	Cu ppm	Mo ppm	As ppm
0.005	14	1	10
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
0.8	1630	-2	270

L646643
SUM13-02

Sampler:
Tom Bell
11/08/2013

Easting:	641134 mE	SampleType:	float	Alteration:	sEP, sGA
Northing:	6843436 mN	Sample Width:	m	Metallics:	1.5%SP
Elevation:	m	True Width:	m	Secondaries:	sGE, sHE, sMN, wJA
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	SKRN		

Skarn float with Sph. Grab from a few different rocks

Au g/t	Cu ppm	Mo ppm	As ppm
0.028	10	2	10
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
1.3	5020	-2	260

Rock Sample Descriptions

L646644
SUM13-02

Sampler:
Tom Bell
11/08/2013

Easting:	641130 mE	SampleType:	float	Alteration:	sEP, sGA
Northing:	6843431 mN	Sample Width:	m	Metallics:	1.5%SP, 1.5%PY
Elevation:	m	True Width:	m	Secondaries:	sGE, sMN, wJA, wHZ
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	SKRN		

Au g/t	Cu ppm	Mo ppm	As ppm
0.008	3	8	14
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
0.4	2300	-2	140

Skarn float with Sph and good oxides

L646645
SUM13-02

Sampler:
Tom Bell
11/08/2013

Easting:	641123 mE	SampleType:	float	Alteration:	sEp, sGA
Northing:	6843430 mN	Sample Width:	m	Metallics:	2.5%HS, trSP
Elevation:	m	True Width:	m	Secondaries:	sGE, sHE, sMN
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	SKRN		

Au g/t	Cu ppm	Mo ppm	As ppm
0.007	12	-1	10
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
0.3	1360	-2	230

Skarn float, 50/50 EP/QZ, with HS, Sph. Looks like showing is pinching out here

L646646
SUM13-02

Sampler:
Tom Bell
11/08/2013

Easting:	641125 mE	SampleType:	float	Alteration:	sMS, sEP, mGA
Northing:	6843445 mN	Sample Width:	m	Metallics:	trSP
Elevation:	m	True Width:	m	Secondaries:	sGE, sHE, sMN, mHZ
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	SKRN		

Au g/t	Cu ppm	Mo ppm	As ppm
0.007	4	-1	6
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
0.8	989	6	180

5-7m to the west, sample more Skarn with trace Sph

L647754
SUM13-02

Sampler:
Jesse Kirkby
02/08/2013

Easting:	638792 mE	SampleType:	float	Alteration:	wCL
Northing:	6839767 mN	Sample Width:	0.1 m	Metallics:	2%CP, 1%PY
Elevation:	m	True Width:	0.1 m	Secondaries:	
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	alsk		

Au g/t	Cu ppm	Mo ppm	As ppm
-0.005	50	9	2
Ag ppm	**Zn ppm**	**Sb ppm**	**Ba_ppm**
0.2	21	-2	180

Gossanous coarse grained ALSK. Up to 2% blebbly CP, lesser disseminated PY. FP megacrysts.

Rock Sample Descriptions

L647755
SUM13-02

Sampler:
Jesse Kirkby
03/08/2013

Easting:	639527 mE	SampleType:	grab	Alteration:	mCL, wEP
Northing:	6839420 mN	Sample Width:	0.1 m	Metallics:	1%CP, 1%MO
Elevation:	m	True Width:	0.1 m	Secondaries:	
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	ALSK		

Au g/t	Cu ppm	Mo ppm	As ppm
0.035	23	2	-2

Ag ppm	Zn ppm	Sb ppm	Ba_ppm
-0.2	65	-2	100

Grab sample of possible MO(?) in sheeted qtz veining. CP and MO occur along vein selvages with rare blebbly concentrations. Qtz veins range from .5-2cm

L647756
SUM13-02

Sampler:
Jesse Kirkby
04/08/2013

Easting:	641243 mE	SampleType:	grab	Alteration:	mMS
Northing:	6838852 mN	Sample Width:	0.1 m	Metallics:	2%MG, 2%PY
Elevation:	m	True Width:	0.1 m	Secondaries:	wHE
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	ALSK		

Au g/t	Cu ppm	Mo ppm	As ppm
-0.005	12	1	3

Ag ppm	Zn ppm	Sb ppm	Ba_ppm
-0.2	421	-2	20

Local blebs of magnetite in MS altered ALSK. Weathed and fresh disseminated py, specular hematite on fracture surfaces.

L647757
SUM13-02

Sampler:
Jesse Kirkby
08/08/2013

Easting:	639941 mE	SampleType:	grab	Alteration:	mCL, mSI
Northing:	6842755 mN	Sample Width:	0.1 m	Metallics:	0.5%CP, 0.5%PY
Elevation:	m	True Width:	0.1 m	Secondaries:	wJA, wGE
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	SKRN		

Au g/t	Cu ppm	Mo ppm	As ppm
0.098	81	3	1745

Ag ppm	Zn ppm	Sb ppm	Ba_ppm
1	152	-2	700

Weak CP-PY mineralization in large SKRN outcrop. Pods of unmineralized QRTZ (5-50cm width) within SKRN oriented at all angles resulting in brecciated te

L647758
SUM13-02

Sampler:
Jesse Kirkby
08/08/2013

Easting:	641171 mE	SampleType:	grab	Alteration:	sPX, mGA
Northing:	6842930 mN	Sample Width:	0.1 m	Metallics:	5%PY, 3%CP, 0.1%SP
Elevation:	m	True Width:	0.1 m	Secondaries:	sJA, mGE
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	PX-GA SKRN		

Au g/t	Cu ppm	Mo ppm	As ppm
0.668	1260	1	19

Ag ppm	Zn ppm	Sb ppm	Ba_ppm
12.2	42200	2	90

Grab sample of highly oxidized PX-GA SKRN with possible sp in veinlets.

Rock Sample Descriptions

L647759
SUM13-02

Sampler:
Jesse Kirkby
09/08/2013

Easting:	639720 mE	SampleType:	grab	Alteration:	wCL, wPX, sSI
Northing:	6843729 mN	Sample Width:	0.1 m	Metallics:	2%PY, 1%CP
Elevation:	m	True Width:	0.1 m	Secondaries:	mJA
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	SKRN		

Au g/t	Cu ppm	Mo ppm	As ppm
-0.005	30	2	13

Ag ppm	Zn ppm	Sb ppm	Ba_ppm
-0.2	126	-2	30

Silicified SKRN w/ minor py and cp in small vuggy veinlets. Sample is a small boulder surrounded by QRTZ float with rare GRNT boulders.

L647760
SUM13-02

Sampler:
Jesse Kirkby
10/08/2013

Easting:	639940 mE	SampleType:	grab	Alteration:	sSI, wCL
Northing:	6842758 mN	Sample Width:	0.1 m	Metallics:	1%PY
Elevation:	m	True Width:	0.1 m	Secondaries:	mJA, wGE
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	SKRN-BX		

Au g/t	Cu ppm	Mo ppm	As ppm
0.005	15	4	2

Ag ppm	Zn ppm	Sb ppm	Ba_ppm
0.3	265	-2	50

grab sample from large brecciated SKRN outcrop. Sample contains minor py in small qz vugs.

L647761
SUM13-02

Sampler:
Jesse Kirkby
10/08/2013

Easting:	640447 mE	SampleType:	grab	Alteration:	sSI, wCL
Northing:	6842784 mN	Sample Width:	0.1 m	Metallics:	1%PY, 0.5%CP, 0.1%SP
Elevation:	m	True Width:	0.1 m	Secondaries:	mJA, mGE
Projection:	NAD83	Structure:		Strike/Dip:	
UTMZone:	7	HostRock:	SKRN		

Au g/t	Cu ppm	Mo ppm	As ppm
0.013	26	2	3

Ag ppm	Zn ppm	Sb ppm	Ba_ppm
0.2	113	-2	160

Possible sphalerite mineralization in silicified SKRN float boulder. Minor py and trace cp along dry fractures.

Appendix D: Geochemical Certificates

ALS Canada Ltd.

2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

CERTIFICATE WH13144733

Project: SUM13-02

P.O. No.: SUM13-02_2

This report is for 237 Soil samples submitted to our lab in Whitehorse, YT, Canada on 13-AUG-2013.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	MURRAY JONES	MASAAKI KOYAMA

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
SCR-41	Screen to -180um and save both
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: MURRAY JONES
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

***** See Appendix Page for comments regarding this certificate *****

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
B369951		0.28	0.005	0.3	1.86	7	<10	80	0.6	2	0.29	<0.5	12	33	39	2.78
B369952		0.36	<0.005	<0.2	1.30	8	<10	90	0.5	3	0.17	<0.5	8	24	55	2.50
B369953		0.40	<0.005	<0.2	1.42	7	<10	70	0.5	<2	0.18	<0.5	8	27	31	2.69
B369954		0.25	<0.005	<0.2	0.52	3	<10	40	<0.5	<2	0.18	<0.5	5	8	18	1.66
B369955		0.32	0.005	<0.2	1.21	6	<10	80	1.1	2	0.17	0.5	7	21	35	2.51
B369956		0.35	<0.005	<0.2	1.28	11	<10	70	0.5	<2	0.13	<0.5	8	25	34	3.02
B369957		0.36	0.006	<0.2	1.23	7	<10	60	1.0	<2	0.14	<0.5	6	21	55	2.69
B369958		0.33	<0.005	0.2	2.32	15	<10	210	1.0	<2	1.54	0.6	17	76	49	3.63
B369959		0.28	0.007	0.3	1.81	14	<10	180	1.1	<2	1.33	0.7	13	45	41	2.90
B369960		0.29	<0.005	0.2	1.87	15	<10	190	1.1	<2	1.45	0.7	14	46	42	3.00
B369961		0.21	0.015	0.5	2.49	40	<10	350	1.7	<2	1.28	2.2	14	57	58	3.47
B369962		0.24	<0.005	1.0	0.71	4	<10	60	<0.5	<2	0.57	1.4	13	8	28	1.51
B369963		0.29	0.006	<0.2	1.04	4	<10	80	<0.5	<2	0.52	<0.5	7	15	22	1.86
B369964		0.28	0.005	<0.2	1.26	7	<10	120	<0.5	<2	0.26	0.7	11	25	23	2.34
B369965		0.30	<0.005	0.2	0.71	3	<10	100	<0.5	<2	0.21	1.4	5	12	17	1.45
B369966		0.34	0.006	<0.2	1.81	10	<10	220	0.8	2	0.42	1.8	13	50	38	2.93
B369967		0.22	<0.005	<0.2	0.98	16	<10	150	<0.5	<2	0.15	1.5	9	29	37	3.03
B369968		0.26	0.005	0.2	1.00	9	<10	110	0.5	<2	0.15	1.1	7	21	32	2.34
B369969		0.29	0.007	0.4	1.65	17	<10	180	<0.5	<2	0.09	<0.5	9	43	44	3.81
B369970		0.30	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
B369971		0.28	0.005	0.9	1.49	12	<10	300	0.6	<2	0.59	2.1	10	49	57	3.05
B369972		0.40	0.013	0.8	1.87	15	<10	320	0.7	<2	0.49	1.8	14	60	61	3.41
B369973		0.26	0.005	3.1	2.22	21	<10	390	1.4	<2	0.50	8.8	19	75	165	3.41
B369974		0.24	0.009	5.4	1.48	26	<10	170	0.5	<2	0.18	0.8	11	31	53	3.32
B369975		0.32	0.005	0.9	1.74	24	<10	130	0.5	<2	0.12	<0.5	14	38	48	3.38
B369976		0.29	0.006	0.4	1.42	14	<10	150	0.7	2	0.17	1.0	11	33	63	3.16
B369977		0.32	0.006	0.2	1.42	15	<10	100	0.6	2	0.14	0.5	8	31	40	3.25
B369978		0.24	<0.005	0.2	0.74	6	<10	70	<0.5	<2	0.14	<0.5	5	15	26	1.77
B369979		0.21	0.008	0.5	1.45	19	<10	110	0.7	2	0.17	0.8	8	23	44	2.52
B369980		0.21	<0.005	0.4	1.15	16	<10	80	0.5	<2	0.13	0.6	6	20	32	2.16
B369981		0.19	<0.005	0.5	0.66	5	<10	180	<0.5	<2	0.30	0.6	7	15	19	1.74
B369982		0.29	0.023	1.0	2.03	20	<10	190	0.8	2	0.21	2.8	17	40	59	3.93
B369983		0.25	<0.005	0.4	0.89	6	<10	80	<0.5	<2	0.14	<0.5	8	11	20	1.60
B369984		0.21	<0.005	<0.2	0.69	5	<10	40	<0.5	<2	0.14	<0.5	4	12	12	1.30
B369985		0.34	<0.005	0.2	2.10	4	<10	100	0.6	2	0.27	<0.5	11	41	26	2.95
B369986		0.20	<0.005	<0.2	0.69	3	<10	40	<0.5	<2	0.15	<0.5	4	11	34	1.57
B369987		0.22	<0.005	0.2	1.07	8	<10	170	<0.5	<2	9.3	1.1	10	35	41	1.70
B369988		0.24	<0.005	0.4	0.54	4	<10	120	<0.5	<2	0.32	1.1	5	10	14	1.30
B369989		0.17	<0.005	0.8	0.65	7	<10	150	<0.5	<2	0.19	1.7	5	16	23	2.08
B369990		0.28	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
B369951		10	<1	0.05	10	0.56	393	3	0.01	27	690	31	0.02	<2	3	18
B369952		10	<1	0.06	10	0.36	293	5	0.01	19	560	15	0.03	<2	2	15
B369953		10	<1	0.05	10	0.43	267	6	0.01	22	480	12	0.04	<2	2	15
B369954		<10	<1	0.02	<10	0.14	148	2	0.01	5	690	3	0.03	<2	<1	12
B369955		<10	<1	0.05	40	0.32	496	2	0.01	18	570	27	0.03	<2	2	14
B369956		10	<1	0.05	10	0.38	531	3	0.01	21	660	15	0.08	<2	1	15
B369957		<10	<1	0.05	30	0.31	384	3	<0.01	15	510	47	0.03	<2	2	11
B369958		10	<1	0.37	20	1.37	432	1	0.04	52	1120	20	0.07	<2	7	93
B369959		10	<1	0.14	20	0.82	548	1	0.02	37	1050	16	0.07	<2	4	76
B369960		10	<1	0.15	30	0.85	572	1	0.03	39	1100	16	0.08	<2	4	82
B369961		10	<1	0.25	40	0.99	653	1	0.02	47	1140	41	0.08	<2	6	68
B369962		<10	1	0.02	10	0.11	965	1	0.02	6	1180	2	0.11	<2	1	20
B369963		<10	<1	0.04	10	0.25	237	1	0.02	11	710	7	0.05	<2	1	21
B369964		10	<1	0.11	10	0.49	338	1	0.02	20	730	8	0.03	<2	2	19
B369965		<10	<1	0.03	10	0.19	154	1	0.01	9	740	4	0.06	<2	1	17
B369966		10	<1	0.24	20	0.72	411	1	0.02	44	1140	10	0.02	<2	4	22
B369967		10	<1	0.08	10	0.31	529	4	0.01	28	780	10	0.07	<2	1	19
B369968		<10	<1	0.04	10	0.29	273	2	0.01	20	660	8	0.06	<2	1	15
B369969		10	<1	0.05	10	0.40	392	4	<0.01	29	730	47	0.07	<2	2	15
B369970		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	<1
B369971		10	<1	0.14	10	0.57	408	3	0.01	48	2170	33	0.05	<2	3	43
B369972		10	<1	0.14	10	0.66	510	4	0.01	53	2020	46	0.08	<2	3	32
B369973		10	<1	0.13	20	0.93	919	3	0.01	122	2620	51	0.17	<2	2	39
B369974		10	<1	0.11	10	0.45	481	3	0.01	26	740	102	0.16	<2	1	24
B369975		10	<1	0.08	10	0.57	757	3	0.01	30	880	25	0.11	<2	2	20
B369976		10	<1	0.18	10	0.54	574	3	0.01	32	780	18	0.06	<2	2	18
B369977		10	<1	0.07	10	0.38	266	3	0.01	26	480	16	0.05	<2	2	16
B369978		<10	<1	0.04	10	0.18	174	2	0.01	12	590	7	0.06	<2	1	15
B369979		10	<1	0.07	10	0.30	336	3	0.01	18	730	14	0.07	<2	2	21
B369980		10	<1	0.06	10	0.26	271	3	0.01	14	620	10	0.05	<2	1	17
B369981		<10	<1	0.06	<10	0.26	475	1	0.01	15	770	6	0.08	<2	1	25
B369982		10	<1	0.08	10	0.64	639	3	<0.01	52	620	33	0.05	<2	3	23
B369983		<10	<1	0.04	10	0.12	711	1	0.01	9	570	8	0.04	<2	1	14
B369984		<10	<1	0.04	<10	0.15	194	1	0.02	8	530	4	0.04	<2	1	11
B369985		10	<1	0.29	20	0.68	228	1	0.01	29	550	13	0.02	<2	4	18
B369986		<10	<1	0.04	10	0.13	104	1	0.01	10	640	4	0.04	<2	1	15
B369987		<10	<1	0.12	10	0.71	453	<1	0.02	29	1130	12	0.16	<2	1	376
B369988		<10	<1	0.05	<10	0.16	303	1	0.01	7	380	6	0.03	<2	1	22
B369989		10	<1	0.06	10	0.18	213	2	<0.01	14	500	12	0.05	<2	1	17
B369990		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	<1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
B369951		<20	0.10	<10	<10	63	<10	135
B369952		<20	0.06	<10	<10	53	<10	82
B369953		<20	0.08	<10	<10	58	<10	78
B369954		<20	0.07	<10	<10	51	<10	31
B369955		<20	0.07	<10	<10	46	<10	140
B369956		<20	0.06	<10	<10	59	<10	101
B369957		<20	0.07	<10	<10	46	<10	182
B369958		<20	0.16	<10	<10	79	<10	112
B369959		<20	0.09	<10	<10	58	<10	110
B369960		<20	0.09	<10	<10	60	<10	119
B369961		<20	0.11	<10	<10	71	<10	379
B369962		<20	0.04	<10	<10	27	<10	26
B369963		<20	0.06	<10	<10	47	<10	49
B369964		<20	0.11	<10	<10	59	<10	68
B369965		<20	0.05	<10	<10	40	<10	45
B369966		<20	0.13	<10	<10	77	<10	207
B369967		<20	0.08	<10	<10	95	<10	101
B369968		<20	0.06	<10	<10	68	<10	206
B369969		<20	0.08	<10	<10	114	<10	145
B369970		<20	<0.01	<10	<10	<1	<10	<2
B369971		<20	0.11	<10	<10	126	<10	252
B369972		<20	0.12	<10	<10	144	<10	305
B369973		<20	0.05	<10	<10	151	<10	1305
B369974		<20	0.07	<10	<10	73	<10	197
B369975		<20	0.08	<10	<10	78	<10	146
B369976		<20	0.10	<10	<10	79	<10	251
B369977		<20	0.09	<10	<10	82	<10	134
B369978		<20	0.05	<10	<10	53	<10	53
B369979		<20	0.08	<10	<10	69	<10	74
B369980		<20	0.08	<10	<10	63	<10	58
B369981		<20	0.05	<10	<10	45	<10	80
B369982		<20	0.11	<10	<10	85	<10	332
B369983		<20	0.06	<10	<10	48	<10	47
B369984		<20	0.05	<10	<10	35	<10	29
B369985		<20	0.15	<10	<10	52	<10	81
B369986		<20	0.06	<10	<10	49	<10	31
B369987		<20	0.04	<10	<10	31	<10	111
B369988		<20	0.05	<10	<10	41	<10	48
B369989		<20	0.05	<10	<10	63	<10	119
B369990		<20	<0.01	<10	<10	<1	<10	<2

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
B369991		0.24	0.007	1.3	1.70	41	<10	550	2.0	5	0.42	3.5	16	46	82	4.47
B369992		0.22	<0.005	1.1	1.31	16	<10	460	0.7	<2	0.23	1.6	7	33	47	2.84
B369993		0.24	<0.005	0.3	1.38	16	<10	370	0.9	<2	0.23	1.4	10	48	58	2.99
B369994		0.24	<0.005	0.3	0.87	6	<10	100	0.5	<2	0.16	0.7	5	15	29	1.74
B369995		0.28	<0.005	<0.2	1.40	13	<10	90	0.6	2	0.18	<0.5	10	32	36	3.18
B369996		0.32	<0.005	<0.2	1.31	18	<10	140	0.6	2	0.23	1.3	10	36	64	3.18
B369997		0.20	<0.005	0.7	1.26	14	<10	200	0.7	3	0.27	1.0	9	29	68	2.39
B369998		0.25	0.007	0.8	1.33	13	<10	270	0.5	5	0.31	1.0	9	33	60	2.60
B369999		0.28	0.011	0.5	1.54	22	<10	150	0.9	4	0.38	1.3	9	35	60	2.85
B370000		0.20	0.013	0.7	1.93	25	<10	190	1.1	5	0.39	1.3	12	42	70	3.21
I102501		0.24	<0.005	1.1	1.28	11	<10	280	0.9	5	0.26	0.9	8	26	40	2.70
I102502		0.24	0.010	1.0	1.97	16	<10	380	1.0	5	0.34	2.6	13	47	55	3.43
I102503		0.25	0.014	0.4	2.03	16	<10	240	1.3	6	0.20	1.0	10	43	44	3.09
I102504		0.22	<0.005	<0.2	1.21	10	<10	110	<0.5	<2	0.14	0.6	6	29	28	2.88
I102505		0.28	0.006	0.2	1.63	11	<10	210	0.7	<2	0.28	1.1	11	38	33	3.34
I102506		0.35	0.007	<0.2	1.56	9	<10	170	0.7	<2	0.28	0.6	11	35	33	2.98
I102507		0.39	0.011	0.3	3.51	4	<10	280	1.8	2	1.13	1.3	35	84	62	7.25
I102508		0.29	<0.005	0.2	2.37	41	<10	130	0.9	<2	0.14	<0.5	13	46	41	3.89
I102509		0.27	0.018	1.4	1.91	21	<10	450	1.0	5	0.26	2.0	24	39	68	4.02
I102510		0.08	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
I102511		0.17	0.006	1.5	1.54	19	<10	1320	0.9	2	0.87	4.6	13	37	82	2.52
I102512		0.22	<0.005	0.3	1.13	26	<10	790	1.2	<2	0.72	11.1	10	22	38	2.40
I102513		0.25	0.007	1.1	2.76	33	<10	720	1.3	4	0.39	2.2	33	87	98	4.67
I102514		0.15	0.011	0.3	0.72	4	<10	410	0.6	<2	0.59	4.4	10	16	26	1.22
I102515		0.30	0.010	0.8	1.76	21	<10	310	1.3	<2	0.31	1.4	17	43	61	3.45
I102516		0.31	0.009	0.9	1.12	10	<10	260	0.6	2	0.24	1.5	14	25	55	2.35
I102517		0.28	<0.005	<0.2	1.57	14	<10	210	0.6	<2	0.15	<0.5	10	50	41	3.34
I102518		0.30	0.005	0.3	1.44	14	<10	180	0.6	2	0.19	0.5	7	35	49	2.88
I102519		0.29	0.068	0.6	1.37	14	<10	120	0.6	9	0.13	0.9	6	33	55	3.23
I102520		0.30	0.021	0.6	1.43	15	<10	120	0.6	10	0.13	0.9	6	33	56	3.33
I102521		0.23	0.020	0.7	1.78	20	<10	150	0.8	10	0.27	1.2	9	46	78	3.50
I102522		0.25	0.012	0.2	1.83	20	<10	290	0.5	11	0.22	0.8	8	44	77	3.66
I102523		0.20	0.007	0.2	0.86	10	<10	90	<0.5	2	0.15	0.6	7	23	30	2.35
I102524		0.21	0.010	0.2	1.10	9	<10	150	<0.5	2	0.18	<0.5	9	26	38	2.38
I102525		0.29	0.012	<0.2	1.79	9	<10	100	0.5	2	0.23	<0.5	14	38	43	2.66
I102526		0.20	0.009	0.2	0.67	6	<10	60	<0.5	<2	0.19	0.6	5	15	18	1.55
I102527		0.18	0.010	0.2	0.69	5	<10	80	<0.5	<2	0.14	<0.5	5	16	24	1.89
I102528		0.20	0.010	0.5	0.78	15	<10	60	<0.5	<2	0.30	0.9	4	25	37	2.11
I102529		0.19	0.009	0.5	0.92	7	<10	100	0.5	<2	0.33	1.1	4	19	81	1.74
I102530		0.10	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
B369991		10	1	0.13	30	0.54	877	4	0.01	70	1480	42	0.06	<2	4	27
B369992		10	<1	0.07	10	0.38	322	3	0.01	29	1050	17	0.09	<2	1	22
B369993		10	<1	0.13	20	0.48	458	2	0.01	47	1110	25	0.08	<2	2	18
B369994		<10	1	0.04	10	0.21	195	1	0.02	15	740	8	0.07	<2	1	15
B369995		10	<1	0.07	10	0.47	607	3	0.01	25	710	17	0.07	<2	2	18
B369996		10	<1	0.12	10	0.49	409	2	0.01	37	980	16	0.05	<2	2	17
B369997		<10	1	0.05	40	0.38	337	2	0.01	32	1220	19	0.11	<2	1	23
B369998		10	<1	0.05	10	0.44	354	2	0.01	29	1330	16	0.09	<2	2	22
B369999		10	<1	0.10	40	0.50	319	2	0.01	31	1500	21	0.04	<2	3	20
B370000		10	<1	0.10	40	0.61	436	2	0.01	38	1620	25	0.07	<2	3	24
I102501		<10	<1	0.07	10	0.40	320	1	0.01	25	860	49	0.05	<2	2	19
I102502		10	<1	0.15	20	0.72	581	2	0.01	45	1040	61	0.06	<2	4	24
I102503		10	<1	0.13	30	0.62	406	2	0.01	34	830	49	0.04	<2	3	16
I102504		10	<1	0.10	10	0.32	222	3	0.01	21	580	13	0.05	<2	2	14
I102505		10	<1	0.14	10	0.58	463	2	0.01	34	910	47	0.02	<2	3	18
I102506		10	<1	0.17	10	0.56	402	1	0.01	34	820	16	0.02	<2	4	15
I102507		10	<1	0.79	20	2.15	729	<1	0.02	56	2670	6	0.02	<2	14	32
I102508		10	1	0.13	10	0.61	433	1	0.01	40	600	20	0.06	<2	3	13
I102509		10	1	0.21	10	0.64	1005	3	0.01	42	630	53	0.05	<2	4	26
I102510		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	<1
I102511		10	<1	0.09	10	0.48	702	3	0.02	39	1330	57	0.12	<2	2	51
I102512		<10	<1	0.06	10	0.31	903	2	0.01	21	810	22	0.09	<2	2	45
I102513		10	<1	0.34	10	1.34	1010	3	0.01	82	1300	51	0.14	<2	3	32
I102514		<10	1	0.12	10	0.23	335	2	0.01	17	1960	16	0.22	<2	<1	50
I102515		10	<1	0.16	10	0.61	845	4	0.01	42	1470	26	0.12	<2	1	33
I102516		10	<1	0.07	10	0.27	1060	4	0.01	19	1580	27	0.16	<2	1	25
I102517		10	<1	0.17	10	0.51	623	3	0.01	35	940	17	0.08	<2	1	18
I102518		10	<1	0.06	10	0.39	227	2	0.01	26	890	19	0.09	<2	1	20
I102519		10	<1	0.07	10	0.38	232	3	<0.01	24	520	21	0.05	<2	2	13
I102520		10	<1	0.08	10	0.39	231	3	0.01	23	500	24	0.05	<2	2	14
I102521		10	<1	0.15	20	0.55	359	3	0.01	36	940	25	0.04	<2	3	16
I102522		10	<1	0.07	10	0.49	289	3	0.01	36	790	17	0.06	<2	2	22
I102523		10	1	0.09	10	0.25	332	2	0.01	16	880	8	0.09	<2	1	17
I102524		10	<1	0.10	10	0.29	720	3	0.01	20	1110	9	0.12	<2	1	21
I102525		10	1	0.11	10	0.57	323	2	0.01	34	540	6	0.03	<2	4	16
I102526		<10	<1	0.04	10	0.18	88	1	0.02	11	700	4	0.11	<2	1	17
I102527		<10	<1	0.03	10	0.16	90	2	0.01	12	600	7	0.07	<2	1	15
I102528		10	<1	0.05	10	0.18	93	5	0.01	15	1250	7	0.10	<2	1	23
I102529		<10	<1	0.09	10	0.21	80	2	0.02	14	1720	10	0.14	<2	1	24
I102530		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	20	<2	0.02	<2	<1	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
B369991		<20	0.04	<10	<10	118	<10	449
B369992		<20	0.06	<10	<10	85	<10	140
B369993		<20	0.07	<10	<10	115	<10	236
B369994		<20	0.04	<10	<10	47	<10	57
B369995		<20	0.07	<10	<10	71	<10	97
B369996		<20	0.09	<10	<10	118	<10	176
B369997		<20	0.05	<10	<10	80	<10	101
B369998		<20	0.06	<10	<10	101	<10	135
B369999		<20	0.08	<10	<10	89	<10	199
B370000		<20	0.08	<10	<10	102	<10	219
I102501		<20	0.06	<10	<10	67	<10	151
I102502		<20	0.10	<10	<10	89	<10	264
I102503		<20	0.07	<10	<10	78	<10	185
I102504		<20	0.08	<10	<10	88	<10	65
I102505		<20	0.07	<10	<10	76	<10	252
I102506		<20	0.08	<10	<10	67	<10	103
I102507		<20	0.34	<10	<10	140	<10	174
I102508		<20	0.09	<10	<10	82	<10	86
I102509		<20	0.08	<10	<10	77	<10	251
I102510		<20	<0.01	<10	<10	<1	<10	<2
I102511		<20	0.05	<10	<10	66	<10	582
I102512		<20	0.03	<10	<10	49	10	484
I102513		<20	0.12	<10	<10	154	<10	378
I102514		<20	0.02	<10	<10	35	<10	197
I102515		<20	0.05	<10	<10	114	<10	177
I102516		<20	0.03	<10	<10	77	<10	130
I102517		<20	0.08	<10	<10	168	<10	106
I102518		<20	0.05	<10	<10	103	<10	95
I102519		<20	0.08	<10	<10	93	<10	125
I102520		<20	0.08	<10	<10	93	<10	128
I102521		<20	0.10	<10	<10	112	<10	238
I102522		<20	0.09	<10	<10	148	<10	127
I102523		<20	0.05	<10	<10	95	<10	64
I102524		<20	0.05	<10	<10	89	<10	63
I102525		<20	0.12	<10	<10	85	<10	63
I102526		<20	0.05	<10	<10	43	<10	39
I102527		<20	0.06	<10	<10	57	<10	43
I102528		<20	0.06	<10	<10	167	<10	45
I102529		<20	0.05	<10	<10	67	<10	64
I102530		<20	<0.01	<10	<10	<1	<10	<2

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
I102531		0.24	0.009	0.7	1.04	4	<10	80	0.6	<2	0.23	0.8	6	17	119	1.13
I102532		0.15	0.009	0.9	1.15	7	<10	140	0.5	<2	0.36	2.1	6	20	77	1.49
I102533		0.22	<0.005	0.5	1.05	11	<10	590	0.5	<2	0.32	6.5	12	24	38	2.16
I102534		0.21	<0.005	0.9	0.28	2	<10	60	<0.5	<2	0.09	1.4	2	7	10	0.96
I102535		0.17	NSS	0.6	0.51	8	<10	550	<0.5	<2	0.17	1.6	3	10	27	1.29
I102536		0.22	0.006	1.8	0.76	10	<10	310	<0.5	<2	0.23	8.7	14	23	29	1.92
I102537		0.16	0.010	1.2	0.68	7	<10	250	<0.5	<2	0.28	0.9	7	22	29	1.77
I102538		0.34	0.011	0.8	1.67	16	<10	410	1.6	<2	0.57	2.2	20	45	88	3.54
I102539		0.26	<0.005	0.2	0.99	8	<10	110	<0.5	<2	0.20	<0.5	7	23	25	2.46
I102540		0.27	<0.005	0.2	1.52	13	<10	130	0.5	<2	0.18	<0.5	9	34	33	3.29
I102541		0.32	0.025	0.2	1.97	12	<10	160	0.7	<2	0.63	0.7	14	51	68	3.39
I102542		0.38	0.044	<0.2	2.12	13	<10	140	1.2	17	0.23	0.6	17	41	78	3.85
I102543		0.32	0.009	1.2	1.64	8	<10	140	0.7	5	0.34	<0.5	11	35	44	2.70
I102544		0.24	0.013	0.3	2.18	20	<10	90	0.6	6	0.18	<0.5	12	47	55	3.45
I102545		0.22	0.011	<0.2	1.07	16	<10	80	<0.5	8	0.13	<0.5	7	26	35	3.28
I102546		0.26	0.011	0.3	1.72	16	<10	90	0.5	9	0.15	<0.5	9	38	36	3.20
I102547		0.18	0.009	0.3	1.20	10	<10	130	<0.5	<2	0.17	<0.5	13	29	41	2.80
I102548		0.21	<0.005	0.2	1.55	10	<10	120	<0.5	<2	0.22	<0.5	9	32	42	2.73
I102549		0.22	0.005	0.5	1.39	12	<10	170	0.6	<2	0.33	<0.5	7	32	48	2.83
I102550		0.09	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
C189701		0.20	<0.005	0.5	1.33	52	<10	90	1.0	2	0.20	1.6	7	29	41	3.57
C189702		0.20	0.020	0.5	2.67	41	<10	210	1.5	2	0.56	1.2	17	38	175	3.93
C189703		0.22	0.007	0.7	1.03	14	<10	70	<0.5	<2	0.26	2.7	4	21	85	1.90
C189704		0.15	0.007	1.0	1.23	9	<10	80	0.6	<2	0.35	2.5	10	21	93	1.75
C189705		0.19	<0.005	0.6	1.05	10	<10	80	<0.5	<2	0.14	<0.5	7	15	21	2.03
C189706		0.27	<0.005	0.2	2.29	14	<10	100	<0.5	<2	0.17	<0.5	10	38	22	4.16
C189707		0.22	0.005	1.4	2.92	49	<10	180	1.0	<2	0.42	0.9	19	42	73	4.03
C189708		0.29	<0.005	<0.2	2.21	7	<10	140	0.5	<2	0.30	<0.5	11	37	24	3.53
C189709		0.22	<0.005	<0.2	1.64	15	<10	70	<0.5	<2	0.13	<0.5	8	33	27	4.34
C189710		0.07	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
C189711		0.22	<0.005	<0.2	1.80	14	<10	70	<0.5	<2	0.16	<0.5	10	36	23	4.72
C189712		0.23	<0.005	<0.2	1.54	13	<10	60	<0.5	<2	0.14	<0.5	7	29	18	4.32
C189713		0.19	<0.005	0.2	1.29	8	<10	70	<0.5	<2	0.13	0.5	5	17	25	2.18
C189714		0.24	<0.005	0.2	0.81	9	<10	70	<0.5	<2	0.10	<0.5	7	15	20	2.36
C189715		0.18	<0.005	1.4	1.68	19	<10	100	<0.5	<2	0.14	0.6	9	33	24	3.92
C189716		0.20	0.013	0.2	0.92	17	<10	80	<0.5	2	0.09	<0.5	5	19	19	2.39
C189717		0.14	<0.005	0.7	1.25	14	<10	140	<0.5	<2	0.21	0.7	5	15	28	1.79
C189718		0.18	0.026	0.4	1.34	19	<10	200	<0.5	<2	0.26	1.0	15	28	34	3.18
C189719		0.28	0.027	0.6	1.48	8	<10	350	0.6	<2	0.42	0.9	12	30	47	2.79
C189720		0.25	0.014	0.7	1.62	10	<10	380	0.7	<2	0.44	0.9	13	30	54	2.64

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
I102531		<10	<1	0.04	10	0.14	166	2	0.01	16	1330	7	0.11	<2	<1	17
I102532		<10	1	0.06	20	0.25	168	2	0.02	21	1320	11	0.10	<2	1	22
I102533		<10	<1	0.08	10	0.34	955	2	0.02	22	870	22	0.10	<2	1	26
I102534		<10	<1	0.03	<10	0.05	49	1	0.01	5	600	3	0.06	<2	<1	10
I102535		<10	<1	0.03	10	0.10	79	2	0.01	12	1280	16	0.13	<2	<1	17
I102536		<10	<1	0.06	10	0.22	2000	2	0.01	19	1210	16	0.13	<2	<1	21
I102537		<10	<1	0.08	10	0.22	378	2	0.01	17	1260	13	0.14	<2	<1	24
I102538		10	<1	0.15	30	0.52	968	2	0.02	72	2620	31	0.10	<2	2	32
I102539		10	1	0.05	10	0.31	262	1	0.02	18	740	9	0.09	<2	1	19
I102540		10	<1	0.07	10	0.44	375	2	0.01	25	770	15	0.09	<2	1	20
I102541		10	<1	0.09	20	0.62	482	1	0.02	46	2620	51	0.06	<2	3	31
I102542		10	<1	0.16	20	0.59	482	2	0.01	33	910	27	0.06	<2	3	18
I102543		10	<1	0.08	10	0.46	413	1	0.02	28	1580	15	0.09	<2	1	18
I102544		10	<1	0.08	10	0.59	401	1	0.01	35	710	15	0.06	<2	2	15
I102545		10	<1	0.04	10	0.23	276	3	0.01	20	690	17	0.08	<2	1	15
I102546		10	<1	0.09	10	0.50	355	2	0.01	24	720	14	0.09	<2	2	16
I102547		10	<1	0.08	10	0.31	713	4	0.01	29	1150	11	0.12	<2	1	22
I102548		10	<1	0.05	10	0.51	330	1	0.02	22	970	8	0.10	<2	1	23
I102549		10	<1	0.06	10	0.35	161	2	0.02	36	1270	10	0.13	<2	2	29
I102550		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.03	<2	<1	1
C189701		10	1	0.07	10	0.21	357	5	0.01	25	930	52	0.05	<2	2	16
C189702		10	<1	0.11	20	0.88	372	4	0.02	58	1770	20	0.11	<2	4	36
C189703		10	<1	0.06	10	0.20	95	2	0.02	13	1330	9	0.10	<2	1	21
C189704		10	<1	0.08	10	0.32	202	1	0.03	19	1540	7	0.10	<2	2	28
C189705		10	<1	0.07	10	0.20	326	2	0.02	12	330	8	0.04	<2	1	18
C189706		10	<1	0.07	10	0.50	302	2	0.01	23	380	14	0.03	<2	3	18
C189707		10	<1	0.11	20	0.51	859	1	0.02	35	1290	22	0.09	<2	3	37
C189708		10	<1	0.20	20	0.65	325	1	0.01	28	420	12	0.03	<2	4	27
C189709		20	<1	0.08	10	0.33	257	3	0.01	18	400	14	0.04	2	3	14
C189710		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.03	<2	<1	<1
C189711		10	<1	0.14	10	0.58	242	1	0.01	25	300	11	0.03	<2	3	15
C189712		10	<1	0.14	10	0.43	251	2	0.01	17	390	12	0.03	<2	3	16
C189713		10	<1	0.05	10	0.17	129	2	0.01	14	280	8	0.04	<2	2	21
C189714		10	<1	0.05	10	0.14	488	3	0.02	14	350	11	0.03	<2	1	14
C189715		10	<1	0.06	10	0.37	365	3	0.01	19	600	22	0.06	<2	2	18
C189716		10	<1	0.06	10	0.19	142	3	0.01	14	330	8	0.03	<2	2	14
C189717		10	<1	0.04	10	0.09	69	3	0.01	15	740	9	0.07	<2	<1	32
C189718		10	<1	0.08	10	0.33	895	4	0.01	24	520	17	0.07	<2	1	34
C189719		10	<1	0.06	10	0.42	484	2	0.02	27	1040	12	0.07	<2	2	29
C189720		10	<1	0.06	20	0.44	562	2	0.02	27	1030	13	0.08	<2	2	31

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
I102531		<20	0.03	<10	<10	38	<10	38
I102532		<20	0.04	<10	<10	50	<10	86
I102533		<20	0.05	<10	<10	55	<10	208
I102534		<20	0.03	<10	<10	30	<10	31
I102535		<20	0.02	<10	<10	28	<10	61
I102536		<20	0.02	<10	<10	68	<10	134
I102537		<20	0.02	<10	<10	68	<10	97
I102538		<20	0.06	<10	<10	159	<10	255
I102539		<20	0.06	<10	<10	76	<10	74
I102540		<20	0.07	<10	<10	94	<10	92
I102541		<20	0.10	<10	<10	117	<10	173
I102542		<20	0.13	<10	<10	126	<10	140
I102543		<20	0.07	<10	<10	92	<10	85
I102544		<20	0.11	<10	<10	126	<10	116
I102545		<20	0.09	<10	<10	107	<10	89
I102546		<20	0.08	<10	<10	87	<10	82
I102547		<20	0.04	<10	<10	101	<10	76
I102548		<20	0.06	<10	<10	76	<10	64
I102549		<20	0.04	<10	<10	91	<10	87
I102550		<20	<0.01	<10	<10	<1	<10	<2
C189701		<20	0.02	<10	<10	83	<10	702
C189702		<20	0.16	<10	<10	147	<10	266
C189703		<20	0.06	<10	<10	93	<10	83
C189704		<20	0.07	<10	<10	64	<10	120
C189705		<20	0.09	<10	<10	76	<10	48
C189706		<20	0.13	<10	<10	89	<10	70
C189707		<20	0.09	<10	<10	91	<10	137
C189708		<20	0.17	<10	<10	73	<10	72
C189709		<20	0.20	<10	<10	129	<10	61
C189710		<20	<0.01	<10	<10	<1	<10	<2
C189711		<20	0.21	<10	<10	95	<10	67
C189712		<20	0.21	<10	<10	100	<10	57
C189713		<20	0.11	<10	<10	71	<10	42
C189714		<20	0.11	<10	<10	83	<10	56
C189715		<20	0.12	<10	<10	105	<10	103
C189716		<20	0.13	<10	<10	132	<10	53
C189717		<20	0.04	<10	<10	91	<10	47
C189718		<20	0.10	<10	<10	116	<10	150
C189719		<20	0.09	<10	<10	91	<10	110
C189720		<20	0.08	<10	<10	83	<10	110

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
C189721		0.29	0.017	0.3	2.07	13	<10	250	1.0	<2	0.33	0.7	17	44	62	3.41
C189722		0.15	<0.005	0.2	0.75	5	<10	110	<0.5	<2	0.08	<0.5	4	13	17	1.41
C189723		0.19	<0.005	0.2	0.74	4	<10	70	<0.5	<2	0.21	0.6	4	13	16	1.45
C189724		0.24	0.012	0.5	2.07	14	<10	190	0.8	<2	0.40	1.0	12	46	65	2.95
C189725		0.28	0.007	0.9	1.62	7	<10	190	<0.5	<2	0.29	<0.5	9	39	45	1.95
C189726		0.30	<0.005	0.6	1.17	11	<10	130	<0.5	<2	0.20	0.5	12	28	46	2.01
C189727		0.30	<0.005	0.9	1.27	11	<10	240	0.5	<2	0.29	1.1	17	32	47	2.04
C189728		0.21	NSS	1.1	1.05	7	<10	410	0.7	<2	0.31	1.5	42	13	53	1.52
C189729		0.33	0.006	0.5	1.18	14	<10	90	0.9	14	0.19	0.7	8	25	113	2.56
C189730		0.06	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	1	0.02
C189731		0.25	<0.005	0.4	0.88	11	<10	130	<0.5	<2	0.14	0.7	6	22	43	2.09
C189732		0.26	<0.005	0.7	1.17	10	<10	270	0.9	<2	0.21	1.3	7	19	42	2.18
C189733		0.20	<0.005	0.8	1.76	16	<10	370	1.2	<2	0.28	2.6	13	31	56	2.76
C189734		0.22	<0.005	0.3	1.73	11	<10	140	0.6	<2	0.21	0.7	13	29	31	3.61
C189735		0.38	0.005	<0.2	2.47	9	<10	210	0.8	<2	0.28	0.7	18	39	41	3.35
C189736		0.27	<0.005	0.4	1.82	11	<10	100	0.5	<2	0.28	0.6	13	48	26	3.59
C189737		0.24	<0.005	0.2	2.38	12	<10	170	0.8	<2	0.57	0.7	17	56	34	3.42
C330551		0.22	<0.005	<0.2	1.42	13	<10	80	0.5	<2	0.19	<0.5	12	29	37	3.01
C330552		0.17	<0.005	<0.2	0.93	8	<10	70	0.5	<2	0.35	0.7	8	15	25	1.57
C330553		0.25	<0.005	0.2	0.98	7	<10	60	<0.5	<2	0.20	<0.5	9	20	45	2.21
C330554		0.30	0.010	1.6	1.36	19	<10	80	<0.5	5	0.20	<0.5	9	26	68	2.46
C330555		0.24	<0.005	<0.2	0.42	<2	<10	20	<0.5	<2	0.09	<0.5	4	8	13	1.37
C330556		0.28	<0.005	0.3	1.55	18	<10	90	<0.5	<2	0.14	<0.5	10	36	48	3.32
C330557		0.25	<0.005	0.4	1.65	14	<10	140	0.7	<2	0.27	0.6	17	38	77	2.97
C330558		0.32	<0.005	<0.2	1.32	8	<10	130	0.6	2	0.43	<0.5	11	33	37	2.99
C330559		0.24	<0.005	<0.2	1.16	8	<10	50	0.6	<2	0.12	<0.5	6	21	29	2.43
C330560		0.24	<0.005	<0.2	1.17	7	<10	50	0.6	<2	0.14	<0.5	7	22	31	2.56
C330561		0.29	0.006	0.2	1.59	12	<10	80	1.2	<2	0.27	0.6	11	30	33	3.12
C330562		0.30	<0.005	<0.2	1.53	5	<10	80	0.6	<2	0.20	<0.5	10	29	28	2.48
C330563		0.22	<0.005	<0.2	0.49	<2	<10	10	<0.5	<2	0.15	<0.5	3	3	13	0.84
C330564		0.25	<0.005	<0.2	0.65	3	<10	40	<0.5	<2	0.18	<0.5	4	8	21	1.37
C330565		0.23	0.005	0.3	1.48	11	<10	130	0.5	<2	0.24	<0.5	11	33	65	2.71
C330566		0.19	<0.005	0.3	1.97	9	<10	150	0.5	<2	0.27	0.6	13	46	84	3.14
C330567		0.21	<0.005	0.2	0.56	7	<10	30	<0.5	<2	0.10	<0.5	4	14	17	1.87
C330568		0.25	<0.005	<0.2	0.29	2	<10	20	<0.5	<2	0.13	<0.5	2	3	8	0.65
C330569		0.29	0.007	0.2	1.97	7	<10	170	0.6	<2	0.39	<0.5	28	61	80	3.33
C330570		0.34	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	1	0.03
C330571		0.26	<0.005	0.2	2.52	9	<10	120	0.7	<2	0.24	<0.5	13	37	47	2.93
C330572		0.22	<0.005	<0.2	1.02	5	<10	130	<0.5	<2	0.12	<0.5	4	14	23	1.65
C330573		0.26	0.006	<0.2	2.35	8	<10	130	0.5	2	0.22	<0.5	14	34	38	3.21

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
C189721		10	<1	0.14	10	0.62	529	2	0.02	45	1190	16	0.09	<2	4	29
C189722		<10	<1	0.03	<10	0.13	67	1	0.02	10	510	4	0.05	<2	1	12
C189723		<10	<1	0.04	10	0.17	81	1	0.02	11	770	4	0.12	<2	<1	21
C189724		10	1	0.12	20	0.63	411	2	0.02	39	1420	19	0.09	<2	4	29
C189725		10	<1	0.06	10	0.54	223	2	0.01	30	1250	18	0.08	<2	2	22
C189726		<10	<1	0.06	10	0.33	504	2	0.01	23	960	8	0.08	<2	1	18
C189727		<10	1	0.05	10	0.35	744	2	0.01	27	1320	13	0.14	<2	1	27
C189728		<10	1	0.03	20	0.14	7650	3	0.01	17	2040	35	0.26	<2	<1	27
C189729		<10	1	0.06	60	0.32	231	3	0.01	22	780	40	0.04	<2	2	14
C189730		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	1	10	<2	0.03	<2	<1	1
C189731		<10	<1	0.05	10	0.22	232	2	0.01	19	820	16	0.11	<2	1	17
C189732		<10	<1	0.06	30	0.25	468	2	0.01	18	900	16	0.10	<2	1	21
C189733		10	<1	0.09	30	0.45	889	2	0.01	30	1020	33	0.09	<2	2	26
C189734		10	<1	0.09	10	0.45	782	3	0.01	22	620	15	0.08	<2	2	27
C189735		10	<1	0.22	10	0.70	446	1	0.01	43	720	17	0.05	<2	4	24
C189736		10	<1	0.16	10	0.67	466	2	0.01	33	400	22	0.04	2	4	23
C189737		10	1	0.12	10	0.97	519	1	0.03	47	590	21	0.04	<2	5	41
C330551		10	1	0.08	10	0.55	452	4	0.01	26	550	8	0.08	<2	2	20
C330552		<10	<1	0.05	10	0.29	589	2	0.02	16	770	5	0.10	<2	1	26
C330553		<10	1	0.06	10	0.31	302	3	0.01	18	770	8	0.06	<2	2	18
C330554		10	<1	0.12	10	0.47	316	6	0.02	28	750	14	0.11	<2	3	26
C330555		<10	<1	0.02	<10	0.10	99	1	0.01	7	540	<2	0.08	<2	<1	11
C330556		10	<1	0.11	10	0.52	405	7	0.01	27	520	13	0.08	<2	3	21
C330557		10	<1	0.09	10	0.54	903	9	0.01	33	950	10	0.11	<2	2	33
C330558		10	<1	0.16	10	0.55	544	7	0.01	31	1540	21	0.05	<2	3	20
C330559		10	<1	0.04	10	0.28	294	6	0.01	17	430	17	0.07	<2	1	13
C330560		10	<1	0.05	10	0.29	333	7	0.01	19	520	16	0.08	<2	1	14
C330561		10	<1	0.07	30	0.46	589	10	0.01	29	990	33	0.07	<2	3	20
C330562		10	<1	0.05	10	0.48	447	2	0.01	25	360	11	0.05	<2	2	16
C330563		<10	<1	0.02	10	0.06	99	<1	0.02	3	540	<2	0.05	<2	<1	12
C330564		<10	<1	0.04	<10	0.10	125	1	0.02	7	520	7	0.03	<2	1	15
C330565		10	<1	0.16	10	0.49	507	4	0.02	34	750	11	0.10	<2	3	23
C330566		10	<1	0.14	10	0.68	435	5	0.02	44	740	11	0.10	<2	3	23
C330567		10	<1	0.03	<10	0.16	101	3	0.01	13	220	4	0.04	<2	1	13
C330568		<10	<1	0.04	<10	0.07	41	<1	0.03	3	350	<2	0.04	<2	<1	13
C330569		10	<1	0.21	10	0.91	509	5	0.03	64	900	7	0.10	<2	4	29
C330570		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	1	10	<2	0.06	<2	<1	1
C330571		10	1	0.10	10	0.51	346	3	0.02	35	770	8	0.09	<2	3	21
C330572		10	1	0.02	10	0.10	69	4	0.01	12	220	8	0.06	<2	1	18
C330573		10	<1	0.06	10	0.54	345	3	0.01	40	410	10	0.02	<2	4	18

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
C189721		<20	0.13	<10	<10	98	<10	150
C189722		<20	0.05	<10	<10	51	<10	30
C189723		<20	0.03	<10	<10	37	<10	39
C189724		<20	0.10	<10	<10	97	<10	161
C189725		<20	0.07	<10	<10	74	<10	115
C189726		<20	0.07	<10	<10	69	<10	79
C189727		<20	0.05	<10	<10	65	<10	96
C189728		<20	0.02	<10	<10	29	<10	40
C189729		<20	0.06	<10	<10	57	<10	149
C189730		<20	<0.01	<10	<10	<1	<10	<2
C189731		<20	0.04	<10	<10	58	<10	91
C189732		<20	0.03	<10	<10	49	<10	108
C189733		<20	0.04	<10	<10	66	<10	215
C189734		<20	0.12	<10	<10	83	<10	140
C189735		<20	0.12	<10	<10	69	<10	127
C189736		<20	0.13	<10	<10	80	<10	122
C189737		<20	0.12	<10	<10	68	<10	120
C330551		<20	0.08	<10	<10	60	<10	93
C330552		<20	0.04	<10	<10	33	<10	78
C330553		<20	0.07	<10	<10	59	<10	61
C330554		<20	0.09	<10	<10	62	<10	91
C330555		<20	0.04	<10	<10	42	<10	28
C330556		<20	0.11	<10	<10	88	<10	87
C330557		<20	0.08	<10	<10	73	<10	124
C330558		<20	0.11	<10	<10	96	<10	156
C330559		<20	0.06	<10	<10	58	<10	110
C330560		<20	0.06	<10	<10	61	<10	107
C330561		<20	0.08	<10	<10	75	<10	135
C330562		<20	0.09	<10	<10	59	<10	82
C330563		<20	0.04	<10	<10	28	<10	17
C330564		<20	0.04	<10	<10	38	<10	50
C330565		<20	0.09	<10	<10	69	<10	106
C330566		<20	0.14	<10	<10	77	<10	101
C330567		<20	0.10	<10	<10	58	<10	37
C330568		<20	0.04	<10	<10	19	<10	12
C330569		<20	0.23	<10	<10	87	<10	167
C330570		<20	<0.01	<10	<10	<1	<10	2
C330571		<20	0.13	<10	<10	69	<10	71
C330572		<20	0.08	<10	<10	84	<10	34
C330573		<20	0.14	<10	<10	72	<10	107

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
C330574		0.25	<0.005	0.2	0.90	4	<10	40	<0.5	<2	0.15	<0.5	4	13	30	1.48
C330575		0.26	0.005	<0.2	1.98	12	<10	80	<0.5	<2	0.14	<0.5	10	38	41	3.73
C330576		0.26	0.008	<0.2	1.76	8	<10	110	0.5	4	0.33	<0.5	11	26	33	2.87
C330577		0.42	0.012	0.2	1.80	6	<10	130	0.5	12	0.33	0.5	12	28	50	3.05
C330578		0.28	<0.005	<0.2	1.36	8	<10	100	<0.5	3	0.21	<0.5	12	25	33	2.83
C330579		0.27	0.015	0.2	1.95	27	<10	120	0.8	9	0.32	0.7	16	34	86	3.22
C330580		0.28	0.013	0.2	1.91	26	<10	110	0.7	8	0.31	0.8	16	32	81	3.08
C330581		0.32	0.015	0.8	1.78	18	<10	100	0.8	12	0.29	2.3	18	36	209	3.46
C330582		0.36	0.013	0.6	1.71	38	<10	90	0.9	14	0.30	0.6	14	29	158	3.20
C330583		0.20	0.026	0.2	1.01	19	<10	70	<0.5	3	0.19	<0.5	8	22	44	2.51
C330584		0.33	<0.005	0.2	1.77	4	<10	90	0.8	<2	0.19	<0.5	10	26	39	2.91
C330585		0.31	<0.005	<0.2	1.86	8	<10	90	0.8	2	0.19	0.5	11	30	31	3.04
C330586		0.22	<0.005	<0.2	0.89	2	<10	60	<0.5	<2	0.16	<0.5	5	10	14	1.25
C330587		0.24	<0.005	<0.2	1.77	8	<10	90	0.6	<2	0.24	0.5	9	29	29	3.05
C330588		0.32	<0.005	<0.2	2.10	6	<10	100	0.7	2	0.20	0.7	10	31	37	3.05
C330589		0.31	<0.005	<0.2	1.14	4	<10	60	<0.5	2	0.17	<0.5	7	19	28	2.22
C330590		0.36	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
C330591		0.33	<0.005	0.2	1.75	7	<10	90	0.6	6	0.18	<0.5	9	27	35	2.76
C330592		0.27	<0.005	<0.2	1.11	3	<10	70	<0.5	6	0.17	<0.5	7	18	26	2.17
C330593		0.32	<0.005	0.3	1.38	3	<10	80	0.5	3	0.20	0.8	8	21	39	2.45
C330594		0.32	<0.005	<0.2	0.97	4	<10	60	<0.5	<2	0.17	<0.5	6	15	28	1.95
C330595		0.31	<0.005	0.3	1.15	<2	<10	70	<0.5	4	0.13	<0.5	5	14	44	1.93
C330596		0.37	<0.005	<0.2	1.09	<2	<10	70	<0.5	<2	0.17	<0.5	7	15	33	2.04
C330597		0.28	<0.005	0.3	1.77	4	<10	140	0.7	9	0.19	<0.5	5	19	40	2.10
C330598		0.32	<0.005	0.4	2.85	8	<10	150	1.2	6	0.18	<0.5	14	38	73	3.64
C330599		0.29	<0.005	0.2	1.98	5	<10	80	0.5	<2	0.17	<0.5	11	29	42	2.77
C330600		0.30	<0.005	<0.2	1.97	6	<10	80	0.5	<2	0.16	<0.5	10	31	39	2.90
C331551		0.22	0.006	<0.2	1.61	17	<10	90	0.6	3	0.21	<0.5	11	37	54	3.53
C331552		0.26	<0.005	0.5	1.18	24	<10	80	<0.5	<2	0.13	0.5	10	28	31	3.09
C331553		0.28	0.022	0.2	1.62	566	<10	70	0.7	2	0.17	0.5	12	28	67	3.30
C331554		0.24	0.014	0.4	1.83	58	<10	60	0.6	9	0.19	0.6	15	37	94	3.43
C331555		0.24	0.097	1.5	2.52	13	<10	160	1.5	7	0.70	3.4	20	62	576	4.47
C331556		0.20	0.006	0.4	2.19	6	<10	90	1.2	2	0.26	1.2	15	53	223	3.88
C331557		0.24	0.009	0.5	1.56	7	<10	80	0.5	4	0.20	<0.5	14	30	128	3.63
C331558		0.27	<0.005	0.3	1.86	7	<10	60	0.6	<2	0.25	1.0	14	41	70	2.83
C331559		0.26	0.007	0.4	2.68	8	<10	90	<0.5	<2	0.34	0.7	33	40	411	3.76
C331560		0.27	0.005	0.4	2.76	11	<10	100	<0.5	2	0.36	0.8	36	41	419	3.92
C331561		0.30	<0.005	0.7	2.62	18	<10	100	1.1	3	0.12	<0.5	17	55	290	5.38
C331562		0.29	0.005	0.2	3.18	7	<10	140	0.7	2	0.28	0.6	32	53	144	3.82
C331563		0.32	<0.005	<0.2	1.88	11	<10	80	1.0	<2	0.16	<0.5	9	24	26	3.22

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
C330574		<10	<1	0.05	<10	0.24	113	9	0.02	12	390	6	0.03	<2	1	18
C330575		10	<1	0.06	10	0.55	304	17	0.01	27	360	14	0.02	<2	4	14
C330576		10	<1	0.06	10	0.57	413	5	0.01	25	720	9	0.04	<2	2	27
C330577		10	<1	0.09	10	0.62	488	4	0.01	26	840	8	0.01	<2	4	25
C330578		10	<1	0.05	10	0.40	594	4	0.01	21	650	10	0.07	<2	1	22
C330579		10	<1	0.12	10	0.80	589	9	0.02	36	860	13	0.04	<2	4	28
C330580		10	<1	0.11	10	0.77	554	8	0.02	33	840	11	0.04	<2	4	28
C330581		10	<1	0.15	20	0.81	559	11	0.01	59	800	79	0.04	<2	6	20
C330582		10	<1	0.13	10	0.71	495	6	0.01	41	870	41	0.02	<2	4	21
C330583		10	<1	0.07	10	0.39	355	4	0.01	16	830	9	0.07	<2	1	19
C330584		10	<1	0.06	10	0.46	390	8	<0.01	20	550	14	0.01	<2	3	15
C330585		10	<1	0.05	10	0.50	404	3	0.01	25	490	14	0.03	<2	2	17
C330586		<10	<1	0.04	10	0.21	172	<1	0.02	9	350	3	0.03	<2	1	17
C330587		10	<1	0.05	10	0.47	423	2	0.01	23	420	17	0.03	<2	2	21
C330588		10	<1	0.07	10	0.49	447	2	<0.01	23	540	26	0.01	<2	3	16
C330589		<10	<1	0.04	10	0.31	218	9	0.01	14	430	10	0.01	<2	2	14
C330590		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	<0.01	<2	<1	1
C330591		10	<1	0.05	10	0.46	357	26	0.01	22	520	16	0.02	<2	2	15
C330592		<10	<1	0.05	10	0.31	248	22	<0.01	12	490	13	0.01	<2	1	13
C330593		<10	<1	0.06	10	0.38	394	12	<0.01	15	690	24	0.01	<2	2	14
C330594		<10	<1	0.03	10	0.26	220	3	0.01	13	590	7	0.02	<2	1	14
C330595		10	<1	0.04	10	0.28	233	9	<0.01	9	470	21	0.02	<2	1	13
C330596		<10	<1	0.04	10	0.29	300	8	0.01	11	620	14	0.02	<2	1	14
C330597		10	<1	0.08	10	0.32	290	56	<0.01	11	770	22	0.06	<2	1	21
C330598		10	<1	0.08	10	0.67	615	34	0.01	31	620	26	0.04	<2	3	18
C330599		10	<1	0.04	10	0.50	314	3	0.01	29	350	9	0.01	<2	3	14
C330600		10	<1	0.04	10	0.52	312	3	0.01	28	370	10	0.02	<2	3	14
C331551		10	<1	0.06	10	0.62	567	6	0.01	27	620	13	0.04	<2	2	23
C331552		10	<1	0.09	10	0.36	627	9	<0.01	20	620	14	0.05	<2	1	17
C331553		10	<1	0.07	10	0.52	574	3	<0.01	24	440	15	0.03	<2	2	15
C331554		10	<1	0.09	10	0.65	645	4	0.01	27	760	13	0.06	3	2	18
C331555		10	<1	0.29	10	1.07	796	8	0.01	71	2790	31	0.03	<2	5	40
C331556		10	<1	0.35	10	1.13	525	10	0.01	39	960	23	0.09	<2	5	16
C331557		10	<1	0.08	10	0.48	723	26	0.01	23	820	36	0.07	<2	2	18
C331558		10	<1	0.10	10	0.78	457	7	0.02	35	540	25	0.05	2	3	18
C331559		10	2	0.17	10	0.78	411	40	0.04	79	1020	23	0.07	<2	4	29
C331560		10	1	0.18	10	0.82	432	40	0.04	82	1040	25	0.07	<2	4	30
C331561		10	1	0.20	10	0.77	1140	39	0.01	41	930	76	0.10	<2	4	16
C331562		10	2	0.37	10	1.02	419	13	0.02	74	660	5	0.07	<2	4	19
C331563		10	1	0.12	10	0.45	493	7	0.01	18	530	11	0.05	<2	2	15

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
C330574		<20	0.05	<10	<10	34	<10	45
C330575		<20	0.13	<10	<10	90	<10	86
C330576		<20	0.10	<10	<10	61	<10	103
C330577		<20	0.12	<10	<10	61	<10	99
C330578		<20	0.06	<10	<10	60	<10	94
C330579		<20	0.12	<10	<10	68	<10	154
C330580		<20	0.11	<10	<10	64	10	146
C330581		<20	0.12	<10	<10	80	10	523
C330582		<20	0.11	<10	<10	70	<10	192
C330583		<20	0.06	<10	<10	56	<10	83
C330584		<20	0.07	<10	<10	56	<10	66
C330585		<20	0.09	<10	<10	64	<10	107
C330586		<20	0.05	<10	<10	30	<10	32
C330587		<20	0.08	<10	<10	65	<10	108
C330588		<20	0.08	<10	<10	64	<10	167
C330589		<20	0.07	<10	<10	48	<10	112
C330590		<20	<0.01	<10	<10	<1	<10	<2
C330591		<20	0.08	<10	<10	57	<10	103
C330592		<20	0.07	<10	<10	45	<10	145
C330593		<20	0.06	<10	<10	45	<10	284
C330594		<20	0.06	<10	<10	44	<10	60
C330595		<20	0.03	<10	<10	35	<10	135
C330596		<20	0.06	<10	<10	45	<10	67
C330597		<20	0.03	<10	<10	40	10	88
C330598		<20	0.09	<10	<10	74	<10	144
C330599		<20	0.10	<10	<10	62	<10	80
C330600		<20	0.10	<10	<10	64	<10	88
C331551		<20	0.11	<10	<10	79	<10	117
C331552		<20	0.08	<10	<10	79	<10	93
C331553		<20	0.07	<10	<10	56	<10	155
C331554		<20	0.08	<10	<10	71	<10	152
C331555		<20	0.13	<10	<10	172	10	1580
C331556		<20	0.16	<10	<10	146	<10	332
C331557		<20	0.08	<10	<10	67	<10	154
C331558		<20	0.11	<10	<10	63	<10	436
C331559		<20	0.13	<10	<10	56	<10	361
C331560		<20	0.13	<10	<10	58	<10	370
C331561		<20	0.10	<10	<10	129	<10	295
C331562		<20	0.26	<10	<10	88	<10	205
C331563		<20	0.05	<10	<10	58	<10	145

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
C331564		0.24	<0.005	<0.2	2.05	11	<10	80	0.8	2	0.18	0.7	11	30	31	3.02
C331565		0.33	0.005	<0.2	1.93	5	<10	100	0.9	<2	0.23	0.6	11	28	32	2.55
C331566		0.28	0.005	<0.2	1.73	13	<10	160	0.6	<2	0.24	<0.5	10	44	34	3.66
C331567		0.24	0.005	0.2	1.97	14	<10	120	1.2	<2	0.39	1.0	16	33	39	3.57
C331568		0.26	0.014	<0.2	2.29	10	<10	100	0.8	<2	0.32	0.6	12	31	50	3.21
C331569		0.29	0.008	0.4	1.78	13	<10	100	1.0	2	0.24	0.9	14	30	82	3.56
C331570		0.16	<0.005	<0.2	0.01	3	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
C331571		0.21	<0.005	<0.2	1.19	16	<10	80	0.6	<2	0.26	<0.5	9	27	33	3.20
C331572		0.30	0.008	<0.2	1.83	13	<10	70	0.5	<2	0.16	<0.5	12	33	31	3.41
C331573		0.22	0.014	0.2	1.14	9	<10	80	<0.5	10	0.17	<0.5	7	19	33	2.99
C331574		0.20	0.005	0.2	1.39	13	<10	60	<0.5	3	0.17	<0.5	8	23	49	3.03
C331575		0.21	0.007	<0.2	1.84	14	<10	60	1.1	2	0.16	0.5	15	28	140	3.89
C331576		0.26	0.009	<0.2	2.05	12	<10	80	0.7	<2	0.20	<0.5	10	33	28	3.00
C331577		0.27	0.005	<0.2	1.43	8	<10	50	1.6	<2	0.11	0.7	8	27	49	3.76
C331578		0.26	0.005	<0.2	1.62	12	<10	70	1.2	<2	0.23	0.5	10	30	31	3.24
C331579		0.31	0.005	<0.2	1.47	10	<10	70	0.9	<2	0.18	<0.5	10	29	26	2.81
C331580		0.33	<0.005	<0.2	1.48	6	<10	70	0.9	<2	0.19	<0.5	10	29	25	2.71
C331581		0.30	0.007	<0.2	1.72	10	<10	70	1.0	<2	0.16	<0.5	9	27	23	2.86
C331582		0.28	0.007	0.2	1.92	8	<10	100	1.6	<2	0.25	0.7	9	25	35	2.71
C331583		0.28	0.006	<0.2	1.29	10	<10	70	1.1	<2	0.22	0.6	7	25	30	3.05
C331584		0.23	0.005	<0.2	1.48	12	<10	60	1.2	2	0.14	0.7	8	25	52	2.98
C331585		0.21	<0.005	<0.2	1.40	10	<10	50	0.5	<2	0.20	<0.5	8	28	27	2.95
C331586		0.28	<0.005	0.2	1.83	9	<10	80	1.1	2	0.17	0.8	10	30	34	2.77
C331587		0.25	<0.005	<0.2	1.48	12	<10	60	0.8	<2	0.13	0.8	10	28	41	3.21
C331588		0.25	0.008	0.2	1.87	12	<10	70	1.0	2	0.15	0.5	11	33	33	3.34
C331589		0.28	<0.005	0.2	1.58	9	<10	90	1.8	<2	0.19	1.8	9	25	82	2.82
C331590		0.08	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
C331591		0.24	<0.005	<0.2	1.34	8	<10	70	0.9	<2	0.13	0.5	7	23	31	2.81
C331592		0.28	0.008	<0.2	0.95	7	<10	50	2.0	<2	0.11	1.2	5	14	71	2.57
C331593		0.36	<0.005	<0.2	1.47	9	<10	60	0.7	<2	0.16	<0.5	8	24	33	2.43
C331594		0.31	<0.005	0.8	2.12	15	<10	340	0.7	<2	0.44	1.5	14	45	58	3.29
C331595		0.24	0.009	1.1	1.90	21	<10	310	0.6	<2	0.13	0.5	9	47	64	3.83
C331596		0.19	<0.005	3.9	1.51	13	<10	690	0.8	<2	0.25	3.6	11	36	63	2.98
C331597		0.30	<0.005	1.2	1.17	12	<10	370	0.5	<2	0.18	1.9	6	29	41	2.63
C331598		0.21	<0.005	0.5	0.70	2	<10	270	0.5	<2	0.31	2.1	4	16	25	1.54
C331599		0.26	<0.005	<0.2	1.69	8	<10	150	0.7	<2	0.25	0.8	13	33	27	3.09
C331600		0.28	<0.005	<0.2	1.81	8	<10	140	0.8	<2	0.24	0.8	13	35	28	3.17

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
C331564		10	1	0.07	20	0.55	627	5	0.01	24	450	9	0.04	<2	3	15
C331565		<10	1	0.06	10	0.54	453	1	0.01	25	260	13	0.02	<2	3	17
C331566		10	2	0.06	10	0.64	344	4	0.01	33	600	12	0.04	<2	2	18
C331567		10	1	0.05	20	0.66	940	4	0.01	28	780	64	0.07	<2	3	33
C331568		10	1	0.09	10	0.70	543	3	0.01	28	570	27	0.06	<2	3	23
C331569		10	2	0.06	10	0.56	876	35	0.01	27	670	43	0.06	<2	2	25
C331570		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	1
C331571		10	1	0.06	10	0.42	460	5	0.01	20	1230	27	0.12	<2	<1	24
C331572		10	1	0.06	10	0.56	482	10	0.01	26	530	17	0.05	<2	2	16
C331573		10	<1	0.07	10	0.32	320	5	0.01	14	930	11	0.09	<2	2	16
C331574		10	<1	0.06	10	0.41	353	6	0.01	20	880	10	0.10	<2	1	17
C331575		10	1	0.06	20	0.41	1110	10	0.01	19	730	20	0.09	<2	1	14
C331576		10	1	0.05	10	0.57	409	2	0.01	26	490	11	0.04	<2	2	18
C331577		10	1	0.04	20	0.36	648	5	<0.01	16	400	26	0.03	<2	2	10
C331578		10	1	0.05	20	0.53	482	2	0.01	23	570	15	0.03	<2	3	17
C331579		<10	<1	0.06	10	0.49	517	1	0.01	23	390	17	0.03	<2	2	14
C331580		<10	1	0.06	10	0.48	494	1	0.01	24	360	15	0.02	<2	3	15
C331581		10	1	0.05	10	0.42	371	1	0.01	24	480	25	0.03	<2	2	13
C331582		<10	<1	0.06	50	0.43	652	1	0.01	21	800	44	0.02	<2	3	18
C331583		10	1	0.05	20	0.39	569	2	0.01	18	590	29	0.04	<2	2	16
C331584		10	<1	0.05	60	0.38	731	2	0.01	18	570	96	0.05	<2	1	14
C331585		10	<1	0.04	10	0.41	409	1	0.01	18	850	15	0.09	<2	1	16
C331586		10	<1	0.05	20	0.53	538	1	0.01	26	390	20	0.02	<2	3	15
C331587		10	<1	0.05	20	0.43	642	2	0.01	23	540	47	0.05	<2	2	12
C331588		10	1	0.05	20	0.55	579	2	0.01	26	470	26	0.04	<2	2	15
C331589		<10	<1	0.08	60	0.41	756	2	0.01	21	670	38	0.02	<2	4	16
C331590		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	1	10	<2	0.02	<2	<1	1
C331591		<10	<1	0.04	20	0.33	450	2	0.01	17	470	25	0.04	<2	1	13
C331592		<10	<1	0.05	90	0.19	522	2	0.01	11	370	54	0.01	<2	2	10
C331593		<10	<1	0.05	20	0.41	357	1	0.01	20	360	15	0.02	<2	2	13
C331594		10	<1	0.10	10	0.59	487	3	0.01	54	1710	30	0.06	<2	4	39
C331595		10	<1	0.08	10	0.49	444	6	0.01	41	1020	116	0.11	2	2	30
C331596		10	<1	0.07	10	0.39	702	5	0.01	41	1730	80	0.17	<2	1	30
C331597		10	<1	0.07	10	0.30	222	3	0.01	25	870	34	0.07	<2	1	23
C331598		<10	1	0.02	10	0.13	434	<1	0.01	10	1700	2	0.16	<2	1	25
C331599		10	<1	0.06	10	0.52	657	2	0.01	28	480	21	0.04	<2	2	23
C331600		10	<1	0.06	20	0.56	687	1	0.01	31	460	22	0.04	<2	3	22

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
C331564		<20	0.10	<10	<10	62	<10	101
C331565		<20	0.11	<10	<10	58	<10	101
C331566		<20	0.11	<10	<10	112	<10	138
C331567		<20	0.07	<10	<10	65	<10	200
C331568		<20	0.13	<10	<10	71	<10	109
C331569		<20	0.07	<10	<10	67	<10	238
C331570		<20	<0.01	<10	<10	<1	<10	<2
C331571		<20	0.03	<10	<10	68	<10	87
C331572		<20	0.09	<10	<10	71	<10	110
C331573		<20	0.07	<10	<10	52	<10	78
C331574		<20	0.05	<10	<10	49	<10	78
C331575		<20	0.05	<10	<10	54	<10	167
C331576		<20	0.09	<10	<10	66	<10	84
C331577		<20	0.07	<10	<10	55	<10	251
C331578		<20	0.10	<10	<10	63	<10	118
C331579		<20	0.09	<10	<10	57	<10	100
C331580		<20	0.10	<10	<10	57	<10	93
C331581		<20	0.09	<10	<10	54	<10	139
C331582		<20	0.11	<10	<10	55	<10	188
C331583		<20	0.07	<10	<10	54	<10	157
C331584		<20	0.05	<10	<10	50	<10	282
C331585		<20	0.05	<10	<10	58	<10	91
C331586		<20	0.09	<10	<10	57	<10	145
C331587		<20	0.07	<10	<10	62	<10	271
C331588		<20	0.08	<10	<10	68	<10	133
C331589		<20	0.08	<10	<10	51	<10	305
C331590		<20	<0.01	<10	<10	<1	<10	<2
C331591		<20	0.05	<10	<10	50	<10	155
C331592		<20	0.05	<10	<10	30	<10	287
C331593		<20	0.08	<10	<10	49	<10	86
C331594		<20	0.13	<10	<10	125	<10	275
C331595		<20	0.06	<10	<10	126	<10	272
C331596		<20	0.04	<10	<10	95	<10	306
C331597		<20	0.06	<10	<10	91	<10	143
C331598		<20	0.04	<10	<10	44	<10	30
C331599		<20	0.09	<10	<10	67	<10	132
C331600		<20	0.10	<10	<10	69	<10	130

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 30-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144733

CERTIFICATE COMMENTS

ANALYTICAL COMMENTS

NSS is non-sufficient sample.
Applies to Method: ALL METHODS

LABORATORY ADDRESSES

Processed at ALS Whitehorse located at 78 Mt. Sima Rd, Whitehorse, YT, Canada.

Applies to Method:				
	LOG-22	LOG-24	SCR-41	WEI-21

Processed at ALS Vancouver located at 2103 Dollarton Hwy, North Vancouver, BC, Canada.

Applies to Method:		
	Au-AA23	ME-ICP41

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

CERTIFICATE WH13144734

Project: SUM13-02

P.O. No.: SUM13-02_2

This report is for 240 Soil samples submitted to our lab in Whitehorse, YT, Canada on 13-AUG-2013.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	MURRAY JONES	MASAAKI KOYAMA

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
SCR-41	Screen to -180um and save both
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: MURRAY JONES
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

***** See Appendix Page for comments regarding this certificate *****

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
B346151		0.27	<0.005	<0.2	0.40	2	<10	30	<0.5	<2	0.12	<0.5	4	9	16	1.74
B346152		0.25	0.027	1.2	1.61	17	<10	220	0.8	7	0.48	0.8	9	42	71	3.29
B346153		0.27	0.013	0.4	1.23	8	<10	90	<0.5	2	0.25	<0.5	7	24	61	2.15
B346154		0.22	0.019	1.3	1.27	25	<10	130	0.5	2	0.19	<0.5	5	30	54	2.74
B346155		0.24	0.016	1.3	1.50	7	<10	120	0.5	3	0.30	0.7	4	27	47	1.75
B346156		0.25	<0.005	0.2	1.07	11	<10	100	<0.5	<2	0.14	<0.5	5	22	27	2.42
B346157		0.21	0.006	0.6	1.58	12	<10	150	0.7	<2	0.33	1.1	13	27	59	2.31
B346158		0.23	<0.005	<0.2	0.45	5	<10	40	<0.5	2	0.13	0.5	3	8	14	1.17
B346159		0.19	<0.005	0.3	0.91	9	<10	60	<0.5	<2	0.18	0.5	4	17	17	2.27
B346160		0.15	<0.005	0.3	0.95	9	<10	70	<0.5	2	0.18	0.6	4	17	17	2.26
B346161		0.27	<0.005	0.2	1.06	13	<10	110	<0.5	<2	0.13	<0.5	4	17	22	2.62
B346162		0.22	<0.005	<0.2	0.50	3	<10	30	<0.5	<2	0.11	<0.5	2	7	7	1.07
B346163		0.28	<0.005	<0.2	2.48	7	<10	130	0.6	<2	0.32	<0.5	13	35	26	3.43
B346164		0.22	<0.005	0.3	1.82	7	<10	100	0.6	<2	0.40	<0.5	11	22	32	2.23
B346165		0.19	<0.005	<0.2	2.00	15	<10	90	<0.5	<2	0.20	<0.5	8	32	25	4.60
B346166		0.21	<0.005	0.6	0.70	6	<10	220	<0.5	<2	0.23	<0.5	5	10	19	1.59
B346167		0.17	<0.005	0.4	0.49	3	<10	240	<0.5	2	0.26	0.7	2	5	10	0.88
B346168		0.20	<0.005	1.0	1.63	13	<10	470	0.7	4	0.28	2.9	18	24	70	3.62
B346169		0.22	<0.005	0.5	1.30	8	<10	1240	0.9	3	0.21	1.9	11	18	53	3.04
B346170		0.26	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
B346171		0.17	<0.005	0.5	0.60	4	<10	760	<0.5	<2	0.22	1.3	5	10	23	1.22
B346172		0.19	0.005	0.4	1.63	11	<10	290	0.5	<2	0.27	<0.5	18	43	61	3.02
B346173		0.25	0.005	0.3	1.32	7	<10	140	<0.5	<2	0.23	<0.5	7	30	32	2.57
B346174		0.29	0.006	<0.2	1.87	8	<10	260	<0.5	<2	0.30	<0.5	7	37	36	3.48
B346175		0.25	0.016	0.2	1.08	8	<10	120	<0.5	3	0.09	<0.5	4	21	28	2.22
B346176		0.32	0.041	0.3	1.80	13	<10	290	0.9	2	1.02	0.8	8	53	118	3.03
B346177		0.26	0.011	<0.2	1.88	12	<10	150	0.6	<2	0.22	<0.5	13	33	47	3.19
B346178		0.32	<0.005	<0.2	1.71	16	<10	130	<0.5	<2	0.15	0.5	10	42	32	3.60
B346179		0.21	<0.005	0.3	0.81	5	<10	100	<0.5	<2	0.15	<0.5	7	14	23	1.90
B346180		0.23	0.005	0.2	0.90	7	<10	110	<0.5	<2	0.15	<0.5	8	16	24	2.19
B346181		0.22	0.022	0.3	0.31	<2	<10	60	<0.5	<2	0.16	<0.5	6	8	13	1.59
B346182		0.22	0.005	<0.2	0.94	8	<10	110	<0.5	<2	0.16	<0.5	8	17	28	2.24
B346183		0.23	0.022	1.4	1.74	177	<10	180	0.8	<2	0.27	0.7	9	33	65	3.13
B346184		0.23	<0.005	0.3	1.00	7	<10	130	<0.5	<2	0.38	0.7	10	18	37	1.77
B346185		0.23	<0.005	0.3	0.64	4	<10	70	<0.5	<2	0.24	<0.5	5	7	18	1.26
B346186		0.18	<0.005	0.4	0.69	9	<10	80	<0.5	<2	0.17	0.5	3	14	32	1.91
B346187		0.29	<0.005	0.2	0.44	2	<10	30	<0.5	<2	0.26	<0.5	3	5	47	1.34
B346188		0.26	0.005	0.7	0.94	3	<10	110	0.7	<2	0.31	<0.5	4	11	57	1.33
B346189		0.22	<0.005	0.2	0.57	4	<10	40	<0.5	<2	0.09	<0.5	3	11	9	1.37
B346190		0.23	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	1	0.03

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
B346151		<10	1	0.02	<10	0.11	81	<1	0.02	6	530	2	0.05	<2	<1	11
B346152		10	1	0.12	10	0.64	315	3	0.02	52	1940	27	0.09	<2	3	27
B346153		<10	<1	0.06	10	0.41	149	2	0.02	23	1090	12	0.10	<2	2	26
B346154		10	<1	0.06	10	0.27	93	3	0.02	20	940	11	0.12	<2	1	28
B346155		10	<1	0.06	10	0.38	105	1	0.02	22	1400	13	0.09	<2	1	24
B346156		10	<1	0.06	10	0.19	148	3	0.01	14	530	12	0.03	<2	2	16
B346157		<10	1	0.06	20	0.39	702	2	0.02	23	1090	21	0.07	<2	2	28
B346158		<10	<1	0.03	<10	0.10	96	<1	0.03	5	610	4	0.04	<2	<1	13
B346159		10	<1	0.06	10	0.18	222	3	0.01	11	760	9	0.06	<2	1	14
B346160		10	1	0.07	10	0.21	244	3	0.01	13	750	9	0.07	<2	1	16
B346161		10	1	0.04	10	0.15	103	3	0.01	13	270	15	0.02	<2	2	18
B346162		<10	<1	0.04	<10	0.09	75	<1	0.03	3	300	3	0.03	<2	<1	12
B346163		10	1	0.31	20	0.75	339	<1	0.02	30	490	11	0.03	<2	4	32
B346164		<10	<1	0.13	30	0.40	350	1	0.03	19	860	9	0.09	<2	2	37
B346165		10	1	0.17	10	0.50	276	2	0.02	22	620	11	0.05	<2	3	22
B346166		<10	<1	0.04	10	0.17	262	<1	0.02	8	760	8	0.06	<2	1	18
B346167		<10	1	0.05	<10	0.09	186	<1	0.03	4	620	3	0.05	<2	<1	21
B346168		10	<1	0.11	10	0.38	1065	3	0.02	22	1440	28	0.12	<2	1	31
B346169		10	<1	0.06	20	0.33	532	6	0.02	19	660	57	0.09	<2	2	21
B346170		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.05	<2	<1	<1
B346171		<10	<1	0.05	20	0.17	291	<1	0.03	11	840	8	0.13	<2	<1	20
B346172		10	<1	0.09	10	0.58	547	1	0.03	30	1110	11	0.12	<2	2	26
B346173		10	<1	0.07	10	0.38	290	2	0.02	22	940	9	0.05	<2	1	18
B346174		10	<1	0.12	10	0.78	274	3	0.01	25	1210	11	0.03	2	3	18
B346175		10	<1	0.03	10	0.17	79	3	0.01	14	380	11	<0.01	<2	1	13
B346176		10	<1	0.22	20	0.76	344	2	0.02	45	4530	13	0.01	<2	4	31
B346177		10	<1	0.09	10	0.51	418	2	0.01	32	710	13	0.02	<2	2	21
B346178		10	<1	0.16	10	0.69	432	2	0.01	29	540	13	0.02	<2	3	17
B346179		10	<1	0.03	<10	0.19	601	1	0.02	11	650	9	0.04	<2	<1	17
B346180		10	<1	0.03	10	0.20	616	1	0.02	13	620	8	0.04	<2	1	17
B346181		<10	<1	0.03	<10	0.10	467	<1	0.02	7	550	4	0.03	<2	<1	15
B346182		10	<1	0.06	10	0.23	311	2	0.02	13	750	7	<0.01	<2	1	14
B346183		10	<1	0.10	10	0.54	234	3	0.02	34	780	66	0.04	<2	3	30
B346184		<10	<1	0.05	10	0.29	422	1	0.02	20	1360	7	0.02	<2	1	24
B346185		<10	<1	0.03	<10	0.12	149	<1	0.02	6	780	2	0.02	<2	<1	18
B346186		10	<1	0.06	10	0.15	80	2	0.02	10	710	8	0.03	<2	1	14
B346187		<10	<1	0.02	10	0.10	132	2	0.03	4	830	<2	0.06	<2	1	16
B346188		<10	<1	0.03	10	0.13	207	1	0.03	13	900	5	0.05	<2	1	24
B346189		<10	<1	0.04	<10	0.12	85	<1	0.02	7	350	5	<0.01	<2	1	9
B346190		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	<0.01	<2	<1	<1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
B346151		<20	0.06	<10	<10	61	<10	30
B346152		<20	0.09	<10	<10	196	<10	120
B346153		<20	0.07	<10	<10	74	<10	63
B346154		<20	0.08	<10	<10	147	<10	50
B346155		<20	0.07	<10	<10	66	<10	83
B346156		<20	0.11	<10	<10	112	<10	49
B346157		<20	0.07	<10	<10	66	<10	128
B346158		<20	0.05	<10	<10	33	<10	23
B346159		<20	0.08	<10	<10	90	<10	57
B346160		<20	0.09	<10	<10	95	<10	59
B346161		<20	0.13	<10	<10	113	<10	44
B346162		<20	0.06	<10	<10	32	<10	16
B346163		<20	0.18	<10	<10	64	<10	78
B346164		<20	0.07	<10	<10	44	<10	47
B346165		<20	0.19	<10	<10	83	<10	61
B346166		<20	0.06	<10	<10	42	<10	44
B346167		<20	0.04	<10	<10	22	<10	84
B346168		<20	0.05	<10	<10	60	<10	207
B346169		<20	0.06	<10	<10	52	<10	225
B346170		<20	<0.01	<10	<10	<1	<10	2
B346171		<20	0.02	<10	<10	29	<10	50
B346172		<20	0.10	<10	<10	74	<10	110
B346173		<20	0.08	<10	<10	107	<10	67
B346174		<20	0.19	<10	<10	188	<10	86
B346175		<20	0.08	<10	<10	110	<10	40
B346176		<20	0.10	<10	<10	149	<10	127
B346177		<20	0.10	<10	<10	99	<10	92
B346178		<20	0.13	<10	<10	107	<10	124
B346179		<20	0.05	<10	<10	50	<10	48
B346180		<20	0.06	<10	<10	62	<10	54
B346181		<20	0.05	<10	<10	50	<10	53
B346182		<20	0.09	<10	<10	81	<10	70
B346183		<20	0.11	<10	<10	112	<10	202
B346184		<20	0.05	<10	<10	89	<10	77
B346185		<20	0.04	<10	<10	39	<10	38
B346186		<20	0.09	<10	<10	95	<10	42
B346187		<20	0.06	<10	<10	36	<10	16
B346188		<20	0.03	<10	<10	31	<10	32
B346189		<20	0.05	<10	<10	37	<10	24
B346190		<20	<0.01	<10	<10	<1	<10	<2

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
B346191		0.19	<0.005	0.3	0.73	3	<10	100	<0.5	<2	0.34	1.5	6	13	18	1.44
B346192		0.19	<0.005	0.6	1.73	21	<10	130	0.6	<2	0.27	0.7	13	24	37	2.54
B346193		0.25	0.006	<0.2	1.91	17	<10	140	<0.5	<2	0.21	<0.5	9	31	35	3.42
B346194		0.33	0.031	0.8	2.89	50	<10	250	0.8	<2	0.18	2.1	17	44	97	4.68
B346195		0.20	<0.005	0.3	1.56	6	<10	150	<0.5	<2	0.14	<0.5	8	21	19	2.43
B346196		0.32	0.011	0.8	2.26	28	<10	730	2.0	2	0.44	2.1	22	39	63	4.15
B346197		0.21	<0.005	<0.2	0.28	3	<10	60	<0.5	<2	0.25	1.1	3	3	9	0.66
B346198		0.18	<0.005	0.5	0.86	4	<10	160	<0.5	<2	0.14	<0.5	6	7	16	1.00
B346199		0.28	0.012	2.8	1.80	38	<10	9150	1.9	6	0.37	8.4	31	25	121	5.19
B346200		0.31	0.014	2.3	1.88	37	<10	9650	1.9	5	0.35	8.0	32	24	117	5.34
N899002		0.30	<0.005	0.2	1.94	5	<10	150	2.2	<2	0.55	<0.5	10	18	40	2.39
N899003		0.26	<0.005	<0.2	1.69	11	<10	120	0.8	2	0.41	<0.5	7	25	29	3.17
N899004		0.32	<0.005	<0.2	1.72	20	<10	90	0.7	<2	0.17	<0.5	12	35	39	4.06
N899005		0.38	<0.005	0.2	1.58	7	<10	70	1.1	<2	0.53	0.8	12	34	43	2.60
N899006		0.28	<0.005	<0.2	0.74	3	<10	40	<0.5	<2	0.20	<0.5	6	10	26	1.69
N899007		0.37	<0.005	0.2	1.36	<2	<10	90	0.9	<2	0.40	<0.5	10	26	37	2.64
N899008		0.33	<0.005	0.2	1.61	8	<10	70	0.8	<2	0.28	<0.5	11	40	50	3.06
N899009		0.38	<0.005	0.2	1.92	6	<10	100	1.1	<2	0.39	<0.5	15	52	58	3.34
N899010		0.18	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
N899011		0.34	<0.005	<0.2	1.44	8	<10	90	0.8	<2	0.48	<0.5	12	40	43	2.94
N899012		0.36	<0.005	<0.2	1.22	5	<10	100	0.5	<2	0.32	<0.5	9	21	27	2.40
N899013		0.32	<0.005	0.2	1.53	7	<10	120	0.7	<2	0.42	<0.5	13	32	35	2.82
N899014		0.24	<0.005	0.4	2.66	4	<10	250	1.6	<2	1.63	0.5	23	73	127	3.88
N899015		0.33	0.021	0.2	2.27	7	<10	160	1.1	<2	0.99	<0.5	20	73	139	3.73
N899016		0.34	<0.005	0.2	2.00	5	<10	140	1.0	<2	0.87	<0.5	14	34	77	2.88
N899017		0.29	<0.005	<0.2	1.82	10	<10	80	1.1	<2	0.32	<0.5	15	39	44	3.40
N899018		0.34	<0.005	0.2	0.97	6	10	60	0.6	<2	8.2	<0.5	5	15	29	1.50
N899019		0.23	<0.005	<0.2	1.30	9	<10	120	<0.5	<2	2.02	<0.5	14	28	46	2.61
N899020		0.25	<0.005	<0.2	1.34	9	<10	120	0.5	<2	2.07	<0.5	14	30	42	2.82
N899021		0.38	<0.005	0.2	2.07	5	<10	140	0.8	2	0.71	<0.5	29	52	216	4.99
N899022		0.38	0.005	<0.2	1.87	7	<10	70	1.1	<2	0.44	<0.5	12	27	49	3.26
N899023		0.27	<0.005	<0.2	1.80	6	<10	80	1.4	<2	0.40	<0.5	12	25	45	3.02
N899024		0.32	<0.005	0.2	1.49	4	<10	70	1.2	<2	0.50	<0.5	12	27	49	2.58
N899025		0.33	<0.005	0.2	2.72	14	<10	90	1.6	2	0.36	<0.5	24	43	86	3.94
N899026		0.38	<0.005	<0.2	2.17	9	<10	110	1.2	<2	0.41	<0.5	18	32	78	3.28
N899027		0.32	<0.005	0.2	2.42	8	<10	120	1.0	<2	0.36	<0.5	25	105	68	3.36
N899028		0.26	<0.005	0.2	3.00	9	<10	120	1.3	<2	0.33	<0.5	20	71	66	4.21
N899029		0.29	<0.005	0.2	1.68	11	<10	80	0.9	<2	0.22	<0.5	12	36	43	3.44
N899030		0.09	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
N899031		0.29	0.005	<0.2	2.00	12	<10	70	0.9	<2	0.18	<0.5	13	41	51	3.80

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
B346191		<10	<1	0.06	<10	0.18	288	<1	0.03	10	620	4	0.02	<2	<1	29
B346192		10	<1	0.08	10	0.41	435	1	0.03	21	640	9	<0.01	<2	2	23
B346193		10	<1	0.10	10	0.53	315	2	0.01	29	440	13	<0.01	<2	3	21
B346194		10	<1	0.20	10	0.71	359	3	0.02	41	590	25	0.19	<2	5	26
B346195		10	<1	0.05	10	0.27	487	1	0.02	14	560	12	0.02	<2	1	17
B346196		10	<1	0.26	30	0.95	1055	2	0.01	50	840	91	<0.01	<2	7	38
B346197		<10	<1	0.05	<10	0.08	115	<1	0.04	5	640	<2	<0.01	<2	<1	15
B346198		<10	<1	0.03	<10	0.10	222	<1	0.03	8	500	3	0.02	<2	<1	17
B346199		10	<1	0.15	20	0.37	1945	6	0.01	68	1470	142	0.03	<2	7	53
B346200		10	<1	0.15	20	0.38	1975	6	0.01	69	1460	142	0.03	<2	8	53
N899002		10	<1	0.08	10	0.55	664	1	0.03	15	680	47	0.01	<2	3	127
N899003		10	<1	0.07	10	0.57	391	2	0.02	17	570	38	0.01	<2	3	62
N899004		10	<1	0.07	10	0.53	554	4	0.01	27	410	23	0.01	2	3	23
N899005		<10	1	0.09	10	0.63	569	1	0.02	24	1040	26	0.02	<2	4	68
N899006		<10	<1	0.04	<10	0.21	213	<1	0.02	7	610	6	0.03	<2	1	17
N899007		10	<1	0.14	10	0.53	414	1	0.02	17	990	17	0.05	<2	3	45
N899008		10	1	0.12	10	0.60	370	2	0.01	25	910	19	0.08	<2	2	39
N899009		10	1	0.26	10	0.81	425	1	0.02	35	940	15	0.06	<2	5	54
N899010		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	1
N899011		10	<1	0.13	10	0.62	432	1	0.02	26	1100	11	0.07	<2	3	51
N899012		10	1	0.07	10	0.45	455	2	0.01	15	930	8	0.06	<2	2	32
N899013		10	<1	0.07	10	0.66	613	7	0.02	24	680	14	0.08	<2	2	41
N899014		10	<1	0.50	20	2.09	910	1	0.03	75	1960	19	0.09	<2	5	148
N899015		10	1	0.34	10	1.25	651	2	0.03	70	1810	9	0.09	<2	6	95
N899016		10	1	0.25	10	1.16	688	2	0.02	29	1110	10	0.10	<2	3	76
N899017		10	1	0.08	10	0.79	686	3	0.01	29	1050	12	0.08	<2	2	53
N899018		<10	<1	0.04	10	8.47	733	1	0.01	13	880	8	0.07	<2	1	75
N899019		<10	<1	0.05	10	1.12	1205	1	0.02	23	960	12	0.16	<2	2	37
N899020		<10	1	0.05	10	1.21	1270	1	0.02	25	950	13	0.16	<2	2	36
N899021		10	1	0.66	20	1.27	597	7	0.04	52	1920	8	0.23	<2	6	78
N899022		10	1	0.06	20	0.71	577	1	0.01	25	980	16	0.02	<2	4	78
N899023		10	<1	0.05	20	0.72	528	2	0.02	20	840	21	0.06	<2	2	83
N899024		10	<1	0.07	20	0.63	677	3	0.02	20	1080	12	0.06	<2	3	65
N899025		10	1	0.09	30	0.85	839	9	0.01	47	1160	14	0.07	<2	3	52
N899026		10	<1	0.07	20	0.67	656	4	0.02	34	890	12	0.07	<2	3	52
N899027		10	1	0.08	10	1.35	488	2	0.02	98	430	6	0.04	<2	3	35
N899028		10	<1	0.13	20	1.13	829	5	0.02	49	960	12	0.13	<2	3	61
N899029		10	1	0.06	10	0.60	594	3	0.01	25	820	12	0.09	<2	2	41
N899030		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	<1
N899031		10	1	0.13	10	0.67	542	8	0.01	28	650	20	0.13	<2	3	34

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
B346191		<20	0.05	<10	<10	36	<10	49
B346192		<20	0.08	<10	<10	57	<10	76
B346193		<20	0.13	<10	<10	82	<10	93
B346194		<20	0.13	<10	<10	86	<10	273
B346195		<20	0.09	<10	<10	54	<10	64
B346196		<20	0.07	<10	<10	60	<10	468
B346197		<20	0.03	<10	<10	20	<10	53
B346198		<20	0.03	<10	<10	25	<10	22
B346199		<20	0.03	<10	10	72	<10	688
B346200		<20	0.03	<10	<10	73	<10	699
N899002		<20	0.07	<10	10	50	<10	125
N899003		<20	0.09	<10	<10	76	<10	111
N899004		<20	0.12	<10	<10	87	<10	126
N899005		<20	0.11	<10	<10	67	<10	118
N899006		<20	0.08	<10	<10	50	<10	41
N899007		<20	0.11	<10	<10	67	<10	85
N899008		<20	0.09	<10	<10	74	<10	77
N899009		<20	0.14	<10	<10	81	<10	82
N899010		<20	<0.01	<10	<10	<1	<10	2
N899011		<20	0.10	<10	<10	77	<10	66
N899012		<20	0.07	<10	10	56	<10	69
N899013		<20	0.08	<10	<10	57	<10	96
N899014		<20	0.22	<10	<10	78	<10	113
N899015		<20	0.18	<10	<10	91	<10	87
N899016		<20	0.12	<10	<10	57	<10	77
N899017		<20	0.07	<10	<10	79	10	98
N899018		<20	0.03	<10	<10	27	<10	61
N899019		<20	0.05	<10	<10	45	<10	90
N899020		<20	0.05	<10	<10	47	<10	95
N899021		<20	0.23	<10	<10	103	<10	89
N899022		<20	0.07	<10	<10	81	<10	70
N899023		<20	0.05	<10	<10	63	<10	76
N899024		<20	0.06	<10	<10	56	<10	79
N899025		<20	0.09	<10	<10	82	<10	93
N899026		<20	0.08	<10	<10	69	<10	86
N899027		<20	0.19	<10	<10	74	<10	68
N899028		<20	0.12	<10	<10	101	<10	87
N899029		<20	0.06	<10	<10	83	<10	72
N899030		<20	<0.01	<10	<10	<1	<10	<2
N899031		<20	0.10	<10	<10	82	<10	82

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
N899032		0.34	<0.005	0.2	2.05	10	<10	90	0.9	<2	0.27	<0.5	19	55	82	4.00
N899033		0.31	<0.005	0.2	1.94	11	<10	100	0.8	<2	0.21	<0.5	15	43	43	3.39
N899034		0.21	<0.005	<0.2	0.57	9	<10	40	<0.5	<2	0.26	<0.5	4	17	24	1.75
N899035		0.35	<0.005	<0.2	1.61	20	<10	160	0.7	2	0.26	<0.5	11	38	83	3.21
N899036		0.31	<0.005	0.4	1.57	6	<10	350	1.1	2	0.39	0.5	17	39	70	2.91
N899037		0.28	<0.005	0.4	2.92	82	<10	300	1.5	<2	0.43	1.0	23	91	126	3.95
N899038		0.27	<0.005	0.4	1.48	12	<10	170	1.3	<2	0.61	0.7	14	44	65	3.00
N899039		0.30	<0.005	0.5	1.94	12	<10	120	1.0	2	0.36	0.6	17	35	38	3.00
N899040		0.38	<0.005	0.6	2.84	8	<10	150	1.8	3	0.63	0.8	17	40	36	3.69
N899041		0.32	<0.005	0.7	2.91	16	<10	90	2.9	3	0.67	0.9	20	48	51	3.98
N899042		0.35	<0.005	0.8	2.47	29	<10	100	1.3	<2	0.33	<0.5	16	61	186	4.72
N899043		0.31	<0.005	0.2	1.69	22	<10	170	0.7	<2	0.51	<0.5	14	50	37	3.62
N899044		0.25	<0.005	<0.2	1.36	7	<10	120	0.5	<2	0.24	0.9	6	22	58	2.14
N899045		0.35	0.017	0.2	1.69	12	<10	100	0.9	<2	0.57	<0.5	14	37	52	3.04
N899046		0.38	0.011	0.3	1.78	12	<10	100	1.5	<2	0.55	0.8	15	43	76	3.22
N899047		0.43	<0.005	<0.2	1.86	7	<10	80	1.0	3	0.54	<0.5	23	64	181	3.43
N899048		0.23	<0.005	<0.2	1.71	8	<10	80	0.7	<2	0.49	<0.5	17	51	52	2.84
N899049		0.30	<0.005	0.7	1.94	8	<10	70	1.4	2	0.44	1.0	17	47	100	2.68
N899050		0.15	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
L644459		0.26	<0.005	0.2	1.90	13	<10	110	1.5	2	0.32	0.6	13	31	38	2.99
L644460		0.28	<0.005	<0.2	1.65	8	<10	60	1.8	<2	0.17	<0.5	10	28	26	2.79
L644461		0.32	0.005	<0.2	1.74	8	<10	60	1.6	2	0.18	<0.5	11	30	28	2.86
L644462		0.34	0.007	<0.2	1.38	10	<10	80	2.9	5	0.26	0.5	8	22	28	2.99
L644463		0.32	<0.005	<0.2	1.47	11	<10	80	3.0	4	0.29	0.5	9	24	30	3.11
L644464		0.30	<0.005	0.2	0.65	6	<10	20	1.0	<2	0.20	<0.5	5	10	17	1.61
L644465		0.31	<0.005	<0.2	1.64	15	<10	90	0.5	<2	0.13	<0.5	9	36	30	3.58
L644466		0.20	<0.005	0.3	1.69	8	<10	110	0.5	<2	0.30	<0.5	8	32	61	2.68
L644467		0.34	<0.005	0.2	2.00	22	<10	140	0.8	3	0.20	<0.5	11	48	48	3.53
L644468		0.28	<0.005	0.5	1.50	10	<10	130	0.6	<2	0.28	<0.5	12	43	60	3.23
L644469		0.18	<0.005	0.7	0.82	6	<10	70	<0.5	<2	0.24	<0.5	7	22	28	2.04
L644470		0.11	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
L644471		0.25	<0.005	<0.2	2.26	11	<10	110	0.7	<2	0.16	<0.5	12	56	57	3.63
L644472		0.19	<0.005	0.4	1.13	5	<10	50	<0.5	<2	0.11	<0.5	4	20	31	2.05
L644473		0.23	<0.005	0.3	1.41	19	<10	80	<0.5	<2	0.11	<0.5	10	30	37	3.79
L644474		0.19	<0.005	0.2	1.54	13	<10	110	<0.5	<2	0.13	<0.5	12	32	35	3.19
L644475		0.18	0.009	0.7	2.68	31	<10	150	1.1	<2	0.27	<0.5	27	65	149	4.37
L644476		0.20	<0.005	0.2	0.67	4	<10	50	<0.5	<2	0.11	<0.5	4	14	20	1.59
L644477		0.19	<0.005	0.2	0.82	5	<10	70	<0.5	<2	0.29	<0.5	7	12	28	1.56
L644478		0.20	0.010	0.2	0.85	7	<10	70	<0.5	<2	0.16	<0.5	5	19	33	1.95
L644479		0.19	<0.005	0.4	1.65	14	<10	110	<0.5	<2	0.17	<0.5	10	39	46	3.49

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
N899032		10	<1	0.22	10	0.98	624	17	0.02	42	710	13	0.19	<2	5	52
N899033		10	1	0.09	10	0.72	715	6	0.02	34	1040	14	0.10	<2	2	30
N899034		<10	<1	0.07	10	0.18	127	9	0.01	13	1140	5	0.13	<2	1	25
N899035		10	1	0.08	10	0.60	355	7	0.02	26	690	16	0.08	<2	2	35
N899036		10	1	0.13	20	0.69	486	5	0.02	30	780	27	0.09	<2	3	56
N899037		10	<1	0.21	10	1.14	564	10	0.02	64	1260	42	0.14	<2	5	75
N899038		10	1	0.20	10	0.73	501	3	0.02	32	1370	31	0.12	<2	3	93
N899039		10	<1	0.06	10	0.69	992	2	0.02	24	1150	53	0.13	<2	1	62
N899040		10	1	0.08	10	1.15	841	1	0.02	27	1110	126	0.08	<2	2	114
N899041		10	<1	0.08	20	1.17	940	1	0.02	40	1390	126	0.07	<2	2	116
N899042		10	1	0.15	30	0.81	508	11	0.02	36	1040	26	0.10	<2	4	53
N899043		10	<1	0.11	10	0.70	745	2	0.02	31	1010	26	0.09	<2	2	58
N899044		10	<1	0.03	10	0.16	129	2	0.01	17	970	10	0.12	<2	1	25
N899045		10	<1	0.11	20	0.65	483	1	0.02	29	1360	17	0.02	<2	4	54
N899046		10	<1	0.15	20	0.79	569	1	0.03	35	1340	24	0.03	<2	5	59
N899047		10	<1	0.23	20	0.99	449	4	0.03	75	940	12	0.06	<2	5	48
N899048		10	<1	0.13	10	0.73	366	1	0.04	43	830	11	0.07	<2	3	40
N899049		10	<1	0.11	20	0.74	412	3	0.03	49	680	56	0.04	<2	3	42
N899050		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.01	<2	<1	1
L644459		10	<1	0.09	20	0.56	754	4	0.02	28	620	22	0.04	<2	3	26
L644460		10	<1	0.08	20	0.50	441	2	0.01	24	420	18	0.03	<2	3	15
L644461		10	<1	0.08	20	0.53	461	3	0.01	27	410	17	0.03	<2	3	15
L644462		10	<1	0.10	40	0.41	807	9	0.02	21	650	49	0.03	<2	3	20
L644463		10	<1	0.11	50	0.45	882	9	0.02	23	710	50	0.03	<2	3	21
L644464		<10	<1	0.04	20	0.18	374	3	0.02	8	820	42	0.05	<2	1	14
L644465		10	<1	0.05	10	0.43	252	4	0.01	23	570	10	0.05	<2	2	14
L644466		10	<1	0.06	10	0.45	216	1	0.02	28	1030	8	0.12	<2	2	27
L644467		10	<1	0.13	10	0.65	443	1	0.01	45	810	10	0.07	<2	3	19
L644468		10	<1	0.14	10	0.54	379	2	0.02	37	990	19	0.11	<2	3	29
L644469		<10	<1	0.06	10	0.24	194	2	0.02	19	950	16	0.13	<2	1	23
L644470		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	1
L644471		10	<1	0.10	10	0.59	327	2	0.02	42	680	28	0.12	<2	3	26
L644472		<10	<1	0.02	10	0.11	65	2	0.01	10	1010	8	0.13	<2	1	14
L644473		10	<1	0.08	10	0.37	288	5	0.01	25	300	13	0.02	<2	3	17
L644474		10	<1	0.12	10	0.53	825	3	0.02	23	490	12	0.03	<2	3	20
L644475		10	<1	0.14	20	0.92	632	8	0.02	70	1140	28	0.10	<2	5	30
L644476		<10	<1	0.03	10	0.11	62	2	0.02	12	580	4	0.06	<2	1	13
L644477		<10	<1	0.04	10	0.20	290	1	0.02	10	780	3	0.05	<2	1	22
L644478		10	<1	0.04	10	0.19	105	5	0.01	17	580	5	0.06	<2	1	20
L644479		10	<1	0.16	10	0.57	358	4	0.01	30	670	11	0.05	<2	4	20

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
N899032		<20	0.15	<10	<10	81	<10	82
N899033		<20	0.08	<10	<10	64	<10	96
N899034		<20	0.04	<10	<10	43	<10	47
N899035		<20	0.09	<10	<10	85	<10	146
N899036		<20	0.10	<10	<10	69	<10	123
N899037		<20	0.12	<10	<10	148	<10	262
N899038		<20	0.09	<10	<10	84	<10	129
N899039		<20	0.04	<10	<10	66	<10	109
N899040		<20	0.06	<10	<10	80	<10	141
N899041		<20	0.06	<10	<10	91	<10	155
N899042		<20	0.12	<10	10	117	<10	101
N899043		<20	0.09	<10	<10	87	<10	119
N899044		<20	0.03	<10	<10	53	<10	69
N899045		<20	0.12	<10	<10	72	<10	89
N899046		<20	0.13	<10	<10	73	<10	147
N899047		<20	0.17	<10	<10	72	30	115
N899048		<20	0.12	<10	<10	66	<10	86
N899049		<20	0.12	<10	<10	56	<10	139
N899050		<20	<0.01	<10	<10	<1	<10	2
L644459		<20	0.07	<10	<10	54	<10	123
L644460		<20	0.09	<10	<10	53	<10	105
L644461		<20	0.10	<10	<10	55	<10	108
L644462		30	0.07	<10	10	42	<10	143
L644463		30	0.07	<10	10	45	<10	156
L644464		<20	0.04	<10	<10	33	<10	75
L644465		<20	0.11	<10	<10	121	<10	70
L644466		<20	0.07	<10	<10	72	<10	72
L644467		<20	0.12	<10	<10	124	<10	118
L644468		<20	0.12	<10	<10	90	<10	115
L644469		<20	0.05	<10	<10	57	<10	58
L644470		<20	<0.01	<10	<10	<1	<10	4
L644471		<20	0.13	<10	<10	124	<10	117
L644472		<20	0.04	<10	<10	44	<10	31
L644473		<20	0.14	<10	<10	119	<10	83
L644474		<20	0.12	<10	<10	86	<10	94
L644475		<20	0.14	<10	<10	93	<10	267
L644476		<20	0.04	<10	<10	47	<10	32
L644477		<20	0.05	<10	<10	41	<10	47
L644478		<20	0.06	<10	<10	68	<10	48
L644479		<20	0.14	<10	<10	105	<10	75

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
L644480		0.27	0.005	0.3	1.98	17	<10	120	0.6	<2	0.19	<0.5	11	46	52	3.93
L644481		0.30	<0.005	0.2	1.48	13	<10	100	0.5	<2	0.23	<0.5	14	35	62	3.04
L644482		0.20	<0.005	<0.2	1.14	6	<10	90	<0.5	<2	0.20	<0.5	6	27	40	2.34
L644483		0.21	<0.005	<0.2	1.11	10	<10	80	<0.5	<2	0.14	<0.5	9	30	43	3.04
L644484		0.16	<0.005	0.5	1.86	11	<10	150	0.7	2	0.23	0.6	11	45	64	3.56
L644485		0.34	0.013	<0.2	1.47	10	<10	120	0.9	5	0.19	0.6	10	30	62	2.99
L644486		0.17	<0.005	<0.2	0.58	3	<10	60	<0.5	2	0.24	<0.5	6	14	18	1.48
L644487		0.37	<0.005	<0.2	0.84	7	<10	70	1.2	<2	0.22	0.5	6	15	19	2.20
L644488		0.18	<0.005	0.3	1.49	29	<10	110	<0.5	<2	0.15	0.5	9	27	34	3.83
L644489		0.13	<0.005	0.5	1.12	13	<10	100	<0.5	<2	0.19	1.5	15	24	31	2.66
L644490		0.10	<0.005	<0.2	0.01	<2	<10	<10	<0.5	3	0.01	<0.5	<1	<1	<1	0.03
L644491		0.13	0.006	1.1	0.89	23	<10	110	<0.5	<2	0.57	4.6	15	17	47	1.93
L644492		0.19	<0.005	<0.2	1.03	9	<10	100	<0.5	<2	0.16	<0.5	9	20	28	1.93
L644493		0.26	0.005	0.2	2.48	14	<10	120	1.0	<2	0.29	1.8	18	40	53	3.66
L644494		0.19	<0.005	0.4	1.48	11	<10	160	0.5	<2	0.21	1.5	11	35	41	3.63
L644495		0.15	<0.005	<0.2	0.23	<2	<10	40	<0.5	<2	0.14	<0.5	2	7	8	0.77
L644496		0.24	<0.005	0.2	0.62	10	<10	50	<0.5	2	0.15	<0.5	5	15	17	1.79
L644497		0.31	<0.005	<0.2	2.05	35	<10	90	0.6	<2	0.13	<0.5	12	33	39	3.26
L644498		0.25	<0.005	<0.2	1.78	13	<10	90	<0.5	<2	0.11	<0.5	12	38	38	3.54
L644499		0.25	0.007	<0.2	1.99	9	<10	60	0.6	<2	0.16	<0.5	12	34	49	2.65
L644500		0.29	<0.005	<0.2	2.01	6	<10	60	0.5	<2	0.19	<0.5	12	37	24	2.65
L646652		0.34	<0.005	0.3	1.17	8	<10	50	1.2	<2	0.40	<0.5	14	27	81	2.54
L646653		0.41	<0.005	1.2	1.96	10	<10	60	2.8	10	0.37	<0.5	15	26	164	3.56
L646654		0.40	<0.005	0.6	1.89	47	<10	1810	1.7	<2	0.30	1.7	26	42	190	4.60
L646655		0.33	0.008	0.7	1.81	88	<10	980	1.7	2	0.21	1.0	27	57	235	4.99
L646656		0.31	<0.005	0.2	1.05	30	<10	930	<0.5	<2	0.16	<0.5	10	29	43	3.22
L646657		0.25	<0.005	0.3	1.20	39	<10	230	0.5	2	0.14	<0.5	8	35	49	3.22
L646658		0.30	<0.005	0.2	1.13	24	<10	320	<0.5	4	0.19	<0.5	8	38	40	3.01
L646659		0.29	<0.005	<0.2	1.99	12	<10	130	0.7	<2	0.16	<0.5	15	43	62	3.77
L646660		0.28	<0.005	<0.2	2.02	8	<10	130	0.7	<2	0.16	<0.5	16	43	64	3.47
L646661		0.29	<0.005	0.2	1.39	15	<10	170	<0.5	<2	0.21	<0.5	19	51	47	3.55
L646662		0.36	<0.005	<0.2	1.33	16	<10	190	0.5	<2	0.17	<0.5	15	34	40	3.81
L646663		0.23	<0.005	<0.2	0.95	6	<10	180	<0.5	<2	0.12	<0.5	8	26	32	2.51
L646664		0.29	<0.005	<0.2	2.35	7	<10	140	0.6	<2	0.33	<0.5	20	63	45	3.22
L646665		0.27	<0.005	<0.2	2.22	4	<10	110	0.5	<2	0.35	<0.5	18	66	41	3.10
L646666		0.30	<0.005	0.2	4.28	32	<10	300	1.3	<2	0.93	<0.5	38	167	94	5.78
L646667		0.27	0.023	0.2	2.61	104	<10	230	0.8	<2	0.25	<0.5	24	65	78	4.36
L646668		0.30	<0.005	0.2	2.45	19	<10	110	1.0	<2	0.12	<0.5	24	50	127	4.81
L646669		0.28	<0.005	<0.2	1.78	22	<10	120	0.7	2	0.18	<0.5	24	43	50	4.08
L646670		0.22	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
L644480		10	1	0.19	10	0.71	398	5	0.01	33	580	14	0.04	<2	5	21
L644481		10	<1	0.18	10	0.65	426	6	0.02	33	670	12	0.05	<2	4	20
L644482		10	<1	0.04	10	0.15	97	3	0.01	19	1040	10	0.11	<2	1	21
L644483		10	<1	0.07	10	0.34	339	4	0.01	22	780	9	0.07	<2	2	18
L644484		10	<1	0.12	10	0.69	504	23	0.02	30	990	30	0.09	<2	4	26
L644485		<10	<1	0.13	20	0.46	449	30	0.01	27	620	32	0.02	<2	3	14
L644486		<10	<1	0.06	10	0.21	198	1	0.02	10	520	4	0.09	<2	1	20
L644487		<10	<1	0.07	20	0.26	667	4	0.01	13	570	32	0.01	<2	2	15
L644488		10	<1	0.07	10	0.29	483	3	0.01	21	460	11	0.03	<2	2	23
L644489		10	<1	0.07	10	0.34	514	2	0.02	18	490	8	0.05	<2	2	25
L644490		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.01	<2	<1	1
L644491		<10	<1	0.13	10	0.34	973	1	0.02	18	1470	25	0.13	<2	1	50
L644492		<10	<1	0.08	10	0.36	398	1	0.02	16	680	9	0.05	<2	1	17
L644493		10	<1	0.12	10	0.64	889	2	0.01	36	890	14	0.05	<2	4	26
L644494		10	<1	0.13	10	0.43	652	6	0.01	25	700	12	0.09	<2	2	32
L644495		<10	<1	0.03	<10	0.08	46	<1	0.01	4	550	<2	0.04	<2	<1	14
L644496		<10	<1	0.04	<10	0.21	188	1	0.02	10	530	3	0.06	<2	1	16
L644497		10	<1	0.07	10	0.59	569	3	0.01	24	540	11	0.05	<2	2	18
L644498		10	<1	0.06	10	0.57	674	4	0.01	27	590	11	0.05	<2	2	16
L644499		10	<1	0.08	10	0.59	394	4	0.01	30	440	6	0.03	<2	3	15
L644500		10	<1	0.10	10	0.61	407	1	0.01	26	330	8	0.02	<2	4	15
L646652		<10	<1	0.07	20	0.50	445	6	0.02	22	1000	12	0.04	<2	3	53
L646653		10	<1	0.07	30	0.70	846	31	0.02	21	850	38	0.07	<2	4	99
L646654		10	<1	0.12	20	0.95	1230	7	0.01	55	1180	26	0.13	<2	6	61
L646655		10	<1	0.28	20	0.88	1370	8	0.04	67	1630	16	0.28	<2	7	51
L646656		10	<1	0.09	10	0.35	493	5	0.02	23	790	15	0.12	<2	1	26
L646657		10	1	0.10	10	0.39	365	7	0.02	26	1190	19	0.18	<2	1	32
L646658		10	<1	0.09	10	0.34	365	5	0.02	21	1130	11	0.18	<2	1	43
L646659		10	<1	0.16	10	0.81	739	2	0.02	50	570	7	0.12	<2	3	29
L646660		10	<1	0.16	10	0.81	670	2	0.02	48	540	6	0.12	<2	4	28
L646661		10	<1	0.13	10	0.55	986	4	0.01	47	680	11	0.10	<2	2	29
L646662		10	<1	0.10	10	0.46	1160	3	0.01	28	550	12	0.05	<2	2	22
L646663		10	<1	0.05	10	0.30	352	2	0.01	16	750	6	0.09	<2	1	17
L646664		10	<1	0.32	10	1.07	385	<1	0.03	52	730	7	0.03	<2	4	29
L646665		10	<1	0.28	10	1.26	335	1	0.04	46	870	7	0.13	<2	3	35
L646666		10	<1	0.88	20	2.53	1355	<1	0.05	109	1800	12	0.03	<2	9	74
L646667		10	<1	0.30	20	1.06	635	1	0.03	54	760	8	0.11	<2	5	25
L646668		10	<1	0.13	30	0.92	1915	2	0.01	51	640	25	0.05	<2	3	17
L646669		10	<1	0.09	10	0.66	2350	3	0.02	40	640	16	0.06	<2	3	21
L646670		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.01	<2	<1	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
L644480		<20	0.16	<10	<10	109	<10	83
L644481		<20	0.11	<10	<10	75	<10	86
L644482		<20	0.04	<10	<10	69	<10	56
L644483		<20	0.08	<10	<10	97	<10	74
L644484		<20	0.11	<10	<10	92	<10	159
L644485		<20	0.09	<10	<10	66	<10	280
L644486		<20	0.04	<10	<10	33	<10	48
L644487		<20	0.05	<10	<10	32	<10	141
L644488		<20	0.12	<10	<10	95	<10	78
L644489		<20	0.08	<10	<10	63	<10	79
L644490		<20	<0.01	<10	<10	<1	<10	2
L644491		<20	0.03	<10	<10	36	<10	184
L644492		<20	0.06	<10	<10	52	<10	99
L644493		<20	0.10	<10	<10	75	<10	200
L644494		<20	0.10	<10	<10	118	<10	117
L644495		<20	0.03	<10	<10	23	<10	22
L644496		<20	0.06	<10	<10	49	<10	42
L644497		<20	0.09	<10	<10	70	<10	111
L644498		<20	0.09	<10	<10	78	<10	103
L644499		<20	0.11	<10	<10	67	<10	70
L644500		<20	0.13	<10	<10	64	<10	66
L646652		<20	0.06	<10	<10	57	<10	74
L646653		<20	0.04	<10	<10	74	10	105
L646654		<20	0.05	<10	<10	109	<10	167
L646655		<20	0.08	<10	<10	141	<10	164
L646656		<20	0.07	<10	<10	85	<10	97
L646657		<20	0.05	<10	<10	109	<10	111
L646658		<20	0.06	<10	<10	112	<10	86
L646659		<20	0.14	<10	<10	78	<10	124
L646660		<20	0.13	<10	<10	83	<10	123
L646661		<20	0.11	<10	<10	91	<10	103
L646662		<20	0.11	<10	<10	85	<10	95
L646663		<20	0.05	<10	<10	61	<10	57
L646664		<20	0.14	<10	<10	65	<10	71
L646665		<20	0.12	<10	<10	74	<10	75
L646666		<20	0.27	<10	<10	102	<10	109
L646667		<20	0.17	<10	<10	96	<10	103
L646668		<20	0.07	<10	<10	91	<10	128
L646669		<20	0.10	<10	<10	83	<10	118
L646670		<20	<0.01	<10	<10	<1	<10	<2

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
L646671		0.24	<0.005	<0.2	1.70	27	<10	170	0.9	<2	0.18	<0.5	26	33	71	3.11
L646672		0.33	<0.005	<0.2	2.10	13	<10	160	0.7	<2	0.27	<0.5	18	40	92	3.28
L646673		0.25	<0.005	<0.2	2.04	15	<10	180	0.5	<2	0.37	<0.5	12	48	72	2.98
L646674		0.35	<0.005	<0.2	1.13	5	<10	60	0.8	<2	0.16	<0.5	6	12	22	1.93
L646675		0.37	<0.005	0.2	1.24	5	<10	60	0.8	<2	0.15	<0.5	5	14	22	2.06
L646676		0.36	<0.005	<0.2	1.12	7	<10	60	0.5	<2	0.16	<0.5	6	17	27	2.31
L646677		0.38	<0.005	0.2	1.46	7	<10	80	0.7	<2	0.28	0.7	8	19	34	2.61
L646678		0.42	<0.005	<0.2	1.31	6	<10	60	0.6	<2	0.20	0.5	7	19	30	2.44
L646679		0.29	<0.005	<0.2	1.28	6	<10	70	0.9	<2	0.20	<0.5	8	18	33	2.11
L646680		0.37	<0.005	<0.2	1.06	6	<10	60	0.7	<2	0.19	<0.5	7	16	27	1.96
L646681		0.33	<0.005	<0.2	1.61	9	<10	80	1.2	<2	0.21	<0.5	11	28	35	3.84
L646682		0.42	<0.005	<0.2	1.35	3	<10	60	1.0	2	0.43	<0.5	10	25	27	3.36
L646683		0.48	<0.005	0.2	1.70	3	<10	90	1.5	3	0.73	0.9	13	19	53	3.65
L646684		0.43	<0.005	<0.2	1.39	<2	<10	70	1.5	2	0.61	<0.5	12	26	32	4.18
L646685		0.46	<0.005	<0.2	1.40	<2	<10	20	2.1	<2	0.74	<0.5	13	25	28	4.28
L646686		0.32	<0.005	0.3	1.62	34	<10	1130	0.8	<2	0.28	0.5	17	46	133	3.15
L646687		0.42	0.005	0.2	0.76	7	<10	110	0.5	<2	0.38	0.5	12	23	64	2.06
L646688		0.37	<0.005	0.6	1.06	23	<10	90	0.5	4	0.49	1.1	17	30	134	2.79
L646689		0.32	<0.005	0.5	1.25	11	<10	150	0.8	2	0.94	1.0	17	39	155	3.57
L646690		0.11	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	1	0.03
L646691		0.35	<0.005	<0.2	1.07	4	<10	60	1.0	3	0.52	0.6	10	28	36	2.35
L646692		0.34	<0.005	0.8	0.96	4	<10	60	0.6	2	0.49	1.5	9	25	76	2.44
L646693		0.35	<0.005	0.2	1.27	3	<10	80	1.3	3	0.44	<0.5	10	27	55	2.33
L646694		0.30	<0.005	0.2	1.74	7	<10	90	1.4	3	0.25	0.7	9	22	72	2.67
L646695		0.37	<0.005	0.9	1.64	12	<10	90	1.6	5	0.23	1.1	8	21	117	2.85
L646696		0.30	<0.005	1.0	1.63	6	<10	80	1.8	3	0.25	0.7	9	21	95	2.44
L646697		0.34	<0.005	0.5	0.97	6	<10	50	0.8	3	0.15	0.5	5	17	30	2.20
L646698		0.39	<0.005	0.5	1.34	9	<10	60	0.8	3	0.16	0.5	6	21	50	2.71
L646699		0.37	<0.005	<0.2	1.25	4	<10	100	0.6	2	0.18	<0.5	6	12	34	3.06
L646700		0.42	<0.005	<0.2	1.51	5	<10	140	0.8	3	0.19	<0.5	7	12	31	3.73
L646751		0.26	<0.005	0.4	2.43	25	<10	100	1.9	5	0.32	2.5	11	35	105	3.64
L646752		0.36	<0.005	0.3	1.03	4	<10	50	<0.5	<2	0.24	<0.5	6	15	20	1.84
L646753		0.30	<0.005	<0.2	0.53	<2	<10	30	<0.5	<2	0.16	<0.5	4	6	9	1.28
L646754		0.32	<0.005	<0.2	1.46	4	<10	70	0.5	2	0.24	<0.5	8	23	21	2.75
L646755		0.25	<0.005	<0.2	0.91	3	<10	60	<0.5	<2	0.15	<0.5	6	13	15	1.57
L646756		0.36	<0.005	<0.2	1.56	5	<10	90	<0.5	2	0.23	<0.5	8	23	23	2.68
L646757		0.33	<0.005	<0.2	1.73	7	<10	100	0.5	3	0.26	0.5	9	26	31	2.98
L646758		0.34	<0.005	<0.2	1.17	7	<10	70	<0.5	<2	0.18	<0.5	6	26	23	3.22
L646759		0.31	<0.005	<0.2	1.61	7	<10	90	<0.5	2	0.15	<0.5	8	25	20	2.83
L646760		0.31	0.005	<0.2	2.02	7	<10	100	0.5	2	0.17	<0.5	9	30	24	3.20

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
L646671		10	<1	0.11	10	0.52	5200	2	0.02	58	730	12	0.03	<2	4	26
L646672		10	<1	0.24	10	0.73	1530	1	0.02	43	1050	11	0.02	<2	5	20
L646673		10	<1	0.10	10	0.72	310	1	0.03	43	1170	9	0.17	<2	3	30
L646674		10	<1	0.11	10	0.33	406	1	0.01	9	670	23	0.07	<2	1	14
L646675		10	<1	0.10	10	0.34	266	1	0.01	10	670	14	0.08	<2	1	14
L646676		10	<1	0.06	10	0.34	259	1	0.01	12	560	11	0.05	<2	1	15
L646677		10	<1	0.11	10	0.43	383	<1	0.01	14	810	15	0.01	<2	3	20
L646678		10	<1	0.11	10	0.45	356	<1	0.01	15	450	8	0.03	<2	2	16
L646679		<10	<1	0.08	10	0.36	356	<1	0.02	12	700	6	0.04	<2	2	24
L646680		<10	<1	0.08	10	0.30	312	<1	0.02	11	610	6	0.03	<2	2	21
L646681		10	<1	0.05	10	0.46	660	2	0.01	20	710	12	0.06	<2	3	25
L646682		10	<1	0.07	10	0.36	460	1	0.02	17	1200	6	<0.01	<2	3	50
L646683		10	1	0.26	10	0.55	743	1	0.02	15	1810	11	<0.01	<2	5	123
L646684		10	1	0.06	10	0.31	740	1	0.02	14	1830	6	<0.01	<2	6	52
L646685		10	1	0.03	10	0.26	1105	<1	0.02	14	1970	6	<0.01	<2	8	169
L646686		10	1	0.28	10	0.78	432	26	0.03	55	910	19	0.09	<2	4	28
L646687		<10	<1	0.11	10	0.34	290	7	0.02	22	930	11	0.01	<2	2	42
L646688		<10	1	0.20	10	0.49	456	22	0.03	32	1250	15	0.04	<2	3	41
L646689		10	<1	0.21	10	0.53	604	31	0.03	45	2790	39	0.09	<2	3	51
L646690		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	20	<2	<0.01	<2	<1	1
L646691		<10	1	0.06	10	0.40	374	2	0.03	18	1100	25	0.03	<2	1	90
L646692		<10	<1	0.08	10	0.35	298	1	0.03	16	1020	11	<0.01	<2	2	87
L646693		10	1	0.10	10	0.46	431	1	0.03	16	980	15	<0.01	<2	3	93
L646694		10	<1	0.12	10	0.51	504	2	0.02	20	640	25	0.03	<2	1	25
L646695		10	<1	0.18	10	0.49	539	10	0.02	14	430	33	0.01	<2	3	20
L646696		10	1	0.10	10	0.42	528	2	0.03	16	680	68	0.02	<2	2	25
L646697		10	1	0.07	10	0.28	408	2	0.02	12	410	24	0.02	<2	1	14
L646698		10	<1	0.15	10	0.37	389	5	0.01	14	310	16	<0.01	<2	2	14
L646699		10	<1	0.23	10	0.36	539	3	0.01	10	410	12	0.01	<2	3	14
L646700		10	<1	0.30	20	0.42	680	4	0.02	10	410	14	0.01	<2	4	13
L646751		10	1	0.15	20	0.66	746	8	0.02	25	800	36	0.06	<2	3	25
L646752		<10	1	0.07	10	0.30	325	4	0.03	11	590	12	0.02	<2	1	18
L646753		<10	<1	0.03	<10	0.10	157	1	0.03	4	570	2	<0.01	<2	1	12
L646754		10	1	0.12	10	0.49	332	2	0.02	18	520	11	<0.01	<2	2	17
L646755		<10	1	0.06	10	0.22	327	2	0.03	10	510	5	0.02	<2	1	14
L646756		10	1	0.07	10	0.41	290	3	0.02	16	520	13	0.01	<2	2	19
L646757		10	<1	0.10	10	0.48	484	6	0.02	20	560	16	0.02	<2	2	21
L646758		10	1	0.09	10	0.41	279	3	0.01	19	480	12	0.04	<2	2	16
L646759		10	1	0.08	10	0.41	327	2	0.01	18	480	9	0.03	<2	2	13
L646760		10	<1	0.07	10	0.48	386	2	0.01	21	530	11	0.03	<2	2	15

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
L646671		<20	0.08	<10	<10	62	<10	86
L646672		<20	0.13	<10	<10	67	<10	82
L646673		<20	0.09	<10	<10	69	<10	68
L646674		<20	0.07	<10	<10	30	<10	98
L646675		<20	0.08	<10	<10	33	<10	87
L646676		<20	0.07	<10	<10	56	<10	77
L646677		<20	0.10	<10	<10	67	<10	103
L646678		<20	0.10	<10	<10	59	<10	86
L646679		<20	0.08	<10	<10	52	<10	59
L646680		<20	0.07	<10	<10	52	<10	51
L646681		<20	0.07	<10	<10	100	<10	103
L646682		<20	0.07	<10	<10	104	<10	66
L646683		<20	0.14	<10	<10	105	<10	148
L646684		<20	0.05	<10	<10	132	<10	85
L646685		<20	0.04	<10	<10	141	<10	65
L646686		<20	0.11	<10	<10	109	<10	154
L646687		<20	0.05	<10	<10	60	<10	97
L646688		<20	0.08	<10	<10	65	<10	200
L646689		<20	0.08	<10	<10	102	10	183
L646690		<20	<0.01	<10	<10	<1	<10	2
L646691		<20	0.05	<10	<10	63	<10	80
L646692		<20	0.06	<10	<10	69	<10	136
L646693		<20	0.08	<10	<10	54	<10	98
L646694		<20	0.06	<10	<10	46	10	163
L646695		<20	0.11	<10	<10	33	<10	306
L646696		<20	0.08	<10	<10	51	<10	253
L646697		<20	0.06	<10	<10	38	<10	125
L646698		<20	0.10	<10	<10	39	<10	172
L646699		<20	0.16	<10	<10	28	<10	174
L646700		<20	0.21	<10	<10	29	<10	222
L646751		<20	0.09	<10	10	54	<10	313
L646752		<20	0.08	<10	<10	46	<10	62
L646753		<20	0.06	<10	<10	40	<10	24
L646754		<20	0.14	<10	<10	61	<10	78
L646755		<20	0.07	<10	<10	40	<10	37
L646756		<20	0.12	<10	<10	65	<10	60
L646757		<20	0.12	<10	<10	68	<10	120
L646758		<20	0.14	<10	<10	77	<10	83
L646759		<20	0.11	<10	<10	59	<10	73
L646760		<20	0.11	<10	<10	65	<10	81

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
L646761		0.22	<0.005	0.5	2.16	8	<10	250	0.9	2	0.38	<0.5	12	34	46	3.16
L646762		0.27	<0.005	<0.2	0.76	3	<10	60	<0.5	<2	0.16	<0.5	4	12	25	1.43
L646763		0.33	<0.005	<0.2	1.75	7	<10	150	1.0	2	0.33	<0.5	11	35	42	3.01
L646764		0.32	0.005	<0.2	0.73	9	<10	60	<0.5	<2	0.13	<0.5	5	14	19	2.06
L646765		0.33	0.007	<0.2	0.57	3	<10	30	<0.5	<2	0.15	<0.5	4	9	11	1.14
L646766		0.33	<0.005	<0.2	0.38	<2	<10	20	<0.5	<2	0.15	<0.5	2	3	13	0.76
L646767		0.37	<0.005	<0.2	0.81	4	<10	60	1.1	<2	0.20	<0.5	5	11	16	1.33
L646768		0.29	<0.005	<0.2	1.47	7	<10	80	2.3	3	0.25	0.5	7	21	29	1.95
L646769		0.40	0.009	<0.2	1.56	3	<10	90	2.2	2	0.40	0.5	12	44	26	3.17
L646770		0.45	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
L646771		0.35	0.011	<0.2	1.63	6	<10	80	3.4	<2	0.23	<0.5	7	17	22	3.80
L646772		0.31	0.007	<0.2	2.16	7	<10	100	0.6	<2	0.33	0.6	15	47	48	3.15
L646773		0.43	0.008	<0.2	2.07	6	<10	150	0.7	3	0.42	0.9	14	54	48	3.48
L646774		0.24	0.006	<0.2	0.42	2	<10	30	<0.5	<2	0.18	<0.5	4	7	17	1.39
L646775		0.27	0.023	0.6	1.41	50	<10	90	1.0	10	0.48	1.4	14	30	162	3.37
L646776		0.23	<0.005	<0.2	0.57	<2	<10	30	<0.5	<2	0.14	<0.5	3	5	14	0.95
L646777		0.28	<0.005	0.2	1.10	4	<10	70	<0.5	<2	0.21	<0.5	6	15	22	1.65
L646778		0.23	0.009	0.2	0.61	3	<10	30	<0.5	2	0.12	<0.5	4	12	13	1.55
L646779		0.31	0.008	<0.2	1.65	7	<10	110	0.9	4	0.42	<0.5	10	38	30	2.76
L646780		0.32	0.013	<0.2	1.54	4	<10	100	0.9	2	0.40	<0.5	10	35	29	2.57
L646781		0.31	0.005	<0.2	1.38	6	<10	100	1.1	2	0.30	<0.5	7	20	27	2.19
L646782		0.20	0.005	<0.2	0.62	3	<10	20	<0.5	<2	0.19	<0.5	5	10	16	1.42
L646783		0.21	0.008	<0.2	0.93	7	<10	40	<0.5	<2	0.15	<0.5	6	17	27	2.26
L646784		0.25	0.011	0.2	0.97	3	<10	70	0.5	2	0.24	0.6	6	13	42	1.69
L646785		0.27	0.012	<0.2	1.39	4	<10	80	0.9	<2	0.27	<0.5	9	19	34	2.28
L646786		0.30	0.010	<0.2	1.22	9	<10	100	<0.5	2	0.18	0.5	10	28	26	2.77
L646787		0.31	0.015	0.7	1.94	11	<10	110	0.6	<2	0.19	<0.5	11	33	47	3.26
L646788		0.24	0.008	0.3	0.50	4	<10	30	<0.5	<2	0.11	<0.5	3	9	13	1.49
L646789		0.29	0.007	<0.2	3.12	8	<10	170	0.8	2	0.52	0.7	23	43	70	4.69
L646790		0.35	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
L646791		0.28	0.011	<0.2	1.43	14	<10	80	<0.5	<2	0.10	<0.5	7	34	55	3.05
L646792		0.35	0.010	0.3	1.61	9	<10	140	0.6	<2	0.37	0.5	12	41	69	2.83
L646793		0.31	0.011	<0.2	1.68	13	<10	120	0.5	<2	0.18	<0.5	10	38	50	2.89
L646794		0.28	0.006	<0.2	2.34	22	<10	100	0.5	<2	0.18	<0.5	13	39	50	2.83
L646795		0.33	0.006	<0.2	1.78	8	<10	140	0.6	<2	0.20	<0.5	12	42	48	2.69
L646796		0.22	0.007	0.2	0.77	13	<10	50	<0.5	<2	0.14	<0.5	9	16	26	2.17
L646797		0.22	0.006	<0.2	0.59	3	<10	30	<0.5	<2	0.15	<0.5	4	7	18	1.37
L646798		0.20	0.010	<0.2	0.38	2	<10	30	<0.5	<2	0.12	<0.5	5	12	14	1.50
L646799		0.23	0.008	<0.2	0.93	7	<10	60	<0.5	<2	0.24	<0.5	10	18	58	1.98
L646800		0.22	0.010	0.2	1.10	11	<10	70	<0.5	<2	0.24	<0.5	11	21	66	1.98

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
L646761		10	1	0.10	20	0.60	587	6	0.01	23	930	20	0.08	<2	3	36
L646762		<10	<1	0.04	10	0.22	151	1	0.01	9	510	4	0.03	<2	1	14
L646763		10	<1	0.10	10	0.59	470	4	0.01	29	700	12	0.03	<2	3	23
L646764		10	<1	0.07	10	0.16	137	5	<0.01	14	340	8	0.04	<2	1	14
L646765		<10	<1	0.03	10	0.15	176	1	0.01	7	460	3	0.03	<2	1	12
L646766		<10	<1	0.03	<10	0.07	59	<1	0.02	1	570	<2	0.02	<2	<1	9
L646767		<10	<1	0.06	10	0.22	278	3	0.02	10	490	8	0.03	<2	1	17
L646768		10	<1	0.08	20	0.45	280	3	0.03	18	650	14	0.06	<2	2	21
L646769		10	<1	0.10	30	0.91	586	9	0.04	37	900	14	0.03	<2	3	35
L646770		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	<1
L646771		10	<1	0.28	50	0.37	655	4	0.01	16	510	21	0.05	<2	4	18
L646772		10	<1	0.11	10	0.85	544	4	0.02	39	540	14	0.03	<2	4	21
L646773		10	1	0.11	10	0.94	545	5	0.02	40	1100	16	0.02	<2	4	27
L646774		<10	<1	0.03	<10	0.12	121	1	0.01	5	660	4	0.02	<2	<1	11
L646775		10	1	0.12	30	0.76	777	17	0.02	32	1170	46	0.03	<2	4	31
L646776		<10	<1	0.03	<10	0.11	113	<1	0.02	3	530	2	0.03	<2	<1	10
L646777		<10	<1	0.05	10	0.31	304	6	0.02	13	580	17	0.04	<2	1	17
L646778		<10	<1	0.04	<10	0.26	100	4	0.02	11	340	5	0.03	<2	1	14
L646779		<10	<1	0.11	10	0.67	496	4	0.02	29	1020	20	0.03	<2	3	25
L646780		10	1	0.10	10	0.63	448	5	0.02	28	980	19	0.03	<2	3	23
L646781		10	<1	0.09	30	0.42	597	2	0.01	18	710	17	0.02	<2	3	22
L646782		<10	<1	0.03	<10	0.17	178	1	0.02	7	650	4	0.05	<2	1	14
L646783		<10	<1	0.04	10	0.25	199	3	0.01	12	550	10	0.08	<2	1	15
L646784		<10	<1	0.08	10	0.31	332	8	0.02	10	590	32	0.04	<2	1	20
L646785		10	<1	0.10	20	0.49	409	10	0.02	15	770	23	0.06	<2	2	27
L646786		10	1	0.06	10	0.40	729	2	0.01	21	610	9	0.06	<2	1	19
L646787		10	<1	0.12	10	0.57	396	2	0.01	29	720	15	0.11	<2	3	25
L646788		<10	<1	0.03	<10	0.13	99	1	0.01	5	460	4	0.04	<2	<1	11
L646789		10	1	0.12	10	1.31	934	1	0.03	56	1830	13	0.06	<2	4	41
L646790		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	<1
L646791		10	<1	0.06	10	0.32	287	3	0.01	20	560	12	0.06	<2	1	14
L646792		10	1	0.11	10	0.58	377	2	0.01	41	1340	13	0.05	<2	3	23
L646793		10	<1	0.08	10	0.52	277	3	0.01	35	730	13	0.06	<2	2	18
L646794		10	1	0.08	10	0.66	424	1	0.01	33	470	14	0.05	<2	4	17
L646795		10	1	0.09	10	0.58	347	2	0.01	37	720	7	0.04	<2	3	21
L646796		<10	1	0.04	<10	0.28	309	1	0.01	12	510	5	0.05	<2	1	15
L646797		<10	1	0.03	<10	0.12	101	<1	0.02	6	530	2	0.04	<2	<1	12
L646798		<10	<1	0.04	<10	0.12	108	1	0.02	6	390	<2	0.06	<2	<1	10
L646799		<10	1	0.06	10	0.31	341	5	0.02	21	870	6	0.06	<2	2	19
L646800		<10	<1	0.07	10	0.36	379	5	0.02	24	830	7	0.07	<2	2	20

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
L646761		<20	0.11	<10	<10	71	<10	93
L646762		<20	0.05	<10	<10	34	<10	39
L646763		<20	0.12	<10	<10	70	<10	114
L646764		<20	0.07	<10	<10	57	<10	62
L646765		<20	0.05	<10	<10	28	<10	37
L646766		<20	0.04	<10	<10	24	<10	16
L646767		<20	0.05	<10	<10	25	<10	61
L646768		<20	0.06	<10	<10	34	<10	102
L646769		<20	0.11	<10	<10	57	<10	157
L646770		<20	<0.01	<10	<10	<1	<10	<2
L646771		50	0.13	<10	10	30	<10	232
L646772		<20	0.16	<10	<10	74	<10	168
L646773		<20	0.15	<10	<10	80	<10	171
L646774		<20	0.06	<10	<10	43	<10	38
L646775		<20	0.11	<10	10	67	10	313
L646776		<20	0.04	<10	<10	27	<10	24
L646777		<20	0.06	<10	<10	38	<10	83
L646778		<20	0.06	<10	<10	42	<10	52
L646779		<20	0.11	<10	<10	65	<10	144
L646780		<20	0.11	<10	<10	58	<10	152
L646781		<20	0.06	<10	<10	41	<10	109
L646782		<20	0.05	<10	<10	38	<10	37
L646783		<20	0.06	<10	<10	54	<10	63
L646784		<20	0.06	<10	<10	34	<10	156
L646785		<20	0.08	<10	10	42	<10	109
L646786		<20	0.08	<10	<10	73	<10	69
L646787		<20	0.11	<10	<10	74	<10	101
L646788		<20	0.06	<10	<10	47	<10	32
L646789		<20	0.11	<10	<10	64	<10	211
L646790		<20	<0.01	<10	<10	<1	<10	<2
L646791		<20	0.07	<10	<10	90	<10	65
L646792		<20	0.10	<10	<10	96	<10	125
L646793		<20	0.10	<10	<10	99	<10	97
L646794		<20	0.12	<10	<10	77	<10	83
L646795		<20	0.11	<10	<10	94	<10	111
L646796		<20	0.08	<10	<10	62	<10	68
L646797		<20	0.06	<10	<10	43	<10	30
L646798		<20	0.06	<10	<10	52	<10	31
L646799		<20	0.07	<10	<10	51	<10	63
L646800		<20	0.06	<10	<10	46	<10	68

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 1-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144734

CERTIFICATE COMMENTS

LABORATORY ADDRESSES

Processed at ALS Whitehorse located at 78 Mt. Sima Rd, Whitehorse, YT, Canada.

Applies to Method:			
LOG-22	LOG-24	SCR-41	WEI-21

Processed at ALS Vancouver located at 2103 Dollarton Hwy, North Vancouver, BC, Canada.

Applies to Method:	
Au-AA23	ME-ICP41

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

CERTIFICATE WH13144735

Project: SUM13-02

P.O. No.: SUM13-02_2

This report is for 159 Soil samples submitted to our lab in Whitehorse, YT, Canada on 13-AUG-2013.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	MURRAY JONES	MASAAKI KOYAMA

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
SCR-41	Screen to -180um and save both
LOG-24	Pulp Login - Rcd w/o Barcode

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: MURRAY JONES
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

***** See Appendix Page for comments regarding this certificate *****

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
L647901		0.27	<0.005	0.2	2.21	8	<10	150	1.1	<2	0.67	0.7	27	50	110	3.45
L647902		0.18	<0.005	0.2	2.07	7	<10	130	1.0	<2	0.47	0.6	21	60	78	3.00
L647903		0.25	<0.005	0.2	2.27	11	<10	110	1.6	<2	0.32	0.6	17	52	43	3.60
L647904		0.26	<0.005	0.2	3.64	4	<10	120	2.7	<2	0.86	<0.5	28	93	79	4.90
L647905		0.20	<0.005	0.4	1.90	5	<10	180	0.6	<2	0.52	<0.5	18	66	51	3.59
L647906		0.18	<0.005	0.3	1.40	7	<10	140	0.5	2	0.47	0.6	12	35	46	3.26
L647907		0.23	0.012	0.4	1.87	13	<10	280	1.5	<2	0.28	0.7	17	41	152	3.83
L647908		0.22	0.005	0.6	2.13	12	<10	5970	1.5	<2	0.38	1.5	24	46	176	4.49
L647909		0.17	<0.005	0.5	2.01	12	<10	1810	1.5	<2	0.42	1.2	19	41	90	3.62
L647910		0.14	<0.005	<0.2	0.01	<2	<10	10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
L647911		0.39	<0.005	0.2	1.98	21	<10	1290	1.4	<2	0.40	0.8	16	41	92	3.69
L647912		0.27	<0.005	<0.2	1.73	11	<10	130	1.1	<2	0.36	0.5	14	34	43	3.80
L647913		0.24	<0.005	<0.2	2.18	6	<10	350	1.0	<2	0.34	<0.5	17	87	37	2.95
L647914		0.35	<0.005	<0.2	1.57	9	<10	100	1.0	<2	0.27	<0.5	8	22	27	2.70
L647915		0.24	<0.005	0.2	2.01	7	<10	150	1.4	<2	0.35	<0.5	11	29	46	3.05
L647916		0.24	<0.005	<0.2	1.58	9	<10	90	0.8	<2	0.22	<0.5	10	28	27	3.08
L647917		0.31	<0.005	<0.2	1.41	8	<10	120	<0.5	<2	0.20	<0.5	7	26	31	3.00
L647918		0.30	<0.005	<0.2	1.77	9	<10	110	0.7	<2	0.22	<0.5	9	30	24	3.16
L647919		0.43	<0.005	<0.2	1.40	6	<10	100	0.7	<2	0.26	<0.5	7	23	18	2.42
L647920		0.38	0.005	<0.2	1.50	5	<10	90	0.8	<2	0.26	<0.5	8	26	20	2.53
L647921		0.34	<0.005	<0.2	1.08	8	<10	80	<0.5	<2	0.15	<0.5	5	18	19	2.24
L647922		0.40	<0.005	<0.2	1.67	6	<10	120	0.7	<2	0.25	<0.5	9	28	24	2.80
L647923		0.26	0.006	<0.2	1.14	10	<10	70	<0.5	<2	0.10	<0.5	7	22	19	3.38
L647924		0.31	0.007	<0.2	1.77	12	<10	80	0.6	<2	0.17	<0.5	9	29	26	3.14
L647925		0.35	<0.005	0.2	1.38	6	<10	80	0.7	<2	0.18	<0.5	9	21	25	2.29
L647926		0.37	<0.005	<0.2	2.20	8	<10	70	0.6	<2	0.14	<0.5	9	31	28	3.11
L647927		0.31	0.005	<0.2	1.99	7	<10	80	0.7	<2	0.16	<0.5	8	34	39	3.48
L647928		0.25	<0.005	<0.2	1.85	5	<10	90	0.5	<2	0.21	<0.5	11	26	38	2.67
L647929		0.30	<0.005	<0.2	1.88	4	<10	100	0.6	<2	0.28	<0.5	10	27	49	3.03
L647930		0.11	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	1	0.02
L647931		0.23	0.005	<0.2	1.57	5	<10	90	0.5	<2	0.25	<0.5	9	25	31	2.67
L647932		0.31	<0.005	<0.2	1.61	10	<10	70	0.5	<2	0.15	<0.5	8	30	23	3.50
L647933		0.34	0.006	<0.2	1.70	8	<10	100	0.5	<2	0.20	<0.5	10	30	31	2.83
L647934		0.30	<0.005	<0.2	1.36	7	<10	90	0.6	<2	0.20	<0.5	8	24	25	2.46
L647935		0.29	<0.005	<0.2	1.23	6	<10	90	0.6	<2	0.27	<0.5	8	20	23	2.22
L647936		0.26	<0.005	<0.2	1.29	8	<10	110	1.0	<2	0.29	0.5	8	20	27	2.47
L647937		0.25	<0.005	<0.2	0.68	<2	<10	40	<0.5	<2	0.16	<0.5	3	7	15	1.18
L647938		0.17	<0.005	<0.2	0.62	3	<10	30	<0.5	<2	0.15	<0.5	4	8	13	1.05
L647939		0.19	<0.005	<0.2	1.36	11	<10	80	<0.5	<2	0.14	<0.5	8	22	29	2.53
L647940		0.27	0.006	<0.2	1.42	12	<10	80	<0.5	<2	0.12	<0.5	7	25	25	3.20

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
L647901		10	<1	0.26	20	1.07	603	1	0.04	55	1530	20	0.10	<2	4	55
L647902		10	<1	0.17	20	0.96	291	2	0.03	54	850	25	0.11	2	3	42
L647903		10	<1	0.09	20	0.88	845	3	0.02	36	740	34	0.06	<2	3	60
L647904		20	<1	0.34	20	1.95	902	4	0.02	79	690	38	0.02	<2	8	182
L647905		10	<1	0.62	10	1.36	394	2	0.03	37	880	22	0.13	<2	3	54
L647906		10	<1	0.29	10	0.65	564	3	0.02	24	740	12	0.07	<2	2	103
L647907		10	1	0.09	30	0.78	749	9	0.02	81	730	24	0.06	<2	4	47
L647908		10	<1	0.17	30	0.80	1130	8	0.01	64	1120	46	0.11	<2	4	61
L647909		10	1	0.12	30	0.73	832	6	0.02	46	1180	32	0.14	<2	3	66
L647910		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	1
L647911		10	<1	0.13	50	0.79	985	4	0.02	43	610	29	0.06	<2	4	48
L647912		10	<1	0.11	20	0.53	1135	4	0.01	30	750	29	0.06	<2	1	39
L647913		10	<1	0.19	20	1.19	510	1	0.03	67	490	18	0.05	<2	3	51
L647914		10	<1	0.09	10	0.42	397	2	0.02	17	760	13	0.05	<2	2	20
L647915		10	<1	0.09	20	0.57	575	1	0.03	21	800	15	0.06	<2	3	31
L647916		10	<1	0.06	10	0.48	462	1	0.01	23	540	13	0.05	<2	2	19
L647917		10	<1	0.05	10	0.42	291	1	0.01	17	430	11	0.03	<2	2	16
L647918		10	<1	0.07	10	0.52	382	1	0.02	23	490	12	0.02	2	3	19
L647919		10	<1	0.08	10	0.40	359	1	0.01	15	640	13	0.02	<2	3	17
L647920		10	<1	0.08	10	0.43	374	1	0.01	17	640	14	0.02	<2	3	17
L647921		10	<1	0.04	10	0.25	163	1	0.02	12	480	10	0.03	<2	1	14
L647922		10	1	0.07	20	0.54	417	1	0.02	21	770	11	0.02	<2	4	18
L647923		10	1	0.06	10	0.22	1055	2	0.01	12	250	12	0.02	<2	2	13
L647924		10	1	0.05	10	0.40	366	2	0.01	24	280	12	0.02	<2	2	17
L647925		<10	<1	0.06	10	0.34	462	2	0.02	15	690	22	0.04	<2	2	14
L647926		10	1	0.05	10	0.49	345	1	0.01	21	580	13	0.06	<2	2	13
L647927		10	<1	0.06	10	0.55	331	1	0.01	20	510	17	0.05	<2	2	15
L647928		10	1	0.07	10	0.51	374	<1	0.02	21	570	13	0.05	<2	2	17
L647929		10	<1	0.10	20	0.55	445	1	0.02	22	620	14	0.03	2	3	18
L647930		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	1
L647931		10	<1	0.10	10	0.50	391	<1	0.02	20	650	10	0.03	<2	3	16
L647932		10	1	0.05	10	0.44	275	1	0.01	18	420	12	0.03	<2	2	13
L647933		10	<1	0.05	10	0.50	353	1	0.01	26	430	12	0.03	<2	2	16
L647934		<10	1	0.06	10	0.41	365	1	0.01	18	670	11	0.05	<2	2	17
L647935		10	<1	0.07	20	0.35	440	1	0.02	14	780	14	0.04	<2	2	22
L647936		<10	<1	0.08	30	0.39	615	1	0.02	17	780	24	0.03	<2	3	23
L647937		<10	1	0.03	<10	0.12	88	<1	0.02	5	520	3	0.05	<2	<1	13
L647938		<10	1	0.04	<10	0.11	100	<1	0.03	6	520	7	0.06	<2	<1	13
L647939		10	1	0.03	10	0.29	308	2	0.02	18	460	10	0.06	2	1	17
L647940		10	1	0.03	10	0.32	228	3	0.01	20	380	16	0.04	3	1	14

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
L647901		<20	0.15	<10	<10	74	<10	148
L647902		<20	0.14	<10	<10	63	<10	132
L647903		<20	0.09	<10	<10	69	<10	151
L647904		<20	0.21	<10	<10	81	<10	136
L647905		<20	0.20	<10	<10	83	<10	88
L647906		<20	0.11	<10	<10	72	<10	127
L647907		<20	0.09	<10	<10	80	<10	213
L647908		<20	0.08	<10	<10	88	<10	252
L647909		<20	0.06	<10	<10	79	<10	234
L647910		<20	<0.01	<10	<10	<1	<10	2
L647911		<20	0.07	<10	<10	88	<10	231
L647912		<20	0.05	<10	<10	67	<10	158
L647913		<20	0.16	<10	<10	51	<10	104
L647914		<20	0.09	<10	<10	57	10	83
L647915		<20	0.10	<10	<10	65	<10	86
L647916		<20	0.09	<10	<10	63	<10	85
L647917		<20	0.10	<10	<10	69	<10	72
L647918		<20	0.11	<10	<10	66	<10	75
L647919		<20	0.10	<10	<10	52	<10	89
L647920		<20	0.11	<10	<10	55	<10	86
L647921		<20	0.06	<10	<10	53	<10	51
L647922		<20	0.10	<10	<10	59	<10	78
L647923		<20	0.13	<10	<10	88	<10	73
L647924		<20	0.11	<10	<10	80	<10	85
L647925		<20	0.06	<10	<10	50	<10	65
L647926		<20	0.09	<10	<10	63	<10	59
L647927		<20	0.10	<10	<10	66	<10	153
L647928		<20	0.10	<10	<10	58	10	74
L647929		<20	0.13	<10	<10	64	10	94
L647930		<20	<0.01	<10	<10	<1	<10	<2
L647931		<20	0.11	<10	<10	56	<10	79
L647932		<20	0.11	<10	<10	73	<10	70
L647933		<20	0.09	<10	<10	64	<10	66
L647934		<20	0.07	<10	<10	48	<10	72
L647935		<20	0.06	<10	<10	48	<10	67
L647936		<20	0.05	<10	<10	42	<10	105
L647937		<20	0.05	<10	<10	32	<10	27
L647938		<20	0.04	<10	<10	26	<10	27
L647939		<20	0.05	<10	<10	55	<10	64
L647940		<20	0.06	<10	<10	70	<10	85

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
L647941		0.26	<0.005	<0.2	1.59	12	<10	130	1.2	<2	0.31	0.5	11	31	41	3.13
L647942		0.31	<0.005	<0.2	1.68	11	<10	100	1.7	<2	0.20	0.5	12	27	51	2.86
L647943		0.35	<0.005	<0.2	1.39	7	<10	160	2.9	<2	0.31	0.9	9	23	24	2.94
L647944		0.30	<0.005	<0.2	1.01	6	<10	60	1.9	<2	0.24	<0.5	7	17	25	1.89
L647945		0.33	<0.005	<0.2	0.85	2	<10	40	0.8	<2	0.21	<0.5	5	10	23	1.39
L647946		0.31	0.005	<0.2	1.74	9	<10	110	1.3	<2	0.25	<0.5	12	31	30	3.04
L647947		0.30	0.005	<0.2	2.25	16	<10	160	1.1	<2	0.21	<0.5	20	43	40	4.32
L647948		0.25	<0.005	<0.2	1.78	17	<10	170	0.6	<2	0.26	<0.5	16	39	34	4.22
L647949		0.31	0.008	<0.2	1.36	6	<10	70	0.7	<2	0.16	<0.5	8	29	21	2.95
L647950		0.10	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
M717801		0.24	0.005	0.3	2.30	14	<10	120	2.5	<2	0.28	0.6	14	36	48	3.44
M717802		0.18	<0.005	0.2	2.08	7	<10	200	1.1	<2	1.87	1.0	17	62	38	3.55
M717803		0.24	<0.005	0.4	2.38	12	<10	250	1.0	<2	1.97	1.3	20	81	44	3.96
M717804		0.14	0.008	<0.2	0.70	3	<10	140	<0.5	<2	3.63	2.9	4	7	38	0.68
M717805		0.20	<0.005	<0.2	1.85	7	<10	150	0.5	<2	1.46	<0.5	13	42	41	2.39
M717806		0.24	<0.005	0.2	2.20	9	<10	170	<0.5	<2	0.26	<0.5	20	144	36	3.86
M717807		0.21	<0.005	<0.2	2.27	10	<10	130	0.5	<2	0.20	<0.5	21	55	40	4.01
M717808		0.15	<0.005	0.4	1.75	10	<10	180	0.8	<2	2.26	1.6	12	48	49	2.51
M717809		0.30	0.005	0.3	1.41	122	<10	180	1.4	2	0.71	0.8	14	35	44	3.62
M717810		0.07	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
M717811		0.22	<0.005	<0.2	1.30	5	<10	180	0.9	<2	0.54	1.1	7	20	31	1.90
M717812		0.22	0.012	0.5	2.51	23	<10	350	3.5	3	0.27	2.2	12	39	58	3.43
M717813		0.33	0.010	0.6	3.78	18	<10	880	5.2	3	0.85	3.3	20	83	111	5.54
M717814		0.20	<0.005	0.6	1.04	6	<10	510	0.6	<2	0.70	4.0	7	17	34	1.63
M717815		0.19	0.009	1.9	1.75	10	<10	620	0.9	2	0.64	2.7	13	50	57	2.98
M717816		0.17	0.005	0.3	0.90	6	<10	110	<0.5	<2	0.13	0.6	5	17	28	2.02
M717817		0.20	0.005	2.3	1.79	17	<10	770	0.9	<2	0.30	3.2	10	42	79	3.49
M717818		0.22	0.006	0.5	1.30	16	<10	320	<0.5	<2	0.12	<0.5	10	41	35	3.61
M717819		0.20	0.006	1.2	1.66	15	<10	520	0.6	<2	0.27	3.1	10	53	64	3.43
M717820		0.21	<0.005	1.3	1.67	18	<10	520	0.6	3	0.28	3.2	13	54	65	3.43
M717821		0.30	0.010	2.6	2.18	29	<10	470	1.8	2	0.79	5.1	18	42	162	4.61
M717822		0.23	<0.005	0.3	1.88	12	<10	170	0.7	2	0.16	<0.5	18	41	52	3.62
M717823		0.22	0.007	0.8	1.46	15	<10	140	0.5	3	0.08	<0.5	19	36	54	3.94
M717824		Not Recvd														
M717825		Not Recvd														
M717826		Not Recvd														
M717827		Not Recvd														
M717828		Not Recvd														
M717829		0.22	<0.005	<0.2	2.19	5	<10	90	0.5	3	0.25	<0.5	14	33	25	2.97
M717830		0.09	<0.005	<0.2	0.01	2	<10	<10	<0.5	3	0.01	<0.5	<1	<1	1	0.02

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
L647941		10	<1	0.06	20	0.59	592	1	0.02	32	770	23	0.04	<2	3	25
L647942		10	<1	0.06	20	0.50	710	2	0.02	27	610	19	0.05	<2	2	20
L647943		10	<1	0.08	40	0.50	711	2	0.01	18	630	38	0.02	<2	4	24
L647944		<10	<1	0.07	20	0.34	472	1	0.03	14	620	17	0.02	<2	2	18
L647945		<10	<1	0.04	10	0.21	196	<1	0.03	8	620	6	0.04	<2	1	16
L647946		10	<1	0.05	10	0.58	598	1	0.01	27	550	14	0.05	<2	2	20
L647947		10	<1	0.06	10	0.77	1130	2	0.01	39	640	20	0.06	<2	2	22
L647948		10	1	0.05	10	0.65	1175	3	0.01	31	630	18	0.05	2	2	26
L647949		10	<1	0.05	10	0.44	295	1	0.01	21	300	11	0.02	<2	2	13
L647950		<10	1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	1
M717801		10	1	0.10	30	0.72	796	1	0.02	32	720	28	0.04	<2	3	26
M717802		10	<1	0.26	20	1.36	559	<1	0.04	43	960	22	0.09	<2	5	111
M717803		10	<1	0.52	20	1.70	559	<1	0.04	58	1360	48	0.06	<2	6	92
M717804		<10	1	0.06	10	0.18	288	1	0.02	10	1130	2	0.22	<2	<1	143
M717805		10	1	0.28	20	0.70	489	<1	0.03	30	900	11	0.11	<2	2	109
M717806		10	<1	0.27	10	1.36	942	1	0.01	87	360	20	0.03	<2	3	29
M717807		10	1	0.33	10	0.82	987	2	0.02	33	480	15	0.03	<2	4	26
M717808		10	1	0.20	10	0.87	473	<1	0.03	35	890	25	0.12	<2	3	125
M717809		10	<1	0.17	20	0.52	663	3	0.02	41	890	35	0.03	<2	5	38
M717810		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	1
M717811		<10	<1	0.07	30	0.39	266	<1	0.03	16	770	12	0.07	<2	2	31
M717812		10	<1	0.34	20	0.75	773	1	0.02	31	830	511	0.07	<2	4	23
M717813		10	<1	0.97	60	1.41	847	<1	0.02	54	2200	746	0.01	<2	13	45
M717814		<10	<1	0.05	20	0.25	443	1	0.02	12	1160	13	0.11	<2	1	48
M717815		10	<1	0.07	20	0.73	593	1	0.02	38	1240	49	0.12	<2	3	43
M717816		<10	1	0.03	10	0.16	116	2	0.01	14	880	7	0.12	<2	<1	17
M717817		10	<1	0.08	10	0.53	445	3	0.02	47	1290	45	0.09	2	2	38
M717818		10	<1	0.06	10	0.33	496	3	0.01	28	850	24	0.09	3	1	18
M717819		10	<1	0.09	10	0.45	485	7	0.01	55	2330	47	0.21	<2	1	40
M717820		10	1	0.10	10	0.47	707	7	0.01	55	2210	47	0.21	<2	1	41
M717821		10	<1	0.17	20	0.70	874	6	0.01	139	3430	60	0.05	<2	5	50
M717822		10	<1	0.11	10	0.65	1075	3	0.02	33	1100	20	0.12	<2	2	25
M717823		10	1	0.07	10	0.38	1145	5	0.01	29	960	19	0.11	<2	1	21
M717824																
M717825																
M717826																
M717827																
M717828																
M717829		10	1	0.16	10	0.63	374	1	0.01	30	390	7	0.03	<2	4	25
M717830		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	1	10	<2	0.02	<2	<1	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
L647941		<20	0.08	<10	<10	60	<10	170
L647942		<20	0.06	<10	<10	48	<10	178
L647943		20	0.06	<10	<10	48	<10	199
L647944		<20	0.05	<10	<10	34	<10	91
L647945		<20	0.05	<10	<10	31	<10	42
L647946		<20	0.07	<10	<10	60	<10	107
L647947		<20	0.08	<10	<10	81	<10	166
L647948		<20	0.08	<10	<10	85	<10	162
L647949		<20	0.08	<10	<10	56	<10	98
L647950		<20	<0.01	<10	<10	<1	<10	<2
M717801		<20	0.09	<10	<10	66	<10	172
M717802		<20	0.16	<10	<10	74	<10	111
M717803		<20	0.15	<10	<10	81	<10	124
M717804		<20	0.02	<10	<10	13	<10	67
M717805		<20	0.06	<10	<10	41	<10	59
M717806		<20	0.17	<10	<10	87	<10	85
M717807		<20	0.18	<10	<10	88	<10	94
M717808		<20	0.09	<10	<10	48	<10	116
M717809		<20	0.05	<10	<10	56	<10	186
M717810		<20	<0.01	<10	<10	<1	<10	<2
M717811		<20	0.06	<10	<10	43	<10	105
M717812		<20	0.11	<10	<10	58	<10	508
M717813		<20	0.20	<10	<10	118	<10	1025
M717814		<20	0.04	<10	<10	40	<10	63
M717815		<20	0.07	<10	<10	69	<10	242
M717816		<20	0.03	<10	<10	57	<10	60
M717817		<20	0.06	<10	<10	102	<10	416
M717818		<20	0.08	<10	<10	126	<10	104
M717819		<20	0.04	<10	<10	149	<10	376
M717820		<20	0.05	<10	<10	153	<10	389
M717821		<20	0.13	<10	<10	179	<10	1065
M717822		<20	0.06	<10	<10	84	<10	148
M717823		<20	0.06	<10	<10	87	<10	133
M717824								
M717825								
M717826								
M717827								
M717828								
M717829		<20	0.17	<10	<10	57	<10	56
M717830		<20	<0.01	<10	<10	<1	<10	<2

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
M717831		0.15	0.007	<0.2	1.07	7	<10	60	<0.5	3	0.11	<0.5	5	17	23	1.91
M717832		0.21	<0.005	0.2	1.46	4	<10	70	<0.5	3	0.22	<0.5	8	28	19	2.64
M717833		0.14	<0.005	0.5	1.90	8	<10	120	0.6	3	0.35	1.6	8	27	29	2.31
M717834		0.13	0.011	1.3	0.36	<2	<10	30	<0.5	2	0.10	0.5	3	8	11	1.04
M717835		0.24	0.009	0.5	1.85	48	<10	110	0.6	2	0.25	3.0	19	31	50	3.59
M717836		0.13	<0.005	0.8	0.86	5	<10	80	<0.5	2	0.46	1.4	5	17	84	1.58
M717837		0.21	<0.005	0.2	0.93	15	<10	100	<0.5	2	0.13	0.9	5	19	35	2.16
M717838		0.23	<0.005	0.3	0.78	2	<10	110	<0.5	2	0.13	<0.5	2	8	21	1.06
M717839		0.15	0.005	0.4	1.08	9	<10	90	0.6	3	0.48	1.1	9	14	41	1.57
M717840		0.17	0.006	0.4	1.15	9	<10	120	0.7	2	0.58	1.4	11	16	50	1.79
M717841		0.23	0.026	0.8	1.89	15	<10	130	2.0	4	0.32	2.0	13	34	99	4.05
M717842		0.22	<0.005	0.3	1.16	8	<10	100	<0.5	2	0.12	<0.5	4	18	18	2.33
M717843		0.18	<0.005	2.1	1.24	6	<10	780	0.6	2	0.40	3.1	9	18	46	1.64
M717844		0.17	<0.005	0.5	0.53	4	<10	170	<0.5	2	0.14	2.5	2	10	16	1.17
M717845		0.26	0.006	0.5	1.70	14	<10	130	<0.5	3	0.21	0.5	7	33	35	3.54
M717846		0.27	0.010	0.4	1.81	8	<10	120	0.7	2	0.29	1.9	19	35	93	3.07
M717847		0.25	0.014	0.2	1.80	7	<10	120	0.5	5	0.24	0.9	10	29	33	3.06
M717848		0.15	<0.005	1.0	1.23	4	<10	320	0.8	3	0.32	3.9	7	19	36	1.96
M717849		0.25	<0.005	1.3	1.47	11	<10	400	1.0	6	0.33	0.8	8	29	47	2.80
M717850		0.07	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	1	0.03
E860751		0.24	0.005	0.5	1.79	19	<10	270	0.8	5	0.46	2.4	13	65	67	3.56
E860752		0.28	<0.005	0.3	1.50	12	<10	310	0.7	4	0.29	<0.5	11	32	38	3.07
E860753		0.24	0.006	0.2	1.17	8	<10	130	0.5	3	0.20	0.5	6	28	36	2.15
E860754		0.24	0.007	0.2	0.96	4	<10	160	<0.5	4	0.22	<0.5	6	27	36	2.34
E860755		0.20	0.016	0.4	1.07	7	<10	130	0.5	3	0.31	1.1	7	21	66	2.06
E860756		0.20	0.006	0.3	1.42	9	<10	180	<0.5	4	0.20	0.5	14	28	35	3.13
E860757		0.21	0.015	0.3	1.56	9	<10	190	0.6	6	0.44	<0.5	10	41	50	3.27
E860758		0.23	0.013	<0.2	1.97	8	<10	90	0.6	3	0.17	<0.5	9	42	36	3.14
E860759		0.22	<0.005	0.5	0.94	6	<10	120	<0.5	4	0.16	<0.5	4	18	33	1.85
E860760		0.26	0.006	0.4	1.00	6	<10	150	<0.5	<2	0.17	<0.5	5	18	44	1.84
E860761		0.20	0.006	0.5	1.67	10	<10	210	0.5	2	0.25	0.7	12	33	48	2.89
E860762		0.22	<0.005	0.3	0.62	5	<10	60	<0.5	<2	0.12	0.6	5	14	22	1.97
E860763		0.22	<0.005	0.3	0.77	5	<10	110	<0.5	<2	0.53	0.6	10	14	31	1.49
E860764		0.16	0.008	0.3	1.35	24	<10	190	0.7	<2	0.47	3.1	13	34	53	2.88
E860765		0.20	0.005	0.8	1.04	32	<10	100	<0.5	2	0.23	1.0	5	24	29	2.37
E860766		0.22	<0.005	0.7	0.65	9	<10	40	<0.5	<2	0.07	<0.5	3	11	20	1.44
E860767		0.18	<0.005	0.3	1.53	5	<10	100	0.5	<2	0.38	1.0	9	25	24	2.34
E860768		0.21	<0.005	0.2	0.56	<2	<10	40	<0.5	<2	0.17	<0.5	4	5	8	1.06
E860769		0.21	0.005	0.6	2.08	8	<10	270	1.0	<2	1.68	1.8	13	43	57	2.74
E860770		0.26	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.02

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
M717831		10	1	0.04	10	0.19	116	3	0.01	16	240	10	0.03	<2	1	16
M717832		10	<1	0.25	10	0.55	193	1	0.01	21	420	10	0.03	<2	3	18
M717833		10	1	0.12	20	0.40	270	1	0.02	24	790	16	0.08	<2	2	34
M717834		<10	1	0.04	<10	0.09	49	1	0.02	8	550	4	0.07	<2	<1	14
M717835		10	<1	0.08	10	0.38	725	4	0.01	24	980	12	0.06	<2	2	25
M717836		<10	1	0.07	10	0.23	207	3	0.02	18	1310	4	0.15	<2	<1	38
M717837		10	<1	0.05	10	0.17	203	3	0.01	18	580	9	0.05	<2	1	22
M717838		<10	1	0.02	10	0.07	46	1	0.02	6	530	5	0.04	<2	<1	18
M717839		<10	<1	0.05	30	0.31	505	2	0.03	19	930	17	0.05	<2	1	29
M717840		<10	1	0.06	40	0.38	695	2	0.02	24	1090	19	0.07	<2	1	37
M717841		<10	<1	0.06	80	0.51	725	5	0.01	33	1020	55	0.04	<2	4	21
M717842		10	<1	0.03	10	0.18	138	3	0.01	13	250	16	0.03	<2	2	15
M717843		<10	1	0.05	10	0.26	540	3	0.03	15	1130	6	0.12	<2	1	38
M717844		<10	1	0.04	10	0.11	57	2	0.02	8	670	2	0.08	<2	1	18
M717845		10	<1	0.05	10	0.40	232	2	0.01	20	480	13	0.03	<2	3	24
M717846		10	<1	0.05	10	0.50	463	1	0.01	30	630	12	0.02	<2	3	20
M717847		10	1	0.05	10	0.41	281	1	0.02	24	620	9	0.05	<2	2	19
M717848		<10	1	0.05	20	0.29	343	1	0.03	17	990	26	0.13	<2	1	27
M717849		10	<1	0.08	20	0.43	323	1	0.02	26	1000	30	0.10	<2	2	25
M717850		<10	<1	<0.01	<10	<0.01	<5	<1	0.01	1	10	<2	0.02	<2	<1	1
E860751		10	<1	0.19	20	0.63	608	5	0.02	54	1420	18	0.11	<2	2	44
E860752		10	1	0.08	10	0.44	740	3	0.01	28	1370	19	0.12	<2	1	27
E860753		10	<1	0.10	10	0.33	282	2	0.02	23	1270	8	0.12	<2	<1	18
E860754		10	<1	0.11	10	0.28	238	2	0.02	23	870	10	0.07	<2	1	20
E860755		10	<1	0.09	20	0.34	295	2	0.02	20	1110	10	0.06	<2	1	22
E860756		10	1	0.07	10	0.41	817	3	0.02	24	720	14	0.07	<2	1	23
E860757		10	<1	0.11	10	0.56	705	4	0.02	30	1850	20	0.09	<2	1	27
E860758		10	<1	0.09	10	0.70	268	1	0.01	31	400	10	0.04	<2	4	13
E860759		10	<1	0.04	10	0.16	93	3	0.02	16	790	7	0.07	<2	1	18
E860760		<10	<1	0.04	10	0.16	89	3	0.01	18	890	10	0.08	<2	1	19
E860761		10	<1	0.08	10	0.49	433	3	0.02	31	870	12	0.07	<2	2	27
E860762		<10	<1	0.04	10	0.14	106	2	0.01	11	550	7	0.06	<2	<1	15
E860763		<10	<1	0.06	10	0.26	425	<1	0.03	11	970	6	0.12	<2	<1	36
E860764		10	<1	0.20	10	0.58	286	2	0.02	34	1140	9	0.13	2	2	32
E860765		10	<1	0.09	10	0.31	135	5	0.01	17	960	11	0.10	<2	1	20
E860766		10	<1	0.03	10	0.07	52	3	0.02	8	330	8	0.04	<2	1	13
E860767		10	<1	0.19	20	0.50	217	1	0.02	20	550	10	0.05	<2	2	36
E860768		<10	<1	0.04	<10	0.11	176	<1	0.03	4	390	2	0.01	<2	<1	16
E860769		10	<1	0.18	20	1.34	479	1	0.04	35	1410	24	0.06	<2	5	83
E860770		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	1

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
M717831		<20	0.07	<10	<10	73	<10	40
M717832		<20	0.15	<10	<10	52	<10	67
M717833		<20	0.08	<10	<10	46	<10	114
M717834		<20	0.03	<10	<10	29	<10	27
M717835		<20	0.13	<10	<10	114	<10	124
M717836		<20	0.03	<10	<10	45	<10	89
M717837		<20	0.08	<10	<10	88	<10	58
M717838		<20	0.04	<10	<10	37	<10	24
M717839		<20	0.05	<10	<10	42	<10	146
M717840		<20	0.05	<10	<10	45	<10	163
M717841		20	0.08	<10	<10	71	<10	323
M717842		<20	0.10	<10	<10	94	<10	49
M717843		<20	0.04	<10	<10	44	<10	64
M717844		<20	0.03	<10	<10	28	<10	30
M717845		<20	0.14	<10	<10	103	<10	97
M717846		<20	0.11	<10	<10	71	<10	310
M717847		<20	0.10	<10	<10	73	<10	115
M717848		<20	0.04	<10	<10	46	<10	94
M717849		<20	0.06	<10	<10	65	<10	104
M717850		<20	<0.01	<10	<10	<1	<10	2
E860751		<20	0.08	<10	<10	157	<10	280
E860752		<20	0.04	<10	<10	120	<10	113
E860753		<20	0.04	<10	<10	102	<10	71
E860754		<20	0.07	<10	<10	130	<10	63
E860755		<20	0.08	<10	<10	68	<10	76
E860756		<20	0.07	<10	<10	82	<10	106
E860757		<20	0.08	<10	<10	118	<10	109
E860758		<20	0.13	<10	<10	87	<10	71
E860759		<20	0.05	<10	<10	90	<10	40
E860760		<20	0.04	<10	<10	80	<10	45
E860761		<20	0.09	<10	<10	90	<10	79
E860762		<20	0.06	<10	<10	69	<10	52
E860763		<20	0.04	<10	<10	44	<10	69
E860764		<20	0.09	<10	<10	113	<10	94
E860765		<20	0.09	<10	<10	134	<10	52
E860766		<20	0.09	<10	<10	81	<10	27
E860767		<20	0.10	<10	<10	42	<10	61
E860768		<20	0.05	<10	<10	30	<10	22
E860769		<20	0.10	<10	<10	58	<10	171
E860770		<20	<0.01	<10	<10	<1	<10	2

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
E860771		0.21	<0.005	0.5	1.09	6	<10	60	<0.5	7	0.20	2.8	7	21	36	2.33
E860772		0.25	0.010	<0.2	2.04	14	<10	160	1.1	<2	0.36	0.5	13	31	35	3.14
E860773		0.26	0.005	0.6	2.51	4	<10	330	1.3	<2	1.38	0.8	20	74	60	4.55
E860774		0.29	0.005	0.3	1.25	13	<10	80	<0.5	2	0.17	0.5	7	26	23	2.93
E860775		0.28	0.008	0.4	1.91	11	<10	170	0.9	3	0.39	1.0	11	38	33	3.03
E860776		0.27	0.008	<0.2	1.32	9	<10	140	0.9	3	0.25	0.7	8	26	28	2.75
E860777		0.26	0.005	0.3	1.91	9	<10	120	0.7	<2	0.19	<0.5	10	38	31	2.95
E860778		0.25	<0.005	0.4	1.29	7	<10	130	<0.5	<2	0.23	0.9	9	26	26	2.66
E860779		0.24	<0.005	0.6	1.13	7	<10	120	<0.5	<2	0.15	0.7	7	22	27	2.37
E860780		0.24	<0.005	0.9	0.79	<2	<10	90	<0.5	<2	0.14	0.5	5	14	18	1.66
E860781		0.27	<0.005	0.2	1.56	12	<10	330	<0.5	<2	0.14	<0.5	10	34	39	3.65
E860782		0.25	<0.005	0.4	0.88	7	<10	180	<0.5	<2	0.12	0.6	6	18	28	2.19
E860783		0.22	<0.005	0.4	1.07	3	<10	130	<0.5	<2	0.15	<0.5	6	15	26	2.08
E860784		0.20	<0.005	1.6	0.85	10	<10	220	<0.5	<2	0.26	1.5	5	17	20	1.88
E860785		0.22	0.009	0.8	1.28	12	<10	130	0.5	2	0.25	0.9	12	23	36	2.43
E860786		0.27	0.007	0.3	1.43	16	<10	120	0.5	<2	0.13	1.1	11	35	37	3.62
E860787		0.25	0.005	0.3	1.20	9	<10	120	<0.5	<2	0.14	<0.5	12	24	31	2.95
E860788		0.32	<0.005	0.3	1.59	16	<10	110	<0.5	<2	0.14	<0.5	10	39	27	4.29
E860789		0.26	0.009	0.3	1.81	13	<10	140	0.8	<2	0.20	0.7	9	34	42	3.51
E860790		0.27	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	<1	0.03
E860791		0.20	0.015	1.1	1.79	6	<10	130	0.9	2	0.35	0.6	20	28	117	2.31
E860792		0.17	0.006	0.5	0.60	4	<10	80	<0.5	<2	0.16	1.3	5	13	16	1.33
E860793		0.24	0.006	0.8	1.21	12	<10	100	<0.5	<2	0.13	0.9	6	19	28	2.55
E860794		0.25	0.005	0.4	1.75	6	<10	120	0.5	2	0.37	0.6	7	29	25	2.41
E860795		0.20	<0.005	0.2	0.90	5	<10	40	<0.5	<2	0.15	<0.5	5	13	16	1.80
E860796		0.29	<0.005	<0.2	1.81	6	<10	90	0.5	2	0.24	<0.5	10	32	23	3.06
E860797		0.29	0.007	<0.2	1.91	3	<10	110	0.5	<2	0.20	<0.5	13	32	28	3.23
C332907		0.44	0.006	0.2	0.54	2	<10	50	<0.5	<2	0.20	<0.5	4	10	23	1.45
C332908		0.37	<0.005	<0.2	0.40	2	<10	40	<0.5	2	0.12	<0.5	3	5	12	1.12
C332909		0.38	<0.005	0.2	1.14	6	<10	90	<0.5	<2	0.09	0.8	10	13	25	1.91
C332910		0.40	<0.005	<0.2	0.01	<2	<10	<10	<0.5	<2	0.01	<0.5	<1	<1	1	0.02
C332911		0.45	0.009	0.3	4.36	12	<10	130	1.4	2	0.27	0.6	11	49	62	3.78
C332912		0.38	0.043	<0.2	0.85	9	<10	90	<0.5	<2	0.09	0.5	3	20	15	2.07
C332913		0.49	0.021	0.4	2.26	11	<10	280	0.7	3	0.20	1.2	12	45	61	4.35
C332914		0.46	0.011	0.2	1.89	11	<10	790	0.5	2	0.23	0.7	12	44	42	3.78
C332915		0.44	0.008	0.2	1.59	11	<10	2160	0.5	<2	0.32	1.0	13	37	53	3.18
C332916		0.40	0.005	0.2	1.08	7	<10	1430	<0.5	2	0.18	0.7	8	25	30	2.93
C332917		0.46	0.010	0.3	1.79	10	<10	370	0.7	<2	0.28	0.7	13	34	54	3.19
C332918		0.44	<0.005	0.3	0.69	3	<10	100	<0.5	<2	0.08	<0.5	3	7	12	1.36

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
E860771		10	<1	0.06	10	0.29	257	2	0.02	14	490	16	0.05	<2	1	22
E860772		10	<1	0.06	20	0.55	809	1	0.02	27	1020	15	0.12	<2	1	28
E860773		10	<1	0.27	20	1.65	510	<1	0.04	55	1460	34	0.02	<2	9	121
E860774		10	<1	0.06	10	0.29	195	3	0.01	17	410	30	0.03	<2	2	18
E860775		10	<1	0.12	10	0.61	455	1	0.02	33	980	45	0.03	<2	3	21
E860776		<10	<1	0.16	40	0.36	318	1	0.01	20	1050	21	0.03	<2	3	15
E860777		10	<1	0.16	20	0.53	310	1	0.01	28	690	11	0.03	<2	3	14
E860778		10	<1	0.05	10	0.37	367	2	0.01	22	680	13	0.05	<2	2	19
E860779		10	<1	0.05	10	0.24	330	3	0.02	16	1130	9	0.14	<2	1	18
E860780		<10	<1	0.04	10	0.18	200	1	0.02	11	950	4	0.12	2	<1	16
E860781		10	<1	0.06	10	0.38	557	4	0.01	27	900	15	0.09	2	1	21
E860782		10	<1	0.06	10	0.16	221	4	0.02	15	670	10	0.07	<2	1	18
E860783		10	<1	0.03	10	0.12	259	2	0.02	11	900	7	0.08	<2	<1	17
E860784		<10	<1	0.06	10	0.16	163	2	0.02	14	1060	12	0.10	2	<1	29
E860785		10	<1	0.10	10	0.34	643	2	0.02	22	1070	20	0.08	<2	1	23
E860786		10	<1	0.13	10	0.47	493	3	0.01	28	620	12	0.06	<2	2	21
E860787		10	<1	0.06	10	0.30	847	3	0.01	22	690	11	0.07	2	1	19
E860788		10	<1	0.07	10	0.45	700	5	0.01	25	520	16	0.03	<2	2	18
E860789		10	1	0.06	20	0.41	283	4	0.01	25	580	22	0.04	<2	3	26
E860790		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.02	<2	<1	1
E860791		10	<1	0.07	30	0.33	816	3	0.02	24	1520	20	0.13	<2	1	35
E860792		<10	<1	0.05	<10	0.19	115	<1	0.02	9	740	6	0.08	<2	1	17
E860793		10	<1	0.05	10	0.18	215	3	0.01	14	540	18	0.04	<2	1	20
E860794		10	<1	0.11	10	0.42	250	1	0.02	21	660	14	0.07	<2	2	31
E860795		10	<1	0.06	10	0.19	127	<1	0.02	10	370	5	0.03	<2	1	14
E860796		10	<1	0.21	20	0.56	276	<1	0.02	23	500	8	0.01	<2	3	19
E860797		10	<1	0.30	20	0.67	251	<1	0.01	29	510	10	0.01	<2	3	22
C332907		<10	<1	0.05	10	0.16	139	1	0.03	6	600	4	0.01	<2	1	15
C332908		<10	<1	0.02	<10	0.05	85	<1	0.03	3	420	<2	<0.01	<2	<1	12
C332909		10	1	0.04	10	0.11	1010	1	0.03	9	570	7	0.02	<2	1	13
C332910		<10	<1	<0.01	<10	<0.01	<5	<1	<0.01	<1	10	<2	0.01	<2	<1	1
C332911		10	<1	0.06	10	0.46	305	1	0.02	38	1120	21	0.03	2	5	18
C332912		10	<1	0.09	10	0.31	133	1	0.01	8	260	10	0.01	2	2	11
C332913		10	<1	0.07	10	0.64	371	3	0.02	35	430	17	0.03	3	4	21
C332914		10	<1	0.13	10	0.66	497	2	0.02	29	610	13	0.03	<2	3	23
C332915		10	<1	0.14	10	0.55	703	2	0.02	25	840	13	0.05	2	3	28
C332916		10	<1	0.08	10	0.35	299	2	0.02	17	590	11	0.03	<2	2	20
C332917		10	<1	0.06	10	0.47	453	2	0.02	28	710	19	0.02	2	3	20
C332918		<10	<1	0.02	<10	0.08	106	<1	0.03	4	240	3	0.01	<2	1	11

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Th	Ti	Tl	U	V	W	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm
	LOR	20	0.01	10	10	1	10	2
E860771		<20	0.08	<10	<10	52	<10	188
E860772		<20	0.06	<10	<10	65	<10	130
E860773		<20	0.19	<10	<10	76	<10	252
E860774		<20	0.10	<10	<10	94	<10	71
E860775		<20	0.10	<10	<10	63	<10	160
E860776		<20	0.07	<10	<10	56	<10	103
E860777		<20	0.09	<10	<10	76	<10	108
E860778		<20	0.08	<10	<10	72	<10	135
E860779		<20	0.04	<10	<10	60	<10	83
E860780		<20	0.03	<10	<10	42	<10	49
E860781		<20	0.06	<10	<10	104	<10	105
E860782		<20	0.05	<10	<10	79	<10	88
E860783		<20	0.03	<10	<10	74	<10	50
E860784		<20	0.02	<10	<10	77	<10	101
E860785		<20	0.07	<10	<10	69	<10	146
E860786		<20	0.11	<10	<10	100	<10	179
E860787		<20	0.07	<10	<10	85	<10	91
E860788		<20	0.14	<10	<10	145	<10	100
E860789		<20	0.11	<10	<10	101	<10	114
E860790		<20	<0.01	<10	<10	<1	<10	3
E860791		<20	0.05	<10	<10	66	<10	91
E860792		<20	0.04	<10	<10	46	<10	43
E860793		<20	0.09	<10	<10	80	<10	79
E860794		<20	0.09	<10	<10	54	<10	97
E860795		<20	0.09	<10	<10	48	<10	34
E860796		<20	0.16	<10	<10	63	<10	60
E860797		<20	0.16	<10	<10	54	<10	74
C332907		<20	0.07	<10	<10	46	<10	44
C332908		<20	0.06	<10	<10	39	<10	19
C332909		<20	0.08	<10	<10	77	<10	71
C332910		<20	<0.01	<10	<10	<1	<10	<2
C332911		<20	0.16	<10	<10	91	<10	99
C332912		<20	0.14	<10	<10	90	<10	45
C332913		<20	0.13	<10	<10	105	<10	224
C332914		<20	0.14	<10	<10	109	<10	196
C332915		<20	0.11	<10	<10	100	<10	175
C332916		<20	0.12	<10	<10	98	<10	126
C332917		<20	0.12	<10	<10	88	<10	130
C332918		<20	0.06	<10	<10	41	<10	27

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 2-SEP-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144735

CERTIFICATE COMMENTS

LABORATORY ADDRESSES

Processed at ALS Whitehorse located at 78 Mt. Sima Rd, Whitehorse, YT, Canada.

Applies to Method:	LOG-22	LOG-24	SCR-41	WEI-21

Processed at ALS Vancouver located at 2103 Dollarton Hwy, North Vancouver, BC, Canada.

Applies to Method:	Au-AA23	ME-ICP41

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 31-AUG-2013
Account: EIASUM

CERTIFICATE WH13144736

Project: SUM13-02

P.O. No.: SUM13-02_2

This report is for 57 Rock samples submitted to our lab in Whitehorse, YT, Canada on 13-AUG-2013.

The following have access to data associated with this certificate:

EQUITY ENG E-MAIL	MURRAY JONES	MASAAKI KOYAMA

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-22	Sample login - Rcd w/o BarCode
CRU-QC	Crushing QC Test
PUL-QC	Pulverizing QC Test
CRU-31	Fine crushing - 70% <2mm
SPL-21	Split sample - riffle splitter
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
Au-AA23	Au 30g FA-AA finish	AAS
ME-ICP41	35 Element Aqua Regia ICP-AES	ICP-AES
ME-OG46	Ore Grade Elements - AquaRegia	ICP-AES
Pb-OG46	Ore Grade Pb - Aqua Regia	VARIABLE
Zn-OG46	Ore Grade Zn - Aqua Regia	VARIABLE

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
ATTN: MURRAY JONES
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All pages of this report have been checked and approved for release.

***** See Appendix Page for comments regarding this certificate *****

Signature:

Colin Ramshaw, Vancouver Laboratory Manager

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 31-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144736

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
L647751		0.63	<0.005	0.2	0.31	5	<10	30	<0.5	<2	0.34	<0.5	4	12	49	1.51
L647752		0.64	<0.005	0.2	0.58	3	<10	40	<0.5	<2	0.59	<0.5	9	12	20	1.85
L647753		0.64	<0.005	0.2	0.81	4	<10	390	0.6	<2	0.36	<0.5	<1	59	22	1.76
L647754		0.63	<0.005	0.2	0.77	2	<10	180	<0.5	2	0.27	<0.5	1	7	50	1.58
L647755		0.51	0.035	<0.2	0.90	<2	<10	100	<0.5	5	0.45	<0.5	3	8	23	1.59
L647756		0.67	<0.005	<0.2	0.24	3	<10	20	0.7	2	0.03	4.2	<1	7	12	1.70
L647757		0.71	0.098	1.0	1.50	1745	<10	700	0.9	4	0.16	27.9	3	11	81	1.67
L647758		1.06	0.668	12.2	0.33	19	<10	90	0.8	78	2.40	641	94	4	1260	5.41
L647759		0.74	<0.005	<0.2	0.14	13	<10	30	<0.5	2	0.04	1.4	2	16	30	0.83
L647760		0.65	0.005	0.3	0.74	2	<10	50	<0.5	3	0.23	2.4	3	29	15	1.54
L647761		0.49	0.013	0.2	0.60	3	<10	160	<0.5	7	0.25	0.6	7	39	26	1.29
L646601		0.61	<0.005	0.3	2.92	4	<10	30	0.9	2	2.67	<0.5	14	43	38	3.03
L646602		0.84	<0.005	0.3	1.10	6	<10	320	<0.5	<2	0.45	<0.5	6	40	50	2.01
L646603		0.76	<0.005	0.5	0.63	43	<10	300	<0.5	2	0.35	0.5	5	34	30	1.38
L646604		0.44	<0.005	<0.2	2.72	<2	<10	220	<0.5	<2	1.37	<0.5	25	129	34	3.53
L646605		0.67	<0.005	0.4	1.96	10	<10	30	0.9	<2	1.27	<0.5	10	16	57	2.70
L646606		0.72	<0.005	0.2	0.30	<2	<10	50	<0.5	<2	0.12	<0.5	<1	5	15	1.36
L646607		0.83	<0.005	<0.2	3.44	8	<10	130	1.2	2	0.09	<0.5	21	97	21	4.51
L646608		0.54	<0.005	<0.2	1.78	2	<10	60	0.9	2	0.03	<0.5	12	34	34	2.75
L646609		0.36	<0.005	<0.2	0.49	6	<10	30	<0.5	2	0.06	<0.5	3	12	5	0.62
L646610		0.70	<0.005	0.2	2.84	4	<10	40	1.0	2	2.22	<0.5	17	44	57	2.37
L646611		0.91	<0.005	<0.2	0.24	2	<10	130	<0.5	<2	0.03	<0.5	2	16	18	0.81
L646612		0.83	<0.005	<0.2	0.09	2	<10	10	<0.5	2	0.01	<0.5	<1	12	1	0.36
L646613		0.52	<0.005	<0.2	0.24	<2	<10	20	<0.5	2	0.01	<0.5	<1	12	3	0.62
L646614		0.97	<0.005	0.2	0.31	3	<10	80	<0.5	11	0.08	<0.5	1	10	12	0.74
L646615		0.97	<0.005	1.9	0.33	2	<10	70	<0.5	22	0.13	<0.5	2	11	17	2.41
L646616		0.80	<0.005	<0.2	0.78	4	<10	130	<0.5	<2	0.04	<0.5	6	26	7	1.14
L646617		0.74	<0.005	<0.2	2.18	10	<10	380	0.6	2	0.24	<0.5	6	141	87	3.45
L646618		0.69	<0.005	0.5	0.79	4	<10	40	<0.5	2	0.72	<0.5	11	30	126	1.84
L646619		0.78	<0.005	0.5	1.41	19	<10	240	<0.5	2	0.70	<0.5	6	3	19	5.13
L646620		0.68	<0.005	0.8	1.08	3	<10	100	0.6	2	0.46	0.5	8	41	116	2.03
L646621		0.91	0.023	5.6	1.69	392	<10	160	0.6	10	0.74	11.1	15	111	280	3.25
L646622		0.56	<0.005	0.2	0.88	2	<10	90	<0.5	4	0.53	<0.5	3	8	20	1.08
L646623		0.68	<0.005	<0.2	0.31	3	<10	30	<0.5	<2	0.04	<0.5	1	11	6	0.99
L646624		0.72	0.028	0.4	8.12	16	<10	100	1.7	8	4.68	<0.5	44	286	345	5.48
L646625		0.77	<0.005	1.0	1.26	6	<10	380	0.5	3	1.20	0.9	14	20	211	3.05
L646626		0.65	0.007	0.2	0.22	16	<10	50	<0.5	3	0.04	<0.5	1	14	5	0.96
L646627		0.92	0.005	0.3	2.02	12	<10	390	1.1	2	1.69	2.7	5	41	61	1.09
L646628		0.43	0.008	1.0	0.46	140	<10	120	1.5	<2	0.02	2.5	18	10	194	9.47
L646629		0.58	0.005	0.8	0.80	<2	<10	630	1.2	4	1.57	4.0	10	36	3	3.29

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 31-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
L647751		<10	<1	0.15	10	0.07	89	3	0.06	4	610	6	0.49	<2	1	39
L647752		<10	<1	0.18	10	0.27	291	2	0.08	9	790	5	0.63	<2	3	32
L647753		<10	<1	0.24	10	0.46	112	16	0.02	11	1980	3	0.08	3	4	29
L647754		<10	<1	0.42	10	0.37	98	9	0.11	2	730	<2	0.06	<2	2	45
L647755		10	<1	0.48	20	0.41	162	2	0.09	3	680	5	<0.01	<2	2	28
L647756		<10	<1	0.11	40	<0.01	190	1	0.07	1	20	8	0.01	<2	<1	3
L647757		10	<1	0.66	10	0.52	87	3	0.02	23	760	32	0.12	<2	3	17
L647758		<10	<1	0.04	<10	0.52	826	1	<0.01	18	440	36	1.56	2	<1	16
L647759		<10	<1	0.07	<10	0.01	81	2	<0.01	11	180	2	<0.01	<2	1	5
L647760		<10	<1	0.14	<10	0.36	243	4	0.02	17	610	27	0.01	<2	3	6
L647761		<10	<1	0.35	10	0.39	197	2	0.07	24	320	8	<0.01	<2	4	8
L646601		10	<1	0.28	20	0.39	68	2	0.36	35	430	5	1.80	2	4	130
L646602		<10	<1	0.38	10	0.58	187	2	0.10	18	670	<2	0.38	<2	3	48
L646603		<10	<1	0.22	10	0.30	120	7	0.01	16	1670	3	0.57	<2	2	20
L646604		10	<1	1.09	10	2.15	208	1	0.20	85	2050	<2	0.15	<2	5	66
L646605		10	<1	0.20	10	0.30	318	<1	0.22	10	800	27	1.16	<2	3	94
L646606		<10	<1	0.09	20	0.03	58	18	0.07	2	230	4	0.10	<2	2	7
L646607		10	<1	1.49	20	1.42	309	36	0.06	55	320	3	0.15	<2	16	12
L646608		10	<1	0.55	20	0.89	176	2	0.03	19	210	7	0.59	<2	4	14
L646609		<10	<1	0.19	10	0.23	115	<1	0.02	7	200	3	<0.01	<2	1	3
L646610		10	<1	0.32	20	0.62	68	5	0.27	45	540	6	1.05	<2	3	73
L646611		<10	<1	0.08	<10	0.06	131	1	0.01	10	170	2	<0.01	<2	1	2
L646612		<10	<1	0.04	<10	<0.01	43	<1	0.01	1	10	3	<0.01	<2	<1	1
L646613		<10	<1	0.09	<10	0.02	63	<1	0.04	1	10	5	<0.01	<2	<1	1
L646614		<10	<1	0.15	10	0.08	125	377	0.06	1	170	11	0.04	<2	1	9
L646615		<10	<1	0.17	10	0.09	109	21	0.07	2	190	24	0.05	<2	1	13
L646616		<10	<1	0.45	<10	0.49	395	3	0.02	19	150	<2	<0.01	<2	4	3
L646617		10	<1	1.49	10	1.50	309	78	0.06	37	1110	7	0.17	<2	9	8
L646618		<10	<1	0.11	10	0.21	75	1	0.13	50	640	5	0.34	<2	1	33
L646619		10	<1	0.67	20	0.40	573	3	0.12	4	1910	17	1.15	<2	10	39
L646620		10	<1	0.28	10	0.38	241	2	0.07	25	300	6	0.98	<2	4	47
L646621		10	<1	0.80	10	0.75	385	7	0.06	84	2700	42	1.28	<2	6	35
L646622		10	<1	0.27	20	0.33	158	13	0.08	3	840	9	0.01	<2	2	27
L646623		<10	<1	0.15	<10	0.03	310	2	0.03	2	20	8	<0.01	<2	<1	5
L646624		20	<1	1.11	<10	1.39	735	1	0.14	292	480	25	1.46	<2	5	1055
L646625		10	<1	0.09	20	0.37	571	3	0.13	59	930	18	0.63	<2	1	100
L646626		<10	<1	0.13	<10	0.02	82	<1	0.01	11	120	15	0.01	<2	1	4
L646627		10	<1	0.15	10	0.48	239	<1	0.24	23	1020	7	0.01	<2	4	118
L646628		<10	<1	0.09	10	0.01	557	2	0.01	25	1580	21	0.03	<2	2	15
L646629		<10	<1	0.06	10	0.58	1400	1	0.03	32	2870	6	<0.01	<2	5	58

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 31-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46
	Analyte	Th	Ti	Tl	U	V	W	Zn	Pb	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%
	LOR	20	0.01	10	10	1	10	2	0.001	0.001
L647751		<20	0.07	<10	<10	32	<10	7		
L647752		<20	0.09	<10	<10	46	<10	17		
L647753		<20	0.05	<10	<10	244	<10	42		
L647754		<20	0.16	<10	<10	33	<10	21		
L647755		<20	0.12	<10	<10	31	20	65		
L647756		20	0.01	<10	<10	1	<10	421		
L647757		<20	0.04	<10	<10	27	<10	152		
L647758		<20	0.02	<10	<10	11	10	>10000		4.22
L647759		<20	<0.01	<10	<10	18	<10	126		
L647760		<20	<0.01	<10	<10	43	<10	265		
L647761		<20	0.07	<10	<10	65	<10	113		
L646601		<20	0.16	<10	<10	38	<10	35		
L646602		<20	0.13	<10	<10	44	<10	36		
L646603		<20	0.03	<10	<10	77	<10	37		
L646604		<20	0.32	<10	<10	75	<10	50		
L646605		<20	0.10	<10	<10	61	10	37		
L646606		20	0.06	<10	<10	4	<10	38		
L646607		<20	0.32	<10	<10	106	<10	53		
L646608		<20	0.02	<10	<10	38	<10	44		
L646609		<20	<0.01	<10	<10	9	<10	14		
L646610		<20	0.16	<10	<10	56	<10	41		
L646611		<20	<0.01	<10	<10	13	<10	31		
L646612		<20	<0.01	<10	<10	1	<10	10		
L646613		<20	<0.01	<10	<10	1	<10	25		
L646614		<20	0.02	<10	<10	5	<10	26		
L646615		<20	0.04	<10	<10	9	20	23		
L646616		<20	0.06	<10	<10	32	<10	27		
L646617		<20	0.18	<10	<10	140	<10	93		
L646618		<20	0.18	<10	<10	19	<10	24		
L646619		<20	0.29	<10	<10	6	<10	116		
L646620		<20	0.05	<10	<10	52	<10	70		
L646621		<20	0.09	<10	<10	254	<10	737		
L646622		<20	0.12	<10	<10	32	10	61		
L646623		<20	<0.01	<10	<10	2	<10	116		
L646624		<20	0.30	<10	<10	131	<10	163		
L646625		<20	0.15	<10	<10	46	<10	76		
L646626		<20	<0.01	<10	<10	15	<10	106		
L646627		<20	0.20	<10	<10	50	<10	202		
L646628		<20	<0.01	<10	<10	15	<10	713		
L646629		<20	0.12	<10	<10	110	<10	173		

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 31-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144736

Sample Description	Method	WEI-21	Au-AA23	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Recvd Wt.	Au	Ag	Al	As	B	Ba	Be	Bi	Ca	Cd	Co	Cr	Cu	Fe
	Units	kg	ppm	ppm	%	ppm	ppm	ppm	ppm	ppm	%	ppm	ppm	ppm	ppm	%
	LOR	0.02	0.005	0.2	0.01	2	10	10	0.5	2	0.01	0.5	1	1	1	0.01
L646630		0.42	0.077	1.7	0.38	572	<10	180	0.5	3	0.02	2.1	5	19	73	3.81
L646631		0.35	0.063	1.6	0.45	848	<10	240	0.6	3	0.04	3.1	4	18	91	4.78
L646632		0.57	<0.005	0.3	1.18	8	<10	440	0.5	2	1.07	0.5	4	72	23	2.02
L646633		0.62	0.810	75.3	1.59	150	<10	100	0.6	16	0.03	6.8	4	39	459	10.55
L646634		0.83	0.062	20.0	0.49	172	<10	410	0.7	3	0.02	17.5	7	20	173	6.46
L646635		0.91	0.009	1.4	0.43	15	<10	110	<0.5	<2	0.02	0.5	2	20	52	1.62
L646636		1.10	<0.005	0.7	0.36	9	<10	110	<0.5	2	0.01	<0.5	1	21	33	1.03
L646637		0.62	<0.005	0.5	0.84	9	<10	690	<0.5	2	0.27	<0.5	4	35	55	1.64
L646638		0.56	0.006	0.8	1.03	85	<10	290	0.6	2	0.82	1.3	7	90	154	2.43
L646639		0.75	<0.005	9.0	2.34	25	<10	190	0.5	2	4.77	13.1	26	38	2090	4.25
L646640		1.38	0.006	0.8	1.46	5	<10	390	0.7	5	5.15	19.8	11	28	17	4.58
L646641		1.08	<0.005	0.4	1.07	<2	<10	270	0.5	3	2.70	16.8	7	15	29	2.87
L646642		1.32	0.005	0.8	1.47	10	<10	270	0.5	5	3.18	14.5	10	21	14	3.34
L646643		1.30	0.028	1.3	1.36	10	<10	260	1.0	6	5.99	35.5	16	12	10	6.02
L646644		1.72	0.008	0.4	1.65	14	<10	140	<0.5	4	9.5	19.4	7	17	3	7.10
L646645		1.12	0.007	0.3	1.38	10	<10	230	<0.5	2	5.55	12.2	7	12	12	4.28
L646646		0.91	0.007	0.8	1.04	6	<10	180	0.6	10	4.01	8.1	8	10	4	2.87

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 31-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41
	Analyte	Ga	Hg	K	La	Mg	Mn	Mo	Na	Ni	P	Pb	S	Sb	Sc	Sr
	Units	ppm	ppm	%	ppm	%	ppm	ppm	%	ppm	ppm	ppm	%	ppm	ppm	ppm
	LOR	10	1	0.01	10	0.01	5	1	0.01	1	10	2	0.01	2	1	1
L646630		<10	<1	0.16	10	0.02	56	3	0.02	18	990	3	0.05	<2	1	24
L646631		<10	<1	0.22	20	0.03	68	3	0.02	15	1190	4	0.14	<2	1	45
L646632		10	<1	0.12	20	0.66	536	3	0.02	76	5010	30	<0.01	<2	3	24
L646633		10	<1	0.17	10	0.21	213	15	0.01	27	2430	>10000	0.30	<2	4	5
L646634		<10	<1	0.06	10	0.12	362	3	0.01	26	1090	1920	0.03	5	1	9
L646635		<10	<1	0.07	10	0.14	155	1	0.01	10	270	391	0.01	<2	2	10
L646636		<10	<1	0.08	10	0.10	81	1	0.01	4	190	44	0.01	<2	2	8
L646637		<10	<1	0.14	<10	0.39	143	5	0.04	21	460	12	0.38	<2	3	24
L646638		10	<1	0.40	10	0.34	90	74	0.07	97	3740	8	0.58	<2	6	61
L646639		10	<1	0.03	10	1.04	1320	<1	0.04	78	830	1325	0.30	<2	3	123
L646640		10	<1	0.02	10	0.52	1690	6	0.01	23	430	25	0.04	<2	2	53
L646641		<10	<1	0.01	10	0.36	1115	<1	0.01	9	440	24	0.03	<2	2	69
L646642		10	<1	0.03	10	0.43	1245	1	0.03	19	300	15	0.03	<2	2	64
L646643		10	<1	0.02	<10	0.41	2710	2	0.01	15	760	25	0.13	<2	2	48
L646644		10	<1	0.02	<10	0.45	2160	8	0.01	16	1940	15	0.12	<2	3	39
L646645		10	<1	0.01	<10	0.21	886	<1	0.01	6	580	12	0.02	<2	2	34
L646646		<10	<1	0.02	10	0.27	789	<1	<0.01	7	770	14	<0.01	6	2	25

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 31-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144736

Sample Description	Method	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	ME-ICP41	Pb-OG46	Zn-OG46
	Analyte	Th	Ti	Tl	U	V	W	Zn	Pb	Zn
	Units	ppm	%	ppm	ppm	ppm	ppm	ppm	%	%
	LOR	20	0.01	10	10	1	10	2	0.001	0.001
L646630		<20	<0.01	<10	<10	37	<10	24		
L646631		<20	<0.01	<10	<10	47	<10	25		
L646632		<20	0.01	<10	<10	263	<10	96		
L646633		<20	<0.01	<10	<10	77	<10	3400	1.525	
L646634		<20	<0.01	<10	<10	39	<10	1800		
L646635		<20	<0.01	<10	<10	22	<10	201		
L646636		<20	<0.01	<10	<10	17	<10	82		
L646637		<20	0.04	<10	<10	87	<10	32		
L646638		<20	0.08	<10	10	766	<10	110		
L646639		<20	0.21	<10	<10	43	<10	2100		
L646640		<20	0.12	<10	<10	25	<10	2410		
L646641		<20	0.09	<10	<10	15	<10	1940		
L646642		<20	0.14	<10	<10	20	<10	1630		
L646643		<20	0.06	<10	<10	20	<10	5020		
L646644		<20	0.09	<10	<10	24	100	2300		
L646645		<20	0.11	<10	<10	17	<10	1360		
L646646		<20	0.07	<10	<10	17	<10	989		

***** See Appendix Page for comments regarding this certificate *****

ALS Canada Ltd.
2103 Dollarton Hwy
North Vancouver BC V7H 0A7
Phone: 604 984 0221 Fax: 604 984 0218 www.alsglobal.com

To: **EQUITY EXPLORATION CONSULTANTS LTD.**
SUITE 200, 900 WEST HASTINGS STREET
VANCOUVER BC V6C 1E5

Finalized Date: 31-AUG-2013
Account: EIASUM

Project: SUM13-02

CERTIFICATE OF ANALYSIS WH13144736

CERTIFICATE COMMENTS

LABORATORY ADDRESSES

Processed at ALS Whitehorse located at 78 Mt. Sima Rd, Whitehorse, YT, Canada.

Applies to Method:				
	CRU-31	CRU-QC	LOG-22	PUL-31
	PUL-QC	SPL-21	WEI-21	

Processed at ALS Vancouver located at 2103 Dollarton Hwy, North Vancouver, BC, Canada.

Applies to Method:				
	Au-AA23	ME-ICP41	ME-OG46	Pb-OG46
	Zn-OG46			

Appendix E: Quality Assurance/Quality Control

QUALITY ASSURANCE / QUALITY CONTROL

i. Standards

Due to the early stage nature of the work on the Polly Property, no standards were used in the program.

ii. Blanks


Blanks are samples which are known to be barren of mineralization. Blanks are inserted into the sample stream in the field to determine whether contamination has occurred after sample collection. A total of 31 blanks were inserted into the sample sequence and submitted for analysis. The blank material consists of commercially available, pre-pulverized silica sand.

Visual inspection of the blank results shows no contamination is present in the elements of interest, or for any of the elements analysed. The use of the prepared pulp blank meant that several steps in the analytical process, including the crushing and pulverization of the sample were not tested.

iii. Field Duplicate Analysis

Field duplicates consist of the collection and analysis of two separate samples from the same field location. They are used to measure the reproducibility of sampling, which includes both laboratory variation and sample variation. The most important duplicate is the field duplicate as precision error estimated with these data is a cumulative error, which will include all subsequent sample preparation and analytical error as well as the natural variability of the parent material.

During the 2013 Polly program, field duplicate samples were collected roughly every 20 samples. A total of 30 duplicate pairs were submitted for analysis.



Scatter Plot for Copper in soil results from the Polly Property shows that the results fall well within tolerances for the 20% precision, indicating reasonable reproducibility of results. This is common to all elements of interest.

Scatter plots of the duplicate data allow a visual comparison of the precision at the two stages of sample size reduction. Duplicate sets are presented both as linear plots which emphasize the higher values and log-log plots (below) that provide detail at lower concentrations. The scatter plots show high reproducibility for all elements of interest at 20% precision limits, 30% for gold.

Conclusions

- A total of 31 blanks inserted into the sample stream showed no contamination in the sample preparation process.
- Inspection of a total of 30 field duplicate pairs inserted into the sample stream show consistently and acceptably low variability, within 20% precision limits (30% for gold).
- Results of the soil sampling program on the Polly Property area considered to be valid and robust.

Appendix F: Geologist's Certificate

GEOLOGIST'S CERTIFICATE

I, Murray I. Jones, of 8606 144A St., City of Surrey, in the Province of British Columbia, DO HEREBY CERTIFY:

1. THAT I am a Consulting Geologist with offices at Suite 200, 900 West Hastings Street, Vancouver, British Columbia.

2. THAT I am a graduate of the University of British Columbia with a Bachelor of Science degree in Geology in 1982, and a graduate of the University of Ottawa with a Master of Science degree in Geology in 1992.

3. THAT I am a Professional Geoscientist registered in good standing with the Association of Professional Engineers and Geoscientists of the Province of British Columbia (#20063).

4. THAT this report is based on a field program carried out under my direction in the period between July 31 to August 12, 2012 and on publicly available and company reports

DATED at Vancouver, British Columbia, this 18th day of December, 2013.



Murray I. Jones, M.Sc., P.Geo.

Equity Exploration Consultants Ltd.

Regional Stratigraphy/Lithology Legend

Quaternary
- Unconsolidated glacial, fluvial, soil and organic deposits

Eocene
- Hayden Lake Suite:salt and pepper, light and dark hornblende, +/- biotite, diorite to quartz diorite; masssive, medium to caorse grained
- Mafic Dyke
- Diorite Dyke

Paleocene
- Rhyolite Creek Complex: light grey to purple quartz-feldspar porphyry; quartz is commonly smokey grey and up to 3mm in diameter, occcurs as narow dykes to large intrusive bodies
- Rhyolite Creek Complex: light grey, green. maroon, purple, and black rhyolite and dacite locally flow banded, commonly a breccia with clasts of rhyolite within a crystal rich matrix
- Rhyolite Creek Complex: maroon to reddish purple (weathered and fresh), fine to very coarse grained andesite, brecciated with clasts of feldspar-rich andesite in the same matrix
- Rhyolite Creek Complex: dark grey to black weathered very fine grained basalt; geographically limited to east fo Porphyry Peak
- Rhyolite Creek Complex: basal conglomerate/breccia; rounded to angular clasts of underlying metamorphic rocks within a sandy volcaniclastic matrix
- Ruby Range Batholith: fine to coarse grained, salt and pepper, hornblende +/- biotite, quartz diorite, rare garnets; medium grained, light grey to pinkish biotite +/- hornblende granodiorite; fine to medium-grained, beige to grey tonalite with distinctive smokey grey quartz

Late-Cretaceous
- Gneiss: beige, orange to grey/black medium to coarse-grained orthogneiss and paragneiss; mafic layers composed primarily of biotite +/- hornblende, leucocratic layers consist of quartz, potassium feldspar and plagioclase

Late-Triassic
- Doghead Assemblage: deformed harzburgite and gabbro

Mississippian (?) or Permian (?)
- medium to coarse-grained hornblende-biotite quartz-diorite and diorite orthogniess; occurs as strongly deformed lenses within Snowcap assemblage

Upper Devonian to Lower Mississippian
- Finlayson Assemblage: polydeformed and metamorphosed mafic to felsic metavolcanic rocks; carbonaceous pelite, quartzite and pssamite; quartz-muscovite schist; rare metaplutonic rocks
- Quartz dk
- Quartz ca
- Skarn
- Finlayson Assemblage: white to cream-coloured, fine to coarse-grained marble; strongly deformed and metamorphosed; locally silicified; occurs as lenses and large bodies within carbonaceous schist

Lower Devonian and Older
- Snowcap Assemblage: polydeformed and metamorphosed quartzite, psammite and pelite; minor garnet amphibolite; quartz-muscovite schist; rare metaplutonic rocks
- Snowcap Assemblage: light grey and cream weathered marble; occurs as lenses within quartzite and psammitic to pelitic schist

Reference: Israel et al. 2010, 2011 Yukon Geological Survey

SYMBOLS & LINES

- Bedding - top known (inclined, vertical, overturned)
- Foliation (inclined, vertical)
- Crenulation (inclined, vertical)
- Vein (inclined, vertical)
- Joint / Fracture (inclined, vert.)
- Fault (inclined, vertical)
- Dyke (inclined, vertical)
- Cleavage (inclined, vertical)
- Fault
- Contact
- Outcrop, Float/Boulder
- Magnetic Lineament
- Showing
- Alteration Zone

Polly Ck
Cracker Ck
Dwarf Birch Ck
Deimos Ck

PDs
QRTZ
DACT
QRTZ phy
QRTZ dk
QRTZ BI-SCHS
QRTZ/PHYL
QRTZ ca
SKRN
Polly Soil
Danna jaw
GRNT
QRTZ/BI SCHS
RYDC
RHYL
MRBL
LMST
PR
PRp
DACT/MAFC
MAFC
GRNT/QRTZ
QRTZ/Dmf
PX-GA SKRN
BI (QZ) SCHS
INTM por
QFPO
FELS/SKRN

1000 m

SUMAC MINES LTD.			
Polly Property Property Geology			
EQUITY	Date: DEC 2013	Scale: 1:10,000	Figure 4
	U.T.M. Zone: UTM7 - NAD83	Mining District: WHITEHORSE	
	N.T.S.: 115G/09	State/Province: YUKON	

Regional Stratigraphy/Lithology Legend

Quaternary

Unconsolidated glacial, fluvial, soil and organic deposits

Eocene

Hayden Lake Suite:salt and pepper, light and dark hornblende, +/- biotite, diorite to quartz diorite; masssive, medium to caorse grained

Mafic Dyke

Diorite Dyke

Paleocene

Rhyolite Creek Complex: light grey to purple quartz-feldspar porphyry; quartz is commonly smokey grey and up to 3mm in diameter, occcurs as narow dykes to large intrusive bodies

Rhyolite Creek Complex: light grey, green. maroon, purple, and black rhyolite and dacite locally flow banded, commonly a breccia with clasts of rhyolite within a crystal rich matrix

Rhyolite Creek Complex: maroon to reddish purple (weathered and fresh), fine to very coarse grained andesite, brecciated with clasts of feldspar-rich andesite in the same matrix

Rhyolite Creek Complex: dark grey to black weathered very fine grained basalt; geographically limited to east fo Porphyry Peak

Rhyolite Creek Complex: basal conglomerate/breccia; rounded to angular clasts of underlying metamorphic rocks within a sandy volcaniclastic matrix

Ruby Range Batholith: fine to coarse grained, salt and pepper, hornblende +/- biotite, quartz diorite, rare garnets; medium grained, light grey to pinkish biotite +/- hornblende granodiorite; fine to medium-grained, beige to grey tonalite with distinctive smokey grey quartz

Late-Cretaceous

Gneiss: beige, orange to grey/black medium to coarse-grained orthogneiss and paragneiss; mafic layers composed primarily of biotite +/- hornblende, leucocratic layers consist of quartz, potassium feldspar and plagioclase

Late-Triassic

Doghead Assemblage: deformed harzburgite and gabbro

Mississippian (?) or Permian (?)

medium to coarse-grained hornblende-biotite quartz-diorite and diorite orthognieiss; occurs as strongly deformed lenses within Snowcap assemblage

Upper Devonian to Lower Mississippian

Finlayson Assemblage: polydeformed and metamorphosed mafic to felsic metavolcanic rocks; carbonaceous pelite, quartzite and pssamite; quartz-muscovite schist; rare metaplutonic rocks

Quartz dk

Quartz ca

Skarn

Finlayson Assemblage: white to cream-coloured, fine to coarse-grained marble; strongly deformed and metamorphosed; locally silicified; occurs as lenses and large bodies within carbonaceous schist

Lower Devonian and Older

Snowcap Assemblage: polydeformed and metamorphosed quartzite, psammite and pelite; minor garnet amphibolite; quartz-muscovite schist; rare metaplutonic rocks

Snowcap Assemblage: light grey and cream weathered marble; occurs as lenses within quartzite and psammitic to pelitic schist

Reference: Israel et al. 2010, 2011 Yukon Geological Survey

SYMBOLS & LINES

- Bedding - top known (inclined, vertical, overturned)
- Foliation (inclined, vertical)
- Crenulation (inclined, vertical)
- Vein (inclined, vertical)
- Joint / Fracture (inclined, vert.)
- Fault (inclined, vertical)
- Dyke (inclined, vertical)
- Cleavage (inclined, vertical)
- Fault
- Contact
- Outcrop, Float/Boulder
- Magnetic Lineament
- Showing
- Alteration Zone

SAMPLE_ID	Easting	Northing	Cu_ppm	Au_ppm	Mo_ppm	Zn_ppm
I101928	348,148	6,856,748	28	0.106	7	342
I101929	348,120	6,856,613	57	0.149	7	133
I101930	347,928	6,856,320	5	0.013	-1	29
I101931	347,850	6,855,831	34	2.13	-1	17
I101932	348,784	6,855,940	10	0.043	-1	70
L646601	652,549	6,826,391	38	-0.005	2	35
L646602	652,298	6,826,007	50	-0.005	2	36
L646603	652,276	6,825,999	30	-0.005	7	37
L646604	651,707	6,824,826	34	-0.005	1	50
L646605	651,587	6,824,334	57	-0.005	-1	37
L646606	650,990	6,823,018	15	-0.005	18	38
L646607	648,489	6,826,404	21	-0.005	36	53
L646608	648,935	6,827,239	34	-0.005	2	44
L646609	649,040	6,827,179	5	-0.005	-1	14
L646610	649,900	6,827,028	57	-0.005	5	41
L646611	650,507	6,826,283	18	-0.005	1	31
L646612	641,205	6,838,422	1	-0.005	-1	10
L646613	641,314	6,838,427	3	-0.005	-1	25
L646614	641,847	6,837,585	12	-0.005	377	26
L646615	641,898	6,837,601	17	-0.005	21	23
L646616	639,042	6,839,773	7	-0.005	3	27
L646617	638,829	6,839,881	87	-0.005	78	93
L646618	638,589	6,839,846	126	-0.005	1	24
L646619	637,909	6,840,362	19	-0.005	3	116
L646620	637,950	6,840,395	116	-0.005	2	70
L646621	638,725	6,840,703	280	0.023	7	737
L646622	639,895	6,839,562	20	-0.005	13	61
L646623	640,092	6,838,452	6	-0.005	2	116
L646624	639,627	6,838,105	345	0.028	1	163
L646625	641,181	6,842,875	211	-0.005	3	76
L646626	641,019	6,843,256	5	0.007	-1	106
L646627	640,670	6,843,657	61	0.005	-1	202
L646628	640,063	6,843,840	194	0.008	2	713
L646629	640,518	6,844,547	3	0.005	1	173
L646630	640,646	6,844,520	73	0.077	3	24
L646631	640,646	6,844,520	91	0.063	3	25
L646632	639,385	6,844,455	23	-0.005	3	96
L646633	639,657	6,844,506	459	0.81	15	3,400
L646634	639,660	6,844,499	173	0.062	3	1,800
L646635	639,948	6,844,470	52	0.009	1	201
L646636	639,947	6,844,469	33	-0.005	1	82
L646637	640,131	6,843,288	55	-0.005	5	32
L646638	640,208	6,843,128	154	0.006	74	110
L646639	641,155	6,843,456	2,090	-0.005	-1	2,100
L646640	641,148	6,843,447	17	0.006	6	2,410
L646641	641,144	6,843,447	29	-0.005	-1	1,940
L646642	641,137	6,843,444	14	0.005	1	1,630
L646643	641,134	6,843,436	10	0.028	2	5,020
L646644	641,130	6,843,431	3	0.008	8	2,300
L646645	641,123	6,843,430	12	0.007	-1	1,360
L646646	641,125	6,843,445	4	0.007	-1	989
L647751	650,251	6,825,363	49	-0.005	3	7
L647752	650,046	6,824,486	20	-0.005	2	17
L647753	650,406	6,825,911	22	-0.005	16	42
L647754	638,792	6,839,767	50	-0.005	9	21
L647755	639,527	6,839,420	23	0.035	2	65
L647756	641,243	6,838,852	12	-0.005	1	421
L647757	639,941	6,842,755	81	0.098	3	152
L647758	641,171	6,842,930	1,260	0.668	1	42,200
L647759	639,720	6,843,729	30	-0.005	2	126
L647760	639,940	6,842,758	15	0.005	4	265
L647761	640,447	6,842,784	26	0.013	2	113

- 2013 ROCK SAMPLES
- ROCK SAMPLES
- 2013 SOIL SAMPLES
- SOIL SAMPLES
- SILT SAMPLES

1000 m

SUMAC MINES LTD.

Polly Property

Geochemistry
2013 Sample Locations

EQUITY

Date: DEC 2013	Scale: 1:10,000	Figure 5a
U.T.M. Zone UTM7 - NAD83	Mining District WHITEHORSE	
N.T.S. 115G/09	State/Province YUKON	

Regional Stratigraphy/Lithology Legend

Quaternary
- Unconsolidated glacial, fluvial, soil and organic deposits

Eocene
- Hayden Lake Suite:salt and pepper, light and dark hornblende, +/- biotite, diorite to quartz diorite; masssive, medium to caorse grained
- Mafic Dyke
- Diorite Dyke

Paleocene
- Rhyolite Creek Complex: light grey to purple quartz-feldspar porphyry; quartz is commonly smokey grey and up to 3mm in diameter, occurs as narow dykes to large intrusive bodies
- Rhyolite Creek Complex: light grey, green. maroon, purple, and black rhyolite and dacite locally flow banded, commonly a breccia with clasts of rhyolite within a crystal rich matrix
- Rhyolite Creek Complex: maroon to reddish purple (weathered and fresh), fine to very coarse grained andesite, brecciated with clasts of feldspar-rich andesite in the same matrix
- Rhyolite Creek Complex: dark grey to black weathered very fine grained basalt; geographically limited to east fo Porphyry Peak
- Rhyolite Creek Complex: basal conglomerate/breccia; rounded to angular clasts of underlying metamorphic rocks within a sandy volcaniclastic matrix
- Ruby Range Batholith: fine to coarse grained, salt and pepper, hornblende +/- biotite, quartz diorite, rare garnets; medium grained, light grey to pinkish biotite +/- hornblende granodiorite; fine to medium-grained, beige to grey tonalite with distinctive smokey grey quartz

Late-Cretaceous
- Gneiss: beige, orange to grey/black medium to coarse-grained orthogneiss and paragneiss; mafic layers composed primarily of biotite +/- hornblende, leucocratic layers consist of quartz, potassium feldspar and plagioclase

Late-Triassic
- Doghead Assemblage: deformed harzburgite and gabbro

Mississippian (?) or Permian (?)
- medium to coarse-grained hornblende-biotite quartz-diorite and diorite orthogniess; occurs as strongly deformed lenses within Snowcap assemblage

Upper Devonian to Lower Mississippian
- Finlayson Assemblage: polydeformed and metamorphosed mafic to felsic metavolcanic rocks; carbonaceous pelite, quartzite and pssamite; quartz-muscovite schist; rare metaplutonic rocks
- Quartz dk
- Quartz ca
- Skarn
- Finlayson Assemblage: white to cream-coloured, fine to coarse-grained marble; strongly deformed and metamorphosed; locally silicified; occurs as lenses and large bodies within carbonaceous schist

Lower Devonian and Older
- Snowcap Assemblage: polydeformed and metamorphosed quartzite, psammite and pelite; minor garnet amphibolite; quartz-muscovite schist; rare metaplutonic rocks
- Snowcap Assemblage: light grey and cream weathered marble; occurs as lenses within quartzite and psammitic to pelitic schist

Reference: Israel et al. 2010, 2011 Yukon Geological Survey

SYMBOLS & LINES

- Bedding - top known (inclined, vertical, overturned)
- Foliation (inclined, vertical)
- Crenulation (inclined, vertical)
- Vein (inclined, vertical)
- Joint / Fracture (inclined, vert.)
- Fault (inclined, vertical)
- Dyke (inclined, vertical)
- Cleavage (inclined, vertical)
- Fault
- Contact
- Outcrop, Float/Boulder
- Magnetic Lineament
- Showing
- Alteration Zone

2012 Rock Geochemistry
Copper (ppm)

> 1,000 ppm	(2)
250 to 500	(3)
100 to 250	(6)
75 to 100	(3)
50 to 75	(9)
25 to 50	(11)
< 25 pm	(28)

2013 Soil Geochemistry
Copper (ppm)

> 200 ppm	(9)
100 to 200	(36)
50 to 100	(172)
20 to 50	(430)
15 to 20	(45)
10 to 15	(22)
5 to 10	(8)
< 5 ppm	(0)

Rock Geochemistry pre 2013
Copper (ppm)

> 6,000 ppm	(18)
2,500 to 6,000	(32)
400 to 2,500	(84)
100 to 400	(137)
< 100 ppm	(669)

Soil Geochemistry pre 2012
Copper (ppm)

> 200 ppm	(52)
100 to 200	(202)
50 to 100	(655)
20 to 50	(1453)
15 to 20	(145)
10 to 15	(44)
5 to 10	(16)
< 5 ppm	(23)

Silt Geochemistry pre 2012
Copper (ppm)

102.9 to 750	(49)
76 to 102.9	(77)
48 to 76	(243)
33 to 48	(371)
all others	(1675)

- 2013 ROCK SAMPLES
- ROCK SAMPLES
- 2013 SOIL SAMPLES
- SOIL SAMPLES
- SILT SAMPLES

1000 m

SUMAC MINES LTD.

Polly Property

Geochemistry
Copper (ppm)

EQUITY

Date: DEC 2013	Scale: 1:10,000	Figure
U.T.M. Zone: UTM7 - NAD83	Mining District: WHITEHORSE	5b
N.T.S.: 115G/09	State/Province: YUKON	

Regional Stratigraphy/Lithology Legend

Quaternary
- Unconsolidated glacial, fluvial, soil and organic deposits

Eocene
- Hayden Lake Suite:salt and pepper, light and dark hornblende, +/- biotite, diorite to quartz diorite; masssive, medium to caorse grained
- Mafic Dyke
- Diorite Dyke

Paleocene
- Rhyolite Creek Complex: light grey to purple quartz-feldspar porphyry; quartz is commonly smokey grey and up to 3mm in diameter, occcurs as narow dykes to large intrusive bodies
- Rhyolite Creek Complex: light grey, green. maroon, purple, and black rhyolite and dacite locally flow banded, commonly a breccia with clasts of rhyolite within a crystal rich matrix
- Rhyolite Creek Complex: maroon to reddish purple (weathered and fresh), fine to very coarse grained andesite, brecciated with clasts of feldspar-rich andesite in the same matrix
- Rhyolite Creek Complex: dark grey to black weathered very fine grained basalt; geographically limited to east fo Porphyry Peak
- Rhyolite Creek Complex: basal conglomerate/breccia; rounded to angular clasts of underlying metamorphic rocks within a sandy volcaniclastic matrix
- Ruby Range Batholith: fine to coarse grained, salt and pepper, hornblende +/- biotite, quartz diorite, rare garnets; medium grained, light grey to pinkish biotite +/- hornblende granodiorite; fine to medium-grained, beige to grey tonalite with distinctive smokey grey quartz

Late-Cretaceous
- Gneiss: beige, orange to grey/black medium to coarse-grained orthogneiss and paragneiss; mafic layers composed primarily of biotite +/- hornblende, leucocratic layers consist of quartz, potassium feldspar and plagioclase

Late-Triassic
- Doghead Assemblage: deformed harzburgite and gabbro

Mississippian (?) or Permian (?)
- medium to coarse-grained hornblende-biotite quartz-diorite and diorite orthogniess; occurs as strongly deformed lenses within Snowcap assemblage

Upper Devonian to Lower Mississippian
- Finlayson Assemblage: polydeformed and metamorphosed mafic to felsic metavolcanic rocks; carbonaceous pelite, quartzite and pssamite; quartz-muscovite schist; rare metaplutonic rocks
- Quartz dk
- Quartz ca
- Skarn
- Finlayson Assemblage: white to cream-coloured, fine to coarse-grained marble; strongly deformed and metamorphosed; locally silicified; occurs as lenses and large bodies within carbonaceous schist

Lower Devonian and Older
- Snowcap Assemblage: polydeformed and metamorphosed quartzite, psammite and pelite; minor garnet amphibolite; quartz-muscovite schist; rare metaplutonic rocks
- Snowcap Assemblage: light grey and cream weathered marble; occurs as lenses within quartzite and psammitic to pelitic schist

Reference: Israel et al. 2010, 2011 Yukon Geological Survey

SYMBOLS & LINES

- Bedding - top known (inclined, vertical, overturned)
- Foliation (inclined, vertical)
- Crenulation (inclined, vertical)
- Vein (inclined, vertical)
- Joint / Fracture (inclined, vert.)
- Fault (inclined, vertical)
- Dyke (inclined, vertical)
- Cleavage (inclined, vertical)
- Fault
- Contact
- Outcrop, Float/Boulder
- Magnetic Lineament
- Showing
- Alteration Zone

2013 Rock Geochemistry
Gold (ppm)

> 1 ppm		(1)
0.5	to 1	(2)
0.1	to 0.25	(2)
0.075	to 0.1	(2)
0.05	to 0.075	(2)
0.0025	to 0.005	(0)
< 0.0025		(53)

2013 Soil Geochemistry
Gold (ppm)

> 0.2 ppm		(1)
0.1	to 0.2	(0)
0.05	to 0.1	(3)
0.02	to 0.05	(28)
0.015	to 0.02	(14)
0.01	to 0.015	(62)
0.005	to 0.01	(173)
< 0.005 ppm		(439)

Rock Geochemistry pre 2013
Gold (ppm)

> 1 ppm		(15)
0.5	to 1	(8)
0.25	to 0.5	(10)
0.1	to 0.25	(37)
0.075	to 0.1	(16)
0.05	to 0.075	(38)
0.0025	to 0.005	(8)
< 0.0025		(808)

Soil Geochemistry pre 2013
Gold (ppm)

> 0.2 ppm		(1)
0.1	to 0.2	(7)
0.05	to 0.1	(31)
0.02	to 0.05	(291)
0.015	to 0.02	(142)
0.01	to 0.015	(277)
0.005	to 0.01	(688)
< 0.005 ppm		(1153)

Silt Geochemistry
Gold (ppm)

> 0.044 ppm		(45)
0.022	to 0.044	(72)
0.01	to 0.022	(245)
0.006	to 0.01	(448)
< 0.006 ppm		(1605)

- 2013 ROCK SAMPLES
- ROCK SAMPLES
- 2013 SOIL SAMPLES
- SOIL SAMPLES
- SILT SAMPLES

1000 m

SUMAC MINES LTD.

Polly Property

Geochemistry
Gold (ppm)

EQUITY

Date: DEC 2013	Scale: 1:10,000	Figure
U.T.M. Zone UTM7 - NAD83	Mining District WHITEHORSE	5c
N.T.S. 115G/09	State/Province YUKON	

Regional Stratigraphy/Lithology Legend

Quaternary
- Unconsolidated glacial, fluvial, soil and organic deposits

Eocene
- Hayden Lake Suite:salt and pepper, light and dark hornblende, +/- biotite, diorite to quartz diorite; masssive, medium to caorse grained
- Mafic Dyke
- Diorite Dyke

Paleocene
- Rhyolite Creek Complex: light grey to purple quartz-feldspar porphyry; quartz is commonly smokey grey and up to 3mm in diameter, occurs as narow dykes to large intrusive bodies
- Rhyolite Creek Complex: light grey, green. maroon, purple, and black rhyolite and dacite locally flow banded, commonly a breccia with clasts of rhyolite within a crystal rich matrix
- Rhyolite Creek Complex: maroon to reddish purple (weathered and fresh), fine to very coarse grained andesite, brecciated with clasts of feldspar-rich andesite in the same matrix
- Rhyolite Creek Complex: dark grey to black weathered very fine grained basalt; geographically limited to east fo Porphyry Peak
- Rhyolite Creek Complex: basal conglomerate/breccia; rounded to angular clasts of underlying metamorphic rocks within a sandy volcaniclastic matrix
- Ruby Range Batholith: fine to coarse grained, salt and pepper, hornblende +/- biotite, quartz diorite, rare garnets; medium grained, light grey to pinkish biotite +/- hornblende granodiorite; fine to medium-grained, beige to grey tonalite with distinctive smokey grey quartz

Late-Cretaceous
- Gneiss: beige, orange to grey/black medium to coarse-grained orthogneiss and paragneiss; mafic layers composed primarily of biotite +/- hornblende, leucocratic layers consist of quartz, potassium feldspar and plagioclase

Late-Triassic
- Doghead Assemblage: deformed harzburgite and gabbro

Mississippian (?) or Permian (?)
- medium to coarse-grained hornblende-biotite quartz-diorite and diorite orthogniess; occurs as strongly deformed lenses within Snowcap assemblage

Upper Devonian to Lower Mississippian
- Finlayson Assemblage: polydeformed and metamorphosed mafic to felsic metavolcanic rocks; carbonaceous pelite, quartzite and pssamite; quartz-muscovite schist; rare metaplutonic rocks
- Quartz dk
- Quartz ca
- Skarn
- Finlayson Assemblage: white to cream-coloured, fine to coarse-grained marble; strongly deformed and metamorphosed; locally silicified; occurs as lenses and large bodies within carbonaceous schist

Lower Devonian and Older
- Snowcap Assemblage: polydeformed and metamorphosed quartzite, psammite and pelite; minor garnet amphibolite; quartz-muscovite schist; rare metaplutonic rocks
- Snowcap Assemblage: light grey and cream weathered marble; occurs as lenses within quartzite and psammitic to pelitic schist

Reference: Israel et al. 2010, 2011 Yukon Geological Survey

SYMBOLS & LINES

- Bedding - top known (inclined, vertical, overturned)
- Foliation (inclined, vertical)
- Crenulation (inclined, vertical)
- Vein (inclined, vertical)
- Joint / Fracture (inclined, vert.)
- Fault (inclined, vertical)
- Dyke (inclined, vertical)
- Cleavage (inclined, vertical)
- Fault
- Contact
- Outcrop, Float/Boulder
- Magnetic Lineament
- Showing
- Alteration Zone

2013 Rock Geochemistry
Molybdenum (ppm)

> 250 ppm	(1)
50 to 100	(2)
25 to 50	(1)
10 to 25	(5)
5 to 10	(9)
2.5 to 5	(10)
< 2.5 ppm	(34)

2013 Soil Geochemistry
Molybdenum (ppm)

> 50 ppm	(1)
20 to 50	(14)
10 to 20	(15)
5 to 10	(88)
2 to 5	(322)
1 to 2	(203)
< 0.5 ppm	(79)

Rock Geochemistry pre 2013
Molybdenum (ppm)

> 250 ppm	(12)
100 to 250	(13)
50 to 100	(12)
25 to 50	(26)
10 to 25	(122)
5 to 10	(173)
2.5 to 5	(103)
< 2.5 ppm	(442)

Soil Geochemistry pre 2013
Molybdenum (ppm)

> 50 ppm	(1)
20 to 50	(13)
10 to 20	(33)
5 to 10	(196)
2 to 5	(1065)
1 to 2	(865)
0.5 to 1	(51)
< 0.5 ppm	(366)

Silt Geochemistry
Molybdenum (ppm)

6 to 150	(54)
4.1 to 6	(69)
2.3 to 4.1	(243)
1.2 to 2.3	(362)
all others	(1687)

- 2013 ROCK SAMPLES
- ROCK SAMPLES
- 2013 SOIL SAMPLES
- SOIL SAMPLES
- SILT SAMPLES

1000 m

SUMAC MINES LTD.

Polly Property

Geochemistry
Molybdenum (ppm)

EQUITY

Date: DEC 2013	Scale: 1:10,000	Figure
U.T.M. Zone: UTM7 - NAD83	Mining District: WHITEHORSE	5d
N.T.S.: 115G/09	State/Province: YUKON	

Regional Stratigraphy/Lithology Legend

Quaternary
- Unconsolidated glacial, fluvial, soil and organic deposits

Eocene
- Hayden Lake Suite:salt and pepper, light and dark hornblende, +/- biotite, diorite to quartz diorite; masssive, medium to caorse grained
- Mafic Dyke
- Diorite Dyke

Paleocene
- Rhyolite Creek Complex: light grey to purple quartz-feldspar porphyry; quartz is commonly smokey grey and up to 3mm in diameter, occcurs as narow dykes to large intrusive bodies
- Rhyolite Creek Complex: light grey, green. maroon, purple, and black rhyolite and dacite locally flow banded, commonly a breccia with clasts of rhyolite within a crystal rich matrix
- Rhyolite Creek Complex: maroon to reddish purple (weathered and fresh), fine to very coarse grained andesite, brecciated with clasts of feldspar-rich andesite in the same matrix
- Rhyolite Creek Complex: dark grey to black weathered very fine grained basalt; geographically limited to east fo Porphyry Peak
- Rhyolite Creek Complex: basal conglomerate/breccia; rounded to angular clasts of underlying metamorphic rocks within a sandy volcaniclastic matrix
- Ruby Range Batholith: fine to coarse grained, salt and pepper, hornblende +/- biotite, quartz diorite, rare garnets; medium grained, light grey to pinkish biotite +/- hornblende granodiorite; fine to medium-grained, beige to grey tonalite with distinctive smokey grey quartz

Late-Cretaceous
- Gneiss: beige, orange to grey/black medium to coarse-grained orthogneiss and paragneiss; mafic layers composed primarily of biotite +/- hornblende, leucocratic layers consist of quartz, potassium feldspar and plagioclase

Late-Triassic
- Doghead Assemblage: deformed harzburgite and gabbro

Mississippian (?) or Permian (?)
- medium to coarse-grained hornblende-biotite quartz-diorite and diorite orthogniess; occurs as strongly deformed lenses within Snowcap assemblage

Upper Devonian to Lower Mississippian
- Finlayson Assemblage: polydeformed and metamorphosed mafic to felsic metavolcanic rocks; carbonaceous pelite, quartzite and pssamite; quartz-muscovite schist; rare metaplutonic rocks
- Quartz dk
- Quartz ca
- Skarn
- Finlayson Assemblage: white to cream-coloured, fine to coarse-grained marble; strongly deformed and metamorphosed; locally silicified; occurs as lenses and large bodies within carbonaceous schist

Lower Devonian and Older
- Snowcap Assemblage: polydeformed and metamorphosed quartzite, psammite and pelite; minor garnet amphibolite; quartz-muscovite schist; rare metaplutonic rocks
- Snowcap Assemblage: light grey and cream weathered marble; occurs as lenses within quartzite and psammitic to pelitic schist

Reference: Israel et al. 2010, 2011 Yukon Geological Survey

SYMBOLS & LINES

- Bedding - top known (inclined, vertical, overturned)
- Foliation (inclined, vertical)
- Crenulation (inclined, vertical)
- Vein (inclined, vertical)
- Joint / Fracture (inclined, vert.)
- Fault (inclined, vertical)
- Dyke (inclined, vertical)
- Cleavage (inclined, vertical)
- Fault
- Contact
- Outcrop, Float/Boulder
- Magnetic Lineament
- Showing
- Alteration Zone

2013 Rock Geochemistry
Zinc (ppm)

> 7,500 ppm	(1)
5,000 to 7,500	(1)
2,500 to 5,000	(1)
1,000 to 2,500	(7)
500 to 1,000	(3)
250 to 500	(3)
100 to 250	(12)
< 100 ppm	(34)

2013 Soil Geochemistry
Zinc (ppm)

> 1,500 ppm	(2)
1,000 to 1,500	(4)
500 to 1,000	(7)
200 to 500	(76)
100 to 200	(239)
50 to 100	(293)
20 to 50	(93)
< 20 ppm	(8)

Rock Geochemistry pre 2013
Zinc (ppm)

> 7,500 ppm	(7)
5,000 to 7,500	(3)
2,500 to 5,000	(8)
1,000 to 2,500	(24)
500 to 1,000	(19)
250 to 500	(47)
100 to 250	(169)
< 100 ppm	(662)

Soil Geochemistry pre 2013
Zinc (ppm)

> 1,500 ppm	(8)
1,000 to 1,500	(7)
500 to 1,000	(35)
200 to 500	(199)
100 to 200	(660)
50 to 100	(1445)
20 to 50	(201)
< 20 ppm	(13)

Silt Geochemistry pre 2013
Zinc (ppm)

> 1,000 ppm	
350 to 1,000	
150 to 350	
80 to 150	
< 80 ppm	

- 2013 ROCK SAMPLES
- ROCK SAMPLES
- 2013 SOIL SAMPLES
- SOIL SAMPLES
- SILT SAMPLES

1000 m

SUMAC MINES LTD.

Polly Property

Geochemistry
Zinc (ppm)

EQUITY

Date: DEC 2013	Scale: 1:10,000	Figure 5e
U.T.M. Zone UTM7 - NAD83	Mining District WHITEHORSE	
N.T.S. 115G/09	State/Province YUKON	