ASSESSMENT REPORT
YMEP No. 20-027

2020 TRENCHING, SOIL SAMPLING, and PROSPECTING

on the

# Bullseye Property

Whitehorse Mining District, Yukon Territory

**for**

# Golden Sky Minerals Corp.

1010 – 1130 West Pender Street
Vancouver, British Columbia
Canada V6E 4A4
Telephone: (604) 568-8807
Facsimile: (604) 681-1864

**NTS Mapsheets:** 115j05, 115j12, 115k08
**UTM Coordinates:** E555000, N6931000 (NAD83, Zone7)
**Claim filed:** BE 1 – BE 106 (YF05301 – YF05406), BE 107 – BE 112 (YF05495 – YF05500), BE 113 – BE 122 (YF55583 – YF55592), BE 123 – BE 142 (YF05503 – YF05522)
**Owner(s):** Luckystrike Resources Ltd., Golden Sky Minerals Corp.
**Author:** D. Ferraro, HBSc.
**Dates worked performed:** July 1st, 2020 to July 12th, 2020

**TABLE OF CONTENTS**


1.0 Summary ....4
2.0 Introduction ....6
3.0 Property Location and Access ....6
4.0 Physiography, Vegetation, and Climate ....8
5.0 Property Description ....10
6.0 Property History ....10
7.0 Geology
  7.1 Regional Geology ....14
  7.2 Property Geology and Mineralization ....15
8.0 2020 Mechanical Trenching Program
  8.1 Summary of Trenching Program ....18
  8.2 Sampling Methodology ....18
  8.3 Sample Preparation, Analysis, and QA/QC ....18
  8.4 Trenching Results ....19
9.0 2020 Prospecting and Soil Sampling Program
  9.1 Summary of Prospecting and Soil Sampling Program ....23
  9.2 Sampling Methodology ....23
  9.3 Sample Preparation, Analysis, and QA/QC ....23
  9.4 Prospecting and Soil Sampling Results ....24
10.0 Discussion ....34
11.0 Conclusions and Recommendations ....35
References ....38
Statement of Expenditures ....38
Certificates of Qualifications ....39


**Figures, Photos, and Tables**


Figure 1: Location Map of the Bullseye Property ....7
Figure 2: Glacial Limits Map ....9
Figure 3: Claim Map ....12
Figure 4: Mineral Occurrences Map ....13
Figure 5: Bedrock Geology ....16
Figure 6: Total Magnetic Intensity (TMI) Map of the Bullseye Area ....17
Figure 7: Trenching Results at the Gold Crest Zone ....22
Figure 8: Sample Location Map – Property-wide ....26
Figure 9: Sample Location Map – Gold Crest zone ....27
Figure 10: Surface Geochemistry – Gold – Property-wide ....28
Figure 11: Surface Geochemistry – Gold – Gold Crest area ....29
Figure 12: Surface Geochemistry – Silver – Gold Crest area ....30
Figure 13: Surface Geochemistry – Arsenic – Gold Crest area ....31
Figure 14: Surface Geochemistry – Antimony – Gold Crest area ....32

**TABLE OF CONTENTS (CONTINUED)**

Figure 15: Annotated photo of the Gold Crest zone looking southeast.....33
Figure 16: Annotated photo of the Gold Crest trend looking northeast.....33
Figure 17: Recommended Future Work at Gold Crest .....37

Photo 1: Physiography of the Bullseye Property .....8
Photo 2: BETR-20-01, 12-14m – oxidized quartz-sericite schist with limonitic pyrite .....20
Photo 3: BETR-20-01, 30-32m – oxidized quartz-sericite schist with quartz stockwork...20
Photo 4: BETR-20-01, 8-10m – quartz-sericite schist, chlorite schist, leucogabbro.....21
Photo 5: Pit sample 1878264 – limonitic schist and quartz stockwork.....29

Table 1: Gold intercepts from trench BETR-20-01.....19
Table 2: Correlations to gold.....34

**Appendices**

Appendix I: List of Claims.....40
Appendix II: Trench Sample Descriptions.....44
Appendix III: Rock Grab Sample Descriptions.....48
Appendix IV: Soil Sample Descriptions .....51
Appendix V: Trench Sample Assay Certificates.....61
Appendix VI: Prospecting Rock Sample Assay Certificates.....73
Appendix VII: Soil Sample Assay Certificates.....83
Appendix VIII: YMEP Final Submission Form .....134

## 1.0 SUMMARY

A trenching, soil sampling, and prospecting program was conducted on the Bullseye property between July 1st and July 12th, 2020. The program consisted of one 134m trench, 562 soil samples, and 49 prospecting grab samples. The property is owned 100% by Golden Sky Minerals Corp. and consists of 142 contiguous quartz claims located in the Whitehorse Mining District.

The Bullseye property is located on NTS mapsheets 115K 08, 115J 05, and 115J 12. It is approximately 325 kilometers northwest of Whitehorse, 175 km south of Dawson City, and 50 km due east of Beaver Creek, Yukon Territory. The property is situated at the northern end of the Wellesley Lake basin near the confluence of the Donjek and White Rivers. Access is only possible by helicopter, best chartered out of Dawson City or Beaver Creek.

The original Bullseye property was staked and worked in 2017 by Goldstrike Resources Ltd. In 2018 the property was spun out to Luckystrike Resources Ltd. In 2020 the company name was changed to Golden Sky Minerals Ltd. No work was done after the 2017 program until the 2020 program which this report describes.

The Bullseye property encompasses a large block of unexplored ground directly adjacent to two large claim groups that were subject to significant surface exploration from 2013 to 2017. These claim groups include the Wels Gold property owned by K2 Gold Corp. and the Wells property owned by White Gold Corp. The Bullseye property was staked primarily based on the elevated gold values seen in regional stream sediment samples in conjunction with similar geology to K2 Gold's Wels Gold showing.

The property is located at the fringe of unglaciated terrain with the north-eastern portion of the property remaining unglaciated. The southern portion of the property was subjected to the glacial ice sheet of the pre-Reid and Reid glaciations during the Pleistocene (60 ka to 3 ma). The glaciated terrain is marked by a thick blanket of glacial fluvial sediments making exploration efforts difficult.

The Bullseye property is underlain by Devonian to Mississippian siliceous phyllite and schist of the White River Formation that are extensively intruded by Triassic gabbro of the Snag Creek suite. The Gold Crest zone (which has received the majority of exploration to date) is hosted along this regionally mapped contact between the older schist of the White River Formation and the much younger mafic intrusion of the Snag Creek Suite. This regional scale mapped contact runs NE-SW and extends the length of the property.

The 2020 mechanical trenching program consisted of 1 trench totalling 134m. Work on the trench was performed from July 8th, 2020 to July 12th, 2020. The trench was designed to cover the highest gold-in-soil values from the 2017 survey at the Gold Crest zone while taking into account budgetary constraints. Trench BETR-20-01 was successful in intersecting significant gold mineralization, yielding an intercept of 0.69 g/t Au over 78 meters. Results from the trench indicate the bedrock source of the geochemical anomaly was not fully exposed. The easternmost trench sample assayed 0.39 g/t Au over 2m.

Prospecting and soil sampling at Bullseye was conducted by 4 men between July 1st 2020 and July 11th, 2020. The crew collected 49 rock samples and 562 soil samples. The goal of the program was to expand upon known anomalies (particularly the Gold Crest zone) and to perform reconnaissance ridge-and-spur sampling in unexplored areas.

The 2020 exploration program successfully confirmed a bedrock source to the Gold Crest zone soil anomaly. The trench displayed a 78-meter intercept of consistent low- to mid-grade gold mineralization with open-ended gold values on the east end of the trench. Soil sampling extended the strike length of the zone to 2 kilometers and confirmed the relation of gold to the gabbro-schist contact. Observations from the trench indicate that mineralization is related to quartz stockwork, silicification, pyrite, and shearing along the contact. Soil sampling also indicates the potential of a cross-structure in the Gold Crest zone area.

## 1.0 SUMMARY (CONTINUED)

Due to the amount of glacial till and permafrost beyond the Gold Crest zone, very little additional surface geochemistry can be done here. It is recommended that the area be drilled. For logistics and budgetary concerns, a small, heli-portable RC drill is ideal for the job. Drilling should be conducted at a 280-300 degree azimuth and should be set back at least 15m from the east edge of the trench. Four drill holes spaced 50m apart could be drilled along strike to cover 200m of the Gold Crest zone. Depth of holes would be limited by the equipment, but should be 100-150m and drilled at a -45 degree (or similar) dip. Additional drill holes should be done further along strike in either direction where surface sampling methods failed. The cross structure heading north of Gold Crest should be investigated with at least 1 hole. The gold-in-soil values along the contact ~600m northeast of Gold Crest should be investigated with either 1-2 drill holes or a mechanical trench. The gold-in-soil values ~2km northeast of Gold Crest should be investigated with hand pits or a mechanical trench.

The area directly west and northwest of the Gold Crest trench displayed a strong Ag-Sb signature despite soil samples being affected by permafrost. At least one hole could be drilled in this area to test for a parallel north-south cross-structure.

Windage zone: This area displays ~250m of anomalous gold-in-soil values with a much broader As-Ag-Sb-Pb anomaly. No rock sampling was done. Further soiling sampling, prospecting, and hand dug pits should be done in this area to define the anomaly and determine a bedrock source. Trenching or drilling may be warranted.

Marksmen zone: Traditional surface sampling techniques in this area are problematic due to the amount of glacial till. Further prospecting should be done along western edge where outcrop was observed.

Dovetail zone: Although no significant gold values were returned from the rock or soil samples, an impressive amount of quartz stockwork was observed in this area, and only a few hours were spent exploring it. Further, more detailed prospecting should be done in here.

In addition to these zones, all non-glaciated areas should receive at least reconnaissance soil sampling. There is a small 750x400m gabbro plug mapped in the north end of the property. A single gabbro rock sample was taken within this unit in 2017 which assayed 0.16 g/t Au. A nearby soil sample also displayed a slightly anomalous gold value (13 ppb Au). This should receive follow-up prospecting and additional soil samples.

Due to the amount of glacial material, geophysical methods should be investigated to explore in blind spots along the Gold Crest trend and across the property as a whole. An IP survey is unlikely to be effective as very little sulphide has been observed in zones of mineralization. A property-wide airborne magnetic and radiometric survey would have the best chance of identifying structures and locating any potential reduced intrusion on the property. Failing this, a ground magnetic survey at the Gold Crest zone would be beneficial.

## 2.0 INTRODUCTION

This assessment report has been prepared on behalf of Golden Sky Minerals Corp. of Vancouver, BC to fulfill the requirements of the Yukon Mineral Exploration Program (YMEP) grant as well as the assessment requirements of the Whitehorse Mining Recorder. The report describes the 2020 surficial exploration program on the Bullseye property in the Whitehorse Mining District of the Yukon Territory.

The Bullseye Property was formerly held by Goldstrike Resources Ltd., of Vancouver, BC. In May of 2018 Goldstrike Resources Ltd. announced a proposed spin-off of its White Gold District properties, including the Bullseye Property. The arrangement was completed in August, 2018 and the new company was named Luckystrike Resources Ltd. In 2020 the company name was changed to Golden Sky Minerals Corp.

Field work for the 2020 season was performed by Druid Exploration Inc. of Dawson City, YT. The report was prepared by D. Ferraro of Dawson, YT.

## 3.0 PROPERTY LOCATION AND ACCESS

The Bullseye property is located within the Whitehorse Mining District on NTS mapsheets 115K 08, 115J 05, and 115J 12. The Gold Crest Zone on the property is geographically centred at 62° 29' 9 " N,139° 57' 33" W or UTM 553644 E 6928712 N (NAD 83, Zone 7).

Bullseye is approximately 325 kilometers northwest of Whitehorse, 175 km south of Dawson City, and 50 km due east of Beaver Creek, Yukon Territory (Figure 1). The property is situated at the northern end of the Wellesley Lake basin near the confluence of the Donjek and White Rivers.

Bullseye is only accessible by helicopter best chartered from Dawson City; however, the Beaver Creek community and Snag airstrip would provide a much closer staging area for future larger scale programs.

The 2020 program utilized the Independence Creek airstrip north of Bullseye to stage personnel and equipment closer to the property.

# FIGURE 1: PROPERTY LOCATION MAP

## BULL'S EYE PROPERTY



## 4.0 PHISIOGRAPHY, VEGETATION, AND CLIMATE

The property is located at the fringe of unglaciated terrain, with the northeastern portion of the property remaining unglaciated (see Photo 1 and Figure 2 for glacial limits). The southwestern portion of the property was subjected to the edges of the glacial limits of the pre-Reid and Reid glaciations during the Pleistocene (60 Ka to 3 Ma). The glaciated terrain contains a thick blanket of glacial fluvial sediments making exploration efforts difficult. Bedrock is confined mostly to the ridge tops and local cliffs and gullies in the creek valleys. The majority of the property was subjected to a forest fire in 2004 that has left a combination of mature dead standing and wind-blown trees intermixed with 10-15 year-old deciduous saplings. The combination of deadfall and thick saplings makes walking difficult in certain areas of the property.

Elevations on the property range from 580m in the White River valley bottom, (southwest end of the property) to a maximum height of 1150m along the ridgetops (east and north end of the property).

The Yukon has a sub-arctic continental climate. Summer temperatures can reach up to 35° C but the mean temperature is 10° C. Winter temperatures can be very cold reaching down to -55° C but with a mean winter temperature of -23°C.

**Photo 1**: Looking south along the length of the Bullseye Property. Note the White River to the right (west) and the snowcapped Kluane mountain range at the top (south). The unglaciated upper ridges contain mostly standing dead (burnt) forest while the glacial sediment-fill lowlands towards the White River contain thick moss mats with limited forest growth.

# FIGURE 2: GLACIAL LIMITS

## BULL'S EYE PROPERTY

545000 550000 555000 560000 565000

6950000 6945000 6940000 6935000 6930000 6925000 6920000 6915000 6910000

### Glacial Limts

**EPOCH**

- Late Pleistocene
- Middle Pleistocene
- UN GLACIATED
- Pliocene To Early Pleistocene

- Bull's Eye Property Outline
- CREEK
- WETLAND
- WATER BODY

N

1:100,000

Kilometers

0 0.8 1.6 2.4 3.2

DATUM: UTM ZN 7 NAD 83
NTS MAP SHEET: 115K, 115 J
CREATED BY: C. JONES
DATE: NOVEMBER 15, 2020

DONJEK RIVER

WHITE RIVER

GOLD CREST ZONE

WELLESLEY LAKE

## 5.0 PROPERTY DESCRIPTION

The Bullseye property is comprised of 142 contiguous quartz claims located in the Whitehorse Mining District (Figure 3). The claims stretch almost 10 km long and cover 29.7 square kilometers of land within NTS mapsheets 115K 08, 115J 05, and 115J 12. The majority of the property was staked in 2017, however 30 of the claims were staked in 2020 prior to the beginning of the work program.

The 142 'BE' claims are owned by both Luckystrike Resources Ltd. and Golden Sky Minerals Corp. Golden Sky Minerals is the new name of Luckystrike Resources, thus the property is 100%-owned by Golden Sky Minerals Corp.

A complete list of the claims and their statuses can be found in Appendix I.

## 6.0 PROPERTY HISTORY

The Bullseye property encompasses a large block of unexplored ground directly adjacent to two large claim groups that have been the subject significant surface exploration from 2013 to 2017. These claim groups include the Wels Gold property owned by K2 Gold Corp. and the Wells property owned by White Gold Corp. The Bullseye property was staked primarily based on the elevated gold values seen in regional stream sediment samples in conjunction with similar geology to K2 Gold's Wels Gold showing. Refer to Figure 4 showing neighboring gold properties, regional stream geochemistry, and historic minfiles.

<u>K2 Gold's Wels Property</u>

The Wels property is located directly south of the property and comprises 351 contiguous quartz claims covering an area of approximately 73.3 square kilometers. The property was staked in 2011 with ridge spur sampling outlining a gold anomaly. Follow-up prospecting in 2012–2013 retuned rock grab samples up to 149.5 g/t Au. A trenching program in 2014 intersected high grade gold mineralization with best intercepts of 9.15 g/t Au over 40.5m. The host rocks to the mineralization are a reduced granite, similar to the Tombstone Suite intrusions located in the Selwyn Basin. This style of mineralization is known as an intrusion-related gold system (IRGS) and describes several significant gold deposits in the Yukon and Alaska. Examples of these deposits include the 4M oz Dublin Gulch gold deposit in the Yukon and the 6M oz Fort Knox gold deposit in Alaska.

The Wels Gold showing represents a brand new IRGS gold discovery in the Yukon and was previously unrecognized in this part of the Yukon.

The first drilling commenced in 2015 and returned 0.76 g/t Au over 97.5m, including 3.11 g/t Au over 19.5m and 5.71 g/t Au over 9m with visible gold (K2 Gold Corp.). Continued drilling in 2017 returned 2.37 g/t Au over 28.5m, 5.08 g/t Au over 12.5m, and 0.28 g/t Au over 144m with visible

gold observed in 3 of the 10 drill holes (K2 Gold Corp). These drill intercepts are from the 'Saddle zone' which is located only 6 km due south of the newly discovered Gold Crest zone on the Bullseye property.

Aside from drilling, 2017 prospecting at K2's Wels property identified additional gold targets hosted in multiple different rock types thereby increasing the potential for a district-scale, robust mineralizing system. These discoveries include grab sample highlights of 28.2 g/t Au and 13.6 g/t Au hosted in gabbro and 1.93 g/t and 1.68 g/t Au hosted in quartzite.

White Gold Corp.'s Wells Property

White Gold Corp.'s Wells property straddles the eastern edge of the Bullseye property and consists of 245 contiguous quartz claims covering an area of 51.2 square kilometers. Limited exploration has been completed to date however a reconnaissance ridge and spur exploration program has outlined several gold–arsenic–antimony soil anomalies with Au values up to 1698 ppb (White Gold Corp.). This high-grade gold sample is located <1 km from the Bullseye property border. Refer to Figure 4 showing the location of the 1698 ppb soil sample in relation to the Bullseye property.

Goldstrike Resources Ltd.

In 2017 Goldstrike Resources Ltd. performed a 2-phase reconnaissance exploration program. Phase 1 consisted of reconnaissance ridge and spur soil sampling with sample spacing at 50- and 100-meter intervals. Phase 2 consisted of a detailed soil grid set up to cover anomalous Au-As-Sb values seen in soil samples with rock grab samples taken from hand excavated sample pits within the soil anomaly.

A total of 307 soil and 14 rock samples were acquired and sent for geochemical analysis during the 2017 program. The program was successful in delineating a strong gold - arsenic soil anomaly coined the Gold Crest zone. The zone consisted of a 200x250m gold-in-soil anomaly with values up to 215 ppb Au. The anomaly was open to the north and south and was found along a regionally mapped bedrock contact separating the Paleozoic basement schists (west) and the Triassic mafic plutonic rocks (east). Rock grab samples from hand excavated pits within the soil anomaly contained values up to 0.25 g/t Au.

In 2018 the property was spun out from Goldstrike Resources Ltd. to Luckystrike Resources Ltd., and in 2020 the company name changed to Golden Sky Minerals Corp.

548000 550000 552000 554000 556000 558000 560000 562000 564000

6936000 6934000 6932000 6930000 6928000

Ten Mile Creek

Ten Mile Creek

White River

BE 75 YF05375
BE 73 YF05373
BE 76 YF05376
BE 71 YF05371
BE 74 YF05374
BE 83 YF05383
BE 69 YF05369
BE 72 YF05372
BE 81 YF05381
BE 84 YF05384
BE 53 YF05353
BE 70 YF05370
BE 79 YF05379
BE 82 YF05382
BE 54 YF05354
BE 55 YF05355
BE 77 YF05377
BE 80 YF05380
BE 114 YF55584
BE 56 YF05356
BE 57 YF05357
BE 78 YF05378
BE 116 YF55586
BE 113 YF55583
BE 58 YF05358
BE 59 YF05359
BE 118 YF55588
BE 115 YF55585
BE 124 YF05504
BE 60 YF05360
BE 61 YF05361
BE 120 YF55590
BE 117 YF55587
BE 126 YF05506
BE 123 YF05503
BE 62 YF05362
BE 63 YF05363
BE 122 YF55592
BE 119 YF55589
BE 128 YF05508
BE 125 YF05505
BE 134 YF05514
BE 64 YF05364
BE 65 YF05365
BE 121 YF55591
BE 130 YF05510
BE 127 YF05507
BE 136 YF05516
BE 133 YF05513
BE 66 YF05366
BE 67 YF05367
BE 132 YF05512
BE 129 YF05509
BE 138 YF05518
BE 135 YF05515
BE 51 YF05351
BE 68 YF05368
BE 111 YF05499
BE 131 YF05511
BE 140 YF05520
BE 137 YF05517
BE 49 YF05349
BE 52 YF05352
BE 109 YF05497
BE 112 YF05500
BE 142 YF05522
BE 139 YF05519
BE 47 YF05347
BE 50 YF05350
BE 107 YF05495
BE 110 YF05498
BE 97 YF05397
BE 141 YF05521
BE 45 YF05345
BE 48 YF05348
BE 105 YF05405
BE 108 YF05496
BE 95 YF05395
BE 98 YF05398
BE 43 YF05343
BE 46 YF05346
BE 103 YF05403
BE 106 YF05406
BE 93 YF05393
BE 96 YF05396
BE 41 YF05341
BE 44 YF05344
BE 101 YF05401
BE 104 YF05404
BE 91 YF05391
BE 94 YF05394
BE 39 YF05339
BE 42 YF05342
BE 28 YF05328
BE 99 YF05399
BE 102 YF05402
BE 89 YF05389
BE 92 YF05392
BE 37 YF05337
BE 40 YF05340
BE 27 YF05327
BE 26 YF05326
BE 100 YF05400
BE 87 YF05387
BE 90 YF05390
BE 35 YF05335
BE 38 YF05338
BE 14 YF05314
BE 25 YF05325
BE 24 YF05324
BE 85 YF05385
BE 88 YF05388
BE 33 YF05333
BE 36 YF05336
BE 13 YF05313
BE 12 YF05312
BE 23 YF05323
BE 22 YF05322
BE 86 YF05386
BE 31 YF05331
BE 34 YF05334
BE 11 YF05311
BE 10 YF05310
BE 21 YF05321
BE 20 YF05320
BE 29 YF05329
BE 32 YF05332
BE 9 YF05309
BE 8 YF05308
BE 19 YF05319
BE 18 YF05318
BE 30 YF05330
BE 7 YF05307
BE 6 YF05306
BE 17 YF05317
BE 16 YF05316
BE 5 YF05305
BE 4 YF05304
BE 15 YF05315
BE 3 YF05303
BE 2 YF05302
BE 1 YF05301

WELLS 296 YF03876
WELLS 294 YF03874
WELLS 297 YF03877
WELLS 292 YF03872
WELLS 295 YF03875
WELLS 280 YF03860
WELLS 290 YF03870
WELLS 293 YF03873
WELLS 278 YF03858
WELLS 281 YF03861
WELLS 288 YF03868
WELLS 291 YF03871
WELLS 276 YF03856
WELLS 279 YF03859
WELLS 264 YF03844
WELLS 286 YF03866
WELLS 289 YF03869
WELLS 274 YF03854
WELLS 277 YF03857
WELLS 262 YF03842
WELLS 287 YF03867
WELLS 272 YF03852
WELLS 275 YF03855
WELLS 260 YF03840
WELLS 263 YF03843
WELLS 270 YF03850
WELLS 273 YF03853
WELLS 258 YF03838
WELLS 261 YF03841
WELLS 271 YF03851
WELLS 256 YF03836
WELLS 259 YF03839
WELLS 116 YE76126
WELLS 254 YF03834
WELLS 257 YF03837
WELLS 115 YE76125
WELLS 252 YF03832
WELLS 255 YF03835
WELLS 128 YE76138
WELLS 113 YE76123
WELLS 250 YF03830
WELLS 253 YF03833
WELLS 127 YE76137
WELLS 126 YE76136
WELLS 248 YF03828
WELLS 251 YF03831
WELLS 140 YE76150
WELLS 125 YE76135
WELLS 124 YE76134
WELLS 246 YF03826
WELLS 249 YF03829
WELLS 139 YE76149
WELLS 138 YE76148
WELLS 123 YE76133
WELLS 244 YF03824
WELLS 247 YF03827
WELLS 152 YE76162
WELLS 137 YE76147
WELLS 136 YE76146
WELLS 121 YE76131
WELLS 242 YF03822
WELLS 245 YF03825
WELLS 151 YE76161
WELLS 150 YE76160
WELLS 135 YE76145
WELLS 134 YE76144
WELLS 240 YF03820
WELLS 243 YF03823
WELLS 164 YE76174
WELLS 149 YE76159
WELLS 148 YE76158
WELLS 133 YE76143
WELLS 132 YE76142
WELLS 238 YF03818
WELLS 241 YF03821
WELLS 163 YE76173
WELLS 162 YE76172
WELLS 147 YE76157
WELLS 146 YE76156
WELLS 131 YE76141
WELLS 236 YF03816
WELLS 239 YF03819
WELLS 176 YE76186
WELLS 161 YE76171
WELLS 160 YE76170
WELLS 145 YE76155
WELLS 144 YE76154
WELLS 129 YE76139
WELLS 234 YF03814
WELLS 237 YF03817
WELLS 175 YE76185
WELLS 174 YE76184
WELLS 159 YE76169
WELLS 158 YE76168
WELLS 143 YE76153
WELLS 142 YE76152
WELLS 232 YF03812
WELLS 235 YF03815
WELLS 188 YE76198
WELLS 173 YE76183
WELLS 172 YE76182
WELLS 157 YE76167
WELLS 156 YE76166
WELLS 141 YE76151
WELLS 230 YF03810
WELLS 233 YF03813
WELLS 187 YE76197
WELLS 186 YE76196
WELLS 171 YE76181
WELLS 170 YE76180
WELLS 155 YE76165
WELLS 154 YE76164
WELLS 415 YF48735
WELLS 231 YF03811
WELLS 200 YE76210
WELLS 185 YE76195
WELLS 184 YE76194
WELLS 169 YE76179
WELLS 168 YE76178
WELLS 153 YE76163
WELLS 413 YF48733
WELLS 414 YF48734
WELLS 199 YE76209
WELLS 198 YE76208
WELLS 183 YE76193
WELLS 182 YE76192
WELLS 167 YE76177
WELLS 166 YE76176
WELLS 411 YF48731
WELLS 412 YF48732
WELLS 212 YE76222
WELLS 197 YE76207
WELLS 196 YE76206
WELLS 181 YE76191
WELLS 180 YE76190
WELLS 165 YE76175
WELLS 409 YF48729
WELLS 410 YF48730
WELLS 211 YE76221
WELLS 210 YE76220
WELLS 195 YE76205
WELLS 194 YE76204
WELLS 179 YE76189
WELLS 178 YE76188
WELLS 416 YF48736
WELLS 408 YF48728
WELLS 220 YE76230
WELLS 209 YE76219
WELLS 208 YE76218
WELLS 193 YE76203
WELLS 192 YE76202
WELLS 177 YE76187
WELLS 418 YF48738
WELLS 218 YE76228
WELLS 207 YE76217
WELLS 206 YE76216
WELLS 191 YE76201
WELLS 190 YE76200
WELLS 417 YF48737
WELLS 419 YF48739
WELLS 216 YE76226
WELLS 205 YE76215
WELLS 204 YE76214
WELLS 189 YE76199

WELLS 354 YE90886
WELLS 352 YE90884
WELLS 350 YE90882
WELLS 348 YE90880
WELLS 346 YE90878
WELLS 344F YE90876
WELLS 355 YE90887
WELLS 353 YE90885
WELLS 351 YE90883
WELLS 349 YE90881
WELLS 347 YE90879
WELLS 345 YE90877
WELLS 357F YE90889
WELLS 342 YE90874
WELLS 340 YE90872
WELLS 338 YE90870
WELLS 336 YE90868
WELLS 334 YE90866
WELLS 332 YE90864
WELLS 330F YE90862
WELLS 328F YE90860
WELLS 343 YE90875
WELLS 341 YE90873
WELLS 339 YE90871
WELLS 337 YE90869
WELLS 335 YE90867
WELLS 333 YE90865
WELLS 331 YE90863
WELLS 329 YE90861
WELLS 356F YE90888
WELLS 326 YE90858
WELLS 324 YE90856
WELLS 322 YE90854
WELLS 320 YE90852
WELLS 298 YF44198
WELLS 296 YF44196
WELLS 294 YF44194
WELLS 292 YF44192
WELLS 290 YF44190
WELLS 288 YF44188
WELLS 286 YF44186
WELLS 284 YF44184
WELLS 327 YE90859
WELLS 325 YE90857
WELLS 323 YE90855
WELLS 321 YE90853
WELLS 299 YF44199
WELLS 297 YF44197
WELLS 295 YF44195
WELLS 293 YF44193
WELLS 291 YF44191
WELLS 289 YF44189
WELLS 287 YF44187
WELLS 285 YF44185
WELLS 318 YE90850
WELLS 316 YE90848
WELLS 314 YE90846
WELLS 312 YE90844
WELLS 310 YE90842
WELLS 247 YF44147
WELLS 248 YF44148

# Bullseye Property

*Figure 3: Claim Location Map*

*Wellsley Lake area, Whitehorse Mining District*

*Golden Sky Minerals Corp.*

## Legend

Bullseye Property

Yukon Quartz Claims

N
W E
S

0 500 1,000 2,000 Meters

Date: November, 2020
Mapsheet: 115J05, 115J12, 115K08
Daturn: UTM NAD83 Zone 7

GOLDEN SKY MINERALS

www.GoldenSkyMinerals.com

# FIGURE 4: MINERAL OCCURENCES MAP

## BULLSEYE PROPERTY

545000 550000 555000 560000 565000 570000 575000

6935000 6930000 6925000 6920000

GOLDEN SKY MINERALS
BULLSEYE PROPERTY

WHITE GOLD CORP
WELS PROPERTY

K2 GOLD CORP
WELS PROPERTY

WHITE RIVER

DONJEK RIVER

WELLESLEY
LAKE

MOG

WELS NICKEL

WELS GOLD

*approximate location of
1698 ppb Au soil sample*

*2015 drilling returned 97.5m @ 0.76 g/t Au,
including 3.11 g/t Au over 19.5m and
5.71 g/t Au over 9 m with visible gold.*

LEGEND

Regional Stream Geochemistry (Au ppb)

- 0.5 - 1.0
- 1.1 - 2.0
- 2.1 - 4.0
- 4.1 - 7.0
- 7.1 - 14.0

MINFILE

BULLSEYE PROPERTY
K2 GOLD CORP - WELLS PROPERTY
WHITE GOLD CORP - WELLS PROPERTY
FIRST NATION LAND
CONTOUR
CREEK
WATER BODY
SWAMP

N

1:75,000

Kilometers

0 1 2 3 4

DATUM: UTM ZN 7 NAD 83
NTS MAP SHEET: 115K, 115 J
CREATED BY: C. JONES
DATE: NOVEMBER 15, 2020

## 7.0 GEOLOGY

### 7.1 Regional Geology

The Bullseye property is located in an area of the Yukon that has received relatively less geological mapping and academic study. This area is underlain by the Yukon Tanana Terrane (YTT), and is generally to the south and east of a large block of displaced North American Basin Terrain (Selwyn Basin) with Eikland Mountain Formation (Slide Mountain Terrane) over-thrust on Selwyn basin lithologies and Yukon Tanana Terrane (Murphy, 2007; Doherty, 2016). Locally these older terranes are overlain by Upper Cretaceous volcanic rocks of the Donjek Formation Groups.

The Bullseye property is underlain by Devonian to Mississippian siliceous phyllite and schist of the White River Formation that is extensively intruded by Triassic gabbro of the Snag Creek Suite. The far northwest end of the property is underlain by Ordovician to Devonian schists and quartzites of the Scottie Creek Formation.

The rock sub types of the White Formation, Snag Creek Suite and Scottie Creek Formation are described in detail below by the Yukon Geological Survey (YGS). These descriptions were taken from the 2017 Yukon Bedrock Geology legend.

**WHITE RIVER (391-345 Ma)**: black carbonaceous sand siliceous phyllite and schist (1), and intercalated felsic to mafic metavolcanic rocks (2); extensively intruded by gabbro of the Snag Creek suite (Tgs).

1. Carbonaceous muscovite-quartz phyllite, grey psammitic schist, and quartzite - DMWs
2. Felsic to mafic metavolcanic schist; quartz and/or feldspar-augen felsic schist; mafic schist locally amygdaloidal – DMWv

**SNAG CREEK SUITE (232-228 Ma):** massive, medium-grained hornblende gabbro and pyroxenite sills

**SCOTTIE CREEK (488-380 Ma):** quartzose psammite, pelitic schist and minor marble (1); locally migmatized (2); north of Beaver Creek

1. grey to white quartzite, micaceous quartzite and psammitic quartz-muscovite-biotite ± garnet schist; local metaconglomerate - ODs
2. layered paragneiss with mica-rich melanosome and garnet-bearing quartzofeldspathic leucosome - ODsmm

Refer to Figure 5 showing the bedrock geology for the Bullseye claims and surrounding area.

A regional-scale, coarse detail, magnetic survey was done in 2000–2001 by the Geological Survey of Canada (GSC). The TMI clearly highlights the contacts between the northeast-trending regionally mapped White River Formation and the Cretaceous age Donjek volcanics (Figure 6). The Bullseye property contains subtle circular magnetic lows throughout the property similar to

what is observed at K2 Gold's Wels property. The magnetic lows are hypothesized to represent underlying granitic plutons like the ones that host the high-grade gold encountered at the Wels Gold property.

### 7.2 Property Geology and Mineralization

The property geology is not well understood as to date, only first pass reconnaissance ridge and spur soil sampling has been completed across the majority of the property with a few rock grab samples taken along the sample lines. Furthermore, the south western part of the property contains a thick blanket of till hampering the geological interpretation.

The Bullseye property is underlain by Devonian to Mississippian siliceous phyllite and schist of the White River Formation that are extensively intruded by Triassic gabbro of the Snag Creek suite. The Gold Crest zone (which has received the majority of exploration to date) is hosted along this regionally mapped contact between the older schist of the White River Formation and the much younger mafic intrusion of the Snag Creek Suite. This regional scale mapped contact runs NE-SW and extends the length of the property. Refer to Figure 5 for location of the Gold Crest showing in relation to the regionally mapped bedrock contact.

The trenching and surrounding rock grab samples excavated from hand dug pits in felsenmeer within the Gold Crest zone contain auriferous sheared and brecciated quartz-sericite schist as well as leucogabbro and intermediate to mafic strongly altered schists. The mineralization seen at the Gold Crest zone is believed to be hosted along a fault surface at the bedrock contact. Evidence for this faulting is seen in strongly sheared and brecciated grab samples within the zone and further supported by a linear north – south deeply incised canyon parallel to the soil anomaly, postulated to be a cross-cutting structure.

# FIGURE 5: BEDROCK GEOLOGY

## BULLSEYE PROPERTY

**LEGEND**

- Bullseye Property
- Other Exploration Property
- MINERAL OCCURENCE

**FAULT TYPE**

- normal
- strike slip
- thrust

N

1:75,000

Kilometers

0 1 2 3 4

DATUM: UTM ZN 7 NAD 83
NTS MAP SHEET: 115K, 115 J
CREATED BY: C. JONES
DATE: NOVEMBER 15, 2020

545000 550000 555000 560000 565000 570000 575000

6935000 6930000 6925000 6920000

LDMB
LKP
ODS
TrG
DMW
uKC

WHITE RIVER
DONJEK RIVER
WELLESLEY LAKE

BULLSEYE
DMW
GOLD CREST ZONE

WHITE GOLD CORP
WELLS PROPERTY

k2 GOLD CORP
WELLS PROPERTY

MOG
WELS NICKEL
WELS GOLD

## CRETACEOUS

### uKC

**CARMACKS:** *volcanic succession dominated by basic volcanic strata (1), but including intermediate (2) and locally felsic volcanic rocks (3) dominantly at the base of the succession, and locally, basal clastic strata (4); rare gabbro (5) (ca. 72-68 Ma)*
***1,*** *augite olivine basalt and breccia; hornblende feldspar porphyry andesite and dacite flows; vesicular, augite phyric andesite and trachyte; minor sandy tuff, granite boulder conglomerate, agglomerate and associated epiclastic rocks* ***(Carmacks Gp, Little Ridge Volcanics, Casino Volcanics)*** *- uKCv*
***2,*** *andesite, porphyry* - uKCa
***3,*** *acid vitric crystal tuff, lapilli tuff and welded tuff including feeder plugs and necks; felsic volcanic flow rocks and quartz feldspar porphyries; green and purple massive tuff-breccia with feldspar phyric fragments* ***(Carmacks Gp, Donjek Volcanics, some rocks formerly mapped as Mt. Nansen Gp;*** *the felsic part of the Carmacks Gp is difficult to distinguish from similar Tertiary and mid-Cretaceous (Mt. Nansen) felsic volcanic strata)* - uKCt
***4,*** *medium-bedded, poorly sorted, coarse to fine-grained sandstone, pebble conglomerate, shale, tuff, and coal; massive to thick-bedded locally derived granite or quartzite pebble to boulder conglomerate* ***(Carmacks Gp; Colorado Creek Conglomerate)*** *- uKCs*
***5,*** *gabbro and monzonite bodies near Carmacks* - uKCg

## TRIASSIC

### LKP

**PROSPECTOR MOUNTAIN SUITE (72-68 Ma):** *grey, fine to coarse-grained, massive, granitic rocks of felsic (g) intermediate (g) rarely mafic (d) composition and related felsic dikes (f)*
***d,*** *coarsely crystalline gabbro and diorite*
***g,*** *hornblende-biotite granodiorite, hornblende diorite, quartz diorite* ***(Wheaton Valley granodiorite; Katrina Creek suite)***
***q,*** *quartz monzonite, biotite quartz-rich granite; porphyritic alaskite and granite with plagioclase and quartz-eye phenocrysts; biotite and hornblende quartz monzodiorite, granite, and leucocratic granodiorite with local alkali feldspar phenocrysts* ***(Prospector Mountain Suite, Carcross pluton)***
***y,*** *syenite*
***f,*** *quartz-feldspar porphyry*

### TrG

**GALENA SUITE:** *massive, medium-grained hornblende diorite and gabbro sills; massive chloritic and locally serpentinized greenstone (diorite, gabbro, and altered equivalents) sills; minor occurrences of possible mid to late Paleozoic age*

## DEVONIAN TO MISSISSIPPIAN

### DMW

**WHITE RIVER:** *black carbonaceous and siliceous phyllite and schist (1), and interca-lated felsic to mafic metavolcanic rocks (2); extensively intruded by gabbro of the Snag Creek suite (TGa)* ***(correlative with Earn Gp northeast of Tintina fault (?) and Totatlanika schist in eastern Alaska)***
***1,*** *carbonaceous muscovite-quartz phyllite, grey psammitic schist, and quartzite* - DMws
***2,*** *felsic to mafic metavolcanic schist; quartz and/or feldspar-augen felsic schist; mafic schist locally amygdaloidal* - DMwv

### LDMB

**MOUNT BAKER SUITE (ca. 365 Ma):** *metaplutonic suite dominated by orthogneiss of intermediate (g) to mafic (y) compositions*
***g,*** *strongly foliated to gneissic granodiorite, diorite and monzogranite*
***y,*** *strongly foliated to gneissic diorite, gabbro and minor pyroxenite*

## UPPER DEVONIAN TO LOWER PERMIAN

### CPSM

**SLIDE MOUNTAIN:** *oceanic assemblage of chert, argillite, minor sandstone and conglomerate (1,3), basalt (2), serpentinite (4), gabbro (5), rare felsic metavolcanic rocks (6)*
***1,*** *variably deformed, dark grey to black carbonaceous phyllite, chert and argillite; grey, green and white chert; minor chert sandstone and pebble conglomerate; locally feldspar grit; rare limestone, dolostone; mafic metavolcanic rocks* ***(Fortin Creek gp)*** *- CPSms*
***2,*** *dark green to black basalt, greenstone, locally pillowed; hyaloclastite; generally weakly deformed and metamorphosed* ***(Campbell Range fm)*** *- CPSmv*
***3,*** *grey, red and green chert and argillite; local dolostone, sandstone* ***(Campbell Range fm)*** *- CPSmc*
***4,*** *brown weathering, dark green to black, variably serpentinized ultramafic rocks; metapyroxenite, dunite; harzburgite* - CPSum
***5,*** *medium to coarse-grained gabbro; quartz monzonite; locally rodingite* - CPgbSM
***6,*** *muscovite-quartz phyllite, augen schist* ***(felsic metavolcanic rocks in Fortin Creek gp)*** *- CPSmf*
***7,*** *leucogabbro, gabbro, diabase; rare plagiogranite* - CPlgSM

### TrG

**GALENA SUITE:** *massive, medium-grained hornblende diorite and gabbro sills; massive chloritic and locally serpentinized greenstone (diorite, gabbro, and altered equivalents) sills; minor occurrences of possible mid to late Paleozoic age*

## ORDOVICIAN TO DEVONIAN

### ODS

**SCOTTIE CREEK:** *quartzose psammite, pelitic schist and minor marble (1); locally migmatized (2); north of Beaver Creek* ***(correlative with Lake George assemblage in east-central Alaska)***
***1,*** *grey to white quartzite, micaceous quartzite and psammitic quartz-muscovite-biotite ± garnet schist; local metaconglomerate* - ODS
***2,*** *layered paragneiss with mica-rich melanosome and garnet-bearing quartzofeld-spathic leucosome* - ODSmm

# FIGURE 6: REGIONAL MAGNETICS (TMI)

## BULLSEYE PROPERTY

**LEGEND**

- Bullseye Property
- Other Exploration Property
- Bedrock Geology Contacts
- Mineral Occurence

**FAULT TYPE**

- normal
- strike slip
- thrust

N

1:75,000

Kilometers

0 1 2 3 4

DATUM: UTM ZN 7 NAD 83
NTS MAP SHEET: 115K, 115 J
CREATED BY: C. JONES
DATE: NOVEMBER 15, 2020

545000 550000 555000 560000 565000 570000 575000

6935000 6930000 6925000 6920000

LDMB
ODS
TrG
LKP
WHITE RIVER
DONJEK RIVER
MOG
BULLSEYE
DMW
GOLD CREST ZONE
WHITE GOLD CORP
WELLS PROPERTY
uKC
k2 GOLD CORP
WELS PROPERTY
WELS GOLD
WELS NICKEL
WELLESLEY
LAKE

## 8.0 2020 MECHANICAL TRENCHING PROGRAM

### 8.1 Summary of Trenching Program

The 2020 mechanical trenching program consisted of 1 trench totalling 134m. Work on the trench was performed from July 8th, 2020 to July 12th, 2020. The trench was designed to cover the highest gold-in-soil values from the 2017 survey at the Gold Crest zone while taking into account budgetary constraints. See Appendix II for sample descriptions and Appendix V for the full assay certificates.

### 8.2 Sampling Methodology

A Candig CD21 mini-excavator was used to trench. The Candig was limited to excavating to a depth of approximately 2 meters and a width of approximately 0.5 m. The trench was sampled at 2m intervals. If bedrock and/or subcrop was not encountered, a representative grab sample of soil and rock fragments were taken along the trench bottom over the sample interval. For bedrock samples, a large continuous representative chip sample across the outcrop was taken. Typically, the material sampled was fairly competent fractured bedrock.

Trench samples were described and photographed in situ prior to sealing in labelled sample bags with a lab tag. The samples were in camp before transport to Druid Exploration's secure office in Dawson City. They were then transported by truck to Bureau Veritas' prep lab in Whitehorse. Representative trench samples were preferentially selected for future reference and stored at Druid Exploration's office in Dawson City.

The trench start and end locations were recorded using hand-held GPS units (accuracy 1-10 m) and flagged with biodegradable flagging tape. All Individual sample intervals are mapped and the following information is recorded on all-weather paper: trench ID, sample ID, easting, northing, type of sample (outcrop, subcrop, float), azimuth, to, from, width, depth, and a brief description.

The trench was reclaimed after sampling was completed.

### 8.3 Sample Preparation, Analysis, and QA/QC

Trench samples were crushed and pulverized in the Bureau Veritas laboratory in Whitehorse, YT and the sample pulps were then analyzed by Bureau Veritas in Vancouver, BC. The samples were first dried at 60 degrees and then up to 1 kg were crushed to 70% passing a 10 mesh (2mm). A split of 250 g is then further pulverized to 85% passing 200 mesh (75um). The remaining coarse reject portions of the sample remains in storage at the Bureau Veritas storage facility in Vancouver, BC and are disposed after 3 months from the date of analytical completion.

Th samples received both Aqua Regia ICP-MS, 36 element analytical analysis (AQ200) and fire assay ICP–ES analytical analysis (FA350–Au) for gold only. The Aqua Regia ICP-MS (AQ200)

analysis involves a 0.5 g split leached in hot (95°C) Aqua Regia solution with an inductively-coupled plasma mass spectroscopy (ICP-MS) finish. The fire assay ICP-ES (FA350-Au) analysis involves a 50 gram split being fully decomposed in a 3B lead-collection fire assay fusion procedure with inductively-coupled plasma [atomic] emission spectroscopy (ICP-ES) finish. The 3B lead-collection fire assay is used because refractory, massive sulphide and graphitic samples can limit Au solubility potentially yielding lower gold values in the standard Aqua Regia ICP-MS procedure (AQ200).

Standards and blanks were inserted into the sample stream by Druid Exploration personnel every 25 samples. Overall, the precision of the assay data was considered to be satisfactory.

### 8.4 Trenching Results

The 134-metre-long discovery trench (BETR-20-01) was completed in the center of the Gold Crest zone. It was successful in intersecting significant gold mineralization, yielding an intercept of 0.69 g/t Au over 78 meters (Table 1). Results from the trench indicate the bedrock source of the geochemical anomaly was not fully exposed. The easternmost trench sample assayed 0.39 g/t Au over 2m (0.0m to 2.0m).

**Table 1:** Gold intercepts from trench BETR-20-01.

| Trench ID | From (m) | To (m) | Interval (m) | Au (g/t) |
|---|---|---|---|---|
| BETR-20-01 | 0.0 | 78.0 | 78.0 | 0.69 |
| *including* | | | | |
| BETR-20-01 | 12.0 | 56.0 | 44.0 | 1.03 |
| *including* | | | | |
| BETR-20-01 | 14.0 | 38.0 | 24.0 | 1.42 |

Figure 7 displays gold geochemistry at the Gold Crest zone. For reference, sample 1878401 (0.0m to 2.0m) is located at the easternmost end of the trench, and sample numbers run consecutively to the west, with the westernmost sample (132.0m to 134.0m) being 1878471 (excluding standards and blanks).

Starting from the east, the trench began in an oxidized quartz-sericite schist with quartz stockwork. This unit hosts varying amount of quartz veining and quartz stockwork, often with pyrite pseudomorphs, limonitic pyrite or (rarely) fresh pyrite (Photo 2). The unit was also typically silicified throughout, with zones of more intense silicification and quartz stockwork corresponding to increased gold values (Photo 3).

Carbonate stringers were present from 6.0m to 24.0m. Regional geology indicates the trench is located on a gabbro-schist contact. Small zones of sheared chloritic rock were noted from 8.0m to 12.0m. This is likely some expression of the mapped gabbro unit. Some cobbles of more typical gabbro or leucogabbro were also noted in this area (Photo 4). Nickel and cobalt values are

elevated are elevated from 0.0m to 30.0m which aid in marking the diffuse and sheared gabbro contact.




**Photo 2:** Sample 1878407, 12.0m – 14.0m: Oxidized quartz-sericite schist with limonitic pyrite (black spots), assaying 0.68 g/t Au over 2.0m.

**Photo 3:** Sample 1878416, 30.0m – 32.0m: Oxidized and silicified quartz-sericite schist with abundant quartz stockwork, assaying 1.17 g/t Au over 2.0m.

**Photo 4:** Sample 1878405, 8.0m – 10.0m: Oxidized and silicified quartz-sericite schist (center), sheared chloritic schist with quartz-carbonate stringers (left), and leucogabbro (right).

At 58.0m the lithology graded to a less quartz-rich sericite schist. Gold values decreased to a 100-300 ppb Au range, then drop below 100 ppb Au at 78.0. A small zone of elevated gold values (~100 ppb Au) is present at 86.0m to 92.0m and corresponds to increased quartz content in the schist (described as a 'grit' in this zone).

At 100.0m, pervasive carbonate alteration in the host rock occurs and continues more or less to the end of the trench. Lithology grades to more of a limey schist around 106.0m. This unit displayed some pyrite mineralization but did not yield any significant gold values.

Overall the most significant pathfinder element for gold is arsenic. A zone of elevated selenium (up to 7.5 ppb Se) corresponds to the highest gold values, from 16.0m to 56.0m. Some sporadic silver values occur from 26.0m to 38.0m with the highest value being 28.6 ppm Ag. This area also displayed increased antimony, with the highest value being 24.4 ppb Sb. Correlations to gold are displayed and discussed in Section 10.0, Table 2.

553000 553500 554000 554500

6929000

6928500




*Additional contact-related geochemical anomalies require follow-up*

*500m open-ended gold-in-soil anomaly, confirmed by trenching and hand-dug pits*

54Wv

*Permafrost and glacial material*

*Glaciated terrain*

2020 trench
See bottom-left

=Gs

*Government-mapped schist - gabbro geological contact*

0 125 250 500 Meters




# Bullseye Property

*Figure 7: Surfical Gold Results at the Gold Crest Zone*

*Golden Sky Minerals Corp.*

## Legend

**2020 Trench**

**Au (g/t)**

- <2 - 0.1
- 0.1 - 0.5
- 0.5 - 1.0
- 1.0 - 2.0
- 2.0 - 2.41

**2017-2020 rock grabs**

**Au (g/t)**

- 0 - 0.1
- 0.1 - 0.5
- 0.5 - 0.936

**2017-2020 soil samples**

**Au (ppb)**

- 0.25 - 10.0
- 10.1 - 20.0
- 20.1 - 50.0
- 50.1 - 100.0
- 100.1 - 889.1

Date: August, 2020
Mapsheet: 115J05
Datum: UTM NAD83 Zone 7

GOLDEN SKY MINERALS

www.GoldenSkyMinerals.com

## 9.0 2020 PROSPECTING AND SOIL SAMPLING PROGRAM

### 9.1 Summary of Prospecting and Soil Sampling Program

Prospecting and soil sampling at Bullseye was conducted by 4 men between July 1st 2020 and July 11th, 2020. The crew collected 49 rock samples and 562 soil samples. The goal of the program was to expand upon known anomalies (particularly the Gold Crest zone) and to perform reconnaissance ridge-and-spur sampling in unexplored areas. Appendices III and IV contain rock and soil sample descriptions while Appendices VI and VII contain the assay certificates.

### 9.2 Sampling Methodology

Rock samples were taken based on mineralogy, structure and lithology. Due to the lack of outcrop in most areas of the property, some samples were taken by digging small pits and sampling the felsenmeer. Samples were placed inside labeled plastic poly bags with the corresponding sample tag. Sample descriptions were recorded in a field notebook and the location recorded by GPS unit. Sample locations were marked with flagging tape labeled with the sample number.

Soil sample locations were based on three methodologies:
- Typical ridge and spur lines in unexplored areas;
- Follow-up lines paralleling known geochemical anomalies;
- Grid pattern around a known anomaly

Samples were generally taken at 50m spacings. Samplers used Dutch augurs to collect an adequate soil sample, preferably from the 'C' horizon, and placed them in a Kraft paper bag. Locations were marked with a handheld GPS and flagging tape labeled with the sample number was left at the site. Sample conditions, environment and attributes were recorded in a field notebook. The GPS units were downloaded daily for plotting in ArcGIS. Soil samples were hung up to dry, then packed and shipped to the lab.

### 9.3 Sample Preparation, Analysis, and QA/QC

Rock samples received the same assay treatment as the trench samples, outlined in section 8.3.

The soil samples were dried at 60° C and sieved to -80 mesh (<177 microns). A 15.0 gram sub-sample was digested in hot (95° C) Aqua Regia (HCl-HNO3-H2O). Following this, the samples were analysed by inductively-coupled plasma mass spectrometry (ICP-MS) techniques. Bureau Veritas' AQ201 package was used, giving analyses of 36 elements.

## 9.4 Prospecting and Soil Sampling Results

The prospecting and soil sampling program at Bullseye was successful in extending the Gold Crest zone anomaly but generally unsuccessful in defining a trend at the Marksmen zone. It is important to consider the reliability of soil samples beyond the glacial limits (see Figure 2). A large number soil samples below the NE-trending ridgeline and slope spanning the property were noted to have glacial till content or were affected by permafrost. Figures 8 and 9 display sample locations while Figures 10 to 14 display geochemistry. Refer to Figures 8 and 10 for zone locations.

<u>Gold Crest</u>

The 2020 soil sampling program expanded upon a small grid completed at Gold Crest in 2017. The program was successful in further delineating the Gold Crest trend with values up to 216 ppb Au in soil. While gold values appear to follow the NE-trending schist-gabbro contact, another roughly north-south trend is visible, possibly related to a cross-cutting structure (see Figure 15). As mentioned above, inferences beyond the ridgeline are difficult due to glacial till and permafrost. Sample reliability on the hump NW of the main Gold Crest zone is also questionable for these same reasons. Gold correlates best with As-Ag-Sb, and to a lesser extent Pb-Zn-Se. A series of lines to the northeast of the main zone along the schist-gabbro contact (above Dovetail) have extended the anomaly to 2km strike length. Samples here reach 31 ppb Au (see Figure 16).

A series of hand-dug pits were completed around Gold Crest to confirm the bedrock source along strike of the trench. One sample from a pit 100m north of the trench yielded 0.18 g/t Au, while a sample from a pit 100m south of the trenched yielded 0.94 g/t Au (Photo 5).

**Photo 5**: Pit sample 1878264 – limonitic quartz stockwork in schist with minor pyrite assayed 0.94 g/t Au

Windage

The Windage zone is an area of anomalous soil samples on the ridge above (ESE) Gold Crest. Anomalous gold values span a 250m long area and reach up to 31 ppb Au. Antimony, arsenic, silver, and lead are also elevated in this area and form a much broader anomaly. No rock samples were taken in this area. Sample quality was typically good and noted to be reflective of bedrock.

Marksmen

The Marksmen zone is an isolated rounded ridge covering approximately 800x600m. The grid at Marksmen was designed to follow-up on a number of isolated anomalous soil samples on a reconnaissance line completed in 2017, with values up to 135 ppb Au. Pits were dug at these sample sites and additional soil and rock samples taken. This investigation revealed that the source material for the 2017 soil samples was generally glacial material. Gold-in-soil values were found to be not repeatable. Bedrock exposure (schist) was found on the western side of the ridge; however, samples did not yield any significant assay values.

Dovetail

The Dovetail zone is a series of small ridges north of the Gold Crest zone and down the ridge line from the NE extension of Gold Crest (visible in Figure 16). This zone was considered visually prospective due to intense stockwork observed in chlorite and sericite schist. Unfortunately, no significant results were returned from soil or rock samples in this area.

Ironsight

The Ironsight zone is a steeply incised creek valley south of Gold Crest. Four samples of gabbroic rock were taken from this area but did not return significant values. One soil sample taken from the area (ID 1321055) returned a value of 889 ppb Au but was noted to be glacial in origin and did not have any other elevated elements.

# Bullseye Property

*Figure 8: 2020 Sample Location Map - Property-wide*

*Wellsley Lake area, Whitehorse Mining District*

*Golden Sky Minerals Corp.*

## Legend

- 2020 rock samples
- 2020 trench samples
- 2020 soil samples
- Bullseye Property

N W E S

0 250 500 1,000 Meters

Date: November, 2020
Mapsheet: 115J05, 115J12, 115K08
Datum: UTM NAD83 Zone 7

www.GoldenSkyMinerals.com

Dovetail

Marksmen

Gold Crest

Windage

Ironsight

1878251 - 1878253
1878201

From west to east
1321201 - 1321217

From west to east
1320841 - 1320857

From west to east
1321018 - 1321031

From west to east
1321301 - 1321317

1878254

1878302

From east to west
1321001 - 1321017

From east to west
1321318 - 1321322

1878318
1878320
1878319

1878316
1878317
1878321
1878260
1878262

1878261

1878315

*See Figure 9 for Gold Crest area sample locations*

552500 553000 553500 554000 554500 555000

6929500 6929000 6928500 6928000

# Bullseye Property

*Figure 9: 2020 Sample Location Map - Gold Crest area*

*Wellsley Lake area, Whitehorse Mining District*

*Golden Sky Minerals Corp.*

## Legend

- 2020 rock samples
- 2020 trench samples
- 2020 soil samples
- Bullseye Property

N W E S

0 100 200 400 Meters

Date: November, 2020
Mapsheet: 115J05, 115J12, 115K08
Daturn: UTM NAD83 Zone 7

GOLDEN SKY MINERALS

www.GoldenSkyMinerals.com

# Bullseye Property

*Figure 10: Surface Geochemistry - Gold - Property-wide*

*Golden Sky Minerals Corp.*

## Legend

**2017-2020 rock grabs**

**Au (g/t)**

- 0 - 0.1
- 0.1 - 0.5
- 0.5 - 0.936

**2017-2020 soil samples**

**Au (ppb)**

- 0.25 - 10.0
- 10.1 - 20.0
- 20.1 - 50.0
- 50.1 - 100.1
- 100.1 - 889.1
- Bullseye Property

N
W E
S

0 375 750 1,500 Meters

Date: November, 2020
Mapsheet: 115J05, 115J12, 115K08
Datum: UTM NAD83 Zone 7

GOLDEN SKY MINERALS

www.GoldenSkyMinerals.com

*Dovetail*

*Gold Crest*

*Marksmen*

*Windage*

*Ironsight*

*See Figures 11 to 14 for Gold Crest area geochemistry*

550000 551000 552000 553000 554000 555000 556000 557000 558000 559000 560000 561000 562000 563000

6936000 6935000 6934000 6933000 6932000 6931000 6930000 6929000 6928000 6927000

552500 553000 553500 554000 554500 555000 555500 556000 556500

6930000 6929500 6929000 6928500 6928000

# Bullseye Property

*Figure 11: Surface Geochemistry - Gold - Gold Crest area*

*Golden Sky Minerals Corp.*

## Legend

**2020 Trench**

**Au (g/t)**

- <2 - 0.1
- 0.1 - 0.5
- 0.5 - 1.0
- 1.0 - 2.0
- 2.0 - 2.41

**2017-2020 rock grabs**

**Au (g/t)**

- 0 - 0.1
- 0.1 - 0.5
- 0.5 - 0.936

**2017-2020 soil samples**

**Au (ppb)**

- 0.25 - 10.0
- 10.1 - 20.0
- 20.1 - 50.0
- 50.1 - 100.0
- 100.1 - 889.1

Schist-gabbro contact

Bullseye Property

N W E S

0 125 250 500 Meters

Date: November, 2020
Mapsheet: 115J05, 115J12, 115K08
Datum: UTM NAD83 Zone 7

*Regional geological contact*
*Schist (NW) - Gabbro (SE)*

GOLDEN SKY MINERALS

www.GoldenSkyMinerals.com

552500 553000 553500 554000 554500 555000 555500 556000 556500

6930000 6929500 6929000 6928500 6928000

# Bullseye Property

*Figure 12: Surface Geochemistry - Silver - Gold Crest area*

*Golden Sky Minerals Corp.*

**Legend**

**2020 trench samples**

**Ag (ppm)**

- 0.050000 - 0.500000
- 0.500001 - 1.000000
- 1.000001 - 5.000000
- 5.000001 - 15.000000
- 15.000001 - 28.600000

**2017-2020 rock samples**

**Ag (ppm)**

- 0.000000 - 0.500000
- 0.500001 - 1.000000
- 1.000001 - 2.300000

**2017-2020 soil samples**

**Ag (ppm)**

- 0.050000 - 0.200000
- 0.200001 - 0.700000
- 0.700001 - 1.500000
- 1.500001 - 2.600000
- 2.600001 - 4.500000

Schist-gabbro contact

Bullseye Property

N W E S

0 125 250 500 Meters

Date: November, 2020
Mapsheet: 115J05, 115J12, 115K08
Datum: UTM NAD83 Zone 7

*Regional geological contact*
*Schist (NW) - Gabbro (SE)*

GOLDEN SKY MINERALS

www.GoldenSkyMinerals.com

552500 553000 553500 554000 554500 555000 555500 556000 556500

6930000 6929500 6929000 6928500 6928000

# Bullseye Property

*Figure 13: Surface Geochemistry - Arsenic - Gold Crest area*

*Golden Sky Minerals Corp.*

## Legend

**2020 trench samples**

**As (ppm)**

- 2.900000 - 25.000000
- 25.000001 - 100.000000
- 100.000001 - 1000.000000
- 1000.000001 - 5000.000000
- 5000.000001 - 10000.100000

**2017-2020 rock samples**

**As (ppm)**

- 0.000000 - 25.000000
- 25.000001 - 100.000000
- 100.000001 - 1000.000000
- 1000.000001 - 1354.300000

**2017-2020 soil samples**

**As (ppm)**

- 1.100000 - 26.300000
- 26.300001 - 95.800000
- 95.800001 - 218.000000
- 218.000001 - 373.700000
- 373.700001 - 593.400000
- Schist-gabbro contact
- Bullseye Property

N W E S

0 125 250 500 Meters

Date: November, 2020
Mapsheet: 115J05, 115J12, 115K08
Datum: UTM NAD83 Zone 7

*Regional geological contact*
*Schist (NW) - Gabbro (SE)*

GOLDEN SKY MINERALS

www.GoldenSkyMinerals.com

552500 553000 553500 554000 554500 555000 555500 556000 556500

6930000 6929500 6929000 6928500 6928000

# Bullseye Property

*Figure 14: Surface Geochemistry - Antimony - Gold Crest area*

*Golden Sky Minerals Corp.*

## Legend

**2020 trench samples**

**Sb (ppm)**

- 0.050000 - 1.000000
- 1.000001 - 2.500000
- 2.500001 - 5.000000
- 5.000001 - 10.000000
- 10.000001 - 25.000000

**2017-2020 rock samples**

**Sb (ppm)**

- 0.000000 - 1.000000
- 1.000001 - 2.500000
- 2.500001 - 5.000000
- 5.000001 - 10.000000
- 10.000001 - 26.600000

**2017-2020 soil samples**

**Sb (ppm)**

- 0.200000 - 1.200000
- 1.200001 - 3.200000
- 3.200001 - 6.600000
- 6.600001 - 14.300000
- 14.300001 - 23.100000
- Schist-gabbro contact
- Bullseye Property

N W E S

0 125 250 500 Meters

Date: November, 2020
Mapsheet: 115J05, 115J12, 115K08
Datum: UTM NAD83 Zone 7

*Regional geological contact*
*Schist (NW) - Gabbro (SE)*

GOLDEN SKY MINERALS

www.GoldenSkyMinerals.com




**Figure 15:** Annotate drone photo of the Gold Crest zone looking southeast.




**Figure 16:** Annotate drone photo of the Gold Crest trend looking northeast.

## 10.0 DISCUSSION

Gold mineralization at the Gold Crest zone appears to be related to the sheared gabbro-schist contact and a potential cross-cutting structure. Trenching shows a correlation of gold to As-Ag-Sb-Se (Table 2). While lead and bismuth appear to show a positive correlation to gold, values are fairly low when objectively looking through the assays. Correlation to gold in the full set of soil samples was found to be mostly unreliable due to the large number of soil samples taken in glaciated areas. Gold mineralization in the trench and grab samples is associated with sheared sericite and chlorite schist with minor leucogabbro gabbro, quartz stockwork, silicification, and minor limonitic and fresh pyrite. The percentage of quartz in samples appears to be one of the most important contributing factors to gold content.

The bulk of mineralization at K2 Gold Corp.'s Wels property is hosted in a Mid Cretaceous (101.4 Ma) granite with a pathfinder signature of Ag-As-Sb +/- Bi (Doherty, 2016). Very little pyrite has been noted. As no granite was ever mapped on the property by government surveys, mineralization was initially thought to be epithermal in origin. However, further exploration (trenching and drilling) revealed a host of strongly weathered granite. Mineralization was then theorized to be reduced-intrusion related.

No felsic intrusive rock has been identified on the Bullseye property. The granite units mapped on the Wels property are roughly 5km away. Mineralization at Gold Crest is not likely to be directly related to these units, however they may extend towards Bullseye at depth. There is also potential for a separate intrusive body to be located somewhere beneath the glacial cover on the Bullseye property. This is supported by the circular magnetic lows on the regional magnetic map (Figure 6) but would require more detailed, property-scale geophysical surveys to investigate.

**Table 2:** Surface sample correlation to gold

| | Trenching (67 samples)* | | Soil samples (868 samples)** | |
|---|---|---|---|---|
| **Rank** | **Element** | **Correlation** | **Element** | **Correlation** |
| | Au | 1 | Au | 1 |
| *1* | As | 0.94 | As | 0.44 |
| *2* | Sb | 0.78 | W | 0.07 |
| *3* | Se | 0.76 | Sb | 0.06 |
| *4* | Pb | 0.62 | Sc | 0.06 |
| *5* | U | 0.62 | Ag | 0.05 |
| *6* | Ag | 0.50 | La | 0.05 |
| *7* | Hg | 0.49 | Pb | 0.04 |
| *8* | Bi | 0.40 | Ba | 0.04 |
| *9* | Cd | 0.37 | Sr | 0.03 |
| *10* | Th | 0.31 | Na | 0.03 |

*Trench sample elements are correlated to fire assay gold values while soil sample elements are correlated to aqua regia-digested ICP gold values

**Uranium excluded in soil samples as it was not assayed for in 2017

## 11.0 CONCLUSIONS AND RECOMMENDATIONS

Gold Crest

The 2020 exploration program successfully confirmed a bedrock source to the Gold Crest zone soil anomaly. The trench displayed a 78-meter intercept of consistent low- to mid-grade gold mineralization with open-ended gold values on the east end of the trench. Soil sampling extended the strike length of the zone to 2 kilometers and confirmed the relation of gold to the gabbro-schist contact. Observations from the trench indicate that mineralization is related to quartz stockwork, silicification, pyrite, and shearing along the contact. Soil sampling also indicates the potential of a cross-structure in the Gold Crest zone area.

Due to the amount of glacial till and permafrost beyond the Gold Crest zone, very little additional surface geochemistry can be done here. It is recommended that the area be drilled (see Figure 17). For logistics and budgetary concerns, a small, heli-portable RC drill is ideal for the job. Drilling should be conducted at a 280-300 degree azimuth and should be set back at least 15m from the east edge of the trench. Four drill holes spaced 50m apart could be drilled along strike to cover 200m of the Gold Crest zone. Depth of holes would be limited by the equipment, but should be 100-150m and drilled at a -45 degree (or similar) dip. Additional drill holes should be done further along strike in either direction where surface sampling methods failed. The cross structure heading north of Gold Crest should be investigated with at least 1 hole. The gold-in-soil values along the contact ~600m northeast of Gold Crest should be investigated with either 1-2 drill holes or a mechanical trench. The gold-in-soil values ~2km northeast of Gold Crest should be investigated with hand pits or a mechanical trench.

The area directly west and northwest of the Gold Crest trench displayed a strong Ag-Sb signature despite soil samples being affected by permafrost. At least one hole could be drilled in this area to test for a parallel north-south cross-structure.

Windage

This area displays ~250m of anomalous gold-in-soil values with a much broader As-Ag-Sb-Pb anomaly. No rock sampling was done. Further soiling sampling, prospecting, and hand dug pits should be done in this area to define the anomaly and determine a bedrock source. Trenching or drilling may be warranted.

Marksmen

Traditional surface sampling techniques in this area are problematic due to the amount of glacial till. Further prospecting should be done along western edge where outcrop was observed.

Dovetail

Although no significant gold values were returned from the rock or soil samples, an impressive amount of quartz stockwork was observed in this area, and only a few hours were spent exploring it. Further, more detailed prospecting should be done in here.

In addition to these zones, all non-glaciated areas should receive at least reconnaissance soil sampling. There is a small 750x400m gabbro plug mapped in the north end of the property. A single gabbro rock sample was taken within this unit in 2017 which assayed 0.16 g/t Au. A nearby soil sample also displayed a slightly anomalous gold value (13 ppb Au). This should receive follow-up prospecting and additional soil samples.

Due to the amount of glacial material, geophysical methods should be investigated to explore in blind spots along the Gold Crest trend and across the property as a whole. An IP survey is unlikely to be effective as very little sulphide has been observed in zones of mineralization. A property-wide airborne magnetic and radiometric survey would have the best chance of identifying structures and locating any potential reduced intrusion on the property. Failing this, a ground magnetic survey at the Gold Crest zone would be beneficial.

# Bullseye Property

*Figure 17: Recommended Future Work at Gold Crest*

553000 553500 554000 554500 555000 555500

6930000 6929500 6929000 6928500

0 125 250 500 Meters

0 2.5 5 10 Kilometers

Golden Sky Minerals

White Gold Corp.

Gold Crest zone

K2 Gold Corp.

N

LOCATION MAP

*Hand pits, trenching*

*Addtional drilling or trenching*

*Additional soils, prospecting, hand pits*

*Low priority drill targets (Ag-Sb anomalous soils)*

*Recommended drillhole traces (280-300 degree azimuth, -45 degree dip, 150m depth)*

*Regional geological contact Schist (NW) - Gabbro (SE)*

*Additional soils, prospecting, hand pits*

## Legend

Recommended drill traces

**2020 Trench**

**Au (g/t)**

- <2 - 0.1
- 0.1 - 0.5
- 0.5 - 1.0
- 1.0 - 2.0
- 2.0 - 2.41

**2017-2020 rock grabs**

**Au (g/t)**

- 0 - 0.1
- 0.1 - 0.5
- 0.5 - 0.936

**2017-2020 soil samples**

**Au (ppb)**

- 0.25 - 10.0
- 10.1 - 20.0
- 20.1 - 50.0
- 50.1 - 100.0
- 100.1 - 889.1

Schist-gabbro contact

Date: December, 2020
Mapsheet: 115K12
Datum: UTM NAD83 Zone 7

GOLDEN SKY MINERALS

www.GoldenSkyMinerals.com

## REFERENCES


Yukon Bedrock Geology Legend,
http://data.geology.gov.yk.ca/Compilation/DownloadProduct/114.

Doherty, R.A., 2016. Technical Report on the Wels Gold Property, Whitehorse Mining District, Yukon, Canada (43-101 compliant). Aurum Geological Consultants Inc., Whitehorse, YT.

K2 Gold Corp. website http://k2gold.com/projects/wels-project/

Lipovsky, P.S. and Bond, J.D., 2013. Surficial geology of the Wellesley Lake (115J/05), Yukon (1:50, 000 scale) Yukon Geological Survey, EMR, Government of Yukon, Open File 2013-9.

Murphy, D.C., 2007. The three Windy-McKinley terranes of Stevenson Ridge (115JK) western Yukon. In Yukon Exploration and Geology 2006, L.H. Weston, L. R. Blackburn, and L.L. Lewis (eds) Yukon Geological Survey p 195-209.

White Gold Corp. website http://whitegoldcorp.ca/projects/beaver-creek/snapshot/


## STATEMENT OF EXPENDITURES

| **EXPLORATION COSTS 2020 - BE (Bullseye) claims**<br>Worked from July 1st, 2020 to July 12th, 2020 | | | | |
|---|---|---|---|---|
| ITEM | COMPANY | Rate | Unit | AMOUNT |
| Helicopter - Astar + Fuel | Great slave Helicopters | by invoice | | $ 29,619.28 |
| Fixed wing aircraft (flight to Independence Ck) | Great River Air | by invoice | | $ 7,455.87 |
| Camp costs | $100/man for 55 man days | $ 100.00 | 55 | $ 5,500.00 |
| Candig rental | Druid Exploration Inc | $ 650.00 | 7 | $ 4,550.00 |
| Wages - D.Ferraro (project geo) | Druid Exploration Inc | $ 450.00 | 14 | $ 6,300.00 |
| Wages - C.Jones (geo) | Druid Exploration Inc | $ 400.00 | 14 | $ 5,600.00 |
| Wages - P.Severinsen (labourer) | Druid Exploration Inc | $ 300.00 | 12 | $ 3,600.00 |
| Wages - G.Drinnan | Druid Exploration Inc | $ 300.00 | 12 | $ 3,600.00 |
| Wages - D.Dunwoody | Druid Exploration Inc | $ 300.00 | 7 | $ 2,100.00 |
| Report | D. Ferraro | $ 450.00 | 5 | $ 2,250.00 |
| Assays - Trench | Bureau Veritas | by invoice | 71 | $ 2,645.32 |
| Assays - Rock | Bureau Veritas | by invoice | 49 | $ 1,754.46 |
| Assays - Soil | Bureau Veritas | by invoice | 562 | $ 11,423.00 |
| | | | | |
| | **TOTAL** | | | **$ 86,397.93** |

## CERTIFICATE OF QUALIFICATIONS

I, Daniel Ferraro, of PO Box 1485 Dawson City, Yukon, Canada, certify that:

1. I am a graduate of Lakehead University, 2008, and a hold an H. B.Sc. Geology degree.

2. I am an independent geological consultant.

3. I am a member of the Ontario Prospectors Association (2010).

4. I have been employed as a geological assistant for the Ontario Geological Survey and the Geological Survey of Canada during the summers of, respectively, 2006 and 2007.

5. I have been working in the mineral exploration industry since 2008 consulting for Pacific North West Capital Corporation, East West Resources Corporation, Rainy Mountain Royalty Corporation, Black Panther Mining Corporation, White Tiger Mining Corporation, Trillium North Minerals Ltd., Nebu Resources Inc., Canoe Mining Ventures Corp., Harte Gold Corp., Goldstrike Resources Ltd., Goldspike Exploration Inc., Nevada Zinc Corp., Luckystrike Resources Ltd., and Golden Sky Minerals Corp.

6. This report was prepared by myself.

7. I have no personal knowledge from the date of this certificate of any material fact or change not reflected in this report.

Date: Jan. 5, 2021

Daniel Ferraro, HBSc.

Appendix I: List of Claims

**Appendix I**
**Bullseye Property Claim List, November 2020**
**Golden Sky Minerals Corp.**

| Claim Name | Claim No. | Grant No. | Owner | Status | Staking Date | Recording Date | Expiry Date | District |
|---|---|---|---|---|---|---|---|---|
| BE | 1 | YF05301 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 2 | YF05302 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 3 | YF05303 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 4 | YF05304 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 5 | YF05305 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 6 | YF05306 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 7 | YF05307 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 8 | YF05308 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 9 | YF05309 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 10 | YF05310 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 11 | YF05311 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 12 | YF05312 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 13 | YF05313 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 14 | YF05314 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 15 | YF05315 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 16 | YF05316 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 17 | YF05317 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 18 | YF05318 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 19 | YF05319 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 20 | YF05320 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 21 | YF05321 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 22 | YF05322 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 23 | YF05323 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 24 | YF05324 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 25 | YF05325 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 26 | YF05326 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 27 | YF05327 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 28 | YF05328 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 29 | YF05329 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 30 | YF05330 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 31 | YF05331 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 32 | YF05332 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 33 | YF05333 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 34 | YF05334 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 35 | YF05335 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 36 | YF05336 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 37 | YF05337 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 38 | YF05338 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 39 | YF05339 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 40 | YF05340 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 41 | YF05341 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 42 | YF05342 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 43 | YF05343 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 44 | YF05344 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 45 | YF05345 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 46 | YF05346 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 47 | YF05347 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 48 | YF05348 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 49 | YF05349 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 50 | YF05350 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 51 | YF05351 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 52 | YF05352 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |

| Claim Name | Claim No. | Grant No. | Owner | Status | Staking Date | Recording Date | Expiry Date | District |
|---|---|---|---|---|---|---|---|---|
| BE | 53 | YF05353 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 54 | YF05354 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 55 | YF05355 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 56 | YF05356 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 57 | YF05357 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 58 | YF05358 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 59 | YF05359 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 60 | YF05360 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 61 | YF05361 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 62 | YF05362 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 63 | YF05363 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 64 | YF05364 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 65 | YF05365 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 66 | YF05366 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 67 | YF05367 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 68 | YF05368 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 69 | YF05369 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 70 | YF05370 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 71 | YF05371 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 72 | YF05372 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 73 | YF05373 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 74 | YF05374 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 75 | YF05375 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 76 | YF05376 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 77 | YF05377 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 78 | YF05378 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 79 | YF05379 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 80 | YF05380 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 81 | YF05381 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 82 | YF05382 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 83 | YF05383 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 84 | YF05384 | Luckystrike Resources Ltd. - 100% | Active | 2017-05-22 | 2017-05-25 | 2025-05-25 | Whitehorse |
| BE | 85 | YF05385 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 86 | YF05386 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 87 | YF05387 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 88 | YF05388 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 89 | YF05389 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 90 | YF05390 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 91 | YF05391 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 92 | YF05392 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 93 | YF05393 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 94 | YF05394 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 95 | YF05395 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 96 | YF05396 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 97 | YF05397 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 98 | YF05398 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 99 | YF05399 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 100 | YF05400 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 101 | YF05401 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 102 | YF05402 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 103 | YF05403 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 104 | YF05404 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 105 | YF05405 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 106 | YF05406 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 107 | YF05495 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 108 | YF05496 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |

| Claim Name | Claim No. | Grant No. | Owner | Status | Staking Date | Recording Date | Expiry Date | District |
|---|---|---|---|---|---|---|---|---|
| BE | 109 | YF05497 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 110 | YF05498 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 111 | YF05499 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 112 | YF05500 | Luckystrike Resources Ltd. - 100% | Active | 2017-09-15 | 2017-10-04 | 2025-10-04 | Whitehorse |
| BE | 113 | YF55583 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 114 | YF55584 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 115 | YF55585 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 116 | YF55586 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 117 | YF55587 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 118 | YF55588 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 119 | YF55589 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 120 | YF55590 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 121 | YF55591 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 122 | YF55592 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 123 | YF05503 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 124 | YF05504 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 125 | YF05505 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 126 | YF05506 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 127 | YF05507 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 128 | YF05508 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 129 | YF05509 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 130 | YF05510 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 131 | YF05511 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 132 | YF05512 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 133 | YF05513 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 134 | YF05514 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 135 | YF05515 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 136 | YF05516 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 137 | YF05517 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 138 | YF05518 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 139 | YF05519 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 140 | YF05520 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 141 | YF05521 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |
| BE | 142 | YF05522 | Golden Sky Minerals Corp - 100% | Pending | 2020-06-30 | 2020-06-30 | 2026-06-30 | Whitehorse |

Appendix II: Trench Sample Descriptions

# Abbreviations

| Code | Lithology |
|---|---|
| SSH | Sericite Schist |
| QSSH | Quartz-Sericite Schist |
| QTT | Quartzite |
| CHLSH | Chlorite Schist |
| GAB | Gabbro |
| LS | Limestone |

| Code | Sulphides & Oxides |
|---|---|
| aspy | arsenopyrite |
| az | azurite |
| bis | bismuthinite |
| cpy | chalcopyrite |
| gn | galena |
| hem | hematite |
| lim | limonite |
| mag | magnetite |
| mal | malachite |
| MnO | manganese oxide |
| mo | molybdenite |
| po | pyrrhotite |
| py | pyrite |
| sc | scorordite |
| sch | scheelite |
| sp | sphalerite |
| spec hem | specular hematite |
| tel | tellurides |
| VG | visible gold |

| Code | Alteration Intensity |
|---|---|
| w | weak |
| m | moderate |
| s | strong |
| i | intense |

| Code | Silicates & Alteration |
|---|---|
| ab | albite (albititized) |
| Al-sil | Aluminum silicate |
| alt | alteration |
| amp | amphibole class |
| ad | andalusite |
| ank | ankerite |
| arg | argillic |
| bio | biotite |
| cal | calcite |
| cl | amorphous clay alteration |
| crd | cordierite |
| cs | calcite stringers |
| carb | carbonate alteration (unspecified) |
| chl | chlorite (chloritized) |
| chltd | chloritoid |
| dol | dolomite |
| ep | epidote |
| fu | fuschite |
| fd | feldspar |
| gar | garnet |
| gf | graphite |
| ksp | K-feldspar |
| px | pyroxene class |
| qcs | quartz-carbonate stringer |
| qcv | quartz-carbonate vein |
| qs | quartz stringer |
| qtz | quartz |
| qtsw | quartz stockwork |
| qv | quartz vein |
| ox/oxi | oxidized |
| ser | sericite |
| sid | siderite |
| sil | silicified |
| sl | sillimanite |
| str | stringer |
| tour | tourmaline |
| xtls | crystals |

| Code | Structure |
|---|---|
| ap | axial plane |
| bd | bedding |
| bnd | banding |
| boud | boudinage |
| bx | breccia |
| clvg | cleavage |
| crn | crenulated/crenulation |
| cg | coarse-grained |
| decomp | decomposed |
| dtca | degrees to core axis |
| def | deformed |
| diss | disseminated |
| drf | drag fold |
| flt | fault |
| fltbx | fault breccia |
| fltg | fault gouge |
| fg | fine-grained |
| fol | foliation |
| frac | fracture |
| incl | inclusion |
| jnt | joint/jointed |
| lam | laminated/lamination |
| ln | lineament |
| mg | medium-grained |
| mega | megacrysts |
| msv | massive |
| pheno | phenocrysts |
| pmorph | pseudomorph |
| porp | porphyritic |
| sch | schistosity |
| sh | shear |
| slk | slickenside |
| tr | trace |
| vfg | very fine grained |
| vn | vein |

## Trench BETR-20-01 Sample Descriptions with Select Element Assay Results

**Coordinate System UTM NAD83 Zone 7**
**Trench Start E553686, N6928753**
**Trench End E553556, N6928772**

| Sample ID | Sample Easting | Sample Northing | From (m) | To (m) | Length (m) | Azi-muth | Depth (cm) | Date | Competancy | Geology | | | Alteration | | | | | Mineralization | Description | Au (ppb) | Ag (ppm) | As (ppm) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Primary Lithology | Secondary Lithology | Veining | Carb | Sil | Ox | Chl | Bleach | | | | | |
| 1878401 | 553685 | 6928753 | 0 | 2 | 2 | 280 | 110 | 08-Jul-20 | moderate | QSSH | | QTSW (dark) | | m/s | s/i | | | lim | Strongly oxidized and silicified beige to light brown quartz sericite schist, dark grey < 1 mm quartz stringers / stockwork | 392 | 0.6 | 2062.2 |
| 1878402 | 553683 | 6928754 | 2 | 4 | 2 | 280 | 110 | 08-Jul-20 | moderate | QSSH | | QTSW (dark) | | m/s | s/i | | | lim | Same as above | 269 | 0.5 | 1854.2 |
| 1878403 | 553681 | 6928754 | 4 | 6 | 2 | 280 | 100 | 08-Jul-20 | moderate | QSSH | | QTSW (dark) | | m | m | | | lim | Same as above, less pervasive oxidation with darker manganese oxide staining on fractures | 318 | 0.6 | 3756.9 |
| 1878404 | 553679 | 6928754 | 6 | 8 | 2 | 280 | 100 | 08-Jul-20 | moderate | QSSH | CHLSH | QCS | w | m | m | | | lim | Same as above, grading into green chlorite schist? | 283 | 0.5 | 1810.8 |
| 1878405 | 553677 | 6928755 | 8 | 10 | 2 | 280 | 100 | 08-Jul-20 | moderate | CHLSH | QSSH/GAB | QCS | m | m/s | m | m | | lim, local tr frash py | Litho change, green chlorite schist (dominant rock type), trace fresh disseminated py locally, < 1 mm carbonate stringers, minor gabbro at end of sample (9.75m) | 137 | 0.2 | 655.3 |
| 1878406 | 553675 | 6928755 | 10 | 12 | 2 | 280 | 100 | 08-Jul-20 | moderate | CHLSH | QSSH/GAB | QCS | m | m/s | m | m | | lim, local tr fresh py | Dominate rock type is chlorite schist with carbonate stringers, trace fresh py locally, minor gabbro throughout, quartz veining with lim fracture throughout | 221 | 0.4 | 1858.4 |
| 1878407 | 553673 | 6928755 | 12 | 14 | 2 | 278 | 150 | 08-Jul-20 | moderate | QSSH | QV | QV, QTSW | m | s/i | s/i | | | lim, py pseudo | Litho change, depth of trench increases significantly (out of permafrost zone), C horizon soil changes from dark brown to orange, strongly oxidized and silicified quartz sericite schist, abundant limonitic fractures, < 1 mm dark quartz and beige carbonate stringers, conchoidal fracture, < 1mm py pseudomorphs locally | 681 | 0.7 | 3831 |
| 1878408 | 553671 | 6928756 | 14 | 16 | 2 | 278 | 150 | 08-Jul-20 | moderate | QSSH | QV | QV, QTSW | m | s/i | s/i | | | lim, py pseudo | Same but less orange oxidation, increase in dark brown manganese oxide staining on fractures, local light grey clay altered units with < 1 mm cubic py pseudomorphs | 870 | 1.1 | 6304.8 |
| 1878409 | 553669 | 6928756 | 16 | 18 | 2 | 278 | 140 | 08-Jul-20 | moderate | QSSH | QV | QV, QTSW | m | m/s | m/s | | | lim, py pseudo | Same as above | 2414 | 1.6 | >10000.0 |
| 1878410 | 553667 | 6928756 | 18 | 20 | 2 | 278 | 150 | 08-Jul-20 | moderate | QSSH | QV | QV, QTSW | w | w | m | | | lim | Less silicified with weak foliation development and phylitic texture, moderate oxidation with local strong oxidized zones | 1465 | 1 | 9485.4 |
| 1878411 | 553665 | 6928756 | 20 | 22 | 2 | 284 | 170 | 08-Jul-20 | moderate | QSSH | QV | QV, QTSW | w | s | m | | | lim | Moderate to strong silicified quartz sericite schist, patchy strong oxidized zones, dark manganese oxide staining on fractures, abundant quartz veins and stockwork, minor calcite stringers | 919 | 0.5 | 5450 |
| 1878412 | 553663 | 6928757 | 22 | 24 | 2 | 284 | 190 | 08-Jul-20 | moderate | QSSH | QV | QV, QTSW | w | s | m/s | | | lim | Same as above | 1370 | 1.6 | 5813.2 |
| 1878413 | 553661 | 6928757 | 24 | 26 | 2 | 284 | 160 | 08-Jul-20 | moderate | QSSH | QV | QV, QTSW | | s | m/s | | | lim | Same, less silicified with increased phylitic texture, py pseudomorphs < 1mm in phylitic schist host | 1203 | 1 | 4604.9 |
| 1878414 | 553659 | 6928758 | 26 | 28 | 2 | 284 | 170 | 08-Jul-20 | moderate | QSSH | light grey unit? | QV, QTSW | | m/s | m/s | | m | lim, py pseudo | Strongly altered sericite schist, light grey clay altered / bleached zone | 924 | 24.2 | 6421.1 |
| 1878415 | 553657 | 6928758 | 28 | 30 | 2 | 284 | 170 | 08-Jul-20 | moderate | QSSH | light grey unit? | QV, QTSW | | m/s | m/s | | m | lim, py pseudo | Same as above | 1753 | 16.4 | >10000.0 |
| 1878416 | 553655 | 6928759 | 30 | 32 | 2 | 280 | 175 | 09-Jul-20 | moderate | dark grey unit? | QSSH | QV, BX, QTSW | | s | m/s | | | lim, py pseudo | Change to darker grey quartz / strong silic unit?, sub brecciated with intense drk quartz stockwork? , white quartz vein throughout, overall strong silicification and moderate oxidation , limonitic with py pseudomorphs in quartz vein material and host dark grey unit | 1166 | 2.2 | 7883.4 |
| 1878417 | 553654 | 6928759 | 32 | 34 | 2 | 280 | 165 | 09-Jul-20 | moderate | dark grey unit? | QSSH | QV, BX, QTSW | | s | m/s | | | lim, py pseudo | Same but slight increase in white quartz veining, lim and py pseudomorphs | 1611 | 1.1 | 7739.8 |
| 1878418 | 553652 | 6928760 | 34 | 36 | 2 | 280 | 75 | 09-Jul-20 | moderate | QSSH | light to dark grey unit? | QV, BX, QTSW | | m | m | | | lim, py pseudo | Same but less silicified then previous sample, grades back into less altered sericite schist with metamorphic fabric (foliated), phylitic texture, patchy strong oxi zones with 60 % qv material (light and dark color) | 1855 | 10.5 | 5551.2 |
| 1878419 | 553650 | 6928760 | 36 | 38 | 2 | 280 | 85 | 09-Jul-20 | moderate | QSSH | light to dark grey unit? | QV | | m/s | m/s | | | lim, py pseudo | Same as above | 1519 | 28.6 | 4734 |
| 1878420 | 553648 | 6928760 | 38 | 40 | 2 | 276 | 120 | 09-Jul-20 | moderate | QSSH | light to dark grey unit? | QV, QTSW | | m | m | | | lim, py pseudo | Muscovite / sericite schist with moderate silicification, white quartz vein and stockwork throughout, increase silicification towards end of sample. | 550 | 0.4 | 3179.9 |
| 1878421 | 553646 | 6928760 | 40 | 42 | 2 | 276 | 110 | 09-Jul-20 | moderate | QSSH | light to dark grey unit? | QV, QTCSW | w | m | m | | | lim, py pseudo | Silicified sericite schist, sections of dark grey silicified zones with quartz carb stringers, large quartz vein at last 30 cm of sample, quartz is white with rusty frac and some dark grey (graphite?) stringers | 281 | 0.4 | 1651.7 |
| 1878422 | 553644 | 6928761 | 42 | 44 | 2 | 276 | 165 | 09-Jul-20 | mod-strong | QSSH | | QV, QTSW | | m/s | m | | | lim, py pseudo | White rusty quartz vein grading to grey silic sericite schist with fine qtsw | 228 | 0.3 | 1015.7 |
| 1878423 | 553642 | 6928761 | 44 | 46 | 2 | 279 | 120 | 09-Jul-20 | mod-strong | QSSH | | QV, BX | | m/s | m | | | lim, py pseudo | Moderate to strong silicification, light grey sericite schist with fine quartz stockwork | 255 | 0.3 | 1883.1 |
| 1878424 | 553640 | 6928761 | 46 | 48 | 2 | 279 | 150 | 09-Jul-20 | mod-strong | QSSH | | QTSW | | m | m | | | lim, py pseudo | Light grey strongly silicified sericite schist with good qtsw at start of sample (46 - 47m), end of sample grades into less silicified muscovite schist with strong metamorphic fabric ( foliation and crenulations), white qv material (20%) throughout, limonitic fractures and py pseudomorphs | 554 | 0.4 | 2514.2 |
| 1878425 | | | | | | | | 09-Jul-20 | | | | | | | | | | | STANDARD CDN-GS-6B | 6333 | 0.1 | 4363.7 |
| 1878426 | | | | | | | | 09-Jul-20 | | | | | | | | | | | BLANK CDN-BL-9 | 3 | 0.5 | 3.7 |
| 1878427 | 553638 | 6928761 | 48 | 50 | 2 | 279 | 125 | 09-Jul-20 | strong | QSSH | SSH | QTSW | | m/s | m | | | lim, py pseudo | Light grey moderate to strong silicified sericite schist, some patchy darker grey quartz / silicified schist zones, patchy strong oxidized zones with lim fractures, minor white quartz veining | 486 | 0.4 | 2636.4 |
| 1878428 | 553636 | 6928762 | 50 | 52 | 2 | 281 | 150 | 09-Jul-20 | strong | QSSH | SSH | QTSW, QV | | m/s | m | | | lim, py pseudo | Light grey / blueish quartz sericite schist with qtsw, moderate to strong silicification, lim fractures and py pseudomorphs in schist and white quartz veins, foliated with strong sericite alteration, local patchy zones of strong oxi and clay alteration (beige to rusty brown) | 860 | 0.6 | 3732.8 |
| 1878429 | 553634 | 6928762 | 52 | 54 | 2 | 281 | 160 | 09-Jul-20 | strong | QSSH | SSH | QTSW, QV | | m/s | s | | | lim, py pseudo | Same as above but stronger oxidation (increase lim fractures) | 601 | 0.8 | 2882.8 |
| 1878430 | 553632 | 6928763 | 54 | 56 | 2 | 281 | 150 | 09-Jul-20 | strong | QSSH | SSH | QTSW, QV | | m/s | m/s | | | lim, py pseudo | Same as above | 1105 | 0.8 | 3300.5 |
| 1878431 | 553630 | 6928763 | 56 | 58 | 2 | 281 | 125 | 09-Jul-20 | strong | QSSH | SSH | QV, QTSW | | s | m/s | | | lim, py pseudo | Very strong silicified sericite schist with qtsw @ end of sample (57.5 - 58 m), some fresh py cubes and blebs, abundant py pseudomorphs (cubes < 1mm) | 428 | 0.5 | 1947.3 |
| 1878432 | 553628 | 6928763 | 58 | 60 | 2 | 280 | 120 | 10-Jul-20 | strong | SSH | | QV, QTSW | | m | m | | | lim, py pseudo | Grey silicified sericite schist with white qv and fine qtsw, lim fractures and py pseudomorphs < 1mm | 315 | 0.4 | 1843.5 |
| 1878433 | 553626 | 6928764 | 60 | 62 | 2 | 280 | 120 | 10-Jul-20 | strong | SSH | | QV, QTSW | | m | m/s | | | lim, py pseudo | Same as above, increase in oxidation towards end of sample | 265 | 0.5 | 829 |
| 1878434 | 553624 | 6928764 | 62 | 64 | 2 | 280 | 160 | 10-Jul-20 | moderate | SSH | | QV, QTSW | | m | s/i | | | lim, py pseudo | Strong oxidation and silicification (grey sericite schist), abundant limonite in fractures and voids, some rock pieces with 80% limonite (punky) | 498 | 1.6 | 1832.6 |
| 1878435 | 553622 | 6928764 | 64 | 66 | 2 | 280 | 160 | 10-Jul-20 | mod-strong | SSH | | QV, QTSW | | m | m/s | | | lim, py pseudo | Same but grades into less silicified and oxidized sericite schist with good foliation development at end of sample | 232 | 0.7 | 1593.4 |

| Sample ID | Sample Easting | Sample Northing | From (m) | To (m) | Length (m) | Azi-muth | Depth (cm) | Date | Competancy | Geology | | | Alteration | | | | | Mineralization | Description | Au (ppb) | Ag (ppm) | As (ppm) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Primary Lithology | Secondary Lithology | Veining | Carb | Sil | Ox | Chl | Bleach | | | | | |
| 1878436 | 553620 | 6928765 | 66 | 68 | 2 | 280 | 140 | 10-Jul-20 | strong | SSH | | QV, QTSW | | w/m | m/s | | | lim, py pseudo | Color change / litho change?, sericite muscovite schist?, moderate oxidation throughout, weaker silicification, local patchy strong oxidized and silicified zones, minor white qv material, consistent fine qtsw throughout, overall poorer competency, (very broken and decomposed) | 112 | 0.3 | 861.2 |
| 1878437 | 553618 | 6928765 | 68 | 70 | 2 | 280 | 130 | 10-Jul-20 | moderate | SSH | | QV, QTSW | | w/m | m/s | | | lim, py pseudo | Same as above | 138 | 0.3 | 757.2 |
| 1878438 | 553616 | 6928765 | 70 | 72 | 2 | 280 | 110 | 10-Jul-20 | moderate | SSH | | QV, QTSW | | m | m | | | lim, py pseudo, tr fresh py | Increased sil and oxi, minor darker grey sil zones with tr fresh py, minor white qv with lim frac, dark grey stringers and py pseudomorphs < 1mm, fine qtsw throughout | 225 | 0.3 | 1111.3 |
| 1878439 | 553614 | 6928766 | 72 | 74 | 2 | 280 | 110 | 10-Jul-20 | moderate | SSH | dark grey unit? | QV, QTSW, dark veining | | w/m | m | | w | lim, py pseudo | Oxidized sil sericite schist with white qv and fine qtsw, weak bleached white - beige unoxidized schist | 169 | 0.9 | 986 |
| 1878440 | 553612 | 6928766 | 74 | 76 | 2 | 280 | 150 | 10-Jul-20 | weak-mod | SSH | | QV, QTSW | | w/m | m | | w | lim, py pseudo | Lesser oxi and sil sericite schist, bleached white - beige on fresh unoxidized samples (clay alt'd?), fine qtsw throughout, very little white quartz vein material, limonite fractures and py pseudomorphs | 123 | 0.1 | 882.9 |
| 1878441 | 553610 | 6928766 | 76 | 78 | 2 | 280 | 150 | 10-Jul-20 | weak-mod | SSH | | QTSW | | w/m | m | | m | lim, py pseudo | Same as above | 110 | 0.1 | 876.1 |
| 1878442 | 553608 | 6928767 | 78 | 80 | 2 | 280 | 150 | 10-Jul-20 | moderate | SSH | | QTSW | | m | m | | m | lim, py pseudo | Increase in competency, increase silicification, less metamorphic schistose fabric (foliation / phylitic texture), oxi sil sericite schist with fine qtsw and lim fractures | 68 | <0.1 | 526.4 |
| 1878443 | 553606 | 6928767 | 80 | 82 | 2 | 280 | 130 | 10-Jul-20 | strong | SSH | | QV, QTSW | | m/s | m/s | | w | lim, py pseudo | Moderate to strong sil and oxi, moderate bleaching (clay alt?), local qv material with grey blue stringers / silicification, qtsw with abundant lim filled voids and vugs | 32 | <0.1 | 259.8 |
| 1878444 | 553604 | 6928767 | 82 | 84 | 2 | 280 | 120 | 10-Jul-20 | mod-strong | SSH | | QV, QTSW | | s | m | | w | lim, py pseudo | Beige bleached out sericite schist (un oxidized samples) with fine qtsw and white quartz veins, locally quartz veins are vuggy and filled with limonite, possible feldspar alt? beige stringers ? | 30 | <0.1 | 224.5 |
| 1878445 | 553602 | 6928768 | 84 | 86 | 2 | 280 | 110 | 10-Jul-20 | mod-strong | SSH | | QV, QTSW | | m/s | m | | w | lim, py pseudo | Same as above | 57 | 0.1 | 401.3 |
| 1878446 | 553600 | 6928768 | 86 | 88 | 2 | 280 | 120 | 10-Jul-20 | moderate | SSH | Grit? | QV, QTSW | | w/m | m | | | lim, py pseudo | Oxidized sericite schist, limonitic frac and fine qtsw, protolith looks like grit?, coarser texture? | 102 | 0.1 | 395.8 |
| 1878447 | 553598 | 6928769 | 88 | 90 | 2 | 280 | 100 | 10-Jul-20 | moderate | SSH | Grit? | QV, QTSW | | w/m | m | | | lim, py pseudo | Gritty sericite schist, limonitic fracs, weaker sil and moderate oxidation | 143 | 0.1 | 575.4 |
| 1878448 | 553596 | 6928769 | 90 | 92 | 2 | 280 | 100 | 11-Jul-20 | moderate | SSH | | QV, QTSW | | w/m | m | | | lim, py pseudo | Same as above | 85 | 0.1 | 545.5 |
| 1878449 | 553594 | 6928769 | 92 | 94 | 2 | 280 | 100 | 11-Jul-20 | moderate | SSH | | QTSW | | w/m | m | | | lim, py pseudo | Weak sil, moderate oxidized quartz sericite schist, some stronger sil and oxi zones, local white qv vein with fol (< 10%), soft phylitic texture, less gritty | 54 | 0.1 | 319.9 |
| 1878450 | | | | | | | | 11-Jul-20 | | | | | | | | | | | STANDARD CDN-CM-25 | 256 | 0.7 | 18.5 |
| 1878451 | | | | | | | | 11-Jul-20 | | | | | | | | | | | BLANK CDN-BL-9 | 5 | 0.6 | 3.5 |
| 1878452 | 553592 | 6928770 | 94 | 96 | 2 | 280 | 120 | 11-Jul-20 | moderate | SSH | | QTSW, QV | | w/m | m | | | lim | Same as above | 17 | <0.1 | 146.9 |
| 1878453 | 553590 | 6928770 | 96 | 98 | 3 | 280 | 110 | 11-Jul-20 | moderate | SSH | | QV | | w | m | | | lim | Same as above | 27 | <0.1 | 184.1 |
| 1878454 | 553588 | 6928770 | 98 | 100 | 4 | 280 | 120 | 11-Jul-20 | moderate | SSH | | QV (dark) | | w/m | m/s | | | lim | same, stronger silicification / drk qrtz veining zones with stronger oxidation (approx. 10%), abundant lim fracture fill, minor white qv | 9 | <0.1 | 134.7 |
| 1878455 | 553586 | 6928771 | 100 | 102 | 5 | 280 | 130 | 11-Jul-20 | moderate | SSH | | QV | w | w/m | m | | | lim | same but grades into darker schist (chlorite muscovite schist) | 14 | 0.2 | 189.9 |
| 1878456 | 553585 | 6928771 | 102 | 104 | 6 | 280 | 110 | 11-Jul-20 | moderate | CHLSH | SSH | CS | m | w/m | w/m | | | lim, fresh py tr - 1% | litho change, dark grey chlorite sericite schist?, weak fine calcite stringers throughout < 2mm wide, tr fresh py | 18 | <0.1 | 88.9 |
| 1878457 | 553583 | 6928771 | 104 | 106 | 7 | 280 | 110 | 11-Jul-20 | moderate | CHLSH | SSH | CS | m | w | w/m | | | lim, fresh py tr - 1% | same, slight coarsening of texture, grading into carb schist / limestone?, | 23 | <0.1 | 128.7 |
| 1878458 | 553581 | 6928772 | 106 | 108 | 8 | 280 | 100 | 11-Jul-20 | mod-strong | LS | CHLSH | QCV, CS | s | w | w | | | lim, fresh py tr - 1% | dark grey weak foliated limestone?, calcite veins (< 5cm) and stringer (< 2mm), minor white quartz carb veins mixed, tr fresh py and weak oxidation with lim fractures | 42 | <0.1 | 131.6 |
| 1878459 | 553579 | 6928772 | 108 | 110 | 9 | 280 | 90 | 11-Jul-20 | mod-strong | LS | CHLSH | QCV, CS | s | w | w | | | lim, fresh py tr - 1% | Same as above | 5 | <0.1 | 21.6 |
| 1878460 | 553577 | 6928772 | 110 | 112 | 10 | 280 | 65 | 11-Jul-20 | mod-strong | LS | CHLSH | QCV, CS | s | w | w | | | lim, fresh py tr - 1% | Same as above | 48 | <0.1 | 26.2 |
| 1878461 | 553575 | 6928773 | 112 | 114 | 11 | 280 | 50 | 11-Jul-20 | mod-strong | LS | CHLSH | QCV, CS | s | w | w | | | tr fresh py, lim | Grades into lighter green limestone / carb chlorite schist?, very fine discontinuous dark brown / black stringers, minor quartz carb veining with fol @ < 10% | 10 | <0.1 | 50.8 |
| 1878462 | 553573 | 6928773 | 114 | 116 | 12 | 280 | 75 | 11-Jul-20 | mod-strong | LS | CHLSH | QCV, CS | s | w | w | | | tr fresh py, lim | Same as above | 53 | 0.1 | 188.2 |
| 1878463 | 553571 | 6928773 | 116 | 118 | 13 | 280 | 100 | 11-Jul-20 | mod-strong | LS | CHLSH | QCV, CS | s | w | w | | | tr fresh py, lim | Same as above | 5 | <0.1 | 18.5 |
| 1878464 | 553569 | 6928774 | 118 | 120 | 14 | 280 | 60 | 11-Jul-20 | mod-strong | QSSH | | QV | s | m | w | | w | lim | Same as above | 7 | <0.1 | 26.3 |
| 1878465 | 553567 | 6928774 | 120 | 122 | 15 | 280 | 110 | 11-Jul-20 | mod-strong | QSSH | | QV | | m | m | | w | lim | 10 cm calcite vein at start of sample, litho change, moderate silicified quartz sericite schist, well foliated with weak bleaching in un oxidized samples, patchy strong oxi zones with lim filled foliation lenses | 19 | 0.1 | 35.5 |
| 1878466 | 553565 | 6928774 | 122 | 124 | 16 | 280 | 110 | 11-Jul-20 | mod-strong | QSSH | | | | m | m | | w | lim | As above, no quartz veining | 5 | <0.1 | 17.2 |
| 1878467 | 553563 | 6928775 | 124 | 126 | 17 | 280 | 120 | 11-Jul-20 | mod-strong | QSSH | | | | m | m | | | lim | Same as above | 8 | <0.1 | 27.1 |
| 1878468 | 553561 | 6928775 | 126 | 128 | 18 | 280 | 70 | 11-Jul-20 | mod-strong | QSSH | | QV | | s | m | | | lim | As above, grading into darker muscovite chlorite schist, local white quartz veining | 3 | <0.1 | 8 |
| 1878469 | 553559 | 6928775 | 128 | 130 | 19 | 280 | 70 | 11-Jul-20 | mod-strong | LS | SSH | CV, CS | s | w | w/m | | | tr fresh py, lim | Grades into green limestone (weak fol), mixed with dark grey lim, carb veins and stringers., fresh tr py cubes throughout | <2 | <0.1 | 8.7 |
| 1878470 | 553557 | 6928776 | 130 | 132 | 20 | 280 | 60 | 11-Jul-20 | mod-strong | LS | SSH | CV, CS | m | w | w | | | tr fresh py, lim | Same as above, less carbonate | <2 | <0.1 | 5.4 |
| 1878471 | 553555 | 6928776 | 132 | 134 | 21 | 280 | 50 | 11-Jul-20 | mod-strong | QTT | | CS | w | w | w | | | lim | Grades into green weak foliated quartzite, no carbonate in matrix, minor calcite stringers, mod silicification, weak oxidation | <2 | <0.1 | 2.9 |

Appendix III: Prospecting Rock Sample Descriptions

**Prospecting Rock Sample Descriptions with Select Element Assay Results**

UTM NAD83 Zone 7

| GENERAL | | | LOCATION | | | | SAMPLE | | | GEOLOGY | | | | | Au | Ag | As |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Sample ID | User | Date | Easting | Northing | Altitude (m) | Area | Material | Exposure | Sample type | Lithology | Alt'n | Veining | Min | Description | (ppb) | (ppm) | (ppm) |
| 1878251 | Dan Ferraro | 02-Jul-20 | 551583 | 6929229 | 657 | Marksmen | rock | float | grab | schist | | QV | lim | Small pit dug at high Au soil sample. Dk grey chloritic schist with metamporphic qtz, minor remnant py cubes. Some sulfur smell. Def, cren cleavage, minor microfaults and offsets | 36 | 2.3 | 74.4 |
| 1878252 | Dan Ferraro | 02-Jul-20 | 551618 | 6929251 | 664 | Marksmen | rock | float | grab | schist | | QV | lim | Float from turned up tree roots. Gently deformed schist with 30% metamorphic qtz, minor lim py and rem py cubes | 10 | <0.1 | 61 |
| 1878253 | Dan Ferraro | 02-Jul-20 | 551625 | 6929242 | 673 | Marksmen | rock | outcrop | grab | schist | | QV | lim | Outcrop. Fairly flat lying. More competant schist with up to 1" qtz nodules. Samples with 65% qtz. Rusty. MnO. | 6 | <0.1 | 34.8 |
| 1878254 | Phil Severinsen | 02-Jul-20 | 551591 | 6929044 | 690 | Marksmen | rock | outcrop | grab | schist | | QV | lim | Mostly qtz vein material . Nice remnant py cubes. Some white clay alteration (likely feldspar). | <2 | <0.1 | 3.4 |
| 1878255 | Dan Ferraro | 04-Jul-20 | 553397 | 6928728 | 781 | Gold Crest | rock | float | grab | schist | carb | QV | lim | Qtz vein float from near chopper pad (unflagged). Mostly qtz material with dark shaley lenses. Rusty limonitic pits and fractures. Strong carb alt. likely iron carb. | 4 | 0.2 | 3.7 |
| 1878256 | Phil Severinsen | 04-Jul-20 | 553834 | 6927782 | 753 | Iron Sight | rock | outcrop | grab | gabbro | carb, ep | qtz-cal | | Epidote qtz-cal veining in mafic host? | 6 | <0.1 | <0.5 |
| 1878257 | Phil Severinsen | 04-Jul-20 | 553814 | 6927774 | 757 | Iron Sight | rock | outcrop | grab | gabbro? schist? | sil | qv | | Cherty dk grey material and some qtz vein material. Looks more like schist host but in gabbro? Looks like slickenslides? | 9 | <0.1 | 0.5 |
| 1878258 | Phil Severinsen | 04-Jul-20 | 553734 | 6927865 | 704 | Iron Sight | rock | outcrop | grab | gabbro | carb | qtz-cal | | Qtz-cal vein material, likely gabbro host | 3 | <0.1 | 0.6 |
| 1878259 | Phil Severinsen | 04-Jul-20 | 553691 | 6927865 | 695 | Iron Sight | rock | subcrop | grab | gabbro | sil | | | Cherty material from within gabbro | <2 | <0.1 | 1.9 |
| 1878260 | Dan Ferraro | 07-Jul-20 | 554336 | 6930661 | 783 | Dovetail | rock | outcrop | grab | chlorite schist | | QV | | Sample mostly qv. Within rustly phillitic schist, strongly creunlated with outcrop scale folds and smaller. Qv is up to 2" thick with rusty fractures, MnO or goethite. No carb | <2 | <0.1 | 1.1 |
| 1878261 | Phil Severinsen | 06-Jul-20 | 555015 | 6929859 | 817 | Dovetail | rock | float | grab | schist | | QV | | Weakly creunlated QSSH with 0.5cm qtz in foliation. Dk grey silicified foliations as well. No carb | 3 | <0.1 | 5.9 |
| 1878262 | Phil Severinsen | 06-Jul-20 | 554381 | 6930624 | 762 | Dovetail | rock | outcrop | grab | schist | | QV | | Moderately cenulated schist with qtz with foliation. Rusty. Limonitic. No carb | 15 | <0.1 | 27.9 |
| 1878263 | Dan Ferraro | 10-Jul-20 | 553564 | 6928665 | 793 | Gold Crest | rock | subcrop | pit grab | schist | | QTSW | | 1m hand dug pit at high Au soil sample (89ppb, sample3218). This rock sample is representative of lots of the larger float rocks in the pit. Strongly crenulated and folded silicious mica schist or qtz-ser-schist with 3mm xxing qtz veining. Rust fx and fol planes. | 151 | 0.1 | 296.5 |
| 1878264 | Dan Ferraro | 10-Jul-20 | 553564 | 6928665 | 793 | Gold Crest | rock | outcrop | pit grab | schist and QV | | QV | | Same pit as above. Large quartz vein boulder or outcrop. White qtz with oragne fx planes. Rem py cube and tr fresh py. Sample is 90% qtz. Sulfur smell when broken. | 936 | 0.3 | 1354.3 |
| 1878265 | Dan Ferraro | 10-Jul-20 | 553564 | 6928665 | 793 | Gold Crest | rock | subcrop | pit grab | schist | | QTSW | | Same pit as above. This sample is more QTSW in much more silicious schist. Less common than the schist in 8263 but still found in large blocks in the pit. Trace fresh py and lots of rem py cubes. Rusty fx planes. | 183 | 0.2 | 698 |
| 1878266 | Dan Ferraro | 10-Jul-20 | 553585 | 6928770 | | Gold Crest | rock | float | trench grab | schist | sil | QTSW | | Dup of trench rep BETR-20-01-REP12. Boulder grab from trench, not really representative of what was found in french at this interval (102-104m). Intensely silicified sericite schist with nice qtz stockwork xxing foliation. | 9 | <0.1 | 15 |
| 1878267 | Dan Ferraro | 11-Jul-20 | 553663 | 6928812 | 810 | Gold Crest | rock | outcrop | pit grab | schist | sil | QTSW | | 1m pit by 91 ppb soil sample 1553306. This sample seems to be outcrop. Very hard. Dark grey silicious schist? With ~40% qtsw, not linear, more like qtz nodules and tightly folded veinlets. Tr py? | 14 | 0.8 | 186.9 |
| 1878268 | Dan Ferraro | 11-Jul-20 | 553663 | 6928812 | 810 | Gold Crest | rock | subcrop | pit grab | schist | sil | QTSW | | Same pit as above. Very similar rock type but more yellow-orange oxidation on fractures. And less deformed qtz veining. Looks nicer. Common in pit but float still. | 67 | 0.1 | 249.2 |
| 1878269 | Dan Ferraro | 11-Jul-20 | 553663 | 6928812 | 810 | Gold Crest | rock | subcrop | pit grab | schist | sil | QTSW | | Same pit as above. Very similar rock to 8268 but oxidized throughout. Still very siliceous but pervasive orange/yellow colour. | 12 | 0.1 | 52.7 |
| 1878301 | Clayton Jones | 02-Jul-20 | 551592 | 6929226 | 657 | Marksmen | Rock | float | grab | Schist | | QV | py | Darker grey quartz sericite schist, under tree stump (close to source), oxi qrtz vein with crenulated fabric, slicken slide surface, limonite fracture and clay alt'd feldspar (orange) with minor < 1 mm cubic py pseudomorphs | 25 | 1 | 40.3 |
| 1878302 | Clayton Jones | 02-Jul-20 | 551523 | 6929170 | 650 | Marksmen | Rock | outcrop | grab | Schist | | | lim | Metamorphic quartz vein following fol in quartz sericite schist outcrop, oxi with lim fractures and beige to orange clay alt'd feldspar | 9 | <0.1 | 3.5 |
| 1878303 | Clayton Jones | 03-Jul-20 | 554078 | 6928767 | 876 | Gold Crest | Rock | float | grab | Schist | | | py lim | Large float block, 1 m x 1 m, strong silic qrtz ser schist, minor < 1 m qrtz stringers, oxidized with lim fracture fill, and minor py pseudomorph | 30 | <0.1 | 14.5 |
| 1878304 | Clayton Jones | 03-Jul-20 | 554183 | 6928000 | 845 | Gold Crest | Rock | float | grab | Schist | | | py lim | Float in soil pit (1320878), qrtz vein material with lim fracture fill, minor < 1 mm cubic py pseudomorphs in lim | <2 | <0.1 | 1.3 |
| 1878305 | Clayton Jones | 03-Jul-20 | 553859 | 6928625 | 848 | Gold Crest | Rock | outcrop | grab | Schist | sil | | lim | Large outcrop SE of min zone, strong sil quartz ser schist, local vuggy lim quartz zone (5 cm with fol), high-grade sample, slicken slide surface with fol | 3 | 0.3 | 11 |
| 1878306 | Clayton Jones | 03-Jul-20 | 553859 | 6928624 | 847 | Gold Crest | Rock | outcrop | grab | Schist | sil | | lim | Same outcrop as 1878305, qrtz ser schist, strong silic with lim cavities, increase graphite/shale with fol | 2 | 0.1 | 5.5 |
| 1878307 | Clayton Jones | 03-Jul-20 | 553871 | 6928616 | 848 | Gold Crest | Rock | outcrop | grab | Schist | sil | QV | lim | Same outcrop as 1878305, qrtz ser schist with 10 cm quartz vein, lim fracture fill | 2 | <0.1 | 4.8 |
| 1878308 | Clayton Jones | 05-Jul-20 | 554371 | 6929031 | 896 | Gold Crest | Rock | float | grab | schist | | | lim | Talus slabs under moss, sub crop?, crenulated qrtz ser schist, abundant lim filled voids, silicified, dark grey qrtz / phyllite lenses following fol | 8 | <0.1 | 13.5 |
| 1878309 | Clayton Jones | 05-Jul-20 | 554374 | 6929010 | 898 | Gold Crest | Rock | float | grab | schist | | QTSW, bx | py lim | Quartz bx / stw hosted in qrtz ser schist, float blocks (talus), narrow phyllite lamination with fol, < 1 mm cubic py pseudomorph, small drowsy / vuggy quartz crystal texture locally | 91 | <0.1 | 90.7 |
| 1878310 | Clayton Jones | 05-Jul-20 | 554376 | 6929014 | 900 | Gold Crest | Rock | float | grab | schist | | | lim | Similar to 1878308 but increase dark grey laminations with fol and increase lim filled voids, talus under moss | 5 | <0.1 | 10.5 |
| 1878311 | Clayton Jones | 05-Jul-20 | 554439 | 6929101 | 871 | Gold Crest | Rock | outcrop | grab | schist | sil clay | QTSW | lim | Large 4 x 4 m outcrop, prominent slicken slide surfaces, qrtz ser schist with strong clay alt, phyllitic texture, dark grey stringers / laminations with fol | 11 | 0.1 | 10.1 |

| GENERAL | | | LOCATION | | | | SAMPLE | | | GEOLOGY | | | | | Au (ppb) | Ag (ppm) | As (ppm) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Sample ID | User | Date | Easting | Northing | Altitude (m) | Area | Material | Exposure | Sample type | Litholog y | Alt'n | Veining | Min | Description | | | |
| 1878312 | Clayton Jones | 05-Jul-20 | 554444 | 6929102 | 873 | Gold Crest | Rock | outcrop | grab | schist | sil clay | QV | lim | Same outcrop as 1878311, strong altered portion, strong silic and clay alt, patchy vuggy voids filled with limonite, sub brecciated with dark qrtz matrix | 12 | 0.1 | 9.9 |
| 1878313 | Clayton Jones | 05-Jul-20 | 554341 | 6929197 | 813 | Gold Crest | Rock | float | grab | schist | sil | Qstr | lim, py | Angular float block sticking out of permafrost slope, strong silic schist, very fine diss'd sulphide < 1% in dark quartz matrix, < 1 mm lim/qrtz stringers | 4 | <0.1 | 11.2 |
| 1878314 | Clayton Jones | 05-Jul-20 | 554289 | 6929270 | 771 | Gold Crest | Rock | float | grab | schist | | | lim | Oxidized float talus taken from soil sample site (1320898),dark grey cherty laminations < 5mm with fol, strong oxidation with abundant lim, coarse tex gabbro found in talus pit also but not in sample? | <2 | <0.1 | 4 |
| 1878315 | Clayton Jones | 06-Jul-20 | 554884 | 6929616 | 805 | Gold Crest | Rock | float | grab | schist | | QTSW | lim py | Float block stumbled across while hiking back to camp, no investigation, strong silic schist / qtsw with lim and < 2mm cubic py pseudomorphs | 10 | <0.1 | 47.3 |
| 1878316 | Clayton Jones | 07-Jul-20 | 554277 | 6930718 | 757 | Dovetail | Rock | outcrop | grab | schist | | QTSW | lim | Intense quartz stockwork in phylitic schist / gneiss outcrop, strong shear fabric with crenulations forming, lim fractures | 9 | 0.1 | 7.4 |
| 1878317 | Clayton Jones | 07-Jul-20 | 554280 | 6930711 | 767 | Dovetail | Rock | outcrop | grab | schist | | QTSW | lim | 40 cm chip sample across quartz stockwork in schist outcrop, limonitic with strong sericite altn | 11 | <0.1 | 16.6 |
| 1878318 | Clayton Jones | 07-Jul-20 | 554536 | 6930619 | 789 | Dovetail | Rock | float | grab | schist | | drk str | lim | Greenish beige sericite schist, dark grey stringers, patchy lim fractures | 5 | <0.1 | 2.3 |
| 1878319 | Clayton Jones | 07-Jul-20 | 554545 | 6930581 | 794 | Dovetail | Rock | float | grab | schist | | | py lim | Float, non abundant, strong alt'd quartz vein material, strong oxidation with vuggy limonite filled voids, py pseudomorphs | 42 | 0.1 | 63.6 |
| 1878320 | Clayton Jones | 07-Jul-20 | 554523 | 6930607 | 773 | Dovetail | Rock | float | grab | quartzite | | drk str | lim | Quartzite float, milky white, dark grey stringers < 1 mm | 2 | <0.1 | 0.6 |
| 1878321 | Clayton Jones | 07-Jul-20 | 554338 | 6930655 | 781 | Dovetail | Rock | outcrop | grab | schist | | QV | py lim | 10 cm quartz vein with fol hosted in sericite schist, oxi cubic py up to 2 mm, | <2 | <0.1 | 1.1 |
| 1878322 | Clayton Jones | 06-Jul-20 | 556200 | 6929600 | 1011 | off claims | Rock | float | grab | bx qv | sil | bx | lim | Strong silicified and oxidized sericite schist, sub brecciated | 21 | 0.7 | 266.4 |
| 1878323 | Clayton Jones | 10-Jul-20 | 553514 | 6928679 | 786 | Gold Crest | Rock | float | grab | schist | sil | QTSW | lim py | Large 75 cm long float slab, good qtsw in light grey silic qrtz sericite schist, limonitic fracture, tr py pseudomorphs | 45 | <0.1 | 94.8 |
| 1878324 | Clayton Jones | 10-Jul-20 | 553514 | 6928679 | 786 | Gold Crest | Rock | float | grab | qv | | QV | lim | White quartz vein material in ser schist float block (sample 1878323), lim and graphite stringers | 107 | <0.1 | 320.6 |
| 1878325 | Clayton Jones | 10-Jul-20 | 553511 | 6928627 | 822 | Gold Crest | Rock | float | grab | schist | sil | Qstr | py lim | Sample pit at historic soil 1553236, approx. 60 cm deep, float blocks of sil oxi ser schist resting on top of glacial till, marks limit of glacial till, abundant lim filled fractures and tr py pseudomorphs | 77 | <0.1 | 359.4 |
| 1878326 | Clayton Jones | 10-Jul-20 | 553529 | 6928646 | 780 | Gold Crest | Rock | float | grab | schist | sil | QTSW | lim | Angular float block 1 m wide, light grey silicified schist with good qtsw and sheeted veinlets ( < 5 mm thick), lim fractures | 100 | <0.1 | 460.3 |
| 1878327 | Clayton Jones | 10-Jul-20 | 553644 | 6928861 | 799 | Gold Crest | Rock | float | grab | schist | | | | Sample pit at historic soil (1513853), bottom of 1.2 m pit, rep sample of C horizon soil and rock fragments, brown orange clay rich soil with quartz and oxi ser schist | 176 | 0.6 | 926.7 |
| 1878328 | Clayton Jones | 10-Jul-20 | 553644 | 6928861 | 799 | Gold Crest | Rock | float | grab | schist | | | py lim | Sample pit, 1.2 m, crenulated quartz sericite schist with dark pinch and swell quartz? lenses with fol < 5 mm thick, tr py pseodomorphs, oxi with lim frac | 5 | <0.1 | 16.9 |
| 1878329 | Clayton Jones | 10-Jul-20 | 553644 | 6928861 | 799 | Gold Crest | Rock | float | grab | schist | | QTCSW | py pseudos | Dark grey graphite schist with 1 -2 % cubic py pseudomorphs < 2 mm, fine qtsw | 71 | 0.2 | 42.3 |
| 1878330 | Clayton Jones | 10-Jul-20 | 553644 | 6928861 | 799 | Gold Crest | Rock | float | grab | schist | | QV | py | White quartz vein material in ser schist, later stage beige stained stringers in quartz, 1 -2 % fresh py diss'd, | 20 | 0.6 | 71.4 |

Appendix IV: Soil Sample Descriptions

## Soil Sample Descriptions

UTM NAD83 Zone 7

| GENERAL | | | LOCATION | | | | SAMPLE DESCRIPTION | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Sample Composition (%) | | | | | | | | | |
| Sample ID | User | Date | Easting | Northing | Alt. (m) | Area | Sample Depth (cm) | Horizon Sampled | Sample Colour | Organics | Ang. Rock | Gravel | Sand | Silt | Clay | Parent Material | Moisture Content | Vegetation Cover | Topo Position | Comments |
| 1320801 | Clayton Jones | 30-Jun-20 | 556158 | 6934156 | 1030 | Northeast | 40 | b/c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320802 | Clayton Jones | 30-Jun-20 | 556158 | 6934106 | 1025 | Northeast | 60 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320803 | Clayton Jones | 30-Jun-20 | 556156 | 6934056 | 1020 | Northeast | 60 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320804 | Clayton Jones | 30-Jun-20 | 556154 | 6934005 | 1017 | Northeast | 60 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320805 | Clayton Jones | 30-Jun-20 | 556158 | 6933956 | 1008 | Northeast | 75 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320806 | Clayton Jones | 30-Jun-20 | 556163 | 6933906 | 1003 | Northeast | 75 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320807 | Clayton Jones | 30-Jun-20 | 556161 | 6933856 | 999 | Northeast | 50 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320808 | Clayton Jones | 30-Jun-20 | 556169 | 6933806 | 991 | Northeast | 100 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | sugary texture |
| 1320809 | Clayton Jones | 30-Jun-20 | 556168 | 6933754 | 983 | Northeast | 75 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | qrtz chips |
| 1320810 | Clayton Jones | 30-Jun-20 | 556170 | 6933706 | 976 | Northeast | 75 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | qrtz chips |
| 1320811 | Clayton Jones | 30-Jun-20 | 556172 | 6933657 | 970 | Northeast | 75 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | rock chips |
| 1320812 | Clayton Jones | 30-Jun-20 | 556179 | 6933608 | 961 | Northeast | 60 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | qrtz chips |
| 1320813 | Clayton Jones | 30-Jun-20 | 556193 | 6933562 | 954 | Northeast | 60 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320814 | Clayton Jones | 30-Jun-20 | 556196 | 6933508 | 950 | Northeast | 50 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | qrtz chips |
| 1320815 | Clayton Jones | 30-Jun-20 | 556210 | 6933462 | 943 | Northeast | 50 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | qrtz chips |
| 1320816 | Clayton Jones | 30-Jun-20 | 556213 | 6933409 | 941 | Northeast | 50 | b/c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | rocky silt |
| 1320817 | Clayton Jones | 30-Jun-20 | 556219 | 6933358 | 939 | Northeast | 100 | b/c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | rocky silt with qrtz chips |
| 1320818 | Clayton Jones | 30-Jun-20 | 556229 | 6933310 | 935 | Northeast | 60 | b/c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | rocky silt with qrtz chips |
| 1320819 | Clayton Jones | 30-Jun-20 | 556229 | 6933262 | 923 | Northeast | 70 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | rocky |
| 1320820 | Clayton Jones | 30-Jun-20 | 556230 | 6933210 | 932 | Northeast | 50 | c | beige | | | | | | | weathered bedrock | moist | mix / burn | mid slope | unique feldspar rich |
| 1320822 | Clayton Jones | 30-Jun-20 | 556205 | 6933113 | 934 | Northeast | 40 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320823 | Clayton Jones | 30-Jun-20 | 556191 | 6933068 | 930 | Northeast | 50 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320825 | Clayton Jones | 30-Jun-20 | 556162 | 6932971 | 922 | Northeast | 40 | c | grey brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320826 | Clayton Jones | 30-Jun-20 | 556156 | 6932922 | 914 | Northeast | 60 | c | grey brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320827 | Clayton Jones | 30-Jun-20 | 556133 | 6932876 | 913 | Northeast | 60 | b/c | dark brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | rocky |
| 1320828 | Clayton Jones | 30-Jun-20 | 556114 | 6932833 | 906 | Northeast | 100 | c | grey brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320829 | Clayton Jones | 30-Jun-20 | 556098 | 6932785 | 903 | Northeast | 30 | c | light brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320830 | Clayton Jones | 30-Jun-20 | 556070 | 6932738 | 892 | Northeast | 50 | c | light brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | good sample |
| 1320831 | Clayton Jones | 30-Jun-20 | 556045 | 6932696 | 878 | Northeast | 30 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320832 | Clayton Jones | 30-Jun-20 | 556025 | 6932652 | 867 | Northeast | 30 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320833 | Clayton Jones | 30-Jun-20 | 556008 | 6932604 | 846 | Northeast | 50 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320834 | Clayton Jones | 30-Jun-20 | 555988 | 6932560 | 832 | Northeast | 30 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320835 | Clayton Jones | 30-Jun-20 | 555962 | 6932510 | 812 | Northeast | 60 | b/c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320836 | Clayton Jones | 30-Jun-20 | 555924 | 6932416 | 786 | Northeast | 120 | b/c | brown | | | | | | | till | wet | mix / burn | mid slope | silt clay wet |
| 1320837 | Clayton Jones | 30-Jun-20 | 555902 | 6932334 | 754 | Northeast | 90 | b/c | brown | | | | | | | till | wet | mix / burn | mid slope | silt clay wet |
| 1320838 | Clayton Jones | 2-Jul-20 | 552073 | 6929024 | 771 | Marksmen | 75 | b/c | brown grey | | | | | | | till | moist | mix / burn | mid slope | |
| 1320839 | Clayton Jones | 2-Jul-20 | 552018 | 6929043 | 777 | Marksmen | 50 | b/c | brown grey | | | | | | | till | moist | mix / burn | mid slope | |
| 1320840 | Clayton Jones | 2-Jul-20 | 551608 | 6929206 | 672 | Marksmen | 30 | b/c | brown | | | | | | | talus | moist | mix / burn | mid slope | |
| 1320841 | Clayton Jones | 2-Jul-20 | 551472 | 6929194 | 627 | Marksmen | 40 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320842 | Clayton Jones | 2-Jul-20 | 551513 | 6929174 | 639 | Marksmen | 40 | c | brown | | | | | | | weathered bedrock | moist | mix / burn | mid slope | |
| 1320843 | Clayton Jones | 2-Jul-20 | 551560 | 6929158 | 669 | Marksmen | 75 | b/c | grey | | | | | | | talus | moist | mix / burn | steep slope | permafrost |
| 1320844 | Clayton Jones | 2-Jul-20 | 551610 | 6929143 | 694 | Marksmen | 40 | c | light brown | | | | | | | weathered bedrock | dry | mix / burn | steep slope | |
| 1320845 | Clayton Jones | 2-Jul-20 | 551655 | 6929123 | 712 | Marksmen | 60 | b/c | dark brown | | | | | | | till | moist | mix / burn | mid slope | |
| 1320846 | Clayton Jones | 2-Jul-20 | 551701 | 6929108 | 733 | Marksmen | 30 | b/c | brown | | | | | | | till | moist | mix / burn | mid slope | |
| 1320847 | Clayton Jones | 2-Jul-20 | 551753 | 6929088 | 752 | Marksmen | 60 | b | brown | | | | | | | till | moist | mix / burn | mid slope | permafrost |
| 1320848 | Clayton Jones | 2-Jul-20 | 551805 | 6929070 | 765 | Marksmen | 60 | b | brown | | | | | | | till | moist | mix / burn | mid slope | |
| 1320849 | Clayton Jones | 2-Jul-20 | 551850 | 6929057 | 774 | Marksmen | 50 | b/c | brown grey | | | | | | | till | moist | mix / burn | mid slope | |
| 1320850 | Clayton Jones | 2-Jul-20 | 551891 | 6929045 | 777 | Marksmen | 70 | b/c | brown grey | | | | | | | till | moist | mix / burn | mid slope | |
| 1320851 | Clayton Jones | 2-Jul-20 | 551939 | 6929029 | 779 | Marksmen | 80 | b/c | brown grey | | | | | | | till | moist | mix / burn | mid slope | |
| 1320852 | Clayton Jones | 2-Jul-20 | 551988 | 6929011 | 772 | Marksmen | 80 | b/c | brown grey | | | | | | | till | moist | mix / burn | mid slope | |
| 1320853 | Clayton Jones | 2-Jul-20 | 552039 | 6928998 | 769 | Marksmen | 50 | b/c | brown | | | | | | | till | moist | mix / burn | mid slope | |
| 1320854 | Clayton Jones | 2-Jul-20 | 552079 | 6928977 | 760 | Marksmen | 100 | b/c | grey | | | | | | | till | moist | mix / burn | mid slope | |
| 1320855 | Clayton Jones | 2-Jul-20 | 552127 | 6928966 | 756 | Marksmen | 80 | b/c | brown | | | | | | | till | moist | mix / burn | mid slope | |
| 1320856 | Clayton Jones | 2-Jul-20 | 552174 | 6928950 | 746 | Marksmen | 100 | b | brown | | | | | | | till | moist | mix / burn | mid slope | |
| 1320857 | Clayton Jones | 2-Jul-20 | 552217 | 6928932 | 740 | Marksmen | 100 | b | brown | | | | | | | till | moist | mix / burn | mid slope | |
| 1320858 | Clayton Jones | 2-Jul-20 | 552258 | 6929023 | 735 | Marksmen | 75 | b/c | brown | | | | | | | till | moist | mix / burn | mid slope | |
| 1320859 | Clayton Jones | 2-Jul-20 | 552208 | 6929038 | 741 | Marksmen | 50 | b/c | brown grey | | | | | | | till | moist | mix / burn | mid slope | |
| 1320860 | Clayton Jones | 3-Jul-20 | 554711 | 6928663 | 1009 | Goldcrest | 65 | c | light brown | | | | | | | weathered bedrock | moist | burn | mid slope | |
| 1320861 | Clayton Jones | 3-Jul-20 | 554702 | 6928613 | 998 | Goldcrest | 40 | c | dark brown | | | | | | | weathered bedrock | moist | burn | mid slope | waxy shale clasts |
| 1320862 | Clayton Jones | 3-Jul-20 | 554685 | 6928570 | 990 | Goldcrest | 70 | c | grey | | | | | | | weathered bedrock | moist | burn | mid slope | oxi waxy shale |
| 1320863 | Clayton Jones | 3-Jul-20 | 554674 | 6928519 | 980 | Goldcrest | 70 | c | grey | | | | | | | weathered bedrock | moist | burn | mid slope | oxi waxy shale |
| 1320864 | Clayton Jones | 3-Jul-20 | 554656 | 6928474 | 973 | Goldcrest | 80 | c | dark brown | | | | | | | weathered bedrock | moist | burn | mid slope | increase clay |
| 1320865 | Clayton Jones | 3-Jul-20 | 554622 | 6928435 | 962 | Goldcrest | 80 | c | dark brown | | | | | | | weathered bedrock | moist | burn | mid slope | bear encounter |
| 1320866 | Clayton Jones | 3-Jul-20 | 554576 | 6928414 | 953 | Goldcrest | 40 | c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | |
| 1320867 | Clayton Jones | 3-Jul-20 | 554545 | 6928375 | 938 | Goldcrest | 60 | c | brown | | | | | | | weathered bedrock | wet/perm | burn | mid slope | tree stump |
| 1320868 | Clayton Jones | 3-Jul-20 | 554521 | 6928327 | 931 | Goldcrest | 60 | c | grey | | | | | | | weathered bedrock | moist | burn | mid slope | good sample, increase oxi shale |

| GENERAL | | | LOCATION | | | | SAMPLE DESCRIPTION | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Sample Composition (%) | | | | | | | | | |
| Sample ID | User | Date | Easting | Northing | Alt. (m) | Area | Sample Depth (cm) | Horizon Sampled | Sample Colour | Organics | Ang. Rock | Gravel | Sand | Silt | Clay | Parent Material | Moisture Content | Vegetation Cover | Topo Position | Comments |
| 1320869 | Clayton Jones | 3-Jul-20 | 554485 | 6928290 | 919 | Goldcrest | 80 | c | light grey | | | | | | | weathered bedrock | dry | burn | mid slope | good sample, oxi waxy shale |
| 1320870 | Clayton Jones | 3-Jul-20 | 554444 | 6928260 | 909 | Goldcrest | 60 | c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | dark grey matrix supported bx clasts in sample |
| 1320871 | Clayton Jones | 3-Jul-20 | 554431 | 6928209 | 904 | Goldcrest | 50 | b/c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | shale |
| 1320872 | Clayton Jones | 3-Jul-20 | 554401 | 6928166 | 896 | Goldcrest | 60 | c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | |
| 1320873 | Clayton Jones | 3-Jul-20 | 554374 | 6928126 | 888 | Goldcrest | 60 | c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | increase oxi clay with quartz chips |
| 1320874 | Clayton Jones | 3-Jul-20 | 554348 | 6928085 | 884 | Goldcrest | 60 | c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | increase oxi clay with quartz chips |
| 1320875 | Clayton Jones | 3-Jul-20 | 554318 | 6928041 | 878 | Goldcrest | 50 | b/c | dark brown | | | | | | | weathered bedrock | moist | burn | mid slope | |
| 1320876 | Clayton Jones | 3-Jul-20 | 554272 | 6928023 | 868 | Goldcrest | 50 | b/c | dark brown | | | | | | | weathered bedrock | moist | burn | mid slope | |
| 1320877 | Clayton Jones | 3-Jul-20 | 554226 | 6928013 | 856 | Goldcrest | 50 | b/c | dark brown | | | | | | | weathered bedrock | moist | burn | mid slope | |
| 1320878 | Clayton Jones | 3-Jul-20 | 554179 | 6927998 | 846 | Goldcrest | 70 | b/c | dark brown | | | | | | | weathered bedrock | moist | burn | mid slope | |
| 1320879 | Clayton Jones | 3-Jul-20 | 554125 | 6927990 | 829 | Goldcrest | 80 | b/c | dark brown | | | | | | | weathered bedrock | moist | burn | mid slope | |
| 1320880 | Clayton Jones | 3-Jul-20 | 554081 | 6927974 | 817 | Goldcrest | 50 | c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | abundant volcanic porphyry (dark green fine texture matrix with beige to white feldspar? Clasts) |
| 1320881 | Clayton Jones | 4-Jul-20 | 553138 | 6928426 | 752 | Goldcrest | 100 | c | brown | | | | | | | till | moist | burn | mid slope | increase clay |
| 1320882 | Clayton Jones | 4-Jul-20 | 552860 | 6928104 | 700 | Goldcrest | 70 | c | grey brown | | | | | | | till | moist | burn | mid slope | |
| 1320883 | Clayton Jones | 4-Jul-20 | 552830 | 6928146 | 705 | Goldcrest | 70 | c | grey brown | | | | | | | till | moist | burn | mid slope | |
| 1320884 | Clayton Jones | 4-Jul-20 | 552798 | 6928186 | 699 | Goldcrest | 60 | c | grey brown | | | | | | | till | permafrost | burn | mid slope | |
| 1320885 | Clayton Jones | 4-Jul-20 | 552766 | 6928226 | 698 | Goldcrest | 40 | a/b | black | | | | | | | till | permafrost | burn | mid slope | |
| 1320886 | Clayton Jones | 4-Jul-20 | 552905 | 6928363 | 731 | Goldcrest | 80 | c | grey brown | | | | | | | till | moist | burn | mid slope | |
| 1320887 | Clayton Jones | 4-Jul-20 | 552950 | 6928330 | 729 | Goldcrest | 40 | a/b | dark brown | | | | | | | till | permafrost | burn | mid slope | |
| 1320888 | Clayton Jones | 4-Jul-20 | 552972 | 6928289 | 726 | Goldcrest | 100 | c | grey | | | | | | | till | moist | burn | mid slope | |
| 1320889 | Clayton Jones | 4-Jul-20 | 553003 | 6928246 | 729 | Goldcrest | 50 | c | brown grey | | | | | | | till | wet | burn | mid slope | |
| 1320890 | Clayton Jones | 4-Jul-20 | 553032 | 6928207 | 730 | Goldcrest | 110 | c | grey brown | | | | | | | till | wet | burn | mid slope | |
| 1320891 | Clayton Jones | 4-Jul-20 | 553065 | 6928169 | 731 | Goldcrest | 110 | c | grey brown | | | | | | | till | wet | burn | mid slope | |
| 1320892 | Clayton Jones | 5-Jul-20 | 554486 | 6929035 | 900 | Goldcrest | 50 | b/c | brown | | | | | | | weathered bedrock | moist | buck brush | mid slope | |
| 1320893 | Clayton Jones | 5-Jul-20 | 554451 | 6929076 | 883 | Goldcrest | 20 | b/c | brown | | | | | | | weathered bedrock | dry | buck brush | mid slope | |
| 1320894 | Clayton Jones | 5-Jul-20 | 554426 | 6929120 | 867 | Goldcrest | 30 | a/b | brown | | | | | | | weathered bedrock | permafrost | evergreen forest | mid slope | |
| 1320895 | Clayton Jones | 5-Jul-20 | 554382 | 6929158 | 846 | Goldcrest | 30 | a/b | brown | | | | | | | weathered bedrock | permafrost | evergreen forest | mid slope | |
| 1320896 | Clayton Jones | 5-Jul-20 | 554346 | 6929191 | 821 | Goldcrest | 30 | a/b | brown | | | | | | | weathered bedrock | permafrost | evergreen forest | mid slope | |
| 1320897 | Clayton Jones | 5-Jul-20 | 554307 | 6929229 | 791 | Goldcrest | 30 | a/b | brown | | | | | | | weathered bedrock | permafrost | evergreen forest | mid slope | |
| 1320898 | Clayton Jones | 5-Jul-20 | 554289 | 6929270 | 771 | Goldcrest | 30 | a/b | brown | | | | | | | weathered bedrock | permafrost | evergreen forest | mid slope | |
| 1320899 | Clayton Jones | 5-Jul-20 | 554215 | 6929358 | 757 | Goldcrest | 30 | a/b | brown | | | | | | | weathered bedrock | permafrost | evergreen forest | mid slope | |
| 1320900 | Clayton Jones | 5-Jul-20 | 554190 | 6929405 | 755 | Goldcrest | 30 | a/b | brown | | | | | | | weathered bedrock | permafrost | buck brush | mid slope | |
| 1320901 | Clayton Jones | 5-Jul-20 | 554161 | 6929441 | 755 | Goldcrest | 90 | c | brown | | | | | | | till | permafrost | buck brush | mid slope | |
| 1320902 | Clayton Jones | 5-Jul-20 | 554117 | 6929481 | 746 | Goldcrest | 60 | b/c | brown | | | | | | | till | permafrost | buck brush | mid slope | |
| 1320903 | Clayton Jones | 6-Jul-20 | 556176 | 6929702 | 988 | Goldcrest | 40 | b/c | brown | | | | | | | weathered bedrock | moist | burn | ridge top | |
| 1320904 | Clayton Jones | 6-Jul-20 | 556141 | 6929733 | 982 | Goldcrest | 40 | b | brown | | | | | | | weathered bedrock | moist | burn | ridge top | |
| 1320905 | Clayton Jones | 6-Jul-20 | 556108 | 6929782 | 973 | Goldcrest | 90 | c | dark grey | | | | | | | weathered bedrock | dry | burn | saddle | sooty black texture, geo change / fault? |
| 1320906 | Clayton Jones | 6-Jul-20 | 556097 | 6929805 | 972 | Goldcrest | 50 | c | brown | | | | | | | weathered bedrock | moist | burn | saddle | |
| 1320907 | Clayton Jones | 6-Jul-20 | 556075 | 6929855 | | Goldcrest | 40 | c | brown | | | | | | | weathered bedrock | moist | burn | ridge top | |
| 1320908 | Clayton Jones | 6-Jul-20 | 556062 | 6929899 | | Goldcrest | 10 | b/c | brown | | | | | | | weathered bedrock | moist | burn | ridge top | gabbro |
| 1320909 | Clayton Jones | 6-Jul-20 | 556070 | 6929992 | 963 | Goldcrest | 20 | b/c | brown | | | | | | | weathered bedrock | moist | burn | ridge top | poor soil development in talus |
| 1320910 | Clayton Jones | 6-Jul-20 | 556059 | 6930091 | 928 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | ridge top | poor soil development in talus |
| 1320911 | Clayton Jones | 6-Jul-20 | 556052 | 6930177 | 944 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | ridge top | poor soil development in talus |
| 1320912 | Clayton Jones | 6-Jul-20 | 556059 | 6930226 | 960 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | ridge top | poor soil development in talus |
| 1320913 | Clayton Jones | 6-Jul-20 | 556065 | 6930281 | 947 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | ridge top | poor soil development in talus |
| 1320914 | Clayton Jones | 6-Jul-20 | 556034 | 6930320 | 933 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | ridge top | poor soil development in talus |
| 1320915 | Clayton Jones | 6-Jul-20 | 556002 | 6930430 | 901 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | ridge top | poor soil development in talus |
| 1320916 | Clayton Jones | 6-Jul-20 | 556018 | 6930369 | 903 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | ridge top | poor soil development in talus |
| 1320917 | Clayton Jones | 6-Jul-20 | 555993 | 6930481 | 886 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | ridge top | poor soil development in talus |
| 1320918 | Clayton Jones | 6-Jul-20 | 556001 | 6930535 | 868 | Goldcrest | 40 | a/b | dark brown | | | | | | | weathered bedrock | permafrost | burn | mid slope | poor soil development in talus |
| 1320919 | Clayton Jones | 6-Jul-20 | 556001 | 6930584 | 840 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | poor soil development in talus |
| 1320920 | Clayton Jones | 6-Jul-20 | 556006 | 6930634 | 812 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | poor soil development in talus |
| 1320921 | Clayton Jones | 6-Jul-20 | 556018 | 6930679 | 794 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | poor soil development in talus |
| 1320922 | Clayton Jones | 6-Jul-20 | 556032 | 6930742 | 767 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | poor soil development in talus |
| 1320923 | Clayton Jones | 6-Jul-20 | 556055 | 6930791 | 734 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | poor soil development in talus |
| 1320924 | Clayton Jones | 6-Jul-20 | 556100 | 6930835 | 735 | Goldcrest | 30 | b/c | brown | | | | | | | weathered bedrock | moist | burn | mid slope | poor soil development in talus |
| 1320925 | Gary Drinan | 9-Jul-20 | 554032 | 6928499 | 812 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1320926 | Gary Drinan | 9-Jul-20 | 553993 | 6928510 | 809 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1320927 | Gary Drinan | 9-Jul-20 | 553933 | 6928510 | 805 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1320928 | Gary Drinan | 9-Jul-20 | 553887 | 6928521 | 805 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1320929 | Gary Drinan | 9-Jul-20 | 553837 | 6928525 | 808 | Goldcrest | 60 | b/c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1320930 | Gary Drinan | 9-Jul-20 | 553792 | 6928529 | 810 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | df | moist | |
| 1320931 | Gary Drinan | 9-Jul-20 | 553742 | 6928544 | 810 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | df | moist | |
| 1320932 | Gary Drinan | 9-Jul-20 | 553696 | 6928546 | 803 | Goldcrest | 30 | c | light brown | | | | | | | weathered bedrock | dry | df | moist | |

| GENERAL | | | LOCATION | | | | SAMPLE DESCRIPTION | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Sample Composition (%) | | | | | | | | | |
| Sample ID | User | Date | Easting | Northing | Alt. (m) | Area | Sample Depth (cm) | Horizon Sampled | Sample Colour | Organics | Ang. Rock | Gravel | Sand | Silt | Clay | Parent Material | Moisture Content | Vegetation Cover | Topo Position | Comments |
| 1321001 | Phil Severinsen | 2-Jul-20 | 552290 | 6929120 | 718 | Marksmen | 50 | B | Brown/Grey | 10 | 10 | | | 60 | 20 | Till | Frozen | Old Burn | Mid-Slope | |
| 1321002 | Phil Severinsen | 2-Jul-20 | 552243 | 6929134 | 725 | Marksmen | 70 | B/C | Brown/Grey | | 20 | | 40 | 40 | | Till | Moist | Old Burn | Mid-Slope | |
| 1321003 | Phil Severinsen | 2-Jul-20 | 552195 | 6929148 | 731 | Marksmen | 80 | B/C | Brown/Grey | 5 | 20 | | 25 | 50 | | Till | Moist | Old Burn | Mid-Slope | |
| 1321004 | Phil Severinsen | 2-Jul-20 | 552149 | 6929168 | 736 | Marksmen | 50 | B/C | Brown | | 10 | | 30 | 60 | | Till | Moist | Old Burn | Mid-Slope | |
| 1321005 | Phil Severinsen | 2-Jul-20 | 552102 | 6929186 | 741 | Marksmen | 50 | B | Brown/Grey | 10 | 20 | | 20 | 50 | | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321006 | Phil Severinsen | 2-Jul-20 | 552053 | 6929200 | 745 | Marksmen | 60 | B/C | Brown | 10 | 20 | | 10 | 20 | 50 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321007 | Phil Severinsen | 2-Jul-20 | 552007 | 6929217 | 744 | Marksmen | 60 | B/C | Brown | | 20 | | 20 | 20 | 40 | Till | Moist | Old Burn | Mid-Slope | |
| 1321008 | Phil Severinsen | 2-Jul-20 | 551959 | 6929233 | 736 | Marksmen | 80 | A/B | Dark Grey | 20 | 20 | | | 30 | 30 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321009 | Phil Severinsen | 2-Jul-20 | 551904 | 6929244 | 725 | Marksmen | 60 | B | Brown/Grey | 10 | 10 | | | 40 | 40 | Till | Frozen | Old Burn | Mid-Slope | Moved due to Drainage |
| 1321010 | Phil Severinsen | 2-Jul-20 | 551865 | 6929266 | 709 | Marksmen | 60 | B | Brown | 10 | 10 | | | 40 | 40 | Till | Frozen | Deciduous | Steep Slope | |
| 1321011 | Phil Severinsen | 2-Jul-20 | 551817 | 6929283 | 688 | Marksmen | 60 | B/C | Brown/Grey | 5 | 15 | | 20 | 30 | 30 | Till | Partially Frozen | Deciduous | Steep Slope | |
| 1321012 | Phil Severinsen | 2-Jul-20 | 551771 | 6929301 | 667 | Marksmen | 80 | B/C | Brown/Grey | 5 | 15 | | 40 | 20 | 20 | Till | Moist | Deciduous | Mid-Slope | |
| 1321013 | Phil Severinsen | 2-Jul-20 | 551723 | 6929315 | 653 | Marksmen | 70 | B/C | Brown/Grey | | 20 | | 20 | | 60 | Till | Moist | Old Burn | Mid-Slope | |
| 1321014 | Phil Severinsen | 2-Jul-20 | 551675 | 6929333 | 642 | Marksmen | 50 | B | Grey | 10 | 20 | | 30 | 20 | 20 | Weathered Bedrock | Frozen | Old Burn | Bench | |
| 1321015 | Phil Severinsen | 2-Jul-20 | 551628 | 6929350 | 638 | Marksmen | 50 | B/C | Brown | 10 | 10 | | | 40 | 40 | Weathered Bedrock | Frozen | Old Burn | Bench | |
| 1321016 | Phil Severinsen | 2-Jul-20 | 551579 | 6929361 | 634 | Marksmen | 70 | C | Light Brown | | 10 | | 20 | | 70 | Weathered Bedrock | Frozen | Old Burn | Mid-Slope | |
| 1321017 | Phil Severinsen | 2-Jul-20 | 551534 | 6929379 | 622 | Marksmen | 40 | B/C | Light Brown | | 30 | | 60 | 10 | | Weathered Bedrock | Moist | Old Burn | Bench | |
| 1321018 | Phil Severinsen | 2-Jul-20 | 551434 | 6929097 | 612 | Marksmen | 50 | C | Light Brown | 5 | 15 | | 20 | 60 | | Weathered Bedrock | Dry | Evergreen Forest | Mid-Slope | |
| 1321019 | Phil Severinsen | 2-Jul-20 | 551482 | 6929082 | 631 | Marksmen | 60 | B/C | Light Grey | | 10 | | 60 | 30 | | Weathered Bedrock | Moist | Deciduous | Mid-Slope | |
| 1321020 | Phil Severinsen | 2-Jul-20 | 551529 | 6929064 | 665 | Marksmen | 50 | C | Light Grey | | 10 | | 20 | 20 | 50 | Weathered Bedrock | Moist | Old Burn | Steep Slope | |
| 1321021 | Phil Severinsen | 2-Jul-20 | 551575 | 6929046 | 681 | Marksmen | 50 | C | Light Brown | | 20 | | 40 | 40 | | Weathered Bedrock | Dry | Old Burn | Steep Slope | |
| 1321022 | Phil Severinsen | 2-Jul-20 | 551624 | 6929030 | 711 | Marksmen | 40 | B/C | Brown/Grey | | 20 | | 40 | 40 | | Weathered Bedrock | Dry | Old Burn | Mid-Slope | Outcrop Nearby |
| 1321023 | Phil Severinsen | 2-Jul-20 | 551672 | 6929018 | 736 | Marksmen | 60 | B/C | Brown | | 20 | | | 20 | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321024 | Phil Severinsen | 2-Jul-20 | 551718 | 6928999 | 753 | Marksmen | 70 | B/C | Brown/Grey | | 20 | | | 20 | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321025 | Phil Severinsen | 2-Jul-20 | 551767 | 6928982 | 764 | Marksmen | 50 | C | Light Brown | | 20 | | | | 80 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321026 | Phil Severinsen | 2-Jul-20 | 551812 | 6928967 | 773 | Marksmen | 60 | C | Light Brown | | 20 | | 60 | | 20 | Weathered Bedrock | Moist | Old Burn | Ridge Top | |
| 1321027 | Phil Severinsen | 2-Jul-20 | 551859 | 6928951 | 775 | Marksmen | 80 | C | Light Brown | | 20 | | 60 | 20 | | Weathered Bedrock | Moist | Old Burn | Ridge Top | |
| 1321028 | Phil Severinsen | 2-Jul-20 | 551826 | 6928996 | 775 | Marksmen | 80 | B/C | Light Brown | | 20 | | 60 | | 20 | Weathered Bedrock | Moist | Old Burn | Ridge Top | |
| 1321029 | Phil Severinsen | 2-Jul-20 | 551781 | 6929015 | 768 | Marksmen | 70 | B/C | Brown | | 10 | | 20 | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321030 | Phil Severinsen | 2-Jul-20 | 551907 | 6928938 | 770 | Marksmen | 60 | B/C | Brown | | 20 | | 10 | | 70 | Weathered Bedrock | Moist | Evergreen Forest | Mid-Slope | |
| 1321031 | Phil Severinsen | 2-Jul-20 | 551954 | 6928920 | 756 | Marksmen | 60 | B/C | Brown | | 20 | | 10 | | 70 | Weathered Bedrock | Moist | Deciduous | Mid-Slope | |
| 1321032 | Phil Severinsen | 3-Jul-20 | 553883 | 6929493 | 730 | Gold Crest | 60 | C | Brown/Grey | | 20 | | 80 | | | Till | Moist | Old Burn | Valley Bottom | |
| 1321033 | Phil Severinsen | 3-Jul-20 | 553912 | 6929456 | 742 | Gold Crest | 50 | B/C | Brown | | 20 | | 20 | | 60 | Till | Moist | Old Burn | Valley Bottom | |
| 1321034 | Phil Severinsen | 3-Jul-20 | 553946 | 6929417 | 749 | Gold Crest | 90 | B | Brown | 10 | 10 | | | | 80 | Till | Partially Frozen | Old Burn | Valley Bottom | |
| 1321035 | Phil Severinsen | 3-Jul-20 | 553975 | 6929378 | 753 | Gold Crest | 80 | B | Brown | 10 | 10 | | | | 80 | Till | Partially Frozen | Old Burn | Valley Bottom | |
| 1321036 | Phil Severinsen | 3-Jul-20 | 554008 | 6929340 | 766 | Gold Crest | 50 | C | Light Brown | | 30 | | 40 | 30 | | Weathered Bedrock | Dry | Old Burn | Mid-Slope | |
| 1321037 | Phil Severinsen | 3-Jul-20 | 554039 | 6929300 | 781 | Gold Crest | 40 | B/C | Brown | 10 | 20 | | 20 | 50 | | Weathered Bedrock | Dry | Old Burn | Mid-Slope | |
| 1321038 | Phil Severinsen | 3-Jul-20 | 554053 | 6929280 | 787 | Gold Crest | 50 | C | Light Grey | | 30 | | 50 | | 20 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321039 | Phil Severinsen | 3-Jul-20 | 554069 | 6929260 | 792 | Gold Crest | 70 | C | Light Grey | | 30 | | 50 | | 20 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321040 | Phil Severinsen | 3-Jul-20 | 554086 | 6929242 | 799 | Gold Crest | 60 | B/C | Brown/Grey | | 20 | | 40 | | 40 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321041 | Phil Severinsen | 3-Jul-20 | 554100 | 6929222 | 805 | Gold Crest | 70 | B/C | Light Brown | | 20 | | 20 | | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321042 | Phil Severinsen | 3-Jul-20 | 554116 | 6929201 | 811 | Gold Crest | 60 | B/C | Brown | | 10 | | 20 | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321043 | Phil Severinsen | 3-Jul-20 | 554131 | 6929182 | 815 | Gold Crest | 70 | B/C | Light Brown | | 10 | | 20 | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321044 | Phil Severinsen | 3-Jul-20 | 554148 | 6929163 | 821 | Gold Crest | 90 | B/C | Brown/Grey | | 10 | | 10 | | 80 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321045 | Phil Severinsen | 3-Jul-20 | 554162 | 6929141 | 826 | Gold Crest | 70 | B/C | Brown/Grey | | 10 | | 10 | | 80 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321046 | Phil Severinsen | 3-Jul-20 | 554180 | 6929124 | 832 | Gold Crest | 60 | B/C | Brown/Grey | | 10 | | 20 | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321047 | Phil Severinsen | 3-Jul-20 | 554194 | 6929104 | 840 | Gold Crest | 70 | B | Brown/Grey | | 20 | | | 20 | 60 | Weathered Bedrock | Wet | Old Burn | Mid-Slope | |
| 1321048 | Phil Severinsen | 3-Jul-20 | 554228 | 6929066 | 858 | Gold Crest | 60 | B/C | Grey | | 10 | | 20 | 20 | 50 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321049 | Phil Severinsen | 3-Jul-20 | 554258 | 6929027 | 872 | Gold Crest | 80 | B/C | Brown/Grey | | 10 | | 20 | 30 | 40 | Weathered Bedrock | Wet | Old Burn | Mid-Slope | |
| 1321050 | Phil Severinsen | 3-Jul-20 | 554290 | 6928988 | 886 | Gold Crest | 80 | B/C | Brown | | 20 | | 20 | | 60 | Weathered Bedrock | Wet | Old Burn | Mid-Slope | |
| 1321051 | Phil Severinsen | 3-Jul-20 | 554321 | 6928948 | 900 | Gold Crest | 60 | B | Light Brown | 10 | 10 | | 20 | | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321052 | Phil Severinsen | 3-Jul-20 | 554352 | 6928911 | 912 | Gold Crest | 80 | B/C | Light Brown | | 10 | | 20 | 20 | 50 | Weathered Bedrock | Partially Frozen | Old Burn | Mid-Slope | |
| 1321053 | Phil Severinsen | 4-Jul-20 | 553714 | 6927677 | 739 | Gold Crest | 60 | B/C | Brown/Grey | 10 | | 10 | 30 | | 50 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321054 | Phil Severinsen | 4-Jul-20 | 553679 | 6927719 | 718 | Gold Crest | 70 | A/B | Dark Brown | 20 | | 10 | 10 | 60 | | Till | Frozen | Old Burn | Mid-Slope | |
| 1321055 | Phil Severinsen | 4-Jul-20 | 553654 | 6927760 | 703 | Gold Crest | 70 | B | Dark Grey | 10 | | 20 | 20 | | 50 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321056 | Phil Severinsen | 4-Jul-20 | 553611 | 6927792 | 688 | Gold Crest | 60 | B | Brown/Grey | 10 | | 20 | 10 | | 60 | Till | Partially Frozen | Old Burn | Valley Bottom | |
| 1321057 | Phil Severinsen | 4-Jul-20 | 553597 | 6927841 | 688 | Gold Crest | 70 | B | Dark Brown | 10 | | 10 | 10 | | 70 | Till | Partially Frozen | Old Burn | Valley Bottom | |
| 1321058 | Phil Severinsen | 4-Jul-20 | 553560 | 6927869 | 688 | Gold Crest | 60 | B | Brown | 10 | | 10 | | 40 | 40 | Till | Partially Frozen | Old Burn | Valley Bottom | |
| 1321059 | Phil Severinsen | 4-Jul-20 | 553529 | 6927916 | 689 | Gold Crest | 90 | B/C | Brown/Grey | | | 10 | 20 | 30 | 40 | Till | Partially Frozen | Old Burn | Valley Bottom | |
| 1321060 | Phil Severinsen | 4-Jul-20 | 553495 | 6927952 | 710 | Gold Crest | 50 | C | Light Brown | | 10 | 10 | | 40 | 40 | Till | Dry | Deciduous | Mid-Slope | |
| 1321061 | Phil Severinsen | 4-Jul-20 | 553469 | 6927993 | 726 | Gold Crest | 30 | C | Light Brown | | 10 | 20 | | 60 | 10 | Till | Dry | Deciduous | Mid-Slope | |
| 1321062 | Phil Severinsen | 4-Jul-20 | 553435 | 6928031 | 734 | Gold Crest | 40 | B/C | Light Brown | | 5 | 5 | | 40 | 40 | Till | Moist | Deciduous | Ridge Top | |
| 1321063 | Phil Severinsen | 4-Jul-20 | 553394 | 6928068 | 734 | Gold Crest | 50 | C | Brown/Grey | | 10 | 10 | 20 | 40 | 20 | Till | Dry | Deciduous | Bench | |
| 1321064 | Phil Severinsen | 4-Jul-20 | 553370 | 6928107 | 762 | Gold Crest | 50 | B/C | Light Brown | 10 | 10 | 10 | | 30 | 40 | Till | Dry | Deciduous | Bench | |
| 1321065 | Phil Severinsen | 4-Jul-20 | 553340 | 6928148 | 770 | Gold Crest | 40 | B/C | Light Brown | | 10 | 10 | | 40 | 40 | Till | Dry | Deciduous | Ridge Top | |
| 1321066 | Phil Severinsen | 4-Jul-20 | 553308 | 6928185 | 758 | Gold Crest | 70 | B/C | Light Grey | 10 | | 10 | | 40 | 40 | Till | Moist | Old Burn | Mid-Slope | |
| 1321067 | Phil Severinsen | 4-Jul-20 | 553278 | 6928227 | 751 | Gold Crest | 70 | B | Brown/Grey | | 10 | 10 | | 40 | 40 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321068 | Phil Severinsen | 4-Jul-20 | 553245 | 6928262 | 744 | Gold Crest | 60 | B/C | Brown/Grey | 20 | | 10 | | 40 | 30 | Till | Partially Frozen | Old Burn | Valley Bottom | |
| 1321069 | Phil Severinsen | 4-Jul-20 | 553184 | 6928342 | 741 | Gold Crest | 60 | A/B | Dark Brown | 10 | | 10 | | 40 | 40 | Till | Frozen | Old Burn | Valley Bottom | |
| 1321070 | Phil Severinsen | 4-Jul-20 | 553149 | 6928378 | 742 | Gold Crest | 80 | B | Brown/Grey | 10 | | 10 | | 40 | 40 | Till | Partially Frozen | Old Burn | Valley Bottom | |
| 1321071 | Phil Severinsen | 4-Jul-20 | 553118 | 6928419 | 748 | Gold Crest | 50 | B/C | Light Brown | | 10 | 10 | 20 | 60 | | Till | Dry | Old Burn | Ridge Top | |

| GENERAL | | | LOCATION | | | | SAMPLE DESCRIPTION | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Sample Composition (%) | | | | | | | | | |
| Sample ID | User | Date | Easting | Northing | Alt. (m) | Area | Sample Depth (cm) | Horizon Sampled | Sample Colour | Organics | Ang. Rock | Gravel | Sand | Silt | Clay | Parent Material | Moisture Content | Vegetation Cover | Topo Position | Comments |
| 1321072 | Phil Severinsen | 4-Jul-20 | 553087 | 6928457 | 752 | Gold Crest | 100 | B/C | Brown/Grey | | 10 | 10 | | 20 | 60 | Till | Moist | Old Burn | Mid-Slope | |
| 1321073 | Phil Severinsen | 4-Jul-20 | 553055 | 6928496 | 756 | Gold Crest | 60 | B | Brown | 10 | 10 | 10 | | 40 | 30 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321074 | Phil Severinsen | 4-Jul-20 | 553024 | 6928536 | 764 | Gold Crest | 70 | B/C | Brown/Grey | | 10 | 10 | | 20 | 60 | Till | Moist | Old Burn | Mid-Slope | |
| 1321075 | Phil Severinsen | 4-Jul-20 | 552995 | 6928574 | 778 | Gold Crest | 60 | B/C | Brown | | 10 | 10 | | 40 | 40 | Till | Moist | Old Burn | Mid-Slope | |
| 1321076 | Phil Severinsen | 6-Jul-20 | 555121 | 6929725 | 872 | Gold Crest | 70 | C | Light Brown | | 30 | | 20 | | 50 | Weathered Bedrock | Moist | Old Burn | Ridge Top | |
| 1321077 | Phil Severinsen | 6-Jul-20 | 555088 | 6929762 | 859 | Gold Crest | 70 | B/C | Brown | 10 | 20 | | 20 | | 50 | Weathered Bedrock | Partially Frozen | Old Burn | Mid-Slope | |
| 1321078 | Phil Severinsen | 6-Jul-20 | 555057 | 6929802 | 841 | Gold Crest | 80 | B/C | Light Brown | 10 | 30 | | 20 | | 40 | Weathered Bedrock | Partially Frozen | Old Burn | Mid-Slope | |
| 1321079 | Phil Severinsen | 6-Jul-20 | 555029 | 6929841 | 824 | Gold Crest | 70 | B/C | Brown | 10 | 20 | | 20 | | 50 | Weathered Bedrock | Frozen | Old Burn | Mid-Slope | |
| 1321080 | Phil Severinsen | 6-Jul-20 | 554995 | 6929880 | 814 | Gold Crest | 60 | B/C | Light Brown | | 20 | | 40 | | 40 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321081 | Phil Severinsen | 6-Jul-20 | 554966 | 6929920 | 808 | Gold Crest | 70 | B/C | Brown/Grey | | 20 | | 20 | | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Quartz + Rusty Rock Chip |
| 1321082 | Phil Severinsen | 6-Jul-20 | 554935 | 6929962 | 807 | Gold Crest | 40 | C | Light Brown | | 20 | | 40 | 20 | 20 | Weathered Bedrock | Dry | Old Burn | Mid-Slope | |
| 1321083 | Phil Severinsen | 6-Jul-20 | 554903 | 6929999 | 807 | Gold Crest | 60 | B | Brown | 10 | 20 | | 20 | 20 | 30 | Weathered Bedrock | Partially Frozen | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321084 | Phil Severinsen | 6-Jul-20 | 554871 | 6930036 | 812 | Gold Crest | 60 | C | Grey | | 20 | | 50 | | 30 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Bright Orange Rust |
| 1321085 | Phil Severinsen | 6-Jul-20 | 554821 | 6929980 | 819 | Gold Crest | 50 | C | Light Brown | | 20 | | 60 | | 20 | Weathered Bedrock | Moist | Old Burn | Ridge Top | Rusty Rock Chip |
| 1321086 | Phil Severinsen | 6-Jul-20 | 554841 | 6929932 | 819 | Gold Crest | 80 | C | Light Grey | | 30 | | 40 | | 30 | Weathered Bedrock | Moist | Old Burn | Ridge Top | Bright Orange Rust |
| 1321087 | Phil Severinsen | 6-Jul-20 | 554857 | 6929885 | 819 | Gold Crest | 50 | C | Grey | | 30 | | 50 | | 20 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321088 | Phil Severinsen | 6-Jul-20 | 554879 | 6929841 | 819 | Gold Crest | 50 | B/C | Brown/Grey | 10 | 20 | | 40 | | 30 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321089 | Phil Severinsen | 6-Jul-20 | 554916 | 6929806 | 825 | Gold Crest | 40 | B/C | Brown | 10 | 10 | | 40 | 40 | | Weathered Bedrock | Dry | Old Burn | Mid-Slope | |
| 1321090 | Phil Severinsen | 6-Jul-20 | 554952 | 6929774 | 832 | Gold Crest | 70 | B/C | Brown/Grey | | 20 | | 20 | | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321091 | Phil Severinsen | 6-Jul-20 | 554987 | 6929737 | 843 | Gold Crest | 50 | B/C | Light Brown | | 20 | | 20 | | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Bright Orange Rust |
| 1321092 | Phil Severinsen | 6-Jul-20 | 554706 | 6930197 | 804 | Gold Crest | 70 | B/C | Brown/Grey | | 20 | | 30 | | 50 | Weathered Bedrock | Moist | Old Burn | Ridge Top | |
| 1321093 | Phil Severinsen | 6-Jul-20 | 554667 | 6930286 | 808 | Gold Crest | 50 | B/C | Brown | | 10 | | 20 | | 70 | Weathered Bedrock | Moist | Old Burn | Ridge Top | Bright Orange Rust |
| 1321094 | Phil Severinsen | 6-Jul-20 | 554632 | 6930379 | 802 | Gold Crest | 60 | B/C | Light Brown | | 20 | | 40 | | 40 | Weathered Bedrock | Moist | Old Burn | Ridge Top | |
| 1321095 | Phil Severinsen | 6-Jul-20 | 554604 | 6930477 | 806 | Gold Crest | 60 | B/C | Light Brown | | 20 | | 20 | | 60 | Weathered Bedrock | Moist | Old Burn | Ridge Top | Bright Orange Rust |
| 1321096 | Phil Severinsen | 6-Jul-20 | 554542 | 6930604 | 796 | Gold Crest | 50 | B/C | Orange Brown | | 10 | | 20 | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321097 | Phil Severinsen | 6-Jul-20 | 554454 | 6930639 | 767 | Gold Crest | 80 | B/C | Brown/Grey | | 10 | | 10 | | 80 | Weathered Bedrock | Moist | Old Burn | Valley Bottom | Rusty Rock Chip |
| 1321098 | Phil Severinsen | 6-Jul-20 | 554354 | 6930632 | 783 | Gold Crest | 40 | C | Light Brown | | 20 | | 10 | | 70 | Weathered Bedrock | Moist | Old Burn | Ridge Top | |
| 1321099 | Phil Severinsen | 6-Jul-20 | 554209 | 6930654 | 749 | Gold Crest | 70 | B/C | Grey | | 10 | 10 | 10 | | 70 | Till | Moist | Old Burn | Mid-Slope | |
| 1321100 | Phil Severinsen | 6-Jul-20 | 554119 | 6930698 | 721 | Gold Crest | 60 | B | Brown | 10 | 10 | 10 | | | 70 | Till | Moist | Old Burn | Mid-Slope | |
| 1321101 | Phil Severinsen | 6-Jul-20 | 554082 | 6930727 | 712 | Gold Crest | 80 | B/C | Light Grey | 10 | 10 | 10 | | | 70 | Till | Moist | Old Burn | Mid-Slope | |
| 1321102 | Phil Severinsen | 6-Jul-20 | 554012 | 6930794 | 699 | Gold Crest | 70 | A/B | Dark Brown | 20 | | 10 | | | 70 | Till | Frozen | Old Burn | Valley Bottom | |
| 1321103 | Phil Severinsen | 6-Jul-20 | 553956 | 6930877 | 694 | Gold Crest | 70 | B | Brown/Grey | | | 20 | | | 80 | Till | Partially Frozen | Old Burn | Valley Bottom | |
| 1321104 | Phil Severinsen | 7-Jul-20 | 552769 | 6929070 | 702 | Gold Crest | 60 | B/C | Light Grey | | | 10 | 20 | | 70 | Till | Moist | Old Burn | Mid-Slope | |
| 1321105 | Phil Severinsen | 7-Jul-20 | 552816 | 6929062 | 715 | Gold Crest | 70 | A/B | Dark Brown | 10 | | 10 | 20 | 40 | 30 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321106 | Phil Severinsen | 7-Jul-20 | 552867 | 6929056 | 730 | Gold Crest | 80 | B | Brown | 10 | | 10 | 10 | | 70 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321107 | Phil Severinsen | 7-Jul-20 | 552914 | 6929042 | 744 | Gold Crest | 50 | B | Dark Brown | 10 | | 20 | 20 | | 50 | Till | Moist | Old Burn | Mid-Slope | |
| 1321108 | Phil Severinsen | 7-Jul-20 | 552964 | 6929035 | 758 | Gold Crest | 70 | B | Brown | 10 | | 10 | 10 | | 70 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321109 | Phil Severinsen | 7-Jul-20 | 553013 | 6929025 | 771 | Gold Crest | 70 | B | Brown | 10 | | 10 | 20 | 20 | 40 | Till | Moist | Old Burn | Mid-Slope | |
| 1321110 | Phil Severinsen | 7-Jul-20 | 553063 | 6929017 | 779 | Gold Crest | 60 | B | Brown | 10 | | 10 | 10 | | 70 | Till | Moist | Old Burn | Mid-Slope | |
| 1321111 | Phil Severinsen | 7-Jul-20 | 553113 | 6929008 | 784 | Gold Crest | 50 | B/C | Light Brown | 10 | 10 | 10 | 20 | | 50 | Till | Moist | Old Burn | Mid-Slope | |
| 1321112 | Phil Severinsen | 7-Jul-20 | 553162 | 6928998 | 782 | Gold Crest | 60 | B/C | Brown | 10 | 10 | 10 | | | 70 | Till | Moist | Old Burn | Mid-Slope | |
| 1321113 | Phil Severinsen | 7-Jul-20 | 553212 | 6928992 | 773 | Gold Crest | 80 | B/C | Light Brown | 10 | | 20 | 50 | | 30 | Till | Wet | Old Burn | Mid-Slope | |
| 1321114 | Phil Severinsen | 7-Jul-20 | 553270 | 6928980 | 764 | Gold Crest | 60 | B | Dark Brown | 10 | | 10 | | 40 | 40 | Till | Frozen | Old Burn | Mid-Slope | |
| 1321115 | Phil Severinsen | 7-Jul-20 | 553330 | 6928970 | 750 | Gold Crest | 70 | B | Grey | 10 | | 20 | 20 | | 50 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321116 | Phil Severinsen | 7-Jul-20 | 553378 | 6928962 | 742 | Gold Crest | 60 | B/C | Grey | 10 | | 10 | 30 | | 50 | Till | Moist | Old Burn | Mid-Slope | |
| 1321117 | Phil Severinsen | 7-Jul-20 | 553428 | 6928953 | 744 | Gold Crest | 50 | B/C | Brown/Grey | 10 | | 10 | | 40 | 40 | Till | Moist | Old Burn | Mid-Slope | |
| 1321118 | Phil Severinsen | 7-Jul-20 | 553290 | 6929026 | 747 | Gold Crest | 70 | B | Dark Brown | 20 | | 10 | 20 | | 50 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321119 | Phil Severinsen | 7-Jul-20 | 553339 | 6929017 | 741 | Gold Crest | 60 | B | Brown/Grey | 20 | | 20 | 20 | | 40 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321120 | Phil Severinsen | 7-Jul-20 | 553388 | 6929012 | 739 | Gold Crest | 70 | B/C | Brown/Grey | | | 10 | 20 | | 70 | Till | Frozen | Old Burn | Mid-Slope | |
| 1321121 | Phil Severinsen | 7-Jul-20 | 553438 | 6929002 | 745 | Gold Crest | 60 | B | Brown/Grey | 20 | | 10 | 10 | | 60 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321122 | Phil Severinsen | 8-Jul-20 | 553478 | 6928943 | 762 | Gold Crest | 70 | B/C | Brown/Grey | | | 10 | | 40 | 50 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321123 | Phil Severinsen | 8-Jul-20 | 553528 | 6928939 | 766 | Gold Crest | 60 | B | Dark Brown | 10 | | 10 | | 40 | 40 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321124 | Phil Severinsen | 8-Jul-20 | 553577 | 6928930 | 773 | Gold Crest | 70 | B/C | Brown/Grey | | | 10 | 30 | | 60 | Till | Moist | Old Burn | Mid-Slope | |
| 1321125 | Phil Severinsen | 8-Jul-20 | 553627 | 6928920 | 781 | Gold Crest | 80 | B | Brown/Grey | 10 | | 10 | | 40 | 40 | Till | Partially Frozen | Old Burn | Mid-Slope | |
| 1321126 | Phil Severinsen | 8-Jul-20 | 553675 | 6928912 | 792 | Gold Crest | 70 | B/C | Brown/Grey | 10 | 10 | 10 | | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321127 | Phil Severinsen | 8-Jul-20 | 553724 | 6928901 | 803 | Gold Crest | 80 | B/C | Brown | | 10 | 10 | 10 | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321128 | Phil Severinsen | 8-Jul-20 | 553773 | 6928890 | 815 | Gold Crest | 70 | B/C | Brown | | 10 | 10 | | 20 | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Quartz Chips |
| 1321129 | Phil Severinsen | 8-Jul-20 | 553822 | 6928882 | 824 | Gold Crest | 70 | B/C | Brown/Grey | 10 | 10 | 10 | 30 | | 40 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321130 | Phil Severinsen | 8-Jul-20 | 553871 | 6928873 | 833 | Gold Crest | 50 | B/C | Light Brown | | 10 | | 30 | | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321131 | Phil Severinsen | 8-Jul-20 | 553920 | 6928863 | 845 | Gold Crest | 50 | C | Light Brown | | 20 | 40 | | 40 | | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Bright Orange Rust |
| 1321132 | Phil Severinsen | 8-Jul-20 | 553989 | 6928611 | 838 | Gold Crest | 50 | C | Light Brown | | 20 | | 40 | | 40 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321133 | Phil Severinsen | 8-Jul-20 | 553938 | 6928616 | 838 | Gold Crest | 50 | B/C | Brown | | 20 | | 10 | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321134 | Phil Severinsen | 8-Jul-20 | 553890 | 6928625 | 842 | Gold Crest | 60 | B/C | Brown/Grey | | 10 | | 10 | | 80 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321135 | Phil Severinsen | 8-Jul-20 | 553842 | 6928635 | 843 | Gold Crest | 50 | B/C | Brown | | 10 | | 20 | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321136 | Phil Severinsen | 8-Jul-20 | 553845 | 6928676 | 848 | Gold Crest | 50 | B/C | Brown/Grey | | 10 | | 10 | | 80 | Weathered Bedrock | Moist | Old Burn | Ridge Top | Rusty Rock Chip |
| 1321137 | Phil Severinsen | 8-Jul-20 | 553896 | 6928676 | 854 | Gold Crest | 60 | B/C | Brown | | 20 | | 20 | | 60 | Weathered Bedrock | Moist | Old Burn | Ridge Top | |
| 1321138 | Phil Severinsen | 8-Jul-20 | 553946 | 6928670 | 853 | Gold Crest | 50 | B/C | Light Brown | | 20 | | 40 | | 40 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321139 | Phil Severinsen | 8-Jul-20 | 553995 | 6928661 | 851 | Gold Crest | 60 | C | Light Brown | | 30 | | 20 | | 50 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Quartz Chips |
| 1321140 | Phil Severinsen | 8-Jul-20 | 553995 | 6928713 | 862 | Gold Crest | 70 | C | Light Brown | | 10 | | 10 | | 80 | Weathered Bedrock | Moist | Old Burn | Ridge Top | |
| 1321141 | Phil Severinsen | 8-Jul-20 | 553935 | 6928704 | 858 | Gold Crest | 60 | B/C | Light Brown | | 10 | | 20 | | 70 | Weathered Bedrock | Moist | Old Burn | Ridge Top | |
| 1321142 | Phil Severinsen | 9-Jul-20 | 553990 | 6928178 | 780 | Gold Crest | 80 | B | Brown | 10 | | | | | 90 | Fluvial | Wet | Old Burn | Mid-Slope | |

| GENERAL | | | LOCATION | | | | SAMPLE DESCRIPTION | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Sample Composition (%) | | | | | | | | |
| Sample ID | User | Date | Easting | Northing | Alt. (m) | Area | Sample Depth (cm) | Horizon Sampled | Sample Colour | Organics | Ang. Rock | Gravel | Sand | Silt | Clay | Parent Material | Moisture Content | Vegetation Cover | Topo Position | Comments |
| 1321143 | Phil Severinsen | 9-Jul-20 | 554036 | 6928180 | 791 | Gold Crest | 70 | B/C | Brown/Grey | | | | 40 | | 60 | Weathered Bedrock | Partially Frozen | Old Burn | Mid-Slope | |
| 1321144 | Phil Severinsen | 9-Jul-20 | 554085 | 6928172 | 803 | Gold Crest | 70 | B/C | Brown | | 30 | | | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321145 | Phil Severinsen | 9-Jul-20 | 554132 | 6928157 | 819 | Gold Crest | 60 | B/C | Brown | | 20 | | 30 | | 50 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321146 | Phil Severinsen | 9-Jul-20 | 554184 | 6928151 | 838 | Gold Crest | 70 | B/C | Brown/Grey | | 20 | | 30 | | 50 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Bright Orange Rust |
| 1321147 | Phil Severinsen | 9-Jul-20 | 554233 | 6928143 | 855 | Gold Crest | 70 | B/C | Brown/Grey | | 20 | | 20 | | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321148 | Phil Severinsen | 9-Jul-20 | 554283 | 6928130 | 868 | Gold Crest | 60 | B/C | Brown | | 20 | | 10 | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321149 | Phil Severinsen | 9-Jul-20 | 554331 | 6928120 | 881 | Gold Crest | 50 | B/C | Light Brown | | 20 | | 20 | | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321150 | Phil Severinsen | 9-Jul-20 | 554393 | 6928212 | 895 | Gold Crest | 60 | B/C | Brown/Grey | | 20 | | 10 | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321151 | Gary Drinan | 8-Jul-20 | 553580 | 6928979 | 758 | Goldcrest | 50 | c | dark grey | | | | | | | till | moist | df | moist | |
| 1321152 | Gary Drinan | 8-Jul-20 | 553640 | 6928968 | 768 | Goldcrest | 50 | c | dark grey | | | | | | | till | moist | df | moist | |
| 1321153 | Gary Drinan | 8-Jul-20 | 553690 | 6928959 | 779 | Goldcrest | 50 | c | dark grey | | | | | | | till | moist | df | moist | |
| 1321154 | Gary Drinan | 8-Jul-20 | 553733 | 6928951 | 788 | Goldcrest | 70 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321155 | Gary Drinan | 8-Jul-20 | 553780 | 6928939 | 800 | Goldcrest | 80 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321156 | Gary Drinan | 8-Jul-20 | 553837 | 6928931 | 812 | Goldcrest | 50 | c | light grey | | | | | | | till | moist | df | moist | |
| 1321157 | Gary Drinan | 8-Jul-20 | 553880 | 6928922 | 822 | Goldcrest | 70 | c | dark brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321158 | Gary Drinan | 8-Jul-20 | 553933 | 6928921 | 830 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321159 | Gary Drinan | 8-Jul-20 | 553985 | 6928908 | 842 | Goldcrest | 40 | b/c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321160 | Gary Drinan | 8-Jul-20 | 553971 | 6928862 | 850 | Goldcrest | 50 | c | dark grey | | | | | | | till | moist | df | moist | |
| 1321161 | Gary Drinan | 8-Jul-20 | 553837 | 6929103 | 773 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321162 | Gary Drinan | 8-Jul-20 | 553868 | 6929086 | 784 | Goldcrest | 50 | c | light grey | | | | | | | till | wet | df | moist | |
| 1321163 | Gary Drinan | 8-Jul-20 | 553915 | 6929062 | 800 | Goldcrest | 50 | c | dark grey | | | | | | | till | wet | df | moist | |
| 1321164 | Gary Drinan | 8-Jul-20 | 553970 | 6929016 | 821 | Goldcrest | 50 | b/c | light brown | | | | | | | till | wet | df | moist | |
| 1321165 | Gary Drinan | 8-Jul-20 | 553991 | 6928957 | 835 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321166 | Gary Drinan | 8-Jul-20 | 554033 | 6928909 | 855 | Goldcrest | 30 | b/c | light brown | | | | | | | weathered bedrock | dry | df | moist | |
| 1321167 | Gary Drinan | 8-Jul-20 | 554071 | 6928858 | 870 | Goldcrest | 50 | c | dark brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321168 | Gary Drinan | 8-Jul-20 | 554020 | 6928861 | 863 | Goldcrest | 40 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321169 | Gary Drinan | 8-Jul-20 | 554560 | 6928624 | 964 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321170 | Gary Drinan | 8-Jul-20 | 554505 | 6928631 | 952 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | df | moist | |
| 1321171 | Gary Drinan | 8-Jul-20 | 554454 | 6928644 | 938 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321172 | Gary Drinan | 8-Jul-20 | 554411 | 6928647 | 925 | Goldcrest | 40 | b/c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321173 | Gary Drinan | 8-Jul-20 | 554366 | 6928659 | 908 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321174 | Gary Drinan | 8-Jul-20 | 554305 | 6928662 | 896 | Goldcrest | 50 | b/c | dark grey | | | | | | | till | permoistafrost | df | moist | |
| 1321175 | Gary Drinan | 8-Jul-20 | 554255 | 6928670 | 884 | Goldcrest | 60 | c | dark grey | | | | | | | weathered bedrock | moist | df | moist | |
| 1321176 | Gary Drinan | 8-Jul-20 | 554213 | 6928671 | 876 | Goldcrest | 50 | b/c | dark grey | | | | | | | weathered bedrock | wet | df | moist | |
| 1321177 | Gary Drinan | 8-Jul-20 | 554167 | 6928683 | 870 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321178 | Gary Drinan | 8-Jul-20 | 554109 | 6928693 | 864 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321179 | Gary Drinan | 8-Jul-20 | 554061 | 6928697 | 863 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321180 | Gary Drinan | 9-Jul-20 | 554051 | 6928593 | 836 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321181 | Gary Drinan | 9-Jul-20 | 554105 | 6928591 | 840 | Goldcrest | 70 | c | light brown | | | | | | | weathered bedrock | wet | df | moist | |
| 1321182 | Gary Drinan | 9-Jul-20 | 554145 | 6928586 | 848 | Goldcrest | 80 | c | light brown | | | | | | | weathered bedrock | veathered bedroc | df | moist | |
| 1321183 | Gary Drinan | 9-Jul-20 | 554198 | 6928577 | 855 | Goldcrest | 80 | c | light grey | | | | | | | weathered bedrock | moist | df | moist | |
| 1321184 | Gary Drinan | 9-Jul-20 | 554247 | 6928575 | 867 | Goldcrest | 80 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321185 | Gary Drinan | 9-Jul-20 | 554298 | 6928563 | 882 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321186 | Gary Drinan | 9-Jul-20 | 554342 | 6928564 | 896 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321187 | Gary Drinan | 9-Jul-20 | 554399 | 6928556 | 912 | Goldcrest | 70 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321188 | Gary Drinan | 9-Jul-20 | 554446 | 6928546 | 926 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321189 | Gary Drinan | 9-Jul-20 | 554498 | 6928537 | 939 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321190 | Gary Drinan | 9-Jul-20 | 554540 | 6928532 | 948 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321191 | Gary Drinan | 9-Jul-20 | 554527 | 6928433 | 939 | Goldcrest | 50 | b/c | light brown | | | | | | | weathered bedrock | permoistafrost | df | moist | |
| 1321192 | Gary Drinan | 9-Jul-20 | 554486 | 6928435 | 926 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321193 | Gary Drinan | 9-Jul-20 | 554432 | 6928444 | 911 | Goldcrest | 70 | b/c | dark grey | | | | | | | weathered bedrock | moist | df | moist | |
| 1321194 | Gary Drinan | 9-Jul-20 | 554381 | 6928450 | 897 | Goldcrest | 50 | b/c | dark grey | | | | | | | weathered bedrock | moist | df | moist | |
| 1321195 | Gary Drinan | 9-Jul-20 | 554335 | 6928455 | 883 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321196 | Gary Drinan | 9-Jul-20 | 554288 | 6928468 | 869 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321197 | Gary Drinan | 9-Jul-20 | 554237 | 6928470 | 853 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321198 | Gary Drinan | 9-Jul-20 | 554182 | 6928472 | 841 | Goldcrest | 50 | c | dark grey | | | | | | | weathered bedrock | moist | df | moist | |
| 1321199 | Gary Drinan | 9-Jul-20 | 554127 | 6928480 | 827 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321200 | Gary Drinan | 9-Jul-20 | 554081 | 6928492 | 818 | Goldcrest | 50 | c | dark grey | | | | | | | weathered bedrock | moist | df | moist | |
| 1321201 | Dan Ferraro | 2-Jul-20 | 552041 | 6929036 | 779 | Marksmen | 60-70 | b/c | lt grey | | | x | | | x | till | moist | deciduous | mid slope | At old high Au soil. Dug pit to 50cm then auger |
| 1321202 | Dan Ferraro | 2-Jul-20 | 551560 | 6929250 | 647 | Marksmen | 50-60 | b/c | dk brown | | x | | | x | | weathered bedrock | moist | deciduous | mid slope | dirt with mica RC |
| 1321203 | Dan Ferraro | 2-Jul-20 | 551503 | 6929283 | 630 | Marksmen | 40-50 | b | dk brown | x | x | | | x | | weathered bedrock | partially frozen | deciduous | mid slope | hit perma, some RC |
| 1321204 | Dan Ferraro | 2-Jul-20 | 551553 | 6929272 | 644 | Marksmen | 50-60 | b/c | lt brown | | x | | | | | weathered bedrock | wet | deciduous | mid slope | wet but lots of mica RC |
| 1321205 | Dan Ferraro | 2-Jul-20 | 551597 | 6929256 | 655 | Marksmen | 60-70 | b/c | lt brown | | | x | | | | till | moist | deciduous | mid slope | till, large granite boulder 5 ft away |
| 1321206 | Dan Ferraro | 2-Jul-20 | 551640 | 6929236 | 684 | Marksmen | 30-40 | b/c | lt brown | | x | | | | | weathered bedrock | dry | deciduous | mid slope | lots of mica schist RC |
| 1321207 | Dan Ferraro | 2-Jul-20 | 551693 | 6929217 | 705 | Marksmen | 30-40 | c | lt brown | | x | | | | | weathered bedrock | dry | deciduous | mid slope | lots of mica schist RC |
| 1321208 | Dan Ferraro | 2-Jul-20 | 551738 | 6929198 | 718 | Marksmen | 60-70 | c | lt brown | | x | | | | | weathered bedrock | dry | deciduous | mid slope | ang RC |
| 1321209 | Dan Ferraro | 2-Jul-20 | 551789 | 6929190 | 672 | Marksmen | 50-60 | b/c | dk brown | | x | | | x | | weathered bedrock | moist | deciduous | mid slope | fine RC |
| 1321210 | Dan Ferraro | 2-Jul-20 | 551829 | 6929172 | 699 | Marksmen | 30-40 | b or a-b | dk brown | x | | | | x | | bedrock or till | partially frozen | deciduous | mid slope | permafrost shit |
| 1321211 | Dan Ferraro | 2-Jul-20 | 551879 | 6929156 | 725 | Marksmen | 30-40 | b | dk grey-brown | | x | x | | | x | till | partially frozen | deciduous | mid slope | permafrost |
| 1321212 | Dan Ferraro | 2-Jul-20 | 551927 | 6929137 | 742 | Marksmen | 40-50 | b | lt grey-brown | | | x | | x | x | till | partially frozen | deciduous | mid slope | till and perma |

| GENERAL | | | LOCATION | | | | SAMPLE DESCRIPTION | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Sample Composition (%) | | | | | | | | | |
| Sample ID | User | Date | Easting | Northing | Alt. (m) | Area | Sample Depth (cm) | Horizon Sampled | Sample Colour | Organics | Ang. Rock | Gravel | Sand | Silt | Clay | Parent Material | Moisture Content | Vegetation Cover | Topo Position | Comments |
| 1321213 | Dan Ferraro | 2-Jul-20 | 551973 | 6929130 | | Marksmen | 60-70 | b/c | lt brown | | x | x | | | | bedrock or till | moist | deciduous | mid slope | till? |
| 1321214 | Dan Ferraro | 2-Jul-20 | 552015 | 6929104 | 762 | Marksmen | 40-50 | c | lt brown | | x | | | | | weathered bedrock | moist | deciduous | mid slope | lots of qtz RC, sort of unique |
| 1321215 | Dan Ferraro | 2-Jul-20 | 552066 | 6929090 | 761 | Marksmen | 50-60 | c | lt brown | | x | | | | x | bedrock or till | moist | deciduous | mid slope | clayish with chl RC |
| 1321216 | Dan Ferraro | 2-Jul-20 | 552113 | 6929074 | 757 | Marksmen | 40-50 | c | lt brown | | x | x | | | | till maybe some bedrock | dry | deciduous | mid slope | till present in sample |
| 1321217 | Dan Ferraro | 2-Jul-20 | 552162 | 6929059 | 750 | Marksmen | 40-50 | c | lt brown | | | x | | | | till | moist | deciduous | mid slope | all till |
| 1321218 | Dan Ferraro | 3-Jul-20 | 553724 | 6929369 | 734 | Gold Crest | 70-80 | b/c | lt brown | | x | | | x | | weathered bedrock | frozen but dry | evergreen burn | mid slope | perma, fine RC |
| 1321219 | Dan Ferraro | 3-Jul-20 | 553757 | 6929331 | 739 | Gold Crest | 50-60 | b | lt brown | | | | | x | | weathered bedrock | frozen, moist | evergreen burn | mid slope | hit perma,trace fine RC |
| 1321220 | Dan Ferraro | 3-Jul-20 | 553788 | 6929292 | 744 | Gold Crest | 30-40 | b/c | lt brown | | x | | | x | | weathered bedrock | partially frozen | evergreen burn | mid slope | hit perma,trace fine RC |
| 1321221 | Dan Ferraro | 3-Jul-20 | 553823 | 6929256 | 750 | Gold Crest | 40-50 | b | lt brown | | | | | x | | weathered bedrock | partially frozen | evergreen burn | mid slope | perma, fine micas |
| 1321222 | Dan Ferraro | 3-Jul-20 | 553852 | 6929216 | 758 | Gold Crest | 30-40 | b | brown | | x | | | x | | weathered bedrock | partially frozen | evergreen burn | mid slope | perma, large RC, nice ox schist |
| 1321223 | Dan Ferraro | 3-Jul-20 | 553885 | 6929177 | 770 | Gold Crest | 70-80 | b/c | dk brown | | x | | | x | | weathered bedrock | wet | evergreen burn | mid slope | nice ox RC and some qtz |
| 1321224 | Dan Ferraro | 3-Jul-20 | 553902 | 6929160 | 778 | Gold Crest | 50-60 | b/c | lt brown | | x | | | x | | weathered bedrock | wet | evergreen burn | mid slope | nice ox RC and some qtz |
| 1321225 | Dan Ferraro | 3-Jul-20 | 553914 | 6929136 | 786 | Gold Crest | 60-70 | b/c | dk brown | | x | | | x | | weathered bedrock | artially frozen, we | evergreen burn | mid slope | perma but nice ox RC |
| 1321226 | Dan Ferraro | 3-Jul-20 | 553930 | 6929116 | 794 | Gold Crest | 80-90 | b | dk brown | | x | | | x | | weathered bedrock | wet | evergreen burn | mid slope | turned over stump, RC but not really |
| 1321227 | Dan Ferraro | 3-Jul-20 | 553950 | 6929098 | 803 | Gold Crest | 50-60 | b/c | lt brown | | x | | | x | | weathered bedrock | partially frozen | evergreen burn | mid slope | perma, nice ox RC again |
| 1321228 | Dan Ferraro | 3-Jul-20 | 553963 | 6929079 | 810 | Gold Crest | 50-60 | b/c | lt brown | | x | | | x | | weathered bedrock | frozen | evergreen burn | mid slope | perma, less ox RC than previous (downhill) |
| 1321229 | Dan Ferraro | 3-Jul-20 | 553977 | 6929060 | 816 | Gold Crest | 30-40 | b/c | brown | | x | | | x | | weathered bedrock | partially frozen | evergreen burn | mid slope | perma, had to do 5 or 6 holes, ox RC similar to last |
| 1321230 | Dan Ferraro | 3-Jul-20 | 553994 | 6929040 | 822 | Gold Crest | 90-100 | b/c | lt brown | | x | | | x | | weathered bedrock | moist | evergreen burn | mid slope | minor ox RC |
| 1321231 | Dan Ferraro | 3-Jul-20 | 554009 | 6929019 | 828 | Gold Crest | 50-60 | b/c | brown | | x | | | x | | weathered bedrock | partially frozen | evergreen burn | mid slope | perma, minor ox RC |
| 1321232 | Dan Ferraro | 3-Jul-20 | 554021 | 6929002 | 835 | Gold Crest | 60-70 | b/c | brown | | x | | | x | | weathered bedrock | partially frozen | evergreen burn | mid slope | perma, minor ox RC |
| 1321233 | Dan Ferraro | 3-Jul-20 | 554038 | 6928981 | 842 | Gold Crest | 40-50 | c | lt brown | | x | | | | | weathered bedrock | dry | evergreen burn | mid slope | minor ox RC |
| 1321234 | Dan Ferraro | 3-Jul-20 | 554055 | 6928962 | 852 | Gold Crest | 40-50 | c | lt brown | | x | | | | | weathered bedrock | dry | evergreen burn | mid slope | lots of RC, mod ox |
| 1321235 | Dan Ferraro | 3-Jul-20 | 554068 | 6928943 | 859 | Gold Crest | 30-40 | c | lt brown | | x | | | | | weathered bedrock | moist | evergreen burn | mid slope | large RC, mod ox, bedrock is close |
| 1321236 | Dan Ferraro | 3-Jul-20 | 554084 | 6928919 | 868 | Gold Crest | 40-50 | b/c | lt brown | | x | | | | | weathered bedrock | moist | evergreen burn | mid slope | larger RC, minor ox |
| 1321237 | Dan Ferraro | 3-Jul-20 | 554101 | 6928902 | 875 | Gold Crest | 30-40 | c | lt brown | | x | | | | | weathered bedrock | dry | evergreen burn | mid slope | close bedrock, minor ox |
| 1321238 | Dan Ferraro | 3-Jul-20 | 554134 | 6928861 | 886 | Gold Crest | 30-40 | c | lt brown | | x | | | | | weathered bedrock | dry | evergreen burn | mid slope | close bedrock trace ox |
| 1321239 | Dan Ferraro | 4-Jul-20 | 552680 | 6928777 | 752 | Gay Mound | 40-50 | b | lt brown | | | x | | | | till | dry | evergreen burn | mid slope | |
| 1321240 | Dan Ferraro | 4-Jul-20 | 552727 | 6928768 | 767 | Gay Mound | 40-50 | b/c | lt brown | | | x | | | x | till | dry | evergreen burn | mid slope | till w minor clay |
| 1321241 | Dan Ferraro | 4-Jul-20 | 552776 | 6928762 | 781 | Gay Mound | 70-80 | b/c | lt brown | | | x | | | x | till | moist | evergreen burn | mid slope | |
| 1321242 | Dan Ferraro | 4-Jul-20 | 552825 | 6928752 | 794 | Gay Mound | 30-40 | b/c | lt brown | | | x | | | x | till | moist | evergreen burn | mid slope | |
| 1321243 | Dan Ferraro | 4-Jul-20 | 552877 | 6928746 | 803 | Gay Mound | 40-50 | c | lt grey-brown | | | x | | | | till | dry | evergreen burn | mid slope | |
| 1321244 | Dan Ferraro | 4-Jul-20 | 552927 | 6928733 | 810 | Gay Mound | 30-40 | b/c | lt brown | | | x | | | | till | dry | evergreen burn | mid slope | tough to get deep |
| 1321245 | Dan Ferraro | 4-Jul-20 | 552972 | 6928726 | 811 | Gay Mound | 60-70 | b/c | grey | | | x | | | x | till | moist | evergreen burn | ridge top | |
| 1321246 | Dan Ferraro | 4-Jul-20 | 553022 | 6928717 | 814 | Gay Mound | 30-40 | b/c | lt brown | | tr | x | | | | till | dry | evergreen burn | mid slope | trace ox schist |
| 1321247 | Dan Ferraro | 4-Jul-20 | 553072 | 6928705 | 814 | Gay Mound | 30-40 | b/c | lt brown | | x | x | | | | till | dry | evergreen burn | mid slope | minor schist chips |
| 1321248 | Dan Ferraro | 4-Jul-20 | 553121 | 6928700 | 810 | Gay Mound | 40-50 | b/c | lt brown | | x | x | | | | till | dry | evergreen burn | mid slope | mostly till but some cherty bedrock, some greenish clay |
| 1321249 | Dan Ferraro | 4-Jul-20 | 553150 | 6928643 | 787 | Gay Mound | 50-60 | c | lt brown | | x | x | | | | till and bedrock | dry | evergreen burn | mid slope | mix, mostly bedrock? |
| 1321250 | Dan Ferraro | 4-Jul-20 | 553168 | 6928693 | 804 | Gay Mound | 30-40 | c | lt brown | | x | x | | | | till and bedrock | dry | evergreen burn | mid slope | chl and cherty schist, some till |
| 1321251 | Dan Ferraro | 4-Jul-20 | 553177 | 6928739 | 808 | Gay Mound | 70-80 | b/c | lt brown | | | x | | x | x | till | moist | evergreen burn | mid slope | mostly clay, some RC, likely till |
| 1321252 | Dan Ferraro | 4-Jul-20 | 553183 | 6928789 | 807 | Gay Mound | 70-80 | b/c | dk brown | | x | x | | x | x | till | partially frozen | evergreen burn | mid slope | perma? Some RC, 50/50 |
| 1321253 | Dan Ferraro | 4-Jul-20 | 553234 | 6928782 | 803 | Gay Mound | 50-60 | c | grey-brown | | x | | | | | weathered bedrock | dry | evergreen burn | mid slope | nice sample, maybe perma |
| 1321254 | Dan Ferraro | 4-Jul-20 | 553224 | 6928731 | 804 | Gay Mound | 60-70 | b/c | lt grey | | | | | | x | till | moist | evergreen burn | mid slope | all clay, perma? |
| 1321255 | Dan Ferraro | 4-Jul-20 | 553216 | 6928683 | 802 | Gay Mound | 50-60 | b/c | lt brown | | x | x | | | | till | dry | evergreen burn | mid slope | mostly till, some bedrock |
| 1321256 | Dan Ferraro | 4-Jul-20 | 553205 | 6928633 | 785 | Gay Mound | 40-50 | b/c | lt brown | | tr | x | | | | till | dry | evergreen burn | mid slope | mostly till |
| 1321257 | Dan Ferraro | 4-Jul-20 | 553250 | 6928626 | 780 | Gay Mound | 60-70 | b/c | lt brown | | x | x | | | x | till | moist | evergreen burn | mid slope | mostly till, some bedrock |
| 1321258 | Dan Ferraro | 4-Jul-20 | 553264 | 6928676 | 790 | Gay Mound | 40-50 | b/c | lt brown | | tr | x | | | | till | dry | evergreen burn | mid slope | mostly till, some bedrock, tr ox |
| 1321259 | Dan Ferraro | 4-Jul-20 | 553274 | 6928723 | 792 | Gay Mound | 50-60 | b/c | lt brown | | | x | | | | till | dry | evergreen burn | mid slope | mostly till, minor chl altered schist |
| 1321260 | Dan Ferraro | 4-Jul-20 | 553283 | 6928773 | 792 | Gay Mound | 50-60 | c | lt brown | | x | | | | | weathered bedrock | dry | evergreen burn | mid slope | actually a nice sample, minor ox RC |
| 1321261 | Dan Ferraro | 4-Jul-20 | 553332 | 6928765 | 779 | Gay Mound | 30-40 | b | brown | | | | | x | x | till | frozen | evergreen burn | saddle | perma |
| 1321262 | Dan Ferraro | 4-Jul-20 | 553320 | 6928717 | 780 | Gay Mound | 70-80 | b/c | lt brown | | | | | | x | till | partially frozen | evergreen burn | mid slope | perma, grey clay |
| 1321263 | Dan Ferraro | 4-Jul-20 | 553313 | 6928664 | 778 | Gay Mound | 60-70 | b/c | brown-grey | | | x | | | | till | moist | evergreen burn | mid slope | brown grey dirt w till |
| 1321264 | Dan Ferraro | 4-Jul-20 | 553303 | 6928614 | 771 | Gay Mound | 70-80 | b/c | grey | | | | | | x | till | moist | evergreen burn | saddle | perma, clay |
| 1321265 | Dan Ferraro | 4-Jul-20 | 553353 | 6928618 | 770 | Gay Mound | 50-60 | b, some a | dk brown | | x | | | | | till | frozen | evergreen burn | saddle | perma, but some nice ox RC |
| 1321266 | Phil Severinsen | 9-Jul-20 | 554350 | 6928223 | 885 | Gold Crest | 70 | C | Light Brown | | 20 | | 40 | | 40 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321267 | Phil Severinsen | 9-Jul-20 | 554299 | 6928232 | 866 | Gold Crest | 60 | C | Brown/Grey | | 30 | | 40 | | 30 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321268 | Phil Severinsen | 9-Jul-20 | 554251 | 6928238 | 850 | Gold Crest | 50 | C | Light Brown | | 20 | | 40 | | 40 | Weathered Bedrock | Dry | Old Burn | Mid-Slope | |
| 1321269 | Phil Severinsen | 9-Jul-20 | 554201 | 6928250 | 832 | Gold Crest | 60 | B/C | Brown/Grey | | 30 | | 30 | | 40 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rocky Terrain |
| 1321270 | Phil Severinsen | 9-Jul-20 | 554151 | 6928257 | 814 | Gold Crest | 70 | B | Brown | 10 | 20 | | | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321271 | Phil Severinsen | 9-Jul-20 | 554101 | 6928261 | 800 | Gold Crest | 60 | B | Brown | 10 | 20 | | 20 | | 50 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Drainage Nearby |
| 1321272 | Phil Severinsen | 9-Jul-20 | 554053 | 6928273 | 787 | Gold Crest | 70 | B | Dark Brown | 20 | 20 | | | 20 | 40 | Weathered Bedrock | Partially Frozen | Old Burn | Valley Bottom | |
| 1321273 | Phil Severinsen | 9-Jul-20 | 554003 | 6928283 | 778 | Gold Crest | 60 | A/B | Brown | 20 | 30 | | 20 | | 30 | Weathered Bedrock | Frozen | Old Burn | Valley Bottom | |
| 1321274 | Phil Severinsen | 9-Jul-20 | 553972 | 6929218 | 772 | Gold Crest | 60 | B/C | Light Brown | | 20 | | 30 | | 50 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321275 | Phil Severinsen | 9-Jul-20 | 554005 | 6929175 | 790 | Gold Crest | 80 | B/C | Light Brown | 10 | 20 | | 20 | | 50 | Weathered Bedrock | Wet | Old Burn | Mid-Slope | |
| 1321276 | Phil Severinsen | 9-Jul-20 | 554036 | 6929136 | 806 | Gold Crest | 90 | B/C | Light Brown | 10 | 10 | | 20 | | 60 | Weathered Bedrock | Wet | Old Burn | Mid-Slope | |
| 1321277 | Phil Severinsen | 9-Jul-20 | 554064 | 6929095 | 825 | Gold Crest | 90 | B/C | Light Brown | 10 | 30 | | 10 | | 50 | Weathered Bedrock | Wet | Old Burn | Mid-Slope | |
| 1321278 | Phil Severinsen | 9-Jul-20 | 554093 | 6929049 | 834 | Gold Crest | 80 | C | Light Brown | | 20 | | 20 | | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Rusty Rock Chip |
| 1321279 | Phil Severinsen | 9-Jul-20 | 554124 | 6929016 | 847 | Gold Crest | 50 | B/C | Brown/Grey | | 30 | | 10 | 30 | 30 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Sphagnum Covering Boulders |
| 1321280 | Phil Severinsen | 9-Jul-20 | 554156 | 6928977 | 862 | Gold Crest | 60 | B | Brown | 10 | 20 | | | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Sphagnum Covering Boulders |

| GENERAL | | | LOCATION | | | | SAMPLE DESCRIPTION | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Sample Composition (%) | | | | | | | | | |
| Sample ID | User | Date | Easting | Northing | Alt. (m) | Area | Sample Depth (cm) | Horizon Sampled | Sample Colour | Organics | Ang. Rock | Gravel | Sand | Silt | Clay | Parent Material | Moisture Content | Vegetation Cover | Topo Position | Comments |
| 1321281 | Phil Severinsen | 9-Jul-20 | 554185 | 6928937 | 875 | Gold Crest | 50 | B/C | Brown/Grey | | 20 | | 20 | | 60 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | Sphagnum Covering Boulders |
| 1321282 | Phil Severinsen | 9-Jul-20 | 554215 | 6928895 | 886 | Gold Crest | 50 | B/C | Light Brown | | 20 | | 10 | | 70 | Weathered Bedrock | Moist | Old Burn | Mid-Slope | |
| 1321301 | Gary Drinan | 2-Jul-20 | 551403 | 6929008 | 609 | Marksmen | 30 | c | dark grey | | | | | | | weathered bedrock | moist | evergreen forest | mid slope | |
| 1321302 | Gary Drinan | 2-Jul-20 | 551454 | 6928989 | 627 | Marksmen | 30 | c | dark grey | | | | | | | weathered bedrock | moist | evergreen forest | mid slope | |
| 1321303 | Gary Drinan | 2-Jul-20 | 551491 | 6928976 | 652 | Marksmen | 40 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321304 | Gary Drinan | 2-Jul-20 | 551545 | 6928959 | 680 | Marksmen | 40 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321305 | Gary Drinan | 2-Jul-20 | 551590 | 6928943 | 712 | Marksmen | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321306 | Gary Drinan | 2-Jul-20 | 551654 | 6928919 | 734 | Marksmen | 70 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321307 | Gary Drinan | 2-Jul-20 | 551684 | 6928903 | 738 | Marksmen | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321308 | Gary Drinan | 2-Jul-20 | 551728 | 6928890 | 741 | Marksmen | 40 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321309 | Gary Drinan | 2-Jul-20 | 551778 | 6928873 | 742 | Marksmen | 40 | c | light grey | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321310 | Gary Drinan | 2-Jul-20 | 551828 | 6928856 | 745 | Marksmen | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321311 | Gary Drinan | 2-Jul-20 | 551872 | 6928832 | 740 | Marksmen | 20 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321312 | Gary Drinan | 2-Jul-20 | 551924 | 6928823 | 732 | Marksmen | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321313 | Gary Drinan | 2-Jul-20 | 551983 | 6928810 | 723 | Marksmen | 50 | c | light grey | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321314 | Gary Drinan | 2-Jul-20 | 552018 | 6928791 | 711 | Marksmen | 50 | c | light grey | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321315 | Gary Drinan | 2-Jul-20 | 552063 | 6928773 | 702 | Marksmen | 40 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321316 | Gary Drinan | 2-Jul-20 | 552109 | 6928755 | 699 | Marksmen | 40 | c | dark grey | | | | | | | weathered bedrock | dry | evergreen forest | mid slope | |
| 1321317 | Gary Drinan | 2-Jul-20 | 552159 | 6928744 | 697 | Marksmen | 50 | c | dark grey | | | | | | | weathered bedrock | dry | evergreen forest | mid slope | |
| 1321318 | Gary Drinan | 2-Jul-20 | 552194 | 6928837 | 716 | Marksmen | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321319 | Gary Drinan | 2-Jul-20 | 552147 | 6928849 | 725 | Marksmen | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321320 | Gary Drinan | 2-Jul-20 | 552102 | 6928864 | 727 | Marksmen | 40 | c | light brown | | | | | | | weathered bedrock | moist | evergreen forest | mid slope | |
| 1321321 | Gary Drinan | 2-Jul-20 | 552055 | 6928884 | 733 | Marksmen | 40 | c | light grey | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321322 | Gary Drinan | 2-Jul-20 | 552006 | 6928901 | 745 | Marksmen | 40 | c | light grey | | | | | | | weathered bedrock | dry | evergreen forest | mid slope | |
| 1321323 | Gary Drinan | 3-Jul-20 | 554413 | 6928318 | 893 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321324 | Gary Drinan | 3-Jul-20 | 554371 | 6928323 | 885 | Goldcrest | 50 | b/c | light grey | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321325 | Gary Drinan | 3-Jul-20 | 554320 | 6928329 | 869 | Goldcrest | 60 | c | dark grey | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321326 | Gary Drinan | 3-Jul-20 | 554275 | 6928334 | 854 | Goldcrest | 50 | c | dark grey | | | | | | | till | moist | deciduous forest | mid slope | |
| 1321327 | Gary Drinan | 3-Jul-20 | 554220 | 6928348 | 836 | Goldcrest | 50 | c | dark grey | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321328 | Gary Drinan | 3-Jul-20 | 554171 | 6928349 | 821 | Goldcrest | 50 | c | dark grey | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321329 | Gary Drinan | 3-Jul-20 | 554122 | 6928372 | 807 | Goldcrest | 50 | c | dark grey | | | | | | | weathered bedrock | moist | buck brush | mid slope | |
| 1321330 | Gary Drinan | 3-Jul-20 | 554072 | 6928366 | 797 | Goldcrest | 60 | c | dark brown | | | | | | | weathered bedrock | wet | evergreen forest | mid slope | |
| 1321331 | Gary Drinan | 3-Jul-20 | 554026 | 6928377 | 788 | Goldcrest | 40 | c | dark grey | | | | | | | weathered bedrock | wet | deciduous forest | mid slope | |
| 1321332 | Gary Drinan | 3-Jul-20 | 553972 | 6928390 | 782 | Goldcrest | 50 | c | dark grey | | | | | | | weathered bedrock | wet | deciduous forest | mid slope | |
| 1321333 | Gary Drinan | 3-Jul-20 | 553929 | 6928396 | 782 | Goldcrest | 40 | c | light brown | | | | | | | weathered bedrock | wet | deciduous forest | mid slope | |
| 1321334 | Gary Drinan | 3-Jul-20 | 553876 | 6928411 | 781 | Goldcrest | 60 | c | dark grey | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321335 | Gary Drinan | 3-Jul-20 | 553825 | 6928417 | 779 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321336 | Gary Drinan | 3-Jul-20 | 553778 | 6928428 | 778 | Goldcrest | 80 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321337 | Gary Drinan | 3-Jul-20 | 553730 | 6928432 | 778 | Goldcrest | 80 | c | light grey | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321338 | Gary Drinan | 3-Jul-20 | 553679 | 6928443 | 777 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321339 | Gary Drinan | 3-Jul-20 | 553630 | 6928464 | 775 | Goldcrest | 70 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321340 | Gary Drinan | 3-Jul-20 | 553580 | 6928466 | 773 | Goldcrest | 50 | a/b | black | | | | | | | organics | frozen | buck brush | mid slope | |
| 1321341 | Gary Drinan | 3-Jul-20 | 553528 | 6928480 | 769 | Goldcrest | 40 | a/b | black | | | | | | | organics | frozen | buck brush | mid slope | |
| 1321342 | Gary Drinan | 3-Jul-20 | 553478 | 6928489 | 765 | Goldcrest | 40 | a/b | black | | | | | | | organics | frozen | buck brush | mid slope | |
| 1321343 | Gary Drinan | 3-Jul-20 | 553282 | 6928515 | 756 | Goldcrest | 50 | b/c | light brown | | | | | | | weathered bedrock | moist | evergreen forest | mid slope | |
| 1321344 | Gary Drinan | 3-Jul-20 | 553233 | 6928525 | 759 | Goldcrest | 70 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321345 | Gary Drinan | 3-Jul-20 | 553185 | 6928537 | 763 | Goldcrest | 70 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321346 | Gary Drinan | 3-Jul-20 | 553136 | 6928541 | 764 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | aridge topial froze | deciduous forest | mid slope | |
| 1321347 | Gary Drinan | 4-Jul-20 | 552666 | 6928674 | 739 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | evergreen forest | mid slope | |
| 1321348 | Gary Drinan | 4-Jul-20 | 552703 | 6928673 | 752 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321349 | Gary Drinan | 4-Jul-20 | 552756 | 6928666 | 769 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321350 | Gary Drinan | 4-Jul-20 | 552806 | 6928658 | 782 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321351 | Gary Drinan | 4-Jul-20 | 552857 | 6928648 | 792 | Goldcrest | 80 | c | dark grey | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321352 | Gary Drinan | 4-Jul-20 | 552906 | 6928640 | 797 | Goldcrest | 80 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321353 | Gary Drinan | 4-Jul-20 | 552931 | 6928655 | 801 | Goldcrest | 80 | c | dark grey | | | | | | | weathered bedrock | dry | dry | mid slope | |
| 1321354 | Gary Drinan | 4-Jul-20 | 552962 | 6928618 | 792 | Goldcrest | 60 | c | dark brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321355 | Gary Drinan | 4-Jul-20 | 552999 | 6928619 | 787 | Goldcrest | 80 | c | light grey | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321356 | Gary Drinan | 4-Jul-20 | 553050 | 6928614 | 780 | Goldcrest | 40 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321357 | Gary Drinan | 4-Jul-20 | 553111 | 6928595 | 773 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321358 | Gary Drinan | 4-Jul-20 | 553139 | 6928588 | 772 | Goldcrest | 80 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321359 | Gary Drinan | 4-Jul-20 | 553183 | 6928584 | 770 | Goldcrest | 70 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321360 | Gary Drinan | 4-Jul-20 | 553238 | 6928580 | 767 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | evergreen forest | mid slope | |
| 1321361 | Gary Drinan | 4-Jul-20 | 553292 | 6928571 | 761 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | evergreen forest | mid slope | |
| 1321362 | Gary Drinan | 4-Jul-20 | 553334 | 6928568 | 762 | Goldcrest | 40 | c | light brown | | | | | | | weathered bedrock | permafrost | evergreen forest | mid slope | |
| 1321363 | Gary Drinan | 4-Jul-20 | 553391 | 6928549 | 760 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | permafrost | buck brush | mid slope | |
| 1321364 | Gary Drinan | 4-Jul-20 | 553432 | 6928547 | 762 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | permafrost | buck brush | mid slope | |
| 1321365 | Gary Drinan | 4-Jul-20 | 553485 | 6928534 | 767 | Goldcrest | 50 | a | black | | | | | | | weathered bedrock | permafrost | buck brush | valley bottom | |
| 1321366 | Gary Drinan | 4-Jul-20 | 553538 | 6928520 | 770 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | buck brush | mid slope | |
| 1321367 | Gary Drinan | 4-Jul-20 | 553585 | 6928516 | 774 | Goldcrest | 50 | c | light | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321368 | Gary Drinan | 4-Jul-20 | 553629 | 6928508 | 781 | Goldcrest | 50 | c | dark brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |

| GENERAL | | | LOCATION | | | | SAMPLE DESCRIPTION | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Sample Composition (%) | | | | | | | | | |
| Sample ID | User | Date | Easting | Northing | Alt. (m) | Area | Sample Depth (cm) | Horizon Sampled | Sample Colour | Organics | Ang. Rock | Gravel | Sand | Silt | Clay | Parent Material | Moisture Content | Vegetation Cover | Topo Position | Comments |
| 1321369 | Gary Drinan | 4-Jul-20 | 553641 | 6928551 | 791 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321370 | Gary Drinan | 4-Jul-20 | 553593 | 6928563 | 782 | Goldcrest | 40 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321371 | Gary Drinan | 4-Jul-20 | 553544 | 6928572 | 775 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | permafrost | deciduous forest | mid slope | |
| 1321372 | Gary Drinan | 4-Jul-20 | 553497 | 6928582 | 770 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | wet | buck brush | mid slope | |
| 1321373 | Gary Drinan | 4-Jul-20 | 553445 | 6928579 | 766 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | permafrost | buck brush | valley bottom | |
| 1321374 | Gary Drinan | 4-Jul-20 | 553401 | 6928596 | 764 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | buck brush | valley bottom | |
| 1321375 | Gary Drinan | 5-Jul-20 | 552837 | 6929158 | 713 | Goldcrest | 70 | c | light grey | | | | | | | till | moist | deciduous forest | mid slope | |
| 1321376 | Gary Drinan | 5-Jul-20 | 552882 | 6929156 | 724 | Goldcrest | 80 | c | dark grey | | | | | | | till | moist | deciduous forest | mid slope | |
| 1321377 | Gary Drinan | 5-Jul-20 | 552930 | 6929145 | 732 | Goldcrest | 80 | b/c | dark grey | | | | | | | till | permafrost | deciduous forest | mid slope | |
| 1321378 | Gary Drinan | 5-Jul-20 | 552981 | 6929138 | 741 | Goldcrest | 70 | b/c | dark grey | | | | | | | till | permafrost | buck brush | mid slope | |
| 1321379 | Gary Drinan | 5-Jul-20 | 553033 | 6929129 | 745 | Goldcrest | 60 | c | dark grey | | | | | | | till | moist | buck brush | mid slope | |
| 1321380 | Gary Drinan | 5-Jul-20 | 553078 | 6929118 | 745 | Goldcrest | 50 | c | dark grey | | | | | | | till | moist | buck brush | mid slope | |
| 1321381 | Gary Drinan | 5-Jul-20 | 553127 | 6929110 | 744 | Goldcrest | 50 | b/c | dark grey | | | | | | | till | permafrost | buck brush | mid slope | |
| 1321382 | Gary Drinan | 5-Jul-20 | 553180 | 6929098 | 743 | Goldcrest | 50 | b/c | dark grey | | | | | | | till | permafrost | deciduous forest | mid slope | |
| 1321383 | Gary Drinan | 5-Jul-20 | 553226 | 6929090 | 737 | Goldcrest | 40 | b/c | dark grey | | | | | | | till | moist | deciduous forest | mid slope | |
| 1321384 | Gary Drinan | 5-Jul-20 | 553297 | 6929081 | 730 | Goldcrest | 60 | c | dark grey | | | | | | | till | moist | buck brush | mid slope | |
| 1321385 | Gary Drinan | 5-Jul-20 | 553344 | 6929069 | 724 | Goldcrest | 50 | c | dark grey | | | | | | | till | permafrost | buck brush | mid slope | |
| 1321386 | Gary Drinan | 5-Jul-20 | 553391 | 6929063 | 722 | Goldcrest | 40 | b/c | dark grey | | | | | | | till | moist | buck brush | mid slope | |
| 1321387 | Gary Drinan | 5-Jul-20 | 553449 | 6929056 | 729 | Goldcrest | 80 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321388 | Gary Drinan | 5-Jul-20 | 553495 | 6929043 | 735 | Goldcrest | 80 | c | light brown | | | | | | | weathered bedrock | permafrost | buck brush | mid slope | |
| 1321389 | Gary Drinan | 5-Jul-20 | 553544 | 6929036 | 738 | Goldcrest | 80 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321390 | Gary Drinan | 5-Jul-20 | 553594 | 6929027 | 749 | Goldcrest | 70 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321391 | Gary Drinan | 5-Jul-20 | 553645 | 6929014 | 760 | Goldcrest | 90 | c | light grey | | | | | | | till | permafrost | deciduous forest | mid slope | |
| 1321392 | Gary Drinan | 5-Jul-20 | 553694 | 6929009 | 767 | Goldcrest | 70 | c | light grey | | | | | | | till | moist | deciduous forest | mid slope | |
| 1321393 | Gary Drinan | 5-Jul-20 | 553739 | 6928998 | 781 | Goldcrest | 60 | c | light grey | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321394 | Gary Drinan | 5-Jul-20 | 553789 | 6928994 | 792 | Goldcrest | 60 | c | dark grey | | | | | | | till | moist | deciduous forest | mid slope | |
| 1321395 | Gary Drinan | 5-Jul-20 | 553841 | 6928974 | 807 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321396 | Gary Drinan | 5-Jul-20 | 553889 | 6928977 | 816 | Goldcrest | 70 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321397 | Gary Drinan | 5-Jul-20 | 553938 | 6928963 | 826 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | buck brush | mid slope | |
| 1321398 | Gary Drinan | 5-Jul-20 | 553930 | 6929017 | 812 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321399 | Gary Drinan | 5-Jul-20 | 553883 | 6929022 | 800 | Goldcrest | 60 | c | dark brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321400 | Gary Drinan | 5-Jul-20 | 553831 | 6929026 | 788 | Goldcrest | 50 | b/c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321401 | Gary Drinan | 5-Jul-20 | 553778 | 6929046 | 774 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321402 | Gary Drinan | 5-Jul-20 | 553736 | 6929054 | 763 | Goldcrest | 30 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321403 | Gary Drinan | 5-Jul-20 | 553686 | 6929061 | 749 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321404 | Gary Drinan | 5-Jul-20 | 553639 | 6929068 | 744 | Goldcrest | 40 | b/c | light brown | | | | | | | weathered bedrock | wet | deciduous forest | mid slope | |
| 1321405 | Gary Drinan | 5-Jul-20 | 553584 | 6929082 | 736 | Goldcrest | 80 | c | dark grey | | | | | | | till | moist | deciduous forest | mid slope | |
| 1321406 | Gary Drinan | 5-Jul-20 | 553540 | 6929089 | 735 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321407 | Gary Drinan | 6-Jul-20 | 554973 | 6929601 | 843 | Goldcrest | 30 | b/c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321408 | Gary Drinan | 6-Jul-20 | 554940 | 6929640 | 829 | Goldcrest | 40 | b/c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321409 | Gary Drinan | 6-Jul-20 | 554906 | 6929679 | 819 | Goldcrest | 40 | b/c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321410 | Gary Drinan | 6-Jul-20 | 554881 | 6929720 | 811 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321411 | Gary Drinan | 6-Jul-20 | 554842 | 6929755 | 803 | Goldcrest | 40 | b/c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321412 | Gary Drinan | 6-Jul-20 | 554807 | 6929795 | 800 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321413 | Gary Drinan | 6-Jul-20 | 554779 | 6929825 | 798 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321414 | Gary Drinan | 6-Jul-20 | 554747 | 6929868 | 795 | Goldcrest | 40 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | mid slope | |
| 1321415 | Gary Drinan | 6-Jul-20 | 554718 | 6929909 | 797 | Goldcrest | 50 | b/c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | mid slope | |
| 1321416 | Gary Drinan | 6-Jul-20 | 554809 | 6930028 | 818 | Goldcrest | 60 | b/c | light brown | | | | | | | weathered bedrock | deciduous forest | deciduous forest | mid slope | |
| 1321417 | Gary Drinan | 6-Jul-20 | 554788 | 6930071 | 812 | Goldcrest | 60 | c | light grey | | | | | | | weathered bedrock | dry | deciduous forest | ridge top | |
| 1321418 | Gary Drinan | 6-Jul-20 | 554769 | 6930117 | 810 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | ridge top | |
| 1321419 | Gary Drinan | 6-Jul-20 | 554737 | 6930155 | 807 | Goldcrest | 40 | b/c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | ridge top | |
| 1321420 | Gary Drinan | 6-Jul-20 | 554643 | 6930337 | 808 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | ridge top | |
| 1321421 | Gary Drinan | 6-Jul-20 | 554620 | 6930425 | 804 | Goldcrest | 40 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | ridge top | |
| 1321422 | Gary Drinan | 6-Jul-20 | 554599 | 6930529 | 810 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | ridge top | |
| 1321423 | Gary Drinan | 6-Jul-20 | 554582 | 6930577 | 808 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | ridge top | |
| 1321424 | Gary Drinan | 6-Jul-20 | 554505 | 6930626 | 774 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | ridge top | |
| 1321425 | Gary Drinan | 6-Jul-20 | 554404 | 6930646 | 764 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | valley bottom | |
| 1321426 | Gary Drinan | 6-Jul-20 | 554308 | 6930645 | 777 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | deciduous forest | ridge top | |
| 1321427 | Gary Drinan | 6-Jul-20 | 554260 | 6930652 | 763 | Goldcrest | 40 | c | light brown | | | | | | | weathered bedrock | dry | deciduous forest | ridge top | |
| 1321428 | Gary Drinan | 6-Jul-20 | 554156 | 6930677 | 733 | Goldcrest | 50 | c | light grey | | | | | | | till | moist | deciduous forest | ridge top | |
| 1321429 | Gary Drinan | 6-Jul-20 | 554038 | 6930757 | 706 | Goldcrest | 50 | b/c | dark grey | | | | | | | till | moist | deciduous forest | ridge top | |
| 1321430 | Gary Drinan | 6-Jul-20 | 553975 | 6930838 | 694 | Goldcrest | 50 | c | dark grey | | | | | | | till | moist | deciduous forest | valley bottom | |
| 1321431 | Gary Drinan | 7-Jul-20 | 552718 | 6928971 | 719 | Goldcrest | 30 | c | light grey | | | | | | | till | wet | df | moist | |
| 1321432 | Gary Drinan | 7-Jul-20 | 552760 | 6928970 | 726 | Goldcrest | 70 | c | dark grey | | | | | | | till | wet | df | moist | |
| 1321433 | Gary Drinan | 7-Jul-20 | 552810 | 6928957 | 741 | Goldcrest | 60 | b | light grey | | | | | | | till | permoistafrost | df | moist | |
| 1321434 | Gary Drinan | 7-Jul-20 | 552865 | 6928953 | 756 | Goldcrest | 80 | c | light grey | | | | | | | till | wet | bb | moist | |
| 1321435 | Gary Drinan | 7-Jul-20 | 552909 | 6928938 | 772 | Goldcrest | 50 | b/c | light grey | | | | | | | till | wet | wet | moist | |
| 1321436 | Gary Drinan | 7-Jul-20 | 552959 | 6928933 | 782 | Goldcrest | 50 | a/b | dark brown | | | | | | | till | permoistafrost | bb | moist | |

| GENERAL | | | LOCATION | | | | SAMPLE DESCRIPTION | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | Sample Composition (%) | | | | | | | | | |
| Sample ID | User | Date | Easting | Northing | Alt. (m) | Area | Sample Depth (cm) | Horizon Sampled | Sample Colour | Organics | Ang. Rock | Gravel | Sand | Silt | Clay | Parent Material | Moisture Content | Vegetation Cover | Topo Position | Comments |
| 1321437 | Gary Drinan | 7-Jul-20 | 553009 | 6928922 | 794 | Goldcrest | 50 | c | light brown | | | | | | | till | moist | df | moist | |
| 1321438 | Gary Drinan | 7-Jul-20 | 553065 | 6928918 | 804 | Goldcrest | 50 | b/c | light brown | | | | | | | till | moist | df | moist | |
| 1321439 | Gary Drinan | 7-Jul-20 | 553111 | 6928900 | 805 | Goldcrest | 50 | c | light brown | | | | | | | till | moist | df | moist | |
| 1321440 | Gary Drinan | 7-Jul-20 | 553154 | 6928897 | 796 | Goldcrest | 70 | c | light grey | | | | | | | till | wet | df | moist | |
| 1321441 | Gary Drinan | 7-Jul-20 | 553200 | 6928890 | 791 | Goldcrest | 50 | b/c | dark grey | | | | | | | till | moist | df | moist | |
| 1321442 | Gary Drinan | 7-Jul-20 | 553262 | 6928874 | 787 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321443 | Gary Drinan | 7-Jul-20 | 553303 | 6928871 | 784 | Goldcrest | 60 | c | light brown | | | | | | | weathered bedrock | moist | df | moist | |
| 1321444 | Gary Drinan | 7-Jul-20 | 553345 | 6928864 | 766 | Goldcrest | 50 | a/b | black | | | | | | | till | permoistafrost | bb | valley bottomoist | |
| 1321445 | Gary Drinan | 7-Jul-20 | 553210 | 6928934 | 784 | Goldcrest | 60 | c | light grey | | | | | | | till | moist | df | moist | |
| 1321446 | Gary Drinan | 7-Jul-20 | 553262 | 6928928 | 776 | Goldcrest | 50 | c | light brown | | | | | | | weathered bedrock | moist | bb | moist | |
| 1321447 | Gary Drinan | 7-Jul-20 | 553308 | 6928921 | 771 | Goldcrest | 50 | b/c | light brown | | | | | | | weathered bedrock | wet | df | moist | |
| 1321448 | Gary Drinan | 7-Jul-20 | 553360 | 6928908 | 758 | Goldcrest | 50 | a/b | black | | | | | | | till | permoistafrost | bb | valley bottomoist | |
| 1321449 | Gary Drinan | 8-Jul-20 | 553490 | 6928988 | 753 | Goldcrest | 50 | c | dark grey | | | | | | | till | moist | df | moist | |
| 1321450 | Gary Drinan | 8-Jul-20 | 553531 | 6928982 | 755 | Goldcrest | 60 | b/c | light brown | | | | | | | weathered bedrock | moist | df | moist | |

Appendix V: Trench Sample Assay Certificate

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.
9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

| | |
|---|---|
| Submitted By: | Dan Ferraro |
| Receiving Lab: | Canada-Whitehorse |
| Received: | July 17, 2020 |
| Analysis Start: | August 05, 2020 |
| Report Date: | August 12, 2020 |
| Page: | 1 of 4 |

# CERTIFICATE OF ANALYSIS WHI20000134.1

## CLIENT JOB INFORMATION

| | |
|---|---|
| Project: | BE |
| Shipment ID: | BETR-20-01 |
| P.O. Number | |
| Number of Samples: | 71 |

## SAMPLE DISPOSAL

| | |
|---|---|
| DISP-PLP | Dispose of Pulp After 90 days |
| DISP-RJT | Dispose of Reject After 60 days |

Bureau Veritas does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

## SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

| Procedure Code | Number of Samples | Code Description | Test Wgt (g) | Report Status | Lab |
|---|---|---|---|---|---|
| PRP70-250 | 67 | Crush, split and pulverize 250 g rock to 200 mesh | | | WHI |
| FA350-Au | 71 | 50g Fire assay fusion Au by ICP-ES | 50 | Completed | VAN |
| AQ200 | 71 | 1:1:1 Aqua Regia digestion ICP-MS analysis | 0.5 | Completed | VAN |
| SLBHP | 4 | Sort, label and box pulps | | | WHI |
| SHP01 | 71 | Per sample shipping charges for branch shipments | | | VAN |

## ADDITIONAL COMMENTS

Invoice To: Druid Exploration
Box 1485
Dawson City Yukon Y0B 1G0
Canada

CC: Clayton Jones
Daithi Mac Gerailt

BRITISH COLUMBIA CERTIFIED ASSAYER
MARCUS LAU
Production Manager

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Bureau Veritas assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# CERTIFICATE OF ANALYSIS WHI20000134.1

| | Method | WGHT | FA350 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Wgt | Au | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V |
| | Unit | kg | ppb | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm |
| | MDL | 0.01 | 2 | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 |
| 1878401 | Rock | 4.04 | 392 | 0.5 | 18.2 | 11.0 | 77 | 0.6 | 13.0 | 7.6 | 454 | 2.26 | 2062.2 | 0.7 | 276.9 | 7.2 | 84 | 0.6 | 3.2 | 0.1 | 34 |
| 1878402 | Rock | 5.17 | 269 | 0.4 | 8.7 | 12.2 | 87 | 0.5 | 11.5 | 3.6 | 275 | 1.66 | 1854.2 | 0.5 | 199.8 | 7.4 | 33 | 0.5 | 2.5 | 0.1 | 14 |
| 1878403 | Rock | 3.52 | 318 | 0.3 | 10.0 | 8.4 | 48 | 0.6 | 8.2 | 3.1 | 308 | 1.48 | 3756.9 | 1.1 | 264.3 | 5.6 | 53 | 0.5 | 3.3 | 0.1 | 11 |
| 1878404 | Rock | 4.34 | 283 | 0.4 | 11.9 | 10.6 | 62 | 0.5 | 11.6 | 5.0 | 395 | 1.68 | 1810.8 | 0.6 | 201.8 | 6.5 | 62 | 0.6 | 2.9 | 0.1 | 26 |
| 1878405 | Rock | 4.29 | 137 | 0.5 | 33.1 | 7.1 | 69 | 0.2 | 22.1 | 17.2 | 1113 | 4.55 | 655.3 | 0.3 | 108.7 | 3.2 | 111 | 0.3 | 1.5 | <0.1 | 112 |
| 1878406 | Rock | 3.79 | 221 | 0.5 | 19.6 | 8.4 | 73 | 0.4 | 14.7 | 12.8 | 733 | 3.68 | 1858.4 | 0.4 | 174.2 | 4.8 | 83 | 0.5 | 2.4 | <0.1 | 78 |
| 1878407 | Rock | 4.12 | 681 | 0.4 | 12.3 | 9.6 | 59 | 0.7 | 28.6 | 10.8 | 554 | 2.29 | 3831.0 | 0.7 | 506.8 | 6.9 | 32 | 0.3 | 3.9 | 0.1 | 9 |
| 1878408 | Rock | 4.66 | 870 | 0.4 | 11.5 | 9.7 | 64 | 1.1 | 29.1 | 12.7 | 878 | 2.24 | 6304.8 | 1.0 | 689.9 | 7.1 | 48 | 0.3 | 6.1 | <0.1 | 6 |
| 1878409 | Rock | 4.70 | 2414 | 0.3 | 12.3 | 18.6 | 51 | 1.6 | 22.9 | 10.1 | 717 | 2.78 | >10000 | 0.8 | 1982.4 | 7.0 | 169 | 0.3 | 15.5 | 0.2 | 6 |
| 1878410 | Rock | 4.49 | 1465 | 0.3 | 26.4 | 18.5 | 58 | 1.0 | 23.3 | 14.9 | 506 | 2.26 | 9485.4 | 0.7 | 1107.3 | 8.0 | 148 | 0.3 | 11.1 | 0.2 | 7 |
| 1878411 | Rock | 3.71 | 919 | 0.3 | 25.2 | 14.5 | 55 | 0.5 | 21.5 | 10.0 | 671 | 1.90 | 5450.0 | 0.6 | 738.3 | 6.0 | 77 | 0.2 | 7.0 | 0.1 | 6 |
| 1878412 | Rock | 3.87 | 1370 | 0.2 | 29.8 | 16.4 | 46 | 1.6 | 16.5 | 9.5 | 401 | 2.22 | 5813.2 | 0.7 | 1359.6 | 7.9 | 52 | 0.2 | 6.1 | 0.1 | 4 |
| 1878413 | Rock | 4.03 | 1203 | 0.2 | 39.2 | 19.2 | 54 | 1.0 | 14.9 | 7.4 | 277 | 2.59 | 4604.9 | 0.6 | 1090.1 | 9.5 | 33 | 0.2 | 4.8 | 0.1 | 7 |
| 1878414 | Rock | 4.66 | 924 | 0.2 | 88.3 | 59.7 | 89 | 24.2 | 13.7 | 8.8 | 416 | 1.58 | 6421.1 | 0.6 | 853.6 | 6.7 | 85 | 1.0 | 25.0 | 0.2 | 4 |
| 1878415 | Rock | 4.52 | 1753 | 0.4 | 113.3 | 46.8 | 169 | 16.4 | 26.9 | 17.3 | 914 | 3.00 | >10000 | 1.0 | 1438.4 | 8.4 | 189 | 1.6 | 24.4 | 0.2 | 8 |
| 1878416 | Rock | 4.01 | 1166 | 0.3 | 17.9 | 12.9 | 38 | 2.2 | 7.1 | 4.0 | 149 | 1.78 | 7883.4 | 0.4 | 795.6 | 5.1 | 67 | 0.2 | 8.0 | 0.1 | 4 |
| 1878417 | Rock | 3.73 | 1611 | 0.3 | 12.6 | 11.0 | 14 | 1.1 | 3.8 | 2.0 | 113 | 1.38 | 7739.8 | 0.2 | 1093.2 | 3.3 | 17 | 0.1 | 7.1 | 0.1 | 4 |
| 1878418 | Rock | 3.64 | 1855 | 0.2 | 26.0 | 54.7 | 35 | 10.5 | 7.9 | 3.8 | 238 | 1.59 | 5551.2 | 0.4 | 1330.6 | 5.8 | 61 | 0.4 | 9.1 | 0.2 | 8 |
| 1878419 | Rock | 3.46 | 1519 | 0.2 | 69.6 | 60.9 | 66 | 28.6 | 9.6 | 4.1 | 197 | 1.37 | 4734.0 | 0.3 | 1155.1 | 4.0 | 32 | 1.0 | 20.7 | 0.2 | 10 |
| 1878420 | Rock | 3.05 | 550 | 0.2 | 8.6 | 13.1 | 26 | 0.4 | 7.7 | 4.1 | 511 | 1.26 | 3179.9 | 0.3 | 425.0 | 2.9 | 26 | 0.1 | 3.7 | <0.1 | 4 |
| 1878421 | Rock | 3.51 | 281 | 0.2 | 7.9 | 7.4 | 21 | 0.4 | 8.2 | 4.0 | 453 | 1.11 | 1651.7 | 0.3 | 234.8 | 4.0 | 21 | 0.1 | 2.5 | <0.1 | 5 |
| 1878422 | Rock | 3.33 | 228 | 0.3 | 8.1 | 12.9 | 19 | 0.3 | 7.4 | 3.8 | 165 | 0.96 | 1015.7 | 0.2 | 196.1 | 4.1 | 14 | <0.1 | 2.1 | <0.1 | 6 |
| 1878423 | Rock | 4.85 | 255 | 0.3 | 14.0 | 9.3 | 32 | 0.3 | 9.2 | 3.3 | 145 | 1.98 | 1883.1 | 0.3 | 143.8 | 5.3 | 15 | 0.1 | 2.5 | <0.1 | 6 |
| 1878424 | Rock | 3.73 | 554 | 0.2 | 23.7 | 12.8 | 51 | 0.4 | 18.6 | 6.1 | 164 | 1.92 | 2514.2 | 0.5 | 462.4 | 6.6 | 9 | 0.2 | 3.4 | <0.1 | 7 |
| 1878425 | Rock Pulp | 0.06 | 6333 | 1.4 | 13.7 | 19.0 | 58 | 0.1 | 10.6 | 1.1 | 1068 | 0.46 | 4363.7 | 1.7 | 6063.3 | 1.3 | 187 | 0.5 | 17.5 | 0.4 | 22 |
| 1878426 | Rock Pulp | 0.06 | 3 | 3.2 | 21.4 | 2.3 | 35 | 0.5 | 19.2 | 9.3 | 363 | 1.92 | 3.7 | 0.3 | <0.5 | 0.9 | 30 | 0.3 | 0.2 | <0.1 | 58 |
| 1878427 | Rock | 2.98 | 486 | 0.2 | 19.4 | 16.5 | 16 | 0.4 | 5.4 | 1.8 | 112 | 1.44 | 2636.4 | 0.4 | 425.3 | 4.8 | 9 | <0.1 | 2.4 | 0.1 | 5 |
| 1878428 | Rock | 3.64 | 860 | 0.2 | 22.9 | 10.8 | 21 | 0.6 | 8.0 | 2.1 | 93 | 1.32 | 3732.8 | 0.5 | 788.2 | 7.4 | 21 | <0.1 | 2.9 | <0.1 | 7 |
| 1878429 | Rock | 3.36 | 601 | 0.2 | 22.8 | 13.1 | 38 | 0.8 | 13.6 | 5.1 | 230 | 1.69 | 2882.8 | 0.5 | 557.0 | 5.7 | 39 | 0.1 | 3.4 | <0.1 | 7 |
| 1878430 | Rock | 3.58 | 1105 | 0.3 | 41.6 | 22.4 | 58 | 0.8 | 17.6 | 9.2 | 324 | 2.34 | 3300.5 | 0.9 | 1036.1 | 7.9 | 29 | 0.2 | 3.8 | 0.2 | 6 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# CERTIFICATE OF ANALYSIS WHI20000134.1

| | Method | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Ca | P | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | % | % | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 0.01 | 0.001 | 1 | 1 | 0.01 | 1 | 0.001 | 20 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1878401 | Rock | 0.54 | 0.101 | 22 | 13 | 0.28 | 221 | 0.007 | <20 | 0.79 | 0.035 | 0.11 | 0.1 | 0.02 | 5.3 | <0.1 | <0.05 | 2 | <0.5 | <0.2 |
| 1878402 | Rock | 0.22 | 0.042 | 20 | 9 | 0.10 | 166 | 0.003 | <20 | 0.45 | 0.038 | 0.11 | <0.1 | 0.02 | 4.2 | <0.1 | <0.05 | 2 | <0.5 | <0.2 |
| 1878403 | Rock | 0.27 | 0.043 | 13 | 9 | 0.07 | 440 | 0.005 | <20 | 0.39 | 0.041 | 0.09 | <0.1 | 0.01 | 3.6 | <0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878404 | Rock | 0.43 | 0.063 | 18 | 13 | 0.22 | 204 | 0.010 | <20 | 0.60 | 0.044 | 0.09 | <0.1 | 0.01 | 4.7 | <0.1 | <0.05 | 2 | <0.5 | <0.2 |
| 1878405 | Rock | 1.82 | 0.142 | 14 | 24 | 1.30 | 203 | 0.019 | <20 | 1.47 | 0.030 | 0.06 | <0.1 | 0.02 | 7.1 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1878406 | Rock | 1.39 | 0.142 | 20 | 13 | 0.83 | 278 | 0.015 | <20 | 1.33 | 0.035 | 0.07 | <0.1 | 0.03 | 6.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1878407 | Rock | 0.27 | 0.041 | 19 | 11 | 0.07 | 374 | 0.002 | <20 | 0.41 | 0.026 | 0.11 | 0.1 | 0.02 | 5.1 | <0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878408 | Rock | 0.25 | 0.029 | 20 | 6 | 0.04 | 764 | 0.001 | <20 | 0.34 | 0.021 | 0.12 | 0.2 | 0.02 | 5.7 | <0.1 | <0.05 | <1 | 0.8 | <0.2 |
| 1878409 | Rock | 0.36 | 0.030 | 18 | 6 | 0.04 | 1084 | 0.002 | <20 | 0.35 | 0.021 | 0.16 | 0.2 | 0.03 | 4.0 | <0.1 | <0.05 | 1 | 5.4 | <0.2 |
| 1878410 | Rock | 0.23 | 0.027 | 21 | 6 | 0.05 | 390 | 0.002 | <20 | 0.32 | 0.010 | 0.14 | 0.2 | 0.03 | 3.4 | <0.1 | <0.05 | 1 | 1.7 | <0.2 |
| 1878411 | Rock | 0.17 | 0.024 | 17 | 6 | 0.06 | 241 | 0.003 | <20 | 0.39 | 0.012 | 0.17 | 0.1 | 0.02 | 2.6 | <0.1 | <0.05 | 1 | 0.9 | <0.2 |
| 1878412 | Rock | 0.16 | 0.027 | 18 | 4 | 0.03 | 122 | 0.001 | <20 | 0.28 | 0.014 | 0.17 | 0.1 | 0.02 | 2.3 | <0.1 | <0.05 | <1 | 1.3 | <0.2 |
| 1878413 | Rock | 0.19 | 0.031 | 22 | 6 | 0.07 | 208 | 0.003 | <20 | 0.45 | 0.018 | 0.21 | 0.1 | 0.02 | 2.5 | <0.1 | <0.05 | 2 | 1.7 | <0.2 |
| 1878414 | Rock | 0.16 | 0.028 | 14 | 4 | 0.03 | 184 | 0.002 | <20 | 0.27 | 0.017 | 0.12 | 0.2 | 0.05 | 2.7 | <0.1 | <0.05 | <1 | 1.9 | <0.2 |
| 1878415 | Rock | 0.33 | 0.036 | 23 | 7 | 0.07 | 340 | 0.005 | <20 | 0.39 | 0.019 | 0.20 | 0.2 | 0.02 | 5.7 | 0.1 | <0.05 | 1 | 2.4 | 0.3 |
| 1878416 | Rock | 0.10 | 0.020 | 12 | 3 | 0.03 | 389 | 0.002 | <20 | 0.28 | 0.013 | 0.12 | <0.1 | 0.01 | 2.3 | <0.1 | <0.05 | <1 | 4.0 | <0.2 |
| 1878417 | Rock | 0.09 | 0.013 | 8 | 3 | 0.03 | 244 | 0.003 | <20 | 0.24 | 0.010 | 0.11 | <0.1 | 0.02 | 1.4 | <0.1 | <0.05 | <1 | 7.5 | <0.2 |
| 1878418 | Rock | 0.15 | 0.021 | 15 | 5 | 0.05 | 302 | 0.004 | <20 | 0.33 | 0.016 | 0.15 | <0.1 | 0.03 | 2.7 | <0.1 | <0.05 | <1 | 1.2 | <0.2 |
| 1878419 | Rock | 0.14 | 0.014 | 10 | 5 | 0.13 | 269 | 0.006 | <20 | 0.38 | 0.015 | 0.11 | 0.1 | 0.04 | 2.0 | <0.1 | <0.05 | 1 | 1.7 | <0.2 |
| 1878420 | Rock | 0.18 | 0.011 | 7 | 3 | 0.03 | 395 | 0.002 | <20 | 0.18 | 0.006 | 0.09 | <0.1 | <0.01 | 1.3 | <0.1 | <0.05 | <1 | 0.7 | <0.2 |
| 1878421 | Rock | 0.34 | 0.011 | 10 | 4 | 0.06 | 209 | 0.004 | <20 | 0.21 | 0.011 | 0.11 | <0.1 | 0.01 | 1.5 | <0.1 | <0.05 | <1 | 0.9 | <0.2 |
| 1878422 | Rock | 0.07 | 0.011 | 9 | 4 | 0.03 | 193 | 0.004 | <20 | 0.23 | 0.013 | 0.12 | <0.1 | 0.01 | 1.5 | <0.1 | <0.05 | <1 | 0.6 | <0.2 |
| 1878423 | Rock | 0.07 | 0.018 | 8 | 4 | 0.03 | 237 | 0.003 | <20 | 0.24 | 0.011 | 0.14 | <0.1 | 0.02 | 1.2 | <0.1 | 0.07 | <1 | 1.1 | <0.2 |
| 1878424 | Rock | 0.09 | 0.016 | 12 | 5 | 0.04 | 188 | 0.004 | <20 | 0.29 | 0.007 | 0.17 | <0.1 | 0.01 | 1.8 | <0.1 | <0.05 | <1 | 1.7 | <0.2 |
| 1878425 | Rock Pulp | 31.86 | 0.019 | 6 | 23 | 5.96 | 42 | 0.001 | <20 | 0.20 | 0.012 | 0.06 | 3.7 | 4.42 | 2.1 | 16.0 | <0.05 | <1 | <0.5 | <0.2 |
| 1878426 | Rock Pulp | 0.73 | 0.050 | 5 | 23 | 0.46 | 93 | 0.115 | <20 | 1.05 | 0.056 | 0.08 | 19.1 | 0.02 | 4.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1878427 | Rock | 0.08 | 0.017 | 13 | 4 | 0.03 | 200 | 0.002 | <20 | 0.27 | 0.012 | 0.17 | <0.1 | 0.02 | 1.5 | <0.1 | <0.05 | <1 | 2.0 | <0.2 |
| 1878428 | Rock | 0.09 | 0.017 | 15 | 5 | 0.04 | 242 | 0.003 | <20 | 0.38 | 0.014 | 0.17 | <0.1 | <0.01 | 1.6 | <0.1 | <0.05 | 1 | 3.0 | <0.2 |
| 1878429 | Rock | 0.11 | 0.021 | 13 | 5 | 0.04 | 373 | 0.003 | <20 | 0.37 | 0.018 | 0.20 | <0.1 | 0.01 | 2.4 | <0.1 | 0.08 | 1 | 1.1 | <0.2 |
| 1878430 | Rock | 0.12 | 0.037 | 17 | 5 | 0.04 | 344 | 0.002 | <20 | 0.35 | 0.008 | 0.20 | <0.1 | 0.01 | 2.7 | <0.1 | <0.05 | 1 | 1.8 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# CERTIFICATE OF ANALYSIS WHI20000134.1

| | Method | WGHT | FA350 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Wgt | Au | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V |
| | Unit | kg | ppb | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm |
| | MDL | 0.01 | 2 | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 |
| 1878431 | Rock | 4.14 | 428 | 0.3 | 15.9 | 14.9 | 30 | 0.5 | 8.3 | 1.8 | 95 | 1.64 | 1947.3 | 0.4 | 294.0 | 4.5 | 9 | 0.2 | 2.3 | <0.1 | 4 |
| 1878432 | Rock | 3.59 | 315 | 0.2 | 12.3 | 10.1 | 29 | 0.4 | 9.4 | 4.9 | 266 | 1.07 | 1843.5 | 0.2 | 257.2 | 3.3 | 8 | 0.1 | 2.4 | <0.1 | 5 |
| 1878433 | Rock | 3.17 | 265 | 0.3 | 20.5 | 17.9 | 54 | 0.5 | 21.9 | 12.1 | 746 | 1.68 | 829.0 | 0.2 | 131.6 | 4.2 | 11 | 0.2 | 2.0 | <0.1 | 9 |
| 1878434 | Rock | 4.37 | 498 | 0.8 | 27.4 | 19.7 | 73 | 1.6 | 35.0 | 18.2 | 1353 | 3.05 | 1832.6 | 0.5 | 173.5 | 5.1 | 41 | 0.5 | 3.9 | 0.2 | 12 |
| 1878435 | Rock | 4.59 | 232 | 0.4 | 12.3 | 10.4 | 57 | 0.7 | 32.2 | 7.9 | 381 | 1.75 | 1593.4 | 0.4 | 177.3 | 6.3 | 10 | 0.4 | 1.4 | 0.1 | 6 |
| 1878436 | Rock | 3.85 | 112 | 2.0 | 10.3 | 9.5 | 46 | 0.3 | 12.3 | 3.1 | 275 | 1.91 | 861.2 | 0.3 | 97.4 | 6.4 | 10 | 0.2 | 0.9 | 0.1 | 3 |
| 1878437 | Rock | 2.75 | 138 | 1.7 | 8.5 | 11.7 | 58 | 0.3 | 12.9 | 3.9 | 383 | 2.06 | 757.2 | 0.3 | 133.1 | 7.1 | 8 | 0.3 | 0.8 | 0.1 | 5 |
| 1878438 | Rock | 3.56 | 225 | 0.6 | 12.2 | 10.9 | 42 | 0.3 | 11.1 | 4.0 | 256 | 1.64 | 1111.3 | 0.3 | 185.2 | 5.9 | 10 | 0.1 | 1.0 | 0.1 | 9 |
| 1878439 | Rock | 3.01 | 169 | 0.7 | 11.7 | 20.3 | 41 | 0.9 | 10.2 | 3.3 | 270 | 1.82 | 986.0 | 0.3 | 144.5 | 6.0 | 10 | 0.2 | 1.4 | 0.2 | 6 |
| 1878440 | Rock | 3.25 | 123 | 0.5 | 9.8 | 13.3 | 43 | 0.1 | 8.3 | 3.1 | 354 | 1.69 | 882.9 | 0.3 | 117.1 | 6.9 | 9 | 0.1 | 0.7 | 0.1 | 5 |
| 1878441 | Rock | 3.31 | 110 | 0.4 | 8.9 | 14.1 | 58 | 0.1 | 8.3 | 2.7 | 353 | 1.90 | 876.1 | 0.3 | 111.0 | 7.6 | 8 | <0.1 | 0.6 | 0.2 | 3 |
| 1878442 | Rock | 3.12 | 68 | 0.5 | 8.6 | 13.8 | 48 | <0.1 | 5.7 | 2.2 | 259 | 1.43 | 526.4 | 0.2 | 64.6 | 8.4 | 6 | <0.1 | 0.5 | 0.2 | <2 |
| 1878443 | Rock | 3.33 | 32 | 1.6 | 6.1 | 11.3 | 21 | <0.1 | 4.3 | 1.4 | 127 | 1.40 | 259.8 | 0.3 | 30.3 | 5.5 | 11 | <0.1 | 0.4 | <0.1 | 4 |
| 1878444 | Rock | 3.66 | 30 | 1.0 | 6.5 | 11.7 | 24 | <0.1 | 5.3 | 1.4 | 104 | 1.08 | 224.5 | 0.3 | 28.1 | 6.3 | 13 | <0.1 | 0.5 | <0.1 | 4 |
| 1878445 | Rock | 4.10 | 57 | 0.7 | 9.3 | 14.1 | 43 | 0.1 | 7.0 | 2.4 | 160 | 1.54 | 401.3 | 0.3 | 58.7 | 8.4 | 10 | 0.1 | 0.6 | 0.2 | 6 |
| 1878446 | Rock | 3.63 | 102 | 0.4 | 8.4 | 14.2 | 50 | 0.1 | 6.7 | 2.7 | 163 | 1.40 | 395.8 | 0.3 | 89.5 | 9.4 | 8 | 0.1 | 0.5 | 0.2 | 6 |
| 1878447 | Rock | 3.19 | 143 | 0.2 | 8.3 | 15.0 | 44 | 0.1 | 5.2 | 2.1 | 187 | 1.31 | 575.4 | 0.3 | 114.4 | 9.0 | 10 | 0.1 | 0.5 | 0.2 | 7 |
| 1878448 | Rock | 3.24 | 85 | 0.3 | 12.1 | 12.5 | 43 | 0.1 | 8.9 | 3.2 | 229 | 1.64 | 545.5 | 0.2 | 72.6 | 7.7 | 10 | 0.1 | 0.7 | 0.1 | 12 |
| 1878449 | Rock | 2.35 | 54 | 0.5 | 11.0 | 11.5 | 45 | 0.1 | 8.6 | 3.3 | 249 | 1.66 | 319.9 | 0.2 | 45.7 | 7.3 | 9 | 0.1 | 0.7 | 0.1 | 12 |
| 1878450 | Rock Pulp | 0.06 | 256 | 198.6 | 2385.2 | 37.7 | 314 | 0.7 | 33.7 | 12.7 | 541 | 3.33 | 18.5 | 0.3 | 154.2 | 1.1 | 43 | 1.1 | 0.7 | 0.3 | 80 |
| 1878451 | Rock Pulp | 0.06 | 5 | 3.3 | 23.8 | 2.4 | 36 | 0.6 | 20.3 | 10.1 | 355 | 2.07 | 3.5 | 0.3 | 1.3 | 1.0 | 28 | 0.2 | 0.2 | <0.1 | 54 |
| 1878452 | Rock | 2.91 | 17 | 0.3 | 5.9 | 13.2 | 41 | <0.1 | 5.5 | 2.0 | 215 | 1.36 | 146.9 | 0.2 | 16.4 | 7.3 | 6 | <0.1 | 0.3 | 0.1 | 4 |
| 1878453 | Rock | 2.62 | 27 | 0.8 | 6.4 | 14.3 | 37 | <0.1 | 4.4 | 2.0 | 257 | 1.71 | 184.1 | 0.3 | 19.7 | 7.5 | 4 | <0.1 | 0.4 | 0.2 | 2 |
| 1878454 | Rock | 2.88 | 9 | 2.8 | 27.9 | 9.7 | 65 | <0.1 | 55.6 | 14.5 | 759 | 3.03 | 134.7 | 0.5 | 3.8 | 6.5 | 52 | 0.5 | 1.0 | 0.1 | 19 |
| 1878455 | Rock | 2.48 | 14 | 0.9 | 66.7 | 3.3 | 71 | 0.2 | 95.8 | 26.1 | 1159 | 3.07 | 189.9 | 0.2 | 4.6 | 1.3 | 210 | 1.0 | 3.6 | <0.1 | 49 |
| 1878456 | Rock | 4.27 | 18 | 0.4 | 69.7 | 1.6 | 93 | <0.1 | 193.2 | 48.5 | 1333 | 6.51 | 88.9 | <0.1 | 2.0 | 0.5 | 84 | 0.3 | 2.0 | <0.1 | 159 |
| 1878457 | Rock | 3.47 | 23 | 0.3 | 52.2 | 1.7 | 58 | <0.1 | 118.5 | 33.5 | 1172 | 4.79 | 128.7 | 0.1 | 8.8 | 0.7 | 154 | 0.1 | 0.9 | <0.1 | 105 |
| 1878458 | Rock | 3.90 | 42 | 0.4 | 54.3 | 1.4 | 64 | <0.1 | 133.7 | 34.1 | 1422 | 4.88 | 131.6 | 0.1 | 17.9 | 0.5 | 197 | 0.2 | 1.2 | <0.1 | 94 |
| 1878459 | Rock | 3.07 | 5 | 0.2 | 46.0 | 0.8 | 59 | <0.1 | 139.0 | 33.9 | 1697 | 5.07 | 21.6 | <0.1 | <0.5 | 0.3 | 284 | 0.1 | 0.4 | <0.1 | 138 |
| 1878460 | Rock | 2.46 | 48 | 0.3 | 48.9 | 1.1 | 59 | <0.1 | 124.4 | 34.1 | 1621 | 5.09 | 26.2 | 0.1 | 1.1 | 0.3 | 338 | 0.2 | 0.4 | <0.1 | 132 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# CERTIFICATE OF ANALYSIS WHI20000134.1

| | Method | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Ca | P | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | % | % | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 0.01 | 0.001 | 1 | 1 | 0.01 | 1 | 0.001 | 20 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1878431 | Rock | 0.06 | 0.013 | 10 | 3 | 0.01 | 359 | <0.001 | <20 | 0.20 | 0.004 | 0.17 | <0.1 | 0.01 | 1.4 | <0.1 | 0.07 | <1 | 0.9 | <0.2 |
| 1878432 | Rock | 0.07 | 0.009 | 9 | 3 | 0.03 | 959 | 0.002 | <20 | 0.21 | 0.007 | 0.11 | <0.1 | <0.01 | 1.4 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878433 | Rock | 0.10 | 0.014 | 11 | 5 | 0.05 | 345 | 0.006 | <20 | 0.29 | 0.007 | 0.13 | <0.1 | 0.01 | 2.6 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878434 | Rock | 0.13 | 0.024 | 11 | 7 | 0.06 | 535 | 0.004 | <20 | 0.41 | 0.009 | 0.15 | <0.1 | 0.02 | 4.0 | 0.1 | 0.07 | 1 | 1.4 | <0.2 |
| 1878435 | Rock | 0.11 | 0.014 | 23 | 4 | 0.04 | 370 | 0.002 | <20 | 0.34 | 0.026 | 0.19 | <0.1 | <0.01 | 4.4 | 0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878436 | Rock | 0.07 | 0.017 | 26 | 2 | 0.04 | 401 | 0.002 | <20 | 0.35 | 0.022 | 0.16 | <0.1 | <0.01 | 3.0 | 0.2 | <0.05 | 1 | <0.5 | <0.2 |
| 1878437 | Rock | 0.07 | 0.015 | 24 | 3 | 0.04 | 385 | 0.003 | <20 | 0.38 | 0.011 | 0.15 | <0.1 | 0.03 | 2.4 | 0.3 | <0.05 | 1 | 0.5 | <0.2 |
| 1878438 | Rock | 0.11 | 0.017 | 20 | 5 | 0.09 | 300 | 0.006 | <20 | 0.44 | 0.017 | 0.16 | <0.1 | 0.02 | 2.6 | 0.2 | <0.05 | 1 | <0.5 | <0.2 |
| 1878439 | Rock | 0.09 | 0.014 | 21 | 5 | 0.06 | 327 | 0.004 | <20 | 0.41 | 0.018 | 0.17 | <0.1 | 0.02 | 2.4 | 0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878440 | Rock | 0.10 | 0.014 | 23 | 3 | 0.06 | 260 | 0.003 | <20 | 0.36 | 0.015 | 0.17 | <0.1 | 0.02 | 2.8 | 0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878441 | Rock | 0.08 | 0.019 | 30 | 2 | 0.05 | 270 | 0.001 | <20 | 0.41 | 0.015 | 0.20 | <0.1 | 0.01 | 2.5 | <0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878442 | Rock | 0.06 | 0.016 | 32 | 2 | 0.05 | 338 | 0.001 | <20 | 0.34 | 0.006 | 0.20 | <0.1 | 0.02 | 2.1 | <0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878443 | Rock | 0.05 | 0.014 | 20 | 3 | 0.04 | 333 | 0.003 | <20 | 0.37 | 0.014 | 0.22 | <0.1 | <0.01 | 1.0 | 0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878444 | Rock | 0.04 | 0.012 | 20 | 5 | 0.04 | 467 | 0.004 | <20 | 0.34 | 0.028 | 0.18 | <0.1 | 0.01 | 1.2 | 0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878445 | Rock | 0.08 | 0.015 | 29 | 4 | 0.07 | 599 | 0.005 | <20 | 0.51 | 0.017 | 0.25 | <0.1 | 0.01 | 2.1 | 0.2 | <0.05 | 1 | <0.5 | <0.2 |
| 1878446 | Rock | 0.09 | 0.015 | 32 | 4 | 0.08 | 460 | 0.004 | <20 | 0.46 | 0.009 | 0.26 | <0.1 | 0.02 | 2.4 | 0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878447 | Rock | 0.09 | 0.015 | 29 | 3 | 0.08 | 411 | 0.003 | <20 | 0.44 | 0.011 | 0.26 | <0.1 | 0.01 | 2.4 | 0.2 | <0.05 | 1 | <0.5 | <0.2 |
| 1878448 | Rock | 0.14 | 0.017 | 27 | 6 | 0.11 | 349 | 0.009 | <20 | 0.56 | 0.014 | 0.22 | <0.1 | 0.02 | 2.5 | 0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878449 | Rock | 0.12 | 0.017 | 25 | 7 | 0.11 | 388 | 0.010 | <20 | 0.58 | 0.014 | 0.25 | <0.1 | 0.02 | 2.6 | 0.2 | <0.05 | 2 | <0.5 | <0.2 |
| 1878450 | Rock Pulp | 0.97 | 0.059 | 5 | 41 | 0.83 | 222 | 0.143 | <20 | 1.77 | 0.110 | 0.16 | 5.5 | 0.09 | 6.0 | 0.1 | 0.36 | 6 | 0.6 | <0.2 |
| 1878451 | Rock Pulp | 0.76 | 0.060 | 5 | 24 | 0.53 | 95 | 0.104 | <20 | 1.22 | 0.065 | 0.10 | 20.2 | 0.03 | 4.4 | <0.1 | 0.07 | 4 | <0.5 | <0.2 |
| 1878452 | Rock | 0.08 | 0.013 | 26 | 4 | 0.09 | 344 | 0.002 | <20 | 0.48 | 0.012 | 0.26 | <0.1 | 0.01 | 2.3 | 0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878453 | Rock | 0.06 | 0.014 | 24 | 2 | 0.05 | 437 | 0.001 | <20 | 0.47 | 0.013 | 0.25 | <0.1 | <0.01 | 2.0 | 0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878454 | Rock | 2.79 | 0.029 | 20 | 39 | 0.37 | 454 | <0.001 | <20 | 0.68 | 0.022 | 0.21 | <0.1 | 0.02 | 8.3 | 0.3 | <0.05 | 2 | 0.7 | <0.2 |
| 1878455 | Rock | 11.12 | 0.060 | 6 | 95 | 0.82 | 451 | 0.002 | <20 | 0.99 | 0.018 | 0.20 | <0.1 | 0.04 | 13.2 | 0.2 | 0.07 | 2 | 0.8 | <0.2 |
| 1878456 | Rock | 5.07 | 0.045 | 3 | 306 | 3.36 | 285 | 0.003 | <20 | 3.10 | 0.020 | 0.08 | <0.1 | <0.01 | 24.2 | <0.1 | <0.05 | 10 | <0.5 | <0.2 |
| 1878457 | Rock | 6.96 | 0.039 | 3 | 240 | 3.33 | 230 | 0.004 | <20 | 2.62 | 0.014 | 0.11 | <0.1 | 0.01 | 14.8 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1878458 | Rock | 10.28 | 0.037 | 3 | 221 | 2.71 | 297 | 0.007 | <20 | 2.43 | 0.010 | 0.10 | <0.1 | <0.01 | 16.9 | 0.1 | 0.05 | 7 | <0.5 | <0.2 |
| 1878459 | Rock | 13.00 | 0.033 | 2 | 262 | 4.15 | 266 | 0.049 | <20 | 3.64 | 0.010 | 0.09 | <0.1 | <0.01 | 17.8 | <0.1 | 0.07 | 9 | <0.5 | <0.2 |
| 1878460 | Rock | 13.43 | 0.033 | 3 | 235 | 3.80 | 270 | 0.055 | <20 | 3.20 | 0.010 | 0.06 | <0.1 | <0.01 | 17.5 | <0.1 | <0.05 | 8 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# CERTIFICATE OF ANALYSIS WHI20000134.1

| | Method | WGHT | FA350 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Wgt | Au | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V |
| | Unit | kg | ppb | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm |
| | MDL | 0.01 | 2 | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 |
| 1878461 | Rock | 3.16 | 10 | 0.3 | 55.6 | 1.3 | 70 | <0.1 | 161.3 | 35.8 | 1268 | 5.15 | 50.8 | <0.1 | 3.9 | 0.4 | 122 | 0.2 | 0.8 | <0.1 | 136 |
| 1878462 | Rock | 3.66 | 53 | 0.5 | 46.7 | 2.7 | 60 | 0.1 | 109.9 | 30.4 | 924 | 3.76 | 188.2 | 0.1 | 33.8 | 0.6 | 177 | 0.4 | 0.8 | <0.1 | 114 |
| 1878463 | Rock | 2.97 | 5 | 0.2 | 58.7 | 1.6 | 51 | <0.1 | 108.7 | 33.7 | 907 | 4.06 | 18.5 | 0.2 | 0.5 | 0.5 | 102 | 0.1 | 0.5 | <0.1 | 139 |
| 1878464 | Rock | 3.48 | 7 | 0.2 | 69.5 | 1.5 | 63 | <0.1 | 127.0 | 37.6 | 1125 | 4.86 | 26.3 | 0.2 | <0.5 | 0.8 | 147 | 0.2 | 0.5 | <0.1 | 132 |
| 1878465 | Rock | 3.55 | 19 | 1.3 | 15.1 | 10.3 | 32 | 0.1 | 21.9 | 5.9 | 257 | 1.85 | 35.5 | 0.2 | 12.6 | 4.6 | 28 | 0.2 | 0.7 | <0.1 | 15 |
| 1878466 | Rock | 3.65 | 5 | 0.4 | 5.0 | 12.8 | 32 | <0.1 | 5.0 | 2.1 | 147 | 1.03 | 17.2 | 0.1 | 2.2 | 5.4 | 4 | <0.1 | 0.2 | 0.1 | 2 |
| 1878467 | Rock | 2.86 | 8 | 0.3 | 5.5 | 11.7 | 43 | <0.1 | 4.4 | 2.2 | 162 | 1.41 | 27.1 | 0.1 | 3.2 | 6.7 | 5 | <0.1 | 0.2 | 0.1 | <2 |
| 1878468 | Rock | 2.74 | 3 | 0.2 | 4.7 | 12.4 | 40 | <0.1 | 3.8 | 2.0 | 173 | 1.58 | 8.0 | 0.2 | 0.9 | 7.2 | 4 | <0.1 | <0.1 | 0.2 | <2 |
| 1878469 | Rock | 3.42 | <2 | 0.3 | 33.4 | 4.1 | 58 | <0.1 | 94.8 | 24.7 | 769 | 3.77 | 8.7 | 0.1 | <0.5 | 2.2 | 142 | 0.2 | 0.4 | <0.1 | 81 |
| 1878470 | Rock | 6.09 | <2 | 0.2 | 63.9 | 0.7 | 61 | <0.1 | 94.4 | 35.7 | 844 | 5.54 | 5.4 | 0.1 | <0.5 | 0.4 | 52 | 0.2 | 0.4 | <0.1 | 161 |
| 1878471 | Rock | 4.09 | <2 | 0.2 | 57.5 | 0.5 | 52 | <0.1 | 113.4 | 32.4 | 820 | 4.90 | 2.9 | <0.1 | <0.5 | 0.3 | 30 | 0.2 | 0.2 | <0.1 | 146 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# CERTIFICATE OF ANALYSIS WHI20000134.1

| | Method | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Ca | P | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | % | % | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 0.01 | 0.001 | 1 | 1 | 0.01 | 1 | 0.001 | 20 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1878461 | Rock | 6.13 | 0.040 | 2 | 267 | 3.65 | 335 | 0.073 | <20 | 3.52 | 0.017 | 0.09 | <0.1 | <0.01 | 21.5 | <0.1 | <0.05 | 10 | <0.5 | <0.2 |
| 1878462 | Rock | 7.79 | 0.038 | 3 | 247 | 2.52 | 229 | 0.030 | <20 | 2.35 | 0.008 | 0.07 | 0.1 | <0.01 | 14.6 | 0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1878463 | Rock | 6.33 | 0.048 | 2 | 334 | 3.80 | 311 | 0.154 | <20 | 3.73 | 0.014 | 0.05 | 0.2 | <0.01 | 20.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1878464 | Rock | 7.56 | 0.050 | 5 | 424 | 4.35 | 338 | 0.074 | <20 | 3.54 | 0.007 | 0.08 | 0.4 | <0.01 | 26.7 | <0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1878465 | Rock | 1.46 | 0.016 | 18 | 55 | 0.54 | 461 | 0.003 | <20 | 0.68 | 0.016 | 0.12 | <0.1 | <0.01 | 4.7 | <0.1 | <0.05 | 2 | 0.6 | <0.2 |
| 1878466 | Rock | 0.08 | 0.011 | 17 | 4 | 0.12 | 328 | 0.001 | <20 | 0.46 | 0.018 | 0.13 | <0.1 | 0.01 | 1.5 | <0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878467 | Rock | 0.11 | 0.010 | 13 | 2 | 0.22 | 379 | <0.001 | <20 | 0.77 | 0.015 | 0.19 | <0.1 | 0.01 | 2.4 | 0.2 | <0.05 | 2 | <0.5 | <0.2 |
| 1878468 | Rock | 0.08 | 0.010 | 12 | 2 | 0.28 | 284 | <0.001 | <20 | 0.76 | 0.012 | 0.17 | <0.1 | <0.01 | 2.0 | 0.1 | <0.05 | 2 | <0.5 | <0.2 |
| 1878469 | Rock | 6.62 | 0.029 | 5 | 158 | 2.30 | 475 | 0.039 | <20 | 2.62 | 0.012 | 0.08 | <0.1 | <0.01 | 12.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1878470 | Rock | 3.88 | 0.041 | 2 | 255 | 3.82 | 333 | 0.194 | <20 | 4.90 | 0.011 | 0.03 | 0.2 | <0.01 | 16.2 | <0.1 | <0.05 | 12 | <0.5 | <0.2 |
| 1878471 | Rock | 3.09 | 0.038 | 1 | 263 | 3.45 | 146 | 0.216 | <20 | 4.46 | 0.014 | <0.01 | 0.3 | <0.01 | 9.9 | <0.1 | <0.05 | 11 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.
9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# QUALITY CONTROL REPORT WHI20000134.1

| | Method | WGHT | FA350 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Wgt | Au | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V |
| | Unit | kg | ppb | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm |
| | MDL | 0.01 | 2 | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 |
| Pulp Duplicates | | | | | | | | | | | | | | | | | | | | | |
| 1878423 | Rock | 4.85 | 255 | 0.3 | 14.0 | 9.3 | 32 | 0.3 | 9.2 | 3.3 | 145 | 1.98 | 1883.1 | 0.3 | 143.8 | 5.3 | 15 | 0.1 | 2.5 | <0.1 | 6 |
| REP 1878423 | QC | | | 0.3 | 13.4 | 9.5 | 33 | 0.3 | 8.9 | 2.9 | 140 | 1.92 | 1984.0 | 0.4 | 143.4 | 5.6 | 15 | 0.1 | 2.4 | <0.1 | 4 |
| REP 1878429 | QC | | 635 | | | | | | | | | | | | | | | | | | |
| 1878457 | Rock | 3.47 | 23 | 0.3 | 52.2 | 1.7 | 58 | <0.1 | 118.5 | 33.5 | 1172 | 4.79 | 128.7 | 0.1 | 8.8 | 0.7 | 154 | 0.1 | 0.9 | <0.1 | 105 |
| REP 1878457 | QC | | | 0.3 | 50.1 | 1.7 | 59 | <0.1 | 127.1 | 32.9 | 1216 | 4.60 | 124.0 | 0.1 | 8.2 | 0.7 | 152 | 0.2 | 1.0 | <0.1 | 95 |
| REP 1878463 | QC | | 5 | | | | | | | | | | | | | | | | | | |
| Core Reject Duplicates | | | | | | | | | | | | | | | | | | | | | |
| 1878429 | Rock | 3.36 | 601 | 0.2 | 22.8 | 13.1 | 38 | 0.8 | 13.6 | 5.1 | 230 | 1.69 | 2882.8 | 0.5 | 557.0 | 5.7 | 39 | 0.1 | 3.4 | <0.1 | 7 |
| DUP 1878429 | QC | | 650 | 0.2 | 22.1 | 12.9 | 37 | 0.8 | 13.1 | 5.1 | 261 | 1.69 | 2581.7 | 0.5 | 532.8 | 5.6 | 38 | 0.2 | 3.3 | 0.1 | 7 |
| 1878463 | Rock | 2.97 | 5 | 0.2 | 58.7 | 1.6 | 51 | <0.1 | 108.7 | 33.7 | 907 | 4.06 | 18.5 | 0.2 | 0.5 | 0.5 | 102 | 0.1 | 0.5 | <0.1 | 139 |
| DUP 1878463 | QC | | 7 | 0.2 | 67.7 | 1.6 | 58 | <0.1 | 117.0 | 36.2 | 919 | 4.24 | 19.5 | 0.1 | 1.8 | 0.5 | 103 | 0.2 | 0.5 | <0.1 | 141 |
| Reference Materials | | | | | | | | | | | | | | | | | | | | | |
| STD BVGEO01 | Standard | | | 11.5 | 4178.9 | 176.4 | 1859 | 2.5 | 153.7 | 24.8 | 658 | 3.96 | 118.4 | 3.2 | 212.2 | 13.4 | 48 | 6.7 | 2.1 | 23.4 | 77 |
| STD DS11 | Standard | | | 13.5 | 137.0 | 128.6 | 337 | 1.7 | 76.5 | 13.1 | 1099 | 2.93 | 44.4 | 2.3 | 59.0 | 6.5 | 60 | 2.2 | 6.0 | 10.8 | 50 |
| STD DS11 | Standard | | | 14.5 | 150.4 | 140.8 | 360 | 2.0 | 81.1 | 14.1 | 990 | 3.20 | 45.9 | 2.8 | 55.0 | 8.1 | 68 | 2.8 | 8.1 | 12.2 | 53 |
| STD OREAS262 | Standard | | | 0.6 | 116.1 | 54.5 | 149 | 0.5 | 60.5 | 26.0 | 548 | 3.27 | 39.6 | 1.1 | 55.2 | 7.9 | 33 | 0.5 | 2.7 | 0.9 | 21 |
| STD OREAS262 | Standard | | | 0.6 | 126.5 | 57.0 | 156 | 0.5 | 67.3 | 29.4 | 560 | 3.40 | 36.8 | 1.0 | 56.7 | 8.3 | 33 | 0.6 | 2.2 | 0.9 | 22 |
| STD OREAS262 | Standard | | | 0.6 | 120.6 | 60.3 | 164 | 0.5 | 68.2 | 29.3 | 526 | 3.54 | 39.7 | 1.3 | 57.2 | 10.0 | 40 | 0.8 | 2.3 | 1.1 | 24 |
| STD OXA131 | Standard | | 74 | | | | | | | | | | | | | | | | | | |
| STD OXA131 | Standard | | 74 | | | | | | | | | | | | | | | | | | |
| STD OXA131 | Standard | | 75 | | | | | | | | | | | | | | | | | | |
| STD OXA131 | Standard | | 77 | | | | | | | | | | | | | | | | | | |
| STD OXG123 | Standard | | 980 | | | | | | | | | | | | | | | | | | |
| STD OXG123 | Standard | | 1017 | | | | | | | | | | | | | | | | | | |
| STD OXG123 | Standard | | 969 | | | | | | | | | | | | | | | | | | |
| STD OXG141 | Standard | | 929 | | | | | | | | | | | | | | | | | | |
| STD OXG141 Expected | | | 930 | | | | | | | | | | | | | | | | | | |
| STD BVGEO01 Expected | | | | 10.8 | 4415 | 187 | 1741 | 2.53 | 163 | 25 | 733 | 3.7 | 121 | 3.77 | 219 | 14.4 | 55 | 6.5 | 2.2 | 25.6 | 73 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.
9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# QUALITY CONTROL REPORT WHI20000134.1

| | Method | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Ca | P | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | % | % | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 0.01 | 0.001 | 1 | 1 | 0.01 | 1 | 0.001 | 20 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| Pulp Duplicates | | | | | | | | | | | | | | | | | | | | |
| 1878423 | Rock | 0.07 | 0.018 | 8 | 4 | 0.03 | 237 | 0.003 | <20 | 0.24 | 0.011 | 0.14 | <0.1 | 0.02 | 1.2 | <0.1 | 0.07 | <1 | 1.1 | <0.2 |
| REP 1878423 | QC | 0.07 | 0.018 | 8 | 3 | 0.02 | 238 | 0.002 | <20 | 0.22 | 0.010 | 0.13 | <0.1 | <0.01 | 1.2 | <0.1 | <0.05 | <1 | 1.1 | <0.2 |
| REP 1878429 | QC | | | | | | | | | | | | | | | | | | | |
| 1878457 | Rock | 6.96 | 0.039 | 3 | 240 | 3.33 | 230 | 0.004 | <20 | 2.62 | 0.014 | 0.11 | <0.1 | 0.01 | 14.8 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| REP 1878457 | QC | 6.40 | 0.043 | 3 | 228 | 3.68 | 238 | 0.004 | <20 | 2.81 | 0.015 | 0.10 | <0.1 | 0.02 | 14.9 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| REP 1878463 | QC | | | | | | | | | | | | | | | | | | | |
| Core Reject Duplicates | | | | | | | | | | | | | | | | | | | | |
| 1878429 | Rock | 0.11 | 0.021 | 13 | 5 | 0.04 | 373 | 0.003 | <20 | 0.37 | 0.018 | 0.20 | <0.1 | 0.01 | 2.4 | <0.1 | 0.08 | 1 | 1.1 | <0.2 |
| DUP 1878429 | QC | 0.10 | 0.023 | 13 | 5 | 0.04 | 368 | 0.003 | <20 | 0.41 | 0.020 | 0.19 | <0.1 | <0.01 | 2.4 | <0.1 | <0.05 | <1 | 0.9 | <0.2 |
| 1878463 | Rock | 6.33 | 0.048 | 2 | 334 | 3.80 | 311 | 0.154 | <20 | 3.73 | 0.014 | 0.05 | 0.2 | <0.01 | 20.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| DUP 1878463 | QC | 5.97 | 0.054 | 2 | 346 | 3.75 | 310 | 0.148 | <20 | 3.54 | 0.016 | 0.05 | 0.2 | <0.01 | 19.1 | <0.1 | <0.05 | 8 | <0.5 | <0.2 |
| Reference Materials | | | | | | | | | | | | | | | | | | | | |
| STD BVGEO01 | Standard | 1.29 | 0.075 | 23 | 149 | 1.24 | 343 | 0.215 | 30 | 2.32 | 0.200 | 0.89 | 3.8 | 0.10 | 5.4 | 0.7 | 0.61 | 8 | 3.9 | 0.9 |
| STD DS11 | Standard | 1.13 | 0.080 | 15 | 60 | 0.80 | 423 | 0.091 | <20 | 1.11 | 0.064 | 0.37 | 2.7 | 0.28 | 3.0 | 5.2 | 0.28 | 5 | 2.6 | 4.5 |
| STD DS11 | Standard | 1.08 | 0.076 | 19 | 61 | 0.88 | 443 | 0.095 | <20 | 1.16 | 0.073 | 0.41 | 3.0 | 0.28 | 3.4 | 4.9 | 0.31 | 5 | 2.6 | 4.7 |
| STD OREAS262 | Standard | 3.25 | 0.044 | 14 | 38 | 1.22 | 259 | 0.003 | <20 | 1.11 | 0.062 | 0.25 | 0.2 | 0.17 | 3.1 | 0.4 | 0.29 | 4 | <0.5 | 0.2 |
| STD OREAS262 | Standard | 3.07 | 0.037 | 14 | 43 | 1.08 | 254 | 0.003 | <20 | 1.07 | 0.063 | 0.30 | 0.1 | 0.17 | 3.3 | 0.5 | 0.25 | 4 | <0.5 | 0.2 |
| STD OREAS262 | Standard | 3.18 | 0.042 | 18 | 44 | 1.25 | 276 | 0.003 | <20 | 1.28 | 0.069 | 0.32 | 0.1 | 0.18 | 3.6 | 0.5 | 0.26 | 4 | 0.8 | 0.2 |
| STD OXA131 | Standard | | | | | | | | | | | | | | | | | | | |
| STD OXA131 | Standard | | | | | | | | | | | | | | | | | | | |
| STD OXA131 | Standard | | | | | | | | | | | | | | | | | | | |
| STD OXA131 | Standard | | | | | | | | | | | | | | | | | | | |
| STD OXG123 | Standard | | | | | | | | | | | | | | | | | | | |
| STD OXG123 | Standard | | | | | | | | | | | | | | | | | | | |
| STD OXG123 | Standard | | | | | | | | | | | | | | | | | | | |
| STD OXG141 | Standard | | | | | | | | | | | | | | | | | | | |
| STD OXG141 Expected | | | | | | | | | | | | | | | | | | | | |
| STD BVGEO01 Expected | | 1.3219 | 0.0727 | 25.9 | 171 | 1.2963 | 340 | 0.233 | | 2.347 | 0.1924 | 0.89 | 3.5 | 0.1 | 5.97 | 0.62 | 0.6655 | 7.37 | 4.84 | 1.02 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada

PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE

Report Date: August 12, 2020



# QUALITY CONTROL REPORT WHI20000134.1

| | | WGHT Wgt kg 0.01 | FA350 Au ppb 2 | AQ200 Mo ppm 0.1 | AQ200 Cu ppm 0.1 | AQ200 Pb ppm 0.1 | AQ200 Zn ppm 1 | AQ200 Ag ppm 0.1 | AQ200 Ni ppm 0.1 | AQ200 Co ppm 0.1 | AQ200 Mn ppm 1 | AQ200 Fe % 0.01 | AQ200 As ppm 0.5 | AQ200 U ppm 0.1 | AQ200 Au ppb 0.5 | AQ200 Th ppm 0.1 | AQ200 Sr ppm 1 | AQ200 Cd ppm 0.1 | AQ200 Sb ppm 0.1 | AQ200 Bi ppm 0.1 | AQ200 V ppm 2 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| STD DS11 Expected | | | | 13.9 | 149 | 138 | 345 | 1.71 | 77.7 | 14.2 | 1055 | 3.1 | 42.8 | 2.59 | 79 | 7.65 | 67.3 | 2.37 | 7.2 | 12.2 | 50 |
| STD OREAS262 Expected | | | | 0.68 | 118 | 56 | 154 | 0.45 | 62 | 26.9 | 530 | 3.284 | 35.8 | 1.22 | 65 | 9.33 | 36 | 0.61 | 3.39 | 1.03 | 22.5 |
| STD OXA131 Expected | | | 77 | | | | | | | | | | | | | | | | | | |
| STD OXG123 Expected | | | 1008 | | | | | | | | | | | | | | | | | | |
| BLK | Blank | | 3 | | | | | | | | | | | | | | | | | | |
| BLK | Blank | | <2 | | | | | | | | | | | | | | | | | | |
| BLK | Blank | | | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 |
| BLK | Blank | | | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 |
| BLK | Blank | | <2 | | | | | | | | | | | | | | | | | | |
| BLK | Blank | | | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | 0.2 | <1 | <0.1 | <0.1 | <0.1 | <2 |
| BLK | Blank | | <2 | | | | | | | | | | | | | | | | | | |
| Prep Wash | | | | | | | | | | | | | | | | | | | | | |
| ROCK-WHI | Prep Blank | | <2 | 0.9 | 4.1 | 1.1 | 32 | <0.1 | 1.4 | 3.9 | 518 | 1.76 | 0.8 | 0.4 | <0.5 | 2.0 | 26 | <0.1 | <0.1 | <0.1 | 25 |
| ROCK-WHI | Prep Blank | | <2 | 0.8 | 4.1 | 1.2 | 33 | <0.1 | 1.8 | 4.2 | 580 | 1.73 | 0.8 | 0.4 | <0.5 | 1.9 | 18 | <0.1 | <0.1 | <0.1 | 31 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada

PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE

Report Date: August 12, 2020



# QUALITY CONTROL REPORT WHI20000134.1

| | | AQ200 Ca % 0.01 | AQ200 P % 0.001 | AQ200 La ppm 1 | AQ200 Cr ppm 1 | AQ200 Mg % 0.01 | AQ200 Ba ppm 1 | AQ200 Ti % 0.001 | AQ200 B ppm 20 | AQ200 Al % 0.01 | AQ200 Na % 0.001 | AQ200 K % 0.01 | AQ200 W ppm 0.1 | AQ200 Hg ppm 0.01 | AQ200 Sc ppm 0.1 | AQ200 Tl ppm 0.1 | AQ200 S % 0.05 | AQ200 Ga ppm 1 | AQ200 Se ppm 0.5 | AQ200 Te ppm 0.2 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| STD DS11 Expected | | 1.063 | 0.0701 | 18.6 | 61.5 | 0.85 | 417 | 0.0976 | | 1.129 | 0.0694 | 0.4 | 2.9 | 0.26 | 3.1 | 4.9 | 0.2835 | 4.7 | 2.2 | 4.56 |
| STD OREAS262 Expected | | 2.98 | 0.04 | 15.9 | 41.7 | 1.17 | 248 | 0.003 | | 1.3 | 0.071 | 0.312 | 0.13 | 0.17 | 3.24 | 0.47 | 0.269 | 3.9 | 0.4 | 0.23 |
| STD OXA131 Expected | | | | | | | | | | | | | | | | | | | | |
| STD OXG123 Expected | | | | | | | | | | | | | | | | | | | | |
| BLK | Blank | | | | | | | | | | | | | | | | | | | |
| BLK | Blank | | | | | | | | | | | | | | | | | | | |
| BLK | Blank | <0.01 | <0.001 | <1 | <1 | <0.01 | <1 | <0.001 | <20 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <0.01 | <0.001 | <1 | <1 | <0.01 | <1 | <0.001 | <20 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | 0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | | | | | | | | | | | | | | | | | | | |
| BLK | Blank | <0.01 | <0.001 | <1 | <1 | <0.01 | <1 | <0.001 | <20 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | | | | | | | | | | | | | | | | | | | |
| Prep Wash | | | | | | | | | | | | | | | | | | | | |
| ROCK-WHI | Prep Blank | 0.81 | 0.043 | 5 | 3 | 0.50 | 64 | 0.072 | <20 | 0.90 | 0.060 | 0.08 | <0.1 | <0.01 | 2.3 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| ROCK-WHI | Prep Blank | 0.71 | 0.049 | 5 | 5 | 0.58 | 48 | 0.079 | <20 | 0.94 | 0.057 | 0.07 | <0.1 | <0.01 | 3.1 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Appendix VI: Prospecting Rock Sample Assay Certificate

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.
9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

| | |
|---|---|
| Submitted By: | Dan Ferraro |
| Receiving Lab: | Canada-Whitehorse |
| Received: | July 17, 2020 |
| Analysis Start: | August 05, 2020 |
| Report Date: | August 12, 2020 |
| Page: | 1 of 3 |

# CERTIFICATE OF ANALYSIS WHI20000135.1

## CLIENT JOB INFORMATION

| | |
|---|---|
| Project: | BE |
| Shipment ID: | BE-2020-ROCK-01 |
| P.O. Number | |
| Number of Samples: | 49 |

## SAMPLE DISPOSAL

| | |
|---|---|
| DISP-PLP | Dispose of Pulp After 90 days |
| DISP-RJT | Dispose of Reject After 60 days |

Bureau Veritas does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

## SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

| Procedure Code | Number of Samples | Code Description | Test Wgt (g) | Report Status | Lab |
|---|---|---|---|---|---|
| PRP70-250 | 49 | Crush, split and pulverize 250 g rock to 200 mesh | | | WHI |
| FA350-Au | 49 | 50g Fire assay fusion Au by ICP-ES | 50 | Completed | VAN |
| AQ200 | 49 | 1:1:1 Aqua Regia digestion ICP-MS analysis | 0.5 | Completed | VAN |
| SLBHP | 0 | Sort, label and box pulps | | | WHI |
| SHP01 | 49 | Per sample shipping charges for branch shipments | | | VAN |

## ADDITIONAL COMMENTS

Invoice To: Golden Sky Minerals Corp.
1010 – 1130 West Pender Street
Vancouver British Columbia V6E 4A4
Canada

CC: Clayton Jones
Daithi Mac Gerailt

BRITISH COLUMBIA CERTIFIED ASSAYER
MARCUS LAU
Production Manager

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Bureau Veritas assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# CERTIFICATE OF ANALYSIS WHI20000135.1

| | Method | WGHT | FA350 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Wgt | Au | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V |
| | Unit | kg | ppb | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm |
| | MDL | 0.01 | 2 | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 |
| 1878251 | Rock | 0.55 | 36 | 8.1 | 42.5 | 19.1 | 28 | 2.3 | 11.4 | 1.2 | 81 | 2.92 | 74.4 | 1.9 | 4.4 | 4.3 | 108 | 0.2 | 5.2 | 0.2 | 124 |
| 1878252 | Rock | 0.76 | 10 | 3.0 | 95.4 | 5.9 | 104 | <0.1 | 53.9 | 7.2 | 115 | 1.65 | 61.0 | 0.5 | 4.4 | 2.3 | 43 | 0.6 | 3.4 | 0.1 | 16 |
| 1878253 | Rock | 0.82 | 6 | 0.7 | 44.9 | 3.9 | 64 | <0.1 | 27.6 | 2.8 | 169 | 1.16 | 34.8 | 0.2 | 4.1 | 1.6 | 10 | 0.2 | 0.8 | <0.1 | 15 |
| 1878254 | Rock | 0.97 | <2 | 0.5 | 14.9 | 3.5 | 26 | <0.1 | 10.7 | 1.9 | 94 | 0.85 | 3.4 | 0.1 | <0.5 | 1.0 | 47 | <0.1 | 0.1 | <0.1 | 8 |
| 1878255 | Rock | 1.17 | 4 | 0.7 | 7.6 | 6.7 | 22 | 0.2 | 4.2 | 0.4 | 104 | 0.32 | 3.7 | 0.4 | 1.1 | 0.8 | 1384 | 1.8 | 3.8 | <0.1 | 3 |
| 1878256 | Rock | 0.99 | 6 | 0.2 | 101.6 | 0.4 | 25 | <0.1 | 14.5 | 9.8 | 337 | 1.93 | <0.5 | <0.1 | 1.3 | 0.2 | 40 | <0.1 | 0.1 | <0.1 | 55 |
| 1878257 | Rock | 1.16 | 9 | 0.1 | 74.9 | 0.3 | 20 | <0.1 | 15.7 | 9.9 | 205 | 1.61 | 0.5 | <0.1 | 12.3 | 0.1 | 55 | <0.1 | <0.1 | <0.1 | 29 |
| 1878258 | Rock | 0.60 | 3 | <0.1 | 14.3 | 0.3 | 9 | <0.1 | 12.5 | 5.3 | 501 | 0.98 | 0.6 | <0.1 | <0.5 | <0.1 | 85 | <0.1 | <0.1 | <0.1 | 25 |
| 1878259 | Rock | 1.00 | <2 | 0.3 | 28.1 | 6.6 | 28 | <0.1 | 23.5 | 11.4 | 205 | 1.61 | 1.9 | 0.2 | <0.5 | 6.3 | 7 | <0.1 | 0.2 | <0.1 | 26 |
| 1878260 | Rock | 1.12 | <2 | 0.5 | 13.8 | 12.5 | 36 | <0.1 | 15.2 | 4.2 | 4432 | 0.89 | 1.1 | 0.2 | <0.5 | 1.2 | 68 | <0.1 | 0.1 | <0.1 | 4 |
| 1878261 | Rock | 0.84 | 3 | 0.1 | 2.6 | 1.2 | 4 | <0.1 | 1.2 | 0.4 | 40 | 0.35 | 5.9 | <0.1 | 1.0 | 2.7 | 2 | <0.1 | 0.1 | <0.1 | <2 |
| 1878262 | Rock | 0.70 | 15 | 0.8 | 57.6 | 10.7 | 68 | <0.1 | 38.2 | 6.1 | 282 | 1.90 | 27.9 | 0.5 | 6.1 | 3.0 | 48 | <0.1 | 1.3 | 0.1 | 14 |
| 1878263 | Rock | 2.17 | 151 | 0.2 | 7.4 | 10.4 | 18 | 0.1 | 6.5 | 2.2 | 107 | 0.85 | 296.5 | 0.3 | 88.9 | 7.9 | 6 | <0.1 | 0.5 | <0.1 | 4 |
| 1878264 | Rock | 0.96 | 936 | 0.3 | 4.8 | 8.8 | 5 | 0.3 | 2.0 | 0.8 | 113 | 0.73 | 1354.3 | 0.2 | 958.7 | 2.4 | 13 | <0.1 | 7.7 | <0.1 | 2 |
| 1878265 | Rock | 1.71 | 183 | 0.2 | 10.3 | 31.5 | 21 | 0.2 | 6.6 | 2.5 | 188 | 1.13 | 698.0 | 0.2 | 122.6 | 5.3 | 16 | <0.1 | 1.2 | <0.1 | 5 |
| 1878266 | Rock | 1.21 | 9 | 0.2 | 6.9 | 2.6 | 6 | <0.1 | 3.4 | 1.6 | 144 | 0.72 | 15.0 | 0.2 | 4.8 | 3.7 | 6 | <0.1 | 0.3 | <0.1 | 6 |
| 1878267 | Rock | 0.60 | 14 | 0.5 | 10.3 | 6.1 | 17 | 0.8 | 4.1 | 1.3 | 81 | 0.71 | 186.9 | 1.1 | 1.7 | 2.0 | 100 | 0.5 | 1.4 | <0.1 | 49 |
| 1878268 | Rock | 1.40 | 67 | 0.5 | 7.0 | 8.3 | 28 | 0.1 | 8.7 | 1.9 | 94 | 0.78 | 249.2 | 0.4 | 28.5 | 7.1 | 9 | 0.3 | 1.1 | 0.1 | 4 |
| 1878269 | Rock | 1.34 | 12 | 0.5 | 5.0 | 16.0 | 19 | 0.1 | 5.7 | 1.5 | 61 | 0.50 | 52.7 | 0.5 | 11.9 | 7.6 | 8 | <0.1 | 0.6 | 0.2 | 2 |
| 1878301 | Rock | 0.89 | 25 | 7.3 | 37.9 | 16.1 | 35 | 1.0 | 8.3 | 0.6 | 65 | 2.36 | 40.3 | 2.1 | 7.0 | 3.0 | 134 | 0.1 | 4.2 | <0.1 | 131 |
| 1878302 | Rock | 0.98 | 9 | 0.3 | 45.2 | 2.9 | 33 | <0.1 | 14.5 | 1.8 | 45 | 1.25 | 3.5 | <0.1 | 1.4 | 0.6 | 43 | <0.1 | 0.2 | <0.1 | 8 |
| 1878303 | Rock | 1.16 | 30 | 0.4 | 13.7 | 6.4 | 24 | <0.1 | 10.5 | 3.7 | 97 | 0.98 | 14.5 | 0.2 | 10.6 | 2.6 | 5 | <0.1 | 0.3 | <0.1 | 7 |
| 1878304 | Rock | 1.20 | <2 | 0.3 | 4.3 | 0.9 | 21 | <0.1 | 3.8 | 2.2 | 111 | 0.74 | 1.3 | 0.8 | <0.5 | 16.5 | 11 | <0.1 | <0.1 | <0.1 | 4 |
| 1878305 | Rock | 1.21 | 3 | 0.4 | 27.6 | 10.8 | 52 | 0.3 | 14.6 | 4.2 | 68 | 1.36 | 11.0 | 0.4 | 1.1 | 2.5 | 10 | 0.2 | 0.7 | <0.1 | 5 |
| 1878306 | Rock | 0.91 | 2 | 0.2 | 17.1 | 4.3 | 45 | 0.1 | 15.6 | 8.2 | 99 | 0.60 | 5.5 | 0.3 | <0.5 | 1.7 | 8 | 0.1 | 0.2 | <0.1 | 4 |
| 1878307 | Rock | 0.76 | 2 | 0.2 | 4.9 | 11.9 | 7 | <0.1 | 3.1 | 0.8 | 61 | 0.93 | 4.8 | <0.1 | <0.5 | 0.4 | 2 | <0.1 | 0.2 | <0.1 | 3 |
| 1878308 | Rock | 1.09 | 8 | 0.5 | 17.1 | 9.8 | 54 | <0.1 | 15.1 | 3.4 | 130 | 1.41 | 13.5 | 0.4 | 3.2 | 3.0 | 4 | 0.1 | 0.5 | <0.1 | 6 |
| 1878309 | Rock | 1.57 | 91 | 2.1 | 6.5 | 11.4 | 12 | <0.1 | 2.9 | 0.6 | 50 | 1.29 | 90.7 | 0.2 | 34.0 | 4.5 | 20 | <0.1 | 1.2 | <0.1 | 6 |
| 1878310 | Rock | 1.00 | 5 | 0.2 | 13.0 | 4.6 | 29 | <0.1 | 10.1 | 2.9 | 138 | 0.98 | 10.5 | 0.6 | 3.0 | 2.6 | 5 | <0.1 | 0.4 | <0.1 | 6 |
| 1878311 | Rock | 1.61 | 11 | 0.4 | 4.4 | 5.1 | 5 | 0.1 | 1.3 | 0.5 | 48 | 0.90 | 10.1 | 0.1 | 3.6 | 2.0 | 16 | <0.1 | 0.3 | <0.1 | 3 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# CERTIFICATE OF ANALYSIS WHI20000135.1

| | | Method | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Ca | P | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | % | % | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 0.01 | 0.001 | 1 | 1 | 0.01 | 1 | 0.001 | 20 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1878251 | Rock | | 0.27 | 0.585 | 12 | 18 | 0.06 | 1037 | 0.009 | <20 | 0.50 | 0.013 | 0.31 | 0.2 | 0.07 | 2.3 | 0.2 | 0.38 | 2 | 8.4 | <0.2 |
| 1878252 | Rock | | 0.04 | 0.022 | 10 | 9 | 0.08 | 1801 | 0.003 | <20 | 0.41 | 0.003 | 0.10 | <0.1 | <0.01 | 2.0 | <0.1 | <0.05 | 1 | 1.0 | <0.2 |
| 1878253 | Rock | | 0.03 | 0.015 | 6 | 7 | 0.13 | 412 | 0.001 | <20 | 0.34 | 0.002 | 0.08 | <0.1 | <0.01 | 1.5 | <0.1 | <0.05 | 2 | 0.6 | <0.2 |
| 1878254 | Rock | | 0.05 | 0.020 | 3 | 8 | 0.10 | 109 | 0.001 | <20 | 0.24 | 0.036 | 0.04 | <0.1 | <0.01 | 0.8 | <0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878255 | Rock | | 20.72 | 0.081 | 6 | 3 | 0.16 | 193 | <0.001 | <20 | 0.07 | 0.006 | 0.03 | <0.1 | 0.02 | 1.5 | <0.1 | <0.05 | <1 | 0.9 | <0.2 |
| 1878256 | Rock | | 2.79 | 0.024 | 2 | 3 | 0.55 | 8 | 0.196 | <20 | 1.20 | 0.011 | <0.01 | <0.1 | <0.01 | 2.5 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1878257 | Rock | | 0.99 | 0.011 | <1 | 5 | 0.72 | 8 | 0.078 | <20 | 1.14 | 0.009 | <0.01 | <0.1 | <0.01 | 2.2 | <0.1 | <0.05 | 3 | <0.5 | <0.2 |
| 1878258 | Rock | | 13.62 | 0.004 | <1 | 22 | 0.53 | 4 | 0.023 | <20 | 0.54 | 0.002 | <0.01 | <0.1 | 0.02 | 2.6 | <0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878259 | Rock | | 0.30 | 0.034 | 5 | 17 | 0.49 | 35 | 0.011 | <20 | 0.92 | 0.014 | 0.20 | <0.1 | 0.03 | 4.4 | <0.1 | <0.05 | 3 | <0.5 | <0.2 |
| 1878260 | Rock | | 0.11 | 0.031 | 4 | 4 | 0.03 | 218 | 0.005 | <20 | 0.12 | 0.026 | 0.03 | <0.1 | <0.01 | 1.7 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878261 | Rock | | 0.01 | 0.003 | 10 | 2 | 0.02 | 37 | <0.001 | <20 | 0.15 | 0.002 | 0.11 | <0.1 | <0.01 | 0.4 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878262 | Rock | | 0.13 | 0.066 | 15 | 9 | 0.08 | 696 | 0.006 | <20 | 0.45 | 0.010 | 0.16 | <0.1 | <0.01 | 2.2 | <0.1 | <0.05 | 1 | 0.8 | 0.3 |
| 1878263 | Rock | | 0.04 | 0.008 | 19 | 4 | 0.02 | 125 | 0.002 | <20 | 0.27 | 0.005 | 0.17 | <0.1 | <0.01 | 0.9 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878264 | Rock | | 0.03 | 0.005 | 7 | 2 | <0.01 | 255 | <0.001 | <20 | 0.13 | 0.002 | 0.09 | <0.1 | <0.01 | 0.5 | <0.1 | <0.05 | <1 | 0.5 | <0.2 |
| 1878265 | Rock | | 0.04 | 0.008 | 11 | 4 | 0.02 | 235 | 0.002 | <20 | 0.23 | 0.005 | 0.15 | <0.1 | <0.01 | 1.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878266 | Rock | | 0.33 | 0.033 | 7 | 5 | 0.22 | 78 | 0.039 | <20 | 0.10 | 0.030 | 0.02 | 0.1 | <0.01 | 0.6 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878267 | Rock | | 0.23 | 0.190 | 10 | 6 | 0.03 | 441 | 0.005 | <20 | 0.25 | 0.004 | 0.09 | 0.2 | 0.03 | 0.9 | <0.1 | <0.05 | <1 | 1.1 | <0.2 |
| 1878268 | Rock | | 0.03 | 0.009 | 27 | 3 | 0.02 | 274 | 0.002 | <20 | 0.25 | 0.025 | 0.18 | <0.1 | <0.01 | 2.2 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878269 | Rock | | 0.01 | 0.008 | 29 | 2 | 0.01 | 171 | 0.001 | <20 | 0.18 | 0.052 | 0.10 | <0.1 | <0.01 | 1.8 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878301 | Rock | | 0.16 | 0.624 | 11 | 28 | 0.02 | 447 | 0.004 | <20 | 0.35 | 0.006 | 0.22 | 0.1 | 0.04 | 1.3 | 0.2 | 0.20 | 2 | 12.7 | <0.2 |
| 1878302 | Rock | | 0.04 | 0.016 | 2 | 5 | 0.05 | 401 | <0.001 | <20 | 0.19 | 0.026 | 0.05 | <0.1 | <0.01 | 1.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878303 | Rock | | 0.05 | 0.027 | 7 | 3 | 0.05 | 66 | <0.001 | <20 | 0.23 | 0.002 | 0.10 | <0.1 | 0.01 | 0.8 | <0.1 | <0.05 | <1 | 0.5 | <0.2 |
| 1878304 | Rock | | 0.14 | 0.054 | 45 | 2 | 0.02 | 22 | 0.002 | <20 | 0.26 | 0.085 | 0.05 | <0.1 | <0.01 | 1.9 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878305 | Rock | | 0.08 | 0.057 | 8 | 3 | <0.01 | 76 | <0.001 | <20 | 0.19 | 0.003 | 0.11 | <0.1 | 0.04 | 1.2 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878306 | Rock | | 0.20 | 0.043 | 5 | 3 | 0.03 | 84 | <0.001 | <20 | 0.18 | 0.004 | 0.11 | <0.1 | 0.02 | 0.7 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878307 | Rock | | 0.02 | 0.022 | <1 | 3 | <0.01 | 15 | <0.001 | <20 | 0.04 | 0.002 | 0.02 | <0.1 | <0.01 | 0.5 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878308 | Rock | | 0.08 | 0.050 | 11 | 3 | 0.04 | 117 | <0.001 | <20 | 0.23 | 0.001 | 0.10 | <0.1 | 0.01 | 1.3 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878309 | Rock | | <0.01 | 0.017 | 8 | 3 | <0.01 | 48 | <0.001 | <20 | 0.12 | 0.002 | 0.09 | <0.1 | <0.01 | 0.4 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878310 | Rock | | 0.10 | 0.050 | 10 | 4 | 0.03 | 54 | 0.001 | <20 | 0.20 | 0.002 | 0.09 | <0.1 | <0.01 | 1.2 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878311 | Rock | | <0.01 | 0.014 | 9 | 3 | <0.01 | 47 | <0.001 | <20 | 0.13 | 0.002 | 0.09 | <0.1 | 0.01 | 0.4 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# CERTIFICATE OF ANALYSIS WHI20000135.1

| | Method | WGHT | FA350 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Wgt | Au | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V |
| | Unit | kg | ppb | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm |
| | MDL | 0.01 | 2 | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 |
| 1878312 | Rock | 1.08 | 12 | 0.6 | 21.1 | 4.8 | 16 | 0.1 | 3.3 | 0.7 | 42 | 1.07 | 9.9 | 0.6 | 2.6 | 3.4 | 6 | <0.1 | 0.3 | <0.1 | 9 |
| 1878313 | Rock | 1.38 | 4 | 0.2 | 6.9 | 2.1 | 22 | <0.1 | 6.8 | 3.6 | 679 | 1.86 | 11.2 | 0.3 | 2.0 | 4.1 | 43 | <0.1 | 0.5 | <0.1 | 17 |
| 1878314 | Rock | 0.82 | <2 | 0.2 | 7.5 | 3.5 | 19 | <0.1 | 5.8 | 3.2 | 439 | 1.13 | 4.0 | 0.3 | <0.5 | 2.3 | 6 | <0.1 | 0.4 | <0.1 | 6 |
| 1878315 | Rock | 0.84 | 10 | 0.2 | 9.3 | 27.3 | 35 | <0.1 | 3.7 | 1.1 | 112 | 1.30 | 47.3 | 0.2 | 6.8 | 4.8 | 11 | <0.1 | 0.5 | <0.1 | <2 |
| 1878316 | Rock | 1.07 | 9 | 0.3 | 37.1 | 4.0 | 44 | 0.1 | 12.5 | 1.8 | 311 | 1.17 | 7.4 | 0.5 | 3.4 | 1.4 | 25 | <0.1 | 1.6 | <0.1 | 7 |
| 1878317 | Rock | 1.06 | 11 | 0.4 | 41.1 | 5.7 | 36 | <0.1 | 14.1 | 2.5 | 313 | 1.08 | 16.6 | 0.5 | 8.1 | 1.6 | 47 | <0.1 | 0.5 | 0.1 | 11 |
| 1878318 | Rock | 0.54 | 5 | 0.3 | 102.4 | 11.5 | 75 | <0.1 | 31.2 | 19.6 | 1871 | 2.69 | 2.3 | <0.1 | 1.1 | 2.6 | 26 | <0.1 | 0.3 | 0.2 | 42 |
| 1878319 | Rock | 0.59 | 42 | 4.4 | 115.3 | 15.8 | 87 | 0.1 | 38.9 | 10.1 | 527 | 3.85 | 63.6 | 0.7 | 25.2 | 3.9 | 67 | 0.2 | 2.8 | 0.3 | 29 |
| 1878320 | Rock | 1.11 | 2 | 0.1 | 2.5 | 0.7 | 2 | <0.1 | 1.5 | 0.6 | 189 | 0.36 | 0.6 | <0.1 | <0.5 | 0.2 | 11 | <0.1 | 0.4 | <0.1 | <2 |
| 1878321 | Rock | 0.89 | <2 | 0.3 | 36.5 | 3.8 | 6 | <0.1 | 3.0 | 2.7 | 1178 | 0.59 | 1.1 | 0.1 | <0.5 | 0.3 | 19 | <0.1 | 0.1 | <0.1 | <2 |
| 1878322 | Rock | 0.73 | 21 | 0.7 | 17.0 | 9.5 | 72 | 0.7 | 119.3 | 6.0 | 102 | 2.75 | 266.4 | 0.2 | 18.4 | 0.7 | 11 | 0.2 | 26.6 | <0.1 | 11 |
| 1878323 | Rock | 1.50 | 45 | 0.3 | 8.6 | 2.1 | 24 | <0.1 | 7.4 | 1.5 | 145 | 0.85 | 94.8 | 0.1 | 29.4 | 2.5 | 2 | 0.1 | 0.5 | <0.1 | 4 |
| 1878324 | Rock | 0.90 | 107 | 0.2 | 4.5 | 3.7 | 10 | <0.1 | 3.2 | 0.9 | 122 | 0.66 | 320.6 | 0.1 | 72.5 | 2.0 | 3 | <0.1 | 0.7 | <0.1 | <2 |
| 1878325 | Rock | 2.03 | 77 | 0.3 | 7.1 | 5.1 | 16 | <0.1 | 7.4 | 2.8 | 296 | 1.18 | 359.4 | 0.3 | 79.0 | 3.7 | 12 | <0.1 | 1.0 | <0.1 | 8 |
| 1878326 | Rock | 1.17 | 100 | 0.2 | 6.0 | 5.7 | 7 | <0.1 | 1.9 | 0.4 | 39 | 0.75 | 460.3 | 0.2 | 63.3 | 4.4 | 25 | <0.1 | 0.9 | <0.1 | <2 |
| 1878327 | Rock | 1.32 | 176 | 2.8 | 55.2 | 11.3 | 139 | 0.6 | 127.2 | 24.9 | 933 | 4.23 | 926.7 | 0.8 | 111.0 | 5.2 | 35 | 0.9 | 8.6 | 0.1 | 40 |
| 1878328 | Rock | 0.49 | 5 | 0.3 | 11.9 | 5.0 | 17 | <0.1 | 6.0 | 2.2 | 780 | 0.64 | 16.9 | 0.2 | 3.2 | 2.0 | 8 | 0.2 | 0.4 | <0.1 | 6 |
| 1878329 | Rock | 0.68 | 71 | 0.3 | 3.0 | 12.2 | 6 | 0.2 | 2.3 | 1.1 | 112 | 0.50 | 42.3 | 0.2 | 11.3 | 7.0 | 10 | <0.1 | 0.4 | <0.1 | 3 |
| 1878330 | Rock | 0.45 | 20 | 0.7 | 13.7 | 218.3 | 16 | 0.6 | 4.7 | 1.2 | 131 | 0.62 | 71.4 | 0.8 | 13.6 | 6.8 | 22 | <0.1 | 8.9 | 0.1 | 3 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# CERTIFICATE OF ANALYSIS WHI20000135.1

| | Method | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Ca | P | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | % | % | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 0.01 | 0.001 | 1 | 1 | 0.01 | 1 | 0.001 | 20 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1878312 | Rock | 0.03 | 0.023 | 11 | 5 | 0.16 | 46 | <0.001 | <20 | 0.48 | 0.004 | 0.10 | <0.1 | <0.01 | 1.3 | <0.1 | <0.05 | 1 | <0.5 | <0.2 |
| 1878313 | Rock | 3.31 | 0.025 | 11 | 9 | 1.14 | 93 | 0.003 | <20 | 0.62 | 0.011 | 0.03 | <0.1 | <0.01 | 2.2 | <0.1 | <0.05 | 2 | <0.5 | <0.2 |
| 1878314 | Rock | 1.65 | 0.029 | 5 | 4 | 0.11 | 66 | <0.001 | <20 | 0.23 | 0.004 | 0.09 | <0.1 | 0.02 | 0.9 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878315 | Rock | 0.02 | 0.009 | 9 | 3 | 0.02 | 27 | 0.001 | <20 | 0.11 | 0.041 | 0.06 | <0.1 | <0.01 | 0.3 | <0.1 | 0.06 | <1 | <0.5 | <0.2 |
| 1878316 | Rock | 0.01 | 0.010 | 6 | 5 | 0.02 | 2814 | 0.001 | <20 | 0.26 | 0.008 | 0.10 | <0.1 | 0.01 | 1.8 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878317 | Rock | 0.03 | 0.025 | 6 | 6 | 0.05 | 2641 | 0.001 | <20 | 0.30 | 0.005 | 0.12 | <0.1 | <0.01 | 1.4 | <0.1 | 0.09 | 1 | 1.6 | <0.2 |
| 1878318 | Rock | 0.09 | 0.033 | 14 | 15 | 1.17 | 701 | 0.003 | <20 | 1.64 | 0.010 | 0.10 | <0.1 | <0.01 | 7.6 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1878319 | Rock | 0.03 | 0.036 | 16 | 18 | 0.03 | 194 | 0.001 | <20 | 0.43 | 0.005 | 0.08 | <0.1 | 0.01 | 5.9 | 0.1 | <0.05 | 1 | 0.8 | <0.2 |
| 1878320 | Rock | 0.24 | 0.004 | 2 | 2 | 0.14 | 33 | <0.001 | <20 | 0.02 | 0.002 | <0.01 | <0.1 | <0.01 | 0.2 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878321 | Rock | 0.04 | 0.021 | 2 | 5 | 0.02 | 146 | <0.001 | <20 | 0.07 | 0.020 | 0.01 | <0.1 | <0.01 | 0.6 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878322 | Rock | <0.01 | 0.011 | 3 | 85 | 0.01 | 2337 | <0.001 | <20 | 0.19 | 0.003 | 0.05 | <0.1 | 0.11 | 1.0 | 0.2 | 0.07 | <1 | 1.1 | <0.2 |
| 1878323 | Rock | 0.01 | 0.004 | 8 | 3 | 0.01 | 62 | <0.001 | <20 | 0.16 | 0.002 | 0.09 | <0.1 | <0.01 | 0.7 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878324 | Rock | 0.02 | 0.005 | 5 | 3 | <0.01 | 58 | <0.001 | <20 | 0.09 | 0.002 | 0.06 | <0.1 | <0.01 | 0.4 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878325 | Rock | 0.08 | 0.014 | 10 | 5 | 0.05 | 141 | 0.006 | <20 | 0.26 | 0.009 | 0.11 | <0.1 | <0.01 | 1.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878326 | Rock | 0.01 | 0.004 | 9 | 2 | <0.01 | 91 | <0.001 | <20 | 0.15 | 0.002 | 0.13 | <0.1 | <0.01 | 0.6 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878327 | Rock | 0.45 | 0.066 | 20 | 70 | 0.38 | 420 | 0.028 | <20 | 1.19 | 0.023 | 0.21 | <0.1 | 0.04 | 13.1 | 0.2 | <0.05 | 3 | 0.6 | <0.2 |
| 1878328 | Rock | 0.29 | 0.021 | 4 | 5 | 0.03 | 118 | 0.004 | <20 | 0.19 | 0.006 | 0.09 | <0.1 | <0.01 | 0.7 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878329 | Rock | 0.02 | 0.005 | 27 | 3 | 0.02 | 739 | 0.002 | <20 | 0.25 | 0.008 | 0.25 | <0.1 | <0.01 | 0.6 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| 1878330 | Rock | 0.03 | 0.011 | 29 | 3 | 0.02 | 862 | 0.004 | <20 | 0.20 | 0.056 | 0.09 | <0.1 | <0.01 | 1.0 | <0.1 | <0.05 | <1 | 0.7 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.
9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# QUALITY CONTROL REPORT WHI20000135.1

| | Method | WGHT | FA350 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Wgt | Au | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V |
| | Unit | kg | ppb | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm |
| | MDL | 0.01 | 2 | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 |
| Pulp Duplicates | | | | | | | | | | | | | | | | | | | | | |
| 1878301 | Rock | 0.89 | 25 | 7.3 | 37.9 | 16.1 | 35 | 1.0 | 8.3 | 0.6 | 65 | 2.36 | 40.3 | 2.1 | 7.0 | 3.0 | 134 | 0.1 | 4.2 | <0.1 | 131 |
| REP 1878301 | QC | | | 7.3 | 36.3 | 15.9 | 33 | 1.0 | 7.9 | 0.6 | 64 | 2.30 | 40.7 | 2.1 | 5.4 | 2.7 | 130 | 0.1 | 4.2 | <0.1 | 124 |
| REP 1878306 | QC | | 2 | | | | | | | | | | | | | | | | | | |
| 1878324 | Rock | 0.90 | 107 | 0.2 | 4.5 | 3.7 | 10 | <0.1 | 3.2 | 0.9 | 122 | 0.66 | 320.6 | 0.1 | 72.5 | 2.0 | 3 | <0.1 | 0.7 | <0.1 | <2 |
| REP 1878324 | QC | | | 0.2 | 4.5 | 3.7 | 10 | <0.1 | 3.2 | 0.9 | 125 | 0.66 | 314.0 | 0.1 | 83.4 | 2.0 | 3 | <0.1 | 0.7 | <0.1 | <2 |
| Core Reject Duplicates | | | | | | | | | | | | | | | | | | | | | |
| 1878306 | Rock | 0.91 | 2 | 0.2 | 17.1 | 4.3 | 45 | 0.1 | 15.6 | 8.2 | 99 | 0.60 | 5.5 | 0.3 | <0.5 | 1.7 | 8 | 0.1 | 0.2 | <0.1 | 4 |
| DUP 1878306 | QC | | 2 | 0.2 | 17.7 | 4.4 | 46 | 0.1 | 16.4 | 8.4 | 103 | 0.64 | 5.4 | 0.3 | <0.5 | 1.7 | 8 | 0.1 | 0.3 | <0.1 | 4 |
| Reference Materials | | | | | | | | | | | | | | | | | | | | | |
| STD BVGEO01 | Standard | | | 11.2 | 4437.9 | 182.4 | 1682 | 2.6 | 168.9 | 25.7 | 759 | 3.93 | 114.4 | 3.8 | 205.7 | 13.7 | 56 | 6.0 | 2.0 | 23.2 | 81 |
| STD DS11 | Standard | | | 14.5 | 150.4 | 140.8 | 360 | 2.0 | 81.1 | 14.1 | 990 | 3.20 | 45.9 | 2.8 | 55.0 | 8.1 | 68 | 2.8 | 8.1 | 12.2 | 53 |
| STD OREAS262 | Standard | | | 0.6 | 120.6 | 60.3 | 164 | 0.5 | 68.2 | 29.3 | 526 | 3.54 | 39.7 | 1.3 | 57.2 | 10.0 | 40 | 0.8 | 2.3 | 1.1 | 24 |
| STD OREAS262 | Standard | | | 0.7 | 118.0 | 56.0 | 151 | 0.5 | 65.4 | 28.4 | 573 | 3.45 | 35.1 | 1.2 | 55.1 | 9.3 | 36 | 0.6 | 2.0 | 1.0 | 24 |
| STD OXA131 | Standard | | 75 | | | | | | | | | | | | | | | | | | |
| STD OXA131 | Standard | | 74 | | | | | | | | | | | | | | | | | | |
| STD OXG123 | Standard | | 1017 | | | | | | | | | | | | | | | | | | |
| STD OXG141 | Standard | | 946 | | | | | | | | | | | | | | | | | | |
| STD OXG123 Expected | | | 1008 | | | | | | | | | | | | | | | | | | |
| STD DS11 Expected | | | | 13.9 | 149 | 138 | 345 | 1.71 | 77.7 | 14.2 | 1055 | 3.1 | 42.8 | 2.59 | 79 | 7.65 | 67.3 | 2.37 | 7.2 | 12.2 | 50 |
| STD OXA131 Expected | | | 77 | | | | | | | | | | | | | | | | | | |
| STD OXG141 Expected | | | 930 | | | | | | | | | | | | | | | | | | |
| STD BVGEO01 Expected | | | | 10.8 | 4415 | 187 | 1741 | 2.53 | 163 | 25 | 733 | 3.7 | 121 | 3.77 | 219 | 14.4 | 55 | 6.5 | 2.2 | 25.6 | 73 |
| STD OREAS262 Expected | | | | 0.68 | 118 | 56 | 154 | 0.45 | 62 | 26.9 | 530 | 3.284 | 35.8 | 1.22 | 65 | 9.33 | 36 | 0.61 | 3.39 | 1.03 | 22.5 |
| BLK | Blank | | <2 | | | | | | | | | | | | | | | | | | |
| BLK | Blank | | | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | 0.2 | <1 | <0.1 | <0.1 | <0.1 | <2 |
| BLK | Blank | | <2 | | | | | | | | | | | | | | | | | | |
| BLK | Blank | | | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 |
| Prep Wash | | | | | | | | | | | | | | | | | | | | | |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.
9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 12, 2020



# QUALITY CONTROL REPORT WHI20000135.1

| | | Method | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Ca | P | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | % | % | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 0.01 | 0.001 | 1 | 1 | 0.01 | 1 | 0.001 | 20 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| Pulp Duplicates | | | | | | | | | | | | | | | | | | | | | |
| 1878301 | Rock | | 0.16 | 0.624 | 11 | 28 | 0.02 | 447 | 0.004 | <20 | 0.35 | 0.006 | 0.22 | 0.1 | 0.04 | 1.3 | 0.2 | 0.20 | 2 | 12.7 | <0.2 |
| REP 1878301 | QC | | 0.15 | 0.608 | 11 | 27 | 0.02 | 433 | 0.004 | <20 | 0.34 | 0.006 | 0.21 | 0.1 | 0.03 | 1.1 | 0.1 | 0.20 | 2 | 12.2 | <0.2 |
| REP 1878306 | QC | | | | | | | | | | | | | | | | | | | | |
| 1878324 | Rock | | 0.02 | 0.005 | 5 | 3 | <0.01 | 58 | <0.001 | <20 | 0.09 | 0.002 | 0.06 | <0.1 | <0.01 | 0.4 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| REP 1878324 | QC | | 0.02 | 0.005 | 5 | 3 | <0.01 | 58 | <0.001 | <20 | 0.09 | 0.002 | 0.06 | <0.1 | <0.01 | 0.4 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| Core Reject Duplicates | | | | | | | | | | | | | | | | | | | | | |
| 1878306 | Rock | | 0.20 | 0.043 | 5 | 3 | 0.03 | 84 | <0.001 | <20 | 0.18 | 0.004 | 0.11 | <0.1 | 0.02 | 0.7 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| DUP 1878306 | QC | | 0.21 | 0.045 | 5 | 3 | 0.03 | 83 | <0.001 | <20 | 0.18 | 0.004 | 0.12 | <0.1 | 0.02 | 0.8 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| Reference Materials | | | | | | | | | | | | | | | | | | | | | |
| STD BVGEO01 | Standard | | 1.37 | 0.072 | 26 | 186 | 1.38 | 332 | 0.253 | <20 | 2.48 | 0.192 | 0.92 | 3.3 | 0.09 | 6.6 | 0.6 | 0.80 | 7 | 4.7 | 0.9 |
| STD DS11 | Standard | | 1.08 | 0.076 | 19 | 61 | 0.88 | 443 | 0.095 | <20 | 1.16 | 0.073 | 0.41 | 3.0 | 0.28 | 3.4 | 4.9 | 0.31 | 5 | 2.6 | 4.7 |
| STD OREAS262 | Standard | | 3.18 | 0.042 | 18 | 44 | 1.25 | 276 | 0.003 | <20 | 1.28 | 0.069 | 0.32 | 0.1 | 0.18 | 3.6 | 0.5 | 0.26 | 4 | 0.8 | 0.2 |
| STD OREAS262 | Standard | | 3.07 | 0.039 | 17 | 45 | 1.23 | 250 | 0.003 | <20 | 1.33 | 0.068 | 0.32 | <0.1 | 0.16 | 3.4 | 0.5 | 0.32 | 4 | <0.5 | 0.2 |
| STD OXA131 | Standard | | | | | | | | | | | | | | | | | | | | |
| STD OXA131 | Standard | | | | | | | | | | | | | | | | | | | | |
| STD OXG123 | Standard | | | | | | | | | | | | | | | | | | | | |
| STD OXG141 | Standard | | | | | | | | | | | | | | | | | | | | |
| STD OXG123 Expected | | | | | | | | | | | | | | | | | | | | | |
| STD DS11 Expected | | | 1.063 | 0.0701 | 18.6 | 61.5 | 0.85 | 417 | 0.0976 | | 1.129 | 0.0694 | 0.4 | 2.9 | 0.26 | 3.1 | 4.9 | 0.2835 | 4.7 | 2.2 | 4.56 |
| STD OXA131 Expected | | | | | | | | | | | | | | | | | | | | | |
| STD OXG141 Expected | | | | | | | | | | | | | | | | | | | | | |
| STD BVGEO01 Expected | | | 1.3219 | 0.0727 | 25.9 | 171 | 1.2963 | 340 | 0.233 | | 2.347 | 0.1924 | 0.89 | 3.5 | 0.1 | 5.97 | 0.62 | 0.6655 | 7.37 | 4.84 | 1.02 |
| STD OREAS262 Expected | | | 2.98 | 0.04 | 15.9 | 41.7 | 1.17 | 248 | 0.003 | | 1.3 | 0.071 | 0.312 | 0.13 | 0.17 | 3.24 | 0.47 | 0.269 | 3.9 | 0.4 | 0.23 |
| BLK | Blank | | | | | | | | | | | | | | | | | | | | |
| BLK | Blank | | <0.01 | <0.001 | <1 | <1 | <0.01 | <1 | <0.001 | <20 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | | | | | | | | | | | | | | | | | | | | |
| BLK | Blank | | <0.01 | <0.001 | <1 | <1 | <0.01 | <1 | <0.001 | <20 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| Prep Wash | | | | | | | | | | | | | | | | | | | | | |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada

PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE

Report Date: August 12, 2020



# QUALITY CONTROL REPORT WHI20000135.1

| | | WGHT | FA350 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 | AQ200 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Wgt | Au | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V |
| | | kg | ppb | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm |
| | | 0.01 | 2 | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 |
| ROCK-WHI | Prep Blank | | <2 | 0.9 | 4.1 | 1.1 | 32 | <0.1 | 1.2 | 3.8 | 476 | 1.75 | 0.9 | 0.4 | <0.5 | 2.3 | 21 | <0.1 | <0.1 | <0.1 | 24 |
| ROCK-WHI | Prep Blank | | <2 | 0.8 | 3.6 | 1.1 | 30 | <0.1 | 0.8 | 3.5 | 458 | 1.74 | 1.0 | 0.4 | <0.5 | 2.3 | 24 | <0.1 | <0.1 | <0.1 | 24 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada

PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE

Report Date: August 12, 2020



# QUALITY CONTROL REPORT WHI20000135.1

| | | AQ200 Ca % 0.01 | AQ200 P % 0.001 | AQ200 La ppm 1 | AQ200 Cr ppm 1 | AQ200 Mg % 0.01 | AQ200 Ba ppm 1 | AQ200 Ti % 0.001 | AQ200 B ppm 20 | AQ200 Al % 0.01 | AQ200 Na % 0.001 | AQ200 K % 0.01 | AQ200 W ppm 0.1 | AQ200 Hg ppm 0.01 | AQ200 Sc ppm 0.1 | AQ200 Tl ppm 0.1 | AQ200 S % 0.05 | AQ200 Ga ppm 1 | AQ200 Se ppm 0.5 | AQ200 Te ppm 0.2 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ROCK-WHI | Prep Blank | 0.62 | 0.040 | 6 | 3 | 0.48 | 49 | 0.074 | <20 | 0.80 | 0.054 | 0.08 | <0.1 | <0.01 | 2.7 | <0.1 | <0.05 | 3 | <0.5 | <0.2 |
| ROCK-WHI | Prep Blank | 0.65 | 0.041 | 6 | 2 | 0.44 | 55 | 0.072 | <20 | 0.81 | 0.061 | 0.08 | <0.1 | <0.01 | 2.7 | <0.1 | <0.05 | 3 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Appendix VII: Soil Sample Assay Certificates

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.
9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

| | |
|---|---|
| Submitted By: | Dan Ferraro |
| Receiving Lab: | Canada-Whitehorse |
| Received: | July 17, 2020 |
| Analysis Start: | July 28, 2020 |
| Report Date: | August 04, 2020 |
| Page: | 1 of 11 |

# CERTIFICATE OF ANALYSIS WHI20000132.1

## CLIENT JOB INFORMATION

| | |
|---|---|
| Project: | BE |
| Shipment ID: | BE_2020_SOIL_1 |
| P.O. Number | |
| Number of Samples: | 280 |

## SAMPLE DISPOSAL

| | |
|---|---|
| DISP-PLP | Dispose of Pulp After 90 days |
| DISP-RJT-SOIL | Immediate Disposal of Soil Reject |

Bureau Veritas does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

## SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

| Procedure Code | Number of Samples | Code Description | Test Wgt (g) | Report Status | Lab |
|---|---|---|---|---|---|
| DY060 | 280 | Dry at 60C | | | WHI |
| SS80 | 280 | Dry at 60C sieve 100g to -80 mesh | | | WHI |
| AQ201 | 279 | 1:1:1 Aqua Regia digestion ICP-MS analysis | 15 | Completed | VAN |
| DISPL | 280 | Disposal of pulps | | | VAN |
| SHP01 | 280 | Per sample shipping charges for branch shipments | | | VAN |

## ADDITIONAL COMMENTS

Invoice To: Druid Exploration
Box 1485
Dawson City Yukon Y0B 1G0
Canada

CC: Clayton Jones
Daithi Mac Gerailt

BRITISH COLUMBIA CERTIFIED ASSAYER
MARCUS LAU
Production Manager

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Bureau Veritas assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1320801 | Soil | | 1.0 | 37.7 | 13.2 | 69 | 0.2 | 36.1 | 15.8 | 561 | 3.70 | 12.5 | 1.1 | 6.0 | 4.9 | 39 | 0.2 | 0.7 | 0.2 | 92 | 0.43 | 0.030 |
| 1320802 | Soil | | 1.3 | 51.2 | 16.1 | 71 | 0.1 | 43.7 | 15.3 | 455 | 3.72 | 18.1 | 1.0 | 5.2 | 5.0 | 36 | 0.3 | 0.6 | 0.2 | 90 | 0.45 | 0.030 |
| 1320803 | Soil | | 0.9 | 38.4 | 13.7 | 66 | <0.1 | 33.8 | 11.7 | 375 | 3.23 | 13.7 | 1.0 | 9.1 | 4.9 | 35 | 0.2 | 0.5 | 0.2 | 81 | 0.42 | 0.022 |
| 1320804 | Soil | | 1.1 | 47.6 | 22.0 | 92 | 0.2 | 38.4 | 12.4 | 578 | 3.59 | 18.4 | 1.0 | 8.8 | 5.8 | 43 | 0.3 | 0.8 | 0.3 | 79 | 0.59 | 0.039 |
| 1320805 | Soil | | 1.0 | 36.6 | 16.1 | 78 | <0.1 | 33.3 | 10.7 | 423 | 3.49 | 14.2 | 0.8 | 5.7 | 6.0 | 37 | 0.2 | 0.6 | 0.2 | 81 | 0.47 | 0.029 |
| 1320806 | Soil | | 1.3 | 43.1 | 18.1 | 76 | 0.1 | 34.5 | 13.0 | 574 | 3.74 | 25.2 | 0.9 | 4.3 | 5.9 | 46 | <0.1 | 1.3 | 0.2 | 77 | 0.59 | 0.035 |
| 1320807 | Soil | | 1.2 | 28.0 | 16.9 | 77 | 0.1 | 37.5 | 14.9 | 421 | 3.70 | 11.6 | 0.6 | 5.0 | 9.0 | 24 | 0.2 | 1.3 | 0.2 | 73 | 0.27 | 0.024 |
| 1320808 | Soil | | 0.9 | 66.4 | 28.3 | 88 | 0.2 | 435.0 | 66.4 | 2231 | 6.43 | 32.4 | 0.8 | 2.9 | 6.5 | 77 | 0.1 | 3.7 | 0.1 | 126 | 0.77 | 0.124 |
| 1320809 | Soil | | 0.7 | 40.3 | 22.1 | 78 | 0.2 | 39.4 | 14.4 | 635 | 3.62 | 25.8 | 0.7 | 5.5 | 9.2 | 34 | 0.1 | 3.0 | 0.2 | 73 | 0.40 | 0.022 |
| 1320810 | Soil | | 0.6 | 25.9 | 16.2 | 52 | 0.1 | 26.1 | 13.1 | 432 | 2.64 | 10.4 | 0.5 | 2.8 | 6.2 | 33 | <0.1 | 0.9 | <0.1 | 69 | 0.45 | 0.028 |
| 1320811 | Soil | | 1.2 | 51.7 | 17.9 | 75 | 0.1 | 42.7 | 15.2 | 666 | 3.71 | 13.7 | 0.9 | 4.1 | 7.8 | 42 | 0.2 | 1.2 | 0.2 | 79 | 0.55 | 0.043 |
| 1320812 | Soil | | 1.5 | 33.8 | 17.2 | 76 | <0.1 | 48.9 | 19.6 | 869 | 3.38 | 12.7 | 0.8 | 2.1 | 7.1 | 30 | 0.4 | 1.1 | 0.2 | 73 | 0.38 | 0.026 |
| 1320813 | Soil | | 1.2 | 31.6 | 13.0 | 59 | <0.1 | 37.0 | 12.7 | 306 | 3.50 | 9.5 | 0.6 | 1.7 | 6.1 | 30 | <0.1 | 0.9 | 0.2 | 73 | 0.35 | 0.026 |
| 1320814 | Soil | | 1.2 | 41.2 | 17.0 | 61 | <0.1 | 37.4 | 14.4 | 533 | 3.51 | 10.3 | 1.2 | 5.0 | 5.9 | 42 | 0.1 | 0.8 | 0.1 | 92 | 0.49 | 0.028 |
| 1320815 | Soil | | 1.0 | 37.7 | 15.0 | 57 | <0.1 | 34.3 | 12.1 | 425 | 3.35 | 9.3 | 1.2 | 1.1 | 5.6 | 39 | <0.1 | 0.7 | 0.1 | 79 | 0.45 | 0.028 |
| 1320816 | Soil | | 1.2 | 33.5 | 14.6 | 51 | 0.1 | 32.0 | 13.2 | 431 | 3.23 | 8.1 | 1.4 | 5.0 | 3.8 | 44 | <0.1 | 0.5 | 0.1 | 87 | 0.55 | 0.038 |
| 1320817 | Soil | | 1.1 | 30.1 | 13.6 | 51 | <0.1 | 31.3 | 11.9 | 383 | 3.29 | 9.8 | 0.6 | 3.8 | 4.4 | 38 | <0.1 | 0.7 | 0.1 | 84 | 0.45 | 0.035 |
| 1320818 | Soil | | 0.8 | 34.3 | 10.6 | 60 | <0.1 | 35.4 | 15.4 | 502 | 3.80 | 9.3 | 0.8 | 1.2 | 4.4 | 43 | <0.1 | 0.6 | 0.1 | 96 | 0.50 | 0.033 |
| 1320819 | Soil | | 0.6 | 42.6 | 11.8 | 58 | <0.1 | 34.3 | 14.4 | 515 | 3.60 | 10.8 | 0.9 | 6.3 | 5.2 | 42 | <0.1 | 0.5 | 0.1 | 90 | 0.51 | 0.028 |
| 1320820 | Soil | | 0.7 | 28.0 | 14.6 | 42 | <0.1 | 21.7 | 9.4 | 331 | 2.48 | 9.4 | 0.9 | 2.8 | 7.8 | 30 | <0.1 | 0.4 | 0.1 | 55 | 0.41 | 0.027 |
| 1320822 | Soil | | 0.7 | 23.1 | 19.5 | 52 | <0.1 | 23.1 | 11.3 | 371 | 2.82 | 9.7 | 0.6 | 4.2 | 6.6 | 30 | 0.1 | 0.6 | 0.2 | 66 | 0.35 | 0.021 |
| 1320823 | Soil | | 0.7 | 35.7 | 16.4 | 57 | <0.1 | 32.6 | 13.3 | 478 | 3.46 | 12.2 | 0.7 | 2.1 | 6.1 | 40 | <0.1 | 0.7 | 0.2 | 87 | 0.46 | 0.020 |
| 1320825 | Soil | | 0.9 | 30.7 | 27.0 | 77 | <0.1 | 30.7 | 11.1 | 292 | 3.79 | 14.3 | 0.6 | 2.8 | 22.1 | 15 | <0.1 | 0.7 | 0.4 | 38 | 0.19 | 0.023 |
| 1320826 | Soil | | 0.9 | 28.4 | 27.5 | 63 | <0.1 | 35.4 | 13.1 | 648 | 3.38 | 10.8 | 0.7 | 2.0 | 15.4 | 18 | <0.1 | 0.6 | 0.3 | 44 | 0.23 | 0.027 |
| 1320827 | Soil | | 1.0 | 30.7 | 12.5 | 61 | <0.1 | 34.2 | 14.3 | 332 | 3.63 | 11.4 | 0.7 | 2.4 | 5.0 | 33 | <0.1 | 0.5 | 0.1 | 89 | 0.41 | 0.024 |
| 1320828 | Soil | | 0.7 | 41.1 | 32.4 | 61 | 0.1 | 34.3 | 12.7 | 548 | 3.22 | 7.3 | 0.7 | 5.4 | 12.7 | 32 | <0.1 | 0.5 | 0.2 | 51 | 0.46 | 0.031 |
| 1320829 | Soil | | 1.0 | 30.3 | 24.2 | 61 | <0.1 | 30.1 | 10.6 | 280 | 3.06 | 9.3 | 0.6 | 4.7 | 10.6 | 22 | <0.1 | 1.1 | 0.2 | 43 | 0.32 | 0.024 |
| 1320830 | Soil | | 0.8 | 37.6 | 21.7 | 66 | 0.1 | 38.5 | 13.4 | 453 | 3.76 | 13.4 | 0.8 | 2.0 | 11.9 | 18 | <0.1 | 0.7 | 0.2 | 60 | 0.23 | 0.021 |
| 1320831 | Soil | | 0.9 | 32.4 | 22.0 | 65 | <0.1 | 36.0 | 14.8 | 823 | 3.45 | 8.7 | 0.6 | 1.5 | 11.4 | 26 | <0.1 | 0.8 | 0.2 | 50 | 0.50 | 0.027 |
| 1320832 | Soil | | 1.2 | 24.4 | 23.6 | 68 | <0.1 | 30.3 | 13.0 | 484 | 3.02 | 8.2 | 0.5 | 1.1 | 7.6 | 22 | <0.1 | 0.6 | 0.2 | 62 | 0.35 | 0.032 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1320801 | Soil | | 19 | 57 | 0.84 | 211 | 0.134 | 4 | 2.95 | 0.022 | 0.06 | <0.1 | 0.06 | 10.4 | 0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1320802 | Soil | | 15 | 64 | 0.96 | 184 | 0.128 | 4 | 2.88 | 0.023 | 0.06 | <0.1 | 0.05 | 10.9 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320803 | Soil | | 15 | 51 | 0.79 | 172 | 0.123 | 4 | 2.39 | 0.022 | 0.05 | 0.1 | 0.04 | 8.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320804 | Soil | | 19 | 49 | 0.85 | 230 | 0.111 | 3 | 2.40 | 0.025 | 0.07 | 0.1 | 0.05 | 10.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320805 | Soil | | 17 | 51 | 0.86 | 203 | 0.119 | 4 | 2.54 | 0.025 | 0.06 | <0.1 | 0.03 | 9.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320806 | Soil | | 17 | 46 | 0.78 | 215 | 0.106 | 4 | 2.13 | 0.034 | 0.07 | <0.1 | 0.06 | 9.1 | 0.1 | <0.05 | 6 | 0.9 | <0.2 |
| 1320807 | Soil | | 23 | 41 | 0.68 | 162 | 0.078 | 3 | 2.79 | 0.014 | 0.08 | <0.1 | 0.03 | 5.0 | 0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320808 | Soil | | 16 | 675 | 4.04 | 177 | 0.050 | <1 | 3.79 | 0.017 | 0.06 | <0.1 | 0.02 | 19.4 | 0.1 | <0.05 | 9 | <0.5 | <0.2 |
| 1320809 | Soil | | 24 | 54 | 0.69 | 185 | 0.093 | 2 | 2.24 | 0.024 | 0.07 | <0.1 | 0.03 | 9.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320810 | Soil | | 19 | 42 | 0.62 | 134 | 0.121 | 2 | 1.84 | 0.024 | 0.05 | 0.1 | 0.01 | 5.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320811 | Soil | | 24 | 53 | 0.80 | 192 | 0.094 | 2 | 2.21 | 0.031 | 0.06 | <0.1 | 0.05 | 8.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320812 | Soil | | 15 | 46 | 0.67 | 250 | 0.087 | 2 | 2.73 | 0.017 | 0.06 | <0.1 | 0.02 | 4.5 | 0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320813 | Soil | | 18 | 45 | 0.75 | 186 | 0.110 | 3 | 2.94 | 0.021 | 0.06 | <0.1 | 0.02 | 4.9 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320814 | Soil | | 24 | 55 | 0.78 | 191 | 0.138 | 2 | 2.62 | 0.030 | 0.05 | <0.1 | 0.05 | 11.1 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320815 | Soil | | 20 | 49 | 0.70 | 182 | 0.122 | 3 | 2.38 | 0.027 | 0.06 | <0.1 | 0.05 | 9.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320816 | Soil | | 15 | 51 | 0.68 | 211 | 0.131 | 3 | 2.34 | 0.029 | 0.05 | 0.1 | 0.03 | 7.5 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320817 | Soil | | 15 | 46 | 0.63 | 170 | 0.132 | 2 | 2.30 | 0.024 | 0.06 | <0.1 | 0.02 | 7.7 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320818 | Soil | | 16 | 57 | 0.84 | 204 | 0.137 | 2 | 2.67 | 0.026 | 0.05 | <0.1 | 0.03 | 10.7 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320819 | Soil | | 21 | 51 | 0.73 | 180 | 0.130 | 3 | 2.30 | 0.034 | 0.06 | <0.1 | 0.04 | 9.9 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320820 | Soil | | 26 | 32 | 0.48 | 205 | 0.076 | 1 | 1.61 | 0.020 | 0.09 | <0.1 | 0.02 | 7.8 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1320822 | Soil | | 20 | 37 | 0.54 | 139 | 0.088 | 2 | 2.03 | 0.017 | 0.07 | <0.1 | 0.03 | 5.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320823 | Soil | | 17 | 50 | 0.69 | 184 | 0.134 | 3 | 2.37 | 0.026 | 0.08 | 0.1 | 0.04 | 9.9 | 0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320825 | Soil | | 67 | 27 | 0.64 | 88 | 0.025 | <1 | 2.23 | 0.009 | 0.08 | <0.1 | 0.01 | 3.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320826 | Soil | | 48 | 33 | 0.67 | 119 | 0.042 | 1 | 2.16 | 0.009 | 0.06 | <0.1 | 0.01 | 4.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320827 | Soil | | 14 | 53 | 0.73 | 150 | 0.130 | <1 | 2.72 | 0.026 | 0.07 | <0.1 | 0.01 | 6.0 | <0.1 | 0.06 | 7 | 0.6 | <0.2 |
| 1320828 | Soil | | 30 | 36 | 0.62 | 87 | 0.080 | 1 | 1.77 | 0.028 | 0.09 | 0.1 | 0.06 | 6.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320829 | Soil | | 35 | 31 | 0.51 | 122 | 0.036 | 1 | 1.82 | 0.013 | 0.08 | <0.1 | 0.02 | 3.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320830 | Soil | | 33 | 43 | 0.70 | 123 | 0.053 | 1 | 2.48 | 0.012 | 0.08 | <0.1 | 0.01 | 7.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320831 | Soil | | 23 | 36 | 0.62 | 145 | 0.038 | 2 | 2.21 | 0.014 | 0.12 | <0.1 | 0.02 | 6.3 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1320832 | Soil | | 25 | 38 | 0.60 | 149 | 0.059 | 2 | 1.98 | 0.016 | 0.10 | <0.1 | 0.03 | 4.5 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1320833 | Soil | | 1.4 | 20.2 | 9.7 | 43 | <0.1 | 26.0 | 12.8 | 469 | 2.85 | 6.0 | 0.5 | <0.5 | 3.2 | 32 | <0.1 | 0.4 | <0.1 | 74 | 0.44 | 0.023 |
| 1320834 | Soil | | 1.4 | 17.6 | 19.1 | 48 | <0.1 | 23.8 | 12.5 | 401 | 2.63 | 8.6 | 0.5 | 4.3 | 5.2 | 28 | <0.1 | 0.6 | 0.1 | 66 | 0.35 | 0.017 |
| 1320835 | Soil | | 1.3 | 29.4 | 19.7 | 50 | <0.1 | 32.6 | 13.7 | 467 | 3.33 | 8.5 | 0.6 | 4.6 | 5.6 | 36 | 0.2 | 0.6 | 0.1 | 82 | 0.54 | 0.025 |
| 1320836 | Soil | | 0.9 | 33.3 | 26.1 | 58 | 0.2 | 34.4 | 13.6 | 546 | 3.44 | 9.6 | 0.5 | 7.4 | 6.4 | 36 | <0.1 | 0.7 | 0.1 | 80 | 0.59 | 0.034 |
| 1320837 | Soil | | 0.9 | 31.7 | 17.4 | 62 | 0.1 | 33.3 | 13.8 | 514 | 3.22 | 7.8 | 0.7 | 0.9 | 6.6 | 38 | <0.1 | 0.6 | 0.1 | 70 | 0.62 | 0.040 |
| 1320838 | Soil | | 0.9 | 45.0 | 8.7 | 58 | <0.1 | 43.1 | 14.3 | 516 | 3.60 | 10.6 | 0.7 | 0.9 | 3.6 | 46 | 0.1 | 0.5 | <0.1 | 97 | 1.13 | 0.048 |
| 1320839 | Soil | | 0.8 | 42.5 | 6.8 | 52 | <0.1 | 34.6 | 13.6 | 487 | 3.47 | 8.1 | 0.7 | 3.2 | 2.7 | 38 | <0.1 | 0.6 | <0.1 | 95 | 0.74 | 0.055 |
| 1320840 | Soil | | 1.2 | 19.6 | 8.5 | 40 | 0.1 | 15.2 | 6.5 | 241 | 2.06 | 6.0 | 0.3 | 0.5 | 1.4 | 24 | 0.1 | 0.5 | 0.1 | 56 | 0.39 | 0.054 |
| 1320841 | Soil | | 1.0 | 42.2 | 6.8 | 66 | <0.1 | 34.7 | 10.3 | 545 | 2.90 | 8.9 | 0.4 | 4.5 | 2.5 | 69 | 0.1 | 0.6 | 0.1 | 77 | 1.97 | 0.075 |
| 1320842 | Soil | | 1.1 | 51.4 | 9.6 | 71 | 0.2 | 41.0 | 12.2 | 702 | 2.77 | 9.4 | 0.4 | 6.6 | 2.9 | 64 | 0.5 | 0.8 | 0.1 | 66 | 1.42 | 0.064 |
| 1320843 | Soil | | 0.6 | 40.6 | 5.4 | 51 | <0.1 | 26.8 | 11.6 | 442 | 2.74 | 6.9 | 0.5 | 12.6 | 2.7 | 65 | 0.1 | 0.3 | <0.1 | 78 | 1.69 | 0.089 |
| 1320844 | Soil | | 0.8 | 40.5 | 10.4 | 61 | <0.1 | 34.0 | 14.8 | 851 | 3.19 | 7.2 | 0.5 | 2.3 | 3.3 | 44 | 0.2 | 0.6 | 0.1 | 71 | 0.69 | 0.043 |
| 1320845 | Soil | | 1.8 | 25.6 | 7.1 | 44 | 0.1 | 18.0 | 11.9 | 950 | 2.05 | 5.4 | 0.4 | 0.7 | 1.5 | 31 | 0.4 | 0.6 | 0.1 | 50 | 0.42 | 0.039 |
| 1320846 | Soil | | 1.2 | 65.5 | 11.5 | 64 | 0.2 | 36.5 | 15.5 | 1022 | 3.27 | 11.8 | 1.2 | 9.8 | 2.7 | 62 | <0.1 | 0.6 | 0.1 | 79 | 0.89 | 0.063 |
| 1320847 | Soil | | 1.2 | 31.6 | 7.3 | 53 | 0.2 | 29.5 | 12.5 | 412 | 3.13 | 8.6 | 0.6 | 1.7 | 2.4 | 35 | 0.2 | 0.6 | 0.1 | 80 | 0.56 | 0.035 |
| 1320848 | Soil | | 0.6 | 43.9 | 7.2 | 55 | <0.1 | 34.7 | 13.7 | 482 | 3.27 | 7.9 | 0.5 | 2.3 | 2.9 | 54 | 0.1 | 0.6 | 0.1 | 83 | 0.92 | 0.058 |
| 1320849 | Soil | | 0.9 | 49.2 | 7.4 | 55 | 0.1 | 43.5 | 13.9 | 418 | 3.49 | 7.5 | 0.5 | 46.9 | 3.7 | 49 | <0.1 | 0.5 | 0.1 | 90 | 0.93 | 0.069 |
| 1320850 | Soil | | 0.8 | 33.6 | 8.9 | 60 | <0.1 | 36.9 | 13.9 | 540 | 3.32 | 7.4 | 0.4 | 3.1 | 2.6 | 61 | <0.1 | 0.4 | <0.1 | 86 | 2.00 | 0.083 |
| 1320851 | Soil | | 0.8 | 43.8 | 7.4 | 53 | <0.1 | 37.0 | 13.1 | 524 | 3.21 | 7.3 | 0.5 | 3.8 | 2.8 | 50 | <0.1 | 0.4 | <0.1 | 86 | 1.19 | 0.067 |
| 1320852 | Soil | | 0.4 | 52.4 | 6.6 | 48 | <0.1 | 38.5 | 14.6 | 462 | 3.09 | 6.9 | 0.4 | 4.6 | 2.3 | 110 | 0.1 | 0.4 | <0.1 | 85 | 4.71 | 0.051 |
| 1320853 | Soil | | 0.5 | 50.8 | 8.3 | 61 | <0.1 | 53.2 | 17.0 | 558 | 3.82 | 7.0 | 0.5 | 5.5 | 3.3 | 42 | <0.1 | 0.3 | 0.1 | 101 | 0.80 | 0.056 |
| 1320854 | Soil | | 0.6 | 49.8 | 6.8 | 50 | 0.1 | 35.7 | 12.5 | 447 | 3.02 | 6.7 | 0.4 | 5.4 | 2.6 | 112 | 0.1 | 0.4 | <0.1 | 74 | 6.18 | 0.061 |
| 1320855 | Soil | | 0.6 | 36.1 | 4.2 | 46 | <0.1 | 30.2 | 12.5 | 456 | 2.62 | 4.8 | 0.3 | 4.8 | 1.8 | 66 | 0.1 | 0.3 | <0.1 | 68 | 2.71 | 0.083 |
| 1320856 | Soil | | 0.5 | 40.3 | 5.3 | 49 | <0.1 | 28.5 | 12.1 | 441 | 2.69 | 8.0 | 0.4 | 2.9 | 2.2 | 112 | 0.1 | 0.5 | <0.1 | 74 | 4.64 | 0.046 |
| 1320857 | Soil | | 0.8 | 39.8 | 6.5 | 60 | <0.1 | 38.2 | 14.2 | 507 | 3.22 | 8.9 | 0.4 | 8.5 | 3.0 | 62 | 0.1 | 0.4 | <0.1 | 86 | 1.67 | 0.062 |
| 1320858 | Soil | | 0.5 | 31.8 | 5.1 | 49 | <0.1 | 31.4 | 12.4 | 463 | 2.82 | 5.5 | 0.4 | 0.9 | 2.2 | 53 | 0.1 | 0.3 | <0.1 | 77 | 1.55 | 0.078 |
| 1320859 | Soil | | 1.1 | 53.0 | 7.2 | 62 | 0.1 | 34.7 | 15.0 | 553 | 3.41 | 7.7 | 0.4 | 4.9 | 2.3 | 60 | 0.1 | 0.7 | <0.1 | 85 | 1.34 | 0.066 |
| 1320860 | Soil | | 0.9 | 33.9 | 5.9 | 42 | <0.1 | 905.4 | 54.3 | 1267 | 3.70 | 10.1 | 0.2 | 3.0 | 1.3 | 113 | 0.3 | 2.6 | <0.1 | 68 | 8.29 | 0.030 |
| 1320861 | Soil | | 2.1 | 32.9 | 12.1 | 100 | 0.2 | 80.0 | 16.2 | 533 | 3.60 | 12.0 | 0.4 | 2.7 | 2.0 | 27 | 1.0 | 1.4 | 0.1 | 86 | 0.57 | 0.030 |
| 1320862 | Soil | | 1.5 | 61.8 | 12.7 | 74 | 0.1 | 693.6 | 48.8 | 1226 | 6.04 | 15.0 | 0.4 | 3.8 | 3.4 | 16 | 0.2 | 4.5 | 0.1 | 67 | 0.31 | 0.043 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1320833 | Soil | | 11 | 41 | 0.54 | 131 | 0.097 | 2 | 2.06 | 0.027 | 0.08 | <0.1 | 0.01 | 5.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320834 | Soil | | 15 | 35 | 0.48 | 114 | 0.092 | 2 | 1.60 | 0.022 | 0.10 | <0.1 | <0.01 | 4.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320835 | Soil | | 16 | 51 | 0.67 | 133 | 0.121 | 2 | 2.08 | 0.038 | 0.06 | 0.1 | 0.02 | 7.8 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320836 | Soil | | 18 | 50 | 0.69 | 138 | 0.130 | 1 | 2.12 | 0.040 | 0.07 | <0.1 | 0.03 | 8.4 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320837 | Soil | | 18 | 45 | 0.68 | 138 | 0.114 | 3 | 1.92 | 0.044 | 0.08 | <0.1 | 0.04 | 6.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320838 | Soil | | 21 | 60 | 1.02 | 145 | 0.137 | 3 | 2.17 | 0.052 | 0.07 | <0.1 | 0.03 | 11.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320839 | Soil | | 19 | 48 | 0.88 | 118 | 0.119 | 4 | 1.92 | 0.046 | 0.06 | <0.1 | <0.01 | 11.0 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320840 | Soil | | 6 | 22 | 0.33 | 120 | 0.076 | 3 | 0.98 | 0.023 | 0.06 | <0.1 | 0.03 | 2.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320841 | Soil | | 12 | 35 | 0.81 | 316 | 0.111 | 4 | 1.45 | 0.063 | 0.07 | <0.1 | 0.04 | 5.2 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1320842 | Soil | | 12 | 34 | 0.79 | 455 | 0.093 | 4 | 1.47 | 0.053 | 0.08 | <0.1 | 0.01 | 5.0 | 0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320843 | Soil | | 11 | 36 | 0.81 | 130 | 0.111 | 4 | 1.39 | 0.057 | 0.08 | 0.1 | 0.02 | 5.1 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1320844 | Soil | | 12 | 38 | 0.63 | 439 | 0.097 | 4 | 1.91 | 0.040 | 0.10 | <0.1 | 0.02 | 7.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320845 | Soil | | 8 | 23 | 0.37 | 302 | 0.066 | 2 | 1.18 | 0.034 | 0.07 | <0.1 | <0.01 | 2.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320846 | Soil | | 16 | 40 | 0.74 | 389 | 0.093 | 3 | 1.96 | 0.045 | 0.06 | <0.1 | 0.05 | 7.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320847 | Soil | | 10 | 39 | 0.62 | 259 | 0.095 | 2 | 2.15 | 0.038 | 0.05 | <0.1 | 0.02 | 5.0 | 0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320848 | Soil | | 15 | 42 | 0.81 | 206 | 0.109 | 3 | 1.88 | 0.055 | 0.06 | <0.1 | 0.03 | 7.1 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320849 | Soil | | 19 | 58 | 1.01 | 202 | 0.120 | 3 | 2.10 | 0.056 | 0.05 | <0.1 | 0.03 | 9.1 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320850 | Soil | | 13 | 47 | 1.00 | 154 | 0.127 | 4 | 1.84 | 0.064 | 0.08 | <0.1 | 0.02 | 6.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320851 | Soil | | 15 | 48 | 0.89 | 155 | 0.122 | 3 | 1.89 | 0.056 | 0.07 | <0.1 | 0.04 | 8.1 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320852 | Soil | | 13 | 47 | 1.22 | 151 | 0.143 | 3 | 1.81 | 0.070 | 0.07 | <0.1 | 0.06 | 6.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320853 | Soil | | 20 | 68 | 1.37 | 119 | 0.161 | 3 | 2.08 | 0.063 | 0.09 | <0.1 | 0.03 | 8.2 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320854 | Soil | | 13 | 40 | 1.07 | 158 | 0.126 | 3 | 1.60 | 0.067 | 0.08 | <0.1 | 0.06 | 6.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320855 | Soil | | 10 | 35 | 0.92 | 99 | 0.107 | 2 | 1.36 | 0.059 | 0.07 | <0.1 | <0.01 | 5.4 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1320856 | Soil | | 10 | 31 | 0.85 | 147 | 0.115 | 2 | 1.50 | 0.064 | 0.05 | <0.1 | 0.01 | 4.8 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1320857 | Soil | | 14 | 45 | 0.93 | 169 | 0.132 | 2 | 1.93 | 0.059 | 0.09 | <0.1 | 0.02 | 7.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320858 | Soil | | 11 | 38 | 0.91 | 112 | 0.113 | 2 | 1.54 | 0.067 | 0.06 | <0.1 | 0.01 | 6.6 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1320859 | Soil | | 15 | 42 | 0.85 | 204 | 0.112 | 3 | 1.85 | 0.066 | 0.07 | 0.1 | 0.02 | 6.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320860 | Soil | | 7 | 337 | 2.77 | 59 | 0.043 | <1 | 1.95 | 0.013 | 0.02 | <0.1 | 0.64 | 9.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320861 | Soil | | 8 | 71 | 0.97 | 208 | 0.090 | 1 | 2.43 | 0.017 | 0.06 | <0.1 | 0.29 | 4.4 | 0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320862 | Soil | | 16 | 155 | 2.77 | 97 | 0.025 | <1 | 3.04 | 0.010 | 0.04 | <0.1 | 0.27 | 10.8 | 0.6 | <0.05 | 7 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1320863 | Soil | | 2.3 | 62.5 | 13.3 | 108 | 0.1 | 1297.5 | 90.1 | 1295 | 7.78 | 21.6 | 0.6 | 4.1 | 2.7 | 26 | 1.0 | 6.6 | 0.1 | 80 | 0.38 | 0.032 |
| 1320864 | Soil | | 1.3 | 37.5 | 11.0 | 54 | 0.4 | 89.3 | 12.8 | 409 | 3.71 | 49.9 | 0.5 | 10.0 | 3.0 | 45 | <0.1 | 8.8 | 0.1 | 76 | 0.67 | 0.048 |
| 1320865 | Soil | | 1.7 | 38.1 | 10.3 | 52 | 0.3 | 55.3 | 15.1 | 480 | 3.51 | 34.6 | 0.7 | 5.8 | 3.1 | 44 | 0.1 | 7.8 | 0.1 | 78 | 0.65 | 0.037 |
| 1320866 | Soil | | 1.1 | 33.4 | 12.7 | 51 | 0.3 | 77.7 | 14.2 | 367 | 3.91 | 84.1 | 0.5 | 9.2 | 3.0 | 38 | <0.1 | 11.4 | 0.1 | 77 | 0.43 | 0.036 |
| 1320867 | Soil | | 2.8 | 26.5 | 15.5 | 38 | 1.1 | 30.3 | 8.9 | 255 | 3.74 | 107.4 | 0.8 | 26.7 | 2.8 | 41 | <0.1 | 19.3 | 0.1 | 61 | 0.50 | 0.046 |
| 1320868 | Soil | | 0.8 | 34.1 | 8.3 | 40 | 0.6 | 29.2 | 8.4 | 273 | 4.08 | 58.4 | 0.8 | 31.6 | 2.0 | 51 | <0.1 | 9.8 | <0.1 | 72 | 0.64 | 0.054 |
| 1320869 | Soil | | 1.0 | 7.5 | 10.5 | 11 | 0.4 | 6.0 | 2.7 | 73 | 2.76 | 60.5 | 0.2 | 13.1 | 1.0 | 29 | <0.1 | 14.3 | <0.1 | 32 | 0.15 | 0.026 |
| 1320870 | Soil | | 1.1 | 23.1 | 29.3 | 38 | 1.0 | 19.1 | 7.8 | 255 | 2.78 | 22.6 | 0.8 | 19.2 | 2.2 | 36 | 0.1 | 11.0 | <0.1 | 63 | 0.42 | 0.046 |
| 1320871 | Soil | | 1.0 | 32.7 | 8.7 | 82 | 0.4 | 37.5 | 14.7 | 515 | 3.14 | 8.9 | 0.6 | 2.6 | 2.8 | 35 | 0.3 | 0.7 | 0.1 | 77 | 0.52 | 0.072 |
| 1320872 | Soil | | 0.9 | 42.2 | 12.0 | 84 | <0.1 | 49.9 | 22.5 | 564 | 4.43 | 9.2 | 0.7 | 5.1 | 2.4 | 36 | 0.3 | 0.6 | <0.1 | 101 | 0.80 | 0.030 |
| 1320873 | Soil | | 2.2 | 54.0 | 17.4 | 251 | 0.1 | 57.1 | 16.1 | 357 | 4.19 | 10.4 | 0.5 | 3.0 | 3.7 | 34 | 0.2 | 1.9 | 0.1 | 112 | 0.54 | 0.051 |
| 1320874 | Soil | | 1.1 | 63.6 | 15.6 | 66 | <0.1 | 42.1 | 28.6 | 989 | 5.61 | 12.9 | 0.8 | 5.1 | 2.5 | 44 | <0.1 | 0.8 | <0.1 | 127 | 0.76 | 0.047 |
| 1320875 | Soil | | 1.0 | 24.2 | 10.3 | 61 | <0.1 | 30.8 | 14.9 | 452 | 3.73 | 7.9 | 0.4 | 1.6 | 2.8 | 39 | 0.3 | 0.5 | 0.1 | 96 | 0.59 | 0.032 |
| 1320876 | Soil | | 0.8 | 25.5 | 14.9 | 52 | <0.1 | 28.7 | 13.3 | 373 | 3.54 | 10.8 | 0.5 | 5.7 | 3.7 | 36 | 0.1 | 0.4 | 0.1 | 93 | 0.49 | 0.028 |
| 1320877 | Soil | | 1.4 | 30.3 | 14.2 | 58 | <0.1 | 32.4 | 14.0 | 487 | 3.73 | 8.7 | 0.8 | 4.9 | 5.2 | 42 | <0.1 | 0.5 | 0.1 | 97 | 0.67 | 0.041 |
| 1320878 | Soil | | 0.7 | 37.3 | 14.1 | 66 | <0.1 | 34.4 | 14.9 | 425 | 3.85 | 8.4 | 1.0 | 7.8 | 5.5 | 47 | <0.1 | 0.6 | 0.1 | 94 | 0.72 | 0.060 |
| 1320879 | Soil | | 1.1 | 31.1 | 10.5 | 55 | 0.2 | 29.1 | 11.2 | 311 | 3.33 | 17.9 | 0.8 | 7.6 | 3.7 | 40 | <0.1 | 3.7 | 0.1 | 81 | 0.57 | 0.045 |
| 1320880 | Soil | | 0.9 | 19.3 | 13.3 | 46 | <0.1 | 24.8 | 11.9 | 260 | 3.47 | 17.1 | 0.4 | 5.4 | 2.9 | 38 | <0.1 | 3.3 | <0.1 | 80 | 0.43 | 0.030 |
| 1320881 | Soil | | 1.2 | 57.6 | 7.7 | 71 | 0.1 | 43.0 | 16.8 | 685 | 3.65 | 5.5 | 0.4 | 2.7 | 3.0 | 93 | 0.1 | 0.4 | <0.1 | 93 | 4.00 | 0.086 |
| 1320882 | Soil | | 0.9 | 48.2 | 6.5 | 66 | <0.1 | 39.9 | 15.9 | 642 | 3.59 | 6.9 | 0.5 | 5.8 | 2.8 | 77 | <0.1 | 0.5 | <0.1 | 91 | 3.02 | 0.082 |
| 1320883 | Soil | | 0.7 | 45.7 | 5.3 | 70 | <0.1 | 39.1 | 16.7 | 729 | 3.91 | 6.5 | 0.4 | 2.6 | 2.9 | 56 | 0.2 | 0.4 | <0.1 | 93 | 1.33 | 0.085 |
| 1320884 | Soil | | 0.6 | 38.4 | 5.2 | 70 | <0.1 | 34.5 | 14.5 | 521 | 3.32 | 5.5 | 0.5 | 3.3 | 2.7 | 53 | 0.1 | 0.4 | <0.1 | 84 | 1.26 | 0.083 |
| 1320885 | Soil | | 0.3 | 25.3 | 3.7 | 37 | <0.1 | 21.4 | 9.8 | 391 | 2.02 | 5.7 | 1.0 | 2.8 | 1.4 | 68 | <0.1 | 0.3 | <0.1 | 52 | 1.59 | 0.065 |
| 1320886 | Soil | | 0.7 | 59.7 | 6.3 | 64 | 0.1 | 41.1 | 17.3 | 640 | 3.63 | 6.9 | 0.5 | 4.0 | 2.6 | 79 | 0.2 | 0.7 | <0.1 | 90 | 2.65 | 0.067 |
| 1320887 | Soil | | 0.8 | 46.1 | 5.8 | 63 | 0.1 | 35.4 | 14.9 | 496 | 3.39 | 7.7 | 0.5 | 4.4 | 2.7 | 56 | 0.1 | 0.5 | <0.1 | 89 | 1.14 | 0.081 |
| 1320888 | Soil | | 0.6 | 53.3 | 5.9 | 66 | <0.1 | 40.7 | 15.8 | 622 | 3.61 | 5.2 | 0.4 | 2.3 | 2.7 | 60 | <0.1 | 0.5 | <0.1 | 91 | 1.81 | 0.085 |
| 1320889 | Soil | | 0.5 | 39.3 | 4.8 | 59 | <0.1 | 33.4 | 12.9 | 409 | 3.26 | 6.6 | 0.4 | 7.6 | 2.4 | 55 | 0.1 | 0.4 | <0.1 | 89 | 1.52 | 0.079 |
| 1320890 | Soil | | 1.8 | 49.7 | 6.6 | 68 | <0.1 | 37.3 | 13.5 | 543 | 3.89 | 9.3 | 1.2 | 6.3 | 2.7 | 57 | 0.2 | 0.4 | <0.1 | 91 | 1.27 | 0.109 |
| 1320891 | Soil | | 0.6 | 47.5 | 5.8 | 57 | <0.1 | 35.0 | 13.7 | 510 | 3.17 | 6.5 | 0.6 | 3.0 | 2.8 | 49 | <0.1 | 0.5 | <0.1 | 79 | 0.98 | 0.067 |
| 1320892 | Soil | | 1.0 | 42.3 | 22.5 | 61 | 0.1 | 30.3 | 15.0 | 612 | 3.05 | 70.1 | 1.4 | 33.5 | 5.1 | 36 | 0.1 | 1.4 | 0.2 | 62 | 0.80 | 0.041 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1320863 | Soil | | 11 | 232 | 1.11 | 158 | 0.034 | <1 | 2.70 | 0.014 | 0.04 | <0.1 | 0.24 | 9.7 | 0.5 | <0.05 | 6 | <0.5 | <0.2 |
| 1320864 | Soil | | 11 | 85 | 0.82 | 195 | 0.104 | 2 | 1.82 | 0.055 | 0.10 | 0.1 | 0.49 | 8.0 | 0.6 | 0.12 | 5 | 0.5 | <0.2 |
| 1320865 | Soil | | 14 | 61 | 0.73 | 193 | 0.106 | 1 | 1.97 | 0.044 | 0.07 | <0.1 | 0.18 | 7.3 | 0.4 | 0.07 | 6 | <0.5 | <0.2 |
| 1320866 | Soil | | 12 | 93 | 0.75 | 151 | 0.088 | 1 | 1.88 | 0.031 | 0.09 | <0.1 | 0.13 | 4.8 | 0.9 | 0.12 | 6 | <0.5 | <0.2 |
| 1320867 | Soil | | 12 | 57 | 0.56 | 244 | 0.065 | 2 | 1.52 | 0.047 | 0.21 | <0.1 | 1.78 | 5.1 | 2.4 | 0.41 | 5 | <0.5 | <0.2 |
| 1320868 | Soil | | 8 | 52 | 0.49 | 356 | 0.065 | 2 | 1.23 | 0.179 | 0.17 | <0.1 | 1.45 | 6.6 | 1.6 | 0.74 | 6 | 1.4 | <0.2 |
| 1320869 | Soil | | 4 | 25 | 0.15 | 234 | 0.012 | 3 | 0.52 | 0.156 | 0.19 | 0.1 | 1.17 | 2.0 | 2.5 | 0.80 | 4 | 0.5 | <0.2 |
| 1320870 | Soil | | 10 | 33 | 0.44 | 692 | 0.079 | <1 | 1.38 | 0.044 | 0.09 | 0.1 | 4.32 | 4.6 | 1.3 | 0.19 | 5 | 0.7 | <0.2 |
| 1320871 | Soil | | 10 | 42 | 0.64 | 225 | 0.082 | 1 | 2.26 | 0.027 | 0.04 | <0.1 | 0.07 | 6.5 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320872 | Soil | | 13 | 56 | 1.04 | 233 | 0.189 | <1 | 2.77 | 0.023 | 0.05 | <0.1 | 0.11 | 12.9 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320873 | Soil | | 13 | 69 | 1.01 | 243 | 0.081 | <1 | 2.86 | 0.015 | 0.07 | <0.1 | 0.06 | 10.9 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320874 | Soil | | 19 | 62 | 1.36 | 257 | 0.187 | <1 | 3.06 | 0.027 | 0.08 | <0.1 | 0.05 | 21.5 | 0.1 | <0.05 | 9 | <0.5 | <0.2 |
| 1320875 | Soil | | 9 | 50 | 0.73 | 203 | 0.139 | 3 | 2.57 | 0.027 | 0.05 | <0.1 | 0.03 | 5.4 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320876 | Soil | | 12 | 49 | 0.73 | 172 | 0.142 | 2 | 2.44 | 0.023 | 0.06 | 0.1 | <0.01 | 6.1 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320877 | Soil | | 16 | 52 | 0.76 | 214 | 0.148 | 3 | 2.55 | 0.034 | 0.06 | 0.1 | 0.03 | 8.4 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320878 | Soil | | 17 | 52 | 0.83 | 207 | 0.136 | 3 | 2.34 | 0.045 | 0.06 | 0.1 | 0.04 | 10.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320879 | Soil | | 13 | 48 | 0.66 | 222 | 0.126 | 2 | 2.08 | 0.047 | 0.06 | <0.1 | 0.20 | 7.5 | 0.2 | 0.10 | 6 | <0.5 | <0.2 |
| 1320880 | Soil | | 8 | 44 | 0.61 | 217 | 0.128 | 2 | 1.96 | 0.064 | 0.08 | <0.1 | 0.06 | 5.0 | 0.4 | 0.24 | 6 | <0.5 | <0.2 |
| 1320881 | Soil | | 14 | 49 | 1.22 | 149 | 0.160 | 5 | 1.99 | 0.089 | 0.12 | <0.1 | 0.04 | 8.3 | 0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320882 | Soil | | 14 | 46 | 1.06 | 141 | 0.155 | 5 | 1.97 | 0.081 | 0.11 | 0.1 | 0.04 | 8.2 | 0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320883 | Soil | | 14 | 47 | 1.24 | 138 | 0.157 | 6 | 2.14 | 0.080 | 0.13 | <0.1 | 0.02 | 9.0 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320884 | Soil | | 13 | 42 | 0.95 | 126 | 0.144 | 26 | 1.78 | 0.078 | 0.11 | <0.1 | 0.01 | 8.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320885 | Soil | | 8 | 24 | 0.55 | 123 | 0.078 | 4 | 1.15 | 0.043 | 0.04 | <0.1 | 0.02 | 4.1 | <0.1 | 0.07 | 3 | <0.5 | <0.2 |
| 1320886 | Soil | | 16 | 47 | 1.42 | 114 | 0.141 | 3 | 2.06 | 0.077 | 0.08 | <0.1 | 0.05 | 8.5 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320887 | Soil | | 14 | 40 | 0.92 | 159 | 0.141 | 4 | 1.97 | 0.071 | 0.09 | 0.1 | 0.03 | 7.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320888 | Soil | | 13 | 48 | 1.07 | 152 | 0.150 | 3 | 1.99 | 0.072 | 0.11 | <0.1 | 0.03 | 8.4 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320889 | Soil | | 12 | 42 | 0.99 | 129 | 0.147 | 4 | 1.80 | 0.073 | 0.11 | <0.1 | 0.02 | 7.5 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320890 | Soil | | 15 | 42 | 0.92 | 148 | 0.142 | 4 | 1.81 | 0.073 | 0.11 | 0.1 | 0.03 | 7.5 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320891 | Soil | | 13 | 40 | 0.79 | 165 | 0.130 | 5 | 1.91 | 0.060 | 0.09 | <0.1 | 0.02 | 6.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320892 | Soil | | 20 | 34 | 0.55 | 163 | 0.051 | 1 | 2.01 | 0.021 | 0.06 | <0.1 | 0.03 | 4.0 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1320893 | Soil | 1.2 | 24.1 | 12.9 | 77 | 0.2 | 34.9 | 13.0 | 335 | 3.58 | 49.2 | 0.6 | 19.9 | 4.9 | 24 | 0.2 | 1.3 | 0.2 | 75 | 0.31 | 0.040 |
| 1320894 | Soil | 0.8 | 21.8 | 13.3 | 55 | 0.3 | 18.4 | 8.4 | 254 | 1.96 | 18.5 | 1.0 | 26.3 | 2.1 | 27 | 0.1 | 0.5 | 0.2 | 40 | 0.36 | 0.054 |
| 1320895 | Soil | 0.9 | 26.6 | 10.6 | 62 | 0.2 | 23.2 | 12.5 | 527 | 2.66 | 28.0 | 0.8 | 14.5 | 2.3 | 28 | 0.2 | 0.6 | 0.2 | 66 | 0.39 | 0.056 |
| 1320896 | Soil | 0.8 | 20.0 | 11.5 | 63 | 0.1 | 24.3 | 15.4 | 711 | 2.63 | 42.1 | 0.6 | 23.1 | 3.0 | 30 | <0.1 | 0.9 | 0.1 | 61 | 0.49 | 0.049 |
| 1320897 | Soil | 0.8 | 24.9 | 9.4 | 64 | 0.2 | 24.0 | 13.0 | 577 | 2.67 | 19.2 | 0.6 | 10.1 | 2.5 | 36 | 0.1 | 0.6 | <0.1 | 68 | 0.66 | 0.058 |
| 1320898 | Soil | 0.8 | 22.3 | 7.5 | 54 | 0.1 | 18.6 | 12.4 | 837 | 2.32 | 17.6 | 0.6 | 9.8 | 1.6 | 36 | 0.2 | 0.6 | 0.1 | 59 | 0.64 | 0.061 |
| 1320899 | Soil | 8.8 | 21.1 | 8.7 | 60 | <0.1 | 20.5 | 11.6 | 703 | 2.49 | 10.4 | 0.7 | 3.0 | 1.7 | 37 | <0.1 | 1.5 | 0.2 | 69 | 0.44 | 0.060 |
| 1320900 | Soil | 2.1 | 42.9 | 8.1 | 58 | 0.2 | 26.5 | 12.9 | 709 | 2.80 | 21.2 | 1.1 | 16.4 | 2.4 | 43 | 0.1 | 1.6 | 0.1 | 66 | 0.58 | 0.073 |
| 1320901 | Soil | 0.6 | 42.9 | 6.7 | 63 | <0.1 | 34.1 | 12.9 | 453 | 3.40 | 13.6 | 0.7 | 5.6 | 3.4 | 49 | <0.1 | 0.7 | <0.1 | 85 | 0.76 | 0.055 |
| 1320902 | Soil | 0.4 | 44.0 | 6.7 | 62 | <0.1 | 29.1 | 11.9 | 509 | 2.86 | 11.3 | 0.7 | 7.2 | 2.8 | 54 | 0.1 | 0.8 | 0.1 | 75 | 0.87 | 0.065 |
| 1320903 | Soil | 1.0 | 47.1 | 8.5 | 72 | 0.3 | 222.9 | 22.3 | 458 | 3.13 | 278.8 | 0.8 | 48.4 | 2.1 | 33 | 0.3 | 3.0 | 0.1 | 76 | 0.73 | 0.046 |
| 1320904 | Soil | 0.7 | 32.3 | 8.6 | 57 | 0.1 | 81.0 | 16.3 | 359 | 3.70 | 46.6 | 0.6 | 9.3 | 2.8 | 30 | 0.2 | 3.9 | 0.1 | 86 | 0.43 | 0.025 |
| 1320905 | Soil | 2.5 | 41.1 | 19.7 | 144 | 1.2 | 36.3 | 7.4 | 204 | 4.42 | 28.7 | 1.9 | 3.6 | 4.6 | 43 | 0.5 | 12.9 | 0.2 | 82 | 0.45 | 0.122 |
| 1320906 | Soil | 5.4 | 29.0 | 18.9 | 75 | 0.4 | 25.2 | 11.1 | 356 | 3.95 | 18.7 | 1.0 | 4.3 | 4.5 | 29 | 0.1 | 1.9 | 0.3 | 79 | 0.29 | 0.068 |
| 1320907 | Soil | 1.5 | 33.2 | 10.1 | 67 | 0.2 | 27.9 | 11.9 | 302 | 3.36 | 10.6 | 0.9 | 3.9 | 3.3 | 28 | <0.1 | 0.8 | 0.1 | 74 | 0.37 | 0.030 |
| 1320908 | Soil | 1.5 | 24.1 | 7.8 | 48 | 0.1 | 23.0 | 14.9 | 659 | 3.02 | 10.9 | 0.4 | 1.8 | 2.0 | 26 | 0.2 | 0.5 | 0.1 | 89 | 0.35 | 0.037 |
| 1320909 | Soil | 1.0 | 54.2 | 6.6 | 55 | <0.1 | 37.1 | 15.4 | 318 | 4.05 | 18.7 | 0.5 | 8.0 | 2.5 | 24 | 0.1 | 0.5 | 0.1 | 95 | 0.32 | 0.039 |
| 1320910 | Soil | 2.3 | 62.8 | 12.7 | 89 | 0.4 | 33.4 | 13.1 | 438 | 3.75 | 37.3 | 0.9 | 9.6 | 4.6 | 56 | 0.2 | 4.5 | 0.2 | 64 | 0.56 | 0.085 |
| 1320911 | Soil | 1.1 | 33.3 | 13.1 | 60 | <0.1 | 34.1 | 15.3 | 659 | 3.66 | 8.5 | 0.6 | <0.5 | 5.8 | 31 | <0.1 | 0.5 | 0.2 | 87 | 0.43 | 0.019 |
| 1320912 | Soil | 1.4 | 44.0 | 6.0 | 83 | <0.1 | 40.6 | 15.7 | 462 | 3.83 | 7.3 | 0.3 | 3.4 | 1.4 | 28 | 0.1 | 0.6 | 0.2 | 107 | 0.66 | 0.085 |
| 1320913 | Soil | 0.9 | 29.3 | 7.0 | 61 | <0.1 | 29.9 | 11.7 | 371 | 3.46 | 8.1 | 0.4 | 2.5 | 1.9 | 29 | <0.1 | 0.4 | 0.2 | 92 | 0.41 | 0.034 |
| 1320914 | Soil | 1.0 | 35.4 | 6.6 | 44 | <0.1 | 28.0 | 11.5 | 255 | 3.26 | 6.0 | 0.4 | 0.9 | 1.8 | 26 | <0.1 | 0.4 | 0.1 | 93 | 0.36 | 0.018 |
| 1320915 | Soil | 1.0 | 25.8 | 6.4 | 48 | <0.1 | 26.5 | 12.6 | 349 | 3.12 | 7.5 | 0.4 | <0.5 | 1.8 | 30 | <0.1 | 0.5 | 0.1 | 85 | 0.48 | 0.018 |
| 1320916 | Soil | 0.6 | 53.2 | 5.8 | 46 | <0.1 | 34.9 | 13.9 | 564 | 3.45 | 7.3 | 0.4 | 0.8 | 2.1 | 33 | <0.1 | 0.4 | 0.1 | 95 | 0.68 | 0.032 |
| 1320917 | Soil | 1.0 | 14.4 | 5.8 | 41 | <0.1 | 15.6 | 7.9 | 188 | 2.46 | 5.4 | 0.2 | <0.5 | 1.1 | 16 | <0.1 | 0.4 | 0.1 | 70 | 0.19 | 0.019 |
| 1320918 | Soil | 0.4 | 14.8 | 3.2 | 21 | <0.1 | 6.9 | 2.9 | 149 | 1.04 | 2.1 | 0.2 | <0.5 | 0.6 | 17 | <0.1 | 0.2 | <0.1 | 29 | 0.28 | 0.025 |
| 1320919 | Soil | 1.6 | 22.9 | 6.3 | 60 | <0.1 | 20.8 | 8.6 | 418 | 3.40 | 6.7 | 0.3 | 5.3 | 1.1 | 15 | <0.1 | 0.5 | 0.2 | 89 | 0.19 | 0.037 |
| 1320920 | Soil | 0.9 | 54.7 | 5.6 | 60 | <0.1 | 27.7 | 12.8 | 420 | 2.84 | 11.5 | 0.3 | <0.5 | 1.1 | 20 | 0.1 | 0.3 | <0.1 | 74 | 0.31 | 0.038 |
| 1320921 | Soil | 1.1 | 21.7 | 4.1 | 34 | <0.1 | 13.9 | 5.6 | 129 | 2.16 | 4.5 | 0.2 | <0.5 | 0.9 | 14 | <0.1 | 0.4 | <0.1 | 60 | 0.16 | 0.017 |
| 1320922 | Soil | 0.8 | 53.5 | 4.7 | 50 | <0.1 | 40.7 | 15.2 | 278 | 3.80 | 7.5 | 0.3 | 1.2 | 1.6 | 26 | 0.1 | 0.3 | <0.1 | 105 | 0.44 | 0.031 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1320893 | Soil | 14 | 42 | 0.61 | 117 | 0.100 | 2 | 2.02 | 0.020 | 0.10 | 0.1 | 0.02 | 4.4 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320894 | Soil | 12 | 23 | 0.34 | 110 | 0.050 | <1 | 1.29 | 0.024 | 0.06 | <0.1 | 0.03 | 3.1 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320895 | Soil | 12 | 34 | 0.52 | 134 | 0.073 | 2 | 1.56 | 0.028 | 0.06 | <0.1 | 0.04 | 4.0 | <0.1 | 0.06 | 5 | <0.5 | <0.2 |
| 1320896 | Soil | 12 | 30 | 0.46 | 128 | 0.080 | 2 | 1.51 | 0.029 | 0.05 | 0.1 | 0.07 | 4.2 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320897 | Soil | 10 | 36 | 0.57 | 122 | 0.090 | 3 | 1.66 | 0.035 | 0.06 | 0.2 | 0.03 | 4.7 | <0.1 | 0.06 | 5 | <0.5 | <0.2 |
| 1320898 | Soil | 9 | 29 | 0.45 | 122 | 0.077 | 2 | 1.40 | 0.029 | 0.05 | <0.1 | 0.04 | 4.3 | <0.1 | <0.05 | 5 | 0.5 | <0.2 |
| 1320899 | Soil | 9 | 30 | 0.54 | 171 | 0.099 | <1 | 1.68 | 0.028 | 0.05 | <0.1 | 0.02 | 3.3 | 0.2 | <0.05 | 6 | <0.5 | <0.2 |
| 1320900 | Soil | 13 | 33 | 0.55 | 237 | 0.096 | 2 | 1.85 | 0.041 | 0.05 | <0.1 | 0.06 | 6.1 | 0.1 | <0.05 | 6 | 0.9 | <0.2 |
| 1320901 | Soil | 15 | 42 | 0.73 | 216 | 0.142 | 2 | 1.98 | 0.051 | 0.07 | <0.1 | 0.05 | 8.0 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320902 | Soil | 12 | 35 | 0.68 | 217 | 0.124 | 3 | 1.84 | 0.054 | 0.06 | 0.1 | 0.02 | 6.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320903 | Soil | 13 | 91 | 0.65 | 1090 | 0.096 | 1 | 1.93 | 0.032 | 0.04 | <0.1 | 0.08 | 6.6 | 0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320904 | Soil | 10 | 70 | 0.74 | 547 | 0.125 | <1 | 2.48 | 0.025 | 0.05 | <0.1 | 0.09 | 6.4 | 0.4 | <0.05 | 7 | 0.6 | <0.2 |
| 1320905 | Soil | 20 | 38 | 0.53 | 148 | 0.054 | 1 | 1.61 | 0.016 | 0.12 | 0.1 | 0.06 | 4.9 | 0.2 | 0.38 | 5 | 3.5 | <0.2 |
| 1320906 | Soil | 21 | 38 | 0.49 | 196 | 0.075 | 2 | 2.11 | 0.025 | 0.07 | 0.1 | 0.02 | 4.9 | 0.1 | 0.09 | 7 | <0.5 | <0.2 |
| 1320907 | Soil | 15 | 39 | 0.56 | 122 | 0.097 | <1 | 2.10 | 0.022 | 0.08 | <0.1 | 0.03 | 5.8 | <0.1 | 0.05 | 7 | <0.5 | <0.2 |
| 1320908 | Soil | 7 | 33 | 0.51 | 196 | 0.096 | 2 | 2.21 | 0.023 | 0.05 | <0.1 | 0.03 | 4.0 | 0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1320909 | Soil | 8 | 45 | 0.75 | 128 | 0.123 | 3 | 2.93 | 0.021 | 0.09 | <0.1 | 0.05 | 5.5 | <0.1 | 0.05 | 7 | <0.5 | <0.2 |
| 1320910 | Soil | 23 | 33 | 0.59 | 136 | 0.087 | <1 | 1.67 | 0.043 | 0.09 | <0.1 | 0.05 | 6.7 | 0.1 | 0.07 | 5 | <0.5 | <0.2 |
| 1320911 | Soil | 18 | 54 | 0.71 | 182 | 0.095 | 2 | 2.79 | 0.020 | 0.07 | 0.1 | 0.03 | 8.7 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320912 | Soil | 5 | 63 | 0.88 | 92 | 0.094 | 2 | 2.31 | 0.025 | 0.05 | 0.1 | 0.04 | 4.8 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320913 | Soil | 7 | 44 | 0.71 | 200 | 0.110 | 1 | 2.48 | 0.022 | 0.04 | <0.1 | 0.03 | 4.5 | 0.1 | <0.05 | 7 | 0.6 | <0.2 |
| 1320914 | Soil | 8 | 44 | 0.65 | 127 | 0.118 | <1 | 2.24 | 0.022 | 0.04 | <0.1 | 0.03 | 4.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320915 | Soil | 7 | 40 | 0.65 | 152 | 0.104 | <1 | 2.24 | 0.026 | 0.04 | <0.1 | 0.01 | 4.1 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320916 | Soil | 9 | 44 | 0.71 | 234 | 0.100 | <1 | 2.35 | 0.032 | 0.05 | <0.1 | 0.03 | 6.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320917 | Soil | 5 | 24 | 0.30 | 103 | 0.086 | 1 | 1.44 | 0.024 | 0.04 | <0.1 | 0.02 | 2.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320918 | Soil | 4 | 12 | 0.17 | 71 | 0.049 | <1 | 0.73 | 0.030 | 0.03 | <0.1 | 0.02 | 1.7 | <0.1 | <0.05 | 3 | <0.5 | <0.2 |
| 1320919 | Soil | 5 | 32 | 0.37 | 79 | 0.088 | <1 | 1.58 | 0.018 | 0.05 | <0.1 | 0.05 | 2.7 | <0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1320920 | Soil | 6 | 37 | 0.48 | 112 | 0.082 | <1 | 1.70 | 0.022 | 0.04 | <0.1 | 0.07 | 4.0 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320921 | Soil | 4 | 22 | 0.27 | 59 | 0.079 | <1 | 1.06 | 0.024 | 0.05 | 0.1 | 0.01 | 2.2 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320922 | Soil | 6 | 59 | 0.77 | 119 | 0.121 | 2 | 2.50 | 0.022 | 0.05 | <0.1 | 0.03 | 4.6 | <0.1 | <0.05 | 7 | 0.9 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1320923 | Soil | | 0.9 | 26.5 | 5.7 | 42 | <0.1 | 28.1 | 11.3 | 240 | 3.08 | 6.3 | 0.3 | <0.5 | 1.2 | 22 | <0.1 | 0.4 | <0.1 | 87 | 0.27 | 0.016 |
| 1320924 | Soil | | 0.9 | 41.8 | 5.2 | 47 | <0.1 | 24.8 | 9.8 | 397 | 2.79 | 5.4 | 0.4 | <0.5 | 1.3 | 18 | <0.1 | 0.4 | 0.1 | 82 | 0.28 | 0.027 |
| 1320925 | Soil | | 0.8 | 41.9 | 9.3 | 53 | 0.2 | 37.6 | 12.0 | 468 | 3.10 | 9.7 | 0.8 | 2.1 | 2.6 | 46 | 0.2 | 0.5 | <0.1 | 68 | 0.81 | 0.058 |
| 1320926 | Soil | | 0.9 | 49.1 | 9.9 | 56 | 0.3 | 36.1 | 12.9 | 755 | 3.16 | 10.9 | 0.6 | <0.5 | 3.3 | 44 | 0.3 | 0.5 | 0.1 | 73 | 0.72 | 0.035 |
| 1320927 | Soil | | 0.9 | 30.0 | 9.7 | 52 | 0.1 | 31.9 | 13.9 | 443 | 3.41 | 14.5 | 0.6 | 3.8 | 3.7 | 38 | <0.1 | 0.5 | <0.1 | 85 | 0.66 | 0.030 |
| 1320928 | Soil | | 0.7 | 35.4 | 7.9 | 48 | 0.1 | 31.0 | 13.4 | 450 | 3.46 | 10.7 | 0.6 | 2.2 | 3.7 | 41 | <0.1 | 0.6 | <0.1 | 88 | 0.76 | 0.030 |
| 1320929 | Soil | | 0.6 | 43.8 | 6.3 | 51 | <0.1 | 34.7 | 12.7 | 490 | 3.16 | 8.4 | 0.4 | <0.5 | 2.9 | 51 | <0.1 | 0.5 | <0.1 | 81 | 1.28 | 0.048 |
| 1320930 | Soil | | 0.7 | 31.6 | 7.4 | 52 | <0.1 | 33.3 | 15.3 | 458 | 3.69 | 12.6 | 0.7 | <0.5 | 3.5 | 37 | <0.1 | 0.5 | <0.1 | 93 | 0.72 | 0.016 |
| 1320931 | Soil | | 0.4 | 47.6 | 5.5 | 49 | <0.1 | 35.4 | 12.6 | 403 | 3.06 | 10.1 | 0.4 | 1.5 | 3.4 | 45 | <0.1 | 0.5 | <0.1 | 89 | 0.83 | 0.046 |
| 1320932 | Soil | | 1.2 | 23.6 | 8.5 | 62 | 0.2 | 31.6 | 15.4 | 344 | 3.64 | 9.9 | 0.5 | 1.1 | 3.9 | 30 | 0.1 | 0.8 | <0.1 | 84 | 0.45 | 0.023 |
| 1321301 | Soil | | 0.8 | 43.8 | 5.4 | 52 | <0.1 | 30.1 | 11.5 | 399 | 3.04 | 8.2 | 0.9 | <0.5 | 2.7 | 65 | <0.1 | 0.5 | <0.1 | 81 | 1.06 | 0.046 |
| 1321302 | Soil | | 0.7 | 53.5 | 6.1 | 67 | 0.2 | 40.5 | 13.8 | 489 | 3.12 | 10.2 | 0.6 | 5.0 | 2.5 | 56 | 0.1 | 0.5 | <0.1 | 78 | 1.26 | 0.061 |
| 1321303 | Soil | | 1.0 | 76.6 | 7.1 | 73 | <0.1 | 46.0 | 14.1 | 413 | 3.51 | 10.0 | 0.6 | 3.3 | 4.0 | 46 | <0.1 | 0.6 | <0.1 | 76 | 0.73 | 0.032 |
| 1321304 | Soil | | 0.9 | 55.4 | 7.7 | 55 | <0.1 | 39.6 | 15.8 | 610 | 3.29 | 8.6 | 0.5 | 1.7 | 3.3 | 48 | <0.1 | 0.6 | <0.1 | 76 | 0.79 | 0.026 |
| 1321305 | Soil | | 1.1 | 46.0 | 7.9 | 51 | <0.1 | 35.1 | 14.6 | 447 | 3.49 | 7.6 | 0.4 | <0.5 | 3.1 | 46 | <0.1 | 0.5 | <0.1 | 84 | 0.80 | 0.022 |
| 1321306 | Soil | | 0.6 | 54.8 | 5.6 | 56 | <0.1 | 35.2 | 13.8 | 474 | 3.43 | 8.4 | 0.4 | 1.6 | 2.7 | 62 | <0.1 | 0.5 | <0.1 | 83 | 1.93 | 0.036 |
| 1321307 | Soil | | 1.1 | 31.0 | 7.1 | 52 | 0.1 | 33.7 | 17.0 | 596 | 3.84 | 8.9 | 0.4 | 3.9 | 3.0 | 39 | <0.1 | 0.5 | 0.1 | 90 | 0.77 | 0.023 |
| 1321308 | Soil | | 0.9 | 40.0 | 5.9 | 49 | 0.1 | 39.4 | 15.9 | 471 | 3.95 | 9.9 | 0.5 | <0.5 | 3.2 | 40 | <0.1 | 0.5 | <0.1 | 93 | 0.80 | 0.021 |
| 1321309 | Soil | | 0.8 | 81.7 | 8.3 | 64 | <0.1 | 42.9 | 12.4 | 656 | 2.37 | 6.0 | 0.5 | <0.5 | 3.6 | 30 | <0.1 | 0.4 | 0.1 | 38 | 0.32 | 0.018 |
| 1321310 | Soil | | 0.8 | 51.1 | 7.2 | 50 | <0.1 | 37.6 | 16.0 | 823 | 3.46 | 12.3 | 0.4 | 5.2 | 3.2 | 42 | <0.1 | 0.7 | <0.1 | 90 | 0.66 | 0.013 |
| 1321311 | Soil | | 3.9 | 149.0 | 18.9 | 78 | <0.1 | 54.6 | 25.2 | 1988 | 3.40 | 18.2 | 1.0 | 9.9 | 5.3 | 34 | 0.1 | 2.3 | 0.3 | 41 | 0.45 | 0.038 |
| 1321312 | Soil | | 0.9 | 24.3 | 6.7 | 59 | <0.1 | 29.6 | 14.7 | 743 | 3.42 | 6.5 | 0.3 | 9.3 | 3.0 | 42 | <0.1 | 0.5 | <0.1 | 74 | 0.70 | 0.038 |
| 1321313 | Soil | | 0.5 | 40.0 | 5.4 | 48 | <0.1 | 38.2 | 13.9 | 438 | 3.48 | 9.1 | 0.4 | 0.6 | 3.2 | 48 | <0.1 | 0.5 | <0.1 | 87 | 0.73 | 0.029 |
| 1321314 | Soil | | 0.4 | 43.4 | 4.2 | 49 | 0.1 | 29.0 | 11.5 | 449 | 2.89 | 7.6 | 0.5 | 1.4 | 2.4 | 89 | <0.1 | 0.4 | <0.1 | 84 | 3.29 | 0.088 |
| 1321315 | Soil | | 0.8 | 32.7 | 5.0 | 47 | <0.1 | 27.9 | 12.6 | 432 | 2.89 | 6.2 | 0.5 | 1.9 | 2.5 | 44 | <0.1 | 0.5 | 0.1 | 70 | 0.86 | 0.040 |
| 1321316 | Soil | | 0.7 | 39.9 | 5.2 | 50 | <0.1 | 31.5 | 12.3 | 400 | 2.91 | 7.7 | 0.5 | 12.6 | 2.3 | 70 | <0.1 | 0.4 | <0.1 | 75 | 2.70 | 0.067 |
| 1321317 | Soil | | 0.4 | 39.7 | 5.4 | 57 | <0.1 | 30.9 | 12.7 | 447 | 2.92 | 7.7 | 0.4 | 6.7 | 2.3 | 95 | 0.2 | 0.5 | <0.1 | 75 | 3.30 | 0.058 |
| 1321318 | Soil | | 0.9 | 23.8 | 4.5 | 47 | <0.1 | 19.8 | 9.9 | 597 | 2.24 | 3.0 | 0.3 | 2.9 | 2.0 | 28 | 0.2 | 0.2 | <0.1 | 47 | 0.44 | 0.063 |
| 1321319 | Soil | | 0.7 | 23.3 | 5.6 | 48 | <0.1 | 27.7 | 12.3 | 377 | 3.03 | 7.4 | 0.4 | 2.5 | 2.2 | 34 | <0.1 | 0.5 | <0.1 | 74 | 0.65 | 0.048 |
| 1321320 | Soil | | 0.8 | 43.9 | 5.8 | 54 | <0.1 | 34.1 | 13.9 | 517 | 3.24 | 7.2 | 0.4 | 8.3 | 3.0 | 56 | <0.1 | 0.5 | <0.1 | 83 | 1.57 | 0.070 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1320923 | Soil | | 5 | 39 | 0.51 | 125 | 0.110 | <1 | 2.04 | 0.020 | 0.05 | <0.1 | 0.01 | 3.1 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320924 | Soil | | 7 | 38 | 0.45 | 121 | 0.092 | <1 | 1.59 | 0.027 | 0.05 | <0.1 | 0.04 | 3.9 | <0.1 | <0.05 | 6 | 0.5 | <0.2 |
| 1320925 | Soil | | 14 | 45 | 0.65 | 161 | 0.089 | <1 | 2.08 | 0.028 | 0.08 | <0.1 | 0.06 | 6.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320926 | Soil | | 14 | 42 | 0.64 | 229 | 0.100 | 1 | 2.17 | 0.037 | 0.09 | <0.1 | 0.03 | 6.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320927 | Soil | | 11 | 47 | 0.70 | 134 | 0.120 | <1 | 2.21 | 0.038 | 0.08 | <0.1 | 0.02 | 7.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320928 | Soil | | 15 | 46 | 0.70 | 139 | 0.135 | <1 | 2.33 | 0.042 | 0.08 | <0.1 | 0.04 | 8.4 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1320929 | Soil | | 14 | 37 | 0.79 | 147 | 0.126 | 2 | 1.86 | 0.061 | 0.06 | 0.1 | 0.03 | 6.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320930 | Soil | | 13 | 50 | 0.75 | 179 | 0.133 | <1 | 2.53 | 0.041 | 0.07 | <0.1 | 0.03 | 8.9 | <0.1 | <0.05 | 7 | 0.5 | <0.2 |
| 1320931 | Soil | | 15 | 37 | 0.78 | 121 | 0.144 | 1 | 1.83 | 0.064 | 0.07 | 0.1 | 0.03 | 6.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320932 | Soil | | 11 | 48 | 0.70 | 147 | 0.098 | <1 | 2.47 | 0.021 | 0.11 | <0.1 | 0.02 | 6.5 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321301 | Soil | | 12 | 38 | 0.80 | 201 | 0.127 | 2 | 1.82 | 0.064 | 0.09 | <0.1 | 0.03 | 6.5 | <0.1 | <0.05 | 5 | 0.6 | <0.2 |
| 1321302 | Soil | | 14 | 38 | 0.83 | 297 | 0.114 | 3 | 1.80 | 0.054 | 0.10 | 0.1 | 0.05 | 6.7 | <0.1 | <0.05 | 5 | 1.2 | <0.2 |
| 1321303 | Soil | | 17 | 38 | 0.88 | 512 | 0.120 | 2 | 1.86 | 0.053 | 0.09 | <0.1 | 0.04 | 6.6 | <0.1 | <0.05 | 6 | 1.0 | <0.2 |
| 1321304 | Soil | | 16 | 39 | 0.73 | 650 | 0.112 | 2 | 2.00 | 0.050 | 0.09 | <0.1 | 0.03 | 7.0 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321305 | Soil | | 15 | 44 | 0.79 | 1061 | 0.128 | 2 | 2.08 | 0.055 | 0.07 | <0.1 | 0.04 | 8.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321306 | Soil | | 15 | 39 | 0.87 | 181 | 0.129 | 4 | 1.85 | 0.063 | 0.09 | 0.1 | 0.03 | 7.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321307 | Soil | | 15 | 47 | 0.72 | 215 | 0.134 | 2 | 2.56 | 0.042 | 0.12 | 0.1 | 0.03 | 9.9 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321308 | Soil | | 14 | 54 | 0.84 | 182 | 0.140 | 2 | 2.51 | 0.044 | 0.11 | <0.1 | 0.03 | 10.8 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321309 | Soil | | 15 | 29 | 0.63 | 1360 | 0.032 | <1 | 1.55 | 0.012 | 0.09 | <0.1 | 0.02 | 4.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321310 | Soil | | 13 | 47 | 0.71 | 518 | 0.131 | 1 | 2.23 | 0.039 | 0.08 | <0.1 | 0.03 | 8.8 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321311 | Soil | | 22 | 22 | 0.58 | 601 | 0.029 | 4 | 1.69 | 0.015 | 0.10 | <0.1 | 0.10 | 5.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321312 | Soil | | 10 | 41 | 0.66 | 353 | 0.114 | 3 | 2.10 | 0.043 | 0.12 | <0.1 | <0.01 | 7.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321313 | Soil | | 15 | 42 | 0.86 | 149 | 0.146 | <1 | 1.95 | 0.059 | 0.10 | 0.1 | 0.02 | 7.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321314 | Soil | | 10 | 34 | 0.94 | 146 | 0.122 | 3 | 1.54 | 0.065 | 0.09 | 0.2 | 0.06 | 5.0 | <0.1 | <0.05 | 5 | 0.6 | <0.2 |
| 1321315 | Soil | | 11 | 34 | 0.73 | 144 | 0.118 | 6 | 1.60 | 0.054 | 0.09 | 0.1 | <0.01 | 6.3 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321316 | Soil | | 12 | 37 | 0.84 | 142 | 0.124 | 5 | 1.62 | 0.057 | 0.09 | 0.2 | 0.01 | 6.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321317 | Soil | | 11 | 34 | 0.93 | 146 | 0.130 | 7 | 1.56 | 0.065 | 0.07 | 0.2 | 0.02 | 6.1 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321318 | Soil | | 7 | 26 | 0.42 | 246 | 0.075 | 4 | 1.42 | 0.035 | 0.10 | <0.1 | <0.01 | 4.8 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321319 | Soil | | 9 | 41 | 0.69 | 146 | 0.115 | 4 | 1.92 | 0.040 | 0.14 | <0.1 | <0.01 | 6.5 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321320 | Soil | | 14 | 39 | 0.87 | 151 | 0.135 | 4 | 1.82 | 0.067 | 0.10 | <0.1 | 0.04 | 7.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321321 | Soil | | 0.5 | 33.9 | 4.9 | 48 | <0.1 | 30.2 | 14.5 | 408 | 3.37 | 8.2 | 0.3 | 2.5 | 2.9 | 39 | 0.1 | 0.3 | <0.1 | 77 | 0.72 | 0.021 |
| 1321322 | Soil | | 0.8 | 29.9 | 5.8 | 46 | <0.1 | 33.1 | 14.8 | 451 | 3.42 | 8.1 | 0.4 | 1.2 | 3.1 | 38 | <0.1 | 0.4 | <0.1 | 84 | 0.70 | 0.020 |
| 1321323 | Soil | | 3.6 | 32.6 | 13.7 | 49 | 0.2 | 84.8 | 13.4 | 382 | 4.52 | 75.7 | 0.4 | 10.9 | 1.9 | 25 | <0.1 | 23.1 | 0.1 | 70 | 0.25 | 0.060 |
| 1321324 | Soil | | 0.5 | 25.9 | 4.3 | 24 | 0.2 | 19.9 | 4.1 | 86 | 1.30 | 7.8 | 0.4 | 2.2 | 0.8 | 19 | 0.4 | 2.0 | <0.1 | 33 | 0.28 | 0.016 |
| 1321325 | Soil | | 1.3 | 47.6 | 9.0 | 65 | 0.3 | 90.3 | 14.3 | 323 | 3.09 | 27.6 | 0.8 | 9.2 | 1.8 | 44 | 0.6 | 8.1 | 0.1 | 60 | 0.76 | 0.062 |
| 1321326 | Soil | | 0.9 | 42.5 | 7.0 | 60 | 0.3 | 75.5 | 14.7 | 353 | 2.67 | 14.9 | 1.0 | 5.3 | 1.8 | 48 | 0.4 | 4.7 | <0.1 | 54 | 0.90 | 0.065 |
| 1321327 | Soil | | 0.9 | 38.2 | 5.7 | 63 | 0.2 | 58.0 | 13.2 | 367 | 2.48 | 12.2 | 0.7 | 5.1 | 1.5 | 53 | 0.4 | 3.2 | <0.1 | 54 | 1.05 | 0.058 |
| 1321328 | Soil | | 0.7 | 31.1 | 5.8 | 57 | 0.1 | 69.5 | 12.7 | 393 | 2.56 | 11.4 | 0.6 | 3.4 | 1.5 | 55 | 0.3 | 1.8 | <0.1 | 57 | 1.23 | 0.057 |
| 1321329 | Soil | | 0.7 | 52.9 | 5.4 | 54 | <0.1 | 51.1 | 15.7 | 418 | 2.95 | 9.8 | 0.7 | 4.2 | 2.1 | 50 | <0.1 | 0.7 | <0.1 | 85 | 1.19 | 0.051 |
| 1321330 | Soil | | 0.7 | 47.7 | 5.6 | 61 | <0.1 | 48.8 | 15.2 | 426 | 3.53 | 11.9 | 0.6 | 5.0 | 2.5 | 42 | 0.1 | 0.8 | <0.1 | 88 | 0.84 | 0.058 |
| 1321331 | Soil | | 0.7 | 39.6 | 5.6 | 49 | <0.1 | 37.3 | 11.9 | 352 | 2.60 | 7.5 | 0.9 | 6.4 | 1.6 | 49 | 0.2 | 0.6 | <0.1 | 69 | 1.07 | 0.053 |
| 1321332 | Soil | | 1.0 | 31.6 | 6.7 | 57 | <0.1 | 40.4 | 12.4 | 438 | 2.84 | 6.9 | 0.6 | 6.3 | 1.7 | 44 | <0.1 | 0.5 | <0.1 | 73 | 0.86 | 0.056 |
| 1321333 | Soil | | 0.3 | 56.2 | 11.0 | 62 | 0.2 | 41.2 | 14.3 | 427 | 3.27 | 18.2 | 0.8 | 11.7 | 4.2 | 46 | 0.1 | 0.8 | 0.1 | 82 | 0.88 | 0.075 |
| 1321334 | Soil | | 0.7 | 42.0 | 8.3 | 60 | 0.1 | 31.4 | 13.0 | 435 | 3.12 | 12.4 | 0.4 | 4.8 | 3.2 | 51 | 0.2 | 0.5 | 0.1 | 78 | 1.25 | 0.065 |
| 1321335 | Soil | | 1.0 | 42.5 | 10.7 | 60 | 0.1 | 34.2 | 13.2 | 469 | 3.13 | 11.9 | 0.5 | 7.8 | 3.2 | 62 | <0.1 | 0.7 | 0.1 | 79 | 1.68 | 0.059 |
| 1321336 | Soil | | 0.5 | 42.7 | 7.9 | 62 | <0.1 | 31.7 | 12.8 | 449 | 3.01 | 11.1 | 0.4 | 5.7 | 2.9 | 60 | <0.1 | 0.5 | 0.1 | 78 | 1.60 | 0.060 |
| 1321337 | Soil | | 0.4 | 43.1 | 7.5 | 58 | 0.1 | 31.7 | 13.1 | 511 | 3.04 | 9.0 | 0.9 | 5.4 | 2.4 | 64 | <0.1 | 0.6 | 0.1 | 77 | 1.77 | 0.071 |
| 1321338 | Soil | | 0.6 | 38.9 | 6.8 | 49 | <0.1 | 29.3 | 12.3 | 511 | 2.81 | 8.2 | 0.6 | 4.0 | 1.9 | 63 | <0.1 | 0.5 | <0.1 | 72 | 1.33 | 0.057 |
| 1321339 | Soil | | 0.5 | 42.6 | 6.7 | 58 | <0.1 | 33.4 | 13.4 | 506 | 3.17 | 9.4 | 0.4 | 7.3 | 2.7 | 61 | 0.1 | 0.5 | <0.1 | 81 | 1.89 | 0.059 |
| 1321340 | Soil | | 0.3 | 17.7 | 2.9 | 13 | <0.1 | 8.9 | 4.6 | 246 | 0.93 | 2.9 | 1.0 | 3.0 | 0.6 | 62 | <0.1 | 0.4 | <0.1 | 21 | 1.80 | 0.043 |
| 1321341 | Soil | | 0.6 | 22.6 | 4.5 | 18 | <0.1 | 13.5 | 5.0 | 415 | 1.23 | 4.0 | 0.6 | 3.6 | 0.5 | 86 | 0.1 | 0.5 | <0.1 | 26 | 1.91 | 0.082 |
| 1321342 | Soil | | 0.8 | 25.8 | 3.9 | 27 | <0.1 | 17.1 | 6.8 | 487 | 1.41 | 5.2 | 0.5 | 2.4 | 0.5 | 103 | <0.1 | 0.3 | <0.1 | 37 | 2.53 | 0.072 |
| 1321343 | Soil | | 0.4 | 46.5 | 6.5 | 54 | <0.1 | 33.8 | 13.8 | 438 | 3.07 | 5.5 | 1.0 | 3.7 | 2.1 | 57 | <0.1 | 0.5 | <0.1 | 79 | 1.21 | 0.065 |
| 1321344 | Soil | | 0.9 | 50.5 | 7.5 | 65 | 0.1 | 37.9 | 13.9 | 521 | 3.31 | 9.7 | 0.7 | 4.6 | 2.4 | 58 | <0.1 | 0.4 | 0.1 | 80 | 1.35 | 0.066 |
| 1321345 | Soil | | 0.5 | 44.5 | 7.3 | 57 | 0.1 | 34.7 | 14.9 | 486 | 3.15 | 10.5 | 0.5 | 6.8 | 2.8 | 61 | 0.1 | 0.4 | <0.1 | 84 | 1.25 | 0.058 |
| 1321346 | Soil | | 0.8 | 49.0 | 6.5 | 62 | 0.1 | 37.5 | 15.3 | 735 | 3.17 | 9.5 | 1.0 | 3.8 | 2.4 | 66 | 0.3 | 0.7 | 0.1 | 80 | 1.40 | 0.080 |
| 1321347 | Soil | | 0.8 | 47.2 | 6.0 | 63 | <0.1 | 37.1 | 14.9 | 543 | 3.42 | 6.2 | 0.4 | 4.4 | 2.3 | 79 | <0.1 | 0.4 | <0.1 | 82 | 3.43 | 0.087 |
| 1321348 | Soil | | 0.8 | 38.2 | 7.8 | 50 | <0.1 | 34.8 | 14.5 | 361 | 3.49 | 7.7 | 0.5 | 3.3 | 2.9 | 37 | <0.1 | 0.4 | <0.1 | 89 | 0.82 | 0.033 |
| 1321349 | Soil | | 0.9 | 47.9 | 7.1 | 56 | <0.1 | 44.3 | 17.7 | 515 | 3.95 | 11.2 | 0.7 | 3.2 | 3.4 | 39 | <0.1 | 0.3 | 0.1 | 101 | 0.82 | 0.040 |
| 1321350 | Soil | | 0.6 | 40.0 | 9.3 | 52 | <0.1 | 36.9 | 14.0 | 419 | 3.58 | 9.8 | 0.5 | 7.4 | 3.3 | 43 | <0.1 | 0.5 | 0.1 | 93 | 0.81 | 0.027 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321321 | Soil | | 11 | 41 | 0.78 | 123 | 0.138 | 4 | 1.88 | 0.051 | 0.12 | <0.1 | 0.02 | 7.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321322 | Soil | | 11 | 48 | 0.76 | 186 | 0.132 | 5 | 2.05 | 0.044 | 0.09 | <0.1 | 0.02 | 9.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321323 | Soil | | 10 | 98 | 0.60 | 122 | 0.065 | 4 | 1.33 | 0.023 | 0.10 | 0.1 | 0.36 | 4.2 | 1.2 | 0.16 | 6 | 0.7 | <0.2 |
| 1321324 | Soil | | 5 | 19 | 0.21 | 83 | 0.047 | 2 | 0.68 | 0.024 | 0.04 | <0.1 | 0.05 | 2.1 | 0.4 | <0.05 | 3 | 0.5 | <0.2 |
| 1321325 | Soil | | 12 | 57 | 0.61 | 165 | 0.075 | 3 | 1.68 | 0.026 | 0.05 | <0.1 | 0.46 | 5.8 | 0.8 | <0.05 | 5 | <0.5 | <0.2 |
| 1321326 | Soil | | 12 | 53 | 0.74 | 162 | 0.078 | 4 | 1.77 | 0.029 | 0.05 | 0.1 | 0.33 | 6.2 | 0.4 | <0.05 | 5 | <0.5 | <0.2 |
| 1321327 | Soil | | 10 | 45 | 0.69 | 128 | 0.086 | 3 | 1.62 | 0.034 | 0.04 | 0.1 | 0.17 | 5.5 | 0.1 | 0.05 | 4 | <0.5 | <0.2 |
| 1321328 | Soil | | 9 | 52 | 0.70 | 126 | 0.077 | 4 | 1.53 | 0.031 | 0.04 | 0.1 | 0.11 | 4.8 | 0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321329 | Soil | | 11 | 58 | 0.78 | 137 | 0.117 | 4 | 1.90 | 0.034 | 0.05 | <0.1 | 0.05 | 7.8 | <0.1 | <0.05 | 6 | 0.8 | <0.2 |
| 1321330 | Soil | | 11 | 52 | 0.84 | 134 | 0.136 | 3 | 1.98 | 0.044 | 0.05 | <0.1 | 0.02 | 8.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321331 | Soil | | 10 | 47 | 0.71 | 133 | 0.109 | 3 | 1.72 | 0.039 | 0.04 | 0.1 | 0.04 | 6.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321332 | Soil | | 10 | 57 | 0.71 | 133 | 0.094 | 3 | 1.62 | 0.030 | 0.05 | 0.2 | 0.03 | 5.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321333 | Soil | | 16 | 50 | 0.80 | 139 | 0.123 | 3 | 2.00 | 0.051 | 0.06 | <0.1 | 0.04 | 8.8 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321334 | Soil | | 13 | 38 | 0.74 | 159 | 0.136 | 3 | 1.75 | 0.056 | 0.08 | <0.1 | 0.02 | 6.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321335 | Soil | | 14 | 41 | 0.81 | 174 | 0.131 | 3 | 1.87 | 0.060 | 0.07 | <0.1 | 0.04 | 7.1 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321336 | Soil | | 13 | 39 | 0.73 | 156 | 0.131 | 2 | 1.76 | 0.059 | 0.08 | 0.1 | 0.03 | 6.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321337 | Soil | | 12 | 37 | 0.72 | 153 | 0.120 | 2 | 1.74 | 0.058 | 0.06 | 0.1 | 0.03 | 6.1 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321338 | Soil | | 11 | 35 | 0.70 | 165 | 0.108 | 4 | 1.73 | 0.055 | 0.05 | 0.1 | 0.04 | 5.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321339 | Soil | | 13 | 39 | 0.86 | 159 | 0.135 | 3 | 1.85 | 0.059 | 0.07 | <0.1 | 0.03 | 6.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321340 | Soil | | 4 | 10 | 0.20 | 75 | 0.031 | 3 | 0.49 | 0.032 | 0.02 | <0.1 | 0.04 | 1.7 | <0.1 | 0.12 | 2 | 0.5 | <0.2 |
| 1321341 | Soil | | 7 | 16 | 0.31 | 132 | 0.034 | 4 | 0.79 | 0.028 | 0.02 | <0.1 | 0.04 | 2.2 | <0.1 | 0.12 | 2 | <0.5 | <0.2 |
| 1321342 | Soil | | 4 | 17 | 0.46 | 141 | 0.045 | 5 | 0.82 | 0.029 | 0.04 | <0.1 | 0.05 | 2.9 | <0.1 | 0.12 | 2 | <0.5 | <0.2 |
| 1321343 | Soil | | 13 | 40 | 0.85 | 159 | 0.121 | 3 | 1.74 | 0.060 | 0.07 | <0.1 | 0.03 | 7.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321344 | Soil | | 14 | 42 | 0.96 | 203 | 0.123 | 4 | 1.96 | 0.062 | 0.08 | 0.1 | 0.04 | 6.8 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1321345 | Soil | | 14 | 39 | 0.85 | 218 | 0.124 | 3 | 1.96 | 0.056 | 0.07 | <0.1 | 0.03 | 7.2 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321346 | Soil | | 14 | 38 | 0.82 | 231 | 0.114 | 5 | 1.78 | 0.060 | 0.06 | 0.1 | 0.03 | 6.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321347 | Soil | | 13 | 44 | 1.09 | 140 | 0.134 | 4 | 1.73 | 0.064 | 0.10 | 0.1 | 0.03 | 7.9 | 0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321348 | Soil | | 17 | 49 | 0.78 | 133 | 0.137 | 4 | 2.08 | 0.046 | 0.10 | <0.1 | 0.03 | 10.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321349 | Soil | | 20 | 57 | 1.01 | 146 | 0.156 | 3 | 2.36 | 0.046 | 0.12 | <0.1 | <0.01 | 12.4 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321350 | Soil | | 17 | 47 | 0.83 | 168 | 0.144 | 3 | 2.07 | 0.052 | 0.08 | <0.1 | 0.01 | 9.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321351 | Soil | | 0.8 | 46.4 | 7.7 | 62 | 0.1 | 38.6 | 15.3 | 542 | 3.64 | 8.6 | 0.5 | 5.6 | 2.9 | 50 | 0.1 | 0.5 | <0.1 | 86 | 1.54 | 0.068 |
| 1321352 | Soil | | 0.7 | 52.6 | 6.2 | 60 | <0.1 | 42.0 | 15.2 | 567 | 3.37 | 7.7 | 0.4 | 1.5 | 2.2 | 81 | <0.1 | 0.4 | <0.1 | 79 | 3.95 | 0.080 |
| 1321353 | Soil | | 0.4 | 42.4 | 4.9 | 39 | <0.1 | 27.9 | 9.9 | 385 | 2.62 | 7.8 | 0.3 | 7.5 | 2.1 | 103 | 0.2 | 0.4 | <0.1 | 63 | 7.49 | 0.033 |
| 1321354 | Soil | | 1.3 | 38.2 | 10.0 | 50 | <0.1 | 39.8 | 15.8 | 353 | 3.69 | 10.6 | 0.7 | 1.0 | 3.4 | 28 | <0.1 | 0.5 | 0.1 | 90 | 0.58 | 0.016 |
| 1321355 | Soil | | 0.8 | 36.3 | 7.2 | 57 | <0.1 | 30.9 | 12.5 | 491 | 3.11 | 9.3 | 0.5 | 4.0 | 2.7 | 47 | 0.1 | 0.5 | <0.1 | 77 | 0.91 | 0.065 |
| 1321356 | Soil | | 1.1 | 26.9 | 8.9 | 46 | <0.1 | 34.5 | 12.3 | 370 | 3.24 | 7.1 | 0.5 | 3.4 | 2.5 | 36 | 0.1 | 0.4 | 0.1 | 79 | 0.73 | 0.025 |
| 1321357 | Soil | | 0.7 | 41.1 | 6.3 | 58 | <0.1 | 30.7 | 11.8 | 461 | 3.06 | 5.7 | 0.5 | 3.0 | 2.1 | 77 | <0.1 | 0.4 | <0.1 | 74 | 2.54 | 0.058 |
| 1321358 | Soil | | 0.5 | 40.8 | 6.8 | 57 | <0.1 | 31.0 | 12.4 | 465 | 3.03 | 6.6 | 0.4 | 5.2 | 2.5 | 70 | <0.1 | 0.6 | 0.1 | 77 | 2.04 | 0.068 |
| 1321359 | Soil | | 0.9 | 42.6 | 6.2 | 58 | <0.1 | 31.9 | 12.7 | 494 | 3.08 | 6.7 | 0.4 | 4.4 | 2.3 | 86 | 0.1 | 0.6 | <0.1 | 72 | 2.99 | 0.061 |
| 1321360 | Soil | | 0.6 | 44.2 | 6.8 | 63 | <0.1 | 32.1 | 12.3 | 494 | 3.16 | 6.7 | 0.4 | <0.5 | 2.1 | 84 | <0.1 | 0.5 | <0.1 | 75 | 3.68 | 0.051 |
| 1321361 | Soil | | 1.0 | 40.9 | 7.0 | 68 | <0.1 | 42.5 | 16.3 | 632 | 3.73 | 6.8 | 0.6 | 10.8 | 2.8 | 54 | 0.1 | 0.5 | <0.1 | 93 | 1.06 | 0.057 |
| 1321362 | Soil | | 0.7 | 45.4 | 6.1 | 47 | <0.1 | 32.9 | 12.7 | 539 | 2.99 | 7.9 | 1.7 | 5.6 | 2.2 | 70 | <0.1 | 0.9 | <0.1 | 75 | 1.48 | 0.055 |
| 1321363 | Soil | | 0.7 | 31.8 | 5.3 | 40 | 0.1 | 25.5 | 10.0 | 321 | 2.45 | 16.4 | 1.1 | 3.0 | 1.6 | 62 | 0.2 | 0.8 | <0.1 | 61 | 1.34 | 0.067 |
| 1321364 | Soil | | 0.7 | 27.7 | 7.2 | 48 | <0.1 | 23.9 | 12.1 | 341 | 2.99 | 157.3 | 1.4 | 24.4 | 2.2 | 58 | <0.1 | 0.8 | 0.1 | 75 | 0.97 | 0.075 |
| 1321365 | Soil | | 0.9 | 21.5 | 4.8 | 30 | <0.1 | 15.7 | 8.2 | 879 | 1.33 | 4.0 | 0.5 | 1.5 | 0.7 | 132 | 0.5 | 0.9 | <0.1 | 29 | 2.79 | 0.086 |
| 1321366 | Soil | | 0.6 | 46.1 | 9.1 | 48 | 0.1 | 38.2 | 14.8 | 540 | 3.09 | 7.5 | 1.5 | 9.8 | 3.3 | 52 | 0.1 | 0.6 | 0.1 | 75 | 1.06 | 0.045 |
| 1321367 | Soil | | 0.8 | 42.8 | 15.5 | 81 | 0.2 | 39.4 | 14.4 | 616 | 2.85 | 11.2 | 1.7 | 1.8 | 5.5 | 45 | 1.1 | 1.1 | 0.1 | 62 | 0.75 | 0.040 |
| 1321368 | Soil | | 0.9 | 28.2 | 11.2 | 51 | <0.1 | 33.1 | 14.6 | 491 | 3.36 | 10.5 | 0.7 | <0.5 | 3.7 | 40 | <0.1 | 0.6 | 0.1 | 85 | 0.73 | 0.018 |
| 1321369 | Soil | | 1.6 | 17.7 | 9.3 | 44 | <0.1 | 21.7 | 11.0 | 397 | 2.42 | 7.1 | 0.3 | <0.5 | 2.5 | 30 | 0.1 | 0.5 | 0.1 | 62 | 0.45 | 0.020 |
| 1321370 | Soil | | 1.1 | 33.9 | 19.0 | 57 | <0.1 | 34.8 | 14.8 | 534 | 3.44 | 10.2 | 0.8 | 6.2 | 5.5 | 41 | 0.2 | 0.6 | 0.1 | 80 | 0.69 | 0.041 |
| 1321371 | Soil | | 0.5 | 42.5 | 7.8 | 50 | 0.1 | 30.6 | 12.1 | 357 | 2.69 | 8.0 | 1.0 | 4.1 | 2.9 | 57 | 0.4 | 0.6 | 0.1 | 68 | 1.08 | 0.050 |
| 1321372 | Soil | | 0.5 | 43.7 | 8.3 | 54 | 0.1 | 34.6 | 15.1 | 522 | 3.09 | 8.7 | 1.0 | 1.1 | 3.2 | 57 | <0.1 | 0.6 | 0.1 | 78 | 1.03 | 0.053 |
| 1321373 | Soil | | 1.2 | 34.1 | 6.7 | 39 | 0.1 | 25.3 | 11.7 | 528 | 2.65 | 277.8 | 1.3 | 22.9 | 1.8 | 58 | 0.2 | 0.9 | 0.1 | 63 | 0.94 | 0.066 |
| 1321374 | Soil | | 0.4 | 34.2 | 6.5 | 52 | <0.1 | 31.1 | 13.9 | 536 | 3.12 | 9.7 | 0.6 | 3.6 | 2.1 | 47 | 0.1 | 0.4 | <0.1 | 79 | 1.01 | 0.077 |
| 1321375 | Soil | | 0.4 | 34.5 | 5.7 | 62 | <0.1 | 29.9 | 12.8 | 443 | 2.82 | 5.4 | 0.6 | 5.3 | 2.3 | 49 | 0.2 | 0.4 | <0.1 | 76 | 1.13 | 0.069 |
| 1321376 | Soil | | 0.5 | 36.3 | 6.9 | 57 | <0.1 | 29.2 | 12.8 | 467 | 2.68 | 4.5 | 0.9 | 1.4 | 2.3 | 47 | 0.1 | 0.4 | <0.1 | 74 | 0.96 | 0.063 |
| 1321377 | Soil | | 0.8 | 27.5 | 5.0 | 52 | <0.1 | 23.4 | 12.8 | 955 | 2.67 | 5.1 | 0.8 | 6.8 | 1.5 | 53 | 0.1 | 0.5 | <0.1 | 68 | 1.25 | 0.069 |
| 1321378 | Soil | | 0.5 | 32.9 | 5.3 | 56 | <0.1 | 27.9 | 12.2 | 315 | 2.74 | 4.2 | 0.8 | 1.2 | 2.4 | 47 | <0.1 | 0.3 | 0.1 | 79 | 1.09 | 0.065 |
| 1321379 | Soil | | 0.3 | 32.0 | 5.3 | 52 | <0.1 | 27.4 | 11.3 | 367 | 2.61 | 4.3 | 0.7 | 4.2 | 1.8 | 49 | <0.1 | 0.4 | <0.1 | 70 | 1.21 | 0.058 |
| 1321380 | Soil | | 0.3 | 27.8 | 5.3 | 56 | <0.1 | 26.9 | 12.7 | 370 | 2.69 | 4.7 | 0.7 | 4.1 | 2.1 | 47 | 0.1 | 0.4 | <0.1 | 73 | 1.05 | 0.064 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321351 | Soil | | 14 | 45 | 0.92 | 168 | 0.138 | 4 | 1.99 | 0.056 | 0.07 | 0.2 | 0.03 | 9.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321352 | Soil | | 12 | 41 | 1.12 | 114 | 0.132 | 4 | 1.69 | 0.059 | 0.09 | <0.1 | 0.05 | 7.6 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321353 | Soil | | 19 | 29 | 0.81 | 96 | 0.091 | 2 | 1.47 | 0.031 | 0.04 | 0.1 | 0.05 | 6.9 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321354 | Soil | | 12 | 50 | 0.75 | 136 | 0.127 | 3 | 2.41 | 0.032 | 0.06 | 0.1 | 0.02 | 10.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321355 | Soil | | 11 | 35 | 0.78 | 168 | 0.111 | 2 | 1.71 | 0.053 | 0.06 | 0.1 | 0.01 | 5.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321356 | Soil | | 8 | 42 | 0.64 | 122 | 0.115 | 2 | 2.06 | 0.034 | 0.08 | <0.1 | 0.01 | 6.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321357 | Soil | | 11 | 35 | 0.87 | 151 | 0.120 | 2 | 1.67 | 0.059 | 0.07 | 0.1 | 0.03 | 6.1 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321358 | Soil | | 12 | 36 | 0.92 | 147 | 0.126 | 2 | 1.67 | 0.060 | 0.06 | 0.1 | 0.02 | 5.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321359 | Soil | | 12 | 34 | 0.91 | 169 | 0.117 | 2 | 1.68 | 0.061 | 0.06 | 0.1 | 0.03 | 5.9 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321360 | Soil | | 12 | 35 | 0.91 | 165 | 0.117 | 3 | 1.64 | 0.064 | 0.05 | <0.1 | 0.03 | 5.7 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321361 | Soil | | 15 | 45 | 1.03 | 164 | 0.143 | 2 | 2.10 | 0.069 | 0.07 | <0.1 | <0.01 | 9.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321362 | Soil | | 11 | 36 | 0.76 | 196 | 0.105 | 3 | 1.81 | 0.048 | 0.05 | <0.1 | 0.04 | 6.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321363 | Soil | | 10 | 31 | 0.55 | 251 | 0.084 | 1 | 1.47 | 0.040 | 0.04 | 0.1 | 0.05 | 5.1 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321364 | Soil | | 12 | 34 | 0.59 | 202 | 0.096 | <1 | 1.74 | 0.036 | 0.04 | 0.2 | 0.05 | 6.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321365 | Soil | | 6 | 15 | 0.38 | 180 | 0.032 | 4 | 0.78 | 0.025 | 0.03 | <0.1 | 0.07 | 2.3 | <0.1 | 0.10 | 2 | 0.7 | <0.2 |
| 1321366 | Soil | | 14 | 41 | 0.66 | 186 | 0.117 | 1 | 1.87 | 0.037 | 0.05 | <0.1 | 0.06 | 7.1 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321367 | Soil | | 21 | 38 | 0.68 | 135 | 0.092 | <1 | 1.95 | 0.034 | 0.05 | <0.1 | 0.04 | 6.7 | <0.1 | <0.05 | 5 | 0.7 | <0.2 |
| 1321368 | Soil | | 15 | 50 | 0.66 | 161 | 0.100 | <1 | 2.16 | 0.029 | 0.05 | <0.1 | 0.05 | 9.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321369 | Soil | | 9 | 30 | 0.46 | 180 | 0.067 | <1 | 1.46 | 0.023 | 0.05 | <0.1 | 0.02 | 3.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321370 | Soil | | 17 | 51 | 0.72 | 164 | 0.124 | <1 | 2.21 | 0.036 | 0.07 | <0.1 | 0.01 | 9.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321371 | Soil | | 14 | 35 | 0.63 | 174 | 0.106 | 2 | 1.82 | 0.043 | 0.06 | <0.1 | 0.05 | 6.4 | <0.1 | <0.05 | 5 | 0.5 | <0.2 |
| 1321372 | Soil | | 14 | 40 | 0.68 | 191 | 0.120 | <1 | 1.94 | 0.040 | 0.05 | 0.1 | 0.05 | 7.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321373 | Soil | | 10 | 29 | 0.48 | 205 | 0.072 | <1 | 1.35 | 0.033 | 0.03 | 0.1 | 0.03 | 5.1 | <0.1 | <0.05 | 4 | 0.6 | <0.2 |
| 1321374 | Soil | | 11 | 37 | 0.69 | 174 | 0.112 | 1 | 1.66 | 0.046 | 0.05 | <0.1 | 0.02 | 6.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321375 | Soil | | 12 | 36 | 0.73 | 162 | 0.116 | 2 | 1.72 | 0.046 | 0.06 | 0.1 | 0.03 | 5.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321376 | Soil | | 12 | 36 | 0.71 | 159 | 0.112 | 2 | 1.64 | 0.044 | 0.05 | <0.1 | 0.03 | 5.8 | <0.1 | <0.05 | 5 | 0.5 | <0.2 |
| 1321377 | Soil | | 10 | 30 | 0.58 | 181 | 0.087 | 2 | 1.51 | 0.037 | 0.04 | <0.1 | 0.03 | 4.9 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321378 | Soil | | 11 | 33 | 0.70 | 167 | 0.123 | 1 | 1.72 | 0.045 | 0.06 | 0.1 | 0.03 | 5.6 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321379 | Soil | | 10 | 32 | 0.65 | 169 | 0.103 | 1 | 1.60 | 0.047 | 0.05 | <0.1 | 0.03 | 5.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321380 | Soil | | 11 | 33 | 0.64 | 166 | 0.105 | 2 | 1.52 | 0.038 | 0.05 | 0.1 | 0.02 | 5.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321381 | Soil | | 0.6 | 27.8 | 5.0 | 56 | <0.1 | 24.6 | 11.2 | 456 | 2.58 | 5.0 | 0.7 | 1.2 | 1.8 | 54 | 0.1 | 0.4 | <0.1 | 70 | 1.19 | 0.066 |
| 1321382 | Soil | | 0.5 | 31.8 | 5.2 | 53 | <0.1 | 24.4 | 10.7 | 292 | 2.30 | 4.0 | 0.9 | 2.6 | 1.7 | 57 | 0.2 | 0.4 | <0.1 | 66 | 1.65 | 0.058 |
| 1321383 | Soil | | 0.7 | 27.3 | 5.6 | 58 | <0.1 | 26.7 | 13.1 | 425 | 2.89 | 4.7 | 0.7 | 3.3 | 2.1 | 48 | 0.1 | 0.4 | <0.1 | 78 | 1.13 | 0.044 |
| 1321384 | Soil | | 0.5 | 38.5 | 5.6 | 52 | <0.1 | 30.9 | 12.6 | 395 | 2.78 | 4.2 | 1.1 | 10.5 | 2.4 | 56 | 0.2 | 0.5 | <0.1 | 78 | 1.43 | 0.061 |
| 1321385 | Soil | | 0.6 | 26.4 | 5.6 | 54 | <0.1 | 22.5 | 9.9 | 271 | 2.47 | 4.4 | 0.9 | 4.6 | 1.9 | 44 | <0.1 | 0.5 | <0.1 | 72 | 0.98 | 0.050 |
| 1321386 | Soil | | 1.1 | 24.8 | 6.5 | 91 | 0.2 | 27.1 | 11.1 | 520 | 2.41 | 8.4 | 0.8 | 13.2 | 2.1 | 59 | 0.5 | 1.1 | <0.1 | 64 | 1.18 | 0.085 |
| 1321387 | Soil | | 0.8 | 29.7 | 6.2 | 49 | <0.1 | 25.9 | 11.6 | 415 | 2.89 | 10.0 | 0.6 | 3.0 | 2.5 | 46 | 0.2 | 0.5 | 0.1 | 83 | 0.73 | 0.058 |
| 1321388 | Soil | | 0.5 | 31.4 | 5.6 | 59 | <0.1 | 26.7 | 12.0 | 322 | 2.84 | 13.2 | 0.6 | 4.0 | 2.7 | 47 | 0.2 | 0.5 | 0.1 | 75 | 0.88 | 0.075 |
| 1321389 | Soil | | 0.9 | 20.9 | 8.5 | 59 | <0.1 | 23.5 | 13.5 | 648 | 2.44 | 14.3 | 0.7 | 5.4 | 2.9 | 42 | 0.1 | 0.6 | 0.1 | 62 | 0.74 | 0.060 |
| 1321390 | Soil | | 0.7 | 33.6 | 8.6 | 56 | <0.1 | 26.5 | 11.6 | 298 | 2.52 | 11.8 | 0.9 | 5.2 | 2.9 | 49 | 0.2 | 0.6 | 0.1 | 63 | 0.79 | 0.061 |
| 1321391 | Soil | | 0.7 | 43.8 | 5.0 | 57 | <0.1 | 33.0 | 12.7 | 486 | 2.86 | 7.6 | 0.6 | 5.7 | 2.5 | 78 | 0.2 | 0.5 | 0.1 | 76 | 2.08 | 0.094 |
| 1321392 | Soil | | 0.6 | 24.3 | 9.6 | 55 | <0.1 | 21.6 | 9.5 | 305 | 2.31 | 9.7 | 0.7 | 3.8 | 3.0 | 40 | 0.1 | 0.3 | 0.1 | 60 | 0.60 | 0.056 |
| 1321393 | Soil | | 0.6 | 28.8 | 8.3 | 53 | <0.1 | 22.6 | 11.3 | 399 | 2.45 | 8.2 | 0.8 | 4.8 | 2.5 | 40 | 0.2 | 0.4 | 0.1 | 64 | 0.67 | 0.056 |
| 1321394 | Soil | | 0.7 | 30.9 | 10.1 | 57 | <0.1 | 24.9 | 10.8 | 330 | 2.78 | 11.4 | 0.9 | 6.4 | 3.5 | 37 | 0.1 | 0.4 | 0.1 | 71 | 0.60 | 0.057 |
| 1321395 | Soil | | 0.6 | 32.1 | 9.3 | 55 | <0.1 | 26.5 | 10.7 | 311 | 2.81 | 6.7 | 0.9 | 3.3 | 3.5 | 42 | 0.1 | 0.5 | 0.1 | 67 | 0.68 | 0.059 |
| 1321396 | Soil | | 0.7 | 34.4 | 12.0 | 56 | 0.1 | 27.8 | 12.1 | 429 | 2.68 | 8.6 | 0.9 | 5.3 | 3.2 | 43 | 0.1 | 0.5 | 0.1 | 67 | 0.77 | 0.056 |
| 1321397 | Soil | | 0.5 | 38.7 | 9.1 | 60 | 0.1 | 30.8 | 12.6 | 458 | 2.98 | 25.0 | 0.9 | 13.7 | 3.4 | 50 | 0.2 | 0.6 | 0.1 | 78 | 0.89 | 0.070 |
| 1321398 | Soil | | 0.6 | 44.1 | 12.6 | 54 | 0.1 | 30.9 | 13.7 | 592 | 2.60 | 10.1 | 1.2 | 6.3 | 3.0 | 44 | 0.1 | 0.6 | 0.1 | 68 | 0.85 | 0.063 |
| 1321399 | Soil | | 0.6 | 34.9 | 9.5 | 56 | 0.1 | 30.0 | 11.5 | 424 | 2.62 | 21.2 | 1.0 | 11.0 | 2.9 | 42 | 0.2 | 0.6 | 0.1 | 65 | 0.74 | 0.061 |
| 1321400 | Soil | | 0.8 | 25.2 | 9.4 | 62 | 0.1 | 23.7 | 11.9 | 440 | 2.76 | 10.7 | 0.7 | 6.1 | 2.8 | 40 | 0.1 | 0.6 | <0.1 | 74 | 0.63 | 0.062 |
| 1321401 | Soil | | 0.6 | 22.5 | 8.5 | 55 | <0.1 | 19.8 | 9.8 | 325 | 2.44 | 5.9 | 0.7 | 3.6 | 2.5 | 37 | 0.1 | 0.3 | <0.1 | 62 | 0.63 | 0.054 |
| 1321402 | Soil | | 0.9 | 24.7 | 9.0 | 57 | <0.1 | 22.0 | 11.7 | 428 | 2.68 | 9.0 | 0.6 | 4.3 | 2.3 | 38 | 0.1 | 0.4 | <0.1 | 68 | 0.59 | 0.045 |
| 1321403 | Soil | | 0.6 | 24.9 | 5.5 | 62 | <0.1 | 23.7 | 11.4 | 515 | 2.73 | 7.1 | 0.6 | 4.1 | 2.2 | 52 | 0.2 | 0.4 | <0.1 | 80 | 0.88 | 0.071 |
| 1321404 | Soil | | 0.5 | 22.4 | 6.0 | 55 | <0.1 | 22.3 | 11.0 | 339 | 2.45 | 6.8 | 0.6 | 11.8 | 2.3 | 47 | 0.2 | 0.4 | <0.1 | 68 | 0.77 | 0.064 |
| 1321405 | Soil | | 0.5 | 28.7 | 5.0 | 62 | <0.1 | 26.6 | 11.6 | 297 | 2.73 | 7.9 | 0.6 | 3.6 | 2.3 | 47 | 0.2 | 0.4 | <0.1 | 77 | 0.94 | 0.078 |
| 1321406 | Soil | | 0.5 | 37.4 | 5.6 | 64 | <0.1 | 31.9 | 13.7 | 469 | 3.33 | 11.0 | 0.5 | 4.3 | 2.5 | 61 | 0.2 | 0.4 | <0.1 | 87 | 1.37 | 0.082 |
| 1321407 | Soil | | 1.2 | 24.6 | 10.8 | 49 | 0.2 | 17.8 | 9.7 | 392 | 2.38 | 15.1 | 0.5 | 2.2 | 1.6 | 18 | 0.2 | 0.4 | 0.1 | 61 | 0.24 | 0.023 |
| 1321408 | Soil | | 1.5 | 46.0 | 17.4 | 61 | 0.3 | 34.3 | 16.0 | 843 | 3.73 | 22.8 | 1.0 | 11.2 | 2.8 | 48 | 0.2 | 0.6 | 0.2 | 78 | 0.69 | 0.049 |
| 1321409 | Soil | | 1.1 | 17.3 | 14.0 | 53 | <0.1 | 24.3 | 10.9 | 352 | 3.14 | 12.8 | 0.5 | 12.5 | 4.4 | 29 | <0.1 | 0.5 | 0.1 | 79 | 0.35 | 0.018 |
| 1321410 | Soil | | 0.5 | 33.9 | 16.5 | 47 | 0.2 | 27.0 | 10.3 | 633 | 2.60 | 13.3 | 0.8 | 8.0 | 4.3 | 55 | 0.2 | 0.7 | 0.1 | 49 | 1.13 | 0.043 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321381 | Soil | | 10 | 31 | 0.63 | 154 | 0.101 | 2 | 1.51 | 0.045 | 0.05 | 0.1 | 0.06 | 4.8 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321382 | Soil | | 11 | 32 | 0.63 | 137 | 0.097 | 4 | 1.31 | 0.041 | 0.05 | <0.1 | 0.06 | 5.1 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321383 | Soil | | 11 | 39 | 0.79 | 142 | 0.124 | 2 | 1.61 | 0.045 | 0.06 | 0.1 | 0.05 | 6.1 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321384 | Soil | | 12 | 38 | 0.71 | 157 | 0.116 | 3 | 1.60 | 0.042 | 0.05 | 0.1 | 0.02 | 6.6 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321385 | Soil | | 11 | 33 | 0.64 | 159 | 0.100 | <1 | 1.70 | 0.039 | 0.04 | <0.1 | 0.03 | 5.2 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321386 | Soil | | 10 | 33 | 0.60 | 215 | 0.087 | 1 | 1.40 | 0.037 | 0.04 | <0.1 | 0.04 | 4.7 | <0.1 | <0.05 | 4 | 1.0 | <0.2 |
| 1321387 | Soil | | 11 | 36 | 0.70 | 157 | 0.117 | 2 | 1.85 | 0.049 | 0.04 | 0.1 | 0.03 | 5.2 | <0.1 | <0.05 | 5 | 0.6 | <0.2 |
| 1321388 | Soil | | 11 | 36 | 0.76 | 131 | 0.127 | 3 | 1.61 | 0.061 | 0.06 | 0.1 | 0.02 | 5.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321389 | Soil | | 11 | 34 | 0.58 | 176 | 0.099 | 3 | 1.56 | 0.039 | 0.05 | 0.1 | 0.04 | 4.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321390 | Soil | | 13 | 35 | 0.60 | 197 | 0.100 | 2 | 1.67 | 0.045 | 0.05 | 0.1 | 0.04 | 5.1 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321391 | Soil | | 11 | 37 | 0.96 | 132 | 0.131 | 7 | 1.48 | 0.081 | 0.08 | 0.1 | 0.02 | 4.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321392 | Soil | | 11 | 34 | 0.55 | 160 | 0.106 | 2 | 1.69 | 0.039 | 0.04 | 0.1 | 0.03 | 4.6 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321393 | Soil | | 11 | 32 | 0.56 | 172 | 0.100 | 2 | 1.69 | 0.039 | 0.05 | 0.1 | 0.03 | 4.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321394 | Soil | | 13 | 38 | 0.58 | 180 | 0.112 | 2 | 1.91 | 0.036 | 0.04 | 0.2 | 0.03 | 5.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321395 | Soil | | 13 | 39 | 0.61 | 168 | 0.119 | 3 | 1.94 | 0.043 | 0.04 | 0.1 | 0.03 | 5.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321396 | Soil | | 13 | 41 | 0.69 | 170 | 0.119 | 3 | 2.32 | 0.044 | 0.05 | 0.1 | 0.03 | 6.1 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321397 | Soil | | 13 | 43 | 0.75 | 148 | 0.136 | 3 | 1.93 | 0.050 | 0.07 | <0.1 | 0.04 | 5.8 | <0.1 | <0.05 | 5 | 0.5 | <0.2 |
| 1321398 | Soil | | 15 | 44 | 0.67 | 178 | 0.105 | 2 | 2.12 | 0.040 | 0.04 | <0.1 | 0.05 | 7.1 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321399 | Soil | | 14 | 42 | 0.65 | 181 | 0.103 | 2 | 2.03 | 0.037 | 0.05 | 0.1 | 0.04 | 5.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321400 | Soil | | 12 | 40 | 0.57 | 151 | 0.107 | 2 | 1.71 | 0.034 | 0.05 | 0.1 | 0.03 | 4.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321401 | Soil | | 11 | 36 | 0.55 | 149 | 0.102 | 2 | 1.71 | 0.036 | 0.05 | 0.1 | 0.03 | 4.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321402 | Soil | | 10 | 35 | 0.58 | 180 | 0.101 | 2 | 1.79 | 0.039 | 0.04 | <0.1 | 0.02 | 4.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321403 | Soil | | 10 | 35 | 0.68 | 151 | 0.124 | 2 | 1.73 | 0.062 | 0.06 | 0.1 | 0.03 | 4.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321404 | Soil | | 10 | 33 | 0.60 | 135 | 0.111 | 3 | 1.63 | 0.048 | 0.05 | 0.1 | 0.02 | 4.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321405 | Soil | | 11 | 35 | 0.72 | 131 | 0.128 | 2 | 1.58 | 0.067 | 0.06 | 0.1 | 0.02 | 4.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321406 | Soil | | 12 | 38 | 0.83 | 145 | 0.134 | 3 | 1.65 | 0.070 | 0.05 | 0.1 | 0.02 | 5.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321407 | Soil | | 9 | 26 | 0.41 | 135 | 0.073 | 2 | 1.54 | 0.031 | 0.07 | <0.1 | 0.02 | 2.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321408 | Soil | | 18 | 42 | 0.62 | 168 | 0.065 | 3 | 2.46 | 0.024 | 0.09 | 0.3 | 0.03 | 5.1 | <0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1321409 | Soil | | 15 | 42 | 0.62 | 113 | 0.101 | 3 | 2.11 | 0.020 | 0.10 | <0.1 | 0.02 | 3.8 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321410 | Soil | | 21 | 31 | 0.42 | 163 | 0.063 | 2 | 1.50 | 0.038 | 0.07 | <0.1 | 0.04 | 5.5 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321411 | Soil | | 0.7 | 26.7 | 8.7 | 30 | 0.2 | 14.7 | 8.6 | 476 | 1.85 | 34.7 | 0.6 | 11.9 | 1.1 | 52 | 0.2 | 0.5 | 0.1 | 43 | 1.13 | 0.041 |
| 1321412 | Soil | | 3.2 | 39.1 | 10.0 | 97 | 0.5 | 41.5 | 14.3 | 565 | 3.58 | 21.6 | 0.9 | 12.6 | 4.2 | 62 | 0.3 | 2.8 | 0.1 | 76 | 0.94 | 0.068 |
| 1321413 | Soil | | 3.6 | 55.9 | 12.4 | 153 | 0.5 | 53.8 | 17.8 | 1084 | 3.61 | 28.7 | 1.1 | 16.0 | 3.6 | 68 | 0.8 | 3.5 | 0.2 | 74 | 1.08 | 0.078 |
| 1321414 | Soil | | 2.3 | 37.1 | 13.3 | 164 | 1.1 | 33.6 | 11.6 | 681 | 2.95 | 19.4 | 1.7 | 2.8 | 4.7 | 96 | 2.0 | 2.3 | 0.2 | 86 | 0.99 | 0.146 |
| 1321415 | Soil | | 2.2 | 79.5 | 8.4 | 92 | 0.4 | 36.3 | 14.3 | 1451 | 3.01 | 33.9 | 1.7 | 14.7 | 2.6 | 57 | 1.6 | 1.5 | 0.1 | 71 | 0.72 | 0.058 |
| 1321416 | Soil | | 5.8 | 47.3 | 14.0 | 139 | 0.4 | 46.8 | 16.6 | 523 | 3.28 | 17.7 | 0.9 | 3.3 | 5.8 | 75 | 0.6 | 3.9 | 0.2 | 44 | 1.24 | 0.151 |
| 1321417 | Soil | | 7.2 | 48.6 | 14.6 | 160 | 0.2 | 57.0 | 17.7 | 744 | 3.41 | 14.9 | 1.1 | 0.8 | 7.3 | 35 | 0.7 | 2.9 | 0.2 | 31 | 0.50 | 0.139 |
| 1321418 | Soil | | 1.9 | 34.1 | 10.1 | 93 | 0.3 | 35.1 | 13.3 | 516 | 3.17 | 9.0 | 0.5 | 1.1 | 3.6 | 101 | 0.6 | 0.8 | 0.1 | 68 | 1.89 | 0.139 |
| 1321419 | Soil | | 3.6 | 41.7 | 15.5 | 121 | <0.1 | 45.4 | 17.2 | 389 | 3.82 | 11.4 | 0.9 | 1.3 | 7.5 | 43 | 0.3 | 1.7 | 0.2 | 48 | 0.57 | 0.144 |
| 1321420 | Soil | | 3.4 | 36.7 | 11.6 | 96 | 0.1 | 28.0 | 14.4 | 509 | 3.56 | 8.8 | 0.4 | 7.1 | 2.6 | 29 | 0.3 | 1.0 | 0.2 | 91 | 0.25 | 0.041 |
| 1321421 | Soil | | 2.8 | 34.8 | 9.8 | 101 | 0.3 | 38.0 | 15.5 | 1034 | 3.90 | 17.2 | 0.5 | 5.1 | 2.9 | 38 | 0.5 | 1.2 | 0.1 | 104 | 0.56 | 0.035 |
| 1321422 | Soil | | 3.1 | 22.8 | 10.2 | 81 | 0.5 | 22.9 | 10.3 | 434 | 3.78 | 12.4 | 0.4 | 2.3 | 1.9 | 18 | 1.0 | 0.6 | 0.1 | 94 | 0.19 | 0.081 |
| 1321423 | Soil | | 1.4 | 49.8 | 8.4 | 61 | <0.1 | 36.1 | 12.9 | 863 | 3.09 | 10.5 | 0.5 | 4.7 | 3.7 | 33 | 0.2 | 0.8 | 0.2 | 83 | 0.38 | 0.017 |
| 1321424 | Soil | | 0.9 | 83.6 | 13.9 | 63 | <0.1 | 30.6 | 13.7 | 1118 | 2.80 | 9.4 | 1.1 | 5.7 | 2.1 | 67 | 0.2 | 0.4 | 0.2 | 63 | 0.75 | 0.103 |
| 1321425 | Soil | | 0.6 | 57.0 | 7.1 | 67 | 0.1 | 32.8 | 13.1 | 978 | 2.96 | 7.6 | 0.4 | 6.7 | 2.9 | 55 | <0.1 | 0.5 | 0.1 | 77 | 0.90 | 0.097 |
| 1321426 | Soil | | 0.7 | 49.9 | 6.5 | 53 | <0.1 | 32.6 | 10.8 | 469 | 2.91 | 10.0 | 0.7 | 4.1 | 3.3 | 45 | 0.1 | 0.6 | 0.1 | 79 | 0.69 | 0.024 |
| 1321427 | Soil | | 1.1 | 19.4 | 6.8 | 88 | 0.4 | 24.9 | 9.6 | 1209 | 2.15 | 5.6 | 0.3 | 3.7 | 1.0 | 31 | 0.3 | 0.6 | 0.2 | 56 | 0.36 | 0.042 |
| 1321428 | Soil | | 0.3 | 42.0 | 5.3 | 59 | <0.1 | 31.1 | 11.7 | 464 | 2.83 | 7.0 | 0.5 | 3.3 | 2.3 | 61 | 0.2 | 0.4 | <0.1 | 75 | 1.60 | 0.073 |
| 1321429 | Soil | | 0.4 | 34.8 | 5.2 | 53 | <0.1 | 28.1 | 11.5 | 492 | 2.74 | 5.8 | 0.9 | 3.4 | 2.4 | 64 | 0.1 | 0.3 | <0.1 | 67 | 1.51 | 0.056 |
| 1321430 | Soil | | 0.7 | 28.4 | 5.3 | 47 | <0.1 | 22.6 | 11.5 | 433 | 2.49 | 5.9 | 0.9 | 2.6 | 2.2 | 58 | <0.1 | 0.5 | <0.1 | 68 | 1.14 | 0.059 |
| 1321431 | Soil | | 0.9 | 25.0 | 4.8 | 56 | <0.1 | 22.1 | 11.0 | 535 | 2.40 | 4.2 | 0.7 | 5.7 | 1.6 | 56 | 0.1 | 0.3 | <0.1 | 64 | 1.20 | 0.062 |
| 1321432 | Soil | | 0.6 | 34.3 | 4.8 | 55 | <0.1 | 28.2 | 11.6 | 481 | 2.72 | 7.4 | 0.5 | 3.8 | 2.8 | 74 | 0.1 | 0.5 | <0.1 | 74 | 2.33 | 0.085 |
| 1321433 | Soil | | 0.7 | 28.8 | 4.8 | 53 | <0.1 | 20.9 | 10.7 | 482 | 2.28 | 4.8 | 0.8 | <0.5 | 1.8 | 57 | 0.2 | 0.4 | 0.1 | 62 | 1.40 | 0.056 |
| 1321434 | Soil | | 0.4 | 35.6 | 5.1 | 54 | <0.1 | 26.4 | 10.8 | 409 | 2.53 | 4.7 | 0.8 | 2.6 | 2.1 | 56 | 0.2 | 0.3 | <0.1 | 70 | 1.28 | 0.061 |
| 1321435 | Soil | | 0.5 | 29.9 | 4.5 | 47 | <0.1 | 23.7 | 10.0 | 432 | 2.44 | 5.0 | 0.7 | 3.5 | 2.0 | 59 | 0.2 | 0.5 | <0.1 | 61 | 1.30 | 0.060 |
| 1321436 | Soil | | 0.3 | 16.8 | 1.8 | 23 | <0.1 | 11.1 | 4.2 | 255 | 0.93 | 2.1 | 0.4 | 2.2 | 0.6 | 61 | 0.3 | 0.2 | <0.1 | 20 | 2.06 | 0.041 |
| 1321437 | Soil | | 0.5 | 33.4 | 5.5 | 55 | <0.1 | 39.2 | 15.5 | 395 | 3.39 | 5.9 | 0.4 | 15.6 | 2.4 | 44 | 0.1 | 0.4 | 0.1 | 86 | 1.03 | 0.061 |
| 1321438 | Soil | | 1.4 | 26.7 | 6.6 | 61 | <0.1 | 33.3 | 14.4 | 578 | 3.48 | 7.6 | 0.4 | 0.8 | 2.1 | 32 | <0.1 | 0.4 | <0.1 | 93 | 0.64 | 0.055 |
| 1321439 | Soil | | 1.4 | 22.6 | 8.3 | 57 | 0.1 | 33.2 | 15.0 | 292 | 3.78 | 7.4 | 0.4 | <0.5 | 2.3 | 25 | 0.1 | 0.5 | 0.1 | 105 | 0.37 | 0.014 |
| 1321440 | Soil | | 0.6 | 40.3 | 5.4 | 57 | <0.1 | 28.3 | 11.9 | 469 | 2.86 | 7.6 | 0.4 | 4.9 | 3.0 | 74 | 0.3 | 0.4 | 0.1 | 77 | 2.64 | 0.069 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321411 | Soil | | 8 | 22 | 0.34 | 168 | 0.049 | 2 | 1.23 | 0.043 | 0.07 | <0.1 | 0.02 | 3.3 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321412 | Soil | | 19 | 38 | 0.71 | 304 | 0.093 | 2 | 1.84 | 0.049 | 0.07 | <0.1 | 0.06 | 8.3 | <0.1 | <0.05 | 5 | 0.6 | <0.2 |
| 1321413 | Soil | | 17 | 39 | 0.67 | 438 | 0.069 | 2 | 1.97 | 0.045 | 0.08 | 0.1 | 0.06 | 7.1 | 0.1 | <0.05 | 5 | 1.4 | <0.2 |
| 1321414 | Soil | | 15 | 34 | 0.62 | 473 | 0.074 | 3 | 1.88 | 0.042 | 0.11 | 0.1 | 0.05 | 5.6 | 0.2 | <0.05 | 5 | 1.4 | <0.2 |
| 1321415 | Soil | | 16 | 34 | 0.57 | 502 | 0.075 | 2 | 1.86 | 0.032 | 0.08 | <0.1 | 0.03 | 5.3 | <0.1 | <0.05 | 6 | 1.1 | <0.2 |
| 1321416 | Soil | | 20 | 25 | 0.65 | 255 | 0.036 | 1 | 1.51 | 0.021 | 0.09 | <0.1 | 0.05 | 5.3 | 0.1 | <0.05 | 4 | 1.6 | <0.2 |
| 1321417 | Soil | | 27 | 22 | 0.74 | 286 | 0.017 | 1 | 1.41 | 0.010 | 0.09 | <0.1 | 0.08 | 6.3 | 0.1 | <0.05 | 3 | 0.9 | <0.2 |
| 1321418 | Soil | | 15 | 34 | 0.66 | 271 | 0.068 | 2 | 1.99 | 0.026 | 0.06 | <0.1 | 0.05 | 5.5 | 0.1 | <0.05 | 5 | 0.7 | <0.2 |
| 1321419 | Soil | | 28 | 34 | 1.12 | 661 | 0.008 | 1 | 2.46 | 0.011 | 0.09 | <0.1 | 0.02 | 5.6 | 0.2 | <0.05 | 6 | 0.7 | <0.2 |
| 1321420 | Soil | | 10 | 40 | 0.52 | 375 | 0.064 | 2 | 2.45 | 0.024 | 0.07 | <0.1 | 0.01 | 3.8 | 0.2 | <0.05 | 8 | <0.5 | <0.2 |
| 1321421 | Soil | | 11 | 50 | 0.63 | 588 | 0.092 | <1 | 2.81 | 0.027 | 0.05 | <0.1 | 0.02 | 6.4 | 0.2 | <0.05 | 9 | <0.5 | <0.2 |
| 1321422 | Soil | | 7 | 36 | 0.44 | 189 | 0.084 | 2 | 1.97 | 0.018 | 0.06 | 0.1 | 0.03 | 3.1 | 0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1321423 | Soil | | 11 | 43 | 0.69 | 413 | 0.108 | 4 | 2.26 | 0.024 | 0.06 | <0.1 | 0.02 | 6.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321424 | Soil | | 12 | 32 | 0.68 | 297 | 0.077 | 5 | 1.59 | 0.046 | 0.06 | <0.1 | 0.03 | 5.4 | <0.1 | 0.07 | 5 | 0.8 | <0.2 |
| 1321425 | Soil | | 12 | 35 | 0.77 | 188 | 0.120 | 4 | 1.66 | 0.063 | 0.06 | <0.1 | <0.01 | 6.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321426 | Soil | | 15 | 40 | 0.71 | 280 | 0.128 | 2 | 1.69 | 0.057 | 0.06 | <0.1 | 0.03 | 7.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321427 | Soil | | 6 | 24 | 0.34 | 236 | 0.058 | 1 | 1.37 | 0.029 | 0.05 | <0.1 | 0.03 | 2.4 | <0.1 | 0.07 | 5 | 1.0 | <0.2 |
| 1321428 | Soil | | 11 | 34 | 0.76 | 175 | 0.124 | 5 | 1.57 | 0.065 | 0.07 | <0.1 | 0.03 | 5.7 | <0.1 | 0.08 | 4 | 0.6 | <0.2 |
| 1321429 | Soil | | 11 | 34 | 0.67 | 186 | 0.108 | 4 | 1.64 | 0.054 | 0.06 | 0.1 | 0.02 | 5.6 | <0.1 | 0.05 | 5 | 0.9 | <0.2 |
| 1321430 | Soil | | 10 | 32 | 0.63 | 179 | 0.107 | 2 | 1.74 | 0.047 | 0.05 | <0.1 | 0.04 | 5.3 | <0.1 | <0.05 | 5 | 0.7 | <0.2 |
| 1321431 | Soil | | 10 | 31 | 0.61 | 141 | 0.103 | 4 | 1.52 | 0.051 | 0.05 | <0.1 | 0.05 | 4.8 | <0.1 | 0.07 | 5 | <0.5 | <0.2 |
| 1321432 | Soil | | 11 | 34 | 0.92 | 117 | 0.120 | 4 | 1.41 | 0.061 | 0.08 | 0.1 | 0.02 | 5.1 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321433 | Soil | | 10 | 30 | 0.63 | 153 | 0.103 | 5 | 1.52 | 0.051 | 0.06 | 0.1 | 0.06 | 5.4 | <0.1 | 0.06 | 4 | 0.5 | <0.2 |
| 1321434 | Soil | | 11 | 33 | 0.64 | 160 | 0.121 | 3 | 1.64 | 0.054 | 0.06 | 0.2 | 0.03 | 5.1 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321435 | Soil | | 10 | 29 | 0.58 | 153 | 0.103 | 3 | 1.43 | 0.049 | 0.05 | <0.1 | 0.02 | 5.0 | <0.1 | 0.05 | 4 | 1.0 | <0.2 |
| 1321436 | Soil | | 4 | 12 | 0.31 | 95 | 0.037 | 5 | 0.60 | 0.023 | 0.03 | <0.1 | 0.04 | 2.2 | <0.1 | 0.09 | 2 | 0.6 | <0.2 |
| 1321437 | Soil | | 9 | 47 | 0.92 | 170 | 0.137 | 3 | 2.10 | 0.058 | 0.08 | 0.1 | 0.03 | 7.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321438 | Soil | | 8 | 47 | 0.74 | 198 | 0.122 | 3 | 2.28 | 0.037 | 0.10 | <0.1 | 0.02 | 6.1 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321439 | Soil | | 7 | 50 | 0.72 | 175 | 0.125 | <1 | 2.90 | 0.020 | 0.04 | <0.1 | 0.02 | 5.1 | 0.2 | <0.05 | 8 | <0.5 | <0.2 |
| 1321440 | Soil | | 12 | 33 | 0.78 | 135 | 0.133 | 2 | 1.55 | 0.063 | 0.09 | 0.1 | 0.02 | 5.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321441 | Soil | | 0.7 | 40.6 | 5.4 | 49 | <0.1 | 30.1 | 12.1 | 429 | 2.35 | 5.6 | 0.6 | 4.8 | 2.1 | 58 | <0.1 | 0.5 | <0.1 | 65 | 1.38 | 0.059 |
| 1321442 | Soil | | 2.4 | 46.7 | 9.1 | 151 | 0.5 | 55.2 | 15.6 | 582 | 3.11 | 27.4 | 0.7 | 10.4 | 2.1 | 59 | 1.4 | 2.8 | 0.1 | 83 | 0.94 | 0.066 |
| 1321443 | Soil | | 1.0 | 44.2 | 8.6 | 67 | 0.5 | 46.3 | 16.6 | 466 | 3.97 | 12.2 | 0.9 | 2.3 | 4.3 | 40 | 0.7 | 0.9 | 0.2 | 93 | 0.55 | 0.060 |
| 1321444 | Soil | | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. |
| 1321445 | Soil | | 0.3 | 33.2 | 4.9 | 54 | <0.1 | 25.3 | 10.7 | 402 | 2.63 | 6.3 | 0.7 | 2.8 | 2.2 | 58 | 0.2 | 0.4 | <0.1 | 67 | 1.28 | 0.060 |
| 1321446 | Soil | | 1.4 | 50.0 | 9.3 | 109 | 0.6 | 42.0 | 13.1 | 471 | 2.76 | 16.5 | 0.9 | 14.8 | 3.2 | 62 | 1.0 | 1.9 | 0.1 | 64 | 1.24 | 0.078 |
| 1321447 | Soil | | 2.1 | 29.0 | 9.4 | 97 | 0.6 | 28.4 | 12.3 | 632 | 2.43 | 23.2 | 0.6 | 7.3 | 2.3 | 48 | 1.5 | 1.6 | 0.2 | 72 | 0.70 | 0.059 |
| 1321448 | Soil | | 2.0 | 14.9 | 1.9 | 27 | 0.1 | 9.3 | 3.4 | 158 | 0.66 | 1.1 | 1.0 | 4.2 | 0.7 | 159 | 0.5 | 0.7 | <0.1 | 18 | 3.53 | 0.073 |
| 1321449 | Soil | | 2.2 | 33.1 | 7.2 | 89 | 0.3 | 27.0 | 13.7 | 601 | 2.85 | 13.9 | 0.8 | 10.1 | 2.4 | 61 | 0.7 | 1.3 | 0.1 | 71 | 0.94 | 0.080 |
| 1321450 | Soil | | 1.2 | 32.0 | 6.0 | 76 | 0.2 | 28.0 | 10.3 | 328 | 2.56 | 10.6 | 0.8 | 5.9 | 2.3 | 82 | 0.6 | 1.3 | <0.1 | 69 | 1.19 | 0.069 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# CERTIFICATE OF ANALYSIS WHI20000132.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321441 | Soil | 12 | 32 | 0.61 | 160 | 0.107 | 2 | 1.67 | 0.044 | 0.05 | <0.1 | 0.03 | 5.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321442 | Soil | 12 | 53 | 0.78 | 443 | 0.073 | 2 | 1.90 | 0.038 | 0.07 | <0.1 | 0.09 | 7.0 | 0.1 | 0.06 | 6 | 1.0 | <0.2 |
| 1321443 | Soil | 17 | 55 | 0.86 | 268 | 0.120 | 1 | 2.36 | 0.048 | 0.05 | <0.1 | 0.03 | 11.2 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321444 | Soil | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. |
| 1321445 | Soil | 11 | 31 | 0.63 | 139 | 0.120 | 3 | 1.54 | 0.053 | 0.07 | <0.1 | 0.01 | 5.8 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321446 | Soil | 15 | 37 | 0.64 | 394 | 0.081 | 1 | 1.74 | 0.038 | 0.06 | <0.1 | 0.06 | 7.2 | 0.1 | <0.05 | 5 | 1.2 | <0.2 |
| 1321447 | Soil | 12 | 41 | 0.52 | 587 | 0.072 | 2 | 1.70 | 0.030 | 0.07 | 0.1 | 0.06 | 4.8 | 0.2 | <0.05 | 6 | 0.6 | <0.2 |
| 1321448 | Soil | 2 | 8 | 0.32 | 894 | 0.021 | 10 | 0.40 | 0.031 | 0.03 | <0.1 | 0.09 | 1.4 | <0.1 | 0.33 | <1 | 11.7 | <0.2 |
| 1321449 | Soil | 12 | 34 | 0.62 | 241 | 0.109 | 2 | 1.73 | 0.045 | 0.06 | 0.1 | 0.05 | 5.7 | 0.1 | <0.05 | 5 | 1.2 | <0.2 |
| 1321450 | Soil | 11 | 33 | 0.62 | 188 | 0.113 | 3 | 1.63 | 0.050 | 0.05 | <0.1 | 0.03 | 5.3 | <0.1 | 0.06 | 5 | 1.1 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.
9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# QUALITY CONTROL REPORT WHI20000132.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| Pulp Duplicates | | | | | | | | | | | | | | | | | | | | | |
| 1320823 | Soil | 0.7 | 35.7 | 16.4 | 57 | <0.1 | 32.6 | 13.3 | 478 | 3.46 | 12.2 | 0.7 | 2.1 | 6.1 | 40 | <0.1 | 0.7 | 0.2 | 87 | 0.46 | 0.020 |
| REP 1320823 | QC | 0.9 | 36.9 | 17.1 | 59 | <0.1 | 33.5 | 13.5 | 478 | 3.53 | 12.6 | 0.6 | 2.3 | 5.8 | 42 | 0.1 | 0.6 | 0.2 | 91 | 0.48 | 0.022 |
| 1320860 | Soil | 0.9 | 33.9 | 5.9 | 42 | <0.1 | 905.4 | 54.3 | 1267 | 3.70 | 10.1 | 0.2 | 3.0 | 1.3 | 113 | 0.3 | 2.6 | <0.1 | 68 | 8.29 | 0.030 |
| REP 1320860 | QC | 0.8 | 31.7 | 6.1 | 37 | <0.1 | 890.0 | 54.3 | 1305 | 3.80 | 10.3 | 0.2 | 2.8 | 1.4 | 111 | 0.1 | 2.4 | <0.1 | 66 | 8.17 | 0.031 |
| 1320896 | Soil | 0.8 | 20.0 | 11.5 | 63 | 0.1 | 24.3 | 15.4 | 711 | 2.63 | 42.1 | 0.6 | 23.1 | 3.0 | 30 | <0.1 | 0.9 | 0.1 | 61 | 0.49 | 0.049 |
| REP 1320896 | QC | 0.7 | 20.8 | 11.7 | 71 | 0.1 | 25.1 | 16.3 | 740 | 2.74 | 43.8 | 0.7 | 18.5 | 3.0 | 31 | <0.1 | 0.8 | 0.1 | 63 | 0.51 | 0.056 |
| 1320932 | Soil | 1.2 | 23.6 | 8.5 | 62 | 0.2 | 31.6 | 15.4 | 344 | 3.64 | 9.9 | 0.5 | 1.1 | 3.9 | 30 | 0.1 | 0.8 | <0.1 | 84 | 0.45 | 0.023 |
| REP 1320932 | QC | 1.1 | 24.7 | 8.6 | 65 | 0.1 | 33.5 | 16.2 | 347 | 3.76 | 9.6 | 0.5 | <0.5 | 3.8 | 29 | <0.1 | 0.8 | 0.1 | 85 | 0.47 | 0.022 |
| 1321336 | Soil | 0.5 | 42.7 | 7.9 | 62 | <0.1 | 31.7 | 12.8 | 449 | 3.01 | 11.1 | 0.4 | 5.7 | 2.9 | 60 | <0.1 | 0.5 | 0.1 | 78 | 1.60 | 0.060 |
| REP 1321336 | QC | 0.8 | 44.0 | 7.6 | 56 | <0.1 | 31.6 | 12.9 | 454 | 3.04 | 11.1 | 0.4 | 4.9 | 3.2 | 59 | <0.1 | 0.5 | 0.1 | 77 | 1.56 | 0.064 |
| 1321372 | Soil | 0.5 | 43.7 | 8.3 | 54 | 0.1 | 34.6 | 15.1 | 522 | 3.09 | 8.7 | 1.0 | 1.1 | 3.2 | 57 | <0.1 | 0.6 | 0.1 | 78 | 1.03 | 0.053 |
| REP 1321372 | QC | 0.5 | 42.0 | 8.5 | 53 | 0.1 | 32.0 | 14.3 | 500 | 3.04 | 9.9 | 1.0 | 4.7 | 3.0 | 57 | 0.2 | 0.5 | 0.1 | 78 | 1.01 | 0.052 |
| 1321408 | Soil | 1.5 | 46.0 | 17.4 | 61 | 0.3 | 34.3 | 16.0 | 843 | 3.73 | 22.8 | 1.0 | 11.2 | 2.8 | 48 | 0.2 | 0.6 | 0.2 | 78 | 0.69 | 0.049 |
| REP 1321408 | QC | 1.5 | 48.4 | 17.6 | 62 | 0.3 | 35.7 | 16.2 | 812 | 3.53 | 23.6 | 1.0 | 13.0 | 2.9 | 49 | 0.3 | 0.6 | 0.2 | 75 | 0.74 | 0.052 |
| 1321439 | Soil | 1.4 | 22.6 | 8.3 | 57 | 0.1 | 33.2 | 15.0 | 292 | 3.78 | 7.4 | 0.4 | <0.5 | 2.3 | 25 | 0.1 | 0.5 | 0.1 | 105 | 0.37 | 0.014 |
| REP 1321439 | QC | 1.2 | 23.0 | 8.1 | 60 | <0.1 | 34.2 | 14.6 | 293 | 3.89 | 8.1 | 0.4 | <0.5 | 2.1 | 26 | 0.1 | 0.6 | 0.1 | 106 | 0.37 | 0.014 |
| Reference Materials | | | | | | | | | | | | | | | | | | | | | |
| STD BVGEO01 | Standard | 10.3 | 4236.4 | 181.4 | 1694 | 2.5 | 159.0 | 23.8 | 660 | 3.76 | 113.3 | 3.7 | 200.9 | 15.0 | 54 | 6.3 | 3.5 | 24.3 | 76 | 1.23 | 0.070 |
| STD BVGEO01 | Standard | 9.9 | 4198.3 | 183.1 | 1567 | 2.5 | 159.2 | 24.5 | 682 | 3.73 | 109.2 | 3.6 | 221.6 | 14.9 | 56 | 6.1 | 3.6 | 23.2 | 77 | 1.25 | 0.067 |
| STD BVGEO01 | Standard | 9.9 | 4392.4 | 192.2 | 1645 | 2.3 | 166.7 | 24.4 | 691 | 3.71 | 110.8 | 3.7 | 193.2 | 15.7 | 55 | 5.8 | 3.1 | 24.0 | 75 | 1.29 | 0.071 |
| STD BVGEO01 | Standard | 10.4 | 4305.5 | 176.2 | 1731 | 2.4 | 164.6 | 24.4 | 697 | 3.71 | 116.6 | 3.4 | 225.6 | 14.7 | 57 | 6.0 | 3.1 | 22.4 | 66 | 1.28 | 0.068 |
| STD DS11 | Standard | 13.1 | 144.4 | 138.5 | 346 | 1.7 | 81.9 | 13.4 | 991 | 3.04 | 43.1 | 2.5 | 73.4 | 8.3 | 67 | 2.3 | 8.2 | 11.2 | 53 | 1.00 | 0.068 |
| STD DS11 | Standard | 14.3 | 143.0 | 134.8 | 345 | 1.6 | 79.8 | 13.6 | 1019 | 3.20 | 41.8 | 2.5 | 75.5 | 8.7 | 69 | 1.9 | 9.0 | 11.2 | 54 | 1.03 | 0.068 |
| STD DS11 | Standard | 14.5 | 140.3 | 132.6 | 338 | 1.6 | 77.3 | 13.3 | 952 | 3.16 | 43.6 | 2.5 | 87.9 | 8.3 | 68 | 2.3 | 8.7 | 10.7 | 51 | 0.99 | 0.070 |
| STD DS11 | Standard | 14.3 | 147.1 | 135.7 | 357 | 1.6 | 79.4 | 13.7 | 1037 | 3.30 | 42.2 | 2.5 | 61.8 | 7.8 | 66 | 2.3 | 8.0 | 10.7 | 52 | 1.07 | 0.065 |
| STD DS11 | Standard | 14.0 | 144.8 | 131.7 | 321 | 1.6 | 73.5 | 12.6 | 1028 | 3.03 | 39.7 | 2.4 | 61.3 | 8.0 | 64 | 2.1 | 7.8 | 10.8 | 48 | 1.01 | 0.064 |
| STD OREAS262 | Standard | 0.6 | 112.6 | 54.2 | 149 | 0.4 | 67.0 | 27.6 | 495 | 3.42 | 35.9 | 1.2 | 73.6 | 9.3 | 36 | 0.7 | 5.6 | 1.0 | 22 | 2.95 | 0.037 |
| STD OREAS262 | Standard | 0.7 | 119.1 | 58.6 | 163 | 0.5 | 67.6 | 27.6 | 510 | 3.38 | 39.5 | 1.2 | 67.3 | 10.1 | 36 | 0.8 | 5.6 | 1.1 | 23 | 3.16 | 0.042 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.
9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# QUALITY CONTROL REPORT WHI20000132.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| Pulp Duplicates | | | | | | | | | | | | | | | | | | | |
| 1320823 | Soil | | 17 | 50 | 0.69 | 184 | 0.134 | 3 | 2.37 | 0.026 | 0.08 | 0.1 | 0.04 | 9.9 | 0.1 | <0.05 | 6 | <0.5 | <0.2 |
| REP 1320823 | QC | | 16 | 51 | 0.70 | 183 | 0.137 | 2 | 2.43 | 0.027 | 0.08 | <0.1 | 0.03 | 10.0 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1320860 | Soil | | 7 | 337 | 2.77 | 59 | 0.043 | <1 | 1.95 | 0.013 | 0.02 | <0.1 | 0.64 | 9.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| REP 1320860 | QC | | 7 | 330 | 2.90 | 61 | 0.040 | <1 | 2.01 | 0.013 | 0.02 | <0.1 | 0.60 | 8.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1320896 | Soil | | 12 | 30 | 0.46 | 128 | 0.080 | 2 | 1.51 | 0.029 | 0.05 | 0.1 | 0.07 | 4.2 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| REP 1320896 | QC | | 13 | 30 | 0.50 | 128 | 0.086 | 2 | 1.63 | 0.033 | 0.05 | 0.1 | 0.07 | 4.7 | <0.1 | 0.08 | 5 | <0.5 | <0.2 |
| 1320932 | Soil | | 11 | 48 | 0.70 | 147 | 0.098 | <1 | 2.47 | 0.021 | 0.11 | <0.1 | 0.02 | 6.5 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| REP 1320932 | QC | | 11 | 48 | 0.65 | 143 | 0.096 | <1 | 2.51 | 0.020 | 0.11 | <0.1 | 0.01 | 6.6 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321336 | Soil | | 13 | 39 | 0.73 | 156 | 0.131 | 2 | 1.76 | 0.059 | 0.08 | 0.1 | 0.03 | 6.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| REP 1321336 | QC | | 13 | 39 | 0.71 | 163 | 0.126 | 3 | 1.77 | 0.057 | 0.08 | 0.1 | 0.03 | 6.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321372 | Soil | | 14 | 40 | 0.68 | 191 | 0.120 | <1 | 1.94 | 0.040 | 0.05 | 0.1 | 0.05 | 7.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| REP 1321372 | QC | | 14 | 38 | 0.67 | 189 | 0.119 | 2 | 1.89 | 0.041 | 0.05 | <0.1 | 0.04 | 7.1 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321408 | Soil | | 18 | 42 | 0.62 | 168 | 0.065 | 3 | 2.46 | 0.024 | 0.09 | 0.3 | 0.03 | 5.1 | <0.1 | <0.05 | 8 | <0.5 | <0.2 |
| REP 1321408 | QC | | 19 | 43 | 0.66 | 179 | 0.085 | 3 | 2.73 | 0.027 | 0.11 | 0.4 | 0.05 | 5.8 | <0.1 | 0.06 | 8 | <0.5 | <0.2 |
| 1321439 | Soil | | 7 | 50 | 0.72 | 175 | 0.125 | <1 | 2.90 | 0.020 | 0.04 | <0.1 | 0.02 | 5.1 | 0.2 | <0.05 | 8 | <0.5 | <0.2 |
| REP 1321439 | QC | | 7 | 52 | 0.73 | 170 | 0.131 | 2 | 3.02 | 0.022 | 0.04 | <0.1 | 0.01 | 4.8 | 0.2 | <0.05 | 8 | <0.5 | <0.2 |
| Reference Materials | | | | | | | | | | | | | | | | | | | |
| STD BVGEO01 | Standard | | 25 | 182 | 1.23 | 309 | 0.227 | 4 | 2.17 | 0.185 | 0.87 | 6.0 | 0.10 | 6.1 | 0.6 | 0.57 | 6 | 4.8 | 1.0 |
| STD BVGEO01 | Standard | | 25 | 196 | 1.26 | 297 | 0.221 | 4 | 2.23 | 0.192 | 0.84 | 5.0 | 0.07 | 6.5 | 0.6 | 0.69 | 7 | 3.8 | 1.0 |
| STD BVGEO01 | Standard | | 25 | 183 | 1.26 | 257 | 0.217 | 3 | 2.19 | 0.186 | 0.86 | 5.0 | 0.09 | 6.4 | 0.6 | 0.71 | 7 | 3.8 | 1.3 |
| STD BVGEO01 | Standard | | 25 | 202 | 1.30 | 287 | 0.223 | 2 | 2.34 | 0.196 | 0.85 | 5.0 | 0.11 | 5.6 | 0.6 | 0.63 | 7 | 4.5 | 1.0 |
| STD DS11 | Standard | | 19 | 60 | 0.83 | 385 | 0.090 | 7 | 1.09 | 0.073 | 0.38 | 3.2 | 0.22 | 3.7 | 4.8 | 0.25 | 5 | 1.9 | 3.9 |
| STD DS11 | Standard | | 19 | 60 | 0.86 | 374 | 0.099 | 9 | 1.18 | 0.068 | 0.42 | 3.0 | 0.22 | 3.4 | 5.0 | 0.31 | 5 | 1.5 | 5.0 |
| STD DS11 | Standard | | 19 | 59 | 0.84 | 372 | 0.094 | 7 | 1.16 | 0.072 | 0.38 | 2.9 | 0.21 | 2.9 | 4.7 | 0.28 | 4 | 2.0 | 4.7 |
| STD DS11 | Standard | | 18 | 60 | 0.82 | 374 | 0.095 | 6 | 1.13 | 0.076 | 0.38 | 3.0 | 0.25 | 3.1 | 4.8 | 0.27 | 5 | 1.9 | 4.3 |
| STD DS11 | Standard | | 17 | 60 | 0.84 | 350 | 0.084 | 6 | 1.16 | 0.077 | 0.38 | 2.9 | 0.25 | 3.3 | 4.7 | 0.28 | 5 | 2.1 | 4.4 |
| STD OREAS262 | Standard | | 15 | 42 | 1.16 | 241 | 0.003 | 4 | 1.23 | 0.063 | 0.29 | 0.2 | 0.16 | 3.1 | 0.5 | 0.22 | 4 | <0.5 | 0.4 |
| STD OREAS262 | Standard | | 17 | 45 | 1.19 | 257 | 0.003 | 5 | 1.25 | 0.065 | 0.32 | 0.3 | 0.16 | 3.5 | 0.5 | 0.28 | 4 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# QUALITY CONTROL REPORT WHI20000132.1

| | | AQ201 Mo ppm 0.1 | AQ201 Cu ppm 0.1 | AQ201 Pb ppm 0.1 | AQ201 Zn ppm 1 | AQ201 Ag ppm 0.1 | AQ201 Ni ppm 0.1 | AQ201 Co ppm 0.1 | AQ201 Mn ppm 1 | AQ201 Fe % 0.01 | AQ201 As ppm 0.5 | AQ201 U ppm 0.1 | AQ201 Au ppb 0.5 | AQ201 Th ppm 0.1 | AQ201 Sr ppm 1 | AQ201 Cd ppm 0.1 | AQ201 Sb ppm 0.1 | AQ201 Bi ppm 0.1 | AQ201 V ppm 2 | AQ201 Ca % 0.01 | AQ201 P % 0.001 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| STD OREAS262 | Standard | 0.8 | 112.0 | 56.4 | 151 | 0.5 | 62.7 | 26.7 | 515 | 3.34 | 34.4 | 1.2 | 81.3 | 9.8 | 35 | 0.5 | 5.9 | 0.9 | 25 | 2.84 | 0.040 |
| STD OREAS262 | Standard | 0.5 | 113.1 | 54.9 | 146 | 0.4 | 61.7 | 26.0 | 488 | 3.15 | 34.2 | 1.2 | 79.1 | 10.0 | 35 | 0.5 | 5.9 | 1.1 | 24 | 2.83 | 0.037 |
| STD OREAS262 | Standard | 0.5 | 112.2 | 55.6 | 149 | 0.4 | 63.9 | 27.3 | 520 | 3.23 | 35.3 | 1.2 | 62.9 | 9.6 | 33 | 0.6 | 5.6 | 1.0 | 23 | 2.82 | 0.037 |
| STD OREAS262 | Standard | 0.6 | 110.3 | 57.4 | 154 | 0.4 | 68.8 | 27.1 | 527 | 3.43 | 35.5 | 1.3 | 73.5 | 9.7 | 36 | 0.5 | 6.2 | 1.0 | 26 | 2.90 | 0.043 |
| STD OREAS262 | Standard | 0.5 | 116.2 | 53.2 | 151 | 0.4 | 65.9 | 27.3 | 549 | 3.42 | 37.5 | 1.1 | 66.1 | 9.3 | 36 | 0.6 | 4.7 | 0.9 | 22 | 2.89 | 0.039 |
| STD OREAS262 | Standard | 0.5 | 114.3 | 57.2 | 147 | 0.5 | 61.4 | 25.9 | 547 | 3.24 | 34.1 | 1.2 | 58.3 | 9.6 | 35 | 0.6 | 4.8 | 1.0 | 24 | 3.04 | 0.037 |
| STD OREAS262 | Standard | 0.7 | 113.2 | 56.8 | 150 | 0.4 | 61.8 | 26.6 | 532 | 3.37 | 34.9 | 1.2 | 60.8 | 9.5 | 34 | 0.6 | 5.2 | 1.0 | 22 | 2.81 | 0.039 |
| STD BVGEO01 Expected | | 11.2 | 4415 | 187 | 1741 | 2.53 | 163 | 25 | 733 | 3.7 | 121 | 3.77 | 219 | 14.4 | 55 | 6.5 | 3.39 | 25.6 | 73 | 1.3219 | 0.0727 |
| STD DS11 Expected | | 14.6 | 149 | 138 | 345 | 1.71 | 77.7 | 14.2 | 1055 | 3.1 | 42.8 | 2.59 | 79 | 7.65 | 67.3 | 2.37 | 8.74 | 12.2 | 50 | 1.063 | 0.0701 |
| STD OREAS262 Expected | | 0.68 | 118 | 56 | 154 | 0.45 | 62 | 26.9 | 530 | 3.284 | 35.8 | 1.22 | 65 | 9.33 | 36 | 0.61 | 5.06 | 1.03 | 22.5 | 2.98 | 0.04 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | 2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | 1.0 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | 0.7 | <0.1 | <0.5 | 0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 04, 2020



# QUALITY CONTROL REPORT WHI20000132.1

| | | AQ201 La ppm 1 | AQ201 Cr ppm 1 | AQ201 Mg % 0.01 | AQ201 Ba ppm 1 | AQ201 Ti % 0.001 | AQ201 B ppm 1 | AQ201 Al % 0.01 | AQ201 Na % 0.001 | AQ201 K % 0.01 | AQ201 W ppm 0.1 | AQ201 Hg ppm 0.01 | AQ201 Sc ppm 0.1 | AQ201 Tl ppm 0.1 | AQ201 S % 0.05 | AQ201 Ga ppm 1 | AQ201 Se ppm 0.5 | AQ201 Te ppm 0.2 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| STD OREAS262 | Standard | 18 | 44 | 1.17 | 257 | 0.003 | 5 | 1.36 | 0.064 | 0.30 | 0.3 | 0.18 | 3.4 | 0.5 | 0.28 | 4 | 0.6 | <0.2 |
| STD OREAS262 | Standard | 18 | 45 | 1.16 | 252 | 0.003 | 4 | 1.36 | 0.061 | 0.32 | 0.2 | 0.14 | 3.7 | 0.4 | 0.30 | 4 | <0.5 | <0.2 |
| STD OREAS262 | Standard | 16 | 43 | 1.16 | 237 | 0.003 | 3 | 1.25 | 0.064 | 0.30 | 0.2 | 0.13 | 3.3 | 0.5 | 0.28 | 4 | 0.5 | <0.2 |
| STD OREAS262 | Standard | 19 | 45 | 1.24 | 248 | 0.003 | 5 | 1.40 | 0.066 | 0.32 | 0.3 | 0.18 | 3.5 | 0.4 | 0.28 | 4 | <0.5 | 0.4 |
| STD OREAS262 | Standard | 17 | 44 | 1.21 | 245 | 0.003 | 3 | 1.34 | 0.068 | 0.31 | 0.2 | 0.19 | 3.5 | 0.5 | 0.23 | 5 | <0.5 | 0.3 |
| STD OREAS262 | Standard | 17 | 45 | 1.14 | 255 | 0.003 | 3 | 1.30 | 0.066 | 0.31 | 0.2 | 0.15 | 3.2 | 0.5 | 0.31 | 4 | <0.5 | <0.2 |
| STD OREAS262 | Standard | 16 | 44 | 1.26 | 260 | 0.004 | 3 | 1.42 | 0.067 | 0.29 | 0.2 | 0.17 | 3.5 | 0.5 | 0.30 | 4 | <0.5 | <0.2 |
| STD BVGEO01 Expected | | 25.9 | 187 | 1.2963 | 260 | 0.233 | 3.8 | 2.347 | 0.1924 | 0.89 | 5.3 | 0.1 | 5.97 | 0.62 | 0.6655 | 7.37 | 4.84 | 1.02 |
| STD DS11 Expected | | 18.6 | 61.5 | 0.85 | 385 | 0.0976 | | 1.1795 | 0.0762 | 0.4 | 2.9 | 0.26 | 3.4 | 4.9 | 0.2835 | 5.1 | 2.2 | 4.56 |
| STD OREAS262 Expected | | 15.9 | 41.7 | 1.17 | 248 | 0.0027 | 4 | 1.3 | 0.071 | 0.312 | 0.2 | 0.17 | 3.24 | 0.47 | 0.253 | 4.1 | 0.4 | 0.23 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | 0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.
9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

| | |
|---|---|
| Submitted By: | Dan Ferraro |
| Receiving Lab: | Canada-Whitehorse |
| Received: | July 17, 2020 |
| Analysis Start: | July 30, 2020 |
| Report Date: | August 06, 2020 |
| Page: | 1 of 11 |

# CERTIFICATE OF ANALYSIS WHI20000133.1

## CLIENT JOB INFORMATION

| | |
|---|---|
| Project: | BE |
| Shipment ID: | BE_2020_SOIL_1 |
| P.O. Number | |
| Number of Samples: | 282 |

## SAMPLE DISPOSAL

| | |
|---|---|
| DISP-PLP | Dispose of Pulp After 90 days |
| DISP-RJT-SOIL | Immediate Disposal of Soil Reject |

Bureau Veritas does not accept responsibility for samples left at the laboratory after 90 days without prior written instructions for sample storage or return.

## SAMPLE PREPARATION AND ANALYTICAL PROCEDURES

| Procedure Code | Number of Samples | Code Description | Test Wgt (g) | Report Status | Lab |
|---|---|---|---|---|---|
| DY060 | 282 | Dry at 60C | | | WHI |
| SS80 | 282 | Dry at 60C sieve 100g to -80 mesh | | | WHI |
| AQ201 | 281 | 1:1:1 Aqua Regia digestion ICP-MS analysis | 15 | Completed | VAN |
| DISPL | 282 | Disposal of pulps | | | VAN |
| SHP01 | 282 | Per sample shipping charges for branch shipments | | | VAN |

## ADDITIONAL COMMENTS

Invoice To: Druid Exploration
Box 1485
Dawson City Yukon Y0B 1G0
Canada

CC: Clayton Jones
Daithi Mac Gerailt

BRITISH COLUMBIA CERTIFIED ASSAYER
MARCUS LAU
Production Manager

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.
All results are considered the confidential property of the client. Bureau Veritas assumes the liabilities for actual cost of analysis only. Results apply to samples as submitted.
"*" asterisk indicates that an analytical result could not be provided due to unusually high levels of interference from other elements.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321001 | Soil | | 0.5 | 42.2 | 4.8 | 45 | <0.1 | 27.8 | 11.9 | 532 | 2.60 | 4.9 | 1.8 | 2.2 | 2.3 | 60 | 0.2 | 0.5 | <0.1 | 67 | 1.31 | 0.065 |
| 1321002 | Soil | | 0.6 | 45.2 | 5.4 | 57 | <0.1 | 36.3 | 13.4 | 481 | 3.33 | 7.8 | 0.5 | 3.0 | 2.5 | 47 | <0.1 | 0.4 | <0.1 | 81 | 0.98 | 0.066 |
| 1321003 | Soil | | 0.6 | 35.0 | 4.9 | 53 | 0.1 | 30.1 | 11.4 | 436 | 2.84 | 5.5 | 0.6 | 2.8 | 2.3 | 58 | 0.1 | 0.4 | <0.1 | 73 | 1.52 | 0.084 |
| 1321004 | Soil | | 0.6 | 44.6 | 5.6 | 53 | 0.1 | 32.2 | 12.7 | 464 | 3.03 | 7.1 | 0.8 | 3.7 | 2.1 | 54 | 0.1 | 0.5 | <0.1 | 78 | 1.24 | 0.069 |
| 1321005 | Soil | | 0.7 | 38.8 | 5.6 | 73 | 0.1 | 33.0 | 12.3 | 525 | 2.99 | 5.9 | 0.6 | 3.0 | 2.1 | 61 | 0.2 | 0.5 | <0.1 | 69 | 1.51 | 0.088 |
| 1321006 | Soil | | 0.8 | 37.2 | 7.0 | 49 | <0.1 | 29.9 | 13.0 | 448 | 3.31 | 7.8 | 1.0 | 1.8 | 2.3 | 45 | <0.1 | 0.5 | <0.1 | 81 | 0.82 | 0.050 |
| 1321007 | Soil | | 0.7 | 40.2 | 6.5 | 55 | 0.1 | 32.7 | 12.6 | 429 | 3.25 | 7.1 | 0.8 | 4.5 | 3.0 | 45 | <0.1 | 0.5 | <0.1 | 78 | 0.80 | 0.058 |
| 1321008 | Soil | | 0.6 | 39.0 | 5.2 | 56 | <0.1 | 26.3 | 11.5 | 603 | 2.57 | 4.7 | 1.3 | 3.0 | 1.7 | 66 | 0.2 | 0.5 | <0.1 | 59 | 1.31 | 0.070 |
| 1321009 | Soil | | 0.5 | 49.6 | 5.4 | 62 | <0.1 | 32.0 | 12.2 | 524 | 2.68 | 4.5 | 1.4 | 7.0 | 2.4 | 59 | 0.2 | 0.5 | <0.1 | 68 | 1.32 | 0.063 |
| 1321010 | Soil | | 0.6 | 36.5 | 5.4 | 51 | <0.1 | 26.0 | 11.8 | 520 | 2.60 | 5.4 | 1.0 | 2.4 | 1.9 | 56 | 0.2 | 0.5 | <0.1 | 69 | 1.11 | 0.057 |
| 1321011 | Soil | | 0.6 | 25.0 | 4.8 | 52 | <0.1 | 21.2 | 10.4 | 455 | 2.38 | 5.1 | 0.7 | 5.7 | 1.6 | 49 | 0.1 | 0.4 | <0.1 | 63 | 1.07 | 0.060 |
| 1321012 | Soil | | 1.0 | 26.1 | 5.7 | 66 | 0.1 | 22.4 | 10.9 | 547 | 2.38 | 9.0 | 0.6 | 4.2 | 1.9 | 48 | 0.2 | 0.5 | <0.1 | 63 | 0.93 | 0.058 |
| 1321013 | Soil | | 1.2 | 37.1 | 7.6 | 65 | 0.2 | 24.9 | 11.2 | 601 | 2.67 | 7.0 | 1.2 | 6.9 | 2.2 | 62 | 0.3 | 0.8 | 0.1 | 64 | 1.03 | 0.075 |
| 1321014 | Soil | | 2.4 | 56.9 | 8.9 | 69 | 0.3 | 32.9 | 14.9 | 940 | 3.30 | 11.5 | 1.2 | 4.9 | 2.8 | 46 | 0.2 | 0.8 | 0.1 | 70 | 0.56 | 0.064 |
| 1321015 | Soil | | 1.4 | 36.4 | 6.2 | 55 | 0.1 | 26.0 | 12.5 | 576 | 2.75 | 8.7 | 0.8 | 2.9 | 2.1 | 49 | 0.1 | 0.6 | <0.1 | 68 | 0.96 | 0.075 |
| 1321016 | Soil | | 0.8 | 40.7 | 5.7 | 57 | <0.1 | 26.8 | 11.9 | 402 | 3.13 | 8.0 | 0.6 | 1.9 | 2.3 | 47 | <0.1 | 0.4 | <0.1 | 78 | 0.92 | 0.066 |
| 1321017 | Soil | | 32.3 | 82.4 | 31.0 | 86 | 1.4 | 22.7 | 4.2 | 303 | 3.69 | 27.2 | 1.9 | 10.8 | 8.3 | 313 | 0.8 | 4.5 | 0.3 | 42 | 0.50 | 0.139 |
| 1321018 | Soil | | 1.3 | 52.5 | 7.5 | 77 | 0.2 | 33.6 | 10.9 | 453 | 2.87 | 9.8 | 1.2 | 5.4 | 2.3 | 57 | 0.5 | 1.0 | <0.1 | 60 | 0.98 | 0.058 |
| 1321019 | Soil | | 1.1 | 34.4 | 6.6 | 50 | <0.1 | 33.0 | 13.2 | 592 | 3.11 | 8.9 | 0.4 | 3.8 | 2.6 | 47 | 0.2 | 0.5 | <0.1 | 73 | 0.73 | 0.034 |
| 1321020 | Soil | | 0.6 | 38.1 | 5.1 | 51 | <0.1 | 26.6 | 10.9 | 456 | 2.83 | 7.3 | 0.5 | 3.8 | 2.6 | 71 | 0.1 | 0.5 | <0.1 | 73 | 2.24 | 0.094 |
| 1321021 | Soil | | 0.9 | 39.3 | 8.4 | 62 | 0.1 | 32.4 | 13.3 | 685 | 2.98 | 13.3 | 0.5 | 9.4 | 2.9 | 44 | 0.1 | 0.8 | 0.1 | 69 | 0.68 | 0.044 |
| 1321022 | Soil | | 1.3 | 56.6 | 10.4 | 87 | 0.2 | 41.0 | 13.4 | 656 | 3.30 | 25.4 | 0.7 | 12.3 | 3.3 | 65 | 0.2 | 1.2 | 0.1 | 79 | 0.71 | 0.072 |
| 1321023 | Soil | | 1.3 | 27.1 | 9.6 | 59 | 0.1 | 30.2 | 15.3 | 667 | 3.62 | 8.6 | 0.6 | 0.7 | 2.3 | 39 | 0.2 | 0.6 | <0.1 | 89 | 0.65 | 0.035 |
| 1321024 | Soil | | 0.8 | 41.9 | 7.9 | 65 | <0.1 | 34.5 | 14.3 | 594 | 3.62 | 8.3 | 0.5 | 2.9 | 3.1 | 45 | <0.1 | 0.6 | 0.1 | 85 | 0.82 | 0.054 |
| 1321025 | Soil | | 1.4 | 34.9 | 8.5 | 67 | <0.1 | 32.3 | 15.2 | 723 | 3.83 | 9.8 | 0.6 | 6.5 | 3.0 | 37 | <0.1 | 0.7 | 0.1 | 87 | 0.61 | 0.032 |
| 1321026 | Soil | | 1.1 | 87.8 | 11.2 | 67 | <0.1 | 56.1 | 14.5 | 1959 | 3.18 | 12.6 | 0.7 | 4.1 | 4.8 | 34 | <0.1 | 0.5 | 0.2 | 59 | 0.47 | 0.024 |
| 1321027 | Soil | | 0.8 | 118.8 | 12.8 | 85 | <0.1 | 59.1 | 19.1 | 1426 | 2.78 | 5.3 | 0.5 | 2.2 | 5.8 | 22 | <0.1 | 0.5 | 0.2 | 32 | 0.29 | 0.028 |
| 1321028 | Soil | | 4.3 | 141.2 | 19.3 | 104 | <0.1 | 65.7 | 23.8 | 4881 | 3.38 | 8.7 | 0.8 | 2.9 | 5.5 | 56 | <0.1 | 0.9 | 0.3 | 47 | 0.31 | 0.035 |
| 1321029 | Soil | | 1.9 | 42.5 | 9.1 | 67 | <0.1 | 34.3 | 14.0 | 658 | 3.55 | 9.0 | 0.7 | 3.1 | 3.3 | 40 | 0.1 | 0.6 | 0.1 | 85 | 0.59 | 0.033 |
| 1321030 | Soil | | 1.5 | 34.8 | 9.9 | 63 | <0.1 | 37.0 | 16.8 | 777 | 3.71 | 9.3 | 0.5 | 1.1 | 2.9 | 41 | <0.1 | 0.7 | <0.1 | 87 | 0.75 | 0.027 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321001 | Soil | 11 | 32 | 0.67 | 166 | 0.110 | 4 | 1.59 | 0.050 | 0.07 | <0.1 | 0.04 | 5.5 | <0.1 | 0.07 | 5 | <0.5 | <0.2 |
| 1321002 | Soil | 13 | 42 | 0.90 | 188 | 0.119 | 3 | 1.76 | 0.059 | 0.09 | <0.1 | 0.04 | 6.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321003 | Soil | 11 | 38 | 0.91 | 131 | 0.116 | 5 | 1.61 | 0.058 | 0.10 | <0.1 | 0.03 | 5.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321004 | Soil | 11 | 42 | 0.85 | 189 | 0.113 | 4 | 1.77 | 0.055 | 0.10 | <0.1 | 0.03 | 5.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321005 | Soil | 12 | 40 | 0.88 | 216 | 0.111 | 4 | 1.63 | 0.060 | 0.09 | <0.1 | 0.03 | 5.9 | <0.1 | 0.06 | 5 | <0.5 | <0.2 |
| 1321006 | Soil | 13 | 40 | 0.71 | 278 | 0.111 | 2 | 2.33 | 0.042 | 0.05 | 0.1 | 0.02 | 6.4 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321007 | Soil | 14 | 42 | 0.77 | 223 | 0.115 | 3 | 2.01 | 0.053 | 0.06 | 0.1 | 0.04 | 6.6 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321008 | Soil | 11 | 34 | 0.63 | 254 | 0.082 | 3 | 1.71 | 0.046 | 0.05 | <0.1 | 0.03 | 5.2 | <0.1 | 0.06 | 5 | <0.5 | <0.2 |
| 1321009 | Soil | 12 | 37 | 0.70 | 179 | 0.110 | 5 | 1.74 | 0.055 | 0.07 | <0.1 | 0.04 | 5.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321010 | Soil | 11 | 34 | 0.63 | 189 | 0.107 | 2 | 1.72 | 0.043 | 0.05 | <0.1 | 0.04 | 5.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321011 | Soil | 10 | 29 | 0.62 | 172 | 0.096 | 2 | 1.66 | 0.044 | 0.05 | <0.1 | 0.04 | 4.6 | <0.1 | 0.07 | 5 | <0.5 | <0.2 |
| 1321012 | Soil | 10 | 29 | 0.58 | 179 | 0.096 | 3 | 1.41 | 0.042 | 0.06 | <0.1 | 0.03 | 3.9 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321013 | Soil | 11 | 32 | 0.64 | 275 | 0.089 | 4 | 1.70 | 0.046 | 0.06 | <0.1 | 0.04 | 4.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321014 | Soil | 14 | 37 | 0.67 | 534 | 0.084 | 2 | 2.17 | 0.033 | 0.07 | <0.1 | 0.04 | 5.8 | 0.1 | <0.05 | 6 | 0.5 | <0.2 |
| 1321015 | Soil | 11 | 34 | 0.67 | 246 | 0.096 | 4 | 1.78 | 0.051 | 0.06 | <0.1 | 0.03 | 5.6 | <0.1 | 0.06 | 5 | <0.5 | <0.2 |
| 1321016 | Soil | 12 | 36 | 0.71 | 189 | 0.101 | 2 | 1.69 | 0.056 | 0.05 | 0.1 | 0.02 | 6.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321017 | Soil | 24 | 18 | 0.40 | 578 | 0.007 | 2 | 1.04 | 0.029 | 0.16 | <0.1 | 0.20 | 2.4 | 0.3 | 0.43 | 3 | 4.7 | <0.2 |
| 1321018 | Soil | 12 | 33 | 0.68 | 428 | 0.078 | 3 | 1.64 | 0.051 | 0.09 | <0.1 | 0.04 | 5.1 | <0.1 | <0.05 | 5 | 1.1 | <0.2 |
| 1321019 | Soil | 13 | 39 | 0.75 | 328 | 0.123 | 3 | 1.74 | 0.060 | 0.12 | <0.1 | 0.03 | 6.6 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321020 | Soil | 11 | 35 | 0.93 | 153 | 0.115 | 3 | 1.60 | 0.068 | 0.10 | 0.1 | 0.02 | 4.9 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321021 | Soil | 11 | 33 | 0.59 | 508 | 0.092 | 3 | 1.73 | 0.040 | 0.08 | <0.1 | 0.02 | 5.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321022 | Soil | 13 | 36 | 0.57 | 557 | 0.086 | 4 | 1.65 | 0.041 | 0.07 | 0.1 | 0.03 | 6.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321023 | Soil | 10 | 46 | 0.72 | 466 | 0.102 | 3 | 2.52 | 0.038 | 0.06 | <0.1 | 0.02 | 6.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321024 | Soil | 15 | 44 | 0.84 | 223 | 0.116 | 2 | 2.21 | 0.060 | 0.06 | <0.1 | 0.01 | 7.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321025 | Soil | 11 | 51 | 0.72 | 293 | 0.112 | 2 | 2.35 | 0.034 | 0.07 | <0.1 | 0.02 | 7.9 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321026 | Soil | 25 | 39 | 0.72 | 245 | 0.071 | 2 | 1.88 | 0.026 | 0.08 | <0.1 | 0.05 | 8.6 | <0.1 | 0.05 | 5 | <0.5 | <0.2 |
| 1321027 | Soil | 24 | 24 | 0.69 | 306 | 0.016 | 2 | 1.46 | 0.009 | 0.11 | <0.1 | 0.04 | 3.6 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321028 | Soil | 23 | 28 | 0.78 | 349 | 0.041 | 1 | 1.78 | 0.015 | 0.10 | <0.1 | 0.03 | 8.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321029 | Soil | 14 | 48 | 0.75 | 241 | 0.115 | 2 | 2.42 | 0.040 | 0.06 | <0.1 | 0.02 | 8.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321030 | Soil | 14 | 53 | 0.70 | 214 | 0.125 | 3 | 2.18 | 0.043 | 0.09 | <0.1 | 0.03 | 9.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321031 | Soil | | 0.9 | 38.5 | 6.0 | 47 | <0.1 | 31.0 | 13.6 | 680 | 3.12 | 6.4 | 0.4 | 4.1 | 2.6 | 37 | <0.1 | 0.4 | <0.1 | 76 | 0.76 | 0.038 |
| 1321032 | Soil | | 0.8 | 42.3 | 5.5 | 65 | <0.1 | 34.0 | 13.3 | 521 | 3.13 | 5.4 | 0.4 | 3.0 | 2.4 | 53 | 0.1 | 0.6 | <0.1 | 83 | 1.53 | 0.087 |
| 1321033 | Soil | | 0.8 | 37.8 | 7.2 | 52 | <0.1 | 29.5 | 12.2 | 489 | 3.05 | 6.6 | 0.7 | 2.9 | 2.1 | 47 | <0.1 | 0.5 | <0.1 | 76 | 1.18 | 0.051 |
| 1321034 | Soil | | 0.7 | 52.0 | 7.1 | 57 | 0.1 | 31.3 | 12.2 | 530 | 2.88 | 8.9 | 1.0 | 4.0 | 2.6 | 58 | 0.2 | 0.8 | <0.1 | 67 | 1.01 | 0.061 |
| 1321035 | Soil | | 0.7 | 50.0 | 5.7 | 62 | <0.1 | 31.6 | 13.3 | 516 | 3.04 | 8.2 | 0.5 | 10.0 | 2.5 | 69 | 0.2 | 0.6 | <0.1 | 79 | 1.93 | 0.078 |
| 1321036 | Soil | | 2.2 | 26.9 | 10.4 | 77 | 0.1 | 23.9 | 11.1 | 456 | 3.24 | 12.3 | 0.5 | 3.3 | 2.0 | 30 | 0.1 | 0.8 | 0.1 | 76 | 0.40 | 0.072 |
| 1321037 | Soil | | 1.7 | 22.1 | 6.7 | 91 | 0.2 | 11.8 | 8.3 | 838 | 1.97 | 5.0 | 0.4 | 6.6 | 1.4 | 21 | 0.5 | 0.4 | 0.2 | 50 | 0.28 | 0.143 |
| 1321038 | Soil | | 9.0 | 37.9 | 21.4 | 160 | 0.7 | 35.7 | 8.0 | 183 | 3.75 | 25.9 | 2.0 | 4.2 | 8.1 | 57 | 0.5 | 6.1 | 0.4 | 55 | 0.34 | 0.128 |
| 1321039 | Soil | | 5.3 | 42.3 | 14.5 | 140 | 0.8 | 33.8 | 10.1 | 259 | 3.30 | 24.2 | 1.6 | 7.4 | 6.2 | 46 | 0.7 | 4.0 | 0.2 | 67 | 0.40 | 0.099 |
| 1321040 | Soil | | 4.8 | 42.4 | 10.1 | 67 | 0.5 | 28.7 | 11.0 | 260 | 3.27 | 29.4 | 1.6 | 10.6 | 4.0 | 44 | 0.2 | 2.5 | 0.2 | 67 | 0.48 | 0.059 |
| 1321041 | Soil | | 1.8 | 28.0 | 9.9 | 59 | 0.2 | 29.4 | 14.9 | 414 | 3.57 | 47.3 | 0.8 | 20.1 | 3.9 | 36 | 0.1 | 1.7 | 0.1 | 83 | 0.45 | 0.044 |
| 1321042 | Soil | | 1.1 | 30.7 | 12.3 | 51 | <0.1 | 31.4 | 12.5 | 354 | 3.13 | 48.0 | 0.8 | 27.1 | 3.7 | 40 | <0.1 | 2.7 | 0.1 | 71 | 0.54 | 0.062 |
| 1321043 | Soil | | 0.7 | 25.4 | 8.1 | 57 | <0.1 | 29.8 | 13.6 | 381 | 3.15 | 13.3 | 0.7 | 23.6 | 3.3 | 41 | <0.1 | 0.5 | 0.1 | 80 | 0.63 | 0.051 |
| 1321044 | Soil | | 0.6 | 31.8 | 8.8 | 59 | <0.1 | 33.0 | 12.8 | 404 | 3.22 | 12.1 | 0.9 | 6.9 | 3.4 | 42 | 0.1 | 0.5 | 0.1 | 78 | 0.63 | 0.055 |
| 1321045 | Soil | | 0.8 | 41.3 | 9.8 | 65 | 0.2 | 34.7 | 13.7 | 487 | 3.36 | 11.7 | 1.2 | 5.6 | 3.1 | 45 | 0.1 | 0.5 | 0.2 | 83 | 0.67 | 0.057 |
| 1321046 | Soil | | 1.1 | 19.7 | 8.8 | 60 | <0.1 | 27.3 | 14.1 | 397 | 3.31 | 11.1 | 0.5 | 1.7 | 2.5 | 33 | <0.1 | 0.4 | 0.1 | 91 | 0.53 | 0.047 |
| 1321047 | Soil | | 0.9 | 27.5 | 8.4 | 62 | 0.1 | 29.4 | 12.7 | 414 | 2.93 | 9.0 | 0.8 | 5.0 | 2.7 | 38 | 0.2 | 0.4 | 0.1 | 76 | 0.56 | 0.052 |
| 1321048 | Soil | | 0.8 | 24.6 | 9.6 | 62 | <0.1 | 31.5 | 14.2 | 410 | 3.21 | 10.2 | 0.7 | 5.5 | 3.4 | 37 | <0.1 | 0.4 | 0.1 | 84 | 0.63 | 0.047 |
| 1321049 | Soil | | 0.6 | 33.5 | 8.4 | 59 | 0.1 | 33.0 | 13.7 | 422 | 3.09 | 9.3 | 0.9 | 3.9 | 3.0 | 43 | 0.1 | 0.4 | 0.1 | 72 | 0.71 | 0.053 |
| 1321050 | Soil | | 0.6 | 28.5 | 8.2 | 60 | <0.1 | 34.7 | 13.6 | 340 | 3.11 | 9.3 | 0.7 | 5.2 | 3.6 | 41 | 0.1 | 0.4 | 0.1 | 81 | 0.65 | 0.046 |
| 1321051 | Soil | | 0.6 | 34.8 | 8.3 | 55 | 0.2 | 29.2 | 10.3 | 315 | 2.64 | 7.2 | 0.7 | 2.4 | 2.6 | 40 | 0.1 | 0.4 | 0.1 | 60 | 0.70 | 0.042 |
| 1321052 | Soil | | 0.8 | 23.9 | 7.3 | 57 | <0.1 | 38.8 | 15.0 | 411 | 3.32 | 10.5 | 0.5 | 3.4 | 2.5 | 40 | <0.1 | 0.5 | <0.1 | 89 | 0.66 | 0.045 |
| 1321053 | Soil | | 0.5 | 41.5 | 5.1 | 44 | <0.1 | 30.8 | 12.9 | 476 | 2.98 | 6.6 | 0.6 | 1.8 | 2.1 | 51 | <0.1 | 0.4 | <0.1 | 81 | 1.46 | 0.043 |
| 1321054 | Soil | | 0.4 | 25.2 | 3.6 | 34 | <0.1 | 19.6 | 9.7 | 384 | 1.89 | 2.5 | 0.6 | 1.9 | 0.9 | 64 | 0.1 | 0.3 | <0.1 | 49 | 2.13 | 0.054 |
| 1321055 | Soil | | 0.4 | 41.0 | 6.0 | 61 | 0.2 | 30.8 | 11.4 | 218 | 2.64 | 4.0 | 0.7 | 889.1 | 2.8 | 54 | 0.1 | 0.4 | <0.1 | 89 | 1.27 | 0.064 |
| 1321056 | Soil | | 0.5 | 31.5 | 3.8 | 51 | <0.1 | 27.3 | 11.1 | 522 | 2.62 | 4.0 | 0.5 | 0.9 | 1.4 | 52 | 0.1 | 0.3 | <0.1 | 76 | 1.38 | 0.073 |
| 1321057 | Soil | | 0.3 | 26.8 | 4.7 | 56 | <0.1 | 25.8 | 10.5 | 276 | 2.58 | 4.6 | 0.6 | 3.5 | 2.4 | 48 | 0.1 | 0.4 | <0.1 | 76 | 1.02 | 0.074 |
| 1321058 | Soil | | 0.5 | 23.4 | 4.9 | 53 | <0.1 | 27.6 | 11.6 | 436 | 2.89 | 6.9 | 0.6 | 2.6 | 2.1 | 53 | 0.1 | 0.6 | <0.1 | 71 | 1.13 | 0.069 |
| 1321059 | Soil | | 0.5 | 48.4 | 5.0 | 53 | <0.1 | 34.8 | 13.8 | 531 | 3.04 | 4.7 | 0.5 | 3.4 | 2.4 | 118 | 0.1 | 0.4 | <0.1 | 80 | 5.04 | 0.076 |
| 1321060 | Soil | | 0.7 | 26.7 | 6.5 | 47 | <0.1 | 31.9 | 14.7 | 515 | 3.67 | 7.7 | 0.4 | 36.3 | 3.2 | 44 | <0.1 | 0.5 | <0.1 | 90 | 0.81 | 0.023 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321031 | Soil | 12 | 42 | 0.79 | 187 | 0.115 | 3 | 2.08 | 0.046 | 0.07 | <0.1 | 0.03 | 7.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321032 | Soil | 12 | 38 | 1.07 | 132 | 0.122 | 4 | 1.52 | 0.065 | 0.09 | <0.1 | 0.03 | 7.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321033 | Soil | 13 | 41 | 0.76 | 194 | 0.104 | 3 | 2.04 | 0.046 | 0.07 | <0.1 | 0.04 | 6.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321034 | Soil | 13 | 34 | 0.70 | 304 | 0.112 | 4 | 1.82 | 0.053 | 0.06 | 0.1 | 0.04 | 5.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321035 | Soil | 11 | 33 | 0.83 | 152 | 0.130 | 5 | 1.61 | 0.069 | 0.07 | 0.1 | 0.03 | 5.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321036 | Soil | 9 | 35 | 0.51 | 279 | 0.088 | 2 | 2.15 | 0.017 | 0.12 | <0.1 | 0.02 | 4.1 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321037 | Soil | 5 | 22 | 0.22 | 308 | 0.063 | 3 | 1.13 | 0.028 | 0.08 | <0.1 | 0.02 | 2.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321038 | Soil | 13 | 24 | 0.38 | 471 | 0.065 | 3 | 1.23 | 0.050 | 0.08 | <0.1 | 0.06 | 3.7 | 0.4 | 0.14 | 4 | 1.6 | <0.2 |
| 1321039 | Soil | 14 | 31 | 0.50 | 305 | 0.078 | 3 | 1.94 | 0.043 | 0.06 | <0.1 | 0.08 | 4.3 | 0.2 | 0.08 | 5 | 1.9 | <0.2 |
| 1321040 | Soil | 13 | 36 | 0.55 | 358 | 0.080 | 2 | 2.10 | 0.039 | 0.06 | <0.1 | 0.07 | 5.3 | 0.1 | <0.05 | 6 | 1.3 | <0.2 |
| 1321041 | Soil | 12 | 45 | 0.68 | 236 | 0.096 | 2 | 2.61 | 0.029 | 0.05 | <0.1 | 0.02 | 5.4 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321042 | Soil | 15 | 47 | 0.66 | 214 | 0.093 | 2 | 2.01 | 0.030 | 0.05 | 0.1 | 0.02 | 5.5 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321043 | Soil | 12 | 48 | 0.79 | 183 | 0.127 | 2 | 2.31 | 0.038 | 0.05 | <0.1 | 0.03 | 5.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321044 | Soil | 13 | 50 | 0.77 | 195 | 0.118 | 1 | 2.48 | 0.035 | 0.05 | <0.1 | 0.02 | 6.8 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321045 | Soil | 15 | 54 | 0.75 | 212 | 0.110 | 2 | 2.61 | 0.031 | 0.06 | <0.1 | 0.04 | 7.6 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321046 | Soil | 9 | 44 | 0.71 | 142 | 0.121 | 2 | 2.42 | 0.025 | 0.08 | <0.1 | 0.03 | 4.5 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321047 | Soil | 11 | 47 | 0.70 | 186 | 0.109 | 1 | 2.35 | 0.031 | 0.05 | <0.1 | 0.03 | 5.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321048 | Soil | 11 | 54 | 0.82 | 187 | 0.128 | 1 | 2.60 | 0.032 | 0.05 | <0.1 | 0.02 | 5.6 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321049 | Soil | 13 | 51 | 0.75 | 201 | 0.113 | 2 | 2.39 | 0.038 | 0.05 | 0.1 | 0.04 | 6.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321050 | Soil | 12 | 56 | 0.86 | 192 | 0.122 | 1 | 2.57 | 0.036 | 0.05 | <0.1 | 0.03 | 6.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321051 | Soil | 9 | 44 | 0.59 | 172 | 0.102 | 2 | 2.13 | 0.040 | 0.06 | <0.1 | 0.03 | 5.0 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321052 | Soil | 9 | 55 | 0.85 | 191 | 0.124 | 1 | 2.49 | 0.032 | 0.05 | 0.1 | 0.02 | 5.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321053 | Soil | 13 | 37 | 0.76 | 197 | 0.111 | 1 | 1.89 | 0.054 | 0.05 | <0.1 | 0.04 | 6.1 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321054 | Soil | 8 | 24 | 0.50 | 132 | 0.073 | 3 | 1.20 | 0.045 | 0.04 | <0.1 | 0.03 | 3.7 | <0.1 | 0.13 | 3 | <0.5 | <0.2 |
| 1321055 | Soil | 14 | 42 | 0.86 | 156 | 0.141 | 3 | 1.92 | 0.061 | 0.09 | 0.1 | 0.04 | 7.8 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321056 | Soil | 10 | 30 | 0.74 | 118 | 0.114 | 4 | 1.41 | 0.075 | 0.06 | <0.1 | 0.02 | 5.2 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321057 | Soil | 11 | 34 | 0.74 | 113 | 0.129 | 3 | 1.65 | 0.074 | 0.06 | <0.1 | 0.04 | 5.1 | <0.1 | 0.06 | 5 | <0.5 | <0.2 |
| 1321058 | Soil | 10 | 35 | 0.72 | 140 | 0.116 | 3 | 1.76 | 0.063 | 0.06 | <0.1 | 0.06 | 5.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321059 | Soil | 11 | 38 | 1.14 | 153 | 0.137 | 5 | 1.77 | 0.086 | 0.11 | <0.1 | 0.03 | 6.6 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321060 | Soil | 13 | 47 | 0.77 | 187 | 0.141 | 3 | 2.36 | 0.054 | 0.11 | <0.1 | 0.02 | 9.1 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321061 | Soil | | 0.7 | 28.1 | 5.6 | 52 | <0.1 | 28.4 | 13.6 | 555 | 3.44 | 5.3 | 0.3 | 1.0 | 2.6 | 39 | 0.1 | 0.4 | <0.1 | 84 | 0.94 | 0.036 |
| 1321062 | Soil | | 0.5 | 40.5 | 4.8 | 63 | 0.1 | 34.6 | 14.2 | 654 | 3.22 | 4.7 | 0.3 | 3.0 | 2.1 | 75 | 0.2 | 0.3 | <0.1 | 79 | 2.26 | 0.087 |
| 1321063 | Soil | | 0.6 | 34.3 | 4.0 | 49 | <0.1 | 33.0 | 13.1 | 482 | 3.07 | 5.0 | 0.3 | 1.7 | 2.0 | 60 | <0.1 | 0.3 | <0.1 | 83 | 1.90 | 0.072 |
| 1321064 | Soil | | 1.0 | 28.6 | 6.2 | 45 | <0.1 | 29.7 | 14.7 | 579 | 3.42 | 5.9 | 0.3 | 14.9 | 2.4 | 34 | <0.1 | 0.4 | <0.1 | 83 | 0.64 | 0.020 |
| 1321065 | Soil | | 1.0 | 40.2 | 5.3 | 62 | <0.1 | 40.4 | 15.6 | 577 | 3.85 | 7.5 | 0.6 | 3.9 | 3.0 | 54 | 0.1 | 0.5 | <0.1 | 102 | 0.90 | 0.036 |
| 1321066 | Soil | | 0.6 | 47.4 | 6.1 | 63 | <0.1 | 37.3 | 15.0 | 540 | 3.50 | 5.7 | 0.4 | 4.2 | 3.0 | 55 | <0.1 | 0.4 | <0.1 | 94 | 1.15 | 0.066 |
| 1321067 | Soil | | 0.3 | 41.1 | 5.9 | 55 | <0.1 | 32.5 | 13.4 | 549 | 3.19 | 7.2 | 0.9 | 4.0 | 2.6 | 55 | 0.1 | 0.4 | <0.1 | 81 | 1.07 | 0.059 |
| 1321068 | Soil | | 0.5 | 32.6 | 5.3 | 53 | <0.1 | 25.3 | 11.7 | 335 | 2.72 | 5.7 | 0.5 | 3.4 | 2.3 | 50 | 0.1 | 0.4 | <0.1 | 74 | 0.88 | 0.068 |
| 1321069 | Soil | | 0.4 | 22.0 | 4.3 | 49 | <0.1 | 21.3 | 10.4 | 261 | 2.29 | 8.8 | 0.6 | 4.0 | 2.3 | 51 | <0.1 | 0.3 | <0.1 | 64 | 0.96 | 0.072 |
| 1321070 | Soil | | 0.5 | 54.7 | 5.5 | 53 | <0.1 | 34.8 | 13.5 | 414 | 3.29 | 5.7 | 1.0 | 15.7 | 2.4 | 60 | <0.1 | 0.5 | <0.1 | 83 | 1.38 | 0.051 |
| 1321071 | Soil | | 0.9 | 38.6 | 6.6 | 53 | <0.1 | 36.4 | 15.3 | 397 | 4.00 | 6.5 | 0.5 | 24.2 | 2.9 | 37 | <0.1 | 0.4 | <0.1 | 100 | 0.72 | 0.024 |
| 1321072 | Soil | | 1.1 | 41.9 | 5.9 | 65 | <0.1 | 38.8 | 17.5 | 740 | 3.94 | 5.9 | 0.6 | 2.1 | 3.8 | 109 | <0.1 | 0.4 | <0.1 | 97 | 2.76 | 0.082 |
| 1321073 | Soil | | 0.6 | 41.2 | 4.8 | 41 | <0.1 | 30.2 | 11.9 | 579 | 2.59 | 5.7 | 1.8 | 2.6 | 1.7 | 118 | 0.1 | 0.6 | <0.1 | 61 | 3.18 | 0.069 |
| 1321074 | Soil | | 0.7 | 39.8 | 5.7 | 51 | <0.1 | 33.3 | 13.4 | 463 | 3.15 | 7.6 | 0.4 | 3.8 | 2.7 | 51 | <0.1 | 0.5 | 0.1 | 88 | 1.17 | 0.046 |
| 1321075 | Soil | | 1.1 | 26.8 | 7.7 | 47 | <0.1 | 32.4 | 14.0 | 519 | 3.47 | 7.5 | 0.6 | 3.4 | 2.7 | 34 | <0.1 | 0.4 | 0.1 | 89 | 0.64 | 0.018 |
| 1321076 | Soil | | 1.2 | 23.0 | 14.8 | 62 | <0.1 | 28.5 | 12.9 | 424 | 3.20 | 14.5 | 0.5 | 3.3 | 4.0 | 23 | 0.1 | 0.5 | 0.2 | 71 | 0.30 | 0.032 |
| 1321077 | Soil | | 1.0 | 29.6 | 14.5 | 54 | 0.3 | 24.6 | 11.0 | 348 | 2.47 | 12.5 | 0.9 | 17.4 | 1.4 | 39 | 0.2 | 0.5 | 0.2 | 52 | 0.49 | 0.058 |
| 1321078 | Soil | | 0.6 | 22.5 | 14.8 | 59 | 0.2 | 24.7 | 11.6 | 944 | 2.28 | 8.3 | 0.8 | 2.4 | 3.8 | 40 | 0.2 | 0.4 | 0.1 | 51 | 0.73 | 0.038 |
| 1321079 | Soil | | 0.5 | 26.8 | 24.3 | 58 | 0.3 | 27.5 | 12.3 | 955 | 2.22 | 15.2 | 1.1 | 5.5 | 5.3 | 54 | 0.2 | 0.7 | 0.2 | 36 | 1.24 | 0.051 |
| 1321080 | Soil | | 1.6 | 15.1 | 19.2 | 53 | 0.2 | 15.7 | 7.4 | 243 | 2.02 | 50.4 | 0.6 | 31.2 | 4.7 | 27 | 0.2 | 1.3 | 0.2 | 40 | 0.38 | 0.033 |
| 1321081 | Soil | | 4.6 | 39.7 | 11.2 | 184 | 0.5 | 46.8 | 15.8 | 1095 | 3.06 | 23.5 | 1.2 | 10.8 | 2.4 | 126 | 1.6 | 3.0 | 0.2 | 61 | 1.66 | 0.106 |
| 1321082 | Soil | | 5.8 | 45.5 | 16.2 | 233 | 0.6 | 55.2 | 14.6 | 545 | 3.69 | 29.5 | 0.8 | 2.4 | 4.8 | 55 | 1.4 | 3.0 | 0.3 | 95 | 0.44 | 0.117 |
| 1321083 | Soil | | 1.7 | 25.9 | 8.6 | 70 | 0.3 | 29.9 | 11.7 | 311 | 2.90 | 8.0 | 0.7 | 1.8 | 2.3 | 87 | 0.8 | 0.9 | 0.1 | 72 | 1.12 | 0.035 |
| 1321084 | Soil | | 8.9 | 56.7 | 15.7 | 190 | 0.5 | 58.6 | 19.7 | 634 | 4.04 | 39.9 | 1.2 | 14.3 | 7.2 | 59 | 0.8 | 4.0 | 0.2 | 71 | 0.79 | 0.154 |
| 1321085 | Soil | | 2.9 | 27.4 | 8.4 | 80 | 0.3 | 30.7 | 12.1 | 352 | 2.71 | 8.2 | 0.5 | 0.9 | 2.4 | 41 | 0.4 | 0.9 | 0.1 | 66 | 0.65 | 0.038 |
| 1321086 | Soil | | 6.6 | 59.2 | 20.7 | 193 | 0.5 | 62.5 | 21.1 | 709 | 4.01 | 27.6 | 1.5 | 8.6 | 9.9 | 131 | 0.8 | 5.2 | 0.3 | 54 | 2.78 | 0.312 |
| 1321087 | Soil | | 15.1 | 44.6 | 23.3 | 145 | 0.6 | 54.6 | 14.0 | 375 | 4.16 | 27.7 | 0.9 | 4.0 | 6.7 | 84 | 0.8 | 4.7 | 0.3 | 92 | 0.35 | 0.060 |
| 1321088 | Soil | | 2.2 | 21.0 | 9.0 | 91 | 0.3 | 23.6 | 12.5 | 1166 | 2.47 | 15.2 | 0.4 | 2.4 | 3.1 | 36 | 0.5 | 1.4 | 0.2 | 54 | 0.47 | 0.039 |
| 1321089 | Soil | | 1.4 | 22.0 | 11.8 | 42 | 0.1 | 13.7 | 6.6 | 189 | 2.18 | 42.4 | 0.5 | 11.7 | 6.0 | 29 | 0.2 | 0.9 | 0.2 | 52 | 0.34 | 0.025 |
| 1321090 | Soil | | 0.7 | 38.4 | 14.2 | 64 | 0.2 | 33.0 | 13.5 | 619 | 3.14 | 14.8 | 0.7 | 2.9 | 5.5 | 45 | <0.1 | 0.8 | 0.2 | 68 | 0.95 | 0.031 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321061 | Soil | 12 | 42 | 0.70 | 148 | 0.128 | 4 | 2.14 | 0.047 | 0.26 | <0.1 | 0.02 | 7.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321062 | Soil | 12 | 42 | 0.97 | 164 | 0.123 | 6 | 2.02 | 0.071 | 0.16 | <0.1 | 0.03 | 7.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321063 | Soil | 12 | 38 | 0.88 | 97 | 0.130 | 5 | 1.74 | 0.065 | 0.15 | <0.1 | 0.02 | 6.2 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321064 | Soil | 11 | 46 | 0.64 | 176 | 0.123 | 2 | 2.38 | 0.041 | 0.10 | <0.1 | 0.02 | 7.8 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321065 | Soil | 29 | 54 | 0.84 | 181 | 0.133 | 2 | 2.64 | 0.064 | 0.08 | <0.1 | 0.02 | 10.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321066 | Soil | 14 | 46 | 0.99 | 146 | 0.151 | 3 | 2.18 | 0.082 | 0.08 | <0.1 | 0.04 | 8.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321067 | Soil | 13 | 38 | 0.72 | 182 | 0.124 | 2 | 1.95 | 0.060 | 0.07 | <0.1 | 0.03 | 6.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321068 | Soil | 11 | 35 | 0.68 | 160 | 0.117 | 1 | 1.82 | 0.061 | 0.06 | 0.1 | 0.03 | 5.6 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321069 | Soil | 10 | 30 | 0.62 | 123 | 0.122 | 2 | 1.57 | 0.061 | 0.05 | 0.1 | 0.03 | 4.9 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321070 | Soil | 13 | 41 | 0.86 | 183 | 0.128 | 3 | 2.07 | 0.069 | 0.08 | <0.1 | 0.04 | 7.1 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321071 | Soil | 14 | 56 | 0.84 | 159 | 0.134 | 2 | 2.75 | 0.051 | 0.08 | <0.1 | 0.02 | 11.3 | <0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1321072 | Soil | 15 | 52 | 1.15 | 147 | 0.149 | 4 | 2.18 | 0.082 | 0.13 | <0.1 | 0.01 | 8.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321073 | Soil | 10 | 31 | 0.77 | 196 | 0.088 | 7 | 1.60 | 0.058 | 0.06 | 0.1 | 0.02 | 5.1 | <0.1 | 0.08 | 5 | 1.0 | <0.2 |
| 1321074 | Soil | 13 | 39 | 0.81 | 156 | 0.131 | 4 | 1.84 | 0.062 | 0.07 | 0.1 | 0.02 | 5.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321075 | Soil | 10 | 51 | 0.67 | 192 | 0.113 | 2 | 2.40 | 0.038 | 0.06 | <0.1 | 0.02 | 6.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321076 | Soil | 14 | 35 | 0.55 | 155 | 0.088 | 2 | 2.21 | 0.019 | 0.07 | <0.1 | 0.01 | 3.8 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321077 | Soil | 18 | 29 | 0.36 | 155 | 0.037 | 3 | 2.01 | 0.018 | 0.07 | <0.1 | 0.04 | 4.0 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321078 | Soil | 20 | 27 | 0.34 | 162 | 0.053 | 2 | 1.58 | 0.029 | 0.08 | <0.1 | 0.03 | 4.1 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321079 | Soil | 22 | 24 | 0.35 | 138 | 0.037 | 4 | 1.47 | 0.026 | 0.09 | <0.1 | 0.06 | 4.2 | <0.1 | 0.05 | 4 | <0.5 | <0.2 |
| 1321080 | Soil | 20 | 19 | 0.30 | 149 | 0.040 | 2 | 1.32 | 0.019 | 0.11 | <0.1 | 0.03 | 2.8 | 0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321081 | Soil | 17 | 31 | 0.58 | 437 | 0.044 | 3 | 1.88 | 0.034 | 0.07 | <0.1 | 0.06 | 5.8 | 0.1 | <0.05 | 5 | 2.5 | <0.2 |
| 1321082 | Soil | 15 | 37 | 0.63 | 309 | 0.069 | 3 | 2.25 | 0.021 | 0.10 | <0.1 | 0.02 | 4.0 | 0.2 | <0.05 | 7 | 1.2 | <0.2 |
| 1321083 | Soil | 9 | 39 | 0.60 | 233 | 0.072 | 3 | 1.93 | 0.029 | 0.06 | <0.1 | 0.04 | 4.1 | 0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1321084 | Soil | 23 | 40 | 1.48 | 353 | 0.039 | 2 | 2.38 | 0.017 | 0.11 | 0.1 | 0.04 | 7.8 | 0.2 | <0.05 | 6 | 1.2 | <0.2 |
| 1321085 | Soil | 10 | 38 | 0.55 | 222 | 0.070 | 2 | 2.03 | 0.032 | 0.05 | <0.1 | 0.02 | 4.8 | 0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321086 | Soil | 31 | 25 | 0.94 | 279 | 0.016 | 3 | 1.68 | 0.013 | 0.13 | <0.1 | 0.06 | 6.9 | 0.2 | <0.05 | 5 | 1.1 | <0.2 |
| 1321087 | Soil | 20 | 59 | 0.73 | 473 | 0.036 | 3 | 2.01 | 0.039 | 0.19 | <0.1 | 0.01 | 4.7 | 0.3 | 0.25 | 7 | 2.6 | <0.2 |
| 1321088 | Soil | 17 | 24 | 0.38 | 284 | 0.036 | 2 | 1.49 | 0.031 | 0.08 | <0.1 | 0.02 | 2.8 | 0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321089 | Soil | 23 | 20 | 0.31 | 162 | 0.041 | 1 | 1.48 | 0.028 | 0.10 | <0.1 | 0.02 | 2.6 | 0.1 | 0.06 | 6 | <0.5 | <0.2 |
| 1321090 | Soil | 22 | 36 | 0.56 | 242 | 0.075 | 3 | 2.03 | 0.041 | 0.07 | <0.1 | 0.04 | 6.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321091 | Soil | | 1.2 | 17.0 | 12.1 | 63 | <0.1 | 25.2 | 10.9 | 436 | 3.30 | 11.3 | 0.5 | 1.1 | 3.2 | 25 | 0.1 | 0.5 | 0.2 | 80 | 0.30 | 0.038 |
| 1321092 | Soil | | 2.1 | 32.0 | 10.3 | 69 | 0.2 | 36.7 | 13.6 | 574 | 3.57 | 10.5 | 0.9 | 1.6 | 4.4 | 65 | 0.3 | 1.1 | 0.1 | 73 | 0.99 | 0.124 |
| 1321093 | Soil | | 1.9 | 57.4 | 8.4 | 65 | 0.2 | 108.5 | 20.4 | 666 | 4.45 | 11.6 | 0.8 | 1.9 | 4.2 | 50 | <0.1 | 0.7 | 0.1 | 115 | 0.62 | 0.078 |
| 1321094 | Soil | | 5.5 | 39.8 | 12.1 | 100 | 0.2 | 41.8 | 17.2 | 554 | 3.62 | 13.8 | 0.9 | 2.7 | 5.4 | 62 | 0.3 | 1.7 | 0.2 | 73 | 0.87 | 0.128 |
| 1321095 | Soil | | 1.1 | 27.4 | 6.9 | 46 | <0.1 | 32.5 | 14.0 | 332 | 3.50 | 9.3 | 0.6 | 4.5 | 3.5 | 35 | <0.1 | 0.5 | 0.1 | 95 | 0.47 | 0.016 |
| 1321096 | Soil | | 1.5 | 28.5 | 8.9 | 54 | 0.1 | 35.2 | 15.8 | 1507 | 3.40 | 7.5 | 0.5 | 0.7 | 2.9 | 36 | <0.1 | 0.6 | 0.1 | 90 | 0.39 | 0.019 |
| 1321097 | Soil | | 0.8 | 61.0 | 9.6 | 64 | 0.1 | 39.4 | 15.5 | 1154 | 3.07 | 8.2 | 1.0 | 3.1 | 3.1 | 57 | 0.2 | 0.6 | 0.1 | 79 | 0.93 | 0.061 |
| 1321098 | Soil | | 1.7 | 25.7 | 8.3 | 60 | 0.2 | 32.3 | 12.7 | 484 | 3.42 | 8.0 | 0.5 | 2.6 | 2.7 | 37 | <0.1 | 0.6 | 0.1 | 94 | 0.52 | 0.015 |
| 1321099 | Soil | | 0.6 | 41.5 | 5.5 | 61 | <0.1 | 34.1 | 13.7 | 553 | 3.31 | 6.5 | 0.4 | 2.3 | 2.9 | 50 | <0.1 | 0.4 | <0.1 | 90 | 0.95 | 0.062 |
| 1321100 | Soil | | 0.7 | 42.9 | 6.5 | 67 | 0.2 | 32.0 | 10.7 | 666 | 2.71 | 6.5 | 0.7 | 2.1 | 2.4 | 58 | 0.2 | 0.5 | 0.1 | 72 | 1.05 | 0.054 |
| 1321101 | Soil | | 0.6 | 49.7 | 5.8 | 62 | 0.1 | 33.6 | 12.6 | 469 | 3.15 | 6.6 | 0.5 | 2.5 | 2.5 | 58 | 0.1 | 0.5 | <0.1 | 81 | 1.36 | 0.069 |
| 1321102 | Soil | | 0.7 | 24.5 | 4.7 | 40 | <0.1 | 22.4 | 13.1 | 498 | 2.49 | 6.5 | 0.8 | <0.5 | 1.8 | 57 | <0.1 | 0.3 | <0.1 | 67 | 1.40 | 0.056 |
| 1321103 | Soil | | 0.6 | 41.8 | 5.9 | 54 | <0.1 | 34.3 | 14.7 | 553 | 3.21 | 7.0 | 1.2 | 1.2 | 3.0 | 54 | 0.1 | 0.5 | <0.1 | 80 | 1.08 | 0.060 |
| 1321104 | Soil | | 0.5 | 33.2 | 5.0 | 58 | <0.1 | 30.1 | 12.8 | 487 | 3.06 | 7.4 | 0.6 | 1.3 | 2.9 | 54 | 0.1 | 0.4 | <0.1 | 84 | 1.17 | 0.080 |
| 1321105 | Soil | | 0.5 | 24.7 | 4.8 | 49 | <0.1 | 21.0 | 10.6 | 314 | 2.39 | 4.3 | 0.6 | 1.0 | 1.6 | 55 | 0.2 | 0.3 | <0.1 | 65 | 1.29 | 0.059 |
| 1321106 | Soil | | 0.4 | 31.9 | 4.9 | 48 | <0.1 | 26.3 | 11.1 | 426 | 2.56 | 4.3 | 0.8 | 1.6 | 2.2 | 54 | 0.2 | 0.4 | <0.1 | 71 | 1.27 | 0.061 |
| 1321107 | Soil | | 0.5 | 26.6 | 5.1 | 51 | <0.1 | 25.4 | 12.1 | 462 | 2.64 | 5.1 | 0.7 | 8.1 | 2.1 | 57 | 0.1 | 0.3 | <0.1 | 74 | 1.29 | 0.060 |
| 1321108 | Soil | | 0.4 | 30.5 | 5.4 | 58 | <0.1 | 26.1 | 13.0 | 501 | 2.79 | 5.0 | 0.8 | 1.4 | 2.6 | 56 | 0.2 | 0.4 | <0.1 | 78 | 1.23 | 0.065 |
| 1321109 | Soil | | 0.5 | 36.4 | 5.1 | 53 | <0.1 | 28.5 | 11.6 | 509 | 2.70 | 5.1 | 0.6 | 4.1 | 2.7 | 52 | 0.1 | 0.4 | 0.1 | 77 | 1.16 | 0.068 |
| 1321110 | Soil | | 0.4 | 42.1 | 4.9 | 54 | <0.1 | 28.1 | 11.5 | 353 | 2.65 | 4.1 | 0.7 | 2.4 | 2.6 | 53 | 0.2 | 0.4 | <0.1 | 77 | 1.45 | 0.072 |
| 1321111 | Soil | | 0.8 | 30.9 | 6.6 | 68 | <0.1 | 36.6 | 15.0 | 666 | 3.32 | 6.2 | 0.5 | 2.6 | 2.8 | 44 | 0.2 | 0.3 | 0.1 | 92 | 1.01 | 0.075 |
| 1321112 | Soil | | 0.8 | 19.5 | 5.2 | 45 | <0.1 | 19.6 | 9.1 | 436 | 2.38 | 3.9 | 0.3 | 3.0 | 1.5 | 19 | 0.1 | 0.4 | <0.1 | 66 | 0.33 | 0.026 |
| 1321113 | Soil | | 0.7 | 40.8 | 5.6 | 49 | <0.1 | 33.7 | 14.4 | 371 | 3.39 | 6.1 | 0.5 | 3.5 | 3.0 | 43 | 0.1 | 0.4 | <0.1 | 91 | 1.03 | 0.039 |
| 1321114 | Soil | | 0.5 | 28.5 | 5.5 | 46 | <0.1 | 24.6 | 12.4 | 443 | 2.57 | 5.4 | 1.1 | 3.4 | 2.2 | 54 | 0.2 | 0.3 | 0.1 | 75 | 1.20 | 0.050 |
| 1321115 | Soil | | 1.5 | 42.6 | 9.2 | 115 | 0.4 | 39.7 | 12.6 | 399 | 3.01 | 13.6 | 1.2 | 12.7 | 3.8 | 60 | 1.3 | 1.8 | 0.2 | 75 | 1.15 | 0.081 |
| 1321116 | Soil | | 4.1 | 39.2 | 12.2 | 130 | 1.2 | 40.8 | 10.1 | 451 | 2.52 | 9.1 | 0.7 | 6.1 | 4.5 | 65 | 2.4 | 3.1 | 0.2 | 44 | 1.25 | 0.147 |
| 1321117 | Soil | | 1.8 | 24.6 | 9.0 | 85 | 0.3 | 30.2 | 10.8 | 254 | 2.61 | 12.6 | 0.9 | 4.8 | 3.1 | 53 | 0.7 | 1.4 | 0.1 | 70 | 0.90 | 0.042 |
| 1321118 | Soil | | 0.6 | 35.4 | 5.5 | 51 | <0.1 | 27.0 | 11.6 | 393 | 2.76 | 5.1 | 0.9 | 2.6 | 2.4 | 53 | 0.2 | 0.4 | <0.1 | 77 | 1.21 | 0.057 |
| 1321119 | Soil | | 1.5 | 30.8 | 7.9 | 83 | 0.2 | 32.4 | 16.2 | 1015 | 2.78 | 13.6 | 1.0 | 10.4 | 2.6 | 59 | 0.7 | 1.1 | 0.1 | 69 | 1.29 | 0.078 |
| 1321120 | Soil | | 1.6 | 42.2 | 10.1 | 112 | 0.5 | 40.6 | 12.0 | 380 | 2.82 | 13.1 | 0.9 | 6.9 | 4.4 | 63 | 1.1 | 2.0 | 0.2 | 68 | 1.23 | 0.084 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321091 | Soil | | 12 | 35 | 0.50 | 165 | 0.089 | 2 | 1.88 | 0.020 | 0.08 | <0.1 | <0.01 | 3.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321092 | Soil | | 17 | 40 | 0.63 | 339 | 0.070 | 2 | 2.14 | 0.035 | 0.07 | <0.1 | 0.03 | 7.4 | 0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321093 | Soil | | 15 | 162 | 1.59 | 483 | 0.172 | 2 | 3.15 | 0.033 | 0.13 | 0.1 | 0.03 | 9.6 | 0.3 | <0.05 | 9 | <0.5 | <0.2 |
| 1321094 | Soil | | 19 | 37 | 0.62 | 516 | 0.038 | 2 | 2.12 | 0.024 | 0.09 | <0.1 | 0.03 | 5.7 | 0.2 | <0.05 | 6 | 1.0 | <0.2 |
| 1321095 | Soil | | 9 | 52 | 0.77 | 344 | 0.139 | 2 | 2.52 | 0.034 | 0.06 | <0.1 | 0.01 | 6.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321096 | Soil | | 10 | 48 | 0.64 | 483 | 0.106 | 1 | 2.78 | 0.031 | 0.04 | <0.1 | 0.03 | 6.2 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321097 | Soil | | 14 | 42 | 0.70 | 297 | 0.120 | 3 | 1.99 | 0.060 | 0.06 | <0.1 | 0.03 | 7.4 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321098 | Soil | | 10 | 51 | 0.70 | 492 | 0.093 | 2 | 2.72 | 0.022 | 0.04 | <0.1 | 0.01 | 5.7 | 0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1321099 | Soil | | 14 | 42 | 0.81 | 174 | 0.133 | 2 | 1.95 | 0.076 | 0.06 | <0.1 | 0.03 | 6.6 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321100 | Soil | | 11 | 35 | 0.61 | 244 | 0.102 | 2 | 1.79 | 0.056 | 0.06 | <0.1 | 0.03 | 5.2 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321101 | Soil | | 13 | 40 | 0.84 | 195 | 0.124 | 4 | 2.04 | 0.066 | 0.08 | <0.1 | 0.04 | 6.5 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321102 | Soil | | 10 | 30 | 0.58 | 146 | 0.098 | 3 | 1.51 | 0.049 | 0.04 | <0.1 | 0.03 | 4.5 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321103 | Soil | | 13 | 40 | 0.74 | 199 | 0.120 | 3 | 2.02 | 0.060 | 0.06 | <0.1 | 0.04 | 6.5 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1321104 | Soil | | 12 | 37 | 0.77 | 135 | 0.133 | 3 | 1.68 | 0.070 | 0.07 | <0.1 | 0.02 | 5.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321105 | Soil | | 9 | 30 | 0.61 | 157 | 0.101 | 3 | 1.69 | 0.056 | 0.05 | <0.1 | 0.03 | 4.3 | <0.1 | 0.05 | 5 | <0.5 | <0.2 |
| 1321106 | Soil | | 11 | 33 | 0.67 | 167 | 0.116 | 2 | 1.79 | 0.061 | 0.05 | <0.1 | 0.02 | 5.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321107 | Soil | | 11 | 33 | 0.62 | 172 | 0.117 | 3 | 1.59 | 0.056 | 0.06 | 0.1 | 0.02 | 4.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321108 | Soil | | 12 | 36 | 0.73 | 152 | 0.127 | 3 | 1.79 | 0.066 | 0.06 | 0.1 | 0.03 | 5.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321109 | Soil | | 12 | 37 | 0.71 | 149 | 0.121 | 3 | 1.74 | 0.062 | 0.06 | 0.1 | 0.03 | 5.4 | <0.1 | <0.05 | 5 | 0.9 | <0.2 |
| 1321110 | Soil | | 13 | 37 | 0.84 | 144 | 0.122 | 4 | 1.72 | 0.067 | 0.07 | <0.1 | 0.03 | 5.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321111 | Soil | | 11 | 44 | 0.85 | 194 | 0.126 | 4 | 2.08 | 0.057 | 0.10 | <0.1 | <0.01 | 6.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321112 | Soil | | 5 | 29 | 0.44 | 141 | 0.093 | 2 | 1.67 | 0.039 | 0.07 | <0.1 | <0.01 | 3.2 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321113 | Soil | | 13 | 45 | 0.77 | 211 | 0.127 | 4 | 2.23 | 0.054 | 0.07 | <0.1 | 0.02 | 6.9 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1321114 | Soil | | 10 | 34 | 0.66 | 174 | 0.107 | 3 | 1.90 | 0.051 | 0.04 | <0.1 | 0.03 | 5.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321115 | Soil | | 14 | 47 | 0.77 | 286 | 0.094 | 2 | 1.94 | 0.048 | 0.06 | 0.2 | 0.05 | 6.4 | <0.1 | <0.05 | 5 | 1.3 | <0.2 |
| 1321116 | Soil | | 20 | 25 | 0.58 | 273 | 0.035 | 2 | 1.44 | 0.033 | 0.08 | <0.1 | 0.07 | 4.3 | 0.1 | <0.05 | 4 | 2.5 | <0.2 |
| 1321117 | Soil | | 11 | 34 | 0.48 | 313 | 0.072 | 2 | 2.01 | 0.037 | 0.06 | <0.1 | 0.03 | 5.0 | <0.1 | <0.05 | 6 | 1.1 | <0.2 |
| 1321118 | Soil | | 11 | 36 | 0.70 | 159 | 0.114 | 3 | 1.94 | 0.060 | 0.05 | <0.1 | 0.03 | 5.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321119 | Soil | | 12 | 37 | 0.69 | 333 | 0.081 | 3 | 1.80 | 0.044 | 0.05 | <0.1 | 0.04 | 5.5 | <0.1 | 0.08 | 5 | 0.9 | <0.2 |
| 1321120 | Soil | | 15 | 47 | 0.75 | 274 | 0.091 | 2 | 1.93 | 0.050 | 0.06 | <0.1 | 0.05 | 6.4 | <0.1 | <0.05 | 5 | 1.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321121 | Soil | | 2.8 | 42.8 | 10.4 | 173 | 0.7 | 39.5 | 9.5 | 348 | 2.61 | 21.1 | 1.2 | 6.6 | 2.7 | 84 | 2.4 | 3.6 | 0.2 | 55 | 1.41 | 0.114 |
| 1321122 | Soil | | 3.0 | 49.4 | 8.8 | 99 | 0.4 | 32.9 | 11.7 | 360 | 2.89 | 16.8 | 1.4 | 8.2 | 3.7 | 66 | 0.9 | 2.2 | 0.1 | 71 | 0.90 | 0.086 |
| 1321123 | Soil | | 0.8 | 33.2 | 7.6 | 86 | 0.3 | 29.9 | 11.4 | 329 | 2.58 | 20.3 | 0.8 | 15.1 | 2.8 | 99 | 1.0 | 2.3 | 0.1 | 60 | 1.43 | 0.074 |
| 1321124 | Soil | | 0.7 | 36.8 | 7.8 | 69 | 0.3 | 39.2 | 13.6 | 540 | 2.65 | 86.5 | 1.5 | 29.4 | 3.3 | 56 | 0.5 | 1.9 | 0.1 | 61 | 0.97 | 0.063 |
| 1321125 | Soil | | 0.3 | 30.0 | 8.0 | 57 | 0.1 | 35.7 | 12.2 | 376 | 2.55 | 27.4 | 1.1 | 8.6 | 2.8 | 58 | 0.2 | 1.1 | 0.1 | 61 | 1.04 | 0.066 |
| 1321126 | Soil | | 0.6 | 30.2 | 9.9 | 56 | <0.1 | 28.2 | 10.0 | 283 | 2.65 | 6.8 | 1.0 | 4.2 | 4.3 | 41 | <0.1 | 0.8 | 0.1 | 57 | 0.71 | 0.050 |
| 1321127 | Soil | | 0.4 | 31.1 | 10.0 | 56 | <0.1 | 24.5 | 9.1 | 264 | 2.57 | 9.1 | 1.2 | 4.5 | 4.5 | 39 | <0.1 | 0.5 | 0.1 | 57 | 0.53 | 0.050 |
| 1321128 | Soil | | 0.4 | 24.6 | 10.3 | 55 | <0.1 | 20.0 | 8.3 | 239 | 2.47 | 12.4 | 0.9 | 9.5 | 4.8 | 35 | 0.1 | 0.5 | 0.1 | 52 | 0.50 | 0.049 |
| 1321129 | Soil | | 0.5 | 28.7 | 9.9 | 57 | <0.1 | 21.9 | 9.3 | 310 | 2.41 | 15.4 | 0.8 | 10.7 | 4.0 | 40 | 0.2 | 0.6 | 0.1 | 48 | 0.61 | 0.049 |
| 1321130 | Soil | | 0.6 | 28.4 | 11.9 | 57 | <0.1 | 24.6 | 12.7 | 346 | 3.23 | 17.6 | 0.6 | 6.3 | 3.9 | 37 | <0.1 | 0.4 | 0.1 | 81 | 0.61 | 0.037 |
| 1321131 | Soil | | 0.9 | 30.5 | 10.3 | 57 | <0.1 | 24.4 | 11.1 | 341 | 2.95 | 20.4 | 0.5 | 9.4 | 2.9 | 36 | 0.2 | 0.4 | 0.1 | 78 | 0.63 | 0.047 |
| 1321132 | Soil | | 1.0 | 33.8 | 9.9 | 54 | <0.1 | 34.3 | 14.0 | 456 | 3.30 | 13.4 | 0.7 | 9.2 | 5.1 | 39 | <0.1 | 0.6 | 0.1 | 82 | 0.57 | 0.032 |
| 1321133 | Soil | | 0.8 | 34.9 | 8.1 | 47 | <0.1 | 35.5 | 13.9 | 420 | 3.34 | 20.7 | 0.7 | 8.5 | 4.3 | 39 | <0.1 | 0.7 | 0.1 | 88 | 0.69 | 0.031 |
| 1321134 | Soil | | 1.0 | 38.2 | 8.7 | 54 | 0.3 | 39.5 | 15.5 | 480 | 3.57 | 10.5 | 0.8 | 4.7 | 3.9 | 36 | <0.1 | 0.6 | 0.1 | 99 | 0.62 | 0.022 |
| 1321135 | Soil | | 0.8 | 36.6 | 8.3 | 55 | 0.1 | 36.7 | 15.1 | 463 | 3.92 | 13.7 | 1.1 | 5.9 | 4.5 | 40 | <0.1 | 0.6 | 0.1 | 99 | 0.63 | 0.029 |
| 1321136 | Soil | | 1.2 | 21.6 | 8.4 | 56 | 0.2 | 28.2 | 12.7 | 380 | 3.38 | 8.8 | 0.4 | 3.2 | 2.7 | 30 | <0.1 | 0.6 | 0.1 | 91 | 0.41 | 0.023 |
| 1321137 | Soil | | 1.4 | 20.9 | 9.0 | 56 | <0.1 | 30.2 | 13.3 | 340 | 3.55 | 10.9 | 0.4 | 2.6 | 2.5 | 28 | 0.2 | 0.5 | 0.1 | 95 | 0.39 | 0.036 |
| 1321138 | Soil | | 1.3 | 20.8 | 9.3 | 51 | 0.2 | 28.1 | 10.8 | 251 | 3.45 | 9.4 | 0.4 | 3.3 | 2.5 | 30 | 0.1 | 0.5 | 0.1 | 93 | 0.41 | 0.023 |
| 1321139 | Soil | | 0.9 | 18.1 | 7.1 | 39 | 0.1 | 21.3 | 11.3 | 369 | 2.59 | 7.1 | 0.4 | 1.9 | 2.3 | 29 | <0.1 | 0.3 | 0.1 | 76 | 0.37 | 0.019 |
| 1321140 | Soil | | 0.9 | 36.4 | 8.7 | 51 | <0.1 | 38.8 | 16.3 | 447 | 3.77 | 11.4 | 0.9 | 5.3 | 4.7 | 39 | <0.1 | 0.5 | 0.1 | 97 | 0.49 | 0.021 |
| 1321141 | Soil | | 1.2 | 27.5 | 8.8 | 51 | <0.1 | 35.7 | 15.5 | 377 | 3.76 | 11.1 | 0.7 | 1.7 | 3.8 | 34 | <0.1 | 0.5 | 0.1 | 94 | 0.45 | 0.019 |
| 1321142 | Soil | | 0.7 | 29.5 | 5.9 | 47 | <0.1 | 27.5 | 13.0 | 370 | 3.05 | 6.6 | 0.9 | 2.7 | 2.7 | 47 | <0.1 | 0.4 | <0.1 | 85 | 0.83 | 0.059 |
| 1321143 | Soil | | 0.4 | 33.6 | 5.3 | 52 | <0.1 | 29.4 | 11.7 | 412 | 2.96 | 6.7 | 0.4 | 3.3 | 3.0 | 54 | 0.2 | 0.4 | <0.1 | 83 | 1.13 | 0.073 |
| 1321144 | Soil | | 0.8 | 36.5 | 6.4 | 56 | 0.1 | 31.9 | 12.5 | 359 | 3.13 | 9.1 | 1.0 | 7.9 | 2.9 | 48 | 0.2 | 1.3 | 0.1 | 80 | 0.80 | 0.071 |
| 1321145 | Soil | | 0.8 | 32.5 | 6.3 | 57 | 0.2 | 27.9 | 11.8 | 328 | 3.25 | 10.3 | 0.8 | 7.3 | 2.7 | 43 | 0.1 | 1.3 | 0.1 | 80 | 0.70 | 0.067 |
| 1321146 | Soil | | 1.1 | 38.6 | 7.6 | 56 | 0.2 | 32.3 | 14.1 | 353 | 3.53 | 13.5 | 1.1 | 5.8 | 3.2 | 49 | 0.1 | 1.9 | 0.1 | 88 | 0.77 | 0.069 |
| 1321147 | Soil | | 1.4 | 42.7 | 10.4 | 56 | 0.3 | 28.5 | 12.3 | 358 | 3.65 | 21.5 | 1.1 | 5.3 | 3.2 | 43 | 0.1 | 2.7 | 0.1 | 92 | 0.68 | 0.069 |
| 1321148 | Soil | | 1.1 | 29.0 | 7.4 | 56 | 0.3 | 32.3 | 14.5 | 310 | 4.05 | 10.6 | 0.6 | 5.7 | 2.4 | 33 | 0.2 | 0.5 | 0.1 | 106 | 0.56 | 0.061 |
| 1321149 | Soil | | 1.0 | 34.6 | 7.9 | 60 | 0.1 | 35.0 | 15.9 | 450 | 3.90 | 8.6 | 0.8 | 4.8 | 3.7 | 42 | <0.1 | 0.5 | 0.1 | 103 | 0.67 | 0.028 |
| 1321150 | Soil | | 2.0 | 36.1 | 19.2 | 71 | 1.0 | 28.1 | 10.4 | 539 | 3.76 | 32.8 | 1.6 | 5.5 | 3.6 | 41 | 0.2 | 2.9 | 0.2 | 96 | 0.52 | 0.112 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321121 | Soil | | 12 | 30 | 0.46 | 411 | 0.056 | 3 | 1.56 | 0.039 | 0.05 | <0.1 | 0.06 | 4.6 | 0.1 | 0.06 | 4 | 4.0 | <0.2 |
| 1321122 | Soil | | 13 | 35 | 0.61 | 287 | 0.107 | 3 | 1.76 | 0.054 | 0.06 | <0.1 | 0.06 | 6.1 | 0.1 | 0.08 | 5 | 1.8 | <0.2 |
| 1321123 | Soil | | 12 | 31 | 0.55 | 198 | 0.097 | 4 | 1.72 | 0.048 | 0.05 | 0.1 | 0.06 | 5.4 | <0.1 | <0.05 | 5 | 1.0 | <0.2 |
| 1321124 | Soil | | 13 | 41 | 0.65 | 463 | 0.101 | 4 | 1.91 | 0.047 | 0.06 | <0.1 | 0.04 | 7.4 | <0.1 | <0.05 | 5 | 1.0 | <0.2 |
| 1321125 | Soil | | 12 | 49 | 0.62 | 190 | 0.089 | 3 | 1.88 | 0.040 | 0.05 | <0.1 | 0.06 | 6.1 | <0.1 | <0.05 | 5 | 0.6 | <0.2 |
| 1321126 | Soil | | 14 | 39 | 0.55 | 171 | 0.111 | 2 | 1.99 | 0.041 | 0.05 | <0.1 | 0.04 | 5.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321127 | Soil | | 15 | 34 | 0.55 | 201 | 0.114 | 1 | 2.11 | 0.044 | 0.05 | <0.1 | 0.03 | 5.4 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321128 | Soil | | 14 | 28 | 0.48 | 158 | 0.103 | 1 | 1.85 | 0.036 | 0.05 | 0.1 | 0.02 | 4.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321129 | Soil | | 12 | 30 | 0.51 | 154 | 0.096 | 2 | 1.75 | 0.037 | 0.05 | 0.2 | 0.04 | 4.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321130 | Soil | | 12 | 41 | 0.59 | 157 | 0.117 | 1 | 2.31 | 0.033 | 0.05 | <0.1 | 0.03 | 5.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321131 | Soil | | 11 | 39 | 0.60 | 156 | 0.116 | 2 | 2.36 | 0.028 | 0.07 | <0.1 | 0.02 | 5.4 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321132 | Soil | | 15 | 50 | 0.62 | 143 | 0.119 | 2 | 2.16 | 0.038 | 0.06 | <0.1 | 0.02 | 8.8 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321133 | Soil | | 14 | 48 | 0.69 | 121 | 0.134 | 3 | 2.15 | 0.047 | 0.09 | <0.1 | 0.03 | 9.1 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321134 | Soil | | 18 | 55 | 0.79 | 138 | 0.134 | 1 | 2.37 | 0.051 | 0.07 | <0.1 | 0.04 | 9.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321135 | Soil | | 17 | 59 | 0.73 | 161 | 0.135 | 3 | 2.62 | 0.041 | 0.06 | <0.1 | 0.03 | 10.7 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321136 | Soil | | 9 | 44 | 0.59 | 177 | 0.104 | 1 | 2.40 | 0.021 | 0.04 | <0.1 | 0.01 | 4.2 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321137 | Soil | | 7 | 45 | 0.65 | 190 | 0.106 | 1 | 2.76 | 0.022 | 0.05 | <0.1 | 0.01 | 4.4 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321138 | Soil | | 9 | 47 | 0.61 | 159 | 0.105 | 1 | 2.32 | 0.020 | 0.07 | <0.1 | 0.01 | 4.4 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321139 | Soil | | 8 | 33 | 0.51 | 164 | 0.099 | <1 | 1.80 | 0.027 | 0.04 | <0.1 | 0.01 | 3.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321140 | Soil | | 15 | 59 | 0.73 | 171 | 0.144 | 1 | 2.69 | 0.030 | 0.05 | <0.1 | 0.03 | 11.0 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321141 | Soil | | 11 | 55 | 0.77 | 177 | 0.124 | 1 | 2.84 | 0.027 | 0.05 | <0.1 | 0.02 | 7.6 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321142 | Soil | | 11 | 36 | 0.65 | 160 | 0.121 | 2 | 1.98 | 0.052 | 0.05 | 0.1 | 0.03 | 5.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321143 | Soil | | 11 | 36 | 0.74 | 124 | 0.125 | 3 | 1.63 | 0.073 | 0.08 | 0.1 | 0.02 | 5.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321144 | Soil | | 12 | 48 | 0.76 | 217 | 0.127 | 2 | 2.09 | 0.056 | 0.05 | 0.1 | 0.18 | 6.6 | 0.2 | <0.05 | 6 | <0.5 | <0.2 |
| 1321145 | Soil | | 11 | 45 | 0.75 | 260 | 0.127 | 3 | 2.28 | 0.050 | 0.05 | <0.1 | 0.19 | 6.0 | 0.2 | <0.05 | 6 | <0.5 | <0.2 |
| 1321146 | Soil | | 13 | 52 | 0.79 | 322 | 0.136 | 3 | 2.56 | 0.048 | 0.06 | 0.1 | 0.34 | 8.4 | 0.2 | <0.05 | 7 | <0.5 | <0.2 |
| 1321147 | Soil | | 13 | 56 | 0.75 | 469 | 0.134 | 4 | 2.64 | 0.062 | 0.08 | <0.1 | 0.66 | 8.3 | 0.6 | 0.17 | 7 | <0.5 | <0.2 |
| 1321148 | Soil | | 9 | 50 | 0.83 | 272 | 0.130 | 3 | 3.46 | 0.022 | 0.07 | <0.1 | 0.04 | 6.7 | 0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1321149 | Soil | | 14 | 61 | 0.90 | 249 | 0.160 | 2 | 3.21 | 0.034 | 0.05 | <0.1 | 0.03 | 11.6 | <0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1321150 | Soil | | 21 | 43 | 0.52 | 350 | 0.094 | 3 | 2.05 | 0.026 | 0.06 | 0.2 | 0.29 | 5.9 | 0.2 | <0.05 | 7 | 0.8 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321151 | Soil | | 0.8 | 27.7 | 7.3 | 71 | 0.2 | 31.2 | 13.3 | 557 | 2.77 | 120.2 | 0.8 | 27.6 | 2.9 | 63 | 0.4 | 1.5 | 0.1 | 63 | 1.09 | 0.068 |
| 1321152 | Soil | | 0.5 | 24.8 | 8.0 | 62 | <0.1 | 24.8 | 10.1 | 320 | 2.62 | 12.3 | 0.8 | 8.6 | 3.4 | 47 | 0.1 | 0.8 | 0.1 | 60 | 0.81 | 0.065 |
| 1321153 | Soil | | 0.3 | 27.8 | 9.1 | 58 | <0.1 | 21.0 | 8.6 | 294 | 2.49 | 11.6 | 1.0 | 9.9 | 4.7 | 39 | 0.1 | 0.5 | 0.1 | 53 | 0.57 | 0.055 |
| 1321154 | Soil | | 0.5 | 22.0 | 7.5 | 59 | <0.1 | 17.6 | 9.1 | 365 | 2.39 | 9.9 | 0.9 | 6.4 | 3.3 | 44 | 0.2 | 0.4 | 0.1 | 50 | 0.68 | 0.063 |
| 1321155 | Soil | | 0.4 | 30.5 | 6.7 | 56 | <0.1 | 22.8 | 11.0 | 422 | 2.55 | 9.2 | 1.1 | 5.6 | 3.1 | 51 | 0.2 | 0.5 | 0.1 | 64 | 0.89 | 0.064 |
| 1321156 | Soil | | 0.4 | 29.8 | 9.9 | 57 | <0.1 | 19.3 | 9.6 | 354 | 2.52 | 13.4 | 1.2 | 10.4 | 4.2 | 40 | 0.1 | 0.5 | 0.1 | 52 | 0.67 | 0.054 |
| 1321157 | Soil | | 0.4 | 35.7 | 7.9 | 58 | <0.1 | 27.6 | 11.0 | 416 | 2.71 | 7.0 | 1.0 | 8.7 | 3.6 | 52 | 0.1 | 0.4 | 0.1 | 69 | 0.93 | 0.065 |
| 1321158 | Soil | | 0.5 | 40.4 | 14.2 | 53 | 0.2 | 27.5 | 10.3 | 324 | 2.66 | 13.2 | 1.1 | 7.0 | 4.1 | 46 | 0.1 | 0.5 | 0.2 | 52 | 0.84 | 0.043 |
| 1321159 | Soil | | 0.8 | 31.4 | 7.2 | 52 | 0.2 | 24.6 | 11.4 | 536 | 2.89 | 45.3 | 0.7 | 10.9 | 2.2 | 40 | 0.2 | 0.5 | 0.1 | 65 | 0.66 | 0.054 |
| 1321160 | Soil | | 1.5 | 20.3 | 10.1 | 52 | 0.2 | 18.5 | 9.3 | 278 | 3.40 | 11.0 | 0.5 | 3.6 | 2.3 | 31 | <0.1 | 0.5 | 0.2 | 94 | 0.46 | 0.031 |
| 1321161 | Soil | | 0.7 | 25.0 | 8.5 | 53 | <0.1 | 23.6 | 10.7 | 383 | 2.57 | 12.0 | 0.8 | 8.1 | 2.7 | 40 | 0.1 | 0.6 | 0.1 | 64 | 0.69 | 0.059 |
| 1321162 | Soil | | 0.8 | 28.7 | 8.4 | 57 | 0.1 | 26.4 | 11.6 | 381 | 2.65 | 12.0 | 0.8 | 12.3 | 2.9 | 44 | 0.1 | 0.8 | 0.1 | 63 | 0.72 | 0.066 |
| 1321163 | Soil | | 0.6 | 29.2 | 9.4 | 57 | 0.1 | 29.9 | 11.9 | 390 | 2.72 | 11.5 | 0.8 | 6.1 | 2.9 | 46 | <0.1 | 0.9 | <0.1 | 66 | 0.75 | 0.057 |
| 1321164 | Soil | | 0.7 | 36.6 | 9.7 | 63 | 0.1 | 31.6 | 13.4 | 443 | 3.04 | 10.8 | 0.9 | 7.6 | 3.6 | 50 | 0.1 | 0.6 | 0.1 | 80 | 0.88 | 0.064 |
| 1321165 | Soil | | 0.6 | 34.7 | 15.9 | 58 | 0.1 | 26.5 | 10.5 | 357 | 2.72 | 15.6 | 0.9 | 11.5 | 4.5 | 39 | <0.1 | 0.4 | 0.1 | 60 | 0.72 | 0.053 |
| 1321166 | Soil | | 1.0 | 15.8 | 8.3 | 48 | 0.1 | 17.3 | 7.6 | 274 | 2.21 | 8.6 | 0.3 | 5.4 | 1.5 | 25 | <0.1 | 0.3 | 0.1 | 56 | 0.38 | 0.042 |
| 1321167 | Soil | | 1.3 | 18.8 | 11.4 | 52 | <0.1 | 25.2 | 10.8 | 251 | 3.43 | 16.6 | 0.4 | 4.5 | 2.4 | 31 | 0.2 | 0.5 | 0.1 | 93 | 0.38 | 0.041 |
| 1321168 | Soil | | 1.2 | 25.0 | 11.5 | 61 | 0.1 | 25.6 | 16.7 | 699 | 3.61 | 11.8 | 0.7 | 8.9 | 3.2 | 33 | 0.1 | 0.5 | 0.1 | 92 | 0.50 | 0.035 |
| 1321169 | Soil | | 0.8 | 55.7 | 8.9 | 47 | 0.2 | 45.9 | 15.7 | 648 | 3.22 | 11.1 | 0.7 | 6.6 | 2.1 | 44 | 0.1 | 0.5 | 0.1 | 84 | 0.73 | 0.041 |
| 1321170 | Soil | | 1.0 | 28.5 | 8.2 | 55 | <0.1 | 37.0 | 15.3 | 425 | 3.51 | 8.3 | 0.5 | 4.9 | 2.3 | 45 | 0.1 | 0.4 | 0.1 | 95 | 0.81 | 0.039 |
| 1321171 | Soil | | 0.9 | 37.8 | 8.8 | 51 | <0.1 | 41.2 | 14.9 | 617 | 3.58 | 7.8 | 0.6 | 2.8 | 2.3 | 41 | 0.1 | 0.5 | 0.1 | 96 | 0.68 | 0.035 |
| 1321172 | Soil | | 1.1 | 29.2 | 8.8 | 53 | <0.1 | 37.1 | 16.6 | 578 | 3.42 | 7.5 | 0.5 | 3.0 | 2.9 | 44 | <0.1 | 0.5 | <0.1 | 96 | 0.74 | 0.041 |
| 1321173 | Soil | | 0.9 | 33.6 | 8.5 | 45 | <0.1 | 32.6 | 10.0 | 355 | 2.87 | 5.7 | 0.6 | 2.9 | 1.8 | 36 | 0.2 | 0.4 | <0.1 | 82 | 0.58 | 0.026 |
| 1321174 | Soil | | 0.4 | 39.2 | 5.3 | 51 | <0.1 | 33.7 | 11.0 | 393 | 2.74 | 5.4 | 0.7 | 5.8 | 2.2 | 59 | 0.2 | 0.4 | <0.1 | 67 | 1.36 | 0.061 |
| 1321175 | Soil | | 0.6 | 42.1 | 7.7 | 54 | <0.1 | 41.5 | 13.5 | 497 | 2.94 | 6.7 | 0.8 | 5.7 | 2.2 | 54 | 0.2 | 0.4 | 0.1 | 75 | 1.08 | 0.062 |
| 1321176 | Soil | | 0.6 | 40.9 | 5.3 | 49 | 0.1 | 37.8 | 11.7 | 421 | 2.86 | 6.9 | 0.7 | 5.8 | 1.7 | 53 | 0.2 | 0.5 | <0.1 | 69 | 1.06 | 0.056 |
| 1321177 | Soil | | 1.2 | 29.6 | 11.5 | 64 | 0.1 | 30.7 | 13.6 | 535 | 3.54 | 11.2 | 0.7 | 4.6 | 3.5 | 37 | 0.1 | 0.5 | 0.1 | 92 | 0.56 | 0.037 |
| 1321178 | Soil | | 1.2 | 23.7 | 15.9 | 65 | 0.1 | 28.4 | 13.7 | 389 | 3.43 | 15.6 | 0.5 | 5.5 | 3.5 | 37 | 0.1 | 0.5 | 0.1 | 92 | 0.50 | 0.029 |
| 1321179 | Soil | | 1.1 | 33.5 | 11.2 | 64 | 0.2 | 31.9 | 14.3 | 484 | 3.77 | 12.1 | 0.9 | 7.3 | 4.6 | 43 | 0.1 | 0.6 | 0.1 | 93 | 0.67 | 0.041 |
| 1321180 | Soil | | 0.7 | 32.3 | 9.9 | 57 | <0.1 | 38.0 | 12.9 | 426 | 3.45 | 9.7 | 0.7 | 6.5 | 3.4 | 44 | <0.1 | 0.4 | <0.1 | 88 | 0.76 | 0.053 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321151 | Soil | 12 | 40 | 0.65 | 320 | 0.092 | 3 | 1.74 | 0.047 | 0.06 | 0.1 | 0.05 | 6.2 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321152 | Soil | 13 | 37 | 0.64 | 171 | 0.107 | 3 | 1.95 | 0.047 | 0.05 | 0.1 | 0.03 | 5.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321153 | Soil | 14 | 28 | 0.49 | 180 | 0.100 | 3 | 1.84 | 0.038 | 0.06 | <0.1 | 0.05 | 5.3 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321154 | Soil | 12 | 29 | 0.52 | 166 | 0.092 | 3 | 1.70 | 0.047 | 0.06 | 0.1 | 0.03 | 5.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321155 | Soil | 13 | 32 | 0.62 | 196 | 0.104 | 3 | 1.84 | 0.047 | 0.05 | 0.1 | 0.03 | 5.8 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321156 | Soil | 15 | 27 | 0.49 | 180 | 0.095 | 3 | 1.94 | 0.035 | 0.05 | <0.1 | 0.03 | 4.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321157 | Soil | 13 | 37 | 0.73 | 153 | 0.124 | 3 | 1.96 | 0.060 | 0.06 | 0.1 | 0.03 | 6.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321158 | Soil | 19 | 32 | 0.51 | 171 | 0.079 | 2 | 2.30 | 0.036 | 0.07 | <0.1 | 0.03 | 5.5 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321159 | Soil | 14 | 34 | 0.51 | 193 | 0.089 | 2 | 2.51 | 0.032 | 0.06 | 0.1 | 0.04 | 6.1 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321160 | Soil | 10 | 37 | 0.54 | 162 | 0.115 | 2 | 2.43 | 0.024 | 0.05 | <0.1 | 0.01 | 4.8 | 0.2 | <0.05 | 9 | <0.5 | <0.2 |
| 1321161 | Soil | 12 | 37 | 0.61 | 171 | 0.096 | 2 | 1.91 | 0.039 | 0.05 | <0.1 | 0.03 | 5.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321162 | Soil | 12 | 41 | 0.66 | 184 | 0.098 | 2 | 2.02 | 0.041 | 0.05 | 0.1 | 0.04 | 6.0 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321163 | Soil | 13 | 46 | 0.68 | 178 | 0.106 | 2 | 2.12 | 0.043 | 0.05 | <0.1 | 0.05 | 6.4 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321164 | Soil | 13 | 47 | 0.75 | 187 | 0.137 | 2 | 2.40 | 0.053 | 0.06 | <0.1 | 0.04 | 7.6 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321165 | Soil | 18 | 38 | 0.59 | 145 | 0.100 | 2 | 2.19 | 0.034 | 0.06 | <0.1 | 0.03 | 5.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321166 | Soil | 8 | 27 | 0.43 | 116 | 0.081 | 1 | 1.60 | 0.029 | 0.06 | 0.1 | 0.02 | 3.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321167 | Soil | 9 | 40 | 0.65 | 170 | 0.118 | 2 | 2.62 | 0.023 | 0.06 | <0.1 | 0.02 | 4.8 | 0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1321168 | Soil | 12 | 46 | 0.58 | 219 | 0.118 | 2 | 2.75 | 0.025 | 0.06 | <0.1 | 0.02 | 6.3 | 0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1321169 | Soil | 14 | 49 | 0.78 | 193 | 0.101 | 2 | 2.32 | 0.046 | 0.05 | <0.1 | 0.06 | 7.8 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321170 | Soil | 8 | 54 | 0.82 | 194 | 0.125 | 3 | 2.53 | 0.042 | 0.07 | <0.1 | 0.02 | 6.1 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321171 | Soil | 10 | 57 | 0.88 | 209 | 0.132 | 2 | 2.49 | 0.044 | 0.06 | 0.1 | 0.02 | 6.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321172 | Soil | 10 | 59 | 0.86 | 198 | 0.141 | 3 | 2.54 | 0.049 | 0.07 | 0.1 | 0.03 | 7.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321173 | Soil | 9 | 47 | 0.66 | 171 | 0.115 | 2 | 2.10 | 0.039 | 0.04 | <0.1 | 0.03 | 5.5 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321174 | Soil | 10 | 41 | 0.73 | 154 | 0.115 | 4 | 1.86 | 0.065 | 0.05 | 0.1 | 0.04 | 6.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321175 | Soil | 11 | 50 | 0.77 | 172 | 0.116 | 3 | 2.07 | 0.061 | 0.05 | <0.1 | 0.04 | 6.5 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321176 | Soil | 12 | 46 | 0.74 | 168 | 0.104 | 2 | 1.95 | 0.053 | 0.06 | <0.1 | 0.04 | 6.2 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321177 | Soil | 12 | 50 | 0.79 | 198 | 0.125 | 2 | 2.43 | 0.031 | 0.07 | <0.1 | <0.01 | 6.2 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321178 | Soil | 11 | 50 | 0.70 | 157 | 0.120 | 2 | 2.36 | 0.029 | 0.07 | <0.1 | 0.01 | 5.6 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321179 | Soil | 15 | 55 | 0.82 | 187 | 0.131 | 2 | 2.63 | 0.039 | 0.09 | <0.1 | 0.03 | 7.7 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321180 | Soil | 12 | 62 | 0.88 | 182 | 0.130 | 2 | 2.41 | 0.049 | 0.06 | <0.1 | 0.02 | 7.5 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321181 | Soil | | 0.8 | 37.1 | 7.8 | 57 | 0.1 | 38.9 | 12.9 | 489 | 2.93 | 8.7 | 0.6 | 3.4 | 2.0 | 46 | 0.2 | 0.5 | 0.1 | 72 | 0.82 | 0.055 |
| 1321182 | Soil | | 0.7 | 39.0 | 6.3 | 54 | <0.1 | 43.8 | 13.4 | 467 | 3.06 | 7.6 | 0.7 | 7.3 | 2.2 | 49 | 0.2 | 0.5 | 0.1 | 79 | 0.98 | 0.058 |
| 1321183 | Soil | | 0.5 | 42.9 | 7.2 | 50 | <0.1 | 43.0 | 12.5 | 401 | 2.85 | 6.2 | 0.7 | 3.3 | 2.8 | 55 | 0.2 | 0.6 | <0.1 | 74 | 1.25 | 0.053 |
| 1321184 | Soil | | 0.6 | 39.9 | 6.3 | 47 | <0.1 | 36.7 | 11.8 | 441 | 2.56 | 6.2 | 0.7 | 3.7 | 1.9 | 59 | 0.1 | 0.5 | <0.1 | 69 | 1.42 | 0.061 |
| 1321185 | Soil | | 0.7 | 38.0 | 10.5 | 51 | <0.1 | 35.2 | 13.9 | 508 | 3.20 | 7.6 | 0.6 | 2.6 | 2.5 | 45 | 0.2 | 0.5 | 0.1 | 86 | 0.76 | 0.041 |
| 1321186 | Soil | | 0.8 | 29.2 | 8.4 | 52 | <0.1 | 40.6 | 14.6 | 416 | 3.50 | 8.7 | 0.5 | 1.2 | 2.8 | 42 | <0.1 | 0.5 | 0.2 | 96 | 0.74 | 0.041 |
| 1321187 | Soil | | 0.8 | 47.5 | 10.3 | 55 | <0.1 | 48.5 | 15.7 | 577 | 3.50 | 8.9 | 0.7 | 5.2 | 2.6 | 45 | 0.1 | 0.5 | 0.1 | 89 | 0.83 | 0.045 |
| 1321188 | Soil | | 0.8 | 37.6 | 7.3 | 49 | <0.1 | 43.5 | 13.4 | 435 | 3.54 | 12.6 | 0.6 | 4.7 | 2.5 | 42 | <0.1 | 0.5 | 0.1 | 91 | 0.73 | 0.042 |
| 1321189 | Soil | | 0.7 | 51.5 | 9.0 | 52 | 0.1 | 66.7 | 16.8 | 546 | 3.47 | 12.5 | 0.9 | 3.1 | 2.6 | 46 | 0.2 | 0.7 | 0.1 | 87 | 0.94 | 0.050 |
| 1321190 | Soil | | 0.8 | 32.2 | 9.5 | 54 | 0.1 | 81.8 | 19.0 | 620 | 3.61 | 10.6 | 0.7 | 4.9 | 3.2 | 47 | 0.2 | 0.9 | 0.1 | 84 | 0.94 | 0.040 |
| 1321191 | Soil | | 0.6 | 34.5 | 8.7 | 50 | 0.3 | 86.9 | 15.5 | 363 | 3.55 | 31.7 | 0.7 | 7.1 | 2.7 | 53 | <0.1 | 9.5 | 0.1 | 72 | 1.10 | 0.046 |
| 1321192 | Soil | | 1.0 | 28.2 | 9.4 | 71 | 0.1 | 111.2 | 18.5 | 544 | 3.41 | 13.4 | 0.4 | 2.4 | 2.4 | 41 | 0.3 | 2.7 | 0.1 | 70 | 0.76 | 0.047 |
| 1321193 | Soil | | 0.8 | 49.4 | 11.1 | 85 | 0.2 | 110.5 | 17.9 | 523 | 2.74 | 7.3 | 1.2 | 5.3 | 1.9 | 59 | 0.7 | 2.1 | 0.1 | 59 | 1.40 | 0.060 |
| 1321194 | Soil | | 0.5 | 40.9 | 6.1 | 51 | 0.1 | 122.2 | 15.0 | 400 | 2.38 | 5.0 | 0.6 | 3.5 | 1.3 | 62 | 0.3 | 0.8 | <0.1 | 54 | 1.76 | 0.062 |
| 1321195 | Soil | | 0.7 | 53.8 | 7.1 | 57 | 0.1 | 66.2 | 15.5 | 487 | 3.06 | 10.3 | 0.8 | 2.0 | 2.2 | 47 | 0.2 | 0.6 | 0.1 | 75 | 0.91 | 0.041 |
| 1321196 | Soil | | 0.8 | 49.8 | 7.4 | 53 | <0.1 | 42.1 | 14.6 | 534 | 3.25 | 11.8 | 0.8 | 4.7 | 2.1 | 44 | 0.2 | 0.5 | 0.1 | 81 | 0.84 | 0.044 |
| 1321197 | Soil | | 0.7 | 37.6 | 9.1 | 59 | <0.1 | 37.0 | 14.9 | 492 | 3.57 | 8.8 | 0.6 | 2.9 | 2.6 | 42 | <0.1 | 0.6 | <0.1 | 93 | 0.75 | 0.041 |
| 1321198 | Soil | | 0.6 | 45.4 | 5.5 | 54 | <0.1 | 39.8 | 11.3 | 407 | 2.72 | 6.0 | 0.7 | 1.8 | 1.9 | 59 | 0.3 | 0.6 | <0.1 | 68 | 1.27 | 0.061 |
| 1321199 | Soil | | 0.5 | 31.2 | 5.2 | 46 | <0.1 | 31.5 | 10.3 | 356 | 2.67 | 6.0 | 0.6 | 3.0 | 1.6 | 52 | <0.1 | 0.5 | <0.1 | 69 | 1.13 | 0.057 |
| 1321200 | Soil | | 0.7 | 33.5 | 4.8 | 47 | <0.1 | 31.4 | 11.2 | 440 | 2.58 | 5.5 | 0.6 | 3.7 | 1.5 | 56 | 0.2 | 0.5 | <0.1 | 66 | 1.22 | 0.060 |
| 1321201 | Soil | | 0.6 | 49.0 | 7.1 | 57 | <0.1 | 38.3 | 13.1 | 428 | 3.39 | 8.2 | 0.4 | 4.6 | 2.6 | 72 | 0.1 | 0.6 | <0.1 | 87 | 2.87 | 0.066 |
| 1321202 | Soil | | 1.0 | 89.8 | 6.9 | 63 | 0.3 | 38.4 | 10.3 | 648 | 2.43 | 10.3 | 2.0 | 5.7 | 1.8 | 86 | 0.4 | 1.1 | <0.1 | 61 | 1.98 | 0.107 |
| 1321203 | Soil | | 0.7 | 44.3 | 6.7 | 90 | <0.1 | 32.7 | 14.6 | 917 | 3.12 | 7.3 | 1.0 | 4.1 | 2.2 | 67 | 0.5 | 0.5 | <0.1 | 74 | 1.26 | 0.065 |
| 1321204 | Soil | | 1.0 | 42.7 | 8.5 | 65 | 0.2 | 29.4 | 10.0 | 480 | 2.92 | 8.6 | 0.8 | 9.1 | 2.8 | 71 | 0.2 | 0.6 | 0.1 | 71 | 1.00 | 0.081 |
| 1321205 | Soil | | 0.8 | 54.1 | 6.7 | 70 | 0.1 | 33.7 | 12.6 | 610 | 3.19 | 8.9 | 0.5 | 6.9 | 2.6 | 74 | 0.3 | 0.6 | 0.1 | 76 | 1.79 | 0.085 |
| 1321206 | Soil | | 1.2 | 32.9 | 9.3 | 79 | 0.3 | 33.3 | 13.5 | 1377 | 3.00 | 8.5 | 0.5 | 1.4 | 2.4 | 51 | 0.3 | 0.8 | 0.1 | 71 | 0.74 | 0.067 |
| 1321207 | Soil | | 0.9 | 17.0 | 6.2 | 40 | <0.1 | 15.4 | 7.4 | 425 | 1.97 | 5.2 | 0.3 | <0.5 | 1.3 | 31 | 0.1 | 0.3 | <0.1 | 48 | 0.45 | 0.069 |
| 1321208 | Soil | | 1.2 | 45.9 | 11.8 | 66 | 0.1 | 33.6 | 14.8 | 971 | 2.94 | 7.6 | 0.8 | 4.2 | 2.8 | 54 | 0.2 | 0.5 | 0.1 | 69 | 0.74 | 0.065 |
| 1321209 | Soil | | 0.7 | 39.0 | 7.0 | 53 | <0.1 | 29.9 | 12.6 | 518 | 2.90 | 6.8 | 0.9 | 2.6 | 2.4 | 61 | 0.1 | 0.4 | 0.1 | 73 | 1.15 | 0.064 |
| 1321210 | Soil | | 0.5 | 26.3 | 4.1 | 43 | 0.1 | 21.1 | 9.1 | 446 | 2.05 | 4.2 | 0.8 | 117.4 | 1.3 | 77 | 0.1 | 0.4 | <0.1 | 50 | 1.78 | 0.060 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321181 | Soil | | 11 | 49 | 0.72 | 166 | 0.091 | 3 | 1.94 | 0.044 | 0.06 | <0.1 | 0.03 | 5.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321182 | Soil | | 11 | 55 | 0.84 | 157 | 0.115 | 4 | 2.05 | 0.055 | 0.06 | <0.1 | 0.04 | 6.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321183 | Soil | | 11 | 50 | 0.78 | 167 | 0.116 | 3 | 2.04 | 0.057 | 0.05 | 0.1 | 0.05 | 6.9 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321184 | Soil | | 10 | 41 | 0.73 | 148 | 0.097 | 5 | 1.86 | 0.056 | 0.05 | <0.1 | 0.04 | 5.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321185 | Soil | | 11 | 50 | 0.79 | 186 | 0.121 | 3 | 2.25 | 0.051 | 0.06 | <0.1 | 0.04 | 6.4 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321186 | Soil | | 8 | 57 | 0.91 | 173 | 0.129 | 2 | 2.49 | 0.045 | 0.05 | <0.1 | 0.02 | 6.2 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321187 | Soil | | 13 | 56 | 0.87 | 195 | 0.122 | 3 | 2.40 | 0.049 | 0.05 | 0.1 | 0.03 | 8.3 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321188 | Soil | | 10 | 53 | 0.86 | 163 | 0.127 | 2 | 2.44 | 0.042 | 0.06 | <0.1 | 0.02 | 7.5 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321189 | Soil | | 12 | 58 | 0.81 | 182 | 0.110 | 3 | 2.35 | 0.040 | 0.06 | <0.1 | 0.05 | 8.1 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321190 | Soil | | 12 | 71 | 1.06 | 258 | 0.110 | 2 | 2.68 | 0.045 | 0.06 | <0.1 | 0.07 | 6.7 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321191 | Soil | | 12 | 87 | 0.83 | 189 | 0.093 | 3 | 2.16 | 0.053 | 0.05 | <0.1 | 0.25 | 7.1 | 0.4 | <0.05 | 6 | <0.5 | <0.2 |
| 1321192 | Soil | | 9 | 66 | 0.98 | 116 | 0.093 | 3 | 2.03 | 0.044 | 0.06 | <0.1 | 0.05 | 4.7 | 0.2 | <0.05 | 5 | 0.7 | <0.2 |
| 1321193 | Soil | | 13 | 63 | 0.93 | 129 | 0.071 | 3 | 1.96 | 0.039 | 0.05 | <0.1 | 0.38 | 6.2 | <0.1 | <0.05 | 5 | 0.8 | <0.2 |
| 1321194 | Soil | | 9 | 98 | 1.10 | 119 | 0.074 | 4 | 1.81 | 0.043 | 0.04 | <0.1 | 0.12 | 5.3 | <0.1 | 0.06 | 5 | 0.5 | <0.2 |
| 1321195 | Soil | | 11 | 50 | 0.72 | 170 | 0.109 | 2 | 2.20 | 0.046 | 0.06 | <0.1 | 0.05 | 6.8 | <0.1 | <0.05 | 7 | 0.6 | <0.2 |
| 1321196 | Soil | | 11 | 48 | 0.73 | 171 | 0.107 | 2 | 2.22 | 0.044 | 0.06 | <0.1 | 0.04 | 7.1 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321197 | Soil | | 11 | 52 | 0.86 | 176 | 0.131 | 3 | 2.37 | 0.047 | 0.07 | <0.1 | 0.03 | 7.1 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321198 | Soil | | 10 | 41 | 0.74 | 155 | 0.103 | 3 | 1.83 | 0.056 | 0.05 | <0.1 | 0.03 | 5.8 | <0.1 | <0.05 | 5 | 0.6 | <0.2 |
| 1321199 | Soil | | 9 | 42 | 0.70 | 142 | 0.103 | 2 | 1.83 | 0.056 | 0.05 | <0.1 | 0.04 | 5.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321200 | Soil | | 9 | 41 | 0.67 | 151 | 0.092 | 2 | 1.82 | 0.054 | 0.05 | <0.1 | 0.05 | 5.6 | <0.1 | <0.05 | 5 | 0.6 | <0.2 |
| 1321201 | Soil | | 14 | 46 | 1.14 | 135 | 0.142 | 2 | 2.03 | 0.085 | 0.09 | <0.1 | 0.04 | 7.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321202 | Soil | | 12 | 31 | 0.67 | 297 | 0.075 | 5 | 1.53 | 0.061 | 0.07 | <0.1 | 0.05 | 5.0 | <0.1 | <0.05 | 4 | 1.6 | <0.2 |
| 1321203 | Soil | | 11 | 36 | 0.69 | 337 | 0.098 | 5 | 1.86 | 0.070 | 0.07 | <0.1 | 0.02 | 5.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321204 | Soil | | 13 | 35 | 0.74 | 437 | 0.112 | 3 | 1.88 | 0.069 | 0.07 | <0.1 | 0.03 | 5.5 | <0.1 | <0.05 | 5 | 0.7 | <0.2 |
| 1321205 | Soil | | 12 | 35 | 0.86 | 357 | 0.119 | 4 | 1.78 | 0.084 | 0.08 | <0.1 | 0.03 | 6.0 | <0.1 | <0.05 | 5 | 0.7 | <0.2 |
| 1321206 | Soil | | 9 | 37 | 0.62 | 677 | 0.088 | 3 | 2.09 | 0.045 | 0.09 | <0.1 | 0.02 | 4.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321207 | Soil | | 5 | 21 | 0.38 | 222 | 0.070 | 2 | 1.33 | 0.037 | 0.08 | <0.1 | <0.01 | 2.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321208 | Soil | | 12 | 38 | 0.68 | 361 | 0.098 | 3 | 2.07 | 0.047 | 0.09 | <0.1 | 0.04 | 5.5 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321209 | Soil | | 13 | 36 | 0.70 | 316 | 0.106 | 2 | 1.82 | 0.057 | 0.06 | <0.1 | 0.04 | 5.8 | <0.1 | <0.05 | 5 | 0.7 | <0.2 |
| 1321210 | Soil | | 9 | 27 | 0.57 | 146 | 0.079 | 4 | 1.36 | 0.050 | 0.06 | <0.1 | 0.02 | 4.3 | <0.1 | <0.05 | 4 | 0.7 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321211 | Soil | | 0.8 | 36.0 | 6.7 | 44 | 0.1 | 24.8 | 9.7 | 448 | 2.35 | 5.8 | 1.4 | 2.8 | 1.4 | 72 | <0.1 | 0.6 | <0.1 | 58 | 1.58 | 0.075 |
| 1321212 | Soil | | 0.9 | 72.5 | 7.4 | 58 | 0.2 | 34.9 | 14.5 | 609 | 3.03 | 6.9 | 1.0 | 5.6 | 2.3 | 67 | 0.2 | 0.7 | 0.1 | 73 | 1.47 | 0.066 |
| 1321213 | Soil | | 0.9 | 54.2 | 8.7 | 60 | 0.1 | 38.2 | 15.2 | 608 | 3.50 | 8.6 | 0.7 | 5.6 | 3.2 | 54 | 0.2 | 0.6 | <0.1 | 87 | 1.07 | 0.078 |
| 1321214 | Soil | | 0.8 | 29.4 | 7.6 | 64 | <0.1 | 30.1 | 13.4 | 502 | 3.46 | 8.6 | 0.5 | 3.3 | 3.2 | 40 | 0.1 | 0.5 | <0.1 | 88 | 0.69 | 0.055 |
| 1321215 | Soil | | 0.7 | 40.1 | 10.4 | 57 | <0.1 | 37.5 | 14.2 | 543 | 3.59 | 8.0 | 0.4 | 1.3 | 3.1 | 52 | <0.1 | 0.5 | <0.1 | 91 | 1.05 | 0.076 |
| 1321216 | Soil | | 0.7 | 35.2 | 5.9 | 50 | <0.1 | 37.7 | 13.8 | 473 | 3.35 | 7.4 | 0.5 | 2.9 | 3.1 | 49 | <0.1 | 0.4 | <0.1 | 89 | 0.87 | 0.064 |
| 1321217 | Soil | | 0.9 | 39.3 | 8.0 | 53 | <0.1 | 34.7 | 14.7 | 548 | 3.70 | 8.7 | 0.5 | 4.2 | 2.9 | 44 | <0.1 | 0.5 | <0.1 | 92 | 0.81 | 0.031 |
| 1321218 | Soil | | 0.5 | 49.8 | 6.0 | 65 | 0.1 | 31.4 | 13.5 | 494 | 3.10 | 8.8 | 0.6 | 3.4 | 2.4 | 58 | 0.3 | 0.6 | <0.1 | 82 | 1.23 | 0.079 |
| 1321219 | Soil | | 0.5 | 39.8 | 6.2 | 61 | <0.1 | 31.3 | 13.6 | 456 | 3.05 | 9.0 | 0.7 | 3.9 | 2.6 | 55 | 0.2 | 0.6 | 0.1 | 80 | 0.98 | 0.076 |
| 1321220 | Soil | | 0.5 | 27.7 | 4.8 | 53 | <0.1 | 24.7 | 10.6 | 376 | 2.79 | 7.2 | 0.6 | 3.5 | 2.0 | 50 | <0.1 | 0.4 | <0.1 | 75 | 0.90 | 0.064 |
| 1321221 | Soil | | 0.6 | 39.5 | 5.3 | 57 | <0.1 | 30.2 | 12.5 | 529 | 2.98 | 8.2 | 0.5 | 7.1 | 2.6 | 75 | 0.2 | 0.5 | <0.1 | 79 | 2.17 | 0.087 |
| 1321222 | Soil | | 0.7 | 30.4 | 7.1 | 60 | 0.1 | 28.8 | 12.8 | 508 | 2.81 | 23.1 | 0.7 | 12.8 | 1.9 | 44 | 0.2 | 1.1 | 0.1 | 70 | 0.75 | 0.065 |
| 1321223 | Soil | | 0.8 | 27.8 | 9.4 | 61 | 0.1 | 28.8 | 12.4 | 522 | 2.75 | 20.3 | 0.7 | 10.8 | 2.1 | 39 | 0.2 | 0.8 | 0.1 | 67 | 0.66 | 0.059 |
| 1321224 | Soil | | 0.8 | 30.5 | 9.8 | 61 | 0.1 | 31.9 | 11.9 | 396 | 2.77 | 15.5 | 0.8 | 11.8 | 2.5 | 42 | 0.1 | 0.9 | 0.1 | 67 | 0.74 | 0.061 |
| 1321225 | Soil | | 0.7 | 26.3 | 9.3 | 59 | <0.1 | 27.8 | 12.4 | 403 | 2.71 | 13.9 | 0.7 | 8.3 | 2.1 | 41 | 0.1 | 0.7 | 0.1 | 67 | 0.74 | 0.061 |
| 1321226 | Soil | | 0.6 | 30.2 | 8.2 | 70 | <0.1 | 29.4 | 12.2 | 401 | 2.72 | 15.0 | 0.8 | 9.5 | 2.3 | 43 | 0.2 | 0.7 | 0.1 | 68 | 0.77 | 0.058 |
| 1321227 | Soil | | 0.5 | 28.7 | 8.3 | 54 | <0.1 | 27.4 | 11.5 | 423 | 2.51 | 13.4 | 0.8 | 11.1 | 2.1 | 44 | 0.1 | 0.8 | 0.1 | 63 | 0.79 | 0.064 |
| 1321228 | Soil | | 0.4 | 34.2 | 6.3 | 51 | 0.1 | 27.0 | 11.0 | 455 | 2.34 | 9.2 | 0.8 | 9.1 | 1.6 | 51 | 0.2 | 0.8 | <0.1 | 61 | 0.94 | 0.062 |
| 1321229 | Soil | | 0.6 | 34.2 | 9.2 | 59 | 0.1 | 29.4 | 12.6 | 554 | 2.70 | 12.2 | 0.9 | 11.5 | 2.3 | 48 | 0.2 | 0.7 | 0.1 | 68 | 0.89 | 0.064 |
| 1321230 | Soil | | 0.5 | 40.0 | 7.4 | 58 | 0.1 | 31.0 | 12.4 | 594 | 2.71 | 12.5 | 1.0 | 6.7 | 2.1 | 52 | 0.2 | 0.6 | 0.1 | 68 | 0.99 | 0.072 |
| 1321231 | Soil | | 0.6 | 40.0 | 9.7 | 65 | 0.1 | 30.6 | 12.2 | 486 | 2.83 | 10.8 | 0.8 | 8.0 | 3.0 | 50 | 0.2 | 0.5 | 0.1 | 74 | 0.92 | 0.070 |
| 1321232 | Soil | | 0.7 | 33.2 | 10.2 | 59 | 0.1 | 27.9 | 11.7 | 393 | 2.98 | 18.3 | 0.7 | 10.9 | 2.9 | 40 | 0.1 | 0.4 | 0.1 | 75 | 0.73 | 0.053 |
| 1321233 | Soil | | 1.0 | 32.0 | 14.9 | 57 | 0.1 | 28.1 | 12.4 | 455 | 2.96 | 14.3 | 0.7 | 10.4 | 2.3 | 36 | 0.1 | 0.4 | 0.1 | 74 | 0.62 | 0.052 |
| 1321234 | Soil | | 1.1 | 37.8 | 12.0 | 56 | 0.1 | 33.2 | 12.6 | 423 | 3.17 | 15.4 | 0.6 | 13.1 | 2.8 | 39 | <0.1 | 0.5 | 0.1 | 82 | 0.71 | 0.055 |
| 1321235 | Soil | | 1.0 | 23.4 | 12.7 | 58 | <0.1 | 29.0 | 11.4 | 365 | 3.36 | 10.1 | 0.5 | 2.9 | 2.4 | 35 | 0.1 | 0.5 | 0.1 | 86 | 0.61 | 0.050 |
| 1321236 | Soil | | 1.0 | 32.8 | 11.2 | 59 | 0.1 | 32.9 | 14.9 | 549 | 3.80 | 10.9 | 0.6 | 4.1 | 2.6 | 38 | 0.1 | 0.4 | 0.1 | 95 | 0.64 | 0.050 |
| 1321237 | Soil | | 0.8 | 21.6 | 12.3 | 52 | <0.1 | 27.3 | 11.6 | 366 | 3.08 | 7.9 | 0.5 | 5.5 | 2.8 | 36 | <0.1 | 0.4 | 0.1 | 81 | 0.53 | 0.049 |
| 1321238 | Soil | | 0.9 | 29.8 | 9.6 | 51 | <0.1 | 29.9 | 13.1 | 444 | 3.27 | 10.8 | 0.7 | 6.3 | 3.1 | 41 | <0.1 | 0.4 | 0.1 | 87 | 0.54 | 0.035 |
| 1321239 | Soil | | 0.7 | 37.9 | 6.5 | 56 | <0.1 | 31.3 | 13.0 | 451 | 3.27 | 5.0 | 0.4 | 2.4 | 1.9 | 57 | 0.1 | 0.4 | <0.1 | 89 | 1.76 | 0.086 |
| 1321240 | Soil | | 0.7 | 51.7 | 7.1 | 58 | 0.1 | 35.2 | 14.5 | 621 | 3.34 | 5.8 | 0.4 | 7.2 | 1.9 | 60 | 0.1 | 0.4 | <0.1 | 85 | 1.93 | 0.076 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321211 | Soil | 13 | 31 | 0.62 | 221 | 0.078 | 3 | 1.58 | 0.057 | 0.05 | <0.1 | 0.04 | 5.1 | <0.1 | <0.05 | 5 | 0.9 | <0.2 |
| 1321212 | Soil | 17 | 38 | 0.70 | 296 | 0.093 | 3 | 2.06 | 0.059 | 0.06 | <0.1 | 0.08 | 7.4 | <0.1 | <0.05 | 5 | 0.8 | <0.2 |
| 1321213 | Soil | 14 | 47 | 0.91 | 238 | 0.129 | 3 | 2.12 | 0.073 | 0.09 | 0.1 | 0.05 | 8.4 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321214 | Soil | 11 | 44 | 0.81 | 274 | 0.120 | 3 | 2.44 | 0.045 | 0.07 | <0.1 | 0.02 | 6.6 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321215 | Soil | 14 | 51 | 0.99 | 181 | 0.136 | 3 | 2.26 | 0.076 | 0.08 | <0.1 | 0.03 | 9.8 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321216 | Soil | 21 | 46 | 0.92 | 1046 | 0.120 | 2 | 1.99 | 0.064 | 0.07 | <0.1 | 0.02 | 9.1 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321217 | Soil | 14 | 49 | 0.90 | 152 | 0.134 | 2 | 2.20 | 0.059 | 0.07 | <0.1 | 0.03 | 8.8 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1321218 | Soil | 12 | 36 | 0.74 | 173 | 0.124 | 4 | 1.84 | 0.066 | 0.06 | 0.1 | 0.02 | 5.9 | <0.1 | <0.05 | 5 | 0.7 | <0.2 |
| 1321219 | Soil | 13 | 38 | 0.79 | 160 | 0.136 | 3 | 1.89 | 0.067 | 0.06 | 0.1 | 0.03 | 6.3 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1321220 | Soil | 10 | 34 | 0.67 | 133 | 0.122 | 3 | 1.72 | 0.065 | 0.05 | 0.1 | 0.03 | 4.9 | <0.1 | <0.05 | 5 | 0.5 | <0.2 |
| 1321221 | Soil | 12 | 37 | 0.93 | 133 | 0.129 | 4 | 1.66 | 0.072 | 0.09 | 0.1 | 0.02 | 5.3 | <0.1 | <0.05 | 5 | 0.6 | <0.2 |
| 1321222 | Soil | 12 | 41 | 0.64 | 175 | 0.097 | 2 | 1.92 | 0.041 | 0.05 | 0.1 | 0.04 | 5.6 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1321223 | Soil | 11 | 43 | 0.64 | 170 | 0.094 | 2 | 1.90 | 0.034 | 0.05 | 0.1 | 0.03 | 5.6 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1321224 | Soil | 12 | 46 | 0.68 | 172 | 0.104 | 2 | 2.06 | 0.036 | 0.05 | 0.1 | 0.04 | 6.1 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1321225 | Soil | 11 | 44 | 0.67 | 166 | 0.101 | 2 | 1.97 | 0.036 | 0.05 | <0.1 | 0.03 | 5.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321226 | Soil | 12 | 44 | 0.68 | 171 | 0.108 | 2 | 2.02 | 0.039 | 0.05 | <0.1 | 0.03 | 5.7 | <0.1 | <0.05 | 6 | 0.5 | <0.2 |
| 1321227 | Soil | 12 | 40 | 0.60 | 164 | 0.095 | 2 | 1.86 | 0.037 | 0.05 | <0.1 | 0.04 | 5.6 | <0.1 | <0.05 | 6 | 0.5 | <0.2 |
| 1321228 | Soil | 12 | 35 | 0.58 | 162 | 0.092 | 2 | 1.84 | 0.041 | 0.04 | <0.1 | 0.04 | 5.5 | <0.1 | <0.05 | 5 | 0.7 | <0.2 |
| 1321229 | Soil | 13 | 42 | 0.66 | 185 | 0.106 | 2 | 2.13 | 0.040 | 0.05 | <0.1 | 0.05 | 6.4 | <0.1 | <0.05 | 6 | 0.7 | <0.2 |
| 1321230 | Soil | 13 | 39 | 0.65 | 165 | 0.108 | 2 | 2.01 | 0.046 | 0.05 | 0.1 | 0.05 | 6.4 | <0.1 | <0.05 | 6 | 0.8 | <0.2 |
| 1321231 | Soil | 13 | 42 | 0.73 | 138 | 0.131 | 2 | 1.90 | 0.057 | 0.06 | <0.1 | 0.04 | 6.4 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1321232 | Soil | 13 | 45 | 0.68 | 161 | 0.119 | 2 | 2.30 | 0.036 | 0.05 | <0.1 | 0.03 | 6.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321233 | Soil | 12 | 44 | 0.63 | 174 | 0.109 | 2 | 2.25 | 0.032 | 0.05 | <0.1 | 0.03 | 5.8 | <0.1 | <0.05 | 7 | 0.5 | <0.2 |
| 1321234 | Soil | 13 | 52 | 0.74 | 178 | 0.123 | 1 | 2.29 | 0.036 | 0.05 | 0.1 | 0.04 | 7.0 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321235 | Soil | 11 | 46 | 0.67 | 177 | 0.119 | 2 | 2.48 | 0.026 | 0.06 | <0.1 | 0.03 | 5.4 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321236 | Soil | 12 | 53 | 0.75 | 209 | 0.127 | 2 | 2.95 | 0.026 | 0.06 | <0.1 | 0.03 | 6.8 | <0.1 | <0.05 | 8 | 0.5 | <0.2 |
| 1321237 | Soil | 11 | 44 | 0.69 | 162 | 0.128 | 2 | 2.29 | 0.025 | 0.05 | <0.1 | 0.01 | 4.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321238 | Soil | 14 | 50 | 0.70 | 193 | 0.129 | 1 | 2.50 | 0.028 | 0.05 | <0.1 | 0.03 | 7.2 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321239 | Soil | 12 | 42 | 1.01 | 121 | 0.134 | 4 | 1.70 | 0.076 | 0.08 | <0.1 | 0.03 | 6.9 | <0.1 | <0.05 | 5 | 0.6 | <0.2 |
| 1321240 | Soil | 13 | 44 | 0.93 | 173 | 0.125 | 3 | 1.99 | 0.067 | 0.09 | <0.1 | 0.04 | 6.9 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321241 | Soil | | 0.6 | 43.0 | 5.6 | 64 | <0.1 | 36.0 | 15.9 | 673 | 3.52 | 5.8 | 0.4 | 3.2 | 2.3 | 55 | 0.1 | 0.4 | <0.1 | 90 | 1.23 | 0.079 |
| 1321242 | Soil | | 0.7 | 51.2 | 8.2 | 63 | 0.1 | 37.9 | 15.8 | 672 | 3.62 | 7.2 | 0.4 | 3.0 | 2.2 | 51 | <0.1 | 0.4 | <0.1 | 90 | 1.06 | 0.064 |
| 1321243 | Soil | | 0.9 | 46.9 | 7.9 | 61 | <0.1 | 37.7 | 15.8 | 692 | 3.47 | 5.1 | 0.4 | 2.7 | 2.1 | 60 | 0.1 | 0.4 | <0.1 | 90 | 1.74 | 0.083 |
| 1321244 | Soil | | 1.0 | 31.5 | 6.7 | 57 | <0.1 | 33.6 | 15.1 | 388 | 4.10 | 8.5 | 0.6 | 2.3 | 3.5 | 34 | <0.1 | 0.4 | <0.1 | 113 | 0.63 | 0.052 |
| 1321245 | Soil | | 0.7 | 43.3 | 5.9 | 55 | <0.1 | 30.4 | 13.3 | 572 | 3.16 | 6.4 | 0.4 | 4.6 | 2.3 | 77 | 0.1 | 0.4 | <0.1 | 82 | 2.68 | 0.070 |
| 1321246 | Soil | | 1.1 | 39.7 | 8.2 | 54 | <0.1 | 37.6 | 15.1 | 569 | 3.84 | 7.8 | 0.4 | 2.0 | 2.6 | 38 | <0.1 | 0.5 | <0.1 | 91 | 0.81 | 0.026 |
| 1321247 | Soil | | 1.0 | 34.3 | 6.9 | 53 | <0.1 | 34.7 | 17.1 | 498 | 4.17 | 8.7 | 0.5 | 13.0 | 2.9 | 35 | <0.1 | 0.5 | 0.1 | 101 | 0.64 | 0.020 |
| 1321248 | Soil | | 0.9 | 50.5 | 4.9 | 51 | <0.1 | 36.9 | 18.0 | 655 | 4.19 | 9.0 | 0.4 | 3.5 | 1.9 | 46 | <0.1 | 0.4 | <0.1 | 117 | 1.20 | 0.101 |
| 1321249 | Soil | | 0.9 | 40.1 | 5.6 | 60 | <0.1 | 29.0 | 13.0 | 544 | 3.16 | 6.4 | 0.4 | 3.3 | 1.9 | 73 | 0.1 | 0.4 | <0.1 | 79 | 1.99 | 0.067 |
| 1321250 | Soil | | 1.1 | 39.1 | 9.9 | 52 | <0.1 | 39.6 | 17.6 | 512 | 4.24 | 9.0 | 0.6 | 1.7 | 3.8 | 38 | <0.1 | 0.5 | <0.1 | 104 | 0.76 | 0.035 |
| 1321251 | Soil | | 0.5 | 45.7 | 6.1 | 59 | <0.1 | 31.3 | 13.4 | 547 | 3.20 | 5.8 | 0.5 | 3.4 | 2.4 | 69 | 0.1 | 0.4 | <0.1 | 82 | 1.83 | 0.069 |
| 1321252 | Soil | | 0.5 | 50.1 | 6.5 | 54 | 0.1 | 34.3 | 14.8 | 641 | 3.24 | 6.5 | 1.1 | 4.6 | 2.2 | 64 | 0.1 | 0.5 | <0.1 | 83 | 1.28 | 0.064 |
| 1321253 | Soil | | 4.4 | 32.3 | 10.3 | 84 | 0.1 | 31.1 | 13.3 | 655 | 3.01 | 12.3 | 0.5 | 3.1 | 4.0 | 42 | 0.4 | 1.5 | 0.2 | 55 | 0.73 | 0.095 |
| 1321254 | Soil | | 0.6 | 39.0 | 5.4 | 57 | <0.1 | 29.2 | 11.6 | 480 | 2.88 | 6.4 | 0.4 | 4.9 | 2.9 | 67 | 0.1 | 0.5 | <0.1 | 74 | 2.21 | 0.084 |
| 1321255 | Soil | | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. |
| 1321256 | Soil | | 1.1 | 36.6 | 8.7 | 54 | <0.1 | 36.2 | 14.2 | 504 | 3.71 | 6.3 | 0.7 | 3.3 | 3.4 | 40 | <0.1 | 0.5 | 0.1 | 95 | 0.80 | 0.027 |
| 1321257 | Soil | | 0.7 | 39.0 | 5.1 | 61 | <0.1 | 36.2 | 15.3 | 594 | 3.28 | 6.3 | 0.4 | 3.5 | 2.4 | 95 | 0.2 | 0.4 | <0.1 | 80 | 3.59 | 0.070 |
| 1321258 | Soil | | 1.0 | 44.3 | 7.2 | 65 | <0.1 | 40.0 | 16.3 | 604 | 3.94 | 7.2 | 0.6 | 3.5 | 3.2 | 40 | <0.1 | 0.6 | <0.1 | 94 | 0.93 | 0.043 |
| 1321259 | Soil | | 0.8 | 38.5 | 7.4 | 59 | <0.1 | 40.3 | 16.0 | 583 | 3.61 | 6.5 | 0.5 | 4.4 | 2.9 | 44 | 0.1 | 0.5 | <0.1 | 96 | 1.01 | 0.071 |
| 1321260 | Soil | | 9.4 | 47.6 | 11.3 | 89 | 0.4 | 45.9 | 14.5 | 607 | 3.42 | 17.0 | 0.7 | 2.7 | 6.1 | 51 | 0.7 | 1.9 | 0.1 | 49 | 1.06 | 0.086 |
| 1321261 | Soil | | 0.6 | 32.7 | 6.3 | 54 | 0.1 | 26.9 | 11.8 | 336 | 2.94 | 7.1 | 0.8 | 3.4 | 2.7 | 53 | 0.2 | 0.4 | <0.1 | 77 | 1.02 | 0.058 |
| 1321262 | Soil | | 0.6 | 36.1 | 4.9 | 54 | <0.1 | 27.7 | 11.6 | 456 | 2.85 | 6.6 | 0.4 | 6.7 | 2.3 | 66 | 0.1 | 0.5 | <0.1 | 82 | 1.91 | 0.081 |
| 1321263 | Soil | | 0.8 | 41.5 | 7.0 | 56 | <0.1 | 36.1 | 14.3 | 519 | 3.29 | 8.1 | 0.3 | 2.8 | 2.3 | 59 | <0.1 | 0.5 | <0.1 | 86 | 1.61 | 0.045 |
| 1321264 | Soil | | 0.8 | 39.8 | 7.6 | 53 | <0.1 | 30.6 | 12.7 | 523 | 3.00 | 6.7 | 0.4 | 2.7 | 2.1 | 88 | 0.1 | 0.5 | <0.1 | 78 | 3.13 | 0.048 |
| 1321265 | Soil | | 0.8 | 26.3 | 5.1 | 52 | <0.1 | 29.1 | 13.4 | 442 | 2.85 | 8.5 | 0.6 | 4.2 | 1.7 | 66 | 0.1 | 0.6 | <0.1 | 71 | 1.36 | 0.088 |
| 1321266 | Soil | | 0.8 | 16.9 | 10.3 | 26 | 0.9 | 12.2 | 3.6 | 105 | 1.69 | 33.1 | 0.5 | 23.3 | 1.3 | 25 | <0.1 | 6.0 | <0.1 | 42 | 0.29 | 0.053 |
| 1321267 | Soil | | 2.0 | 22.2 | 10.7 | 37 | 0.4 | 20.8 | 6.5 | 187 | 2.59 | 30.3 | 0.7 | 10.0 | 2.1 | 31 | <0.1 | 7.3 | 0.1 | 62 | 0.37 | 0.055 |
| 1321268 | Soil | | 1.4 | 24.8 | 8.1 | 49 | 0.3 | 23.6 | 9.6 | 289 | 3.24 | 22.5 | 0.5 | 7.2 | 1.7 | 31 | <0.1 | 5.5 | 0.1 | 84 | 0.44 | 0.055 |
| 1321269 | Soil | | 1.6 | 37.7 | 8.5 | 53 | 0.3 | 34.9 | 11.7 | 370 | 3.22 | 19.4 | 0.7 | 8.4 | 2.1 | 40 | 0.2 | 5.1 | 0.1 | 80 | 0.58 | 0.061 |
| 1321270 | Soil | | 0.9 | 45.6 | 6.6 | 61 | 0.2 | 72.0 | 10.8 | 215 | 3.47 | 18.9 | 0.7 | 8.9 | 1.6 | 37 | 0.2 | 2.6 | <0.1 | 73 | 0.53 | 0.053 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321241 | Soil | 13 | 45 | 1.01 | 163 | 0.143 | 3 | 2.07 | 0.075 | 0.09 | <0.1 | 0.03 | 7.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321242 | Soil | 14 | 47 | 0.95 | 188 | 0.136 | 3 | 2.21 | 0.068 | 0.08 | <0.1 | 0.05 | 7.5 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1321243 | Soil | 12 | 48 | 1.06 | 146 | 0.141 | 3 | 1.99 | 0.077 | 0.10 | <0.1 | 0.04 | 8.0 | 0.1 | <0.05 | 6 | 0.5 | <0.2 |
| 1321244 | Soil | 15 | 52 | 0.94 | 196 | 0.167 | 2 | 2.81 | 0.034 | 0.09 | <0.1 | 0.01 | 7.0 | 0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1321245 | Soil | 12 | 38 | 0.90 | 157 | 0.137 | 3 | 1.91 | 0.076 | 0.09 | <0.1 | 0.02 | 6.3 | <0.1 | <0.05 | 6 | 0.5 | <0.2 |
| 1321246 | Soil | 16 | 49 | 0.82 | 183 | 0.132 | 3 | 2.33 | 0.047 | 0.08 | <0.1 | 0.02 | 9.3 | <0.1 | <0.05 | 7 | 0.6 | <0.2 |
| 1321247 | Soil | 13 | 58 | 0.80 | 160 | 0.139 | 2 | 2.78 | 0.040 | 0.08 | <0.1 | 0.02 | 11.2 | <0.1 | <0.05 | 8 | <0.5 | <0.2 |
| 1321248 | Soil | 15 | 65 | 1.61 | 148 | 0.150 | 2 | 2.81 | 0.116 | 0.09 | 0.1 | 0.02 | 12.0 | <0.1 | <0.05 | 8 | 0.6 | <0.2 |
| 1321249 | Soil | 12 | 37 | 0.88 | 158 | 0.128 | 3 | 1.81 | 0.076 | 0.08 | <0.1 | 0.03 | 5.7 | <0.1 | <0.05 | 5 | 0.5 | <0.2 |
| 1321250 | Soil | 14 | 58 | 0.90 | 141 | 0.165 | 3 | 2.77 | 0.038 | 0.15 | <0.1 | 0.02 | 10.5 | 0.1 | <0.05 | 8 | 0.5 | <0.2 |
| 1321251 | Soil | 13 | 39 | 0.87 | 165 | 0.140 | 3 | 1.94 | 0.078 | 0.09 | <0.1 | 0.03 | 6.7 | <0.1 | <0.05 | 6 | 0.6 | <0.2 |
| 1321252 | Soil | 14 | 41 | 0.83 | 193 | 0.130 | 3 | 2.09 | 0.068 | 0.07 | <0.1 | 0.04 | 6.8 | <0.1 | <0.05 | 6 | 0.8 | <0.2 |
| 1321253 | Soil | 15 | 30 | 0.69 | 201 | 0.055 | 2 | 1.72 | 0.025 | 0.07 | <0.1 | 0.02 | 3.7 | <0.1 | <0.05 | 5 | 1.3 | <0.2 |
| 1321254 | Soil | 11 | 35 | 0.90 | 124 | 0.115 | 3 | 1.55 | 0.076 | 0.10 | 0.1 | 0.02 | 5.4 | <0.1 | <0.05 | 5 | 0.8 | <0.2 |
| 1321255 | Soil | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. | I.S. |
| 1321256 | Soil | 14 | 50 | 0.82 | 161 | 0.131 | 2 | 2.45 | 0.054 | 0.07 | 0.1 | 0.02 | 8.7 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321257 | Soil | 12 | 42 | 1.14 | 147 | 0.119 | 3 | 1.79 | 0.081 | 0.09 | <0.1 | 0.02 | 6.2 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321258 | Soil | 18 | 51 | 0.98 | 137 | 0.152 | 1 | 2.35 | 0.056 | 0.08 | 0.1 | 0.02 | 9.0 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321259 | Soil | 14 | 50 | 1.02 | 153 | 0.132 | 2 | 2.00 | 0.058 | 0.08 | <0.1 | 0.02 | 8.4 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321260 | Soil | 26 | 32 | 0.67 | 182 | 0.040 | 2 | 1.60 | 0.023 | 0.12 | <0.1 | 0.05 | 7.9 | <0.1 | <0.05 | 4 | 1.9 | <0.2 |
| 1321261 | Soil | 12 | 36 | 0.69 | 191 | 0.108 | 3 | 1.98 | 0.051 | 0.05 | 0.1 | 0.04 | 6.3 | <0.1 | <0.05 | 5 | 0.6 | <0.2 |
| 1321262 | Soil | 10 | 34 | 0.88 | 118 | 0.122 | 3 | 1.58 | 0.066 | 0.09 | 0.1 | 0.02 | 5.7 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321263 | Soil | 13 | 42 | 0.90 | 168 | 0.128 | 3 | 1.98 | 0.066 | 0.07 | <0.1 | 0.03 | 7.0 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321264 | Soil | 12 | 37 | 0.89 | 163 | 0.130 | 3 | 1.87 | 0.066 | 0.07 | <0.1 | 0.02 | 6.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321265 | Soil | 10 | 35 | 0.72 | 175 | 0.104 | 3 | 1.71 | 0.051 | 0.06 | <0.1 | 0.03 | 5.7 | <0.1 | <0.05 | 5 | 0.6 | <0.2 |
| 1321266 | Soil | 7 | 22 | 0.23 | 203 | 0.055 | 1 | 0.96 | 0.035 | 0.05 | 0.1 | 0.49 | 2.5 | 0.3 | 0.08 | 4 | 0.7 | <0.2 |
| 1321267 | Soil | 10 | 40 | 0.45 | 259 | 0.097 | 2 | 1.54 | 0.034 | 0.08 | <0.1 | 0.58 | 4.3 | 0.7 | 0.12 | 5 | 0.7 | <0.2 |
| 1321268 | Soil | 9 | 41 | 0.61 | 210 | 0.091 | 2 | 2.30 | 0.026 | 0.10 | <0.1 | 0.21 | 5.0 | 0.3 | <0.05 | 7 | 0.5 | <0.2 |
| 1321269 | Soil | 11 | 49 | 0.62 | 194 | 0.100 | 2 | 2.06 | 0.030 | 0.05 | <0.1 | 0.31 | 6.0 | 0.4 | <0.05 | 6 | 0.6 | <0.2 |
| 1321270 | Soil | 9 | 50 | 0.52 | 148 | 0.099 | 1 | 1.99 | 0.030 | 0.04 | <0.1 | 0.27 | 7.3 | 0.3 | <0.05 | 6 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| 1321271 | Soil | 0.9 | 49.1 | 6.3 | 66 | 0.2 | 42.5 | 11.7 | 272 | 3.82 | 31.0 | 0.8 | 9.2 | 2.3 | 43 | 0.2 | 2.5 | 0.1 | 88 | 0.56 | 0.074 |
| 1321272 | Soil | 1.0 | 46.1 | 5.8 | 42 | 0.3 | 35.5 | 7.1 | 207 | 2.37 | 11.7 | 0.8 | 14.4 | 1.0 | 42 | 0.3 | 2.3 | <0.1 | 55 | 0.64 | 0.061 |
| 1321273 | Soil | 1.1 | 36.3 | 6.8 | 70 | 0.2 | 54.6 | 13.8 | 364 | 3.55 | 18.0 | 0.7 | 6.4 | 1.8 | 40 | 0.2 | 3.0 | <0.1 | 88 | 0.67 | 0.075 |
| 1321274 | Soil | 0.8 | 21.7 | 8.4 | 51 | 0.1 | 20.3 | 8.4 | 259 | 2.21 | 15.1 | 0.4 | 5.3 | 1.5 | 29 | 0.1 | 0.7 | 0.1 | 57 | 0.45 | 0.038 |
| 1321275 | Soil | 0.9 | 26.1 | 7.9 | 52 | 0.1 | 25.2 | 10.8 | 421 | 2.62 | 10.1 | 0.7 | 22.4 | 1.9 | 37 | 0.1 | 0.6 | 0.1 | 67 | 0.58 | 0.047 |
| 1321276 | Soil | 0.7 | 27.9 | 8.4 | 57 | 0.1 | 28.6 | 10.6 | 332 | 2.63 | 8.7 | 0.8 | 7.5 | 2.0 | 44 | 0.1 | 0.6 | 0.1 | 65 | 0.71 | 0.062 |
| 1321277 | Soil | 0.7 | 31.0 | 8.8 | 63 | <0.1 | 29.6 | 10.6 | 323 | 2.92 | 11.1 | 0.8 | 13.9 | 2.9 | 42 | 0.1 | 0.5 | 0.1 | 74 | 0.68 | 0.057 |
| 1321278 | Soil | 1.0 | 30.8 | 12.6 | 63 | <0.1 | 30.7 | 12.7 | 454 | 3.11 | 13.2 | 0.8 | 5.7 | 2.8 | 40 | 0.1 | 0.5 | 0.1 | 81 | 0.65 | 0.054 |
| 1321279 | Soil | 0.7 | 29.0 | 8.3 | 46 | 0.2 | 23.3 | 8.7 | 263 | 2.39 | 5.8 | 0.8 | 2.6 | 1.9 | 37 | 0.2 | 0.4 | 0.1 | 58 | 0.59 | 0.039 |
| 1321280 | Soil | 0.7 | 21.6 | 7.8 | 49 | 0.1 | 20.5 | 9.0 | 301 | 2.21 | 5.4 | 0.5 | 1.7 | 1.6 | 35 | 0.2 | 0.4 | 0.1 | 53 | 0.51 | 0.037 |
| 1321281 | Soil | 0.7 | 18.4 | 6.9 | 46 | <0.1 | 20.7 | 8.4 | 235 | 2.13 | 6.7 | 0.4 | 2.4 | 1.8 | 32 | <0.1 | 0.6 | 0.1 | 53 | 0.47 | 0.053 |
| 1321282 | Soil | 0.8 | 18.6 | 9.8 | 52 | <0.1 | 27.5 | 10.6 | 319 | 2.92 | 9.7 | 0.4 | 4.0 | 2.3 | 34 | <0.1 | 0.5 | 0.1 | 78 | 0.53 | 0.042 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# CERTIFICATE OF ANALYSIS WHI20000133.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| 1321271 | Soil | 11 | 70 | 0.71 | 174 | 0.127 | 1 | 2.34 | 0.031 | 0.05 | <0.1 | 0.29 | 8.5 | 0.4 | <0.05 | 7 | 0.6 | <0.2 |
| 1321272 | Soil | 10 | 39 | 0.47 | 164 | 0.076 | 2 | 1.59 | 0.029 | 0.04 | <0.1 | 0.37 | 6.5 | 0.3 | 0.05 | 5 | 0.7 | <0.2 |
| 1321273 | Soil | 10 | 53 | 0.72 | 168 | 0.113 | 2 | 2.05 | 0.034 | 0.05 | <0.1 | 0.24 | 7.1 | 0.3 | <0.05 | 6 | 0.6 | <0.2 |
| 1321274 | Soil | 8 | 34 | 0.53 | 141 | 0.091 | 1 | 1.61 | 0.028 | 0.04 | <0.1 | 0.02 | 4.0 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321275 | Soil | 10 | 39 | 0.59 | 164 | 0.096 | 1 | 2.00 | 0.033 | 0.04 | <0.1 | 0.02 | 5.7 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321276 | Soil | 11 | 42 | 0.62 | 174 | 0.096 | 2 | 2.07 | 0.031 | 0.05 | <0.1 | 0.04 | 6.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321277 | Soil | 12 | 48 | 0.68 | 165 | 0.123 | 2 | 2.15 | 0.039 | 0.05 | <0.1 | 0.03 | 7.0 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321278 | Soil | 11 | 48 | 0.69 | 184 | 0.115 | 2 | 2.25 | 0.032 | 0.05 | <0.1 | 0.03 | 6.6 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321279 | Soil | 10 | 35 | 0.50 | 161 | 0.092 | 1 | 1.95 | 0.031 | 0.04 | <0.1 | 0.03 | 5.1 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321280 | Soil | 9 | 32 | 0.47 | 148 | 0.086 | 2 | 1.77 | 0.029 | 0.05 | <0.1 | 0.03 | 4.3 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321281 | Soil | 10 | 32 | 0.45 | 113 | 0.089 | 1 | 1.42 | 0.029 | 0.04 | <0.1 | 0.02 | 3.4 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321282 | Soil | 9 | 45 | 0.67 | 166 | 0.112 | 1 | 2.13 | 0.026 | 0.05 | <0.1 | 0.01 | 4.8 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.
9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# QUALITY CONTROL REPORT WHI20000133.1

| | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Analyte | Mo | Cu | Pb | Zn | Ag | Ni | Co | Mn | Fe | As | U | Au | Th | Sr | Cd | Sb | Bi | V | Ca | P |
| | Unit | ppm | ppm | ppm | ppm | ppm | ppm | ppm | ppm | % | ppm | ppm | ppb | ppm | ppm | ppm | ppm | ppm | ppm | % | % |
| | MDL | 0.1 | 0.1 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 1 | 0.01 | 0.5 | 0.1 | 0.5 | 0.1 | 1 | 0.1 | 0.1 | 0.1 | 2 | 0.01 | 0.001 |
| Pulp Duplicates | | | | | | | | | | | | | | | | | | | | | |
| 1321024 | Soil | 0.8 | 41.9 | 7.9 | 65 | <0.1 | 34.5 | 14.3 | 594 | 3.62 | 8.3 | 0.5 | 2.9 | 3.1 | 45 | <0.1 | 0.6 | 0.1 | 85 | 0.82 | 0.054 |
| REP 1321024 | QC | 0.7 | 39.8 | 7.5 | 65 | <0.1 | 33.6 | 14.0 | 631 | 3.53 | 8.5 | 0.5 | 4.1 | 3.2 | 45 | <0.1 | 0.5 | <0.1 | 84 | 0.80 | 0.057 |
| 1321066 | Soil | 0.6 | 47.4 | 6.1 | 63 | <0.1 | 37.3 | 15.0 | 540 | 3.50 | 5.7 | 0.4 | 4.2 | 3.0 | 55 | <0.1 | 0.4 | <0.1 | 94 | 1.15 | 0.066 |
| REP 1321066 | QC | 0.6 | 48.0 | 6.2 | 66 | <0.1 | 37.0 | 15.9 | 530 | 3.59 | 5.6 | 0.5 | 7.2 | 3.1 | 56 | 0.1 | 0.4 | <0.1 | 92 | 1.08 | 0.066 |
| 1321102 | Soil | 0.7 | 24.5 | 4.7 | 40 | <0.1 | 22.4 | 13.1 | 498 | 2.49 | 6.5 | 0.8 | <0.5 | 1.8 | 57 | <0.1 | 0.3 | <0.1 | 67 | 1.40 | 0.056 |
| REP 1321102 | QC | 0.6 | 23.3 | 4.3 | 38 | <0.1 | 20.3 | 12.7 | 473 | 2.34 | 6.0 | 0.7 | 2.2 | 1.8 | 52 | <0.1 | 0.3 | <0.1 | 60 | 1.28 | 0.048 |
| 1321138 | Soil | 1.3 | 20.8 | 9.3 | 51 | 0.2 | 28.1 | 10.8 | 251 | 3.45 | 9.4 | 0.4 | 3.3 | 2.5 | 30 | 0.1 | 0.5 | 0.1 | 93 | 0.41 | 0.023 |
| REP 1321138 | QC | 1.4 | 20.3 | 9.3 | 49 | 0.2 | 27.6 | 10.9 | 244 | 3.24 | 9.7 | 0.4 | 4.7 | 2.6 | 30 | <0.1 | 0.4 | 0.1 | 88 | 0.40 | 0.023 |
| 1321174 | Soil | 0.4 | 39.2 | 5.3 | 51 | <0.1 | 33.7 | 11.0 | 393 | 2.74 | 5.4 | 0.7 | 5.8 | 2.2 | 59 | 0.2 | 0.4 | <0.1 | 67 | 1.36 | 0.061 |
| REP 1321174 | QC | 0.3 | 39.2 | 5.2 | 51 | <0.1 | 34.1 | 11.3 | 383 | 2.62 | 5.3 | 0.7 | 3.9 | 2.1 | 58 | 0.1 | 0.4 | <0.1 | 64 | 1.33 | 0.061 |
| 1321210 | Soil | 0.5 | 26.3 | 4.1 | 43 | 0.1 | 21.1 | 9.1 | 446 | 2.05 | 4.2 | 0.8 | 117.4 | 1.3 | 77 | 0.1 | 0.4 | <0.1 | 50 | 1.78 | 0.060 |
| REP 1321210 | QC | 0.5 | 26.8 | 4.3 | 46 | <0.1 | 21.8 | 9.4 | 453 | 2.06 | 4.4 | 0.9 | 2.5 | 1.4 | 80 | 0.2 | 0.4 | <0.1 | 50 | 1.82 | 0.063 |
| 1321245 | Soil | 0.7 | 43.3 | 5.9 | 55 | <0.1 | 30.4 | 13.3 | 572 | 3.16 | 6.4 | 0.4 | 4.6 | 2.3 | 77 | 0.1 | 0.4 | <0.1 | 82 | 2.68 | 0.070 |
| REP 1321245 | QC | 0.7 | 43.6 | 6.2 | 55 | <0.1 | 30.4 | 13.6 | 577 | 3.18 | 6.3 | 0.4 | 3.0 | 2.3 | 76 | 0.1 | 0.4 | <0.1 | 82 | 2.69 | 0.070 |
| 1321257 | Soil | 0.7 | 39.0 | 5.1 | 61 | <0.1 | 36.2 | 15.3 | 594 | 3.28 | 6.3 | 0.4 | 3.5 | 2.4 | 95 | 0.2 | 0.4 | <0.1 | 80 | 3.59 | 0.070 |
| REP 1321257 | QC | 0.7 | 38.2 | 5.1 | 62 | <0.1 | 36.1 | 15.4 | 598 | 3.28 | 6.2 | 0.4 | 7.3 | 2.4 | 95 | 0.2 | 0.4 | <0.1 | 81 | 3.66 | 0.073 |
| 1321277 | Soil | 0.7 | 31.0 | 8.8 | 63 | <0.1 | 29.6 | 10.6 | 323 | 2.92 | 11.1 | 0.8 | 13.9 | 2.9 | 42 | 0.1 | 0.5 | 0.1 | 74 | 0.68 | 0.057 |
| REP 1321277 | QC | 0.7 | 31.1 | 8.8 | 61 | <0.1 | 29.3 | 10.5 | 320 | 2.89 | 11.1 | 0.8 | 6.1 | 3.0 | 41 | 0.1 | 0.5 | 0.1 | 73 | 0.67 | 0.056 |
| Reference Materials | | | | | | | | | | | | | | | | | | | | | |
| STD BVGEO01 | Standard | 10.6 | 4159.9 | 183.0 | 1647 | 2.6 | 172.7 | 25.6 | 702 | 3.91 | 117.0 | 3.6 | 220.7 | 15.0 | 59 | 6.1 | 3.1 | 23.2 | 71 | 1.34 | 0.070 |
| STD BVGEO01 | Standard | 10.2 | 4288.4 | 182.1 | 1648 | 2.4 | 162.5 | 23.7 | 643 | 3.59 | 106.4 | 3.5 | 209.9 | 15.4 | 54 | 5.6 | 3.2 | 23.4 | 75 | 1.27 | 0.066 |
| STD BVGEO01 | Standard | 10.1 | 4287.6 | 182.5 | 1581 | 2.5 | 153.0 | 23.1 | 665 | 3.70 | 111.6 | 3.6 | 203.8 | 15.2 | 56 | 6.0 | 3.3 | 24.0 | 71 | 1.34 | 0.073 |
| STD DS11 | Standard | 15.2 | 149.3 | 136.8 | 337 | 1.7 | 76.0 | 13.1 | 1004 | 3.10 | 41.0 | 2.6 | 71.5 | 8.2 | 67 | 2.6 | 8.5 | 11.2 | 48 | 1.05 | 0.067 |
| STD DS11 | Standard | 15.7 | 149.2 | 138.1 | 365 | 1.7 | 84.7 | 14.6 | 1040 | 3.43 | 42.5 | 2.7 | 69.1 | 8.8 | 70 | 2.1 | 8.5 | 11.2 | 52 | 1.11 | 0.067 |
| STD DS11 | Standard | 14.4 | 152.5 | 134.9 | 338 | 1.6 | 80.5 | 13.6 | 1056 | 3.21 | 38.5 | 2.4 | 74.9 | 7.2 | 69 | 2.1 | 7.6 | 9.6 | 52 | 1.08 | 0.068 |
| STD DS11 | Standard | 14.5 | 144.7 | 137.9 | 342 | 1.7 | 77.1 | 13.2 | 947 | 3.13 | 41.2 | 2.5 | 69.2 | 8.3 | 64 | 2.1 | 8.6 | 11.3 | 50 | 1.04 | 0.067 |
| STD DS11 | Standard | 15.5 | 144.1 | 137.7 | 340 | 1.7 | 79.7 | 13.6 | 979 | 3.23 | 43.3 | 2.7 | 75.3 | 8.8 | 70 | 2.3 | 8.1 | 11.5 | 52 | 1.09 | 0.068 |
| STD OREAS262 | Standard | 0.8 | 112.9 | 55.8 | 146 | 0.5 | 62.4 | 25.3 | 556 | 3.23 | 34.2 | 1.2 | 62.9 | 9.5 | 35 | 0.6 | 5.5 | 1.0 | 23 | 2.96 | 0.038 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.
9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# QUALITY CONTROL REPORT WHI20000133.1

| | | Method | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 | AQ201 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Analyte | La | Cr | Mg | Ba | Ti | B | Al | Na | K | W | Hg | Sc | Tl | S | Ga | Se | Te |
| | | Unit | ppm | ppm | % | ppm | % | ppm | % | % | % | ppm | ppm | ppm | ppm | % | ppm | ppm | ppm |
| | | MDL | 1 | 1 | 0.01 | 1 | 0.001 | 1 | 0.01 | 0.001 | 0.01 | 0.1 | 0.01 | 0.1 | 0.1 | 0.05 | 1 | 0.5 | 0.2 |
| Pulp Duplicates | | | | | | | | | | | | | | | | | | | |
| 1321024 | Soil | | 15 | 44 | 0.84 | 223 | 0.116 | 2 | 2.21 | 0.060 | 0.06 | <0.1 | 0.01 | 7.9 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| REP 1321024 | QC | | 15 | 44 | 0.83 | 220 | 0.113 | 3 | 2.05 | 0.055 | 0.06 | <0.1 | 0.02 | 8.0 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321066 | Soil | | 14 | 46 | 0.99 | 146 | 0.151 | 3 | 2.18 | 0.082 | 0.08 | <0.1 | 0.04 | 8.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| REP 1321066 | QC | | 14 | 47 | 1.01 | 150 | 0.153 | 3 | 2.08 | 0.080 | 0.08 | <0.1 | 0.04 | 8.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| 1321102 | Soil | | 10 | 30 | 0.58 | 146 | 0.098 | 3 | 1.51 | 0.049 | 0.04 | <0.1 | 0.03 | 4.5 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| REP 1321102 | QC | | 9 | 27 | 0.52 | 139 | 0.086 | 2 | 1.39 | 0.049 | 0.04 | <0.1 | 0.03 | 4.1 | <0.1 | <0.05 | 4 | <0.5 | <0.2 |
| 1321138 | Soil | | 9 | 47 | 0.61 | 159 | 0.105 | 1 | 2.32 | 0.020 | 0.07 | <0.1 | 0.01 | 4.4 | <0.1 | <0.05 | 7 | <0.5 | <0.2 |
| REP 1321138 | QC | | 9 | 45 | 0.66 | 149 | 0.107 | 2 | 2.39 | 0.021 | 0.07 | <0.1 | 0.01 | 4.3 | 0.1 | <0.05 | 7 | <0.5 | <0.2 |
| 1321174 | Soil | | 10 | 41 | 0.73 | 154 | 0.115 | 4 | 1.86 | 0.065 | 0.05 | 0.1 | 0.04 | 6.0 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| REP 1321174 | QC | | 10 | 40 | 0.73 | 148 | 0.111 | 3 | 1.86 | 0.064 | 0.05 | <0.1 | 0.04 | 5.5 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321210 | Soil | | 9 | 27 | 0.57 | 146 | 0.079 | 4 | 1.36 | 0.050 | 0.06 | <0.1 | 0.02 | 4.3 | <0.1 | <0.05 | 4 | 0.7 | <0.2 |
| REP 1321210 | QC | | 8 | 27 | 0.61 | 148 | 0.081 | 4 | 1.44 | 0.054 | 0.06 | <0.1 | 0.05 | 4.3 | <0.1 | <0.05 | 4 | 0.6 | <0.2 |
| 1321245 | Soil | | 12 | 38 | 0.90 | 157 | 0.137 | 3 | 1.91 | 0.076 | 0.09 | <0.1 | 0.02 | 6.3 | <0.1 | <0.05 | 6 | 0.5 | <0.2 |
| REP 1321245 | QC | | 13 | 39 | 0.90 | 159 | 0.139 | 3 | 1.90 | 0.074 | 0.09 | <0.1 | 0.03 | 6.4 | <0.1 | <0.05 | 6 | 0.5 | <0.2 |
| 1321257 | Soil | | 12 | 42 | 1.14 | 147 | 0.119 | 3 | 1.79 | 0.081 | 0.09 | <0.1 | 0.02 | 6.2 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| REP 1321257 | QC | | 11 | 42 | 1.14 | 150 | 0.120 | 3 | 1.78 | 0.079 | 0.09 | <0.1 | 0.02 | 6.1 | <0.1 | <0.05 | 5 | <0.5 | <0.2 |
| 1321277 | Soil | | 12 | 48 | 0.68 | 165 | 0.123 | 2 | 2.15 | 0.039 | 0.05 | <0.1 | 0.03 | 7.0 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| REP 1321277 | QC | | 12 | 47 | 0.67 | 166 | 0.120 | 2 | 2.12 | 0.039 | 0.05 | <0.1 | 0.03 | 6.6 | <0.1 | <0.05 | 6 | <0.5 | <0.2 |
| Reference Materials | | | | | | | | | | | | | | | | | | | |
| STD BVGEO01 | Standard | | 26 | 212 | 1.38 | 250 | 0.224 | 3 | 2.46 | 0.202 | 0.88 | 4.4 | 0.10 | 5.9 | 0.6 | 0.71 | 8 | 4.8 | 0.9 |
| STD BVGEO01 | Standard | | 24 | 207 | 1.22 | 237 | 0.217 | 3 | 2.17 | 0.186 | 0.81 | 4.8 | 0.10 | 5.6 | 0.6 | 0.61 | 7 | 4.0 | 0.9 |
| STD BVGEO01 | Standard | | 25 | 186 | 1.32 | 260 | 0.224 | 4 | 2.31 | 0.203 | 0.90 | 5.0 | 0.09 | 5.8 | 0.6 | 0.64 | 8 | 4.6 | 1.1 |
| STD DS11 | Standard | | 19 | 59 | 0.86 | 384 | 0.092 | 8 | 1.18 | 0.073 | 0.43 | 3.1 | 0.26 | 3.5 | 4.8 | 0.28 | 5 | 2.0 | 4.6 |
| STD DS11 | Standard | | 20 | 64 | 0.88 | 382 | 0.099 | 7 | 1.18 | 0.077 | 0.41 | 2.9 | 0.25 | 3.1 | 4.9 | 0.36 | 5 | 1.6 | 4.6 |
| STD DS11 | Standard | | 19 | 61 | 0.87 | 361 | 0.096 | 7 | 1.21 | 0.072 | 0.40 | 3.2 | 0.29 | 3.2 | 5.1 | 0.34 | 5 | 2.6 | 4.8 |
| STD DS11 | Standard | | 17 | 59 | 0.86 | 362 | 0.090 | 8 | 1.17 | 0.077 | 0.40 | 3.0 | 0.26 | 3.2 | 4.8 | 0.25 | 5 | 2.9 | 4.4 |
| STD DS11 | Standard | | 20 | 60 | 0.88 | 380 | 0.097 | 7 | 1.21 | 0.080 | 0.41 | 2.9 | 0.25 | 3.3 | 5.1 | 0.25 | 5 | 1.6 | 4.9 |
| STD OREAS262 | Standard | | 16 | 42 | 1.18 | 256 | 0.003 | 4 | 1.32 | 0.064 | 0.31 | 0.2 | 0.17 | 3.4 | 0.5 | 0.30 | 4 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# QUALITY CONTROL REPORT WHI20000133.1

| | | AQ201 Mo ppm 0.1 | AQ201 Cu ppm 0.1 | AQ201 Pb ppm 0.1 | AQ201 Zn ppm 1 | AQ201 Ag ppm 0.1 | AQ201 Ni ppm 0.1 | AQ201 Co ppm 0.1 | AQ201 Mn ppm 1 | AQ201 Fe % 0.01 | AQ201 As ppm 0.5 | AQ201 U ppm 0.1 | AQ201 Au ppb 0.5 | AQ201 Th ppm 0.1 | AQ201 Sr ppm 1 | AQ201 Cd ppm 0.1 | AQ201 Sb ppm 0.1 | AQ201 Bi ppm 0.1 | AQ201 V ppm 2 | AQ201 Ca % 0.01 | AQ201 P % 0.001 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| STD OREAS262 | Standard | 0.7 | 111.5 | 53.8 | 147 | 0.5 | 63.2 | 26.6 | 536 | 3.29 | 34.2 | 1.1 | 68.2 | 8.8 | 35 | 0.6 | 5.8 | 1.0 | 23 | 2.95 | 0.039 |
| STD OREAS262 | Standard | 0.6 | 115.2 | 55.2 | 149 | 0.5 | 64.8 | 28.1 | 503 | 3.36 | 35.7 | 1.2 | 63.0 | 9.6 | 36 | 0.6 | 4.7 | 1.0 | 21 | 2.97 | 0.037 |
| STD OREAS262 | Standard | 0.6 | 119.3 | 56.1 | 154 | 0.5 | 69.8 | 28.2 | 545 | 3.47 | 36.1 | 1.2 | 61.1 | 10.2 | 36 | 0.7 | 4.9 | 1.0 | 22 | 3.07 | 0.038 |
| STD OREAS262 | Standard | 0.6 | 109.6 | 55.2 | 142 | 0.5 | 65.3 | 27.5 | 502 | 3.27 | 32.9 | 1.2 | 60.0 | 9.5 | 33 | 0.6 | 4.5 | 0.9 | 22 | 2.83 | 0.038 |
| STD OREAS262 | Standard | 0.6 | 118.9 | 55.5 | 147 | 0.4 | 64.1 | 27.8 | 564 | 3.43 | 32.3 | 1.2 | 59.9 | 9.2 | 36 | 0.6 | 4.1 | 0.9 | 25 | 3.07 | 0.039 |
| STD OREAS262 | Standard | 0.7 | 114.7 | 55.8 | 150 | 0.4 | 65.7 | 27.8 | 517 | 3.41 | 34.6 | 1.2 | 63.5 | 9.6 | 34 | 0.6 | 5.4 | 0.9 | 24 | 3.08 | 0.039 |
| STD OREAS262 | Standard | 0.6 | 111.0 | 56.7 | 150 | 0.4 | 64.3 | 27.3 | 528 | 3.45 | 35.4 | 1.2 | 59.6 | 10.1 | 35 | 0.7 | 4.5 | 1.0 | 23 | 3.06 | 0.040 |
| STD OREAS262 | Standard | 0.7 | 115.2 | 57.6 | 156 | 0.5 | 63.9 | 27.7 | 528 | 3.49 | 36.7 | 1.2 | 64.6 | 10.2 | 37 | 0.7 | 4.5 | 1.0 | 23 | 3.14 | 0.042 |
| STD DS11 Expected | | 14.6 | 149 | 138 | 345 | 1.71 | 77.7 | 14.2 | 1055 | 3.1 | 42.8 | 2.59 | 79 | 7.65 | 67.3 | 2.37 | 8.74 | 12.2 | 50 | 1.063 | 0.0701 |
| STD BVGEO01 Expected | | 11.2 | 4415 | 187 | 1741 | 2.53 | 163 | 25 | 733 | 3.7 | 121 | 3.77 | 219 | 14.4 | 55 | 6.5 | 3.39 | 25.6 | 73 | 1.3219 | 0.0727 |
| STD OREAS262 Expected | | 0.68 | 118 | 56 | 154 | 0.45 | 62 | 26.9 | 530 | 3.284 | 35.8 | 1.22 | 65 | 9.33 | 36 | 0.61 | 5.06 | 1.03 | 22.5 | 2.98 | 0.04 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |
| BLK | Blank | <0.1 | <0.1 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <1 | <0.01 | <0.5 | <0.1 | <0.5 | <0.1 | <1 | <0.1 | <0.1 | <0.1 | <2 | <0.01 | <0.001 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

BUREAU VERITAS MINERAL LABORATORIES Canada

www.bureauveritas.com/um

Bureau Veritas Commodities Canada Ltd.

9050 Shaughnessy St Vancouver British Columbia V6P 6E5 Canada
PHONE (604) 253-3158

**Client:** **Druid Exploration**
Box 1485
Dawson City Yukon Y0B 1G0 Canada

Project: BE
Report Date: August 06, 2020



# QUALITY CONTROL REPORT WHI20000133.1

| | | AQ201 La ppm 1 | AQ201 Cr ppm 1 | AQ201 Mg % 0.01 | AQ201 Ba ppm 1 | AQ201 Ti % 0.001 | AQ201 B ppm 1 | AQ201 Al % 0.01 | AQ201 Na % 0.001 | AQ201 K % 0.01 | AQ201 W ppm 0.1 | AQ201 Hg ppm 0.01 | AQ201 Sc ppm 0.1 | AQ201 Tl ppm 0.1 | AQ201 S % 0.05 | AQ201 Ga ppm 1 | AQ201 Se ppm 0.5 | AQ201 Te ppm 0.2 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| STD OREAS262 | Standard | 16 | 44 | 1.19 | 242 | 0.003 | 4 | 1.38 | 0.066 | 0.31 | 0.2 | 0.16 | 3.2 | 0.5 | 0.32 | 4 | 0.6 | 0.2 |
| STD OREAS262 | Standard | 16 | 43 | 1.21 | 264 | 0.003 | 4 | 1.40 | 0.072 | 0.29 | 0.2 | 0.17 | 3.0 | 0.5 | 0.20 | 4 | <0.5 | <0.2 |
| STD OREAS262 | Standard | 18 | 47 | 1.21 | 263 | 0.003 | 3 | 1.48 | 0.065 | 0.31 | 0.2 | 0.17 | 3.3 | 0.5 | 0.27 | 4 | <0.5 | 0.2 |
| STD OREAS262 | Standard | 17 | 44 | 1.14 | 234 | 0.002 | 4 | 1.37 | 0.067 | 0.30 | 0.2 | 0.17 | 3.1 | 0.5 | 0.26 | 4 | <0.5 | 0.2 |
| STD OREAS262 | Standard | 17 | 47 | 1.21 | 254 | 0.004 | 4 | 1.49 | 0.067 | 0.34 | 0.2 | 0.17 | 3.3 | 0.5 | 0.32 | 4 | 0.8 | 0.2 |
| STD OREAS262 | Standard | 16 | 45 | 1.22 | 239 | 0.003 | 4 | 1.35 | 0.071 | 0.30 | 0.2 | 0.16 | 3.4 | 0.5 | 0.26 | 4 | <0.5 | 0.3 |
| STD OREAS262 | Standard | 17 | 46 | 1.23 | 264 | 0.003 | 5 | 1.50 | 0.075 | 0.33 | 0.2 | 0.17 | 3.6 | 0.5 | 0.26 | 4 | <0.5 | 0.2 |
| STD OREAS262 | Standard | 16 | 45 | 1.28 | 251 | 0.003 | 6 | 1.45 | 0.079 | 0.33 | 0.2 | 0.17 | 3.5 | 0.5 | 0.25 | 5 | <0.5 | 0.2 |
| STD DS11 Expected | | 18.6 | 61.5 | 0.85 | 385 | 0.0976 | | 1.1795 | 0.0762 | 0.4 | 2.9 | 0.26 | 3.4 | 4.9 | 0.2835 | 5.1 | 2.2 | 4.56 |
| STD BVGEO01 Expected | | 25.9 | 187 | 1.2963 | 260 | 0.233 | 3.8 | 2.347 | 0.1924 | 0.89 | 5.3 | 0.1 | 5.97 | 0.62 | 0.6655 | 7.37 | 4.84 | 1.02 |
| STD OREAS262 Expected | | 15.9 | 41.7 | 1.17 | 248 | 0.0027 | 4 | 1.3 | 0.071 | 0.312 | 0.2 | 0.17 | 3.24 | 0.47 | 0.253 | 4.1 | 0.4 | 0.23 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |
| BLK | Blank | <1 | <1 | <0.01 | <1 | <0.001 | <1 | <0.01 | <0.001 | <0.01 | <0.1 | <0.01 | <0.1 | <0.1 | <0.05 | <1 | <0.5 | <0.2 |

This report supersedes all previous preliminary and final reports with this file number dated prior to the date on this certificate. Signature indicates final approval; preliminary reports are unsigned and should be used for reference only.

Appendix VIII: YMEP Final Submission Form

# YMEP FINAL SUBMISSION FORM

| | | | |
|---|---|---|---|
| | | Date submitted: Jan. 6, 2021 | |
| *submit by January 31st to:*<br><br>*(winter placer projects may submit at pre-approved date)* | YMEP- EMR/ YTG<br>Street address: 102-300 Main Street<br>Mailing address: Box 2703, K-102<br>Whitehorse, Yt, Y1A 2C6 | YMEP@gov.yk .ca<br>phone: 867-456-3828<br>fax: 867-667-3198 | |

| ***CONTACT INFO*** | | ***PROJECT INFO*** | |
|---|---|---|---|
| Name: | Golden Sky Minerals Corp. | YMEP no: | 20-027 |
| Address: | 1010-1130 West Pender St. | Project name: | Bullseye |
| | Vancouver, BC. V6E 4A4 | Project type: | hardrock |
| email | danferraro@hotmail.com | Project module: | target evaluation |
| Phone: | 807-708-7445 | | |

Is the final report enclosed? [4] yes [ ] no

[ ] hard copy
[4] pdf copy
[ ] digital spreadsheet of station location data

Comment:

***PROJECT SUMMARY***

Total project expenditures: 86397.93

Number of new claims since March 31st: yes

Has an option resulted since March 31? [ ] yes [4] no [ ] in negotiation

Number of calendar field days: 12

Number of person-days of employment: 59 paid _____ days of unpaid work

Total no. of samples: 49 rocks silts 562 soils 71 trench other

Total length/volume of trenching/ shafting: 134m trench

Total number of line-km of geophysics

Total meters drilled _____ diamond drill _____ RC drill _____ auger/percussion drill

Other products (provide details):

*This is not an expense claim form.To request reimbursement of expenses, please submit a separate detailed expense claim form.*

***FINANCIAL SUMMARY***

| | | | |
|---|---|---|---|
| Total daily field allowance | 5500 | Total contractor costs | |
| Total field air transportation costs (helicopter/plane) | 37075.93 | Total excavating/ heavy equipment costs | 4550 |
| Total truck/ mileage costs | | Total assay/analyses costs | 15822.78 |
| Total wages paid | 21200 | Total reclamation costs | |
| Total light equipment rental costs | | Total report writing cost | 2250 |
| Other (please specify) | | Total staking costs | (5699.20) |
| Other (please specify) | | | |



*(see reverse)*

YMEP FINAL SUBMISSION FORM

Your feedback on any aspect of the program:

Program went as planned. The main Gold Crest zone soil grid was expanded and new areas of the property were explored. Trenching yielded an intercept of 0.69 g/t Au over 78 meters. Mineralization is open on the east end of the trench. Results from recon soil lines provided many new areas for future follow-up.

Claims were staked on June 30th, 2020 (the day before camp mobilization). The only claim staking costs included in the expenses is helicopter ($4849.20) and two of the man days ($850). The 55 camp man days does not include the staking day.

YMEP support for this program was very much appreciated.

The Department of Energy, Mines and Resources may verify all statements related to and made on this form, in any previously submitted reports, interim claims and in the Summary or Technical Report which accompanies it.

I certify that;

1. I am the person, or the representative of the company or partnership, named in the Application for Funding and in the Contribution Agreement under the Yukon Mining Incentives Program.

2. I am a person who is nineteen years of age or older, and I have complied with all the requirements of the said program.

3. I hereby apply for the final payment of a contribution under the Yukon Mineral Exploration Program (YMEP) and declare the information contained within the Summary or Technical Report and this form to be true and accurate.

Date Jan. 5, 2020

Signature of Applicant Daniel Ferraro

Digitally signed by Daniel Ferraro
DN: cn=Daniel Ferraro, o, ou, email=ferraroconsulting@gmail.com, c=CA
Date: 2021.01.05 20:25:06 -07'00'

Name (print) Dan Ferraro



*(see reverse)*